



CHIQUITA CANYON
A Waste Connections Company

February 11, 2025

Via E-Mail

Karen Gork
Chief Environmental Health Specialist
Los Angeles County Department of Public Health
Local Enforcement Agency
Environmental Programs Division
5050 Commerce Drive,
Baldwin Park, California 91706
KGork@ph.lacounty.gov

Re: Chiquita Canyon, LLC's Weekly Report on the Documentation and Tracking of Cover Issues

Dear Ms. Gork:

In accordance with the Local Enforcement Agency's ("LEA") May 2, 2024 letter approving Chiquita's April 16, 2024 Second Revised Written Plan for Documenting and Tracking Cover Issues ("Second Revised Written Plan"), the LEA's May 29, 2024 letter, and the LEA's June 6, 2024 Compliance Order, Chiquita presents the enclosed report for documenting and tracking cover issues for the week of February 3, 2025 to February 8, 2025.

Please contact me if you have any questions regarding this matter.

Regards,

Amanda Froman
Compliance Manager
Chiquita Canyon, LLC

Attachment: February 3, 2025 Weekly Cover Issues Report

cc: Mark Como, Department of Public Health
Eric Morofuji, Department of Public Health

Fissures and Tension Cracks

4050 - Chiquita Reaction Area Tracking of Fissures and Tension Cracks

3 Feb 2025 / Nancy Bahena Hernandez

Complete

Conducted on

3 Feb 2025 10:26 AM PST

Prepared by

Nancy Bahena Hernandez

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks
1

Fissure or Tension Crack Found?

No

Grid 159



Photo 1

Instability

Are there any indications of slope stability concerns?

No

4050 - Chiquita Reaction Area Tracking of Fissures and Tension Cracks

4 Feb 2025 / Nancy Bahena Hernandez

Complete

Conducted on

4 Feb 2025 12:14 PM PST

Prepared by

Nancy Bahena Hernandez

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks
1

Fissure or Tension Crack Found?

No

Grid 147



Photo 1

Instability

Are there any indications of slope stability concerns?

No

4050 - Chiquita Reaction Area Tracking of Fissures and Tension Cracks

5 Feb 2025 / John Boucher

Complete

Conducted on

5 Feb 2025 8:46 AM PST

Prepared by

John Boucher

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks
1

Fissure or Tension Crack Found?

No

Grid 167



Photo 1

Instability

Are there any indications of slope stability concerns?

No

4050 - Chiquita Reaction Area Tracking of Fissures and Tension Cracks

6 Feb 2025 / John Boucher

Complete

Conducted on

6 Feb 2025 10:56 AM PST

Prepared by

John Boucher

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks
1

Fissure or Tension Crack Found?

No

Grid 170



Photo 1

Instability

Are there any indications of slope stability concerns?

No

4050 - Chiquita Reaction Area Tracking of Fissures and Tension Cracks

7 Feb 2025 / John Boucher

Complete

Conducted on

7 Feb 2025 9:29 AM PST

Prepared by

John Boucher

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks
1

Fissure or Tension Crack Found?

No

Grid 153



Photo 1

Instability

Are there any indications of slope stability concerns?

No

4050 - Chiquita Reaction Area Tracking of Fissures and Tension Cracks

8 Feb 2025 / John Boucher

Complete

Conducted on

8 Feb 2025 9:10 AM PST

Prepared by

John Boucher

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks
1

Fissure or Tension Crack Found?

No

Grid 159



Photo 1

Instability

Are there any indications of slope stability concerns?

No

Settlement

The bi-weekly drone flyover was not conducted this week. The drone data from the next flyover event will be included in the next weekly report.

Geosynthetic Cover

4050 - Geosynthetic Cover Inspection

3 Feb 2025 / Nancy Bahena Hernandez

Complete

Flagged items

0

Conducted on

3 Feb 2025 9:55 AM PST

Prepared by

Nancy Bahena Hernandez

Identification of Issues

Identified Issue

Identified Issue 1

Are there any issues with the geosynthetic cover?

No



Photo 1



Photo 2



Photo 3



Photo 4

Instability under the cover

Are there any anomalous (unusual or unexpected) areas of cover damage or deformation that may indicate underlying instability?

No

Are there any signs of a downslope tension crack at the top of the slope or bulging at or near the toe of the slope?

No

Is there any movement of the equipment that vertically penetrates the cover (e.g., tilting)?

No

4050 - Geosynthetic Cover Inspection

4 Feb 2025 / Nancy Bahena Hernandez

Complete

Flagged items

0

Conducted on

4 Feb 2025 10:15 AM PST

Prepared by

Nancy Bahena Hernandez

Identification of Issues

Identified Issue

Identified Issue 1

Are there any issues with the geosynthetic cover?

No



Photo 1



Photo 2



Photo 3



Photo 4

Instability under the cover

Are there any anomalous (unusual or unexpected) areas of cover damage or deformation that may indicate underlying instability?

No

Are there any signs of a downslope tension crack at the top of the slope or bulging at or near the toe of the slope?

No

Is there any movement of the equipment that vertically penetrates the cover (e.g., tilting)?

No

4050 - Geosynthetic Cover Inspection

5 Feb 2025 / John Boucher

Complete

Flagged items

0

Conducted on

5 Feb 2025 9:36 AM PST

Prepared by

John Boucher

Identification of Issues

Identified Issue

Identified Issue 1

Are there any issues with the geosynthetic cover?

No



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6

Instability under the cover

Are there any anomalous (unusual or unexpected) areas of cover damage or deformation that may indicate underlying instability?

No

Are there any signs of a downslope tension crack at the top of the slope or bulging at or near the toe of the slope?

No

Is there any movement of the equipment that vertically penetrates the cover (e.g., tilting)?

No

4050 - Geosynthetic Cover Inspection

6 Feb 2025 / John Boucher

Complete

Flagged items

0

Conducted on

6 Feb 2025 12:38 PM PST

Prepared by

John Boucher

Identification of Issues

Identified Issue

Identified Issue 1

Are there any issues with the geosynthetic cover?

No



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5

Instability under the cover

Are there any anomalous (unusual or unexpected) areas of cover damage or deformation that may indicate underlying instability?

No

Are there any signs of a downslope tension crack at the top of the slope or bulging at or near the toe of the slope?

No

Is there any movement of the equipment that vertically penetrates the cover (e.g., tilting)?

No

4050 - Geosynthetic Cover Inspection

7 Feb 2025 / John Boucher

Complete

Flagged items

0

Conducted on

7 Feb 2025 10:58 AM PST

Prepared by

John Boucher

Identification of Issues

Identified Issue

Identified Issue 1

Are there any issues with the geosynthetic cover?

Yes

Take photo of identified issues



Photo 1

Notate what the issue is and what needs to be repaired

Near the west side perimeter road, the seam between the 30mm and 60mm liners separated and needed to be re-sealed together.

Take photo of repair



Photo 2



Photo 3

Description of repair work

Seam was temporarily sealed. Permanent repairs were conducted when weather conditions improved from the recent rain. Liners were sealed together on 2/10/25.

Date and time of repair (within 2 hours)

10 Feb 2025 5:00 PM PST

Are further permanent repairs required?

No

Instability under the cover

Are there any anomalous (unusual or unexpected) areas of cover damage or deformation that may indicate underlying instability?

No

Are there any signs of a downslope tension crack at the top of the slope or bulging at or near the toe of the slope?

No

Is there any movement of the equipment that vertically penetrates the cover (e.g., tilting)?

No

4050 - Geosynthetic Cover Inspection

8 Feb 2025 / John Boucher

Complete

Flagged items

0

Conducted on

8 Feb 2025 10:08 AM PST

Prepared by

John Boucher

Identification of Issues

Identified Issue

Identified Issue 1

Are there any issues with the geosynthetic cover?

No



Photo 1



Photo 2



Photo 3




Photo 4



Photo 5



Photo 6

Instability under the cover

Are there any anomalous (unusual or unexpected) areas of cover damage or deformation that may indicate underlying instability?

No

Are there any signs of a downslope tension crack at the top of the slope or bulging at or near the toe of the slope?

No

Is there any movement of the equipment that vertically penetrates the cover (e.g., tilting)?

No

February 10, 2025

Mr. Steve Cassulo
Chiquita Canyon Landfill
29201 Henry Mayo Drive
Castaic, California 91384

**JANUARY 2025 FISSURE AND TENSION CRACK MONITORING SUMMARY
CHIQUITA CANYON LANDFILL
CASTAIC, CALIFORNIA**

Dear Mr. Cassulo:

This monthly summary report was prepared by Geo-Logic Associates, Inc. (GLA) to summarize the monitoring and tracking of fissures and tension cracks that was performed at the Chiquita Canyon Landfill (Landfill) between January 1 and January 31, 2024. This summary was prepared in accordance with Chiquita Canyon, LLC's (Chiquita) April 16, 2024 Second Revised Written Plan (Second Revised Written Plan) to document and track cover issues and is associated with Milestone 2B of the Local Enforcement Agency's (LEA) June 6, 2024 Compliance Order, formerly referred to as Mitigation Measure #2B. The conclusions in this summary are based on GLA's review and evaluation of Chiquita's daily Reaction Area Tracking of Fissures and Tension Cracks data sheets that document and track cover issues, and on information from Chiquita's drone aerial surveys.

January Observations

Chiquita conducts daily monitoring of the soil cover for fissures and tension cracks and of the geomembrane-covered area for damage or evidence of possible instability. The cracks and fissures that were observed in January 2025 are summarized in Table 1. Table 2 summarizes the daily observations performed in geomembrane-covered areas in January. As indicated in these tables, no evidence of instability was observed in the soil cover areas or the geomembrane-covered areas.

As indicated in Table 1, no cracks or fissures that met the definition of significant in the Second Revised Written Plan were observed in January.¹ Although not significant, the following cracks with "medium" to "large" horizontal offset were observed in January:

¹ Pursuant to the Second Revised Written Plan, a "significant" fissure or tension crack is one that (1) is 100 feet or longer in length; (2) has a horizontal offset of 0.5 inches or more when the fissure/crack is at

- An approximately 15-ft-long crack with 2 to 4 inches of horizontal offset (defined as “medium”) and less than 0.5 inches of vertical offset (defined as “extra small”) was observed in Grid 146 on January 2, 2025.
- An approximately 5 ft x 15 ft area with one or more cracks with 2 to 4 inches of horizontal offset (defined as “medium”) and less than 0.5 inches of vertical offset (defined as “extra small”) was observed in Grid 146 on January 9, 2025.
- An approximately 3-ft-long crack with 2 to 4 inches of horizontal offset (defined as “medium”) and less than 0.5 inches of vertical offset (defined as “extra small”) was observed in Grid 146 on January 13, 2025.
- An approximately 10 ft x 20 ft area with one or more cracks with 2 to 4 inches of horizontal offset (defined as “medium”) and less than 0.5 inches of vertical offset (defined as “extra small”) was observed in Grid 165 on January 17, 2025.
- An approximately 3-ft-long crack with 2 to 4 inches of horizontal offset (defined as “medium”) and less than 0.5 inches of vertical offset (defined as “extra small”) was observed in Grid 146 on January 21, 2025.
- An approximately 12 ft x 4 ft area with one or more cracks with greater than 4 inches of horizontal offset (defined as “large”) and less than 0.5 inches of vertical offset (defined as “extra small”) was observed in Grid 146 on January 28, 2025.
- An approximately 30 ft x 20 ft area with one or more cracks with 2 to 4 inches of horizontal offset (defined as “medium”) and less than 0.5 inches of vertical offset (defined as “extra small”) was observed in Grid 160 on January 28, 2025.

All the cracks were repaired by placing soil and track-walking over the crack. The locations of the grids and the relative orientations of the cracks identified above are shown in Figure 1. The grid locations of these cracks on the top deck of the landfill and the orientations of the cracks indicate they were likely associated with settlement and not with slope instability.

Cross Sections

Cross sections that compare December 26, 2024 and January 29, 2025 topography are shown in Figures 2A through 2E. The locations of the cross sections are shown in Figure 1. The sections show no significant differences in slope between the December 2024 and January 2025 profiles, and no evidence of deformation indicative of instability, which is

least 50 feet in length; or (3) has a vertical offset of 0.5 inches or more when the fissure/crack is at least 50 feet in length or there are multiple fissures/cracks oriented in the same direction.

consistent with the daily site observations described above and the information summarized in Tables 1 and 2.

Previous Monitoring Results and Trends

Previous monitoring in May, June, and December 2024 indicated potentially significant cracking in the following grids:

- **Grid 183.** The May 2024 monthly summary report described one potentially significant tension crack in Grid 183 identified on May 23, 2024 that was approximately 65 feet long with 0.5 to 2 inches of horizontal offset (defined as “small”). This crack was repaired by track-walking, and no significant or potentially significant cracks were observed in this grid during subsequent monitoring in May or June. This grid has been covered with a geomembrane and there was no evidence of instability associated with this (or any) geomembrane-covered area in July, August, September, October, November, or December 2024, or January 2025.
- **Grid 151.** The May 2024 monthly report indicated that potentially significant cracking may have been present in Grid 151 on May 20 and May 28, 2024. The June monthly report identified a crack, although not significant, with more than 4 inches of horizontal offset (defined as “large”) and 0.5 to 2 inches of vertical offset (defined as “small”) that was observed within an approximately 15-foot x 35-foot area of multiple cracks in this grid on June 19, 2024. The July monthly report identified a non-significant crack with more than 4 inches of horizontal offset and 0.5 to 2 inches of vertical offset that was observed in this grid on July 2, 2024. The July crack was repaired, and no cracks were observed in this grid during subsequent July, August, September, October, November, or December 2024, or January 2025 monitoring rounds.
- **Grid 180.** An approximately 60-foot-long crack was observed within Grid 180 on June 3, 2024. The horizontal offset was “small,” which means it was between 0.5-inches and 2-inches in width. This crack was not observed or noted during subsequent June monitoring rounds. This grid has been covered with a geomembrane and there was no evidence of instability associated with this (or any) geomembrane-covered area during subsequent July, August, September, October, November, or December 2024, or January 2025 monitoring rounds.
- **Grid 152.** An approximately 55-foot-long crack was observed within Grid 152 on June 24, 2024. The horizontal offset was identified as “small.” This crack was not noted during subsequent monitoring rounds in June, and there was no cracking observed in this grid during subsequent July, August, September, October,

November, or December 2024, or January 2025 monitoring rounds. Grid 152 has been partially covered with a geomembrane and is near the center of the Landfill's top deck.

- **Grid 146.** An approximately 55-foot-long crack was observed within Grid 146 on December 4, 2024. The horizontal offset was identified as "medium" whereas the vertical offset was identified as "extra small". This crack was repaired by track-walking and was not observed during subsequent December monitoring rounds. No other potentially significant cracks or fissures were observed within this grid during December 2024 or January 2025 monitoring rounds.

Most of the fissures and tension cracks identified between April 2024 and January 2025 were identified in grids located on the top deck of the Landfill. Although much of the reaction area has been covered with a geomembrane and the soil cover cannot be observed in the geomembrane-covered areas, the January 2025 observations are consistent with previous observations that show no evidence of slope instability. Based on the Chiquita monitoring logs and on GLA observations during site visits, the above-described cracks documented in January 2025 were associated with settlement and do not provide evidence of slope instability.

Please let me know if you have any questions regarding the information in this report.

Very truly yours,
Geo-Logic Associates, Inc.


Richard A. Mitchell, PG, CEG
Principal Engineering Geologist



Table 1
SUMMARY OF JANUARY 2025 FISSURE AND TENSION CRACK
OBSERVATIONS Chiquita Canyon Landfill

DATE	INSPECTOR	GRID	LOCATION	TYPE	LENGTH (ft)	AREA (ft x ft)	HORIZONTAL OFFSET	VERTICAL OFFSET	ORIENTATION	LATITUDE	LONGITUDE	REPAIRED	INDICATIONS OF SLOPE STABILITY CONCERNs
1/2/2025	John Boucher	146	Top Deck	Linear	15		Medium	Extra Small	NS	34.435957	-118.646867	Yes	No
1/3/2025	John Boucher		No Cracks Found	Area									No
1/4/2025	John Boucher		No Cracks Found	Area									No
1/6/2025	Nancy Bahena	147	Top Deck	Area		5x4	Small	Extra Small	NS	NR	NR	Yes	No
1/6/2025	Nancy Bahena	170	Top Deck-South End	Linear	12		Small	Extra Small	NW	34.433894	-118.649172	Yes	No
1/7/2025	Nancy Bahena		No Cracks Found	Area									No
1/8/2025	John Boucher		No Cracks Found	Area									No
1/9/2025	John Boucher	146	Top Deck	Area		5x15	Medium	Extra Small	NS	34.436371	-118.647135	Yes	No
1/10/2025	John Boucher		No Cracks Found	Area									No
1/11/2025	John Boucher		No Cracks Found	Area									No
1/13/2025	Nancy Bahena	146	Top Deck	Linear	3		Medium	Extra Small	NS	34.440156	-118.628916	Yes	No
1/14/2025	Nancy Bahena	167	Top Deck-South End	Area		10x6	Small	Extra Small	NW	34.433704	-118.648975	Yes	No
1/14/2025	Nancy Bahena	170	Top Deck-South End	Linear	12		Small	Extra Small	NW	34.434071	-118.649399	Yes	No
1/15/2025	John Boucher		No Cracks Found	Area									No
1/16/2025	Nancy Bahena		No Cracks Found	Area									No
1/17/2025	John Boucher	165	Top Deck-South End	Area		10x20	Medium	Extra Small	NW	34.433413	-118.647875	Yes	No
1/18/2025	John Boucher		No Cracks Found	Area									No
1/20/2025	Nancy Bahena		No Cracks Found	Area									No
1/21/2025	Nancy Bahena	146	Top Deck	Linear	3		Medium	Extra Small	NW	34.436277	-118.647338	Yes	No
1/21/2025	Nancy Bahena	167	Top Deck-South End	Area		20x15	Small	Extra Small	NW	34.433729	-118.648745	Yes	No
1/23/2025	John Boucher		No Cracks Found	Area									No
1/24/2025	John Boucher	171	Top Deck-South End	Area		6x7	Small	Extra Small	NW	34.431773	-118.637548	Yes	No
1/25/2025	John Boucher		No Cracks Found	Area									No
1/27/2025	Nancy Bahena		No Cracks Found	Area									No
1/28/2025	Nancy Bahena	146	Top Deck	Area		12x4	Large	Extra Small	NW	34.435910	-118.647068	Yes	No
1/28/2025	Nancy Bahena	160	Top Deck-South End	Area		30x20	Medium	Extra Small	NE	34.433763	-118.647797	Yes	No
1/29/2025	John Boucher		No Cracks Found	Area									No
1/30/2025	John Boucher		No Cracks Found	Area									No
1/31/2025	John Boucher		No Cracks Found	Area									No

HORIZONTAL CRACK DEFINITIONS

Extra Small <0.5-in Width
 Small 0.5-in to 2-in Width
 Medium 2-in to 4-in Width
 Large >4-in Width

VERTICAL CRACK DEFINITIONS



Extra Small <0.5-in Height
 Small 0.5-in to 2-in Height

Table 2
SUMMARY OF JANUARY 2025 GEOMEMBRANE COVER OBSERVATIONS
Chiquita Canyon Landfill

DATE	ISSUES OR CONCERNS			
	Issue Identified	Evidence of Underlying Deformation	Tension Cracks at Top of Slope or Bulging at Toe of Slope	Vertical Deformation of Infrastructure Such as Wells or Probes
1/2/2025	No	No	No	No
1/3/2025	No	No	No	No
1/4/2025	Yes ^a	No	No	No
1/6/2025	No	No	No	No
1/7/2025	Yes ^b	No	No	No
1/8/2025	No	No	No	No
1/9/2025	No	No	No	No
1/10/2025	No	No	No	No
1/11/2025	No	No	No	No
1/13/2025	No	No	No	No
1/14/2025	No	No	No	No
1/15/2025	No	No	No	No
1/16/2025	No	No	No	No
1/17/2025	No	No	No	No
1/18/2025	No	No	No	No
1/20/2025	No	No	No	No
1/21/2025	No	No	No	No
1/22/2025	No	No	No	No
1/24/2025	No	No	No	No
1/25/2025	No	No	No	No
1/27/2025	No	No	No	No
1/28/2025	No	No	No	No
1/29/2025	No	No	No	No
1/30/2025	No	No	No	No
1/31/2025	No	No	No	No

^aLiner was separated at a seam. The seam was subsequently patched.

^bLiner lifted from the cover at two locations. Subsequently patched and no further repairs required.



P:\TESTS\UHQUITA\CTN\LT\MONITORING_SUMMARY FIGURES\RM2211\U-(2020-02-06).JPG February 1, 2020 - 9:12 AM BY: GLA-USER

This drawing has not been published but rather has been prepared by Geo-Logic Associates, Inc. for use by the client named in the title block, solely in respect of the construction operation, and maintenance of the facility named in the title block. Geo-Logic Associates, Inc. shall not be liable for the use of this drawing on any other facility or for any other purpose.

REFERENCE AERIAL TOPO BASED ON JANUARY 16, 2024 AERIAL SURVEY BY TETRATECH WITH MONTHLY UPDATES ON JANUARY 29, 2025

REV. NO.	DATE	DESCRIPTION	APPROVED BY	DATE OF ISSUE: <u>FEBRUARY 2025</u>
				DESIGNED BY: <u>R MITCHELL</u>
				CAD DESIGN BY: <u>L PADILLA</u>
				CHECKED BY: <u>R MITCHELL</u>
				APPROVED BY: <u>R MITCHELL</u>



Geo-Logic ASSOCIATES

2777 EAST GUASTI ROAD
SUITE 1
ONTARIO, CA 91761
(909) 626-2282
www.gocologic.com



CHIQUITA CANYON

A Waste Connections Company

29201 HENRY MAYO DRIVE
CASTAIC, CA 91384

JANUARY 2025 MONITORING SUMMARY
CHIQUITA CANYON LANDFILL
COUNTY OF LOS ANGELES, CA

FIG NO.
01
PROJECT NO.
RM22.1077






FIGURE 2A

WESTERN SLOPE CROSS SECTION A
JANUARY 2025 MONITORING SUMMARY
CHIQUITA CANYON LANDFILL
COUNTY OF LOS ANGELES, CA

Geo-Logic
ASSOCIATES





FIGURE 2B
WESTERN SLOPE CROSS SECTION B
JANUARY 2025 MONITORING SUMMARY
CHIQUITA CANYON LANDFILL
COUNTY OF LOS ANGELES, CA

Geo-Logic
ASSOCIATES








FIGURE 2C
WESTERN SLOPE CROSS SECTION C
JANUARY 2025 MONITORING SUMMARY
CHIQUITA CANYON LANDFILL
COUNTY OF LOS ANGELES, CA

Geo-Logic
ASSOCIATES



150' 0' 75' 150'
SCALE: 1" = 150'



300' 0' 150' 300'
SCALE: 1" = 300'

FIGURE 2D
WESTERN SLOPE CROSS SECTION D
JANUARY 2025 MONITORING SUMMARY
CHIQUITA CANYON LANDFILL
COUNTY OF LOS ANGELES, CA

Geo-Logic
ASSOCIATES






FIGURE 2E

WESTERN SLOPE CROSS SECTION E
JANUARY 2025 MONITORING SUMMARY
CHIQUITA CANYON LANDFILL
COUNTY OF LOS ANGELES, CA

Geo-Logic
ASSOCIATES