



January 13, 2026

Via E-Mail

Karen Gork
Chief Environmental Health Specialist
Los Angeles County Department of Public Health
Local Enforcement Agency
Environmental Programs Division
5050 Commerce Drive,
Baldwin Park, California 91706
KGork@ph.lacounty.gov

Re: Chiquita Canyon, LLC's Weekly Report on the Documentation and Tracking of Cover Issues, Monthly Summary and Monthly Isopach Map

Dear Ms. Gork:

In accordance with the Local Enforcement Agency's ("LEA") May 2, 2024 letter approving Chiquita's April 16, 2024 Second Revised Written Plan for Documenting and Tracking Cover Issues ("Second Revised Written Plan"), the LEA's May 29, 2024 letter, and the LEA's June 6, 2024 Compliance Order, Chiquita presents the enclosed report for documenting and tracking cover issues for the week of January 5, 2026 to January 10, 2026.

Also included in this report are the monthly isopach map and the monthly summary of fissures and tension cracks prepared for December 2025, pursuant to the Second Revised Written Plan.

Please contact me if you have any questions regarding this matter.

Regards,

Amanda Froman

Amanda Froman
Compliance Manager
Chiquita Canyon, LLC

Attachment: January 13, 2026 Weekly Cover Issues Report

cc: Mark Como, Department of Public Health
Eric Morofuji, Department of Public Health

Fissures and Tension Cracks

4050 - Chiquita Reaction Area Tracking of Fissures and Tension Cracks

5 Jan 2026 / Tom Roe

Complete

Conducted on

5 Jan 2026 10:23 AM PST

Prepared by

Tom Roe

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks
1

Fissure or Tension Crack Found?

No

Grid 163



Photo 1

Instability

Are there any indications of slope stability concerns?

No

4050 - Chiquita Reaction Area Tracking of Fissures and Tension Cracks

6 Jan 2026 / Tom Roe

Complete

Conducted on

6 Jan 2026 9:46 AM PST

Prepared by

Tom Roe

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks
1

Fissure or Tension Crack Found?

No

Grid 160



Photo 1

Instability

Are there any indications of slope stability concerns?

No

4050 - Chiquita Reaction Area Tracking of Fissures and Tension Cracks

7 Jan 2026 / Tom Roe

Complete

Conducted on

7 Jan 2026 9:03 AM PST

Prepared by

Tom Roe

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks
1

Fissure or Tension Crack Found?

No

Grid 147



Photo 1

Instability

Are there any indications of slope stability concerns?

No

4050 - Chiquita Reaction Area Tracking of Fissures and Tension Cracks

8 Jan 2026 / John Boucher

Complete

Conducted on

8 Jan 2026 8:32 AM PST

Prepared by

John Boucher

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks
1

Fissure or Tension Crack Found?

No

Grid 164



Photo 1

Instability

Are there any indications of slope stability concerns?

No

4050 - Chiquita Reaction Area Tracking of Fissures and Tension Cracks

9 Jan 2026 / Nancy Bahena Hernandez

Complete

Conducted on

9 Jan 2026 11:46 AM PST

Prepared by

Nancy Bahena Hernandez

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks
1

Fissure or Tension Crack Found?

No

Grid 147



Photo 1

Instability

Are there any indications of slope stability concerns?

No

4050 - Chiquita Reaction Area Tracking of Fissures and Tension Cracks

10 Jan 2026 / John Boucher

Complete

Conducted on

10 Jan 2026 7:26 AM PST

Prepared by

John Boucher

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks
1

Fissure or Tension Crack Found?

No

Grid 147



Photo 1

Instability

Are there any indications of slope stability concerns?

No

Settlement

The bi-weekly drone flyover was not conducted this week. The drone data from the next flyover event will be included in the next weekly report.

Geosynthetic Cover

4050 - Geosynthetic Cover Inspection

5 Jan 2026 / Tom Roe

Complete

Flagged items

0

Conducted on

5 Jan 2026 9:18 AM PST

Prepared by

Tom Roe

Identification of Issues

Identified Issue

Identified Issue 1

Are there any issues with the geosynthetic cover?

No



Photo 1



Photo 2



Photo 3



Photo 4

Instability under the cover

Are there any anomalous (unusual or unexpected) areas of cover damage or deformation that may indicate underlying instability?

No

Are there any signs of a downslope tension crack at the top of the slope or bulging at or near the toe of the slope?

No

Is there any movement of the equipment that vertically penetrates the cover (e.g., tilting)?

No

4050 - Geosynthetic Cover Inspection

6 Jan 2026 / Tom Roe

Complete

Flagged items

0

Conducted on

6 Jan 2026 7:30 AM PST

Prepared by

Tom Roe

Identification of Issues

Identified Issue

Identified Issue 1

Are there any issues with the geosynthetic cover?

No



Photo 1



Photo 2



Photo 3



Photo 4

Instability under the cover

Are there any anomalous (unusual or unexpected) areas of cover damage or deformation that may indicate underlying instability?

No

Are there any signs of a downslope tension crack at the top of the slope or bulging at or near the toe of the slope?

No

Is there any movement of the equipment that vertically penetrates the cover (e.g., tilting)?

No

4050 - Geosynthetic Cover Inspection

7 Jan 2026 / Tom Roe

Complete

Flagged items

0

Conducted on

7 Jan 2026 9:08 AM PST

Prepared by

Tom Roe

Identification of Issues

Identified Issue

Identified Issue 1


Are there any issues with the geosynthetic cover?

Yes

Date and Time Issue Found

7 Jan 2026 9:17 AM PST

Grid Location



Grid 183

Take photo of identified issues



Photo 1

Notate what the issue is and what needs to be repaired

Tear in liner needs to be patched and extrusion welded.

Take photo of repair



Photo 2

Description of repair work

Tear taped and sandbagged upon discovery. Final repair completed on 1/8/26.

Date and time of repair (within 2 hours)

7 Jan 2026 9:29 AM PST

Are further permanent repairs required?

No

Permanent repair conducted on 1/8/26



Photo 3

Instability under the cover

Are there any anomalous (unusual or unexpected) areas of cover damage or deformation that may indicate underlying instability?

No

Are there any signs of a downslope tension crack at the top of the slope or bulging at or near the toe of the slope?

No

Is there any movement of the equipment that vertically penetrates the cover (e.g., tilting)?

No

4050 - Geosynthetic Cover Inspection

8 Jan 2026 / John Boucher

Complete

Flagged items

0

Conducted on

8 Jan 2026 8:32 AM PST

Prepared by

John Boucher

Identification of Issues

Identified Issue

Identified Issue 1

Are there any issues with the geosynthetic cover?

No



Photo 1



Photo 2




Photo 3



Photo 4

Instability under the cover

Are there any anomalous (unusual or unexpected) areas of cover damage or deformation that may indicate underlying instability?

No

Are there any signs of a downslope tension crack at the top of the slope or bulging at or near the toe of the slope?

No

Is there any movement of the equipment that vertically penetrates the cover (e.g., tilting)?

No

4050 - Geosynthetic Cover Inspection

9 Jan 2026 / Nancy Bahena Hernandez

Complete

Flagged items

0

Conducted on

9 Jan 2026 11:45 AM PST

Prepared by

Nancy Bahena Hernandez

Identification of Issues

Identified Issue

Identified Issue 1


Are there any issues with the geosynthetic cover?

Yes

Date and Time Issue Found

9 Jan 2026 2:14 PM PST

Grid Location



Grid 191

Take photo of identified issues



Photo 1

Notate what the issue is and what needs to be repaired

A tear was found in grid 191

Take photo of repair



Photo 2

Description of repair work

Flex tape was used upon discovery, final repair scheduled for 1/13/25.

Date and time of repair (within 2 hours)

9 Jan 2026 2:25 PM PST

Are further permanent repairs required?

Yes

Instability under the cover

Are there any anomalous (unusual or unexpected) areas of cover damage or deformation that may indicate underlying instability?

No

Are there any signs of a downslope tension crack at the top of the slope or bulging at or near the toe of the slope?

No

Is there any movement of the equipment that vertically penetrates the cover (e.g., tilting)?

No

4050 - Geosynthetic Cover Inspection

10 Jan 2026 / John Boucher

Complete

Flagged items

0

Conducted on

10 Jan 2026 7:26 AM PST

Prepared by

John Boucher

Identification of Issues

Identified Issue

Identified Issue 1

Are there any issues with the geosynthetic cover?

No



Photo 1



Photo 2



Photo 3



Photo 4

Instability under the cover

Are there any anomalous (unusual or unexpected) areas of cover damage or deformation that may indicate underlying instability?

No

Are there any signs of a downslope tension crack at the top of the slope or bulging at or near the toe of the slope?

No

Is there any movement of the equipment that vertically penetrates the cover (e.g., tilting)?

No



January 13, 2026

Ms. Kate Logan
Chiquita Canyon Landfill
29201 Henry Mayo Drive
Castaic, California 91384

**DECEMBER 2025 FISSURE AND TENSION CRACK MONITORING SUMMARY
CHIQUITA CANYON LANDFILL
CASTAIC, CALIFORNIA**

Dear Ms. Logan:

This monthly summary report was prepared by Geo-Logic Associates, Inc. (GLA) to summarize the monitoring and tracking of fissures and tension cracks that was performed at the Chiquita Canyon Landfill (Landfill) between December 1 and December 31, 2025, in accordance with Milestone 2B of the Local Enforcement Agency's (LEA) June 6, 2024 Compliance Order, formerly referred to as Mitigation Measure #2B. This summary was prepared in accordance with Chiquita Canyon, LLC's (Chiquita) April 16, 2024 Second Revised Written Plan (Second Revised Written Plan) to document and track cover issues and is associated with Milestone 2B.

DECEMBER OBSERVATIONS

Chiquita conducts daily monitoring of the soil cover for fissures and tension cracks and of the geomembrane-covered area for damage or evidence of possible instability. The cracks and fissures that were observed in December 2025 are summarized in Table 1. Table 2 summarizes the daily observations performed in geomembrane-covered areas in December 2025. Chiquita repaired all the cracks identified in Table 1 and all the small geomembrane tears identified in Table 2.

As indicated in these tables, no evidence of instability was reported in the soil-covered areas or the geomembrane-covered areas. The cracks and fissures summarized in Table 1 were reviewed with respect to the criteria for "significant" as that term is defined in Chiquita's Second Revised Written Plan.¹ As shown in this table, no cracks or fissures that met any of these criteria were observed in December.

¹ Pursuant to the Second Revised Written Plan, a "significant" fissure or tension crack is one that (1) is 100 feet or longer in length; (2) has a horizontal offset of 0.5 inches or more when the fissure/crack is at least 50 feet in length; or (3) has a vertical offset of 0.5 inches or more when the fissure/crack is at least 50 feet in length or there are multiple fissures/cracks oriented in the same direction. The classification of

As summarized in Table 1, four instances of cracking or fissuring were documented in December:

- An approximately 65 ft by 6 ft area with “small” horizontal offset and “extra small” vertical offset cracks were observed in Grid 147 on December 1, 2025. The longest crack in this area was approximately 25 ft. This area of cracking is not significant.
- An approximately 20 ft by 40 ft area with “extra small” horizontal and vertical offset cracks were observed in Grid 148 on December 4, 2025. This area of cracking is not significant.
- An approximately 6 ft long crack with “small” horizontal offset and “extra small” vertical offset was observed in Grid 161 on December 4, 2025. This crack is not significant.
- An approximately 4 ft long crack with “medium” horizontal offset and “extra small” vertical offset was observed in Grid 161 on December 18, 2025. This crack is not significant. The approximate location of this crack is shown in Figure 1 for consistency with prior documentation of all cracks or fissures with medium or greater horizontal and/or vertical offsets.

All the cracks identified in Table 1 and summarized above were repaired. Cross sections that compare November 26, 2025 and December 30, 2025 topography are shown in Figures 2A through 2E. The locations of these cross sections are shown in Figure 1. The sections show no significant differences in slope or evidence of instability between the November 2025 and December 2025 profiles, which is consistent with the observational records summarized in Tables 1 and 2.

GRID TRENDS

Monitoring in May, June, and December 2024 and in June, July, August, September, and October 2025 documented cracks potentially meeting the definition of “significant”, as that term is defined in Chiquita’s Second Revised Written Plan, in the following grids:

- **Grid 183.** On May 23, 2024, a 65-ft tension crack with 0.5–2 in. horizontal offset (“small”) was observed. It was repaired by track-walking, and no further cracking was reported in subsequent May and June 2024 inspections. The grid has since

a crack or fissure as “significant” for purposes of this summary does not mean that there is a concern for slope instability or that the Landfill’s containment system is compromised. The criteria were established for comparison purposes only.

been geomembrane-covered, with no evidence of instability observed from July 2024 through December 2025.

- **Grid 151.** Cracking was noted on May 20 and 28, 2024. A June 19, 2024 inspection confirmed multiple cracks within a 15 ft x 35 ft area, including one with >4 in. horizontal offset (“large”) and 0.5–2 in. vertical offset (“small”). On July 2, 2024, an additional non-significant crack with similar offsets was observed and repaired. This grid has since been geomembrane-covered and there has been no evidence of instability from August 2024 through December 2025.
- **Grid 180.** On June 3, 2024, a 60-ft crack with “small” horizontal offset was observed. The feature was not present in subsequent June 2024 monitoring. The grid has been geomembrane-covered, with no evidence of instability observed through December 2025.
- **Grid 152.** On June 24, 2024, a 55-ft crack with “small” horizontal offset was observed. No cracking was reported in this grid in subsequent inspections until more than a year later. On July 30, 2025, a 10 ft x 5 ft area of cracks with “medium” horizontal and “extra small” vertical offsets was documented, classified as nonsignificant, and repaired. This grid is geomembrane-covered, and there has been no evidence of instability through December 2025.
- **Grid 146.** A 55-ft crack with “medium” horizontal and “extra-small” vertical offsets was documented and repaired on December 4, 2024. Additional minor cracks with “medium” to “large” horizontal offsets were identified and repaired in May and June 2025. On July 8, 2025, a 75-ft-long crack with “small” horizontal and “extra-small” vertical offsets was observed across the Grid 146/147 boundary and repaired. Two minor cracks were noted later in July, one in August, and five in September 2025; all were repaired. In October 2025, one potentially “significant” and two minor cracks were documented and subsequently repaired by soil placement and track-walking. One non-significant crack with “large” displacement was identified in November 2025 and was repaired. Most of this grid is now geomembrane covered and no cracking was observed in the exposed portions of the grid in December 2025.
- **Grid 147.** A 100-ft crack with “large” horizontal and “medium” vertical offsets was documented and repaired on June 23, 2025. On July 8, 2025, a 75-ft crack spanning Grids 146 and 147 with “small” horizontal and “extra-small” vertical offsets was observed and repaired. Later July inspections identified three minor cracks with “medium” to “large” offsets; all were repaired. In August 2025, one 65-ft crack and several localized cracks or small settlement-related “collapse”

features were documented and repaired. Five additional minor cracks were observed and repaired in September. In October 2025, two potentially “significant” cracks within Grid 147 and one spanning Grids 147–148 were documented, along with three minor cracks. All October features were repaired by soil placement and track-walking. One non-significant crack with “large” displacement was identified in November 2025 and was repaired. Approximately two thirds of this grid is now geomembrane covered. One non-significant crack with “small” horizontal offset and “extra small” vertical offset was identified in the exposed portion of the grid in December 2025 and was repaired.

- **Grid 164.** On September 12, 2025, potentially “significant” cracking was observed in Grid 164 based on the presence of an approximately 40-ft x 50-ft area containing multiple intersecting cracks, the longest of which was about 50 ft. The horizontal offset (width) of the crack(s) was identified as “large,” the vertical offset (height) of the crack(s) was identified as “extra small”, and the orientation of the crack(s) was identified as northeast-to-southwest. No slope-stability concerns were noted in this grid at the time of observation, and the cracks were repaired. Approximately 50 percent of this grid is now covered by the geomembrane. No cracking was documented in exposed portions of Grid 164 in the October through December 2025 field records.

CONCLUSIONS

As summarized in Table 1, no “significant” cracks or fissures were identified in December 2025. One non-significant crack with “medium” offset and “extra small” vertical offset was observed in Grid 161 at the approximate location shown in Figure 1 during December 2025. Although much of the affected area is now geomembrane-covered, monitoring to date indicates the documented cracking is attributable to settlement and does not constitute evidence of slope instability.

Please let me know if you have any questions regarding the information in this report.

Very truly yours,
Geo-Logic Associates, Inc.


Richard A. Mitchell, PG, CEG
Principal Engineering Geologist



Table 1
SUMMARY OF DECEMBER 2025 FISSURE AND TENSION CRACK OBSERVATIONS
Chiquita Canyon Landfill

DATE	INSPECTOR	GRID	LOCATION	TYPE	LENGTH (ft)	AREA (ft x ft)	HORIZONTAL OFFSET	VERTICAL OFFSET	ORIENTATION	LATITUDE	LONGITUDE	REPAIRED	INDICATIONS OF SLOPE STABILITY CONCERNs
12/1/2025	Tom Roe	147	Top Deck	Area		65x6 (25)	Small	Extra Small	NE	34.435360	-118.647904	Yes	No
12/2/2025	Tom Roe		No Cracks Found	N/A									No
12/3/2025	Tom Roe		No Cracks Found	N/A									No
12/4/2025	John Boucher	148	Top Deck	Area		20x40	Extra Small	Extra Small	NW	34.435446	-118.646811	Yes	No
12/4/2025	John Boucher	161	Top Deck (South)	Linear	6		Small	Extra Small	EW	34.429885	-118.645392	Yes	No
12/5/2025	John Boucher		No Cracks Found	N/A									No
12/6/2025	John Boucher		No Cracks Found	N/A									No
12/8/2025	Tom Roe		No Cracks Found	N/A									No
12/9/2025	Tom Roe		No Cracks Found	N/A									No
12/10/2025	Tom Roe		No Cracks Found	N/A									No
12/11/2025	John Boucher		No Cracks Found	N/A									No
12/12/2025	John Boucher		No Cracks Found	N/A									No
12/13/2025	John Boucher		No Cracks Found	N/A									No
12/15/2025	Tom Roe		No Cracks Found	N/A									No
12/16/2025	Tom Roe		No Cracks Found	N/A									No
12/17/2025	Tom Roe		No Cracks Found	N/A									No
12/18/2025	John Boucher	161	Top Deck (South)	Linear	4		Medium	Extra Small	NE	34.433018	-118.647151	Yes	No
12/19/2025	John Boucher		No Cracks Found	N/A									No
12/20/2025	John Boucher		No Cracks Found	N/A									No
12/22/2025	Tom Roe		No Cracks Found	N/A									No
12/23/2025	Tom Roe		No Cracks Found	N/A									No
12/24/2025	John Boucher		No Cracks Found	N/A									No
12/26/2025	John Boucher		No Cracks Found	N/A									No
12/27/2025	John Boucher		No Cracks Found	N/A									No
12/29/2025	Tom Roe		No Cracks Found	N/A									No
12/30/2025	Tom Roe		No Cracks Found	N/A									No
12/31/2025	Tom Roe		No Cracks Found	N/A									No

HORIZONTAL CRACK DEFINITIONS

Extra Small <0.5-in Width
 Small 0.5-in to 2-in Width
 Medium 2-in to 4-in Width
 Large >4-in Width

VERTICAL CRACK DEFINITIONS

Extra Small <0.5-in Height
 Small 0.5-in to 2-in Height
 Medium 2-in to 4-in Height
 Large >4-in Height



Pursuant to the Second Revised Written Plan, a "significant" fissure or tension crack is one that (1) is 100 feet or longer in length; (2) has a horizontal offset of 0.5 inches or more when the fissure/crack is at least 50 feet in length; or (3) has a vertical offset of 0.5 inches or more when the fissure/crack is at least 50 feet in length or there are multiple fissures/cracks oriented in the same direction. The classification of a crack or fissure as "significant" for purposes of this summary does not mean that there is a concern for slope instability or that the Landfill's containment system is compromised. The criteria were established for comparison purposes only.

Table 2
SUMMARY OF DECEMBER 2025 GEOMEMBRANE COVER OBSERVATIONS
Chiquita Canyon Landfill

DATE	ISSUES OR CONCERNS			
	Issue Identified	Evidence of Underlying Deformation	Tension Cracks at Top of Slope or Bulging at Toe of Slope	Vertical Deformation of Infrastructure Such as Wells or Probes
12/1/2025	No	No	No	No
12/2/2025	No	No	No	No
12/3/2025	No	No	No	No
12/4/2025	No	No	No	No
12/5/2025	No	No	No	No
12/6/2025	No	No	No	No
12/8/2025	No	No	No	No
12/9/2025	No	No	No	No
12/10/2025	Yes ¹	No	No	No
12/11/2025	No	No	No	No
12/12/2025	No	No	No	No
12/13/2025	No	No	No	No
12/15/2025	No	No	No	No
12/16/2025	Yes ^{2,3}	No	No	No
12/17/2025	No	No	No	No
12/18/2025	No	No	No	No
12/19/2025	No	No	No	No
12/20/2025	No	No	No	No
12/22/2025	No	No	No	No
12/23/2025	No	No	No	No
12/24/2025	No	No	No	No
12/26/2025	No	No	No	No
12/27/2025	No	No	No	No
12/28/2025	No	No	No	No
12/29/2025	No	No	No	No
12/30/2025	Yes ^{4,5}	No	No	No
12/31/2025	No	No	No	No

December 2025 Notes:

1. Tear in liner in Grid 208. Tear taped and sandbagged on discovery. Tear taped on sandbagged on 12/10/2025. Permanent repairs by patch and extrusion welding was on 12/11/2025.
2. Several small tears in Grid 209. Tears taped on discovery and repaired the same day by extrusion welding.
3. Two holes in Grid 146. Holes were taped and sandbagged on discovery. Repairs by extrusion welding and patches completed the same day.
4. One tear in the liner in Grid 187. The tear was taped and sandbagged on discovery and repaired the same day by patching and extrusion welding.
5. Three adjacent tears in liner in Grid 180. Tears were taped on discovery and permanent repairs were scheduled for 1/7/2026 after the liner dries following rain.



This drawing has not been published but rather has been prepared by Geo-Logic Associates, Inc. for use by the client named in the title block, solely in respect of the construction operation, and maintenance of the facility named in the title block. Geo-Logic Associates, Inc. shall not be liable for the use of this drawing on any other facility or for any other purpose.

REV. NO.	DATE	DESCRIPTION	APPROVED BY	DATE OF ISSUE: <u>JANUARY 2026</u>	DESIGNED BY: <u>R. MITCHELL</u>	CAD DESIGN BY: <u>L. PADILLA</u>	CHECKED BY: <u>R. MITCHELL</u>	APPROVED BY: <u>R. MITCHELL</u>

DIGITALERT
811

Geo-Logic
ASSOCIATES

2777 EAST GUASTI ROAD
SUITE 1
ONTARIO, CA 91761
(909) 626-2282
www.geo-logic.com

CHIQUITA CANYON
A Waste Connections Company
29201 HENRY MAYO DRIVE
CASTAIC, CA 91384

REFERENCE AERIAL TOPO BASED ON DECEMBER 30, 2025 AERIAL SURVEY PROVIDED BY PROPELLER	DECEMBER 2025 MONITORING SUMMARY CHIQUITA CANYON LANDFILL COUNTY OF LOS ANGELES, CA	FIG NO. 01 PROJECT NO. RM22.1077
	MONITORING GRID	







FIGURE 2A

WESTERN SLOPE CROSS SECTION A
DECEMBER 2025 MONITORING SUMMARY
CHIQUITA CANYON LANDFILL
COUNTY OF LOS ANGELES, CA

Geo-Logic
ASSOCIATES

DRAWN BY: LP/RM DATE: JANUARY 2026 JOB NO.: RM22.1077









FIGURE 2C
WESTERN SLOPE CROSS SECTION C
DECEMBER 2025 MONITORING SUMMARY
CHIQUITA CANYON LANDFILL
COUNTY OF LOS ANGELES, CA

Geo-Logic
ASSOCIATES

WS-D SECTION



LEGEND:



WS-D SECTION

WS-D SECTION






FIGURE 2D
WESTERN SLOPE CROSS SECTION D
DECEMBER 2025 MONITORING SUMMARY
CHIQUITA CANYON LANDFILL
COUNTY OF LOS ANGELES, CA

Geo-Logic
ASSOCIATES

DRAWN BY: LP/RM DATE: JANUARY 2026 JOB NO.: RM22.1077








FIGURE 2E
WESTERN SLOPE CROSS SECTION E
DECEMBER 2025 MONITORING SUMMARY
CHIQUITA CANYON LANDFILL
COUNTY OF LOS ANGELES, CA

Geo-Logic
ASSOCIATES

Chiquita Canyon Landfill - Isopach



December 30, 2025 Survey Image. December 3, 2025 vs. December 30, 2025