

**Archived:** Tuesday, March 10, 2026 9:10:49 AM  
**From:** [Matt Breuer](#)  
**Sent:** Friday, March 6, 2026 9:20:08 PM  
**To:** [Baitong Chen](#)  
**Cc:** [Sarah Phillips](#)  
**Subject:** Chiquita Canyon Landfill – Case No. 6177-4: Leak Report (Condition 27(e))  
**Importance:** Normal  
**Sensitivity:** None

---

[EXTERNAL SENDER: Use caution with links/attachments]

---

All,

In accordance with Condition 27(e) of the Stipulated Order for Abatement in Case No. 6177-4, based on its current knowledge of the event, Chiquita Canyon, LLC (Chiquita) provides the following report detailing a leak of approximately 1 cup of characteristically hazardous liquid associated with Group A and well CV-2411 from a hose in Grid 183.

(1) the date and time of the leak or spill;

0. The leak was discovered on March 5, 2026, at approximately 1:30 p.m.

(2) area designation inspected;

- Characteristically hazardous liquid associated with Group A and well CV-2411 leaked from a hose in Grid 183. Liquid from the leak did not reach the stormwater channel or either stormwater basin.

(3) the name of the person that discovered the leak or spill;

0. Donald Senegal

(4) written acknowledgement that they did, or did not, take corrective action with rationale for these actions;

- Upon discovering the leak, absorbent was immediately applied to the affected area.

(5) a root cause analysis on why and how the leak or spill occurred;

- Based on Chiquita's current knowledge, the leak appears to have occurred because the hose was missing a clamp and became disconnected as a result of strong winds, causing some liquid to leak onto dirt placed on the geomembrane cover. Chiquita attributes this leak to weather conditions.

(6) the estimated quantity of the leak or spill;

0. Chiquita conservatively estimates that approximately 1 cup of characteristically hazardous liquid associated with Group A leaked from the hose.

(7) corrective actions to clean and/or remove the leak or spill;

- In addition to the measures discussed above, the affected soil and soiled absorbent were promptly removed and placed into a container for proper disposal. Cleanup commenced immediately and was completed within approximately 15 minutes.

(8) corrective actions implemented or to be implemented, including an estimated timeline, to prevent future recurrence;

- Chiquita will continue to perform inspections of its landfill gas collection and control system and implement appropriate corrective actions as needed.

(9) the type of affiliation of the operator involved in the root cause;

- No individuals were involved in the root cause of this leak.

(10) whether any individuals involved in the root cause had previously received training on applicable operations to avoid leaks or spills; and

- No individuals were involved in the root cause of this leak; however, Chiquita personnel have been trained on applicable operations to avoid leaks and spills.

(11) the number of times individuals involved in the root cause had previously been involved in the root cause of a leachate leak or spill.

- No individuals were involved in the root cause of this leak.

**Matt Breuer, PE**

Region Environmental Manager

Waste Connections - Western Region

425-414-2903 (mobile)