



CHIQUITA CANYON
A Waste Connections Company

March 10, 2026

Via E-Mail

Karen Gork
Chief Environmental Health Specialist
Los Angeles County Department of Public Health
Local Enforcement Agency
Environmental Programs Division
5050 Commerce Drive,
Baldwin Park, California 91706
KGork@ph.lacounty.gov

Re: Chiquita Canyon, LLC's Weekly Report on the Documentation and Tracking of Cover Issues, Monthly Summary and Monthly Isopach Map

Dear Ms. Gork:

In accordance with the Local Enforcement Agency's ("LEA") May 2, 2024 letter approving Chiquita's April 16, 2024 Second Revised Written Plan for Documenting and Tracking Cover Issues ("Second Revised Written Plan"), the LEA's May 29, 2024 letter, and the LEA's June 6, 2024 Compliance Order, Chiquita presents the enclosed report for documenting and tracking cover issues for the week of March 2, 2026 to March 7, 2026.

Also included in this report are the monthly isopach map and the monthly summary of fissures and tension cracks prepared for February 2026, pursuant to the Second Revised Written Plan.

Please contact me if you have any questions regarding this matter.

Regards,

Matt Breuer
Region Environmental Manager
Chiquita Canyon

Attachment: March 10, 2026 Weekly Cover Issues Report, Monthly Summary, and Monthly Isopach Map

cc: Mark Como, Department of Public Health
Eric Morofuji, Department of Public Health

Fissures and Tension Cracks

4050 - Chiquita Reaction Area Tracking of Fissures and Tension Cracks

2 Mar 2026 / Tom Roe

Complete

Conducted on

2 Mar 2026 10:10 AM PST

Prepared by

Tom Roe

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks
1

Fissure or Tension Crack Found?

No

Grid 160



Photo 1

Instability

Are there any indications of slope stability concerns?

No

4050 - Chiquita Reaction Area Tracking of Fissures and Tension Cracks

3 Mar 2026 / Tom Roe

Complete

Conducted on

3 Mar 2026 10:28 AM PST

Prepared by

Tom Roe

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks
1

Fissure or Tension Crack Found?

No

Grid 164



Photo 1

Instability

Are there any indications of slope stability concerns?

No

4050 - Chiquita Reaction Area Tracking of Fissures and Tension Cracks

4 Mar 2026 / Tom Roe

Complete

Conducted on

4 Mar 2026 9:34 AM PST

Prepared by

Tom Roe

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks
1

Fissure or Tension Crack Found?

No

Grid 160



Photo 1

Instability

Are there any indications of slope stability concerns?

No

4050 - Chiquita Reaction Area Tracking of Fissures and Tension Cracks

5 Mar 2026 / John Boucher

Complete

Conducted on

5 Mar 2026 7:07 AM PST

Prepared by

John Boucher

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks
1

Fissure or Tension Crack Found?

No

Grid 164



Photo 1

Instability

Are there any indications of slope stability concerns?

No

4050 - Chiquita Reaction Area Tracking of Fissures and Tension Cracks

6 Mar 2026 / John Boucher

Complete

Conducted on

6 Mar 2026 7:29 AM PST

Prepared by

John Boucher

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks
1

Fissure or Tension Crack Found?

No

Grid 212



Photo 1

Instability

Are there any indications of slope stability concerns?

No

4050 - Chiquita Reaction Area Tracking of Fissures and Tension Cracks

7 Mar 2026 / John Boucher

Complete

Conducted on

7 Mar 2026 7:54 AM PST

Prepared by

John Boucher

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks
1

Fissure or Tension Crack Found?

No

Grid 198



Photo 1

Instability

Are there any indications of slope stability concerns?

No

Settlement

The bi-weekly drone flyover was not conducted this week. The drone data from the next flyover event will be included in the next weekly report.

Geosynthetic Cover

4050 - Geosynthetic Cover Inspection

2 Mar 2026 / Tom Roe

Complete

Flagged items	0
Conducted on	2 Mar 2026 10:46 AM PST
Prepared by	Tom Roe

Identification of Issues

Identified Issue

Identified Issue 1

Are there any issues with the geosynthetic cover?

Yes

Date and Time Issue Found

2 Mar 2026 10:50 AM PST

Grid Location



Grid Number

208

Take photo of identified issues



Photo 1

Notate what the issue is and what needs to be repaired

Tear in liner needs to be patched/extrusion welded

Take photo of repair



Photo 2



Photo 3

Description of repair work

Tear taped and sandbagged upon discovery and later patched and extrusion welded

Date and time of repair (within 2 hours)

2 Mar 2026 10:52 AM PST

Are further permanent repairs required?

No

Date and Time of final repair (if necessary)

2 Mar 2026 2:35 PM PST

Identified Issue 2


Are there any issues with the geosynthetic cover?

Yes

Date and Time Issue Found

2 Mar 2026 1:35 PM PST

Grid Location



Grid Number

180

Take photo of identified issues



Photo 4



Photo 5

Notate what the issue is and what needs to be repaired

Tears in liner needs to be patched/extrusion welded.

Take photo of repair



Photo 6



Photo 7

Description of repair work

Tears taped and sandbagged upon discovery and later patched and extrusion welded.

Date and time of repair (within 2 hours)

2 Mar 2026 1:39 PM PST

Are further permanent repairs required?

No

Date and Time of final repair (if necessary)

3 Mar 2026 7:05 AM PST

Instability under the cover

Are there any anomalous (unusual or unexpected) areas of cover damage or deformation that may indicate underlying instability?

No

Are there any signs of a downslope tension crack at the top of the slope or bulging at or near the toe of the slope?

No

Is there any movement of the equipment that vertically penetrates the cover (e.g., tilting)?

No

4050 - Geosynthetic Cover Inspection

3 Mar 2026 / Tom Roe

Complete

Flagged items

0

Conducted on

3 Mar 2026 10:46 AM PST

Prepared by

Tom Roe

Identification of Issues

Identified Issue

Identified Issue 1

Are there any issues with the geosynthetic cover?

Yes

Date and Time Issue Found

3 Mar 2026 11:16 AM PST

Grid Location



Grid Number

187

Take photo of identified issues



Photo 1

Notate what the issue is and what needs to be repaired

Small tear in liner above existing extrusion weld, needs to be extrusion welded

Take photo of repair



Photo 2



Photo 3

Description of repair work

Tear taped and sandbagged upon discovery and later extrusion welded

Date and time of repair (within 2 hours)

3 Mar 2026 11:20 AM PST

Are further permanent repairs required?

No

Date and Time of final repair (if necessary)

3 Mar 2026 2:21 PM PST

Instability under the cover

Are there any anomalous (unusual or unexpected) areas of cover damage or deformation that may indicate underlying instability?

No

Are there any signs of a downslope tension crack at the top of the slope or bulging at or near the toe of the slope?

No

Is there any movement of the equipment that vertically penetrates the cover (e.g., tilting)?

No

4050 - Geosynthetic Cover Inspection

4 Mar 2026 / Tom Roe

Complete

Flagged items

0

Conducted on

4 Mar 2026 9:48 AM PST

Prepared by

Tom Roe

Identification of Issues

Identified Issue

Identified Issue 1

Are there any issues with the geosynthetic cover?

No



Photo 1



Photo 2



Photo 3



Photo 4

Instability under the cover

Are there any anomalous (unusual or unexpected) areas of cover damage or deformation that may indicate underlying instability?

No

Are there any signs of a downslope tension crack at the top of the slope or bulging at or near the toe of the slope?

No

Is there any movement of the equipment that vertically penetrates the cover (e.g., tilting)?

No

4050 - Geosynthetic Cover Inspection

5 Mar 2026 / John Boucher

Complete

Flagged items

0

Conducted on

5 Mar 2026 7:07 AM PST

Prepared by

John Boucher

Identification of Issues

Identified Issue

Identified Issue 1


Are there any issues with the geosynthetic cover?

Yes

Date and Time Issue Found

5 Mar 2026 12:22 PM PST

Grid Location



Grid Number

180

Take photo of identified issues



Photo 1



Photo 2

Notate what the issue is and what needs to be repaired

Liner torn, needs to be patched and extrusion welded

Take photo of repair



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7

Description of repair work

Liner tears taped and sandbagged upon discovery

Date and time of repair (within 2 hours)

5 Mar 2026 12:28 PM PST

Are further permanent repairs required?

Yes

Permanent repairs are scheduled for 3/11/26

Date and Time of final repair (if necessary)

Identified Issue 2


Are there any issues with the geosynthetic cover?

Yes

Date and Time Issue Found

5 Mar 2026 12:32 PM PST

Grid Location



Grid Number

180

Take photo of identified issues



Photo 8

Notate what the issue is and what needs to be repaired

Liner torn. Needs to be patched and extrusion welded

Take photo of repair

Description of repair work

Due to safety concerns in the area tape was not able to be placed over tears upon discovery

Date and time of repair (within 2 hours)

Are further permanent repairs required?

Yes

Permanent repairs are scheduled for 3/11/26

Date and Time of final repair (if necessary)

Instability under the cover

Are there any anomalous (unusual or unexpected) areas of cover damage or deformation that may indicate underlying instability?

No

Are there any signs of a downslope tension crack at the top of the slope or bulging at or near the toe of the slope?

No

Is there any movement of the equipment that vertically penetrates the cover (e.g., tilting)?

No

4050 - Geosynthetic Cover Inspection

6 Mar 2026 / John Boucher

Complete

Flagged items	0
Conducted on	6 Mar 2026 7:29 AM PST
Prepared by	John Boucher

Identification of Issues

Identified Issue

Identified Issue 1

Are there any issues with the geosynthetic cover?

No



Photo 1



Photo 2



Photo 3



Photo 4

Instability under the cover

Are there any anomalous (unusual or unexpected) areas of cover damage or deformation that may indicate underlying instability?

No

Are there any signs of a downslope tension crack at the top of the slope or bulging at or near the toe of the slope?

No

Is there any movement of the equipment that vertically penetrates the cover (e.g., tilting)?

No

4050 - Geosynthetic Cover Inspection

7 Mar 2026 / John Boucher

Complete

Flagged items

0

Conducted on

7 Mar 2026 7:54 AM PST

Prepared by

John Boucher

Identification of Issues

Identified Issue

Identified Issue 1

Are there any issues with the geosynthetic cover?

No



Photo 1



Photo 2



Photo 3



Photo 4

Instability under the cover

Are there any anomalous (unusual or unexpected) areas of cover damage or deformation that may indicate underlying instability?

No

Are there any signs of a downslope tension crack at the top of the slope or bulging at or near the toe of the slope?

No

Is there any movement of the equipment that vertically penetrates the cover (e.g., tilting)?

No

March 9, 2026

Mr. Kevin Green
Chiquita Canyon Landfill
29201 Henry Mayo Drive
Castaic, California 91384

FEBRUARY 2026 FISSURE AND TENSION CRACK MONITORING SUMMARY
CHIQUITA CANYON LANDFILL
CASTAIC, CALIFORNIA

Dear Mr. Green:

This monthly summary report was prepared by Geo-Logic Associates, Inc. (GLA) to summarize the monitoring and tracking of fissures and tension cracks that was performed at the Chiquita Canyon Landfill (Landfill) between February 1 and February 28, 2026, in accordance with Milestone 2B of the Local Enforcement Agency's (LEA) June 6, 2024 Compliance Order, formerly referred to as Mitigation Measure #2B. This summary was prepared in accordance with Chiquita Canyon, LLC's (Chiquita) April 16, 2024 Second Revised Written Plan (Second Revised Written Plan) to document and track cover issues and is associated with Milestone 2B.

FEBRUARY OBSERVATIONS

Chiquita conducts daily monitoring of the soil cover for fissures and tension cracks and of the geomembrane-covered area for damage or evidence of possible instability. The cracks and fissures that were observed in February 2026 are summarized in Table 1. Table 2 summarizes the daily observations performed in geomembrane-covered areas in February 2026. Chiquita repaired all the cracks identified in Table 1 and all the small geomembrane tears identified in Table 2.

As indicated in these tables, no evidence of instability was reported in the soil-covered areas or the geomembrane-covered areas. The cracks and fissures summarized in Table 1 were reviewed with respect to the criteria for "significant" as that term is defined in Chiquita's Second Revised Written Plan.¹ As shown in this table, no cracks or fissures

¹ Pursuant to the Second Revised Written Plan, a "significant" fissure or tension crack is one that (1) is 100 feet or longer in length; (2) has a horizontal offset of 0.5 inches or more when the fissure/crack is at least 50 feet in length; or (3) has a vertical offset of 0.5 inches or more when the fissure/crack is at least 50 feet in length or there are multiple fissures/cracks oriented in the same direction. The classification of a crack or fissure as "significant" for purposes of this summary does not mean that there is a concern for

that potentially met these criteria were observed in February. Field logs note that an approximately 3 ft by 3 ft “crack” with “large” horizontal offset was observed on February 24, 2026 in Grid 196. The logs further indicate that the feature is an erosion depression containing an approximately 1-ft-long crack at the bottom. Based on review of the photographs, it is GLA’s opinion that this condition is associated with surface erosion and does not provide evidence of slope instability.

All the cracks identified in Table 1 were repaired. Cross sections that compare January 28, 2026 and February 25, 2026 topography are shown in Figures 2A through 2E. The locations of these cross sections are shown in Figure 1. The sections show no significant differences in slope or evidence of instability between the January 2026 and February 2026 profiles, which is consistent with the observational records summarized in Tables 1 and 2.

GRID TRENDS

Monitoring in May, June, and December 2024 and in June, July, August, September, and October 2025 documented cracks potentially meeting the definition of “significant”, as that term is defined in Chiquita’s Second Revised Written Plan, in the following grids:

- **Grid 183.** On May 23, 2024, a 65-ft tension crack with 0.5–2 in. horizontal offset (“small”) was observed. It was repaired by track-walking, and no further cracking was reported in subsequent May and June 2024 inspections. The grid has since been geomembrane-covered, with no evidence of instability observed from July 2024 through February 2026.
- **Grid 151.** Cracking was noted on May 20 and 28, 2024. A June 19, 2024 inspection confirmed multiple cracks within a 15 ft x 35 ft area, including one with >4 in. horizontal offset (“large”) and 0.5–2 in. vertical offset (“small”). On July 2, 2024, an additional non-significant crack with similar offsets was observed and repaired. This grid has since been geomembrane-covered and there has been no evidence of instability from August 2024 through February 2026.
- **Grid 180.** On June 3, 2024, a 60-ft crack with “small” horizontal offset was observed. The feature was not present in subsequent June 2024 monitoring. The grid has been geomembrane-covered, with no evidence of instability observed through February 2026.
- **Grid 152.** On June 24, 2024, a 55-ft crack with “small” horizontal offset was observed. No cracking was reported in this grid in subsequent inspections until

slope instability or that the Landfill’s containment system is compromised. The criteria were established for comparison purposes only.

- more than a year later. On July 30, 2025, a 10 ft x 5 ft area of cracks with “medium” horizontal and “extra small” vertical offsets was documented, classified as nonsignificant, and repaired. This grid is geomembrane-covered, and there has been no evidence of instability through February 2026.
- **Grid 146.** A 55-ft crack with “medium” horizontal and “extra-small” vertical offsets was documented and repaired on December 4, 2024. Additional minor cracks with “medium” to “large” horizontal offsets were identified and repaired in May and June 2025. On July 8, 2025, a 75-ft-long crack with “small” horizontal and “extra-small” vertical offsets was observed across the Grid 146/147 boundary and repaired. Two minor cracks were noted later in July, one in August, and five in September 2025; all were repaired. In October 2025, one potentially “significant” and two minor cracks were documented and subsequently repaired by soil placement and track-walking. One non-significant crack with “large” displacement was identified in November 2025 and was repaired. This grid was partially covered at the beginning of January 2026 and was completely covered by geomembrane by the end of January. No cracking was observed in the exposed portions of the grid in December 2025, January 2026, or February 2026.
 - **Grid 147.** A 100-ft crack with “large” horizontal and “medium” vertical offsets was documented and repaired on June 23, 2025. On July 8, 2025, a 75-ft crack spanning Grids 146 and 147 with “small” horizontal and “extra-small” vertical offsets was observed and repaired. Later July inspections identified three minor cracks with “medium” to “large” offsets; all were repaired. In August 2025, one 65-ft crack and several localized cracks or small settlement-related “collapse” features were documented and repaired. Five additional minor cracks were observed and repaired in September. In October 2025, two potentially “significant” cracks within Grid 147 and one spanning Grids 147–148 were documented, along with three minor cracks. All October features were repaired by soil placement and track-walking. One non-significant crack with “large” displacement was identified in November 2025 and was repaired. One non-significant crack with “small” horizontal offset and “extra small” vertical offset was identified in the exposed portion of the grid in December 2025 and was repaired. This grid was partially covered at the beginning of January 2026 and was completely covered by geomembrane by the end of January. Non-significant cracking was observed in the exposed portion of the grid on January 19, 2026 or in February 2026.
 - **Grid 164.** On September 12, 2025, potentially “significant” cracking was observed in Grid 164 based on the presence of an approximately 40-ft x 50-ft area

containing multiple intersecting cracks, the longest of which was about 50 ft. The horizontal offset (width) of the crack(s) was identified as “large,” the vertical offset (height) of the crack(s) was identified as “extra small”, and the orientation of the crack(s) was identified as northeast-to-southwest. No slope-stability concerns were noted in this grid at the time of observation, and the cracks were repaired. Approximately 50 percent of this grid is now covered by the geomembrane. No cracking was documented in exposed portions of Grid 164 in the October 2025 through December 2026 field records. Non-significant cracking was documented in the grid on January 20, 2026. No cracking was observed in this grid in February 2026.

CONCLUSIONS

As summarized in Table 1, no potentially significant cracks or crack fissures were identified in February 2026, and the field logs provide no evidence of slope instability. Please let me know if you have any questions regarding the information in this report.

Very truly yours,

Geo-Logic Associates, Inc.


Richard A. Mitchell, PG, CEG
Principal Engineering Geologist



Table 1
SUMMARY OF FEBRUARY 2026 FISSURE AND TENSION CRACK OBSERVATIONS
Chiquita Canyon Landfill

DATE	INSPECTOR	GRID	LOCATION	TYPE	LENGTH (ft)	AREA (ft x ft)	HORIZONTAL OFFSET	VERTICAL OFFSET	ORIENTATION	LATITUDE	LONGITUDE	REPAIRED	INDICATIONS OF SLOPE STABILITY CONCERNS
2/2/2026	Tom Roe		No Cracks Found	N/A									No
2/3/2026	Tom Roe		No Cracks Found	N/A									No
2/4/2026	Tom Roe		No Cracks Found	N/A									No
2/5/2026	John Boucher	198	Top Deck South	Linear	4		Extra Small	Extra Small	EW	34.432302	-118.648694	Yes	No
2/5/2026	John Boucher	83	Top Deck South	Linear	11		Extra Small	Extra Small	EW	34.435019	-118.644912	Yes	No
2/6/2026	John Boucher	83	Top Deck South	Area		11x16	Small	Extra Small	EW	34.434194	-118.646038	Yes	No
2/7/2026	John Boucher		No Cracks Found	N/A									No
2/9/2026	Tom Roe		No Cracks Found	N/A									No
2/10/2026	Tom Roe		No Cracks Found	N/A									No
2/11/2026	John Boucher		No Cracks Found	N/A									No
2/12/2026	Nancy Bahena		No Cracks Found	N/A									No
2/13/2026	John Boucher		No Cracks Found	N/A									No
2/16/2026	Tom Roe		No Cracks Found	N/A									No
2/17/2026	Tom Roe		No Cracks Found	N/A									No
2/18/2026	Tom Roe		No Cracks Found	N/A									No
2/19/2026	John Boucher		No Cracks Found	N/A									No
2/20/2026	John Boucher		No Cracks Found	N/A									No
2/21/2026	John Boucher		No Cracks Found	N/A									No
2/23/2026	Tom Roe		No Cracks Found	N/A									No
2/24/2026	Tom Roe	196	Top Deck South	Area		3x3	Large	Extra Small	NE	34.432093	-118.647844	Yes	No
2/25/2026	Tom Roe		No Cracks Found	N/A									No
2/26/2026	John Boucher		No Cracks Found	N/A									No
2/27/2026	John Boucher		No Cracks Found	N/A									No
2/28/2026	John Boucher		No Cracks Found	N/A									No

HORIZONTAL CRACK DEFINITIONS

Extra Small <0.5-in Width
 Small 0.5-in to 2-in Width
 Medium 2-in to 4-in Width
 Large >4-in Width

VERTICAL CRACK DEFINITIONS

Extra Small <0.5-in Height
 Small 0.5-in to 2-in Height
 Medium 2-in to 4-in Height
 Large >4-in Height

Pursuant to the Second Revised Written Plan, a "significant" fissure or tension crack is one that (1) is 100 feet or longer in length; (2) has a horizontal offset of 0.5 inches or more when the fissure/crack is at least 50 feet in length; or (3) has a vertical offset of 0.5 inches or more when the fissure/crack is at least 50 feet in length or there are multiple fissures/cracks oriented in the same direction. The classification of a crack or fissure as "significant" for purposes of this summary does not mean that there is a concern for slope instability or that the Landfill's containment system is compromised. The criteria were established for comparison purposes only.

NOTES:




1. 2/24/2026 observation was an approximately 3 ft x 3 ft erosion depression with an approximately 1 ft long crack at the bottom.

Table 2
SUMMARY OF FEBRUARY 2026 GEOMEMBRANE COVER OBSERVATIONS
Chiquita Canyon Landfill

DATE	ISSUES OR CONCERNS			
	Issue Identified	Evidence of Underlying Deformation	Tension Cracks at Top of Slope or Bulging at Toe of Slope	Vetical Deformation of Infrastructure Such as Wells or Probes
2/2/2026	Yes ^{1,2,3,4,5,6}	No	No	No
2/3/2026	Yes ⁷	No	No	No
2/4/2026	No	No	No	No
2/5/2026	No	No	No	No
2/6/2026	No	No	No	No
2/7/2026	No	No	No	No
2/9/2026	Yes ⁸	No	No	No
2/10/2026	No	No	No	No
2/11/2026	Yes ⁹	No	No	No
2/12/2026	No	No	No	No
2/13/2026	No	No	No	No
2/16/2026	No	No	No	No
2/17/2026	No	No	No	No
2/18/2026	No	No	No	No
2/19/2026	No	No	No	No
2/20/2026	No	No	No	No
2/21/2026	No	No	No	No
2/23/2026	Yes ^{10,11}	No	No	No
2/24/2026	Yes ^{12,13}	No	No	No
2/25/2026	No	No	No	No
2/26/2026	No	No	No	No
2/27/2026	No	No	No	No
2/28/2026	No	No	No	No

FEBRUARY 2026 NOTES:

1. A hole where a pole was removed in Grid 184 needs to be patched and repaired. Hole was taped and sandbagged on discovery and the area was covered with soil. This area is scheduled to be covered with new EVOH liner.
2. A hole in the liner in Grid 170 needs to be patched and extrusion welded. The hole was taped and sandbagged on discovery and was later patched and extrusion welded.
3. A tear in the liner in Grid 152 needs to be patched and extrusion welded. The hole was taped and sandbagged on discovery and was later patched and extrusion welded.
4. A hole in the liner in Grid 167 needs to be patched and extrusion welded. The hole was taped and sandbagged on discovery and later extrusion welded.
5. A hole in the liner in Grid 165 needs to be patched and extrusion welded. The hole was taped and sandbagged on discovery and later extrusion welded.
6. Two small tears in the liner in Grid 166 need to be extrusion welded. The tears were taped and sandbagged on discovery and later extrusion welded.
7. A hole in the liner in Grid 168 needs to be patched and extrusion welded. The hole was taped and sandbagged on discovery and later extrusion welded.
8. Tear in liner in Grid 200 Needs to be patched and extrusion welded. The tear was patched and welded on 2/10/2026.
9. Small tear in liner in Grid 169 needs to be patched and extrusion welded. The tear was taped and sandbagged on discovery and then patched and extrusion welded.
10. Tear in liner seam in Grid 145 needs to be patched and extrusion welded. Tears were taped and sandbagged on discovery. Permanent repairs scheduled for 3/2/2026.
11. Tear in liner in Grid 200 needs to be patched and extrusion welded. Tear taped on discovery. Permanent repairs scheduled for 3/2/2026.
12. Tear in liner in Grid 146 needs to be patched and extrusion welded. Tear taped and sandbagged on discovery. Permanent repairs scheduled for 3/2/2026.
13. Two tears in liner in Grid 147 need to be extrusion welded. Tears taped and sandbagged on discovery. Permanent repairs scheduled for 3/2/2026.



This drawing has not been published but rather has been prepared by Geo-Logic Associates, Inc. for use by the client named in the title block, solely in respect of the construction operation, and maintenance of the facility named in the title block. Geo-Logic Associates, Inc. shall not be liable for the use of this drawing on any other facility or for any other purpose.

ISSUED FOR REVIEW
 REFERENCE AERIAL TOPO BASED ON FEBRUARY 25, 2026 AERIAL SURVEY PROVIDED BY PROPELLER

REV. NO.	DATE	DESCRIPTION	APPROVED BY

DATE OF ISSUE: **MARCH 2026**
 DESIGNED BY: **R MITCHELL**
 CAD DESIGN BY: **L PADILLA**
 CHECKED BY: **R MITCHELL**
 APPROVED BY: **R MITCHELL**



Geo-Logic ASSOCIATES
 2777 EAST GUASTI ROAD
 SUITE 1
 ONTARIO, CA 91761
 (909) 626-2282
 www.geo-logic.com


CHIQUITA CANYON
A Waste Connections Company
 29201 HENRY MAYO DRIVE
 CASTAIC, CA 91384

FEBRUARY 2026 MONITORING SUMMARY
 CHIQUITA CANYON LANDFILL
 COUNTY OF LOS ANGELES, CA
 MONITORING GRID

FIG NO. **01**
 PROJECT NO. **RM22.1077**

PA\SITES\CHIQUITA_CYN_LF_MONITORING_SUMMARY\FIGURES\RM22-1077-COL-MS-FIG 1-(2026-03-09).DWG March 9, 2026 - 10:21 AM BY: GJA-USER

P:\SITES\CHIQUITA CYN LF\MONITORING SUMMARY\FIGURES\RM22.1077-CCL-MS-FIG 2A-2E-(2026-03-09).DWG March 9, 2026 - 10:51 AM BY: GLA-USER



LEGEND:

- SUBGRADE
- TOPO 2026-01-28
- TOPO 2026-02-25








FIGURE 2A

WESTERN SLOPE CROSS SECTION A
FEBRUARY 2026 MONITORING SUMMARY
CHIQUITA CANYON LANDFILL
COUNTY OF LOS ANGELES, CA



DRAWN BY: LP/RM | DATE: MARCH 2026 | JOB NO.: RM22.1077

P:\SITES\CHIQUITA CYN LF\MONITORING SUMMARY\FIGURES\RM22.1077-CCL-MS-FIG 2A-2E-(2026-03-09).DWG March 9, 2026 - 10:51 AM BY: GLA-USER



LEGEND:

- ▬ SUBGRADE
- ▬ TOPO 2026-01-28
- ▬ TOPO 2026-02-25








FIGURE 2B

WESTERN SLOPE CROSS SECTION B
FEBRUARY 2026 MONITORING SUMMARY
CHIQUITA CANYON LANDFILL
COUNTY OF LOS ANGELES, CA



DRAWN BY: LP/RM | DATE: MARCH 2026 | JOB NO.: RM22.1077

P:\SITES\CHIQUITA CYN LF\MONITORING SUMMARY\FIGURES\RM22.1077-CCL-MS-FIG 2A-2E-(2026-03-09).DWG March 9, 2026 - 10:50 AM BY: GLA-USER



LEGEND:

- SUBGRADE
- TOPO 2026-01-28
- TOPO 2026-02-25








FIGURE 2C

WESTERN SLOPE CROSS SECTION C
FEBRUARY 2026 MONITORING SUMMARY
CHIQUITA CANYON LANDFILL
COUNTY OF LOS ANGELES, CA




DRAWN BY: LP/RM DATE: MARCH 2026 JOB NO.: RM22.1077

P:\SITES\CHIQUITA CYN LF\MONITORING SUMMARY\FIGURES\RM22.1077-CCL-MS-FIG 2A-2E-(2026-03-09).DWG March 9, 2026 - 10:50 AM BY: GLA-USER



LEGEND:

-  SUBGRADE
-  TOPO 2026-01-28
-  TOPO 2026-02-25








FIGURE 2D

WESTERN SLOPE CROSS SECTION D
FEBRUARY 2026 MONITORING SUMMARY
CHIQUITA CANYON LANDFILL
COUNTY OF LOS ANGELES, CA



DRAWN BY: LP/RM | DATE: MARCH 2026 | JOB NO.: RM22.1077

P:\SITES\CHIQUITA CYN LF\MONITORING SUMMARY\FIGURES\RM22.1077-CCL-MS-FIG 2A-2E-(2026-03-09).DWG March 9, 2026 - 10:50 AM BY: GLA-USER



LEGEND:

- SUBGRADE
- TOPO 2026-01-28
- TOPO 2026-02-25









FIGURE 2E

WESTERN SLOPE CROSS SECTION E
FEBRUARY 2026 MONITORING SUMMARY
CHIQUITA CANYON LANDFILL
COUNTY OF LOS ANGELES, CA



DRAWN BY: LP/RM | DATE: MARCH 2026 | JOB NO.: RM22.1077

Chiquita Canyon Landfill -Isopach



February 04, 2026 Survey Image. February 04, 2026 vs. February 25, 2026