
From: Matt Breuer <Matt.Breuer@WasteConnections.com>
Sent: Friday, May 29, 2026 2:25 PM
To: Baitong Chen; Nathaniel Dickel; Christina Ojeda
Cc: Sarah Phillips; WILLIAM.HALEY@WasteConnections.com; McGuire, Christopher@DTSC; Zmily, Zanalee@DTSC; Eric Morofuji
Subject: Chiquita Canyon Landfill – Case No. 6177-4: Leak Report (Condition 27(e))

All,

In accordance with Condition 27(e) of the Stipulated Order for Abatement in Case No. 6177-4, based on its current knowledge of the event, Chiquita Canyon, LLC (Chiquita) provides the following report detailing a leak of characteristically hazardous leachate associated with Group A, well number CV-114, in Grid 145.

(1) the date and time of the leak or spill;

- The leak was discovered on May 27, 2026, at approximately 1:15 p.m.

(2) area designation inspected;

- Characteristically hazardous leachate leaked from a wellhead associated with well number CV-114 in Grid 145. No liquid from the leak entered the stormwater channel or either stormwater basin.

(3) the name of the person that discovered the leak or spill;

- Nancy Rodriguez

(4) written acknowledgement that they did, or did not, take corrective action with rationale for these actions;

- Upon discovering the leak, Chiquita personnel inserted a vacuum hose into the well casing to remove the accumulated liquid and contain the leak.

(5) a root cause analysis on why and how the leak or spill occurred;

- Based on Chiquita's current knowledge, it appears that the leak was caused by a failed wellhead, which allowed liquid to escape from the well casing, resulting in the observed leak. Chiquita attributes this leak to mechanical equipment failure.

(6) the estimated quantity of the leak or spill;

- Chiquita conservatively estimates that up to 2 gallons of characteristically hazardous leachate leaked.

(7) corrective actions to clean and/or remove the leak or spill;

- In addition to the measures discussed above, the wellhead was removed, replaced, bolted, and fully sealed by Chiquita personnel. Cleanup commenced immediately and was completed within approximately 1 hour.

(8) corrective actions implemented or to be implemented, including an estimated timeline, to prevent future recurrence;

- Chiquita replaced the wellhead and secured it by bolting and fully sealing the connection to prevent future leaks. In addition, Chiquita will continue to inspect equipment, perform maintenance, and implement appropriate corrective actions as needed.

(9) the type of affiliation of the operator involved in the root cause;

- No individuals were involved in the root cause of this leak.

(10) whether any individuals involved in the root cause had previously received training on applicable operations to avoid leaks or spills; and

- No individuals were involved in the root cause of this leak; however, Chiquita personnel have been trained on applicable operations to avoid leaks and spills.

(11) the number of times individuals involved in the root cause had previously been involved in the root cause of a leachate leak or spill.

- No individuals were involved in the root cause of the leak.

Matt Breuer, PE

Region Environmental Manager

Waste Connections - Western Region

425-414-2903 (mobile)