



June 2, 2026

Via E-Mail

Karen Gork
Chief Environmental Health Specialist
Los Angeles County Department of Public Health
Local Enforcement Agency
Environmental Programs Division
5050 Commerce Drive,
Baldwin Park, California 91706
KGork@ph.lacounty.gov

Re: Chiquita Canyon, LLC's Weekly Report on the Documentation and Tracking of Cover Issues

Dear Ms. Gork:

In accordance with the Local Enforcement Agency's ("LEA") May 2, 2024 letter approving Chiquita's April 16, 2024 Second Revised Written Plan for Documenting and Tracking Cover Issues ("Second Revised Written Plan"), the LEA's May 29, 2024 letter, and the LEA's June 6, 2024 Compliance Order, Chiquita presents the enclosed report for documenting and tracking cover issues for the week of May 25, 2026 to May 30, 2026. Please note that May 25, 2026 was a federal holiday (Memorial Day), and therefore no inspections were conducted on that day.

Please contact me if you have any questions regarding this matter.

Regards,

Matt Breuer
Region Environmental Manager
Chiquita Canyon

Attachment: June 2, 2026 Weekly Cover Issues Report
cc: Mark Como, Department of Public Health
Eric Morofuji, Department of Public Health

Fissures and Tension Cracks

4050 - Chiquita Reaction Area Tracking of Fissures and Tension Cracks

26 May 2026 / Tom Roe

Complete

Conducted on

26 May 2026 9:56 AM PDT

Prepared by

Tom Roe

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks
1

Fissure or Tension Crack Found?

Yes

Using the attached image, annotate all areas where inspectors identified a fissure or tension crack.



Grid Location

160.161

Date and Time Found

26 May 2026 10:04 AM PDT

Image of Fissure/Tension Crack



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5

Length of crack (ft) or area containing multiple cracks (ft x ft)

30ft x 55ft

No single crack 50ft or more in length

Horizontal Offset (width)

Small 0.5-2" in width

Vertical Offset (height)

Extra small <0.5" in height

Orientation (direction)

N to S

Location

Castaic CA 91384
United States
(34.433107063109446,
-118.64757821770812)

Was Fissure or Crack fixed? If yes, add photo and description of repairs performed

Yes



Photo 6

Date and time of repairs	26 May 2026 10:42 AM PDT
Description of repairs	Cracks were track walked.
Instability	
Are there any indications of slope stability concerns?	No

4050 - Chiquita Reaction Area Tracking of Fissures and Tension Cracks

27 May 2026 / Tom Roe

Complete

Conducted on

27 May 2026 2:15 PM PDT

Prepared by

Tom Roe

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks
1

Fissure or Tension Crack Found?

No

Grid 160



Photo 1

Instability

Are there any indications of slope stability concerns?

No

4050 - Chiquita Reaction Area Tracking of Fissures and Tension Cracks

28 May 2026 / John Boucher

Complete

Conducted on

28 May 2026 7:06 AM PDT

Prepared by

John Boucher

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks
1

Fissure or Tension Crack Found?

No

Grid 198



Photo 1

Instability

Are there any indications of slope stability concerns?

No

4050 - Chiquita Reaction Area Tracking of Fissures and Tension Cracks

29 May 2026 / John Boucher

Complete

Conducted on

29 May 2026 7:17 AM PDT

Prepared by

John Boucher

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks
1

Fissure or Tension Crack Found?

No

Grid 164



Photo 1

Instability

Are there any indications of slope stability concerns?

No

4050 - Chiquita Reaction Area Tracking of Fissures and Tension Cracks

30 May 2026 / John Boucher

Complete

Conducted on

30 May 2026 7:37 AM PDT

Prepared by

John Boucher

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks

Chiquita Reaction Area Tracking of Fissures and Tension Cracks
1

Fissure or Tension Crack Found?

No

Grid 163



Photo 1

Instability

Are there any indications of slope stability concerns?

No

Settlement

The bi-weekly drone flyover was not conducted this week. The drone data from the next flyover event will be included in the next weekly report.

Geosynthetic Cover

4050 - Geosynthetic Cover Inspection

26 May 2026 / Tom Roe

Complete

Flagged items	0
Conducted on	26 May 2026 8:43 AM PDT
Prepared by	Tom Roe

Identification of Issues

Identified Issue

Identified Issue 1

Are there any issues with the geosynthetic cover?

Yes

Date and Time Issue Found

26 May 2026 8:45 AM PDT

Grid Location



Grid Number

188

Take photo of identified issues



Photo 1



Photo 2

Notate what the issue is and what needs to be repaired

Two tears in liner to be patched/extrusion welded.

Take photo of repair



Photo 3



Photo 4



Photo 5



Photo 6

Description of repair work

Tears taped upon discovery.

Date and time of repair (within 2 hours)

26 May 2026 8:57 AM PDT

Are further permanent repairs required?

No

Date and Time of final repair (if necessary)

26 May 2026 12:36 PM PDT

Instability under the cover

Are there any anomalous (unusual or unexpected) areas of cover damage or deformation that may indicate underlying instability?

No

Are there any signs of a downslope tension crack at the top of the slope or bulging at or near the toe of the slope?

No

Is there any movement of the equipment that vertically penetrates the cover (e.g., tilting)?

No

4050 - Geosynthetic Cover Inspection

27 May 2026 / Tom Roe

Complete

Flagged items

0

Conducted on

27 May 2026 9:44 AM PDT

Prepared by

Tom Roe

Identification of Issues

Identified Issue

Identified Issue 1

Are there any issues with the geosynthetic cover?

Yes

Date and Time Issue Found

27 May 2026 12:59 PM PDT

Grid Location



Grid Number

208

Take photo of identified issues



Photo 1



Photo 2



Photo 3



Photo 4

Notate what the issue is and what needs to be repaired

Multiple tears in close proximity to each other need to be patched/extrusion welded.

Take photo of repair



Photo 5



Photo 6



Photo 7



Photo 8

Description of repair work	Tears taped upon discovery. Extrusion welded on 5/28/26
Date and time of repair (within 2 hours)	27 May 2026 1:19 PM PDT
Are further permanent repairs required?	No
Date and Time of final repair (if necessary)	28 May 2026 12:00 PM PDT
Instability under the cover	
Are there any anomalous (unusual or unexpected) areas of cover damage or deformation that may indicate underlying instability?	No
Are there any signs of a downslope tension crack at the top of the slope or bulging at or near the toe of the slope?	No
Is there any movement of the equipment that vertically penetrates the cover (e.g., tilting)?	No

4050 - Geosynthetic Cover Inspection

28 May 2026 / John Boucher

Complete

Flagged items

0

Conducted on

28 May 2026 7:06 AM PDT

Prepared by

John Boucher

Identification of Issues

Identified Issue

Identified Issue 1

Are there any issues with the geosynthetic cover?

Yes

Date and Time Issue Found

28 May 2026 8:37 AM PDT

Grid Location



Grid Number

181

Take photo of identified issues



Photo 1



Photo 2

Notate what the issue is and what needs to be repaired

Two small tears in close proximity.
Need to be patched and extrusion welded

Take photo of repair



Photo 3



Photo 4



Photo 5



Photo 6

Description of repair work

Taped and sandbagged upon discovery, then patched and extrusion welded

Date and time of repair (within 2 hours)

28 May 2026 8:39 AM PDT

Are further permanent repairs required?

No

Date and Time of final repair (if necessary)

29 May 2026 11:03 AM PDT

Identified Issue 2

Are there any issues with the geosynthetic cover?

Yes

Date and Time Issue Found

28 May 2026 9:17 AM PDT

Grid Location



Grid Number

145

Take photo of identified issues



Photo 7

Notate what the issue is and what needs to be repaired

Small hole in weld. Needs to be re
extrusion welded

Take photo of repair



Photo 8



Photo 9



Photo 10

Description of repair work

Taped and sandbagged upon discovery and later extrusion welded.

Date and time of repair (within 2 hours)

28 May 2026 9:31 AM PDT

Are further permanent repairs required?

No

Date and Time of final repair (if necessary)

29 May 2026 10:03 AM PDT

Identified Issue 3


Are there any issues with the geosynthetic cover?

Yes

Date and Time Issue Found

28 May 2026 9:30 AM PDT

Grid Location



Grid Number

146

Take photo of identified issues



Photo 11

Notate what the issue is and what needs to be repaired

Liner torn. Needs to be patched and extrusion welded

Take photo of repair



Photo 12



Photo 13



Photo 14

Description of repair work

Taped and sandbagged upon discovery then patched and extrusion welded

Date and time of repair (within 2 hours)

28 May 2026 9:33 AM PDT

Are further permanent repairs required?

No

Date and Time of final repair (if necessary)

29 May 2026 10:06 AM PDT

Instability under the cover

Are there any anomalous (unusual or unexpected) areas of cover damage or deformation that may indicate underlying instability?

No

Are there any signs of a downslope tension crack at the top of the slope or bulging at or near the toe of the slope?

No

Is there any movement of the equipment that vertically

No

penetrates the cover (e.g., tilting)?



4050 - Geosynthetic Cover Inspection

29 May 2026 / John Boucher

Complete

Flagged items

0

Conducted on

29 May 2026 7:17 AM PDT

Prepared by

John Boucher

Identification of Issues

Identified Issue

Identified Issue 1

Are there any issues with the geosynthetic cover?

No



Photo 1



Photo 2



Photo 3



Photo 4

Instability under the cover

Are there any anomalous (unusual or unexpected) areas of cover damage or deformation that may indicate underlying instability?

No

Are there any signs of a downslope tension crack at the top of the slope or bulging at or near the toe of the slope?

No

Is there any movement of the equipment that vertically penetrates the cover (e.g., tilting)?

No

4050 - Geosynthetic Cover Inspection

30 May 2026 / John Boucher

Complete

Flagged items

0

Conducted on

30 May 2026 7:37 AM PDT

Prepared by

John Boucher

Identification of Issues

Identified Issue

Identified Issue 1

Are there any issues with the geosynthetic cover?

No



Photo 1



Photo 2



Photo 3



Photo 4

Instability under the cover

Are there any anomalous (unusual or unexpected) areas of cover damage or deformation that may indicate underlying instability?

No

Are there any signs of a downslope tension crack at the top of the slope or bulging at or near the toe of the slope?

No

Is there any movement of the equipment that vertically penetrates the cover (e.g., tilting)?

No