
From: Matt Breuer <Matt.Breuer@WasteConnections.com>
Sent: Friday, June 5, 2026 8:03 PM
To: Baitong Chen; Nathaniel Dickel; Christina Ojeda
Cc: Sarah Phillips; WILLIAM.HALEY@WasteConnections.com; McGuire, Christopher@DTSC; Zmily, Zanalee@DTSC; Eric Morofuji
Subject: Re: Chiquita Canyon Landfill – Case No. 6177-4: Leak Report (Condition 27(e))

All,
After continued investigation, Chiquita hereby revises and resubmits the following Condition 27(e) report, which was previously submitted on May 29, 2026.

In accordance with Condition 27(e) of the Stipulated Order for Abatement in Case No. 6177-4, based on its current knowledge of the event, Chiquita Canyon, LLC (Chiquita) provides the following report detailing an anticipated and actively managed pressurized leachate release (PLR) involving characteristically hazardous leachate associated with the East Perimeter from well number H-1803N located northeast of Grid 185.

(1) the date and time of the leak or spill;

- The PLR occurred on May 28, 2026, at approximately 12:00 p.m.

(2) area designation inspected;

- The PLR involved characteristically hazardous leachate associated with the East Perimeter from well number H-1803N located northeast of Grid 185. Liquid from the PLR remained in the containment and did not reach the stormwater channel or either stormwater basin.

(3) the name of the person that discovered the leak or spill;

- Chris Fear

(4) written acknowledgement that they did, or did not, take corrective action with rationale for these actions;

- Because the potential for a PLR was foreseeable during the well work, Chiquita personnel proactively implemented preventative measures before commencing the work to minimize the likelihood and potential extent of a PLR. Chiquita personnel also placed containment measures at the well site before commencing work. After the PLR occurred, personnel promptly inserted a vacuum hose into the well casing to remove the accumulated liquid and contain the flow of leachate.

(5) a root cause analysis on why and how the leak or spill occurred;

- There is no attributable error for this event. The potential for a PLR was anticipated and was being actively managed.

(6) the estimated quantity of the leak or spill;

- Chiquita conservatively estimates that well H-1803N released approximately 10 gallons of characteristically hazardous leachate associated with the East Perimeter during the PLR.

(7) corrective actions to clean and/or remove the leak or spill;

- In addition to the measures discussed above, the wellhead was removed and replaced. Cleanup commenced immediately and was completed within approximately 30 minutes.

(8) corrective actions implemented or to be implemented, including an estimated timeline, to prevent future recurrence;

- Chiquita personnel replaced the wellhead and secured it by bolting and fully sealing the wellhead, which will prevent future releases.

(9) the type of affiliation of the operator involved in the root cause;

- Chiquita personnel were involved in the well work associated with this PLR; however, the PLR resulted from conditions associated with the wellhead rather than from personnel error.

(10) whether any individuals involved in the root cause had previously received training on applicable operations to avoid leaks or spills; and

- The Chiquita personnel involved in the event had previously received training on applicable operational procedures to help prevent leaks and spills and to minimize both the likelihood and potential extent of a PLR. The occurrence of a PLR that was anticipated as a potential outcome of the work does not, by itself, indicate a failure to exercise reasonable care, particularly where preventative and containment measures were implemented in advance to minimize the risk and extent of the release.

(11) the number of times individuals involved in the root cause had previously been involved in the root cause of a leachate leak or spill.

- As noted above, although Chiquita personnel were involved in the well work associated with this PLR, the PLR resulted from conditions associated with the wellhead rather than from personnel error.

Matt Breuer, PE

Region Environmental Manager

Waste Connections - Western Region

425-414-2903 (mobile)

From: Matt Breuer <Matt.Breuer@WasteConnections.com>

Sent: Friday, May 29, 2026 4:04 PM

To: Baitong Chen <bchen@aqmd.gov>; Nathaniel Dickel <ndickel@aqmd.gov>; Christina Ojeda <cojeda@aqmd.gov>

Cc: Sarah Phillips <Sarah.Phillips@WasteConnections.com>; Bill Haley <WILLIAM.HALEY@WasteConnections.com>; McGuire, Christopher@DTSC <christopher.mcguire@dtsc.ca.gov>; Zmily, Zanalee@DTSC <zanalee.zmily@dtsc.ca.gov>; Eric Morofuji <emorofuji@ph.lacounty.gov>

Subject: Chiquita Canyon Landfill – Case No. 6177-4: Leak Report (Condition 27(e))

All,

In accordance with Condition 27(e) of the Stipulated Order for Abatement in Case No. 6177-4, based on its current knowledge of the event, Chiquita Canyon, LLC (Chiquita) provides the following report detailing a leak of characteristically hazardous leachate associated with the East Perimeter from well number H-1803N located northeast of Grid 185.

(1) the date and time of the leak or spill;

- The leak was discovered on May 28, 2026, at approximately 12:00 p.m.

(2) area designation inspected;

- Characteristically hazardous leachate associated with the East Perimeter leaked from well number H-1803N located northeast of Grid 185. Liquid from the leak did not reach the stormwater channel or either stormwater basin.

(3) the name of the person that discovered the leak or spill;

- Chris Fear.

(4) written acknowledgement that they did, or did not, take corrective action with rationale for these actions;

- Upon discovering the leak, personnel inserted a vacuum hose into the well casing to remove the accumulated liquid and contain the flow of leachate.

(5) a root cause analysis on why and how the leak or spill occurred;

- Based on Chiquita's current knowledge, it appears that the leak was caused by a failed wellhead, which allowed liquid to escape from the well casing, resulting in the observed leak. This occurred during preventive maintenance. Chiquita attributes this leak to mechanical equipment failure.

(6) the estimated quantity of the leak or spill;

- Chiquita conservatively estimates that approximately 10 gallons of characteristically hazardous leachate leaked.

(7) corrective actions to clean and/or remove the leak or spill;

- In addition to the measures discussed above, the wellhead was removed and replaced. Cleanup commenced immediately and was completed within approximately 30 minutes.

(8) corrective actions implemented or to be implemented, including an estimated timeline, to prevent future recurrence;

- Chiquita replaced the wellhead and secured it by bolting and fully sealing the connection to prevent future leaks. In addition, Chiquita will continue to inspect equipment, perform maintenance, and implement appropriate corrective actions as needed.

(9) the type of affiliation of the operator involved in the root cause;

- No individuals were involved in the root cause of this leak.

(10) whether any individuals involved in the root cause had previously received training on applicable operations to avoid leaks or spills; and

- No individuals were involved in the root cause of this leak; however, Chiquita personnel have been trained on applicable operations to avoid leaks and spills.

(11) the number of times individuals involved in the root cause had previously been involved in the root cause of a leachate leak or spill.

- No individuals were involved in the root cause of this leak.

Matt Breuer, PE

Region Environmental Manager

Waste Connections - Western Region

425-414-2903 (mobile)