



CHIQUITA CANYON
A Waste Connections Company

June 12, 2026

California Regional Water Quality Control Board
Los Angeles Region
320 W. 4th Street, Suite 200
Los Angeles, California 90013
ATTN: Information Technology Unit

**Subject: Leachate Seep Report
Chiquita Canyon Landfill
WDRs Order No. R4-2018-0172
File No. 67-020**

Pursuant to MRP No. CI-6231 Section B.3.a, Chiquita Canyon, LLC (“Chiquita”) hereby provides the following information regarding a seep discovered on June 5, 2026, during which approximately 0.5 gallons of characteristically non-hazardous leachate associated with Group C entered the stormwater channel but did not reach either sedimentation basin. This is a conservative estimate based on visual observations by Chiquita staff. Chiquita maintains appropriate response materials, including fully stocked spill kits, and has trained staff on site to respond to seeps to prevent liquids from entering the stormwater system.

i. Map - A map showing the location(s) of seepage.

The seep was observed in grid 93, as indicated in **Attachment A**.

ii. Flow rate - An estimate of the flow rate.

The seep had a very low flow rate.

iii. Description - A description of the nature of the discharge (e.g., all pertinent observations and analyses).

On June 5, 2026, at approximately 7:14 a.m., Chiquita personnel observed a small seep that entered the stormwater channel in grid 93. The seep had a very low flow. Approximately 0.5 gallons of liquid from the seep entered the stormwater channel but did not reach either sedimentation basin. The small amount of liquid came from a joint in the concrete of the stormwater channel. The liquid was dark brown in color with low viscosity and traveled with a very low flow rate.

iv. Location – Location of sample(s) collected for laboratory analysis, as appropriate.

No sampling was conducted for this seep.

June 12, 2026

Page 2 of 2

v. Corrective measures – approved (or proposed for consideration) by the Regional Board Executive Officer.



Upon discovery, Chiquita constructed a check dam in the stormwater channel to contain the liquid and pressure washed the affected concrete while applying vacuum to ensure the proper collection of all wash water. Chiquita also applied silicone to the area to seal the concrete joint where the seep occurred. This work was completed by approximately 10 a.m. that same day. No additional seeps have been observed in this area since cleanup was completed.

If you should have any questions regarding this report, please do not hesitate to contact me at (661) 257-3655.

Sincerely,
Chiquita Canyon, LLC

Matt Breuer
Environmental Manager
Chiquita Canyon

Attachments: Attachment A – Grid Map of Seep Location



LEGEND

- CV-01 ACTIVE VERTICAL WELLS ABOVE GRADE
- CV-02 ACTIVE VERTICAL WELLS WITH HOV TEMP
- CV-03 ACTIVE VERTICAL WELLS WITH HOV O2
- CV-04 ACTIVE VERTICAL WELL WITH ELEVATED H2S
- CV-05 ACTIVE VERTICAL WELLS BELOW GRADE
- C-01 ACTIVE HORIZONTAL WELLS
- C-02 ACTIVE HORIZONTAL WELLS WITH HOV TEMP
- C-03 ACTIVE HORIZONTAL WELLS WITH ELEVATED H2S
- C-04 ACTIVE HORIZONTAL WELLS WITH STINGERS
- DW-1 DETECTION WELLS
- ▲ PZ-1 PIEZOMETER
- ▲ CV-30 REMOTE VERTICAL WELL HEADS
- ▲ CV-31 REMOTE VERTICAL WELL HEADS WITH HOV O2
- ▲ CV-32 REMOTE VERTICAL WELL HEADS WITH HOV TEMP
- GP-0 GAS PROBE
- ✕ VALVE
- ⊕ VALVE VAULT
- ⊙ AC ACTIVATED CARBON VESSEL
- LC-5 SAMPLE POINT

NOTES:

1. EXISTING TOPOGRAPHY PLAN IS FROM PROPELLER DATA. THE TOPOGRAPHY DATA IS BASED ON AUGUST 11, 2023.
2. EXISTING GCCS AS-BUILTS DATED 10-18-23.

DATE		REVISION							
NO.									
LANDFILL GAS COLLECTION SYSTEM WITH SEM MAP									
CHIQUITA CANYON LANDFILL					29201 HENRY MAYO DRIVE, CASTAIC, CALIFORNIA 91384				
SCS ENGINEERS ENVIRONMENTAL CONSULTANTS									
1 of 1									