

From: Sarah Phillips <Sarah.Phillips@WasteConnections.com>
Sent: Wednesday, January 21, 2026 1:25 PM
To: bchen@aqmd.gov; ndickel@aqmd.gov; cojeda@aqmd.gov
Cc: Ryan.Rietzel@WasteConnections.com; Neal, Erin@DTSC; Zmily, Zanalee@DTSC
Subject: Chiquita Canyon Landfill – Case No. 6177-4: Leak Report (Condition 27(e))

All,

In accordance with Condition 27(e) of the Stipulated Order for Abatement in Case No. 6177-4, based on its current knowledge of the event, Chiquita Canyon, LLC (Chiquita) provides the following report detailing a leak from a third-party tanker truck of treated non-hazardous leachate associated with tank number L13 (70-72), manifest number CCL01641-A.

(1) the date and time of the leak or spill;

1. The leak was discovered on January 19, 2026, at approximately 12:50 a.m.

(2) area designation inspected;

- Treated non-hazardous leachate associated with tank number L13 (70-72), manifest number CCL01641-A, leaked from a third-party tanker truck near the scale house adjacent to grid 141. Liquid from the leak did not enter the stormwater channel or either stormwater basin.

(3) the name of the person that discovered the leak or spill;

1. Robert Negrete

(4) written acknowledgement that they did, or did not, take corrective action with rationale for these actions;

1. Upon discovering the leak, the leak was stopped and absorbent was applied to the area impacted by the leak.

(5) a root cause analysis on why and how the leak or spill occurred;

1. Based on Chiquita's current knowledge, it appears that the leak was caused by a broken weld on the third-party tanker trailer. Chiquita attributes this leak to third-party equipment malfunction.

(6) the estimated quantity of the leak or spill;

1. Chiquita conservatively estimates that approximately 10 gallons of treated non-hazardous leachate associated with tank number L13 (70-72), manifest number CCL01641-A, leaked from the third-party tanker truck.

(7) corrective actions to clean and/or remove the leak or spill;

- In addition to the measures discussed above, Chiquita personnel promptly removed the soiled absorbent and placed it into a container for proper disposal. Cleanup commenced immediately and was completed within approximately 30 minutes.

(8) corrective actions implemented or to be implemented, including an estimated timeline, to prevent future recurrence;

1. Chiquita personnel will update the applicable existing Standard Operating Procedures and continue to inspect tanker trucks for leaks prior to leaving the site.

(9) the type of affiliation of the operator involved in the root cause;

1. No individuals were involved in the root cause of this leak.

(10) whether any individuals involved in the root cause had previously received training on applicable operations to avoid leaks or spills; and

1. No individuals were involved in the root cause of this leak; however, Chiquita personnel have been trained on the applicable operations to avoid leaks and spills.

(11) the number of times individuals involved in the root cause had previously been involved in the root cause of a leachate leak or spill.

- To Chiquita's knowledge, no individuals involved in the root cause of this leak have previously been involved in the root cause of a leachate leak or spill.

Sarah Phillips

248.930.2779

Corporate Compliance Manager

Waste Connections

