

Archived: Friday, February 6, 2026 9:13:24 AM
From: [Matt Breuer](#)
Sent: Thursday, February 5, 2026 6:10:19 PM
To: bchen@aqmd.gov
Cc: [Sarah Phillips](#)
Subject: Chiquita Canyon Landfill – Case No. 6177-4: Spill Report (Condition 27(e))
Importance: Normal
Sensitivity: None

[EXTERNAL SENDER: Use caution with links/attachments]

All,

In accordance with Condition 27(e) of the Stipulated Order for Abatement in Case No. 6177-4, based on its current knowledge of the event, Chiquita Canyon, LLC (Chiquita) provides the following report detailing a spill of characteristically hazardous condensate from well number CV-2311 in grid 184.

(1) the date and time of the leak or spill;

0. The spill was discovered on February 4, 2026, at approximately 4:15 p.m.

(2) area designation inspected;

- Characteristically hazardous condensate from well number CV-2311 spilled in grid 184 onto dirt on the liner. Leachate from the spill did not enter the stormwater channel or either stormwater basin.

(3) the name of the person that discovered the leak or spill;

0. Anthony Braz

(4) written acknowledgement that they did, or did not, take corrective action with rationale for these actions;

- Upon discovering the spill, the impacted dirt was promptly removed.

(5) a root cause analysis on why and how the leak or spill occurred;

0. Based on Chiquita's current knowledge, while a contractor was working on a condensate line that had been disconnected for repair, the containment pan collecting condensate was inadvertently tipped over when an unexpected shift in the line occurred, causing liquid to spill onto dirt on the liner. Chiquita attributes this spill to third-party operator error.

(6) the estimated quantity of the leak or spill;

1. Chiquita conservatively estimates that less than 2 gallons of characteristically hazardous condensate spilled onto dirt on the liner.

(7) corrective actions to clean and/or remove the leak or spill;

- In addition to the measures discussed above, the impacted dirt was placed into a container for proper disposal. Cleanup commenced immediately and was completed within approximately 15 minutes.

(8) corrective actions implemented or to be implemented, including an estimated timeline, to prevent future recurrence;

0. Chiquita discussed situational awareness and the proper use of secondary containment during repair activities with the relevant third-party contractor.

(9) the type of affiliation of the operator involved in the root cause;

0. A third-party contractor was involved in the root cause of this spill.

(10) whether any individuals involved in the root cause had previously received training on applicable operations to avoid leaks or spills; and

1. Chiquita does not provide training to its contractors; however, appropriate practices to minimize the potential for leaks and spills is regularly discussed. Chiquita personnel have been trained on applicable operations to avoid leaks and spills.

(11) the number of times individuals involved in the root cause had previously been involved in the root cause of a leachate leak or spill.

- Chiquita has been unable to determine whether this third-party contractor has previously been involved in the root cause of a leachate leak or spill.

Matt Breuer, PE

Region Environmental Manager

Waste Connections - Western Region

425-414-2903 (mobile)