

Archived: Wednesday, February 11, 2026 2:07:42 PM
From: [Matt Breuer](#)
Sent: Saturday, February 7, 2026 7:46:46 AM
To: bchen@aqmd.gov
Cc: [Sarah Phillips](#)
Subject: Chiquita Canyon Landfill – Case No. 6177-4: Leak Report (Condition 27(e))
Importance: Normal
Sensitivity: None

[EXTERNAL SENDER: Use caution with links/attachments]

All,

In accordance with Condition 27(e) of the Stipulated Order for Abatement in Case No. 6177-4, based on its current knowledge of the event, Chiquita Canyon, LLC (Chiquita) provides the following report detailing a leak of characteristically hazardous leachate associated with Group A from a pipe related to well number CV-2428 in grid 178.

(1) the date and time of the leak or spill;

0. The leak was discovered on February 5, 2026, at approximately 8:00 a.m.

(2) area designation inspected;

- Characteristically hazardous leachate associated with Group A leaked from a pipe related to well number CV-2428 onto dirt on the geomembrane cover in grid 178. Liquid from the leak did not enter the stormwater channel or either stormwater basin.

(3) the name of the person that discovered the leak or spill;

0. Anthony Braz

(4) written acknowledgement that they did, or did not, take corrective action with rationale for these actions;

0. Upon discovering the leak, the pipe weld was immediately repaired to stop the flow of liquid.

(5) a root cause analysis on why and how the leak or spill occurred;

0. Based on Chiquita's current knowledge, the leak appears to have occurred when work on other sections of the line generated vibrations that inadvertently compromised the pipe weld, resulting in a leak. Chiquita attributes this leak to mechanical equipment failure.

(6) the estimated quantity of the leak or spill;

1. Chiquita conservatively estimates that less than 5 gallons of characteristically hazardous leachate associated with Group A leaked onto dirt on the geomembrane cover.

(7) corrective actions to clean and/or remove the leak or spill;

- In addition to the measures discussed above, the impacted dirt was removed and placed into a container for proper disposal. Cleanup commenced immediately and was completed within approximately 30 minutes.

(8) corrective actions implemented or to be implemented, including an estimated timeline, to prevent future recurrence;

- Chiquita will continue to inspect piping and implement appropriate corrective action as needed in accordance with the Stipulated Order.

(9) the type of affiliation of the operator involved in the root cause;

0. No individuals were involved in the root cause of this leak.

(10) whether any individuals involved in the root cause had previously received training on applicable operations to avoid leaks or spills; and

1. No individuals were involved in the root cause of this leak; however, Chiquita personnel has been trained on applicable operations to avoid leaks and spills.

(11) the number of times individuals involved in the root cause had previously been involved in the root cause of a leachate leak or spill.

- No individuals were involved in the root cause of this leak.

Waste Connections - Western Region
425-414-2903 (mobile)