
From: Matt Breuer <Matt.Breuer@WasteConnections.com>
Sent: Saturday, March 28, 2026 9:46 AM
To: Baitong Chen; Nathaniel Dickel; Christina Ojeda
Cc: Sarah Phillips; McGuire, Christopher@DTSC; Zmily, Zanalee@DTSC; Eric Morofuji
Subject: Chiquita Canyon Landfill – Case No. 6177-4: Leak Report (Condition 27(e))

[EXTERNAL SENDER: Use caution with links/attachments]

All,

In accordance with Condition 27(e) of the Stipulated Order for Abatement in Case No. 6177-4, based on its current knowledge of the event, Chiquita Canyon, LLC (Chiquita) provides the following report detailing a leak of approximately 0.5 gallons of characteristically hazardous leachate associated with well number CV-2303 onto the liner in grid 176.

(1) the date and time of the leak or spill;

1. The leak was discovered on March 26, 2026, at approximately 9:34 a.m.

(2) area designation inspected;

- Characteristically hazardous leachate associated with well number CV-2303 leaked onto the liner in grid 176. Liquid from the leak did not reach the stormwater channel or either stormwater basin.

(3) the name of the person that discovered the leak or spill;

1. Dennis Kennedy

(4) written acknowledgement that they did, or did not, take corrective action with rationale for these actions;

- No liquid was actively flowing upon discovering the leak; however, the standing liquid on the liner was promptly cleaned up.

(5) a root cause analysis on why and how the leak or spill occurred;

- Based on Chiquita's current knowledge, the leak appears to have resulted from a compromised gasket on the well. Chiquita attributes this leak to mechanical equipment failure.

(6) the estimated quantity of the leak or spill;

- Chiquita conservatively estimates that approximately 0.5 gallons of characteristically hazardous leachate leaked onto the liner.

(7) corrective actions to clean and/or remove the leak or spill;

- In addition to the measures discussed above, the liner was immediately pressure washed while applying vacuum to ensure the collection of all wash water and standing liquid. Cleanup was completed within approximately 1.5 hours.

(8) corrective actions implemented or to be implemented, including an estimated timeline, to prevent future recurrence;

- Chiquita will continue to inspect equipment, perform maintenance, and implement appropriate corrective actions as needed.

(9) the type of affiliation of the operator involved in the root cause;

- No individuals were involved in the root cause of this leak.

(10) whether any individuals involved in the root cause had previously received training on applicable operations to avoid leaks or spills; and

- No individuals were involved in the root cause of this leak; however, Chiquita personnel have been trained on applicable operations to avoid leaks and spills.

(11) the number of times individuals involved in the root cause had previously been involved in the root cause of a leachate leak or spill.

- No individuals were involved in the root cause of this leak.

Matt Breuer, PE

Region Environmental Manager

Waste Connections - Western Region

425-414-2903 (mobile)