
From: Matt Breuer <Matt.Breuer@WasteConnections.com>
Sent: Saturday, April 25, 2026 8:54 AM
To: Baitong Chen; Nathaniel Dickel; Christina Ojeda
Cc: Sarah Phillips; McGuire, Christopher@DTSC; Zmily, Zanalee@DTSC; Eric Morofuji
Subject: Chiquita Canyon Landfill – Case No. 6177-4: Leak Report (Condition 27(e))

[EXTERNAL SENDER: Use caution with links/attachments]

All,

In accordance with Condition 27(e) of the Stipulated Order for Abatement in Case No. 6177-4, based on its current knowledge of the event, Chiquita Canyon, LLC (Chiquita) provides the following report detailing a leak of approximately 0.25 gallons of characteristically hazardous leachate from a discharge hose associated with well number CV-24138 located in grid 201.

(1) the date and time of the leak or spill;

1. The leak was discovered on April 23, 2026, at approximately 9:30 a.m.

(2) area designation inspected;

- Characteristically hazardous leachate leaked from a 1-inch discharge hose associated with well number CV-24138 in grid 201. Liquid from the leak did not reach the stormwater channel or either stormwater basin.

(3) the name of the person that discovered the leak or spill;

1. Derek Biasi.

(4) written acknowledgement that they did, or did not, take corrective action with rationale for these actions;

- Upon discovering the leak, the related force main was immediately closed to stop the flow of liquid. The hose was then emptied of residual liquid and disconnected.

(5) a root cause analysis on why and how the leak or spill occurred;

- Based on Chiquita's current knowledge, the leak appears to have been caused by a compromised 1-inch discharge hose. Chiquita attributes this leak to mechanical equipment failure.

(6) the estimated quantity of the leak or spill;

- Chiquita conservatively estimates that approximately 0.25 gallons of characteristically hazardous leachate leaked.

(7) corrective actions to clean and/or remove the leak or spill;

- In addition to the measures discussed above, the well and related wellhead were promptly wiped to remove the residual liquid. The affected sediment was then removed and placed into a container for proper disposal. Cleanup commenced immediately and was completed within approximately 20 minutes.

(8) corrective actions implemented or to be implemented, including an estimated timeline, to prevent future recurrence;

- Chiquita replaced the compromised discharge hose to prevent similar leaks. Chiquita will continue to inspect equipment, perform maintenance, and implement appropriate corrective actions as needed.

(9) the type of affiliation of the operator involved in the root cause;

- No individuals were involved in the root cause of this leak.

(10) whether any individuals involved in the root cause had previously received training on applicable operations to avoid leaks or spills; and

- No individuals were involved in the root cause of this leak; however, Chiquita personnel have been trained on applicable operations to avoid leaks and spills.

(11) the number of times individuals involved in the root cause had previously been involved in the root cause of a leachate leak or spill.

- No individuals were involved in the root cause of this leak.

Matt Breuer, PE

Region Environmental Manager

Waste Connections - Western Region

425-414-2903 (mobile)