



June 30, 2026

***Via E-Mail***

Baitong Chen, Air Quality Engineer, [bchen@aqmd.gov](mailto:bchen@aqmd.gov)  
Nathaniel Dickel, Senior Air Quality Engineer, [ndickel@aqmd.gov](mailto:ndickel@aqmd.gov)  
Christina Ojeda, Air Quality Inspector, [cojeda@aqmd.gov](mailto:cojeda@aqmd.gov)  
South Coast Air Quality Management District  
21865 East Copley Drive  
Diamond Bar, California 91765-4182

**Re: Chiquita Canyon, LLC's Weekly Leachate Inspection Report for Stipulated Order for Abatement (Case No. 6177-4), Condition 27(c)**

All:

Pursuant to Condition 27(c) of the Stipulated Order for Abatement with the South Coast Air Quality Management District in Case No. 6177-4, as modified on June 3, 2026 (the "Order"), Chiquita Canyon, LLC ("Chiquita") hereby submits the enclosed compilation of the twice daily leachate seep inspection logs for the period of June 22, 2026 through June 28, 2026. No leachate seepage or pooling was observed at the Chiquita Canyon Landfill during these inspections.

During this reporting period, Chiquita also conducted and documented an expanded leachate seep inspection of the entire Main Canyon area on the afternoon of June 26, 2026, in accordance with the new Condition 27(b)(ii) of the Order. No leachate seepage or pooling was observed during that inspection, as reflected in the enclosed log for that afternoon. Consistent with modified Condition 27(c), this report also identifies any leachate seepage or pooling observed outside of the Condition 27(b) inspections during the reporting period.

Chiquita is continuing to monitor the previously reported containment area on the west side of the Landfill and to remove liquids, as necessary, using a vacuum truck. Chiquita and its consultants are also continuing to plan, design, and construct a soil buttress on the west side of the Landfill, adjacent to the prior "west slope toe drain project," in response to the continued extrusion of reacted material at certain preferential pathways that daylight on the west slope. The total approximate amount of leachate collected from the west side was 22,272 gallons between June 22 and June 28, 2026.

June 30, 2026

Page 2 of 2

Chiquita is also continuing to monitor the area between Grids 171 and 172, where previously reported seepage was observed. Chiquita currently plans to begin work on the installation of a new sump in that area in mid-July.

Please contact me if you have any questions regarding this matter.

Regards,

Matt Breuer  
Environmental Manager  
Chiquita Canyon

Attachment: Leachate Inspection Logs from June 22 – June 28, 2026

# 4050 - Chiquita Leachate Seep/Pooling Inspection

22 Jun 2026 / Tom Roe

Complete

**Conducted on**

22 Jun 2026 6:47 AM PDT

---

**Prepared by**

Tom Roe

---

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road. None of the seepage previously observed in this area or in Grids 171/172 was observed at the time of this inspection.

# 4050 - Chiquita Leachate Seep/Pooling Inspection

22 Jun 2026 / Tom Roe

Complete

**Conducted on**

22 Jun 2026 3:27 PM PDT

---

**Prepared by**

Tom Roe

---

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road. None of the seepage previously observed in this area or in Grids 171/172 was observed at the time of this inspection.

# 4050 - Chiquita Leachate Seep/Pooling Inspection

23 Jun 2026 / Tom Roe

Complete

**Conducted on**

23 Jun 2026 6:31 AM PDT

---

**Prepared by**

Tom Roe

---

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road. None of the seepage previously observed in this area or in Grids 171/172 was observed at the time of this inspection.

# 4050 - Chiquita Leachate Seep/Pooling Inspection

23 Jun 2026 / Tom Roe

Complete

**Conducted on**

23 Jun 2026 1:36 PM PDT

---

**Prepared by**

Tom Roe

---

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road. None of the seepage previously observed in this area or in Grids 171/172 was observed at the time of this inspection.

# 4050 - Chiquita Leachate Seep/Pooling Inspection

24 Jun 2026 / Tom Roe

Complete

**Conducted on**

24 Jun 2026 7:22 AM PDT

---

**Prepared by**

Tom Roe

---

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Grid 80. None of the seepage previously observed in this area, the Westside or in Grids 171/172 was observed at the time of this inspection.

# 4050 - Chiquita Leachate Seep/Pooling Inspection

24 Jun 2026 / Tom Roe

Complete

**Conducted on**

24 Jun 2026 3:04 PM PDT

---

**Prepared by**

Tom Roe

---

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road. None of the seepage previously observed in this area or in Grids 171/172 was observed at the time of this inspection.

# 4050 - Chiquita Leachate Seep/Pooling Inspection

25 Jun 2026 / John Boucher

Complete

**Conducted on**

25 Jun 2026 7:12 AM PDT

---

**Prepared by**

John Boucher

---

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road. None of the seepage previously observed in this area or in Grids 171/172 was observed at the time of this inspection

# 4050 - Chiquita Leachate Seep/Pooling Inspection

25 Jun 2026 / John Boucher

Complete

**Conducted on**

25 Jun 2026 2:31 PM PDT

---

**Prepared by**

John Boucher

---

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road. None of the seepage previously observed in this area or in Grids 171/172 was observed at the time of this inspection

# 4050 - Chiquita Leachate Seep/Pooling Inspection

26 Jun 2026 / John Boucher

Complete

**Conducted on**

26 Jun 2026 7:37 AM PDT

---

**Prepared by**

John Boucher

---

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road. None of the seepage previously observed in this area or in Grids 171/172 was observed at the time of this inspection

# 4050 - Chiquita Leachate Seep/Pooling Inspection

26 Jun 2026 / John Boucher

Complete

---

**Conducted on**

26 Jun 2026 1:20 PM PDT

Entire main canyon inspected for 27(b)(ii)

---

**Prepared by**

John Boucher

---

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road. None of the seepage previously observed in this area or in Grids 171/172 was observed at the time of this inspection

# 4050 - Chiquita Leachate Seep/Pooling Inspection

27 Jun 2026 / John Boucher

Complete

**Conducted on**

27 Jun 2026 8:01 AM PDT

---

**Prepared by**

John Boucher

---

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road. None of the seepage previously observed in this area or in Grids 171/172 was observed at the time of this inspection

# 4050 - Chiquita Leachate Seep/Pooling Inspection

27 Jun 2026 / John Boucher

Complete

**Conducted on**

27 Jun 2026 1:00 PM PDT

---

**Prepared by**

John Boucher

---

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road. None of the seepage previously observed in this area or in Grids 171/172 was observed at the time of this inspection

# 4050 - Chiquita Leachate Seep/Pooling Inspection

28 Jun 2026 / Tom Roe

Complete

**Conducted on**

28 Jun 2026 6:50 AM PDT

---

**Prepared by**

Tom Roe

---

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road. None of the seepage previously observed in this area or in Grids 171/172 was observed at the time of this inspection.

# 4050 - Chiquita Leachate Seep/Pooling Inspection

28 Jun 2026 / Tom Roe

Complete

**Conducted on**

28 Jun 2026 1:14 PM PDT

---

**Prepared by**

Tom Roe

---

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road. None of the seepage previously observed in this area or in Grids 171/172 was observed at the time of this inspection.