

Archived: Tuesday, September 22, 2026 9:15:27 AM
From: [Sarah Phillips](#)
Sent: Fri, 18 Sep 2026 18:10:42
To: [Baitong Chen](#)
Cc: [Matt Breuer](#)
Subject: Chiquita Canyon Landfill – Case No. 6177-4: Leak Report (Condition 27(e))
Importance: Normal
Sensitivity: None
Attachments:  [image.png](#)  [image.png](#)

All,

Consistent with reports provided under Condition 27(e) of the Stipulated Order for Abatement in Case No. 6177-4, based on its current knowledge of the event, Chiquita Canyon, LLC (Chiquita) provides the following report detailing a leak of approximately 2 cups of characteristically hazardous leachate associated with Group A from a well casing related to well number CV-2352 located in Grid 175.

This report is not compelled by Condition 27(e), as the leak is estimated at less than 1 gallon. Chiquita nevertheless provides this courtesy report in the interest of transparency and given ongoing reporting requests from other regulators.

(1) the date and time of the leak or spill;

- The leak was discovered on September 16, 2026, at approximately 7:40 a.m.

(2) area designation inspected;

- Characteristically hazardous leachate associated with Group A leaked from a well casing related to well number CV-2352 located in Grid 175. Liquid from the leak did not reach the stormwater channel or either stormwater basin.

(3) the name of the person that discovered the leak or spill;

- Tom Roe.

(4) written acknowledgement that they did, or did not, take corrective action with rationale for these actions;

- Upon discovering the leak, a containment tray was immediately placed by the well casing to capture the liquid. Absorbent was then applied to the affected area.

(5) a root cause analysis on why and how the leak or spill occurred;

- Based on Chiquita's current knowledge, it appears a compromised well casing caused the leak. Chiquita attributes this leak to mechanical equipment failure.

(6) the estimated quantity of the leak or spill;

- Chiquita conservatively estimates that approximately 2 cups of characteristically hazardous leachate associated with Group A leaked from the well casing.

(7) corrective actions to clean and/or remove the leak or spill;

- In addition to the measures discussed above, the soiled absorbent was placed into a container for proper disposal. Cleanup commenced immediately and was completed within approximately 10 minutes.

(8) corrective actions implemented or to be implemented, including an estimated timeline, to prevent future recurrence;

- Chiquita will continue to inspect equipment, perform preventative maintenance, and implement appropriate corrective actions as needed, and is evaluating the use of stainless steel components where appropriate to minimize the potential for similar leaks.

(9) the type of affiliation of the operator involved in the root cause;

- No individuals were involved in the root cause of this leak.

(10) whether any individuals involved in the root cause had previously received training on applicable operations to avoid leaks or spills; and

- No individuals were involved in the root cause of this leak; however, Chiquita routinely reviews spill- and-leak prevention practices with its contractors, and Chiquita personnel have been trained on applicable operations to avoid leaks and spills.

(11) the number of times individuals involved in the root cause had previously been involved in the root cause of a leachate leak or spill.

- No individuals were involved in the root cause of the leak.

Sarah Phillips

248.930.2779

Corporate Compliance Manager

Waste Connections

