


1/2 DIAMETER OF PIPE
OR 12" WHICHEVER IS
GREATER

COARSE AGGREGATE
6" DEEP

EARTH FILL COVERED BY
LARGE ANGULAR ROCK

FILTER FABRIC




CAPACITY OF PIPE CULVERTS
TOGETHER = BANK FULL FLOW

ELEVATION

COARSE AGGREGATE

FLOW

EARTH FILL COVERED BY
LARGE ANGULAR ROCK



25'
MINIMUM
TOP OF BANK

STREAM CHANNEL

25'
MINIMUM
TOP OF BANK

PLAN

MAINTENANCE NOTES:

1. INSPECT FILTRATION GEOTEXTILE, STONE AND PIPE(S) AFTER EACH SIGNIFICANT RAINFALL OF 1 INCHES OR GREATER, OVER A 24-HOUR PERIOD.
2. REPLACE GEOTEXTILE AND REPLENISH THE STONE WHEN THEY BECOME CONTAMINATED WITH SEDIMENT.
3. DAMAGED TEMPORARY PIPE(S) SHOULD BE REPAIRED OR REPLACED IMMEDIATELY.
4. REPLACE ANY CLASS B OR NO. 57 STONE THAT GETS DISLODGED OR DAMAGED.
5. CLEAN PIPE(S) IF CLOGGED WITH DEBRIS.



STANDARD TEMPORARY STREAM CROSSING