Archived: Monday, October 26, 2026 1:08:17 PM
From: Tessa.Lenz@WasteConnections.com
Sent: Fri, 23 Oct 2026 21:50:04
To: bchen@aqmd.gov
Cc: Sarah Phillips
Subject: Chiquita Canyon Landfill – Case No. 6177-4: Leak Report (Condition 27(e))
Importance: Normal
Sensitivity: None

All,

Consistent with reports provided under Condition 27(e) of the Stipulated Order for Abatement in Case No. 6177-4, based on its current knowledge of the event, Chiquita Canyon, LLC (Chiquita) provides the following report detailing a leak of 0.25 cups of characteristically non-hazardous leachate associated with Group C from well number CV-2689 located in Grid 39.

This report is not compelled by Condition 27(e), as the leak is estimated at less than 1 gallon. Chiquita nevertheless provides this courtesy report in the interest of transparency and given ongoing reporting requests from other regulators.
(1) the date and time of the leak or spill;

- The leak was discovered on October 21, 2026, at approximately 11:23 a.m.

(2) area designation inspected;

- Characteristically non-hazardous leachate associated with Group C leaked from well number CV-2689 in Grid 39. Liquid from the leak did not reach the stormwater channel or either stormwater basin.

(3) the name of the person that discovered the leak or spill;

- Tom Roe.

(4) written acknowledgement that they did, or did not, take corrective action with rationale for these actions;

- An absorbent wipe was used to clean the liquid that leaked from the wellhead onto the well stem. No liquid reached the ground.

(5) a root cause analysis on why and how the leak or spill occurred;

- Based on Chiquita's current knowledge, it appears that an encirclement clamp on the wellhead became loose, causing liquid to leak onto the well stem. Chiquita attributes this leak to mechanical equipment failure.

(6) the estimated quantity of the leak or spill;

- Chiquita conservatively estimates that less than 0.25 cups of characteristically non-hazardous leachate associated with Group C leaked.

(7) corrective actions to clean and/or remove the leak or spill;

- In addition to the measures discussed above, the absorbent wipe was properly disposed of in an appropriate container. Cleanup commenced immediately and was completed within approximately 30 minutes.

(8) corrective actions implemented or to be implemented, including an estimated timeline, to prevent future recurrence;

- The encirclement clamp was tightened to minimize the potential for similar leaks at this wellhead. Chiquita will also continue to inspect equipment, perform preventative maintenance, and implement appropriate corrective actions as needed to reduce the potential for similar leaks.

(9) the type of affiliation of the operator involved in the root cause;

- No individuals were involved in the root cause of this leak.

(10) whether any individuals involved in the root cause had previously received training on applicable operations to avoid leaks or spills; and

- No individuals were involved in the root cause of this leak; however, Chiquita routinely reviews spill- and-leak prevention practices with its contractors, and Chiquita personnel have been trained on applicable operations to avoid leaks and spills.

(11) the number of times individuals involved in the root cause had previously been involved in the root cause of a leachate leak or spill.

- No individuals were involved in the root cause of this leak.

Best Regards,

Tessa Lenz
Environmental Manager
Chiquita Canyon Landfill
Cell: (661) 812-2661
Waste Connections | 29201 Henry Mayo Dr. | Castaic, CA 91384
Connect With the Future © *www.wasteconnections.com*