Archived: Tuesday, November 10, 2026 10:14:36 AM
From: Tessa.Lenz@WasteConnections.com
Sent: Thu, 5 Nov 2026 16:24:31
To: bchen@aqmd.gov
Cc: Sarah Phillips
Subject: Chiquita Canyon Landfill – Case No. 6177-4: Leak Report (Condition 27(e))
Importance: Normal
Sensitivity: None

All,

Consistent with reports provided under Condition 27(e) of the Stipulated Order for Abatement in Case No. 6177-4, based on its current knowledge of the event, Chiquita Canyon, LLC (Chiquita) provides the following report detailing a leak of approximately 1 ounce of characteristically hazardous leachate associated with Group A from a threaded flange related to well number CV-2339 located in Grid 174.

This report is not compelled by Condition 27(e), as the leak is estimated at less than 1 gallon. Chiquita nevertheless provides this courtesy report in the interest of transparency and given ongoing reporting requests from other regulators.
(1) the date and time of the leak or spill;

- The leak was discovered on November 2, 2026, at approximately 11:20 a.m.

(2) area designation inspected;

- Characteristically hazardous leachate associated with Group A leaked from well number CV-2339 in Grid 174. Liquid from the leak did not reach the stormwater channel or either stormwater basin.

(3) the name of the person that discovered the leak or spill;

- Gage Hayes.

(4) written acknowledgement that they did, or did not, take corrective action with rationale for these actions;

- Upon discovering the leak, an encirclement clamp was installed on the well casing to stop the flow of liquid.

(5) a root cause analysis on why and how the leak or spill occurred;

- Based on Chiquita's current knowledge, the leak appears to have resulted from a compromised well gasket, causing liquid to leak from the threaded flange on the well casing. Chiquita attributes this leak to mechanical equipment failure.

(6) the estimated quantity of the leak or spill;

- Chiquita conservatively estimates that approximately 1 ounce of characteristically hazardous leachate associated with Group A leaked.

(7) corrective actions to clean and/or remove the leak or spill;

- In addition to the measures discussed above, an absorbent wipe was used to clean the liquid that leaked onto the well casing. No liquid reached the ground. Cleanup commenced immediately and was completed within approximately 20 minutes.

(8) corrective actions implemented or to be implemented, including an estimated timeline, to prevent future recurrence;

- Chiquita will continue to inspect equipment, perform preventative maintenance, and implement appropriate corrective actions as needed to reduce the potential for similar leaks.

(9) the type of affiliation of the operator involved in the root cause;

- No individuals were involved in the root cause of this leak.

(10) whether any individuals involved in the root cause had previously received training on applicable operations to avoid leaks or spills; and

- No individuals were involved in the root cause of this leak; however, Chiquita routinely reviews spill- and-leak prevention practices with its contractors, and Chiquita personnel have been trained on applicable operations to avoid leaks and spills.

(11) the number of times individuals involved in the root cause had previously been involved in the root cause of a leachate leak or spill.

- No individuals were involved in the root cause of this leak.

Best Regards,

Tessa Lenz
Environmental Manager
Chiquita Canyon Landfill
Cell: (661) 812-2661
Waste Connections | 29201 Henry Mayo Dr. | Castaic, CA 91384
Connect With the Future © *www.wasteconnections.com*