Archived: Tuesday, November 10, 2026 10:14:03 AM
From: Tessa.Lenz@WasteConnections.com
Sent: Sat, 7 Nov 2026 04:28:40
To: bchen@aqmd.gov
Cc: Sarah Phillips
Subject: Chiquita Canyon Landfill – Case No. 6177-4: Leak Report (Condition 27(e))
Importance: Normal
Sensitivity: None

All,

Consistent with reports provided under Condition 27(e) of the Stipulated Order for Abatement in Case No. 6177-4, based on its current knowledge of the event, Chiquita Canyon, LLC (Chiquita) provides the following report detailing a leak of approximately 0.25 cups of characteristically hazardous liquid associated with Group A from well number CV-2311 in Grid 184.

This report is not compelled by Condition 27(e), as the leak is estimated at less than 1 gallon. Chiquita nevertheless provides this courtesy report in the interest of transparency and given ongoing reporting requests from other regulators.

(1) the date and time of the leak or spill;

- The leak was discovered on November 5, 2026, at approximately 9:33 a.m.

(2) area designation inspected;

- Characteristically hazardous liquid associated with Group A leaked from well number CV-2311 in Grid 184. Liquid from the leak did not reach either stormwater basin.

(3) the name of the person that discovered the leak or spill;

- Tom Roe.

(4) written acknowledgement that they did, or did not, take corrective action with rationale for these actions;

- Upon discovering the leak, the bolts securing the well casing sleeve were tightened to stop the flow of liquid.

(5) a root cause analysis on why and how the leak or spill occurred;

- Based on Chiquita's current knowledge, the leak appears to have resulted from loose bolts on the well casing sleeve of well number CV-2311, allowing liquid to leak past the sleeve. Chiquita attributes this leak to mechanical equipment failure.

(6) the estimated quantity of the leak or spill;

- Chiquita conservatively estimates that approximately 0.25 cups of liquid leaked.

(7) corrective actions to clean and/or remove the leak or spill;

- In addition to the measures discussed above, the affected area was cleaned with absorbent wipes, which were then placed into a container for proper disposal. Cleanup was completed within approximately 20 minutes.

(8) corrective actions implemented or to be implemented, including an estimated timeline, to prevent future recurrence;

- Chiquita will continue to inspect equipment, perform maintenance, and implement appropriate corrective actions as needed.

(9) the type of affiliation of the operator involved in the root cause;

- No individuals were involved in the root cause of this leak.

(10) whether any individuals involved in the root cause had previously received training on applicable operations to avoid leaks or spills; and

- No individuals were involved in the root cause of this leak; however, Chiquita personnel have been trained on applicable operations to avoid leaks and spills.

(11) the number of times individuals involved in the root cause had previously been involved in the root cause of a leachate leak or spill.

- No individuals were involved in the root cause of this leak.

Best Regards,

Tessa Lenz
Environmental Manager
Chiquita Canyon Landfill
Cell: (661) 812-2661
Waste Connections | 29201 Henry Mayo Dr. | Castaic, CA 91384
Connect With the Future © *www.wasteconnections.com*