CHIQUITA CANYON
A Waste Connections Company

November 10, 2026

Via E-Mail

Baitong Chen, Air Quality Engineer, bchen@aqmd.gov
Nathaniel Dickel, Senior Air Quality Engineer, ndickel@aqmd.gov
Christina Ojeda, Air Quality Inspector, cojeda@aqmd.gov
South Coast Air Quality Management District
21865 East Copley Drive
Diamond Bar, California 91765-4182

Re: Chiquita Canyon, LLC's Weekly Leachate Inspection Report for Stipulated Order for Abatement (Case No. 6177-4), Condition 27(c)

All:

Pursuant to Condition 27(c) of the Stipulated Order for Abatement with the South Coast Air Quality Management District in Case No. 6177-4, as modified on October 28, 2026 (the "Order"), Chiquita Canyon, LLC ("Chiquita") hereby submits the enclosed compilation of the twice daily leachate seep inspection logs for the period of November 2, 2026 through November 8, 2026. No leachate seepage or pooling was observed at the Chiquita Canyon Landfill (the "Landfill") during the reporting period.

During this reporting period, Chiquita also conducted and documented an expanded leachate seep inspection of the entire Main Canyon area on the morning of November 3, 2026, in accordance with Condition 27(b)(ii) of the Order. No leachate seepage was observed during that inspection, as reflected in the enclosed inspection log for that morning. Consistent with modified Condition 27(c), this report also identifies any leachate seepage or pooling observed outside of the Condition 27(b) inspections during the reporting period. No leachate seepage or pooling was observed outside of those inspections during the reporting period.

Please contact me if you have any questions regarding this matter.

Regards,

Tessa Lenz

Tessa Lenz
Environmental Manager
Chiquita Canyon

Attachment: Leachate Seep/Pooling Inspection Logs from November 2 – November 8, 2026

4050 - Chiquita Leachate Seep/Pooling Inspection

2 Nov 2026 / John Boucher

Complete

Conducted on	2 Nov 2026 7:21 AM PST
Prepared by	John Boucher

Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?	No



Photo 1

Description of area in photo where there is no leachate seepage or pooling.	West side perimeter road

4050 - Chiquita Leachate Seep/Pooling Inspection

2 Nov 2026 / Tom Roe

Complete

Conducted on	2 Nov 2026 2:24 PM PST
Prepared by	Tom Roe

Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?	No




Photo 1

Description of area in photo where there is no leachate seepage or pooling.	North perimeter road.

4050 - Chiquita Leachate Seep/Pooling Inspection

3 Nov 2026 / John Boucher

Complete

Conducted on	3 Nov 2026 7:36 AM PST

Entire main canyon inspected for 27(b)(ii)

Prepared by	John Boucher

Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?	No



Photo 1

Description of area in photo where there is no leachate seepage or pooling.	Westside perimeter road

4050 - Chiquita Leachate Seep/Pooling Inspection

3 Nov 2026 / Tom Roe

Complete

Conducted on	3 Nov 2026 2:22 PM PST
Prepared by	Tom Roe

Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?	No



Photo 1

Description of area in photo where there is no leachate seepage or pooling.	North perimeter road.

4050 - Chiquita Leachate Seep/Pooling Inspection

4 Nov 2026 / John Boucher

Complete

Conducted on	4 Nov 2026 7:19 AM PST
Prepared by	John Boucher

Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?	No



Photo 1

Description of area in photo where there is no leachate seepage or pooling.	Westside perimeter road

4050 - Chiquita Leachate Seep/Pooling Inspection

4 Nov 2026 / Tom Roe

Complete

Conducted on	4 Nov 2026 2:05 PM PST
Prepared by	Tom Roe

Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?	No



Photo 1

Description of area in photo where there is no leachate seepage or pooling.	North perimeter road.

4050 - Chiquita Leachate Seep/Pooling Inspection

5 Nov 2026 / John Boucher

Complete

Conducted on	5 Nov 2026 7:16 AM PST
Prepared by	John Boucher

Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?	No



Photo 1

Description of area in photo where there is no leachate seepage or pooling.	Westside perimeter road

4050 - Chiquita Leachate Seep/Pooling Inspection

5 Nov 2026 / Tom Roe

Complete

Conducted on	5 Nov 2026 2:32 PM PST
Prepared by	Tom Roe

Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?	No



Photo 1

Description of area in photo where there is no leachate seepage or pooling.	North perimeter road.

4050 - Chiquita Leachate Seep/Pooling Inspection

6 Nov 2026 / John Boucher

Complete

Conducted on	6 Nov 2026 7:51 AM PST
Prepared by	John Boucher

Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?	No




Photo 1

Description of area in photo where there is no leachate seepage or pooling.	Westside perimeter road

4050 - Chiquita Leachate Seep/Pooling Inspection

6 Nov 2026 / John Boucher

Complete

Conducted on	6 Nov 2026 2:07 PM PST
Prepared by	John Boucher

Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?	No




Photo 1

Description of area in photo where there is no leachate seepage or pooling.	Northside perimeter road

4050 - Chiquita Leachate Seep/Pooling Inspection

7 Nov 2026 / Edwin De Leon

Complete

Conducted on	7 Nov 2026 6:43 AM PST
Prepared by	Edwin De Leon

Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?	No



Photo 1

Description of area in photo where there is no leachate seepage or pooling.	West perimeter road

4050 - Chiquita Leachate Seep/Pooling Inspection

7 Nov 2026 / Edwin De Leon

Complete

Conducted on	7 Nov 2026 1:52 PM PST
Prepared by	Edwin De Leon

Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?	No



Photo 1

Description of area in photo where there is no leachate seepage or pooling.	North westside perimeter road

4050 - Chiquita Leachate Seep/Pooling Inspection

8 Nov 2026 / Edwin De Leon

Complete

Conducted on	8 Nov 2026 6:50 AM PST
Prepared by	Edwin De Leon

Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?	No




Photo 1

Description of area in photo where there is no leachate seepage or pooling.	Westside perlterrimeter road

4050 - Chiquita Leachate Seep/Pooling Inspection

8 Nov 2026 / Edwin De Leon

Complete

Conducted on	8 Nov 2026 1:36 PM PST
Prepared by	Edwin De Leon

Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?	No



Photo 1

Description of area in photo where there is no leachate seepage or pooling.	Westside perimeter road