



Alteryx Automotive
17200 Laguna Canyon Road
Irvine, CA 92618
(888) 836-4274
Putting the data in your day-to-day drive!




DATE	2021-03-25	ORDER NO	10340	
NAME	Archibald Burhill			
ADDRESS	44926 Village Plaza			
CITY	Charleston	STATE	SC	
		COUNTRY	United States	
MAKE	Volkswagen	MODEL	Routan	
		YEAR	2011	
VIN	WAUTFAFH8BN538947		MECHANIC	William

QTY	PART NO	DESCRIPTION	SALES AMOUNT	TOTAL
5	UITZ-73458-TV	Ignition coil	\$714.23	\$3,571.15
1	DWMF-10239-YK	Knock sensor	\$379.44	\$379.44
6	BAXO-85367-QN	Thermostat	\$492.42	\$2,954.52
7	OXCT-05932-NJ	Fan blade	\$499.22	\$3,494.54
7	BGVF-38576-GB	Starter pinion	\$780.22	\$5,461.54
4	BXSL-78021-UF	Shift lever	\$859.11	\$3,436.44
7	RUHP-01578-LU	Alternator	\$179.91	\$1,259.37
TOTAL PARTS			\$3,904.55	\$20,557.00

DESCRIPTION OF WORK	NO. HOURS	LABOR RATE	TOTAL
Inspection	2	70	\$140.00
Parts Installation	11	150	\$1,650.00
TOTAL LABOR		220	\$1,790.00

I hereby authorize the above repair work to be done with the necessary material and grant permission to operate equipment for purpose of testing and inspection. An express mechanic's lien is acknowledged to secure the amount of repairs.	TOTAL PARTS	\$20,557.00
	TOTAL LABOR	\$1,790.00
	TAX	7.25%
	TOTAL	\$23,967.16

	2021-03-25
SIGNATURE	DATE