



Alteryx Automotive  
17200 Laguna Canyon Road  
Irvine, CA 92618  
(888) 836-4274  
*Putting the data in your day-to-day drive!*



DATE	2021-11-01	ORDER NO	56117
NAME	Leese Caban		
ADDRESS	95673 Kenwood Terrace		
CITY	Austin	STATE	TX
		COUNTRY	United States
MAKE	BMW	MODEL	X5
		YEAR	2011
VIN	2T3BFREV3FW441416	MECHANIC	Worf

QTY	PART NO	DESCRIPTION	SALES AMOUNT	TOTAL
2	VKNP-39174-OW	Spiral spring	\$452.53	\$905.06
4	MZUF-78205-SZ	Reservoir	\$195.80	\$783.20
2	XSOV-37086-UZ	A/C clutch	\$832.99	\$1,665.98
3	QXLS-09358-OK	Roof rack	\$420.63	\$1,261.89
3	GMFO-39186-EP	Roller bearing	\$432.04	\$1,296.12
TOTAL PARTS			\$2,333.99	\$5,912.25

DESCRIPTION OF WORK	NO. HOURS	LABOR RATE	TOTAL
Inspection	4	70	\$280.00
Parts Installation	3	150	\$450.00
TOTAL LABOR		220	\$730.00

I hereby authorize the above repair work to be done with the necessary material and grant permission to operate equipment for purpose of testing and inspection. An express mechanic's lien is acknowledged to secure the amount of repairs.	TOTAL PARTS	\$5,912.25
	TOTAL LABOR	\$730.00
	TAX	7.25%
	TOTAL	\$7,123.81

	2021-11-01
SIGNATURE	DATE