



Alteryx Automotive
17200 Laguna Canyon Road
Irvine, CA 92618
(888) 836-4274
Putting the data in your day-to-day drive!




DATE	2022-02-19	ORDER NO	89015	
NAME	Kendall Burcher			
ADDRESS	02033 Trailway Park			
CITY	Lake Charles	STATE	LA	
		COUNTRY	United States	
MAKE	Ford	MODEL	Crown Victoria	
		YEAR	2003	
VIN	WAUDN94F58N757896		MECHANIC	Jean-Luc

QTY	PART NO	DESCRIPTION	SALES AMOUNT	TOTAL
3	DLJB-32068-KR	gear shifter)	\$886.03	\$2,658.09
9	LMOC-27581-IX	Oil strainer	\$264.87	\$2,383.83
9	BHAF-26570-WR	Shoe web	\$200.78	\$1,807.02
3	JPQT-51873-LA	Brake shoe	\$875.54	\$2,626.62
8	HZJN-95602-KZ	Brake lining	\$897.03	\$7,176.24
2	GBZE-82093-UW	Pulley part	\$628.52	\$1,257.04
5	KEZI-60715-WX	Starter pinion	\$677.40	\$3,387.00
TOTAL PARTS			\$4,430.17	\$21,295.84

DESCRIPTION OF WORK	NO. HOURS	LABOR RATE	TOTAL
Inspection	3	70	\$210.00
Parts Installation	3	150	\$450.00
TOTAL LABOR		220	\$660.00

I hereby authorize the above repair work to be done with the necessary material and grant permission to operate equipment for purpose of testing and inspection. An express mechanic's lien is acknowledged to secure the amount of repairs.	TOTAL PARTS	\$21,295.84
	TOTAL LABOR	\$660.00
	TAX	7.25%
	TOTAL	\$23,547.64


SIGNATURE

2022-02-19
DATE