

**Archived:** Friday, May 23, 2025 9:55:43 AM

**From:** [Amanda Froman](#)

**Sent:** Mon, 19 May 2025 02:49:19

**To:** [Baitong Chen](#) [Nathaniel Dickel](#) [Christina Ojeda](#)

**Cc:** [Steve Cassulo](#) [Nicole Ward](#) [Kelly Kincella](#) [Kate Logan](#) [Neal](#), [Erin@DTSC.Zmily](mailto:Erin@DTSC.Zmily), [Zanalee@DTSC](mailto:Zanalee@DTSC)

**Subject:** Chiquita Canyon Landfill – Case No. 6177-4: Spill Report (Condition 27(e))

**Importance:** Normal

**Sensitivity:** None

---

**[EXTERNAL SENDER: Use caution with links/attachments]**

All,

In accordance with Condition 27(e) of the Stipulated Order for Abatement in Case No. 6177-4, Chiquita Canyon, LLC (Chiquita) provides the following report of a leachate spill, based on Chiquita's current knowledge of the event:

(1) the date and time of the leak or spill

0. 0. The spill was discovered on May 17, 2025, at approximately 1:30 a.m.

(2) area designation inspected

0. 0. Treated leachate spilled from a third-party haul truck onto the outbound scale outside of the scale house. The spill did not reach any stormwater channel or either stormwater basin.

(3) the name of the person that discovered the leak or spill

1. 1. Robert Aguilar

(4) written acknowledgement that they did, or did not, take corrective action with rationale for these actions

0. 0. Upon discovering the spill, absorbent was applied to the area.

(5) a root cause analysis on why and how the leak or spill occurred

0. 0. Based on Chiquita's current knowledge, it appears that as a third-party haul truck drove down the hill to the scale house and leveled out, the treated leachate spilled from a partially open bleeder valve onto the outbound scale outside the scale house.

(6) the estimated quantity of the leak or spill

1. 1. Chiquita conservatively estimates that approximately 20 gallons of treated leachate spilled.

(7) corrective actions to clean and/or remove the leak or spill

- \* After applying absorbent to the area, Chiquita personnel removed and contained the used absorbent. Cleanup commenced immediately and was completed the same day.

(8) corrective actions implemented or to be implemented, including an estimated timeline, to prevent future recurrence

- \* Chiquita will continue to monitor drivers as they close the valves on their trucks.

(9) the type of affiliation of the operator involved in the root cause

- \* A third-party truck hauler was involved in the root cause of the spill.

(10) whether any individuals involved in the root cause had previously received training on applicable operations to avoid leaks or spills

- \* Chiquita does not provide training to third-party truck drivers; however, Chiquita tank farm personnel have been trained on applicable operations to avoid leaks and spills.

(11) the number of times individuals involved in the root cause had previously been involved in the root cause of a leachate leak or spill

- \* No individuals involved in the root cause had previously been involved in the root cause of a leachate leak or spill.

Regards,

Amanda Froman  
Compliance Manager  
Chiquita Canyon Landfill  
Waste Connections, Inc.  
(m) 661-625-1409