
From: Sarah Phillips <Sarah.Phillips@WasteConnections.com>
Sent: Tuesday, May 19, 2026 1:16 PM
To: bchen@aqmd.gov; ndickel@aqmd.gov; cojeda@aqmd.gov
Cc: Matt Breuer; christopher.mcguire@dtsc.ca.gov; zanalee.zmily@dtsc.ca.gov; emorofuji@ph.lacounty.gov
Subject: Chiquita Canyon Landfill – Case No. 6177-4: Spill Report (Condition 27(e))

All,

In accordance with Condition 27(e) of the Stipulated Order for Abatement in Case No. 6177-4, based on its current knowledge of the event, Chiquita Canyon, LLC (Chiquita) provides the following report detailing a spill of approximately 1 cup of treated non-hazardous leachate associated with manifest CCL003740-X from a third-party tanker truck located in the loadout area of Tank Farm 13, Grid 250.

(1) the date and time of the leak or spill;

1. The spill was discovered on May 17, 2026, at approximately 7:30 p.m.

(2) area designation inspected;

- Treated non-hazardous leachate spilled from a third-party tanker truck in the loadout area of Tank Farm 13, Grid 250. Liquid from the spill did not enter the stormwater channel or either stormwater basin.

(3) the name of the person that discovered the leak or spill;

1. Paul Ramos.

(4) written acknowledgement that they did, or did not, take corrective action with rationale for these actions;

- Upon discovering the spill, Chiquita personnel directed the third-party driver to stop the tanker truck. The driver then tightened the truck's top dome lid, which stopped the flow of liquid.

(5) a root cause analysis on why and how the leak or spill occurred;

1. Based on Chiquita's current knowledge, the spill appears to have occurred because a third-party driver inadvertently did not fully secure the tanker truck's top dome lid before moving the truck, causing leachate to spill from the seal of the top dome lid. Chiquita attributes this spill to third-party driver error.

(6) the estimated quantity of the leak or spill;

1. Chiquita conservatively estimates that approximately 1 cup of treated non-hazardous leachate associated with manifest CCL003740-X spilled from the third-party tanker truck.

(7) corrective actions to clean and/or remove the leak or spill;

- In addition to the measures discussed above, the affected soil was promptly removed and placed into a container for proper disposal. Cleanup was completed within approximately 5 minutes.

(8) corrective actions implemented or to be implemented, including an estimated timeline, to prevent future recurrence;

- Chiquita will remind third-party drivers to inspect equipment prior to moving their trucks.

(9) the type of affiliation of the operator involved in the root cause;

- A third-party driver was involved in the root cause of this spill.

(10) whether any individuals involved in the root cause had previously received training on applicable operations to avoid leaks or spills; and

- Chiquita does not provide training to its third-party drivers; however, Chiquita routinely reviews spill- and-leak prevention practices with its drivers, and Chiquita personnel have been trained on applicable operational procedures to help prevent leaks and spills.

(11) the number of times individuals involved in the root cause had previously been involved in the root cause of a leachate leak or spill.

- To the best of Chiquita's knowledge, the individual involved in the root cause of this spill has not previously been involved in the root cause of a leachate leak or spill.

Anshika Agrawal

Associate



T: [+1.202.789.6021](tel:+12027896021) | M: [+1.703.606.7845](tel:+17036067845) | AAgrawal@bdlaw.com

1900 N Street, NW, Suite 100, Washington, DC 20036

CONFIDENTIALITY STATEMENT: This electronic message contains information from the law firm of Beveridge & Diamond, PC and may be confidential or privileged. If you have received this e-mail in error, please notify us immediately by telephone at +1.202.789.6000 or by e-mail reply and delete this message.

Sarah Phillips
248.930.2779