



May 26, 2026

***Via E-Mail***

Baitong Chen, Air Quality Engineer, [bchen@aqmd.gov](mailto:bchen@aqmd.gov)  
Nathaniel Dickel, Senior Air Quality Engineer, [ndickel@aqmd.gov](mailto:ndickel@aqmd.gov)  
Christina Ojeda, Air Quality Inspector, [cojeda@aqmd.gov](mailto:cojeda@aqmd.gov)  
South Coast Air Quality Management District  
21865 East Copley Drive  
Diamond Bar, California 91765-4182

**Re: Chiquita Canyon, LLC's Weekly Leachate Inspection Report for Stipulated Order for Abatement (Case No. 6177-4), Condition 27(c)**

All:

Pursuant to Condition 27(c) of the Stipulated Order for Abatement with the South Coast Air Quality Management District in Case No. 6177-4 (the "Order"), Chiquita Canyon, LLC ("Chiquita") encloses a compilation of the twice daily leachate seep inspection logs for the dates of May 18, 2026 through May 24, 2026. No leachate seepage or pooling was observed at the Chiquita Canyon Landfill during these inspections.

Chiquita continues to monitor the previously reported containment area and to remove liquids, as necessary, using a vacuum truck. Chiquita will be constructing a soil buttress on the west side of the Landfill, adjacent to the prior "west slope toe drain project," considering the continued extrusion of reacted material at certain preferential pathways that daylight on the west slope. Chiquita and consultants are in the process of planning and designing this project. The total approximate amount of leachate collected from the west side was 24,019.5 gallons between May 18, 2026 and May 24, 2026.

Please contact me if you have any questions regarding this matter.

Regards,

Matt Breuer  
Environmental Manager  
Chiquita Canyon

Attachment: Leachate Inspection Logs from May 18 – May 24, 2026

# 4050 - Chiquita Leachate Seep/Pooling Inspection

18 May 2026 / Tom Roe

Complete

**Conducted on**

18 May 2026 6:36 AM PDT

---

**Prepared by**

Tom Roe

---

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road. None of the seeps that occurred in this area were observed at the time of this inspection. Area continues to be monitored and vacuumed out as needed to prevent pooling

# 4050 - Chiquita Leachate Seep/Pooling Inspection

18 May 2026 / Tom Roe

Complete

**Conducted on**

18 May 2026 2:30 PM PDT

---

**Prepared by**

Tom Roe

---

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road. None of the seeps that occurred in this area were observed at the time of this inspection. Area continues to be monitored and vacuumed out as needed to prevent pooling

# 4050 - Chiquita Leachate Seep/Pooling Inspection

19 May 2026 / Tom Roe

Complete

**Conducted on**

19 May 2026 7:34 AM PDT

---

**Prepared by**

Tom Roe

---

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road. None of the seeps that occurred in this area were observed at the time of this inspection. Area continues to be monitored and vacuumed out as needed to prevent pooling

# 4050 - Chiquita Leachate Seep/Pooling Inspection

19 May 2026 / Tom Roe

Complete

**Conducted on**

19 May 2026 2:06 PM PDT

---

**Prepared by**

Tom Roe

---

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road. None of the seeps that occurred in this area were observed at the time of this inspection. Area continues to be monitored and vacuumed out as needed to prevent pooling

# 4050 - Chiquita Leachate Seep/Pooling Inspection

20 May 2026 / Tom Roe

Complete

**Conducted on**

20 May 2026 6:41 AM PDT

---

**Prepared by**

Tom Roe

---

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road. None of the seeps that occurred in this area were observed at the time of this inspection. Area continues to be monitored and vacuumed out as needed to prevent pooling

# 4050 - Chiquita Leachate Seep/Pooling Inspection

20 May 2026 / Tom Roe

Complete

**Conducted on**

20 May 2026 2:40 PM PDT

---

**Prepared by**

Tom Roe

---

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road. None of the seeps that occurred in this area were observed at the time of this inspection. Area continues to be monitored and vacuumed out as needed to prevent pooling

# 4050 - Chiquita Leachate Seep/Pooling Inspection

21 May 2026 / John Boucher

Complete

**Conducted on**

21 May 2026 7:34 AM PDT

---

**Prepared by**

John Boucher

---

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road. None of the seeps that occurred in this area were observed at the time of this inspection. Area continues to be monitored and vacuumed out as needed to prevent pooling.

# 4050 - Chiquita Leachate Seep/Pooling Inspection

21 May 2026 / John Boucher

Complete

**Conducted on**

21 May 2026 2:58 PM PDT

---

**Prepared by**

John Boucher

---

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road. None of the seeps that occurred in this area were observed at the time of this inspection. Area continues to be monitored and vacuumed out as needed to prevent pooling.

# 4050 - Chiquita Leachate Seep/Pooling Inspection

22 May 2026 / John Boucher

Complete

**Conducted on**

22 May 2026 7:05 AM PDT

---

**Prepared by**

John Boucher

---

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road. None of the seeps that occurred in this area were observed at the time of this inspection. Area continues to be monitored and vacuumed out as needed to prevent pooling.

# 4050 - Chiquita Leachate Seep/Pooling Inspection

22 May 2026 / John Boucher

Complete

**Conducted on**

22 May 2026 2:05 PM PDT

---

**Prepared by**

John Boucher

---

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road. None of the seeps that occurred in this area were observed at the time of this inspection. Area continues to be monitored and vacuumed out as needed to prevent pooling.

# 4050 - Chiquita Leachate Seep/Pooling Inspection

23 May 2026 / John Boucher

Complete

**Conducted on**

23 May 2026 8:01 AM PDT

---

**Prepared by**

John Boucher

---

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road. None of the seeps that occurred in this area were observed at the time of this inspection. Area continues to be monitored and vacuumed out as needed to prevent pooling.

# 4050 - Chiquita Leachate Seep/Pooling Inspection

23 May 2026 / John Boucher

Complete

**Conducted on**

23 May 2026 1:06 PM PDT

---

**Prepared by**

John Boucher

---

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road. None of the seeps that occurred in this area were observed at the time of this inspection. Area continues to be monitored and vacuumed out as needed to prevent pooling.

# 4050 - Chiquita Leachate Seep/Pooling Inspection

24 May 2026 / Tom Roe

Complete

**Conducted on**

24 May 2026 6:40 AM PDT

---

**Prepared by**

Tom Roe

---

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road. None of the seeps that occurred in this area were observed at the time of this inspection. Area continues to be monitored and vacuumed out as needed to prevent pooling

# 4050 - Chiquita Leachate Seep/Pooling Inspection

24 May 2026 / Tom Roe

Complete

**Conducted on**

24 May 2026 1:00 PM PDT

---

**Prepared by**

Tom Roe

---

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

Has a leachate seep/pooling been located?

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road. None of the seeps that occurred in this area were observed at the time of this inspection. Area continues to be monitored and vacuumed out as needed to prevent pooling