



August 7, 2026

California Regional Water Quality Control Board
Los Angeles Region
320 W. 4th Street, Suite 200
Los Angeles, California 90013
ATTN: Information Technology Unit

**Subject: Leachate Seep Report
Chiquita Canyon Landfill
WDRs Order No. R4-2018-0172
File No. 67-020**

Pursuant to MRP No. CI-6231 Section B.3.a, Chiquita Canyon, LLC (“Chiquita”) hereby provides the following information regarding a seep discovered on July 31, 2026 during which approximately less than one gallon of characteristically non-hazardous liquid associated with Group C reached the stormwater channel but did not reach either sedimentation basin. This is a conservative estimate based on visual observations by Chiquita staff. Chiquita maintains appropriate response materials, including fully stocked spill kits, and has trained staff on site to respond to seeps to prevent liquids from entering the stormwater system.

i. Map - A map showing the location(s) of seepage.

The seep was observed in Grid 93, as indicated in **Attachment A**.

ii. Flow rate - An estimate of the flow rate.

The seep had a low flow rate.

iii. Description - A description of the nature of the discharge (e.g., all pertinent observations and analyses).

On July 31, 2026, at approximately 6:31 a.m., Chiquita personnel observed a small seep in Grid 93 that had a low flow rate. Approximately less than one gallon of liquid seeped into the stormwater channel but did not reach either sedimentation basin. The liquid was dark brown in color with low viscosity and traveled with a low flow rate.

iv. Location – Location of sample(s) collected for laboratory analysis, as appropriate.

No sampling was conducted for this seep.

August 7, 2026

Page 2 of 2

v. Corrective measures – approved (or proposed for consideration) by the Regional Board Executive Officer.


Upon discovery of the seep, Chiquita promptly initiated response and mitigation measures, including installing a check dam to contain the liquid, removing impacted soil and placing it in a container for appropriate disposal. Chiquita then pressure-washed the stormwater channel and added fresh soil to the affected area. The response work was completed by approximately 8:30 a.m. on July 31, 2026. This seepage is related to the seepage that occurred in Grid 93 on July 23, 2026. Chiquita is planning to install a collection sump in the area to minimize the potential for future recurrence.

If you should have any questions regarding this report, please do not hesitate to contact me at (661) 257-3655.

Sincerely,
Chiquita Canyon, LLC

Sarah Phillips
Corporate Compliance Manager
Chiquita Canyon

Attachments: Attachment A – Grid Map of Seep Location



LEGEND

- CV-69 ACTIVE VERTICAL WELLS ABOVE GRADE
- CV-69 ACTIVE VERTICAL WELLS WITH HOV TEMP
- CV-69 ACTIVE VERTICAL WELLS WITH HOV O2
- CV-69 ACTIVE VERTICAL WELL WITH ELEVATED H2S
- CV-43 ACTIVE VERTICAL WELLS BELOW GRADE
- C-31 ACTIVE HORIZONTAL WELLS
- C-31 ACTIVE HORIZONTAL WELLS WITH HOV TEMP
- C-31 ACTIVE HORIZONTAL WELLS WITH ELEVATED H2S
- C-31 ACTIVE HORIZONTAL WELLS WITH STINGERS
- DW-1 DETECTION WELLS
- PZ-1 PIEZOMETER
- CV-38 REMOTE VERTICAL WELL HEADS
- CV-38 REMOTE VERTICAL WELL HEADS WITH HOV O2
- CV-38 REMOTE VERTICAL WELL HEADS WITH HOV TEMP
- GP-9 GAS PROBE
- V VALVE
- V VALVE VAULT
- AC ACTIVATED CARBON VESSEL
- LC-5 SAMPLE POINT

NOTES:

- EXISTING TOPOGRAPHY PLAN IS FROM PROPELLER DATA. THE TOPOGRAPHY DATA IS BASED ON AUGUST 11, 2023.
- EXISTING GCCS AS-BUILTS DATED 10-18-23.

DATE		REVISION		NO.	
SHEET TITLE:		PROJECT TITLE:		CLIENT:	
LANDFILL GAS COLLECTION SYSTEM WITH SEM MAP		CHICUITA CANYON LANDFILL 29201 HENRY MAYO DRIVE, CASTAIC, CALIFORNIA 91384		SCS ENGINEERS ENVIRONMENTAL CONSULTANTS 10200 15TH AVE, SUITE 100 LONG BEACH, CA 90804 PH: (562) 409-2544 FAX: (562) 409-2544	
DATE:		SCALE:		1" = 100'	
10-20-2013		1" = 100'		1 of 1	