SCS ENGINEERS

October 15, 2025

Karen Gork
Chief Environmental Health Specialist
Los Angeles County Local Enforcement Agency
5050 Commerce Drive
Baldwin Park, California 91706

Subject: September 2025 Monthly Report Pursuant to Milestones 1A-3 and 5 of the LEA June 6, 2024 Compliance Order and July 30, 2024 Letter, Chiquita Canyon Landfill, Castaic, California

Dear Ms. Gork:

SCS Engineers (SCS), on behalf of Chiquita Canyon, LLC (Chiquita), hereby provides the Los Angeles County Department of Public Health, Solid Waste Management Program, acting as the Local Enforcement Agency (LEA) with a monthly report pursuant to Milestones 1A-3 and 5 of the LEA Compliance Order dated June 6, 2024 (Compliance Order) and subsequent related correspondence received from the LEA. This report covers the monthly period for September 2025.

Chiquita Canyon Landfill (CCL or Landfill) is a landfill/solid waste disposal facility located at 29201 Henry Mayo Drive in Castaic, California. In connection with the Landfill, Chiquita operates a landfill gas collection and control system. SCS prepared and submitted the Carbon Monoxide and Hydrogen Reading Summary Report (Summary Report) to the LEA on June 6, 2024, on behalf of Chiquita, in response to the directives in the LEA letters dated April 5, 2024 and May 28, 2024 regarding collection of landfill gas data and in accordance with Milestone 1A-2 of the Compliance Order. The LEA, in collaboration with the California Department of Resources, Recycling, and Recovery (CalRecycle), reviewed the Summary Report and determined that it complied with Milestone 1A-2. The LEA set forth several new requirements for Chiquita to comply with Milestone 1A-3 in follow-up correspondence dated July 30, 2024.

This report was prepared in accordance with Milestones 1A-3 and 5 of the Compliance Order, the LEA's follow-up correspondence dated July 30, 2024, Chiquita's letter dated September 3, 2024, the September 12, 2024, meeting with the LEA, and follow-up correspondence from the LEA dated November 19 and 27 and December 3, 2024.

Milestone 1A-3 Compliance Items

1. Submit the laboratory test results for monthly sampling of carbon monoxide (CO) and hydrogen (H2) from a set of landfill gas (LFG) wells selected by the LEA. Please see Table 1, columns labeled "CO" and "H2."

Results for wells monitored are shown in **Attachment A**.[1] The data is being submitted to the LEA in a standalone report signed by a licensed engineer, in accordance with Milestone 1A-3 of the Compliance Order. As noted in Chiquita's prior correspondence and monthly reports, this report does not include data from wells CV-100, CV-1420, CV-1532, CV-2202, H-1774S, TC-2385A, and TC-2385S, as those wells have been abandoned, or from well CV-2332, as that well was never installed. All remaining wells were tested during the month of September 2025.

As discussed during the September 12, 2024 meeting, and as previously reported, graphics showing CO and H2 trends are provided in **Attachment D** and are discussed further below.

In August 2025, CV-2328 was unable to be sampled because it was offline for EVOH deployment. CV-2328 was reconnected on September 10, 2025 and a sample was collected. The results are available in **Attachment A**.

2. Provide data from readings for fixed gases (CH4, O2, and CO2) from a set of LFG wells selected by the LEA. See Table 1, column labeled "Fixed Gas CH4, O2, CO2."

The results for wells monitored are provided in **Attachment A**.

As discussed above, CV-2328 was reconnected to the gas collection system on September 10, 2025. Well monitoring results for September 2025 are included in **Attachment A**.

3. Collect down well temperatures at 34 wells to confirm the gas wellhead temperature readings per the requirement of the New Source Performance Standards (NSPS). See Table 1, column labeled "Down Well Temp Monitoring."

It is Chiquita's understanding from the LEA's November 27, 2024 correspondence, and as noted in prior monthly reports, that, at this time, Chiquita is only required to sample the wells at the annual frequency provided in the NSPS protocols, but that the LEA may require more frequent monitoring for up to ten (10) wells selected by the LEA. Chiquita is awaiting the LEA's selection of those wells.

---

[1] The lab(s) reported data from additional LFG wells outside of those selected for sampling by the LEA; the additional data is related to separate South Coast Air Quality Management District (South Coast AQMD) reporting requirements and therefore can be disregarded for purposes of this report.

Chiquita nevertheless provides in **Attachment B** the down-hole temperature graphs[2] concerning the following wells from fixed locations which contain the Lorentz Pumping System with integral temperature sensors: CV-2303, CV-2315, CV-2350, CV-2351 (9-1 to 9-2) and CV-24065 (9-1 to 9-27).

Please note that the Lorentz pump and/or temperature monitoring system for the pumps in CV-2301, CV-2302, CV-2351, CV-2352, CV-24017, CV-24065 and CV-24095 are currently offline due to either the deployment of the approved EVOH 60-mil geomembrane or the interim relocation of the tank farm, or are in the process of being repaired. (See **Attachment B** Monitoring List).

As previously noted, SCS will continue to collect down-hole temperatures for wells on an annual basis and will report the results as the data is obtained at each location. (See **Attachment B**). SCS has completed annual 2025 downhole temperature monitoring at all locations requested as of June 2025. However, in order to provide additional information to the LEA regarding the new Soil Vapor Extraction Wells, downhole temperature monitoring was performed for the second time this year at well CV-24139 on August 18, 2025 (initial annual monitoring occurred on 3/10/2025) and this data was submitted in the August 2025 report.

4. Sample the selected 40 wells for VOCs by method TO-15. See Table 1, column labeled "VOC (TO-15)."

The results for wells monitored are provided in **Attachment A**.[3] Please note that all 40 locations for VOC sampling were tested during September 2025.

5. Continue to sample and monitor 6 horizontal wells as indicated in Attachment 1, well numbers highlighted in yellow. At this time, 42 horizontal wells may be released from continued sampling, however, wells may be included later depending on future data submissions. See Table 1, well numbers highlighted in blue.

As noted in the September 3, 2024 letter and reported in prior monthly reports, two (2) of the six (6) horizontal wells (H-1774S and H-1560S) were abandoned when the new vertical extraction wells were installed, and thus data from those wells are not included. Data from the four (4) other horizontal wells are in **Attachment A**.

6. Add 20 vertical wells to the monthly wellhead temperature and LFG sampling protocols. See Table 1 well numbers highlighted in green.

As conveyed by the LEA during our September 12, 2024 meeting, and restated in our prior monthly reports, we understand the LEA is requiring laboratory analytical data for fixed gases,

---

[2] Each graph notes a single temperature data point due to changes in the software.
[3] Well CV-24142 is listed twice in Table 1 of the LEA's July 30, 2024 letter – one requires VOC sampling, and the other does not. Chiquita sampled this well for VOCs.

CO, and H2, as well as field data. Laboratory results are in **Attachment A**. Field data with wellhead gas temperatures are shown on Table 2 in **Attachment A**.

We understand from the LEA's November 27, 2024 correspondence that laboratory analytical data will be required for the specified fixed gases.

Note that following wells were again not sampled in September 2025, for the following reasons noted in prior monthly reports:

CV-1420 – Abandoned during 2024 GCCS Expansion due to declining gas flows.
CV-2202 – Abandoned during 2024 GCCS Expansion due to declining gas flows.
CV-2332 – This well does not exist. This well was proposed for installation in Fall 2023, but other wells were installed in the area in lieu of CV-2332 when the number of wells increased pursuant to the Stipulated Order for Abatement (Stipulated Order) with the South Coast Air Quality Management District (South Coast AQMD).

7. Plot to show the locations of the following 19 wells on the site map titled "Existing GCCS Map – LFG Vertical Extraction Wells" dated 06/06/2024: CV-24002, CV-24003, CV-24007, CV-24017, CV-24053, CV-24055, CV-24065, CV-24071, CV-24075, CV-24077, CV-24079, CV-24082, CV-24083, CV-24088, CV-24095, CV-24096, CV-24097, CV-24098 and H-1403W. For well H-1403W, provide the horizontal location of piping and an estimate where the high temperature (195°F) is most likely occurring. See Table 1, well numbers highlighted in red and H-1403W (highlighted in yellow).

The locations of the above-identified wells are shown on the Map in **Attachment C**.[4]

8. Include in the monthly report, a settlement/heat map as shown below, beginning with the earliest heat map data available for each month to present. The topographic maps should show 2-foot contour intervals if possible.

The LEA directed Chiquita on June 2, 2025 to submit isopach maps on a monthly basis to comply with this request. For ease of reference, we are submitting as **Attachment F** a copy of the September 2025 isopach map.

9. Provide the sampling results in a standalone report with the appropriate discussion, tables, QA/QC, methods and signed by a registered professional, etc., as described in the Compliance Order Milestone 1A-2 and 1A-3.

[4] The LEA acknowledged in its November 20, 2024 correspondence that a high temperature is not occurring in well H-1403W. We therefore did not map the maximum temperature at well H-1403W.

CCL has provided the above-requested information and the raw data in **Attachment A**, as well as a figure with the data-driven reaction area which incorporates settlement data (see **Attachment F**). Temperature graphs are provided for wells with Lorentz pumps (5 locations).

Please note that in addition to the wells listed in response to the request dated July 30, 2024 (in Table 1) that could not be tested, the following wells that only required analytical data could also not be tested, as previously reported, because they were abandoned during the 2024 GCCS expansion due to declining gas flows in accordance with the requirements of the NSPS: CV-100, CV-1532, H-1560S, H-1774S, TC-2385A, TC-2385S, CV-2202, and CV-1420. Finally, as also previously reported, CV-2332 was never installed.

<u>Sampling Procedures</u>

Gas samples were collected using Tedlar/Mylar bags, as described in Chiquita's September 3, 2024 letter and the prior monthly reports, and then delivered to certified laboratories for testing. All permanent gas (CH_4, CO_2, O_2, N_2, CO, and H_2) data were analyzed within the requested 24 hours of sampling, except as noted below. SCS continues to believe that use of the EPA-approved 72-hour holding time for these samples would be appropriate and accurate. Nevertheless, in response to the LEA's March 17, 2025 correspondence, SCS will continue to request 24-hour holding times for all fixed gases, including CO, H_2, and VOCs, collected using Mylar or Tedlar bags. However, if additional sampling is required or if the laboratories have a change in workload, this holding time may change, in which case the LEA will be notified accordingly. During September 2025, all wells were tested for VOC's (EPA method TO-15) and permanent gases (EPA methods 1946 and Alt-144) within 24 hours by providing the laboratory with duplicate bag samples as needed for VOC testing. Note that due to an issue with the laboratory equipment the following wells which were sampled on September 9 and 10, 2025 had to be resampled on September 25, 2025 to maintain the 24 hour hold time: H-1770N, CV-1902A, CV-1535, CV-108-52, CV-1532A, CV-2301, CV-2302 and H-2273W. Of these 8 wells that were resampled on September 25, 2025, all were analyzed within 24 hours with the exception of CV-108-52 (24 hours 17 minutes) and CV-1902A (24 hours 40 minutes) due to an equipment issue which stopped the sampling process and had to be reset at the laboratory. The issues observed are written in the laboratory report narratives.

Additional gas and pressure data were collected using either an Envision Irwin Gas Meter or Landtec GEM 5000 Gas monitoring device. These instruments measure combustible gas concentrations in air directly on either of two scales, the first as a percent by volume of the lower explosive limit (LEL) of methane gas in air (0 to 5 percent) and the other as a percent by volume (0 to 100 percent) in the gas sampled. The detection limit for these instruments is approximately 0.10 percent by volume.

Gas monitoring testing procedures were as follows:

- Connect sample tubing, open test valve, observe pressure, and record data.
- Turn on sample pump, purge a minimum of one probe volume, and observe and record methane, oxygen, and carbon dioxide gas concentrations when readings have

stabilized.

- Close test valve, disconnect sample instruments, and secure sample location.

Milestone 1A-3 Conclusions

September 2025 was the fourteenth monitoring performed pursuant to Milestone 1A-3 of the Compliance Order. The data collected in September 2025 and evaluated for this report are consistent with the data collected in the previous months of August 2024 through August 2025 as well as the data collected and evaluated by the Reaction Committee established under the supervision of South Coast AQMD and in accordance with the Stipulated Order to assess the reaction area, including the September 2025 data most recently evaluated by the Reaction Committee on October 10, 2025, as required by Condition 9(b) of the Stipulated Order. (See **Attachment E**.)

For the reasons described in the attached October 10, 2025 Reaction Committee report, the alignment of the estimated extent of the elevated temperature landfill (ETLF) conditions exhibited at the Landfill (referred to as the “Reaction Area” limits) and identified in that report remains the same as that identified in the Reaction Committee’s September 2025 report. The Reaction Committee determined that no adjustments were warranted and that ETLF conditions had not expanded. There was no evidence of reaction conditions or reaction gas present outside of the currently delineated reaction area boundary.

As liquid levels continue to change due to the installation of additional Lorentz Electric and Pneumatic Pumps, we continue to see the anticipated changes in percentages of Permanent Gases, Carbon Monoxide, and Hydrogen and changes to temperatures as more gas is able to move towards and to be removed by the extraction wells as the levels of liquid decline. This continues to be demonstrated by the multiscale well graphics included in **Attachment D**, which includes graphics on permanent gases, temperature, and other trends over a six (6)-month period. Note that these graphs were created using standard landfill gas monitoring equipment and the results do not contain laboratory data. SCS has also included separate Hydrogen and Carbon Monoxide graphs using laboratory results for your use and review for each well.

Additionally, the installation of larger diameter piping has improved the collection of additional gases throughout the Landfill. Since March 2025, the flow rates of landfill gas being combusted by the abatement devices have ranged from 13,500 cfm to 16,000 cfm. During September 2025, the overall gas extraction from the Landfill was approximately 653,669,568 cubic feet. This landfill gas extraction rate and anticipated future increases of this extraction rate as the collection systems continue to expand, is expected to improve the gas composition of the wells in the reaction area as more vacuum and resulting movement of gas allows more reaction and normal landfill gas to be extracted.

Chiquita will continue to evaluate the data in future monthly reports as additional data is collected.

<u>Milestone 5 Compliance Items</u>

This report includes in **Attachment D** individual maps overlayed with the following data for September 2025 in an easily understood format, in accordance with Milestone 5 of the Compliance Order:

- Defined reaction area;
- Expansion of reaction area, if any;
- Weekly TMP data; and
- LFG data including, but not limited to, CH4, CO2, O2, Temperature, CO, and H2 data.

Milestone 5 also requires "settlement with heat maps," but as discussed earlier in this report and in accordance with LEA correspondence dated November 27 and December 3, 2024, this requirement is satisfied by Chiquita's submittal of its monthly isopach maps to the LEA. For the LEA's convenience, the September 2025 isopach map is included herein as **Attachment F**.

The signatories below are a licensed professional and a Regional Manager VP of SCS Engineers.

Sincerely,

Bill Haley

William C. Haley, PE
Project Director
SCS Engineers

Arthur E Jones Jr
Vice President
SCS Engineers

Attachments:

Attachment A – Laboratory Analysis and LFG Extraction Well Instrument and Temperature Data
Attachment B – Down Well Temperatures and List of Wells for Monitoring
Attachment C – Item 7 - Well Location Map
Attachment D – Milestone 5 Compliance Data
Attachment E – October 10, 2025 Reaction Committee Report
Attachment F – September 2025 Isopach Map

Electronic Data of Laboratory Results are in Excel format, with additional PDFs for gas well data.

cc: John Perkey, Waste Connections
Steve Cassulo, Waste Connections
Kate Logan, Waste Connections

Amanda Froman, Waste Connections
Mark Adams, Waste Connections
Pat Sullivan, SCS Engineers
Robert Ragland, Los Angeles County Department of Public Health
Liza Frias, Los Angeles County Department of Public Health
Nichole Quick, M.D., Los Angeles County Department of Public Health
Ken Habaradas, Los Angeles County LEA
Eric Morofuji, Los Angeles County LEA
Renee Jensen, LEA Counsel
Blaine McPhillips, Senior Deputy County Counsel
Emiko Thompson, Los Angeles County Department of Public Works
Alex Garcia, Los Angeles County Department of Regional Planning
Phillip Chen, Los Angeles County Department of Regional Planning
Steven Jareb, Los Angeles County Department of Regional Planning
Wes Mindermann, CalRecycle
Todd Thalhamer, CalRecycle
Emel Wadhwani, CalRecycle
Jeff Linberg, California Air Recourses Board
Nancy Fletcher, California Air Recourses Board
Jack Cheng, South Coast Air Quality Management Board
Larry Israel, South Coast Air Quality Management Board
Enrique Casas, Los Angeles Regional Water Quality Control Board
Joshua Wirtschafter, United States Environmental Protection Agency
Laura Friedli, United States Environmental Protection Agency
Tyler Holybee, United States Environmental Protection Agency
Mark Anthony Relon, United States Environmental Protection Agency
Tim Crick, Department of Toxic Substances Control
Pete Ruttan, Department of Toxic Substances Control

Attachment A

Laboratory Analysis

And

LFG Extraction Well Instrument and Temperature Data

AirTECHNOLOGY Laboratories, Inc.

September 12, 2025

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175

TX Cert T104704450-14-6
EPA Methods TO14A, TO15

ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference:	Chiquita Canyon Landfill
Project Number:	07224200.24 Task 1
Lab Number:	S090202-01/10

Enclosed are the results for sample(s) received 9/2/25 by Air Technology. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Vinyl acetate and bromoform exhibited low recovery in the initial calibration verification indicating possible low bias. Results have been flagged with the Q qualifier.
- Ethyl acetate exhibited high recovery in the initial calibration verification indicating a possible high bias. Results have been flagged with the Q qualifier.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Jenny Kim, Art Jones and Ali Ferrara on 9/11/25.

ATL appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Annika Sotelo-Sanchez for

Mark Johnson
Operations Manager
MJohnson@AirTechLabs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME: Standard ■ | Same Day ☐ | 24 hours ☐ | 48 hours ☐ | 72 hours ☐ | 96 hours ☐ | Other:

DELIVERABLES: EDD ■ | EDF ☐ | Level 3 ☐ | Level 4 ☐

PAGE: 1 OF

Condition upon receipt:
Sealed Yes ☐ No ☐
Intact Yes ☐ No ☐
Chilled ______ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 100
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.: 07-SO05310
Bill to:
07FSAccountspayable@scsengineers.com
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
S090202-01	CV-24123	9/2/2025	9:20AM	1L	Gas	N	X					
-02	CV-24122	9/2/2025	9:30AM	2-1L	Gas	N	X	X	X	X		
-03	CV-99	9/2/2025	9:35AM	1L	Gas	N	X	X	X			
-04	CV-113	9/2/2025	9:40AM	2-1L	Gas	N	X	X	X	X		
-05	CV-24121	9/2/2025	9:45AM	1L	Gas	N	X	X	X			
-06	CV-24128	9/2/2025	10:00AM	1L	Gas	N	X	X	X			
-07	CV-2334	9/2/2025	10:05AM	1L	Gas	N	X	X	X			
-08	CV-2333	9/2/2025	10:10AM	1L	Gas	N	X	X	X			
-09	CV-24126	9/2/2025	10:15AM	1L	Gas	N	X					
-10	CV-24127	9/2/2025	10:20AM	2-1L	Gas	N	X	X	X	X		

AUTHORIZATION TO PERFORM WORK	COMPANY			DATE/TIME
SAMPLED BY: Fabian Chavez	COMPANY: SCS			DATE/TIME: 9-2-25 11:21am
RELINQUISHED BY: [signature]	DATE/TIME: 9-2-25 11:21am	RECEIVED BY: Ruben G		DATE/TIME: 9-2-25 11:21
RELINQUISHED BY: Ruben G	DATE/TIME: 9/2/25 12:36	RECEIVED BY: [signature]		DATE/TIME: 9/2/25 12:36
RELINQUISHED BY	DATE/TIME	RECEIVED BY		DATE/TIME

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other______

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/02/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	S090202-02		S090202-04		S090202-10			
Client Sample I.D.:	CV-24122		CV-113		CV-24127			
Date/Time Sampled:	9/2/25 9:30		9/2/25 9:40		9/2/25 10:20			
Date/Time Analyzed:	9/2/25 19:56		9/2/25 20:38		9/2/25 21:20			
QC Batch No.:	250902MS2A1		250902MS2A1		250902MS2A1			
Analyst Initials:	RC		RC		RC			
Dilution Factor:	150		2,500		500			
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv		
1,2-Dibromoethane	ND	150	ND	2,500	ND	500		
Chlorobenzene	ND	150	ND	2,500	ND	500		
Ethylbenzene	ND	150	ND	2,500	ND	500		
p,&m-Xylene	ND	150	ND	2,500	ND	500		
o-Xylene	ND	150	ND	2,500	ND	500		
Styrene	ND	150	ND	2,500	ND	500		
Bromoform	ND Q	150	ND Q	2,500	ND Q	500		
1,1,2,2-Tetrachloroethane	ND	150	ND	2,500	ND	500		
Benzyl Chloride	ND	150	ND	2,500	ND	500		
4-Ethyl Toluene	ND	150	ND	2,500	ND	500		
1,3,5-Trimethylbenzene	ND	150	ND	2,500	ND	500		
1,2,4-Trimethylbenzene	ND	150	ND	2,500	ND	500		
1,3-Dichlorobenzene	ND	150	ND	2,500	ND	500		
1,4-Dichlorobenzene	ND	150	ND	2,500	ND	500		
1,2-Dichlorobenzene	ND	150	ND	2,500	ND	500		
1,2,4-Trichlorobenzene	ND	150	ND	2,500	ND	500		
Hexachlorobutadiene	ND	150	ND	2,500	ND	500		
1,3-Butadiene	ND	750	ND	13,000	ND	2,500		
Isopropanol	19,000	750	ND	13,000	ND	2,500		
n-Hexane	ND	750	ND	13,000	ND	2,500		
Ethyl Acetate	3,600 Q	750	ND	13,000	5,800 Q	2,500		
Tetrahydrofuran	1,700	750	ND	13,000	54,000	2,500		
Cyclohexane	ND	750	ND	13,000	ND	2,500		
Heptane	ND	750	ND	13,000	ND	2,500		
1,4-Dioxane	ND	750	ND	13,000	ND	2,500		

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Refer to Report Narrative

Reviewed/Approved By: Annika Sotelo Sanchez for
Mark Johnson
Operations Manager

Date 9-11-25

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/02/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	S090202-02		S090202-04		S090202-10			
Client Sample I.D.:	CV-24122		CV-113		CV-24127			
Date/Time Sampled:	9/2/25 9:30		9/2/25 9:40		9/2/25 10:20			
Date/Time Analyzed:	9/2/25 19:56		9/2/25 20:38		9/2/25 21:20			
QC Batch No.:	250902MS2A1		250902MS2A1		250902MS2A1			
Analyst Initials:	RC		RC		RC			
Dilution Factor:	150		2,500		500			
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv		
Dichlorodifluoromethane (12)	440	150	ND	2,500	ND	500		
Chloromethane	ND	150	ND	2,500	ND	500		
1,2-Cl-1,1,2,2-F ethane (114)	ND	150	ND	2,500	ND	500		
Vinyl Chloride	ND	150	ND	2,500	ND	500		
Bromomethane	ND	150	ND	2,500	ND	500		
Chloroethane	ND	150	ND	2,500	ND	500		
Trichlorofluoromethane (11)	ND	150	ND	2,500	ND	500		
1,1-Dichloroethene	ND	150	ND	2,500	ND	500		
Carbon Disulfide	180	150	ND	2,500	ND	500		
1,1,2-Cl 1,2,2-F ethane (113)	ND	150	ND	2,500	ND	500		
Acetone	20,000	150	75,000	2,500	61,000	500		
Methylene Chloride	ND	150	ND	2,500	ND	500		
t-1,2-Dichloroethene	ND	150	ND	2,500	ND	500		
1,1-Dichloroethane	ND	150	ND	2,500	ND	500		
Vinyl Acetate	ND Q	150	ND Q	2,500	ND Q	500		
c-1,2-Dichloroethene	ND	150	ND	2,500	ND	500		
2-Butanone	19,000	300	39,000	5,000	41,000	1,000		
t-Butyl Methyl Ether (MTBE)	ND	150	ND	2,500	ND	500		
Chloroform	ND	150	ND	2,500	ND	500		
1,1,1-Trichloroethane	ND	150	ND	2,500	ND	500		
Carbon Tetrachloride	ND	150	ND	2,500	ND	500		
Benzene	1,000	150	16,000	2,500	42,000	500		
1,2-Dichloroethane	ND	150	ND	2,500	ND	500		
Trichloroethene	ND	150	ND	2,500	ND	500		
1,2-Dichloropropane	ND	150	ND	2,500	ND	500		
Bromodichloromethane	ND	150	ND	2,500	ND	500		
c-1,3-Dichloropropene	ND	150	ND	2,500	ND	500		
4-Methyl-2-Pentanone	530	150	ND	2,500	1,800	500		
Toluene	660	150	ND	2,500	2,100	500		
t-1,3-Dichloropropene	ND	150	ND	2,500	ND	500		
1,1,2-Trichloroethane	ND	150	ND	2,500	ND	500		
Tetrachloroethene	ND	150	ND	2,500	ND	500		
2-Hexanone	ND	150	ND	2,500	ND	500		
Dibromochloromethane	ND	150	ND	2,500	ND	500		

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/02/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD_BLANK						
Client Sample I.D.:	--						
Date/Time Sampled:	--						
Date/Time Analyzed:	9/2/25 15:15						
QC Batch No.:	250902MS2A1						
Analyst Initials:	RC						
Dilution Factor:	0.20						
ANALYTE	**Result ppbv**	**RL ppbv**					
Dichlorodifluoromethane (12)	ND	0.20					
Chloromethane	ND	0.20					
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20					
Vinyl Chloride	ND	0.20					
Bromomethane	ND	0.20					
Chloroethane	ND	0.20					
Trichlorofluoromethane (11)	ND	0.20					
1,1-Dichloroethene	ND	0.20					
Carbon Disulfide	ND	0.20					
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20					
Acetone	ND	0.20					
Methylene Chloride	ND	0.20					
t-1,2-Dichloroethene	ND	0.20					
1,1-Dichloroethane	ND	0.20					
Vinyl Acetate	ND Q	0.20					
c-1,2-Dichloroethene	ND	0.20					
2-Butanone	ND	0.40					
t-Butyl Methyl Ether (MTBE)	ND	0.20					
Chloroform	ND	0.20					
1,1,1-Trichloroethane	ND	0.20					
Carbon Tetrachloride	ND	0.20					
Benzene	ND	0.20					
1,2-Dichloroethane	ND	0.20					
Trichloroethene	ND	0.20					
1,2-Dichloropropane	ND	0.20					
Bromodichloromethane	ND	0.20					
c-1,3-Dichloropropene	ND	0.20					
4-Methyl-2-Pentanone	ND	0.20					
Toluene	ND	0.20					
t-1,3-Dichloropropene	ND	0.20					
1,1,2-Trichloroethane	ND	0.20					
Tetrachloroethene	ND	0.20					
2-Hexanone	ND	0.20					
Dibromochloromethane	ND	0.20					

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/02/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD_BLANK							
Client Sample I.D.:	--							
Date/Time Sampled:	--							
Date/Time Analyzed:	9/2/25 15:15							
QC Batch No.:	250902MS2A1							
Analyst Initials:	RC							
Dilution Factor:	0.20							
ANALYTE	Result ppbv	RL ppbv						
1,2-Dibromoethane	ND	0.20						
Chlorobenzene	ND	0.20						
Ethylbenzene	ND	0.20						
p,&m-Xylene	ND	0.20						
o-Xylene	ND	0.20						
Styrene	ND	0.20						
Bromoform	ND Q	0.20						
1,1,2,2-Tetrachloroethane	ND	0.20						
Benzyl Chloride	ND	0.20						
4-Ethyl Toluene	ND	0.20						
1,3,5-Trimethylbenzene	ND	0.20						
1,2,4-Trimethylbenzene	ND	0.20						
1,3-Dichlorobenzene	ND	0.20						
1,4-Dichlorobenzene	ND	0.20						
1,2-Dichlorobenzene	ND	0.20						
1,2,4-Trichlorobenzene	ND	0.20						
Hexachlorobutadiene	ND	0.20						
1,3-Butadiene	ND	1.0						
Isopropanol	ND	1.0						
n-Hexane	ND	1.0						
Ethyl Acetate	ND	1.0						
Tetrahydrofuran	ND	1.0						
Cyclohexane	ND	1.0						
Heptane	ND	1.0						
1,4-Dioxane	ND	1.0						

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Refer to Report Narrative

Reviewed/Approved By: Amika Sotelo Sanchez for   Date 9-11-25
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 250902MS2A1

Matrix: Air
Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	9/2/25 15:15			9/2/25 13:17		9/2/25 13:56					
Analyst Initials:	RC			RC		RC					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	0.20	10	9.10	91	9.31	93	2.3	70	130	30
Methylene Chloride	ND	0.20	10	9.54	95	9.74	97	2.1	70	130	30
Trichloroethene	ND	0.20	10	10.2	102	10.3	103	1.3	70	130	30
Toluene	ND	0.20	10	9.14	91	9.23	92	0.9	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	7.84	78	7.96	80	1.5	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: Annika Sotelo Sanchez for
Mark Johnson
Operations Manager

Date: 9-11-25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/02/25
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	S090202-02		S090202-03		S090202-04		S090202-05	
Client Sample I.D.:	CV-24122		CV-99		CV-113		CV-24121	
Date/Time Sampled:	9/2/25 9:30		9/2/25 9:35		9/2/25 9:40		9/2/25 9:45	
Date/Time Analyzed:	9/2/25 17:13		9/2/25 17:27		9/2/25 17:42		9/2/25 17:56	
QC Batch No.:	250902GC8A1		250902GC8A1		250902GC8A1		250902GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	ND	10	ND	10	ND	10	74	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: Annika Sotelo-Sanchez for
Mark Johnson
Operations Manager

Date 9-11-25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/02/25
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	S090202-06		S090202-07		S090202-08		S090202-10	
Client Sample I.D.:	CV-24128		CV-2334		CV-2333		CV-24127	
Date/Time Sampled:	9/2/25 10:00		9/2/25 10:05		9/2/25 10:10		9/2/25 10:20	
Date/Time Analyzed:	9/2/25 18:11		9/2/25 18:25		9/2/25 18:40		9/2/25 19:09	
QC Batch No.:	250902GC8A1		250902GC8A1		250902GC8A1		250902GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	120	10	200	10	2,200	10	480	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: Anika Sotelo Sanchez for
Mark Johnson
Operations Manager

Date 9-11-25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

QC Batch No: 250902GC8A1
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	9/2/25 9:46			9/2/25 9:03		9/2/25 9:17					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,070	106	1,060	105	0.9	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: Anita Sotelo Sanchez for
Mark Johnson
Operations Manager

Date 9-11-25

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/02/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S090202-02			S090202-03			S090202-04			S090202-05		
Client Sample I.D.:	CV-24122			CV-99			CV-113			CV-24121		
Date/Time Sampled:	9/2/25 9:30			9/2/25 9:35			9/2/25 9:40			9/2/25 9:45		
Date/Time Analyzed:	9/2/25 17:13			9/2/25 17:27			9/2/25 17:42			9/2/25 17:56		
QC Batch No.:	250902GC8A1			250902GC8A1			250902GC8A1			250902GC8A1		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	0.36 J	1.0	0.059	ND	1.0	0.059	ND	1.0	0.059	0.53 J	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: Anika Sotelo Sanchez for
Mark Johnson
Operations Manager

Date 9-11-25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/02/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S090202-06			S090202-07			S090202-08			S090202-10		
Client Sample I.D.:	CV-24128			CV-2334			CV-2333			CV-24127		
Date/Time Sampled:	9/2/25 10:00			9/2/25 10:05			9/2/25 10:10			9/2/25 10:20		
Date/Time Analyzed:	9/2/25 18:11			9/2/25 18:25			9/2/25 18:40			9/2/25 19:09		
QC Batch No.:	250902GC8A1			250902GC8A1			250902GC8A1			250902GC8A1		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	1.7	1.0	0.059	1.8	1.0	0.059	13	1.0	0.059	3.6	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: Annika Sotelo Sanchez for
Mark Johnson
Operations Manager

Date 9-11-25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

QC Batch No: 250902GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	9/2/25 9:46				9/2/25 9:03		9/2/25 9:17					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	5.26	106	5.24	106	0.2	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: Anika SoteloSanchez for
Mark Johnson
Operations Manager

Date 9-11-25

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/02/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S090202-01		S090202-02		S090202-03		S090202-04	
Client Sample I.D.:	CV-24123		CV-24122		CV-99		CV-113	
Date/Time Sampled:	9/2/25 9:20		9/2/25 9:30		9/2/25 9:35		9/2/25 9:40	
Date/Time Analyzed:	9/2/25 16:58		9/2/25 17:13		9/2/25 17:27		9/2/25 17:42	
QC Batch No.:	250902GC8A1		250902GC8A1		250902GC8A1		250902GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	45	0.010	37	0.010	66	0.010	81	0.010
Oxygen/Argon	1.7	0.50	3.7	0.50	0.89	0.50	0.81	0.50
Nitrogen	6.2	1.0	14	1.0	3.3	1.0	2.9	1.0
Methane	47	0.0010	45	0.0010	29	0.0010	15	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: Anika Sotelo Sanchez for
Mark Johnson
Operations Manager

Date 9-11-25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/02/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S090202-05		S090202-06		S090202-07		S090202-08	
Client Sample I.D.:	CV-24121		CV-24128		CV-2334		CV-2333	
Date/Time Sampled:	9/2/25 9:45		9/2/25 10:00		9/2/25 10:05		9/2/25 10:10	
Date/Time Analyzed:	9/2/25 17:56		9/2/25 18:11		9/2/25 18:25		9/2/25 18:40	
QC Batch No.:	250902GC8A1		250902GC8A1		250902GC8A1		250902GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	70	0.010	36	0.010	56	0.010	54	0.010
Oxygen/Argon	1.2	0.50	2.7	0.50	0.63	0.50	6.4	0.50
Nitrogen	4.4	1.0	37	1.0	3.0	1.0	24	1.0
Methane	24	0.0010	23	0.0010	39	0.0010	1.5	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: Amila Sotelo Sanchez for
Mark Johnson
Operations Manager

Date 9-12-25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/02/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S090202-09		S090202-10					
Client Sample I.D.:	CV-24126		CV-24127					
Date/Time Sampled:	9/2/25 10:15		9/2/25 10:20					
Date/Time Analyzed:	9/2/25 18:54		9/2/25 19:09					
QC Batch No.:	250902GC8A1		250902GC8A1					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v				
Carbon Dioxide	33	0.010	31	0.010				
Oxygen/Argon	9.8	0.50	8.6	0.50				
Nitrogen	46	1.0	44	1.0				
Methane	3.4	0.0010	13	0.0010				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: Anika Sotelo Sanchez for
Mark Johnson
Operations Manager

Date 9-12-25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

QC Batch No: 250902GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	9/2/25 9:46			9/2/25 9:03		9/2/25 9:17					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	10.0	100	9.98	100	0.3	70	130	30
Oxygen/Argon	ND	0.50	15	15.0	100	15.0	100	0.0	70	130	30
Nitrogen	ND	1.0	70	72.4	104	72.4	104	0.0	70	130	30
Methane	ND	0.0010	0.10	0.104	103	0.103	102	1.1	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: Annika Sotelo Sanchez for
Mark Johnson
Operations Manager

Date 9-11-25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.

September 15, 2025

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175

TX Cert T104704450-14-6
EPA Methods TO14A, TO15

ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference:	Chiquita Canyon Landfill
Project Number:	07224200.24 Task 1
Lab Number:	S090301-01/09

Enclosed are the results for sample(s) received 9/3/25 by Air Technology. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Vinyl acetate and bromoform exhibited low recovery in the initial calibration verification indicating possible low bias. Results have been flagged with the Q qualifier.
- Ethyl acetate exhibited high recovery in the initial calibration verification indicating a possible high bias. Results have been flagged with the Q qualifier.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Jenny Kim, Art Jones and Ali Ferrara on 9/12/25.

ATL appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Amika Soldsanchez for

Mark Johnson
Operations Manager
MJohnson@AirTechLabs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 100
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

TURNAROUND TIME

Standard	☒	48 hours	☐
Same Day	☐	72 hours	☐
24 hours	☐	96 hours	☐
Other:			

DELIVERABLES

EDD	☒
EDF	☐
Level 3	☐
Level 4	☐

PAGE: 1 **OF**

Condition upon receipt:
Sealed Yes ☐ No ☐
Intact Yes ☐ No ☐
Chilled ______ deg C

BILLING

P.O. No.: 07-SO05310
Bill to:
07FSAccountspayable@scsengineers.com
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
S090301-01	CV-24125	9/3/2025	8:50AM	1L	Gas	N	X	X	X			
-02	CV-24134	9/3/2025	9:20AM	1L	Gas	N	X					
-03	CV-24064	9/3/2025	10:50AM	1L	Gas	N	x	x	x			
-04	CV-2007	9/3/2025	9:40AM	2-1L	Gas	N	X	X	X	X		
-05	CV-24049	9/3/2025	9:45AM	1L	Gas	N	X	X	X			
-06	CV-24065	9/3/2025	9:55AM	2-1L	Gas	N	X	X	X	X		
-07	CV-2305	9/3/2025	10:30AM	1L	Gas	N	X	X	X			
-08	CV-2315	9/3/2025	10:40AM	2-1L	Gas	N	X	X	X	X		
-09	CV-24055	9/3/2025	9:50AM	1L	Gas	N	X	X	X			

AUTHORIZATION TO PERFORM WORK	COMPANY	DATE/TIME	
SAMPLED BY Antonio A	COMPANY SCS	DATE/TIME 9/3/25 11:00am	
RELINQUISHED BY Antonio Ambriz	DATE/TIME 9/3/25 11:40am	RECEIVED BY Rubican 6	DATE/TIME 9/3/25 11:40
RELINQUISHED BY Rubican 6	DATE/TIME 9/3/25 13:00	RECEIVED BY [illegible]	DATE/TIME 9/3/25 13:00
RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other________

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

Client:	**SCS Engineers**
Attn:	**Cornelius Fong**
Project Name:	**Chiquita Canyon Landfill**
Project No.:	**07224200.24 Task 1**
Date Received:	**09/03/25**
Matrix:	**Air**
Reporting Units:	**ppbv**

EPA Method TO-15

Lab No.:	S090301-04		S090301-06		S090301-08			
Client Sample I.D.:	CV-2007		CV-24065		CV-2315			
Date/Time Sampled:	9/3/25 9:40		9/3/25 9:55		9/3/25 10:40			
Date/Time Analyzed:	9/3/25 20:08		9/3/25 20:49		9/3/25 21:30			
QC Batch No.:	250903MS2A1		250903MS2A1		250903MS2A1			
Analyst Initials:	RC		RC		RC			
Dilution Factor:	1,300		600		4,000			
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv		
Dichlorodifluoromethane (12)	ND	1,300	ND	600	ND	4,000		
Chloromethane	ND	1,300	ND	600	ND	4,000		
1,2-Cl-1,1,2,2-F ethane (114)	ND	1,300	ND	600	ND	4,000		
Vinyl Chloride	ND	1,300	ND	600	ND	4,000		
Bromomethane	ND	1,300	ND	600	ND	4,000		
Chloroethane	ND	6,300	ND	3,000	ND	20,000		
Trichlorofluoromethane (11)	ND	1,300	ND	600	ND	4,000		
1,1-Dichloroethene	ND	1,300	ND	600	ND	4,000		
Carbon Disulfide	ND	1,300	ND	600	ND	4,000		
1,1,2-Cl 1,2,2-F ethane (113)	ND	1,300	ND	600	ND	4,000		
Acetone	170,000	8,800	77,000	4,200	520,000	28,000		
Methylene Chloride	ND	1,300	ND	600	ND	4,000		
t-1,2-Dichloroethene	ND	1,300	ND	600	ND	4,000		
1,1-Dichloroethane	ND	1,300	ND	600	ND	4,000		
Vinyl Acetate	ND Q	1,300	ND Q	600	ND Q	4,000		
c-1,2-Dichloroethene	ND	1,300	ND	600	ND	4,000		
2-Butanone	77,000	6,300	50,000	3,000	310,000	20,000		
t-Butyl Methyl Ether (MTBE)	ND	1,300	ND	600	ND	4,000		
Chloroform	ND	1,300	ND	600	ND	4,000		
1,1,1-Trichloroethane	ND	1,300	ND	600	ND	4,000		
Carbon Tetrachloride	ND	1,300	ND	600	ND	4,000		
Benzene	63,000	1,300	17,000	600	210,000	4,000		
1,2-Dichloroethane	ND	1,300	ND	600	ND	4,000		
Trichloroethene	ND	1,300	ND	600	ND	4,000		
1,2-Dichloropropane	ND	1,300	ND	600	ND	4,000		
Bromodichloromethane	ND	1,300	ND	600	ND	4,000		
c-1,3-Dichloropropene	ND	1,300	ND	600	ND	4,000		
4-Methyl-2-Pentanone	1,600	1,300	940	600	4,900	4,000		
Toluene	2,100	1,300	1,500	600	8,600	4,000		
t-1,3-Dichloropropene	ND	2,500	ND	1,200	ND	8,000		
1,1,2-Trichloroethane	ND	1,300	ND	600	ND	4,000		
Tetrachloroethene	ND	1,300	ND	600	ND	4,000		
2-Hexanone	ND	1,300	ND	600	ND	4,000		
Dibromochloromethane	ND	1,300	ND	600	ND	4,000		

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client:	**SCS Engineers**
Attn:	**Cornelius Fong**
Project Name:	**Chiquita Canyon Landfill**
Project No.:	**07224200.24 Task 1**
Date Received:	**09/03/25**
Matrix:	**Air**
Reporting Units:	**ppbv**

EPA Method TO-15

Lab No.:	S090301-04		S090301-06		S090301-08			
Client Sample I.D.:	CV-2007		CV-24065		CV-2315			
Date/Time Sampled:	9/3/25 9:40		9/3/25 9:55		9/3/25 10:40			
Date/Time Analyzed:	9/3/25 20:08		9/3/25 20:49		9/3/25 21:30			
QC Batch No.:	250903MS2A1		250903MS2A1		250903MS2A1			
Analyst Initials:	RC		RC		RC			
Dilution Factor:	1,300		600		4,000			
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv		
1,2-Dibromoethane	ND	1,300	ND	600	ND	4,000		
Chlorobenzene	ND	1,300	ND	600	ND	4,000		
Ethylbenzene	ND	1,300	ND	600	ND	4,000		
p,&m-Xylene	ND	2,500	ND	1,200	ND	8,000		
o-Xylene	ND	1,300	ND	600	ND	4,000		
Styrene	ND	1,300	ND	600	ND	4,000		
Bromoform	ND Q	1,300	ND Q	600	ND Q	4,000		
1,1,2,2-Tetrachloroethane	ND	1,300	ND	600	ND	4,000		
Benzyl Chloride	ND	1,300	ND	600	ND	4,000		
4-Ethyl Toluene	ND	1,300	ND	600	ND	4,000		
1,3,5-Trimethylbenzene	ND	1,300	ND	600	ND	4,000		
1,2,4-Trimethylbenzene	ND	1,300	ND	600	ND	4,000		
1,3-Dichlorobenzene	ND	1,300	ND	600	ND	4,000		
1,4-Dichlorobenzene	ND	1,300	ND	600	ND	4,000		
1,2-Dichlorobenzene	ND	1,300	ND	600	ND	4,000		
1,2,4-Trichlorobenzene	ND	2,500	ND	1,200	ND	8,000		
Hexachlorobutadiene	ND	1,300	ND	600	ND	4,000		
1,3-Butadiene	ND	6,300	**5,300**	3,000	ND	20,000		
Isopropanol	**43,000**	6,300	**24,000**	3,000	**150,000**	20,000		
n-Hexane	ND	6,300	ND	3,000	ND	20,000		
Ethyl Acetate	ND	6,300	**3,900** Q	3,000	**21,000** Q	20,000		
Tetrahydrofuran	**64,000**	6,300	**23,000**	3,000	**270,000**	20,000		
Cyclohexane	ND	6,300	ND	3,000	ND	20,000		
Heptane	ND	6,300	ND	3,000	ND	20,000		
1,4-Dioxane	ND	6,300	ND	3,000	ND	20,000		

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Refer to Report Narrative

Reviewed/Approved By: Annika Sotelo Sanchez for
Mark Johnson
Operations Manager

Date 9-12-25

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/03/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD_BLANK							
Client Sample I.D.:	--							
Date/Time Sampled:	--							
Date/Time Analyzed:	9/3/25 12:18							
QC Batch No.:	250903MS2A1							
Analyst Initials:	RC							
Dilution Factor:	0.20							
ANALYTE	Result ppbv	RL ppbv						
Dichlorodifluoromethane (12)	ND	0.20						
Chloromethane	ND	0.20						
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20						
Vinyl Chloride	ND	0.20						
Bromomethane	ND	0.20						
Chloroethane	ND	1.0						
Trichlorofluoromethane (11)	ND	0.20						
1,1-Dichloroethene	ND	0.20						
Carbon Disulfide	ND	0.20						
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20						
Acetone	ND	1.4						
Methylene Chloride	ND	0.20						
t-1,2-Dichloroethene	ND	0.20						
1,1-Dichloroethane	ND	0.20						
Vinyl Acetate	ND Q	0.20						
c-1,2-Dichloroethene	ND	0.20						
2-Butanone	ND	1.0						
t-Butyl Methyl Ether (MTBE)	ND	0.20						
Chloroform	ND	0.20						
1,1,1-Trichloroethane	ND	0.20						
Carbon Tetrachloride	ND	0.20						
Benzene	ND	0.20						
1,2-Dichloroethane	ND	0.20						
Trichloroethene	ND	0.20						
1,2-Dichloropropane	ND	0.20						
Bromodichloromethane	ND	0.20						
c-1,3-Dichloropropene	ND	0.20						
4-Methyl-2-Pentanone	ND	0.20						
Toluene	ND	0.20						
t-1,3-Dichloropropene	ND	0.40						
1,1,2-Trichloroethane	ND	0.20						
Tetrachloroethene	ND	0.20						
2-Hexanone	ND	0.20						
Dibromochloromethane	ND	0.20						

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/03/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD_BLANK							
Client Sample I.D.:	--							
Date/Time Sampled:	--							
Date/Time Analyzed:	9/3/25 12:18							
QC Batch No.:	250903MS2A1							
Analyst Initials:	RC							
Dilution Factor:	0.20							
ANALYTE	Result ppbv	RL ppbv						
1,2-Dibromoethane	ND	0.20						
Chlorobenzene	ND	0.20						
Ethylbenzene	ND	0.20						
p,&m-Xylene	ND	0.40						
o-Xylene	ND	0.20						
Styrene	ND	0.20						
Bromoform	ND Q	0.20						
1,1,2,2-Tetrachloroethane	ND	0.20						
Benzyl Chloride	ND	0.20						
4-Ethyl Toluene	ND	0.20						
1,3,5-Trimethylbenzene	ND	0.20						
1,2,4-Trimethylbenzene	ND	0.20						
1,3-Dichlorobenzene	ND	0.20						
1,4-Dichlorobenzene	ND	0.20						
1,2-Dichlorobenzene	ND	0.20						
1,2,4-Trichlorobenzene	ND	0.40						
Hexachlorobutadiene	ND	0.20						
1,3-Butadiene	ND	1.0						
Isopropanol	ND	1.0						
n-Hexane	ND	1.0						
Ethyl Acetate	ND	1.0						
Tetrahydrofuran	ND	1.0						
Cyclohexane	ND	1.0						
Heptane	ND	1.0						
1,4-Dioxane	ND	1.0						

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Refer to Report Narrative

Reviewed/Approved By: Anika Sotelo Sanchez for
Mark Johnson
Operations Manager

Date 9-12-25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 250903MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	9/3/25 12:18			9/3/25 5:14		9/3/25 5:55					
Analyst Initials:	RC			RC		RC					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	0.20	10	9.55	96	9.79	98	2.4	70	130	30
Methylene Chloride	ND	0.20	10	9.71	97	9.79	98	0.8	70	130	30
Trichloroethene	ND	0.20	10	10.1	101	10.2	102	0.5	70	130	30
Toluene	ND	0.20	10	9.20	92	9.08	91	1.3	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	7.77	78	7.90	79	1.6	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: Anika Sotelo Sanchez for
Mark Johnson
Operations Manager

Date: 9-12-25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/03/25
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	S090301-01		S090301-03		S090301-04		S090301-05	
Client Sample I.D.:	CV-24125		CV-24064		CV-2007		CV-24049	
Date/Time Sampled:	9/3/25 8:50		9/3/25 10:50		9/3/25 9:40		9/3/25 9:45	
Date/Time Analyzed:	9/3/25 15:14		9/3/25 15:43		9/3/25 15:58		9/3/25 16:12	
QC Batch No.:	250903GC8A1		250903GC8A1		250903GC8A1		250903GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	36	10	2,500	10	33	10	2,500	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: Annika Sotelo Sanchez for
Mark Johnson
Operations Manager

Date 9-12-25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/03/25
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	S090301-06		S090301-07		S090301-08		S090301-09	
Client Sample I.D.:	CV-24065		CV-2305		CV-2315		CV-24055	
Date/Time Sampled:	9/3/25 9:55		9/3/25 10:30		9/3/25 10:40		9/3/25 9:50	
Date/Time Analyzed:	9/3/25 16:27		9/3/25 16:41		9/3/25 16:56		9/3/25 17:10	
QC Batch No.:	250903GC8A1		250903GC8A1		250903GC8A1		250903GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	180	10	1,400	10	1,700	10	870	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: Annika Sotelo Sanchez for
Mark Johnson
Operations Manager

Date 9-12-25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

QC Batch No: 250903GC8A1
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD			Limits		
Date Analyzed:	9/3/25 8:51			9/3/25 14:45		9/3/25 14:59					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0					
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,100	109	1,080	107	1.2	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: Annika Sotelo Sanchez for
Mark Johnson
Operations Manager

Date 9-12-25

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/03/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S090301-01			S090301-03			S090301-04			S090301-05		
Client Sample I.D.:	CV-24125			CV-24064			CV-2007			CV-24049		
Date/Time Sampled:	9/3/25 8:50			9/3/25 10:50			9/3/25 9:40			9/3/25 9:45		
Date/Time Analyzed:	9/3/25 15:14			9/3/25 15:43			9/3/25 15:58			9/3/25 16:12		
QC Batch No.:	250903GC8A1			250903GC8A1			250903GC8A1			250903GC8A1		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	**Result % v/v**	**RL % v/v**	**MDL % v/v**	**Result % v/v**	**RL % v/v**	**MDL % v/v**	**Result % v/v**	**RL % v/v**	**MDL % v/v**	**Result % v/v**	**RL % v/v**	**MDL % v/v**
Hydrogen	**0.38 J**	1.0	0.059	**13**	1.0	0.059	**0.46 J**	1.0	0.059	**16**	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: Anika Sotelo Sanchez for
Mark Johnson
Operations Manager

Date 9-12-25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/03/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S090301-06			S090301-07			S090301-08			S090301-09		
Client Sample I.D.:	CV-24065			CV-2305			CV-2315			CV-24055		
Date/Time Sampled:	9/3/25 9:55			9/3/25 10:30			9/3/25 10:40			9/3/25 9:50		
Date/Time Analyzed:	9/3/25 16:27			9/3/25 16:41			9/3/25 16:56			9/3/25 17:10		
QC Batch No.:	250903GC8A1			250903GC8A1			250903GC8A1			250903GC8A1		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	0.67 J	1.0	0.059	5.2	1.0	0.059	8.2	1.0	0.059	8.6	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: Annika Sotelo Sanchez for
Mark Johnson
Operations Manager

Date 9-12-25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

QC Batch No: 250903GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	9/3/25 8:51				9/3/25 14:45		9/3/25 14:59					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	4.91	99	4.85	98	1.2	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: Annika Sotelo Sanchez for
Mark Johnson
Operations Manager

Date 9-12-25

The cover letter is an integral part of this analytical report

18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/03/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S090301-01		S090301-02		S090301-03		S090301-04	
Client Sample I.D.:	CV-24125		CV-24134		CV-24064		CV-2007	
Date/Time Sampled:	9/3/25 8:50		9/3/25 9:20		9/3/25 10:50		9/3/25 9:40	
Date/Time Analyzed:	9/3/25 15:14		9/3/25 15:29		9/3/25 15:43		9/3/25 15:58	
QC Batch No.:	250903GC8A1		250903GC8A1		250903GC8A1		250903GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	51	0.010	56	0.010	77	0.010	29	0.010
Oxygen/Argon	1.4	0.50	0.88	0.50	1.3	0.50	13	0.50
Nitrogen	8.3	1.0	3.3	1.0	4.5	1.0	48	1.0
Methane	39	0.0010	37	0.0010	2.2	0.0010	10	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: Anika Sotelo Sanchez for
Mark Johnson
Operations Manager

Date 9-12-25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/03/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S090301-05		S090301-06		S090301-07		S090301-08	
Client Sample I.D.:	CV-24049		CV-24065		CV-2305		CV-2315	
Date/Time Sampled:	9/3/25 9:45		9/3/25 9:55		9/3/25 10:30		9/3/25 10:40	
Date/Time Analyzed:	9/3/25 16:12		9/3/25 16:27		9/3/25 16:41		9/3/25 16:56	
QC Batch No.:	250903GC8A1		250903GC8A1		250903GC8A1		250903GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	73	0.010	76	0.010	69	0.010	79	0.010
Oxygen/Argon	1.5	0.50	0.57	0.50	1.2	0.50	0.74	0.50
Nitrogen	5.7	1.0	2.1	1.0	9.0	1.0	2.7	1.0
Methane	1.8	0.0010	21	0.0010	16	0.0010	8.0	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: [signature] for
Mark Johnson
Operations Manager

Date 9-12-25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/03/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S090301-09							
Client Sample I.D.:	CV-24055							
Date/Time Sampled:	9/3/25 9:50							
Date/Time Analyzed:	9/3/25 17:10							
QC Batch No.:	250903GC8A1							
Analyst Initials:	KD							
Dilution Factor:	1.0							
ANALYTE	**Result % v/v**	**RL % v/v**						
Carbon Dioxide	51	0.010						
Oxygen/Argon	3.4	0.50						
Nitrogen	21	1.0						
Methane	16	0.0010						

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: Amika Sotelo Sanchez for
Mark Johnson
Operations Manager

Date 9-12-25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

QC Batch No: 250903GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	9/3/25 8:51			9/3/25 14:45		9/3/25 14:59					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	9.86	98	9.69	97	1.7	70	130	30
Oxygen/Argon	ND	0.50	15	15.2	101	15.1	101	0.5	70	130	30
Nitrogen	ND	1.0	70	73.0	105	72.6	104	0.5	70	130	30
Methane	ND	0.0010	0.10	0.106	105	0.105	104	1.6	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: Annika Sotelo Sanchez for
Mark Johnson
Operations Manager

Date 9-12-25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.

September 24, 2025

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175

TX Cert T104704450-14-6
EPA Methods TO14A, TO15

ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference:	Chiquita Canyon Landfill
Project Number:	07224200.24 Task 1
Lab Number:	S090403-01/11

Enclosed are the results for sample(s) received 9/4/25 by Air Technology. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags. Vinyl acetate and bromoform exhibited low recoveries in the initial calibration verification indicating possible low bias. Results are flagged with the Q qualifier. Ethyl acetate exhibited high recovery in the initial calibration verification indicating a high bias. Results above the reporting limit are flagged with the Q qualifier.
- The closing continuing calibration verification for ASTM D1946 exhibited high recovery for the lower detection of carbon dioxide and methane. Results were confirmed outside of holding -time and are flagged with the Q qualifier.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Jenny Kim, Art Jones and Ali Ferrara on 9/23/25.

ATL appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Anika Sotelo Sanchez for

Mark Johnson
Operations Manager
MJohnson@AirTechLabs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐ No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐ No ☐
Other:				Level 4	☐	Chilled ______ deg C

Project No.: 07224200.24 Task 1
Project Name: Chiquita Canyon Landfill
Report To: Cornelius Fong
Company: SCS Engineers
Street: 3900 Kilroy Airport Way, Suite 100
City/State/Zip: Long Beach, CA 90806-6816
Phone& Fax: 562-743-7895
e-mail: cfong@scsengineers.com

BILLING
P.O. No.: 07-SO05310
Bill to:
07FSAccountspayable@scsengineers.com
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
S090403-01	CV-2351	9/4/2025	9:00AM	2-1L	Gas	N	X	X	X	X		
-02	CV-24141	9/4/2025	9:10AM	1L	Gas	N	X	X	X			
-03	CV-24143	9/4/2025	9:15AM	2-1L	Gas	N	X	X	X	X		
-04	CV-24140	9/4/2025	9:20AM	2-1L	Gas	N	X	X	X	X		
-05	CV-24139	9/4/2025	9:25AM	2-1L	Gas	N	X	X	X	X		
-06	CV-24138	9/4/2025	9:30AM	2-1L	Gas	N	X	X	X	X		
-07	CV-2354	9/4/2025	9:35AM	1L	Gas	N	X	X	X			
-08	CV-2349	9/4/2025	9:40AM	1L	Gas	N	X	X	X			
-09	CV-24144	9/4/2025	9:45AM	1L	Gas	N	X					
-10	CV-2002	9/4/2025	9:55AM	2-1L	Gas	N	X	X	X	X		

AUTHORIZATION TO PERFORM WORK	COMPANY			DATE/TIME
SAMPLED BY Antonio Ambriz	COMPANY SCS			DATE/TIME 9/4/25 11:00 am
RELINQUISHED BY [signature]	DATE/TIME 9/4/25 11:17am	RECEIVED BY [signature]		DATE/TIME 9/4/25 11:00
RELINQUISHED BY [signature]	DATE/TIME 9/4/25 12:28	RECEIVED BY [signature]		DATE/TIME 9/4/25 12:28
RELINQUISHED BY	DATE/TIME	RECEIVED BY		DATE/TIME

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other________

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF			
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:			
Same Day	☐	72 hours	☐	EDF	☐	Sealed	Yes ☐	No ☐	
24 hours	☐	96 hours	☐	Level 3	☐	Intact	Yes ☐	No ☐	
Other:				Level 4	☐	Chilled	______ deg C		

Project No.: 07224200.24 Task 1
Project Name: Chiquita Canyon Landfill
Report To: Cornelius Fong
Company: SCS Engineers
Street: 3900 Kilroy Airport Way, Suite 100
City/State/Zip: Long Beach, CA 90806-6816
Phone& Fax: 562-743-7895
e-mail: cfong@scsengineers.com

BILLING
P.O. No.: 07-SO05310
Bill to:
07FSAccountspayable@scsengineers.com
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
S090403-11	CV-2352	9/4/2025	9:28AM	1L	Gas	N	X	X	X			
				1L	Gas	N						
				1L	Gas	N						
				1L	Gas	N						
				1L	Gas	N						
				1L	Gas	N						
				1L	Gas	N						
				1L	Gas	N						
				1L	Gas	N						
				1L	Gas	N						

AUTHORIZATION TO PERFORM WORK		COMPANY	DATE/TIME
SAMPLED BY Antonio Ambriz		COMPANY SCS	DATE/TIME 9/4/25 11:00 am
RELINQUISHED BY [signature]	DATE/TIME 9/4/25 11:13am	RECEIVED BY [signature]	DATE/TIME 9/4/25 11:16 AM
RELINQUISHED BY [signature]	DATE/TIME 9/4/25 12:28	RECEIVED BY [signature]	DATE/TIME 9/4/25 12:28
RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other________

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/04/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	S090403-01		S090403-03		S090403-04		S090403-05	
Client Sample I.D.:	CV-2351		CV-24143		CV-24140		CV-24139	
Date/Time Sampled:	9/4/25 9:00		9/4/25 9:15		9/4/25 9:20		9/4/25 9:25	
Date/Time Analyzed:	9/4/25 19:58		9/4/25 20:37		9/4/25 21:17		9/4/25 21:58	
QC Batch No.:	250904MS2A1		250904MS2A1		250904MS2A1		250904MS2A1	
Analyst Initials:	RC		RC		RC		RC	
Dilution Factor:	4,000		10,000		8,000		2,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	4,000	ND	10,000	ND	8,000	ND	2,000
Chloromethane	ND	4,000	ND	10,000	ND	8,000	ND	2,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	4,000	ND	10,000	ND	8,000	ND	2,000
Vinyl Chloride	ND	4,000	ND	10,000	ND	8,000	ND	2,000
Bromomethane	ND	4,000	ND	10,000	ND	8,000	ND	2,000
Chloroethane	ND	20,000	ND	50,000	ND	40,000	ND	10,000
Trichlorofluoromethane (11)	ND	4,000	ND	10,000	ND	8,000	ND	2,000
1,1-Dichloroethene	ND	4,000	ND	10,000	ND	8,000	ND	2,000
Carbon Disulfide	**4,200**	4,000	ND	10,000	ND	8,000	ND	2,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	4,000	ND	10,000	ND	8,000	ND	2,000
Acetone	**46,000**	28,000	**1,400,000**	70,000	**840,000**	56,000	**190,000**	14,000
Methylene Chloride	ND	4,000	ND	10,000	ND	8,000	ND	2,000
t-1,2-Dichloroethene	ND	4,000	ND	10,000	ND	8,000	ND	2,000
1,1-Dichloroethane	ND	4,000	ND	10,000	ND	8,000	ND	2,000
Vinyl Acetate	ND Q	4,000	ND Q	10,000	ND Q	8,000	ND Q	2,000
c-1,2-Dichloroethene	ND	4,000	ND	10,000	ND	8,000	ND	2,000
2-Butanone	ND	20,000	**830,000**	50,000	**500,000**	40,000	**120,000**	10,000
t-Butyl Methyl Ether (MTBE)	ND	4,000	ND	10,000	ND	8,000	ND	2,000
Chloroform	ND	4,000	ND	10,000	ND	8,000	ND	2,000
1,1,1-Trichloroethane	ND	4,000	ND	10,000	ND	8,000	ND	2,000
Carbon Tetrachloride	ND	4,000	ND	10,000	ND	8,000	ND	2,000
Benzene	ND	4,000	**290,000**	10,000	**200,000**	8,000	**20,000**	2,000
1,2-Dichloroethane	ND	4,000	ND	10,000	ND	8,000	ND	2,000
Trichloroethene	ND	4,000	ND	10,000	ND	8,000	ND	2,000
1,2-Dichloropropane	ND	4,000	ND	10,000	ND	8,000	ND	2,000
Bromodichloromethane	ND	4,000	ND	10,000	ND	8,000	ND	2,000
c-1,3-Dichloropropene	ND	4,000	ND	10,000	ND	8,000	ND	2,000
4-Methyl-2-Pentanone	ND	4,000	**10,000**	10,000	ND	8,000	**2,000**	2,000
Toluene	ND	4,000	**11,000**	10,000	ND	8,000	ND	2,000
t-1,3-Dichloropropene	ND	8,000	ND	20,000	ND	16,000	ND	4,000
1,1,2-Trichloroethane	ND	4,000	ND	10,000	ND	8,000	ND	2,000
Tetrachloroethene	ND	4,000	ND	10,000	ND	8,000	ND	2,000
2-Hexanone	ND	4,000	ND	10,000	ND	8,000	ND	2,000
Dibromochloromethane	ND	4,000	ND	10,000	ND	8,000	ND	2,000

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/04/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	S090403-01		S090403-03		S090403-04		S090403-05	
Client Sample I.D.:	CV-2351		CV-24143		CV-24140		CV-24139	
Date/Time Sampled:	9/4/25 9:00		9/4/25 9:15		9/4/25 9:20		9/4/25 9:25	
Date/Time Analyzed:	9/4/25 19:58		9/4/25 20:37		9/4/25 21:17		9/4/25 21:58	
QC Batch No.:	250904MS2A1		250904MS2A1		250904MS2A1		250904MS2A1	
Analyst Initials:	RC		RC		RC		RC	
Dilution Factor:	4,000		10,000		8,000		2,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	4,000	ND	10,000	ND	8,000	ND	2,000
Chlorobenzene	ND	4,000	ND	10,000	ND	8,000	ND	2,000
Ethylbenzene	ND	4,000	ND	10,000	ND	8,000	ND	2,000
p,&m-Xylene	ND	8,000	ND	20,000	ND	16,000	ND	4,000
o-Xylene	ND	4,000	ND	10,000	ND	8,000	ND	2,000
Styrene	ND	4,000	ND	10,000	ND	8,000	ND	2,000
Bromoform	ND Q	4,000	ND Q	10,000	ND Q	8,000	ND Q	2,000
1,1,2,2-Tetrachloroethane	ND	4,000	ND	10,000	ND	8,000	ND	2,000
Benzyl Chloride	ND	4,000	ND	10,000	ND	8,000	ND	2,000
4-Ethyl Toluene	ND	4,000	ND	10,000	ND	8,000	ND	2,000
1,3,5-Trimethylbenzene	ND	4,000	ND	10,000	ND	8,000	ND	2,000
1,2,4-Trimethylbenzene	ND	4,000	ND	10,000	ND	8,000	ND	2,000
1,3-Dichlorobenzene	ND	4,000	ND	10,000	ND	8,000	ND	2,000
1,4-Dichlorobenzene	ND	4,000	ND	10,000	ND	8,000	ND	2,000
1,2-Dichlorobenzene	ND	4,000	ND	10,000	ND	8,000	ND	2,000
1,2,4-Trichlorobenzene	ND	8,000	ND	20,000	ND	16,000	ND	4,000
Hexachlorobutadiene	ND	4,000	ND	10,000	ND	8,000	ND	2,000
1,3-Butadiene	ND	20,000	ND	50,000	ND	40,000	ND	10,000
Isopropanol	25,000	20,000	110,000	50,000	97,000	40,000	57,000	10,000
n-Hexane	ND	20,000	ND	50,000	ND	40,000	ND	10,000
Ethyl Acetate	ND	20,000	50,000 Q	50,000	ND	40,000	ND	10,000
Tetrahydrofuran	ND	20,000	910,000	50,000	540,000	40,000	99,000	10,000
Cyclohexane	ND	20,000	ND	50,000	ND	40,000	ND	10,000
Heptane	ND	20,000	ND	50,000	ND	40,000	ND	10,000
1,4-Dioxane	ND	20,000	ND	50,000	ND	40,000	ND	10,000

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Refer to Report Narrative

Reviewed/Approved By: ______ Date 9/23/25
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client:	SCS Engineers
Attn:	Cornelius Fong
Project Name:	Chiquita Canyon Landfill
Project No.:	07224200.24 Task 1
Date Received:	09/04/25
Matrix:	Air
Reporting Units:	ppbv

EPA Method TO-15

Lab No.:	S090403-06		S090403-10					
Client Sample I.D.:	CV-24138		CV-2002					
Date/Time Sampled:	9/4/25 9:30		9/4/25 9:55					
Date/Time Analyzed:	9/4/25 22:40		9/4/25 23:22					
QC Batch No.:	250904MS2A1		250904MS2A1					
Analyst Initials:	RC		RC					
Dilution Factor:	1,400		2,000					
ANALYTE	**Result ppbv**	**RL ppbv**	**Result ppbv**	**RL ppbv**				
Dichlorodifluoromethane (12)	ND	1,400	ND	2,000				
Chloromethane	ND	1,400	ND	2,000				
1,2-Cl-1,1,2,2-F ethane (114)	ND	1,400	ND	2,000				
Vinyl Chloride	ND	1,400	ND	2,000				
Bromomethane	ND	1,400	ND	2,000				
Chloroethane	ND	7,000	ND	10,000				
Trichlorofluoromethane (11)	ND	1,400	ND	2,000				
1,1-Dichloroethene	ND	1,400	ND	2,000				
Carbon Disulfide	ND	1,400	ND	2,000				
1,1,2-Cl 1,2,2-F ethane (113)	ND	1,400	ND	2,000				
Acetone	**120,000**	9,800	**160,000**	14,000				
Methylene Chloride	ND	1,400	ND	2,000				
t-1,2-Dichloroethene	ND	1,400	ND	2,000				
1,1-Dichloroethane	ND	1,400	ND	2,000				
Vinyl Acetate	ND Q	1,400	ND Q	2,000				
c-1,2-Dichloroethene	ND	1,400	ND	2,000				
2-Butanone	**71,000**	7,000	**96,000**	10,000				
t-Butyl Methyl Ether (MTBE)	ND	1,400	ND	2,000				
Chloroform	ND	1,400	ND	2,000				
1,1,1-Trichloroethane	ND	1,400	ND	2,000				
Carbon Tetrachloride	ND	1,400	ND	2,000				
Benzene	**12,000**	1,400	**38,000**	2,000				
1,2-Dichloroethane	ND	1,400	ND	2,000				
Trichloroethene	ND	1,400	ND	2,000				
1,2-Dichloropropane	ND	1,400	ND	2,000				
Bromodichloromethane	ND	1,400	ND	2,000				
c-1,3-Dichloropropene	ND	1,400	ND	2,000				
4-Methyl-2-Pentanone	ND	1,400	ND	2,000				
Toluene	ND	1,400	ND	2,000				
t-1,3-Dichloropropene	ND	2,800	ND	4,000				
1,1,2-Trichloroethane	ND	1,400	ND	2,000				
Tetrachloroethene	ND	1,400	ND	2,000				
2-Hexanone	ND	1,400	ND	2,000				
Dibromochloromethane	ND	1,400	ND	2,000				

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/04/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	S090403-06		S090403-10					
Client Sample I.D.:	CV-24138		CV-2002					
Date/Time Sampled:	9/4/25 9:30		9/4/25 9:55					
Date/Time Analyzed:	9/4/25 22:40		9/4/25 23:22					
QC Batch No.:	250904MS2A1		250904MS2A1					
Analyst Initials:	RC		RC					
Dilution Factor:	1,400		2,000					
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv				
1,2-Dibromoethane	ND	1,400	ND	2,000				
Chlorobenzene	ND	1,400	ND	2,000				
Ethylbenzene	ND	1,400	ND	2,000				
p,&m-Xylene	ND	2,800	ND	4,000				
o-Xylene	ND	1,400	ND	2,000				
Styrene	ND	1,400	ND	2,000				
Bromoform	ND Q	1,400	ND Q	2,000				
1,1,2,2-Tetrachloroethane	ND	1,400	ND	2,000				
Benzyl Chloride	ND	1,400	ND	2,000				
4-Ethyl Toluene	ND	1,400	ND	2,000				
1,3,5-Trimethylbenzene	ND	1,400	ND	2,000				
1,2,4-Trimethylbenzene	ND	1,400	ND	2,000				
1,3-Dichlorobenzene	ND	1,400	ND	2,000				
1,4-Dichlorobenzene	ND	1,400	ND	2,000				
1,2-Dichlorobenzene	ND	1,400	ND	2,000				
1,2,4-Trichlorobenzene	ND	2,800	ND	4,000				
Hexachlorobutadiene	ND	1,400	ND	2,000				
1,3-Butadiene	ND	7,000	ND	10,000				
Isopropanol	28,000	7,000	69,000	10,000				
n-Hexane	ND	7,000	ND	10,000				
Ethyl Acetate	ND	7,000	ND	10,000				
Tetrahydrofuran	51,000	7,000	60,000	10,000				
Cyclohexane	ND	7,000	ND	10,000				
Heptane	ND	7,000	ND	10,000				
1,4-Dioxane	ND	7,000	ND	10,000				

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Refer to Report Narrative

Reviewed/Approved By: ____ Date 9/23/25
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client:	SCS Engineers
Attn:	Cornelius Fong
Project Name:	Chiquita Canyon Landfill
Project No.:	07224200.24 Task 1
Date Received:	09/04/25
Matrix:	Air
Reporting Units:	ppbv

EPA Method TO-15

Lab No.:	METHOD_BLANK							
Client Sample I.D.:	--							
Date/Time Sampled:	--							
Date/Time Analyzed:	9/4/25 14:34							
QC Batch No.:	250904MS2A1							
Analyst Initials:	RC							
Dilution Factor:	0.20							
ANALYTE	Result ppbv	RL ppbv						
Dichlorodifluoromethane (12)	ND	0.20						
Chloromethane	ND	0.20						
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20						
Vinyl Chloride	ND	0.20						
Bromomethane	ND	0.20						
Chloroethane	ND	1.0						
Trichlorofluoromethane (11)	ND	0.20						
1,1-Dichloroethene	ND	0.20						
Carbon Disulfide	ND	0.20						
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20						
Acetone	ND	1.4						
Methylene Chloride	ND	0.20						
t-1,2-Dichloroethene	ND	0.20						
1,1-Dichloroethane	ND	0.20						
Vinyl Acetate	ND Q	0.20						
c-1,2-Dichloroethene	ND	0.20						
2-Butanone	ND	1.0						
t-Butyl Methyl Ether (MTBE)	ND	0.20						
Chloroform	ND	0.20						
1,1,1-Trichloroethane	ND	0.20						
Carbon Tetrachloride	ND	0.20						
Benzene	ND	0.20						
1,2-Dichloroethane	ND	0.20						
Trichloroethene	ND	0.20						
1,2-Dichloropropane	ND	0.20						
Bromodichloromethane	ND	0.20						
c-1,3-Dichloropropene	ND	0.20						
4-Methyl-2-Pentanone	ND	0.20						
Toluene	ND	0.20						
t-1,3-Dichloropropene	ND	0.40						
1,1,2-Trichloroethane	ND	0.20						
Tetrachloroethene	ND	0.20						
2-Hexanone	ND	0.20						
Dibromochloromethane	ND	0.20						

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client:	SCS Engineers
Attn:	Cornelius Fong
Project Name:	Chiquita Canyon Landfill
Project No.:	07224200.24 Task 1
Date Received:	09/04/25
Matrix:	Air
Reporting Units:	ppbv

EPA Method TO-15

Lab No.:	METHOD_BLANK						
Client Sample I.D.:	--						
Date/Time Sampled:	--						
Date/Time Analyzed:	9/4/25 14:34						
QC Batch No.:	250904MS2A1						
Analyst Initials:	RC						
Dilution Factor:	0.20						
ANALYTE	**Result ppbv**	**RL ppbv**					
1,2-Dibromoethane	ND	0.20					
Chlorobenzene	ND	0.20					
Ethylbenzene	ND	0.20					
p,&m-Xylene	ND	0.40					
o-Xylene	ND	0.20					
Styrene	ND	0.20					
Bromoform	ND Q	0.20					
1,1,2,2-Tetrachloroethane	ND	0.20					
Benzyl Chloride	ND	0.20					
4-Ethyl Toluene	ND	0.20					
1,3,5-Trimethylbenzene	ND	0.20					
1,2,4-Trimethylbenzene	ND	0.20					
1,3-Dichlorobenzene	ND	0.20					
1,4-Dichlorobenzene	ND	0.20					
1,2-Dichlorobenzene	ND	0.20					
1,2,4-Trichlorobenzene	ND	0.40					
Hexachlorobutadiene	ND	0.20					
1,3-Butadiene	ND	1.0					
Isopropanol	ND	1.0					
n-Hexane	ND	1.0					
Ethyl Acetate	ND	1.0					
Tetrahydrofuran	ND	1.0					
Cyclohexane	ND	1.0					
Heptane	ND	1.0					
1,4-Dioxane	ND	1.0					

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Refer to Report Narrative

Reviewed/Approved By: _______________ Date 9/23/25
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 250904MS2A1

Matrix: Air
Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	9/4/25 14:34			9/4/25 6:14		9/4/25 6:54					
Analyst Initials:	RC			RC		RC					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	0.20	10	9.32	93	9.59	96	2.8	70	130	30
Methylene Chloride	ND	0.20	10	9.68	97	9.86	99	1.9	70	130	30
Trichloroethene	ND	0.20	10	10.1	101	10.1	101	0.5	70	130	30
Toluene	ND	0.20	10	9.00	90	9.05	91	0.6	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	7.90	79	8.02	80	1.4	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: Mark Johnson
Mark Johnson
Operations Manager

Date: 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/04/25
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	S090403-01		S090403-02		S090403-03		S090403-04	
Client Sample I.D.:	CV-2351		CV-24141		CV-24143		CV-24140	
Date/Time Sampled:	9/4/25 9:00		9/4/25 9:10		9/4/25 9:15		9/4/25 9:20	
Date/Time Analyzed:	9/4/25 15:41		9/4/25 15:56		9/4/25 16:10		9/4/25 16:25	
QC Batch No.:	250904GC8A1		250904GC8A1		250904GC8A1		250904GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	32	10	41	10	1,800	10	1,100	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: [signature]
Mark Johnson
Operations Manager

Date 9/22/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/04/25
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	S090403-05		S090403-06		S090403-07		S090403-08	
Client Sample I.D.:	CV-24139		CV-24138		CV-2354		CV-2349	
Date/Time Sampled:	9/4/25 9:25		9/4/25 9:30		9/4/25 9:35		9/4/25 9:40	
Date/Time Analyzed:	9/4/25 16:39		9/4/25 16:54		9/4/25 17:08		9/4/25 17:22	
QC Batch No.:	250904GC8A1		250904GC8A1		250904GC8A1		250904GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	50	10	19	10	2,800	10	2,900	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: Mark Johnson

Mark Johnson
Operations Manager

Date 9/22/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/04/25
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	S090403-10		S090403-11					
Client Sample I.D.:	CV-2002		CV-2352					
Date/Time Sampled:	9/4/25 9:55		9/4/25 9:28					
Date/Time Analyzed:	9/4/25 17:51		9/4/25 18:06					
QC Batch No.:	250904GC8A1		250904GC8A1					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv				
Carbon Monoxide	330	10	220	10				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: [signature]
Mark Johnson
Operations Manager

Date 9/22/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

QC Batch No: 250904GC8A1
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	9/4/25 9:35			9/3/25 21:17		9/3/25 21:31					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,070	106	1,070	106	0.6	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _______________ Date 9/22/25
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/04/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S090403-01			S090403-02			S090403-03			S090403-04		
Client Sample I.D.:	CV-2351			CV-24141			CV-24143			CV-24140		
Date/Time Sampled:	9/4/25 9:00			9/4/25 9:10			9/4/25 9:15			9/4/25 9:20		
Date/Time Analyzed:	9/4/25 15:41			9/4/25 15:56			9/4/25 16:10			9/4/25 16:25		
QC Batch No.:	250904GC8A1			250904GC8A1			250904GC8A1			250904GC8A1		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	0.28 J	1.0	0.059	ND	1.0	0.059	18	1.0	0.059	18	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By:
Mark Johnson
Operations Manager

Date 9/22/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/04/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S090403-05			S090403-06			S090403-07			S090403-08		
Client Sample I.D.:	CV-24139			CV-24138			CV-2354			CV-2349		
Date/Time Sampled:	9/4/25 9:25			9/4/25 9:30			9/4/25 9:35			9/4/25 9:40		
Date/Time Analyzed:	9/4/25 16:39			9/4/25 16:54			9/4/25 17:08			9/4/25 17:22		
QC Batch No.:	250904GC8A1			250904GC8A1			250904GC8A1			250904GC8A1		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	1.1	1.0	0.059	0.64 J	1.0	0.059	12	1.0	0.059	11	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: Mark Johnson
Operations Manager

Date 9/22/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/04/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S090403-10			S090403-11								
Client Sample I.D.:	CV-2002			CV-2352								
Date/Time Sampled:	9/4/25 9:55			9/4/25 9:28								
Date/Time Analyzed:	9/4/25 17:51			9/4/25 18:06								
QC Batch No.:	250904GC8A1			250904GC8A1								
Analyst Initials:	KD			KD								
Dilution Factor:	1.0			1.0								
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v						
Hydrogen	0.43 J	1.0	0.059	3.0	1.0	0.059						

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: MJ
Mark Johnson
Operations Manager

Date 9/22/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

QC Batch No: 250904GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	9/4/25 9:35				9/3/25 21:17		9/3/25 21:31					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	4.82	97	4.84	97	0.6	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: WMJ
Mark Johnson
Operations Manager

Date 9/22/25

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/04/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S090403-01		S090403-02		S090403-03		S090403-04	
Client Sample I.D.:	CV-2351		CV-24141		CV-24143		CV-24140	
Date/Time Sampled:	9/4/25 9:00		9/4/25 9:10		9/4/25 9:15		9/4/25 9:20	
Date/Time Analyzed:	9/4/25 15:41		9/4/25 15:56		9/4/25 16:10		9/4/25 16:25	
QC Batch No.:	250904GC8A1		250904GC8A1		250904GC8A1		250904GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	0.57 Q	0.010	40	0.010	73	0.010	64	0.010
Oxygen/Argon	21	0.50	3.3	0.50	0.82	0.50	2.9	0.50
Nitrogen	78	1.0	16	1.0	3.0	1.0	11	1.0
Methane	0.030 Q	0.0010	40	0.0010	3.7	0.0010	2.4	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit
Q = Refer to report narrative

Reviewed/Approved By: Anika Sotelo-Sanchez for
Mark Johnson
Operations Manager

Date 9-24-25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/04/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S090403-05		S090403-06		S090403-07		S090403-08	
Client Sample I.D.:	CV-24139		CV-24138		CV-2354		CV-2349	
Date/Time Sampled:	9/4/25 9:25		9/4/25 9:30		9/4/25 9:35		9/4/25 9:40	
Date/Time Analyzed:	9/4/25 16:39		9/4/25 16:54		9/4/25 17:08		9/4/25 17:22	
QC Batch No.:	250904GC8A1		250904GC8A1		250904GC8A1		250904GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	2.3	0.010	1.3	0.010	55	0.010	78	0.010
Oxygen/Argon	20	0.50	21	0.50	3.2	0.50	0.78	0.50
Nitrogen	76	1.0	77	1.0	12	1.0	2.8	1.0
Methane	0.084 Q	0.0010	0.097 Q	0.0010	16	0.0010	5.8	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit
Q = Refer to report narrative

Reviewed/Approved By: Amika Sotelo Sanchez for
Mark Johnson
Operations Manager

Date 9-24-25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/04/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S090403-09		S090403-10		S090403-11			
Client Sample I.D.:	CV-24144		CV-2002		CV-2352			
Date/Time Sampled:	9/4/25 9:45		9/4/25 9:55		9/4/25 9:28			
Date/Time Analyzed:	9/4/25 17:37		9/4/25 17:51		9/4/25 18:06			
QC Batch No.:	250904GC8A1		250904GC8A1		250904GC8A1			
Analyst Initials:	KD		KD		KD			
Dilution Factor:	1.0		1.0		1.0			
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v		
Carbon Dioxide	42	0.010	56	0.010	10	0.010		
Oxygen/Argon	0.71	0.50	1.2	0.50	18	0.50		
Nitrogen	2.6	1.0	4.3	1.0	67	1.0		
Methane	54	0.0010	37	0.0010	0.29 Q	0.0010		

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit
Q = Refer to report narrative

Reviewed/Approved By: Anika Sotelo Sanchez for
Mark Johnson
Operations Manager

Date 9-24-25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

QC Batch No: 250904GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	9/4/25 9:35			9/3/25 21:17		9/3/25 21:31					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	9.81	98	9.83	98	0.2	70	130	30
Oxygen/Argon	ND	0.50	15	15.2	101	15.3	102	0.2	70	130	30
Nitrogen	ND	1.0	70	73.2	105	73.4	105	0.2	70	130	30
Methane	ND	0.0010	0.10	0.103	102	0.102	101	0.4	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: ____________________ Date 9/22/25
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.

September 24, 2025

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175

TX Cert T104704450-14-6
EPA Methods TO14A, TO15

ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: S090801-01/11

Enclosed are the results for sample(s) received 9/8/25 by Air Technology. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags. Vinyl acetate and bromoform exhibited low recoveries in the initial calibration verification indicating possible low bias and are flagged with the Q qualifier. Ethyl acetate exhibited high recovery in the initial calibration verification indicating a high bias. Results above the reporting limit are flagged with the Q qualifier. Hexachlorobutadiene exhibited low recovery in the continuing calibration verification indicating possible low bias and are flagged with the Q qualifier.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Jenny Kim, Art Jones and Ali Ferrara on 9/23/25.

ATL appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Anika SotoSanchez for
Mark Johnson
Operations Manager
MJohnson@AirTechLabs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐ No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐ No ☐
Other:				Level 4	☐	Chilled ______ deg C

Project No.: 07224200.24 Task 1
Project Name: Chiquita Canyon Landfill
Report To: Cornelius Fong
Company: SCS Engineers
Street: 3900 Kilroy Airport Way, Suite 100
City/State/Zip: Long Beach, CA 90806-6816
Phone& Fax: 562-743-7895
e-mail: cfong@scsengineers.com

BILLING
P.O. No.: 07-SO05310
Bill to:
07FSAccountspayable@scsengineers.com
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
S090801 -01	CV-24102	9/8/2025	8:30AM	1L	Gas	N	X					
-02	CV-24101	9/8/2025	8:40AM	2-1L	Gas	N	X	X	X	X		
-03	CV-24100	9/8/2025	8:45AM	1L	Gas	N	X	X	X			
-04	H-2165W	9/8/2025	8:50AM	2-1L	Gas	N	X	X	X	X		
-05	CV-2001	9/8/2025	9:00AM	2-1L	Gas	N	X	X	X	X		
-06	CV-24099	9/8/2025	9:05AM	1L	Gas	N	X					
-07	CV-2350	9/8/2025	9:10AM	2-1L	Gas	N	X	X	X	X		
-08	CV-24095	9/8/2025	9:15AM	2-1L	Gas	N	X	X	X	X		
-09	CV-24142	9/8/2025	9:30AM	2-1L	Gas	N	X	X	X	X		
-10	CV-2353	9/8/2025	9:35AM	1L	Gas	N	X	X	X			

	COMPANY	DATE/TIME		
AUTHORIZATION TO PERFORM WORK				
SAMPLED BY: Antonio Ambriz	SCS	9-8-25		
RELINQUISHED BY: [signature]	DATE/TIME: 9-8-25 11:15am	RECEIVED BY: [signature]	DATE/TIME: 9-8-25 11:15am	
RELINQUISHED BY: [signature]	DATE/TIME: 9-8-25 12:30	RECEIVED BY: [signature]	DATE/TIME: 9/8/25 12:30	
RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME	

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other________

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

Air Technology Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME: Standard [X] | 48 hours [ ] | Same Day [ ] | 72 hours [ ] | 24 hours [ ] | 96 hours [ ] | Other:

DELIVERABLES: EDD [X] | EDF [ ] | Level 3 [ ] | Level 4 [ ]

PAGE: 1 OF

Condition upon receipt: Sealed Yes [ ] No [ ] | Intact Yes [ ] No [ ] | Chilled ______ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 100
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.: 07-SO05310
Bill to:
07FSAccountspayable@scsengineers.com
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
S090801-1	CV-2344	9/8/2025	9:45AM	1L	Gas	N	X	X	X			

AUTHORIZATION TO PERFORM WORK	COMPANY	DATE/TIME
SAMPLED BY: Antonio Ambriz	COMPANY: SCS	DATE/TIME: 9-8-25

RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME
[signature]	9-8-25 11:15am	Ruben G	9-8-25 11:15am
Ruben G	9-8-25 12:31	[signature]	9/8/25 12:31

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other________

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: H=HCl N=None / Container: B=Bag C=Can V=VOA O=Other *Rev. 03 - 5/7/09*

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	S090801-02		S090801-04		S090801-05		S090801-07	
Client Sample I.D.:	CV-24101		H-2165W		CV-2001		CV-2350	
Date/Time Sampled:	9/8/25 8:40		9/8/25 8:50		9/8/25 9:00		9/8/25 9:10	
Date/Time Analyzed:	9/8/25 20:34		9/8/25 21:13		9/8/25 21:51		9/8/25 22:31	
QC Batch No.:	250908MS2A1		250908MS2A1		250908MS2A1		250908MS2A1	
Analyst Initials:	RC		RC		RC		RC	
Dilution Factor:	150		500		500		300	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	150	ND	500	ND	500	ND	300
Chloromethane	ND	150	ND	500	990	500	ND	300
1,2-Cl-1,1,2,2-F ethane (114)	ND	150	ND	500	ND	500	ND	300
Vinyl Chloride	ND	150	ND	500	ND	500	ND	300
Bromomethane	ND	150	ND	500	ND	500	ND	300
Chloroethane	ND	750	ND	2,500	ND	2,500	ND	1,500
Trichlorofluoromethane (11)	ND	150	ND	500	ND	500	ND	300
1,1-Dichloroethene	ND	150	ND	500	ND	500	ND	300
Carbon Disulfide	280	150	ND	500	ND	500	970	300
1,1,2-Cl 1,2,2-F ethane (113)	ND	150	ND	500	ND	500	ND	300
Acetone	19,000	1,100	65,000	3,500	55,000	3,500	52,000	2,100
Methylene Chloride	ND	150	ND	500	ND	500	ND	300
t-1,2-Dichloroethene	ND	150	ND	500	ND	500	ND	300
1,1-Dichloroethane	ND	150	ND	500	ND	500	ND	300
Vinyl Acetate	ND Q	150	ND Q	500	ND Q	500	ND Q	300
c-1,2-Dichloroethene	ND	150	ND	500	ND	500	ND	300
2-Butanone	17,000	750	39,000	2,500	31,000	2,500	23,000	1,500
t-Butyl Methyl Ether (MTBE)	ND	150	580	500	530	500	510	300
Chloroform	ND	150	ND	500	ND	500	ND	300
1,1,1-Trichloroethane	ND	150	ND	500	ND	500	ND	300
Carbon Tetrachloride	ND	150	ND	500	ND	500	ND	300
Benzene	4,600	150	26,000	500	12,000	500	32,000	300
1,2-Dichloroethane	190	150	ND	500	ND	500	ND	300
Trichloroethene	ND	150	ND	500	ND	500	ND	300
1,2-Dichloropropane	ND	150	ND	500	ND	500	ND	300
Bromodichloromethane	ND	150	ND	500	ND	500	ND	300
c-1,3-Dichloropropene	ND	150	ND	500	ND	500	ND	300
4-Methyl-2-Pentanone	470	150	1,000	500	990	500	660	300
Toluene	980	150	1,800	500	1,300	500	900	300
t-1,3-Dichloropropene	ND	300	ND	1,000	ND	1,000	ND	600
1,1,2-Trichloroethane	ND	150	ND	500	ND	500	ND	300
Tetrachloroethene	ND	150	ND	500	ND	500	ND	300
2-Hexanone	ND	150	ND	500	ND	500	ND	300
Dibromochloromethane	ND	150	ND	500	ND	500	ND	300

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	S090801-02		S090801-04		S090801-05		S090801-07	
Client Sample I.D.:	CV-24101		H-2165W		CV-2001		CV-2350	
Date/Time Sampled:	9/8/25 8:40		9/8/25 8:50		9/8/25 9:00		9/8/25 9:10	
Date/Time Analyzed:	9/8/25 20:34		9/8/25 21:13		9/8/25 21:51		9/8/25 22:31	
QC Batch No.:	250908MS2A1		250908MS2A1		250908MS2A1		250908MS2A1	
Analyst Initials:	RC		RC		RC		RC	
Dilution Factor:	150		500		500		300	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	150	ND	500	ND	500	ND	300
Chlorobenzene	ND	150	ND	500	ND	500	ND	300
Ethylbenzene	ND	150	ND	500	ND	500	ND	300
p,&m-Xylene	ND	300	ND	1,000	ND	1,000	ND	600
o-Xylene	ND	150	ND	500	ND	500	ND	300
Styrene	ND	150	ND	500	ND	500	ND	300
Bromoform	ND Q	150	ND Q	500	ND Q	500	ND Q	300
1,1,2,2-Tetrachloroethane	ND	150	ND	500	ND	500	ND	300
Benzyl Chloride	ND	150	ND	500	ND	500	ND	300
4-Ethyl Toluene	ND	150	ND	500	ND	500	ND	300
1,3,5-Trimethylbenzene	ND	150	ND	500	ND	500	ND	300
1,2,4-Trimethylbenzene	ND	150	ND	500	ND	500	ND	300
1,3-Dichlorobenzene	ND	150	ND	500	ND	500	ND	300
1,4-Dichlorobenzene	ND	150	ND	500	ND	500	ND	300
1,2-Dichlorobenzene	ND	150	ND	500	ND	500	ND	300
1,2,4-Trichlorobenzene	ND	300	ND	1,000	ND	1,000	ND	600
Hexachlorobutadiene	ND Q	150	ND Q	500	ND Q	500	ND Q	300
1,3-Butadiene	**1,100**	750	**7,000**	2,500	**11,000**	2,500	**7,800**	1,500
Isopropanol	**30,000**	750	**100,000**	2,500	**100,000**	2,500	**50,000**	1,500
n-Hexane	**780**	750	**4,800**	2,500	ND	2,500	ND	1,500
Ethyl Acetate	**12,000** Q	750	**35,000** Q	2,500	**7,300** Q	2,500	**4,900** Q	1,500
Tetrahydrofuran	**6,800**	750	**32,000**	2,500	**32,000**	2,500	**18,000**	1,500
Cyclohexane	ND	750	ND	2,500	ND	2,500	ND	1,500
Heptane	ND	750	**2,800**	2,500	ND	2,500	**1,600**	1,500
1,4-Dioxane	ND	750	ND	2,500	ND	2,500	ND	1,500

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Refer to Report Narrative

Reviewed/Approved By: ______________ Date 10-14-25
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	S090801-08		S090801-09					
Client Sample I.D.:	CV-24095		CV-24142					
Date/Time Sampled:	9/8/25 9:15		9/8/25 9:30					
Date/Time Analyzed:	9/8/25 23:10		9/8/25 23:50					
QC Batch No.:	250908MS2A1		250908MS2A1					
Analyst Initials:	RC		RC					
Dilution Factor:	2,500		4,400					
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv				
Dichlorodifluoromethane (12)	ND	2,500	ND	4,400				
Chloromethane	ND	2,500	ND	4,400				
1,2-Cl-1,1,2,2-F ethane (114)	ND	2,500	ND	4,400				
Vinyl Chloride	ND	2,500	ND	4,400				
Bromomethane	ND	2,500	ND	4,400				
Chloroethane	ND	13,000	ND	22,000				
Trichlorofluoromethane (11)	ND	2,500	ND	4,400				
1,1-Dichloroethene	ND	2,500	ND	4,400				
Carbon Disulfide	ND	2,500	ND	4,400				
1,1,2-Cl 1,2,2-F ethane (113)	ND	2,500	ND	4,400				
Acetone	320,000	18,000	520,000	31,000				
Methylene Chloride	ND	2,500	ND	4,400				
t-1,2-Dichloroethene	ND	2,500	ND	4,400				
1,1-Dichloroethane	ND	2,500	ND	4,400				
Vinyl Acetate	ND Q	2,500	ND Q	4,400				
c-1,2-Dichloroethene	ND	2,500	ND	4,400				
2-Butanone	180,000	13,000	220,000	22,000				
t-Butyl Methyl Ether (MTBE)	ND	2,500	ND	4,400				
Chloroform	ND	2,500	ND	4,400				
1,1,1-Trichloroethane	ND	2,500	ND	4,400				
Carbon Tetrachloride	ND	2,500	ND	4,400				
Benzene	280,000	2,500	110,000	4,400				
1,2-Dichloroethane	ND	2,500	ND	4,400				
Trichloroethene	ND	2,500	ND	4,400				
1,2-Dichloropropane	ND	2,500	ND	4,400				
Bromodichloromethane	ND	2,500	ND	4,400				
c-1,3-Dichloropropene	ND	2,500	ND	4,400				
4-Methyl-2-Pentanone	4,700	2,500	ND	4,400				
Toluene	6,600	2,500	ND	4,400				
t-1,3-Dichloropropene	ND	5,000	ND	8,800				
1,1,2-Trichloroethane	ND	2,500	ND	4,400				
Tetrachloroethene	ND	2,500	ND	4,400				
2-Hexanone	ND	2,500	ND	4,400				
Dibromochloromethane	ND	2,500	ND	4,400				

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	S090801-08		S090801-09					
Client Sample I.D.:	CV-24095		CV-24142					
Date/Time Sampled:	9/8/25 9:15		9/8/25 9:30					
Date/Time Analyzed:	9/8/25 23:10		9/8/25 23:50					
QC Batch No.:	250908MS2A1		250908MS2A1					
Analyst Initials:	RC		RC					
Dilution Factor:	2,500		4,400					
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv				
1,2-Dibromoethane	ND	2,500	ND	4,400				
Chlorobenzene	ND	2,500	ND	4,400				
Ethylbenzene	ND	2,500	ND	4,400				
p,&m-Xylene	ND	5,000	ND	8,800				
o-Xylene	ND	2,500	ND	4,400				
Styrene	ND	2,500	ND	4,400				
Bromoform	ND Q	2,500	ND Q	4,400				
1,1,2,2-Tetrachloroethane	ND	2,500	ND	4,400				
Benzyl Chloride	ND	2,500	ND	4,400				
4-Ethyl Toluene	ND	2,500	ND	4,400				
1,3,5-Trimethylbenzene	ND	2,500	ND	4,400				
1,2,4-Trimethylbenzene	ND	2,500	ND	4,400				
1,3-Dichlorobenzene	ND	2,500	ND	4,400				
1,4-Dichlorobenzene	ND	2,500	ND	4,400				
1,2-Dichlorobenzene	ND	2,500	ND	4,400				
1,2,4-Trichlorobenzene	ND	5,000	ND	8,800				
Hexachlorobutadiene	ND Q	2,500	ND Q	4,400				
1,3-Butadiene	ND	13,000	ND	22,000				
Isopropanol	**200,000**	13,000	**110,000**	22,000				
n-Hexane	ND	13,000	ND	22,000				
Ethyl Acetate	**71,000** Q	13,000	**43,000** Q	22,000				
Tetrahydrofuran	**300,000**	13,000	**260,000**	22,000				
Cyclohexane	ND	13,000	ND	22,000				
Heptane	**14,000**	13,000	ND	22,000				
1,4-Dioxane	ND	13,000	ND	22,000				

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Refer to Report Narrative

Reviewed/Approved By: Amika Sotelo Sanchez Jr. Date 10-14-25
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD_BLANK			
Client Sample I.D.:	--			
Date/Time Sampled:	--			
Date/Time Analyzed:	9/8/25 12:08			
QC Batch No.:	250908MS2A1			
Analyst Initials:	RC			
Dilution Factor:	0.20			

ANALYTE	Result ppbv	RL ppbv						
Dichlorodifluoromethane (12)	ND	0.20						
Chloromethane	ND	0.20						
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20						
Vinyl Chloride	ND	0.20						
Bromomethane	ND	0.20						
Chloroethane	ND	1.0						
Trichlorofluoromethane (11)	ND	0.20						
1,1-Dichloroethene	ND	0.20						
Carbon Disulfide	ND	0.20						
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20						
Acetone	ND	1.4						
Methylene Chloride	ND	0.20						
t-1,2-Dichloroethene	ND	0.20						
1,1-Dichloroethane	ND	0.20						
Vinyl Acetate	ND Q	0.20						
c-1,2-Dichloroethene	ND	0.20						
2-Butanone	ND	1.0						
t-Butyl Methyl Ether (MTBE)	ND	0.20						
Chloroform	ND	0.20						
1,1,1-Trichloroethane	ND	0.20						
Carbon Tetrachloride	ND	0.20						
Benzene	ND	0.20						
1,2-Dichloroethane	ND	0.20						
Trichloroethene	ND	0.20						
1,2-Dichloropropane	ND	0.20						
Bromodichloromethane	ND	0.20						
c-1,3-Dichloropropene	ND	0.20						
4-Methyl-2-Pentanone	ND	0.20						
Toluene	ND	0.20						
t-1,3-Dichloropropene	ND	0.40						
1,1,2-Trichloroethane	ND	0.20						
Tetrachloroethene	ND	0.20						
2-Hexanone	ND	0.20						
Dibromochloromethane	ND	0.20						

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD_BLANK			
Client Sample I.D.:	--			
Date/Time Sampled:	--			
Date/Time Analyzed:	9/8/25 12:08			
QC Batch No.:	250908MS2A1			
Analyst Initials:	RC			
Dilution Factor:	0.20			

ANALYTE	Result ppbv	RL ppbv						
1,2-Dibromoethane	ND	0.20						
Chlorobenzene	ND	0.20						
Ethylbenzene	ND	0.20						
p,&m-Xylene	ND	0.40						
o-Xylene	ND	0.20						
Styrene	ND	0.20						
Bromoform	ND Q	0.20						
1,1,2,2-Tetrachloroethane	ND	0.20						
Benzyl Chloride	ND	0.20						
4-Ethyl Toluene	ND	0.20						
1,3,5-Trimethylbenzene	ND	0.20						
1,2,4-Trimethylbenzene	ND	0.20						
1,3-Dichlorobenzene	ND	0.20						
1,4-Dichlorobenzene	ND	0.20						
1,2-Dichlorobenzene	ND	0.20						
1,2,4-Trichlorobenzene	ND	0.40						
Hexachlorobutadiene	ND Q	0.20						
1,3-Butadiene	ND	1.0						
Isopropanol	ND	1.0						
n-Hexane	ND	1.0						
Ethyl Acetate	ND	1.0						
Tetrahydrofuran	ND	1.0						
Cyclohexane	ND	1.0						
Heptane	ND	1.0						
1,4-Dioxane	ND	1.0						

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Refer to Report Narrative

Reviewed/Approved By: ____________ Date 10-14-25

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 250908MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	9/8/25 12:08			9/8/25 10:40		9/8/25 11:19					
Analyst Initials:	RC			RC		RC					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	0.20	10	9.06	91	9.44	94	4.1	70	130	30
Methylene Chloride	ND	0.20	10	9.36	94	9.51	95	1.6	70	130	30
Trichloroethene	ND	0.20	10	9.92	99	9.87	99	0.5	70	130	30
Toluene	ND	0.20	10	8.80	88	8.84	88	0.4	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	7.70	77	7.65	77	0.6	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: [signature]
Mark Johnson
Operations Manager

Date: 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/25
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	S090801-02		S090801-03		S090801-04		S090801-05	
Client Sample I.D.:	CV-24101		CV-24100		H-2165W		CV-2001	
Date/Time Sampled:	9/8/25 8:40		9/8/25 8:45		9/8/25 8:50		9/8/25 9:00	
Date/Time Analyzed:	9/8/25 21:37		9/8/25 21:52		9/8/25 22:06		9/8/25 22:21	
QC Batch No.:	250908GC8A2		250908GC8A2		250908GC8A2		250908GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	19	10	17	10	41	10	880	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: ______________________ Date 9/23/25
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/25
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	S090801-07		S090801-08		S090801-09		S090801-10	
Client Sample I.D.:	CV-2350		CV-24095		CV-24142		CV-2353	
Date/Time Sampled:	9/8/25 9:10		9/8/25 9:15		9/8/25 9:30		9/8/25 9:35	
Date/Time Analyzed:	9/8/25 22:50		9/8/25 23:04		9/8/25 23:19		9/8/25 23:33	
QC Batch No.:	250908GC8A2		250908GC8A2		250908GC8A2		250908GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	2,500	10	5,000	10	1,300	10	650	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: [signature]
Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/25
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	S090801-11							
Client Sample I.D.:	CV-2344							
Date/Time Sampled:	9/8/25 9:45							
Date/Time Analyzed:	9/8/25 23:48							
QC Batch No.:	250908GC8A2							
Analyst Initials:	KD							
Dilution Factor:	1.0							
ANALYTE	Result ppmv	RL ppmv						
Carbon Monoxide	1,800	10						

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

QC Batch No: 250908GC8A2
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	9/8/25 21:08			9/8/25 20:10		9/8/25 20:25					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,070	106	1,080	106	0.1	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: ____________________ Date 9/23/25
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S090801-02			S090801-03			S090801-04			S090801-05		
Client Sample I.D.:	CV-24101			CV-24100			H-2165W			CV-2001		
Date/Time Sampled:	9/8/25 8:40			9/8/25 8:45			9/8/25 8:50			9/8/25 9:00		
Date/Time Analyzed:	9/8/25 21:37			9/8/25 21:52			9/8/25 22:06			9/8/25 22:21		
QC Batch No.:	250908GC8A2			250908GC8A2			250908GC8A2			250908GC8A2		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	0.41 J	1.0	0.059	0.45 J	1.0	0.059	0.94 J	1.0	0.059	2.3	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: MJ

Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S090801-07			S090801-08			S090801-09			S090801-10		
Client Sample I.D.:	CV-2350			CV-24095			CV-24142			CV-2353		
Date/Time Sampled:	9/8/25 9:10			9/8/25 9:15			9/8/25 9:30			9/8/25 9:35		
Date/Time Analyzed:	9/8/25 22:50			9/8/25 23:04			9/8/25 23:19			9/8/25 23:33		
QC Batch No.:	250908GC8A2			250908GC8A2			250908GC8A2			250908GC8A2		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	7.5	1.0	0.059	15	1.0	0.059	13	1.0	0.059	19	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: ______________
Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S090801-11										
Client Sample I.D.:	CV-2344										
Date/Time Sampled:	9/8/25 9:45										
Date/Time Analyzed:	9/8/25 23:48										
QC Batch No.:	250908GC8A2										
Analyst Initials:	KD										
Dilution Factor:	1.0										
ANALYTE	Result % v/v	RL % v/v	MDL % v/v								
Hydrogen	9.9	1.0	0.059								

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: Mark Johnson, Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

QC Batch No: 250908GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	9/8/25 21:08				9/8/25 20:10		9/8/25 20:25					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v		RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	0.12	J	1.0	0.059	5.0	5.81	115	5.79	114	0.5	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: ______________________ Date 9/23/25
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S090801-01		S090801-02		S090801-03		S090801-04	
Client Sample I.D.:	CV-24102		CV-24101		CV-24100		H-2165W	
Date/Time Sampled:	9/8/25 8:30		9/8/25 8:40		9/8/25 8:45		9/8/25 8:50	
Date/Time Analyzed:	9/8/25 21:23		9/8/25 21:37		9/8/25 21:52		9/8/25 22:06	
QC Batch No.:	250908GC8A2		250908GC8A2		250908GC8A2		250908GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	35	0.010	38	0.010	59	0.010	74	0.010
Oxygen/Argon	2.4	0.50	2.2	0.50	2.3	0.50	0.76	0.50
Nitrogen	22	1.0	33	1.0	12	1.0	3.3	1.0
Methane	40	0.0010	26	0.0010	26	0.0010	20	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: ______________________
Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S090801-05		S090801-06		S090801-07		S090801-08	
Client Sample I.D.:	CV-2001		CV-24099		CV-2350		CV-24095	
Date/Time Sampled:	9/8/25 9:00		9/8/25 9:05		9/8/25 9:10		9/8/25 9:15	
Date/Time Analyzed:	9/8/25 22:21		9/8/25 22:35		9/8/25 22:50		9/8/25 23:04	
QC Batch No.:	250908GC8A2		250908GC8A2		250908GC8A2		250908GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	83	0.010	84	0.010	80	0.010	74	0.010
Oxygen/Argon	0.67	0.50	ND	0.50	0.75	0.50	0.57	0.50
Nitrogen	2.5	1.0	1.7	1.0	2.7	1.0	2.0	1.0
Methane	11	0.0010	11	0.0010	8.8	0.0010	7.1	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: [signature]
Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S090801-09		S090801-10		S090801-11			
Client Sample I.D.:	CV-24142		CV-2353		CV-2344			
Date/Time Sampled:	9/8/25 9:30		9/8/25 9:35		9/8/25 9:45			
Date/Time Analyzed:	9/8/25 23:19		9/8/25 23:33		9/8/25 23:48			
QC Batch No.:	250908GC8A2		250908GC8A2		250908GC8A2			
Analyst Initials:	KD		KD		KD			
Dilution Factor:	1.0		1.0		1.0			
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v		
Carbon Dioxide	37	0.010	53	0.010	70	0.010		
Oxygen/Argon	10.0	0.50	5.4	0.50	1.0	0.50		
Nitrogen	37	1.0	20	1.0	6.5	1.0		
Methane	2.3	0.0010	1.8	0.0010	11	0.0010		

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: ____________________ Date 9/23/25
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

QC Batch No: 250908GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	9/8/25 21:08			9/8/25 20:10		9/8/25 20:25					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	10.2	102	10.2	101	0.5	70	130	30
Oxygen/Argon	ND	0.50	15	15.0	100	15.0	100	0.3	70	130	30
Nitrogen	ND	1.0	70	72.2	103	71.9	103	0.4	70	130	30
Methane	ND	0.0010	0.10	0.101	100	0.102	101	0.4	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: ____________________
Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.

September 29, 2025

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175

TX Cert T104704450-14-6
EPA Methods TO14A, TO15

ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: S090904-01/10

Enclosed are the results for sample(s) received 9/9/25 by Air Technology. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were received in Mylar bags. Benzyl chloride required quadratic regression calibration.
- The TO-15 analyses were performed outside the 24-hr holding-time due to an instrument fault.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Jenny Kim, Art Jones and Ali Ferrara on 9/23/25.

ATL appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Anika Sotelo Sanchez for

Mark Johnson
Operations Manager
MJohnson@AirTechLabs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐ No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐ No ☐
Other:				Level 4	☐	Chilled ______ deg C

Project No.: 07224200.24 Task 1
Project Name: Chiquita Canyon Landfill
Report To: Cornelius Fong
Company: SCS Engineers
Street: 3900 Kilroy Airport Way, Suite 100
City/State/Zip: Long Beach, CA 90806-6816
Phone& Fax: 562-743-7895
e-mail: cfong@scsengineers.com

BILLING
P.O. No.: 07-SO05310
Bill to:
07FSAccountspayable@scsengineers.com
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
S090904 -01	~~H-1770W~~ H-1770N tto 9/9/25	9/9/2025	8:25AM	2-1L	Gas	N	X	X	X	X		
-02	CV-2337	9/9/2025	8:35AM	1L	Gas	N	X	X	X			
-03	CV-1902A	9/9/2025	8:45AM	2-1L	Gas	N	X	X	X	X		
-04	CV-2341	9/9/2025	8:50AM	1L	Gas	N	X	X	X			
-05	CV-1535	9/9/2025	9:00AM	2-1L	Gas	N	X	X	X	X		
-06	CV-24066	9/9/2025	9:05AM	1L	Gas	N	X	X	X			
-07	CV-2348	9/9/2025	9:10AM	1L	Gas	N	X	X	X			
-08	CV-2347	9/9/2025	9:15AM	1L	Gas	N	X	X	X			
-09	CV-2346	9/9/2025	9:20AM	1L	Gas	N	X	X	X			
-10	CV-2345	9/9/2025	9:25AM	1L	Gas	N	X	X	X			

AUTHORIZATION TO PERFORM WORK	COMPANY	DATE/TIME		
SAMPLED BY Antonio Ambriz	COMPANY SCS	DATE/TIME 9/9/25		
RELINQUISHED BY Fabian Chavez	DATE/TIME 9-9-25 10:58am	RECEIVED BY Ruben 6	DATE/TIME 9/9/25 11:00am	
RELINQUISHED BY Ruben 6	DATE/TIME 9-9-25 12:30	RECEIVED BY [signature]	DATE/TIME 9/9/25 12:30	
RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME	

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other________

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy
Preservation: H=HCl N=None / Container: B=Bag C=Can V=VOA O=Other *Rev. 03 - 5/7/09*

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/09/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	S090904-01		S090904-03		S090904-05			
Client Sample I.D.:	H-1770N		CV-1902A		CV-1535			
Date/Time Sampled:	9/9/25 8:25		9/9/25 8:45		9/9/25 9:00			
Date/Time Analyzed:	9/12/2025 12:45*		9/12/2025 1:25*		9/12/2025 2:04*			
QC Batch No.:	250911MS2A1		250911MS2A1		250911MS2A1			
Analyst Initials:	RC		RC		RC			
Dilution Factor:	800		10,000		1,000			
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv		
Dichlorodifluoromethane (12)	ND	800	ND	10,000	ND	1,000		
Chloromethane	ND	800	11,000	10,000	1,900	1,000		
1,2-Cl-1,1,2,2-F ethane (114)	ND	800	ND	10,000	ND	1,000		
Vinyl Chloride	ND	800	ND	10,000	ND	1,000		
Bromomethane	ND	800	ND	10,000	ND	1,000		
Chloroethane	ND	4,000	ND	50,000	ND	5,000		
Trichlorofluoromethane (11)	ND	800	ND	10,000	ND	1,000		
1,1-Dichloroethene	ND	800	ND	10,000	ND	1,000		
Carbon Disulfide	ND	800	ND	10,000	ND	1,000		
1,1,2-Cl 1,2,2-F ethane (113)	ND	800	ND	10,000	ND	1,000		
Acetone	43,000	5,600	1,300,000	70,000	180,000	7,000		
Methylene Chloride	ND	800	ND	10,000	ND	1,000		
t-1,2-Dichloroethene	ND	800	ND	10,000	ND	1,000		
1,1-Dichloroethane	ND	800	ND	10,000	ND	1,000		
Vinyl Acetate	ND	800	ND	10,000	ND	1,000		
c-1,2-Dichloroethene	ND	800	ND	10,000	ND	1,000		
2-Butanone	28,000	4,000	640,000	50,000	99,000	5,000		
t-Butyl Methyl Ether (MTBE)	1,000	800	ND	10,000	ND	1,000		
Chloroform	ND	800	ND	10,000	ND	1,000		
1,1,1-Trichloroethane	ND	800	ND	10,000	ND	1,000		
Carbon Tetrachloride	ND	800	ND	10,000	ND	1,000		
Benzene	190,000	800	140,000	10,000	40,000	1,000		
1,2-Dichloroethane	ND	800	ND	10,000	ND	1,000		
Trichloroethene	ND	800	ND	10,000	ND	1,000		
1,2-Dichloropropane	ND	800	ND	10,000	ND	1,000		
Bromodichloromethane	ND	800	ND	10,000	ND	1,000		
c-1,3-Dichloropropene	ND	800	ND	10,000	ND	1,000		
4-Methyl-2-Pentanone	1,500	800	ND	10,000	2,100	1,000		
Toluene	3,800	800	ND	10,000	2,300	1,000		
t-1,3-Dichloropropene	ND	1,600	ND	20,000	ND	2,000		
1,1,2-Trichloroethane	ND	800	ND	10,000	ND	1,000		
Tetrachloroethene	ND	800	ND	10,000	ND	1,000		
2-Hexanone	ND	800	ND	10,000	ND	1,000		
Dibromochloromethane	ND	800	ND	10,000	ND	1,000		

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/09/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	S090904-01		S090904-03		S090904-05			
Client Sample I.D.:	H-1770N		CV-1902A		CV-1535			
Date/Time Sampled:	9/9/25 8:25		9/9/25 8:45		9/9/25 9:00			
Date/Time Analyzed:	9/12/2025 12:45*		9/12/2025 1:25*		9/12/2025 2:04*			
QC Batch No.:	250911MS2A1		250911MS2A1		250911MS2A1			
Analyst Initials:	RC		RC		RC			
Dilution Factor:	800		10,000		1,000			
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv		
1,2-Dibromoethane	ND	800	ND	10,000	ND	1,000		
Chlorobenzene	ND	800	ND	10,000	ND	1,000		
Ethylbenzene	ND	800	ND	10,000	ND	1,000		
p,&m-Xylene	ND	1,600	ND	20,000	ND	2,000		
o-Xylene	ND	800	ND	10,000	ND	1,000		
Styrene	ND	800	ND	10,000	ND	1,000		
Bromoform	ND	800	ND	10,000	ND	1,000		
1,1,2,2-Tetrachloroethane	ND	800	ND	10,000	ND	1,000		
Benzyl Chloride	ND	800	ND	10,000	ND	1,000		
4-Ethyl Toluene	ND	800	ND	10,000	ND	1,000		
1,3,5-Trimethylbenzene	ND	800	ND	10,000	ND	1,000		
1,2,4-Trimethylbenzene	ND	800	ND	10,000	ND	1,000		
1,3-Dichlorobenzene	ND	800	ND	10,000	ND	1,000		
1,4-Dichlorobenzene	ND	800	ND	10,000	ND	1,000		
1,2-Dichlorobenzene	ND	800	ND	10,000	ND	1,000		
1,2,4-Trichlorobenzene	ND	1,600	ND	20,000	ND	2,000		
Hexachlorobutadiene	ND	800	ND	10,000	ND	1,000		
1,3-Butadiene	4,600	4,000	ND	50,000	ND	5,000		
Isopropanol	78,000	4,000	210,000	50,000	86,000	5,000		
n-Hexane	ND	4,000	ND	50,000	ND	5,000		
Ethyl Acetate	9,700	4,000	ND	50,000	11,000	5,000		
Tetrahydrofuran	29,000	4,000	410,000	50,000	65,000	5,000		
Cyclohexane	ND	4,000	ND	50,000	ND	5,000		
Heptane	ND	4,000	ND	50,000	ND	5,000		
1,4-Dioxane	ND	4,000	ND	50,000	ND	5,000		

RL = Reporting Limit
ND = Not Detected (below RL)
* = Samples were analyzed out side the recommended 24 hour hold time.

Reviewed/Approved By: [signature] Date 9/23/25
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/09/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD_BLANK							
Client Sample I.D.:	--							
Date/Time Sampled:	--							
Date/Time Analyzed:	9/11/25 20:46							
QC Batch No.:	250911MS2A1							
Analyst Initials:	RC							
Dilution Factor:	1.0							
ANALYTE	Result ppbv	RL ppbv						
Dichlorodifluoromethane (12)	ND	1.0						
Chloromethane	ND	1.0						
1,2-Cl-1,1,2,2-F ethane (114)	ND	1.0						
Vinyl Chloride	ND	1.0						
Bromomethane	ND	1.0						
Chloroethane	ND	5.0						
Trichlorofluoromethane (11)	ND	1.0						
1,1-Dichloroethene	ND	1.0						
Carbon Disulfide	ND	1.0						
1,1,2-Cl 1,2,2-F ethane (113)	ND	1.0						
Acetone	ND	7.0						
Methylene Chloride	ND	1.0						
t-1,2-Dichloroethene	ND	1.0						
1,1-Dichloroethane	ND	1.0						
Vinyl Acetate	ND	1.0						
c-1,2-Dichloroethene	ND	1.0						
2-Butanone	ND	5.0						
t-Butyl Methyl Ether (MTBE)	ND	1.0						
Chloroform	ND	1.0						
1,1,1-Trichloroethane	ND	1.0						
Carbon Tetrachloride	ND	1.0						
Benzene	ND	1.0						
1,2-Dichloroethane	ND	1.0						
Trichloroethene	ND	1.0						
1,2-Dichloropropane	ND	1.0						
Bromodichloromethane	ND	1.0						
c-1,3-Dichloropropene	ND	1.0						
4-Methyl-2-Pentanone	ND	1.0						
Toluene	ND	1.0						
t-1,3-Dichloropropene	ND	2.0						
1,1,2-Trichloroethane	ND	1.0						
Tetrachloroethene	ND	1.0						
2-Hexanone	ND	1.0						
Dibromochloromethane	ND	1.0						

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/09/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD_BLANK							
Client Sample I.D.:	--							
Date/Time Sampled:	--							
Date/Time Analyzed:	9/11/25 20:46							
QC Batch No.:	250911MS2A1							
Analyst Initials:	RC							
Dilution Factor:	1.0							
ANALYTE	Result ppbv	RL ppbv						
1,2-Dibromoethane	ND	1.0						
Chlorobenzene	ND	1.0						
Ethylbenzene	ND	1.0						
p,&m-Xylene	ND	2.0						
o-Xylene	ND	1.0						
Styrene	ND	1.0						
Bromoform	ND	1.0						
1,1,2,2-Tetrachloroethane	ND	1.0						
Benzyl Chloride	ND	1.0						
4-Ethyl Toluene	ND	1.0						
1,3,5-Trimethylbenzene	ND	1.0						
1,2,4-Trimethylbenzene	ND	1.0						
1,3-Dichlorobenzene	ND	1.0						
1,4-Dichlorobenzene	ND	1.0						
1,2-Dichlorobenzene	ND	1.0						
1,2,4-Trichlorobenzene	ND	2.0						
Hexachlorobutadiene	ND	1.0						
1,3-Butadiene	ND	5.0						
Isopropanol	ND	5.0						
n-Hexane	ND	5.0						
Ethyl Acetate	ND	5.0						
Tetrahydrofuran	ND	5.0						
Cyclohexane	ND	5.0						
Heptane	ND	5.0						
1,4-Dioxane	ND	5.0						

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: ______________________ **Date** 9/23/25
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 250911MS2A1

Matrix: Air
Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	9/11/25 20:46			9/11/25 19:26		9/11/25 20:06					
Analyst Initials:	RC			RC		RC					
Dilution Factor:	1.0			1.0		1.0					
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	1.0	10	11.1	111	11.5	115	3.3	70	130	30
Methylene Chloride	ND	1.0	10	11.0	110	11.3	113	2.6	70	130	30
Trichloroethene	ND	1.0	10	10.7	107	10.6	106	1.3	70	130	30
Toluene	ND	1.0	10	10.5	105	10.4	104	0.5	70	130	30
1,1,2,2-Tetrachloroethane	ND	1.0	10	11.6	116	11.5	115	0.9	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: [signature]
Mark Johnson
Operations Manager

Date: 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/09/25
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	S090904-01		S090904-02		S090904-03		S090904-04	
Client Sample I.D.:	H-1770N		CV-2337		CV-1902A		CV-2341	
Date/Time Sampled:	9/9/25 8:25		9/9/25 8:35		9/9/25 8:45		9/9/25 8:50	
Date/Time Analyzed:	9/9/25 16:53		9/9/25 17:08		9/9/25 17:22		9/9/25 17:37	
QC Batch No.:	250909GC8A2		250909GC8A2		250909GC8A2		250909GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	56	10	2,000	10	1,000	10	770	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: [signature]
Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/09/25
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	S090904-05		S090904-06		S090904-07		S090904-08	
Client Sample I.D.:	CV-1535		CV-24066		CV-2348		CV-2347	
Date/Time Sampled:	9/9/25 9:00		9/9/25 9:05		9/9/25 9:10		9/9/25 9:15	
Date/Time Analyzed:	9/9/25 17:51		9/9/25 18:06		9/9/25 18:20		9/9/25 18:35	
QC Batch No.:	250909GC8A2		250909GC8A2		250909GC8A2		250909GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	180	10	390	10	400	10	1,700	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: MJ. for
Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/09/25
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	S090904-09		S090904-10					
Client Sample I.D.:	CV-2346		CV-2345					
Date/Time Sampled:	9/9/25 9:20		9/9/25 9:25					
Date/Time Analyzed:	9/9/25 18:49		9/9/25 19:04					
QC Batch No.:	250909GC8A2		250909GC8A2					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv				
Carbon Monoxide	2,400	10	500	10				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: [signature]
Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

QC Batch No: 250909GC8A2
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	9/9/25 16:24			9/9/25 15:41		9/9/25 15:55					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,080	107	1,070	106	0.5	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: Mark Johnson fz
Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/09/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S090904-01			S090904-02			S090904-03			S090904-04		
Client Sample I.D.:	H-1770N			CV-2337			CV-1902A			CV-2341		
Date/Time Sampled:	9/9/25 8:25			9/9/25 8:35			9/9/25 8:45			9/9/25 8:50		
Date/Time Analyzed:	9/9/25 16:53			9/9/25 17:08			9/9/25 17:22			9/9/25 17:37		
QC Batch No.:	250909GC8A2			250909GC8A2			250909GC8A2			250909GC8A2		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	0.50 J	1.0	0.059	16	1.0	0.059	20	1.0	0.059	17	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: ____________
Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/09/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S090904-05			S090904-06			S090904-07			S090904-08		
Client Sample I.D.:	CV-1535			CV-24066			CV-2348			CV-2347		
Date/Time Sampled:	9/9/25 9:00			9/9/25 9:05			9/9/25 9:10			9/9/25 9:15		
Date/Time Analyzed:	9/9/25 17:51			9/9/25 18:06			9/9/25 18:20			9/9/25 18:35		
QC Batch No.:	250909GC8A2			250909GC8A2			250909GC8A2			250909GC8A2		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	2.5	1.0	0.059	3.5	1.0	0.059	1.9	1.0	0.059	6.8	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: [signature]
Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/09/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S090904-09			S090904-10								
Client Sample I.D.:	CV-2346			CV-2345								
Date/Time Sampled:	9/9/25 9:20			9/9/25 9:25								
Date/Time Analyzed:	9/9/25 18:49			9/9/25 19:04								
QC Batch No.:	250909GC8A2			250909GC8A2								
Analyst Initials:	KD			KD								
Dilution Factor:	1.0			1.0								
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v						
Hydrogen	9.5	1.0	0.059	3.3	1.0	0.059						

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: [signature]
Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

QC Batch No: 250909GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	9/9/25 16:24				9/9/25 15:41		9/9/25 15:55					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	5.59	112	5.59	112	0.1	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: [signature]
Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

Client:	**SCS Engineers**
Attn:	**Cornelius Fong**
Project Name:	**Chiquita Canyon Landfill**
Project No.:	**07224200.24 Task 1**
Date Received:	**09/09/25**
Matrix:	**Air**
Reporting Units:	**% v/v**

ASTM D1946

Lab No.:	S090904-01		S090904-02		S090904-03		S090904-04	
Client Sample I.D.:	H-1770N		CV-2337		CV-1902A		CV-2341	
Date/Time Sampled:	9/9/25 8:25		9/9/25 8:35		9/9/25 8:45		9/9/25 8:50	
Date/Time Analyzed:	9/9/25 16:53		9/9/25 17:08		9/9/25 17:22		9/9/25 17:37	
QC Batch No.:	250909GC8A2		250909GC8A2		250909GC8A2		250909GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	66	0.010	42	0.010	71	0.010	61	0.010
Oxygen/Argon	1.4	0.50	6.5	0.50	1.1	0.50	0.89	0.50
Nitrogen	5.3	1.0	25	1.0	3.9	1.0	3.2	1.0
Methane	26	0.0010	10	0.0010	2.3	0.0010	17	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: [signature]
Mark Johnson
Operations Manager

Date 9/22/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/09/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S090904-05		S090904-06		S090904-07		S090904-08	
Client Sample I.D.:	CV-1535		CV-24066		CV-2348		CV-2347	
Date/Time Sampled:	9/9/25 9:00		9/9/25 9:05		9/9/25 9:10		9/9/25 9:15	
Date/Time Analyzed:	9/9/25 17:51		9/9/25 18:06		9/9/25 18:20		9/9/25 18:35	
QC Batch No.:	250909GC8A2		250909GC8A2		250909GC8A2		250909GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	52	0.010	61	0.010	75	0.010	72	0.010
Oxygen/Argon	1.2	0.50	0.50	0.50	1.3	0.50	1.2	0.50
Nitrogen	5.1	1.0	3.0	1.0	4.9	1.0	9.3	1.0
Methane	39	0.0010	32	0.0010	16	0.0010	10	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: Mark Johnson
Operations Manager

Date 9/23/27

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/09/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S090904-09		S090904-10					
Client Sample I.D.:	CV-2346		CV-2345					
Date/Time Sampled:	9/9/25 9:20		9/9/25 9:25					
Date/Time Analyzed:	9/9/25 18:49		9/9/25 19:04					
QC Batch No.:	250909GC8A2		250909GC8A2					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v				
Carbon Dioxide	71	0.010	74	0.010				
Oxygen/Argon	1.5	0.50	0.59	0.50				
Nitrogen	9.3	1.0	3.0	1.0				
Methane	8.2	0.0010	19	0.0010				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: ______________________
Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

QC Batch No: 250909GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	9/9/25 16:24			9/9/25 15:41		9/9/25 15:55					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	10.00	100	9.97	100	0.2	70	130	30
Oxygen/Argon	ND	0.50	15	15.0	99	14.9	99	0.2	70	130	30
Nitrogen	ND	1.0	70	71.6	103	71.5	103	0.2	70	130	30
Methane	ND	0.0010	0.10	0.101	100	0.101	100	0.5	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _______________ Date 9/23/25
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

AirTECHNOLOGY
Laboratories, Inc.

September 29, 2025

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175

TX Cert T104704450-14-6
EPA Methods TO14A, TO15

ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference:	Chiquita Canyon Landfill
Project Number:	07224200.24 Task 1
Lab Number:	S091007-01/10

Enclosed are the results for sample(s) received 9/10/25 by Air Technology. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were received in Mylar bags. Benzyl chloride required quadratic regression calibration.
- The TO-15 analyses were performed outside the 24-hr holding-time due to low liquid nitrogen pressure.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Jenny Kim, Art Jones and Ali Ferrara on 9/23/25.

ATL appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Annika Sotelo Sanchez for

Mark Johnson
Operations Manager
MJohnson@AirTechLabs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME: Standard ☒ 48 hours ☐ Same Day ☐ 72 hours ☐ 24 hours ☐ 96 hours ☐ Other:

DELIVERABLES: EDD ☒ EDF ☐ Level 3 ☐ Level 4 ☐

PAGE: 1 OF

Condition upon receipt: Sealed Yes ☐ No ☐ Intact Yes ☐ No ☐ Chilled ______ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 100
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.: 07-SO05310
Bill to:
07FSAccountspayable@scsengineers.com
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
S091007-01	CV-108-52	9/10/2025	10:00AM	2-1L	Gas	N	X	X	X	X		
-02	CV-1532A	9/10/2025	10:10AM	2-1L	Gas	N	X	X	X	X		
-03	CV-2301	9/10/2025	9:20AM	2-1L	Gas	N	X	X	X	X		
-04	CV-2302	9/10/2025	9:15AM	2-1L	Gas	N	X	X	X	X		
-05	CV-2328	9/10/2025	8:55AM	1L	Gas	N	X	X	X			
-06	H-2273W	9/10/2025	10:25AM	2-1L	Gas	N	X	X	X	X		
-07	CV-24069	9/10/2025	9:30AM	1L	Gas	N	X	X	X			
-08	CV-24070	9/10/2025	9:45AM	1L	Gas	N	X	X	X			
-09	CV-24071	9/10/2025	9:40AM	1L	Gas	N	X	X	X			
-10	CV-24062	9/10/2025	9:10AM	1L	Gas	N	X	X	X			

AUTHORIZATION TO PERFORM WORK	COMPANY	DATE/TIME
SAMPLED BY: Fabian Chavez	COMPANY: SCS	DATE/TIME: 9-10-25

RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME
Antonio Ambriz	9/10/25 11:15am	Rubens 6	9/10/25 11:15am
Rubens 6	9/10/25 12:35	[illegible]	9/10/25 1255

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other________

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: H=HCl N=None / Container: B=Bag C=Can V=VOA O=Other

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/10/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	S091007-01		S091007-02		S091007-03		S091007-04	
Client Sample I.D.:	CV-108-52		CV-1532A		CV-2301		CV-2302	
Date/Time Sampled:	9/10/25 10:00		9/10/25 10:10		9/10/25 9:20		9/10/25 9:15	
Date/Time Analyzed:	9/11/2025 21:26*		9/11/2025 22:06*		9/11/2025 22:46*		9/11/2025 23:25*	
QC Batch No.:	250911MS2A1		250911MS2A1		250911MS2A1		250911MS2A1	
Analyst Initials:	RC		RC		RC		RC	
Dilution Factor:	1,000		1,300		6,000		900	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	1,000	ND	1,300	ND	6,000	ND	900
Chloromethane	ND	1,000	ND	1,300	ND	6,000	ND	900
1,2-Cl-1,1,2,2-F ethane (114)	ND	1,000	ND	1,300	ND	6,000	ND	900
Vinyl Chloride	ND	1,000	ND	1,300	ND	6,000	ND	900
Bromomethane	ND	1,000	ND	1,300	ND	6,000	ND	900
Chloroethane	ND	5,000	ND	6,300	ND	30,000	ND	4,500
Trichlorofluoromethane (11)	ND	1,000	ND	1,300	ND	6,000	ND	900
1,1-Dichloroethene	ND	1,000	ND	1,300	ND	6,000	ND	900
Carbon Disulfide	**1,000**	1,000	**3,800**	1,300	**11,000**	6,000	**1,400**	900
1,1,2-Cl 1,2,2-F ethane (113)	ND	1,000	ND	1,300	ND	6,000	ND	900
Acetone	**160,000**	7,000	**240,000**	8,800	**910,000**	42,000	**110,000**	6,300
Methylene Chloride	ND	1,000	ND	1,300	ND	6,000	ND	900
t-1,2-Dichloroethene	ND	1,000	ND	1,300	ND	6,000	ND	900
1,1-Dichloroethane	ND	1,000	ND	1,300	ND	6,000	ND	900
Vinyl Acetate	ND	1,000	ND	1,300	ND	6,000	ND	900
c-1,2-Dichloroethene	ND	1,000	ND	1,300	ND	6,000	ND	900
2-Butanone	**89,000**	5,000	**100,000**	6,300	**430,000**	30,000	**51,000**	4,500
t-Butyl Methyl Ether (MTBE)	ND	1,000	ND	1,300	ND	6,000	ND	900
Chloroform	ND	1,000	ND	1,300	ND	6,000	ND	900
1,1,1-Trichloroethane	ND	1,000	ND	1,300	ND	6,000	ND	900
Carbon Tetrachloride	ND	1,000	ND	1,300	ND	6,000	ND	900
Benzene	**96,000**	1,000	**37,000**	1,300	**190,000**	6,000	**17,000**	900
1,2-Dichloroethane	ND	1,000	ND	1,300	ND	6,000	ND	900
Trichloroethene	ND	1,000	ND	1,300	ND	6,000	ND	900
1,2-Dichloropropane	ND	1,000	ND	1,300	ND	6,000	ND	900
Bromodichloromethane	ND	1,000	ND	1,300	ND	6,000	ND	900
c-1,3-Dichloropropene	ND	1,000	ND	1,300	ND	6,000	ND	900
4-Methyl-2-Pentanone	**1,800**	1,000	ND	1,300	**6,600**	6,000	ND	900
Toluene	**3,100**	1,000	**1,600**	1,300	**11,000**	6,000	**990**	900
t-1,3-Dichloropropene	ND	2,000	ND	2,500	ND	12,000	ND	1,800
1,1,2-Trichloroethane	ND	1,000	ND	1,300	ND	6,000	ND	900
Tetrachloroethene	ND	1,000	ND	1,300	ND	6,000	ND	900
2-Hexanone	ND	1,000	ND	1,300	ND	6,000	ND	900
Dibromochloromethane	ND	1,000	ND	1,300	ND	6,000	ND	900

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/10/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	S091007-01		S091007-02		S091007-03		S091007-04	
Client Sample I.D.:	CV-108-52		CV-1532A		CV-2301		CV-2302	
Date/Time Sampled:	9/10/25 10:00		9/10/25 10:10		9/10/25 9:20		9/10/25 9:15	
Date/Time Analyzed:	9/11/2025 21:26*		9/11/2025 22:06*		9/11/2025 22:46*		9/11/2025 23:25*	
QC Batch No.:	250911MS2A1		250911MS2A1		250911MS2A1		250911MS2A1	
Analyst Initials:	RC		RC		RC		RC	
Dilution Factor:	1,000		1,300		6,000		900	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	1,000	ND	1,300	ND	6,000	ND	900
Chlorobenzene	ND	1,000	ND	1,300	ND	6,000	ND	900
Ethylbenzene	ND	1,000	ND	1,300	ND	6,000	ND	900
p,&m-Xylene	ND	2,000	ND	2,500	ND	12,000	ND	1,800
o-Xylene	ND	1,000	ND	1,300	ND	6,000	ND	900
Styrene	ND	1,000	ND	1,300	ND	6,000	ND	900
Bromoform	ND	1,000	ND	1,300	ND	6,000	ND	900
1,1,2,2-Tetrachloroethane	ND	1,000	ND	1,300	ND	6,000	ND	900
Benzyl Chloride	ND	1,000	ND	1,300	ND	6,000	ND	900
4-Ethyl Toluene	ND	1,000	ND	1,300	ND	6,000	ND	900
1,3,5-Trimethylbenzene	ND	1,000	ND	1,300	ND	6,000	ND	900
1,2,4-Trimethylbenzene	ND	1,000	ND	1,300	ND	6,000	ND	900
1,3-Dichlorobenzene	ND	1,000	ND	1,300	ND	6,000	ND	900
1,4-Dichlorobenzene	ND	1,000	ND	1,300	ND	6,000	ND	900
1,2-Dichlorobenzene	ND	1,000	ND	1,300	ND	6,000	ND	900
1,2,4-Trichlorobenzene	ND	2,000	ND	2,500	ND	12,000	ND	1,800
Hexachlorobutadiene	ND	1,000	ND	1,300	ND	6,000	ND	900
1,3-Butadiene	ND	5,000	ND	6,300	ND	30,000	ND	4,500
Isopropanol	**78,000**	5,000	**65,000**	6,300	**170,000**	30,000	**64,000**	4,500
n-Hexane	ND	5,000	ND	6,300	ND	30,000	ND	4,500
Ethyl Acetate	**10,000**	5,000	**12,000**	6,300	**69,000**	30,000	**7,400**	4,500
Tetrahydrofuran	**87,000**	5,000	**68,000**	6,300	**390,000**	30,000	**29,000**	4,500
Cyclohexane	ND	5,000	ND	6,300	ND	30,000	ND	4,500
Heptane	ND	5,000	ND	6,300	ND	30,000	ND	4,500
1,4-Dioxane	ND	5,000	ND	6,300	ND	30,000	ND	4,500

RL = Reporting Limit
ND = Not Detected (below RL)
* = Samples were analyzed outside the 24 HR recommended hold time.

Reviewed/Approved By: MJ
Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/10/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	S091007-06							
Client Sample I.D.:	H-2273W							
Date/Time Sampled:	9/10/25 10:25							
Date/Time Analyzed:	9/12/2025 00:05*							
QC Batch No.:	250911MS2A1							
Analyst Initials:	RC							
Dilution Factor:	1,200							
ANALYTE	Result ppbv	RL ppbv						
Dichlorodifluoromethane (12)	ND	1,200						
Chloromethane	ND	1,200						
1,2-Cl-1,1,2,2-F ethane (114)	ND	1,200						
Vinyl Chloride	ND	1,200						
Bromomethane	ND	1,200						
Chloroethane	ND	6,000						
Trichlorofluoromethane (11)	ND	1,200						
1,1-Dichloroethene	ND	1,200						
Carbon Disulfide	ND	1,200						
1,1,2-Cl 1,2,2-F ethane (113)	ND	1,200						
Acetone	140,000	8,400						
Methylene Chloride	ND	1,200						
t-1,2-Dichloroethene	ND	1,200						
1,1-Dichloroethane	ND	1,200						
Vinyl Acetate	ND	1,200						
c-1,2-Dichloroethene	ND	1,200						
2-Butanone	71,000	6,000						
t-Butyl Methyl Ether (MTBE)	ND	1,200						
Chloroform	ND	1,200						
1,1,1-Trichloroethane	ND	1,200						
Carbon Tetrachloride	ND	1,200						
Benzene	16,000	1,200						
1,2-Dichloroethane	ND	1,200						
Trichloroethene	ND	1,200						
1,2-Dichloropropane	ND	1,200						
Bromodichloromethane	ND	1,200						
c-1,3-Dichloropropene	ND	1,200						
4-Methyl-2-Pentanone	2,000	1,200						
Toluene	2,500	1,200						
t-1,3-Dichloropropene	ND	2,400						
1,1,2-Trichloroethane	ND	1,200						
Tetrachloroethene	ND	1,200						
2-Hexanone	ND	1,200						
Dibromochloromethane	ND	1,200						

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client:	SCS Engineers
Attn:	Cornelius Fong
Project Name:	Chiquita Canyon Landfill
Project No.:	07224200.24 Task 1
Date Received:	09/10/25
Matrix:	Air
Reporting Units:	ppbv

EPA Method TO-15

Lab No.:	S091007-06							
Client Sample I.D.:	H-2273W							
Date/Time Sampled:	9/10/25 10:25							
Date/Time Analyzed:	9/12/2025 00:05*							
QC Batch No.:	250911MS2A1							
Analyst Initials:	RC							
Dilution Factor:	1,200							
ANALYTE	Result ppbv	RL ppbv						
1,2-Dibromoethane	ND	1,200						
Chlorobenzene	ND	1,200						
Ethylbenzene	ND	1,200						
p,&m-Xylene	ND	2,400						
o-Xylene	ND	1,200						
Styrene	ND	1,200						
Bromoform	ND	1,200						
1,1,2,2-Tetrachloroethane	ND	1,200						
Benzyl Chloride	ND	1,200						
4-Ethyl Toluene	ND	1,200						
1,3,5-Trimethylbenzene	ND	1,200						
1,2,4-Trimethylbenzene	ND	1,200						
1,3-Dichlorobenzene	ND	1,200						
1,4-Dichlorobenzene	ND	1,200						
1,2-Dichlorobenzene	ND	1,200						
1,2,4-Trichlorobenzene	ND	2,400						
Hexachlorobutadiene	ND	1,200						
1,3-Butadiene	ND	6,000						
Isopropanol	81,000	6,000						
n-Hexane	ND	6,000						
Ethyl Acetate	14,000	6,000						
Tetrahydrofuran	38,000	6,000						
Cyclohexane	ND	6,000						
Heptane	ND	6,000						
1,4-Dioxane	ND	6,000						

RL = Reporting Limit
ND = Not Detected (below RL)
* = Samples were analyzed outside the 24 HR recommended hold time.

Reviewed/Approved By: _[signature]_ Date 9/23/25
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client:	SCS Engineers
Attn:	Cornelius Fong
Project Name:	Chiquita Canyon Landfill
Project No.:	07224200.24 Task 1
Date Received:	09/10/25
Matrix:	Air
Reporting Units:	ppbv

EPA Method TO-15

Lab No.:	METHOD_BLANK						
Client Sample I.D.:	--						
Date/Time Sampled:	--						
Date/Time Analyzed:	9/11/25 20:46						
QC Batch No.:	250911MS2A1						
Analyst Initials:	RC						
Dilution Factor:	1.0						
ANALYTE	**Result ppbv**	**RL ppbv**					
Dichlorodifluoromethane (12)	ND	1.0					
Chloromethane	ND	1.0					
1,2-Cl-1,1,2,2-F ethane (114)	ND	1.0					
Vinyl Chloride	ND	1.0					
Bromomethane	ND	1.0					
Chloroethane	ND	5.0					
Trichlorofluoromethane (11)	ND	1.0					
1,1-Dichloroethene	ND	1.0					
Carbon Disulfide	ND	1.0					
1,1,2-Cl 1,2,2-F ethane (113)	ND	1.0					
Acetone	ND	7.0					
Methylene Chloride	ND	1.0					
t-1,2-Dichloroethene	ND	1.0					
1,1-Dichloroethane	ND	1.0					
Vinyl Acetate	ND	1.0					
c-1,2-Dichloroethene	ND	1.0					
2-Butanone	ND	5.0					
t-Butyl Methyl Ether (MTBE)	ND	1.0					
Chloroform	ND	1.0					
1,1,1-Trichloroethane	ND	1.0					
Carbon Tetrachloride	ND	1.0					
Benzene	ND	1.0					
1,2-Dichloroethane	ND	1.0					
Trichloroethene	ND	1.0					
1,2-Dichloropropane	ND	1.0					
Bromodichloromethane	ND	1.0					
c-1,3-Dichloropropene	ND	1.0					
4-Methyl-2-Pentanone	ND	1.0					
Toluene	ND	1.0					
t-1,3-Dichloropropene	ND	2.0					
1,1,2-Trichloroethane	ND	1.0					
Tetrachloroethene	ND	1.0					
2-Hexanone	ND	1.0					
Dibromochloromethane	ND	1.0					

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client:	SCS Engineers
Attn:	Cornelius Fong
Project Name:	Chiquita Canyon Landfill
Project No.:	07224200.24 Task 1
Date Received:	09/10/25
Matrix:	Air
Reporting Units:	ppbv

EPA Method TO-15

Lab No.:	METHOD_BLANK							
Client Sample I.D.:	--							
Date/Time Sampled:	--							
Date/Time Analyzed:	9/11/25 20:46							
QC Batch No.:	250911MS2A1							
Analyst Initials:	RC							
Dilution Factor:	1.0							
ANALYTE	**Result ppbv**	**RL ppbv**						
1,2-Dibromoethane	ND	1.0						
Chlorobenzene	ND	1.0						
Ethylbenzene	ND	1.0						
p,&m-Xylene	ND	2.0						
o-Xylene	ND	1.0						
Styrene	ND	1.0						
Bromoform	ND	1.0						
1,1,2,2-Tetrachloroethane	ND	1.0						
Benzyl Chloride	ND	1.0						
4-Ethyl Toluene	ND	1.0						
1,3,5-Trimethylbenzene	ND	1.0						
1,2,4-Trimethylbenzene	ND	1.0						
1,3-Dichlorobenzene	ND	1.0						
1,4-Dichlorobenzene	ND	1.0						
1,2-Dichlorobenzene	ND	1.0						
1,2,4-Trichlorobenzene	ND	2.0						
Hexachlorobutadiene	ND	1.0						
1,3-Butadiene	ND	5.0						
Isopropanol	ND	5.0						
n-Hexane	ND	5.0						
Ethyl Acetate	ND	5.0						
Tetrahydrofuran	ND	5.0						
Cyclohexane	ND	5.0						
Heptane	ND	5.0						
1,4-Dioxane	ND	5.0						

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: ______________
Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 250911MS2A1

Matrix: Air
Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD						
Date/Time Analyzed:	9/11/25 20:46			9/11/25 19:26		9/11/25 20:06						
Analyst Initials:	RC			RC		RC						
Dilution Factor:	1.0			1.0		1.0						
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	1.0	10	11.1	111	11.5	115	3.3	70	130	30
Methylene Chloride	ND	1.0	10	11.0	110	11.3	113	2.6	70	130	30
Trichloroethene	ND	1.0	10	10.7	107	10.6	106	1.3	70	130	30
Toluene	ND	1.0	10	10.5	105	10.4	104	0.5	70	130	30
1,1,2,2-Tetrachloroethane	ND	1.0	10	11.6	116	11.5	115	0.9	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: [signature]
Mark Johnson
Operations Manager

Date: 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/10/25
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	S091007-01		S091007-02		S091007-03		S091007-04	
Client Sample I.D.:	CV-108-52		CV-1532A		CV-2301		CV-2302	
Date/Time Sampled:	9/10/25 10:00		9/10/25 10:10		9/10/25 9:20		9/10/25 9:15	
Date/Time Analyzed:	9/10/25 18:45		9/10/25 19:00		9/10/25 19:14		9/10/25 19:29	
QC Batch No.:	250910GC8A2		250910GC8A2		250910GC8A2		250910GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	380	10	730	10	890	10	100	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: Mark Johnson
Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/10/25
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	S091007-05		S091007-06		S091007-07		S091007-08	
Client Sample I.D.:	CV-2328		H-2273W		CV-24069		CV-24070	
Date/Time Sampled:	9/10/25 8:55		9/10/25 10:25		9/10/25 9:30		9/10/25 9:45	
Date/Time Analyzed:	9/10/25 19:43		9/10/25 19:58		9/10/25 20:12		9/10/25 20:27	
QC Batch No.:	250910GC8A2		250910GC8A2		250910GC8A2		250910GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	1,400	10	110	10	310	10	150	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: Matt. f
Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/10/25
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	S091007-09		S091007-10					
Client Sample I.D.:	CV-24071		CV-24062					
Date/Time Sampled:	9/10/25 9:40		9/10/25 9:10					
Date/Time Analyzed:	9/10/25 20:41		9/10/25 20:56					
QC Batch No.:	250910GC8A2		250910GC8A2					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv				
Carbon Monoxide	220	10	780	10				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: ______________ Date 9/23/25
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

QC Batch No: 250910GC8A2
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	9/10/25 18:16			9/10/25 17:33		9/10/25 17:47					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,070	106	1,070	106	0.0	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: [signature]
Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

Client:	SCS Engineers
Attn:	Cornelius Fong
Project Name:	Chiquita Canyon Landfill
Project No.:	07224200.24 Task 1
Date Received:	09/10/25
Matrix:	Air
Reporting Units:	% v/v

ASTM D1946

Lab No.:	S091007-01			S091007-02			S091007-03			S091007-04		
Client Sample I.D.:	CV-108-52			CV-1532A			CV-2301			CV-2302		
Date/Time Sampled:	9/10/25 10:00			9/10/25 10:10			9/10/25 9:20			9/10/25 9:15		
Date/Time Analyzed:	9/10/25 18:45			9/10/25 19:00			9/10/25 19:14			9/10/25 19:29		
QC Batch No.:	250910GC8A2			250910GC8A2			250910GC8A2			250910GC8A2		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	2.1	1.0	0.059	6.1	1.0	0.059	11	1.0	0.059	1.9	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: [signature]
Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/10/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S091007-05			S091007-06			S091007-07			S091007-08		
Client Sample I.D.:	CV-2328			H-2273W			CV-24069			CV-24070		
Date/Time Sampled:	9/10/25 8:55			9/10/25 10:25			9/10/25 9:30			9/10/25 9:45		
Date/Time Analyzed:	9/10/25 19:43			9/10/25 19:58			9/10/25 20:12			9/10/25 20:27		
QC Batch No.:	250910GC8A2			250910GC8A2			250910GC8A2			250910GC8A2		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	11	1.0	0.059	1.5	1.0	0.059	4.5	1.0	0.059	2.8	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: Matt
Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/10/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946												
Lab No.:	S091007-09			S091007-10								
Client Sample I.D.:	CV-24071			CV-24062								
Date/Time Sampled:	9/10/25 9:40			9/10/25 9:10								
Date/Time Analyzed:	9/10/25 20:41			9/10/25 20:56								
QC Batch No.:	250910GC8A2			250910GC8A2								
Analyst Initials:	KD			KD								
Dilution Factor:	1.0			1.0								
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v						
Hydrogen	2.8	1.0	0.059	7.5	1.0	0.059						

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _______________
Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

QC Batch No: 250910GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	9/10/25 18:16				9/10/25 17:33		9/10/25 17:47					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	5.28	106	5.28	106	0.1	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: MM for
Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/10/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S091007-01		S091007-02		S091007-03		S091007-04	
Client Sample I.D.:	CV-108-52		CV-1532A		CV-2301		CV-2302	
Date/Time Sampled:	9/10/25 10:00		9/10/25 10:10		9/10/25 9:20		9/10/25 9:15	
Date/Time Analyzed:	9/10/25 18:45		9/10/25 19:00		9/10/25 19:14		9/10/25 19:29	
QC Batch No.:	250910GC8A2		250910GC8A2		250910GC8A2		250910GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	55	0.010	28	0.010	64	0.010	41	0.010
Oxygen/Argon	0.67	0.50	14	0.50	0.68	0.50	1.9	0.50
Nitrogen	2.4	1.0	50	1.0	2.4	1.0	7.0	1.0
Methane	40	0.0010	1.7	0.0010	21	0.0010	48	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: MJohnson for
Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client:	SCS Engineers
Attn:	Cornelius Fong
Project Name:	Chiquita Canyon Landfill
Project No.:	07224200.24 Task 1
Date Received:	09/10/25
Matrix:	Air
Reporting Units:	% v/v

ASTM D1946

Lab No.:	S091007-05		S091007-06		S091007-07		S091007-08	
Client Sample I.D.:	CV-2328		H-2273W		CV-24069		CV-24070	
Date/Time Sampled:	9/10/25 8:55		9/10/25 10:25		9/10/25 9:30		9/10/25 9:45	
Date/Time Analyzed:	9/10/25 19:43		9/10/25 19:58		9/10/25 20:12		9/10/25 20:27	
QC Batch No.:	250910GC8A2		250910GC8A2		250910GC8A2		250910GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	67	0.010	47	0.010	43	0.010	51	0.010
Oxygen/Argon	4.2	0.50	0.86	0.50	5.0	0.50	1.3	0.50
Nitrogen	15	1.0	13	1.0	18	1.0	4.7	1.0
Methane	1.7	0.0010	37	0.0010	28	0.0010	39	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: [signature]
Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/10/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S091007-09		S091007-10					
Client Sample I.D.:	CV-24071		CV-24062					
Date/Time Sampled:	9/10/25 9:40		9/10/25 9:10					
Date/Time Analyzed:	9/10/25 20:41		9/10/25 20:56					
QC Batch No.:	250910GC8A2		250910GC8A2					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v				
Carbon Dioxide	51	0.010	61	0.010				
Oxygen/Argon	1.4	0.50	2.4	0.50				
Nitrogen	4.9	1.0	8.5	1.0				
Methane	40	0.0010	20	0.0010				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: ________________
Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

QC Batch No: 250910GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD				
Date Analyzed:	9/10/25 18:16			9/10/25 17:33		9/10/25 17:47				
Analyst Initials:	KD			KD		KD				
Dilution Factor:	1.0			1.0		1.0			Limits	
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	9.86	98	9.82	98	0.4	70	130	30
Oxygen/Argon	ND	0.50	15	15.1	100	15.0	100	0.2	70	130	30
Nitrogen	ND	1.0	70	72.0	103	71.9	103	0.2	70	130	30
Methane	ND	0.0010	0.10	0.101	100	0.101	100	0.2	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: Mark Johnson
Mark Johnson
Operations Manager

Date 9/23/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.

September 29, 2025

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175

TX Cert T104704450-14-6
EPA Methods TO14A, TO15

ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: S091102-01/07

Enclosed are the results for sample(s) received 9/11/25 by Air Technology. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags. Benzyl chloride required quadratic regression calibration.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Jenny Kim, Art Jones and Ali Ferrara on 9/26/25.

ATL appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Annika Sotelo Sanchez for

Mark Johnson
Operations Manager
MJohnson@AirTechLabs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐
Other:				Level 4	☐	Chilled ____

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 100
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.: 07-SO05310

Bill to:

07FSAccountspayable@scsengineers.com

3900 Kilroy Airport Way, Suite 100

Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15	
S091102-01	CV-2314	9/11/2025	8:25AM	1L	Gas	N	X	X	X		
-02	CV-114	9/11/2025	8:55AM	1L	Gas	N	X	X	X		
-03	CV-24120	9/11/2025	9:00AM	1L	Gas	N	X	X	X		
-04	CV-24053	9/11/2025	8:20AM	2-1L	Gas	N	X	X	X	X	
-05	CV-24017	9/11/2025	7:50AM	2-1L	Gas	N	X	X	X	X	
-06	CV-24007	9/11/2025	7:45AM	2-1L	Gas	N	X	X	X	X	
-07	CV-2303	9/11/2025	8:05AM	2-1L	Gas	N	X	X	X	X	

AUTHORIZATION TO PERFORM WORK	COMPANY			DATE/TIME
SAMPLED BY **Jaime Coronel**	**SCS**			DATE/TIME 9/11/25
RELINQUISHED BY **Antonio Ambriz**	DATE/TIME 9/11/25 11:47am	RECEIVED BY S Ferrer		DATE/TIME 11:47 9-11-25
RELINQUISHED BY S Ferrer	DATE/TIME 9/11/25 12:52	RECEIVED BY [signature]		DATE/TIME 9/11/25 12:52
RELINQUISHED BY	DATE/TIME	RECEIVED BY		DATE/TIME

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other________

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: H=HCl N=None / Container: B=Bag C=Can V=VOA O=Other *Rev. 03*

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/11/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	S091102-04		S091102-05		S091102-06		S091102-07	
Client Sample I.D.:	CV-24053		CV-24017		CV-24007		CV-2303	
Date/Time Sampled:	9/11/25 8:20		9/11/25 7:50		9/11/25 7:45		9/11/25 8:05	
Date/Time Analyzed:	9/12/25 2:44		9/12/25 3:23		9/12/25 4:02		9/12/25 4:42	
QC Batch No.:	250911MS2A1		250911MS2A1		250911MS2A1		250911MS2A1	
Analyst Initials:	RC		RC		RC		RC	
Dilution Factor:	4,000		1,300		700		1,500	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	4,000	ND	1,300	ND	700	ND	1,500
Chloromethane	ND	4,000	7,400	1,300	ND	700	ND	1,500
1,2-Cl-1,1,2,2-F ethane (114)	ND	4,000	ND	1,300	ND	700	ND	1,500
Vinyl Chloride	ND	4,000	ND	1,300	ND	700	ND	1,500
Bromomethane	ND	4,000	ND	1,300	ND	700	ND	1,500
Chloroethane	ND	20,000	ND	6,300	ND	3,500	ND	7,500
Trichlorofluoromethane (11)	ND	4,000	ND	1,300	ND	700	ND	1,500
1,1-Dichloroethene	ND	4,000	ND	1,300	ND	700	ND	1,500
Carbon Disulfide	5,300	4,000	ND	1,300	ND	700	2,800	1,500
1,1,2-Cl 1,2,2-F ethane (113)	ND	4,000	ND	1,300	ND	700	ND	1,500
Acetone	630,000	28,000	210,000	8,800	140,000	4,900	290,000	11,000
Methylene Chloride	ND	4,000	ND	1,300	ND	700	ND	1,500
t-1,2-Dichloroethene	ND	4,000	ND	1,300	ND	700	ND	1,500
1,1-Dichloroethane	ND	4,000	ND	1,300	ND	700	ND	1,500
Vinyl Acetate	ND	4,000	ND	1,300	ND	700	ND	1,500
c-1,2-Dichloroethene	ND	4,000	ND	1,300	ND	700	ND	1,500
2-Butanone	290,000	20,000	91,000	6,300	58,000	3,500	130,000	7,500
t-Butyl Methyl Ether (MTBE)	ND	4,000	ND	1,300	ND	700	ND	1,500
Chloroform	ND	4,000	ND	1,300	ND	700	ND	1,500
1,1,1-Trichloroethane	ND	4,000	ND	1,300	ND	700	ND	1,500
Carbon Tetrachloride	ND	4,000	ND	1,300	ND	700	ND	1,500
Benzene	240,000	4,000	72,000	1,300	64,000	700	120,000	1,500
1,2-Dichloroethane	ND	4,000	ND	1,300	ND	700	ND	1,500
Trichloroethene	ND	4,000	ND	1,300	ND	700	ND	1,500
1,2-Dichloropropane	ND	4,000	ND	1,300	ND	700	ND	1,500
Bromodichloromethane	ND	4,000	ND	1,300	ND	700	ND	1,500
c-1,3-Dichloropropene	ND	4,000	ND	1,300	ND	700	ND	1,500
4-Methyl-2-Pentanone	ND	4,000	1,400	1,300	800	700	2,300	1,500
Toluene	11,000	4,000	2,100	1,300	1,100	700	4,100	1,500
t-1,3-Dichloropropene	ND	8,000	ND	2,500	ND	1,400	ND	3,000
1,1,2-Trichloroethane	ND	4,000	ND	1,300	ND	700	ND	1,500
Tetrachloroethene	ND	4,000	ND	1,300	ND	700	ND	1,500
2-Hexanone	ND	4,000	ND	1,300	ND	700	ND	1,500
Dibromochloromethane	ND	4,000	ND	1,300	ND	700	ND	1,500

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/11/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	S091102-04		S091102-05		S091102-06		S091102-07	
Client Sample I.D.:	CV-24053		CV-24017		CV-24007		CV-2303	
Date/Time Sampled:	9/11/25 8:20		9/11/25 7:50		9/11/25 7:45		9/11/25 8:05	
Date/Time Analyzed:	9/12/25 2:44		9/12/25 3:23		9/12/25 4:02		9/12/25 4:42	
QC Batch No.:	250911MS2A1		250911MS2A1		250911MS2A1		250911MS2A1	
Analyst Initials:	RC		RC		RC		RC	
Dilution Factor:	4,000		1,300		700		1,500	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	4,000	ND	1,300	ND	700	ND	1,500
Chlorobenzene	ND	4,000	ND	1,300	ND	700	ND	1,500
Ethylbenzene	ND	4,000	ND	1,300	ND	700	ND	1,500
p,&m-Xylene	ND	8,000	ND	2,500	ND	1,400	ND	3,000
o-Xylene	ND	4,000	ND	1,300	ND	700	ND	1,500
Styrene	ND	4,000	ND	1,300	ND	700	ND	1,500
Bromoform	ND	4,000	ND	1,300	ND	700	ND	1,500
1,1,2,2-Tetrachloroethane	ND	4,000	ND	1,300	ND	700	ND	1,500
Benzyl Chloride	ND	4,000	ND	1,300	ND	700	ND	1,500
4-Ethyl Toluene	ND	4,000	ND	1,300	ND	700	ND	1,500
1,3,5-Trimethylbenzene	ND	4,000	ND	1,300	ND	700	ND	1,500
1,2,4-Trimethylbenzene	ND	4,000	ND	1,300	ND	700	ND	1,500
1,3-Dichlorobenzene	ND	4,000	ND	1,300	ND	700	ND	1,500
1,4-Dichlorobenzene	ND	4,000	ND	1,300	ND	700	ND	1,500
1,2-Dichlorobenzene	ND	4,000	ND	1,300	ND	700	ND	1,500
1,2,4-Trichlorobenzene	ND	8,000	ND	2,500	ND	1,400	ND	3,000
Hexachlorobutadiene	ND	4,000	ND	1,300	ND	700	ND	1,500
1,3-Butadiene	ND	20,000	ND	6,300	**5,400**	3,500	ND	7,500
Isopropanol	**86,000**	20,000	**64,000**	6,300	**34,000**	3,500	**64,000**	7,500
n-Hexane	ND	20,000	ND	6,300	ND	3,500	ND	7,500
Ethyl Acetate	**33,000**	20,000	**10,000**	6,300	**5,700**	3,500	**15,000**	7,500
Tetrahydrofuran	**220,000**	20,000	**89,000**	6,300	**49,000**	3,500	**110,000**	7,500
Cyclohexane	ND	20,000	ND	6,300	ND	3,500	ND	7,500
Heptane	ND	20,000	ND	6,300	ND	3,500	ND	7,500
1,4-Dioxane	ND	20,000	ND	6,300	ND	3,500	ND	7,500

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: [signature]
Mark Johnson
Operations Manager

Date 9/26/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/11/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD_BLANK							
Client Sample I.D.:	--							
Date/Time Sampled:	--							
Date/Time Analyzed:	9/11/25 20:46							
QC Batch No.:	250911MS2A1							
Analyst Initials:	RC							
Dilution Factor:	1.0							
ANALYTE	Result ppbv	RL ppbv						
Dichlorodifluoromethane (12)	ND	1.0						
Chloromethane	ND	1.0						
1,2-Cl-1,1,2,2-F ethane (114)	ND	1.0						
Vinyl Chloride	ND	1.0						
Bromomethane	ND	1.0						
Chloroethane	ND	5.0						
Trichlorofluoromethane (11)	ND	1.0						
1,1-Dichloroethene	ND	1.0						
Carbon Disulfide	ND	1.0						
1,1,2-Cl 1,2,2-F ethane (113)	ND	1.0						
Acetone	ND	7.0						
Methylene Chloride	ND	1.0						
t-1,2-Dichloroethene	ND	1.0						
1,1-Dichloroethane	ND	1.0						
Vinyl Acetate	ND	1.0						
c-1,2-Dichloroethene	ND	1.0						
2-Butanone	ND	5.0						
t-Butyl Methyl Ether (MTBE)	ND	1.0						
Chloroform	ND	1.0						
1,1,1-Trichloroethane	ND	1.0						
Carbon Tetrachloride	ND	1.0						
Benzene	ND	1.0						
1,2-Dichloroethane	ND	1.0						
Trichloroethene	ND	1.0						
1,2-Dichloropropane	ND	1.0						
Bromodichloromethane	ND	1.0						
c-1,3-Dichloropropene	ND	1.0						
4-Methyl-2-Pentanone	ND	1.0						
Toluene	ND	1.0						
t-1,3-Dichloropropene	ND	2.0						
1,1,2-Trichloroethane	ND	1.0						
Tetrachloroethene	ND	1.0						
2-Hexanone	ND	1.0						
Dibromochloromethane	ND	1.0						

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/11/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD_BLANK							
Client Sample I.D.:	--							
Date/Time Sampled:	--							
Date/Time Analyzed:	9/11/25 20:46							
QC Batch No.:	250911MS2A1							
Analyst Initials:	RC							
Dilution Factor:	1.0							
ANALYTE	**Result ppbv**	**RL ppbv**						
1,2-Dibromoethane	ND	1.0						
Chlorobenzene	ND	1.0						
Ethylbenzene	ND	1.0						
p,&m-Xylene	ND	2.0						
o-Xylene	ND	1.0						
Styrene	ND	1.0						
Bromoform	ND	1.0						
1,1,2,2-Tetrachloroethane	ND	1.0						
Benzyl Chloride	ND	1.0						
4-Ethyl Toluene	ND	1.0						
1,3,5-Trimethylbenzene	ND	1.0						
1,2,4-Trimethylbenzene	ND	1.0						
1,3-Dichlorobenzene	ND	1.0						
1,4-Dichlorobenzene	ND	1.0						
1,2-Dichlorobenzene	ND	1.0						
1,2,4-Trichlorobenzene	ND	2.0						
Hexachlorobutadiene	ND	1.0						
1,3-Butadiene	ND	5.0						
Isopropanol	ND	5.0						
n-Hexane	ND	5.0						
Ethyl Acetate	ND	5.0						
Tetrahydrofuran	ND	5.0						
Cyclohexane	ND	5.0						
Heptane	ND	5.0						
1,4-Dioxane	ND	5.0						

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: ______ **Date** 9/26/25
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 250911MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	9/11/25 20:46			9/11/25 19:26		9/11/25 20:06					
Analyst Initials:	RC			RC		RC					
Dilution Factor:	1.0			1.0		1.0					
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	1.0	10	11.1	111	11.5	115	3.3	70	130	30
Methylene Chloride	ND	1.0	10	11.0	110	11.3	113	2.6	70	130	30
Trichloroethene	ND	1.0	10	10.7	107	10.6	106	1.3	70	130	30
Toluene	ND	1.0	10	10.5	105	10.4	104	0.5	70	130	30
1,1,2,2-Tetrachloroethane	ND	1.0	10	11.6	116	11.5	115	0.9	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: [signature]
Mark Johnson
Operations Manager

Date: 9/26/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/11/25
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	S091102-01		S091102-02		S091102-03		S091102-04	
Client Sample I.D.:	CV-2314		CV-114		CV-24120		CV-24053	
Date/Time Sampled:	9/11/25 8:25		9/11/25 8:55		9/11/25 9:00		9/11/25 8:20	
Date/Time Analyzed:	9/11/25 15:37		9/11/25 15:52		9/11/25 16:06		9/11/25 16:21	
QC Batch No.:	250911GC8A2		250911GC8A2		250911GC8A2		250911GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	1,200	10	2,100	10	1,300	10	1,700	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: Mark Johnson
Operations Manager

Date 9/12/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/11/25
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	S091102-05		S091102-06		S091102-07			
Client Sample I.D.:	CV-24017		CV-24007		CV-2303			
Date/Time Sampled:	9/11/25 7:50		9/11/25 7:45		9/11/25 8:05			
Date/Time Analyzed:	9/11/25 16:35		9/11/25 16:50		9/11/25 17:04			
QC Batch No.:	250911GC8A2		250911GC8A2		250911GC8A2			
Analyst Initials:	KD		KD		KD			
Dilution Factor:	1.0		1.0		1.0			
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv		
Carbon Monoxide	660	10	680	10	1,500	10		

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: Mark Johnson
Operations Manager

Date 9/26/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

QC Batch No: 250911GC8A2
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	9/11/25 15:08			9/11/25 14:25		9/11/25 14:39					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,070	106	1,070	106	0.2	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: Mark Johnson

Mark Johnson
Operations Manager

Date 9/26/25

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/11/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S091102-01			S091102-02			S091102-03			S091102-04		
Client Sample I.D.:	CV-2314			CV-114			CV-24120			CV-24053		
Date/Time Sampled:	9/11/25 8:25			9/11/25 8:55			9/11/25 9:00			9/11/25 8:20		
Date/Time Analyzed:	9/11/25 15:37			9/11/25 15:52			9/11/25 16:06			9/11/25 16:21		
QC Batch No.:	250911GC8A2			250911GC8A2			250911GC8A2			250911GC8A2		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	11	1.0	0.059	13	1.0	0.059	7.2	1.0	0.059	18	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: [signature]
Mark Johnson
Operations Manager

Date 9/26/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/11/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S091102-05			S091102-06			S091102-07					
Client Sample I.D.:	CV-24017			CV-24007			CV-2303					
Date/Time Sampled:	9/11/25 7:50			9/11/25 7:45			9/11/25 8:05					
Date/Time Analyzed:	9/11/25 16:35			9/11/25 16:50			9/11/25 17:04					
QC Batch No.:	250911GC8A2			250911GC8A2			250911GC8A2					
Analyst Initials:	KD			KD			KD					
Dilution Factor:	1.0			1.0			1.0					
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v			
Hydrogen	6.5	1.0	0.059	6.5	1.0	0.059	12	1.0	0.059			

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: Mark Johnson
Operations Manager

Date 9/26/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

QC Batch No: 250911GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	9/11/25 15:08				9/11/25 14:25		9/11/25 14:39					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	5.05	102	5.00	101	1.0	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: ______________________
Mark Johnson
Operations Manager

Date 9/26/25

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/11/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S091102-01		S091102-02		S091102-03		S091102-04	
Client Sample I.D.:	CV-2314		CV-114		CV-24120		CV-24053	
Date/Time Sampled:	9/11/25 8:25		9/11/25 8:55		9/11/25 9:00		9/11/25 8:20	
Date/Time Analyzed:	9/11/25 15:37		9/11/25 15:52		9/11/25 16:06		9/11/25 16:21	
QC Batch No.:	250911GC8A2		250911GC8A2		250911GC8A2		250911GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	67	0.010	60	0.010	78	0.010	71	0.010
Oxygen/Argon	1.4	0.50	5.4	0.50	1.3	0.50	ND	0.50
Nitrogen	5.1	1.0	20	1.0	4.6	1.0	1.5	1.0
Methane	15	0.0010	0.77	0.0010	8.4	0.0010	7.9	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: MMA
Mark Johnson
Operations Manager

Date 9/26/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/11/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S091102-05		S091102-06		S091102-07			
Client Sample I.D.:	CV-24017		CV-24007		CV-2303			
Date/Time Sampled:	9/11/25 7:50		9/11/25 7:45		9/11/25 8:05			
Date/Time Analyzed:	9/11/25 16:35		9/11/25 16:50		9/11/25 17:04			
QC Batch No.:	250911GC8A2		250911GC8A2		250911GC8A2			
Analyst Initials:	KD		KD		KD			
Dilution Factor:	1.0		1.0		1.0			
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v		
Carbon Dioxide	45	0.010	70	0.010	51	0.010		
Oxygen/Argon	7.8	0.50	3.2	0.50	7.7	0.50		
Nitrogen	29	1.0	12	1.0	29	1.0		
Methane	11	0.0010	8.3	0.0010	0.77	0.0010		

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _[signature]_
Mark Johnson
Operations Manager

Date 9/26/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

QC Batch No: 250911GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	9/11/25 15:08			9/11/25 14:25		9/11/25 14:39					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	9.67	97	9.66	96	0.1	70	130	30
Oxygen/Argon	ND	0.50	15	15.1	101	15.2	101	0.1	70	130	30
Nitrogen	ND	1.0	70	72.2	104	72.2	104	0.1	70	130	30
Methane	ND	0.0010	0.10	0.102	101	0.101	100	0.1	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: Mark Johnson
Operations Manager

Date 9/26/25

The cover letter is an integral part of this analytical report

18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

AirTECHNOLOGY Laboratories, Inc.

September 30, 2025

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175

TX Cert T104704450-14-6
EPA Methods TO14A, TO15

ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference:	Chiquita Canyon Landfill
Project Number:	07224200.24 Task 1
Lab Number:	S091508-01/03

Enclosed are the results for sample(s) received 9/15/25 by Air Technology. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were received in Mylar bags. Benzyl chloride required quadratic regression calibration.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Jenny Kim, Art Jones and Ali Ferrara on 9/29/25.

ATL appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
MJohnson@AirTechLabs.com

Note: The cover letter is an integral part of this analytical report.

Air TECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐ No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐ No ☐
Other:				Level 4	☐	Chilled ______ deg C

Project No.: 07224200.24 Task 1
Project Name: Chiquita Canyon Landfill
Report To: Cornelius Fong
Company: SCS Engineers
Street: 3900 Kilroy Airport Way, Suite 100
City/State/Zip: Long Beach, CA 90806-6816
Phone& Fax: 562-743-7895
e-mail: cfong@scsengineers.com

BILLING
P.O. No.: 07-SO05310
Bill to:
07FSAccountspayable@scsengineers.com
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
S091508 -01	CV-2312	9/15/2025	8:00AM	2-1L	Gas	N	X	X	X	X		
-02	CV-24084	9/15/2025	8:15AM	1L	Gas	N	X					
-03	CV-24063	9/5/2025	8:30AM	1L	Gas	N	X	X	X			
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						

AUTHORIZATION TO PERFORM WORK	COMPANY	DATE/TIME		
SAMPLED BY Antonio Ambriz	COMPANY SCS	DATE/TIME		
RELINQUISHED BY [signature]	DATE/TIME 9/15/25 11:00 Am	RECEIVED BY [signature]	DATE/TIME 9/15/25 11:00 Am	
RELINQUISHED BY [signature]	DATE/TIME 9/15/25 12:20	RECEIVED BY [signature]	DATE/TIME 9/15/25 12:20	
RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME	

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other________

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: H=HCl N=None / Container: B=Bag C=Can V=VOA O=Other

Client:	**SCS Engineers**
Attn:	**Cornelius Fong**
Project Name:	**Chiquita Canyon Landfill**
Project No.:	**07224200.24 Task 1**
Date Received:	**09/15/25**
Matrix:	**Air**
Reporting Units:	**ppbv**

EPA Method TO-15

Lab No.:	S091508-01							
Client Sample I.D.:	CV-2312							
Date/Time Sampled:	9/15/25 8:00							
Date/Time Analyzed:	9/16/25 1:30							
QC Batch No.:	250915MS2A1							
Analyst Initials:	RC							
Dilution Factor:	2,000							
ANALYTE	**Result ppbv**	**RL ppbv**						
Dichlorodifluoromethane (12)	ND	2,000						
Chloromethane	ND	2,000						
1,2-Cl-1,1,2,2-F ethane (114)	ND	2,000						
Vinyl Chloride	ND	2,000						
Bromomethane	ND	2,000						
Chloroethane	ND	10,000						
Trichlorofluoromethane (11)	ND	2,000						
1,1-Dichloroethene	ND	2,000						
Carbon Disulfide	2,600	2,000						
1,1,2-Cl 1,2,2-F ethane (113)	ND	2,000						
Acetone	370,000	14,000						
Methylene Chloride	ND	2,000						
t-1,2-Dichloroethene	ND	2,000						
1,1-Dichloroethane	ND	2,000						
Vinyl Acetate	ND	2,000						
c-1,2-Dichloroethene	ND	2,000						
2-Butanone	170,000	10,000						
t-Butyl Methyl Ether (MTBE)	ND	2,000						
Chloroform	ND	2,000						
1,1,1-Trichloroethane	ND	2,000						
Carbon Tetrachloride	ND	2,000						
Benzene	71,000	2,000						
1,2-Dichloroethane	ND	2,000						
Trichloroethene	ND	2,000						
1,2-Dichloropropane	ND	2,000						
Bromodichloromethane	ND	2,000						
c-1,3-Dichloropropene	ND	2,000						
4-Methyl-2-Pentanone	2,600	2,000						
Toluene	2,400	2,000						
t-1,3-Dichloropropene	ND	4,000						
1,1,2-Trichloroethane	ND	2,000						
Tetrachloroethene	ND	2,000						
2-Hexanone	ND	2,000						
Dibromochloromethane	ND	2,000						

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/15/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	S091508-01							
Client Sample I.D.:	CV-2312							
Date/Time Sampled:	9/15/25 8:00							
Date/Time Analyzed:	9/16/25 1:30							
QC Batch No.:	250915MS2A1							
Analyst Initials:	RC							
Dilution Factor:	2,000							
ANALYTE	Result ppbv	RL ppbv						
1,2-Dibromoethane	ND	2,000						
Chlorobenzene	ND	2,000						
Ethylbenzene	ND	2,000						
p,&m-Xylene	ND	4,000						
o-Xylene	ND	2,000						
Styrene	ND	2,000						
Bromoform	ND	2,000						
1,1,2,2-Tetrachloroethane	ND	2,000						
Benzyl Chloride	ND	2,000						
4-Ethyl Toluene	ND	2,000						
1,3,5-Trimethylbenzene	ND	2,000						
1,2,4-Trimethylbenzene	ND	2,000						
1,3-Dichlorobenzene	ND	2,000						
1,4-Dichlorobenzene	ND	2,000						
1,2-Dichlorobenzene	ND	2,000						
1,2,4-Trichlorobenzene	ND	4,000						
Hexachlorobutadiene	ND	2,000						
1,3-Butadiene	ND	10,000						
Isopropanol	150,000	10,000						
n-Hexane	ND	10,000						
Ethyl Acetate	13,000	10,000						
Tetrahydrofuran	140,000	10,000						
Cyclohexane	ND	10,000						
Heptane	ND	10,000						
1,4-Dioxane	ND	10,000						

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: ______________________ Date 9/26/25
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client:	SCS Engineers
Attn:	Cornelius Fong
Project Name:	Chiquita Canyon Landfill
Project No.:	07224200.24 Task 1
Date Received:	09/15/25
Matrix:	Air
Reporting Units:	ppbv

EPA Method TO-15

Lab No.:	METHOD_BLANK							
Client Sample I.D.:	--							
Date/Time Sampled:	--							
Date/Time Analyzed:	9/15/25 13:04							
QC Batch No.:	250915MS2A1							
Analyst Initials:	RC							
Dilution Factor:	1.0							
ANALYTE	Result ppbv	RL ppbv						
Dichlorodifluoromethane (12)	ND	1.0						
Chloromethane	ND	1.0						
1,2-Cl-1,1,2,2-F ethane (114)	ND	1.0						
Vinyl Chloride	ND	1.0						
Bromomethane	ND	1.0						
Chloroethane	ND	5.0						
Trichlorofluoromethane (11)	ND	1.0						
1,1-Dichloroethene	ND	1.0						
Carbon Disulfide	ND	1.0						
1,1,2-Cl 1,2,2-F ethane (113)	ND	1.0						
Acetone	ND	7.0						
Methylene Chloride	ND	1.0						
t-1,2-Dichloroethene	ND	1.0						
1,1-Dichloroethane	ND	1.0						
Vinyl Acetate	ND	1.0						
c-1,2-Dichloroethene	ND	1.0						
2-Butanone	ND	5.0						
t-Butyl Methyl Ether (MTBE)	ND	1.0						
Chloroform	ND	1.0						
1,1,1-Trichloroethane	ND	1.0						
Carbon Tetrachloride	ND	1.0						
Benzene	ND	1.0						
1,2-Dichloroethane	ND	1.0						
Trichloroethene	ND	1.0						
1,2-Dichloropropane	ND	1.0						
Bromodichloromethane	ND	1.0						
c-1,3-Dichloropropene	ND	1.0						
4-Methyl-2-Pentanone	ND	1.0						
Toluene	ND	1.0						
t-1,3-Dichloropropene	ND	2.0						
1,1,2-Trichloroethane	ND	1.0						
Tetrachloroethene	ND	1.0						
2-Hexanone	ND	1.0						
Dibromochloromethane	ND	1.0						

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/15/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD_BLANK							
Client Sample I.D.:	--							
Date/Time Sampled:	--							
Date/Time Analyzed:	9/15/25 13:04							
QC Batch No.:	250915MS2A1							
Analyst Initials:	RC							
Dilution Factor:	1.0							
ANALYTE	Result ppbv	RL ppbv						
1,2-Dibromoethane	ND	1.0						
Chlorobenzene	ND	1.0						
Ethylbenzene	ND	1.0						
p,&m-Xylene	ND	2.0						
o-Xylene	ND	1.0						
Styrene	ND	1.0						
Bromoform	ND	1.0						
1,1,2,2-Tetrachloroethane	ND	1.0						
Benzyl Chloride	ND	1.0						
4-Ethyl Toluene	ND	1.0						
1,3,5-Trimethylbenzene	ND	1.0						
1,2,4-Trimethylbenzene	ND	1.0						
1,3-Dichlorobenzene	ND	1.0						
1,4-Dichlorobenzene	ND	1.0						
1,2-Dichlorobenzene	ND	1.0						
1,2,4-Trichlorobenzene	ND	2.0						
Hexachlorobutadiene	ND	1.0						
1,3-Butadiene	ND	5.0						
Isopropanol	ND	5.0						
n-Hexane	ND	5.0						
Ethyl Acetate	ND	5.0						
Tetrahydrofuran	ND	5.0						
Cyclohexane	ND	5.0						
Heptane	ND	5.0						
1,4-Dioxane	ND	5.0						

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: ____________ Date 9/26/25
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 250915MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	9/15/25 13:04			9/15/25 10:52		9/15/25 11:48					
Analyst Initials:	RC			RC		RC					
Dilution Factor:	1.0			1.0		1.0					
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	1.0	10	11.1	111	11.0	110	0.7	70	130	30
Methylene Chloride	ND	1.0	10	11.1	111	11.1	111	0.6	70	130	30
Trichloroethene	ND	1.0	10	10.8	108	10.5	105	2.8	70	130	30
Toluene	ND	1.0	10	10.5	105	10.4	104	1.0	70	130	30
1,1,2,2-Tetrachloroethane	ND	1.0	10	11.6	116	11.4	114	2.4	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: [signature]
Mark Johnson
Operations Manager

Date: 9/26/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/15/25
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	S091508-01		S091508-03					
Client Sample I.D.:	CV-2312		CV-24063					
Date/Time Sampled:	9/15/25 8:00		9/15/25 8:30					
Date/Time Analyzed:	9/15/25 15:59		9/15/25 16:28					
QC Batch No.:	250915GC8A2		250915GC8A2					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv				
Carbon Monoxide	2,100	10	1,900	10				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: [signature]
Mark Johnson
Operations Manager

Date 9/26/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

QC Batch No: 250915GC8A2
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	9/15/25 15:15			9/15/25 13:53		9/15/25 14:08					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,170	116	1,140	113	2.5	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: ________________ Date 9/26/25
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/15/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S091508-01			S091508-03								
Client Sample I.D.:	CV-2312			CV-24063								
Date/Time Sampled:	9/15/25 8:00			9/15/25 8:30								
Date/Time Analyzed:	9/15/25 15:59			9/15/25 16:28								
QC Batch No.:	250915GC8A2			250915GC8A2								
Analyst Initials:	KD			KD								
Dilution Factor:	1.0			1.0								
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v						
Hydrogen	13	1.0	0.059	11	1.0	0.059						

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: [signature]
Mark Johnson
Operations Manager

Date 9/26/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

QC Batch No: 250915GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	9/15/25 15:15				9/15/25 13:53		9/15/25 14:08					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	4.44	89	4.38	88	1.3	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: [signature]
Mark Johnson
Operations Manager

Date 9/26/25

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/15/25
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	S091508-01		S091508-02		S091508-03			
Client Sample I.D.:	CV-2312		CV-24084		CV-24063			
Date/Time Sampled:	9/15/25 8:00		9/15/25 8:15		9/15/25 8:30			
Date/Time Analyzed:	9/15/25 15:59		9/15/25 16:13		9/15/25 16:28			
QC Batch No.:	250915GC8A2		250915GC8A2		250915GC8A2			
Analyst Initials:	KD		KD		KD			
Dilution Factor:	1.0		1.0		1.0			
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v		
Carbon Dioxide	76	0.010	79	0.010	69	0.010		
Oxygen/Argon	0.85	0.50	0.93	0.50	1.1	0.50		
Nitrogen	3.0	1.0	3.0	1.0	3.9	1.0		
Methane	7.0	0.0010	2.7	0.0010	15	0.0010		

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: Mark Johnson
Mark Johnson
Operations Manager

Date 9/26/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

QC Batch No: 250915GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	9/15/25 15:15			9/15/25 13:53		9/15/25 14:08					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	9.20	92	9.20	92	0.0	70	130	30
Oxygen/Argon	ND	0.50	15	14.6	97	14.6	97	0.0	70	130	30
Nitrogen	ND	1.0	70	70.3	101	70.3	101	0.1	70	130	30
Methane	ND	0.0010	0.10	0.106	105	0.103	102	2.3	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: MJohnson
Mark Johnson
Operations Manager

Date 9/26/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.

September 29, 2025

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175

TX Cert T104704450-14-6
EPA Methods TO14A, TO15

ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference:	Chiquita Canyon Landfill
Project Number:	07224200.24 Task 1
Lab Number:	S092505-01/08

Enclosed are the results for sample(s) received 9/25/25 by Air Technology. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags. Benzyl chloride required quadratic regression calibration.
- Samples S092505-07 (CV-108-52) and S092505-08 (CV-1902A) were analyzed 17 minutes and 40 minutes respectively outside the 24-hr holding-time. The samples were initially analyzed within holding-time but a data acquisition error caused a loss of the data files.
- performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Jenny Kim, Art Jones and Ali Ferrara on 9/26/25.

ATL appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Amika Sotelo Sanchez for

Mark Johnson
Operations Manager
MJohnson@AirTechLabs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF	
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:	
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐	No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐	No ☐
Other:				Level 4	☐	Chilled ______ deg C	

Project No.: 07224200.24 Task 1
Project Name: Chiquita Canyon Landfill
Report To: Cornelius Fong
Company: SCS Engineers
Street: 3900 Kilroy Airport Way, Suite 100
City/State/Zip: Long Beach, CA 90806-6816
Phone& Fax: 562-743-7895
e-mail: cfong@scsengineers.com

BILLING
P.O. No.: 07-SO05310
Bill to:
07FSAccountspayable@scsengineers.com
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
S092505-01	CV-2302	9/25/2025	9:10AM	1L	Gas	N				X		
-02	CV-2301	9/25/2025	9:05AM	1L	Gas	N				X		
-03	H-2273W	9/25/2025	8:45AM	1L	Gas	N				X		
-04	H-1770N	9/25/2025	8:30AM	1L	Gas	N				X		
-05	CV-1532A	9/25/2025	8:50AM	1L	Gas	N				X		
-06	CV-1535	9/25/2025	8:40AM	1L	Gas	N				X		
-07	CV-108-52	9/25/2025	8:20AM	1L	Gas	N				X		
-08	CV-1902A	9/25/2025	8:35AM	1L	Gas	N				X		

AUTHORIZATION TO PERFORM WORK		COMPANY		DATE/TIME
SAMPLED BY: Jaime		COMPANY: SCS		DATE/TIME: 9-25-2025
RELINQUISHED BY: [signature]	DATE/TIME: 9-25-25 10:46	RECEIVED BY: Ruben 6		DATE/TIME: 9/25/25 10:50
RELINQUISHED BY: Ruben 6	DATE/TIME: 9/25/25 12:30	RECEIVED BY: [signature]		DATE/TIME: 9/25/25 12:30
RELINQUISHED BY	DATE/TIME	RECEIVED BY		DATE/TIME

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other________

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: H=HCl N=None / Container: B=Bag C=Can V=VOA O=Other

Client: SCS Engineers
Attn: Corn Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24
Date Received: 09/25/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	S092505-01		S092505-02		S092505-03		S092505-04	
Client Sample I.D.:	CV-2302		CV-2301		H-2273W		H-1770N	
Date/Time Sampled:	9/25/25 9:10		9/25/25 9:05		9/25/25 8:45		9/25/25 8:30	
Date/Time Analyzed:	9/25/25 16:39		9/25/25 17:58		9/25/25 18:41		9/25/25 19:20	
QC Batch No.:	250925MS2A1		250925MS2A1		250925MS2A1		250925MS2A1	
Analyst Initials:	RC		RC		RC		RC	
Dilution Factor:	10		10		250		10	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	10	ND	10	ND	250	ND	10
Chloromethane	ND	10	ND	10	ND	250	ND	10
1,2-Cl-1,1,2,2-F ethane (114)	ND	10	ND	10	ND	250	ND	10
Vinyl Chloride	ND	10	ND	10	ND	250	ND	10
Bromomethane	ND	10	ND	10	ND	250	ND	10
Chloroethane	ND	10	ND	10	ND	250	ND	10
Trichlorofluoromethane (11)	ND	10	ND	10	ND	250	ND	10
1,1-Dichloroethene	ND	10	ND	10	ND	250	ND	10
Carbon Disulfide	ND	10	ND	10	310	250	ND	10
1,1,2-Cl 1,2,2-F ethane (113)	ND	10	ND	10	ND	250	ND	10
Acetone	91	10	32	10	39,000	250	58	10
Methylene Chloride	ND	10	ND	10	ND	250	ND	10
t-1,2-Dichloroethene	ND	10	ND	10	ND	250	ND	10
1,1-Dichloroethane	ND	10	ND	10	ND	250	ND	10
Vinyl Acetate	ND	10	ND	10	ND	250	ND	10
c-1,2-Dichloroethene	ND	10	ND	10	ND	250	ND	10
2-Butanone	48	20	ND	20	15,000	500	33	20
t-Butyl Methyl Ether (MTBE)	ND	10	ND	10	ND	250	ND	10
Chloroform	ND	10	ND	10	ND	250	ND	10
1,1,1-Trichloroethane	ND	10	ND	10	ND	250	ND	10
Carbon Tetrachloride	ND	10	ND	10	ND	250	ND	10
Benzene	26	10	ND	10	3,600	250	17	10
1,2-Dichloroethane	ND	10	ND	10	ND	250	ND	10
Trichloroethene	ND	10	ND	10	ND	250	ND	10
1,2-Dichloropropane	ND	10	ND	10	ND	250	ND	10
Bromodichloromethane	ND	10	ND	10	ND	250	ND	10
c-1,3-Dichloropropene	ND	10	ND	10	ND	250	ND	10
4-Methyl-2-Pentanone	ND	10	ND	10	460	250	ND	10
Toluene	ND	10	ND	10	ND	250	ND	10
t-1,3-Dichloropropene	ND	10	ND	10	ND	250	ND	10
1,1,2-Trichloroethane	ND	10	ND	10	ND	250	ND	10
Tetrachloroethene	ND	10	ND	10	ND	250	ND	10
2-Hexanone	ND	10	ND	10	ND	250	ND	10
Dibromochloromethane	ND	10	ND	10	ND	250	ND	10

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Corn Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24
Date Received: 09/25/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	S092505-01		S092505-02		S092505-03		S092505-04	
Client Sample I.D.:	CV-2302		CV-2301		H-2273W		H-1770N	
Date/Time Sampled:	9/25/25 9:10		9/25/25 9:05		9/25/25 8:45		9/25/25 8:30	
Date/Time Analyzed:	9/25/25 16:39		9/25/25 17:58		9/25/25 18:41		9/25/25 19:20	
QC Batch No.:	250925MS2A1		250925MS2A1		250925MS2A1		250925MS2A1	
Analyst Initials:	RC		RC		RC		RC	
Dilution Factor:	10		10		250		10	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	10	ND	10	ND	250	ND	10
Chlorobenzene	ND	10	11	10	ND	250	ND	10
Ethylbenzene	ND	10	ND	10	ND	250	ND	10
p,&m-Xylene	ND	10	ND	10	ND	250	ND	10
o-Xylene	ND	10	ND	10	ND	250	ND	10
Styrene	ND	10	ND	10	ND	250	ND	10
Bromoform	ND	10	ND	10	ND	250	ND	10
1,1,2,2-Tetrachloroethane	ND	10	ND	10	ND	250	ND	10
Benzyl Chloride	ND	10	ND	10	ND	250	ND	10
4-Ethyl Toluene	ND	10	ND	10	ND	250	ND	10
1,3,5-Trimethylbenzene	ND	10	ND	10	ND	250	ND	10
1,2,4-Trimethylbenzene	ND	10	ND	10	ND	250	ND	10
1,3-Dichlorobenzene	ND	10	ND	10	ND	250	ND	10
1,4-Dichlorobenzene	ND	10	ND	10	ND	250	ND	10
1,2-Dichlorobenzene	ND	10	ND	10	ND	250	ND	10
1,2,4-Trichlorobenzene	ND	10	ND	10	ND	250	ND	10
Hexachlorobutadiene	ND	10	ND	10	ND	250	ND	10
1,3-Butadiene	ND	50	ND	50	2,000	1,300	ND	50
Isopropanol	ND	50	ND	50	35,000	1,300	ND	50
n-Hexane	ND	50	95	50	ND	1,300	ND	50
Ethyl Acetate	ND	50	ND	50	2,900	1,300	ND	50
Tetrahydrofuran	ND	50	ND	50	6,500	1,300	ND	50
Cyclohexane	ND	50	ND	50	ND	1,300	ND	50
Heptane	ND	50	ND	50	ND	1,300	ND	50
1,4-Dioxane	ND	50	ND	50	ND	1,300	ND	50

RL = Reporting Limit
ND = Not Detected (below RL)
* = Samples analyzed outside hold-time

Reviewed/Approved By: [signature]
Mark Johnson
Operations Manager

Date 9/26/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Corn Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24
Date Received: 09/25/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	S092505-05		S092505-06		S092505-07		S092505-08	
Client Sample I.D.:	CV-1532A		CV-1535		CV-108-52		CV-1902A	
Date/Time Sampled:	9/25/25 8:50		9/25/25 8:40		9/25/25 8:20		9/25/25 8:35	
Date/Time Analyzed:	9/25/25 19:58		9/25/25 20:37		9/26/25 8:37*		9/26/25 9:15*	
QC Batch No.:	250925MS2A1		250925MS2A1		250925MS2A1		250925MS2A1	
Analyst Initials:	RC		RC		RC		RC	
Dilution Factor:	10		50		100		10	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	10	ND	50	ND	100	ND	10
Chloromethane	ND	10	ND	50	ND	100	ND	10
1,2-Cl-1,1,2,2-F ethane (114)	ND	10	ND	50	ND	100	ND	10
Vinyl Chloride	ND	10	ND	50	ND	100	ND	10
Bromomethane	ND	10	ND	50	ND	100	ND	10
Chloroethane	ND	10	ND	50	ND	100	ND	10
Trichlorofluoromethane (11)	ND	10	ND	50	ND	100	ND	10
1,1-Dichloroethene	ND	10	ND	50	ND	100	ND	10
Carbon Disulfide	ND	10	ND	50	160	100	ND	10
1,1,2-Cl 1,2,2-F ethane (113)	ND	10	ND	50	ND	100	ND	10
Acetone	87	10	6,000	50	17,000	100	39	10
Methylene Chloride	ND	10	ND	50	ND	100	ND	10
t-1,2-Dichloroethene	ND	10	ND	50	ND	100	ND	10
1,1-Dichloroethane	ND	10	ND	50	ND	100	ND	10
Vinyl Acetate	ND	10	ND	50	ND	100	ND	10
c-1,2-Dichloroethene	ND	10	ND	50	ND	100	ND	10
2-Butanone	61	20	3,000	100	6,700	200	ND	20
t-Butyl Methyl Ether (MTBE)	ND	10	ND	50	ND	100	ND	10
Chloroform	ND	10	ND	50	ND	100	ND	10
1,1,1-Trichloroethane	ND	10	ND	50	ND	100	ND	10
Carbon Tetrachloride	ND	10	ND	50	ND	100	ND	10
Benzene	23	10	850	50	3,200	100	ND	10
1,2-Dichloroethane	ND	10	ND	50	ND	100	ND	10
Trichloroethene	ND	10	ND	50	ND	100	ND	10
1,2-Dichloropropane	ND	10	ND	50	ND	100	ND	10
Bromodichloromethane	ND	10	ND	50	ND	100	ND	10
c-1,3-Dichloropropene	ND	10	ND	50	ND	100	ND	10
4-Methyl-2-Pentanone	ND	10	ND	50	280	100	ND	10
Toluene	ND	10	63	50	160	100	150	10
t-1,3-Dichloropropene	ND	10	ND	50	ND	100	ND	10
1,1,2-Trichloroethane	ND	10	ND	50	ND	100	ND	10
Tetrachloroethene	ND	10	ND	50	ND	100	ND	10
2-Hexanone	ND	10	ND	50	ND	100	ND	10
Dibromochloromethane	ND	10	ND	50	ND	100	ND	10

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Corn Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24
Date Received: 09/25/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	S092505-05		S092505-06		S092505-07		S092505-08	
Client Sample I.D.:	CV-1532A		CV-1535		CV-108-52		CV-1902A	
Date/Time Sampled:	9/25/25 8:50		9/25/25 8:40		9/25/25 8:20		9/25/25 8:35	
Date/Time Analyzed:	9/25/25 19:58		9/25/25 20:37		9/26/25 8:37*		9/26/25 9:15*	
QC Batch No.:	250925MS2A1		250925MS2A1		250925MS2A1		250925MS2A1	
Analyst Initials:	RC		RC		RC		RC	
Dilution Factor:	10		50		100		10	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	10	ND	50	ND	100	ND	10
Chlorobenzene	ND	10	ND	50	ND	100	ND	10
Ethylbenzene	ND	10	ND	50	ND	100	ND	10
p,&m-Xylene	ND	10	ND	50	ND	100	ND	10
o-Xylene	ND	10	ND	50	ND	100	ND	10
Styrene	ND	10	ND	50	ND	100	ND	10
Bromoform	ND	10	ND	50	ND	100	ND	10
1,1,2,2-Tetrachloroethane	ND	10	ND	50	ND	100	ND	10
Benzyl Chloride	ND	10	ND	50	ND	100	ND	10
4-Ethyl Toluene	ND	10	ND	50	ND	100	ND	10
1,3,5-Trimethylbenzene	ND	10	ND	50	ND	100	ND	10
1,2,4-Trimethylbenzene	ND	10	ND	50	ND	100	ND	10
1,3-Dichlorobenzene	ND	10	ND	50	ND	100	ND	10
1,4-Dichlorobenzene	ND	10	ND	50	ND	100	ND	10
1,2-Dichlorobenzene	ND	10	ND	50	ND	100	ND	10
1,2,4-Trichlorobenzene	ND	10	ND	50	ND	100	ND	10
Hexachlorobutadiene	ND	10	ND	50	ND	100	ND	10
1,3-Butadiene	ND	50	ND	250	1,200	500	ND	50
Isopropanol	68	50	3,500	250	10,000	500	ND	50
n-Hexane	100	50	ND	250	ND	500	ND	50
Ethyl Acetate	ND	50	ND	250	770	500	ND	50
Tetrahydrofuran	ND	50	2,200	250	4,100	500	ND	50
Cyclohexane	ND	50	ND	250	ND	500	ND	50
Heptane	ND	50	ND	250	ND	500	ND	50
1,4-Dioxane	ND	50	ND	250	ND	500	ND	50

RL = Reporting Limit
ND = Not Detected (below RL)
* = Samples analyzed outside hold-time

Reviewed/Approved By: ____________ Date 9/26/25
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client: SCS Engineers
Attn: Corn Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24
Date Received: 09/25/25
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	Method_Blank							
Client Sample I.D.:	-							
Date/Time Sampled:	-							
Date/Time Analyzed:	9/25/25 14:37							
QC Batch No.:	250925MS2A1							
Analyst Initials:	RC							
Dilution Factor:	0.20							
ANALYTE	Result ppbv	RL ppbv						
Dichlorodifluoromethane (12)	ND	0.20						
Chloromethane	ND	0.20						
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20						
Vinyl Chloride	ND	0.20						
Bromomethane	ND	0.20						
Chloroethane	ND	0.20						
Trichlorofluoromethane (11)	ND	0.20						
1,1-Dichloroethene	ND	0.20						
Carbon Disulfide	ND	0.20						
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20						
Acetone	ND	0.20						
Methylene Chloride	ND	0.20						
t-1,2-Dichloroethene	ND	0.20						
1,1-Dichloroethane	ND	0.20						
Vinyl Acetate	ND	0.20						
c-1,2-Dichloroethene	ND	0.20						
2-Butanone	ND	0.40						
t-Butyl Methyl Ether (MTBE)	ND	0.20						
Chloroform	ND	0.20						
1,1,1-Trichloroethane	ND	0.20						
Carbon Tetrachloride	ND	0.20						
Benzene	ND	0.20						
1,2-Dichloroethane	ND	0.20						
Trichloroethene	ND	0.20						
1,2-Dichloropropane	ND	0.20						
Bromodichloromethane	ND	0.20						
c-1,3-Dichloropropene	ND	0.20						
4-Methyl-2-Pentanone	ND	0.20						
Toluene	ND	0.20						
t-1,3-Dichloropropene	ND	0.20						
1,1,2-Trichloroethane	ND	0.20						
Tetrachloroethene	ND	0.20						
2-Hexanone	ND	0.20						
Dibromochloromethane	ND	0.20						

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

Client:	SCS Engineers
Attn:	Corn Fong
Project Name:	Chiquita Canyon Landfill
Project No.:	07224200.24
Date Received:	09/25/25
Matrix:	Air
Reporting Units:	ppbv

EPA Method TO-15

Lab No.:	Method_Blank						
Client Sample I.D.:	-						
Date/Time Sampled:	-						
Date/Time Analyzed:	9/25/25 14:37						
QC Batch No.:	250925MS2A1						
Analyst Initials:	RC						
Dilution Factor:	0.20						
ANALYTE	**Result ppbv**	**RL ppbv**					
1,2-Dibromoethane	ND	0.20					
Chlorobenzene	ND	0.20					
Ethylbenzene	ND	0.20					
p,&m-Xylene	ND	0.20					
o-Xylene	ND	0.20					
Styrene	ND	0.20					
Bromoform	ND	0.20					
1,1,2,2-Tetrachloroethane	ND	0.20					
Benzyl Chloride	ND	0.20					
4-Ethyl Toluene	ND	0.20					
1,3,5-Trimethylbenzene	ND	0.20					
1,2,4-Trimethylbenzene	ND	0.20					
1,3-Dichlorobenzene	ND	0.20					
1,4-Dichlorobenzene	ND	0.20					
1,2-Dichlorobenzene	ND	0.20					
1,2,4-Trichlorobenzene	ND	0.20					
Hexachlorobutadiene	ND	0.20					
1,3-Butadiene	ND	1.0					
Isopropanol	ND	1.0					
n-Hexane	ND	1.0					
Ethyl Acetate	ND	1.0					
Tetrahydrofuran	ND	1.0					
Cyclohexane	ND	1.0					
Heptane	ND	1.0					
1,4-Dioxane	ND	1.0					

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: ____________ Mark Johnson
Operations Manager

Date 9/26/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 250925MS2A1
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	9/25/25 14:37			9/25/25 12:42		9/25/25 13:20					
Analyst Initials:	RC			RC		RC					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	0.20	10	11.6	116	11.9	119	2.2	70	130	30
Methylene Chloride	ND	0.20	10	11.2	112	11.7	117	4.3	70	130	30
Trichloroethene	ND	0.20	10	10.8	108	10.8	108	0.7	70	130	30
Toluene	ND	0.20	10	10.7	107	10.9	109	2.2	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	12.6	126	12.8	128	1.7	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: [signature]
Mark Johnson
Operations Manager

Date: 9/26/25

The cover letter is an integral part of this analytical report

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Avenue, Suite 130 ♦ City of Industry, CA 91748 ♦ Ph: (626) 964-4032 ♦ Fx: (626) 964-5832

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
A-01	9/11/2025 10:42:03 AM	56.7	41.7	0.0	1.6	0.0	1.4		
A-01	9/15/2025 12:58:22 PM	59.1	38.4	0.0	2.5	0.0	1.5		
A-02	9/11/2025 10:49:23 AM	57.2	40.1	0.0	2.7	0.0	1.4		
A-03	9/11/2025 10:53:20 AM	56.4	40.5	0.0	3.1	0.0	1.4		
A-04	9/11/2025 10:55:43 AM	54.9	42.0	0.0	3.1	0.0	1.3		
A-05	9/15/2025 1:11:50 PM	51.7	37.3	1.7	9.3	5.5	1.4		
B-01	9/2/2025 1:15:34 PM	22.8	24.8	0.0	52.4	0.0	0.9		
B-02R	9/2/2025 1:20:45 PM	41.6	30.7	1.1	26.6	24.2	1.4		
B-03R	9/2/2025 1:33:42 PM	30.7	29.9	0.0	39.4	0.0	1.0		
B-05	9/2/2025 2:00:24 PM	25.3	29.9	0.0	44.8	0.0	0.8		
B-06	9/2/2025 2:11:06 PM	31.5	27.5	0.0	41.0	0.0	1.1		
B-06	9/2/2025 2:11:59 PM	31.7	26.3	0.0	42.0	0.0	1.2		
B-07R	9/8/2025 1:40:51 PM	39.8	32.5	0.0	27.7	0.0	1.2		
B-08	9/2/2025 2:26:34 PM	8.5	26.2	0.0	65.3	0.0	0.3		
B-09	9/8/2025 1:35:36 PM	29.7	28.8	0.2	41.3	206.5	1.0		
B-10	9/2/2025 2:32:34 PM	11.9	24.5	0.0	63.6	0.0	0.5		
B-11	9/8/2025 1:56:06 PM	29.0	31.7	0.1	39.2	392.0	0.9		
B-12	9/2/2025 1:41:34 PM	25.4	31.3	0.0	43.3	0.0	0.8		
B-13	9/8/2025 1:45:02 PM	35.3	31.4	0.0	33.3	0.0	1.1		
B-14	9/8/2025 2:00:18 PM	12.5	26.1	0.0	61.4	0.0	0.5		
C-03	9/11/2025 10:44:49 AM	55.3	40.9	0.0	3.8	0.0	1.4		
C-07	9/26/2025 1:08:23 PM	57.3	39.5	0.0	3.2	0.0	1.5		
C-08	9/25/2025 2:18:07 PM	54.0	40.6	0.4	5.0	12.5	1.3		
C-10	9/15/2025 1:20:04 PM	56.0	40.6	0.0	3.4	0.0	1.4		
C-11	9/15/2025 1:34:37 PM	56.0	40.7	0.0	3.3	0.0	1.4		
C-12	9/10/2025 10:18:50 AM	56.2	40.6	0.1	3.1	31.0	1.4		
C-12	9/15/2025 1:42:47 PM	53.9	42.4	0.0	3.7	0.0	1.3		
C-15	9/10/2025 10:26:52 AM	55.6	40.7	0.0	3.7	0.0	1.4		
C-15	9/15/2025 1:46:38 PM	54.7	41.1	0.0	4.2	0.0	1.3		
C-17B	9/22/2025 11:09:30 AM	56.3	39.0	0.1	4.6	46.0	1.4		
C-18	9/25/2025 2:18:43 PM	54.1	38.7	0.6	6.6	11.0	1.4		
C-19	9/22/2025 11:23:57 AM	54.4	41.1	0.0	4.5	0.0	1.3		
C-20	9/25/2025 2:27:31 PM	54.7	40.5	0.0	4.8	0.0	1.4		
C-23	9/25/2025 2:22:36 PM	54.6	40.0	0.0	5.4	0.0	1.4		
C-24	9/22/2025 11:21:21 AM	39.1	37.0	0.0	23.9	0.0	1.1		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
C-25	9/15/2025 2:05:56 PM	49.8	42.0	0.1	8.1	81.0	1.2		
C-26	9/15/2025 1:59:34 PM	47.4	36.5	3.3	12.8	3.9	1.3		
C-27	9/10/2025 10:22:35 AM	55.5	40.7	0.0	3.8	0.0	1.4		
C-28	9/15/2025 1:37:08 PM	54.1	42.9	0.0	3.0	0.0	1.3		
C-29	9/15/2025 1:27:37 PM	51.6	43.6	0.0	4.8	0.0	1.2		
C-30	9/25/2025 2:14:01 PM	52.0	43.2	0.0	4.8	0.0	1.2		
CV-02	9/11/2025 10:16:16 AM	30.5	34.4	0.0	35.1	0.0	0.9		
CV-02	9/11/2025 10:17:03 AM	30.5	34.2	0.0	35.3	0.0	0.9		
CV-03	9/11/2025 10:13:17 AM	52.6	42.5	0.0	4.9	0.0	1.2		
CV-04	9/11/2025 10:09:39 AM	49.8	37.7	0.0	12.5	0.0	1.3		
CV-05	9/11/2025 10:06:21 AM	57.9	39.3	0.0	2.8	0.0	1.5		
CV-06	9/11/2025 11:02:54 AM	53.0	42.7	0.5	3.8	7.6	1.2		
CV-09	9/11/2025 11:17:07 AM	54.1	44.6	0.0	1.3	0.0	1.2		
CV-108-52	9/2/2025 10:35:26 AM	42.5	54.7	0.0	2.8	0.0	0.8		
CV-108-52	9/10/2025 10:00:00 AM							380	
CV-108-52	9/10/2025 10:00:00 AM								21000
CV-108-52	9/17/2025 8:58:55 AM	42.9	56.3	0.0	0.8	0.0	0.8		
CV-113	9/2/2025 9:40:00 AM							0	
CV-113	9/2/2025 9:40:00 AM								0
CV-113	9/3/2025 9:08:14 AM	0.9	85.6	0.5	13.0	26.0	0.0		
CV-113	9/3/2025 9:13:00 AM							1520	
CV-113	9/3/2025 9:13:00 AM								66500
CV-113	9/9/2025 8:53:00 AM							2870	
CV-113	9/9/2025 8:54:45 AM	0.6	77.1	0.1	22.2	222.0	0.0		
CV-113	9/15/2025 8:58:37 AM	1.5	86.5	0.0	12.0	0.0	0.0		
CV-113	9/15/2025 9:03:00 AM							1710	
CV-113	9/22/2025 8:29:56 AM	1.4	84.3	1.3	13.0	10.0	0.0		
CV-113	9/29/2025 11:25:43 AM	0.9	70.2	3.5	25.4	7.3	0.0		
CV-114	9/11/2025 8:55:00 AM							2100	
CV-114	9/11/2025 8:55:00 AM								130000
CV-1424	9/3/2025 10:36:01 AM	19.7	68.4	0.0	11.9	0.0	0.3		
CV-1532A	9/4/2025 9:18:52 AM	1.8	75.0	0.9	22.3	24.8	0.0		
CV-1532A	9/4/2025 9:20:00 AM							2050	
CV-1532A	9/4/2025 9:20:00 AM								93600

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-1532A	9/10/2025 10:10:00 AM							730	
CV-1532A	9/10/2025 10:10:00 AM								21000
CV-1532A	9/10/2025 11:02:22 AM		69.1	2.5					
CV-1532A	9/10/2025 11:04:00 AM							2590	
CV-1532A	9/12/2025 2:19:15 PM	3.7	74.6	2.1	19.6	9.3	0.0		
CV-1532A	9/18/2025 10:36:35 AM	9.5	81.8	0.5	8.2	16.4	0.1		
CV-1532A	9/24/2025 9:41:10 AM	1.6	75.5	2.0	20.9	10.5	0.0		
CV-1534A-PLR	9/5/2025 7:38:51 AM	1.3	78.3	1.3	19.1	14.7	0.0		
CV-1534A-PLR	9/5/2025 7:40:00 AM							2640	
CV-1534A-PLR	9/5/2025 7:40:00 AM								141000
CV-1534A-PLR	9/10/2025 11:21:04 AM	45.3	43.6	7.4	3.7	0.5	1.0		
CV-1534A-PLR	9/10/2025 11:22:00 AM							194	
CV-1534A-PLR	9/18/2025 9:25:06 AM	5.7	67.0	3.4	23.9	7.0	0.1		
CV-1534A-PLR	9/24/2025 9:23:39 AM	0.3	31.0	12.1	56.6	4.7	0.0		
CV-1535	9/2/2025 10:32:14 AM	44.9	52.3	0.0	2.8	0.0	0.9		
CV-1535	9/9/2025 9:00:00 AM							180	
CV-1535	9/9/2025 9:00:00 AM								25000
CV-1535	9/17/2025 8:55:16 AM	44.5	53.3	0.0	2.2	0.0	0.8		
CV-1601D	9/4/2025 9:21:21 AM	45.9	49.7	0.0	4.4	0.0	0.9		
CV-1601D	9/17/2025 10:18:46 AM	45.5	50.4	0.0	4.1	0.0	0.9		
CV-1601S	9/4/2025 9:15:43 AM	38.5	55.2	0.0	6.3	0.0	0.7		
CV-1601S	9/17/2025 10:16:46 AM	36.6	53.6	0.0	9.8	0.0	0.7		
CV-1604	9/10/2025 11:04:29 AM	52.4	45.6	0.0	2.0	0.0	1.1		
CV-1605	9/5/2025 1:57:42 PM	48.1	41.7	1.3	8.9	6.8	1.2		
CV-1701D	9/4/2025 2:27:54 PM	31.4	53.8	0.0	14.8	0.0	0.6		
CV-1701S	9/4/2025 2:25:05 PM	37.1	55.3	0.0	7.6	0.0	0.7		
CV-1901	9/9/2025 9:32:11 AM								
CV-1901	9/10/2025 9:59:41 AM	27.5	68.5	0.0	4.0	0.0	0.4		
CV-1901	9/17/2025 8:51:25 AM	25.1	69.0	0.0	5.9	0.0	0.4		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-1902A	9/4/2025 8:41:25 AM	1.9	78.6	0.0	19.5	0.0	0.0		
CV-1902A	9/4/2025 8:45:00 AM							1340	
CV-1902A	9/4/2025 8:45:00 AM								148300
CV-1902A	9/9/2025 8:45:00 AM							1000	
CV-1902A	9/9/2025 8:45:00 AM								200000
CV-1902A	9/10/2025 10:11:35 AM	24.2	75.4	0.4	0.0	0.0	0.3		
CV-1902A	9/10/2025 10:13:00 AM							1860	
CV-1902A	9/18/2025 8:46:48 AM	10.3	82.9	0.0	6.8	0.0	0.1		
CV-1902A	9/24/2025 11:10:16 AM	2.3	75.2	0.8	21.7	27.1	0.0		
CV-1903	9/5/2025 9:04:43 AM	11.2	26.2	1.4	61.2	43.7	0.4		
CV-1903	9/9/2025 9:37:05 AM								
CV-1903	9/16/2025 9:01:06 AM	2.0	13.2	4.0	80.8	20.2	0.2		
CV-1903	9/18/2025 1:34:31 PM	19.1	37.2	0.6	43.1	71.8	0.5		
CV-1905	9/9/2025 10:52:49 AM	52.7	47.3	0.0	0.0	0.0	1.1		
CV-2001	9/2/2025 2:14:25 PM	9.2	72.7	1.0	17.1	17.1	0.1		
CV-2001	9/8/2025 9:00:00 AM							880	
CV-2001	9/8/2025 9:00:00 AM								23000
CV-2001	9/8/2025 9:26:03 AM	7.8	70.4	4.8	17.0	3.5	0.1		
CV-2001	9/8/2025 9:33:34 AM	8.5	75.1	3.8	12.7	3.4	0.1		
CV-2001	9/17/2025 10:35:12 AM	9.9	85.4	1.1	3.6	3.3	0.1		
CV-2002	9/2/2025 2:29:12 PM	35.1	63.1	0.0	1.8	0.0	0.6		
CV-2002	9/4/2025 9:55:00 AM							330	
CV-2002	9/4/2025 9:55:00 AM								4300
CV-2002	9/17/2025 10:59:06 AM	29.9	70.1	0.0	0.0	0.0	0.4		
CV-2002	9/17/2025 11:00:32 AM	31.1	67.4	0.0	1.5	0.0	0.5		
CV-2003	9/2/2025 10:42:09 AM	22.2	70.1	0.0	7.7	0.0	0.3		
CV-2003	9/17/2025 9:01:22 AM	23.6	71.2	0.0	5.2	0.0	0.3		
CV-2006	9/4/2025 8:25:11 AM	1.1	74.0	0.2	24.7	123.5	0.0		
CV-2006	9/4/2025 8:28:00 AM							2490	
CV-2006	9/4/2025 8:28:00 AM								121700
CV-2006	9/10/2025 10:29:29 AM	22.0	77.9	0.1	0.0	0.0	0.3		
CV-2006	9/10/2025 10:32:00 AM							3500	
CV-2006	9/18/2025 8:04:41 AM	2.0	84.0	0.0	14.0	0.0	0.0		
CV-2006	9/24/2025 10:41:53 AM	1.2	76.2	1.3	21.3	16.4	0.0		
CV-2007	9/2/2025 1:44:21 PM	29.9	65.7	0.0	4.4	0.0	0.5		
CV-2007	9/3/2025 9:40:00 AM							33	
CV-2007	9/3/2025 9:40:00 AM								4600
CV-2008	9/2/2025 1:51:51 PM	20.1	75.3	0.0	4.6	0.0	0.3		
CV-2008	9/10/2025 10:51:30 AM	26.8	73.2	0.0	0.0	0.0	0.4		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-2008	9/10/2025 10:53:39 AM	23.2	76.8	0.0	0.0	0.0	0.3		
CV-2009	9/2/2025 2:09:17 PM	45.3	51.4	0.0	3.3	0.0	0.9		
CV-2009	9/2/2025 2:10:23 PM	44.0	53.9	0.0	2.1	0.0	0.8		
CV-2009A	9/3/2025 9:44:32 AM	47.3	47.8	0.0	4.9	0.0	1.0		
CV-2009A	9/9/2025 11:06:16 AM								
CV-2010	9/9/2025 1:47:09 PM	33.0	58.8	0.0	8.2	0.0	0.6		
CV-2010A	9/9/2025 1:43:50 PM	44.9	44.5	0.0	10.6	0.0	1.0		
CV-2010A	9/12/2025 1:41:53 PM	48.0	45.3	0.0	6.7	0.0	1.1		
CV-2010A	9/12/2025 1:43:56 PM	47.4	44.8	0.0	7.8	0.0	1.1		
CV-2011	9/4/2025 2:10:02 PM	50.5	43.8	0.0	5.7	0.0	1.2		
CV-2011A	9/2/2025 10:00:00 AM							155	
CV-2011A	9/2/2025 10:02:07 AM	28.6	46.5	0.0	24.9	0.0	0.6		
CV-2011A	9/8/2025 10:08:08 AM	32.3	49.9	0.0	17.8	0.0	0.6		
CV-2011A	9/8/2025 10:10:00 AM							302	
CV-2011A	9/18/2025 6:45:46 AM	22.9	51.7	0.0	25.4	0.0	0.4		
CV-2011A	9/22/2025 1:42:17 PM	24.0	0.0	1.1	74.9	68.1			
CV-2011A	9/29/2025 8:15:34 AM	21.8	47.7	1.0	29.5	29.5	0.5		
CV-2012	9/4/2025 1:45:24 PM	46.7	47.8	0.0	5.5	0.0	1.0		
CV-2012	9/4/2025 1:46:31 PM	46.1	47.9	0.0	6.0	0.0	1.0		
CV-2201-PLR	9/4/2025 6:42:47 AM	4.7	83.4	0.4	11.5	28.8	0.1		
CV-2201-PLR	9/4/2025 6:45:00 AM							749	
CV-2201-PLR	9/4/2025 6:45:00 AM								49300
CV-2201-PLR	9/9/2025 10:31:01 AM	9.7	72.1	2.8	15.4	5.5	0.1		
CV-2201-PLR	9/9/2025 10:32:00 AM							1640	
CV-2201-PLR	9/17/2025 10:57:30 AM	8.0	78.5	0.6	12.9	21.5	0.1		
CV-2201-PLR	9/23/2025 9:21:57 AM	3.4	82.2	0.0	14.4	0.0	0.0		
CV-2201-PLR	9/30/2025 9:14:55 AM	3.5	77.8	2.1	16.6	7.9	0.0		
CV-2204-PLR	9/2/2025 10:54:31 AM	1.8	78.4	1.8	18.0	10.0	0.0		
CV-2204-PLR	9/2/2025 10:59:00 AM							810	
CV-2204-PLR	9/2/2025 10:59:00 AM								37500

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-2204-PLR	9/8/2025 8:50:08 AM	1.8	84.9	0.0	13.3	0.0	0.0		
CV-2204-PLR	9/8/2025 8:52:00 AM							2200	
CV-2204-PLR	9/15/2025 11:40:53 AM	4.5	78.6	0.0	16.9	0.0	0.1		
CV-2204-PLR	9/15/2025 11:42:00 AM							1980	
CV-2204-PLR	9/22/2025 11:03:04 AM	2.4	78.8	1.8	17.0	9.4	0.0		
CV-2204-PLR	9/29/2025 9:52:43 AM	1.3	75.7	2.8	20.2	7.2	0.0		
CV-2205	9/9/2025 2:06:11 PM	37.6	51.1	0.0	11.3	0.0	0.7		
CV-2206-PLR	9/10/2025 9:20:31 AM	0.0	5.8	19.8	74.4	3.8	0.0		
CV-2206-PLR	9/10/2025 9:21:33 AM	0.0	5.6	19.7	74.6	3.8	0.0		
CV-2206-PLR	9/23/2025 9:31:55 AM	0.1	2.5	20.2	77.2	3.8	0.0		
CV-2207	9/3/2025 9:55:10 AM	46.4	47.3	0.0	6.3	0.0	1.0		
CV-2207	9/9/2025 10:21:32 AM								
CV-2208A	9/2/2025 10:14:04 AM	24.7	52.2	0.0	23.1	0.0	0.5		
CV-2208A	9/2/2025 10:15:00 AM							552	
CV-2208A	9/8/2025 8:21:14 AM	25.8	55.2	0.0	19.0	0.0	0.5		
CV-2208A	9/8/2025 8:25:00 AM							406	
CV-2208A	9/15/2025 8:11:31 AM	23.2	56.3	0.0	20.5	0.0	0.4		
CV-2208A	9/15/2025 8:42:00 AM							415	
CV-2208A	9/22/2025 8:13:27 AM	21.5	54.7	1.3	22.5	17.3	0.4		
CV-2208A	9/29/2025 8:41:20 AM	20.3	57.5	0.5	21.7	43.4	0.4		
CV-2301	9/3/2025 9:44:41 AM	20.4	69.4	0.2	10.0	52.7	0.3		
CV-2301	9/4/2025 10:47:00 AM	6.5	79.9	0.0	13.6	0.0	0.1		
CV-2301	9/10/2025 9:20:00 AM							890	
CV-2301	9/10/2025 9:20:00 AM								110000
CV-2301	9/11/2025 10:20:00 AM							1730	
CV-2301	9/11/2025 10:21:11 AM	19.5	70.3	0.5	9.7	19.4	0.3		
CV-2301	9/17/2025 9:47:54 AM	23.2	62.9	0.8	13.1	16.4	0.4		
CV-2301	9/24/2025 2:06:26 PM	21.0	62.9	2.3	13.8	6.0	0.3		
CV-2302	9/3/2025 10:01:02 AM	49.6	43.6	0.3	6.6	24.3	1.1		
CV-2302	9/10/2025 9:15:00 AM							100	
CV-2302	9/10/2025 9:15:00 AM								19000

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-2302	9/16/2025 2:11:57 PM	49.1	43.1	0.2	7.6	38.0	1.1		
CV-2303	9/3/2025 1:59:37 PM	8.2	0.0	0.5	91.3	182.6			
CV-2303	9/3/2025 2:05:00 PM							2700	
CV-2303	9/3/2025 2:05:00 PM								117700
CV-2303	9/9/2025 1:42:11 PM	5.7	81.7	0.1	12.5	125.0	0.1		
CV-2303	9/9/2025 1:43:00 PM							2770	
CV-2303	9/11/2025 8:05:00 AM							1500	
CV-2303	9/11/2025 8:05:00 AM								120000
CV-2303	9/16/2025 11:08:40 AM	13.1	80.9	0.0	6.0	0.0	0.2		
CV-2303	9/16/2025 11:10:00 AM							1610	
CV-2303	9/23/2025 9:07:14 AM	1.3	83.5	0.2	15.0	75.0	0.0		
CV-2303	9/30/2025 9:44:00 AM	2.0	76.2	1.9	19.9	10.5	0.0		
CV-2304	9/8/2025 8:21:49 AM	1.8	83.4	0.0	14.8	0.0	0.0		
CV-2304	9/16/2025 11:05:57 AM	2.3	80.2	0.0	17.5	0.0	0.0		
CV-2304	9/16/2025 2:04:00 PM							2070	
CV-2304	9/23/2025 10:49:37 AM	3.4	84.8	0.0	11.8	0.0	0.0		
CV-2305	9/3/2025 10:30:00 AM							1400	
CV-2305	9/3/2025 10:30:00 AM								52000
CV-2305	9/9/2025 12:59:25 PM	17.3	80.5	0.2	2.1	13.7	0.2		
CV-2305	9/9/2025 1:17:51 PM	16.6	83.2	0.2	0.1	0.2	0.2		
CV-2305	9/26/2025 2:20:50 PM	12.3	80.0	0.0	7.7	0.0	0.2		
CV-2306	9/2/2025 10:51:19 AM	4.8	69.1	2.3	23.8	10.3	0.1		
CV-2306	9/2/2025 10:55:00 AM							1670	
CV-2306	9/2/2025 10:55:00 AM								112000
CV-2306	9/8/2025 8:57:45 AM	2.2	97.8	0.0	0.0	0.0	0.0		
CV-2306	9/8/2025 8:58:00 AM							1700	
CV-2306	9/15/2025 11:35:00 AM							2400	
CV-2306	9/15/2025 11:35:10 AM	8.7	79.5	0.0	11.8	0.0	0.1		
CV-2306	9/22/2025 11:07:37 AM	2.2	76.5	2.6	18.7	7.2	0.0		
CV-2306	9/29/2025 10:02:52 AM	1.5	69.4	1.6	27.5	17.2	0.0		
CV-2308-PLR	9/4/2025 7:55:00 AM							1290	
CV-2308-PLR	9/4/2025 7:55:00 AM								78600
CV-2308-PLR	9/4/2025 7:56:04 AM	2.9	79.9	0.0	17.2	0.0	0.0		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-2308-PLR	9/9/2025 10:36:09 AM	5.7	82.6	0.2	11.5	57.5	0.1		
CV-2308-PLR	9/9/2025 10:38:00 AM							2010	
CV-2308-PLR	9/17/2025 10:54:00 AM	7.8	82.6	0.0	9.6	0.0	0.1		
CV-2308-PLR	9/23/2025 9:25:08 AM	3.8	81.9	0.0	14.3	0.0	0.0		
CV-2308-PLR	9/30/2025 9:22:24 AM	3.2	80.3	0.9	15.6	17.3	0.0		
CV-2310-PLR	9/4/2025 6:34:32 AM	1.2	26.0	9.4	63.4	6.7	0.0		
CV-2310-PLR	9/4/2025 6:35:00 AM							106	
CV-2310-PLR	9/4/2025 6:35:00 AM								1000
CV-2310-PLR	9/9/2025 2:18:16 PM	5.8	37.9	2.8	53.5	19.1	0.2		
CV-2310-PLR	9/9/2025 2:20:00 PM							1990	
CV-2310-PLR	9/17/2025 11:14:27 AM	9.8	89.2	0.0	1.0	0.0	0.1		
CV-2310-PLR	9/23/2025 9:18:29 AM	1.7	81.4	0.4	16.5	41.3	0.0		
CV-2310-PLR	9/30/2025 9:32:33 AM	2.1	76.3	2.3	19.3	8.4	0.0		
CV-2311	9/3/2025 10:21:35 AM	21.7	63.3	0.5	14.5	29.0	0.3		
CV-2311	9/3/2025 10:22:00 AM							684	
CV-2311	9/3/2025 10:22:00 AM								33200
CV-2311	9/8/2025 11:02:28 AM	30.3	69.7	0.0	0.0	0.0	0.4		
CV-2311	9/8/2025 11:08:00 AM							1050	
CV-2311	9/16/2025 9:30:00 AM							695	
CV-2311	9/16/2025 9:33:42 AM	28.0	60.0	0.8	11.2	14.0	0.5		
CV-2311	9/23/2025 7:59:37 AM	18.6	67.1	0.3	14.0	46.7	0.3		
CV-2311	9/30/2025 10:45:24 AM	20.7	67.1	1.7	10.5	6.2	0.3		
CV-2312	9/15/2025 8:00:00 AM							2100	
CV-2312	9/15/2025 8:25:00 AM								130000
CV-2312	9/15/2025 9:23:42 AM	6.8	86.1	0.5	6.7	13.3	0.1		
CV-2312	9/15/2025 9:31:05 AM	6.3	85.9	0.2	7.6	36.4	0.1		
CV-2312	9/17/2025 8:48:14 AM	11.4	78.2	0.0	10.4	0.0	0.1		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-2312	9/25/2025 10:07:46 AM	3.1	83.6	0.0	13.3	0.0	0.0		
CV-2312	9/30/2025 1:37:00 PM								
CV-2314	9/11/2025 8:25:00 AM							1200	
CV-2314	9/11/2025 8:25:00 AM								110000
CV-2314	9/11/2025 9:43:41 AM	15.4	79.3	0.2	5.1	23.4	0.2		
CV-2314	9/11/2025 9:45:27 AM	15.3	80.0	0.2	4.5	21.6	0.2		
CV-2314	9/11/2025 9:49:46 AM	13.2	81.8	0.0	4.9	0.0	0.2		
CV-2314	9/11/2025 11:09:14 AM	14.6	79.2	0.0	6.2	0.0	0.2		
CV-2314	9/11/2025 11:11:40 AM	18.4	75.9	0.0	5.7	0.0	0.2		
CV-2314	9/19/2025 11:09:06 AM	17.0	76.9	0.0	6.1	0.0	0.2		
CV-2314	9/19/2025 11:10:00 AM	16.3	75.5	0.0	8.2	0.0	0.2		
CV-2315	9/2/2025 11:00:49 AM	8.6	79.0	0.5	11.9	23.8	0.1		
CV-2315	9/2/2025 11:04:00 AM							1620	
CV-2315	9/2/2025 11:04:00 AM								57750
CV-2315	9/3/2025 10:40:00 AM							1700	
CV-2315	9/3/2025 10:40:00 AM								82000
CV-2315	9/10/2025 2:14:09 PM		77.4	1.5					
CV-2315	9/10/2025 2:17:00 PM							2510	
CV-2315	9/12/2025 1:44:21 PM	12.8	81.3	1.0	4.9	4.9	0.2		
CV-2315	9/17/2025 6:55:43 AM	9.9	85.5	0.0	4.6	0.0	0.1		
CV-2315	9/25/2025 9:01:33 AM	10.5	77.7	0.7	11.1	15.9	0.1		
CV-2316	9/2/2025 11:09:20 AM	6.5	74.6	0.0	18.9	0.0	0.1		
CV-2316	9/9/2025 10:53:03 AM								
CV-2319	9/2/2025 11:21:07 AM	14.8	78.0	0.0	7.2	0.0	0.2		
CV-2319	9/5/2025 1:28:24 PM	18.4	76.1	0.0	5.5	0.0	0.2		
CV-2319	9/5/2025 1:29:22 PM	18.3	75.4	0.0	6.3	0.0	0.2		
CV-2321	9/3/2025 11:04:43 AM	25.4	64.3	0.0	10.3	0.0	0.4		
CV-2321	9/11/2025 1:20:09 PM	4.2	86.4	0.0	9.4	0.0	0.0		
CV-2321	9/11/2025 1:21:13 PM	4.3	81.4	0.0	14.3	0.0	0.1		
CV-2322	9/8/2025 2:08:07 PM	3.1	82.2	0.1	14.6	146.0	0.0		
CV-2322	9/16/2025 1:43:01 PM	19.4	71.8	0.8	8.0	10.0	0.3		
CV-2324	9/3/2025 10:22:37 AM	47.3	45.6	0.0	7.1	0.0	1.0		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-2324	9/9/2025 1:52:48 PM	46.5	50.2	0.0	3.3	0.0	0.9		
CV-2326	9/5/2025 9:23:50 AM	20.8	66.6	1.8	10.8	6.0	0.3		
CV-2326	9/16/2025 9:11:07 AM	15.7	68.8	1.4	14.1	10.1	0.2		
CV-2326	9/18/2025 2:23:16 PM	15.8	73.5	0.4	10.3	25.8	0.2		
CV-2327	9/2/2025 2:48:37 PM	2.0	82.2	0.5	15.3	30.6	0.0		
CV-2327	9/2/2025 2:55:00 PM							2760	
CV-2327	9/2/2025 2:55:00 PM								117500
CV-2327	9/9/2025 9:19:28 AM	9.7	78.0	0.0	12.3	0.0	0.1		
CV-2327	9/9/2025 9:21:14 AM	3.5	83.3	0.0	13.2	0.0	0.0		
CV-2327	9/11/2025 9:26:15 AM	3.4	82.3	1.2	13.1	10.9	0.0		
CV-2327	9/11/2025 9:27:00 AM							2540	
CV-2327	9/17/2025 8:22:31 AM	7.0	87.0	0.0	6.0	0.0	0.1		
CV-2327	9/25/2025 10:26:27 AM	3.8	81.6	0.6	14.0	23.3	0.0		
CV-2328	9/10/2025 8:55:00 AM							1400	
CV-2328	9/10/2025 8:55:00 AM								110000
CV-2328	9/10/2025 1:17:41 PM	10.8	81.9	0.5	6.9	14.9	0.1		
CV-2328	9/10/2025 1:18:29 PM	10.7	81.6	0.4	7.3	17.0	0.1		
CV-2328	9/11/2025 11:03:12 AM	23.7	69.4	1.2	5.7	4.8	0.3		
CV-2328	9/11/2025 1:30:00 PM							889	
CV-2328	9/17/2025 8:35:20 AM	25.4	72.0	0.0	2.6	0.0	0.4		
CV-2328	9/24/2025 2:31:29 PM	45.9	52.7	1.4	0.0	0.0	0.9		
CV-2333	9/2/2025 10:10:00 AM							2200	
CV-2333	9/2/2025 10:10:00 AM								130000
CV-2333	9/10/2025 8:36:34 AM	0.6	87.1	1.0	11.4	11.9	0.0		
CV-2333	9/10/2025 8:37:45 AM	0.5	84.3	1.2	14.1	11.4	0.0		
CV-2333	9/30/2025 1:38:09 PM	0.6	82.4	0.2	16.8	84.0	0.0		
CV-2333	9/30/2025 1:38:52 PM	0.5	81.9	0.1	17.5	175.0	0.0		
CV-2334	9/2/2025 10:05:00 AM							200	
CV-2334	9/2/2025 10:05:00 AM								18000
CV-2334	9/5/2025 2:02:08 PM	43.3	56.6	0.1	0.0	0.0	0.8		
CV-2334	9/30/2025 12:30:03 PM	39.2	56.9	0.1	3.8	34.5	0.7		
CV-2335	9/10/2025 10:08:50 AM	45.7	53.9	0.4	0.0	0.0	0.8		
CV-2335	9/17/2025 8:43:46 AM	48.6	46.8	0.7	3.9	5.6	1.0		
CV-2336	9/10/2025 10:05:30 AM	32.3	59.0	1.3	7.4	5.7	0.5		
CV-2336	9/17/2025 8:48:03 AM	27.7	54.2	3.0	15.1	5.0	0.5		
CV-2337	9/9/2025 8:35:00 AM							2000	
CV-2337	9/9/2025 8:35:00 AM								160000
CV-2337	9/12/2025 9:00:59 AM	8.7	39.7	8.3	43.3	5.2	0.2		
CV-2337	9/12/2025 9:04:21 AM	9.8	43.3	6.6	40.3	6.1	0.2		
CV-2337	9/26/2025 8:16:28 AM	5.8	84.4	0.0	9.8	0.0	0.1		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-2337	9/26/2025 8:17:33 AM	5.9	86.2	0.0	7.9	0.0	0.1		
CV-2338	9/4/2025 8:35:16 AM	1.5	78.9	0.2	19.4	97.0	0.0		
CV-2338	9/4/2025 8:37:00 AM							1940	
CV-2338	9/4/2025 8:37:00 AM								111700
CV-2338	9/10/2025 10:18:03 AM	21.9	76.4	0.6	1.1	1.8	0.3		
CV-2338	9/10/2025 10:21:00 AM							1780	
CV-2338	9/18/2025 8:33:45 AM	6.6	86.9	0.3	6.2	20.7	0.1		
CV-2338	9/24/2025 10:56:05 AM	1.3	78.3	1.5	18.9	12.6	0.0		
CV-2339	9/8/2025 11:17:21 AM	0.4	12.0	17.2	70.4	4.1	0.0		
CV-2339	9/8/2025 11:20:05 AM	0.8	21.6	14.6	63.0	4.3	0.0		
CV-2339	9/9/2025 11:16:42 AM								
CV-2339	9/23/2025 8:48:34 AM	0.7	22.3	15.1	61.9	4.1	0.0		
CV-2341	9/8/2025 11:25:50 AM	5.4	74.9	0.0	19.7	0.0	0.1		
CV-2341	9/9/2025 8:50:00 AM							770	
CV-2341	9/9/2025 8:50:00 AM								170000
CV-2341	9/16/2025 10:49:48 AM	23.3	60.2	0.1	16.4	164.0	0.4		
CV-2342A-PLR	9/4/2025 9:24:20 AM	2.9	76.1	0.1	20.9	209.0	0.0		
CV-2342A-PLR	9/4/2025 9:25:00 AM							722	
CV-2342A-PLR	9/4/2025 9:25:00 AM								102000
CV-2342A-PLR	9/10/2025 10:55:01 AM		62.7	2.7					
CV-2342A-PLR	9/10/2025 10:58:00 AM							1170	
CV-2342A-PLR	9/12/2025 2:13:51 PM	4.7	69.4	1.9	24.0	12.6	0.1		
CV-2342A-PLR	9/18/2025 10:41:09 AM	13.8	78.7	0.0	7.5	0.0	0.2		
CV-2342A-PLR	9/24/2025 10:03:10 AM	2.3	70.8	1.8	25.1	13.9	0.0		
CV-2343	9/4/2025 9:05:29 AM	1.2	82.2	0.0	16.6	0.0	0.0		
CV-2343	9/4/2025 9:25:00 AM							4660	
CV-2343	9/4/2025 9:25:00 AM								110600
CV-2343	9/10/2025 11:41:53 AM	1.6	83.6	0.0	14.8	0.0	0.0		
CV-2343	9/10/2025 11:42:00 AM							4845	
CV-2343	9/12/2025 1:37:54 PM								
CV-2343	9/18/2025 9:11:19 AM	5.2	83.0	0.0	11.8	0.0	0.1		
CV-2343	9/24/2025 9:09:31 AM	0.7	78.7	1.6	19.0	11.9	0.0		
CV-2344	9/4/2025 8:56:00 AM							2210	
CV-2344	9/4/2025 8:56:00 AM								66800
CV-2344	9/4/2025 8:58:42 AM	14.6	70.5	0.0	14.9	0.0	0.2		
CV-2344	9/8/2025 9:45:00 AM							1800	
CV-2344	9/8/2025 9:45:00 AM								99000

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-2344	9/11/2025 1:47:51 PM	14.1	75.9	0.2	9.8	49.0	0.2		
CV-2344	9/11/2025 2:20:00 PM							3560	
CV-2344	9/17/2025 2:28:09 PM	8.8	78.3	0.0	12.9	0.0	0.1		
CV-2344	9/17/2025 2:28:57 PM	9.2	78.8	0.0	12.0	0.0	0.1		
CV-2344	9/18/2025 2:11:01 PM	26.6	73.4	0.0	0.0	0.0	0.4		
CV-2344	9/24/2025 8:57:50 AM	11.3	73.0	1.0	14.7	14.7	0.2		
CV-2345	9/8/2025 9:31:17 AM	23.1	69.4	0.2	7.3	36.5	0.3		
CV-2345	9/9/2025 9:25:00 AM							500	
CV-2345	9/9/2025 9:25:00 AM								33000
CV-2345	9/17/2025 9:11:25 AM	23.2	72.9	0.0	3.9	0.0	0.3		
CV-2345	9/17/2025 9:12:21 AM	22.1	76.2	0.0	1.7	0.0	0.3		
CV-2346	9/2/2025 11:03:58 AM	6.0	84.5	0.0	9.5	0.0	0.1		
CV-2346	9/9/2025 9:20:00 AM							2400	
CV-2346	9/9/2025 9:20:00 AM								95000
CV-2346	9/17/2025 9:16:34 AM	8.0	80.5	0.0	11.5	0.0	0.1		
CV-2347	9/2/2025 11:25:43 AM	20.0	54.3	0.0	25.7	0.0	0.4		
CV-2347	9/9/2025 9:15:00 AM							1700	
CV-2347	9/9/2025 9:15:00 AM								68000
CV-2347	9/17/2025 9:28:38 AM	14.1	71.1	0.0	14.8	0.0	0.2		
CV-2348	9/2/2025 11:32:39 AM	23.5	71.1	0.0	5.4	0.0	0.3		
CV-2348	9/2/2025 11:33:48 AM	22.6	72.1	0.0	5.3	0.0	0.3		
CV-2348	9/9/2025 9:10:00 AM							400	
CV-2348	9/9/2025 9:10:00 AM								19000
CV-2348	9/17/2025 9:33:34 AM	16.4	79.0	0.0	4.6	0.0	0.2		
CV-2348	9/17/2025 9:34:01 AM	15.6	83.6	0.0	0.8	0.0	0.2		
CV-2349	9/4/2025 9:40:00 AM							2900	
CV-2349	9/4/2025 9:40:00 AM								110000
CV-2349	9/5/2025 7:49:52 AM	5.0	80.4	0.4	14.2	35.5	0.1		
CV-2349	9/5/2025 7:50:00 AM							4210	
CV-2349	9/5/2025 7:50:00 AM								84200
CV-2349	9/11/2025 1:56:53 PM	7.5	83.1	0.0	9.4	0.0	0.1		
CV-2349	9/11/2025 2:00:00 PM							4240	
CV-2349	9/18/2025 11:04:29 AM	17.7	82.3	0.0	0.0	0.0	0.2		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-2349	9/18/2025 2:43:09 PM	5.9	83.1	0.0	11.0	0.0	0.1		
CV-2349	9/18/2025 2:44:16 PM	5.9	83.1	0.0	11.0	0.0	0.1		
CV-2350	9/2/2025 2:26:16 PM	10.3	81.0	0.0	8.7	0.0	0.1		
CV-2350	9/8/2025 9:10:00 AM							2500	
CV-2350	9/8/2025 9:10:00 AM								75000
CV-2350	9/17/2025 10:55:34 AM	8.8	83.4	0.1	7.7	77.0	0.1		
CV-2351	9/4/2025 9:00:00 AM							32	
CV-2351	9/4/2025 9:00:00 AM								2800
CV-2351	9/10/2025 8:47:36 AM	0.1	2.0	21.0	76.9	3.7	0.1		
CV-2351	9/17/2025 2:13:22 PM	0.0	0.7	20.0	79.3	4.0	0.0		
CV-2352	9/4/2025 9:28:00 AM							220	
CV-2352	9/4/2025 9:28:00 AM								30000
CV-2352	9/5/2025 10:40:34 AM								
CV-2352	9/10/2025 8:58:04 AM	0.0	6.4	20.0	73.6	3.7	0.0		
CV-2352	9/17/2025 2:17:54 PM	0.0	2.8	19.9	77.3	3.9	0.0		
CV-2353-PLR	9/4/2025 9:36:47 AM	2.2	55.9	4.9	37.0	7.6	0.0		
CV-2353-PLR	9/4/2025 9:40:00 AM							555	
CV-2353-PLR	9/4/2025 9:40:00 AM								92900
CV-2353-PLR	9/8/2025 9:35:00 AM							650	
CV-2353-PLR	9/8/2025 9:35:00 AM								190000
CV-2353-PLR	9/10/2025 10:48:50 AM		57.6	3.3					
CV-2353-PLR	9/10/2025 10:50:00 AM							1830	
CV-2353-PLR	9/12/2025 2:09:56 PM	3.9	66.2	3.4	26.5	7.8	0.1		
CV-2353-PLR	9/18/2025 10:48:02 AM	18.0	63.8	4.3	13.9	3.2	0.3		
CV-2353-PLR	9/24/2025 10:20:25 AM	2.0	64.1	3.8	30.1	7.9	0.0		
CV-2354	9/4/2025 9:35:00 AM							2800	
CV-2354	9/4/2025 9:35:00 AM								120000
CV-2354	9/8/2025 3:32:46 PM	20.2	58.6	3.2	18.0	5.6	0.3		
CV-2354	9/26/2025 8:52:45 AM	3.6	14.9	17.5	64.0	3.7	0.2		
CV-2354	9/26/2025 8:53:43 AM	3.9	15.5	17.0	63.6	3.7	0.3		
CV-24001	9/4/2025 8:04:16 AM	30.5	69.5	0.0	0.0	0.0	0.4		
CV-24001	9/16/2025 10:33:58 AM	30.8	69.0	0.2	0.0	0.0	0.4		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24002	9/9/2025 10:26:26 AM	33.8	66.2	0.0	0.0	0.0	0.5		
CV-24002	9/16/2025 10:22:25 AM	32.8	66.8	0.5	0.0	0.0	0.5		
CV-24003	9/9/2025 10:22:43 AM	39.7	60.3	0.0	0.0	0.0	0.7		
CV-24003	9/16/2025 9:31:10 AM	38.6	60.6	0.2	0.6	3.2	0.6		
CV-24004	9/9/2025 10:03:41 AM	38.0	55.2	1.0	5.8	6.1	0.7		
CV-24004	9/16/2025 9:37:44 AM	36.6	53.8	1.8	7.9	4.5	0.7		
CV-24006	9/5/2025 9:08:53 AM	17.8	80.0	0.0	2.2	0.0	0.2		
CV-24006	9/5/2025 9:10:33 AM	17.2	81.9	0.0	0.9	0.0	0.2		
CV-24006	9/16/2025 9:05:01 AM	14.9	82.0	0.0	3.1	0.0	0.2		
CV-24006	9/18/2025 1:42:35 PM	14.9	79.6	0.0	5.5	0.0	0.2		
CV-24006	9/18/2025 1:43:55 PM	13.8	80.7	0.0	5.5	0.0	0.2		
CV-24007	9/10/2025 10:11:39 AM	12.6	87.3	0.1	0.0	0.0	0.1		
CV-24007	9/11/2025 7:45:00 AM							680	
CV-24007	9/11/2025 7:45:00 AM								65000
CV-24007	9/16/2025 12:28:29 PM	10.4	84.6	0.1	5.0	55.3	0.1		
CV-24008	9/10/2025 10:21:55 AM	3.3	85.0	0.0	11.7	0.0	0.0		
CV-24008	9/10/2025 10:23:16 AM	3.5	84.9	0.0	11.6	0.0	0.0		
CV-24008	9/16/2025 12:35:36 PM	2.1	80.5	0.0	17.4	0.0	0.0		
CV-24008	9/16/2025 12:36:23 PM	1.9	81.2	0.0	16.9	0.0	0.0		
CV-24009	9/2/2025 2:20:10 PM	14.0	77.0	0.4	8.6	21.5	0.2		
CV-24009	9/2/2025 2:28:00 PM							1070	
CV-24009	9/2/2025 2:28:00 PM								75300
CV-24009	9/8/2025 10:47:07 AM	28.6	70.9	0.0	0.5	0.0	0.4		
CV-24009	9/8/2025 10:50:00 AM							495	
CV-24009	9/16/2025 9:10:00 AM							646	
CV-24009	9/16/2025 9:10:33 AM	29.2	70.8	0.0	0.0	0.0	0.4		
CV-24009	9/22/2025 10:49:46 AM	16.1	72.9	0.6	10.4	17.3	0.2		
CV-24010	9/9/2025 9:54:20 AM	31.4	62.8	0.0	5.8	0.0	0.5		
CV-24010	9/16/2025 9:15:19 AM	28.1	62.2	0.3	9.4	32.5	0.5		
CV-24010	9/16/2025 9:18:31 AM	27.3	60.9	0.7	11.2	17.2	0.4		
CV-24010	9/16/2025 10:56:12 AM								
CV-24011	9/3/2025 1:45:00 PM							3530	
CV-24011	9/3/2025 1:45:00 PM								108200
CV-24011	9/3/2025 1:45:11 PM	13.5	62.1	0.1	24.3	243.0	0.2		
CV-24011	9/8/2025 11:10:59 AM	20.9	76.4	0.0	2.7	0.0	0.3		
CV-24011	9/8/2025 11:13:00 AM							4280	
CV-24011	9/16/2025 1:29:16 PM	43.3	55.4	0.4	0.9	2.3	0.8		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24011	9/16/2025 1:33:00 PM							2210	
CV-24011	9/23/2025 8:46:19 AM	13.1	72.9	0.0	14.0	0.0	0.2		
CV-24011	9/30/2025 11:14:08 AM	11.2	76.0	0.0	12.8	0.0	0.1		
CV-24012	9/3/2025 10:32:37 AM	3.0	80.7	0.5	15.8	31.6	0.0		
CV-24012	9/3/2025 10:35:00 AM							1920	
CV-24012	9/3/2025 10:35:00 AM								145600
CV-24012	9/9/2025 10:45:52 AM	3.1	77.9	0.1	18.9	189.0	0.0		
CV-24012	9/9/2025 10:48:00 AM							2210	
CV-24012	9/16/2025 9:44:30 AM	5.1	81.1	0.0	13.8	0.0	0.1		
CV-24012	9/16/2025 9:48:00 AM							1530	
CV-24012	9/23/2025 8:08:57 AM	1.4	81.6	0.0	17.0	0.0	0.0		
CV-24012	9/30/2025 11:07:38 AM	3.2	75.9	1.8	19.1	10.6	0.0		
CV-24013	9/4/2025 10:09:59 AM	0.0	1.2	20.9	77.9	3.7	0.0		
CV-24013	9/4/2025 10:11:31 AM	0.1	1.6	20.8	77.6	3.7	0.1		
CV-24014	9/2/2025 2:14:50 PM	3.4	73.1	0.7	22.8	32.6	0.0		
CV-24014	9/2/2025 2:23:00 PM							2010	
CV-24014	9/2/2025 2:23:00 PM								176300
CV-24014	9/8/2025 10:40:40 AM	4.8	80.7	0.0	14.5	0.0	0.1		
CV-24014	9/8/2025 10:41:40 AM	4.9	79.8	0.0	15.3	0.0	0.1		
CV-24014	9/8/2025 10:44:00 AM							2180	
CV-24014	9/15/2025 10:57:09 AM	2.8	75.3	0.0	21.9	0.0	0.0		
CV-24014	9/15/2025 11:00:00 AM							2340	
CV-24014	9/22/2025 10:38:26 AM	4.2	80.2	0.5	15.1	30.2	0.1		
CV-24014	9/29/2025 2:31:43 PM	4.0	75.3	0.6	20.1	33.5	0.1		
CV-24015	9/3/2025 9:49:26 AM	2.1	68.0	3.0	26.9	9.0	0.0		
CV-24015	9/3/2025 9:55:00 AM							2060	
CV-24015	9/3/2025 9:55:00 AM								137400
CV-24015	9/5/2025 8:17:48 AM	1.1	79.4	0.1	19.4	194.0	0.0		
CV-24015	9/9/2025 9:33:21 AM	1.5	78.5	0.0	20.0	0.0	0.0		
CV-24015	9/9/2025 9:34:00 AM							1238	
CV-24015	9/15/2025 10:00:29 AM	1.4	75.3	0.3	23.0	76.7	0.0		
CV-24015	9/15/2025 10:05:00 AM							2260	

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24015	9/16/2025 11:15:52 AM								
CV-24015	9/22/2025 9:06:44 AM	1.5	77.8	1.2	19.5	16.3	0.0		
CV-24015	9/29/2025 1:59:42 PM	1.7	75.4	0.6	22.3	37.2	0.0		
CV-24016	9/3/2025 1:49:15 PM	22.2	61.9	0.6	15.3	25.5	0.4		
CV-24016	9/3/2025 1:54:00 PM							2460	
CV-24016	9/3/2025 1:54:00 PM								71300
CV-24016	9/8/2025 11:14:40 AM	29.2	65.7	0.0	5.1	0.0	0.4		
CV-24016	9/8/2025 11:18:00 AM							4100	
CV-24016	9/16/2025 10:07:50 AM	20.4	77.1	0.0	2.5	0.0	0.3		
CV-24016	9/16/2025 10:10:00 AM							1700	
CV-24016	9/23/2025 8:40:55 AM	20.6	69.7	0.0	9.7	0.0	0.3		
CV-24016	9/30/2025 11:22:26 AM	23.5	47.3	0.9	28.3	31.4	0.5		
CV-24017	9/3/2025 10:38:48 AM	13.5	75.8	0.0	10.7	0.0	0.2		
CV-24017	9/3/2025 10:40:00 AM							2160	
CV-24017	9/3/2025 10:40:00 AM								123500
CV-24017	9/9/2025 10:59:21 AM	20.6	74.2	0.3	4.9	16.3	0.3		
CV-24017	9/9/2025 11:00:00 AM							1790	
CV-24017	9/11/2025 7:50:00 AM							660	
CV-24017	9/11/2025 7:50:00 AM								65000
CV-24017	9/16/2025 9:51:04 AM	27.5	72.5	0.0	0.0	0.0	0.4		
CV-24017	9/16/2025 9:52:00 AM							1060	
CV-24017	9/23/2025 8:18:33 AM	21.4	73.5	0.1	5.0	50.0	0.3		
CV-24017	9/30/2025 10:51:29 AM	7.0	76.0	1.0	16.0	16.0	0.1		
CV-24018	9/5/2025 10:24:23 AM	16.8	75.9	0.0	7.3	0.0	0.2		
CV-24018	9/16/2025 9:19:19 AM	11.5	76.9	0.0	11.6	0.0	0.1		
CV-24019	9/3/2025 10:57:10 AM	5.9	80.1	0.0	14.0	0.0	0.1		
CV-24019	9/3/2025 10:58:00 AM							2780	
CV-24019	9/3/2025 10:58:00 AM								153700
CV-24019	9/9/2025 11:04:11 AM	6.3	78.7	0.2	14.8	74.0	0.1		
CV-24019	9/9/2025 11:05:00 AM							2040	
CV-24019	9/16/2025 10:00:31 AM	5.9	61.7	4.7	27.7	5.9	0.1		
CV-24019	9/16/2025 10:02:00 AM							853	
CV-24019	9/23/2025 8:27:43 AM	1.9	73.2	0.0	24.9	0.0	0.0		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24020	9/10/2025 9:44:19 AM	0.4	83.0	0.3	16.3	56.2	0.0		
CV-24020	9/10/2025 9:48:04 AM	0.3	79.4	1.1	19.2	17.7	0.0		
CV-24020	9/12/2025 9:47:03 AM	0.7	73.6	0.0	25.7	0.0	0.0		
CV-24020	9/23/2025 9:39:18 AM	0.7	79.6	0.0	19.7	0.0	0.0		
CV-24021	9/10/2025 9:38:22 AM	0.0	2.7	19.7	77.6	3.9	0.0		
CV-24021	9/10/2025 9:39:32 AM	0.0	1.9	19.8	78.3	4.0	0.0		
CV-24021	9/16/2025 2:10:21 PM	8.5	0.8	19.4	71.3	3.7	10.6		
CV-24022-PLR	9/2/2025 2:07:56 PM	2.2	77.2	0.4	20.2	50.5	0.0		
CV-24022-PLR	9/2/2025 2:18:00 PM							2570	
CV-24022-PLR	9/3/2025 2:18:00 PM								131400
CV-24022-PLR	9/8/2025 10:35:45 AM	2.7	73.4	0.0	23.9	0.0	0.0		
CV-24022-PLR	9/8/2025 10:38:00 AM							2120	
CV-24022-PLR	9/15/2025 11:04:36 AM	1.5	75.7	0.0	22.8	0.0	0.0		
CV-24022-PLR	9/15/2025 2:05:40 PM	4.9	71.2	0.0	23.9	0.0	0.1		
CV-24022-PLR	9/16/2025 8:54:00 AM							1545	
CV-24022-PLR	9/22/2025 10:29:57 AM	1.8	70.8	1.9	25.5	13.4	0.0		
CV-24022-PLR	9/29/2025 2:24:05 PM	1.8	72.7	1.2	24.3	20.3	0.0		
CV-24023	9/2/2025 1:57:28 PM	0.9	58.2	4.6	36.3	7.9	0.0		
CV-24023	9/2/2025 2:14:00 PM							2310	
CV-24023	9/2/2025 2:14:00 PM								104200
CV-24023	9/8/2025 10:26:00 AM							596	
CV-24023	9/8/2025 10:26:17 AM	0.6	37.2	3.9	58.3	14.9	0.0		
CV-24023	9/9/2025 9:50:00 AM							3330	
CV-24023	9/9/2025 9:50:03 AM	1.9	54.9	4.8	38.4	8.0	0.0		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24023	9/15/2025 10:13:46 AM	0.7	67.8	2.1	29.4	14.0	0.0		
CV-24023	9/15/2025 10:15:00 AM							3700	
CV-24023	9/22/2025 9:29:28 AM	0.5	58.0	4.5	37.0	8.2	0.0		
CV-24023	9/29/2025 2:11:07 PM	1.1	75.1	0.2	23.6	118.0	0.0		
CV-24024-PLR	9/3/2025 9:38:14 AM	2.0	66.6	3.0	28.4	9.5	0.0		
CV-24024-PLR	9/3/2025 9:40:00 AM							2370	
CV-24024-PLR	9/3/2025 9:40:00 AM								121500
CV-24024-PLR	9/9/2025 9:22:16 AM	1.4	75.1	1.4	22.1	15.8	0.0		
CV-24024-PLR	9/9/2025 9:24:00 AM							2450	
CV-24024-PLR	9/15/2025 9:28:10 AM	1.1	77.8	0.5	20.6	41.2	0.0		
CV-24024-PLR	9/15/2025 9:30:00 AM							2650	
CV-24024-PLR	9/22/2025 8:56:46 AM	1.0	69.5	3.4	26.1	7.7	0.0		
CV-24024-PLR	9/29/2025 1:45:31 PM	1.6	72.9	1.6	23.9	14.9	0.0		
CV-24025	9/3/2025 1:56:13 PM	10.5	60.7	1.3	27.5	21.2	0.2		
CV-24025	9/3/2025 2:00:00 PM							2030	
CV-24025	9/3/2025 2:00:00 PM								58200
CV-24025	9/9/2025 1:37:04 PM	10.0	64.6	1.5	23.9	15.9	0.2		
CV-24025	9/9/2025 1:38:00 PM							1885	
CV-24025	9/16/2025 10:59:39 AM	15.2	64.9	1.7	18.2	10.7	0.2		
CV-24025	9/16/2025 11:00:00 AM							1525	
CV-24025	9/23/2025 9:03:55 AM	3.1	59.0	3.0	34.9	11.6	0.1		
CV-24025	9/30/2025 9:51:56 AM	4.7	71.3	2.3	21.7	9.4	0.1		
CV-24026	9/2/2025 2:33:13 PM	0.3	9.9	18.0	71.8	4.0	0.0		
CV-24026	9/2/2025 2:34:10 PM	0.3	11.4	17.6	70.7	4.0	0.0		
CV-24026	9/3/2025 8:24:30 AM	0.1	5.1	19.3	75.5	3.9	0.0		
CV-24026	9/3/2025 8:32:39 AM	0.0	6.2	19.7	74.1	3.8	0.0		
CV-24026	9/3/2025 9:04:21 AM								
CV-24026	9/8/2025 1:27:07 PM	0.5	70.1	2.0	27.4	13.7	0.0		
CV-24026	9/9/2025 11:13:09 AM	1.7	83.1	0.2	15.0	75.0	0.0		
CV-24026	9/23/2025 9:47:18 AM	3.8	80.9	0.3	15.0	50.0	0.0		
CV-24026	9/23/2025 9:48:10 AM	3.5	82.0	0.1	14.4	144.0	0.0		
CV-24026	9/25/2025 11:00:40 AM	5.3	83.1	0.0	11.6	0.0	0.1		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24026	9/25/2025 11:05:05 AM	5.5	85.3	0.0	9.2	0.0	0.1		
CV-24027	9/10/2025 9:33:45 AM	0.2	34.3	12.0	53.5	4.5	0.0		
CV-24027	9/10/2025 9:34:58 AM	0.1	26.3	13.8	59.8	4.3	0.0		
CV-24027	9/16/2025 2:04:15 PM	12.1	64.7	1.6	21.6	13.5	0.2		
CV-24028	9/2/2025 2:02:21 PM	2.2	72.3	1.0	24.5	24.5	0.0		
CV-24028	9/2/2025 2:05:00 PM							1860	
CV-24028	9/2/2025 2:05:00 PM								164600
CV-24028	9/8/2025 10:30:45 AM	3.4	77.4	0.0	19.2	0.0	0.0		
CV-24028	9/8/2025 10:32:00 AM							2140	
CV-24028	9/15/2025 2:00:13 PM	4.6	77.8	0.0	17.6	0.0	0.1		
CV-24028	9/15/2025 2:04:00 PM							1100	
CV-24028	9/22/2025 10:24:26 AM	2.1	75.5	1.9	20.5	10.8	0.0		
CV-24028	9/29/2025 2:16:54 PM	1.9	73.4	1.0	23.7	23.7	0.0		
CV-24029	9/5/2025 8:26:17 AM	1.4	81.1	0.0	17.5	0.0	0.0		
CV-24029	9/16/2025 1:28:21 PM								
CV-24029	9/23/2025 10:27:04 AM	1.8	32.1	13.4	52.7	3.9	0.1		
CV-24029	9/23/2025 10:28:20 AM	1.0	24.3	14.4	60.3	4.2	0.0		
CV-24030	9/3/2025 9:18:20 AM	1.7	79.1	0.2	19.0	95.0	0.0		
CV-24030	9/3/2025 9:20:00 AM							2050	
CV-24030	9/3/2025 9:20:00 AM								135100
CV-24030	9/9/2025 9:07:55 AM	1.6	82.3	0.1	16.0	160.0	0.0		
CV-24030	9/9/2025 9:10:00 AM							2800	
CV-24030	9/11/2025 9:10:00 AM							1990	
CV-24030	9/15/2025 9:09:04 AM	1.3	79.7	0.0	19.0	0.0	0.0		
CV-24030	9/22/2025 8:38:56 AM	1.1	75.4	2.7	20.8	7.7	0.0		
CV-24030	9/29/2025 11:36:38 AM	1.6	80.1	0.8	17.5	21.9	0.0		
CV-24031	9/5/2025 10:38:27 AM	34.7	65.3	0.0	0.0	0.0	0.5		
CV-24031	9/16/2025 9:23:45 AM	27.5	69.0	0.0	3.5	0.0	0.4		
CV-24031	9/16/2025 2:06:59 PM								
CV-24032	9/3/2025 2:07:25 PM	4.8	92.2	1.4	1.6	1.1	0.1		
CV-24032	9/3/2025 2:12:00 PM							2450	
CV-24032	9/3/2025 2:12:00 PM								121300

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24032	9/9/2025 1:50:39 PM	3.9	79.5	2.4	14.2	5.9	0.0		
CV-24032	9/9/2025 1:52:00 PM							2030	
CV-24032	9/16/2025 11:20:08 AM	16.0	78.8	0.9	4.3	4.8	0.2		
CV-24032	9/16/2025 11:25:00 AM							1190	
CV-24032	9/23/2025 9:59:19 AM	1.9	82.0	0.8	15.3	19.1	0.0		
CV-24032	9/30/2025 1:52:28 PM	1.0	62.0	3.8	33.2	8.7	0.0		
CV-24033	9/3/2025 2:02:43 PM	5.4	77.6	0.4	16.6	41.5	0.1		
CV-24033	9/3/2025 2:09:00 PM							2065	
CV-24033	9/3/2025 2:09:00 PM								149300
CV-24033	9/9/2025 1:46:18 PM	5.7	77.4	0.0	16.9	0.0	0.1		
CV-24033	9/9/2025 1:48:00 PM							1540	
CV-24033	9/16/2025 11:13:45 AM	14.0	78.8	0.0	7.2	0.0	0.2		
CV-24033	9/16/2025 11:15:00 AM							3260	
CV-24033	9/23/2025 9:14:05 AM	1.3	83.7	0.0	15.0	0.0	0.0		
CV-24033	9/30/2025 9:38:26 AM	1.8	80.7	0.9	16.6	18.4	0.0		
CV-24034	9/2/2025 10:43:35 AM	0.1	13.9	16.8	69.2	4.1	0.0		
CV-24034	9/2/2025 10:44:22 AM	0.1	12.7	17.0	70.2	4.1	0.0		
CV-24034	9/2/2025 10:48:00 AM							266	
CV-24034	9/8/2025 9:04:59 AM	0.2	13.2	16.7	69.9	4.2	0.0		
CV-24034	9/8/2025 9:07:00 AM							674	
CV-24034	9/8/2025 9:08:20 AM	0.6	34.6	11.5	53.3	4.6	0.0		
CV-24034	9/15/2025 11:19:52 AM	1.0	82.9	0.0	16.1	0.0	0.0		
CV-24034	9/15/2025 11:25:00 AM							405	
CV-24034	9/15/2025 11:28:07 AM	4.1	37.7	10.9	47.3	4.3	0.1		
CV-24034	9/16/2025 11:41:28 AM	19.7	22.0	13.8	44.5	3.2	0.9		
CV-24034	9/22/2025 11:13:29 AM	0.5	12.0	17.9	69.6	3.9	0.0		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24034	9/29/2025 10:09:45 AM	0.1	19.5	16.7	63.7	3.8	0.0		
CV-24035	9/2/2025 1:48:03 PM	2.0	76.0	1.1	20.9	19.0	0.0		
CV-24035	9/2/2025 2:10:00 PM							3220	
CV-24035	9/2/2025 2:10:00 PM								160100
CV-24035	9/9/2025 8:39:33 AM	1.5	79.7	0.1	18.7	187.0	0.0		
CV-24035	9/9/2025 8:42:00 AM							1485	
CV-24035	9/11/2025 8:51:00 AM							2190	
CV-24035	9/15/2025 8:51:12 AM	1.6	78.5	0.0	19.9	0.0	0.0		
CV-24035	9/22/2025 8:21:28 AM	3.1	74.1	1.6	21.2	13.3	0.0		
CV-24035	9/29/2025 11:14:11 AM	1.8	76.7	1.0	20.5	20.5	0.0		
CV-24036	9/5/2025 10:47:48 AM	46.9	41.3	3.2	8.6	2.7	1.1		
CV-24036	9/16/2025 9:26:40 AM	41.4	45.5	2.5	10.6	4.2	0.9		
CV-24037	9/8/2025 8:39:03 AM	13.5	74.4	0.0	12.1	0.0	0.2		
CV-24037	9/8/2025 8:39:31 AM	13.0	76.0	0.1	10.9	109.0	0.2		
CV-24037	9/16/2025 11:09:08 AM	9.1	79.1	0.0	11.8	0.0	0.1		
CV-24037	9/16/2025 1:38:00 PM							847	
CV-24037	9/23/2025 9:47:48 AM	9.8	76.0	1.7	12.5	7.4	0.1		
CV-24037	9/30/2025 8:36:23 AM	10.6	74.5	1.5	13.4	8.9	0.1		
CV-24038	9/3/2025 2:18:42 PM	7.6	82.1	0.0	10.3	0.0	0.1		
CV-24038	9/3/2025 2:22:00 PM							2130	
CV-24038	9/3/2025 2:22:00 PM								154500
CV-24038	9/3/2025 2:22:02 PM	12.4	67.5	3.5	16.6	4.7	0.2		
CV-24038	9/9/2025 2:01:00 PM							2520	
CV-24038	9/9/2025 2:01:38 PM	6.7	75.0	0.0	18.3	0.0	0.1		
CV-24038	9/16/2025 1:48:08 PM	18.8	74.6	0.0	6.6	0.0	0.3		
CV-24038	9/16/2025 1:49:59 PM	18.2	76.6	0.0	5.2	0.0	0.2		
CV-24038	9/16/2025 1:50:00 PM							2410	
CV-24038	9/23/2025 9:38:31 AM	1.8	81.3	0.0	16.9	0.0	0.0		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24038	9/30/2025 8:49:35 AM	1.9	83.3	0.0	14.8	0.0	0.0		
CV-24039	9/3/2025 2:27:52 PM	5.5	56.1	4.3	34.1	7.9	0.1		
CV-24039	9/3/2025 2:28:00 PM							2580	
CV-24039	9/3/2025 2:28:00 PM								200100
CV-24039	9/9/2025 2:05:13 PM	4.5	74.1	0.4	21.0	52.5	0.1		
CV-24039	9/9/2025 2:09:00 PM							2700	
CV-24039	9/16/2025 1:53:55 PM	16.6	71.5	0.2	11.7	58.5	0.2		
CV-24039	9/16/2025 1:55:00 PM							1920	
CV-24039	9/23/2025 9:33:15 AM	1.5	78.5	0.4	19.6	49.0	0.0		
CV-24039	9/30/2025 9:00:55 AM	1.0	79.1	1.5	18.4	12.3	0.0		
CV-24040	9/8/2025 10:13:26 AM	0.0	30.9	12.0	57.1	4.8	0.0		
CV-24040	9/8/2025 10:16:36 AM	0.1	46.4	9.6	43.9	4.6	0.0		
CV-24040	9/16/2025 1:19:05 PM	0.4	72.1	0.0	27.5	0.0	0.0		
CV-24040	9/16/2025 1:19:57 PM	0.4	75.1	0.0	24.5	0.0	0.0		
CV-24040	9/16/2025 2:10:00 PM							2750	
CV-24040	9/23/2025 10:57:33 AM	2.0	85.7	0.0	12.3	0.0	0.0		
CV-24041	9/8/2025 10:22:24 AM	0.7	77.2	1.9	20.2	10.6	0.0		
CV-24041	9/16/2025 1:34:33 PM	15.5	75.8	0.0	8.7	0.0	0.2		
CV-24041	9/16/2025 1:36:00 PM	11.8	77.1	0.0	11.1	0.0	0.2		
CV-24041	9/16/2025 2:16:00 PM							1730	
CV-24041	9/23/2025 11:13:01 AM	10.7	22.6	13.5	53.2	3.9	0.5		
CV-24041	9/23/2025 11:16:11 AM	5.6	19.8	15.4	59.2	3.8	0.3		
CV-24042	9/2/2025 10:31:52 AM	7.3	71.1	0.2	21.4	107.0	0.1		
CV-24042	9/2/2025 10:34:00 AM							2300	
CV-24042	9/8/2025 8:40:10 AM	10.8	73.5	0.0	15.7	0.0	0.1		
CV-24042	9/8/2025 8:45:00 AM							1980	
CV-24042	9/15/2025 2:13:22 PM	13.2	73.8	0.1	12.9	129.0	0.2		
CV-24042	9/15/2025 2:15:00 PM							1850	
CV-24042	9/16/2025 1:37:19 PM								
CV-24042	9/22/2025 1:15:59 PM	8.9	62.3	1.4	27.4	19.6	0.1		
CV-24042	9/29/2025 9:23:47 AM	4.3	75.8	0.5	19.4	38.8	0.1		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24043	9/8/2025 10:59:55 AM	51.6	43.9	0.0	4.5	0.0	1.2		
CV-24043	9/16/2025 9:39:54 AM	49.5	44.0	0.0	6.5	0.0	1.1		
CV-24044	9/5/2025 10:52:35 AM	45.9	53.7	0.4	0.0	0.0	0.9		
CV-24044	9/16/2025 10:55:01 AM	37.7	56.2	0.7	5.4	7.7	0.7		
CV-24045	9/3/2025 2:14:13 PM	8.6	77.0	0.9	13.5	15.0	0.1		
CV-24045	9/3/2025 2:18:00 PM							2160	
CV-24045	9/3/2025 2:18:00 PM								157500
CV-24045	9/9/2025 1:56:13 PM	8.6	77.3	0.2	13.9	69.5	0.1		
CV-24045	9/9/2025 1:58:00 PM							1610	
CV-24045	9/16/2025 1:42:07 PM	23.3	71.9	0.0	4.8	0.0	0.3		
CV-24045	9/16/2025 1:43:00 PM							733	
CV-24045	9/23/2025 9:42:57 AM	2.0	80.6	0.0	17.4	0.0	0.0		
CV-24045	9/30/2025 8:42:13 AM	3.2	77.7	1.1	18.0	16.4	0.0		
CV-24046	9/8/2025 10:04:52 AM	0.1	19.5	15.6	64.8	4.2	0.0		
CV-24046	9/8/2025 10:05:32 AM	0.1	20.1	15.2	64.6	4.3	0.0		
CV-24046	9/16/2025 1:13:19 PM	0.4	70.5	1.8	27.3	15.2	0.0		
CV-24048	9/8/2025 10:26:19 AM	20.8	72.0	0.4	6.8	17.0	0.3		
CV-24048	9/16/2025 1:41:18 PM	44.6	55.2	0.2	0.0	0.0	0.8		
CV-24049	9/2/2025 11:18:25 AM	1.8	77.0	1.6	19.6	12.3	0.0		
CV-24049	9/2/2025 11:25:00 AM							4470	
CV-24049	9/2/2025 11:25:00 AM								145300
CV-24049	9/3/2025 9:45:00 AM							2500	
CV-24049	9/3/2025 9:45:00 AM								160000
CV-24049	9/8/2025 8:45:03 AM	1.9	89.8	0.0	8.3	0.0	0.0		
CV-24049	9/8/2025 8:48:00 AM							4100	
CV-24049	9/15/2025 2:22:04 PM	4.3	84.2	0.0	11.5	0.0	0.1		
CV-24049	9/15/2025 2:22:59 PM	4.0	83.6	0.0	12.4	0.0	0.0		
CV-24049	9/15/2025 2:24:00 PM							2850	
CV-24049	9/22/2025 1:21:53 PM	5.4	73.3	1.3	20.0	15.4	0.1		
CV-24049	9/29/2025 9:33:42 AM	1.3	82.4	0.4	15.9	39.8	0.0		
CV-24050	9/8/2025 10:50:27 AM	48.8	47.4	0.0	3.8	0.0	1.0		
CV-24050	9/16/2025 10:46:01 AM	47.4	46.0	0.0	6.6	0.0	1.0		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24051	9/8/2025 8:16:33 AM	27.3	52.7	3.5	16.5	4.7	0.5		
CV-24051	9/16/2025 11:02:28 AM	35.4	59.9	0.1	4.6	46.0	0.6		
CV-24052	9/9/2025 9:09:07 AM	18.0	68.6	0.1	13.3	133.0	0.3		
CV-24052	9/9/2025 9:10:08 AM	18.5	67.5	0.0	14.0	0.0	0.3		
CV-24052	9/16/2025 1:50:21 PM	46.2	53.7	0.1	0.0	0.0	0.9		
CV-24053	9/8/2025 2:11:38 PM	8.9	37.3	11.2	42.6	3.8	0.2		
CV-24053	9/8/2025 2:17:33 PM	7.8	19.4	14.9	57.9	3.9	0.4		
CV-24053	9/11/2025 8:20:00 AM							1700	
CV-24053	9/11/2025 8:20:00 AM								180000
CV-24053	9/16/2025 1:45:54 PM	26.5	72.5	0.0	1.0	0.0	0.4		
CV-24054	9/2/2025 11:13:00 AM							1650	
CV-24054	9/2/2025 11:13:00 AM								90400
CV-24054	9/2/2025 11:13:04 AM	8.2	73.1	2.0	16.7	8.4	0.1		
CV-24054	9/10/2025 2:20:09 PM		81.1	0.0					
CV-24054	9/10/2025 2:22:00 PM							1690	
CV-24054	9/12/2025 1:48:31 PM	10.1	77.9	1.2	10.8	9.0	0.1		
CV-24054	9/17/2025 6:49:53 AM	9.8	86.2	0.0	4.0	0.0	0.1		
CV-24054	9/25/2025 8:51:28 AM	11.5	75.5	1.0	12.0	12.0	0.2		
CV-24054	9/29/2025 9:40:14 AM	6.8	79.7	1.5	12.0	8.0	0.1		
CV-24055	9/2/2025 11:04:57 AM	16.2	54.1	2.8	26.9	9.6	0.3		
CV-24055	9/3/2025 9:50:00 AM							870	
CV-24055	9/3/2025 9:50:00 AM								86000
CV-24055	9/29/2025 12:51:51 PM	3.3	76.5	0.0	20.2	0.0	0.0		
CV-24055	9/29/2025 12:52:44 PM	4.0	78.7	0.0	17.3	0.0	0.1		
CV-24056	9/4/2025 8:48:53 AM	29.6	64.6	0.0	5.8	0.0	0.5		
CV-24056	9/4/2025 8:50:00 AM							1500	
CV-24056	9/4/2025 8:50:00 AM								48400
CV-24056	9/10/2025 9:59:34 AM	41.3	57.9	0.8	0.0	0.0	0.7		
CV-24056	9/10/2025 10:00:00 AM							762	
CV-24056	9/18/2025 8:57:35 AM	36.5	63.5	0.0	0.0	0.0	0.6		
CV-24056	9/24/2025 11:21:31 AM	29.1	68.7	0.3	1.9	6.3	0.4		
CV-24057	9/8/2025 10:46:34 AM	46.9	49.9	0.0	3.2	0.0	0.9		
CV-24057	9/26/2025 8:28:21 AM	48.8	41.0	0.0	10.2	0.0	1.2		
CV-24058	9/3/2025 9:35:56 AM	48.2	42.1	0.0	9.8	0.0	1.1		
CV-24058	9/16/2025 2:16:50 PM	44.8	41.3	0.0	13.9	0.0	1.1		
CV-24058	9/17/2025 9:37:05 AM								
CV-24059	9/3/2025 9:53:15 AM	40.5	49.1	0.1	10.3	114.4	0.8		
CV-24059	9/3/2025 9:54:19 AM	39.9	50.2	0.0	10.0	0.0	0.8		
CV-24059	9/16/2025 2:22:20 PM	42.0	47.5	0.0	10.5	0.0	0.9		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24059	9/16/2025 2:22:48 PM	41.4	48.6	0.0	10.0	0.0	0.9		
CV-24060	9/3/2025 10:17:43 AM	43.9	51.7	0.0	4.4	0.0	0.8		
CV-24060	9/16/2025 2:01:22 PM	35.8	57.6	0.1	6.5	65.0	0.6		
CV-24061	9/10/2025 1:37:18 PM	40.6	54.0	0.7	4.8	6.9	0.8		
CV-24061	9/17/2025 9:57:04 AM								
CV-24061	9/18/2025 11:29:36 AM	48.7	47.6	0.0	3.7	0.0	1.0		
CV-24062	9/5/2025 6:49:16 AM	22.5	74.4	0.6	2.5	4.2	0.3		
CV-24062	9/5/2025 6:50:00 AM							701	
CV-24062	9/5/2025 6:50:00 AM								36000
CV-24062	9/10/2025 9:10:00 AM								75000
CV-24062	9/10/2025 9:10:00 AM							780	
CV-24062	9/11/2025 9:35:00 AM	25.5	69.0	1.3	4.2	3.2	0.4		
CV-24062	9/17/2025 8:27:01 AM	33.0	67.0	0.0	0.0	0.0	0.5		
CV-24062	9/24/2025 2:40:00 PM	50.5	47.8	1.7	0.0	0.0	1.1		
CV-24063	9/9/2025 9:39:46 AM	29.0	65.7	0.0	5.3	0.0	0.4		
CV-24063	9/9/2025 9:41:34 AM	10.4	77.0	0.0	12.6	0.0	0.1		
CV-24063	9/15/2025 8:30:00 AM							1900	
CV-24063	9/15/2025 8:30:00 AM								110000
CV-24063	9/26/2025 8:51:30 AM	6.3	79.9	0.0	13.8	0.0	0.1		
CV-24063	9/26/2025 8:53:44 AM	6.3	79.6	0.0	14.1	0.0	0.1		
CV-24063	9/30/2025 2:31:24 PM	6.6	73.2	0.8	19.4	24.3	0.1		
CV-24064	9/3/2025 10:50:00 AM							2500	
CV-24064	9/3/2025 10:50:00 AM								130000
CV-24064	9/5/2025 6:24:17 AM	2.3	87.4	0.7	9.6	13.7	0.0		
CV-24064	9/5/2025 9:44:00 AM							2180	
CV-24064	9/5/2025 9:44:00 AM								71100
CV-24064	9/11/2025 8:49:26 AM	2.7	86.0	0.7	10.6	15.1	0.0		
CV-24064	9/11/2025 8:50:00 AM							3635	
CV-24064	9/17/2025 8:07:55 AM	2.2	96.1	0.0	1.7	0.0	0.0		
CV-24065-TP17	9/2/2025 11:39:29 AM	20.4	76.6	0.0	3.0	0.0	0.3		
CV-24065-TP17	9/3/2025 9:55:00 AM							180	
CV-24065-TP17	9/3/2025 9:55:00 AM								6700
CV-24065-TP17	9/5/2025 1:45:04 PM	23.0	77.0	0.0	0.0	0.0	0.3		
CV-24065-TP17	9/10/2025 10:45:53 AM	26.6	72.4	0.0	1.0	0.0	0.4		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24065-TP17	9/29/2025 1:03:31 PM	23.1	73.9	0.0	3.0	0.0	0.3		
CV-24066	9/2/2025 10:20:16 AM	29.5	53.1	0.8	16.6	20.8	0.6		
CV-24066	9/9/2025 9:05:00 AM							390	
CV-24066	9/9/2025 9:05:00 AM								35000
CV-24066	9/17/2025 8:47:58 AM	29.6	61.7	0.0	8.7	0.0	0.5		
CV-24067	9/8/2025 10:41:44 AM	1.7	81.9	1.2	15.2	12.7	0.0		
CV-24067	9/23/2025 8:36:00 AM	1.3	92.2	1.1	5.4	4.9	0.0		
CV-24068	9/11/2025 12:47:05 PM	27.9	67.3	0.0	4.7	0.0	0.4		
CV-24068	9/18/2025 10:59:15 AM	32.7	61.3	0.0	6.0	0.0	0.5		
CV-24069	9/3/2025 10:37:15 AM	34.4	42.3	3.5	19.9	5.7	0.8		
CV-24069	9/10/2025 9:30:00 AM							310	
CV-24069	9/10/2025 9:30:00 AM								45000
CV-24069	9/18/2025 11:10:36 AM	39.4	41.7	3.6	15.3	4.3	0.9		
CV-24070	9/3/2025 10:25:01 AM	41.1	55.8	0.0	3.1	0.0	0.7		
CV-24070	9/3/2025 10:28:46 AM	39.9	56.5	0.0	3.6	0.0	0.7		
CV-24070	9/10/2025 9:45:00 AM							150	
CV-24070	9/10/2025 9:45:00 AM								28000
CV-24070	9/18/2025 11:16:50 AM	44.7	53.5	0.0	1.8	0.0	0.8		
CV-24071	9/10/2025 9:40:00 AM							220	
CV-24071	9/10/2025 9:40:00 AM								28000
CV-24071	9/10/2025 1:26:51 PM	39.8	55.7	0.8	3.7	4.8	0.7		
CV-24071	9/10/2025 1:28:08 PM	38.9	54.9	0.7	5.5	7.4	0.7		
CV-24071	9/18/2025 11:26:39 AM	47.5	50.6	0.0	1.9	0.0	0.9		
CV-24072	9/11/2025 10:19:27 AM	33.9	66.2	0.0	0.0	0.0	0.5		
CV-24072	9/11/2025 10:20:49 AM	33.6	66.4	0.0	0.0	0.0	0.5		
CV-24072	9/18/2025 8:57:56 AM	41.7	57.6	0.0	0.7	0.0	0.7		
CV-24073-TP13	9/9/2025 9:52:51 AM	33.1	62.8	0.0	4.1	0.0	0.5		
CV-24073-TP13	9/9/2025 9:54:05 AM	33.1	62.6	0.0	4.3	0.0	0.5		
CV-24073-TP13	9/14/2025 12:49:28 PM	36.2	58.6	0.2	5.0	21.9	0.6		
CV-24073-TP13	9/14/2025 12:50:48 PM	25.8	64.8	0.4	9.0	24.4	0.4		
CV-24073-TP13	9/18/2025 8:38:00 AM	47.5	49.0	0.0	3.5	0.0	1.0		
CV-24073-TP13	9/18/2025 8:39:42 AM	42.9	53.1	0.0	4.0	0.0	0.8		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24074	9/5/2025 2:09:04 PM	20.9	77.6	0.0	1.5	0.0	0.3		
CV-24074	9/12/2025 10:31:27 AM	10.9	55.2	4.6	29.3	6.4	0.2		
CV-24074	9/18/2025 8:46:15 AM	13.9	72.5	0.5	13.1	26.2	0.2		
CV-24075-TP15	9/5/2025 6:38:38 AM	3.8	76.3	1.7	18.2	10.7	0.0		
CV-24075-TP15	9/5/2025 6:43:00 AM							1630	
CV-24075-TP15	9/5/2025 6:43:00 AM								56300
CV-24075-TP15	9/10/2025 11:13:25 AM								
CV-24075-TP15	9/11/2025 9:14:51 AM	5.0	79.9	1.9	13.2	6.9	0.1		
CV-24075-TP15	9/11/2025 9:15:00 AM							2700	
CV-24075-TP15	9/17/2025 8:12:05 AM	4.6	87.8	0.0	7.6	0.0	0.1		
CV-24076	9/2/2025 1:44:10 PM	13.2	79.1	0.3	7.4	29.8	0.2		
CV-24076	9/2/2025 1:44:46 PM	13.3	77.1	0.5	9.2	19.1	0.2		
CV-24077	9/2/2025 9:43:04 AM	7.1	81.1	0.4	11.4	28.5	0.1		
CV-24077	9/2/2025 9:54:12 AM	9.9	72.1	1.1	16.9	15.4	0.1		
CV-24077	9/17/2025 8:44:36 AM	13.5	78.2	0.0	8.3	0.0	0.2		
CV-24078	9/8/2025 10:36:46 AM	23.6	70.4	0.1	5.9	59.0	0.3		
CV-24078	9/23/2025 8:28:46 AM	34.9	59.5	0.0	5.6	0.0	0.6		
CV-24079-TP8	9/4/2025 10:32:00 AM	13.8	79.2	0.0	7.0	0.0	0.2		
CV-24079-TP8	9/11/2025 10:43:31 AM	12.9	81.3	0.0	5.8	0.0	0.2		
CV-24079-TP8	9/11/2025 10:44:00 AM							1720	
CV-24079-TP8	9/17/2025 9:30:11 AM	15.2	80.3	0.0	4.5	0.0	0.2		
CV-24079-TP8	9/24/2025 1:54:29 PM	18.9	72.0	1.3	7.8	6.0	0.3		
CV-24080	9/3/2025 10:43:46 AM	42.7	54.9	0.0	2.4	0.0	0.8		
CV-24080	9/26/2025 8:39:34 AM	46.7	51.4	0.0	1.9	0.0	0.9		
CV-24081-TP10	9/3/2025 1:35:47 PM	44.2	55.8	0.0	0.0	0.0	0.8		
CV-24081-TP10	9/17/2025 1:56:55 PM								
CV-24081-TP10	9/18/2025 9:15:56 AM	47.8	51.4	0.0	0.8	0.0	0.9		
CV-24082	9/3/2025 9:26:31 AM	31.1	63.4	0.3	5.1	15.1	0.5		
CV-24082	9/17/2025 1:34:05 PM								
CV-24082	9/18/2025 9:12:44 AM	40.1	55.7	0.3	3.9	13.0	0.7		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24083	9/11/2025 10:33:03 AM	33.4	65.0	0.7	1.0	1.5	0.5		
CV-24083	9/11/2025 10:34:54 AM	35.6	63.8	0.1	0.6	11.2	0.6		
CV-24083	9/11/2025 1:34:03 PM	28.8	69.1	0.0	2.1	0.0	0.4		
CV-24083	9/11/2025 1:35:12 PM	27.4	69.4	0.0	3.2	0.0	0.4		
CV-24083	9/18/2025 11:21:42 AM	43.3	54.9	0.0	1.8	0.0	0.8		
CV-24084-TP11	9/15/2025 10:12:22 AM	3.7	93.3	0.0	3.0	0.0	0.0		
CV-24084-TP11	9/15/2025 10:16:30 AM	4.0	89.9	0.7	5.5	7.6	0.0		
CV-24084-TP11	9/17/2025 9:01:42 AM	3.7	87.1	0.0	9.2	0.0	0.0		
CV-24084-TP11	9/25/2025 10:16:39 AM	6.3	83.5	0.1	10.1	101.0	0.1		
CV-24085	9/4/2025 1:58:05 PM	44.2	41.7	0.1	14.0	140.0	1.1		
CV-24085	9/21/2025 12:33:53 PM	30.9	36.1	0.8	32.3	41.4	0.9		
CV-24086	9/4/2025 2:12:10 PM	46.6	53.4	0.0	0.0	0.0	0.9		
CV-24086	9/17/2025 2:10:47 PM								
CV-24086	9/18/2025 10:50:47 AM	46.1	51.0	0.0	2.9	0.0	0.9		
CV-24087	9/4/2025 2:42:56 PM	47.4	50.5	0.0	2.1	0.0	0.9		
CV-24087	9/18/2025 10:37:04 AM	43.0	42.6	0.3	14.1	47.0	1.0		
CV-24088	9/15/2025 10:01:29 AM	39.5	60.1	0.1	0.4	5.3	0.7		
CV-24088	9/15/2025 10:07:06 AM	39.5	59.7	0.3	0.5	2.0	0.7		
CV-24088	9/16/2025 1:44:00 PM	40.0	55.2	0.0	4.8	0.0	0.7		
CV-24088	9/16/2025 1:44:47 PM	39.6	56.7	0.0	3.7	0.0	0.7		
CV-24089	9/3/2025 10:39:27 AM								
CV-24089	9/4/2025 11:34:01 AM	46.9	46.2	0.0	6.9	0.0	1.0		
CV-24089	9/23/2025 10:35:49 AM	44.7	50.0	0.9	4.4	4.7	0.9		
CV-24090	9/4/2025 2:55:25 PM	28.7	35.5	0.4	35.4	88.5	0.8		
CV-24090	9/18/2025 12:50:51 PM	22.7	34.6	0.1	42.6	609.1	0.7		
CV-24090	9/18/2025 1:02:54 PM	21.4	33.8	0.1	44.8	639.9	0.6		
CV-24091	9/3/2025 1:51:33 PM	44.4	42.3	0.3	13.0	43.3	1.0		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24091	9/18/2025 8:49:34 AM	39.5	41.1	0.3	19.1	56.1	1.0		
CV-24091	9/18/2025 8:54:49 AM	38.9	41.7	0.3	19.1	57.8	0.9		
CV-24092	9/9/2025 11:04:26 AM	50.6	43.1	0.0	6.3	0.0	1.2		
CV-24092	9/18/2025 12:14:08 PM	46.3	41.5	0.2	12.1	66.9	1.1		
CV-24092	9/18/2025 12:20:59 PM	45.0	44.0	0.0	11.0	0.0	1.0		
CV-24093	9/3/2025 11:15:17 AM	47.0	53.0	0.0	0.0	0.0	0.9		
CV-24093	9/22/2025 10:02:13 AM	50.0	47.6	0.1	2.3	38.0	1.1		
CV-24093	9/22/2025 10:06:08 AM	49.9	47.6	0.1	2.4	34.4	1.0		
CV-24093	9/22/2025 10:10:33 AM	51.0	46.4	0.1	2.5	31.8	1.1		
CV-24094	9/3/2025 10:11:52 AM								
CV-24094	9/10/2025 9:44:46 AM								
CV-24094	9/11/2025 8:53:46 AM	10.9	86.3	1.0	1.8	1.8	0.1		
CV-24094	9/11/2025 1:09:03 PM	19.2	73.0	0.8	7.0	8.8	0.3		
CV-24094	9/16/2025 9:15:41 AM								
CV-24094	9/25/2025 10:19:22 AM								
CV-24095	9/8/2025 9:15:00 AM								150000
CV-24095	9/8/2025 9:15:00 AM							5000	
CV-24095	9/8/2025 9:30:00 AM								130000
CV-24095	9/8/2025 2:36:21 PM	8.3	80.9	0.1	10.7	107.0	0.1		
CV-24095	9/18/2025 2:48:19 PM	8.9	74.7	0.0	16.4	0.0	0.1		
CV-24096	9/8/2025 2:22:07 PM	0.1	2.2	20.5	77.2	3.8	0.0		
CV-24096	9/8/2025 2:23:48 PM	0.1	2.0	20.5	77.4	3.8	0.1		
CV-24096	9/10/2025 12:28:40 PM	44.6	51.9	0.3	3.3	12.1	0.9		
CV-24096	9/10/2025 12:29:19 PM	43.9	50.6	0.2	5.3	24.0	0.9		
CV-24096	9/26/2025 8:42:20 AM	35.8	52.4	1.7	10.1	5.9	0.7		
CV-24097	9/8/2025 2:15:19 PM	41.2	33.7	3.8	21.3	5.6	1.2		
CV-24097	9/17/2025 11:07:58 AM	35.0	64.7	0.0	0.3	0.0	0.5		
CV-24097	9/17/2025 11:08:45 AM	35.4	64.6	0.0	0.0	0.0	0.5		
CV-24098	9/2/2025 2:33:25 PM	30.7	55.5	1.9	11.9	6.3	0.6		
CV-24098	9/18/2025 2:37:11 PM	37.2	61.5	0.0	1.3	0.0	0.6		
CV-24099	9/2/2025 2:22:52 PM	16.2	79.6	0.0	4.2	0.0	0.2		
CV-24099	9/8/2025 9:45:58 AM	12.3	87.7	0.0	0.0	0.0	0.1		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24099	9/8/2025 9:47:03 AM	12.0	88.0	0.0	0.0	0.0	0.1		
CV-24099	9/9/2025 1:28:04 PM								
CV-24099	9/17/2025 10:47:54 AM	12.3	84.6	0.0	3.1	0.0	0.1		
CV-24100	9/2/2025 2:04:58 PM	30.9	66.7	0.0	2.4	0.0	0.5		
CV-24100	9/2/2025 2:06:02 PM	30.5	67.4	0.0	2.1	0.0	0.5		
CV-24100	9/8/2025 8:45:00 AM							17	
CV-24100	9/8/2025 8:45:00 AM								4500
CV-24100	9/18/2025 2:29:29 PM	24.0	73.8	0.0	2.2	0.0	0.3		
CV-24100	9/18/2025 2:32:23 PM	24.3	74.2	0.0	1.5	0.0	0.3		
CV-24101	9/2/2025 2:00:02 PM	31.4	41.7	1.2	25.7	21.4	0.8		
CV-24101	9/8/2025 8:40:00 AM							19	
CV-24101	9/8/2025 8:40:00 AM								4100
CV-24101	9/17/2025 10:22:43 AM	18.8	35.1	2.8	43.3	15.5	0.5		
CV-24102	9/8/2025 9:18:43 AM	43.6	37.4	0.0	19.0	0.0	1.2		
CV-24102	9/17/2025 9:38:43 AM	34.0	41.2	0.1	24.7	247.0	0.8		
CV-24103	9/4/2025 8:42:44 AM	48.9	48.3	0.1	2.7	27.0	1.0		
CV-24103	9/17/2025 1:22:44 PM	47.6	49.5	0.0	2.9	0.0	1.0		
CV-24103	9/30/2025 9:42:10 AM								
CV-24104	9/4/2025 9:55:02 AM	50.0	47.0	0.0	3.0	0.0	1.1		
CV-24104	9/10/2025 11:08:23 AM	48.4	49.9	0.0	1.7	0.0	1.0		
CV-24104	9/17/2025 1:13:15 PM	49.0	46.4	0.0	4.6	0.0	1.1		
CV-24104	9/30/2025 9:33:12 AM								
CV-24105	9/4/2025 9:49:04 AM	43.8	48.9	0.0	7.3	0.0	0.9		
CV-24105	9/17/2025 1:06:55 PM	44.3	46.2	0.0	9.5	0.0	1.0		
CV-24105	9/30/2025 9:10:47 AM								
CV-24106	9/4/2025 11:03:25 AM	41.6	38.0	0.0	20.4	0.0	1.1		
CV-24106	9/17/2025 10:00:21 AM	45.2	40.0	0.0	14.8	0.0	1.1		
CV-24106	9/25/2025 2:39:04 PM	58.6	40.8	0.0	0.6	0.0	1.4		
CV-24107	9/10/2025 2:01:13 PM	40.7	48.8	0.2	10.3	51.5	0.8		
CV-24108	9/10/2025 1:14:32 PM	44.3	38.8	3.2	13.7	4.3	1.1		
CV-24109	9/9/2025 2:45:16 PM	27.0	33.4	4.4	35.2	8.0	0.8		
CV-24110	9/3/2025 10:26:09 AM	46.2	50.2	0.0	3.6	0.0	0.9		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24110	9/11/2025 10:30:33 AM	49.3	48.8	0.0	1.9	0.0	1.0		
CV-24111	9/3/2025 10:30:26 AM	37.6	59.9	0.0	2.5	0.0	0.6		
CV-24111	9/11/2025 10:43:06 AM	45.4	54.6	0.0	0.0	0.0	0.8		
CV-24112	9/3/2025 10:16:20 AM	53.9	42.0	0.0	4.1	0.0	1.3		
CV-24112	9/10/2025 1:35:13 PM								
CV-24112	9/11/2025 2:03:06 PM	51.3	41.2	0.0	7.5	0.0	1.2		
CV-24113	9/8/2025 9:04:58 AM	59.1	39.4	0.0	1.5	0.0	1.5		
CV-24113	9/15/2025 10:30:40 AM	56.2	39.2	0.0	4.6	0.0	1.4		
CV-24114	9/10/2025 1:55:47 PM								
CV-24114	9/15/2025 2:35:15 AM	56.0	41.5	0.0	2.5	0.0	1.3		
CV-24115	9/5/2025 8:24:13 AM	59.1	36.8	0.3	3.8	12.7	1.6		
CV-24115	9/10/2025 2:15:03 PM								
CV-24115	9/24/2025 10:09:43 AM	53.5	36.0	0.7	9.8	14.0	1.5		
CV-24116	9/5/2025 8:41:41 AM	52.7	44.1	0.0	3.2	0.0	1.2		
CV-24116	9/18/2025 9:38:02 AM	36.6	38.0	3.1	22.3	7.2	1.0		
CV-24116	9/26/2025 9:12:19 AM	36.0	37.8	2.0	24.2	12.1	1.0		
CV-24117	9/10/2025 10:29:11 AM	37.8	40.2	0.0	22.0	0.0	0.9		
CV-24118	9/4/2025 2:46:28 PM	18.0	55.0	1.4	25.6	18.3	0.3		
CV-24118	9/4/2025 2:49:20 PM	14.8	61.4	1.0	22.8	22.8	0.2		
CV-24119	9/11/2025 9:30:21 AM	46.0	49.2	0.0	4.8	0.0	0.9		
CV-24119	9/11/2025 9:32:05 AM	45.9	47.3	0.0	6.8	0.0	1.0		
CV-24120	9/9/2025 9:41:57 AM	8.7	84.7	1.2	5.5	4.7	0.1		
CV-24120	9/9/2025 9:42:55 AM	8.8	85.4	1.0	4.8	4.7	0.1		
CV-24120	9/11/2025 9:00:00 AM							1300	
CV-24120	9/11/2025 9:00:00 AM								72000
CV-24120	9/29/2025 9:37:29 AM	9.3	83.8	0.3	6.6	20.6	0.1		
CV-24121	9/2/2025 9:45:00 AM							74	
CV-24121	9/2/2025 9:45:00 AM								5300
CV-24121	9/9/2025 9:34:59 AM	24.5	74.9	0.3	0.4	1.2	0.3		
CV-24121	9/9/2025 2:05:11 PM								
CV-24121	9/29/2025 9:30:55 AM	25.8	72.7	0.1	1.4	19.9	0.4		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24122	9/2/2025 9:30:00 AM							0	
CV-24122	9/2/2025 9:30:00 AM								3600
CV-24122	9/9/2025 9:27:27 AM	49.7	48.0	0.2	2.2	12.7	1.0		
CV-24122	9/29/2025 9:57:41 AM	52.7	43.2	0.0	4.1	0.0	1.2		
CV-24123	9/9/2025 2:22:03 PM								
CV-24123	9/17/2025 2:05:12 PM	49.9	46.8	0.0	3.3	0.0	1.1		
CV-24124	9/5/2025 2:10:36 PM	18.7	71.7	0.3	9.3	31.0	0.3		
CV-24125-TP20	9/3/2025 8:50:00 AM							36	
CV-24125-TP20	9/3/2025 8:50:00 AM								3800
CV-24125-TP20	9/10/2025 10:36:51 AM								
CV-24125-TP20	9/29/2025 9:13:59 AM	35.2	49.2	0.0	15.6	518.3	0.7		
CV-24126	9/11/2025 1:31:45 PM	10.2	42.4	7.2	40.2	5.6	0.2		
CV-24126	9/11/2025 1:32:45 PM	10.1	42.5	7.2	40.2	5.6	0.2		
CV-24126	9/18/2025 11:42:24 AM	12.8	63.3	5.0	18.9	3.8	0.2		
CV-24126	9/22/2025 1:07:42 PM	3.2	66.1	2.6	28.1	10.8	0.0		
CV-24127	9/2/2025 10:20:00 AM							480	
CV-24127	9/2/2025 10:20:00 AM								36000
CV-24127	9/5/2025 2:23:46 PM	23.5	54.3	0.1	22.1	221.0	0.4		
CV-24127	9/30/2025 12:59:10 PM	14.2	29.1	7.4	49.4	6.7	0.5		
CV-24127	9/30/2025 1:32:54 PM	14.6	38.3	4.9	42.2	8.6	0.4		
CV-24128	9/2/2025 10:00:00 AM							120	
CV-24128	9/2/2025 10:00:00 AM								17000
CV-24128	9/5/2025 1:54:54 PM	25.9	40.7	1.0	32.4	32.4	0.6		
CV-24129	9/5/2025 1:50:28 PM	41.5	57.4	0.4	0.7	1.8	0.7		
CV-24130	9/29/2025 9:03:27 AM	23.5	66.6	0.0	9.9	0.0	0.4		
CV-24131	9/3/2025 9:05:01 AM								
CV-24131	9/10/2025 8:55:13 AM								
CV-24131	9/16/2025 8:19:01 AM								
CV-24131	9/24/2025 1:20:08 PM								
CV-24131	9/29/2025 8:45:14 AM	34.2	59.9	0.0	5.9	0.0	0.6		
CV-24131	9/29/2025 8:48:13 AM	36.2	58.1	0.0	5.8	0.0	0.6		
CV-24131	9/29/2025 8:50:41 AM	36.7	59.1	0.0	4.2	0.0	0.6		
CV-24132	9/11/2025 1:21:43 PM								
CV-24132	9/22/2025 2:27:44 PM	50.9	42.6	0.0	6.5	0.0	1.2		
CV-24133	9/22/2025 1:57:31 PM	46.1	38.6	0.0	15.3	0.0	1.2		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24134-TP19	9/8/2025 8:34:35 AM	41.8	56.2	0.0	2.0	0.0	0.7		
CV-24134-TP19	9/8/2025 8:35:59 AM	41.3	54.8	0.0	3.9	0.0	0.8		
CV-24135	9/2/2025 10:22:28 AM	18.1	64.3	0.2	17.4	87.0	0.3		
CV-24135	9/2/2025 10:23:00 AM							579	
CV-24135	9/8/2025 8:28:16 AM	21.6	65.6	0.0	12.8	0.0	0.3		
CV-24135	9/8/2025 8:30:00 AM							643	
CV-24135	9/15/2025 2:35:35 PM	29.4	64.6	0.0	6.0	0.0	0.5		
CV-24135	9/15/2025 2:48:00 PM							935	
CV-24135	9/22/2025 1:33:27 PM	19.7	65.3	0.8	14.2	17.8	0.3		
CV-24135	9/25/2025 10:20:13 AM	20.9	70.4	0.0	8.7	0.0	0.3		
CV-24135	9/25/2025 10:25:49 AM	21.5	69.4	0.0	9.1	0.0	0.3		
CV-24135	9/29/2025 8:53:02 AM	16.3	70.1	0.0	13.6	0.0	0.2		
CV-24136	9/2/2025 2:27:57 PM	34.7	55.1	0.0	10.2	0.0	0.6		
CV-24136	9/2/2025 2:29:10 PM	35.9	55.3	0.0	8.8	0.0	0.6		
CV-24137	9/4/2025 11:18:53 AM	41.9	50.0	0.0	8.1	0.0	0.8		
CV-24138	9/4/2025 9:30:00 AM							19	
CV-24138	9/4/2025 9:30:00 AM								6400
CV-24138	9/10/2025 9:06:38 AM	0.1	3.0	20.8	76.1	3.7	0.0		
CV-24138	9/26/2025 9:09:34 AM	1.8	67.4	3.1	27.7	8.9	0.0		
CV-24138	9/30/2025 2:04:46 PM	2.2	66.3	1.8	29.7	16.5	0.0		
CV-24139	9/4/2025 9:25:00 AM							50	
CV-24139	9/4/2025 9:25:00 AM								11000
CV-24139	9/10/2025 9:10:08 AM	0.0	0.4	21.5	78.1	3.6	0.0		
CV-24139	9/26/2025 9:16:26 AM	0.0	8.2	20.7	71.1	3.4	0.0		
CV-24140	9/4/2025 9:20:00 AM								180000
CV-24140	9/4/2025 9:20:00 AM							1100	

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24140	9/4/2025 9:44:56 AM	3.8	72.9	0.0	23.3	0.0	0.1		
CV-24140	9/4/2025 9:46:00 AM							1300	
CV-24140	9/4/2025 9:46:00 AM								150800
CV-24140	9/10/2025 1:44:43 PM		74.8	0.7					
CV-24140	9/10/2025 1:47:00 PM							1630	
CV-24140	9/12/2025 2:03:32 PM	5.7	71.0	1.0	22.3	22.3	0.1		
CV-24140	9/18/2025 10:57:14 AM	15.8	76.5	0.5	7.2	14.4	0.2		
CV-24140	9/24/2025 8:35:53 AM	3.1	69.9	2.7	24.3	9.0	0.0		
CV-24141	9/4/2025 9:10:00 AM							41	
CV-24141	9/4/2025 9:10:00 AM								0
CV-24141	9/12/2025 8:37:12 AM	46.5	41.8	0.9	10.8	12.0	1.1		
CV-24141	9/17/2025 2:05:06 PM	22.0	35.0	6.2	36.8	5.9	0.6		
CV-24141	9/17/2025 2:07:40 PM	23.6	38.9	4.4	33.1	7.5	0.6		
CV-24142	9/4/2025 9:51:54 AM	4.7	68.0	1.8	25.5	14.2	0.1		
CV-24142	9/4/2025 9:53:00 AM							2670	
CV-24142	9/4/2025 9:53:00 AM								175900
CV-24142	9/8/2025 9:15:00 AM								130000
CV-24142	9/8/2025 9:30:00 AM							1300	
CV-24142	9/10/2025 1:52:20 PM	36.5	34.6	9.6	19.3	2.0	1.1		
CV-24142	9/24/2025 2:22:25 PM	2.2	36.6	11.1	50.1	4.5	0.1		
CV-24142	9/24/2025 2:22:58 PM	2.3	39.4	10.1	48.2	4.8	0.1		
CV-24142	9/30/2025 2:12:50 PM	2.9	54.0	5.3	37.8	7.1	0.1		
CV-24142	9/30/2025 2:15:54 PM	3.4	62.0	3.3	31.3	9.5	0.1		
CV-24143	9/4/2025 9:15:00 AM							1800	
CV-24143	9/4/2025 9:15:00 AM								180000
CV-24143	9/10/2025 8:52:16 AM	0.9	63.8	5.8	29.5	5.1	0.0		
CV-24143	9/10/2025 8:53:21 AM	0.9	64.4	5.7	29.0	5.1	0.0		
CV-24143	9/26/2025 9:20:08 AM	2.8	70.1	3.6	23.5	6.5	0.0		
CV-24143	9/26/2025 9:22:02 AM	2.6	71.1	3.5	22.8	6.5	0.0		
CV-24144	9/8/2025 2:04:31 PM	57.6	40.0	0.2	2.2	11.0	1.4		
CV-24144	9/17/2025 11:12:19 AM	55.0	43.6	0.0	1.4	0.0	1.3		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24145	9/3/2025 10:28:27 AM	11.9	75.6	0.1	12.4	124.0	0.2		
CV-24145	9/3/2025 10:30:00 AM							1415	
CV-24145	9/3/2025 10:30:00 AM								142850
CV-24145	9/9/2025 10:54:17 AM	4.4	79.8	0.1	15.7	157.0	0.1		
CV-24145	9/9/2025 10:55:00 AM							2640	
CV-24145	9/16/2025 9:38:53 AM	7.8	80.0	0.0	12.2	0.0	0.1		
CV-24145	9/16/2025 9:40:00 AM							2750	
CV-24145	9/17/2025 8:30:14 AM								
CV-24145	9/23/2025 8:05:10 AM	8.5	76.3	0.0	15.2	0.0	0.1		
CV-24145	9/30/2025 10:58:02 AM	5.8	76.6	1.3	16.3	12.5	0.1		
CV-24146	9/2/2025 1:10:17 PM	52.7	43.9	0.0	3.5	0.0	1.2		
CV-24146	9/4/2025 1:50:34 PM								
CV-24146	9/16/2025 12:53:02 PM	51.1	48.9	0.0	0.0	1.0	1.0		
CV-24146	9/16/2025 12:54:53 PM	51.3	45.4	0.0	3.3	108.3	1.1		
CV-24147	9/2/2025 1:06:07 PM	48.6	37.8	2.4	11.2	4.6	1.3		
CV-24147	9/16/2025 12:58:32 PM	49.4	39.6	2.2	8.9	4.1	1.2		
CV-24148	9/8/2025 1:50:05 PM	8.0	85.8	0.0	6.2	0.0	0.1		
CV-24148	9/8/2025 1:50:56 PM	6.3	87.8	0.0	5.9	0.0	0.1		
CV-24148	9/11/2025 11:20:16 AM	8.5	86.8	0.0	4.7	0.0	0.1		
CV-24148	9/11/2025 11:23:07 AM	7.8	86.7	0.0	5.5	0.0	0.1		
CV-24148	9/11/2025 1:20:00 PM							3080	
CV-24148	9/18/2025 1:44:58 PM	17.5	81.0	0.0	1.5	0.0	0.2		
CV-24148	9/18/2025 1:45:48 PM	16.3	83.7	0.0	0.0	0.0	0.2		
CV-24149	9/3/2025 10:12:29 AM								
CV-24149	9/8/2025 2:03:34 PM	34.6	65.4	0.0	0.0	0.0	0.5		
CV-24149	9/10/2025 9:58:14 AM								
CV-24149	9/16/2025 9:27:40 AM								
CV-24149	9/18/2025 11:37:29 AM	38.5	59.6	0.0	1.9	0.0	0.6		
CV-24150	9/9/2025 1:28:17 PM	36.7	63.3	0.0	0.0	0.0	0.6		
CV-24151	9/14/2025 12:54:25 PM	46.3	50.5	0.4	2.9	6.9	0.9		
CV-24151	9/18/2025 8:34:26 AM	51.9	44.4	0.0	3.7	0.0	1.2		
CV-24152	9/14/2025 1:00:39 PM	22.7	73.7	0.1	3.5	70.0	0.3		
CV-24152	9/19/2025 11:01:16 AM	30.5	69.5	0.0	0.0	0.0	0.4		
CV-24153	9/15/2025 12:43:12 PM	52.9	44.2	0.0	3.0	0.0	1.2		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24153	9/16/2025 10:30:17 AM	56.9	39.9	0.0	3.2	0.0	1.4		
CV-24153	9/25/2025 2:22:57 PM	52.6	47.2	0.2	0.0	0.0	1.1		
CV-24154	9/9/2025 10:40:09 AM	46.5	53.3	0.0	0.2	0.0	0.9		
CV-24154	9/11/2025 10:57:05 AM	47.6	49.0	0.5	2.9	5.8	1.0		
CV-24154	9/16/2025 10:35:50 AM	43.9	45.8	0.7	9.6	13.7	1.0		
CV-24155	9/15/2025 12:48:21 PM	34.0	62.8	0.0	3.2	0.0	0.5		
CV-24155	9/16/2025 10:40:28 AM	39.8	55.9	0.0	4.3	0.0	0.7		
CV-24156	9/15/2025 10:33:33 AM	32.8	66.9	0.4	0.0	0.0	0.5		
CV-24156	9/15/2025 10:37:02 AM	32.7	67.2	0.2	0.0	0.0	0.5		
CV-24156	9/22/2025 10:21:52 AM	43.8	55.3	0.0	0.9	0.0	0.8		
CV-24156	9/22/2025 10:22:35 AM	42.9	56.4	0.0	0.7	0.0	0.8		
CV-24157	9/15/2025 9:54:30 AM	50.4	48.0	0.4	1.2	3.2	1.0		
CV-24157	9/16/2025 11:06:04 AM	50.1	47.8	0.0	2.1	0.0	1.0		
CV-24157	9/30/2025 1:53:22 PM								
CV-24158	9/12/2025 2:20:01 PM	51.7	46.2	0.0	2.1	0.0	1.1		
CV-24158	9/15/2025 9:16:48 AM	50.5	46.4	0.0	3.1	0.0	1.1		
CV-24158	9/16/2025 1:38:54 PM	49.3	46.0	0.0	4.7	0.0	1.1		
CV-24159	9/3/2025 1:33:10 PM	46.0	49.0	0.0	5.0	0.0	0.9		
CV-24159	9/5/2025 2:21:09 PM	46.4	53.6	0.0	0.0	0.0	0.9		
CV-24159	9/12/2025 2:02:19 PM	51.3	46.3	0.0	2.4	0.0	1.1		
CV-24159	9/16/2025 1:48:55 PM	48.2	45.7	0.0	6.1	0.0	1.1		
CV-24160	9/5/2025 2:26:19 PM	48.5	50.9	0.0	0.6	0.0	1.0		
CV-24160	9/12/2025 1:53:45 PM	48.1	42.6	2.1	7.2	3.4	1.1		
CV-24160	9/22/2025 9:37:53 AM	51.8	43.9	0.2	4.2	28.0	1.2		
CV-24161	9/9/2025 10:48:23 AM	38.9	58.7	0.0	2.4	0.0	0.7		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24162	9/9/2025 2:26:45 PM	35.5	32.1	6.0	26.4	4.4	1.1		
CV-24163	9/10/2025 2:32:29 PM	37.0	60.2	0.0	2.8	0.0	0.6		
CV-24164	9/5/2025 11:26:06 AM	19.6	80.4	0.0	0.0	0.0	0.2		
CV-24164	9/5/2025 11:29:18 AM	20.2	79.8	0.0	0.0	0.0	0.3		
CV-24164	9/10/2025 10:05:47 AM	37.7	62.1	0.0	0.2	0.0	0.6		
CV-24164	9/10/2025 10:07:47 AM	37.4	62.2	0.0	0.4	0.0	0.6		
CV-24164	9/15/2025 8:58:33 AM	35.8	64.2	0.0	0.0	0.0	0.6		
CV-24164	9/15/2025 8:59:23 AM	35.5	62.8	0.0	1.7	0.0	0.6		
CV-24164	9/18/2025 9:02:45 AM	33.1	66.9	0.0	0.0	0.0	0.5		
CV-24164	9/18/2025 9:03:31 AM	32.4	67.6	0.0	0.0	0.0	0.5		
CV-24164	9/19/2025 9:49:51 AM								
CV-24165	9/5/2025 11:13:22 AM	36.6	61.3	0.0	2.1	0.0	0.6		
CV-24165	9/16/2025 11:14:45 AM	45.2	54.7	0.0	0.1	0.0	0.8		
CV-24166	9/3/2025 2:26:52 PM	52.4	43.3	0.0	4.3	0.0	1.2		
CV-24166	9/12/2025 2:06:12 PM	56.6	42.5	0.0	0.9	0.0	1.3		
CV-24166	9/12/2025 2:12:14 PM	48.7	51.1	0.0	0.2	0.0	1.0		
CV-24166	9/16/2025 1:46:25 PM	52.5	42.2	0.0	5.3	0.0	1.2		
CV-24167	9/3/2025 1:36:08 PM	42.7	42.7	0.0	14.6	0.0	1.0		
CV-24167	9/22/2025 9:46:33 AM	42.4	38.7	0.1	18.9	209.4	1.1		
CV-24168	9/3/2025 9:12:29 AM	40.4	46.7	2.5	10.4	4.2	0.9		
CV-24168	9/16/2025 2:14:56 PM	40.0	43.1	1.7	15.2	8.9	0.9		
CV-24169	9/5/2025 11:19:16 AM	30.6	68.9	0.0	0.5	0.0	0.4		
CV-24169	9/5/2025 11:21:39 AM	33.1	66.7	0.0	0.2	0.0	0.5		
CV-24169	9/15/2025 9:05:52 AM	38.8	44.8	0.0	16.4	0.0	0.9		
CV-24169	9/18/2025 9:06:32 AM	39.1	47.4	0.0	13.5	0.0	0.8		
CV-24170	9/4/2025 2:20:45 PM	27.5	72.5	0.0	0.0	0.0	0.4		
CV-24170	9/18/2025 10:47:10 AM	35.5	61.9	0.6	2.0	3.3	0.6		
CV-24171	9/3/2025 1:42:09 PM	50.1	43.4	0.0	6.5	0.0	1.2		
CV-24171	9/18/2025 8:19:42 AM	51.0	44.2	0.1	4.7	94.6	1.2		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24171	9/18/2025 8:23:27 AM	51.0	43.8	0.0	5.3	0.0	1.2		
CV-24172	9/3/2025 1:56:27 PM	26.8	31.6	7.8	33.8	4.3	0.8		
CV-24172	9/18/2025 9:45:48 AM	8.8	15.5	11.9	63.9	5.4	0.6		
CV-24172	9/18/2025 9:59:20 AM	5.2	10.7	14.0	70.1	5.0	0.5		
CV-24173	9/3/2025 2:00:35 PM	42.9	53.0	0.3	3.8	12.7	0.8		
CV-24173	9/3/2025 2:02:26 PM	44.1	52.0	0.3	3.6	12.0	0.8		
CV-24173	9/18/2025 10:23:36 AM	36.9	44.7	0.3	18.1	72.5	0.8		
CV-24173	9/18/2025 10:27:53 AM	36.2	45.8	0.0	18.0	599.0	0.8		
CV-24174	9/3/2025 2:10:26 PM	35.1	54.2	0.0	10.7	0.0	0.6		
CV-24174	9/23/2025 10:51:24 AM	17.0	74.7	0.1	8.2	102.6	0.2		
CV-24175	9/3/2025 2:14:17 PM	37.6	47.7	0.0	14.7	0.0	0.8		
CV-24175	9/23/2025 11:03:52 AM	26.5	40.2	0.0	33.3	0.0	0.7		
CV-24176	9/4/2025 2:01:20 PM	40.7	55.6	0.0	3.7	0.0	0.7		
CV-24176	9/21/2025 12:40:37 PM	35.0	43.3	0.1	21.6	166.1	0.8		
CV-24176	9/23/2025 8:22:02 AM	35.6	42.0	0.0	22.4	0.0	0.8		
CV-24177	9/2/2025 11:43:58 AM	23.7	37.5	2.4	36.4	15.2	0.6		
CV-24177	9/2/2025 11:46:58 AM	23.2	33.9	2.8	40.1	14.3	0.7		
CV-24177	9/17/2025 9:41:15 AM	21.0	42.0	2.7	34.3	12.7	0.5		
CV-24178	9/4/2025 11:41:55 AM	40.6	45.0	0.0	14.4	0.0	0.9		
CV-24178	9/21/2025 12:54:05 PM	35.0	43.1	0.3	21.7	83.3	0.8		
CV-24179	9/4/2025 1:50:33 PM	37.9	49.5	0.2	12.4	62.0	0.8		
CV-24179	9/17/2025 1:46:51 PM	37.7	47.1	0.0	15.2	0.0	0.8		
CV-24180	9/4/2025 11:46:05 AM	45.6	50.8	0.0	3.6	0.0	0.9		
CV-24180	9/21/2025 12:25:59 PM	38.4	49.0	0.2	12.4	68.8	0.8		
CV-24183	9/3/2025 10:24:34 AM								
CV-24183	9/4/2025 11:30:11 AM	45.4	42.2	2.0	10.4	5.2	1.1		
CV-24183	9/10/2025 10:16:07 AM								
CV-24183	9/16/2025 9:47:03 AM								
CV-24183	9/18/2025 1:17:21 PM	39.7	43.4	1.9	15.1	8.1	0.9		
CV-24183	9/24/2025 2:02:23 PM								
CV-24184	9/4/2025 11:24:32 AM	11.5	9.5	17.1	61.9	3.6	1.2		
CV-24184	9/4/2025 11:27:07 AM	6.1	5.1	19.5	69.3	3.6	1.2		
CV-24185	9/4/2025 3:09:41 PM	42.8	44.2	0.0	13.0	0.0	1.0		
CV-24185	9/17/2025 2:29:29 PM	40.3	40.7	0.0	19.0	0.0	1.0		
CV-24186	9/11/2025 8:24:52 AM	27.0	33.9	4.2	34.9	8.2	0.8		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24186	9/11/2025 8:35:51 AM	19.5	23.7	5.5	51.3	9.3	0.8		
CV-24186	9/11/2025 8:38:04 AM	22.0	26.0	4.7	47.3	10.0	0.8		
CV-24186	9/18/2025 1:24:22 PM	49.5	48.9	0.0	1.6	0.0	1.0		
CV-24186	9/18/2025 1:26:38 PM	48.4	48.9	0.0	2.7	0.0	1.0		
CV-24187	9/8/2025 8:30:08 AM	40.9	38.7	0.2	20.2	101.0	1.1		
CV-24187	9/23/2025 9:46:35 AM	37.7	40.4	0.0	21.9	1096.5	0.9		
CV-24188	9/2/2025 1:55:34 PM	46.9	38.5	0.0	14.6	0.0	1.2		
CV-24188	9/17/2025 9:53:39 AM	41.7	40.4	0.2	17.7	88.5	1.0		
CV-24189	9/2/2025 1:52:51 PM	45.4	38.2	0.8	15.6	19.5	1.2		
CV-24189	9/18/2025 2:21:49 PM	43.2	38.7	0.9	17.2	19.1	1.1		
CV-24190	9/8/2025 8:35:49 AM	55.8	42.7	0.0	1.5	0.0	1.3		
CV-24190	9/11/2025 1:59:31 PM								
CV-24190	9/23/2025 9:53:23 AM	50.9	42.0	0.4	6.7	18.1	1.2		
CV-24190	9/23/2025 9:55:55 AM	50.3	43.0	0.3	6.4	22.9	1.2		
CV-24192	9/8/2025 8:53:26 AM	59.4	40.3	0.0	0.3	0.0	1.5		
CV-24192	9/23/2025 10:06:28 AM	51.9	41.9	0.4	5.8	15.0	1.2		
CV-24193	9/4/2025 8:57:40 AM	55.4	42.2	0.0	2.4	0.0	1.3		
CV-24193	9/17/2025 1:19:27 PM	51.8	43.1	0.0	5.1	0.0	1.2		
CV-24194	9/3/2025 11:45:22 AM								
CV-24194	9/4/2025 8:53:03 AM	53.2	44.7	0.0	2.1	0.0	1.2		
CV-24194	9/17/2025 1:32:21 PM	51.6	42.8	0.0	5.6	0.0	1.2		
CV-24195	9/3/2025 1:39:42 PM								
CV-24195	9/4/2025 9:52:14 AM	48.3	48.9	0.0	2.8	0.0	1.0		
CV-24195	9/10/2025 11:16:09 AM	47.7	51.0	0.0	1.3	0.0	0.9		
CV-24195	9/17/2025 1:09:20 PM	48.3	46.7	0.0	5.0	0.0	1.0		
CV-24196	9/4/2025 10:57:58 AM	51.4	42.3	0.1	6.2	62.0	1.2		
CV-24196	9/17/2025 1:04:09 PM	49.6	44.2	0.0	6.2	0.0	1.1		
CV-24196	9/30/2025 9:22:59 AM								
CV-24197	9/4/2025 11:07:50 AM	38.2	39.3	0.0	22.5	0.0	1.0		
CV-24197	9/21/2025 12:06:54 PM	33.7	39.0	0.3	27.0	81.9	0.9		
CV-24197	9/21/2025 12:10:28 PM	33.2	38.6	0.3	28.0	84.7	0.9		
CV-24198	9/3/2025 2:29:42 PM								

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24198	9/4/2025 9:42:09 AM	46.4	44.7	0.0	8.9	0.0	1.0		
CV-24198	9/17/2025 10:08:43 AM	43.5	45.0	0.0	11.5	0.0	1.0		
CV-24199	9/3/2025 2:39:28 PM								
CV-24199	9/4/2025 9:45:49 AM	48.7	43.2	0.0	8.1	0.0	1.1		
CV-24199	9/10/2025 11:20:46 AM	48.0	43.5	0.0	8.5	0.0	1.1		
CV-24199	9/17/2025 10:05:04 AM	47.5	42.6	0.0	9.9	0.0	1.1		
CV-24200	9/4/2025 8:51:20 AM								
CV-24200	9/5/2025 1:37:21 PM	50.5	43.3	0.0	6.2	0.0	1.2		
CV-24200	9/26/2025 9:29:13 AM	48.5	41.0	0.0	10.5	0.0	1.2		
CV-24200	9/26/2025 1:39:27 PM	49.7	43.8	0.0	6.5	0.0	1.1		
CV-24201	9/4/2025 9:09:09 AM								
CV-24201	9/5/2025 1:43:49 PM	46.1	37.9	2.3	13.7	6.0	1.2		
CV-24201	9/17/2025 2:02:03 PM	41.1	32.8	2.2	23.9	10.9	1.3		
CV-24202	9/4/2025 9:40:41 AM								
CV-24202	9/5/2025 1:50:54 PM	35.1	36.5	0.0	28.4	0.0	1.0		
CV-24202	9/17/2025 2:09:52 PM	34.1	37.3	0.0	28.6	0.0	0.9		
CV-24203	9/5/2025 8:37:08 AM	49.4	42.9	0.0	7.7	0.0	1.2		
CV-24203	9/24/2025 10:24:27 AM	43.3	42.0	0.0	14.7	0.0	1.0		
CV-24204	9/4/2025 10:05:13 AM								
CV-24204	9/5/2025 8:33:00 AM	50.9	41.7	0.0	7.4	0.0	1.2		
CV-24204	9/24/2025 10:18:11 AM	46.3	39.8	0.0	13.9	0.0	1.2		
CV-24205	9/5/2025 8:29:59 AM	48.9	38.0	0.1	13.0	130.0	1.3		
CV-24205	9/24/2025 10:14:34 AM	43.9	37.8	0.1	18.2	182.0	1.2		
CV-24206	9/5/2025 1:27:54 PM	23.0	26.8	0.7	49.5	70.7	0.9		
CV-24206	9/17/2025 9:05:47 AM								
CV-24206	9/24/2025 11:20:40 AM	14.6	22.3	1.9	61.2	32.2	0.7		
CV-24207	9/3/2025 2:21:04 PM	42.4	55.4	0.0	2.2	0.0	0.8		
CV-24207	9/16/2025 1:57:47 PM	45.5	51.6	0.0	2.9	0.0	0.9		
CV-24207	9/16/2025 1:58:46 PM	45.4	51.5	0.0	3.1	0.0	0.9		
CV-24208	9/18/2025 9:29:37 AM	44.4	53.1	0.0	2.5	0.0	0.8		
CV-24209	9/4/2025 10:48:05 AM								
CV-24209	9/17/2025 2:19:12 PM	18.6	49.6	1.4	30.4	21.7	0.4		
CV-24210	9/4/2025 11:11:48 AM								
CV-24210	9/10/2025 1:34:07 PM	31.5	27.5	2.4	38.6	16.1	1.1		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24211	9/11/2025 9:16:26 AM	29.6	59.6	0.0	10.8	0.0	0.5		
CV-24211	9/11/2025 9:17:31 AM	29.3	61.2	0.0	9.5	0.0	0.5		
CV-24212	9/11/2025 9:25:25 AM	11.1	52.8	1.0	35.1	35.1	0.2		
CV-24212	9/11/2025 9:26:08 AM	12.4	57.9	3.4	26.3	7.7	0.2		
CV-24213	9/4/2025 11:07:29 AM	52.5	42.5	0.0	5.0	0.0	1.2		
CV-24213	9/4/2025 11:09:42 AM	50.8	44.4	0.0	4.8	0.0	1.1		
CV-24214	9/2/2025 2:34:46 PM	36.9	45.1	0.1	17.9	179.0	0.8		
CV-24215	9/26/2025 1:39:06 PM	45.0	42.9	0.8	11.3	14.1	1.0		
CV-24216	9/25/2025 2:00:14 PM	38.1	37.3	0.0	24.6	0.0	1.0		
CV-24217	9/3/2025 9:51:28 AM	43.3	45.5	0.4	10.8	27.0	1.0		
CV-24217	9/11/2025 2:33:52 PM								
CV-24218	9/2/2025 11:15:28 AM	45.3	54.7	0.0	0.0	0.0	0.8		
CV-24218	9/3/2025 10:11:17 AM								
CV-24218	9/5/2025 1:38:20 PM	49.0	50.1	0.0	0.9	0.0	1.0		
CV-24218	9/10/2025 9:23:52 AM								
CV-24218	9/18/2025 8:11:15 AM								
CV-24218	9/24/2025 1:38:41 PM								
CV-24219	9/2/2025 11:24:26 AM	20.3	74.7	0.0	5.0	0.0	0.3		
CV-24219	9/26/2025 2:25:25 PM	24.7	70.8	0.0	4.5	0.0	0.3		
CV-24220	9/10/2025 2:43:22 PM	19.1	61.9	1.9	17.1	9.0	0.3		
CV-24222	9/23/2025 11:02:05 AM	56.6	42.2	0.0	1.2	0.0	1.3		
CV-24223	9/23/2025 11:11:38 AM	31.0	34.9	6.7	27.4	4.1	0.9		
CV-24224	9/10/2025 2:17:00 PM	49.3	49.2	0.0	1.5	0.0	1.0		
CV-24225	9/4/2025 2:53:55 PM	50.7	45.8	0.0	3.5	0.0	1.1		
CV-24226	9/11/2025 9:10:56 AM	52.6	47.0	0.0	0.4	0.0	1.1		
CV-24227	9/8/2025 8:58:58 AM	49.5	39.3	0.0	11.2	0.0	1.3		
CV-24231	9/15/2025 2:01:40 AM	44.1	44.1	0.2	11.6	58.0	1.0		
CV-24236	9/2/2025 1:31:44 PM	42.6	35.5	0.0	21.9	0.0	1.2		
CV-24237	9/2/2025 1:34:54 PM	42.2	35.6	0.0	22.2	0.0	1.2		
CV-24243	9/15/2025 9:54:28 AM	53.0	43.3	0.0	3.7	0.0	1.2		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-24244	9/4/2025 10:33:00 AM	45.5	41.0	0.5	13.0	26.0	1.1		
CV-24245	9/24/2025 1:46:00 PM	25.0	27.7	0.0	47.3	0.0	0.9		
CV-24246	9/24/2025 1:39:28 PM	32.0	29.1	4.9	34.0	6.9	1.1		
CV-25	9/22/2025 1:33:04 PM	52.2	41.1	0.4	6.3	15.8	1.3		
CV-2501	9/4/2025 9:26:58 AM	52.7	45.4	0.0	1.9	0.0	1.2		
CV-2501	9/12/2025 8:11:46 AM								
CV-2501	9/17/2025 1:16:02 PM	48.4	47.7	0.0	3.9	0.0	1.0		
CV-2502	9/4/2025 9:07:05 AM	50.7	44.8	0.0	4.5	0.0	1.1		
CV-2502	9/12/2025 8:37:44 AM								
CV-2502	9/17/2025 1:37:06 PM	52.1	43.2	0.0	4.7	0.0	1.2		
CV-2502	9/17/2025 1:40:06 PM	52.6	42.4	0.0	5.0	0.0	1.2		
CV-2503	9/5/2025 2:10:33 PM	54.6	41.5	0.0	3.9	0.0	1.3		
CV-2503	9/12/2025 8:53:21 AM								
CV-2504	9/15/2025 2:27:48 AM	51.0	44.8	0.0	4.2	0.0	1.1		
CV-2505	9/15/2025 2:51:03 AM	55.5	41.3	0.0	3.2	0.0	1.3		
CV-2506	9/15/2025 2:56:05 AM	53.7	43.9	0.0	2.4	0.0	1.2		
CV-2507	9/15/2025 3:01:27 AM	54.2	42.7	0.0	3.1	0.0	1.3		
CV-2508	9/15/2025 3:05:48 AM	54.5	42.8	0.0	2.7	0.0	1.3		
CV-2509	9/15/2025 3:12:04 AM	53.7	43.3	0.0	3.0	0.0	1.2		
CV-2510	9/24/2025 2:14:02 PM	54.2	44.0	0.0	1.8	0.0	1.2		
CV-2511	9/15/2025 2:17:24 AM	47.4	42.6	0.1	9.9	99.0	1.1		
CV-2512	9/15/2025 2:22:20 AM	45.1	44.3	0.0	10.6	0.0	1.0		
CV-2513	9/24/2025 1:31:05 PM	43.5	36.6	0.0	19.9	0.0	1.2		
CV-2514	9/24/2025 1:14:29 PM	55.8	41.2	0.0	3.0	0.0	1.4		
CV-2515	9/12/2025 9:12:13 AM								
CV-2515	9/22/2025 2:04:33 PM	45.6	37.3	0.8	16.3	20.4	1.2		
CV-2516	9/29/2025 1:24:18 PM	53.2	42.9	0.1	3.8	38.0	1.2		
CV-2516	9/30/2025 2:40:00 PM	54.6	40.6	0.0	4.8	0.0	1.3		
CV-2524	9/16/2025 2:25:42 PM	54.9	45.1	0.0	0.0	0.0	1.2		
CV-2529	9/12/2025 10:06:55 AM								
CV-2529	9/23/2025 11:23:06 AM	49.0	41.4	0.9	8.7	9.7	1.2		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-2530	9/11/2025 11:07:58 AM	28.9	44.8	4.8	21.5	4.5	0.6		
CV-2531	9/12/2025 9:47:27 AM								
CV-2531	9/30/2025 2:01:16 PM	18.1	63.5	3.9	14.5	3.7	0.3		
CV-2532	9/11/2025 11:13:42 AM	50.8	48.5	0.0	0.7	0.0	1.0		
CV-2532	9/12/2025 9:31:38 AM								
CV-2532	9/12/2025 9:52:08 AM								
CV-2532	9/15/2025 11:20:47 AM	52.0	44.4	0.0	3.6	0.0	1.2		
CV-2540	9/3/2025 9:18:47 AM	30.7	64.5	0.0	4.9	0.0	0.5		
CV-2540	9/18/2025 9:09:19 AM	43.2	55.2	0.0	1.6	0.0	0.8		
CV-2540	9/19/2025 10:16:17 AM								
CV-2541	9/3/2025 1:19:03 PM	19.9	74.9	0.0	5.2	0.0	0.3		
CV-2541	9/3/2025 1:20:05 PM	18.2	75.1	0.0	6.7	0.0	0.2		
CV-2541	9/4/2025 10:36:24 AM	20.1	75.4	0.0	4.5	0.0	0.3		
CV-2541	9/4/2025 10:37:00 AM							1050	
CV-2541	9/4/2025 10:37:00 AM								59100
CV-2541	9/11/2025 10:30:46 AM	25.1	69.2	0.5	5.2	10.4	0.4		
CV-2541	9/11/2025 10:33:00 AM							758.5	
CV-2541	9/17/2025 9:36:45 AM	30.8	66.8	0.0	2.4	0.0	0.5		
CV-2541	9/24/2025 1:59:39 PM	30.8	55.7	1.7	11.8	6.9	0.6		
CV-2542	9/12/2025 2:27:00 PM	52.0	45.6	0.0	2.4	0.0	1.1		
CV-2542	9/15/2025 2:22:21 PM	52.8	44.2	0.0	3.0	0.0	1.2		
CV-2542	9/16/2025 11:09:30 AM	53.1	44.5	0.0	2.4	0.0	1.2		
CV-2542	9/16/2025 1:36:05 PM	51.3	41.2	0.0	7.5	0.0	1.2		
CV-2542	9/30/2025 2:00:32 PM								
CV-2543-PLR	9/3/2025 1:44:12 PM	1.9	86.9	0.0	11.1	0.0	0.0		
CV-2543-PLR	9/3/2025 1:46:08 PM	2.1	87.4	0.0	10.6	0.0	0.0		
CV-2543-PLR	9/4/2025 10:56:23 AM	4.1	80.4	0.0	15.5	0.0	0.1		
CV-2543-PLR	9/4/2025 11:00:00 AM							2290	
CV-2543-PLR	9/4/2025 11:00:00 AM								84400
CV-2543-PLR	9/11/2025 10:07:20 AM	0.0	0.5	21.5	78.0	3.6	0.0		
CV-2543-PLR	9/11/2025 10:08:00 AM							2740	
CV-2543-PLR	9/11/2025 10:57:29 AM	5.6	69.8	3.7	20.9	5.6	0.1		
CV-2543-PLR	9/17/2025 9:10:37 AM	12.7	72.4	2.0	12.9	6.5	0.2		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-2543-PLR	9/19/2025 2:07:17 PM								
CV-2543-PLR	9/24/2025 2:21:15 PM	31.9	38.4	8.5	21.2	2.5	0.8		
CV-2543-PLR	9/24/2025 2:24:50 PM	31.4	32.8	10.0	25.8	2.6	1.0		
CV-2544	9/15/2025 9:48:46 AM	28.5	69.3	0.2	2.0	9.3	0.4		
CV-2544	9/16/2025 11:01:44 AM	31.5	67.5	0.0	1.0	0.0	0.5		
CV-2544	9/30/2025 1:35:33 PM								
CV-2545	9/15/2025 1:21:14 PM	39.2	59.6	0.0	1.2	0.0	0.7		
CV-2545	9/16/2025 10:54:02 AM	43.1	56.0	0.0	0.9	0.0	0.8		
CV-2545	9/30/2025 10:44:50 AM								
CV-2546	9/15/2025 1:02:30 PM	32.9	65.4	0.0	1.8	0.0	0.5		
CV-2546	9/16/2025 10:44:29 AM	40.3	59.1	0.0	0.6	0.0	0.7		
CV-2546	9/30/2025 11:16:04 AM								
CV-2548	9/29/2025 1:59:17 PM	38.6	55.9	0.0	5.5	0.0	0.7		
CV-2549	9/29/2025 2:09:51 PM	42.6	47.0	0.0	10.4	0.0	0.9		
CV-2552	9/8/2025 1:55:39 PM	35.1	64.9	0.0	0.0	0.0	0.5		
CV-2553	9/3/2025 10:07:37 AM	49.1	44.9	0.0	6.0	0.0	1.1		
CV-2553	9/12/2025 10:46:09 AM								
CV-2553	9/16/2025 2:05:00 PM	49.6	46.7	0.0	3.7	0.0	1.1		
CV-2554	9/4/2025 11:04:58 AM	33.3	66.7	0.0	0.0	0.0	0.5		
CV-2554	9/4/2025 11:05:00 AM							511	
CV-2554	9/4/2025 11:05:00 AM								23100
CV-2554	9/11/2025 9:44:39 AM	19.7	65.4	2.7	12.2	4.5	0.3		
CV-2554	9/11/2025 9:45:00 AM							1830	
CV-2554	9/12/2025 10:41:06 AM	18.1	75.4	0.0	6.5	0.0	0.2		
CV-2554	9/12/2025 10:42:15 AM	16.8	77.1	0.0	6.1	0.0	0.2		
CV-2554	9/17/2025 8:33:41 AM	13.8	77.1	0.0	9.1	0.0	0.2		
CV-2554	9/24/2025 2:35:06 PM	34.4	64.7	0.9	0.0	0.0	0.5		
CV-2555	9/9/2025 9:48:29 AM	50.9	48.6	0.0	0.5	0.0	1.0		
CV-2555	9/12/2025 10:30:57 AM								
CV-2555	9/18/2025 8:53:01 AM	50.0	45.4	0.0	4.6	0.0	1.1		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-2556	9/5/2025 6:32:15 AM	2.1	87.9	0.0	10.0	0.0	0.0		
CV-2556	9/5/2025 6:33:56 AM	2.1	88.4	0.0	9.5	0.0	0.0		
CV-2556	9/5/2025 6:38:00 AM							3290	
CV-2556	9/5/2025 6:38:00 AM								122600
CV-2556	9/11/2025 9:06:00 AM							3750	
CV-2556	9/11/2025 9:06:04 AM	2.2	87.8	0.3	9.7	32.3	0.0		
CV-2556	9/17/2025 8:03:13 AM	2.1	89.6	0.0	8.3	0.0	0.0		
CV-2556	9/19/2025 3:06:07 PM								
CV-2557	9/2/2025 11:32:28 AM	24.4	72.3	0.0	3.3	0.0	0.3		
CV-2557	9/10/2025 10:24:15 AM	35.2	62.0	0.0	2.8	0.0	0.6		
CV-2557	9/29/2025 1:11:46 PM	28.5	63.9	0.0	7.7	0.0	0.4		
CV-2557	9/29/2025 1:12:58 PM	32.4	63.1	0.0	4.5	0.0	0.5		
CV-2558	9/9/2025 12:42:12 PM	2.1	91.2	0.0	6.6	0.0	0.0		
CV-2558	9/9/2025 12:43:57 PM	2.1	89.8	0.0	8.1	0.0	0.0		
CV-2558	9/18/2025 2:00:23 PM	22.2	70.3	0.9	6.6	7.3	0.3		
CV-2558	9/25/2025 10:50:16 AM	8.2	67.2	1.6	23.0	14.4	0.1		
CV-2558	9/30/2025 2:43:43 PM								
CV-2564	9/3/2025 1:26:22 PM	40.2	59.8	0.0	0.0	0.0	0.7		
CV-2564	9/18/2025 9:19:52 AM	38.4	61.0	0.0	0.6	0.0	0.6		
CV-2564	9/19/2025 10:41:12 AM								
CV-48R	9/9/2025 8:43:50 AM								
CV-48R	9/17/2025 2:32:14 PM	52.5	44.5	0.0	3.0	0.0	1.2		
CV-55R	9/2/2025 9:48:00 AM							112	
CV-55R	9/2/2025 9:49:28 AM	30.5	45.7	0.5	23.3	46.6	0.7		
CV-55R	9/8/2025 9:56:46 AM	35.7	47.7	0.4	16.2	40.5	0.7		
CV-55R	9/8/2025 10:00:00 AM							162	
CV-55R	9/18/2025 6:41:09 AM	33.8	49.9	0.2	16.1	80.5	0.7		
CV-55R	9/22/2025 1:52:58 PM	27.9	46.9	1.2	24.0	20.0	0.6		
CV-55R	9/29/2025 8:28:29 AM	29.1	47.2	1.1	22.6	20.5	0.6		
CV-56D	9/4/2025 2:32:23 PM	49.1	43.4	0.1	7.4	74.0	1.1		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
CV-56S	9/4/2025 2:34:59 PM	48.9	42.1	0.0	9.0	0.0	1.2		
CV-57R	9/4/2025 2:05:03 PM	51.2	42.1	0.0	6.7	0.0	1.2		
CV-79R	9/9/2025 11:28:26 AM								
CV-79R	9/10/2025 2:27:03 PM	52.4	45.4	0.0	2.2	0.0	1.2		
CV-84S	9/9/2025 10:59:31 AM	25.2	24.3	7.7	42.8	5.6	1.0		
CV-94	9/4/2025 1:57:52 PM	51.1	41.5	0.0	7.4	0.0	1.2		
CV-95	9/4/2025 2:08:11 PM	50.0	40.4	0.0	9.6	0.0	1.2		
CV-99	9/2/2025 9:35:00 AM							0	
CV-99	9/2/2025 9:35:00 AM								0
CV-99	9/11/2025 2:34:59 PM	33.1	66.5	0.0	0.4	0.0	0.5		
D-02	9/26/2025 2:11:24 PM	58.1	41.3	0.0	0.6	0.0	1.4		
D-03	9/26/2025 2:13:33 PM	56.8	41.9	0.0	1.3	0.0	1.4		
D-04	9/26/2025 2:16:04 PM	55.4	43.9	0.0	0.7	0.0	1.3		
D-05	9/30/2025 2:12:56 PM	24.7	22.8	10.9	41.6	3.8	1.1		
D-09	9/24/2025 1:45:59 PM	55.9	40.2	0.0	3.9	0.0	1.4		
D-10	9/24/2025 1:54:54 PM	51.9	36.0	1.2	10.9	9.1	1.4		
FP-001	9/5/2025 1:45:04 PM	22.0	35.4	3.2	39.4	12.3	0.6		
FP-002	9/5/2025 1:47:56 PM	20.9	31.4	8.0	39.7	5.0	0.7		
FP-003	9/5/2025 1:59:13 PM	3.4	6.9	17.4	72.3	4.2	0.5		
FP-005	9/5/2025 2:13:48 PM	4.2	10.2	13.7	71.9	5.2	0.4		
FP-006	9/10/2025 8:58:02 AM	0.3	7.2	18.2	74.3	4.1	0.0		
FP-008	9/30/2025 1:28:23 PM	2.1	16.0	13.7	68.2	5.0	0.1		
FP-009	9/23/2025 10:20:12 AM	11.4	62.9	5.2	20.5	3.9	0.2		
FP-011	9/4/2025 10:15:17 AM	15.3	72.3	2.8	9.6	3.5	0.2		
FP-012	9/9/2025 10:12:05 AM	5.6	19.9	14.0	60.5	4.3	0.3		
FP-012	9/16/2025 10:10:17 AM	0.3	4.0	19.2	76.5	4.0	0.1		
FP-013	9/4/2025 8:17:32 AM	6.0	9.6	14.5	69.9	4.8	0.6		
FP-013	9/16/2025 10:18:50 AM	4.0	7.4	14.8	73.7	5.0	0.5		
FP-014	9/30/2025 1:47:02 PM	4.0	40.1	10.6	45.3	4.3	0.1		
FP-015	9/10/2025 9:05:52 AM	0.9	9.7	17.5	71.9	4.1	0.1		
FP-016	9/10/2025 9:02:26 AM	2.8	15.3	13.0	68.8	5.3	0.2		
FP-017	9/8/2025 8:25:40 AM	26.0	49.5	2.9	21.6	7.4	0.5		
FP-018	9/23/2025 10:00:57 AM	2.3	4.0	19.3	74.4	3.9	0.6		
FP-019	9/8/2025 8:34:20 AM	37.5	54.7	1.7	6.1	3.6	0.7		
FP-020	9/8/2025 9:49:07 AM	7.7	48.4	8.1	35.8	4.4	0.2		
FP-021	9/8/2025 9:53:20 AM	5.6	70.0	4.4	20.0	4.5	0.1		
FP-022	9/8/2025 9:57:51 AM	9.2	65.6	4.5	20.7	4.6	0.1		
FP-023	9/23/2025 9:51:51 AM	30.6	63.7	0.0	5.7	0.0	0.5		
FP-024	9/8/2025 10:29:20 AM	18.8	54.5	3.9	22.8	5.8	0.3		
FP-025	9/8/2025 10:32:45 AM	7.1	18.2	11.6	63.1	5.4	0.4		
FP-026	9/9/2025 9:12:47 AM	18.7	43.7	4.7	32.9	7.0	0.4		
FP-027	9/9/2025 9:24:02 AM	18.9	30.3	7.5	43.3	5.8	0.6		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
FP-028	9/9/2025 9:30:20 AM	27.4	32.6	5.5	34.5	6.3	0.8		
FP-029	9/8/2025 8:28:58 AM	37.6	45.9	2.0	14.5	7.3	0.8		
FP-030	9/5/2025 10:45:05 AM	37.4	44.2	3.5	14.9	4.3	0.8		
FP-031	9/5/2025 10:41:40 AM	7.3	11.2	15.5	66.0	4.3	0.7		
FP-032	9/5/2025 10:33:41 AM	5.9	18.4	11.5	64.2	5.6	0.3		
FP-033	9/5/2025 10:27:54 AM	1.5	13.3	16.2	69.0	4.3	0.1		
FP-034	9/5/2025 10:21:23 AM	9.0	9.9	16.2	64.9	4.0	0.9		
FP-035	9/5/2025 10:16:28 AM	15.9	24.6	7.0	52.5	7.5	0.6		
FP-036	9/18/2025 2:08:17 PM	0.2	0.6	20.4	78.8	3.9	0.3		
FP-036	9/18/2025 2:11:54 PM	1.9	2.3	19.1	76.7	4.0	0.8		
FP-037	9/5/2025 9:16:08 AM	0.7	5.7	19.0	74.6	3.9	0.1		
FP-037	9/18/2025 2:01:40 PM	0.4	3.4	18.3	77.9	4.3	0.1		
FP-038	9/10/2025 8:35:07 AM	5.5	42.8	7.9	43.8	5.5	0.1		
FP-038	9/16/2025 9:36:00 AM	8.0	11.3	13.0	67.7	5.2	0.7		
FP-039	9/16/2025 9:31:44 AM	16.6	21.8	7.7	53.9	7.0	0.8		
FP-040	9/10/2025 8:38:58 AM	9.9	49.9	6.1	34.1	5.6	0.2		
FP-041	9/10/2025 8:43:16 AM	40.6	43.9	1.5	14.0	9.3	0.9		
FP-042	9/10/2025 9:17:47 AM	0.8	2.7	20.5	76.0	3.7	0.3		
FP-043	9/10/2025 8:24:49 AM	18.8	33.6	3.4	44.2	13.0	0.6		
FP-044	9/10/2025 8:28:48 AM	4.3	20.5	14.1	61.1	4.3	0.2		
FP-046	9/10/2025 8:47:15 AM	5.8	12.1	14.1	67.9	4.8	0.5		
FP-047	9/5/2025 2:05:11 PM	1.4	7.7	16.3	74.6	4.6	0.2		
H-01 (EXP-01)	9/4/2025 1:05:14 PM	11.0	49.9	0.0	39.1	0.0	0.2		
H-01 (EXP-01)	9/4/2025 1:08:50 PM	10.4	49.7	0.0	39.9	0.0	0.2		
H-01 (EXP-01)	9/17/2025 11:09:01 AM	10.4	45.9	0.0	43.7	0.0	0.2		
H-01 (EXP-01)	9/17/2025 11:09:42 AM	10.4	45.5	0.0	44.1	0.0	0.2		
H-02 (EXP-02)	9/8/2025 10:16:58 AM	18.5	50.7	0.1	30.7	307.1	0.4		
H-02 (EXP-02)	9/8/2025 10:34:02 AM	18.6	51.9	0.0	29.5	0.0	0.4		
H-02 (EXP-02)	9/17/2025 1:37:53 PM	20.8	47.2	0.0	32.0	0.0	0.4		
H-03 (EXP-03)	9/8/2025 10:22:40 AM	52.0	47.2	0.0	0.8	0.0	1.1		
H-03 (EXP-03)	9/17/2025 1:41:01 PM	51.1	44.5	0.0	4.4	0.0	1.1		
H-04 (EXP-04)	9/8/2025 10:29:11 AM	3.0	58.1	0.0	39.0	0.0	0.1		
H-04 (EXP-04)	9/16/2025 1:31:30 PM	3.5	56.8	0.0	39.7	0.0	0.1		
H-04 (EXP-04)	9/16/2025 1:32:14 PM	3.1	57.4	0.0	39.5	0.0	0.1		
H-08 (EXP-08)	9/2/2025 1:28:32 PM	45.8	52.2	0.0	1.9	0.0	0.9		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
H-08 (EXP-08)	9/16/2025 1:08:27 PM	47.7	51.9	0.0	0.4	0.0	0.9		
H-10 (EXP-10)	9/2/2025 1:24:32 PM	16.0	70.8	0.2	13.0	56.4	0.2		
H-10 (EXP-10)	9/16/2025 1:14:12 PM	16.1	73.9	0.0	10.0	0.0	0.2		
H-101W	9/4/2025 10:18:02 AM	55.1	37.2	1.0	6.7	6.7	1.5		
H-102A	9/4/2025 10:06:04 AM	60.6	37.0	0.3	2.1	7.0	1.6		
H-1401W	9/4/2025 10:09:32 AM	49.3	30.9	3.8	16.0	4.2	1.6		
H-1404C	9/4/2025 11:36:42 AM	39.9	38.5	0.0	21.6	0.0	1.0		
H-1404C	9/23/2025 10:25:54 AM	41.1	40.6	0.1	18.2	302.7	1.0		
H-1404C	9/23/2025 10:28:02 AM	40.9	42.0	0.0	17.1	0.0	1.0		
H-1405C	9/2/2025 11:14:44 AM	8.0	28.5	1.0	62.5	62.5	0.3		
H-1405C	9/17/2025 9:23:59 AM	15.0	29.5	1.1	54.4	49.5	0.5		
H-1406W	9/2/2025 2:18:09 PM	27.9	70.0	0.0	2.1	0.0	0.4		
H-1406W	9/17/2025 10:40:11 AM	24.5	75.5	0.0	0.0	0.0	0.3		
H-1408CR	9/5/2025 2:06:03 PM	21.7	36.2	0.0	42.1	0.0	0.6		
H-1408E	9/3/2025 9:02:29 AM	48.2	40.5	0.8	10.5	13.5	1.2		
H-1408E	9/16/2025 2:11:47 PM	48.6	38.2	0.5	12.7	25.4	1.3		
H-1408W	9/2/2025 1:49:59 PM	38.5	33.1	3.4	25.0	7.4	1.2		
H-1409N	9/4/2025 3:01:47 PM	20.9	27.3	0.0	51.8	0.0	0.8		
H-1409N	9/17/2025 2:33:39 PM	9.2	21.0	0.0	69.8	0.0	0.4		
H-1409N	9/17/2025 2:34:42 PM	8.0	21.4	0.0	70.6	0.0	0.4		
H-1410S	9/5/2025 8:46:48 AM	53.7	39.9	0.8	5.6	7.0	1.3		
H-1563N	9/8/2025 10:53:11 AM	47.2	40.4	0.0	12.4	0.0	1.2		
H-1563N	9/16/2025 10:40:40 AM	45.2	40.6	0.0	14.2	0.0	1.1		
H-1563S	9/2/2025 11:18:36 AM	16.5	30.5	0.0	53.0	0.0	0.5		
H-1563S	9/17/2025 9:25:54 AM	37.9	39.5	0.0	22.6	0.0	1.0		
H-1565E	9/5/2025 11:05:08 AM	52.8	43.4	0.1	3.7	37.0	1.2		
H-1565E	9/16/2025 2:18:16 PM	51.7	41.5	0.0	6.8	0.0	1.2		
H-1568N	9/3/2025 8:56:33 AM	47.0	41.8	0.0	11.3	0.0	1.1		
H-1568N	9/16/2025 2:03:44 PM	23.4	30.6	0.0	46.0	0.0	0.8		
H-1571S	9/10/2025 11:08:36 AM	42.8	42.9	0.0	14.3	0.0	1.0		
H-1572N	9/9/2025 2:17:13 PM	45.0	46.0	0.0	9.0	0.0	1.0		
H-1572S	9/10/2025 10:58:45 AM	33.8	37.6	0.0	28.6	0.0	0.9		
H-1574N	9/8/2025 2:06:13 PM	43.3	52.2	0.0	4.5	0.0	0.8		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
H-1574N	9/17/2025 11:16:09 AM	35.1	59.7	0.0	5.2	0.0	0.6		
H-1753S	9/8/2025 10:56:51 AM	52.7	42.3	0.0	5.0	0.0	1.2		
H-1753S	9/16/2025 10:36:21 AM	50.5	41.7	0.0	7.8	0.0	1.2		
H-1756S	9/2/2025 11:01:13 AM	25.3	38.7	1.0	35.0	35.0	0.7		
H-1756S	9/17/2025 9:08:42 AM	25.4	43.7	0.0	30.9	0.0	0.6		
H-1757S	9/2/2025 11:10:19 AM	38.3	48.1	0.0	13.6	0.0	0.8		
H-1757S	9/17/2025 9:22:06 AM	40.0	48.4	0.0	11.6	0.0	0.8		
H-1760S	9/3/2025 2:05:45 PM	37.4	50.6	0.0	12.0	0.0	0.7		
H-1760S	9/18/2025 12:03:19 PM	17.3	54.0	0.0	28.7	0.0	0.3		
H-1762N	9/3/2025 2:24:11 PM	49.4	44.3	0.0	6.3	0.0	1.1		
H-1762N	9/16/2025 1:52:23 PM	45.3	38.3	0.0	16.4	0.0	1.2		
H-1763N	9/9/2025 10:55:22 AM	30.1	32.6	4.9	32.4	6.6	0.9		
H-1763S	9/10/2025 1:53:38 PM	31.2	35.7	0.3	32.8	109.3	0.9		
H-1764N	9/10/2025 1:19:03 PM	51.9	41.3	0.0	6.8	0.0	1.3		
H-1764S	9/10/2025 11:12:59 AM	30.4	39.4	0.0	30.2	0.0	0.8		
H-1764S	9/10/2025 1:48:16 PM	39.0	38.0	3.0	20.0	6.7	1.0		
H-1767N	9/23/2025 11:17:56 AM	45.0	47.6	0.0	7.4	0.0	0.9		
H-1769N	9/9/2025 10:07:48 AM	25.9	63.2	0.0	10.9	0.0	0.4		
H-1769N	9/16/2025 9:45:36 AM	20.8	61.6	0.2	17.4	91.7	0.3		
H-1770A	9/5/2025 10:12:48 AM	41.1	58.2	0.0	0.7	0.0	0.7		
H-1770A	9/16/2025 9:15:11 AM	38.7	60.9	0.0	0.4	0.0	0.6		
H-1770N	9/9/2025 8:25:00 AM							56	
H-1770N	9/9/2025 8:25:00 AM								5000
H-1770N	9/9/2025 10:18:27 AM	27.5	72.5	0.0	0.0	0.0	0.4		
H-1770N	9/16/2025 9:58:12 AM	23.4	76.3	0.3	0.0	0.0	0.3		
H-1770N	9/16/2025 10:05:15 AM	22.9	77.1	0.1	0.0	0.0	0.3		
H-1770S	9/2/2025 10:29:06 AM	23.0	31.7	0.0	45.3	0.0	0.7		
H-1770S	9/17/2025 8:51:23 AM	39.2	38.3	0.0	22.5	0.0	1.0		
H-1771A	9/2/2025 1:48:09 PM	31.1	41.9	0.8	26.2	32.8	0.7		
H-1771B	9/2/2025 11:35:50 AM	41.2	58.8	0.0	0.0	0.0	0.7		
H-1771B	9/5/2025 1:48:42 PM	45.6	54.4	0.0	0.0	0.0	0.8		
H-1774N	9/4/2025 7:58:57 AM	37.0	60.8	0.0	2.3	0.0	0.6		
H-1774N	9/16/2025 10:30:15 AM	35.5	64.5	0.1	0.0	0.0	0.5		
H-1801S	9/11/2025 8:38:13 AM	53.4	46.2	0.1	0.3	3.0	1.2		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
H-1802S	9/9/2025 2:20:40 PM	53.7	45.5	0.0	0.8	0.0	1.2		
H-1802S	9/9/2025 2:21:52 PM	53.9	45.4	0.0	0.7	0.0	1.2		
H-1803N	9/4/2025 8:13:49 AM	1.2	64.8	4.6	29.4	6.4	0.0		
H-1803N	9/4/2025 8:15:00 AM							1950	
H-1803N	9/4/2025 8:15:00 AM								122200
H-1803N	9/9/2025 9:29:00 AM							2810	
H-1803N	9/9/2025 9:29:20 AM	1.4	72.2	2.4	24.0	10.0	0.0		
H-1803N	9/17/2025 1:37:14 PM	8.0	67.0	1.8	23.2	12.9	0.1		
H-1803N	9/22/2025 9:13:03 AM	0.9	63.2	5.0	30.9	6.2	0.0		
H-1803N	9/25/2025 11:24:34 AM	1.2	60.2	4.6	34.0	7.4	0.0		
H-1803N	9/29/2025 1:53:02 PM	1.4	60.0	4.3	34.3	8.0	0.0		
H-1804B	9/9/2025 10:44:31 AM	49.0	51.0	0.0	0.0	0.0	1.0		
H-1804N	9/2/2025 1:56:19 PM	53.0	43.6	0.0	3.4	0.0	1.2		
H-1804S	9/10/2025 1:24:21 PM	43.2	38.3	0.0	18.5	0.0	1.1		
H-1805A	9/3/2025 10:39:10 AM	47.9	51.2	0.0	0.9	0.0	0.9		
H-1805B	9/9/2025 2:37:46 PM	53.6	44.6	0.1	1.7	17.0	1.2		
H-1805S	9/10/2025 1:41:01 PM	54.1	43.9	0.0	2.0	0.0	1.2		
H-1806A	9/3/2025 10:01:21 AM	52.6	43.4	0.0	4.0	0.0	1.2		
H-1806A	9/11/2025 1:57:13 PM	50.8	42.9	0.0	6.3	0.0	1.2		
H-1806B	9/9/2025 2:13:40 PM	33.0	65.7	0.0	1.3	0.0	0.5		
H-1806N	9/2/2025 2:20:16 PM	48.2	48.5	0.0	3.3	0.0	1.0		
H-1806S	9/4/2025 2:58:47 PM	47.6	46.8	0.0	5.6	0.0	1.0		
H-1807A	9/4/2025 1:51:37 PM	53.1	43.4	0.0	3.5	0.0	1.2		
H-1807N	9/26/2025 1:13:28 PM	12.8	10.3	15.2	61.7	4.1	1.2		
H-1807N	9/26/2025 1:14:17 PM	12.1	10.2	16.3	61.4	3.8	1.2		
H-1807N	9/26/2025 2:00:16 PM	27.4	18.4	10.8	43.4	4.0	1.5		
H-1807N	9/26/2025 2:08:42 PM	23.5	16.0	12.1	48.4	4.0	1.5		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
H-1807S	9/4/2025 2:16:55 PM	49.8	44.1	0.0	6.1	0.0	1.1		
H-1952S	9/15/2025 10:24:17 AM	43.7	55.4	0.6	0.3	0.5	0.8		
H-1952S	9/16/2025 1:38:39 PM	45.5	50.8	0.1	3.6	36.0	0.9		
H-1953N	9/5/2025 2:21:22 PM	27.8	58.5	1.9	11.8	6.2	0.5		
H-1953N	9/29/2025 2:24:25 PM	24.4	51.5	4.1	20.0	4.9	0.5		
H-1953N	9/29/2025 2:27:26 PM	27.3	59.3	2.5	10.9	4.4	0.5		
H-1954C	9/2/2025 11:28:47 AM	11.5	87.2	0.0	1.3	0.0	0.1		
H-1955C	9/3/2025 10:41:57 AM	47.2	49.4	0.0	3.4	0.0	1.0		
H-1955C	9/11/2025 10:39:37 AM	51.9	45.6	0.0	2.5	0.0	1.1		
H-1955N	9/2/2025 2:05:36 PM	39.5	38.1	0.0	22.4	0.0	1.0		
H-1956B	9/11/2025 1:05:43 PM	44.5	54.3	0.0	1.2	0.0	0.8		
H-1956N	9/2/2025 2:13:34 PM	44.8	44.5	0.0	10.7	0.0	1.0		
H-1956S	9/10/2025 2:22:07 PM	53.0	45.3	0.0	1.7	0.0	1.2		
H-1957B	9/9/2025 1:57:55 PM	47.0	41.8	0.0	11.2	0.0	1.1		
H-1957N	9/2/2025 2:23:01 PM	49.3	44.2	0.0	6.5	0.0	1.1		
H-1957S	9/11/2025 8:41:14 AM	20.8	57.3	4.2	17.7	4.2	0.4		
H-1958C	9/4/2025 1:49:18 PM	49.7	41.7	0.0	8.6	0.0	1.2		
H-1958N	9/26/2025 1:17:27 PM	28.9	33.7	0.0	37.4	0.0	0.9		
H-1958N	9/26/2025 2:11:07 PM	31.5	32.1	0.0	36.4	0.0	1.0		
H-1958S	9/4/2025 2:14:33 PM	48.8	40.5	0.0	10.7	0.0	1.2		
H-1962N	9/4/2025 8:20:52 AM	16.3	83.5	0.0	0.2	0.0	0.2		
H-1962N	9/16/2025 10:15:27 AM	11.1	87.0	0.4	1.5	3.4	0.1		
H-1963N	9/4/2025 8:28:41 AM	28.6	66.5	0.0	4.9	0.0	0.4		
H-1963N	9/16/2025 9:50:06 AM	26.6	65.9	0.2	7.3	48.8	0.4		
H-1966N	9/4/2025 8:09:16 AM	33.0	51.5	0.0	15.6	0.0	0.6		
H-1966N	9/4/2025 8:13:18 AM	31.5	52.3	0.0	16.2	541.0	0.6		
H-1966N	9/16/2025 10:37:50 AM	35.0	57.0	0.2	7.8	52.2	0.6		
H-1967E	9/24/2025 1:59:15 PM	47.5	36.8	2.0	13.7	6.9	1.3		
H-1967W	9/2/2025 1:05:01 PM	56.0	39.2	0.0	4.8	0.0	1.4		
H-2050E	9/25/2025 10:10:00 AM	55.2	42.0	0.5	2.3	4.6	1.3		
H-2050W	9/15/2025 3:15:02 AM	40.2	39.6	0.0	20.2	0.0	1.0		
H-2051W	9/2/2025 1:00:27 PM	56.8	37.3	0.0	5.9	0.0	1.5		
H-2053E	9/24/2025 2:06:57 PM	52.9	41.5	0.0	5.6	0.0	1.3		
H-2053W	9/4/2025 10:12:14 AM	59.2	39.5	0.0	1.3	0.0	1.5		
H-2055E	9/5/2025 1:46:46 PM	17.3	26.5	0.0	56.2	0.0	0.7		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
H-2055E	9/17/2025 2:05:00 PM	14.3	25.8	0.0	59.9	0.0	0.6		
H-2056B	9/24/2025 1:10:25 PM	36.5	33.2	0.1	30.2	302.0	1.1		
H-2056W	9/2/2025 1:09:23 PM	54.8	39.8	0.0	5.4	0.0	1.4		
H-2057E	9/24/2025 2:02:27 PM	55.5	40.5	0.0	4.0	0.0	1.4		
H-2057W	9/4/2025 10:23:26 AM	56.0	41.6	0.0	2.4	0.0	1.3		
H-2058E	9/24/2025 1:49:04 PM	52.6	40.6	0.0	6.8	0.0	1.3		
H-2058W	9/2/2025 1:12:00 PM	43.4	36.1	0.0	20.5	0.0	1.2		
H-2059E	9/24/2025 2:13:04 PM	44.2	37.4	3.2	15.2	4.8	1.2		
H-2059W	9/2/2025 1:42:22 PM	52.3	42.0	0.0	5.7	0.0	1.2		
H-2160E	9/24/2025 10:51:59 AM	0.5	1.3	19.7	78.5	4.0	0.4		
H-2160E	9/24/2025 10:54:32 AM	0.1	0.4	20.1	79.4	4.0	0.3		
H-2161E	9/24/2025 10:43:45 AM	54.4	42.6	0.0	3.0	0.0	1.3		
H-2161W	9/2/2025 1:39:12 PM	55.0	38.9	0.0	6.1	0.0	1.4		
H-2163C	9/4/2025 9:18:37 AM	31.9	51.9	0.0	16.2	0.0	0.6		
H-2163C	9/17/2025 10:14:10 AM	31.7	49.4	0.0	18.9	0.0	0.6		
H-2163W	9/2/2025 1:46:59 PM	42.8	48.6	0.0	8.6	0.0	0.9		
H-2164A	9/4/2025 8:46:43 AM	38.7	55.1	0.0	6.2	0.0	0.7		
H-2164A	9/17/2025 1:26:34 PM	38.3	54.2	0.0	7.5	0.0	0.7		
H-2164E	9/5/2025 1:54:04 PM	43.1	41.7	0.0	15.2	0.0	1.0		
H-2164E	9/17/2025 2:12:25 PM	43.7	41.0	0.0	15.3	0.0	1.1		
H-2165E	9/18/2025 9:22:00 AM	34.5	40.4	0.0	25.1	0.0	0.9		
H-2165W	9/2/2025 2:08:31 PM	24.2	72.7	0.0	3.1	0.0	0.3		
H-2165W	9/8/2025 8:50:00 AM								9400
H-2165W	9/8/2025 8:50:00 AM							41	
H-2165W	9/17/2025 10:28:09 AM	19.1	77.1	0.2	3.6	18.0	0.2		
H-2165W	9/17/2025 10:29:10 AM	19.1	76.7	0.0	4.2	0.0	0.2		
H-2166C	9/3/2025 10:45:07 AM	45.6	48.6	0.0	5.8	0.0	0.9		
H-2166E	9/9/2025 1:40:34 PM	50.9	45.6	0.0	3.5	0.0	1.1		
H-2167A	9/4/2025 1:40:32 PM	33.4	65.7	0.0	0.9	0.0	0.5		
H-2167A	9/4/2025 1:44:14 PM	35.3	63.2	0.2	1.4	8.4	0.6		
H-2167E	9/4/2025 1:55:32 PM	16.8	25.7	1.8	55.7	30.9	0.7		
H-2168C	9/11/2025 1:18:33 PM	56.0	43.5	0.0	0.6	0.0	1.3		
H-2168E	9/9/2025 2:02:29 PM	36.3	60.4	0.0	3.3	0.0	0.6		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
H-2169C	9/9/2025 2:41:52 PM	53.3	44.9	0.0	1.8	0.0	1.2		
H-2169E	9/9/2025 2:08:32 PM	40.5	41.1	0.0	18.4	0.0	1.0		
H-2170N	9/25/2025 1:48:51 PM	52.5	40.9	0.0	6.6	0.0	1.3		
H-2170S	9/11/2025 10:20:40 AM	38.0	37.2	0.4	24.4	61.0	1.0		
H-2171A	9/26/2025 1:23:26 PM	51.0	39.2	0.0	9.8	0.0	1.3		
H-2171B	9/22/2025 1:13:39 PM	48.3	39.2	0.1	12.4	124.0	1.2		
H-2171N	9/22/2025 2:09:45 PM	17.0	25.6	1.9	55.5	29.2	0.7		
H-2171S	9/25/2025 1:45:48 PM	55.2	41.7	0.0	3.1	0.0	1.3		
H-2272W	9/8/2025 9:12:55 AM	40.5	41.0	0.0	18.5	0.0	1.0		
H-2272W	9/17/2025 9:44:23 AM	30.4	43.8	0.0	25.8	0.0	0.7		
H-2273W	9/2/2025 11:28:47 AM	37.9	50.5	0.0	11.6	0.0	0.8		
H-2273W	9/10/2025 10:25:00 AM							110	
H-2273W	9/10/2025 10:25:00 AM								15000
H-2273W	9/17/2025 9:31:19 AM	32.1	47.4	0.0	20.5	0.0	0.7		
H-2274B	9/4/2025 11:11:50 AM	49.0	45.8	0.0	5.2	0.0	1.1		
H-2274B	9/21/2025 12:14:18 PM	47.3	44.8	0.2	7.8	51.8	1.1		
H-2274W	9/2/2025 10:50:19 AM	37.1	55.1	0.0	7.8	0.0	0.7		
H-2274W	9/17/2025 9:06:21 AM	22.5	46.1	0.0	31.4	0.0	0.5		
H-2275E	9/10/2025 1:57:24 PM	43.0	46.2	0.0	10.8	0.0	0.9		
H-2275W	9/2/2025 11:37:01 AM	24.0	36.6	0.5	38.9	77.8	0.7		
H-2275W	9/17/2025 9:37:22 AM	12.9	29.3	0.7	57.1	81.6	0.4		
H-2276A	9/4/2025 2:35:58 PM	52.2	44.9	0.0	2.9	0.0	1.2		
H-2276A	9/18/2025 10:41:48 AM	25.8	33.2	0.1	40.9	409.0	0.8		
H-2276B	9/4/2025 3:06:24 PM	28.0	27.1	0.0	44.9	0.0	1.0		
H-2276B	9/17/2025 2:37:23 PM	24.8	28.1	0.0	47.1	0.0	0.9		
H-2276E	9/10/2025 1:38:22 PM	39.3	44.0	0.1	16.6	166.0	0.9		
H-2276W	9/2/2025 11:07:22 AM	35.7	50.6	0.0	13.7	0.0	0.7		
H-2276W	9/17/2025 9:19:50 AM	42.4	56.7	0.0	0.9	0.0	0.7		
H-2277A	9/4/2025 2:25:54 PM	41.9	57.4	0.0	0.7	0.0	0.7		
H-2277A	9/18/2025 9:22:51 AM	46.6	49.6	0.0	3.8	0.0	0.9		
H-2277B	9/3/2025 1:48:32 PM	30.8	36.8	0.0	32.4	0.0	0.8		
H-2277B	9/18/2025 8:40:52 AM	16.7	29.7	0.0	53.6	0.0	0.6		
H-23 (EXP-23)	9/22/2025 1:27:26 PM	65.2	30.2	0.0	4.6	0.0	2.2		
H-23 (EXP-23)	9/22/2025 1:28:11 PM	65.8	28.3	0.0	5.9	0.0	2.3		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
H-2301E	9/26/2025 10:18:59 AM	49.3	40.8	0.0	9.9	0.0	1.2		
H-2301E	9/28/2025 9:41:01 AM	48.0	41.3	0.0	10.7	0.0	1.2		
H-2302C	9/26/2025 10:05:25 AM	47.4	36.9	0.2	15.5	77.5	1.3		
H-2302E	9/26/2025 10:24:06 AM	54.3	41.3	0.0	4.4	0.0	1.3		
H-2303E	9/29/2025 12:23:25 PM	55.0	40.5	0.1	4.4	36.8	1.4		
H-2303N	9/24/2025 1:26:15 PM	27.8	31.6	0.0	40.6	0.0	0.9		
H-2303N	9/26/2025 10:30:36 AM	56.1	40.3	0.0	3.6	0.0	1.4		
H-2304S	9/25/2025 9:34:44 AM	39.9	39.9	0.4	19.8	49.5	1.0		
H-2304S	9/25/2025 9:36:47 AM	46.1	42.3	0.0	11.6	0.0	1.1		
H-2304S	9/28/2025 10:01:06 AM	52.9	42.9	0.0	4.2	0.0	1.2		
H-2304S	9/28/2025 10:02:10 AM	53.2	42.6	0.0	4.3	0.0	1.2		
H-2305N	9/15/2025 10:55:37 AM	37.4	36.9	0.0	25.7	0.0	1.0		
H-2305S	9/25/2025 9:23:38 AM	48.4	42.7	0.0	8.9	0.0	1.1		
H-2306N	9/25/2025 9:09:05 AM	43.9	40.3	0.0	15.8	0.0	1.1		
H-2306S	9/25/2025 10:02:00 AM	6.8	7.8	18.2	67.2	3.7	0.9		
H-2309N	9/4/2025 9:10:43 AM	45.2	46.8	0.5	7.5	15.0	1.0		
H-2309S	9/25/2025 9:44:15 AM	49.4	43.0	0.0	7.6	0.0	1.1		
H-2402N	9/24/2025 2:19:19 PM	31.5	34.2	0.0	34.3	0.0	0.9		
H-2402S	9/26/2025 9:54:58 AM	42.7	36.0	0.2	21.1	105.5	1.2		
H-2403N	9/24/2025 2:26:03 PM	30.6	30.9	4.3	34.2	8.0	1.0		
H-2403S	9/15/2025 9:46:37 AM	52.6	43.3	0.0	4.1	0.0	1.2		
H-2404N	9/24/2025 2:35:49 PM	49.6	44.3	0.0	6.1	0.0	1.1		
H-2404S	9/24/2025 1:35:09 PM	55.3	43.2	0.0	1.5	0.0	1.3		
H-2405N	9/15/2025 2:07:22 AM	23.8	39.6	0.0	36.6	0.0	0.6		
H-29	9/25/2025 11:06:12 AM	26.0	45.5	0.0	28.5	0.0	0.6		
H-31	9/26/2025 1:18:15 PM	15.0	22.5	1.3	61.2	47.1	0.7		
H-72	9/26/2025 1:36:30 PM	42.6	52.0	0.1	5.3	53.0	0.8		
H-74	9/22/2025 2:35:19 PM	52.6	42.0	0.0	5.4	0.0	1.3		
H-79	9/4/2025 2:39:10 PM	47.6	50.0	0.0	2.4	0.0	1.0		
H-79	9/4/2025 2:40:50 PM	47.7	50.9	0.0	1.4	0.0	0.9		
P-02R	9/9/2025 2:05:59 PM	20.7	29.4	0.0	49.9	0.0	0.7		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
P-02R	9/9/2025 2:06:41 PM	20.5	29.5	0.0	50.0	0.0	0.7		
P-03R	9/9/2025 1:58:57 PM	34.4	32.4	0.0	33.2	0.0	1.1		
P-04	9/9/2025 1:54:13 PM	40.5	38.8	0.0	20.7	0.0	1.0		
P-05	9/10/2025 1:07:01 PM	25.8	29.4	0.0	44.8	0.0	0.9		
P-06R	9/9/2025 2:32:42 PM	51.4	38.9	0.0	9.7	0.0	1.3		
P-07R	9/23/2025 2:25:44 PM	31.3	27.8	0.0	40.9	0.0	1.1		
P-08R	9/9/2025 2:11:47 PM	50.2	37.1	0.0	12.7	0.0	1.4		
P-09	9/9/2025 2:20:26 PM	28.0	31.8	0.0	40.2	0.0	0.9		
P-10	9/9/2025 10:10:17 AM	22.3	29.2	0.1	48.4	484.0	0.8		
P-11	9/9/2025 10:20:54 AM	30.5	32.6	0.1	36.8	368.0	0.9		
P-12	9/9/2025 10:47:34 AM	44.6	36.5	0.0	18.9	0.0	1.2		
P-13	9/9/2025 10:42:54 AM	35.7	32.6	0.0	31.7	0.0	1.1		
P-14	9/9/2025 10:33:15 AM	18.6	25.7	0.7	55.0	78.6	0.7		
P-15R	9/10/2025 10:45:32 AM	39.4	33.9	0.0	26.7	0.0	1.2		
P-16	9/23/2025 9:39:29 AM	45.9	35.4	0.0	18.7	0.0	1.3		
P-17	9/10/2025 1:19:43 PM	27.0	30.5	0.2	42.3	211.5	0.9		
P-18RD	9/10/2025 11:25:13 AM	57.4	38.9	0.1	3.6	36.0	1.5		
P-18RS	9/10/2025 11:13:40 AM	35.0	33.9	0.0	31.1	0.0	1.0		
P-19	9/23/2025 10:10:10 AM	26.5	28.9	0.0	44.6	0.0	0.9		
P-20R	9/10/2025 11:07:12 AM	39.2	35.7	0.0	25.1	0.0	1.1		
P-21	9/10/2025 11:02:39 AM	22.9	29.0	0.6	47.5	79.2	0.8		
P-21RD	9/23/2025 10:17:50 AM	34.7	33.7	0.0	31.6	0.0	1.0		
P-21RS	9/23/2025 10:13:04 AM	29.5	31.8	0.0	38.7	0.0	0.9		
P-22RD	9/23/2025 10:54:08 AM	51.7	42.2	0.0	6.1	0.0	1.2		
P-22RS	9/23/2025 10:52:10 AM	19.0	26.6	0.0	54.4	0.0	0.7		
P-23	9/10/2025 10:55:26 AM	5.9	23.2	0.9	70.0	77.8	0.3		
P-24	9/10/2025 1:30:15 PM	12.2	24.6	0.3	62.9	209.7	0.5		
P-26	9/10/2025 1:48:18 PM	41.9	35.4	0.0	22.7	0.0	1.2		
P-27	9/11/2025 1:32:24 PM	9.6	21.7	0.2	68.5	342.5	0.4		
P-28	9/11/2025 1:38:30 PM	37.6	33.8	0.0	28.6	0.0	1.1		
P-29R	9/11/2025 1:45:33 PM	32.8	32.2	0.0	35.0	0.0	1.0		
P-30R	9/11/2025 1:50:22 PM	37.1	35.8	0.0	27.1	0.0	1.0		
P-32R1	9/12/2025 1:42:57 PM	20.2	24.3	2.5	53.0	21.2	0.8		
P-32R1	9/15/2025 11:26:51 AM	15.0	19.2	4.9	60.9	12.4	0.8		
P-32R1	9/15/2025 11:28:36 AM	16.0	20.2	4.5	59.3	13.2	0.8		
P-32R2	9/12/2025 1:48:49 PM	21.9	27.9	0.9	49.3	54.8	0.8		
P-33	9/12/2025 1:59:27 PM	36.7	34.7	1.1	27.5	25.0	1.1		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
P-36	9/12/2025 2:24:21 PM	12.6	24.5	0.6	62.3	103.8	0.5		
P-37	9/12/2025 2:35:09 PM	5.1	21.0	0.6	73.3	122.2	0.2		
P-38RD	9/15/2025 2:12:37 PM	43.3	35.7	0.0	21.0	0.0	1.2		
P-38RS	9/15/2025 2:10:06 PM	36.7	34.2	0.0	29.1	0.0	1.1		
P-39	9/15/2025 2:17:59 PM	54.2	40.5	0.2	5.1	25.5	1.3		
P-41	9/15/2025 2:24:21 PM	47.2	37.7	0.2	14.9	74.5	1.3		
P-42R	9/16/2025 11:13:42 AM	50.7	39.8	0.0	9.5	0.0	1.3		
P-43	9/16/2025 11:07:52 AM	29.9	31.0	0.9	38.2	42.4	1.0		
P-44RD	9/16/2025 11:03:01 AM	47.0	35.5	0.0	17.5	0.0	1.3		
P-44RS	9/16/2025 11:01:00 AM	40.1	35.0	0.0	24.9	0.0	1.1		
P-45RD	9/16/2025 11:32:08 AM	45.0	38.2	0.0	16.8	0.0	1.2		
P-45RS	9/16/2025 11:29:26 AM	4.2	20.2	0.0	75.6	0.0	0.2		
P-46RD	9/18/2025 12:33:45 PM	49.9	36.8	0.0	13.3	0.0	1.4		
P-46RS	9/18/2025 12:31:10 PM	22.1	28.8	0.0	49.1	0.0	0.8		
P-47	9/23/2025 10:47:12 AM	9.7	20.1	2.0	68.2	34.1	0.5		
P-48	9/23/2025 11:09:02 AM	9.8	22.4	0.0	67.8	0.0	0.4		
P-49RD	9/23/2025 11:21:23 AM	51.8	37.5	0.0	10.7	0.0	1.4		
P-49RS	9/23/2025 11:18:57 AM	16.4	24.3	0.0	59.3	0.0	0.7		
P-52	9/23/2025 1:48:00 PM	20.3	26.1	0.0	53.6	0.0	0.8		
P-53	9/23/2025 1:51:50 PM	25.6	28.3	0.0	46.1	0.0	0.9		
P-54	9/23/2025 2:00:58 PM	41.6	35.9	0.0	22.5	0.0	1.2		
P-55	9/23/2025 2:03:19 PM	33.8	32.0	0.0	34.2	0.0	1.1		
P-56	9/23/2025 2:10:00 PM	18.9	25.3	0.0	55.8	0.0	0.7		
P-57	9/23/2025 2:07:49 PM	39.8	31.0	1.3	27.9	21.5	1.3		
P-60R	9/18/2025 12:57:02 PM	50.9	35.7	0.0	13.4	0.0	1.4		
P-61	9/18/2025 12:50:37 PM	37.2	33.5	0.0	29.3	0.0	1.1		
P-65	9/18/2025 12:44:48 PM	36.8	32.0	0.0	31.2	0.0	1.2		
P-71	9/23/2025 11:29:47 AM	26.3	27.6	0.0	46.1	0.0	1.0		
P-75	9/23/2025 2:18:03 PM	51.7	35.5	0.0	12.8	0.0	1.5		
P-76	9/23/2025 10:33:21 AM	16.8	25.0	0.3	57.9	193.0	0.7		
P-79	9/23/2025 9:43:35 AM	18.6	25.8	1.4	54.2	38.7	0.7		
SC-2000E	9/24/2025 10:46:30 AM	49.7	40.0	0.0	10.3	0.0	1.2		
SC-2501E	9/3/2025 9:30:42 AM	3.0	53.1	8.0	35.9	4.5	0.1		
SC-2501E	9/3/2025 9:45:00 AM							1400	
SC-2501E	9/3/2025 9:45:00 AM								93800
SC-2501E	9/5/2025 8:09:33 AM	1.4	54.8	7.9	35.9	4.5	0.0		
SC-2501E	9/5/2025 8:13:54 AM	2.1	80.2	0.3	17.4	58.0	0.0		
SC-2501E	9/9/2025 9:14:26 AM	1.9	54.1	6.7	37.3	5.6	0.0		
SC-2501E	9/9/2025 9:15:00 AM							1360	
SC-2501E	9/15/2025 9:20:39 AM	1.4	57.2	6.6	34.8	5.3	0.0		
SC-2501E	9/15/2025 9:22:00 AM							1230	

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
SC-2501E	9/15/2025 9:22:26 AM	1.5	57.6	6.5	34.4	5.3	0.0		
SC-2501E	9/22/2025 8:49:03 AM	1.0	36.3	12.1	50.6	4.2	0.0		
SC-2501E	9/29/2025 11:44:34 AM	1.7	58.2	7.8	32.3	4.1	0.0		
SC-2501W	9/3/2025 9:44:19 AM	2.7	74.2	0.8	22.3	27.9	0.0		
SC-2501W	9/3/2025 9:45:00 AM							1910	
SC-2501W	9/3/2025 9:45:00 AM								180400
SC-2501W	9/9/2025 9:40:33 AM	2.5	74.9	0.4	22.2	55.5	0.0		
SC-2501W	9/9/2025 9:42:00 AM							1355	
SC-2501W	9/15/2025 10:06:49 AM	2.2	73.9	1.4	22.5	16.1	0.0		
SC-2501W	9/15/2025 10:08:00 AM							1255	
SC-2501W	9/22/2025 9:20:28 AM	1.9	70.6	3.0	24.5	8.2	0.0		
SC-2501W	9/29/2025 2:05:42 PM	2.7	74.3	0.7	22.3	31.9	0.0		
SW-10	9/25/2025 1:59:04 PM	23.2	31.2	0.1	45.5	455.0	0.7		
SW-115	9/15/2025 1:25:47 PM	53.0	39.1	0.0	7.9	0.0	1.4		
SW-1445	9/4/2025 9:57:23 AM	3.9	5.7	15.7	74.7	4.8	0.7		
SW-1445	9/19/2025 10:26:13 AM	3.5	5.4	16.5	74.6	4.5	0.6		
SW-1455	9/4/2025 9:51:46 AM	14.4	12.4	12.5	60.7	4.9	1.2		
SW-1455	9/19/2025 10:22:21 AM	13.3	10.8	13.6	62.3	4.6	1.2		
SW-154	9/17/2025 1:54:35 PM	0.1	0.5	20.3	79.1	3.9	0.2		
SW-17-135	9/4/2025 9:54:36 AM	29.6	23.6	2.6	44.2	17.0	1.3		
SW-17-135	9/19/2025 10:24:22 AM	30.8	23.9	2.8	42.5	15.2	1.3		
SW-187	9/2/2025 1:15:10 PM	25.7	33.0	3.1	38.2	12.3	0.8		
SW-187	9/25/2025 1:44:17 PM	23.9	30.7	5.6	39.8	7.1	0.8		
SW-1930	9/4/2025 8:26:54 AM	45.2	50.7	0.0	4.1	0.0	0.9		
SW-1930	9/19/2025 9:10:49 AM	43.5	52.5	0.0	4.0	0.0	0.8		
SW-20	9/23/2025 2:29:32 PM	0.5	4.0	17.3	78.2	4.5	0.1		
SW-25	9/4/2025 8:21:56 AM	36.3	42.1	1.6	20.0	12.5	0.9		
SW-25	9/19/2025 9:15:05 AM	37.4	40.3	1.5	20.8	13.9	0.9		
SW-30	9/4/2025 9:05:50 AM	16.7	70.1	2.5	10.7	4.3	0.2		
SW-30	9/19/2025 9:57:49 AM	14.9	59.1	6.5	19.5	3.0	0.3		
SW-32	9/4/2025 9:13:29 AM	10.8	18.5	15.3	55.4	3.6	0.6		
SW-32	9/19/2025 10:01:56 AM	6.1	10.9	17.7	65.3	3.7	0.6		
SW-64	9/4/2025 9:03:50 AM	6.5	23.0	15.2	55.3	3.6	0.3		
SW-64	9/19/2025 9:55:17 AM	4.2	14.6	17.4	63.8	3.7	0.3		
SW-65	9/15/2025 1:24:13 PM	47.2	37.2	0.1	15.5	155.0	1.3		
SW-66	9/17/2025 1:51:53 PM	10.7	11.0	13.0	65.3	5.0	1.0		
SW-68	9/4/2025 9:11:40 AM	15.4	72.3	2.3	10.0	4.3	0.2		
SW-68	9/19/2025 10:00:00 AM	13.9	60.7	5.5	19.9	3.6	0.2		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CH4:CO2	CO Reading [ppmv]	H2 Reading [ppmv]
SW-7	9/4/2025 8:23:54 AM	1.9	4.9	19.0	74.2	3.9	0.4		
SW-7	9/19/2025 9:13:16 AM	1.9	7.0	18.9	72.2	3.8	0.3		
SW-70	9/2/2025 1:18:04 PM	19.5	69.6	0.6	10.3	16.1	0.3		
SW-70	9/25/2025 1:47:35 PM	19.7	66.0	0.0	14.3	0.0	0.3		
SW-71	9/10/2025 1:36:10 PM	9.5	18.7	3.3	68.5	20.8	0.5		
SW-72	9/12/2025 2:04:39 PM	24.3	26.0	3.1	46.6	15.0	0.9		
SW-80	9/17/2025 10:58:29 AM	34.6	28.7	0.1	36.6	366.0	1.2		
SW-9	9/2/2025 1:20:48 PM	1.7	26.8	7.7	63.9	8.3	0.1		
SW-9	9/25/2025 1:51:45 PM	1.5	23.2	9.7	65.6	6.8	0.1		
TC-1961C	9/10/2025 11:16:06 AM	10.4	29.4	0.0	60.2	0.0	0.4		
TC-1961E	9/4/2025 2:56:15 PM	50.7	45.3	0.0	4.0	0.0	1.1		
TC-2174	9/3/2025 9:13:40 AM	2.7	78.9	0.2	18.2	91.0	0.0		
TC-2174	9/3/2025 9:14:00 AM							2080	
TC-2174	9/3/2025 9:14:00 AM								122500
TC-2174	9/3/2025 9:14:00 AM								122500
TC-2174	9/9/2025 8:57:46 AM	2.8	89.9	0.0	7.3	0.0	0.0		
TC-2174	9/9/2025 9:00:00 AM							1630	
TC-2174	9/15/2025 9:03:55 AM	2.8	80.5	0.1	16.6	166.0	0.0		
TC-2174	9/15/2025 9:06:00 AM							1820	
TC-2174	9/22/2025 8:32:49 AM	2.5	72.0	2.0	23.5	11.8	0.0		
TC-2174	9/29/2025 11:30:06 AM	3.4	77.0	1.3	18.3	14.1	0.0		
VL-02	9/26/2025 2:03:23 PM	59.9	38.1	0.0	2.0	0.0	1.6		

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
A-01	9/11/2025 10:42:03 AM	86.9	86.9	-15.10	-15.17	15.301	15.314			-14.82	-14.82
A-01	9/15/2025 12:58:22 PM	97.9	97.9	-16.98	-16.97	17.122	17.121			-16.70	-16.70
A-02	9/11/2025 10:49:23 AM	106.5	106.6	-14.87	-14.86	15.079	15.079			0.34	0.34
A-03	9/11/2025 10:53:20 AM	92.4	92.4	-14.53	-14.53	14.646	14.641			0.35	0.42
A-04	9/11/2025 10:55:43 AM	96.0	96.0	-8.86	-8.87	9.083	9.219			0.34	0.34
A-05	9/15/2025 1:11:50 PM	107.3	107.6	-15.70	-15.69	15.774	15.759			0.09	0.06
B-01	9/2/2025 1:15:34 PM	102.4	102.7	-0.36	-0.20	0.438	0.140	1.3	0.7	-11.13	-11.11
B-02R	9/2/2025 1:20:45 PM	96.0	95.9	-0.29	-0.30	0.013	0.012	0.4	0.3	-10.89	-10.93
B-03R	9/2/2025 1:33:42 PM	106.5	106.5	-0.14	-0.14	0.089	0.089	0.9	0.9	-9.31	-9.32
B-05	9/2/2025 2:00:24 PM	101.4	101.2	-0.10	-0.09	5.288	5.334	7.1	7.1	-9.38	-9.55
B-06	9/2/2025 2:11:06 PM	96.5	92.4	0.08	-0.08	0.000	0.000			-9.21	-9.03
B-06	9/2/2025 2:11:59 PM	92.3	92.2	-0.09	-0.09	0.000	0.000			-9.00	-9.00
B-07R	9/8/2025 1:40:51 PM	101.0	100.8	-0.20	-0.20	0.507	0.517	2.2	2.2	-9.26	-9.40
B-08	9/2/2025 2:26:34 PM	101.5	101.5	-0.08	-0.08	0.063	0.059			-9.00	-9.09
B-09	9/8/2025 1:35:36 PM	106.3	106.3	-0.36	-0.35	0.336	0.334			-9.47	-9.53
B-10	9/2/2025 2:32:34 PM	101.0	101.0	-0.32	-0.13	0.300	0.120			-8.33	-7.74
B-11	9/8/2025 1:56:06 PM	113.8	113.8	-0.27	-0.27	0.000	0.000			-9.75	-9.75
B-12	9/2/2025 1:41:34 PM	98.4	98.4	-0.22	-0.22	3.583	3.617	5.8	5.9	-9.27	-9.42
B-13	9/8/2025 1:45:02 PM	95.6	96.0	-0.10	-0.10	0.026	0.024	11.3	10.9	-10.82	-10.91
B-14	9/8/2025 2:00:18 PM	111.8	112.0	-0.13	-0.13	0.272	0.278	1.6	1.6	-9.65	-9.61
C-03	9/11/2025 10:44:49 AM	100.1	101.0	-13.94	-13.94	14.198	14.192			0.37	0.38
C-07	9/26/2025 1:08:23 PM	86.7	87.0	-13.13	-13.13	13.291	13.294			-0.03	-0.02
C-08	9/25/2025 2:18:07 PM	97.8	98.7	-12.44	-12.20	12.354	12.253			-12.17	-12.12
C-10	9/15/2025 1:20:04 PM	118.1	118.7	-13.76	-13.80	13.931	13.877	45.5	45.4	-0.02	-0.02
C-11	9/15/2025 1:34:37 PM	101.7	101.9	-12.51	-12.51	0.095	0.093			-12.55	-12.56
C-12	9/10/2025 10:18:50 AM	88.3	88.1	-9.06	-9.06	0.010	0.032	1.3	2.3	-8.98	-9.02
C-12	9/15/2025 1:42:47 PM	97.5	97.7	-9.40	-9.40	0.103	0.149	4.1	4.9	-9.20	-9.39
C-15	9/10/2025 10:26:52 AM	86.4	86.4	-8.85	-8.79	0.003	0.025	1.1	3.3	-8.75	-8.75
C-15	9/15/2025 1:46:38 PM	104.6	104.6	-9.28	-9.26	0.070	0.070	5.5	5.5	-9.06	-9.06
C-17B	9/22/2025 11:09:30 AM	110.3	110.3	-6.93	-6.92	6.914	6.896			-8.11	-8.07
C-18	9/25/2025 2:18:43 PM	100.7	100.9	-7.26	-7.26	7.129	7.031			-7.15	-7.07
C-19	9/22/2025 11:23:57 AM	105.0	105.2	-7.57	-7.59	7.631	7.635			-8.29	-8.24
C-20	9/25/2025 2:27:31 PM	98.5	100.0	-7.34	-7.28	7.148	7.080			-7.28	-7.26
C-23	9/25/2025 2:22:36 PM	111.9	112.0	-7.14	-7.06	6.969	6.845			0.03	0.00
C-24	9/22/2025 11:21:21 AM	109.9	109.9	-4.07	-1.11	4.078	1.989			-8.25	-8.38

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
C-25	9/15/2025 2:05:56 PM	126.0	126.0	-3.63	-3.71	3.638	3.706			-8.37	-8.23
C-26	9/15/2025 1:59:34 PM	121.7	123.1	-8.72	-8.73	8.824	8.858			-8.72	-8.72
C-27	9/10/2025 10:22:35 AM	100.0	100.0	-7.68	-7.72	0.056	0.092			-8.76	-8.75
C-28	9/15/2025 1:37:08 PM	108.2	108.7	-12.49	-12.46	0.113	0.112			-12.40	-12.40
C-29	9/15/2025 1:27:37 PM	113.3	113.3	-11.08	-11.07	11.222	11.220			-13.58	-13.53
C-30	9/25/2025 2:14:01 PM	127.7	127.7	-0.16	-0.15	0.015	0.014	1.5	1.5	-11.69	-11.63
CV-02	9/11/2025 10:16:16 AM	130.1	130.3	-2.04	-2.12	0.086	0.148	0.9	1.2	-12.96	-12.93
CV-02	9/11/2025 10:17:03 AM	130.1	129.6	-2.07	-1.60	0.115	0.080	1.0	0.9	-13.02	-12.94
CV-03	9/11/2025 10:13:17 AM	119.3	119.2	-5.87	-5.95	2.271	2.295	18.8	18.9	-13.12	-12.97
CV-04	9/11/2025 10:09:39 AM	110.0	111.0	-2.38	-2.37	2.310	2.294	104.8	104.4	-13.08	-12.54
CV-05	9/11/2025 10:06:21 AM	85.2	86.3	-14.25	-14.32	0.051	0.035	1.6	1.3	-14.05	-14.16
CV-06	9/11/2025 11:02:54 AM	83.3	83.3	-2.17	-2.10	0.011	0.004	1.3	0.8	-11.12	-11.12
CV-09	9/11/2025 11:17:07 AM	91.5	91.6	0.03	0.03	0.007	0.004	1.7	1.3	0.55	0.49
CV-108-52	9/2/2025 10:35:26 AM	122.4	122.3	-1.41	-1.42	0.038	0.030			-6.54	-6.63
CV-108-52	9/10/2025 10:00:00 AM										
CV-108-52	9/10/2025 10:00:00 AM										
CV-108-52	9/17/2025 8:58:55 AM	121.7	121.4	-1.92	-1.74	0.017	0.014			-8.28	-8.73
CV-113	9/2/2025 9:40:00 AM										
CV-113	9/2/2025 9:40:00 AM										
CV-113	9/3/2025 9:08:14 AM	181.0	181.0	-2.26	-1.74	2.211	2.078	39.1	37.9	0.34	0.34
CV-113	9/3/2025 9:13:00 AM										
CV-113	9/3/2025 9:13:00 AM										
CV-113	9/9/2025 8:53:00 AM										
CV-113	9/9/2025 8:54:45 AM	183.1	183.1	-3.12	-3.43	0.167	0.002	10.7	1.0	0.34	0.34
CV-113	9/15/2025 8:58:37 AM	165.0	168.6	-5.32	-5.87	5.530	6.054			0.08	0.01
CV-113	9/15/2025 9:03:00 AM										
CV-113	9/22/2025 8:29:56 AM	185.2	185.1	-4.61	-4.34	4.523	4.386			0.01	0.01
CV-113	9/29/2025 11:25:43 AM	177.5	177.0	-2.21	-1.06	2.146	1.014			0.69	0.74
CV-114	9/11/2025 8:55:00 AM										
CV-114	9/11/2025 8:55:00 AM										
CV-1424	9/3/2025 10:36:01 AM	120.8	120.1	-4.56	-3.14	0.257	0.020	6.3	1.8	-4.98	-4.85
CV-1532A	9/4/2025 9:18:52 AM	173.7	179.2	-4.61	-4.36	3.775	3.892			0.34	0.33
CV-1532A	9/4/2025 9:20:00 AM										
CV-1532A	9/4/2025 9:20:00 AM										

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-1532A	9/10/2025 10:10:00 AM										
CV-1532A	9/10/2025 10:10:00 AM										
CV-1532A	9/10/2025 11:02:22 AM	178.4	178.6	-6.78	-5.33	6.565	6.097	0.0	0.0	-6.62	
CV-1532A	9/10/2025 11:04:00 AM										
CV-1532A	9/12/2025 2:19:15 PM	175.9	179.8	-7.26	-7.41	7.597	7.755			0.51	0.53
CV-1532A	9/18/2025 10:36:35 AM	170.1	165.5	-9.30	-9.46	9.039	9.176			-0.84	-0.84
CV-1532A	9/24/2025 9:41:10 AM	178.0	182.0	-7.88	-7.32	8.262	4.918			0.50	0.51
CV-1534A-PLR	9/5/2025 7:38:51 AM	197.6	197.4	2.34	2.10	0.000	0.000			0.02	0.03
CV-1534A-PLR	9/5/2025 7:40:00 AM										
CV-1534A-PLR	9/5/2025 7:40:00 AM										
CV-1534A-PLR	9/10/2025 11:21:04 AM	184.0	184.0	25.27	20.30			0.0	0.0	15.88	
CV-1534A-PLR	9/10/2025 11:22:00 AM										
CV-1534A-PLR	9/18/2025 9:25:06 AM	197.7	198.1	3.70	7.38	0.000	0.000			-0.51	-0.51
CV-1534A-PLR	9/24/2025 9:23:39 AM	197.7	197.7	3.44	3.66	0.000	0.000			0.49	0.48
CV-1535	9/2/2025 10:32:14 AM	120.5	120.8	-0.61	-0.60	0.126	0.117			-4.02	-3.93
CV-1535	9/9/2025 9:00:00 AM										
CV-1535	9/9/2025 9:00:00 AM										
CV-1535	9/17/2025 8:55:16 AM	122.3	122.2	-1.00	-0.87	0.021	0.344			-8.65	-8.11
CV-1601D	9/4/2025 9:21:21 AM	111.7	111.7	-0.49	-0.49	5.449	5.451	7.0	7.0	-9.03	
CV-1601D	9/17/2025 10:18:46 AM	114.6	114.7	-0.64	-0.64	6.631	6.691	5.0	5.0	-10.95	-11.04
CV-1601S	9/4/2025 9:15:43 AM	108.7	108.7	-0.76	-0.71	1.524	1.201	8.3	7.3	-9.23	
CV-1601S	9/17/2025 10:16:46 AM	111.5	111.6	-0.88	-0.79	1.361	0.991	14.7	12.5	-11.41	-11.32
CV-1604	9/10/2025 11:04:29 AM	129.8	129.6	-2.20	-2.20	0.326	0.329	3.9	3.9	-14.48	-14.55
CV-1605	9/5/2025 1:57:42 PM	105.2	105.1	-6.55	-6.59	0.057	0.057	0.5	0.5	-9.46	
CV-1701D	9/4/2025 2:27:54 PM	129.1	128.7	-0.97	-0.33	0.214	0.505	0.9	1.4	-8.58	-8.74
CV-1701S	9/4/2025 2:25:05 PM	129.4	129.9	-0.07	-0.10	0.169	0.072	5.1	3.3	-9.84	-9.77
CV-1901	9/9/2025 9:32:11 AM										
CV-1901	9/10/2025 9:59:41 AM	111.7	111.8	-3.23	-3.27	0.759	2.274	10.9	18.9	-9.85	-9.98
CV-1901	9/17/2025 8:51:25 AM	116.0	116.2	-2.64	-2.64	1.500	1.539	15.3	15.5	-10.20	-10.81

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-1902A	9/4/2025 8:41:25 AM	181.9	182.2	-0.95	-0.97	0.952	0.987			-7.08	-6.95
CV-1902A	9/4/2025 8:45:00 AM										
CV-1902A	9/4/2025 8:45:00 AM										
CV-1902A	9/9/2025 8:45:00 AM										
CV-1902A	9/9/2025 8:45:00 AM										
CV-1902A	9/10/2025 10:11:35 AM	161.4	161.7	-1.57	-1.58	1.724	1.676	0.0	0.0	-8.76	
CV-1902A	9/10/2025 10:13:00 AM										
CV-1902A	9/18/2025 8:46:48 AM	169.1	168.8	-2.61	-2.62	2.571	2.689			-7.08	-7.20
CV-1902A	9/24/2025 11:10:16 AM	182.7	183.7	-1.88	-1.97	1.783	1.889			-7.07	-7.08
CV-1903	9/5/2025 9:04:43 AM	109.3	109.3	-0.31	-0.30	0.037	0.039	0.6	0.6	-8.46	-8.70
CV-1903	9/9/2025 9:37:05 AM										
CV-1903	9/16/2025 9:01:06 AM	107.5	107.5	-0.33	-0.33	0.005	0.011	0.2	0.3	-8.26	-8.64
CV-1903	9/18/2025 1:34:31 PM	109.4	125.1	-0.32	-0.32	1.334	1.342	3.5	3.5	-7.81	-7.51
CV-1905	9/9/2025 10:52:49 AM	112.9	113.3	-3.61	-4.13	0.081	0.612	3.6	9.8	-12.62	-12.61
CV-2001	9/2/2025 2:14:25 PM	114.9	116.1	-0.62	-0.30	0.106	0.092	9.1	8.4	-2.29	-2.26
CV-2001	9/8/2025 9:00:00 AM										
CV-2001	9/8/2025 9:00:00 AM										
CV-2001	9/8/2025 9:26:03 AM	100.5	99.1	-3.22	-3.13	0.047	0.070	6.1	7.5	-4.42	-4.25
CV-2001	9/8/2025 9:33:34 AM	100.1	102.7	-0.57	-0.57	0.036	0.036	5.3	5.3	-4.21	-4.21
CV-2001	9/17/2025 10:35:12 AM	116.0	106.8	-2.80	-2.16	0.112	0.197	9.3	12.4	-2.51	-2.79
CV-2002	9/2/2025 2:29:12 PM	128.2	127.7	-0.22	-0.29	0.026	0.023	9.9	9.3	0.01	0.01
CV-2002	9/4/2025 9:55:00 AM										
CV-2002	9/4/2025 9:55:00 AM										
CV-2002	9/17/2025 10:59:06 AM	123.5	124.1	0.66	0.33	0.000	0.000			1.01	-0.24
CV-2002	9/17/2025 11:00:32 AM	124.4	124.3	0.61	0.74	0.000	0.000			1.01	0.68
CV-2003	9/2/2025 10:42:09 AM	126.3	126.4	-0.30	-0.32	0.319	0.318	1.7	1.7	-7.19	-7.17
CV-2003	9/17/2025 9:01:22 AM	126.3	127.0	-0.37	-0.39	1.241	0.047	3.4	0.7	-8.33	-8.24
CV-2006	9/4/2025 8:25:11 AM	187.0		-3.83		1.117		27.6		-8.99	
CV-2006	9/4/2025 8:28:00 AM										
CV-2006	9/4/2025 8:28:00 AM										
CV-2006	9/10/2025 10:29:29 AM	185.4	185.4	-4.11	-1.89	0.135	0.375	8.7	14.6	-3.41	
CV-2006	9/10/2025 10:32:00 AM										
CV-2006	9/18/2025 8:04:41 AM	186.8	186.6	-8.65	-8.87	4.811	4.265	56.6	53.3	-9.62	-9.56
CV-2006	9/24/2025 10:41:53 AM	187.1	187.1	-2.48	-2.49	0.719	0.624	22.2	20.7	-9.94	-9.78
CV-2007	9/2/2025 1:44:21 PM	110.2	110.2	-0.10	-0.11	0.088	0.105	11.9	13.0	-8.10	-8.08
CV-2007	9/3/2025 9:40:00 AM										
CV-2007	9/3/2025 9:40:00 AM										
CV-2008	9/2/2025 1:51:51 PM	126.7	126.9	-0.10	-0.12	0.126	0.127	9.9	10.0	-8.33	-8.14
CV-2008	9/10/2025 10:51:30 AM	117.6	116.1	-4.23	-2.50	0.075	0.063	7.7	7.1	-10.01	-10.72

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2008	9/10/2025 10:53:39 AM	117.4	117.5	-2.20	-2.21	0.034	0.034	5.2	5.2	-10.60	-10.63
CV-2009	9/2/2025 2:09:17 PM	135.0	135.2	-0.29	-0.20	0.178	0.182	11.5	11.7	-8.33	-8.32
CV-2009	9/2/2025 2:10:23 PM	135.2	135.2	-0.19	-0.17	0.105	0.148	8.9	10.5	-8.38	-8.37
CV-2009A	9/3/2025 9:44:32 AM	129.9	129.8	-2.38	-2.08	1.026	0.698	12.5	10.3	-8.89	-9.08
CV-2009A	9/9/2025 11:06:16 AM										
CV-2010	9/9/2025 1:47:09 PM	99.4	100.7	-2.40	-2.40	0.011	0.003	2.9	1.6	-9.86	-9.87
CV-2010A	9/9/2025 1:43:50 PM	138.3	138.2	-5.26	-5.27	1.189	1.202	20.4	20.5	-9.99	-10.00
CV-2010A	9/12/2025 1:41:53 PM	137.1	134.0	-5.37	-3.07	0.896	0.086	17.7	5.5	-9.58	-9.43
CV-2010A	9/12/2025 1:43:56 PM	132.3	132.0	-2.30	-2.29	0.081	0.072	5.4	5.1	-9.44	-9.53
CV-2011	9/4/2025 2:10:02 PM	124.2	124.6	-0.46	-0.45	0.197	0.180	12.2	11.7	-9.53	-9.52
CV-2011A	9/2/2025 10:00:00 AM										
CV-2011A	9/2/2025 10:02:07 AM	151.9	151.9	-3.19	-3.20	0.251	0.241	30.1	29.5	-9.52	-9.56
CV-2011A	9/8/2025 10:08:08 AM	152.2	151.7	-3.96	-2.01	0.130	0.050	4.4	2.7	-10.45	-10.72
CV-2011A	9/8/2025 10:10:00 AM										
CV-2011A	9/18/2025 6:45:46 AM	150.4	150.4	-1.15	-1.15	0.104	0.104	19.4	19.4	-14.54	-14.51
CV-2011A	9/22/2025 1:42:17 PM	149.9	150.1	-0.56	-0.56	0.480	0.475	41.7	41.5	-10.33	-10.42
CV-2011A	9/29/2025 8:15:34 AM	148.3	148.5	-1.38	-1.38	0.106	0.109	19.6	19.9	-10.51	-10.47
CV-2012	9/4/2025 1:45:24 PM	140.2	139.2	-5.90	-0.15	0.417	0.137	17.4	10.1	-9.21	-9.47
CV-2012	9/4/2025 1:46:31 PM	139.3	139.2	-0.19	-0.19	0.140	0.147	10.2	10.4	-9.55	-9.41
CV-2201-PLR	9/4/2025 6:42:47 AM	184.5	185.7	-10.39	-10.30	10.461	10.408			-10.41	-10.54
CV-2201-PLR	9/4/2025 6:45:00 AM										
CV-2201-PLR	9/4/2025 6:45:00 AM										
CV-2201-PLR	9/9/2025 10:31:01 AM	190.7	191.2	-9.79	-9.48	10.279	9.964			-8.87	-8.78
CV-2201-PLR	9/9/2025 10:32:00 AM										
CV-2201-PLR	9/17/2025 10:57:30 AM	195.2	195.5	-8.45	-8.42	8.910	8.819			0.64	0.64
CV-2201-PLR	9/23/2025 9:21:57 AM	195.9	196.2	-12.89	-12.98	13.100	13.177			0.45	0.43
CV-2201-PLR	9/30/2025 9:14:55 AM	196.1	193.0	-9.78	-0.96	10.045	0.972			-9.69	-9.65
CV-2204-PLR	9/2/2025 10:54:31 AM	191.7	191.8	-5.11	-5.23	5.382	5.521			0.31	0.30
CV-2204-PLR	9/2/2025 10:59:00 AM										
CV-2204-PLR	9/2/2025 10:59:00 AM										

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2204-PLR	9/8/2025 8:50:08 AM	191.1	191.1	-7.44	-7.44	7.683	7.702			0.32	0.32
CV-2204-PLR	9/8/2025 8:52:00 AM										
CV-2204-PLR	9/15/2025 11:40:53 AM	190.5	190.4	-9.77	-9.67	10.272	10.074			0.95	0.99
CV-2204-PLR	9/15/2025 11:42:00 AM										
CV-2204-PLR	9/22/2025 11:03:04 AM	190.6	190.6	-7.90	-7.86	9.051	9.034			0.68	0.68
CV-2204-PLR	9/29/2025 9:52:43 AM	190.9	190.6	-3.68	-3.68	3.612	3.647			0.67	0.66
CV-2205	9/9/2025 2:06:11 PM	133.3	132.6	-1.10	-0.74	0.043	0.144	12.8	23.4	-10.38	-10.35
CV-2206-PLR	9/10/2025 9:20:31 AM	76.8	76.8	-11.29	-11.32	11.212	11.278			-11.33	-11.36
CV-2206-PLR	9/10/2025 9:21:33 AM	76.8	76.8	-11.16	-11.41	11.115	11.335			-11.07	-11.42
CV-2206-PLR	9/23/2025 9:31:55 AM	94.6	94.7	-13.14	-13.37	13.513	13.665			0.61	0.62
CV-2207	9/3/2025 9:55:10 AM	127.4	128.1	-0.47	-0.75	0.004	0.029	3.8	10.6	-9.41	-9.42
CV-2207	9/9/2025 10:21:32 AM										
CV-2208A	9/2/2025 10:14:04 AM	155.4	155.3	-1.27	-1.25	0.032	0.042	10.8	12.4	-8.74	-8.78
CV-2208A	9/2/2025 10:15:00 AM										
CV-2208A	9/8/2025 8:21:14 AM	155.0	153.4	-1.55	-0.45	0.037	0.023	11.6	9.2	-10.82	-10.78
CV-2208A	9/8/2025 8:25:00 AM										
CV-2208A	9/15/2025 8:11:31 AM	154.7	154.8	-3.13	-3.12	7.627	7.287	164.1	160.4	-3.10	-3.08
CV-2208A	9/15/2025 8:42:00 AM										
CV-2208A	9/22/2025 8:13:27 AM	154.4	154.5	-2.35	-2.34	0.120	0.138	20.8	22.3	-9.89	-10.04
CV-2208A	9/29/2025 8:41:20 AM	153.8	154.0	-1.34	-1.32	0.041	0.043	12.3	12.5	-7.49	-7.33
CV-2301	9/3/2025 9:44:41 AM	116.9	108.5	-5.30	-0.35	5.335	0.355			-5.98	-7.70
CV-2301	9/4/2025 10:47:00 AM	185.0	102.4	-0.95	-0.86	0.936	0.856			-6.08	-5.90
CV-2301	9/10/2025 9:20:00 AM										
CV-2301	9/10/2025 9:20:00 AM										
CV-2301	9/11/2025 10:20:00 AM										
CV-2301	9/11/2025 10:21:11 AM	181.0	181.0	-2.67	-2.58	2.659	2.570			-6.94	-6.85
CV-2301	9/17/2025 9:47:54 AM	185.2	185.3	-3.28	-3.29	3.264	3.276			-8.38	-8.47
CV-2301	9/24/2025 2:06:26 PM	183.3	182.8	-6.84	-6.84	7.009	6.998			-0.05	-0.09
CV-2302	9/3/2025 10:01:02 AM	117.6	117.8	-3.39	-2.08	3.437	2.086			-3.71	-3.08
CV-2302	9/10/2025 9:15:00 AM										
CV-2302	9/10/2025 9:15:00 AM										

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init °F Temp [ ]	Adj °F Temp [ ]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2302	9/16/2025 2:11:57 PM	117.8	117.6	-2.66	-2.91	2.585	2.863			-4.88	-4.71
CV-2303	9/3/2025 1:59:37 PM	187.4	187.5	-5.81	-5.94	5.679	5.740			-0.03	-0.06
CV-2303	9/3/2025 2:05:00 PM										
CV-2303	9/3/2025 2:05:00 PM										
CV-2303	9/9/2025 1:42:11 PM	185.1	185.1	-7.26	-7.25	7.362	7.279			0.00	0.00
CV-2303	9/9/2025 1:43:00 PM										
CV-2303	9/11/2025 8:05:00 AM										
CV-2303	9/11/2025 8:05:00 AM										
CV-2303	9/16/2025 11:08:40 AM	189.3	189.5	-10.43	-10.47	10.817	10.862			0.60	0.60
CV-2303	9/16/2025 11:10:00 AM										
CV-2303	9/23/2025 9:07:14 AM	187.8	187.8	-11.00	-10.94	11.322	11.193			0.35	0.35
CV-2303	9/30/2025 9:44:00 AM	186.0	186.1	-7.97	-7.98	8.274	8.357			0.45	0.44
CV-2304	9/8/2025 8:21:49 AM	142.0	142.0	16.88	16.41	0.000	0.000			-0.04	-0.04
CV-2304	9/16/2025 11:05:57 AM	154.0	154.0	16.28	15.89	0.000	0.000			0.88	0.94
CV-2304	9/16/2025 2:04:00 PM										
CV-2304	9/23/2025 10:49:37 AM	160.0	159.7	11.96	12.56	0.000	0.000			0.69	0.69
CV-2305	9/3/2025 10:30:00 AM										
CV-2305	9/3/2025 10:30:00 AM										
CV-2305	9/9/2025 12:59:25 PM	136.8	137.0	-1.21	-0.88	0.985	0.771	60.8	53.8	-8.07	-7.20
CV-2305	9/9/2025 1:17:51 PM	137.7	136.5	-0.80	-1.17	0.757	0.983	53.3	60.7	-9.15	-8.91
CV-2305	9/26/2025 2:20:50 PM	129.8	129.6	-1.40	-0.85	0.659	0.394	31.8	24.6	-7.80	-7.90
CV-2306	9/2/2025 10:51:19 AM	189.0	189.0	-1.60	-1.47	1.541	1.238			0.33	0.32
CV-2306	9/2/2025 10:55:00 AM										
CV-2306	9/2/2025 10:55:00 AM										
CV-2306	9/8/2025 8:57:45 AM	190.0	190.0	-3.47	-3.53	3.116	3.442			0.31	0.32
CV-2306	9/8/2025 8:58:00 AM										
CV-2306	9/15/2025 11:35:00 AM										
CV-2306	9/15/2025 11:35:10 AM	185.0	185.0	-5.30	-4.53	5.673	3.962			0.71	0.70
CV-2306	9/22/2025 11:07:37 AM	189.0	189.0	-6.02	-6.35	6.785	7.076			0.68	0.68
CV-2306	9/29/2025 10:02:52 AM	184.0	184.0	-8.23	-8.31	8.660	8.734			0.66	0.66
CV-2308-PLR	9/4/2025 7:55:00 AM										
CV-2308-PLR	9/4/2025 7:55:00 AM										
CV-2308-PLR	9/4/2025 7:56:04 AM	157.5	158.0	-7.32	-7.60	4.810	4.810			0.00	0.00

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2308-PLR	9/9/2025 10:36:09 AM	161.6	161.7	-8.90	-9.14	9.367	9.606			0.67	0.67
CV-2308-PLR	9/9/2025 10:38:00 AM										
CV-2308-PLR	9/17/2025 10:54:00 AM	176.7	176.1	-7.80	-7.74	8.199	8.132			0.64	0.64
CV-2308-PLR	9/23/2025 9:25:08 AM	171.5	171.6	-12.73	-12.73	13.214	13.194			0.53	0.55
CV-2308-PLR	9/30/2025 9:22:24 AM	174.0	174.5	-3.97	-3.85	3.951	3.835			0.35	0.34
CV-2310-PLR	9/4/2025 6:34:32 AM	221.0	71.9	2.35	1.48	0.000	0.000			0.00	0.00
CV-2310-PLR	9/4/2025 6:35:00 AM										
CV-2310-PLR	9/4/2025 6:35:00 AM										
CV-2310-PLR	9/9/2025 2:18:16 PM	223.0		-0.60		0.602				0.01	
CV-2310-PLR	9/9/2025 2:20:00 PM										
CV-2310-PLR	9/17/2025 11:14:27 AM	189.8	190.0	-10.44	-10.49	10.936	10.969			0.64	0.64
CV-2310-PLR	9/23/2025 9:18:29 AM	186.4	186.3	-12.82	-12.75	13.305	13.270			0.35	0.35
CV-2310-PLR	9/30/2025 9:32:33 AM	183.3	183.3	-8.72	-8.80	9.109	9.182			0.38	0.43
CV-2311	9/3/2025 10:21:35 AM	178.2	178.0	-2.90	-2.88	2.772	2.786			-0.38	-0.23
CV-2311	9/3/2025 10:22:00 AM										
CV-2311	9/3/2025 10:22:00 AM										
CV-2311	9/8/2025 11:02:28 AM	176.2	176.9	-2.75	-2.39	2.760	2.399			-6.09	-6.13
CV-2311	9/8/2025 11:08:00 AM										
CV-2311	9/16/2025 9:30:00 AM										
CV-2311	9/16/2025 9:33:42 AM	176.7	176.7	-4.30	-3.74	4.254	3.708			-6.97	-6.99
CV-2311	9/23/2025 7:59:37 AM	181.0	181.0	-7.59	-7.45	7.898	7.742			0.02	0.02
CV-2311	9/30/2025 10:45:24 AM	181.0	75.1	-5.73	-5.89	6.054	6.175			0.52	0.52
CV-2312	9/15/2025 8:00:00 AM										
CV-2312	9/15/2025 8:25:00 AM										
CV-2312	9/15/2025 9:23:42 AM	154.0	153.5	-4.13	-1.93	0.341	0.127	34.9	21.4	-9.00	-9.70
CV-2312	9/15/2025 9:31:05 AM	152.5	151.9	-1.96	-0.87	1.224	0.508	20.6	13.3	-13.37	-13.96
CV-2312	9/17/2025 8:48:14 AM	153.8	153.7	-1.59	-1.58	0.896	0.915	56.8	57.4	-11.42	-11.37

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2312	9/25/2025 10:07:46 AM	157.0	156.6	-1.92	-1.66	2.987	2.906	103.2	101.8	-9.99	-10.05
CV-2312	9/30/2025 1:37:00 PM										
CV-2314	9/11/2025 8:25:00 AM										
CV-2314	9/11/2025 8:25:00 AM										
CV-2314	9/11/2025 9:43:41 AM	144.9	144.9	-0.17	-0.16	0.407	0.418	38.6	39.2	-10.29	-10.20
CV-2314	9/11/2025 9:45:27 AM	144.9	144.9	-0.14	-0.04	0.675	0.596	31.8	29.9	-10.25	-10.20
CV-2314	9/11/2025 9:49:46 AM	144.9	144.9	-0.05	-0.05	0.371	0.373	36.9	37.0	-10.47	-10.24
CV-2314	9/11/2025 11:09:14 AM	144.7	144.7	0.06	-0.05	0.238	0.148	29.6	23.3	-9.36	-9.33
CV-2314	9/11/2025 11:11:40 AM	144.5	144.8	-0.02	-0.04	0.037	0.027	11.6	10.0	-9.29	-9.30
CV-2314	9/19/2025 11:09:06 AM	144.0	144.3	-0.24	-0.08	0.259	0.083	30.8	17.4	-0.74	-0.73
CV-2314	9/19/2025 11:10:00 AM	144.2	144.5	-0.09	-0.06	0.104	0.071	19.5	16.1	-0.75	-0.69
CV-2315	9/2/2025 11:00:49 AM	164.1	163.9	-0.88	-0.97	0.259	0.196	30.7	26.7	-3.58	-3.71
CV-2315	9/2/2025 11:04:00 AM										
CV-2315	9/2/2025 11:04:00 AM										
CV-2315	9/3/2025 10:40:00 AM										
CV-2315	9/3/2025 10:40:00 AM										
CV-2315	9/10/2025 2:14:09 PM	162.5	162.5	-2.98	-2.96	2.905	2.903	0.0	0.0		
CV-2315	9/10/2025 2:17:00 PM										
CV-2315	9/12/2025 1:44:21 PM	164.3	164.4	-1.21	-1.21	0.041	0.036	12.1	11.4	-4.29	-4.37
CV-2315	9/17/2025 6:55:43 AM	157.0	157.0	-2.59	-2.49	0.072	0.079	16.2	16.9	-5.03	-4.80
CV-2315	9/25/2025 9:01:33 AM	164.6	164.6	-3.58	-3.59	0.033	0.039	10.8	11.9	-8.31	-8.14
CV-2316	9/2/2025 11:09:20 AM	133.0	135.1	-0.08	-0.08	0.092	0.073	11.9	10.6	-7.57	-7.90
CV-2316	9/9/2025 10:53:03 AM										
CV-2319	9/2/2025 11:21:07 AM	139.6	139.6	-0.45	-0.44	0.446	0.387	40.6	37.8	-7.50	-7.36
CV-2319	9/5/2025 1:28:24 PM	138.2	138.2	-0.36	-0.37	0.389	0.357	37.9	36.3	-8.44	-8.73
CV-2319	9/5/2025 1:29:22 PM	138.2	138.2	-0.39	-0.39	0.413	0.418	39.0	39.2	-8.34	-8.36
CV-2321	9/3/2025 11:04:43 AM	139.9	139.3	-1.39	-0.09	0.006	0.003	3.0	2.0	-8.62	-8.89
CV-2321	9/11/2025 1:20:09 PM	140.3	141.8	-0.04	-0.06	0.360	0.692	23.3	32.2	-10.78	-9.13
CV-2321	9/11/2025 1:21:13 PM	142.3	142.3	-0.07	-0.07	0.965	0.943	38.0	37.6	-9.09	-9.00
CV-2322	9/8/2025 2:08:07 PM	101.7	101.8	-8.43	-8.49	8.571	8.641			0.33	0.34
CV-2322	9/16/2025 1:43:01 PM	116.6	116.8	-9.66	-10.02	9.895	10.170			0.66	0.65
CV-2324	9/3/2025 10:22:37 AM	126.3		-1.32		0.224		18.6		-8.98	

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2324	9/9/2025 1:52:48 PM	125.0	125.0	-1.24	-1.13	0.355	0.197	23.3	17.4	-10.35	-9.77
CV-2326	9/5/2025 9:23:50 AM	123.0	123.0	-10.73	-10.67	10.886	10.836			0.73	0.72
CV-2326	9/16/2025 9:11:07 AM	121.0	121.0	-11.19	-10.79	11.440	10.862			0.26	0.29
CV-2326	9/18/2025 2:23:16 PM	100.0	100.0	-0.88	-0.90	0.875	0.896			-7.69	-7.84
CV-2327	9/2/2025 2:48:37 PM	163.9	164.8	1.62	-1.25	1.614	1.224	76.6	66.5	-6.80	-6.86
CV-2327	9/2/2025 2:55:00 PM										
CV-2327	9/2/2025 2:55:00 PM										
CV-2327	9/9/2025 9:19:28 AM	156.1	156.2	-3.75	-0.53	3.672	0.516	115.2	43.5	-8.91	-8.82
CV-2327	9/9/2025 9:21:14 AM	156.5	156.5	-0.48	-0.47	0.467	0.452	41.4	40.7	-8.88	-8.85
CV-2327	9/11/2025 9:26:15 AM	164.9	165.5	-0.82	-0.82	0.813	0.823	54.2	54.5	-9.76	-9.72
CV-2327	9/11/2025 9:27:00 AM										
CV-2327	9/17/2025 8:22:31 AM	162.9	163.9	-3.06	-3.07	3.050	3.055	104.7	104.7	-11.47	-11.52
CV-2327	9/25/2025 10:26:27 AM	171.1	171.4	-3.09	-3.29	3.108	3.306	105.0	108.2	-10.84	-11.09
CV-2328	9/10/2025 8:55:00 AM										
CV-2328	9/10/2025 8:55:00 AM										
CV-2328	9/10/2025 1:17:41 PM	178.1	178.0	-2.01	-2.01	1.314	1.308	22.6	22.5	-9.39	-9.36
CV-2328	9/10/2025 1:18:29 PM	178.0	178.1	-1.98	-1.96	0.996	1.149	19.7	21.1	-9.29	-9.40
CV-2328	9/11/2025 11:03:12 AM	173.7	173.6	-2.30	-2.28	0.464	0.413	40.6	38.3	-9.31	-9.04
CV-2328	9/11/2025 1:30:00 PM										
CV-2328	9/17/2025 8:35:20 AM	166.5	166.5	-5.33	-5.06	0.433	0.546	39.3	44.2	-11.68	-11.83
CV-2328	9/24/2025 2:31:29 PM	161.9		-3.86		0.168		24.6		-10.83	
CV-2333	9/2/2025 10:10:00 AM										
CV-2333	9/2/2025 10:10:00 AM										
CV-2333	9/10/2025 8:36:34 AM	136.9	137.1	-2.94	-2.86	0.157	0.018	15.4	5.2	-6.38	-6.61
CV-2333	9/10/2025 8:37:45 AM	137.4	137.0	-2.86	-2.90	0.043	0.036	8.1	7.4	-6.64	-6.68
CV-2333	9/30/2025 1:38:09 PM	137.1	138.5	-1.03	-1.05	0.065	0.011	9.9	4.2	-6.04	-6.39
CV-2333	9/30/2025 1:38:52 PM	139.4	139.6	-1.12	-1.02	0.026	0.053	6.3	9.0	-6.33	-6.69
CV-2334	9/2/2025 10:05:00 AM										
CV-2334	9/2/2025 10:05:00 AM										
CV-2334	9/5/2025 2:02:08 PM	128.8	129.0	-1.05	-0.99	0.019	0.058	5.5	9.5	0.34	0.34
CV-2334	9/30/2025 12:30:03 PM	128.6	128.2	-2.20	-1.64	0.115	0.094	6.5	5.8	-10.94	-11.02
CV-2335	9/10/2025 10:08:50 AM	106.5	107.4	-9.12	-8.60	9.300	8.787			-9.26	-8.74
CV-2335	9/17/2025 8:43:46 AM	108.0	108.0	-9.53	-9.25	9.701	9.409			-9.76	-9.48
CV-2336	9/10/2025 10:05:30 AM	73.2	73.2	-0.76	-0.76	0.737	0.750			0.29	0.29
CV-2336	9/17/2025 8:48:03 AM	81.5	81.3	-1.02	-1.01	0.985	0.973			0.32	0.35
CV-2337	9/9/2025 8:35:00 AM										
CV-2337	9/9/2025 8:35:00 AM										
CV-2337	9/12/2025 9:00:59 AM	78.8	78.7	-2.03	-1.99	0.016	0.016			-9.43	-9.41
CV-2337	9/12/2025 9:04:21 AM	78.3	79.2	-2.00	-1.52	0.021	0.020			-9.27	-9.20
CV-2337	9/26/2025 8:16:28 AM	142.2	143.4	-4.91	-5.07	7.275	6.977	50.2	49.1	-12.11	-11.47

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2337	9/26/2025 8:17:33 AM	142.3	142.9	-5.34	-5.33	6.829	7.150	48.6	49.7	-11.71	-12.02
CV-2338	9/4/2025 8:35:16 AM	191.4	191.4	-6.79	-6.96	4.810	4.810			0.31	0.31
CV-2338	9/4/2025 8:37:00 AM										
CV-2338	9/4/2025 8:37:00 AM										
CV-2338	9/10/2025 10:18:03 AM	165.9	166.5	-7.88	-8.25	8.178	7.939	0.0	0.0	-7.86	
CV-2338	9/10/2025 10:21:00 AM										
CV-2338	9/18/2025 8:33:45 AM	195.2	193.7	-9.81	-9.80	9.881	9.774			-6.84	-6.86
CV-2338	9/24/2025 10:56:05 AM	193.9	192.8	-6.31	-6.32	6.723	6.758			0.52	0.52
CV-2339	9/8/2025 11:17:21 AM	95.8	95.7	-2.22	-2.20	1.992	1.991	0.0	0.0	-7.87	
CV-2339	9/8/2025 11:20:05 AM	96.8	96.8	-2.84	-2.83	2.888	2.883	0.0	0.0	-7.99	
CV-2339	9/9/2025 11:16:42 AM										
CV-2339	9/23/2025 8:48:34 AM	93.1	93.6	-1.76	-0.98	1.753	0.982			0.34	0.34
CV-2341	9/8/2025 11:25:50 AM	113.0	113.0	-1.23	-1.26	1.359	1.348	0.0	0.0	-7.25	
CV-2341	9/9/2025 8:50:00 AM										
CV-2341	9/9/2025 8:50:00 AM										
CV-2341	9/16/2025 10:49:48 AM	138.4	136.4	-2.78	-1.39	2.706	1.338			-7.36	-8.15
CV-2342A-PLR	9/4/2025 9:24:20 AM	191.6	191.9	-7.91	-8.03	4.810	4.810			0.34	0.34
CV-2342A-PLR	9/4/2025 9:25:00 AM										
CV-2342A-PLR	9/4/2025 9:25:00 AM										
CV-2342A-PLR	9/10/2025 10:55:01 AM	169.1	169.5	-8.67	-8.67	8.690	7.865	0.0	0.0	-7.45	
CV-2342A-PLR	9/10/2025 10:58:00 AM										
CV-2342A-PLR	9/12/2025 2:13:51 PM	191.0	192.7	-9.77	-9.75	10.132	10.103			0.33	0.33
CV-2342A-PLR	9/18/2025 10:41:09 AM	190.6	191.5	-11.99	-11.94	11.842	11.822			-12.42	-12.45
CV-2342A-PLR	9/24/2025 10:03:10 AM	192.9	193.4	-10.50	-10.59	10.838	10.881			-10.72	-10.66
CV-2343	9/4/2025 9:05:29 AM	156.4	157.6	-6.30	-6.27	4.810	4.810			-8.18	-7.78
CV-2343	9/4/2025 9:25:00 AM										
CV-2343	9/4/2025 9:25:00 AM										
CV-2343	9/10/2025 11:41:53 AM	165.9	166.8	-7.07	-7.10	7.335	7.381			-8.51	-8.33
CV-2343	9/10/2025 11:42:00 AM										
CV-2343	9/12/2025 1:37:54 PM										
CV-2343	9/18/2025 9:11:19 AM	160.6	161.2	-4.42	-4.39	4.383	4.436			-5.15	-5.05
CV-2343	9/24/2025 9:09:31 AM	168.0	168.2	-7.85	-7.88	8.123	8.186			-8.87	-8.96
CV-2344	9/4/2025 8:56:00 AM										
CV-2344	9/4/2025 8:56:00 AM										
CV-2344	9/4/2025 8:58:42 AM	157.3	157.3	-1.43	-1.44	1.419	1.425			-8.31	-8.30
CV-2344	9/8/2025 9:45:00 AM										
CV-2344	9/8/2025 9:45:00 AM										

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2344	9/11/2025 1:47:51 PM	157.6	157.8	-1.71	-1.71	1.696	1.705			-7.69	-8.02
CV-2344	9/11/2025 2:20:00 PM										
CV-2344	9/17/2025 2:28:09 PM	143.1	143.2	-1.15	-1.13	1.103	1.044			-6.53	-6.03
CV-2344	9/17/2025 2:28:57 PM	144.1	144.1	-1.23	-1.29	1.213	1.202			-7.11	-7.00
CV-2344	9/18/2025 2:11:01 PM	160.6	161.1	-0.75	-0.75	0.740	0.746			-5.38	-5.56
CV-2344	9/24/2025 8:57:50 AM	158.5	158.4	-2.66	-2.69	2.602	2.624			-9.21	-9.13
CV-2345	9/8/2025 9:31:17 AM	133.7	134.4	-1.81	-0.72	1.776	0.706	0.0	0.0	-8.91	
CV-2345	9/9/2025 9:25:00 AM										
CV-2345	9/9/2025 9:25:00 AM										
CV-2345	9/17/2025 9:11:25 AM	143.0	142.9	-0.53	-0.33	0.535	0.372			-8.33	-8.70
CV-2345	9/17/2025 9:12:21 AM	143.0	142.7	-0.25	-0.25	0.275	0.254			-7.86	-9.03
CV-2346	9/2/2025 11:03:58 AM	128.1	128.0	-1.01	-0.89	1.051	0.855			-6.00	-5.67
CV-2346	9/9/2025 9:20:00 AM										
CV-2346	9/9/2025 9:20:00 AM										
CV-2346	9/17/2025 9:16:34 AM	128.4	128.5	-0.28	-0.26	0.314	0.285			-6.44	-6.44
CV-2347	9/2/2025 11:25:43 AM	112.2	112.3	-3.35	-1.05	3.341	1.069			-5.70	-6.78
CV-2347	9/9/2025 9:15:00 AM										
CV-2347	9/9/2025 9:15:00 AM										
CV-2347	9/17/2025 9:28:38 AM	117.4	117.5	-0.60	-0.36	0.616	0.361			-8.02	-7.97
CV-2348	9/2/2025 11:32:39 AM	134.5	134.0	-1.05	-0.54	1.086	0.550			-6.82	-6.69
CV-2348	9/2/2025 11:33:48 AM	133.4	133.3	-0.44	-0.34	0.464	0.353			-6.61	-6.72
CV-2348	9/9/2025 9:10:00 AM										
CV-2348	9/9/2025 9:10:00 AM										
CV-2348	9/17/2025 9:33:34 AM	133.8	134.2	-0.16	-0.11	0.169	0.120			-10.30	-8.34
CV-2348	9/17/2025 9:34:01 AM	134.1	134.2	-0.10	-0.10	0.108	0.096			-8.44	-8.15
CV-2349	9/4/2025 9:40:00 AM										
CV-2349	9/4/2025 9:40:00 AM										
CV-2349	9/5/2025 7:49:52 AM	150.0	150.3	-1.31	-1.82	1.295	1.853			-3.54	-4.17
CV-2349	9/5/2025 7:50:00 AM										
CV-2349	9/5/2025 7:50:00 AM										
CV-2349	9/11/2025 1:56:53 PM	152.5	152.3	-0.47	-0.50	0.493	0.478			-2.46	-2.32
CV-2349	9/11/2025 2:00:00 PM										
CV-2349	9/18/2025 11:04:29 AM	152.5	152.5	-2.50	-2.53	2.530	2.521			-5.39	-5.22

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2349	9/18/2025 2:43:09 PM	143.4	144.2	-0.81	-0.33	0.866	0.394			-5.80	-4.81
CV-2349	9/18/2025 2:44:16 PM	144.2	142.7	-0.34	-0.05	0.429	0.098			-4.60	-5.27
CV-2350	9/2/2025 2:26:16 PM	126.3	126.5	-1.42	-1.25	1.426	1.029			-2.76	-2.72
CV-2350	9/8/2025 9:10:00 AM										
CV-2350	9/8/2025 9:10:00 AM										
CV-2350	9/17/2025 10:55:34 AM	126.3	126.8	-1.88	-1.78	1.790	1.704			-2.52	-2.50
CV-2351	9/4/2025 9:00:00 AM										
CV-2351	9/4/2025 9:00:00 AM										
CV-2351	9/10/2025 8:47:36 AM	64.0	64.0	-0.07	-0.04	0.047	0.040			0.03	0.04
CV-2351	9/17/2025 2:13:22 PM	109.7	109.9	-0.06	-0.09	0.065	0.079			-7.69	-8.01
CV-2352	9/4/2025 9:28:00 AM										
CV-2352	9/4/2025 9:28:00 AM										
CV-2352	9/5/2025 10:40:34 AM										
CV-2352	9/10/2025 8:58:04 AM	88.6	89.4	-8.70	-8.53	8.784	8.661			-8.75	-8.67
CV-2352	9/17/2025 2:17:54 PM	121.0	120.8	-7.40	-7.64	7.540	7.842			0.23	0.24
CV-2353-PLR	9/4/2025 9:36:47 AM	180.1	180.4	-7.75	-7.78	4.810	4.810			0.34	0.34
CV-2353-PLR	9/4/2025 9:40:00 AM										
CV-2353-PLR	9/4/2025 9:40:00 AM										
CV-2353-PLR	9/8/2025 9:35:00 AM										
CV-2353-PLR	9/8/2025 9:35:00 AM										
CV-2353-PLR	9/10/2025 10:48:50 AM	174.4	174.6	-1.13	-0.73	0.800	0.735	0.0	0.0	-0.63	
CV-2353-PLR	9/10/2025 10:50:00 AM										
CV-2353-PLR	9/12/2025 2:09:56 PM	182.0	182.2	-5.90	-5.99	6.243	6.374			0.24	0.21
CV-2353-PLR	9/18/2025 10:48:02 AM	181.4	181.7	-7.47	-7.45	7.331	7.314			-12.11	-12.05
CV-2353-PLR	9/24/2025 10:20:25 AM	185.4	185.7	-5.09	-5.08	5.484	5.484			0.52	0.52
CV-2354	9/4/2025 9:35:00 AM										
CV-2354	9/4/2025 9:35:00 AM										
CV-2354	9/8/2025 3:32:46 PM	116.9	117.9	-2.66	-3.47	2.749	5.932	0.0	0.0	-2.45	
CV-2354	9/26/2025 8:52:45 AM	89.0	90.2	-3.61	-4.21	3.342	3.867			-3.66	-4.20
CV-2354	9/26/2025 8:53:43 AM	89.9	89.5	-6.76	-5.74	6.808	4.854			-7.03	-4.90
CV-24001	9/4/2025 8:04:16 AM	87.6	87.6	-0.41	-0.40	0.419	0.399			-8.70	-9.40
CV-24001	9/16/2025 10:33:58 AM	99.3	99.3	-0.45	-0.45	0.458	0.452			-8.77	-7.42

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24002	9/9/2025 10:26:26 AM	112.2	112.3	-0.68	-0.67	0.688	0.674			-3.27	-3.52
CV-24002	9/16/2025 10:22:25 AM	113.1	113.1	-1.13	-1.14	1.137	1.133			-3.84	-4.03
CV-24003	9/9/2025 10:22:43 AM	110.4	110.6	-0.50	-0.50	0.068	0.059	5.0	4.7	-3.32	-3.33
CV-24003	9/16/2025 9:31:10 AM	104.8	107.5	-0.89	-0.92	0.027	0.062	3.2	4.8	-4.06	-3.92
CV-24004	9/9/2025 10:03:41 AM	112.9	112.9	-0.69	-0.68	0.046	0.075	4.2	5.3	-9.08	-9.03
CV-24004	9/16/2025 9:37:44 AM	111.8	111.4	-1.29	-1.22	0.172	0.061	8.0	4.8	-11.21	-10.21
CV-24006	9/5/2025 9:08:53 AM	132.1	132.1	-0.60	-0.60	1.833	1.901	25.6	26.1	-8.82	-9.05
CV-24006	9/5/2025 9:10:33 AM	132.2	132.1	-0.58	-0.59	1.831	2.030	25.6	27.0	-8.28	-9.25
CV-24006	9/16/2025 9:05:01 AM	129.8	128.9	-0.54	-0.50	1.821	1.801	25.6	25.5	-8.71	-8.22
CV-24006	9/18/2025 1:42:35 PM	130.5	130.2	-0.16	-0.05	1.812	1.509	25.5	23.3	-8.39	-6.27
CV-24006	9/18/2025 1:43:55 PM	130.2	130.3	-0.12	-0.13	1.776	1.802	25.3	25.5	-7.35	-7.38
CV-24007	9/10/2025 10:11:39 AM	127.8	127.3	-0.35	-0.29	1.100	0.868	20.0	17.7	-3.56	-3.45
CV-24007	9/11/2025 7:45:00 AM										
CV-24007	9/11/2025 7:45:00 AM										
CV-24007	9/16/2025 12:28:29 PM	129.5	129.5	-0.16	-0.16	0.700	0.700	15.9	15.9	-2.72	-2.72
CV-24008	9/10/2025 10:21:55 AM	97.9	97.4	1.56	1.56	0.039	0.030	8.0	7.1	1.45	1.45
CV-24008	9/10/2025 10:23:16 AM	97.5	97.5	1.57	1.56	0.039	0.036	8.0	7.7	1.45	1.45
CV-24008	9/16/2025 12:35:36 PM	115.3	114.4	1.59	1.61	0.062	0.099	10.0	12.5	1.78	1.79
CV-24008	9/16/2025 12:36:23 PM	113.9	113.9	1.61	1.62	0.064	0.060	10.1	9.8	1.94	1.94
CV-24009	9/2/2025 2:20:10 PM	160.6	161.0	-1.02	-0.94	0.761	0.649			-7.32	-7.42
CV-24009	9/2/2025 2:28:00 PM										
CV-24009	9/2/2025 2:28:00 PM										
CV-24009	9/8/2025 10:47:07 AM	149.6	149.2	-1.78	-1.08	0.149	0.111			-8.82	-8.19
CV-24009	9/8/2025 10:50:00 AM										
CV-24009	9/16/2025 9:10:00 AM										
CV-24009	9/16/2025 9:10:33 AM	145.6	145.7	-1.85	-1.84	0.016	0.015			-11.51	-11.35
CV-24009	9/22/2025 10:49:46 AM	147.7	147.7	-0.93	-0.94	0.162	0.154			-6.86	-7.41
CV-24010	9/9/2025 9:54:20 AM	99.5	99.8	-0.70	-0.68	0.694	0.670			-8.58	-8.55
CV-24010	9/16/2025 9:15:19 AM			-1.36	-1.36	1.386	1.386			-11.59	-11.59
CV-24010	9/16/2025 9:18:31 AM	96.4	96.3	-1.28	-1.28	1.301	1.299			-11.54	-11.62
CV-24010	9/16/2025 10:56:12 AM										
CV-24011	9/3/2025 1:45:00 PM										
CV-24011	9/3/2025 1:45:00 PM										
CV-24011	9/3/2025 1:45:11 PM	174.3	173.2	-2.44	-2.87	0.106	0.100			-4.27	-4.76
CV-24011	9/8/2025 11:10:59 AM	171.9	172.2	-0.75	-0.66	8.032	7.303	51.8	49.4	-7.45	-7.08
CV-24011	9/8/2025 11:13:00 AM										
CV-24011	9/16/2025 1:29:16 PM	156.6	156.8	-6.19	-6.04	0.374	0.001			-8.14	-8.42

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24011	9/16/2025 1:33:00 PM										
CV-24011	9/23/2025 8:46:19 AM	173.7	173.5	-0.85	-0.84	5.578	5.642	43.1	43.3	-11.37	-11.51
CV-24011	9/30/2025 11:14:08 AM	174.9	174.9	-0.37	-0.38	5.406	5.490	42.6	42.9	-9.82	-9.35
CV-24012	9/3/2025 10:32:37 AM	187.8	186.6	-8.40	-8.36	8.189	8.119			-2.72	-2.60
CV-24012	9/3/2025 10:35:00 AM										
CV-24012	9/3/2025 10:35:00 AM										
CV-24012	9/9/2025 10:45:52 AM	186.0	186.0	-8.62	-8.91	9.156	9.348			-8.64	-9.08
CV-24012	9/9/2025 10:48:00 AM										
CV-24012	9/16/2025 9:44:30 AM	182.9	182.9	-11.71	-11.66	11.972	11.899			-11.50	-11.48
CV-24012	9/16/2025 9:48:00 AM										
CV-24012	9/23/2025 8:08:57 AM	187.1	187.3	-12.94	-12.99	13.070	13.050			-13.14	-13.15
CV-24012	9/30/2025 11:07:38 AM	187.5	186.6	-10.68	-5.25	11.001	5.525			-11.89	-12.04
CV-24013	9/4/2025 10:09:59 AM	110.1	106.8	-9.29	-1.56	9.424	1.551			-9.22	-9.36
CV-24013	9/4/2025 10:11:31 AM	110.6	109.8	-8.42	-8.42	8.555	8.561			-9.23	-9.21
CV-24014	9/2/2025 2:14:50 PM	178.8	178.7	-0.28	-0.19	0.156	0.116			-7.23	-7.12
CV-24014	9/2/2025 2:23:00 PM										
CV-24014	9/2/2025 2:23:00 PM										
CV-24014	9/8/2025 10:40:40 AM	178.2	178.3	-0.42	-0.12	0.000	0.000			-2.32	0.17
CV-24014	9/8/2025 10:41:40 AM	178.2	178.2	-0.12	-0.12	0.000	0.000			-8.64	-8.82
CV-24014	9/8/2025 10:44:00 AM										
CV-24014	9/15/2025 10:57:09 AM	179.3	179.4	-2.59	-2.49	2.510	2.421			0.69	0.68
CV-24014	9/15/2025 11:00:00 AM										
CV-24014	9/22/2025 10:38:26 AM	179.1	178.9	-0.36	-0.43	0.270	0.283			-7.72	-9.25
CV-24014	9/29/2025 2:31:43 PM	177.9	178.8	-0.21	-0.34	0.000	0.000			-7.94	-8.62
CV-24015	9/3/2025 9:49:26 AM	188.3	188.1	-6.93	-6.77	7.193	6.948			0.36	0.34
CV-24015	9/3/2025 9:55:00 AM										
CV-24015	9/3/2025 9:55:00 AM										
CV-24015	9/5/2025 8:17:48 AM	186.5	186.1	-9.12	-9.12	9.074	9.192			0.35	0.39
CV-24015	9/9/2025 9:33:21 AM	187.2	188.0	-8.62	-8.38	9.025	8.745			0.67	0.67
CV-24015	9/9/2025 9:34:00 AM										
CV-24015	9/15/2025 10:00:29 AM	185.0	185.6	-9.81	-5.70	10.185	5.994			0.35	0.38
CV-24015	9/15/2025 10:05:00 AM										

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24015	9/16/2025 11:15:52 AM										
CV-24015	9/22/2025 9:06:44 AM	186.9	187.6	-4.66	-4.62	4.574	4.536			0.33	0.34
CV-24015	9/29/2025 1:59:42 PM	186.4	187.1	-3.28	-3.28	3.212	3.182			-0.01	-0.01
CV-24016	9/3/2025 1:49:15 PM	167.8	168.6	-1.48	-1.45	1.461	1.414			-5.29	-5.53
CV-24016	9/3/2025 1:54:00 PM										
CV-24016	9/3/2025 1:54:00 PM										
CV-24016	9/8/2025 11:14:40 AM	177.4	177.0	-0.94	-0.66	0.955	0.669			-7.21	-7.42
CV-24016	9/8/2025 11:18:00 AM										
CV-24016	9/16/2025 10:07:50 AM	187.6	187.6	-1.57	-0.74	1.593	0.748			-9.38	-9.39
CV-24016	9/16/2025 10:10:00 AM										
CV-24016	9/23/2025 8:40:55 AM	176.5	176.6	-1.94	-1.93	2.011	1.969			-10.94	-11.04
CV-24016	9/30/2025 11:22:26 AM	160.7	148.1	-7.16	-1.42	7.567	1.418			-8.57	-10.14
CV-24017	9/3/2025 10:38:48 AM	175.5	176.0	-2.52	-1.49	2.415	1.394			-1.69	-2.12
CV-24017	9/3/2025 10:40:00 AM										
CV-24017	9/3/2025 10:40:00 AM										
CV-24017	9/9/2025 10:59:21 AM	160.0	159.7	-3.79	-3.76	3.768	3.732			0.73	0.67
CV-24017	9/9/2025 11:00:00 AM										
CV-24017	9/11/2025 7:50:00 AM										
CV-24017	9/11/2025 7:50:00 AM										
CV-24017	9/16/2025 9:51:04 AM	166.2	166.4	-5.35	-5.38	5.565	5.580			-10.97	-10.98
CV-24017	9/16/2025 9:52:00 AM										
CV-24017	9/23/2025 8:18:33 AM	167.1	167.2	-2.86	-2.70	2.831	2.696			-12.51	-12.61
CV-24017	9/30/2025 10:51:29 AM	188.2	188.9	-1.69	-1.69	1.689	1.664			-11.59	-11.50
CV-24018	9/5/2025 10:24:23 AM	129.5	129.5	-1.18	-0.70	1.147	0.660			-7.59	-7.49
CV-24018	9/16/2025 9:19:19 AM	123.6	123.8	-0.76	-0.72	0.737	0.696			0.30	0.30
CV-24019	9/3/2025 10:57:10 AM	189.3	190.5	-1.65	-1.68	1.490	1.565			-1.69	2.78
CV-24019	9/3/2025 10:58:00 AM										
CV-24019	9/3/2025 10:58:00 AM										
CV-24019	9/9/2025 11:04:11 AM	188.4	188.7	-5.46	-5.15	5.997	5.724			0.74	0.74
CV-24019	9/9/2025 11:05:00 AM										
CV-24019	9/16/2025 10:00:31 AM	177.9	177.6	-5.97	-5.95	6.219	6.199			-10.90	-10.68
CV-24019	9/16/2025 10:02:00 AM										
CV-24019	9/23/2025 8:27:43 AM	188.5	178.6	-4.83	-5.01	4.968	5.495			-12.68	-12.91

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24020	9/10/2025 9:44:19 AM	72.7	72.6	2.21	-8.07	0.000	8.124			-8.16	-8.24
CV-24020	9/10/2025 9:48:04 AM	73.0	73.0	-7.88	-8.08	8.034	8.219			-8.04	-8.32
CV-24020	9/12/2025 9:47:03 AM	94.1	93.7	-4.20	-2.06	4.190	2.056			-8.44	-7.49
CV-24020	9/23/2025 9:39:18 AM	101.6	101.8	-8.41	-8.10	8.716	8.483			-10.25	-10.20
CV-24021	9/10/2025 9:38:22 AM	71.8	71.7	-10.50	-10.95	10.593	11.037			-10.67	-11.19
CV-24021	9/10/2025 9:39:32 AM	71.4	71.4	-11.06	-10.95	11.163	10.974			-11.23	-10.98
CV-24021	9/16/2025 2:10:21 PM	112.6	112.9	-9.30	-8.88	9.473	9.168			0.54	0.66
CV-24022-PLR	9/2/2025 2:07:56 PM	193.0	193.0	-7.62	-7.26	7.507	7.121			0.00	0.00
CV-24022-PLR	9/2/2025 2:18:00 PM										
CV-24022-PLR	9/3/2025 2:18:00 PM										
CV-24022-PLR	9/8/2025 10:35:45 AM	192.6	192.8	-8.39	-8.39	8.712	8.753			0.34	0.34
CV-24022-PLR	9/8/2025 10:38:00 AM										
CV-24022-PLR	9/15/2025 11:04:36 AM	193.1	193.4	-13.62	-13.45	13.971	13.817			0.70	0.69
CV-24022-PLR	9/15/2025 2:05:40 PM	192.8	193.0	-10.97	-6.38	10.929	6.443			-0.21	-0.20
CV-24022-PLR	9/16/2025 8:54:00 AM										
CV-24022-PLR	9/22/2025 10:29:57 AM	192.9	193.2	-8.57	-9.05	9.112	9.711			0.45	0.44
CV-24022-PLR	9/29/2025 2:24:05 PM	191.0	191.5	-5.53	-5.86	5.617	5.938			-0.10	-0.14
CV-24023	9/2/2025 1:57:28 PM	191.2	190.8	-7.90	-7.07	7.753	6.942			-6.97	-6.91
CV-24023	9/2/2025 2:14:00 PM										
CV-24023	9/2/2025 2:14:00 PM										
CV-24023	9/8/2025 10:26:00 AM										
CV-24023	9/8/2025 10:26:17 AM	189.4	188.2	-8.37	-8.14	8.727	8.564			-8.46	-8.36
CV-24023	9/9/2025 9:50:00 AM										
CV-24023	9/9/2025 9:50:03 AM	190.4	189.9	-2.68	-2.58	2.677	2.542			0.66	0.63

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24023	9/15/2025 10:13:46 AM	192.5	193.5	-3.89	-3.83	3.816	3.676			-12.14	-12.12
CV-24023	9/15/2025 10:15:00 AM										
CV-24023	9/22/2025 9:29:28 AM	190.7	191.2	-0.55	-0.54	0.556	0.524			0.34	0.35
CV-24023	9/29/2025 2:11:07 PM	187.7	188.0	-1.17	-1.21	1.151	1.204			0.00	0.00
CV-24024-PLR	9/3/2025 9:38:14 AM	183.7	182.2	-8.87	-8.16	9.156	8.383			-8.03	-8.07
CV-24024-PLR	9/3/2025 9:40:00 AM										
CV-24024-PLR	9/3/2025 9:40:00 AM										
CV-24024-PLR	9/9/2025 9:22:16 AM	178.3	176.8	-9.11	-9.18	9.384	9.434			-9.06	-8.97
CV-24024-PLR	9/9/2025 9:24:00 AM										
CV-24024-PLR	9/15/2025 9:28:10 AM	173.1	173.2	-10.40	-10.37	10.559	10.555			-9.88	-9.93
CV-24024-PLR	9/15/2025 9:30:00 AM										
CV-24024-PLR	9/22/2025 8:56:46 AM	178.9	178.8	-10.26	-10.52	10.408	10.581			-12.02	-12.13
CV-24024-PLR	9/29/2025 1:45:31 PM	168.9	168.5	-8.76	-8.72	8.948	8.914			-9.33	-9.32
CV-24025	9/3/2025 1:56:13 PM	162.2	162.3	-4.50	-4.34	4.483	4.275			0.04	0.03
CV-24025	9/3/2025 2:00:00 PM										
CV-24025	9/3/2025 2:00:00 PM										
CV-24025	9/9/2025 1:37:04 PM	160.5	160.5	-6.71	-6.55	6.669	6.489			0.00	0.00
CV-24025	9/9/2025 1:38:00 PM										
CV-24025	9/16/2025 10:59:39 AM	161.5	161.5	-7.38	-7.42	7.733	7.726			0.60	0.60
CV-24025	9/16/2025 11:00:00 AM										
CV-24025	9/23/2025 9:03:55 AM	159.8	159.7	-8.53	-8.58	8.983	9.017			0.38	0.35
CV-24025	9/30/2025 9:51:56 AM	170.6	170.7	-4.89	-4.85	5.159	5.134			0.62	0.65
CV-24026	9/2/2025 2:33:13 PM	105.1	105.8	-1.23	-1.03	1.211	1.010			-7.38	-7.40
CV-24026	9/2/2025 2:34:10 PM	108.1	108.4	-1.55	-1.38	1.480	1.330			-7.46	-7.20
CV-24026	9/3/2025 8:24:30 AM	85.2	85.4	-0.41	-0.37	0.407	0.371			-9.57	-9.90
CV-24026	9/3/2025 8:32:39 AM	86.3	87.4	-8.34	-8.54	8.371	8.607			-9.39	-9.54
CV-24026	9/3/2025 9:04:21 AM										
CV-24026	9/8/2025 1:27:07 PM	103.2	103.4	-7.05	-6.38	7.015	6.299			-7.54	-7.63
CV-24026	9/9/2025 11:13:09 AM	100.8	101.3	-3.59	-3.59	3.581	3.581			0.67	0.67
CV-24026	9/23/2025 9:47:18 AM	157.8	157.9	-12.46	-6.07	12.813	6.428			-12.26	-12.24
CV-24026	9/23/2025 9:48:10 AM	157.1	157.5	-5.57	-5.64	5.928	5.940			-12.25	-11.93
CV-24026	9/25/2025 11:00:40 AM	138.1	136.4	-1.46	-1.23	1.458	1.380	0.0	0.0	-12.00	

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24026	9/25/2025 11:05:05 AM	135.8	136.8	-0.95	-0.48	0.918	0.505	0.0	0.0	-12.87	
CV-24027	9/10/2025 9:33:45 AM	70.5	70.8	-1.65	-1.62	1.650	1.629			-10.82	-11.07
CV-24027	9/10/2025 9:34:58 AM	71.0	71.0	-1.35	-1.38	1.357	1.373			-10.72	-11.07
CV-24027	9/16/2025 2:04:15 PM	113.2	113.2	-0.39	-0.39	0.311	0.316			-9.02	-8.77
CV-24028	9/2/2025 2:02:21 PM	194.5	194.5	-7.46	-6.35	7.351	6.161			-0.01	0.00
CV-24028	9/2/2025 2:05:00 PM										
CV-24028	9/2/2025 2:05:00 PM										
CV-24028	9/8/2025 10:30:45 AM	194.4	194.5	-6.46	-6.44	6.844	6.824			0.36	0.35
CV-24028	9/8/2025 10:32:00 AM										
CV-24028	9/15/2025 2:00:13 PM	193.9	192.6	-6.47	-1.79	6.522	1.753			-0.19	-0.21
CV-24028	9/15/2025 2:04:00 PM										
CV-24028	9/22/2025 10:24:26 AM	194.2	194.3	-8.43	-8.64	8.810	9.028			0.36	0.35
CV-24028	9/29/2025 2:16:54 PM	191.0	191.4	-7.11	-7.49	7.184	7.609			0.00	0.00
CV-24029	9/5/2025 8:26:17 AM	91.6	92.7	-6.08	-6.07	6.298	6.199			-10.68	-11.01
CV-24029	9/16/2025 1:28:21 PM										
CV-24029	9/23/2025 10:27:04 AM	106.3	106.9	-11.23	-11.19	11.669	11.715	22.9	22.9	0.67	0.65
CV-24029	9/23/2025 10:28:20 AM	106.9	107.1	-11.22	-11.28	11.658	11.729	22.9	22.9	0.67	0.63
CV-24030	9/3/2025 9:18:20 AM	194.0	194.0	-4.27	-4.38	4.177	4.366			-4.73	-4.88
CV-24030	9/3/2025 9:20:00 AM										
CV-24030	9/3/2025 9:20:00 AM										
CV-24030	9/9/2025 9:07:55 AM	194.0	194.0	-1.53	-1.35	1.376	1.386			-6.74	-5.95
CV-24030	9/9/2025 9:10:00 AM										
CV-24030	9/11/2025 9:10:00 AM										
CV-24030	9/15/2025 9:09:04 AM	192.0	192.0	-2.88	-2.64	2.879	2.555			-6.69	-6.61
CV-24030	9/22/2025 8:38:56 AM	193.5	193.4	-2.72	-2.75	2.678	2.659			0.01	0.01
CV-24030	9/29/2025 11:36:38 AM	193.4	193.4	-2.07	-2.08	2.008	2.003			0.72	0.86
CV-24031	9/5/2025 10:38:27 AM	124.8	124.7	-1.26	-1.27	1.201	1.214			1.01	1.03
CV-24031	9/16/2025 9:23:45 AM	123.9	124.0	-1.94	-1.95	1.880	1.878			0.30	0.30
CV-24031	9/16/2025 2:06:59 PM										
CV-24032	9/3/2025 2:07:25 PM	183.4	184.7	-0.07	-0.33	0.025	0.383			-6.29	-6.45
CV-24032	9/3/2025 2:12:00 PM										
CV-24032	9/3/2025 2:12:00 PM										

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24032	9/9/2025 1:50:39 PM	180.4	182.7	-1.00	-0.95	1.006	0.923			0.00	0.00
CV-24032	9/9/2025 1:52:00 PM										
CV-24032	9/16/2025 11:20:08 AM	187.8	188.7	-8.89	-8.55	9.298	8.986			0.60	0.60
CV-24032	9/16/2025 11:25:00 AM										
CV-24032	9/23/2025 9:59:19 AM	187.7	189.1	-4.64	-4.92	5.113	4.906			-10.39	-10.29
CV-24032	9/30/2025 1:52:28 PM	183.5	184.4	-7.32	-7.05	7.073	6.868			-9.88	-9.87
CV-24033	9/3/2025 2:02:43 PM	178.6	178.4	-1.25	-1.31	1.300	1.352			-5.91	-5.19
CV-24033	9/3/2025 2:09:00 PM										
CV-24033	9/3/2025 2:09:00 PM										
CV-24033	9/9/2025 1:46:18 PM	177.6	177.9	-1.40	-1.79	1.364	1.742			-3.82	-7.86
CV-24033	9/9/2025 1:48:00 PM										
CV-24033	9/16/2025 11:13:45 AM	182.2	182.6	-4.67	-4.40	4.630	4.396			-7.85	-6.95
CV-24033	9/16/2025 11:15:00 AM										
CV-24033	9/23/2025 9:14:05 AM	182.0	181.5	-2.66	-2.71	2.797	2.676			-10.39	-9.33
CV-24033	9/30/2025 9:38:26 AM	183.7	184.0	-2.95	-2.79	2.911	2.800			-6.62	-6.83
CV-24034	9/2/2025 10:43:35 AM	149.1	148.0	-6.79	-6.78	7.122	7.069			-7.14	-7.15
CV-24034	9/2/2025 10:44:22 AM	150.2	149.3	-6.86	-6.74	7.097	6.999			-7.23	-7.10
CV-24034	9/2/2025 10:48:00 AM										
CV-24034	9/8/2025 9:04:59 AM	152.6	152.8	-5.25	-4.99	5.482	5.025			-9.11	-9.61
CV-24034	9/8/2025 9:07:00 AM										
CV-24034	9/8/2025 9:08:20 AM	164.2	156.2	-4.50	-2.60	4.535	2.627			-9.70	-9.70
CV-24034	9/15/2025 11:19:52 AM	160.6	159.5	18.20	-9.69	0.000	10.061			-11.15	-12.06
CV-24034	9/15/2025 11:25:00 AM										
CV-24034	9/15/2025 11:28:07 AM	169.6	171.8	-10.40	-10.43	10.637	10.808			-11.72	-11.82
CV-24034	9/16/2025 11:41:28 AM	165.1	164.4	-11.56	-11.27	12.021	11.759			-9.99	-9.81
CV-24034	9/22/2025 11:13:29 AM	161.6	160.5	-10.08	-10.06	10.935	10.962			-9.93	-9.97

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24034	9/29/2025 10:09:45 AM	155.5	156.4	-10.92	-10.83	11.157	11.006			-10.85	-10.61
CV-24035	9/2/2025 1:48:03 PM	189.6	189.6	-2.57	-2.43	2.576	2.376			0.00	0.00
CV-24035	9/2/2025 2:10:00 PM										
CV-24035	9/2/2025 2:10:00 PM										
CV-24035	9/9/2025 8:39:33 AM	188.7	188.7	-4.94	-5.91	4.785	6.018			0.24	0.25
CV-24035	9/9/2025 8:42:00 AM										
CV-24035	9/11/2025 8:51:00 AM										
CV-24035	9/15/2025 8:51:12 AM	188.3	188.3	-4.99	-5.07	4.698	5.427			0.12	0.05
CV-24035	9/22/2025 8:21:28 AM	187.8	187.7	-5.94	-5.83	5.965	5.950			0.00	0.00
CV-24035	9/29/2025 11:14:11 AM	187.0	187.4	-4.51	-4.46	4.426	4.476			0.68	0.67
CV-24036	9/5/2025 10:47:48 AM	104.5	104.8	-1.15	-1.17	1.089	1.115			-6.64	-6.87
CV-24036	9/16/2025 9:26:40 AM	100.6	100.8	-1.63	-1.64	1.590	1.601			-10.04	-10.63
CV-24037	9/8/2025 8:39:03 AM	136.3	136.4	-0.17	-0.14	0.161	0.152			0.30	0.30
CV-24037	9/8/2025 8:39:31 AM	136.4	136.4	-0.15	-0.12	0.158	0.117			0.30	0.30
CV-24037	9/16/2025 11:09:08 AM	147.9	147.9	-0.13	-0.03	0.060	0.006			0.64	0.64
CV-24037	9/16/2025 1:38:00 PM										
CV-24037	9/23/2025 9:47:48 AM	151.5	151.7	-0.25	-0.22	0.546	0.520			-9.54	-9.25
CV-24037	9/30/2025 8:36:23 AM	150.3	150.3	-0.14	-0.12	0.146	0.117			0.22	0.15
CV-24038	9/3/2025 2:18:42 PM	190.0	191.4	15.64	15.39	0.000	0.000			15.79	15.62
CV-24038	9/3/2025 2:22:00 PM										
CV-24038	9/3/2025 2:22:00 PM										
CV-24038	9/3/2025 2:22:02 PM	190.0	190.4	9.45	9.02	0.000	0.000			17.37	16.75
CV-24038	9/9/2025 2:01:00 PM										
CV-24038	9/9/2025 2:01:38 PM	191.1	191.0	16.58	18.75	0.000	0.000			18.66	19.16
CV-24038	9/16/2025 1:48:08 PM	190.4	190.4	6.23	11.81	0.000	0.000			17.69	17.10
CV-24038	9/16/2025 1:49:59 PM	190.9	190.2	11.79	12.88	0.000	0.000			17.35	18.70
CV-24038	9/16/2025 1:50:00 PM										
CV-24038	9/23/2025 9:38:31 AM	193.2	192.5	14.57	14.09	0.000	0.000			0.67	0.67

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24038	9/30/2025 8:49:35 AM	193.8	192.9	12.60	12.50	0.000	0.000			0.34	0.34
CV-24039	9/3/2025 2:27:52 PM	189.6	188.9	-1.16	-1.09	1.155	1.072			-7.55	-7.42
CV-24039	9/3/2025 2:28:00 PM										
CV-24039	9/3/2025 2:28:00 PM										
CV-24039	9/9/2025 2:05:13 PM	183.6	184.7	-2.52	-2.44	2.334	2.307			-8.64	-8.70
CV-24039	9/9/2025 2:09:00 PM										
CV-24039	9/16/2025 1:53:55 PM	189.0	188.6	-10.31	-10.09	10.185	9.891			-8.71	-8.67
CV-24039	9/16/2025 1:55:00 PM										
CV-24039	9/23/2025 9:33:15 AM	189.8	189.3	-6.78	-6.76	7.248	7.229			-11.96	-11.89
CV-24039	9/30/2025 9:00:55 AM	189.4	189.5	-2.55	-2.55	2.536	2.533			-9.23	-9.03
CV-24040	9/8/2025 10:13:26 AM	103.0	103.2	-4.74	-4.71	4.645	4.618			-9.46	-9.31
CV-24040	9/8/2025 10:16:36 AM	101.8	102.1	-9.43	-9.36	9.817	9.725			-9.31	-9.21
CV-24040	9/16/2025 1:19:05 PM	177.6	177.5	-10.39	-1.77	10.535	1.669			-10.07	-10.03
CV-24040	9/16/2025 1:19:57 PM	175.9	176.0	-1.77	-1.67	1.754	1.834			-9.89	-10.14
CV-24040	9/16/2025 2:10:00 PM										
CV-24040	9/23/2025 10:57:33 AM	179.4	180.2	-4.52	-4.59	4.658	4.840			-9.82	-10.25
CV-24041	9/8/2025 10:22:24 AM	108.6	108.9	-9.31	-4.11	9.579	4.023			-9.30	-9.30
CV-24041	9/16/2025 1:34:33 PM	152.9	152.5	-3.50	-1.21	3.430	1.088			-9.85	-9.84
CV-24041	9/16/2025 1:36:00 PM	154.5	152.2	-2.75	-0.87	2.680	0.728			-9.87	-9.89
CV-24041	9/16/2025 2:16:00 PM										
CV-24041	9/23/2025 11:13:01 AM	97.0	99.2	-0.63	-0.27	0.612	0.258			-11.45	-11.35
CV-24041	9/23/2025 11:16:11 AM	103.4	100.5	-4.44	-4.51	4.347	4.412			-11.47	-11.45
CV-24042	9/2/2025 10:31:52 AM	189.2	188.9	-0.62	-0.46	0.542	0.463			-1.59	-1.59
CV-24042	9/2/2025 10:34:00 AM										
CV-24042	9/8/2025 8:40:10 AM	187.4	187.1	-0.75	-0.76	0.741	0.787			-2.46	-2.73
CV-24042	9/8/2025 8:45:00 AM										
CV-24042	9/15/2025 2:13:22 PM	185.4	185.2	-1.13	-1.05	1.095	0.973			-3.40	-3.70
CV-24042	9/15/2025 2:15:00 PM										
CV-24042	9/16/2025 1:37:19 PM										
CV-24042	9/22/2025 1:15:59 PM	186.1	186.0	-0.77	-0.74	0.475	0.470			-2.56	-2.49
CV-24042	9/29/2025 9:23:47 AM	188.8	188.7	-0.49	-0.36	0.449	0.360			-1.15	-1.04

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24043	9/8/2025 10:59:55 AM	113.0	113.3	-3.57	-4.11	4.471	3.587	0.0	0.0	-4.69	
CV-24043	9/16/2025 9:39:54 AM	108.1	108.3	-4.75	-5.59	4.581	5.943			-4.69	-5.56
CV-24044	9/5/2025 10:52:35 AM	119.9	120.1	-6.08	-4.73	6.438	5.213			-5.34	-4.18
CV-24044	9/16/2025 10:55:01 AM	114.6	114.8	-5.88	-5.77	6.333	4.984			-5.71	-5.34
CV-24045	9/3/2025 2:14:13 PM	180.2	179.2	-1.64	-1.33	1.567	1.286			-3.98	-4.23
CV-24045	9/3/2025 2:18:00 PM										
CV-24045	9/3/2025 2:18:00 PM										
CV-24045	9/9/2025 1:56:13 PM	180.0	180.1	-0.23	-0.90	0.226	0.946			-2.56	-2.39
CV-24045	9/9/2025 1:58:00 PM										
CV-24045	9/16/2025 1:42:07 PM	179.2	106.7	-3.37	-3.50	4.060	3.395			-1.36	-1.40
CV-24045	9/16/2025 1:43:00 PM										
CV-24045	9/23/2025 9:42:57 AM	183.1	183.1	-2.16	-2.18	2.250	2.327			-3.94	-4.16
CV-24045	9/30/2025 8:42:13 AM	184.0	183.2	-2.63	-2.76	2.625	2.695			-6.25	-6.69
CV-24046	9/8/2025 10:04:52 AM	96.2	96.4	-4.83	-4.82	4.737	4.727			0.34	0.34
CV-24046	9/8/2025 10:05:32 AM	96.6	96.7	-4.94	-4.93	4.848	4.834			0.46	0.43
CV-24046	9/16/2025 1:13:19 PM	106.7	106.9	-1.17	-1.20	1.135	1.162			0.65	0.66
CV-24048	9/8/2025 10:26:19 AM	119.5	119.6	-2.34	-2.34	2.278	2.272			-9.17	-9.10
CV-24048	9/16/2025 1:41:18 PM	118.2	118.3	-2.82	-2.80	2.688	2.683			-9.74	-9.63
CV-24049	9/2/2025 11:18:25 AM	187.8	188.1	-0.29	-0.17	0.314	0.187			-6.75	-6.59
CV-24049	9/2/2025 11:25:00 AM										
CV-24049	9/2/2025 11:25:00 AM										
CV-24049	9/3/2025 9:45:00 AM										
CV-24049	9/3/2025 9:45:00 AM										
CV-24049	9/8/2025 8:45:03 AM	188.5	188.8	-0.33	-0.25	0.346	0.270			-8.95	-8.90
CV-24049	9/8/2025 8:48:00 AM										
CV-24049	9/15/2025 2:22:04 PM	185.2	187.7	1.13	-1.28	0.000	1.269			-7.10	-5.71
CV-24049	9/15/2025 2:22:59 PM	188.6	188.7	-1.33	-1.30	1.311	1.199			-5.85	-5.91
CV-24049	9/15/2025 2:24:00 PM										
CV-24049	9/22/2025 1:21:53 PM	188.4	188.7	-0.29	-0.29	0.571	0.469			-3.10	-2.89
CV-24049	9/29/2025 9:33:42 AM	188.4	189.4	-0.02	-0.10	0.013	0.070			-1.44	-1.94
CV-24050	9/8/2025 10:50:27 AM	114.4	114.4	-2.34	-2.33	2.211	2.316	0.0	0.0	-6.91	
CV-24050	9/16/2025 10:46:01 AM	93.7	97.7	-3.09	-3.09	2.985	3.004			-7.97	-7.55

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24051	9/8/2025 8:16:33 AM	86.7	86.8	-8.95	-8.80	8.976	8.875			-9.10	-9.13
CV-24051	9/16/2025 11:02:28 AM	114.4	111.1	-0.62	-0.62	0.588	0.582			0.64	0.64
CV-24052	9/9/2025 9:09:07 AM	107.3	108.3	0.46	-0.81	0.000	0.786			-10.15	-10.21
CV-24052	9/9/2025 9:10:08 AM	109.2	109.3	-1.01	-0.99	0.975	0.968			-10.08	-10.09
CV-24052	9/16/2025 1:50:21 PM	122.9	122.5	-1.63	-1.64	1.518	1.519			-9.31	-9.22
CV-24053	9/8/2025 2:11:38 PM	97.9	98.1	-0.31	-0.24	0.200	0.156			-8.60	-8.15
CV-24053	9/8/2025 2:17:33 PM	98.3	98.4	-0.03	-0.04	0.000	0.000			-8.46	-8.57
CV-24053	9/11/2025 8:20:00 AM										
CV-24053	9/11/2025 8:20:00 AM										
CV-24053	9/16/2025 1:45:54 PM	111.8	111.9	-0.07	-0.08	0.000	0.000			-8.85	-9.65
CV-24054	9/2/2025 11:13:00 AM										
CV-24054	9/2/2025 11:13:00 AM										
CV-24054	9/2/2025 11:13:04 AM	177.1	177.4	-1.28	-1.19	1.299	1.207			-4.70	-4.71
CV-24054	9/10/2025 2:20:09 PM	156.9	158.0	-3.53	-3.54	3.551	3.550	0.0	0.0	-8.53	
CV-24054	9/10/2025 2:22:00 PM										
CV-24054	9/12/2025 1:48:31 PM	175.0	174.9	-2.81	-2.78	2.739	2.698			-8.27	-8.33
CV-24054	9/17/2025 6:49:53 AM	164.2	164.2	-3.75	-3.69	3.736	3.670			-6.49	-6.37
CV-24054	9/25/2025 8:51:28 AM	174.0	174.2	-4.71	-4.69	4.717	4.715			-9.84	-9.77
CV-24054	9/29/2025 9:40:14 AM	175.5	175.6	-1.73	-1.73	1.669	1.689			-4.49	-4.49
CV-24055	9/2/2025 11:04:57 AM	127.3	127.3	-0.27	-0.18	0.241	0.145			-7.65	-7.57
CV-24055	9/3/2025 9:50:00 AM										
CV-24055	9/3/2025 9:50:00 AM										
CV-24055	9/29/2025 12:51:51 PM	120.5	121.4	0.02	-0.02	0.000	0.026			-7.61	-7.48
CV-24055	9/29/2025 12:52:44 PM	121.5	121.5	-0.02	-0.01	0.021	0.021			-7.48	-7.50
CV-24056	9/4/2025 8:48:53 AM	160.0	160.0	-0.50	-0.50	0.489	0.490			-9.39	-10.14
CV-24056	9/4/2025 8:50:00 AM										
CV-24056	9/4/2025 8:50:00 AM										
CV-24056	9/10/2025 9:59:34 AM	151.9	151.8	-1.37	-1.35	1.384	1.370	0.0	0.0		
CV-24056	9/10/2025 10:00:00 AM										
CV-24056	9/18/2025 8:57:35 AM	161.9	161.8	-0.76	-0.75	0.782	0.749			-4.50	-4.48
CV-24056	9/24/2025 11:21:31 AM	161.2	161.0	-1.02	-1.02	0.981	0.989			-5.41	-5.29
CV-24057	9/8/2025 10:46:34 AM	122.5	122.5	-2.81	-2.78	0.031	0.022			-2.72	
CV-24057	9/26/2025 8:28:21 AM	120.3	120.4	-4.85	-4.85	0.119	0.119			-9.97	-9.97
CV-24058	9/3/2025 9:35:56 AM	106.6	107.0	-2.04	-2.08	2.057	2.091			-7.32	-7.70
CV-24058	9/16/2025 2:16:50 PM	112.7	113.0	-2.10	-2.10	2.067	2.054			-5.77	-5.82
CV-24058	9/17/2025 9:37:05 AM										
CV-24059	9/3/2025 9:53:15 AM	143.6	141.8	-0.47	-0.47	0.008	0.009	1.7	1.8	-8.32	-8.50
CV-24059	9/3/2025 9:54:19 AM	142.6	142.6	-0.48	-0.47	0.001	0.005	0.5	1.3	-8.16	-8.85
CV-24059	9/16/2025 2:22:20 PM	140.7	140.6	-0.37	-0.24	0.003	0.003	2.1	2.3	-7.80	-7.94

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24059	9/16/2025 2:22:48 PM	140.3	140.3	-0.19	-0.19	0.006	0.005	3.1	2.6	-8.03	-8.67
CV-24060	9/3/2025 10:17:43 AM	129.0	128.0	-1.95	-0.35	1.955	0.360			-7.92	-7.82
CV-24060	9/16/2025 2:01:22 PM	123.7	118.5	-3.82	-0.59	3.717	0.546			-8.43	-8.21
CV-24061	9/10/2025 1:37:18 PM	102.3	102.5	-2.61	-2.49	2.596	2.475			-9.09	-9.00
CV-24061	9/17/2025 9:57:04 AM										
CV-24061	9/18/2025 11:29:36 AM	96.9	97.3	-4.60	-4.60	4.618	4.623			-11.40	-11.42
CV-24062	9/5/2025 6:49:16 AM	152.1	149.2	-0.97	-0.75	0.965	0.741			-9.95	-10.16
CV-24062	9/5/2025 6:50:00 AM										
CV-24062	9/5/2025 6:50:00 AM										
CV-24062	9/10/2025 9:10:00 AM										
CV-24062	9/10/2025 9:10:00 AM										
CV-24062	9/11/2025 9:35:00 AM	155.6	155.3	-0.74	-0.77	0.735	0.761			-9.07	-9.10
CV-24062	9/17/2025 8:27:01 AM	154.2	154.0	-5.43	-5.41	5.728	5.697			-11.22	-11.02
CV-24062	9/24/2025 2:40:00 PM	147.9	149.3	-4.49	-4.58	4.431	4.556			-10.78	-10.25
CV-24063	9/9/2025 9:39:46 AM	135.8	135.4	-5.41	-0.02	5.731	0.007			-9.11	-9.16
CV-24063	9/9/2025 9:41:34 AM	135.0	134.7	-0.06	-0.06	0.050	0.044			-9.04	-8.93
CV-24063	9/15/2025 8:30:00 AM										
CV-24063	9/15/2025 8:30:00 AM										
CV-24063	9/26/2025 8:51:30 AM	165.8	165.7	1.16	-0.10	0.000	0.092			-9.62	-9.41
CV-24063	9/26/2025 8:53:44 AM	165.6	166.0	-0.16	-0.18	0.190	0.188			-9.16	-9.70
CV-24063	9/30/2025 2:31:24 PM	163.1	162.6	-1.15	-1.10	1.099	0.941			-10.49	-10.37
CV-24064	9/3/2025 10:50:00 AM										
CV-24064	9/3/2025 10:50:00 AM										
CV-24064	9/5/2025 6:24:17 AM	188.8	189.2	-3.93	-3.72	3.719	3.596			-9.93	-10.07
CV-24064	9/5/2025 9:44:00 AM										
CV-24064	9/5/2025 9:44:00 AM										
CV-24064	9/11/2025 8:49:26 AM	189.7	189.9	-1.37	-1.59	1.399	1.510			-9.99	-9.98
CV-24064	9/11/2025 8:50:00 AM										
CV-24064	9/17/2025 8:07:55 AM	190.2	190.0	-1.83	-0.65	1.986	0.700			-9.26	-9.24
CV-24065-TP17	9/2/2025 11:39:29 AM	114.9	115.1	-0.43	-0.40	0.401	0.362	0.0	0.0	-7.27	-7.24
CV-24065-TP17	9/3/2025 9:55:00 AM										
CV-24065-TP17	9/3/2025 9:55:00 AM										
CV-24065-TP17	9/5/2025 1:45:04 PM	122.2	121.9	-0.42	-0.48	0.433	0.499			-8.06	-7.96
CV-24065-TP17	9/10/2025 10:45:53 AM	113.0	113.2	-0.64	-0.70	0.656	0.726			-10.23	-10.43

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24065-TP17	9/29/2025 1:03:31 PM	113.2	112.5	-3.35	-1.44	3.305	1.443			-7.30	-7.64
CV-24066	9/2/2025 10:20:16 AM	112.8	117.3	-0.83	-0.73	0.890	0.752			-5.89	-5.94
CV-24066	9/9/2025 9:05:00 AM										
CV-24066	9/9/2025 9:05:00 AM										
CV-24066	9/17/2025 8:47:58 AM	118.5	118.2	-0.56	-0.41	0.567	0.413			-6.76	-7.90
CV-24067	9/8/2025 10:41:44 AM	124.9	125.1	-3.17	-2.75	0.028	0.028	0.0	0.0	-7.38	
CV-24067	9/23/2025 8:36:00 AM	129.0	127.5	-4.58	-3.50	0.042	0.037	3.9	3.6	-7.97	-8.07
CV-24068	9/11/2025 12:47:05 PM	116.2	116.2	-0.22	-0.21	0.206	0.205			-5.91	-5.88
CV-24068	9/18/2025 10:59:15 AM	122.5	122.4	-0.43	-0.42	0.444	0.433			-9.21	-9.20
CV-24069	9/3/2025 10:37:15 AM	119.1	118.9	-1.30	-0.39	1.297	0.400			-7.46	-7.82
CV-24069	9/10/2025 9:30:00 AM										
CV-24069	9/10/2025 9:30:00 AM										
CV-24069	9/18/2025 11:10:36 AM	77.2	77.1	-8.07	-7.80	8.208	7.951			-9.87	-9.98
CV-24070	9/3/2025 10:25:01 AM	132.2	132.2	-0.06	-0.07	1.019	0.982	6.9	6.7	-8.17	-7.83
CV-24070	9/3/2025 10:28:46 AM	132.1	132.0	-0.02	-0.09	0.999	1.218	6.8	7.5	-8.05	-8.08
CV-24070	9/10/2025 9:45:00 AM										
CV-24070	9/10/2025 9:45:00 AM										
CV-24070	9/18/2025 11:16:50 AM	127.3	127.0	-1.89	-1.68	1.206	0.751	7.5	5.9	-11.03	-11.48
CV-24071	9/10/2025 9:40:00 AM										
CV-24071	9/10/2025 9:40:00 AM										
CV-24071	9/10/2025 1:26:51 PM	133.7	133.8	-4.74	-4.44	2.898	2.855	20.9	20.8	-9.05	-9.15
CV-24071	9/10/2025 1:28:08 PM	133.9	133.8	-4.54	-4.54	2.670	2.809	20.1	20.6	-9.02	-9.12
CV-24071	9/18/2025 11:26:39 AM	128.2	128.3	-7.05	-6.87	1.834	1.771	16.7	16.4	-10.01	-9.10
CV-24072	9/11/2025 10:19:27 AM	97.6	99.1	4.39	-0.10	0.000	0.095			-9.53	-8.35
CV-24072	9/11/2025 10:20:49 AM	99.6	99.7	-0.33	-0.33	0.319	0.323			-8.35	-8.33
CV-24072	9/18/2025 8:57:56 AM	97.1	98.8	-4.12	-3.50	4.164	3.539			-8.07	-8.24
CV-24073-TP13	9/9/2025 9:52:51 AM	136.9	137.3	-0.75	-0.76	0.724	0.731			0.50	0.51
CV-24073-TP13	9/9/2025 9:54:05 AM	137.2	137.4	-0.73	-0.77	0.699	0.741			0.47	0.49
CV-24073-TP13	9/14/2025 12:49:28 PM	133.6	130.7	-3.74	-1.11	3.711	1.096			-6.51	-8.38
CV-24073-TP13	9/14/2025 12:50:48 PM	130.6	130.9	-0.82	-0.86	0.804	0.851			-8.27	-8.55
CV-24073-TP13	9/18/2025 8:38:00 AM	133.4	131.9	-6.38	-3.54	6.459	3.529			-10.50	-10.66
CV-24073-TP13	9/18/2025 8:39:42 AM	128.5	129.5	-1.74	-1.61	1.745	1.621			-10.87	-10.43

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24074	9/5/2025 2:09:04 PM	117.2	117.3	-0.05	-0.12	0.054	0.128			-5.53	-5.36
CV-24074	9/12/2025 10:31:27 AM	115.9	115.6	-0.20	-0.30	0.234	0.197			-8.14	-6.10
CV-24074	9/18/2025 8:46:15 AM	94.6	100.1	-1.52	-1.32	1.533	1.400			-5.75	-4.52
CV-24075-TP15	9/5/2025 6:38:38 AM	178.1	181.9	-2.78	-2.84	2.764	2.831			0.02	0.02
CV-24075-TP15	9/5/2025 6:43:00 AM										
CV-24075-TP15	9/5/2025 6:43:00 AM										
CV-24075-TP15	9/10/2025 11:13:25 AM										
CV-24075-TP15	9/11/2025 9:14:51 AM	180.1	180.3	-5.08	-5.25	5.370	5.554			0.37	0.35
CV-24075-TP15	9/11/2025 9:15:00 AM										
CV-24075-TP15	9/17/2025 8:12:05 AM	184.9	184.7	-5.94	-5.78	5.997	5.916			0.31	0.31
CV-24076	9/2/2025 1:44:10 PM	128.8	129.1	0.06	-0.02	0.000	0.020			-8.96	-8.93
CV-24076	9/2/2025 1:44:46 PM	129.6	129.7	-0.08	-0.02	0.082	0.026			-8.81	-9.04
CV-24077	9/2/2025 9:43:04 AM	142.0	135.2	-2.95	-0.95	2.965	0.964			-6.82	-6.72
CV-24077	9/2/2025 9:54:12 AM	129.2	129.3	-1.00	-0.27	1.019	0.298			-6.80	-6.08
CV-24077	9/17/2025 8:44:36 AM	129.6	126.2	-1.99	-1.69	2.016	1.729			-7.81	-8.94
CV-24078	9/8/2025 10:36:46 AM	127.2	127.3	-1.05	-0.93	-0.012	-0.024	0.0	0.0	-7.23	
CV-24078	9/23/2025 8:28:46 AM	124.5	124.5	-0.84	-0.84	0.133	0.136	7.0	7.0	-6.61	-9.76
CV-24079-TP8	9/4/2025 10:32:00 AM	116.7	146.7	-0.26	-0.07	0.264	0.072			-6.30	-1.49
CV-24079-TP8	9/11/2025 10:43:31 AM	147.1	149.2	-0.16	-0.19	0.170	0.199			-6.21	-6.20
CV-24079-TP8	9/11/2025 10:44:00 AM										
CV-24079-TP8	9/17/2025 9:30:11 AM	151.3	151.0	-2.01	-2.01	2.008	2.001			-7.51	-7.42
CV-24079-TP8	9/24/2025 1:54:29 PM	148.4	148.1	-2.08	-2.06	1.995	2.004			-8.30	-8.32
CV-24080	9/3/2025 10:43:46 AM	122.5	121.7	-1.61	-0.56	1.453	0.197	23.0	8.5	-6.39	-6.50
CV-24080	9/26/2025 8:39:34 AM	116.3	116.2	-2.30	-2.20	0.000	0.000			-11.53	-11.55
CV-24081-TP10	9/3/2025 1:35:47 PM	122.5	122.4	-2.76	-1.34	2.785	1.352			-7.04	-7.12
CV-24081-TP10	9/17/2025 1:56:55 PM										
CV-24081-TP10	9/18/2025 9:15:56 AM	114.9	114.3	-3.21	-2.81	3.218	2.820			-9.71	-9.85
CV-24082	9/3/2025 9:26:31 AM	119.9	120.1	-2.12	-0.42	2.132	0.425			-4.77	-5.74
CV-24082	9/17/2025 1:34:05 PM										
CV-24082	9/18/2025 9:12:44 AM	122.7	122.7	-3.08	-2.51	3.080	2.518			-9.32	-10.26

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24083	9/11/2025 10:33:03 AM	138.4	130.7	-4.73	-0.28	4.764	0.286			-8.59	-9.09
CV-24083	9/11/2025 10:34:54 AM	128.8	129.8	-0.13	-0.11	0.135	0.108			-9.36	-9.23
CV-24083	9/11/2025 1:34:03 PM	109.5	113.7	1.06	0.28	0.000	0.000			-8.22	-8.22
CV-24083	9/11/2025 1:35:12 PM	117.2	118.4	-0.03	-0.11	0.041	0.527			-8.00	-7.67
CV-24083	9/18/2025 11:21:42 AM	128.5	128.6	-2.25	-1.80	2.267	1.957			-10.01	-9.95
CV-24084-TP11	9/15/2025 10:12:22 AM	166.9	169.7	14.33	-0.18	0.000	0.199			-11.43	-10.72
CV-24084-TP11	9/15/2025 10:16:30 AM	169.7	168.7	-4.06	-0.93	4.073	0.926			-10.74	-11.25
CV-24084-TP11	9/17/2025 9:01:42 AM	169.0	169.6	-1.87	-1.89	1.895	1.891			-9.11	-9.12
CV-24084-TP11	9/25/2025 10:16:39 AM	168.9	168.9	-1.29	-1.33	1.275	1.329			-8.55	-9.52
CV-24085	9/4/2025 1:58:05 PM	126.7	126.7	-0.10	-0.10	0.818	0.820	17.4	17.4	-6.32	
CV-24085	9/21/2025 12:33:53 PM	125.3	125.1	-0.74	-0.57	1.264	0.716	21.5	16.2	-10.46	-10.49
CV-24086	9/4/2025 2:12:10 PM	116.1	116.1	-0.16	-0.16	-0.061	-0.063	0.0	0.0		
CV-24086	9/17/2025 2:10:47 PM										
CV-24086	9/18/2025 10:50:47 AM	119.3	117.0	-0.83	-0.74	0.000	0.000			-9.80	-9.89
CV-24087	9/4/2025 2:42:56 PM	117.9	117.9	-0.31	-0.31	0.018	0.021	0.0	0.0	-6.36	
CV-24087	9/18/2025 10:37:04 AM	114.1	114.1	-1.17	-1.17	0.002	0.017	0.8	2.5	-8.88	-8.90
CV-24088	9/15/2025 10:01:29 AM	115.2	116.4	0.61	-0.93	0.000	0.923			-11.62	-11.58
CV-24088	9/15/2025 10:07:06 AM	122.1	122.2	-1.14	-0.92	1.141	0.913			-11.36	-11.38
CV-24088	9/16/2025 1:44:00 PM	126.6	127.8	0.67	-0.32	0.000	0.316			-6.86	-6.84
CV-24088	9/16/2025 1:44:47 PM	128.0	128.2	-0.37	-0.37	0.358	0.357			-6.62	-6.61
CV-24089	9/3/2025 10:39:27 AM										
CV-24089	9/4/2025 11:34:01 AM	125.7	125.7	-0.89	-0.90	0.202	0.201	18.0	17.9	-6.46	
CV-24089	9/23/2025 10:35:49 AM	101.1	101.7	-10.72	-10.70	0.191	0.219	8.4	9.0	-10.97	-10.92
CV-24090	9/4/2025 2:55:25 PM	111.3	111.3	-5.38	-5.38	5.578	5.582	0.0	0.0	-6.78	
CV-24090	9/18/2025 12:50:51 PM	108.3	108.4	-7.72	-4.85	7.653	4.882			-10.37	-10.74
CV-24090	9/18/2025 1:02:54 PM	105.9	105.5	-4.31	-1.71	4.339	1.710			-10.61	-11.15
CV-24091	9/3/2025 1:51:33 PM	126.9	126.9	-3.23	-3.24	0.602	0.602	9.3	9.3	-3.82	-3.85

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24091	9/18/2025 8:49:34 AM	125.1	125.0	-4.76	-4.76	0.711	0.720	51.9	52.2	-5.69	-5.76
CV-24091	9/18/2025 8:54:49 AM	124.0	124.2	-3.30	-2.47	4.544	1.047	40.4	19.4	-7.16	-7.89
CV-24092	9/9/2025 11:04:26 AM	115.8	115.8	-5.79	-5.79	0.893	0.831	58.6	56.5	-6.64	-6.60
CV-24092	9/18/2025 12:14:08 PM	116.4	116.5	-8.77	-8.73	1.409	1.323	73.1	70.9	-10.40	-10.29
CV-24092	9/18/2025 12:20:59 PM	116.0	116.1	-5.39	-5.41	4.554	4.547	40.6	40.5	-9.28	-9.20
CV-24093	9/3/2025 11:15:17 AM	126.7	127.7	-0.11	-0.25	7.033	7.671	32.8	34.2	-11.76	-11.86
CV-24093	9/22/2025 10:02:13 AM	92.2	95.7	0.09	-0.06	0.133	0.025	4.7	2.0	-16.04	-16.08
CV-24093	9/22/2025 10:06:08 AM	86.1	87.3	-0.10	-0.10	0.251	0.251	10.7	10.7	-15.77	-15.77
CV-24093	9/22/2025 10:10:33 AM	83.0	82.0	-0.09	-0.09	0.775	0.778	6.2	6.3	-15.76	-15.93
CV-24094	9/3/2025 10:11:52 AM										
CV-24094	9/10/2025 9:44:46 AM										
CV-24094	9/11/2025 8:53:46 AM	97.4	99.4	-2.61	-4.68	0.702	1.565	2.6	3.8	-9.22	-9.12
CV-24094	9/11/2025 1:09:03 PM	108.5	108.9	-0.05	-0.14	4.816	4.982	15.2	15.4	-3.98	-3.81
CV-24094	9/16/2025 9:15:41 AM										
CV-24094	9/25/2025 10:19:22 AM										
CV-24095	9/8/2025 9:15:00 AM										
CV-24095	9/8/2025 9:15:00 AM										
CV-24095	9/8/2025 9:30:00 AM										
CV-24095	9/8/2025 2:36:21 PM	124.3	128.0	-5.87	-4.20	5.480	4.338	0.0	0.0	-5.15	
CV-24095	9/18/2025 2:48:19 PM	129.6	127.1	-4.81	-4.39	4.728	4.502			0.06	0.06
CV-24096	9/8/2025 2:22:07 PM	106.8	107.3	-0.21	-0.14	0.204	0.106	0.0	0.0	-0.12	
CV-24096	9/8/2025 2:23:48 PM	107.0	107.0	-0.07	-0.07	0.166	0.164	0.0	0.0	-0.08	
CV-24096	9/10/2025 12:28:40 PM	96.1	96.3	-0.29	-0.23	0.253	0.263			-0.34	-0.34
CV-24096	9/10/2025 12:29:19 PM	97.0	97.0	-0.29	-0.32	0.298	0.298			-0.33	-0.30
CV-24096	9/26/2025 8:42:20 AM	116.7	116.8	-1.89	-1.66	1.844	1.615			0.26	0.26
CV-24097	9/8/2025 2:15:19 PM	89.8	87.9	-1.50	-0.56	1.452	0.662	0.0	0.0	-1.50	
CV-24097	9/17/2025 11:07:58 AM	99.5	98.5	11.36	-0.92	0.000	0.817			-0.92	-0.91
CV-24097	9/17/2025 11:08:45 AM	97.9	97.8	-1.15	-1.09	1.101	1.031			-0.97	-1.00
CV-24098	9/2/2025 2:33:25 PM	100.1	101.9	-3.08	-3.08	3.099	3.088			-3.45	-3.43
CV-24098	9/18/2025 2:37:11 PM	108.9	109.5	-6.00	-5.84	5.964	5.773			-6.31	-6.19
CV-24099	9/2/2025 2:22:52 PM	109.6	109.8	-2.21	-2.23	2.210	2.239			-2.28	-2.31
CV-24099	9/8/2025 9:45:58 AM	94.8	94.8	8.71	-0.50	0.000	1.024			-4.35	-4.39

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24099	9/8/2025 9:47:03 AM	95.6	95.6	-0.52	-0.56	0.547	0.591			-4.39	-4.32
CV-24099	9/9/2025 1:28:04 PM										
CV-24099	9/17/2025 10:47:54 AM	108.8	109.7	-0.34	-0.32	0.309	0.291			-2.71	-2.70
CV-24100	9/2/2025 2:04:58 PM	142.4	141.4	-1.91	-1.78	1.923	1.769			-2.14	-2.16
CV-24100	9/2/2025 2:06:02 PM	142.8	141.4	-1.57	-1.57	1.589	1.610			-2.28	-2.37
CV-24100	9/8/2025 8:45:00 AM										
CV-24100	9/8/2025 8:45:00 AM										
CV-24100	9/18/2025 2:29:29 PM	144.4	144.2	-1.40	-0.09	1.409	0.104			-5.37	-5.44
CV-24100	9/18/2025 2:32:23 PM	144.6	144.1	-0.05	-0.06	0.056	0.068			-5.38	-5.37
CV-24101	9/2/2025 2:00:02 PM	116.2	116.0	-1.53	-1.39	1.548	1.398			-1.95	-1.92
CV-24101	9/8/2025 8:40:00 AM										
CV-24101	9/8/2025 8:40:00 AM										
CV-24101	9/17/2025 10:22:43 AM	112.2	112.2	-4.66	-4.58	4.630	4.532			0.68	0.68
CV-24102	9/8/2025 9:18:43 AM	111.8	111.8	-1.78	-1.77	1.756	1.756	0.0	0.0	-8.82	
CV-24102	9/17/2025 9:38:43 AM	116.8	116.8	-2.18	-2.17	2.115	2.108			-10.15	-10.03
CV-24103	9/4/2025 8:42:44 AM	114.7	114.9	-0.98	-0.89	3.135	2.601	22.4	20.4	-9.04	
CV-24103	9/17/2025 1:22:44 PM	117.7	117.8	-0.65	-0.65	3.353	3.378	35.0	35.2	-9.29	-9.22
CV-24103	9/30/2025 9:42:10 AM										
CV-24104	9/4/2025 9:55:02 AM	114.4	114.4	-2.09	-2.09	0.158	0.159	5.0	5.1	-8.48	
CV-24104	9/10/2025 11:08:23 AM	111.9	112.0	-2.06	-2.13	0.086	0.120	5.6	6.7	-8.61	-8.63
CV-24104	9/17/2025 1:13:15 PM	116.4	116.4	-1.48	-1.47	0.082	0.092	5.5	5.8	-9.13	-9.41
CV-24104	9/30/2025 9:33:12 AM										
CV-24105	9/4/2025 9:49:04 AM	108.9	109.0	-0.45	-0.45	0.646	0.645	10.1	10.1	-8.44	
CV-24105	9/17/2025 1:06:55 PM	111.9	111.9	-0.18	-0.19	0.000	0.000			-9.12	-9.25
CV-24105	9/30/2025 9:10:47 AM										
CV-24106	9/4/2025 11:03:25 AM	124.3	120.9	-0.94	-0.66	0.042	0.044	8.3	8.6	-9.40	
CV-24106	9/17/2025 10:00:21 AM	119.2	119.1	-0.61	-0.61	0.056	0.054			0.30	0.31
CV-24106	9/25/2025 2:39:04 PM	116.9	117.9	-0.28	-0.40	0.165	0.188	0.0	0.0	-11.57	
CV-24107	9/10/2025 2:01:13 PM	118.6	118.8	-1.15	-1.15	1.106	1.080			-8.77	-8.51
CV-24108	9/10/2025 1:14:32 PM	125.4	125.6	-0.23	-0.22	0.014	0.020			-0.13	-0.07
CV-24109	9/9/2025 2:45:16 PM	110.8	111.2	-1.78	-1.39	1.745	1.334			-10.21	-10.65
CV-24110	9/3/2025 10:26:09 AM	128.0	127.9	-0.96	-0.77	2.391	1.489	10.4	8.2	-8.99	-9.20

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24110	9/11/2025 10:30:33 AM	125.1	125.4	-0.78	-0.85	0.000	0.000			-10.46	-10.45
CV-24111	9/3/2025 10:30:26 AM	125.6	125.7	-0.84	-0.86	0.810	0.802			-8.53	-8.62
CV-24111	9/11/2025 10:43:06 AM	119.5	119.5	-1.15	-1.22	1.203	1.252			-10.05	-9.82
CV-24112	9/3/2025 10:16:20 AM	122.8	123.2	-1.04	-0.99	1.027	1.086	6.9	7.1	-9.45	-9.40
CV-24112	9/10/2025 1:35:13 PM										
CV-24112	9/11/2025 2:03:06 PM	129.0	128.3	-1.05	-1.13	1.055	1.150			-10.29	-10.08
CV-24113	9/8/2025 9:04:58 AM	97.8	101.7	-6.21	-7.04	0.024	-0.031	0.0	0.0	-9.05	
CV-24113	9/15/2025 10:30:40 AM	111.6	105.3	-7.31	-7.41	0.083	0.091			-10.67	-10.50
CV-24114	9/10/2025 1:55:47 PM										
CV-24114	9/15/2025 2:35:15 AM	119.8	120.4	-7.43	-7.96	-0.815	-0.886	0.0	0.0	-10.56	
CV-24115	9/5/2025 8:24:13 AM	96.9	97.3	-7.86	-7.19	-0.084	-0.081	0.0	0.0	-8.23	
CV-24115	9/10/2025 2:15:03 PM										
CV-24115	9/24/2025 10:09:43 AM	101.7	102.0	-9.74	-10.34	-0.133	-0.054	0.0	0.0	-10.36	
CV-24116	9/5/2025 8:41:41 AM	122.9	123.1	-3.31	-3.30	3.310	3.310	0.0	0.0	-10.71	
CV-24116	9/18/2025 9:38:02 AM	116.0	116.0	-7.80	-7.87	8.023	8.039			0.18	0.13
CV-24116	9/26/2025 9:12:19 AM	118.2	118.3	-7.39	-7.47	7.610	7.686			-9.60	-9.64
CV-24117	9/10/2025 10:29:11 AM	101.7	101.8	-1.31	-1.31	1.297	1.289			0.34	0.34
CV-24118	9/4/2025 2:46:28 PM	143.8	143.4	-8.73	-2.33	8.845	2.350			-8.58	-10.00
CV-24118	9/4/2025 2:49:20 PM	141.7	141.7	-0.41	-0.11	0.446	0.137			-10.08	-9.58
CV-24119	9/11/2025 9:30:21 AM	143.5	143.9	-0.90	-0.90	0.877	0.874			0.29	0.29
CV-24119	9/11/2025 9:32:05 AM	142.0	143.1	-0.90	-0.90	0.877	0.872			0.34	0.33
CV-24120	9/9/2025 9:41:57 AM	129.4	127.9	-5.75	-5.47	5.803	5.433			-6.59	-6.19
CV-24120	9/9/2025 9:42:55 AM	127.9	128.2	-5.37	-5.37	5.368	5.368			-6.09	-6.09
CV-24120	9/11/2025 9:00:00 AM										
CV-24120	9/11/2025 9:00:00 AM										
CV-24120	9/29/2025 9:37:29 AM	126.7	126.4	-4.86	-4.45	4.965	4.416			-5.40	-5.36
CV-24121	9/2/2025 9:45:00 AM										
CV-24121	9/2/2025 9:45:00 AM										
CV-24121	9/9/2025 9:34:59 AM	121.3	121.3	-4.53	-3.07	4.578	3.068			-7.83	-7.81
CV-24121	9/9/2025 2:05:11 PM										
CV-24121	9/29/2025 9:30:55 AM	118.8	119.9	-2.75	-2.75	2.794	2.794			-6.30	-6.30

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24122	9/2/2025 9:30:00 AM										
CV-24122	9/2/2025 9:30:00 AM										
CV-24122	9/9/2025 9:27:27 AM	120.5	120.4	-7.49	-7.39	0.722	0.847	3.7	4.0	-9.45	-9.63
CV-24122	9/29/2025 9:57:41 AM	119.8	120.9	-6.53	-9.57	0.380	0.752	2.7	3.7	-8.26	-10.85
CV-24123	9/9/2025 2:22:03 PM										
CV-24123	9/17/2025 2:05:12 PM	117.0	117.3	-0.33	-0.75	0.243	0.573	9.5	14.6	-2.53	-2.78
CV-24124	9/5/2025 2:10:36 PM	122.9	116.1	-2.89	-0.23	2.799	0.203			-6.94	-6.39
CV-24125-TP20	9/3/2025 8:50:00 AM										
CV-24125-TP20	9/3/2025 8:50:00 AM										
CV-24125-TP20	9/10/2025 10:36:51 AM										
CV-24125-TP20	9/29/2025 9:13:59 AM	112.8	112.6	-8.56	-4.49	8.750	4.447			-8.44	-8.75
CV-24126	9/11/2025 1:31:45 PM	163.8	163.8	-0.14	-0.12	0.146	0.119			-8.15	-7.98
CV-24126	9/11/2025 1:32:45 PM	163.4	163.2	-0.11	-0.10	0.067	0.033			-7.88	-8.13
CV-24126	9/18/2025 11:42:24 AM	174.1	174.2	-2.52	-2.40	2.515	2.417			-12.14	-12.61
CV-24126	9/22/2025 1:07:42 PM	184.9	185.5	-8.03	-7.82	7.579	7.329			-10.20	-10.09
CV-24127	9/2/2025 10:20:00 AM										
CV-24127	9/2/2025 10:20:00 AM										
CV-24127	9/5/2025 2:23:46 PM	111.4	113.1	-3.87	-2.61	3.688	2.422			-9.28	-9.52
CV-24127	9/30/2025 12:59:10 PM	102.7	100.6	-9.09	-1.57	9.365	1.576			-9.94	-11.08
CV-24127	9/30/2025 1:32:54 PM	101.0	101.2	-0.94	-0.94	0.941	0.935			-11.15	-11.05
CV-24128	9/2/2025 10:00:00 AM										
CV-24128	9/2/2025 10:00:00 AM										
CV-24128	9/5/2025 1:54:54 PM	119.4	118.0	-5.22	-1.49	5.403	1.433			-7.47	-7.92
CV-24129	9/5/2025 1:50:28 PM	128.1	128.6	-1.19	-1.20	1.129	1.117			-7.47	-7.49
CV-24130	9/29/2025 9:03:27 AM	103.5	103.5	-0.59	-0.59	0.585	0.585			-7.83	-7.83
CV-24131	9/3/2025 9:05:01 AM										
CV-24131	9/10/2025 8:55:13 AM										
CV-24131	9/16/2025 8:19:01 AM										
CV-24131	9/24/2025 1:20:08 PM										
CV-24131	9/29/2025 8:45:14 AM	110.4	130.3	0.51	-0.03	0.003	0.025	1.1	3.0	-6.82	-6.72
CV-24131	9/29/2025 8:48:13 AM	134.9	134.7	-0.10	-0.02	0.023	0.026	9.3	10.0	-6.73	-6.67
CV-24131	9/29/2025 8:50:41 AM	135.4	135.4	-0.05	-0.01	0.132	0.135	6.9	7.0	-6.72	-6.72
CV-24132	9/11/2025 1:21:43 PM										
CV-24132	9/22/2025 2:27:44 PM	130.1	130.0	-4.68	-3.95	0.034	0.034	11.3	11.4	-8.67	-8.58
CV-24133	9/22/2025 1:57:31 PM	120.5	120.5	-3.46	-3.45	1.786	1.823	25.5	25.8	-7.54	-7.53

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24134-TP19	9/8/2025 8:34:35 AM	136.4	127.0	-8.44	-3.41	8.609	3.419			-10.21	-10.66
CV-24134-TP19	9/8/2025 8:35:59 AM	126.5	125.2	-1.73	-1.73	1.745	1.742			-10.54	-10.52
CV-24135	9/2/2025 10:22:28 AM	150.4	150.1	-0.07	-0.07	0.043	0.042			-8.43	-8.31
CV-24135	9/2/2025 10:23:00 AM										
CV-24135	9/8/2025 8:28:16 AM	150.3	150.4	-1.01	-0.25	1.030	0.262			-10.46	-10.53
CV-24135	9/8/2025 8:30:00 AM										
CV-24135	9/15/2025 2:35:35 PM	150.7	150.7	-1.81	-1.80	1.778	1.749			-9.34	-9.39
CV-24135	9/15/2025 2:48:00 PM										
CV-24135	9/22/2025 1:33:27 PM	150.8	150.6	-1.72	-1.84	2.240	2.357			-6.50	-6.76
CV-24135	9/25/2025 10:20:13 AM	147.9	148.3	-0.14	-0.22	0.213	0.527	0.0	0.0	-9.36	
CV-24135	9/25/2025 10:25:49 AM	148.4	148.1	-0.33	-0.22	0.141	0.257	0.0	0.0	-9.35	
CV-24135	9/29/2025 8:53:02 AM	150.8	150.7	-1.08	-1.10	1.056	1.069			-6.98	-7.08
CV-24136	9/2/2025 2:27:57 PM	132.4	133.0	-0.21	-0.22	0.189	0.190			-8.26	-8.12
CV-24136	9/2/2025 2:29:10 PM	133.8	133.8	-0.37	-0.23	0.357	0.205			-8.15	-8.34
CV-24137	9/4/2025 11:18:53 AM	99.7	100.0	-0.62	-0.62	0.613	0.611			-8.22	-8.24
CV-24138	9/4/2025 9:30:00 AM										
CV-24138	9/4/2025 9:30:00 AM										
CV-24138	9/10/2025 9:06:38 AM	74.2	74.2	-9.30	-9.27	9.325	9.305			-9.96	-9.45
CV-24138	9/26/2025 9:09:34 AM	154.1	163.1	-7.93	-1.64	8.045	1.575			-7.84	-8.09
CV-24138	9/30/2025 2:04:46 PM	183.1	183.9	-3.48	-3.47	3.375	3.405			-0.06	-0.06
CV-24139	9/4/2025 9:25:00 AM										
CV-24139	9/4/2025 9:25:00 AM										
CV-24139	9/10/2025 9:10:08 AM	106.3	106.4	-0.45	-0.47	0.438	0.461			-8.88	-10.00
CV-24139	9/26/2025 9:16:26 AM	110.0	110.1	-0.54	-0.57	0.525	0.555			-8.36	-8.65
CV-24140	9/4/2025 9:20:00 AM										
CV-24140	9/4/2025 9:20:00 AM										

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24140	9/4/2025 9:44:56 AM	169.6	170.7	-1.79	-1.79	1.777	1.770			-7.76	-7.93
CV-24140	9/4/2025 9:46:00 AM										
CV-24140	9/4/2025 9:46:00 AM										
CV-24140	9/10/2025 1:44:43 PM	132.2	133.0	-3.07	-3.05	2.983	3.021	0.0	0.0	-8.22	
CV-24140	9/10/2025 1:47:00 PM										
CV-24140	9/12/2025 2:03:32 PM	158.9	161.4	-3.54	-3.55	3.469	3.464			-9.52	-10.02
CV-24140	9/18/2025 10:57:14 AM	151.8	153.0	-4.53	-4.61	4.528	4.615			-11.42	-11.30
CV-24140	9/24/2025 8:35:53 AM	164.9	169.5	-9.40	-9.25	9.602	9.386			-10.86	-10.89
CV-24141	9/4/2025 9:10:00 AM										
CV-24141	9/4/2025 9:10:00 AM										
CV-24141	9/12/2025 8:37:12 AM	74.6	73.5	-6.38	-6.38	6.458	6.531			-8.08	-8.32
CV-24141	9/17/2025 2:05:06 PM	107.9	107.8	-7.52	-7.43	7.722	7.465			-7.57	-7.78
CV-24141	9/17/2025 2:07:40 PM	108.3	108.2	-8.81	-8.80	9.034	9.020			-7.59	-7.31
CV-24142	9/4/2025 9:51:54 AM	166.0	166.8	-0.35	-0.44	0.379	0.441			-0.92	-1.10
CV-24142	9/4/2025 9:53:00 AM										
CV-24142	9/4/2025 9:53:00 AM										
CV-24142	9/8/2025 9:15:00 AM										
CV-24142	9/8/2025 9:30:00 AM										
CV-24142	9/10/2025 1:52:20 PM	137.7	137.7	-1.33	-1.35	1.463	1.456	0.0	0.0		
CV-24142	9/24/2025 2:22:25 PM	151.1	152.2	-0.99	-0.94	0.980	0.952			-1.68	-1.49
CV-24142	9/24/2025 2:22:58 PM	150.8	148.8	-0.86	-0.71	0.913	0.710			-1.12	-1.18
CV-24142	9/30/2025 2:12:50 PM	156.0	155.2	-1.29	-1.23	1.258	1.186			-1.25	-1.40
CV-24142	9/30/2025 2:15:54 PM	151.1	151.1	-1.13	-1.11	1.108	1.083			-1.42	-1.42
CV-24143	9/4/2025 9:15:00 AM										
CV-24143	9/4/2025 9:15:00 AM										
CV-24143	9/10/2025 8:52:16 AM	68.7	68.6	1.86	1.81	0.000	0.000			0.01	0.02
CV-24143	9/10/2025 8:53:21 AM	68.7	68.7	1.88	1.88	0.000	0.000			0.01	0.00
CV-24143	9/26/2025 9:20:08 AM	79.9	80.3	1.96	1.82	0.000	0.000			0.26	0.24
CV-24143	9/26/2025 9:22:02 AM	79.3	78.8	1.77	1.89	0.000	0.000			0.26	0.26
CV-24144	9/8/2025 2:04:31 PM	108.2	108.2	-0.96	-0.96	1.005	1.001	0.0	0.0	-0.93	
CV-24144	9/17/2025 11:12:19 AM	105.1	105.2	-1.34	-1.30	1.225	1.225			0.76	0.89

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24145	9/3/2025 10:28:27 AM	182.1	181.9	-2.39	-1.77	0.011	0.007	1.2	1.0	-2.86	-2.85
CV-24145	9/3/2025 10:30:00 AM										
CV-24145	9/3/2025 10:30:00 AM										
CV-24145	9/9/2025 10:54:17 AM	185.1	186.0	-1.85	-1.82	0.801	0.827	10.6	10.8	-8.49	-8.49
CV-24145	9/9/2025 10:55:00 AM										
CV-24145	9/16/2025 9:38:53 AM	185.8	185.7	-2.31	-2.31	0.013	0.018	1.3	1.6	-11.66	-11.69
CV-24145	9/16/2025 9:40:00 AM										
CV-24145	9/17/2025 8:30:14 AM										
CV-24145	9/23/2025 8:05:10 AM	183.5	183.3	-3.38	-3.38	0.655	0.629	21.5	21.1	-13.15	-13.29
CV-24145	9/30/2025 10:58:02 AM	184.0	183.6	-1.44	-1.46	0.000	0.000			-12.04	-11.95
CV-24146	9/2/2025 1:10:17 PM	114.5	114.5	-1.90	-1.84	0.589	0.693	16.0	17.3	-2.38	-2.39
CV-24146	9/4/2025 1:50:34 PM										
CV-24146	9/16/2025 12:53:02 PM	114.9	114.9	-1.93	-1.90	0.690	0.693	17.3	17.3	-2.52	-2.38
CV-24146	9/16/2025 12:54:53 PM	114.9	115.0	-2.08	-2.08	0.401	0.416	17.6	17.9	-2.35	-2.47
CV-24147	9/2/2025 1:06:07 PM	117.7	117.8	-2.47	-2.42	0.302	0.289	21.8	21.3	-3.02	-3.02
CV-24147	9/16/2025 12:58:32 PM	117.7	117.8	-2.51	-2.52	0.223	0.224	18.7	18.8	-2.68	-2.69
CV-24148	9/8/2025 1:50:05 PM	143.5	135.7	2.48	-0.07	0.000	0.067			-8.42	-7.13
CV-24148	9/8/2025 1:50:56 PM	136.8	136.9	-0.19	-0.21	0.154	0.168			-7.21	-7.17
CV-24148	9/11/2025 11:20:16 AM	157.9	157.8	-0.55	-0.42	0.579	0.442			-8.26	-8.46
CV-24148	9/11/2025 11:23:07 AM	157.8	156.9	-0.35	-0.26	0.363	0.291			-8.50	-8.55
CV-24148	9/11/2025 1:20:00 PM										
CV-24148	9/18/2025 1:44:58 PM	162.1	162.4	1.47	1.51	0.000	0.000			0.71	0.73
CV-24148	9/18/2025 1:45:48 PM	162.3	162.3	1.51	1.50	0.000	0.000			0.67	0.71
CV-24149	9/3/2025 10:12:29 AM										
CV-24149	9/8/2025 2:03:34 PM	113.5	113.5	-0.21	-0.20	0.026	0.044	4.0	5.1	-8.19	-8.29
CV-24149	9/10/2025 9:58:14 AM										
CV-24149	9/16/2025 9:27:40 AM										
CV-24149	9/18/2025 11:37:29 AM	112.4	112.3	-0.10	-0.12	0.005	0.014	4.5	7.3	-1.33	-1.38
CV-24150	9/9/2025 1:28:17 PM	104.3	104.2	-0.64	-0.62	0.573	0.559			-7.37	-7.02
CV-24151	9/14/2025 12:54:25 PM	106.3	106.3	-3.69	-3.69	3.731	3.731			-5.88	-5.88
CV-24151	9/18/2025 8:34:26 AM	106.1	107.1	-0.96	-0.95	0.972	0.957			-10.41	-10.24
CV-24152	9/14/2025 1:00:39 PM	118.8	118.4	-0.19	-0.11	0.965	0.517	12.3	9.0	-6.33	-6.97
CV-24152	9/19/2025 11:01:16 AM	117.3	118.8	-0.05	-0.08	0.000	0.000			-8.12	-7.23
CV-24153	9/15/2025 12:43:12 PM	105.8	105.7	-0.46	-0.46	0.434	0.434			-0.52	-0.51

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24153	9/16/2025 10:30:17 AM	105.2	107.1	-0.21	-0.46	0.211	0.465			-0.82	-0.91
CV-24153	9/25/2025 2:22:57 PM	103.4	103.1	-0.06	-0.10	0.070	0.042	0.0	0.0	-0.21	
CV-24154	9/9/2025 10:40:09 AM	115.8	115.7	-1.02	-1.01	0.965	0.965			-8.15	-8.26
CV-24154	9/11/2025 10:57:05 AM	119.7	118.4	-0.77	-0.84	0.778	0.851			-9.82	-8.91
CV-24154	9/16/2025 10:35:50 AM	120.7	112.4	-2.82	-1.45	2.812	1.464			-2.73	-8.57
CV-24155	9/15/2025 12:48:21 PM	115.9	116.1	-0.58	-0.54	0.570	0.544			-0.71	-0.61
CV-24155	9/16/2025 10:40:28 AM	126.1	126.0	-0.95	-0.85	0.967	0.867			-0.60	-3.34
CV-24156	9/15/2025 10:33:33 AM	123.3	123.2	-0.18	-0.17	0.051	0.042	14.0	12.8	-10.51	-10.46
CV-24156	9/15/2025 10:37:02 AM	123.2	123.4	-0.18	-0.22	0.336	0.418	22.9	25.5	-10.46	-10.26
CV-24156	9/22/2025 10:21:52 AM	89.1	88.2	0.03	-0.04	0.884	1.277	18.5	22.3	-9.35	-8.85
CV-24156	9/22/2025 10:22:35 AM	90.2	90.4	-0.04	-0.04	1.229	1.242	21.8	21.9	-8.67	-8.62
CV-24157	9/15/2025 9:54:30 AM	118.9	119.6	-1.66	-1.66	1.669	1.657			-2.00	-1.85
CV-24157	9/16/2025 11:06:04 AM	123.2	123.5	-1.30	-1.29	1.326	1.295			-0.98	-0.94
CV-24157	9/30/2025 1:53:22 PM										
CV-24158	9/12/2025 2:20:01 PM	121.7	121.0	-0.47	-0.48	0.000	0.000			-0.10	-0.11
CV-24158	9/15/2025 9:16:48 AM	122.9	123.1	-1.66	-1.70	0.006	0.000			-2.36	-2.03
CV-24158	9/16/2025 1:38:54 PM	125.8	125.8	-0.51	-0.51	0.000	0.000			-1.32	-1.41
CV-24159	9/3/2025 1:33:10 PM	116.2	116.2	-0.77	-0.74	1.733	1.745	27.3	27.4	-11.52	-11.49
CV-24159	9/5/2025 2:21:09 PM	115.7	115.7	-0.52	-0.60	1.854	2.059	17.0	17.9	-12.20	-12.43
CV-24159	9/12/2025 2:02:19 PM	114.3	114.3	-1.68	-1.79	2.404	2.684	19.4	20.5	-16.13	-16.10
CV-24159	9/16/2025 1:48:55 PM	115.2	115.3	-1.97	-1.93	2.253	2.290	18.8	18.9	-13.88	-14.02
CV-24160	9/5/2025 2:26:19 PM	122.1	122.1	-0.07	-0.17	0.000	0.000			-11.63	-11.87
CV-24160	9/12/2025 1:53:45 PM	118.1	116.3	-0.25	-0.30	0.000	0.000			-16.08	-15.89
CV-24160	9/22/2025 9:37:53 AM	121.5	121.3	-0.83	-0.83	0.938	0.951	12.1	12.2	-16.86	-17.16
CV-24161	9/9/2025 10:48:23 AM	109.2	110.1	-0.07	-0.08	0.049	0.059			-12.48	-12.68

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24162	9/9/2025 2:26:45 PM	104.4	104.5	-3.25	-2.19	3.221	2.122			-10.10	-10.45
CV-24163	9/10/2025 2:32:29 PM	102.6	103.5	-0.07	-0.08	0.000	0.000			-12.98	-13.05
CV-24164	9/5/2025 11:26:06 AM	131.5	131.6	-0.97	-0.98	1.037	1.077	0.0	0.0	-6.49	
CV-24164	9/5/2025 11:29:18 AM	132.4	132.4	-0.59	-0.60	0.626	0.625	0.0	0.0	-7.22	
CV-24164	9/10/2025 10:05:47 AM	135.1	135.1	-1.12	-1.18	1.127	1.191			-9.73	-9.51
CV-24164	9/10/2025 10:07:47 AM	135.0	135.1	-1.25	-0.75	1.289	0.781			-10.25	-9.27
CV-24164	9/15/2025 8:58:33 AM	134.3	134.2	-1.29	-0.75	1.314	0.763			-9.72	-9.59
CV-24164	9/15/2025 8:59:23 AM	134.1	134.1	-0.70	-0.70	0.696	0.704			-9.55	-10.00
CV-24164	9/18/2025 9:02:45 AM	133.0	132.8	-1.01	-0.04	1.009	0.063			-9.21	-9.44
CV-24164	9/18/2025 9:03:31 AM	132.4	131.8	-0.17	-0.04	0.181	0.063			-9.40	-9.52
CV-24164	9/19/2025 9:49:51 AM										
CV-24165	9/5/2025 11:13:22 AM	124.9	124.9	-0.85	-0.83	0.785	0.777	0.0	0.0	-5.17	
CV-24165	9/16/2025 11:14:45 AM	128.5	127.4	-0.49	-0.80	0.499	0.815			-5.56	-6.48
CV-24166	9/3/2025 2:26:52 PM	115.8	115.9	-5.20	-5.11	5.271	5.183			-5.37	-5.38
CV-24166	9/12/2025 2:06:12 PM	110.5	112.2	-6.85	-5.71	6.820	5.676			-6.92	-7.17
CV-24166	9/12/2025 2:12:14 PM	109.2	109.1	-3.19	-3.19	3.191	3.242			-6.69	-6.88
CV-24166	9/16/2025 1:46:25 PM	121.9	120.3	-2.15	-2.15	2.154	2.142			-6.46	-6.55
CV-24167	9/3/2025 1:36:08 PM	119.5	119.5	-0.46	-0.45	0.415	0.363			-5.10	-5.13
CV-24167	9/22/2025 9:46:33 AM	114.1	113.9	-1.05	-1.04	1.057	1.055			-9.51	-9.78
CV-24168	9/3/2025 9:12:29 AM	115.4	116.3	-0.12	-0.08	0.103	0.050			-2.52	-2.15
CV-24168	9/16/2025 2:14:56 PM	120.0	120.2	-0.37	-0.40	0.420	0.409			-3.08	-3.31
CV-24169	9/5/2025 11:19:16 AM	134.8	135.0	-0.79	-0.78	0.684	0.689	24.5	24.6		
CV-24169	9/5/2025 11:21:39 AM	137.6	137.6	-0.91	-0.90	0.840	0.842	27.4	27.4		
CV-24169	9/15/2025 9:05:52 AM	127.2	126.8	-2.39	-1.56	2.395	1.580			-9.35	-9.68
CV-24169	9/18/2025 9:06:32 AM	123.4	123.6	-1.11	-1.15	1.114	1.136			-9.58	-10.45
CV-24170	9/4/2025 2:20:45 PM	128.1	128.2	-0.13	-0.13	0.036	0.037	6.9	7.0	-6.21	
CV-24170	9/18/2025 10:47:10 AM	123.0	121.9	-1.48	-1.36	0.262	0.218			-9.05	-9.35
CV-24171	9/3/2025 1:42:09 PM	123.4	123.4	-2.30	-2.30	3.350	3.385	22.8	22.9	-5.02	-5.18
CV-24171	9/18/2025 8:19:42 AM	122.3	122.3	-3.25	-3.24	5.624	5.670	29.3	29.4	-7.96	-7.78

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24171	9/18/2025 8:23:27 AM	122.8	122.3	-4.13	-3.15	3.724	1.724	39.5	27.0	-7.70	-8.91
CV-24172	9/3/2025 1:56:27 PM	118.3	118.4	-0.37	-0.37	2.139	2.201	17.7	18.0	-6.04	-6.05
CV-24172	9/18/2025 9:45:48 AM	103.1	101.3	-0.80	-0.45	3.017	0.011	33.7	2.1	-11.88	-11.72
CV-24172	9/18/2025 9:59:20 AM	99.1	92.1	-0.46	-0.12	0.742	0.346	16.8	11.6	-11.90	-11.48
CV-24173	9/3/2025 2:00:35 PM	118.1	118.2	-0.96	-0.97	0.543	0.579	14.1	14.6	-6.19	-6.39
CV-24173	9/3/2025 2:02:26 PM	118.3	118.4	-0.94	-0.95	0.631	0.652	27.4	27.8	-6.29	-6.81
CV-24173	9/18/2025 10:23:36 AM	114.8	113.6	-2.32	-2.30	0.974	0.885	27.3	26.1	-11.29	-11.45
CV-24173	9/18/2025 10:27:53 AM	115.1	114.5	-2.32	-1.94	1.829	0.785	28.0	18.4	-11.27	-10.97
CV-24174	9/3/2025 2:10:26 PM	118.7	118.7	-0.51	-0.47	0.446	0.447			0.01	0.01
CV-24174	9/23/2025 10:51:24 AM	105.9	106.1	-0.23	-0.23	0.194	0.193			-10.70	-10.70
CV-24175	9/3/2025 2:14:17 PM	118.4	118.3	-0.70	-0.64	0.240	0.290	9.4	10.3	0.01	0.01
CV-24175	9/23/2025 11:03:52 AM	117.1	117.0	-1.14	-0.86	2.208	1.046	28.4	19.6	-10.49	-10.32
CV-24176	9/4/2025 2:01:20 PM	127.2	127.2	-0.55	-0.54	1.762	1.764	24.5	24.5	-6.86	
CV-24176	9/21/2025 12:40:37 PM	121.8	121.7	-1.85	-1.85	2.330	2.315	29.1	29.0	-10.56	-10.61
CV-24176	9/23/2025 8:22:02 AM	121.2	121.1	-2.18	-1.99	0.000	0.000			-11.21	-11.42
CV-24177	9/2/2025 11:43:58 AM	131.0	126.8	-3.94	-0.43	3.949	0.435			-6.22	-6.56
CV-24177	9/2/2025 11:46:58 AM	125.8	126.0	-0.33	-0.37	0.339	0.378			-6.34	-6.34
CV-24177	9/17/2025 9:41:15 AM	125.9	123.1	-3.68	-3.46	3.695	3.464			-10.40	-10.38
CV-24178	9/4/2025 11:41:55 AM	126.9	126.9	-0.57	-0.57	0.512	0.508	13.6	13.5	-5.56	
CV-24178	9/21/2025 12:54:05 PM	126.9	126.8	-1.30	-1.20	0.851	0.646	17.6	15.3	-11.28	-11.15
CV-24179	9/4/2025 1:50:33 PM	127.2	127.1	-0.27	-0.26	0.101	0.102	12.4	12.4	-6.89	
CV-24179	9/17/2025 1:46:51 PM	126.0	126.0	-0.42	-0.41	0.000	0.000			-9.19	-9.14
CV-24180	9/4/2025 11:46:05 AM	124.8	124.7	-0.45	-0.44	0.299	0.304	10.3	10.4	-6.81	
CV-24180	9/21/2025 12:25:59 PM	123.4	123.4	-1.06	-1.07	0.386	0.386	11.9	11.9	-11.11	-11.41
CV-24183	9/3/2025 10:24:34 AM										
CV-24183	9/4/2025 11:30:11 AM	114.4	114.6	-0.78	-0.77	0.807	0.794	0.0	0.0	-7.03	
CV-24183	9/10/2025 10:16:07 AM										
CV-24183	9/16/2025 9:47:03 AM										
CV-24183	9/18/2025 1:17:21 PM	112.2	106.5	-1.12	-0.53	1.118	0.526			-10.85	-10.99
CV-24183	9/24/2025 2:02:23 PM										
CV-24184	9/4/2025 11:24:32 AM	113.2	111.5	-0.54	-0.18	0.314	-0.006	11.0	0.0	-7.22	
CV-24184	9/4/2025 11:27:07 AM	110.1	110.1	-0.18	-0.17	-0.033	-0.033	0.0	0.0	-7.48	
CV-24185	9/4/2025 3:09:41 PM	122.3	122.4	-0.53	-0.53	0.035	0.037	3.6	3.7	-7.37	
CV-24185	9/17/2025 2:29:29 PM	121.3	121.3	-0.87	-0.77	0.000	0.000			-9.17	-9.38
CV-24186	9/11/2025 8:24:52 AM	134.7	130.5	-0.82	-0.47	0.055	0.028	14.5	10.3	-9.38	-9.42

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24186	9/11/2025 8:35:51 AM	122.4	127.9	-0.38	-0.50	0.001	0.019	1.0	5.5	-9.35	-9.35
CV-24186	9/11/2025 8:38:04 AM	129.9	130.6	-0.54	-0.54	0.019	0.014	5.4	4.7	-9.36	-9.35
CV-24186	9/18/2025 1:24:22 PM	113.6	117.3	0.05	-0.01	0.037	0.006	7.7	3.1	-10.99	-10.97
CV-24186	9/18/2025 1:26:38 PM	120.9	124.7	-0.03	-0.09	0.004	0.016	2.6	4.9	-10.91	-11.08
CV-24187	9/8/2025 8:30:08 AM	116.6	116.9	-1.78	-1.64	1.183	0.980	21.1	19.2	-8.82	
CV-24187	9/23/2025 9:46:35 AM	122.5	122.2	-1.65	-1.26	1.282	0.649	21.6	15.4	-11.39	-11.35
CV-24188	9/2/2025 1:55:34 PM	118.6	118.7	-1.39	-1.42	0.187	0.198	17.1	17.6	-6.83	-6.83
CV-24188	9/17/2025 9:53:39 AM	117.8	117.8	-2.60	-2.54	0.001	0.080	1.2	11.2	-10.01	-10.32
CV-24189	9/2/2025 1:52:51 PM	118.9	119.0	-0.71	-0.71	0.916	0.835	19.9	19.0	-7.01	-6.86
CV-24189	9/18/2025 2:21:49 PM	117.4	116.3	-0.89	-0.60	0.902	0.116	19.7	7.1	-10.42	-10.55
CV-24190	9/8/2025 8:35:49 AM	119.8	120.4	-2.41	-3.09	-1.092	-0.543	0.0	0.0	-8.66	
CV-24190	9/11/2025 1:59:31 PM										
CV-24190	9/23/2025 9:53:23 AM	122.0	122.0	-6.14	-6.05	0.572	0.580	29.7	29.9	-11.23	-11.20
CV-24190	9/23/2025 9:55:55 AM	121.7	121.6	-5.70	-5.70	1.273	1.274	21.4	21.4	-11.33	-11.34
CV-24192	9/8/2025 8:53:26 AM	85.9	98.6	-0.78	-1.86	-0.056	0.009	0.0	2.9	-9.23	
CV-24192	9/23/2025 10:06:28 AM	119.4	119.6	-4.30	-4.29	0.217	0.240	12.8	13.5	-11.51	-11.68
CV-24193	9/4/2025 8:57:40 AM	111.5	111.7	-3.82	-3.88	4.589	4.945	15.3	15.8	-8.21	
CV-24193	9/17/2025 1:19:27 PM	114.8	114.8	-6.38	-6.38	0.000	0.000			-9.08	-9.08
CV-24194	9/3/2025 11:45:22 AM										
CV-24194	9/4/2025 8:53:03 AM	117.1	117.1	-7.67	-7.66	0.439	0.363	4.6	4.2	-7.97	
CV-24194	9/17/2025 1:32:21 PM	119.9	119.9	-7.72	-7.38	0.000	0.000			-9.08	-9.40
CV-24195	9/3/2025 1:39:42 PM										
CV-24195	9/4/2025 9:52:14 AM	116.1	116.1	-0.74	-0.73	5.093	5.100	15.5	15.5	-8.55	
CV-24195	9/10/2025 11:16:09 AM	115.9	115.1	-0.57	-0.66	0.000	0.000			-8.69	-8.81
CV-24195	9/17/2025 1:09:20 PM	117.8	117.7	-0.10	-0.10	0.000	0.000			-9.15	-9.04
CV-24196	9/4/2025 10:57:58 AM	127.2	127.5	-3.84	-3.95	1.393	1.525	33.9	35.4	-8.17	
CV-24196	9/17/2025 1:04:09 PM	128.9	128.8	-4.53	-4.30	0.000	0.000			-9.48	-9.66
CV-24196	9/30/2025 9:22:59 AM										
CV-24197	9/4/2025 11:07:50 AM	123.7	123.8	-1.25	-1.24	0.019	0.011	0.0	0.0	-7.85	
CV-24197	9/21/2025 12:06:54 PM	124.3	124.2	-1.47	-1.46	2.040	2.004	27.2	27.0	-11.69	-11.74
CV-24197	9/21/2025 12:10:28 PM	124.3	123.9	-1.50	-1.27	2.061	1.099	27.4	20.0	-11.79	-11.82
CV-24198	9/3/2025 2:29:42 PM										

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24198	9/4/2025 9:42:09 AM	119.6	119.7	-0.58	-0.57	0.863	0.865	11.7	11.8	-10.22	
CV-24198	9/17/2025 10:08:43 AM	122.6	122.6	-0.68	-0.68	0.000	0.000			-12.71	-12.40
CV-24199	9/3/2025 2:39:28 PM										
CV-24199	9/4/2025 9:45:49 AM	125.1	125.3	-2.03	-1.89	4.010	3.997	57.2	57.2	-11.51	
CV-24199	9/10/2025 11:20:46 AM	125.9	125.9	-2.14	-1.75	0.000	0.000			-11.91	-11.02
CV-24199	9/17/2025 10:05:04 AM	126.6	126.9	-2.10	-1.74	0.000	0.000			-14.50	-13.42
CV-24200	9/4/2025 8:51:20 AM										
CV-24200	9/5/2025 1:37:21 PM	116.7	116.7	-0.41	-0.41	1.299	1.405	24.5	25.5	-8.30	
CV-24200	9/26/2025 9:29:13 AM	115.9	115.9	-0.75	-0.75	1.420	1.534	24.7	25.7	-10.22	-10.47
CV-24200	9/26/2025 1:39:27 PM	117.2	117.3	-0.46	-0.94	1.665	3.589	26.8	39.2	-10.16	-10.99
CV-24201	9/4/2025 9:09:09 AM										
CV-24201	9/5/2025 1:43:49 PM	116.7	116.8	-0.36	-0.37	0.114	0.113	6.6	6.6	-8.97	
CV-24201	9/17/2025 2:02:03 PM	121.5	120.7	-1.63	-1.35	0.573	0.362	14.5	11.5	-11.28	-11.42
CV-24202	9/4/2025 9:40:41 AM										
CV-24202	9/5/2025 1:50:54 PM	122.0	122.1	-4.41	-4.41	4.321	4.317	0.0	0.0	-8.48	
CV-24202	9/17/2025 2:09:52 PM	124.2	124.1	-5.37	-4.06	5.473	4.073			-11.06	-11.29
CV-24203	9/5/2025 8:37:08 AM	126.5	126.6	-2.33	-2.13	1.635	1.435	27.1	25.4	-10.75	
CV-24203	9/24/2025 10:24:27 AM	127.4	127.4	-3.08	-2.93	1.611	1.280	26.6	23.7	-13.13	
CV-24204	9/4/2025 10:05:13 AM										
CV-24204	9/5/2025 8:33:00 AM	122.4	122.4	-8.45	-8.40	1.937	1.987	39.9	40.4	-10.73	
CV-24204	9/24/2025 10:18:11 AM	123.3	123.2	-10.19	-9.97	2.078	1.849	41.0	38.7	-13.13	
CV-24205	9/5/2025 8:29:59 AM	118.8	119.2	-5.74	-5.47	3.180	3.077	51.8	50.9	-10.87	
CV-24205	9/24/2025 10:14:34 AM	119.3	119.6	-6.85	-6.70	3.732	3.399	55.4	52.9	-12.86	
CV-24206	9/5/2025 1:27:54 PM	113.4	113.3	-3.96	-3.96	3.889	3.896	0.0	0.0	-6.96	
CV-24206	9/17/2025 9:05:47 AM										
CV-24206	9/24/2025 11:20:40 AM	115.6	115.0	-5.37	-2.88	5.253	2.702	0.0	0.0	-10.03	
CV-24207	9/3/2025 2:21:04 PM	137.8	137.9	-0.77	-0.04	2.388	1.762	31.4	27.0	-5.51	-4.32
CV-24207	9/16/2025 1:57:47 PM	137.9	137.3	-1.76	-0.10	2.007	1.238	28.8	22.7	-6.62	-6.74
CV-24207	9/16/2025 1:58:46 PM	137.0	136.9	-0.08	-0.10	1.407	1.435	24.2	24.4	-6.78	-6.89
CV-24208	9/18/2025 9:29:37 AM	122.6	122.4	-1.05	-1.01	1.367	1.429	24.4	24.9	-8.46	-8.41
CV-24209	9/4/2025 10:48:05 AM										
CV-24209	9/17/2025 2:19:12 PM	129.4	128.0	-5.59	-4.86	5.646	4.895			-14.81	-15.19
CV-24210	9/4/2025 11:11:48 AM										
CV-24210	9/10/2025 1:34:07 PM	114.2	109.3	-1.86	-1.82	1.725	1.716			-8.79	-8.76

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24211	9/11/2025 9:16:26 AM	123.4	125.0	6.50	-1.82	0.000	1.777			-10.90	-11.04
CV-24211	9/11/2025 9:17:31 AM	125.2	125.2	-2.43	-2.44	2.379	2.379			-11.27	-11.15
CV-24212	9/11/2025 9:25:25 AM	136.2	134.3	-2.77	-0.96	2.703	0.933			-11.76	-11.93
CV-24212	9/11/2025 9:26:08 AM	133.3	133.0	-0.65	-0.64	0.639	0.625			-11.78	-11.67
CV-24213	9/4/2025 11:07:29 AM	131.4	129.4	-7.66	-6.22	8.128	6.673			-7.82	-8.24
CV-24213	9/4/2025 11:09:42 AM	129.4	129.1	-6.10	-5.04	6.583	5.455			-8.96	-8.79
CV-24214	9/2/2025 2:34:46 PM	123.2	122.0	-0.52	-0.49	0.503	0.462			-8.13	-8.24
CV-24215	9/26/2025 1:39:06 PM	110.3	110.2	-0.53	-0.53	0.020	0.023	5.6	6.1	-6.69	-6.67
CV-24216	9/25/2025 2:00:14 PM	106.3	105.8	-3.99	-3.62	3.817	3.528			-6.92	-7.16
CV-24217	9/3/2025 9:51:28 AM	115.8	115.9	-0.49	-0.45	0.471	0.425			-9.37	-9.37
CV-24217	9/11/2025 2:33:52 PM										
CV-24218	9/2/2025 11:15:28 AM	125.2	124.0	-1.22	-1.04	1.165	0.992			-9.05	-9.09
CV-24218	9/3/2025 10:11:17 AM										
CV-24218	9/5/2025 1:38:20 PM	125.3	125.5	-0.23	-0.30	0.240	0.286			-8.99	-8.69
CV-24218	9/10/2025 9:23:52 AM										
CV-24218	9/18/2025 8:11:15 AM										
CV-24218	9/24/2025 1:38:41 PM										
CV-24219	9/2/2025 11:24:26 AM	109.8	110.5	-3.05	-3.08	2.967	2.965			-5.82	-6.16
CV-24219	9/26/2025 2:25:25 PM	124.7	124.9	-2.19	-1.75	2.204	1.747			-5.07	-5.25
CV-24220	9/10/2025 2:43:22 PM	141.0	141.0	-0.85	-0.85	0.841	0.824			-11.38	-11.64
CV-24222	9/23/2025 11:02:05 AM	123.0	123.0	-5.74	-5.72	0.586	0.587	14.5	14.6	-12.13	-12.18
CV-24223	9/23/2025 11:11:38 AM	127.3	128.4	-0.83	-0.82	0.834	0.831	2.7	2.7	-12.12	-12.10
CV-24224	9/10/2025 2:17:00 PM	137.0	135.8	-1.00	-0.99	0.963	0.966			-13.19	-12.84
CV-24225	9/4/2025 2:53:55 PM	129.3	129.3	-0.11	-0.11	0.117	0.122			0.04	0.03
CV-24226	9/11/2025 9:10:56 AM	102.0	102.8	-6.36	-6.43	0.685	0.727	33.2	34.1	-12.52	-12.41
CV-24227	9/8/2025 8:58:58 AM	114.9	115.0	-4.34	-4.34	2.557	2.629	34.6	35.0		
CV-24231	9/15/2025 2:01:40 AM	120.4	120.4	-0.66	-0.65	-0.694	-0.693	0.0	0.0		
CV-24236	9/2/2025 1:31:44 PM	112.6	112.6	-2.28	-2.07	1.095	0.947	29.2	27.1	-6.39	-6.38
CV-24237	9/2/2025 1:34:54 PM	111.9	111.9	-0.75	-0.77	0.491	0.463	19.6	19.0	-6.84	-6.79
CV-24243	9/15/2025 9:54:28 AM	109.3	109.9	-0.02	-0.10	0.012	0.295	2.2	10.5	-11.81	-11.62

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24244	9/4/2025 10:33:00 AM	111.9	111.9	-0.86	-0.76	0.017	0.023	8.2	9.5	-7.42	-7.44
CV-24245	9/24/2025 1:46:00 PM	112.1	112.3	-4.89	-4.55	5.519	4.476	49.9	45.0	-11.31	
CV-24246	9/24/2025 1:39:28 PM	108.5	108.2	-2.01	-0.79	0.065	0.007	0.0	0.0		
CV-25	9/22/2025 1:33:04 PM	114.9	115.0	-7.09	-7.10	0.024	0.023	4.3	4.2	-7.86	-7.86
CV-2501	9/4/2025 9:26:58 AM	123.0	123.2	-0.30	-0.33	-0.013	0.065	0.0	16.5	-8.23	
CV-2501	9/12/2025 8:11:46 AM										
CV-2501	9/17/2025 1:16:02 PM	122.9	123.0	-0.77	-0.77	0.812	0.804	55.9	55.6	-11.08	-11.11
CV-2502	9/4/2025 9:07:05 AM	118.6	118.6	-0.24	-0.25	0.132	0.042	23.5	13.3	-9.05	
CV-2502	9/12/2025 8:37:44 AM										
CV-2502	9/17/2025 1:37:06 PM	112.9	113.4	0.57	-0.02	0.000	0.330			-10.44	-10.28
CV-2502	9/17/2025 1:40:06 PM	114.9	114.5	-0.07	-0.11	0.000	0.000			-10.21	-10.18
CV-2503	9/5/2025 2:10:33 PM	123.6	123.6	-0.20	-0.39	0.458	0.539	44.4	48.2	-5.27	
CV-2503	9/12/2025 8:53:21 AM										
CV-2504	9/15/2025 2:27:48 AM	121.3	121.3	-0.54	-0.53	0.255	0.255	32.7	32.6	-10.14	
CV-2505	9/15/2025 2:51:03 AM	119.2	119.3	-1.82	-1.95	0.591	0.736	50.7	56.6	-11.62	
CV-2506	9/15/2025 2:56:05 AM	121.9	122.1	-0.54	-0.60	0.796	1.063	36.6	42.3	-10.78	
CV-2507	9/15/2025 3:01:27 AM	118.9	118.8	-3.28	-3.50	3.832	4.437	56.9	61.2	-10.68	
CV-2508	9/15/2025 3:05:48 AM	116.6	116.9	-2.55	-2.85	0.874	1.118	38.6	43.7	-8.81	
CV-2509	9/15/2025 3:12:04 AM	111.4	111.4	-3.00	-3.23	1.473	1.777	50.2	55.1	-8.99	
CV-2510	9/24/2025 2:14:02 PM	108.9	109.0	-4.96	-5.10	4.048	4.760	39.7	43.0	-10.81	
CV-2511	9/15/2025 2:17:24 AM	122.4	122.6	-1.12	-0.94	0.334	0.276	37.3	33.9	-9.74	
CV-2512	9/15/2025 2:22:20 AM	118.9	119.1	-0.50	-0.48	0.099	0.099	20.2	20.2	-10.07	
CV-2513	9/24/2025 1:31:05 PM	113.7	114.0	-2.12	-1.72	2.832	2.242	36.3	32.3	-8.41	
CV-2514	9/24/2025 1:14:29 PM	119.3	119.4	-2.13	-2.24	1.644	1.952	37.6	41.0	-8.12	
CV-2515	9/12/2025 9:12:13 AM										
CV-2515	9/22/2025 2:04:33 PM	115.7	115.7	-1.64	-1.65	1.107	1.156	21.8	22.3	-6.85	-6.86
CV-2516	9/29/2025 1:24:18 PM	115.8	119.1	2.24	2.14	0.194	1.141	3.1	7.6	-6.56	
CV-2516	9/30/2025 2:40:00 PM	124.2	125.9	1.17	0.53	0.247	0.719	6.2	10.6	-7.24	-7.24
CV-2524	9/16/2025 2:25:42 PM	135.5	135.5	-0.33	-0.31	0.256	0.259			-11.20	-10.78
CV-2529	9/12/2025 10:06:55 AM										
CV-2529	9/23/2025 11:23:06 AM	102.5	102.6	-8.16	-8.23	0.003	0.011	0.4	0.7	-12.06	-11.98

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2530	9/11/2025 11:07:58 AM	83.0	77.7	-11.19	-4.33	11.502	4.229			-11.12	-11.08
CV-2531	9/12/2025 9:47:27 AM										
CV-2531	9/30/2025 2:01:16 PM	95.4	95.4	-1.12	-1.09	0.964	0.986			-13.61	-13.54
CV-2532	9/11/2025 11:13:42 AM	99.2	99.3	-1.82	-1.82	1.712	1.706			-11.44	-11.45
CV-2532	9/12/2025 9:31:38 AM										
CV-2532	9/12/2025 9:52:08 AM										
CV-2532	9/15/2025 11:20:47 AM	126.9	127.0	-1.05	-1.16	1.097	1.159			-14.38	-14.09
CV-2540	9/3/2025 9:18:47 AM	126.2	125.9	-0.77	-0.56	0.770	0.566			-5.54	-5.65
CV-2540	9/18/2025 9:09:19 AM	113.8	113.2	-2.54	-2.33	2.559	2.345			-9.64	-10.74
CV-2540	9/19/2025 10:16:17 AM										
CV-2541	9/3/2025 1:19:03 PM	162.7	161.7	-0.49	-0.22	0.473	0.228			-6.66	-6.60
CV-2541	9/3/2025 1:20:05 PM	163.3	163.5	-0.28	-0.25	0.277	0.253			-6.66	-6.70
CV-2541	9/4/2025 10:36:24 AM	173.2	173.5	-0.69	-0.77	0.676	0.761			-7.80	-7.68
CV-2541	9/4/2025 10:37:00 AM										
CV-2541	9/4/2025 10:37:00 AM										
CV-2541	9/11/2025 10:30:46 AM	166.7	166.2	-2.78	-2.75	2.750	2.736			-8.24	-8.30
CV-2541	9/11/2025 10:33:00 AM										
CV-2541	9/17/2025 9:36:45 AM	158.6	158.9	-3.99	-3.98	3.961	3.957			-10.06	-9.94
CV-2541	9/24/2025 1:59:39 PM	148.4	148.1	-3.60	-3.53	3.462	3.410			-9.67	-9.76
CV-2542	9/12/2025 2:27:00 PM	84.0	78.6	-2.44	-2.46	2.422	2.448			-0.15	-0.14
CV-2542	9/15/2025 2:22:21 PM	99.1	98.9	-1.54	-1.66	1.590	1.684			0.26	0.26
CV-2542	9/16/2025 11:09:30 AM	105.0	96.2	-3.42	-3.42	3.442	3.442			0.33	0.33
CV-2542	9/16/2025 1:36:05 PM	105.0	105.0	-2.68	-2.68	2.698	2.702			-4.39	-4.46
CV-2542	9/30/2025 2:00:32 PM										
CV-2543-PLR	9/3/2025 1:44:12 PM	194.4	191.2	-4.14	-0.85	4.214	0.874			-4.23	-3.89
CV-2543-PLR	9/3/2025 1:46:08 PM	189.8	189.8	-2.33	-0.36	2.372	0.391			-4.00	-4.09
CV-2543-PLR	9/4/2025 10:56:23 AM	200.5	200.2	-5.35	-5.46	4.810	4.810	25.4	25.5	-6.04	-6.35
CV-2543-PLR	9/4/2025 11:00:00 AM										
CV-2543-PLR	9/4/2025 11:00:00 AM										
CV-2543-PLR	9/11/2025 10:07:20 AM	199.1	199.3	-0.04	-0.03	0.042	0.039	2.4	2.3	0.39	0.36
CV-2543-PLR	9/11/2025 10:08:00 AM										
CV-2543-PLR	9/11/2025 10:57:29 AM	197.0	197.6	-8.00	-8.03	8.465	8.516	33.7	33.8	0.67	0.65
CV-2543-PLR	9/17/2025 9:10:37 AM	198.7	199.1	-10.90	-10.80	11.239	11.180	38.5	38.4	-9.55	-9.43

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2543-PLR	9/19/2025 2:07:17 PM										
CV-2543-PLR	9/24/2025 2:21:15 PM	153.4	150.3	-7.94	-4.68	8.169	4.606			-8.23	-8.79
CV-2543-PLR	9/24/2025 2:24:50 PM	156.6	155.4	-2.28	-2.05	2.234	2.010			-8.68	-8.59
CV-2544	9/15/2025 9:48:46 AM	129.2	129.2	-2.63	-2.64	2.653	2.633			-4.86	-5.02
CV-2544	9/16/2025 11:01:44 AM	128.8	128.4	-1.81	-1.39	1.831	1.419			-3.18	-4.44
CV-2544	9/30/2025 1:35:33 PM										
CV-2545	9/15/2025 1:21:14 PM	113.3	113.4	-0.67	-0.69	0.656	0.652			-0.95	-0.75
CV-2545	9/16/2025 10:54:02 AM	122.3	121.5	-1.44	-0.99	1.447	1.000			-1.34	-6.68
CV-2545	9/30/2025 10:44:50 AM										
CV-2546	9/15/2025 1:02:30 PM	115.7	115.6	-0.47	-0.49	0.457	0.439			-1.23	-1.25
CV-2546	9/16/2025 10:44:29 AM	120.0	120.0	-0.95	-0.75	0.943	0.763			-0.95	-3.62
CV-2546	9/30/2025 11:16:04 AM										
CV-2548	9/29/2025 1:59:17 PM	119.5	118.7	-5.04	-0.88	5.088	0.880			-9.39	-10.84
CV-2549	9/29/2025 2:09:51 PM	109.4	109.0	-2.17	-1.19	2.118	1.123			-10.60	-11.47
CV-2552	9/8/2025 1:55:39 PM	92.4	92.4	-3.13	-3.12	3.046	3.040			-7.46	-7.65
CV-2553	9/3/2025 10:07:37 AM	109.4	109.5	-2.89	-3.12	2.815	3.192			-3.27	-3.40
CV-2553	9/12/2025 10:46:09 AM										
CV-2553	9/16/2025 2:05:00 PM	116.3	116.1	-3.08	-2.89	3.005	2.911			-3.02	-2.80
CV-2554	9/4/2025 11:04:58 AM	180.9	180.6	-3.93	-3.97	3.920	3.906	23.4	23.3	-8.02	-7.97
CV-2554	9/4/2025 11:05:00 AM										
CV-2554	9/4/2025 11:05:00 AM										
CV-2554	9/11/2025 9:44:39 AM	182.0	181.3	-0.10	-0.06	0.110	0.064	3.9	3.0	-9.36	-9.23
CV-2554	9/11/2025 9:45:00 AM										
CV-2554	9/12/2025 10:41:06 AM	184.5	183.4	-0.24	-0.26	0.292	0.274			-8.62	-8.64
CV-2554	9/12/2025 10:42:15 AM	184.2	183.5	-0.23	-0.23	0.326	0.288			-8.65	-8.65
CV-2554	9/17/2025 8:33:41 AM	185.0	184.7	-1.99	-2.09	1.946	1.955	16.5	16.5	-11.43	-11.08
CV-2554	9/24/2025 2:35:06 PM	181.8	181.9	-0.68	-0.69	0.607	0.626			-10.64	-10.29
CV-2555	9/9/2025 9:48:29 AM	91.0	91.0	-5.65	-5.71	5.992	6.021			-8.78	-8.81
CV-2555	9/12/2025 10:30:57 AM										
CV-2555	9/18/2025 8:53:01 AM	108.6	108.7	-6.38	-6.38	6.458	6.497			-9.37	-9.18

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2556	9/5/2025 6:32:15 AM	160.0	161.4	9.49	9.59	0.000	0.000			0.01	0.02
CV-2556	9/5/2025 6:33:56 AM	161.6	161.6	9.21	9.25	0.000	0.000			0.02	0.03
CV-2556	9/5/2025 6:38:00 AM										
CV-2556	9/5/2025 6:38:00 AM										
CV-2556	9/11/2025 9:06:00 AM										
CV-2556	9/11/2025 9:06:04 AM	162.9	162.8	6.78	6.96	0.000	0.000			0.34	0.34
CV-2556	9/17/2025 8:03:13 AM	159.9	160.1	11.58	11.65	0.000	0.000			0.31	0.30
CV-2556	9/19/2025 3:06:07 PM										
CV-2557	9/2/2025 11:32:28 AM	134.9	134.8	-0.20	-0.20	0.244	0.219			-8.70	-9.46
CV-2557	9/10/2025 10:24:15 AM	129.5	129.7	-0.58	-0.59	0.600	0.588			-13.15	-11.58
CV-2557	9/29/2025 1:11:46 PM	133.6	132.0	-0.68	-0.66	0.631	0.635			-7.44	-7.33
CV-2557	9/29/2025 1:12:58 PM	133.1	133.1	-0.70	-0.70	0.685	0.688			-7.15	-7.23
CV-2558	9/9/2025 12:42:12 PM	150.8	152.0	-2.37	-0.49	2.378	0.513			-4.26	-7.48
CV-2558	9/9/2025 12:43:57 PM	152.6	152.8	-0.64	-0.64	0.650	0.605			-7.25	-7.33
CV-2558	9/18/2025 2:00:23 PM	163.8	163.8	-5.49	-5.74	5.430	5.552			-5.00	-4.98
CV-2558	9/25/2025 10:50:16 AM	155.1	155.3	-1.81	-1.71	1.793	1.712	80.9	79.1	-8.36	-8.56
CV-2558	9/30/2025 2:43:43 PM										
CV-2564	9/3/2025 1:26:22 PM	123.5	122.0	-2.75	-0.75	2.746	0.720			-5.17	-6.64
CV-2564	9/18/2025 9:19:52 AM	118.2	118.8	-1.79	-1.79	1.812	1.814	16.8	16.8	-9.29	-9.45
CV-2564	9/19/2025 10:41:12 AM										
CV-48R	9/9/2025 8:43:50 AM										
CV-48R	9/17/2025 2:32:14 PM	124.5	124.7	-2.32	-2.32	0.284	0.306	6.6	6.9	-2.60	-2.62
CV-55R	9/2/2025 9:48:00 AM										
CV-55R	9/2/2025 9:49:28 AM	152.0	151.9	-2.38	-2.38	0.058	0.081	2.9	3.5	-9.28	-9.24
CV-55R	9/8/2025 9:56:46 AM	153.0	152.6	-2.65	-2.25	0.092	0.181	3.7	5.2	-10.66	-10.55
CV-55R	9/8/2025 10:00:00 AM										
CV-55R	9/18/2025 6:41:09 AM	151.2	151.4	-1.74	-1.74	0.058	0.074	2.9	3.3	-14.43	-14.37
CV-55R	9/22/2025 1:52:58 PM	153.6	155.0	-1.40	-1.43	0.434	0.410	8.0	7.8	-11.58	-11.48
CV-55R	9/29/2025 8:28:29 AM	152.3	152.6	-3.08	-3.10	0.210	0.207	5.6	5.5	-10.41	-10.50
CV-56D	9/4/2025 2:32:23 PM	126.1	126.0	-1.57	-1.14	0.812	0.430	6.1	4.5	-8.01	-9.71

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-56S	9/4/2025 2:34:59 PM	121.6	122.0	-1.02	-1.05	2.567	1.236	3.1	2.1	-8.53	-8.42
CV-57R	9/4/2025 2:05:03 PM	123.8	123.9	-0.64	-0.64	0.214	0.218	3.2	3.2	-9.00	-8.97
CV-79R	9/9/2025 11:28:26 AM										
CV-79R	9/10/2025 2:27:03 PM	129.3	129.3	-1.19	-1.19	0.139	0.136	10.2	10.1	-13.34	-13.28
CV-84S	9/9/2025 10:59:31 AM	109.8	109.8	-0.07	-0.04	0.786	0.811	6.1	6.2	-10.56	-10.76
CV-94	9/4/2025 1:57:52 PM	126.6	126.8	-2.31	-2.31	1.104	1.100	13.0	13.0	-9.14	-9.15
CV-95	9/4/2025 2:08:11 PM	123.2	124.0	-0.19	-0.20	0.160	0.161	2.7	2.7	-9.13	-9.17
CV-99	9/2/2025 9:35:00 AM										
CV-99	9/2/2025 9:35:00 AM										
CV-99	9/11/2025 2:34:59 PM	101.6	100.2	-0.51	-0.59	0.475	0.369	48.2	42.6	-8.96	-8.63
D-02	9/26/2025 2:11:24 PM	94.4	94.6	-12.19	-12.16	0.020	0.004	4.8	2.1	-12.13	-12.13
D-03	9/26/2025 2:13:33 PM	98.2	98.2	-3.95	-4.16	0.226	0.385	16.4	21.3	-3.81	-3.81
D-04	9/26/2025 2:16:04 PM	97.6	100.8	-0.23	-0.21	0.307	0.277	15.7	14.9	-9.18	-9.43
D-05	9/30/2025 2:12:56 PM	106.2	106.2	-0.35	-0.33	0.335	0.336	19.9	19.9	-14.59	-14.56
D-09	9/24/2025 1:45:59 PM	115.6	115.7	-6.27	-6.40	0.330	0.514	15.9	19.9	-11.43	-12.37
D-10	9/24/2025 1:54:54 PM	102.0		-14.82		14.937				-14.31	
FP-001	9/5/2025 1:45:04 PM	110.9	110.9	-0.20	-0.24	0.126	0.137	2.5	2.6	-6.36	-6.39
FP-002	9/5/2025 1:47:56 PM	99.7	100.6	-0.27	-0.25	0.048	0.063	1.5	1.8	-7.37	-7.49
FP-003	9/5/2025 1:59:13 PM	102.2	102.5	-0.07	-0.07	0.806	0.800	6.2	6.2	-8.00	-7.81
FP-005	9/5/2025 2:13:48 PM	105.0	105.2	-0.12	-0.06	1.140	1.191	7.4	7.6	-8.09	-7.92
FP-006	9/10/2025 8:58:02 AM	70.8	77.0	-0.03	-0.06	0.006	0.543	0.6	5.3	-8.96	-8.48
FP-008	9/30/2025 1:28:23 PM	94.7	94.7	-0.30	-0.27	0.000	0.063			-9.00	-7.80
FP-009	9/23/2025 10:20:12 AM	93.9	93.9	-0.20	-0.20	3.033	3.327	12.2	12.8	-8.70	-9.60
FP-011	9/4/2025 10:15:17 AM	102.2	102.2	-0.23	-0.23	5.602	5.487	16.4	16.3	-9.57	-9.34
FP-012	9/9/2025 10:12:05 AM	88.3	88.0	-0.35	-0.34	0.406	0.395	4.5	4.4	-3.35	-3.19
FP-012	9/16/2025 10:10:17 AM	89.1	89.2	-0.39	-0.39	1.120	1.123	7.5	7.5	-3.79	-3.96
FP-013	9/4/2025 8:17:32 AM	82.4	82.5	-0.33	-0.35	0.762	0.748	6.2	6.1	-2.98	-2.86
FP-013	9/16/2025 10:18:50 AM	93.5	93.5	-0.40	-0.39	0.432	0.575	4.6	5.3	-3.83	-3.86
FP-014	9/30/2025 1:47:02 PM	105.3	106.2	-0.57	-0.58	4.239	4.244	14.3	14.3	-6.05	-6.14
FP-015	9/10/2025 9:05:52 AM	83.0	83.0	-0.37	-0.37	3.850	3.893	13.9	14.0	-6.38	-6.49
FP-016	9/10/2025 9:02:26 AM	74.6	74.6	-0.14	-0.14	1.143	1.145	7.6	7.6	-7.06	-7.05
FP-017	9/8/2025 8:25:40 AM	74.3	74.4	-0.10	-0.09	1.533	1.534	8.9	8.9	-9.19	-9.16
FP-018	9/23/2025 10:00:57 AM	95.1	95.3	-0.08	-0.07	0.005	0.001	0.5	0.2	0.54	0.55
FP-019	9/8/2025 8:34:20 AM	80.3	80.4	-0.10	-0.12	3.373	5.887	13.1	17.2	-3.18	-5.76
FP-020	9/8/2025 9:49:07 AM	85.1	85.1	-0.35	-0.35	0.017	0.006	0.9	0.6	-7.74	-7.91
FP-021	9/8/2025 9:53:20 AM	93.7	93.7	-0.10	-0.11	0.016	0.012	0.9	0.8	-8.50	-7.53
FP-022	9/8/2025 9:57:51 AM	94.4	94.7	-0.20	-0.20	5.998	6.106	17.2	17.3	-7.13	-7.25
FP-023	9/23/2025 9:51:51 AM	110.7	110.9	-0.12	-0.12	4.498	4.516	14.6	14.7	-12.13	-12.20
FP-024	9/8/2025 10:29:20 AM	95.1	95.1	-0.07	-0.07	0.490	0.470	4.9	4.8	-9.00	-9.13
FP-025	9/8/2025 10:32:45 AM	95.4	95.4	-0.16	-0.16	4.416	4.265	14.7	14.5	-9.02	-8.75
FP-026	9/9/2025 9:12:47 AM	86.8	87.1	-0.20	-0.20	1.131	1.087	7.5	7.4	-9.55	-10.05
FP-027	9/9/2025 9:24:02 AM	92.7	92.9	-0.10	-0.10	3.476	3.539	13.1	13.2	-8.81	-9.21

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
FP-028	9/9/2025 9:30:20 AM	85.9	86.1	-0.20	-0.24	0.600	0.670	5.5	5.8	-9.75	-9.48
FP-029	9/8/2025 8:28:58 AM	86.3	86.4	-0.18	-0.18	6.101	5.863	17.4	17.1	-9.66	-9.45
FP-030	9/5/2025 10:45:05 AM	100.9	101.0	-0.10	-0.12	2.036	1.943	9.9	9.7	-6.64	-6.56
FP-031	9/5/2025 10:41:40 AM	98.0	98.7	-0.09	-0.09	0.560	0.613	5.2	5.5	-6.99	-7.89
FP-032	9/5/2025 10:33:41 AM	97.7	97.8	-0.26	-0.15	1.518	1.643	8.6	9.0	-7.33	-7.30
FP-033	9/5/2025 10:27:54 AM	91.3	91.2	-0.21	-0.25	3.837	3.965	13.7	14.0	-6.75	-6.88
FP-034	9/5/2025 10:21:23 AM	94.2	94.2	-0.22	-0.18	5.093	5.271	15.8	16.0	-7.17	-7.36
FP-035	9/5/2025 10:16:28 AM	94.8	94.9	-0.16	-0.11	1.285	1.334	7.9	8.1	-7.18	-7.19
FP-036	9/18/2025 2:08:17 PM	87.4	87.1	-0.07	-0.05	9.298	3.051	6.0	3.5	-9.50	-9.93
FP-036	9/18/2025 2:11:54 PM	87.9	88.0	-0.04	-0.04	3.197	3.298	3.5	3.6	-9.73	-10.01
FP-037	9/5/2025 9:16:08 AM	85.1	85.1	-0.27	-0.26	11.596	11.919	10.5	10.6	-10.31	-10.51
FP-037	9/18/2025 2:01:40 PM	87.5	87.5	-0.10	-0.09	11.853	1.530	10.6	3.8	-10.63	-10.65
FP-038	9/10/2025 8:35:07 AM	80.2	80.3	-0.21	-0.21	0.000	0.032			-8.47	-8.55
FP-038	9/16/2025 9:36:00 AM	83.4	83.6	-1.06	-0.46	2.889	0.992	48.5	28.5	-4.51	-6.05
FP-039	9/16/2025 9:31:44 AM	83.3	83.4	-1.58	-0.89	3.289	1.707	51.7	37.3	-6.04	-5.26
FP-040	9/10/2025 8:38:58 AM	86.6	86.6	-0.20	-0.18	0.025	0.030			-8.80	-9.04
FP-041	9/10/2025 8:43:16 AM	65.1	65.1	-6.46	-6.45	6.666	6.605	18.4	18.3	-8.69	-8.92
FP-042	9/10/2025 9:17:47 AM	71.8	71.8	-0.13	-0.12	0.779	0.875	6.3	6.7	-3.99	-4.53
FP-043	9/10/2025 8:24:49 AM	75.3	75.4	-0.19	-0.19	0.011	0.017			-9.78	-10.39
FP-044	9/10/2025 8:28:48 AM	74.4	74.4	-0.30	-0.32	0.090	0.146	2.1	2.7	-9.84	-10.07
FP-046	9/10/2025 8:47:15 AM	79.5	79.5	-0.12	-0.12	5.180	5.343	16.1	16.4	-7.16	-7.50
FP-047	9/5/2025 2:05:11 PM	98.3	98.8	-0.02	-0.07	0.046	0.044	1.5	1.5	-0.67	-0.63
H-01 (EXP-01)	9/4/2025 1:05:14 PM	112.0	115.5	1.84	-0.28	0.000	0.264			-5.21	-5.22
H-01 (EXP-01)	9/4/2025 1:08:50 PM	115.3	113.7	-0.78	-0.84	0.780	0.817			-5.17	-5.18
H-01 (EXP-01)	9/17/2025 11:09:01 AM	103.6	106.7	0.36	-0.10	0.000	0.109			-5.75	-6.14
H-01 (EXP-01)	9/17/2025 11:09:42 AM	106.8	106.8	-0.20	-0.21	0.211	0.213			-6.51	-6.48
H-02 (EXP-02)	9/8/2025 10:16:58 AM	115.1	115.2	-4.03	-4.08	3.975	4.087			-5.49	-5.53
H-02 (EXP-02)	9/8/2025 10:34:02 AM	116.2	118.0	-3.98	-4.26	3.981	4.297			-5.31	-5.39
H-02 (EXP-02)	9/17/2025 1:37:53 PM	120.9	120.6	-4.87	-3.70	4.809	3.708			-5.91	-5.83
H-03 (EXP-03)	9/8/2025 10:22:40 AM	123.0	123.6	-3.21	-3.15	3.238	3.157			-5.53	-5.50
H-03 (EXP-03)	9/17/2025 1:41:01 PM	123.3	123.3	-3.49	-3.50	3.467	3.467			-5.73	-5.73
H-04 (EXP-04)	9/8/2025 10:29:11 AM	131.7	130.5	-1.45	-0.60	1.450	0.597			-5.92	-5.74
H-04 (EXP-04)	9/16/2025 1:31:30 PM	132.0	131.4	-0.98	-0.45	0.960	0.456			-6.03	-6.05
H-04 (EXP-04)	9/16/2025 1:32:14 PM	131.5	131.5	-0.38	-0.35	0.389	0.362			-6.08	-6.04
H-08 (EXP-08)	9/2/2025 1:28:32 PM	119.6	119.6	-1.68	-1.62	1.699	1.638			-3.78	-3.70

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
H-08 (EXP-08)	9/16/2025 1:08:27 PM	124.8	125.1	-2.53	-2.53	2.543	2.543			-4.71	-4.71
H-10 (EXP-10)	9/2/2025 1:24:32 PM	128.0	128.0	-0.16	-0.16	0.169	0.169			-3.19	-3.19
H-10 (EXP-10)	9/16/2025 1:14:12 PM	128.5	128.5	-1.05	-1.04	1.056	1.024			-4.37	-4.36
H-101W	9/4/2025 10:18:02 AM	104.1	104.2	-6.05	-6.06	0.261	0.217	14.3	13.0	-8.15	-8.22
H-102A	9/4/2025 10:06:04 AM	97.3	97.3	-5.70	-5.70	0.142	0.161	4.8	5.1	-8.78	-8.81
H-1401W	9/4/2025 10:09:32 AM	97.3	97.3	-8.80	-8.79	0.125	0.126	4.5	4.5	-8.72	-8.75
H-1404C	9/4/2025 11:36:42 AM	120.7	120.7	-0.26	-0.26	0.133	0.516	2.5	5.0	-6.78	
H-1404C	9/23/2025 10:25:54 AM	122.7	123.1	-0.55	-0.53	0.820	0.969	2.7	3.0	-11.19	-10.89
H-1404C	9/23/2025 10:28:02 AM	122.9	122.9	-0.58	-0.58	0.793	0.770	6.1	6.0	-11.03	-11.25
H-1405C	9/2/2025 11:14:44 AM	108.7	108.2	-0.66	-0.43	0.031	0.007	2.2	1.1	-6.61	-6.55
H-1405C	9/17/2025 9:23:59 AM	109.1	109.2	-0.49	-0.48	0.011	0.011	1.3	1.3	-8.28	-8.49
H-1406W	9/2/2025 2:18:09 PM	110.7	110.9	-3.52	-0.67	0.114	0.080	4.3	3.6	-6.31	-5.95
H-1406W	9/17/2025 10:40:11 AM	105.5	106.8	-4.64	-4.63	0.033	0.000	2.3	0.0	-4.72	-5.04
H-1408CR	9/5/2025 2:06:03 PM	116.8	116.7	-0.16	-0.16	0.876	0.875	11.6	11.5	-9.52	
H-1408E	9/3/2025 9:02:29 AM	121.8	121.8	-0.93	-0.98	2.191	2.327	18.5	19.0	-5.91	-5.90
H-1408E	9/16/2025 2:11:47 PM	122.0	123.5	-0.28	-0.32	0.095	0.593	3.8	9.6	-6.81	-6.76
H-1408W	9/2/2025 1:49:59 PM	116.2	116.2	-0.22	-0.22	0.028	0.028	4.6	4.6	-6.67	-6.67
H-1409N	9/4/2025 3:01:47 PM	124.9	124.9	-0.36	-0.38	1.486	1.375	2.3	2.2	-6.83	
H-1409N	9/17/2025 2:33:39 PM	134.3	134.0	-0.66	-0.49	0.468	0.410	1.3	1.2	-8.83	-8.99
H-1409N	9/17/2025 2:34:42 PM	133.9	133.7	-0.45	-0.40	0.445	0.412	1.3	1.2	-8.90	-8.93
H-1410S	9/5/2025 8:46:48 AM	86.7	86.6	-5.90	-5.86	-0.046	-0.043	0.0	0.0	-9.11	
H-1563N	9/8/2025 10:53:11 AM	113.8	113.9	-2.70	-2.33	2.404	1.990	20.0	18.2	-4.40	
H-1563N	9/16/2025 10:40:40 AM	115.0	114.9	-4.04	-3.30	2.521	1.996	19.8	17.7	-5.23	-4.08
H-1563S	9/2/2025 11:18:36 AM	114.8	114.4	-0.94	-0.40	2.336	0.285	4.6	1.6	-6.63	-6.42
H-1563S	9/17/2025 9:25:54 AM	117.7	117.7	-0.53	-0.52	1.969	2.022	4.3	4.3	-8.67	-9.32
H-1565E	9/5/2025 11:05:08 AM	114.9	114.9	-3.52	-3.49	1.032	1.069	13.1	13.3	-4.78	
H-1565E	9/16/2025 2:18:16 PM	110.2	110.4	-5.70	-5.40	0.310	0.332	7.0	7.2	-6.24	-6.14
H-1568N	9/3/2025 8:56:33 AM	112.8	112.8	-0.63	-0.63	2.317	2.268	10.5	10.4	-6.41	-5.81
H-1568N	9/16/2025 2:03:44 PM	116.6	116.3	-1.20	-0.94	1.641	0.729	8.8	5.9	-6.30	-5.94
H-1571S	9/10/2025 11:08:36 AM	114.8	114.4	-3.10	-2.58	0.039	0.039	4.1	4.1	-14.00	-13.83
H-1572N	9/9/2025 2:17:13 PM	137.1	137.3	-0.05	-0.04	0.167	0.171	2.8	2.8	-10.81	-10.48
H-1572S	9/10/2025 10:58:45 AM	108.4	108.5	-1.21	-1.21	0.161	0.155	8.4	8.2	-14.54	-14.40
H-1574N	9/8/2025 2:06:13 PM	103.1	103.1	-0.48	-0.47	0.604	0.601	21.9	21.9	-1.04	

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
H-1574N	9/17/2025 11:16:09 AM	100.6	100.7	-0.54	-0.53	0.708	0.779			-0.58	-0.71
H-1753S	9/8/2025 10:56:51 AM	112.6	112.8	-4.34	-4.76	0.100	0.100	6.8	6.8	-4.60	
H-1753S	9/16/2025 10:36:21 AM	116.7	116.6	-4.99	-4.87	0.067	0.041	5.4	4.2	-4.35	-4.36
H-1756S	9/2/2025 11:01:13 AM	125.7	125.7	-1.28	-0.76	0.478	0.326	19.1	15.8	-1.72	-2.07
H-1756S	9/17/2025 9:08:42 AM	126.0	125.9	-1.40	-1.05	0.160	0.092	11.0	8.4	-5.64	-5.56
H-1757S	9/2/2025 11:10:19 AM	117.3	116.9	-1.15	-0.75	0.327	0.048	11.9	4.6	-5.85	-6.52
H-1757S	9/17/2025 9:22:06 AM	115.0	115.1	-0.98	-1.00	0.060	0.104	5.1	6.7	-7.84	-9.82
H-1760S	9/3/2025 2:05:45 PM	115.9	115.9	-0.71	-0.71	0.062	0.062	3.1	3.1	-6.64	-6.64
H-1760S	9/18/2025 12:03:19 PM	110.5	110.5	-1.47	-1.47	0.099	0.085	4.0	3.7	-11.03	-11.06
H-1762N	9/3/2025 2:24:11 PM	119.4	120.5	-0.45	-0.41	1.223	1.285	3.3	3.4	-5.45	-5.38
H-1762N	9/16/2025 1:52:23 PM	121.5	121.5	-0.66	-0.66	1.520	1.513	3.7	3.7	-6.70	-6.70
H-1763N	9/9/2025 10:55:22 AM	118.9	118.8	-0.16	-0.16	0.992	1.029	12.5	12.7	-12.64	-12.68
H-1763S	9/10/2025 1:53:38 PM	112.2	112.6	-0.32	-0.31	0.007	0.004	2.3	1.8	-8.64	-8.70
H-1764N	9/10/2025 1:19:03 PM	116.6	116.9	-4.30	-4.33	0.828	0.806	6.2	6.1	-13.85	-13.56
H-1764S	9/10/2025 11:12:59 AM	115.4	113.5	-5.28	-2.85	0.003	0.006	0.7	1.0	-13.82	-13.88
H-1764S	9/10/2025 1:48:16 PM	85.9	85.8	-0.21	-0.18	0.045	0.014	2.8	1.5	-8.88	-8.86
H-1767N	9/23/2025 11:17:56 AM	114.8	114.8	-0.62	-0.59	4.122	4.191	56.3	56.8	-10.73	-11.46
H-1769N	9/9/2025 10:07:48 AM	102.1	102.1	-0.38	-0.37	0.037	0.030	3.8	3.4	-9.75	-9.53
H-1769N	9/16/2025 9:45:36 AM	99.7	102.8	-0.61	-0.69	0.002	0.077	0.8	5.4	-11.63	-10.42
H-1770A	9/5/2025 10:12:48 AM	126.5	126.5	-1.14	-0.85	0.018	0.160	1.7	5.0	-7.43	-7.35
H-1770A	9/16/2025 9:15:11 AM	123.8	123.8	-1.03	-1.03	0.059	0.058	3.0	3.0	-10.34	-10.53
H-1770N	9/9/2025 8:25:00 AM										
H-1770N	9/9/2025 8:25:00 AM										
H-1770N	9/9/2025 10:18:27 AM	108.3	108.3	-0.46	-0.46	1.139	1.213	22.3	23.0	-3.16	-3.12
H-1770N	9/16/2025 9:58:12 AM	104.1	102.6	-0.89	-0.88	1.405	1.290	24.9	23.9	-3.81	-3.92
H-1770N	9/16/2025 10:05:15 AM	107.0	108.9	-0.96	-0.97	0.363	0.568	4.2	5.2	-3.74	-3.70
H-1770S	9/2/2025 10:29:06 AM	101.7	101.7	-0.77	-0.48	0.014	0.008	0.8	0.6	-5.63	-6.99
H-1770S	9/17/2025 8:51:23 AM	98.4	98.3	-0.78	-0.69	0.492	0.388	4.9	4.4	-6.72	-6.55
H-1771A	9/2/2025 1:48:09 PM	128.3	128.4	-0.42	-0.52	0.793	0.523	11.1	9.0	-8.43	-10.22
H-1771B	9/2/2025 11:35:50 AM	124.2	124.3	-0.63	-0.58	0.025	0.090	1.1	2.1	-7.32	-7.46
H-1771B	9/5/2025 1:48:42 PM	122.7	123.4	-0.44	-0.51	0.122	0.121	2.4	2.4	-7.69	-7.98
H-1774N	9/4/2025 7:58:57 AM	108.4	108.4	-0.54	-0.51	0.586	0.528	5.3	5.0	-3.38	-3.17
H-1774N	9/16/2025 10:30:15 AM	112.1	112.1	-1.02	-1.08	0.396	0.624	4.4	5.5	-3.81	-3.93
H-1801S	9/11/2025 8:38:13 AM	122.8	123.7	-0.39	-0.39	0.014	0.010	0.8	0.7	-11.87	-11.56

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
H-1802S	9/9/2025 2:20:40 PM	120.3	121.7	0.05	-0.08	0.012	0.168	3.0	11.3	-10.54	-10.59
H-1802S	9/9/2025 2:21:52 PM	125.6	130.0	-0.16	-0.77	0.172	0.999	11.4	27.4	-10.87	-10.65
H-1803N	9/4/2025 8:13:49 AM	195.2	195.1	1.64	2.71	1.688	2.519	33.9	41.4	0.27	0.18
H-1803N	9/4/2025 8:15:00 AM										
H-1803N	9/4/2025 8:15:00 AM										
H-1803N	9/9/2025 9:29:00 AM										
H-1803N	9/9/2025 9:29:20 AM	195.0	195.2	2.52	2.59	2.436	2.483	40.8	41.1	0.65	0.65
H-1803N	9/17/2025 1:37:14 PM	195.4	194.9	1.93	1.92	1.934	1.752	36.3	34.5	-0.03	-0.03
H-1803N	9/22/2025 9:13:03 AM	194.8	194.9	1.79	1.73	1.739	1.779	34.4	34.8	0.35	0.35
H-1803N	9/25/2025 11:24:34 AM	194.9	195.0	2.70	1.46	2.764	1.405	43.4	31.0	0.33	0.34
H-1803N	9/29/2025 1:53:02 PM	195.3	195.4	3.97	1.64	4.149	1.572	53.2	32.7	0.00	0.00
H-1804B	9/9/2025 10:44:31 AM	110.8	110.7	-5.32	-4.28	0.805	0.508	11.2	8.9	-8.00	-8.31
H-1804N	9/2/2025 1:56:19 PM	122.0	121.8	-0.52	-0.53	0.013	0.009	0.8	0.7	-8.71	-8.68
H-1804S	9/10/2025 1:24:21 PM	112.5	109.3	-9.99	-2.16	0.294	0.001	6.7	0.5	-13.50	-13.50
H-1805A	9/3/2025 10:39:10 AM	128.6	128.4	-0.33	-0.32	0.013	0.025	3.2	4.4	-6.79	-5.47
H-1805B	9/9/2025 2:37:46 PM	93.4	93.6	-0.68	-0.64	0.044	0.041	1.5	1.4	-10.44	-10.40
H-1805S	9/10/2025 1:41:01 PM	126.3	126.4	-2.89	-2.88	0.213	0.229	9.5	9.8	-13.64	-13.57
H-1806A	9/3/2025 10:01:21 AM	117.5	118.7	-0.29	-1.03	0.717	6.974	17.6	54.4	-9.39	-9.40
H-1806A	9/11/2025 1:57:13 PM	115.5	112.7	-0.44	-0.52	0.439	0.529	13.8	15.1	-9.80	-9.78
H-1806B	9/9/2025 2:13:40 PM	127.9	128.0	-0.06	-0.03	4.069	3.952	13.7	13.5	-9.96	-9.24
H-1806N	9/2/2025 2:20:16 PM	129.9	128.4	-0.49	-0.45	0.034	0.082	5.1	7.9	-8.42	-8.59
H-1806S	9/4/2025 2:58:47 PM	115.5	115.4	-1.17	-0.75	0.203	0.290	9.4	11.2	-10.13	-10.19
H-1807A	9/4/2025 1:51:37 PM	119.2	119.6	-3.21	-3.23	1.274	1.365	31.1	32.2	-9.05	-9.08
H-1807N	9/26/2025 1:13:28 PM	103.7	104.9	-1.65	-0.24	7.442	0.002	34.3	0.6	-8.93	-9.23
H-1807N	9/26/2025 1:14:17 PM	103.6	103.4	-0.06	-0.06	0.002	0.003	0.6	0.7	-8.98	-8.42
H-1807N	9/26/2025 2:00:16 PM	111.8	109.6	-2.89	-2.05	6.323	3.152	31.4	22.3	-9.49	-9.74
H-1807N	9/26/2025 2:08:42 PM	111.4	108.8	-1.88	-1.85	2.526	2.250	19.9	18.9	-8.62	-8.28

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
H-1807S	9/4/2025 2:16:55 PM	104.6	104.7	-0.15	-0.15	0.079	0.077	7.9	7.8	-9.61	-9.54
H-1952S	9/15/2025 10:24:17 AM	126.2	126.3	-2.10	-2.10	1.556	1.554	8.5	8.5	-10.34	-10.84
H-1952S	9/16/2025 1:38:39 PM	126.1	126.2	-0.66	-0.39	1.022	0.816	6.9	6.2	-7.19	-6.80
H-1953N	9/5/2025 2:21:22 PM	133.9	134.1	-0.50	-0.54	0.264	0.273	6.3	6.4	-8.08	-7.61
H-1953N	9/29/2025 2:24:25 PM	134.7	129.2	-0.63	-0.12	0.133	-0.034	4.3	0.0	-10.03	
H-1953N	9/29/2025 2:27:26 PM	121.0	120.8	-0.12	-0.12	-0.026	-0.025	0.0	0.0	-10.07	
H-1954C	9/2/2025 11:28:47 AM	101.2	101.4	-0.71	-0.62	0.244	0.163	6.3	5.1	-7.41	-7.57
H-1955C	9/3/2025 10:41:57 AM	118.8	118.9	-0.96	-1.05	4.086	7.377	55.8	74.7	-4.28	-7.44
H-1955C	9/11/2025 10:39:37 AM	117.3	117.2	-1.34	-1.41	5.091	6.008	62.2	67.5	-5.91	-6.74
H-1955N	9/2/2025 2:05:36 PM	106.3	106.4	-1.17	-1.12	0.117	0.160	4.3	5.1	-8.24	-8.29
H-1956B	9/11/2025 1:05:43 PM	123.8	123.8	-5.59	-5.58	0.757	0.714	17.8	17.3	-10.01	-9.61
H-1956N	9/2/2025 2:13:34 PM	116.0	116.2	-1.85	-1.80	0.384	0.469	7.8	8.6	-8.36	-8.51
H-1956S	9/10/2025 2:22:07 PM	122.9	123.0	-1.26	-1.26	1.226	1.227	7.6	7.6	-13.20	-13.20
H-1957B	9/9/2025 1:57:55 PM	105.8	111.0	-0.02	-0.03	1.428	2.009	15.1	17.8	-10.03	-10.05
H-1957N	9/2/2025 2:23:01 PM	123.5	123.6	-1.28	-1.23	0.120	0.204	4.3	5.6	-8.31	-8.41
H-1957S	9/11/2025 8:41:14 AM	101.7	101.8	-0.51	-0.51	0.023	0.024	1.1	1.1	-11.75	-12.44
H-1958C	9/4/2025 1:49:18 PM	123.4	123.4	-0.48	-0.48	0.071	0.083	3.3	3.6	-9.21	-9.21
H-1958N	9/26/2025 1:17:27 PM	121.8	122.1	-0.60	-0.62	2.851	2.766	5.1	5.0	-10.06	-10.32
H-1958N	9/26/2025 2:11:07 PM	122.1	122.5	-0.62	-0.63	1.986	1.953	38.8	38.5	-9.43	-9.41
H-1958S	9/4/2025 2:14:33 PM	127.7	127.7	-0.42	-0.42	0.077	0.078	3.4	3.5	-9.55	-9.75
H-1962N	9/4/2025 8:20:52 AM	101.1	101.2	-0.71	-0.69	0.041	0.059			-3.01	-2.98
H-1962N	9/16/2025 10:15:27 AM	119.2	119.2	-0.66	-0.39	0.033	0.022			-3.77	-3.94
H-1963N	9/4/2025 8:28:41 AM	130.9	128.0	-1.23	-0.30	1.456	1.234	22.9	21.1	-8.68	-9.53
H-1963N	9/16/2025 9:50:06 AM	130.8	130.6	-1.41	-1.13	0.789	0.195	16.9	8.4	-9.65	-10.21
H-1966N	9/4/2025 8:09:16 AM	108.9	108.1	-0.62	-0.54	0.797	0.501	6.2	4.9	-8.97	-8.75
H-1966N	9/4/2025 8:13:18 AM	107.2	106.6	-0.51	-0.44	2.614	1.144	4.9	3.3	-8.60	-8.64
H-1966N	9/16/2025 10:37:50 AM	107.6	107.8	-0.42	-0.40	2.435	2.496	4.8	4.8	-8.56	-8.58
H-1967E	9/24/2025 1:59:15 PM	104.3	104.2	-1.42	-1.42	0.033	0.021	5.1	4.1	-13.53	-13.36
H-1967W	9/2/2025 1:05:01 PM	110.0	110.3	-1.64	-1.59	3.448	3.523	51.8	52.3	-7.81	-7.85
H-2050E	9/25/2025 10:10:00 AM	96.7	95.2	-12.29	-12.23	1.293	1.206	14.4	13.9	-13.06	-12.93
H-2050W	9/15/2025 3:15:02 AM	107.3	107.1	-1.43	-0.95	0.388	0.182	13.3	9.1	-5.72	
H-2051W	9/2/2025 1:00:27 PM	112.8	120.8	-4.25	-1.74	0.077	0.048	7.7	6.1	-7.06	-7.27
H-2053E	9/24/2025 2:06:57 PM	124.2	124.1	-6.73	-6.38	4.450	3.742	57.7	53.0	-11.78	-11.26
H-2053W	9/4/2025 10:12:14 AM	101.9	101.9	-7.05	-7.05	0.056	0.052	6.6	6.4	-8.83	-8.75
H-2055E	9/5/2025 1:46:46 PM	112.5	112.7	-0.17	-0.23	0.556	1.224	9.4	13.9	-8.46	

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
H-2055E	9/17/2025 2:05:00 PM	114.1	114.2	-0.38	-0.19	1.712	0.306	16.4	7.0	-11.46	-11.43
H-2056B	9/24/2025 1:10:25 PM	105.3	105.4	-1.30	-1.00	1.031	0.536	7.2	5.2	-7.14	
H-2056W	9/2/2025 1:09:23 PM	110.4	111.4	-5.70	-4.14	1.366	0.069	32.5	7.3	-7.07	-7.26
H-2057E	9/24/2025 2:02:27 PM	129.4	129.4	-1.45	-1.29	1.311	1.379	7.8	8.0	-14.80	-14.29
H-2057W	9/4/2025 10:23:26 AM	106.7	106.9	-4.60	-4.59	0.118	0.124	9.6	9.8	-7.93	-7.95
H-2058E	9/24/2025 1:49:04 PM	113.1	113.2	-5.12	-5.28	3.486	3.900	12.8	13.6	-9.03	-9.71
H-2058W	9/2/2025 1:12:00 PM	106.5	106.9	-3.54	-3.03	1.882	1.360	38.3	32.6	-6.59	-7.03
H-2059E	9/24/2025 2:13:04 PM	113.0	113.0	-7.00	-7.14	7.202	7.284	73.9	74.3	-12.73	-12.86
H-2059W	9/2/2025 1:42:22 PM	125.9	125.9	-3.00	-3.00	3.577	3.561	38.8	38.7	-6.27	-6.51
H-2160E	9/24/2025 10:51:59 AM	92.7	91.5	-10.76	-0.12	-0.025	0.066	0.0	7.6	-10.26	
H-2160E	9/24/2025 10:54:32 AM	92.6	92.7	-0.33	-0.23	-0.524	-0.299	0.0	0.0	-10.64	
H-2161E	9/24/2025 10:43:45 AM	122.9	123.1	-1.84	-2.21	1.326	1.514	33.4	35.7	-14.46	
H-2161W	9/2/2025 1:39:12 PM	111.5	111.6	-3.45	-3.46	0.408	0.363	17.8	16.8	-7.13	-6.90
H-2163C	9/4/2025 9:18:37 AM	105.7	105.9	-0.49	-0.48	0.237	0.240	3.3	3.3	-8.99	
H-2163C	9/17/2025 10:14:10 AM	109.3	109.3	-0.63	-0.66	1.049	1.047	28.6	28.6	-1.96	-2.09
H-2163W	9/2/2025 1:46:59 PM	122.8	122.7	-1.24	-1.23	4.691	4.748	26.9	27.1	-6.47	-6.57
H-2164A	9/4/2025 8:46:43 AM	96.6	96.8	-0.77	-0.74	0.687	0.599	5.6	5.2	-8.20	
H-2164A	9/17/2025 1:26:34 PM	102.1	102.4	-1.18	-0.98	0.122	0.044	4.4	2.7	-9.22	-8.83
H-2164E	9/5/2025 1:54:04 PM	124.0	124.0	-0.47	-0.44	-0.018	0.095	0.0	3.9	-9.32	
H-2164E	9/17/2025 2:12:25 PM	124.2	124.2	-0.57	-0.56	0.561	0.601	9.3	9.7	-12.13	-12.30
H-2165E	9/18/2025 9:22:00 AM	118.3	117.7	-6.08	-4.16	6.160	4.070	30.7	25.1	-6.73	-4.01
H-2165W	9/2/2025 2:08:31 PM	121.2	121.5	-0.79	-0.40	0.106	0.404	9.0	17.6	-2.10	-2.20
H-2165W	9/8/2025 8:50:00 AM										
H-2165W	9/8/2025 8:50:00 AM										
H-2165W	9/17/2025 10:28:09 AM	134.0	133.8	-1.42	-1.39	0.018	0.023	0.4	0.5	-2.75	-2.68
H-2165W	9/17/2025 10:29:10 AM	133.2	133.1	-1.39	-1.31	0.088	0.013	0.9	0.4	-2.54	-2.58
H-2166C	9/3/2025 10:45:07 AM	116.2	116.5	-0.54	-0.50	0.197	0.262	5.6	6.4	-8.75	-8.92
H-2166E	9/9/2025 1:40:34 PM	122.7	122.8	-0.58	-0.58	2.793	2.605	20.8	20.1	-7.99	-7.52
H-2167A	9/4/2025 1:40:32 PM	116.2	116.1	-0.22	-0.21	9.693	9.793	21.3	21.4	-8.09	-8.11
H-2167A	9/4/2025 1:44:14 PM	116.8	117.0	-2.53	-0.53	7.311	1.470	18.4	8.3	-7.74	-8.30
H-2167E	9/4/2025 1:55:32 PM	108.4	108.5	-1.89	-1.83	1.611	1.616	3.9	3.9	-9.15	-9.04
H-2168C	9/11/2025 1:18:33 PM	94.3	94.3	-10.07	-10.07	0.023	0.009	4.3	2.7	-10.28	-10.11
H-2168E	9/9/2025 2:02:29 PM	116.5	117.1	-0.03	-0.05	0.186	0.212	5.4	5.8	-9.99	-10.11

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
H-2169C	9/9/2025 2:41:52 PM	108.2	108.2	-0.50	-0.50	0.218	0.253	13.0	14.0	-10.77	-10.53
H-2169E	9/9/2025 2:08:32 PM	120.2	120.2	-0.30	-0.26	2.350	2.121	42.3	40.2	-10.43	-10.69
H-2170N	9/25/2025 1:48:51 PM	120.2	120.2	-0.99	-0.97	2.215	2.221	18.6	18.6	-8.29	-8.47
H-2170S	9/11/2025 10:20:40 AM	111.5	112.2	-4.76	-2.90	0.650	0.195	10.1	5.6	-12.94	-13.19
H-2171A	9/26/2025 1:23:26 PM	103.9	104.0	-0.65	-0.62	0.169	0.028	5.2	2.1	-1.07	-0.56
H-2171B	9/22/2025 1:13:39 PM	119.0	119.0	-1.19	-1.19	1.454	1.465	15.1	15.2	-2.23	-2.24
H-2171N	9/22/2025 2:09:45 PM	129.4	130.3	-0.82	-0.70	0.245	0.104	6.1	4.0	-6.71	-6.73
H-2171S	9/25/2025 1:45:48 PM	121.3	121.4	-0.55	-0.54	2.801	2.864	20.9	21.1	-6.92	-7.03
H-2272W	9/8/2025 9:12:55 AM	118.9	119.1	-1.17	-1.09	2.793	2.138	21.1	18.4	-8.85	
H-2272W	9/17/2025 9:44:23 AM	122.8	122.8	-0.98	-0.98	2.542	2.613	19.9	20.1	-9.86	-10.01
H-2273W	9/2/2025 11:28:47 AM	128.5	128.6	-0.62	-0.66	0.058	0.054	3.0	2.9	-1.67	-1.66
H-2273W	9/10/2025 10:25:00 AM										
H-2273W	9/10/2025 10:25:00 AM										
H-2273W	9/17/2025 9:31:19 AM	128.4	128.2	-0.97	-0.75	0.304	0.023	6.9	1.9	-4.63	-4.82
H-2274B	9/4/2025 11:11:50 AM	120.5	120.5	-1.99	-1.98	-0.024	-0.021	0.0	0.0	-6.15	
H-2274B	9/21/2025 12:14:18 PM	121.1	121.1	-2.76	-2.75	0.027	0.026	6.5	6.3	-10.23	-9.06
H-2274W	9/2/2025 10:50:19 AM	126.7	126.5	-0.60	-0.63	0.023	0.003	1.9	0.7	-1.99	-2.01
H-2274W	9/17/2025 9:06:21 AM	127.3	126.8	-0.93	-0.76	2.352	0.478	19.0	8.6	-5.26	-5.39
H-2275E	9/10/2025 1:57:24 PM	125.0	125.0	-0.93	-0.95	0.668	0.593	10.2	9.6	-8.81	-8.84
H-2275W	9/2/2025 11:37:01 AM	122.1	122.2	-0.82	-0.70	2.046	1.983	17.9	17.6	-6.50	-6.43
H-2275W	9/17/2025 9:37:22 AM	122.4	122.4	-0.99	-0.58	3.414	1.012	23.0	12.6	-10.39	-10.42
H-2276A	9/4/2025 2:35:58 PM	99.1	99.0	-3.04	-3.24	0.637	0.642	17.4	17.4	-6.32	
H-2276A	9/18/2025 10:41:48 AM	105.8	105.0	-5.03	-4.04	1.005	0.728	20.9	17.8	-8.76	-8.90
H-2276B	9/4/2025 3:06:24 PM	116.9	117.4	-2.08	-2.77	0.044	0.473	4.5	14.7	-6.97	
H-2276B	9/17/2025 2:37:23 PM	118.4	117.7	-3.67	-1.80	1.341	0.280	23.8	10.9	-8.95	-9.16
H-2276E	9/10/2025 1:38:22 PM	124.3	124.3	-0.77	-0.76	0.299	0.251	15.1	13.8	-13.72	-13.63
H-2276W	9/2/2025 11:07:22 AM	107.6	107.6	-2.24	-1.25	0.006	0.008	0.9	1.1	-6.20	-6.71
H-2276W	9/17/2025 9:19:50 AM	98.6	98.7	-0.46	-0.46	0.151	0.151	5.0	5.0	-7.55	-7.69
H-2277A	9/4/2025 2:25:54 PM	104.1	104.3	-6.40	-6.23	-0.038	0.000	0.0	0.2	-5.94	
H-2277A	9/18/2025 9:22:51 AM	66.0	65.9	-7.80	-7.74	0.121	0.113	4.5	4.4	-7.71	-7.67
H-2277B	9/3/2025 1:48:32 PM	110.9	111.1	-1.35	-1.36	3.976	3.946	25.0	24.9	-5.09	-5.17
H-2277B	9/18/2025 8:40:52 AM	100.2	100.1	-2.03	-2.03	3.104	3.104	3.4	3.4	-7.82	-7.82
H-23 (EXP-23)	9/22/2025 1:27:26 PM	109.8	111.7	12.67	-5.03	0.012	0.012	2.3	2.2	-7.99	-8.13
H-23 (EXP-23)	9/22/2025 1:28:11 PM	111.1	111.1	-6.01	-6.00	0.023	0.021	3.2	3.0	-7.88	-8.16

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
H-2301E	9/26/2025 10:18:59 AM	109.5	109.6	-1.30	-1.30	0.305	0.307	15.5	15.5	-8.09	-8.08
H-2301E	9/28/2025 9:41:01 AM	109.7	109.3	-1.52	-1.27	2.312	1.107	19.3	13.4	-9.65	-9.78
H-2302C	9/26/2025 10:05:25 AM	114.1	114.0	-1.20	-1.20	0.999	0.999	27.9	27.9	-8.13	-8.13
H-2302E	9/26/2025 10:24:06 AM	102.0	102.0	-3.76	-3.70	0.063	0.182	7.1	12.0	-4.72	-4.83
H-2303E	9/29/2025 12:23:25 PM	91.5	91.1	-5.10	-4.94	0.044	0.013	5.9	3.3	-5.03	-4.86
H-2303N	9/24/2025 1:26:15 PM	101.7	101.9	-2.56	-2.34	2.091	1.331	30.9	24.7	-10.36	
H-2303N	9/26/2025 10:30:36 AM	76.8	76.9	-5.03	-5.03	0.121	0.151	10.0	11.2	-4.74	-4.70
H-2304S	9/25/2025 9:34:44 AM	132.5	131.8	-1.64	-0.22	4.038	0.257	24.9	6.3	-10.53	-10.41
H-2304S	9/25/2025 9:36:47 AM	131.1	131.1	-0.09	-0.08	0.292	0.272	6.7	6.5	-10.38	-10.45
H-2304S	9/28/2025 10:01:06 AM	128.9	129.6	0.15	-0.01	0.578	1.750	5.2	9.1	-9.85	-9.86
H-2304S	9/28/2025 10:02:10 AM	129.9	129.9	-0.01	-0.01	1.658	1.544	8.8	8.5	-9.83	-9.85
H-2305N	9/15/2025 10:55:37 AM	98.9	98.2	-2.83	-2.15	3.342	3.588	38.5	39.9	-9.77	-9.26
H-2305S	9/25/2025 9:23:38 AM	127.4	127.5	-3.41	-2.74	7.993	3.568	35.0	23.5	-11.21	-11.36
H-2306N	9/25/2025 9:09:05 AM	113.5	113.5	-2.05	-2.01	0.606	0.730	21.7	23.9	-13.66	-13.64
H-2306S	9/25/2025 10:02:00 AM	88.0	88.2	-4.89	-4.90	0.033	0.034	3.9	3.9	-12.57	-12.48
H-2309N	9/4/2025 9:10:43 AM	96.2	96.5	-8.90	-8.82	-0.091	-0.132	0.0	0.0	-9.03	
H-2309S	9/25/2025 9:44:15 AM	117.2	117.2	-4.73	-3.88	4.376	2.209	43.3	30.8	-9.77	-11.23
H-2402N	9/24/2025 2:19:19 PM	112.5	112.6	-0.82	-0.82	5.056	5.045	4.4	4.4	-10.51	
H-2402S	9/26/2025 9:54:58 AM	111.7	111.6	-1.00	-0.75	0.628	0.424	22.1	18.2	-10.10	-10.64
H-2403N	9/24/2025 2:26:03 PM	115.8	116.1	-0.31	-0.28	1.140	1.133	7.4	7.4	-11.19	
H-2403S	9/15/2025 9:46:37 AM	92.3	92.2	-0.03	-0.18	0.016	0.015	0.9	0.9	-12.05	-12.31
H-2404N	9/24/2025 2:35:49 PM	108.9	109.1	-0.96	-0.82	0.327	0.189	4.0	3.1	-11.25	
H-2404S	9/24/2025 1:35:09 PM	108.6	108.9	-5.77	-6.11	1.054	0.889	30.0	27.6	-7.32	
H-2405N	9/15/2025 2:07:22 AM	114.3	114.4	-0.22	-0.22	8.299	8.079	8.5	8.4	-10.09	
H-29	9/25/2025 11:06:12 AM	130.1	130.1	-1.05	-1.04	0.246	0.302	3.4	3.7	-11.98	-11.88
H-31	9/26/2025 1:18:15 PM	124.8	124.8	-2.67	-2.61	0.041	0.050	1.4	1.5	-6.78	-6.61
H-72	9/26/2025 1:36:30 PM	103.6	103.8	-0.98	-0.88	0.001	0.006	0.9	2.1	-6.44	-6.35
H-74	9/22/2025 2:35:19 PM	106.1	106.2	-2.97	-3.23	4.603	5.407	6.5	7.1	-9.31	-9.37
H-79	9/4/2025 2:39:10 PM	135.5	134.6	-0.43	-0.21	0.003	0.007	1.6	2.3	-9.24	-9.28
H-79	9/4/2025 2:40:50 PM	134.4	132.4	-0.32	-0.10	0.072	0.007	7.3	2.3	-9.30	-9.27
P-02R	9/9/2025 2:05:59 PM	94.9	93.5	0.00	-0.11	0.020	0.049	1.8	2.9	-19.35	-19.55

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
P-02R	9/9/2025 2:06:41 PM	93.5	93.3	-0.09	-0.09	0.045	0.045	2.7	2.7	-19.54	-19.54
P-03R	9/9/2025 1:58:57 PM	105.0	105.0	-0.15	-0.15	0.316	0.319	1.7	1.7	-18.04	-18.06
P-04	9/9/2025 1:54:13 PM	106.0	106.0	-0.49	-0.49	0.497	0.497			0.00	0.00
P-05	9/10/2025 1:07:01 PM	107.3	107.0	-0.13	-0.13	0.118	0.119			-16.59	-16.48
P-06R	9/9/2025 2:32:42 PM	106.8	113.6	-0.04	-0.69	0.003	0.367	0.2	1.9	-14.60	-14.28
P-07R	9/23/2025 2:25:44 PM	94.8	94.6	-0.92	-0.90	0.513	0.521	2.3	2.3	-20.91	
P-08R	9/9/2025 2:11:47 PM	102.3	102.4	-14.04	-14.47	0.193	0.235	5.5	6.1	-16.91	-16.57
P-09	9/9/2025 2:20:26 PM	102.1	101.2	-1.72	-0.63	1.708	0.614			-8.99	-11.03
P-10	9/9/2025 10:10:17 AM	97.2	97.2	-0.68	-0.60	4.894	2.207	6.8	4.6	-9.49	-9.38
P-11	9/9/2025 10:20:54 AM	108.4	108.5	-0.81	-0.59	8.668	3.516	9.0	5.7	-9.61	-9.77
P-12	9/9/2025 10:47:34 AM	89.2	89.2	-9.93	-9.97	1.440	1.440	8.4	8.4	-11.32	-11.34
P-13	9/9/2025 10:42:54 AM	88.3	88.3	-0.81	-0.81	0.844	0.846	6.5	6.5	-11.45	-11.47
P-14	9/9/2025 10:33:15 AM	86.2	98.2	-0.27	-0.27	0.263	0.264			-10.84	-10.79
P-15R	9/10/2025 10:45:32 AM	89.2	89.2	-1.37	-1.36	0.341	0.348	1.8	1.8	-12.04	-11.65
P-16	9/23/2025 9:39:29 AM	99.3	99.3	-4.82	-4.82	0.085	0.085	0.0	0.0	-12.03	
P-17	9/10/2025 1:19:43 PM	117.5	116.6	-0.87	-0.57	0.822	0.561			-10.43	-10.83
P-18RD	9/10/2025 11:25:13 AM	90.2	89.0	-1.12	-2.02	0.001	0.008	0.1	0.3	-10.78	-10.74
P-18RS	9/10/2025 11:13:40 AM	97.3	97.2	-2.07	-1.53	9.256	2.736	9.3	5.1	-10.61	-10.90
P-19	9/23/2025 10:10:10 AM	92.5	92.5	-1.47	-1.46	2.006	1.999	18.4	18.3	-11.55	
P-20R	9/10/2025 11:07:12 AM	100.0	100.2	-1.17	-1.17	2.795	2.754	5.2	5.1	-10.50	-10.35
P-21	9/10/2025 11:02:39 AM	94.4	90.2	-0.97	-0.74	0.962	0.733			-10.01	-10.36
P-21RD	9/23/2025 10:17:50 AM	104.5	104.5	-5.24	-5.24	4.121	4.314	26.0	26.6	-9.41	
P-21RS	9/23/2025 10:13:04 AM	109.5	109.5	-6.35	-6.34	1.999	2.228	17.9	18.9	-9.82	
P-22RD	9/23/2025 10:54:08 AM	121.2	121.3	-4.24	-4.24	4.662	4.313	27.6	26.6	-8.98	
P-22RS	9/23/2025 10:52:10 AM	120.0	120.0	-1.83	-1.79	2.393	2.433	4.7	4.7	-8.79	
P-23	9/10/2025 10:55:26 AM	114.1	109.2	-4.84	-0.45	0.000	0.002			-9.14	-9.72
P-24	9/10/2025 1:30:15 PM	97.7	97.7	-1.18	-1.15	1.485	1.493	3.8	3.8	-8.98	-8.74
P-26	9/10/2025 1:48:18 PM	86.9	86.9	-2.91	-2.90	2.872	2.872			-0.02	-0.02
P-27	9/11/2025 1:32:24 PM	93.9	94.4	-0.75	-0.44	0.745	0.433			-7.87	-7.78
P-28	9/11/2025 1:38:30 PM	98.2	98.2	-3.52	-3.49	3.490	3.447			-7.65	-7.53
P-29R	9/11/2025 1:45:33 PM	97.7	97.7	-0.65	-0.53	0.017	0.006	1.7	1.0	-7.70	-7.43
P-30R	9/11/2025 1:50:22 PM	89.8	89.9	-2.50	-2.49	0.540	0.536	5.2	5.2	-7.47	-7.51
P-32R1	9/12/2025 1:42:57 PM	129.9	129.9	-7.30	-7.38	7.471	7.554			-7.50	-7.41
P-32R1	9/15/2025 11:26:51 AM	114.4	112.9	-1.28	-1.12	0.238	0.015	1.5	0.4	-9.15	-7.86
P-32R1	9/15/2025 11:28:36 AM	112.9	113.0	-1.05	-1.05	0.010	0.016	0.3	0.4	-7.68	-9.20
P-32R2	9/12/2025 1:48:49 PM	113.6	112.5	-1.38	-1.17	0.541	0.032	5.1	1.2	-6.70	-6.74
P-33	9/12/2025 1:59:27 PM	99.3	99.3	-2.04	-2.04	2.020	2.026			-5.99	-6.40

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
P-36	9/12/2025 2:24:21 PM	114.6	112.5	-1.50	-0.70	1.473	0.689			-4.91	-5.06
P-37	9/12/2025 2:35:09 PM	110.7	110.2	-0.73	-0.64	3.749	2.706	3.8	3.2	-5.16	-5.10
P-38RD	9/15/2025 2:12:37 PM	109.3	109.3	-4.16	-4.14	1.361	1.506	14.7	15.5	-5.35	-5.65
P-38RS	9/15/2025 2:10:06 PM	107.9	107.9	-0.93	-0.92	0.599	0.660	9.8	10.3	-5.09	-5.69
P-39	9/15/2025 2:17:59 PM	105.8	105.9	-7.39	-7.27	0.022	0.026	1.0	1.1	-7.76	-7.58
P-41	9/15/2025 2:24:21 PM	109.7	109.7	-3.54	-3.58	0.000	0.000			-7.63	-7.29
P-42R	9/16/2025 11:13:42 AM	117.6	118.1	-5.96	-6.29	1.189	0.584	3.3	2.3	-8.48	-6.52
P-43	9/16/2025 11:07:52 AM	102.8	103.8	-0.39	-0.35	0.383	0.350			-8.24	-8.42
P-44RD	9/16/2025 11:03:01 AM	103.9	103.9	-8.25	-8.29	0.173	0.248	1.3	1.5	-8.43	-8.52
P-44RS	9/16/2025 11:01:00 AM	119.8	119.9	-1.24	-1.24	3.371	3.287	5.6	5.5	-8.40	-8.21
P-45RD	9/16/2025 11:32:08 AM	116.5	116.5	-3.63	-3.62	0.048	0.047	2.7	2.7	-8.43	-8.42
P-45RS	9/16/2025 11:29:26 AM	116.9	116.8	-0.83	-0.70	6.827	1.447	7.9	3.7	-8.31	-8.38
P-46RD	9/18/2025 12:33:45 PM	106.5	106.5	-7.64	-7.66	0.045	0.047	2.7	2.7	-7.69	-7.73
P-46RS	9/18/2025 12:31:10 PM	122.1	122.3	-2.74	-2.77	5.080	5.307	28.0	28.6	-7.99	-8.18
P-47	9/23/2025 10:47:12 AM	127.7	127.7	-3.88	-3.86	3.815	3.806	0.0	0.0		
P-48	9/23/2025 11:09:02 AM	127.0	126.8	-1.02	-0.96	0.063	0.059	0.0	0.0		
P-49RD	9/23/2025 11:21:23 AM	115.4	115.5	-8.83	-8.86	1.066	1.023	13.4	13.1	-10.24	
P-49RS	9/23/2025 11:18:57 AM	115.2	115.2	-4.31	-4.32	4.765	4.900	45.9	46.6	-9.50	
P-52	9/23/2025 1:48:00 PM	118.0	118.0	-0.51	-0.52	-3.739	-3.661	0.0	0.0		
P-53	9/23/2025 1:51:50 PM	116.4	115.1	-1.41	-1.36	1.235	1.233	0.0	0.0		
P-54	9/23/2025 2:00:58 PM	105.2	105.2	-0.60	-0.59	0.475	0.472	0.0	0.0		
P-55	9/23/2025 2:03:19 PM	102.8	102.8	-0.53	-0.53	0.407	0.406	0.0	0.0		
P-56	9/23/2025 2:10:00 PM	96.9	97.0	-0.65	-0.63	0.093	0.088	0.0	0.0		
P-57	9/23/2025 2:07:49 PM	90.0	89.9	-0.63	-0.61	-0.083	-0.075	0.0	0.0	-20.70	
P-60R	9/18/2025 12:57:02 PM	82.2	82.8	-2.76	-3.00	0.003	0.095	0.4	2.2	-4.73	-5.07
P-61	9/18/2025 12:50:37 PM	88.4	88.4	-0.17	-0.19	2.660	2.812	5.1	5.2	-2.92	-3.26
P-65	9/18/2025 12:44:48 PM	83.5	83.7	-0.49	-0.50	0.234	0.245	3.4	3.5	-5.23	-5.70
P-71	9/23/2025 11:29:47 AM	105.5	105.5	-0.80	-0.76	0.588	0.576	0.0	0.0		
P-75	9/23/2025 2:18:03 PM	95.2	95.2	-4.16	-4.19	2.158	1.915	19.6	18.5	-6.37	
P-76	9/23/2025 10:33:21 AM	98.6	98.5	-2.42	-2.41	-2.271	-2.449	0.0	0.0	-5.85	
P-79	9/23/2025 9:43:35 AM	94.3	94.3	-0.42	-0.39	0.319	0.314	0.0	0.0	-11.57	
SC-2000E	9/24/2025 10:46:30 AM	118.1	118.4	-5.23	-5.26	2.175	2.131	10.4	10.2	-9.78	
SC-2501E	9/3/2025 9:30:42 AM	177.6	177.1	-0.29	-0.21	0.158	0.112	26.5	22.3	-2.66	-2.39
SC-2501E	9/3/2025 9:45:00 AM										
SC-2501E	9/3/2025 9:45:00 AM										
SC-2501E	9/5/2025 8:09:33 AM	175.5	175.7	-0.08	-0.08	0.068	0.067	3.1	3.1	-0.62	-0.62
SC-2501E	9/5/2025 8:13:54 AM	185.0	185.3	-0.11	-0.09	0.537	0.582	8.7	9.1	-9.57	-9.59
SC-2501E	9/9/2025 9:14:26 AM	182.0	182.1	-0.39	-0.41	0.182	0.202	28.3	29.8	-9.52	-9.13
SC-2501E	9/9/2025 9:15:00 AM										
SC-2501E	9/15/2025 9:20:39 AM	180.4	181.4	-0.43	-0.43	0.175	0.252	5.0	6.0	-10.33	-10.68
SC-2501E	9/15/2025 9:22:00 AM										

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
SC-2501E	9/15/2025 9:22:26 AM	182.2	181.8	-0.55	-0.54	0.119	0.111	4.1	4.0	-10.54	-10.51
SC-2501E	9/22/2025 8:49:03 AM	169.5	168.9	-0.33	-0.31	0.033	0.038	2.2	2.3	-13.16	-13.29
SC-2501E	9/29/2025 11:44:34 AM	169.7	170.9	-0.17	-0.17	0.075	0.101	3.3	3.8	-10.03	-10.05
SC-2501W	9/3/2025 9:44:19 AM	185.9	185.8	-1.19	-0.91	0.635	0.381	9.5	7.3	-8.05	-8.04
SC-2501W	9/3/2025 9:45:00 AM										
SC-2501W	9/3/2025 9:45:00 AM										
SC-2501W	9/9/2025 9:40:33 AM	184.0	184.0	-0.12	-0.10	0.538	0.253	8.7	6.0	-9.02	-8.93
SC-2501W	9/9/2025 9:42:00 AM										
SC-2501W	9/15/2025 10:06:49 AM	182.5	182.5	-0.93	-0.92	0.000	0.039			-12.53	-12.83
SC-2501W	9/15/2025 10:08:00 AM										
SC-2501W	9/22/2025 9:20:28 AM	180.3	180.1	-0.30	-0.30	0.000	0.000			-12.02	-11.89
SC-2501W	9/29/2025 2:05:42 PM	182.6	182.9	-0.11	-0.12	0.000	0.000			-9.46	-9.53
SW-10	9/25/2025 1:59:04 PM	93.1	94.2	-3.05	-3.07	0.057	0.000			-3.09	-3.05
SW-115	9/15/2025 1:25:47 PM	102.3	102.3	-7.07	-7.07	0.929	0.926	12.2	12.1	0.00	0.04
SW-1445	9/4/2025 9:57:23 AM	96.9	97.2	-3.37	-3.16	0.020	0.041	4.0	5.7	-3.22	-3.16
SW-1445	9/19/2025 10:26:13 AM	90.3	90.5	-2.77	-2.80	0.008	0.003	2.5	1.6	-2.56	-2.59
SW-1455	9/4/2025 9:51:46 AM	96.1	96.3	-3.29	-3.33	0.130	0.055	10.2	6.6	-2.96	-3.04
SW-1455	9/19/2025 10:22:21 AM	89.4	89.4	-3.82	-3.78	0.049	0.035	6.3	5.3	-3.56	-3.39
SW-154	9/17/2025 1:54:35 PM	116.3	116.6	-5.40	-5.37	5.442	5.415			-5.40	-5.50
SW-17-135	9/4/2025 9:54:36 AM	95.5	96.0	-3.47	-3.46	0.053	0.049	6.5	6.2	-3.22	-3.19
SW-17-135	9/19/2025 10:24:22 AM	81.8	81.9	-3.86	-3.71	0.189	0.102	12.4	9.2	-3.44	-3.39
SW-187	9/2/2025 1:15:10 PM	107.1	107.3	-3.36	-3.38	0.008	0.017	5.6	8.5	-3.40	-3.40
SW-187	9/25/2025 1:44:17 PM	92.8	91.5	-2.66	-2.66	0.005	0.006	4.8	4.9	-2.57	-2.56
SW-1930	9/4/2025 8:26:54 AM	86.1	86.7	-2.82	-2.89	0.010	0.026	2.9	4.6	-2.58	-2.70
SW-1930	9/19/2025 9:10:49 AM	81.4	81.5	-3.50	-3.50	0.188	0.171	12.4	11.8	-3.18	-3.20
SW-20	9/23/2025 2:29:32 PM	97.1	97.0	-6.25	-6.24	-0.058	-0.059	0.0	0.0	-20.68	
SW-25	9/4/2025 8:21:56 AM	79.9	79.9	-3.67	-3.65	0.034	0.013	5.3	3.3	-3.19	-3.25
SW-25	9/19/2025 9:15:05 AM	76.0	76.1	-3.77	-3.79	0.121	0.080	10.0	8.1	-3.58	-3.68
SW-30	9/4/2025 9:05:50 AM	94.9	95.3	-3.39	-3.39	0.104	0.104	9.1	9.1	-3.16	-3.16
SW-30	9/19/2025 9:57:49 AM	82.5	82.7	-4.12	-4.17	0.127	0.127	10.2	10.2	-3.77	-3.82
SW-32	9/4/2025 9:13:29 AM	91.5	90.1	-3.45	-3.48	3.483	3.477			-3.21	-3.23
SW-32	9/19/2025 10:01:56 AM	77.9	78.4	-3.96	-3.99	4.116	4.142			-3.85	-3.88
SW-64	9/4/2025 9:03:50 AM	95.2	96.1	-3.33	-3.29	0.023	0.018	4.3	3.7	-3.02	-3.16
SW-64	9/19/2025 9:55:17 AM	82.7	82.8	-4.02	-4.06	0.182	0.164	12.2	11.6	-3.57	-3.60
SW-65	9/15/2025 1:24:13 PM	100.6	100.9	-9.73	-9.73	0.053	0.057	2.9	3.0	-13.60	-13.86
SW-66	9/17/2025 1:51:53 PM	88.1	87.8	-5.55	-5.45	5.424	5.424			-5.50	-5.50
SW-68	9/4/2025 9:11:40 AM	94.6	96.9	-3.16	-3.18	0.009	0.021	2.7	4.1	-2.93	-3.32
SW-68	9/19/2025 10:00:00 AM	84.3	84.5	-3.99	-4.00	0.060	0.070	7.0	7.5	-4.12	-4.04

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
SW-7	9/4/2025 8:23:54 AM	84.2	84.4	-3.39	-3.36	0.013	0.010	3.3	2.9	-3.34	-3.29
SW-7	9/19/2025 9:13:16 AM	78.9	79.5	-3.86	-3.87	0.001	0.008	1.0	2.5	-3.72	-3.72
SW-70	9/2/2025 1:18:04 PM	98.6	98.4	-3.10	-3.42	0.262	0.022	33.1	9.6	-3.25	-3.36
SW-70	9/25/2025 1:47:35 PM	89.5	89.6	-2.76	-2.82	0.021	0.012	9.5	7.2	-2.76	-2.76
SW-71	9/10/2025 1:36:10 PM	84.6	84.4	-1.75	-1.73	0.025	0.020	0.5	0.4	-8.82	-8.61
SW-72	9/12/2025 2:04:39 PM	96.8	96.5	-3.24	-3.24	0.000	0.000			-5.23	-5.19
SW-80	9/17/2025 10:58:29 AM	109.6	109.8	-4.48	-4.48	0.025	0.025	2.0	2.0	-6.33	-6.33
SW-9	9/2/2025 1:20:48 PM	102.2	102.3	-3.27	-3.26	0.014	0.005	7.7	4.3	-3.32	-3.29
SW-9	9/25/2025 1:51:45 PM	89.2	89.2	-3.59	-3.59	0.002	0.002	2.5	3.1	-3.50	-3.49
TC-1961C	9/10/2025 11:16:06 AM	100.4	100.6	-1.00	-1.00	0.007	0.009	2.4	2.7	-13.73	-13.74
TC-1961E	9/4/2025 2:56:15 PM	124.9	124.9	-0.97	-0.99	0.266	0.078	10.6	5.8	-10.23	-10.21
TC-2174	9/3/2025 9:13:40 AM	185.5	185.5	-1.97	-1.96	2.005	1.960	37.1	36.7	-2.30	-1.99
TC-2174	9/3/2025 9:14:00 AM										
TC-2174	9/3/2025 9:14:00 AM										
TC-2174	9/3/2025 9:14:00 AM										
TC-2174	9/9/2025 8:57:46 AM	185.3	185.3	-2.48	-2.65	7.228	7.312	70.0	70.4	-2.86	-3.05
TC-2174	9/9/2025 9:00:00 AM										
TC-2174	9/15/2025 9:03:55 AM	184.4		-2.95	-2.95	6.491	6.491			-3.37	-3.37
TC-2174	9/15/2025 9:06:00 AM										
TC-2174	9/22/2025 8:32:49 AM	159.1	158.8	-3.25	-3.26	3.193	3.195			0.01	0.03
TC-2174	9/29/2025 11:30:06 AM	183.8	183.8	-3.69	-3.70	3.574	3.585			0.71	0.71
VL-02	9/26/2025 2:03:23 PM	96.1	96.6	-12.75	-12.84	0.040	0.054	5.7	6.6	-12.66	-12.69

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
A-01	9/11/2025 10:42:03 AM	34.4312353	-118.6437717	1167	
A-01	9/15/2025 12:58:22 PM	34.4312235	-118.6437863	1175	Valve Comment:RES SEM;Valve Adjustment:Audible Flow;Well Condition:Fair
A-02	9/11/2025 10:49:23 AM	34.4316195	-118.6433048	1157	
A-03	9/11/2025 10:53:20 AM	34.4320288	-118.6428120	1163	
A-04	9/11/2025 10:55:43 AM	34.4322208	-118.6422233	1177	
A-05	9/15/2025 1:11:50 PM	34.4325020	-118.6416453	1173	Valve Comment:RES SEM;Valve Adjustment:Audible Flow;Well Comment:Valve is buried.;Well Condition:Fair
B-01	9/2/2025 1:15:34 PM	34.4338522	-118.6396210	1241	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
B-02R	9/2/2025 1:20:45 PM	34.4335805	-118.6394897	1247	Valve Adjustment:Barely Open
B-03R	9/2/2025 1:33:42 PM	34.4337972	-118.6388362	1243	Valve Adjustment:Barely Open
B-05	9/2/2025 2:00:24 PM	34.4336108	-118.6382412	1235	Valve Adjustment:Barely Open
B-06	9/2/2025 2:11:06 PM	34.4339803	-118.6377483	1221	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open
B-06	9/2/2025 2:11:59 PM	34.4339833	-118.6377308	1227	Valve Adjustment:NSPS/EG CAC
B-07R	9/8/2025 1:40:51 PM	34.4342745	-118.6374367	1212	Valve Adjustment:Barely Open
B-08	9/2/2025 2:26:34 PM	34.4337810	-118.6373452	1225	Valve Adjustment:Barely Open
B-09	9/8/2025 1:35:36 PM	34.4342033	-118.6370542	1214	Valve Adjustment:Barely Open
B-10	9/2/2025 2:32:34 PM	34.4340083	-118.6365475	1224	Valve Adjustment:Decreased Flow/Vacuum
B-11	9/8/2025 1:56:06 PM	34.4348163	-118.6369000	1151	Valve Adjustment:Barely Open
B-12	9/2/2025 1:41:34 PM	34.4340402	-118.6385342	1228	Valve Adjustment:Barely Open
B-13	9/8/2025 1:45:02 PM	34.4344417	-118.6379283	1216	Valve Adjustment:Barely Open
B-14	9/8/2025 2:00:18 PM	34.4349145	-118.6370707	1150	Valve Adjustment:Barely Open
C-03	9/11/2025 10:44:49 AM	34.4313855	-118.6435373	1173	
C-07	9/26/2025 1:08:23 PM	34.4326483	-118.6414573	1194	
C-08	9/25/2025 2:18:07 PM	34.4336628	-118.6408772	1210	
C-10	9/15/2025 1:20:04 PM	34.4347358	-118.6411945	1190	Valve Comment:RES SEM;Valve Adjustment:Audible Flow;Well Condition:Fair
C-11	9/15/2025 1:34:37 PM	34.4352633	-118.6413230	1205	Valve Comment:RES SEM;Valve Adjustment:Audible Flow;Well Condition:Fair
C-12	9/10/2025 10:18:50 AM	34.4359692	-118.6408903	1238	Valve Adjustment:Audible Flow
C-12	9/15/2025 1:42:47 PM	34.4359925	-118.6409055	1207	Valve Comment:RES SEM;Valve Adjustment:Audible Flow;Well Condition:Fair
C-15	9/10/2025 10:26:52 AM	34.4362368	-118.6410673	1234	Valve Adjustment:Audible Flow
C-15	9/15/2025 1:46:38 PM	34.4362652	-118.6410660	1211	Valve Comment:RES SEM;Valve Adjustment:Audible Flow;Well Condition:Fair;Well Repairs:Valve
C-17B	9/22/2025 11:09:30 AM	34.4373605	-118.6419240	1212	Valve Adjustment:Audible Flow
C-18	9/25/2025 2:18:43 PM	34.4379687	-118.6426040	1239	Valve Adjustment:Audible Flow
C-19	9/22/2025 11:23:57 AM	34.4375860	-118.6421525	1212	Valve Adjustment:Audible Flow
C-20	9/25/2025 2:27:31 PM	34.4377662	-118.6423810	1222	Valve Adjustment:Audible Flow
C-23	9/25/2025 2:22:36 PM	34.4379497	-118.6425987	1228	Valve Adjustment:Audible Flow
C-24	9/22/2025 11:21:21 AM	34.4375292	-118.6421100	1212	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
C-25	9/15/2025 2:05:56 PM	34.4371060	-118.6416657	1208	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum;Well Condition:Fair
C-26	9/15/2025 1:59:34 PM	34.4366535	-118.6412925	1205	
C-27	9/10/2025 10:22:35 AM	34.4361560	-118.6409883	1240	Valve Adjustment:Audible Flow
C-28	9/15/2025 1:37:08 PM	34.4354447	-118.6413947	1215	Valve Adjustment:Audible Flow;Well Condition:Fair
C-29	9/15/2025 1:27:37 PM	34.4348458	-118.6412453	1211	Valve Adjustment:Audible Flow;Well Condition:Fair
C-30	9/25/2025 2:14:01 PM	34.4342463	-118.6412610	1260	
CV-02	9/11/2025 10:16:16 AM	34.4335022	-118.6414362	1170	
CV-02	9/11/2025 10:17:03 AM	34.4335763	-118.6413777	1231	
CV-03	9/11/2025 10:13:17 AM	34.4333438	-118.6414408	1233	
CV-04	9/11/2025 10:09:39 AM	34.4331692	-118.6416388	1226	
CV-05	9/11/2025 10:06:21 AM	34.4328357	-118.6422060	1228	
CV-06	9/11/2025 11:02:54 AM	34.4326992	-118.6428247	1207	
CV-09	9/11/2025 11:17:07 AM	34.4318528	-118.6442558	1202	Valve Adjustment:Positive Static Press.
CV-108-52	9/2/2025 10:35:26 AM	34.4334238	-118.6506822	1278	Valve Adjustment:Decom Well (Temporary),Audible Flow,Barely Open;Well Condition:Good
CV-108-52	9/10/2025 10:00:00 AM				Air Tech Lab
CV-108-52	9/10/2025 10:00:00 AM				Air Tech Lab; [User entered 2.1%]
CV-108-52	9/17/2025 8:58:55 AM	34.4334038	-118.6506762	1282	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum,Barely Open;Well Condition:Good
CV-113	9/2/2025 9:40:00 AM				Air Tech Lab
CV-113	9/2/2025 9:40:00 AM				Air Tech Lab; [User entered 0%]
CV-113	9/3/2025 9:08:14 AM	34.4367255	-118.6476290	1349	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-113	9/3/2025 9:13:00 AM				AtmAA
CV-113	9/3/2025 9:13:00 AM				AtmAA; [User entered 6.65%]
CV-113	9/9/2025 8:53:00 AM				AtmAA
CV-113	9/9/2025 8:54:45 AM	34.4367288	-118.6476260	1344	
CV-113	9/15/2025 8:58:37 AM	34.4367402	-118.6476053	1369	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In)
CV-113	9/15/2025 9:03:00 AM				AtmAA
CV-113	9/22/2025 8:29:56 AM	34.4367182	-118.6476217	1341	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-113	9/29/2025 11:25:43 AM	34.4367388	-118.6476295	1349	Valve Adjustment:High Temp,Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-114	9/11/2025 8:55:00 AM				Air Tech Lab
CV-114	9/11/2025 8:55:00 AM				Air Tech Lab; [User entered 13%]
CV-1424	9/3/2025 10:36:01 AM	34.4351570	-118.6450677	1391	Valve Adjustment:Decreased Flow/Vacuum
CV-1532A	9/4/2025 9:18:52 AM	34.4338982	-118.6508118	1275	Valve Adjustment:No Flow Measurement,High Temp
CV-1532A	9/4/2025 9:20:00 AM				AtmAA
CV-1532A	9/4/2025 9:20:00 AM				AtmAA; [User entered 9.36%]

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-1532A	9/10/2025 10:10:00 AM				Air Tech Lab
CV-1532A	9/10/2025 10:10:00 AM				Air Tech Lab; [User entered 2.1%]
CV-1532A	9/10/2025 11:02:22 AM	34.4338933	-118.6508170	1260	High Temp,,
CV-1532A	9/10/2025 11:04:00 AM				AtmAA
CV-1532A	9/12/2025 2:19:15 PM	34.4338672	-118.6508157	1298	Valve Adjustment:No Flow Measurement,High Temp
CV-1532A	9/18/2025 10:36:35 AM	34.4338638	-118.6508057	1283	Valve Adjustment:No Flow Measurement,High Temp
CV-1532A	9/24/2025 9:41:10 AM	34.4338598	-118.6508178	1294	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-1534A-PLR	9/5/2025 7:38:51 AM	34.4336577	-118.6507987	1282	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:ACTIVE PLR
CV-1534A-PLR	9/5/2025 7:40:00 AM				AtmAA
CV-1534A-PLR	9/5/2025 7:40:00 AM				AtmAA; [User entered 14.10%]
CV-1534A-PLR	9/10/2025 11:21:04 AM	34.4336183	-118.6508300	1293	No Flow Measurement,High Temp,High O2,Positive Static Press.,No Adjustment Made,,,
CV-1534A-PLR	9/10/2025 11:22:00 AM				AtmAA
CV-1534A-PLR	9/18/2025 9:25:06 AM	34.4336248	-118.6507915	1294	Valve Adjustment:No Flow Measurement,High Temp
CV-1534A-PLR	9/24/2025 9:23:39 AM	34.4336510	-118.6508028	1298	Valve Adjustment:No Flow Measurement,High Temp,High O2,Valve 100% Open,Surging Liquid in Well (Watered In);Well Comment:ACTIVE PLR
CV-1535	9/2/2025 10:32:14 AM	34.4333323	-118.6503280	1331	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Good
CV-1535	9/9/2025 9:00:00 AM				Air Tech Lab
CV-1535	9/9/2025 9:00:00 AM				Air Tech Lab; [User entered 2.5%]
CV-1535	9/17/2025 8:55:16 AM	34.4333123	-118.6503497	1320	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum,Barely Open;Well Condition:Good
CV-1601D	9/4/2025 9:21:21 AM	34.4311747	-118.6486767	1325	,,
CV-1601D	9/17/2025 10:18:46 AM	34.4311007	-118.6486853	1341	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Good
CV-1601S	9/4/2025 9:15:43 AM	34.4311235	-118.6486853	1378	,,
CV-1601S	9/17/2025 10:16:46 AM	34.4311233	-118.6486858	1332	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum,Barely Open;Well Condition:Good
CV-1604	9/10/2025 11:04:29 AM	34.4321578	-118.6450510	1295	
CV-1605	9/5/2025 1:57:42 PM	34.4318490	-118.6459563	1250	,,
CV-1701D	9/4/2025 2:27:54 PM	34.4335943	-118.6433405	1304	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Fair
CV-1701S	9/4/2025 2:25:05 PM	34.4335868	-118.6433325	1299	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Fair
CV-1901	9/9/2025 9:32:11 AM				
CV-1901	9/10/2025 9:59:41 AM	34.4356963	-118.6508112	1347	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-1901	9/17/2025 8:51:25 AM	34.4356962	-118.6508225	1324	

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-1902A	9/4/2025 8:41:25 AM	34.4346167	-118.6503110	1316	Valve Adjustment:High Temp
CV-1902A	9/4/2025 8:45:00 AM				AtmAA
CV-1902A	9/4/2025 8:45:00 AM				AtmAA; [User entered 14.83%]
CV-1902A	9/9/2025 8:45:00 AM				Air Tech Lab
CV-1902A	9/9/2025 8:45:00 AM				Air Tech Lab; [User entered 20%]
CV-1902A	9/10/2025 10:11:35 AM	34.4345817	-118.6502920	1306	High Temp,No Flow Measurement,
CV-1902A	9/10/2025 10:13:00 AM				AtmAA
CV-1902A	9/18/2025 8:46:48 AM	34.4345902	-118.6503100	1329	Valve Adjustment:No Flow Measurement,High Temp
CV-1902A	9/24/2025 11:10:16 AM	34.4345972	-118.6503235	1305	Valve Adjustment:High Temp
CV-1903	9/5/2025 9:04:43 AM	34.4363737	-118.6503705	1376	
CV-1903	9/9/2025 9:37:05 AM				
CV-1903	9/16/2025 9:01:06 AM	34.4363708	-118.6503787	1371	
CV-1903	9/18/2025 1:34:31 PM	34.4363805	-118.6503832	1373	
CV-1905	9/9/2025 10:52:49 AM	34.4334908	-118.6460048	1396	Valve Adjustment:Increased Flow/Vacuum
CV-2001	9/2/2025 2:14:25 PM	34.4322957	-118.6505598	1258	Valve Adjustment:Decreased Flow/Vacuum,Barely Open;Well Condition:Fair
CV-2001	9/8/2025 9:00:00 AM				Air Tech Lab
CV-2001	9/8/2025 9:00:00 AM				Air Tech Lab; [User entered 2.3%]
CV-2001	9/8/2025 9:26:03 AM	34.4322857	-118.6505590	1264	Valve Adjustment:Orifice Plate Changed (See OP Log);Well Comment:Fastened bolts
CV-2001	9/8/2025 9:33:34 AM	34.4322967	-118.6505955	1267	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum
CV-2001	9/17/2025 10:35:12 AM	34.4322893	-118.6505668	1266	
CV-2002	9/2/2025 2:29:12 PM	34.4328260	-118.6511482	1266	Valve Comment:unable to reach system;Valve Adjustment:Barely Open;Well Condition:Fair
CV-2002	9/4/2025 9:55:00 AM				Air Tech Lab
CV-2002	9/4/2025 9:55:00 AM				Air Tech Lab; [User entered 0.43%]
CV-2002	9/17/2025 10:59:06 AM	34.4328022	-118.6511445	1276	
CV-2002	9/17/2025 11:00:32 AM	34.4327915	-118.6511628	1279	Valve Adjustment:Surging Liquid in Header
CV-2003	9/2/2025 10:42:09 AM	34.4333940	-118.6507380	1304	Valve Adjustment:Barely Open;Well Condition:Good
CV-2003	9/17/2025 9:01:22 AM	34.4334237	-118.6507185	1291	Valve Adjustment:Barely Open;Well Condition:Good
CV-2006	9/4/2025 8:25:11 AM	34.4352228	-118.6506555	1311	Valve Adjustment:High Temp
CV-2006	9/4/2025 8:28:00 AM				AtmAA
CV-2006	9/4/2025 8:28:00 AM				AtmAA; [User entered 12.17%]
CV-2006	9/10/2025 10:29:29 AM	34.4352085	-118.6506772	1329	No Adjustment Made,High Temp,
CV-2006	9/10/2025 10:32:00 AM				AtmAA
CV-2006	9/18/2025 8:04:41 AM	34.4352078	-118.6506712	1326	Valve Adjustment:High Temp
CV-2006	9/24/2025 10:41:53 AM	34.4352023	-118.6506638	1319	Valve Adjustment:High Temp
CV-2007	9/2/2025 1:44:21 PM	34.4361605	-118.6469840	1392	
CV-2007	9/3/2025 9:40:00 AM				Air Tech Lab
CV-2007	9/3/2025 9:40:00 AM				Air Tech Lab; [User entered 0.46%]
CV-2008	9/2/2025 1:51:51 PM	34.4362122	-118.6462428	1389	
CV-2008	9/10/2025 10:51:30 AM	34.4362103	-118.6462588	1387	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Good

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-2008	9/10/2025 10:53:39 AM	34.4362270	-118.6462442	1387	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Decreased Flow/Vacuum,Barely Open;Well Condition:Good
CV-2009	9/2/2025 2:09:17 PM	34.4362615	-118.6452557	1373	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open
CV-2009	9/2/2025 2:10:23 PM	34.4362510	-118.6452562	1373	Valve Adjustment:High Temp
CV-2009A	9/3/2025 9:44:32 AM	34.4359752	-118.6452587	1408	Valve Adjustment:Decreased Flow/Vacuum
CV-2009A	9/9/2025 11:06:16 AM				
CV-2010	9/9/2025 1:47:09 PM	34.4356615	-118.6435763	1367	
CV-2010A	9/9/2025 1:43:50 PM	34.4357275	-118.6436645	1380	Valve Adjustment:High Temp
CV-2010A	9/12/2025 1:41:53 PM	34.4357077	-118.6436750	1384	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Fair
CV-2010A	9/12/2025 1:43:56 PM	34.4357050	-118.6436675	1401	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open;Well Condition:Fair
CV-2011	9/4/2025 2:10:02 PM	34.4341965	-118.6434452	1338	Valve Adjustment:Audible Flow;Well Condition:Good
CV-2011A	9/2/2025 10:00:00 AM				AtmAA
CV-2011A	9/2/2025 10:02:07 AM	34.4345195	-118.6431667	1326	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2011A	9/8/2025 10:08:08 AM	34.4345315	-118.6431770	1339	Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Decreased Flow/Vacuum
CV-2011A	9/8/2025 10:10:00 AM				AtmAA
CV-2011A	9/18/2025 6:45:46 AM	34.4345667	-118.6431773	1334	Valve Adjustment:High Temp
CV-2011A	9/22/2025 1:42:17 PM	34.4345550	-118.6431627	1318	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2011A	9/29/2025 8:15:34 AM	34.4345250	-118.6431835	1337	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2012	9/4/2025 1:45:24 PM	34.4350132	-118.6432997	1339	Valve Adjustment:NSPS/EG CAI,Decreased Flow/Vacuum;Well Condition:Fair
CV-2012	9/4/2025 1:46:31 PM	34.4350058	-118.6433157	1340	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Fair
CV-2201-PLR	9/4/2025 6:42:47 AM	34.4355625	-118.6488475	1366	Valve Adjustment:No Flow Measurement,High Temp
CV-2201-PLR	9/4/2025 6:45:00 AM				AtmAA
CV-2201-PLR	9/4/2025 6:45:00 AM				AtmAA; [User entered 4.93%]
CV-2201-PLR	9/9/2025 10:31:01 AM	34.4355665	-118.6488472	1351	Valve Adjustment:High Temp
CV-2201-PLR	9/9/2025 10:32:00 AM				AtmAA
CV-2201-PLR	9/17/2025 10:57:30 AM	34.4355602	-118.6488332	1361	Valve Adjustment:No Flow Measurement,High Temp
CV-2201-PLR	9/23/2025 9:21:57 AM	34.4355735	-118.6488508	1354	Valve Adjustment:No Flow Measurement,High Temp
CV-2201-PLR	9/30/2025 9:14:55 AM	34.4355750	-118.6488475	1354	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-2204-PLR	9/2/2025 10:54:31 AM	34.4357548	-118.6474585	1367	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-2204-PLR	9/2/2025 10:59:00 AM				AtmAA
CV-2204-PLR	9/2/2025 10:59:00 AM				AtmAA; [User entered 3.75%]

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-2204-PLR	9/8/2025 8:50:08 AM	34.4357807	-118.6474557	1353	Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp;Well Condition:Good
CV-2204-PLR	9/8/2025 8:52:00 AM				AtmAA
CV-2204-PLR	9/15/2025 11:40:53 AM	34.4357710	-118.6474557	1351	Valve Comment:Hero Tox On;Valve Adjustment:No Flow Measurement,High Temp
CV-2204-PLR	9/15/2025 11:42:00 AM				AtmAA
CV-2204-PLR	9/22/2025 11:03:04 AM	34.4358072	-118.6474453	1366	Valve Adjustment:High Temp
CV-2204-PLR	9/29/2025 9:52:43 AM	34.4357605	-118.6474793	1365	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Surging Liquid in Well (Watered In)
CV-2205	9/9/2025 2:06:11 PM	34.4342410	-118.6440943	1385	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-2206-PLR	9/10/2025 9:20:31 AM	34.4360612	-118.6483958	1363	Valve Adjustment:High O2,Surging Liquid in Well (Watered In)
CV-2206-PLR	9/10/2025 9:21:33 AM	34.4360613	-118.6483830	1356	Valve Adjustment:High O2,Surging Liquid in Well (Watered In)
CV-2206-PLR	9/23/2025 9:31:55 AM	34.4360653	-118.6483885	1359	Valve Adjustment:High O2,Surging Liquid in Well (Watered In);Well Comment:Hard pipped
CV-2207	9/3/2025 9:55:10 AM	34.4359730	-118.6442045	1417	Valve Adjustment:Increased Flow/Vacuum
CV-2207	9/9/2025 10:21:32 AM				
CV-2208A	9/2/2025 10:14:04 AM	34.4365295	-118.6449525	1344	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2208A	9/2/2025 10:15:00 AM				AtmAA
CV-2208A	9/8/2025 8:21:14 AM	34.4365520	-118.6449485	1344	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Good,Lorentz Pump Installed
CV-2208A	9/8/2025 8:25:00 AM				AtmAA
CV-2208A	9/15/2025 8:11:31 AM	34.4365403	-118.6449492	1348	Valve Adjustment:High Temp
CV-2208A	9/15/2025 8:42:00 AM				AtmAA
CV-2208A	9/22/2025 8:13:27 AM	34.4365362	-118.6449587	1344	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2208A	9/29/2025 8:41:20 AM	34.4365423	-118.6449287	1337	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2301	9/3/2025 9:44:41 AM	34.4335153	-118.6491975	1363	Valve Adjustment:Reconnected this Date,Decreased Flow/Vacuum
CV-2301	9/4/2025 10:47:00 AM	34.4335153	-118.6492060	1355	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2301	9/10/2025 9:20:00 AM				Air Tech Lab
CV-2301	9/10/2025 9:20:00 AM				Air Tech Lab; [User entered 11%]
CV-2301	9/11/2025 10:20:00 AM				AtmAA
CV-2301	9/11/2025 10:21:11 AM	34.4335142	-118.6492240	1352	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp
CV-2301	9/17/2025 9:47:54 AM	34.4334987	-118.6492328	1364	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	9/24/2025 2:06:26 PM	34.4335252	-118.6492333	1362	Valve Adjustment:No Flow Measurement,High Temp
CV-2302	9/3/2025 10:01:02 AM	34.4340585	-118.6491883	1361	Valve Adjustment:Reconnected this Date,Decreased Flow/Vacuum
CV-2302	9/10/2025 9:15:00 AM				Air Tech Lab
CV-2302	9/10/2025 9:15:00 AM				Air Tech Lab; [User entered 1.9%]

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-2302	9/16/2025 2:11:57 PM	34.4340495	-118.6491938	1362	Valve Adjustment:Surging Liquid in Header
CV-2303	9/3/2025 1:59:37 PM	34.4353743	-118.6496810	1326	Valve Adjustment:No Flow Measurement,High Temp
CV-2303	9/3/2025 2:05:00 PM				AtmAA
CV-2303	9/3/2025 2:05:00 PM				AtmAA; [User entered 11.77%]
CV-2303	9/9/2025 1:42:11 PM	34.4353850	-118.6496717	1373	Valve Adjustment:No Flow Measurement,High Temp
CV-2303	9/9/2025 1:43:00 PM				AtmAA
CV-2303	9/11/2025 8:05:00 AM				Air Tech Lab
CV-2303	9/11/2025 8:05:00 AM				Air Tech Lab; [User entered 12%]
CV-2303	9/16/2025 11:08:40 AM	34.4353590	-118.6497037	1354	Valve Adjustment:High Temp
CV-2303	9/16/2025 11:10:00 AM				AtmAA
CV-2303	9/23/2025 9:07:14 AM	34.4354052	-118.6496897	1363	Valve Adjustment:High Temp
CV-2303	9/30/2025 9:44:00 AM	34.4353897	-118.6496917	1351	Valve Adjustment:High Temp
CV-2304	9/8/2025 8:21:49 AM	34.4345780	-118.6487697	1335	Valve Adjustment:High Temp,Positive Static Press.,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2304	9/16/2025 11:05:57 AM	34.4345568	-118.6487480	1330	
CV-2304	9/16/2025 2:04:00 PM				AtmAA
CV-2304	9/23/2025 10:49:37 AM	34.4345670	-118.6487492	1349	Valve Adjustment:High Temp,Positive Static Press.
CV-2305	9/3/2025 10:30:00 AM				Air Tech Lab
CV-2305	9/3/2025 10:30:00 AM				Air Tech Lab; [User entered 5.2%]
CV-2305	9/9/2025 12:59:25 PM	34.4352350	-118.6465163	1411	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum
CV-2305	9/9/2025 1:17:51 PM	34.4352353	-118.6465203	1429	Valve Adjustment:High Temp,Increased Flow/Vacuum
CV-2305	9/26/2025 2:20:50 PM	34.4352325	-118.6465258	1396	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum
CV-2306	9/2/2025 10:51:19 AM	34.4360917	-118.6478087	1363	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-2306	9/2/2025 10:55:00 AM				AtmAA
CV-2306	9/2/2025 10:55:00 AM				AtmAA; [User entered 11.2%]
CV-2306	9/8/2025 8:57:45 AM	34.4360982	-118.6478265	1363	Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Surging Liquid in Header;Well Condition:Good
CV-2306	9/8/2025 8:58:00 AM				AtmAA
CV-2306	9/15/2025 11:35:00 AM				AtmAA
CV-2306	9/15/2025 11:35:10 AM	34.4360902	-118.6478083	1350	Valve Comment:Hero Tox On;Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum,Barely Open
CV-2306	9/22/2025 11:07:37 AM	34.4361047	-118.6477948	1350	Valve Adjustment:High Temp,Valve 100% Open
CV-2306	9/29/2025 10:02:52 AM	34.4360888	-118.6478128	1362	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2308-PLR	9/4/2025 7:55:00 AM				AtmAA
CV-2308-PLR	9/4/2025 7:55:00 AM				AtmAA; [User entered 7.86%]
CV-2308-PLR	9/4/2025 7:56:04 AM	34.4358972	-118.6488985	1357	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-2308-PLR	9/9/2025 10:36:09 AM	34.4358850	-118.6489158	1350	Valve Adjustment:No Flow Measurement,High Temp
CV-2308-PLR	9/9/2025 10:38:00 AM				AtmAA
CV-2308-PLR	9/17/2025 10:54:00 AM	34.4358822	-118.6488880	1356	Valve Adjustment:No Flow Measurement,High Temp
CV-2308-PLR	9/23/2025 9:25:08 AM	34.4359160	-118.6489002	1353	Valve Adjustment:No Flow Measurement,High Temp
CV-2308-PLR	9/30/2025 9:22:24 AM	34.4358912	-118.6489038	1355	Valve Adjustment:No Flow Measurement,High Temp
CV-2310-PLR	9/4/2025 6:34:32 AM	34.4353290	-118.6491225	1372	Valve Adjustment:No Flow Measurement,High Temp,High O2,Positive Static Press.,Valve 100% Open;Well Comment:Active PLR
CV-2310-PLR	9/4/2025 6:35:00 AM				AtmAA
CV-2310-PLR	9/4/2025 6:35:00 AM				AtmAA; [User entered 0.10%]
CV-2310-PLR	9/9/2025 2:18:16 PM	34.4353133	-118.6490990	1372	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Header;Well Comment:Active plr
CV-2310-PLR	9/9/2025 2:20:00 PM				AtmAA
CV-2310-PLR	9/17/2025 11:14:27 AM	34.4354143	-118.6490390	1351	Valve Adjustment:No Flow Measurement,High Temp
CV-2310-PLR	9/23/2025 9:18:29 AM	34.4354430	-118.6490390	1349	Valve Adjustment:High Temp
CV-2310-PLR	9/30/2025 9:32:33 AM	34.4354433	-118.6490542	1347	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:Active PLR
CV-2311	9/3/2025 10:21:35 AM	34.4363173	-118.6498650	1376	Valve Adjustment:No Flow Measurement,High Temp
CV-2311	9/3/2025 10:22:00 AM				AtmAA
CV-2311	9/3/2025 10:22:00 AM				AtmAA; [User entered 3.32%]
CV-2311	9/8/2025 11:02:28 AM	34.4363353	-118.6498825	1372	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Good
CV-2311	9/8/2025 11:08:00 AM				AtmAA
CV-2311	9/16/2025 9:30:00 AM				AtmAA
CV-2311	9/16/2025 9:33:42 AM	34.4363313	-118.6498743	1379	Valve Comment:Lorentz pump;Valve Adjustment:High Temp;Well Comment:Lorentz pump;Well Condition:Good
CV-2311	9/23/2025 7:59:37 AM	34.4363342	-118.6498702	1366	Valve Adjustment:NSPS/EG CAI,High Temp;Well Comment:no sample ports installed in well;Well Condition:Lorentz Pump Installed
CV-2311	9/30/2025 10:45:24 AM	34.4363435	-118.6498805	1366	Valve Adjustment:No Flow Measurement,High Temp,Reduce Sys. Vac. - Flare Down
CV-2312	9/15/2025 8:00:00 AM				Air Tech Lab
CV-2312	9/15/2025 8:25:00 AM				Air Tech Lab; [User entered 13%]
CV-2312	9/15/2025 9:23:42 AM	34.4342120	-118.6473503	1393	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-2312	9/15/2025 9:31:05 AM	34.4342163	-118.6473637	1387	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum
CV-2312	9/17/2025 8:48:14 AM	34.4342040	-118.6473578	1371	Valve Adjustment:High Temp

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-2312	9/25/2025 10:07:46 AM	34.4342175	-118.6473667	1395	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2312	9/30/2025 1:37:00 PM				
CV-2314	9/11/2025 8:25:00 AM				Air Tech Lab
CV-2314	9/11/2025 8:25:00 AM				Air Tech Lab; [User entered 11%]
CV-2314	9/11/2025 9:43:41 AM	34.4346898	-118.6466887	1404	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2314	9/11/2025 9:45:27 AM	34.4347065	-118.6466963	1404	Valve Adjustment:Orifice Plate Changed (See OP Log),High Temp,Decreased Flow/Vacuum
CV-2314	9/11/2025 9:49:46 AM	34.4346783	-118.6467055	1393	Valve Adjustment:Orifice Plate Changed (See OP Log)
CV-2314	9/11/2025 11:09:14 AM	34.4347038	-118.6466755	1387	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Good
CV-2314	9/11/2025 11:11:40 AM	34.4346930	-118.6467057	1391	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-2314	9/19/2025 11:09:06 AM	34.4346893	-118.6467027	1395	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open;Well Condition:Good
CV-2314	9/19/2025 11:10:00 AM	34.4346992	-118.6467085	1401	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum
CV-2315	9/2/2025 11:00:49 AM	34.4355073	-118.6472077	1398	Valve Adjustment:High Temp,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2315	9/2/2025 11:04:00 AM				AtmAA
CV-2315	9/2/2025 11:04:00 AM				AtmAA; [User entered 5.775%]
CV-2315	9/3/2025 10:40:00 AM				Air Tech Lab
CV-2315	9/3/2025 10:40:00 AM				Air Tech Lab; [User entered 8.2%]
CV-2315	9/10/2025 2:14:09 PM	34.4354968	-118.6471928	1411	High Temp,,
CV-2315	9/10/2025 2:17:00 PM				AtmAA
CV-2315	9/12/2025 1:44:21 PM	34.4354928	-118.6471947	1402	Valve Adjustment:Valve 100% Open
CV-2315	9/17/2025 6:55:43 AM	34.4355115	-118.6472070	1399	Valve Adjustment:High Temp
CV-2315	9/25/2025 9:01:33 AM	34.4355350	-118.6472335	1399	Valve Adjustment:High Temp,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2316	9/2/2025 11:09:20 AM	34.4360257	-118.6463858	1412	Valve Adjustment:High Temp
CV-2316	9/9/2025 10:53:03 AM				
CV-2319	9/2/2025 11:21:07 AM	34.4353008	-118.6458057	1409	Valve Adjustment:High Temp
CV-2319	9/5/2025 1:28:24 PM	34.4353338	-118.6457885	1410	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp;Well Condition:Good,Lorentz Pump Installed
CV-2319	9/5/2025 1:29:22 PM	34.4353353	-118.6457922	1409	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-2321	9/3/2025 11:04:43 AM	34.4346295	-118.6453357	1392	Valve Adjustment:Decreased Flow/Vacuum
CV-2321	9/11/2025 1:20:09 PM	34.4346598	-118.6453733	1389	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open;Well Condition:Good
CV-2321	9/11/2025 1:21:13 PM	34.4346510	-118.6453605	1392	Valve Adjustment:NSPS/EG CAI,High Temp;Well Condition:Good
CV-2322	9/8/2025 2:08:07 PM	34.4352937	-118.6474995	1361	
CV-2322	9/16/2025 1:43:01 PM	34.4352708	-118.6475348	1382	
CV-2324	9/3/2025 10:22:37 AM	34.4345182	-118.6442052	1373	

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-2324	9/9/2025 1:52:48 PM	34.4345167	-118.6442393	1394	Valve Adjustment:Decreased Flow/Vacuum
CV-2326	9/5/2025 9:23:50 AM	34.4361507	-118.6504840	1371	Well Comment:no sample ports on well
CV-2326	9/16/2025 9:11:07 AM	34.4361533	-118.6504788	1378	
CV-2326	9/18/2025 2:23:16 PM	34.4361273	-118.6504692	1366	Valve Adjustment:Audible Flow
CV-2327	9/2/2025 2:48:37 PM	34.4349075	-118.6479272	1357	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2327	9/2/2025 2:55:00 PM				AtmAA
CV-2327	9/2/2025 2:55:00 PM				AtmAA; [User entered 11.75%]
CV-2327	9/9/2025 9:19:28 AM	34.4348848	-118.6479252	1363	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-2327	9/9/2025 9:21:14 AM	34.4348930	-118.6479270	1366	Valve Adjustment:High Temp
CV-2327	9/11/2025 9:26:15 AM	34.4348997	-118.6479227	1363	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-2327	9/11/2025 9:27:00 AM				AtmAA
CV-2327	9/17/2025 8:22:31 AM	34.4348953	-118.6479283	1370	Valve Adjustment:High Temp
CV-2327	9/25/2025 10:26:27 AM	34.4348838	-118.6479300	1370	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2328	9/10/2025 8:55:00 AM				Air Tech Lab
CV-2328	9/10/2025 8:55:00 AM				Air Tech Lab; [User entered 11%]
CV-2328	9/10/2025 1:17:41 PM	34.4343282	-118.6483402	1381	Valve Adjustment:NSPS/EG CAI,Reconnected this Date,High Temp
CV-2328	9/10/2025 1:18:29 PM	34.4343130	-118.6483167	1376	Valve Adjustment:High Temp
CV-2328	9/11/2025 11:03:12 AM	34.4343178	-118.6483283	1362	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2328	9/11/2025 1:30:00 PM				AtmAA
CV-2328	9/17/2025 8:35:20 AM	34.4343270	-118.6483352	1366	Valve Adjustment:High Temp
CV-2328	9/24/2025 2:31:29 PM	34.4343325	-118.6483492	1373	Valve Adjustment:High Temp
CV-2333	9/2/2025 10:10:00 AM				Air Tech Lab
CV-2333	9/2/2025 10:10:00 AM				Air Tech Lab; [User entered 13%]
CV-2333	9/10/2025 8:36:34 AM	34.4365053	-118.6473662	1377	Valve Adjustment:High Temp
CV-2333	9/10/2025 8:37:45 AM	34.4365138	-118.6473837	1385	Valve Adjustment:High Temp
CV-2333	9/30/2025 1:38:09 PM	34.4365332	-118.6473553	1383	
CV-2333	9/30/2025 1:38:52 PM	34.4365282	-118.6473575	1380	
CV-2334	9/2/2025 10:05:00 AM				Air Tech Lab
CV-2334	9/2/2025 10:05:00 AM				Air Tech Lab; [User entered 1.8%]
CV-2334	9/5/2025 2:02:08 PM	34.4367003	-118.6466903	1362	
CV-2334	9/30/2025 12:30:03 PM	34.4367135	-118.6467258	1347	Valve Adjustment:Decreased Flow/Vacuum
CV-2335	9/10/2025 10:08:50 AM	34.4363607	-118.6509520	1351	Valve Adjustment:Decreased Flow/Vacuum
CV-2335	9/17/2025 8:43:46 AM	34.4363662	-118.6509543	1343	
CV-2336	9/10/2025 10:05:30 AM	34.4359565	-118.6508868	1346	
CV-2336	9/17/2025 8:48:03 AM	34.4359830	-118.6508880	1340	
CV-2337	9/9/2025 8:35:00 AM				Air Tech Lab
CV-2337	9/9/2025 8:35:00 AM				Air Tech Lab; [User entered 16%]
CV-2337	9/12/2025 9:00:59 AM	34.4354533	-118.6507488	1338	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open;Well Condition:Good
CV-2337	9/12/2025 9:04:21 AM	34.4354583	-118.6507503	1332	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-2337	9/26/2025 8:16:28 AM	34.4354658	-118.6507672	1337	Valve Adjustment:High Temp

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-2337	9/26/2025 8:17:33 AM	34.4354483	-118.6507650	1349	Valve Adjustment:High Temp
CV-2338	9/4/2025 8:35:16 AM	34.4348577	-118.6504850	1313	Valve Adjustment:No Flow Measurement,High Temp
CV-2338	9/4/2025 8:37:00 AM				AtmAA
CV-2338	9/4/2025 8:37:00 AM				AtmAA; [User entered 11.17%]
CV-2338	9/10/2025 10:18:03 AM	34.4348185	-118.6504560	1325	High Temp,No Flow Measurement,
CV-2338	9/10/2025 10:21:00 AM				AtmAA
CV-2338	9/18/2025 8:33:45 AM	34.4348535	-118.6504952	1328	Valve Adjustment:No Flow Measurement,High Temp
CV-2338	9/24/2025 10:56:05 AM	34.4348555	-118.6504730	1306	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2339	9/8/2025 11:17:21 AM	34.4341833	-118.6502777	1316	High O2,,
CV-2339	9/8/2025 11:20:05 AM	34.4341997	-118.6502868	1207	,,
CV-2339	9/9/2025 11:16:42 AM				
CV-2339	9/23/2025 8:48:34 AM	34.4341967	-118.6502590	1321	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Surging Liquid in Well (Watered In)
CV-2341	9/8/2025 11:25:50 AM	34.4336720	-118.6502585	1394	,,
CV-2341	9/9/2025 8:50:00 AM				Air Tech Lab
CV-2341	9/9/2025 8:50:00 AM				Air Tech Lab; [User entered 17%]
CV-2341	9/16/2025 10:49:48 AM	34.4336245	-118.6501647	1320	Valve Adjustment:Decreased Flow/Vacuum
CV-2342A-PLR	9/4/2025 9:24:20 AM	34.4342363	-118.6508147	1264	Valve Adjustment:No Flow Measurement,High Temp
CV-2342A-PLR	9/4/2025 9:25:00 AM				AtmAA
CV-2342A-PLR	9/4/2025 9:25:00 AM				AtmAA; [User entered 10.20%]
CV-2342A-PLR	9/10/2025 10:55:01 AM	34.4342518	-118.6508448	1257	No Flow Measurement,High Temp,
CV-2342A-PLR	9/10/2025 10:58:00 AM				AtmAA
CV-2342A-PLR	9/12/2025 2:13:51 PM	34.4342038	-118.6508368	1305	Valve Adjustment:High Temp,Valve 100% Open
CV-2342A-PLR	9/18/2025 10:41:09 AM	34.4342280	-118.6508292	1278	Valve Adjustment:No Flow Measurement,High Temp
CV-2342A-PLR	9/24/2025 10:03:10 AM	34.4342200	-118.6508225	1287	Valve Adjustment:High Temp,Valve 100% Open
CV-2343	9/4/2025 9:05:29 AM	34.4332563	-118.6506667	1292	Valve Adjustment:High Temp
CV-2343	9/4/2025 9:25:00 AM				AtmAA
CV-2343	9/4/2025 9:25:00 AM				AtmAA; [User entered 11.06%]
CV-2343	9/10/2025 11:41:53 AM	34.4332422	-118.6506808	1290	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp;Well Condition:Good
CV-2343	9/10/2025 11:42:00 AM				AtmAA
CV-2343	9/12/2025 1:37:54 PM				
CV-2343	9/18/2025 9:11:19 AM	34.4332525	-118.6506862	1299	Valve Adjustment:No Flow Measurement,High Temp
CV-2343	9/24/2025 9:09:31 AM	34.4332473	-118.6506723	1297	Valve Adjustment:No Flow Measurement,High Temp;Well Comment:pump not working upon arrival
CV-2344	9/4/2025 8:56:00 AM				AtmAA
CV-2344	9/4/2025 8:56:00 AM				AtmAA; [User entered 6.68%]
CV-2344	9/4/2025 8:58:42 AM	34.4329947	-118.6504232	1300	Valve Adjustment:High Temp
CV-2344	9/8/2025 9:45:00 AM				Air Tech Lab
CV-2344	9/8/2025 9:45:00 AM				Air Tech Lab; [User entered 9.9%]

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-2344	9/11/2025 1:47:51 PM	34.4329800	-118.6504317	1308	Valve Adjustment:High Temp
CV-2344	9/11/2025 2:20:00 PM				AtmAA
CV-2344	9/17/2025 2:28:09 PM	34.4330033	-118.6504125	1306	Valve Adjustment:High Temp
CV-2344	9/17/2025 2:28:57 PM	34.4329958	-118.6504090	1311	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2344	9/18/2025 2:11:01 PM	34.4329842	-118.6504255	1309	Valve Adjustment:No Flow Measurement,High Temp
CV-2344	9/24/2025 8:57:50 AM	34.4329922	-118.6504243	1303	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2345	9/8/2025 9:31:17 AM	34.4327713	-118.6502167	1306	,,
CV-2345	9/9/2025 9:25:00 AM				Air Tech Lab
CV-2345	9/9/2025 9:25:00 AM				Air Tech Lab; [User entered 3.3%]
CV-2345	9/17/2025 9:11:25 AM	34.4327222	-118.6501778	1314	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2345	9/17/2025 9:12:21 AM	34.4327270	-118.6501790	1314	Valve Adjustment:NSPS/EG CAI,High Temp;Well Condition:Lorentz Pump Installed
CV-2346	9/2/2025 11:03:58 AM	34.4325847	-118.6500545	1324	Valve Adjustment:Audible Flow;Well Condition:Good
CV-2346	9/9/2025 9:20:00 AM				Air Tech Lab
CV-2346	9/9/2025 9:20:00 AM				Air Tech Lab; [User entered 9.5%]
CV-2346	9/17/2025 9:16:34 AM	34.4325933	-118.6500558	1323	Valve Adjustment:Audible Flow;Well Condition:Lorentz Pump Installed
CV-2347	9/2/2025 11:25:43 AM	34.4323460	-118.6498367	1311	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good
CV-2347	9/9/2025 9:15:00 AM				Air Tech Lab
CV-2347	9/9/2025 9:15:00 AM				Air Tech Lab; [User entered 6.8%]
CV-2347	9/17/2025 9:28:38 AM	34.4323557	-118.6498362	1317	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good,Lorentz Pump Installed
CV-2348	9/2/2025 11:32:39 AM	34.4321545	-118.6495912	1326	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Good
CV-2348	9/2/2025 11:33:48 AM	34.4321628	-118.6496090	1318	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Good
CV-2348	9/9/2025 9:10:00 AM				Air Tech Lab
CV-2348	9/9/2025 9:10:00 AM				Air Tech Lab; [User entered 1.9%]
CV-2348	9/17/2025 9:33:34 AM	34.4321698	-118.6496130	1320	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Good,Lorentz Pump Installed
CV-2348	9/17/2025 9:34:01 AM	34.4321612	-118.6496017	1325	Valve Adjustment:NSPS/EG CAI,High Temp;Well Condition:Lorentz Pump Installed
CV-2349	9/4/2025 9:40:00 AM				Air Tech Lab
CV-2349	9/4/2025 9:40:00 AM				Air Tech Lab; [User entered 11%]
CV-2349	9/5/2025 7:49:52 AM	34.4331575	-118.6512348	1264	Valve Adjustment:High Temp
CV-2349	9/5/2025 7:50:00 AM				AtmAA
CV-2349	9/5/2025 7:50:00 AM				AtmAA; [User entered 8.42%]
CV-2349	9/11/2025 1:56:53 PM	34.4331683	-118.6512487	1253	Valve Adjustment:High Temp
CV-2349	9/11/2025 2:00:00 PM				AtmAA
CV-2349	9/18/2025 11:04:29 AM	34.4331585	-118.6512275	1273	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-2349	9/18/2025 2:43:09 PM	34.4331453	-118.6512642	1260	Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header;Well Condition:Fair
CV-2349	9/18/2025 2:44:16 PM	34.4331472	-118.6512678	1266	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-2350	9/2/2025 2:26:16 PM	34.4327553	-118.6508918	1283	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2350	9/8/2025 9:10:00 AM				Air Tech Lab
CV-2350	9/8/2025 9:10:00 AM				Air Tech Lab; [User entered 7.5%]
CV-2350	9/17/2025 10:55:34 AM	34.4327602	-118.6508923	1280	Valve Adjustment:Decreased Flow/Vacuum
CV-2351	9/4/2025 9:00:00 AM				Air Tech Lab
CV-2351	9/4/2025 9:00:00 AM				Air Tech Lab; [User entered 0.28%]
CV-2351	9/10/2025 8:47:36 AM	34.4351440	-118.6511537	1288	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2351	9/17/2025 2:13:22 PM	34.4351363	-118.6511432	1289	Valve Adjustment:High O2,Surging Liquid in Well (Watered In)
CV-2352	9/4/2025 9:28:00 AM				Air Tech Lab
CV-2352	9/4/2025 9:28:00 AM				Air Tech Lab; [User entered 3.0%]
CV-2352	9/5/2025 10:40:34 AM				
CV-2352	9/10/2025 8:58:04 AM	34.4348437	-118.6510073	1300	Valve Adjustment:High O2,Valve 100% Open,Surging Liquid in Well (Watered In);Well Comment:to tall to adjust
CV-2352	9/17/2025 2:17:54 PM	34.4348733	-118.6510332	1292	
CV-2353-PLR	9/4/2025 9:36:47 AM	34.4345262	-118.6509033	1284	Valve Adjustment:No Flow Measurement,High Temp
CV-2353-PLR	9/4/2025 9:40:00 AM				AtmAA
CV-2353-PLR	9/4/2025 9:40:00 AM				AtmAA; [User entered 9.29%]
CV-2353-PLR	9/8/2025 9:35:00 AM				Air Tech Lab
CV-2353-PLR	9/8/2025 9:35:00 AM				Air Tech Lab; [User entered 19%]
CV-2353-PLR	9/10/2025 10:48:50 AM	34.4345193	-118.6509325	1289	No Flow Measurement,High Temp,
CV-2353-PLR	9/10/2025 10:50:00 AM				AtmAA
CV-2353-PLR	9/12/2025 2:09:56 PM	34.4345385	-118.6508985	1298	Valve Adjustment:High Temp
CV-2353-PLR	9/18/2025 10:48:02 AM	34.4345352	-118.6509073	1287	Valve Adjustment:No Flow Measurement,High Temp
CV-2353-PLR	9/24/2025 10:20:25 AM	34.4345493	-118.6509032	1298	Valve Adjustment:No Flow Measurement,High Temp
CV-2354	9/4/2025 9:35:00 AM				Air Tech Lab
CV-2354	9/4/2025 9:35:00 AM				Air Tech Lab; [User entered 12%]
CV-2354	9/8/2025 3:32:46 PM	34.4337037	-118.6513698	1201	,,
CV-2354	9/26/2025 8:52:45 AM	34.4336670	-118.6513487	1269	Valve Adjustment:High O2,Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2354	9/26/2025 8:53:43 AM	34.4336668	-118.6513320	1271	Valve Adjustment:High O2,Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24001	9/4/2025 8:04:16 AM	34.4366450	-118.6509243	1351	
CV-24001	9/16/2025 10:33:58 AM	34.4366215	-118.6509327	1354	

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24002	9/9/2025 10:26:26 AM	34.4367335	-118.6504692	1359	
CV-24002	9/16/2025 10:22:25 AM	34.4367220	-118.6504598	1365	
CV-24003	9/9/2025 10:22:43 AM	34.4368702	-118.6500802	1367	
CV-24003	9/16/2025 9:31:10 AM	34.4368903	-118.6500603	1357	Valve Adjustment:Increased Flow/Vacuum
CV-24004	9/9/2025 10:03:41 AM	34.4370540	-118.6496933	1363	
CV-24004	9/16/2025 9:37:44 AM	34.4370622	-118.6496845	1366	Valve Adjustment:Decreased Flow/Vacuum
CV-24006	9/5/2025 9:08:53 AM	34.4363807	-118.6504520	1380	Valve Adjustment:High Temp
CV-24006	9/5/2025 9:10:33 AM	34.4363805	-118.6504540	1379	
CV-24006	9/16/2025 9:05:01 AM	34.4363690	-118.6504620	1372	
CV-24006	9/18/2025 1:42:35 PM	34.4363423	-118.6504630	1390	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-24006	9/18/2025 1:43:55 PM	34.4363682	-118.6504588	1376	Valve Adjustment:Audible Flow
CV-24007	9/10/2025 10:11:39 AM	34.4365200	-118.6501303	1378	Valve Adjustment:Decreased Flow/Vacuum
CV-24007	9/11/2025 7:45:00 AM				Air Tech Lab
CV-24007	9/11/2025 7:45:00 AM				Air Tech Lab; [User entered 6.5%]
CV-24007	9/16/2025 12:28:29 PM	34.4365280	-118.6501350	1383	
CV-24008	9/10/2025 10:21:55 AM	34.4366600	-118.6497088	1381	Valve Adjustment:Positive Static Press.;Well Comment:Lateral watered In
CV-24008	9/10/2025 10:23:16 AM	34.4366528	-118.6497088	1376	Valve Adjustment:Positive Static Press.
CV-24008	9/16/2025 12:35:36 PM	34.4366807	-118.6497075	1387	Valve Adjustment:Positive Static Press.;Well Comment:Watered in lateral
CV-24008	9/16/2025 12:36:23 PM	34.4366695	-118.6496955	1385	Valve Adjustment:Positive Static Press.
CV-24009	9/2/2025 2:20:10 PM	34.4368790	-118.6493203	1383	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-24009	9/2/2025 2:28:00 PM				AtmAA
CV-24009	9/2/2025 2:28:00 PM				AtmAA; [User entered 7.53%]
CV-24009	9/8/2025 10:47:07 AM	34.4368777	-118.6493480	1389	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Good
CV-24009	9/8/2025 10:50:00 AM				AtmAA
CV-24009	9/16/2025 9:10:00 AM				AtmAA
CV-24009	9/16/2025 9:10:33 AM	34.4368680	-118.6493402	1385	Valve Adjustment:High Temp
CV-24009	9/22/2025 10:49:46 AM	34.4368777	-118.6493357	1365	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-24010	9/9/2025 9:54:20 AM	34.4370682	-118.6489543	1334	
CV-24010	9/16/2025 9:15:19 AM	34.4370890	-118.6489597	1368	
CV-24010	9/16/2025 9:18:31 AM	34.4371045	-118.6489598	1366	Well Comment:Issue with temp probe first read.
CV-24010	9/16/2025 10:56:12 AM				
CV-24011	9/3/2025 1:45:00 PM				AtmAA
CV-24011	9/3/2025 1:45:00 PM				AtmAA; [User entered 10.82%]
CV-24011	9/3/2025 1:45:11 PM	34.4362245	-118.6501812	1388	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24011	9/8/2025 11:10:59 AM	34.4362075	-118.6501863	1378	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Good
CV-24011	9/8/2025 11:13:00 AM				AtmAA
CV-24011	9/16/2025 1:29:16 PM	34.4362035	-118.6502007	1388	Valve Adjustment:High Temp

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24011	9/16/2025 1:33:00 PM				AtmAA
CV-24011	9/23/2025 8:46:19 AM	34.4362022	-118.6501802	1385	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24011	9/30/2025 11:14:08 AM	34.4362198	-118.6501803	1382	Valve Adjustment:High Temp,Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-24012	9/3/2025 10:32:37 AM	34.4361923	-118.6493558	1361	Valve Adjustment:High Temp
CV-24012	9/3/2025 10:35:00 AM				AtmAA
CV-24012	9/3/2025 10:35:00 AM				AtmAA; [User entered 14.56%]
CV-24012	9/9/2025 10:45:52 AM	34.4361732	-118.6493582	1370	Valve Adjustment:No Flow Measurement,High Temp
CV-24012	9/9/2025 10:48:00 AM				AtmAA
CV-24012	9/16/2025 9:44:30 AM	34.4361945	-118.6493482	1368	Valve Adjustment:High Temp
CV-24012	9/16/2025 9:48:00 AM				AtmAA
CV-24012	9/23/2025 8:08:57 AM	34.4361770	-118.6493518	1380	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-24012	9/30/2025 11:07:38 AM	34.4361867	-118.6493498	1373	Valve Adjustment:NSPS/EG CAI,High Temp,Reduce Sys. Vac. - Flare Down;Well Condition:Pnumatic Pump Installed
CV-24013	9/4/2025 10:09:59 AM	34.4366115	-118.6492410	1367	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Surging Liquid in Well (Watered In)
CV-24013	9/4/2025 10:11:31 AM	34.4366330	-118.6492465	1366	Valve Adjustment:High O2,Surging Liquid in Well (Watered In)
CV-24014	9/2/2025 2:14:50 PM	34.4367943	-118.6489267	1379	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-24014	9/2/2025 2:23:00 PM				AtmAA
CV-24014	9/2/2025 2:23:00 PM				AtmAA; [User entered 17.63%]
CV-24014	9/8/2025 10:40:40 AM	34.4367903	-118.6489560	1388	Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Decreased Flow/Vacuum;Well Condition:Good
CV-24014	9/8/2025 10:41:40 AM	34.4367953	-118.6489545	1379	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open;Well Condition:Good
CV-24014	9/8/2025 10:44:00 AM				AtmAA
CV-24014	9/15/2025 10:57:09 AM	34.4367860	-118.6489293	1375	Valve Adjustment:High Temp
CV-24014	9/15/2025 11:00:00 AM				AtmAA
CV-24014	9/22/2025 10:38:26 AM	34.4367847	-118.6489177	1354	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-24014	9/29/2025 2:31:43 PM	34.4367928	-118.6489150	1349	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-24015	9/3/2025 9:49:26 AM	34.4368410	-118.6486182	1344	Valve Adjustment:High Temp
CV-24015	9/3/2025 9:55:00 AM				AtmAA
CV-24015	9/3/2025 9:55:00 AM				AtmAA; [User entered 13.74%]
CV-24015	9/5/2025 8:17:48 AM	34.4368860	-118.6486135	1344	Valve Adjustment:High Temp;Well Comment:Overpulling well to tall to tune and is at a slope
CV-24015	9/9/2025 9:33:21 AM	34.4368433	-118.6486422	1343	Valve Adjustment:No Flow Measurement,High Temp
CV-24015	9/9/2025 9:34:00 AM				AtmAA
CV-24015	9/15/2025 10:00:29 AM	34.4368883	-118.6486207	1357	Valve Comment:Hero tox was on at this time;Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24015	9/15/2025 10:05:00 AM				AtmAA

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24015	9/16/2025 11:15:52 AM				
CV-24015	9/22/2025 9:06:44 AM	34.4368740	-118.6485953	1367	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24015	9/29/2025 1:59:42 PM	34.4368470	-118.6486087	1339	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24016	9/3/2025 1:49:15 PM	34.4359237	-118.6502728	1374	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24016	9/3/2025 1:54:00 PM				AtmAA
CV-24016	9/3/2025 1:54:00 PM				AtmAA; [User entered 7.13%]
CV-24016	9/8/2025 11:14:40 AM	34.4359248	-118.6502622	1369	Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Decreased Flow/Vacuum;Well Condition:Good
CV-24016	9/8/2025 11:18:00 AM				AtmAA
CV-24016	9/16/2025 10:07:50 AM	34.4358997	-118.6502508	1367	Valve Adjustment:High Temp
CV-24016	9/16/2025 10:10:00 AM				AtmAA
CV-24016	9/23/2025 8:40:55 AM	34.4359205	-118.6502617	1386	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24016	9/30/2025 11:22:26 AM	34.4359393	-118.6502438	1383	Valve Adjustment:NSPS/EG CAI,High Temp,Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-24017	9/3/2025 10:38:48 AM	34.4361185	-118.6498027	1363	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24017	9/3/2025 10:40:00 AM				AtmAA
CV-24017	9/3/2025 10:40:00 AM				AtmAA; [User entered 12.35%]
CV-24017	9/9/2025 10:59:21 AM	34.4361045	-118.6498030	1373	Valve Adjustment:No Flow Measurement,High Temp
CV-24017	9/9/2025 11:00:00 AM				AtmAA
CV-24017	9/11/2025 7:50:00 AM				Air Tech Lab
CV-24017	9/11/2025 7:50:00 AM				Air Tech Lab; [User entered 6.5%]
CV-24017	9/16/2025 9:51:04 AM	34.4361462	-118.6497985	1371	Valve Adjustment:High Temp
CV-24017	9/16/2025 9:52:00 AM				AtmAA
CV-24017	9/23/2025 8:18:33 AM	34.4361123	-118.6498102	1366	Valve Adjustment:NSPS/EG CAI,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	9/30/2025 10:51:29 AM	34.4361423	-118.6498052	1359	Valve Adjustment:High Temp,Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-24018	9/5/2025 10:24:23 AM	34.4355977	-118.6500685	1375	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24018	9/16/2025 9:19:19 AM	34.4356085	-118.6500735	1370	
CV-24019	9/3/2025 10:57:10 AM	34.4357965	-118.6497380	1348	Valve Adjustment:High Temp
CV-24019	9/3/2025 10:58:00 AM				AtmAA
CV-24019	9/3/2025 10:58:00 AM				AtmAA; [User entered 15.37%]
CV-24019	9/9/2025 11:04:11 AM	34.4357885	-118.6497582	1378	Valve Adjustment:No Flow Measurement,High Temp
CV-24019	9/9/2025 11:05:00 AM				AtmAA
CV-24019	9/16/2025 10:00:31 AM	34.4358105	-118.6497582	1368	Valve Adjustment:High Temp
CV-24019	9/16/2025 10:02:00 AM				AtmAA
CV-24019	9/23/2025 8:27:43 AM	34.4357867	-118.6497532	1378	Valve Adjustment:NSPS/EG CAI,High Temp;Well Condition:Poor

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24020	9/10/2025 9:44:19 AM	34.4360052	-118.6493482	1356	Valve Adjustment:NSPS/EG CAI,High O2,Positive Static Press.,Increased Flow/Vacuum,Barely Open
CV-24020	9/10/2025 9:48:04 AM	34.4360073	-118.6493540	1368	Valve Adjustment:NSPS/EG CAC,Barely Open,Surging Liquid in Well (Watered In);Well Comment:no pump installed
CV-24020	9/12/2025 9:47:03 AM	34.4360030	-118.6493478	1361	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Barely Open;Well Comment:Orbinox valve closed Knife Valve;Well Condition:Good
CV-24020	9/23/2025 9:39:18 AM	34.4360285	-118.6493693	1350	Valve Adjustment:Decreased Flow/Vacuum
CV-24021	9/10/2025 9:38:22 AM	34.4361443	-118.6490553	1353	Valve Adjustment:High O2,Surging Liquid in Well (Watered In);Well Comment:Pump disconnected for maintenance
CV-24021	9/10/2025 9:39:32 AM	34.4361417	-118.6490473	1350	Valve Adjustment:High O2,Surging Liquid in Well (Watered In)
CV-24021	9/16/2025 2:10:21 PM	34.4361615	-118.6490482	1373	Valve Adjustment:High O2,Decreased Flow/Vacuum
CV-24022-PLR	9/2/2025 2:07:56 PM	34.4364962	-118.6487802	1367	Valve Adjustment:No Flow Measurement,High Temp
CV-24022-PLR	9/2/2025 2:18:00 PM				AtmAA
CV-24022-PLR	9/3/2025 2:18:00 PM				AtmAA; [User entered 13.14%]
CV-24022-PLR	9/8/2025 10:35:45 AM	34.4365375	-118.6488058	1365	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header;Well Condition:Fair
CV-24022-PLR	9/8/2025 10:38:00 AM				AtmAA
CV-24022-PLR	9/15/2025 11:04:36 AM	34.4365277	-118.6487840	1363	Valve Comment:HERO TOX ON CANT REACH VALVE TO REDUCE TO HIGH;Valve Adjustment:High Temp,Valve 100% Open;Well Comment:Well too high;Well Condition:Poor
CV-24022-PLR	9/15/2025 2:05:40 PM	34.4365268	-118.6488055	1362	Valve Comment:Hero Tox on;Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24022-PLR	9/16/2025 8:54:00 AM				AtmAA
CV-24022-PLR	9/22/2025 10:29:57 AM	34.4365232	-118.6487925	1363	Valve Adjustment:High Temp
CV-24022-PLR	9/29/2025 2:24:05 PM	34.4365347	-118.6487745	1348	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header
CV-24023	9/2/2025 1:57:28 PM	34.4365898	-118.6483952	1371	Valve Adjustment:No Flow Measurement,High Temp
CV-24023	9/2/2025 2:14:00 PM				AtmAA
CV-24023	9/2/2025 2:14:00 PM				AtmAA; [User entered 10.42%]
CV-24023	9/8/2025 10:26:00 AM				AtmAA
CV-24023	9/8/2025 10:26:17 AM	34.4366000	-118.6484288	1371	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Fair
CV-24023	9/9/2025 9:50:00 AM				AtmAA
CV-24023	9/9/2025 9:50:03 AM	34.4365832	-118.6484288	1373	Valve Adjustment:No Flow Measurement,High Temp,Barely Open

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24023	9/15/2025 10:13:46 AM	34.4365863	-118.6484177	1363	Valve Comment:HERO TOX ON;Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-24023	9/15/2025 10:15:00 AM				AtmAA
CV-24023	9/22/2025 9:29:28 AM	34.4365727	-118.6484328	1374	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum
CV-24023	9/29/2025 2:11:07 PM	34.4365797	-118.6484242	1348	Valve Adjustment:No Flow Measurement,High Temp
CV-24024-PLR	9/3/2025 9:38:14 AM	34.4368173	-118.6481227	1349	Valve Adjustment:No Flow Measurement,High Temp
CV-24024-PLR	9/3/2025 9:40:00 AM				AtmAA
CV-24024-PLR	9/3/2025 9:40:00 AM				AtmAA; [User entered 12.15%]
CV-24024-PLR	9/9/2025 9:22:16 AM	34.4368148	-118.6481398	1354	Valve Adjustment:High Temp
CV-24024-PLR	9/9/2025 9:24:00 AM				AtmAA
CV-24024-PLR	9/15/2025 9:28:10 AM	34.4368053	-118.6481405	1351	Valve Adjustment:No Flow Measurement,High Temp
CV-24024-PLR	9/15/2025 9:30:00 AM				AtmAA
CV-24024-PLR	9/22/2025 8:56:46 AM	34.4367905	-118.6481320	1361	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24024-PLR	9/29/2025 1:45:31 PM	34.4368158	-118.6481532	1338	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24025	9/3/2025 1:56:13 PM	34.4352890	-118.6499140	1338	Valve Adjustment:No Flow Measurement,High Temp
CV-24025	9/3/2025 2:00:00 PM				AtmAA
CV-24025	9/3/2025 2:00:00 PM				AtmAA; [User entered 5.82%]
CV-24025	9/9/2025 1:37:04 PM	34.4353040	-118.6499258	1373	Valve Adjustment:No Flow Measurement,High Temp
CV-24025	9/9/2025 1:38:00 PM				AtmAA
CV-24025	9/16/2025 10:59:39 AM	34.4352802	-118.6499397	1348	Valve Adjustment:High Temp
CV-24025	9/16/2025 11:00:00 AM				AtmAA
CV-24025	9/23/2025 9:03:55 AM	34.4352983	-118.6499067	1353	Valve Adjustment:No Flow Measurement,High Temp;Well Comment:Unable to adjust valve due to height
CV-24025	9/30/2025 9:51:56 AM	34.4353028	-118.6499265	1354	Valve Adjustment:High Temp,Reduce Sys. Vac. - Flare Down
CV-24026	9/2/2025 2:33:13 PM	34.4356835	-118.6492307	1357	Valve Adjustment:High Temp,High O2
CV-24026	9/2/2025 2:34:10 PM	34.4356842	-118.6492413	1356	Valve Adjustment:High O2
CV-24026	9/3/2025 8:24:30 AM	34.4356528	-118.6492563	1351	Valve Adjustment:No Flow Measurement,High O2,Barely Open
CV-24026	9/3/2025 8:32:39 AM	34.4356607	-118.6492637	1362	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High O2,Barely Open
CV-24026	9/3/2025 9:04:21 AM				
CV-24026	9/8/2025 1:27:07 PM	34.4356427	-118.6492412	1353	Valve Comment:RES SEM;Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good
CV-24026	9/9/2025 11:13:09 AM	34.4356535	-118.6492538	1371	
CV-24026	9/23/2025 9:47:18 AM	34.4356747	-118.6492503	1355	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header
CV-24026	9/23/2025 9:48:10 AM	34.4356892	-118.6492577	1357	Valve Adjustment:High Temp,Surging Liquid in Header
CV-24026	9/25/2025 11:00:40 AM	34.4356840	-118.6492660	1391	NSPS/EG CAI,High Temp,Decreased Flow/Vacuum

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24026	9/25/2025 11:05:05 AM	34.4357037	-118.6492678	1302	NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24027	9/10/2025 9:33:45 AM	34.4361165	-118.6487038	1373	Valve Comment:pump disconnected for maintenance;Valve Adjustment:High O2,Surging Liquid in Well (Watered In)
CV-24027	9/10/2025 9:34:58 AM	34.4361137	-118.6487165	1357	Valve Adjustment:High O2,Surging Liquid in Well (Watered In)
CV-24027	9/16/2025 2:04:15 PM	34.4361228	-118.6487235	1373	
CV-24028	9/2/2025 2:02:21 PM	34.4363317	-118.6484465	1352	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24028	9/2/2025 2:05:00 PM				AtmAA
CV-24028	9/2/2025 2:05:00 PM				AtmAA; [User entered 16.46%]
CV-24028	9/8/2025 10:30:45 AM	34.4363543	-118.6484798	1363	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header;Well Condition:Fair
CV-24028	9/8/2025 10:32:00 AM				AtmAA
CV-24028	9/15/2025 2:00:13 PM	34.4363492	-118.6484673	1348	Valve Comment:Hero Tox on;Valve Adjustment:No Flow Measurement,High Temp
CV-24028	9/15/2025 2:04:00 PM				AtmAA
CV-24028	9/22/2025 10:24:26 AM	34.4363353	-118.6484668	1358	Valve Adjustment:No Flow Measurement,High Temp
CV-24028	9/29/2025 2:16:54 PM	34.4363315	-118.6484600	1346	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24029	9/5/2025 8:26:17 AM	34.4364718	-118.6480710	1350	Valve Adjustment:Barely Open;Well Comment:valve is damr
CV-24029	9/16/2025 1:28:21 PM				
CV-24029	9/23/2025 10:27:04 AM	34.4364705	-118.6480572	1351	Valve Adjustment:High O2,Barely Open;Well Comment:valve might be damaged;Well Condition:Fair
CV-24029	9/23/2025 10:28:20 AM	34.4364725	-118.6480567	1354	Valve Adjustment:High O2,Barely Open
CV-24030	9/3/2025 9:18:20 AM	34.4366488	-118.6478773	1339	Valve Adjustment:No Flow Measurement,High Temp
CV-24030	9/3/2025 9:20:00 AM				AtmAA
CV-24030	9/3/2025 9:20:00 AM				AtmAA; [User entered 13.51%]
CV-24030	9/9/2025 9:07:55 AM	34.4366375	-118.6478770	1346	Valve Adjustment:No Flow Measurement,High Temp
CV-24030	9/9/2025 9:10:00 AM				AtmAA
CV-24030	9/11/2025 9:10:00 AM				AtmAA
CV-24030	9/15/2025 9:09:04 AM	34.4366467	-118.6478618	1365	Valve Adjustment:No Flow Measurement,High Temp
CV-24030	9/22/2025 8:38:56 AM	34.4366583	-118.6478820	1349	Valve Adjustment:No Flow Measurement,High Temp
CV-24030	9/29/2025 11:36:38 AM	34.4366307	-118.6478905	1351	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24031	9/5/2025 10:38:27 AM	34.4348642	-118.6498175	1358	
CV-24031	9/16/2025 9:23:45 AM	34.4348850	-118.6498135	1352	
CV-24031	9/16/2025 2:06:59 PM				
CV-24032	9/3/2025 2:07:25 PM	34.4351305	-118.6496060	1333	Valve Adjustment:No Flow Measurement,High Temp
CV-24032	9/3/2025 2:12:00 PM				AtmAA
CV-24032	9/3/2025 2:12:00 PM				AtmAA; [User entered 12.13%]

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24032	9/9/2025 1:50:39 PM	34.4350995	-118.6495898	1363	Valve Adjustment:No Flow Measurement,High Temp
CV-24032	9/9/2025 1:52:00 PM				AtmAA
CV-24032	9/16/2025 11:20:08 AM	34.4351093	-118.6496417	1353	Valve Adjustment:High Temp
CV-24032	9/16/2025 11:25:00 AM				AtmAA
CV-24032	9/23/2025 9:59:19 AM	34.4351138	-118.6496120	1369	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24032	9/30/2025 1:52:28 PM	34.4351322	-118.6495930	1349	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24033	9/3/2025 2:02:43 PM	34.4353335	-118.6494530	1329	Valve Adjustment:No Flow Measurement,High Temp
CV-24033	9/3/2025 2:09:00 PM				AtmAA
CV-24033	9/3/2025 2:09:00 PM				AtmAA; [User entered 14.93%]
CV-24033	9/9/2025 1:46:18 PM	34.4353392	-118.6494555	1363	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header
CV-24033	9/9/2025 1:48:00 PM				AtmAA
CV-24033	9/16/2025 11:13:45 AM	34.4353222	-118.6494663	1353	Valve Adjustment:High Temp
CV-24033	9/16/2025 11:15:00 AM				AtmAA
CV-24033	9/23/2025 9:14:05 AM	34.4353698	-118.6494555	1355	Valve Adjustment:NSPS/EG CAI,High Temp;Well Condition:Good
CV-24033	9/30/2025 9:38:26 AM	34.4353483	-118.6494725	1344	Valve Adjustment:High Temp,Reduce Sys. Vac. - Flare Down
CV-24034	9/2/2025 10:43:35 AM	34.4360915	-118.6481237	1360	Valve Adjustment:No Flow Measurement,High Temp,High O2,Barely Open;Well Comment:pump not working;Well Condition:Pnumatic Pump Installed
CV-24034	9/2/2025 10:44:22 AM	34.4360960	-118.6481213	1366	Valve Adjustment:No Flow Measurement,High Temp,High O2,Barely Open;Well Condition:Pnumatic Pump Installed
CV-24034	9/2/2025 10:48:00 AM				AtmAA
CV-24034	9/8/2025 9:04:59 AM	34.4361193	-118.6481375	1349	Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Barely Open
CV-24034	9/8/2025 9:07:00 AM				AtmAA
CV-24034	9/8/2025 9:08:20 AM	34.4361273	-118.6481252	1358	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open
CV-24034	9/15/2025 11:19:52 AM	34.4361180	-118.6481157	1347	Valve Comment:Hero Tox on;Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum,Barely Open;Well Condition:Pnumatic Pump Installed
CV-24034	9/15/2025 11:25:00 AM				AtmAA
CV-24034	9/15/2025 11:28:07 AM	34.4360990	-118.6481182	1355	Valve Comment:Hero Tox On for testing;Valve Adjustment:High Temp,High O2,Barely Open
CV-24034	9/16/2025 11:41:28 AM	34.4360913	-118.6481160	1355	Valve Comment:Pump not working well water in;Valve Adjustment:High Temp,High O2
CV-24034	9/22/2025 11:13:29 AM	34.4361162	-118.6480923	1343	Valve Adjustment:No Flow Measurement,High Temp,High O2,Barely Open;Well Comment:pump not active;Well Condition:Pnumatic Pump Installed

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24034	9/29/2025 10:09:45 AM	34.4361010	-118.6481207	1361	Valve Adjustment:No Flow Measurement,High Temp,High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:Pump not working surging liquid in header;Well Condition:Pnumatic Pump Installed
CV-24035	9/2/2025 1:48:03 PM	34.4363772	-118.6476873	1359	Valve Adjustment:No Flow Measurement,High Temp
CV-24035	9/2/2025 2:10:00 PM				AtmAA
CV-24035	9/2/2025 2:10:00 PM				AtmAA; [User entered 16.01%]
CV-24035	9/9/2025 8:39:33 AM	34.4364077	-118.6477048	1356	Valve Adjustment:No Flow Measurement,High Temp
CV-24035	9/9/2025 8:42:00 AM				AtmAA
CV-24035	9/11/2025 8:51:00 AM				AtmAA
CV-24035	9/15/2025 8:51:12 AM	34.4363777	-118.6476967	1366	Valve Adjustment:No Flow Measurement,High Temp
CV-24035	9/22/2025 8:21:28 AM	34.4363720	-118.6477107	1361	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-24035	9/29/2025 11:14:11 AM	34.4363767	-118.6477062	1357	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-24036	9/5/2025 10:47:48 AM	34.4344345	-118.6496995	1353	
CV-24036	9/16/2025 9:26:40 AM	34.4344785	-118.6497053	1346	
CV-24037	9/8/2025 8:39:03 AM	34.4347607	-118.6494505	1334	Valve Adjustment:High Temp
CV-24037	9/8/2025 8:39:31 AM	34.4347595	-118.6494270	1336	
CV-24037	9/16/2025 11:09:08 AM	34.4347365	-118.6494270	1340	Valve Adjustment:High Temp
CV-24037	9/16/2025 1:38:00 PM				AtmAA
CV-24037	9/23/2025 9:47:48 AM	34.4347535	-118.6494328	1351	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24037	9/30/2025 8:36:23 AM	34.4347490	-118.6494260	1342	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24038	9/3/2025 2:18:42 PM	34.4350050	-118.6488827	1337	Valve Adjustment:High Temp,High O2,Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:ACTIVE PLR
CV-24038	9/3/2025 2:22:00 PM				AtmAA
CV-24038	9/3/2025 2:22:00 PM				AtmAA; [User entered 15.45%]
CV-24038	9/3/2025 2:22:02 PM	34.4349997	-118.6488640	1334	Valve Adjustment:High Temp,Valve 100% Open,Surging Liquid in Header
CV-24038	9/9/2025 2:01:00 PM				AtmAA
CV-24038	9/9/2025 2:01:38 PM	34.4350110	-118.6488525	1355	Valve Adjustment:High Temp,Positive Static Press.,Surging Liquid in Header
CV-24038	9/16/2025 1:48:08 PM	34.4350128	-118.6488790	1340	Valve Adjustment:High Temp,Surging Liquid in Header
CV-24038	9/16/2025 1:49:59 PM	34.4350065	-118.6488647	1346	Valve Adjustment:High Temp,Surging Liquid in Header
CV-24038	9/16/2025 1:50:00 PM				AtmAA
CV-24038	9/23/2025 9:38:31 AM	34.4350442	-118.6488633	1337	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24038	9/30/2025 8:49:35 AM	34.4350120	-118.6488607	1337	Valve Adjustment:High Temp,Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed
CV-24039	9/3/2025 2:27:52 PM	34.4352702	-118.6487135	1350	Valve Adjustment:No Flow Measurement,High Temp
CV-24039	9/3/2025 2:28:00 PM				AtmAA
CV-24039	9/3/2025 2:28:00 PM				AtmAA; [User entered 20.01%]
CV-24039	9/9/2025 2:05:13 PM	34.4352887	-118.6486598	1361	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-24039	9/9/2025 2:09:00 PM				AtmAA
CV-24039	9/16/2025 1:53:55 PM	34.4352802	-118.6486780	1355	Valve Adjustment:High Temp
CV-24039	9/16/2025 1:55:00 PM				AtmAA
CV-24039	9/23/2025 9:33:15 AM	34.4353137	-118.6486510	1343	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24039	9/30/2025 9:00:55 AM	34.4352915	-118.6486713	1357	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-24040	9/8/2025 10:13:26 AM	34.4356625	-118.6483903	1354	
CV-24040	9/8/2025 10:16:36 AM	34.4356748	-118.6483818	1362	
CV-24040	9/16/2025 1:19:05 PM	34.4356432	-118.6483898	1352	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24040	9/16/2025 1:19:57 PM	34.4356432	-118.6483817	1356	Valve Adjustment:High Temp
CV-24040	9/16/2025 2:10:00 PM				AtmAA
CV-24040	9/23/2025 10:57:33 AM	34.4356593	-118.6483577	1341	Valve Adjustment:NSPS/EG CAI,High Temp;Well Condition:Lorentz Pump Installed
CV-24041	9/8/2025 10:22:24 AM	34.4358755	-118.6480523	1351	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24041	9/16/2025 1:34:33 PM	34.4358505	-118.6480403	1365	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24041	9/16/2025 1:36:00 PM	34.4358358	-118.6480462	1365	Valve Adjustment:High Temp
CV-24041	9/16/2025 2:16:00 PM				AtmAA
CV-24041	9/23/2025 11:13:01 AM	34.4358738	-118.6480487	1357	Valve Adjustment:High Temp,High O2,Barely Open,Surging Liquid in Well (Watered In)
CV-24041	9/23/2025 11:16:11 AM	34.4358660	-118.6480460	1360	Valve Adjustment:High Temp,High O2,Barely Open,Surging Liquid in Well (Watered In)
CV-24042	9/2/2025 10:31:52 AM	34.4362392	-118.6474452	1378	Valve Adjustment:No Flow Measurement,High Temp
CV-24042	9/2/2025 10:34:00 AM				AtmAA
CV-24042	9/8/2025 8:40:10 AM	34.4362612	-118.6474712	1378	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open;Well Condition:Good
CV-24042	9/8/2025 8:45:00 AM				AtmAA
CV-24042	9/15/2025 2:13:22 PM	34.4362568	-118.6474842	1361	Valve Adjustment:No Flow Measurement,High Temp
CV-24042	9/15/2025 2:15:00 PM				AtmAA
CV-24042	9/16/2025 1:37:19 PM				
CV-24042	9/22/2025 1:15:59 PM	34.4362623	-118.6474470	1387	Valve Adjustment:High Temp
CV-24042	9/29/2025 9:23:47 AM	34.4362293	-118.6474342	1394	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24043	9/8/2025 10:59:55 AM	34.4340978	-118.6497220	1335	,,
CV-24043	9/16/2025 9:39:54 AM	34.4340867	-118.6496880	1342	Valve Adjustment:Surging Liquid in Header
CV-24044	9/5/2025 10:52:35 AM	34.4343902	-118.6493850	1353	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24044	9/16/2025 10:55:01 AM	34.4343992	-118.6493908	1328	Valve Adjustment:Surging Liquid in Header
CV-24045	9/3/2025 2:14:13 PM	34.4347423	-118.6491037	1341	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp
CV-24045	9/3/2025 2:18:00 PM				AtmAA
CV-24045	9/3/2025 2:18:00 PM				AtmAA; [User entered 15.75%]
CV-24045	9/9/2025 1:56:13 PM	34.4347430	-118.6490465	1349	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header
CV-24045	9/9/2025 1:58:00 PM				AtmAA
CV-24045	9/16/2025 1:42:07 PM	34.4347380	-118.6490740	1349	Valve Adjustment:High Temp
CV-24045	9/16/2025 1:43:00 PM				AtmAA
CV-24045	9/23/2025 9:42:57 AM	34.4347855	-118.6490667	1340	Valve Adjustment:NSPS/EG CAI,High Temp;Well Condition:Lorentz Pump Installed
CV-24045	9/30/2025 8:42:13 AM	34.4347363	-118.6490753	1351	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24046	9/8/2025 10:04:52 AM	34.4350927	-118.6483747	1348	
CV-24046	9/8/2025 10:05:32 AM	34.4350940	-118.6483780	1353	
CV-24046	9/16/2025 1:13:19 PM	34.4350783	-118.6483748	1344	
CV-24048	9/8/2025 10:26:19 AM	34.4355773	-118.6477965	1366	
CV-24048	9/16/2025 1:41:18 PM	34.4355633	-118.6477910	1371	
CV-24049	9/2/2025 11:18:25 AM	34.4359477	-118.6471630	1394	Valve Adjustment:High Temp
CV-24049	9/2/2025 11:25:00 AM				AtmAA
CV-24049	9/2/2025 11:25:00 AM				AtmAA; [User entered 14.53%]
CV-24049	9/3/2025 9:45:00 AM				Air Tech Lab
CV-24049	9/3/2025 9:45:00 AM				Air Tech Lab; [User entered 16%]
CV-24049	9/8/2025 8:45:03 AM	34.4359707	-118.6471857	1392	Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Decreased Flow/Vacuum,Barely Open;Well Condition:Good
CV-24049	9/8/2025 8:48:00 AM				AtmAA
CV-24049	9/15/2025 2:22:04 PM	34.4359475	-118.6471875	1384	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum,Surging Liquid in Header
CV-24049	9/15/2025 2:22:59 PM	34.4359692	-118.6471947	1389	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Surging Liquid in Header
CV-24049	9/15/2025 2:24:00 PM				AtmAA
CV-24049	9/22/2025 1:21:53 PM	34.4359533	-118.6471788	1381	Valve Adjustment:High Temp
CV-24049	9/29/2025 9:33:42 AM	34.4359403	-118.6471855	1387	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24050	9/8/2025 10:50:27 AM	34.4337452	-118.6500262	1365	Audible Flow,,
CV-24050	9/16/2025 10:46:01 AM	34.4337782	-118.6499352	1320	

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24051	9/8/2025 8:16:33 AM	34.4344807	-118.6490290	1339	Valve Adjustment:Barely Open;Well Comment:Possibly damaged valve
CV-24051	9/16/2025 11:02:28 AM	34.4344450	-118.6490302	1339	
CV-24052	9/9/2025 9:09:07 AM	34.4350723	-118.6480662	1371	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Header
CV-24052	9/9/2025 9:10:08 AM	34.4350885	-118.6480538	1365	Valve Adjustment:NSPS/EG CAC,Surging Liquid in Header
CV-24052	9/16/2025 1:50:21 PM	34.4351000	-118.6480585	1371	
CV-24053	9/8/2025 2:11:38 PM	34.4352653	-118.6477900	1367	
CV-24053	9/8/2025 2:17:33 PM	34.4352710	-118.6478033	1363	Valve Adjustment:High O2
CV-24053	9/11/2025 8:20:00 AM				Air Tech Lab
CV-24053	9/11/2025 8:20:00 AM				Air Tech Lab; [User entered 18%]
CV-24053	9/16/2025 1:45:54 PM	34.4352607	-118.6477985	1374	
CV-24054	9/2/2025 11:13:00 AM				AtmAA
CV-24054	9/2/2025 11:13:00 AM				AtmAA; [User entered 9.04%]
CV-24054	9/2/2025 11:13:04 AM	34.4356132	-118.6471563	1404	Valve Adjustment:No Flow Measurement,High Temp
CV-24054	9/10/2025 2:20:09 PM	34.4356385	-118.6471822	1381	High Temp,,
CV-24054	9/10/2025 2:22:00 PM				AtmAA
CV-24054	9/12/2025 1:48:31 PM	34.4356067	-118.6471448	1389	Valve Adjustment:High Temp
CV-24054	9/17/2025 6:49:53 AM	34.4356423	-118.6471802	1389	Valve Adjustment:High Temp
CV-24054	9/25/2025 8:51:28 AM	34.4356410	-118.6471717	1384	Valve Adjustment:High Temp
CV-24054	9/29/2025 9:40:14 AM	34.4356368	-118.6471688	1390	Valve Adjustment:High Temp,Surging Liquid in Well (Watered In)
CV-24055	9/2/2025 11:04:57 AM	34.4358647	-118.6469217	1404	
CV-24055	9/3/2025 9:50:00 AM				Air Tech Lab
CV-24055	9/3/2025 9:50:00 AM				Air Tech Lab; [User entered 8.6%]
CV-24055	9/29/2025 12:51:51 PM	34.4358962	-118.6469135	1405	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum
CV-24055	9/29/2025 12:52:44 PM	34.4358798	-118.6468953	1403	Valve Adjustment:NSPS/EG CAC
CV-24056	9/4/2025 8:48:53 AM	34.4332952	-118.6501358	1336	Valve Adjustment:High Temp
CV-24056	9/4/2025 8:50:00 AM				AtmAA
CV-24056	9/4/2025 8:50:00 AM				AtmAA; [User entered 4.84%]
CV-24056	9/10/2025 9:59:34 AM	34.4332862	-118.6501365	1335	No Flow Measurement,High Temp,
CV-24056	9/10/2025 10:00:00 AM				AtmAA
CV-24056	9/18/2025 8:57:35 AM	34.4332717	-118.6501502	1344	Valve Adjustment:No Flow Measurement,High Temp
CV-24056	9/24/2025 11:21:31 AM	34.4332803	-118.6501765	1316	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-24057	9/8/2025 10:46:34 AM	34.4334022	-118.6496597	1355	Audible Flow,,
CV-24057	9/26/2025 8:28:21 AM	34.4334607	-118.6496548	1351	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Good
CV-24058	9/3/2025 9:35:56 AM	34.4338102	-118.6494258	1350	
CV-24058	9/16/2025 2:16:50 PM	34.4337913	-118.6494555	1362	Valve Adjustment:Audible Flow
CV-24058	9/17/2025 9:37:05 AM				
CV-24059	9/3/2025 9:53:15 AM	34.4337802	-118.6490597	1345	Valve Adjustment:NSPS/EG CAI,Reconnected this Date,High Temp
CV-24059	9/3/2025 9:54:19 AM	34.4337755	-118.6490695	1354	Valve Adjustment:High Temp
CV-24059	9/16/2025 2:22:20 PM	34.4337687	-118.6490773	1349	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24059	9/16/2025 2:22:48 PM	34.4337618	-118.6490698	1351	
CV-24060	9/3/2025 10:17:43 AM	34.4340428	-118.6487742	1359	Valve Adjustment:Reconnected this Date,Decreased Flow/Vacuum
CV-24060	9/16/2025 2:01:22 PM	34.4340163	-118.6487720	1359	Valve Adjustment:Decreased Flow/Vacuum
CV-24061	9/10/2025 1:37:18 PM	34.4343588	-118.6485907	1367	Valve Adjustment:Decreased Flow/Vacuum
CV-24061	9/17/2025 9:57:04 AM				
CV-24061	9/18/2025 11:29:36 AM	34.4343578	-118.6485933	1363	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Good
CV-24062	9/5/2025 6:49:16 AM	34.4345922	-118.6480772	1363	Valve Adjustment:No Flow Measurement,High Temp
CV-24062	9/5/2025 6:50:00 AM				AtmAA
CV-24062	9/5/2025 6:50:00 AM				AtmAA; [User entered 3.60%]
CV-24062	9/10/2025 9:10:00 AM				Air Tech Lab; [User entered 7.5%]
CV-24062	9/10/2025 9:10:00 AM				Air Tech Lab
CV-24062	9/11/2025 9:35:00 AM	34.4346030	-118.6480485	1365	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24062	9/17/2025 8:27:01 AM	34.4345883	-118.6480765	1373	Valve Adjustment:High Temp
CV-24062	9/24/2025 2:40:00 PM	34.4345935	-118.6480892	1379	Valve Adjustment:No Flow Measurement,High Temp
CV-24063	9/9/2025 9:39:46 AM	34.4349483	-118.6475175	1378	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24063	9/9/2025 9:41:34 AM	34.4349528	-118.6475240	1373	Valve Adjustment:High Temp
CV-24063	9/15/2025 8:30:00 AM				Air Tech Lab
CV-24063	9/15/2025 8:30:00 AM				Air Tech Lab; [User entered 11%]
CV-24063	9/26/2025 8:51:30 AM	34.4349388	-118.6475247	1388	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum;Well Condition:Good
CV-24063	9/26/2025 8:53:44 AM	34.4349437	-118.6475412	1385	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open;Well Condition:Good
CV-24063	9/30/2025 2:31:24 PM	34.4349698	-118.6475725	1353	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24064	9/3/2025 10:50:00 AM				Air Tech Lab
CV-24064	9/3/2025 10:50:00 AM				Air Tech Lab; [User entered 13%]
CV-24064	9/5/2025 6:24:17 AM	34.4352422	-118.6471620	1386	Valve Adjustment:No Flow Measurement,High Temp
CV-24064	9/5/2025 9:44:00 AM				AtmAA
CV-24064	9/5/2025 9:44:00 AM				AtmAA; [User entered 7.11%]
CV-24064	9/11/2025 8:49:26 AM	34.4352377	-118.6471488	1378	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24064	9/11/2025 8:50:00 AM				AtmAA
CV-24064	9/17/2025 8:07:55 AM	34.4352375	-118.6471540	1387	Valve Adjustment:High Temp
CV-24065-TP17	9/2/2025 11:39:29 AM	34.4356113	-118.6468040	1393	
CV-24065-TP17	9/3/2025 9:55:00 AM				Air Tech Lab
CV-24065-TP17	9/3/2025 9:55:00 AM				Air Tech Lab; [User entered 0.67%]
CV-24065-TP17	9/5/2025 1:45:04 PM	34.4356203	-118.6467290	1413	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum;Well Condition:Good,Lorentz Pump Installed
CV-24065-TP17	9/10/2025 10:45:53 AM	34.4356252	-118.6467977	1409	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Barely Open;Well Condition:Good

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24065-TP17	9/29/2025 1:03:31 PM	34.4356127	-118.6467942	1400	Valve Adjustment:Decreased Flow/Vacuum
CV-24066	9/2/2025 10:20:16 AM	34.4330243	-118.6498048	1332	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good
CV-24066	9/9/2025 9:05:00 AM				Air Tech Lab
CV-24066	9/9/2025 9:05:00 AM				Air Tech Lab; [User entered 3.5%]
CV-24066	9/17/2025 8:47:58 AM	34.4330140	-118.6498163	1336	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Good
CV-24067	9/8/2025 10:41:44 AM	34.4332108	-118.6496297	1309	,,
CV-24067	9/23/2025 8:36:00 AM	34.4332075	-118.6497027	1339	
CV-24068	9/11/2025 12:47:05 PM	34.4332407	-118.6493073	1362	
CV-24068	9/18/2025 10:59:15 AM	34.4332503	-118.6493235	1359	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Lorentz Pump Installed
CV-24069	9/3/2025 10:37:15 AM	34.4334358	-118.6488853	1344	Valve Adjustment:Reconnected this Date,Decreased Flow/Vacuum;Well Repairs:Sample Port
CV-24069	9/10/2025 9:30:00 AM				Air Tech Lab
CV-24069	9/10/2025 9:30:00 AM				Air Tech Lab; [User entered 4.5%]
CV-24069	9/18/2025 11:10:36 AM	34.4334307	-118.6489020	1361	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good
CV-24070	9/3/2025 10:25:01 AM	34.4337193	-118.6486563	1348	Valve Adjustment:NSPS/EG CAI,Reconnected this Date,High Temp
CV-24070	9/3/2025 10:28:46 AM	34.4337265	-118.6486583	1351	Valve Adjustment:High Temp
CV-24070	9/10/2025 9:45:00 AM				Air Tech Lab
CV-24070	9/10/2025 9:45:00 AM				Air Tech Lab; [User entered 2.8%]
CV-24070	9/18/2025 11:16:50 AM	34.4337228	-118.6486813	1363	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good
CV-24071	9/10/2025 9:40:00 AM				Air Tech Lab
CV-24071	9/10/2025 9:40:00 AM				Air Tech Lab; [User entered 2.8%]
CV-24071	9/10/2025 1:26:51 PM	34.4340110	-118.6484657	1371	Valve Adjustment:NSPS/EG CAI,Reconnected this Date,High Temp
CV-24071	9/10/2025 1:28:08 PM	34.4340190	-118.6484600	1371	Valve Adjustment:Reconnected this Date,High Temp
CV-24071	9/18/2025 11:26:39 AM	34.4340272	-118.6484615	1356	Valve Adjustment:Decreased Flow/Vacuum
CV-24072	9/11/2025 10:19:27 AM	34.4342087	-118.6480250	1376	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Reconnected this Date,Positive Static Press.,Increased Flow/Vacuum
CV-24072	9/11/2025 10:20:49 AM	34.4342058	-118.6480293	1375	
CV-24072	9/18/2025 8:57:56 AM	34.4341685	-118.6480407	1377	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good
CV-24073-TP13	9/9/2025 9:52:51 AM	34.4346470	-118.6477070	1383	Valve Adjustment:High Temp
CV-24073-TP13	9/9/2025 9:54:05 AM	34.4346388	-118.6477070	1381	Valve Adjustment:High Temp
CV-24073-TP13	9/14/2025 12:49:28 PM	34.4346670	-118.6476957	1386	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Reconnected this Date,High Temp,Decreased Flow/Vacuum
CV-24073-TP13	9/14/2025 12:50:48 PM	34.4346455	-118.6476983	1395	
CV-24073-TP13	9/18/2025 8:38:00 AM	34.4346510	-118.6477140	1390	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Good
CV-24073-TP13	9/18/2025 8:39:42 AM	34.4346443	-118.6477038	1401	Valve Adjustment:NSPS/EG CAC;Well Condition:Good

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24074	9/5/2025 2:09:04 PM	34.4347720	-118.6474157	1398	Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum,Barely Open;Well Condition:Good
CV-24074	9/12/2025 10:31:27 AM	34.4347270	-118.6474273	1385	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Fair
CV-24074	9/18/2025 8:46:15 AM	34.4347288	-118.6473897	1399	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Good
CV-24075-TP15	9/5/2025 6:38:38 AM	34.4350182	-118.6471210	1380	Valve Adjustment:No Flow Measurement,High Temp
CV-24075-TP15	9/5/2025 6:43:00 AM				AtmAA
CV-24075-TP15	9/5/2025 6:43:00 AM				AtmAA; [User entered 5.63%]
CV-24075-TP15	9/10/2025 11:13:25 AM				
CV-24075-TP15	9/11/2025 9:14:51 AM	34.4350317	-118.6471242	1389	Valve Adjustment:No Flow Measurement,High Temp
CV-24075-TP15	9/11/2025 9:15:00 AM				AtmAA
CV-24075-TP15	9/17/2025 8:12:05 AM	34.4350182	-118.6471562	1390	Valve Adjustment:No Flow Measurement,High Temp
CV-24076	9/2/2025 1:44:10 PM	34.4353345	-118.6467963	1426	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum
CV-24076	9/2/2025 1:44:46 PM	34.4353273	-118.6468342	1413	
CV-24077	9/2/2025 9:43:04 AM	34.4326870	-118.6492755	1350	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header;Well Condition:Good
CV-24077	9/2/2025 9:54:12 AM	34.4326888	-118.6493015	1349	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum;Well Condition:Good
CV-24077	9/17/2025 8:44:36 AM	34.4326902	-118.6493040	1337	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Good
CV-24078	9/8/2025 10:36:46 AM	34.4329732	-118.6494205	1316	,,
CV-24078	9/23/2025 8:28:46 AM	34.4329102	-118.6494233	1343	
CV-24079-TP8	9/4/2025 10:32:00 AM	34.4329880	-118.6491002	1359	Valve Adjustment:No Flow Measurement
CV-24079-TP8	9/11/2025 10:43:31 AM	34.4330002	-118.6490890	1351	Valve Adjustment:High Temp
CV-24079-TP8	9/11/2025 10:44:00 AM				AtmAA
CV-24079-TP8	9/17/2025 9:30:11 AM	34.4329867	-118.6491118	1360	Valve Adjustment:No Flow Measurement,High Temp
CV-24079-TP8	9/24/2025 1:54:29 PM	34.4330002	-118.6491252	1367	Valve Adjustment:No Flow Measurement,High Temp
CV-24080	9/3/2025 10:43:46 AM	34.4331490	-118.6488287	1351	Valve Adjustment:Reconnected this Date,Decreased Flow/Vacuum
CV-24080	9/26/2025 8:39:34 AM	34.4331243	-118.6488592	1380	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Good
CV-24081-TP10	9/3/2025 1:35:47 PM	34.4334223	-118.6485933	1384	Valve Adjustment:Reconnected this Date,Decreased Flow/Vacuum
CV-24081-TP10	9/17/2025 1:56:55 PM				
CV-24081-TP10	9/18/2025 9:15:56 AM	34.4334047	-118.6485768	1374	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good
CV-24082	9/3/2025 9:26:31 AM	34.4334382	-118.6482943	1380	Valve Adjustment:Reconnected this Date,Decreased Flow/Vacuum
CV-24082	9/17/2025 1:34:05 PM				
CV-24082	9/18/2025 9:12:44 AM	34.4334350	-118.6483148	1381	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Good

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24083	9/11/2025 10:33:03 AM	34.4337298	-118.6483332	1365	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Reconnected this Date,Decreased Flow/Vacuum
CV-24083	9/11/2025 10:34:54 AM	34.4337237	-118.6483250	1362	
CV-24083	9/11/2025 1:34:03 PM	34.4337077	-118.6483483	1363	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Reconnected this Date,Positive Static Press.,Increased Flow/Vacuum;Well Condition:Good
CV-24083	9/11/2025 1:35:12 PM	34.4337155	-118.6483588	1349	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAC,Audible Flow,Barely Open;Well Condition:Good
CV-24083	9/18/2025 11:21:42 AM	34.4337145	-118.6483327	1366	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Good
CV-24084-TP11	9/15/2025 10:12:22 AM	34.4338672	-118.6480107	1376	Valve Adjustment:NSPS/EG CAI,Reconnected this Date,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-24084-TP11	9/15/2025 10:16:30 AM	34.4338695	-118.6480175	1372	Valve Adjustment:Decreased Flow/Vacuum
CV-24084-TP11	9/17/2025 9:01:42 AM	34.4338678	-118.6480322	1375	Valve Adjustment:High Temp
CV-24084-TP11	9/25/2025 10:16:39 AM	34.4338612	-118.6480337	1384	Valve Adjustment:High Temp,Surging Liquid in Header
CV-24085	9/4/2025 1:58:05 PM	34.4324063	-118.6489787	1332	Audible Flow,,
CV-24085	9/21/2025 12:33:53 PM	34.4323843	-118.6489835	1348	Valve Adjustment:Decreased Flow/Vacuum
CV-24086	9/4/2025 2:12:10 PM	34.4328293	-118.6486340	1289	Audible Flow,,
CV-24086	9/17/2025 2:10:47 PM				
CV-24086	9/18/2025 10:50:47 AM	34.4329035	-118.6486712	1383	Valve Adjustment:Decreased Flow/Vacuum,Barely Open;Well Condition:Good
CV-24087	9/4/2025 2:42:56 PM	34.4331067	-118.6481572	1388	Audible Flow,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24087	9/18/2025 10:37:04 AM	34.4329960	-118.6481140	1389	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Good
CV-24088	9/15/2025 10:01:29 AM	34.4335970	-118.6476700	1380	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Reconnected this Date,Positive Static Press.,Increased Flow/Vacuum
CV-24088	9/15/2025 10:07:06 AM	34.4336077	-118.6476600	1377	Valve Adjustment:Decreased Flow/Vacuum
CV-24088	9/16/2025 1:44:00 PM	34.4335808	-118.6476662	1387	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
CV-24088	9/16/2025 1:44:47 PM	34.4335845	-118.6476785	1386	Valve Adjustment:NSPS/EG CAC
CV-24089	9/3/2025 10:39:27 AM				
CV-24089	9/4/2025 11:34:01 AM	34.4324548	-118.6480810	1306	,,
CV-24089	9/23/2025 10:35:49 AM	34.4324522	-118.6480922	1355	Valve Adjustment:Surging Liquid in Well (Watered In)
CV-24090	9/4/2025 2:55:25 PM	34.4327073	-118.6475438	1371	,,
CV-24090	9/18/2025 12:50:51 PM	34.4326937	-118.6475317	1386	Valve Adjustment:Decreased Flow/Vacuum
CV-24090	9/18/2025 1:02:54 PM	34.4327045	-118.6475173	1380	Valve Adjustment:Decreased Flow/Vacuum
CV-24091	9/3/2025 1:51:33 PM	34.4329867	-118.6468973	1363	

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24091	9/18/2025 8:49:34 AM	34.4330055	-118.6468832	1414	Valve Adjustment:Orifice Plate Changed (See OP Log);Well Comment:Potential oxygen intrusion through lorentz pump fitting
CV-24091	9/18/2025 8:54:49 AM	34.4330063	-118.6468938	1404	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum
CV-24092	9/9/2025 11:04:26 AM	34.4333117	-118.6461512	1411	
CV-24092	9/18/2025 12:14:08 PM	34.4333170	-118.6461392	1411	Valve Adjustment:Orifice Plate Changed (See OP Log)
CV-24092	9/18/2025 12:20:59 PM	34.4333390	-118.6461107	1423	
CV-24093	9/3/2025 11:15:17 AM	34.4340522	-118.6463270	1402	Valve Adjustment:Orifice Plate Changed (See OP Log)
CV-24093	9/22/2025 10:02:13 AM	34.4340432	-118.6463470	1402	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum
CV-24093	9/22/2025 10:06:08 AM	34.4340347	-118.6463467	1401	Valve Adjustment:Orifice Plate Changed (See OP Log)
CV-24093	9/22/2025 10:10:33 AM	34.4340297	-118.6463470	1384	Valve Adjustment:Orifice Plate Changed (See OP Log)
CV-24094	9/3/2025 10:11:52 AM				
CV-24094	9/10/2025 9:44:46 AM				
CV-24094	9/11/2025 8:53:46 AM	34.4345898	-118.6460543	1406	Valve Adjustment:Increased Flow/Vacuum
CV-24094	9/11/2025 1:09:03 PM	34.4345872	-118.6460673	1387	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum;Well Condition:Good
CV-24094	9/16/2025 9:15:41 AM				
CV-24094	9/25/2025 10:19:22 AM				
CV-24095	9/8/2025 9:15:00 AM				Air Tech Lab; [User entered 15%]
CV-24095	9/8/2025 9:15:00 AM				Air Tech Lab
CV-24095	9/8/2025 9:30:00 AM				Air Tech Lab; [User entered 13%]
CV-24095	9/8/2025 2:36:21 PM	34.4332243	-118.6514040	1240	,,
CV-24095	9/18/2025 2:48:19 PM	34.4334182	-118.6513063	1257	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Fair;Well Repairs:Sample Port
CV-24096	9/8/2025 2:22:07 PM	34.4332343	-118.6515385	1158	High O2,,
CV-24096	9/8/2025 2:23:48 PM	34.4332558	-118.6516222	1224	,,
CV-24096	9/10/2025 12:28:40 PM	34.4332183	-118.6515483	1264	Valve Adjustment:NSPS/EG CAC
CV-24096	9/10/2025 12:29:19 PM	34.4332195	-118.6515418	1259	
CV-24096	9/26/2025 8:42:20 AM	34.4332217	-118.6515787	1257	
CV-24097	9/8/2025 2:15:19 PM	34.4327700	-118.6515373	1198	,,
CV-24097	9/17/2025 11:07:58 AM	34.4328082	-118.6515712	1265	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
CV-24097	9/17/2025 11:08:45 AM	34.4327942	-118.6515597	1266	Valve Adjustment:NSPS/EG CAC
CV-24098	9/2/2025 2:33:25 PM	34.4325402	-118.6513002	1246	Valve Adjustment:Audible Flow;Well Condition:Fair;Well Repairs:Valve
CV-24098	9/18/2025 2:37:11 PM	34.4325130	-118.6513133	1259	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header;Well Condition:Fair
CV-24099	9/2/2025 2:22:52 PM	34.4323593	-118.6509160	1253	Valve Comment:Unable to adjust;Well Condition:Fair
CV-24099	9/8/2025 9:45:58 AM	34.4323540	-118.6509232	1256	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24099	9/8/2025 9:47:03 AM	34.4323605	-118.6509295	1253	
CV-24099	9/9/2025 1:28:04 PM				
CV-24099	9/17/2025 10:47:54 AM	34.4323050	-118.6509532	1254	
CV-24100	9/2/2025 2:04:58 PM	34.4320482	-118.6504732	1263	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Fair
CV-24100	9/2/2025 2:06:02 PM	34.4320513	-118.6504712	1268	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Fair
CV-24100	9/8/2025 8:45:00 AM				Air Tech Lab
CV-24100	9/8/2025 8:45:00 AM				Air Tech Lab; [User entered 0.45%]
CV-24100	9/18/2025 2:29:29 PM	34.4320640	-118.6504857	1261	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Fair
CV-24100	9/18/2025 2:32:23 PM	34.4320547	-118.6504772	1265	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Fair
CV-24101	9/2/2025 2:00:02 PM	34.4318322	-118.6502830	1267	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Fair
CV-24101	9/8/2025 8:40:00 AM				Air Tech Lab
CV-24101	9/8/2025 8:40:00 AM				Air Tech Lab; [User entered 0.41%]
CV-24101	9/17/2025 10:22:43 AM	34.4318145	-118.6502963	1257	
CV-24102	9/8/2025 9:18:43 AM	34.4316843	-118.6498060	1178	,,
CV-24102	9/17/2025 9:38:43 AM	34.4316322	-118.6497752	1272	
CV-24103	9/4/2025 8:42:44 AM	34.4316123	-118.6487828	1401	Audible Flow,,
CV-24103	9/17/2025 1:22:44 PM	34.4316402	-118.6488300	1346	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Good
CV-24103	9/30/2025 9:42:10 AM				
CV-24104	9/4/2025 9:55:02 AM	34.4316095	-118.6481650	1250	,,
CV-24104	9/10/2025 11:08:23 AM	34.4317107	-118.6480925	1345	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Barely Open;Well Condition:Fair
CV-24104	9/17/2025 1:13:15 PM	34.4317448	-118.6480883	1341	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Good
CV-24104	9/30/2025 9:33:12 AM				
CV-24105	9/4/2025 9:49:04 AM	34.4319680	-118.6476402	1260	Audible Flow,,
CV-24105	9/17/2025 1:06:55 PM	34.4319317	-118.6476337	1361	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Good
CV-24105	9/30/2025 9:10:47 AM				
CV-24106	9/4/2025 11:03:25 AM	34.4320710	-118.6466317	1283	,,
CV-24106	9/17/2025 10:00:21 AM	34.4321142	-118.6467603	1358	Valve Comment:Unable to reach system safely;Valve Adjustment:Audible Flow,Barely Open;Well Condition:Fair
CV-24106	9/25/2025 2:39:04 PM	34.4321633	-118.6467887	1352	Increased Flow/Vacuum,,
CV-24107	9/10/2025 2:01:13 PM	34.4325408	-118.6461577	1349	
CV-24108	9/10/2025 1:14:32 PM	34.4331582	-118.6454140	1359	
CV-24109	9/9/2025 2:45:16 PM	34.4339937	-118.6448845	1389	Valve Adjustment:Decreased Flow/Vacuum
CV-24110	9/3/2025 10:26:09 AM	34.4346353	-118.6446477	1381	Valve Adjustment:Decreased Flow/Vacuum

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24110	9/11/2025 10:30:33 AM	34.4346318	-118.6446670	1383	Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum,Barely Open;Well Condition:Good
CV-24111	9/3/2025 10:30:26 AM	34.4353627	-118.6449313	1382	
CV-24111	9/11/2025 10:43:06 AM	34.4353330	-118.6449375	1389	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Barely Open;Well Condition:Good
CV-24112	9/3/2025 10:16:20 AM	34.4352187	-118.6441877	1387	
CV-24112	9/10/2025 1:35:13 PM				
CV-24112	9/11/2025 2:03:06 PM	34.4352335	-118.6441942	1381	Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum,Barely Open;Well Condition:Good
CV-24113	9/8/2025 9:04:58 AM	34.4308370	-118.6497508	1240	Increased Flow/Vacuum,Opened Valve 1/2 to 1 Turn,
CV-24113	9/15/2025 10:30:40 AM	34.4308372	-118.6497370	1261	Valve Comment:RES SEM;Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum;Well Condition:Good
CV-24114	9/10/2025 1:55:47 PM				
CV-24114	9/15/2025 2:35:15 AM	34.4308342	-118.6485267	1302	Increased Flow/Vacuum,Opened Valve 1/2 to 1 Turn,Audible Flow
CV-24115	9/5/2025 8:24:13 AM	34.4312387	-118.6467577	1250	,,
CV-24115	9/10/2025 2:15:03 PM				
CV-24115	9/24/2025 10:09:43 AM	34.4312107	-118.6467913	1220	,,
CV-24116	9/5/2025 8:41:41 AM	34.4316453	-118.6456685	1224	,,
CV-24116	9/18/2025 9:38:02 AM	34.4316520	-118.6457420	1247	
CV-24116	9/26/2025 9:12:19 AM	34.4316587	-118.6457415	1254	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Barely Open;Well Condition:Good
CV-24117	9/10/2025 10:29:11 AM	34.4323305	-118.6449753	1304	
CV-24118	9/4/2025 2:46:28 PM	34.4332975	-118.6438293	1307	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Good,Lorentz Pump Installed
CV-24118	9/4/2025 2:49:20 PM	34.4333107	-118.6438393	1301	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open;Well Condition:Good,Lorentz Pump Installed
CV-24119	9/11/2025 9:30:21 AM	34.4337387	-118.6423202	1282	Valve Adjustment:High Temp
CV-24119	9/11/2025 9:32:05 AM	34.4337508	-118.6422925	1281	Valve Adjustment:High Temp
CV-24120	9/9/2025 9:41:57 AM	34.4368690	-118.6472953	1343	Valve Adjustment:Decreased Flow/Vacuum
CV-24120	9/9/2025 9:42:55 AM	34.4368613	-118.6472925	1347	Valve Adjustment:NSPS/EG CAC
CV-24120	9/11/2025 9:00:00 AM				Air Tech Lab
CV-24120	9/11/2025 9:00:00 AM				Air Tech Lab; [User entered 7.2%]
CV-24120	9/29/2025 9:37:29 AM	34.4368392	-118.6472865	1349	
CV-24121	9/2/2025 9:45:00 AM				Air Tech Lab
CV-24121	9/2/2025 9:45:00 AM				Air Tech Lab; [User entered 0.53%]
CV-24121	9/9/2025 9:34:59 AM	34.4369235	-118.6470392	1328	Valve Adjustment:Decreased Flow/Vacuum
CV-24121	9/9/2025 2:05:11 PM				
CV-24121	9/29/2025 9:30:55 AM	34.4369370	-118.6470200	1343	

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24122	9/2/2025 9:30:00 AM				Air Tech Lab
CV-24122	9/2/2025 9:30:00 AM				Air Tech Lab; [User entered 0.36%]
CV-24122	9/9/2025 9:27:27 AM	34.4371332	-118.6466085	1313	
CV-24122	9/29/2025 9:57:41 AM	34.4371582	-118.6466292	1327	Valve Adjustment:Increased Flow/Vacuum
CV-24123	9/9/2025 2:22:03 PM				
CV-24123	9/17/2025 2:05:12 PM	34.4373115	-118.6462447	1308	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-24124	9/5/2025 2:10:36 PM	34.4366367	-118.6470328	1370	Valve Adjustment:Decreased Flow/Vacuum
CV-24125-TP20	9/3/2025 8:50:00 AM				Air Tech Lab
CV-24125-TP20	9/3/2025 8:50:00 AM				Air Tech Lab; [User entered 0.38%]
CV-24125-TP20	9/10/2025 10:36:51 AM				
CV-24125-TP20	9/29/2025 9:13:59 AM	34.4369583	-118.6463338	1331	Valve Adjustment:Decreased Flow/Vacuum
CV-24126	9/11/2025 1:31:45 PM	34.4363948	-118.6471260	1384	Valve Adjustment:NSPS/EG CAI,High Temp,High O2
CV-24126	9/11/2025 1:32:45 PM	34.4363932	-118.6471172	1386	Valve Adjustment:High Temp,High O2
CV-24126	9/18/2025 11:42:24 AM	34.4363875	-118.6470940	1392	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In)
CV-24126	9/22/2025 1:07:42 PM	34.4364003	-118.6471307	1386	Valve Adjustment:High Temp
CV-24127	9/2/2025 10:20:00 AM				Air Tech Lab
CV-24127	9/2/2025 10:20:00 AM				Air Tech Lab; [User entered 3.6%]
CV-24127	9/5/2025 2:23:46 PM	34.4364642	-118.6468188	1376	Valve Adjustment:Decreased Flow/Vacuum
CV-24127	9/30/2025 12:59:10 PM	34.4364597	-118.6468302	1394	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-24127	9/30/2025 1:32:54 PM	34.4364692	-118.6468285	1380	Valve Comment:Bolted down flange causing air intrusion;Valve Adjustment:NSPS/EG CAC
CV-24128	9/2/2025 10:00:00 AM				Air Tech Lab
CV-24128	9/2/2025 10:00:00 AM				Air Tech Lab; [User entered 1.7%]
CV-24128	9/5/2025 1:54:54 PM	34.4366945	-118.6464455	1368	Valve Adjustment:Decreased Flow/Vacuum
CV-24129	9/5/2025 1:50:28 PM	34.4366993	-118.6461423	1372	
CV-24130	9/29/2025 9:03:27 AM	34.4368063	-118.6456868	1336	
CV-24131	9/3/2025 9:05:01 AM				
CV-24131	9/10/2025 8:55:13 AM				
CV-24131	9/16/2025 8:19:01 AM				
CV-24131	9/24/2025 1:20:08 PM				
CV-24131	9/29/2025 8:45:14 AM	34.4367232	-118.6451025	1346	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Orifice Plate Changed (See OP Log),Positive Static Press.,Increased Flow/Vacuum
CV-24131	9/29/2025 8:48:13 AM	34.4367222	-118.6450833	1339	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24131	9/29/2025 8:50:41 AM	34.4367040	-118.6450683	1339	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum
CV-24132	9/11/2025 1:21:43 PM				
CV-24132	9/22/2025 2:27:44 PM	34.4372300	-118.6440298	1286	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-24133	9/22/2025 1:57:31 PM	34.4374453	-118.6427050	1276	Valve Adjustment:Audible Flow

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24134-TP19	9/8/2025 8:34:35 AM	34.4363762	-118.6465113	1365	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Good
CV-24134-TP19	9/8/2025 8:35:59 AM	34.4363692	-118.6465080	1365	Valve Adjustment:NSPS/EG CAC;Well Condition:Good
CV-24135	9/2/2025 10:22:28 AM	34.4363672	-118.6459623	1365	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24135	9/2/2025 10:23:00 AM				AtmAA
CV-24135	9/8/2025 8:28:16 AM	34.4363845	-118.6459655	1356	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Good,Lorentz Pump Installed
CV-24135	9/8/2025 8:30:00 AM				AtmAA
CV-24135	9/15/2025 2:35:35 PM	34.4363673	-118.6459653	1359	Valve Comment:Hero Tox on;Valve Adjustment:No Flow Measurement,High Temp
CV-24135	9/15/2025 2:48:00 PM				AtmAA
CV-24135	9/22/2025 1:33:27 PM	34.4363842	-118.6459545	1358	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24135	9/25/2025 10:20:13 AM	34.4364063	-118.6460017	1339	NSPS/EG CAI,High Temp,Increased Flow/Vacuum
CV-24135	9/25/2025 10:25:49 AM	34.4363572	-118.6458947	1299	NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24135	9/29/2025 8:53:02 AM	34.4363513	-118.6459480	1342	Valve Adjustment:NSPS/EG CAI,High Temp;Well Condition:Lorentz Pump Installed
CV-24136	9/2/2025 2:27:57 PM	34.4366263	-118.6442737	1343	Valve Adjustment:High Temp,Barely Open
CV-24136	9/2/2025 2:29:10 PM	34.4366168	-118.6442808	1339	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-24137	9/4/2025 11:18:53 AM	34.4361398	-118.6434885	1353	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Good,Lorentz Pump Installed
CV-24138	9/4/2025 9:30:00 AM				Air Tech Lab
CV-24138	9/4/2025 9:30:00 AM				Air Tech Lab; [User entered 0.64%]
CV-24138	9/10/2025 9:06:38 AM	34.4342660	-118.6512517	1269	Valve Adjustment:High O2,Barely Open,Surging Liquid in Well (Watered In);Well Comment:valve possibly damaged;Well Condition:Poor
CV-24138	9/26/2025 9:09:34 AM	34.4342377	-118.6512303	1274	Valve Adjustment:NSPS/EG CAC,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header
CV-24138	9/30/2025 2:04:46 PM	34.4342422	-118.6512787	1244	Valve Adjustment:High Temp,Reduce Sys. Vac. - Flare Down;Well Condition:Pnumatic Pump Installed
CV-24139	9/4/2025 9:25:00 AM				Air Tech Lab
CV-24139	9/4/2025 9:25:00 AM				Air Tech Lab; [User entered 1.1%]
CV-24139	9/10/2025 9:10:08 AM	34.4344880	-118.6511413	1271	Valve Adjustment:High O2,Barely Open,Surging Liquid in Well (Watered In)
CV-24139	9/26/2025 9:16:26 AM	34.4344835	-118.6511347	1281	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24140	9/4/2025 9:20:00 AM				Air Tech Lab; [User entered 18%]
CV-24140	9/4/2025 9:20:00 AM				Air Tech Lab

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24140	9/4/2025 9:44:56 AM	34.4346868	-118.6511203	1284	Valve Adjustment:No Flow Measurement,High Temp
CV-24140	9/4/2025 9:46:00 AM				AtmAA
CV-24140	9/4/2025 9:46:00 AM				AtmAA; [User entered 15.08%]
CV-24140	9/10/2025 1:44:43 PM	34.4346347	-118.6510852	1296	No Flow Measurement,High Temp,
CV-24140	9/10/2025 1:47:00 PM				AtmAA
CV-24140	9/12/2025 2:03:32 PM	34.4346550	-118.6511242	1299	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24140	9/18/2025 10:57:14 AM	34.4346957	-118.6511000	1280	Valve Adjustment:No Flow Measurement,High Temp
CV-24140	9/24/2025 8:35:53 AM	34.4346983	-118.6511187	1298	Valve Adjustment:No Flow Measurement,High Temp;Well Comment:Pump not pumping upon arrival;Well Condition:Pnumatic Pump Installed
CV-24141	9/4/2025 9:10:00 AM				Air Tech Lab
CV-24141	9/4/2025 9:10:00 AM				Air Tech Lab; [User entered 0%]
CV-24141	9/12/2025 8:37:12 AM	34.4355013	-118.6513273	1292	Valve Adjustment:Audible Flow,Barely Open;Well Repairs:Valve
CV-24141	9/17/2025 2:05:06 PM	34.4354902	-118.6512680	1293	Valve Adjustment:NSPS/EG CAI,High O2,Valve 100% Closed;Well Comment:valve possibly damaged
CV-24141	9/17/2025 2:07:40 PM	34.4354942	-118.6512710	1288	Valve Adjustment:NSPS/EG CAC,Valve 100% Closed
CV-24142	9/4/2025 9:51:54 AM	34.4340107	-118.6513143	1263	Valve Adjustment:No Flow Measurement,High Temp
CV-24142	9/4/2025 9:53:00 AM				AtmAA
CV-24142	9/4/2025 9:53:00 AM				AtmAA; [User entered 17.59%]
CV-24142	9/8/2025 9:15:00 AM				Air Tech Lab; [User entered 13%]
CV-24142	9/8/2025 9:30:00 AM				Air Tech Lab
CV-24142	9/10/2025 1:52:20 PM	34.4340107	-118.6513400	1247	No Flow Measurement,No Adjustment Made,High O2
CV-24142	9/24/2025 2:22:25 PM	34.4339970	-118.6513268	1276	Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Decreased Flow/Vacuum;Well Condition:Poor
CV-24142	9/24/2025 2:22:58 PM	34.4339963	-118.6513220	1270	Valve Adjustment:NSPS/EG CAI,High Temp,High O2
CV-24142	9/30/2025 2:12:50 PM	34.4340032	-118.6513107	1237	Valve Adjustment:High Temp,High O2,Surging Liquid in Header
CV-24142	9/30/2025 2:15:54 PM	34.4340542	-118.6514028	1272	Valve Adjustment:No Flow Measurement,High Temp
CV-24143	9/4/2025 9:15:00 AM				Air Tech Lab
CV-24143	9/4/2025 9:15:00 AM				Air Tech Lab; [User entered 18%]
CV-24143	9/10/2025 8:52:16 AM	34.4350003	-118.6512087	1293	Valve Adjustment:NSPS/EG CAI,High O2,Positive Static Press.,Valve 100% Open,Surging Liquid in Well (Watered In)
CV-24143	9/10/2025 8:53:21 AM	34.4349943	-118.6512098	1291	Valve Adjustment:High O2,Positive Static Press.,Surging Liquid in Well (Watered In)
CV-24143	9/26/2025 9:20:08 AM	34.4349895	-118.6512075	1292	Valve Adjustment:Positive Static Press.,Valve 100% Open,Surging Liquid in Header
CV-24143	9/26/2025 9:22:02 AM	34.4349800	-118.6512012	1297	Valve Adjustment:Positive Static Press.,Valve 100% Closed,Surging Liquid in Header
CV-24144	9/8/2025 2:04:31 PM	34.4325145	-118.6517405	1260	Reduced System Vacuum,,
CV-24144	9/17/2025 11:12:19 AM	34.4325777	-118.6515943	1258	

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24145	9/3/2025 10:28:27 AM	34.4362247	-118.6496248	1374	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-24145	9/3/2025 10:30:00 AM				AtmAA
CV-24145	9/3/2025 10:30:00 AM				AtmAA; [User entered 14.285%]
CV-24145	9/9/2025 10:54:17 AM	34.4362147	-118.6496363	1371	Valve Adjustment:High Temp
CV-24145	9/9/2025 10:55:00 AM				AtmAA
CV-24145	9/16/2025 9:38:53 AM	34.4362263	-118.6496290	1367	Valve Adjustment:High Temp
CV-24145	9/16/2025 9:40:00 AM				AtmAA
CV-24145	9/17/2025 8:30:14 AM				
CV-24145	9/23/2025 8:05:10 AM	34.4362345	-118.6496222	1379	Valve Adjustment:High Temp
CV-24145	9/30/2025 10:58:02 AM	34.4362508	-118.6496143	1366	Valve Adjustment:High Temp,Reduce Sys. Vac. - Flare Down
CV-24146	9/2/2025 1:10:17 PM	34.4374180	-118.6463715	1308	
CV-24146	9/4/2025 1:50:34 PM				
CV-24146	9/16/2025 12:53:02 PM	34.4373945	-118.6463962	1320	
CV-24146	9/16/2025 12:54:53 PM	34.4374003	-118.6463997	1319	Valve Adjustment:Orifice Plate Changed (See OP Log)
CV-24147	9/2/2025 1:06:07 PM	34.4375223	-118.6459258	1277	
CV-24147	9/16/2025 12:58:32 PM	34.4374847	-118.6459652	1292	
CV-24148	9/8/2025 1:50:05 PM	34.4350727	-118.6466595	1390	Valve Adjustment:NSPS/EG CAI,High O2,Positive Static Press.
CV-24148	9/8/2025 1:50:56 PM	34.4350715	-118.6466502	1388	Valve Adjustment:High Temp
CV-24148	9/11/2025 11:20:16 AM	34.4350942	-118.6466322	1384	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Good,Lorentz Pump Installed
CV-24148	9/11/2025 11:23:07 AM	34.4350807	-118.6466505	1387	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Good,Lorentz Pump Installed
CV-24148	9/11/2025 1:20:00 PM				AtmAA
CV-24148	9/18/2025 1:44:58 PM	34.4350692	-118.6466583	1399	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header
CV-24148	9/18/2025 1:45:48 PM	34.4350672	-118.6466588	1403	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header
CV-24149	9/3/2025 10:12:29 AM				
CV-24149	9/8/2025 2:03:34 PM	34.4347815	-118.6469937	1383	
CV-24149	9/10/2025 9:58:14 AM				
CV-24149	9/16/2025 9:27:40 AM				
CV-24149	9/18/2025 11:37:29 AM	34.4347798	-118.6469647	1397	Valve Adjustment:Barely Open;Well Condition:Fair
CV-24150	9/9/2025 1:28:17 PM	34.4346133	-118.6457138	1422	
CV-24151	9/14/2025 12:54:25 PM	34.4344168	-118.6476218	1387	Valve Adjustment:Reconnected this Date
CV-24151	9/18/2025 8:34:26 AM	34.4344085	-118.6476187	1393	Valve Adjustment:Barely Open;Well Condition:Good
CV-24152	9/14/2025 1:00:39 PM	34.4344588	-118.6471553	1393	Valve Adjustment:Reconnected this Date,Decreased Flow/Vacuum
CV-24152	9/19/2025 11:01:16 AM	34.4344533	-118.6471492	1387	Valve Adjustment:Audible Flow,Reduce Sys. Vac. - Flare Down;Well Condition:Good
CV-24153	9/15/2025 12:43:12 PM	34.4343680	-118.6463960	1396	

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24153	9/16/2025 10:30:17 AM	34.4343643	-118.6464162	1409	Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Barely Open;Well Condition:Good
CV-24153	9/25/2025 2:22:57 PM	34.4343775	-118.6463827	1394	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,
CV-24154	9/9/2025 10:40:09 AM	34.4342387	-118.6460898	1412	
CV-24154	9/11/2025 10:57:05 AM	34.4342820	-118.6460572	1384	Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum,Barely Open;Well Condition:Good
CV-24154	9/16/2025 10:35:50 AM	34.4342350	-118.6460972	1400	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Good,Lorentz Pump Installed
CV-24155	9/15/2025 12:48:21 PM	34.4342730	-118.6467213	1399	Valve Adjustment:Increased Flow/Vacuum
CV-24155	9/16/2025 10:40:28 AM	34.4342692	-118.6467133	1400	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good
CV-24156	9/15/2025 10:33:33 AM	34.4340645	-118.6476960	1365	
CV-24156	9/15/2025 10:37:02 AM	34.4340660	-118.6476892	1366	Valve Adjustment:Orifice Plate Changed (See OP Log)
CV-24156	9/22/2025 10:21:52 AM	34.4340722	-118.6477015	1385	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Orifice Plate Changed (See OP Log),Positive Static Press.,Increased Flow/Vacuum
CV-24156	9/22/2025 10:22:35 AM	34.4340618	-118.6476888	1382	
CV-24157	9/15/2025 9:54:30 AM	34.4338140	-118.6473168	1397	Valve Adjustment:Reconnected this Date,Increased Flow/Vacuum
CV-24157	9/16/2025 11:06:04 AM	34.4338063	-118.6473242	1395	Valve Adjustment:Audible Flow;Well Condition:Good
CV-24157	9/30/2025 1:53:22 PM				
CV-24158	9/12/2025 2:20:01 PM	34.4338765	-118.6470535	1400	Valve Comment:RES SEM
CV-24158	9/15/2025 9:16:48 AM	34.4338832	-118.6470373	1403	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum;Well Condition:Good
CV-24158	9/16/2025 1:38:54 PM	34.4338943	-118.6470585	1402	Valve Adjustment:Audible Flow,Barely Open
CV-24159	9/3/2025 1:33:10 PM	34.4337718	-118.6466397	1415	
CV-24159	9/5/2025 2:21:09 PM	34.4338055	-118.6466247	1405	Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum;Well Condition:Good,Lorentz Pump Installed
CV-24159	9/12/2025 2:02:19 PM	34.4337750	-118.6466338	1415	Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum;Well Condition:Fair
CV-24159	9/16/2025 1:48:55 PM	34.4337832	-118.6466405	1416	Valve Adjustment:Audible Flow;Well Condition:Good
CV-24160	9/5/2025 2:26:19 PM	34.4338218	-118.6462432	1415	Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum;Well Condition:Good,Lorentz Pump Installed
CV-24160	9/12/2025 1:53:45 PM	34.4337783	-118.6462618	1420	Valve Adjustment:NSPS/EG CAI,Increased Flow/Vacuum;Well Condition:Good
CV-24160	9/22/2025 9:37:53 AM	34.4338007	-118.6462377	1410	
CV-24161	9/9/2025 10:48:23 AM	34.4338458	-118.6456322	1408	

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24162	9/9/2025 2:26:45 PM	34.4335627	-118.6450992	1391	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Surging Liquid in Header
CV-24163	9/10/2025 2:32:29 PM	34.4334712	-118.6444732	1339	
CV-24164	9/5/2025 11:26:06 AM	34.4334838	-118.6479927	1299	Reconnected this Date,Audible Flow,
CV-24164	9/5/2025 11:29:18 AM	34.4334352	-118.6480232	1352	,,
CV-24164	9/10/2025 10:05:47 AM	34.4334858	-118.6479535	1385	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open;Well Condition:Good
CV-24164	9/10/2025 10:07:47 AM	34.4334953	-118.6479665	1379	Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Decreased Flow/Vacuum;Well Condition:Good
CV-24164	9/15/2025 8:58:33 AM	34.4334850	-118.6479468	1382	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Good
CV-24164	9/15/2025 8:59:23 AM	34.4334827	-118.6479507	1383	Valve Adjustment:NSPS/EG CAI,High Temp;Well Condition:Good
CV-24164	9/18/2025 9:02:45 AM	34.4334895	-118.6479547	1385	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Good
CV-24164	9/18/2025 9:03:31 AM	34.4334868	-118.6479680	1387	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Good
CV-24164	9/19/2025 9:49:51 AM				
CV-24165	9/5/2025 11:13:22 AM	34.4335330	-118.6473037	1312	Reconnected this Date,,
CV-24165	9/16/2025 11:14:45 AM	34.4335150	-118.6472415	1391	Valve Adjustment:Increased Flow/Vacuum;Well Condition:Good
CV-24166	9/3/2025 2:26:52 PM	34.4335908	-118.6468922	1389	
CV-24166	9/12/2025 2:06:12 PM	34.4335983	-118.6468682	1428	Valve Comment:RES SEM;Valve Adjustment:Decreased Flow/Vacuum
CV-24166	9/12/2025 2:12:14 PM	34.4335060	-118.6472233	1407	Valve Comment:RES SEM
CV-24166	9/16/2025 1:46:25 PM	34.4335952	-118.6468862	1411	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Good
CV-24167	9/3/2025 1:36:08 PM	34.4335035	-118.6464855	1403	
CV-24167	9/22/2025 9:46:33 AM	34.4334478	-118.6464705	1402	
CV-24168	9/3/2025 9:12:29 AM	34.4333063	-118.6473183	1408	Well Repairs:Sample Port
CV-24168	9/16/2025 2:14:56 PM	34.4333013	-118.6473065	1397	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Good
CV-24169	9/5/2025 11:19:16 AM	34.4333583	-118.6477690	1299	Reconnected this Date,Audible Flow,
CV-24169	9/5/2025 11:21:39 AM	34.4332810	-118.6476868	1263	,,
CV-24169	9/15/2025 9:05:52 AM	34.4332038	-118.6477018	1387	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAC,Audible Flow,Decreased Flow/Vacuum;Well Condition:Good
CV-24169	9/18/2025 9:06:32 AM	34.4331933	-118.6477035	1401	Valve Adjustment:Audible Flow;Well Condition:Good
CV-24170	9/4/2025 2:20:45 PM	34.4330537	-118.6484643	1329	,,
CV-24170	9/18/2025 10:47:10 AM	34.4331292	-118.6484923	1378	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good
CV-24171	9/3/2025 1:42:09 PM	34.4331812	-118.6466292	1387	
CV-24171	9/18/2025 8:19:42 AM	34.4331562	-118.6466473	1395	Valve Adjustment:Orifice Plate Changed (See OP Log)

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24171	9/18/2025 8:23:27 AM	34.4331540	-118.6466453	1397	Valve Adjustment:Decreased Flow/Vacuum
CV-24172	9/3/2025 1:56:27 PM	34.4329918	-118.6472995	1359	
CV-24172	9/18/2025 9:45:48 AM	34.4329830	-118.6473062	1415	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-24172	9/18/2025 9:59:20 AM	34.4330157	-118.6472875	1408	Valve Adjustment:High O2,Decreased Flow/Vacuum
CV-24173	9/3/2025 2:00:35 PM	34.4328962	-118.6476448	1354	
CV-24173	9/3/2025 2:02:26 PM	34.4329107	-118.6476085	1365	
CV-24173	9/18/2025 10:23:36 AM	34.4328845	-118.6476565	1401	Valve Adjustment:Orifice Plate Changed (See OP Log)
CV-24173	9/18/2025 10:27:53 AM	34.4328883	-118.6476623	1408	Valve Adjustment:Decreased Flow/Vacuum
CV-24174	9/3/2025 2:10:26 PM	34.4327313	-118.6480040	1359	
CV-24174	9/23/2025 10:51:24 AM	34.4327295	-118.6480245	1386	
CV-24175	9/3/2025 2:14:17 PM	34.4326595	-118.6484662	1345	
CV-24175	9/23/2025 11:03:52 AM	34.4326522	-118.6484657	1388	Valve Adjustment:Decreased Flow/Vacuum
CV-24176	9/4/2025 2:01:20 PM	34.4326692	-118.6488957	1358	Audible Flow,,
CV-24176	9/21/2025 12:40:37 PM	34.4326090	-118.6488627	1350	
CV-24176	9/23/2025 8:22:02 AM	34.4325980	-118.6488842	1353	
CV-24177	9/2/2025 11:43:58 AM	34.4322567	-118.6494443	1322	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Good
CV-24177	9/2/2025 11:46:58 AM	34.4322557	-118.6494347	1310	Valve Adjustment:NSPS/EG CAC,Barely Open;Well Condition:Good
CV-24177	9/17/2025 9:41:15 AM	34.4322588	-118.6494512	1326	Valve Adjustment:Decreased Flow/Vacuum
CV-24178	9/4/2025 11:41:55 AM	34.4320505	-118.6487083	1332	,,
CV-24178	9/21/2025 12:54:05 PM	34.4323805	-118.6485903	1352	Valve Adjustment:Decreased Flow/Vacuum;Well Repairs:Sample Port
CV-24179	9/4/2025 1:50:33 PM	34.4321885	-118.6492082	1253	,,
CV-24179	9/17/2025 1:46:51 PM	34.4321058	-118.6492098	1344	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Good
CV-24180	9/4/2025 11:46:05 AM	34.4321330	-118.6489070	1358	Audible Flow,,
CV-24180	9/21/2025 12:25:59 PM	34.4321565	-118.6487895	1340	
CV-24183	9/3/2025 10:24:34 AM				
CV-24183	9/4/2025 11:30:11 AM	34.4322522	-118.6476637	1371	,,
CV-24183	9/10/2025 10:16:07 AM				
CV-24183	9/16/2025 9:47:03 AM				
CV-24183	9/18/2025 1:17:21 PM	34.4323613	-118.6476545	1367	Valve Adjustment:Decreased Flow/Vacuum
CV-24183	9/24/2025 2:02:23 PM				
CV-24184	9/4/2025 11:24:32 AM	34.4325900	-118.6472888	1381	NSPS/EG CAI,High O2,
CV-24184	9/4/2025 11:27:07 AM	34.4324920	-118.6472632	1414	,,
CV-24185	9/4/2025 3:09:41 PM	34.4327123	-118.6470715	1404	,,
CV-24185	9/17/2025 2:29:29 PM	34.4326985	-118.6469357	1361	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good,Lorentz Pump Installed
CV-24186	9/11/2025 8:24:52 AM	34.4328328	-118.6465587	1371	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp,Decreased Flow/Vacuum

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24186	9/11/2025 8:35:51 AM	34.4328357	-118.6465558	1374	Valve Adjustment:NSPS/EG CAI,Orifice Plate Changed (See OP Log),High O2,Increased Flow/Vacuum
CV-24186	9/11/2025 8:38:04 AM	34.4328587	-118.6465665	1381	Valve Adjustment:NSPS/EG CAC
CV-24186	9/18/2025 1:24:22 PM	34.4328315	-118.6465408	1381	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Orifice Plate Changed (See OP Log),Positive Static Press.,Increased Flow/Vacuum
CV-24186	9/18/2025 1:26:38 PM	34.4328443	-118.6465400	1376	Valve Adjustment:Increased Flow/Vacuum
CV-24187	9/8/2025 8:30:08 AM	34.4318733	-118.6494932	1329	,,
CV-24187	9/23/2025 9:46:35 AM	34.4318790	-118.6495813	1306	Valve Adjustment:Decreased Flow/Vacuum
CV-24188	9/2/2025 1:55:34 PM	34.4315308	-118.6501148	1256	Valve Adjustment:Barely Open;Well Condition:Good
CV-24188	9/17/2025 9:53:39 AM	34.4315140	-118.6501133	1273	
CV-24189	9/2/2025 1:52:51 PM	34.4313075	-118.6499867	1261	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Good
CV-24189	9/18/2025 2:21:49 PM	34.4313435	-118.6499967	1273	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Good
CV-24190	9/8/2025 8:35:49 AM	34.4315505	-118.6493768	1316	Increased Flow/Vacuum,Opened Valve 1/2 to 1 Turn,
CV-24190	9/11/2025 1:59:31 PM				
CV-24190	9/23/2025 9:53:23 AM	34.4316048	-118.6494660	1301	Valve Adjustment:Orifice Plate Changed (See OP Log)
CV-24190	9/23/2025 9:55:55 AM	34.4316032	-118.6494923	1325	
CV-24192	9/8/2025 8:53:26 AM	34.4312482	-118.6494028	1325	Increased Flow/Vacuum,Opened Valve 1/2 to 1 Turn,
CV-24192	9/23/2025 10:06:28 AM	34.4313438	-118.6494872	1289	
CV-24193	9/4/2025 8:57:40 AM	34.4314473	-118.6489810	1401	Increased Flow/Vacuum,Opened Valve 1/2 to 1 Turn,
CV-24193	9/17/2025 1:19:27 PM	34.4315208	-118.6490562	1331	Well Condition:Good
CV-24194	9/3/2025 11:45:22 AM				
CV-24194	9/4/2025 8:53:03 AM	34.4316560	-118.6484298	1401	,,
CV-24194	9/17/2025 1:32:21 PM	34.4316887	-118.6484723	1336	Valve Adjustment:Audible Flow,Valve 100% Open,Decreased Flow/Vacuum;Well Condition:Good
CV-24195	9/3/2025 1:39:42 PM				
CV-24195	9/4/2025 9:52:14 AM	34.4318300	-118.6478782	1355	Audible Flow,,
CV-24195	9/10/2025 11:16:09 AM	34.4318380	-118.6478640	1354	Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum;Well Condition:Fair
CV-24195	9/17/2025 1:09:20 PM	34.4318605	-118.6478722	1359	Valve Adjustment:Barely Open;Well Condition:Good
CV-24196	9/4/2025 10:57:58 AM	34.4320088	-118.6470875	1424	Audible Flow,,
CV-24196	9/17/2025 1:04:09 PM	34.4320865	-118.6471733	1362	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Good
CV-24196	9/30/2025 9:22:59 AM				
CV-24197	9/4/2025 11:07:50 AM	34.4323477	-118.6465918	1404	Audible Flow,,
CV-24197	9/21/2025 12:06:54 PM	34.4323740	-118.6465917	1346	Valve Adjustment:Orifice Plate Changed (See OP Log)
CV-24197	9/21/2025 12:10:28 PM	34.4323802	-118.6465845	1350	Valve Adjustment:Decreased Flow/Vacuum
CV-24198	9/3/2025 2:29:42 PM				

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24198	9/4/2025 9:42:09 AM	34.4316187	-118.6476198	1204	Audible Flow,,
CV-24198	9/17/2025 10:08:43 AM	34.4315830	-118.6475913	1346	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Good
CV-24199	9/3/2025 2:39:28 PM				
CV-24199	9/4/2025 9:45:49 AM	34.4318313	-118.6473618	1243	Audible Flow,,
CV-24199	9/10/2025 11:20:46 AM	34.4317612	-118.6473158	1346	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Good
CV-24199	9/17/2025 10:05:04 AM	34.4317978	-118.6473383	1358	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Good
CV-24200	9/4/2025 8:51:20 AM				
CV-24200	9/5/2025 1:37:21 PM	34.4315072	-118.6473685	1243	Audible Flow,,
CV-24200	9/26/2025 9:29:13 AM	34.4314357	-118.6472240	1287	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Good
CV-24200	9/26/2025 1:39:27 PM	34.4314338	-118.6472123	1278	Valve Adjustment:Increased Flow/Vacuum
CV-24201	9/4/2025 9:09:09 AM				
CV-24201	9/5/2025 1:43:49 PM	34.4319025	-118.6466443	1266	,,
CV-24201	9/17/2025 2:02:03 PM	34.4317410	-118.6466328	1288	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good
CV-24202	9/4/2025 9:40:41 AM				
CV-24202	9/5/2025 1:50:54 PM	34.4319525	-118.6462612	1309	,,
CV-24202	9/17/2025 2:09:52 PM	34.4319520	-118.6462692	1298	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good
CV-24203	9/5/2025 8:37:08 AM	34.4315612	-118.6460277	1276	,,
CV-24203	9/24/2025 10:24:27 AM	34.4315042	-118.6460927	1227	Audible Flow,,
CV-24204	9/4/2025 10:05:13 AM				
CV-24204	9/5/2025 8:33:00 AM	34.4314120	-118.6462613	1250	,,
CV-24204	9/24/2025 10:18:11 AM	34.4314550	-118.6462505	1329	Audible Flow,,
CV-24205	9/5/2025 8:29:59 AM	34.4312635	-118.6465447	1211	,,
CV-24205	9/24/2025 10:14:34 AM	34.4312433	-118.6464747	1217	Audible Flow,,
CV-24206	9/5/2025 1:27:54 PM	34.4316833	-118.6469377	1230	,,
CV-24206	9/17/2025 9:05:47 AM				
CV-24206	9/24/2025 11:20:40 AM	34.4315343	-118.6468037	1280	,,
CV-24207	9/3/2025 2:21:04 PM	34.4332742	-118.6469308	1363	Valve Adjustment:Decreased Flow/Vacuum
CV-24207	9/16/2025 1:57:47 PM	34.4332915	-118.6469355	1398	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Good,Lorentz Pump Installed
CV-24207	9/16/2025 1:58:46 PM	34.4332820	-118.6469358	1414	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Good,Lorentz Pump Installed
CV-24208	9/18/2025 9:29:37 AM	34.4319085	-118.6451163	1266	
CV-24209	9/4/2025 10:48:05 AM				
CV-24209	9/17/2025 2:19:12 PM	34.4322187	-118.6456095	1304	Valve Adjustment:NSPS/EG CAC,Audible Flow,Decreased Flow/Vacuum;Well Condition:Fair
CV-24210	9/4/2025 11:11:48 AM				
CV-24210	9/10/2025 1:34:07 PM	34.4326703	-118.6455948	1372	

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24211	9/11/2025 9:16:26 AM	34.4327037	-118.6438533	1261	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24211	9/11/2025 9:17:31 AM	34.4327040	-118.6438680	1258	Valve Adjustment:NSPS/EG CAC
CV-24212	9/11/2025 9:25:25 AM	34.4331673	-118.6430480	1272	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-24212	9/11/2025 9:26:08 AM	34.4331552	-118.6430558	1275	Valve Adjustment:High Temp
CV-24213	9/4/2025 11:07:29 AM	34.4365958	-118.6429677	1324	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Well (Watered In);Well Condition:Fair,Lorentz Pump Installed
CV-24213	9/4/2025 11:09:42 AM	34.4365933	-118.6429692	1326	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum,Surging Liquid in Well (Watered In);Well Condition:Fair
CV-24214	9/2/2025 2:34:46 PM	34.4367302	-118.6434892	1320	
CV-24215	9/26/2025 1:39:06 PM	34.4369262	-118.6448273	1287	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Good
CV-24216	9/25/2025 2:00:14 PM	34.4368175	-118.6423245	1306	Valve Adjustment:Decreased Flow/Vacuum
CV-24217	9/3/2025 9:51:28 AM	34.4359332	-118.6443823	1403	
CV-24217	9/11/2025 2:33:52 PM				
CV-24218	9/2/2025 11:15:28 AM	34.4358142	-118.6458125	1394	Valve Adjustment:Decreased Flow/Vacuum
CV-24218	9/3/2025 10:11:17 AM				
CV-24218	9/5/2025 1:38:20 PM	34.4358148	-118.6458035	1394	Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum;Well Condition:Good
CV-24218	9/10/2025 9:23:52 AM				
CV-24218	9/18/2025 8:11:15 AM				
CV-24218	9/24/2025 1:38:41 PM				
CV-24219	9/2/2025 11:24:26 AM	34.4350818	-118.6462007	1395	Valve Adjustment:Barely Open
CV-24219	9/26/2025 2:25:25 PM	34.4350850	-118.6462193	1401	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-24220	9/10/2025 2:43:22 PM	34.4339523	-118.6439727	1350	Valve Adjustment:High Temp
CV-24222	9/23/2025 11:02:05 AM	34.4335935	-118.6419928	1264	
CV-24223	9/23/2025 11:11:38 AM	34.4334140	-118.6425483	1265	
CV-24224	9/10/2025 2:17:00 PM	34.4331660	-118.6447712	1321	Valve Adjustment:High Temp
CV-24225	9/4/2025 2:53:55 PM	34.4327068	-118.6444447	1288	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Good,Lorentz Pump Installed;Well Repairs:Sample Port
CV-24226	9/11/2025 9:10:56 AM	34.4325108	-118.6442967	1278	Valve Adjustment:Decreased Flow/Vacuum
CV-24227	9/8/2025 8:58:58 AM	34.4310202	-118.6498825	1211	Audible Flow,,
CV-24231	9/15/2025 2:01:40 AM	34.4303883	-118.6498390	1184	Audible Flow,,
CV-24236	9/2/2025 1:31:44 PM	34.4301228	-118.6504818	1212	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good
CV-24237	9/2/2025 1:34:54 PM	34.4306195	-118.6502025	1216	
CV-24243	9/15/2025 9:54:28 AM	34.4287650	-118.6506623	1203	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Barely Open;Well Condition:Good

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-24244	9/4/2025 10:33:00 AM	34.4289965	-118.6513355	1211	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum,Barely Open;Well Condition:Good
CV-24245	9/24/2025 1:46:00 PM	34.4283617	-118.6498960	1214	Audible Flow,,
CV-24246	9/24/2025 1:39:28 PM	34.4286395	-118.6494078	1214	,,
CV-25	9/22/2025 1:33:04 PM	34.4370138	-118.6421065	1262	Valve Adjustment:Audible Flow
CV-2501	9/4/2025 9:26:58 AM	34.4314370	-118.6485527	1401	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,Audible Flow
CV-2501	9/12/2025 8:11:46 AM				
CV-2501	9/17/2025 1:16:02 PM	34.4313440	-118.6484633	1340	Valve Adjustment:Barely Open;Well Condition:Good
CV-2502	9/4/2025 9:07:05 AM	34.4309015	-118.6491408	1306	Audible Flow,,
CV-2502	9/12/2025 8:37:44 AM				
CV-2502	9/17/2025 1:37:06 PM	34.4309032	-118.6491057	1338	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open;Well Condition:Good
CV-2502	9/17/2025 1:40:06 PM	34.4308940	-118.6490988	1333	Valve Adjustment:NSPS/EG CAC,Audible Flow,Increased Flow/Vacuum;Well Condition:Good
CV-2503	9/5/2025 2:10:33 PM	34.4313220	-118.6478060	1250	Audible Flow,,
CV-2503	9/12/2025 8:53:21 AM				
CV-2504	9/15/2025 2:27:48 AM	34.4304603	-118.6489327	1250	Audible Flow,,
CV-2505	9/15/2025 2:51:03 AM	34.4309192	-118.6472957	1329	Audible Flow,Increased Flow/Vacuum,Opened Valve 1/2 to 1 Turn
CV-2506	9/15/2025 2:56:05 AM	34.4305495	-118.6476662	1198	Audible Flow,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-2507	9/15/2025 3:01:27 AM	34.4301200	-118.6482480	1155	Increased Flow/Vacuum,Opened Valve 1/2 to 1 Turn,Audible Flow
CV-2508	9/15/2025 3:05:48 AM	34.4298560	-118.6488270	1214	Audible Flow,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-2509	9/15/2025 3:12:04 AM	34.4293445	-118.6492272	1089	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,Audible Flow
CV-2510	9/24/2025 2:14:02 PM	34.4290958	-118.6497910	1181	Opened Valve 1/2 Turn or Less,Audible Flow,
CV-2511	9/15/2025 2:17:24 AM	34.4295855	-118.6502813	1155	Audible Flow,,
CV-2512	9/15/2025 2:22:20 AM	34.4292667	-118.6505720	1214	Audible Flow,,
CV-2513	9/24/2025 1:31:05 PM	34.4288298	-118.6488008	1129	Audible Flow,,
CV-2514	9/24/2025 1:14:29 PM	34.4296168	-118.6478718	1194	Opened Valve 1/2 Turn or Less,Audible Flow,
CV-2515	9/12/2025 9:12:13 AM				
CV-2515	9/22/2025 2:04:33 PM	34.4378545	-118.6432103	1277	Valve Adjustment:Audible Flow
CV-2516	9/29/2025 1:24:18 PM	34.4374152	-118.6431888	1293	NSPS/EG CAI,Orifice Plate Changed (See OP Log),Positive Static Press.,Increased Flow/Vacuum,,,,
CV-2516	9/30/2025 2:40:00 PM	34.4373858	-118.6431832	1314	Valve Adjustment:NSPS/EG CAI,Orifice Plate Changed (See OP Log),Positive Static Press.,Increased Flow/Vacuum;Well Condition:Good
CV-2524	9/16/2025 2:25:42 PM	34.4347908	-118.6425073	1279	
CV-2529	9/12/2025 10:06:55 AM				
CV-2529	9/23/2025 11:23:06 AM	34.4331310	-118.6423367	1240	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-2530	9/11/2025 11:07:58 AM	34.4328043	-118.6428955	1206	Valve Adjustment:Decreased Flow/Vacuum
CV-2531	9/12/2025 9:47:27 AM				
CV-2531	9/30/2025 2:01:16 PM	34.4325362	-118.6433457	1226	
CV-2532	9/11/2025 11:13:42 AM	34.4322935	-118.6436965	1202	
CV-2532	9/12/2025 9:31:38 AM				
CV-2532	9/12/2025 9:52:08 AM				
CV-2532	9/15/2025 11:20:47 AM	34.4322515	-118.6437195	1202	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum;Well Condition:Good
CV-2540	9/3/2025 9:18:47 AM	34.4332663	-118.6480803	1383	Valve Adjustment:Decreased Flow/Vacuum
CV-2540	9/18/2025 9:09:19 AM	34.4332685	-118.6480880	1387	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Good
CV-2540	9/19/2025 10:16:17 AM				
CV-2541	9/3/2025 1:19:03 PM	34.4332737	-118.6490360	1360	Valve Adjustment:NSPS/EG CAI,Reconnected this Date,High Temp,Decreased Flow/Vacuum
CV-2541	9/3/2025 1:20:05 PM	34.4332775	-118.6490323	1358	Valve Adjustment:High Temp
CV-2541	9/4/2025 10:36:24 AM	34.4332737	-118.6490350	1353	Valve Adjustment:No Flow Measurement,High Temp
CV-2541	9/4/2025 10:37:00 AM				AtmAA
CV-2541	9/4/2025 10:37:00 AM				AtmAA; [User entered 5.91%]
CV-2541	9/11/2025 10:30:46 AM	34.4332743	-118.6490430	1350	Valve Adjustment:High Temp
CV-2541	9/11/2025 10:33:00 AM				AtmAA
CV-2541	9/17/2025 9:36:45 AM	34.4332680	-118.6490277	1364	Valve Adjustment:High Temp
CV-2541	9/24/2025 1:59:39 PM	34.4332852	-118.6490575	1366	Valve Adjustment:No Flow Measurement,High Temp
CV-2542	9/12/2025 2:27:00 PM	34.4337093	-118.6471540	1397	Valve Comment:RES SEM;Valve Adjustment:No Flow Measurement,Reconnected this Date
CV-2542	9/15/2025 2:22:21 PM	34.4337333	-118.6471815	1382	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum;Well Condition:Good
CV-2542	9/16/2025 11:09:30 AM	34.4337057	-118.6471630	1391	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Good;Well Repairs:Sample Port
CV-2542	9/16/2025 1:36:05 PM	34.4337150	-118.6471638	1399	
CV-2542	9/30/2025 2:00:32 PM				
CV-2543-PLR	9/3/2025 1:44:12 PM	34.4338348	-118.6484712	1366	Valve Adjustment:NSPS/EG CAI,Reconnected this Date,High Temp,Decreased Flow/Vacuum
CV-2543-PLR	9/3/2025 1:46:08 PM	34.4338370	-118.6484618	1338	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-2543-PLR	9/4/2025 10:56:23 AM	34.4338330	-118.6484840	1361	Valve Adjustment:No Flow Measurement,High Temp
CV-2543-PLR	9/4/2025 11:00:00 AM				AtmAA
CV-2543-PLR	9/4/2025 11:00:00 AM				AtmAA; [User entered 8.44%]
CV-2543-PLR	9/11/2025 10:07:20 AM	34.4338303	-118.6484643	1361	Valve Adjustment:No Flow Measurement,High Temp,High O2
CV-2543-PLR	9/11/2025 10:08:00 AM				AtmAA
CV-2543-PLR	9/11/2025 10:57:29 AM	34.4338378	-118.6484503	1351	Valve Adjustment:No Flow Measurement,High Temp
CV-2543-PLR	9/17/2025 9:10:37 AM	34.4338250	-118.6484698	1373	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-2543-PLR	9/19/2025 2:07:17 PM				
CV-2543-PLR	9/24/2025 2:21:15 PM	34.4338538	-118.6484742	1360	Valve Adjustment:No Flow Measurement,High Temp,High O2,Decreased Flow/Vacuum,Barely Open
CV-2543-PLR	9/24/2025 2:24:50 PM	34.4338425	-118.6484750	1364	Valve Adjustment:No Flow Measurement,High Temp,High O2,Barely Open
CV-2544	9/15/2025 9:48:46 AM	34.4340392	-118.6472087	1394	Valve Adjustment:Reconnected this Date
CV-2544	9/16/2025 11:01:44 AM	34.4340098	-118.6472168	1391	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Good
CV-2544	9/30/2025 1:35:33 PM				
CV-2545	9/15/2025 1:21:14 PM	34.4340408	-118.6467443	1381	Valve Adjustment:Reconnected this Date,Increased Flow/Vacuum,Valve 100% Open
CV-2545	9/16/2025 10:54:02 AM	34.4340760	-118.6467502	1406	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good
CV-2545	9/30/2025 10:44:50 AM				
CV-2546	9/15/2025 1:02:30 PM	34.4341262	-118.6469765	1382	Valve Adjustment:Reconnected this Date
CV-2546	9/16/2025 10:44:29 AM	34.4341188	-118.6469775	1399	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good
CV-2546	9/30/2025 11:16:04 AM				
CV-2548	9/29/2025 1:59:17 PM	34.4343688	-118.6455738	1381	Valve Adjustment:Reconnected this Date,Decreased Flow/Vacuum
CV-2549	9/29/2025 2:09:51 PM	34.4343860	-118.6452128	1400	Valve Adjustment:Reconnected this Date,Decreased Flow/Vacuum
CV-2552	9/8/2025 1:55:39 PM	34.4348818	-118.6465303	1395	
CV-2553	9/3/2025 10:07:37 AM	34.4341802	-118.6488952	1370	Valve Adjustment:Reconnected this Date,Surging Liquid in Header
CV-2553	9/12/2025 10:46:09 AM				
CV-2553	9/16/2025 2:05:00 PM	34.4341718	-118.6489027	1359	Valve Adjustment:Audible Flow,Surging Liquid in Header
CV-2554	9/4/2025 11:04:58 AM	34.4344775	-118.6482467	1363	Valve Adjustment:No Flow Measurement,High Temp
CV-2554	9/4/2025 11:05:00 AM				AtmAA
CV-2554	9/4/2025 11:05:00 AM				AtmAA; [User entered 2.31%]
CV-2554	9/11/2025 9:44:39 AM	34.4344977	-118.6482400	1367	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2554	9/11/2025 9:45:00 AM				AtmAA
CV-2554	9/12/2025 10:41:06 AM	34.4344615	-118.6482497	1357	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open;Well Condition:Good
CV-2554	9/12/2025 10:42:15 AM	34.4344690	-118.6482685	1367	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open;Well Condition:Good
CV-2554	9/17/2025 8:33:41 AM	34.4344772	-118.6482500	1372	Valve Adjustment:High Temp
CV-2554	9/24/2025 2:35:06 PM	34.4344898	-118.6482542	1379	Valve Adjustment:No Flow Measurement,High Temp
CV-2555	9/9/2025 9:48:29 AM	34.4348122	-118.6477158	1379	
CV-2555	9/12/2025 10:30:57 AM				
CV-2555	9/18/2025 8:53:01 AM	34.4348367	-118.6477017	1383	Valve Adjustment:Audible Flow;Well Condition:Good

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-2556	9/5/2025 6:32:15 AM	34.4351640	-118.6472175	1380	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2556	9/5/2025 6:33:56 AM	34.4351607	-118.6472218	1384	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2556	9/5/2025 6:38:00 AM				AtmAA
CV-2556	9/5/2025 6:38:00 AM				AtmAA; [User entered 12.26%]
CV-2556	9/11/2025 9:06:00 AM				AtmAA
CV-2556	9/11/2025 9:06:04 AM	34.4351697	-118.6472223	1390	Valve Comment:Broken valve cant adjust flow;Valve Adjustment:No Flow Measurement,High Temp
CV-2556	9/17/2025 8:03:13 AM	34.4351585	-118.6472325	1387	Valve Adjustment:High Temp,Surging Liquid in Header
CV-2556	9/19/2025 3:06:07 PM				
CV-2557	9/2/2025 11:32:28 AM	34.4354958	-118.6464700	1401	
CV-2557	9/10/2025 10:24:15 AM	34.4355043	-118.6464750	1401	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAC,Barely Open;Well Condition:Good
CV-2557	9/29/2025 1:11:46 PM	34.4355170	-118.6464353	1405	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2557	9/29/2025 1:12:58 PM	34.4355205	-118.6464682	1395	Valve Adjustment:High Temp,Reduce Sys. Vac. - Flare Down
CV-2558	9/9/2025 12:42:12 PM	34.4353118	-118.6462907	1407	Valve Adjustment:NSPS/EG CAI,Reconnected this Date,High Temp,Decreased Flow/Vacuum;Well Repairs:Sample Port
CV-2558	9/9/2025 12:43:57 PM	34.4353168	-118.6462988	1416	Valve Comment:Well vacuum surging;Valve Adjustment:High Temp
CV-2558	9/18/2025 2:00:23 PM	34.4352953	-118.6462910	1404	Valve Adjustment:No Flow Measurement,High Temp
CV-2558	9/25/2025 10:50:16 AM	34.4352993	-118.6463165	1421	Valve Adjustment:High Temp,Surging Liquid in Header
CV-2558	9/30/2025 2:43:43 PM				
CV-2564	9/3/2025 1:26:22 PM	34.4331190	-118.6487233	1378	Valve Adjustment:Reconnected this Date,Decreased Flow/Vacuum
CV-2564	9/18/2025 9:19:52 AM	34.4331215	-118.6487255	1380	Valve Adjustment:Audible Flow;Well Condition:Good
CV-2564	9/19/2025 10:41:12 AM				
CV-48R	9/9/2025 8:43:50 AM				
CV-48R	9/17/2025 2:32:14 PM	34.4373208	-118.6458570	1314	Valve Adjustment:Audible Flow
CV-55R	9/2/2025 9:48:00 AM				AtmAA
CV-55R	9/2/2025 9:49:28 AM	34.4343788	-118.6427852	1313	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-55R	9/8/2025 9:56:46 AM	34.4343847	-118.6427955	1300	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Good
CV-55R	9/8/2025 10:00:00 AM				AtmAA
CV-55R	9/18/2025 6:41:09 AM	34.4343783	-118.6428070	1309	Valve Adjustment:High Temp
CV-55R	9/22/2025 1:52:58 PM	34.4343877	-118.6427602	1308	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-55R	9/29/2025 8:28:29 AM	34.4343607	-118.6427912	1300	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-56D	9/4/2025 2:32:23 PM	34.4338262	-118.6431357	1309	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
CV-56S	9/4/2025 2:34:59 PM	34.4338025	-118.6431248	1319	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Fair
CV-57R	9/4/2025 2:05:03 PM	34.4343230	-118.6435828	1350	Valve Adjustment:Audible Flow;Well Condition:Fair
CV-79R	9/9/2025 11:28:26 AM				
CV-79R	9/10/2025 2:27:03 PM	34.4332213	-118.6448460	1347	
CV-84S	9/9/2025 10:59:31 AM	34.4336965	-118.6461997	1405	Valve Adjustment:Surging Liquid in Well (Watered In)
CV-94	9/4/2025 1:57:52 PM	34.4348793	-118.6436470	1346	Valve Adjustment:Audible Flow
CV-95	9/4/2025 2:08:11 PM	34.4343053	-118.6436205	1354	Valve Adjustment:Barely Open;Well Condition:Fair
CV-99	9/2/2025 9:35:00 AM				Air Tech Lab
CV-99	9/2/2025 9:35:00 AM				Air Tech Lab; [User entered 0%]
CV-99	9/11/2025 2:34:59 PM	34.4370490	-118.6463447	1322	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum;Well Condition:Fair
D-02	9/26/2025 2:11:24 PM	34.4311510	-118.6442993	1166	
D-03	9/26/2025 2:13:33 PM	34.4311617	-118.6443060	1168	
D-04	9/26/2025 2:16:04 PM	34.4311213	-118.6442720	1172	
D-05	9/30/2025 2:12:56 PM	34.4311680	-118.6443017	1181	
D-09	9/24/2025 1:45:59 PM	34.4301182	-118.6463200	1154	
D-10	9/24/2025 1:54:54 PM	34.4302257	-118.6458202	1160	
FP-001	9/5/2025 1:45:04 PM	34.4366172	-118.6458553	1350	
FP-002	9/5/2025 1:47:56 PM	34.4366253	-118.6462063	1365	
FP-003	9/5/2025 1:59:13 PM	34.4366330	-118.6465308	1365	
FP-005	9/5/2025 2:13:48 PM	34.4364817	-118.6472608	1365	
FP-006	9/10/2025 8:58:02 AM	34.4363788	-118.6476777	1369	Valve Adjustment:Increased Flow/Vacuum,Surging Liquid in Header
FP-008	9/30/2025 1:28:23 PM	34.4363287	-118.6481722	1360	Valve Adjustment:Surging Liquid in Header
FP-009	9/23/2025 10:20:12 AM	34.4366918	-118.6489047	1365	
FP-011	9/4/2025 10:15:17 AM	34.4366380	-118.6492377	1376	
FP-012	9/9/2025 10:12:05 AM	34.4366753	-118.6499143	1377	
FP-012	9/16/2025 10:10:17 AM	34.4366845	-118.6499185	1368	
FP-013	9/4/2025 8:17:32 AM	34.4366040	-118.6502803	1369	
FP-013	9/16/2025 10:18:50 AM	34.4365683	-118.6502878	1386	
FP-014	9/30/2025 1:47:02 PM	34.4365560	-118.6481435	1344	
FP-015	9/10/2025 9:05:52 AM	34.4364672	-118.6479545	1365	
FP-016	9/10/2025 9:02:26 AM	34.4365015	-118.6477180	1364	
FP-017	9/8/2025 8:25:40 AM	34.4344270	-118.6486262	1344	
FP-018	9/23/2025 10:00:57 AM	34.4344813	-118.6489985	1317	
FP-019	9/8/2025 8:34:20 AM	34.4346537	-118.6491303	1335	
FP-020	9/8/2025 9:49:07 AM	34.4350180	-118.6492740	1347	
FP-021	9/8/2025 9:53:20 AM	34.4351480	-118.6495540	1354	
FP-022	9/8/2025 9:57:51 AM	34.4352720	-118.6490883	1353	
FP-023	9/23/2025 9:51:51 AM	34.4357207	-118.6492222	1358	
FP-024	9/8/2025 10:29:20 AM	34.4355235	-118.6477740	1361	
FP-025	9/8/2025 10:32:45 AM	34.4353505	-118.6477552	1363	
FP-026	9/9/2025 9:12:47 AM	34.4351103	-118.6480578	1351	
FP-027	9/9/2025 9:24:02 AM	34.4348087	-118.6482325	1364	

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
FP-028	9/9/2025 9:30:20 AM	34.4347605	-118.6483520	1350	
FP-029	9/8/2025 8:28:58 AM	34.4344103	-118.6489390	1342	
FP-030	9/5/2025 10:45:05 AM	34.4344818	-118.6496627	1343	
FP-031	9/5/2025 10:41:40 AM	34.4347962	-118.6497495	1355	
FP-032	9/5/2025 10:33:41 AM	34.4350765	-118.6498398	1361	
FP-033	9/5/2025 10:27:54 AM	34.4353623	-118.6499445	1368	
FP-034	9/5/2025 10:21:23 AM	34.4356145	-118.6500183	1372	
FP-035	9/5/2025 10:16:28 AM	34.4358477	-118.6501143	1368	
FP-036	9/18/2025 2:08:17 PM	34.4361222	-118.6502212	1374	Valve Comment:OP changed from .40 to .50;Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum
FP-036	9/18/2025 2:11:54 PM	34.4361252	-118.6502140	1382	
FP-037	9/5/2025 9:16:08 AM	34.4362772	-118.6502708	1360	Valve Adjustment:Valve 100% Open
FP-037	9/18/2025 2:01:40 PM	34.4362968	-118.6502917	1380	Valve Comment:Orifice plate changed from .5 to .75. Valve now open to 5percent and not 100percent;Valve Adjustment:Orifice Plate Changed (See OP Log)
FP-038	9/10/2025 8:35:07 AM	34.4348293	-118.6509317	1284	
FP-038	9/16/2025 9:36:00 AM	34.4340732	-118.6497968	1335	Valve Adjustment:Decreased Flow/Vacuum
FP-039	9/16/2025 9:31:44 AM	34.4341990	-118.6498515	1342	Valve Adjustment:Decreased Flow/Vacuum
FP-040	9/10/2025 8:38:58 AM	34.4353108	-118.6510618	1306	
FP-041	9/10/2025 8:43:16 AM	34.4354878	-118.6512990	1291	
FP-042	9/10/2025 9:17:47 AM	34.4333015	-118.6512657	1278	
FP-043	9/10/2025 8:24:49 AM	34.4342477	-118.6508145	1288	
FP-044	9/10/2025 8:28:48 AM	34.4345117	-118.6508017	1288	
FP-046	9/10/2025 8:47:15 AM	34.4365863	-118.6472987	1382	
FP-047	9/5/2025 2:05:11 PM	34.4367295	-118.6469067	1364	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-01 (EXP-01)	9/4/2025 1:05:14 PM	34.4376908	-118.6441797	1236	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum
H-01 (EXP-01)	9/4/2025 1:08:50 PM	34.4376898	-118.6441728	1239	Valve Adjustment:Plugged/Pinched Suspected
H-01 (EXP-01)	9/17/2025 11:09:01 AM	34.4376938	-118.6441767	1250	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
H-01 (EXP-01)	9/17/2025 11:09:42 AM	34.4376958	-118.6441477	1230	Valve Adjustment:NSPS/EG CAC
H-02 (EXP-02)	9/8/2025 10:16:58 AM	34.4376828	-118.6446100	1263	
H-02 (EXP-02)	9/8/2025 10:34:02 AM	34.4377035	-118.6446030	1239	Valve Adjustment:Increased Flow/Vacuum
H-02 (EXP-02)	9/17/2025 1:37:53 PM	34.4377008	-118.6445880	1271	Valve Adjustment:Decreased Flow/Vacuum
H-03 (EXP-03)	9/8/2025 10:22:40 AM	34.4377103	-118.6446362	1250	
H-03 (EXP-03)	9/17/2025 1:41:01 PM	34.4377125	-118.6446165	1255	Valve Adjustment:Audible Flow
H-04 (EXP-04)	9/8/2025 10:29:11 AM	34.4377290	-118.6447080	1247	Valve Adjustment:Decreased Flow/Vacuum
H-04 (EXP-04)	9/16/2025 1:31:30 PM	34.4377405	-118.6447092	1260	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
H-04 (EXP-04)	9/16/2025 1:32:14 PM	34.4377277	-118.6447050	1259	Valve Adjustment:High Temp
H-08 (EXP-08)	9/2/2025 1:28:32 PM	34.4378602	-118.6465335	1281	

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
H-08 (EXP-08)	9/16/2025 1:08:27 PM	34.4378050	-118.6465280	1299	
H-10 (EXP-10)	9/2/2025 1:24:32 PM	34.4374490	-118.6470583	1301	
H-10 (EXP-10)	9/16/2025 1:14:12 PM	34.4374315	-118.6470928	1308	
H-101W	9/4/2025 10:18:02 AM	34.4310863	-118.6505753	1205	Valve Adjustment:Audible Flow;Well Condition:Good
H-102A	9/4/2025 10:06:04 AM	34.4311053	-118.6505677	1190	Valve Adjustment:Audible Flow;Well Condition:Good
H-1401W	9/4/2025 10:09:32 AM	34.4311027	-118.6505820	1204	Valve Adjustment:Audible Flow,Surging Liquid in Header
H-1404C	9/4/2025 11:36:42 AM	34.4324583	-118.6482468	1348	,,
H-1404C	9/23/2025 10:25:54 AM	34.4324227	-118.6483032	1363	Valve Adjustment:Orifice Plate Changed (See OP Log)
H-1404C	9/23/2025 10:28:02 AM	34.4324313	-118.6483012	1353	
H-1405C	9/2/2025 11:14:44 AM	34.4325787	-118.6497125	1325	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Fair
H-1405C	9/17/2025 9:23:59 AM	34.4325892	-118.6497250	1315	Valve Adjustment:Audible Flow;Well Condition:Good
H-1406W	9/2/2025 2:18:09 PM	34.4322060	-118.6507298	1240	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Fair
H-1406W	9/17/2025 10:40:11 AM	34.4321970	-118.6507663	1252	Valve Adjustment:Barely Open
H-1408CR	9/5/2025 2:06:03 PM	34.4315332	-118.6476308	1207	Audible Flow,,
H-1408E	9/3/2025 9:02:29 AM	34.4333877	-118.6471640	1392	
H-1408E	9/16/2025 2:11:47 PM	34.4333515	-118.6471533	1402	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Good
H-1408W	9/2/2025 1:49:59 PM	34.4312155	-118.6499863	1240	Valve Adjustment:Barely Open;Well Condition:Fair
H-1409N	9/4/2025 3:01:47 PM	34.4328820	-118.6469938	1342	,,
H-1409N	9/17/2025 2:33:39 PM	34.4328723	-118.6469465	1380	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Fair
H-1409N	9/17/2025 2:34:42 PM	34.4328613	-118.6469408	1383	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Fair
H-1410S	9/5/2025 8:46:48 AM	34.4309925	-118.6467565	1234	,,
H-1563N	9/8/2025 10:53:11 AM	34.4339503	-118.6498358	1293	Audible Flow,,
H-1563N	9/16/2025 10:40:40 AM	34.4338497	-118.6498125	1334	Valve Adjustment:Decreased Flow/Vacuum
H-1563S	9/2/2025 11:18:36 AM	34.4323872	-118.6496490	1321	Valve Adjustment:Decreased Flow/Vacuum,Barely Open;Well Condition:Good
H-1563S	9/17/2025 9:25:54 AM	34.4323945	-118.6496567	1317	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Good
H-1565E	9/5/2025 11:05:08 AM	34.4336118	-118.6473548	1339	Reconnected this Date,,
H-1565E	9/16/2025 2:18:16 PM	34.4335443	-118.6472212	1398	Valve Adjustment:Decreased Flow/Vacuum
H-1568N	9/3/2025 8:56:33 AM	34.4333352	-118.6471482	1390	
H-1568N	9/16/2025 2:03:44 PM	34.4333530	-118.6471728	1392	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Good
H-1571S	9/10/2025 11:08:36 AM	34.4321360	-118.6452537	1301	Valve Adjustment:Decreased Flow/Vacuum
H-1572N	9/9/2025 2:17:13 PM	34.4337162	-118.6447452	1370	
H-1572S	9/10/2025 10:58:45 AM	34.4321768	-118.6447443	1276	
H-1574N	9/8/2025 2:06:13 PM	34.4326348	-118.6517475	1171	Reduced System Vacuum,,

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
H-1574N	9/17/2025 11:16:09 AM	34.4325082	-118.6517760	1241	Valve Adjustment:Surging Liquid in Header
H-1753S	9/8/2025 10:56:51 AM	34.4340118	-118.6496132	1296	,,
H-1753S	9/16/2025 10:36:21 AM	34.4339147	-118.6495632	1354	
H-1756S	9/2/2025 11:01:13 AM	34.4325582	-118.6502883	1305	Valve Adjustment:Valve 100% Open,Decreased Flow/Vacuum;Well Condition:Fair
H-1756S	9/17/2025 9:08:42 AM	34.4325635	-118.6502848	1294	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Good
H-1757S	9/2/2025 11:10:19 AM	34.4327187	-118.6497610	1329	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good
H-1757S	9/17/2025 9:22:06 AM	34.4327190	-118.6497663	1321	Valve Adjustment:Audible Flow;Well Condition:Fair
H-1760S	9/3/2025 2:05:45 PM	34.4327447	-118.6478813	1357	
H-1760S	9/18/2025 12:03:19 PM	34.4327317	-118.6478758	1387	
H-1762N	9/3/2025 2:24:11 PM	34.4334400	-118.6468217	1389	
H-1762N	9/16/2025 1:52:23 PM	34.4334618	-118.6468707	1411	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Fair
H-1763N	9/9/2025 10:55:22 AM	34.4335087	-118.6461788	1408	
H-1763S	9/10/2025 1:53:38 PM	34.4323748	-118.6460192	1346	
H-1764N	9/10/2025 1:19:03 PM	34.4331550	-118.6456300	1375	
H-1764S	9/10/2025 11:12:59 AM	34.4321505	-118.6454330	1300	Valve Adjustment:Decreased Flow/Vacuum
H-1764S	9/10/2025 1:48:16 PM	34.4323665	-118.6457155	1333	
H-1767N	9/23/2025 11:17:56 AM	34.4326650	-118.6435975	1250	
H-1769N	9/9/2025 10:07:48 AM	34.4370068	-118.6495068	1359	Valve Adjustment:Decreased Flow/Vacuum
H-1769N	9/16/2025 9:45:36 AM	34.4370348	-118.6494947	1380	Valve Adjustment:Increased Flow/Vacuum
H-1770A	9/5/2025 10:12:48 AM	34.4359692	-118.6501102	1376	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
H-1770A	9/16/2025 9:15:11 AM	34.4359777	-118.6501135	1367	
H-1770N	9/9/2025 8:25:00 AM				Air Tech Lab
H-1770N	9/9/2025 8:25:00 AM				Air Tech Lab; [User entered 0.50%]
H-1770N	9/9/2025 10:18:27 AM	34.4367982	-118.6500438	1363	
H-1770N	9/16/2025 9:58:12 AM	34.4368190	-118.6500300	1377	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum
H-1770N	9/16/2025 10:05:15 AM	34.4368115	-118.6500332	1371	Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum
H-1770S	9/2/2025 10:29:06 AM	34.4331268	-118.6501525	1320	Valve Adjustment:Decreased Flow/Vacuum,Barely Open;Well Condition:Good
H-1770S	9/17/2025 8:51:23 AM	34.4331217	-118.6501583	1330	Valve Adjustment:Decreased Flow/Vacuum,Barely Open;Well Condition:Good
H-1771A	9/2/2025 1:48:09 PM	34.4363302	-118.6463932	1369	
H-1771B	9/2/2025 11:35:50 AM	34.4355312	-118.6466352	1394	
H-1771B	9/5/2025 1:48:42 PM	34.4355560	-118.6466352	1403	Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum;Well Condition:Fair
H-1774N	9/4/2025 7:58:57 AM	34.4367335	-118.6508117	1356	
H-1774N	9/16/2025 10:30:15 AM	34.4367318	-118.6507933	1366	Valve Adjustment:Increased Flow/Vacuum
H-1801S	9/11/2025 8:38:13 AM	34.4337657	-118.6440833	1346	

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
H-1802S	9/9/2025 2:20:40 PM	34.4335548	-118.6447398	1360	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
H-1802S	9/9/2025 2:21:52 PM	34.4335618	-118.6447380	1360	Valve Adjustment:NSPS/EG CAC,Increased Flow/Vacuum
H-1803N	9/4/2025 8:13:49 AM	34.4370367	-118.6485960	1354	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open;Well Comment:Active PLR
H-1803N	9/4/2025 8:15:00 AM				AtmAA
H-1803N	9/4/2025 8:15:00 AM				AtmAA; [User entered 12.22%]
H-1803N	9/9/2025 9:29:00 AM				AtmAA
H-1803N	9/9/2025 9:29:20 AM	34.4370262	-118.6485847	1358	
H-1803N	9/17/2025 1:37:14 PM	34.4370312	-118.6485860	1363	Valve Adjustment:No Flow Measurement,High Temp
H-1803N	9/22/2025 9:13:03 AM	34.4370117	-118.6485935	1354	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open;Well Comment:ACTIVE PLR
H-1803N	9/25/2025 11:24:34 AM	34.4370433	-118.6485887	1355	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:ACTIVE PLR
H-1803N	9/29/2025 1:53:02 PM	34.4370157	-118.6485582	1339	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:Active PLR
H-1804B	9/9/2025 10:44:31 AM	34.4342300	-118.6456487	1380	Valve Adjustment:Decreased Flow/Vacuum
H-1804N	9/2/2025 1:56:19 PM	34.4363700	-118.6456910	1355	
H-1804S	9/10/2025 1:24:21 PM	34.4330793	-118.6456770	1376	Valve Adjustment:Decreased Flow/Vacuum
H-1805A	9/3/2025 10:39:10 AM	34.4351542	-118.6450717	1384	
H-1805B	9/9/2025 2:37:46 PM	34.4337128	-118.6451480	1388	
H-1805S	9/10/2025 1:41:01 PM	34.4329260	-118.6451660	1348	
H-1806A	9/3/2025 10:01:21 AM	34.4354600	-118.6442030	1382	Valve Adjustment:Increased Flow/Vacuum
H-1806A	9/11/2025 1:57:13 PM	34.4354612	-118.6442295	1378	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum;Well Condition:Fair;Well Repairs:Valve
H-1806B	9/9/2025 2:13:40 PM	34.4339080	-118.6444485	1374	
H-1806N	9/2/2025 2:20:16 PM	34.4363647	-118.6442837	1365	
H-1806S	9/4/2025 2:58:47 PM	34.4328730	-118.6444643	1284	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum,Barely Open
H-1807A	9/4/2025 1:51:37 PM	34.4353327	-118.6436320	1354	Valve Adjustment:Audible Flow;Well Condition:Fair
H-1807N	9/26/2025 1:13:28 PM	34.4364185	-118.6435102	1349	Valve Adjustment:NSPS/EG CAI,Decreased Flow/Vacuum,Barely Open
H-1807N	9/26/2025 1:14:17 PM	34.4364272	-118.6435162	1352	Valve Adjustment:High O2,Barely Open
H-1807N	9/26/2025 2:00:16 PM	34.4364412	-118.6435153	1341	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
H-1807N	9/26/2025 2:08:42 PM	34.4364468	-118.6435128	1341	Valve Adjustment:NSPS/EG CAI,High O2,Surging Liquid in Header

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
H-1807S	9/4/2025 2:16:55 PM	34.4338085	-118.6434715	1317	Valve Adjustment:Audible Flow;Well Condition:Good
H-1952S	9/15/2025 10:24:17 AM	34.4338268	-118.6475975	1373	
H-1952S	9/16/2025 1:38:39 PM	34.4338147	-118.6476173	1390	Valve Adjustment:Decreased Flow/Vacuum
H-1953N	9/5/2025 2:21:22 PM	34.4364540	-118.6469305	1382	
H-1953N	9/29/2025 2:24:25 PM	34.4365463	-118.6470557	1391	NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
H-1953N	9/29/2025 2:27:26 PM	34.4365218	-118.6468790	1322	NSPS/EG CAC,,
H-1954C	9/2/2025 11:28:47 AM	34.4353837	-118.6460365	1411	
H-1955C	9/3/2025 10:41:57 AM	34.4350483	-118.6453647	1384	
H-1955C	9/11/2025 10:39:37 AM	34.4350487	-118.6454022	1389	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum;Well Condition:Fair
H-1955N	9/2/2025 2:05:36 PM	34.4364648	-118.6454932	1355	
H-1956B	9/11/2025 1:05:43 PM	34.4342837	-118.6447590	1390	
H-1956N	9/2/2025 2:13:34 PM	34.4364603	-118.6448662	1346	
H-1956S	9/10/2025 2:22:07 PM	34.4331637	-118.6448797	1350	
H-1957B	9/9/2025 1:57:55 PM	34.4345552	-118.6441005	1382	
H-1957N	9/2/2025 2:23:01 PM	34.4364212	-118.6441712	1365	
H-1957S	9/11/2025 8:41:14 AM	34.4337515	-118.6441110	1335	
H-1958C	9/4/2025 1:49:18 PM	34.4353718	-118.6434830	1340	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Good
H-1958N	9/26/2025 1:17:27 PM	34.4364425	-118.6435200	1342	
H-1958N	9/26/2025 2:11:07 PM	34.4364483	-118.6435213	1346	Valve Adjustment:Audible Flow,Barely Open,Surging Liquid in Header
H-1958S	9/4/2025 2:14:33 PM	34.4340042	-118.6433312	1332	Valve Adjustment:Audible Flow;Well Condition:Good
H-1962N	9/4/2025 8:20:52 AM	34.4366668	-118.6501490	1387	
H-1962N	9/16/2025 10:15:27 AM	34.4366672	-118.6501152	1374	Valve Adjustment:Decreased Flow/Vacuum
H-1963N	9/4/2025 8:28:41 AM	34.4369330	-118.6495437	1373	Valve Adjustment:Decreased Flow/Vacuum
H-1963N	9/16/2025 9:50:06 AM	34.4369325	-118.6495262	1369	Valve Adjustment:Decreased Flow/Vacuum
H-1966N	9/4/2025 8:09:16 AM	34.4365833	-118.6508108	1346	Valve Adjustment:Decreased Flow/Vacuum
H-1966N	9/4/2025 8:13:18 AM	34.4365582	-118.6508412	1368	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum
H-1966N	9/16/2025 10:37:50 AM	34.4365510	-118.6507962	1354	
H-1967E	9/24/2025 1:59:15 PM	34.4302270	-118.6458362	1161	
H-1967W	9/2/2025 1:05:01 PM	34.4299103	-118.6507835	1185	Valve Adjustment:Audible Flow;Well Condition:Good
H-2050E	9/25/2025 10:10:00 AM	34.4291153	-118.6474618	1111	Valve Adjustment:Orifice Plate Changed (See OP Log)
H-2050W	9/15/2025 3:15:02 AM	34.4290992	-118.6491442	1191	Audible Flow,,
H-2051W	9/2/2025 1:00:27 PM	34.4299087	-118.6507942	1182	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good
H-2053E	9/24/2025 2:06:57 PM	34.4302460	-118.6458967	1168	
H-2053W	9/4/2025 10:12:14 AM	34.4310912	-118.6505757	1199	Valve Adjustment:Audible Flow;Well Condition:Good
H-2055E	9/5/2025 1:46:46 PM	34.4318487	-118.6467582	1207	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
H-2055E	9/17/2025 2:05:00 PM	34.4317773	-118.6466048	1286	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Fair
H-2056B	9/24/2025 1:10:25 PM	34.4298523	-118.6476458	1030	,,
H-2056W	9/2/2025 1:09:23 PM	34.4299108	-118.6507848	1183	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Good
H-2057E	9/24/2025 2:02:27 PM	34.4302020	-118.6458157	1143	
H-2057W	9/4/2025 10:23:26 AM	34.4306548	-118.6506458	1205	Valve Adjustment:Audible Flow;Well Condition:Good
H-2058E	9/24/2025 1:49:04 PM	34.4300625	-118.6464432	1146	
H-2058W	9/2/2025 1:12:00 PM	34.4299217	-118.6507863	1179	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good
H-2059E	9/24/2025 2:13:04 PM	34.4306735	-118.6462933	1193	
H-2059W	9/2/2025 1:42:22 PM	34.4310805	-118.6502112	1219	Valve Adjustment:Audible Flow
H-2160E	9/24/2025 10:51:59 AM	34.4303257	-118.6466525	1230	NSPS/EG CAI,Decom Well (Temporary),High O2,Reduced System Vacuum,,,,
H-2160E	9/24/2025 10:54:32 AM	34.4303598	-118.6467020	1257	,,
H-2161E	9/24/2025 10:43:45 AM	34.4308047	-118.6465072	1125	Audible Flow,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-2161W	9/2/2025 1:39:12 PM	34.4309410	-118.6502055	1222	Valve Adjustment:Audible Flow;Well Condition:Good
H-2163C	9/4/2025 9:18:37 AM	34.4311720	-118.6486758	1276	,,
H-2163C	9/17/2025 10:14:10 AM	34.4310860	-118.6486803	1326	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Good
H-2163W	9/2/2025 1:46:59 PM	34.4311765	-118.6498692	1261	Valve Adjustment:Audible Flow;Well Condition:Good
H-2164A	9/4/2025 8:46:43 AM	34.4317173	-118.6487007	1368	,,
H-2164A	9/17/2025 1:26:34 PM	34.4317558	-118.6486850	1344	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum,Barely Open;Well Condition:Good
H-2164E	9/5/2025 1:54:04 PM	34.4319972	-118.6460658	1158	,,
H-2164E	9/17/2025 2:12:25 PM	34.4319137	-118.6460738	1292	Valve Adjustment:Audible Flow;Well Condition:Fair
H-2165E	9/18/2025 9:22:00 AM	34.4318935	-118.6451357	1265	Valve Adjustment:Decreased Flow/Vacuum
H-2165W	9/2/2025 2:08:31 PM	34.4321553	-118.6504083	1256	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Good
H-2165W	9/8/2025 8:50:00 AM				Air Tech Lab; [User entered 0.94%]
H-2165W	9/8/2025 8:50:00 AM				Air Tech Lab
H-2165W	9/17/2025 10:28:09 AM	34.4321462	-118.6504052	1270	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
H-2165W	9/17/2025 10:29:10 AM	34.4321467	-118.6504277	1273	Valve Adjustment:High Temp
H-2166C	9/3/2025 10:45:07 AM	34.4356260	-118.6448303	1366	
H-2166E	9/9/2025 1:40:34 PM	34.4356380	-118.6438513	1379	
H-2167A	9/4/2025 1:40:32 PM	34.4349783	-118.6463647	1393	Valve Adjustment:Orifice Plate Changed (See OP Log)
H-2167A	9/4/2025 1:44:14 PM	34.4349697	-118.6463413	1399	Valve Adjustment:Decreased Flow/Vacuum
H-2167E	9/4/2025 1:55:32 PM	34.4349278	-118.6438353	1377	Valve Adjustment:Audible Flow;Well Condition:Fair
H-2168C	9/11/2025 1:18:33 PM	34.4344323	-118.6448103	1388	Valve Adjustment:Valve 100% Open,Plugged/Pinched Suspected
H-2168E	9/9/2025 2:02:29 PM	34.4345237	-118.6438997	1374	

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
H-2169C	9/9/2025 2:41:52 PM	34.4340427	-118.6450402	1386	
H-2169E	9/9/2025 2:08:32 PM	34.4342358	-118.6442052	1383	
H-2170N	9/25/2025 1:48:51 PM	34.4357813	-118.6414433	1275	
H-2170S	9/11/2025 10:20:40 AM	34.4335762	-118.6414965	1249	Valve Adjustment:Decreased Flow/Vacuum
H-2171A	9/26/2025 1:23:26 PM	34.4373963	-118.6425372	1250	
H-2171B	9/22/2025 1:13:39 PM	34.4364980	-118.6416662	1249	Valve Adjustment:Audible Flow
H-2171N	9/22/2025 2:09:45 PM	34.4379613	-118.6432920	1263	Valve Adjustment:Decreased Flow/Vacuum
H-2171S	9/25/2025 1:45:48 PM	34.4357807	-118.6414493	1274	
H-2272W	9/8/2025 9:12:55 AM	34.4316647	-118.6497893	1276	Audible Flow,,
H-2272W	9/17/2025 9:44:23 AM	34.4317352	-118.6497568	1277	
H-2273W	9/2/2025 11:28:47 AM	34.4321495	-118.6499748	1308	
H-2273W	9/10/2025 10:25:00 AM				Air Tech Lab
H-2273W	9/10/2025 10:25:00 AM				Air Tech Lab; [User entered 1.5%]
H-2273W	9/17/2025 9:31:19 AM	34.4321490	-118.6499560	1303	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Fair
H-2274B	9/4/2025 11:11:50 AM	34.4324353	-118.6465407	1394	,,
H-2274B	9/21/2025 12:14:18 PM	34.4325898	-118.6466660	1346	
H-2274W	9/2/2025 10:50:19 AM	34.4327785	-118.6503427	1303	Valve Adjustment:Barely Open;Well Condition:Good
H-2274W	9/17/2025 9:06:21 AM	34.4327792	-118.6503530	1312	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good
H-2275E	9/10/2025 1:57:24 PM	34.4323962	-118.6462028	1342	
H-2275W	9/2/2025 11:37:01 AM	34.4322297	-118.6493672	1329	Valve Adjustment:Decreased Flow/Vacuum
H-2275W	9/17/2025 9:37:22 AM	34.4322333	-118.6493867	1326	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Fair
H-2276A	9/4/2025 2:35:58 PM	34.4330430	-118.6484812	1302	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,
H-2276A	9/18/2025 10:41:48 AM	34.4328622	-118.6482623	1379	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Fair;Well Repairs:Sample Port
H-2276B	9/4/2025 3:06:24 PM	34.4328953	-118.6469077	1398	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,
H-2276B	9/17/2025 2:37:23 PM	34.4328818	-118.6469070	1382	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Fair
H-2276E	9/10/2025 1:38:22 PM	34.4327693	-118.6452943	1380	
H-2276W	9/2/2025 11:07:22 AM	34.4326628	-118.6499562	1320	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum,Barely Open;Well Condition:Fair
H-2276W	9/17/2025 9:19:50 AM	34.4326668	-118.6499692	1314	Valve Adjustment:Audible Flow;Well Condition:Good
H-2277A	9/4/2025 2:25:54 PM	34.4331273	-118.6488398	1335	,,
H-2277A	9/18/2025 9:22:51 AM	34.4330225	-118.6487177	1379	Valve Adjustment:Decreased Flow/Vacuum;Well Repairs:Valve
H-2277B	9/3/2025 1:48:32 PM	34.4330667	-118.6469018	1343	
H-2277B	9/18/2025 8:40:52 AM	34.4330573	-118.6469045	1383	
H-23 (EXP-23)	9/22/2025 1:27:26 PM	34.4370143	-118.6420968	1273	Valve Comment:Valve is really sensitive to adjustments;Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
H-23 (EXP-23)	9/22/2025 1:28:11 PM	34.4370050	-118.6421000	1268	

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
H-2301E	9/26/2025 10:18:59 AM	34.4270797	-118.6479728	1024	Valve Adjustment:Audible Flow;Well Condition:Good
H-2301E	9/28/2025 9:41:01 AM	34.4270623	-118.6480065	1017	Valve Adjustment:Orifice Plate Changed (See OP Log)
H-2302C	9/26/2025 10:05:25 AM	34.4283808	-118.6490113	1140	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Good
H-2302E	9/26/2025 10:24:06 AM	34.4275247	-118.6472235	1057	
H-2303E	9/29/2025 12:23:25 PM	34.4278812	-118.6471978	1102	Valve Adjustment:Plugged/Pinched Suspected
H-2303N	9/24/2025 1:26:15 PM	34.4290183	-118.6483473	1207	Audible Flow,,
H-2303N	9/26/2025 10:30:36 AM	34.4278960	-118.6472012	1089	Valve Adjustment:Audible Flow;Well Condition:Good
H-2304S	9/25/2025 9:34:44 AM	34.4273937	-118.6488942	1088	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open
H-2304S	9/25/2025 9:36:47 AM	34.4273907	-118.6489127	1083	Valve Adjustment:High Temp,Barely Open
H-2304S	9/28/2025 10:01:06 AM	34.4273867	-118.6488823	1082	Valve Adjustment:NSPS/EG CAC,Orifice Plate Changed (See OP Log),Positive Static Press.
H-2304S	9/28/2025 10:02:10 AM	34.4273977	-118.6488670	1074	
H-2305N	9/15/2025 10:55:37 AM	34.4289968	-118.6486178	1149	Valve Comment:RES SEM;Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good
H-2305S	9/25/2025 9:23:38 AM	34.4274497	-118.6484980	1068	Valve Adjustment:Decreased Flow/Vacuum
H-2306N	9/25/2025 9:09:05 AM	34.4294095	-118.6475747	1136	
H-2306S	9/25/2025 10:02:00 AM	34.4286767	-118.6481070	1105	Valve Adjustment:High O2,Surging Liquid in Well (Watered In)
H-2309N	9/4/2025 9:10:43 AM	34.4307888	-118.6487707	1250	,,
H-2309S	9/25/2025 9:44:15 AM	34.4280548	-118.6489068	1115	Valve Adjustment:Decreased Flow/Vacuum
H-2402N	9/24/2025 2:19:19 PM	34.4290708	-118.6502150	1201	,,
H-2402S	9/26/2025 9:54:58 AM	34.4287663	-118.6504890	1203	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good
H-2403N	9/24/2025 2:26:03 PM	34.4292835	-118.6501397	1243	Audible Flow,,
H-2403S	9/15/2025 9:46:37 AM	34.4287603	-118.6498852	1179	Valve Comment:RES SEM;Valve Adjustment:Reconnected this Date,Increased Flow/Vacuum,Barely Open;Well Condition:Good
H-2404N	9/24/2025 2:35:49 PM	34.4293183	-118.6494592	1306	,,
H-2404S	9/24/2025 1:35:09 PM	34.4286495	-118.6491667	1224	Opened Valve 1/2 to 1 Turn,,
H-2405N	9/15/2025 2:07:22 AM	34.4300098	-118.6495552	1237	,,
H-29	9/25/2025 11:06:12 AM	34.4354360	-118.6417912	1274	
H-31	9/26/2025 1:18:15 PM	34.4378292	-118.6429692	1249	Valve Adjustment:Audible Flow
H-72	9/26/2025 1:36:30 PM	34.4369085	-118.6448370	1295	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Good
H-74	9/22/2025 2:35:19 PM	34.4371703	-118.6433198	1302	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
H-79	9/4/2025 2:39:10 PM	34.4339380	-118.6427688	1308	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Fair
H-79	9/4/2025 2:40:50 PM	34.4339305	-118.6427892	1315	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
P-02R	9/9/2025 2:05:59 PM	34.4297215	-118.6439110	1174	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
P-02R	9/9/2025 2:06:41 PM	34.4297375	-118.6439108	1184	Valve Adjustment:NSPS/EG CAC
P-03R	9/9/2025 1:58:57 PM	34.4298442	-118.6441865	1172	Valve Adjustment:Barely Open
P-04	9/9/2025 1:54:13 PM	34.4294887	-118.6445318	1172	Valve Adjustment:Barely Open
P-05	9/10/2025 1:07:01 PM	34.4291877	-118.6447468	1162	Valve Adjustment:Barely Open
P-06R	9/9/2025 2:32:42 PM	34.4288520	-118.6450403	1139	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
P-07R	9/23/2025 2:25:44 PM	34.4298273	-118.6433440	1135	,,
P-08R	9/9/2025 2:11:47 PM	34.4294105	-118.6437362	1170	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
P-09	9/9/2025 2:20:26 PM	34.4289890	-118.6442327	1163	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
P-10	9/9/2025 10:10:17 AM	34.4287058	-118.6446470	1148	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
P-11	9/9/2025 10:20:54 AM	34.4285145	-118.6449718	1134	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
P-12	9/9/2025 10:47:34 AM	34.4288535	-118.6456198	1121	Valve Adjustment:Audible Flow
P-13	9/9/2025 10:42:54 AM	34.4284770	-118.6458135	1121	Valve Adjustment:Audible Flow
P-14	9/9/2025 10:33:15 AM	34.4280350	-118.6460507	1120	Valve Adjustment:Barely Open
P-15R	9/10/2025 10:45:32 AM	34.4277640	-118.6459207	1122	Valve Adjustment:Audible Flow
P-16	9/23/2025 9:39:29 AM	34.4275055	-118.6455878	1125	Audible Flow,,
P-17	9/10/2025 1:19:43 PM	34.4273895	-118.6453028	1117	Valve Adjustment:Decreased Flow/Vacuum
P-18RD	9/10/2025 11:25:13 AM	34.4270978	-118.6450222	1110	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
P-18RS	9/10/2025 11:13:40 AM	34.4271060	-118.6450260	1091	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
P-19	9/23/2025 10:10:10 AM	34.4262982	-118.6443910	1224	,,
P-20R	9/10/2025 11:07:12 AM	34.4268312	-118.6448552	1097	Valve Adjustment:Audible Flow
P-21	9/10/2025 11:02:39 AM	34.4264787	-118.6448140	1114	Valve Adjustment:Decreased Flow/Vacuum
P-21RD	9/23/2025 10:17:50 AM	34.4265757	-118.6447557	1066	,,
P-21RS	9/23/2025 10:13:04 AM	34.4263798	-118.6444342	1129	,,
P-22RD	9/23/2025 10:54:08 AM	34.4269232	-118.6437978	1207	,,
P-22RS	9/23/2025 10:52:10 AM	34.4269535	-118.6437752	1191	,,
P-23	9/10/2025 10:55:26 AM	34.4261178	-118.6447255	1132	Valve Adjustment:Decreased Flow/Vacuum
P-24	9/10/2025 1:30:15 PM	34.4260690	-118.6442723	1111	Valve Adjustment:Audible Flow
P-26	9/10/2025 1:48:18 PM	34.4265192	-118.6432008	1139	Valve Comment:System vacuum is -8.7;Valve Adjustment:Audible Flow
P-27	9/11/2025 1:32:24 PM	34.4268315	-118.6427892	1142	Valve Adjustment:Decreased Flow/Vacuum
P-28	9/11/2025 1:38:30 PM	34.4270518	-118.6422867	1141	Valve Adjustment:Audible Flow
P-29R	9/11/2025 1:45:33 PM	34.4271748	-118.6418435	1156	Valve Adjustment:Decreased Flow/Vacuum
P-30R	9/11/2025 1:50:22 PM	34.4274040	-118.6416060	1157	Valve Adjustment:Audible Flow
P-32R1	9/12/2025 1:42:57 PM	34.4282242	-118.6410432	1188	Valve Comment:Cannot make adjustments due to broken valve;Valve Adjustment:Audible Flow
P-32R1	9/15/2025 11:26:51 AM	34.4282118	-118.6410555	1180	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum,Barely Open;Well Condition:Good;Well Repairs:Flex Hose,Valve,Sample Port
P-32R1	9/15/2025 11:28:36 AM	34.4282147	-118.6410557	1187	
P-32R2	9/12/2025 1:48:49 PM	34.4284375	-118.6409470	1181	Valve Adjustment:Decreased Flow/Vacuum
P-33	9/12/2025 1:59:27 PM	34.4288187	-118.6407920	1210	Valve Adjustment:Audible Flow

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
P-36	9/12/2025 2:24:21 PM	34.4301767	-118.6400327	1218	Valve Adjustment:Decreased Flow/Vacuum
P-37	9/12/2025 2:35:09 PM	34.4304803	-118.6403635	1230	Valve Adjustment:Decreased Flow/Vacuum
P-38RD	9/15/2025 2:12:37 PM	34.4299628	-118.6406538	1231	Valve Adjustment:Audible Flow
P-38RS	9/15/2025 2:10:06 PM	34.4299663	-118.6406490	1235	Valve Adjustment:Audible Flow
P-39	9/15/2025 2:17:59 PM	34.4294757	-118.6409928	1223	Valve Adjustment:Audible Flow
P-41	9/15/2025 2:24:21 PM	34.4288585	-118.6413945	1228	Valve Adjustment:Audible Flow
P-42R	9/16/2025 11:13:42 AM	34.4284127	-118.6416753	1215	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
P-43	9/16/2025 11:07:52 AM	34.4282563	-118.6418213	1229	Valve Adjustment:Decreased Flow/Vacuum
P-44RD	9/16/2025 11:03:01 AM	34.4281238	-118.6419387	1219	Valve Adjustment:Audible Flow
P-44RS	9/16/2025 11:01:00 AM	34.4281178	-118.6419457	1224	Valve Adjustment:Audible Flow
P-45RD	9/16/2025 11:32:08 AM	34.4277095	-118.6424628	1219	Valve Adjustment:Audible Flow
P-45RS	9/16/2025 11:29:26 AM	34.4277193	-118.6424737	1214	Valve Adjustment:Decreased Flow/Vacuum
P-46RD	9/18/2025 12:33:45 PM	34.4276712	-118.6426252	1220	Valve Adjustment:Audible Flow
P-46RS	9/18/2025 12:31:10 PM	34.4276573	-118.6426375	1226	Valve Adjustment:Audible Flow
P-47	9/23/2025 10:47:12 AM	34.4274393	-118.6433033	1247	,,
P-48	9/23/2025 11:09:02 AM	34.4275873	-118.6435937	1194	Barely Open,,
P-49RD	9/23/2025 11:21:23 AM	34.4279850	-118.6439057	1191	,,
P-49RS	9/23/2025 11:18:57 AM	34.4279757	-118.6438947	1211	,,
P-52	9/23/2025 1:48:00 PM	34.4287463	-118.6432690	1237	,,
P-53	9/23/2025 1:51:50 PM	34.4290743	-118.6430642	1214	,,
P-54	9/23/2025 2:00:58 PM	34.4297002	-118.6427295	1227	,,
P-55	9/23/2025 2:03:19 PM	34.4297263	-118.6427322	1204	,,
P-56	9/23/2025 2:10:00 PM	34.4301657	-118.6429350	1227	,,
P-57	9/23/2025 2:07:49 PM	34.4301583	-118.6428703	1201	,,
P-60R	9/18/2025 12:57:02 PM	34.4307942	-118.6415568	1266	Valve Adjustment:Audible Flow,Surging Liquid in Header
P-61	9/18/2025 12:50:37 PM	34.4311377	-118.6411575	1267	Valve Adjustment:Surging Liquid in Header
P-65	9/18/2025 12:44:48 PM	34.4303917	-118.6409407	1254	Valve Adjustment:Surging Liquid in Header
P-71	9/23/2025 11:29:47 AM	34.4278242	-118.6432977	1237	,,
P-75	9/23/2025 2:18:03 PM	34.4303510	-118.6415605	1270	,,
P-76	9/23/2025 10:33:21 AM	34.4300773	-118.6403213	1319	,,
P-79	9/23/2025 9:43:35 AM	34.4270617	-118.6460422	1043	,,
SC-2000E	9/24/2025 10:46:30 AM	34.4305962	-118.6468403	1270	,,
SC-2501E	9/3/2025 9:30:42 AM	34.4366942	-118.6479105	1353	Valve Adjustment:High Temp
SC-2501E	9/3/2025 9:45:00 AM				AtmAA
SC-2501E	9/3/2025 9:45:00 AM				AtmAA; [User entered 9.38%]
SC-2501E	9/5/2025 8:09:33 AM	34.4367163	-118.6479290	1345	Valve Adjustment:High Temp,High O2;Well Comment:Flexhose lost its structure;Well Condition:Poor
SC-2501E	9/5/2025 8:13:54 AM	34.4368172	-118.6485478	1351	Valve Adjustment:High Temp
SC-2501E	9/9/2025 9:14:26 AM	34.4367033	-118.6479270	1346	Valve Adjustment:High Temp
SC-2501E	9/9/2025 9:15:00 AM				AtmAA
SC-2501E	9/15/2025 9:20:39 AM	34.4366872	-118.6479090	1349	Valve Adjustment:High Temp,High O2,Barely Open
SC-2501E	9/15/2025 9:22:00 AM				AtmAA

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
SC-2501E	9/15/2025 9:22:26 AM	34.4366947	-118.6479058	1347	Valve Adjustment:High Temp,High O2,Barely Open
SC-2501E	9/22/2025 8:49:03 AM	34.4366907	-118.6479167	1354	Valve Adjustment:High Temp,High O2
SC-2501E	9/29/2025 11:44:34 AM	34.4366953	-118.6479407	1360	Valve Adjustment:High Temp,High O2
SC-2501W	9/3/2025 9:44:19 AM	34.4368015	-118.6485298	1366	Valve Adjustment:High Temp,Barely Open
SC-2501W	9/3/2025 9:45:00 AM				AtmAA
SC-2501W	9/3/2025 9:45:00 AM				AtmAA; [User entered 18.04%]
SC-2501W	9/9/2025 9:40:33 AM	34.4367800	-118.6485532	1359	Valve Adjustment:High Temp,Barely Open
SC-2501W	9/9/2025 9:42:00 AM				AtmAA
SC-2501W	9/15/2025 10:06:49 AM	34.4367922	-118.6485448	1359	Valve Comment:HERO TOX ON;Valve Adjustment:High Temp
SC-2501W	9/15/2025 10:08:00 AM				AtmAA
SC-2501W	9/22/2025 9:20:28 AM	34.4368050	-118.6485313	1377	Valve Adjustment:High Temp
SC-2501W	9/29/2025 2:05:42 PM	34.4368107	-118.6485375	1354	Valve Adjustment:High Temp,Barely Open
SW-10	9/25/2025 1:59:04 PM	34.4370378	-118.6503767	1339	
SW-115	9/15/2025 1:25:47 PM	34.4348377	-118.6412098	1202	Valve Adjustment:Audible Flow;Well Condition:Fair;Well Repairs:Sample Port
SW-1445	9/4/2025 9:57:23 AM	34.4324930	-118.6519968	1202	Valve Adjustment:Audible Flow
SW-1445	9/19/2025 10:26:13 AM	34.4325035	-118.6519817	1206	Valve Adjustment:Audible Flow
SW-1455	9/4/2025 9:51:46 AM	34.4323952	-118.6518797	1214	Valve Adjustment:Audible Flow
SW-1455	9/19/2025 10:22:21 AM	34.4324035	-118.6519047	1196	Valve Adjustment:Audible Flow;Well Condition:Good
SW-154	9/17/2025 1:54:35 PM	34.4379927	-118.6456107	1261	
SW-17-135	9/4/2025 9:54:36 AM	34.4324720	-118.6519995	1197	Valve Adjustment:Audible Flow
SW-17-135	9/19/2025 10:24:22 AM	34.4324772	-118.6519922	1209	Valve Adjustment:Audible Flow;Well Condition:Good
SW-187	9/2/2025 1:15:10 PM	34.4372690	-118.6473220	1315	
SW-187	9/25/2025 1:44:17 PM	34.4372213	-118.6473532	1323	
SW-1930	9/4/2025 8:26:54 AM	34.4353302	-118.6516210	1273	Valve Adjustment:Audible Flow,Valve 100% Open
SW-1930	9/19/2025 9:10:49 AM	34.4353163	-118.6516045	1267	Valve Adjustment:Audible Flow,Valve 100% Open;Well Condition:Good
SW-20	9/23/2025 2:29:32 PM	34.4302433	-118.6436437	1161	,,
SW-25	9/4/2025 8:21:56 AM	34.4351597	-118.6517140	1284	Valve Adjustment:Valve 100% Open
SW-25	9/19/2025 9:15:05 AM	34.4351802	-118.6516977	1257	Valve Adjustment:Valve 100% Open
SW-30	9/4/2025 9:05:50 AM	34.4336922	-118.6519460	1214	
SW-30	9/19/2025 9:57:49 AM	34.4336915	-118.6519470	1207	Valve Adjustment:Audible Flow;Well Condition:Good
SW-32	9/4/2025 9:13:29 AM	34.4335312	-118.6520498	1207	Valve Adjustment:Audible Flow
SW-32	9/19/2025 10:01:56 AM	34.4335252	-118.6520573	1222	Valve Adjustment:Audible Flow;Well Condition:Good
SW-64	9/4/2025 9:03:50 AM	34.4337110	-118.6519627	1221	Valve Adjustment:Audible Flow;Well Condition:Good
SW-64	9/19/2025 9:55:17 AM	34.4336937	-118.6519638	1199	Valve Adjustment:Audible Flow;Well Condition:Good
SW-65	9/15/2025 1:24:13 PM	34.4348380	-118.6412277	1202	Valve Adjustment:Audible Flow;Well Condition:Fair
SW-66	9/17/2025 1:51:53 PM	34.4379730	-118.6456295	1292	
SW-68	9/4/2025 9:11:40 AM	34.4335432	-118.6520293	1203	Valve Adjustment:Audible Flow
SW-68	9/19/2025 10:00:00 AM	34.4335475	-118.6520447	1211	Valve Adjustment:Audible Flow;Well Condition:Good

All LFG Extraction Well Data September 2025
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Elev [ft]	Comments
SW-7	9/4/2025 8:23:54 AM	34.4351647	-118.6517010	1276	Valve Adjustment:Audible Flow,Valve 100% Open
SW-7	9/19/2025 9:13:16 AM	34.4351902	-118.6517028	1267	Valve Adjustment:Valve 100% Open
SW-70	9/2/2025 1:18:04 PM	34.4372765	-118.6472882	1317	
SW-70	9/25/2025 1:47:35 PM	34.4372378	-118.6473573	1318	
SW-71	9/10/2025 1:36:10 PM	34.4259808	-118.6438277	1130	
SW-72	9/12/2025 2:04:39 PM	34.4295900	-118.6401973	1236	
SW-80	9/17/2025 10:58:29 AM	34.4383307	-118.6433772	1218	
SW-9	9/2/2025 1:20:48 PM	34.4372557	-118.6473218	1312	
SW-9	9/25/2025 1:51:45 PM	34.4372327	-118.6473538	1315	
TC-1961C	9/10/2025 11:16:06 AM	34.4321622	-118.6454273	1295	
TC-1961E	9/4/2025 2:56:15 PM	34.4328550	-118.6445075	1290	Valve Adjustment:Audible Flow;Well Condition:Good
TC-2174	9/3/2025 9:13:40 AM	34.4367495	-118.6476278	1343	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
TC-2174	9/3/2025 9:14:00 AM				AtmAA
TC-2174	9/3/2025 9:14:00 AM				AtmAA; [User entered 12.25%]
TC-2174	9/3/2025 9:14:00 AM				AtmAA; [User entered 12.25%]
TC-2174	9/9/2025 8:57:46 AM	34.4367425	-118.6476212	1346	Valve Adjustment:High Temp
TC-2174	9/9/2025 9:00:00 AM				AtmAA
TC-2174	9/15/2025 9:03:55 AM	34.4367440	-118.6476282	1349	Valve Adjustment:High Temp
TC-2174	9/15/2025 9:06:00 AM				AtmAA
TC-2174	9/22/2025 8:32:49 AM	34.4367270	-118.6476457	1334	Valve Adjustment:No Flow Measurement,High Temp
TC-2174	9/29/2025 11:30:06 AM	34.4367487	-118.6476368	1344	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
VL-02	9/26/2025 2:03:23 PM	34.4311612	-118.6443222	1174	Valve Adjustment:Surging Liquid in Header

Table 2. LEA Selected Wells - August 2025
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	BalO2 [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [F]	Adj Temp [F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-108-52	9/2/2025 10:35:26 AM	42.5	54.7	0.0	2.8	0.0			122.4	122.3	-1.41	-1.42	Valve Adjustment:Decom Well (Temporary),Audible Flow,Barely Open;Well Condition:Good
CV-108-52	9/10/2025 10:00:00 AM							21000					Air Tech Lab; [User entered 2.1%]
CV-108-52	9/10/2025 10:00:00 AM						380						Air Tech Lab
CV-108-52	9/17/2025 8:58:55 AM	42.9	56.3	0.0	0.8	0.0			121.7	121.4	-1.92	-1.74	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum,Barely Open;Well Condition:Good
CV-113	9/3/2025 9:08:14 AM	0.9	85.6	0.5	13.0	26.0			181.0	181.0	-2.26	-1.74	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-113	9/3/2025 9:13:00 AM							66500					AtmAA; [User entered 6.65%]
CV-113	9/3/2025 9:13:00 AM						1520						AtmAA
CV-113	9/9/2025 8:53:00 AM						2870						AtmAA
CV-113	9/9/2025 8:54:45 AM	0.6	77.1	0.1	22.2	222.0			183.1	183.1	-3.12	-3.43	
CV-113	9/15/2025 8:58:37 AM	1.5	86.5	0.0	12.0	0.0			165.0	168.6	-5.32	-5.87	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In)
CV-113	9/15/2025 9:03:00 AM						1710						AtmAA
CV-113	9/22/2025 8:29:56 AM	1.4	84.3	1.3	13.0	10.0			185.2	185.1	-4.61	-4.34	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-113	9/29/2025 11:25:43 AM	0.9	70.2	3.5	25.4	7.3			177.5	177.0	-2.21	-1.06	Valve Adjustment:High Temp,Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-114	9/11/2025 8:55:00 AM							130000					Air Tech Lab; [User entered 13%]
CV-114	9/11/2025 8:55:00 AM						2100						Air Tech Lab
CV-1532A	9/4/2025 9:18:52 AM	1.8	75.0	0.9	22.3	24.8			173.7	179.2	-4.61	-4.36	Valve Adjustment:No Flow Measurement,High Temp
CV-1532A	9/4/2025 9:20:00 AM							93600					AtmAA; [User entered 9.36%]
CV-1532A	9/4/2025 9:20:00 AM						2050						AtmAA
CV-1532A	9/10/2025 10:10:00 AM							21000					Air Tech Lab; [User entered 2.1%]
CV-1532A	9/10/2025 10:10:00 AM						730						Air Tech Lab
CV-1532A	9/10/2025 11:02:22 AM		69.1	2.5					178.4	178.6	-6.78	-5.33	High Temp,,
CV-1532A	9/10/2025 11:04:00 AM						2590						AtmAA
CV-1532A	9/12/2025 2:19:15 PM	3.7	74.6	2.1	19.6	9.3			175.9	179.8	-7.26	-7.41	Valve Adjustment:No Flow Measurement,High Temp
CV-1532A	9/18/2025 10:36:35 AM	9.5	81.8	0.5	8.2	16.4			170.1	165.5	-9.30	-9.46	Valve Adjustment:No Flow Measurement,High Temp
CV-1532A	9/24/2025 9:41:10 AM	1.6	75.5	2.0	20.9	10.5			178.0	182.0	-7.88	-7.32	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-1535	9/2/2025 10:32:14 AM	44.9	52.3	0.0	2.8	0.0			120.5	120.8	-0.61	-0.60	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Good
CV-1535	9/9/2025 9:00:00 AM							25000					Air Tech Lab; [User entered 2.5%]

Table 2. LEA Selected Wells - August 2025
Chiquita Canyon Landfill

CV-1535	9/9/2025 9:00:00 AM						180						Air Tech Lab
CV-1535	9/17/2025 8:55:16 AM	44.5	53.3	0.0	2.2	0.0			122.3	122.2	-1.00	-0.87	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum,Barely Open;Well Condition:Good
CV-1902A	9/4/2025 8:41:25 AM	1.9	78.6	0.0	19.5	0.0			181.9	182.2	-0.95	-0.97	Valve Adjustment:High Temp
CV-1902A	9/4/2025 8:45:00 AM							148300					AtmAA; [User entered 14.83%]
CV-1902A	9/4/2025 8:45:00 AM						1340						AtmAA
CV-1902A	9/9/2025 8:45:00 AM							200000					Air Tech Lab; [User entered 20%]
CV-1902A	9/9/2025 8:45:00 AM						1000						Air Tech Lab
CV-1902A	9/10/2025 10:11:35 AM	24.2	75.4	0.4	0.0	0.0			161.4	161.7	-1.57	-1.58	High Temp,No Flow Measurement,
CV-1902A	9/10/2025 10:13:00 AM						1860						AtmAA
CV-1902A	9/18/2025 8:46:48 AM	10.3	82.9	0.0	6.8	0.0			169.1	168.8	-2.61	-2.62	Valve Adjustment:No Flow Measurement,High Temp
CV-1902A	9/24/2025 11:10:16 AM	2.3	75.2	0.8	21.7	27.1			182.7	183.7	-1.88	-1.97	Valve Adjustment:High Temp
CV-2001	9/2/2025 2:14:25 PM	9.2	72.7	1.0	17.1	17.1			114.9	116.1	-0.62	-0.30	Valve Adjustment:Decreased Flow/Vacuum,Barely Open;Well Condition:Fair
CV-2001	9/8/2025 9:00:00 AM							23000					Air Tech Lab; [User entered 2.3%]
CV-2001	9/8/2025 9:00:00 AM						880						Air Tech Lab
CV-2001	9/8/2025 9:26:03 AM	7.8	70.4	4.8	17.0	3.5			100.5	99.1	-3.22	-3.13	Valve Adjustment:Orifice Plate Changed (See OP Log);Well Comment:Fastened bolts
CV-2001	9/8/2025 9:33:34 AM	8.5	75.1	3.8	12.7	3.4			100.1	102.7	-0.57	-0.57	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum
CV-2001	9/17/2025 10:35:12 AM	9.9	85.4	1.1	3.6	3.3			116.0	106.8	-2.80	-2.16	
CV-2002	9/2/2025 2:29:12 PM	35.1	63.1	0.0	1.8	0.0			128.2	127.7	-0.22	-0.29	Valve Comment:unable to reach system;Valve Adjustment:Barely Open;Well Condition:Fair
CV-2002	9/4/2025 9:55:00 AM							4300					Air Tech Lab; [User entered 0.43%]
CV-2002	9/4/2025 9:55:00 AM						330						Air Tech Lab
CV-2002	9/17/2025 10:59:06 AM	29.9	70.1	0.0	0.0	0.0			123.5	124.1	0.66	0.33	
CV-2002	9/17/2025 11:00:32 AM	31.1	67.4	0.0	1.5	0.0			124.4	124.3	0.61	0.74	Valve Adjustment:Surging Liquid in Header
CV-2007	9/2/2025 1:44:21 PM	29.9	65.7	0.0	4.4	0.0			110.2	110.2	-0.10	-0.11	
CV-2007	9/3/2025 9:40:00 AM							4600					Air Tech Lab; [User entered 0.46%]
CV-2007	9/3/2025 9:40:00 AM						33						Air Tech Lab
CV-2301	9/3/2025 9:44:41 AM	20.4	69.4	0.2	10.0	52.7			116.9	108.5	-5.30	-0.35	Valve Adjustment:Reconnected this Date,Decreased Flow/Vacuum
CV-2301	9/4/2025 10:47:00 AM	6.5	79.9	0.0	13.6	0.0			185.0	102.4	-0.95	-0.86	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2301	9/10/2025 9:20:00 AM							110000					Air Tech Lab; [User entered 11%]
CV-2301	9/10/2025 9:20:00 AM						890						Air Tech Lab
CV-2301	9/11/2025 10:20:00 AM						1730						AtmAA
CV-2301	9/11/2025 10:21:11 AM	19.5	70.3	0.5	9.7	19.4			181.0	181.0	-2.67	-2.58	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp
CV-2301	9/17/2025 9:47:54 AM	23.2	62.9	0.8	13.1	16.4			185.2	185.3	-3.28	-3.29	Valve Adjustment:No Flow Measurement,High Temp

Table 2. LEA Selected Wells - August 2025
Chiquita Canyon Landfill

CV-2301	9/24/2025 2:06:26 PM	21.0	62.9	2.3	13.8	6.0			183.3	182.8	-6.84	-6.84	Valve Adjustment:No Flow Measurement,High Temp
CV-2302	9/3/2025 10:01:02 AM	49.6	43.6	0.3	6.6	24.3			117.6	117.8	-3.39	-2.08	Valve Adjustment:Reconnected this Date,Decreased Flow/Vacuum
CV-2302	9/10/2025 9:15:00 AM							19000					Air Tech Lab; [User entered 1.9%]
CV-2302	9/10/2025 9:15:00 AM						100						Air Tech Lab
CV-2302	9/16/2025 2:11:57 PM	49.1	43.1	0.2	7.6	38.0			117.8	117.6	-2.66	-2.91	Valve Adjustment:Surging Liquid in Header
CV-2303	9/3/2025 1:59:37 PM	8.2	0.0	0.5	91.3	182.6			187.4	187.5	-5.81	-5.94	Valve Adjustment:No Flow Measurement,High Temp
CV-2303	9/3/2025 2:05:00 PM							117700					AtmAA; [User entered 11.77%]
CV-2303	9/3/2025 2:05:00 PM						2700						AtmAA
CV-2303	9/9/2025 1:42:11 PM	5.7	81.7	0.1	12.5	125.0			185.1	185.1	-7.26	-7.25	Valve Adjustment:No Flow Measurement,High Temp
CV-2303	9/9/2025 1:43:00 PM						2770						AtmAA
CV-2303	9/11/2025 8:05:00 AM							120000					Air Tech Lab; [User entered 12%]
CV-2303	9/11/2025 8:05:00 AM						1500						Air Tech Lab
CV-2303	9/16/2025 11:08:40 AM	13.1	80.9	0.0	6.0	0.0			189.3	189.5	-10.43	-10.47	Valve Adjustment:High Temp
CV-2303	9/16/2025 11:10:00 AM						1610						AtmAA
CV-2303	9/23/2025 9:07:14 AM	1.3	83.5	0.2	15.0	75.0			187.8	187.8	-11.00	-10.94	Valve Adjustment:High Temp
CV-2303	9/30/2025 9:44:00 AM	2.0	76.2	1.9	19.9	10.5			186.0	186.1	-7.97	-7.98	Valve Adjustment:High Temp
CV-2305	9/3/2025 10:30:00 AM							52000					Air Tech Lab; [User entered 5.2%]
CV-2305	9/3/2025 10:30:00 AM						1400						Air Tech Lab
CV-2305	9/9/2025 12:59:25 PM	17.3	80.5	0.2	2.1	13.7			136.8	137.0	-1.21	-0.88	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum
CV-2305	9/9/2025 1:17:51 PM	16.6	83.2	0.2	0.1	0.2			137.7	136.5	-0.80	-1.17	Valve Adjustment:High Temp,Increased Flow/Vacuum
CV-2305	9/26/2025 2:20:50 PM	12.3	80.0	0.0	7.7	0.0			129.8	129.6	-1.40	-0.85	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum
CV-2312	9/15/2025 8:00:00 AM						2100						Air Tech Lab
CV-2312	9/15/2025 8:25:00 AM							130000					Air Tech Lab; [User entered 13%]
CV-2312	9/15/2025 9:23:42 AM	6.8	86.1	0.5	6.7	13.3			154.0	153.5	-4.13	-1.93	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-2312	9/15/2025 9:31:05 AM	6.3	85.9	0.2	7.6	36.4			152.5	151.9	-1.96	-0.87	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum
CV-2312	9/17/2025 8:48:14 AM	11.4	78.2	0.0	10.4	0.0			153.8	153.7	-1.59	-1.58	Valve Adjustment:High Temp
CV-2312	9/25/2025 10:07:46 AM	3.1	83.6	0.0	13.3	0.0			157.0	156.6	-1.92	-1.66	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2314	9/11/2025 8:25:00 AM							110000					Air Tech Lab; [User entered 11%]
CV-2314	9/11/2025 8:25:00 AM						1200						Air Tech Lab
CV-2314	9/11/2025 9:43:41 AM	15.4	79.3	0.2	5.1	23.4			144.9	144.9	-0.17	-0.16	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2314	9/11/2025 9:45:27 AM	15.3	80.0	0.2	4.5	21.6			144.9	144.9	-0.14	-0.04	Valve Adjustment:Orifice Plate Changed (See OP Log),High Temp,Decreased Flow/Vacuum
CV-2314	9/11/2025 9:49:46 AM	13.2	81.8	0.0	4.9	0.0			144.9	144.9	-0.05	-0.05	Valve Adjustment:Orifice Plate Changed (See OP Log)

Table 2. LEA Selected Wells - August 2025
Chiquita Canyon Landfill

CV-2314	9/11/2025 11:09:14 AM	14.6	79.2	0.0	6.2	0.0			144.7	144.7	0.06	-0.05	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Good
CV-2314	9/11/2025 11:11:40 AM	18.4	75.9	0.0	5.7	0.0			144.5	144.8	-0.02	-0.04	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-2314	9/19/2025 11:09:06 AM	17.0	76.9	0.0	6.1	0.0			144.0	144.3	-0.24	-0.08	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open;Well Condition:Good
CV-2314	9/19/2025 11:10:00 AM	16.3	75.5	0.0	8.2	0.0			144.2	144.5	-0.09	-0.06	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum
CV-2315	9/2/2025 11:00:49 AM	8.6	79.0	0.5	11.9	23.8			164.1	163.9	-0.88	-0.97	Valve Adjustment:High Temp,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2315	9/2/2025 11:04:00 AM							57750					AtmAA; [User entered 5.775%]
CV-2315	9/2/2025 11:04:00 AM						1620						AtmAA
CV-2315	9/3/2025 10:40:00 AM							82000					Air Tech Lab; [User entered 8.2%]
CV-2315	9/3/2025 10:40:00 AM						1700						Air Tech Lab
CV-2315	9/10/2025 2:14:09 PM		77.4	1.5					162.5	162.5	-2.98	-2.96	High Temp,,
CV-2315	9/10/2025 2:17:00 PM						2510						AtmAA
CV-2315	9/12/2025 1:44:21 PM	12.8	81.3	1.0	4.9	4.9			164.3	164.4	-1.21	-1.21	Valve Adjustment:Valve 100% Open
CV-2315	9/17/2025 6:55:43 AM	9.9	85.5	0.0	4.6	0.0			157.0	157.0	-2.59	-2.49	Valve Adjustment:High Temp
CV-2315	9/25/2025 9:01:33 AM	10.5	77.7	0.7	11.1	15.9			164.6	164.6	-3.58	-3.59	Valve Adjustment:High Temp,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2328	9/10/2025 8:55:00 AM							110000					Air Tech Lab; [User entered 11%]
CV-2328	9/10/2025 8:55:00 AM						1400						Air Tech Lab
CV-2328	9/10/2025 1:17:41 PM	10.8	81.9	0.5	6.9	14.9			178.1	178.0	-2.01	-2.01	Valve Adjustment:NSPS/EG CAI,Reconnected this Date,High Temp
CV-2328	9/10/2025 1:18:29 PM	10.7	81.6	0.4	7.3	17.0			178.0	178.1	-1.98	-1.96	Valve Adjustment:High Temp
CV-2328	9/11/2025 11:03:12 AM	23.7	69.4	1.2	5.7	4.8			173.7	173.6	-2.30	-2.28	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2328	9/11/2025 1:30:00 PM						889						AtmAA
CV-2328	9/17/2025 8:35:20 AM	25.4	72.0	0.0	2.6	0.0			166.5	166.5	-5.33	-5.06	Valve Adjustment:High Temp
CV-2328	9/24/2025 2:31:29 PM	45.9	52.7	1.4	0.0	0.0			161.9		-3.86		Valve Adjustment:High Temp
CV-2333	9/2/2025 10:10:00 AM							130000					Air Tech Lab; [User entered 13%]
CV-2333	9/2/2025 10:10:00 AM						2200						Air Tech Lab
CV-2333	9/10/2025 8:36:34 AM	0.6	87.1	1.0	11.4	11.9			136.9	137.1	-2.94	-2.86	Valve Adjustment:High Temp
CV-2333	9/10/2025 8:37:45 AM	0.5	84.3	1.2	14.1	11.4			137.4	137.0	-2.86	-2.90	Valve Adjustment:High Temp
CV-2333	9/30/2025 1:38:09 PM	0.6	82.4	0.2	16.8	84.0			137.1	138.5	-1.03	-1.05	
CV-2333	9/30/2025 1:38:52 PM	0.5	81.9	0.1	17.5	175.0			139.4	139.6	-1.12	-1.02	
CV-2334	9/2/2025 10:05:00 AM							18000					Air Tech Lab; [User entered 1.8%]
CV-2334	9/2/2025 10:05:00 AM						200						Air Tech Lab
CV-2334	9/5/2025 2:02:08 PM	43.3	56.6	0.1	0.0	0.0			128.8	129.0	-1.05	-0.99	
CV-2334	9/30/2025 12:30:03 PM	39.2	56.9	0.1	3.8	34.5			128.6	128.2	-2.20	-1.64	Valve Adjustment:Decreased Flow/Vacuum
CV-2337	9/9/2025 8:35:00 AM							160000					Air Tech Lab; [User entered 16%]
CV-2337	9/9/2025 8:35:00 AM						2000						Air Tech Lab

Table 2. LEA Selected Wells - August 2025
Chiquita Canyon Landfill

CV-2337	9/12/2025 9:00:59 AM	8.7	39.7	8.3	43.3	5.2			78.8	78.7	-2.03	-1.99	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open;Well Condition:Good
CV-2337	9/12/2025 9:04:21 AM	9.8	43.3	6.6	40.3	6.1			78.3	79.2	-2.00	-1.52	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-2337	9/26/2025 8:16:28 AM	5.8	84.4	0.0	9.8	0.0			142.2	143.4	-4.91	-5.07	Valve Adjustment:High Temp
CV-2337	9/26/2025 8:17:33 AM	5.9	86.2	0.0	7.9	0.0			142.3	142.9	-5.34	-5.33	Valve Adjustment:High Temp
CV-2341	9/8/2025 11:25:50 AM	5.4	74.9	0.0	19.7	0.0			113.0	113.0	-1.23	-1.26	,,
CV-2341	9/9/2025 8:50:00 AM							170000					Air Tech Lab; [User entered 17%]
CV-2341	9/9/2025 8:50:00 AM						770						Air Tech Lab
CV-2341	9/16/2025 10:49:48 AM	23.3	60.2	0.1	16.4	164.0			138.4	136.4	-2.78	-1.39	Valve Adjustment:Decreased Flow/Vacuum
CV-2344	9/4/2025 8:56:00 AM							66800					AtmAA; [User entered 6.68%]
CV-2344	9/4/2025 8:56:00 AM						2210						AtmAA
CV-2344	9/4/2025 8:58:42 AM	14.6	70.5	0.0	14.9	0.0			157.3	157.3	-1.43	-1.44	Valve Adjustment:High Temp
CV-2344	9/8/2025 9:45:00 AM							99000					Air Tech Lab; [User entered 9.9%]
CV-2344	9/8/2025 9:45:00 AM						1800						Air Tech Lab
CV-2344	9/11/2025 1:47:51 PM	14.1	75.9	0.2	9.8	49.0			157.6	157.8	-1.71	-1.71	Valve Adjustment:High Temp
CV-2344	9/11/2025 2:20:00 PM						3560						AtmAA
CV-2344	9/17/2025 2:28:09 PM	8.8	78.3	0.0	12.9	0.0			143.1	143.2	-1.15	-1.13	Valve Adjustment:High Temp
CV-2344	9/17/2025 2:28:57 PM	9.2	78.8	0.0	12.0	0.0			144.1	144.1	-1.23	-1.29	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2344	9/18/2025 2:11:01 PM	26.6	73.4	0.0	0.0	0.0			160.6	161.1	-0.75	-0.75	Valve Adjustment:No Flow Measurement,High Temp
CV-2344	9/24/2025 8:57:50 AM	11.3	73.0	1.0	14.7	14.7			158.5	158.4	-2.66	-2.69	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2345	9/8/2025 9:31:17 AM	23.1	69.4	0.2	7.3	36.5			133.7	134.4	-1.81	-0.72	,,
CV-2345	9/9/2025 9:25:00 AM							33000					Air Tech Lab; [User entered 3.3%]
CV-2345	9/9/2025 9:25:00 AM						500						Air Tech Lab
CV-2345	9/17/2025 9:11:25 AM	23.2	72.9	0.0	3.9	0.0			143.0	142.9	-0.53	-0.33	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2345	9/17/2025 9:12:21 AM	22.1	76.2	0.0	1.7	0.0			143.0	142.7	-0.25	-0.25	Valve Adjustment:NSPS/EG CAI,High Temp;Well Condition:Lorentz Pump Installed
CV-2346	9/2/2025 11:03:58 AM	6.0	84.5	0.0	9.5	0.0			128.1	128.0	-1.01	-0.89	Valve Adjustment:Audible Flow;Well Condition:Good
CV-2346	9/9/2025 9:20:00 AM							95000					Air Tech Lab; [User entered 9.5%]
CV-2346	9/9/2025 9:20:00 AM						2400						Air Tech Lab
CV-2346	9/17/2025 9:16:34 AM	8.0	80.5	0.0	11.5	0.0			128.4	128.5	-0.28	-0.26	Valve Adjustment:Audible Flow;Well Condition:Lorentz Pump Installed
CV-2347	9/2/2025 11:25:43 AM	20.0	54.3	0.0	25.7	0.0			112.2	112.3	-3.35	-1.05	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good
CV-2347	9/9/2025 9:15:00 AM							68000					Air Tech Lab; [User entered 6.8%]
CV-2347	9/9/2025 9:15:00 AM						1700						Air Tech Lab
CV-2347	9/17/2025 9:28:38 AM	14.1	71.1	0.0	14.8	0.0			117.4	117.5	-0.60	-0.36	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good,Lorentz Pump Installed

Table 2. LEA Selected Wells - August 2025
Chiquita Canyon Landfill

CV-2348	9/2/2025 11:32:39 AM	23.5	71.1	0.0	5.4	0.0			134.5	134.0	-1.05	-0.54	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Good
CV-2348	9/2/2025 11:33:48 AM	22.6	72.1	0.0	5.3	0.0			133.4	133.3	-0.44	-0.34	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Good
CV-2348	9/9/2025 9:10:00 AM							19000					Air Tech Lab; [User entered 1.9%]
CV-2348	9/9/2025 9:10:00 AM						400						Air Tech Lab
CV-2348	9/17/2025 9:33:34 AM	16.4	79.0	0.0	4.6	0.0			133.8	134.2	-0.16	-0.11	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Good,Lorentz Pump Installed
CV-2348	9/17/2025 9:34:01 AM	15.6	83.6	0.0	0.8	0.0			134.1	134.2	-0.10	-0.10	Valve Adjustment:NSPS/EG CAI,High Temp;Well Condition:Lorentz Pump Installed
CV-2349	9/4/2025 9:40:00 AM							110000					Air Tech Lab; [User entered 11%]
CV-2349	9/4/2025 9:40:00 AM						2900						Air Tech Lab
CV-2349	9/5/2025 7:49:52 AM	5.0	80.4	0.4	14.2	35.5			150.0	150.3	-1.31	-1.82	Valve Adjustment:High Temp
CV-2349	9/5/2025 7:50:00 AM							84200					AtmAA; [User entered 8.42%]
CV-2349	9/5/2025 7:50:00 AM						4210						AtmAA
CV-2349	9/11/2025 1:56:53 PM	7.5	83.1	0.0	9.4	0.0			152.5	152.3	-0.47	-0.50	Valve Adjustment:High Temp
CV-2349	9/11/2025 2:00:00 PM						4240						AtmAA
CV-2349	9/18/2025 11:04:29 AM	17.7	82.3	0.0	0.0	0.0			152.5	152.5	-2.50	-2.53	Valve Adjustment:No Flow Measurement,High Temp
CV-2349	9/18/2025 2:43:09 PM	5.9	83.1	0.0	11.0	0.0			143.4	144.2	-0.81	-0.33	Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header;Well Condition:Fair
CV-2349	9/18/2025 2:44:16 PM	5.9	83.1	0.0	11.0	0.0			144.2	142.7	-0.34	-0.05	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-2350	9/2/2025 2:26:16 PM	10.3	81.0	0.0	8.7	0.0			126.3	126.5	-1.42	-1.25	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2350	9/8/2025 9:10:00 AM							75000					Air Tech Lab; [User entered 7.5%]
CV-2350	9/8/2025 9:10:00 AM						2500						Air Tech Lab
CV-2350	9/17/2025 10:55:34 AM	8.8	83.4	0.1	7.7	77.0			126.3	126.8	-1.88	-1.78	Valve Adjustment:Decreased Flow/Vacuum
CV-2351	9/4/2025 9:00:00 AM							2800					Air Tech Lab; [User entered 0.28%]
CV-2351	9/4/2025 9:00:00 AM						32						Air Tech Lab
CV-2351	9/10/2025 8:47:36 AM	0.1	2.0	21.0	76.9	3.7			64.0	64.0	-0.07	-0.04	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2351	9/17/2025 2:13:22 PM	0.0	0.7	20.0	79.3	4.0			109.7	109.9	-0.06	-0.09	Valve Adjustment:High O2,Surging Liquid in Well (Watered In)
CV-2352	9/4/2025 9:28:00 AM							30000					Air Tech Lab; [User entered 3.0%]
CV-2352	9/4/2025 9:28:00 AM						220						Air Tech Lab
CV-2352	9/10/2025 8:58:04 AM	0.0	6.4	20.0	73.6	3.7			88.6	89.4	-8.70	-8.53	Valve Adjustment:High O2,Valve 100% Open,Surging Liquid in Well (Watered In);Well Comment:to tall to adjust
CV-2352	9/17/2025 2:17:54 PM	0.0	2.8	19.9	77.3	3.9			121.0	120.8	-7.40	-7.64	

Table 2. LEA Selected Wells - August 2025
Chiquita Canyon Landfill

CV-2353-PLR	9/4/2025 9:36:47 AM	2.2	55.9	4.9	37.0	7.6			180.1	180.4	-7.75	-7.78	Valve Adjustment:No Flow Measurement,High Temp
CV-2353-PLR	9/4/2025 9:40:00 AM							92900					AtmAA; [User entered 9.29%]
CV-2353-PLR	9/4/2025 9:40:00 AM						555						AtmAA
CV-2353-PLR	9/8/2025 9:35:00 AM							190000					Air Tech Lab; [User entered 19%]
CV-2353-PLR	9/8/2025 9:35:00 AM						650						Air Tech Lab
CV-2353-PLR	9/10/2025 10:48:50 AM		57.6	3.3					174.4	174.6	-1.13	-0.73	No Flow Measurement,High Temp,
CV-2353-PLR	9/10/2025 10:50:00 AM						1830						AtmAA
CV-2353-PLR	9/12/2025 2:09:56 PM	3.9	66.2	3.4	26.5	7.8			182.0	182.2	-5.90	-5.99	Valve Adjustment:High Temp
CV-2353-PLR	9/18/2025 10:48:02 AM	18.0	63.8	4.3	13.9	3.2			181.4	181.7	-7.47	-7.45	Valve Adjustment:No Flow Measurement,High Temp
CV-2353-PLR	9/24/2025 10:20:25 AM	2.0	64.1	3.8	30.1	7.9			185.4	185.7	-5.09	-5.08	Valve Adjustment:No Flow Measurement,High Temp
CV-2354	9/4/2025 9:35:00 AM							120000					Air Tech Lab; [User entered 12%]
CV-2354	9/4/2025 9:35:00 AM						2800						Air Tech Lab
CV-2354	9/8/2025 3:32:46 PM	20.2	58.6	3.2	18.0	5.6			116.9	117.9	-2.66	-3.47	,,
CV-2354	9/26/2025 8:52:45 AM	3.6	14.9	17.5	64.0	3.7			89.0	90.2	-3.61	-4.21	Valve Adjustment:High O2,Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2354	9/26/2025 8:53:43 AM	3.9	15.5	17.0	63.6	3.7			89.9	89.5	-6.76	-5.74	Valve Adjustment:High O2,Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24002	9/9/2025 10:26:26 AM	33.8	66.2	0.0	0.0	0.0			112.2	112.3	-0.68	-0.67	
CV-24002	9/16/2025 10:22:25 AM	32.8	66.8	0.5	0.0	0.0			113.1	113.1	-1.13	-1.14	
CV-24003	9/9/2025 10:22:43 AM	39.7	60.3	0.0	0.0	0.0			110.4	110.6	-0.50	-0.50	
CV-24003	9/16/2025 9:31:10 AM	38.6	60.6	0.2	0.6	3.2			104.8	107.5	-0.89	-0.92	Valve Adjustment:Increased Flow/Vacuum
CV-24007	9/10/2025 10:11:39 AM	12.6	87.3	0.1	0.0	0.0			127.8	127.3	-0.35	-0.29	Valve Adjustment:Decreased Flow/Vacuum
CV-24007	9/11/2025 7:45:00 AM							65000					Air Tech Lab; [User entered 6.5%]
CV-24007	9/11/2025 7:45:00 AM						680						Air Tech Lab
CV-24007	9/16/2025 12:28:29 PM	10.4	84.6	0.1	5.0	55.3			129.5	129.5	-0.16	-0.16	
CV-24017	9/3/2025 10:38:48 AM	13.5	75.8	0.0	10.7	0.0			175.5	176.0	-2.52	-1.49	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24017	9/3/2025 10:40:00 AM							123500					AtmAA; [User entered 12.35%]
CV-24017	9/3/2025 10:40:00 AM						2160						AtmAA
CV-24017	9/9/2025 10:59:21 AM	20.6	74.2	0.3	4.9	16.3			160.0	159.7	-3.79	-3.76	Valve Adjustment:No Flow Measurement,High Temp
CV-24017	9/9/2025 11:00:00 AM						1790						AtmAA
CV-24017	9/11/2025 7:50:00 AM							65000					Air Tech Lab; [User entered 6.5%]
CV-24017	9/11/2025 7:50:00 AM						660						Air Tech Lab
CV-24017	9/16/2025 9:51:04 AM	27.5	72.5	0.0	0.0	0.0			166.2	166.4	-5.35	-5.38	Valve Adjustment:High Temp
CV-24017	9/16/2025 9:52:00 AM						1060						AtmAA
CV-24017	9/23/2025 8:18:33 AM	21.4	73.5	0.1	5.0	50.0			167.1	167.2	-2.86	-2.70	Valve Adjustment:NSPS/EG CAI,High Temp;Well Condition:Lorentz Pump Installed

Table 2. LEA Selected Wells - August 2025
Chiquita Canyon Landfill

CV-24017	9/30/2025 10:51:29 AM	7.0	76.0	1.0	16.0	16.0			188.2	188.9	-1.69	-1.69	Valve Adjustment:High Temp,Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-24049	9/2/2025 11:18:25 AM	1.8	77.0	1.6	19.6	12.3			187.8	188.1	-0.29	-0.17	Valve Adjustment:High Temp
CV-24049	9/2/2025 11:25:00 AM							145300					AtmAA; [User entered 14.53%]
CV-24049	9/2/2025 11:25:00 AM						4470						AtmAA
CV-24049	9/3/2025 9:45:00 AM							160000					Air Tech Lab; [User entered 16%]
CV-24049	9/3/2025 9:45:00 AM						2500						Air Tech Lab
CV-24049	9/8/2025 8:45:03 AM	1.9	89.8	0.0	8.3	0.0			188.5	188.8	-0.33	-0.25	Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Decreased Flow/Vacuum,Barely Open;Well Condition:Good
CV-24049	9/8/2025 8:48:00 AM						4100						AtmAA
CV-24049	9/15/2025 2:22:04 PM	4.3	84.2	0.0	11.5	0.0			185.2	187.7	1.13	-1.28	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum,Surging Liquid in Header
CV-24049	9/15/2025 2:22:59 PM	4.0	83.6	0.0	12.4	0.0			188.6	188.7	-1.33	-1.30	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Surging Liquid in Header
CV-24049	9/15/2025 2:24:00 PM						2850						AtmAA
CV-24049	9/22/2025 1:21:53 PM	5.4	73.3	1.3	20.0	15.4			188.4	188.7	-0.29	-0.29	Valve Adjustment:High Temp
CV-24049	9/29/2025 9:33:42 AM	1.3	82.4	0.4	15.9	39.8			188.4	189.4	-0.02	-0.10	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24053	9/8/2025 2:11:38 PM	8.9	37.3	11.2	42.6	3.8			97.9	98.1	-0.31	-0.24	
CV-24053	9/8/2025 2:17:33 PM	7.8	19.4	14.9	57.9	3.9			98.3	98.4	-0.03	-0.04	Valve Adjustment:High O2
CV-24053	9/11/2025 8:20:00 AM							180000					Air Tech Lab; [User entered 18%]
CV-24053	9/11/2025 8:20:00 AM						1700						Air Tech Lab
CV-24053	9/16/2025 1:45:54 PM	26.5	72.5	0.0	1.0	0.0			111.8	111.9	-0.07	-0.08	
CV-24055	9/2/2025 11:04:57 AM	16.2	54.1	2.8	26.9	9.6			127.3	127.3	-0.27	-0.18	
CV-24055	9/3/2025 9:50:00 AM							86000					Air Tech Lab; [User entered 8.6%]
CV-24055	9/3/2025 9:50:00 AM						870						Air Tech Lab
CV-24055	9/29/2025 12:51:51 PM	3.3	76.5	0.0	20.2	0.0			120.5	121.4	0.02	-0.02	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum
CV-24055	9/29/2025 12:52:44 PM	4.0	78.7	0.0	17.3	0.0			121.5	121.5	-0.02	-0.01	Valve Adjustment:NSPS/EG CAC
CV-24062	9/5/2025 6:49:16 AM	22.5	74.4	0.6	2.5	4.2			152.1	149.2	-0.97	-0.75	Valve Adjustment:No Flow Measurement,High Temp
CV-24062	9/5/2025 6:50:00 AM							36000					AtmAA; [User entered 3.60%]
CV-24062	9/5/2025 6:50:00 AM						701						AtmAA
CV-24062	9/10/2025 9:10:00 AM							75000					Air Tech Lab; [User entered 7.5%]
CV-24062	9/10/2025 9:10:00 AM						780						Air Tech Lab
CV-24062	9/11/2025 9:35:00 AM	25.5	69.0	1.3	4.2	3.2			155.6	155.3	-0.74	-0.77	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24062	9/17/2025 8:27:01 AM	33.0	67.0	0.0	0.0	0.0			154.2	154.0	-5.43	-5.41	Valve Adjustment:High Temp
CV-24062	9/24/2025 2:40:00 PM	50.5	47.8	1.7	0.0	0.0			147.9	149.3	-4.49	-4.58	Valve Adjustment:No Flow Measurement,High Temp

Table 2. LEA Selected Wells - August 2025
Chiquita Canyon Landfill

CV-24063	9/9/2025 9:39:46 AM	29.0	65.7	0.0	5.3	0.0			135.8	135.4	-5.41	-0.02	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24063	9/9/2025 9:41:34 AM	10.4	77.0	0.0	12.6	0.0			135.0	134.7	-0.06	-0.06	Valve Adjustment:High Temp
CV-24063	9/15/2025 8:30:00 AM							110000					Air Tech Lab; [User entered 11%]
CV-24063	9/15/2025 8:30:00 AM						1900						Air Tech Lab
CV-24063	9/26/2025 8:51:30 AM	6.3	79.9	0.0	13.8	0.0			165.8	165.7	1.16	-0.10	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum;Well Condition:Good
CV-24063	9/26/2025 8:53:44 AM	6.3	79.6	0.0	14.1	0.0			165.6	166.0	-0.16	-0.18	Temp,Barely Open;Well Condition:Good
CV-24063	9/30/2025 2:31:24 PM	6.6	73.2	0.8	19.4	24.3			163.1	162.6	-1.15	-1.10	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24064	9/3/2025 10:50:00 AM							130000					Air Tech Lab; [User entered 13%]
CV-24064	9/3/2025 10:50:00 AM						2500						Air Tech Lab
CV-24064	9/5/2025 6:24:17 AM	2.3	87.4	0.7	9.6	13.7			188.8	189.2	-3.93	-3.72	Valve Adjustment:No Flow Measurement,High Temp
CV-24064	9/5/2025 9:44:00 AM							71100					AtmAA; [User entered 7.11%]
CV-24064	9/5/2025 9:44:00 AM						2180						AtmAA
CV-24064	9/11/2025 8:49:26 AM	2.7	86.0	0.7	10.6	15.1			189.7	189.9	-1.37	-1.59	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24064	9/11/2025 8:50:00 AM						3635						AtmAA
CV-24064	9/17/2025 8:07:55 AM	2.2	96.1	0.0	1.7	0.0			190.2	190.0	-1.83	-0.65	Valve Adjustment:High Temp
CV-24065-TP17	9/2/2025 11:39:29 AM	20.4	76.6	0.0	3.0	0.0			114.9	115.1	-0.43	-0.40	
CV-24065-TP17	9/3/2025 9:55:00 AM							6700					Air Tech Lab; [User entered 0.67%]
CV-24065-TP17	9/3/2025 9:55:00 AM						180						Air Tech Lab
CV-24065-TP17	9/5/2025 1:45:04 PM	23.0	77.0	0.0	0.0	0.0			122.2	121.9	-0.42	-0.48	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum;Well Condition:Good,Lorentz Pump Installed
CV-24065-TP17	9/10/2025 10:45:53 AM	26.6	72.4	0.0	1.0	0.0			113.0	113.2	-0.64	-0.70	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Barely Open;Well Condition:Good
CV-24065-TP17	9/29/2025 1:03:31 PM	23.1	73.9	0.0	3.0	0.0			113.2	112.5	-3.35	-1.44	Valve Adjustment:Decreased Flow/Vacuum
CV-24066	9/2/2025 10:20:16 AM	29.5	53.1	0.8	16.6	20.8			112.8	117.3	-0.83	-0.73	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good
CV-24066	9/9/2025 9:05:00 AM							35000					Air Tech Lab; [User entered 3.5%]
CV-24066	9/9/2025 9:05:00 AM						390						Air Tech Lab
CV-24066	9/17/2025 8:47:58 AM	29.6	61.7	0.0	8.7	0.0			118.5	118.2	-0.56	-0.41	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Good
CV-24069	9/3/2025 10:37:15 AM	34.4	42.3	3.5	19.9	5.7			119.1	118.9	-1.30	-0.39	Valve Adjustment:Reconnected this Date,Decreased Flow/Vacuum;Well Repairs:Sample Port
CV-24069	9/10/2025 9:30:00 AM							45000					Air Tech Lab; [User entered 4.5%]
CV-24069	9/10/2025 9:30:00 AM						310						Air Tech Lab
CV-24069	9/18/2025 11:10:36 AM	39.4	41.7	3.6	15.3	4.3			77.2	77.1	-8.07	-7.80	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good

Table 2. LEA Selected Wells - August 2025
Chiquita Canyon Landfill

CV-24070	9/3/2025 10:25:01 AM	41.1	55.8	0.0	3.1	0.0			132.2	132.2	-0.06	-0.07	Valve Adjustment:NSPS/EG CAI,Reconnected this Date,High Temp
CV-24070	9/3/2025 10:28:46 AM	39.9	56.5	0.0	3.6	0.0			132.1	132.0	-0.02	-0.09	Valve Adjustment:High Temp
CV-24070	9/10/2025 9:45:00 AM							28000					Air Tech Lab; [User entered 2.8%]
CV-24070	9/10/2025 9:45:00 AM						150						Air Tech Lab
CV-24070	9/18/2025 11:16:50 AM	44.7	53.5	0.0	1.8	0.0			127.3	127.0	-1.89	-1.68	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good
CV-24071	9/10/2025 9:40:00 AM							28000					Air Tech Lab; [User entered 2.8%]
CV-24071	9/10/2025 9:40:00 AM						220						Air Tech Lab
CV-24071	9/10/2025 1:26:51 PM	39.8	55.7	0.8	3.7	4.8			133.7	133.8	-4.74	-4.44	Valve Adjustment:NSPS/EG CAI,Reconnected this Date,High Temp
CV-24071	9/10/2025 1:28:08 PM	38.9	54.9	0.7	5.5	7.4			133.9	133.8	-4.54	-4.54	Valve Adjustment:Reconnected this Date,High Temp
CV-24071	9/18/2025 11:26:39 AM	47.5	50.6	0.0	1.9	0.0			128.2	128.3	-7.05	-6.87	Valve Adjustment:Decreased Flow/Vacuum
CV-24075-TP15	9/5/2025 6:38:38 AM	3.8	76.3	1.7	18.2	10.7			178.1	181.9	-2.78	-2.84	Valve Adjustment:No Flow Measurement,High Temp
CV-24075-TP15	9/5/2025 6:43:00 AM							56300					AtmAA; [User entered 5.63%]
CV-24075-TP15	9/5/2025 6:43:00 AM						1630						AtmAA
CV-24075-TP15	9/11/2025 9:14:51 AM	5.0	79.9	1.9	13.2	6.9			180.1	180.3	-5.08	-5.25	Valve Adjustment:No Flow Measurement,High Temp
CV-24075-TP15	9/11/2025 9:15:00 AM						2700						AtmAA
CV-24075-TP15	9/17/2025 8:12:05 AM	4.6	87.8	0.0	7.6	0.0			184.9	184.7	-5.94	-5.78	Valve Adjustment:No Flow Measurement,High Temp
CV-24077	9/2/2025 9:43:04 AM	7.1	81.1	0.4	11.4	28.5			142.0	135.2	-2.95	-0.95	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header;Well Condition:Good
CV-24077	9/2/2025 9:54:12 AM	9.9	72.1	1.1	16.9	15.4			129.2	129.3	-1.00	-0.27	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum;Well Condition:Good
CV-24077	9/17/2025 8:44:36 AM	13.5	78.2	0.0	8.3	0.0			129.6	126.2	-1.99	-1.69	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Good
CV-24079-TP8	9/4/2025 10:32:00 AM	13.8	79.2	0.0	7.0	0.0			116.7	146.7	-0.26	-0.07	Valve Adjustment:No Flow Measurement
CV-24079-TP8	9/11/2025 10:43:31 AM	12.9	81.3	0.0	5.8	0.0			147.1	149.2	-0.16	-0.19	Valve Adjustment:High Temp
CV-24079-TP8	9/11/2025 10:44:00 AM						1720						AtmAA
CV-24079-TP8	9/17/2025 9:30:11 AM	15.2	80.3	0.0	4.5	0.0			151.3	151.0	-2.01	-2.01	Valve Adjustment:No Flow Measurement,High Temp
CV-24079-TP8	9/24/2025 1:54:29 PM	18.9	72.0	1.3	7.8	6.0			148.4	148.1	-2.08	-2.06	Valve Adjustment:No Flow Measurement,High Temp
CV-24082	9/3/2025 9:26:31 AM	31.1	63.4	0.3	5.1	15.1			119.9	120.1	-2.12	-0.42	Valve Adjustment:Reconnected this Date,Decreased Flow/Vacuum
CV-24082	9/18/2025 9:12:44 AM	40.1	55.7	0.3	3.9	13.0			122.7	122.7	-3.08	-2.51	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Good
CV-24083	9/11/2025 10:33:03 AM	33.4	65.0	0.7	1.0	1.5			138.4	130.7	-4.73	-0.28	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Reconnected this Date,Decreased Flow/Vacuum
CV-24083	9/11/2025 10:34:54 AM	35.6	63.8	0.1	0.6	11.2			128.8	129.8	-0.13	-0.11	

Table 2. LEA Selected Wells - August 2025
Chiquita Canyon Landfill

CV-24083	9/11/2025 1:34:03 PM	28.8	69.1	0.0	2.1	0.0			109.5	113.7	1.06	0.28	Adjustment:NSPS/EG CAI,Reconnected this Date,Positive Static Press.,Increased Flow/Vacuum;Well Condition:Good
CV-24083	9/11/2025 1:35:12 PM	27.4	69.4	0.0	3.2	0.0			117.2	118.4	-0.03	-0.11	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAC,Audible Flow,Barely Open;Well Condition:Good
CV-24083	9/18/2025 11:21:42 AM	43.3	54.9	0.0	1.8	0.0			128.5	128.6	-2.25	-1.80	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Good
CV-24084-TP11	9/15/2025 10:12:22 AM	3.7	93.3	0.0	3.0	0.0			166.9	169.7	14.33	-0.18	Valve Adjustment:NSPS/EG CAI,Reconnected this Date,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-24084-TP11	9/15/2025 10:16:30 AM	4.0	89.9	0.7	5.5	7.6			169.7	168.7	-4.06	-0.93	Valve Adjustment:Decreased Flow/Vacuum
CV-24084-TP11	9/17/2025 9:01:42 AM	3.7	87.1	0.0	9.2	0.0			169.0	169.6	-1.87	-1.89	Valve Adjustment:High Temp
CV-24084-TP11	9/25/2025 10:16:39 AM	6.3	83.5	0.1	10.1	101.0			168.9	168.9	-1.29	-1.33	Valve Adjustment:High Temp,Surging Liquid in Header
CV-24088	9/15/2025 10:01:29 AM	39.5	60.1	0.1	0.4	5.3			115.2	116.4	0.61	-0.93	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Reconnected this Date,Positive Static Press.,Increased Flow/Vacuum
CV-24088	9/15/2025 10:07:06 AM	39.5	59.7	0.3	0.5	2.0			122.1	122.2	-1.14	-0.92	Valve Adjustment:Decreased Flow/Vacuum
CV-24088	9/16/2025 1:44:00 PM	40.0	55.2	0.0	4.8	0.0			126.6	127.8	0.67	-0.32	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
CV-24088	9/16/2025 1:44:47 PM	39.6	56.7	0.0	3.7	0.0			128.0	128.2	-0.37	-0.37	Valve Adjustment:NSPS/EG CAC
CV-24095	9/8/2025 9:15:00 AM							150000					Air Tech Lab; [User entered 15%]
CV-24095	9/8/2025 9:15:00 AM						5000						Air Tech Lab
CV-24095	9/8/2025 9:30:00 AM							130000					Air Tech Lab; [User entered 13%]
CV-24095	9/8/2025 2:36:21 PM	8.3	80.9	0.1	10.7	107.0			124.3	128.0	-5.87	-4.20	,,
CV-24095	9/18/2025 2:48:19 PM	8.9	74.7	0.0	16.4	0.0			129.6	127.1	-4.81	-4.39	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Fair;Well Repairs:Sample Port
CV-24096	9/8/2025 2:22:07 PM	0.1	2.2	20.5	77.2	3.8			106.8	107.3	-0.21	-0.14	High O2,,
CV-24096	9/8/2025 2:23:48 PM	0.1	2.0	20.5	77.4	3.8			107.0	107.0	-0.07	-0.07	,,
CV-24096	9/10/2025 12:28:40 PM	44.6	51.9	0.3	3.3	12.1			96.1	96.3	-0.29	-0.23	Valve Adjustment:NSPS/EG CAC
CV-24096	9/10/2025 12:29:19 PM	43.9	50.6	0.2	5.3	24.0			97.0	97.0	-0.29	-0.32	
CV-24096	9/26/2025 8:42:20 AM	35.8	52.4	1.7	10.1	5.9			116.7	116.8	-1.89	-1.66	
CV-24097	9/8/2025 2:15:19 PM	41.2	33.7	3.8	21.3	5.6			89.8	87.9	-1.50	-0.56	,,
CV-24097	9/17/2025 11:07:58 AM	35.0	64.7	0.0	0.3	0.0			99.5	98.5	11.36	-0.92	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
CV-24097	9/17/2025 11:08:45 AM	35.4	64.6	0.0	0.0	0.0			97.9	97.8	-1.15	-1.09	Valve Adjustment:NSPS/EG CAC
CV-24098	9/2/2025 2:33:25 PM	30.7	55.5	1.9	11.9	6.3			100.1	101.9	-3.08	-3.08	Valve Adjustment:Audible Flow;Well Condition:Fair;Well Repairs:Valve
CV-24098	9/18/2025 2:37:11 PM	37.2	61.5	0.0	1.3	0.0			108.9	109.5	-6.00	-5.84	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header;Well Condition:Fair
CV-24099	9/2/2025 2:22:52 PM	16.2	79.6	0.0	4.2	0.0			109.6	109.8	-2.21	-2.23	Valve Comment:Unable to adjust;Well Condition:Fair

Table 2. LEA Selected Wells - August 2025
Chiquita Canyon Landfill

CV-24099	9/8/2025 9:45:58 AM	12.3	87.7	0.0	0.0	0.0			94.8	94.8	8.71	-0.50	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum
CV-24099	9/8/2025 9:47:03 AM	12.0	88.0	0.0	0.0	0.0			95.6	95.6	-0.52	-0.56	
CV-24099	9/17/2025 10:47:54 AM	12.3	84.6	0.0	3.1	0.0			108.8	109.7	-0.34	-0.32	
CV-24100	9/2/2025 2:04:58 PM	30.9	66.7	0.0	2.4	0.0			142.4	141.4	-1.91	-1.78	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Fair
CV-24100	9/2/2025 2:06:02 PM	30.5	67.4	0.0	2.1	0.0			142.8	141.4	-1.57	-1.57	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Fair
CV-24100	9/8/2025 8:45:00 AM							4500					Air Tech Lab; [User entered 0.45%]
CV-24100	9/8/2025 8:45:00 AM						17						Air Tech Lab
CV-24100	9/18/2025 2:29:29 PM	24.0	73.8	0.0	2.2	0.0			144.4	144.2	-1.40	-0.09	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Fair
CV-24100	9/18/2025 2:32:23 PM	24.3	74.2	0.0	1.5	0.0			144.6	144.1	-0.05	-0.06	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Fair
CV-24101	9/2/2025 2:00:02 PM	31.4	41.7	1.2	25.7	21.4			116.2	116.0	-1.53	-1.39	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Fair
CV-24101	9/8/2025 8:40:00 AM							4100					Air Tech Lab; [User entered 0.41%]
CV-24101	9/8/2025 8:40:00 AM						19						Air Tech Lab
CV-24101	9/17/2025 10:22:43 AM	18.8	35.1	2.8	43.3	15.5			112.2	112.2	-4.66	-4.58	
CV-24102	9/8/2025 9:18:43 AM	43.6	37.4	0.0	19.0	0.0			111.8	111.8	-1.78	-1.77	,,
CV-24102	9/17/2025 9:38:43 AM	34.0	41.2	0.1	24.7	247.0			116.8	116.8	-2.18	-2.17	
CV-24120	9/9/2025 9:41:57 AM	8.7	84.7	1.2	5.5	4.7			129.4	127.9	-5.75	-5.47	Valve Adjustment:Decreased Flow/Vacuum
CV-24120	9/9/2025 9:42:55 AM	8.8	85.4	1.0	4.8	4.7			127.9	128.2	-5.37	-5.37	Valve Adjustment:NSPS/EG CAC
CV-24120	9/11/2025 9:00:00 AM							72000					Air Tech Lab; [User entered 7.2%]
CV-24120	9/11/2025 9:00:00 AM						1300						Air Tech Lab
CV-24120	9/29/2025 9:37:29 AM	9.3	83.8	0.3	6.6	20.6			126.7	126.4	-4.86	-4.45	
CV-24121	9/2/2025 9:45:00 AM							5300					Air Tech Lab; [User entered 0.53%]
CV-24121	9/2/2025 9:45:00 AM						74						Air Tech Lab
CV-24121	9/9/2025 9:34:59 AM	24.5	74.9	0.3	0.4	1.2			121.3	121.3	-4.53	-3.07	Valve Adjustment:Decreased Flow/Vacuum
CV-24121	9/29/2025 9:30:55 AM	25.8	72.7	0.1	1.4	19.9			118.8	119.9	-2.75	-2.75	
CV-24122	9/2/2025 9:30:00 AM							3600					Air Tech Lab; [User entered 0.36%]
CV-24122	9/2/2025 9:30:00 AM						0						Air Tech Lab
CV-24122	9/9/2025 9:27:27 AM	49.7	48.0	0.2	2.2	12.7			120.5	120.4	-7.49	-7.39	
CV-24122	9/29/2025 9:57:41 AM	52.7	43.2	0.0	4.1	0.0			119.8	120.9	-6.53	-9.57	Valve Adjustment:Increased Flow/Vacuum
CV-24123	9/17/2025 2:05:12 PM	49.9	46.8	0.0	3.3	0.0			117.0	117.3	-0.33	-0.75	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-24125-TP20	9/3/2025 8:50:00 AM							3800					Air Tech Lab; [User entered 0.38%]
CV-24125-TP20	9/3/2025 8:50:00 AM						36						Air Tech Lab
CV-24125-TP20	9/29/2025 9:13:59 AM	35.2	49.2	0.0	15.6	518.3			112.8	112.6	-8.56	-4.49	Valve Adjustment:Decreased Flow/Vacuum

Table 2. LEA Selected Wells - August 2025
Chiquita Canyon Landfill

CV-24126	9/11/2025 1:31:45 PM	10.2	42.4	7.2	40.2	5.6			163.8	163.8	-0.14	-0.12	Valve Adjustment:NSPS/EG CAI,High Temp,High O2
CV-24126	9/11/2025 1:32:45 PM	10.1	42.5	7.2	40.2	5.6			163.4	163.2	-0.11	-0.10	Valve Adjustment:High Temp,High O2
CV-24126	9/18/2025 11:42:24 AM	12.8	63.3	5.0	18.9	3.8			174.1	174.2	-2.52	-2.40	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In)
CV-24126	9/22/2025 1:07:42 PM	3.2	66.1	2.6	28.1	10.8			184.9	185.5	-8.03	-7.82	Valve Adjustment:High Temp
CV-24127	9/2/2025 10:20:00 AM							36000					Air Tech Lab; [User entered 3.6%]
CV-24127	9/2/2025 10:20:00 AM						480						Air Tech Lab
CV-24127	9/5/2025 2:23:46 PM	23.5	54.3	0.1	22.1	221.0			111.4	113.1	-3.87	-2.61	Valve Adjustment:Decreased Flow/Vacuum
CV-24127	9/30/2025 12:59:10 PM	14.2	29.1	7.4	49.4	6.7			102.7	100.6	-9.09	-1.57	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-24127	9/30/2025 1:32:54 PM	14.6	38.3	4.9	42.2	8.6			101.0	101.2	-0.94	-0.94	Valve Comment:Bolted down flange causing air intrusion;Valve Adjustment:NSPS/EG CAC
CV-24128	9/2/2025 10:00:00 AM							17000					Air Tech Lab; [User entered 1.7%]
CV-24128	9/2/2025 10:00:00 AM						120						Air Tech Lab
CV-24128	9/5/2025 1:54:54 PM	25.9	40.7	1.0	32.4	32.4			119.4	118.0	-5.22	-1.49	Valve Adjustment:Decreased Flow/Vacuum
CV-24134-TP19	9/8/2025 8:34:35 AM	41.8	56.2	0.0	2.0	0.0			136.4	127.0	-8.44	-3.41	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Good
CV-24134-TP19	9/8/2025 8:35:59 AM	41.3	54.8	0.0	3.9	0.0			126.5	125.2	-1.73	-1.73	Valve Adjustment:NSPS/EG CAC;Well Condition:Good
CV-24138	9/4/2025 9:30:00 AM							6400					Air Tech Lab; [User entered 0.64%]
CV-24138	9/4/2025 9:30:00 AM						19						Air Tech Lab
CV-24138	9/10/2025 9:06:38 AM	0.1	3.0	20.8	76.1	3.7			74.2	74.2	-9.30	-9.27	Valve Adjustment:High O2,Barely Open,Surging Liquid in Well (Watered In);Well Comment:valve possibly damaged;Well Condition:Poor
CV-24138	9/26/2025 9:09:34 AM	1.8	67.4	3.1	27.7	8.9			154.1	163.1	-7.93	-1.64	Valve Adjustment:NSPS/EG CAC,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header
CV-24138	9/30/2025 2:04:46 PM	2.2	66.3	1.8	29.7	16.5			183.1	183.9	-3.48	-3.47	Valve Adjustment:High Temp,Reduce Sys. Vac. - Flare Down;Well Condition:Pnumatic Pump Installed
CV-24139	9/4/2025 9:25:00 AM							11000					Air Tech Lab; [User entered 1.1%]
CV-24139	9/4/2025 9:25:00 AM						50						Air Tech Lab
CV-24139	9/10/2025 9:10:08 AM	0.0	0.4	21.5	78.1	3.6			106.3	106.4	-0.45	-0.47	Valve Adjustment:High O2,Barely Open,Surging Liquid in Well (Watered In)
CV-24139	9/26/2025 9:16:26 AM	0.0	8.2	20.7	71.1	3.4			110.0	110.1	-0.54	-0.57	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24140	9/4/2025 9:20:00 AM							180000					Air Tech Lab; [User entered 18%]
CV-24140	9/4/2025 9:20:00 AM						1100						Air Tech Lab
CV-24140	9/4/2025 9:44:56 AM	3.8	72.9	0.0	23.3	0.0			169.6	170.7	-1.79	-1.79	Valve Adjustment:No Flow Measurement,High Temp
CV-24140	9/4/2025 9:46:00 AM							150800					AtmAA; [User entered 15.08%]
CV-24140	9/4/2025 9:46:00 AM						1300						AtmAA

CV-24140	9/10/2025 1:44:43 PM		74.8	0.7					132.2	133.0	-3.07	-3.05	No Flow Measurement,High Temp,
CV-24140	9/10/2025 1:47:00 PM						1630						AtmAA
CV-24140	9/12/2025 2:03:32 PM	5.7	71.0	1.0	22.3	22.3			158.9	161.4	-3.54	-3.55	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24140	9/18/2025 10:57:14 AM	15.8	76.5	0.5	7.2	14.4			151.8	153.0	-4.53	-4.61	Valve Adjustment:No Flow Measurement,High Temp
CV-24140	9/24/2025 8:35:53 AM	3.1	69.9	2.7	24.3	9.0			164.9	169.5	-9.40	-9.25	Valve Adjustment:No Flow Measurement,High Temp;Well Comment:Pump not pumping upon arrival;Well Condition:Pnumatic Pump Installed
CV-24141	9/4/2025 9:10:00 AM						41						Air Tech Lab
CV-24141	9/12/2025 8:37:12 AM	46.5	41.8	0.9	10.8	12.0			74.6	73.5	-6.38	-6.38	Valve Adjustment:Audible Flow,Barely Open;Well Repairs:Valve
CV-24141	9/17/2025 2:05:06 PM	22.0	35.0	6.2	36.8	5.9			107.9	107.8	-7.52	-7.43	Valve Adjustment:NSPS/EG CAI,High O2,Valve 100% Closed;Well Comment:valve possibly damaged
CV-24141	9/17/2025 2:07:40 PM	23.6	38.9	4.4	33.1	7.5			108.3	108.2	-8.81	-8.80	Valve Adjustment:NSPS/EG CAC,Valve 100% Closed
CV-24142	9/4/2025 9:51:54 AM	4.7	68.0	1.8	25.5	14.2			166.0	166.8	-0.35	-0.44	Valve Adjustment:No Flow Measurement,High Temp
CV-24142	9/4/2025 9:53:00 AM							175900					AtmAA; [User entered 17.59%]
CV-24142	9/4/2025 9:53:00 AM						2670						AtmAA
CV-24142	9/8/2025 9:15:00 AM							130000					Air Tech Lab; [User entered 13%]
CV-24142	9/8/2025 9:30:00 AM						1300						Air Tech Lab
CV-24142	9/10/2025 1:52:20 PM	36.5	34.6	9.6	19.3	2.0			137.7	137.7	-1.33	-1.35	No Flow Measurement,No Adjustment Made,High O2
CV-24142	9/24/2025 2:22:25 PM	2.2	36.6	11.1	50.1	4.5			151.1	152.2	-0.99	-0.94	Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Decreased Flow/Vacuum;Well Condition:Poor
CV-24142	9/24/2025 2:22:58 PM	2.3	39.4	10.1	48.2	4.8			150.8	148.8	-0.86	-0.71	Valve Adjustment:NSPS/EG CAI,High Temp,High O2
CV-24142	9/30/2025 2:12:50 PM	2.9	54.0	5.3	37.8	7.1			156.0	155.2	-1.29	-1.23	Valve Adjustment:High Temp,High O2,Surging Liquid in Header
CV-24142	9/30/2025 2:15:54 PM	3.4	62.0	3.3	31.3	9.5			151.1	151.1	-1.13	-1.11	Valve Adjustment:No Flow Measurement,High Temp
CV-24143	9/4/2025 9:15:00 AM							180000					Air Tech Lab; [User entered 18%]
CV-24143	9/4/2025 9:15:00 AM						1800						Air Tech Lab
CV-24143	9/10/2025 8:52:16 AM	0.9	63.8	5.8	29.5	5.1			68.7	68.6	1.86	1.81	Valve Adjustment:NSPS/EG CAI,High O2,Positive Static Press.,Valve 100% Open,Surging Liquid in Well (Watered In)
CV-24143	9/10/2025 8:53:21 AM	0.9	64.4	5.7	29.0	5.1			68.7	68.7	1.88	1.88	Valve Adjustment:High O2,Positive Static Press.,Surging Liquid in Well (Watered In)
CV-24143	9/26/2025 9:20:08 AM	2.8	70.1	3.6	23.5	6.5			79.9	80.3	1.96	1.82	Valve Adjustment:Positive Static Press.,Valve 100% Open,Surging Liquid in Header
CV-24143	9/26/2025 9:22:02 AM	2.6	71.1	3.5	22.8	6.5			79.3	78.8	1.77	1.89	Valve Adjustment:Positive Static Press.,Valve 100% Closed,Surging Liquid in Header
CV-24144	9/8/2025 2:04:31 PM	57.6	40.0	0.2	2.2	11.0			108.2	108.2	-0.96	-0.96	Reduced System Vacuum,,

Table 2. LEA Selected Wells - August 2025
Chiquita Canyon Landfill

CV-24144	9/17/2025 11:12:19 AM	55.0	43.6	0.0	1.4	0.0			105.1	105.2	-1.34	-1.30	
CV-99	9/2/2025 9:35:00 AM						0						Air Tech Lab
CV-99	9/11/2025 2:34:59 PM	33.1	66.5	0.0	0.4	0.0			101.6	100.2	-0.51	-0.59	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum;Well Condition:Fair
H-1770N	9/9/2025 8:25:00 AM							5000					Air Tech Lab; [User entered 0.50%]
H-1770N	9/9/2025 8:25:00 AM						56						Air Tech Lab
H-1770N	9/9/2025 10:18:27 AM	27.5	72.5	0.0	0.0	0.0			108.3	108.3	-0.46	-0.46	
H-1770N	9/16/2025 9:58:12 AM	23.4	76.3	0.3	0.0	0.0			104.1	102.6	-0.89	-0.88	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum
H-1770N	9/16/2025 10:05:15 AM	22.9	77.1	0.1	0.0	0.0			107.0	108.9	-0.96	-0.97	Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum
H-2165W	9/2/2025 2:08:31 PM	24.2	72.7	0.0	3.1	0.0			121.2	121.5	-0.79	-0.40	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Good
H-2165W	9/8/2025 8:50:00 AM							9400					Air Tech Lab; [User entered 0.94%]
H-2165W	9/8/2025 8:50:00 AM						41						Air Tech Lab
H-2165W	9/17/2025 10:28:09 AM	19.1	77.1	0.2	3.6	18.0			134.0	133.8	-1.42	-1.39	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
H-2165W	9/17/2025 10:29:10 AM	19.1	76.7	0.0	4.2	0.0			133.2	133.1	-1.39	-1.31	Valve Adjustment:High Temp
H-2273W	9/2/2025 11:28:47 AM	37.9	50.5	0.0	11.6	0.0			128.5	128.6	-0.62	-0.66	
H-2273W	9/10/2025 10:25:00 AM							15000					Air Tech Lab; [User entered 1.5%]
H-2273W	9/10/2025 10:25:00 AM						110						Air Tech Lab
H-2273W	9/17/2025 9:31:19 AM	32.1	47.4	0.0	20.5	0.0			128.4	128.2	-0.97	-0.75	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Fair

Attachment B

Down Well Temperatures

And

List of Wells for Monitoring

Temperatures

LEA Selected Wells for Down Hole Temperature Monitoring
September 2025

Well Number	Down Well Temp Monitoring (Annually)	Date Monitored for Annual Downwell temperatures	Comments
CV-100	NA	NA	Abandoned Well
CV-103	Yes	3/3/2025	
CV-108-52	Yes	3/4/2025	
CV-113	Yes	3/10/2025	
CV-1532	NA	NA	Abandoned Well
CV-1532A	Yes	3/10/2025	
CV-1535	Yes	3/4/2025	
CV-1902A	Yes	3/18/2025	
CV-2001	Yes	3/4/2025	
CV-2002	Yes	6/2/2025	
CV-2007	Yes	3/5/2025	
CV-2202	NA	NA	Abandoned Well
CV-2301	Yes	3/11/2025	Pump offline - equipment is damaged in the well casing. No timeline on repairs due to safety at this time.
CV-2302	Yes	3/11/2025	Pump is off line for liner installation
CV-2303	Yes	3/11/2025	graph attached 9-1 to 9-30
CV-2312	Yes	3/5/2025	
CV-2315	Yes	3/19/2025	graph attached 9-1 to 9-30
CV-2341	Yes	3/5/2025	
CV-2350	Yes	3/12/2025	graph attached 9-1 to 9-30
CV-2351	Yes	3/12/2025	graph attached 9-1 to 9-2, then offline remainder of September
CV-2352	Yes	3/12/2025	Offline - pump needs repair/replacement
CV-2353	Yes	5/30/2025	
CV-24007	Yes	3/6/2025	
CV-24017	Yes	3/6/2025	Offline - pump needs repair/replacement
CV-24053	Yes	3/6/2025	
CV-24065	Yes	3/6/2025	graph attached 9-1 to 9-27-2025. Pump needs repair/ replacement
CV-24095	Yes	3/7/2025	Pump remained off line/removed during September 2025. Pump is off line for liner installation
CV-24101	Yes	3/7/2025	
CV-24122	Yes	3/7/2025	
CV-24127	Yes	3/7/2025	
CV-24138	Yes	4/1/2025	
CV-24139	Yes	8/18/2025	Two readings in 2025
CV-24143	Yes	3/10/2025	
TC-2385A	NA	NA	Abandoned Well



29 Sep 2025 16:31 (UTC -7)
Temperature sensor [Analog 1]: 201.2 °F
CV-2303
September 2, 2025
September 4, 2025
September 6, 2025
September 8, 2025
September 10, 2025
September 12, 2025
September 14, 2025
September 16, 2025
September 18, 2025
September 20, 2025
September 22, 2025
September 24, 2025
September 26, 2025
September 28, 2025
September 30, 2025



20 Sep 2025 00:15 (UTC -7)
Lorentz Temp. Sensor [Analog 1]: 160.6 °F
CV-2315
September 2, 2025
September 4, 2025
September 6, 2025
September 8, 2025
September 10, 2025
September 12, 2025
September 14, 2025
September 16, 2025
September 18, 2025
September 20, 2025
September 22, 2025
September 24, 2025
September 26, 2025
September 28, 2025
September 30, 2025



20 Sep 2025 00:15 (UTC -7)
Lorentz Temp. Sensor [Analog 1]: 160.6 °F
CV-2315
September 2, 2025
September 4, 2025
September 6, 2025
September 8, 2025
September 10, 2025
September 12, 2025
September 14, 2025
September 16, 2025
September 18, 2025
September 20, 2025
September 22, 2025
September 24, 2025
September 26, 2025
September 28, 2025
September 30, 2025


21 Sep 2025 13:14 (UTC -7)
Temp. Sensor [Analog 1]: 137.5 °F
CV-2350
September 2, 2025
September 4, 2025
September 6, 2025
September 8, 2025
September 10, 2025
September 12, 2025
September 14, 2025
September 16, 2025
September 18, 2025
September 20, 2025
September 22, 2025
September 24, 2025
September 26, 2025
September 28, 2025
September 30, 2025


02 Sep 2025 01:38 (UTC -7)
Lorentz Temp. Sensor [Analog 1]: 266.7 °F
CV-2351
12:00 AM
6:00 AM
12:00 PM
6:00 PM
September 2, 2025
6:00 AM
12:00 PM
6:00 PM
September 3, 2025
6:00 AM
12:00 PM
6:00 PM
September 4, 2025
6:00 AM
12:00 PM
6:00 PM


16 Sep 2025 09:58 (UTC -7)
Temp. Sensor [Analog 1]: 146 °F
CV-24065
September 2, 2025
September 4, 2025
September 6, 2025
September 8, 2025
September 10, 2025
September 12, 2025
September 14, 2025
September 16, 2025
September 18, 2025
September 20, 2025
September 22, 2025
September 24, 2025
September 26, 2025
September 28, 2025
September 30, 2025

Attachment C

Item 7 – Well Location Map



N

GRAPHIC SCALE

150 75 0 150 300 150

SCALE: 1"=150'

LEGEND

1150	TOPOGRAPHIC CONTOUR
	EXISTING CELL LIMITS (APPROXIMATE)
CV-XX	EXISTING VERTICAL LFG EXTRACTION WELL
H-XX	EXISTING HORIZONTAL COLLECTOR
	EXISTING HORIZONTAL COLLECTOR PERFORATED PIPE
	REACTION AREA BOUNDARY (APPROXIMATE) - BASED ON DATA REVIEW
	REACTION AREA BOUNDARY - CONDITION 9A

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY BLUE RIDGE SERVICES. AERIAL PHOTOGRAPHY DATED JULY 09, 2025.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.
3. THE LOCATION OF ANY EXISTING GCCS COMPONENTS AND OTHER FEATURES ARE APPROXIMATE AND SHOULD BE USED FOR INFORMATION PURPOSES ONLY. ACTUAL FIELD CONDITIONS MAY VARY AND SUBJECT TO CHANGE BASED ON FUTURE FILL OPERATIONS, WASTE PLACEMENT, TOPOGRAPHIC FEATURES, AND OTHER SITE-SPECIFIC FACTORS.

NO.	REVISION	DATE

SHEET TITLE: EXISTING VERTICAL & HORIZONTAL LFG EXTRACTION WELL MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
8799 BALBOA AVENUE SUITE 290
SAN DIEGO, CA 92123
(858) 571-5500 FAX. (562) 427-0805

PROJ. NO.: 01204123.41
DSN. BY: -
DWN. BY: SRM
CHK. BY: -
ACAD FILE: F:/FIELD SERVICES
APP. BY: -

DATE: 08/14/2025

SCALE: AS SHOWN

SHEET: 1

N:\CAD\ASBUILT - MASTERS\CHIQUITA\GCCS\2025 ACAD\2025 CCLF_Existing Well Map-For LEA Response_2025-08-14.dwg Aug 14, 2025 - 9:46am By: smedina



GRAPHIC SCALE

150 75 0 150 300 450

SCALE: 1"=150'

LEGEND

1150	TOPOGRAPHIC CONTOUR
	EXISTING CELL LIMITS (APPROXIMATE)
CV-XX	EXISTING LFG VERTICAL EXTRACTION WELL
CV-XX PLR	EXISTING LFG VERTICAL EXTRACTION WELL - PRESSURIZED LEACHATE RELEASE
BH-GB	EXISTING GABION LFG COLLECTOR WELL
SW-XX	EXISTING SOIL VAPOR EXTRACTION WELL
FP-XX	EXISTING SURFACE COLLECTOR WELLHEAD
H-XX	EXISTING HORIZONTAL WELLS
C-XX	EXISTING REMOTE VERTICAL WELLHEAD
GP-XX	EXISTING PERIMETER MIGRATION PROBE
TP-XX	EXISTING TEMPERATURE PROBE
	EXISTING ISOLATION VALVE
AC	EXISTING ACTIVATED CARBON VESSEL
	EXISTING CONDENSATE SUMP
	EXISTING HDPE LINER RISER
	EXISTING CORRUGATED LINER RISER
36"	EXISTING 36" LFG COLLECTION HEADER PIPING
30"	EXISTING 30" LFG COLLECTION HEADER PIPING
24"	EXISTING 24" LFG COLLECTION HEADER PIPING
20"	EXISTING 20" LFG COLLECTION HEADER PIPING
18"	EXISTING 18" LFG COLLECTION HEADER PIPING
12"	EXISTING 12" LFG COLLECTION HEADER PIPING
10"	EXISTING 10" LFG COLLECTION HEADER PIPING
8"	EXISTING 8" LFG COLLECTION LATERAL PIPING
4"/6"	EXISTING 4"/6" LFG COLLECTION LATERAL PIPING
2"/3"	EXISTING 2"/3" LFG COLLECTION LATERAL PIPING
	BELOW-GRADE PIPES ARE SHOWN DASHED
	REACTION AREA BOUNDARY (APPROXIMATE) - BASED ON DATA REVIEW
	EXISTING CAP
	EXISTING FRAC TANKS

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLOR. AERIAL PHOTOGRAPHY DATED SEPTEMBER 24, 2025.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.
3. THE LOCATION OF ANY EXISTING PIPING, VALVES, TIE-IN LOCATIONS AND OTHER FEATURES ARE APPROXIMATE AND SHOULD BE USED FOR INFORMATION PURPOSES ONLY. ACTUAL FIELD CONDITIONS MAY VARY AND SUBJECT TO CHANGE BASED ON FUTURE FILL OPERATIONS, WASTE PLACEMENT, TOPOGRAPHIC FEATURES, AND OTHER SITE-SPECIFIC FACTORS.
4. EXISTING GCCS AS-BUILT DATED OCTOBER 01, 2025.

NO. | REVISION | DATE

SHEET TITLE: EXISTING GCCS MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS

DATE: 10/01/2025

SCALE: AS SHOWN

1 of 1

Attachment D

Milestone 5 Compliance Data



Ranges Mapped

		# Points
>= 0	and < 25	225
>= 25	and < 48	276
>= 48	and < 52	76
>= 52	and < 58	88
>= 58	and < 101	5
N/A	N/A	10

Point Type Legend

well

N

SCSeTools

Chiquita Canyon Landfill

Range Map

Parameter: CH4 (mid range)

Analysis Method: Average

Date Range: 09/01/2025 - 09/30/2025

Map generation date : 10/07/2025



Ranges Mapped

		# Points
	>= 0 and < 0.5	47
	>= 0.5 and < 0.9	23
	>= 0.9 and < 1.1	2
	>= 1.1 and < 1.5	3
	>= 1.5 and < 101	
	N/A	N/A

Point Type Legend

well

N

SCSeTools

Chiquita Canyon Landfill

Range Map

Parameter: CH4/CO2 Ratio (high range)

Analysis Method: Average

Date Range: 09/01/2025 - 09/30/2025

Map generation date : 10/07/2025



Ranges Mapped

		# Points
>= 0	and < 25	3
>= 25	and < 45	11
>= 45	and < 55	10
>= 55	and < 65	15
>= 65	and < 101	36
N/A		N/A

Point Type Legend

well

N

SCSeTools

Chiquita Canyon Landfill

Range Map

Parameter: CO_2 (mid range)

Analysis Method: Average

Date Range: 09/01/2025 - 09/30/2025

Map generation date : 10/07/2025



Ranges Mapped

	# Points
>= 0 and < 500	27
>= 500 and < 1000	6
>= 1000 and < 1500	7
>= 1500 and < 2000	8
>= 2000 and < 100000	11

Point Type Legend

well

N

SCSeTools

Chiquita Canyon Landfill

Range Map

Parameter: CO (mid range)

Analysis Method: Average

Date Range: 09/01/2025 - 09/30/2025

Map generation date : 10/07/2025



Ranges Mapped

				# Points
>= 0	and	<	2000	2
>= 2000	and	<	5000	6
>= 5000	and	<	10000	5
>= 10000	and	<	50000	17
>= 50000	and	<	100000	11
>= 100000	and	<	1000000	17

Point Type Legend

well

N

SCSeTools

Chiquita Canyon Landfill

Range Map

Parameter: H2 (mid range)

Analysis Method: Average

Date Range: 09/01/2025 - 09/30/2025

Map generation date : 10/07/2025



Ranges Mapped

		# Points
	>= 0 and < 0.5	42
	>= 0.5 and < 2	16
	>= 2 and < 3.5	2
	>= 3.5 and < 5	6
	>= 5 and < 101	9
	N/A	N/A

Point Type Legend

well

N

SCSeTools

Chiquita Canyon Landfill

Range Map

Parameter: O2 (mid range)

Analysis Method: Average

Date Range: 09/01/2025 - 09/30/2025

Map generation date : 10/07/2025



Ranges Mapped

		# Points
Cyan	>= -50 and < 131	50
Green	>= 131 and < 150	8
Yellow	>= 150 and < 165	7
Orange	>= 165 and < 180	7
Magenta	>= 180 and < 999	3
Grey	N/A	N/A

Point Type Legend

well

N

SCSeTools

Chiquita Canyon Landfill

Range Map

Parameter: Adj Temp (high range)

Analysis Method: Average

Date Range: 09/01/2025 - 09/30/2025

Map generation date : 10/07/2025



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-99 / CV-99

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point IDs / Names

CV-99 / CV-99

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point ID / Name

CHWCV103 / CV-103

Parameter / Unit

Init. Flow / scfm

% CH4 / %

% CO2 / %

% O2 / %

% Bal Gas / %

Init. Static Press / in. H2O

Init. Temp / Deg. F

Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-103 / CV-103

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point IDs / Names

CV-103 / CV-103

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point ID / Name

CV108-52 / CV-108-52

Parameter / Unit

Init. Flow / scfm
% CH4 / %
% CO2 / %
% O2 / %
% Bal Gas / %
Init. Static Press / in. H2O
Init. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart

Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-108-52 / CV-108-52

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Point IDs / Names

CV-108-52 / CV-108-52

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart

Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-113 / CV-113

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point IDs / Names

CV-113 / CV-113

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point ID / Name

CHWCV114 / CV-114

Parameter / Unit

Init. Flow / scfm

% CH4 / %

% CO2 / %

% O2 / %

% Bal Gas / %

Init. Static Press / in. H2O

Init. Temp / Deg. F

Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-114 / CV-114

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

<u>Point IDs / Names</u>

CV-114 / CV-114

<u>Parameter / Unit</u>

Hydrogen / vol%

SCSeTools



Point ID / Name

CHCV1423 / CV-1423

Parameter / Unit

Init. Flow / scfm

% CH4 / %

% CO2 / %

% O2 / %

% Bal Gas / %

Init. Static Press / in. H2O

Init. Temp / Deg. F

Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-1423 / CV-1423

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-1423 / CV-1423

Parameter / Unit

Hydrogen / vol%

SCSeTools



Point ID / Name

CCV1532A / CV-1532A

Parameter / Unit

Init. Flow / scfm
% CH4 / %
% CO2 / %
% O2 / %
% Bal Gas / %
Init. Static Press / in. H2O
Init. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-1532A / CV-1532A

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Point IDs / Names

CV-1532A / CV-1532A

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-1535 / CV-1535

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Point IDs / Names

CV-1535 / CV-1535

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-1902A / CV-1902A

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-1902A / CV-1902A

Parameter / Unit

Hydrogen / vol%

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25



Point IDs / Names

CV-2001 / CV-2001

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart

Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point IDs / Names

CV-2001 / CV-2001

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

<u>Point IDs / Names</u>

CV-2002 / CV-2002

<u>Parameter / Unit</u>

Carbon Monoxide / ppmv

SCSeTools



Point IDs / Names

CV-2002 / CV-2002

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-2007 / CV-2007

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-2007 / CV-2007

Parameter / Unit

Hydrogen / vol%

SCSeTools



Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-2301 / CV-2301

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-2301 / CV-2301

Parameter / Unit

Hydrogen / vol%

SCSeTools



Point ID / Name

CHCV2302 / CV-2302

Parameter / Unit

Init. Flow / scfm

% CH4 / %

% CO2 / %

% O2 / %

% Bal Gas / %

Init. Static Press / in. H2O

Init. Temp / Deg. F

Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-2302 / CV-2302

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart

Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-2302 / CV-2302

Parameter / Unit

Hydrogen / vol%

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-2303 / CV-2303

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

<u>Point IDs / Names</u>

● CV-2303 / CV-2303

<u>Parameter / Unit</u>

Hydrogen / vol%

SCSeTools



Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-2305 / CV-2305

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart

Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-2305 / CV-2305

Parameter / Unit

Hydrogen / vol%

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-2312 / CV-2312

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point IDs / Names

CV-2312 / CV-2312

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-2314 / CV-2314

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point IDs / Names

CV-2314 / CV-2314

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart

Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point ID / Name

CHCV2315 / CV-2315

Parameter / Unit

Init. Flow / scfm
% CH4 / %
% CO2 / %
% O2 / %
% Bal Gas / %
Init. Static Press / in. H2O
Init. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-2315 / CV-2315

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-2315 / CV-2315

Parameter / Unit

Hydrogen / vol%

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-2328 / CV-2328

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Point IDs / Names

CV-2328 / CV-2328

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-2333 / CV-2333

Parameter / Unit

Hydrogen / vol%

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

<u>Point IDs / Names</u>

● CV-2334 / CV-2334

<u>Parameter / Unit</u>

Carbon Monoxide / ppmv

SCSeTools



Point IDs / Names

CV-2334 / CV-2334

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point ID / Name

CHCV2337 / CV-2337

Parameter / Unit

Init. Flow / scfm
% CH4 / %
% CO2 / %
% O2 / %
% Bal Gas / %
Init. Static Press / in. H2O
Init. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-2337 / CV-2337

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-2337 / CV-2337

Parameter / Unit

Hydrogen / vol%

SCSeTools



Point ID / Name

CHCV2341 / CV-2341

Parameter / Unit

Init. Flow / scfm
% CH4 / %
% CO2 / %
% O2 / %
% Bal Gas / %
Init. Static Press / in. H2O
Init. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart

Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point ID / Name

CHCV2344 / CV-2344

Parameter / Unit

Init. Flow / scfm
% CH4 / %
% CO2 / %
% O2 / %
% Bal Gas / %
Init. Static Press / in. H2O
Init. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-2344 / CV-2344

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point ID / Name

CHCV2345 / CV-2345

Parameter / Unit

Init. Flow / scfm

% CH4 / %

% CO2 / %

% O2 / %

% Bal Gas / %

Init. Static Press / in. H2O

Init. Temp / Deg. F

Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-2345 / CV-2345

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-2345 / CV-2345

Parameter / Unit

Hydrogen / vol%

SCSeTools



Point ID / Name

CHCV2346 / CV-2346

Parameter / Unit

Init. Flow / scfm
% CH4 / %
% CO2 / %
% O2 / %
% Bal Gas / %
Init. Static Press / in. H2O
Init. Temp / Deg. F

Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-2346 / CV-2346

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-2346 / CV-2346

Parameter / Unit

Hydrogen / vol%

SCSeTools

Point ID / Name

CHCV2347 / CV-2347

Parameter / Unit



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-2347 / CV-2347

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart

Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point IDs / Names

CV-2347 / CV-2347

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point ID / Name

CHCV2348 / CV-2348

Parameter / Unit

Init. Flow / scfm

% CH4 / %

% CO2 / %

% O2 / %

% Bal Gas / %

Init. Static Press / in. H2O

Init. Temp / Deg. F

Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-2348 / CV-2348

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Point IDs / Names

CV-2348 / CV-2348

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point ID / Name

CHCV2349 / CV-2349

Parameter / Unit

Init. Flow / scfm
% CH4 / %
% CO2 / %
% O2 / %
% Bal Gas / %
Init. Static Press / in. H2O
Init. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-2349 / CV-2349

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-2350 / CV-2350

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

<u>Point IDs / Names</u>

● CV-2350 / CV-2350

<u>Parameter / Unit</u>

Hydrogen / vol%

SCSeTools



Point ID / Name

CHCV2351 / CV-2351

Parameter / Unit

Init. Flow / scfm

% CH4 / %

% CO2 / %

% O2 / %

% Bal Gas / %

Init. Static Press / in. H2O

Init. Temp / Deg. F

Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-2351 / CV-2351

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

<u>Point IDs / Names</u>

CV-2351 / CV-2351

<u>Parameter / Unit</u>

Hydrogen / vol%

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-2352 / CV-2352

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-2352 / CV-2352

Parameter / Unit

Hydrogen / vol%

SCSeTools



Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

<u>Point IDs / Names</u>

● CV-2353 / CV-2353

<u>Parameter / Unit</u>

Carbon Monoxide / ppmv

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-2354 / CV-2354

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-2354 / CV-2354

Parameter / Unit

Hydrogen / vol%

SCSeTools



Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-24002 / CV-24002

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point ID / Name

CCV24007 / CV-24007

Parameter / Unit

Init. Flow / scfm

% CH4 / %

% CO2 / %

% O2 / %

% Bal Gas / %

Init. Static Press / in. H2O

Init. Temp / Deg. F

Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-24007 / CV-24007

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

<u>Point IDs / Names</u>

● CV-24007 / CV-24007

<u>Parameter / Unit</u>

Hydrogen / vol%

SCSeTools



Point ID / Name

CCV24017 / CV-24017

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

<u>Point IDs / Names</u>

CV-24017 / CV-24017

<u>Parameter / Unit</u>

Carbon Monoxide / ppmv

SCSeTools



Point IDs / Names

CV-24017 / CV-24017

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24049 / CV-24049

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Point IDs / Names

CV-24049 / CV-24049

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart

Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-24053 / CV-24053

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart

Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point IDs / Names

CV-24053 / CV-24053

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart

Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24055 / CV-24055

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24055 / CV-24055

Parameter / Unit

Hydrogen / vol%

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

<u>Point IDs / Names</u>

● CV-24062 / CV-24062

<u>Parameter / Unit</u>

Carbon Monoxide / ppmv

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

<u>Point IDs / Names</u>

CV-24062 / CV-24062

<u>Parameter / Unit</u>

Hydrogen / vol%

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-24063 / CV-24063

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart

Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point ID / Name

CCV24064 / CV-24064

Parameter / Unit

Init. Flow / scfm
% CH4 / %
% CO2 / %
% O2 / %
% Bal Gas / %
Init. Static Press / in. H2O
Init. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

● CV-24064 / CV-24064

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24064 / CV-24064

Parameter / Unit

Hydrogen / vol%

SCSeTools



Point ID / Name

CCV24065 / CV-24065-TP17

Parameter / Unit

Init. Flow / scfm
% CH4 / %
% CO2 / %
% O2 / %
% Bal Gas / %
Init. Static Press / in. H2O
Init. Temp / Deg. F

Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-24065 / CV-24065

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point IDs / Names

CV-24065 / CV-24065

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24066 / CV-24066

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24066 / CV-24066

Parameter / Unit

Hydrogen / vol%

SCSeTools



Point ID / Name

CCV24069 / CV-24069

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F

Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart

Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24069 / CV-24069

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Point IDs / Names

CV-24069 / CV-24069

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart

Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point IDs / Names

CV-24070 / CV-24070

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24071 / CV-24071

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



<u>Point ID / Name</u>

CCV24075 / CV-24075-TP15

<u>Parameter / Unit</u>

Init. Flow / scfm
% CH4 / %
% CO2 / %
% O2 / %
% Bal Gas / %
Init. Static Press / in. H2O
Init. Temp / Deg. F

Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-24075 / CV-24075

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24075 / CV-24075

Parameter / Unit

Hydrogen / vol%

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-24077 / CV-24077

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart

Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24079 / CV-24079

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24079 / CV-24079

Parameter / Unit

Hydrogen / vol%

SCSeTools



Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart

Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point IDs / Names

CV-24082 / CV-24082

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point ID / Name

CCV24083 / CV-24083

Parameter / Unit

Init. Flow / scfm
% CH4 / %
% CO2 / %
% O2 / %
% Bal Gas / %
Init. Static Press / in. H2O
Init. Temp / Deg. F

Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24083 / CV-24083

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Point IDs / Names

CV-24083 / CV-24083

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24084-TP11 / CV-24084-TP11

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Point IDs / Names

CV-24084-TP11 / CV-24084-TP11

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-24088 / CV-24088

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point IDs / Names

CV-24088 / CV-24088

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24095 / CV-24095

Parameter / Unit

Hydrogen / vol%

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-24096 / CV-24096

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24096 / CV-24096

Parameter / Unit

Hydrogen / vol%

SCSeTools



Point ID / Name

CCV24097 / CV-24097

Parameter / Unit

Init. Flow / scfm
% CH4 / %
% CO2 / %
% O2 / %
% Bal Gas / %
Init. Static Press / in. H2O
Init. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24097 / CV-24097

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Point IDs / Names

CV-24097 / CV-24097

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart

Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point ID / Name

CCV24098 / CV-24098

Parameter / Unit

Init. Flow / scfm
% CH4 / %
% CO2 / %
% O2 / %
% Bal Gas / %
Init. Static Press / in. H2O
Init. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-24098 / CV-24098

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

<u>Point IDs / Names</u>

● CV-24098 / CV-24098

<u>Parameter / Unit</u>

Hydrogen / vol%

SCSeTools



Point ID / Name

CCV24099 / CV-24099

Parameter / Unit

Init. Flow / scfm

% CH4 / %

% CO2 / %

% O2 / %

% Bal Gas / %

Init. Static Press / in. H2O

Init. Temp / Deg. F

Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-24099 / CV-24099

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24099 / CV-24099

Parameter / Unit

Hydrogen / vol%

SCSeTools



Point ID / Name

CCV24100 / CV-24100

Parameter / Unit

Init. Flow / scfm
% CH4 / %
% CO2 / %
% O2 / %
% Bal Gas / %
Init. Static Press / in. H2O
Init. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24100 / CV-24100

Parameter / Unit

Hydrogen / vol%

SCSeTools



Point ID / Name

CCV24101 / CV-24101

Parameter / Unit

Init. Flow / scfm

% CH4 / %

% CO2 / %

% O2 / %

% Bal Gas / %

Init. Static Press / in. H2O

Init. Temp / Deg. F

Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

<u>Point IDs / Names</u>

CV-24101 / CV-24101

<u>Parameter / Unit</u>

Carbon Monoxide / ppmv

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24101 / CV-24101

Parameter / Unit

Hydrogen / vol%

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24102 / CV-24102

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Point IDs / Names

CV-24102 / CV-24102

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-24120 / CV-24120

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-24121 / CV-24121

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point IDs / Names

CV-24121 / CV-24121

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart

Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25



Point IDs / Names

CV-24122 / CV-24122

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point IDs / Names

CV-24122 / CV-24122

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point ID / Name

CCV24123 / CV-24123

Parameter / Unit

Init. Flow / scfm
% CH4 / %
% CO2 / %
% O2 / %
% Bal Gas / %
Init. Static Press / in. H2O
Init. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-24123 / CV-24123

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point IDs / Names

CV-24123 / CV-24123

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point ID / Name

CCV24125 / CV-24125-TP20

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F

Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-24125 / CV-24125

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart

Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24125 / CV-24125

Parameter / Unit

Hydrogen / vol%

SCSeTools



Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24126 / CV-24126

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025



Point ID / Name

CCV24127 / CV-24127

Parameter / Unit

Init. Flow / scfm

% CH4 / %

% CO2 / %

% O2 / %

% Bal Gas / %

Init. Static Press / in. H2O

Init. Temp / Deg. F

Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

<u>Point IDs / Names</u>

● CV-24127 / CV-24127

<u>Parameter / Unit</u>

Carbon Monoxide / ppmv

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24127 / CV-24127

Parameter / Unit

Hydrogen / vol%

SCSeTools



Point ID / Name

CCV24128 / CV-24128

Parameter / Unit

Init. Flow / scfm
% CH4 / %
% CO2 / %
% O2 / %
% Bal Gas / %
Init. Static Press / in. H2O
Init. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point IDs / Names

CV-24128 / CV-24128

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart

Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25



Chiquita Canyon Landfill - LAB DATA
Points Chart

Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24134 / CV-24134

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24134 / CV-24134

Parameter / Unit

Hydrogen / vol%

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-24138 / CV-24138

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point IDs / Names

CV-24138 / CV-24138

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24139 / CV-24139

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24139 / CV-24139

Parameter / Unit

Hydrogen / vol%

SCSeTools



Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point IDs / Names

CV-24140 / CV-24140

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point ID / Name

CCV24141 / CV-24141

Parameter / Unit

Init. Flow / scfm
% CH4 / %
% CO2 / %
% O2 / %
% Bal Gas / %
Init. Static Press / in. H2O
Init. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-24141 / CV-24141

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point IDs / Names

CV-24141 / CV-24141

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025



Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart

Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24142 / CV-24142

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Point IDs / Names

CV-24142 / CV-24142

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24143 / CV-24143

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

<u>Point IDs / Names</u>

● CV-24143 / CV-24143

<u>Parameter / Unit</u>

Hydrogen / vol%

SCSeTools



Point ID / Name

CCV24144 / CV-24144

Parameter / Unit

Init. Flow / scfm
% CH4 / %
% CO2 / %
% O2 / %
% Bal Gas / %
Init. Static Press / in. H2O
Init. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

CV-24144 / CV-24144

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

CV-24144 / CV-24144

Parameter / Unit

Hydrogen / vol%

SCSeTools



Point ID / Name

CHH1770N / H-1770N

Parameter / Unit

Init. Flow / scfm
% CH4 / %
% CO2 / %
% O2 / %
% Bal Gas / %
Init. Static Press / in. H2O
Init. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

H-1770N / H-1770N

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



<u>Point ID / Name</u>

CHH2165W / H-2165W

<u>Parameter / Unit</u>

Init. Flow / scfm

% CH4 / %

% CO2 / %

% O2 / %

% Bal Gas / %

Init. Static Press / in. H2O

Init. Temp / Deg. F

Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Point IDs / Names

H-2165W / H-2165W

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

<u>Point IDs / Names</u>

● H-2165W / H-2165W

<u>Parameter / Unit</u>

Hydrogen / vol%

SCSeTools



Point ID / Name

CHH2273W / H-2273W

Parameter / Unit

Init. Flow / scfm
% CH4 / %
% CO2 / %
% O2 / %
% Bal Gas / %
Init. Static Press / in. H2O
Init. Temp / Deg. F

Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

H-2273W / H-2273W

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Point IDs / Names

● H-2273W / H-2273W

Parameter / Unit

Hydrogen / vol%

SCSeTools



Point ID / Name

CSC2001W / SC-2001W

Parameter / Unit

Init. Flow / scfm
% CH4 / %
% CO2 / %
% O2 / %
% Bal Gas / %
Init. Static Press / in. H2O
Init. Temp / Deg. F

Chiquita Canyon Landfill

Parameter Chart: Uniscale

Date Range: 01/01/2025 - 09/30/2025

Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point IDs / Names

SC-2001W / SC-2001W

Parameter / Unit

Hydrogen / vol%

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Point ID / Name

CTC2383S / TC-2383S

Parameter / Unit

Init. Flow / scfm
% CH4 / %
% CO2 / %
% O2 / %
% Bal Gas / %
Init. Static Press / in. H2O
Init. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Uniscale
Date Range: 01/01/2025 - 09/30/2025
Chart generation date: 10/1/25

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 09/01/2024 to 09/30/2025

Chart generation date : 10/06/2025

Thirty Day Maximum Vertical Temperature Map from Temperature Probes at the Chiquita Canyon Landfill - September 2025



BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	166	15
TP02	158	60
TP03	234	45
TP04	163	30
TP05	156	75
TP06	140	80
TP07	153	100
TP08	181	150
TP09	209	125
TP10	149	125
TP11	185	125
TP12	148	125
TP13	168	140
TP14	170	150
TP15	202	100
TP16	143	15
TP17	151	125
TP18	162	45
TP19	164	150
TP20	139	45
TP21	216	110
TP24	192	265
TP25	150	130
TP26	175	150
TP27	156	100
TP28	144	170
TP29	193	240
TP30	171	190
TP31	188	180
TP32	167	130
TP34	151	120
TP35	173	140

Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 7/24/2025 to 9/3/2025

From August 28, 2025, through September 3, 2025, there were two recorded temperature decreases and one recorded temperature increase that triggered the notification limits set forth in the LEA's October 4, 2024 letter.

Additionally, as of April 4, 2025, twelve new TMPs (TMP-21, TMP-24, TMP-25, TMP-26, TMP-27, TMP-28, TMP-29, TMP-30, TMP-31, TMP-32, TMP-34, and TMP-35) have been installed and are online. None of these twelve new TMPs indicate reaction temperatures occurring outside of the currently delineated data-driven reaction area boundary, and the four TMPs that were able to be drilled to within 25 feet of the liner (TMP-24, TMP-27, TMP-31, and TMP-32) show significantly cooler temperatures at the deepest thermocouple, as expected due to the cooling from the underlying earth.

Chiquita provides the following updates:

- TP-07
    - The 60-foot thermocouple showed an anomalous reading on August 21st of 198°F for a single one-hour reading; however, subsequent readings were consistent with previous recorded temperatures and no other thermocouples at TP-07 showed any such changes in temperatures, indicating that this recorded temperature increase was most likely erroneous.
- TP-08
    - The 30-foot thermocouple showed an increase in maximum temperature of 10°F from 149°F to 159°F from September 1st to September 3rd.
- TP-13
    - The 30-foot thermocouple showed a decrease in maximum temperature of 10°F from 152°F to 142°F from August 25th to September 1st.
- TP-15
    - The 30-foot thermocouple showed a decrease in maximum temperature of 10°F from 186°F to 176°F from August 21st to August 28th.
- TP-35
    - All thermocouples were temporarily offline on September 2nd for the repair of the thermocouple casing. As a result, all maximum readings on September 2nd are erroneous.

SCS ENGINEERS

07224053.00 | September 4, 2025

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4

Maximum data for 7/24/2025 to 9/3/2025



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25



Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35



SCS ENGINEERS

Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill



BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	158	15
TP02	158	60
TP03	235	45
TP04	163	30
TP05	156	75
TP06	135	120
TP07	152	100
TP08	169	150
TP09	209	125
TP10	147	125
TP11	184	125
TP12	148	125
TP13	167	140
TP14	170	150
TP15	202	100
TP16	143	15
TP17	151	125
TP18	155	45
TP19	163	150
TP20	139	45
TP21	216	110
TP24	192	265
TP25	148	130
TP26	174	150
TP27	156	100
TP28	144	170
TP29	183	240
TP30	171	190
TP31	187	180
TP32	167	130
TP34	150	120
TP35	171	140



N

GRAPHIC SCALE

130 65 0 130 260 390

SCALE: 1"=130'

LEGEND

1150	EXISTING TOPOGRAPHIC CONTOUR
	EXISTING CELL LIMITS (APPROXIMATE)
TP-XX	INSTALLED TEMPERATURE PROBES - STANDALONE
TP-XX	INSTALLED TEMPERATURE PROBES - INSTALLED WITHIN WELL CASING
	REACTION AREA BOUNDARY (APPROXIMATE) - BASED ON DATA REVIEW
	REACTION AREA BOUNDARY - CONDITION 9A

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER. AERIAL PHOTOGRAPHY DATED MAY 14, 2025.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

DATE | REVISION | NO.

SHEET TITLE: EXISTING TEMPERATURE PROBE MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH. (562) 426-9544

PROJ. NO. 01204123.41 | DWN. BY: - | ACAD FILE: F:/ENGINEERS
DSN. BY: - | CHK. BY: - | APP. BY: -

DATE: 05/28/2025

SCALE: AS SHOWN

SHEET: 1

N:\CAD\ASBUILT - MASTERS\CHIQUITA\GCCS\2025 ACAD\2025 CCLF Existing Temperature Probe Map_2025-06-12.dwg Jun 12, 2025 - 4:48pm By: abolaske

Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 7/31/2025 to 9/10/2025

From September 4, 2025, through September 10, 2025, there were two recorded temperature decreases and two recorded temperature increases that triggered the notification limits set forth in the LEA's October 4, 2024 letter.

Additionally, as of April 4, 2025, twelve new TMPs (TMP-21, TMP-24, TMP-25, TMP-26, TMP-27, TMP-28, TMP-29, TMP-30, TMP-31, TMP-32, TMP-34, and TMP-35) have been installed and are online. None of these twelve new TMPs indicate reaction temperatures occurring outside of the currently delineated data-driven reaction area boundary, and the four TMPs that were able to be drilled to within 25 feet of the liner (TMP-24, TMP-27, TMP-31, and TMP-32) show significantly cooler temperatures at the deepest thermocouple, as expected due to the cooling from the underlying earth.

Chiquita provides the following updates:

- TP-07
    - The 60-foot thermocouple showed an anomalous reading on August 21st of 198°F for a single one-hour reading; however, subsequent readings were consistent with previous recorded temperatures and no other thermocouples at TP-07 showed any such changes in temperatures, indicating that this recorded temperature increase was most likely erroneous.
- TP-08
    - The 30-foot thermocouple remained consistent with previous recorded temperatures.The 45-foot thermocouple showed an increase in maximum temperature of 10°F from 147°F to 157°F from September 1st to September 4th.
- TP-13
    - The 30-foot thermocouple showed a decrease in maximum temperature of 10°F from 144°F to 134°F from September 2nd to September 9th.
- TP-15
    - The 30-foot thermocouple showed an increase in maximum temperature of 10°F from 177°F to 187°F from August 29th to September 5th and then a decrease in maximum temperature of 23°F from 187°F to 164°F from September 5th to September 10th.
- TP-35
    - All thermocouples were temporarily offline on September 2nd for the repair of the thermocouple casing. As a result, all maximum readings on September 2nd are erroneous.

SCS ENGINEERS

07224053.00 | September 11, 2025

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4



Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16



Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30



Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35



SCS ENGINEERS

Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill



BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	158	15
TP02	158	60
TP03	234	45
TP04	163	30
TP05	156	75
TP06	139	80
TP07	153	100
TP08	169	150
TP09	209	125
TP10	147	125
TP11	183	125
TP12	148	125
TP13	167	140
TP14	169	150
TP15	202	100
TP16	140	100
TP17	150	125
TP18	155	45
TP19	163	150
TP20	139	45
TP21	215	110
TP24	192	265
TP25	148	130
TP26	174	150
TP27	156	100
TP28	144	170
TP29	189	240
TP30	171	190
TP31	187	180
TP32	167	130
TP34	150	120
TP35	172	140



N

GRAPHIC SCALE

130 65 0 130 260 390

SCALE: 1"=130'

LEGEND

1150	EXISTING TOPOGRAPHIC CONTOUR
	EXISTING CELL LIMITS (APPROXIMATE)
TP-XX	INSTALLED TEMPERATURE PROBES - STANDALONE
TP-XX	INSTALLED TEMPERATURE PROBES - INSTALLED WITHIN WELL CASING
	REACTION AREA BOUNDARY (APPROXIMATE) - BASED ON DATA REVIEW
	REACTION AREA BOUNDARY - CONDITION 9A

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER. AERIAL PHOTOGRAPHY DATED AUGUST 27, 2025.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

DATE | REVISION | NO.

SHEET TITLE: EXISTING TEMPERATURE PROBE MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH. (562) 426-9544

PROJ. NO. 01204123.41	DWN. BY: -	ACAD FILE: F:/ENGINEERS
DSN. BY: -	CHK. BY: -	APP. BY: -

DATE: 09/08/2025

SCALE: AS SHOWN

SHEET: 1

N:\CAD\ASBUILT - MASTERS\CHIQUITA\GCCS\2025 ACAD\2025 CCLF Existing Temperature Probe Map_2025-09-08.dwg Sep 08, 2025 - 1:10pm By: smedina

Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 8/7/2025 to 9/17/2025

SCS ENGINEERS

07224053.00 | September 18, 2025

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

From September 11, 2025, through September 17, 2025, there was one recorded temperature decrease and four recorded temperature increases that triggered the notification limits set forth in the LEA's October 4, 2024 letter.

Additionally, as of April 4, 2025, twelve new TMPs (TMP-21, TMP-24, TMP-25, TMP-26, TMP-27, TMP-28, TMP-29, TMP-30, TMP-31, TMP-32, TMP-34, and TMP-35) have been installed and are online. None of these twelve new TMPs indicate reaction temperatures occurring outside of the currently delineated data-driven reaction area boundary, and the four TMPs that were able to be drilled to within 25 feet of the liner (TMP-24, TMP-27, TMP-31, and TMP-32) show significantly cooler temperatures at the deepest thermocouple, as expected due to the cooling from the underlying earth.

Chiquita provides the following updates:

- TP-07
  - The 60-foot thermocouple showed an anomalous reading on August 21st of 198°F for a single one-hour reading; however, subsequent readings were consistent with previous recorded temperatures and no other thermocouples at TP-07 showed any such changes in temperatures, indicating that this recorded temperature increase was most likely erroneous.

- TP-08
  - The 45-foot thermocouple remained consistent with previous recorded temperatures.
  - The 150-foot thermocouple showed an anomalous reading on September 15th of 224°F for a single one-hour reading; however, subsequent readings were consistent with previous recorded temperatures and no other thermocouples at TP-08 showed any such changes in temperatures, indicating that this recorded temperature increase was most likely erroneous.
  - The 150-foot thermocouple showed an increase in maximum temperature of 10°F from 169°F to 179°F from September 16th to September 17th.

- TP-11
  - The 15-foot thermocouple showed an increase in maximum temperature of 18°F from 134°F to 152°F from September 14th to September 17th.

- TP-13
  - The 30-foot thermocouple showed an increase in maximum temperature of 15°F from 134°F to 149°F from September 9th to September 12th, and then a decrease in maximum temperature of 13°F from 149°F to 136°F from September 12th to September 17th.

- TP-15
  - The 30-foot thermocouple showed an increase in maximum temperature of 23°F from 168°F to 191°F from September 15th to September 17th.

- TP-35
  - All thermocouples were temporarily offline on September 2nd for the repair of the thermocouple casing. As a result, all maximum readings on September 2nd are erroneous.

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1



Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4

Maximum data for 8/7/2025 to 9/17/2025



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5

Maximum data for 8/7/2025 to 9/17/2025



Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8

Maximum data for 8/7/2025 to 9/17/2025



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12



Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14

Maximum data for 8/7/2025 to 9/17/2025



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19



Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26



Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27



Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35



SCS ENGINEERS

Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill



BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	159	15
TP02	158	60
TP03	234	45
TP04	163	30
TP05	156	75
TP06	135	120
TP07	153	100
TP08	179	150
TP09	209	125
TP10	148	125
TP11	185	125
TP12	148	125
TP13	168	140
TP14	170	150
TP15	196	100
TP16	141	100
TP17	151	125
TP18	157	45
TP19	164	150
TP20	136	45
TP21	215	110
TP24	192	265
TP25	149	130
TP26	175	150
TP27	156	100
TP28	144	170
TP29	191	240
TP30	171	190
TP31	188	180
TP32	167	130
TP34	151	120
TP35	172	140



N

GRAPHIC SCALE

130 65 0 130 260 390

SCALE: 1"=130'

LEGEND

1150	EXISTING TOPOGRAPHIC CONTOUR
	EXISTING CELL LIMITS (APPROXIMATE)
TP-XX	INSTALLED TEMPERATURE PROBES - STANDALONE
TP-XX	INSTALLED TEMPERATURE PROBES - INSTALLED WITHIN WELL CASING
	REACTION AREA BOUNDARY (APPROXIMATE) - BASED ON DATA REVIEW
	REACTION AREA BOUNDARY - CONDITION 9A

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER. AERIAL PHOTOGRAPHY DATED AUGUST 27, 2025.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

DATE | REVISION | NO.

SHEET TITLE: EXISTING TEMPERATURE PROBE MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH. (562) 426-9544

PROJ. NO. 01204123.41 | DSN. BY: - | DWN. BY: - | CHK. BY: - | ACAD FILE: F/ENGINEERS | APP. BY: -

DATE: 09/08/2025

SCALE: AS SHOWN

SHEET: 1

N:\CAD\ASBUILT - MASTERS\CHIQUITA\GCCS\2025 ACAD\2025 CCLF Existing Temperature Probe Map_2025-09-08.dwg Sep 08, 2025 - 1:10pm By: smedina

Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 8/14/2025 to 9/24/2025

SCS ENGINEERS

07224053.00 | September 25, 2025

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

From September 18, 2025, through September 24, 2025, there were two recorded temperature decreases that triggered the notification limits set forth in the LEA's October 4, 2024 letter.

Additionally, as of April 4, 2025, twelve new TMPs (TMP-21, TMP-24, TMP-25, TMP-26, TMP-27, TMP-28, TMP-29, TMP-30, TMP-31, TMP-32, TMP-34, and TMP-35) have been installed and are online. None of these twelve new TMPs indicate reaction temperatures occurring outside of the currently delineated data-driven reaction area boundary, and the four TMPs that were able to be drilled to within 25 feet of the liner (TMP-24, TMP-27, TMP-31, and TMP-32) show significantly cooler temperatures at the deepest thermocouple, as expected due to the cooling from the underlying earth.

Chiquita provides the following updates:

- TP-07
  - As previously reported, the 60-foot thermocouple showed an anomalous reading on August 21st of 198°F for a single one-hour reading; however, subsequent readings were consistent with previous recorded temperatures and no other thermocouples at TP-07 showed any such changes in temperatures, indicating that this recorded temperature increase was most likely erroneous.

- TP-08
  - As previously reported, the 150-foot thermocouple showed an anomalous reading on September 15th of 224°F for a single one-hour reading; however, subsequent readings were consistent with previous recorded temperatures and no other thermocouples at TP-08 showed any such changes in temperatures, indicating that this recorded temperature increase was most likely erroneous. The 150-foot thermocouple remained consistent with previous recorded temperatures.

- TP-11
  - The 15-foot thermocouple remained consistent with previous recorded temperatures.

- TP-13
  - The 30-foot thermocouple showed a decrease in maximum temperature of 15°F from 149°F to 134°F from September 12th to September 19th.

- TP-15
  - The 30-foot thermocouple remained consistent with previous recorded temperatures.

- TP-21
  - The 60-foot thermocouple showed a decrease in maximum temperature of 12°F from 181°F to 169°F from September 17th to September 24th.

- TP-35
  - As previously reported, all thermocouples were temporarily offline on September 2nd for the repair of the thermocouple casing. As a result, all maximum readings on September 2nd are erroneous.

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7



Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8



Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13

Maximum data for 8/14/2025 to 9/24/2025



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14



Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21

Maximum data for 8/14/2025 to 9/24/2025



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34

Maximum data for 8/14/2025 to 9/24/2025



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35



Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill



BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	163	15
TP02	158	60
TP03	234	45
TP04	163	30
TP05	156	75
TP06	135	120
TP07	153	100
TP08	178	150
TP09	209	125
TP10	149	125
TP11	182	125
TP12	148	125
TP13	168	140
TP14	170	150
TP15	200	100
TP16	141	15
TP17	150	125
TP18	159	45
TP19	164	150
TP20	135	45
TP21	215	110
TP24	192	265
TP25	149	130
TP26	175	150
TP27	156	100
TP28	144	170
TP29	193	240
TP30	171	190
TP31	188	180
TP32	167	130
TP34	151	120
TP35	172	140



N

GRAPHIC SCALE

130 65 0 130 260 390

SCALE: 1"=130'

LEGEND

1150	EXISTING TOPOGRAPHIC CONTOUR
	EXISTING CELL LIMITS (APPROXIMATE)
TP-XX	INSTALLED TEMPERATURE PROBES - STANDALONE
TP-XX	INSTALLED TEMPERATURE PROBES - INSTALLED WITHIN WELL CASING
	REACTION AREA BOUNDARY (APPROXIMATE) - BASED ON DATA REVIEW
	REACTION AREA BOUNDARY - CONDITION 9A

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER. AERIAL PHOTOGRAPHY DATED AUGUST 27, 2025.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

DATE | REVISION | NO.

SHEET TITLE: EXISTING TEMPERATURE PROBE MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH. (562) 426-9544

PROJ. NO. 01204123.41 | DSN. BY: - | DWN. BY: - | CHK. BY: - | ACAD FILE: F:/ENGINEERS | APP. BY: -

DATE: 09/08/2025

SCALE: AS SHOWN

SHEET: 1

N:\CAD\ASBUILT - MASTERS\CHIQUITA\GCCS\2025 ACAD\2025 CCLF Existing Temperature Probe Map_2025-09-08.dwg Sep 08, 2025 - 1:10pm By: smedina

Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 8/21/2025 to 10/1/2025

SCS ENGINEERS

07224053.00 | October 2, 2025

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

From September 25, 2025, through October 1, 2025, there was one recorded temperature increase and three recorded temperature decreases that triggered the notification limits set forth in the LEA's October 4, 2024 letter.

Additionally, as of April 4, 2025, twelve new TMPs (TMP-21, TMP-24, TMP-25, TMP-26, TMP-27, TMP-28, TMP-29, TMP-30, TMP-31, TMP-32, TMP-34, and TMP-35) have been installed and are online. None of these twelve new TMPs indicate reaction temperatures occurring outside of the currently delineated data-driven reaction area boundary, and the four TMPs that were able to be drilled to within 25 feet of the liner (TMP-24, TMP-27, TMP-31, and TMP-32) show significantly cooler temperatures at the deepest thermocouple, as expected due to the cooling from the underlying earth.

Chiquita provides the following updates:

- TP-07
  - As previously reported, the 60-foot thermocouple showed an anomalous reading on August 21st of 198°F for a single one-hour reading; however, subsequent readings were consistent with previous recorded temperatures and no other thermocouples at TP-07 showed any such changes in temperatures, indicating that this recorded temperature increase was most likely erroneous.

- TP-08
  - As previously reported, the 150-foot thermocouple showed an anomalous reading on September 15th of 224°F for a single one-hour reading; however, subsequent readings were consistent with previous recorded temperatures and no other thermocouples at TP-08 showed any such changes in temperatures, indicating that this recorded temperature increase was most likely erroneous. The 150-foot thermocouple remained consistent with previous recorded temperatures.
  - The 150-foot thermocouple showed a decrease in maximum temperature of 10°F from 179°F to 169°F from September 23rd to September 26th, then an increase maximum temperature of 12°F from 169°F to 181°F from September 26th to September 30th, and then a decrease in maximum temperature of 12°F from 181°F to 169°F from September 30th to October 1st.

- TP-13
  - The 30-foot thermocouple remained consistent with previous recorded temperatures.

- TP-21
  - The 60-foot thermocouple showed a decrease in maximum temperature of 10°F from 176°F to 166°F from September 20th to September 27th.

- TP-35
  - As previously reported, all thermocouples were temporarily offline on September 2nd for the repair of the thermocouple casing. As a result, all maximum readings on September 2nd are erroneous.

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4

Maximum data for 8/21/2025 to 10/1/2025



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6



Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10



Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12



Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24



Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30



Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31

Maximum data for 8/21/2025 to 10/1/2025



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32



Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34



Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35



SCS ENGINEERS

Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill



BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	166	15
TP02	158	60
TP03	233	45
TP04	162	30
TP05	156	75
TP06	135	120
TP07	153	100
TP08	181	150
TP09	209	125
TP10	149	125
TP11	183	100
TP12	148	125
TP13	168	140
TP14	169	150
TP15	202	100
TP16	143	15
TP17	149	125
TP18	163	45
TP19	164	150
TP20	136	45
TP21	215	110
TP24	192	265
TP25	150	130
TP26	174	150
TP27	156	100
TP28	144	170
TP29	184	240
TP30	171	190
TP31	188	180
TP32	167	130
TP34	151	120
TP35	172	140



N

GRAPHIC SCALE

130 65 0 130 260 390

SCALE: 1"=130'

LEGEND

1150	EXISTING TOPOGRAPHIC CONTOUR
	EXISTING CELL LIMITS (APPROXIMATE)
TP-XX	INSTALLED TEMPERATURE PROBES - STANDALONE
TP-XX	INSTALLED TEMPERATURE PROBES - INSTALLED WITHIN WELL CASING
	REACTION AREA BOUNDARY (APPROXIMATE) - BASED ON DATA REVIEW
	REACTION AREA BOUNDARY - CONDITION 9A

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER. AERIAL PHOTOGRAPHY DATED AUGUST 27, 2025.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

DATE

REVISION

NO.

SHEET TITLE:
EXISTING TEMPERATURE PROBE MAP

PROJECT TITLE:
CHIQUITA CANYON LANDFILL
CASTAIC, CALIFORNIA

CLIENT:
CHIQUITA CANYON LANDFILL
CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH. (562) 426-9544

PROJ. NO. 01204123.41	DWN. BY: -	ACAD FILE: F:/ENGINEERS
DSN. BY: -	CHK. BY: -	APP. BY: -

DATE: 09/08/2025

SCALE: AS SHOWN

SHEET: 1

Attachment E

October 10, 2025

Reaction Committee

Report

October 10, 2025
File No. 01204123.21-13

Mr. Baitong Chen
South Coast Air Quality Management District
21865 Copley Drive
Diamond Bar, California 91765

Subject: Monthly Reaction Committee Determination on Reaction Area Boundary
Chiquita Canyon Landfill – Castaic, California

Dear Mr. Chen:

In accordance with Condition Nos. 9a and 9b of the Modified Stipulated Order for Abatement (SOFA) pertaining to the Chiquita Canyon Landfill (Landfill or Facility) (Case No. 6177-4), the Reaction Committee has reviewed newly acquired applicable data recorded during the month of September 2025, considered revisions of the estimated extent of elevated temperature landfill (ETLF) conditions exhibited at the subject Facility (referred to as the "Reaction Area" limits), and has prepared this determination on potentially revising the Reaction Area map.

Attachment A presents the Drawing, titled "Reaction Area Map", prepared by SCS Engineers (SCS) and dated October 1, 2025. The Drawing depicts the Reaction Area boundary as prescribed in Condition No. 9a, which corresponds to the limits of Cells 1/2A, 2B/3, 4, and Module 2B/3/4 P2, as a solid black line. The Drawing also depicts the estimated extent of ETLF conditions being experienced at the site based on the Reaction Committee's review of scientific data as a dashed magenta line. The rationale that serves as the basis for considering adjustments and modifications to the Reaction Area boundary (or the determination to maintain the decreed boundary), include the following:

- Landfill Gas (LFG) wellhead temperatures in excess of approximately 160 degrees Fahrenheit.
- Poor gas quality (defined as methane levels of less than 30 percent) in conjunction with methane-to-carbon dioxide (CH_4:CO_2) ratios less than 1.0.
- The concentration of hydrogen (H_2) in the LFG measured greater than 2 percent by volume.
- The concentration of carbon monoxide (CO) in the LFG measured greater than 2,000 ppm.
- Accelerated settlement of the landfill surface, defined as approximately 18 inches or greater within a 60-day period, and cracks in landfill cover. This corresponds to a strain value (i.e., settlement rate) rate of 3 percent per year for areas with a 300-foot waste column depth, which we believe is a reasonable average depth in the subject area of interest.
- First-hand observations of Landfill and/or SCS engineering, construction, and operations and maintenance (O&M) field personnel who are on-site related to: 1) atypical excess leachate quantities (presence and quantity of liquids); 2) instances of pressurized liquids emitting from the landfill surface, from boreholes during drilling, and from LFG wells; and, 3) the

characteristics of the odors originating from the select areas of the waste footprint (often described as "chemical-like" and distinctly different from typical LFG or landfill working face odors).

- Observations of subsurface waste conditions and characteristics as noted on borehole drilling logs for recently installed new wells and/or probes.

- Subsurface temperatures recorded at the in-situ waste temperature probes during September 2025.

- Temperature of gas or liquids measured at depth within the LFG well riser pipe (using an automated transmitter or manual field instrumentation).

- Subsurface temperature and pressures associated with drilling activities for new LFG extraction wells during September 2025.

CONSIDERATIONS FOR POTENTIAL ADJUSTMENTS TO THE ESTIMATED EXTENT OF ETLF CONDITIONS (DASHED MAGENTA LINE)

In making its monthly determinations, the Reaction Committee evaluates the above set of data parameters, in conjunction with one another, to identify meaningful trends indicating ETLF conditions, as opposed to fluctuations exhibited in isolated datapoints.

Each month, the Reaction Committee scrutinizes particular areas of the Landfill that have previously exhibited abnormal or fluctuating data, when applicable. As discussed below, despite minor variances in discrete areas of the landfill, the Reaction Committee has not discerned any meaningful trends with respect to the September 2025 data that would indicate the reaction has expanded into these areas.

Near CV-24009

Well CV-24009 is positioned within 60 feet or so of the delineated boundary line. This well recorded a maximum LFG wellhead temperature of 161 degrees F during September, however the average LFG wellhead temperature measured during July through September for this well was 156 degrees F.

The LFG quality is marginal at CV-24009, which exhibited an average methane (CH_4) concentration of 18 percent during July through September, and the methane-to-carbon dioxide (CH_4:CO_2) ratio in September was 0.18. The hydrogen (H_2) concentration measured in September was 7.5 percent.

The Reaction Committee has identified gas movement from within the Reaction Area via existing horizontal collectors as the potential cause of the heat and longer-term trend of marginal to poor quality gas at these wells. Specifically, well CV-24009 is positioned immediately adjacent to H-1769 (at an elevation of 1335 feet), which extends hundreds of feet into the Reaction Area, so it is possible that the source of the heat and reaction gas at this vertical well is offset some distance away and is being conveyed toward the wells by the horizontal collectors' piping and trench. In addition, CV-24009 is equipped with a dedicated dewatering pump, so the recent increase in temperatures and the presence of increased reaction gas (as opposed to typical landfill gas) may be attributable to the lowering of perched leachate levels in this vicinity, which is enabling movement of heat and gas through the void spaces.

Near CV-113

Well CV-113 is positioned approximately 300 feet or so beyond the delineated boundary. This well has experienced increased temperatures since July and recorded a maximum LFG wellhead temperature of 178 degrees F during September.

The LFG quality is poor at CV-113, which exhibited an average CH_4 concentration of 2 percent during July through September, and the CH_4:CO_2 ratio in September was 0.01. The H_2 concentration measured in September was 6.7 percent.

This well does not appear to be in the vicinity of any horizontal collectors that extend out from the Reaction Area and the well is not equipped with a pump. However, the surrounding LFG wells exhibit substantially lower temperatures and more typical LFG composition and well CV-113 exhibited significantly lower temperatures prior to August. Accordingly, the Reaction Committee will continue to monitor the conditions at this well.

Near CV-2333 and CV-24126

Well CV-2333 is positioned within 50 feet or so of the delineated boundary and the well is co-located with temperature probe TP-18. Well CV-24126 is positioned within 100 feet or so of the delineated boundary. Well CV-24126 recorded a maximum LFG wellhead temperature of 186 degrees F during September, however the average LFG wellhead temperature measured during July through September at this well was 159 degrees F. The average LFG wellhead temperature at adjacent well CV-2333 measured during July through September was 135 degrees F. The deepest thermocouple in TP-18 is positioned 45 feet below the landfill surface and has demonstrated increasing temperatures over the past six weeks, most recently indicating an in-situ waste temperature of 162 degrees F.

The LFG quality is poor at CV-2333, which exhibited an average CH_4 concentration of 2 percent during July through September. The H_2 concentration measured in September was 13 percent. The LFG quality is also poor at CV-24126, which exhibited an average CH_4 concentration of 5 percent during July through September, and the CH_4:CO_2 ratio in September was 0.05.

The Reaction Committee has identified gas movement from within the Reaction Area via existing horizontal collectors as the potential cause of the heat and longer-term trend of marginal to poor quality gas at these wells. Specifically, well CV-24126 is positioned immediately adjacent to H-1772 (at an elevation of 1353 feet), which extends south along the Reaction Area border, so it is possible that the source of the heat and reaction gas at this vertical well is offset some distance away and is being conveyed toward the wells by the horizontal collectors' piping and trench. In addition, CV-2433 is equipped with a dedicated dewatering pump (CV-24126 is not), so the heat and the presence of increased reaction gas (as opposed to typical landfill gas) may be attributable to the lowering of perched leachate levels in this vicinity, which is enabling movement of heat and gas through the void spaces.

Near CV-2541

Well CV-2541 is positioned within about 25 feet of the delineated boundary line. It is positioned immediately adjacent to horizontal collectors H-54 (at an elevation of 1225 feet) and H-1564 (at an elevation of 1245 feet), both of which extend hundreds of feet into the Reaction Area. During September, well CV-2541 recorded a maximum LFG wellhead temperature of 167 degrees F, but the average temperature during July through September was 151 degrees F. The average LFG wellhead temperature measured in the adjacent well CV-24068 during July through September was 142 degrees F.

The LFG quality is poor at CV-2541, which exhibited an average CH_4 concentration of 14 percent during July through September. The hydrogen concentration measured at well CV-2541 in September was 5.9 percent. The LFG quality is marginal at CV-24068, which exhibited an average CH_4 concentration of 20 percent during July through September.

Considering the most recent temperatures are relatively low for ETLF conditions, along with the proximity to horizontal collectors, the Reaction Committee does not believe an adjustment to the boundary of the Reaction Area to include the portions of the waste footprint inclusive of CV-2541 is warranted at this time.

Near CV-2344

Well CV-2344 is positioned within 100 feet or so of the delineated boundary. Well CV-2344 recorded a maximum LFG wellhead temperature of 161 degrees F during September, however the average LFG wellhead temperature measured during July through September at this well was 151 degrees F. The maximum in-situ waste temperature recorded in September at TP-05 was only 156 degrees F. The LFG quality at CV-2344 is poor, with an average CH_4 concentration of 14 percent during July through September, and the methane-to-carbon dioxide (CH4:CO2) ratio in September was 0.36. The hydrogen (H2) concentration measured in September was 6.7 percent.

Considering the temperatures at TP-05 and CV-2344 are relatively low for ETLF conditions, along with the proximity to horizontal collector H-1356 (at an elevation of 1278 feet), the Reaction Committee does not believe an adjustment to the boundary of the Reaction Area to include the portions of the waste footprint inclusive of CV-2344 is warranted at this time.

TEMPERATURE MONITORING PROBE DATA

The Reaction Committee reviewed the temperature measurements recorded during September 2025 by the in-situ temperature monitoring probes. As of September 2025, six of the 32 probes (TP-2, TP-3, TP-9, TP-11, TP-15, and TP-21) are located within the current estimated extent of ETLF conditions (dashed magenta line). Of the remaining 26 probes positioned outside of the boundary, twelve probes are positioned within relatively close proximity (within 200 feet) of this boundary. It is the Reaction Committee's opinion that the temperatures recorded by the 26 probes outside of the boundary during September 2025 are not indicative of a subsurface reaction and do not substantiate a decision to adjust the boundary of the Reaction Area at this time.

Several considerations related to data consistency and reliability are noted below:

- TP-08: The 150-foot depth thermocouple at TP-08 exhibited an anomalous reading on September 15th of 224 degrees F for a single one-hour reading; however, subsequent readings were generally consistent with previous recorded temperatures and no other thermocouples at TP-08 demonstrated corresponding significant changes in temperatures, indicating that this recorded temperature increase was most likely erroneous. Since this instance, the 150-foot thermocouple has periodically recorded daily temperature fluctuations of 8 to 10 degrees, which is somewhat atypical. These fluctuations could be attributed to the probe being co-located with LFG extraction well CV-24079, which is equipped with an operational dewatering pump.

- TP-35: All thermocouples in TP-35 were temporarily offline on September 2nd for the repair of the thermocouple casing. As a result, all maximum readings on this date are erroneous.

During September, the 15-foot depth thermocouple at TP-01 continued to demonstrate the gradual increase in temperature that has been ongoing for several months, in which the temperature has increased from approximately 120 degrees F, as recorded in early April 2025, to approximately 166 degrees F during late September. During this same timeframe, the other thermocouples within TP-01 have recorded consistent temperatures from week to week and are not exhibiting corresponding increases in temperature. Furthermore, a review of the wellhead monitoring data for wells positioned near TP-1 (CV-2326, CV-2335, CV-2336, CV-24006, and CV-24011) did not indicate corresponding increases in temperatures or other characteristics of the reaction. There are two horizontal collectors near TP-01, but they are not positioned in the shallow 15-foot zone. Field personnel at the site are investigating the ability to check the validity of the data and to replace the 15-foot thermocouple. Nevertheless, at this time, and for the reasons described above, the Reaction Committee does not believe this increase suggests the presence of ETLF conditions within the waste mass at this location.

The Reaction Committee evaluated the 30-day maximum temperatures recorded in TP-24, TP-26, TP-29, TP-30, and TP-31, which have remained relatively consistent over the previous 6-week period of August 21 through October 1, 2025 (except for a short-term fluctuation at the 240-foot interval in TP-29 for 1 day in mid-September). The abrupt increase at the 240-foot thermocouple in TP-29, from 183 degrees F to 193 degrees F and then back down to 184 degrees F over a 1-day period in mid-September, is irregular. The average daily maximum temperature at this thermocouple during September is approximately 184 degrees F.

The maximum temperatures recorded during September at the deeper thermocouples in TP-26 and TP-30 of 175 degrees F and 171 degrees F, respectively, are not significantly elevated for deeper waste zones and there is significant differentiation between the 30-day maximum temperatures in these five probes compared to the 30-day maximum temperatures measured at the four probes within the current estimated extent of ETLF conditions (dashed magenta line), specifically TP-3, TP-9, TP-15, and TP-21.

The maximum temperatures recorded during September at the deeper thermocouples in TP-24 and TP-31 of 192 degrees F and 188 degrees F, respectively, are somewhat greater than similar depth-intervals in the other 26 probes outside of the Reaction A
rea and the Reaction Committee noted there is less differentiation between the 30-day maximum temperatures in these two probes compared to the 30-day maximum temperatures measured at the four probes within the current estimated extent of ETLF conditions (dashed magenta line),

specifically TP-3, TP-9, TP-15, and TP-21. However, the four wells surrounding TP-24 recorded average LFG wellhead temperatures during July through September ranging from 101 degrees F to 119 degrees F and average methane concentrations between 27 and 46 percent. The three wells surrounding TP-31 recorded average LFG wellhead temperatures during July through September ranging from 114 degrees F to 137 degrees F. While the average methane concentration at CV-2319 is 19 percent, the average methane content at CV-24111 during the past three months was 42 percent. So, the wells surrounding these two probes do not exhibit evidence of atypical heat or the LFG composition associated with ETLF conditions.

Accordingly, the Reaction Committee does not believe an adjustment to the boundary of the Reaction Area to include the portions of the waste footprint inclusive of TP-24, TP-26, TP-29, TP-30, and TP-31 is warranted at this time.

HYDROGEN CONCENTRATIONS

The Reaction Committee also evaluated the concentration of hydrogen in LFG during September 2025. Recall that certain wells positioned to the south and east of the Reaction Area boundary (where dewatering pumping was reactivated) have periodically demonstrated some increased hydrogen content in the LFG during the Reaction Committee's review of the data in previous months, which similarly was the case for the September 2025 data. The Reaction Committee noted in its review of the data that, other than wells CV-113 and CV-2344, these wells did not exhibit elevated temperatures. There was no evidence of the increased heat that is typical with ETLF conditions at the wells exhibiting atypical hydrogen concentrations (except wells CV-113 and CV-2344). As noted previously, the Reaction Committee suspects this increased hydrogen content may be attributable to substantial dewatering being accomplished throughout the Reaction Area and may be associated with gas movement from within the Reaction Area by existing horizontal collectors in close proximity. Thus, the presence of elevated hydrogen in these isolated locations does not suggest that ETLF conditions are expanding south and east of the delineated boundary. Accordingly, the Reaction Committee does not believe an adjustment to the boundary of the Reaction Area is warranted at this time.

CONCLUSION

As presented on the Drawing included as **Attachment A**, the estimated extent of ETLF conditions (dashed magenta line) is fully contained within the Reaction Area boundary decreed in the SOFA (solid black line). Because the ETLF conditions are fully contained within the Reaction Area boundary and have not expanded into a new cell, the Reaction Committee finds no basis to modify the Reaction Area boundary as prescribed in Condition 9a at this time.

There was no dissenting opinion among the Reaction Committee members regarding this monthly determination. Supporting data is presented on the Drawing included as **Attachment A.** The maximum temperature measurements recorded at the 32 in-situ waste temperature monitoring probes (both 7-Day and 30-Day values) during September are presented in **Attachment B** in graphical format. The LFG wellhead temperatures recorded at the extraction wells for the entire Landfill footprint are reflected on the isothermal gradient range map presented as **Attachment C.** The CH_4:CO_2 ratios measured at the LFG wellheads in the vicinity of the data-driven Reaction Area boundary are depicted on the range map presented as **Attachment D.** The H_2 concentrations measured at the LFG wellheads in the vicinity of the data-driven Reaction Area boundary are depicted on the range map presented as **Attachment E.** The CO concentrations measured at the LFG wellheads in the vicinity of the data-driven Reaction Area boundary are depicted on the range map presented as **Attachment F.** The landfill surface settlement isopach values measured on a quarterly basis (July 2, 2025 compared to October 1, 2025) in the vicinity of the data-driven Reaction Area boundary are depicted on the range map presented as **Attachment G.** The electronic database and recordkeeping platform enables these measurements to be downloaded into a tabular spreadsheet format, which can be submitted to the South Coast Air Quality Management District under separate cover, if requested.

Please contact either of the undersigned if you have questions or require additional information.

Sincerely,

Robert E. Dick, PE, BCEE
Senior Vice President
SCS Engineers

Patrick S. Sullivan, BCES, CCP
Senior Vice President
SCS Engineers

RED/PSS

cc: Nathaniel Dickel, SCAQMD
Christina Ojeda, SCAQMD
Patrick S. Sullivan, REPA, CPP, BCES, SCS Engineers
Pablo Sanchez Soria, PhD, CIH, CTEH
Neal Bolton, PE, Blue Ridge Services, Inc.
Richard Pleus, PhD, Intertox
Srividhya Viswanathan, PE, SCS Engineers

Enclosures:

Attachment A – Reaction Area Map
Attachment B – In-Situ Waste Temperature Monitoring Probe Data
Attachment C – Isothermal Gradient Range Map
Attachment D – Wellhead Methane-to-Carbon Dioxide Range Map
Attachment E – Wellhead Hydrogen Range Map
Attachment F – Wellhead Carbon Monoxide Range Map
Attachment G – Settlement Isopach Range Map

ATTACHMENT A



LFG Vertical Extraction Wells Installed: SEPTEMBER 2025						
#	Well I.D.	Bore Depth (Ft.)	Casing Depth (Ft.)	Date of Installation	Excavated/Exposed Waste Characterization	Excavated/Exposed Waste Moisture
1	CV-2525	105	103	9/4/2025	None to Little → Moderate	Dry → Moist
2	CV-2523	124	122	9/8/2025	None to Little → Moderate	Dry → Moist
3	CV-2528	65	63	9/8/2025	None to Little → Moderate	Dry → Moist
4	CV-25100S/D	110	-	9/10/2025	None to Little → Severe	Dry → Saturated
5	CV-25101S/D	140	-	9/11/2025	None to Little → Severe	Dry → Saturated
6	CV-25106S/D	92	-	9/12/2025	None to Little → Severe	Dry → Saturated
7	CV-25105S/D	140	-	9/16/2025	None to Little → Severe	Dry → Saturated
8	CV-25104S/D	115	-	9/17/2025	None to Little → Severe	Dry → Saturated
9	CV-25107S/D	140	-	9/19/2025	None to Little → Severe	Dry → Saturated
10	CV-25102S/D	70	-	9/22/2025	None to Little → Severe	Dry → Saturated
11	CV-2560	175	175	9/23/2025	None to Little → Severe	Dry → Saturated
12	CV-2551	165	165	9/24/2025	None to Little → Severe	Dry → Saturated
13	CV-25103S/D	76	-	9/26/2025	None to Little → Moderate	Dry → Moist
14	CV-2561	190	190	9/29/2025	None to Little → Severe	Dry → Saturated
15	CV-2562	160	160	9/30/2025	None to Little → Severe	Dry → Saturated

GENERAL DRAWING NOTES:

1. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.
2. THE LOCATION OF ANY EXISTING PIPING, VALVES, TIE-IN LOCATIONS AND OTHER FEATURES ARE APPROXIMATE AND SHOULD BE USED FOR INFORMATION PURPOSES ONLY.

NO.	REVISION	DATE

SHEET TITLE: REACTION AREA MAP SEPTEMBER 2025

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH. (562) 426-9544

PROJ. NO. 01204123.41 | DWN. BY: AEK | ACAD FILE: F:/ENGINEERS
DSN. BY: - | CHK. BY: WCH/SRM | APP. BY: WCH

DATE: 10/01/2025

SCALE: AS SHOWN

SHEET: 1

ATTACHMENT B

Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 8/21/2025 to 10/1/2025

SCS ENGINEERS

07224053.00 | October 2, 2025

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

From September 25, 2025, through October 1, 2025, there was one recorded temperature increase and three recorded temperature decreases that triggered the notification limits set forth in the LEA's October 4, 2024 letter.

Additionally, as of April 4, 2025, twelve new TMPs (TMP-21, TMP-24, TMP-25, TMP-26, TMP-27, TMP-28, TMP-29, TMP-30, TMP-31, TMP-32, TMP-34, and TMP-35) have been installed and are online. None of these twelve new TMPs indicate reaction temperatures occurring outside of the currently delineated data-driven reaction area boundary, and the four TMPs that were able to be drilled to within 25 feet of the liner (TMP-24, TMP-27, TMP-31, and TMP-32) show significantly cooler temperatures at the deepest thermocouple, as expected due to the cooling from the underlying earth.

Chiquita provides the following updates:

- TP-07
  - As previously reported, the 60-foot thermocouple showed an anomalous reading on August 21st of 198°F for a single one-hour reading; however, subsequent readings were consistent with previous recorded temperatures and no other thermocouples at TP-07 showed any such changes in temperatures, indicating that this recorded temperature increase was most likely erroneous.

- TP-08
  - As previously reported, the 150-foot thermocouple showed an anomalous reading on September 15th of 224°F for a single one-hour reading; however, subsequent readings were consistent with previous recorded temperatures and no other thermocouples at TP-08 showed any such changes in temperatures, indicating that this recorded temperature increase was most likely erroneous. The 150-foot thermocouple remained consistent with previous recorded temperatures.
  - The 150-foot thermocouple showed a decrease in maximum temperature of 10°F from 179°F to 169°F from September 23rd to September 26th, then an increase maximum temperature of 12°F from 169°F to 181°F from September 26th to September 30th, and then a decrease in maximum temperature of 12°F from 181°F to 169°F from September 30th to October 1st.

- TP-13
  - The 30-foot thermocouple remained consistent with previous recorded temperatures.

- TP-21
  - The 60-foot thermocouple showed a decrease in maximum temperature of 10°F from 176°F to 166°F from September 20th to September 27th.

- TP-35
  - As previously reported, all thermocouples were temporarily offline on September 2nd for the repair of the thermocouple casing. As a result, all maximum readings on September 2nd are erroneous.

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15

Maximum data for 8/21/2025 to 10/1/2025



Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16



Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17



Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24

Maximum data for 8/21/2025 to 10/1/2025



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29



Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35



SCS ENGINEERS

Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill



BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	166	15
TP02	158	60
TP03	233	45
TP04	162	30
TP05	156	75
TP06	135	120
TP07	153	100
TP08	181	150
TP09	209	125
TP10	149	125
TP11	183	100
TP12	148	125
TP13	168	140
TP14	169	150
TP15	202	100
TP16	143	15
TP17	149	125
TP18	163	45
TP19	164	150
TP20	136	45
TP21	215	110
TP24	192	265
TP25	150	130
TP26	174	150
TP27	156	100
TP28	144	170
TP29	184	240
TP30	171	190
TP31	188	180
TP32	167	130
TP34	151	120
TP35	172	140

Thirty Day Maximum Vertical Temperature Map from Temperature Probes at the Chiquita Canyon Landfill - September 2025



BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	166	15
TP02	158	60
TP03	234	45
TP04	163	30
TP05	156	75
TP06	140	80
TP07	153	100
TP08	181	150
TP09	209	125
TP10	149	125
TP11	185	125
TP12	148	125
TP13	168	140
TP14	170	150
TP15	202	100
TP16	143	15
TP17	151	125
TP18	162	45
TP19	164	150
TP20	139	45
TP21	216	110
TP24	192	265
TP25	150	130
TP26	175	150
TP27	156	100
TP28	144	170
TP29	193	240
TP30	171	190
TP31	188	180
TP32	167	130
TP34	151	120
TP35	173	140



N

GRAPHIC SCALE

130 65 0 130 260 390

SCALE: 1"=130'

LEGEND

1150	EXISTING TOPOGRAPHIC CONTOUR
	EXISTING CELL LIMITS (APPROXIMATE)
TP-XX	INSTALLED TEMPERATURE PROBES - STANDALONE
TP-XX	INSTALLED TEMPERATURE PROBES - INSTALLED WITHIN WELL CASING
	REACTION AREA BOUNDARY (APPROXIMATE) - BASED ON DATA REVIEW
	REACTION AREA BOUNDARY - CONDITION 9A

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER. AERIAL PHOTOGRAPHY DATED AUGUST 27, 2025.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

DATE | REVISION | NO.

SHEET TITLE: EXISTING TEMPERATURE PROBE MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH. (562) 426-9544

PROJ. NO. 01204123.41 | DWN. BY: - | ACAD FILE: F:/ENGINEERS
DSN. BY: - | CHK. BY: - | APP. BY: -

DATE: 09/08/2025

SCALE: AS SHOWN

SHEET: 1

N:\CAD\ASBUILT - MASTERS\CHIQUITA\GCCS\2025 ACAD\2025 CCLF Existing Temperature Probe Map_2025-09-08.dwg Sep 08, 2025 - 1:10pm By: smedina



GENERAL DRAWING NOTES:

1. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

NO.	REVISION	DATE

SHEET TITLE: ISOTHERMAL GRADIENT MAP OCTOBER 2025

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH. (562) 426-9544

PROJ. NO. 01204123.41 | DWN. BY: SRM | ACAD FILE: F:/ENGINEERS
DSN. BY: - | CHK. BY: | APP. BY: -

DATE: 10/09/2025
SCALE: AS SHOWN
SHEET: 1



Ranges Mapped

	# Points
>= 0 and < 0.5	128
>= 0.5 and < 0.9	74
>= 0.9 and < 1.1	49
>= 1.1 and < 1.5	64
>= 1.5 and < 101	2

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

ATTACHMENT D

Chiquita Canyon Landfill

Range Map

Parameter: CH4/CO2 Ratio (high range)

Analysis Method: Average

Date Range: 09/01/2025 - 09/30/2025

Map generation date : 10/09/2025



Ranges Mapped

				# Points
>= 0	and	<	20000	18
>= 20000	and	<	50000	16
>= 50000	and	<	100000	18
>= 100000	and	<	999999	41

The range values noted above are in units of parts per million (ppm). Divide by 10,000 to convert these values to units of percent by volume.

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

ATTACHMENT E

Chiquita Canyon Landfill

Range Map

Parameter: H2 (mid range)

Analysis Method: Average

Date Range: 09/01/2025 - 09/30/2025

Map generation date : 10/09/2025



Ranges Mapped

		# Points
	>= 0 and < 500	33
	>= 500 and < 1000	12
	>= 1000 and < 1500	13
	>= 1500 and < 2000	21
	>= 2000 and < 1000000	31

Point Type Legend

well

N

SCSeTools

ATTACHMENT F

Chiquita Canyon Landfill

Range Map

Parameter: CO (mid range)

Analysis Method: Average

Date Range: 09/01/2025 - 09/30/2025

Map generation date : 10/10/2025

Chiquita Canyon Landfill - Quarterly Isopach





October 1, 2025 Survey Image. July 2, 2025 vs. October 1, 2025

Attachment F

Third Quarter 2025

September Map

Chiquita Canyon Landfill - Isopach



October 1, 2025 Survey Image. August 27, 2025 vs October 1, 2025