SCS ENGINEERS

June 15, 2026

Karen Gork
Chief Environmental Health Specialist
Los Angeles County Local Enforcement Agency
5050 Commerce Drive
Baldwin Park, California 91706

**Subject:** **May 2026 Monthly Report Pursuant to Milestones 1A-3 and 5 of the LEA June 6, 2024 Compliance Order and July 30, 2024 Letter, Chiquita Canyon Landfill, Castaic, California**

Dear Ms. Gork:

SCS Engineers (SCS), on behalf of Chiquita Canyon, LLC (Chiquita), hereby provides the Los Angeles County Department of Public Health, Solid Waste Management Program, acting as the Local Enforcement Agency (LEA) with a monthly report pursuant to Milestones 1A-3 and 5 of the LEA Compliance Order dated June 6, 2024 (Compliance Order) and subsequent related correspondence received from the LEA. This report covers the monthly period for May 2026.

Chiquita Canyon Landfill (CCL or Landfill) is a landfill/solid waste disposal facility located at 29201 Henry Mayo Drive in Castaic, California. In connection with the Landfill, Chiquita operates a landfill gas collection and control system. SCS prepared and submitted the Carbon Monoxide and Hydrogen Reading Summary Report (Summary Report) to the LEA on June 6, 2024, on behalf of Chiquita, in response to the directives in the LEA letters dated April 5, 2024 and May 28, 2024 regarding collection of landfill gas data and in accordance with Milestone 1A-2 of the Compliance Order. The LEA, in collaboration with the California Department of Resources, Recycling, and Recovery (CalRecycle), reviewed the Summary Report and determined that it complied with Milestone 1A-2. The LEA set forth several new requirements for Chiquita to comply with Milestone 1A-3 in follow-up correspondence dated July 30, 2024.

This report was prepared in accordance with Milestones 1A-3 and 5 of the Compliance Order, the LEA's follow-up correspondence dated July 30, 2024, Chiquita's letter dated September 3, 2024, the September 12, 2024, meeting with the LEA, and follow-up correspondence from the LEA dated November 19 and 27 and December 3, 2024.

Milestone 1A-3 Compliance Items

**1. Submit the laboratory test results for monthly sampling of carbon monoxide (CO) and hydrogen (H2) from a set of landfill gas (LFG) wells selected by the LEA. Please see Table 1, columns labeled "CO" and "H2".**

Results for wells monitored are shown in **Attachment A**.[1] The data is being submitted to the LEA in a standalone report signed by a licensed engineer, in accordance with Milestone 1A-3 of the Compliance Order. As noted in Chiquita's prior correspondence and monthly reports, this report does not include data from wells CV-100, CV-103, CV-1420, CV-1423, CV-1532, CV-2202, H-1403W, H-1560S, H-1774S, SC-2001W, TC-2383S, TC-2385A, and TC-2385S, as those wells have been abandoned, or from well CV-2332, as that well was never installed. All remaining wells were tested during the month of May 2026.

As discussed during the September 12, 2024 meeting, and as previously reported, graphics showing CO and H2 trends are provided in **Attachment D** and are discussed further below.

**2. Provide data from readings for fixed gases (CH4, O2, and CO2) from a set of LFG wells selected by the LEA. See Table 1, column labeled "Fixed Gas CH4, O2, CO2."**

The results for wells monitored are provided in **Attachment A**.

**3. Collect down well temperatures at 34 wells to confirm the gas wellhead temperature readings per the requirement of the New Source Performance Standards (NSPS). See Table 1, column labeled "Down Well Temp Monitoring."**

It is Chiquita's understanding from the LEA's November 27, 2024 correspondence, and as noted in prior monthly reports, that, at this time, Chiquita is only required to sample the wells at the annual frequency provided in the NSPS protocols, but that the LEA may require more frequent monitoring for up to ten (10) wells selected by the LEA. Chiquita is awaiting the LEA's selection of those wells.

Chiquita nevertheless provides in **Attachment B** the down-hole temperature graphs[2] concerning the following wells from fixed locations which contain the Lorentz Pumping System with integral temperature sensors while they were in operation during May 2026: CV-2302, CV-2315, CV-24017, CV-24065 and CV-24095.

Please note that the Lorentz pump and/or temperature monitoring system for the pumps in CV-2301, CV-2303, CV-2350, CV-2351 and CV-2352 were offline during this reporting period due to either the deployment of the approved EVOH 60-mil geomembrane, were in the process

[1] The lab(s) reported data from additional LFG wells outside of those selected for sampling by the LEA; the additional data is related to separate South Coast Air Quality Management District (South Coast AQMD) reporting requirements and therefore can be disregarded for purposes of this report.
[2] Each graph notes a single temperature data point due to changes in the software.

of being repaired, or were offline due to the reduction in off-site liquid disposal facilities. (See **Attachment B** Monitoring List).

SCS will continue to collect down-hole temperatures for wells on an annual basis and will report the results as the data is obtained at each location. SCS has performed annual down-hole temperature monitoring at 15 locations as of the end of May 2026, as reported in the last monthly report (Results are shown in **Attachment B**). The remaining fourteen (14) wells will be monitored in accordance with the annual requirements and as pumps are repaired or replaced (See **Attachment B for well monitoring dates and remaining locations**).

**4. Sample the selected 40 wells for VOCs by method TO-15. See Table 1, column labeled "VOC (TO-15)."**

The results for wells monitored are provided in **Attachment A**.[3] Please note that 31 locations for VOC sampling were tested during May 2026. Nine locations (CV-100, CV-103, CV-1532, CV-2202, H-1403W, H-1560S, H-1758N, H-1774S, and TC-2385A) were not sampled as they have been abandoned.

**5. Continue to sample and monitor 6 horizontal wells as indicated in Attachment 1, well numbers highlighted in yellow. At this time, 42 horizontal wells may be released from continued sampling, however, wells may be included later depending on future data submissions. See Table 1, well numbers highlighted in blue.**

As noted in the September 3, 2024 letter and reported in prior monthly reports, two (2) of the six (6) horizontal wells (H-1774S and H-1560S) were abandoned when the new vertical extraction wells were installed. Additionally, H-1403W has since been abandoned. Thus, data from those wells are not included. Data from the three (3) other horizontal wells are in **Attachment A**.

**6. Add 20 vertical wells to the monthly wellhead temperature and LFG sampling protocols. See Table 1.**

As conveyed by the LEA during our September 12, 2024 meeting, and restated in our prior monthly reports, we understand the LEA is requiring laboratory analytical data for fixed gases, CO, and H2, as well as field data. Laboratory results are in **Attachment A**. Field data with wellhead gas temperatures are shown on Table 2 in **Attachment A**.

We understand from the LEA's November 27, 2024 correspondence that laboratory analytical data will be required for the specified fixed gases.

Note that following wells were again not sampled in May 2026, for the following reasons noted in prior monthly reports:

[3] Well CV-24142 is listed twice in Table 1 of the LEA's July 30, 2024 letter – one requires VOC sampling, and the other does not. Chiquita sampled this well for VOCs.

CV-1420 – Abandoned during 2024 GCCS Expansion due to declining gas flows.
CV-2202 – Abandoned during 2024 GCCS Expansion due to declining gas flows.
CV-2332 – This well does not exist. This well was proposed for installation in Fall 2023, but other wells were installed in the area in lieu of CV-2332 when the number of wells increased pursuant to the Stipulated Order for Abatement (Stipulated Order) with the South Coast Air Quality Management District (South Coast AQMD).

**7. Plot to show the locations of the following 19 wells on the site map titled "Existing GCCS Map – LFG Vertical Extraction Wells" dated 06/06/2024: CV-24002, CV-24003, CV-24007, CV-24017, CV-24053, CV-24055, CV-24065, CV-24071, CV-24075, CV-24077, CV-24079, CV-24082, CV-24083, CV-24088, CV-24095, CV-24096, CV-24097, CV-24098 and H-1403W. For well H-1403W, provide the horizontal location of piping and an estimate where the high temperature (195°F) is most likely occurring. See Table 1, well numbers highlighted in red and H-1403W (highlighted in yellow).**

The locations of the above-identified wells are shown on the Map in **Attachment C**.[4]

**8. Include in the monthly report, a settlement/heat map as shown below, beginning with the earliest heat map data available for each month to present. The topographic maps should show 2-foot contour intervals if possible.**

The LEA directed Chiquita on June 2, 2025 to submit isopach maps on a monthly basis to comply with this request. For ease of reference, we are submitting as **Attachment F** a copy of the May 2026 isopach map, which was initially submitted to the LEA with the weekly cover logs on June 9, 2026.

**9. Provide the sampling results in a standalone report with the appropriate discussion, tables, QA/QC, methods and signed by a registered professional, etc., as described in the Compliance Order Milestone 1A-2 and 1A-3.**

CCL has provided the above-requested information and the raw data in **Attachment A**, as well as a figure with the data-driven reaction area which incorporates settlement data (see **Attachment F**). Temperature graphs are provided for wells with Lorentz pumps (4 locations).

Please note that in addition to the wells listed in response to the request dated July 30, 2024 (in Table 1) that could not be tested, the following wells that only required analytical data could also not be tested, as previously reported, because they were abandoned during the 2024 and 2025 GCCS expansion due to declining gas flows in accordance with the requirements of the NSPS: CV-100, CV-103, CV-1420, CV-1423, CV-1532, CV-2202, H-

[4] The LEA acknowledged in its November 20, 2024 correspondence that a high temperature is not occurring in well H-1403W. We therefore did not map the maximum temperature at well H-1403W.

1403W, H-1560S, H-1774S, SC-2001W, TC-2383S, TC-2385A, and TC-2385S. Finally, as also previously reported, CV-2332 was never installed.

Sampling Procedures

Gas samples were collected using Tedlar or Mylar bags, as described in Chiquita's September 3, 2024 letter and the prior monthly reports, and then delivered to certified laboratories for testing. All permanent gas (CH4, CO2, O2, N2, CO, and H2) data were analyzed within the requested 24 hours of sampling. SCS continues to believe that use of the EPA-approved 72-hour holding time for these samples would be appropriate and accurate. Nevertheless, in response to the LEA's March 17, 2025 correspondence, SCS will continue to request 24-hour holding times for all fixed gases, including CO, H2, and VOCs, collected using Mylar or Tedlar bags. However, if additional sampling is required or if the laboratories have a change in workload, this holding time may change, in which case the LEA will be notified accordingly. During May 2026, all wells were tested for VOCs (EPA method TO-15) and permanent gases (EPA methods 1946 and Alt-144) within 24 hours by providing the laboratory with duplicate bag samples as needed for VOC testing.

Additional gas and pressure data were collected using either an Envision Irwin Gas Meter or Landtec GEM 5000 Gas monitoring device. These instruments measure combustible gas concentrations in air directly on either of two scales, the first as a percent by volume of the lower explosive limit (LEL) of methane gas in air (0 to 5 percent) and the other as a percent by volume (0 to 100 percent) in the gas sampled. The detection limit for these instruments is approximately 0.10 percent by volume.

Gas monitoring testing procedures were as follows:

- Connect sample tubing, open test valve, observe pressure, and record data.
- Turn on sample pump, purge a minimum of one probe volume, and observe and record methane, oxygen, and carbon dioxide gas concentrations when readings have stabilized.
- Close test valve, disconnect sample instruments, and secure sample location.

Milestone 1A-3 Conclusions

May 2026 was the twenty-second monitoring performed pursuant to Milestone 1A-3 of the Compliance Order. The data collected in May 2026 and evaluated for this report are consistent with the data collected in the previous months of August 2024 through April 2026 as well as the data collected and evaluated by Chiquita's technical experts in accordance with the Stipulated Order to assess the Reaction Mitigation Area, including the May 2026 data most recently evaluated on June 10, 2026, as required by Conditions 9(a) and 9(b) of the Stipulated Order, most recently modified on June 4, 2026. (See **Attachment E**.)

For the reasons described in the attached June 10, 2026 boundary determination, and applying the modified approach set forth in Condition 9(b), the extent of the data-determined Reaction Mitigation Area (dashed magenta line) is fully contained within the Reaction Mitigation Area boundary decreed in the SOFA (solid black line), except for Grid Nos. 38, 41, 53, 76, 77, 82, and 145 through 149, of which all or a portion protrudes east beyond the Cell 1/2A boundary. Because the data-driven Reaction Mitigation Area is not fully contained within the Reaction Mitigation Area boundary, the Reaction Mitigation Area boundary as prescribed in Condition No. 9a is modified to include portions of these Grids that extend beyond the Cell 1/2A boundary.

- Grid No. 38 is being incorporated based on the poor LFG quality criterium;
- Grid No. 41 is being incorporated based on the poor LFG quality and hydrogen criteria;
- Grid No. 53 is being incorporated based on the TMP temperature and poor LFG quality criteria;
- Grid No. 77 is being incorporated based on the TMP temperature, poor LFG quality, and CO concentration criteria;
- Grid No. 82 is being incorporated based on the poor LFG quality, hydrogen, and CO criteria.

As liquid levels fluctuate due to the shutdown and the current restart of multiple Lorentz Electric and Pneumatic Pumps, we have seen the percentages of Permanent Gases, Carbon Monoxide, and Hydrogen and temperatures change as these gases move towards the extraction wells for removal. This continues to be demonstrated by the multiscale well graphics included in Attachment D, which includes graphics on permanent gases, temperature, and other trends over a twelve (12)-month period. Note that these graphs were created using standard landfill gas monitoring equipment and the results do not contain laboratory data. SCS has also included separate Hydrogen and Carbon Monoxide graphs using laboratory results for your use and review for each well.

Additionally, the installation of larger diameter piping has improved the collection of additional gases throughout the Landfill. Since March 2025, the flow rates of landfill gas being combusted by the abatement devices have ranged from 13,500 cfm to 16,700 cfm. During May 2026, the overall gas extraction from the Landfill was approximately 645,851,520 cubic feet. May's daily landfill gas extraction rate was slightly lower than April's rate due to blower issues, flare cleaning, and other GCCS upgrades. Future increases of this extraction rate are anticipated as the collection systems continue to expand, and the gas composition of the wells in the reaction area is expected to improve as more vacuum, liquid removal, and resulting movement of gas allows more reaction and normal landfill gas to be extracted.

Chiquita will continue to evaluate the data in future monthly reports as additional data is collected.

Milestone 5 Compliance Items

This report includes in **Attachment D** individual maps overlayed with the following data for May 2026 in an easily understood format, in accordance with Milestone 5 of the Compliance Order:

- Defined reaction area;
- Expansion of reaction area, if any;
- Weekly TMP data; and
- LFG data including, but not limited to, CH4, CO2, O2, Temperature, CO, and H2 data.

Milestone 5 also requires "settlement with heat maps," but as discussed earlier in this report and in accordance with LEA correspondence dated November 27 and December 3, 2024, this requirement is satisfied by Chiquita's submittal of its monthly isopach maps to the LEA, which was done on June 9, 2026. For the LEA's convenience, the May 2026 isopach map is included herein as **Attachment F**.

The signatories below are a licensed professional/senior VP, the site project manager, and a Regional Manager VP of SCS Engineers.

Sincerely,

Rachelle Huber
Project Manager
SCS Engineers

Arthur E Jones Jr
Vice President
SCS Engineers

Srividhya Viswanathan, P.E.*
Senior Vice President
SCS Engineers

Attachments:

Attachment A – Laboratory Analysis and LFG Extraction Well Instrument and Temperature Data
Attachment B – Down Well Temperatures and List of Wells for Monitoring
Attachment C – Item 7 - Well Location Map

Attachment D – Milestone 5 Compliance Data
Attachment E – June 10, 2026 Reaction Mitigation Area Report
Attachment F – May 2026 Isopach Map

Electronic Data of Laboratory Results and Extraction Well data are in Excel format, with additional PDFs for gas well data.

cc: John Perkey, Chiquita Canyon
Kevin Green, Chiquita Canyon
William Haley, Chiquita Canyon
Dylan Smith, Chiquita Canyon
Sarah Phillips, Chiquita Canyon
Pat Sullivan, SCS Engineers
Liza Frias, Los Angeles County Department of Public Health
Nichole Quick, M.D., Los Angeles County Department of Public Health
Beverly Tway, Los Angeles County LEA
Eric Morofuji, Los Angeles County LEA
Renee Jensen, LEA Counsel
Blaine McPhillips, Senior Deputy County Counsel
Emiko Thompson, Los Angeles County Department of Public Works
Alex Garcia, Los Angeles County Department of Regional Planning
Phillip Chen, Los Angeles County Department of Regional Planning
Steven Jareb, Los Angeles County Department of Regional Planning
Wes Mindermann, CalRecycle
Todd Thalhamer, CalRecycle
Emel Wadhwani, CalRecycle
Jeff Linberg, California Air Recourses Board
Nancy Fletcher, California Air Recourses Board
Jack Cheng, South Coast Air Quality Management Board
Larry Israel, South Coast Air Quality Management Board
Enrique Casas, Los Angeles Regional Water Quality Control Board
Joshua Wirtschafter, United States Environmental Protection Agency
Laura Friedli, United States Environmental Protection Agency
Tyler Holybee, United States Environmental Protection Agency
Mark Anthony Relon, United States Environmental Protection Agency
Gregory Schaffer, Department of Toxic Substances Control
Natasha DiPietro, Department of Toxic Substances Control
Gregory Gentile, Department of Toxic Substances Control

# Attachment A

# Laboratory Analysis

# And

# LFG Extraction Well Instrument and Temperature Data

SGS

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175

TX Cert T104704450-14-6
EPA Methods TO14A, TO15

ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

May 19, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

## LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T050401-01/10

Enclosed are the results for sample(s) received 5/4/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags. High recovery was exhibited for chlorobenzene in the internal standard indicating a possible low bias. Effected results are flagged with the Q qualifier.
- High recovery was exhibited in the continuing calibration verification for 4-ethyl toluene and isopropanol indicating a possible bias. Results are flagged with the Q qualifier.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Jenny Kim, Art Jones and Ali Ferrara on 5/18/26.

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

# CHAIN OF CUSTODY RECORD

| TURNAROUND TIME | | | | DELIVERABLES | | PAGE: 1 OF |
|---|---|---|---|---|---|---|
| Standard | ■ | 48 hours | ☐ | EDD | ■ | Condition upon receipt: |
| Same Day | ☐ | 72 hours | ☐ | EDF | ☐ | Sealed Yes ☐ No ☐ |
| 24 hours | ☐ | 96 hours | ☐ | Level 3 | ☐ | Intact Yes ☐ No ☐ |
| Other: | | | | Level 4 | ☐ | Chilled _____ deg C |

| | |
|---|---|
| *Project No.:* | 07224200.24 Task 1 |
| *Project Name:* | Chiquita Canyon Landfill |
| *Report To:* | Cornelius Fong |
| *Company:* | SCS Engineers |
| *Street:* | 3900 Kilroy Airport Way, Suite 300 |
| *City/State/Zip:* | Long Beach, CA 90806-6816 |
| *Phone& Fax:* | 562-743-7895 |
| *e-mail:* | cfong@scsengineers.com |

**BILLING**

| | |
|---|---|
| *P.O. No.:* | |
| *Bill to:* | 07FSAccountspayable@scsengineers.com |
| | 3900 Kilroy Airport Way, Suite 300 |
| | Long Beach, CA 90806-6816 |

**ANALYSIS REQUEST**

| LAB USE ONLY | SAMPLE IDENTIFICATION | SAMPLE DATE | SAMPLE TIME | CONTAINER QTY/TYPE | MATRIX | PRESERVATION | CH4, CO2, O2, N2 ASTM D1946 | Carbon Monoxide EPA ALT-144 | Hydrogen ASTM D1946 | VOCs EPA TO-15 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| T050401-01 | CV-113 | 05/04/26 | 7:50am | 2-1L | Gas | N | X | X | X | X | | |
| -02 | CV-2007 | 05/04/26 | 8:10am | 2-1L | Gas | N | X | X | X | X | | |
| -03 | CV-24122 | 05/04/26 | 8:20am | 2-1L | Gas | N | X | X | X | X | | |
| -04 | CV-24127 | 05/04/26 | 8:15am | 2-1L | Gas | N | X | X | X | X | | |
| -05 | H-1770N | 05/04/26 | 8:50am | 2-1L | Gas | N | X | X | X | X | | |
| -06 | CV-24121 | 05/04/26 | 7:55am | 1L | Gas | N | X | X | X | | | |
| -07 | CV-24123 | 05/04/26 | 7:40am | 1L | Gas | N | X | | | | | |
| -08 | CV-99 | 05/04/26 | 7:45am | 1L | Gas | N | X | X | X | | | |
| -09 | CV-114 | 05/04/26 | 8:05am | 1L | Gas | N | X | X | X | | | |
| -10 | CV-24120 | 05/04/26 | 8:00am | 1L | Gas | N | X | X | X | | | |

| | COMPANY | DATE/TIME | | | |
|---|---|---|---|---|---|
| AUTHORIZATION TO PERFORM WORK | SCS | | | | |
| SAMPLED BY: Fabian Chavez | SCS | 5/4/26 | | | |
| RELINQUISHED BY | DATE/TIME 5/4/26 9:15am | RECEIVED BY | DATE/TIME 5/4/26 9:16 | | |
| RELINQUISHED BY | DATE/TIME 5/4/26 11:29 | RECEIVED BY | DATE/TIME 5/4/26 11:29 | | |
| RELINQUISHED BY | DATE/TIME | RECEIVED BY | DATE/TIME | | |

**COMMENTS**
Report full list of TO-15 compounds
Raw landfill gas samples
**FLAMMABLE**

**METHOD OF TRANSPORT (circle one):** Walk-In FedEx UPS **Courier** ATLI Other_____

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: H=HCl N=None / Container: B=Bag C=Can V=VOA O=Other *Rev. 03 - 5/7/09*

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/04/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | T050401-01 | | T050401-02 | | T050401-03 | | T050401-04 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-113 | | CV-2007 | | CV-24122 | | CV-24127 | |
| Date/Time Sampled: | 5/4/26 7:50 | | 5/4/26 8:10 | | 5/4/26 8:20 | | 5/4/26 8:15 | |
| Date/Time Analyzed: | 5/4/26 18:14 | | 5/4/26 18:52 | | 5/4/26 19:31 | | 5/4/26 20:09 | |
| QC Batch No.: | 260504MS2A1 | | 260504MS2A1 | | 260504MS2A1 | | 260504MS2A1 | |
| Analyst Initials: | AS/GD | | AS/GD | | AS/GD | | AS/GD | |
| Dilution Factor: | 5,000 | | 1,000 | | 1,500 | | 5,000 | |
| ANALYTE | Result ppbv | RL ppbv | Result ppbv | RL ppbv | Result ppbv | RL ppbv | Result ppbv | RL ppbv |
| Dichlorodifluoromethane (12) | ND | 5,000 | ND | 1,000 | ND | 1,500 | ND | 5,000 |
| Chloromethane | ND | 5,000 | ND | 1,000 | ND | 1,500 | **11,000** | 5,000 |
| 1,2-Cl-1,1,2,2-F ethane (114) | ND | 5,000 | ND | 1,000 | ND | 1,500 | ND | 5,000 |
| Vinyl Chloride | ND | 5,000 | ND | 1,000 | ND | 1,500 | ND | 5,000 |
| Bromomethane | ND | 5,000 | ND | 1,000 | ND | 1,500 | ND | 5,000 |
| Chloroethane | ND | 25,000 | ND | 5,000 | ND | 7,500 | ND | 25,000 |
| Trichlorofluoromethane (11) | ND | 5,000 | ND | 1,000 | ND | 1,500 | ND | 5,000 |
| 1,1-Dichloroethene | ND | 5,000 | ND | 1,000 | ND | 1,500 | ND | 5,000 |
| Carbon Disulfide | ND | 5,000 | ND | 1,000 | ND | 1,500 | ND | 5,000 |
| 1,1,2-Cl 1,2,2-F ethane (113) | ND | 5,000 | ND | 1,000 | ND | 1,500 | ND | 5,000 |
| Acetone | **68,000** | 25,000 | **86,000** | 5,000 | **120,000** | 7,500 | **370,000** | 25,000 |
| Methylene Chloride | ND | 5,000 | ND | 1,000 | ND | 1,500 | ND | 5,000 |
| t-1,2-Dichloroethene | ND | 5,000 | ND | 1,000 | ND | 1,500 | ND | 5,000 |
| 1,1-Dichloroethane | ND | 5,000 | ND | 1,000 | ND | 1,500 | ND | 5,000 |
| Vinyl Acetate | ND | 5,000 | ND | 1,000 | ND | 1,500 | ND | 5,000 |
| c-1,2-Dichloroethene | ND | 5,000 | ND | 1,000 | ND | 1,500 | ND | 5,000 |
| 2-Butanone | **49,000** | 25,000 | **110,000** | 5,000 | **120,000** | 7,500 | **380,000** | 25,000 |
| t-Butyl Methyl Ether (MTBE) | ND | 5,000 | **1,400** | 1,000 | ND | 1,500 | ND | 5,000 |
| Chloroform | ND | 5,000 | ND | 1,000 | ND | 1,500 | ND | 5,000 |
| 1,1,1-Trichloroethane | ND | 5,000 | ND | 1,000 | ND | 1,500 | ND | 5,000 |
| Carbon Tetrachloride | ND | 5,000 | ND | 1,000 | ND | 1,500 | ND | 5,000 |
| Benzene | **110,000** | 5,000 | **150,000** | 1,000 | **31,000** | 1,500 | **250,000** | 5,000 |
| 1,2-Dichloroethane | ND | 5,000 | ND | 1,000 | ND | 1,500 | ND | 5,000 |
| Trichloroethene | ND | 5,000 | ND | 1,000 | ND | 1,500 | ND | 5,000 |
| 1,2-Dichloropropane | ND | 5,000 | ND | 1,000 | ND | 1,500 | ND | 5,000 |
| Bromodichloromethane | ND | 5,000 | ND | 1,000 | ND | 1,500 | ND | 5,000 |
| c-1,3-Dichloropropene | ND | 5,000 | ND | 1,000 | ND | 1,500 | ND | 5,000 |
| 4-Methyl-2-Pentanone | ND | 5,000 | **4,100** | 1,000 | **2,400** | 1,500 | **6,300** | 5,000 |
| Toluene | ND | 5,000 | **8,000** | 1,000 | **3,100** | 1,500 | **12,000** | 5,000 |
| t-1,3-Dichloropropene | ND | 10,000 | ND Q | 2,000 | ND Q | 3,000 | ND Q | 10,000 |
| 1,1,2-Trichloroethane | ND | 5,000 | ND Q | 1,000 | ND Q | 1,500 | ND Q | 5,000 |
| Tetrachloroethene | ND | 5,000 | ND Q | 1,000 | ND Q | 1,500 | ND Q | 5,000 |
| 2-Hexanone | ND | 5,000 | **1,300** Q | 1,000 | ND Q | 1,500 | ND Q | 5,000 |
| Dibromochloromethane | ND | 5,000 | ND Q | 1,000 | ND Q | 1,500 | ND Q | 5,000 |

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/04/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | T050401-01 | | T050401-02 | | T050401-03 | | T050401-04 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-113 | | CV-2007 | | CV-24122 | | CV-24127 | |
| Date/Time Sampled: | 5/4/26 7:50 | | 5/4/26 8:10 | | 5/4/26 8:20 | | 5/4/26 8:15 | |
| Date/Time Analyzed: | 5/4/26 18:14 | | 5/4/26 18:52 | | 5/4/26 19:31 | | 5/4/26 20:09 | |
| QC Batch No.: | 260504MS2A1 | | 260504MS2A1 | | 260504MS2A1 | | 260504MS2A1 | |
| Analyst Initials: | AS/GD | | AS/GD | | AS/GD | | AS/GD | |
| Dilution Factor: | 5,000 | | 1,000 | | 1,500 | | 5,000 | |
| ANALYTE | Result ppbv | RL ppbv | Result ppbv | RL ppbv | Result ppbv | RL ppbv | Result ppbv | RL ppbv |
| 1,2-Dibromoethane | ND | 5,000 | ND Q | 1,000 | ND Q | 1,500 | ND Q | 5,000 |
| Chlorobenzene | ND | 5,000 | ND Q | 1,000 | ND Q | 1,500 | ND Q | 5,000 |
| Ethylbenzene | ND | 5,000 | ND Q | 1,000 | ND Q | 1,500 | ND Q | 5,000 |
| p,&m-Xylene | ND | 10,000 | ND Q | 2,000 | ND Q | 3,000 | ND Q | 10,000 |
| o-Xylene | ND | 5,000 | ND Q | 1,000 | ND Q | 1,500 | ND Q | 5,000 |
| Styrene | ND | 5,000 | ND Q | 1,000 | ND Q | 1,500 | ND Q | 5,000 |
| Bromoform | ND | 5,000 | ND Q | 1,000 | ND Q | 1,500 | ND Q | 5,000 |
| 1,1,2,2-Tetrachloroethane | ND | 5,000 | ND Q | 1,000 | ND Q | 1,500 | ND Q | 5,000 |
| Benzyl Chloride | ND | 5,000 | ND Q | 1,000 | ND Q | 1,500 | ND Q | 5,000 |
| 4-Ethyl Toluene | ND | 5,000 | ND Q | 1,000 | ND Q | 1,500 | ND Q | 5,000 |
| 1,3,5-Trimethylbenzene | ND | 5,000 | ND Q | 1,000 | ND Q | 1,500 | ND Q | 5,000 |
| 1,2,4-Trimethylbenzene | ND | 5,000 | ND Q | 1,000 | ND Q | 1,500 | ND Q | 5,000 |
| 1,3-Dichlorobenzene | ND | 5,000 | ND Q | 1,000 | ND Q | 1,500 | ND Q | 5,000 |
| 1,4-Dichlorobenzene | ND | 5,000 | ND Q | 1,000 | ND Q | 1,500 | ND Q | 5,000 |
| 1,2-Dichlorobenzene | ND | 5,000 | ND Q | 1,000 | ND Q | 1,500 | ND Q | 5,000 |
| 1,2,4-Trichlorobenzene | ND | 5,000 | ND Q | 1,000 | ND Q | 1,500 | ND Q | 5,000 |
| Hexachlorobutadiene | ND | 5,000 | ND Q | 1,000 | ND Q | 1,500 | ND Q | 5,000 |
| 1,3-Butadiene | ND | 25,000 | 6,700 | 5,000 | ND | 7,500 | ND | 25,000 |
| Isopropanol | 68,000 Q | 25,000 | 98,000 Q | 5,000 | 110,000 Q | 7,500 | 120,000 Q | 25,000 |
| n-Hexane | ND | 25,000 | ND | 5,000 | ND | 7,500 | ND | 25,000 |
| Ethyl Acetate | ND | 25,000 | 16,000 | 5,000 | 9,100 | 7,500 | 69,000 | 25,000 |
| Tetrahydrofuran | 61,000 Q | 25,000 | 160,000 Q | 5,000 | 86,000 Q | 7,500 | 330,000 Q | 25,000 |
| Cyclohexane | ND | 25,000 | ND | 5,000 | ND | 7,500 | ND | 25,000 |
| Heptane | ND | 25,000 | 8,800 | 5,000 | ND | 7,500 | ND | 25,000 |
| 1,4-Dioxane | ND | 25,000 | ND | 5,000 | ND | 7,500 | ND | 25,000 |
| | | | | | | | | |

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Refer to report narrative

Reviewed/Approved By: _____ Date 5-18-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/04/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | T050401-05 |
|---|---|
| Client Sample I.D.: | H-1770N |
| Date/Time Sampled: | 5/4/26 8:50 |
| Date/Time Analyzed: | 5/4/26 20:48 |
| QC Batch No.: | 260504MS2A1 |
| Analyst Initials: | AS/GD |
| Dilution Factor: | 1,200 |

| ANALYTE | Result ppbv | RL ppbv |
|---|---|---|
| Dichlorodifluoromethane (12) | ND | 1,200 |
| Chloromethane | ND | 1,200 |
| 1,2-Cl-1,1,2,2-F ethane (114) | ND | 1,200 |
| Vinyl Chloride | ND | 1,200 |
| Bromomethane | ND | 1,200 |
| Chloroethane | ND | 6,000 |
| Trichlorofluoromethane (11) | ND | 1,200 |
| 1,1-Dichloroethene | ND | 1,200 |
| Carbon Disulfide | ND | 1,200 |
| 1,1,2-Cl 1,2,2-F ethane (113) | ND | 1,200 |
| Acetone | 95,000 | 6,000 |
| Methylene Chloride | ND | 1,200 |
| t-1,2-Dichloroethene | ND | 1,200 |
| 1,1-Dichloroethane | ND | 1,200 |
| Vinyl Acetate | ND | 1,200 |
| c-1,2-Dichloroethene | ND | 1,200 |
| 2-Butanone | 120,000 | 6,000 |
| t-Butyl Methyl Ether (MTBE) | ND | 1,200 |
| Chloroform | ND | 1,200 |
| 1,1,1-Trichloroethane | ND | 1,200 |
| Carbon Tetrachloride | ND | 1,200 |
| Benzene | 150,000 | 1,200 |
| 1,2-Dichloroethane | ND | 1,200 |
| Trichloroethene | ND | 1,200 |
| 1,2-Dichloropropane | ND | 1,200 |
| Bromodichloromethane | ND | 1,200 |
| c-1,3-Dichloropropene | ND | 1,200 |
| 4-Methyl-2-Pentanone | 4,000 | 1,200 |
| Toluene | 8,600 | 1,200 |
| t-1,3-Dichloropropene | ND | 2,400 |
| 1,1,2-Trichloroethane | ND | 1,200 |
| Tetrachloroethene | ND | 1,200 |
| 2-Hexanone | ND | 1,200 |
| Dibromochloromethane | ND | 1,200 |

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/04/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | T050401-05 |
|---|---|
| Client Sample I.D.: | H-1770N |
| Date/Time Sampled: | 5/4/26 8:50 |
| Date/Time Analyzed: | 5/4/26 20:48 |
| QC Batch No.: | 260504MS2A1 |
| Analyst Initials: | AS/GD |
| Dilution Factor: | 1,200 |

| ANALYTE | Result ppbv | RL ppbv |
|---|---|---|
| 1,2-Dibromoethane | ND | 1,200 |
| Chlorobenzene | ND | 1,200 |
| Ethylbenzene | ND | 1,200 |
| p,&m-Xylene | ND | 2,400 |
| o-Xylene | ND | 1,200 |
| Styrene | ND | 1,200 |
| Bromoform | ND | 1,200 |
| 1,1,2,2-Tetrachloroethane | ND | 1,200 |
| Benzyl Chloride | ND | 1,200 |
| 4-Ethyl Toluene | ND | 1,200 |
| 1,3,5-Trimethylbenzene | ND | 1,200 |
| 1,2,4-Trimethylbenzene | ND | 1,200 |
| 1,3-Dichlorobenzene | ND | 1,200 |
| 1,4-Dichlorobenzene | ND | 1,200 |
| 1,2-Dichlorobenzene | ND | 1,200 |
| 1,2,4-Trichlorobenzene | ND | 1,200 |
| Hexachlorobutadiene | ND | 1,200 |
| 1,3-Butadiene | ND | 6,000 |
| Isopropanol | 100,000 Q | 6,000 |
| n-Hexane | ND | 6,000 |
| Ethyl Acetate | 14,000 | 6,000 |
| Tetrahydrofuran | 170,000 Q | 6,000 |
| Cyclohexane | ND | 6,000 |
| Heptane | 11,000 | 6,000 |
| 1,4-Dioxane | ND | 6,000 |

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Refer to report narrative

Reviewed/Approved By: _____ Date 5-18-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/04/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | Method Blank | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | - | | | | | | | |
| Date/Time Sampled: | - | | | | | | | |
| Date/Time Analyzed: | 5/4/26 14:01 | | | | | | | |
| QC Batch No.: | 260504MS2A1 | | | | | | | |
| Analyst Initials: | AS/GD | | | | | | | |
| Dilution Factor: | 0.20 | | | | | | | |

| ANALYTE | Result ppbv | RL ppbv | | | | | | |
|---|---|---|---|---|---|---|---|---|
| Dichlorodifluoromethane (12) | ND | 0.20 | | | | | | |
| Chloromethane | ND | 0.20 | | | | | | |
| 1,2-Cl-1,1,2,2-F ethane (114) | ND | 0.20 | | | | | | |
| Vinyl Chloride | ND | 0.20 | | | | | | |
| Bromomethane | ND | 0.20 | | | | | | |
| Chloroethane | ND | 1.0 | | | | | | |
| Trichlorofluoromethane (11) | ND | 0.20 | | | | | | |
| 1,1-Dichloroethene | ND | 0.20 | | | | | | |
| Carbon Disulfide | ND | 0.20 | | | | | | |
| 1,1,2-Cl 1,2,2-F ethane (113) | ND | 0.20 | | | | | | |
| Acetone | ND | 1.0 | | | | | | |
| Methylene Chloride | ND | 0.20 | | | | | | |
| t-1,2-Dichloroethene | ND | 0.20 | | | | | | |
| 1,1-Dichloroethane | ND | 0.20 | | | | | | |
| Vinyl Acetate | ND | 0.20 | | | | | | |
| c-1,2-Dichloroethene | ND | 0.20 | | | | | | |
| 2-Butanone | ND | 1.0 | | | | | | |
| t-Butyl Methyl Ether (MTBE) | ND | 0.20 | | | | | | |
| Chloroform | ND | 0.20 | | | | | | |
| 1,1,1-Trichloroethane | ND | 0.20 | | | | | | |
| Carbon Tetrachloride | ND | 0.20 | | | | | | |
| Benzene | ND | 0.20 | | | | | | |
| 1,2-Dichloroethane | ND | 0.20 | | | | | | |
| Trichloroethene | ND | 0.20 | | | | | | |
| 1,2-Dichloropropane | ND | 0.20 | | | | | | |
| Bromodichloromethane | ND | 0.20 | | | | | | |
| c-1,3-Dichloropropene | ND | 0.20 | | | | | | |
| 4-Methyl-2-Pentanone | ND | 0.20 | | | | | | |
| Toluene | ND | 0.20 | | | | | | |
| t-1,3-Dichloropropene | ND | 0.40 | | | | | | |
| 1,1,2-Trichloroethane | ND | 0.20 | | | | | | |
| Tetrachloroethene | ND | 0.20 | | | | | | |
| 2-Hexanone | ND | 0.20 | | | | | | |
| Dibromochloromethane | ND | 0.20 | | | | | | |

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/04/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | Method Blank |
|---|---|
| Client Sample I.D.: | - |
| Date/Time Sampled: | - |
| Date/Time Analyzed: | 5/4/26 14:01 |
| QC Batch No.: | 260504MS2A1 |
| Analyst Initials: | AS/GD |
| Dilution Factor: | 0.20 |

| ANALYTE | Result ppbv | RL ppbv |
|---|---|---|
| 1,2-Dibromoethane | ND | 0.20 |
| Chlorobenzene | ND | 0.20 |
| Ethylbenzene | ND | 0.20 |
| p,&m-Xylene | ND | 0.40 |
| o-Xylene | ND | 0.20 |
| Styrene | ND | 0.20 |
| Bromoform | ND | 0.20 |
| 1,1,2,2-Tetrachloroethane | ND | 0.20 |
| Benzyl Chloride | ND | 0.20 |
| 4-Ethyl Toluene | ND | 0.20 |
| 1,3,5-Trimethylbenzene | ND | 0.20 |
| 1,2,4-Trimethylbenzene | ND | 0.20 |
| 1,3-Dichlorobenzene | ND | 0.20 |
| 1,4-Dichlorobenzene | ND | 0.20 |
| 1,2-Dichlorobenzene | ND | 0.20 |
| 1,2,4-Trichlorobenzene | ND | 0.20 |
| Hexachlorobutadiene | ND | 0.20 |
| 1,3-Butadiene | ND | 1.0 |
| Isopropanol | ND | 1.0 |
| n-Hexane | ND | 1.0 |
| Ethyl Acetate | ND | 1.0 |
| Tetrahydrofuran | ND | 1.0 |
| Cyclohexane | ND | 1.0 |
| Heptane | ND | 1.0 |
| 1,4-Dioxane | ND | 1.0 |

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 5-18-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

# LCS/LCSD Recovery and RPD Summary Report

## QC Batch #: 260504MS2A1

**Matrix:** Air

**Reporting Units:** ppbv

**EPA Method TO-15**
**LABORATORY CONTROL SAMPLE SUMMARY**

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Lab No.: | METHOD BLANK | | | LCS | | LCSD | | | | | |
| Date/Time Analyzed: | 5/4/26 14:01 | | | 5/4/26 12:45 | | 5/4/26 13:23 | | | | | |
| Analyst Initials: | AS/GD | | | AS/GD | | AS/GD | | | | | |
| Dilution Factor: | 0.20 | | | 1.0 | | 1.0 | | | | | |
| ANALYTE | Result ppbv | RL ppbv | AMT. ppbv | Result ppbv | % Rec. | Result ppbv | % Rec. | RPD | Low %Rec | High %Rec | Max. RPD |
| 1,1-Dichloroethene | ND | 0.20 | 10 | 12.6 | 126 | 12.4 | 124 | 1.7 | 70 | 130 | 30 |
| Methylene Chloride | ND | 0.20 | 10 | 11.6 | 116 | 11.7 | 117 | 0.4 | 70 | 130 | 30 |
| Trichloroethene | ND | 0.20 | 10 | 12.1 | 121 | 11.9 | 119 | 1.8 | 70 | 130 | 30 |
| Toluene | ND | 0.20 | 10 | 11.9 | 119 | 12.0 | 120 | 0.4 | 70 | 130 | 30 |
| 1,1,2,2-Tetrachloroethane | ND | 0.20 | 10 | 9.79 | 98 | 9.93 | 99 | 1.4 | 70 | 130 | 30 |
| | | | | | | | | | | | |

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date: 5-18-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/04/26
**Matrix:** Air
**Reporting Units:** ppmv

## EPA ALT-144 (CO by FID)

| Lab No.: | T050401-01 | | T050401-02 | | T050401-03 | | T050401-04 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-113 | | CV-2007 | | CV-24122 | | CV-24127 | |
| Date/Time Sampled: | 5/4/26 7:50 | | 5/4/26 8:10 | | 5/4/26 8:20 | | 5/4/26 8:15 | |
| Date/Time Analyzed: | 5/4/26 14:46 | | 5/4/26 15:01 | | 5/4/26 15:15 | | 5/4/26 15:30 | |
| QC Batch No.: | 260504GC8A1 | | 260504GC8A1 | | 260504GC8A1 | | 260504GC8A1 | |
| Analyst Initials: | KD | | KD | | KD | | KD | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | 1.0 | |
| ANALYTE | Result ppmv | RL ppmv | Result ppmv | RL ppmv | Result ppmv | RL ppmv | Result ppmv | RL ppmv |
| Carbon Monoxide | 1,400 | 10 | 810 | 10 | 180 | 10 | 3,300 | 10 |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-12-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/04/26
**Matrix:** Air
**Reporting Units:** ppmv

## EPA ALT-144 (CO by FID)

| Lab No.: | T050401-05 | | T050401-06 | | T050401-08 | | T050401-09 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | H-1770N | | CV-24121 | | CV-99 | | CV-114 | |
| Date/Time Sampled: | 5/4/26 8:50 | | 5/4/26 7:55 | | 5/4/26 7:45 | | 5/4/26 8:05 | |
| Date/Time Analyzed: | 5/4/26 15:44 | | 5/4/26 15:58 | | 5/4/26 16:27 | | 5/4/26 16:42 | |
| QC Batch No.: | 260504GC8A1 | | 260504GC8A1 | | 260504GC8A1 | | 260504GC8A1 | |
| Analyst Initials: | KD | | KD | | KD | | KD | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | 1.0 | |
| ANALYTE | Result ppmv | RL ppmv | Result ppmv | RL ppmv | Result ppmv | RL ppmv | Result ppmv | RL ppmv |
| Carbon Monoxide | 81 | 10 | 120 | 10 | 110 | 10 | ND | 10 |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-12-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report



SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com

Member of the SGS Group (SGS SA)

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/04/26
**Matrix:** Air
**Reporting Units:** ppmv

## EPA ALT-144 (CO by FID)

| Lab No.: | T050401-10 | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-24120 | | | | | | | |
| Date/Time Sampled: | 5/4/26 8:00 | | | | | | | |
| Date/Time Analyzed: | 5/4/26 16:56 | | | | | | | |
| QC Batch No.: | 260504GC8A1 | | | | | | | |
| Analyst Initials: | KD | | | | | | | |
| Dilution Factor: | 1.0 | | | | | | | |
| **ANALYTE** | **Result ppmv** | **RL ppmv** | | | | | | |
| Carbon Monoxide | 1,400 | 10 | | | | | | |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-12-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report



SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com
Member of the SGS Group (SGS SA)

**QC Batch No:** 260504GC8A1
**Matrix:** Air
**Reporting Units:** ppmv

## EPA ALT-144 (CO by FID)
## LABORATORY CONTROL SAMPLE SUMMARY

| Lab No.: | METHOD BLANK | | | LCS | | LCSD | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Date Analyzed: | 5/4/26 11:08 | | | 5/4/26 11:23 | | 5/4/26 11:37 | | | | | |
| Analyst Initials: | KD | | | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | | 1.0 | | 1.0 | | | Limits | | |
| ANALYTE | Result ppmv | RL ppmv | SPIKE AMT. ppmv | Result ppmv | % Rec. | Result ppmv | % Rec. | RPD % | Low %Rec | High %Rec | Max. RPD |
| Carbon Monoxide | ND | 10 | 1,010 | 1,020 | 101 | 1,010 | 100 | 0.7 | 70 | 130 | 30 |
| | | | | | | | | | | | |

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 5-12-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/04/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T050401-05 | | | T050401-06 | | | T050401-08 | | | T050401-09 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | H-1770N | | | CV-24121 | | | CV-99 | | | CV-114 | | |
| Date/Time Sampled: | 5/4/26 8:50 | | | 5/4/26 7:55 | | | 5/4/26 7:45 | | | 5/4/26 8:05 | | |
| Date/Time Analyzed: | 5/4/26 15:44 | | | 5/4/26 15:58 | | | 5/4/26 16:27 | | | 5/4/26 16:42 | | |
| QC Batch No.: | 260504GC8A1 | | | 260504GC8A1 | | | 260504GC8A1 | | | 260504GC8A1 | | |
| Analyst Initials: | KD | | | KD | | | KD | | | KD | | |
| Dilution Factor: | 1.0 | | | 1.0 | | | 1.0 | | | 1.0 | | |
| ANALYTE | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v |
| Hydrogen | 1.2 | 1.0 | 0.059 | 0.27 J | 1.0 | 0.059 | 0.26 J | 1.0 | 0.059 | 0.28 J | 1.0 | 0.059 |

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-12-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/04/26
**Matrix:** Air
**Reporting Units:** % v/v

**ASTM D1946**

| | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| **Lab No.:** | **T050401-10** | | | | | | | | | | | |
| **Client Sample I.D.:** | **CV-24120** | | | | | | | | | | | |
| **Date/Time Sampled:** | **5/4/26 8:00** | | | | | | | | | | | |
| **Date/Time Analyzed:** | **5/4/26 16:56** | | | | | | | | | | | |
| **QC Batch No.:** | **260504GC8A1** | | | | | | | | | | | |
| **Analyst Initials:** | **KD** | | | | | | | | | | | |
| **Dilution Factor:** | **1.0** | | | | | | | | | | | |
| **ANALYTE** | **Result % v/v** | **RL % v/v** | **MDL % v/v** | | | | | | | | | |
| Hydrogen | 11 | 1.0 | 0.059 | | | | | | | | | |
| | | | | | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**MDL = Method Detection Limit**
**ND= Not Detected (below MDL)**
**RL = Reporting Limit**
**J = Trace amount. Analyte concentration between RL and MDL.**

**Reviewed/Approved By:** _____ **Date** 5-12-26
**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report



SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com
Member of the SGS Group (SGS SA)

**QC Batch No:** 260504GC8A1
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946
## LABORATORY CONTROL SAMPLE SUMMARY

| Lab No.: | METHOD BLANK | | | | LCS | | LCSD | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Date Analyzed: | 5/4/26 11:08 | | | | 5/4/26 11:23 | | 5/4/26 11:37 | | | | | |
| Analyst Initials: | KD | | | | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | | | 1.0 | | 1.0 | | | Limits | | |
| ANALYTE | Result % v/v | RL % v/v | MDL % v/v | SPIKE AMT. % v/v | Result % v/v | % Rec. | Result % v/v | % Rec. | RPD % | Low %Rec | High %Rec | Max. RPD |
| Hydrogen | ND | 1.0 | 0.059 | 5.0 | 3.73 | 75 | 3.69 | 74 | 1.2 | 70 | 130 | 30 |
| | | | | | | | | | | | | |

**MDL = Method Detection Limit**
**ND= Not Detected (below MDL)**
**RL = Reporting Limit**
**J = Trace amount. Analyte concentration between RL and MDL.**

**Reviewed/Approved By:** _____ **Date** 5-12-26

Mark Johnson
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/04/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T050401-01 | | | T050401-02 | | | T050401-03 | | | T050401-04 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-113 | | | CV-2007 | | | CV-24122 | | | CV-24127 | | |
| Date/Time Sampled: | 5/4/26 7:50 | | | 5/4/26 8:10 | | | 5/4/26 8:20 | | | 5/4/26 8:15 | | |
| Date/Time Analyzed: | 5/4/26 14:46 | | | 5/4/26 15:01 | | | 5/4/26 15:15 | | | 5/4/26 15:30 | | |
| QC Batch No.: | 260504GC8A1 | | | 260504GC8A1 | | | 260504GC8A1 | | | 260504GC8A1 | | |
| Analyst Initials: | KD | | | KD | | | KD | | | KD | | |
| Dilution Factor: | 1.0 | | | 1.0 | | | 1.0 | | | 1.0 | | |
| ANALYTE | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v |
| Hydrogen | 2.4 | 1.0 | 0.059 | 5.9 | 1.0 | 0.059 | 0.91 J | 1.0 | 0.059 | 16 | 1.0 | 0.059 |

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-12-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/04/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T050401-01 | | T050401-02 | | T050401-03 | | T050401-04 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-113 | | CV-2007 | | CV-24122 | | CV-24127 | |
| Date/Time Sampled: | 5/4/26 7:50 | | 5/4/26 8:10 | | 5/4/26 8:20 | | 5/4/26 8:15 | |
| Date/Time Analyzed: | 5/4/26 14:46 | | 5/4/26 15:01 | | 5/4/26 15:15 | | 5/4/26 15:30 | |
| QC Batch No.: | 260504GC8A1 | | 260504GC8A1 | | 260504GC8A1 | | 260504GC8A1 | |
| Analyst Initials: | KD | | KD | | KD | | KD | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | 1.0 | |
| **ANALYTE** | **Result % v/v** | **RL % v/v** | **Result % v/v** | **RL % v/v** | **Result % v/v** | **RL % v/v** | **Result % v/v** | **RL % v/v** |
| Carbon Dioxide | **83** | 0.010 | **73** | 0.010 | **38** | 0.010 | **67** | 0.010 |
| Oxygen/Argon | **0.61** | 0.50 | **0.72** | 0.50 | **5.0** | 0.50 | **3.0** | 0.50 |
| Nitrogen | **2.3** | 1.0 | **2.7** | 1.0 | **19** | 1.0 | **11** | 1.0 |
| Methane | **11** | 0.0010 | **17** | 0.0010 | 37 | 0.0010 | **1.7** | 0.0010 |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-12-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report



SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com

Member of the SGS Group (SGS SA)

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/04/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T050401-05 | | T050401-06 | | T050401-07 | | T050401-08 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | H-1770N | | CV-24121 | | CV-24123 | | CV-99 | |
| Date/Time Sampled: | 5/4/26 8:50 | | 5/4/26 7:55 | | 5/4/26 7:40 | | 5/4/26 7:45 | |
| Date/Time Analyzed: | 5/4/26 15:44 | | 5/4/26 15:58 | | 5/4/26 16:13 | | 5/4/26 16:27 | |
| QC Batch No.: | 260504GC8A1 | | 260504GC8A1 | | 260504GC8A1 | | 260504GC8A1 | |
| Analyst Initials: | KD | | KD | | KD | | KD | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | 1.0 | |
| ANALYTE | Result % v/v | RL % v/v | Result % v/v | RL % v/v | Result % v/v | RL % v/v | Result % v/v | RL % v/v |
| Carbon Dioxide | 59 | 0.010 | 6.9 | 0.010 | 58 | 0.010 | 53 | 0.010 |
| Oxygen/Argon | 0.62 | 0.50 | 19 | 0.50 | 1.9 | 0.50 | 4.7 | 0.50 |
| Nitrogen | 2.8 | 1.0 | 72 | 1.0 | 7.1 | 1.0 | 18 | 1.0 |
| Methane | 36 | 0.0010 | 0.99 | 0.0010 | 32 | 0.0010 | 24 | 0.0010 |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-12-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report



SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com

Member of the SGS Group (SGS SA)

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/04/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T050401-09 | | T050401-10 | | | | | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-114 | | CV-24120 | | | | | |
| Date/Time Sampled: | 5/4/26 8:05 | | 5/4/26 8:00 | | | | | |
| Date/Time Analyzed: | 5/4/26 16:42 | | 5/4/26 16:56 | | | | | |
| QC Batch No.: | 260504GC8A1 | | 260504GC8A1 | | | | | |
| Analyst Initials: | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | 1.0 | | | | | |
| **ANALYTE** | **Result % v/v** | **RL % v/v** | **Result % v/v** | **RL % v/v** | | | | |
| Carbon Dioxide | 0.55 | 0.010 | 55 | 0.010 | | | | |
| Oxygen/Argon | 21 | 0.50 | 6.4 | 0.50 | | | | |
| Nitrogen | 78 | 1.0 | 24 | 1.0 | | | | |
| Methane | 0.034 | 0.0010 | 3.1 | 0.0010 | | | | |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-12-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**QC Batch No:** 260504GC8A1
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946
## LABORATORY CONTROL SAMPLE SUMMARY

| Lab No.: | METHOD BLANK | | | LCS | | LCSD | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Date Analyzed: | 5/4/26 11:08 | | | 5/4/26 11:23 | | 5/4/26 11:37 | | | | | |
| Analyst Initials: | KD | | | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | | 1.0 | | 1.0 | | | Limits | | |
| ANALYTE | Result % v/v | RL % v/v | SPIKE AMT. % v/v | Result % v/v | % Rec. | Result % v/v | % Rec. | RPD % | Low %Rec | High %Rec | Max. RPD |
| Carbon Dioxide | ND | 0.010 | 10 | 8.82 | 88 | 8.80 | 88 | 0.2 | 70 | 130 | 30 |
| Oxygen/Argon | ND | 0.50 | 15 | 15.3 | 102 | 15.2 | 101 | 0.5 | 70 | 130 | 30 |
| Nitrogen | ND | 1.0 | 70 | 72.2 | 104 | 71.9 | 103 | 0.4 | 70 | 130 | 30 |
| Methane | ND | 0.0010 | 0.10 | 0.0996 | 99 | 0.0989 | 98 | 0.7 | 70 | 130 | 30 |
| | | | | | | | | | | | |

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-12-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

SGS

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175
TX Cert T104704450-14-6
EPA Methods TO14A, TO15
ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

May 29, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

## LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T050503-01/10

Enclosed are the results for sample(s) received 5/5/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

# CHAIN OF CUSTODY RECORD

| TURNAROUND TIME | | | | DELIVERABLES | | PAGE: 1 OF |
|---|---|---|---|---|---|---|
| Standard | ■ | 48 hours | ☐ | EDD | ■ | Condition upon receipt: |
| Same Day | ☐ | 72 hours | ☐ | EDF | ☐ | Sealed Yes ☐ No ☐ |
| 24 hours | ☐ | 96 hours | ☐ | Level 3 | ☐ | Intact Yes ☐ No ☐ |
| Other: | | | | Level 4 | ☐ | Chilled _____ deg C |

| | |
|---|---|
| **Project No.:** | 07224200.24 Task 1 |
| **Project Name:** | Chiquita Canyon Landfill |
| **Report To:** | Cornelius Fong |
| **Company:** | SCS Engineers |
| **Street:** | 3900 Kilroy Airport Way, Suite 300 |
| **City/State/Zip:** | Long Beach, CA 90806-6816 |
| **Phone& Fax:** | 562-743-7895 |
| **e-mail:** | cfong@scsengineers.com |

**BILLING**

**P.O. No.:**

**Bill to:** 07FSAccountspayable@scsengineers.com
3900 Kilroy Airport Way, Suite 300
Long Beach, CA 90806-6816

**ANALYSIS REQUEST**

| LAB USE ONLY | SAMPLE IDENTIFICATION | SAMPLE DATE | SAMPLE TIME | CONTAINER QTY/TYPE | MATRIX | PRESERVATION | CH4, CO2, O2, N2 ASTM D1946 | Carbon Monoxide EPA ALT-144 | Hydrogen ASTM D1946 | VOCs EPA TO-15 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| T050503-01 | CV-24141 | 05/05/26 | 7:45AM | 1L | Gas | N | X | X | X | | | |
| -02 | CV-2351 | 05/05/26 | 7:50AM | 2-1L | Gas | N | X | X | X | X | | |
| -03 | CV-24143 | 05/05/26 | 7:55AM | 2-1L | Gas | N | X | X | X | X | | |
| -04 | CV-2352 | 05/05/26 | 8:00AM | 1L | Gas | N | X | X | X | | | |
| -05 | CV-24140 | 05/05/26 | 8:05AM | 2-1L | Gas | N | X | X | X | X | | |
| -06 | CV-24139 | 05/05/26 | 8:10AM | 2-1L | Gas | N | X | X | X | X | | |
| -07 | CV-24138 | 05/05/26 | 8:15AM | 2-1L | Gas | N | X | X | X | X | | |
| -08 | CV-2354 | 05/05/26 | 8:20AM | 1L | Gas | N | X | X | X | | | |
| -09 | CV-2349 | 05/05/26 | 8:25AM | 1L | Gas | N | X | X | X | | | |
| -10 | CV-24144 | 05/05/26 | 8:30AM | 1L | Gas | N | X | | | | | |

| | | | |
|---|---|---|---|
| AUTHORIZATION TO PERFORM WORK | COMPANY | | DATE/TIME |
| SAMPLED BY Fabian Chavez | COMPANY scs | | DATE/TIME |
| RELINQUISHED BY Fabian chavez | DATE/TIME 5-5-26 8:55 am | RECEIVED BY AMEC Highway | DATE/TIME 5-5-26 8:55AM |
| RELINQUISHED BY AMEC Highway | DATE/TIME 5-5-26 9:10 | RECEIVED BY Fabian Chavez | DATE/TIME 5/5/26 9:10 |
| RELINQUISHED BY Fabian Chavez | DATE/TIME 5/5/26 11:28 | RECEIVED BY [signature] | DATE/TIME 5/5/26 11:28 |

**METHOD OF TRANSPORT (circle one):** Walk-In FedEx UPS **Courier** ATLI Other_____

**COMMENTS**
Report full list of TO-15 compounds
Raw landfill gas samples
**FLAMMABLE**

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/05/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | T050503-02 | | T050503-03 | | T050503-05 | | T050503-06 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2351 | | CV-24143 | | CV-24140 | | CV-24139 | |
| Date/Time Sampled: | 5/5/26 7:50 | | 5/5/26 7:55 | | 5/5/26 8:05 | | 5/5/26 8:10 | |
| Date/Time Analyzed: | 5/5/26 18:35 | | 5/5/26 19:14 | | 5/5/26 19:53 | | 5/6/26 6:47 | |
| QC Batch No.: | 260505MS2A1 | | 260505MS2A1 | | 260505MS2A1 | | 260505MS2A1 | |
| Analyst Initials: | AS/GD | | AS/GD | | AS/GD | | AS/GD | |
| Dilution Factor: | 800 | | 6,000 | | 8,000 | | 7,000 | |
| ANALYTE | Result ppbv | RL ppbv | Result ppbv | RL ppbv | Result ppbv | RL ppbv | Result ppbv | RL ppbv |
| Dichlorodifluoromethane (12) | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Chloromethane | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,2-Cl-1,1,2,2-F ethane (114) | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Vinyl Chloride | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Bromomethane | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Chloroethane | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Trichlorofluoromethane (11) | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,1-Dichloroethene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Carbon Disulfide | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,1,2-Cl 1,2,2-F ethane (113) | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Acetone | 53,000 | 800 | 480,000 | 6,000 | 650,000 | 8,000 | 490,000 | 7,000 |
| Methylene Chloride | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| t-1,2-Dichloroethene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,1-Dichloroethane | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Vinyl Acetate | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| c-1,2-Dichloroethene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 2-Butanone | 44,000 | 1,600 | 400,000 | 12,000 | 640,000 | 16,000 | 450,000 | 14,000 |
| t-Butyl Methyl Ether (MTBE) | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Chloroform | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,1,1-Trichloroethane | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Carbon Tetrachloride | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Benzene | 5,700 | 800 | 66,000 | 6,000 | 190,000 | 8,000 | 110,000 | 7,000 |
| 1,2-Dichloroethane | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Trichloroethene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,2-Dichloropropane | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Bromodichloromethane | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| c-1,3-Dichloropropene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 4-Methyl-2-Pentanone | 830 | 800 | ND | 6,000 | 8,800 | 8,000 | ND | 7,000 |
| Toluene | ND | 800 | ND | 6,000 | 11,000 | 8,000 | 7,200 | 7,000 |
| t-1,3-Dichloropropene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,1,2-Trichloroethane | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Tetrachloroethene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 2-Hexanone | 2,100 | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Dibromochloromethane | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/05/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | T050503-02 | | T050503-03 | | T050503-05 | | T050503-06 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2351 | | CV-24143 | | CV-24140 | | CV-24139 | |
| Date/Time Sampled: | 5/5/26 7:50 | | 5/5/26 7:55 | | 5/5/26 8:05 | | 5/5/26 8:10 | |
| Date/Time Analyzed: | 5/5/26 18:35 | | 5/5/26 19:14 | | 5/5/26 19:53 | | 5/6/26 6:47 | |
| QC Batch No.: | 260505MS2A1 | | 260505MS2A1 | | 260505MS2A1 | | 260505MS2A1 | |
| Analyst Initials: | AS/GD | | AS/GD | | AS/GD | | AS/GD | |
| Dilution Factor: | 800 | | 6,000 | | 8,000 | | 7,000 | |
| ANALYTE | Result ppbv | RL ppbv | Result ppbv | RL ppbv | Result ppbv | RL ppbv | Result ppbv | RL ppbv |
| 1,2-Dibromoethane | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Chlorobenzene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Ethylbenzene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| p,&m-Xylene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| o-Xylene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Styrene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Bromoform | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,1,2,2-Tetrachloroethane | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Benzyl Chloride | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 4-Ethyl Toluene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,3,5-Trimethylbenzene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,2,4-Trimethylbenzene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,3-Dichlorobenzene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,4-Dichlorobenzene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,2-Dichlorobenzene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,2,4-Trichlorobenzene | ND | 5,600 | ND | 42,000 | ND | 56,000 | ND | 49,000 |
| Hexachlorobutadiene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,3-Butadiene | ND | 4,000 | ND | 30,000 | ND | 40,000 | ND | 35,000 |
| Isopropanol | 37,000 | 4,000 | 61,000 | 30,000 | 110,000 | 40,000 | 100,000 | 35,000 |
| n-Hexane | ND | 4,000 | ND | 30,000 | ND | 40,000 | ND | 35,000 |
| Ethyl Acetate | ND | 4,000 | ND | 30,000 | ND | 40,000 | ND | 35,000 |
| Tetrahydrofuran | 32,000 | 4,000 | 350,000 | 30,000 | 590,000 | 40,000 | 320,000 | 35,000 |
| Cyclohexane | ND | 4,000 | ND | 30,000 | ND | 40,000 | ND | 35,000 |
| Heptane | ND | 4,000 | ND | 30,000 | ND | 40,000 | ND | 35,000 |
| 1,4-Dioxane | ND | 4,000 | ND | 30,000 | ND | 40,000 | ND | 35,000 |
| | | | | | | | | |

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 5/29/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/05/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | T050503-02 | | T050503-03 | | T050503-05 | | T050503-06 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2351 | | CV-24143 | | CV-24140 | | CV-24139 | |
| Date/Time Sampled: | 5/5/26 7:50 | | 5/5/26 7:55 | | 5/5/26 8:05 | | 5/5/26 8:10 | |
| Date/Time Analyzed: | 5/5/26 18:35 | | 5/5/26 19:14 | | 5/5/26 19:53 | | 5/6/26 6:47 | |
| QC Batch No.: | 260505MS2A1 | | 260505MS2A1 | | 260505MS2A1 | | 260505MS2A1 | |
| Analyst Initials: | AS/GD | | AS/GD | | AS/GD | | AS/GD | |
| Dilution Factor: | 800 | | 6,000 | | 8,000 | | 7,000 | |
| ANALYTE | Result ppbv | RL ppbv | Result ppbv | RL ppbv | Result ppbv | RL ppbv | Result ppbv | RL ppbv |
| Dichlorodifluoromethane (12) | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Chloromethane | ND Q | 800 | ND Q | 6,000 | ND Q | 8,000 | ND Q | 7,000 |
| 1,2-Cl-1,1,2,2-F ethane (114) | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Vinyl Chloride | ND Q | 800 | ND Q | 6,000 | ND Q | 8,000 | ND Q | 7,000 |
| Bromomethane | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Chloroethane | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Trichlorofluoromethane (11) | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,1-Dichloroethene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Carbon Disulfide | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,1,2-Cl 1,2,2-F ethane (113) | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Acetone | 53,000 Q | 800 | 480,000 Q | 6,000 | 650,000 Q | 8,000 | 490,000 Q | 7,000 |
| Methylene Chloride | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| t-1,2-Dichloroethene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,1-Dichloroethane | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Vinyl Acetate | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| c-1,2-Dichloroethene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 2-Butanone | 44,000 | 1,600 | 400,000 | 12,000 | 640,000 | 16,000 | 450,000 | 14,000 |
| t-Butyl Methyl Ether (MTBE) | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Chloroform | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,1,1-Trichloroethane | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Carbon Tetrachloride | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Benzene | 5,700 | 800 | 66,000 | 6,000 | 190,000 | 8,000 | 110,000 | 7,000 |
| 1,2-Dichloroethane | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Trichloroethene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,2-Dichloropropane | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Bromodichloromethane | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| c-1,3-Dichloropropene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 4-Methyl-2-Pentanone | 830 | 800 | ND | 6,000 | 8,800 | 8,000 | ND | 7,000 |
| Toluene | ND | 800 | ND | 6,000 | 11,000 | 8,000 | 7,200 | 7,000 |
| t-1,3-Dichloropropene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,1,2-Trichloroethane | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Tetrachloroethene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 2-Hexanone | 2,100 | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Dibromochloromethane | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/05/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | T050503-02 | | T050503-03 | | T050503-05 | | T050503-06 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2351 | | CV-24143 | | CV-24140 | | CV-24139 | |
| Date/Time Sampled: | 5/5/26 7:50 | | 5/5/26 7:55 | | 5/5/26 8:05 | | 5/5/26 8:10 | |
| Date/Time Analyzed: | 5/5/26 18:35 | | 5/5/26 19:14 | | 5/5/26 19:53 | | 5/6/26 6:47 | |
| QC Batch No.: | 260505MS2A1 | | 260505MS2A1 | | 260505MS2A1 | | 260505MS2A1 | |
| Analyst Initials: | AS/GD | | AS/GD | | AS/GD | | AS/GD | |
| Dilution Factor: | 800 | | 6,000 | | 8,000 | | 7,000 | |
| ANALYTE | Result ppbv | RL ppbv | Result ppbv | RL ppbv | Result ppbv | RL ppbv | Result ppbv | RL ppbv |
| 1,2-Dibromoethane | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Chlorobenzene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Ethylbenzene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| p,&m-Xylene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| o-Xylene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Styrene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Bromoform | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,1,2,2-Tetrachloroethane | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| Benzyl Chloride | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 4-Ethyl Toluene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,3,5-Trimethylbenzene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,2,4-Trimethylbenzene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,3-Dichlorobenzene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,4-Dichlorobenzene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,2-Dichlorobenzene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,2,4-Trichlorobenzene | ND | 5,600 | ND | 42,000 | ND | 56,000 | ND | 49,000 |
| Hexachlorobutadiene | ND | 800 | ND | 6,000 | ND | 8,000 | ND | 7,000 |
| 1,3-Butadiene | ND Q | 4,000 | ND Q | 30,000 | ND Q | 40,000 | ND Q | 35,000 |
| Isopropanol | 37,000 | 4,000 | 61,000 | 30,000 | 110,000 | 40,000 | 100,000 | 35,000 |
| n-Hexane | ND | 4,000 | ND | 30,000 | ND | 40,000 | ND | 35,000 |
| Ethyl Acetate | ND | 4,000 | ND | 30,000 | ND | 40,000 | ND | 35,000 |
| Tetrahydrofuran | 32,000 | 4,000 | 350,000 | 30,000 | 590,000 | 40,000 | 320,000 | 35,000 |
| Cyclohexane | ND | 4,000 | ND | 30,000 | ND | 40,000 | ND | 35,000 |
| Heptane | ND | 4,000 | ND | 30,000 | ND | 40,000 | ND | 35,000 |
| 1,4-Dioxane | ND | 4,000 | ND | 30,000 | ND | 40,000 | ND | 35,000 |
| | | | | | | | | |

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited low recovery in the continuing calibration verification indicating possible low bias

Reviewed/Approved By: _____ Date 5/29/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/05/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | T050503-07 |
|---|---|
| Client Sample I.D.: | CV-24138 |
| Date/Time Sampled: | 5/5/26 8:15 |
| Date/Time Analyzed: | 5/6/26 7:25 |
| QC Batch No.: | 260505MS2A1 |
| Analyst Initials: | AS/GD |
| Dilution Factor: | 6,000 |

| ANALYTE | Result ppbv | RL ppbv |
|---|---|---|
| Dichlorodifluoromethane (12) | ND | 6,000 |
| Chloromethane | ND Q | 6,000 |
| 1,2-Cl-1,1,2,2-F ethane (114) | ND | 6,000 |
| Vinyl Chloride | ND Q | 6,000 |
| Bromomethane | ND | 6,000 |
| Chloroethane | ND | 6,000 |
| Trichlorofluoromethane (11) | ND | 6,000 |
| 1,1-Dichloroethene | ND | 6,000 |
| Carbon Disulfide | ND | 6,000 |
| 1,1,2-Cl 1,2,2-F ethane (113) | ND | 6,000 |
| Acetone | 430,000 Q | 6,000 |
| Methylene Chloride | ND | 6,000 |
| t-1,2-Dichloroethene | ND | 6,000 |
| 1,1-Dichloroethane | ND | 6,000 |
| Vinyl Acetate | ND | 6,000 |
| c-1,2-Dichloroethene | ND | 6,000 |
| 2-Butanone | 480,000 | 12,000 |
| t-Butyl Methyl Ether (MTBE) | ND | 6,000 |
| Chloroform | ND | 6,000 |
| 1,1,1-Trichloroethane | ND | 6,000 |
| Carbon Tetrachloride | ND | 6,000 |
| Benzene | 150,000 | 6,000 |
| 1,2-Dichloroethane | ND | 6,000 |
| Trichloroethene | ND | 6,000 |
| 1,2-Dichloropropane | ND | 6,000 |
| Bromodichloromethane | ND | 6,000 |
| c-1,3-Dichloropropene | ND | 6,000 |
| 4-Methyl-2-Pentanone | 6,600 | 6,000 |
| Toluene | 11,000 | 6,000 |
| t-1,3-Dichloropropene | ND | 6,000 |
| 1,1,2-Trichloroethane | ND | 6,000 |
| Tetrachloroethene | ND | 6,000 |
| 2-Hexanone | ND | 6,000 |
| Dibromochloromethane | ND | 6,000 |

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/05/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | T050503-07 |
|---|---|
| Client Sample I.D.: | CV-24138 |
| Date/Time Sampled: | 5/5/26 8:15 |
| Date/Time Analyzed: | 5/6/26 7:25 |
| QC Batch No.: | 260505MS2A1 |
| Analyst Initials: | AS/GD |
| Dilution Factor: | 6,000 |

| ANALYTE | Result ppbv | RL ppbv |
|---|---|---|
| 1,2-Dibromoethane | ND | 6,000 |
| Chlorobenzene | ND | 6,000 |
| Ethylbenzene | ND | 6,000 |
| p,&m-Xylene | ND | 6,000 |
| o-Xylene | ND | 6,000 |
| Styrene | ND | 6,000 |
| Bromoform | ND | 6,000 |
| 1,1,2,2-Tetrachloroethane | ND | 6,000 |
| Benzyl Chloride | ND | 6,000 |
| 4-Ethyl Toluene | ND | 6,000 |
| 1,3,5-Trimethylbenzene | ND | 6,000 |
| 1,2,4-Trimethylbenzene | ND | 6,000 |
| 1,3-Dichlorobenzene | ND | 6,000 |
| 1,4-Dichlorobenzene | ND | 6,000 |
| 1,2-Dichlorobenzene | ND | 6,000 |
| 1,2,4-Trichlorobenzene | ND | 42,000 |
| Hexachlorobutadiene | ND | 6,000 |
| 1,3-Butadiene | ND Q | 30,000 |
| Isopropanol | 86,000 | 30,000 |
| n-Hexane | ND | 30,000 |
| Ethyl Acetate | 40,000 | 30,000 |
| Tetrahydrofuran | 420,000 | 30,000 |
| Cyclohexane | ND | 30,000 |
| Heptane | ND | 30,000 |
| 1,4-Dioxane | ND | 30,000 |

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited low recovery in the continuing calibration verification indicating possible low bias

**Reviewed/Approved By:** Mark Johnson
Operations Manager

**Date** 5/9/26

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/05/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | METHOD BLANK |
|---|---|
| Client Sample I.D.: | -- |
| Date/Time Sampled: | -- |
| Date/Time Analyzed: | 5/5/26 17:17 |
| QC Batch No.: | 260505MS2A1 |
| Analyst Initials: | AS/GD |
| Dilution Factor: | 0.20 |

| ANALYTE | Result ppbv | | RL ppbv |
|---|---|---|---|
| Dichlorodifluoromethane (12) | ND | | 0.20 |
| Chloromethane | ND | Q | 0.20 |
| 1,2-Cl-1,1,2,2-F ethane (114) | ND | | 0.20 |
| Vinyl Chloride | ND | Q | 0.20 |
| Bromomethane | ND | | 0.20 |
| Chloroethane | ND | | 0.20 |
| Trichlorofluoromethane (11) | ND | | 0.20 |
| 1,1-Dichloroethene | ND | | 0.20 |
| Carbon Disulfide | ND | | 0.20 |
| 1,1,2-Cl 1,2,2-F ethane (113) | ND | | 0.20 |
| Acetone | ND | Q | 0.20 |
| Methylene Chloride | ND | | 0.20 |
| t-1,2-Dichloroethene | ND | | 0.20 |
| 1,1-Dichloroethane | ND | | 0.20 |
| Vinyl Acetate | ND | | 0.20 |
| c-1,2-Dichloroethene | ND | | 0.20 |
| 2-Butanone | ND | | 0.40 |
| t-Butyl Methyl Ether (MTBE) | ND | | 0.20 |
| Chloroform | ND | | 0.20 |
| 1,1,1-Trichloroethane | ND | | 0.20 |
| Carbon Tetrachloride | ND | | 0.20 |
| Benzene | ND | | 0.20 |
| 1,2-Dichloroethane | ND | | 0.20 |
| Trichloroethene | ND | | 0.20 |
| 1,2-Dichloropropane | ND | | 0.20 |
| Bromodichloromethane | ND | | 0.20 |
| c-1,3-Dichloropropene | ND | | 0.20 |
| 4-Methyl-2-Pentanone | ND | | 0.20 |
| Toluene | ND | | 0.20 |
| t-1,3-Dichloropropene | ND | | 0.20 |
| 1,1,2-Trichloroethane | ND | | 0.20 |
| Tetrachloroethene | ND | | 0.20 |
| 2-Hexanone | ND | | 0.20 |
| Dibromochloromethane | ND | | 0.20 |

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/05/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | METHOD BLANK |
|---|---|
| Client Sample I.D.: | -- |
| Date/Time Sampled: | -- |
| Date/Time Analyzed: | 5/5/26 17:17 |
| QC Batch No.: | 260505MS2A1 |
| Analyst Initials: | AS/GD |
| Dilution Factor: | 0.20 |

| ANALYTE | Result ppbv | RL ppbv |
|---|---|---|
| 1,2-Dibromoethane | ND | 0.20 |
| Chlorobenzene | ND | 0.20 |
| Ethylbenzene | ND | 0.20 |
| p,&m-Xylene | ND | 0.20 |
| o-Xylene | ND | 0.20 |
| Styrene | ND | 0.20 |
| Bromoform | ND | 0.20 |
| 1,1,2,2-Tetrachloroethane | ND | 0.20 |
| Benzyl Chloride | ND | 0.20 |
| 4-Ethyl Toluene | ND | 0.20 |
| 1,3,5-Trimethylbenzene | ND | 0.20 |
| 1,2,4-Trimethylbenzene | ND | 0.20 |
| 1,3-Dichlorobenzene | ND | 0.20 |
| 1,4-Dichlorobenzene | ND | 0.20 |
| 1,2-Dichlorobenzene | ND | 0.20 |
| 1,2,4-Trichlorobenzene | ND | 1.4 |
| Hexachlorobutadiene | ND | 0.20 |
| 1,3-Butadiene | ND Q | 1.0 |
| Isopropanol | ND | 1.0 |
| n-Hexane | ND | 1.0 |
| Ethyl Acetate | ND | 1.0 |
| Tetrahydrofuran | ND | 1.0 |
| Cyclohexane | ND | 1.0 |
| Heptane | ND | 1.0 |
| 1,4-Dioxane | ND | 1.0 |

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited low recovery in the continuing calibration verification indicating possible low bias

Reviewed/Approved By: _____ Date 5/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

# LCS/LCSD Recovery and RPD Summary Report

## QC Batch #: 260505MS2A1

**Matrix: Air**

**Reporting Units: ppbv**

**EPA Method TO-15**
**LABORATORY CONTROL SAMPLE SUMMARY**

| Lab No.: | METHOD BLANK | | | LCS | | LCSD | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Date/Time Analyzed: | 5/5/26 17:17 | | | 5/5/26 15:59 | | 5/5/26 16:38 | | | | | |
| Analyst Initials: | AS/GD | | | AS/GD | | AS/GD | | | | | |
| Dilution Factor: | 0.20 | | | 1.0 | | 1.0 | | | | | |
| **ANALYTE** | **Result ppbv** | **RL ppbv** | **AMT. ppbv** | **Result ppbv** | **% Rec.** | **Result ppbv** | **% Rec.** | **RPD** | **Low %Rec** | **High %Rec** | **Max. RPD** |
| 1,1-Dichloroethene | ND | 0.20 | 10 | 9.98 | 100 | 9.38 | 94 | 6.2 | 70 | 130 | 30 |
| Methylene Chloride | ND | 0.20 | 10 | 9.53 | 95 | 9.00 | 90 | 5.6 | 70 | 130 | 30 |
| Trichloroethene | ND | 0.20 | 10 | 10.1 | 101 | 10.3 | 103 | 1.7 | 70 | 130 | 30 |
| Toluene | ND | 0.20 | 10 | 9.83 | 98 | 10.2 | 102 | 3.8 | 70 | 130 | 30 |
| 1,1,2,2-Tetrachloroethane | ND | 0.20 | 10 | 8.92 | 89 | 9.37 | 94 | 4.9 | 70 | 130 | 30 |
| | | | | | | | | | | | |

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date: 5/29/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/05/26
**Matrix:** Air
**Reporting Units:** ppmv

## EPA ALT-144 (CO by FID)

| Lab No.: | T050503-01 | | T050503-02 | | T050503-03 | | T050503-04 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-24141 | | CV-2351 | | CV-24143 | | CV-2352 | |
| Date/Time Sampled: | 5/5/26 7:45 | | 5/5/26 7:50 | | 5/5/26 7:55 | | 5/5/26 8:00 | |
| Date/Time Analyzed: | 5/5/26 16:56 | | 5/5/26 17:10 | | 5/5/26 17:25 | | 5/5/26 17:39 | |
| QC Batch No.: | 260505GC8A1 | | 260505GC8A1 | | 260505GC8A1 | | 260505GC8A1 | |
| Analyst Initials: | KD | | KD | | KD | | KD | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | 1.0 | |
| ANALYTE | Result ppmv | RL ppmv | Result ppmv | RL ppmv | Result ppmv | RL ppmv | Result ppmv | RL ppmv |
| Carbon Monoxide | 94 | 10 | ND | 10 | 460 | 10 | 1,100 | 10 |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-14-26
**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report



SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com
Member of the SGS Group (SGS SA)

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/05/26
**Matrix:** Air
**Reporting Units:** ppmv

## EPA ALT-144 (CO by FID)

| Lab No.: | T050503-05 | | T050503-06 | | T050503-07 | | T050503-08 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-24140 | | CV-24139 | | CV-24138 | | CV-2354 | |
| Date/Time Sampled: | 5/5/26 8:05 | | 5/5/26 8:10 | | 5/5/26 8:15 | | 5/5/26 8:20 | |
| Date/Time Analyzed: | 5/5/26 17:54 | | 5/5/26 18:08 | | 5/5/26 18:23 | | 5/5/26 18:37 | |
| QC Batch No.: | 260505GC8A1 | | 260505GC8A1 | | 260505GC8A1 | | 260505GC8A1 | |
| Analyst Initials: | KD | | KD | | KD | | KD | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | 1.0 | |
| ANALYTE | Result ppmv | RL ppmv | Result ppmv | RL ppmv | Result ppmv | RL ppmv | Result ppmv | RL ppmv |
| Carbon Monoxide | 1,000 | 10 | 630 | 10 | 820 | 10 | 2,500 | 10 |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-14-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/05/26
**Matrix:** Air
**Reporting Units:** ppmv

## EPA ALT-144 (CO by FID)

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| **Lab No.:** | **T050503-09** | | | | | | | |
| **Client Sample I.D.:** | **CV-2349** | | | | | | | |
| **Date/Time Sampled:** | **5/5/26 8:25** | | | | | | | |
| **Date/Time Analyzed:** | **5/5/26 18:52** | | | | | | | |
| **QC Batch No.:** | **260505GC8A1** | | | | | | | |
| **Analyst Initials:** | **KD** | | | | | | | |
| **Dilution Factor:** | **1.0** | | | | | | | |
| **ANALYTE** | **Result ppmv** | **RL ppmv** | | | | | | |
| Carbon Monoxide | 2,600 | 10 | | | | | | |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-14-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**QC Batch No:** 260505GC8A1
**Matrix:** Air
**Reporting Units:** ppmv

## EPA ALT-144 (CO by FID)
## LABORATORY CONTROL SAMPLE SUMMARY

| Lab No.: | METHOD BLANK | | | LCS | | LCSD | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Date Analyzed: | 5/5/26 9:55 | | | 5/5/26 11:22 | | 5/5/26 11:36 | | | | | |
| Analyst Initials: | KD | | | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | | 1.0 | | 1.0 | | | Limits | | |
| ANALYTE | Result ppmv | RL ppmv | SPIKE AMT. ppmv | Result ppmv | % Rec. | Result ppmv | % Rec. | RPD % | Low %Rec | High %Rec | Max. RPD |
| Carbon Monoxide | ND | 10 | 1,010 | 1,100 | 108 | 1,090 | 108 | 0.3 | 70 | 130 | 30 |
| | | | | | | | | | | | |

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-14-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/05/26
**Matrix:** Air
**Reporting Units:** % v/v

**ASTM D1946**

| Lab No.: | T050503-01 | | | T050503-02 | | | T050503-03 | | | T050503-04 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-24141 | | | CV-2351 | | | CV-24143 | | | CV-2352 | | |
| Date/Time Sampled: | 5/5/26 7:45 | | | 5/5/26 7:50 | | | 5/5/26 7:55 | | | 5/5/26 8:00 | | |
| Date/Time Analyzed: | 5/5/26 16:56 | | | 5/5/26 17:10 | | | 5/5/26 17:25 | | | 5/5/26 17:39 | | |
| QC Batch No.: | 260505GC8A1 | | | 260505GC8A1 | | | 260505GC8A1 | | | 260505GC8A1 | | |
| Analyst Initials: | KD | | | KD | | | KD | | | KD | | |
| Dilution Factor: | 1.0 | | | 1.0 | | | 1.0 | | | 1.0 | | |
| ANALYTE | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v |
| Hydrogen | 0.12 J | 1.0 | 0.059 | 0.16 J | 1.0 | 0.059 | 6.1 | 1.0 | 0.059 | 19 | 1.0 | 0.059 |
| | | | | | | | | | | | | |

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-14-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/05/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T050503-05 | | | T050503-06 | | | T050503-07 | | | T050503-08 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-24140 | | | CV-24139 | | | CV-24138 | | | CV-2354 | | |
| Date/Time Sampled: | 5/5/26 8:05 | | | 5/5/26 8:10 | | | 5/5/26 8:15 | | | 5/5/26 8:20 | | |
| Date/Time Analyzed: | 5/5/26 17:54 | | | 5/5/26 18:08 | | | 5/5/26 18:23 | | | 5/5/26 18:37 | | |
| QC Batch No.: | 260505GC8A1 | | | 260505GC8A1 | | | 260505GC8A1 | | | 260505GC8A1 | | |
| Analyst Initials: | KD | | | KD | | | KD | | | KD | | |
| Dilution Factor: | 1.0 | | | 1.0 | | | 1.0 | | | 1.0 | | |
| ANALYTE | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v |
| Hydrogen | 21 | 1.0 | 0.059 | 18 | 1.0 | 0.059 | 21 | 1.0 | 0.059 | 17 | 1.0 | 0.059 |
| | | | | | | | | | | | | |

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-14-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/05/26
**Matrix:** Air
**Reporting Units:** % v/v

**ASTM D1946**

| Lab No.: | T050503-09 | | |
|---|---|---|---|
| Client Sample I.D.: | CV-2349 | | |
| Date/Time Sampled: | 5/5/26 8:25 | | |
| Date/Time Analyzed: | 5/5/26 18:52 | | |
| QC Batch No.: | 260505GC8A1 | | |
| Analyst Initials: | KD | | |
| Dilution Factor: | 1.0 | | |

| ANALYTE | Result % v/v | RL % v/v | MDL % v/v |
|---|---|---|---|
| Hydrogen | 15 | 1.0 | 0.059 |
| | | | |

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-14-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**QC Batch No:** 260505GC8A1
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946
## LABORATORY CONTROL SAMPLE SUMMARY

| Lab No.: | METHOD BLANK | | | | LCS | | LCSD | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Date Analyzed: | 5/5/26 9:55 | | | | 5/5/26 11:22 | | 5/5/26 11:36 | | | | | |
| Analyst Initials: | KD | | | | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | | | 1.0 | | 1.0 | | | Limits | | |
| ANALYTE | Result % v/v | RL % v/v | MDL % v/v | SPIKE AMT. % v/v | Result % v/v | % Rec. | Result % v/v | % Rec. | RPD % | Low %Rec | High %Rec | Max. RPD |
| Hydrogen | ND | 1.0 | 0.059 | 5.0 | 5.59 | 112 | 5.59 | 112 | 0.1 | 70 | 130 | 30 |

**MDL = Method Detection Limit**
**ND= Not Detected (below MDL)**
**RL = Reporting Limit**
**J = Trace amount. Analyte concentration between RL and MDL.**

**Reviewed/Approved By:** _____ **Date** 5-14-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/05/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T050503-01 | | T050503-02 | | T050503-03 | | T050503-04 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-24141 | | CV-2351 | | CV-24143 | | CV-2352 | |
| Date/Time Sampled: | 5/5/26 7:45 | | 5/5/26 7:50 | | 5/5/26 7:55 | | 5/5/26 8:00 | |
| Date/Time Analyzed: | 5/5/26 16:56 | | 5/5/26 17:10 | | 5/5/26 17:25 | | 5/5/26 17:39 | |
| QC Batch No.: | 260505GC8A1 | | 260505GC8A1 | | 260505GC8A1 | | 260505GC8A1 | |
| Analyst Initials: | KD | | KD | | KD | | KD | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | 1.0 | |
| ANALYTE | Result % v/v | RL % v/v | Result % v/v | RL % v/v | Result % v/v | RL % v/v | Result % v/v | RL % v/v |
| Carbon Dioxide | 34 | 0.010 | 1.7 | 0.010 | 24 | 0.010 | 66 | 0.010 |
| Oxygen/Argon | 5.0 | 0.50 | 20 | 0.50 | 15 | 0.50 | 2.5 | 0.50 |
| Nitrogen | 39 | 1.0 | 77 | 1.0 | 55 | 1.0 | 9.3 | 1.0 |
| Methane | 22 | 0.0010 | 0.87 | 0.0010 | 0.58 | 0.0010 | 1.8 | 0.0010 |
| | | | | | | | | |

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 5-14-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/05/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T050503-05 | | T050503-06 | | T050503-07 | | T050503-08 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-24140 | | CV-24139 | | CV-24138 | | CV-2354 | |
| Date/Time Sampled: | 5/5/26 8:05 | | 5/5/26 8:10 | | 5/5/26 8:15 | | 5/5/26 8:20 | |
| Date/Time Analyzed: | 5/5/26 17:54 | | 5/5/26 18:08 | | 5/5/26 18:23 | | 5/5/26 18:37 | |
| QC Batch No.: | 260505GC8A1 | | 260505GC8A1 | | 260505GC8A1 | | 260505GC8A1 | |
| Analyst Initials: | KD | | KD | | KD | | KD | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | 1.0 | |
| ANALYTE | Result % v/v | RL % v/v | Result % v/v | RL % v/v | Result % v/v | RL % v/v | Result % v/v | RL % v/v |
| Carbon Dioxide | 65 | 0.010 | 53 | 0.010 | 57 | 0.010 | 72 | 0.010 |
| Oxygen/Argon | 2.4 | 0.50 | 4.4 | 0.50 | 3.9 | 0.50 | 0.95 | 0.50 |
| Nitrogen | 8.6 | 1.0 | 18 | 1.0 | 14 | 1.0 | 3.3 | 1.0 |
| Methane | 1.8 | 0.0010 | 4.7 | 0.0010 | 2.0 | 0.0010 | 4.7 | 0.0010 |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-14-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report



SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com
Member of the SGS Group (SGS SA)

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/05/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T050503-09 | | T050503-10 | | | | | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2349 | | CV-24144 | | | | | |
| Date/Time Sampled: | 5/5/26 8:25 | | 5/5/26 8:30 | | | | | |
| Date/Time Analyzed: | 5/5/26 18:52 | | 5/5/26 19:06 | | | | | |
| QC Batch No.: | 260505GC8A1 | | 260505GC8A1 | | | | | |
| Analyst Initials: | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | 1.0 | | | | | |
| **ANALYTE** | **Result % v/v** | **RL % v/v** | **Result % v/v** | **RL % v/v** | | | | |
| Carbon Dioxide | 78 | 0.010 | 34 | 0.010 | | | | |
| Oxygen/Argon | 0.74 | 0.50 | 2.6 | 0.50 | | | | |
| Nitrogen | 2.6 | 1.0 | 9.6 | 1.0 | | | | |
| Methane | 2.6 | 0.0010 | 53 | 0.0010 | | | | |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-14-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report



SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com
Member of the SGS Group (SGS SA)

**QC Batch No:** 260505GC8A1
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946
## LABORATORY CONTROL SAMPLE SUMMARY

| Lab No.: | METHOD BLANK | | | LCS | | LCSD | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Date Analyzed: | 5/5/26 9:55 | | | 5/5/26 11:22 | | 5/5/26 11:36 | | | | | |
| Analyst Initials: | KD | | | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | | 1.0 | | 1.0 | | | Limits | | |
| ANALYTE | Result % v/v | RL % v/v | SPIKE AMT. % v/v | Result % v/v | % Rec. | Result % v/v | % Rec. | RPD % | Low %Rec | High %Rec | Max. RPD |
| Carbon Dioxide | ND | 0.010 | 10 | 9.86 | 98 | 9.87 | 98 | 0.1 | 70 | 130 | 30 |
| Oxygen/Argon | ND | 0.50 | 15 | 14.6 | 97 | 14.6 | 97 | 0.0 | 70 | 130 | 30 |
| Nitrogen | ND | 1.0 | 70 | 70.5 | 101 | 70.6 | 101 | 0.1 | 70 | 130 | 30 |
| Methane | ND | 0.0010 | 0.10 | 0.104 | 103 | 0.104 | 103 | 0.3 | 70 | 130 | 30 |
| | | | | | | | | | | | |

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-14-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

SGS

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175

TX Cert T104704450-14-6
EPA Methods TO14A, TO15

ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

May 29, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

## LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T050603-01/10

Enclosed are the results for sample(s) received 5/6/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

# CHAIN OF CUSTODY RECORD

**TURNAROUND TIME**: Standard ■ 48 hours ☐ | Same Day ☐ 72 hours ☐ | 24 hours ☐ 96 hours ☐ | Other:

**DELIVERABLES**: EDD ■ | EDF ☐ | Level 3 ☐ | Level 4 ☐

**PAGE:** 1 OF

Condition upon receipt: Sealed Yes ☐ No ☐ | Intact Yes ☐ No ☐ | Chilled _____ deg C

| | |
|---|---|
| **Project No.:** | 07224200.24 Task 1 |
| **Project Name:** | Chiquita Canyon Landfill |
| **Report To:** | Cornelius Fong |
| **Company:** | SCS Engineers |
| **Street:** | 3900 Kilroy Airport Way, Suite 300 |
| **City/State/Zip:** | Long Beach, CA 90806-6816 |
| **Phone& Fax:** | 562-743-7895 |
| **e-mail:** | cfong@scsengineers.com |

**BILLING**

| | |
|---|---|
| **P.O. No.:** | |
| **Bill to:** | 07FSAccountspayable@scsengineers.com |
| | 3900 Kilroy Airport Way, Suite 300 |
| | Long Beach, CA 90806-6816 |

**ANALYSIS REQUEST**

| LAB USE ONLY | SAMPLE IDENTIFICATION | SAMPLE DATE | SAMPLE TIME | CONTAINER QTY/TYPE | MATRIX | PRESERVATION | CH4, CO2, O2, N2 ASTM D1946 | Carbon Monoxide EPA ALT-144 | Hydrogen ASTM D1946 | VOCs EPA TO-15 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| T050603-01 | CV-24102 | 05/06/26 | 7:30AM | 1L | Gas | N | X | | | | | |
| -02 | CV-24101 | 05/06/26 | 7:40M | 2-1L | Gas | N | X | X | X | X | | |
| -03 | CV-2001 | 05/06/26 | 7:50AM | 2-1L | Gas | N | X | X | X | X | | |
| -04 | CV-24099 | 05/06/26 | 7:55AM | 1L | Gas | N | X | | | | | |
| -05 | CV-24095 | 05/06/26 | 8:05AM | 2-1L | Gas | N | X | X | X | X | | |
| -06 | CV-24142 | 05/06/26 | 8:10AM | 2-1L | Gas | N | X | X | X | X | | |
| -07 | CV-2348 | 05/06/26 | 8:15AM | 1L | Gas | N | X | X | X | | | |
| -08 | CV-2347 | 05/06/26 | 8:20M | 1L | Gas | N | X | X | X | | | |
| -09 | CV-2346 | 05/06/26 | 8:25AM | 1L | Gas | N | X | X | X | | | |
| -10 | CV-108-52 | 05/06/26 | 8:30AM | 2-1L | Gas | N | X | X | X | X | | |

| | | | |
|---|---|---|---|
| AUTHORIZATION TO PERFORM WORK | COMPANY: Eric Navarro SCS | DATE/TIME: 5-6-26 9:10 | |
| SAMPLED BY | COMPANY: SCS | DATE/TIME: 5-6-26 9:10 | |
| RELINQUISHED BY | DATE/TIME: 5-6-26 9:10 | RECEIVED BY | DATE/TIME: 5/6/26 11:34 |
| RELINQUISHED BY | DATE/TIME: 5/6/26 12:52 | RECEIVED BY | DATE/TIME: 5/6/26 1252 |
| RELINQUISHED BY | DATE/TIME | RECEIVED BY | DATE/TIME |

**METHOD OF TRANSPORT (circle one):** Walk-In FedEx UPS **Courier** ATLI Other_____

**COMMENTS**
Report full list of TO-15 compounds
Raw landfill gas samples
**FLAMMABLE**

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: H=HCl N=None / Container: B=Bag C=Can V=VOA O=Other

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/06/26
Matrix: Air
Reporting Units: ppbv

## EPA Method TO-15

| Lab No.: | T050603-02 | | T050603-03 | | T050603-05 | | T050603-06 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-24101 | | CV-2001 | | CV-24095 | | CV-24142 | |
| Date/Time Sampled: | 5/6/26 7:40 | | 5/6/26 7:50 | | 5/6/26 8:05 | | 5/6/26 8:10 | |
| Date/Time Analyzed: | 5/6/26 17:32 | | 5/6/26 18:10 | | 5/6/26 18:48 | | 5/6/26 19:27 | |
| QC Batch No.: | 260506MS2A1 | | 260506MS2A1 | | 260506MS2A1 | | 260506MS2A1 | |
| Analyst Initials: | AS/GD | | AS/GD | | AS/GD | | AS/GD | |
| Dilution Factor: | 5,000 | | 600 | | 10,000 | | 5,000 | |
| ANALYTE | Result ppbv | RL ppbv | Result ppbv | RL ppbv | Result ppbv | RL ppbv | Result ppbv | RL ppbv |
| Dichlorodifluoromethane (12) | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| Chloromethane | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| 1,2-Cl-1,1,2,2-F ethane (114) | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| Vinyl Chloride | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| Bromomethane | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| Chloroethane | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| Trichlorofluoromethane (11) | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| 1,1-Dichloroethene | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| Carbon Disulfide | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| 1,1,2-Cl 1,2,2-F ethane (113) | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| Acetone | 46,000 | 5,000 | 41,000 | 600 | 860,000 | 10,000 | 320,000 | 5,000 |
| Methylene Chloride | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| t-1,2-Dichloroethene | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| 1,1-Dichloroethane | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| Vinyl Acetate | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| c-1,2-Dichloroethene | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| 2-Butanone | 37,000 | 10,000 | 57,000 | 1,200 | 670,000 | 20,000 | 290,000 | 10,000 |
| t-Butyl Methyl Ether (MTBE) | ND | 5,000 | 1,200 | 600 | ND | 10,000 | ND | 5,000 |
| Chloroform | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| 1,1,1-Trichloroethane | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| Carbon Tetrachloride | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| Benzene | 8,000 | 5,000 | 67,000 | 600 | 280,000 | 10,000 | 100,000 | 5,000 |
| 1,2-Dichloroethane | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| Trichloroethene | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| 1,2-Dichloropropane | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| Bromodichloromethane | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| c-1,3-Dichloropropene | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| 4-Methyl-2-Pentanone | ND | 5,000 | 2,200 | 600 | ND | 10,000 | ND | 5,000 |
| Toluene | ND | 5,000 | 3,000 | 600 | 11,000 | 10,000 | 5,600 | 5,000 |
| t-1,3-Dichloropropene | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| 1,1,2-Trichloroethane | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| Tetrachloroethene | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| 2-Hexanone | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| Dibromochloromethane | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/06/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | T050603-02 | | T050603-03 | | T050603-05 | | T050603-06 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-24101 | | CV-2001 | | CV-24095 | | CV-24142 | |
| Date/Time Sampled: | 5/6/26 7:40 | | 5/6/26 7:50 | | 5/6/26 8:05 | | 5/6/26 8:10 | |
| Date/Time Analyzed: | 5/6/26 17:32 | | 5/6/26 18:10 | | 5/6/26 18:48 | | 5/6/26 19:27 | |
| QC Batch No.: | 260506MS2A1 | | 260506MS2A1 | | 260506MS2A1 | | 260506MS2A1 | |
| Analyst Initials: | AS/GD | | AS/GD | | AS/GD | | AS/GD | |
| Dilution Factor: | 5,000 | | 600 | | 10,000 | | 5,000 | |
| ANALYTE | Result ppbv | RL ppbv | Result ppbv | RL ppbv | Result ppbv | RL ppbv | Result ppbv | RL ppbv |
| 1,2-Dibromoethane | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| Chlorobenzene | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| Ethylbenzene | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| p,&m-Xylene | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| o-Xylene | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| Styrene | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| Bromoform | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| 1,1,2,2-Tetrachloroethane | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| Benzyl Chloride | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| 4-Ethyl Toluene | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| 1,3,5-Trimethylbenzene | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| 1,2,4-Trimethylbenzene | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| 1,3-Dichlorobenzene | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| 1,4-Dichlorobenzene | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| 1,2-Dichlorobenzene | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| 1,2,4-Trichlorobenzene | ND | 35,000 | ND | 4,200 | ND | 70,000 | ND | 35,000 |
| Hexachlorobutadiene | ND | 5,000 | ND | 600 | ND | 10,000 | ND | 5,000 |
| 1,3-Butadiene | ND | 25,000 | 6,700 | 3,000 | ND | 50,000 | ND | 25,000 |
| Isopropanol | 47,000 | 25,000 | 30,000 | 3,000 | 160,000 | 50,000 | 130,000 | 25,000 |
| n-Hexane | ND | 25,000 | 3,400 | 3,000 | ND | 50,000 | ND | 25,000 |
| Ethyl Acetate | ND | 25,000 | 10,000 | 3,000 | 92,000 | 50,000 | 48,000 | 25,000 |
| Tetrahydrofuran | ND | 25,000 | 59,000 | 3,000 | 570,000 | 50,000 | 300,000 | 25,000 |
| Cyclohexane | ND | 25,000 | ND | 3,000 | ND | 50,000 | ND | 25,000 |
| Heptane | ND | 25,000 | 4,100 | 3,000 | ND | 50,000 | ND | 25,000 |
| 1,4-Dioxane | ND | 25,000 | ND | 3,000 | ND | 50,000 | ND | 25,000 |
| | | | | | | | | |

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 5/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/06/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | T050603-10 |
|---|---|
| Client Sample I.D.: | CV-108-52 |
| Date/Time Sampled: | 5/6/26 8:30 |
| Date/Time Analyzed: | 5/6/26 20:06 |
| QC Batch No.: | 260506MS2A1 |
| Analyst Initials: | AS/GD |
| Dilution Factor: | 3,600 |

| ANALYTE | Result ppbv | RL ppbv |
|---|---|---|
| Dichlorodifluoromethane (12) | ND | 3,600 |
| Chloromethane | ND | 3,600 |
| 1,2-Cl-1,1,2,2-F ethane (114) | ND | 3,600 |
| Vinyl Chloride | ND | 3,600 |
| Bromomethane | ND | 3,600 |
| Chloroethane | ND | 3,600 |
| Trichlorofluoromethane (11) | ND | 3,600 |
| 1,1-Dichloroethene | ND | 3,600 |
| Carbon Disulfide | ND | 3,600 |
| 1,1,2-Cl 1,2,2-F ethane (113) | ND | 3,600 |
| Acetone | 250,000 | 3,600 |
| Methylene Chloride | ND | 3,600 |
| t-1,2-Dichloroethene | ND | 3,600 |
| 1,1-Dichloroethane | ND | 3,600 |
| Vinyl Acetate | ND | 3,600 |
| c-1,2-Dichloroethene | ND | 3,600 |
| 2-Butanone | 230,000 | 7,200 |
| t-Butyl Methyl Ether (MTBE) | ND | 3,600 |
| Chloroform | ND | 3,600 |
| 1,1,1-Trichloroethane | ND | 3,600 |
| Carbon Tetrachloride | ND | 3,600 |
| Benzene | 41,000 | 3,600 |
| 1,2-Dichloroethane | ND | 3,600 |
| Trichloroethene | ND | 3,600 |
| 1,2-Dichloropropane | ND | 3,600 |
| Bromodichloromethane | ND | 3,600 |
| c-1,3-Dichloropropene | ND | 3,600 |
| 4-Methyl-2-Pentanone | ND | 3,600 |
| Toluene | 3,800 | 3,600 |
| t-1,3-Dichloropropene | ND | 3,600 |
| 1,1,2-Trichloroethane | ND | 3,600 |
| Tetrachloroethene | ND | 3,600 |
| 2-Hexanone | ND | 3,600 |
| Dibromochloromethane | ND | 3,600 |

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/06/26
**Matrix:** Air
**Reporting Units:** ppbv

**EPA Method TO-15**

| Lab No.: | T050603-10 |
|---|---|
| Client Sample I.D.: | CV-108-52 |
| Date/Time Sampled: | 5/6/26 8:30 |
| Date/Time Analyzed: | 5/6/26 20:06 |
| QC Batch No.: | 260506MS2A1 |
| Analyst Initials: | AS/GD |
| Dilution Factor: | 3,600 |

| ANALYTE | Result ppbv | RL ppbv |
|---|---|---|
| 1,2-Dibromoethane | ND | 3,600 |
| Chlorobenzene | ND | 3,600 |
| Ethylbenzene | ND | 3,600 |
| p,&m-Xylene | ND | 3,600 |
| o-Xylene | ND | 3,600 |
| Styrene | ND | 3,600 |
| Bromoform | ND | 3,600 |
| 1,1,2,2-Tetrachloroethane | ND | 3,600 |
| Benzyl Chloride | ND | 3,600 |
| 4-Ethyl Toluene | ND | 3,600 |
| 1,3,5-Trimethylbenzene | ND | 3,600 |
| 1,2,4-Trimethylbenzene | ND | 3,600 |
| 1,3-Dichlorobenzene | ND | 3,600 |
| 1,4-Dichlorobenzene | ND | 3,600 |
| 1,2-Dichlorobenzene | ND | 3,600 |
| 1,2,4-Trichlorobenzene | ND | 25,000 |
| Hexachlorobutadiene | ND | 3,600 |
| 1,3-Butadiene | ND | 18,000 |
| Isopropanol | 200,000 | 18,000 |
| n-Hexane | ND | 18,000 |
| Ethyl Acetate | ND | 18,000 |
| Tetrahydrofuran | 180,000 | 18,000 |
| Cyclohexane | ND | 18,000 |
| Heptane | ND | 18,000 |
| 1,4-Dioxane | ND | 18,000 |

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 5/29/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/06/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | METHOD BLANK | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | -- | | | | | | | |
| Date/Time Sampled: | -- | | | | | | | |
| Date/Time Analyzed: | 5/6/26 15:34 | | | | | | | |
| QC Batch No.: | 260506MS2A1 | | | | | | | |
| Analyst Initials: | AS/GD | | | | | | | |
| Dilution Factor: | 0.20 | | | | | | | |

| ANALYTE | Result ppbv | RL ppbv | | | | | | |
|---|---|---|---|---|---|---|---|---|
| Dichlorodifluoromethane (12) | ND | 0.20 | | | | | | |
| Chloromethane | ND | 0.20 | | | | | | |
| 1,2-Cl-1,1,2,2-F ethane (114) | ND | 0.20 | | | | | | |
| Vinyl Chloride | ND | 0.20 | | | | | | |
| Bromomethane | ND | 0.20 | | | | | | |
| Chloroethane | ND | 0.20 | | | | | | |
| Trichlorofluoromethane (11) | ND | 0.20 | | | | | | |
| 1,1-Dichloroethene | ND | 0.20 | | | | | | |
| Carbon Disulfide | ND | 0.20 | | | | | | |
| 1,1,2-Cl 1,2,2-F ethane (113) | ND | 0.20 | | | | | | |
| Acetone | ND | 0.20 | | | | | | |
| Methylene Chloride | ND | 0.20 | | | | | | |
| t-1,2-Dichloroethene | ND | 0.20 | | | | | | |
| 1,1-Dichloroethane | ND | 0.20 | | | | | | |
| Vinyl Acetate | ND | 0.20 | | | | | | |
| c-1,2-Dichloroethene | ND | 0.20 | | | | | | |
| 2-Butanone | ND | 0.40 | | | | | | |
| t-Butyl Methyl Ether (MTBE) | ND | 0.20 | | | | | | |
| Chloroform | ND | 0.20 | | | | | | |
| 1,1,1-Trichloroethane | ND | 0.20 | | | | | | |
| Carbon Tetrachloride | ND | 0.20 | | | | | | |
| Benzene | ND | 0.20 | | | | | | |
| 1,2-Dichloroethane | ND | 0.20 | | | | | | |
| Trichloroethene | ND | 0.20 | | | | | | |
| 1,2-Dichloropropane | ND | 0.20 | | | | | | |
| Bromodichloromethane | ND | 0.20 | | | | | | |
| c-1,3-Dichloropropene | ND | 0.20 | | | | | | |
| 4-Methyl-2-Pentanone | ND | 0.20 | | | | | | |
| Toluene | ND | 0.20 | | | | | | |
| t-1,3-Dichloropropene | ND | 0.20 | | | | | | |
| 1,1,2-Trichloroethane | ND | 0.20 | | | | | | |
| Tetrachloroethene | ND | 0.20 | | | | | | |
| 2-Hexanone | ND | 0.20 | | | | | | |
| Dibromochloromethane | ND | 0.20 | | | | | | |

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/06/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | METHOD BLANK |
|---|---|
| Client Sample I.D.: | -- |
| Date/Time Sampled: | -- |
| Date/Time Analyzed: | 5/6/26 15:34 |
| QC Batch No.: | 260506MS2A1 |
| Analyst Initials: | AS/GD |
| Dilution Factor: | 0.20 |

| ANALYTE | Result ppbv | RL ppbv |
|---|---|---|
| 1,2-Dibromoethane | ND | 0.20 |
| Chlorobenzene | ND | 0.20 |
| Ethylbenzene | ND | 0.20 |
| p,&m-Xylene | ND | 0.20 |
| o-Xylene | ND | 0.20 |
| Styrene | ND | 0.20 |
| Bromoform | ND | 0.20 |
| 1,1,2,2-Tetrachloroethane | ND | 0.20 |
| Benzyl Chloride | ND | 0.20 |
| 4-Ethyl Toluene | ND | 0.20 |
| 1,3,5-Trimethylbenzene | ND | 0.20 |
| 1,2,4-Trimethylbenzene | ND | 0.20 |
| 1,3-Dichlorobenzene | ND | 0.20 |
| 1,4-Dichlorobenzene | ND | 0.20 |
| 1,2-Dichlorobenzene | ND | 0.20 |
| 1,2,4-Trichlorobenzene | ND | 1.4 |
| Hexachlorobutadiene | ND | 0.20 |
| 1,3-Butadiene | ND | 1.0 |
| Isopropanol | ND | 1.0 |
| n-Hexane | ND | 1.0 |
| Ethyl Acetate | ND | 1.0 |
| Tetrahydrofuran | ND | 1.0 |
| Cyclohexane | ND | 1.0 |
| Heptane | ND | 1.0 |
| 1,4-Dioxane | ND | 1.0 |

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 5/29/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

# LCS/LCSD Recovery and RPD Summary Report

## QC Batch #: 260506MS2A1

**Matrix:** Air

**Reporting Units:** ppbv

**EPA Method TO-15**
**LABORATORY CONTROL SAMPLE SUMMARY**

| Lab No.: | METHOD BLANK | | | LCS | | LCSD | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Date/Time Analyzed: | 5/6/26 15:34 | | | 5/6/26 14:19 | | 5/6/26 14:57 | | | | | |
| Analyst Initials: | AS/GD | | | AS/GD | | AS/GD | | | | | |
| Dilution Factor: | 0.20 | | | 1.0 | | 1.0 | | | | | |
| **ANALYTE** | **Result ppbv** | **RL ppbv** | **AMT. ppbv** | **Result ppbv** | **% Rec.** | **Result ppbv** | **% Rec.** | **RPD** | **Low %Rec** | **High %Rec** | **Max. RPD** |
| 1,1-Dichloroethene | ND | 0.20 | 10 | **10.9** | 109 | **10.6** | 106 | 2.9 | **70** | **130** | 30 |
| Methylene Chloride | ND | 0.20 | 10 | **10.2** | 102 | **10.3** | 103 | 0.2 | **70** | **130** | 30 |
| Trichloroethene | ND | 0.20 | 10 | **11.3** | 113 | **11.0** | 110 | 2.6 | **70** | **130** | 30 |
| Toluene | ND | 0.20 | 10 | **10.9** | 109 | **10.9** | 109 | 0.1 | **70** | **130** | 30 |
| 1,1,2,2-Tetrachloroethane | ND | 0.20 | 10 | **9.91** | 99 | **10.2** | 102 | 2.9 | **70** | **130** | 30 |
| | | | | | | | | | | | |

ND = Not Detected (below RL)
RL = Reporting Limit

**Reviewed/Approved By:** _____ **Date:** 5/7/26
**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/06/26
**Matrix:** Air
**Reporting Units:** ppmv

## EPA ALT-144 (CO by FID)

| Lab No.: | T050603-02 | | T050603-03 | | T050603-05 | | T050603-06 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-24101 | | CV-2001 | | CV-24095 | | CV-24142 | |
| Date/Time Sampled: | 5/6/26 7:40 | | 5/6/26 7:50 | | 5/6/26 8:05 | | 5/6/26 8:10 | |
| Date/Time Analyzed: | 5/6/26 16:07 | | 5/6/26 16:21 | | 5/6/26 16:50 | | 5/6/26 17:05 | |
| QC Batch No.: | 260506GC8A2 | | 260506GC8A2 | | 260506GC8A2 | | 260506GC8A2 | |
| Analyst Initials: | KD | | KD | | KD | | KD | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | 1.0 | |
| ANALYTE | Result ppmv | RL ppmv | Result ppmv | RL ppmv | Result ppmv | RL ppmv | Result ppmv | RL ppmv |
| Carbon Monoxide | ND | 10 | 780 | 10 | 2,800 | 10 | 1,500 | 10 |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-14-26
**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/06/26
**Matrix:** Air
**Reporting Units:** ppmv

## EPA ALT-144 (CO by FID)

| Lab No.: | T050603-07 | | T050603-08 | | T050603-09 | | T050603-10 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2348 | | CV-2347 | | CV-2346 | | CV-108-52 | |
| Date/Time Sampled: | 5/6/26 8:15 | | 5/6/26 8:20 | | 5/6/26 8:25 | | 5/6/26 8:30 | |
| Date/Time Analyzed: | 5/6/26 17:19 | | 5/6/26 17:34 | | 5/6/26 17:48 | | 5/6/26 18:03 | |
| QC Batch No.: | 260506GC8A2 | | 260506GC8A2 | | 260506GC8A2 | | 260506GC8A2 | |
| Analyst Initials: | KD | | KD | | KD | | KD | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | 1.0 | |
| ANALYTE | Result ppmv | RL ppmv | Result ppmv | RL ppmv | Result ppmv | RL ppmv | Result ppmv | RL ppmv |
| Carbon Monoxide | 460 | 10 | 1,100 | 10 | 2,200 | 10 | 100 | 10 |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-14-26
**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**QC Batch No:** 260506GC8A2
**Matrix:** Air
**Reporting Units:** ppmv

## EPA ALT-144 (CO by FID)
## LABORATORY CONTROL SAMPLE SUMMARY

| Lab No.: | METHOD BLANK | | | LCS | | LCSD | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Date Analyzed: | 5/6/26 15:38 | | | 5/6/26 14:54 | | 5/6/26 15:09 | | | | | |
| Analyst Initials: | KD | | | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | | 1.0 | | 1.0 | | | Limits | | |
| ANALYTE | Result ppmv | RL ppmv | SPIKE AMT. ppmv | Result ppmv | % Rec. | Result ppmv | % Rec. | RPD % | Low %Rec | High %Rec | Max. RPD |
| Carbon Monoxide | ND | 10 | 1,010 | 1,110 | 110 | 1,100 | 109 | 0.3 | 70 | 130 | 30 |
| | | | | | | | | | | | |

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-14-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/06/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T050603-02 | | | T050603-03 | | | T050603-05 | | | T050603-06 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-24101 | | | CV-2001 | | | CV-24095 | | | CV-24142 | | |
| Date/Time Sampled: | 5/6/26 7:40 | | | 5/6/26 7:50 | | | 5/6/26 8:05 | | | 5/6/26 8:10 | | |
| Date/Time Analyzed: | 5/6/26 16:07 | | | 5/6/26 16:21 | | | 5/6/26 16:50 | | | 5/6/26 17:05 | | |
| QC Batch No.: | 260506GC8A2 | | | 260506GC8A2 | | | 260506GC8A2 | | | 260506GC8A2 | | |
| Analyst Initials: | KD | | | KD | | | KD | | | KD | | |
| Dilution Factor: | 1.0 | | | 1.0 | | | 1.0 | | | 1.0 | | |
| ANALYTE | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v |
| Hydrogen | 0.094 J | 1.0 | 0.059 | 8.2 | 1.0 | 0.059 | 16 | 1.0 | 0.059 | 12 | 1.0 | 0.059 |

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-14-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/06/26
**Matrix:** Air
**Reporting Units:** % v/v

**ASTM D1946**

| Lab No.: | T050603-07 | | | T050603-08 | | | T050603-09 | | | T050603-10 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2348 | | | CV-2347 | | | CV-2346 | | | CV-108-52 | | |
| Date/Time Sampled: | 5/6/26 8:15 | | | 5/6/26 8:20 | | | 5/6/26 8:25 | | | 5/6/26 8:30 | | |
| Date/Time Analyzed: | 5/6/26 17:19 | | | 5/6/26 17:34 | | | 5/6/26 17:48 | | | 5/6/26 18:03 | | |
| QC Batch No.: | 260506GC8A2 | | | 260506GC8A2 | | | 260506GC8A2 | | | 260506GC8A2 | | |
| Analyst Initials: | KD | | | KD | | | KD | | | KD | | |
| Dilution Factor: | 1.0 | | | 1.0 | | | 1.0 | | | 1.0 | | |
| ANALYTE | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v |
| Hydrogen | 2.7 | 1.0 | 0.059 | 5.6 | 1.0 | 0.059 | 13 | 1.0 | 0.059 | 0.66 J | 1.0 | 0.059 |

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-14-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**QC Batch No:** 260506GC8A2
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946
## LABORATORY CONTROL SAMPLE SUMMARY

| Lab No.: | METHOD BLANK | | | | LCS | | LCSD | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Date Analyzed: | 5/6/26 15:38 | | | | 5/6/26 14:54 | | 5/6/26 15:09 | | | | | |
| Analyst Initials: | KD | | | | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | | | 1.0 | | 1.0 | | | Limits | | |
| ANALYTE | Result % v/v | RL % v/v | MDL % v/v | SPIKE AMT. % v/v | Result % v/v | % Rec. | Result % v/v | % Rec. | RPD % | Low %Rec | High %Rec | Max. RPD |
| Hydrogen | ND | 1.0 | 0.059 | 5.0 | 4.86 | 98 | 4.85 | 98 | 0.2 | 70 | 130 | 30 |
| | | | | | | | | | | | | |

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-14-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/06/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T050603-01 | | T050603-02 | | T050603-03 | | T050603-04 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-24102 | | CV-24101 | | CV-2001 | | CV-24099 | |
| Date/Time Sampled: | 5/6/26 7:30 | | 5/6/26 7:40 | | 5/6/26 7:50 | | 5/6/26 7:55 | |
| Date/Time Analyzed: | 5/6/26 15:52 | | 5/6/26 16:07 | | 5/6/26 16:21 | | 5/6/26 16:36 | |
| QC Batch No.: | 260506GC8A2 | | 260506GC8A2 | | 260506GC8A2 | | 260506GC8A2 | |
| Analyst Initials: | KD | | KD | | KD | | KD | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | 1.0 | |
| **ANALYTE** | **Result % v/v** | **RL % v/v** | **Result % v/v** | **RL % v/v** | **Result % v/v** | **RL % v/v** | **Result % v/v** | **RL % v/v** |
| Carbon Dioxide | 48 | 0.010 | 54 | 0.010 | 73 | 0.010 | 86 | 0.010 |
| Oxygen/Argon | 1.5 | 0.50 | 0.69 | 0.50 | 1.3 | 0.50 | 0.55 | 0.50 |
| Nitrogen | 5.6 | 1.0 | 2.5 | 1.0 | 4.7 | 1.0 | 2.2 | 1.0 |
| Methane | 44 | 0.0010 | 43 | 0.0010 | 12 | 0.0010 | 10 | 0.0010 |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-14-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/06/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T050603-05 | | T050603-06 | | T050603-07 | | T050603-08 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-24095 | | CV-24142 | | CV-2348 | | CV-2347 | |
| Date/Time Sampled: | 5/6/26 8:05 | | 5/6/26 8:10 | | 5/6/26 8:15 | | 5/6/26 8:20 | |
| Date/Time Analyzed: | 5/6/26 16:50 | | 5/6/26 17:05 | | 5/6/26 17:19 | | 5/6/26 17:34 | |
| QC Batch No.: | 260506GC8A2 | | 260506GC8A2 | | 260506GC8A2 | | 260506GC8A2 | |
| Analyst Initials: | KD | | KD | | KD | | KD | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | 1.0 | |
| **ANALYTE** | **Result % v/v** | **RL % v/v** | **Result % v/v** | **RL % v/v** | **Result % v/v** | **RL % v/v** | **Result % v/v** | **RL % v/v** |
| Carbon Dioxide | 76 | 0.010 | 46 | 0.010 | 46 | 0.010 | 57 | 0.010 |
| Oxygen/Argon | 0.63 | 0.50 | 8.3 | 0.50 | 2.9 | 0.50 | 1.8 | 0.50 |
| Nitrogen | 2.2 | 1.0 | 31 | 1.0 | 32 | 1.0 | 24 | 1.0 |
| Methane | 3.4 | 0.0010 | 1.6 | 0.0010 | 16 | 0.0010 | 11 | 0.0010 |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-14-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report



SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com
Member of the SGS Group (SGS SA)

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/06/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T050603-09 | | T050603-10 | | | | | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2346 | | CV-108-52 | | | | | |
| Date/Time Sampled: | 5/6/26 8:25 | | 5/6/26 8:30 | | | | | |
| Date/Time Analyzed: | 5/6/26 17:48 | | 5/6/26 18:03 | | | | | |
| QC Batch No.: | 260506GC8A2 | | 260506GC8A2 | | | | | |
| Analyst Initials: | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | 1.0 | | | | | |
| **ANALYTE** | **Result % v/v** | **RL % v/v** | **Result % v/v** | **RL % v/v** | | | | |
| Carbon Dioxide | 77 | 0.010 | 47 | 0.010 | | | | |
| Oxygen/Argon | 0.79 | 0.50 | 0.95 | 0.50 | | | | |
| Nitrogen | 3.8 | 1.0 | 3.5 | 1.0 | | | | |
| Methane | 3.4 | 0.0010 | 47 | 0.0010 | | | | |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-14-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report



SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com

Member of the SGS Group (SGS SA)

**QC Batch No:** 260506GC8A2
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946
## LABORATORY CONTROL SAMPLE SUMMARY

| Lab No.: | METHOD BLANK | | | LCS | | LCSD | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Date Analyzed: | 5/6/26 15:38 | | | 5/6/26 14:54 | | 5/6/26 15:09 | | | | | |
| Analyst Initials: | KD | | | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | | 1.0 | | 1.0 | | | Limits | | |
| ANALYTE | Result % v/v | RL % v/v | SPIKE AMT. % v/v | Result % v/v | % Rec. | Result % v/v | % Rec. | RPD % | Low %Rec | High %Rec | Max. RPD |
| Carbon Dioxide | ND | 0.010 | 10 | 9.48 | 95 | 9.48 | 95 | 0.0 | 70 | 130 | 30 |
| Oxygen/Argon | ND | 0.50 | 15 | 14.7 | 98 | 14.6 | 97 | 0.3 | 70 | 130 | 30 |
| Nitrogen | ND | 1.0 | 70 | 70.4 | 101 | 70.2 | 101 | 0.3 | 70 | 130 | 30 |
| Methane | ND | 0.0010 | 0.10 | 0.103 | 102 | 0.103 | 102 | 0.1 | 70 | 130 | 30 |
| | | | | | | | | | | | |

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-14-26
**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175
TX Cert T104704450-14-6
EPA Methods TO14A, TO15
ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

May 29, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

## LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T050706-01/10

Enclosed are the results for sample(s) received 5/7/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

# CHAIN OF CUSTODY RECORD

**TURNAROUND TIME**
Standard ■ 48 hours ☐
Same Day ☐ 72 hours ☐
24 hours ☐ 96 hours ☐
Other:

**DELIVERABLES**
EDD ■
EDF ☐
Level 3 ☐
Level 4 ☐

**PAGE:** 1 OF

Condition upon receipt:
Sealed Yes ☐ No ☐
Intact Yes ☐ No ☐
Chilled _____ deg C

| | |
|---|---|
| **Project No.:** | 07224200.24 Task 1 |
| **Project Name:** | Chiquita Canyon Landfill |
| **Report To:** | Cornelius Fong |
| **Company:** | SCS Engineers |
| **Street:** | 3900 Kilroy Airport Way, Suite 300 |
| **City/State/Zip:** | Long Beach, CA 90806-6816 |
| **Phone& Fax:** | 562-743-7895 |
| **e-mail:** | cfong@scsengineers.com |

**BILLING**
**P.O. No.:**
**Bill to:** 07FSAccountspayable@scsengineers.com
3900 Kilroy Airport Way, Suite 300
Long Beach, CA 90806-6816

**ANALYSIS REQUEST**

| LAB USE ONLY | SAMPLE IDENTIFICATION | SAMPLE DATE | SAMPLE TIME | CONTAINER QTY/TYPE | MATRIX | PRESERVATION | CH4, CO2, O2, N2 ASTM D1946 | Carbon Monoxide EPA ALT-144 | Hydrogen ASTM D1946 | VOCs EPA TO-15 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| T050706-01 | CV-2301 | 05/07/26 | 7:55AM | 2-1L | Gas | N | X | X | X | X | | |
| -02 | CV-2302 | 05/07/26 | 8:05am | 2-1L | Gas | N | X | X | X | X | | |
| -03 | CV-24071 | 05/07/26 | 8:10AM | 1L | Gas | N | X | X | X | | | |
| -04 | CV-2328 | 05/07/26 | 8:15AM | 1L | Gas | N | X | X | X | | | |
| -05 | CV-24062 | 05/07/26 | 8:17AM | 1L | Gas | N | X | X | X | | | |
| -06 | CV-24070 | 05/07/26 | 8:20AM | 1L | Gas | N | X | X | X | | | |
| -07 | CV-24084 | 05/07/26 | 8:25AM | 1L | Gas | N | X | | | | | |
| -08 | CV-2315 | 05/07/26 | 8:30AM | 2-1L | Gas | N | X | X | X | X | | |
| -09 | CV-24065 | 05/07/26 | 8:35AM | 2-1L | Gas | N | X | X | X | X | | |
| -10 | CV-24053 | 05/07/26 | 8:40AM | 2-1L | Gas | N | X | X | X | X | | |

| | | | |
|---|---|---|---|
| AUTHORIZATION TO PERFORM WORK | COMPANY SCS | DATE/TIME 5-7-26 9:20AM | |
| SAMPLED BY Erik Navrro | COMPANY SCS | DATE/TIME 5-7-26 9:20AM | |
| RELINQUISHED BY Erik Navrro | DATE/TIME 5/7/26 9:20AM | RECEIVED BY Ruben G | DATE/TIME 5/7/26 9:30 |
| RELINQUISHED BY Ruben G | DATE/TIME 5/7/26 11:55 | RECEIVED BY | DATE/TIME 5/7/26 1155 |
| RELINQUISHED BY | DATE/TIME | RECEIVED BY | DATE/TIME |

**METHOD OF TRANSPORT (circle one):** Walk-In FedEx UPS **Courier** ATLI Other_____

**COMMENTS**
Report full list of TO-15 compounds
Raw landfill gas samples
**FLAMMABLE**

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/07/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | T050706-01 | | T050706-02 | | T050706-08 | | T050706-09 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2301 | | CV-2302 | | CV-2315 | | CV-24065 | |
| Date/Time Sampled: | 5/7/26 7:55 | | 5/7/26 8:05 | | 5/7/26 8:30 | | 5/7/26 8:35 | |
| Date/Time Analyzed: | 5/7/26 17:58 | | 5/7/26 18:37 | | 5/7/26 19:15 | | 5/7/26 19:54 | |
| QC Batch No.: | 260507MS2A1 | | 260507MS2A1 | | 260507MS2A1 | | 260507MS2A1 | |
| Analyst Initials: | AS/GD | | AS/GD | | AS/GD | | AS/GD | |
| Dilution Factor: | 4,000 | | 4,800 | | 4,000 | | 1,000 | |
| ANALYTE | Result ppbv | RL ppbv | Result ppbv | RL ppbv | Result ppbv | RL ppbv | Result ppbv | RL ppbv |
| Dichlorodifluoromethane (12) | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| Chloromethane | ND Q | 4,000 | ND Q | 4,800 | 14,000 Q | 4,000 | ND Q | 1,000 |
| 1,2-Cl-1,1,2,2-F ethane (114) | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| Vinyl Chloride | ND Q | 4,000 | ND Q | 4,800 | ND Q | 4,000 | ND Q | 1,000 |
| Bromomethane | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| Chloroethane | ND | 20,000 | ND | 24,000 | ND | 20,000 | ND | 5,000 |
| Trichlorofluoromethane (11) | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| 1,1-Dichloroethene | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| Carbon Disulfide | 14,000 | 4,000 | ND | 4,800 | 9,900 | 4,000 | 3,600 | 1,000 |
| 1,1,2-Cl 1,2,2-F ethane (113) | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| Acetone | 610,000 E | 20,000 | 130,000 | 24,000 | 770,000 E | 20,000 | 210,000 E | 5,000 |
| Methylene Chloride | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| t-1,2-Dichloroethene | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| 1,1-Dichloroethane | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| Vinyl Acetate | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| c-1,2-Dichloroethene | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| 2-Butanone | 750,000 | 20,000 | 130,000 | 24,000 | 820,000 | 20,000 | 310,000 E | 5,000 |
| t-Butyl Methyl Ether (MTBE) | ND | 4,000 | ND | 4,800 | ND | 4,000 | 1,600 | 1,000 |
| Chloroform | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| 1,1,1-Trichloroethane | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| Carbon Tetrachloride | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| Benzene | 210,000 | 4,000 | 77,000 | 4,800 | 280,000 | 4,000 | 130,000 | 1,000 |
| 1,2-Dichloroethane | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| Trichloroethene | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| 1,2-Dichloropropane | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| Bromodichloromethane | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| c-1,3-Dichloropropene | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| 4-Methyl-2-Pentanone | 8,900 | 4,000 | ND | 4,800 | 9,000 | 4,000 | 6,700 | 1,000 |
| Toluene | 9,800 | 4,000 | ND | 4,800 | 14,000 | 4,000 | 8,200 | 1,000 |
| t-1,3-Dichloropropene | ND | 8,000 | ND | 9,600 | ND | 8,000 | ND | 2,000 |
| 1,1,2-Trichloroethane | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| Tetrachloroethene | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| 2-Hexanone | ND | 4,000 | ND | 4,800 | ND | 4,000 | 1,700 | 1,000 |
| Dibromochloromethane | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/07/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | T050706-01 | | T050706-02 | | T050706-08 | | T050706-09 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2301 | | CV-2302 | | CV-2315 | | CV-24065 | |
| Date/Time Sampled: | 5/7/26 7:55 | | 5/7/26 8:05 | | 5/7/26 8:30 | | 5/7/26 8:35 | |
| Date/Time Analyzed: | 5/7/26 17:58 | | 5/7/26 18:37 | | 5/7/26 19:15 | | 5/7/26 19:54 | |
| QC Batch No.: | 260507MS2A1 | | 260507MS2A1 | | 260507MS2A1 | | 260507MS2A1 | |
| Analyst Initials: | AS/GD | | AS/GD | | AS/GD | | AS/GD | |
| Dilution Factor: | 4,000 | | 4,800 | | 4,000 | | 1,000 | |
| ANALYTE | Result ppbv | RL ppbv | Result ppbv | RL ppbv | Result ppbv | RL ppbv | Result ppbv | RL ppbv |
| 1,2-Dibromoethane | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| Chlorobenzene | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| Ethylbenzene | ND | 4,000 | ND | 4,800 | ND | 4,000 | **1,600** | 1,000 |
| p,&m-Xylene | ND | 8,000 | ND | 9,600 | ND | 8,000 | ND | 2,000 |
| o-Xylene | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| Styrene | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| Bromoform | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| 1,1,2,2-Tetrachloroethane | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| Benzyl Chloride | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| 4-Ethyl Toluene | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| 1,3,5-Trimethylbenzene | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| 1,2,4-Trimethylbenzene | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| 1,3-Dichlorobenzene | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| 1,4-Dichlorobenzene | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| 1,2-Dichlorobenzene | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| 1,2,4-Trichlorobenzene | ND | 28,000 | ND | 34,000 | ND | 28,000 | ND | 7,000 |
| Hexachlorobutadiene | ND | 4,000 | ND | 4,800 | ND | 4,000 | ND | 1,000 |
| 1,3-Butadiene | ND | 20,000 | ND | 24,000 | ND | 20,000 | **8,200** | 5,000 |
| Isopropanol | **160,000** | 20,000 | **82,000** | 24,000 | **230,000** | 20,000 | **160,000** | 5,000 |
| n-Hexane | ND | 20,000 | ND | 24,000 | ND | 20,000 | ND | 5,000 |
| Ethyl Acetate | **46,000** | 20,000 | ND | 24,000 | **80,000** | 20,000 | **14,000** | 5,000 |
| Tetrahydrofuran | **550,000** | 20,000 | **110,000** | 24,000 | **670,000** | 20,000 | **220,000** | 5,000 |
| Cyclohexane | ND | 20,000 | ND | 24,000 | ND | 20,000 | ND | 5,000 |
| Heptane | ND | 20,000 | ND | 24,000 | **22,000** | 20,000 | **11,000** | 5,000 |
| 1,4-Dioxane | ND | 20,000 | ND | 24,000 | ND | 20,000 | **6,500** | 5,000 |
| | | | | | | | | |

**RL = Reporting Limit**
**ND = Not Detected (below RL)**
**Q = Analyte exhibited low recovery in the continuing calibration verification indicating possible low bias**
**E = Estimated. Analyte exceeded the upper calibration range**

**Reviewed/Approved By:** _____ **Date** 5/9/26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/07/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| | |
|---|---|
| Lab No.: | T050706-10 |
| Client Sample I.D.: | CV-24053 |
| Date/Time Sampled: | 5/7/26 8:40 |
| Date/Time Analyzed: | 5/7/26 20:34 |
| QC Batch No.: | 260507MS2A1 |
| Analyst Initials: | AS/GD |
| Dilution Factor: | 960 |

| ANALYTE | Result ppbv | RL ppbv |
|---|---|---|
| Dichlorodifluoromethane (12) | ND | 960 |
| Chloromethane | ND Q | 960 |
| 1,2-Cl-1,1,2,2-F ethane (114) | ND | 960 |
| Vinyl Chloride | ND Q | 960 |
| Bromomethane | ND | 960 |
| Chloroethane | ND | 4,800 |
| Trichlorofluoromethane (11) | ND | 960 |
| 1,1-Dichloroethene | ND | 960 |
| Carbon Disulfide | 2,200 | 960 |
| 1,1,2-Cl 1,2,2-F ethane (113) | ND | 960 |
| Acetone | 110,000 E | 4,800 |
| Methylene Chloride | ND | 960 |
| t-1,2-Dichloroethene | ND | 960 |
| 1,1-Dichloroethane | ND | 960 |
| Vinyl Acetate | ND | 960 |
| c-1,2-Dichloroethene | ND | 960 |
| 2-Butanone | 160,000 | 4,800 |
| t-Butyl Methyl Ether (MTBE) | ND | 960 |
| Chloroform | ND | 960 |
| 1,1,1-Trichloroethane | ND | 960 |
| Carbon Tetrachloride | ND | 960 |
| Benzene | 46,000 | 960 |
| 1,2-Dichloroethane | ND | 960 |
| Trichloroethene | ND | 960 |
| 1,2-Dichloropropane | ND | 960 |
| Bromodichloromethane | ND | 960 |
| c-1,3-Dichloropropene | ND | 960 |
| 4-Methyl-2-Pentanone | 3,600 | 960 |
| Toluene | 3,900 | 960 |
| t-1,3-Dichloropropene | ND | 1,900 |
| 1,1,2-Trichloroethane | ND | 960 |
| Tetrachloroethene | ND | 960 |
| 2-Hexanone | 1,200 | 960 |
| Dibromochloromethane | ND | 960 |

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/07/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | T050706-10 |
|---|---|
| Client Sample I.D.: | CV-24053 |
| Date/Time Sampled: | 5/7/26 8:40 |
| Date/Time Analyzed: | 5/7/26 20:34 |
| QC Batch No.: | 260507MS2A1 |
| Analyst Initials: | AS/GD |
| Dilution Factor: | 960 |

| ANALYTE | Result ppbv | RL ppbv |
|---|---|---|
| 1,2-Dibromoethane | ND | 960 |
| Chlorobenzene | ND | 960 |
| Ethylbenzene | ND | 960 |
| p,&m-Xylene | ND | 1,900 |
| o-Xylene | ND | 960 |
| Styrene | ND | 960 |
| Bromoform | ND | 960 |
| 1,1,2,2-Tetrachloroethane | ND | 960 |
| Benzyl Chloride | ND | 960 |
| 4-Ethyl Toluene | ND | 960 |
| 1,3,5-Trimethylbenzene | ND | 960 |
| 1,2,4-Trimethylbenzene | ND | 960 |
| 1,3-Dichlorobenzene | ND | 960 |
| 1,4-Dichlorobenzene | ND | 960 |
| 1,2-Dichlorobenzene | ND | 960 |
| 1,2,4-Trichlorobenzene | ND | 6,700 |
| Hexachlorobutadiene | ND | 960 |
| 1,3-Butadiene | ND | 4,800 |
| Isopropanol | 84,000 | 4,800 |
| n-Hexane | ND | 4,800 |
| Ethyl Acetate | 6,300 | 4,800 |
| Tetrahydrofuran | 120,000 | 4,800 |
| Cyclohexane | ND | 4,800 |
| Heptane | ND | 4,800 |
| 1,4-Dioxane | ND | 4,800 |

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited low recovery in the continuing calibration verification indicating possible low bias
E = Estimated. Analyte exceeded the upper calibration range

Reviewed/Approved By: _____ Date 5/29/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/07/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | METHOD BLANK | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | -- | | | | | | | |
| Date/Time Sampled: | -- | | | | | | | |
| Date/Time Analyzed: | 5/7/26 16:14 | | | | | | | |
| QC Batch No.: | 260507MS2A1 | | | | | | | |
| Analyst Initials: | AS/GD | | | | | | | |
| Dilution Factor: | 0.20 | | | | | | | |

| ANALYTE | Result ppbv | | RL ppbv | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Dichlorodifluoromethane (12) | ND | | 0.20 | | | | | | |
| Chloromethane | ND | Q | 0.20 | | | | | | |
| 1,2-Cl-1,1,2,2-F ethane (114) | ND | | 0.20 | | | | | | |
| Vinyl Chloride | ND | Q | 0.20 | | | | | | |
| Bromomethane | ND | | 0.20 | | | | | | |
| Chloroethane | ND | | 1.0 | | | | | | |
| Trichlorofluoromethane (11) | ND | | 0.20 | | | | | | |
| 1,1-Dichloroethene | ND | | 0.20 | | | | | | |
| Carbon Disulfide | ND | | 0.20 | | | | | | |
| 1,1,2-Cl 1,2,2-F ethane (113) | ND | | 0.20 | | | | | | |
| Acetone | ND | | 1.0 | | | | | | |
| Methylene Chloride | ND | | 0.20 | | | | | | |
| t-1,2-Dichloroethene | ND | | 0.20 | | | | | | |
| 1,1-Dichloroethane | ND | | 0.20 | | | | | | |
| Vinyl Acetate | ND | | 0.20 | | | | | | |
| c-1,2-Dichloroethene | ND | | 0.20 | | | | | | |
| 2-Butanone | ND | | 1.0 | | | | | | |
| t-Butyl Methyl Ether (MTBE) | ND | | 0.20 | | | | | | |
| Chloroform | ND | | 0.20 | | | | | | |
| 1,1,1-Trichloroethane | ND | | 0.20 | | | | | | |
| Carbon Tetrachloride | ND | | 0.20 | | | | | | |
| Benzene | ND | | 0.20 | | | | | | |
| 1,2-Dichloroethane | ND | | 0.20 | | | | | | |
| Trichloroethene | ND | | 0.20 | | | | | | |
| 1,2-Dichloropropane | ND | | 0.20 | | | | | | |
| Bromodichloromethane | ND | | 0.20 | | | | | | |
| c-1,3-Dichloropropene | ND | | 0.20 | | | | | | |
| 4-Methyl-2-Pentanone | ND | | 0.20 | | | | | | |
| Toluene | ND | | 0.20 | | | | | | |
| t-1,3-Dichloropropene | ND | | 0.40 | | | | | | |
| 1,1,2-Trichloroethane | ND | | 0.20 | | | | | | |
| Tetrachloroethene | ND | | 0.20 | | | | | | |
| 2-Hexanone | ND | | 0.20 | | | | | | |
| Dibromochloromethane | ND | | 0.20 | | | | | | |

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/07/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | METHOD BLANK |
|---|---|
| Client Sample I.D.: | -- |
| Date/Time Sampled: | -- |
| Date/Time Analyzed: | 5/7/26 16:14 |
| QC Batch No.: | 260507MS2A1 |
| Analyst Initials: | AS/GD |
| Dilution Factor: | 0.20 |

| ANALYTE | Result ppbv | RL ppbv |
|---|---|---|
| 1,2-Dibromoethane | ND | 0.20 |
| Chlorobenzene | ND | 0.20 |
| Ethylbenzene | ND | 0.20 |
| p,&m-Xylene | ND | 0.40 |
| o-Xylene | ND | 0.20 |
| Styrene | ND | 0.20 |
| Bromoform | ND | 0.20 |
| 1,1,2,2-Tetrachloroethane | ND | 0.20 |
| Benzyl Chloride | ND | 0.20 |
| 4-Ethyl Toluene | ND | 0.20 |
| 1,3,5-Trimethylbenzene | ND | 0.20 |
| 1,2,4-Trimethylbenzene | ND | 0.20 |
| 1,3-Dichlorobenzene | ND | 0.20 |
| 1,4-Dichlorobenzene | ND | 0.20 |
| 1,2-Dichlorobenzene | ND | 0.20 |
| 1,2,4-Trichlorobenzene | ND | 1.4 |
| Hexachlorobutadiene | ND | 0.20 |
| 1,3-Butadiene | ND | 1.0 |
| Isopropanol | ND | 1.0 |
| n-Hexane | ND | 1.0 |
| Ethyl Acetate | ND | 1.0 |
| Tetrahydrofuran | ND | 1.0 |
| Cyclohexane | ND | 1.0 |
| Heptane | ND | 1.0 |
| 1,4-Dioxane | ND | 1.0 |

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited low recovery in the continuing calibration verification indicating possible low bias

Reviewed/Approved By: _____ Date 5/7/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

# LCS/LCSD Recovery and RPD Summary Report

## QC Batch #: 260507MS2A1

**Matrix:** Air

**Reporting Units:** ppbv

**EPA Method TO-15**
**LABORATORY CONTROL SAMPLE SUMMARY**

| Lab No.: | METHOD BLANK | | | LCS | | LCSD | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Date/Time Analyzed: | 5/7/26 16:14 | | | 5/7/26 11:02 | | 5/7/26 11:40 | | | | | |
| Analyst Initials: | AS/GD | | | AS/GD | | AS/GD | | | | | |
| Dilution Factor: | 0.20 | | | 1.0 | | 1.0 | | | | | |
| ANALYTE | Result ppbv | RL ppbv | AMT. ppbv | Result ppbv | % Rec. | Result ppbv | % Rec. | RPD | Low %Rec | High %Rec | Max. RPD |
| 1,1-Dichloroethene | ND | 0.20 | 10 | 11.4 | 114 | 11.4 | 114 | 0.3 | 70 | 130 | 30 |
| Methylene Chloride | ND | 0.20 | 10 | 10.5 | 105 | 10.5 | 105 | 0.1 | 70 | 130 | 30 |
| Trichloroethene | ND | 0.20 | 10 | 11.4 | 114 | 11.3 | 113 | 0.8 | 70 | 130 | 30 |
| Toluene | ND | 0.20 | 10 | 11.1 | 111 | 11.3 | 113 | 1.2 | 70 | 130 | 30 |
| 1,1,2,2-Tetrachloroethane | ND | 0.20 | 10 | 10.1 | 101 | 10.3 | 103 | 1.4 | 70 | 130 | 30 |
| | | | | | | | | | | | |

ND = Not Detected (below RL)
RL = Reporting Limit

**Reviewed/Approved By:** _____ **Date:** 5/29/26
**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/07/26
**Matrix:** Air
**Reporting Units:** ppmv

## EPA ALT-144 (CO by FID)

| Lab No.: | T050706-01 | | T050706-02 | | T050706-03 | | T050706-04 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2301 | | CV-2302 | | CV-24071 | | CV-2328 | |
| Date/Time Sampled: | 5/7/26 7:55 | | 5/7/26 8:05 | | 5/7/26 8:10 | | 5/7/26 8:15 | |
| Date/Time Analyzed: | 5/7/26 16:41 | | 5/7/26 16:56 | | 5/7/26 17:10 | | 5/7/26 17:25 | |
| QC Batch No.: | 260507GC8A2 | | 260507GC8A2 | | 260507GC8A2 | | 260507GC8A2 | |
| Analyst Initials: | KD | | KD | | KD | | KD | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | 1.0 | |
| ANALYTE | Result ppmv | RL ppmv | Result ppmv | RL ppmv | Result ppmv | RL ppmv | Result ppmv | RL ppmv |
| Carbon Monoxide | 2,200 | 10 | 320 | 10 | 190 | 10 | 980 | 10 |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-20-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/07/26
**Matrix:** Air
**Reporting Units:** ppmv

## EPA ALT-144 (CO by FID)

| Lab No.: | T050706-05 | | T050706-06 | | T050706-08 | | T050706-09 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-24062 | | CV-24070 | | CV-2315 | | CV-24065 | |
| Date/Time Sampled: | 5/7/26 8:17 | | 5/7/26 8:20 | | 5/7/26 8:30 | | 5/7/26 8:35 | |
| Date/Time Analyzed: | 5/7/26 17:39 | | 5/7/26 17:54 | | 5/7/26 18:23 | | 5/7/26 18:37 | |
| QC Batch No.: | 260507GC8A2 | | 260507GC8A2 | | 260507GC8A2 | | 260507GC8A2 | |
| Analyst Initials: | KD | | KD | | KD | | KD | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | 1.0 | |
| ANALYTE | Result ppmv | RL ppmv | Result ppmv | RL ppmv | Result ppmv | RL ppmv | Result ppmv | RL ppmv |
| Carbon Monoxide | 890 | 10 | 1,300 | 10 | 3,900 | 10 | 530 | 10 |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-20-26
**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report


SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com
Member of the SGS Group (SGS SA)

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/07/26
**Matrix:** Air
**Reporting Units:** ppmv

## EPA ALT-144 (CO by FID)

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| **Lab No.:** | **T050706-10** | | | | | | | |
| **Client Sample I.D.:** | **CV-24053** | | | | | | | |
| **Date/Time Sampled:** | **5/7/26 8:40** | | | | | | | |
| **Date/Time Analyzed:** | **5/7/26 18:52** | | | | | | | |
| **QC Batch No.:** | **260507GC8A2** | | | | | | | |
| **Analyst Initials:** | **KD** | | | | | | | |
| **Dilution Factor:** | **1.0** | | | | | | | |
| **ANALYTE** | **Result ppmv** | **RL ppmv** | | | | | | |
| Carbon Monoxide | 88 | 10 | | | | | | |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-20-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**QC Batch No:** 260507GC8A2
**Matrix:** Air
**Reporting Units:** ppmv

## EPA ALT-144 (CO by FID)
## LABORATORY CONTROL SAMPLE SUMMARY

| Lab No.: | METHOD BLANK | | | LCS | | LCSD | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Date Analyzed: | 5/7/26 14:02 | | | 5/7/26 13:04 | | 5/7/26 13:18 | | | | | |
| Analyst Initials: | KD | | | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | | 1.0 | | 1.0 | | | Limits | | |
| ANALYTE | Result ppmv | RL ppmv | SPIKE AMT. ppmv | Result ppmv | % Rec. | Result ppmv | % Rec. | RPD % | Low %Rec | High %Rec | Max. RPD |
| Carbon Monoxide | ND | 10 | 1,010 | 1,080 | 107 | 1,080 | 107 | 0.6 | 70 | 130 | 30 |
| | | | | | | | | | | | |

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-20-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/07/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T050706-01 | | | T050706-02 | | | T050706-03 | | | T050706-04 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2301 | | | CV-2302 | | | CV-24071 | | | CV-2328 | | |
| Date/Time Sampled: | 5/7/26 7:55 | | | 5/7/26 8:05 | | | 5/7/26 8:10 | | | 5/7/26 8:15 | | |
| Date/Time Analyzed: | 5/7/26 16:41 | | | 5/7/26 16:56 | | | 5/7/26 17:10 | | | 5/7/26 17:25 | | |
| QC Batch No.: | 260507GC8A2 | | | 260507GC8A2 | | | 260507GC8A2 | | | 260507GC8A2 | | |
| Analyst Initials: | KD | | | KD | | | KD | | | KD | | |
| Dilution Factor: | 1.0 | | | 1.0 | | | 1.0 | | | 1.0 | | |
| ANALYTE | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v |
| Hydrogen | 15 | 1.0 | 0.059 | 5.3 | 1.0 | 0.059 | 2.4 | 1.0 | 0.059 | 11 | 1.0 | 0.059 |

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/07/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T050706-05 | | | T050706-06 | | | T050706-08 | | | T050706-09 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-24062 | | | CV-24070 | | | CV-2315 | | | CV-24065 | | |
| Date/Time Sampled: | 5/7/26 8:17 | | | 5/7/26 8:20 | | | 5/7/26 8:30 | | | 5/7/26 8:35 | | |
| Date/Time Analyzed: | 5/7/26 17:39 | | | 5/7/26 17:54 | | | 5/7/26 18:23 | | | 5/7/26 18:37 | | |
| QC Batch No.: | 260507GC8A2 | | | 260507GC8A2 | | | 260507GC8A2 | | | 260507GC8A2 | | |
| Analyst Initials: | KD | | | KD | | | KD | | | KD | | |
| Dilution Factor: | 1.0 | | | 1.0 | | | 1.0 | | | 1.0 | | |
| ANALYTE | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v |
| Hydrogen | 8.0 | 1.0 | 0.059 | 11 | 1.0 | 0.059 | 14 | 1.0 | 0.059 | 0.98 J | 1.0 | 0.059 |
| | | | | | | | | | | | | |

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/07/26
**Matrix:** Air
**Reporting Units:** % v/v

**ASTM D1946**

| Lab No.: | T050706-10 | | |
|---|---|---|---|
| Client Sample I.D.: | CV-24053 | | |
| Date/Time Sampled: | 5/7/26 8:40 | | |
| Date/Time Analyzed: | 5/7/26 18:52 | | |
| QC Batch No.: | 260507GC8A2 | | |
| Analyst Initials: | KD | | |
| Dilution Factor: | 1.0 | | |

| ANALYTE | Result % v/v | RL % v/v | MDL % v/v |
|---|---|---|---|
| Hydrogen | 0.53 J | 1.0 | 0.059 |
| | | | |

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**QC Batch No:** 260507GC8A2
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946
## LABORATORY CONTROL SAMPLE SUMMARY

| Lab No.: | METHOD BLANK | | | | LCS | | LCSD | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Date Analyzed: | 5/7/26 14:02 | | | | 5/7/26 13:04 | | 5/7/26 13:18 | | | | | |
| Analyst Initials: | KD | | | | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | | | 1.0 | | 1.0 | | | Limits | | |
| ANALYTE | Result % v/v | RL % v/v | MDL % v/v | SPIKE AMT. % v/v | Result % v/v | % Rec. | Result % v/v | % Rec. | RPD % | Low %Rec | High %Rec | Max. RPD |
| Hydrogen | ND | 1.0 | 0.059 | 5.0 | 4.31 | 87 | 4.33 | 87 | 0.4 | 70 | 130 | 30 |
| | | | | | | | | | | | | |

**MDL = Method Detection Limit**
**ND= Not Detected (below MDL)**
**RL = Reporting Limit**
**J = Trace amount. Analyte concentration between RL and MDL.**

**Reviewed/Approved By:** _____ **Date** 5-20-26
**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/07/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T050706-01 | | T050706-02 | | T050706-03 | | T050706-04 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2301 | | CV-2302 | | CV-24071 | | CV-2328 | |
| Date/Time Sampled: | 5/7/26 7:55 | | 5/7/26 8:05 | | 5/7/26 8:10 | | 5/7/26 8:15 | |
| Date/Time Analyzed: | 5/7/26 16:41 | | 5/7/26 16:56 | | 5/7/26 17:10 | | 5/7/26 17:25 | |
| QC Batch No.: | 260507GC8A2 | | 260507GC8A2 | | 260507GC8A2 | | 260507GC8A2 | |
| Analyst Initials: | KD | | KD | | KD | | KD | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | 1.0 | |
| ANALYTE | Result % v/v | RL % v/v | Result % v/v | RL % v/v | Result % v/v | RL % v/v | Result % v/v | RL % v/v |
| Carbon Dioxide | 76 | 0.010 | 52 | 0.010 | 50 | 0.010 | 77 | 0.010 |
| Oxygen/Argon | 1.3 | 0.50 | 1.4 | 0.50 | 0.66 | 0.50 | 0.59 | 0.50 |
| Nitrogen | 4.6 | 1.0 | 5.1 | 1.0 | 2.4 | 1.0 | 2.1 | 1.0 |
| Methane | 0.71 | 0.0010 | 36 | 0.0010 | 44 | 0.0010 | 8.0 | 0.0010 |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-20-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/07/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T050706-05 | | T050706-06 | | T050706-07 | | T050706-08 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-24062 | | CV-24070 | | CV-24084 | | CV-2315 | |
| Date/Time Sampled: | 5/7/26 8:17 | | 5/7/26 8:20 | | 5/7/26 8:25 | | 5/7/26 8:30 | |
| Date/Time Analyzed: | 5/7/26 17:39 | | 5/7/26 17:54 | | 5/7/26 18:08 | | 5/7/26 18:23 | |
| QC Batch No.: | 260507GC8A2 | | 260507GC8A2 | | 260507GC8A2 | | 260507GC8A2 | |
| Analyst Initials: | KD | | KD | | KD | | KD | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | 1.0 | |
| ANALYTE | Result % v/v | RL % v/v | Result % v/v | RL % v/v | Result % v/v | RL % v/v | Result % v/v | RL % v/v |
| Carbon Dioxide | 61 | 0.010 | 73 | 0.010 | 81 | 0.010 | 79 | 0.010 |
| Oxygen/Argon | 0.77 | 0.50 | 0.51 | 0.50 | 0.56 | 0.50 | 0.75 | 0.50 |
| Nitrogen | 2.8 | 1.0 | 1.9 | 1.0 | 1.9 | 1.0 | 2.6 | 1.0 |
| Methane | 26 | 0.0010 | 13 | 0.0010 | 2.4 | 0.0010 | 1.1 | 0.0010 |
| | | | | | | | | |

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 5-20-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/07/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T050706-09 | | T050706-10 | | | | | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-24065 | | CV-24053 | | | | | |
| Date/Time Sampled: | 5/7/26 8:35 | | 5/7/26 8:40 | | | | | |
| Date/Time Analyzed: | 5/7/26 18:37 | | 5/7/26 18:52 | | | | | |
| QC Batch No.: | 260507GC8A2 | | 260507GC8A2 | | | | | |
| Analyst Initials: | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | 1.0 | | | | | |
| **ANALYTE** | **Result % v/v** | **RL % v/v** | **Result % v/v** | **RL % v/v** | | | | |
| Carbon Dioxide | 83 | 0.010 | 38 | 0.010 | | | | |
| Oxygen/Argon | 0.79 | 0.50 | 4.1 | 0.50 | | | | |
| Nitrogen | 2.9 | 1.0 | 18 | 1.0 | | | | |
| Methane | 11 | 0.0010 | 39 | 0.0010 | | | | |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-20-26
**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**QC Batch No:** 260507GC8A2
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946
## LABORATORY CONTROL SAMPLE SUMMARY

| Lab No.: | METHOD BLANK | | | LCS | | LCSD | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Date Analyzed: | 5/7/26 14:02 | | | 5/7/26 13:04 | | 5/7/26 13:18 | | | | | |
| Analyst Initials: | KD | | | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | | 1.0 | | 1.0 | | | Limits | | |
| ANALYTE | Result % v/v | RL % v/v | SPIKE AMT. % v/v | Result % v/v | % Rec. | Result % v/v | % Rec. | RPD % | Low %Rec | High %Rec | Max. RPD |
| Carbon Dioxide | ND | 0.010 | 10 | 9.16 | 91 | 9.16 | 91 | 0.1 | 70 | 130 | 30 |
| Oxygen/Argon | ND | 0.50 | 15 | 14.9 | 99 | 14.9 | 99 | 0.1 | 70 | 130 | 30 |
| Nitrogen | ND | 1.0 | 70 | 70.8 | 102 | 70.8 | 102 | 0.0 | 70 | 130 | 30 |
| Methane | ND | 0.0010 | 0.10 | 0.101 | 100 | 0.101 | 100 | 0.4 | 70 | 130 | 30 |
| | | | | | | | | | | | |

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-20-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C,
ASTM D1946, RSK-175

TX Cert T104704450-14-6
EPA Methods TO14A, TO15

ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

May 31, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

## LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T051102-01/10

Enclosed are the results for sample(s) received 5/11/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AIR TECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

# CHAIN OF CUSTODY RECORD

| TURNAROUND TIME | | | | DELIVERABLES | | PAGE: 1 OF |
|---|---|---|---|---|---|---|
| Standard | ■ | 48 hours | ☐ | EDD | ■ | Condition upon receipt: |
| Same Day | ☐ | 72 hours | ☐ | EDF | ☐ | Sealed Yes ☐ No ☐ |
| 24 hours | ☐ | 96 hours | ☐ | Level 3 | ☐ | Intact Yes ☐ No ☐ |
| Other: | | | | Level 4 | ☐ | Chilled _____ deg C |

| | |
|---|---|
| **Project No.:** | 07224200.24 Task 1 |
| **Project Name:** | Chiquita Canyon Landfill |
| **Report To:** | Cornelius Fong |
| **Company:** | SCS Engineers |
| **Street:** | 3900 Kilroy Airport Way, Suite 300 |
| **City/State/Zip:** | Long Beach, CA 90806-6816 |
| **Phone& Fax:** | 562-743-7895 |
| **e-mail:** | cfong@scsengineers.com |

**BILLING**

| | |
|---|---|
| **P.O. No.:** | |
| **Bill to:** | |
| | [redacted]@scsengineers.com |
| | 3900 Kilroy Airport Way, Suite 300 |
| | Long Beach, CA 90806-6816 |

| LAB USE ONLY | SAMPLE IDENTIFICATION | SAMPLE DATE | SAMPLE TIME | CONTAINER QTY/TYPE | MATRIX | PRESERVATION | CH4, CO2, O2, N2 ASTM D1946 | Carbon Monoxide EPA ALT-144 | Hydrogen ASTM D1946 | VOCs EPA TO-15 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| T051102-01 | CV-2345 | 05/11/26 | 7:30am | 1L | Gas | N | X | X | X | | | |
| -02 | CV-2344 | 05/11/26 | 7:35am | 1L | Gas | N | X | X | X | | | |
| -03 | CV-2350 | 05/11/26 | 7:40m | 2-1L | Gas | N | X | X | X | X | | |
| -04 | CV-24066 | 05/11/26 | 7:45am | 1L | Gas | N | X | X | X | | | |
| -05 | CV-2341 | 05/11/26 | 7:50m | 1L | Gas | N | X | X | X | | | |
| -06 | CV-1902A | 05/11/26 | 7:55am | 2-1L | Gas | N | X | X | X | X | | |
| -07 | CV-2337 | 05/11/26 | 8:05am | 1L | Gas | N | X | X | X | | | |
| -08 | CV-2002 | 05/11/26 | 8:10am | 2-1L | Gas | N | X | X | X | X | | |
| -09 | CV-1532A | 05/11/26 | 8:15am | 2-1L | Gas | N | X | X | X | X | | |
| -10 | CV-1535 | 05/11/26 | 8:25am | 2-1L | Gas | N | X | X | X | X | | |

| | | | |
|---|---|---|---|
| AUTHORIZATION TO PERFORM WORK | COMPANY | 05/11/26 9:11am | DATE/TIME |
| SAMPLED BY: Erik Navarro | COMPANY 05/11/26 9:11am | | DATE/TIME |
| RELINQUISHED BY: Erik Navarro | DATE/TIME 5/11/2026 10:27 | RECEIVED BY: Juan G. | DATE/TIME 5-11-26 10:27 |
| RELINQUISHED BY: Juan Gutierrez | DATE/TIME 5-11-26 11:40 | RECEIVED BY: [signature] | DATE/TIME 5/11/26 11:40 |
| RELINQUISHED BY | DATE/TIME | RECEIVED BY | DATE/TIME |

**METHOD OF TRANSPORT (circle one):** Walk-In FedEx UPS **Courier** ATLI Other_____

**COMMENTS**
Report full list of TO-15 compounds
Raw landfill gas samples
**FLAMMABLE**

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/11/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | T051102-03 | | T051102-06 | | T051102-08 | | T051102-09 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2350 | | CV-1902A | | CV-2002 | | CV-1532A | |
| Date/Time Sampled: | 5/11/26 7:40 | | 5/11/26 7:55 | | 5/11/26 8:10 | | 5/11/26 8:15 | |
| Date/Time Analyzed: | 5/11/26 18:36 | | 5/11/26 19:14 | | 5/11/26 19:52 | | 5/11/26 20:30 | |
| QC Batch No.: | 260511MS2A1 | | 260511MS2A1 | | 260511MS2A1 | | 260511MS2A1 | |
| Analyst Initials: | VM/GD | | VM/GD | | VM/GD | | VM/GD | |
| Dilution Factor: | 9,000 | | 8,800 | | 4,000 | | 10,000 | |
| ANALYTE | Result ppbv | RL ppbv | Result ppbv | RL ppbv | Result ppbv | RL ppbv | Result ppbv | RL ppbv |
| Dichlorodifluoromethane (12) | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| Chloromethane | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| 1,2-Cl-1,1,2,2-F ethane (114) | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| Vinyl Chloride | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| Bromomethane | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| Chloroethane | ND | 45,000 | ND | 44,000 | ND | 20,000 | ND | 50,000 |
| Trichlorofluoromethane (11) | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| 1,1-Dichloroethene | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| Carbon Disulfide | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| 1,1,2-Cl 1,2,2-F ethane (113) | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| Acetone | 280,000 | 45,000 | 910,000 | 44,000 | 130,000 | 20,000 | 530,000 | 50,000 |
| Methylene Chloride | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| t-1,2-Dichloroethene | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| 1,1-Dichloroethane | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| Vinyl Acetate | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| c-1,2-Dichloroethene | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| 2-Butanone | 210,000 | 45,000 | 630,000 | 44,000 | 110,000 | 20,000 | 390,000 | 50,000 |
| t-Butyl Methyl Ether (MTBE) | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| Chloroform | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| 1,1,1-Trichloroethane | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| Carbon Tetrachloride | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| Benzene | 290,000 | 9,000 | 160,000 | 8,800 | 73,000 | 4,000 | 220,000 | 10,000 |
| 1,2-Dichloroethane | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| Trichloroethene | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| 1,2-Dichloropropane | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| Bromodichloromethane | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| c-1,3-Dichloropropene | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| 4-Methyl-2-Pentanone | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| Toluene | 10,000 | 9,000 | 8,900 | 8,800 | ND | 4,000 | 10,000 | 10,000 |
| t-1,3-Dichloropropene | ND | 18,000 | ND | 18,000 | ND | 8,000 | ND | 20,000 |
| 1,1,2-Trichloroethane | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| Tetrachloroethene | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| 2-Hexanone | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| Dibromochloromethane | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/11/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | T051102-03 | | T051102-06 | | T051102-08 | | T051102-09 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2350 | | CV-1902A | | CV-2002 | | CV-1532A | |
| Date/Time Sampled: | 5/11/26 7:40 | | 5/11/26 7:55 | | 5/11/26 8:10 | | 5/11/26 8:15 | |
| Date/Time Analyzed: | 5/11/26 18:36 | | 5/11/26 19:14 | | 5/11/26 19:52 | | 5/11/26 20:30 | |
| QC Batch No.: | 260511MS2A1 | | 260511MS2A1 | | 260511MS2A1 | | 260511MS2A1 | |
| Analyst Initials: | VM/GD | | VM/GD | | VM/GD | | VM/GD | |
| Dilution Factor: | 9,000 | | 8,800 | | 4,000 | | 10,000 | |
| ANALYTE | Result ppbv | RL ppbv | Result ppbv | RL ppbv | Result ppbv | RL ppbv | Result ppbv | RL ppbv |
| 1,2-Dibromoethane | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| Chlorobenzene | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| Ethylbenzene | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| p,&m-Xylene | ND | 18,000 | ND | 18,000 | ND | 8,000 | ND | 20,000 |
| o-Xylene | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| Styrene | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| Bromoform | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| 1,1,2,2-Tetrachloroethane | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| Benzyl Chloride | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| 4-Ethyl Toluene | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| 1,3,5-Trimethylbenzene | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| 1,2,4-Trimethylbenzene | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| 1,3-Dichlorobenzene | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| 1,4-Dichlorobenzene | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| 1,2-Dichlorobenzene | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| 1,2,4-Trichlorobenzene | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| Hexachlorobutadiene | ND | 9,000 | ND | 8,800 | ND | 4,000 | ND | 10,000 |
| 1,3-Butadiene | ND | 45,000 | ND | 44,000 | ND | 20,000 | ND | 50,000 |
| Isopropanol | 220,000 | 45,000 | 190,000 | 44,000 | 200,000 | 20,000 | 210,000 | 50,000 |
| n-Hexane | ND | 45,000 | ND | 44,000 | ND | 20,000 | ND | 50,000 |
| Ethyl Acetate | ND | 45,000 | ND | 44,000 | ND | 20,000 | ND | 50,000 |
| Tetrahydrofuran | 280,000 | 45,000 | 370,000 | 44,000 | 85,000 | 20,000 | 260,000 | 50,000 |
| Cyclohexane | ND | 45,000 | ND | 44,000 | ND | 20,000 | ND | 50,000 |
| Heptane | ND | 45,000 | ND | 44,000 | ND | 20,000 | ND | 50,000 |
| 1,4-Dioxane | ND | 45,000 | ND | 44,000 | ND | 20,000 | ND | 50,000 |
| | | | | | | | | |

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 5/26/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/11/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | T051102-10 |
|---|---|
| Client Sample I.D.: | CV-1535 |
| Date/Time Sampled: | 5/11/26 8:25 |
| Date/Time Analyzed: | 5/11/26 21:08 |
| QC Batch No.: | 260511MS2A1 |
| Analyst Initials: | VM/GD |
| Dilution Factor: | 160 |

| ANALYTE | Result ppbv | RL ppbv |
|---|---|---|
| Dichlorodifluoromethane (12) | ND | 160 |
| Chloromethane | 340 | 160 |
| 1,2-Cl-1,1,2,2-F ethane (114) | ND | 160 |
| Vinyl Chloride | ND | 160 |
| Bromomethane | ND | 160 |
| Chloroethane | ND | 800 |
| Trichlorofluoromethane (11) | ND | 160 |
| 1,1-Dichloroethene | ND | 160 |
| Carbon Disulfide | 380 | 160 |
| 1,1,2-Cl 1,2,2-F ethane (113) | ND | 160 |
| Acetone | 69,000 E | 800 |
| Methylene Chloride | ND | 160 |
| t-1,2-Dichloroethene | ND | 160 |
| 1,1-Dichloroethane | ND | 160 |
| Vinyl Acetate | ND | 160 |
| c-1,2-Dichloroethene | ND | 160 |
| 2-Butanone | 100,000 E | 800 |
| t-Butyl Methyl Ether (MTBE) | 580 | 160 |
| Chloroform | ND | 160 |
| 1,1,1-Trichloroethane | ND | 160 |
| Carbon Tetrachloride | ND | 160 |
| Benzene | 43,000 E | 160 |
| 1,2-Dichloroethane | ND | 160 |
| Trichloroethene | ND | 160 |
| 1,2-Dichloropropane | ND | 160 |
| Bromodichloromethane | ND | 160 |
| c-1,3-Dichloropropene | ND | 160 |
| 4-Methyl-2-Pentanone | 4,300 | 160 |
| Toluene | 4,700 | 160 |
| t-1,3-Dichloropropene | ND | 320 |
| 1,1,2-Trichloroethane | ND | 160 |
| Tetrachloroethene | ND | 160 |
| 2-Hexanone | 780 | 160 |
| Dibromochloromethane | ND | 160 |

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/11/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | T051102-10 |
|---|---|
| Client Sample I.D.: | CV-1535 |
| Date/Time Sampled: | 5/11/26 8:25 |
| Date/Time Analyzed: | 5/11/26 21:08 |
| QC Batch No.: | 260511MS2A1 |
| Analyst Initials: | VM/GD |
| Dilution Factor: | 160 |

| ANALYTE | Result ppbv | RL ppbv |
|---|---|---|
| 1,2-Dibromoethane | ND | 160 |
| Chlorobenzene | ND | 160 |
| Ethylbenzene | 930 | 160 |
| p,&m-Xylene | 560 | 320 |
| o-Xylene | 170 | 160 |
| Styrene | ND | 160 |
| Bromoform | ND | 160 |
| 1,1,2,2-Tetrachloroethane | ND | 160 |
| Benzyl Chloride | ND | 160 |
| 4-Ethyl Toluene | ND | 160 |
| 1,3,5-Trimethylbenzene | ND | 160 |
| 1,2,4-Trimethylbenzene | ND | 160 |
| 1,3-Dichlorobenzene | ND | 160 |
| 1,4-Dichlorobenzene | ND | 160 |
| 1,2-Dichlorobenzene | ND | 160 |
| 1,2,4-Trichlorobenzene | ND | 160 |
| Hexachlorobutadiene | ND | 160 |
| 1,3-Butadiene | 1,800 | 800 |
| Isopropanol | 71,000 E | 800 |
| n-Hexane | 1,900 | 800 |
| Ethyl Acetate | 10,000 | 800 |
| Tetrahydrofuran | 91,000 E | 800 |
| Cyclohexane | 1,300 | 800 |
| Heptane | 7,300 | 800 |
| 1,4-Dioxane | 3,500 | 800 |

RL = Reporting Limit
ND = Not Detected (below RL)
E = Estimated. Result exceeded the upper calibration range

Reviewed/Approved By: _____ Date 5/26/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/11/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | METHOD BLANK | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | -- | | | | | | | |
| Date/Time Sampled: | -- | | | | | | | |
| Date/Time Analyzed: | 5/11/26 13:18 | | | | | | | |
| QC Batch No.: | 260511MS2A1 | | | | | | | |
| Analyst Initials: | VM/GD | | | | | | | |
| Dilution Factor: | 0.20 | | | | | | | |

| ANALYTE | Result ppbv | RL ppbv | | | | | | |
|---|---|---|---|---|---|---|---|---|
| Dichlorodifluoromethane (12) | ND | 0.20 | | | | | | |
| Chloromethane | ND | 0.20 | | | | | | |
| 1,2-Cl-1,1,2,2-F ethane (114) | ND | 0.20 | | | | | | |
| Vinyl Chloride | ND | 0.20 | | | | | | |
| Bromomethane | ND | 0.20 | | | | | | |
| Chloroethane | ND | 1.0 | | | | | | |
| Trichlorofluoromethane (11) | ND | 0.20 | | | | | | |
| 1,1-Dichloroethene | ND | 0.20 | | | | | | |
| Carbon Disulfide | ND | 0.20 | | | | | | |
| 1,1,2-Cl 1,2,2-F ethane (113) | ND | 0.20 | | | | | | |
| Acetone | ND | 1.0 | | | | | | |
| Methylene Chloride | ND | 0.20 | | | | | | |
| t-1,2-Dichloroethene | ND | 0.20 | | | | | | |
| 1,1-Dichloroethane | ND | 0.20 | | | | | | |
| Vinyl Acetate | ND | 0.20 | | | | | | |
| c-1,2-Dichloroethene | ND | 0.20 | | | | | | |
| 2-Butanone | ND | 1.0 | | | | | | |
| t-Butyl Methyl Ether (MTBE) | ND | 0.20 | | | | | | |
| Chloroform | ND | 0.20 | | | | | | |
| 1,1,1-Trichloroethane | ND | 0.20 | | | | | | |
| Carbon Tetrachloride | ND | 0.20 | | | | | | |
| Benzene | ND | 0.20 | | | | | | |
| 1,2-Dichloroethane | ND | 0.20 | | | | | | |
| Trichloroethene | ND | 0.20 | | | | | | |
| 1,2-Dichloropropane | ND | 0.20 | | | | | | |
| Bromodichloromethane | ND | 0.20 | | | | | | |
| c-1,3-Dichloropropene | ND | 0.20 | | | | | | |
| 4-Methyl-2-Pentanone | ND | 0.20 | | | | | | |
| Toluene | ND | 0.20 | | | | | | |
| t-1,3-Dichloropropene | ND | 0.40 | | | | | | |
| 1,1,2-Trichloroethane | ND | 0.20 | | | | | | |
| Tetrachloroethene | ND | 0.20 | | | | | | |
| 2-Hexanone | ND | 0.20 | | | | | | |
| Dibromochloromethane | ND | 0.20 | | | | | | |

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/11/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | METHOD BLANK |
|---|---|
| Client Sample I.D.: | -- |
| Date/Time Sampled: | -- |
| Date/Time Analyzed: | 5/11/26 13:18 |
| QC Batch No.: | 260511MS2A1 |
| Analyst Initials: | VM/GD |
| Dilution Factor: | 0.20 |

| ANALYTE | Result ppbv | RL ppbv |
|---|---|---|
| 1,2-Dibromoethane | ND | 0.20 |
| Chlorobenzene | ND | 0.20 |
| Ethylbenzene | ND | 0.20 |
| p,&m-Xylene | ND | 0.40 |
| o-Xylene | ND | 0.20 |
| Styrene | ND | 0.20 |
| Bromoform | ND | 0.20 |
| 1,1,2,2-Tetrachloroethane | ND | 0.20 |
| Benzyl Chloride | ND | 0.20 |
| 4-Ethyl Toluene | ND | 0.20 |
| 1,3,5-Trimethylbenzene | ND | 0.20 |
| 1,2,4-Trimethylbenzene | ND | 0.20 |
| 1,3-Dichlorobenzene | ND | 0.20 |
| 1,4-Dichlorobenzene | ND | 0.20 |
| 1,2-Dichlorobenzene | ND | 0.20 |
| 1,2,4-Trichlorobenzene | ND | 0.20 |
| Hexachlorobutadiene | ND | 0.20 |
| 1,3-Butadiene | ND | 1.0 |
| Isopropanol | ND | 1.0 |
| n-Hexane | ND | 1.0 |
| Ethyl Acetate | ND | 1.0 |
| Tetrahydrofuran | ND | 1.0 |
| Cyclohexane | ND | 1.0 |
| Heptane | ND | 1.0 |
| 1,4-Dioxane | ND | 1.0 |

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 5/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

# LCS/LCSD Recovery and RPD Summary Report

## QC Batch #: 260511MS2A1

**Matrix: Air**

**Reporting Units: ppbv**

**EPA Method TO-15**
**LABORATORY CONTROL SAMPLE SUMMARY**

| Lab No.: | METHOD BLANK | | | LCS | | LCSD | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Date/Time Analyzed: | 5/11/26 13:18 | | | 5/11/26 11:26 | | 5/11/26 12:03 | | | | | |
| Analyst Initials: | VM/GD | | | VM/GD | | VM/GD | | | | | |
| Dilution Factor: | 0.20 | | | 1.0 | | 1.0 | | | | | |
| **ANALYTE** | **Result ppbv** | **RL ppbv** | **AMT. ppbv** | **Result ppbv** | **% Rec.** | **Result ppbv** | **% Rec.** | **RPD** | **Low %Rec** | **High %Rec** | **Max. RPD** |
| 1,1-Dichloroethene | ND | 0.20 | 10 | 11.6 | 116 | 11.8 | 118 | 1.7 | 70 | 130 | 30 |
| Methylene Chloride | ND | 0.20 | 10 | 12.0 | 120 | 12.0 | 120 | 0.7 | 70 | 130 | 30 |
| Trichloroethene | ND | 0.20 | 10 | 11.6 | 116 | 11.8 | 118 | 1.4 | 70 | 130 | 30 |
| Toluene | ND | 0.20 | 10 | 12.0 | 120 | 11.9 | 119 | 0.2 | 70 | 130 | 30 |
| 1,1,2,2-Tetrachloroethane | ND | 0.20 | 10 | 11.4 | 114 | 11.4 | 114 | 0.1 | 70 | 130 | 30 |
| | | | | | | | | | | | |

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date:** 5/12/26
**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/11/26
**Matrix:** Air
**Reporting Units:** ppmv

## EPA ALT-144 (CO by FID)

| Lab No.: | T051102-01 | | T051102-02 | | T051102-03 | | T051102-04 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2345 | | CV-2344 | | CV-2350 | | CV-24066 | |
| Date/Time Sampled: | 5/11/26 7:30 | | 5/11/26 7:35 | | 5/11/26 7:40 | | 5/11/26 7:45 | |
| Date/Time Analyzed: | 5/11/26 16:26 | | 5/11/26 16:40 | | 5/11/26 16:55 | | 5/11/26 17:09 | |
| QC Batch No.: | 260511GC8A3 | | 260511GC8A3 | | 260511GC8A3 | | 260511GC8A3 | |
| Analyst Initials: | KD | | KD | | KD | | KD | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | 1.0 | |
| ANALYTE | Result ppmv | RL ppmv | Result ppmv | RL ppmv | Result ppmv | RL ppmv | Result ppmv | RL ppmv |
| Carbon Monoxide | 580 | 10 | 2,900 | 10 | 3,700 | 10 | 390 | 10 |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-20-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report



SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com
Member of the SGS Group (SGS SA)

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/11/26
**Matrix:** Air
**Reporting Units:** ppmv

## EPA ALT-144 (CO by FID)

| Lab No.: | T051102-05 | | T051102-06 | | T051102-07 | | T051102-08 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2341 | | CV-1902A | | CV-2337 | | CV-2002 | |
| Date/Time Sampled: | 5/11/26 7:50 | | 5/11/26 7:55 | | 5/11/26 8:05 | | 5/11/26 8:10 | |
| Date/Time Analyzed: | 5/11/26 17:24 | | 5/11/26 17:38 | | 5/11/26 17:53 | | 5/11/26 18:07 | |
| QC Batch No.: | 260511GC8A3 | | 260511GC8A3 | | 260511GC8A3 | | 260511GC8A3 | |
| Analyst Initials: | KD | | KD | | KD | | KD | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | 1.0 | |
| ANALYTE | Result ppmv | RL ppmv | Result ppmv | RL ppmv | Result ppmv | RL ppmv | Result ppmv | RL ppmv |
| Carbon Monoxide | 850 | 10 | 930 | 10 | 3,500 | 10 | 860 | 10 |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-20-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/11/26
**Matrix:** Air
**Reporting Units:** ppmv

## EPA ALT-144 (CO by FID)

| Lab No.: | T051102-09 | | T051102-10 | | | | | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-1532A | | CV-1535 | | | | | |
| Date/Time Sampled: | 5/11/26 8:15 | | 5/11/26 8:25 | | | | | |
| Date/Time Analyzed: | 5/11/26 18:22 | | 5/11/26 18:36 | | | | | |
| QC Batch No.: | 260511GC8A3 | | 260511GC8A3 | | | | | |
| Analyst Initials: | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | 1.0 | | | | | |
| ANALYTE | Result ppmv | RL ppmv | Result ppmv | RL ppmv | | | | |
| Carbon Monoxide | 580 | 10 | 100 | 10 | | | | |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-20-26
**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**QC Batch No:** 260511GC8A3
**Matrix:** Air
**Reporting Units:** ppmv

## EPA ALT-144 (CO by FID)
## LABORATORY CONTROL SAMPLE SUMMARY

| Lab No.: | METHOD BLANK | | | LCS | | LCSD | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Date Analyzed: | 5/11/26 15:42 | | | 5/11/26 15:13 | | 5/11/26 15:28 | | | | | |
| Analyst Initials: | KD | | | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | | 1.0 | | 1.0 | | | Limits | | |
| ANALYTE | Result ppmv | RL ppmv | SPIKE AMT. ppmv | Result ppmv | % Rec. | Result ppmv | % Rec. | RPD % | Low %Rec | High %Rec | Max. RPD |
| Carbon Monoxide | ND | 10 | 1,010 | 1,050 | 104 | 1,040 | 103 | 0.8 | 70 | 130 | 30 |
| | | | | | | | | | | | |

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-20-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/11/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T051102-01 | | | T051102-02 | | | T051102-03 | | | T051102-04 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2345 | | | CV-2344 | | | CV-2350 | | | CV-24066 | | |
| Date/Time Sampled: | 5/11/26 7:30 | | | 5/11/26 7:35 | | | 5/11/26 7:40 | | | 5/11/26 7:45 | | |
| Date/Time Analyzed: | 5/11/26 16:26 | | | 5/11/26 16:40 | | | 5/11/26 16:55 | | | 5/11/26 17:09 | | |
| QC Batch No.: | 260511GC8A3 | | | 260511GC8A3 | | | 260511GC8A3 | | | 260511GC8A3 | | |
| Analyst Initials: | KD | | | KD | | | KD | | | KD | | |
| Dilution Factor: | 1.0 | | | 1.0 | | | 1.0 | | | 1.0 | | |
| ANALYTE | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v |
| Hydrogen | 2.8 | 1.0 | 0.059 | 16 | 1.0 | 0.059 | 17 | 1.0 | 0.059 | 3.2 | 1.0 | 0.059 |

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/11/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T051102-05 | | | T051102-06 | | | T051102-07 | | | T051102-08 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2341 | | | CV-1902A | | | CV-2337 | | | CV-2002 | | |
| Date/Time Sampled: | 5/11/26 7:50 | | | 5/11/26 7:55 | | | 5/11/26 8:05 | | | 5/11/26 8:10 | | |
| Date/Time Analyzed: | 5/11/26 17:24 | | | 5/11/26 17:38 | | | 5/11/26 17:53 | | | 5/11/26 18:07 | | |
| QC Batch No.: | 260511GC8A3 | | | 260511GC8A3 | | | 260511GC8A3 | | | 260511GC8A3 | | |
| Analyst Initials: | KD | | | KD | | | KD | | | KD | | |
| Dilution Factor: | 1.0 | | | 1.0 | | | 1.0 | | | 1.0 | | |
| ANALYTE | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v |
| Hydrogen | 9.4 | 1.0 | 0.059 | 19 | 1.0 | 0.059 | 13 | 1.0 | 0.059 | 8.3 | 1.0 | 0.059 |

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/11/26
**Matrix:** Air
**Reporting Units:** % v/v

**ASTM D1946**

| Lab No.: | T051102-09 | | | T051102-10 | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-1532A | | | CV-1535 | | | | | | | | |
| Date/Time Sampled: | 5/11/26 8:15 | | | 5/11/26 8:25 | | | | | | | | |
| Date/Time Analyzed: | 5/11/26 18:22 | | | 5/11/26 18:36 | | | | | | | | |
| QC Batch No.: | 260511GC8A3 | | | 260511GC8A3 | | | | | | | | |
| Analyst Initials: | KD | | | KD | | | | | | | | |
| Dilution Factor: | 1.0 | | | 1.0 | | | | | | | | |
| ANALYTE | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | | | | | | |
| Hydrogen | 6.1 | 1.0 | 0.059 | 0.98 J | 1.0 | 0.059 | | | | | | |

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**QC Batch No:** 260511GC8A3
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946
## LABORATORY CONTROL SAMPLE SUMMARY

| Lab No.: | METHOD BLANK | | | | LCS | | LCSD | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Date Analyzed: | 5/11/26 15:42 | | | | 5/11/26 15:13 | | 5/11/26 15:28 | | | | | |
| Analyst Initials: | KD | | | | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | | | 1.0 | | 1.0 | | | Limits | | |
| ANALYTE | Result % v/v | RL % v/v | MDL % v/v | SPIKE AMT. % v/v | Result % v/v | % Rec. | Result % v/v | % Rec. | RPD % | Low %Rec | High %Rec | Max. RPD |
| Hydrogen | ND | 1.0 | 0.059 | 5.0 | 4.22 | 85 | 4.12 | 83 | 2.3 | 70 | 130 | 30 |

**MDL = Method Detection Limit**
**ND= Not Detected (below MDL)**
**RL = Reporting Limit**
**J = Trace amount. Analyte concentration between RL and MDL.**

**Reviewed/Approved By:** _____ **Date** 5-20-26
**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/11/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T051102-01 | | T051102-02 | | T051102-03 | | T051102-04 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2345 | | CV-2344 | | CV-2350 | | CV-24066 | |
| Date/Time Sampled: | 5/11/26 7:30 | | 5/11/26 7:35 | | 5/11/26 7:40 | | 5/11/26 7:45 | |
| Date/Time Analyzed: | 5/11/26 16:26 | | 5/11/26 16:40 | | 5/11/26 16:55 | | 5/11/26 17:09 | |
| QC Batch No.: | 260511GC8A3 | | 260511GC8A3 | | 260511GC8A3 | | 260511GC8A3 | |
| Analyst Initials: | KD | | KD | | KD | | KD | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | 1.0 | |
| ANALYTE | Result % v/v | RL % v/v | Result % v/v | RL % v/v | Result % v/v | RL % v/v | Result % v/v | RL % v/v |
| Carbon Dioxide | 75 | 0.010 | 76 | 0.010 | 75 | 0.010 | 49 | 0.010 |
| Oxygen/Argon | 1.4 | 0.50 | 1.3 | 0.50 | ND | 0.50 | 0.73 | 0.50 |
| Nitrogen | 5.9 | 1.0 | 4.6 | 1.0 | 1.5 | 1.0 | 21 | 1.0 |
| Methane | 14 | 0.0010 | 1.0 | 0.0010 | 3.9 | 0.0010 | 25 | 0.0010 |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-20-26
**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/11/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T051102-05 | | T051102-06 | | T051102-07 | | T051102-08 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2341 | | CV-1902A | | CV-2337 | | CV-2002 | |
| Date/Time Sampled: | 5/11/26 7:50 | | 5/11/26 7:55 | | 5/11/26 8:05 | | 5/11/26 8:10 | |
| Date/Time Analyzed: | 5/11/26 17:24 | | 5/11/26 17:38 | | 5/11/26 17:53 | | 5/11/26 18:07 | |
| QC Batch No.: | 260511GC8A3 | | 260511GC8A3 | | 260511GC8A3 | | 260511GC8A3 | |
| Analyst Initials: | KD | | KD | | KD | | KD | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | 1.0 | |
| **ANALYTE** | **Result % v/v** | **RL % v/v** | **Result % v/v** | **RL % v/v** | **Result % v/v** | **RL % v/v** | **Result % v/v** | **RL % v/v** |
| Carbon Dioxide | 45 | 0.010 | 74 | 0.010 | 72 | 0.010 | 75 | 0.010 |
| Oxygen/Argon | 8.7 | 0.50 | ND | 0.50 | 2.0 | 0.50 | 0.93 | 0.50 |
| Nitrogen | 33 | 1.0 | 1.3 | 1.0 | 7.3 | 1.0 | 3.4 | 1.0 |
| Methane | 3.7 | 0.0010 | 1.9 | 0.0010 | 4.1 | 0.0010 | 11 | 0.0010 |
| | | | | | | | | |

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 5-20-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/11/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T051102-09 | | T051102-10 | | | | | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-1532A | | CV-1535 | | | | | |
| Date/Time Sampled: | 5/11/26 8:15 | | 5/11/26 8:25 | | | | | |
| Date/Time Analyzed: | 5/11/26 18:22 | | 5/11/26 18:36 | | | | | |
| QC Batch No.: | 260511GC8A3 | | 260511GC8A3 | | | | | |
| Analyst Initials: | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | 1.0 | | | | | |
| **ANALYTE** | **Result % v/v** | **RL % v/v** | **Result % v/v** | **RL % v/v** | | | | |
| Carbon Dioxide | 75 | 0.010 | 51 | 0.010 | | | | |
| Oxygen/Argon | ND | 0.50 | ND | 0.50 | | | | |
| Nitrogen | 1.8 | 1.0 | 1.7 | 1.0 | | | | |
| Methane | 15 | 0.0010 | 46 | 0.0010 | | | | |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-20-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report



SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com
Member of the SGS Group (SGS SA)

**QC Batch No:** 260511GC8A3
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946
## LABORATORY CONTROL SAMPLE SUMMARY

| Lab No.: | METHOD BLANK | | | LCS | | LCSD | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Date Analyzed: | 5/11/26 15:42 | | | 5/11/26 15:13 | | 5/11/26 15:28 | | | | | |
| Analyst Initials: | KD | | | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | | 1.0 | | 1.0 | | | Limits | | |
| ANALYTE | Result % v/v | RL % v/v | SPIKE AMT. % v/v | Result % v/v | % Rec. | Result % v/v | % Rec. | RPD % | Low %Rec | High %Rec | Max. RPD |
| Carbon Dioxide | ND | 0.010 | 10 | 9.12 | 91 | 9.09 | 91 | 0.4 | 70 | 130 | 30 |
| Oxygen/Argon | ND | 0.50 | 15 | 15.0 | 100 | 15.0 | 100 | 0.0 | 70 | 130 | 30 |
| Nitrogen | ND | 1.0 | 70 | 71.5 | 102 | 71.4 | 102 | 0.1 | 70 | 130 | 30 |
| Methane | ND | 0.0010 | 0.10 | 0.102 | 101 | 0.101 | 100 | 0.5 | 70 | 130 | 30 |
| | | | | | | | | | | | |

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-20-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175
TX Cert T104704450-14-6
EPA Methods TO14A, TO15
ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

May 31, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

## LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T051203-01/10

Enclosed are the results for sample(s) received 5/12/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

# CHAIN OF CUSTODY RECORD

**TURNAROUND TIME**
Standard ■ 48 hours ☐
Same Day ☐ 72 hours ☐
24 hours ☐ 96 hours ☐
Other:

**DELIVERABLES**
EDD ■
EDF ☐
Level 3 ☐
Level 4 ☐

**PAGE:** 1 OF

Condition upon receipt:
Sealed Yes ☐ No ☐
Intact Yes ☐ No ☐
Chilled _____ deg C

| | |
|---|---|
| **Project No.:** | 07224200.24 Task 1 |
| **Project Name:** | Chiquita Canyon Landfill |
| **Report To:** | Cornelius Fong |
| **Company:** | SCS Engineers |
| **Street:** | 3900 Kilroy Airport Way, Suite 300 |
| **City/State/Zip:** | Long Beach, CA 90806-6816 |
| **Phone& Fax:** | 562-743-7895 |
| **e-mail:** | cfong@scsengineers.com |

**BILLING**
**P.O. No.:**
**Bill to:**
[redacted]@scsengineers.com
3900 Kilroy Airport Way, Suite 300
Long Beach, CA 90806-6816

**ANALYSIS REQUEST**

| LAB USE ONLY | SAMPLE IDENTIFICATION | SAMPLE DATE | SAMPLE TIME | CONTAINER QTY/TYPE | MATRIX | PRESERVATION | CH4, CO2, O2, N2 ASTM D1946 | Carbon Monoxide EPA ALT-144 | Hydrogen ASTM D1946 | VOCs EPA TO-15 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| T051203-01 | CV-2353 | 05/12/26 | 7:35AM | 1L | Gas | N | X | X | X | | | |
| -02 | H-2165W | 05/12/26 | 7:45AM | 2-1L | Gas | N | X | X | X | X | | |
| -03 | H-2273W | 05/12/26 | 7:50AM | 2-1L | Gas | N | X | X | X | X | | |
| -04 | CV-2314 | 05/12/26 | 8:05AM | 1L | Gas | N | X | X | X | | | |
| -05 | CV-2305 | 05/12/26 | 8:10AM | 1L | Gas | N | X | X | X | | | |
| -06 | CV-24064 | 05/12/26 | 8:15AM | 1L | Gas | N | X | X | X | | | |
| -07 | CV-24063 | 05/12/26 | 8:20AM | 1L | Gas | N | X | X | X | | | |
| -08 | CV-2303 | 05/12/26 | 8:30AM | 2-1L | Gas | N | X | X | X | X | | |
| -09 | CV-24017 | 05/12/26 | 8:35AM | 2-1L | Gas | N | X | X | X | X | | |
| -10 | CV-24007 | 05/12/26 | 8:40AM | 2-1L | Gas | N | X | X | X | X | | |

| | | | |
|---|---|---|---|
| AUTHORIZATION TO PERFORM WORK | | COMPANY SCS | DATE/TIME 5-12-26 9:08 |
| SAMPLED BY | ERIK NAVARRO | COMPANY SCS | DATE/TIME 5-12-26 9:08 |
| RELINQUISHED BY | ERIK NAVARRO | DATE/TIME 5-12-26 9:08 | RECEIVED BY [signature] DATE/TIME 5/12/26 9:08 |
| RELINQUISHED BY | [signature] | DATE/TIME 5/12/26 11:58 | RECEIVED BY [signature] DATE/TIME 5/12/26 11:58 |
| RELINQUISHED BY | | DATE/TIME | RECEIVED BY DATE/TIME |

**METHOD OF TRANSPORT (circle one):** Walk-In FedEx UPS **Courier** ATLI Other_____

**COMMENTS**
Report full list of TO-15 compounds
Raw landfill gas samples
**FLAMMABLE**

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/12/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | T051203-02 | | T051203-03 | | T051203-08 | | T051203-09 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | H-2165W | | H-2273W | | CV-2303 | | CV-24017 | |
| Date/Time Sampled: | 5/12/26 7:45 | | 5/12/26 7:50 | | 5/12/26 8:30 | | 5/12/26 8:35 | |
| Date/Time Analyzed: | 5/12/26 18:03 | | 5/12/26 18:41 | | 5/12/26 19:19 | | 5/12/26 19:58 | |
| QC Batch No.: | 260512MS2A1 | | 260512MS2A1 | | 260512MS2A1 | | 260512MS2A1 | |
| Analyst Initials: | VM | | VM | | VM | | VM | |
| Dilution Factor: | 10,000 | | 2,000 | | 10,000 | | 10,000 | |
| ANALYTE | Result ppbv | RL ppbv | Result ppbv | RL ppbv | Result ppbv | RL ppbv | Result ppbv | RL ppbv |
| Dichlorodifluoromethane (12) | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| Chloromethane | ND | 10,000 | ND | 2,000 | ND | 10,000 | **12,000** | 10,000 |
| 1,2-Cl-1,1,2,2-F ethane (114) | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| Vinyl Chloride | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| Bromomethane | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| Chloroethane | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| Trichlorofluoromethane (11) | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| 1,1-Dichloroethene | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| Carbon Disulfide | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| 1,1,2-Cl 1,2,2-F ethane (113) | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| Acetone | **350,000** | 10,000 | **200,000** | 2,000 | **1,200,000 E** | 10,000 | **950,000** | 10,000 |
| Methylene Chloride | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| t-1,2-Dichloroethene | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| 1,1-Dichloroethane | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| Vinyl Acetate | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| c-1,2-Dichloroethene | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| 2-Butanone | **260,000** | 20,000 | **200,000** | 4,000 | **1,100,000** | 20,000 | **700,000** | 20,000 |
| t-Butyl Methyl Ether (MTBE) | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| Chloroform | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| 1,1,1-Trichloroethane | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| Carbon Tetrachloride | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| Benzene | **120,000** | 10,000 | **98,000** | 2,000 | **290,000** | 10,000 | **210,000** | 10,000 |
| 1,2-Dichloroethane | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| Trichloroethene | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| 1,2-Dichloropropane | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| Bromodichloromethane | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| c-1,3-Dichloropropene | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| 4-Methyl-2-Pentanone | ND | 10,000 | **4,600** | 2,000 | **20,000** | 10,000 | ND | 10,000 |
| Toluene | ND | 10,000 | **4,400** | 2,000 | **26,000** | 10,000 | **10,000** | 10,000 |
| t-1,3-Dichloropropene | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| 1,1,2-Trichloroethane | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| Tetrachloroethene | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| 2-Hexanone | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| Dibromochloromethane | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/12/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | T051203-02 | | T051203-03 | | T051203-08 | | T051203-09 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | H-2165W | | H-2273W | | CV-2303 | | CV-24017 | |
| Date/Time Sampled: | 5/12/26 7:45 | | 5/12/26 7:50 | | 5/12/26 8:30 | | 5/12/26 8:35 | |
| Date/Time Analyzed: | 5/12/26 18:03 | | 5/12/26 18:41 | | 5/12/26 19:19 | | 5/12/26 19:58 | |
| QC Batch No.: | 260512MS2A1 | | 260512MS2A1 | | 260512MS2A1 | | 260512MS2A1 | |
| Analyst Initials: | VM | | VM | | VM | | VM | |
| Dilution Factor: | 10,000 | | 2,000 | | 10,000 | | 10,000 | |
| ANALYTE | Result ppbv | RL ppbv | Result ppbv | RL ppbv | Result ppbv | RL ppbv | Result ppbv | RL ppbv |
| 1,2-Dibromoethane | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| Chlorobenzene | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| Ethylbenzene | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| p,&m-Xylene | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| o-Xylene | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| Styrene | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| Bromoform | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| 1,1,2,2-Tetrachloroethane | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| Benzyl Chloride | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| 4-Ethyl Toluene | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| 1,3,5-Trimethylbenzene | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| 1,2,4-Trimethylbenzene | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| 1,3-Dichlorobenzene | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| 1,4-Dichlorobenzene | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| 1,2-Dichlorobenzene | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| 1,2,4-Trichlorobenzene | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| Hexachlorobutadiene | ND | 10,000 | ND | 2,000 | ND | 10,000 | ND | 10,000 |
| 1,3-Butadiene | ND | 50,000 | ND | 10,000 | ND | 50,000 | ND | 50,000 |
| Isopropanol | 140,000 | 50,000 | 110,000 | 10,000 | 160,000 | 50,000 | 150,000 | 50,000 |
| n-Hexane | ND | 50,000 | ND | 10,000 | ND | 50,000 | ND | 50,000 |
| Ethyl Acetate | ND | 50,000 | 21,000 | 10,000 | 98,000 | 50,000 | 62,000 | 50,000 |
| Tetrahydrofuran | 180,000 | 50,000 | 130,000 | 10,000 | 770,000 | 50,000 | 490,000 | 50,000 |
| Cyclohexane | ND | 50,000 | ND | 10,000 | ND | 50,000 | ND | 50,000 |
| Heptane | ND | 50,000 | ND | 10,000 | ND | 50,000 | ND | 50,000 |
| 1,4-Dioxane | ND | 50,000 | ND | 10,000 | ND | 50,000 | ND | 50,000 |
| | | | | | | | | |

RL = Reporting Limit
ND = Not Detected (below RL)
E = Estimated. Result exceeds the upper calibration limit

Reviewed/Approved By: _____ Date 5/31/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/12/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| | |
|---|---|
| Lab No.: | T051203-10 |
| Client Sample I.D.: | CV-24007 |
| Date/Time Sampled: | 5/12/26 8:40 |
| Date/Time Analyzed: | 5/12/26 20:36 |
| QC Batch No.: | 260512MS2A1 |
| Analyst Initials: | VM |
| Dilution Factor: | 10,000 |

| ANALYTE | Result ppbv | RL ppbv |
|---|---|---|
| Dichlorodifluoromethane (12) | ND | 10,000 |
| Chloromethane | ND | 10,000 |
| 1,2-Cl-1,1,2,2-F ethane (114) | ND | 10,000 |
| Vinyl Chloride | ND | 10,000 |
| Bromomethane | ND | 10,000 |
| Chloroethane | ND | 10,000 |
| Trichlorofluoromethane (11) | ND | 10,000 |
| 1,1-Dichloroethene | ND | 10,000 |
| Carbon Disulfide | ND | 10,000 |
| 1,1,2-Cl 1,2,2-F ethane (113) | ND | 10,000 |
| Acetone | 700,000 | 10,000 |
| Methylene Chloride | ND | 10,000 |
| t-1,2-Dichloroethene | ND | 10,000 |
| 1,1-Dichloroethane | ND | 10,000 |
| Vinyl Acetate | ND | 10,000 |
| c-1,2-Dichloroethene | ND | 10,000 |
| 2-Butanone | 510,000 | 20,000 |
| t-Butyl Methyl Ether (MTBE) | ND | 10,000 |
| Chloroform | ND | 10,000 |
| 1,1,1-Trichloroethane | ND | 10,000 |
| Carbon Tetrachloride | ND | 10,000 |
| Benzene | 270,000 | 10,000 |
| 1,2-Dichloroethane | ND | 10,000 |
| Trichloroethene | ND | 10,000 |
| 1,2-Dichloropropane | ND | 10,000 |
| Bromodichloromethane | ND | 10,000 |
| c-1,3-Dichloropropene | ND | 10,000 |
| 4-Methyl-2-Pentanone | ND | 10,000 |
| Toluene | 31,000 | 10,000 |
| t-1,3-Dichloropropene | ND | 10,000 |
| 1,1,2-Trichloroethane | ND | 10,000 |
| Tetrachloroethene | ND | 10,000 |
| 2-Hexanone | ND | 10,000 |
| Dibromochloromethane | ND | 10,000 |

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/12/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | T051203-10 |
|---|---|
| Client Sample I.D.: | CV-24007 |
| Date/Time Sampled: | 5/12/26 8:40 |
| Date/Time Analyzed: | 5/12/26 20:36 |
| QC Batch No.: | 260512MS2A1 |
| Analyst Initials: | VM |
| Dilution Factor: | 10,000 |

| ANALYTE | Result ppbv | RL ppbv |
|---|---|---|
| 1,2-Dibromoethane | ND | 10,000 |
| Chlorobenzene | ND | 10,000 |
| Ethylbenzene | ND | 10,000 |
| p,&m-Xylene | ND | 10,000 |
| o-Xylene | ND | 10,000 |
| Styrene | ND | 10,000 |
| Bromoform | ND | 10,000 |
| 1,1,2,2-Tetrachloroethane | ND | 10,000 |
| Benzyl Chloride | ND | 10,000 |
| 4-Ethyl Toluene | ND | 10,000 |
| 1,3,5-Trimethylbenzene | ND | 10,000 |
| 1,2,4-Trimethylbenzene | ND | 10,000 |
| 1,3-Dichlorobenzene | ND | 10,000 |
| 1,4-Dichlorobenzene | ND | 10,000 |
| 1,2-Dichlorobenzene | ND | 10,000 |
| 1,2,4-Trichlorobenzene | ND | 10,000 |
| Hexachlorobutadiene | ND | 10,000 |
| 1,3-Butadiene | ND | 50,000 |
| Isopropanol | 200,000 | 50,000 |
| n-Hexane | ND | 50,000 |
| Ethyl Acetate | 57,000 | 50,000 |
| Tetrahydrofuran | 560,000 | 50,000 |
| Cyclohexane | ND | 50,000 |
| Heptane | ND | 50,000 |
| 1,4-Dioxane | ND | 50,000 |

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ 5/31/26 Date _____
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/12/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | METHOD BLANK | | | |
|---|---|---|---|---|
| Client Sample I.D.: | -- | | | |
| Date/Time Sampled: | -- | | | |
| Date/Time Analyzed: | 5/12/26 17:25 | | | |
| QC Batch No.: | 260512MS2A1 | | | |
| Analyst Initials: | VM | | | |
| Dilution Factor: | 0.20 | | | |

| ANALYTE | Result ppbv | RL ppbv |
|---|---|---|
| Dichlorodifluoromethane (12) | ND | 0.20 |
| Chloromethane | ND | 0.20 |
| 1,2-Cl-1,1,2,2-F ethane (114) | ND | 0.20 |
| Vinyl Chloride | ND | 0.20 |
| Bromomethane | ND | 0.20 |
| Chloroethane | ND | 0.20 |
| Trichlorofluoromethane (11) | ND | 0.20 |
| 1,1-Dichloroethene | ND | 0.20 |
| Carbon Disulfide | ND | 0.20 |
| 1,1,2-Cl 1,2,2-F ethane (113) | ND | 0.20 |
| Acetone | ND | 0.20 |
| Methylene Chloride | ND | 0.20 |
| t-1,2-Dichloroethene | ND | 0.20 |
| 1,1-Dichloroethane | ND | 0.20 |
| Vinyl Acetate | ND | 0.20 |
| c-1,2-Dichloroethene | ND | 0.20 |
| 2-Butanone | ND | 0.40 |
| t-Butyl Methyl Ether (MTBE) | ND | 0.20 |
| Chloroform | ND | 0.20 |
| 1,1,1-Trichloroethane | ND | 0.20 |
| Carbon Tetrachloride | ND | 0.20 |
| Benzene | ND | 0.20 |
| 1,2-Dichloroethane | ND | 0.20 |
| Trichloroethene | ND | 0.20 |
| 1,2-Dichloropropane | ND | 0.20 |
| Bromodichloromethane | ND | 0.20 |
| c-1,3-Dichloropropene | ND | 0.20 |
| 4-Methyl-2-Pentanone | ND | 0.20 |
| Toluene | ND | 0.20 |
| t-1,3-Dichloropropene | ND | 0.20 |
| 1,1,2-Trichloroethane | ND | 0.20 |
| Tetrachloroethene | ND | 0.20 |
| 2-Hexanone | ND | 0.20 |
| Dibromochloromethane | ND | 0.20 |

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/12/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | METHOD BLANK |
|---|---|
| Client Sample I.D.: | -- |
| Date/Time Sampled: | -- |
| Date/Time Analyzed: | 5/12/26 17:25 |
| QC Batch No.: | 260512MS2A1 |
| Analyst Initials: | VM |
| Dilution Factor: | 0.20 |

| ANALYTE | Result ppbv | RL ppbv |
|---|---|---|
| 1,2-Dibromoethane | ND | 0.20 |
| Chlorobenzene | ND | 0.20 |
| Ethylbenzene | ND | 0.20 |
| p,&m-Xylene | ND | 0.20 |
| o-Xylene | ND | 0.20 |
| Styrene | ND | 0.20 |
| Bromoform | ND | 0.20 |
| 1,1,2,2-Tetrachloroethane | ND | 0.20 |
| Benzyl Chloride | ND | 0.20 |
| 4-Ethyl Toluene | ND | 0.20 |
| 1,3,5-Trimethylbenzene | ND | 0.20 |
| 1,2,4-Trimethylbenzene | ND | 0.20 |
| 1,3-Dichlorobenzene | ND | 0.20 |
| 1,4-Dichlorobenzene | ND | 0.20 |
| 1,2-Dichlorobenzene | ND | 0.20 |
| 1,2,4-Trichlorobenzene | ND | 0.20 |
| Hexachlorobutadiene | ND | 0.20 |
| 1,3-Butadiene | ND | 1.0 |
| Isopropanol | ND | 1.0 |
| n-Hexane | ND | 1.0 |
| Ethyl Acetate | ND | 1.0 |
| Tetrahydrofuran | ND | 1.0 |
| Cyclohexane | ND | 1.0 |
| Heptane | ND | 1.0 |
| 1,4-Dioxane | ND | 1.0 |

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 5/12/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

# LCS/LCSD Recovery and RPD Summary Report

## QC Batch #: 260512MS2A1

**Matrix: Air**

**Reporting Units: ppbv**

**EPA Method TO-15**
**LABORATORY CONTROL SAMPLE SUMMARY**

| Lab No.: | METHOD BLANK | | | LCS | | LCSD | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Date/Time Analyzed: | 5/12/26 17:25 | | | 5/12/26 12:58 | | 5/12/26 13:37 | | | | | |
| Analyst Initials: | VM/GD | | | VM/GD | | VM/GD | | | | | |
| Dilution Factor: | 0.20 | | | 1.0 | | 1.0 | | | | | |
| **ANALYTE** | **Result ppbv** | **RL ppbv** | **AMT. ppbv** | **Result ppbv** | **% Rec.** | **Result ppbv** | **% Rec.** | **RPD** | **Low %Rec** | **High %Rec** | **Max. RPD** |
| 1,1-Dichloroethene | ND | 0.20 | 10 | 11.8 | 118 | 11.3 | 113 | 4.0 | 70 | 130 | 30 |
| Methylene Chloride | ND | 0.20 | 10 | 11.5 | 115 | 11.2 | 112 | 2.5 | 70 | 130 | 30 |
| Trichloroethene | ND | 0.20 | 10 | 11.1 | 111 | 11.1 | 111 | 0.4 | 70 | 130 | 30 |
| Toluene | ND | 0.20 | 10 | 11.3 | 113 | 11.2 | 112 | 0.8 | 70 | 130 | 30 |
| 1,1,2,2-Tetrachloroethane | ND | 0.20 | 10 | 10.5 | 105 | 10.6 | 106 | 0.9 | 70 | 130 | 30 |
| | | | | | | | | | | | |

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date: 5/13/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/12/26
**Matrix:** Air
**Reporting Units:** ppmv

## EPA ALT-144 (CO by FID)

| Lab No.: | T051203-01 | | T051203-02 | | T051203-03 | | T051203-04 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2353 | | H-2165W | | H-2273W | | CV-2314 | |
| Date/Time Sampled: | 5/12/26 7:35 | | 5/12/26 7:45 | | 5/12/26 7:50 | | 5/12/26 8:05 | |
| Date/Time Analyzed: | 5/12/26 13:58 | | 5/12/26 14:12 | | 5/12/26 14:27 | | 5/12/26 14:41 | |
| QC Batch No.: | 260512GC8A1 | | 260512GC8A1 | | 260512GC8A1 | | 260512GC8A1 | |
| Analyst Initials: | KD | | KD | | KD | | KD | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | 1.0 | |
| ANALYTE | Result ppmv | RL ppmv | Result ppmv | RL ppmv | Result ppmv | RL ppmv | Result ppmv | RL ppmv |
| Carbon Monoxide | 760 | 10 | 720 | 10 | 76 | 10 | 3,400 | 10 |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-20-26
**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/12/26
**Matrix:** Air
**Reporting Units:** ppmv

## EPA ALT-144 (CO by FID)

| Lab No.: | T051203-05 | | T051203-06 | | T051203-07 | | T051203-08 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2305 | | CV-24064 | | CV-24063 | | CV-2303 | |
| Date/Time Sampled: | 5/12/26 8:10 | | 5/12/26 8:15 | | 5/12/26 8:20 | | 5/12/26 8:30 | |
| Date/Time Analyzed: | 5/12/26 14:56 | | 5/12/26 15:10 | | 5/12/26 15:25 | | 5/12/26 15:39 | |
| QC Batch No.: | 260512GC8A1 | | 260512GC8A1 | | 260512GC8A1 | | 260512GC8A1 | |
| Analyst Initials: | KD | | KD | | KD | | KD | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | 1.0 | |
| ANALYTE | Result ppmv | RL ppmv | Result ppmv | RL ppmv | Result ppmv | RL ppmv | Result ppmv | RL ppmv |
| Carbon Monoxide | 1,700 | 10 | 2,000 | 10 | 2,400 | 10 | 2,000 | 10 |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-20-26
**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/12/26
**Matrix:** Air
**Reporting Units:** ppmv

## EPA ALT-144 (CO by FID)

| Lab No.: | T051203-09 | | T051203-10 | | | | | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-24017 | | CV-24007 | | | | | |
| Date/Time Sampled: | 5/12/26 8:35 | | 5/12/26 8:40 | | | | | |
| Date/Time Analyzed: | 5/12/26 15:54 | | 5/12/26 16:08 | | | | | |
| QC Batch No.: | 260512GC8A1 | | 260512GC8A1 | | | | | |
| Analyst Initials: | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | 1.0 | | | | | |
| ANALYTE | Result ppmv | RL ppmv | Result ppmv | RL ppmv | | | | |
| Carbon Monoxide | 2,100 | 10 | 1,800 | 10 | | | | |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-20-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**QC Batch No:** 260512GC8A1
**Matrix:** Air
**Reporting Units:** ppmv

## EPA ALT-144 (CO by FID)
## LABORATORY CONTROL SAMPLE SUMMARY

| Lab No.: | METHOD BLANK | | | LCS | | LCSD | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Date Analyzed: | 5/12/26 13:43 | | | 5/12/26 12:59 | | 5/12/26 13:14 | | | | | |
| Analyst Initials: | KD | | | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | | 1.0 | | 1.0 | | | Limits | | |
| ANALYTE | Result ppmv | RL ppmv | SPIKE AMT. ppmv | Result ppmv | % Rec. | Result ppmv | % Rec. | RPD % | Low %Rec | High %Rec | Max. RPD |
| Carbon Monoxide | ND | 10 | 1,010 | 1,060 | 105 | 1,060 | 105 | 0.1 | 70 | 130 | 30 |
| | | | | | | | | | | | |

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/12/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T051203-01 | | | T051203-02 | | | T051203-03 | | | T051203-04 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2353 | | | H-2165W | | | H-2273W | | | CV-2314 | | |
| Date/Time Sampled: | 5/12/26 7:35 | | | 5/12/26 7:45 | | | 5/12/26 7:50 | | | 5/12/26 8:05 | | |
| Date/Time Analyzed: | 5/12/26 13:58 | | | 5/12/26 14:12 | | | 5/12/26 14:27 | | | 5/12/26 14:41 | | |
| QC Batch No.: | 260512GC8A1 | | | 260512GC8A1 | | | 260512GC8A1 | | | 260512GC8A1 | | |
| Analyst Initials: | KD | | | KD | | | KD | | | KD | | |
| Dilution Factor: | 1.0 | | | 1.0 | | | 1.0 | | | 1.0 | | |
| ANALYTE | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v |
| Hydrogen | 21 | 1.0 | 0.059 | 4.8 | 1.0 | 0.059 | 0.59 J | 1.0 | 0.059 | 14 | 1.0 | 0.059 |
| | | | | | | | | | | | | |

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/12/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T051203-05 | | | T051203-06 | | | T051203-07 | | | T051203-08 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2305 | | | CV-24064 | | | CV-24063 | | | CV-2303 | | |
| Date/Time Sampled: | 5/12/26 8:10 | | | 5/12/26 8:15 | | | 5/12/26 8:20 | | | 5/12/26 8:30 | | |
| Date/Time Analyzed: | 5/12/26 14:56 | | | 5/12/26 15:10 | | | 5/12/26 15:25 | | | 5/12/26 15:39 | | |
| QC Batch No.: | 260512GC8A1 | | | 260512GC8A1 | | | 260512GC8A1 | | | 260512GC8A1 | | |
| Analyst Initials: | KD | | | KD | | | KD | | | KD | | |
| Dilution Factor: | 1.0 | | | 1.0 | | | 1.0 | | | 1.0 | | |
| ANALYTE | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v |
| Hydrogen | 8.2 | 1.0 | 0.059 | 13 | 1.0 | 0.059 | 12 | 1.0 | 0.059 | 19 | 1.0 | 0.059 |
| | | | | | | | | | | | | |

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____
Mark Johnson
Operations Manager

Date 5-20-26

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/12/26
**Matrix:** Air
**Reporting Units:** % v/v

**ASTM D1946**

| Lab No.: | T051203-09 | | | T051203-10 | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-24017 | | | CV-24007 | | | | | | | | |
| Date/Time Sampled: | 5/12/26 8:35 | | | 5/12/26 8:40 | | | | | | | | |
| Date/Time Analyzed: | 5/12/26 15:54 | | | 5/12/26 16:08 | | | | | | | | |
| QC Batch No.: | 260512GC8A1 | | | 260512GC8A1 | | | | | | | | |
| Analyst Initials: | KD | | | KD | | | | | | | | |
| Dilution Factor: | 1.0 | | | 1.0 | | | | | | | | |
| ANALYTE | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | | | | | | |
| Hydrogen | 19 | 1.0 | 0.059 | 17 | 1.0 | 0.059 | | | | | | |
| | | | | | | | | | | | | |

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____
Mark Johnson
Operations Manager

Date 5-20-26

The cover letter is an integral part of this analytical report

**QC Batch No:** 260512GC8A1
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946
## LABORATORY CONTROL SAMPLE SUMMARY

| Lab No.: | METHOD BLANK | | | | LCS | | LCSD | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Date Analyzed: | 5/12/26 13:43 | | | | 5/12/26 12:59 | | 5/12/26 13:14 | | | | | |
| Analyst Initials: | KD | | | | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | | | 1.0 | | 1.0 | | | Limits | | |
| ANALYTE | Result % v/v | RL % v/v | MDL % v/v | SPIKE AMT. % v/v | Result % v/v | % Rec. | Result % v/v | % Rec. | RPD % | Low %Rec | High %Rec | Max. RPD |
| Hydrogen | ND | 1.0 | 0.059 | 5.0 | 3.75 | 75 | 3.79 | 76 | 1.1 | 70 | 130 | 30 |
| | | | | | | | | | | | | |

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

**Reviewed/Approved By:** _____ **Date** 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/12/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T051203-01 | | T051203-02 | | T051203-03 | | T051203-04 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2353 | | H-2165W | | H-2273W | | CV-2314 | |
| Date/Time Sampled: | 5/12/26 7:35 | | 5/12/26 7:45 | | 5/12/26 7:50 | | 5/12/26 8:05 | |
| Date/Time Analyzed: | 5/12/26 13:58 | | 5/12/26 14:12 | | 5/12/26 14:27 | | 5/12/26 14:41 | |
| QC Batch No.: | 260512GC8A1 | | 260512GC8A1 | | 260512GC8A1 | | 260512GC8A1 | |
| Analyst Initials: | KD | | KD | | KD | | KD | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | 1.0 | |
| ANALYTE | Result % v/v | RL % v/v | Result % v/v | RL % v/v | Result % v/v | RL % v/v | Result % v/v | RL % v/v |
| Carbon Dioxide | 67 | 0.010 | 79 | 0.010 | 42 | 0.010 | 80 | 0.010 |
| Oxygen/Argon | 1.4 | 0.50 | ND | 0.50 | 1.4 | 0.50 | 0.62 | 0.50 |
| Nitrogen | 5.2 | 1.0 | 1.8 | 1.0 | 38 | 1.0 | 3.0 | 1.0 |
| Methane | 2.3 | 0.0010 | 12 | 0.0010 | 17 | 0.0010 | 0.92 | 0.0010 |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-20-26
**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/12/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T051203-05 | | T051203-06 | | T051203-07 | | T051203-08 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2305 | | CV-24064 | | CV-24063 | | CV-2303 | |
| Date/Time Sampled: | 5/12/26 8:10 | | 5/12/26 8:15 | | 5/12/26 8:20 | | 5/12/26 8:30 | |
| Date/Time Analyzed: | 5/12/26 14:56 | | 5/12/26 15:10 | | 5/12/26 15:25 | | 5/12/26 15:39 | |
| QC Batch No.: | 260512GC8A1 | | 260512GC8A1 | | 260512GC8A1 | | 260512GC8A1 | |
| Analyst Initials: | KD | | KD | | KD | | KD | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | 1.0 | |
| ANALYTE | Result % v/v | RL % v/v | Result % v/v | RL % v/v | Result % v/v | RL % v/v | Result % v/v | RL % v/v |
| Carbon Dioxide | 72 | 0.010 | 79 | 0.010 | 79 | 0.010 | 69 | 0.010 |
| Oxygen/Argon | 0.51 | 0.50 | 0.78 | 0.50 | 0.93 | 0.50 | 1.8 | 0.50 |
| Nitrogen | 1.9 | 1.0 | 2.8 | 1.0 | 3.3 | 1.0 | 6.7 | 1.0 |
| Methane | 16 | 0.0010 | 2.2 | 0.0010 | 2.8 | 0.0010 | 1.3 | 0.0010 |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-20-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/12/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T051203-09 | | T051203-10 | | | | | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-24017 | | CV-24007 | | | | | |
| Date/Time Sampled: | 5/12/26 8:35 | | 5/12/26 8:40 | | | | | |
| Date/Time Analyzed: | 5/12/26 15:54 | | 5/12/26 16:08 | | | | | |
| QC Batch No.: | 260512GC8A1 | | 260512GC8A1 | | | | | |
| Analyst Initials: | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | 1.0 | | | | | |
| **ANALYTE** | **Result % v/v** | **RL % v/v** | **Result % v/v** | **RL % v/v** | | | | |
| Carbon Dioxide | 72 | 0.010 | 75 | 0.010 | | | | |
| Oxygen/Argon | 0.92 | 0.50 | ND | 0.50 | | | | |
| Nitrogen | 3.3 | 1.0 | 1.3 | 1.0 | | | | |
| Methane | 1.9 | 0.0010 | 5.0 | 0.0010 | | | | |
| | | | | | | | | |

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**QC Batch No:** 260512GC8A1
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946
## LABORATORY CONTROL SAMPLE SUMMARY

| Lab No.: | METHOD BLANK | | | LCS | | LCSD | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Date Analyzed: | 5/12/26 13:43 | | | 5/12/26 12:59 | | 5/12/26 13:14 | | | | | |
| Analyst Initials: | KD | | | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | | 1.0 | | 1.0 | | | Limits | | |
| ANALYTE | Result % v/v | RL % v/v | SPIKE AMT. % v/v | Result % v/v | % Rec. | Result % v/v | % Rec. | RPD % | Low %Rec | High %Rec | Max. RPD |
| Carbon Dioxide | ND | 0.010 | 10 | 8.98 | 90 | 8.98 | 90 | 0.1 | 70 | 130 | 30 |
| Oxygen/Argon | ND | 0.50 | 15 | 15.2 | 101 | 15.2 | 101 | 0.2 | 70 | 130 | 30 |
| Nitrogen | ND | 1.0 | 70 | 72.4 | 104 | 72.3 | 104 | 0.1 | 70 | 130 | 30 |
| Methane | ND | 0.0010 | 0.10 | 0.100 | 99 | 0.1000 | 99 | 0.1 | 70 | 130 | 30 |
| | | | | | | | | | | | |

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-20-26
**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175
TX Cert T104704450-14-6
EPA Methods TO14A, TO15
ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

June 1, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

## LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T051302-01/11

Enclosed are the results for sample(s) received 5/13/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

# CHAIN OF CUSTODY RECORD

**TURNAROUND TIME**: Standard ■ 48 hours ☐ | Same Day ☐ 72 hours ☐ | 24 hours ☐ 96 hours ☐ | Other:

**DELIVERABLES**: EDD ■ | EDF ☐ | Level 3 ☐ | Level 4 ☐

**PAGE:** 1 OF

Condition upon receipt: Sealed Yes ☐ No ☐ | Intact Yes ☐ No ☐ | Chilled _____ deg C

| | |
|---|---|
| **Project No.:** | 07224200.24 Task 1 |
| **Project Name:** | Chiquita Canyon Landfill |
| **Report To:** | Cornelius Fong |
| **Company:** | SCS Engineers |
| **Street:** | 3900 Kilroy Airport Way, Suite 300 |
| **City/State/Zip:** | Long Beach, CA 90806-6816 |
| **Phone& Fax:** | 562-743-7895 |
| **e-mail:** | cfong@scsengineers.com |

**BILLING**

**P.O. No.:**

**Bill to:** [illegible]@scsengineers.com

3900 Kilroy Airport Way, Suite 300
Long Beach, CA 90806-6816

| LAB USE ONLY | SAMPLE IDENTIFICATION | SAMPLE DATE | SAMPLE TIME | CONTAINER QTY/TYPE | MATRIX | PRESERVATION | ANALYSIS REQUEST: CH4, CO2, O2, N2 ASTM D1946 | Carbon Monoxide EPA ALT-144 | Hydrogen ASTM D1946 | VOCs EPA TO-15 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| T051302-01 | CV-2333 | 05/13/26 | 7:40M | 1L | Gas | N | X | X | X | | | |
| -02 | CV-2334 | 05/13/26 | 7:45AM | 1L | Gas | N | X | X | X | | | |
| -03 | CV-24128 | 05/13/26 | 7:50AM | 1L | Gas | N | X | X | X | | | |
| -04 | CV-24125 | 05/13/26 | 7:55AM | 1L | Gas | N | X | X | X | | | |
| -05 | CV-24134 | 05/13/26 | 8:00AM | 1L | Gas | N | X | | | | | |
| -06 | CV-24126 | 05/13/26 | 8:05AM | 1L | Gas | N | X | | | | | |
| -07 | CV-24049 | 05/13/26 | 8:10AM | 1L | Gas | N | X | X | X | | | |
| -08 | CV-24055 | 05/13/26 | 8:15AM | 1L | Gas | N | X | X | X | | | |
| -09 | CV-24100 | 05/13/26 | 8:25AM | 1L | Gas | N | X | X | X | | | |
| -10 | CV-24069 | 05/13/26 | 8:20AM | 1L | Gas | N | X | X | X | | | |

| | | | |
|---|---|---|---|
| AUTHORIZATION TO PERFORM WORK | COMPANY SCS | 5-13-26 | DATE/TIME 9:11A |
| SAMPLED BY ERIK NAVARRO | COMPANY SCS | 5-13-26 | DATE/TIME 9:11A |
| RELINQUISHED BY ERIK NAVARRO | DATE/TIME 5-13-26 9:11A | RECEIVED BY [signature] | DATE/TIME 5/13/26 9:19 |
| RELINQUISHED BY [signature] | DATE/TIME 5/13/26 11:34 | RECEIVED BY [signature] | DATE/TIME 5/13/26 11:34 |
| RELINQUISHED BY | DATE/TIME | RECEIVED BY | DATE/TIME |

**METHOD OF TRANSPORT (circle one):** Walk-In FedEx UPS **Courier** ATLI Other_____

**COMMENTS**
Report full list of TO-15 compounds
Raw landfill gas samples
**FLAMMABLE**

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

Air TECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

# CHAIN OF CUSTODY RECORD

**TURNAROUND TIME**: Standard ■ 48 hours ☐ | Same Day ☐ 72 hours ☐ | 24 hours ☐ 96 hours ☐ | Other:

**DELIVERABLES**: EDD ■ | EDF ☐ | Level 3 ☐ | Level 4 ☐

**PAGE:** 2 **OF**

Condition upon receipt: Sealed Yes ☐ No ☐ | Intact Yes ☐ No ☐ | Chilled _____ deg C

| | |
|---|---|
| ***Project No.:*** | 07224200.24 Task 1 |
| ***Project Name:*** | Chiquita Canyon Landfill |
| ***Report To:*** | Cornelius Fong |
| ***Company:*** | SCS Engineers |
| ***Street:*** | 3900 Kilroy Airport Way, Suite 300 |
| ***City/State/Zip:*** | Long Beach, CA 90806-6816 |
| ***Phone& Fax:*** | 562-743-7895 |
| ***e-mail:*** | cfong@scsengineers.com |

**BILLING**

***P.O. No.:***

***Bill to:*** [illegible]SAccountspayable@scsengineers.com
3900 Kilroy Airport Way, Suite 300
Long Beach, CA 90806-6816

| LAB USE ONLY | SAMPLE IDENTIFICATION | SAMPLE DATE | SAMPLE TIME | CONTAINER QTY/TYPE | MATRIX | PRESERVATION | ANALYSIS REQUEST: CH4, CO2, O2, N2 ASTM D1946 | Carbon Monoxide EPA ALT-144 | Hydrogen ASTM D1946 | VOCs EPA TO-15 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| T051302-11 | CV-2312 | 05/13/26 | 8:30AM | 2L ~~1L~~ | Gas | N | X | X | X | X | | |
| | | | | 1L | Gas | N | | | | | | |
| | | | | 1L | Gas | N | | | | | | |
| | | | | 1L | Gas | N | | | | | | |
| | | | | 1L | Gas | N | | | | | | |
| | | | | 1L | Gas | N | | | | | | |
| | | | | 1L | Gas | N | | | | | | |
| | | | | 1L | Gas | N | | | | | | |
| | | | | 1L | Gas | N | | | | | | |
| | | | | 1L | Gas | N | | | | | | |

| | | | |
|---|---|---|---|
| AUTHORIZATION TO PERFORM WORK | COMPANY SCS | 5-13-26 | DATE/TIME 9:11 |
| SAMPLED BY ERIK NAVARRO | COMPANY SCS | 5-13-26 | DATE/TIME 9:11 |
| RELINQUISHED BY ERIK NAVARRO | DATE/TIME 5-13-26 9:11 | RECEIVED BY [signature] 5/13/26 | DATE/TIME 9:19 AM |
| RELINQUISHED BY [signature] | DATE/TIME 5/13/26 11:34 | RECEIVED BY [signature] 5/13/26 | DATE/TIME 11:34 |
| RELINQUISHED BY | DATE/TIME | RECEIVED BY | DATE/TIME |

**METHOD OF TRANSPORT (circle one):** Walk-In FedEx UPS **Courier** ATLI Other_____

**COMMENTS**
Report full list of TO-15 compounds
Raw landfill gas samples
**FLAMMABLE**

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/13/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | T051302-11 |
|---|---|
| Client Sample I.D.: | CV-2312 |
| Date/Time Sampled: | 5/13/26 8:30 |
| Date/Time Analyzed: | 5/13/26 20:16 |
| QC Batch No.: | 260513MS2A1 |
| Analyst Initials: | VM/GD |
| Dilution Factor: | 1,000 |

| ANALYTE | Result ppbv | RL ppbv |
|---|---|---|
| Dichlorodifluoromethane (12) | ND | 1,000 |
| Chloromethane | ND | 1,000 |
| 1,2-Cl-1,1,2,2-F ethane (114) | ND | 1,000 |
| Vinyl Chloride | ND | 1,000 |
| Bromomethane | ND | 1,000 |
| Chloroethane | ND | 5,000 |
| Trichlorofluoromethane (11) | ND | 1,000 |
| 1,1-Dichloroethene | ND | 1,000 |
| Carbon Disulfide | ND | 1,000 |
| 1,1,2-Cl 1,2,2-F ethane (113) | ND | 1,000 |
| Acetone | 75,000 | 5,000 |
| Methylene Chloride | ND | 1,000 |
| t-1,2-Dichloroethene | ND | 1,000 |
| 1,1-Dichloroethane | ND | 1,000 |
| Vinyl Acetate | ND | 1,000 |
| c-1,2-Dichloroethene | ND | 1,000 |
| 2-Butanone | 62,000 | 5,000 |
| t-Butyl Methyl Ether (MTBE) | ND | 1,000 |
| Chloroform | ND | 1,000 |
| 1,1,1-Trichloroethane | ND | 1,000 |
| Carbon Tetrachloride | ND | 1,000 |
| Benzene | 48,000 | 1,000 |
| 1,2-Dichloroethane | ND | 1,000 |
| Trichloroethene | ND | 1,000 |
| 1,2-Dichloropropane | ND | 1,000 |
| Bromodichloromethane | ND | 1,000 |
| c-1,3-Dichloropropene | ND | 1,000 |
| 4-Methyl-2-Pentanone | 1,500 | 1,000 |
| Toluene | 2,100 | 1,000 |
| t-1,3-Dichloropropene | ND | 2,000 |
| 1,1,2-Trichloroethane | ND | 1,000 |
| Tetrachloroethene | ND | 1,000 |
| 2-Hexanone | ND | 1,000 |
| Dibromochloromethane | ND | 1,000 |

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/13/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | T051302-11 |
|---|---|
| Client Sample I.D.: | CV-2312 |
| Date/Time Sampled: | 5/13/26 8:30 |
| Date/Time Analyzed: | 5/13/26 20:16 |
| QC Batch No.: | 260513MS2A1 |
| Analyst Initials: | VM/GD |
| Dilution Factor: | 1,000 |

| ANALYTE | Result ppbv | RL ppbv |
|---|---|---|
| 1,2-Dibromoethane | ND | 1,000 |
| Chlorobenzene | ND | 1,000 |
| Ethylbenzene | ND | 1,000 |
| p,&m-Xylene | ND | 2,000 |
| o-Xylene | ND | 1,000 |
| Styrene | ND | 1,000 |
| Bromoform | ND | 1,000 |
| 1,1,2,2-Tetrachloroethane | ND | 1,000 |
| Benzyl Chloride | ND | 1,000 |
| 4-Ethyl Toluene | ND | 1,000 |
| 1,3,5-Trimethylbenzene | ND | 1,000 |
| 1,2,4-Trimethylbenzene | ND | 1,000 |
| 1,3-Dichlorobenzene | ND | 1,000 |
| 1,4-Dichlorobenzene | ND | 1,000 |
| 1,2-Dichlorobenzene | ND | 1,000 |
| 1,2,4-Trichlorobenzene | ND | 1,000 |
| Hexachlorobutadiene | ND | 1,000 |
| 1,3-Butadiene | ND | 5,000 |
| Isopropanol | 14,000 | 5,000 |
| n-Hexane | ND | 5,000 |
| Ethyl Acetate | 6,200 | 5,000 |
| Tetrahydrofuran | 53,000 | 5,000 |
| Cyclohexane | ND | 5,000 |
| Heptane | ND | 5,000 |
| 1,4-Dioxane | ND | 5,000 |

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 6/1/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/13/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | METHOD BLANK |
|---|---|
| Client Sample I.D.: | -- |
| Date/Time Sampled: | -- |
| Date/Time Analyzed: | 5/13/26 6:48 |
| QC Batch No.: | 260513MS2A1 |
| Analyst Initials: | VM/GD |
| Dilution Factor: | 0.20 |

| ANALYTE | Result ppbv | RL ppbv |
|---|---|---|
| Dichlorodifluoromethane (12) | ND | 0.20 |
| Chloromethane | ND | 0.20 |
| 1,2-Cl-1,1,2,2-F ethane (114) | ND | 0.20 |
| Vinyl Chloride | ND | 0.20 |
| Bromomethane | ND | 0.20 |
| Chloroethane | ND | 1.0 |
| Trichlorofluoromethane (11) | ND | 0.20 |
| 1,1-Dichloroethene | ND | 0.20 |
| Carbon Disulfide | ND | 0.20 |
| 1,1,2-Cl 1,2,2-F ethane (113) | ND | 0.20 |
| Acetone | ND | 1.0 |
| Methylene Chloride | ND | 0.20 |
| t-1,2-Dichloroethene | ND | 0.20 |
| 1,1-Dichloroethane | ND | 0.20 |
| Vinyl Acetate | ND | 0.20 |
| c-1,2-Dichloroethene | ND | 0.20 |
| 2-Butanone | ND | 1.0 |
| t-Butyl Methyl Ether (MTBE) | ND | 0.20 |
| Chloroform | ND | 0.20 |
| 1,1,1-Trichloroethane | ND | 0.20 |
| Carbon Tetrachloride | ND | 0.20 |
| Benzene | ND | 0.20 |
| 1,2-Dichloroethane | ND | 0.20 |
| Trichloroethene | ND | 0.20 |
| 1,2-Dichloropropane | ND | 0.20 |
| Bromodichloromethane | ND | 0.20 |
| c-1,3-Dichloropropene | ND | 0.20 |
| 4-Methyl-2-Pentanone | ND | 0.20 |
| Toluene | ND | 0.20 |
| t-1,3-Dichloropropene | ND | 0.40 |
| 1,1,2-Trichloroethane | ND | 0.20 |
| Tetrachloroethene | ND | 0.20 |
| 2-Hexanone | ND | 0.20 |
| Dibromochloromethane | ND | 0.20 |

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/13/26
**Matrix:** Air
**Reporting Units:** ppbv

## EPA Method TO-15

| Lab No.: | METHOD BLANK |
|---|---|
| Client Sample I.D.: | -- |
| Date/Time Sampled: | -- |
| Date/Time Analyzed: | 5/13/26 6:48 |
| QC Batch No.: | 260513MS2A1 |
| Analyst Initials: | VM/GD |
| Dilution Factor: | 0.20 |

| ANALYTE | Result ppbv | RL ppbv |
|---|---|---|
| 1,2-Dibromoethane | ND | 0.20 |
| Chlorobenzene | ND | 0.20 |
| Ethylbenzene | ND | 0.20 |
| p,&m-Xylene | ND | 0.40 |
| o-Xylene | ND | 0.20 |
| Styrene | ND | 0.20 |
| Bromoform | ND | 0.20 |
| 1,1,2,2-Tetrachloroethane | ND | 0.20 |
| Benzyl Chloride | ND | 0.20 |
| 4-Ethyl Toluene | ND | 0.20 |
| 1,3,5-Trimethylbenzene | ND | 0.20 |
| 1,2,4-Trimethylbenzene | ND | 0.20 |
| 1,3-Dichlorobenzene | ND | 0.20 |
| 1,4-Dichlorobenzene | ND | 0.20 |
| 1,2-Dichlorobenzene | ND | 0.20 |
| 1,2,4-Trichlorobenzene | ND | 0.20 |
| Hexachlorobutadiene | ND | 0.20 |
| 1,3-Butadiene | ND | 1.0 |
| Isopropanol | ND | 1.0 |
| n-Hexane | ND | 1.0 |
| Ethyl Acetate | ND | 1.0 |
| Tetrahydrofuran | ND | 1.0 |
| Cyclohexane | ND | 1.0 |
| Heptane | ND | 1.0 |
| 1,4-Dioxane | ND | 1.0 |

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 6/1/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

# LCS/LCSD Recovery and RPD Summary Report

## QC Batch #: 260513MS2A1

**Matrix:** Air

**Reporting Units:** ppbv

**EPA Method TO-15**
**LABORATORY CONTROL SAMPLE SUMMARY**

| Lab No.: | METHOD BLANK | | | LCS | | LCSD | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Date/Time Analyzed: | 5/13/26 6:48 | | | 5/13/26 5:32 | | 5/13/26 6:10 | | | | | |
| Analyst Initials: | VM/GD | | | VM/GD | | VM/GD | | | | | |
| Dilution Factor: | 0.20 | | | 1.0 | | 1.0 | | | | | |
| ANALYTE | Result ppbv | RL ppbv | AMT. ppbv | Result ppbv | % Rec. | Result ppbv | % Rec. | RPD | Low %Rec | High %Rec | Max. RPD |
| 1,1-Dichloroethene | ND | 0.20 | 10 | **10.9** | 109 | **10.9** | 109 | 0.3 | **70** | **130** | 30 |
| Methylene Chloride | ND | 0.20 | 10 | **10.7** | 107 | **11.0** | 110 | 3.4 | **70** | **130** | 30 |
| Trichloroethene | ND | 0.20 | 10 | **10.8** | 108 | **10.5** | 105 | 2.6 | **70** | **130** | 30 |
| Toluene | ND | 0.20 | 10 | **10.6** | 106 | **10.5** | 105 | 0.6 | **70** | **130** | 30 |
| 1,1,2,2-Tetrachloroethane | ND | 0.20 | 10 | **9.68** | 97 | **9.83** | 98 | 1.6 | **70** | **130** | 30 |
| | | | | | | | | | | | |

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date:** 6/1/26
**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/13/26
**Matrix:** Air
**Reporting Units:** ppmv

## EPA ALT-144 (CO by FID)

| Lab No.: | T051302-01 | | T051302-02 | | T051302-03 | | T051302-04 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2333 | | CV-2334 | | CV-24128 | | CV-24125 | |
| Date/Time Sampled: | 5/13/26 7:40 | | 5/13/26 7:45 | | 5/13/26 7:50 | | 5/13/26 7:55 | |
| Date/Time Analyzed: | 5/14/26 5:41 | | 5/14/26 5:55 | | 5/14/26 6:10 | | 5/14/26 6:24 | |
| QC Batch No.: | 260513GC8A2 | | 260513GC8A2 | | 260513GC8A2 | | 260513GC8A2 | |
| Analyst Initials: | KD | | KD | | KD | | KD | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | 1.0 | |
| ANALYTE | Result ppmv | RL ppmv | Result ppmv | RL ppmv | Result ppmv | RL ppmv | Result ppmv | RL ppmv |
| Carbon Monoxide | 3,600 | 10 | 660 | 10 | 210 | 10 | 30 | 10 |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-20-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/13/26
**Matrix:** Air
**Reporting Units:** ppmv

## EPA ALT-144 (CO by FID)

| Lab No.: | T051302-07 | | T051302-08 | | T051302-09 | | T051302-10 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-24049 | | CV-24055 | | CV-24100 | | CV-24069 | |
| Date/Time Sampled: | 5/13/26 8:10 | | 5/13/26 8:15 | | 5/13/26 8:25 | | 5/13/26 8:20 | |
| Date/Time Analyzed: | 5/14/26 7:08 | | 5/14/26 7:22 | | 5/14/26 7:37 | | 5/14/26 7:51 | |
| QC Batch No.: | 260513GC8A2 | | 260513GC8A2 | | 260513GC8A2 | | 260513GC8A2 | |
| Analyst Initials: | KD | | KD | | KD | | KD | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | 1.0 | |
| ANALYTE | Result ppmv | RL ppmv | Result ppmv | RL ppmv | Result ppmv | RL ppmv | Result ppmv | RL ppmv |
| Carbon Monoxide | 2,800 | 10 | 930 | 10 | 83 | 10 | 470 | 10 |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-20-26
**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/13/26
**Matrix:** Air
**Reporting Units:** ppmv

## EPA ALT-144 (CO by FID)

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| **Lab No.:** | **T051302-11** | | | | | | | |
| **Client Sample I.D.:** | **CV-2312** | | | | | | | |
| **Date/Time Sampled:** | **5/13/26 8:30** | | | | | | | |
| **Date/Time Analyzed:** | **5/14/26 8:06** | | | | | | | |
| **QC Batch No.:** | **260513GC8A2** | | | | | | | |
| **Analyst Initials:** | **KD** | | | | | | | |
| **Dilution Factor:** | **1.0** | | | | | | | |
| **ANALYTE** | **Result ppmv** | **RL ppmv** | | | | | | |
| Carbon Monoxide | 1,800 | 10 | | | | | | |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-20-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**QC Batch No:** 260513GC8A2
**Matrix:** Air
**Reporting Units:** ppmv

## EPA ALT-144 (CO by FID)
## LABORATORY CONTROL SAMPLE SUMMARY

| Lab No.: | METHOD BLANK | | | LCS | | LCSD | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Date Analyzed: | 5/14/26 2:08 | | | 5/14/26 3:21 | | 5/14/26 3:35 | | | | | |
| Analyst Initials: | KD | | | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | | 1.0 | | 1.0 | | | Limits | | |
| ANALYTE | Result ppmv | RL ppmv | SPIKE AMT. ppmv | Result ppmv | % Rec. | Result ppmv | % Rec. | RPD % | Low %Rec | High %Rec | Max. RPD |
| Carbon Monoxide | ND | 10 | 1,010 | 1,290 | 127 | 1,260 | 125 | 1.9 | 70 | 130 | 30 |
| | | | | | | | | | | | |

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-20-26

**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/13/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T051302-01 | | | T051302-02 | | | T051302-03 | | | T051302-04 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2333 | | | CV-2334 | | | CV-24128 | | | CV-24125 | | |
| Date/Time Sampled: | 5/13/26 7:40 | | | 5/13/26 7:45 | | | 5/13/26 7:50 | | | 5/13/26 7:55 | | |
| Date/Time Analyzed: | 5/14/26 5:41 | | | 5/14/26 5:55 | | | 5/14/26 6:10 | | | 5/14/26 6:24 | | |
| QC Batch No.: | 260513GC8A2 | | | 260513GC8A2 | | | 260513GC8A2 | | | 260513GC8A2 | | |
| Analyst Initials: | KD | | | KD | | | KD | | | KD | | |
| Dilution Factor: | 1.0 | | | 1.0 | | | 1.0 | | | 1.0 | | |
| ANALYTE | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v |
| Hydrogen | 16 | 1.0 | 0.059 | 1.1 | 1.0 | 0.059 | 1.1 | 1.0 | 0.059 | 0.13 J | 1.0 | 0.059 |
| | | | | | | | | | | | | |

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/13/26
**Matrix:** Air
**Reporting Units:** % v/v

**ASTM D1946**

| Lab No.: | T051302-07 | | | T051302-08 | | | T051302-09 | | | T051302-10 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-24049 | | | CV-24055 | | | CV-24100 | | | CV-24069 | | |
| Date/Time Sampled: | 5/13/26 8:10 | | | 5/13/26 8:15 | | | 5/13/26 8:25 | | | 5/13/26 8:20 | | |
| Date/Time Analyzed: | 5/14/26 7:08 | | | 5/14/26 7:22 | | | 5/14/26 7:37 | | | 5/14/26 7:51 | | |
| QC Batch No.: | 260513GC8A2 | | | 260513GC8A2 | | | 260513GC8A2 | | | 260513GC8A2 | | |
| Analyst Initials: | KD | | | KD | | | KD | | | KD | | |
| Dilution Factor: | 1.0 | | | 1.0 | | | 1.0 | | | 1.0 | | |
| ANALYTE | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v | Result % v/v | RL % v/v | MDL % v/v |
| Hydrogen | 16 | 1.0 | 0.059 | 5.1 | 1.0 | 0.059 | 0.88 J | 1.0 | 0.059 | 4.0 | 1.0 | 0.059 |
| | | | | | | | | | | | | |

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/13/26
**Matrix:** Air
**Reporting Units:** % v/v

**ASTM D1946**

| Lab No.: | T051302-11 | | |
|---|---|---|---|
| Client Sample I.D.: | CV-2312 | | |
| Date/Time Sampled: | 5/13/26 8:30 | | |
| Date/Time Analyzed: | 5/14/26 8:06 | | |
| QC Batch No.: | 260513GC8A2 | | |
| Analyst Initials: | KD | | |
| Dilution Factor: | 1.0 | | |

| ANALYTE | Result % v/v | RL % v/v | MDL % v/v |
|---|---|---|---|
| Hydrogen | 9.0 | 1.0 | 0.059 |
| | | | |

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

**QC Batch No:** 260513GC8A2
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946
## LABORATORY CONTROL SAMPLE SUMMARY

| Lab No.: | METHOD BLANK | | | | LCS | | LCSD | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Date Analyzed: | 5/14/26 2:08 | | | | 5/14/26 3:21 | | 5/14/26 3:35 | | | | | |
| Analyst Initials: | KD | | | | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | | | 1.0 | | 1.0 | | | Limits | | |
| ANALYTE | Result % v/v | RL % v/v | MDL % v/v | SPIKE AMT. % v/v | Result % v/v | % Rec. | Result % v/v | % Rec. | RPD % | Low %Rec | High %Rec | Max. RPD |
| Hydrogen | ND | 1.0 | 0.059 | 5.0 | 5.27 | 106 | 5.30 | 107 | 0.6 | 70 | 130 | 30 |
| | | | | | | | | | | | | |

**MDL = Method Detection Limit**
**ND= Not Detected (below MDL)**
**RL = Reporting Limit**
**J = Trace amount. Analyte concentration between RL and MDL.**

**Reviewed/Approved By:** _____ **Date** 5-20-26
**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/13/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T051302-01 | | T051302-02 | | T051302-03 | | T051302-04 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-2333 | | CV-2334 | | CV-24128 | | CV-24125 | |
| Date/Time Sampled: | 5/13/26 7:40 | | 5/13/26 7:45 | | 5/13/26 7:50 | | 5/13/26 7:55 | |
| Date/Time Analyzed: | 5/14/26 5:41 | | 5/14/26 5:55 | | 5/14/26 6:10 | | 5/14/26 6:24 | |
| QC Batch No.: | 260513GC8A2 | | 260513GC8A2 | | 260513GC8A2 | | 260513GC8A2 | |
| Analyst Initials: | KD | | KD | | KD | | KD | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | 1.0 | |
| ANALYTE | Result % v/v | RL % v/v | Result % v/v | RL % v/v | Result % v/v | RL % v/v | Result % v/v | RL % v/v |
| Carbon Dioxide | 66 | 0.010 | 74 | 0.010 | 40 | 0.010 | 55 | 0.010 |
| Oxygen/Argon | 3.3 | 0.50 | 2.0 | 0.50 | 3.2 | 0.50 | 3.2 | 0.50 |
| Nitrogen | 12 | 1.0 | 7.6 | 1.0 | 25 | 1.0 | 13 | 1.0 |
| Methane | 0.49 | 0.0010 | 14 | 0.0010 | 31 | 0.0010 | 29 | 0.0010 |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-20-26
**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/13/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T051302-05 | | T051302-06 | | T051302-07 | | T051302-08 | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-24134 | | CV-24126 | | CV-24049 | | CV-24055 | |
| Date/Time Sampled: | 5/13/26 8:00 | | 5/13/26 8:05 | | 5/13/26 8:10 | | 5/13/26 8:15 | |
| Date/Time Analyzed: | 5/14/26 6:39 | | 5/14/26 6:53 | | 5/14/26 7:08 | | 5/14/26 7:22 | |
| QC Batch No.: | 260513GC8A2 | | 260513GC8A2 | | 260513GC8A2 | | 260513GC8A2 | |
| Analyst Initials: | KD | | KD | | KD | | KD | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | 1.0 | |
| **ANALYTE** | **Result % v/v** | **RL % v/v** | **Result % v/v** | **RL % v/v** | **Result % v/v** | **RL % v/v** | **Result % v/v** | **RL % v/v** |
| Carbon Dioxide | **68** | 0.010 | **74** | 0.010 | **74** | 0.010 | **55** | 0.010 |
| Oxygen/Argon | **0.92** | 0.50 | **0.77** | 0.50 | **1.4** | 0.50 | **3.0** | 0.50 |
| Nitrogen | **3.4** | 1.0 | **2.7** | 1.0 | **5.3** | 1.0 | **28** | 1.0 |
| Methane | **13** | 0.0010 | **1.00** | 0.0010 | **0.89** | 0.0010 | **7.9** | 0.0010 |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-20-26
**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**Client:** SCS Engineers
**Attn:** Cornelius Fong
**Project Name:** Chiquita Canyon Landfill
**Project No.:** 07224200.24 Task 1
**Date Received:** 05/13/26
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946

| Lab No.: | T051302-09 | | T051302-10 | | T051302-11 | | | |
|---|---|---|---|---|---|---|---|---|
| Client Sample I.D.: | CV-24100 | | CV-24069 | | CV-2312 | | | |
| Date/Time Sampled: | 5/13/26 8:25 | | 5/13/26 8:20 | | 5/13/26 8:30 | | | |
| Date/Time Analyzed: | 5/14/26 7:37 | | 5/14/26 7:51 | | 5/14/26 8:06 | | | |
| QC Batch No.: | 260513GC8A2 | | 260513GC8A2 | | 260513GC8A2 | | | |
| Analyst Initials: | KD | | KD | | KD | | | |
| Dilution Factor: | 1.0 | | 1.0 | | 1.0 | | | |
| **ANALYTE** | **Result % v/v** | **RL % v/v** | **Result % v/v** | **RL % v/v** | **Result % v/v** | **RL % v/v** | | |
| Carbon Dioxide | 68 | 0.010 | 46 | 0.010 | 47 | 0.010 | | |
| Oxygen/Argon | 1.8 | 0.50 | 1.3 | 0.50 | 8.9 | 0.50 | | |
| Nitrogen | 7.2 | 1.0 | 11 | 1.0 | 34 | 1.0 | | |
| Methane | 22 | 0.0010 | 37 | 0.0010 | 1.5 | 0.0010 | | |
| | | | | | | | | |

**Results normalized including non-methane hydrocarbons**

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-20-26
**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

**QC Batch No:** 260513GC8A2
**Matrix:** Air
**Reporting Units:** % v/v

## ASTM D1946
## LABORATORY CONTROL SAMPLE SUMMARY

| Lab No.: | METHOD BLANK | | | LCS | | LCSD | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Date Analyzed: | 5/14/26 2:08 | | | 5/14/26 3:21 | | 5/14/26 3:35 | | | | | |
| Analyst Initials: | KD | | | KD | | KD | | | | | |
| Dilution Factor: | 1.0 | | | 1.0 | | 1.0 | | | Limits | | |
| ANALYTE | Result % v/v | RL % v/v | SPIKE AMT. % v/v | Result % v/v | % Rec. | Result % v/v | % Rec. | RPD % | Low %Rec | High %Rec | Max. RPD |
| Carbon Dioxide | ND | 0.010 | 10 | 9.89 | 99 | 9.89 | 99 | 0.0 | 70 | 130 | 30 |
| Oxygen/Argon | ND | 0.50 | 15 | 14.8 | 98 | 14.7 | 98 | 0.3 | 70 | 130 | 30 |
| Nitrogen | ND | 1.0 | 70 | 72.1 | 103 | 72.1 | 103 | 0.1 | 70 | 130 | 30 |
| Methane | ND | 0.0010 | 0.10 | 0.109 | 108 | 0.108 | 107 | 0.2 | 70 | 130 | 30 |
| | | | | | | | | | | | |

**ND = Not Detected (below RL)**
**RL = Reporting Limit**

**Reviewed/Approved By:** _____ **Date** 5-20-26
**Mark Johnson**
**Operations Manager**

The cover letter is an integral part of this analytical report

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init °F Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| A-01 | 5/15/2026 8:51:04 AM | 56.1 | 40.2 | 0.1 | 3.6 | | | 1.4 | 36.0 | 79.4 |
| A-02 | 5/11/2026 7:44:04 AM | 58.8 | 38.3 | 0.2 | 2.7 | | | 1.5 | 13.5 | 92.7 |
| A-03 | 5/11/2026 7:56:41 AM | 55.0 | 41.7 | 0.0 | 3.3 | | | 1.3 | 0.0 | 75.5 |
| A-04 | 5/11/2026 8:06:12 AM | 57.4 | 40.9 | 0.0 | 1.7 | | | 1.4 | 0.0 | 94.4 |
| A-05 | 5/11/2026 8:01:26 AM | 57.3 | 40.1 | 0.2 | 2.4 | | | 1.4 | 12.0 | 76.1 |
| B-01 | 5/11/2026 10:37:28 AM | 18.0 | 20.1 | 0.0 | 61.9 | | | 0.9 | 0.0 | 89.4 |
| B-02R | 5/11/2026 10:34:40 AM | 34.5 | 27.0 | 0.3 | 38.2 | | | 1.3 | 127.3 | 100.2 |
| B-03R | 5/11/2026 10:04:48 AM | 31.2 | 28.8 | 0.0 | 40.0 | | | 1.1 | 0.0 | 83.7 |
| B-05 | 5/11/2026 10:25:34 AM | 27.2 | 27.6 | 0.0 | 45.2 | | | 1.0 | 0.0 | 88.7 |
| B-06 | 5/11/2026 10:19:19 AM | 24.1 | 23.7 | 0.0 | 52.2 | | | 1.0 | 0.0 | 80.0 |
| B-07R | 5/11/2026 9:31:57 AM | 50.1 | 35.0 | 0.0 | 14.9 | | | 1.4 | 0.0 | 91.1 |
| B-08 | 5/11/2026 10:15:29 AM | 22.4 | 22.5 | 0.0 | 55.1 | | | 1.0 | 0.0 | 88.5 |
| B-09 | 5/11/2026 9:37:05 AM | 44.3 | 32.4 | 0.0 | 23.3 | | | 1.4 | 0.0 | 92.5 |
| B-10 | 5/11/2026 9:24:54 AM | 33.5 | 30.1 | 0.0 | 36.4 | | | 1.1 | 0.0 | 88.4 |
| B-11 | 5/29/2026 3:03:30 PM | 42.2 | 34.4 | 0.0 | 23.4 | | | 1.2 | 0.0 | 96.7 |
| B-12 | 5/11/2026 10:00:30 AM | 25.7 | 27.8 | 0.1 | 46.4 | | | 0.9 | 464.0 | 92.9 |
| B-13 | 5/11/2026 9:49:42 AM | 39.4 | 30.5 | 0.0 | 30.1 | | | 1.3 | 0.0 | 87.5 |
| B-14 | 5/29/2026 3:07:12 PM | 35.6 | 31.9 | 0.0 | 32.5 | | | 1.1 | 0.0 | 92.0 |
| C-03 | 5/11/2026 7:49:46 AM | 56.3 | 41.8 | 0.0 | 1.9 | | | 1.3 | 0.0 | 66.8 |
| C-07 | 5/1/2026 3:11:09 PM | 49.6 | 36.4 | 1.6 | 12.4 | | | 1.4 | 7.8 | 88.7 |
| C-08 | 5/8/2026 1:03:42 PM | 57.6 | 38.1 | 0.0 | 4.3 | | | 1.5 | 0.0 | 98.5 |
| C-10 | 5/11/2026 9:07:51 AM | 55.2 | 38.8 | 0.2 | 5.8 | | | 1.4 | 29.0 | 89.1 |
| C-11 | 5/11/2026 8:38:28 AM | 53.8 | 37.5 | 0.0 | 8.7 | | | 1.4 | 0.0 | 82.6 |
| C-12 | 5/29/2026 12:20:26 PM | 57.3 | 38.7 | 0.0 | 4.0 | | | 1.5 | 0.0 | 83.5 |
| C-12 | 5/11/2026 1:57:43 PM | 55.4 | 41.7 | 0.0 | 2.9 | | | 1.3 | 0.0 | 99.4 |
| C-15 | 5/11/2026 2:07:31 PM | 38.0 | 27.8 | 5.9 | 28.3 | | | 1.4 | 4.8 | 95.0 |
| C-17B | 5/12/2026 10:45:10 AM | 55.4 | 41.5 | 0.0 | 3.1 | | | 1.3 | 0.0 | 109.9 |
| C-18 | 5/12/2026 1:08:06 PM | 55.5 | 40.4 | 0.0 | 4.1 | | | 1.4 | 0.0 | 103.3 |
| C-19 | 5/12/2026 12:49:10 PM | 55.4 | 40.4 | 0.0 | 4.2 | | | 1.4 | 0.0 | 99.0 |
| C-20 | 5/12/2026 12:57:51 PM | 55.4 | 40.6 | 0.0 | 4.0 | | | 1.4 | 0.0 | 98.9 |
| C-23 | 5/12/2026 11:00:46 AM | 48.4 | 44.0 | 0.0 | 7.6 | | | 1.1 | 0.0 | 128.5 |
| C-24 | 5/15/2026 9:17:41 AM | 42.5 | 34.3 | 3.1 | 20.1 | | | 1.2 | 6.5 | 103.1 |
| C-25 | 5/11/2026 2:14:04 PM | 50.4 | 42.5 | 0.0 | 7.1 | | | 1.2 | 0.0 | 127.0 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| C-26 | 5/29/2026 12:46:54 PM | 52.9 | 34.7 | 1.7 | 10.7 | | | 1.5 | 6.3 | 103.0 |
| C-26 | 5/15/2026 9:07:37 AM | 47.6 | 42.6 | 0.5 | 9.3 | | | 1.1 | 18.6 | 78.2 |
| C-27 | 5/11/2026 2:04:38 PM | 56.3 | 40.5 | 0.0 | 3.2 | | | 1.4 | 0.0 | 96.3 |
| C-28 | 5/29/2026 12:16:57 PM | 56.0 | 40.6 | 0.0 | 3.4 | | | 1.4 | 0.0 | 98.9 |
| C-28 | 5/11/2026 8:35:54 AM | 56.4 | 40.7 | 0.0 | 2.9 | | | 1.4 | 0.0 | 100.1 |
| C-29 | 5/11/2026 8:54:46 AM | 42.8 | 44.4 | 0.0 | 12.8 | | | 1.0 | 0.0 | 107.3 |
| C-30 | 5/11/2026 8:49:08 AM | 52.2 | 43.0 | 0.0 | 4.8 | | | 1.2 | 0.0 | 126.5 |
| CV-02 | 5/11/2026 8:21:58 AM | 49.6 | 41.5 | 0.0 | 8.9 | | | 1.2 | 0.0 | 120.2 |
| CV-03 | 5/11/2026 8:18:37 AM | 53.2 | 40.4 | 0.0 | 6.4 | | | 1.3 | 0.0 | 118.9 |
| CV-04 | 5/11/2026 8:14:52 AM | 52.3 | 41.0 | 0.6 | 6.1 | | | 1.3 | 10.2 | 108.8 |
| CV-05 | 5/8/2026 12:41:33 PM | 57.0 | 39.9 | 0.0 | 3.1 | | | 1.4 | 0.0 | 98.8 |
| CV-06 | 5/12/2026 8:03:49 AM | 48.3 | 49.2 | 0.0 | 2.5 | | | 1.0 | 0.0 | 90.3 |
| CV-108-52 | 5/19/2026 1:02:47 PM | 50.4 | 48.9 | 0.0 | 0.7 | | | 1.0 | 0.0 | 101.2 |
| CV-108-52 | 5/18/2026 11:07:16 AM | | | | | | 6600 | | | |
| CV-108-52 | 5/6/2026 8:30:00 AM | | | | | 100 | | | | |
| CV-108-52 | 5/1/2026 10:29:07 AM | 47.7 | 51.3 | 0.0 | 1.0 | | | 0.9 | 0.0 | 98.6 |
| CV-113 | 5/26/2026 2:01:29 PM | 9.9 | 88.1 | 0.0 | 2.0 | | | 0.1 | 0.0 | 72.8 |
| CV-113 | 5/15/2026 9:28:02 AM | 9.6 | 85.1 | 0.0 | 5.3 | | | 0.1 | 0.0 | 65.9 |
| CV-113 | 5/4/2026 7:50:00 AM | | | | | | 24000 | | | |
| CV-114 | 5/26/2026 8:58:28 AM | 1.0 | 78.6 | 0.0 | 20.4 | | | 0.0 | 0.0 | 170.5 |
| CV-114 | 5/18/2026 9:20:17 AM | 14.4 | 78.4 | 0.0 | 7.2 | | | 0.2 | 0.0 | 164.5 |
| CV-114 | 5/18/2026 9:20:00 AM | | | | | 4380 | | | | |
| CV-114 | 5/18/2026 9:17:57 AM | 14.0 | 75.7 | 0.0 | 10.3 | | | 0.2 | 0.0 | 160.9 |
| CV-114 | 5/12/2026 9:25:00 AM | | | | | 1750 | | | | |
| CV-114 | 5/12/2026 9:22:16 AM | 18.6 | 81.4 | 0.0 | 0.0 | | | 0.2 | 0.0 | 173.1 |
| CV-114 | 5/5/2026 8:35:00 AM | | | | | 3350 | | | | |
| CV-114 | 5/5/2026 8:35:00 AM | | | | | | 161800 | | | |
| CV-114 | 5/5/2026 8:32:18 AM | 2.2 | 80.1 | 0.0 | 17.7 | | | 0.0 | 0.0 | 174.3 |
| CV-114 | 5/4/2026 8:05:00 AM | | | | | | 2800 | | | |
| CV-1424 | 5/1/2026 11:22:59 AM | 50.7 | 40.1 | 0.0 | 9.2 | | | 1.3 | 0.0 | 105.2 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [°F] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-1532A | 5/28/2026 8:54:46 AM | 6.7 | 68.0 | 4.2 | 21.1 | | | 0.1 | 5.0 | 66.9 |
| CV-1532A | 5/13/2026 1:09:52 PM | 8.2 | 38.6 | 11.4 | 41.8 | | | 0.2 | 3.7 | 81.8 |
| CV-1532A | 5/13/2026 1:07:32 PM | 11.9 | 58.0 | 6.5 | 23.6 | | | 0.2 | 3.6 | 81.9 |
| CV-1532A | 5/11/2026 8:15:00 AM | | | | | 580 | | | | |
| CV-1532A | 5/11/2026 8:15:00 AM | | | | | | 61000 | | | |
| CV-1534A-PLR | 5/28/2026 1:23:27 PM | 1.9 | 62.9 | 4.8 | 30.4 | | | 0.0 | 6.3 | 183.9 |
| CV-1534A-PLR | 5/28/2026 1:20:34 PM | 1.7 | 34.7 | 10.2 | 53.4 | | | 0.0 | 5.2 | 188.7 |
| CV-1534A-PLR | 5/20/2026 9:03:59 AM | 19.4 | 77.3 | 0.0 | 3.3 | | | 0.3 | 0.0 | 186.4 |
| CV-1534A-PLR | 5/13/2026 9:42:40 AM | 12.4 | 79.0 | 1.3 | 7.3 | | | 0.2 | 5.6 | 180.9 |
| CV-1534A-PLR | 5/6/2026 10:03:56 AM | 14.6 | 74.8 | 1.7 | 8.9 | | | 0.2 | 5.2 | 181.2 |
| CV-1534A-PLR | 5/6/2026 9:55:00 AM | | | | | 2250 | | | | |
| CV-1534A-PLR | 5/6/2026 9:55:00 AM | | | | | | 123400 | | | |
| CV-1535 | 5/19/2026 12:55:31 PM | 44.5 | 49.2 | 0.0 | 6.3 | | | 0.9 | 0.0 | 119.7 |
| CV-1535 | 5/11/2026 8:25:00 AM | | | | | 100 | | | | |
| CV-1535 | 5/11/2026 8:25:00 AM | | | | | | 9800 | | | |
| CV-1535 | 5/1/2026 10:31:55 AM | 45.2 | 51.2 | 0.0 | 3.6 | | | 0.9 | 0.0 | 120.4 |
| CV-1601D | 5/22/2026 10:03:49 AM | 53.3 | 44.6 | 0.0 | 2.1 | | | 1.2 | 0.0 | 109.2 |
| CV-1601D | 5/4/2026 10:02:19 AM | 52.5 | 45.1 | 0.0 | 2.4 | | | 1.2 | 0.0 | 108.7 |
| CV-1601S | 5/22/2026 10:00:47 AM | 53.0 | 43.8 | 0.2 | 3.0 | | | 1.2 | 15.0 | 103.0 |
| CV-1601S | 5/4/2026 9:59:23 AM | 49.8 | 45.9 | 0.0 | 4.3 | | | 1.1 | 0.0 | 101.2 |
| CV-1604 | 5/4/2026 11:02:38 AM | 51.7 | 44.6 | 0.0 | 3.7 | | | 1.2 | 0.0 | 125.5 |
| CV-1701D | 5/8/2026 1:23:50 PM | 9.9 | 60.8 | 0.0 | 29.3 | | | 0.2 | 0.0 | 105.3 |
| CV-1701D | 5/8/2026 1:22:18 PM | 9.0 | 63.1 | 0.0 | 27.9 | | | 0.1 | 0.0 | 101.2 |
| CV-1701D | 5/7/2026 11:12:23 AM | 7.5 | 50.4 | 0.0 | 42.1 | | | 0.1 | 0.0 | 90.9 |
| CV-1701S | 5/7/2026 11:16:55 AM | 24.4 | 67.2 | 0.0 | 8.4 | | | 0.4 | 0.0 | 137.2 |
| CV-1701S | 5/7/2026 11:15:22 AM | 25.0 | 65.9 | 0.0 | 9.1 | | | 0.4 | 0.0 | 138.9 |
| CV-1901 | 5/19/2026 10:20:41 AM | 13.9 | 74.3 | 0.0 | 11.8 | | | 0.2 | 0.0 | 107.3 |
| CV-1901 | 5/19/2026 10:18:56 AM | 15.8 | 72.2 | 0.0 | 12.0 | | | 0.2 | 0.0 | 107.3 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-1901 | 5/12/2026 10:20:03 AM | 13.4 | 78.1 | 0.0 | 8.5 | | | 0.2 | 0.0 | 106.6 |
| CV-1901 | 5/12/2026 10:17:30 AM | 13.8 | 77.8 | 0.0 | 8.4 | | | 0.2 | 0.0 | 105.7 |
| CV-1902A | 5/28/2026 8:49:43 AM | 1.8 | 79.3 | 0.0 | 18.9 | | | 0.0 | 0.0 | 174.2 |
| CV-1902A | 5/20/2026 8:10:11 AM | 8.0 | 77.7 | 0.0 | 14.3 | | | 0.1 | 0.0 | 156.7 |
| CV-1902A | 5/14/2026 1:48:17 PM | 2.1 | 79.7 | 0.0 | 18.2 | | | 0.0 | 0.0 | 167.2 |
| CV-1902A | 5/11/2026 1:48:31 PM | 9.5 | 80.8 | 0.0 | 9.7 | | | 0.1 | 0.0 | 149.5 |
| CV-1902A | 5/11/2026 7:55:00 AM | | | | | 930 | | | | |
| CV-1902A | 5/11/2026 7:55:00 AM | | | | | | 190000 | | | |
| CV-1902A | 5/6/2026 9:06:28 AM | 10.5 | 78.0 | 0.0 | 11.5 | | | 0.1 | 0.0 | 160.9 |
| CV-1902A | 5/6/2026 9:05:00 AM | | | | | 1130 | | | | |
| CV-1902A | 5/6/2026 9:05:00 AM | | | | | | 161050 | | | |
| CV-1905 | 5/6/2026 12:45:38 PM | 56.2 | 42.9 | 0.0 | 0.9 | | | 1.3 | 0.0 | 109.2 |
| CV-1905 | 5/6/2026 10:44:14 AM | 52.8 | 45.1 | 0.0 | 2.1 | | | 1.2 | 0.0 | 103.4 |
| CV-2001 | 5/20/2026 9:55:23 AM | 11.8 | 79.2 | 0.0 | 9.0 | | | 0.1 | 0.0 | 103.2 |
| CV-2001 | 5/12/2026 8:45:06 AM | 12.0 | 76.2 | 1.0 | 10.8 | | | 0.2 | 10.8 | 76.1 |
| CV-2001 | 5/6/2026 7:50:00 AM | | | | | 780 | | | | |
| CV-2001 | 5/6/2026 7:50:00 AM | | | | | | 82000 | | | |
| CV-2001 | 5/1/2026 10:12:38 AM | 10.4 | 78.3 | 2.1 | 9.2 | | | 0.1 | 4.4 | 85.8 |
| CV-2002 | 5/28/2026 10:15:53 AM | 9.6 | 74.7 | 0.0 | 15.7 | | | 0.1 | 0.0 | 183.5 |
| CV-2002 | 5/28/2026 10:12:21 AM | 9.3 | 74.6 | 0.0 | 16.1 | | | 0.1 | 0.0 | 183.5 |
| CV-2002 | 5/20/2026 9:42:31 AM | 43.3 | 54.7 | 2.0 | 0.0 | | | 0.8 | 0.0 | 178.6 |
| CV-2002 | 5/20/2026 9:41:05 AM | 42.1 | 55.6 | 2.3 | 0.0 | | | 0.8 | 0.0 | 177.9 |
| CV-2002 | 5/13/2026 10:09:19 AM | 9.0 | 64.5 | 2.4 | 24.1 | | | 0.1 | 10.0 | 181.6 |
| CV-2002 | 5/11/2026 8:10:00 AM | | | | | 860 | | | | |
| CV-2002 | 5/11/2026 8:10:00 AM | | | | | | 83000 | | | |
| CV-2002 | 5/6/2026 1:05:00 PM | | | | | 3900 | | | | |
| CV-2002 | 5/6/2026 1:05:00 PM | | | | | | 137200 | | | |
| CV-2002 | 5/6/2026 1:02:03 PM | 35.3 | 64.7 | 0.0 | 0.0 | | | 0.5 | 0.0 | 181.7 |
| CV-2003 | 5/19/2026 1:11:41 PM | 17.2 | 69.4 | 0.8 | 12.6 | | | 0.2 | 15.8 | 110.7 |
| CV-2003 | 5/19/2026 1:06:11 PM | 21.8 | 68.9 | 0.0 | 9.3 | | | 0.3 | 0.0 | 120.8 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2003 | 5/1/2026 10:27:07 AM | 16.7 | 73.2 | 0.2 | 9.9 | | | 0.2 | 49.5 | 118.6 |
| CV-2006 | 5/28/2026 8:42:46 AM | 0.9 | 80.6 | 0.2 | 18.3 | | | 0.0 | 91.5 | 187.3 |
| CV-2006 | 5/20/2026 8:18:51 AM | 8.2 | 77.1 | 0.0 | 14.7 | | | 0.1 | 0.0 | 187.6 |
| CV-2006 | 5/14/2026 2:04:55 PM | 1.8 | 84.4 | 0.0 | 13.8 | | | 0.0 | 0.0 | 184.9 |
| CV-2006 | 5/14/2026 2:03:40 PM | 1.3 | 83.8 | 0.0 | 14.9 | | | 0.0 | 0.0 | 185.2 |
| CV-2006 | 5/11/2026 1:55:37 PM | 20.8 | 75.0 | 0.0 | 4.2 | | | 0.3 | 0.0 | 188.0 |
| CV-2006 | 5/6/2026 9:20:00 AM | | | | | 3010 | | | | |
| CV-2006 | 5/6/2026 9:20:00 AM | | | | | | 173400 | | | |
| CV-2006 | 5/6/2026 9:17:48 AM | 11.6 | 81.7 | 0.0 | 6.7 | | | 0.1 | 0.0 | 187.7 |
| CV-2007 | 5/20/2026 2:00:34 PM | 19.9 | 75.6 | 0.0 | 4.5 | | | 0.3 | 0.0 | 111.1 |
| CV-2007 | 5/8/2026 9:48:29 AM | 20.5 | 75.0 | 0.0 | 4.5 | | | 0.3 | 0.0 | 93.2 |
| CV-2007 | 5/4/2026 8:10:00 AM | | | | | | 59000 | | | |
| CV-2008 | 5/11/2026 2:03:03 PM | 26.3 | 71.4 | 0.0 | 2.3 | | | 0.4 | 0.0 | 110.1 |
| CV-2009 | 5/8/2026 9:02:48 AM | 41.0 | 59.0 | 0.0 | 0.0 | | | 0.7 | 0.0 | 136.0 |
| CV-2009 | 5/8/2026 9:00:33 AM | 41.0 | 58.4 | 0.0 | 0.6 | | | 0.7 | 0.0 | 135.5 |
| CV-2009A | 5/11/2026 1:51:42 PM | 38.9 | 58.1 | 0.0 | 3.0 | | | 0.7 | 0.0 | 129.8 |
| CV-2010 | 5/4/2026 1:15:27 PM | 37.3 | 48.6 | 0.0 | 14.1 | | | 0.8 | 0.0 | 116.0 |
| CV-2010A | 5/21/2026 10:29:08 AM | 42.7 | 46.3 | 0.0 | 11.0 | | | 0.9 | 0.0 | 141.6 |
| CV-2010A | 5/14/2026 9:40:00 AM | | | | | 235.5 | | | | |
| CV-2010A | 5/14/2026 9:38:44 AM | 31.3 | 54.8 | 0.0 | 13.9 | | | 0.6 | 0.0 | 74.7 |
| CV-2010A | 5/5/2026 1:03:57 PM | 33.6 | 49.8 | 0.0 | 16.6 | | | 0.7 | 0.0 | 146.4 |
| CV-2010A | 5/5/2026 1:03:17 PM | 34.4 | 49.2 | 0.0 | 16.4 | | | 0.7 | 0.0 | 146.2 |
| CV-2010A | 5/4/2026 1:29:04 PM | 30.9 | 52.7 | 0.0 | 16.4 | | | 0.6 | 0.0 | 148.1 |
| CV-2010A | 5/4/2026 1:27:58 PM | 30.1 | 53.0 | 0.0 | 16.9 | | | 0.6 | 0.0 | 148.7 |
| CV-2010A | 5/4/2026 1:26:56 PM | 28.3 | 51.1 | 0.0 | 20.6 | | | 0.6 | 0.0 | 146.0 |
| CV-2011 | 5/11/2026 3:39:24 PM | 47.9 | 51.3 | 0.0 | 0.8 | | | 0.9 | 0.0 | 108.0 |
| CV-2011 | 5/11/2026 3:38:18 PM | 49.0 | 51.0 | 0.0 | 0.0 | | | 1.0 | 0.0 | 99.3 |
| CV-2011A | 5/28/2026 8:38:45 AM | 4.6 | 80.9 | 0.3 | 14.2 | | | 0.1 | 47.3 | 150.3 |
| CV-2011A | 5/27/2026 3:15:12 PM | 14.4 | 55.2 | 0.0 | 30.4 | | | 0.3 | 0.0 | 148.1 |
| CV-2011A | 5/27/2026 3:14:19 PM | 15.2 | 60.5 | 0.0 | 24.3 | | | 0.3 | 0.0 | 147.5 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2011A | 5/21/2026 9:16:00 AM | 20.0 | 54.6 | 0.0 | 25.4 | | | 0.4 | 0.0 | 151.5 |
| CV-2011A | 5/20/2026 8:33:37 AM | 19.9 | 56.1 | 0.0 | 24.0 | | | 0.4 | 0.0 | 151.7 |
| CV-2011A | 5/20/2026 8:30:13 AM | 20.0 | 55.8 | 0.0 | 24.2 | | | 0.4 | 0.0 | 152.0 |
| CV-2011A | 5/14/2026 9:40:27 AM | 41.6 | 58.4 | 0.0 | 0.0 | | | 0.7 | 0.0 | 153.6 |
| CV-2011A | 5/11/2026 10:58:37 AM | 43.5 | 56.5 | 0.0 | 0.0 | | | 0.8 | 0.0 | 153.7 |
| CV-2011A | 5/4/2026 8:20:00 AM | | | | | 1040 | | | | |
| CV-2011A | 5/4/2026 8:20:00 AM | | | | | | 199300 | | | |
| CV-2011A | 5/4/2026 8:19:12 AM | 22.3 | 58.4 | 0.0 | 19.3 | | | 0.4 | 0.0 | 151.1 |
| CV-2012 | 5/11/2026 3:24:22 PM | 40.0 | 54.3 | 0.0 | 5.7 | | | 0.7 | 0.0 | 136.9 |
| CV-2012 | 5/11/2026 3:23:03 PM | 38.9 | 54.8 | 0.0 | 6.3 | | | 0.7 | 0.0 | 137.6 |
| CV-2201-PLR | 5/19/2026 11:02:27 AM | 3.0 | 80.1 | 0.0 | 16.9 | | | 0.0 | 0.0 | 130.6 |
| CV-2201-PLR | 5/19/2026 10:46:55 AM | 28.2 | 71.8 | 0.0 | 0.0 | | | 0.4 | 0.0 | 130.8 |
| CV-2201-PLR | 5/13/2026 1:54:50 PM | 2.6 | 77.8 | 0.0 | 19.6 | | | 0.0 | 0.0 | 132.9 |
| CV-2201-PLR | 5/13/2026 1:53:35 PM | 2.5 | 78.6 | 0.1 | 18.8 | | | 0.0 | 188.0 | 133.0 |
| CV-2204-PLR | 5/26/2026 1:23:17 PM | 11.0 | 82.7 | 0.0 | 6.3 | | | 0.1 | 0.0 | 148.6 |
| CV-2204-PLR | 5/18/2026 11:00:00 AM | | | | | 2500 | | | | |
| CV-2204-PLR | 5/18/2026 10:51:06 AM | 17.6 | 76.0 | 0.0 | 6.4 | | | 0.2 | 0.0 | 188.4 |
| CV-2204-PLR | 5/12/2026 10:45:00 AM | | | | | 728 | | | | |
| CV-2204-PLR | 5/12/2026 10:44:05 AM | 23.4 | 76.6 | 0.0 | 0.0 | | | 0.3 | 0.0 | 190.1 |
| CV-2204-PLR | 5/5/2026 9:48:20 AM | 12.3 | 85.4 | 0.0 | 2.3 | | | 0.1 | 0.0 | 189.9 |
| CV-2204-PLR | 5/5/2026 9:45:00 AM | | | | | 2700 | | | | |
| CV-2204-PLR | 5/5/2026 9:45:00 AM | | | | | | 137900 | | | |
| CV-2205 | 5/1/2026 2:09:09 PM | 34.2 | 48.9 | 0.0 | 16.9 | | | 0.7 | 0.0 | 120.4 |
| CV-2207 | 5/11/2026 1:42:35 PM | 44.7 | 51.2 | 0.1 | 4.0 | | | 0.9 | 40.0 | 125.8 |
| CV-2207 | 5/11/2026 1:19:38 PM | 43.2 | 54.8 | 0.0 | 2.0 | | | 0.8 | 0.0 | 127.3 |
| CV-2208A | 5/11/2026 11:49:32 AM | 31.7 | 66.0 | 0.0 | 2.3 | | | 0.5 | 0.0 | 134.0 |
| CV-2208A | 5/11/2026 11:47:10 AM | 29.9 | 59.5 | 0.0 | 10.6 | | | 0.5 | 0.0 | 134.8 |
| CV-2301 | 5/27/2026 10:38:04 AM | 13.5 | 69.3 | 0.0 | 17.2 | | | 0.2 | 0.0 | 158.0 |
| CV-2301 | 5/27/2026 10:36:57 AM | 21.7 | 65.2 | 0.1 | 13.0 | | | 0.3 | 130.0 | 160.0 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init °F Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2301 | 5/19/2026 10:16:23 AM | 47.8 | 52.2 | 0.0 | 0.0 | | | 0.9 | 0.0 | 164.0 |
| CV-2301 | 5/19/2026 10:15:36 AM | 48.3 | 51.4 | 0.3 | 0.0 | | | 0.9 | 0.0 | 165.0 |
| CV-2301 | 5/19/2026 10:15:00 AM | | | | | 990 | | | | |
| CV-2301 | 5/14/2026 11:20:00 AM | | | | | 1170 | | | | |
| CV-2301 | 5/14/2026 10:53:50 AM | 31.1 | 62.4 | 0.0 | 6.5 | | | 0.5 | 0.0 | 182.0 |
| CV-2301 | 5/14/2026 10:52:08 AM | 30.7 | 61.8 | 0.0 | 7.5 | | | 0.5 | 0.0 | 182.0 |
| CV-2301 | 5/7/2026 7:55:00 AM | | | | | 2200 | | | | |
| CV-2301 | 5/7/2026 7:55:00 AM | | | | | | 150000 | | | |
| CV-2302 | 5/22/2026 3:57:06 PM | 42.2 | 50.6 | 0.7 | 6.5 | | | 0.8 | 9.3 | 120.2 |
| CV-2302 | 5/7/2026 8:05:00 AM | | | | | 320 | | | | |
| CV-2302 | 5/7/2026 8:05:00 AM | | | | | | 53000 | | | |
| CV-2302 | 5/4/2026 9:06:38 AM | 42.4 | 51.8 | 0.1 | 5.7 | | | 0.8 | 57.0 | 121.6 |
| CV-2303 | 5/27/2026 9:02:45 AM | 1.3 | 77.6 | 0.0 | 21.1 | | | 0.0 | 0.0 | 181.2 |
| CV-2303 | 5/19/2026 8:40:00 AM | | | | | 2480 | | | | |
| CV-2303 | 5/19/2026 8:36:23 AM | 14.0 | 79.4 | 0.0 | 6.6 | | | 0.2 | 0.0 | 187.2 |
| CV-2303 | 5/13/2026 2:13:55 PM | 2.0 | 75.5 | 0.0 | 22.5 | | | 0.0 | 0.0 | 188.9 |
| CV-2303 | 5/12/2026 8:30:00 AM | | | | | 2000 | | | | |
| CV-2303 | 5/12/2026 8:30:00 AM | | | | | | 190000 | | | |
| CV-2303 | 5/5/2026 2:25:00 PM | | | | | 2170 | | | | |
| CV-2303 | 5/5/2026 2:25:00 PM | | | | | | 165800 | | | |
| CV-2303 | 5/5/2026 2:21:44 PM | 14.0 | 80.9 | 0.0 | 5.1 | | | 0.2 | 0.0 | 189.5 |
| CV-2304 | 5/19/2026 9:15:00 AM | | | | | 1650 | | | | |
| CV-2304 | 5/19/2026 9:14:49 AM | 20.7 | 74.7 | 0.0 | 4.6 | | | 0.3 | 0.0 | 167.0 |
| CV-2304 | 5/13/2026 3:03:41 PM | 7.1 | 76.4 | 0.0 | 16.5 | | | 0.1 | 0.0 | 163.5 |
| CV-2304 | 5/13/2026 3:02:59 PM | 9.0 | 74.3 | 0.0 | 16.7 | | | 0.1 | 0.0 | 162.5 |
| CV-2304 | 5/8/2026 12:51:34 PM | 1.1 | 79.4 | 0.0 | 19.5 | | | 0.0 | 0.0 | 168.1 |
| CV-2304 | 5/8/2026 12:50:06 PM | 1.5 | 79.5 | 0.0 | 19.0 | | | 0.0 | 0.0 | 165.9 |
| CV-2304 | 5/6/2026 3:00:04 PM | 1.7 | 79.1 | 0.0 | 19.2 | | | 0.0 | 0.0 | 162.7 |
| CV-2304 | 5/6/2026 3:00:00 PM | | | | | 1605 | | | | |
| CV-2304 | 5/6/2026 3:00:00 PM | | | | | | 180600 | | | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2304 | 5/6/2026 2:59:41 PM | 1.9 | 69.7 | 0.0 | 28.4 | | | 0.0 | 0.0 | 162.3 |
| CV-2305 | 5/27/2026 2:24:19 PM | 17.7 | 79.8 | 0.0 | 2.5 | | | 0.2 | 0.0 | 149.7 |
| CV-2305 | 5/27/2026 2:23:44 PM | 16.2 | 77.8 | 0.0 | 6.0 | | | 0.2 | 0.0 | 149.1 |
| CV-2305 | 5/19/2026 1:20:00 PM | | | | | 2420 | | | | |
| CV-2305 | 5/19/2026 1:19:18 PM | 38.8 | 61.2 | 0.0 | 0.0 | | | 0.6 | 0.0 | 148.9 |
| CV-2305 | 5/14/2026 10:11:00 AM | | | | | 2380 | | | | |
| CV-2305 | 5/14/2026 10:09:35 AM | 31.0 | 69.0 | 0.0 | 0.0 | | | 0.4 | 0.0 | 150.0 |
| CV-2305 | 5/12/2026 8:10:00 AM | | | | | 1700 | | | | |
| CV-2305 | 5/12/2026 8:10:00 AM | | | | | | 82000 | | | |
| CV-2305 | 5/4/2026 8:50:00 AM | 16.1 | 73.3 | 0.0 | 10.6 | | | 0.2 | 0.0 | 149.9 |
| CV-2306 | 5/26/2026 1:28:47 PM | 10.3 | 77.4 | 0.1 | 12.2 | | | 0.1 | 122.0 | 150.4 |
| CV-2306 | 5/18/2026 11:00:16 AM | 24.1 | 66.6 | 0.0 | 9.3 | | | 0.4 | 0.0 | 133.7 |
| CV-2306 | 5/18/2026 10:56:22 AM | 18.9 | 69.8 | 0.0 | 11.3 | | | 0.3 | 0.0 | 101.4 |
| CV-2306 | 5/12/2026 10:50:18 AM | 25.0 | 75.0 | 0.0 | 0.0 | | | 0.3 | 0.0 | 178.8 |
| CV-2306 | 5/12/2026 10:50:00 AM | | | | | 381 | | | | |
| CV-2306 | 5/5/2026 9:52:13 AM | 15.8 | 81.6 | 0.0 | 2.6 | | | 0.2 | 0.0 | 173.6 |
| CV-2306 | 5/5/2026 9:50:00 AM | | | | | 1800 | | | | |
| CV-2306 | 5/5/2026 9:50:00 AM | | | | | | 161900 | | | |
| CV-2308-PLR | 5/19/2026 10:58:26 AM | 3.2 | 81.1 | 0.0 | 15.7 | | | 0.0 | 0.0 | 134.2 |
| CV-2308-PLR | 5/19/2026 10:56:56 AM | 3.7 | 77.8 | 0.0 | 18.5 | | | 0.0 | 0.0 | 133.5 |
| CV-2308-PLR | 5/13/2026 2:03:12 PM | 4.0 | 78.4 | 0.0 | 17.6 | | | 0.1 | 0.0 | 144.6 |
| CV-2308-PLR | 5/13/2026 2:01:38 PM | 3.6 | 77.9 | 0.1 | 18.4 | | | 0.0 | 184.0 | 146.7 |
| CV-2310-PLR | 5/27/2026 9:22:17 AM | 1.5 | 77.1 | 0.0 | 21.4 | | | 0.0 | 0.0 | 196.0 |
| CV-2310-PLR | 5/19/2026 8:56:41 AM | 14.0 | 74.0 | 0.0 | 12.0 | | | 0.2 | 0.0 | 196.7 |
| CV-2310-PLR | 5/19/2026 8:55:00 AM | | | | | 1920 | | | | |
| CV-2310-PLR | 5/13/2026 2:22:47 PM | 3.1 | 75.3 | 0.0 | 21.6 | | | 0.0 | 0.0 | 197.6 |
| CV-2310-PLR | 5/6/2026 2:40:00 PM | | | | | | 100700 | | | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2310-PLR | 5/6/2026 2:30:00 PM | | | | | 1270 | | | | |
| CV-2310-PLR | 5/6/2026 2:26:12 PM | 1.9 | 79.7 | 0.8 | 17.6 | | | 0.0 | 22.0 | 197.3 |
| CV-2310-PLR | 5/1/2026 11:45:33 AM | 1.7 | 74.3 | 0.0 | 24.0 | | | 0.0 | 0.0 | 197.2 |
| CV-2310-PLR | 5/1/2026 11:44:42 AM | 2.0 | 80.9 | 0.0 | 17.1 | | | 0.0 | 0.0 | 197.1 |
| CV-2311 | 5/26/2026 2:01:48 PM | 22.4 | 71.6 | 0.0 | 6.0 | | | 0.3 | 0.0 | 163.6 |
| CV-2311 | 5/18/2026 2:25:36 PM | 15.6 | 71.5 | 0.0 | 12.9 | | | 0.2 | 0.0 | 169.1 |
| CV-2311 | 5/18/2026 2:25:00 PM | | | | | 2730 | | | | |
| CV-2311 | 5/18/2026 2:24:18 PM | 25.3 | 70.4 | 0.0 | 4.3 | | | 0.4 | 0.0 | 167.0 |
| CV-2311 | 5/12/2026 2:05:46 PM | 32.0 | 66.0 | 2.0 | 0.0 | | | 0.5 | 0.0 | 167.1 |
| CV-2311 | 5/12/2026 2:03:19 PM | 29.0 | 70.7 | 0.3 | 0.0 | | | 0.4 | 0.0 | 166.1 |
| CV-2311 | 5/12/2026 2:00:00 PM | | | | | 915 | | | | |
| CV-2311 | 5/5/2026 10:25:04 AM | 23.3 | 73.8 | 0.0 | 2.9 | | | 0.3 | 0.0 | 168.2 |
| CV-2311 | 5/5/2026 10:25:00 AM | | | | | 1620 | | | | |
| CV-2311 | 5/5/2026 10:25:00 AM | | | | | | 139700 | | | |
| CV-2312 | 5/27/2026 11:01:39 AM | 3.5 | 80.0 | 0.1 | 16.4 | | | 0.0 | 164.0 | 167.9 |
| CV-2312 | 5/19/2026 10:35:25 AM | 16.8 | 78.0 | 0.0 | 5.2 | | | 0.2 | 0.0 | 168.5 |
| CV-2312 | 5/19/2026 10:35:00 AM | | | | | 3070 | | | | |
| CV-2312 | 5/13/2026 11:08:10 AM | 2.5 | 78.9 | 0.4 | 18.2 | | | 0.0 | 45.5 | 169.2 |
| CV-2312 | 5/13/2026 9:06:06 AM | 7.7 | 81.8 | 0.2 | 10.3 | | | 0.1 | 51.5 | 168.2 |
| CV-2312 | 5/13/2026 8:30:00 AM | | | | | 1800 | | | | |
| CV-2312 | 5/13/2026 8:30:00 AM | | | | | | 90000 | | | |
| CV-2312 | 5/4/2026 10:29:04 AM | 1.8 | 78.3 | 0.0 | 19.9 | | | 0.0 | 0.0 | 167.9 |
| CV-2312 | 5/4/2026 10:27:12 AM | 1.5 | 62.9 | 3.1 | 32.5 | | | 0.0 | 10.5 | 168.1 |
| CV-2312 | 5/4/2026 10:15:00 AM | | | | | 3840 | | | | |
| CV-2312 | 5/4/2026 10:15:00 AM | | | | | | 120300 | | | |
| CV-2314 | 5/27/2026 1:46:16 PM | 1.4 | 85.2 | 0.0 | 13.4 | | | 0.0 | 0.0 | 179.7 |
| CV-2314 | 5/27/2026 1:45:46 PM | 1.3 | 84.1 | 0.0 | 14.6 | | | 0.0 | 0.0 | 179.8 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2314 | 5/19/2026 2:00:00 PM | | | | | 3840 | | | | |
| CV-2314 | 5/19/2026 1:53:23 PM | 23.9 | 76.1 | 0.0 | 0.0 | | | 0.3 | 0.0 | 179.3 |
| CV-2314 | 5/14/2026 1:50:56 PM | 0.7 | 90.4 | 0.0 | 8.9 | | | 0.0 | 0.0 | 178.0 |
| CV-2314 | 5/14/2026 1:49:32 PM | 0.9 | 90.5 | 0.1 | 8.5 | | | 0.0 | 85.0 | 177.6 |
| CV-2314 | 5/12/2026 8:05:00 AM | | | | | 3400 | | | | |
| CV-2314 | 5/12/2026 8:05:00 AM | | | | | | 140000 | | | |
| CV-2314 | 5/11/2026 10:32:15 AM | 8.2 | 88.6 | 0.0 | 3.2 | | | 0.1 | 0.0 | 180.2 |
| CV-2314 | 5/4/2026 9:40:25 AM | 7.3 | 77.6 | 0.0 | 15.1 | | | 0.1 | 0.0 | 177.9 |
| CV-2314 | 5/4/2026 9:40:00 AM | | | | | 4010 | | | | |
| CV-2314 | 5/4/2026 9:40:00 AM | | | | | | 110000 | | | |
| CV-2315 | 5/26/2026 10:35:23 AM | 10.0 | 79.9 | 0.1 | 10.0 | | | 0.1 | 100.0 | 182.5 |
| CV-2315 | 5/19/2026 1:35:00 PM | | | | | 4320 | | | | |
| CV-2315 | 5/19/2026 1:31:37 PM | 22.0 | 75.5 | 0.0 | 2.5 | | | 0.3 | 0.0 | 184.8 |
| CV-2315 | 5/13/2026 1:43:34 PM | 5.2 | 78.4 | 0.0 | 16.4 | | | 0.1 | 0.0 | 177.6 |
| CV-2315 | 5/13/2026 1:42:47 PM | 5.1 | 79.0 | 0.1 | 15.8 | | | 0.1 | 158.0 | 177.4 |
| CV-2315 | 5/11/2026 8:41:37 AM | 2.8 | 85.7 | 0.0 | 11.5 | | | 0.0 | 0.0 | 158.8 |
| CV-2315 | 5/7/2026 8:30:00 AM | | | | | 3900 | | | | |
| CV-2315 | 5/7/2026 8:30:00 AM | | | | | | 140000 | | | |
| CV-2315 | 5/6/2026 3:30:00 PM | | | | | 2530 | | | | |
| CV-2315 | 5/6/2026 3:30:00 PM | | | | | | 83300 | | | |
| CV-2315 | 5/6/2026 3:27:40 PM | 4.6 | 80.6 | 0.6 | 14.2 | | | 0.1 | 23.7 | 183.9 |
| CV-2315 | 5/6/2026 3:25:58 PM | 3.1 | 92.1 | 0.0 | 4.8 | | | 0.0 | 0.0 | 183.6 |
| CV-2316 | 5/11/2026 1:59:13 PM | 22.5 | 66.1 | 0.0 | 11.4 | | | 0.3 | 0.0 | 142.0 |
| CV-2316 | 5/11/2026 1:57:51 PM | 24.2 | 65.7 | 0.0 | 10.1 | | | 0.4 | 0.0 | 141.7 |
| CV-2319 | 5/12/2026 8:28:11 AM | 11.2 | 78.5 | 0.0 | 10.3 | | | 0.1 | 0.0 | 142.0 |
| CV-2319 | 5/12/2026 8:26:00 AM | 12.1 | 78.5 | 0.0 | 9.4 | | | 0.2 | 0.0 | 142.0 |
| CV-2321 | 5/27/2026 2:51:44 PM | 25.2 | 74.6 | 0.2 | 0.0 | | | 0.3 | 0.0 | 145.7 |
| CV-2321 | 5/27/2026 2:50:12 PM | 25.6 | 73.7 | 0.3 | 0.4 | | | 0.3 | 1.3 | 145.8 |
| CV-2321 | 5/19/2026 1:00:00 PM | | | | | 3560 | | | | |
| CV-2321 | 5/19/2026 12:59:11 PM | 26.1 | 73.9 | 0.0 | 0.0 | | | 0.4 | 0.0 | 149.0 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2321 | 5/19/2026 12:56:22 PM | 21.2 | 78.8 | 0.0 | 0.0 | | | 0.3 | 0.0 | 147.4 |
| CV-2321 | 5/11/2026 9:19:14 AM | 13.5 | 81.6 | 0.0 | 4.9 | | | 0.2 | 0.0 | 146.6 |
| CV-2321 | 5/11/2026 9:16:26 AM | 35.5 | 64.2 | 0.3 | 0.0 | | | 0.6 | 0.0 | 144.3 |
| CV-2321 | 5/7/2026 9:50:36 AM | 12.2 | 82.2 | 0.0 | 5.6 | | | 0.1 | 0.0 | 149.3 |
| CV-2321 | 5/7/2026 9:50:00 AM | | | | | 2785 | | | | |
| CV-2321 | 5/7/2026 9:50:00 AM | | | | | | 76800 | | | |
| CV-2321 | 5/7/2026 9:49:06 AM | 6.3 | 84.1 | 0.0 | 9.6 | | | 0.1 | 0.0 | 148.0 |
| CV-2321 | 5/1/2026 10:23:30 AM | 4.9 | 87.2 | 0.0 | 7.9 | | | 0.1 | 0.0 | 147.8 |
| CV-2321 | 5/1/2026 10:20:34 AM | 5.2 | 84.1 | 0.0 | 10.7 | | | 0.1 | 0.0 | 147.7 |
| CV-2322 | 5/26/2026 9:22:23 AM | 2.2 | 69.4 | 3.6 | 24.8 | | | 0.0 | 6.9 | 60.6 |
| CV-2322 | 5/4/2026 1:40:46 PM | 2.4 | 77.2 | 0.0 | 20.4 | | | 0.0 | 0.0 | 137.1 |
| CV-2324 | 5/6/2026 2:05:45 PM | 50.1 | 46.6 | 0.0 | 3.3 | | | 1.1 | 0.0 | 117.4 |
| CV-2324 | 5/1/2026 11:00:44 AM | 43.1 | 41.8 | 0.0 | 15.1 | | | 1.0 | 0.0 | 123.0 |
| CV-2326 | 5/19/2026 10:26:12 AM | 1.5 | 83.6 | 0.0 | 14.9 | | | 0.0 | 0.0 | 134.2 |
| CV-2326 | 5/19/2026 10:25:24 AM | 1.6 | 81.3 | 0.0 | 17.1 | | | 0.0 | 0.0 | 134.0 |
| CV-2326 | 5/1/2026 11:33:29 AM | 7.1 | 75.9 | 1.0 | 16.0 | | | 0.1 | 16.0 | 124.2 |
| CV-2327 | 5/28/2026 1:44:39 PM | 1.9 | 83.4 | 0.0 | 14.7 | | | 0.0 | 0.0 | 185.5 |
| CV-2327 | 5/20/2026 2:15:58 PM | 2.1 | 81.9 | 0.0 | 16.0 | | | 0.0 | 0.0 | 172.7 |
| CV-2327 | 5/14/2026 10:00:04 AM | 6.5 | 81.0 | 0.5 | 12.0 | | | 0.1 | 24.0 | 181.4 |
| CV-2327 | 5/14/2026 9:57:08 AM | 5.6 | 78.4 | 1.4 | 14.6 | | | 0.1 | 10.4 | 179.5 |
| CV-2327 | 5/14/2026 9:50:00 AM | | | | | 3630 | | | | |
| CV-2327 | 5/4/2026 1:23:07 PM | 2.8 | 86.5 | 0.0 | 10.7 | | | 0.0 | 0.0 | 185.1 |
| CV-2327 | 5/4/2026 1:20:00 PM | | | | | 1500 | | | | |
| CV-2327 | 5/4/2026 1:20:00 PM | | | | | | 48100 | | | |
| CV-2328 | 5/28/2026 1:37:05 PM | 13.1 | 76.8 | 0.0 | 10.1 | | | 0.2 | 0.0 | 164.9 |
| CV-2328 | 5/20/2026 2:06:30 PM | 13.2 | 72.4 | 0.0 | 14.4 | | | 0.2 | 0.0 | 167.3 |
| CV-2328 | 5/20/2026 2:05:13 PM | 13.2 | 74.3 | 0.0 | 12.5 | | | 0.2 | 0.0 | 167.2 |
| CV-2328 | 5/11/2026 1:26:04 PM | 34.7 | 65.3 | 0.0 | 0.0 | | | 0.5 | 0.0 | 144.6 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2328 | 5/7/2026 8:15:00 AM | | | | | 980 | | | | |
| CV-2328 | 5/7/2026 8:15:00 AM | | | | | | 110000 | | | |
| CV-2328 | 5/4/2026 1:07:16 PM | 5.4 | 87.3 | 0.0 | 7.3 | | | 0.1 | 0.0 | 172.5 |
| CV-2328 | 5/4/2026 1:06:42 PM | 5.8 | 82.6 | 0.0 | 11.6 | | | 0.1 | 0.0 | 171.5 |
| CV-2328 | 5/4/2026 1:05:00 PM | | | | | 661 | | | | |
| CV-2328 | 5/4/2026 1:05:00 PM | | | | | | 53600 | | | |
| CV-2333 | 5/29/2026 9:43:07 AM | 0.9 | 77.1 | 0.0 | 22.0 | | | 0.0 | 0.0 | 188.6 |
| CV-2333 | 5/26/2026 8:54:11 AM | 0.7 | 76.3 | 0.0 | 23.0 | | | 0.0 | 0.0 | 163.1 |
| CV-2333 | 5/18/2026 9:15:00 AM | | | | | 4360 | | | | |
| CV-2333 | 5/18/2026 9:12:06 AM | 8.1 | 75.1 | 0.0 | 16.8 | | | 0.1 | 0.0 | 157.9 |
| CV-2333 | 5/13/2026 7:40:00 AM | | | | | 3600 | | | | |
| CV-2333 | 5/13/2026 7:40:00 AM | | | | | | 160000 | | | |
| CV-2333 | 5/12/2026 9:35:00 AM | | | | | 2400 | | | | |
| CV-2333 | 5/12/2026 9:28:21 AM | 13.6 | 81.1 | 0.0 | 5.3 | | | 0.2 | 0.0 | 177.0 |
| CV-2333 | 5/6/2026 9:45:24 AM | 0.6 | 82.4 | 0.0 | 17.0 | | | 0.0 | 0.0 | 191.3 |
| CV-2333 | 5/6/2026 9:44:40 AM | 0.6 | 82.8 | 0.0 | 16.6 | | | 0.0 | 0.0 | 191.2 |
| CV-2333 | 5/5/2026 8:30:00 AM | | | | | 4590 | | | | |
| CV-2333 | 5/5/2026 8:30:00 AM | | | | | | 160100 | | | |
| CV-2333 | 5/5/2026 8:26:49 AM | 1.3 | 85.7 | 0.0 | 13.0 | | | 0.0 | 0.0 | 165.9 |
| CV-2334 | 5/26/2026 2:23:32 PM | 7.2 | 92.8 | 0.0 | 0.0 | | | 0.1 | 0.0 | 127.6 |
| CV-2334 | 5/13/2026 7:45:00 AM | | | | | 660 | | | | |
| CV-2334 | 5/13/2026 7:45:00 AM | | | | | | 11000 | | | |
| CV-2335 | 5/19/2026 10:11:09 AM | 47.4 | 48.7 | 0.0 | 3.9 | | | 1.0 | 0.0 | 91.5 |
| CV-2335 | 5/12/2026 10:45:40 AM | 46.3 | 48.7 | 0.7 | 4.3 | | | 1.0 | 6.1 | 89.1 |
| CV-2336 | 5/19/2026 10:14:30 AM | 45.3 | 50.4 | 0.0 | 4.3 | | | 0.9 | 0.0 | 79.6 |
| CV-2336 | 5/12/2026 10:27:38 AM | 43.5 | 49.4 | 0.0 | 7.1 | | | 0.9 | 0.0 | 73.9 |
| CV-2337 | 5/20/2026 8:23:36 AM | 18.5 | 80.9 | 0.0 | 0.6 | | | 0.2 | 0.0 | 150.2 |
| CV-2337 | 5/11/2026 2:00:37 PM | 33.1 | 66.9 | 0.0 | 0.0 | | | 0.5 | 0.0 | 149.0 |
| CV-2337 | 5/11/2026 8:05:00 AM | | | | | 3500 | | | | |
| CV-2337 | 5/11/2026 8:05:00 AM | | | | | | 130000 | | | |
| CV-2337 | 5/6/2026 9:26:13 AM | 18.7 | 81.3 | 0.0 | 0.0 | | | 0.2 | 0.0 | 149.3 |
| CV-2337 | 5/6/2026 9:25:00 AM | | | | | 5500 | | | | |
| CV-2337 | 5/6/2026 9:25:00 AM | | | | | | 122300 | | | |
| CV-2338 | 5/28/2026 8:46:22 AM | 1.3 | 78.1 | 0.0 | 20.6 | | | 0.0 | 0.0 | 189.7 |
| CV-2338 | 5/20/2026 8:15:49 AM | 9.6 | 79.0 | 0.0 | 11.4 | | | 0.1 | 0.0 | 169.1 |
| CV-2338 | 5/12/2026 10:09:33 AM | 1.8 | 82.4 | 0.0 | 15.8 | | | 0.0 | 0.0 | 168.3 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [°F] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2338 | 5/12/2026 10:05:03 AM | 1.7 | 77.8 | 0.0 | 20.5 | | | 0.0 | 0.0 | 187.0 |
| CV-2338 | 5/11/2026 1:52:50 PM | 22.3 | 77.7 | 0.0 | 0.0 | | | 0.3 | 0.0 | 172.3 |
| CV-2338 | 5/11/2026 1:52:06 PM | 17.9 | 80.9 | 0.0 | 1.2 | | | 0.2 | 0.0 | 174.6 |
| CV-2338 | 5/6/2026 9:15:00 AM | | | | | 1330 | | | | |
| CV-2338 | 5/6/2026 9:15:00 AM | | | | | | 174100 | | | |
| CV-2338 | 5/6/2026 9:13:21 AM | 14.4 | 85.6 | 0.0 | 0.0 | | | 0.2 | 0.0 | 155.1 |
| CV-2338 | 5/6/2026 9:12:07 AM | 17.6 | 78.1 | 0.4 | 3.9 | | | 0.2 | 9.8 | 156.1 |
| CV-2339 | 5/29/2026 10:41:08 AM | 0.4 | 8.0 | 18.5 | 73.1 | | | 0.1 | 4.0 | 82.2 |
| CV-2339 | 5/29/2026 10:39:26 AM | 0.6 | 12.6 | 17.3 | 69.5 | | | 0.0 | 4.0 | 79.3 |
| CV-2339 | 5/14/2026 2:06:48 PM | 11.7 | 72.7 | 0.0 | 15.6 | | | 0.2 | 0.0 | 88.2 |
| CV-2339 | 5/14/2026 2:04:49 PM | 16.0 | 72.5 | 0.0 | 11.5 | | | 0.2 | 0.0 | 88.3 |
| CV-2341 | 5/29/2026 10:30:39 AM | 9.1 | 67.8 | 1.3 | 21.8 | | | 0.1 | 16.8 | 86.6 |
| CV-2341 | 5/14/2026 1:47:09 PM | 8.8 | 69.3 | 1.1 | 20.8 | | | 0.1 | 18.9 | 92.2 |
| CV-2341 | 5/11/2026 7:50:00 AM | | | | | 850 | | | | |
| CV-2341 | 5/11/2026 7:50:00 AM | | | | | | 94000 | | | |
| CV-2342A-PLR | 5/28/2026 1:15:25 PM | 4.2 | 71.5 | 0.0 | 24.3 | | | 0.1 | 0.0 | 187.6 |
| CV-2342A-PLR | 5/20/2026 9:08:28 AM | 24.7 | 67.8 | 0.0 | 7.5 | | | 0.4 | 0.0 | 167.4 |
| CV-2342A-PLR | 5/13/2026 9:52:01 AM | 18.4 | 72.7 | 0.0 | 8.9 | | | 0.3 | 0.0 | 168.7 |
| CV-2342A-PLR | 5/6/2026 10:10:00 AM | 19.8 | 72.5 | 0.0 | 7.7 | | | 0.3 | 0.0 | 170.6 |
| CV-2343 | 5/26/2026 2:33:45 PM | 9.9 | 78.6 | 0.0 | 11.5 | | | 0.1 | 0.0 | 134.6 |
| CV-2343 | 5/19/2026 2:04:37 PM | 1.1 | 78.4 | 0.0 | 20.5 | | | 0.0 | 0.0 | 175.7 |
| CV-2343 | 5/19/2026 2:03:22 PM | 1.2 | 79.2 | 0.0 | 19.6 | | | 0.0 | 0.0 | 174.9 |
| CV-2343 | 5/6/2026 9:56:02 AM | 8.9 | 76.9 | 0.0 | 14.2 | | | 0.1 | 0.0 | 139.8 |
| CV-2344 | 5/20/2026 8:51:25 AM | 12.2 | 77.4 | 0.6 | 9.8 | | | 0.2 | 16.3 | 141.7 |
| CV-2344 | 5/13/2026 9:31:33 AM | 7.3 | 81.0 | 0.5 | 11.2 | | | 0.1 | 22.4 | 146.2 |
| CV-2344 | 5/13/2026 9:30:38 AM | 6.7 | 80.2 | 0.6 | 12.5 | | | 0.1 | 20.8 | 147.1 |
| CV-2344 | 5/11/2026 7:35:00 AM | | | | | 2900 | | | | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2344 | 5/11/2026 7:35:00 AM | | | | | | 160000 | | | |
| CV-2344 | 5/6/2026 9:52:20 AM | 10.9 | 84.8 | 0.5 | 3.8 | | | 0.1 | 7.6 | 157.7 |
| CV-2344 | 5/6/2026 9:50:00 AM | | | | | 4020 | | | | |
| CV-2344 | 5/6/2026 9:50:00 AM | | | | | | 139400 | | | |
| CV-2345 | 5/19/2026 2:17:28 PM | 14.6 | 77.6 | 0.0 | 7.8 | | | 0.2 | 0.0 | 142.7 |
| CV-2345 | 5/19/2026 2:15:18 PM | 12.4 | 83.4 | 0.0 | 4.2 | | | 0.1 | 0.0 | 143.3 |
| CV-2345 | 5/11/2026 7:30:00 AM | | | | | 580 | | | | |
| CV-2345 | 5/11/2026 7:30:00 AM | | | | | | 28000 | | | |
| CV-2345 | 5/1/2026 10:20:11 AM | 14.2 | 79.3 | 0.1 | 6.4 | | | 0.2 | 64.0 | 138.1 |
| CV-2345 | 5/1/2026 10:19:42 AM | 14.6 | 78.8 | 0.1 | 6.5 | | | 0.2 | 65.0 | 137.8 |
| CV-2346 | 5/28/2026 9:28:07 AM | 1.3 | 78.6 | 0.9 | 19.2 | | | 0.0 | 21.3 | 187.1 |
| CV-2346 | 5/20/2026 8:47:59 AM | 17.4 | 80.5 | 0.0 | 2.1 | | | 0.2 | 0.0 | 183.1 |
| CV-2346 | 5/13/2026 9:20:50 AM | 10.9 | 84.3 | 0.0 | 4.8 | | | 0.1 | 0.0 | 182.1 |
| CV-2346 | 5/6/2026 9:47:10 AM | 17.2 | 82.8 | 0.0 | 0.0 | | | 0.2 | 0.0 | 182.1 |
| CV-2346 | 5/6/2026 9:45:00 AM | | | | | 3400 | | | | |
| CV-2346 | 5/6/2026 9:45:00 AM | | | | | | 118500 | | | |
| CV-2346 | 5/6/2026 8:25:00 AM | | | | | 2200 | | | | |
| CV-2346 | 5/6/2026 8:25:00 AM | | | | | | 130000 | | | |
| CV-2346 | 5/4/2026 1:29:13 PM | 3.5 | 77.6 | 0.0 | 19.0 | | | 0.0 | 0.0 | 178.9 |
| CV-2346 | 5/4/2026 1:27:19 PM | 3.8 | 76.4 | 0.0 | 19.9 | | | 0.0 | 0.0 | 179.5 |
| CV-2347 | 5/20/2026 8:26:42 AM | 15.0 | 64.8 | 0.0 | 20.2 | | | 0.2 | 0.0 | 121.6 |
| CV-2347 | 5/6/2026 8:20:00 AM | | | | | 1100 | | | | |
| CV-2347 | 5/6/2026 8:20:00 AM | | | | | | 56000 | | | |
| CV-2347 | 5/1/2026 10:09:08 AM | 10.7 | 68.3 | 0.1 | 20.9 | | | 0.2 | 209.0 | 116.7 |
| CV-2348 | 5/20/2026 8:15:56 AM | 20.4 | 54.1 | 0.0 | 25.5 | | | 0.4 | 0.0 | 107.8 |
| CV-2348 | 5/13/2026 12:35:31 PM | 19.8 | 56.6 | 0.3 | 23.3 | | | 0.3 | 77.7 | 128.7 |
| CV-2348 | 5/6/2026 8:15:00 AM | | | | | 460 | | | | |
| CV-2348 | 5/6/2026 8:15:00 AM | | | | | | 27000 | | | |
| CV-2349 | 5/28/2026 10:20:04 AM | 2.3 | 79.8 | 0.0 | 17.9 | | | 0.0 | 0.0 | 172.2 |
| CV-2349 | 5/20/2026 10:27:38 AM | 14.1 | 75.3 | 0.0 | 10.6 | | | 0.2 | 0.0 | 162.7 |
| CV-2349 | 5/13/2026 10:48:12 AM | 4.1 | 77.3 | 0.0 | 18.6 | | | 0.1 | 0.0 | 152.3 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2349 | 5/7/2026 11:16:23 AM | 5.3 | 87.9 | 0.0 | 6.8 | | | 0.1 | 0.0 | 147.6 |
| CV-2349 | 5/7/2026 11:15:19 AM | 5.4 | 87.4 | 0.0 | 7.2 | | | 0.1 | 0.0 | 148.3 |
| CV-2349 | 5/7/2026 11:15:00 AM | | | | | 3350 | | | | |
| CV-2349 | 5/7/2026 11:15:00 AM | | | | | | 117000 | | | |
| CV-2349 | 5/5/2026 8:25:00 AM | | | | | 2600 | | | | |
| CV-2349 | 5/5/2026 8:25:00 AM | | | | | | 150000 | | | |
| CV-2350 | 5/20/2026 10:03:44 AM | 4.0 | 79.6 | 0.0 | 16.4 | | | 0.1 | 0.0 | 110.9 |
| CV-2350 | 5/13/2026 12:57:10 PM | 4.5 | 85.3 | 0.0 | 10.2 | | | 0.1 | 0.0 | 116.3 |
| CV-2350 | 5/13/2026 12:56:01 PM | 4.7 | 77.8 | 0.0 | 17.5 | | | 0.1 | 0.0 | 121.4 |
| CV-2350 | 5/11/2026 7:40:00 AM | | | | | 3700 | | | | |
| CV-2350 | 5/11/2026 7:40:00 AM | | | | | | 170000 | | | |
| CV-2351 | 5/28/2026 9:25:03 AM | 2.8 | 0.1 | 21.1 | 76.0 | | | 28.0 | 3.6 | 68.1 |
| CV-2351 | 5/28/2026 9:24:00 AM | 2.8 | 0.1 | 21.2 | 75.9 | | | 28.0 | 3.6 | 62.3 |
| CV-2351 | 5/5/2026 7:50:00 AM | | | | | 0 | | | | |
| CV-2351 | 5/5/2026 7:50:00 AM | | | | | | 1600 | | | |
| CV-2351 | 5/1/2026 9:05:14 AM | 0.0 | 1.8 | 21.2 | 77.0 | | | 0.0 | 3.6 | 83.8 |
| CV-2352 | 5/28/2026 9:16:38 AM | 5.7 | 29.9 | 13.0 | 51.4 | | | 0.2 | 4.0 | 108.7 |
| CV-2352 | 5/28/2026 9:12:47 AM | 2.6 | 25.4 | 15.5 | 56.5 | | | 0.1 | 3.6 | 99.0 |
| CV-2352 | 5/5/2026 8:00:00 AM | | | | | 1100 | | | | |
| CV-2352 | 5/5/2026 8:00:00 AM | | | | | | 190000 | | | |
| CV-2352 | 5/1/2026 9:13:24 AM | 0.0 | 0.5 | 21.4 | 78.1 | | | 0.0 | 3.6 | 115.6 |
| CV-2353-PLR | 5/20/2026 9:13:57 AM | 26.1 | 68.8 | 0.5 | 4.6 | | | 0.4 | 9.2 | 131.8 |
| CV-2353-PLR | 5/20/2026 9:13:10 AM | 25.8 | 66.6 | 1.1 | 6.5 | | | 0.4 | 5.9 | 129.5 |
| CV-2353-PLR | 5/15/2026 8:29:12 AM | 2.7 | 78.1 | 0.0 | 19.2 | | | 0.0 | 0.0 | 147.6 |
| CV-2353-PLR | 5/15/2026 8:27:25 AM | 2.6 | 77.8 | 0.0 | 19.6 | | | 0.0 | 0.0 | 147.9 |
| CV-2353-PLR | 5/14/2026 8:40:00 AM | | | | | 924 | | | | |
| CV-2353-PLR | 5/12/2026 7:35:00 AM | | | | | 760 | | | | |
| CV-2353-PLR | 5/12/2026 7:35:00 AM | | | | | | 210000 | | | |
| CV-2354 | 5/28/2026 10:36:46 AM | 4.2 | 78.4 | 0.0 | 17.4 | | | 0.1 | 0.0 | 183.8 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2354 | 5/20/2026 10:42:07 AM | 35.4 | 64.6 | 0.0 | 0.0 | | | 0.5 | 0.0 | 179.6 |
| CV-2354 | 5/20/2026 10:40:36 AM | 35.6 | 64.4 | 0.0 | 0.0 | | | 0.6 | 0.0 | 179.4 |
| CV-2354 | 5/13/2026 11:03:49 AM | 4.8 | 81.5 | 0.4 | 13.3 | | | 0.1 | 33.3 | 166.6 |
| CV-2354 | 5/13/2026 11:01:08 AM | 4.5 | 77.9 | 1.4 | 16.2 | | | 0.1 | 11.6 | 166.8 |
| CV-2354 | 5/6/2026 10:50:20 AM | 24.8 | 75.2 | 0.0 | 0.0 | | | 0.3 | 0.0 | 174.0 |
| CV-2354 | 5/6/2026 10:50:00 AM | | | | | 3190 | | | | |
| CV-2354 | 5/6/2026 10:50:00 AM | | | | | | 148000 | | | |
| CV-2354 | 5/5/2026 8:20:00 AM | | | | | 2500 | | | | |
| CV-2354 | 5/5/2026 8:20:00 AM | | | | | | 170000 | | | |
| CV-24001 | 5/19/2026 10:02:44 AM | 42.5 | 57.5 | 0.0 | 0.0 | | | 0.7 | 0.0 | 91.2 |
| CV-24001 | 5/12/2026 10:38:27 AM | 43.6 | 56.3 | 0.0 | 0.1 | | | 0.8 | 0.0 | 102.5 |
| CV-24002 | 5/19/2026 9:53:36 AM | 45.8 | 53.6 | 0.0 | 0.6 | | | 0.9 | 0.0 | 89.2 |
| CV-24002 | 5/19/2026 9:51:18 AM | 47.3 | 51.9 | 0.0 | 0.8 | | | 0.9 | 0.0 | 87.8 |
| CV-24002 | 5/1/2026 2:39:31 PM | 44.4 | 53.9 | 0.0 | 1.7 | | | 0.8 | 0.0 | 92.4 |
| CV-24003 | 5/19/2026 9:12:06 AM | 45.8 | 52.7 | 0.0 | 1.5 | | | 0.9 | 0.0 | 107.1 |
| CV-24003 | 5/1/2026 2:37:02 PM | 39.9 | 57.4 | 0.0 | 2.7 | | | 0.7 | 0.0 | 101.6 |
| CV-24004 | 5/19/2026 9:02:30 AM | 42.7 | 56.4 | 0.0 | 0.9 | | | 0.8 | 0.0 | 115.2 |
| CV-24004 | 5/1/2026 2:33:11 PM | 40.4 | 58.6 | 0.0 | 1.0 | | | 0.7 | 0.0 | 115.2 |
| CV-24006 | 5/19/2026 10:36:49 AM | 38.4 | 56.6 | 0.0 | 5.0 | | | 0.7 | 0.0 | 127.2 |
| CV-24006 | 5/1/2026 11:40:45 AM | 37.2 | 59.6 | 0.0 | 3.2 | | | 0.6 | 0.0 | 127.7 |
| CV-24007 | 5/29/2026 9:33:56 AM | 27.8 | 66.3 | 0.0 | 5.9 | | | 0.4 | 0.0 | 148.0 |
| CV-24007 | 5/26/2026 1:56:22 PM | 33.7 | 66.3 | 0.0 | 0.0 | | | 0.5 | 0.0 | 150.7 |
| CV-24007 | 5/26/2026 1:55:46 PM | 28.1 | 71.9 | 0.0 | 0.0 | | | 0.4 | 0.0 | 150.2 |
| CV-24007 | 5/19/2026 10:46:37 AM | 18.2 | 71.0 | 0.0 | 10.8 | | | 0.3 | 0.0 | 150.9 |
| CV-24007 | 5/19/2026 10:45:21 AM | 19.9 | 70.8 | 0.0 | 9.3 | | | 0.3 | 0.0 | 150.9 |
| CV-24007 | 5/15/2026 9:10:41 AM | 4.8 | 66.5 | 0.0 | 28.7 | | | 0.1 | 0.0 | 138.6 |
| CV-24007 | 5/15/2026 9:09:54 AM | 5.6 | 77.6 | 0.0 | 16.8 | | | 0.1 | 0.0 | 132.2 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24007 | 5/12/2026 8:40:00 AM | | | | | 1800 | | | | |
| CV-24007 | 5/12/2026 8:40:00 AM | | | | | | 170000 | | | |
| CV-24008 | 5/26/2026 1:50:27 PM | 7.3 | 76.2 | 0.3 | 16.2 | | | 0.1 | 54.0 | 168.9 |
| CV-24008 | 5/18/2026 2:25:00 PM | | | | | 2220 | | | | |
| CV-24008 | 5/18/2026 2:17:05 PM | 19.6 | 72.9 | 0.0 | 7.5 | | | 0.3 | 0.0 | 170.5 |
| CV-24008 | 5/12/2026 1:41:31 PM | 22.1 | 76.7 | 0.4 | 0.8 | | | 0.3 | 2.0 | 171.4 |
| CV-24008 | 5/12/2026 1:40:00 PM | | | | | 1380 | | | | |
| CV-24008 | 5/5/2026 10:20:00 AM | | | | | 831.5 | | | | |
| CV-24008 | 5/5/2026 10:20:00 AM | | | | | | 86600 | | | |
| CV-24008 | 5/5/2026 10:14:56 AM | 11.9 | 78.3 | 0.0 | 9.8 | | | 0.2 | 0.0 | 172.4 |
| CV-24009 | 5/26/2026 1:46:14 PM | 16.4 | 77.9 | 0.0 | 5.7 | | | 0.2 | 0.0 | 155.5 |
| CV-24009 | 5/18/2026 2:20:00 PM | | | | | 1480 | | | | |
| CV-24009 | 5/18/2026 2:13:29 PM | 34.9 | 65.1 | 0.0 | 0.0 | | | 0.5 | 0.0 | 155.7 |
| CV-24009 | 5/12/2026 1:35:00 PM | | | | | 384 | | | | |
| CV-24009 | 5/12/2026 1:31:36 PM | 27.2 | 72.5 | 0.3 | 0.0 | | | 0.4 | 0.0 | 156.7 |
| CV-24009 | 5/5/2026 10:15:00 AM | | | | | 1300 | | | | |
| CV-24009 | 5/5/2026 10:15:00 AM | | | | | | 135300 | | | |
| CV-24009 | 5/5/2026 10:10:10 AM | 24.6 | 75.4 | 0.0 | 0.0 | | | 0.3 | 0.0 | 156.0 |
| CV-24010 | 5/26/2026 9:45:36 AM | 7.3 | 58.5 | 7.3 | 26.9 | | | 0.1 | 3.7 | 61.0 |
| CV-24010 | 5/13/2026 1:57:52 PM | 5.4 | 49.1 | 8.0 | 37.5 | | | 0.1 | 4.7 | 89.1 |
| CV-24011 | 5/27/2026 8:51:05 AM | 6.7 | 74.3 | 0.1 | 18.9 | | | 0.1 | 189.0 | 188.3 |
| CV-24011 | 5/27/2026 8:49:35 AM | 4.2 | 76.0 | 0.1 | 19.7 | | | 0.1 | 197.0 | 188.5 |
| CV-24011 | 5/19/2026 10:30:22 AM | 6.9 | 78.8 | 0.0 | 14.3 | | | 0.1 | 0.0 | 186.9 |
| CV-24011 | 5/18/2026 2:55:00 PM | | | | | 3180 | | | | |
| CV-24011 | 5/18/2026 2:48:57 PM | 25.9 | 67.2 | 0.0 | 6.9 | | | 0.4 | 0.0 | 187.6 |
| CV-24011 | 5/12/2026 2:43:10 PM | 33.6 | 66.4 | 0.0 | 0.0 | | | 0.5 | 0.0 | 184.2 |
| CV-24011 | 5/12/2026 2:25:00 PM | | | | | 1890 | | | | |
| CV-24011 | 5/5/2026 1:10:54 PM | 26.3 | 73.6 | 0.0 | 0.1 | | | 0.4 | 0.0 | 185.2 |
| CV-24011 | 5/5/2026 1:10:00 PM | | | | | 2020 | | | | |
| CV-24011 | 5/5/2026 1:10:00 PM | | | | | | 107700 | | | |
| CV-24012 | 5/26/2026 2:14:33 PM | 12.8 | 77.0 | 0.0 | 10.2 | | | 0.2 | 0.0 | 151.8 |
| CV-24012 | 5/18/2026 2:56:25 PM | 24.9 | 71.8 | 0.0 | 3.3 | | | 0.3 | 0.0 | 161.9 |
| CV-24012 | 5/18/2026 2:50:00 PM | | | | | 1555 | | | | |
| CV-24012 | 5/18/2026 2:41:34 PM | 24.6 | 73.4 | 0.0 | 2.0 | | | 0.3 | 0.0 | 156.5 |
| CV-24012 | 5/12/2026 2:38:30 PM | 25.0 | 74.9 | 0.0 | 0.1 | | | 0.3 | 0.0 | 174.4 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [°F] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24012 | 5/12/2026 2:20:00 PM | | | | | 1230 | | | | |
| CV-24012 | 5/5/2026 1:30:00 PM | | | | | 2270 | | | | |
| CV-24012 | 5/5/2026 1:30:00 PM | | | | | | 164700 | | | |
| CV-24012 | 5/5/2026 1:26:23 PM | 9.7 | 81.5 | 0.0 | 8.8 | | | 0.1 | 0.0 | 156.8 |
| CV-24013 | 5/26/2026 9:51:46 AM | 1.2 | 42.2 | 11.4 | 45.2 | | | 0.0 | 4.0 | 93.4 |
| CV-24013 | 5/13/2026 10:06:33 AM | 1.5 | 42.5 | 10.7 | 45.3 | | | 0.0 | 4.2 | 99.4 |
| CV-24014 | 5/26/2026 1:42:04 PM | 8.6 | 75.3 | 0.0 | 16.1 | | | 0.1 | 0.0 | 177.2 |
| CV-24014 | 5/18/2026 2:15:00 PM | | | | | 2220 | | | | |
| CV-24014 | 5/18/2026 2:07:26 PM | 25.0 | 72.5 | 0.0 | 2.5 | | | 0.3 | 0.0 | 175.7 |
| CV-24014 | 5/12/2026 1:30:00 PM | | | | | 1800 | | | | |
| CV-24014 | 5/12/2026 1:26:38 PM | 18.5 | 75.5 | 0.5 | 5.5 | | | 0.2 | 11.0 | 176.3 |
| CV-24014 | 5/12/2026 1:25:28 PM | 20.9 | 72.3 | 0.8 | 6.0 | | | 0.3 | 7.5 | 176.2 |
| CV-24014 | 5/5/2026 10:10:00 AM | | | | | 2130 | | | | |
| CV-24014 | 5/5/2026 10:10:00 AM | | | | | | 190100 | | | |
| CV-24014 | 5/5/2026 10:06:41 AM | 18.2 | 78.3 | 0.0 | 3.5 | | | 0.2 | 0.0 | 176.1 |
| CV-24015 | 5/26/2026 9:48:59 AM | 4.0 | 74.0 | 0.0 | 22.0 | | | 0.1 | 0.0 | 186.4 |
| CV-24015 | 5/18/2026 10:08:30 AM | 17.5 | 72.6 | 0.0 | 9.9 | | | 0.2 | 0.0 | 183.6 |
| CV-24015 | 5/18/2026 10:06:48 AM | 17.8 | 72.8 | 0.0 | 9.4 | | | 0.2 | 0.0 | 183.6 |
| CV-24015 | 5/18/2026 10:05:03 AM | 19.0 | 71.5 | 0.0 | 9.5 | | | 0.3 | 0.0 | 183.9 |
| CV-24015 | 5/18/2026 10:05:00 AM | | | | | 1850 | | | | |
| CV-24015 | 5/12/2026 9:01:20 AM | 13.7 | 74.4 | 0.5 | 11.4 | | | 0.2 | 22.8 | 184.0 |
| CV-24015 | 5/12/2026 9:00:00 AM | | | | | 396 | | | | |
| CV-24015 | 5/12/2026 8:59:57 AM | 12.6 | 71.7 | 1.5 | 14.2 | | | 0.2 | 9.5 | 183.9 |
| CV-24015 | 5/5/2026 9:14:20 AM | 6.8 | 77.9 | 0.0 | 15.3 | | | 0.1 | 0.0 | 169.8 |
| CV-24015 | 5/5/2026 9:05:00 AM | | | | | 2140 | | | | |
| CV-24015 | 5/5/2026 9:05:00 AM | | | | | | 203600 | | | |
| CV-24016 | 5/29/2026 9:27:07 AM | 14.3 | 66.1 | 0.0 | 19.6 | | | 0.2 | 0.0 | 178.3 |
| CV-24016 | 5/27/2026 8:54:06 AM | 9.5 | 72.3 | 0.0 | 18.2 | | | 0.1 | 0.0 | 170.6 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24016 | 5/19/2026 10:04:01 AM | 13.6 | 67.4 | 0.0 | 19.0 | | | 0.2 | 0.0 | 182.9 |
| CV-24016 | 5/19/2026 10:02:01 AM | 14.0 | 67.1 | 0.0 | 19.0 | | | 0.2 | 0.0 | 182.0 |
| CV-24016 | 5/18/2026 3:00:00 PM | | | | | 2200 | | | | |
| CV-24016 | 5/18/2026 2:51:00 PM | 48.1 | 51.9 | 0.0 | 0.0 | | | 0.9 | 0.0 | 168.0 |
| CV-24016 | 5/12/2026 2:44:41 PM | 38.6 | 61.4 | 0.0 | 0.0 | | | 0.6 | 0.0 | 160.6 |
| CV-24016 | 5/12/2026 2:30:00 PM | | | | | 1330 | | | | |
| CV-24016 | 5/6/2026 1:26:28 PM | 8.3 | 74.9 | 0.0 | 16.8 | | | 0.1 | 0.0 | 170.2 |
| CV-24016 | 5/6/2026 1:25:16 PM | 9.2 | 73.8 | 0.0 | 17.0 | | | 0.1 | 0.0 | 169.5 |
| CV-24016 | 5/5/2026 1:15:29 PM | 30.4 | 69.6 | 0.0 | 0.0 | | | 0.4 | 0.0 | 161.7 |
| CV-24016 | 5/5/2026 1:15:00 PM | | | | | 1980 | | | | |
| CV-24016 | 5/5/2026 1:15:00 PM | | | | | | 96600 | | | |
| CV-24017 | 5/26/2026 2:08:15 PM | 19.6 | 76.0 | 0.6 | 3.8 | | | 0.3 | 6.3 | 170.4 |
| CV-24017 | 5/26/2026 2:07:20 PM | 17.6 | 76.3 | 0.8 | 5.3 | | | 0.2 | 6.6 | 172.4 |
| CV-24017 | 5/18/2026 2:40:00 PM | | | | | 2520 | | | | |
| CV-24017 | 5/18/2026 2:35:18 PM | 25.5 | 74.5 | 0.0 | 0.0 | | | 0.3 | 0.0 | 171.6 |
| CV-24017 | 5/12/2026 2:47:32 PM | 25.5 | 74.5 | 0.0 | 0.0 | | | 0.3 | 0.0 | 172.2 |
| CV-24017 | 5/12/2026 2:25:14 PM | 18.0 | 72.7 | 0.6 | 8.7 | | | 0.2 | 14.5 | 181.0 |
| CV-24017 | 5/12/2026 2:10:00 PM | | | | | 1230 | | | | |
| CV-24017 | 5/12/2026 8:35:00 AM | | | | | 2100 | | | | |
| CV-24017 | 5/12/2026 8:35:00 AM | | | | | | 190000 | | | |
| CV-24017 | 5/5/2026 1:20:00 PM | | | | | 2760 | | | | |
| CV-24017 | 5/5/2026 1:20:00 PM | | | | | | 155500 | | | |
| CV-24017 | 5/5/2026 1:19:34 PM | 10.8 | 78.7 | 0.6 | 9.9 | | | 0.1 | 16.5 | 159.0 |
| CV-24018 | 5/29/2026 11:06:53 AM | 9.3 | 73.2 | 1.8 | 15.7 | | | 0.1 | 8.7 | 113.7 |
| CV-24018 | 5/13/2026 3:41:42 PM | 22.3 | 71.1 | 0.9 | 5.7 | | | 0.3 | 6.3 | 109.4 |
| CV-24019 | 5/27/2026 8:57:49 AM | 1.6 | 81.3 | 0.0 | 17.1 | | | 0.0 | 0.0 | 169.8 |
| CV-24019 | 5/19/2026 8:35:00 AM | | | | | 1570 | | | | |
| CV-24019 | 5/19/2026 8:31:39 AM | 13.8 | 81.4 | 0.0 | 4.8 | | | 0.2 | 0.0 | 168.0 |
| CV-24019 | 5/13/2026 2:09:27 PM | 1.8 | 75.9 | 0.0 | 22.3 | | | 0.0 | 0.0 | 178.7 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24019 | 5/5/2026 2:30:00 PM | | | | | 2030 | | | | |
| CV-24019 | 5/5/2026 2:30:00 PM | | | | | | 141800 | | | |
| CV-24019 | 5/5/2026 2:26:07 PM | 16.0 | 80.8 | 0.0 | 3.2 | | | 0.2 | 0.0 | 182.8 |
| CV-24020 | 5/26/2026 10:31:13 AM | 0.2 | 62.7 | 7.2 | 29.9 | | | 0.0 | 4.2 | 60.3 |
| CV-24020 | 5/13/2026 1:39:38 PM | 0.7 | 67.6 | 4.2 | 27.5 | | | 0.0 | 6.5 | 84.0 |
| CV-24021 | 5/26/2026 10:19:45 AM | 0.8 | 57.4 | 0.0 | 41.8 | | | 0.0 | 0.0 | 63.1 |
| CV-24021 | 5/13/2026 10:19:21 AM | 1.5 | 58.5 | 1.5 | 38.5 | | | 0.0 | 25.7 | 74.5 |
| CV-24022-PLR | 5/26/2026 1:34:59 PM | 7.4 | 76.1 | 0.3 | 16.2 | | | 0.1 | 54.0 | 194.3 |
| CV-24022-PLR | 5/18/2026 2:10:00 PM | | | | | 2100 | | | | |
| CV-24022-PLR | 5/18/2026 2:04:39 PM | 26.0 | 72.9 | 0.0 | 1.1 | | | 0.4 | 0.0 | 194.7 |
| CV-24022-PLR | 5/12/2026 1:25:00 PM | | | | | 762 | | | | |
| CV-24022-PLR | 5/12/2026 1:18:18 PM | 20.0 | 76.4 | 0.2 | 3.4 | | | 0.3 | 17.0 | 191.4 |
| CV-24022-PLR | 5/5/2026 10:05:00 AM | | | | | 2550 | | | | |
| CV-24022-PLR | 5/5/2026 10:05:00 AM | | | | | | 199200 | | | |
| CV-24022-PLR | 5/5/2026 10:03:55 AM | 14.6 | 78.4 | 0.0 | 7.0 | | | 0.2 | 0.0 | 192.4 |
| CV-24023 | 5/26/2026 10:02:11 AM | 5.0 | 68.9 | 2.2 | 23.9 | | | 0.1 | 10.9 | 174.0 |
| CV-24023 | 5/26/2026 9:58:22 AM | 2.8 | 51.1 | 7.4 | 38.7 | | | 0.1 | 5.2 | 166.4 |
| CV-24023 | 5/18/2026 10:19:04 AM | 15.9 | 70.8 | 0.4 | 12.9 | | | 0.2 | 32.3 | 157.4 |
| CV-24023 | 5/18/2026 10:15:00 AM | 14.9 | 70.7 | 0.2 | 14.2 | | | 0.2 | 71.0 | 159.8 |
| CV-24023 | 5/12/2026 8:52:20 AM | 9.9 | 78.0 | 0.0 | 12.1 | | | 0.1 | 0.0 | 179.7 |
| CV-24023 | 5/12/2026 8:51:10 AM | 7.0 | 75.0 | 0.2 | 17.8 | | | 0.1 | 89.0 | 179.2 |
| CV-24023 | 5/12/2026 8:50:00 AM | | | | | 220.5 | | | | |
| CV-24023 | 5/6/2026 9:28:29 AM | 1.5 | 77.6 | 0.0 | 20.9 | | | 0.0 | 0.0 | 168.4 |
| CV-24023 | 5/6/2026 9:27:29 AM | 1.6 | 76.5 | 0.0 | 21.9 | | | 0.0 | 0.0 | 168.4 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24023 | 5/5/2026 9:36:54 AM | 6.7 | 77.2 | 0.0 | 16.1 | | | 0.1 | 0.0 | 180.0 |
| CV-24023 | 5/5/2026 9:35:20 AM | 6.9 | 75.4 | 0.0 | 17.7 | | | 0.1 | 0.0 | 178.4 |
| CV-24023 | 5/5/2026 9:27:58 AM | 6.0 | 76.8 | 0.0 | 17.2 | | | 0.1 | 0.0 | 157.5 |
| CV-24023 | 5/5/2026 9:25:00 AM | | | | | 1925 | | | | |
| CV-24023 | 5/5/2026 9:25:00 AM | | | | | | 215750 | | | |
| CV-24024-PLR | 5/18/2026 9:51:23 AM | 15.4 | 72.4 | 0.1 | 12.1 | | | 0.2 | 121.0 | 131.2 |
| CV-24024-PLR | 5/15/2026 9:22:07 AM | 1.2 | 77.5 | 0.3 | 21.0 | | | 0.0 | 70.0 | 157.4 |
| CV-24024-PLR | 5/15/2026 9:20:22 AM | 1.3 | 75.2 | 0.2 | 23.3 | | | 0.0 | 116.5 | 155.8 |
| CV-24025 | 5/28/2026 2:28:43 PM | 2.3 | 82.3 | 0.0 | 15.4 | | | 0.0 | 0.0 | 188.2 |
| CV-24025 | 5/19/2026 9:27:53 AM | 16.7 | 80.0 | 0.0 | 3.3 | | | 0.2 | 0.0 | 186.5 |
| CV-24025 | 5/19/2026 9:26:52 AM | 19.7 | 78.0 | 0.0 | 2.3 | | | 0.3 | 0.0 | 184.2 |
| CV-24025 | 5/19/2026 9:25:00 AM | | | | | 2300 | | | | |
| CV-24025 | 5/13/2026 2:30:31 PM | 1.8 | 77.5 | 0.0 | 20.7 | | | 0.0 | 0.0 | 187.2 |
| CV-24025 | 5/6/2026 8:57:31 AM | 1.6 | 79.7 | 0.0 | 18.7 | | | 0.0 | 0.0 | 186.2 |
| CV-24025 | 5/6/2026 8:56:37 AM | 1.8 | 77.5 | 0.0 | 20.7 | | | 0.0 | 0.0 | 186.3 |
| CV-24025 | 5/5/2026 2:13:13 PM | 13.0 | 84.0 | 0.0 | 3.0 | | | 0.2 | 0.0 | 185.0 |
| CV-24025 | 5/5/2026 2:10:00 PM | | | | | 3280 | | | | |
| CV-24025 | 5/5/2026 2:10:00 PM | | | | | | 110700 | | | |
| CV-24026 | 5/22/2026 12:25:54 PM | 2.7 | 74.6 | 2.1 | 20.6 | | | 0.0 | 9.8 | 92.5 |
| CV-24026 | 5/13/2026 1:43:47 PM | 0.5 | 76.1 | 0.9 | 22.5 | | | 0.0 | 25.0 | 88.7 |
| CV-24027 | 5/26/2026 10:11:09 AM | 2.4 | 71.7 | 2.2 | 23.7 | | | 0.0 | 10.8 | 63.6 |
| CV-24027 | 5/13/2026 10:15:50 AM | 2.6 | 52.6 | 7.9 | 36.9 | | | 0.0 | 4.7 | 74.6 |
| CV-24027 | 5/6/2026 9:11:56 AM | 2.9 | 65.8 | 3.6 | 27.7 | | | 0.0 | 7.7 | 81.7 |
| CV-24028 | 5/26/2026 1:15:48 PM | 2.7 | 73.7 | 0.0 | 23.6 | | | 0.0 | 0.0 | 187.3 |
| CV-24028 | 5/26/2026 1:13:13 PM | 2.6 | 72.6 | 0.0 | 24.8 | | | 0.0 | 0.0 | 188.1 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24028 | 5/18/2026 2:05:00 PM | | | | | 1015 | | | | |
| CV-24028 | 5/18/2026 2:01:26 PM | 33.7 | 66.3 | 0.0 | 0.0 | | | 0.5 | 0.0 | 189.1 |
| CV-24028 | 5/12/2026 1:20:00 PM | | | | | 440 | | | | |
| CV-24028 | 5/12/2026 1:14:56 PM | 21.1 | 75.5 | 0.4 | 3.0 | | | 0.3 | 7.5 | 187.8 |
| CV-24028 | 5/5/2026 10:00:52 AM | 16.0 | 75.4 | 0.0 | 8.6 | | | 0.2 | 0.0 | 193.4 |
| CV-24028 | 5/5/2026 10:00:00 AM | | | | | 1320 | | | | |
| CV-24028 | 5/5/2026 10:00:00 AM | | | | | | 186700 | | | |
| CV-24029 | 5/29/2026 11:19:30 AM | 0.3 | 10.8 | 17.9 | 71.0 | | | 0.0 | 4.0 | 87.9 |
| CV-24029 | 5/29/2026 11:15:41 AM | 0.4 | 11.1 | 17.7 | 70.8 | | | 0.0 | 4.0 | 86.3 |
| CV-24029 | 5/13/2026 2:06:48 PM | 0.5 | 8.7 | 18.0 | 72.8 | | | 0.1 | 4.0 | 85.2 |
| CV-24030 | 5/26/2026 9:14:08 AM | 1.8 | 73.9 | 0.0 | 24.3 | | | 0.0 | 0.0 | 192.1 |
| CV-24030 | 5/26/2026 9:07:52 AM | 2.1 | 74.3 | 1.1 | 22.5 | | | 0.0 | 20.5 | 192.2 |
| CV-24030 | 5/18/2026 9:35:03 AM | 11.3 | 74.3 | 0.3 | 14.1 | | | 0.2 | 47.0 | 190.7 |
| CV-24030 | 5/18/2026 9:35:00 AM | | | | | 1760 | | | | |
| CV-24030 | 5/12/2026 9:18:44 AM | 19.0 | 78.0 | 0.2 | 2.8 | | | 0.2 | 14.0 | 193.0 |
| CV-24030 | 5/12/2026 9:15:00 AM | | | | | 93.6 | | | | |
| CV-24030 | 5/5/2026 8:46:48 AM | 3.0 | 78.0 | 1.3 | 17.7 | | | 0.0 | 13.6 | 191.0 |
| CV-24030 | 5/5/2026 8:45:00 AM | | | | | 2080 | | | | |
| CV-24030 | 5/5/2026 8:45:00 AM | | | | | | 172600 | | | |
| CV-24030 | 5/5/2026 8:44:58 AM | 2.8 | 75.0 | 2.1 | 20.1 | | | 0.0 | 9.6 | 191.2 |
| CV-24031 | 5/29/2026 1:15:41 PM | 39.9 | 60.1 | 0.0 | 0.0 | | | 0.7 | 0.0 | 116.9 |
| CV-24031 | 5/22/2026 12:15:48 PM | 25.8 | 71.0 | 0.0 | 3.2 | | | 0.4 | 0.0 | 131.7 |
| CV-24031 | 5/22/2026 12:14:13 PM | 25.2 | 71.1 | 0.0 | 3.7 | | | 0.4 | 0.0 | 133.3 |
| CV-24031 | 5/12/2026 1:32:07 PM | 20.7 | 70.8 | 0.0 | 8.5 | | | 0.3 | 0.0 | 121.3 |
| CV-24032 | 5/27/2026 9:19:07 AM | 1.2 | 79.2 | 0.0 | 19.6 | | | 0.0 | 0.0 | 191.6 |
| CV-24032 | 5/27/2026 9:17:20 AM | 1.3 | 81.9 | 0.0 | 16.8 | | | 0.0 | 0.0 | 191.9 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24032 | 5/27/2026 9:09:02 AM | 1.3 | 85.0 | 0.1 | 13.6 | | | 0.0 | 136.0 | 193.5 |
| CV-24032 | 5/24/2026 12:06:03 PM | 0.6 | 38.1 | 12.6 | 48.7 | | | 0.0 | 3.9 | 147.4 |
| CV-24032 | 5/24/2026 12:02:54 PM | 0.6 | 36.7 | 12.7 | 50.0 | | | 0.0 | 3.9 | 140.3 |
| CV-24032 | 5/19/2026 8:41:47 AM | 15.2 | 80.5 | 0.0 | 4.3 | | | 0.2 | 0.0 | 137.9 |
| CV-24032 | 5/14/2026 10:31:39 AM | 1.1 | 86.8 | 0.0 | 12.1 | | | 0.0 | 0.0 | 180.5 |
| CV-24032 | 5/13/2026 2:37:29 PM | 3.5 | 81.6 | 0.0 | 14.9 | | | 0.0 | 0.0 | 151.2 |
| CV-24032 | 5/5/2026 2:20:00 PM | | | | | 1855 | | | | |
| CV-24032 | 5/5/2026 2:20:00 PM | | | | | | 129050 | | | |
| CV-24032 | 5/5/2026 2:17:41 PM | 16.4 | 83.6 | 0.0 | 0.0 | | | 0.2 | 0.0 | 150.1 |
| CV-24033 | 5/28/2026 2:24:12 PM | 1.7 | 77.5 | 0.0 | 20.8 | | | 0.0 | 0.0 | 190.8 |
| CV-24033 | 5/19/2026 8:45:00 AM | | | | | 2240 | | | | |
| CV-24033 | 5/19/2026 8:39:24 AM | 13.9 | 73.3 | 0.0 | 12.8 | | | 0.2 | 0.0 | 183.8 |
| CV-24033 | 5/13/2026 2:17:00 PM | 2.3 | 75.5 | 0.0 | 22.2 | | | 0.0 | 0.0 | 185.4 |
| CV-24033 | 5/7/2026 1:00:00 PM | | | | | | 171000 | | | |
| CV-24033 | 5/7/2026 12:59:49 PM | 5.6 | 79.7 | 0.4 | 14.3 | | | 0.1 | 35.8 | 188.1 |
| CV-24033 | 5/7/2026 1:00:00 AM | | | | | 2300 | | | | |
| CV-24034 | 5/18/2026 11:08:37 AM | 25.1 | 66.8 | 3.2 | 4.9 | | | 0.4 | 1.5 | 108.1 |
| CV-24034 | 5/18/2026 11:06:51 AM | 25.2 | 66.9 | 3.0 | 4.9 | | | 0.4 | 1.6 | 109.5 |
| CV-24034 | 5/12/2026 10:57:45 AM | 24.2 | 75.5 | 0.3 | 0.0 | | | 0.3 | 0.0 | 165.5 |
| CV-24034 | 5/12/2026 10:55:50 AM | 26.3 | 72.9 | 0.8 | 0.0 | | | 0.4 | 0.0 | 170.4 |
| CV-24034 | 5/12/2026 10:55:00 AM | | | | | 247.5 | | | | |
| CV-24034 | 5/5/2026 9:57:30 AM | 13.6 | 83.8 | 0.0 | 2.6 | | | 0.2 | 0.0 | 185.0 |
| CV-24034 | 5/5/2026 9:56:30 AM | 14.3 | 81.5 | 0.0 | 4.2 | | | 0.2 | 0.0 | 185.4 |
| CV-24034 | 5/5/2026 9:55:00 AM | | | | | 1730 | | | | |
| CV-24034 | 5/5/2026 9:55:00 AM | | | | | | 166300 | | | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [°F] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24035 | 5/26/2026 8:50:47 AM | 1.8 | 80.2 | 0.0 | 18.0 | | | 0.0 | 0.0 | 181.1 |
| CV-24035 | 5/18/2026 9:10:00 AM | | | | | 1735 | | | | |
| CV-24035 | 5/18/2026 9:05:47 AM | 10.9 | 76.7 | 0.4 | 12.0 | | | 0.1 | 30.0 | 193.5 |
| CV-24035 | 5/18/2026 9:03:47 AM | 8.3 | 81.8 | 0.0 | 9.9 | | | 0.1 | 0.0 | 189.5 |
| CV-24035 | 5/12/2026 9:40:00 AM | | | | | 2255 | | | | |
| CV-24035 | 5/12/2026 9:31:35 AM | 14.8 | 83.4 | 0.0 | 1.8 | | | 0.2 | 0.0 | 177.3 |
| CV-24035 | 5/5/2026 8:25:00 AM | | | | | 2305 | | | | |
| CV-24035 | 5/5/2026 8:25:00 AM | | | | | | 142450 | | | |
| CV-24035 | 5/5/2026 8:24:01 AM | 2.2 | 82.1 | 0.0 | 15.7 | | | 0.0 | 0.0 | 178.7 |
| CV-24036 | 5/29/2026 2:20:04 PM | 62.3 | 37.0 | 0.7 | 0.0 | | | 1.7 | 0.0 | 82.5 |
| CV-24036 | 5/24/2026 11:45:25 AM | 53.2 | 40.4 | 0.6 | 5.9 | | | 1.3 | 10.3 | 73.3 |
| CV-24036 | 5/13/2026 10:53:14 AM | 55.5 | 42.1 | 0.1 | 2.3 | | | 1.3 | 23.0 | 77.2 |
| CV-24036 | 5/6/2026 8:46:55 AM | 46.2 | 36.5 | 3.1 | 14.2 | | | 1.3 | 4.6 | 68.0 |
| CV-24037 | 5/26/2026 9:09:53 AM | 0.5 | 25.3 | 15.3 | 58.9 | | | 0.0 | 3.8 | 59.2 |
| CV-24037 | 5/26/2026 9:08:28 AM | 0.5 | 23.4 | 15.7 | 60.4 | | | 0.0 | 3.8 | 58.7 |
| CV-24037 | 5/12/2026 1:53:15 PM | 1.9 | 61.5 | 4.8 | 31.8 | | | 0.0 | 6.6 | 80.2 |
| CV-24038 | 5/27/2026 9:29:33 AM | 1.9 | 77.0 | 0.6 | 20.5 | | | 0.0 | 34.2 | 178.6 |
| CV-24038 | 5/27/2026 9:27:49 AM | 1.6 | 72.4 | 2.0 | 24.0 | | | 0.0 | 12.0 | 176.7 |
| CV-24038 | 5/19/2026 9:05:00 AM | | | | | 1240 | | | | |
| CV-24038 | 5/19/2026 9:04:35 AM | 18.1 | 76.9 | 0.0 | 5.0 | | | 0.2 | 0.0 | 170.8 |
| CV-24038 | 5/19/2026 9:04:12 AM | 16.8 | 71.9 | 0.0 | 11.3 | | | 0.2 | 0.0 | 171.1 |
| CV-24038 | 5/13/2026 2:51:36 PM | 8.5 | 72.6 | 1.0 | 17.9 | | | 0.1 | 17.9 | 172.0 |
| CV-24038 | 5/13/2026 2:48:58 PM | 7.6 | 72.8 | 1.2 | 18.4 | | | 0.1 | 15.3 | 175.2 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [°F] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24038 | 5/6/2026 3:05:00 PM | | | | | 1840 | | | | |
| CV-24038 | 5/6/2026 3:05:00 PM | | | | | | 170600 | | | |
| CV-24038 | 5/6/2026 3:04:57 PM | 2.9 | 80.4 | 0.0 | 16.7 | | | 0.0 | 0.0 | 182.3 |
| CV-24038 | 5/6/2026 3:04:21 PM | 3.1 | 80.3 | 0.0 | 16.6 | | | 0.0 | 0.0 | 181.8 |
| CV-24039 | 5/22/2026 12:04:33 PM | 1.3 | 69.8 | 0.0 | 28.9 | | | 0.0 | 0.0 | 144.7 |
| CV-24039 | 5/22/2026 12:01:47 PM | 0.9 | 69.8 | 0.0 | 29.3 | | | 0.0 | 0.0 | 149.7 |
| CV-24039 | 5/22/2026 11:58:20 AM | 4.6 | 65.2 | 0.0 | 30.2 | | | 0.1 | 0.0 | 118.9 |
| CV-24039 | 5/14/2026 1:31:24 PM | 0.6 | 1.1 | 19.6 | 78.7 | | | 0.5 | 4.0 | 87.8 |
| CV-24039 | 5/14/2026 1:29:39 PM | 0.4 | 2.1 | 19.6 | 77.9 | | | 0.2 | 4.0 | 86.4 |
| CV-24040 | 5/29/2026 9:07:46 AM | 0.4 | 79.7 | 0.0 | 19.9 | | | 0.0 | 0.0 | 172.6 |
| CV-24040 | 5/29/2026 9:07:06 AM | 0.5 | 79.9 | 0.0 | 19.6 | | | 0.0 | 0.0 | 172.3 |
| CV-24040 | 5/29/2026 9:05:56 AM | 0.6 | 78.5 | 0.0 | 20.9 | | | 0.0 | 0.0 | 171.2 |
| CV-24040 | 5/19/2026 10:40:23 AM | 4.5 | 48.6 | 9.1 | 37.8 | | | 0.1 | 4.2 | 86.6 |
| CV-24040 | 5/19/2026 10:38:38 AM | 4.0 | 43.2 | 11.0 | 41.8 | | | 0.1 | 3.8 | 85.8 |
| CV-24040 | 5/13/2026 1:35:35 PM | 0.0 | 11.8 | 16.7 | 71.5 | | | 0.0 | 4.3 | 82.2 |
| CV-24040 | 5/13/2026 1:32:34 PM | 0.0 | 11.4 | 16.8 | 71.8 | | | 0.0 | 4.3 | 81.7 |
| CV-24041 | 5/26/2026 10:04:46 AM | 8.2 | 45.5 | 8.4 | 37.9 | | | 0.2 | 4.5 | 65.0 |
| CV-24041 | 5/8/2026 8:06:27 AM | 17.8 | 55.5 | 4.2 | 22.5 | | | 0.3 | 5.4 | 70.8 |
| CV-24042 | 5/26/2026 11:03:38 AM | 13.0 | 75.4 | 0.0 | 11.6 | | | 0.2 | 0.0 | 181.8 |
| CV-24042 | 5/26/2026 11:02:42 AM | 20.7 | 71.0 | 0.0 | 8.3 | | | 0.3 | 0.0 | 184.9 |
| CV-24042 | 5/18/2026 10:55:00 AM | | | | | 2040 | | | | |
| CV-24042 | 5/18/2026 10:47:52 AM | 17.1 | 78.4 | 0.0 | 4.5 | | | 0.2 | 0.0 | 189.6 |
| CV-24042 | 5/12/2026 10:15:58 AM | 28.7 | 71.3 | 0.0 | 0.0 | | | 0.4 | 0.0 | 184.3 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24042 | 5/12/2026 10:15:09 AM | 30.9 | 69.1 | 0.0 | 0.0 | | | 0.4 | 0.0 | 180.3 |
| CV-24042 | 5/12/2026 10:15:00 AM | | | | | 45.4 | | | | |
| CV-24042 | 5/7/2026 10:08:18 AM | 3.1 | 81.3 | 0.0 | 15.6 | | | 0.0 | 0.0 | 190.6 |
| CV-24042 | 5/7/2026 10:06:45 AM | 2.9 | 86.2 | 0.0 | 10.9 | | | 0.0 | 0.0 | 191.5 |
| CV-24042 | 5/7/2026 10:05:00 AM | | | | | 2930 | | | | |
| CV-24042 | 5/7/2026 10:05:00 AM | | | | | | 139400 | | | |
| CV-24043 | 5/22/2026 2:06:15 PM | 41.3 | 56.0 | 0.4 | 2.3 | | | 0.7 | 5.8 | 91.4 |
| CV-24043 | 5/15/2026 8:55:16 AM | 41.1 | 57.2 | 0.1 | 1.6 | | | 0.7 | 16.0 | 84.7 |
| CV-24044 | 5/26/2026 8:46:58 AM | 20.0 | 76.6 | 0.0 | 3.4 | | | 0.3 | 0.0 | 130.0 |
| CV-24044 | 5/26/2026 8:42:07 AM | 20.7 | 75.5 | 0.0 | 3.8 | | | 0.3 | 0.0 | 129.1 |
| CV-24044 | 5/8/2026 12:36:24 PM | 30.9 | 58.6 | 0.4 | 10.1 | | | 0.5 | 25.3 | 87.2 |
| CV-24045 | 5/27/2026 9:33:35 AM | 1.0 | 81.8 | 0.0 | 17.2 | | | 0.0 | 0.0 | 155.6 |
| CV-24045 | 5/27/2026 9:32:48 AM | 1.1 | 80.9 | 0.0 | 18.0 | | | 0.0 | 0.0 | 152.9 |
| CV-24045 | 5/19/2026 9:11:34 AM | 20.0 | 69.4 | 0.9 | 9.7 | | | 0.3 | 10.8 | 149.7 |
| CV-24045 | 5/19/2026 9:10:36 AM | 18.5 | 72.9 | 1.5 | 7.1 | | | 0.3 | 4.7 | 151.2 |
| CV-24045 | 5/19/2026 9:10:00 AM | | | | | 1880 | | | | |
| CV-24045 | 5/13/2026 2:58:14 PM | 6.9 | 72.5 | 0.8 | 19.8 | | | 0.1 | 24.8 | 149.9 |
| CV-24045 | 5/13/2026 2:56:09 PM | 6.6 | 73.0 | 2.0 | 18.4 | | | 0.1 | 9.2 | 150.8 |
| CV-24045 | 5/6/2026 2:55:47 PM | 1.3 | 80.6 | 0.1 | 18.0 | | | 0.0 | 180.0 | 161.9 |
| CV-24045 | 5/6/2026 2:54:58 PM | 1.4 | 80.6 | 0.5 | 17.5 | | | 0.0 | 35.0 | 162.2 |
| CV-24045 | 5/6/2026 2:45:00 PM | | | | | 2510 | | | | |
| CV-24045 | 5/6/2026 2:45:00 PM | | | | | | 161800 | | | |
| CV-24046 | 5/29/2026 1:33:04 PM | 4.0 | 77.6 | 0.0 | 18.4 | | | 0.1 | 0.0 | 126.8 |
| CV-24046 | 5/29/2026 1:30:24 PM | 2.7 | 73.4 | 0.0 | 23.9 | | | 0.0 | 0.0 | 132.5 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24046 | 5/28/2026 11:56:16 AM | 0.2 | 47.1 | 9.3 | 43.4 | | | 0.0 | 4.7 | 73.3 |
| CV-24046 | 5/28/2026 11:54:22 AM | 0.2 | 46.4 | 9.5 | 43.9 | | | 0.0 | 4.6 | 72.4 |
| CV-24046 | 5/13/2026 10:32:28 AM | 0.9 | 66.4 | 3.3 | 29.4 | | | 0.0 | 8.9 | 96.0 |
| CV-24048 | 5/20/2026 2:12:35 PM | 2.2 | 54.6 | 5.1 | 38.1 | | | 0.0 | 7.5 | 97.3 |
| CV-24048 | 5/19/2026 10:25:00 AM | | | | | 2320 | | | | |
| CV-24048 | 5/8/2026 8:14:16 AM | 2.2 | 69.1 | 2.5 | 26.2 | | | 0.0 | 10.5 | 83.0 |
| CV-24049 | 5/26/2026 10:45:00 AM | 3.5 | 81.4 | 0.0 | 15.1 | | | 0.0 | 0.0 | 179.0 |
| CV-24049 | 5/26/2026 10:43:34 AM | 4.4 | 78.6 | 0.0 | 17.0 | | | 0.1 | 0.0 | 179.9 |
| CV-24049 | 5/18/2026 10:35:00 AM | | | | | 3260 | | | | |
| CV-24049 | 5/18/2026 10:30:56 AM | 18.5 | 77.4 | 0.0 | 4.1 | | | 0.2 | 0.0 | 179.6 |
| CV-24049 | 5/13/2026 8:10:00 AM | | | | | 2800 | | | | |
| CV-24049 | 5/13/2026 8:10:00 AM | | | | | | 160000 | | | |
| CV-24049 | 5/11/2026 8:49:25 AM | 2.9 | 84.8 | 0.0 | 12.3 | | | 0.0 | 0.0 | 186.0 |
| CV-24049 | 5/11/2026 8:47:07 AM | 2.8 | 83.6 | 0.0 | 13.6 | | | 0.0 | 0.0 | 186.2 |
| CV-24049 | 5/4/2026 2:40:00 PM | | | | | 705 | | | | |
| CV-24049 | 5/4/2026 2:40:00 PM | | | | | | 25900 | | | |
| CV-24049 | 5/4/2026 2:36:19 PM | 2.0 | 88.0 | 0.0 | 10.0 | | | 0.0 | 0.0 | 188.6 |
| CV-24050 | 5/22/2026 2:16:54 PM | 47.4 | 52.5 | 0.0 | 0.1 | | | 0.9 | 0.0 | 103.5 |
| CV-24050 | 5/11/2026 12:53:12 PM | 46.1 | 47.9 | 0.0 | 6.0 | | | 1.0 | 0.0 | 109.5 |
| CV-24051 | 5/26/2026 8:54:30 AM | 14.7 | 73.1 | 1.2 | 11.0 | | | 0.2 | 9.2 | 101.9 |
| CV-24051 | 5/8/2026 12:45:09 PM | 0.4 | 1.8 | 19.4 | 78.4 | | | 0.2 | 4.0 | 83.5 |
| CV-24052 | 5/20/2026 2:26:23 PM | 30.3 | 48.6 | 2.5 | 18.6 | | | 0.6 | 7.4 | 93.6 |
| CV-24052 | 5/13/2026 10:05:26 AM | 28.4 | 51.2 | 1.0 | 19.4 | | | 0.6 | 19.4 | 73.3 |
| CV-24053 | 5/20/2026 2:23:25 PM | 50.4 | 48.4 | 0.0 | 1.2 | | | 1.0 | 0.0 | 100.2 |
| CV-24053 | 5/8/2026 8:18:44 AM | 39.3 | 43.1 | 2.5 | 15.1 | | | 0.9 | 6.0 | 75.4 |
| CV-24053 | 5/7/2026 8:40:00 AM | | | | | 88 | | | | |
| CV-24053 | 5/7/2026 8:40:00 AM | | | | | | 5300 | | | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24054 | 5/26/2026 10:39:35 AM | 6.9 | 82.5 | 0.0 | 10.6 | | | 0.1 | 0.0 | 153.4 |
| CV-24054 | 5/26/2026 10:39:02 AM | 8.7 | 83.3 | 0.0 | 8.0 | | | 0.1 | 0.0 | 154.0 |
| CV-24054 | 5/18/2026 10:30:00 AM | | | | | 2560 | | | | |
| CV-24054 | 5/18/2026 10:27:38 AM | 23.7 | 76.3 | 0.0 | 0.0 | | | 0.3 | 0.0 | 145.7 |
| CV-24054 | 5/18/2026 10:26:19 AM | 23.7 | 76.3 | 0.0 | 0.0 | | | 0.3 | 0.0 | 146.7 |
| CV-24054 | 5/11/2026 8:39:09 AM | 3.6 | 88.3 | 0.0 | 8.1 | | | 0.0 | 0.0 | 163.9 |
| CV-24054 | 5/11/2026 8:36:54 AM | 3.4 | 86.9 | 0.0 | 9.7 | | | 0.0 | 0.0 | 163.3 |
| CV-24054 | 5/4/2026 2:35:00 PM | | | | | 2310 | | | | |
| CV-24054 | 5/4/2026 2:35:00 PM | | | | | | 105800 | | | |
| CV-24054 | 5/4/2026 2:34:03 PM | 3.0 | 90.5 | 0.0 | 6.5 | | | 0.0 | 0.0 | 174.6 |
| CV-24054 | 5/4/2026 1:54:35 PM | 2.2 | 77.0 | 0.0 | 20.8 | | | 0.0 | 0.0 | 147.2 |
| CV-24054 | 5/4/2026 1:51:53 PM | 2.5 | 76.4 | 0.0 | 21.1 | | | 0.0 | 0.0 | 150.7 |
| CV-24055 | 5/26/2026 9:28:17 AM | 14.4 | 66.0 | 1.1 | 18.5 | | | 0.2 | 16.8 | 137.4 |
| CV-24055 | 5/26/2026 9:27:16 AM | 14.3 | 66.2 | 1.1 | 18.4 | | | 0.2 | 16.7 | 137.4 |
| CV-24055 | 5/13/2026 8:15:00 AM | | | | | 930 | | | | |
| CV-24055 | 5/13/2026 8:15:00 AM | | | | | | 51000 | | | |
| CV-24055 | 5/12/2026 1:49:20 PM | 9.1 | 62.3 | 1.6 | 27.0 | | | 0.1 | 16.9 | 137.8 |
| CV-24055 | 5/12/2026 1:47:04 PM | 9.0 | 65.6 | 2.2 | 23.2 | | | 0.1 | 10.5 | 136.9 |
| CV-24056 | 5/19/2026 12:46:55 PM | 38.9 | 56.8 | 0.0 | 4.3 | | | 0.7 | 0.0 | 126.5 |
| CV-24056 | 5/1/2026 10:37:33 AM | 37.8 | 57.6 | 0.0 | 4.6 | | | 0.7 | 0.0 | 125.0 |
| CV-24057 | 5/22/2026 2:21:55 PM | 21.0 | 70.8 | 0.0 | 8.2 | | | 0.3 | 0.0 | 144.2 |
| CV-24057 | 5/11/2026 1:01:48 PM | 29.8 | 57.3 | 0.0 | 12.9 | | | 0.5 | 0.0 | 139.5 |
| CV-24057 | 5/11/2026 1:00:44 PM | 29.8 | 57.3 | 0.0 | 13.0 | | | 0.5 | 0.0 | 139.4 |
| CV-24058 | 5/22/2026 1:59:19 PM | 39.5 | 44.4 | 0.0 | 16.1 | | | 0.9 | 0.0 | 105.7 |
| CV-24058 | 5/11/2026 12:33:09 PM | 40.2 | 44.8 | 0.0 | 14.9 | | | 0.9 | 0.0 | 109.8 |
| CV-24059 | 5/22/2026 2:29:34 PM | 34.5 | 55.8 | 0.0 | 9.7 | | | 0.6 | 0.0 | 114.1 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24059 | 5/4/2026 9:02:50 AM | 44.9 | 48.0 | 0.0 | 7.1 | | | 0.9 | 0.0 | 124.0 |
| CV-24059 | 5/4/2026 9:01:40 AM | 44.7 | 48.6 | 0.0 | 6.7 | | | 0.9 | 0.0 | 132.9 |
| CV-24060 | 5/20/2026 1:29:27 PM | 34.9 | 55.3 | 0.5 | 9.3 | | | 0.6 | 18.6 | 112.7 |
| CV-24060 | 5/4/2026 9:39:35 AM | 36.7 | 55.7 | 0.2 | 7.4 | | | 0.7 | 37.0 | 110.4 |
| CV-24061 | 5/26/2026 11:38:49 AM | 55.3 | 44.7 | 0.0 | 0.0 | | | 1.2 | 0.0 | 99.6 |
| CV-24061 | 5/8/2026 12:59:31 PM | 50.6 | 47.5 | 0.0 | 1.9 | | | 1.1 | 0.0 | 97.7 |
| CV-24062 | 5/22/2026 11:10:33 AM | 29.1 | 63.7 | 0.4 | 6.8 | | | 0.5 | 17.0 | 144.9 |
| CV-24062 | 5/22/2026 11:08:48 AM | 28.1 | 59.3 | 1.3 | 11.3 | | | 0.5 | 8.7 | 140.5 |
| CV-24062 | 5/8/2026 1:05:26 PM | 28.8 | 63.9 | 0.0 | 7.3 | | | 0.5 | 0.0 | 133.9 |
| CV-24062 | 5/7/2026 8:17:00 AM | | | | | 890 | | | | |
| CV-24062 | 5/7/2026 8:17:00 AM | | | | | | 80000 | | | |
| CV-24062 | 5/4/2026 1:16:07 PM | 28.3 | 66.3 | 0.0 | 5.4 | | | 0.4 | 0.0 | 145.5 |
| CV-24062 | 5/4/2026 1:15:00 PM | | | | | 1080 | | | | |
| CV-24062 | 5/4/2026 1:15:00 PM | | | | | | 56100 | | | |
| CV-24063 | 5/28/2026 1:49:33 PM | 6.8 | 84.2 | 0.0 | 9.0 | | | 0.1 | 0.0 | 184.1 |
| CV-24063 | 5/20/2026 2:20:53 PM | 5.1 | 80.1 | 0.0 | 14.8 | | | 0.1 | 0.0 | 171.8 |
| CV-24063 | 5/14/2026 11:02:15 AM | 11.4 | 83.8 | 0.0 | 4.8 | | | 0.1 | 0.0 | 172.8 |
| CV-24063 | 5/14/2026 11:01:37 AM | 10.7 | 83.6 | 0.0 | 5.7 | | | 0.1 | 0.0 | 174.9 |
| CV-24063 | 5/14/2026 11:00:00 AM | | | | | 3230 | | | | |
| CV-24063 | 5/12/2026 8:20:00 AM | | | | | 2400 | | | | |
| CV-24063 | 5/12/2026 8:20:00 AM | | | | | | 120000 | | | |
| CV-24063 | 5/4/2026 1:35:00 PM | | | | | 2470 | | | | |
| CV-24063 | 5/4/2026 1:35:00 PM | | | | | | 71600 | | | |
| CV-24063 | 5/4/2026 1:34:44 PM | 3.7 | 86.5 | 0.0 | 9.8 | | | 0.0 | 0.0 | 183.9 |
| CV-24063 | 5/4/2026 1:33:24 PM | 3.7 | 84.4 | 0.6 | 11.3 | | | 0.0 | 18.8 | 182.4 |
| CV-24064 | 5/28/2026 2:15:41 PM | 1.9 | 79.7 | 0.0 | 18.4 | | | 0.0 | 0.0 | 165.5 |
| CV-24064 | 5/27/2026 1:55:09 PM | 3.2 | 80.3 | 0.0 | 16.5 | | | 0.0 | 0.0 | 191.7 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24064 | 5/19/2026 1:40:00 PM | | | | | 2470 | | | | |
| CV-24064 | 5/19/2026 1:36:22 PM | 14.8 | 76.2 | 0.0 | 9.0 | | | 0.2 | 0.0 | 192.0 |
| CV-24064 | 5/12/2026 8:15:00 AM | | | | | | 130000 | | | |
| CV-24064 | 5/11/2026 10:07:41 AM | 9.0 | 87.1 | 0.6 | 3.3 | | | 0.1 | 5.5 | 192.5 |
| CV-24064 | 5/4/2026 9:10:00 AM | | | | | 2680 | | | | |
| CV-24064 | 5/4/2026 9:10:00 AM | | | | | | 111000 | | | |
| CV-24064 | 5/4/2026 9:09:33 AM | 2.9 | 78.6 | 0.0 | 18.5 | | | 0.0 | 0.0 | 191.9 |
| CV-24065-TP1 | 5/22/2026 10:27:26 AM | 15.0 | 83.3 | 0.4 | 1.3 | | | 0.2 | 3.3 | 82.9 |
| CV-24065-TP1 | 5/12/2026 8:15:00 AM | | | | | 2000 | | | | |
| CV-24065-TP1 | 5/11/2026 1:07:25 PM | 21.6 | 73.3 | 0.0 | 5.1 | | | 0.3 | 0.0 | 100.0 |
| CV-24065-TP1 | 5/7/2026 8:35:00 AM | | | | | 530 | | | | |
| CV-24065-TP1 | 5/7/2026 8:35:00 AM | | | | | | 9800 | | | |
| CV-24066 | 5/19/2026 12:41:10 PM | 25.0 | 45.2 | 0.0 | 29.8 | | | 0.6 | 0.0 | 109.2 |
| CV-24066 | 5/11/2026 7:45:00 AM | | | | | 390 | | | | |
| CV-24066 | 5/11/2026 7:45:00 AM | | | | | | 32000 | | | |
| CV-24066 | 5/1/2026 10:40:05 AM | 23.9 | 49.4 | 0.0 | 26.7 | | | 0.5 | 0.0 | 116.8 |
| CV-24067 | 5/26/2026 2:27:02 PM | 46.1 | 53.9 | 0.0 | 0.0 | | | 0.9 | 0.0 | 152.5 |
| CV-24067 | 5/26/2026 2:26:30 PM | 46.5 | 53.5 | 0.0 | 0.0 | | | 0.9 | 0.0 | 151.9 |
| CV-24067 | 5/19/2026 8:57:43 AM | 22.4 | 63.3 | 0.0 | 14.3 | | | 0.4 | 0.0 | 160.7 |
| CV-24067 | 5/19/2026 8:55:05 AM | 22.9 | 62.9 | 0.0 | 14.2 | | | 0.4 | 0.0 | 161.3 |
| CV-24067 | 5/14/2026 11:37:11 AM | 1.5 | 89.6 | 0.0 | 8.9 | | | 0.0 | 0.0 | 134.5 |
| CV-24067 | 5/14/2026 11:35:44 AM | 1.4 | 88.2 | 0.0 | 10.4 | | | 0.0 | 0.0 | 134.4 |
| CV-24068 | 5/26/2026 12:08:57 PM | 32.9 | 44.5 | 0.0 | 22.6 | | | 0.7 | 0.0 | 129.6 |
| CV-24068 | 5/26/2026 12:06:40 PM | 35.2 | 40.4 | 0.0 | 24.4 | | | 0.9 | 0.0 | 133.8 |
| CV-24068 | 5/1/2026 11:18:00 AM | 29.8 | 49.8 | 0.0 | 20.4 | | | 0.6 | 0.0 | 115.0 |
| CV-24069 | 5/28/2026 9:36:45 AM | 31.0 | 44.0 | 0.3 | 24.7 | | | 0.7 | 82.4 | 93.4 |
| CV-24069 | 5/28/2026 9:35:46 AM | 31.9 | 43.5 | 0.4 | 24.2 | | | 0.7 | 69.2 | 94.5 |
| CV-24069 | 5/28/2026 9:30:09 AM | 35.8 | 42.0 | 0.3 | 21.9 | | | 0.9 | 70.5 | 96.1 |
| CV-24069 | 5/13/2026 8:20:00 AM | | | | | 470 | | | | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24069 | 5/13/2026 8:20:00 AM | | | | | | 40000 | | | |
| CV-24069 | 5/4/2026 8:56:06 AM | 40.8 | 48.8 | 0.0 | 10.4 | | | 0.8 | 0.0 | 93.2 |
| CV-24070 | 5/20/2026 2:35:15 PM | 11.4 | 77.9 | 0.0 | 10.7 | | | 0.1 | 0.0 | 136.2 |
| CV-24070 | 5/20/2026 2:34:29 PM | 10.7 | 77.6 | 0.0 | 11.7 | | | 0.1 | 0.0 | 136.2 |
| CV-24070 | 5/20/2026 2:33:43 PM | 10.2 | 74.7 | 0.0 | 15.1 | | | 0.1 | 0.0 | 133.9 |
| CV-24070 | 5/7/2026 8:20:00 AM | | | | | 1300 | | | | |
| CV-24070 | 5/7/2026 8:20:00 AM | | | | | | 110000 | | | |
| CV-24070 | 5/4/2026 9:12:35 AM | 22.4 | 63.4 | 0.0 | 14.2 | | | 0.4 | 0.0 | 130.4 |
| CV-24070 | 5/4/2026 9:11:52 AM | 23.2 | 65.8 | 1.9 | 9.1 | | | 0.4 | 4.8 | 131.6 |
| CV-24071 | 5/20/2026 1:35:21 PM | 42.5 | 52.0 | 0.0 | 5.5 | | | 0.8 | 0.0 | 123.3 |
| CV-24071 | 5/7/2026 8:10:00 AM | | | | | 190 | | | | |
| CV-24071 | 5/7/2026 8:10:00 AM | | | | | | 24000 | | | |
| CV-24071 | 5/4/2026 9:43:04 AM | 43.3 | 55.1 | 0.0 | 1.6 | | | 0.8 | 0.0 | 121.6 |
| CV-24072 | 5/22/2026 2:05:23 PM | 44.2 | 49.9 | 0.0 | 5.9 | | | 0.9 | 0.0 | 110.0 |
| CV-24072 | 5/4/2026 2:18:34 PM | 46.1 | 52.5 | 0.0 | 1.4 | | | 0.9 | 0.0 | 88.1 |
| CV-24072 | 5/4/2026 2:17:08 PM | 45.4 | 52.9 | 0.0 | 1.7 | | | 0.9 | 0.0 | 87.1 |
| CV-24073-TP1 | 5/26/2026 8:45:28 AM | 3.8 | 86.1 | 0.0 | 10.1 | | | 0.0 | 0.0 | 132.2 |
| CV-24073-TP1 | 5/26/2026 8:40:41 AM | 3.6 | 85.9 | 0.0 | 10.5 | | | 0.0 | 0.0 | 133.1 |
| CV-24073-TP1 | 5/8/2026 1:15:17 PM | 2.2 | 84.6 | 0.0 | 13.2 | | | 0.0 | 0.0 | 128.3 |
| CV-24073-TP1 | 5/6/2026 2:09:30 PM | 2.1 | 82.8 | 0.0 | 15.1 | | | 0.0 | 0.0 | 126.2 |
| CV-24074 | 5/22/2026 11:17:05 AM | 2.4 | 88.1 | 0.0 | 9.5 | | | 0.0 | 0.0 | 110.1 |
| CV-24074 | 5/6/2026 2:14:23 PM | 1.7 | 86.3 | 0.0 | 12.0 | | | 0.0 | 0.0 | 108.1 |
| CV-24075-TP1 | 5/29/2026 4:03:35 PM | 1.0 | 76.4 | 2.8 | 19.8 | | | 0.0 | 7.1 | 186.8 |
| CV-24075-TP1 | 5/29/2026 4:02:17 PM | 0.9 | 72.9 | 2.6 | 23.6 | | | 0.0 | 9.1 | 186.7 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [°F] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24075-TP1 | 5/11/2026 10:25:13 AM | 10.2 | 84.1 | 0.8 | 4.9 | | | 0.1 | 6.1 | 109.5 |
| CV-24075-TP1 | 5/4/2026 9:21:41 AM | 1.0 | 82.0 | 0.8 | 16.2 | | | 0.0 | 20.3 | 187.2 |
| CV-24075-TP1 | 5/4/2026 9:20:10 AM | 1.0 | 81.8 | 0.8 | 16.4 | | | 0.0 | 20.5 | 61.7 |
| CV-24075-TP1 | 5/4/2026 9:20:00 AM | | | | | 2260 | | | | |
| CV-24075-TP1 | 5/4/2026 9:20:00 AM | | | | | | 114700 | | | |
| CV-24076 | 5/27/2026 2:11:24 PM | 18.4 | 77.4 | 0.0 | 4.2 | | | 0.2 | 0.0 | 171.8 |
| CV-24076 | 5/19/2026 1:30:00 PM | | | | | 1590 | | | | |
| CV-24076 | 5/19/2026 1:22:53 PM | 33.9 | 66.0 | 0.0 | 0.1 | | | 0.5 | 0.0 | 167.7 |
| CV-24076 | 5/14/2026 10:30:00 AM | | | | | 1750 | | | | |
| CV-24076 | 5/14/2026 10:29:35 AM | 33.9 | 66.1 | 0.0 | 0.0 | | | 0.5 | 0.0 | 174.4 |
| CV-24076 | 5/4/2026 9:06:09 AM | 10.7 | 68.0 | 0.2 | 21.1 | | | 0.2 | 105.5 | 176.8 |
| CV-24076 | 5/4/2026 9:05:00 AM | | | | | 1650 | | | | |
| CV-24076 | 5/4/2026 9:05:00 AM | | | | | | 62700 | | | |
| CV-24077 | 5/28/2026 9:18:10 AM | 10.1 | 65.9 | 0.0 | 24.0 | | | 0.2 | 0.0 | 146.7 |
| CV-24077 | 5/28/2026 9:16:41 AM | 12.2 | 59.5 | 0.0 | 28.3 | | | 0.2 | 0.0 | 143.6 |
| CV-24077 | 5/20/2026 8:03:01 AM | 19.8 | 53.5 | 0.0 | 26.7 | | | 0.4 | 0.0 | 142.7 |
| CV-24077 | 5/11/2026 1:38:12 PM | 18.6 | 77.2 | 0.0 | 4.2 | | | 0.2 | 0.0 | 146.5 |
| CV-24077 | 5/7/2026 10:50:33 AM | 7.9 | 86.4 | 0.1 | 5.6 | | | 0.1 | 56.0 | 149.0 |
| CV-24077 | 5/7/2026 10:50:00 AM | | | | | 2820 | | | | |
| CV-24077 | 5/7/2026 10:50:00 AM | | | | | | 72200 | | | |
| CV-24077 | 5/1/2026 10:03:08 AM | 4.6 | 87.3 | 0.0 | 8.1 | | | 0.1 | 0.0 | 151.0 |
| CV-24077 | 5/1/2026 10:01:59 AM | 5.0 | 82.0 | 0.0 | 13.0 | | | 0.1 | 0.0 | 150.8 |
| CV-24078 | 5/19/2026 8:40:05 AM | 30.6 | 56.6 | 0.0 | 12.9 | | | 0.5 | 0.0 | 130.6 |
| CV-24078 | 5/19/2026 8:35:10 AM | 31.3 | 56.0 | 0.0 | 12.7 | | | 0.6 | 0.0 | 130.8 |
| CV-24078 | 5/19/2026 8:34:05 AM | 31.8 | 55.9 | 0.0 | 12.3 | | | 0.6 | 0.0 | 130.6 |
| CV-24078 | 5/19/2026 8:31:45 AM | 31.4 | 56.2 | 0.0 | 12.5 | | | 0.6 | 0.0 | 132.3 |
| CV-24078 | 5/1/2026 10:43:48 AM | 29.1 | 62.6 | 0.0 | 8.3 | | | 0.5 | 0.0 | 126.2 |
| CV-24079-TP8 | 5/26/2026 12:13:32 PM | 37.3 | 49.5 | 0.0 | 13.2 | | | 0.8 | 0.0 | 137.7 |
| CV-24079-TP8 | 5/26/2026 12:12:54 PM | 37.0 | 50.4 | 0.1 | 12.5 | | | 0.7 | 125.0 | 137.8 |
| CV-24079-TP8 | 5/11/2026 1:15:47 PM | 52.0 | 48.0 | 0.0 | 0.0 | | | 1.1 | 0.0 | 140.1 |
| CV-24079-TP8 | 5/7/2026 10:41:06 AM | 2.3 | 87.0 | 0.0 | 10.7 | | | 0.0 | 0.0 | 170.5 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [°F] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24079-TP8 | 5/7/2026 10:40:00 AM | | | | | 2450 | | | | |
| CV-24079-TP8 | 5/7/2026 10:40:00 AM | | | | | | 111700 | | | |
| CV-24079-TP8 | 5/7/2026 10:38:33 AM | 2.0 | 89.4 | 0.0 | 8.6 | | | 0.0 | 0.0 | 153.6 |
| CV-24079-TP8 | 5/1/2026 11:22:57 AM | 18.3 | 70.1 | 0.0 | 11.6 | | | 0.3 | 0.0 | 152.4 |
| CV-24079-TP8 | 5/1/2026 11:22:12 AM | 18.3 | 65.8 | 0.0 | 15.9 | | | 0.3 | 0.0 | 156.5 |
| CV-24080 | 5/21/2026 9:36:06 AM | 9.3 | 81.5 | 0.0 | 9.2 | | | 0.1 | 0.0 | 117.1 |
| CV-24080 | 5/1/2026 11:09:29 AM | 30.9 | 64.8 | 0.0 | 4.3 | | | 0.5 | 0.0 | 122.9 |
| CV-24081-TP1 | 5/20/2026 2:26:51 PM | 45.3 | 53.1 | 0.0 | 1.6 | | | 0.9 | 0.0 | 118.2 |
| CV-24081-TP1 | 5/20/2026 2:25:55 PM | 46.0 | 52.8 | 0.0 | 1.2 | | | 0.9 | 0.0 | 117.7 |
| CV-24081-TP1 | 5/14/2026 10:40:33 AM | 48.3 | 51.7 | 0.0 | 0.0 | | | 0.9 | 0.0 | 119.9 |
| CV-24082 | 5/20/2026 11:24:26 AM | 30.9 | 69.1 | 0.0 | 0.0 | | | 0.4 | 0.0 | 124.3 |
| CV-24082 | 5/4/2026 10:11:50 AM | 28.2 | 68.8 | 0.0 | 3.0 | | | 0.4 | 0.0 | 110.9 |
| CV-24083 | 5/20/2026 1:53:17 PM | 42.6 | 55.2 | 0.0 | 2.2 | | | 0.8 | 0.0 | 126.8 |
| CV-24083 | 5/4/2026 9:58:27 AM | 41.5 | 56.2 | 0.0 | 2.3 | | | 0.7 | 0.0 | 108.0 |
| CV-24083 | 5/4/2026 9:56:08 AM | 40.4 | 57.1 | 0.0 | 2.5 | | | 0.7 | 0.0 | 104.4 |
| CV-24084-TP1 | 5/27/2026 10:49:57 AM | 2.9 | 76.5 | 0.0 | 20.6 | | | 0.0 | 0.0 | 180.2 |
| CV-24084-TP1 | 5/19/2026 10:24:00 AM | 18.9 | 81.1 | 0.0 | 0.0 | | | 0.2 | 0.0 | 180.6 |
| CV-24084-TP1 | 5/11/2026 1:05:39 PM | 11.7 | 61.3 | 0.0 | 27.0 | | | 0.2 | 0.0 | 179.6 |
| CV-24084-TP1 | 5/4/2026 2:08:40 PM | 3.7 | 91.0 | 0.0 | 5.3 | | | 0.0 | 0.0 | 180.6 |
| CV-24084-TP1 | 5/4/2026 2:05:00 PM | | | | | 2420 | | | | |
| CV-24084-TP1 | 5/4/2026 2:05:00 PM | | | | | | 77400 | | | |
| CV-24085 | 5/20/2026 10:07:30 AM | 30.3 | 38.8 | 0.2 | 30.7 | | | 0.8 | 153.5 | 127.9 |
| CV-24085 | 5/1/2026 10:47:32 AM | 37.5 | 41.5 | 0.0 | 21.0 | | | 0.9 | 0.0 | 126.5 |
| CV-24086 | 5/21/2026 9:49:26 AM | 50.8 | 47.9 | 0.0 | 1.3 | | | 1.1 | 0.0 | 114.8 |
| CV-24086 | 5/1/2026 11:00:38 AM | 46.9 | 48.2 | 0.0 | 4.9 | | | 1.0 | 0.0 | 115.7 |
| CV-24087 | 5/20/2026 1:36:05 PM | 44.6 | 46.5 | 0.0 | 9.0 | | | 1.0 | 0.0 | 119.0 |
| CV-24087 | 5/5/2026 10:43:05 AM | 44.2 | 46.2 | 0.0 | 9.7 | | | 1.0 | 0.0 | 115.8 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [°F] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24088 | 5/28/2026 9:04:04 AM | 41.7 | 53.9 | 0.0 | 4.4 | | | 0.8 | 0.0 | 99.1 |
| CV-24088 | 5/4/2026 1:51:55 PM | 38.8 | 59.1 | 0.0 | 2.1 | | | 0.7 | 0.0 | 100.0 |
| CV-24089 | 5/20/2026 11:52:44 AM | 4.1 | 7.2 | 17.8 | 70.9 | | | 0.6 | 4.0 | 99.0 |
| CV-24089 | 5/20/2026 11:51:37 AM | 2.5 | 7.4 | 18.4 | 71.7 | | | 0.3 | 3.9 | 99.1 |
| CV-24089 | 5/4/2026 11:15:57 AM | 1.8 | 5.2 | 19.0 | 74.0 | | | 0.3 | 3.9 | 71.8 |
| CV-24089 | 5/4/2026 11:14:40 AM | 6.5 | 13.0 | 15.6 | 64.9 | | | 0.5 | 4.2 | 73.5 |
| CV-24090 | 5/20/2026 11:45:41 AM | 38.1 | 60.9 | 0.0 | 1.0 | | | 0.6 | 0.0 | 120.1 |
| CV-24090 | 5/11/2026 1:42:21 PM | 40.4 | 50.2 | 0.0 | 9.4 | | | 0.8 | 0.0 | 113.1 |
| CV-24090 | 5/6/2026 1:52:09 PM | 28.5 | 69.1 | 0.0 | 2.4 | | | 0.4 | 0.0 | 115.8 |
| CV-24091 | 5/21/2026 9:33:38 AM | 55.6 | 44.4 | 0.0 | 0.0 | | | 1.3 | 0.0 | 99.3 |
| CV-24091 | 5/4/2026 2:15:54 PM | 52.7 | 44.3 | 0.2 | 2.8 | | | 1.2 | 14.0 | 77.1 |
| CV-24092 | 5/6/2026 10:10:24 AM | 51.5 | 43.3 | 0.0 | 5.2 | | | 1.2 | 0.0 | 120.5 |
| CV-24093 | 5/22/2026 12:11:17 PM | 45.0 | 55.0 | 0.0 | 0.0 | | | 0.8 | 0.0 | 119.2 |
| CV-24093 | 5/1/2026 3:13:57 PM | 42.6 | 57.4 | 0.0 | 0.0 | | | 0.7 | 0.0 | 118.5 |
| CV-24094 | 5/22/2026 11:49:38 AM | 10.9 | 80.1 | 2.0 | 7.0 | | | 0.1 | 3.5 | 88.9 |
| CV-24094 | 5/22/2026 11:48:00 AM | 7.9 | 59.7 | 6.8 | 25.6 | | | 0.1 | 3.8 | 88.3 |
| CV-24094 | 5/1/2026 2:32:48 PM | 15.0 | 77.5 | 2.1 | 5.4 | | | 0.2 | 2.6 | 88.4 |
| CV-24095 | 5/28/2026 10:32:51 AM | 2.9 | 83.5 | 0.0 | 13.6 | | | 0.0 | 0.0 | 179.1 |
| CV-24095 | 5/28/2026 10:30:18 AM | 2.3 | 83.9 | 0.3 | 13.5 | | | 0.0 | 45.0 | 179.6 |
| CV-24095 | 5/20/2026 10:30:33 AM | 27.6 | 72.4 | 0.0 | 0.0 | | | 0.4 | 0.0 | 178.6 |
| CV-24095 | 5/14/2026 1:28:11 PM | 3.5 | 81.5 | 0.0 | 15.0 | | | 0.0 | 0.0 | 178.8 |
| CV-24095 | 5/13/2026 10:56:02 AM | 2.2 | 71.8 | 2.8 | 23.2 | | | 0.0 | 8.3 | 178.3 |
| CV-24095 | 5/13/2026 10:53:04 AM | 3.2 | 82.3 | 0.0 | 14.5 | | | 0.0 | 0.0 | 177.8 |
| CV-24095 | 5/6/2026 10:46:15 AM | 19.2 | 80.8 | 0.0 | 0.0 | | | 0.2 | 0.0 | 176.2 |
| CV-24095 | 5/6/2026 10:45:00 AM | | | | | 2700 | | | | |
| CV-24095 | 5/6/2026 10:45:00 AM | | | | | | 108400 | | | |
| CV-24095 | 5/6/2026 8:05:00 AM | | | | | 2800 | | | | |
| CV-24095 | 5/6/2026 8:05:00 AM | | | | | | 160000 | | | |
| CV-24096 | 5/20/2026 10:19:24 AM | 37.6 | 55.4 | 0.3 | 6.7 | | | 0.7 | 22.3 | 95.9 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24096 | 5/12/2026 9:25:00 AM | 25.3 | 37.4 | 7.2 | 30.1 | | | 0.7 | 4.2 | 82.9 |
| CV-24096 | 5/12/2026 9:22:51 AM | 23.5 | 34.9 | 8.4 | 33.2 | | | 0.7 | 4.0 | 74.1 |
| CV-24097 | 5/20/2026 10:29:27 AM | 46.8 | 46.8 | 1.3 | 5.1 | | | 1.0 | 3.9 | 86.7 |
| CV-24097 | 5/20/2026 10:28:10 AM | 42.7 | 45.7 | 2.3 | 9.3 | | | 0.9 | 4.0 | 88.4 |
| CV-24097 | 5/12/2026 9:16:39 AM | 44.2 | 50.8 | 0.4 | 4.6 | | | 0.9 | 11.5 | 81.1 |
| CV-24097 | 5/12/2026 9:13:02 AM | 48.0 | 51.4 | 0.0 | 0.6 | | | 0.9 | 0.0 | 78.9 |
| CV-24098 | 5/20/2026 10:43:25 AM | 42.4 | 38.2 | 4.4 | 15.0 | | | 1.1 | 3.4 | 95.4 |
| CV-24098 | 5/3/2026 11:01:16 AM | 48.9 | 43.0 | 0.4 | 7.8 | | | 1.1 | 20.9 | 70.4 |
| CV-24098 | 5/3/2026 11:00:24 AM | 48.8 | 41.9 | 0.8 | 8.5 | | | 1.2 | 10.8 | 69.0 |
| CV-24098 | 5/1/2026 10:01:03 AM | 42.9 | 39.3 | 3.2 | 14.6 | | | 1.1 | 4.6 | 92.6 |
| CV-24099 | 5/20/2026 10:48:09 AM | 24.4 | 66.0 | 0.0 | 9.6 | | | 0.4 | 0.0 | 97.5 |
| CV-24099 | 5/3/2026 10:28:51 AM | 12.3 | 75.2 | 0.0 | 12.5 | | | 0.2 | 0.0 | 61.5 |
| CV-24099 | 5/3/2026 10:28:19 AM | 11.4 | 75.4 | 0.0 | 13.2 | | | 0.2 | 0.0 | 61.2 |
| CV-24099 | 5/3/2026 10:27:26 AM | 11.8 | 76.1 | 0.0 | 12.1 | | | 0.2 | 0.0 | 61.8 |
| CV-24099 | 5/1/2026 10:08:04 AM | 9.4 | 35.2 | 8.1 | 47.3 | | | 0.3 | 5.8 | 83.2 |
| CV-24100 | 5/28/2026 10:02:06 AM | 21.1 | 74.5 | 0.0 | 4.4 | | | 0.3 | 0.0 | 147.5 |
| CV-24100 | 5/20/2026 10:01:19 AM | 46.0 | 54.0 | 0.0 | 0.0 | | | 0.9 | 0.0 | 150.0 |
| CV-24100 | 5/20/2026 10:00:42 AM | 46.9 | 53.1 | 0.0 | 0.0 | | | 0.9 | 0.0 | 149.8 |
| CV-24100 | 5/20/2026 9:37:52 AM | 21.4 | 75.4 | 0.0 | 3.2 | | | 0.3 | 0.0 | 151.2 |
| CV-24100 | 5/20/2026 9:36:36 AM | 21.3 | 73.8 | 0.0 | 4.9 | | | 0.3 | 0.0 | 150.8 |
| CV-24100 | 5/13/2026 10:42:49 AM | 21.8 | 78.0 | 0.1 | 0.1 | | | 0.3 | 1.0 | 143.5 |
| CV-24100 | 5/13/2026 10:41:16 AM | 21.9 | 77.3 | 0.2 | 0.6 | | | 0.3 | 3.0 | 143.4 |
| CV-24100 | 5/13/2026 8:25:00 AM | | | | | 83 | | | | |
| CV-24100 | 5/13/2026 8:25:00 AM | | | | | | 8800 | | | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [°F] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24100 | 5/7/2026 11:06:06 AM | 25.4 | 74.4 | 0.2 | 0.0 | | | 0.3 | 0.0 | 146.0 |
| CV-24100 | 5/7/2026 11:05:00 AM | | | | | 228 | | | | |
| CV-24100 | 5/7/2026 11:05:00 AM | | | | | | 8500 | | | |
| CV-24100 | 5/7/2026 11:04:29 AM | 25.0 | 75.0 | 0.0 | 0.0 | | | 0.3 | 0.0 | 144.3 |
| CV-24100 | 5/1/2026 10:25:18 AM | 19.0 | 80.8 | 0.1 | 0.1 | | | 0.2 | 1.0 | 143.7 |
| CV-24101 | 5/20/2026 9:41:50 AM | 41.4 | 54.8 | 0.0 | 3.8 | | | 0.8 | 0.0 | 112.0 |
| CV-24101 | 5/12/2026 8:51:03 AM | 38.8 | 53.6 | 1.3 | 6.3 | | | 0.7 | 4.8 | 112.6 |
| CV-24101 | 5/6/2026 7:40:00 AM | | | | | 0 | | | | |
| CV-24101 | 5/6/2026 7:40:00 AM | | | | | | 940 | | | |
| CV-24101 | 5/1/2026 10:20:22 AM | 42.6 | 57.1 | 0.3 | 0.0 | | | 0.7 | 0.0 | 106.9 |
| CV-24102 | 5/19/2026 10:30:38 AM | 47.8 | 50.6 | 0.0 | 1.6 | | | 0.9 | 0.0 | 103.0 |
| CV-24102 | 5/4/2026 9:42:22 AM | 46.9 | 48.6 | 0.0 | 4.5 | | | 1.0 | 0.0 | 89.0 |
| CV-24103 | 5/20/2026 9:42:52 AM | 51.2 | 46.6 | 0.3 | 1.9 | | | 1.1 | 6.3 | 95.8 |
| CV-24103 | 5/4/2026 9:28:18 AM | 45.1 | 47.3 | 0.0 | 7.6 | | | 1.0 | 0.0 | 95.3 |
| CV-24104 | 5/20/2026 12:16:58 PM | 38.2 | 61.8 | 0.0 | 0.0 | | | 0.6 | 0.0 | 96.4 |
| CV-24104 | 5/4/2026 9:39:11 AM | 47.2 | 49.7 | 0.0 | 3.1 | | | 0.9 | 0.0 | 93.5 |
| CV-24105 | 5/20/2026 11:35:42 AM | 49.1 | 47.9 | 0.0 | 3.0 | | | 1.0 | 0.0 | 109.2 |
| CV-24105 | 5/4/2026 9:49:47 AM | 48.8 | 44.1 | 0.0 | 7.1 | | | 1.1 | 0.0 | 102.2 |
| CV-24106 | 5/28/2026 12:51:23 PM | 41.2 | 35.5 | 0.0 | 23.3 | | | 1.2 | 0.0 | 127.7 |
| CV-24106 | 5/20/2026 2:33:03 PM | 42.1 | 41.2 | 0.0 | 16.7 | | | 1.0 | 0.0 | 129.0 |
| CV-24106 | 5/8/2026 11:07:42 AM | 45.0 | 41.9 | 0.0 | 13.1 | | | 1.1 | 0.0 | 126.9 |
| CV-24107 | 5/4/2026 11:30:05 AM | 49.4 | 44.0 | 0.0 | 6.6 | | | 1.1 | 0.0 | 121.4 |
| CV-24108 | 5/28/2026 12:33:54 PM | 52.8 | 41.3 | 0.0 | 5.9 | | | 1.3 | 0.0 | 128.9 |
| CV-24108 | 5/4/2026 1:40:16 PM | 51.4 | 42.1 | 0.0 | 6.5 | | | 1.2 | 0.0 | 128.7 |
| CV-24109 | 5/4/2026 11:58:26 AM | 31.3 | 38.9 | 1.2 | 28.6 | | | 0.8 | 23.8 | 104.9 |
| CV-24110 | 5/1/2026 10:54:33 AM | 41.0 | 52.3 | 0.0 | 6.7 | | | 0.8 | 0.0 | 128.1 |
| CV-24111 | 5/1/2026 11:14:00 AM | 46.5 | 44.4 | 0.0 | 9.1 | | | 1.0 | 0.0 | 111.1 |
| CV-24112 | 5/1/2026 11:04:34 AM | 45.6 | 39.1 | 0.1 | 15.2 | | | 1.2 | 152.0 | 128.0 |
| CV-24114 | 5/5/2026 2:47:36 PM | 54.3 | 44.2 | 0.0 | 1.5 | | | 1.2 | 0.0 | 119.9 |
| CV-24116 | 5/11/2026 9:58:53 AM | 46.5 | 45.0 | 0.2 | 8.3 | | | 1.0 | 41.5 | 125.3 |
| CV-24117 | 5/28/2026 12:44:53 PM | 45.1 | 40.4 | 0.0 | 14.5 | | | 1.1 | 0.0 | 100.9 |
| CV-24117 | 5/4/2026 10:48:48 AM | 44.0 | 42.9 | 0.0 | 13.1 | | | 1.0 | 0.0 | 90.5 |
| CV-24118 | 5/11/2026 1:37:44 PM | 24.3 | 68.8 | 0.0 | 6.9 | | | 0.4 | 0.0 | 129.0 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24119 | 5/8/2026 2:33:20 PM | 47.0 | 46.0 | 0.0 | 7.0 | | | 1.0 | 0.0 | 144.0 |
| CV-24119 | 5/8/2026 2:32:34 PM | 47.6 | 45.4 | 0.0 | 7.0 | | | 1.0 | 0.0 | 144.4 |
| CV-24119 | 5/7/2026 10:38:27 AM | 42.1 | 47.6 | 0.0 | 10.3 | | | 0.9 | 0.0 | 135.9 |
| CV-24119 | 5/7/2026 10:35:25 AM | 42.2 | 45.0 | 0.0 | 12.8 | | | 0.9 | 0.0 | 137.1 |
| CV-24120 | 5/26/2026 2:15:09 PM | 4.8 | 80.5 | 0.6 | 14.1 | | | 0.1 | 23.5 | 88.0 |
| CV-24120 | 5/11/2026 10:28:50 AM | 4.7 | 71.6 | 0.4 | 23.4 | | | 0.1 | 58.4 | 98.1 |
| CV-24120 | 5/4/2026 8:00:00 AM | | | | | | 110000 | | | |
| CV-24121 | 5/26/2026 2:08:29 PM | 0.6 | 5.5 | 20.0 | 73.9 | | | 0.1 | 3.7 | 75.9 |
| CV-24121 | 5/11/2026 10:33:56 AM | 2.8 | 15.0 | 16.1 | 66.2 | | | 0.2 | 4.1 | 101.4 |
| CV-24121 | 5/11/2026 10:33:18 AM | 2.7 | 15.3 | 16.4 | 65.6 | | | 0.2 | 4.0 | 101.3 |
| CV-24121 | 5/4/2026 7:55:00 AM | | | | | | 2700 | | | |
| CV-24122 | 5/29/2026 9:40:41 AM | 35.0 | 40.3 | 4.3 | 20.4 | | | 0.9 | 4.7 | 81.1 |
| CV-24122 | 5/29/2026 9:33:20 AM | 27.0 | 31.6 | 7.9 | 33.5 | | | 0.9 | 4.2 | 76.1 |
| CV-24122 | 5/6/2026 10:31:06 AM | 42.7 | 42.2 | 3.2 | 11.9 | | | 1.0 | 3.7 | 84.9 |
| CV-24122 | 5/4/2026 8:20:00 AM | | | | | | 9100 | | | |
| CV-24123 | 5/28/2026 11:46:50 AM | 37.2 | 57.7 | 0.0 | 5.1 | | | 0.6 | 0.0 | 116.6 |
| CV-24123 | 5/28/2026 11:46:25 AM | 38.4 | 57.2 | 0.0 | 4.4 | | | 0.7 | 0.0 | 116.1 |
| CV-24123 | 5/15/2026 11:28:22 AM | 31.9 | 66.2 | 0.0 | 1.9 | | | 0.5 | 0.0 | 113.9 |
| CV-24123 | 5/15/2026 11:24:46 AM | 26.4 | 69.8 | 0.0 | 3.8 | | | 0.4 | 0.0 | 84.7 |
| CV-24123 | 5/14/2026 10:54:34 AM | 32.0 | 67.3 | 0.0 | 0.7 | | | 0.5 | 0.0 | 117.2 |
| CV-24123 | 5/14/2026 10:53:53 AM | 30.9 | 69.1 | 0.0 | 0.0 | | | 0.4 | 0.0 | 116.7 |
| CV-24124 | 5/29/2026 11:28:31 AM | 5.9 | 81.4 | 0.2 | 12.5 | | | 0.1 | 62.5 | 127.0 |
| CV-24125-TP2 | 5/26/2026 1:56:27 PM | 28.5 | 67.0 | 1.1 | 3.4 | | | 0.4 | 3.1 | 99.9 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24125-TP2 | 5/13/2026 7:55:00 AM | | | | | 30 | | | | |
| CV-24125-TP2 | 5/13/2026 7:55:00 AM | | | | | | 1300 | | | |
| CV-24126 | 5/26/2026 10:58:38 AM | 4.1 | 73.0 | 0.0 | 22.9 | | | 0.1 | 0.0 | 186.7 |
| CV-24126 | 5/22/2026 12:29:20 PM | 1.6 | 76.9 | 0.0 | 21.5 | | | 0.0 | 0.0 | 188.7 |
| CV-24126 | 5/22/2026 12:28:40 PM | 1.3 | 75.6 | 0.0 | 23.1 | | | 0.0 | 0.0 | 188.3 |
| CV-24126 | 5/18/2026 10:50:00 AM | | | | | 4310 | | | | |
| CV-24126 | 5/18/2026 10:44:28 AM | 14.0 | 77.0 | 0.0 | 9.0 | | | 0.2 | 0.0 | 186.7 |
| CV-24126 | 5/18/2026 10:43:37 AM | 21.8 | 71.7 | 0.0 | 6.5 | | | 0.3 | 0.0 | 186.3 |
| CV-24126 | 5/12/2026 10:30:00 AM | | | | | 2330 | | | | |
| CV-24126 | 5/12/2026 10:28:41 AM | 20.1 | 79.9 | 0.0 | 0.0 | | | 0.3 | 0.0 | 188.0 |
| CV-24126 | 5/4/2026 2:50:00 PM | | | | | 3200 | | | | |
| CV-24126 | 5/4/2026 2:50:00 PM | | | | | | 135800 | | | |
| CV-24126 | 5/4/2026 2:40:40 PM | 1.9 | 85.1 | 0.0 | 13.0 | | | 0.0 | 0.0 | 186.0 |
| CV-24127 | 5/7/2026 10:22:55 AM | 2.9 | 83.5 | 0.0 | 13.6 | | | 0.0 | 0.0 | 141.8 |
| CV-24127 | 5/7/2026 10:21:43 AM | 2.7 | 82.2 | 0.0 | 15.1 | | | 0.0 | 0.0 | 141.6 |
| CV-24127 | 5/7/2026 10:20:00 AM | | | | | 5180 | | | | |
| CV-24127 | 5/7/2026 10:20:00 AM | | | | | | 152600 | | | |
| CV-24127 | 5/4/2026 8:15:00 AM | | | | | | 160000 | | | |
| CV-24128 | 5/26/2026 2:25:15 PM | 33.4 | 51.7 | 1.2 | 13.7 | | | 0.6 | 11.4 | 91.8 |
| CV-24128 | 5/13/2026 7:50:00 AM | | | | | 210 | | | | |
| CV-24128 | 5/13/2026 7:50:00 AM | | | | | | 11000 | | | |
| CV-24128 | 5/8/2026 9:33:23 AM | 34.4 | 43.9 | 1.2 | 20.5 | | | 0.8 | 17.1 | 99.5 |
| CV-24129 | 5/26/2026 1:33:50 PM | 41.4 | 57.8 | 0.3 | 0.5 | | | 0.7 | 1.7 | 119.2 |
| CV-24129 | 5/8/2026 9:24:27 AM | 45.2 | 52.9 | 0.0 | 1.9 | | | 0.9 | 0.0 | 121.8 |
| CV-24130 | 5/26/2026 1:42:41 PM | 20.1 | 69.3 | 0.0 | 10.6 | | | 0.3 | 0.0 | 108.8 |
| CV-24131 | 5/29/2026 1:47:07 PM | 45.4 | 49.7 | 0.2 | 4.7 | | | 0.9 | 23.5 | 120.4 |
| CV-24132 | 5/6/2026 10:15:34 AM | 52.7 | 44.1 | 0.0 | 3.2 | | | 1.2 | 0.0 | 129.2 |
| CV-24133 | 5/7/2026 9:28:04 AM | 51.8 | 40.2 | 0.0 | 8.0 | | | 1.3 | 0.0 | 121.5 |
| CV-24134-TP1 | 5/26/2026 10:55:47 AM | 23.2 | 68.7 | 0.0 | 8.1 | | | 0.3 | 0.0 | 151.0 |
| CV-24134-TP1 | 5/18/2026 10:45:00 AM | | | | | 3300 | | | | |
| CV-24134-TP1 | 5/18/2026 10:39:38 AM | 33.1 | 64.1 | 0.0 | 2.8 | | | 0.5 | 0.0 | 151.5 |
| CV-24134-TP1 | 5/12/2026 10:35:00 AM | | | | | 2470 | | | | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [°F] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24134-TP1 | 5/12/2026 10:33:32 AM | 38.2 | 61.8 | 0.0 | 0.0 | | | 0.6 | 0.0 | 150.6 |
| CV-24134-TP1 | 5/12/2026 10:32:12 AM | 36.7 | 63.3 | 0.0 | 0.0 | | | 0.6 | 0.0 | 150.1 |
| CV-24134-TP1 | 5/11/2026 2:33:48 PM | 16.6 | 73.9 | 0.0 | 9.5 | | | 0.2 | 0.0 | 146.9 |
| CV-24134-TP1 | 5/11/2026 2:29:03 PM | 18.3 | 65.8 | 0.0 | 15.9 | | | 0.3 | 0.0 | 146.2 |
| CV-24134-TP1 | 5/7/2026 1:15:00 PM | | | | | 1220 | | | | |
| CV-24134-TP1 | 5/7/2026 1:14:04 PM | 22.6 | 74.7 | 0.0 | 2.7 | | | 0.3 | 0.0 | 150.0 |
| CV-24135 | 5/11/2026 2:17:55 PM | 24.6 | 71.2 | 0.0 | 4.2 | | | 0.3 | 0.0 | 140.6 |
| CV-24135 | 5/11/2026 2:15:34 PM | 20.1 | 74.1 | 0.0 | 5.8 | | | 0.3 | 0.0 | 139.7 |
| CV-24136 | 5/11/2026 11:29:51 AM | 30.1 | 46.4 | 0.0 | 23.5 | | | 0.6 | 0.0 | 125.7 |
| CV-24137 | 5/4/2026 1:08:31 PM | 25.3 | 54.6 | 0.0 | 20.1 | | | 0.5 | 0.0 | 75.0 |
| CV-24137 | 5/4/2026 1:07:02 PM | 26.1 | 54.1 | 0.0 | 19.8 | | | 0.5 | 0.0 | 73.4 |
| CV-24138 | 5/28/2026 9:03:38 AM | 0.3 | 0.2 | 21.5 | 78.0 | | | 1.5 | 3.6 | 95.8 |
| CV-24138 | 5/28/2026 9:02:31 AM | 0.3 | 0.2 | 21.6 | 77.9 | | | 1.5 | 3.6 | 96.3 |
| CV-24138 | 5/13/2026 1:14:42 PM | 2.4 | 68.4 | 0.0 | 29.2 | | | 0.0 | 0.0 | 131.5 |
| CV-24138 | 5/6/2026 11:00:00 AM | | | | | 1010 | | | | |
| CV-24138 | 5/6/2026 11:00:00 AM | | | | | | 171800 | | | |
| CV-24138 | 5/6/2026 10:58:19 AM | 17.2 | 74.8 | 0.0 | 8.0 | | | 0.2 | 0.0 | 158.7 |
| CV-24138 | 5/5/2026 8:15:00 AM | | | | | 820 | | | | |
| CV-24138 | 5/5/2026 8:15:00 AM | | | | | | 210000 | | | |
| CV-24139 | 5/28/2026 9:08:34 AM | 4.1 | 58.6 | 4.7 | 32.6 | | | 0.1 | 6.9 | 127.4 |
| CV-24139 | 5/15/2026 8:22:50 AM | 0.7 | 30.7 | 13.2 | 55.4 | | | 0.0 | 4.2 | 144.2 |
| CV-24139 | 5/15/2026 8:12:50 AM | 0.1 | 3.3 | 20.8 | 75.8 | | | 0.0 | 3.6 | 111.7 |
| CV-24139 | 5/5/2026 8:10:00 AM | | | | | 630 | | | | |
| CV-24139 | 5/5/2026 8:10:00 AM | | | | | | 180000 | | | |
| CV-24140 | 5/28/2026 10:52:29 AM | 1.9 | 72.1 | 0.4 | 25.6 | | | 0.0 | 64.0 | 171.1 |
| CV-24140 | 5/28/2026 10:50:34 AM | 1.9 | 75.0 | 0.0 | 23.1 | | | 0.0 | 0.0 | 168.4 |
| CV-24140 | 5/20/2026 1:28:20 PM | 5.1 | 71.3 | 0.2 | 23.4 | | | 0.1 | 117.0 | 148.6 |
| CV-24140 | 5/20/2026 1:26:41 PM | 3.6 | 73.1 | 0.3 | 23.0 | | | 0.0 | 76.7 | 146.3 |
| CV-24140 | 5/13/2026 1:18:30 PM | 2.2 | 69.8 | 0.0 | 28.0 | | | 0.0 | 0.0 | 156.3 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24140 | 5/6/2026 11:05:00 AM | | | | | 1350 | | | | |
| CV-24140 | 5/6/2026 11:05:00 AM | | | | | | 203000 | | | |
| CV-24140 | 5/6/2026 11:04:58 AM | 14.4 | 78.6 | 0.0 | 7.0 | | | 0.2 | 0.0 | 163.7 |
| CV-24140 | 5/5/2026 8:05:00 AM | | | | | 1000 | | | | |
| CV-24140 | 5/5/2026 8:05:00 AM | | | | | | 210000 | | | |
| CV-24141 | 5/28/2026 9:31:07 AM | 10.8 | 6.8 | 18.3 | 64.1 | | | 1.6 | 3.5 | 66.1 |
| CV-24141 | 5/28/2026 9:30:26 AM | 10.7 | 6.5 | 18.4 | 64.4 | | | 1.6 | 3.5 | 65.6 |
| CV-24141 | 5/5/2026 7:45:00 AM | | | | | 94 | | | | |
| CV-24141 | 5/5/2026 7:45:00 AM | | | | | | 1200 | | | |
| CV-24141 | 5/1/2026 8:57:18 AM | 20.8 | 33.2 | 5.1 | 40.9 | | | 0.6 | 8.0 | 79.1 |
| CV-24142 | 5/28/2026 10:41:54 AM | 2.3 | 72.2 | 0.6 | 24.9 | | | 0.0 | 41.5 | 100.6 |
| CV-24142 | 5/28/2026 10:40:43 AM | 2.3 | 72.4 | 0.6 | 24.7 | | | 0.0 | 41.2 | 100.2 |
| CV-24142 | 5/20/2026 1:14:55 PM | 2.6 | 59.0 | 3.6 | 34.8 | | | 0.0 | 9.7 | 152.3 |
| CV-24142 | 5/20/2026 1:02:37 PM | 3.8 | 58.4 | 2.6 | 35.2 | | | 0.1 | 13.5 | 153.3 |
| CV-24142 | 5/15/2026 8:03:40 AM | 0.0 | 0.2 | 21.9 | 77.9 | | | 0.0 | 3.6 | 174.7 |
| CV-24142 | 5/15/2026 7:59:13 AM | 0.0 | 1.3 | 21.7 | 77.0 | | | 0.0 | 3.5 | 174.3 |
| CV-24142 | 5/14/2026 8:35:00 AM | | | | | 2300 | | | | |
| CV-24142 | 5/6/2026 8:10:00 AM | | | | | 1500 | | | | |
| CV-24142 | 5/6/2026 8:10:00 AM | | | | | | 120000 | | | |
| CV-24143 | 5/28/2026 9:20:03 AM | 4.3 | 24.2 | 15.2 | 56.3 | | | 0.2 | 3.7 | 72.5 |
| CV-24143 | 5/28/2026 9:19:15 AM | 4.2 | 23.6 | 15.2 | 57.0 | | | 0.2 | 3.8 | 73.4 |
| CV-24143 | 5/5/2026 7:55:00 AM | | | | | 460 | | | | |
| CV-24143 | 5/5/2026 7:55:00 AM | | | | | | 61000 | | | |
| CV-24143 | 5/1/2026 2:16:44 PM | 0.7 | 23.5 | 14.9 | 60.9 | | | 0.0 | 4.1 | 96.9 |
| CV-24143 | 5/1/2026 2:15:01 PM | 0.7 | 23.9 | 14.4 | 61.0 | | | 0.0 | 4.2 | 95.5 |
| CV-24144 | 5/20/2026 10:35:16 AM | 56.8 | 40.5 | 0.0 | 2.7 | | | 1.4 | 0.0 | 103.0 |
| CV-24144 | 5/12/2026 9:03:44 AM | 58.5 | 40.0 | 0.0 | 1.5 | | | 1.5 | 0.0 | 79.1 |
| CV-24145 | 5/26/2026 2:12:30 PM | 11.7 | 62.3 | 4.4 | 21.6 | | | 0.2 | 4.9 | 99.2 |
| CV-24145 | 5/18/2026 2:54:25 PM | 21.9 | 73.1 | 0.0 | 5.0 | | | 0.3 | 0.0 | 145.7 |
| CV-24145 | 5/18/2026 2:45:00 PM | | | | | 2450 | | | | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24145 | 5/18/2026 2:38:58 PM | 20.7 | 71.9 | 0.0 | 7.4 | | | 0.3 | 0.0 | 146.3 |
| CV-24145 | 5/12/2026 2:40:29 PM | 20.6 | 70.7 | 0.0 | 8.7 | | | 0.3 | 0.0 | 162.9 |
| CV-24145 | 5/12/2026 2:34:47 PM | 17.1 | 74.6 | 0.5 | 7.8 | | | 0.2 | 15.6 | 162.6 |
| CV-24145 | 5/12/2026 2:32:19 PM | 17.0 | 66.9 | 1.2 | 14.9 | | | 0.3 | 12.4 | 160.8 |
| CV-24145 | 5/12/2026 2:15:00 PM | | | | | 915 | | | | |
| CV-24145 | 5/5/2026 1:25:00 PM | | | | | 2480 | | | | |
| CV-24145 | 5/5/2026 1:25:00 PM | | | | | | 165900 | | | |
| CV-24145 | 5/5/2026 1:22:41 PM | 8.2 | 81.3 | 0.0 | 10.5 | | | 0.1 | 0.0 | 170.8 |
| CV-24146 | 5/28/2026 10:15:05 AM | 49.7 | 47.0 | 0.0 | 3.3 | | | 1.1 | 0.0 | 106.1 |
| CV-24146 | 5/28/2026 10:14:14 AM | 50.3 | 46.6 | 0.0 | 3.1 | | | 1.1 | 0.0 | 108.1 |
| CV-24146 | 5/11/2026 9:52:43 AM | 49.8 | 45.5 | 0.0 | 4.6 | | | 1.1 | 0.0 | 115.1 |
| CV-24147 | 5/28/2026 11:28:34 AM | 55.9 | 37.9 | 0.6 | 5.6 | | | 1.5 | 9.3 | 102.7 |
| CV-24147 | 5/26/2026 9:21:12 AM | 55.0 | 41.9 | 0.9 | 2.2 | | | 1.3 | 2.4 | 100.4 |
| CV-24147 | 5/14/2026 2:08:02 PM | 51.2 | 42.5 | 1.5 | 4.8 | | | 1.2 | 3.2 | 108.2 |
| CV-24147 | 5/11/2026 10:06:39 AM | 52.6 | 41.4 | 0.2 | 5.8 | | | 1.3 | 29.0 | 110.9 |
| CV-24147 | 5/11/2026 10:05:05 AM | 55.0 | 41.0 | 0.0 | 4.0 | | | 1.3 | 0.0 | 110.0 |
| CV-24147 | 5/11/2026 10:02:23 AM | 54.5 | 41.3 | 0.0 | 4.2 | | | 1.3 | 0.0 | 108.8 |
| CV-24148 | 5/27/2026 1:49:59 PM | 2.4 | 83.0 | 0.0 | 14.6 | | | 0.0 | 0.0 | 169.1 |
| CV-24148 | 5/19/2026 1:50:00 PM | | | | | 2320 | | | | |
| CV-24148 | 5/19/2026 1:44:57 PM | 22.2 | 77.8 | 0.0 | 0.0 | | | 0.3 | 0.0 | 171.5 |
| CV-24148 | 5/19/2026 1:43:50 PM | 17.6 | 77.8 | 0.2 | 4.4 | | | 0.2 | 22.0 | 173.0 |
| CV-24148 | 5/11/2026 10:02:23 AM | 5.4 | 88.3 | 0.1 | 6.2 | | | 0.1 | 62.0 | 178.1 |
| CV-24148 | 5/4/2026 9:31:25 AM | 0.8 | 80.7 | 0.0 | 18.5 | | | 0.0 | 0.0 | 180.4 |
| CV-24148 | 5/4/2026 9:30:00 AM | | | | | 3480 | | | | |
| CV-24148 | 5/4/2026 9:30:00 AM | | | | | | 106200 | | | |
| CV-24149 | 5/28/2026 12:48:18 PM | 3.7 | 81.4 | 2.4 | 12.5 | | | 0.0 | 5.2 | 82.2 |
| CV-24149 | 5/6/2026 2:58:21 PM | 3.5 | 86.0 | 0.5 | 10.0 | | | 0.0 | 20.0 | 96.0 |
| CV-24150 | 5/22/2026 11:53:52 AM | 41.7 | 58.3 | 0.0 | 0.0 | | | 0.7 | 0.0 | 111.7 |
| CV-24150 | 5/1/2026 10:15:37 AM | 45.9 | 52.7 | 0.3 | 1.1 | | | 0.9 | 3.7 | 111.1 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24151 | 5/21/2026 1:59:13 PM | 50.6 | 49.4 | 0.0 | 0.0 | | | 1.0 | 0.0 | 103.2 |
| CV-24151 | 5/6/2026 2:05:59 PM | 48.0 | 48.0 | 0.1 | 3.9 | | | 1.0 | 39.0 | 87.9 |
| CV-24152 | 5/26/2026 8:32:21 AM | 25.4 | 70.6 | 0.0 | 4.0 | | | 0.4 | 0.0 | 129.7 |
| CV-24152 | 5/26/2026 8:31:06 AM | 25.4 | 68.9 | 0.0 | 5.7 | | | 0.4 | 0.0 | 130.3 |
| CV-24152 | 5/6/2026 2:21:42 PM | 20.4 | 72.7 | 0.0 | 6.9 | | | 0.3 | 0.0 | 131.4 |
| CV-24152 | 5/6/2026 2:21:09 PM | 20.2 | 74.2 | 0.0 | 5.6 | | | 0.3 | 0.0 | 130.7 |
| CV-24153 | 5/22/2026 11:40:23 AM | 41.3 | 54.6 | 0.0 | 4.1 | | | 0.8 | 0.0 | 114.9 |
| CV-24153 | 5/1/2026 3:03:06 PM | 49.9 | 50.1 | 0.0 | 0.0 | | | 1.0 | 0.0 | 104.2 |
| CV-24153 | 5/1/2026 3:02:03 PM | 51.9 | 48.1 | 0.1 | | | | 1.1 | | 98.8 |
| CV-24154 | 5/22/2026 11:58:09 AM | 44.0 | 53.0 | 0.3 | 2.7 | | | 0.8 | 9.0 | 112.9 |
| CV-24154 | 5/1/2026 3:20:22 PM | 47.7 | 52.0 | 0.3 | 0.0 | | | 0.9 | 0.0 | 104.1 |
| CV-24155 | 5/26/2026 8:18:02 AM | 34.1 | 65.9 | 0.0 | 0.0 | | | 0.5 | 0.0 | 119.1 |
| CV-24155 | 5/1/2026 3:09:53 PM | 32.8 | 67.2 | 0.0 | 0.0 | | | 0.5 | 0.0 | 118.8 |
| CV-24155 | 5/1/2026 3:08:32 PM | 32.0 | 68.0 | 0.0 | 0.0 | | | 0.5 | 0.0 | 98.2 |
| CV-24156 | 5/22/2026 2:00:28 PM | 43.2 | 52.5 | 0.2 | 4.1 | | | 0.8 | 20.5 | 124.0 |
| CV-24156 | 5/4/2026 2:11:53 PM | 42.8 | 54.5 | 0.0 | 2.7 | | | 0.8 | 0.0 | 122.5 |
| CV-24157 | 5/21/2026 2:09:04 PM | 48.6 | 51.4 | 0.0 | 0.0 | | | 0.9 | 0.0 | 105.5 |
| CV-24157 | 5/21/2026 2:08:15 PM | 48.7 | 51.3 | 0.0 | 0.0 | | | 0.9 | 0.0 | 104.5 |
| CV-24157 | 5/4/2026 2:00:15 PM | 47.2 | 50.8 | 0.0 | 2.0 | | | 0.9 | 0.0 | 94.3 |
| CV-24158 | 5/21/2026 10:58:26 AM | 43.6 | 56.3 | 0.1 | 0.0 | | | 0.8 | 0.0 | 128.3 |
| CV-24158 | 5/6/2026 10:59:56 AM | 38.9 | 61.1 | 0.0 | 0.0 | | | 0.6 | 0.0 | 125.4 |
| CV-24159 | 5/21/2026 9:02:31 AM | 41.8 | 58.2 | 0.0 | 0.0 | | | 0.7 | 0.0 | 131.8 |
| CV-24159 | 5/21/2026 9:01:50 AM | 42.0 | 58.0 | 0.0 | 0.0 | | | 0.7 | 0.0 | 131.7 |
| CV-24159 | 5/6/2026 10:49:41 AM | 42.9 | 54.6 | 0.0 | 2.5 | | | 0.8 | 0.0 | 126.4 |
| CV-24160 | 5/22/2026 12:06:28 PM | 46.7 | 53.1 | 0.1 | 0.1 | | | 0.9 | 1.0 | 127.4 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24160 | 5/6/2026 12:39:52 PM | 46.7 | 52.2 | 0.0 | 1.1 | | | 0.9 | 0.0 | 125.0 |
| CV-24160 | 5/6/2026 10:29:54 AM | 43.4 | 54.3 | 0.0 | 2.3 | | | 0.8 | 0.0 | 122.4 |
| CV-24161 | 5/6/2026 10:20:39 AM | 20.3 | 76.5 | 0.0 | 3.2 | | | 0.3 | 0.0 | 111.1 |
| CV-24161 | 5/6/2026 10:19:18 AM | 18.6 | 76.5 | 0.0 | 4.9 | | | 0.2 | 0.0 | 104.4 |
| CV-24162 | 5/4/2026 12:02:44 PM | 37.0 | 52.0 | 0.5 | 10.5 | | | 0.7 | 21.0 | 86.4 |
| CV-24163 | 5/1/2026 2:33:25 PM | 33.2 | 57.8 | 0.0 | 9.0 | | | 0.6 | 0.0 | 129.6 |
| CV-24163 | 5/1/2026 2:32:24 PM | 32.1 | 57.6 | 0.0 | 10.3 | | | 0.6 | 0.0 | 132.2 |
| CV-24164 | 5/20/2026 2:08:15 PM | 33.5 | 65.0 | 0.0 | 1.5 | | | 0.5 | 0.0 | 131.9 |
| CV-24164 | 5/20/2026 2:06:56 PM | 35.4 | 64.6 | 0.0 | 0.0 | | | 0.5 | 0.0 | 132.3 |
| CV-24164 | 5/20/2026 11:14:31 AM | 40.0 | 60.0 | 0.0 | 0.0 | | | 0.7 | 0.0 | 100.1 |
| CV-24164 | 5/4/2026 10:23:58 AM | 27.2 | 72.4 | 0.0 | 0.4 | | | 0.4 | 0.0 | 126.8 |
| CV-24165 | 5/20/2026 11:18:42 AM | 42.5 | 57.5 | 0.0 | 0.0 | | | 0.7 | 0.0 | 121.3 |
| CV-24165 | 5/14/2026 11:24:07 AM | 21.4 | 78.6 | 0.0 | 0.0 | | | 0.3 | 0.0 | 132.5 |
| CV-24165 | 5/14/2026 11:22:03 AM | 20.9 | 78.1 | 0.0 | 1.0 | | | 0.3 | 0.0 | 134.4 |
| CV-24166 | 5/21/2026 9:08:04 AM | 52.8 | 47.2 | 0.0 | 0.0 | | | 1.1 | 0.0 | 123.3 |
| CV-24166 | 5/20/2026 11:21:55 AM | 45.9 | 54.1 | 0.0 | 0.0 | | | 0.8 | 0.0 | 128.8 |
| CV-24166 | 5/6/2026 10:54:07 AM | 49.3 | 46.5 | 0.0 | 4.2 | | | 1.1 | 0.0 | 106.6 |
| CV-24167 | 5/28/2026 8:45:13 AM | 47.8 | 39.6 | 0.0 | 12.6 | | | 1.2 | 0.0 | 110.2 |
| CV-24167 | 5/6/2026 9:59:13 AM | 50.1 | 40.3 | 0.2 | 9.4 | | | 1.2 | 47.0 | 112.3 |
| CV-24168 | 5/28/2026 8:59:25 AM | 26.5 | 49.6 | 2.3 | 21.6 | | | 0.5 | 9.2 | 104.7 |
| CV-24168 | 5/6/2026 10:55:15 AM | 28.6 | 55.8 | 2.7 | 12.9 | | | 0.5 | 4.8 | 111.0 |
| CV-24169 | 5/20/2026 11:11:16 AM | 41.2 | 58.8 | 0.0 | 0.0 | | | 0.7 | 0.0 | 100.1 |
| CV-24169 | 5/4/2026 10:19:18 AM | 32.8 | 64.3 | 0.0 | 2.9 | | | 0.5 | 0.0 | 115.5 |
| CV-24170 | 5/21/2026 9:20:08 AM | 9.5 | 82.3 | 0.0 | 8.2 | | | 0.1 | 0.0 | 126.9 |
| CV-24170 | 5/6/2026 8:37:17 AM | 14.6 | 81.3 | 0.0 | 4.1 | | | 0.2 | 0.0 | 125.8 |
| CV-24170 | 5/1/2026 10:56:54 AM | 15.1 | 76.1 | 0.0 | 8.8 | | | 0.2 | 0.0 | 126.7 |
| CV-24171 | 5/21/2026 9:23:58 AM | 53.8 | 46.2 | 0.0 | 0.0 | | | 1.2 | 0.0 | 127.3 |
| CV-24171 | 5/6/2026 10:03:52 AM | 52.3 | 45.2 | 0.0 | 2.5 | | | 1.2 | 0.0 | 123.2 |
| CV-24172 | 5/21/2026 10:00:21 AM | 42.7 | 41.8 | 2.5 | 13.0 | | | 1.0 | 5.2 | 121.6 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24172 | 5/4/2026 2:28:48 PM | 35.4 | 35.6 | 3.6 | 25.4 | | | 1.0 | 7.1 | 116.2 |
| CV-24173 | 5/21/2026 10:06:44 AM | 49.1 | 41.3 | 0.9 | 8.7 | | | 1.2 | 9.7 | 115.4 |
| CV-24173 | 5/6/2026 1:00:35 PM | 46.2 | 40.1 | 0.9 | 12.8 | | | 1.2 | 14.2 | 113.5 |
| CV-24174 | 5/21/2026 10:15:48 AM | 26.6 | 50.1 | 0.0 | 23.3 | | | 0.5 | 0.0 | 111.2 |
| CV-24174 | 5/11/2026 1:20:08 PM | 30.3 | 40.0 | 0.0 | 29.7 | | | 0.8 | 0.0 | 111.2 |
| CV-24175 | 5/21/2026 10:19:57 AM | 25.7 | 63.6 | 0.0 | 10.7 | | | 0.4 | 0.0 | 121.2 |
| CV-24175 | 5/5/2026 1:28:08 PM | 26.9 | 54.6 | 0.0 | 18.5 | | | 0.5 | 0.0 | 120.8 |
| CV-24175 | 5/5/2026 1:26:42 PM | 25.7 | 55.1 | 0.0 | 19.3 | | | 0.5 | 0.0 | 121.6 |
| CV-24175 | 5/5/2026 1:21:04 PM | 23.8 | 56.4 | 0.4 | 19.5 | | | 0.4 | 52.6 | 121.9 |
| CV-24175 | 5/5/2026 1:13:21 PM | 24.1 | 57.2 | 0.3 | 18.4 | | | 0.4 | 57.6 | 122.2 |
| CV-24176 | 5/20/2026 10:16:41 AM | 23.0 | 72.2 | 0.5 | 4.3 | | | 0.3 | 8.6 | 130.6 |
| CV-24176 | 5/20/2026 10:14:10 AM | 29.7 | 60.2 | 0.0 | 10.1 | | | 0.5 | 0.0 | 132.4 |
| CV-24176 | 5/8/2026 11:05:11 AM | 17.9 | 80.5 | 0.0 | 1.6 | | | 0.2 | 0.0 | 137.8 |
| CV-24176 | 5/8/2026 11:03:01 AM | 15.5 | 81.6 | 0.0 | 2.9 | | | 0.2 | 0.0 | 130.2 |
| CV-24177 | 5/20/2026 8:06:52 AM | 13.9 | 42.9 | 4.7 | 38.5 | | | 0.3 | 8.2 | 131.7 |
| CV-24177 | 5/20/2026 7:56:33 AM | 11.9 | 24.8 | 8.5 | 54.8 | | | 0.5 | 6.4 | 135.2 |
| CV-24177 | 5/8/2026 11:20:50 AM | 16.9 | 28.3 | 5.5 | 49.3 | | | 0.6 | 9.0 | 126.2 |
| CV-24177 | 5/8/2026 11:19:26 AM | 17.2 | 27.3 | 5.5 | 50.0 | | | 0.6 | 9.1 | 126.8 |
| CV-24178 | 5/20/2026 12:02:57 PM | 28.7 | 53.7 | 0.0 | 17.6 | | | 0.5 | 0.0 | 130.5 |
| CV-24178 | 5/20/2026 12:01:45 PM | 29.7 | 54.5 | 0.0 | 15.8 | | | 0.5 | 0.0 | 131.6 |
| CV-24178 | 5/8/2026 10:58:25 AM | 31.5 | 56.1 | 0.0 | 12.4 | | | 0.6 | 0.0 | 129.3 |
| CV-24179 | 5/20/2026 9:55:47 AM | 27.8 | 51.1 | 0.0 | 21.1 | | | 0.5 | 0.0 | 130.2 |
| CV-24179 | 5/4/2026 1:09:48 PM | 17.5 | 69.0 | 0.0 | 13.4 | | | 0.3 | 0.0 | 123.9 |
| CV-24179 | 5/4/2026 1:08:00 PM | 14.4 | 72.0 | 0.0 | 13.6 | | | 0.2 | 0.0 | 113.0 |
| CV-24179 | 5/4/2026 1:03:56 PM | 13.3 | 67.7 | 2.4 | 16.5 | | | 0.2 | 6.8 | 77.6 |
| CV-24180 | 5/20/2026 10:03:08 AM | 26.5 | 38.5 | 0.2 | 34.8 | | | 0.7 | 174.0 | 126.6 |
| CV-24180 | 5/8/2026 10:53:15 AM | 24.8 | 40.0 | 0.0 | 35.2 | | | 0.6 | 0.0 | 124.7 |
| CV-24181 | 5/20/2026 12:05:54 PM | 37.8 | 62.1 | 0.0 | 0.1 | | | 0.6 | 0.0 | 111.7 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [°F] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24181 | 5/4/2026 11:08:54 AM | 35.3 | 53.6 | 0.0 | 11.1 | | | 0.7 | 0.0 | 107.1 |
| CV-24182 | 5/22/2026 10:34:25 AM | 38.9 | 55.3 | 0.5 | 5.3 | | | 0.7 | 10.6 | 112.1 |
| CV-24182 | 5/4/2026 11:12:00 AM | 37.1 | 54.9 | 0.0 | 8.0 | | | 0.7 | 0.0 | 99.1 |
| CV-24183 | 5/20/2026 11:42:38 AM | 48.3 | 51.6 | 0.1 | 0.0 | | | 0.9 | 0.0 | 107.0 |
| CV-24183 | 5/4/2026 11:26:46 AM | 48.9 | 47.5 | 0.0 | 3.6 | | | 1.0 | 0.0 | 84.8 |
| CV-24184 | 5/28/2026 1:18:12 PM | 22.4 | 29.5 | 5.7 | 42.4 | | | 0.8 | 7.4 | 135.6 |
| CV-24184 | 5/28/2026 1:16:04 PM | 23.0 | 31.0 | 5.7 | 40.3 | | | 0.7 | 7.1 | 139.9 |
| CV-24184 | 5/20/2026 11:25:50 AM | 38.1 | 61.9 | 0.0 | 0.0 | | | 0.6 | 0.0 | 133.7 |
| CV-24184 | 5/20/2026 11:24:32 AM | 37.1 | 62.9 | 0.0 | 0.0 | | | 0.6 | 0.0 | 132.0 |
| CV-24184 | 5/20/2026 11:22:55 AM | 39.0 | 61.0 | 0.0 | 0.0 | | | 0.6 | 0.0 | 118.5 |
| CV-24184 | 5/4/2026 1:19:41 PM | 33.3 | 32.5 | 4.6 | 29.6 | | | 1.0 | 6.4 | 133.2 |
| CV-24184 | 5/4/2026 1:18:22 PM | 34.6 | 33.2 | 4.3 | 27.9 | | | 1.0 | 6.5 | 135.0 |
| CV-24185 | 5/20/2026 2:14:16 PM | 38.2 | 59.9 | 0.0 | 1.9 | | | 0.6 | 0.0 | 128.3 |
| CV-24185 | 5/20/2026 2:12:58 PM | 36.2 | 63.8 | 0.0 | 0.0 | | | 0.6 | 0.0 | 127.0 |
| CV-24185 | 5/4/2026 1:26:49 PM | 39.0 | 59.6 | 0.0 | 1.4 | | | 0.7 | 0.0 | 123.2 |
| CV-24186 | 5/20/2026 2:18:02 PM | 44.2 | 48.6 | 0.1 | 7.1 | | | 0.9 | 71.0 | 128.5 |
| CV-24186 | 5/4/2026 2:56:41 PM | 43.6 | 44.7 | 0.4 | 11.3 | | | 1.0 | 28.3 | 125.3 |
| CV-24187 | 5/19/2026 10:36:55 AM | 48.1 | 47.8 | 0.0 | 4.0 | | | 1.0 | 0.0 | 125.1 |
| CV-24187 | 5/4/2026 10:28:37 AM | 48.5 | 47.7 | 0.0 | 3.8 | | | 1.0 | 0.0 | 124.2 |
| CV-24187 | 5/4/2026 10:27:50 AM | 48.9 | 47.9 | 0.0 | 3.2 | | | 1.0 | 0.0 | 123.4 |
| CV-24187 | 5/4/2026 10:19:29 AM | 49.4 | 47.4 | 0.0 | 3.2 | | | 1.0 | 0.0 | 67.2 |
| CV-24188 | 5/20/2026 12:45:56 PM | 50.8 | 43.7 | 0.0 | 5.5 | | | 1.2 | 0.0 | 118.9 |
| CV-24188 | 5/20/2026 8:59:37 AM | 51.4 | 43.2 | 0.0 | 5.4 | | | 1.2 | 0.0 | 118.0 |
| CV-24188 | 5/4/2026 9:36:30 AM | 50.4 | 43.9 | 0.0 | 5.7 | | | 1.1 | 0.0 | 117.7 |
| CV-24188 | 5/4/2026 9:34:45 AM | 50.7 | 43.6 | 0.0 | 5.7 | | | 1.2 | 0.0 | 117.1 |
| CV-24189 | 5/20/2026 8:49:58 AM | 47.3 | 39.8 | 0.0 | 12.9 | | | 1.2 | 0.0 | 118.0 |
| CV-24189 | 5/4/2026 9:28:20 AM | 49.2 | 40.2 | 0.0 | 10.6 | | | 1.2 | 0.0 | 117.5 |
| CV-24190 | 5/19/2026 10:21:44 AM | 51.1 | 47.0 | 0.0 | 1.9 | | | 1.1 | 0.0 | 123.1 |
| CV-24190 | 5/4/2026 10:10:47 AM | 51.3 | 44.4 | 0.0 | 4.3 | | | 1.2 | 0.0 | 122.5 |
| CV-24192 | 5/22/2026 10:15:13 AM | 55.3 | 44.2 | 0.0 | 0.5 | | | 1.3 | 0.0 | 115.2 |
| CV-24192 | 5/4/2026 10:02:40 AM | 52.3 | 43.0 | 0.0 | 4.7 | | | 1.2 | 0.0 | 117.5 |
| CV-24192 | 5/4/2026 10:01:48 AM | 52.5 | 43.0 | 0.0 | 4.6 | | | 1.2 | 0.0 | 116.9 |
| CV-24192 | 5/4/2026 9:58:01 AM | 53.4 | 42.3 | 0.0 | 4.3 | | | 1.3 | 0.0 | 116.3 |
| CV-24193 | 5/19/2026 2:15:47 PM | 51.4 | 42.5 | 0.0 | 6.2 | | | 1.2 | 0.0 | 116.3 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24193 | 5/4/2026 9:13:38 AM | 51.8 | 43.2 | 0.0 | 5.0 | | | 1.2 | 0.0 | 112.5 |
| CV-24194 | 5/20/2026 12:10:04 PM | 39.7 | 37.1 | 4.6 | 18.6 | | | 1.1 | 4.0 | 103.7 |
| CV-24194 | 5/5/2026 1:47:55 PM | 53.0 | 43.0 | 0.0 | 4.0 | | | 1.2 | 0.0 | 92.6 |
| CV-24194 | 5/4/2026 9:33:10 AM | 52.2 | 43.8 | 0.0 | 4.0 | | | 1.2 | 0.0 | 89.4 |
| CV-24195 | 5/28/2026 1:01:56 PM | 50.2 | 44.6 | 0.0 | 5.2 | | | 1.1 | 0.0 | 118.2 |
| CV-24195 | 5/20/2026 12:23:03 PM | 50.0 | 49.9 | 0.0 | 0.1 | | | 1.0 | 0.0 | 118.2 |
| CV-24195 | 5/4/2026 9:46:22 AM | 50.0 | 46.1 | 0.0 | 3.9 | | | 1.1 | 0.0 | 114.9 |
| CV-24196 | 5/28/2026 12:55:54 PM | 49.2 | 44.1 | 0.0 | 6.7 | | | 1.1 | 0.0 | 123.3 |
| CV-24196 | 5/20/2026 11:31:51 AM | 50.0 | 50.0 | 0.0 | 0.0 | | | 1.0 | 0.0 | 125.3 |
| CV-24196 | 5/4/2026 11:32:25 AM | 48.7 | 47.4 | 0.0 | 3.9 | | | 1.0 | 0.0 | 122.2 |
| CV-24197 | 5/22/2026 10:52:22 AM | 51.6 | 44.6 | 0.0 | 3.8 | | | 1.2 | 0.0 | 124.0 |
| CV-24197 | 5/8/2026 11:18:02 AM | 52.5 | 45.3 | 0.0 | 2.2 | | | 1.2 | 0.0 | 125.3 |
| CV-24198 | 5/22/2026 10:50:58 AM | 45.6 | 43.1 | 0.0 | 11.3 | | | 1.1 | 0.0 | 118.4 |
| CV-24198 | 5/8/2026 10:50:53 AM | 53.3 | 42.9 | 0.0 | 3.8 | | | 1.2 | 0.0 | 117.4 |
| CV-24199 | 5/22/2026 10:41:08 AM | 48.4 | 46.0 | 0.0 | 5.6 | | | 1.1 | 0.0 | 128.3 |
| CV-24199 | 5/8/2026 10:55:45 AM | 52.5 | 44.5 | 0.0 | 3.0 | | | 1.2 | 0.0 | 127.3 |
| CV-24200 | 5/22/2026 9:57:47 AM | 51.8 | 42.6 | 0.0 | 5.6 | | | 1.2 | 0.0 | 118.3 |
| CV-24200 | 5/6/2026 2:43:38 PM | 52.4 | 41.9 | 0.1 | 5.6 | | | 1.3 | 56.0 | 117.6 |
| CV-24201 | 5/22/2026 10:05:48 AM | 49.1 | 40.5 | 0.2 | 10.2 | | | 1.2 | 51.0 | 119.7 |
| CV-24201 | 5/6/2026 3:11:02 PM | 48.8 | 43.1 | 0.2 | 7.9 | | | 1.1 | 39.5 | 121.8 |
| CV-24202 | 5/22/2026 10:29:59 AM | 43.3 | 48.4 | 0.0 | 8.3 | | | 0.9 | 0.0 | 114.6 |
| CV-24202 | 5/6/2026 3:17:39 PM | 38.0 | 49.4 | 0.0 | 12.6 | | | 0.8 | 0.0 | 117.1 |
| CV-24203 | 5/22/2026 9:36:46 AM | 52.8 | 45.4 | 0.2 | 1.6 | | | 1.2 | 8.0 | 126.7 |
| CV-24203 | 5/11/2026 10:07:30 AM | 50.4 | 45.5 | 0.0 | 4.1 | | | 1.1 | 0.0 | 125.9 |
| CV-24204 | 5/22/2026 9:39:46 AM | 50.0 | 48.6 | 0.1 | 1.3 | | | 1.0 | 13.0 | 126.4 |
| CV-24204 | 5/11/2026 10:10:41 AM | 47.5 | 48.6 | 0.0 | 3.9 | | | 1.0 | 0.0 | 125.8 |
| CV-24205 | 5/22/2026 9:45:39 AM | 55.7 | 43.4 | 0.0 | 0.9 | | | 1.3 | 0.0 | 122.6 |
| CV-24205 | 5/6/2026 12:13:07 PM | 49.5 | 42.8 | 0.0 | 7.7 | | | 1.2 | 0.0 | 121.1 |
| CV-24206 | 5/22/2026 10:00:36 AM | 46.8 | 40.8 | 0.0 | 12.4 | | | 1.1 | 0.0 | 92.1 |
| CV-24206 | 5/6/2026 3:04:18 PM | 42.5 | 40.7 | 0.0 | 16.8 | | | 1.0 | 0.0 | 86.6 |
| CV-24207 | 5/21/2026 9:17:20 AM | 52.4 | 43.6 | 1.3 | 2.7 | | | 1.2 | 2.1 | 130.6 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24207 | 5/21/2026 9:15:43 AM | 49.8 | 42.7 | 2.4 | 5.1 | | | 1.2 | 2.1 | 131.6 |
| CV-24207 | 5/4/2026 2:35:22 PM | 51.4 | 48.2 | 0.0 | 0.4 | | | 1.1 | 0.0 | 126.2 |
| CV-24208 | 5/4/2026 10:58:55 AM | 43.9 | 49.9 | 0.0 | 6.2 | | | 0.9 | 0.0 | 125.5 |
| CV-24209 | 5/4/2026 11:15:06 AM | 13.7 | 72.3 | 0.0 | 14.0 | | | 0.2 | 0.0 | 125.0 |
| CV-24210 | 5/5/2026 1:26:15 PM | 44.4 | 51.1 | 0.0 | 4.5 | | | 0.9 | 0.0 | 101.3 |
| CV-24210 | 5/4/2026 11:34:40 AM | 46.5 | 47.4 | 0.0 | 6.1 | | | 1.0 | 0.0 | 121.4 |
| CV-24211 | 5/7/2026 10:23:15 AM | 18.7 | 79.7 | 0.0 | 1.6 | | | 0.2 | 0.0 | 117.6 |
| CV-24212 | 5/11/2026 9:45:09 AM | 7.4 | 67.7 | 0.4 | 24.5 | | | 0.1 | 61.3 | 136.6 |
| CV-24212 | 5/11/2026 9:43:52 AM | 7.4 | 68.1 | 0.6 | 23.9 | | | 0.1 | 39.8 | 135.2 |
| CV-24213 | 5/1/2026 1:55:50 PM | 43.1 | 46.8 | 0.0 | 10.1 | | | 0.9 | 0.0 | 117.9 |
| CV-24213 | 5/1/2026 1:54:28 PM | 43.6 | 46.0 | 0.0 | 10.4 | | | 0.9 | 0.0 | 122.1 |
| CV-24213 | 5/1/2026 1:34:20 PM | 38.4 | 50.0 | 0.0 | 11.6 | | | 0.8 | 0.0 | 108.6 |
| CV-24213 | 5/1/2026 1:32:27 PM | 38.4 | 50.7 | 0.0 | 10.9 | | | 0.8 | 0.0 | 108.7 |
| CV-24214 | 5/26/2026 12:44:02 PM | 40.3 | 41.4 | 0.0 | 18.3 | | | 1.0 | 0.0 | 108.4 |
| CV-24214 | 5/26/2026 12:41:30 PM | 40.8 | 41.4 | 0.0 | 17.9 | | | 1.0 | 0.0 | 110.1 |
| CV-24215 | 5/29/2026 9:58:57 AM | 31.5 | 49.7 | 0.0 | 18.8 | | | 0.6 | 0.0 | 96.2 |
| CV-24216 | 5/1/2026 1:59:49 PM | 48.0 | 41.3 | 1.2 | 9.5 | | | 1.2 | 7.9 | 105.0 |
| CV-24217 | 5/11/2026 1:45:32 PM | 38.4 | 55.9 | 0.0 | 5.7 | | | 0.7 | 0.0 | 115.7 |
| CV-24217 | 5/11/2026 1:25:59 PM | 39.3 | 56.1 | 0.0 | 4.6 | | | 0.7 | 0.0 | 110.4 |
| CV-24217 | 5/11/2026 10:19:12 AM | 43.1 | 50.5 | 0.0 | 6.4 | | | 0.9 | 0.0 | 121.6 |
| CV-24218 | 5/8/2026 8:42:59 AM | 43.0 | 56.1 | 0.0 | 0.9 | | | 0.8 | 0.0 | 123.6 |
| CV-24219 | 5/27/2026 2:44:32 PM | 15.5 | 82.2 | 0.3 | 2.0 | | | 0.2 | 6.7 | 180.1 |
| CV-24219 | 5/19/2026 1:10:00 PM | | | | | 2820 | | | | |
| CV-24219 | 5/19/2026 1:07:47 PM | 24.4 | 75.6 | 0.0 | 0.0 | | | 0.3 | 0.0 | 182.4 |
| CV-24219 | 5/19/2026 1:07:21 PM | 22.1 | 77.9 | 0.0 | 0.0 | | | 0.3 | 0.0 | 181.5 |
| CV-24219 | 5/11/2026 9:27:37 AM | 5.4 | 83.9 | 0.0 | 10.7 | | | 0.1 | 0.0 | 188.3 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24219 | 5/11/2026 9:26:02 AM | 5.5 | 88.0 | 0.0 | 6.5 | | | 0.1 | 0.0 | 188.6 |
| CV-24219 | 5/4/2026 8:40:00 AM | | | | | 3760 | | | | |
| CV-24219 | 5/4/2026 8:40:00 AM | | | | | | 105700 | | | |
| CV-24219 | 5/4/2026 8:37:52 AM | 2.4 | 92.8 | 0.0 | 4.8 | | | 0.0 | 0.0 | 187.1 |
| CV-24220 | 5/1/2026 2:28:38 PM | 14.9 | 58.2 | 0.9 | 26.0 | | | 0.3 | 28.9 | 131.7 |
| CV-24220 | 5/1/2026 2:26:20 PM | 18.1 | 50.2 | 1.2 | 30.5 | | | 0.4 | 25.4 | 135.4 |
| CV-24221 | 5/7/2026 10:47:53 AM | 37.4 | 46.4 | 0.0 | 16.2 | | | 0.8 | 0.0 | 91.5 |
| CV-24222 | 5/11/2026 9:28:59 AM | 55.9 | 40.4 | 0.2 | 3.5 | | | 1.4 | 17.5 | 122.5 |
| CV-24223 | 5/11/2026 9:35:14 AM | 28.0 | 46.3 | 0.0 | 25.7 | | | 0.6 | 0.0 | 130.3 |
| CV-24224 | 5/1/2026 2:36:53 PM | 41.3 | 39.9 | 0.3 | 18.5 | | | 1.0 | 61.7 | 114.4 |
| CV-24225 | 5/4/2026 10:44:54 AM | 49.6 | 42.4 | 0.7 | 7.3 | | | 1.2 | 10.4 | 105.0 |
| CV-24226 | 5/7/2026 10:18:42 AM | 50.9 | 44.4 | 0.0 | 4.7 | | | 1.1 | 0.0 | 112.5 |
| CV-24227 | 5/8/2026 11:27:46 AM | 53.8 | 41.9 | 0.0 | 4.3 | | | 1.3 | 0.0 | 114.8 |
| CV-24231 | 5/5/2026 2:20:38 PM | 44.6 | 39.6 | 0.3 | 15.5 | | | 1.1 | 51.7 | 123.6 |
| CV-24236 | 5/7/2026 9:58:34 AM | 53.9 | 40.0 | 0.0 | 6.1 | | | 1.3 | 0.0 | 102.6 |
| CV-24237 | 5/7/2026 10:03:50 AM | 52.1 | 38.1 | 0.0 | 9.8 | | | 1.4 | 0.0 | 111.5 |
| CV-24243 | 5/8/2026 10:05:46 AM | 54.3 | 41.5 | 0.0 | 4.2 | | | 1.3 | 0.0 | 114.6 |
| CV-24244 | 5/7/2026 11:23:42 AM | 51.9 | 42.4 | 0.1 | 5.6 | | | 1.2 | 56.0 | 112.1 |
| CV-24245 | 5/7/2026 2:21:55 PM | 43.5 | 37.6 | 0.0 | 18.9 | | | 1.2 | 0.0 | 115.3 |
| CV-24246 | 5/7/2026 2:17:13 PM | 52.8 | 42.8 | 0.0 | 4.4 | | | 1.2 | 0.0 | 116.4 |
| CV-24253 | 5/7/2026 2:35:07 PM | 53.0 | 42.6 | 0.1 | 4.3 | | | 1.2 | 43.0 | 115.4 |
| CV-25 | 5/13/2026 1:44:59 PM | 51.7 | 41.4 | 0.4 | 6.5 | | | 1.2 | 16.7 | 92.9 |
| CV-2501 | 5/4/2026 9:55:50 AM | 51.2 | 46.4 | 0.0 | 2.4 | | | 1.1 | 0.0 | 120.3 |
| CV-2502 | 5/4/2026 10:08:04 AM | 50.0 | 43.5 | 0.0 | 6.5 | | | 1.1 | 0.0 | 119.0 |
| CV-2503 | 5/6/2026 2:52:46 PM | 51.6 | 45.3 | 0.0 | 3.1 | | | 1.1 | 0.0 | 125.8 |
| CV-2504 | 5/5/2026 2:41:25 PM | 47.0 | 41.9 | 0.0 | 11.1 | | | 1.1 | 0.0 | 125.8 |
| CV-2505 | 5/5/2026 2:55:39 PM | 50.1 | 42.6 | 0.0 | 7.3 | | | 1.2 | 0.0 | 117.4 |
| CV-2506 | 5/5/2026 3:55:25 PM | 50.1 | 43.4 | 0.0 | 6.5 | | | 1.2 | 0.0 | 119.7 |
| CV-2507 | 5/8/2026 1:37:11 PM | 55.3 | 42.3 | 0.0 | 2.4 | | | 1.3 | 0.0 | 122.7 |
| CV-2507 | 5/5/2026 3:50:55 PM | 55.9 | 42.0 | 0.0 | 2.1 | | | 1.3 | 0.0 | 120.1 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2508 | 5/5/2026 3:46:09 PM | 55.4 | 43.4 | 0.0 | 1.2 | | | 1.3 | 0.0 | 118.5 |
| CV-2509 | 5/8/2026 1:42:52 PM | 55.2 | 41.8 | 0.0 | 3.0 | | | 1.3 | 0.0 | 115.3 |
| CV-2509 | 5/5/2026 3:31:32 PM | 52.0 | 42.7 | 0.0 | 5.3 | | | 1.2 | 0.0 | 113.5 |
| CV-2510 | 5/8/2026 1:46:50 PM | 56.1 | 41.2 | 0.0 | 2.7 | | | 1.4 | 0.0 | 113.8 |
| CV-2510 | 5/5/2026 2:25:18 PM | 56.1 | 41.7 | 0.0 | 2.2 | | | 1.3 | 0.0 | 113.4 |
| CV-25100D | 5/18/2026 10:35:31 AM | 37.2 | 62.8 | 0.0 | 0.0 | | | 0.6 | 0.0 | 118.5 |
| CV-25100D | 5/12/2026 10:22:21 AM | 30.8 | 69.2 | 0.0 | 0.0 | | | 0.4 | 0.0 | 147.0 |
| CV-25100D | 5/12/2026 10:20:00 AM | | | | | 504 | | | | |
| CV-25100D | 5/8/2026 9:54:19 AM | 5.0 | 80.5 | 0.0 | 14.5 | | | 0.1 | 0.0 | 177.5 |
| CV-25100D | 5/8/2026 9:52:49 AM | 5.7 | 74.0 | 0.2 | 20.1 | | | 0.1 | 100.5 | 177.3 |
| CV-25100S | 5/26/2026 10:48:42 AM | 4.0 | 80.8 | 0.0 | 15.2 | | | 0.0 | 0.0 | 160.8 |
| CV-25100S | 5/26/2026 10:48:08 AM | 4.0 | 78.6 | 0.0 | 17.4 | | | 0.1 | 0.0 | 158.1 |
| CV-25100S | 5/18/2026 10:40:00 AM | | | | | 3960 | | | | |
| CV-25100S | 5/18/2026 10:33:27 AM | 16.7 | 75.9 | 0.0 | 7.4 | | | 0.2 | 0.0 | 151.8 |
| CV-25100S | 5/12/2026 10:25:18 AM | 18.8 | 81.2 | 0.0 | 0.0 | | | 0.2 | 0.0 | 163.6 |
| CV-25100S | 5/12/2026 10:25:00 AM | | | | | 1030 | | | | |
| CV-25100S | 5/8/2026 10:01:43 AM | 1.2 | 83.1 | 0.0 | 15.7 | | | 0.0 | 0.0 | 182.3 |
| CV-25100S | 5/8/2026 10:00:14 AM | 1.2 | 76.1 | 0.0 | 22.7 | | | 0.0 | 0.0 | 182.8 |
| CV-25100S | 5/4/2026 2:45:00 PM | | | | | 3650 | | | | |
| CV-25100S | 5/4/2026 2:45:00 PM | | | | | | 138200 | | | |
| CV-25100S | 5/4/2026 2:38:27 PM | 1.8 | 86.7 | 0.0 | 11.5 | | | 0.0 | 0.0 | 181.2 |
| CV-25101D | 5/22/2026 10:43:56 AM | 5.2 | 68.1 | 4.0 | 22.7 | | | 0.1 | 5.7 | 80.3 |
| CV-25101D | 5/12/2026 1:33:31 PM | 5.4 | 76.9 | 1.0 | 16.7 | | | 0.1 | 16.7 | 82.6 |
| CV-25101S | 5/22/2026 10:46:24 AM | 24.4 | 64.4 | 0.0 | 11.2 | | | 0.4 | 0.0 | 112.3 |
| CV-25101S | 5/12/2026 1:23:51 PM | 18.7 | 59.6 | 0.2 | 21.5 | | | 0.3 | 107.5 | 122.9 |
| CV-25102_ | 5/20/2026 2:05:47 PM | 12.0 | 55.1 | 6.5 | 26.4 | | | 0.2 | 4.1 | 100.1 |
| CV-25102_ | 5/8/2026 10:11:54 AM | 4.5 | 28.4 | 13.0 | 54.1 | | | 0.2 | 4.2 | 83.2 |
| CV-25102_ | 5/8/2026 10:09:29 AM | 6.9 | 44.3 | 8.7 | 40.1 | | | 0.2 | 4.6 | 83.6 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-25103 | 5/22/2026 11:13:05 AM | 2.7 | 87.1 | 0.0 | 10.2 | | | 0.0 | 0.0 | 127.7 |
| CV-25103 | 5/20/2026 1:53:20 PM | 51.3 | 48.7 | 0.0 | 0.0 | | | 1.1 | 0.0 | 106.0 |
| CV-25103 | 5/12/2026 10:47:21 AM | 21.7 | 41.1 | 0.0 | 37.2 | | | 0.5 | 0.0 | 125.2 |
| CV-25103 | 5/12/2026 10:45:57 AM | 22.3 | 42.5 | 0.0 | 35.2 | | | 0.5 | 0.0 | 141.3 |
| CV-25104D | 5/20/2026 2:32:23 PM | 9.2 | 72.7 | 1.8 | 16.3 | | | 0.1 | 9.1 | 94.7 |
| CV-25104D | 5/13/2026 9:49:44 AM | 4.6 | 75.6 | 1.7 | 18.1 | | | 0.1 | 10.6 | 94.5 |
| CV-25104S | 5/20/2026 2:35:06 PM | 8.7 | 78.5 | 0.0 | 12.8 | | | 0.1 | 0.0 | 104.5 |
| CV-25104S | 5/13/2026 9:54:31 AM | 3.8 | 82.8 | 0.0 | 13.4 | | | 0.0 | 0.0 | 120.8 |
| CV-25105D | 5/22/2026 10:19:59 AM | 15.8 | 35.6 | 2.7 | 45.9 | | | 0.4 | 17.0 | 93.0 |
| CV-25105D | 5/8/2026 8:27:56 AM | 22.6 | 50.6 | 0.9 | 25.9 | | | 0.4 | 28.8 | 74.3 |
| CV-25105S | 5/20/2026 1:43:43 PM | 22.9 | 38.0 | 0.7 | 38.4 | | | 0.6 | 54.9 | 128.3 |
| CV-25105S | 5/8/2026 8:30:20 AM | 17.5 | 41.5 | 1.3 | 39.7 | | | 0.4 | 30.5 | 128.5 |
| CV-25106D | 5/26/2026 9:05:29 AM | 0.7 | 3.8 | 20.6 | 74.9 | | | 0.2 | 3.6 | 60.0 |
| CV-25106D | 5/26/2026 9:03:18 AM | 0.6 | 3.3 | 20.9 | 75.2 | | | 0.2 | 3.6 | 59.9 |
| CV-25106D | 5/12/2026 2:19:11 PM | 1.8 | 9.1 | 17.8 | 71.3 | | | 0.2 | 4.0 | 87.1 |
| CV-25106D | 5/12/2026 2:18:07 PM | 1.7 | 9.9 | 17.7 | 70.7 | | | 0.2 | 4.0 | 87.2 |
| CV-25106S | 5/26/2026 9:12:30 AM | 7.5 | 10.5 | 18.1 | 63.9 | | | 0.7 | 3.5 | 66.6 |
| CV-25106S | 5/26/2026 9:11:40 AM | 7.5 | 10.4 | 18.1 | 64.0 | | | 0.7 | 3.5 | 66.0 |
| CV-25106S | 5/12/2026 2:25:06 PM | 5.3 | 7.4 | 18.0 | 69.3 | | | 0.7 | 3.9 | 87.8 |
| CV-25106S | 5/12/2026 2:23:49 PM | 5.6 | 8.9 | 17.7 | 67.8 | | | 0.6 | 3.8 | 87.4 |
| CV-25107D | 5/1/2026 2:47:38 PM | 2.6 | 70.5 | 4.5 | 22.4 | | | 0.0 | 5.0 | 89.4 |
| CV-25107S | 5/1/2026 2:50:28 PM | 47.4 | 52.6 | 0.0 | 0.0 | | | 0.9 | 0.0 | 100.3 |
| CV-2511 | 5/5/2026 2:33:06 PM | 48.1 | 42.6 | 0.0 | 9.3 | | | 1.1 | 0.0 | 124.0 |
| CV-2512 | 5/5/2026 2:28:36 PM | 46.3 | 42.2 | 0.0 | 11.5 | | | 1.1 | 0.0 | 122.8 |
| CV-2513 | 5/7/2026 3:05:57 PM | 53.0 | 43.7 | 0.0 | 3.3 | | | 1.2 | 0.0 | 119.1 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init °F Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2514 | 5/8/2026 2:58:55 PM | 53.9 | 42.0 | 0.0 | 4.1 | | | 1.3 | 0.0 | 122.4 |
| CV-2515 | 5/7/2026 9:16:53 AM | 54.2 | 38.5 | 0.0 | 7.3 | | | 1.4 | 0.0 | 114.6 |
| CV-2516 | 5/11/2026 11:15:10 AM | 51.3 | 43.9 | 0.0 | 4.8 | | | 1.2 | 0.0 | 125.7 |
| CV-2517 | 5/7/2026 9:40:45 AM | 45.9 | 39.4 | 0.0 | 14.7 | | | 1.2 | 0.0 | 111.5 |
| CV-2518 | 5/7/2026 10:00:08 AM | 53.0 | 42.8 | 0.0 | 4.2 | | | 1.2 | 0.0 | 104.6 |
| CV-2518 | 5/7/2026 9:57:35 AM | 53.3 | 42.7 | 0.0 | 4.0 | | | 1.2 | 0.0 | 92.3 |
| CV-2519 | 5/1/2026 1:11:22 PM | 48.9 | 42.1 | 0.0 | 9.0 | | | 1.2 | 0.0 | 125.2 |
| CV-2520 | 5/1/2026 1:26:15 PM | 26.2 | 53.4 | 0.0 | 20.4 | | | 0.5 | 0.0 | 140.9 |
| CV-2520 | 5/1/2026 1:25:06 PM | 25.9 | 53.8 | 0.0 | 20.3 | | | 0.5 | 0.0 | 139.7 |
| CV-2521 | 5/26/2026 12:24:46 PM | 35.8 | 48.5 | 0.0 | 15.8 | | | 0.7 | 0.0 | 109.3 |
| CV-2522 | 5/5/2026 12:53:32 PM | 38.3 | 44.4 | 0.0 | 17.3 | | | 0.9 | 0.0 | 129.7 |
| CV-2522 | 5/1/2026 10:59:06 AM | 38.9 | 46.1 | 0.0 | 15.0 | | | 0.8 | 0.0 | 135.3 |
| CV-2522 | 5/1/2026 10:57:27 AM | 35.4 | 45.7 | 0.0 | 18.9 | | | 0.8 | 0.0 | 128.6 |
| CV-2523 | 5/4/2026 2:07:42 PM | 54.4 | 40.3 | 0.0 | 5.3 | | | 1.3 | 0.0 | 124.5 |
| CV-2524 | 5/1/2026 10:45:46 AM | 32.2 | 47.2 | 0.0 | 20.6 | | | 0.7 | 0.0 | 141.2 |
| CV-2524 | 5/1/2026 10:44:23 AM | 33.2 | 46.7 | 0.0 | 20.1 | | | 0.7 | 0.0 | 139.4 |
| CV-2525 | 5/4/2026 2:13:54 PM | 55.7 | 42.1 | 0.0 | 2.2 | | | 1.3 | 0.0 | 120.2 |
| CV-2525 | 5/4/2026 2:13:24 PM | 55.5 | 39.6 | 0.0 | 4.9 | | | 1.4 | 0.0 | 116.1 |
| CV-2526 | 5/4/2026 2:18:08 PM | 54.0 | 42.3 | 0.0 | 3.7 | | | 1.3 | 0.0 | 119.7 |
| CV-2527 | 5/15/2026 11:27:42 AM | 42.4 | 45.8 | 0.2 | 11.6 | | | 0.9 | 58.0 | 126.2 |
| CV-2528 | 5/11/2026 8:25:29 AM | 52.7 | 39.3 | 0.0 | 8.0 | | | 1.3 | 0.0 | 109.3 |
| CV-2529 | 5/8/2026 12:47:59 PM | 56.6 | 41.3 | 0.2 | 1.9 | | | 1.4 | 9.5 | 87.9 |
| CV-2530 | 5/12/2026 7:58:10 AM | 42.2 | 49.9 | 0.0 | 7.9 | | | 0.8 | 0.0 | 122.8 |
| CV-2531 | 5/8/2026 12:35:03 PM | 31.5 | 54.9 | 0.0 | 13.6 | | | 0.6 | 0.0 | 118.0 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [°F] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2531 | 5/8/2026 12:34:13 PM | 31.1 | 54.6 | 0.0 | 14.3 | | | 0.6 | 0.0 | 98.2 |
| CV-2532 | 5/12/2026 7:54:00 AM | 50.4 | 42.4 | 1.1 | 6.1 | | | 1.2 | 5.5 | 73.4 |
| CV-2533 | 5/12/2026 7:48:32 AM | 52.7 | 44.9 | 0.2 | 2.2 | | | 1.2 | 11.0 | 128.4 |
| CV-2534 | 5/11/2026 2:17:18 PM | 53.0 | 43.3 | 0.0 | 3.7 | | | 1.2 | 0.0 | 123.0 |
| CV-2535 | 5/5/2026 2:52:23 PM | 37.7 | 35.2 | 0.0 | 27.1 | | | 1.1 | 0.0 | 107.4 |
| CV-2536 | 5/14/2026 10:27:30 AM | 40.5 | 36.0 | 4.1 | 19.4 | | | 1.1 | 4.7 | 89.0 |
| CV-2537 | 5/6/2026 12:17:48 PM | 45.7 | 39.3 | 0.1 | 14.9 | | | 1.2 | 149.0 | 113.7 |
| CV-2538 | 5/6/2026 12:25:17 PM | 50.4 | 40.8 | 0.0 | 8.8 | | | 1.2 | 0.0 | 118.6 |
| CV-2539 | 5/20/2026 9:49:24 AM | 42.4 | 43.7 | 0.0 | 13.9 | | | 1.0 | 0.0 | 122.2 |
| CV-2539 | 5/4/2026 9:17:28 AM | 38.2 | 42.2 | 0.0 | 19.6 | | | 0.9 | 0.0 | 116.6 |
| CV-2540 | 5/20/2026 2:18:42 PM | 2.6 | 84.3 | 0.0 | 13.1 | | | 0.0 | 0.0 | 128.9 |
| CV-2540 | 5/20/2026 2:15:08 PM | 1.5 | 76.2 | 0.0 | 22.3 | | | 0.0 | 0.0 | 131.1 |
| CV-2540 | 5/14/2026 1:17:10 PM | 4.3 | 80.5 | 0.4 | 14.8 | | | 0.1 | 37.0 | 129.8 |
| CV-2540 | 5/14/2026 1:13:24 PM | 5.1 | 79.6 | 0.6 | 14.7 | | | 0.1 | 24.5 | 134.7 |
| CV-2541 | 5/19/2026 9:38:49 AM | 28.5 | 56.4 | 0.0 | 15.1 | | | 0.5 | 0.0 | 130.9 |
| CV-2541 | 5/19/2026 9:36:57 AM | 29.6 | 55.8 | 0.0 | 14.6 | | | 0.5 | 0.0 | 133.3 |
| CV-2541 | 5/1/2026 11:15:47 AM | 4.6 | 84.3 | 0.0 | 11.1 | | | 0.1 | 0.0 | 84.8 |
| CV-2541 | 5/1/2026 11:15:26 AM | 4.8 | 76.3 | 0.0 | 18.9 | | | 0.1 | 0.0 | 84.9 |
| CV-2542 | 5/21/2026 2:04:28 PM | 49.7 | 50.3 | 0.0 | 0.0 | | | 1.0 | 0.0 | 92.0 |
| CV-2542 | 5/4/2026 1:56:22 PM | 44.6 | 53.2 | 0.0 | 2.2 | | | 0.8 | 0.0 | 70.6 |
| CV-2543-PLR | 5/20/2026 1:43:43 PM | 20.5 | 66.9 | 0.5 | 12.1 | | | 0.3 | 24.2 | 104.5 |
| CV-2543-PLR | 5/4/2026 9:50:49 AM | 26.7 | 60.3 | 1.2 | 11.8 | | | 0.4 | 9.8 | 83.0 |
| CV-2544 | 5/21/2026 1:52:17 PM | 13.5 | 77.0 | 0.0 | 9.5 | | | 0.2 | 0.0 | 94.3 |
| CV-2544 | 5/21/2026 1:51:00 PM | 13.1 | 78.8 | 0.0 | 8.1 | | | 0.2 | 0.0 | 95.5 |
| CV-2544 | 5/6/2026 11:06:39 AM | 12.3 | 81.6 | 0.0 | 6.1 | | | 0.2 | 0.0 | 83.4 |
| CV-2545 | 5/22/2026 12:19:27 PM | 31.1 | 68.9 | 0.0 | 0.0 | | | 0.5 | 0.0 | 127.4 |
| CV-2545 | 5/22/2026 12:15:46 PM | 32.5 | 65.2 | 0.0 | 2.3 | | | 0.5 | 0.0 | 131.2 |
| CV-2545 | 5/6/2026 2:44:01 PM | 31.1 | 64.9 | 0.0 | 4.0 | | | 0.5 | 0.0 | 115.4 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [°F] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2545 | 5/6/2026 2:43:10 PM | 31.2 | 66.0 | 0.0 | 2.8 | | | 0.5 | 0.0 | 116.2 |
| CV-2546 | 5/22/2026 12:25:12 PM | 18.1 | 80.2 | 0.0 | 1.7 | | | 0.2 | 0.0 | 129.8 |
| CV-2546 | 5/22/2026 12:24:00 PM | 18.1 | 81.7 | 0.1 | 0.1 | | | 0.2 | 1.0 | 132.1 |
| CV-2546 | 5/6/2026 2:35:53 PM | 13.3 | 79.5 | 0.0 | 7.2 | | | 0.2 | 0.0 | 120.1 |
| CV-2547 | 5/28/2026 12:23:14 PM | 51.5 | 43.9 | 0.1 | 4.5 | | | 1.2 | 45.0 | 94.3 |
| CV-2547 | 5/22/2026 12:03:11 PM | 52.1 | 46.2 | 0.0 | 1.7 | | | 1.1 | 0.0 | 95.7 |
| CV-2547 | 5/6/2026 10:25:52 AM | 48.8 | 47.4 | 0.0 | 3.8 | | | 1.0 | 0.0 | 102.4 |
| CV-2548 | 5/13/2026 9:58:56 AM | 12.6 | 76.5 | 0.0 | 10.9 | | | 0.2 | 0.0 | 127.3 |
| CV-2548 | 5/1/2026 10:34:59 AM | 12.0 | 81.1 | 0.0 | 6.9 | | | 0.1 | 0.0 | 128.0 |
| CV-2549 | 5/28/2026 12:13:13 PM | 49.3 | 41.5 | 0.0 | 9.2 | | | 1.2 | 0.0 | 110.0 |
| CV-2549 | 5/13/2026 9:51:28 AM | 49.4 | 46.4 | 0.0 | 4.2 | | | 1.1 | 0.0 | 110.8 |
| CV-2549 | 5/6/2026 12:31:15 PM | 48.7 | 48.6 | 0.0 | 2.7 | | | 1.0 | 0.0 | 109.5 |
| CV-2549 | 5/1/2026 10:30:41 AM | 44.2 | 50.4 | 0.3 | 5.1 | | | 0.9 | 17.0 | 111.6 |
| CV-2550 | 5/27/2026 1:19:05 PM | 3.1 | 80.0 | 0.0 | 16.9 | | | 0.0 | 0.0 | 168.2 |
| CV-2550 | 5/21/2026 10:06:57 AM | 5.1 | 78.6 | 0.0 | 16.3 | | | 0.1 | 0.0 | 183.4 |
| CV-2550 | 5/21/2026 10:04:40 AM | 5.0 | 75.9 | 0.0 | 19.1 | | | 0.1 | 0.0 | 182.1 |
| CV-2550 | 5/11/2026 9:52:55 AM | 9.6 | 84.0 | 0.9 | 5.5 | | | 0.1 | 6.1 | 179.9 |
| CV-2550 | 5/4/2026 9:00:00 AM | | | | | 2670 | | | | |
| CV-2550 | 5/4/2026 8:59:59 AM | 3.4 | 77.8 | 0.0 | 18.8 | | | 0.0 | 0.0 | 183.8 |
| CV-2551 | 5/1/2026 2:40:59 PM | 13.9 | 84.0 | 0.0 | 2.1 | | | 0.2 | 0.0 | 134.9 |
| CV-2551 | 5/1/2026 2:39:32 PM | 14.2 | 79.8 | 0.1 | 5.9 | | | 0.2 | 59.0 | 135.5 |
| CV-2552 | 5/19/2026 1:50:38 PM | 53.6 | 46.4 | 0.0 | 0.0 | | | 1.2 | 0.0 | 115.0 |
| CV-2552 | 5/19/2026 1:49:24 PM | 50.9 | 49.1 | 0.0 | 0.0 | | | 1.0 | 0.0 | 112.0 |
| CV-2552 | 5/11/2026 9:58:44 AM | 34.9 | 64.8 | 0.3 | 0.0 | | | 0.5 | 0.0 | 176.5 |
| CV-2552 | 5/4/2026 9:36:17 AM | 23.7 | 63.1 | 0.0 | 13.2 | | | 0.4 | 0.0 | 173.8 |
| CV-2552 | 5/4/2026 9:35:00 AM | | | | | 2130 | | | | |
| CV-2552 | 5/4/2026 9:35:00 AM | | | | | | 67100 | | | |
| CV-2553 | 5/20/2026 1:24:17 PM | 43.3 | 51.7 | 0.2 | 4.8 | | | 0.8 | 24.0 | 112.9 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init °F Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2553 | 5/4/2026 9:36:18 AM | 47.2 | 51.3 | 0.0 | 1.5 | | | 0.9 | 0.0 | 87.3 |
| CV-2554 | 5/28/2026 1:40:06 PM | 25.3 | 70.7 | 0.0 | 4.0 | | | 0.4 | 0.0 | 148.6 |
| CV-2554 | 5/20/2026 2:11:24 PM | 24.3 | 69.4 | 0.1 | 6.2 | | | 0.4 | 62.0 | 148.5 |
| CV-2554 | 5/14/2026 11:13:27 AM | 33.9 | 66.0 | 0.1 | 0.0 | | | 0.5 | 0.0 | 158.2 |
| CV-2554 | 5/14/2026 11:12:34 AM | 31.9 | 68.0 | 0.1 | 0.0 | | | 0.5 | 0.0 | 159.4 |
| CV-2554 | 5/14/2026 11:10:00 AM | | | | | 1040 | | | | |
| CV-2554 | 5/4/2026 1:13:35 PM | 4.7 | 95.0 | 0.3 | 0.0 | | | 0.0 | 0.0 | 168.5 |
| CV-2554 | 5/4/2026 1:12:59 PM | 4.5 | 82.2 | 0.0 | 13.3 | | | 0.1 | 0.0 | 169.3 |
| CV-2554 | 5/4/2026 1:10:00 PM | | | | | 928 | | | | |
| CV-2554 | 5/4/2026 1:10:00 PM | | | | | | 70800 | | | |
| CV-2555 | 5/22/2026 11:41:33 AM | 4.2 | 8.8 | 20.1 | 66.9 | | | 0.5 | 3.3 | 92.3 |
| CV-2555 | 5/22/2026 11:39:04 AM | 6.9 | 10.2 | 18.6 | 64.3 | | | 0.7 | 3.5 | 83.4 |
| CV-2555 | 5/8/2026 1:12:17 PM | 12.8 | 26.0 | 12.4 | 48.8 | | | 0.5 | 3.9 | 83.2 |
| CV-2556 | 5/27/2026 2:02:24 PM | 3.3 | 82.4 | 0.0 | 14.3 | | | 0.0 | 0.0 | 177.0 |
| CV-2556 | 5/19/2026 1:45:00 PM | | | | | 2070 | | | | |
| CV-2556 | 5/19/2026 1:38:41 PM | 16.0 | 79.2 | 0.0 | 4.8 | | | 0.2 | 0.0 | 179.4 |
| CV-2556 | 5/11/2026 10:20:58 AM | 7.9 | 86.8 | 0.0 | 5.3 | | | 0.1 | 0.0 | 179.2 |
| CV-2556 | 5/4/2026 9:15:00 AM | | | | | 2935 | | | | |
| CV-2556 | 5/4/2026 9:15:00 AM | | | | | | 110800 | | | |
| CV-2556 | 5/4/2026 9:13:52 AM | 1.5 | 82.5 | 0.0 | 16.0 | | | 0.0 | 0.0 | 175.8 |
| CV-2557 | 5/20/2026 1:47:47 PM | 30.2 | 61.2 | 0.0 | 8.6 | | | 0.5 | 0.0 | 125.9 |
| CV-2557 | 5/8/2026 8:36:19 AM | 23.3 | 66.3 | 0.0 | 10.4 | | | 0.4 | 0.0 | 121.2 |
| CV-2558 | 5/27/2026 2:34:42 PM | 8.3 | 76.3 | 1.2 | 14.2 | | | 0.1 | 11.8 | 179.6 |
| CV-2558 | 5/27/2026 2:33:21 PM | 8.5 | 75.8 | 1.6 | 14.1 | | | 0.1 | 8.8 | 179.7 |
| CV-2558 | 5/19/2026 1:15:50 PM | 21.0 | 76.1 | 0.2 | 2.7 | | | 0.3 | 13.5 | 179.4 |
| CV-2558 | 5/19/2026 1:15:00 PM | | | | | 2790 | | | | |
| CV-2558 | 5/14/2026 10:19:35 AM | 16.1 | 79.8 | 0.0 | 4.1 | | | 0.2 | 0.0 | 183.9 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2558 | 5/14/2026 10:18:44 AM | 17.2 | 80.2 | 0.2 | 2.4 | | | 0.2 | 12.0 | 181.4 |
| CV-2558 | 5/14/2026 10:15:00 AM | | | | | 3750 | | | | |
| CV-2558 | 5/4/2026 8:47:30 AM | 3.8 | 74.2 | 0.9 | 21.1 | | | 0.1 | 23.4 | 186.9 |
| CV-2558 | 5/4/2026 8:45:31 AM | 3.6 | 71.4 | 2.4 | 22.6 | | | 0.1 | 9.4 | 186.2 |
| CV-2558 | 5/4/2026 8:45:00 AM | | | | | 4000 | | | | |
| CV-2559 | 5/8/2026 8:53:26 AM | 17.8 | 81.1 | 0.0 | 1.1 | | | 0.2 | 0.0 | 124.9 |
| CV-2559 | 5/8/2026 8:49:36 AM | 19.7 | 79.2 | 0.0 | 1.1 | | | 0.2 | 0.0 | 123.6 |
| CV-2560 | 5/22/2026 10:39:45 AM | 23.0 | 44.9 | 0.5 | 31.6 | | | 0.5 | 63.2 | 111.4 |
| CV-2560 | 5/12/2026 1:09:28 PM | 19.0 | 36.8 | 0.5 | 43.7 | | | 0.5 | 87.4 | 125.4 |
| CV-2561 | 5/11/2026 2:38:47 PM | 13.6 | 35.2 | 0.0 | 51.2 | | | 0.4 | 0.0 | 128.6 |
| CV-2562 | 5/11/2026 2:10:20 PM | 39.3 | 53.9 | 0.0 | 6.8 | | | 0.7 | 0.0 | 125.0 |
| CV-2563 | 5/28/2026 11:37:21 AM | 37.3 | 53.7 | 0.0 | 9.0 | | | 0.7 | 0.0 | 113.1 |
| CV-2563 | 5/28/2026 11:36:57 AM | 37.6 | 49.1 | 0.0 | 13.3 | | | 0.8 | 0.0 | 109.5 |
| CV-2563 | 5/15/2026 11:37:25 AM | 33.5 | 60.6 | 0.1 | 5.8 | | | 0.6 | 58.0 | 111.3 |
| CV-2563 | 5/15/2026 11:35:25 AM | 33.8 | 60.6 | 0.0 | 5.6 | | | 0.6 | 0.0 | 107.1 |
| CV-2564 | 5/21/2026 9:30:21 AM | 20.3 | 75.1 | 0.0 | 4.6 | | | 0.3 | 0.0 | 129.1 |
| CV-2564 | 5/21/2026 9:29:15 AM | 19.7 | 77.3 | 0.0 | 3.0 | | | 0.3 | 0.0 | 128.4 |
| CV-2564 | 5/1/2026 11:06:39 AM | 23.6 | 70.1 | 0.0 | 6.3 | | | 0.3 | 0.0 | 128.0 |
| CV-2565 | 5/20/2026 9:51:50 AM | 33.5 | 37.6 | 0.0 | 28.9 | | | 0.9 | 0.0 | 113.5 |
| CV-2565 | 5/4/2026 9:20:17 AM | 31.0 | 38.6 | 0.0 | 30.4 | | | 0.8 | 0.0 | 111.0 |
| CV-2566 | 5/20/2026 9:46:01 AM | 51.5 | 48.5 | 0.1 | | | | 1.1 | | 108.2 |
| CV-2566 | 5/4/2026 9:24:42 AM | 48.7 | 46.3 | 0.0 | 5.0 | | | 1.1 | 0.0 | 100.7 |
| CV-2567 | 5/20/2026 12:20:18 PM | 48.6 | 48.7 | 0.1 | 2.6 | | | 1.0 | 26.0 | 109.2 |
| CV-2567 | 5/4/2026 9:43:22 AM | 49.6 | 46.8 | 0.0 | 3.6 | | | 1.1 | 0.0 | 99.5 |
| CV-2568 | 5/20/2026 11:39:12 AM | 44.0 | 50.3 | 0.0 | 5.7 | | | 0.9 | 0.0 | 109.3 |
| CV-2568 | 5/4/2026 11:23:44 AM | 42.5 | 45.6 | 0.0 | 11.9 | | | 0.9 | 0.0 | 91.4 |
| CV-2569 | 5/20/2026 11:29:23 AM | 45.4 | 54.6 | 0.0 | 0.0 | | | 0.8 | 0.0 | 110.3 |
| CV-2569 | 5/4/2026 11:29:19 AM | 45.4 | 47.9 | 0.0 | 6.7 | | | 0.9 | 0.0 | 92.7 |
| CV-2570 | 5/20/2026 11:15:26 AM | 50.8 | 49.2 | 0.0 | 0.0 | | | 1.0 | 0.0 | 112.6 |
| CV-2570 | 5/4/2026 11:34:49 AM | 49.8 | 45.3 | 0.0 | 4.9 | | | 1.1 | 0.0 | 98.5 |
| CV-2571 | 5/7/2026 1:00:36 PM | 51.2 | 41.2 | 0.0 | 7.6 | | | 1.2 | 0.0 | 96.5 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2572 | 5/7/2026 1:32:16 PM | 52.6 | 42.0 | 0.0 | 5.4 | | | 1.3 | 0.0 | 121.9 |
| CV-48R | 5/28/2026 11:41:20 AM | 51.7 | 43.5 | 0.0 | 4.8 | | | 1.2 | 0.0 | 116.4 |
| CV-48R | 5/28/2026 11:40:34 AM | 50.6 | 41.0 | 0.0 | 8.4 | | | 1.2 | 0.0 | 116.0 |
| CV-48R | 5/15/2026 11:44:42 AM | 49.0 | 50.2 | 0.0 | 0.8 | | | 1.0 | 0.0 | 116.1 |
| CV-48R | 5/6/2026 10:23:03 AM | 53.1 | 46.8 | 0.0 | 0.1 | | | 1.1 | 0.0 | 119.9 |
| CV-52D | 5/1/2026 1:17:29 PM | 30.1 | 50.2 | 1.3 | 18.4 | | | 0.6 | 14.2 | 94.8 |
| CV-55R | 5/27/2026 3:07:28 PM | 33.0 | 48.7 | 0.4 | 17.9 | | | 0.7 | 44.8 | 142.0 |
| CV-55R | 5/21/2026 9:11:16 AM | 20.8 | 54.1 | 0.0 | 25.1 | | | 0.4 | 0.0 | 133.4 |
| CV-55R | 5/21/2026 9:10:09 AM | 14.0 | 46.3 | 0.0 | 39.7 | | | 0.3 | 0.0 | 90.1 |
| CV-55R | 5/11/2026 11:02:29 AM | 49.6 | 50.4 | 0.0 | 0.0 | | | 1.0 | 0.0 | 153.3 |
| CV-55R | 5/4/2026 8:05:00 AM | | | | | 181.5 | | | | |
| CV-55R | 5/4/2026 8:05:00 AM | | | | | | 140550 | | | |
| CV-55R | 5/4/2026 8:04:21 AM | 37.3 | 44.5 | 0.0 | 18.2 | | | 0.8 | 0.0 | 149.7 |
| CV-56D | 5/7/2026 11:25:28 AM | 4.1 | 4.7 | 18.5 | 72.7 | | | 0.9 | 3.9 | 92.3 |
| CV-56D | 5/7/2026 11:22:51 AM | 18.5 | 20.7 | 11.8 | 49.0 | | | 0.9 | 4.2 | 92.4 |
| CV-56S | 5/7/2026 11:32:33 AM | 2.6 | 32.0 | 7.5 | 57.9 | | | 0.1 | 7.7 | 89.2 |
| CV-56S | 5/7/2026 11:29:21 AM | 2.9 | 33.4 | 6.9 | 56.8 | | | 0.1 | 8.2 | 90.9 |
| CV-57R | 5/1/2026 2:21:40 PM | 52.1 | 41.9 | 0.0 | 6.0 | | | 1.2 | 0.0 | 87.9 |
| CV-79R | 5/1/2026 2:41:23 PM | 52.3 | 43.5 | 0.0 | 4.2 | | | 1.2 | 0.0 | 125.4 |
| CV-94 | 5/11/2026 3:29:38 PM | 51.7 | 42.4 | 0.0 | 5.9 | | | 1.2 | 0.0 | 114.0 |
| CV-94 | 5/11/2026 3:28:29 PM | 54.9 | 43.4 | 0.0 | 1.7 | | | 1.3 | 0.0 | 108.3 |
| CV-95 | 5/1/2026 2:19:24 PM | 52.4 | 39.5 | 0.0 | 8.1 | | | 1.3 | 0.0 | 104.3 |
| CV-95 | 5/1/2026 2:18:38 PM | 51.3 | 38.6 | 0.0 | 10.1 | | | 1.3 | 0.0 | 93.6 |
| CV-99 | 5/26/2026 1:51:48 PM | 26.1 | 73.9 | 0.0 | 0.0 | | | 0.4 | 0.0 | 77.4 |
| CV-99 | 5/4/2026 7:45:00 AM | | | | | | 2600 | | | |
| D-02 | 5/28/2026 3:29:22 PM | 57.8 | 42.2 | 0.0 | 0.0 | | | 1.4 | 0.0 | 84.9 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init °F Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| D-03 | 5/28/2026 3:32:52 PM | 53.1 | 41.6 | 1.6 | 3.7 | | | 1.3 | 2.3 | 86.8 |
| D-04 | 5/28/2026 3:41:09 PM | 58.5 | 41.5 | 0.0 | 0.0 | | | 1.4 | 0.0 | 76.9 |
| D-09 | 5/7/2026 1:18:48 PM | 52.1 | 40.6 | 0.0 | 7.3 | | | 1.3 | 0.0 | 111.4 |
| D-10 | 5/7/2026 1:08:35 PM | 45.6 | 35.0 | 2.7 | 16.7 | | | 1.3 | 6.2 | 107.3 |
| FP-001 | 5/8/2026 9:19:36 AM | 9.3 | 21.4 | 4.7 | 64.6 | | | 0.4 | 13.7 | 81.0 |
| FP-002 | 5/8/2026 9:28:39 AM | 16.5 | 25.5 | 4.0 | 54.0 | | | 0.6 | 13.5 | 78.6 |
| FP-003 | 5/8/2026 9:39:47 AM | 8.7 | 16.6 | 8.1 | 66.6 | | | 0.5 | 8.2 | 79.4 |
| FP-003 | 5/8/2026 9:36:36 AM | 8.4 | 16.6 | 8.3 | 66.7 | | | 0.5 | 8.0 | 79.6 |
| FP-005 | 5/15/2026 2:55:43 PM | 6.0 | 23.1 | 12.4 | 58.5 | | | 0.3 | 4.7 | 82.4 |
| FP-006 | 5/15/2026 2:51:55 PM | 20.7 | 78.2 | 0.0 | 1.1 | | | 0.3 | 0.0 | 82.4 |
| FP-008 | 5/15/2026 3:10:45 PM | 14.7 | 70.2 | 1.4 | 13.7 | | | 0.2 | 9.8 | 88.4 |
| FP-008 | 5/6/2026 9:22:39 AM | 18.8 | 76.7 | 0.0 | 4.5 | | | 0.2 | 0.0 | 80.2 |
| FP-009 | 5/13/2026 10:12:04 AM | 11.7 | 79.4 | 0.0 | 8.9 | | | 0.1 | 0.0 | 94.3 |
| FP-010 | 5/13/2026 10:03:04 AM | 17.6 | 79.9 | 0.0 | 2.5 | | | 0.2 | 0.0 | 105.2 |
| FP-011 | 5/13/2026 10:00:11 AM | 30.2 | 62.9 | 1.4 | 5.5 | | | 0.5 | 3.9 | 73.6 |
| FP-012 | 5/19/2026 8:39:03 AM | 13.1 | 18.8 | 14.6 | 53.5 | | | 0.7 | 3.7 | 82.2 |
| FP-012 | 5/1/2026 11:49:02 AM | 9.4 | 10.5 | 17.4 | 62.7 | | | 0.9 | 3.6 | 83.7 |
| FP-013 | 5/19/2026 9:34:22 AM | 25.1 | 35.6 | 6.1 | 33.2 | | | 0.7 | 5.4 | 77.7 |
| FP-013 | 5/13/2026 9:55:27 AM | 19.9 | 25.3 | 9.2 | 45.6 | | | 0.8 | 5.0 | 75.1 |
| FP-014 | 5/13/2026 2:03:06 PM | 19.4 | 72.7 | 0.0 | 7.9 | | | 0.3 | 0.0 | 85.0 |
| FP-015 | 5/15/2026 2:35:16 PM | 1.7 | 49.5 | 8.1 | 40.7 | | | 0.0 | 5.0 | 79.6 |
| FP-015 | 5/14/2026 2:08:49 PM | 2.5 | 70.5 | 0.7 | 26.3 | | | 0.0 | 38.1 | 171.9 |
| FP-015 | 5/13/2026 2:12:26 PM | 4.7 | 75.2 | 0.8 | 19.3 | | | 0.1 | 24.1 | 175.6 |
| FP-016 | 5/15/2026 2:43:10 PM | 11.5 | 54.8 | 6.2 | 27.5 | | | 0.2 | 4.4 | 88.6 |
| FP-016 | 5/13/2026 2:15:57 PM | 13.7 | 55.9 | 6.6 | 23.8 | | | 0.2 | 3.6 | 88.7 |
| FP-017 | 5/8/2026 12:57:34 PM | 45.4 | 33.2 | 3.2 | 18.2 | | | 1.4 | 5.7 | 88.5 |
| FP-018 | 5/8/2026 12:40:54 PM | 22.4 | 17.2 | 11.4 | 49.0 | | | 1.3 | 4.3 | 87.3 |
| FP-019 | 5/12/2026 1:48:27 PM | 53.7 | 42.4 | 0.0 | 3.9 | | | 1.3 | 0.0 | 79.3 |
| FP-020 | 5/12/2026 1:57:00 PM | 14.5 | 71.5 | 0.0 | 14.0 | | | 0.2 | 0.0 | 83.0 |
| FP-021 | 5/13/2026 10:41:14 AM | 29.1 | 63.4 | 0.0 | 7.5 | | | 0.5 | 0.0 | 90.8 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| FP-021 | 5/12/2026 1:59:43 PM | 21.8 | 70.3 | 0.0 | 7.9 | | | 0.3 | 0.0 | 95.6 |
| FP-022 | 5/13/2026 10:32:37 AM | 18.1 | 66.0 | 0.7 | 15.2 | | | 0.3 | 21.7 | 90.2 |
| FP-023 | 5/13/2026 1:46:18 PM | 22.6 | 58.6 | 3.6 | 15.2 | | | 0.4 | 4.2 | 84.5 |
| FP-024 | 5/20/2026 2:16:33 PM | 33.1 | 65.0 | 0.6 | 1.3 | | | 0.5 | 2.2 | 96.6 |
| FP-025 | 5/20/2026 2:19:20 PM | 27.3 | 51.6 | 2.0 | 19.1 | | | 0.5 | 9.6 | 84.1 |
| FP-026 | 5/29/2026 4:20:14 PM | 12.5 | 39.6 | 8.4 | 39.5 | | | 0.3 | 4.7 | 78.0 |
| FP-027 | 5/29/2026 4:24:24 PM | 12.6 | 29.6 | 10.1 | 47.7 | | | 0.4 | 4.7 | 88.0 |
| FP-028 | 5/28/2026 11:39:27 AM | 0.3 | 0.4 | 20.7 | 78.6 | | | 0.8 | 3.8 | 81.3 |
| FP-029 | 5/28/2026 11:31:57 AM | 0.0 | 0.3 | 20.9 | 78.8 | | | 0.0 | 3.8 | 74.2 |
| FP-030 | 5/12/2026 1:41:15 PM | 52.2 | 47.8 | 0.0 | 0.0 | | | 1.1 | 0.0 | 76.4 |
| FP-031 | 5/29/2026 9:22:16 AM | 33.3 | 55.8 | 1.3 | 9.6 | | | 0.6 | 7.4 | 76.3 |
| FP-031 | 5/12/2026 1:37:06 PM | 31.5 | 53.2 | 1.3 | 14.0 | | | 0.6 | 10.8 | 77.9 |
| FP-032 | 5/12/2026 1:28:30 PM | 23.9 | 53.3 | 4.5 | 18.3 | | | 0.4 | 4.1 | 80.6 |
| FP-033 | 5/12/2026 1:23:05 PM | 6.3 | 35.3 | 10.9 | 47.5 | | | 0.2 | 4.4 | 86.3 |
| FP-034 | 5/12/2026 1:19:44 PM | 19.7 | 37.5 | 5.9 | 36.9 | | | 0.5 | 6.3 | 84.6 |
| FP-035 | 5/12/2026 1:16:01 PM | 34.1 | 48.9 | 2.3 | 14.7 | | | 0.7 | 6.4 | 76.8 |
| FP-036 | 5/1/2026 11:36:11 AM | 31.3 | 49.3 | 2.7 | 16.7 | | | 0.6 | 6.2 | 77.8 |
| FP-037 | 5/19/2026 10:33:25 AM | 6.2 | 18.7 | 16.7 | 58.4 | | | 0.3 | 3.5 | 84.7 |
| FP-037 | 5/1/2026 11:38:38 AM | 2.9 | 7.0 | 19.5 | 70.6 | | | 0.4 | 3.6 | 83.2 |
| FP-038 | 5/14/2026 2:24:47 PM | 44.8 | 37.9 | 3.0 | 14.3 | | | 1.2 | 4.8 | 86.9 |
| FP-039 | 5/14/2026 2:15:09 PM | 52.9 | 44.8 | 0.1 | 2.2 | | | 1.2 | 22.0 | 89.9 |
| FP-040 | 5/29/2026 2:30:36 PM | 16.6 | 68.3 | 1.6 | 13.5 | | | 0.2 | 8.4 | 104.5 |
| FP-041 | 5/13/2026 1:16:55 PM | 20.7 | 33.1 | 4.0 | 42.2 | | | 0.6 | 10.6 | 88.1 |
| FP-042 | 5/20/2026 10:11:54 AM | 19.2 | 61.9 | 3.6 | 15.3 | | | 0.3 | 4.3 | 97.0 |
| FP-043 | 5/13/2026 1:22:06 PM | 14.0 | 33.0 | 6.4 | 46.6 | | | 0.4 | 7.3 | 89.9 |
| FP-044 | 5/13/2026 1:25:38 PM | 4.0 | 21.3 | 14.0 | 60.7 | | | 0.2 | 4.3 | 91.6 |
| FP-045 | 5/11/2026 1:04:40 PM | 29.5 | 38.9 | 2.8 | 28.8 | | | 0.8 | 10.2 | 121.6 |
| FP-046 | 5/15/2026 3:02:41 PM | 22.0 | 73.7 | 1.2 | 3.1 | | | 0.3 | 2.6 | 81.9 |
| FP-047 | 5/29/2026 11:36:35 AM | 19.3 | 51.2 | 2.5 | 27.0 | | | 0.4 | 10.8 | 86.1 |
| FP-050 | 5/6/2026 2:53:31 PM | 16.4 | 41.9 | 4.9 | 36.8 | | | 0.4 | 7.5 | 87.3 |
| FP-051 | 5/6/2026 2:48:25 PM | 36.4 | 48.1 | 1.0 | 14.5 | | | 0.8 | 14.5 | 92.2 |
| FP-052 | 5/22/2026 2:09:54 PM | 11.2 | 15.2 | 11.6 | 62.0 | | | 0.7 | 5.3 | 89.0 |
| FP-052 | 5/4/2026 2:20:50 PM | 16.2 | 21.0 | 9.8 | 53.0 | | | 0.8 | 5.4 | 80.4 |
| FP-053 | 5/21/2026 2:19:03 PM | 45.7 | 54.3 | 0.0 | 0.0 | | | 0.8 | 0.0 | 100.2 |
| FP-053 | 5/4/2026 2:08:41 PM | 37.2 | 36.6 | 3.4 | 22.8 | | | 1.0 | 6.7 | 85.2 |
| FP-054 | 5/1/2026 11:30:37 AM | 36.6 | 34.7 | 0.9 | 27.8 | | | 1.1 | 30.9 | 86.0 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| FP-055 | 5/20/2026 2:00:54 PM | 52.4 | 41.8 | 0.0 | 5.8 | | | 1.3 | 0.0 | 103.6 |
| FP-055 | 5/4/2026 10:03:30 AM | 48.5 | 39.7 | 1.2 | 10.6 | | | 1.2 | 8.8 | 78.7 |
| FP-056 | 5/4/2026 9:15:22 AM | 47.3 | 40.3 | 0.4 | 12.0 | | | 1.2 | 30.0 | 74.3 |
| FP-057 | 5/4/2026 9:17:47 AM | 39.7 | 45.5 | 0.0 | 14.8 | | | 0.9 | 0.0 | 104.8 |
| FP-057 | 5/1/2026 11:34:44 AM | 40.1 | 33.2 | 2.5 | 24.2 | | | 1.2 | 9.7 | 79.6 |
| FP-058 | 5/29/2026 3:51:49 PM | 41.8 | 38.7 | 1.3 | 18.2 | | | 1.1 | 14.0 | 85.7 |
| FP-059 | 5/1/2026 2:35:49 PM | 50.1 | 40.3 | 1.5 | 8.1 | | | 1.2 | 5.4 | 92.7 |
| FP-060 | 5/1/2026 2:53:38 PM | 43.2 | 35.8 | 3.1 | 17.9 | | | 1.2 | 5.8 | 91.0 |
| FP-061 | 5/15/2026 2:38:19 PM | 5.3 | 76.0 | 0.8 | 17.9 | | | 0.1 | 22.4 | 148.5 |
| FP-061 | 5/14/2026 2:22:44 PM | 4.0 | 70.6 | 0.5 | 24.9 | | | 0.1 | 47.9 | 158.1 |
| FP-061 | 5/14/2026 2:19:38 PM | 4.4 | 64.7 | 2.3 | 28.6 | | | 0.1 | 12.4 | 161.6 |
| H-01 (EXP-01) | 5/26/2026 8:45:19 AM | 17.8 | 46.9 | 0.0 | 35.3 | | | 0.4 | 0.0 | 61.8 |
| H-01 (EXP-01) | 5/12/2026 1:49:58 PM | 15.8 | 46.3 | 0.0 | 38.0 | | | 0.3 | 0.0 | 96.9 |
| H-02 (EXP-02) | 5/26/2026 8:27:48 AM | 16.7 | 48.7 | 0.0 | 34.6 | | | 0.3 | 0.0 | 84.1 |
| H-02 (EXP-02) | 5/12/2026 1:55:38 PM | 12.8 | 48.1 | 0.0 | 39.2 | | | 0.3 | 0.0 | 110.4 |
| H-03 (EXP-03) | 5/26/2026 8:31:53 AM | 56.5 | 43.5 | 0.0 | 0.0 | | | 1.3 | 0.0 | 112.6 |
| H-03 (EXP-03) | 5/12/2026 2:02:02 PM | 50.8 | 45.2 | 0.0 | 4.1 | | | 1.1 | 0.0 | 118.9 |
| H-04 (EXP-04) | 5/26/2026 8:34:46 AM | 3.6 | 55.1 | 0.0 | 41.3 | | | 0.1 | 0.0 | 124.2 |
| H-04 (EXP-04) | 5/14/2026 10:16:02 AM | 3.0 | 55.2 | 0.0 | 41.8 | | | 0.1 | 0.0 | 131.1 |
| H-04 (EXP-04) | 5/14/2026 10:14:56 AM | 3.0 | 54.1 | 0.0 | 42.9 | | | 0.1 | 0.0 | 131.2 |
| H-04 (EXP-04) | 5/14/2026 10:13:50 AM | 3.4 | 55.1 | 0.0 | 41.5 | | | 0.1 | 0.0 | 130.7 |
| H-08 (EXP-08) | 5/26/2026 8:55:13 AM | 52.1 | 47.9 | 0.0 | 0.0 | | | 1.1 | 0.0 | 119.2 |
| H-08 (EXP-08) | 5/11/2026 9:46:50 AM | 48.8 | 46.1 | 0.0 | 5.1 | | | 1.1 | 0.0 | 88.4 |
| H-10 (EXP-10) | 5/26/2026 9:06:45 AM | 12.5 | 72.3 | 0.0 | 15.2 | | | 0.2 | 0.0 | 130.8 |
| H-10 (EXP-10) | 5/11/2026 9:40:46 AM | 10.6 | 66.8 | 0.0 | 22.6 | | | 0.2 | 0.0 | 130.8 |
| H-10 (EXP-10) | 5/11/2026 9:40:06 AM | 10.8 | 66.1 | 0.0 | 23.0 | | | 0.2 | 0.0 | 130.8 |
| H-101W | 5/13/2026 8:32:50 AM | 22.3 | 15.9 | 13.6 | 48.2 | | | 1.4 | 3.5 | 65.5 |
| H-101W | 5/13/2026 8:24:13 AM | 24.1 | 18.7 | 12.8 | 44.4 | | | 1.3 | 3.5 | 64.3 |
| H-102A | 5/13/2026 8:17:41 AM | 56.3 | 35.3 | 1.4 | 7.0 | | | 1.6 | 5.0 | 66.5 |
| H-1401W | 5/13/2026 8:48:53 AM | 54.9 | 33.8 | 2.2 | 9.1 | | | 1.6 | 4.1 | 70.1 |
| H-1404C | 5/20/2026 11:55:54 AM | 27.5 | 36.8 | 0.1 | 35.6 | | | 0.7 | 356.0 | 129.2 |
| H-1404C | 5/4/2026 11:20:18 AM | 25.8 | 32.1 | 0.0 | 42.1 | | | 0.8 | 0.0 | 124.8 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| H-1405C | 5/20/2026 8:39:42 AM | 26.3 | 38.0 | 0.0 | 35.7 | | | 0.7 | 0.0 | 94.7 |
| H-1405C | 5/1/2026 10:13:01 AM | 42.8 | 46.0 | 0.0 | 11.2 | | | 0.9 | 0.0 | 87.5 |
| H-1406W | 5/20/2026 9:30:46 AM | 40.6 | 41.7 | 3.6 | 14.1 | | | 1.0 | 3.9 | 88.8 |
| H-1406W | 5/1/2026 10:30:28 AM | 35.6 | 50.7 | 3.1 | 10.6 | | | 0.7 | 3.4 | 80.7 |
| H-1408CR | 5/6/2026 2:48:15 PM | 28.1 | 37.4 | 0.0 | 34.5 | | | 0.8 | 0.0 | 125.8 |
| H-1408CR | 5/6/2026 2:46:51 PM | 37.4 | 42.1 | 0.0 | 20.5 | | | 0.9 | 0.0 | 118.0 |
| H-1408E | 5/20/2026 2:13:20 PM | 49.3 | 42.6 | 0.0 | 8.1 | | | 1.2 | 0.0 | 111.7 |
| H-1408E | 5/4/2026 2:44:00 PM | 36.9 | 37.6 | 0.1 | 25.4 | | | 1.0 | 254.0 | 107.3 |
| H-1408E | 5/4/2026 2:42:19 PM | 39.8 | 38.2 | 0.1 | 21.9 | | | 1.0 | 219.0 | 103.3 |
| H-1408W | 5/7/2026 10:26:18 AM | 52.7 | 42.9 | 0.0 | 4.4 | | | 1.2 | 0.0 | 102.9 |
| H-1409N | 5/20/2026 2:26:47 PM | 37.7 | 36.9 | 0.0 | 25.4 | | | 1.0 | 0.0 | 116.1 |
| H-1409N | 5/4/2026 2:02:48 PM | 36.0 | 34.1 | 0.0 | 29.9 | | | 1.1 | 0.0 | 111.5 |
| H-1410S | 5/6/2026 12:22:14 PM | 41.2 | 35.3 | 2.3 | 21.2 | | | 1.2 | 9.2 | 87.5 |
| H-1563N | 5/22/2026 2:12:17 PM | 49.7 | 44.6 | 0.0 | 5.7 | | | 1.1 | 0.0 | 115.7 |
| H-1563N | 5/11/2026 12:47:48 PM | 47.3 | 45.1 | 0.0 | 7.6 | | | 1.0 | 0.0 | 114.9 |
| H-1563S | 5/20/2026 8:43:45 AM | 10.4 | 25.8 | 0.0 | 63.8 | | | 0.4 | 0.0 | 89.3 |
| H-1563S | 5/1/2026 10:06:27 AM | 18.4 | 38.6 | 0.0 | 43.0 | | | 0.5 | 0.0 | 93.5 |
| H-1565E | 5/21/2026 10:26:51 AM | 54.0 | 40.3 | 0.0 | 5.7 | | | 1.3 | 0.0 | 116.3 |
| H-1565E | 5/6/2026 10:50:58 AM | 49.1 | 48.8 | 0.0 | 2.1 | | | 1.0 | 0.0 | 114.8 |
| H-1568N | 5/21/2026 10:57:34 AM | 44.2 | 55.8 | 0.0 | 0.0 | | | 0.8 | 0.0 | 124.8 |
| H-1568N | 5/20/2026 2:05:18 PM | 46.5 | 41.0 | 0.0 | 12.5 | | | 1.1 | 0.0 | 113.8 |
| H-1568N | 5/4/2026 2:46:50 PM | 33.8 | 34.3 | 0.0 | 31.9 | | | 1.0 | 0.0 | 107.3 |
| H-1571S | 5/4/2026 11:05:46 AM | 47.5 | 43.5 | 0.0 | 9.0 | | | 1.1 | 0.0 | 81.3 |
| H-1572N | 5/1/2026 2:47:42 PM | 42.4 | 36.3 | 0.4 | 20.9 | | | 1.2 | 52.3 | 101.0 |
| H-1572S | 5/4/2026 10:51:40 AM | 40.0 | 38.4 | 0.0 | 21.6 | | | 1.0 | 0.0 | 96.0 |
| H-1574N | 5/20/2026 10:38:18 AM | 47.2 | 43.4 | 0.0 | 9.4 | | | 1.1 | 0.0 | 103.6 |
| H-1574N | 5/13/2026 9:52:29 AM | 8.7 | 79.6 | 0.0 | 11.7 | | | 0.1 | 0.0 | 140.4 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| H-1574N | 5/12/2026 8:59:40 AM | 43.3 | 43.8 | 1.1 | 11.8 | | | 1.0 | 10.7 | 98.5 |
| H-1753N | 5/26/2026 9:00:32 AM | 47.7 | 47.2 | 0.8 | 4.3 | | | 1.0 | 5.4 | 66.7 |
| H-1753N | 5/12/2026 1:45:21 PM | 40.8 | 32.4 | 4.7 | 22.1 | | | 1.3 | 4.7 | 84.5 |
| H-1753S | 5/22/2026 2:02:07 PM | 53.8 | 39.6 | 0.0 | 6.6 | | | 1.4 | 0.0 | 111.9 |
| H-1753S | 5/11/2026 12:40:59 PM | 52.9 | 41.3 | 0.0 | 5.8 | | | 1.3 | 0.0 | 107.2 |
| H-1756S | 5/19/2026 1:28:24 PM | 36.4 | 61.1 | 0.0 | 2.5 | | | 0.6 | 0.0 | 129.8 |
| H-1756S | 5/19/2026 1:25:39 PM | 36.1 | 62.4 | 0.0 | 1.5 | | | 0.6 | 0.0 | 131.0 |
| H-1756S | 5/13/2026 12:47:50 PM | 32.3 | 58.2 | 0.1 | 9.4 | | | 0.6 | 94.0 | 127.6 |
| H-1757S | 5/20/2026 8:35:55 AM | 45.9 | 45.3 | 0.0 | 8.8 | | | 1.0 | 0.0 | 80.8 |
| H-1757S | 5/1/2026 10:14:46 AM | 46.1 | 44.3 | 0.0 | 9.6 | | | 1.0 | 0.0 | 81.3 |
| H-1760S | 5/21/2026 10:10:39 AM | 38.7 | 48.8 | 0.0 | 12.5 | | | 0.8 | 0.0 | 115.9 |
| H-1760S | 5/11/2026 1:37:59 PM | 38.2 | 45.2 | 0.0 | 16.6 | | | 0.8 | 0.0 | 119.0 |
| H-1762N | 5/20/2026 1:57:03 PM | 51.7 | 42.3 | 0.0 | 6.0 | | | 1.2 | 0.0 | 108.7 |
| H-1762N | 5/20/2026 1:55:17 PM | 51.5 | 42.7 | 0.0 | 5.8 | | | 1.2 | 0.0 | 108.6 |
| H-1762N | 5/4/2026 2:38:51 PM | 51.2 | 40.6 | 0.0 | 8.2 | | | 1.3 | 0.0 | 100.5 |
| H-1763N | 5/6/2026 10:36:14 AM | 26.5 | 66.5 | 0.0 | 7.0 | | | 0.4 | 0.0 | 104.7 |
| H-1763N | 5/6/2026 10:34:51 AM | 23.5 | 67.8 | 0.0 | 8.7 | | | 0.3 | 0.0 | 95.6 |
| H-1763S | 5/4/2026 11:26:50 AM | 43.0 | 40.8 | 0.0 | 16.2 | | | 1.1 | 0.0 | 102.6 |
| H-1764N | 5/28/2026 12:39:39 PM | 54.1 | 40.7 | 0.0 | 5.2 | | | 1.3 | 0.0 | 116.8 |
| H-1764N | 5/5/2026 1:16:30 PM | 53.8 | 39.4 | 0.0 | 6.8 | | | 1.4 | 0.0 | 117.3 |
| H-1764N | 5/4/2026 11:45:03 AM | 55.1 | 40.1 | 0.0 | 4.8 | | | 1.4 | 0.0 | 117.2 |
| H-1764S | 5/4/2026 11:08:05 AM | 48.3 | 45.4 | 0.0 | 6.3 | | | 1.1 | 0.0 | 91.0 |
| H-1767N | 5/11/2026 9:51:22 AM | 39.0 | 54.5 | 0.0 | 6.5 | | | 0.7 | 0.0 | 101.8 |
| H-1769N | 5/19/2026 8:53:05 AM | 24.1 | 65.8 | 0.0 | 10.1 | | | 0.4 | 0.0 | 107.8 |
| H-1769N | 5/1/2026 2:30:15 PM | 20.8 | 52.8 | 0.9 | 25.5 | | | 0.4 | 28.3 | 110.1 |
| H-1770N | 5/19/2026 9:18:49 AM | 36.3 | 61.0 | 0.0 | 2.7 | | | 0.6 | 0.0 | 99.2 |
| H-1770N | 5/4/2026 8:50:00 AM | | | | | | 12000 | | | |
| H-1770N | 5/1/2026 2:42:44 PM | 35.3 | 62.8 | 0.0 | 1.9 | | | 0.6 | 0.0 | 100.2 |
| H-1770S | 5/19/2026 12:50:46 PM | 31.2 | 59.0 | 0.0 | 9.8 | | | 0.5 | 0.0 | 102.4 |
| H-1770S | 5/1/2026 10:34:30 AM | 17.2 | 41.1 | 1.6 | 40.1 | | | 0.4 | 25.1 | 101.2 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| H-1771A | 5/11/2026 2:21:58 PM | 43.9 | 39.4 | 0.0 | 16.7 | | | 1.1 | 0.0 | 113.2 |
| H-1771B | 5/13/2026 11:22:20 AM | 45.2 | 53.4 | 0.0 | 1.4 | | | 0.8 | 0.0 | 130.4 |
| H-1771B | 5/13/2026 11:19:01 AM | 40.2 | 59.1 | 0.0 | 0.7 | | | 0.7 | 0.0 | 132.7 |
| H-1771B | 5/11/2026 1:05:25 PM | 51.3 | 46.2 | 0.0 | 2.5 | | | 1.1 | 0.0 | 104.5 |
| H-1771B | 5/11/2026 1:04:43 PM | 50.8 | 46.8 | 0.0 | 2.4 | | | 1.1 | 0.0 | 104.3 |
| H-1774N | 5/19/2026 9:58:15 AM | 29.2 | 68.7 | 0.0 | 2.1 | | | 0.4 | 0.0 | 115.8 |
| H-1774N | 5/12/2026 10:34:14 AM | 29.8 | 70.2 | 0.0 | 0.0 | | | 0.4 | 0.0 | 115.8 |
| H-1801S | 5/11/2026 11:15:54 AM | 42.9 | 33.8 | 2.5 | 20.8 | | | 1.3 | 8.3 | 101.8 |
| H-1802S | 5/1/2026 2:44:17 PM | 54.5 | 41.1 | 0.0 | 4.4 | | | 1.3 | 0.0 | 104.8 |
| H-1803N | 5/26/2026 9:42:57 AM | 4.0 | 76.7 | 0.0 | 19.3 | | | 0.1 | 0.0 | 196.0 |
| H-1803N | 5/18/2026 10:00:00 AM | | | | | 1730 | | | | |
| H-1803N | 5/18/2026 9:58:45 AM | 17.7 | 72.4 | 0.0 | 9.9 | | | 0.2 | 0.0 | 196.5 |
| H-1803N | 5/12/2026 9:08:34 AM | 15.5 | 77.5 | 0.0 | 7.0 | | | 0.2 | 0.0 | 196.4 |
| H-1803N | 5/12/2026 9:05:00 AM | | | | | 242 | | | | |
| H-1803N | 5/5/2026 9:07:24 AM | 5.3 | 78.3 | 0.0 | 16.4 | | | 0.1 | 0.0 | 196.0 |
| H-1803N | 5/5/2026 9:00:00 AM | | | | | 1840 | | | | |
| H-1803N | 5/5/2026 9:00:00 AM | | | | | | 170700 | | | |
| H-1804B | 5/1/2026 10:39:08 AM | 54.1 | 44.4 | 0.0 | 1.5 | | | 1.2 | 0.0 | 108.4 |
| H-1804N | 5/8/2026 9:11:50 AM | 59.4 | 39.5 | 0.0 | 1.1 | | | 1.5 | 0.0 | 88.4 |
| H-1804S | 5/4/2026 11:47:34 AM | 56.1 | 41.6 | 0.0 | 2.3 | | | 1.3 | 0.0 | 98.1 |
| H-1805A | 5/1/2026 11:19:57 AM | 42.5 | 52.7 | 0.1 | 4.7 | | | 0.8 | 47.0 | 102.6 |
| H-1805B | 5/4/2026 11:52:01 AM | 49.7 | 42.8 | 0.0 | 7.5 | | | 1.2 | 0.0 | 70.9 |
| H-1805S | 5/4/2026 11:39:55 AM | 53.5 | 43.6 | 0.0 | 2.9 | | | 1.2 | 0.0 | 127.6 |
| H-1806A | 5/1/2026 11:08:54 AM | 47.7 | 38.6 | 0.0 | 13.7 | | | 1.2 | 0.0 | 98.8 |
| H-1806B | 5/1/2026 2:52:26 PM | 17.6 | 27.9 | 0.0 | 54.5 | | | 0.6 | 0.0 | 114.0 |
| H-1806N | 5/11/2026 11:37:48 AM | 44.4 | 51.7 | 0.0 | 3.9 | | | 0.9 | 0.0 | 129.3 |
| H-1806S | 5/4/2026 10:39:51 AM | 40.3 | 47.2 | 0.0 | 12.5 | | | 0.9 | 0.0 | 117.6 |
| H-1807A | 5/4/2026 1:18:09 PM | 54.3 | 42.8 | 0.0 | 2.9 | | | 1.3 | 0.0 | 102.7 |
| H-1807N | 5/29/2026 10:10:34 AM | 28.3 | 33.1 | 0.0 | 38.6 | | | 0.9 | 0.0 | 80.6 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [°F] |
|---|---|---|---|---|---|---|---|---|---|---|
| H-1807S | 5/7/2026 11:08:13 AM | 47.7 | 46.3 | 0.0 | 6.0 | | | 1.0 | 0.0 | 91.7 |
| H-1952S | 5/21/2026 2:14:50 PM | 54.3 | 45.7 | 0.0 | 0.0 | | | 1.2 | 0.0 | 126.2 |
| H-1952S | 5/21/2026 2:13:14 PM | 54.9 | 45.1 | 0.0 | 0.0 | | | 1.2 | 0.0 | 125.3 |
| H-1952S | 5/4/2026 2:04:02 PM | 50.4 | 48.2 | 0.0 | 1.4 | | | 1.0 | 0.0 | 121.7 |
| H-1955C | 5/1/2026 11:26:41 AM | 29.9 | 28.7 | 4.5 | 36.9 | | | 1.0 | 8.2 | 82.4 |
| H-1955N | 5/8/2026 9:07:44 AM | 52.9 | 41.9 | 0.1 | 5.1 | | | 1.3 | 51.0 | 88.3 |
| H-1956B | 5/1/2026 10:44:44 AM | 35.7 | 53.3 | 0.0 | 11.0 | | | 0.7 | 0.0 | 120.7 |
| H-1956N | 5/11/2026 11:40:47 AM | 52.5 | 43.8 | 0.0 | 3.7 | | | 1.2 | 0.0 | 107.0 |
| H-1956S | 5/1/2026 2:39:31 PM | 45.8 | 38.4 | 0.0 | 15.8 | | | 1.2 | 0.0 | 112.1 |
| H-1957B | 5/6/2026 2:10:22 PM | 50.9 | 40.5 | 0.0 | 8.6 | | | 1.3 | 0.0 | 101.1 |
| H-1957B | 5/1/2026 2:13:12 PM | 41.5 | 37.0 | 0.0 | 21.5 | | | 1.1 | 0.0 | 102.6 |
| H-1957N | 5/11/2026 11:33:03 AM | 45.0 | 42.2 | 0.0 | 12.8 | | | 1.1 | 0.0 | 121.9 |
| H-1957S | 5/11/2026 11:18:08 AM | 37.9 | 49.6 | 0.1 | 12.4 | | | 0.8 | 124.0 | 114.6 |
| H-1958C | 5/4/2026 1:20:33 PM | 51.1 | 40.6 | 0.0 | 8.3 | | | 1.3 | 0.0 | 122.5 |
| H-1958N | 5/28/2026 1:56:37 PM | 57.8 | 42.2 | 0.0 | 0.0 | | | 1.4 | 0.0 | 90.6 |
| H-1958S | 5/7/2026 11:03:31 AM | 48.9 | 39.0 | 0.0 | 12.1 | | | 1.3 | 0.0 | 122.4 |
| H-1962N | 5/19/2026 9:28:05 AM | 22.8 | 52.2 | 4.5 | 20.5 | | | 0.4 | 4.6 | 123.2 |
| H-1962N | 5/19/2026 9:26:00 AM | 23.4 | 53.4 | 4.1 | 19.1 | | | 0.4 | 4.7 | 127.1 |
| H-1962N | 5/1/2026 2:46:00 PM | 15.4 | 69.2 | 0.0 | 15.4 | | | 0.2 | 0.0 | 113.7 |
| H-1963N | 5/19/2026 8:46:36 AM | 23.4 | 68.5 | 0.0 | 8.1 | | | 0.3 | 0.0 | 140.0 |
| H-1963N | 5/19/2026 8:44:46 AM | 24.1 | 67.7 | 0.0 | 8.2 | | | 0.4 | 0.0 | 140.2 |
| H-1963N | 5/1/2026 12:06:22 PM | 24.0 | 72.5 | 0.0 | 3.5 | | | 0.3 | 0.0 | 141.4 |
| H-1963N | 5/1/2026 12:04:32 PM | 22.1 | 72.6 | 0.0 | 5.3 | | | 0.3 | 0.0 | 135.1 |
| H-1966N | 5/19/2026 10:06:37 AM | 46.8 | 50.3 | 0.0 | 2.9 | | | 0.9 | 0.0 | 105.5 |
| H-1966N | 5/12/2026 10:42:28 AM | 46.9 | 48.2 | 0.0 | 4.9 | | | 1.0 | 0.0 | 105.7 |
| H-1967E | 5/7/2026 1:04:55 PM | 52.6 | 40.6 | 0.0 | 6.8 | | | 1.3 | 0.0 | 105.5 |
| H-1967W | 5/7/2026 9:49:11 AM | 56.1 | 39.9 | 0.0 | 4.0 | | | 1.4 | 0.0 | 94.4 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [°F] |
|---|---|---|---|---|---|---|---|---|---|---|
| H-1967W | 5/7/2026 9:47:56 AM | 56.2 | 39.7 | 0.0 | 4.1 | | | 1.4 | 0.0 | 93.7 |
| H-2050E | 5/14/2026 9:38:59 AM | 55.2 | 41.0 | 0.3 | 3.5 | | | 1.3 | 11.7 | 85.0 |
| H-2050W | 5/5/2026 3:39:36 PM | 47.7 | 41.7 | 0.0 | 10.6 | | | 1.1 | 0.0 | 100.7 |
| H-2051W | 5/7/2026 9:44:33 AM | 56.7 | 40.5 | 0.0 | 2.8 | | | 1.4 | 0.0 | 85.2 |
| H-2053E | 5/7/2026 1:13:15 PM | 47.8 | 39.9 | 0.0 | 12.3 | | | 1.2 | 0.0 | 119.2 |
| H-2053W | 5/13/2026 8:39:25 AM | 60.0 | 38.5 | 0.0 | 1.5 | | | 1.6 | 0.0 | 91.3 |
| H-2055E | 5/22/2026 10:10:19 AM | 30.3 | 33.3 | 0.0 | 36.4 | | | 0.9 | 0.0 | 107.8 |
| H-2055E | 5/6/2026 3:07:33 PM | 30.8 | 33.7 | 0.0 | 35.5 | | | 0.9 | 0.0 | 107.4 |
| H-2056B | 5/8/2026 3:07:26 PM | 28.8 | 29.8 | 0.0 | 41.4 | | | 1.0 | 0.0 | 90.4 |
| H-2056W | 5/7/2026 9:41:29 AM | 56.9 | 39.8 | 0.0 | 3.3 | | | 1.4 | 0.0 | 95.6 |
| H-2057E | 5/7/2026 1:10:46 PM | 50.6 | 37.7 | 0.0 | 11.7 | | | 1.3 | 0.0 | 125.6 |
| H-2057W | 5/28/2026 8:44:04 AM | 55.9 | 37.4 | 1.0 | 5.7 | | | 1.5 | 5.7 | 80.9 |
| H-2057W | 5/13/2026 8:09:16 AM | 46.0 | 31.6 | 3.6 | 18.8 | | | 1.5 | 5.2 | 80.3 |
| H-2057W | 5/13/2026 8:05:12 AM | 43.6 | 28.5 | 4.1 | 23.8 | | | 1.5 | 5.8 | 82.1 |
| H-2058E | 5/7/2026 1:22:33 PM | 50.9 | 40.0 | 0.0 | 9.1 | | | 1.3 | 0.0 | 110.1 |
| H-2058W | 5/7/2026 9:34:28 AM | 55.9 | 39.8 | 0.0 | 4.3 | | | 1.4 | 0.0 | 94.7 |
| H-2058W | 5/7/2026 9:33:03 AM | 57.3 | 38.9 | 0.1 | 3.7 | | | 1.5 | 37.0 | 93.7 |
| H-2059E | 5/6/2026 12:36:07 PM | 54.5 | 42.2 | 0.0 | 3.3 | | | 1.3 | 0.0 | 116.6 |
| H-2059W | 5/7/2026 10:12:44 AM | 50.6 | 46.1 | 0.0 | 3.3 | | | 1.1 | 0.0 | 126.5 |
| H-2161E | 5/6/2026 12:32:34 PM | 51.0 | 42.1 | 0.0 | 6.9 | | | 1.2 | 0.0 | 123.6 |
| H-2161W | 5/7/2026 10:08:23 AM | 57.4 | 39.7 | 0.0 | 2.9 | | | 1.4 | 0.0 | 106.7 |
| H-2163C | 5/22/2026 10:05:49 AM | 50.3 | 44.1 | 0.0 | 5.6 | | | 1.1 | 0.0 | 90.0 |
| H-2163C | 5/4/2026 10:05:22 AM | 51.8 | 44.1 | 0.0 | 4.1 | | | 1.2 | 0.0 | 83.7 |
| H-2163W | 5/7/2026 10:22:23 AM | 39.4 | 58.7 | 0.0 | 1.9 | | | 0.7 | 0.0 | 125.5 |
| H-2164E | 5/22/2026 10:41:07 AM | 34.9 | 62.7 | 0.0 | 2.4 | | | 0.6 | 0.0 | 125.3 |
| H-2164E | 5/6/2026 3:22:38 PM | 31.3 | 68.7 | 0.0 | 0.0 | | | 0.5 | 0.0 | 127.2 |
| H-2164E | 5/6/2026 3:21:24 PM | 32.1 | 67.9 | 0.0 | 0.0 | | | 0.5 | 0.0 | 124.4 |
| H-2165E | 5/4/2026 10:55:10 AM | 48.3 | 46.7 | 0.0 | 5.0 | | | 1.0 | 0.0 | 109.8 |
| H-2165W | 5/20/2026 9:46:57 AM | 12.9 | 79.8 | 0.0 | 7.3 | | | 0.2 | 0.0 | 119.8 |
| H-2165W | 5/12/2026 7:45:00 AM | | | | | 720 | | | | |
| H-2165W | 5/12/2026 7:45:00 AM | | | | | | 48000 | | | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| H-2165W | 5/1/2026 10:16:24 AM | 10.9 | 86.4 | 0.0 | 2.7 | | | 0.1 | 0.0 | 118.0 |
| H-2166E | 5/4/2026 1:12:58 PM | 54.2 | 40.8 | 0.2 | 4.8 | | | 1.3 | 24.0 | 101.5 |
| H-2168C | 5/1/2026 10:48:38 AM | 56.3 | 41.3 | 0.0 | 2.4 | | | 1.4 | 0.0 | 84.9 |
| H-2168E | 5/28/2026 12:08:16 PM | 37.9 | 37.6 | 0.0 | 24.5 | | | 1.0 | 0.0 | 118.3 |
| H-2168E | 5/6/2026 2:36:05 PM | 45.5 | 40.3 | 0.0 | 14.2 | | | 1.1 | 0.0 | 120.1 |
| H-2168E | 5/5/2026 10:39:26 AM | 39.5 | 34.5 | 0.2 | 25.8 | | | 1.1 | 129.0 | 71.4 |
| H-2168E | 5/5/2026 10:37:49 AM | 22.7 | 21.3 | 9.6 | 46.4 | | | 1.1 | 4.8 | 70.1 |
| H-2168E | 5/1/2026 2:15:28 PM | 42.4 | 38.7 | 0.0 | 18.9 | | | 1.1 | 0.0 | 120.0 |
| H-2169C | 5/4/2026 11:55:39 AM | 53.1 | 41.0 | 0.0 | 5.9 | | | 1.3 | 0.0 | 104.4 |
| H-2169E | 5/1/2026 2:05:32 PM | 44.3 | 39.2 | 0.0 | 16.5 | | | 1.1 | 0.0 | 114.8 |
| H-2170N | 5/4/2026 2:04:41 PM | 51.0 | 40.4 | 0.0 | 8.6 | | | 1.3 | 0.0 | 117.3 |
| H-2170S | 5/11/2026 8:29:12 AM | 50.7 | 40.2 | 0.0 | 9.1 | | | 1.3 | 0.0 | 101.9 |
| H-2171A | 5/14/2026 8:58:08 AM | 43.5 | 37.1 | 0.0 | 19.4 | | | 1.2 | 0.0 | 94.8 |
| H-2171A | 5/14/2026 8:54:11 AM | 43.8 | 36.9 | 0.0 | 19.3 | | | 1.2 | 0.0 | 95.9 |
| H-2171A | 5/13/2026 10:13:53 AM | 43.2 | 38.0 | 0.0 | 18.7 | | | 1.1 | 0.0 | 94.7 |
| H-2171A | 5/13/2026 10:08:18 AM | 43.1 | 37.0 | 0.0 | 19.9 | | | 1.2 | 0.0 | 97.6 |
| H-2171A | 5/7/2026 9:32:22 AM | 50.6 | 38.4 | 0.0 | 11.0 | | | 1.3 | 0.0 | 91.9 |
| H-2171B | 5/13/2026 2:00:46 PM | 51.0 | 40.8 | 0.0 | 8.2 | | | 1.2 | 0.0 | 119.6 |
| H-2171N | 5/7/2026 9:22:04 AM | 43.3 | 37.9 | 0.0 | 18.8 | | | 1.1 | 0.0 | 108.4 |
| H-2171S | 5/4/2026 2:02:33 PM | 48.7 | 41.7 | 0.0 | 9.6 | | | 1.2 | 0.0 | 119.2 |
| H-2272W | 5/19/2026 10:27:12 AM | 38.3 | 43.8 | 0.0 | 17.9 | | | 0.9 | 0.0 | 124.4 |
| H-2272W | 5/4/2026 9:50:05 AM | 33.4 | 40.5 | 0.0 | 26.2 | | | 0.8 | 0.0 | 122.9 |
| H-2272W | 5/4/2026 9:47:59 AM | 34.8 | 39.9 | 0.0 | 25.3 | | | 0.9 | 0.0 | 122.0 |
| H-2273W | 5/20/2026 8:21:56 AM | 25.2 | 50.1 | 0.0 | 24.7 | | | 0.5 | 0.0 | 129.9 |
| H-2273W | 5/13/2026 12:42:00 PM | 17.2 | 42.0 | 0.1 | 40.7 | | | 0.4 | 407.0 | 125.4 |
| H-2273W | 5/12/2026 7:50:00 AM | | | | | 76 | | | | |
| H-2273W | 5/12/2026 7:50:00 AM | | | | | | 5900 | | | |
| H-2274B | 5/20/2026 2:09:49 PM | 50.6 | 46.7 | 0.1 | 2.6 | | | 1.1 | 26.0 | 96.3 |
| H-2274B | 5/4/2026 1:23:52 PM | 49.7 | 45.6 | 0.0 | 4.7 | | | 1.1 | 0.0 | 82.5 |
| H-2274W | 5/19/2026 1:17:54 PM | 27.7 | 68.7 | 0.0 | 3.6 | | | 0.4 | 0.0 | 125.2 |
| H-2274W | 5/1/2026 10:22:35 AM | 24.0 | 60.6 | 0.3 | 15.1 | | | 0.4 | 50.3 | 129.9 |
| H-2275E | 5/4/2026 11:24:01 AM | 38.1 | 59.7 | 0.0 | 2.2 | | | 0.6 | 0.0 | 121.7 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| H-2275W | 5/20/2026 7:50:11 AM | 15.6 | 33.8 | 1.9 | 48.7 | | | 0.5 | 25.6 | 126.0 |
| H-2275W | 5/8/2026 11:15:19 AM | 33.9 | 63.2 | 0.0 | 2.9 | | | 0.5 | 0.0 | 112.5 |
| H-2275W | 5/8/2026 11:13:59 AM | 34.3 | 64.3 | 0.0 | 1.4 | | | 0.5 | 0.0 | 82.9 |
| H-2276A | 5/20/2026 1:13:04 PM | 38.5 | 36.8 | 0.1 | 24.6 | | | 1.0 | 223.6 | 108.2 |
| H-2276A | 5/11/2026 1:32:34 PM | 41.1 | 37.1 | 0.0 | 21.8 | | | 1.1 | 0.0 | 106.7 |
| H-2276B | 5/20/2026 2:22:12 PM | 51.4 | 43.3 | 0.0 | 5.3 | | | 1.2 | 0.0 | 117.5 |
| H-2276B | 5/4/2026 2:06:44 PM | 53.5 | 41.4 | 0.0 | 5.1 | | | 1.3 | 0.0 | 114.0 |
| H-2276E | 5/4/2026 11:37:57 AM | 46.8 | 41.4 | 0.0 | 11.8 | | | 1.1 | 0.0 | 116.2 |
| H-2276W | 5/20/2026 8:32:50 AM | 37.9 | 54.7 | 0.0 | 7.4 | | | 0.7 | 0.0 | 92.8 |
| H-2276W | 5/1/2026 10:16:43 AM | 24.8 | 62.0 | 0.0 | 13.2 | | | 0.4 | 0.0 | 101.3 |
| H-2277A | 5/21/2026 9:41:03 AM | 46.0 | 54.0 | 0.0 | 0.0 | | | 0.9 | 0.0 | 92.3 |
| H-2277A | 5/1/2026 11:04:15 AM | 42.2 | 44.2 | 2.7 | 10.9 | | | 1.0 | 4.0 | 79.1 |
| H-2277B | 5/21/2026 9:35:16 AM | 55.1 | 43.4 | 0.0 | 1.5 | | | 1.3 | 0.0 | 117.5 |
| H-2277B | 5/4/2026 2:19:04 PM | 48.2 | 40.6 | 0.0 | 11.2 | | | 1.2 | 0.0 | 115.3 |
| H-23 (EXP-23) | 5/13/2026 1:17:40 PM | 8.0 | 4.3 | 17.8 | 69.9 | | | 1.9 | 3.9 | 93.9 |
| H-23 (EXP-23) | 5/13/2026 1:13:21 PM | 8.1 | 4.1 | 17.7 | 70.1 | | | 1.9 | 4.0 | 91.9 |
| H-23 (EXP-23) | 5/13/2026 10:53:27 AM | 7.4 | 4.7 | 18.0 | 69.8 | | | 1.6 | 3.9 | 85.0 |
| H-23 (EXP-23) | 5/13/2026 10:40:54 AM | 5.5 | 4.6 | 18.9 | 71.0 | | | 1.2 | 3.8 | 76.3 |
| H-2301E | 5/13/2026 9:05:55 AM | 48.3 | 39.3 | 0.0 | 12.4 | | | 1.2 | 0.0 | 105.3 |
| H-2301W | 5/15/2026 10:14:58 AM | 23.6 | 19.3 | 11.2 | 45.9 | | | 1.2 | 4.1 | 73.0 |
| H-2301W | 5/15/2026 10:13:21 AM | 22.3 | 16.5 | 11.2 | 50.0 | | | 1.4 | 4.5 | 72.6 |
| H-2302C | 5/7/2026 2:47:12 PM | 53.8 | 40.8 | 0.0 | 5.4 | | | 1.3 | 0.0 | 116.8 |
| H-2302E | 5/8/2026 12:55:32 PM | 55.9 | 40.9 | 0.1 | 3.1 | | | 1.4 | 31.0 | 105.2 |
| H-2303E | 5/8/2026 1:01:15 PM | 55.3 | 41.8 | 0.0 | 2.9 | | | 1.3 | 0.0 | 88.8 |
| H-2303N | 5/7/2026 2:55:44 PM | 54.3 | 41.9 | 0.0 | 3.8 | | | 1.3 | 0.0 | 102.4 |
| H-2304E | 5/8/2026 1:05:45 PM | 56.4 | 41.7 | 0.0 | 1.9 | | | 1.4 | 0.0 | 95.6 |
| H-2304S | 5/8/2026 1:30:30 PM | 54.0 | 43.5 | 0.0 | 2.5 | | | 1.2 | 0.0 | 123.3 |
| H-2305N | 5/7/2026 3:01:47 PM | 54.7 | 41.3 | 0.0 | 4.0 | | | 1.3 | 0.0 | 97.5 |
| H-2305S | 5/8/2026 1:14:11 PM | 54.8 | 43.0 | 0.0 | 2.2 | | | 1.3 | 0.0 | 125.8 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| H-2306N | 5/15/2026 10:33:03 AM | 50.7 | 40.5 | 0.0 | 8.8 | | | 1.3 | 0.0 | 116.5 |
| H-2307S | 5/22/2026 11:53:04 AM | 53.3 | 39.2 | 0.3 | 7.2 | | | 1.4 | 24.0 | 114.7 |
| H-2307S | 5/7/2026 2:41:47 PM | 52.4 | 43.3 | 0.0 | 4.3 | | | 1.2 | 0.0 | 119.9 |
| H-2307S | 5/7/2026 2:40:20 PM | 53.9 | 42.6 | 0.0 | 3.5 | | | 1.3 | 0.0 | 114.6 |
| H-2308S | 5/7/2026 2:29:52 PM | 50.8 | 42.0 | 0.0 | 7.2 | | | 1.2 | 0.0 | 118.8 |
| H-2309N | 5/4/2026 10:13:40 AM | 51.4 | 43.8 | 0.0 | 4.8 | | | 1.2 | 0.0 | 83.6 |
| H-2309S | 5/8/2026 1:53:32 PM | 55.0 | 42.5 | 0.0 | 2.5 | | | 1.3 | 0.0 | 108.9 |
| H-2310N | 5/8/2026 3:03:25 PM | 54.5 | 40.5 | 0.0 | 5.0 | | | 1.3 | 0.0 | 109.7 |
| H-2310S | 5/22/2026 12:06:57 PM | 52.1 | 39.4 | 0.0 | 8.5 | | | 1.3 | 0.0 | 102.7 |
| H-2310S | 5/14/2026 9:47:40 AM | 40.7 | 37.1 | 0.2 | 22.0 | | | 1.1 | 110.0 | 101.3 |
| H-2401S | 5/7/2026 11:32:52 AM | 54.8 | 42.7 | 0.0 | 2.5 | | | 1.3 | 0.0 | 108.7 |
| H-2402N | 5/8/2026 9:47:00 AM | 47.4 | 43.4 | 0.0 | 9.2 | | | 1.1 | 0.0 | 105.9 |
| H-2402S | 5/8/2026 9:58:19 AM | 52.1 | 40.8 | 0.0 | 7.1 | | | 1.3 | 0.0 | 109.5 |
| H-2403N | 5/8/2026 9:51:09 AM | 53.4 | 42.6 | 0.0 | 4.0 | | | 1.3 | 0.0 | 110.9 |
| H-2403S | 5/8/2026 9:35:34 AM | 39.5 | 33.9 | 3.3 | 23.3 | | | 1.2 | 7.1 | 80.3 |
| H-2404N | 5/5/2026 3:35:40 PM | 53.3 | 42.6 | 0.0 | 4.1 | | | 1.3 | 0.0 | 107.6 |
| H-2404S | 5/8/2026 8:59:38 AM | 56.7 | 41.0 | 0.1 | 2.2 | | | 1.4 | 22.0 | 111.3 |
| H-2405N | 5/5/2026 2:23:59 PM | 22.7 | 31.6 | 0.0 | 45.7 | | | 0.7 | 0.0 | 111.7 |
| H-29 | 5/29/2026 12:05:20 PM | 17.4 | 45.3 | 0.0 | 37.3 | | | 0.4 | 0.0 | 92.4 |
| H-29 | 5/29/2026 12:00:31 PM | 17.5 | 44.9 | 0.0 | 37.6 | | | 0.4 | 0.0 | 78.6 |
| H-29 | 5/4/2026 1:58:42 PM | 19.9 | 47.7 | 0.0 | 32.4 | | | 0.4 | 0.0 | 71.3 |
| H-29 | 5/4/2026 1:55:50 PM | 20.0 | 45.7 | 0.0 | 34.3 | | | 0.4 | 0.0 | 76.8 |
| H-72 | 5/29/2026 9:51:57 AM | 52.9 | 41.3 | 0.4 | 5.4 | | | 1.3 | 13.5 | 80.9 |
| H-74 | 5/11/2026 11:20:34 AM | 52.5 | 41.8 | 0.0 | 5.7 | | | 1.3 | 0.0 | 101.6 |
| H-75 | 5/14/2026 11:59:28 AM | 46.1 | 46.1 | 0.0 | 7.8 | | | 1.0 | 0.0 | 90.5 |
| H-79 | 5/15/2026 11:24:44 AM | 45.6 | 48.2 | 0.1 | 6.1 | | | 0.9 | 61.0 | 128.7 |
| P-02R | 5/13/2026 8:15:30 AM | 28.4 | 31.1 | 0.0 | 40.5 | | | 0.9 | 0.0 | 82.2 |
| P-03R | 5/13/2026 8:26:58 AM | 37.8 | 33.0 | 0.0 | 29.1 | | | 1.1 | 0.0 | 87.6 |
| P-04 | 5/5/2026 7:38:51 AM | 52.6 | 39.3 | 0.0 | 8.1 | | | 1.3 | 0.0 | 91.5 |
| P-05 | 5/5/2026 7:46:02 AM | 35.6 | 35.8 | 0.0 | 28.6 | | | 1.0 | 0.0 | 102.6 |
| P-06R | 5/5/2026 7:49:46 AM | 41.8 | 36.3 | 0.0 | 21.9 | | | 1.2 | 0.0 | 105.9 |
| P-07R | 5/12/2026 8:59:48 AM | 32.9 | 30.2 | 0.0 | 36.9 | | | 1.1 | 0.0 | 83.4 |
| P-08R | 5/11/2026 10:46:01 AM | 53.4 | 37.2 | 0.0 | 9.4 | | | 1.4 | 0.0 | 101.8 |
| P-09 | 5/5/2026 8:01:21 AM | 46.5 | 38.0 | 0.0 | 15.5 | | | 1.2 | 0.0 | 94.6 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| P-10 | 5/5/2026 7:56:04 AM | 42.5 | 36.6 | 0.0 | 20.9 | | | 1.2 | 0.0 | 85.8 |
| P-11 | 5/12/2026 9:25:09 AM | 48.6 | 37.1 | 0.0 | 14.4 | | | 1.3 | 0.0 | 104.3 |
| P-12 | 5/15/2026 7:59:36 AM | 57.4 | 40.4 | 0.0 | 2.2 | | | 1.4 | 0.0 | 74.1 |
| P-13 | 5/15/2026 8:05:44 AM | 47.7 | 34.6 | 0.0 | 17.7 | | | 1.4 | 0.0 | 78.0 |
| P-14 | 5/5/2026 8:13:25 AM | 24.8 | 28.2 | 0.7 | 46.3 | | | 0.9 | 66.1 | 73.0 |
| P-15R | 5/5/2026 8:17:20 AM | 48.7 | 36.8 | 0.0 | 14.5 | | | 1.3 | 0.0 | 70.6 |
| P-16 | 5/5/2026 8:25:52 AM | 51.0 | 36.4 | 0.0 | 12.6 | | | 1.4 | 0.0 | 79.0 |
| P-17 | 5/5/2026 8:30:43 AM | 35.8 | 34.5 | 0.0 | 29.7 | | | 1.0 | 0.0 | 109.1 |
| P-18RD | 5/5/2026 8:41:50 AM | 51.2 | 38.3 | 0.0 | 10.5 | | | 1.3 | 0.0 | 81.1 |
| P-18RS | 5/5/2026 8:36:36 AM | 38.7 | 35.6 | 0.0 | 25.7 | | | 1.1 | 0.0 | 91.1 |
| P-19 | 5/4/2026 11:16:30 AM | 33.6 | 28.9 | 0.0 | 37.5 | | | 1.2 | 0.0 | 84.0 |
| P-20R | 5/5/2026 8:45:27 AM | 48.6 | 37.5 | 0.0 | 13.9 | | | 1.3 | 0.0 | 96.3 |
| P-21 | 5/5/2026 8:49:59 AM | 34.2 | 33.5 | 0.0 | 32.3 | | | 1.0 | 0.0 | 89.6 |
| P-21RD | 5/4/2026 10:03:26 AM | 39.4 | 33.8 | 0.1 | 26.7 | | | 1.2 | 267.0 | 99.0 |
| P-21RS | 5/4/2026 10:00:38 AM | 47.7 | 30.3 | 0.3 | 21.7 | | | 1.6 | 72.3 | 107.1 |
| P-22RD | 5/4/2026 10:32:00 AM | 54.0 | 43.0 | 0.0 | 3.0 | | | 1.3 | 0.0 | 114.4 |
| P-22RS | 5/4/2026 10:28:52 AM | 29.5 | 29.6 | 0.0 | 40.9 | | | 1.0 | 0.0 | 119.2 |
| P-23 | 5/5/2026 8:59:25 AM | 3.1 | 22.0 | 0.8 | 74.1 | | | 0.1 | 92.6 | 82.3 |
| P-24 | 5/6/2026 8:17:07 AM | 19.2 | 25.1 | 0.0 | 55.7 | | | 0.8 | 0.0 | 88.3 |
| P-26 | 5/6/2026 8:34:09 AM | 43.9 | 34.3 | 0.0 | 21.8 | | | 1.3 | 0.0 | 80.7 |
| P-27 | 5/6/2026 8:43:29 AM | 4.9 | 18.8 | 1.2 | 75.1 | | | 0.3 | 62.6 | 73.0 |
| P-28 | 5/6/2026 8:51:00 AM | 31.8 | 31.0 | 0.0 | 37.2 | | | 1.0 | 0.0 | 95.1 |
| P-29R | 5/6/2026 8:57:44 AM | 19.9 | 26.6 | 0.4 | 53.1 | | | 0.7 | 132.8 | 90.8 |
| P-30R | 5/6/2026 9:04:44 AM | 16.4 | 24.2 | 0.0 | 59.4 | | | 0.7 | 0.0 | 83.5 |
| P-32R1 | 5/6/2026 9:10:45 AM | 22.0 | 28.8 | 0.4 | 48.8 | | | 0.8 | 122.0 | 109.6 |
| P-32R2 | 5/6/2026 9:14:09 AM | 23.8 | 28.8 | 0.3 | 47.1 | | | 0.8 | 157.0 | 110.8 |
| P-33 | 5/6/2026 9:19:40 AM | 30.5 | 30.1 | 2.0 | 37.4 | | | 1.0 | 18.7 | 93.1 |
| P-36 | 5/6/2026 9:31:05 AM | 21.1 | 23.8 | 0.4 | 54.7 | | | 0.9 | 136.8 | 69.7 |
| P-37 | 5/6/2026 9:35:20 AM | 9.1 | 22.3 | 0.8 | 67.8 | | | 0.4 | 84.8 | 82.6 |
| P-38RD | 5/6/2026 9:48:07 AM | 38.9 | 33.9 | 0.0 | 27.2 | | | 1.1 | 0.0 | 106.4 |
| P-38RS | 5/6/2026 9:44:32 AM | 31.4 | 28.9 | 0.0 | 39.7 | | | 1.1 | 0.0 | 104.3 |
| P-39 | 5/6/2026 9:55:17 AM | 43.5 | 36.9 | 0.8 | 18.8 | | | 1.2 | 23.5 | 78.9 |
| P-41 | 5/6/2026 10:07:48 AM | 14.8 | 16.3 | 8.2 | 60.7 | | | 0.9 | 7.4 | 108.3 |
| P-41 | 5/6/2026 10:06:10 AM | 14.7 | 16.3 | 8.2 | 60.8 | | | 0.9 | 7.4 | 108.6 |
| P-42R | 5/6/2026 10:15:47 AM | 51.6 | 36.1 | 0.2 | 12.1 | | | 1.4 | 60.5 | 111.5 |
| P-43 | 5/6/2026 10:22:56 AM | 20.6 | 24.0 | 0.8 | 54.6 | | | 0.9 | 68.3 | 116.8 |
| P-44RD | 5/6/2026 10:37:00 AM | 47.3 | 33.6 | 0.0 | 19.1 | | | 1.4 | 0.0 | 90.1 |
| P-44RS | 5/6/2026 10:33:49 AM | 18.5 | 22.4 | 0.1 | 59.0 | | | 0.8 | 590.0 | 121.7 |
| P-45RD | 5/6/2026 10:50:26 AM | 40.0 | 34.6 | 0.0 | 25.4 | | | 1.2 | 0.0 | 114.9 |
| P-45RS | 5/6/2026 10:47:34 AM | 2.9 | 17.7 | 0.1 | 79.3 | | | 0.2 | 793.0 | 90.4 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| P-46RD | 5/6/2026 11:02:37 AM | 48.2 | 34.9 | 0.0 | 16.9 | | | 1.4 | 0.0 | 99.1 |
| P-46RS | 5/6/2026 10:55:16 AM | 15.2 | 21.5 | 0.0 | 63.3 | | | 0.7 | 0.0 | 120.7 |
| P-47 | 5/4/2026 10:21:39 AM | 10.6 | 21.7 | 1.2 | 66.5 | | | 0.5 | 55.4 | 96.4 |
| P-48 | 5/4/2026 10:38:03 AM | 17.3 | 24.8 | 0.0 | 57.9 | | | 0.7 | 0.0 | 113.0 |
| P-49RD | 5/4/2026 10:58:34 AM | 52.0 | 38.1 | 0.4 | 9.5 | | | 1.4 | 23.8 | 112.6 |
| P-49RS | 5/4/2026 10:55:41 AM | 33.7 | 28.3 | 0.2 | 37.8 | | | 1.2 | 189.0 | 113.8 |
| P-52 | 5/28/2026 2:38:45 PM | 33.1 | 33.7 | 0.0 | 33.2 | | | 1.0 | 0.0 | 117.0 |
| P-53 | 5/15/2026 8:37:53 AM | 20.7 | 25.3 | 0.0 | 54.0 | | | 0.8 | 0.0 | 114.6 |
| P-54 | 5/15/2026 8:35:38 AM | 29.8 | 31.3 | 0.0 | 38.9 | | | 1.0 | 0.0 | 100.9 |
| P-55 | 5/15/2026 8:24:48 AM | 29.5 | 29.5 | 0.0 | 41.0 | | | 1.0 | 0.0 | 93.9 |
| P-56 | 5/26/2026 9:15:49 AM | 19.8 | 28.9 | 0.0 | 51.3 | | | 0.7 | 0.0 | 101.7 |
| P-57 | 5/13/2026 9:14:04 AM | 17.1 | 22.5 | 4.0 | 56.4 | | | 0.8 | 14.2 | 76.5 |
| P-60R | 5/7/2026 8:52:45 AM | 13.9 | 9.1 | 15.5 | 61.5 | | | 1.5 | 4.0 | 76.0 |
| P-60R | 5/7/2026 8:48:07 AM | 3.4 | 3.5 | 19.3 | 73.8 | | | 1.0 | 3.8 | 75.1 |
| P-61 | 5/7/2026 8:30:07 AM | 41.3 | 35.7 | 0.0 | 23.0 | | | 1.2 | 0.0 | 83.4 |
| P-65 | 5/7/2026 8:25:21 AM | 29.5 | 27.2 | 0.0 | 43.3 | | | 1.1 | 0.0 | 71.4 |
| P-71 | 5/4/2026 10:47:48 AM | 30.4 | 27.4 | 0.2 | 42.0 | | | 1.1 | 210.0 | 72.3 |
| P-75 | 5/6/2026 11:19:49 AM | 51.7 | 33.5 | 0.0 | 14.8 | | | 1.5 | 0.0 | 92.0 |
| P-76 | 5/6/2026 9:41:27 AM | 17.4 | 22.8 | 0.1 | 59.7 | | | 0.8 | 597.0 | 91.4 |
| P-79 | 5/4/2026 11:21:51 AM | 17.5 | 22.2 | 1.6 | 58.7 | | | 0.8 | 36.7 | 86.4 |
| SC-2000E | 5/6/2026 12:28:45 PM | 44.1 | 37.1 | 0.0 | 18.8 | | | 1.2 | 0.0 | 118.8 |
| SC-2501E | 5/26/2026 9:21:31 AM | 3.2 | 78.4 | 0.0 | 18.4 | | | 0.0 | 0.0 | 189.1 |
| SC-2501E | 5/18/2026 9:40:35 AM | 15.6 | 75.2 | 0.0 | 9.2 | | | 0.2 | 0.0 | 189.0 |
| SC-2501E | 5/18/2026 9:40:00 AM | | | | | 211 | | | | |
| SC-2501E | 5/18/2026 9:38:11 AM | 15.0 | 73.0 | 0.0 | 12.0 | | | 0.2 | 0.0 | 189.0 |
| SC-2501E | 5/18/2026 9:29:29 AM | 15.4 | 75.0 | 0.0 | 9.6 | | | 0.2 | 0.0 | 190.7 |
| SC-2501E | 5/12/2026 9:13:45 AM | 21.2 | 78.8 | 0.0 | 0.0 | | | 0.3 | 0.0 | 188.9 |
| SC-2501E | 5/12/2026 9:10:00 AM | | | | | 743 | | | | |
| SC-2501E | 5/5/2026 8:56:40 AM | 5.0 | 80.7 | 0.0 | 14.3 | | | 0.1 | 0.0 | 188.8 |
| SC-2501E | 5/5/2026 8:51:59 AM | 4.7 | 82.8 | 0.0 | 12.5 | | | 0.1 | 0.0 | 188.5 |
| SC-2501E | 5/5/2026 8:50:00 AM | | | | | 1400 | | | | |
| SC-2501E | 5/5/2026 8:50:00 AM | | | | | | 177700 | | | |
| SC-2501W | 5/5/2026 9:19:42 AM | 6.2 | 76.9 | 0.0 | 16.9 | | | 0.1 | 0.0 | 91.3 |
| SW-10 | 5/28/2026 9:37:50 AM | 35.2 | 33.3 | 1.5 | 30.0 | | | 1.1 | 20.0 | 71.5 |
| SW-115 | 5/11/2026 8:59:04 AM | 48.4 | 39.9 | 0.0 | 11.7 | | | 1.2 | 0.0 | 87.1 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [°F] |
|---|---|---|---|---|---|---|---|---|---|---|
| SW-1445 | 5/22/2026 7:39:28 AM | 26.5 | 29.3 | 0.0 | 44.2 | | | 0.9 | 0.0 | 61.8 |
| SW-1445 | 5/4/2026 7:53:57 AM | 0.9 | 12.6 | 17.2 | 69.3 | | | 0.1 | 4.0 | 80.8 |
| SW-1455 | 5/22/2026 7:44:18 AM | 19.4 | 26.2 | 0.0 | 54.4 | | | 0.7 | 0.0 | 66.3 |
| SW-1455 | 5/4/2026 7:57:56 AM | 8.6 | 11.3 | 15.1 | 65.0 | | | 0.8 | 4.3 | 83.4 |
| SW-154 | 5/15/2026 9:34:29 AM | 0.0 | 1.1 | 20.0 | 78.9 | | | 0.0 | 3.9 | 66.7 |
| SW-154 | 5/15/2026 9:31:56 AM | 0.1 | 1.7 | 19.7 | 78.5 | | | 0.1 | 4.0 | 67.1 |
| SW-17-135 | 5/22/2026 7:41:29 AM | 30.1 | 29.3 | 0.0 | 40.6 | | | 1.0 | 0.0 | 65.4 |
| SW-17-135 | 5/4/2026 7:56:03 AM | 19.5 | 19.6 | 5.3 | 55.6 | | | 1.0 | 10.5 | 72.2 |
| SW-187 | 5/4/2026 9:31:29 AM | 15.9 | 27.5 | 5.5 | 51.1 | | | 0.6 | 9.3 | 81.2 |
| SW-1930 | 5/1/2026 7:51:05 AM | 33.2 | 51.7 | 2.7 | 12.4 | | | 0.6 | 4.6 | 81.3 |
| SW-20 | 5/12/2026 9:06:57 AM | 0.0 | 5.4 | 14.0 | 80.6 | | | 0.0 | 5.8 | 80.3 |
| SW-25 | 5/1/2026 7:53:15 AM | 0.6 | 0.6 | 21.5 | 77.3 | | | 1.0 | 3.6 | 65.8 |
| SW-2501D | 5/29/2026 7:21:12 AM | 21.1 | 76.6 | 0.0 | 2.3 | | | 0.3 | 0.0 | 71.9 |
| SW-2501D | 5/28/2026 6:16:27 AM | 22.8 | 76.5 | 0.0 | 0.7 | | | 0.3 | 0.0 | 71.6 |
| SW-2501D | 5/27/2026 6:04:20 AM | 23.7 | 76.3 | 0.0 | 0.0 | | | 0.3 | 0.0 | 68.6 |
| SW-2501D | 5/26/2026 6:11:29 AM | 23.0 | 76.3 | 0.0 | 0.7 | | | 0.3 | 0.0 | 72.6 |
| SW-2501D | 5/22/2026 6:19:43 AM | 21.1 | 77.0 | 0.0 | 1.9 | | | 0.3 | 0.0 | 70.5 |
| SW-2501D | 5/21/2026 6:35:47 AM | 21.4 | 78.0 | 0.0 | 0.6 | | | 0.3 | 0.0 | 76.9 |
| SW-2501D | 5/20/2026 8:30:45 AM | 22.8 | 77.2 | 0.0 | 0.0 | | | 0.3 | 0.0 | 78.9 |
| SW-2501D | 5/19/2026 9:01:29 AM | 20.3 | 79.4 | 0.0 | 0.3 | | | 0.3 | 0.0 | 80.0 |
| SW-2501D | 5/18/2026 8:44:45 AM | 20.8 | 74.8 | 0.0 | 4.4 | | | 0.3 | 0.0 | 76.1 |
| SW-2501D | 5/15/2026 9:25:43 AM | 14.5 | 33.0 | 11.9 | 40.6 | | | 0.4 | 3.4 | 77.8 |
| SW-2501D | 5/14/2026 8:19:05 AM | 20.5 | 78.2 | 0.0 | 1.3 | | | 0.3 | 0.0 | 75.4 |
| SW-2501D | 5/13/2026 8:08:49 AM | 21.3 | 78.4 | 0.0 | 0.3 | | | 0.3 | 0.0 | 75.4 |
| SW-2501D | 5/12/2026 9:15:23 AM | 20.9 | 78.5 | 0.0 | 0.6 | | | 0.3 | 0.0 | 79.4 |
| SW-2501D | 5/11/2026 8:24:00 AM | 21.0 | 77.7 | 0.0 | 1.3 | | | 0.3 | 0.0 | 77.2 |
| SW-2501D | 5/8/2026 9:35:42 AM | 20.6 | 79.4 | 0.0 | 0.0 | | | 0.3 | 0.0 | 75.7 |
| SW-2501D | 5/7/2026 8:55:20 AM | 20.7 | 79.2 | 0.0 | 0.1 | | | 0.3 | 0.0 | 74.7 |
| SW-2501D | 5/6/2026 8:47:06 AM | 20.5 | 79.5 | 0.0 | 0.0 | | | 0.3 | 0.0 | 72.8 |
| SW-2501D | 5/5/2026 8:31:57 AM | 20.3 | 78.4 | 0.0 | 1.3 | | | 0.3 | 0.0 | 72.1 |
| SW-2501D | 5/4/2026 8:20:15 AM | 22.6 | 72.7 | 0.0 | 4.7 | | | 0.3 | 0.0 | 71.3 |
| SW-2501D | 5/1/2026 8:28:56 AM | 26.9 | 73.1 | 0.0 | 0.0 | | | 0.4 | 0.0 | 71.7 |
| SW-2501M | 5/29/2026 7:24:25 AM | 29.9 | 57.8 | 0.2 | 12.1 | | | 0.5 | 60.5 | 61.8 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [°F] |
|---|---|---|---|---|---|---|---|---|---|---|
| SW-2501M | 5/28/2026 6:12:29 AM | 33.6 | 51.8 | 0.6 | 14.0 | | | 0.6 | 23.3 | 62.8 |
| SW-2501M | 5/27/2026 5:59:22 AM | 37.7 | 56.6 | 0.0 | 5.7 | | | 0.7 | 0.0 | 66.1 |
| SW-2501M | 5/26/2026 6:01:33 AM | 34.3 | 54.8 | 0.0 | 10.9 | | | 0.6 | 0.0 | 67.5 |
| SW-2501M | 5/22/2026 6:14:16 AM | 33.5 | 52.7 | 0.3 | 13.5 | | | 0.6 | 45.0 | 64.4 |
| SW-2501M | 5/21/2026 6:30:13 AM | 33.2 | 55.4 | 0.2 | 11.2 | | | 0.6 | 56.0 | 69.4 |
| SW-2501M | 5/20/2026 8:25:51 AM | 33.7 | 58.2 | 0.5 | 7.6 | | | 0.6 | 15.2 | 76.7 |
| SW-2501M | 5/19/2026 8:55:12 AM | 30.6 | 56.0 | 0.4 | 13.0 | | | 0.5 | 32.5 | 76.3 |
| SW-2501M | 5/18/2026 8:38:11 AM | 36.4 | 0.0 | 0.0 | 63.6 | | | | 0.0 | 73.9 |
| SW-2501M | 5/15/2026 9:19:11 AM | 33.3 | 58.4 | 0.5 | 7.8 | | | 0.6 | 15.6 | 71.9 |
| SW-2501M | 5/14/2026 8:13:12 AM | 32.4 | 54.9 | 0.4 | 12.3 | | | 0.6 | 30.8 | 71.6 |
| SW-2501M | 5/13/2026 8:03:42 AM | 31.3 | 55.3 | 0.6 | 12.8 | | | 0.6 | 21.3 | 70.4 |
| SW-2501M | 5/12/2026 9:11:04 AM | 32.2 | 57.2 | 0.2 | 10.4 | | | 0.6 | 52.0 | 76.0 |
| SW-2501M | 5/11/2026 8:20:03 AM | 32.1 | 59.0 | 0.0 | 8.9 | | | 0.5 | 0.0 | 78.4 |
| SW-2501M | 5/8/2026 9:30:13 AM | 33.7 | 61.9 | 0.0 | 4.4 | | | 0.5 | 0.0 | 75.7 |
| SW-2501M | 5/7/2026 8:50:28 AM | 36.4 | 61.4 | 0.0 | 2.2 | | | 0.6 | 0.0 | 73.4 |
| SW-2501M | 5/6/2026 8:42:31 AM | 31.6 | 57.5 | 0.4 | 10.5 | | | 0.5 | 26.3 | 66.5 |
| SW-2501M | 5/5/2026 8:23:44 AM | 30.0 | 58.9 | 0.6 | 10.5 | | | 0.5 | 17.5 | 64.8 |
| SW-2501M | 5/4/2026 8:14:55 AM | 33.3 | 53.2 | 0.4 | 13.1 | | | 0.6 | 32.8 | 67.6 |
| SW-2501M | 5/1/2026 8:25:32 AM | 39.5 | 53.8 | 0.6 | 6.1 | | | 0.7 | 10.2 | 66.1 |
| SW-2501MD | 5/29/2026 7:15:49 AM | 13.2 | 40.0 | 11.4 | 35.4 | | | 0.3 | 3.1 | 76.5 |
| SW-2501MD | 5/28/2026 6:14:16 AM | 15.7 | 38.7 | 10.7 | 34.9 | | | 0.4 | 3.3 | 74.9 |
| SW-2501MD | 5/27/2026 6:02:25 AM | 17.8 | 40.7 | 9.7 | 31.8 | | | 0.4 | 3.3 | 75.7 |
| SW-2501MD | 5/26/2026 6:05:27 AM | 15.9 | 40.1 | 10.0 | 34.0 | | | 0.4 | 3.4 | 72.4 |
| SW-2501MD | 5/22/2026 6:16:46 AM | 15.0 | 38.1 | 10.3 | 36.6 | | | 0.4 | 3.6 | 70.5 |
| SW-2501MD | 5/21/2026 6:32:26 AM | 14.7 | 39.6 | 10.1 | 35.6 | | | 0.4 | 3.5 | 76.6 |
| SW-2501MD | 5/20/2026 8:28:56 AM | 17.0 | 39.6 | 9.9 | 33.5 | | | 0.4 | 3.4 | 78.9 |
| SW-2501MD | 5/19/2026 8:58:19 AM | 12.8 | 36.0 | 10.5 | 40.7 | | | 0.4 | 3.9 | 79.9 |
| SW-2501MD | 5/18/2026 8:41:43 AM | 13.1 | 36.2 | 11.1 | 39.6 | | | 0.4 | 3.6 | 77.5 |
| SW-2501MD | 5/14/2026 8:16:25 AM | 13.8 | 38.5 | 10.0 | 37.7 | | | 0.4 | 3.8 | 77.9 |
| SW-2501MD | 5/13/2026 8:06:36 AM | 11.7 | 31.3 | 12.5 | 44.5 | | | 0.4 | 3.6 | 77.1 |
| SW-2501MD | 5/12/2026 9:12:49 AM | 13.1 | 32.7 | 11.1 | 43.1 | | | 0.4 | 3.9 | 77.3 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [°F] |
|---|---|---|---|---|---|---|---|---|---|---|
| SW-2501MD | 5/11/2026 8:21:50 AM | 11.6 | 31.1 | 11.8 | 45.5 | | | 0.4 | 3.9 | 78.1 |
| SW-2501MD | 5/8/2026 9:32:28 AM | 13.3 | 36.4 | 10.9 | 39.4 | | | 0.4 | 3.6 | 76.7 |
| SW-2501MD | 5/7/2026 8:53:13 AM | 13.9 | 37.1 | 10.4 | 38.6 | | | 0.4 | 3.7 | 77.1 |
| SW-2501MD | 5/6/2026 8:45:13 AM | 11.7 | 31.4 | 12.5 | 44.4 | | | 0.4 | 3.6 | 76.6 |
| SW-2501MD | 5/5/2026 8:27:56 AM | 12.1 | 33.1 | 12.4 | 42.4 | | | 0.4 | 3.4 | 76.4 |
| SW-2501MD | 5/4/2026 8:17:07 AM | 12.4 | 32.3 | 12.3 | 43.0 | | | 0.4 | 3.5 | 76.4 |
| SW-2501MD | 5/1/2026 8:27:27 AM | 16.5 | 31.0 | 12.2 | 40.3 | | | 0.5 | 3.3 | 76.7 |
| SW-2501S | 5/29/2026 7:18:48 AM | 0.4 | 7.1 | 21.0 | 71.5 | | | 0.1 | 3.4 | 66.2 |
| SW-2501S | 5/28/2026 6:18:35 AM | 0.2 | 0.3 | 22.3 | 77.2 | | | 0.7 | 3.5 | 65.4 |
| SW-2501S | 5/27/2026 6:06:12 AM | 0.4 | 0.9 | 21.4 | 77.3 | | | 0.4 | 3.6 | 68.3 |
| SW-2501S | 5/26/2026 6:14:28 AM | 0.1 | 0.3 | 21.9 | 77.7 | | | 0.3 | 3.5 | 68.3 |
| SW-2501S | 5/22/2026 6:22:20 AM | 0.0 | 1.4 | 21.8 | 76.8 | | | 0.0 | 3.5 | 69.5 |
| SW-2501S | 5/21/2026 6:38:09 AM | 0.1 | 1.5 | 21.4 | 77.0 | | | 0.1 | 3.6 | 71.2 |
| SW-2501S | 5/20/2026 8:33:18 AM | 0.4 | 0.3 | 20.7 | 78.6 | | | 1.3 | 3.8 | 72.6 |
| SW-2501S | 5/19/2026 9:04:28 AM | 0.1 | 5.2 | 19.6 | 75.1 | | | 0.0 | 3.8 | 72.4 |
| SW-2501S | 5/18/2026 8:47:27 AM | 0.1 | 5.5 | 20.3 | 74.1 | | | 0.0 | 3.7 | 70.4 |
| SW-2501S | 5/15/2026 9:27:58 AM | 23.0 | 75.7 | 0.0 | 1.3 | | | 0.3 | 0.0 | 75.8 |
| SW-2501S | 5/15/2026 9:22:25 AM | 1.0 | 5.0 | 21.2 | 72.8 | | | 0.2 | 3.4 | 71.8 |
| SW-2501S | 5/14/2026 8:22:49 AM | 0.1 | 7.0 | 19.4 | 73.5 | | | 0.0 | 3.8 | 71.3 |
| SW-2501S | 5/13/2026 8:12:06 AM | 0.0 | 1.9 | 21.5 | 76.6 | | | 0.0 | 3.6 | 72.6 |
| SW-2501S | 5/12/2026 9:17:43 AM | 0.1 | 2.3 | 20.4 | 77.2 | | | 0.0 | 3.8 | 74.8 |
| SW-2501S | 5/11/2026 8:26:36 AM | 0.1 | 3.1 | 20.5 | 76.3 | | | 0.0 | 3.7 | 73.3 |
| SW-2501S | 5/8/2026 9:39:11 AM | 0.1 | 0.8 | 21.1 | 78.0 | | | 0.1 | 3.7 | 73.0 |
| SW-2501S | 5/7/2026 9:00:17 AM | 0.0 | 0.3 | 21.1 | 78.6 | | | 0.0 | 3.7 | 70.2 |
| SW-2501S | 5/6/2026 8:51:41 AM | 0.0 | 1.5 | 21.6 | 76.9 | | | 0.0 | 3.6 | 66.4 |
| SW-2501S | 5/5/2026 8:36:07 AM | 0.0 | 2.6 | 21.8 | 75.6 | | | 0.0 | 3.5 | 66.3 |
| SW-2501S | 5/4/2026 8:22:18 AM | 0.2 | 7.4 | 20.6 | 71.8 | | | 0.0 | 3.5 | 67.3 |
| SW-2501S | 5/1/2026 8:30:42 AM | 0.5 | 0.7 | 21.2 | 77.6 | | | 0.7 | 3.7 | 68.6 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [°F] |
|---|---|---|---|---|---|---|---|---|---|---|
| SW-2502D | 5/29/2026 7:02:56 AM | 9.9 | 87.3 | 0.0 | 2.8 | | | 0.1 | 0.0 | 71.6 |
| SW-2502D | 5/28/2026 6:27:56 AM | 9.1 | 72.6 | 1.0 | 17.3 | | | 0.1 | 17.3 | 64.5 |
| SW-2502D | 5/27/2026 6:15:12 AM | 12.4 | 86.3 | 0.0 | 1.3 | | | 0.1 | 0.0 | 70.4 |
| SW-2502D | 5/26/2026 6:28:54 AM | 11.6 | 85.6 | 0.0 | 2.8 | | | 0.1 | 0.0 | 69.2 |
| SW-2502D | 5/22/2026 6:34:30 AM | 10.6 | 86.3 | 0.0 | 3.1 | | | 0.1 | 0.0 | 68.6 |
| SW-2502D | 5/21/2026 6:50:59 AM | 10.8 | 86.3 | 0.0 | 2.9 | | | 0.1 | 0.0 | 71.1 |
| SW-2502D | 5/20/2026 8:15:28 AM | 11.8 | 88.2 | 0.0 | 0.0 | | | 0.1 | 0.0 | 75.0 |
| SW-2502D | 5/19/2026 9:17:49 AM | 9.5 | 88.5 | 0.0 | 2.0 | | | 0.1 | 0.0 | 77.8 |
| SW-2502D | 5/18/2026 8:59:18 AM | 9.9 | 85.2 | 0.0 | 4.9 | | | 0.1 | 0.0 | 74.1 |
| SW-2502D | 5/15/2026 9:08:52 AM | 11.8 | 88.2 | 0.0 | 0.0 | | | 0.1 | 0.0 | 73.2 |
| SW-2502D | 5/14/2026 8:37:14 AM | 10.0 | 87.2 | 0.0 | 2.8 | | | 0.1 | 0.0 | 72.3 |
| SW-2502D | 5/13/2026 8:21:57 AM | 10.1 | 89.5 | 0.0 | 0.4 | | | 0.1 | 0.0 | 74.4 |
| SW-2502D | 5/12/2026 9:27:18 AM | 10.7 | 87.7 | 0.0 | 1.6 | | | 0.1 | 0.0 | 77.1 |
| SW-2502D | 5/11/2026 8:36:30 AM | 9.8 | 87.9 | 0.0 | 2.3 | | | 0.1 | 0.0 | 76.6 |
| SW-2502D | 5/8/2026 9:49:11 AM | 9.9 | 89.8 | 0.0 | 0.3 | | | 0.1 | 0.0 | 74.6 |
| SW-2502D | 5/7/2026 9:13:11 AM | 10.0 | 88.9 | 0.0 | 1.1 | | | 0.1 | 0.0 | 74.3 |
| SW-2502D | 5/6/2026 9:03:29 AM | 9.9 | 90.1 | 0.0 | 0.0 | | | 0.1 | 0.0 | 72.1 |
| SW-2502D | 5/5/2026 8:48:17 AM | 10.1 | 88.4 | 0.0 | 1.5 | | | 0.1 | 0.0 | 72.4 |
| SW-2502D | 5/4/2026 8:29:47 AM | 11.1 | 80.2 | 0.0 | 8.7 | | | 0.1 | 0.0 | 69.9 |
| SW-2502D | 5/1/2026 8:39:01 AM | 15.4 | 84.2 | 0.0 | 0.4 | | | 0.2 | 0.0 | 72.6 |
| SW-2502M | 5/29/2026 6:58:21 AM | 16.0 | 73.8 | 0.0 | 10.2 | | | 0.2 | 0.0 | 72.9 |
| SW-2502M | 5/28/2026 6:26:04 AM | 16.6 | 75.4 | 0.0 | 8.0 | | | 0.2 | 0.0 | 71.9 |
| SW-2502M | 5/27/2026 6:13:20 AM | 18.0 | 75.9 | 0.0 | 6.1 | | | 0.2 | 0.0 | 73.9 |
| SW-2502M | 5/26/2026 6:25:59 AM | 16.8 | 76.1 | 0.0 | 7.1 | | | 0.2 | 0.0 | 76.0 |
| SW-2502M | 5/22/2026 6:31:26 AM | 16.0 | 76.2 | 0.0 | 7.8 | | | 0.2 | 0.0 | 70.3 |
| SW-2502M | 5/21/2026 6:48:59 AM | 17.1 | 77.0 | 0.0 | 5.9 | | | 0.2 | 0.0 | 77.6 |
| SW-2502M | 5/20/2026 8:13:58 AM | 18.1 | 81.3 | 0.0 | 0.6 | | | 0.2 | 0.0 | 77.7 |
| SW-2502M | 5/19/2026 9:14:46 AM | 15.2 | 83.9 | 0.0 | 0.9 | | | 0.2 | 0.0 | 79.8 |
| SW-2502M | 5/18/2026 8:56:28 AM | 15.4 | 79.4 | 0.0 | 5.2 | | | 0.2 | 0.0 | 76.6 |
| SW-2502M | 5/15/2026 9:04:47 AM | 17.5 | 82.5 | 0.0 | 0.0 | | | 0.2 | 0.0 | 75.9 |
| SW-2502M | 5/14/2026 8:34:30 AM | 16.2 | 79.3 | 0.0 | 4.5 | | | 0.2 | 0.0 | 76.3 |
| SW-2502M | 5/13/2026 8:19:53 AM | 16.1 | 82.2 | 0.0 | 1.7 | | | 0.2 | 0.0 | 77.1 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| SW-2502M | 5/12/2026 9:25:33 AM | 16.2 | 82.8 | 0.0 | 1.0 | | | 0.2 | 0.0 | 78.7 |
| SW-2502M | 5/11/2026 8:34:43 AM | 15.5 | 82.6 | 0.0 | 1.9 | | | 0.2 | 0.0 | 77.3 |
| SW-2502M | 5/8/2026 9:47:15 AM | 15.4 | 84.5 | 0.0 | 0.1 | | | 0.2 | 0.0 | 74.7 |
| SW-2502M | 5/7/2026 9:10:36 AM | 16.1 | 82.5 | 0.0 | 1.4 | | | 0.2 | 0.0 | 72.4 |
| SW-2502M | 5/6/2026 9:01:23 AM | 16.5 | 82.0 | 0.0 | 1.5 | | | 0.2 | 0.0 | 71.0 |
| SW-2502M | 5/5/2026 8:46:24 AM | 16.1 | 82.3 | 0.0 | 1.6 | | | 0.2 | 0.0 | 71.8 |
| SW-2502M | 5/4/2026 8:28:19 AM | 17.1 | 79.1 | 0.0 | 3.8 | | | 0.2 | 0.0 | 71.9 |
| SW-2502M | 5/1/2026 8:36:49 AM | 22.4 | 76.5 | 0.0 | 1.1 | | | 0.3 | 0.0 | 72.2 |
| SW-2502MD | 5/29/2026 7:08:57 AM | 7.6 | 39.7 | 12.2 | 40.5 | | | 0.2 | 3.3 | 77.6 |
| SW-2502MD | 5/28/2026 6:29:56 AM | 9.6 | 37.6 | 11.3 | 41.5 | | | 0.3 | 3.7 | 75.6 |
| SW-2502MD | 5/27/2026 6:16:47 AM | 11.6 | 43.5 | 9.2 | 35.7 | | | 0.3 | 3.9 | 75.2 |
| SW-2502MD | 5/26/2026 6:31:21 AM | 10.0 | 42.2 | 10.0 | 37.8 | | | 0.2 | 3.8 | 77.6 |
| SW-2502MD | 5/22/2026 6:36:17 AM | 9.1 | 41.7 | 10.5 | 38.7 | | | 0.2 | 3.7 | 76.9 |
| SW-2502MD | 5/21/2026 6:52:38 AM | 9.0 | 40.5 | 10.4 | 40.1 | | | 0.2 | 3.9 | 77.0 |
| SW-2502MD | 5/20/2026 8:17:46 AM | 10.3 | 42.1 | 9.8 | 37.8 | | | 0.2 | 3.9 | 79.6 |
| SW-2502MD | 5/19/2026 9:20:34 AM | 7.7 | 43.5 | 10.4 | 38.4 | | | 0.2 | 3.7 | 82.2 |
| SW-2502MD | 5/18/2026 9:02:05 AM | 6.5 | 39.1 | 11.7 | 42.7 | | | 0.2 | 3.6 | 79.7 |
| SW-2502MD | 5/15/2026 9:12:10 AM | 7.1 | 33.5 | 13.6 | 45.8 | | | 0.2 | 3.4 | 78.6 |
| SW-2502MD | 5/14/2026 8:39:47 AM | 8.7 | 44.9 | 9.3 | 37.1 | | | 0.2 | 4.0 | 79.1 |
| SW-2502MD | 5/13/2026 8:24:00 AM | 5.2 | 33.1 | 13.7 | 48.0 | | | 0.2 | 3.5 | 78.8 |
| SW-2502MD | 5/12/2026 9:28:53 AM | 6.7 | 38.1 | 11.6 | 43.6 | | | 0.2 | 3.8 | 80.0 |
| SW-2502MD | 5/11/2026 8:38:07 AM | 6.4 | 40.6 | 11.1 | 41.9 | | | 0.2 | 3.8 | 78.9 |
| SW-2502MD | 5/8/2026 9:51:10 AM | 8.8 | 49.1 | 9.3 | 32.8 | | | 0.2 | 3.5 | 79.1 |
| SW-2502MD | 5/7/2026 9:14:39 AM | 9.0 | 53.0 | 8.6 | 29.4 | | | 0.2 | 3.4 | 77.2 |
| SW-2502MD | 5/6/2026 9:05:22 AM | 5.5 | 34.6 | 13.2 | 46.7 | | | 0.2 | 3.5 | 77.1 |
| SW-2502MD | 5/5/2026 8:50:15 AM | 5.8 | 35.0 | 13.2 | 46.0 | | | 0.2 | 3.5 | 77.5 |
| SW-2502MD | 5/4/2026 8:31:32 AM | 5.8 | 36.0 | 12.9 | 45.3 | | | 0.2 | 3.5 | 77.9 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| SW-2502MD | 5/1/2026 8:41:00 AM | 9.1 | 32.9 | 13.1 | 44.9 | | | 0.3 | 3.4 | 77.8 |
| SW-2502S | 5/29/2026 6:54:54 AM | 0.1 | 9.6 | 20.8 | 69.5 | | | 0.0 | 3.3 | 73.3 |
| SW-2502S | 5/28/2026 6:24:10 AM | 0.2 | 0.1 | 22.2 | 77.5 | | | 2.0 | 3.5 | 65.1 |
| SW-2502S | 5/27/2026 6:11:24 AM | 0.4 | 0.2 | 21.4 | 78.0 | | | 2.0 | 3.6 | 70.6 |
| SW-2502S | 5/26/2026 6:23:43 AM | 0.1 | 0.1 | 21.9 | 77.9 | | | 1.0 | 3.6 | 70.5 |
| SW-2502S | 5/22/2026 6:29:06 AM | 0.0 | 0.3 | 21.9 | 77.8 | | | 0.0 | 3.6 | 69.4 |
| SW-2502S | 5/21/2026 6:47:21 AM | 0.0 | 0.2 | 21.7 | 78.1 | | | 0.0 | 3.6 | 75.0 |
| SW-2502S | 5/20/2026 8:12:10 AM | 0.3 | 0.9 | 20.6 | 78.2 | | | 0.3 | 3.8 | 73.8 |
| SW-2502S | 5/19/2026 9:11:46 AM | 0.0 | 0.8 | 20.4 | 78.8 | | | 0.0 | 3.9 | 73.4 |
| SW-2502S | 5/18/2026 8:53:31 AM | 0.0 | 1.1 | 21.1 | 77.8 | | | 0.0 | 3.7 | 74.8 |
| SW-2502S | 5/15/2026 9:00:33 AM | 0.2 | 0.6 | 21.8 | 77.4 | | | 0.3 | 3.6 | 74.8 |
| SW-2502S | 5/14/2026 8:31:19 AM | 0.0 | 1.6 | 20.3 | 78.1 | | | 0.0 | 3.8 | 74.6 |
| SW-2502S | 5/13/2026 8:17:54 AM | 0.0 | 0.4 | 21.8 | 77.8 | | | 0.0 | 3.6 | 75.5 |
| SW-2502S | 5/12/2026 9:23:35 AM | 0.0 | 0.4 | 20.6 | 79.0 | | | 0.0 | 3.8 | 75.0 |
| SW-2502S | 5/11/2026 8:32:32 AM | 0.0 | 1.0 | 20.7 | 78.3 | | | 0.0 | 3.8 | 75.6 |
| SW-2502S | 5/8/2026 9:44:33 AM | 0.1 | 0.3 | 21.2 | 78.4 | | | 0.3 | 3.7 | 73.8 |
| SW-2502S | 5/7/2026 9:08:55 AM | 0.0 | 0.1 | 21.1 | 78.8 | | | 0.0 | 3.7 | 71.8 |
| SW-2502S | 5/6/2026 8:59:15 AM | 0.0 | 0.4 | 21.7 | 77.9 | | | 0.0 | 3.6 | 68.9 |
| SW-2502S | 5/5/2026 8:44:34 AM | 0.0 | 1.5 | 21.8 | 76.7 | | | 0.0 | 3.5 | 68.8 |
| SW-2502S | 5/4/2026 8:26:37 AM | 0.0 | 2.0 | 21.4 | 76.6 | | | 0.0 | 3.6 | 69.0 |
| SW-2502S | 5/1/2026 8:35:09 AM | 0.6 | 0.2 | 21.1 | 78.1 | | | 3.0 | 3.7 | 68.7 |
| SW-2503D | 5/12/2026 8:21:40 AM | 3.9 | 6.6 | 18.6 | 70.9 | | | 0.6 | 3.8 | 80.5 |
| SW-2503D | 5/4/2026 8:56:42 AM | 13.2 | 9.3 | 10.4 | 67.1 | | | 1.4 | 6.5 | 69.8 |
| SW-2503M | 5/12/2026 8:27:21 AM | 25.9 | 53.2 | 0.0 | 20.9 | | | 0.5 | 0.0 | 75.2 |
| SW-2503M | 5/4/2026 9:01:03 AM | 23.9 | 45.6 | 0.0 | 30.5 | | | 0.5 | 0.0 | 73.9 |
| SW-2503MD | 5/12/2026 8:24:48 AM | 15.9 | 7.2 | 9.0 | 67.9 | | | 2.2 | 7.5 | 77.0 |
| SW-2503MD | 5/4/2026 8:58:22 AM | 4.0 | 5.2 | 19.5 | 71.3 | | | 0.8 | 3.7 | 76.2 |
| SW-2503S | 5/12/2026 8:35:33 AM | 0.2 | 0.6 | 20.5 | 78.7 | | | 0.3 | 3.8 | 80.5 |
| SW-2503S | 5/4/2026 9:03:12 AM | 0.6 | 5.7 | 20.4 | 73.3 | | | 0.1 | 3.6 | 79.7 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| SW-2504D | 5/12/2026 8:47:37 AM | 0.1 | 0.5 | 20.3 | 79.1 | | | 0.2 | 3.9 | 82.3 |
| SW-2504D | 5/4/2026 9:08:28 AM | 0.1 | 1.2 | 21.1 | 77.6 | | | 0.1 | 3.7 | 78.9 |
| SW-2504M | 5/12/2026 8:49:55 AM | 25.6 | 3.3 | 9.5 | 61.6 | | | 7.8 | 6.5 | 79.9 |
| SW-2504M | 5/4/2026 9:18:12 AM | 21.4 | 2.4 | 11.6 | 64.6 | | | 8.9 | 5.6 | 80.5 |
| SW-2504MD | 5/20/2026 1:56:54 PM | 13.0 | 62.0 | 1.3 | 23.7 | | | 0.2 | 18.2 | 132.1 |
| SW-2504MD | 5/12/2026 8:55:07 AM | 2.1 | 8.3 | 16.9 | 72.7 | | | 0.3 | 4.3 | 78.2 |
| SW-2504MD | 5/4/2026 9:22:21 AM | 1.4 | 7.1 | 18.1 | 73.4 | | | 0.2 | 4.1 | 73.0 |
| SW-2504S | 5/12/2026 8:51:59 AM | 3.1 | 0.8 | 19.3 | 76.8 | | | 3.9 | 4.0 | 81.1 |
| SW-2504S | 5/4/2026 9:20:08 AM | 2.6 | 0.7 | 20.4 | 76.3 | | | 3.7 | 3.7 | 75.4 |
| SW-30 | 5/22/2026 6:43:04 AM | 3.2 | 22.7 | 16.3 | 57.8 | | | 0.1 | 3.5 | 52.9 |
| SW-30 | 5/21/2026 7:02:29 AM | 7.9 | 46.6 | 10.6 | 34.9 | | | 0.2 | 3.3 | 60.0 |
| SW-30 | 5/20/2026 8:03:41 AM | 5.9 | 25.8 | 14.5 | 53.8 | | | 0.2 | 3.7 | 73.3 |
| SW-30 | 5/19/2026 9:31:23 AM | 0.0 | 0.6 | 20.7 | 78.7 | | | 0.0 | 3.8 | 83.3 |
| SW-30 | 5/18/2026 9:09:16 AM | 12.7 | 54.3 | 1.1 | 31.9 | | | 0.2 | 29.0 | 79.8 |
| SW-30 | 5/15/2026 8:48:17 AM | 13.5 | 55.0 | 1.6 | 29.9 | | | 0.2 | 18.7 | 71.6 |
| SW-30 | 5/14/2026 8:48:35 AM | 2.3 | 24.5 | 15.8 | 57.4 | | | 0.1 | 3.6 | 75.7 |
| SW-30 | 5/13/2026 8:34:30 AM | 11.3 | 52.2 | 1.6 | 34.9 | | | 0.2 | 21.8 | 67.7 |
| SW-30 | 5/12/2026 9:39:11 AM | 12.2 | 53.2 | 1.5 | 33.1 | | | 0.2 | 22.1 | 81.8 |
| SW-30 | 5/11/2026 8:48:10 AM | 11.6 | 51.2 | 1.5 | 35.7 | | | 0.2 | 23.8 | 85.6 |
| SW-30 | 5/8/2026 10:07:17 AM | 12.3 | 55.3 | 1.3 | 31.1 | | | 0.2 | 23.9 | 83.2 |
| SW-30 | 5/7/2026 9:27:26 AM | 11.2 | 54.6 | 1.4 | 32.8 | | | 0.2 | 23.4 | 85.5 |
| SW-30 | 5/6/2026 9:14:39 AM | 10.1 | 52.9 | 1.9 | 35.1 | | | 0.2 | 18.5 | 78.3 |
| SW-30 | 5/5/2026 9:02:34 AM | 10.1 | 51.9 | 2.0 | 36.0 | | | 0.2 | 18.0 | 66.8 |
| SW-30 | 5/4/2026 8:36:47 AM | 11.0 | 44.9 | 2.0 | 42.1 | | | 0.2 | 21.1 | 69.8 |
| SW-30 | 5/1/2026 8:52:33 AM | 13.8 | 46.8 | 2.0 | 37.4 | | | 0.3 | 18.7 | 77.5 |
| SW-32 | 5/22/2026 6:47:07 AM | 38.8 | 49.8 | 2.7 | 8.7 | | | 0.8 | 3.2 | 52.4 |
| SW-32 | 5/21/2026 7:10:28 AM | 40.3 | 50.7 | 1.4 | 7.6 | | | 0.8 | 5.4 | 69.1 |
| SW-32 | 5/20/2026 7:45:31 AM | 28.3 | 35.3 | 8.5 | 27.9 | | | 0.8 | 3.3 | 73.0 |
| SW-32 | 5/19/2026 9:36:21 AM | 1.4 | 1.6 | 19.8 | 77.2 | | | 0.9 | 3.9 | 90.2 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ ] |
|---|---|---|---|---|---|---|---|---|---|---|
| SW-32 | 5/18/2026 9:14:33 AM | 39.4 | 52.2 | 0.8 | 7.6 | | | 0.8 | 9.5 | 83.5 |
| SW-32 | 5/15/2026 8:38:38 AM | 40.8 | 54.3 | 1.0 | 3.9 | | | 0.8 | 3.9 | 71.0 |
| SW-32 | 5/14/2026 8:53:16 AM | 11.2 | 16.5 | 13.6 | 58.7 | | | 0.7 | 4.3 | 82.8 |
| SW-32 | 5/13/2026 8:29:37 AM | 31.4 | 47.0 | 2.3 | 19.3 | | | 0.7 | 8.4 | 64.2 |
| SW-32 | 5/12/2026 9:35:51 AM | 38.7 | 52.2 | 1.1 | 8.0 | | | 0.7 | 7.3 | 86.0 |
| SW-32 | 5/11/2026 8:43:32 AM | 36.0 | 53.6 | 1.2 | 9.2 | | | 0.7 | 7.7 | 76.0 |
| SW-32 | 5/8/2026 10:02:48 AM | 36.5 | 52.7 | 1.4 | 9.4 | | | 0.7 | 6.7 | 85.0 |
| SW-32 | 5/7/2026 9:20:49 AM | 33.4 | 50.9 | 0.9 | 14.8 | | | 0.7 | 16.4 | 88.0 |
| SW-32 | 5/6/2026 9:10:33 AM | 13.3 | 34.6 | 5.4 | 46.7 | | | 0.4 | 8.6 | 80.0 |
| SW-32 | 5/5/2026 8:56:30 AM | 29.4 | 45.3 | 2.9 | 22.4 | | | 0.6 | 7.7 | 62.9 |
| SW-32 | 5/4/2026 8:41:26 AM | 33.7 | 47.7 | 1.0 | 17.6 | | | 0.7 | 17.6 | 82.3 |
| SW-32 | 5/1/2026 8:45:18 AM | 35.3 | 43.3 | 2.6 | 18.8 | | | 0.8 | 7.2 | 75.0 |
| SW-64 | 5/22/2026 6:40:52 AM | 14.0 | 81.6 | 0.2 | 4.2 | | | 0.2 | 21.0 | 55.3 |
| SW-64 | 5/21/2026 6:58:46 AM | 14.0 | 82.9 | 0.1 | 3.0 | | | 0.2 | 30.0 | 62.7 |
| SW-64 | 5/20/2026 8:05:22 AM | 15.9 | 83.3 | 0.8 | 0.0 | | | 0.2 | 0.0 | 75.2 |
| SW-64 | 5/19/2026 9:28:23 AM | 0.6 | 3.6 | 19.7 | 76.1 | | | 0.2 | 3.9 | 88.2 |
| SW-64 | 5/18/2026 9:06:40 AM | 10.5 | 66.2 | 4.7 | 18.6 | | | 0.2 | 4.0 | 78.7 |
| SW-64 | 5/15/2026 8:53:43 AM | 11.0 | 65.5 | 5.6 | 17.9 | | | 0.2 | 3.2 | 67.8 |
| SW-64 | 5/15/2026 8:43:20 AM | 11.2 | 65.1 | 5.5 | 18.2 | | | 0.2 | 3.3 | 68.3 |
| SW-64 | 5/14/2026 8:44:43 AM | 13.6 | 81.2 | 0.9 | 4.3 | | | 0.2 | 4.8 | 77.6 |
| SW-64 | 5/13/2026 8:36:34 AM | 7.7 | 54.1 | 8.4 | 29.8 | | | 0.1 | 3.5 | 64.9 |
| SW-64 | 5/12/2026 9:41:18 AM | 9.2 | 57.2 | 6.8 | 26.8 | | | 0.2 | 3.9 | 86.0 |
| SW-64 | 5/11/2026 8:51:06 AM | 7.9 | 54.4 | 7.7 | 30.0 | | | 0.1 | 3.9 | 88.6 |
| SW-64 | 5/8/2026 10:09:00 AM | 9.1 | 61.0 | 6.2 | 23.7 | | | 0.1 | 3.8 | 84.0 |
| SW-64 | 5/7/2026 9:29:18 AM | 8.9 | 60.9 | 6.4 | 23.8 | | | 0.1 | 3.7 | 86.9 |
| SW-64 | 5/6/2026 9:16:27 AM | 7.4 | 52.5 | 9.6 | 30.5 | | | 0.1 | 3.2 | 78.6 |
| SW-64 | 5/5/2026 9:04:48 AM | 7.8 | 55.6 | 8.0 | 28.6 | | | 0.1 | 3.6 | 64.0 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| SW-64 | 5/4/2026 8:34:50 AM | 7.9 | 47.7 | 9.1 | 35.3 | | | 0.2 | 3.9 | 66.7 |
| SW-64 | 5/1/2026 8:47:28 AM | 9.8 | 46.9 | 9.8 | 33.5 | | | 0.2 | 3.4 | 76.3 |
| SW-65 | 5/11/2026 9:04:20 AM | 49.8 | 37.6 | 0.0 | 12.6 | | | 1.3 | 0.0 | 86.8 |
| SW-66 | 5/15/2026 9:29:15 AM | 12.3 | 14.8 | 9.9 | 63.0 | | | 0.8 | 6.4 | 86.2 |
| SW-66 | 5/15/2026 9:27:52 AM | 12.2 | 14.8 | 9.9 | 63.1 | | | 0.8 | 6.4 | 86.3 |
| SW-68 | 5/22/2026 6:45:28 AM | 10.3 | 43.5 | 10.0 | 36.2 | | | 0.2 | 3.6 | 52.3 |
| SW-68 | 5/21/2026 7:08:10 AM | 8.8 | 30.1 | 13.1 | 48.0 | | | 0.3 | 3.7 | 65.1 |
| SW-68 | 5/20/2026 7:47:12 AM | 3.7 | 10.4 | 18.6 | 67.3 | | | 0.4 | 3.6 | 72.0 |
| SW-68 | 5/19/2026 9:34:10 AM | 0.0 | 0.3 | 20.7 | 79.0 | | | 0.0 | 3.8 | 88.3 |
| SW-68 | 5/18/2026 9:11:53 AM | 22.7 | 72.6 | 0.0 | 4.7 | | | 0.3 | 0.0 | 78.5 |
| SW-68 | 5/15/2026 8:34:05 AM | 25.3 | 74.2 | 0.3 | 0.2 | | | 0.3 | 0.7 | 72.3 |
| SW-68 | 5/14/2026 8:50:57 AM | 1.2 | 9.5 | 18.8 | 70.5 | | | 0.1 | 3.8 | 80.7 |
| SW-68 | 5/13/2026 8:31:50 AM | 22.2 | 73.8 | 0.1 | 3.9 | | | 0.3 | 39.0 | 68.7 |
| SW-68 | 5/12/2026 9:37:18 AM | 23.7 | 72.0 | 0.1 | 4.2 | | | 0.3 | 42.0 | 80.7 |
| SW-68 | 5/11/2026 8:45:53 AM | 21.9 | 71.8 | 0.5 | 5.8 | | | 0.3 | 11.6 | 83.4 |
| SW-68 | 5/8/2026 10:04:26 AM | 23.0 | 75.2 | 0.0 | 1.8 | | | 0.3 | 0.0 | 82.4 |
| SW-68 | 5/7/2026 9:24:55 AM | 22.2 | 76.5 | 0.0 | 1.3 | | | 0.3 | 0.0 | 84.4 |
| SW-68 | 5/6/2026 9:12:20 AM | 22.8 | 74.8 | 0.1 | 2.3 | | | 0.3 | 23.0 | 78.9 |
| SW-68 | 5/5/2026 8:59:48 AM | 21.8 | 74.4 | 0.5 | 3.3 | | | 0.3 | 6.6 | 67.9 |
| SW-68 | 5/4/2026 8:39:10 AM | 23.3 | 70.8 | 0.5 | 5.4 | | | 0.3 | 10.8 | 70.5 |
| SW-68 | 5/1/2026 8:43:53 AM | 28.6 | 67.6 | 0.3 | 3.5 | | | 0.4 | 11.7 | 75.4 |
| SW-7 | 5/1/2026 7:54:58 AM | 0.6 | 0.5 | 20.9 | 78.0 | | | 1.2 | 3.7 | 66.7 |
| SW-70 | 5/4/2026 9:33:46 AM | 17.0 | 68.8 | 0.0 | 14.2 | | | 0.2 | 0.0 | 73.2 |
| SW-71 | 5/6/2026 8:31:08 AM | 10.7 | 17.4 | 7.2 | 64.7 | | | 0.6 | 9.0 | 73.2 |
| SW-71 | 5/6/2026 8:23:03 AM | 11.1 | 18.8 | 7.1 | 63.0 | | | 0.6 | 8.9 | 73.3 |
| SW-72 | 5/6/2026 9:25:28 AM | 6.8 | 18.9 | 3.3 | 71.0 | | | 0.4 | 21.5 | 78.8 |
| SW-80 | 5/12/2026 1:23:15 PM | 34.2 | 32.0 | 0.0 | 33.8 | | | 1.1 | 1691.0 | 82.8 |
| SW-9 | 5/4/2026 9:35:40 AM | 1.8 | 28.1 | 10.0 | 60.1 | | | 0.1 | 6.0 | 81.4 |
| TC-1961C | 5/4/2026 11:11:27 AM | 27.3 | 36.3 | 0.0 | 36.4 | | | 0.8 | 0.0 | 92.5 |
| TC-1961E | 5/4/2026 10:42:18 AM | 51.9 | 44.5 | 0.0 | 3.6 | | | 1.2 | 0.0 | 114.5 |
| TC-2174 | 5/26/2026 9:02:15 AM | 2.6 | 76.4 | 0.0 | 21.0 | | | 0.0 | 0.0 | 183.1 |
| TC-2174 | 5/18/2026 9:25:30 AM | 18.3 | 75.6 | 0.0 | 6.1 | | | 0.2 | 0.0 | 182.9 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [ °F ] |
|---|---|---|---|---|---|---|---|---|---|---|
| TC-2174 | 5/18/2026 9:25:00 AM | | | | | 1900 | | | | |
| TC-2174 | 5/18/2026 9:24:46 AM | 19.0 | 75.0 | 0.0 | 6.0 | | | 0.3 | 0.0 | 183.2 |
| TC-2174 | 5/12/2026 9:30:00 AM | | | | | 854 | | | | |
| TC-2174 | 5/12/2026 9:24:37 AM | 21.9 | 78.1 | 0.0 | 0.0 | | | 0.3 | 0.0 | 183.1 |
| TC-2174 | 5/5/2026 8:40:00 AM | | | | | 2130 | | | | |
| TC-2174 | 5/5/2026 8:40:00 AM | | | | | | 159000 | | | |
| TC-2174 | 5/5/2026 8:34:39 AM | 4.5 | 81.5 | 0.0 | 14.0 | | | 0.1 | 0.0 | 182.7 |
| VL-02 | 5/28/2026 3:26:30 PM | 53.9 | 35.0 | 2.4 | 8.7 | | | 1.5 | 3.6 | 88.4 |
| WTD-01 | 5/21/2026 5:51:51 AM | 15.3 | 33.9 | 10.4 | 40.4 | | | 0.5 | 3.9 | 139.9 |
| WTD-01 | 5/21/2026 5:51:17 AM | 15.5 | 32.4 | 10.5 | 41.6 | | | 0.5 | 4.0 | 140.0 |
| WTD-01 | 5/1/2026 7:48:21 AM | 20.7 | 38.7 | 8.5 | 32.1 | | | 0.5 | 3.8 | 141.4 |
| WTD-01 | 5/1/2026 7:47:42 AM | 20.5 | 37.5 | 8.5 | 33.5 | | | 0.5 | 3.9 | 141.3 |
| WTD-02 | 5/21/2026 5:58:44 AM | 9.4 | 47.2 | 7.5 | 35.9 | | | 0.2 | 4.8 | 155.3 |
| WTD-02 | 5/21/2026 5:58:19 AM | 9.4 | 45.7 | 7.5 | 37.4 | | | 0.2 | 5.0 | 155.3 |
| WTD-02 | 5/13/2026 1:51:34 PM | 11.2 | 46.7 | 7.2 | 34.9 | | | 0.2 | 4.8 | 154.9 |
| WTD-02 | 5/13/2026 1:50:30 PM | 11.0 | 46.5 | 7.3 | 35.2 | | | 0.2 | 4.8 | 154.8 |
| WTD-02 | 5/6/2026 1:50:52 PM | 13.2 | 52.4 | 5.2 | 29.2 | | | 0.3 | 5.6 | 156.2 |
| WTD-02 | 5/6/2026 1:50:00 PM | | | | | 1080 | | | | |
| WTD-02 | 5/6/2026 1:50:00 PM | | | | | | 76800 | | | |
| WTD-02 | 5/6/2026 1:49:41 PM | 13.5 | 52.1 | 5.2 | 29.2 | | | 0.3 | 5.6 | 156.2 |
| WTD-03 | 5/21/2026 6:07:17 AM | 1.5 | 11.6 | 18.2 | 68.7 | | | 0.1 | 3.8 | 112.5 |
| WTD-03 | 5/21/2026 6:06:19 AM | 1.5 | 12.3 | 18.5 | 67.7 | | | 0.1 | 3.7 | 112.5 |
| WTD-03 | 5/1/2026 8:09:37 AM | 4.1 | 11.7 | 17.9 | 66.3 | | | 0.4 | 3.7 | 119.0 |
| WTD-03 | 5/1/2026 8:08:56 AM | 4.0 | 11.2 | 18.0 | 66.8 | | | 0.4 | 3.7 | 118.8 |
| WTD-04 | 5/21/2026 6:19:17 AM | 0.3 | 1.4 | 20.9 | 77.4 | | | 0.2 | 3.7 | 60.1 |
| WTD-04 | 5/21/2026 6:16:55 AM | 0.3 | 1.4 | 21.1 | 77.2 | | | 0.2 | 3.7 | 60.2 |
| WTD-04 | 5/1/2026 8:15:02 AM | 0.6 | 0.8 | 21.2 | 77.4 | | | 0.8 | 3.7 | 64.3 |
| WTD-04 | 5/1/2026 8:14:32 AM | 0.6 | 0.8 | 21.2 | 77.4 | | | 0.8 | 3.7 | 63.9 |
| WTD-05 | 5/21/2026 6:13:19 AM | 0.9 | 4.1 | 19.8 | 75.2 | | | 0.2 | 3.8 | 67.3 |
| WTD-05 | 5/21/2026 6:12:45 AM | 0.9 | 4.0 | 19.9 | 75.2 | | | 0.2 | 3.8 | 67.2 |
| WTD-05 | 5/1/2026 8:12:57 AM | 2.0 | 3.4 | 20.0 | 74.6 | | | 0.6 | 3.7 | 71.9 |
| WTD-05 | 5/1/2026 8:12:16 AM | 1.8 | 2.7 | 20.0 | 75.5 | | | 0.7 | 3.8 | 72.6 |
| WTD-06 | 5/21/2026 6:21:19 AM | 2.4 | 6.6 | 18.1 | 72.9 | | | 0.4 | 4.0 | 110.8 |
| WTD-06 | 5/21/2026 6:20:59 AM | 2.3 | 6.3 | 18.2 | 73.2 | | | 0.4 | 4.0 | 110.8 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | CH4:CO2 | BalO2 [%] | Init Temp [°F] |
|---|---|---|---|---|---|---|---|---|---|---|
| WTD-06 | 5/1/2026 8:20:07 AM | 5.2 | 9.7 | 17.2 | 67.9 | | | 0.5 | 3.9 | 116.8 |
| WTD-06 | 5/1/2026 8:17:56 AM | 5.1 | 9.2 | 17.3 | 68.4 | | | 0.6 | 4.0 | 116.6 |
| WTD-07 | 5/21/2026 6:25:15 AM | 0.0 | 0.0 | 21.5 | 78.5 | | | | 3.7 | 67.4 |
| WTD-07 | 5/21/2026 6:24:46 AM | 0.0 | 0.0 | 21.6 | 78.4 | | | | 3.6 | 67.5 |
| WTD-07 | 5/1/2026 8:22:32 AM | 1.7 | 2.3 | 20.2 | 75.8 | | | 0.7 | 3.8 | 65.8 |
| WTD-07 | 5/1/2026 8:21:58 AM | 1.5 | 2.2 | 20.4 | 75.9 | | | 0.7 | 3.7 | 65.6 |
| WTD-10 | 5/21/2026 7:17:44 AM | 15.7 | 25.4 | 10.4 | 48.5 | | | 0.6 | 4.7 | 110.2 |
| WTD-10 | 5/21/2026 7:17:13 AM | 15.7 | 25.0 | 10.4 | 48.9 | | | 0.6 | 4.7 | 110.1 |
| WTD-10 | 5/4/2026 8:01:28 AM | 16.9 | 26.8 | 10.0 | 46.3 | | | 0.6 | 4.6 | 106.3 |
| WTD-10 | 5/4/2026 8:00:56 AM | 16.9 | 26.0 | 10.1 | 47.0 | | | 0.7 | 4.7 | 106.4 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj °F Temp [ ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| A-01 | 5/15/2026 8:51:04 AM | 79.4 | -16.59 | -16.50 | 0.0 | 0.0 | | | | |
| A-02 | 5/11/2026 7:44:04 AM | 92.7 | -12.16 | -12.14 | 0.0 | 0.0 | | | | |
| A-03 | 5/11/2026 7:56:41 AM | 75.5 | -12.00 | -12.18 | 0.0 | 0.0 | | | | |
| A-04 | 5/11/2026 8:06:12 AM | 94.6 | -8.29 | -8.28 | 0.0 | 0.0 | 8.488 | 7.453 | | |
| A-05 | 5/11/2026 8:01:26 AM | 76.3 | -11.36 | -11.37 | 0.0 | 0.0 | | | | |
| B-01 | 5/11/2026 10:37:28 AM | 89.7 | -0.19 | -0.17 | 0.0 | 0.0 | -0.042 | -0.034 | -12.42 | |
| B-02R | 5/11/2026 10:34:40 AM | 100.0 | -0.26 | -0.19 | 0.0 | 0.0 | -0.126 | -0.101 | -12.25 | |
| B-03R | 5/11/2026 10:04:48 AM | 83.7 | -0.78 | -0.73 | 1.9 | 1.9 | 0.372 | 0.374 | -11.95 | |
| B-05 | 5/11/2026 10:25:34 AM | 89.0 | -0.34 | -0.28 | 3.5 | 3.5 | 0.072 | 0.072 | -11.63 | |
| B-06 | 5/11/2026 10:19:19 AM | 80.0 | -0.39 | -0.36 | 5.9 | 5.8 | 0.197 | 0.190 | -11.66 | |
| B-07R | 5/11/2026 9:31:57 AM | 91.1 | -0.36 | -0.36 | 2.6 | 3.6 | 1.624 | 3.016 | -10.29 | |
| B-08 | 5/11/2026 10:15:29 AM | 88.6 | -0.37 | -0.32 | 0.0 | 0.0 | 0.226 | 0.219 | -11.76 | |
| B-09 | 5/11/2026 9:37:05 AM | 92.6 | -0.21 | -0.20 | 0.0 | 0.0 | 0.212 | 0.210 | -12.04 | |
| B-10 | 5/11/2026 9:24:54 AM | 88.5 | -0.13 | -0.11 | 0.0 | 0.0 | 0.177 | 0.167 | -11.69 | |
| B-11 | 5/29/2026 3:03:30 PM | 96.7 | -0.24 | -0.24 | | | 0.000 | 0.000 | -16.52 | -16.24 |
| B-12 | 5/11/2026 10:00:30 AM | 92.9 | -0.16 | -0.16 | 2.8 | 2.4 | 2.009 | 1.505 | -11.34 | |
| B-13 | 5/11/2026 9:49:42 AM | 87.5 | -0.21 | -0.17 | 16.3 | 15.4 | 0.078 | 0.070 | -12.09 | |
| B-14 | 5/29/2026 3:07:12 PM | 92.1 | -0.98 | -0.92 | 2.5 | 2.3 | 0.622 | 0.562 | -15.07 | -15.17 |
| C-03 | 5/11/2026 7:49:46 AM | 69.1 | -11.67 | -12.12 | 0.0 | 0.0 | | | | |
| C-07 | 5/1/2026 3:11:09 PM | 88.3 | -13.31 | -13.32 | | | 13.300 | 13.300 | -13.09 | -13.08 |
| C-08 | 5/8/2026 1:03:42 PM | 100.4 | -7.77 | -7.78 | | | 7.816 | 7.877 | -7.79 | -7.81 |
| C-10 | 5/11/2026 9:07:51 AM | 89.3 | -12.95 | -12.90 | 0.0 | 0.0 | | | | |
| C-11 | 5/11/2026 8:38:28 AM | 83.7 | -11.49 | -11.48 | 0.0 | 0.0 | 0.069 | 0.049 | | |
| C-12 | 5/29/2026 12:20:26 PM | 84.3 | -7.18 | -7.52 | 12.3 | 12.4 | 0.909 | 0.935 | -9.22 | -9.16 |
| C-12 | 5/11/2026 1:57:43 PM | 99.7 | -7.09 | -7.09 | 3.3 | 3.2 | 0.067 | 0.064 | -7.73 | -7.41 |
| C-15 | 5/11/2026 2:07:31 PM | 95.3 | -7.52 | -7.53 | 0.5 | 0.9 | 0.000 | 0.002 | -7.42 | -7.42 |
| C-17B | 5/12/2026 10:45:10 AM | 109.9 | -7.60 | -7.72 | | | 7.507 | 7.592 | -8.43 | -8.40 |
| C-18 | 5/12/2026 1:08:06 PM | 103.5 | -8.73 | -8.73 | | | 8.844 | 8.821 | -9.06 | -9.06 |
| C-19 | 5/12/2026 12:49:10 PM | 99.2 | -8.39 | -8.39 | | | 8.465 | 8.440 | -9.06 | -9.06 |
| C-20 | 5/12/2026 12:57:51 PM | 99.0 | -8.75 | -8.73 | | | 8.909 | 8.882 | -8.72 | -8.72 |
| C-23 | 5/12/2026 11:00:46 AM | 128.4 | -4.39 | -4.39 | | | 4.422 | 4.420 | -9.49 | -9.56 |
| C-24 | 5/15/2026 9:17:41 AM | 103.1 | -1.52 | -1.50 | 0.0 | 0.0 | 1.557 | 1.547 | | |
| C-25 | 5/11/2026 2:14:04 PM | 97.9 | -7.17 | -7.09 | | | 7.754 | 7.720 | 0.67 | 0.67 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| C-26 | 5/29/2026 12:46:54 PM | 103.6 | -7.09 | -7.14 | | | 7.011 | 7.119 | 0.00 | 0.00 |
| C-26 | 5/15/2026 9:07:37 AM | 78.1 | -10.30 | -10.20 | 0.0 | 0.0 | | | | |
| C-27 | 5/11/2026 2:04:38 PM | 97.2 | -2.03 | -2.47 | 0.9 | 1.6 | 0.002 | 0.006 | -7.44 | -7.43 |
| C-28 | 5/29/2026 12:16:57 PM | 98.9 | -10.85 | -10.98 | 28.1 | 28.3 | 1.013 | 1.028 | -10.84 | -11.09 |
| C-28 | 5/11/2026 8:35:54 AM | 100.1 | -11.30 | -11.28 | 0.0 | 0.0 | -0.049 | -0.041 | | |
| C-29 | 5/11/2026 8:54:46 AM | 107.7 | -7.99 | -7.98 | 0.0 | 0.0 | 8.136 | 8.112 | | |
| C-30 | 5/11/2026 8:49:08 AM | 126.7 | -3.58 | -3.56 | 0.0 | 0.0 | -0.030 | -0.015 | -9.14 | |
| CV-02 | 5/11/2026 8:21:58 AM | 120.1 | -0.36 | -0.36 | 0.0 | 0.0 | -0.038 | -0.024 | -13.25 | |
| CV-03 | 5/11/2026 8:18:37 AM | 118.9 | -5.68 | -5.73 | 15.3 | 16.6 | 1.412 | 1.657 | -13.44 | |
| CV-04 | 5/11/2026 8:14:52 AM | 109.1 | -1.69 | -1.78 | 14.1 | 11.8 | 0.055 | 0.039 | | |
| CV-05 | 5/8/2026 12:41:33 PM | 100.0 | -8.11 | -8.13 | 7.5 | 7.5 | 1.154 | 1.171 | -8.09 | -8.16 |
| CV-06 | 5/12/2026 8:03:49 AM | 90.3 | -10.30 | -10.28 | 3.4 | 3.4 | 0.072 | 0.073 | -12.49 | |
| CV-108-52 | 5/19/2026 1:02:47 PM | 101.6 | -2.70 | -2.78 | | | 0.563 | 0.567 | -2.90 | -3.03 |
| CV-108-52 | 5/18/2026 11:07:16 AM | | | | | | | | | |
| CV-108-52 | 5/6/2026 8:30:00 AM | | | | | | | | | |
| CV-108-52 | 5/1/2026 10:29:07 AM | 99.7 | -6.51 | -6.42 | | | 1.173 | 1.296 | -7.71 | -7.62 |
| CV-113 | 5/26/2026 2:01:29 PM | 72.9 | -0.39 | -0.35 | 2.2 | 1.8 | 0.030 | 0.019 | -3.32 | -2.61 |
| CV-113 | 5/15/2026 9:28:02 AM | 66.6 | -0.24 | -0.23 | 3.0 | 2.9 | 0.052 | 0.050 | -3.12 | -3.43 |
| CV-113 | 5/4/2026 7:50:00 AM | | | | | | | | | |
| CV-114 | 5/26/2026 8:58:28 AM | 170.7 | -0.17 | -0.65 | | | 0.154 | 0.821 | 0.23 | 0.24 |
| CV-114 | 5/18/2026 9:20:17 AM | 164.4 | 1.25 | 1.34 | | | 0.000 | 0.000 | -1.86 | -1.82 |
| CV-114 | 5/18/2026 9:20:00 AM | | | | | | | | | |
| CV-114 | 5/18/2026 9:17:57 AM | 163.8 | 1.57 | 1.59 | | | 0.000 | 0.000 | -1.83 | -1.83 |
| CV-114 | 5/12/2026 9:25:00 AM | | | | | | | | | |
| CV-114 | 5/12/2026 9:22:16 AM | 174.3 | -1.52 | -1.56 | | | 1.658 | 1.701 | -5.10 | -5.10 |
| CV-114 | 5/5/2026 8:35:00 AM | | | | | | | | | |
| CV-114 | 5/5/2026 8:35:00 AM | | | | | | | | | |
| CV-114 | 5/5/2026 8:32:18 AM | 173.1 | -2.04 | -2.13 | | | 1.906 | 2.157 | -5.67 | -5.62 |
| CV-114 | 5/4/2026 8:05:00 AM | | | | | | | | | |
| CV-1424 | 5/1/2026 11:22:59 AM | 105.2 | -2.80 | -2.79 | 19.7 | 19.7 | 2.280 | 2.280 | -12.70 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-1532A | 5/28/2026 8:54:46 AM | 66.6 | -6.50 | -6.24 | | | 6.772 | 6.518 | -5.83 | -5.42 |
| CV-1532A | 5/13/2026 1:09:52 PM | 81.7 | -4.01 | -5.13 | 0.0 | 0.0 | 3.625 | 5.054 | -5.14 | |
| CV-1532A | 5/13/2026 1:07:32 PM | 81.9 | -3.42 | -3.87 | 0.0 | 0.0 | 4.299 | 3.752 | -5.11 | |
| CV-1532A | 5/11/2026 8:15:00 AM | | | | | | | | | |
| CV-1532A | 5/11/2026 8:15:00 AM | | | | | | | | | |
| CV-1534A-PLR | 5/28/2026 1:23:27 PM | 185.1 | 4.04 | 3.77 | | | 0.000 | 0.000 | 0.00 | 0.00 |
| CV-1534A-PLR | 5/28/2026 1:20:34 PM | 185.9 | 4.04 | 4.19 | | | 0.000 | 0.000 | 0.00 | 0.00 |
| CV-1534A-PLR | 5/20/2026 9:03:59 AM | 185.1 | 3.27 | 4.63 | | | 0.000 | 0.000 | 0.21 | 0.21 |
| CV-1534A-PLR | 5/13/2026 9:42:40 AM | 184.4 | 1.96 | 1.90 | | | 0.000 | 0.000 | 0.28 | 0.28 |
| CV-1534A-PLR | 5/6/2026 10:03:56 AM | 179.3 | -0.84 | -0.51 | | | 0.893 | 0.473 | 0.27 | 0.30 |
| CV-1534A-PLR | 5/6/2026 9:55:00 AM | | | | | | | | | |
| CV-1534A-PLR | 5/6/2026 9:55:00 AM | | | | | | | | | |
| CV-1535 | 5/19/2026 12:55:31 PM | 119.5 | -0.23 | -0.22 | | | 0.058 | 0.050 | -3.25 | -3.43 |
| CV-1535 | 5/11/2026 8:25:00 AM | | | | | | | | | |
| CV-1535 | 5/11/2026 8:25:00 AM | | | | | | | | | |
| CV-1535 | 5/1/2026 10:31:55 AM | 120.4 | -0.90 | -0.82 | | | 0.638 | 0.551 | -8.20 | -8.13 |
| CV-1601D | 5/22/2026 10:03:49 AM | 111.4 | -0.35 | -0.40 | 2.5 | 9.9 | 0.120 | 1.968 | -8.77 | |
| CV-1601D | 5/4/2026 10:02:19 AM | 110.2 | -0.38 | -0.41 | 6.0 | 9.0 | 0.721 | 1.636 | -10.41 | |
| CV-1601S | 5/22/2026 10:00:47 AM | 104.5 | -0.10 | -0.17 | 2.1 | 4.0 | 0.085 | 0.320 | -8.46 | |
| CV-1601S | 5/4/2026 9:59:23 AM | 101.4 | -0.26 | -0.27 | 3.7 | 3.7 | 0.281 | 0.268 | -10.85 | |
| CV-1604 | 5/4/2026 11:02:38 AM | 125.5 | -1.55 | -1.37 | 3.3 | 2.2 | 0.240 | 0.099 | -14.41 | -14.37 |
| CV-1701D | 5/8/2026 1:23:50 PM | 100.5 | -0.25 | -0.26 | 0.5 | 0.8 | 0.062 | 0.177 | -14.14 | -14.23 |
| CV-1701D | 5/8/2026 1:22:18 PM | 99.0 | 0.71 | -0.25 | 0.7 | 0.5 | 0.118 | 0.059 | -13.11 | -13.13 |
| CV-1701D | 5/7/2026 11:12:23 AM | 91.6 | -1.01 | -0.98 | 0.2 | 0.2 | 0.008 | 0.010 | -4.74 | |
| CV-1701S | 5/7/2026 11:16:55 AM | 137.1 | -0.83 | -0.82 | 0.0 | 0.0 | -0.029 | -0.023 | -4.86 | |
| CV-1701S | 5/7/2026 11:15:22 AM | 138.6 | -1.21 | -1.11 | 0.0 | 0.0 | -0.051 | -0.010 | -4.95 | |
| CV-1901 | 5/19/2026 10:20:41 AM | 107.6 | -0.19 | -0.18 | 1.1 | 1.1 | 0.027 | 0.026 | -5.38 | -5.32 |
| CV-1901 | 5/19/2026 10:18:56 AM | 106.7 | 0.39 | -0.11 | 1.4 | 0.9 | 0.041 | 0.018 | -5.24 | -5.29 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-1901 | 5/12/2026 10:20:03 AM | 106.6 | -0.11 | -0.12 | 0.0 | 0.0 | -0.029 | -0.027 | -6.42 | |
| CV-1901 | 5/12/2026 10:17:30 AM | 106.4 | 0.54 | -0.02 | 0.0 | 0.0 | -0.178 | -0.049 | -5.88 | |
| CV-1902A | 5/28/2026 8:49:43 AM | 172.3 | -7.63 | -7.66 | | | 7.675 | 7.692 | -7.45 | -7.48 |
| CV-1902A | 5/20/2026 8:10:11 AM | 157.4 | -5.28 | -5.26 | | | 5.281 | 5.258 | -5.00 | -4.98 |
| CV-1902A | 5/14/2026 1:48:17 PM | 168.6 | -5.46 | -5.64 | | | 5.491 | 5.604 | -5.50 | -5.69 |
| CV-1902A | 5/11/2026 1:48:31 PM | 152.7 | -3.48 | -3.32 | | | 3.400 | 3.318 | 9.42 | 9.42 |
| CV-1902A | 5/11/2026 7:55:00 AM | | | | | | | | | |
| CV-1902A | 5/11/2026 7:55:00 AM | | | | | | | | | |
| CV-1902A | 5/6/2026 9:06:28 AM | 159.6 | -6.78 | -6.73 | | | 6.742 | 6.696 | -6.80 | -6.80 |
| CV-1902A | 5/6/2026 9:05:00 AM | | | | | | | | | |
| CV-1902A | 5/6/2026 9:05:00 AM | | | | | | | | | |
| CV-1905 | 5/6/2026 12:45:38 PM | 109.4 | -1.57 | -1.83 | 3.4 | 7.0 | 0.072 | 0.309 | -8.17 | -8.09 |
| CV-1905 | 5/6/2026 10:44:14 AM | 104.5 | -1.10 | -2.17 | 5.3 | 8.4 | 0.169 | 0.420 | -13.38 | |
| CV-2001 | 5/20/2026 9:55:23 AM | 103.3 | -4.03 | -4.05 | 21.5 | 20.7 | 0.590 | 0.548 | -4.19 | -4.10 |
| CV-2001 | 5/12/2026 8:45:06 AM | 76.2 | -2.86 | -3.81 | 0.0 | 0.0 | -0.083 | -0.092 | -4.37 | |
| CV-2001 | 5/6/2026 7:50:00 AM | | | | | | | | | |
| CV-2001 | 5/6/2026 7:50:00 AM | | | | | | | | | |
| CV-2001 | 5/1/2026 10:12:38 AM | 86.2 | -6.24 | -5.48 | 5.0 | 6.4 | 0.031 | 0.051 | -6.26 | -6.58 |
| CV-2002 | 5/28/2026 10:15:53 AM | 182.2 | -0.75 | -0.81 | 15.8 | 16.5 | 0.749 | 0.818 | -0.97 | -1.05 |
| CV-2002 | 5/28/2026 10:12:21 AM | 183.6 | 0.35 | -0.67 | 3.9 | 13.4 | 0.045 | 0.541 | -2.10 | -1.90 |
| CV-2002 | 5/20/2026 9:42:31 AM | 178.6 | -2.21 | -2.02 | 23.7 | 21.5 | 1.686 | 1.389 | -3.82 | -3.64 |
| CV-2002 | 5/20/2026 9:41:05 AM | 178.0 | -3.15 | -2.83 | 32.8 | 31.2 | 3.238 | 2.938 | -4.07 | -4.27 |
| CV-2002 | 5/13/2026 10:09:19 AM | 181.8 | -0.82 | -1.05 | 23.7 | 23.4 | 1.684 | 1.645 | 0.23 | 0.22 |
| CV-2002 | 5/11/2026 8:10:00 AM | | | | | | | | | |
| CV-2002 | 5/11/2026 8:10:00 AM | | | | | | | | | |
| CV-2002 | 5/6/2026 1:05:00 PM | | | | | | | | | |
| CV-2002 | 5/6/2026 1:05:00 PM | | | | | | | | | |
| CV-2002 | 5/6/2026 1:02:03 PM | 181.8 | -1.14 | -1.31 | 22.9 | 21.2 | 1.571 | 1.350 | -4.81 | -4.69 |
| CV-2003 | 5/19/2026 1:11:41 PM | 119.2 | -0.07 | -0.06 | 0.4 | 0.8 | 0.020 | 0.064 | -4.50 | -4.50 |
| CV-2003 | 5/19/2026 1:06:11 PM | 121.5 | 0.11 | -0.10 | 1.8 | 1.6 | 0.341 | 0.287 | -3.61 | -3.65 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2003 | 5/1/2026 10:27:07 AM | 118.7 | -0.21 | -0.20 | 1.7 | 1.7 | 0.305 | 0.298 | -7.82 | -7.83 |
| CV-2006 | 5/28/2026 8:42:46 AM | 187.4 | -5.22 | -5.43 | 15.8 | 10.9 | 0.367 | 0.174 | -8.22 | -8.48 |
| CV-2006 | 5/20/2026 8:18:51 AM | 187.5 | -3.64 | -3.64 | 17.2 | 17.2 | 0.435 | 0.435 | -6.85 | -6.85 |
| CV-2006 | 5/14/2026 2:04:55 PM | 184.9 | -2.55 | -2.56 | 1.9 | 8.7 | 0.007 | 0.146 | -6.01 | |
| CV-2006 | 5/14/2026 2:03:40 PM | 185.4 | -4.31 | -2.22 | 7.7 | 7.7 | 0.114 | 0.113 | -6.52 | |
| CV-2006 | 5/11/2026 1:55:37 PM | 188.2 | 2.57 | 2.99 | 11.7 | 10.1 | 0.198 | 0.147 | 4.05 | 4.05 |
| CV-2006 | 5/6/2026 9:20:00 AM | | | | | | | | | |
| CV-2006 | 5/6/2026 9:20:00 AM | | | | | | | | | |
| CV-2006 | 5/6/2026 9:17:48 AM | 187.5 | -2.10 | -2.23 | 5.6 | 6.1 | 0.046 | 0.054 | -6.57 | -7.38 |
| CV-2007 | 5/20/2026 2:00:34 PM | 112.8 | -0.10 | -0.11 | 0.7 | 3.5 | 0.001 | 0.033 | -7.42 | -9.01 |
| CV-2007 | 5/8/2026 9:48:29 AM | 93.8 | -0.01 | -0.03 | 0.0 | 0.0 | -0.055 | -0.054 | -3.18 | |
| CV-2007 | 5/4/2026 8:10:00 AM | | | | | | | | | |
| CV-2008 | 5/11/2026 2:03:03 PM | 111.4 | -0.88 | -0.44 | 2.1 | 0.4 | 0.106 | 0.005 | -4.49 | |
| CV-2009 | 5/8/2026 9:02:48 AM | 136.0 | -0.11 | -0.07 | 16.0 | 15.6 | 0.355 | 0.336 | -1.36 | |
| CV-2009 | 5/8/2026 9:00:33 AM | 136.1 | 0.54 | -0.02 | 14.4 | 16.6 | 0.285 | 0.380 | -1.11 | |
| CV-2009A | 5/11/2026 1:51:42 PM | 129.8 | -0.16 | -0.16 | 6.2 | 6.2 | 0.905 | 0.909 | -6.01 | |
| CV-2010 | 5/4/2026 1:15:27 PM | 117.5 | -1.88 | -1.68 | 14.1 | 12.3 | 0.257 | 0.196 | -12.95 | -12.97 |
| CV-2010A | 5/21/2026 10:29:08 AM | 142.2 | -8.80 | -8.78 | 27.0 | 25.1 | 2.110 | 1.833 | -9.92 | -9.96 |
| CV-2010A | 5/14/2026 9:40:00 AM | | | | | | | | | |
| CV-2010A | 5/14/2026 9:38:44 AM | 153.5 | 11.78 | -2.01 | 2.3 | 55.1 | 0.012 | 8.896 | -11.74 | -11.83 |
| CV-2010A | 5/5/2026 1:03:57 PM | 146.5 | -1.94 | -1.94 | 11.0 | 9.8 | 0.348 | 0.275 | -10.88 | -11.65 |
| CV-2010A | 5/5/2026 1:03:17 PM | 146.3 | -1.85 | -1.89 | 8.7 | 13.1 | 0.215 | 0.493 | -11.24 | -11.37 |
| CV-2010A | 5/4/2026 1:29:04 PM | 148.2 | -0.10 | -0.10 | 16.9 | 17.7 | 0.816 | 0.894 | -12.87 | -13.21 |
| CV-2010A | 5/4/2026 1:27:58 PM | 148.1 | -0.20 | -0.21 | 14.5 | 14.6 | 0.600 | 0.605 | -13.13 | -13.24 |
| CV-2010A | 5/4/2026 1:26:56 PM | 148.6 | 1.36 | -0.10 | 13.4 | 19.6 | 0.510 | 1.095 | -13.13 | -13.20 |
| CV-2011 | 5/11/2026 3:39:24 PM | 108.1 | -0.31 | -0.30 | 0.0 | 0.0 | -0.014 | -0.012 | -12.72 | |
| CV-2011 | 5/11/2026 3:38:18 PM | 105.7 | 0.48 | -0.18 | 0.0 | 1.7 | -0.020 | 0.004 | -12.31 | |
| CV-2011A | 5/28/2026 8:38:45 AM | 150.4 | -4.82 | -4.96 | 130.9 | 132.4 | 4.809 | 4.927 | 0.27 | 0.29 |
| CV-2011A | 5/27/2026 3:15:12 PM | 148.0 | -1.15 | -1.14 | 47.9 | 47.5 | 0.634 | 0.623 | -3.04 | -3.15 |
| CV-2011A | 5/27/2026 3:14:19 PM | 147.7 | -0.62 | -1.13 | 49.1 | 47.7 | 0.664 | 0.628 | -3.51 | -3.05 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2011A | 5/21/2026 9:16:00 AM | 151.7 | -4.56 | -4.52 | 24.0 | 22.5 | 0.160 | 0.141 | -6.65 | -6.38 |
| CV-2011A | 5/20/2026 8:33:37 AM | 151.6 | -7.72 | -7.72 | 20.3 | 18.9 | 0.283 | 0.247 | -12.73 | -11.91 |
| CV-2011A | 5/20/2026 8:30:13 AM | 151.7 | -7.72 | -7.73 | 19.5 | 20.1 | 0.263 | 0.279 | -11.84 | -12.06 |
| CV-2011A | 5/14/2026 9:40:27 AM | 153.6 | -2.67 | -2.53 | 175.1 | 169.1 | 8.637 | 8.049 | -12.33 | -11.47 |
| CV-2011A | 5/11/2026 10:58:37 AM | 153.9 | -1.57 | -1.56 | 41.3 | 41.0 | 0.472 | 0.466 | -11.42 | -11.44 |
| CV-2011A | 5/4/2026 8:20:00 AM | | | | | | | | | |
| CV-2011A | 5/4/2026 8:20:00 AM | | | | | | | | | |
| CV-2011A | 5/4/2026 8:19:12 AM | 151.7 | -2.86 | -2.86 | 32.7 | 31.0 | 0.295 | 0.266 | -13.16 | -13.19 |
| CV-2012 | 5/11/2026 3:24:22 PM | 136.9 | -3.75 | -3.75 | 7.6 | 7.7 | 0.080 | 0.082 | -10.91 | |
| CV-2012 | 5/11/2026 3:23:03 PM | 137.3 | -5.88 | -4.36 | 13.0 | 6.2 | 0.235 | 0.053 | -10.83 | |
| CV-2201-PLR | 5/19/2026 11:02:27 AM | 130.4 | -0.73 | -0.71 | | | 0.503 | 0.507 | -2.13 | -2.18 |
| CV-2201-PLR | 5/19/2026 10:46:55 AM | 130.5 | -0.77 | -0.47 | | | 0.684 | 0.419 | -1.67 | -1.74 |
| CV-2201-PLR | 5/13/2026 1:54:50 PM | 133.1 | -0.96 | -0.97 | | | 0.940 | 0.949 | -2.53 | -1.90 |
| CV-2201-PLR | 5/13/2026 1:53:35 PM | 133.2 | -1.08 | -0.80 | | | 1.008 | 0.772 | -2.56 | -2.66 |
| CV-2204-PLR | 5/26/2026 1:23:17 PM | 155.6 | -7.79 | -7.07 | | | 7.904 | 7.098 | 0.71 | 0.67 |
| CV-2204-PLR | 5/18/2026 11:00:00 AM | | | | | | | | | |
| CV-2204-PLR | 5/18/2026 10:51:06 AM | 189.1 | -2.25 | -2.22 | | | 2.310 | 2.305 | 0.35 | 0.35 |
| CV-2204-PLR | 5/12/2026 10:45:00 AM | | | | | | | | | |
| CV-2204-PLR | 5/12/2026 10:44:05 AM | 190.0 | -7.01 | -7.28 | | | 7.123 | 7.387 | 0.34 | 0.34 |
| CV-2204-PLR | 5/5/2026 9:48:20 AM | 190.1 | -7.29 | -8.83 | | | 7.395 | 8.865 | 0.01 | 0.00 |
| CV-2204-PLR | 5/5/2026 9:45:00 AM | | | | | | | | | |
| CV-2204-PLR | 5/5/2026 9:45:00 AM | | | | | | | | | |
| CV-2205 | 5/1/2026 2:09:09 PM | | -0.36 | -0.36 | 15.9 | 15.9 | 0.065 | 0.065 | -12.64 | -12.64 |
| CV-2207 | 5/11/2026 1:42:35 PM | 125.0 | -0.94 | -0.56 | 18.1 | 16.1 | 0.083 | 0.066 | -8.87 | |
| CV-2207 | 5/11/2026 1:19:38 PM | 127.2 | -1.08 | -1.02 | 8.3 | 11.2 | 0.018 | 0.033 | 0.64 | 0.61 |
| CV-2208A | 5/11/2026 11:49:32 AM | 134.0 | -1.31 | -1.32 | 12.2 | 12.3 | 0.043 | 0.044 | -6.59 | |
| CV-2208A | 5/11/2026 11:47:10 AM | 134.7 | -1.27 | -1.27 | 13.3 | 13.5 | 0.050 | 0.052 | -6.64 | |
| CV-2301 | 5/27/2026 10:38:04 AM | 158.0 | -2.47 | -2.44 | | | 2.434 | 2.430 | -6.22 | -6.32 |
| CV-2301 | 5/27/2026 10:36:57 AM | 158.0 | -4.82 | -1.81 | | | 4.791 | 1.802 | -6.24 | -6.22 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2301 | 5/19/2026 10:16:23 AM | | -5.72 | | | | 5.799 | | -6.88 | |
| CV-2301 | 5/19/2026 10:15:36 AM | 165.0 | -7.06 | -5.74 | | | 7.053 | 5.875 | -6.74 | -6.82 |
| CV-2301 | 5/19/2026 10:15:00 AM | | | | | | | | | |
| CV-2301 | 5/14/2026 11:20:00 AM | | | | | | | | | |
| CV-2301 | 5/14/2026 10:53:50 AM | 182.0 | -7.32 | -7.34 | | | 7.376 | 7.366 | -7.59 | -7.56 |
| CV-2301 | 5/14/2026 10:52:08 AM | 182.0 | -7.30 | -7.24 | | | 7.276 | 7.189 | -7.47 | -7.33 |
| CV-2301 | 5/7/2026 7:55:00 AM | | | | | | | | | |
| CV-2301 | 5/7/2026 7:55:00 AM | | | | | | | | | |
| CV-2302 | 5/22/2026 3:57:06 PM | 121.0 | -5.04 | -5.07 | | | 5.135 | 5.088 | -5.32 | -5.35 |
| CV-2302 | 5/7/2026 8:05:00 AM | | | | | | | | | |
| CV-2302 | 5/7/2026 8:05:00 AM | | | | | | | | | |
| CV-2302 | 5/4/2026 9:06:38 AM | 121.6 | -9.44 | -9.45 | | | 9.620 | 9.648 | -9.66 | -9.82 |
| CV-2303 | 5/27/2026 9:02:45 AM | 179.8 | -2.09 | -2.13 | | | 2.014 | 2.067 | 0.01 | 0.01 |
| CV-2303 | 5/19/2026 8:40:00 AM | | | | | | | | | |
| CV-2303 | 5/19/2026 8:36:23 AM | 187.5 | -4.52 | -4.52 | | | 4.498 | 4.501 | -4.26 | -4.28 |
| CV-2303 | 5/13/2026 2:13:55 PM | 190.0 | -4.70 | -4.13 | | | 4.721 | 4.208 | -4.68 | -4.07 |
| CV-2303 | 5/12/2026 8:30:00 AM | | | | | | | | | |
| CV-2303 | 5/12/2026 8:30:00 AM | | | | | | | | | |
| CV-2303 | 5/5/2026 2:25:00 PM | | | | | | | | | |
| CV-2303 | 5/5/2026 2:25:00 PM | | | | | | | | | |
| CV-2303 | 5/5/2026 2:21:44 PM | 187.7 | -3.85 | -3.77 | | | 3.847 | 3.710 | 0.27 | 0.30 |
| CV-2304 | 5/19/2026 9:15:00 AM | | | | | | | | | |
| CV-2304 | 5/19/2026 9:14:49 AM | 168.5 | -2.38 | -2.51 | | | 2.314 | 2.356 | 0.34 | 0.34 |
| CV-2304 | 5/13/2026 3:03:41 PM | 163.9 | -5.65 | -5.66 | | | 5.854 | 5.852 | 0.00 | 0.00 |
| CV-2304 | 5/13/2026 3:02:59 PM | 161.2 | -7.61 | -5.44 | | | 7.765 | 5.595 | 0.00 | 0.00 |
| CV-2304 | 5/8/2026 12:51:34 PM | 169.9 | -5.70 | -5.54 | | | 5.691 | 5.519 | 0.00 | 0.00 |
| CV-2304 | 5/8/2026 12:50:06 PM | 167.5 | -5.71 | -5.43 | | | 5.760 | 5.433 | -5.64 | 0.00 |
| CV-2304 | 5/6/2026 3:00:04 PM | 163.7 | 11.07 | 11.19 | | | 0.000 | 0.000 | 11.51 | 11.50 |
| CV-2304 | 5/6/2026 3:00:00 PM | | | | | | | | | |
| CV-2304 | 5/6/2026 3:00:00 PM | | | | | | | | | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2304 | 5/6/2026 2:59:41 PM | 163.1 | 11.46 | 11.51 | | | 0.000 | 0.000 | 11.63 | 11.66 |
| CV-2305 | 5/27/2026 2:24:19 PM | 149.4 | 2.23 | 2.20 | | | 0.000 | 0.000 | 2.14 | 2.09 |
| CV-2305 | 5/27/2026 2:23:44 PM | 149.3 | 2.27 | 1.95 | | | 0.000 | 0.000 | 2.18 | 2.16 |
| CV-2305 | 5/19/2026 1:20:00 PM | | | | | | | | | |
| CV-2305 | 5/19/2026 1:19:18 PM | 149.2 | -0.17 | -0.60 | | | 0.119 | 0.826 | -0.74 | -1.01 |
| CV-2305 | 5/14/2026 10:11:00 AM | | | | | | | | | |
| CV-2305 | 5/14/2026 10:09:35 AM | 150.3 | -1.47 | -1.47 | | | 1.475 | 1.475 | -1.89 | -1.89 |
| CV-2305 | 5/12/2026 8:10:00 AM | | | | | | | | | |
| CV-2305 | 5/12/2026 8:10:00 AM | | | | | | | | | |
| CV-2305 | 5/4/2026 8:50:00 AM | 149.9 | -1.66 | -1.01 | | | 1.681 | 1.122 | -1.61 | -1.69 |
| CV-2306 | 5/26/2026 1:28:47 PM | 149.1 | -8.35 | -8.35 | | | 8.434 | 8.434 | 0.99 | 0.99 |
| CV-2306 | 5/18/2026 11:00:16 AM | 133.9 | -4.06 | -4.67 | | | 4.078 | 4.575 | 0.34 | 0.35 |
| CV-2306 | 5/18/2026 10:56:22 AM | 102.9 | -3.87 | -4.19 | | | 4.155 | 4.690 | 0.42 | 0.34 |
| CV-2306 | 5/12/2026 10:50:18 AM | 178.3 | -9.29 | -9.23 | | | 9.437 | 9.385 | 0.33 | 0.33 |
| CV-2306 | 5/12/2026 10:50:00 AM | | | | | | | | | |
| CV-2306 | 5/5/2026 9:52:13 AM | 173.6 | -9.33 | -9.36 | | | 9.490 | 9.527 | 0.00 | 0.00 |
| CV-2306 | 5/5/2026 9:50:00 AM | | | | | | | | | |
| CV-2306 | 5/5/2026 9:50:00 AM | | | | | | | | | |
| CV-2308-PLR | 5/19/2026 10:58:26 AM | 136.5 | -1.76 | -1.81 | | | 1.750 | 1.724 | -4.15 | -4.72 |
| CV-2308-PLR | 5/19/2026 10:56:56 AM | 133.9 | -2.27 | -1.43 | | | 2.121 | 1.440 | -4.38 | -4.16 |
| CV-2308-PLR | 5/13/2026 2:03:12 PM | 143.9 | -1.71 | -1.66 | | | 1.608 | 1.593 | -3.86 | -3.96 |
| CV-2308-PLR | 5/13/2026 2:01:38 PM | 146.4 | -3.18 | -1.58 | | | 3.087 | 1.533 | -3.98 | -4.25 |
| CV-2310-PLR | 5/27/2026 9:22:17 AM | 196.1 | -1.24 | -1.24 | | | 1.216 | 1.216 | 0.19 | 0.19 |
| CV-2310-PLR | 5/19/2026 8:56:41 AM | 197.9 | -0.21 | -2.46 | | | 0.099 | 2.350 | 0.34 | 0.34 |
| CV-2310-PLR | 5/19/2026 8:55:00 AM | | | | | | | | | |
| CV-2310-PLR | 5/13/2026 2:22:47 PM | 197.5 | -1.78 | -2.08 | | | 1.813 | 2.337 | -0.04 | 0.00 |
| CV-2310-PLR | 5/6/2026 2:40:00 PM | | | | | | | | | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2310-PLR | 5/6/2026 2:30:00 PM | | | | | | | | | |
| CV-2310-PLR | 5/6/2026 2:26:12 PM | 197.3 | -1.08 | -2.54 | | | 1.010 | 2.676 | 0.08 | 0.00 |
| CV-2310-PLR | 5/1/2026 11:45:33 AM | 197.2 | -4.35 | -4.06 | | | 4.114 | 3.201 | 0.67 | 0.65 |
| CV-2310-PLR | 5/1/2026 11:44:42 AM | 197.3 | -4.23 | -4.10 | | | 4.033 | 4.799 | 0.65 | 0.69 |
| CV-2311 | 5/26/2026 2:01:48 PM | 162.4 | -3.39 | -3.36 | | | 3.396 | 3.358 | 0.86 | 0.83 |
| CV-2311 | 5/18/2026 2:25:36 PM | 183.3 | -3.81 | -3.81 | | | 3.993 | 3.993 | 0.33 | 0.33 |
| CV-2311 | 5/18/2026 2:25:00 PM | | | | | | | | | |
| CV-2311 | 5/18/2026 2:24:18 PM | 163.7 | 4.39 | 4.34 | | | 0.000 | 0.000 | 2.33 | 2.31 |
| CV-2311 | 5/12/2026 2:05:46 PM | 165.1 | -1.78 | -1.81 | | | 1.722 | 1.717 | -7.19 | -6.93 |
| CV-2311 | 5/12/2026 2:03:19 PM | 163.6 | -2.48 | -2.01 | | | 2.409 | 1.934 | -7.09 | -7.20 |
| CV-2311 | 5/12/2026 2:00:00 PM | | | | | | | | | |
| CV-2311 | 5/5/2026 10:25:04 AM | 166.9 | -2.53 | -2.52 | | | 2.525 | 2.518 | -8.39 | -8.32 |
| CV-2311 | 5/5/2026 10:25:00 AM | | | | | | | | | |
| CV-2311 | 5/5/2026 10:25:00 AM | | | | | | | | | |
| CV-2312 | 5/27/2026 11:01:39 AM | 167.7 | -3.07 | -5.30 | 31.2 | 41.4 | 2.922 | 5.179 | -3.98 | -4.28 |
| CV-2312 | 5/19/2026 10:35:25 AM | 168.5 | -2.64 | -1.13 | 34.1 | 14.8 | 3.468 | 0.647 | -5.08 | -3.40 |
| CV-2312 | 5/19/2026 10:35:00 AM | | | | | | | | | |
| CV-2312 | 5/13/2026 11:08:10 AM | 169.3 | -16.73 | -16.28 | 73.7 | 72.9 | 17.149 | 16.742 | -7.70 | -6.29 |
| CV-2312 | 5/13/2026 9:06:06 AM | 168.2 | -6.54 | -4.12 | 46.2 | 35.3 | 6.431 | 3.725 | -8.03 | -8.48 |
| CV-2312 | 5/13/2026 8:30:00 AM | | | | | | | | | |
| CV-2312 | 5/13/2026 8:30:00 AM | | | | | | | | | |
| CV-2312 | 5/4/2026 10:29:04 AM | 168.0 | 27.20 | 23.82 | 97.2 | 90.7 | 27.050 | 23.636 | -8.85 | -9.06 |
| CV-2312 | 5/4/2026 10:27:12 AM | 168.1 | 23.02 | 25.84 | 89.1 | 94.9 | 22.809 | 25.782 | -9.17 | -9.23 |
| CV-2312 | 5/4/2026 10:15:00 AM | | | | | | | | | |
| CV-2312 | 5/4/2026 10:15:00 AM | | | | | | | | | |
| CV-2314 | 5/27/2026 1:46:16 PM | 179.8 | -3.66 | -3.61 | | | 3.627 | 3.552 | -7.85 | -7.78 |
| CV-2314 | 5/27/2026 1:45:46 PM | 179.5 | -0.26 | -3.78 | | | 0.286 | 3.790 | -7.67 | -7.11 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2314 | 5/19/2026 2:00:00 PM | | | | | | | | | |
| CV-2314 | 5/19/2026 1:53:23 PM | 180.1 | -3.30 | -3.03 | | | 3.257 | 3.147 | 0.00 | 0.00 |
| CV-2314 | 5/14/2026 1:50:56 PM | 178.0 | -2.53 | -2.89 | 0.0 | 0.0 | 2.499 | 2.861 | -11.70 | |
| CV-2314 | 5/14/2026 1:49:32 PM | 178.0 | -8.65 | -2.73 | 0.0 | 0.0 | 8.764 | 2.495 | -11.53 | |
| CV-2314 | 5/12/2026 8:05:00 AM | | | | | | | | | |
| CV-2314 | 5/12/2026 8:05:00 AM | | | | | | | | | |
| CV-2314 | 5/11/2026 10:32:15 AM | 180.2 | -2.16 | -1.11 | | | 2.126 | 1.008 | -13.13 | -14.46 |
| CV-2314 | 5/4/2026 9:40:25 AM | 178.1 | -2.93 | -2.18 | | | 2.960 | 2.480 | -13.31 | -13.49 |
| CV-2314 | 5/4/2026 9:40:00 AM | | | | | | | | | |
| CV-2314 | 5/4/2026 9:40:00 AM | | | | | | | | | |
| CV-2315 | 5/26/2026 10:35:23 AM | 182.5 | -5.71 | -5.70 | | | 5.715 | 5.794 | 0.34 | 0.36 |
| CV-2315 | 5/19/2026 1:35:00 PM | | | | | | | | | |
| CV-2315 | 5/19/2026 1:31:37 PM | 184.8 | -1.16 | -1.16 | | | 1.126 | 1.126 | 0.00 | 0.00 |
| CV-2315 | 5/13/2026 1:43:34 PM | 178.3 | -2.68 | -2.67 | | | 2.600 | 2.574 | -3.16 | -3.11 |
| CV-2315 | 5/13/2026 1:42:47 PM | 177.7 | -2.57 | -3.27 | | | 2.444 | 3.279 | -3.13 | -3.76 |
| CV-2315 | 5/11/2026 8:41:37 AM | 156.4 | 0.34 | 0.79 | | | 0.000 | 0.000 | 1.38 | 1.90 |
| CV-2315 | 5/7/2026 8:30:00 AM | | | | | | | | | |
| CV-2315 | 5/7/2026 8:30:00 AM | | | | | | | | | |
| CV-2315 | 5/6/2026 3:30:00 PM | | | | | | | | | |
| CV-2315 | 5/6/2026 3:30:00 PM | | | | | | | | | |
| CV-2315 | 5/6/2026 3:27:40 PM | 183.9 | -2.69 | -2.61 | | | 2.781 | 2.680 | -4.69 | -4.54 |
| CV-2315 | 5/6/2026 3:25:58 PM | 183.9 | -0.26 | -1.85 | | | 0.284 | 1.822 | -5.72 | -4.32 |
| CV-2316 | 5/11/2026 1:59:13 PM | 142.0 | -0.67 | -0.67 | 11.4 | 11.4 | 0.100 | 0.100 | -4.74 | |
| CV-2316 | 5/11/2026 1:57:51 PM | 141.7 | -0.66 | -0.66 | 11.5 | 11.5 | 0.100 | 0.100 | -5.16 | |
| CV-2319 | 5/12/2026 8:28:11 AM | 142.0 | -0.48 | -0.47 | 0.0 | 0.0 | | | -11.34 | |
| CV-2319 | 5/12/2026 8:26:00 AM | 142.0 | -0.51 | -0.45 | 0.0 | 0.0 | | | -11.08 | |
| CV-2321 | 5/27/2026 2:51:44 PM | 145.7 | -3.34 | -3.32 | | | 0.374 | 0.314 | -9.07 | -9.07 |
| CV-2321 | 5/27/2026 2:50:12 PM | 145.8 | -4.11 | -2.31 | | | 1.105 | 0.702 | -9.07 | -9.07 |
| CV-2321 | 5/19/2026 1:00:00 PM | | | | | | | | | |
| CV-2321 | 5/19/2026 12:59:11 PM | 149.0 | -1.10 | -1.07 | | | 0.071 | 0.084 | -6.36 | -6.22 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2321 | 5/19/2026 12:56:22 PM | 148.9 | 2.31 | -2.14 | 53.5 | 5.1 | 8.196 | 0.074 | -6.06 | -5.52 |
| CV-2321 | 5/11/2026 9:19:14 AM | 146.6 | -2.88 | -2.79 | 65.7 | 66.0 | 12.614 | 12.724 | -15.85 | -15.37 |
| CV-2321 | 5/11/2026 9:16:26 AM | 146.2 | -13.09 | -1.90 | | | 2.309 | 13.293 | -15.13 | -15.92 |
| CV-2321 | 5/7/2026 9:50:36 AM | 149.3 | -2.94 | -2.94 | | | 0.337 | 0.342 | -7.77 | -7.77 |
| CV-2321 | 5/7/2026 9:50:00 AM | | | | | | | | | |
| CV-2321 | 5/7/2026 9:50:00 AM | | | | | | | | | |
| CV-2321 | 5/7/2026 9:49:06 AM | 149.3 | 2.87 | -2.50 | 57.0 | 5.5 | 9.304 | 0.088 | -5.20 | -7.39 |
| CV-2321 | 5/1/2026 10:23:30 AM | 147.7 | -0.16 | -0.15 | | | | | -13.29 | |
| CV-2321 | 5/1/2026 10:20:34 AM | 147.8 | 0.14 | -0.14 | | | | | -13.21 | |
| CV-2322 | 5/26/2026 9:22:23 AM | 60.6 | -5.96 | -5.96 | | | 6.023 | 6.017 | 0.09 | 0.08 |
| CV-2322 | 5/4/2026 1:40:46 PM | 138.7 | -8.58 | -8.35 | | | 8.534 | 8.316 | -0.30 | -0.34 |
| CV-2324 | 5/6/2026 2:05:45 PM | 118.4 | -0.10 | -0.10 | 12.0 | 12.2 | 0.092 | 0.094 | -9.25 | -9.27 |
| CV-2324 | 5/1/2026 11:00:44 AM | 120.9 | -2.28 | -1.17 | 16.3 | 0.0 | 0.165 | -0.040 | -13.37 | |
| CV-2326 | 5/19/2026 10:26:12 AM | 134.2 | -5.62 | -5.41 | | | 6.172 | 5.928 | 0.63 | 0.63 |
| CV-2326 | 5/19/2026 10:25:24 AM | 134.2 | -5.65 | -5.25 | | | 6.202 | 5.855 | 0.63 | 0.62 |
| CV-2326 | 5/1/2026 11:33:29 AM | 124.2 | -7.58 | -7.21 | | | 7.765 | 7.443 | 0.07 | 0.04 |
| CV-2327 | 5/28/2026 1:44:39 PM | 185.6 | -3.56 | -3.52 | | | 3.576 | 3.537 | -6.47 | -6.48 |
| CV-2327 | 5/20/2026 2:15:58 PM | 182.8 | -2.57 | -2.53 | | | 2.461 | 2.370 | -6.03 | -6.05 |
| CV-2327 | 5/14/2026 10:00:04 AM | 181.6 | -2.34 | -2.47 | | | 2.550 | 2.582 | -6.47 | -6.51 |
| CV-2327 | 5/14/2026 9:57:08 AM | 181.6 | -6.87 | -4.24 | | | 6.955 | 4.245 | 0.34 | 0.34 |
| CV-2327 | 5/14/2026 9:50:00 AM | | | | | | | | | |
| CV-2327 | 5/4/2026 1:23:07 PM | 185.7 | -7.67 | -7.76 | | | 7.701 | 7.744 | -0.13 | -0.25 |
| CV-2327 | 5/4/2026 1:20:00 PM | | | | | | | | | |
| CV-2327 | 5/4/2026 1:20:00 PM | | | | | | | | | |
| CV-2328 | 5/28/2026 1:37:05 PM | 164.9 | -3.56 | -3.67 | 41.3 | 41.8 | 4.346 | 4.447 | -8.49 | -8.86 |
| CV-2328 | 5/20/2026 2:06:30 PM | 167.3 | -1.36 | -1.29 | 44.5 | 42.0 | 5.048 | 4.500 | -6.96 | -7.10 |
| CV-2328 | 5/20/2026 2:05:13 PM | 167.4 | -0.64 | -1.43 | 42.2 | 45.5 | 4.527 | 5.277 | -7.41 | -7.41 |
| CV-2328 | 5/11/2026 1:26:04 PM | 146.7 | -0.54 | -0.53 | 12.0 | 11.7 | 0.351 | 0.333 | -1.24 | -1.21 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2328 | 5/7/2026 8:15:00 AM | | | | | | | | | |
| CV-2328 | 5/7/2026 8:15:00 AM | | | | | | | | | |
| CV-2328 | 5/4/2026 1:07:16 PM | 172.4 | -2.16 | -2.13 | 42.0 | 43.2 | 4.543 | 4.815 | -10.37 | -11.40 |
| CV-2328 | 5/4/2026 1:06:42 PM | 172.4 | 8.45 | -2.28 | 24.9 | 38.5 | 1.538 | 3.814 | -11.61 | -10.53 |
| CV-2328 | 5/4/2026 1:05:00 PM | | | | | | | | | |
| CV-2328 | 5/4/2026 1:05:00 PM | | | | | | | | | |
| CV-2333 | 5/29/2026 9:43:07 AM | 188.5 | -3.29 | -3.45 | 67.4 | 68.9 | 3.259 | 3.408 | -3.28 | -3.68 |
| CV-2333 | 5/26/2026 8:54:11 AM | 170.3 | -2.38 | -2.72 | | | 2.363 | 2.781 | -2.18 | -2.52 |
| CV-2333 | 5/18/2026 9:15:00 AM | | | | | | | | | |
| CV-2333 | 5/18/2026 9:12:06 AM | 158.1 | -1.10 | -0.47 | | | 0.918 | 0.296 | -1.03 | -0.63 |
| CV-2333 | 5/13/2026 7:40:00 AM | | | | | | | | | |
| CV-2333 | 5/13/2026 7:40:00 AM | | | | | | | | | |
| CV-2333 | 5/12/2026 9:35:00 AM | | | | | | | | | |
| CV-2333 | 5/12/2026 9:28:21 AM | 178.1 | -5.29 | -4.99 | | | 5.253 | 4.892 | -4.80 | -4.50 |
| CV-2333 | 5/6/2026 9:45:24 AM | 191.3 | -3.95 | -3.93 | | | 3.700 | 4.121 | -3.32 | -3.65 |
| CV-2333 | 5/6/2026 9:44:40 AM | 191.2 | -3.78 | -3.83 | | | 3.663 | 3.720 | -2.94 | -2.94 |
| CV-2333 | 5/5/2026 8:30:00 AM | | | | | | | | | |
| CV-2333 | 5/5/2026 8:30:00 AM | | | | | | | | | |
| CV-2333 | 5/5/2026 8:26:49 AM | 165.9 | -6.44 | -6.41 | | | 6.272 | 6.226 | -5.79 | -5.75 |
| CV-2334 | 5/26/2026 2:23:32 PM | 127.2 | -1.36 | -1.68 | 2.3 | 7.0 | 0.015 | 0.138 | -1.14 | -1.28 |
| CV-2334 | 5/13/2026 7:45:00 AM | | | | | | | | | |
| CV-2334 | 5/13/2026 7:45:00 AM | | | | | | | | | |
| CV-2335 | 5/19/2026 10:11:09 AM | 92.6 | -1.21 | -1.19 | | | 1.242 | 1.228 | -3.94 | -3.84 |
| CV-2335 | 5/12/2026 10:45:40 AM | 88.9 | -1.53 | -1.51 | 0.0 | 0.0 | 1.577 | 1.564 | -4.57 | |
| CV-2336 | 5/19/2026 10:14:30 AM | 79.7 | -0.11 | -0.12 | | | 0.104 | 0.081 | -5.36 | -5.51 |
| CV-2336 | 5/12/2026 10:27:38 AM | 73.8 | -0.43 | -0.18 | 0.0 | 0.0 | 0.275 | 0.163 | -5.93 | |
| CV-2337 | 5/20/2026 8:23:36 AM | 150.2 | -3.45 | -3.45 | 29.1 | 29.6 | 2.441 | 2.539 | 0.25 | 0.21 |
| CV-2337 | 5/11/2026 2:00:37 PM | 149.4 | -0.74 | -0.82 | 15.6 | 16.7 | 0.699 | 0.796 | 6.97 | 6.97 |
| CV-2337 | 5/11/2026 8:05:00 AM | | | | | | | | | |
| CV-2337 | 5/11/2026 8:05:00 AM | | | | | | | | | |
| CV-2337 | 5/6/2026 9:26:13 AM | 149.9 | -2.47 | -2.48 | 18.7 | 19.1 | 1.006 | 1.040 | -3.11 | -3.14 |
| CV-2337 | 5/6/2026 9:25:00 AM | | | | | | | | | |
| CV-2337 | 5/6/2026 9:25:00 AM | | | | | | | | | |
| CV-2338 | 5/28/2026 8:46:22 AM | 190.5 | -3.58 | -3.60 | | | 3.569 | 3.591 | 0.03 | 0.04 |
| CV-2338 | 5/20/2026 8:15:49 AM | 169.5 | -2.73 | -2.00 | | | 2.779 | 2.031 | 0.00 | 0.00 |
| CV-2338 | 5/12/2026 10:09:33 AM | 168.6 | -1.98 | -1.94 | 0.0 | 0.0 | 2.117 | 1.971 | -2.57 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2338 | 5/12/2026 10:05:03 AM | 188.6 | -1.72 | -1.15 | 0.0 | 0.0 | 1.855 | 1.481 | -2.14 | |
| CV-2338 | 5/11/2026 1:52:50 PM | 172.5 | 0.09 | 0.03 | | | 0.000 | 0.000 | 9.80 | 9.80 |
| CV-2338 | 5/11/2026 1:52:06 PM | 172.5 | 0.72 | 0.72 | | | 0.000 | 0.000 | 9.64 | 9.64 |
| CV-2338 | 5/6/2026 9:15:00 AM | | | | | | | | | |
| CV-2338 | 5/6/2026 9:15:00 AM | | | | | | | | | |
| CV-2338 | 5/6/2026 9:13:21 AM | 155.1 | -2.02 | -2.00 | | | 1.997 | 1.981 | 0.01 | 0.01 |
| CV-2338 | 5/6/2026 9:12:07 AM | 155.3 | -4.99 | -1.81 | | | 4.749 | 1.797 | 0.00 | 0.00 |
| CV-2339 | 5/29/2026 10:41:08 AM | 82.3 | -1.15 | -1.03 | 0.0 | 0.0 | 0.866 | 0.770 | -5.79 | |
| CV-2339 | 5/29/2026 10:39:26 AM | 80.2 | -4.95 | -1.00 | 0.0 | 0.0 | 4.634 | 1.081 | -6.02 | |
| CV-2339 | 5/14/2026 2:06:48 PM | 88.1 | -4.84 | -4.97 | | | 4.999 | 4.873 | -5.64 | -6.42 |
| CV-2339 | 5/14/2026 2:04:49 PM | 88.6 | 118.78 | -4.78 | | | 0.000 | 4.716 | -5.80 | -5.95 |
| CV-2341 | 5/29/2026 10:30:39 AM | 86.4 | -1.16 | -1.13 | 0.0 | 0.0 | 1.062 | 1.064 | -6.04 | |
| CV-2341 | 5/14/2026 1:47:09 PM | 92.1 | -0.94 | -0.93 | | | 0.921 | 0.917 | -5.13 | -5.32 |
| CV-2341 | 5/11/2026 7:50:00 AM | | | | | | | | | |
| CV-2341 | 5/11/2026 7:50:00 AM | | | | | | | | | |
| CV-2342A-PLR | 5/28/2026 1:15:25 PM | 187.8 | -6.59 | -6.65 | | | 6.627 | 6.717 | -6.59 | -6.60 |
| CV-2342A-PLR | 5/20/2026 9:08:28 AM | 168.1 | -6.26 | -6.11 | | | 6.431 | 6.236 | -5.66 | -5.56 |
| CV-2342A-PLR | 5/13/2026 9:52:01 AM | 168.6 | -6.73 | -6.73 | | | 6.799 | 6.754 | -6.40 | -6.38 |
| CV-2342A-PLR | 5/6/2026 10:10:00 AM | 170.2 | -11.74 | -11.62 | | | 4.753 | 4.753 | 0.31 | 0.32 |
| CV-2343 | 5/26/2026 2:33:45 PM | 132.2 | -7.97 | -7.99 | | | 8.064 | 8.091 | 0.21 | 0.21 |
| CV-2343 | 5/19/2026 2:04:37 PM | 175.4 | -4.36 | -4.32 | | | 4.335 | 4.345 | -4.86 | -4.73 |
| CV-2343 | 5/19/2026 2:03:22 PM | 177.0 | -4.24 | -4.15 | | | 4.260 | 4.021 | -4.70 | -4.77 |
| CV-2343 | 5/6/2026 9:56:02 AM | 143.0 | -7.81 | -7.84 | | | 4.753 | 4.753 | 0.31 | 0.32 |
| CV-2344 | 5/20/2026 8:51:25 AM | 141.9 | -6.82 | -6.73 | | | 6.842 | 6.799 | -7.55 | -7.52 |
| CV-2344 | 5/13/2026 9:31:33 AM | 146.1 | -5.39 | -5.33 | | | 5.158 | 5.112 | -7.71 | -7.64 |
| CV-2344 | 5/13/2026 9:30:38 AM | 147.2 | -8.12 | -5.43 | | | 8.076 | 5.329 | -7.90 | -7.79 |
| CV-2344 | 5/11/2026 7:35:00 AM | | | | | | | | | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2344 | 5/11/2026 7:35:00 AM | | | | | | | | | |
| CV-2344 | 5/6/2026 9:52:20 AM | 157.4 | -8.39 | -8.35 | | | 4.753 | 4.753 | 0.30 | 0.34 |
| CV-2344 | 5/6/2026 9:50:00 AM | | | | | | | | | |
| CV-2344 | 5/6/2026 9:50:00 AM | | | | | | | | | |
| CV-2345 | 5/19/2026 2:17:28 PM | 142.7 | -0.14 | -0.12 | | | 0.159 | 0.150 | -4.50 | -4.34 |
| CV-2345 | 5/19/2026 2:15:18 PM | 143.5 | 0.40 | -0.05 | | | 0.000 | 0.058 | -4.66 | -4.46 |
| CV-2345 | 5/11/2026 7:30:00 AM | | | | | | | | | |
| CV-2345 | 5/11/2026 7:30:00 AM | | | | | | | | | |
| CV-2345 | 5/1/2026 10:20:11 AM | 138.4 | -0.71 | -0.71 | | | 0.707 | 0.706 | 0.36 | 0.36 |
| CV-2345 | 5/1/2026 10:19:42 AM | 138.2 | -0.71 | -0.68 | | | 0.708 | 0.674 | 0.50 | 0.39 |
| CV-2346 | 5/28/2026 9:28:07 AM | 186.9 | -8.63 | -8.69 | | | 8.630 | 8.688 | -9.37 | -9.36 |
| CV-2346 | 5/20/2026 8:47:59 AM | 184.4 | -5.63 | -5.72 | | | 5.602 | 5.722 | -7.17 | -7.48 |
| CV-2346 | 5/13/2026 9:20:50 AM | 182.1 | -1.84 | -1.95 | | | 1.850 | 1.966 | -7.41 | -7.20 |
| CV-2346 | 5/6/2026 9:47:10 AM | 182.2 | -3.78 | -3.77 | | | 3.748 | 3.734 | -6.82 | -6.71 |
| CV-2346 | 5/6/2026 9:45:00 AM | | | | | | | | | |
| CV-2346 | 5/6/2026 9:45:00 AM | | | | | | | | | |
| CV-2346 | 5/6/2026 8:25:00 AM | | | | | | | | | |
| CV-2346 | 5/6/2026 8:25:00 AM | | | | | | | | | |
| CV-2346 | 5/4/2026 1:29:13 PM | 178.7 | -2.59 | -2.58 | | | 2.537 | 2.469 | -5.77 | -5.75 |
| CV-2346 | 5/4/2026 1:27:19 PM | 179.2 | -2.10 | -2.04 | | | 2.077 | 2.033 | -5.67 | -5.79 |
| CV-2347 | 5/20/2026 8:26:42 AM | 124.3 | -2.67 | -2.69 | | | 2.647 | 2.657 | -7.58 | -7.46 |
| CV-2347 | 5/6/2026 8:20:00 AM | | | | | | | | | |
| CV-2347 | 5/6/2026 8:20:00 AM | | | | | | | | | |
| CV-2347 | 5/1/2026 10:09:08 AM | 116.7 | -2.15 | -2.07 | | | 2.127 | 2.047 | -6.86 | -6.71 |
| CV-2348 | 5/20/2026 8:15:56 AM | 108.3 | -7.53 | -7.47 | | | 7.779 | 7.724 | 0.03 | 0.03 |
| CV-2348 | 5/13/2026 12:35:31 PM | 128.8 | -3.81 | -3.82 | 0.0 | 0.0 | 3.808 | 3.809 | -5.97 | |
| CV-2348 | 5/6/2026 8:15:00 AM | | | | | | | | | |
| CV-2348 | 5/6/2026 8:15:00 AM | | | | | | | | | |
| CV-2349 | 5/28/2026 10:20:04 AM | 172.5 | -1.12 | -0.52 | | | 1.107 | 0.372 | -1.79 | -1.26 |
| CV-2349 | 5/20/2026 10:27:38 AM | 163.1 | -2.00 | -2.00 | | | 2.287 | 2.251 | -0.29 | -0.29 |
| CV-2349 | 5/13/2026 10:48:12 AM | 150.2 | -0.05 | -0.13 | | | 0.000 | 0.205 | 0.13 | -0.34 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2349 | 5/7/2026 11:16:23 AM | 147.7 | 0.29 | 0.40 | | | 0.000 | 0.000 | 0.33 | 0.34 |
| CV-2349 | 5/7/2026 11:15:19 AM | 147.8 | 0.27 | 0.59 | | | 0.000 | 0.000 | 0.33 | 0.34 |
| CV-2349 | 5/7/2026 11:15:00 AM | | | | | | | | | |
| CV-2349 | 5/7/2026 11:15:00 AM | | | | | | | | | |
| CV-2349 | 5/5/2026 8:25:00 AM | | | | | | | | | |
| CV-2349 | 5/5/2026 8:25:00 AM | | | | | | | | | |
| CV-2350 | 5/20/2026 10:03:44 AM | 112.1 | -4.09 | -4.05 | | | 4.103 | 3.992 | -4.09 | -4.08 |
| CV-2350 | 5/13/2026 12:57:10 PM | 116.4 | -0.49 | -1.29 | 0.0 | 0.0 | 0.524 | 1.059 | -3.38 | |
| CV-2350 | 5/13/2026 12:56:01 PM | 116.6 | 8.91 | -3.00 | 0.0 | 0.0 | -8.618 | 2.220 | -3.98 | |
| CV-2350 | 5/11/2026 7:40:00 AM | | | | | | | | | |
| CV-2350 | 5/11/2026 7:40:00 AM | | | | | | | | | |
| CV-2351 | 5/28/2026 9:25:03 AM | 77.5 | -6.12 | -6.08 | | | 6.525 | 6.308 | -5.97 | -5.30 |
| CV-2351 | 5/28/2026 9:24:00 AM | 65.4 | -6.82 | -6.66 | | | 7.176 | 6.961 | -6.76 | -6.67 |
| CV-2351 | 5/5/2026 7:50:00 AM | | | | | | | | | |
| CV-2351 | 5/5/2026 7:50:00 AM | | | | | | | | | |
| CV-2351 | 5/1/2026 9:05:14 AM | 77.5 | -6.60 | -6.39 | | | 6.687 | 6.457 | -6.56 | -6.21 |
| CV-2352 | 5/28/2026 9:16:38 AM | 108.9 | -0.77 | -0.76 | | | 0.752 | 0.747 | -6.25 | -6.44 |
| CV-2352 | 5/28/2026 9:12:47 AM | 97.8 | -5.81 | -2.75 | | | 6.088 | 2.734 | -6.36 | -6.28 |
| CV-2352 | 5/5/2026 8:00:00 AM | | | | | | | | | |
| CV-2352 | 5/5/2026 8:00:00 AM | | | | | | | | | |
| CV-2352 | 5/1/2026 9:13:24 AM | 116.7 | -0.02 | -5.72 | | | 0.000 | 5.794 | -6.40 | -6.63 |
| CV-2353-PLR | 5/20/2026 9:13:57 AM | 131.5 | -5.36 | -5.36 | | | 5.452 | 5.458 | -5.45 | -5.40 |
| CV-2353-PLR | 5/20/2026 9:13:10 AM | 131.4 | -5.82 | -5.04 | | | 5.928 | 5.201 | -5.65 | -5.64 |
| CV-2353-PLR | 5/15/2026 8:29:12 AM | 147.9 | -6.86 | -6.79 | | | 7.058 | 7.011 | -7.01 | -6.98 |
| CV-2353-PLR | 5/15/2026 8:27:25 AM | 149.2 | -7.01 | -6.99 | | | 7.162 | 7.127 | -6.87 | -6.76 |
| CV-2353-PLR | 5/14/2026 8:40:00 AM | | | | | | | | | |
| CV-2353-PLR | 5/12/2026 7:35:00 AM | | | | | | | | | |
| CV-2353-PLR | 5/12/2026 7:35:00 AM | | | | | | | | | |
| CV-2354 | 5/28/2026 10:36:46 AM | 183.9 | -0.52 | -0.52 | | | 0.502 | 0.502 | -2.81 | -2.81 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2354 | 5/20/2026 10:42:07 AM | 180.2 | 1.88 | 1.91 | | | 0.000 | 0.000 | -0.10 | -0.46 |
| CV-2354 | 5/20/2026 10:40:36 AM | 178.6 | 1.82 | 1.87 | | | 0.000 | 0.000 | 0.29 | -0.11 |
| CV-2354 | 5/13/2026 11:03:49 AM | 167.4 | -1.06 | -1.11 | | | 1.021 | 1.091 | -2.62 | -2.74 |
| CV-2354 | 5/13/2026 11:01:08 AM | 166.8 | -0.98 | -0.98 | | | 0.980 | 0.901 | -2.75 | -2.98 |
| CV-2354 | 5/6/2026 10:50:20 AM | 175.3 | -3.33 | -3.39 | | | 3.289 | 3.344 | 0.34 | 0.32 |
| CV-2354 | 5/6/2026 10:50:00 AM | | | | | | | | | |
| CV-2354 | 5/6/2026 10:50:00 AM | | | | | | | | | |
| CV-2354 | 5/5/2026 8:20:00 AM | | | | | | | | | |
| CV-2354 | 5/5/2026 8:20:00 AM | | | | | | | | | |
| CV-24001 | 5/19/2026 10:02:44 AM | 90.8 | -1.05 | -1.10 | | | 1.083 | 1.105 | -3.92 | -4.14 |
| CV-24001 | 5/12/2026 10:38:27 AM | 102.6 | -1.40 | -1.41 | 0.0 | 0.0 | 1.501 | 1.497 | | |
| CV-24002 | 5/19/2026 9:53:36 AM | 89.1 | -0.13 | -0.15 | | | 0.094 | 0.064 | -5.87 | -5.88 |
| CV-24002 | 5/19/2026 9:51:18 AM | 88.6 | 0.11 | -0.04 | | | 0.000 | 0.023 | -5.90 | -5.88 |
| CV-24002 | 5/1/2026 2:39:31 PM | 93.2 | -0.06 | -0.01 | | | 0.029 | 0.000 | 0.28 | 0.29 |
| CV-24003 | 5/19/2026 9:12:06 AM | 101.3 | -0.41 | -0.43 | 7.2 | 6.8 | 0.031 | 0.028 | -5.97 | -5.97 |
| CV-24003 | 5/1/2026 2:37:02 PM | 101.6 | -0.76 | -0.63 | 12.6 | 8.4 | 0.098 | 0.043 | -6.86 | -6.54 |
| CV-24004 | 5/19/2026 9:02:30 AM | 113.1 | -0.70 | -0.49 | 5.9 | 8.0 | 0.093 | 0.171 | -6.47 | -6.58 |
| CV-24004 | 5/1/2026 2:33:11 PM | 115.3 | -1.05 | -1.05 | 4.7 | 4.8 | 0.059 | 0.063 | -7.35 | -7.39 |
| CV-24006 | 5/19/2026 10:36:49 AM | 127.3 | -0.58 | -0.58 | 11.3 | 11.3 | 0.348 | 0.348 | -2.65 | -2.65 |
| CV-24006 | 5/1/2026 11:40:45 AM | 127.9 | -0.65 | -0.68 | 15.2 | 14.9 | 0.634 | 0.610 | -3.87 | -3.94 |
| CV-24007 | 5/29/2026 9:33:56 AM | 148.2 | -1.32 | -1.34 | 29.9 | 30.7 | 2.551 | 2.693 | -6.72 | -6.61 |
| CV-24007 | 5/26/2026 1:56:22 PM | 150.8 | -1.44 | -1.44 | 25.2 | 25.2 | 1.836 | 1.836 | 0.88 | 0.88 |
| CV-24007 | 5/26/2026 1:55:46 PM | 150.9 | -0.79 | -1.05 | 13.8 | 28.1 | 0.548 | 2.288 | 1.01 | 0.87 |
| CV-24007 | 5/19/2026 10:46:37 AM | 150.7 | -0.16 | -0.16 | 12.4 | 14.7 | 0.436 | 0.618 | -3.26 | -4.40 |
| CV-24007 | 5/19/2026 10:45:21 AM | 150.7 | -0.31 | -0.18 | 16.3 | 13.6 | 0.764 | 0.530 | -3.87 | -3.95 |
| CV-24007 | 5/15/2026 9:10:41 AM | 138.7 | -0.12 | -0.14 | 5.0 | 6.7 | 0.071 | 0.125 | -0.21 | -0.49 |
| CV-24007 | 5/15/2026 9:09:54 AM | 132.4 | 0.04 | -0.02 | 3.5 | 4.7 | 0.035 | 0.062 | -0.36 | 0.04 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24007 | 5/12/2026 8:40:00 AM | | | | | | | | | |
| CV-24007 | 5/12/2026 8:40:00 AM | | | | | | | | | |
| CV-24008 | 5/26/2026 1:50:27 PM | 170.0 | -9.70 | -9.59 | 11.5 | 13.1 | 0.093 | 0.123 | -8.95 | -9.16 |
| CV-24008 | 5/18/2026 2:25:00 PM | | | | | | | | | |
| CV-24008 | 5/18/2026 2:17:05 PM | 170.7 | -4.49 | -3.38 | 81.0 | 71.5 | 4.637 | 3.595 | -4.10 | -3.36 |
| CV-24008 | 5/12/2026 1:41:31 PM | 171.5 | -7.21 | -6.93 | 10.0 | 4.5 | 0.070 | 0.014 | -7.41 | -7.08 |
| CV-24008 | 5/12/2026 1:40:00 PM | | | | | | | | | |
| CV-24008 | 5/5/2026 10:20:00 AM | | | | | | | | | |
| CV-24008 | 5/5/2026 10:20:00 AM | | | | | | | | | |
| CV-24008 | 5/5/2026 10:14:56 AM | 172.4 | -8.88 | -8.90 | 17.4 | 15.6 | 0.214 | 0.172 | -9.66 | -9.68 |
| CV-24009 | 5/26/2026 1:46:14 PM | 155.7 | -6.44 | -6.40 | | | 0.179 | 0.171 | -9.20 | -9.08 |
| CV-24009 | 5/18/2026 2:20:00 PM | | | | | | | | | |
| CV-24009 | 5/18/2026 2:13:29 PM | 155.9 | -1.22 | -1.13 | | | 1.376 | 1.346 | -0.92 | -1.01 |
| CV-24009 | 5/12/2026 1:35:00 PM | | | | | | | | | |
| CV-24009 | 5/12/2026 1:31:36 PM | 156.8 | -3.74 | -3.79 | | | 0.185 | 0.146 | -7.09 | -7.09 |
| CV-24009 | 5/5/2026 10:15:00 AM | | | | | | | | | |
| CV-24009 | 5/5/2026 10:15:00 AM | | | | | | | | | |
| CV-24009 | 5/5/2026 10:10:10 AM | 156.7 | -4.14 | -4.16 | | | 0.221 | 0.207 | -8.98 | -8.80 |
| CV-24010 | 5/26/2026 9:45:36 AM | 61.0 | -4.66 | -4.84 | | | 4.590 | 4.734 | -4.43 | -4.58 |
| CV-24010 | 5/13/2026 1:57:52 PM | 89.2 | -6.88 | -7.43 | | | 6.921 | 7.524 | -6.64 | -7.30 |
| CV-24011 | 5/27/2026 8:51:05 AM | 188.2 | -1.27 | -1.22 | 30.5 | 32.5 | 2.865 | 3.242 | -4.35 | -4.66 |
| CV-24011 | 5/27/2026 8:49:35 AM | 188.3 | -0.73 | -0.88 | 26.2 | 32.8 | 2.112 | 3.312 | -4.49 | -4.37 |
| CV-24011 | 5/19/2026 10:30:22 AM | 186.7 | -0.69 | -0.78 | 27.1 | 28.2 | 2.235 | 2.422 | -5.10 | -5.66 |
| CV-24011 | 5/18/2026 2:55:00 PM | | | | | | | | | |
| CV-24011 | 5/18/2026 2:48:57 PM | 187.7 | -3.47 | -3.70 | 25.6 | 25.9 | 2.010 | 2.065 | 0.46 | 0.34 |
| CV-24011 | 5/12/2026 2:43:10 PM | 185.6 | -1.13 | -1.13 | 30.9 | 31.1 | 2.906 | 2.933 | 0.10 | 0.09 |
| CV-24011 | 5/12/2026 2:25:00 PM | | | | | | | | | |
| CV-24011 | 5/5/2026 1:10:54 PM | 185.1 | -2.55 | -2.53 | 25.1 | 25.1 | 1.925 | 1.923 | -7.21 | -7.17 |
| CV-24011 | 5/5/2026 1:10:00 PM | | | | | | | | | |
| CV-24011 | 5/5/2026 1:10:00 PM | | | | | | | | | |
| CV-24012 | 5/26/2026 2:14:33 PM | 154.3 | -7.03 | -7.03 | | | 7.171 | 7.071 | -0.13 | -0.13 |
| CV-24012 | 5/18/2026 2:56:25 PM | 162.0 | -0.20 | -0.24 | | | 0.177 | 0.207 | 0.24 | 0.25 |
| CV-24012 | 5/18/2026 2:50:00 PM | | | | | | | | | |
| CV-24012 | 5/18/2026 2:41:34 PM | 157.1 | -1.83 | -1.72 | | | 1.810 | 1.802 | 0.28 | 0.34 |
| CV-24012 | 5/12/2026 2:38:30 PM | 173.9 | -4.67 | -4.65 | | | 4.498 | 4.499 | 0.00 | 0.00 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24012 | 5/12/2026 2:20:00 PM | | | | | | | | | |
| CV-24012 | 5/5/2026 1:30:00 PM | | | | | | | | | |
| CV-24012 | 5/5/2026 1:30:00 PM | | | | | | | | | |
| CV-24012 | 5/5/2026 1:26:23 PM | 157.4 | -7.01 | -7.01 | | | 6.757 | 6.745 | 0.00 | 0.00 |
| CV-24013 | 5/26/2026 9:51:46 AM | 92.1 | -0.21 | -0.12 | | | 0.212 | 0.121 | -5.91 | -6.41 |
| CV-24013 | 5/13/2026 10:06:33 AM | 99.1 | -0.34 | -0.31 | | | 0.323 | 0.307 | -7.83 | -8.05 |
| CV-24014 | 5/26/2026 1:42:04 PM | 176.9 | -8.52 | -8.71 | 52.5 | 53.0 | 8.560 | 8.719 | -8.19 | -8.48 |
| CV-24014 | 5/18/2026 2:15:00 PM | | | | | | | | | |
| CV-24014 | 5/18/2026 2:07:26 PM | 176.9 | -0.58 | -0.53 | 18.6 | 28.3 | 1.031 | 2.402 | 0.97 | 2.03 |
| CV-24014 | 5/12/2026 1:30:00 PM | | | | | | | | | |
| CV-24014 | 5/12/2026 1:26:38 PM | 176.2 | -2.90 | -2.01 | 30.3 | 25.4 | 2.757 | 1.930 | -5.00 | -6.80 |
| CV-24014 | 5/12/2026 1:25:28 PM | 176.4 | -3.55 | -1.48 | 33.8 | 21.3 | 3.448 | 1.364 | -5.95 | -5.51 |
| CV-24014 | 5/5/2026 10:10:00 AM | | | | | | | | | |
| CV-24014 | 5/5/2026 10:10:00 AM | | | | | | | | | |
| CV-24014 | 5/5/2026 10:06:41 AM | 176.1 | -3.60 | -3.60 | 34.4 | 34.4 | 3.580 | 3.580 | -6.08 | -6.08 |
| CV-24015 | 5/26/2026 9:48:59 AM | 186.5 | -1.07 | -1.07 | | | 1.074 | 1.071 | -3.23 | -3.32 |
| CV-24015 | 5/18/2026 10:08:30 AM | 183.6 | -0.79 | -0.74 | | | 0.649 | 0.664 | -3.75 | -3.57 |
| CV-24015 | 5/18/2026 10:06:48 AM | 184.2 | 0.47 | -0.96 | | | 0.000 | 0.935 | -4.09 | -4.07 |
| CV-24015 | 5/18/2026 10:05:03 AM | 183.6 | 0.66 | 0.63 | | | 0.000 | 0.000 | 0.29 | 0.33 |
| CV-24015 | 5/18/2026 10:05:00 AM | | | | | | | | | |
| CV-24015 | 5/12/2026 9:01:20 AM | 183.7 | -3.88 | -3.88 | | | 3.844 | 3.843 | -7.97 | -8.00 |
| CV-24015 | 5/12/2026 9:00:00 AM | | | | | | | | | |
| CV-24015 | 5/12/2026 8:59:57 AM | 183.8 | -8.33 | -5.00 | | | 8.403 | 5.082 | -8.44 | -8.31 |
| CV-24015 | 5/5/2026 9:14:20 AM | 170.0 | -8.67 | -8.47 | | | 8.672 | 8.636 | -8.72 | -8.83 |
| CV-24015 | 5/5/2026 9:05:00 AM | | | | | | | | | |
| CV-24015 | 5/5/2026 9:05:00 AM | | | | | | | | | |
| CV-24016 | 5/29/2026 9:27:07 AM | 178.1 | -3.74 | -3.67 | | | 3.685 | 3.614 | -5.13 | -5.11 |
| CV-24016 | 5/27/2026 8:54:06 AM | 171.8 | -2.49 | -2.24 | | | 2.477 | 2.212 | -2.81 | -2.98 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24016 | 5/19/2026 10:04:01 AM | 182.8 | -2.48 | -2.49 | | | 2.449 | 2.395 | -3.65 | -3.81 |
| CV-24016 | 5/19/2026 10:02:01 AM | 182.2 | -2.51 | -2.41 | | | 2.486 | 2.343 | -4.04 | -3.80 |
| CV-24016 | 5/18/2026 3:00:00 PM | | | | | | | | | |
| CV-24016 | 5/18/2026 2:51:00 PM | 169.0 | -2.29 | -2.36 | | | 2.255 | 2.308 | -2.42 | -2.65 |
| CV-24016 | 5/12/2026 2:44:41 PM | 161.1 | -2.53 | -2.50 | | | 2.540 | 2.510 | -6.21 | -6.63 |
| CV-24016 | 5/12/2026 2:30:00 PM | | | | | | | | | |
| CV-24016 | 5/6/2026 1:26:28 PM | 170.1 | -0.10 | -0.10 | | | 0.103 | 0.101 | -2.08 | -2.04 |
| CV-24016 | 5/6/2026 1:25:16 PM | 170.1 | -0.06 | -0.21 | | | 0.074 | 0.215 | -2.08 | -2.16 |
| CV-24016 | 5/5/2026 1:15:29 PM | 163.4 | -2.76 | -2.74 | | | 2.760 | 2.744 | -6.84 | -6.84 |
| CV-24016 | 5/5/2026 1:15:00 PM | | | | | | | | | |
| CV-24016 | 5/5/2026 1:15:00 PM | | | | | | | | | |
| CV-24017 | 5/26/2026 2:08:15 PM | 171.5 | -3.75 | -3.69 | | | 4.049 | 3.793 | 0.21 | 0.21 |
| CV-24017 | 5/26/2026 2:07:20 PM | 172.6 | -7.16 | -5.22 | | | 7.241 | 5.251 | 0.21 | 0.21 |
| CV-24017 | 5/18/2026 2:40:00 PM | | | | | | | | | |
| CV-24017 | 5/18/2026 2:35:18 PM | 170.6 | -2.24 | -2.10 | | | 2.273 | 2.078 | 0.34 | 0.34 |
| CV-24017 | 5/12/2026 2:47:32 PM | 174.6 | -2.11 | -2.05 | | | 2.017 | 1.912 | 0.00 | 0.00 |
| CV-24017 | 5/12/2026 2:25:14 PM | 180.5 | -4.81 | -1.21 | | | 4.666 | 1.101 | -0.05 | -0.02 |
| CV-24017 | 5/12/2026 2:10:00 PM | | | | | | | | | |
| CV-24017 | 5/12/2026 8:35:00 AM | | | | | | | | | |
| CV-24017 | 5/12/2026 8:35:00 AM | | | | | | | | | |
| CV-24017 | 5/5/2026 1:20:00 PM | | | | | | | | | |
| CV-24017 | 5/5/2026 1:20:00 PM | | | | | | | | | |
| CV-24017 | 5/5/2026 1:19:34 PM | 159.6 | -3.14 | -3.12 | | | 3.132 | 3.122 | 0.00 | 0.00 |
| CV-24018 | 5/29/2026 11:06:53 AM | 114.0 | -0.87 | -0.87 | 0.0 | 0.0 | 0.874 | 0.876 | -6.41 | |
| CV-24018 | 5/13/2026 3:41:42 PM | 109.4 | -0.69 | -0.67 | | | 0.703 | 0.665 | -7.07 | -6.05 |
| CV-24019 | 5/27/2026 8:57:49 AM | 171.6 | -2.95 | -2.96 | | | 2.916 | 3.043 | -2.50 | -2.60 |
| CV-24019 | 5/19/2026 8:35:00 AM | | | | | | | | | |
| CV-24019 | 5/19/2026 8:31:39 AM | 168.5 | -4.35 | -4.33 | | | 4.361 | 4.368 | -4.60 | -4.58 |
| CV-24019 | 5/13/2026 2:09:27 PM | 179.5 | -2.41 | -2.95 | | | 2.997 | 3.048 | -3.07 | -3.25 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24019 | 5/5/2026 2:30:00 PM | | | | | | | | | |
| CV-24019 | 5/5/2026 2:30:00 PM | | | | | | | | | |
| CV-24019 | 5/5/2026 2:26:07 PM | 182.5 | -3.66 | -3.76 | | | 3.567 | 3.674 | -3.67 | -3.69 |
| CV-24020 | 5/26/2026 10:31:13 AM | 59.9 | -3.65 | -3.98 | 1.9 | 1.8 | 0.009 | 0.008 | -3.57 | -3.96 |
| CV-24020 | 5/13/2026 1:39:38 PM | 83.0 | -0.64 | -0.74 | 0.5 | 1.2 | 0.001 | 0.004 | -1.33 | -1.03 |
| CV-24021 | 5/26/2026 10:19:45 AM | 62.3 | -2.20 | -2.25 | | | 2.065 | 2.162 | -2.77 | -2.63 |
| CV-24021 | 5/13/2026 10:19:21 AM | 75.7 | -4.87 | -4.74 | | | 5.121 | 5.071 | -4.90 | -5.06 |
| CV-24022-PLR | 5/26/2026 1:34:59 PM | 194.1 | -8.42 | -8.21 | | | 8.257 | 8.035 | 1.01 | 0.90 |
| CV-24022-PLR | 5/18/2026 2:10:00 PM | | | | | | | | | |
| CV-24022-PLR | 5/18/2026 2:04:39 PM | 194.9 | -2.81 | -1.08 | | | 2.700 | 1.305 | 0.34 | 0.34 |
| CV-24022-PLR | 5/12/2026 1:25:00 PM | | | | | | | | | |
| CV-24022-PLR | 5/12/2026 1:18:18 PM | 191.3 | -6.27 | -6.67 | | | 6.041 | 6.412 | -0.18 | -0.34 |
| CV-24022-PLR | 5/5/2026 10:05:00 AM | | | | | | | | | |
| CV-24022-PLR | 5/5/2026 10:05:00 AM | | | | | | | | | |
| CV-24022-PLR | 5/5/2026 10:03:55 AM | 192.3 | -6.02 | -6.12 | | | 6.095 | 6.197 | 0.23 | 0.23 |
| CV-24023 | 5/26/2026 10:02:11 AM | 175.5 | -2.17 | -2.29 | | | 2.157 | 2.273 | 0.67 | 0.67 |
| CV-24023 | 5/26/2026 9:58:22 AM | 167.2 | -5.34 | -3.29 | | | 5.399 | 3.268 | 0.34 | 0.36 |
| CV-24023 | 5/18/2026 10:19:04 AM | 159.0 | -2.05 | -2.52 | | | 2.024 | 2.485 | 0.34 | 0.34 |
| CV-24023 | 5/18/2026 10:15:00 AM | 157.6 | -2.04 | -1.46 | | | 1.990 | 1.458 | 0.34 | 0.36 |
| CV-24023 | 5/12/2026 8:52:20 AM | 181.3 | -7.39 | -7.38 | | | 7.445 | 7.366 | 0.74 | 0.55 |
| CV-24023 | 5/12/2026 8:51:10 AM | 179.8 | -9.09 | -7.68 | | | 9.203 | 7.582 | 0.78 | 0.84 |
| CV-24023 | 5/12/2026 8:50:00 AM | | | | | | | | | |
| CV-24023 | 5/6/2026 9:28:29 AM | 168.5 | -3.01 | -3.00 | | | 2.979 | 2.940 | -2.31 | -2.26 |
| CV-24023 | 5/6/2026 9:27:29 AM | 168.6 | -2.70 | -2.68 | | | 2.672 | 2.642 | -1.97 | -1.93 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24023 | 5/5/2026 9:36:54 AM | 181.2 | -9.52 | -9.49 | | | 9.638 | 9.611 | -9.12 | -9.12 |
| CV-24023 | 5/5/2026 9:35:20 AM | 177.0 | 0.71 | -8.56 | | | 0.000 | 8.648 | -9.01 | -9.03 |
| CV-24023 | 5/5/2026 9:27:58 AM | 157.0 | -9.45 | -9.40 | | | 9.590 | 9.536 | -8.93 | -9.12 |
| CV-24023 | 5/5/2026 9:25:00 AM | | | | | | | | | |
| CV-24023 | 5/5/2026 9:25:00 AM | | | | | | | | | |
| CV-24024-PLR | 5/18/2026 9:51:23 AM | 131.0 | -4.84 | -4.17 | | | 4.856 | 4.210 | -4.45 | -4.03 |
| CV-24024-PLR | 5/15/2026 9:22:07 AM | 157.6 | -8.10 | -8.11 | | | 8.419 | 8.389 | -8.02 | -8.06 |
| CV-24024-PLR | 5/15/2026 9:20:22 AM | 157.0 | -7.92 | -7.85 | | | 8.243 | 8.172 | -7.86 | -7.98 |
| CV-24025 | 5/28/2026 2:28:43 PM | 187.2 | -4.29 | -4.29 | | | 4.298 | 4.294 | 0.00 | 0.00 |
| CV-24025 | 5/19/2026 9:27:53 AM | 186.5 | -1.60 | -1.64 | | | 1.570 | 1.662 | -4.93 | -5.19 |
| CV-24025 | 5/19/2026 9:26:52 AM | 186.3 | 2.20 | -1.58 | | | 0.000 | 1.577 | -5.14 | -4.88 |
| CV-24025 | 5/19/2026 9:25:00 AM | | | | | | | | | |
| CV-24025 | 5/13/2026 2:30:31 PM | 187.3 | -1.45 | -1.45 | | | 1.359 | 1.356 | -5.49 | -5.50 |
| CV-24025 | 5/6/2026 8:57:31 AM | 186.2 | -1.81 | -1.77 | | | 1.738 | 1.728 | -7.66 | -6.75 |
| CV-24025 | 5/6/2026 8:56:37 AM | 186.3 | -1.61 | -1.77 | | | 1.557 | 1.768 | -6.82 | -7.10 |
| CV-24025 | 5/5/2026 2:13:13 PM | 185.0 | -2.61 | -2.26 | | | 2.644 | 2.308 | -6.26 | -5.24 |
| CV-24025 | 5/5/2026 2:10:00 PM | | | | | | | | | |
| CV-24025 | 5/5/2026 2:10:00 PM | | | | | | | | | |
| CV-24026 | 5/22/2026 12:25:54 PM | 92.2 | -3.02 | -0.38 | | | 2.942 | 0.329 | -7.33 | -8.07 |
| CV-24026 | 5/13/2026 1:43:47 PM | 88.8 | -1.30 | -1.24 | | | 1.195 | 1.153 | -6.78 | -5.98 |
| CV-24027 | 5/26/2026 10:11:09 AM | 63.5 | -6.23 | -6.11 | | | 6.243 | 6.223 | -6.22 | -5.93 |
| CV-24027 | 5/13/2026 10:15:50 AM | 74.6 | -8.36 | -8.45 | | | 8.607 | 8.662 | -8.49 | -8.41 |
| CV-24027 | 5/6/2026 9:11:56 AM | 81.7 | -8.74 | -8.95 | | | 8.972 | 9.158 | -8.46 | -8.66 |
| CV-24028 | 5/26/2026 1:15:48 PM | 189.1 | -9.51 | -9.07 | | | 9.601 | 9.178 | -9.85 | -9.16 |
| CV-24028 | 5/26/2026 1:13:13 PM | 185.8 | -8.17 | -8.19 | | | 8.311 | 8.341 | -8.54 | -8.60 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24028 | 5/18/2026 2:05:00 PM | | | | | | | | | |
| CV-24028 | 5/18/2026 2:01:26 PM | 188.8 | 2.34 | 1.97 | | | 0.000 | 0.000 | 0.91 | 0.64 |
| CV-24028 | 5/12/2026 1:20:00 PM | | | | | | | | | |
| CV-24028 | 5/12/2026 1:14:56 PM | 188.0 | -5.15 | -4.97 | | | 4.939 | 4.808 | -6.23 | -5.74 |
| CV-24028 | 5/5/2026 10:00:52 AM | 193.0 | -6.04 | -6.04 | | | 6.141 | 6.141 | -8.78 | -8.78 |
| CV-24028 | 5/5/2026 10:00:00 AM | | | | | | | | | |
| CV-24028 | 5/5/2026 10:00:00 AM | | | | | | | | | |
| CV-24029 | 5/29/2026 11:19:30 AM | 87.8 | -4.30 | -3.01 | 0.0 | 0.0 | 4.479 | 2.855 | -6.48 | |
| CV-24029 | 5/29/2026 11:15:41 AM | 87.1 | -6.28 | -5.73 | 0.0 | 0.0 | 6.916 | 5.774 | -6.88 | |
| CV-24029 | 5/13/2026 2:06:48 PM | 85.9 | -7.47 | -7.31 | | | 7.585 | 7.394 | -7.45 | -7.24 |
| CV-24030 | 5/26/2026 9:14:08 AM | 192.7 | -1.22 | -1.23 | | | 1.208 | 1.220 | -3.42 | -3.41 |
| CV-24030 | 5/26/2026 9:07:52 AM | 193.0 | -3.16 | -1.62 | | | 3.139 | 1.658 | -3.06 | -3.31 |
| CV-24030 | 5/18/2026 9:35:03 AM | 190.8 | -1.75 | -1.75 | | | 1.794 | 1.802 | -1.85 | -1.87 |
| CV-24030 | 5/18/2026 9:35:00 AM | | | | | | | | | |
| CV-24030 | 5/12/2026 9:18:44 AM | 193.2 | -0.90 | -0.93 | | | 0.000 | 0.000 | 0.14 | 0.13 |
| CV-24030 | 5/12/2026 9:15:00 AM | | | | | | | | | |
| CV-24030 | 5/5/2026 8:46:48 AM | 190.7 | -2.22 | -2.04 | | | 2.164 | 2.073 | -5.87 | -5.87 |
| CV-24030 | 5/5/2026 8:45:00 AM | | | | | | | | | |
| CV-24030 | 5/5/2026 8:45:00 AM | | | | | | | | | |
| CV-24030 | 5/5/2026 8:44:58 AM | 190.9 | -6.38 | -4.42 | | | 6.141 | 4.485 | -6.08 | -6.01 |
| CV-24031 | 5/29/2026 1:15:41 PM | 116.1 | -6.98 | -7.00 | | | 7.051 | 7.058 | -6.68 | -6.72 |
| CV-24031 | 5/22/2026 12:15:48 PM | 131.4 | -0.35 | -0.34 | | | 0.216 | 0.243 | -7.99 | -8.00 |
| CV-24031 | 5/22/2026 12:14:13 PM | 132.8 | -0.55 | -0.34 | | | 0.350 | 0.230 | -7.90 | -8.18 |
| CV-24031 | 5/12/2026 1:32:07 PM | 121.9 | -0.26 | -0.19 | | | 0.190 | 0.135 | -5.85 | -6.42 |
| CV-24032 | 5/27/2026 9:19:07 AM | 192.1 | 2.10 | 2.67 | | | 0.000 | 0.000 | 1.93 | 2.23 |
| CV-24032 | 5/27/2026 9:17:20 AM | 192.0 | 0.54 | 0.29 | | | 0.000 | 0.000 | 2.23 | 1.91 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24032 | 5/27/2026 9:09:02 AM | 193.3 | -0.94 | -1.08 | | | 0.930 | 1.104 | 0.99 | 1.54 |
| CV-24032 | 5/24/2026 12:06:03 PM | 147.9 | -3.53 | -3.43 | | | 3.562 | 3.484 | -3.52 | -3.38 |
| CV-24032 | 5/24/2026 12:02:54 PM | 140.3 | -3.68 | -3.36 | | | 3.719 | 3.410 | -3.74 | -3.36 |
| CV-24032 | 5/19/2026 8:41:47 AM | 137.2 | -3.91 | -3.77 | | | 3.769 | 3.670 | -3.68 | -3.40 |
| CV-24032 | 5/14/2026 10:31:39 AM | 178.8 | -4.64 | -4.80 | | | 4.539 | 4.696 | -3.86 | -4.03 |
| CV-24032 | 5/13/2026 2:37:29 PM | 150.7 | -2.50 | -2.63 | | | 2.433 | 2.583 | -2.52 | -2.69 |
| CV-24032 | 5/5/2026 2:20:00 PM | | | | | | | | | |
| CV-24032 | 5/5/2026 2:20:00 PM | | | | | | | | | |
| CV-24032 | 5/5/2026 2:17:41 PM | 169.6 | -0.43 | -0.63 | | | 0.482 | 0.685 | 0.39 | 0.68 |
| CV-24033 | 5/28/2026 2:24:12 PM | 191.1 | -1.54 | -1.54 | | | 1.451 | 1.513 | -1.75 | -1.81 |
| CV-24033 | 5/19/2026 8:45:00 AM | | | | | | | | | |
| CV-24033 | 5/19/2026 8:39:24 AM | 184.7 | -3.21 | -3.22 | | | 3.198 | 3.205 | -3.70 | -3.73 |
| CV-24033 | 5/13/2026 2:17:00 PM | 185.3 | -3.26 | -3.28 | | | 3.265 | 3.281 | -4.01 | -4.05 |
| CV-24033 | 5/7/2026 1:00:00 PM | | | | | | | | | |
| CV-24033 | 5/7/2026 12:59:49 PM | 188.3 | -0.99 | -0.91 | | | 0.913 | 0.852 | -0.31 | -0.30 |
| CV-24033 | 5/7/2026 1:00:00 AM | | | | | | | | | |
| CV-24034 | 5/18/2026 11:08:37 AM | 105.9 | -1.53 | -1.57 | | | 1.490 | 1.498 | -2.02 | -2.02 |
| CV-24034 | 5/18/2026 11:06:51 AM | 108.0 | -3.76 | -1.48 | | | 3.784 | 1.470 | -3.19 | -3.48 |
| CV-24034 | 5/12/2026 10:57:45 AM | 166.6 | -2.34 | -2.32 | | | 2.322 | 2.304 | -9.40 | -9.41 |
| CV-24034 | 5/12/2026 10:55:50 AM | 168.0 | -9.52 | -7.24 | | | 9.563 | 7.234 | -9.16 | -9.29 |
| CV-24034 | 5/12/2026 10:55:00 AM | | | | | | | | | |
| CV-24034 | 5/5/2026 9:57:30 AM | 185.4 | -8.10 | -8.10 | | | 8.251 | 8.251 | -10.00 | -10.00 |
| CV-24034 | 5/5/2026 9:56:30 AM | 185.4 | -8.02 | -6.96 | | | 8.186 | 7.056 | -9.25 | -9.28 |
| CV-24034 | 5/5/2026 9:55:00 AM | | | | | | | | | |
| CV-24034 | 5/5/2026 9:55:00 AM | | | | | | | | | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24035 | 5/26/2026 8:50:47 AM | 180.7 | -3.40 | -3.28 | | | 3.494 | 3.095 | -0.01 | 0.00 |
| CV-24035 | 5/18/2026 9:10:00 AM | | | | | | | | | |
| CV-24035 | 5/18/2026 9:05:47 AM | 193.0 | -0.63 | -2.91 | | | 0.000 | 0.757 | 0.00 | 0.00 |
| CV-24035 | 5/18/2026 9:03:47 AM | 198.1 | 30.95 | 0.76 | | | 0.000 | 0.000 | -0.31 | -0.01 |
| CV-24035 | 5/12/2026 9:40:00 AM | | | | | | | | | |
| CV-24035 | 5/12/2026 9:31:35 AM | 177.3 | -5.39 | -5.33 | | | 5.402 | 5.403 | -4.84 | -5.28 |
| CV-24035 | 5/5/2026 8:25:00 AM | | | | | | | | | |
| CV-24035 | 5/5/2026 8:25:00 AM | | | | | | | | | |
| CV-24035 | 5/5/2026 8:24:01 AM | 179.2 | -6.09 | -5.70 | | | 5.877 | 5.502 | -5.68 | -6.00 |
| CV-24036 | 5/29/2026 2:20:04 PM | 83.1 | -4.43 | -4.39 | | | 4.301 | 4.190 | -8.25 | -8.74 |
| CV-24036 | 5/24/2026 11:45:25 AM | 73.3 | -8.22 | -7.95 | | | 8.039 | 7.899 | -8.17 | -7.85 |
| CV-24036 | 5/13/2026 10:53:14 AM | 77.0 | -7.49 | -7.44 | | | 7.925 | 7.887 | -7.44 | -7.46 |
| CV-24036 | 5/6/2026 8:46:55 AM | 68.6 | -7.62 | -7.69 | | | 7.706 | 7.837 | -7.23 | -6.64 |
| CV-24037 | 5/26/2026 9:09:53 AM | 59.2 | -3.83 | -3.74 | | | 3.758 | 3.664 | -6.15 | -5.73 |
| CV-24037 | 5/26/2026 9:08:28 AM | 58.8 | -6.41 | -3.51 | | | 6.474 | 3.423 | -6.41 | -6.23 |
| CV-24037 | 5/12/2026 1:53:15 PM | 80.6 | -4.98 | -4.77 | | | 5.298 | 4.976 | -4.79 | -4.67 |
| CV-24038 | 5/27/2026 9:29:33 AM | 177.8 | -0.91 | -0.99 | | | 1.162 | 1.178 | -4.07 | -4.20 |
| CV-24038 | 5/27/2026 9:27:49 AM | 178.8 | -2.38 | -1.72 | | | 2.425 | 1.800 | -5.78 | -5.77 |
| CV-24038 | 5/19/2026 9:05:00 AM | | | | | | | | | |
| CV-24038 | 5/19/2026 9:04:35 AM | 170.6 | -1.93 | -2.00 | | | 1.858 | 1.991 | -5.24 | -5.54 |
| CV-24038 | 5/19/2026 9:04:12 AM | 171.4 | -0.08 | -2.09 | | | 0.234 | 2.042 | -5.87 | -5.44 |
| CV-24038 | 5/13/2026 2:51:36 PM | 171.0 | -3.36 | -3.17 | | | 3.294 | 2.997 | -8.13 | -7.39 |
| CV-24038 | 5/13/2026 2:48:58 PM | 172.7 | -7.66 | -3.26 | | | 7.860 | 3.364 | -7.52 | -8.16 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24038 | 5/6/2026 3:05:00 PM | | | | | | | | | |
| CV-24038 | 5/6/2026 3:05:00 PM | | | | | | | | | |
| CV-24038 | 5/6/2026 3:04:57 PM | 182.8 | -4.92 | -4.46 | | | 4.757 | 3.554 | 0.00 | 0.00 |
| CV-24038 | 5/6/2026 3:04:21 PM | 183.2 | 0.83 | -0.06 | | | 0.000 | 0.000 | 0.00 | 0.00 |
| CV-24039 | 5/22/2026 12:04:33 PM | 143.8 | -7.62 | -7.77 | | | 7.664 | 7.868 | -8.33 | -8.72 |
| CV-24039 | 5/22/2026 12:01:47 PM | 149.1 | -6.16 | -6.16 | | | 6.220 | 6.226 | -8.77 | -8.76 |
| CV-24039 | 5/22/2026 11:58:20 AM | 137.0 | 50.09 | -5.15 | | | 0.000 | 5.244 | -8.49 | -8.18 |
| CV-24039 | 5/14/2026 1:31:24 PM | 86.9 | -7.81 | -7.97 | | | 7.882 | 7.917 | -8.95 | -8.59 |
| CV-24039 | 5/14/2026 1:29:39 PM | 87.3 | -7.91 | -8.04 | | | 8.039 | 8.097 | -8.11 | -8.27 |
| CV-24040 | 5/29/2026 9:07:46 AM | 172.2 | -0.72 | -0.72 | | | 0.717 | 0.687 | -8.74 | -9.06 |
| CV-24040 | 5/29/2026 9:07:06 AM | 171.2 | -0.59 | -0.59 | | | 0.569 | 0.599 | -8.09 | -8.68 |
| CV-24040 | 5/29/2026 9:05:56 AM | | 25.41 | | | | 0.000 | | -7.68 | |
| CV-24040 | 5/19/2026 10:40:23 AM | 86.6 | -8.40 | -8.40 | | | 8.480 | 8.478 | -9.24 | -9.26 |
| CV-24040 | 5/19/2026 10:38:38 AM | 85.9 | -8.40 | -8.40 | | | 8.383 | 8.421 | -9.20 | -9.42 |
| CV-24040 | 5/13/2026 1:35:35 PM | 82.3 | -7.88 | -7.85 | | | 7.997 | 7.964 | -7.80 | -7.78 |
| CV-24040 | 5/13/2026 1:32:34 PM | 81.8 | -8.50 | -8.90 | | | 8.545 | 8.953 | -8.95 | -9.73 |
| CV-24041 | 5/26/2026 10:04:46 AM | 65.4 | -6.50 | -5.72 | | | 6.603 | 5.698 | -6.37 | -6.18 |
| CV-24041 | 5/8/2026 8:06:27 AM | 71.8 | -5.22 | -5.19 | 0.0 | 0.0 | 5.202 | 5.194 | -5.37 | |
| CV-24042 | 5/26/2026 11:03:38 AM | 185.6 | -5.74 | -5.39 | | | 5.708 | 5.432 | -11.16 | -11.17 |
| CV-24042 | 5/26/2026 11:02:42 AM | 184.2 | -10.01 | -6.36 | | | 10.042 | 6.373 | -11.18 | -11.15 |
| CV-24042 | 5/18/2026 10:55:00 AM | | | | | | | | | |
| CV-24042 | 5/18/2026 10:47:52 AM | 188.5 | -2.89 | -2.92 | | | 2.665 | 2.633 | -5.08 | -4.96 |
| CV-24042 | 5/12/2026 10:15:58 AM | 183.3 | -6.96 | -6.97 | | | 6.966 | 6.985 | -11.66 | -11.55 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24042 | 5/12/2026 10:15:09 AM | 182.5 | -10.36 | -7.21 | | | 10.386 | 7.200 | -11.36 | -11.61 |
| CV-24042 | 5/12/2026 10:15:00 AM | | | | | | | | | |
| CV-24042 | 5/7/2026 10:08:18 AM | 191.5 | -2.88 | -2.79 | | | 2.712 | 2.774 | -3.80 | -3.67 |
| CV-24042 | 5/7/2026 10:06:45 AM | 190.4 | 2.93 | -3.17 | | | 0.000 | 3.143 | -3.96 | -3.97 |
| CV-24042 | 5/7/2026 10:05:00 AM | | | | | | | | | |
| CV-24042 | 5/7/2026 10:05:00 AM | | | | | | | | | |
| CV-24043 | 5/22/2026 2:06:15 PM | 91.6 | -2.26 | -4.48 | | | 2.209 | 4.284 | -2.41 | -5.77 |
| CV-24043 | 5/15/2026 8:55:16 AM | 85.7 | -5.29 | -5.11 | | | 5.492 | 5.318 | -5.27 | -4.93 |
| CV-24044 | 5/26/2026 8:46:58 AM | 130.2 | -2.80 | -2.40 | | | 2.740 | 2.354 | -6.52 | -7.02 |
| CV-24044 | 5/26/2026 8:42:07 AM | 129.2 | 2.24 | -1.62 | | | 0.000 | 1.590 | -6.84 | -6.38 |
| CV-24044 | 5/8/2026 12:36:24 PM | 87.5 | -6.31 | -5.90 | | | 6.315 | 5.948 | -6.22 | -6.34 |
| CV-24045 | 5/27/2026 9:33:35 AM | 157.7 | -2.10 | -2.08 | | | 2.128 | 2.114 | -2.79 | -2.79 |
| CV-24045 | 5/27/2026 9:32:48 AM | 156.8 | -0.60 | -2.14 | | | 0.639 | 2.114 | -2.60 | -2.74 |
| CV-24045 | 5/19/2026 9:11:34 AM | 152.4 | -3.47 | -3.46 | | | 3.468 | 3.458 | -5.72 | -5.51 |
| CV-24045 | 5/19/2026 9:10:36 AM | 151.1 | -6.96 | -3.44 | | | 7.055 | 3.452 | -6.83 | -5.38 |
| CV-24045 | 5/19/2026 9:10:00 AM | | | | | | | | | |
| CV-24045 | 5/13/2026 2:58:14 PM | 150.1 | -4.34 | -4.44 | | | 4.294 | 4.476 | -7.81 | -8.74 |
| CV-24045 | 5/13/2026 2:56:09 PM | 149.6 | -7.29 | -3.98 | | | 7.415 | 3.972 | -7.41 | -8.39 |
| CV-24045 | 5/6/2026 2:55:47 PM | 161.0 | -3.53 | -3.49 | | | 3.536 | 3.537 | -5.86 | -5.76 |
| CV-24045 | 5/6/2026 2:54:58 PM | 162.2 | -5.61 | -3.47 | | | 5.525 | 3.335 | -5.49 | -6.27 |
| CV-24045 | 5/6/2026 2:45:00 PM | | | | | | | | | |
| CV-24045 | 5/6/2026 2:45:00 PM | | | | | | | | | |
| CV-24046 | 5/29/2026 1:33:04 PM | 125.7 | -2.98 | -2.94 | | | 2.990 | 2.894 | -3.35 | -2.71 |
| CV-24046 | 5/29/2026 1:30:24 PM | 124.4 | 132.32 | -1.93 | | | 0.000 | 1.934 | 9.74 | -2.60 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24046 | 5/28/2026 11:56:16 AM | 73.2 | -7.10 | -7.13 | 0.0 | 0.0 | 7.116 | 7.297 | -7.89 | |
| CV-24046 | 5/28/2026 11:54:22 AM | 71.7 | -7.75 | -6.99 | 0.0 | 0.0 | 7.986 | 7.182 | -7.74 | |
| CV-24046 | 5/13/2026 10:32:28 AM | 93.1 | -7.60 | -7.87 | | | 7.925 | 8.185 | -7.73 | -8.03 |
| CV-24048 | 5/20/2026 2:12:35 PM | 97.2 | -8.02 | -7.73 | | | 7.729 | 7.666 | -7.96 | -7.66 |
| CV-24048 | 5/19/2026 10:25:00 AM | | | | | | | | | |
| CV-24048 | 5/8/2026 8:14:16 AM | 83.3 | -5.18 | -5.07 | 0.0 | 0.0 | 5.283 | 4.841 | -5.26 | |
| CV-24049 | 5/26/2026 10:45:00 AM | 179.6 | -5.95 | -5.74 | | | 5.960 | 5.690 | -11.49 | -12.01 |
| CV-24049 | 5/26/2026 10:43:34 AM | 179.2 | -11.36 | -5.97 | | | 11.387 | 5.903 | -11.24 | -11.51 |
| CV-24049 | 5/18/2026 10:35:00 AM | | | | | | | | | |
| CV-24049 | 5/18/2026 10:30:56 AM | 180.2 | -4.87 | -4.90 | | | 5.071 | 5.059 | -4.97 | -4.95 |
| CV-24049 | 5/13/2026 8:10:00 AM | | | | | | | | | |
| CV-24049 | 5/13/2026 8:10:00 AM | | | | | | | | | |
| CV-24049 | 5/11/2026 8:49:25 AM | 185.0 | -1.84 | -1.69 | | | 1.846 | 1.839 | -0.36 | -0.08 |
| CV-24049 | 5/11/2026 8:47:07 AM | 186.6 | 3.00 | -0.64 | | | 0.000 | 0.600 | -0.87 | -0.63 |
| CV-24049 | 5/4/2026 2:40:00 PM | | | | | | | | | |
| CV-24049 | 5/4/2026 2:40:00 PM | | | | | | | | | |
| CV-24049 | 5/4/2026 2:36:19 PM | 189.2 | -4.01 | -3.94 | | | 3.706 | 3.731 | -10.48 | -10.49 |
| CV-24050 | 5/22/2026 2:16:54 PM | 103.0 | -2.05 | -2.06 | | | 1.991 | 2.002 | -8.30 | -8.24 |
| CV-24050 | 5/11/2026 12:53:12 PM | 109.5 | -1.58 | -1.57 | | | 1.421 | 1.381 | -5.74 | -5.70 |
| CV-24051 | 5/26/2026 8:54:30 AM | 102.2 | -4.70 | -0.74 | | | 4.616 | 0.722 | -5.94 | -6.75 |
| CV-24051 | 5/8/2026 12:45:09 PM | 83.3 | -6.10 | -5.57 | | | 6.044 | 5.631 | -5.82 | -5.61 |
| CV-24052 | 5/20/2026 2:26:23 PM | 94.2 | -4.19 | -4.19 | | | 4.128 | 4.120 | -4.25 | -4.25 |
| CV-24052 | 5/13/2026 10:05:26 AM | 73.4 | -6.11 | -6.22 | | | 6.384 | 6.466 | -6.22 | -6.31 |
| CV-24053 | 5/20/2026 2:23:25 PM | 100.5 | -4.32 | -4.99 | | | 4.201 | 4.770 | -4.39 | -5.14 |
| CV-24053 | 5/8/2026 8:18:44 AM | 75.5 | -3.03 | -3.04 | 0.0 | 0.0 | 3.012 | 3.166 | -3.36 | |
| CV-24053 | 5/7/2026 8:40:00 AM | | | | | | | | | |
| CV-24053 | 5/7/2026 8:40:00 AM | | | | | | | | | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24054 | 5/26/2026 10:39:35 AM | 153.1 | -4.69 | -4.61 | | | 4.676 | 4.634 | -12.19 | -12.31 |
| CV-24054 | 5/26/2026 10:39:02 AM | 154.4 | -10.28 | -4.08 | | | 10.280 | 4.069 | -11.31 | -11.75 |
| CV-24054 | 5/18/2026 10:30:00 AM | | | | | | | | | |
| CV-24054 | 5/18/2026 10:27:38 AM | 145.6 | -4.41 | -4.48 | | | 4.080 | 4.118 | -4.89 | -4.92 |
| CV-24054 | 5/18/2026 10:26:19 AM | 146.6 | -5.95 | -4.75 | | | 5.826 | 4.606 | -5.85 | -5.54 |
| CV-24054 | 5/11/2026 8:39:09 AM | 160.1 | -2.69 | -2.67 | | | 2.666 | 2.649 | -2.19 | -2.32 |
| CV-24054 | 5/11/2026 8:36:54 AM | 164.1 | 1.50 | -2.55 | | | 0.000 | 2.520 | -2.36 | -2.21 |
| CV-24054 | 5/4/2026 2:35:00 PM | | | | | | | | | |
| CV-24054 | 5/4/2026 2:35:00 PM | | | | | | | | | |
| CV-24054 | 5/4/2026 2:34:03 PM | 173.8 | -1.43 | -1.39 | | | 1.333 | 1.385 | -11.00 | -11.11 |
| CV-24054 | 5/4/2026 1:54:35 PM | 147.1 | -2.12 | -2.13 | | | 2.120 | 2.128 | -11.31 | -11.31 |
| CV-24054 | 5/4/2026 1:51:53 PM | 148.2 | -4.62 | -3.41 | | | 4.646 | 3.449 | -11.47 | -11.45 |
| CV-24055 | 5/26/2026 9:28:17 AM | 136.8 | -0.35 | -0.35 | | | 0.350 | 0.356 | -7.59 | -7.86 |
| CV-24055 | 5/26/2026 9:27:16 AM | 137.2 | -0.44 | -0.34 | | | 0.431 | 0.340 | -8.47 | -8.01 |
| CV-24055 | 5/13/2026 8:15:00 AM | | | | | | | | | |
| CV-24055 | 5/13/2026 8:15:00 AM | | | | | | | | | |
| CV-24055 | 5/12/2026 1:49:20 PM | 137.3 | -0.58 | -0.57 | | | 0.534 | 0.504 | -9.05 | -8.62 |
| CV-24055 | 5/12/2026 1:47:04 PM | 137.9 | -0.52 | -0.62 | | | 0.514 | 0.629 | -11.04 | -10.68 |
| CV-24056 | 5/19/2026 12:46:55 PM | 122.8 | -0.58 | -0.38 | | | 0.573 | 0.379 | -4.46 | -4.66 |
| CV-24056 | 5/1/2026 10:37:33 AM | 124.8 | -0.96 | -0.96 | | | 0.942 | 0.936 | -6.07 | -6.08 |
| CV-24057 | 5/22/2026 2:21:55 PM | 144.2 | -0.27 | -0.25 | 17.2 | 17.5 | 0.838 | 0.873 | -7.07 | -7.35 |
| CV-24057 | 5/11/2026 1:01:48 PM | 139.5 | -0.82 | -0.84 | 15.0 | 15.0 | 0.635 | 0.629 | -5.37 | -5.49 |
| CV-24057 | 5/11/2026 1:00:44 PM | 139.4 | -0.84 | -0.83 | 15.1 | 15.0 | 0.642 | 0.631 | -5.60 | -5.72 |
| CV-24058 | 5/22/2026 1:59:19 PM | 105.3 | -2.87 | -3.28 | | | 2.819 | 3.187 | -4.29 | -5.12 |
| CV-24058 | 5/11/2026 12:33:09 PM | 110.0 | -0.33 | -1.50 | | | 0.316 | 1.508 | -1.15 | -2.80 |
| CV-24059 | 5/22/2026 2:29:34 PM | 114.1 | -1.32 | -1.32 | 0.4 | 0.7 | 0.000 | 0.001 | -8.29 | -8.40 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24059 | 5/4/2026 9:02:50 AM | 123.9 | -2.37 | -2.31 | 3.7 | 1.4 | 0.037 | 0.006 | -10.18 | -9.78 |
| CV-24059 | 5/4/2026 9:01:40 AM | 121.0 | -5.28 | -2.38 | 3.0 | 1.3 | 0.025 | 0.005 | -9.80 | -9.95 |
| CV-24060 | 5/20/2026 1:29:27 PM | 113.6 | -5.44 | -4.61 | | | 5.359 | 4.575 | -6.69 | -6.80 |
| CV-24060 | 5/4/2026 9:39:35 AM | 109.2 | -9.42 | -7.94 | | | 9.679 | 8.217 | -9.50 | -9.28 |
| CV-24061 | 5/26/2026 11:38:49 AM | 100.6 | -5.98 | -6.96 | | | 6.087 | 7.055 | -11.07 | -11.15 |
| CV-24061 | 5/8/2026 12:59:31 PM | 97.8 | -2.99 | -2.95 | | | 2.900 | 2.886 | -6.74 | -6.06 |
| CV-24062 | 5/22/2026 11:10:33 AM | 143.7 | -1.88 | -1.78 | 0.0 | 0.0 | 1.829 | 1.760 | -8.22 | |
| CV-24062 | 5/22/2026 11:08:48 AM | 140.3 | -3.49 | -3.46 | 0.0 | 0.0 | 3.461 | 3.337 | -8.26 | |
| CV-24062 | 5/8/2026 1:05:26 PM | 134.2 | -2.10 | -2.02 | | | 2.018 | 1.948 | -6.46 | -5.92 |
| CV-24062 | 5/7/2026 8:17:00 AM | | | | | | | | | |
| CV-24062 | 5/7/2026 8:17:00 AM | | | | | | | | | |
| CV-24062 | 5/4/2026 1:16:07 PM | 148.7 | -6.22 | -6.38 | | | 6.249 | 6.276 | -10.23 | -10.14 |
| CV-24062 | 5/4/2026 1:15:00 PM | | | | | | | | | |
| CV-24062 | 5/4/2026 1:15:00 PM | | | | | | | | | |
| CV-24063 | 5/28/2026 1:49:33 PM | 183.7 | -2.47 | -2.43 | | | 2.461 | 2.410 | -7.15 | -7.17 |
| CV-24063 | 5/20/2026 2:20:53 PM | 173.7 | -2.92 | -2.92 | | | 3.045 | 3.045 | 0.00 | 0.00 |
| CV-24063 | 5/14/2026 11:02:15 AM | 171.9 | -3.36 | -3.31 | | | 3.386 | 3.216 | -8.44 | -8.43 |
| CV-24063 | 5/14/2026 11:01:37 AM | 173.4 | 0.65 | -3.17 | | | 0.000 | 3.171 | 0.34 | -8.71 |
| CV-24063 | 5/14/2026 11:00:00 AM | | | | | | | | | |
| CV-24063 | 5/12/2026 8:20:00 AM | | | | | | | | | |
| CV-24063 | 5/12/2026 8:20:00 AM | | | | | | | | | |
| CV-24063 | 5/4/2026 1:35:00 PM | | | | | | | | | |
| CV-24063 | 5/4/2026 1:35:00 PM | | | | | | | | | |
| CV-24063 | 5/4/2026 1:34:44 PM | 182.5 | -3.44 | -3.34 | | | 3.362 | 3.318 | -11.05 | -10.94 |
| CV-24063 | 5/4/2026 1:33:24 PM | 181.7 | -7.10 | -3.43 | | | 7.018 | 3.326 | -11.01 | -10.81 |
| CV-24064 | 5/28/2026 2:15:41 PM | 165.7 | -7.85 | -7.85 | | | 7.902 | 7.905 | -8.16 | -8.16 |
| CV-24064 | 5/27/2026 1:55:09 PM | 192.0 | -6.74 | -6.78 | | | 6.851 | 6.944 | -6.68 | -7.14 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24064 | 5/19/2026 1:40:00 PM | | | | | | | | | |
| CV-24064 | 5/19/2026 1:36:22 PM | 192.5 | -5.48 | -4.27 | | | 4.594 | 4.805 | -9.16 | -9.07 |
| CV-24064 | 5/12/2026 8:15:00 AM | | | | | | | | | |
| CV-24064 | 5/11/2026 10:07:41 AM | 192.5 | -10.46 | -10.56 | | | 10.565 | 10.676 | -13.49 | -13.40 |
| CV-24064 | 5/4/2026 9:10:00 AM | | | | | | | | | |
| CV-24064 | 5/4/2026 9:10:00 AM | | | | | | | | | |
| CV-24064 | 5/4/2026 9:09:33 AM | 191.8 | -11.35 | -10.47 | | | 11.611 | 10.682 | -12.85 | -13.23 |
| CV-24065-TP1 | 5/22/2026 10:27:26 AM | 83.8 | -0.33 | -0.32 | | | 0.319 | 0.319 | -10.19 | -10.50 |
| CV-24065-TP1 | 5/12/2026 8:15:00 AM | | | | | | | | | |
| CV-24065-TP1 | 5/11/2026 1:07:25 PM | 100.2 | -0.10 | -0.03 | | | 0.054 | 0.001 | 0.48 | 0.67 |
| CV-24065-TP1 | 5/7/2026 8:35:00 AM | | | | | | | | | |
| CV-24065-TP1 | 5/7/2026 8:35:00 AM | | | | | | | | | |
| CV-24066 | 5/19/2026 12:41:10 PM | 110.5 | -0.94 | -0.93 | | | 0.940 | 0.926 | -6.12 | -5.98 |
| CV-24066 | 5/11/2026 7:45:00 AM | | | | | | | | | |
| CV-24066 | 5/11/2026 7:45:00 AM | | | | | | | | | |
| CV-24066 | 5/1/2026 10:40:05 AM | 117.5 | -1.19 | -1.18 | | | 1.198 | 1.180 | -8.39 | -7.76 |
| CV-24067 | 5/26/2026 2:27:02 PM | 152.4 | -6.42 | -6.45 | | | 0.056 | 0.048 | -7.79 | -7.77 |
| CV-24067 | 5/26/2026 2:26:30 PM | 152.4 | -7.13 | -6.63 | | | 0.000 | 0.000 | -7.71 | -7.51 |
| CV-24067 | 5/19/2026 8:57:43 AM | 160.7 | -6.62 | -6.65 | 5.8 | 5.6 | 0.099 | 0.093 | -7.16 | -7.16 |
| CV-24067 | 5/19/2026 8:55:05 AM | 160.8 | -6.96 | -6.65 | 5.2 | 6.1 | 0.079 | 0.110 | -7.16 | -7.27 |
| CV-24067 | 5/14/2026 11:37:11 AM | 134.5 | 0.40 | 0.37 | 0.0 | 0.0 | -0.043 | -0.038 | 0.35 | |
| CV-24067 | 5/14/2026 11:35:44 AM | 134.5 | 0.29 | 0.30 | 0.0 | 0.0 | -0.018 | -0.021 | 0.31 | |
| CV-24068 | 5/26/2026 12:08:57 PM | 129.1 | -2.40 | -2.40 | | | 2.342 | 2.342 | -9.23 | -8.68 |
| CV-24068 | 5/26/2026 12:06:40 PM | 129.7 | -5.07 | -3.21 | | | 4.947 | 3.150 | -8.52 | -8.94 |
| CV-24068 | 5/1/2026 11:18:00 AM | 116.0 | -5.07 | -4.88 | | | 5.611 | 5.406 | -7.76 | -7.74 |
| CV-24069 | 5/28/2026 9:36:45 AM | 93.4 | -1.66 | -1.65 | | | 1.681 | 1.663 | -9.09 | -8.46 |
| CV-24069 | 5/28/2026 9:35:46 AM | 93.7 | -1.98 | -1.68 | | | 2.008 | 1.703 | -8.97 | -8.90 |
| CV-24069 | 5/28/2026 9:30:09 AM | 96.2 | -2.80 | -2.08 | | | 2.836 | 2.106 | -9.63 | -10.08 |
| CV-24069 | 5/13/2026 8:20:00 AM | | | | | | | | | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24069 | 5/13/2026 8:20:00 AM | | | | | | | | | |
| CV-24069 | 5/4/2026 8:56:06 AM | 93.4 | -1.42 | -1.43 | | | 1.390 | 1.399 | 0.01 | 0.00 |
| CV-24070 | 5/20/2026 2:35:15 PM | 136.2 | -0.15 | -0.10 | 3.3 | 3.2 | 0.230 | 0.220 | -3.35 | -3.53 |
| CV-24070 | 5/20/2026 2:34:29 PM | 136.1 | -0.13 | -0.15 | 4.8 | 5.8 | 0.493 | 0.736 | -3.49 | -3.63 |
| CV-24070 | 5/20/2026 2:33:43 PM | 135.6 | 0.95 | -0.10 | 5.3 | 4.9 | 0.601 | 0.513 | -3.46 | -3.51 |
| CV-24070 | 5/7/2026 8:20:00 AM | | | | | | | | | |
| CV-24070 | 5/7/2026 8:20:00 AM | | | | | | | | | |
| CV-24070 | 5/4/2026 9:12:35 AM | 130.3 | -1.21 | -1.13 | 6.5 | 6.6 | 0.903 | 0.932 | -10.00 | -9.79 |
| CV-24070 | 5/4/2026 9:11:52 AM | 130.3 | -1.65 | -1.07 | 6.8 | 6.5 | 1.010 | 0.923 | -10.01 | -9.90 |
| CV-24071 | 5/20/2026 1:35:21 PM | 123.2 | -3.74 | -3.33 | 8.7 | 8.5 | 0.491 | 0.462 | -6.65 | -6.63 |
| CV-24071 | 5/7/2026 8:10:00 AM | | | | | | | | | |
| CV-24071 | 5/7/2026 8:10:00 AM | | | | | | | | | |
| CV-24071 | 5/4/2026 9:43:04 AM | 121.4 | -5.57 | -5.24 | 14.9 | 15.1 | 1.428 | 1.465 | -9.94 | -10.58 |
| CV-24072 | 5/22/2026 2:05:23 PM | 108.9 | -2.50 | -1.94 | 0.0 | 0.0 | 2.372 | 1.785 | -8.01 | |
| CV-24072 | 5/4/2026 2:18:34 PM | 87.9 | -0.66 | -0.66 | | | 0.732 | 0.642 | -10.14 | -11.51 |
| CV-24072 | 5/4/2026 2:17:08 PM | 87.8 | 1.80 | -0.35 | | | 0.000 | 0.319 | -10.27 | -10.18 |
| CV-24073-TP1 | 5/26/2026 8:45:28 AM | 132.6 | -0.34 | -0.30 | | | 0.327 | 0.283 | -4.46 | -4.51 |
| CV-24073-TP1 | 5/26/2026 8:40:41 AM | 133.5 | -0.39 | -0.34 | | | 0.388 | 0.334 | -4.05 | -4.01 |
| CV-24073-TP1 | 5/8/2026 1:15:17 PM | 128.9 | -1.69 | -1.61 | | | 1.673 | 1.558 | -5.57 | -4.83 |
| CV-24073-TP1 | 5/6/2026 2:09:30 PM | 125.8 | -0.53 | -0.56 | | | 0.526 | 0.516 | -4.50 | -4.20 |
| CV-24074 | 5/22/2026 11:17:05 AM | 111.0 | -6.04 | -3.69 | | | 6.001 | 3.582 | -7.29 | -7.39 |
| CV-24074 | 5/6/2026 2:14:23 PM | 107.0 | -5.18 | -4.71 | | | 5.207 | 4.588 | -5.82 | -5.79 |
| CV-24075-TP1 | 5/29/2026 4:03:35 PM | 187.0 | -13.96 | -14.01 | | | 14.314 | 14.356 | -14.15 | -14.30 |
| CV-24075-TP1 | 5/29/2026 4:02:17 PM | 186.7 | -14.48 | -14.48 | | | 14.792 | 14.792 | -15.16 | -15.16 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24075-TP1 | 5/11/2026 10:25:13 AM | 99.5 | -11.66 | -11.98 | | | 11.789 | 12.211 | 0.04 | 0.04 |
| CV-24075-TP1 | 5/4/2026 9:21:41 AM | 187.2 | -13.08 | -13.16 | | | 13.372 | 13.398 | 0.04 | 0.04 |
| CV-24075-TP1 | 5/4/2026 9:20:10 AM | 60.6 | -13.32 | -13.51 | | | 13.587 | 13.736 | 0.07 | 0.04 |
| CV-24075-TP1 | 5/4/2026 9:20:00 AM | | | | | | | | | |
| CV-24075-TP1 | 5/4/2026 9:20:00 AM | | | | | | | | | |
| CV-24076 | 5/27/2026 2:11:24 PM | 172.3 | -2.33 | -2.17 | | | 2.219 | 2.125 | -4.45 | -4.54 |
| CV-24076 | 5/19/2026 1:30:00 PM | | | | | | | | | |
| CV-24076 | 5/19/2026 1:22:53 PM | 169.0 | -3.53 | -3.49 | | | 3.539 | 3.433 | -6.72 | -6.55 |
| CV-24076 | 5/14/2026 10:30:00 AM | | | | | | | | | |
| CV-24076 | 5/14/2026 10:29:35 AM | 174.6 | -4.43 | -4.29 | | | 4.392 | 4.275 | -7.93 | -7.35 |
| CV-24076 | 5/4/2026 9:06:09 AM | 176.9 | -6.12 | -5.74 | | | 6.253 | 5.927 | 0.00 | 0.00 |
| CV-24076 | 5/4/2026 9:05:00 AM | | | | | | | | | |
| CV-24076 | 5/4/2026 9:05:00 AM | | | | | | | | | |
| CV-24077 | 5/28/2026 9:18:10 AM | 147.0 | -2.62 | -2.61 | | | 2.611 | 2.602 | -9.05 | -9.02 |
| CV-24077 | 5/28/2026 9:16:41 AM | 144.5 | -4.76 | -4.77 | | | 4.761 | 4.767 | -9.14 | -9.16 |
| CV-24077 | 5/20/2026 8:03:01 AM | 142.4 | -4.52 | -4.48 | | | 4.525 | 4.494 | -6.99 | -7.10 |
| CV-24077 | 5/11/2026 1:38:12 PM | 146.1 | -2.00 | -2.00 | | | 1.956 | 1.960 | 5.79 | 6.10 |
| CV-24077 | 5/7/2026 10:50:33 AM | 148.8 | -0.95 | -0.98 | | | 0.957 | 0.990 | -2.92 | -3.04 |
| CV-24077 | 5/7/2026 10:50:00 AM | | | | | | | | | |
| CV-24077 | 5/7/2026 10:50:00 AM | | | | | | | | | |
| CV-24077 | 5/1/2026 10:03:08 AM | 151.0 | -1.23 | -1.24 | | | 1.237 | 1.244 | -6.62 | -6.63 |
| CV-24077 | 5/1/2026 10:01:59 AM | 151.0 | -1.95 | -1.20 | | | 1.941 | 1.188 | -5.89 | -6.33 |
| CV-24078 | 5/19/2026 8:40:05 AM | 130.7 | -2.01 | -2.00 | 8.6 | 9.4 | 0.207 | 0.243 | -6.99 | -7.34 |
| CV-24078 | 5/19/2026 8:35:10 AM | 130.8 | -2.24 | -2.23 | 8.1 | 8.3 | 0.182 | 0.191 | -7.00 | -6.90 |
| CV-24078 | 5/19/2026 8:34:05 AM | 130.8 | -2.13 | -2.21 | 7.9 | 8.2 | 0.173 | 0.189 | -7.05 | -7.02 |
| CV-24078 | 5/19/2026 8:31:45 AM | 130.9 | -2.77 | -2.21 | 12.1 | 8.8 | 0.407 | 0.217 | -6.95 | -7.18 |
| CV-24078 | 5/1/2026 10:43:48 AM | 126.2 | -0.94 | -0.83 | 8.1 | 6.9 | 0.178 | 0.131 | -5.99 | -5.70 |
| CV-24079-TP8 | 5/26/2026 12:13:32 PM | 135.9 | -5.41 | -5.41 | | | 5.321 | 5.294 | -0.27 | -0.14 |
| CV-24079-TP8 | 5/26/2026 12:12:54 PM | 137.0 | -7.80 | -5.70 | | | 7.727 | 5.474 | -0.06 | -0.04 |
| CV-24079-TP8 | 5/11/2026 1:15:47 PM | 141.7 | -5.34 | -5.34 | | | 5.190 | 5.193 | 0.02 | 0.02 |
| CV-24079-TP8 | 5/7/2026 10:41:06 AM | 172.6 | -1.59 | -1.63 | | | 1.581 | 1.594 | 0.33 | 0.32 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24079-TP8 | 5/7/2026 10:40:00 AM | | | | | | | | | |
| CV-24079-TP8 | 5/7/2026 10:40:00 AM | | | | | | | | | |
| CV-24079-TP8 | 5/7/2026 10:38:33 AM | 168.1 | 0.98 | -1.80 | | | 0.000 | 1.777 | 0.33 | 0.33 |
| CV-24079-TP8 | 5/1/2026 11:22:57 AM | 152.4 | -0.16 | -0.16 | | | 0.148 | 0.150 | 0.68 | 0.65 |
| CV-24079-TP8 | 5/1/2026 11:22:12 AM | 154.7 | -0.62 | -0.25 | | | 0.618 | 0.246 | 0.66 | 0.67 |
| CV-24080 | 5/21/2026 9:36:06 AM | 117.0 | -0.38 | -0.36 | 2.8 | 3.2 | 0.021 | 0.028 | -1.24 | -0.96 |
| CV-24080 | 5/1/2026 11:09:29 AM | 123.0 | -0.56 | -0.58 | 2.5 | 5.1 | 0.017 | 0.071 | -5.24 | -8.14 |
| CV-24081-TP1 | 5/20/2026 2:26:51 PM | 117.4 | -0.23 | -0.22 | | | 0.220 | 0.206 | -3.04 | -2.89 |
| CV-24081-TP1 | 5/20/2026 2:25:55 PM | 118.7 | 0.33 | -0.12 | | | 0.000 | 0.126 | -3.10 | -3.13 |
| CV-24081-TP1 | 5/14/2026 10:40:33 AM | 120.2 | -0.76 | -0.75 | | | 0.745 | 0.743 | -7.68 | -7.55 |
| CV-24082 | 5/20/2026 11:24:26 AM | 124.4 | -0.20 | -0.13 | | | 0.167 | 0.107 | -6.11 | -6.36 |
| CV-24082 | 5/4/2026 10:11:50 AM | 111.4 | -0.42 | -0.44 | | | 0.390 | 0.411 | -8.93 | -9.09 |
| CV-24083 | 5/20/2026 1:53:17 PM | 125.0 | -0.17 | -0.17 | | | 0.171 | 0.181 | -6.95 | -7.14 |
| CV-24083 | 5/4/2026 9:58:27 AM | 108.4 | -0.80 | -0.81 | | | 0.780 | 0.787 | -10.17 | -10.44 |
| CV-24083 | 5/4/2026 9:56:08 AM | 105.9 | 0.60 | -0.69 | | | 0.000 | 0.674 | -10.39 | -10.34 |
| CV-24084-TP1 | 5/27/2026 10:49:57 AM | 180.7 | -2.12 | -2.36 | | | 1.995 | 2.378 | -5.06 | -5.12 |
| CV-24084-TP1 | 5/19/2026 10:24:00 AM | 180.9 | -3.47 | -3.40 | | | 3.626 | 3.026 | -6.08 | -5.94 |
| CV-24084-TP1 | 5/11/2026 1:05:39 PM | 181.3 | -1.83 | -1.69 | | | 1.848 | 1.723 | -4.96 | -4.94 |
| CV-24084-TP1 | 5/4/2026 2:08:40 PM | 180.8 | -1.49 | -1.39 | | | 1.341 | 1.272 | -8.12 | -8.12 |
| CV-24084-TP1 | 5/4/2026 2:05:00 PM | | | | | | | | | |
| CV-24084-TP1 | 5/4/2026 2:05:00 PM | | | | | | | | | |
| CV-24085 | 5/20/2026 10:07:30 AM | 128.5 | -0.76 | -0.86 | 12.3 | 17.0 | 0.429 | 0.818 | -7.52 | |
| CV-24085 | 5/1/2026 10:47:32 AM | 126.8 | -0.59 | -0.58 | 10.0 | 10.2 | 0.277 | 0.284 | -7.83 | -7.72 |
| CV-24086 | 5/21/2026 9:49:26 AM | 114.5 | -0.24 | -0.23 | 9.4 | 9.5 | 0.239 | 0.242 | -4.68 | -4.61 |
| CV-24086 | 5/1/2026 11:00:38 AM | 116.2 | -0.61 | -0.40 | 13.2 | 11.5 | 0.468 | 0.355 | -7.80 | -7.55 |
| CV-24087 | 5/20/2026 1:36:05 PM | 119.0 | -1.12 | -1.13 | 38.9 | 39.1 | 4.144 | 4.189 | -5.49 | -5.55 |
| CV-24087 | 5/5/2026 10:43:05 AM | 115.8 | -0.76 | -0.78 | 22.3 | 21.8 | 1.345 | 1.284 | -9.08 | -9.18 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24088 | 5/28/2026 9:04:04 AM | 99.2 | -1.94 | -1.94 | | | 1.943 | 1.949 | -8.79 | -8.56 |
| CV-24088 | 5/4/2026 1:51:55 PM | 100.1 | -2.03 | -1.98 | | | 1.968 | 1.927 | -7.61 | -7.59 |
| CV-24089 | 5/20/2026 11:52:44 AM | 99.0 | -7.28 | -7.29 | 0.0 | 0.0 | -0.012 | -0.010 | -7.30 | |
| CV-24089 | 5/20/2026 11:51:37 AM | 99.1 | -7.33 | -7.34 | 0.0 | 0.5 | -0.001 | 0.001 | -7.33 | |
| CV-24089 | 5/4/2026 11:15:57 AM | 71.8 | -8.91 | -8.88 | 0.0 | 0.0 | -0.019 | -0.017 | -8.82 | |
| CV-24089 | 5/4/2026 11:14:40 AM | 73.5 | -8.85 | -8.81 | 0.0 | 0.0 | -0.008 | -0.008 | -8.89 | |
| CV-24090 | 5/20/2026 11:45:41 AM | 120.2 | -0.70 | -0.70 | 0.0 | 0.0 | 0.698 | 0.698 | -7.71 | |
| CV-24090 | 5/11/2026 1:42:21 PM | 113.1 | -0.71 | -0.68 | | | 0.781 | 0.765 | -6.31 | -6.38 |
| CV-24090 | 5/6/2026 1:52:09 PM | 116.9 | -0.03 | -0.11 | | | 0.032 | 0.116 | -4.41 | -4.40 |
| CV-24091 | 5/21/2026 9:33:38 AM | 99.6 | -0.60 | -0.59 | 5.4 | 5.3 | 0.076 | 0.073 | -6.07 | -6.78 |
| CV-24091 | 5/4/2026 2:15:54 PM | 79.3 | -0.57 | -0.69 | 10.5 | 9.5 | 0.024 | 0.020 | -7.57 | |
| CV-24092 | 5/6/2026 10:10:24 AM | 120.7 | -2.34 | -2.42 | 0.0 | 0.0 | -2.306 | -3.024 | -9.10 | |
| CV-24093 | 5/22/2026 12:11:17 PM | 118.3 | -0.90 | -0.66 | 16.0 | 10.2 | 1.694 | 0.684 | -13.31 | |
| CV-24093 | 5/1/2026 3:13:57 PM | 118.5 | -0.06 | -0.07 | 14.2 | 14.2 | 1.362 | 1.363 | -12.91 | |
| CV-24094 | 5/22/2026 11:49:38 AM | 88.3 | -1.91 | -1.97 | 1.0 | 1.0 | 0.149 | 0.150 | -11.94 | |
| CV-24094 | 5/22/2026 11:48:00 AM | 87.0 | -4.45 | -2.49 | 1.4 | 1.0 | 0.255 | 0.120 | -11.15 | |
| CV-24094 | 5/1/2026 2:32:48 PM | 88.6 | -1.42 | -1.45 | 1.0 | 1.0 | 0.137 | 0.137 | -12.58 | |
| CV-24095 | 5/28/2026 10:32:51 AM | 179.1 | 0.32 | 0.14 | | | 0.000 | 0.000 | 0.16 | -0.59 |
| CV-24095 | 5/28/2026 10:30:18 AM | 179.3 | 0.50 | 0.47 | | | 0.000 | 0.000 | -0.54 | -0.22 |
| CV-24095 | 5/20/2026 10:30:33 AM | 178.7 | -2.17 | -2.41 | | | 2.175 | 2.373 | -4.22 | -4.45 |
| CV-24095 | 5/14/2026 1:28:11 PM | 178.7 | 1.35 | 0.75 | | | 0.000 | 0.000 | 0.24 | 0.81 |
| CV-24095 | 5/13/2026 10:56:02 AM | 178.3 | 0.59 | 0.95 | | | 0.000 | 0.000 | 0.62 | 1.83 |
| CV-24095 | 5/13/2026 10:53:04 AM | 177.9 | 0.91 | 1.66 | | | 0.000 | 0.000 | 0.65 | 1.13 |
| CV-24095 | 5/6/2026 10:46:15 AM | 176.2 | -1.28 | -1.30 | | | 1.269 | 1.290 | 0.34 | 0.34 |
| CV-24095 | 5/6/2026 10:45:00 AM | | | | | | | | | |
| CV-24095 | 5/6/2026 10:45:00 AM | | | | | | | | | |
| CV-24095 | 5/6/2026 8:05:00 AM | | | | | | | | | |
| CV-24095 | 5/6/2026 8:05:00 AM | | | | | | | | | |
| CV-24096 | 5/20/2026 10:19:24 AM | 98.5 | -2.34 | -1.97 | | | 2.330 | 1.963 | -3.33 | -3.16 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24096 | 5/12/2026 9:25:00 AM | 81.9 | -2.06 | -2.02 | 0.0 | 0.0 | 2.089 | 2.087 | -3.71 | |
| CV-24096 | 5/12/2026 9:22:51 AM | 81.8 | -2.99 | -1.86 | 0.0 | 0.0 | 3.021 | 1.991 | -3.62 | |
| CV-24097 | 5/20/2026 10:29:27 AM | 86.8 | -1.19 | -1.19 | | | 1.181 | 1.189 | -4.94 | -4.90 |
| CV-24097 | 5/20/2026 10:28:10 AM | 91.2 | -3.87 | -1.12 | | | 3.844 | 1.117 | -4.95 | -4.95 |
| CV-24097 | 5/12/2026 9:16:39 AM | 81.2 | -0.10 | -0.10 | 0.0 | 0.0 | 0.206 | 0.119 | -5.64 | |
| CV-24097 | 5/12/2026 9:13:02 AM | 87.4 | 0.02 | -0.04 | 0.0 | 0.0 | -0.237 | -0.349 | -5.38 | |
| CV-24098 | 5/20/2026 10:43:25 AM | 95.9 | -4.18 | -4.01 | | | 4.188 | 3.970 | -3.80 | -3.67 |
| CV-24098 | 5/3/2026 11:01:16 AM | 70.5 | -6.65 | -6.20 | | | 4.952 | 4.889 | -6.53 | -6.36 |
| CV-24098 | 5/3/2026 11:00:24 AM | 69.7 | -7.60 | -7.39 | | | 7.739 | 7.492 | -7.81 | -7.58 |
| CV-24098 | 5/1/2026 10:01:03 AM | 93.8 | -4.22 | -4.01 | | | 3.841 | 3.605 | -4.30 | -4.12 |
| CV-24099 | 5/20/2026 10:48:09 AM | 97.6 | -0.54 | -0.48 | | | 0.549 | 0.494 | -3.60 | -3.52 |
| CV-24099 | 5/3/2026 10:28:51 AM | 61.5 | -1.09 | -1.03 | | | 1.101 | 1.051 | -6.43 | -3.83 |
| CV-24099 | 5/3/2026 10:28:19 AM | 61.4 | -0.90 | -1.00 | | | 0.905 | 1.013 | -7.63 | -7.22 |
| CV-24099 | 5/3/2026 10:27:26 AM | 61.4 | -0.01 | -1.06 | | | 0.000 | 1.044 | -7.32 | -6.38 |
| CV-24099 | 5/1/2026 10:08:04 AM | 83.2 | -4.81 | -4.58 | | | 4.424 | 4.479 | -4.91 | -5.27 |
| CV-24100 | 5/28/2026 10:02:06 AM | 148.5 | -0.47 | -0.51 | | | 0.459 | 0.512 | -4.78 | -4.75 |
| CV-24100 | 5/20/2026 10:01:19 AM | 149.5 | -2.99 | -2.99 | | | 3.025 | 3.008 | -6.69 | -6.55 |
| CV-24100 | 5/20/2026 10:00:42 AM | 150.4 | 0.10 | -2.39 | | | 0.000 | 2.400 | -6.84 | -6.73 |
| CV-24100 | 5/20/2026 9:37:52 AM | 151.5 | -0.21 | -0.23 | | | 0.219 | 0.240 | -7.51 | -7.54 |
| CV-24100 | 5/20/2026 9:36:36 AM | 150.9 | -1.42 | -0.31 | | | 1.419 | 0.310 | -7.43 | -7.41 |
| CV-24100 | 5/13/2026 10:42:49 AM | 143.8 | -2.64 | -2.64 | | | 2.642 | 2.642 | -7.80 | -7.80 |
| CV-24100 | 5/13/2026 10:41:16 AM | 141.9 | -7.76 | -2.95 | | | 7.702 | 2.953 | -7.76 | -7.70 |
| CV-24100 | 5/13/2026 8:25:00 AM | | | | | | | | | |
| CV-24100 | 5/13/2026 8:25:00 AM | | | | | | | | | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24100 | 5/7/2026 11:06:06 AM | 146.9 | -3.18 | -3.18 | | | 3.160 | 3.159 | -3.06 | -3.06 |
| CV-24100 | 5/7/2026 11:05:00 AM | | | | | | | | | |
| CV-24100 | 5/7/2026 11:05:00 AM | | | | | | | | | |
| CV-24100 | 5/7/2026 11:04:29 AM | 146.0 | 2.22 | -2.88 | | | 0.000 | 2.849 | -3.06 | -3.22 |
| CV-24100 | 5/1/2026 10:25:18 AM | 147.6 | -0.61 | -0.60 | | | 0.582 | 0.572 | -8.60 | -8.69 |
| CV-24101 | 5/20/2026 9:41:50 AM | 115.3 | -7.37 | -7.22 | | | 7.534 | 7.438 | -7.34 | -7.38 |
| CV-24101 | 5/12/2026 8:51:03 AM | 112.4 | -7.47 | -7.36 | 0.0 | 0.0 | 7.674 | 7.698 | -7.01 | |
| CV-24101 | 5/6/2026 7:40:00 AM | | | | | | | | | |
| CV-24101 | 5/6/2026 7:40:00 AM | | | | | | | | | |
| CV-24101 | 5/1/2026 10:20:22 AM | | -7.56 | | | | 7.603 | | -7.94 | |
| CV-24102 | 5/19/2026 10:30:38 AM | 103.0 | -0.48 | -0.48 | | | 0.478 | 0.482 | -6.89 | -6.89 |
| CV-24102 | 5/4/2026 9:42:22 AM | 89.0 | -0.59 | -0.59 | | | 0.596 | 0.590 | -8.51 | -8.62 |
| CV-24103 | 5/20/2026 9:42:52 AM | 95.8 | -0.95 | -0.95 | 5.0 | 4.6 | 0.488 | 0.412 | -8.39 | |
| CV-24103 | 5/4/2026 9:28:18 AM | 95.4 | -1.15 | -1.13 | 5.6 | 5.1 | 0.631 | 0.529 | -9.08 | |
| CV-24104 | 5/20/2026 12:16:58 PM | 96.5 | -1.12 | -0.95 | 2.8 | 2.2 | 0.931 | 0.571 | -6.94 | |
| CV-24104 | 5/4/2026 9:39:11 AM | 93.1 | -3.25 | -2.75 | 3.5 | 1.2 | 0.247 | 0.032 | -8.54 | |
| CV-24105 | 5/20/2026 11:35:42 AM | 109.2 | -0.32 | -0.30 | 8.9 | 8.9 | 0.488 | 0.489 | -7.40 | |
| CV-24105 | 5/4/2026 9:49:47 AM | 102.3 | -0.52 | -0.52 | 10.3 | 12.2 | 0.631 | 0.893 | -8.73 | |
| CV-24106 | 5/28/2026 12:51:23 PM | 127.9 | -1.50 | -1.50 | 10.7 | 10.8 | 0.316 | 0.320 | -13.59 | -13.68 |
| CV-24106 | 5/20/2026 2:33:03 PM | 128.8 | -0.83 | -0.70 | 0.0 | 0.0 | -0.963 | -1.111 | -8.97 | |
| CV-24106 | 5/8/2026 11:07:42 AM | 127.2 | -0.57 | -0.54 | 8.0 | 5.2 | 0.171 | 0.072 | -6.25 | |
| CV-24107 | 5/4/2026 11:30:05 AM | 122.5 | -4.33 | -4.05 | | | 4.316 | 4.037 | -8.71 | -8.89 |
| CV-24108 | 5/28/2026 12:33:54 PM | 128.9 | -13.62 | -13.83 | 49.4 | 47.9 | 1.641 | 1.544 | -14.69 | -15.53 |
| CV-24108 | 5/4/2026 1:40:16 PM | 128.1 | -12.38 | -12.37 | 55.1 | 54.9 | 0.820 | 0.813 | -13.71 | -13.71 |
| CV-24109 | 5/4/2026 11:58:26 AM | 106.0 | -8.47 | -7.77 | | | 9.014 | 8.273 | -12.23 | -12.53 |
| CV-24110 | 5/1/2026 10:54:33 AM | 127.3 | -1.44 | -1.13 | 29.6 | 16.0 | 2.547 | 0.737 | -13.24 | |
| CV-24111 | 5/1/2026 11:14:00 AM | 111.5 | -7.44 | -6.42 | 0.0 | 0.0 | 7.382 | 6.288 | -11.95 | |
| CV-24112 | 5/1/2026 11:04:34 AM | 127.7 | -1.05 | -0.90 | 14.3 | 10.8 | 0.542 | 0.310 | -12.39 | |
| CV-24114 | 5/5/2026 2:47:36 PM | 119.9 | -9.32 | -9.32 | 4.6 | 4.6 | 0.057 | 0.057 | -9.46 | |
| CV-24116 | 5/11/2026 9:58:53 AM | 126.6 | -7.93 | -5.48 | 0.0 | 0.0 | 7.987 | 5.245 | -10.77 | |
| CV-24117 | 5/28/2026 12:44:53 PM | 101.7 | -1.33 | -1.33 | | | 1.317 | 1.317 | -15.47 | -15.56 |
| CV-24117 | 5/4/2026 10:48:48 AM | 90.0 | -1.32 | -1.32 | | | 1.305 | 1.306 | -14.35 | -14.47 |
| CV-24118 | 5/11/2026 1:37:44 PM | 128.9 | -1.81 | -1.84 | | | 1.750 | 1.762 | -12.57 | -12.23 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24119 | 5/8/2026 2:33:20 PM | 144.1 | -4.47 | -4.45 | | | 4.365 | 4.288 | -12.29 | -12.35 |
| CV-24119 | 5/8/2026 2:32:34 PM | 143.9 | -5.72 | -5.09 | | | 5.665 | 5.068 | -11.98 | -12.29 |
| CV-24119 | 5/7/2026 10:38:27 AM | 137.4 | -0.12 | -0.14 | 0.0 | 0.0 | 0.105 | 0.223 | -3.72 | |
| CV-24119 | 5/7/2026 10:35:25 AM | 137.3 | -0.27 | -0.29 | 0.0 | 0.0 | 0.247 | 0.320 | -4.00 | |
| CV-24120 | 5/26/2026 2:15:09 PM | 89.0 | -8.11 | -7.69 | | | 8.054 | 7.880 | -7.45 | -7.59 |
| CV-24120 | 5/11/2026 10:28:50 AM | 98.1 | -1.16 | -1.18 | | | 1.186 | 1.219 | -1.37 | -1.37 |
| CV-24120 | 5/4/2026 8:00:00 AM | | | | | | | | | |
| CV-24121 | 5/26/2026 2:08:29 PM | 78.2 | -8.13 | -0.55 | | | 8.299 | 0.533 | -8.06 | -8.01 |
| CV-24121 | 5/11/2026 10:33:56 AM | 101.4 | -1.05 | -0.86 | | | 1.054 | 0.869 | -1.27 | -0.87 |
| CV-24121 | 5/11/2026 10:33:18 AM | 101.3 | -0.80 | -0.82 | | | 0.812 | 0.830 | -0.89 | -0.97 |
| CV-24121 | 5/4/2026 7:55:00 AM | | | | | | | | | |
| CV-24122 | 5/29/2026 9:40:41 AM | 81.5 | -2.22 | -2.27 | 0.7 | 0.0 | 0.028 | -0.023 | -4.97 | |
| CV-24122 | 5/29/2026 9:33:20 AM | 76.9 | -4.68 | -2.41 | 0.5 | 0.0 | 0.015 | -0.017 | -5.20 | |
| CV-24122 | 5/6/2026 10:31:06 AM | 85.9 | -2.43 | -2.92 | 1.8 | 2.8 | 0.156 | 0.396 | -0.81 | -1.19 |
| CV-24122 | 5/4/2026 8:20:00 AM | | | | | | | | | |
| CV-24123 | 5/28/2026 11:46:50 AM | 116.7 | 0.63 | 0.60 | 6.3 | 5.6 | 0.107 | 0.084 | 0.47 | 0.33 |
| CV-24123 | 5/28/2026 11:46:25 AM | 116.6 | 0.65 | 0.67 | 8.9 | 5.9 | 0.215 | 0.094 | 0.42 | 0.29 |
| CV-24123 | 5/15/2026 11:28:22 AM | 113.9 | -0.16 | -0.16 | 3.7 | 3.7 | 0.042 | 0.043 | -0.44 | |
| CV-24123 | 5/15/2026 11:24:46 AM | 112.5 | 3.24 | -0.20 | 3.5 | 2.0 | 0.038 | 0.013 | -2.56 | |
| CV-24123 | 5/14/2026 10:54:34 AM | 117.3 | 0.18 | 0.18 | 19.2 | 20.5 | 0.994 | 1.128 | 0.29 | 0.00 |
| CV-24123 | 5/14/2026 10:53:53 AM | 117.1 | 0.40 | 0.33 | 18.5 | 21.3 | 0.925 | 1.222 | 0.34 | 0.04 |
| CV-24124 | 5/29/2026 11:28:31 AM | 127.0 | -1.49 | -1.46 | 0.0 | 0.0 | 1.486 | 1.529 | -5.53 | |
| CV-24125-TP2 | 5/26/2026 1:56:27 PM | 99.8 | -1.35 | -1.41 | | | 1.297 | 1.385 | -3.85 | -3.22 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24125-TP2 | 5/13/2026 7:55:00 AM | | | | | | | | | |
| CV-24125-TP2 | 5/13/2026 7:55:00 AM | | | | | | | | | |
| CV-24126 | 5/26/2026 10:58:38 AM | 187.1 | -2.02 | -1.91 | | | 2.452 | 1.770 | -2.13 | -1.68 |
| CV-24126 | 5/22/2026 12:29:20 PM | 188.6 | -0.30 | -0.38 | | | 0.276 | 0.835 | -1.18 | -1.26 |
| CV-24126 | 5/22/2026 12:28:40 PM | 188.5 | -0.20 | -0.22 | | | 0.265 | 0.416 | -1.11 | -1.07 |
| CV-24126 | 5/18/2026 10:50:00 AM | | | | | | | | | |
| CV-24126 | 5/18/2026 10:44:28 AM | 186.3 | 1.42 | 1.36 | | | 0.000 | 0.000 | 1.78 | 1.71 |
| CV-24126 | 5/18/2026 10:43:37 AM | 187.2 | 1.28 | 1.80 | | | 0.000 | 0.000 | 1.52 | 1.93 |
| CV-24126 | 5/12/2026 10:30:00 AM | | | | | | | | | |
| CV-24126 | 5/12/2026 10:28:41 AM | 188.4 | -2.83 | -2.62 | | | 2.743 | 2.583 | -2.72 | -2.45 |
| CV-24126 | 5/4/2026 2:50:00 PM | | | | | | | | | |
| CV-24126 | 5/4/2026 2:50:00 PM | | | | | | | | | |
| CV-24126 | 5/4/2026 2:40:40 PM | 187.1 | -2.12 | -2.63 | | | 1.963 | 2.083 | -2.27 | -2.45 |
| CV-24127 | 5/7/2026 10:22:55 AM | 141.2 | 2.20 | 2.31 | | | 0.000 | 0.000 | 0.32 | 0.34 |
| CV-24127 | 5/7/2026 10:21:43 AM | 141.1 | 5.40 | 2.26 | | | 0.000 | 0.000 | 0.32 | 0.33 |
| CV-24127 | 5/7/2026 10:20:00 AM | | | | | | | | | |
| CV-24127 | 5/7/2026 10:20:00 AM | | | | | | | | | |
| CV-24127 | 5/4/2026 8:15:00 AM | | | | | | | | | |
| CV-24128 | 5/26/2026 2:25:15 PM | 91.7 | -1.98 | -1.98 | | | 1.926 | 1.931 | -10.24 | -10.61 |
| CV-24128 | 5/13/2026 7:50:00 AM | | | | | | | | | |
| CV-24128 | 5/13/2026 7:50:00 AM | | | | | | | | | |
| CV-24128 | 5/8/2026 9:33:23 AM | 99.5 | -0.86 | -0.77 | 0.0 | 0.0 | 0.748 | 0.739 | -3.16 | |
| CV-24129 | 5/26/2026 1:33:50 PM | 121.1 | -5.09 | -5.15 | | | 5.194 | 5.324 | -12.17 | -12.90 |
| CV-24129 | 5/8/2026 9:24:27 AM | 122.5 | -1.60 | -1.58 | 0.0 | 0.0 | 1.696 | 1.645 | -3.75 | |
| CV-24130 | 5/26/2026 1:42:41 PM | 109.0 | -9.86 | -7.80 | | | 10.033 | 7.913 | -11.29 | -11.40 |
| CV-24131 | 5/29/2026 1:47:07 PM | 120.1 | -1.78 | -1.09 | 16.4 | 11.1 | 0.744 | 0.340 | -8.14 | |
| CV-24132 | 5/6/2026 10:15:34 AM | 129.4 | -4.57 | -4.74 | 42.2 | 43.0 | 0.469 | 0.486 | -7.48 | -7.96 |
| CV-24133 | 5/7/2026 9:28:04 AM | 121.5 | -2.04 | -2.05 | 12.5 | 12.7 | 0.402 | 0.418 | -3.18 | |
| CV-24134-TP1 | 5/26/2026 10:55:47 AM | 151.4 | -3.84 | -3.90 | | | 3.849 | 3.874 | -5.03 | -5.38 |
| CV-24134-TP1 | 5/18/2026 10:45:00 AM | | | | | | | | | |
| CV-24134-TP1 | 5/18/2026 10:39:38 AM | 151.6 | -0.11 | -0.08 | | | 0.000 | 0.000 | -1.01 | -1.22 |
| CV-24134-TP1 | 5/12/2026 10:35:00 AM | | | | | | | | | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24134-TP1 | 5/12/2026 10:33:32 AM | 150.9 | -2.75 | -2.74 | | | 2.745 | 2.735 | -4.05 | -4.05 |
| CV-24134-TP1 | 5/12/2026 10:32:12 AM | 150.8 | 0.95 | -2.25 | | | 0.000 | 2.255 | -4.10 | -3.95 |
| CV-24134-TP1 | 5/11/2026 2:33:48 PM | 146.9 | -1.74 | -1.76 | 0.0 | 0.0 | 1.833 | 1.831 | -5.30 | |
| CV-24134-TP1 | 5/11/2026 2:29:03 PM | 146.4 | -4.14 | -1.81 | 0.0 | 0.0 | 4.209 | 1.833 | -5.22 | |
| CV-24134-TP1 | 5/7/2026 1:15:00 PM | | | | | | | | | |
| CV-24134-TP1 | 5/7/2026 1:14:04 PM | 149.5 | -0.65 | -0.62 | | | 0.632 | 0.602 | -0.30 | -0.30 |
| CV-24135 | 5/11/2026 2:17:55 PM | 140.7 | -0.51 | -0.52 | 0.0 | 0.0 | 0.565 | 0.568 | -5.20 | |
| CV-24135 | 5/11/2026 2:15:34 PM | 140.7 | 2.11 | -0.33 | 0.0 | 0.0 | -2.031 | 0.558 | -5.32 | |
| CV-24136 | 5/11/2026 11:29:51 AM | 125.6 | -4.72 | -4.08 | 0.0 | 0.0 | 4.598 | 3.945 | -6.96 | |
| CV-24137 | 5/4/2026 1:08:31 PM | 75.6 | -0.10 | -0.12 | | | 0.147 | 0.134 | 0.17 | 0.29 |
| CV-24137 | 5/4/2026 1:07:02 PM | 74.0 | 3.07 | -0.10 | | | 0.000 | 0.179 | 0.19 | 0.22 |
| CV-24138 | 5/28/2026 9:03:38 AM | 96.9 | -2.02 | -1.80 | | | 2.744 | 1.725 | -1.85 | -1.33 |
| CV-24138 | 5/28/2026 9:02:31 AM | 95.5 | -2.69 | -2.09 | | | 2.751 | 2.112 | -2.20 | -1.67 |
| CV-24138 | 5/13/2026 1:14:42 PM | 131.6 | -0.58 | -0.38 | | | 0.568 | 0.314 | -0.52 | -0.30 |
| CV-24138 | 5/6/2026 11:00:00 AM | | | | | | | | | |
| CV-24138 | 5/6/2026 11:00:00 AM | | | | | | | | | |
| CV-24138 | 5/6/2026 10:58:19 AM | 160.2 | -3.80 | -3.60 | | | 3.840 | 3.429 | 0.32 | 0.34 |
| CV-24138 | 5/5/2026 8:15:00 AM | | | | | | | | | |
| CV-24138 | 5/5/2026 8:15:00 AM | | | | | | | | | |
| CV-24139 | 5/28/2026 9:08:34 AM | 125.5 | -6.44 | -6.10 | | | 6.765 | 6.401 | -6.76 | -6.69 |
| CV-24139 | 5/15/2026 8:22:50 AM | 139.8 | -0.21 | -0.20 | | | 0.213 | 0.202 | -6.72 | -6.33 |
| CV-24139 | 5/15/2026 8:12:50 AM | 136.1 | 25.00 | -0.23 | | | 0.000 | 0.227 | -6.42 | -6.14 |
| CV-24139 | 5/5/2026 8:10:00 AM | | | | | | | | | |
| CV-24139 | 5/5/2026 8:10:00 AM | | | | | | | | | |
| CV-24140 | 5/28/2026 10:52:29 AM | 170.8 | -1.75 | -1.97 | | | 1.726 | 1.959 | -5.22 | -4.88 |
| CV-24140 | 5/28/2026 10:50:34 AM | 170.8 | 5.74 | -1.38 | | | 0.000 | 1.356 | -4.68 | -4.83 |
| CV-24140 | 5/20/2026 1:28:20 PM | 148.4 | -2.42 | -2.47 | | | 2.416 | 2.451 | -3.40 | -3.74 |
| CV-24140 | 5/20/2026 1:26:41 PM | 148.5 | -3.62 | -2.56 | | | 3.630 | 2.558 | -3.60 | -3.62 |
| CV-24140 | 5/13/2026 1:18:30 PM | 157.7 | -2.58 | -2.53 | | | 2.565 | 2.555 | -4.54 | -4.03 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24140 | 5/6/2026 11:05:00 AM | | | | | | | | | |
| CV-24140 | 5/6/2026 11:05:00 AM | | | | | | | | | |
| CV-24140 | 5/6/2026 11:04:58 AM | 164.9 | -5.03 | -5.03 | | | 4.753 | 4.753 | -5.22 | -5.24 |
| CV-24140 | 5/5/2026 8:05:00 AM | | | | | | | | | |
| CV-24140 | 5/5/2026 8:05:00 AM | | | | | | | | | |
| CV-24141 | 5/28/2026 9:31:07 AM | 65.9 | -5.95 | -5.76 | | | 6.238 | 6.176 | -5.94 | -5.76 |
| CV-24141 | 5/28/2026 9:30:26 AM | 65.7 | -6.76 | -5.94 | | | 7.127 | 6.330 | -7.11 | -5.99 |
| CV-24141 | 5/5/2026 7:45:00 AM | | | | | | | | | |
| CV-24141 | 5/5/2026 7:45:00 AM | | | | | | | | | |
| CV-24141 | 5/1/2026 8:57:18 AM | 76.3 | -0.08 | -0.95 | | | 0.073 | 0.928 | -6.86 | -6.53 |
| CV-24142 | 5/28/2026 10:41:54 AM | 100.8 | -1.89 | -1.89 | | | 1.876 | 1.890 | -1.58 | -1.60 |
| CV-24142 | 5/28/2026 10:40:43 AM | 100.7 | -1.92 | -1.91 | | | 1.912 | 1.936 | -1.66 | -1.68 |
| CV-24142 | 5/20/2026 1:14:55 PM | 151.1 | -2.68 | -2.87 | | | 2.629 | 2.780 | 0.00 | -0.04 |
| CV-24142 | 5/20/2026 1:02:37 PM | 151.5 | -3.36 | -2.50 | | | 3.313 | 2.494 | -3.07 | -2.49 |
| CV-24142 | 5/15/2026 8:03:40 AM | 174.7 | -3.95 | -3.94 | | | 3.946 | 3.985 | -4.77 | -4.78 |
| CV-24142 | 5/15/2026 7:59:13 AM | 174.0 | -4.10 | -4.10 | | | 4.115 | 4.115 | -4.96 | -4.96 |
| CV-24142 | 5/14/2026 8:35:00 AM | | | | | | | | | |
| CV-24142 | 5/6/2026 8:10:00 AM | | | | | | | | | |
| CV-24142 | 5/6/2026 8:10:00 AM | | | | | | | | | |
| CV-24143 | 5/28/2026 9:20:03 AM | 72.4 | -6.42 | -6.44 | | | 6.724 | 6.767 | -6.31 | -6.38 |
| CV-24143 | 5/28/2026 9:19:15 AM | 72.9 | -7.01 | -6.42 | | | 7.249 | 6.661 | -6.80 | -6.27 |
| CV-24143 | 5/5/2026 7:55:00 AM | | | | | | | | | |
| CV-24143 | 5/5/2026 7:55:00 AM | | | | | | | | | |
| CV-24143 | 5/1/2026 2:16:44 PM | 96.8 | -2.80 | -2.85 | 0.0 | 0.0 | 2.808 | 2.964 | -4.29 | |
| CV-24143 | 5/1/2026 2:15:01 PM | 97.6 | -4.24 | -2.26 | 0.0 | 0.0 | 4.120 | 2.401 | -4.36 | |
| CV-24144 | 5/20/2026 10:35:16 AM | 100.3 | -4.49 | -4.52 | | | 4.462 | 4.516 | -4.27 | -4.34 |
| CV-24144 | 5/12/2026 9:03:44 AM | 88.3 | -4.85 | -4.84 | 0.0 | 0.0 | 4.953 | 4.881 | -4.77 | |
| CV-24145 | 5/26/2026 2:12:30 PM | 105.8 | -8.40 | -8.38 | | | 0.000 | 0.000 | -9.24 | -8.44 |
| CV-24145 | 5/18/2026 2:54:25 PM | 145.7 | -2.63 | -2.56 | | | 0.000 | 0.141 | -3.22 | -3.74 |
| CV-24145 | 5/18/2026 2:45:00 PM | | | | | | | | | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24145 | 5/18/2026 2:38:58 PM | 146.8 | -0.66 | -0.63 | | | 2.650 | 2.653 | -0.40 | -0.38 |
| CV-24145 | 5/12/2026 2:40:29 PM | 163.8 | -4.56 | -4.58 | | | 0.000 | 0.000 | -7.74 | -7.43 |
| CV-24145 | 5/12/2026 2:34:47 PM | 161.5 | -4.85 | -4.85 | | | 0.851 | 0.822 | -7.28 | -7.14 |
| CV-24145 | 5/12/2026 2:32:19 PM | 162.7 | -6.13 | -5.73 | | | 2.042 | 1.210 | -6.49 | -6.94 |
| CV-24145 | 5/12/2026 2:15:00 PM | | | | | | | | | |
| CV-24145 | 5/5/2026 1:25:00 PM | | | | | | | | | |
| CV-24145 | 5/5/2026 1:25:00 PM | | | | | | | | | |
| CV-24145 | 5/5/2026 1:22:41 PM | 171.5 | -7.02 | -7.01 | | | 0.876 | 0.868 | -8.22 | -9.16 |
| CV-24146 | 5/28/2026 10:15:05 AM | 106.4 | 1.38 | 1.31 | 4.3 | 7.4 | 0.024 | 0.070 | 1.49 | 1.48 |
| CV-24146 | 5/28/2026 10:14:14 AM | 107.5 | 1.16 | 1.34 | 6.3 | 2.1 | 0.051 | 0.006 | 1.35 | 1.59 |
| CV-24146 | 5/11/2026 9:52:43 AM | 115.2 | -0.09 | -0.10 | 13.8 | 13.8 | 0.246 | 0.246 | -0.46 | -0.38 |
| CV-24147 | 5/28/2026 11:28:34 AM | 102.6 | -0.31 | -0.37 | 22.3 | 23.8 | 0.124 | 0.141 | -0.23 | -0.38 |
| CV-24147 | 5/26/2026 9:21:12 AM | 100.4 | -1.00 | -0.99 | 1.7 | 0.6 | 0.001 | 0.000 | -1.02 | -1.02 |
| CV-24147 | 5/14/2026 2:08:02 PM | 108.2 | -1.51 | -1.53 | 13.4 | 5.4 | 0.045 | 0.007 | -1.59 | -1.71 |
| CV-24147 | 5/11/2026 10:06:39 AM | | -0.66 | -0.73 | 6.9 | 11.5 | 0.012 | 0.034 | -0.81 | -0.96 |
| CV-24147 | 5/11/2026 10:05:05 AM | 110.6 | -0.58 | -0.71 | 6.9 | 8.0 | 0.012 | 0.016 | -0.78 | -0.96 |
| CV-24147 | 5/11/2026 10:02:23 AM | 109.5 | 0.56 | -0.07 | 6.0 | 5.2 | 0.009 | 0.007 | -0.93 | -0.77 |
| CV-24148 | 5/27/2026 1:49:59 PM | 168.8 | -3.52 | -3.48 | | | 3.481 | 3.361 | -7.43 | -7.35 |
| CV-24148 | 5/19/2026 1:50:00 PM | | | | | | | | | |
| CV-24148 | 5/19/2026 1:44:57 PM | 171.8 | -3.45 | -3.56 | | | 3.468 | 3.577 | -9.45 | -9.38 |
| CV-24148 | 5/19/2026 1:43:50 PM | 172.7 | -7.79 | -4.26 | | | 7.808 | 4.299 | -9.07 | -9.22 |
| CV-24148 | 5/11/2026 10:02:23 AM | 178.6 | -4.29 | -3.94 | | | 4.261 | 3.909 | -13.74 | -13.72 |
| CV-24148 | 5/4/2026 9:31:25 AM | 177.6 | -6.99 | -6.93 | | | 7.121 | 6.900 | -13.43 | -13.36 |
| CV-24148 | 5/4/2026 9:30:00 AM | | | | | | | | | |
| CV-24148 | 5/4/2026 9:30:00 AM | | | | | | | | | |
| CV-24149 | 5/28/2026 12:48:18 PM | 85.3 | -8.23 | -7.68 | 8.8 | 9.2 | 0.025 | 0.027 | | |
| CV-24149 | 5/6/2026 2:58:21 PM | 96.1 | -8.33 | -8.37 | 14.3 | 5.5 | 0.051 | 0.008 | -10.23 | -10.08 |
| CV-24150 | 5/22/2026 11:53:52 AM | 108.5 | -1.38 | -1.05 | 0.0 | 0.0 | 1.294 | 0.967 | -11.23 | |
| CV-24150 | 5/1/2026 10:15:37 AM | 110.5 | -1.00 | -0.82 | 0.0 | 0.0 | 1.058 | 0.892 | -13.50 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24151 | 5/21/2026 1:59:13 PM | 102.8 | -2.29 | -2.19 | | | 2.205 | 2.163 | -4.47 | -4.44 |
| CV-24151 | 5/6/2026 2:05:59 PM | 88.0 | -4.39 | -4.28 | | | 4.287 | 4.203 | -6.52 | -5.75 |
| CV-24152 | 5/26/2026 8:32:21 AM | 129.7 | -0.10 | -0.11 | 17.9 | 17.1 | 0.765 | 0.696 | -3.96 | -4.00 |
| CV-24152 | 5/26/2026 8:31:06 AM | 129.8 | -0.43 | -0.12 | 19.9 | 17.2 | 0.941 | 0.707 | -3.78 | -3.81 |
| CV-24152 | 5/6/2026 2:21:42 PM | 131.4 | -0.22 | -0.13 | 29.0 | 29.6 | 1.996 | 2.088 | -3.33 | -3.30 |
| CV-24152 | 5/6/2026 2:21:09 PM | 131.3 | 0.31 | -0.07 | 23.7 | 28.6 | 1.327 | 1.939 | -3.29 | -3.40 |
| CV-24153 | 5/22/2026 11:40:23 AM | 111.9 | -1.17 | -0.94 | 0.0 | 0.0 | 1.108 | 0.879 | -11.73 | |
| CV-24153 | 5/1/2026 3:03:06 PM | 104.1 | -0.20 | -0.20 | 0.0 | 0.0 | 0.183 | 0.172 | -12.52 | |
| CV-24153 | 5/1/2026 3:02:03 PM | 103.9 | 0.45 | -0.05 | 0.0 | 0.0 | -0.485 | 0.024 | -12.49 | |
| CV-24154 | 5/22/2026 11:58:09 AM | 111.5 | -2.26 | -1.99 | 0.0 | 0.0 | 2.165 | 1.946 | -7.87 | |
| CV-24154 | 5/1/2026 3:20:22 PM | 103.0 | -1.41 | -0.76 | 0.0 | 0.0 | 1.453 | 0.854 | -7.55 | |
| CV-24155 | 5/26/2026 8:18:02 AM | 119.3 | -0.44 | -0.44 | | | 0.428 | 0.427 | -7.66 | -7.66 |
| CV-24155 | 5/1/2026 3:09:53 PM | 119.0 | -0.07 | -0.07 | 0.0 | 0.0 | 0.058 | 0.052 | -9.99 | |
| CV-24155 | 5/1/2026 3:08:32 PM | 115.8 | 0.33 | -0.02 | 0.0 | 0.0 | -0.386 | -0.020 | -10.00 | |
| CV-24156 | 5/22/2026 2:00:28 PM | 123.0 | -0.79 | -0.56 | 20.3 | 20.4 | 0.106 | 0.107 | -0.55 | |
| CV-24156 | 5/4/2026 2:11:53 PM | 122.4 | -0.29 | -0.24 | 13.7 | 19.0 | 0.049 | 0.094 | -8.06 | -8.06 |
| CV-24157 | 5/21/2026 2:09:04 PM | 105.6 | -0.20 | -0.19 | | | 0.084 | 0.095 | -2.79 | -3.13 |
| CV-24157 | 5/21/2026 2:08:15 PM | 105.2 | 0.28 | -0.14 | | | 0.000 | 0.000 | -2.80 | -2.85 |
| CV-24157 | 5/4/2026 2:00:15 PM | 93.6 | -0.76 | -0.76 | | | 0.819 | 0.700 | -8.45 | -8.27 |
| CV-24158 | 5/21/2026 10:58:26 AM | 128.4 | -0.38 | -0.38 | 32.7 | 32.8 | 2.978 | 2.989 | -2.56 | -2.62 |
| CV-24158 | 5/6/2026 10:59:56 AM | 125.3 | -0.15 | -0.14 | 14.8 | 14.9 | 0.602 | 0.608 | -8.17 | -8.04 |
| CV-24159 | 5/21/2026 9:02:31 AM | 131.6 | -0.29 | -0.29 | 23.9 | 23.8 | 1.361 | 1.350 | -12.32 | -12.71 |
| CV-24159 | 5/21/2026 9:01:50 AM | 131.7 | -0.38 | -0.30 | 26.4 | 24.2 | 1.669 | 1.401 | -12.90 | -13.30 |
| CV-24159 | 5/6/2026 10:49:41 AM | 125.5 | -0.80 | -0.39 | 23.3 | 16.0 | 1.309 | 0.618 | -13.79 | |
| CV-24160 | 5/22/2026 12:06:28 PM | 127.0 | -3.82 | -3.36 | 31.7 | 27.8 | 2.393 | 1.835 | -12.52 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24160 | 5/6/2026 12:39:52 PM | 124.8 | -2.59 | -2.80 | 19.2 | 21.6 | 0.874 | 1.100 | -11.29 | -11.10 |
| CV-24160 | 5/6/2026 10:29:54 AM | 122.5 | -4.90 | -3.86 | 40.1 | 29.9 | 3.869 | 2.157 | -14.16 | |
| CV-24161 | 5/6/2026 10:20:39 AM | 111.3 | -0.26 | -0.26 | 0.0 | 0.0 | 0.254 | 0.252 | -14.46 | |
| CV-24161 | 5/6/2026 10:19:18 AM | 108.8 | 0.05 | -0.14 | 0.0 | 0.0 | -0.094 | 0.190 | -14.32 | |
| CV-24162 | 5/4/2026 12:02:44 PM | 86.5 | -0.45 | -0.34 | | | 0.416 | 0.317 | -13.70 | -13.52 |
| CV-24163 | 5/1/2026 2:33:25 PM | 129.3 | -0.37 | -0.37 | | | 0.411 | 0.374 | -12.81 | -12.47 |
| CV-24163 | 5/1/2026 2:32:24 PM | 131.4 | -2.55 | -1.37 | | | 2.539 | 1.302 | -12.74 | -12.76 |
| CV-24164 | 5/20/2026 2:08:15 PM | 132.0 | -0.14 | -0.13 | | | 0.092 | 0.078 | -6.78 | -6.96 |
| CV-24164 | 5/20/2026 2:06:56 PM | 132.1 | -0.65 | -0.12 | | | 0.705 | 0.124 | -6.75 | -6.87 |
| CV-24164 | 5/20/2026 11:14:31 AM | 100.1 | -0.99 | -0.92 | | | 0.955 | 0.903 | -6.39 | -6.61 |
| CV-24164 | 5/4/2026 10:23:58 AM | 130.5 | -0.38 | -1.29 | | | 0.374 | 1.251 | -9.01 | -8.95 |
| CV-24165 | 5/20/2026 11:18:42 AM | 122.0 | -1.44 | -0.89 | | | 1.378 | 0.850 | -5.52 | -5.75 |
| CV-24165 | 5/14/2026 11:24:07 AM | 132.6 | -0.35 | -0.37 | 0.0 | 0.0 | 0.426 | 0.586 | -2.22 | |
| CV-24165 | 5/14/2026 11:22:03 AM | 133.2 | 11.87 | -0.25 | 0.0 | 0.0 | -10.037 | 0.779 | -2.07 | |
| CV-24166 | 5/21/2026 9:08:04 AM | 123.2 | -4.53 | -4.54 | | | 4.427 | 4.420 | -5.21 | -4.93 |
| CV-24166 | 5/20/2026 11:21:55 AM | 128.2 | -0.25 | -0.25 | | | 0.224 | 0.224 | -6.06 | -6.06 |
| CV-24166 | 5/6/2026 10:54:07 AM | 106.9 | -5.34 | -5.32 | 0.0 | 0.0 | 5.252 | 5.163 | -6.56 | |
| CV-24167 | 5/28/2026 8:45:13 AM | 110.3 | -3.01 | -3.02 | | | 3.032 | 3.038 | -7.54 | -7.60 |
| CV-24167 | 5/6/2026 9:59:13 AM | 112.4 | -1.44 | -1.43 | 0.0 | 0.0 | 1.485 | 1.476 | -7.35 | |
| CV-24168 | 5/28/2026 8:59:25 AM | 104.4 | -1.66 | -1.66 | | | 1.665 | 1.677 | -7.37 | -7.38 |
| CV-24168 | 5/6/2026 10:55:15 AM | | -0.71 | | | | 0.693 | | -3.97 | |
| CV-24169 | 5/20/2026 11:11:16 AM | 100.1 | -0.20 | -0.18 | | | 0.173 | 0.156 | -6.69 | -6.69 |
| CV-24169 | 5/4/2026 10:19:18 AM | 115.0 | -0.26 | -0.26 | | | 0.270 | 0.270 | -8.88 | -8.59 |
| CV-24170 | 5/21/2026 9:20:08 AM | 127.0 | -0.14 | -0.14 | 24.1 | 24.1 | 0.145 | 0.145 | -4.05 | -4.21 |
| CV-24170 | 5/6/2026 8:37:17 AM | 125.6 | -0.53 | -0.54 | 12.2 | 13.7 | 0.037 | 0.046 | -8.49 | -8.45 |
| CV-24170 | 5/1/2026 10:56:54 AM | 126.9 | -0.04 | -0.04 | 11.9 | 12.5 | 0.035 | 0.039 | -8.20 | -8.14 |
| CV-24171 | 5/21/2026 9:23:58 AM | 127.2 | -0.96 | -0.94 | 16.0 | 14.5 | 0.339 | 0.279 | 0.46 | 0.36 |
| CV-24171 | 5/6/2026 10:03:52 AM | 123.6 | -0.59 | -0.69 | 15.5 | 17.4 | 0.290 | 0.369 | -8.38 | |
| CV-24172 | 5/21/2026 10:00:21 AM | 121.6 | -0.26 | -0.27 | 9.7 | 9.7 | 0.257 | 0.259 | -5.50 | -5.92 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24172 | 5/4/2026 2:28:48 PM | 116.3 | -0.47 | -0.45 | 0.0 | 0.0 | -0.468 | -0.465 | -8.13 | |
| CV-24173 | 5/21/2026 10:06:44 AM | 115.4 | -1.20 | -1.19 | 21.8 | 21.4 | 1.110 | 1.066 | 0.67 | 0.67 |
| CV-24173 | 5/6/2026 1:00:35 PM | 113.8 | -0.74 | -0.83 | 14.9 | 16.4 | 0.513 | 0.620 | -4.90 | -5.46 |
| CV-24174 | 5/21/2026 10:15:48 AM | 111.1 | -1.79 | -1.79 | | | 1.741 | 1.753 | -5.11 | -5.08 |
| CV-24174 | 5/11/2026 1:20:08 PM | 111.9 | -2.10 | -2.10 | | | 2.103 | 2.090 | -6.22 | -6.17 |
| CV-24175 | 5/21/2026 10:19:57 AM | 121.4 | -0.72 | -0.70 | 13.0 | 13.3 | 0.459 | 0.482 | -5.09 | -4.91 |
| CV-24175 | 5/5/2026 1:28:08 PM | 120.6 | -1.01 | -1.00 | 30.7 | 31.3 | 0.607 | 0.628 | -8.48 | -8.48 |
| CV-24175 | 5/5/2026 1:26:42 PM | 121.3 | -0.89 | -0.89 | 32.8 | 32.6 | 0.694 | 0.683 | -8.54 | -7.89 |
| CV-24175 | 5/5/2026 1:21:04 PM | 121.8 | -0.66 | -0.75 | 28.4 | 30.5 | 0.519 | 0.599 | -8.23 | -8.22 |
| CV-24175 | 5/5/2026 1:13:21 PM | 122.7 | -0.49 | -0.55 | 25.2 | 28.1 | 1.739 | 2.167 | -8.39 | -8.38 |
| CV-24176 | 5/20/2026 10:16:41 AM | 130.7 | -0.71 | -0.71 | 8.2 | 8.2 | 0.230 | 0.228 | -7.23 | |
| CV-24176 | 5/20/2026 10:14:10 AM | 130.8 | -1.92 | -0.82 | 15.8 | 8.5 | 0.796 | 0.230 | -7.29 | |
| CV-24176 | 5/8/2026 11:05:11 AM | 137.8 | -0.23 | -0.22 | 16.4 | 16.4 | 0.979 | 0.978 | -3.35 | |
| CV-24176 | 5/8/2026 11:03:01 AM | 136.7 | 0.92 | -0.10 | 10.6 | 17.8 | 0.403 | 1.164 | -3.26 | |
| CV-24177 | 5/20/2026 8:06:52 AM | 131.5 | -0.57 | -0.55 | | | 0.563 | 0.547 | -8.42 | -8.49 |
| CV-24177 | 5/20/2026 7:56:33 AM | 134.2 | -2.20 | -1.01 | | | 2.175 | 0.996 | -9.06 | -9.12 |
| CV-24177 | 5/8/2026 11:20:50 AM | 126.2 | -1.17 | -1.16 | 0.0 | 0.0 | 1.178 | 1.178 | -4.57 | |
| CV-24177 | 5/8/2026 11:19:26 AM | 126.5 | -2.80 | -1.42 | 0.0 | 0.0 | 2.765 | 1.314 | -4.47 | |
| CV-24178 | 5/20/2026 12:02:57 PM | 130.6 | -0.63 | -0.60 | 8.1 | 8.1 | 0.199 | 0.201 | -6.74 | |
| CV-24178 | 5/20/2026 12:01:45 PM | 130.9 | -1.01 | -0.56 | 15.7 | 9.3 | 0.760 | 0.263 | -6.71 | |
| CV-24178 | 5/8/2026 10:58:25 AM | 129.4 | -0.11 | -0.10 | 13.0 | 12.4 | 0.518 | 0.473 | -3.42 | |
| CV-24179 | 5/20/2026 9:55:47 AM | 130.2 | -1.03 | -1.01 | 6.9 | 7.0 | 0.143 | 0.148 | -7.95 | |
| CV-24179 | 5/4/2026 1:09:48 PM | 123.9 | -1.03 | -1.01 | 9.4 | 9.2 | 0.240 | 0.230 | -8.67 | -8.26 |
| CV-24179 | 5/4/2026 1:08:00 PM | 119.4 | -1.00 | -1.02 | 9.2 | 9.2 | 0.225 | 0.228 | -8.59 | -8.43 |
| CV-24179 | 5/4/2026 1:03:56 PM | 78.1 | -0.61 | -0.57 | 3.0 | 2.9 | 0.023 | 0.021 | -8.43 | -8.51 |
| CV-24180 | 5/20/2026 10:03:08 AM | 126.6 | -3.18 | -3.18 | 56.7 | 57.5 | 2.098 | 2.162 | -8.02 | |
| CV-24180 | 5/8/2026 10:53:15 AM | 124.9 | -1.60 | -1.60 | 37.4 | 37.5 | 0.918 | 0.926 | -3.70 | |
| CV-24181 | 5/20/2026 12:05:54 PM | 111.7 | -0.49 | -0.48 | 2.6 | 3.3 | 0.829 | 1.314 | -7.28 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24181 | 5/4/2026 11:08:54 AM | 107.4 | -1.03 | -0.93 | 4.4 | 3.7 | 2.280 | 1.554 | -8.81 | |
| CV-24182 | 5/22/2026 10:34:25 AM | 112.1 | -0.57 | -0.52 | 0.0 | 0.0 | 0.499 | 0.494 | -8.06 | |
| CV-24182 | 5/4/2026 11:12:00 AM | 99.0 | -0.62 | -0.62 | 0.0 | 0.0 | 0.568 | 0.570 | -9.05 | |
| CV-24183 | 5/20/2026 11:42:38 AM | 106.9 | -0.53 | -0.53 | 0.0 | 0.0 | 0.513 | 0.512 | -7.29 | |
| CV-24183 | 5/4/2026 11:26:46 AM | 84.8 | -0.90 | -0.90 | 0.0 | 0.0 | 0.856 | 0.861 | -8.77 | |
| CV-24184 | 5/28/2026 1:18:12 PM | 135.1 | -0.16 | -0.11 | 2.5 | 3.1 | 0.133 | 0.203 | -10.10 | -10.11 |
| CV-24184 | 5/28/2026 1:16:04 PM | 139.3 | -0.41 | -0.17 | 10.0 | 4.5 | 2.217 | 0.438 | -9.81 | -10.06 |
| CV-24184 | 5/20/2026 11:25:50 AM | 133.8 | -0.09 | -0.08 | 4.1 | 4.1 | 0.403 | 0.400 | -7.95 | |
| CV-24184 | 5/20/2026 11:24:32 AM | 132.1 | -0.05 | -0.05 | 4.2 | 4.2 | 0.420 | 0.421 | -7.83 | |
| CV-24184 | 5/20/2026 11:22:55 AM | 125.5 | 0.07 | -0.02 | 0.0 | 4.5 | -0.017 | 0.474 | -7.75 | |
| CV-24184 | 5/4/2026 1:19:41 PM | 133.2 | -0.23 | -0.23 | 6.6 | 6.6 | 0.928 | 0.924 | -8.60 | |
| CV-24184 | 5/4/2026 1:18:22 PM | 133.9 | -0.40 | -0.21 | 11.5 | 6.3 | 2.789 | 0.843 | -8.56 | |
| CV-24185 | 5/20/2026 2:14:16 PM | 128.3 | -0.21 | -0.20 | 19.3 | 19.3 | 1.133 | 1.133 | -7.67 | |
| CV-24185 | 5/20/2026 2:12:58 PM | 128.0 | 0.05 | -0.05 | 12.4 | 19.2 | 0.477 | 1.150 | -7.55 | |
| CV-24185 | 5/4/2026 1:26:49 PM | 123.2 | -0.21 | -0.21 | 14.0 | 14.0 | 0.585 | 0.588 | -8.57 | |
| CV-24186 | 5/20/2026 2:18:02 PM | 128.5 | -0.29 | -0.29 | 16.7 | 16.8 | 0.788 | 0.789 | -7.36 | |
| CV-24186 | 5/4/2026 2:56:41 PM | 124.0 | -0.87 | -0.52 | 23.1 | 13.9 | 1.461 | 0.531 | -8.51 | |
| CV-24187 | 5/19/2026 10:36:55 AM | 124.9 | -0.39 | -0.36 | 4.3 | 5.4 | 0.050 | 0.079 | -6.56 | -6.63 |
| CV-24187 | 5/4/2026 10:28:37 AM | 124.3 | -0.20 | -0.16 | 9.9 | 10.5 | 0.266 | 0.300 | -7.99 | -8.10 |
| CV-24187 | 5/4/2026 10:27:50 AM | 124.0 | -0.10 | -0.21 | 7.9 | 9.7 | 0.169 | 0.259 | -8.17 | -8.06 |
| CV-24187 | 5/4/2026 10:19:29 AM | 67.9 | -0.32 | -0.33 | 7.0 | 7.8 | 0.121 | 0.150 | -7.99 | -7.99 |
| CV-24188 | 5/20/2026 12:45:56 PM | 117.0 | -2.84 | -2.83 | 32.2 | 32.2 | 2.842 | 2.835 | -7.57 | -7.50 |
| CV-24188 | 5/20/2026 8:59:37 AM | 118.4 | -3.18 | -3.38 | 12.9 | 13.9 | 0.451 | 0.526 | -8.73 | -8.70 |
| CV-24188 | 5/4/2026 9:36:30 AM | 117.6 | -3.10 | -3.10 | 14.0 | 14.0 | 0.534 | 0.532 | -9.27 | -9.06 |
| CV-24188 | 5/4/2026 9:34:45 AM | 117.5 | -2.61 | -2.98 | 11.8 | 14.0 | 0.375 | 0.534 | -8.82 | -9.10 |
| CV-24189 | 5/20/2026 8:49:58 AM | 118.0 | -1.88 | -1.87 | 9.0 | 9.0 | 1.702 | 1.710 | -8.75 | -8.73 |
| CV-24189 | 5/4/2026 9:28:20 AM | 117.6 | -1.79 | -1.79 | 9.1 | 9.1 | 1.761 | 1.746 | -9.10 | -8.93 |
| CV-24190 | 5/19/2026 10:21:44 AM | 123.2 | -3.56 | -3.56 | 17.1 | 17.1 | 0.804 | 0.802 | -6.76 | -6.64 |
| CV-24190 | 5/4/2026 10:10:47 AM | 122.5 | -4.08 | -4.09 | 20.2 | 20.2 | 1.127 | 1.126 | -8.32 | -8.27 |
| CV-24192 | 5/22/2026 10:15:13 AM | 116.1 | -6.39 | -7.26 | 14.5 | 18.1 | 0.454 | 0.712 | -7.81 | |
| CV-24192 | 5/4/2026 10:02:40 AM | 117.4 | -6.38 | -6.48 | 14.5 | 14.5 | 0.497 | 0.497 | -8.93 | -8.92 |
| CV-24192 | 5/4/2026 10:01:48 AM | 117.3 | -6.12 | -6.38 | 13.5 | 14.7 | 0.427 | 0.509 | -8.63 | -8.77 |
| CV-24192 | 5/4/2026 9:58:01 AM | 116.8 | -5.60 | -5.92 | 11.2 | 13.3 | 0.165 | 0.232 | -8.95 | -8.74 |
| CV-24193 | 5/19/2026 2:15:47 PM | 116.4 | -5.05 | -5.04 | 10.9 | 11.2 | 0.156 | 0.164 | -5.48 | -5.45 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24193 | 5/4/2026 9:13:38 AM | 113.0 | -7.77 | -7.88 | 17.8 | 18.0 | 0.380 | 0.389 | -8.74 | |
| CV-24194 | 5/20/2026 12:10:04 PM | 102.8 | -4.95 | -3.58 | 4.6 | 1.7 | 0.439 | 0.062 | -7.11 | |
| CV-24194 | 5/5/2026 1:47:55 PM | 92.6 | -3.78 | -3.85 | 13.1 | 13.5 | 0.385 | 0.409 | -5.71 | -5.67 |
| CV-24194 | 5/4/2026 9:33:10 AM | 91.8 | -4.34 | -5.02 | 4.0 | 5.7 | 0.095 | 0.191 | -8.88 | |
| CV-24195 | 5/28/2026 1:01:56 PM | 118.3 | -0.91 | -0.94 | 12.5 | 13.6 | 3.336 | 3.917 | -9.42 | -9.74 |
| CV-24195 | 5/20/2026 12:23:03 PM | 118.2 | -0.55 | -0.55 | 12.5 | 12.5 | 3.299 | 3.303 | -7.13 | |
| CV-24195 | 5/4/2026 9:46:22 AM | 115.0 | -0.97 | -0.97 | 13.7 | 13.1 | 3.853 | 3.542 | -8.73 | |
| CV-24196 | 5/28/2026 12:55:54 PM | 123.1 | -1.57 | -1.85 | | | 1.357 | 1.676 | -9.64 | -9.64 |
| CV-24196 | 5/20/2026 11:31:51 AM | 125.4 | -1.36 | -1.34 | 15.6 | 14.5 | 0.306 | 0.267 | -7.75 | |
| CV-24196 | 5/4/2026 11:32:25 AM | 122.7 | -1.96 | -1.86 | 15.8 | 12.1 | 0.310 | 0.183 | -8.52 | |
| CV-24197 | 5/22/2026 10:52:22 AM | 123.9 | -1.11 | -1.11 | 22.3 | 22.4 | 1.317 | 1.333 | -5.23 | |
| CV-24197 | 5/8/2026 11:18:02 AM | 125.3 | -0.62 | -0.62 | 22.1 | 22.1 | 1.298 | 1.294 | -4.95 | |
| CV-24198 | 5/22/2026 10:50:58 AM | 118.4 | -0.22 | -0.21 | 7.1 | 7.1 | 1.051 | 1.054 | -5.47 | |
| CV-24198 | 5/8/2026 10:50:53 AM | 119.2 | -0.14 | -0.07 | 5.7 | 10.2 | 0.651 | 2.074 | -5.14 | |
| CV-24199 | 5/22/2026 10:41:08 AM | 128.1 | -0.78 | -0.44 | 28.3 | 23.4 | 0.998 | 0.683 | -5.36 | |
| CV-24199 | 5/8/2026 10:55:45 AM | 127.3 | -0.43 | -0.45 | 27.8 | 27.7 | 0.940 | 0.933 | -5.81 | |
| CV-24200 | 5/22/2026 9:57:47 AM | 118.3 | -0.74 | -0.64 | 13.2 | 13.4 | 1.057 | 1.079 | -6.06 | |
| CV-24200 | 5/6/2026 2:43:38 PM | 117.7 | -0.31 | -0.42 | 14.7 | 18.0 | 1.288 | 1.946 | -11.64 | |
| CV-24201 | 5/22/2026 10:05:48 AM | 119.9 | -1.00 | -1.01 | 9.2 | 9.3 | 0.220 | 0.224 | | |
| CV-24201 | 5/6/2026 3:11:02 PM | 121.5 | -1.35 | -1.24 | 12.4 | 10.8 | 0.407 | 0.309 | | |
| CV-24202 | 5/22/2026 10:29:59 AM | 113.7 | -3.37 | -3.38 | 0.0 | 0.0 | 3.478 | 3.453 | -11.87 | |
| CV-24202 | 5/6/2026 3:17:39 PM | 118.7 | -4.97 | -3.53 | 0.0 | 0.0 | 4.924 | 3.585 | -11.80 | |
| CV-24203 | 5/22/2026 9:36:46 AM | 126.6 | -1.38 | -1.33 | 21.6 | 22.3 | 2.886 | 3.085 | | |
| CV-24203 | 5/11/2026 10:07:30 AM | 125.9 | -1.32 | -1.31 | 20.2 | 20.2 | 2.548 | 2.551 | -10.37 | |
| CV-24204 | 5/22/2026 9:39:46 AM | 126.5 | -1.10 | -1.09 | 13.1 | 12.7 | 0.391 | 0.366 | -11.61 | |
| CV-24204 | 5/11/2026 10:10:41 AM | 125.9 | -1.37 | -0.91 | 14.0 | 11.9 | 0.447 | 0.325 | -10.51 | |
| CV-24205 | 5/22/2026 9:45:39 AM | 122.6 | -2.73 | -2.71 | 27.2 | 28.6 | 0.880 | 0.970 | -11.33 | |
| CV-24205 | 5/6/2026 12:13:07 PM | 121.1 | -2.21 | -2.20 | 22.4 | 22.5 | 0.605 | 0.611 | -8.56 | |
| CV-24206 | 5/22/2026 10:00:36 AM | 92.2 | -0.86 | -0.87 | 0.0 | 0.0 | 0.904 | 0.914 | -7.02 | |
| CV-24206 | 5/6/2026 3:04:18 PM | 86.5 | -0.79 | -0.79 | 0.0 | 0.0 | 0.564 | 0.564 | -0.02 | |
| CV-24207 | 5/21/2026 9:17:20 AM | 130.6 | -2.38 | -2.39 | 10.1 | 9.9 | 0.135 | 0.132 | -5.52 | -5.76 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24207 | 5/21/2026 9:15:43 AM | 130.7 | -4.87 | -2.81 | 16.3 | 8.9 | 0.358 | 0.106 | -5.26 | -5.08 |
| CV-24207 | 5/4/2026 2:35:22 PM | 126.3 | -5.80 | -5.79 | 21.6 | 20.5 | 0.589 | 0.526 | -6.38 | |
| CV-24208 | 5/4/2026 10:58:55 AM | 125.4 | -1.90 | -1.49 | 27.2 | 22.7 | 1.745 | 1.209 | -9.20 | -9.17 |
| CV-24209 | 5/4/2026 11:15:06 AM | 124.7 | -0.29 | -0.31 | | | 0.302 | 0.310 | -14.09 | -14.30 |
| CV-24210 | 5/5/2026 1:26:15 PM | 101.2 | -0.16 | -0.35 | | | 0.146 | 0.350 | -9.13 | -9.17 |
| CV-24210 | 5/4/2026 11:34:40 AM | 119.8 | -0.51 | -0.48 | | | 0.553 | 0.484 | -8.86 | -8.83 |
| CV-24211 | 5/7/2026 10:23:15 AM | 118.1 | -2.98 | -2.91 | 0.0 | 0.0 | 3.039 | 2.730 | -4.55 | |
| CV-24212 | 5/11/2026 9:45:09 AM | 136.8 | -0.86 | -0.87 | 0.0 | 0.0 | 0.896 | 0.897 | -12.79 | |
| CV-24212 | 5/11/2026 9:43:52 AM | 135.1 | -0.88 | -0.88 | 0.0 | 0.0 | 0.893 | 0.893 | -12.71 | |
| CV-24213 | 5/1/2026 1:55:50 PM | 111.8 | -0.71 | -0.92 | | | 0.711 | 0.945 | -1.45 | -1.47 |
| CV-24213 | 5/1/2026 1:54:28 PM | 121.8 | -0.94 | -1.01 | | | 0.910 | 0.988 | -1.10 | -1.16 |
| CV-24213 | 5/1/2026 1:34:20 PM | 109.6 | 1.46 | 1.48 | | | 0.000 | 0.000 | 0.06 | 1.14 |
| CV-24213 | 5/1/2026 1:32:27 PM | 109.4 | 1.44 | 1.45 | | | 0.000 | 0.000 | -0.01 | 0.12 |
| CV-24214 | 5/26/2026 12:44:02 PM | 108.7 | -3.43 | -3.42 | | | 3.477 | 3.459 | -4.39 | -4.31 |
| CV-24214 | 5/26/2026 12:41:30 PM | 109.1 | -3.61 | -3.47 | | | 3.654 | 3.505 | -4.08 | -4.33 |
| CV-24215 | 5/29/2026 9:58:57 AM | 96.2 | -0.25 | -0.25 | 13.7 | 13.7 | 0.120 | 0.120 | -7.83 | |
| CV-24216 | 5/1/2026 1:59:49 PM | 104.2 | -3.65 | -3.64 | | | 3.587 | 3.559 | -8.90 | -8.98 |
| CV-24217 | 5/11/2026 1:45:32 PM | 115.7 | -0.16 | -0.16 | 0.0 | 0.0 | 0.145 | 0.150 | | |
| CV-24217 | 5/11/2026 1:25:59 PM | 110.5 | -0.22 | -0.21 | | | 0.205 | 0.192 | -8.73 | -8.68 |
| CV-24217 | 5/11/2026 10:19:12 AM | 121.5 | -0.44 | -0.32 | | | 0.431 | 0.316 | -10.32 | -10.42 |
| CV-24218 | 5/8/2026 8:42:59 AM | 124.1 | -0.48 | -0.52 | 0.0 | 0.0 | 0.555 | 0.571 | | |
| CV-24219 | 5/27/2026 2:44:32 PM | 179.3 | -4.70 | -4.39 | | | 4.685 | 4.386 | -5.96 | -5.96 |
| CV-24219 | 5/19/2026 1:10:00 PM | | | | | | | | | |
| CV-24219 | 5/19/2026 1:07:47 PM | 182.4 | -2.55 | -2.46 | | | 2.583 | 2.396 | -4.09 | -4.07 |
| CV-24219 | 5/19/2026 1:07:21 PM | 182.1 | 6.06 | -2.11 | | | 0.000 | 2.130 | -4.70 | -3.83 |
| CV-24219 | 5/11/2026 9:27:37 AM | 188.3 | -6.96 | -6.50 | | | 6.916 | 6.475 | -13.85 | -13.07 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-24219 | 5/11/2026 9:26:02 AM | 188.2 | 1.54 | -5.97 | | | 0.000 | 5.945 | -13.82 | -13.34 |
| CV-24219 | 5/4/2026 8:40:00 AM | | | | | | | | | |
| CV-24219 | 5/4/2026 8:40:00 AM | | | | | | | | | |
| CV-24219 | 5/4/2026 8:37:52 AM | 187.1 | -1.73 | -1.64 | | | 1.908 | 1.772 | -11.22 | -11.52 |
| CV-24220 | 5/1/2026 2:28:38 PM | 131.1 | -0.57 | -0.56 | | | 0.547 | 0.534 | -13.06 | -12.81 |
| CV-24220 | 5/1/2026 2:26:20 PM | 133.5 | -5.99 | -2.52 | | | 5.986 | 2.502 | -12.46 | -12.78 |
| CV-24221 | 5/7/2026 10:47:53 AM | 91.5 | -0.02 | -0.03 | 0.0 | 0.0 | -0.026 | -0.026 | -3.82 | |
| CV-24222 | 5/11/2026 9:28:59 AM | 122.8 | -10.04 | -10.78 | 20.8 | 23.4 | 1.119 | 1.423 | -12.00 | |
| CV-24223 | 5/11/2026 9:35:14 AM | 129.6 | -4.99 | -3.40 | 0.0 | 0.0 | 5.000 | 3.346 | | |
| CV-24224 | 5/1/2026 2:36:53 PM | 116.0 | -6.80 | -5.00 | | | 6.882 | 4.991 | -13.15 | -11.52 |
| CV-24225 | 5/4/2026 10:44:54 AM | 105.0 | -0.36 | -0.35 | | | 0.346 | 0.351 | -13.59 | -13.84 |
| CV-24226 | 5/7/2026 10:18:42 AM | 112.6 | -4.57 | -4.58 | 0.0 | 3.4 | -0.054 | 0.007 | -4.51 | |
| CV-24227 | 5/8/2026 11:27:46 AM | 115.3 | -1.95 | -2.05 | 19.0 | 23.2 | 0.764 | 1.145 | | |
| CV-24231 | 5/5/2026 2:20:38 PM | 123.6 | -1.09 | -0.70 | 36.4 | 24.7 | 0.803 | 0.368 | -9.44 | |
| CV-24236 | 5/7/2026 9:58:34 AM | 103.0 | -0.32 | -0.47 | 8.1 | 10.8 | 0.375 | 0.666 | -3.40 | |
| CV-24237 | 5/7/2026 10:03:50 AM | 111.8 | -0.12 | -0.21 | 12.8 | 15.9 | 0.343 | 0.526 | -3.09 | |
| CV-24243 | 5/8/2026 10:05:46 AM | 116.4 | -0.03 | -0.12 | 32.7 | 50.3 | 0.244 | 0.579 | -4.54 | |
| CV-24244 | 5/7/2026 11:23:42 AM | 112.4 | -0.42 | -0.51 | 0.0 | 13.8 | -0.030 | 0.044 | -3.27 | |
| CV-24245 | 5/7/2026 2:21:55 PM | 115.1 | -1.51 | -0.50 | 24.7 | 13.7 | 1.319 | 0.404 | -4.99 | |
| CV-24246 | 5/7/2026 2:17:13 PM | 116.5 | -0.10 | -0.07 | 3.1 | 3.0 | 0.025 | 0.023 | -1.05 | |
| CV-24253 | 5/7/2026 2:35:07 PM | 116.0 | -0.12 | -0.22 | 27.6 | 30.8 | 1.621 | 2.018 | -7.27 | |
| CV-25 | 5/13/2026 1:44:59 PM | 93.3 | -7.02 | -6.95 | 4.8 | 5.3 | 0.029 | 0.035 | -8.94 | -8.83 |
| CV-2501 | 5/4/2026 9:55:50 AM | 120.3 | -0.84 | -0.83 | 0.0 | 0.0 | -0.035 | -0.042 | -11.08 | |
| CV-2502 | 5/4/2026 10:08:04 AM | 119.1 | -0.69 | -0.68 | 15.3 | 16.3 | 0.056 | 0.063 | -10.41 | |
| CV-2503 | 5/6/2026 2:52:46 PM | 125.8 | -0.41 | -0.52 | 50.2 | 38.8 | 0.607 | 0.363 | -10.74 | |
| CV-2504 | 5/5/2026 2:41:25 PM | 125.9 | -1.02 | -0.87 | 142.0 | 120.9 | 4.865 | 3.530 | -9.25 | |
| CV-2505 | 5/5/2026 2:55:39 PM | 117.5 | -3.03 | -3.04 | 35.9 | 35.8 | 0.769 | 0.766 | -10.96 | |
| CV-2506 | 5/5/2026 3:55:25 PM | 119.8 | -1.88 | -1.88 | 52.0 | 51.9 | 1.624 | 1.621 | -10.08 | |
| CV-2507 | 5/8/2026 1:37:11 PM | 122.8 | -3.77 | -3.89 | 58.9 | 58.4 | 4.489 | 4.403 | -11.33 | -11.59 |
| CV-2507 | 5/5/2026 3:50:55 PM | 120.1 | -2.97 | -3.34 | 54.5 | 59.2 | 3.486 | 4.103 | -10.12 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2508 | 5/5/2026 3:46:09 PM | 118.6 | -6.15 | -6.47 | 74.9 | 82.7 | 1.317 | 1.607 | -10.13 | |
| CV-2509 | 5/8/2026 1:42:52 PM | 115.2 | -7.11 | -7.40 | 56.6 | 60.7 | 2.048 | 2.363 | -13.04 | -12.96 |
| CV-2509 | 5/5/2026 3:31:32 PM | 113.5 | -5.20 | -5.41 | 54.4 | 59.3 | 1.749 | 2.081 | -8.99 | |
| CV-2510 | 5/8/2026 1:46:50 PM | 113.9 | -3.81 | -4.15 | 29.1 | 31.3 | 2.283 | 2.653 | -12.36 | -12.55 |
| CV-2510 | 5/5/2026 2:25:18 PM | 113.5 | -2.48 | -2.75 | 19.4 | 22.6 | 1.014 | 1.372 | -9.32 | -8.83 |
| CV-25100D | 5/18/2026 10:35:31 AM | 121.0 | -1.88 | -1.87 | | | 1.881 | 1.885 | -4.03 | -4.37 |
| CV-25100D | 5/12/2026 10:22:21 AM | 146.4 | -1.69 | -1.55 | | | 1.721 | 1.599 | -10.57 | -10.60 |
| CV-25100D | 5/12/2026 10:20:00 AM | | | | | | | | | |
| CV-25100D | 5/8/2026 9:54:19 AM | 178.2 | -0.07 | -0.04 | 0.0 | 0.0 | 0.107 | 0.098 | -3.41 | |
| CV-25100D | 5/8/2026 9:52:49 AM | 177.5 | -0.05 | -0.03 | 0.0 | 0.0 | 0.107 | 0.035 | -3.51 | |
| CV-25100S | 5/26/2026 10:48:42 AM | 161.0 | -7.04 | -7.04 | | | 7.116 | 7.116 | -11.52 | -11.52 |
| CV-25100S | 5/26/2026 10:48:08 AM | 160.7 | -10.08 | -7.27 | | | 10.084 | 7.236 | -11.19 | -11.47 |
| CV-25100S | 5/18/2026 10:40:00 AM | | | | | | | | | |
| CV-25100S | 5/18/2026 10:33:27 AM | 157.2 | -3.42 | -3.47 | | | 3.376 | 3.533 | -4.42 | -4.41 |
| CV-25100S | 5/12/2026 10:25:18 AM | 164.4 | -8.85 | -9.07 | | | 8.818 | 8.985 | -10.53 | -10.55 |
| CV-25100S | 5/12/2026 10:25:00 AM | | | | | | | | | |
| CV-25100S | 5/8/2026 10:01:43 AM | 181.9 | -0.43 | -0.28 | 0.0 | 0.0 | 0.677 | 1.154 | -3.20 | |
| CV-25100S | 5/8/2026 10:00:14 AM | 182.3 | -1.16 | -0.95 | 0.0 | 0.0 | 1.307 | 1.194 | -3.29 | |
| CV-25100S | 5/4/2026 2:45:00 PM | | | | | | | | | |
| CV-25100S | 5/4/2026 2:45:00 PM | | | | | | | | | |
| CV-25100S | 5/4/2026 2:38:27 PM | 182.8 | -6.31 | -6.71 | | | 6.165 | 6.596 | -10.21 | -10.05 |
| CV-25101D | 5/22/2026 10:43:56 AM | 80.5 | -8.07 | -7.89 | | | 7.928 | 7.721 | -8.05 | -7.92 |
| CV-25101D | 5/12/2026 1:33:31 PM | 83.3 | -10.20 | -9.13 | | | 10.328 | 9.173 | -10.30 | -9.38 |
| CV-25101S | 5/22/2026 10:46:24 AM | 112.0 | -1.50 | -1.48 | | | 1.458 | 1.442 | -7.23 | -7.13 |
| CV-25101S | 5/12/2026 1:23:51 PM | | -3.23 | | | | 3.181 | | -10.20 | |
| CV-25102_ | 5/20/2026 2:05:47 PM | 100.0 | -9.04 | -9.04 | | | 8.735 | 8.876 | -9.42 | -9.42 |
| CV-25102_ | 5/8/2026 10:11:54 AM | 83.1 | -4.06 | -3.97 | 0.0 | 0.0 | 3.871 | 3.864 | -3.84 | |
| CV-25102_ | 5/8/2026 10:09:29 AM | 83.5 | -4.02 | -3.93 | 0.0 | 0.0 | 3.957 | 3.944 | -3.62 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-25103 | 5/22/2026 11:13:05 AM | 127.2 | -2.07 | -2.02 | | | 2.013 | 1.938 | -5.83 | -8.08 |
| CV-25103 | 5/20/2026 1:53:20 PM | 106.5 | -0.01 | -0.12 | | | 0.000 | 0.083 | -8.79 | -8.66 |
| CV-25103 | 5/12/2026 10:47:21 AM | 124.9 | -0.62 | -0.61 | | | 0.598 | 0.597 | -11.88 | -11.73 |
| CV-25103 | 5/12/2026 10:45:57 AM | 127.6 | -3.74 | -0.66 | | | 3.671 | 0.657 | -12.20 | -11.84 |
| CV-25104D | 5/20/2026 2:32:23 PM | 94.7 | -5.28 | -5.66 | 7.0 | 7.2 | 5.255 | 5.589 | -5.52 | -5.68 |
| CV-25104D | 5/13/2026 9:49:44 AM | 94.6 | -9.27 | -8.86 | | | 9.549 | 9.102 | -9.40 | -8.91 |
| CV-25104S | 5/20/2026 2:35:06 PM | 104.6 | -5.20 | -4.98 | | | 5.120 | 4.965 | -5.44 | -5.60 |
| CV-25104S | 5/13/2026 9:54:31 AM | 121.4 | -9.95 | -9.37 | | | 10.253 | 9.646 | -10.34 | -9.89 |
| CV-25105D | 5/22/2026 10:19:59 AM | | -4.93 | | | | 4.642 | | -5.29 | |
| CV-25105D | 5/8/2026 8:27:56 AM | 74.1 | -0.64 | -0.69 | 0.0 | 0.0 | 0.838 | 0.728 | -1.19 | |
| CV-25105S | 5/20/2026 1:43:43 PM | 128.5 | -1.63 | -1.66 | | | 1.529 | 1.515 | -3.43 | -3.67 |
| CV-25105S | 5/8/2026 8:30:20 AM | 129.3 | -0.39 | -0.36 | 0.0 | 0.0 | 0.676 | 0.393 | -0.82 | |
| CV-25106D | 5/26/2026 9:05:29 AM | 60.2 | -1.16 | -1.15 | | | 1.153 | 1.134 | -7.55 | -7.57 |
| CV-25106D | 5/26/2026 9:03:18 AM | 60.0 | -4.03 | -1.06 | | | 4.001 | 1.043 | -8.42 | -8.14 |
| CV-25106D | 5/12/2026 2:19:11 PM | 87.0 | -3.62 | -3.65 | | | 3.500 | 3.498 | -8.82 | -8.79 |
| CV-25106D | 5/12/2026 2:18:07 PM | 87.3 | -4.23 | -4.27 | | | 4.097 | 4.151 | -10.44 | -10.29 |
| CV-25106S | 5/26/2026 9:12:30 AM | 66.4 | -4.62 | -4.62 | | | 4.580 | 4.577 | -7.75 | -7.51 |
| CV-25106S | 5/26/2026 9:11:40 AM | 66.7 | -7.39 | -4.62 | | | 7.439 | 4.585 | -7.90 | -7.38 |
| CV-25106S | 5/12/2026 2:25:06 PM | 87.8 | -7.99 | -8.06 | | | 8.093 | 8.159 | -8.66 | -8.92 |
| CV-25106S | 5/12/2026 2:23:49 PM | 84.6 | -7.93 | -8.03 | | | 8.084 | 8.186 | -8.79 | -8.74 |
| CV-25107D | 5/1/2026 2:47:38 PM | 89.4 | -11.51 | -11.52 | 0.0 | 0.0 | | | -11.43 | |
| CV-25107S | 5/1/2026 2:50:28 PM | 100.3 | -0.49 | -0.49 | 0.0 | 0.0 | 0.518 | 0.520 | -11.48 | |
| CV-2511 | 5/5/2026 2:33:06 PM | 124.5 | -0.72 | -0.61 | 23.5 | 23.3 | 0.133 | 0.131 | -7.27 | |
| CV-2512 | 5/5/2026 2:28:36 PM | 122.8 | -0.63 | -0.62 | 28.3 | 28.1 | 0.192 | 0.189 | -7.67 | |
| CV-2513 | 5/7/2026 3:05:57 PM | 119.1 | -0.65 | -0.74 | 32.6 | 35.8 | 2.292 | 2.761 | -8.74 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2514 | 5/8/2026 2:58:55 PM | 122.2 | -1.51 | -1.61 | 38.0 | 40.2 | 1.707 | 1.910 | -4.15 | |
| CV-2515 | 5/7/2026 9:16:53 AM | 115.0 | -0.30 | -0.33 | 9.0 | 14.3 | 0.092 | 0.232 | -3.72 | |
| CV-2516 | 5/11/2026 11:15:10 AM | 126.3 | -1.75 | -1.97 | 11.4 | 14.9 | 0.808 | 1.385 | -7.13 | |
| CV-2517 | 5/7/2026 9:40:45 AM | 111.7 | -0.63 | -0.63 | 0.0 | 0.0 | -0.038 | -0.037 | -3.95 | |
| CV-2518 | 5/7/2026 10:00:08 AM | 104.9 | -0.01 | -0.08 | 0.0 | 0.0 | -0.044 | -0.042 | -3.78 | |
| CV-2518 | 5/7/2026 9:57:35 AM | 102.0 | 1.64 | -0.03 | 0.0 | 0.0 | -0.059 | -0.035 | -3.50 | |
| CV-2519 | 5/1/2026 1:11:22 PM | 125.2 | -0.68 | -0.86 | 20.4 | 25.1 | 1.136 | 1.730 | -11.17 | -10.96 |
| CV-2520 | 5/1/2026 1:26:15 PM | 141.0 | -0.13 | -0.13 | 5.3 | 5.3 | 0.078 | 0.079 | -10.84 | -10.84 |
| CV-2520 | 5/1/2026 1:25:06 PM | 141.0 | 0.42 | -0.09 | 4.1 | 5.5 | 0.046 | 0.086 | -10.84 | -10.84 |
| CV-2521 | 5/26/2026 12:24:46 PM | 109.8 | -1.07 | -1.06 | | | 1.075 | 1.061 | -12.77 | -12.92 |
| CV-2522 | 5/5/2026 12:53:32 PM | 129.6 | -0.05 | -0.13 | 4.8 | 2.5 | 0.054 | 0.014 | -11.53 | -11.44 |
| CV-2522 | 5/1/2026 10:59:06 AM | 134.7 | -0.15 | -0.12 | 5.0 | 5.5 | 0.069 | 0.084 | -11.46 | -11.51 |
| CV-2522 | 5/1/2026 10:57:27 AM | 134.8 | 0.59 | -0.16 | 4.7 | 6.8 | 0.061 | 0.130 | -11.50 | -11.41 |
| CV-2523 | 5/4/2026 2:07:42 PM | 124.6 | -2.25 | -2.37 | 22.3 | 22.9 | 3.217 | 3.413 | -12.09 | -11.42 |
| CV-2524 | 5/1/2026 10:45:46 AM | 140.6 | -0.19 | -0.18 | 8.6 | 8.3 | 0.210 | 0.193 | -11.58 | -11.57 |
| CV-2524 | 5/1/2026 10:44:23 AM | 141.0 | 0.22 | -0.14 | 8.5 | 7.0 | 0.203 | 0.139 | -11.67 | -11.61 |
| CV-2525 | 5/4/2026 2:13:54 PM | 120.2 | -0.23 | -0.23 | 23.3 | 23.4 | 1.268 | 1.269 | -11.18 | -11.17 |
| CV-2525 | 5/4/2026 2:13:24 PM | 120.0 | 0.25 | -0.11 | 8.9 | 22.9 | 0.182 | 1.214 | -11.44 | -10.62 |
| CV-2526 | 5/4/2026 2:18:08 PM | 120.0 | -0.03 | -0.15 | 19.5 | 21.0 | 0.094 | 0.108 | -11.59 | -11.46 |
| CV-2527 | 5/15/2026 11:27:42 AM | 126.6 | -3.71 | -3.66 | 0.0 | 0.0 | -3.662 | -3.649 | -13.67 | |
| CV-2528 | 5/11/2026 8:25:29 AM | 108.8 | -2.81 | -2.82 | 12.1 | 14.6 | 0.085 | 0.122 | -13.34 | |
| CV-2529 | 5/8/2026 12:47:59 PM | 88.1 | -6.53 | -6.78 | 2.7 | 3.0 | 0.781 | 0.924 | -6.87 | -6.71 |
| CV-2530 | 5/12/2026 7:58:10 AM | 124.1 | -1.38 | -1.36 | 0.0 | 0.0 | 1.373 | 1.371 | -12.17 | |
| CV-2531 | 5/8/2026 12:35:03 PM | 118.6 | -0.14 | -0.13 | | | 0.107 | 0.093 | -8.56 | -8.42 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2531 | 5/8/2026 12:34:13 PM | 117.4 | 45.23 | -0.13 | | | 0.000 | 0.074 | -8.24 | -8.35 |
| CV-2532 | 5/12/2026 7:54:00 AM | 73.6 | -13.68 | -13.64 | 0.0 | 0.0 | | | -13.52 | |
| CV-2533 | 5/12/2026 7:48:32 AM | 128.4 | -11.82 | -11.81 | 20.5 | 20.7 | 1.147 | 1.173 | -13.28 | |
| CV-2534 | 5/11/2026 2:17:18 PM | 123.0 | -3.20 | -3.97 | 40.7 | 44.5 | 2.169 | 2.604 | -16.17 | -16.36 |
| CV-2535 | 5/5/2026 2:52:23 PM | 107.5 | -0.37 | -0.37 | 7.2 | 7.2 | 1.053 | 1.053 | -8.37 | |
| CV-2536 | 5/14/2026 10:27:30 AM | 89.2 | -9.77 | -3.58 | 3.0 | 2.7 | 0.906 | 0.760 | -10.58 | |
| CV-2537 | 5/6/2026 12:17:48 PM | 109.4 | -1.71 | -0.64 | 0.0 | 0.0 | 1.663 | 0.561 | -6.21 | |
| CV-2538 | 5/6/2026 12:25:17 PM | 118.6 | -0.55 | -0.54 | 11.2 | 10.9 | 2.500 | 2.366 | -7.02 | |
| CV-2539 | 5/20/2026 9:49:24 AM | 122.3 | -3.41 | -3.15 | 0.0 | 0.0 | 3.410 | 3.065 | -7.24 | |
| CV-2539 | 5/4/2026 9:17:28 AM | 116.5 | -1.88 | -1.88 | 0.0 | 0.0 | 1.896 | 1.894 | -8.37 | |
| CV-2540 | 5/20/2026 2:18:42 PM | 129.7 | -1.92 | -2.09 | | | 1.659 | 2.068 | -6.97 | -6.42 |
| CV-2540 | 5/20/2026 2:15:08 PM | 128.9 | -1.83 | -1.93 | | | 1.813 | 1.913 | -6.87 | -7.00 |
| CV-2540 | 5/14/2026 1:17:10 PM | 129.2 | -0.97 | -1.09 | | | 0.952 | 1.029 | -6.70 | -6.67 |
| CV-2540 | 5/14/2026 1:13:24 PM | 129.8 | -6.29 | -0.92 | | | 6.286 | 0.904 | -6.35 | -6.58 |
| CV-2541 | 5/19/2026 9:38:49 AM | 130.6 | -2.43 | -2.43 | | | 2.413 | 2.413 | -6.33 | -6.50 |
| CV-2541 | 5/19/2026 9:36:57 AM | 130.8 | -3.08 | -2.47 | | | 3.055 | 2.423 | -6.36 | -6.35 |
| CV-2541 | 5/1/2026 11:15:47 AM | 85.1 | 0.06 | 0.06 | | | 0.000 | 0.000 | 0.65 | 0.65 |
| CV-2541 | 5/1/2026 11:15:26 AM | 82.5 | 0.06 | 0.06 | | | 0.000 | 0.000 | 0.66 | 0.65 |
| CV-2542 | 5/21/2026 2:04:28 PM | 92.0 | -0.23 | -0.25 | | | 0.197 | 0.147 | -3.07 | -2.89 |
| CV-2542 | 5/4/2026 1:56:22 PM | 72.7 | -3.26 | -2.51 | | | 3.106 | 2.296 | -8.29 | -8.49 |
| CV-2543-PLR | 5/20/2026 1:43:43 PM | 101.3 | -5.07 | -3.98 | | | 5.041 | 3.962 | -7.22 | -6.84 |
| CV-2543-PLR | 5/4/2026 9:50:49 AM | 82.0 | -9.93 | -8.29 | | | 10.180 | 8.654 | -9.85 | -10.37 |
| CV-2544 | 5/21/2026 1:52:17 PM | 94.3 | -0.22 | -0.23 | | | 0.140 | 0.137 | -3.69 | -3.53 |
| CV-2544 | 5/21/2026 1:51:00 PM | 94.3 | 0.39 | -0.12 | | | 0.000 | 0.069 | -3.39 | -3.40 |
| CV-2544 | 5/6/2026 11:06:39 AM | 77.1 | -0.37 | -0.45 | | | 0.351 | 0.432 | -6.35 | -7.34 |
| CV-2545 | 5/22/2026 12:19:27 PM | 127.4 | -0.39 | -0.40 | 0.0 | 0.0 | 0.399 | 0.394 | -3.83 | |
| CV-2545 | 5/22/2026 12:15:46 PM | 127.5 | -0.96 | -0.53 | 0.0 | 0.0 | 0.854 | 0.488 | -3.39 | |
| CV-2545 | 5/6/2026 2:44:01 PM | 115.2 | -0.07 | -0.07 | | | 0.055 | 0.048 | -2.98 | -3.01 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2545 | 5/6/2026 2:43:10 PM | 115.3 | 0.17 | -0.01 | | | 0.000 | 0.000 | -2.90 | -2.94 |
| CV-2546 | 5/22/2026 12:25:12 PM | 129.8 | -0.52 | -0.50 | 0.0 | 0.0 | 0.483 | 0.477 | -3.71 | |
| CV-2546 | 5/22/2026 12:24:00 PM | 130.1 | -0.87 | -0.59 | 0.0 | 0.0 | 0.879 | 0.511 | -3.57 | |
| CV-2546 | 5/6/2026 2:35:53 PM | 121.1 | -0.36 | -0.36 | | | 0.341 | 0.359 | -2.47 | -2.65 |
| CV-2547 | 5/28/2026 12:23:14 PM | 95.7 | -1.39 | -1.53 | | | 1.381 | 1.513 | -14.29 | -13.09 |
| CV-2547 | 5/22/2026 12:03:11 PM | 97.0 | -1.05 | -1.13 | 0.0 | 0.0 | 0.932 | 1.091 | -11.83 | |
| CV-2547 | 5/6/2026 10:25:52 AM | 102.5 | -1.12 | -0.92 | 0.0 | 0.0 | 1.074 | 0.777 | -12.92 | |
| CV-2548 | 5/13/2026 9:58:56 AM | 127.8 | -0.79 | -0.84 | 9.9 | 11.2 | 2.108 | 2.699 | -9.91 | -9.81 |
| CV-2548 | 5/1/2026 10:34:59 AM | 127.9 | -0.88 | -0.78 | 0.0 | 0.0 | -2.413 | -2.210 | | |
| CV-2549 | 5/28/2026 12:13:13 PM | 110.2 | -1.60 | -1.62 | 34.8 | 37.4 | 3.268 | 3.782 | -15.17 | -12.91 |
| CV-2549 | 5/13/2026 9:51:28 AM | 111.4 | -0.89 | -0.93 | 25.9 | 32.0 | 1.790 | 2.748 | -11.33 | -12.41 |
| CV-2549 | 5/6/2026 12:31:15 PM | 111.3 | -0.25 | -0.32 | 26.2 | 28.9 | 1.832 | 2.237 | -12.30 | -11.48 |
| CV-2549 | 5/1/2026 10:30:41 AM | 110.7 | -1.04 | -0.92 | 0.0 | 0.0 | -2.740 | -1.298 | | |
| CV-2550 | 5/27/2026 1:19:05 PM | 168.9 | -6.90 | -6.70 | | | 6.973 | 6.774 | -7.16 | -7.17 |
| CV-2550 | 5/21/2026 10:06:57 AM | 183.7 | -1.39 | -2.69 | | | 1.503 | 2.106 | -5.87 | -8.40 |
| CV-2550 | 5/21/2026 10:04:40 AM | 182.9 | 1.27 | -2.02 | | | 0.000 | 2.043 | -7.38 | -8.67 |
| CV-2550 | 5/11/2026 9:52:55 AM | 180.6 | -2.36 | -2.41 | | | 2.348 | 2.403 | -13.58 | -13.66 |
| CV-2550 | 5/4/2026 9:00:00 AM | | | | | | | | | |
| CV-2550 | 5/4/2026 8:59:59 AM | 185.0 | -5.13 | -5.53 | | | 4.927 | 5.545 | -13.66 | -14.54 |
| CV-2551 | 5/1/2026 2:40:59 PM | 135.0 | -0.78 | -0.77 | 0.0 | 0.0 | 0.742 | 0.747 | -11.81 | |
| CV-2551 | 5/1/2026 2:39:32 PM | 135.5 | -0.90 | -0.91 | 0.0 | 0.0 | 0.963 | 0.856 | -11.84 | |
| CV-2552 | 5/19/2026 1:50:38 PM | 114.0 | -5.61 | -5.73 | | | 5.816 | 5.895 | -8.50 | -8.54 |
| CV-2552 | 5/19/2026 1:49:24 PM | 112.0 | 0.99 | -2.00 | | | 0.000 | 2.003 | -8.75 | -8.66 |
| CV-2552 | 5/11/2026 9:58:44 AM | 176.5 | -0.28 | -0.27 | | | 0.296 | 0.262 | -13.69 | -12.71 |
| CV-2552 | 5/4/2026 9:36:17 AM | 173.8 | -0.72 | -0.71 | | | 0.744 | 0.751 | 0.11 | 0.08 |
| CV-2552 | 5/4/2026 9:35:00 AM | | | | | | | | | |
| CV-2552 | 5/4/2026 9:35:00 AM | | | | | | | | | |
| CV-2553 | 5/20/2026 1:24:17 PM | 114.2 | -0.28 | -0.28 | | | 0.276 | 0.277 | -6.84 | -6.69 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2553 | 5/4/2026 9:36:18 AM | 88.1 | -3.77 | -2.95 | | | 3.689 | 2.876 | 0.30 | 0.33 |
| CV-2554 | 5/28/2026 1:40:06 PM | 149.2 | -4.27 | -4.20 | | | 4.267 | 4.190 | 0.00 | 0.00 |
| CV-2554 | 5/20/2026 2:11:24 PM | 148.6 | -3.24 | -3.25 | | | 3.202 | 3.211 | -3.80 | -3.79 |
| CV-2554 | 5/14/2026 11:13:27 AM | 158.7 | -4.55 | -4.67 | | | 4.543 | 4.646 | 0.00 | 0.00 |
| CV-2554 | 5/14/2026 11:12:34 AM | 157.5 | -10.10 | -4.42 | | | 10.104 | 4.388 | -0.34 | -0.01 |
| CV-2554 | 5/14/2026 11:10:00 AM | | | | | | | | | |
| CV-2554 | 5/4/2026 1:13:35 PM | 167.6 | -7.05 | -7.01 | | | 7.105 | 7.105 | 10.47 | 10.56 |
| CV-2554 | 5/4/2026 1:12:59 PM | 168.5 | -9.63 | -6.34 | | | 9.822 | 6.489 | -8.61 | 4.94 |
| CV-2554 | 5/4/2026 1:10:00 PM | | | | | | | | | |
| CV-2554 | 5/4/2026 1:10:00 PM | | | | | | | | | |
| CV-2555 | 5/22/2026 11:41:33 AM | 93.6 | -6.23 | -6.04 | 0.0 | 0.0 | 6.285 | 6.130 | -6.83 | |
| CV-2555 | 5/22/2026 11:39:04 AM | 86.7 | -5.88 | -5.62 | 0.0 | 0.0 | 6.006 | 5.623 | -6.48 | |
| CV-2555 | 5/8/2026 1:12:17 PM | 83.2 | -1.66 | -1.01 | | | 1.607 | 0.987 | -4.74 | -4.48 |
| CV-2556 | 5/27/2026 2:02:24 PM | 176.8 | -7.61 | -7.45 | | | 7.627 | 7.488 | 0.25 | 0.25 |
| CV-2556 | 5/19/2026 1:45:00 PM | | | | | | | | | |
| CV-2556 | 5/19/2026 1:38:41 PM | 179.5 | -10.11 | -9.43 | | | 10.267 | 9.552 | 0.00 | 0.00 |
| CV-2556 | 5/11/2026 10:20:58 AM | 179.2 | -12.62 | -13.42 | | | 12.753 | 13.579 | 0.04 | 0.02 |
| CV-2556 | 5/4/2026 9:15:00 AM | | | | | | | | | |
| CV-2556 | 5/4/2026 9:15:00 AM | | | | | | | | | |
| CV-2556 | 5/4/2026 9:13:52 AM | 175.8 | -14.12 | -14.12 | | | 14.419 | 14.430 | 0.01 | 0.01 |
| CV-2557 | 5/20/2026 1:47:47 PM | 126.4 | -1.45 | -1.54 | | | 1.436 | 1.436 | -3.75 | -4.32 |
| CV-2557 | 5/8/2026 8:36:19 AM | 121.7 | -0.36 | -0.35 | 0.0 | 0.0 | 0.471 | 0.431 | -1.39 | |
| CV-2558 | 5/27/2026 2:34:42 PM | 179.5 | 7.37 | 7.37 | | | 0.000 | 0.000 | 0.25 | 0.25 |
| CV-2558 | 5/27/2026 2:33:21 PM | 179.4 | 1.98 | 2.48 | | | 0.000 | 0.000 | 0.25 | 0.25 |
| CV-2558 | 5/19/2026 1:15:50 PM | 179.5 | 7.93 | 9.09 | | | 0.000 | 0.000 | 0.00 | 0.00 |
| CV-2558 | 5/19/2026 1:15:00 PM | | | | | | | | | |
| CV-2558 | 5/14/2026 10:19:35 AM | 184.0 | 1.32 | 1.81 | | | 0.000 | 0.000 | 0.34 | 0.34 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2558 | 5/14/2026 10:18:44 AM | 183.6 | -1.14 | 3.49 | | | 0.769 | 0.000 | 0.34 | 0.34 |
| CV-2558 | 5/14/2026 10:15:00 AM | | | | | | | | | |
| CV-2558 | 5/4/2026 8:47:30 AM | 187.0 | 3.58 | 3.70 | | | 0.000 | 0.000 | 1.06 | 0.00 |
| CV-2558 | 5/4/2026 8:45:31 AM | 187.6 | 3.99 | 12.53 | | | 0.000 | 0.000 | 0.70 | 11.42 |
| CV-2558 | 5/4/2026 8:45:00 AM | | | | | | | | | |
| CV-2559 | 5/8/2026 8:53:26 AM | 125.6 | -0.04 | -0.02 | 0.0 | 0.0 | -0.038 | 0.184 | -1.14 | |
| CV-2559 | 5/8/2026 8:49:36 AM | 123.8 | 0.04 | -0.02 | 0.0 | 0.0 | 0.063 | 0.218 | -1.29 | |
| CV-2560 | 5/22/2026 10:39:45 AM | 111.8 | -2.41 | -1.38 | | | 2.357 | 1.353 | -8.96 | -9.13 |
| CV-2560 | 5/12/2026 1:09:28 PM | 124.4 | -6.11 | -3.21 | | | 6.179 | 3.074 | -8.83 | -10.13 |
| CV-2561 | 5/11/2026 2:38:47 PM | 128.9 | -0.74 | -0.85 | 0.0 | 0.0 | 0.720 | 0.901 | -4.85 | |
| CV-2562 | 5/11/2026 2:10:20 PM | 121.0 | -3.33 | -0.80 | 0.0 | 0.0 | -3.199 | -1.003 | -5.04 | |
| CV-2563 | 5/28/2026 11:37:21 AM | 113.5 | -0.15 | -0.11 | 2.3 | 0.7 | 0.111 | 0.011 | -0.17 | -0.26 |
| CV-2563 | 5/28/2026 11:36:57 AM | 112.4 | 0.34 | -0.08 | 1.4 | 1.7 | 0.043 | 0.057 | -0.31 | -0.38 |
| CV-2563 | 5/15/2026 11:37:25 AM | 111.3 | -0.13 | -0.12 | 0.0 | 0.0 | -0.002 | -0.006 | -1.14 | |
| CV-2563 | 5/15/2026 11:35:25 AM | 110.7 | 0.18 | -0.07 | 2.7 | 0.0 | 0.895 | -0.209 | -0.08 | |
| CV-2564 | 5/21/2026 9:30:21 AM | 129.3 | -0.06 | -0.05 | | | 0.070 | 0.054 | -1.31 | -1.48 |
| CV-2564 | 5/21/2026 9:29:15 AM | 129.4 | 0.14 | -0.03 | | | 0.000 | 0.028 | -1.60 | -1.19 |
| CV-2564 | 5/1/2026 11:06:39 AM | 128.1 | -0.14 | -0.15 | | | 0.141 | 0.154 | -6.15 | -6.04 |
| CV-2565 | 5/20/2026 9:51:50 AM | 113.6 | -3.93 | -3.92 | 0.0 | 0.0 | 3.926 | 3.924 | -6.86 | |
| CV-2565 | 5/4/2026 9:20:17 AM | 111.1 | -4.23 | -4.21 | 0.0 | 0.0 | 4.199 | 4.197 | -7.69 | |
| CV-2566 | 5/20/2026 9:46:01 AM | 108.3 | -1.67 | -1.67 | 0.0 | 0.0 | 1.740 | 1.736 | -8.44 | |
| CV-2566 | 5/4/2026 9:24:42 AM | 100.3 | -2.33 | -2.07 | 0.0 | 0.0 | 2.368 | 2.075 | -8.80 | |
| CV-2567 | 5/20/2026 12:20:18 PM | 108.4 | -1.65 | -1.32 | 0.0 | 0.0 | 1.613 | 1.198 | -7.36 | |
| CV-2567 | 5/4/2026 9:43:22 AM | 99.5 | -2.39 | -2.38 | 0.0 | 0.0 | 2.354 | 2.350 | -8.74 | |
| CV-2568 | 5/20/2026 11:39:12 AM | 109.2 | -0.42 | -0.41 | 0.0 | 0.0 | 0.367 | 0.365 | -7.78 | |
| CV-2568 | 5/4/2026 11:23:44 AM | 91.4 | -0.66 | -0.65 | 0.0 | 0.0 | 0.546 | 0.546 | -8.69 | |
| CV-2569 | 5/20/2026 11:29:23 AM | 110.3 | -0.30 | -0.30 | 0.0 | 0.0 | 0.335 | 0.333 | -7.93 | |
| CV-2569 | 5/4/2026 11:29:19 AM | 92.7 | -0.50 | -0.50 | 0.0 | 0.0 | 0.496 | 0.496 | -8.77 | |
| CV-2570 | 5/20/2026 11:15:26 AM | 112.6 | -0.76 | -0.73 | 0.0 | 0.0 | 0.636 | 0.636 | -7.88 | |
| CV-2570 | 5/4/2026 11:34:49 AM | 98.5 | -0.96 | -0.95 | 0.0 | 0.0 | 0.875 | 0.874 | -9.10 | |
| CV-2571 | 5/7/2026 1:00:36 PM | 96.5 | -1.42 | -1.46 | 32.4 | 32.1 | 0.599 | 0.587 | -4.59 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| CV-2572 | 5/7/2026 1:32:16 PM | 121.9 | -0.07 | -0.06 | 0.0 | 0.0 | -0.006 | -0.006 | -0.87 | |
| CV-48R | 5/28/2026 11:41:20 AM | 115.8 | 0.41 | 0.47 | 4.8 | 1.3 | 0.147 | 0.011 | 0.39 | 0.67 |
| CV-48R | 5/28/2026 11:40:34 AM | 115.9 | 0.29 | 0.26 | 4.6 | 3.1 | 0.135 | 0.060 | 0.33 | 0.29 |
| CV-48R | 5/15/2026 11:44:42 AM | 116.1 | -0.15 | -0.14 | 0.0 | 0.0 | -0.130 | -0.131 | -0.10 | |
| CV-48R | 5/6/2026 10:23:03 AM | 120.0 | -0.82 | -0.92 | 3.4 | 2.8 | 0.073 | 0.051 | -0.96 | -0.64 |
| CV-52D | 5/1/2026 1:17:29 PM | 94.5 | -3.26 | -2.86 | 0.6 | 2.9 | 0.002 | 0.050 | -10.84 | -10.84 |
| CV-55R | 5/27/2026 3:07:28 PM | 142.1 | -2.73 | -2.73 | 12.0 | 12.2 | 0.964 | 0.994 | -6.68 | -7.31 |
| CV-55R | 5/21/2026 9:11:16 AM | 134.1 | -3.92 | -3.90 | 7.3 | 7.0 | 0.352 | 0.327 | -10.65 | -10.36 |
| CV-55R | 5/21/2026 9:10:09 AM | 118.0 | 3.03 | -3.56 | 1.1 | 8.9 | 0.008 | 0.503 | -11.24 | -10.14 |
| CV-55R | 5/11/2026 11:02:29 AM | 153.5 | -3.01 | -3.01 | 6.3 | 6.4 | 0.268 | 0.281 | -11.12 | -11.17 |
| CV-55R | 5/4/2026 8:05:00 AM | | | | | | | | | |
| CV-55R | 5/4/2026 8:05:00 AM | | | | | | | | | |
| CV-55R | 5/4/2026 8:04:21 AM | 149.2 | -7.05 | -7.05 | 4.8 | 4.4 | 0.157 | 0.129 | -13.02 | -13.32 |
| CV-56D | 5/7/2026 11:25:28 AM | 92.3 | -2.18 | -2.17 | 0.0 | 0.0 | -0.055 | -0.052 | -4.76 | |
| CV-56D | 5/7/2026 11:22:51 AM | 92.4 | -4.91 | -4.82 | 0.0 | 0.0 | -0.053 | -0.047 | -4.76 | |
| CV-56S | 5/7/2026 11:32:33 AM | 89.0 | -0.59 | -0.51 | 0.0 | 0.0 | -0.065 | -0.058 | -4.78 | |
| CV-56S | 5/7/2026 11:29:21 AM | 90.4 | -0.92 | -0.82 | 0.0 | 0.0 | -0.076 | -0.063 | -4.51 | |
| CV-57R | 5/1/2026 2:21:40 PM | 93.4 | -0.05 | -0.10 | 1.2 | 1.1 | 0.030 | 0.027 | -12.51 | -12.49 |
| CV-79R | 5/1/2026 2:41:23 PM | 125.3 | -0.83 | -0.83 | 6.9 | 6.8 | 0.111 | 0.109 | -13.27 | -12.96 |
| CV-94 | 5/11/2026 3:29:38 PM | 114.0 | -8.74 | -8.75 | 2.3 | 2.2 | 0.032 | 0.029 | -11.57 | |
| CV-94 | 5/11/2026 3:28:29 PM | 110.8 | 2.14 | -9.33 | 0.0 | 1.9 | -0.011 | 0.022 | -12.07 | |
| CV-95 | 5/1/2026 2:19:24 PM | 105.0 | -0.10 | -0.11 | 2.6 | 2.3 | 0.143 | 0.109 | -12.64 | -12.54 |
| CV-95 | 5/1/2026 2:18:38 PM | 99.1 | 0.05 | -0.07 | 1.1 | 1.8 | 0.024 | 0.064 | -7.32 | -7.34 |
| CV-99 | 5/26/2026 1:51:48 PM | 77.4 | -3.43 | -2.93 | 0.7 | 1.3 | 0.009 | 0.035 | -3.44 | -2.72 |
| CV-99 | 5/4/2026 7:45:00 AM | | | | | | | | | |
| D-02 | 5/28/2026 3:29:22 PM | 85.0 | -10.41 | -10.47 | 4.9 | 7.9 | 0.030 | 0.078 | -10.09 | -10.34 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| D-03 | 5/28/2026 3:32:52 PM | 87.1 | -3.36 | -4.87 | 8.6 | 6.5 | 0.061 | 0.035 | -3.10 | -4.83 |
| D-04 | 5/28/2026 3:41:09 PM | 77.8 | -14.97 | -14.91 | 4.5 | 6.3 | 0.025 | 0.049 | -14.64 | -14.53 |
| D-09 | 5/7/2026 1:18:48 PM | 111.7 | -3.08 | -3.31 | 9.8 | 11.5 | 0.569 | 0.785 | -3.67 | |
| D-10 | 5/7/2026 1:08:35 PM | 107.5 | -4.73 | -4.64 | 0.0 | 0.0 | -0.024 | -0.012 | -4.49 | |
| FP-001 | 5/8/2026 9:19:36 AM | 81.1 | -0.01 | -0.02 | 1.3 | 1.3 | 0.165 | 0.179 | -4.83 | |
| FP-002 | 5/8/2026 9:28:39 AM | 78.7 | -0.03 | -0.02 | 1.6 | 0.9 | 0.272 | 0.089 | -3.77 | |
| FP-003 | 5/8/2026 9:39:47 AM | 79.4 | -0.01 | -0.01 | 6.6 | 6.6 | 0.865 | 0.865 | -3.48 | |
| FP-003 | 5/8/2026 9:36:36 AM | 79.6 | -0.03 | -0.03 | 1.7 | 1.8 | 0.059 | 0.062 | -3.15 | |
| FP-005 | 5/15/2026 2:55:43 PM | 82.4 | -0.08 | -0.08 | 13.5 | 14.5 | 3.780 | 4.343 | -0.08 | |
| FP-006 | 5/15/2026 2:51:55 PM | 81.5 | -1.37 | -1.02 | 1.7 | 1.0 | 0.072 | 0.027 | -4.06 | |
| FP-008 | 5/15/2026 3:10:45 PM | 87.8 | -0.76 | -0.19 | 4.1 | 2.7 | 0.414 | 0.182 | -3.06 | |
| FP-008 | 5/6/2026 9:22:39 AM | 79.7 | 0.20 | -0.02 | 0.3 | 0.2 | 0.020 | 0.007 | 0.77 | 0.62 |
| FP-009 | 5/13/2026 10:12:04 AM | 94.3 | -0.15 | -0.11 | 4.0 | 3.4 | 0.324 | 0.233 | -6.98 | -5.41 |
| FP-010 | 5/13/2026 10:03:04 AM | 105.2 | -0.08 | -0.06 | 8.6 | 8.3 | 1.537 | 1.406 | -8.89 | -7.82 |
| FP-011 | 5/13/2026 10:00:11 AM | 74.5 | -1.72 | -1.12 | 5.8 | 4.4 | 0.646 | 0.381 | -8.15 | -8.36 |
| FP-012 | 5/19/2026 8:39:03 AM | 82.4 | -0.10 | -0.11 | 0.9 | 0.8 | 0.015 | 0.013 | -6.15 | -6.30 |
| FP-012 | 5/1/2026 11:49:02 AM | 83.8 | -0.10 | -0.12 | 1.0 | 0.7 | 0.020 | 0.009 | -7.02 | -7.22 |
| FP-013 | 5/19/2026 9:34:22 AM | 76.5 | -0.13 | -0.18 | 6.1 | 9.8 | 0.722 | 1.876 | -5.96 | -5.82 |
| FP-013 | 5/13/2026 9:55:27 AM | 75.1 | -0.17 | -0.14 | 6.6 | 6.8 | 0.836 | 0.897 | -7.27 | -7.29 |
| FP-014 | 5/13/2026 2:03:06 PM | 91.0 | -0.08 | -0.07 | 2.0 | 2.3 | 0.420 | 0.530 | -2.40 | -3.03 |
| FP-015 | 5/15/2026 2:35:16 PM | 79.7 | -0.25 | -0.29 | 1.1 | 1.1 | 0.027 | 0.027 | -3.55 | |
| FP-015 | 5/14/2026 2:08:49 PM | 127.4 | -2.20 | -2.07 | 2.2 | 0.2 | 0.556 | 0.004 | -2.58 | -2.69 |
| FP-015 | 5/13/2026 2:12:26 PM | 176.4 | -2.19 | -2.20 | 2.4 | 2.2 | 0.135 | 0.108 | -2.28 | -2.33 |
| FP-016 | 5/15/2026 2:43:10 PM | 84.3 | -1.81 | -1.27 | 11.0 | 2.0 | 2.904 | 0.093 | -3.97 | |
| FP-016 | 5/13/2026 2:15:57 PM | 89.7 | -1.28 | -1.25 | 2.1 | 2.0 | 1.129 | 1.002 | -2.17 | -2.02 |
| FP-017 | 5/8/2026 12:57:34 PM | 88.7 | -0.09 | -0.11 | 2.6 | 2.3 | 0.138 | 0.107 | 0.02 | 0.29 |
| FP-018 | 5/8/2026 12:40:54 PM | 87.6 | -0.25 | -0.26 | 0.3 | 0.5 | 0.002 | 0.004 | -5.90 | -5.73 |
| FP-019 | 5/12/2026 1:48:27 PM | 79.4 | -0.12 | -0.13 | 1.4 | 1.2 | 0.041 | 0.026 | -3.05 | -4.57 |
| FP-020 | 5/12/2026 1:57:00 PM | 83.2 | -1.09 | -1.05 | | | 0.054 | 0.000 | -4.30 | -4.23 |
| FP-021 | 5/13/2026 10:41:14 AM | 90.9 | -6.85 | -6.93 | 7.5 | 7.7 | 1.138 | 1.213 | -7.46 | -7.61 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| FP-021 | 5/12/2026 1:59:43 PM | 95.7 | -4.27 | -3.67 | | | 0.000 | 0.000 | -5.51 | -5.40 |
| FP-022 | 5/13/2026 10:32:37 AM | 90.5 | -3.57 | -4.07 | 2.5 | 3.6 | 0.130 | 0.258 | -7.96 | -8.10 |
| FP-023 | 5/13/2026 1:46:18 PM | 84.7 | -1.24 | -1.17 | 1.7 | 1.9 | 0.059 | 0.069 | -3.99 | -4.40 |
| FP-024 | 5/20/2026 2:16:33 PM | 96.9 | -0.22 | -0.19 | 2.4 | 1.7 | 0.113 | 0.056 | -7.09 | -7.20 |
| FP-025 | 5/20/2026 2:19:20 PM | 84.5 | -2.99 | -2.62 | 1.6 | 0.6 | 0.051 | 0.008 | -7.58 | -7.49 |
| FP-026 | 5/29/2026 4:20:14 PM | 77.8 | -7.05 | -7.05 | 19.2 | 19.2 | 7.419 | 7.464 | 0.20 | 0.11 |
| FP-027 | 5/29/2026 4:24:24 PM | 88.1 | -8.01 | -8.01 | 20.1 | 20.1 | 8.355 | 8.366 | 0.03 | 0.02 |
| FP-028 | 5/28/2026 11:39:27 AM | 80.7 | -0.78 | -0.59 | 14.5 | 2.7 | 3.991 | 0.140 | -8.46 | |
| FP-029 | 5/28/2026 11:31:57 AM | 74.2 | -0.07 | -0.08 | 0.0 | 0.0 | -0.348 | -0.338 | -0.11 | |
| FP-030 | 5/12/2026 1:41:15 PM | 76.4 | -0.31 | -0.36 | 13.8 | 14.5 | 3.736 | 4.133 | -6.65 | -7.41 |
| FP-031 | 5/29/2026 9:22:16 AM | 76.4 | -1.86 | -1.81 | 9.1 | 9.5 | 1.629 | 1.770 | -7.91 | -8.09 |
| FP-031 | 5/12/2026 1:37:06 PM | 77.7 | -1.63 | -1.49 | 2.6 | 2.6 | 1.628 | 1.641 | -5.82 | -6.08 |
| FP-032 | 5/12/2026 1:28:30 PM | 77.8 | -4.17 | -3.93 | 2.7 | 3.4 | 0.746 | 1.211 | -6.50 | -6.71 |
| FP-033 | 5/12/2026 1:23:05 PM | 86.9 | -2.64 | -1.10 | 5.0 | 1.8 | 0.493 | 0.061 | -6.37 | -6.46 |
| FP-034 | 5/12/2026 1:19:44 PM | 84.6 | -0.14 | -0.13 | 6.1 | 5.8 | 0.729 | 0.673 | -7.56 | -6.34 |
| FP-035 | 5/12/2026 1:16:01 PM | 76.7 | -3.36 | -2.54 | 6.0 | 4.9 | 0.713 | 0.478 | -6.74 | -6.54 |
| FP-036 | 5/1/2026 11:36:11 AM | 77.8 | -1.03 | -1.00 | 3.1 | 3.2 | 2.468 | 2.506 | -6.86 | -6.82 |
| FP-037 | 5/19/2026 10:33:25 AM | 84.8 | -0.15 | -0.14 | 0.2 | 0.2 | 0.005 | 0.004 | -5.65 | -5.62 |
| FP-037 | 5/1/2026 11:38:38 AM | 83.4 | -0.12 | -0.11 | | | 0.022 | 0.023 | -7.74 | -7.73 |
| FP-038 | 5/14/2026 2:24:47 PM | 86.7 | -0.73 | -0.21 | 25.8 | 22.7 | 0.753 | 0.745 | -4.85 | |
| FP-039 | 5/14/2026 2:15:09 PM | 90.1 | -0.10 | -0.14 | 16.8 | 15.9 | 5.474 | 4.864 | -4.74 | |
| FP-040 | 5/29/2026 2:30:36 PM | 104.5 | -0.29 | -0.30 | 23.1 | 26.6 | 4.048 | 5.386 | -4.67 | |
| FP-041 | 5/13/2026 1:16:55 PM | 88.3 | -0.02 | -0.11 | 9.7 | 9.7 | 1.949 | 1.935 | -6.01 | |
| FP-042 | 5/20/2026 10:11:54 AM | 88.7 | -0.02 | -0.03 | 9.7 | 11.2 | 1.903 | 2.497 | -2.81 | -2.52 |
| FP-043 | 5/13/2026 1:22:06 PM | 90.0 | -0.20 | -0.21 | 8.6 | 8.6 | 1.591 | 1.579 | -6.21 | |
| FP-044 | 5/13/2026 1:25:38 PM | 91.7 | -0.32 | -0.17 | 18.2 | 8.4 | 2.089 | 0.442 | -5.69 | |
| FP-045 | 5/11/2026 1:04:40 PM | 122.1 | -0.20 | -0.22 | 10.9 | 10.8 | 2.516 | 2.490 | -5.55 | -5.58 |
| FP-046 | 5/15/2026 3:02:41 PM | 81.9 | -0.25 | -0.25 | 7.1 | 7.1 | 1.253 | 1.250 | -4.12 | |
| FP-047 | 5/29/2026 11:36:35 AM | 86.1 | -0.11 | -0.04 | 0.0 | 0.0 | -0.029 | -0.017 | -0.06 | |
| FP-050 | 5/6/2026 2:53:31 PM | 88.3 | -1.86 | -1.49 | 15.3 | 13.7 | 1.426 | 1.137 | -11.04 | -10.41 |
| FP-051 | 5/6/2026 2:48:25 PM | 92.3 | -4.47 | -3.58 | 6.5 | 7.7 | 0.052 | 0.074 | -10.60 | -11.17 |
| FP-052 | 5/22/2026 2:09:54 PM | 89.0 | -0.37 | -0.25 | 8.9 | 4.1 | 8.135 | 1.706 | -8.36 | |
| FP-052 | 5/4/2026 2:20:50 PM | 80.4 | -0.24 | -0.30 | 41.0 | 41.8 | 10.194 | 10.597 | -4.06 | -4.16 |
| FP-053 | 5/21/2026 2:19:03 PM | 106.2 | -0.11 | -0.54 | 6.0 | 1.0 | 0.740 | 0.019 | -2.34 | -1.81 |
| FP-053 | 5/4/2026 2:08:41 PM | 85.3 | -0.40 | -0.38 | 10.3 | 10.6 | 2.118 | 2.241 | -7.93 | -8.06 |
| FP-054 | 5/1/2026 11:30:37 AM | 86.1 | -0.74 | -0.74 | 29.1 | 29.2 | 1.763 | 1.766 | -12.41 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| FP-055 | 5/20/2026 2:00:54 PM | 105.9 | -0.02 | -0.11 | 11.0 | 17.1 | 2.495 | 6.107 | -6.89 | -6.90 |
| FP-055 | 5/4/2026 10:03:30 AM | 79.3 | -0.12 | -0.12 | 2.9 | 2.9 | 0.167 | 0.167 | -9.14 | -9.03 |
| FP-056 | 5/4/2026 9:15:22 AM | 74.3 | -0.28 | -0.27 | 4.0 | 4.0 | 3.898 | 3.925 | -9.54 | -9.46 |
| FP-057 | 5/4/2026 9:17:47 AM | 105.9 | -0.98 | -0.94 | 6.8 | 6.7 | 0.967 | 0.922 | 0.25 | 0.29 |
| FP-057 | 5/1/2026 11:34:44 AM | 79.6 | -0.58 | -0.58 | 23.7 | 23.7 | 3.162 | 3.157 | -12.43 | |
| FP-058 | 5/29/2026 3:51:49 PM | 85.7 | -0.68 | -0.67 | 31.2 | 31.8 | 2.021 | 2.104 | -13.04 | |
| FP-059 | 5/1/2026 2:35:49 PM | 92.8 | -0.36 | -0.36 | 12.9 | 12.9 | 0.953 | 0.954 | -12.83 | |
| FP-060 | 5/1/2026 2:53:38 PM | 91.0 | -0.46 | -0.46 | 16.1 | 16.1 | 1.491 | 1.488 | -12.50 | |
| FP-061 | 5/15/2026 2:38:19 PM | 148.5 | -0.66 | -0.67 | 0.0 | 0.0 | -0.310 | -0.490 | -4.59 | |
| FP-061 | 5/14/2026 2:22:44 PM | 158.2 | -0.51 | -0.48 | 3.9 | 4.1 | 0.335 | 0.379 | -3.89 | -3.32 |
| FP-061 | 5/14/2026 2:19:38 PM | 158.9 | -2.22 | -0.41 | 3.5 | 1.5 | 1.476 | 0.273 | -3.41 | -3.52 |
| H-01 (EXP-01) | 5/26/2026 8:45:19 AM | 61.8 | -4.15 | -4.15 | | | 4.087 | 4.087 | -7.84 | -7.79 |
| H-01 (EXP-01) | 5/12/2026 1:49:58 PM | 97.1 | -3.72 | -3.71 | | | 3.728 | 3.724 | -7.74 | -7.65 |
| H-02 (EXP-02) | 5/26/2026 8:27:48 AM | 83.7 | -1.22 | -1.23 | | | 1.197 | 1.212 | -7.60 | -7.63 |
| H-02 (EXP-02) | 5/12/2026 1:55:38 PM | 110.3 | -0.42 | -0.42 | | | 0.362 | 0.343 | -7.26 | -7.42 |
| H-03 (EXP-03) | 5/26/2026 8:31:53 AM | 112.6 | -6.85 | -6.88 | | | 6.954 | 6.971 | -7.50 | -7.55 |
| H-03 (EXP-03) | 5/12/2026 2:02:02 PM | 119.0 | -7.34 | -7.33 | | | 7.332 | 7.340 | -8.07 | -8.07 |
| H-04 (EXP-04) | 5/26/2026 8:34:46 AM | 124.1 | -0.80 | -0.80 | | | 0.786 | 0.784 | -7.63 | -7.65 |
| H-04 (EXP-04) | 5/14/2026 10:16:02 AM | 131.1 | -0.16 | -0.15 | | | 0.167 | 0.152 | -7.86 | -7.76 |
| H-04 (EXP-04) | 5/14/2026 10:14:56 AM | 131.2 | -0.14 | -0.14 | | | 0.142 | 0.143 | -8.01 | -8.03 |
| H-04 (EXP-04) | 5/14/2026 10:13:50 AM | 131.5 | 1.83 | -0.15 | | | 0.000 | 0.157 | -7.87 | -7.86 |
| H-08 (EXP-08) | 5/26/2026 8:55:13 AM | 119.3 | -4.97 | -5.00 | | | 4.978 | 4.958 | -6.70 | -6.75 |
| H-08 (EXP-08) | 5/11/2026 9:46:50 AM | 88.4 | -4.09 | -4.08 | | | 4.120 | 4.107 | -5.61 | -5.49 |
| H-10 (EXP-10) | 5/26/2026 9:06:45 AM | 130.8 | -1.09 | -0.67 | | | 1.071 | 0.655 | -6.60 | -6.61 |
| H-10 (EXP-10) | 5/11/2026 9:40:46 AM | 130.8 | -0.17 | -0.17 | | | 0.166 | 0.165 | -5.41 | -5.41 |
| H-10 (EXP-10) | 5/11/2026 9:40:06 AM | 130.9 | 1.20 | -0.01 | | | 0.000 | 0.013 | -5.25 | -5.32 |
| H-101W | 5/13/2026 8:32:50 AM | 65.3 | -4.22 | -4.18 | 16.8 | 16.8 | 0.333 | 0.333 | -8.30 | -8.32 |
| H-101W | 5/13/2026 8:24:13 AM | 64.3 | -8.12 | -7.62 | 22.5 | 22.0 | 0.603 | 0.574 | -8.32 | -8.31 |
| H-102A | 5/13/2026 8:17:41 AM | 66.5 | -8.25 | -8.37 | 10.3 | 10.3 | 0.622 | 0.628 | -8.33 | -8.38 |
| H-1401W | 5/13/2026 8:48:53 AM | 70.2 | -8.15 | -8.21 | 11.0 | 11.3 | 0.715 | 0.748 | -8.41 | -8.20 |
| H-1404C | 5/20/2026 11:55:54 AM | 129.1 | -0.66 | -0.66 | 9.2 | 8.8 | 1.852 | 1.695 | -7.16 | |
| H-1404C | 5/4/2026 11:20:18 AM | 124.8 | -0.87 | -0.86 | 9.8 | 9.8 | 2.047 | 2.050 | -8.56 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| H-1405C | 5/20/2026 8:39:42 AM | 94.2 | -0.68 | -0.65 | 2.9 | 2.4 | 0.050 | 0.035 | -0.99 | -1.17 |
| H-1405C | 5/1/2026 10:13:01 AM | 90.1 | -2.46 | -1.56 | 7.6 | 6.6 | 0.351 | 0.266 | -2.28 | -3.10 |
| H-1406W | 5/20/2026 9:30:46 AM | 94.2 | -7.35 | -0.96 | 13.8 | 5.5 | 1.170 | 0.184 | -7.47 | -7.47 |
| H-1406W | 5/1/2026 10:30:28 AM | 80.8 | -8.43 | -8.32 | 2.6 | 2.8 | 0.041 | 0.049 | -8.65 | -8.74 |
| H-1408CR | 5/6/2026 2:48:15 PM | 125.8 | -0.11 | -0.11 | 1.7 | 3.5 | 0.331 | 1.387 | -11.69 | |
| H-1408CR | 5/6/2026 2:46:51 PM | 122.4 | 0.14 | -0.04 | 0.0 | 6.0 | -0.095 | 4.011 | -11.69 | |
| H-1408E | 5/20/2026 2:13:20 PM | 111.8 | -0.01 | -0.03 | 1.7 | 1.5 | 0.062 | 0.046 | -2.73 | -3.06 |
| H-1408E | 5/4/2026 2:44:00 PM | 107.3 | -0.10 | -0.09 | 4.1 | 3.6 | 0.352 | 0.272 | -5.56 | |
| H-1408E | 5/4/2026 2:42:19 PM | 105.4 | 0.02 | -0.10 | 2.5 | 3.3 | 0.122 | 0.222 | -6.11 | |
| H-1408W | 5/7/2026 10:26:18 AM | 103.9 | -0.02 | -0.11 | 0.0 | 0.0 | -0.269 | -0.010 | -3.06 | |
| H-1409N | 5/20/2026 2:26:47 PM | 116.4 | -0.95 | -1.06 | 2.4 | 2.7 | 0.124 | 0.150 | -6.38 | |
| H-1409N | 5/4/2026 2:02:48 PM | 112.0 | -1.74 | -2.90 | 2.0 | 3.8 | 0.084 | 0.294 | -8.06 | |
| H-1410S | 5/6/2026 12:22:14 PM | 87.5 | -7.42 | -7.39 | 1.2 | 1.4 | 0.008 | 0.011 | -8.07 | |
| H-1563N | 5/22/2026 2:12:17 PM | 115.9 | -2.58 | -2.76 | 5.6 | 6.7 | 0.202 | 0.289 | -3.88 | -4.39 |
| H-1563N | 5/11/2026 12:47:48 PM | 114.1 | -0.59 | -1.23 | 13.1 | 13.8 | 0.222 | 0.245 | -1.72 | -2.53 |
| H-1563S | 5/20/2026 8:43:45 AM | 89.4 | -0.32 | -0.32 | 0.5 | 0.5 | 0.024 | 0.029 | -8.23 | -8.15 |
| H-1563S | 5/1/2026 10:06:27 AM | 93.9 | -0.30 | -0.29 | 0.3 | 0.3 | 0.008 | 0.010 | -7.20 | -6.82 |
| H-1565E | 5/21/2026 10:26:51 AM | 116.5 | -0.42 | -0.33 | 3.1 | 1.0 | 0.060 | 0.007 | -2.39 | -1.92 |
| H-1565E | 5/6/2026 10:50:58 AM | 114.9 | -0.85 | -0.92 | 2.5 | 4.8 | 0.040 | 0.145 | -4.46 | -6.57 |
| H-1568N | 5/21/2026 10:57:34 AM | 128.0 | 0.88 | -0.28 | 4.2 | 11.9 | 0.372 | 3.078 | -2.69 | -2.51 |
| H-1568N | 5/20/2026 2:05:18 PM | 113.9 | -1.13 | -1.15 | 5.2 | 5.4 | 0.567 | 0.625 | -3.67 | -3.60 |
| H-1568N | 5/4/2026 2:46:50 PM | 108.0 | -1.25 | -1.35 | 5.7 | 5.9 | 0.654 | 0.701 | -4.35 | |
| H-1571S | 5/4/2026 11:05:46 AM | 82.8 | -0.68 | -0.57 | 6.1 | 5.2 | 0.081 | 0.059 | -14.29 | -14.18 |
| H-1572N | 5/1/2026 2:47:42 PM | 109.8 | -0.02 | -0.08 | 0.6 | 2.0 | 0.008 | 0.086 | -9.57 | -9.23 |
| H-1572S | 5/4/2026 10:51:40 AM | 96.5 | -3.07 | -2.07 | 15.4 | 13.2 | 0.532 | 0.390 | -13.67 | -14.28 |
| H-1574N | 5/20/2026 10:38:18 AM | 104.7 | -0.06 | -0.06 | 9.6 | 10.0 | 0.115 | 0.125 | -4.92 | -4.96 |
| H-1574N | 5/13/2026 9:52:29 AM | 140.3 | -0.15 | -0.04 | 6.4 | 4.9 | 0.056 | 0.033 | -1.24 | -1.32 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| H-1574N | 5/12/2026 8:59:40 AM | 98.6 | -0.11 | -0.11 | 7.1 | 9.9 | 0.059 | 0.117 | -5.56 | |
| H-1753N | 5/26/2026 9:00:32 AM | 66.7 | -0.10 | -0.08 | 1.5 | 1.2 | 0.004 | 0.003 | -6.49 | -6.41 |
| H-1753N | 5/12/2026 1:45:21 PM | 84.5 | -0.58 | -0.59 | 5.0 | 4.1 | 0.054 | 0.037 | -7.12 | -8.21 |
| H-1753S | 5/22/2026 2:02:07 PM | 112.2 | -3.95 | -3.80 | 3.4 | 3.4 | 0.252 | 0.246 | -4.34 | -4.17 |
| H-1753S | 5/11/2026 12:40:59 PM | 107.0 | -2.14 | -1.05 | 4.3 | 6.6 | 0.389 | 0.910 | -2.46 | -1.93 |
| H-1756S | 5/19/2026 1:28:24 PM | 128.7 | -0.05 | -0.04 | 4.8 | 4.2 | 0.031 | 0.024 | -2.74 | -2.73 |
| H-1756S | 5/19/2026 1:25:39 PM | 130.5 | -0.19 | -0.01 | 9.0 | 19.6 | 0.108 | 0.506 | -2.56 | -2.36 |
| H-1756S | 5/13/2026 12:47:50 PM | 127.8 | -0.49 | -0.50 | 8.1 | 8.2 | 0.168 | 0.174 | -5.44 | |
| H-1757S | 5/20/2026 8:35:55 AM | 81.0 | -0.54 | -0.53 | 5.6 | 5.1 | 0.068 | 0.057 | -7.64 | -7.77 |
| H-1757S | 5/1/2026 10:14:46 AM | 83.0 | -0.14 | -0.15 | 1.4 | 2.2 | 0.005 | 0.011 | -7.51 | -6.79 |
| H-1760S | 5/21/2026 10:10:39 AM | 115.9 | -1.37 | -1.36 | 3.3 | 3.8 | 0.070 | 0.090 | -5.03 | -5.25 |
| H-1760S | 5/11/2026 1:37:59 PM | 119.1 | -1.27 | -1.31 | 3.3 | 3.7 | 0.069 | 0.089 | -6.02 | -6.17 |
| H-1762N | 5/20/2026 1:57:03 PM | 108.6 | -0.08 | -0.06 | 4.6 | 4.5 | 2.260 | 2.147 | -5.63 | -5.41 |
| H-1762N | 5/20/2026 1:55:17 PM | 108.6 | 0.01 | -0.09 | 4.6 | 4.6 | 2.230 | 2.303 | -5.47 | -5.57 |
| H-1762N | 5/4/2026 2:38:51 PM | 100.5 | -0.07 | -0.07 | 5.0 | 5.1 | 2.507 | 2.668 | -6.15 | |
| H-1763N | 5/6/2026 10:36:14 AM | 104.8 | -0.12 | -0.12 | 6.6 | 6.6 | 0.316 | 0.317 | -13.92 | |
| H-1763N | 5/6/2026 10:34:51 AM | 100.8 | 0.01 | -0.09 | 1.5 | 5.8 | 0.016 | 0.251 | -13.79 | |
| H-1763S | 5/4/2026 11:26:50 AM | 102.5 | -0.41 | -0.25 | 5.4 | 4.6 | 0.036 | 0.027 | -9.15 | -9.00 |
| H-1764N | 5/28/2026 12:39:39 PM | 117.8 | -4.20 | -4.76 | 3.1 | 2.6 | 0.208 | 0.149 | -14.48 | -15.76 |
| H-1764N | 5/5/2026 1:16:30 PM | 116.7 | -3.77 | -3.99 | 1.1 | 2.1 | 0.025 | 0.092 | -13.78 | -13.67 |
| H-1764N | 5/4/2026 11:45:03 AM | 117.5 | -4.13 | -4.47 | 3.6 | 4.8 | 0.278 | 0.488 | -13.62 | -13.42 |
| H-1764S | 5/4/2026 11:08:05 AM | 94.2 | -1.75 | -1.70 | 5.7 | 5.5 | 0.197 | 0.183 | -14.09 | -14.15 |
| H-1767N | 5/11/2026 9:51:22 AM | 102.4 | -1.89 | -1.62 | 19.9 | 18.5 | 0.934 | 0.801 | -13.53 | |
| H-1769N | 5/19/2026 8:53:05 AM | 105.1 | -0.08 | -0.03 | 21.0 | 20.5 | 1.175 | 1.115 | -7.01 | -6.78 |
| H-1769N | 5/1/2026 2:30:15 PM | 110.2 | -0.45 | -0.49 | 36.7 | 38.8 | 3.638 | 4.054 | -7.49 | -8.25 |
| H-1770N | 5/19/2026 9:18:49 AM | 98.4 | -0.44 | -0.37 | 14.2 | 6.5 | 4.118 | 0.866 | -6.73 | -5.92 |
| H-1770N | 5/4/2026 8:50:00 AM | | | | | | | | | |
| H-1770N | 5/1/2026 2:42:44 PM | 100.2 | -0.68 | -0.60 | 9.9 | 9.2 | 2.030 | 1.743 | -6.48 | -6.39 |
| H-1770S | 5/19/2026 12:50:46 PM | 102.4 | -0.18 | -0.18 | 1.1 | 0.9 | 0.026 | 0.017 | -4.80 | -4.79 |
| H-1770S | 5/1/2026 10:34:30 AM | 101.9 | -0.39 | -0.33 | 1.6 | 1.2 | 0.051 | 0.032 | -6.81 | -6.73 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| H-1771A | 5/11/2026 2:21:58 PM | 113.2 | -0.48 | -0.48 | 9.3 | 9.3 | 0.530 | 0.527 | -4.99 | |
| H-1771B | 5/13/2026 11:22:20 AM | 130.5 | -3.08 | -2.96 | 4.0 | 3.3 | 0.343 | 0.234 | -11.09 | -9.94 |
| H-1771B | 5/13/2026 11:19:01 AM | 132.6 | -4.92 | -4.05 | 4.4 | 2.4 | 0.423 | 0.129 | -11.13 | -10.87 |
| H-1771B | 5/11/2026 1:05:25 PM | 104.5 | 0.02 | 0.07 | 1.6 | 0.7 | 0.052 | 0.010 | 0.89 | 0.67 |
| H-1771B | 5/11/2026 1:04:43 PM | 104.4 | 0.02 | 0.04 | 1.0 | 0.9 | 0.020 | 0.018 | 0.44 | 0.67 |
| H-1774N | 5/19/2026 9:58:15 AM | 116.0 | -0.11 | -0.07 | 8.4 | 8.9 | 1.484 | 1.677 | -5.71 | -5.81 |
| H-1774N | 5/12/2026 10:34:14 AM | 115.8 | -0.82 | -0.72 | 24.8 | 32.9 | 0.907 | 1.596 | -6.40 | |
| H-1801S | 5/11/2026 11:15:54 AM | 101.8 | -0.20 | -0.20 | 0.0 | 0.0 | -0.105 | -0.100 | -12.22 | |
| H-1802S | 5/1/2026 2:44:17 PM | 114.0 | -0.02 | -0.42 | 7.2 | 5.4 | 0.066 | 0.037 | -11.24 | -11.22 |
| H-1803N | 5/26/2026 9:42:57 AM | 196.0 | -1.69 | -0.89 | 39.7 | 29.7 | 2.347 | 1.312 | 0.34 | 0.31 |
| H-1803N | 5/18/2026 10:00:00 AM | | | | | | | | | |
| H-1803N | 5/18/2026 9:58:45 AM | 196.4 | -0.27 | -0.11 | 21.8 | 17.5 | 0.700 | 0.450 | 0.34 | 0.34 |
| H-1803N | 5/12/2026 9:08:34 AM | 196.4 | -2.79 | -2.79 | 43.4 | 43.4 | 2.806 | 2.806 | 0.68 | 0.68 |
| H-1803N | 5/12/2026 9:05:00 AM | | | | | | | | | |
| H-1803N | 5/5/2026 9:07:24 AM | 196.0 | -2.95 | -2.52 | 46.7 | 43.8 | 3.260 | 2.858 | 0.00 | 0.00 |
| H-1803N | 5/5/2026 9:00:00 AM | | | | | | | | | |
| H-1803N | 5/5/2026 9:00:00 AM | | | | | | | | | |
| H-1804B | 5/1/2026 10:39:08 AM | 108.5 | -10.92 | -11.22 | 12.6 | 16.3 | 0.955 | 1.618 | -12.91 | |
| H-1804N | 5/8/2026 9:11:50 AM | 90.8 | -1.00 | -0.99 | 0.0 | 0.0 | -0.063 | -0.021 | -1.42 | |
| H-1804S | 5/4/2026 11:47:34 AM | 99.8 | -4.58 | -5.79 | 8.4 | 8.7 | 0.435 | 0.473 | -10.88 | -11.32 |
| H-1805A | 5/1/2026 11:19:57 AM | 98.3 | -2.19 | -2.07 | 3.6 | 3.0 | 1.420 | 0.996 | -13.55 | |
| H-1805B | 5/4/2026 11:52:01 AM | 71.2 | -0.43 | -0.43 | 2.4 | 2.5 | 0.116 | 0.116 | -13.66 | -13.57 |
| H-1805S | 5/4/2026 11:39:55 AM | 127.9 | -4.88 | -4.89 | 17.6 | 18.0 | 0.736 | 0.772 | -13.69 | -13.74 |
| H-1806A | 5/1/2026 11:08:54 AM | 98.9 | -0.31 | -0.32 | 1.7 | 1.7 | 0.057 | 0.058 | -12.14 | |
| H-1806B | 5/1/2026 2:52:26 PM | 115.7 | -0.03 | -0.08 | 0.5 | 2.8 | 0.006 | 0.162 | -12.22 | -12.04 |
| H-1806N | 5/11/2026 11:37:48 AM | 129.4 | -3.18 | -2.60 | 11.6 | 6.4 | 0.177 | 0.055 | -9.02 | |
| H-1806S | 5/4/2026 10:39:51 AM | 116.7 | -4.73 | -3.93 | 14.5 | 10.8 | 0.490 | 0.273 | -13.81 | -13.81 |
| H-1807A | 5/4/2026 1:18:09 PM | 103.6 | -8.49 | -8.66 | 26.2 | 28.1 | 0.887 | 1.019 | -10.90 | -13.04 |
| H-1807N | 5/29/2026 10:10:34 AM | 80.6 | -0.45 | -0.43 | 0.0 | 0.0 | -0.029 | -0.028 | -5.31 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| H-1807S | 5/7/2026 11:08:13 AM | 91.7 | -0.13 | -0.13 | 0.0 | 0.0 | -0.064 | -0.064 | -4.72 | |
| H-1952S | 5/21/2026 2:14:50 PM | 126.1 | -0.04 | -0.04 | 7.0 | 6.9 | 1.058 | 1.013 | -2.73 | -2.80 |
| H-1952S | 5/21/2026 2:13:14 PM | 125.9 | 0.26 | -0.04 | 5.4 | 6.6 | 0.626 | 0.944 | -2.46 | -2.81 |
| H-1952S | 5/4/2026 2:04:02 PM | 122.3 | -0.34 | -0.58 | 6.4 | 7.2 | 0.861 | 1.112 | -8.23 | -8.35 |
| H-1955C | 5/1/2026 11:26:41 AM | 82.6 | -0.48 | -0.49 | 7.9 | 7.9 | 1.209 | 1.211 | -13.30 | |
| H-1955N | 5/8/2026 9:07:44 AM | 88.6 | -0.03 | -0.03 | 0.0 | 0.0 | -0.025 | -0.009 | -1.38 | |
| H-1956B | 5/1/2026 10:44:44 AM | 119.3 | -1.89 | -1.29 | 13.1 | 5.8 | 0.420 | 0.081 | -12.25 | |
| H-1956N | 5/11/2026 11:40:47 AM | 107.3 | -0.23 | -0.33 | 3.2 | 4.5 | 0.061 | 0.118 | -6.20 | |
| H-1956S | 5/1/2026 2:39:31 PM | 111.8 | -11.04 | -10.52 | 3.7 | 3.5 | 1.535 | 1.321 | -12.99 | -12.56 |
| H-1957B | 5/6/2026 2:10:22 PM | 102.8 | -0.15 | -0.10 | 19.3 | 18.9 | 2.304 | 2.215 | -9.70 | -9.77 |
| H-1957B | 5/1/2026 2:13:12 PM | 102.7 | -0.12 | -0.11 | 14.1 | 14.2 | 1.234 | 1.249 | -12.58 | -12.58 |
| H-1957N | 5/11/2026 11:33:03 AM | 121.8 | -2.42 | -2.12 | 6.1 | 0.0 | 0.231 | -0.019 | -7.94 | |
| H-1957S | 5/11/2026 11:18:08 AM | 114.9 | -0.46 | -0.41 | 0.0 | 0.0 | -0.083 | -0.076 | -11.49 | |
| H-1958C | 5/4/2026 1:20:33 PM | 123.0 | -0.88 | -0.91 | 4.8 | 5.9 | 0.149 | 0.225 | -12.87 | -12.96 |
| H-1958N | 5/28/2026 1:56:37 PM | 90.7 | -0.01 | -0.01 | 33.9 | 43.8 | 1.428 | 2.380 | -4.34 | -4.19 |
| H-1958S | 5/7/2026 11:03:31 AM | 122.7 | -0.41 | -0.39 | 6.7 | 7.0 | 0.283 | 0.295 | -4.69 | |
| H-1962N | 5/19/2026 9:28:05 AM | 122.8 | -0.43 | -0.31 | | | 0.042 | 0.033 | -5.73 | -5.99 |
| H-1962N | 5/19/2026 9:26:00 AM | 124.9 | -0.64 | -0.58 | | | 0.058 | 0.043 | -5.81 | -5.84 |
| H-1962N | 5/1/2026 2:46:00 PM | 126.9 | -0.02 | -0.03 | | | 0.000 | 0.000 | -6.42 | -6.76 |
| H-1963N | 5/19/2026 8:46:36 AM | 140.2 | -0.07 | -0.11 | 4.4 | 4.9 | 0.053 | 0.068 | -6.73 | -6.93 |
| H-1963N | 5/19/2026 8:44:46 AM | 139.9 | -0.24 | -0.22 | 5.5 | 4.5 | 0.086 | 0.056 | -6.87 | -7.30 |
| H-1963N | 5/1/2026 12:06:22 PM | 141.6 | -0.31 | -0.30 | 8.2 | 8.2 | 0.190 | 0.189 | -8.11 | -7.82 |
| H-1963N | 5/1/2026 12:04:32 PM | 141.3 | 0.49 | -0.23 | 2.6 | 9.3 | 0.019 | 0.246 | -7.82 | -7.86 |
| H-1966N | 5/19/2026 10:06:37 AM | 105.4 | -0.29 | -0.30 | 3.7 | 3.6 | 1.442 | 1.416 | -4.18 | -4.11 |
| H-1966N | 5/12/2026 10:42:28 AM | 105.7 | -0.29 | -0.27 | 4.0 | 3.9 | 1.684 | 1.681 | -4.50 | |
| H-1967E | 5/7/2026 1:04:55 PM | 105.5 | -2.08 | -2.10 | 2.9 | 2.8 | 0.009 | 0.009 | -3.70 | |
| H-1967W | 5/7/2026 9:49:11 AM | 94.4 | -0.15 | -0.15 | 48.2 | 48.2 | 2.554 | 2.555 | -3.45 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| H-1967W | 5/7/2026 9:47:56 AM | 94.1 | 1.20 | -0.07 | 32.9 | 49.0 | 1.182 | 2.624 | -2.55 | |
| H-2050E | 5/14/2026 9:38:59 AM | 86.5 | -10.17 | -10.30 | 0.0 | 0.0 | -0.023 | -0.009 | -10.26 | |
| H-2050W | 5/5/2026 3:39:36 PM | 100.5 | -0.84 | -0.73 | 5.7 | 6.8 | 0.639 | 0.911 | -4.87 | |
| H-2051W | 5/7/2026 9:44:33 AM | 85.8 | -0.15 | -1.35 | 0.0 | 3.2 | -0.013 | 0.011 | -3.43 | |
| H-2053E | 5/7/2026 1:13:15 PM | 119.4 | -2.16 | -1.48 | 31.4 | 26.0 | 1.177 | 0.806 | -4.01 | |
| H-2053W | 5/13/2026 8:39:25 AM | 91.6 | -7.55 | -7.81 | 20.7 | 22.1 | 0.534 | 0.612 | -7.88 | -7.91 |
| H-2055E | 5/22/2026 10:10:19 AM | 107.7 | -1.34 | -1.32 | 2.9 | 2.6 | 2.279 | 1.801 | -11.77 | |
| H-2055E | 5/6/2026 3:07:33 PM | 107.6 | -1.27 | -1.25 | 2.7 | 2.7 | 1.911 | 1.909 | -11.91 | |
| H-2056B | 5/8/2026 3:07:26 PM | 91.2 | -1.33 | -1.34 | 0.8 | 1.0 | 0.072 | 0.095 | -4.44 | |
| H-2056W | 5/7/2026 9:41:29 AM | 95.7 | -0.05 | -0.51 | 54.4 | 54.1 | 3.235 | 3.205 | -3.64 | |
| H-2057E | 5/7/2026 1:10:46 PM | 125.6 | -1.32 | -1.78 | 6.1 | 6.3 | 0.749 | 0.798 | -4.35 | |
| H-2057W | 5/28/2026 8:44:04 AM | 82.1 | -0.24 | -0.66 | | | 0.319 | 0.690 | -7.05 | -7.02 |
| H-2057W | 5/13/2026 8:09:16 AM | 79.4 | -4.45 | -4.48 | | | 4.417 | 4.465 | -7.78 | -7.92 |
| H-2057W | 5/13/2026 8:05:12 AM | 80.1 | -7.28 | -6.22 | | | 7.360 | 6.348 | -7.97 | -7.83 |
| H-2058E | 5/7/2026 1:22:33 PM | 110.1 | -1.20 | -1.20 | 26.6 | 23.3 | 0.817 | 0.626 | -2.15 | |
| H-2058W | 5/7/2026 9:34:28 AM | 94.7 | -0.16 | -0.15 | 24.0 | 23.9 | 0.633 | 0.628 | -3.74 | |
| H-2058W | 5/7/2026 9:33:03 AM | 94.1 | 0.36 | -0.18 | 11.6 | 24.8 | 0.145 | 0.666 | -3.33 | |
| H-2059E | 5/6/2026 12:36:07 PM | 117.7 | -9.28 | -9.30 | 5.8 | 5.2 | 0.684 | 0.541 | -10.03 | |
| H-2059W | 5/7/2026 10:12:44 AM | 126.7 | -1.02 | -1.02 | 38.5 | 38.5 | 1.827 | 1.824 | -3.03 | |
| H-2161E | 5/6/2026 12:32:34 PM | 124.0 | -2.77 | -3.35 | 39.0 | 42.2 | 1.829 | 2.152 | -9.76 | |
| H-2161W | 5/7/2026 10:08:23 AM | 107.3 | -3.37 | -3.28 | 0.0 | 3.5 | -0.001 | 0.013 | -3.33 | |
| H-2163C | 5/22/2026 10:05:49 AM | 90.0 | -0.49 | -0.48 | 0.8 | 0.9 | 0.072 | 0.078 | -9.13 | |
| H-2163C | 5/4/2026 10:05:22 AM | 83.7 | -0.34 | -0.34 | 0.4 | 0.4 | 0.019 | 0.020 | -10.46 | |
| H-2163W | 5/7/2026 10:22:23 AM | 125.5 | -0.06 | -0.06 | 17.8 | 17.8 | 2.214 | 2.210 | -3.09 | |
| H-2164E | 5/22/2026 10:41:07 AM | 125.4 | -0.04 | -0.07 | 3.8 | 4.0 | 0.105 | 0.115 | -5.30 | |
| H-2164E | 5/6/2026 3:22:38 PM | 127.2 | -0.14 | -0.13 | 7.5 | 7.5 | 0.426 | 0.428 | -12.25 | |
| H-2164E | 5/6/2026 3:21:24 PM | 126.2 | 0.01 | -0.06 | 0.0 | 5.7 | -0.022 | 0.240 | -11.72 | |
| H-2165E | 5/4/2026 10:55:10 AM | 109.5 | -1.70 | -1.54 | 12.3 | 13.9 | 0.955 | 1.216 | -8.79 | -8.82 |
| H-2165W | 5/20/2026 9:46:57 AM | 120.0 | -0.68 | -0.55 | 4.5 | 3.9 | 0.127 | 0.096 | -7.28 | -7.30 |
| H-2165W | 5/12/2026 7:45:00 AM | | | | | | | | | |
| H-2165W | 5/12/2026 7:45:00 AM | | | | | | | | | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| H-2165W | 5/1/2026 10:16:24 AM | 117.5 | -0.09 | -0.05 | 2.2 | 2.5 | 0.032 | 0.040 | -8.60 | -8.63 |
| H-2166E | 5/4/2026 1:12:58 PM | 101.5 | -0.36 | -0.31 | 1.6 | 0.7 | 0.016 | 0.003 | -2.12 | -2.10 |
| H-2168C | 5/1/2026 10:48:38 AM | 85.4 | -12.70 | -12.64 | | | 0.010 | 0.016 | -12.62 | |
| H-2168E | 5/28/2026 12:08:16 PM | 120.1 | -0.92 | -1.00 | 5.8 | 6.0 | 0.218 | 0.233 | -14.91 | -15.02 |
| H-2168E | 5/6/2026 2:36:05 PM | 120.0 | -0.16 | -0.17 | 4.0 | 4.1 | 0.099 | 0.105 | -13.97 | -14.71 |
| H-2168E | 5/5/2026 10:39:26 AM | 71.5 | -0.24 | -0.24 | 6.4 | 6.5 | 0.237 | 0.244 | 0.13 | 0.14 |
| H-2168E | 5/5/2026 10:37:49 AM | 70.2 | -0.23 | -0.22 | 6.2 | 6.1 | 0.226 | 0.216 | 0.08 | 0.12 |
| H-2168E | 5/1/2026 2:15:28 PM | 120.2 | -0.11 | -0.11 | 4.2 | 4.2 | 0.113 | 0.113 | -12.59 | -12.59 |
| H-2169C | 5/4/2026 11:55:39 AM | 104.8 | -2.56 | -2.69 | 17.7 | 18.8 | 0.401 | 0.453 | -12.16 | -12.25 |
| H-2169E | 5/1/2026 2:05:32 PM | 114.9 | -0.12 | -0.12 | 10.9 | 11.1 | 0.153 | 0.160 | -12.60 | -12.71 |
| H-2170N | 5/4/2026 2:04:41 PM | 117.2 | -0.65 | -0.66 | 14.1 | 15.2 | 1.266 | 1.472 | -10.39 | -10.55 |
| H-2170S | 5/11/2026 8:29:12 AM | 102.0 | -2.15 | -2.03 | 1.9 | 3.9 | 0.016 | 0.088 | -13.92 | |
| H-2171A | 5/14/2026 8:58:08 AM | 94.8 | -0.70 | -0.70 | 0.7 | 0.8 | 0.054 | 0.058 | -1.60 | -1.59 |
| H-2171A | 5/14/2026 8:54:11 AM | 94.4 | -0.80 | -0.69 | 2.7 | 0.7 | 0.778 | 0.049 | -1.26 | -1.59 |
| H-2171A | 5/13/2026 10:13:53 AM | 94.5 | -0.88 | -0.88 | 2.4 | 2.4 | 0.035 | 0.035 | -1.98 | -2.03 |
| H-2171A | 5/13/2026 10:08:18 AM | 96.6 | -1.07 | -0.92 | 4.2 | 1.3 | 0.108 | 0.011 | -1.19 | -1.62 |
| H-2171A | 5/7/2026 9:32:22 AM | 93.3 | -0.76 | -0.76 | 0.0 | 0.0 | -0.016 | -0.033 | -0.72 | |
| H-2171B | 5/13/2026 2:00:46 PM | 119.7 | -1.16 | -1.16 | 16.3 | 16.0 | 1.690 | 1.619 | -2.44 | -2.26 |
| H-2171N | 5/7/2026 9:22:04 AM | 111.0 | -0.03 | -0.09 | 0.0 | 3.2 | -0.073 | 0.061 | -3.61 | |
| H-2171S | 5/4/2026 2:02:33 PM | 119.2 | -1.27 | -1.15 | 21.2 | 19.1 | 2.864 | 2.341 | -10.59 | -10.85 |
| H-2272W | 5/19/2026 10:27:12 AM | 124.1 | -0.57 | -0.57 | 7.0 | 6.9 | 1.049 | 1.003 | -6.71 | -6.71 |
| H-2272W | 5/4/2026 9:50:05 AM | 122.9 | -0.55 | -0.56 | 5.5 | 5.5 | 0.632 | 0.633 | -8.46 | -8.60 |
| H-2272W | 5/4/2026 9:47:59 AM | 122.7 | -0.56 | -0.59 | 4.6 | 6.0 | 0.455 | 0.759 | -8.44 | -8.57 |
| H-2273W | 5/20/2026 8:21:56 AM | 129.3 | -0.77 | -0.67 | 10.7 | 10.1 | 0.749 | 0.665 | -8.30 | -8.16 |
| H-2273W | 5/13/2026 12:42:00 PM | 127.0 | -0.53 | -0.64 | 1.2 | 5.0 | 0.010 | 0.176 | -7.48 | |
| H-2273W | 5/12/2026 7:50:00 AM | | | | | | | | | |
| H-2273W | 5/12/2026 7:50:00 AM | | | | | | | | | |
| H-2274B | 5/20/2026 2:09:49 PM | 96.2 | -0.78 | -0.80 | 10.8 | 10.8 | 0.299 | 0.298 | -7.77 | |
| H-2274B | 5/4/2026 1:23:52 PM | 82.5 | -1.96 | -1.96 | 2.5 | 2.5 | 0.015 | 0.015 | -8.60 | |
| H-2274W | 5/19/2026 1:17:54 PM | 125.3 | -0.22 | -0.20 | 1.7 | 2.1 | 0.020 | 0.029 | -2.88 | -2.67 |
| H-2274W | 5/1/2026 10:22:35 AM | 129.6 | -0.45 | -0.36 | 8.4 | 5.5 | 0.458 | 0.193 | -8.39 | -6.58 |
| H-2275E | 5/4/2026 11:24:01 AM | 121.8 | -1.01 | -0.70 | 6.3 | 1.5 | 0.253 | 0.015 | -8.83 | -8.96 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| H-2275W | 5/20/2026 7:50:11 AM | 122.8 | -0.93 | -0.85 | 12.1 | 11.5 | 0.944 | 0.846 | -9.28 | -9.20 |
| H-2275W | 5/8/2026 11:15:19 AM | 112.5 | -0.08 | -0.08 | 2.5 | 2.5 | 0.148 | 0.146 | -4.76 | |
| H-2275W | 5/8/2026 11:13:59 AM | 116.4 | 0.26 | -0.13 | 4.0 | 1.0 | 0.355 | 0.026 | -4.77 | |
| H-2276A | 5/20/2026 1:13:04 PM | 107.9 | -2.91 | -2.87 | 13.0 | 12.8 | 0.216 | 0.212 | -3.30 | -3.28 |
| H-2276A | 5/11/2026 1:32:34 PM | 106.7 | -4.99 | -4.92 | 20.5 | 20.2 | 0.544 | 0.525 | -5.72 | -5.58 |
| H-2276B | 5/20/2026 2:22:12 PM | 118.3 | -2.11 | -2.16 | 17.0 | 19.4 | 0.625 | 0.822 | -7.61 | |
| H-2276B | 5/4/2026 2:06:44 PM | 114.3 | -2.00 | -2.21 | 14.2 | 19.5 | 0.427 | 0.806 | -8.27 | |
| H-2276E | 5/4/2026 11:37:57 AM | 115.6 | -0.55 | -0.53 | 10.0 | 7.7 | 0.129 | 0.076 | -13.75 | -14.05 |
| H-2276W | 5/20/2026 8:32:50 AM | 92.7 | -5.75 | -4.89 | 10.5 | 9.2 | 0.675 | 0.519 | -7.71 | -7.68 |
| H-2276W | 5/1/2026 10:16:43 AM | 102.9 | -6.28 | -5.79 | 14.9 | 12.7 | 1.388 | 1.011 | -7.54 | -7.30 |
| H-2277A | 5/21/2026 9:41:03 AM | 93.8 | -0.14 | -0.11 | 1.5 | 1.5 | 0.013 | 0.014 | -3.79 | -3.86 |
| H-2277A | 5/1/2026 11:04:15 AM | 79.9 | -7.45 | -7.10 | 15.2 | 13.0 | 1.403 | 1.021 | -7.38 | -7.52 |
| H-2277B | 5/21/2026 9:35:16 AM | 117.5 | -2.16 | -2.13 | 1.6 | 1.6 | 0.673 | 0.725 | -5.27 | -5.23 |
| H-2277B | 5/4/2026 2:19:04 PM | 115.5 | -3.28 | -2.60 | 19.9 | 16.6 | 2.414 | 1.673 | -7.85 | |
| H-23 (EXP-23) | 5/13/2026 1:17:40 PM | 94.1 | -0.99 | -0.90 | 1.9 | 2.1 | 0.004 | 0.006 | -8.68 | -8.71 |
| H-23 (EXP-23) | 5/13/2026 1:13:21 PM | 92.2 | -4.99 | -4.99 | 0.4 | 0.1 | 0.003 | 0.000 | -8.93 | -8.69 |
| H-23 (EXP-23) | 5/13/2026 10:53:27 AM | 86.9 | -1.06 | -0.91 | 0.2 | 0.6 | 0.001 | 0.006 | -9.66 | -9.39 |
| H-23 (EXP-23) | 5/13/2026 10:40:54 AM | 77.4 | -9.82 | -9.65 | 3.5 | 2.7 | 0.027 | 0.016 | -10.06 | -10.09 |
| H-2301E | 5/13/2026 9:05:55 AM | 105.3 | -3.31 | -3.31 | 14.6 | 16.4 | 0.270 | 0.340 | -9.93 | -10.12 |
| H-2301W | 5/15/2026 10:14:58 AM | 73.0 | -10.51 | -10.46 | 0.0 | 0.0 | -0.056 | -0.039 | -10.50 | |
| H-2301W | 5/15/2026 10:13:21 AM | 72.5 | -10.39 | -10.37 | 0.0 | 0.0 | -0.019 | -0.022 | -10.64 | |
| H-2302C | 5/7/2026 2:47:12 PM | 117.4 | -0.50 | -0.75 | 9.9 | 14.4 | 0.576 | 1.232 | -5.42 | |
| H-2302E | 5/8/2026 12:55:32 PM | 105.2 | -1.88 | -1.87 | 31.7 | 31.6 | 1.136 | 1.130 | -3.30 | |
| H-2303E | 5/8/2026 1:01:15 PM | 88.7 | -2.57 | -2.57 | 0.0 | 0.0 | -0.009 | -0.009 | -2.49 | |
| H-2303N | 5/7/2026 2:55:44 PM | 102.5 | -0.10 | -0.21 | 12.9 | 16.6 | 3.195 | 5.298 | -7.43 | |
| H-2304E | 5/8/2026 1:05:45 PM | 95.6 | -1.26 | -1.27 | 40.9 | 32.9 | 0.366 | 0.236 | -1.84 | |
| H-2304S | 5/8/2026 1:30:30 PM | 123.8 | -0.18 | -0.29 | 18.0 | 19.7 | 6.591 | 7.878 | -9.97 | |
| H-2305N | 5/7/2026 3:01:47 PM | 98.7 | -3.09 | -3.64 | 3.6 | 4.6 | 0.027 | 0.043 | -7.43 | |
| H-2305S | 5/8/2026 1:14:11 PM | 126.4 | -0.11 | -0.24 | 21.2 | 23.5 | 2.715 | 3.344 | | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| H-2306N | 5/15/2026 10:33:03 AM | 116.5 | -2.83 | -2.83 | 39.7 | 39.7 | 3.374 | 3.374 | -11.44 | |
| H-2307S | 5/22/2026 11:53:04 AM | 115.0 | -2.02 | -2.02 | 36.1 | 36.1 | 3.027 | 3.031 | -9.85 | -9.80 |
| H-2307S | 5/7/2026 2:41:47 PM | 120.0 | -0.23 | -0.22 | 37.7 | 38.2 | 3.066 | 3.148 | -6.93 | |
| H-2307S | 5/7/2026 2:40:20 PM | 118.6 | 0.84 | -0.04 | 10.2 | 38.5 | 0.218 | 3.157 | -6.80 | |
| H-2308S | 5/7/2026 2:29:52 PM | 120.3 | -1.54 | -1.44 | 42.9 | 39.9 | 2.189 | 1.903 | -7.18 | |
| H-2309N | 5/4/2026 10:13:40 AM | 83.7 | -1.30 | -1.29 | 0.0 | 0.0 | -0.157 | -0.158 | -10.55 | |
| H-2309S | 5/8/2026 1:53:32 PM | 109.3 | -0.19 | -0.40 | 18.4 | 23.2 | 0.388 | 0.622 | -11.11 | |
| H-2310N | 5/8/2026 3:03:25 PM | 110.2 | -0.41 | -0.52 | 7.3 | 13.1 | 0.306 | 0.998 | -4.08 | |
| H-2310S | 5/22/2026 12:06:57 PM | 102.8 | -1.16 | -0.55 | 2.3 | 1.3 | 0.552 | 0.180 | -10.32 | -10.02 |
| H-2310S | 5/14/2026 9:47:40 AM | 100.9 | -2.64 | -1.71 | | | 0.193 | 0.091 | -10.07 | |
| H-2401S | 5/7/2026 11:32:52 AM | 108.8 | -1.35 | -1.62 | 4.6 | 5.7 | 0.424 | 0.638 | -3.74 | |
| H-2402N | 5/8/2026 9:47:00 AM | 105.9 | -0.34 | -0.33 | 1.5 | 1.5 | 0.239 | 0.238 | -4.36 | |
| H-2402S | 5/8/2026 9:58:19 AM | 109.7 | -0.39 | -0.50 | 15.8 | 19.5 | 0.288 | 0.439 | -4.72 | |
| H-2403N | 5/8/2026 9:51:09 AM | 112.3 | -0.03 | -0.13 | 0.0 | 4.1 | -0.126 | 0.339 | -4.34 | |
| H-2403S | 5/8/2026 9:35:34 AM | 80.3 | -0.53 | -0.51 | 1.3 | 1.3 | 0.169 | 0.174 | -4.16 | |
| H-2404N | 5/5/2026 3:35:40 PM | 109.0 | -1.26 | -2.14 | 7.2 | 11.0 | 1.019 | 2.417 | -9.28 | |
| H-2404S | 5/8/2026 8:59:38 AM | 111.4 | -3.40 | -3.39 | 6.9 | 25.8 | 0.054 | 0.762 | -3.81 | |
| H-2405N | 5/5/2026 2:23:59 PM | 111.8 | -0.59 | -0.58 | 14.0 | 14.0 | 4.131 | 4.133 | -8.69 | |
| H-29 | 5/29/2026 12:05:20 PM | 84.1 | -0.10 | -0.10 | 1.0 | 0.9 | 0.019 | 0.017 | -10.76 | -10.76 |
| H-29 | 5/29/2026 12:00:31 PM | 89.1 | 0.93 | -0.13 | 2.3 | 3.7 | 0.101 | 0.271 | -10.71 | -11.09 |
| H-29 | 5/4/2026 1:58:42 PM | 71.0 | -0.31 | -0.31 | 1.0 | 1.0 | 0.020 | 0.020 | -11.23 | -11.23 |
| H-29 | 5/4/2026 1:55:50 PM | 71.1 | 1.61 | -0.20 | 2.5 | 6.0 | 0.119 | 0.706 | -11.13 | -11.23 |
| H-72 | 5/29/2026 9:51:57 AM | 82.2 | -0.37 | -0.45 | 0.0 | 0.0 | -0.096 | -0.016 | -4.60 | |
| H-74 | 5/11/2026 11:20:34 AM | 101.6 | -1.20 | -1.23 | 5.2 | 6.2 | 0.534 | 0.755 | 0.02 | |
| H-75 | 5/14/2026 11:59:28 AM | 90.5 | -0.23 | -0.23 | 2.2 | 2.2 | 1.230 | 1.233 | -10.58 | |
| H-79 | 5/15/2026 11:24:44 AM | 128.6 | -2.71 | -2.70 | 2.4 | 1.9 | 0.007 | 0.005 | -14.33 | |
| P-02R | 5/13/2026 8:15:30 AM | 82.2 | -0.65 | -0.64 | 8.9 | 10.4 | 0.465 | 0.644 | -20.57 | -21.01 |
| P-03R | 5/13/2026 8:26:58 AM | 87.7 | -1.65 | -1.65 | 3.0 | 2.9 | 0.899 | 0.873 | -19.68 | -19.72 |
| P-04 | 5/5/2026 7:38:51 AM | 91.5 | -0.50 | -0.50 | | | 0.502 | 0.503 | -17.63 | -17.65 |
| P-05 | 5/5/2026 7:46:02 AM | 102.1 | -0.27 | -0.27 | | | 0.272 | 0.272 | -16.42 | -16.56 |
| P-06R | 5/5/2026 7:49:46 AM | 106.2 | -0.69 | -0.69 | 0.2 | 0.3 | 0.003 | 0.011 | -15.79 | -15.62 |
| P-07R | 5/12/2026 8:59:48 AM | 83.4 | -0.88 | -0.88 | 4.5 | 4.5 | 2.046 | 2.066 | -19.06 | -19.13 |
| P-08R | 5/11/2026 10:46:01 AM | 101.9 | -15.23 | -15.52 | 1.7 | 5.9 | 0.018 | 0.220 | -16.37 | -16.59 |
| P-09 | 5/5/2026 8:01:21 AM | 94.5 | -0.61 | -0.61 | | | 0.609 | 0.608 | -11.96 | -11.91 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| P-10 | 5/5/2026 7:56:04 AM | 85.8 | -0.34 | -0.33 | 3.1 | 3.1 | 0.983 | 1.007 | -11.51 | -11.93 |
| P-11 | 5/12/2026 9:25:09 AM | 104.2 | -0.43 | -0.43 | 6.3 | 6.4 | 4.248 | 4.419 | -11.64 | -12.06 |
| P-12 | 5/15/2026 7:59:36 AM | 74.1 | -11.34 | -11.89 | 4.0 | 1.4 | 0.292 | 0.036 | -14.20 | |
| P-13 | 5/15/2026 8:05:44 AM | 78.1 | -1.24 | -1.26 | 8.3 | 8.3 | 1.250 | 1.266 | -14.84 | |
| P-14 | 5/5/2026 8:13:25 AM | 73.0 | -0.40 | -0.34 | | | 0.394 | 0.342 | -13.69 | -13.02 |
| P-15R | 5/5/2026 8:17:20 AM | 71.3 | -1.20 | -1.21 | 0.8 | 0.9 | 0.066 | 0.075 | -12.57 | -12.71 |
| P-16 | 5/5/2026 8:25:52 AM | 79.3 | -2.73 | -2.73 | 3.7 | 3.6 | 3.369 | 3.292 | -12.19 | -12.14 |
| P-17 | 5/5/2026 8:30:43 AM | 109.2 | -1.08 | -1.08 | | | 1.065 | 1.068 | -11.59 | -12.12 |
| P-18RD | 5/5/2026 8:41:50 AM | 81.6 | -9.67 | -9.66 | 3.5 | 3.5 | 1.281 | 1.274 | -10.96 | -11.09 |
| P-18RS | 5/5/2026 8:36:36 AM | 91.2 | -1.43 | -1.42 | 5.3 | 5.2 | 2.871 | 2.769 | -11.48 | -11.00 |
| P-19 | 5/4/2026 11:16:30 AM | 84.0 | -1.13 | -1.07 | 7.6 | 5.8 | 0.325 | 0.189 | -11.82 | |
| P-20R | 5/5/2026 8:45:27 AM | 96.2 | -1.36 | -1.36 | 8.2 | 8.3 | 7.101 | 7.187 | -10.85 | -10.90 |
| P-21 | 5/5/2026 8:49:59 AM | 89.3 | -0.67 | -0.67 | | | 0.666 | 0.665 | -10.65 | -10.38 |
| P-21RD | 5/4/2026 10:03:26 AM | 98.9 | -4.27 | -4.27 | 21.0 | 20.7 | 2.614 | 2.525 | -8.94 | |
| P-21RS | 5/4/2026 10:00:38 AM | 107.1 | -4.23 | -4.12 | 11.2 | 11.2 | 0.712 | 0.714 | -9.22 | |
| P-22RD | 5/4/2026 10:32:00 AM | 114.2 | -4.38 | -4.37 | 4.5 | 4.4 | 5.289 | 5.075 | -8.95 | |
| P-22RS | 5/4/2026 10:28:52 AM | 119.1 | -1.28 | -1.25 | 40.5 | 39.3 | 1.946 | 1.828 | -9.30 | |
| P-23 | 5/5/2026 8:59:25 AM | 82.4 | -0.68 | -0.68 | 6.3 | 6.3 | 0.250 | 0.253 | -9.81 | -9.79 |
| P-24 | 5/6/2026 8:17:07 AM | 88.3 | -2.34 | -2.32 | 11.7 | 11.2 | 2.738 | 2.506 | -10.03 | |
| P-26 | 5/6/2026 8:34:09 AM | 80.9 | -6.27 | -6.31 | 0.0 | 0.0 | 6.235 | 6.447 | | |
| P-27 | 5/6/2026 8:43:29 AM | 72.3 | -0.94 | -0.84 | 0.0 | 0.0 | 0.961 | 0.820 | | |
| P-28 | 5/6/2026 8:51:00 AM | 95.1 | -5.34 | -5.27 | 0.0 | 0.0 | 5.370 | 5.256 | | |
| P-29R | 5/6/2026 8:57:44 AM | 90.8 | -1.53 | -1.53 | 1.5 | 0.6 | 0.014 | 0.002 | -7.84 | |
| P-30R | 5/6/2026 9:04:44 AM | 83.5 | -6.22 | -6.14 | 10.2 | 9.9 | 2.085 | 1.984 | -7.66 | |
| P-32R1 | 5/6/2026 9:10:45 AM | 109.7 | -1.92 | -1.89 | 2.8 | 2.3 | 8.334 | 5.730 | -7.14 | |
| P-32R2 | 5/6/2026 9:14:09 AM | 110.5 | -2.36 | -2.32 | 11.3 | 10.1 | 2.670 | 2.131 | -7.35 | |
| P-33 | 5/6/2026 9:19:40 AM | 93.1 | -2.79 | -2.69 | 0.0 | 0.0 | 2.778 | 2.631 | | |
| P-36 | 5/6/2026 9:31:05 AM | 69.6 | -0.44 | -0.47 | 0.0 | 0.0 | 0.513 | 0.513 | | |
| P-37 | 5/6/2026 9:35:20 AM | 84.4 | -0.50 | -0.47 | 0.9 | 0.9 | 0.232 | 0.233 | -4.56 | |
| P-38RD | 5/6/2026 9:48:07 AM | 106.4 | -4.18 | -4.19 | 32.6 | 17.1 | 1.255 | 0.346 | -4.19 | |
| P-38RS | 5/6/2026 9:44:32 AM | 104.4 | -1.44 | -1.40 | 10.7 | 12.3 | 0.688 | 0.897 | -4.30 | |
| P-39 | 5/6/2026 9:55:17 AM | 78.9 | -6.11 | -6.96 | 2.2 | 0.0 | 0.094 | -0.016 | -7.06 | |
| P-41 | 5/6/2026 10:07:48 AM | 108.2 | -2.99 | -2.89 | 0.0 | 0.0 | -0.154 | -0.007 | | |
| P-41 | 5/6/2026 10:06:10 AM | 108.6 | -3.22 | -3.14 | 0.0 | 0.0 | -0.019 | 0.139 | | |
| P-42R | 5/6/2026 10:15:47 AM | 111.6 | -6.82 | -6.76 | 3.6 | 3.1 | 1.292 | 0.951 | -8.60 | |
| P-43 | 5/6/2026 10:22:56 AM | 116.6 | -4.38 | -4.34 | 0.0 | 0.0 | 4.403 | 4.303 | | |
| P-44RD | 5/6/2026 10:37:00 AM | 90.4 | -7.70 | -7.71 | 0.0 | 0.0 | -0.038 | -0.020 | -8.41 | |
| P-44RS | 5/6/2026 10:33:49 AM | 121.8 | -5.71 | -5.69 | 18.4 | 18.6 | 2.145 | 2.188 | -7.72 | |
| P-45RD | 5/6/2026 10:50:26 AM | 114.9 | -7.01 | -7.06 | 3.7 | 3.5 | 0.287 | 0.247 | -7.72 | |
| P-45RS | 5/6/2026 10:47:34 AM | 92.2 | -0.64 | -0.61 | 0.0 | 0.0 | -0.084 | -0.003 | -7.62 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| P-46RD | 5/6/2026 11:02:37 AM | 102.4 | -7.60 | -7.66 | 2.0 | 0.8 | 0.023 | 0.003 | -7.60 | |
| P-46RS | 5/6/2026 10:55:16 AM | 120.7 | -2.42 | -2.34 | 24.6 | 21.9 | 3.805 | 3.028 | -7.77 | |
| P-47 | 5/4/2026 10:21:39 AM | 96.9 | -0.16 | -0.12 | 0.0 | 0.0 | 0.170 | 0.166 | | |
| P-48 | 5/4/2026 10:38:03 AM | 111.5 | -0.17 | -0.12 | 0.0 | 0.0 | 0.011 | 0.000 | | |
| P-49RD | 5/4/2026 10:58:34 AM | 112.8 | -10.02 | -10.06 | 16.0 | 16.4 | 1.525 | 1.595 | -11.71 | |
| P-49RS | 5/4/2026 10:55:41 AM | 113.7 | -1.23 | -1.18 | 18.1 | 18.7 | 0.699 | 0.745 | -12.10 | |
| P-52 | 5/28/2026 2:38:45 PM | 117.0 | -0.42 | -0.38 | | | 0.000 | 0.000 | -13.73 | -13.98 |
| P-53 | 5/15/2026 8:37:53 AM | 114.6 | -2.32 | -2.20 | 0.0 | 0.0 | -0.013 | -0.009 | -17.38 | |
| P-54 | 5/15/2026 8:35:38 AM | 100.8 | -1.22 | -1.14 | 0.0 | 0.0 | 1.161 | 0.999 | | |
| P-55 | 5/15/2026 8:24:48 AM | 94.0 | -0.74 | -0.65 | 0.0 | 0.0 | 0.710 | 0.695 | | |
| P-56 | 5/26/2026 9:15:49 AM | 101.8 | -0.31 | -0.31 | | | 0.302 | 0.301 | -15.62 | -15.63 |
| P-57 | 5/13/2026 9:14:04 AM | 76.4 | -0.54 | -0.53 | 3.6 | 3.4 | 0.015 | 0.014 | -19.39 | -19.13 |
| P-60R | 5/7/2026 8:52:45 AM | 76.5 | -2.40 | -2.29 | 0.0 | 0.0 | -0.060 | -0.075 | -2.82 | |
| P-60R | 5/7/2026 8:48:07 AM | 75.5 | -2.46 | -2.37 | 0.0 | 0.0 | 0.000 | -0.014 | -2.78 | |
| P-61 | 5/7/2026 8:30:07 AM | 83.4 | -0.34 | -0.31 | 5.0 | 5.0 | 2.472 | 2.502 | -2.75 | |
| P-65 | 5/7/2026 8:25:21 AM | 71.5 | -0.61 | -0.62 | 2.0 | 1.9 | 0.999 | 0.853 | -2.88 | |
| P-71 | 5/4/2026 10:47:48 AM | 72.3 | -0.39 | -0.38 | 0.0 | 0.0 | 0.373 | 0.377 | | |
| P-75 | 5/6/2026 11:19:49 AM | 92.0 | -3.99 | -4.02 | 17.4 | 17.5 | 1.669 | 1.689 | -4.37 | |
| P-76 | 5/6/2026 9:41:27 AM | 97.2 | -1.85 | -1.78 | 0.0 | 0.0 | -1.760 | -1.750 | -4.17 | |
| P-79 | 5/4/2026 11:21:51 AM | 86.4 | -0.35 | -0.30 | 0.0 | 0.0 | 0.261 | 0.264 | -10.40 | |
| SC-2000E | 5/6/2026 12:28:45 PM | 119.4 | -3.42 | -3.22 | 5.2 | 5.9 | 0.553 | 0.703 | -7.89 | |
| SC-2501E | 5/26/2026 9:21:31 AM | 189.2 | -0.77 | -0.88 | 14.2 | 13.0 | 0.531 | 0.441 | -4.08 | -4.41 |
| SC-2501E | 5/18/2026 9:40:35 AM | | 0.16 | | 10.5 | | 0.288 | | -2.97 | |
| SC-2501E | 5/18/2026 9:40:00 AM | | | | | | | | | |
| SC-2501E | 5/18/2026 9:38:11 AM | 189.1 | 0.65 | 0.72 | 44.0 | 41.7 | 5.079 | 4.563 | -3.93 | -3.49 |
| SC-2501E | 5/18/2026 9:29:29 AM | 190.6 | 1.07 | -0.76 | 20.4 | 16.6 | 1.086 | 0.722 | -2.01 | -2.32 |
| SC-2501E | 5/12/2026 9:13:45 AM | 188.9 | -1.07 | -1.13 | 53.0 | 52.5 | 7.423 | 7.294 | -8.18 | -8.02 |
| SC-2501E | 5/12/2026 9:10:00 AM | | | | | | | | | |
| SC-2501E | 5/5/2026 8:56:40 AM | 188.8 | -1.63 | -1.63 | 52.3 | 51.7 | 7.247 | 7.078 | -8.76 | -8.66 |
| SC-2501E | 5/5/2026 8:51:59 AM | 188.6 | -0.64 | -1.24 | 38.7 | 32.1 | 10.915 | 7.472 | -9.63 | -8.78 |
| SC-2501E | 5/5/2026 8:50:00 AM | | | | | | | | | |
| SC-2501E | 5/5/2026 8:50:00 AM | | | | | | | | | |
| SC-2501W | 5/5/2026 9:19:42 AM | 94.4 | -0.04 | -0.01 | 3.7 | 3.2 | 0.083 | 0.064 | -7.23 | -7.22 |
| SW-10 | 5/28/2026 9:37:50 AM | 71.4 | -7.45 | -7.43 | | | 0.975 | 0.954 | -7.45 | -7.32 |
| SW-115 | 5/11/2026 8:59:04 AM | 88.6 | -6.65 | -6.61 | 12.4 | 14.1 | 0.892 | 1.160 | -11.97 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| SW-1445 | 5/22/2026 7:39:28 AM | 61.4 | -0.03 | -0.03 | 5.3 | 4.9 | 0.033 | 0.028 | 0.22 | 0.21 |
| SW-1445 | 5/4/2026 7:53:57 AM | 80.9 | -5.41 | -5.41 | 22.8 | 23.1 | 0.640 | 0.653 | -5.26 | -5.17 |
| SW-1455 | 5/22/2026 7:44:18 AM | 67.3 | 0.02 | 0.02 | 2.1 | 2.3 | 0.005 | 0.006 | 0.32 | 0.08 |
| SW-1455 | 5/4/2026 7:57:56 AM | 83.5 | -5.75 | -5.75 | 25.4 | 25.0 | 0.795 | 0.772 | -5.37 | -5.42 |
| SW-154 | 5/15/2026 9:34:29 AM | 66.8 | -8.39 | -8.34 | 0.0 | 0.0 | 8.477 | 8.394 | | |
| SW-154 | 5/15/2026 9:31:56 AM | 67.0 | -8.11 | -8.06 | 0.0 | 0.0 | 8.020 | 8.115 | | |
| SW-17-135 | 5/22/2026 7:41:29 AM | 65.9 | -0.06 | -0.05 | 8.1 | 7.4 | 0.077 | 0.065 | 0.29 | 0.30 |
| SW-17-135 | 5/4/2026 7:56:03 AM | 72.4 | -5.36 | -5.39 | 23.3 | 22.9 | 0.655 | 0.635 | -5.22 | -5.27 |
| SW-187 | 5/4/2026 9:31:29 AM | 81.6 | -7.79 | -7.79 | 69.8 | 68.8 | 1.149 | 1.115 | -7.52 | -7.54 |
| SW-1930 | 5/1/2026 7:51:05 AM | 81.3 | -8.39 | -8.45 | 81.4 | 81.2 | 8.347 | 8.317 | -8.44 | -8.44 |
| SW-20 | 5/12/2026 9:06:57 AM | 80.3 | -0.07 | -0.06 | 0.4 | 0.4 | 0.016 | 0.013 | -19.34 | -19.19 |
| SW-25 | 5/1/2026 7:53:15 AM | 65.9 | -0.81 | -0.81 | 25.9 | 25.7 | 0.791 | 0.782 | -8.44 | -8.39 |
| SW-2501D | 5/29/2026 7:21:12 AM | 72.0 | -7.73 | -7.72 | 7.6 | 8.6 | 0.069 | 0.090 | -7.44 | -7.19 |
| SW-2501D | 5/28/2026 6:16:27 AM | 71.7 | -8.11 | -8.11 | 2.5 | 2.5 | 0.643 | 0.628 | -8.29 | -8.29 |
| SW-2501D | 5/27/2026 6:04:20 AM | 68.7 | -5.23 | -5.22 | 2.5 | 2.5 | 0.649 | 0.647 | -5.09 | -5.09 |
| SW-2501D | 5/26/2026 6:11:29 AM | 72.7 | -6.63 | -6.63 | 3.0 | 3.0 | 0.941 | 0.935 | -6.31 | -6.40 |
| SW-2501D | 5/22/2026 6:19:43 AM | 70.5 | -8.32 | -8.32 | 2.9 | 2.9 | 0.835 | 0.839 | -8.18 | -8.15 |
| SW-2501D | 5/21/2026 6:35:47 AM | 77.0 | -7.73 | -7.73 | 2.2 | 2.3 | 0.519 | 0.528 | -7.74 | -7.74 |
| SW-2501D | 5/20/2026 8:30:45 AM | 78.9 | -7.46 | -7.43 | 0.7 | 0.5 | 0.048 | 0.024 | -7.59 | -7.45 |
| SW-2501D | 5/19/2026 9:01:29 AM | 79.8 | -6.08 | -6.08 | 0.4 | 0.4 | 0.018 | 0.015 | -6.08 | -6.08 |
| SW-2501D | 5/18/2026 8:44:45 AM | 76.1 | -4.74 | -4.74 | 0.4 | 0.5 | 0.017 | 0.024 | -4.85 | -4.82 |
| SW-2501D | 5/15/2026 9:25:43 AM | 77.9 | -7.43 | -7.14 | 1.5 | 0.4 | 0.239 | 0.015 | -7.12 | -7.41 |
| SW-2501D | 5/14/2026 8:19:05 AM | 75.6 | -6.67 | -6.67 | 0.7 | 0.7 | 0.052 | 0.053 | -6.74 | -6.74 |
| SW-2501D | 5/13/2026 8:08:49 AM | 75.6 | -7.62 | -7.77 | 0.5 | 0.4 | 0.021 | 0.016 | -7.69 | -7.88 |
| SW-2501D | 5/12/2026 9:15:23 AM | 79.3 | -6.64 | -6.76 | 0.8 | 0.8 | 0.061 | 0.070 | -6.76 | -6.76 |
| SW-2501D | 5/11/2026 8:24:00 AM | 77.2 | -5.46 | -5.11 | 1.1 | 0.8 | 0.120 | 0.070 | -5.40 | -5.21 |
| SW-2501D | 5/8/2026 9:35:42 AM | 75.7 | -3.41 | -3.29 | 0.6 | 0.4 | 0.040 | 0.013 | -3.22 | -3.16 |
| SW-2501D | 5/7/2026 8:55:20 AM | 74.7 | -3.60 | -3.68 | 0.8 | 0.8 | 0.061 | 0.063 | -3.17 | -3.22 |
| SW-2501D | 5/6/2026 8:47:06 AM | 72.8 | -7.47 | -7.43 | 2.7 | 2.7 | 0.737 | 0.732 | -7.62 | -7.68 |
| SW-2501D | 5/5/2026 8:31:57 AM | 72.1 | -8.28 | -8.32 | 1.2 | 0.7 | 0.154 | 0.050 | -8.14 | -8.08 |
| SW-2501D | 5/4/2026 8:20:15 AM | 71.5 | -8.15 | -8.11 | 3.7 | 3.8 | 1.430 | 1.432 | -7.97 | -7.95 |
| SW-2501D | 5/1/2026 8:28:56 AM | 71.9 | -8.31 | -8.35 | 9.0 | 9.1 | 8.452 | 8.495 | -8.41 | -8.42 |
| SW-2501M | 5/29/2026 7:24:25 AM | 62.3 | -7.56 | -7.72 | 2.7 | 0.8 | 0.009 | 0.001 | -7.40 | -7.52 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| SW-2501M | 5/28/2026 6:12:29 AM | 62.8 | -8.10 | -8.11 | 3.2 | 3.1 | 1.001 | 0.966 | -8.03 | -8.04 |
| SW-2501M | 5/27/2026 5:59:22 AM | 66.2 | -5.29 | -5.35 | 2.4 | 2.3 | 0.577 | 0.511 | -5.08 | -5.20 |
| SW-2501M | 5/26/2026 6:01:33 AM | 68.2 | -6.63 | -6.63 | 3.0 | 3.0 | 0.897 | 0.900 | -6.40 | -6.40 |
| SW-2501M | 5/22/2026 6:14:16 AM | 64.9 | -8.27 | -8.27 | 2.4 | 2.4 | 0.577 | 0.579 | -8.18 | -8.17 |
| SW-2501M | 5/21/2026 6:30:13 AM | 69.6 | -7.73 | -7.73 | 2.7 | 2.7 | 0.742 | 0.762 | -7.68 | -7.40 |
| SW-2501M | 5/20/2026 8:25:51 AM | 76.4 | -7.46 | -7.43 | 0.2 | 0.2 | 0.003 | 0.004 | -7.44 | -7.36 |
| SW-2501M | 5/19/2026 8:55:12 AM | 76.2 | -6.13 | -6.23 | 0.4 | 0.2 | 0.016 | 0.002 | -6.26 | -6.40 |
| SW-2501M | 5/18/2026 8:38:11 AM | 73.8 | -4.97 | -5.00 | 0.5 | 0.4 | 0.027 | 0.018 | -4.66 | -4.88 |
| SW-2501M | 5/15/2026 9:19:11 AM | 72.0 | -7.43 | -7.24 | 0.9 | 0.8 | 0.080 | 0.059 | -7.41 | -7.31 |
| SW-2501M | 5/14/2026 8:13:12 AM | 71.6 | -6.68 | -6.68 | 0.8 | 0.8 | 0.069 | 0.070 | -6.69 | -6.69 |
| SW-2501M | 5/13/2026 8:03:42 AM | 70.9 | -7.74 | -7.73 | 0.7 | 0.4 | 0.050 | 0.016 | -7.53 | -7.53 |
| SW-2501M | 5/12/2026 9:11:04 AM | 75.7 | -6.77 | -6.76 | 0.1 | 0.1 | 0.001 | 0.001 | -6.85 | -6.76 |
| SW-2501M | 5/11/2026 8:20:03 AM | 77.8 | -5.11 | -5.19 | 0.4 | 0.4 | 0.017 | 0.014 | -4.85 | -4.90 |
| SW-2501M | 5/8/2026 9:30:13 AM | 73.5 | -3.41 | -3.42 | 0.1 | 0.5 | 0.001 | 0.025 | -3.22 | -3.18 |
| SW-2501M | 5/7/2026 8:50:28 AM | 73.3 | -3.77 | -3.68 | 1.0 | 0.6 | 0.109 | 0.032 | -3.27 | -3.28 |
| SW-2501M | 5/6/2026 8:42:31 AM | 66.6 | -7.47 | -7.72 | 0.4 | 0.3 | 0.012 | 0.011 | -7.67 | -7.92 |
| SW-2501M | 5/5/2026 8:23:44 AM | 64.9 | -8.43 | -8.40 | 1.0 | 0.3 | 0.099 | 0.008 | -8.14 | -8.34 |
| SW-2501M | 5/4/2026 8:14:55 AM | 67.6 | -8.11 | -8.11 | 3.7 | 3.6 | 1.368 | 1.273 | -7.95 | -7.99 |
| SW-2501M | 5/1/2026 8:25:32 AM | 66.4 | -8.26 | -8.28 | 9.1 | 9.1 | 8.403 | 8.471 | -8.39 | -8.44 |
| SW-2501MD | 5/29/2026 7:15:49 AM | 76.6 | -7.78 | -7.72 | 0.8 | 1.2 | 0.004 | 0.009 | -7.69 | -7.52 |
| SW-2501MD | 5/28/2026 6:14:16 AM | 74.9 | -8.35 | -8.36 | 13.0 | 13.0 | 1.010 | 1.009 | -8.27 | -8.27 |
| SW-2501MD | 5/27/2026 6:02:25 AM | 75.8 | -5.35 | -5.36 | 10.3 | 10.3 | 0.637 | 0.636 | -5.17 | -5.17 |
| SW-2501MD | 5/26/2026 6:05:27 AM | 72.5 | -6.63 | -6.68 | 12.7 | 12.6 | 0.957 | 0.952 | -6.74 | -6.54 |
| SW-2501MD | 5/22/2026 6:16:46 AM | 70.6 | -8.34 | -8.33 | 13.1 | 13.1 | 1.030 | 1.032 | -8.16 | -8.15 |
| SW-2501MD | 5/21/2026 6:32:26 AM | 76.8 | -7.71 | -7.71 | 9.1 | 9.2 | 0.495 | 0.508 | -7.45 | -7.43 |
| SW-2501MD | 5/20/2026 8:28:56 AM | 79.0 | -7.43 | -7.43 | 2.2 | 0.6 | 0.030 | 0.002 | -7.57 | -7.56 |
| SW-2501MD | 5/19/2026 8:58:19 AM | 80.0 | -6.08 | -6.08 | 0.7 | 0.7 | 0.003 | 0.003 | -6.15 | -6.15 |
| SW-2501MD | 5/18/2026 8:41:43 AM | 77.9 | -4.78 | -4.78 | 0.5 | 0.5 | 0.002 | 0.002 | -4.72 | -4.72 |
| SW-2501MD | 5/14/2026 8:16:25 AM | 78.1 | -6.50 | -6.49 | 1.2 | 1.2 | 0.008 | 0.008 | -6.72 | -6.72 |
| SW-2501MD | 5/13/2026 8:06:36 AM | 77.1 | -7.47 | -7.60 | 1.9 | 1.7 | 0.021 | 0.018 | -7.67 | -7.73 |
| SW-2501MD | 5/12/2026 9:12:49 AM | 77.4 | -6.74 | -6.76 | 2.2 | 4.9 | 0.030 | 0.141 | -6.94 | -6.88 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| SW-2501MD | 5/11/2026 8:21:50 AM | 78.2 | -4.92 | -4.74 | 1.9 | 1.5 | 0.021 | 0.013 | -4.67 | -4.55 |
| SW-2501MD | 5/8/2026 9:32:28 AM | 76.8 | -3.40 | -3.45 | 1.4 | 1.9 | 0.012 | 0.022 | -3.27 | -3.31 |
| SW-2501MD | 5/7/2026 8:53:13 AM | 77.2 | -3.65 | -3.57 | 3.0 | 0.0 | 0.054 | 0.000 | -3.29 | -3.30 |
| SW-2501MD | 5/6/2026 8:45:13 AM | 76.6 | -7.70 | -7.62 | 2.3 | 0.9 | 0.032 | 0.004 | -7.77 | -7.81 |
| SW-2501MD | 5/5/2026 8:27:56 AM | 76.5 | -8.39 | -8.40 | 4.2 | 1.1 | 0.107 | 0.007 | -8.18 | -8.13 |
| SW-2501MD | 5/4/2026 8:17:07 AM | 76.4 | -8.11 | -8.15 | 12.6 | 12.9 | 0.957 | 0.998 | -8.01 | -7.99 |
| SW-2501MD | 5/1/2026 8:27:27 AM | 76.8 | -8.11 | -8.11 | 36.8 | 36.8 | 8.244 | 8.247 | -8.16 | -8.18 |
| SW-2501S | 5/29/2026 7:18:48 AM | 66.2 | -7.61 | -7.58 | 12.5 | 11.8 | 0.186 | 0.167 | -7.66 | -7.57 |
| SW-2501S | 5/28/2026 6:18:35 AM | 65.4 | -8.11 | -8.11 | 2.9 | 3.0 | 0.855 | 0.884 | -8.29 | -8.29 |
| SW-2501S | 5/27/2026 6:06:12 AM | 68.4 | -5.11 | -5.11 | 2.6 | 2.6 | 0.662 | 0.662 | -5.32 | -5.32 |
| SW-2501S | 5/26/2026 6:14:28 AM | 68.3 | -6.63 | -6.71 | 3.1 | 3.1 | 0.940 | 0.957 | -6.59 | -6.74 |
| SW-2501S | 5/22/2026 6:22:20 AM | 69.5 | -7.98 | -7.96 | 2.1 | 2.1 | 0.464 | 0.449 | -8.08 | -8.10 |
| SW-2501S | 5/21/2026 6:38:09 AM | 71.2 | -7.63 | -7.64 | 1.9 | 1.7 | 0.361 | 0.293 | -7.51 | -7.49 |
| SW-2501S | 5/20/2026 8:33:18 AM | 72.5 | -7.09 | -7.09 | 1.2 | 1.3 | 0.144 | 0.162 | -7.41 | -7.45 |
| SW-2501S | 5/19/2026 9:04:28 AM | 72.4 | -5.74 | -5.74 | 1.2 | 1.1 | 0.139 | 0.129 | -6.03 | -6.06 |
| SW-2501S | 5/18/2026 8:47:27 AM | 70.4 | -4.72 | -4.72 | 1.0 | 1.0 | 0.106 | 0.106 | -4.47 | -4.49 |
| SW-2501S | 5/15/2026 9:27:58 AM | 75.8 | -7.77 | -7.66 | 0.8 | 0.7 | 0.059 | 0.048 | -8.08 | -7.75 |
| SW-2501S | 5/15/2026 9:22:25 AM | 71.8 | -6.42 | -6.42 | 0.7 | 1.2 | 0.052 | 0.138 | -6.40 | -6.74 |
| SW-2501S | 5/14/2026 8:22:49 AM | 71.3 | -6.09 | -6.10 | 1.2 | 1.2 | 0.154 | 0.153 | -6.44 | -6.47 |
| SW-2501S | 5/13/2026 8:12:06 AM | 72.6 | -7.40 | -7.45 | 1.4 | 1.4 | 0.189 | 0.189 | -7.74 | -7.74 |
| SW-2501S | 5/12/2026 9:17:43 AM | 74.8 | -6.51 | -6.52 | 1.0 | 1.3 | 0.107 | 0.166 | -6.76 | -6.76 |
| SW-2501S | 5/11/2026 8:26:36 AM | 73.3 | -5.07 | -5.01 | 0.6 | 1.0 | 0.038 | 0.103 | -5.39 | -5.23 |
| SW-2501S | 5/8/2026 9:39:11 AM | 73.0 | -3.39 | -3.31 | 0.5 | 0.8 | 0.027 | 0.069 | -3.22 | -3.17 |
| SW-2501S | 5/7/2026 9:00:17 AM | 70.2 | -3.45 | -3.47 | 0.7 | 0.7 | 0.056 | 0.053 | -3.05 | -3.08 |
| SW-2501S | 5/6/2026 8:51:41 AM | 66.3 | -7.30 | -7.43 | 1.3 | 1.3 | 0.173 | 0.179 | -7.64 | -7.75 |
| SW-2501S | 5/5/2026 8:36:07 AM | 66.3 | -8.07 | -8.07 | 1.2 | 1.4 | 0.136 | 0.189 | -8.10 | -8.08 |
| SW-2501S | 5/4/2026 8:22:18 AM | 67.3 | -7.84 | -7.83 | 2.6 | 2.6 | 0.686 | 0.694 | -8.06 | -8.01 |
| SW-2501S | 5/1/2026 8:30:42 AM | 68.5 | -8.05 | -8.11 | 8.9 | 8.9 | 8.112 | 8.154 | -8.39 | -8.39 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| SW-2502D | 5/29/2026 7:02:56 AM | 71.6 | -7.88 | -7.88 | 0.7 | 0.7 | 0.044 | 0.044 | -7.71 | -7.71 |
| SW-2502D | 5/28/2026 6:27:56 AM | 64.5 | -8.11 | -8.09 | 3.1 | 3.1 | 0.953 | 0.952 | -8.08 | -8.12 |
| SW-2502D | 5/27/2026 6:15:12 AM | 70.6 | -5.07 | -5.07 | 2.1 | 2.1 | 0.447 | 0.435 | -5.24 | -5.26 |
| SW-2502D | 5/26/2026 6:28:54 AM | 69.5 | -6.78 | -6.79 | 2.4 | 2.4 | 0.579 | 0.559 | -6.57 | -6.59 |
| SW-2502D | 5/22/2026 6:34:30 AM | 68.7 | -8.33 | -8.32 | 2.7 | 2.7 | 0.726 | 0.724 | -8.01 | -8.02 |
| SW-2502D | 5/21/2026 6:50:59 AM | 71.1 | -7.61 | -7.64 | 2.3 | 2.2 | 0.553 | 0.496 | -7.29 | -7.40 |
| SW-2502D | 5/20/2026 8:15:28 AM | 75.1 | -7.50 | -7.46 | 0.5 | 0.4 | 0.026 | 0.018 | -7.28 | -7.33 |
| SW-2502D | 5/19/2026 9:17:49 AM | 77.8 | -5.78 | -5.79 | 0.5 | 0.1 | 0.025 | 0.001 | -5.88 | -5.89 |
| SW-2502D | 5/18/2026 8:59:18 AM | 74.1 | -4.90 | -4.85 | 0.5 | 0.5 | 0.025 | 0.026 | -4.54 | -4.48 |
| SW-2502D | 5/15/2026 9:08:52 AM | 73.2 | -5.74 | -5.76 | 0.9 | 0.8 | 0.077 | 0.067 | -5.77 | -5.92 |
| SW-2502D | 5/14/2026 8:37:14 AM | 72.5 | -6.42 | -6.42 | 0.6 | 0.9 | 0.033 | 0.081 | -6.41 | -6.40 |
| SW-2502D | 5/13/2026 8:21:57 AM | 74.7 | -7.77 | -7.77 | 0.3 | 0.2 | 0.011 | 0.006 | -7.76 | -7.91 |
| SW-2502D | 5/12/2026 9:27:18 AM | 77.2 | -6.74 | -6.76 | 0.8 | 0.6 | 0.061 | 0.033 | -6.75 | -6.76 |
| SW-2502D | 5/11/2026 8:36:30 AM | 76.6 | -5.11 | -5.07 | 0.5 | 0.5 | 0.027 | 0.030 | -5.09 | -5.18 |
| SW-2502D | 5/8/2026 9:49:11 AM | 74.6 | -3.68 | -3.64 | 0.7 | 0.3 | 0.046 | 0.010 | -3.63 | -3.64 |
| SW-2502D | 5/7/2026 9:13:11 AM | 74.4 | -3.53 | -3.45 | 0.8 | 0.6 | 0.068 | 0.041 | -3.04 | -3.02 |
| SW-2502D | 5/6/2026 9:03:29 AM | 72.2 | -7.45 | -7.63 | 0.8 | 1.1 | 0.062 | 0.132 | -7.47 | -7.46 |
| SW-2502D | 5/5/2026 8:48:17 AM | 72.6 | -8.14 | -8.34 | 0.6 | 0.6 | 0.042 | 0.040 | -7.99 | -8.08 |
| SW-2502D | 5/4/2026 8:29:47 AM | 70.0 | -8.45 | -8.45 | 3.4 | 3.5 | 1.158 | 1.215 | -8.21 | -8.14 |
| SW-2502D | 5/1/2026 8:39:01 AM | 72.7 | -8.17 | -8.16 | 9.0 | 9.0 | 8.328 | 8.326 | -8.33 | -8.33 |
| SW-2502M | 5/29/2026 6:58:21 AM | 73.3 | -7.91 | -7.93 | 0.8 | 0.8 | 0.071 | 0.071 | -7.83 | -7.83 |
| SW-2502M | 5/28/2026 6:26:04 AM | 72.6 | -8.11 | -8.11 | 2.4 | 2.5 | 0.568 | 0.625 | -8.29 | -8.29 |
| SW-2502M | 5/27/2026 6:13:20 AM | 73.9 | -5.31 | -5.38 | 2.5 | 2.5 | 0.632 | 0.632 | -5.21 | -5.16 |
| SW-2502M | 5/26/2026 6:25:59 AM | 76.0 | -6.65 | -6.63 | 2.4 | 2.3 | 0.585 | 0.538 | -6.36 | -6.57 |
| SW-2502M | 5/22/2026 6:31:26 AM | 70.2 | -8.32 | -8.32 | 2.7 | 2.6 | 0.721 | 0.705 | -8.08 | -8.12 |
| SW-2502M | 5/21/2026 6:48:59 AM | 77.7 | -7.98 | -7.98 | 2.4 | 2.3 | 0.583 | 0.565 | -7.74 | -7.74 |
| SW-2502M | 5/20/2026 8:13:58 AM | 77.9 | -6.80 | -6.76 | 0.6 | 0.3 | 0.032 | 0.010 | -6.85 | -6.85 |
| SW-2502M | 5/19/2026 9:14:46 AM | 79.9 | -5.75 | -5.75 | 0.8 | 0.7 | 0.058 | 0.056 | -5.76 | -5.77 |
| SW-2502M | 5/18/2026 8:56:28 AM | 76.7 | -4.87 | -4.97 | 0.8 | 0.8 | 0.063 | 0.060 | -4.42 | -4.46 |
| SW-2502M | 5/15/2026 9:04:47 AM | 75.9 | -7.43 | -7.22 | 1.5 | 0.5 | 0.221 | 0.028 | -7.58 | -7.42 |
| SW-2502M | 5/14/2026 8:34:30 AM | 76.7 | -6.42 | -6.42 | 0.7 | 0.6 | 0.048 | 0.033 | -6.48 | -6.44 |
| SW-2502M | 5/13/2026 8:19:53 AM | 77.2 | -7.62 | -7.64 | 0.6 | 0.2 | 0.031 | 0.002 | -7.66 | -7.86 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| SW-2502M | 5/12/2026 9:25:33 AM | 78.8 | -6.59 | -6.64 | 0.6 | 0.6 | 0.037 | 0.031 | -6.74 | -6.74 |
| SW-2502M | 5/11/2026 8:34:43 AM | 77.3 | -5.07 | -5.07 | 1.0 | 0.6 | 0.097 | 0.038 | -5.05 | -5.07 |
| SW-2502M | 5/8/2026 9:47:15 AM | 74.8 | -3.45 | -3.50 | 0.8 | 0.6 | 0.072 | 0.035 | -3.37 | -3.46 |
| SW-2502M | 5/7/2026 9:10:36 AM | 72.4 | -3.55 | -3.52 | 0.9 | 0.8 | 0.080 | 0.068 | -3.07 | -3.05 |
| SW-2502M | 5/6/2026 9:01:23 AM | 71.2 | -7.42 | -7.44 | 1.0 | 0.7 | 0.096 | 0.052 | -7.56 | -7.53 |
| SW-2502M | 5/5/2026 8:46:24 AM | 71.8 | -8.29 | -8.29 | 1.0 | 0.9 | 0.101 | 0.089 | -8.00 | -8.07 |
| SW-2502M | 5/4/2026 8:28:19 AM | 71.9 | -8.40 | -8.41 | 3.4 | 3.4 | 1.202 | 1.174 | -7.98 | -7.98 |
| SW-2502M | 5/1/2026 8:36:49 AM | 72.5 | -8.23 | -8.23 | 9.0 | 9.0 | 8.407 | 8.403 | -8.39 | -8.39 |
| SW-2502MD | 5/29/2026 7:08:57 AM | 77.7 | -21.95 | -21.88 | 11.2 | 11.1 | 13.657 | 13.520 | -7.81 | -8.21 |
| SW-2502MD | 5/28/2026 6:29:56 AM | 75.5 | -7.77 | -7.77 | 2.2 | 2.2 | 0.514 | 0.510 | -7.93 | -7.91 |
| SW-2502MD | 5/27/2026 6:16:47 AM | 75.4 | -5.42 | -5.41 | 2.6 | 2.6 | 0.704 | 0.681 | -5.30 | -5.18 |
| SW-2502MD | 5/26/2026 6:31:21 AM | 77.6 | -6.67 | -6.67 | 2.3 | 2.3 | 0.560 | 0.558 | -6.48 | -6.47 |
| SW-2502MD | 5/22/2026 6:36:17 AM | 77.0 | -8.33 | -8.32 | 2.7 | 2.6 | 0.746 | 0.684 | -8.08 | -8.16 |
| SW-2502MD | 5/21/2026 6:52:38 AM | 77.1 | -7.86 | -7.83 | 2.7 | 2.7 | 0.777 | 0.763 | -7.63 | -7.60 |
| SW-2502MD | 5/20/2026 8:17:46 AM | 80.0 | -7.47 | -7.46 | 0.0 | 0.2 | 0.000 | 0.005 | -7.38 | -7.37 |
| SW-2502MD | 5/19/2026 9:20:34 AM | 82.3 | -5.73 | -5.73 | 0.2 | 0.2 | 0.004 | 0.004 | -5.76 | -5.76 |
| SW-2502MD | 5/18/2026 9:02:05 AM | 80.0 | -4.98 | -4.89 | 0.2 | 0.1 | 0.003 | 0.001 | -4.66 | -4.48 |
| SW-2502MD | 5/15/2026 9:12:10 AM | 78.8 | -7.43 | -7.32 | 0.7 | 0.3 | 0.053 | 0.010 | -7.41 | -7.34 |
| SW-2502MD | 5/14/2026 8:39:47 AM | 79.2 | -6.55 | -6.54 | 0.4 | 0.4 | 0.016 | 0.015 | -6.71 | -6.71 |
| SW-2502MD | 5/13/2026 8:24:00 AM | 79.0 | -7.77 | -7.77 | 0.4 | 0.6 | 0.013 | 0.040 | -7.74 | -7.78 |
| SW-2502MD | 5/12/2026 9:28:53 AM | 80.2 | -6.77 | -6.65 | 0.4 | 0.5 | 0.017 | 0.021 | -6.85 | -6.90 |
| SW-2502MD | 5/11/2026 8:38:07 AM | 79.0 | -5.11 | -5.08 | 0.7 | 0.2 | 0.044 | 0.005 | -5.15 | -5.15 |
| SW-2502MD | 5/8/2026 9:51:10 AM | 79.3 | -3.82 | -3.80 | 0.3 | 0.4 | 0.009 | 0.013 | -3.68 | -3.68 |
| SW-2502MD | 5/7/2026 9:14:39 AM | 77.6 | -3.60 | -3.55 | 0.5 | 0.1 | 0.024 | 0.002 | -3.07 | -3.06 |
| SW-2502MD | 5/6/2026 9:05:22 AM | 77.2 | -7.40 | -7.47 | 0.7 | 0.2 | 0.049 | 0.002 | -7.42 | -7.54 |
| SW-2502MD | 5/5/2026 8:50:15 AM | 77.6 | -8.31 | -8.46 | 0.6 | 0.0 | 0.040 | 0.000 | -8.07 | -8.19 |
| SW-2502MD | 5/4/2026 8:31:32 AM | 78.0 | -8.11 | -8.11 | 2.9 | 2.9 | 0.875 | 0.882 | -8.29 | -7.99 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| SW-2502MD | 5/1/2026 8:41:00 AM | 77.9 | -7.93 | -7.94 | 8.8 | 8.8 | 8.091 | 8.094 | -7.98 | -7.98 |
| SW-2502S | 5/29/2026 6:54:54 AM | 73.1 | -21.47 | -21.66 | 11.0 | 11.4 | 13.144 | 13.994 | -8.54 | -10.89 |
| SW-2502S | 5/28/2026 6:24:10 AM | 65.5 | -7.83 | -7.83 | 2.1 | 2.1 | 0.439 | 0.431 | -8.17 | -8.17 |
| SW-2502S | 5/27/2026 6:11:24 AM | 71.6 | -5.07 | -5.08 | 2.1 | 2.2 | 0.448 | 0.486 | -5.21 | -5.32 |
| SW-2502S | 5/26/2026 6:23:43 AM | 70.8 | -6.51 | -6.53 | 1.9 | 1.9 | 0.356 | 0.356 | -6.49 | -6.50 |
| SW-2502S | 5/22/2026 6:29:06 AM | 69.9 | -7.96 | -7.96 | 2.1 | 2.1 | 0.436 | 0.428 | -8.00 | -8.01 |
| SW-2502S | 5/21/2026 6:47:21 AM | 75.3 | -7.47 | -7.46 | 1.3 | 1.3 | 0.168 | 0.166 | -7.72 | -7.69 |
| SW-2502S | 5/20/2026 8:12:10 AM | 73.8 | -6.42 | -6.42 | 1.6 | 1.5 | 0.244 | 0.230 | -6.51 | -6.54 |
| SW-2502S | 5/19/2026 9:11:46 AM | 73.4 | -5.53 | -5.53 | 1.5 | 1.5 | 0.216 | 0.213 | -5.89 | -5.81 |
| SW-2502S | 5/18/2026 8:53:31 AM | 74.8 | -4.92 | -4.95 | 1.2 | 1.2 | 0.153 | 0.152 | -4.73 | -4.76 |
| SW-2502S | 5/15/2026 9:00:33 AM | 74.8 | -6.78 | -6.90 | 1.6 | 1.7 | 0.267 | 0.294 | -7.29 | -7.42 |
| SW-2502S | 5/14/2026 8:31:19 AM | 74.6 | -6.08 | -6.08 | 1.5 | 1.5 | 0.236 | 0.231 | -6.54 | -6.65 |
| SW-2502S | 5/13/2026 8:17:54 AM | 75.6 | -7.23 | -7.28 | 1.7 | 1.8 | 0.296 | 0.320 | -7.70 | -7.79 |
| SW-2502S | 5/12/2026 9:23:35 AM | 75.0 | -6.42 | -6.76 | 1.5 | 1.6 | 0.230 | 0.250 | -7.09 | -7.09 |
| SW-2502S | 5/11/2026 8:32:32 AM | 75.4 | -4.90 | -4.77 | 1.4 | 1.3 | 0.190 | 0.166 | -5.22 | -5.05 |
| SW-2502S | 5/8/2026 9:44:33 AM | 73.7 | -3.29 | -3.41 | 0.6 | 1.0 | 0.036 | 0.092 | -3.16 | -3.43 |
| SW-2502S | 5/7/2026 9:08:55 AM | 71.8 | -3.66 | -3.61 | 0.8 | 0.8 | 0.064 | 0.068 | -3.37 | -3.13 |
| SW-2502S | 5/6/2026 8:59:15 AM | 68.7 | -7.37 | -6.76 | 1.5 | 1.5 | 0.232 | 0.215 | -7.81 | -7.12 |
| SW-2502S | 5/5/2026 8:44:34 AM | 69.1 | -7.84 | -7.88 | 1.8 | 1.7 | 0.315 | 0.307 | -8.06 | -8.07 |
| SW-2502S | 5/4/2026 8:26:37 AM | 69.1 | -7.58 | -7.56 | 2.3 | 2.2 | 0.550 | 0.499 | -7.85 | -7.99 |
| SW-2502S | 5/1/2026 8:35:09 AM | 68.7 | -7.77 | -7.77 | 8.8 | 8.8 | 7.864 | 7.891 | -8.10 | -8.10 |
| SW-2503D | 5/12/2026 8:21:40 AM | 80.8 | -6.59 | -6.47 | 0.4 | 0.3 | 0.014 | 0.012 | -6.38 | -6.34 |
| SW-2503D | 5/4/2026 8:56:42 AM | 70.0 | -7.69 | -7.69 | 2.9 | 2.9 | 0.824 | 0.824 | -7.61 | -7.61 |
| SW-2503M | 5/12/2026 8:27:21 AM | 75.3 | -6.63 | -6.57 | 0.7 | 0.8 | 0.053 | 0.059 | -6.59 | -6.59 |
| SW-2503M | 5/4/2026 9:01:03 AM | 73.8 | -7.77 | -7.77 | 2.9 | 2.9 | 0.849 | 0.848 | -7.61 | -7.61 |
| SW-2503MD | 5/12/2026 8:24:48 AM | 76.9 | -6.49 | -6.44 | 0.7 | 0.3 | 0.047 | 0.011 | -6.53 | -6.63 |
| SW-2503MD | 5/4/2026 8:58:22 AM | 76.4 | -7.81 | -7.80 | 3.2 | 3.2 | 1.063 | 1.021 | -7.61 | -7.61 |
| SW-2503S | 5/12/2026 8:35:33 AM | 81.0 | -6.53 | -6.55 | 0.2 | 0.4 | 0.003 | 0.020 | -6.70 | -6.69 |
| SW-2503S | 5/4/2026 9:03:12 AM | 79.7 | -7.47 | -7.47 | 2.6 | 2.6 | 0.675 | 0.686 | -7.61 | -7.61 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| SW-2504D | 5/12/2026 8:47:37 AM | 82.3 | -6.69 | -6.44 | 0.6 | 0.6 | 0.007 | 0.007 | -6.73 | -6.69 |
| SW-2504D | 5/4/2026 9:08:28 AM | 79.3 | -7.47 | -7.47 | 6.1 | 6.0 | 0.756 | 0.723 | -7.44 | -7.61 |
| SW-2504M | 5/12/2026 8:49:55 AM | 79.9 | -6.76 | -6.76 | | | 0.086 | 0.054 | -6.69 | -6.69 |
| SW-2504M | 5/4/2026 9:18:12 AM | 80.4 | -7.32 | -7.30 | | | 1.177 | 1.171 | -7.21 | -7.22 |
| SW-2504MD | 5/20/2026 1:56:54 PM | 132.4 | -0.48 | -0.38 | 4.6 | 4.2 | 0.451 | 0.393 | -9.04 | -8.87 |
| SW-2504MD | 5/12/2026 8:55:07 AM | 78.2 | -6.59 | -6.46 | 1.2 | 1.4 | 0.028 | 0.037 | -6.54 | -6.69 |
| SW-2504MD | 5/4/2026 9:22:21 AM | 73.1 | -7.45 | -7.43 | 7.4 | 7.2 | 1.076 | 1.027 | -7.33 | -7.28 |
| SW-2504S | 5/12/2026 8:51:59 AM | 81.2 | -6.57 | -6.57 | 1.0 | 1.5 | 0.021 | 0.043 | -6.56 | -6.63 |
| SW-2504S | 5/4/2026 9:20:08 AM | 75.4 | -7.42 | -7.47 | 7.8 | 7.5 | 1.213 | 1.123 | -7.28 | -7.49 |
| SW-30 | 5/22/2026 6:43:04 AM | 52.8 | -0.17 | -0.16 | 12.1 | 12.0 | 0.168 | 0.166 | 0.00 | 0.00 |
| SW-30 | 5/21/2026 7:02:29 AM | 59.8 | -0.08 | -0.08 | 2.0 | 1.9 | 0.005 | 0.004 | 0.04 | 0.04 |
| SW-30 | 5/20/2026 8:03:41 AM | 74.0 | 0.00 | 0.00 | 0.0 | 0.0 | 0.000 | 0.000 | 0.01 | 0.00 |
| SW-30 | 5/19/2026 9:31:23 AM | 83.3 | -0.19 | -0.18 | 0.9 | 1.1 | 0.001 | 0.001 | 0.34 | 0.34 |
| SW-30 | 5/18/2026 9:09:16 AM | 79.9 | -4.70 | -4.71 | 1.6 | 1.1 | 0.003 | 0.002 | -4.29 | -4.33 |
| SW-30 | 5/15/2026 8:48:17 AM | 71.5 | -6.79 | -6.63 | 2.0 | 1.7 | 0.005 | 0.004 | -6.95 | -6.77 |
| SW-30 | 5/14/2026 8:48:35 AM | 75.8 | 0.00 | 0.00 | 4.8 | 4.7 | 0.028 | 0.027 | 0.36 | 0.34 |
| SW-30 | 5/13/2026 8:34:30 AM | 67.9 | -7.14 | -7.14 | 8.7 | 5.2 | 0.090 | 0.033 | -7.40 | -7.40 |
| SW-30 | 5/12/2026 9:39:11 AM | 82.1 | -6.53 | -6.42 | 6.1 | 4.1 | 0.046 | 0.021 | -6.53 | -6.39 |
| SW-30 | 5/11/2026 8:48:10 AM | 85.5 | -3.91 | -3.93 | 3.3 | 3.0 | 0.013 | 0.011 | -3.71 | -3.73 |
| SW-30 | 5/8/2026 10:07:17 AM | 83.3 | -3.63 | -3.57 | 6.7 | 3.5 | 0.055 | 0.015 | -3.67 | -3.68 |
| SW-30 | 5/7/2026 9:27:26 AM | 85.9 | -3.06 | -3.17 | 3.5 | 4.1 | 0.015 | 0.021 | -3.11 | -3.11 |
| SW-30 | 5/6/2026 9:14:39 AM | 78.5 | -7.18 | -7.11 | 6.2 | 10.6 | 0.047 | 0.136 | -7.30 | -7.14 |
| SW-30 | 5/5/2026 9:02:34 AM | 67.1 | -8.01 | -8.01 | 4.0 | 4.0 | 0.019 | 0.019 | -7.94 | -7.94 |
| SW-30 | 5/4/2026 8:36:47 AM | 69.9 | -8.11 | -8.11 | 26.5 | 26.6 | 0.848 | 0.860 | -8.17 | -7.95 |
| SW-30 | 5/1/2026 8:52:33 AM | 78.3 | -8.08 | -8.11 | 27.8 | 27.0 | 0.947 | 0.899 | -8.08 | -8.10 |
| SW-32 | 5/22/2026 6:47:07 AM | 53.2 | -0.14 | -0.14 | | | 0.140 | 0.142 | 0.00 | 0.00 |
| SW-32 | 5/21/2026 7:10:28 AM | 68.7 | -0.16 | -0.16 | | | 0.160 | 0.158 | 0.00 | 0.00 |
| SW-32 | 5/20/2026 7:45:31 AM | 73.0 | 0.00 | 0.00 | | | 0.004 | 0.004 | 0.00 | -0.01 |
| SW-32 | 5/19/2026 9:36:21 AM | 90.3 | -0.18 | -0.19 | | | 0.180 | 0.160 | 0.34 | 0.34 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| SW-32 | 5/18/2026 9:14:33 AM | 83.6 | -4.82 | -4.83 | | | 4.790 | 4.789 | -4.35 | -4.38 |
| SW-32 | 5/15/2026 8:38:38 AM | 71.0 | -6.66 | -6.86 | | | 7.032 | 7.202 | -6.83 | -6.94 |
| SW-32 | 5/14/2026 8:53:16 AM | 83.6 | -0.02 | -0.02 | | | 0.022 | 0.021 | 0.34 | 0.34 |
| SW-32 | 5/13/2026 8:29:37 AM | 64.4 | -7.71 | -7.87 | | | 7.719 | 7.932 | -7.68 | -7.95 |
| SW-32 | 5/12/2026 9:35:51 AM | 77.2 | -6.71 | -6.46 | | | 6.844 | 6.826 | -6.76 | -6.76 |
| SW-32 | 5/11/2026 8:43:32 AM | 78.3 | -4.26 | -4.28 | | | 4.190 | 4.176 | -4.06 | -4.08 |
| SW-32 | 5/8/2026 10:02:48 AM | 85.0 | -3.41 | -3.36 | | | 3.348 | 3.277 | -3.36 | -3.49 |
| SW-32 | 5/7/2026 9:20:49 AM | 81.6 | -3.06 | -3.17 | | | 2.996 | 3.113 | -3.01 | -3.11 |
| SW-32 | 5/6/2026 9:10:33 AM | 81.4 | -7.15 | -7.12 | | | 7.552 | 7.494 | -7.28 | -7.24 |
| SW-32 | 5/5/2026 8:56:30 AM | 60.6 | -8.01 | -7.98 | | | 8.112 | 8.045 | -7.80 | -7.77 |
| SW-32 | 5/4/2026 8:41:26 AM | 82.7 | -8.17 | -8.11 | | | 8.452 | 8.398 | -7.97 | -7.99 |
| SW-32 | 5/1/2026 8:45:18 AM | 74.4 | -7.88 | -7.87 | | | 8.147 | 8.149 | -7.99 | -7.99 |
| SW-64 | 5/22/2026 6:40:52 AM | 55.0 | -0.13 | -0.12 | 10.4 | 10.1 | 0.125 | 0.119 | 0.02 | 0.00 |
| SW-64 | 5/21/2026 6:58:46 AM | 62.3 | -0.20 | -0.20 | 4.5 | 4.2 | 0.023 | 0.021 | 0.00 | 0.00 |
| SW-64 | 5/20/2026 8:05:22 AM | 75.2 | 0.00 | 0.00 | 1.6 | 1.4 | 0.003 | 0.002 | -0.03 | 0.01 |
| SW-64 | 5/19/2026 9:28:23 AM | 88.3 | -0.20 | -0.20 | 2.3 | 2.3 | 0.007 | 0.006 | 0.34 | 0.34 |
| SW-64 | 5/18/2026 9:06:40 AM | 78.7 | -4.78 | -4.77 | 5.4 | 5.5 | 0.035 | 0.037 | -4.32 | -4.30 |
| SW-64 | 5/15/2026 8:53:43 AM | 67.8 | -6.78 | -6.98 | 2.1 | 2.3 | 0.005 | 0.007 | -6.99 | -7.07 |
| SW-64 | 5/15/2026 8:43:20 AM | | -6.67 | | 8.1 | | 0.079 | | -6.84 | |
| SW-64 | 5/14/2026 8:44:43 AM | 77.9 | -0.09 | -0.09 | 7.1 | 7.1 | 0.060 | 0.060 | 0.35 | 0.35 |
| SW-64 | 5/13/2026 8:36:34 AM | 65.0 | -7.65 | -7.14 | 5.6 | 1.6 | 0.038 | 0.003 | -7.68 | -7.32 |
| SW-64 | 5/12/2026 9:41:18 AM | 86.5 | -6.42 | -6.42 | 2.8 | 3.1 | 0.010 | 0.012 | -6.51 | -6.42 |
| SW-64 | 5/11/2026 8:51:06 AM | 89.5 | -3.88 | -3.87 | 4.4 | 6.6 | 0.024 | 0.053 | -3.71 | -3.71 |
| SW-64 | 5/8/2026 10:09:00 AM | 84.2 | -3.31 | -3.40 | 7.0 | 6.1 | 0.060 | 0.045 | -3.35 | -3.35 |
| SW-64 | 5/7/2026 9:29:18 AM | 87.8 | -3.16 | -3.08 | 0.6 | 2.1 | 0.000 | 0.005 | -3.09 | -3.11 |
| SW-64 | 5/6/2026 9:16:27 AM | 79.1 | -6.42 | -6.42 | 2.3 | 0.6 | 0.007 | 0.000 | -6.57 | -6.54 |
| SW-64 | 5/5/2026 9:04:48 AM | 64.0 | -8.12 | -8.17 | 3.9 | 6.5 | 0.018 | 0.050 | -8.14 | -8.13 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| SW-64 | 5/4/2026 8:34:50 AM | 66.8 | -8.00 | -8.00 | 27.5 | 27.5 | 0.910 | 0.910 | -7.94 | -7.94 |
| SW-64 | 5/1/2026 8:47:28 AM | 76.7 | -8.11 | -8.11 | 81.5 | 81.7 | 8.253 | 8.308 | -8.39 | -8.10 |
| SW-65 | 5/11/2026 9:04:20 AM | 87.2 | -10.99 | -10.91 | 0.9 | 0.8 | 0.005 | 0.003 | -12.38 | |
| SW-66 | 5/15/2026 9:29:15 AM | 86.2 | -7.79 | -7.80 | 0.0 | 0.0 | 7.831 | 7.879 | | |
| SW-66 | 5/15/2026 9:27:52 AM | 86.3 | -8.19 | -8.11 | 0.0 | 0.0 | 8.302 | 7.972 | | |
| SW-68 | 5/22/2026 6:45:28 AM | 52.3 | -0.17 | -0.17 | 12.5 | 12.3 | 0.179 | 0.174 | 0.00 | 0.00 |
| SW-68 | 5/21/2026 7:08:10 AM | 63.5 | -0.13 | -0.13 | 2.5 | 1.6 | 0.007 | 0.003 | 0.00 | 0.00 |
| SW-68 | 5/20/2026 7:47:12 AM | 72.4 | 0.00 | 0.00 | 2.4 | 2.8 | 0.007 | 0.009 | 0.01 | 0.03 |
| SW-68 | 5/19/2026 9:34:10 AM | 88.4 | -0.19 | -0.19 | 1.0 | 0.0 | 0.001 | 0.000 | 0.34 | 0.34 |
| SW-68 | 5/18/2026 9:11:53 AM | 78.8 | -4.71 | -4.70 | 5.3 | 1.6 | 0.035 | 0.003 | -4.28 | -4.29 |
| SW-68 | 5/15/2026 8:34:05 AM | 72.3 | -6.91 | -6.95 | 1.6 | 3.4 | 0.003 | 0.014 | -7.05 | -7.10 |
| SW-68 | 5/14/2026 8:50:57 AM | 80.7 | -0.02 | -0.02 | 3.3 | 3.3 | 0.013 | 0.013 | 0.36 | 0.34 |
| SW-68 | 5/13/2026 8:31:50 AM | 68.7 | -7.77 | -7.77 | 0.0 | 1.9 | 0.000 | 0.004 | -7.74 | -7.78 |
| SW-68 | 5/12/2026 9:37:18 AM | 81.4 | -6.46 | -6.59 | 5.6 | 10.7 | 0.038 | 0.141 | -6.51 | -6.46 |
| SW-68 | 5/11/2026 8:45:53 AM | 84.2 | -4.19 | -4.21 | 6.4 | 2.9 | 0.049 | 0.010 | -4.03 | -4.01 |
| SW-68 | 5/8/2026 10:04:26 AM | 82.7 | -3.32 | -3.33 | 8.3 | 7.9 | 0.084 | 0.076 | -3.25 | -3.35 |
| SW-68 | 5/7/2026 9:24:55 AM | 86.5 | -3.27 | -3.30 | 3.8 | 3.1 | 0.018 | 0.012 | -3.15 | -3.11 |
| SW-68 | 5/6/2026 9:12:20 AM | 79.1 | -7.28 | -7.43 | 6.8 | 7.2 | 0.056 | 0.064 | -7.42 | -7.41 |
| SW-68 | 5/5/2026 8:59:48 AM | 68.1 | -8.07 | -8.07 | 5.4 | 2.4 | 0.036 | 0.007 | -8.08 | -8.08 |
| SW-68 | 5/4/2026 8:39:10 AM | 70.5 | -8.11 | -8.11 | 29.2 | 29.1 | 1.033 | 1.025 | -7.89 | -7.91 |
| SW-68 | 5/1/2026 8:43:53 AM | 75.7 | -8.02 | -8.03 | 81.2 | 81.2 | 8.191 | 8.199 | -8.16 | -8.15 |
| SW-7 | 5/1/2026 7:54:58 AM | 66.9 | -0.20 | -0.20 | 13.2 | 13.0 | 0.204 | 0.198 | -8.46 | -8.46 |
| SW-70 | 5/4/2026 9:33:46 AM | 72.6 | -7.74 | -7.74 | 62.4 | 62.1 | 0.902 | 0.895 | -7.58 | -7.58 |
| SW-71 | 5/6/2026 8:31:08 AM | 73.0 | -5.74 | -5.70 | 2.1 | 1.9 | 0.435 | 0.356 | -10.24 | |
| SW-71 | 5/6/2026 8:23:03 AM | 73.2 | -5.74 | -5.67 | 1.9 | 2.0 | 0.386 | 0.397 | -9.33 | |
| SW-72 | 5/6/2026 9:25:28 AM | 79.8 | -1.36 | -1.28 | 0.0 | 0.0 | 0.030 | 0.026 | -3.64 | |
| SW-80 | 5/12/2026 1:23:15 PM | 82.8 | -6.04 | -6.04 | 1.4 | 1.5 | 0.040 | 0.046 | -8.61 | -8.54 |
| SW-9 | 5/4/2026 9:35:40 AM | 81.4 | -7.72 | -7.68 | 66.2 | 65.8 | 1.033 | 1.021 | -7.59 | -7.59 |
| TC-1961C | 5/4/2026 11:11:27 AM | 93.9 | -0.50 | -0.35 | 4.9 | 4.6 | 0.053 | 0.047 | -14.09 | -14.28 |
| TC-1961E | 5/4/2026 10:42:18 AM | 114.6 | -1.72 | -1.69 | 8.9 | 10.5 | 0.182 | 0.254 | -14.36 | -14.09 |
| TC-2174 | 5/26/2026 9:02:15 AM | 183.2 | -1.18 | -1.20 | | | 3.904 | 4.034 | -1.61 | -1.68 |
| TC-2174 | 5/18/2026 9:25:30 AM | 182.9 | -0.04 | -0.07 | | | 3.111 | 3.007 | -0.46 | -0.55 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| TC-2174 | 5/18/2026 9:25:00 AM | | | | | | | | | |
| TC-2174 | 5/18/2026 9:24:46 AM | 182.9 | 0.91 | 0.00 | | | 2.560 | 3.348 | -1.42 | -0.49 |
| TC-2174 | 5/12/2026 9:30:00 AM | | | | | | | | | |
| TC-2174 | 5/12/2026 9:24:37 AM | 183.1 | -1.35 | -1.33 | | | 4.089 | 4.047 | -4.98 | -4.61 |
| TC-2174 | 5/5/2026 8:40:00 AM | | | | | | | | | |
| TC-2174 | 5/5/2026 8:40:00 AM | | | | | | | | | |
| TC-2174 | 5/5/2026 8:34:39 AM | 182.7 | -2.63 | -2.45 | | | 6.162 | 6.051 | -5.01 | -5.36 |
| VL-02 | 5/28/2026 3:26:30 PM | 91.0 | -14.89 | -14.86 | 14.3 | 14.9 | 0.251 | 0.274 | -14.61 | -15.20 |
| WTD-01 | 5/21/2026 5:51:51 AM | 140.0 | -3.65 | -3.65 | | | 3.622 | 3.618 | -7.40 | -7.36 |
| WTD-01 | 5/21/2026 5:51:17 AM | 139.9 | -3.71 | -3.70 | | | 3.709 | 3.695 | -7.24 | -7.27 |
| WTD-01 | 5/1/2026 7:48:21 AM | 141.4 | -4.94 | -4.93 | | | 4.892 | 4.881 | -8.39 | -8.34 |
| WTD-01 | 5/1/2026 7:47:42 AM | 141.3 | -4.93 | -4.93 | | | 4.887 | 4.884 | -8.41 | -8.41 |
| WTD-02 | 5/21/2026 5:58:44 AM | 155.4 | -3.90 | -3.89 | | | 3.865 | 3.866 | -3.76 | -3.79 |
| WTD-02 | 5/21/2026 5:58:19 AM | 155.3 | -3.90 | -3.91 | | | 3.874 | 3.872 | -3.74 | -3.74 |
| WTD-02 | 5/13/2026 1:51:34 PM | 154.8 | -3.63 | -3.62 | | | 3.635 | 3.620 | 0.00 | 0.00 |
| WTD-02 | 5/13/2026 1:50:30 PM | 154.8 | -3.61 | -3.61 | | | 3.587 | 3.588 | 0.00 | 0.00 |
| WTD-02 | 5/6/2026 1:50:52 PM | 156.2 | -1.76 | -1.79 | | | 1.739 | 1.758 | 0.00 | 0.00 |
| WTD-02 | 5/6/2026 1:50:00 PM | | | | | | | | | |
| WTD-02 | 5/6/2026 1:50:00 PM | | | | | | | | | |
| WTD-02 | 5/6/2026 1:49:41 PM | 82.9 | -1.74 | -1.69 | | | 1.726 | 1.647 | -0.01 | 0.00 |
| WTD-03 | 5/21/2026 6:07:17 AM | 112.5 | -4.20 | -4.20 | | | 4.169 | 4.164 | -4.14 | -4.11 |
| WTD-03 | 5/21/2026 6:06:19 AM | 112.5 | -4.20 | -4.20 | | | 4.173 | 4.177 | -4.27 | -4.26 |
| WTD-03 | 5/1/2026 8:09:37 AM | 119.0 | -5.11 | -5.11 | | | 5.367 | 5.385 | -5.41 | -5.36 |
| WTD-03 | 5/1/2026 8:08:56 AM | 118.8 | -5.21 | -5.11 | | | 5.430 | 5.385 | -5.36 | -5.36 |
| WTD-04 | 5/21/2026 6:19:17 AM | 60.1 | -3.87 | -3.87 | | | 3.842 | 3.855 | -5.38 | -5.43 |
| WTD-04 | 5/21/2026 6:16:55 AM | 60.1 | -3.87 | -3.87 | | | 3.843 | 3.842 | -5.43 | -5.38 |
| WTD-04 | 5/1/2026 8:15:02 AM | 64.4 | -4.77 | -4.77 | | | 4.990 | 4.996 | -6.39 | -6.37 |
| WTD-04 | 5/1/2026 8:14:32 AM | 64.0 | -4.97 | -4.98 | | | 4.984 | 4.978 | -6.40 | -6.39 |
| WTD-05 | 5/21/2026 6:13:19 AM | 67.4 | -3.87 | -3.87 | | | 3.840 | 3.840 | -5.33 | -5.34 |
| WTD-05 | 5/21/2026 6:12:45 AM | 67.4 | -3.87 | -3.87 | | | 3.845 | 3.843 | -5.32 | -5.33 |
| WTD-05 | 5/1/2026 8:12:57 AM | 73.8 | -4.79 | -4.77 | | | 4.946 | 4.995 | -6.23 | -6.23 |
| WTD-05 | 5/1/2026 8:12:16 AM | 72.8 | -4.79 | -4.78 | | | 4.928 | 4.951 | -6.28 | -6.22 |
| WTD-06 | 5/21/2026 6:21:19 AM | 110.8 | -3.94 | -3.94 | | | 3.897 | 3.899 | -5.47 | -5.51 |
| WTD-06 | 5/21/2026 6:20:59 AM | 110.8 | -3.92 | -3.93 | | | 3.892 | 3.897 | -5.47 | -5.51 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Init Flow [scfm] | Adj Flow [scfm] | Init Diff Press ["H2O] | Adj Diff Press ["H2O] | Sys Pressure ["H2O] | Adj Avail Press ["H2O] |
|---|---|---|---|---|---|---|---|---|---|---|
| WTD-06 | 5/1/2026 8:20:07 AM | 117.1 | -4.96 | -4.90 | | | 5.164 | 5.090 | -6.79 | -6.90 |
| WTD-06 | 5/1/2026 8:17:56 AM | 116.7 | -5.00 | -4.86 | | | 5.105 | 5.023 | -6.85 | -6.71 |
| WTD-07 | 5/21/2026 6:25:15 AM | 67.4 | -5.62 | -5.62 | | | 5.578 | 5.593 | -5.60 | -5.57 |
| WTD-07 | 5/21/2026 6:24:46 AM | 67.5 | -5.60 | -5.61 | | | 5.498 | 5.525 | -5.41 | -5.41 |
| WTD-07 | 5/1/2026 8:22:32 AM | 65.8 | -6.76 | -6.76 | | | 6.974 | 6.986 | -6.74 | -6.73 |
| WTD-07 | 5/1/2026 8:21:58 AM | 65.7 | -6.76 | -6.76 | | | 6.929 | 6.928 | -6.72 | -6.73 |
| WTD-10 | 5/21/2026 7:17:44 AM | 110.2 | -3.99 | -3.99 | | | 3.974 | 3.948 | -6.30 | -6.23 |
| WTD-10 | 5/21/2026 7:17:13 AM | 110.2 | -4.00 | -4.01 | | | 3.968 | 3.950 | -6.31 | -6.23 |
| WTD-10 | 5/4/2026 8:01:28 AM | 106.3 | -4.77 | -4.77 | | | 5.005 | 5.018 | -7.28 | -7.26 |
| WTD-10 | 5/4/2026 8:00:56 AM | 106.3 | -4.77 | -4.77 | | | 5.032 | 5.018 | -7.24 | -7.11 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| A-01 | 5/15/2026 8:51:04 AM | 28.78 | 1198 | 34.4312780 | -118.6438358 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| A-02 | 5/11/2026 7:44:04 AM | 28.75 | 1184 | 34.4315883 | -118.6433073 | No Flow Measurement,No Adjustment Made |
| A-03 | 5/11/2026 7:56:41 AM | 28.74 | 1171 | 34.4318593 | -118.6428253 | No Flow Measurement |
| A-04 | 5/11/2026 8:06:12 AM | 28.74 | 1184 | 34.4321948 | -118.6422235 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,Audible Flow,No Flow Measurement |
| A-05 | 5/11/2026 8:01:26 AM | 28.74 | 1165 | 34.4324613 | -118.6416893 | No Flow Measurement |
| B-01 | 5/11/2026 10:37:28 AM | 28.73 | | | | |
| B-02R | 5/11/2026 10:34:40 AM | 28.72 | 1191 | 34.4333675 | -118.6396157 | |
| B-03R | 5/11/2026 10:04:48 AM | 28.73 | 1211 | 34.4338248 | -118.6388093 | |
| B-05 | 5/11/2026 10:25:34 AM | 28.73 | 1253 | 34.4336600 | -118.6383268 | |
| B-06 | 5/11/2026 10:19:19 AM | 28.73 | 1217 | 34.4340717 | -118.6378192 | |
| B-07R | 5/11/2026 9:31:57 AM | 28.73 | 1188 | 34.4342770 | -118.6374250 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| B-08 | 5/11/2026 10:15:29 AM | 28.73 | 1181 | 34.4338193 | -118.6373255 | No Flow Measurement |
| B-09 | 5/11/2026 9:37:05 AM | 28.74 | 1191 | 34.4342012 | -118.6370725 | |
| B-10 | 5/11/2026 9:24:54 AM | 28.73 | 1224 | 34.4339978 | -118.6365650 | No Flow Measurement |
| B-11 | 5/29/2026 3:03:30 PM | 28.81 | 1150 | 34.4348343 | -118.6369015 | |
| B-12 | 5/11/2026 10:00:30 AM | 28.73 | 1211 | 34.4340375 | -118.6385235 | |
| B-13 | 5/11/2026 9:49:42 AM | 28.73 | 1211 | 34.4344310 | -118.6379303 | |
| B-14 | 5/29/2026 3:07:12 PM | 28.82 | 1133 | 34.4349390 | -118.6370690 | |
| C-03 | 5/11/2026 7:49:46 AM | 28.77 | 1198 | 34.4313543 | -118.6435513 | No Flow Measurement,No Adjustment Made |
| C-07 | 5/1/2026 3:11:09 PM | 28.64 | 1190 | 34.4326408 | -118.6414288 | Valve Adjustment:Reconnected this Date,Valve 100% Open |
| C-08 | 5/8/2026 1:03:42 PM | 28.74 | 1198 | 34.4336587 | -118.6408628 | Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum |
| C-10 | 5/11/2026 9:07:51 AM | 28.73 | 1145 | 34.4347607 | -118.6411188 | No Flow Measurement,No Adjustment Made |
| C-11 | 5/11/2026 8:38:28 AM | 28.72 | 1198 | 34.4352575 | -118.6413622 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| C-12 | 5/29/2026 12:20:26 PM | 28.74 | 1225 | 34.4359885 | -118.6408897 | Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum |
| C-12 | 5/11/2026 1:57:43 PM | 28.67 | 1235 | 34.4359890 | -118.6408977 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| C-15 | 5/11/2026 2:07:31 PM | 28.67 | 1223 | 34.4362840 | -118.6410517 | Valve Adjustment:Valve 100% Open |
| C-17B | 5/12/2026 10:45:10 AM | 28.7 | 1226 | 34.4373525 | -118.6419448 | |
| C-18 | 5/12/2026 1:08:06 PM | 28.72 | 1230 | 34.4379865 | -118.6426292 | |
| C-19 | 5/12/2026 12:49:10 PM | 28.72 | 1226 | 34.4375570 | -118.6421588 | |
| C-20 | 5/12/2026 12:57:51 PM | 28.72 | 1234 | 34.4377843 | -118.6424115 | |
| C-23 | 5/12/2026 11:00:46 AM | 28.71 | 1213 | 34.4370875 | -118.6416698 | Well Repairs:Sample Port |
| C-24 | 5/15/2026 9:17:41 AM | 28.74 | 1201 | 34.4375270 | -118.6421700 | |
| C-25 | 5/11/2026 2:14:04 PM | 28.67 | 1235 | 34.4371358 | -118.6416700 | Valve Adjustment:Valve 100% Open |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| C-26 | 5/29/2026 12:46:54 PM | 28.74 | 1227 | 34.4366562 | -118.6412765 | Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum |
| C-26 | 5/15/2026 9:07:37 AM | 28.75 | 1230 | 34.4366148 | -118.6412708 | |
| C-27 | 5/11/2026 2:04:38 PM | 28.67 | 1238 | 34.4362008 | -118.6409862 | Valve Adjustment:Increased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| C-28 | 5/29/2026 12:16:57 PM | 28.72 | 1239 | 34.4354523 | -118.6413823 | Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum |
| C-28 | 5/11/2026 8:35:54 AM | 28.71 | 1247 | 34.4354155 | -118.6413187 | No Adjustment Made |
| C-29 | 5/11/2026 8:54:46 AM | 28.73 | 1270 | 34.4347552 | -118.6411677 | Audible Flow,No Flow Measurement |
| C-30 | 5/11/2026 8:49:08 AM | 28.7 | 1224 | 34.4342760 | -118.6413048 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-02 | 5/11/2026 8:21:58 AM | 28.64 | 1240 | 34.4335742 | -118.6413765 | No Adjustment Made |
| CV-03 | 5/11/2026 8:18:37 AM | 28.7 | 1234 | 34.4333008 | -118.6414685 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-04 | 5/11/2026 8:14:52 AM | 28.7 | 1207 | 34.4331483 | -118.6416422 | Increased Flow/Vacuum |
| CV-05 | 5/8/2026 12:41:33 PM | 28.74 | 1203 | 34.4328332 | -118.6422098 | Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Valve 100% Open |
| CV-06 | 5/12/2026 8:03:49 AM | 28.69 | 1247 | 34.4326172 | -118.6428073 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-108-52 | 5/19/2026 1:02:47 PM | 28.67 | 1280 | 34.4334190 | -118.6506818 | Valve Adjustment:Barely Open,Surging Liquid in Header |
| CV-108-52 | 5/18/2026 11:07:16 AM | | | | | |
| CV-108-52 | 5/6/2026 8:30:00 AM | | | | | Air Tech Lab |
| CV-108-52 | 5/1/2026 10:29:07 AM | 28.65 | 1285 | 34.4334083 | -118.6506870 | Valve Adjustment:Barely Open |
| CV-113 | 5/26/2026 2:01:29 PM | 28.39 | 1330 | 34.4369985 | -118.6467360 | Valve Adjustment:Barely Open |
| CV-113 | 5/15/2026 9:28:02 AM | 28.59 | 1344 | 34.4369835 | -118.6467223 | |
| CV-113 | 5/4/2026 7:50:00 AM | | | | | Air Tech Lab; [User entered 2.4%] |
| CV-114 | 5/26/2026 8:58:28 AM | 28.47 | 1362 | 34.4367389 | -118.6476076 | Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-114 | 5/18/2026 9:20:17 AM | 28.52 | 1365 | 34.4367361 | -118.6476114 | Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down |
| CV-114 | 5/18/2026 9:20:00 AM | | | | | AtmAA |
| CV-114 | 5/18/2026 9:17:57 AM | 28.51 | 1365 | 34.4367354 | -118.6476131 | Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum,Valve 100% Open,Reduce Sys. Vac. - Flare Down |
| CV-114 | 5/12/2026 9:25:00 AM | | | | | AtmAA |
| CV-114 | 5/12/2026 9:22:16 AM | 28.55 | 1386 | 34.4367167 | -118.6476261 | Valve Adjustment:High Temp |
| CV-114 | 5/5/2026 8:35:00 AM | | | | | AtmAA |
| CV-114 | 5/5/2026 8:35:00 AM | | | | | AtmAA; [User entered 16.18%] |
| CV-114 | 5/5/2026 8:32:18 AM | 28.53 | 1336 | 34.4367155 | -118.6476129 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-114 | 5/4/2026 8:05:00 AM | | | | | Air Tech Lab; [User entered 0.28%] |
| CV-1424 | 5/1/2026 11:22:59 AM | 28.45 | 1358 | 34.4350948 | -118.6450823 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-1532A | 5/28/2026 8:54:46 AM | 28.6 | 1277 | 34.4338675 | -118.6508340 | Valve Adjustment:Barely Open;Well Comment:System surging |
| CV-1532A | 5/13/2026 1:09:52 PM | 28.61 | 1257 | 34.4339078 | -118.6507662 | |
| CV-1532A | 5/13/2026 1:07:32 PM | 28.68 | 1289 | 34.4339437 | -118.6508210 | |
| CV-1532A | 5/11/2026 8:15:00 AM | | | | | Air Tech Lab |
| CV-1532A | 5/11/2026 8:15:00 AM | | | | | Air Tech Lab; [User entered 6.1%] |
| CV-1534A-PLR | 5/28/2026 1:23:27 PM | 28.62 | 1290 | 34.4336179 | -118.6508080 | Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Surging Liquid in Header |
| CV-1534A-PLR | 5/28/2026 1:20:34 PM | 28.62 | 1283 | 34.4336241 | -118.6507961 | Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Surging Liquid in Header |
| CV-1534A-PLR | 5/20/2026 9:03:59 AM | 28.63 | 1283 | 34.4336324 | -118.6508042 | Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Surging Liquid in Well (Watered In) |
| CV-1534A-PLR | 5/13/2026 9:42:40 AM | 28.77 | 1291 | 34.4336253 | -118.6507774 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In) |
| CV-1534A-PLR | 5/6/2026 10:03:56 AM | 28.73 | 1286 | 34.4336278 | -118.6507907 | Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Well (Watered In) |
| CV-1534A-PLR | 5/6/2026 9:55:00 AM | | | | | AtmAA |
| CV-1534A-PLR | 5/6/2026 9:55:00 AM | | | | | AtmAA; [User entered 12.34%] |
| CV-1535 | 5/19/2026 12:55:31 PM | 28.63 | 1298 | 34.4333412 | -118.6503412 | Valve Adjustment:Barely Open |
| CV-1535 | 5/11/2026 8:25:00 AM | | | | | Air Tech Lab |
| CV-1535 | 5/11/2026 8:25:00 AM | | | | | Air Tech Lab; [User entered 0.98%] |
| CV-1535 | 5/1/2026 10:31:55 AM | 28.59 | 1318 | 34.4333060 | -118.6503550 | Valve Adjustment:Audible Flow;Well Condition:Good |
| CV-1601D | 5/22/2026 10:03:49 AM | 28.43 | 1322 | 34.4311242 | -118.6486432 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-1601D | 5/4/2026 10:02:19 AM | 28.54 | 1296 | 34.4311578 | -118.6487380 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-1601S | 5/22/2026 10:00:47 AM | 28.58 | 1316 | 34.4311025 | -118.6486852 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-1601S | 5/4/2026 9:59:23 AM | 28.53 | 1329 | 34.4311523 | -118.6486630 | |
| CV-1604 | 5/4/2026 11:02:38 AM | 28.63 | 1279 | 34.4321760 | -118.6450297 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-1701D | 5/8/2026 1:23:50 PM | 28.63 | 1283 | 34.4335962 | -118.6433443 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAC |
| CV-1701D | 5/8/2026 1:22:18 PM | 28.63 | 1280 | 34.4335972 | -118.6433448 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum;Well Condition:Fair;Well Repairs:Flex Hose |
| CV-1701D | 5/7/2026 11:12:23 AM | 28.69 | 1276 | 34.4335535 | -118.6433258 | Reduced System Vacuum |
| CV-1701S | 5/7/2026 11:16:55 AM | 28.68 | 1214 | 34.4335183 | -118.6433695 | Reduced System Vacuum,High Temp,NSPS/EG CAI |
| CV-1701S | 5/7/2026 11:15:22 AM | 28.68 | 1260 | 34.4335477 | -118.6433292 | NSPS/EG CAI,High Temp,Reduced System Vacuum |
| CV-1901 | 5/19/2026 10:20:41 AM | 28.63 | 1338 | 34.4357227 | -118.6508190 | Valve Adjustment:NSPS/EG CAC |
| CV-1901 | 5/19/2026 10:18:56 AM | 28.63 | 1336 | 34.4357087 | -118.6508223 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-1901 | 5/12/2026 10:20:03 AM | 28.61 | 1325 | 34.4357342 | -118.6508607 | NSPS/EG CAC,No Adjustment Made |
| CV-1901 | 5/12/2026 10:17:30 AM | 28.61 | 1335 | 34.4357073 | -118.6506798 | NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-1902A | 5/28/2026 8:49:43 AM | 28.58 | 1315 | 34.4346018 | -118.6502966 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-1902A | 5/20/2026 8:10:11 AM | 28.59 | 1329 | 34.4346010 | -118.6503184 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-1902A | 5/14/2026 1:48:17 PM | 28.63 | 1311 | 34.4346105 | -118.6503170 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum |
| CV-1902A | 5/11/2026 1:48:31 PM | 28.59 | 1312 | 34.4346165 | -118.6503003 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-1902A | 5/11/2026 7:55:00 AM | | | | | Air Tech Lab |
| CV-1902A | 5/11/2026 7:55:00 AM | | | | | Air Tech Lab; [User entered 19%] |
| CV-1902A | 5/6/2026 9:06:28 AM | 28.67 | 1330 | 34.4345924 | -118.6503030 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-1902A | 5/6/2026 9:05:00 AM | | | | | AtmAA |
| CV-1902A | 5/6/2026 9:05:00 AM | | | | | AtmAA; [User entered 16.105%] |
| CV-1905 | 5/6/2026 12:45:38 PM | 28.63 | 1393 | 34.4334975 | -118.6460023 | Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum |
| CV-1905 | 5/6/2026 10:44:14 AM | 28.56 | 1348 | 34.4334800 | -118.6459913 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-2001 | 5/20/2026 9:55:23 AM | 28.63 | 1259 | 34.4322752 | -118.6505602 | Valve Adjustment:Barely Open |
| CV-2001 | 5/12/2026 8:45:06 AM | 28.62 | 1289 | 34.4323085 | -118.6505502 | No Adjustment Made |
| CV-2001 | 5/6/2026 7:50:00 AM | | | | | Air Tech Lab |
| CV-2001 | 5/6/2026 7:50:00 AM | | | | | Air Tech Lab; [User entered 8.2%] |
| CV-2001 | 5/1/2026 10:12:38 AM | 28.64 | 1273 | 34.4322787 | -118.6505635 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-2002 | 5/28/2026 10:15:53 AM | 28.64 | 1276 | 34.4327983 | -118.6511690 | Valve Adjustment:NSPS/EG CAC,High Temp |
| CV-2002 | 5/28/2026 10:12:21 AM | 28.64 | 1273 | 34.4328116 | -118.6511672 | Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum,Plugged/Pinched Suspected;Well Comment:Pinched in the vacuum line |
| CV-2002 | 5/20/2026 9:42:31 AM | 28.67 | 1275 | 34.4328174 | -118.6511816 | Valve Adjustment:High Temp |
| CV-2002 | 5/20/2026 9:41:05 AM | 28.66 | 1274 | 34.4328116 | -118.6511773 | Valve Adjustment:High Temp,Decreased Flow/Vacuum |
| CV-2002 | 5/13/2026 10:09:19 AM | 28.8 | 1271 | 34.4328016 | -118.6511663 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2002 | 5/11/2026 8:10:00 AM | | | | | Air Tech Lab |
| CV-2002 | 5/11/2026 8:10:00 AM | | | | | Air Tech Lab; [User entered 8.3%] |
| CV-2002 | 5/6/2026 1:05:00 PM | | | | | AtmAA |
| CV-2002 | 5/6/2026 1:05:00 PM | | | | | AtmAA; [User entered 13.72%] |
| CV-2002 | 5/6/2026 1:02:03 PM | 28.7 | 1266 | 34.4327936 | -118.6511792 | Valve Adjustment:High Temp,Surging Liquid in Well (Watered In) |
| CV-2003 | 5/19/2026 1:11:41 PM | 28.67 | 1280 | 34.4334358 | -118.6507350 | Valve Adjustment:NSPS/EG CAC,Barely Open |
| CV-2003 | 5/19/2026 1:06:11 PM | 28.67 | 1278 | 34.4334113 | -118.6507280 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-2003 | 5/1/2026 10:27:07 AM | 28.63 | 1285 | 34.4334052 | -118.6507277 | Valve Adjustment:Barely Open |
| CV-2006 | 5/28/2026 8:42:46 AM | 28.58 | 1327 | 34.4352391 | -118.6506276 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-2006 | 5/20/2026 8:18:51 AM | 28.58 | 1318 | 34.4352464 | -118.6506517 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2006 | 5/14/2026 2:04:55 PM | 28.53 | 1293 | 34.4352200 | -118.6507065 | |
| CV-2006 | 5/14/2026 2:03:40 PM | 28.53 | 1227 | 34.4351588 | -118.6506133 | High Temp |
| CV-2006 | 5/11/2026 1:55:37 PM | 28.59 | 1326 | 34.4352436 | -118.6506369 | Valve Adjustment:No Flow Measurement,High Temp,Reduce Sys. Vac. - Flare Down |
| CV-2006 | 5/6/2026 9:20:00 AM | | | | | AtmAA |
| CV-2006 | 5/6/2026 9:20:00 AM | | | | | AtmAA; [User entered 17.34%] |
| CV-2006 | 5/6/2026 9:17:48 AM | 28.66 | 1323 | 34.4352251 | -118.6506474 | Valve Adjustment:Orifice Plate Changed (See OP Log),High Temp |
| CV-2007 | 5/20/2026 2:00:34 PM | 28.41 | 1371 | 34.4361610 | -118.6469898 | Valve Adjustment:Barely Open |
| CV-2007 | 5/8/2026 9:48:29 AM | 28.59 | 1398 | 34.4360997 | -118.6469230 | Reduced System Vacuum |
| CV-2007 | 5/4/2026 8:10:00 AM | | | | | Air Tech Lab; [User entered 5.9%] |
| CV-2008 | 5/11/2026 2:03:03 PM | 28.48 | 1411 | 34.4362800 | -118.6463063 | |
| CV-2009 | 5/8/2026 9:02:48 AM | 28.6 | 1365 | 34.4362193 | -118.6452257 | NSPS/EG CAI,High Temp,Reduced System Vacuum |
| CV-2009 | 5/8/2026 9:00:33 AM | 28.6 | 1371 | 34.4363270 | -118.6453092 | NSPS/EG CAI,High Temp,Positive Static Press.,Reduced System Vacuum |
| CV-2009A | 5/11/2026 1:51:42 PM | 28.47 | 1404 | 34.4359782 | -118.6452695 | |
| CV-2010 | 5/4/2026 1:15:27 PM | 28.58 | 1352 | 34.4356558 | -118.6435827 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-2010A | 5/21/2026 10:29:08 AM | 28.51 | 1360 | 34.4357273 | -118.6436773 | Valve Adjustment:Audible Flow |
| CV-2010A | 5/14/2026 9:40:00 AM | | | | | AtmAA |
| CV-2010A | 5/14/2026 9:38:44 AM | 28.58 | 1361 | 34.4357452 | -118.6436314 | Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum |
| CV-2010A | 5/5/2026 1:03:57 PM | 28.52 | 1362 | 34.4357605 | -118.6436593 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp |
| CV-2010A | 5/5/2026 1:03:17 PM | 28.52 | 1356 | 34.4357552 | -118.6436610 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Increased Flow/Vacuum |
| CV-2010A | 5/4/2026 1:29:04 PM | 28.54 | 1369 | 34.4357562 | -118.6436638 | Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open |
| CV-2010A | 5/4/2026 1:27:58 PM | 28.54 | 1366 | 34.4357503 | -118.6436622 | Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open |
| CV-2010A | 5/4/2026 1:26:56 PM | 28.54 | 1363 | 34.4357462 | -118.6436527 | Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed |
| CV-2011 | 5/11/2026 3:39:24 PM | 28.53 | 1381 | 34.4341870 | -118.6435198 | |
| CV-2011 | 5/11/2026 3:38:18 PM | 28.53 | 1345 | 34.4342182 | -118.6434168 | NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-2011A | 5/28/2026 8:38:45 AM | 28.55 | 1334 | 34.4354559 | -118.6507572 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-2011A | 5/27/2026 3:15:12 PM | 28.43 | 1333 | 34.4345451 | -118.6431606 | Valve Adjustment:High Temp |
| CV-2011A | 5/27/2026 3:14:19 PM | 28.45 | 1332 | 34.4345381 | -118.6431537 | Valve Adjustment:High Temp,Increased Flow/Vacuum |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-2011A | 5/21/2026 9:16:00 AM | 28.54 | 1340 | 34.4345424 | -118.6431436 | Valve Adjustment:High Temp |
| CV-2011A | 5/20/2026 8:33:37 AM | 28.57 | 1318 | 34.4345460 | -118.6431632 | Valve Adjustment:High Temp,Barely Open;Well Comment:pump turned off;Well Condition:Lorentz Pump Installed |
| CV-2011A | 5/20/2026 8:30:13 AM | 28.57 | 1345 | 34.4345285 | -118.6431620 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Comment:Lorentz pump activated;Well Condition:Lorentz Pump Installed;Well Repairs:Sample Port |
| CV-2011A | 5/14/2026 9:40:27 AM | 28.62 | 1362 | 34.4357199 | -118.6436604 | Valve Comment:Lorentz pump offline due to limber expansion;Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed |
| CV-2011A | 5/11/2026 10:58:37 AM | 28.59 | 1328 | 34.4345080 | -118.6431584 | Valve Adjustment:High Temp |
| CV-2011A | 5/4/2026 8:20:00 AM | | | | | AtmAA |
| CV-2011A | 5/4/2026 8:20:00 AM | | | | | AtmAA; [User entered 19.93%] |
| CV-2011A | 5/4/2026 8:19:12 AM | 28.59 | 1322 | 34.4345241 | -118.6431850 | Valve Adjustment:High Temp |
| CV-2012 | 5/11/2026 3:24:22 PM | 28.51 | 1345 | 34.4351362 | -118.6432447 | |
| CV-2012 | 5/11/2026 3:23:03 PM | 28.51 | 1332 | 34.4351127 | -118.6433065 | NSPS/EG CAI,High Temp |
| CV-2201-PLR | 5/19/2026 11:02:27 AM | 28.71 | 1348 | 34.4355533 | -118.6488568 | Valve Adjustment:Barely Open,Surging Liquid in Header |
| CV-2201-PLR | 5/19/2026 10:46:55 AM | 28.71 | 1344 | 34.4355575 | -118.6488530 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header |
| CV-2201-PLR | 5/13/2026 1:54:50 PM | 28.75 | 1354 | 34.4355558 | -118.6488543 | |
| CV-2201-PLR | 5/13/2026 1:53:35 PM | 28.74 | 1352 | 34.4355668 | -118.6488530 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header |
| CV-2204-PLR | 5/26/2026 1:23:17 PM | 28.43 | 1365 | 34.4357832 | -118.6474838 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2204-PLR | 5/18/2026 11:00:00 AM | | | | | AtmAA |
| CV-2204-PLR | 5/18/2026 10:51:06 AM | 28.51 | 1373 | 34.4357649 | -118.6474788 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2204-PLR | 5/12/2026 10:45:00 AM | | | | | AtmAA |
| CV-2204-PLR | 5/12/2026 10:44:05 AM | 28.55 | 1348 | 34.4357681 | -118.6474664 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2204-PLR | 5/5/2026 9:48:20 AM | 28.51 | 1362 | 34.4357712 | -118.6474761 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2204-PLR | 5/5/2026 9:45:00 AM | | | | | AtmAA |
| CV-2204-PLR | 5/5/2026 9:45:00 AM | | | | | AtmAA; [User entered 13.79%] |
| CV-2205 | 5/1/2026 2:09:09 PM | 28.48 | 1374 | 34.4342773 | -118.6441135 | Valve Adjustment:Audible Flow,Barely Open;Well Condition:Fair |
| CV-2207 | 5/11/2026 1:42:35 PM | 28.65 | 1424 | 34.4360663 | -118.6441428 | |
| CV-2207 | 5/11/2026 1:19:38 PM | 28.52 | 1384 | 34.4359988 | -118.6442250 | Valve Comment:well too tall for system |
| CV-2208A | 5/11/2026 11:49:32 AM | 28.53 | 1312 | 34.4365748 | -118.6449385 | |
| CV-2208A | 5/11/2026 11:47:10 AM | 28.53 | 1309 | 34.4364772 | -118.6449732 | High Temp |
| CV-2301 | 5/27/2026 10:38:04 AM | 28.43 | 1342 | 34.4334932 | -118.6492167 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2301 | 5/27/2026 10:36:57 AM | 28.43 | 1341 | 34.4334943 | -118.6492188 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-2301 | 5/19/2026 10:16:23 AM | 28.65 | 1343 | 34.4334867 | -118.6492477 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2301 | 5/19/2026 10:15:36 AM | 28.63 | 1343 | 34.4334866 | -118.6492474 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-2301 | 5/19/2026 10:15:00 AM | | | | | AtmAA |
| CV-2301 | 5/14/2026 11:20:00 AM | | | | | AtmAA |
| CV-2301 | 5/14/2026 10:53:50 AM | 28.71 | 1355 | 34.4335122 | -118.6492387 | |
| CV-2301 | 5/14/2026 10:52:08 AM | 28.71 | 1357 | 34.4335168 | -118.6492318 | Valve Comment:Valve too high to adjust;Valve Adjustment:NSPS/EG CAI,High Temp;Well Comment:No Pump |
| CV-2301 | 5/7/2026 7:55:00 AM | | | | | Air Tech Lab |
| CV-2301 | 5/7/2026 7:55:00 AM | | | | | Air Tech Lab; [User entered 15%] |
| CV-2302 | 5/22/2026 3:57:06 PM | 30 | 1348 | 34.4340720 | -118.6492185 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-2302 | 5/7/2026 8:05:00 AM | | | | | Air Tech Lab |
| CV-2302 | 5/7/2026 8:05:00 AM | | | | | Air Tech Lab; [User entered 5.3%] |
| CV-2302 | 5/4/2026 9:06:38 AM | 28.56 | 1342 | 34.4340388 | -118.6492105 | Valve Adjustment:Valve 100% Open;Well Comment:valve stuck open |
| CV-2303 | 5/27/2026 9:02:45 AM | 28.4 | 1356 | 34.4353757 | -118.6496996 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2303 | 5/19/2026 8:40:00 AM | | | | | AtmAA |
| CV-2303 | 5/19/2026 8:36:23 AM | 28.59 | 1354 | 34.4353850 | -118.6496840 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2303 | 5/13/2026 2:13:55 PM | 28.66 | 1372 | 34.4353776 | -118.6497053 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2303 | 5/12/2026 8:30:00 AM | | | | | Air Tech Lab |
| CV-2303 | 5/12/2026 8:30:00 AM | | | | | Air Tech Lab; [User entered 19%] |
| CV-2303 | 5/5/2026 2:25:00 PM | | | | | AtmAA |
| CV-2303 | 5/5/2026 2:25:00 PM | | | | | AtmAA; [User entered 16.58%] |
| CV-2303 | 5/5/2026 2:21:44 PM | 28.51 | 1356 | 34.4353789 | -118.6497006 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2304 | 5/19/2026 9:15:00 AM | | | | | AtmAA |
| CV-2304 | 5/19/2026 9:14:49 AM | 28.64 | 1339 | 34.4345563 | -118.6487464 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2304 | 5/13/2026 3:03:41 PM | 28.67 | 1341 | 34.4345633 | -118.6487399 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2304 | 5/13/2026 3:02:59 PM | 28.67 | 1341 | 34.4345654 | -118.6487425 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-2304 | 5/8/2026 12:51:34 PM | 28.56 | 1309 | 34.4345933 | -118.6487710 | Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-2304 | 5/8/2026 12:50:06 PM | 28.56 | 1323 | 34.4345802 | -118.6487640 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-2304 | 5/6/2026 3:00:04 PM | 28.59 | 1344 | 34.4345532 | -118.6487415 | Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Surging Liquid in Header |
| CV-2304 | 5/6/2026 3:00:00 PM | | | | | AtmAA |
| CV-2304 | 5/6/2026 3:00:00 PM | | | | | AtmAA; [User entered 18.06%] |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-2304 | 5/6/2026 2:59:41 PM | 28.59 | 1344 | 34.4345533 | -118.6487415 | Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Surging Liquid in Header |
| CV-2305 | 5/27/2026 2:24:19 PM | 28.39 | 1389 | 34.4352222 | -118.6465334 | Valve Adjustment:High Temp,Positive Static Press.,Surging Liquid in Header |
| CV-2305 | 5/27/2026 2:23:44 PM | 28.39 | 1389 | 34.4352225 | -118.6465340 | Valve Adjustment:High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Header |
| CV-2305 | 5/19/2026 1:20:00 PM | | | | | AtmAA |
| CV-2305 | 5/19/2026 1:19:18 PM | 28.58 | 1393 | 34.4352347 | -118.6465351 | Valve Adjustment:High Temp,Valve 100% Open,Surging Liquid in Header |
| CV-2305 | 5/14/2026 10:11:00 AM | | | | | AtmAA |
| CV-2305 | 5/14/2026 10:09:35 AM | 28.58 | 1397 | 34.4352173 | -118.6465290 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed |
| CV-2305 | 5/12/2026 8:10:00 AM | | | | | Air Tech Lab |
| CV-2305 | 5/12/2026 8:10:00 AM | | | | | Air Tech Lab; [User entered 8.2%] |
| CV-2305 | 5/4/2026 8:50:00 AM | 28.53 | 1383 | 34.4352262 | -118.6465321 | Valve Adjustment:High Temp |
| CV-2306 | 5/26/2026 1:28:47 PM | 28.42 | 1364 | 34.4360980 | -118.6478160 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2306 | 5/18/2026 11:00:16 AM | 28.51 | 1375 | 34.4360822 | -118.6478078 | Valve Adjustment:No Flow Measurement,Surging Liquid in Well (Watered In) |
| CV-2306 | 5/18/2026 10:56:22 AM | 28.52 | 1369 | 34.4360784 | -118.6478269 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In) |
| CV-2306 | 5/12/2026 10:50:18 AM | 28.55 | 1360 | 34.4360887 | -118.6478090 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2306 | 5/12/2026 10:50:00 AM | | | | | AtmAA |
| CV-2306 | 5/5/2026 9:52:13 AM | 28.51 | 1360 | 34.4360792 | -118.6478149 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2306 | 5/5/2026 9:50:00 AM | | | | | AtmAA |
| CV-2306 | 5/5/2026 9:50:00 AM | | | | | AtmAA; [User entered 16.19%] |
| CV-2308-PLR | 5/19/2026 10:58:26 AM | 28.71 | 1348 | 34.4358842 | -118.6488933 | |
| CV-2308-PLR | 5/19/2026 10:56:56 AM | 28.7 | 1338 | 34.4358738 | -118.6489067 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In) |
| CV-2308-PLR | 5/13/2026 2:03:12 PM | 28.74 | 1344 | 34.4358813 | -118.6489105 | |
| CV-2308-PLR | 5/13/2026 2:01:38 PM | 28.74 | 1351 | 34.4358865 | -118.6489180 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header |
| CV-2310-PLR | 5/27/2026 9:22:17 AM | 28.43 | 1356 | 34.4353188 | -118.6491328 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header |
| CV-2310-PLR | 5/19/2026 8:56:41 AM | 28.62 | 1353 | 34.4353190 | -118.6491396 | Valve Comment:Surging in well;Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In);Well Repairs:Surging |
| CV-2310-PLR | 5/19/2026 8:55:00 AM | | | | | AtmAA |
| CV-2310-PLR | 5/13/2026 2:22:47 PM | 28.66 | 1365 | 34.4353284 | -118.6491404 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In) |
| CV-2310-PLR | 5/6/2026 2:40:00 PM | | | | | AtmAA; [User entered 10.07%] |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-2310-PLR | 5/6/2026 2:30:00 PM | | | | | AtmAA |
| CV-2310-PLR | 5/6/2026 2:26:12 PM | 28.59 | 1350 | 34.4353306 | -118.6491158 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In) |
| CV-2310-PLR | 5/1/2026 11:45:33 AM | 28.52 | 1368 | 34.4353170 | -118.6491418 | Valve Adjustment:NSPS/EG CAI,High Temp,Valve 100% Open,Surging Liquid in Header |
| CV-2310-PLR | 5/1/2026 11:44:42 AM | 28.52 | 1368 | 34.4353170 | -118.6491418 | Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Valve 100% Open |
| CV-2311 | 5/26/2026 2:01:48 PM | 28.41 | 1376 | 34.4363199 | -118.6498953 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2311 | 5/18/2026 2:25:36 PM | 28.47 | 1370 | 34.4363289 | -118.6498830 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Valve 100% Open |
| CV-2311 | 5/18/2026 2:25:00 PM | | | | | AtmAA |
| CV-2311 | 5/18/2026 2:24:18 PM | 28.51 | 1369 | 34.4363298 | -118.6498817 | Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open |
| CV-2311 | 5/12/2026 2:05:46 PM | 28.55 | 1362 | 34.4363119 | -118.6498960 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2311 | 5/12/2026 2:03:19 PM | 28.55 | 1360 | 34.4363189 | -118.6498914 | Valve Adjustment:High Temp,Decreased Flow/Vacuum |
| CV-2311 | 5/12/2026 2:00:00 PM | | | | | AtmAA |
| CV-2311 | 5/5/2026 10:25:04 AM | 28.51 | 1371 | 34.4363116 | -118.6498841 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2311 | 5/5/2026 10:25:00 AM | | | | | AtmAA |
| CV-2311 | 5/5/2026 10:25:00 AM | | | | | AtmAA; [User entered 13.97%] |
| CV-2312 | 5/27/2026 11:01:39 AM | 28.41 | 1373 | 34.4342058 | -118.6473544 | Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Well (Watered In) |
| CV-2312 | 5/19/2026 10:35:25 AM | 28.62 | 1378 | 34.4342068 | -118.6473721 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In) |
| CV-2312 | 5/19/2026 10:35:00 AM | | | | | AtmAA |
| CV-2312 | 5/13/2026 11:08:10 AM | 28.67 | 1377 | 34.4342078 | -118.6473685 | Valve Adjustment:NSPS/EG CAI,Audible Flow,No Flow Measurement,High Temp |
| CV-2312 | 5/13/2026 9:06:06 AM | 28.62 | 1392 | 34.4342185 | -118.6473540 | Valve Comment:ACTIVE PLR;Valve Adjustment:No Flow Measurement,High Temp;Well Comment:Installed sample ports on now hard pipe well |
| CV-2312 | 5/13/2026 8:30:00 AM | | | | | Air Tech Lab |
| CV-2312 | 5/13/2026 8:30:00 AM | | | | | Air Tech Lab; [User entered 9.0%] |
| CV-2312 | 5/4/2026 10:29:04 AM | 28.53 | 1387 | 34.4342201 | -118.6473614 | Valve Comment:Active PLR;Valve Adjustment:No Flow Measurement,High Temp |
| CV-2312 | 5/4/2026 10:27:12 AM | 28.56 | 1387 | 34.4342224 | -118.6473626 | Valve Comment:Active plr;Valve Adjustment:No Flow Measurement |
| CV-2312 | 5/4/2026 10:15:00 AM | | | | | AtmAA |
| CV-2312 | 5/4/2026 10:15:00 AM | | | | | AtmAA; [User entered 12.03%] |
| CV-2314 | 5/27/2026 1:46:16 PM | 28.38 | 1386 | 34.4347126 | -118.6466876 | Valve Adjustment:High Temp |
| CV-2314 | 5/27/2026 1:45:46 PM | 28.38 | 1384 | 34.4347176 | -118.6466899 | Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-2314 | 5/19/2026 2:00:00 PM | | | | | AtmAA |
| CV-2314 | 5/19/2026 1:53:23 PM | 28.58 | 1392 | 34.4346978 | -118.6467182 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2314 | 5/14/2026 1:50:56 PM | 28.67 | 1371 | 34.4347190 | -118.6467362 | |
| CV-2314 | 5/14/2026 1:49:32 PM | 28.67 | 1398 | 34.4345485 | -118.6465587 | NSPS/EG CAI,High Temp |
| CV-2314 | 5/12/2026 8:05:00 AM | | | | | Air Tech Lab |
| CV-2314 | 5/12/2026 8:05:00 AM | | | | | Air Tech Lab; [User entered 14%] |
| CV-2314 | 5/11/2026 10:32:15 AM | 28.53 | 1385 | 34.4346920 | -118.6467260 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header |
| CV-2314 | 5/4/2026 9:40:25 AM | 28.56 | 1384 | 34.4346873 | -118.6467112 | Valve Adjustment:High Temp |
| CV-2314 | 5/4/2026 9:40:00 AM | | | | | AtmAA |
| CV-2314 | 5/4/2026 9:40:00 AM | | | | | AtmAA; [User entered 11%] |
| CV-2315 | 5/26/2026 10:35:23 AM | 28.43 | 1397 | 34.4354928 | -118.6472032 | Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open |
| CV-2315 | 5/19/2026 1:35:00 PM | | | | | AtmAA |
| CV-2315 | 5/19/2026 1:31:37 PM | 28.58 | 1382 | 34.4355198 | -118.6472000 | Valve Comment:Lorentz pump disconnected;Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open;Well Condition:Lorentz Pump Installed |
| CV-2315 | 5/13/2026 1:43:34 PM | 28.74 | 1386 | 34.4355063 | -118.6472078 | |
| CV-2315 | 5/13/2026 1:42:47 PM | 28.71 | 1380 | 34.4355038 | -118.6471995 | Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header |
| CV-2315 | 5/11/2026 8:41:37 AM | 28.51 | 1388 | 34.4355101 | -118.6471938 | Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open |
| CV-2315 | 5/7/2026 8:30:00 AM | | | | | Air Tech Lab |
| CV-2315 | 5/7/2026 8:30:00 AM | | | | | Air Tech Lab; [User entered 14%] |
| CV-2315 | 5/6/2026 3:30:00 PM | | | | | AtmAA |
| CV-2315 | 5/6/2026 3:30:00 PM | | | | | AtmAA; [User entered 8.33%] |
| CV-2315 | 5/6/2026 3:27:40 PM | 28.55 | 1379 | 34.4355252 | -118.6472020 | Valve Comment:LORENTZ PUMP DISCONECTED;Valve Adjustment:No Flow Measurement,High Temp |
| CV-2315 | 5/6/2026 3:25:58 PM | 28.55 | 1379 | 34.4355265 | -118.6471998 | Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum |
| CV-2316 | 5/11/2026 1:59:13 PM | 28.47 | 1467 | 34.4361423 | -118.6464818 | |
| CV-2316 | 5/11/2026 1:57:51 PM | 28.47 | 1463 | 34.4361048 | -118.6464438 | High Temp |
| CV-2319 | 5/12/2026 8:28:11 AM | 28.5 | 1417 | 34.4353043 | -118.6458277 | NSPS/EG CAI,High Temp |
| CV-2319 | 5/12/2026 8:26:00 AM | 28.5 | 1427 | 34.4352733 | -118.6458283 | |
| CV-2321 | 5/27/2026 2:51:44 PM | 28.36 | 1397 | 34.4346293 | -118.6453636 | Valve Comment:Lorentz pump on upon arrival;Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed |
| CV-2321 | 5/27/2026 2:50:12 PM | 28.36 | 1396 | 34.4346303 | -118.6453635 | Valve Adjustment:High Temp,Decreased Flow/Vacuum |
| CV-2321 | 5/19/2026 1:00:00 PM | | | | | AtmAA |
| CV-2321 | 5/19/2026 12:59:11 PM | 28.58 | 1395 | 34.4346305 | -118.6453974 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-2321 | 5/19/2026 12:56:22 PM | 28.58 | 1393 | 34.4346333 | -118.6454210 | Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum |
| CV-2321 | 5/11/2026 9:19:14 AM | 28.53 | 1389 | 34.4346294 | -118.6453868 | Valve Adjustment:High Temp |
| CV-2321 | 5/11/2026 9:16:26 AM | 28.52 | 1388 | 34.4346288 | -118.6453930 | Valve Adjustment:High Temp,Decreased Flow/Vacuum |
| CV-2321 | 5/7/2026 9:50:36 AM | 28.53 | 1380 | 34.4346396 | -118.6453619 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp |
| CV-2321 | 5/7/2026 9:50:00 AM | | | | | AtmAA |
| CV-2321 | 5/7/2026 9:50:00 AM | | | | | AtmAA; [User entered 7.68%] |
| CV-2321 | 5/7/2026 9:49:06 AM | 28.54 | 1371 | 34.4346431 | -118.6453347 | Valve Adjustment:NSPS/EG CAI,Orifice Plate Changed (See OP Log),No Flow Measurement,High Temp,Increased Flow/Vacuum |
| CV-2321 | 5/1/2026 10:23:30 AM | 28.44 | 1434 | 34.4345733 | -118.6453842 | |
| CV-2321 | 5/1/2026 10:20:34 AM | 28.44 | 1417 | 34.4346207 | -118.6453583 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,NSPS/EG CAI,NSPS/EG CAC,Audible Flow,High Temp,Positive Static Press., |
| CV-2322 | 5/26/2026 9:22:23 AM | 28.41 | 1376 | 34.4352687 | -118.6475092 | Valve Adjustment:Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| CV-2322 | 5/4/2026 1:40:46 PM | 28.51 | 1362 | 34.4352915 | -118.6475316 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement |
| CV-2324 | 5/6/2026 2:05:45 PM | 28.61 | 1389 | 34.4345107 | -118.6442275 | Valve Adjustment:Barely Open |
| CV-2324 | 5/1/2026 11:00:44 AM | 28.46 | 1385 | 34.4345068 | -118.6442455 | |
| CV-2326 | 5/19/2026 10:26:12 AM | 28.59 | 1377 | 34.4361458 | -118.6504698 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-2326 | 5/19/2026 10:25:24 AM | 28.59 | 1375 | 34.4361437 | -118.6504750 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-2326 | 5/1/2026 11:33:29 AM | 28.52 | 1377 | 34.4361170 | -118.6504862 | Valve Comment:no system port;Valve Adjustment:Valve 100% Open |
| CV-2327 | 5/28/2026 1:44:39 PM | 28.55 | 1368 | 34.4349085 | -118.6479494 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-2327 | 5/20/2026 2:15:58 PM | 28.52 | 1367 | 34.4348793 | -118.6479346 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2327 | 5/14/2026 10:00:04 AM | 28.62 | 1368 | 34.4349305 | -118.6479449 | Valve Comment:Installed sample port on system side;Valve Adjustment:No Flow Measurement,High Temp |
| CV-2327 | 5/14/2026 9:57:08 AM | 28.61 | 1365 | 34.4349206 | -118.6479368 | Valve Comment:Going to drill port on system side;Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-2327 | 5/14/2026 9:50:00 AM | | | | | AtmAA |
| CV-2327 | 5/4/2026 1:23:07 PM | 28.52 | 1364 | 34.4348905 | -118.6479357 | Valve Adjustment:High Temp |
| CV-2327 | 5/4/2026 1:20:00 PM | | | | | AtmAA |
| CV-2327 | 5/4/2026 1:20:00 PM | | | | | AtmAA; [User entered 4.81%] |
| CV-2328 | 5/28/2026 1:37:05 PM | 28.53 | 1369 | 34.4343299 | -118.6483422 | Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header |
| CV-2328 | 5/20/2026 2:06:30 PM | 28.53 | 1355 | 34.4343211 | -118.6483402 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed |
| CV-2328 | 5/20/2026 2:05:13 PM | 28.53 | 1354 | 34.4343222 | -118.6483424 | Valve Adjustment:High Temp,Increased Flow/Vacuum |
| CV-2328 | 5/11/2026 1:26:04 PM | 28.55 | 1357 | 34.4343503 | -118.6483110 | Valve Adjustment:High Temp,Reduce Sys. Vac. - Flare Down |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-2328 | 5/7/2026 8:15:00 AM | | | | | Air Tech Lab |
| CV-2328 | 5/7/2026 8:15:00 AM | | | | | Air Tech Lab; [User entered 11%] |
| CV-2328 | 5/4/2026 1:07:16 PM | 28.51 | 1358 | 34.4343214 | -118.6483639 | Valve Adjustment:NSPS/EG CAC,Audible Flow,High Temp |
| CV-2328 | 5/4/2026 1:06:42 PM | 28.52 | 1358 | 34.4343212 | -118.6483640 | Valve Adjustment:NSPS/EG CAI,Audible Flow,Increased Flow/Vacuum |
| CV-2328 | 5/4/2026 1:05:00 PM | | | | | AtmAA |
| CV-2328 | 5/4/2026 1:05:00 PM | | | | | AtmAA; [User entered 5.36%] |
| CV-2333 | 5/29/2026 9:43:07 AM | 28.66 | 1362 | 34.4365133 | -118.6473637 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-2333 | 5/26/2026 8:54:11 AM | 28.44 | 1377 | 34.4365219 | -118.6473562 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2333 | 5/18/2026 9:15:00 AM | | | | | AtmAA |
| CV-2333 | 5/18/2026 9:12:06 AM | 28.47 | 1377 | 34.4365329 | -118.6473685 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2333 | 5/13/2026 7:40:00 AM | | | | | Air Tech Lab |
| CV-2333 | 5/13/2026 7:40:00 AM | | | | | Air Tech Lab; [User entered 16%] |
| CV-2333 | 5/12/2026 9:35:00 AM | | | | | AtmAA |
| CV-2333 | 5/12/2026 9:28:21 AM | 28.52 | 1381 | 34.4365299 | -118.6473812 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2333 | 5/6/2026 9:45:24 AM | 28.64 | 1370 | 34.4365270 | -118.6473628 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-2333 | 5/6/2026 9:44:40 AM | 28.64 | 1366 | 34.4365335 | -118.6473665 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-2333 | 5/5/2026 8:30:00 AM | | | | | AtmAA |
| CV-2333 | 5/5/2026 8:30:00 AM | | | | | AtmAA; [User entered 16.01%] |
| CV-2333 | 5/5/2026 8:26:49 AM | 28.51 | 1358 | 34.4365039 | -118.6473630 | Valve Adjustment:Audible Flow,High Temp |
| CV-2334 | 5/26/2026 2:23:32 PM | 28.37 | 1357 | 34.4366867 | -118.6466828 | Valve Adjustment:Barely Open |
| CV-2334 | 5/13/2026 7:45:00 AM | | | | | Air Tech Lab |
| CV-2334 | 5/13/2026 7:45:00 AM | | | | | Air Tech Lab; [User entered 1.1%] |
| CV-2335 | 5/19/2026 10:11:09 AM | 28.63 | 1323 | 34.4364060 | -118.6509820 | |
| CV-2335 | 5/12/2026 10:45:40 AM | 28.6 | 1329 | 34.4363798 | -118.6509515 | No Flow Measurement |
| CV-2336 | 5/19/2026 10:14:30 AM | 28.63 | 1354 | 34.4359915 | -118.6508988 | |
| CV-2336 | 5/12/2026 10:27:38 AM | 28.61 | 1362 | 34.4359502 | -118.6509048 | No Flow Measurement |
| CV-2337 | 5/20/2026 8:23:36 AM | 28.58 | 1328 | 34.4354665 | -118.6507628 | Valve Adjustment:High Temp |
| CV-2337 | 5/11/2026 2:00:37 PM | 28.59 | 1327 | 34.4354710 | -118.6507658 | Valve Adjustment:No Flow Measurement,High Temp,Reduce Sys. Vac. - Flare Down |
| CV-2337 | 5/11/2026 8:05:00 AM | | | | | Air Tech Lab |
| CV-2337 | 5/11/2026 8:05:00 AM | | | | | Air Tech Lab; [User entered 13%] |
| CV-2337 | 5/6/2026 9:26:13 AM | 28.66 | 1331 | 34.4354664 | -118.6507838 | Valve Adjustment:High Temp,Valve 100% Open |
| CV-2337 | 5/6/2026 9:25:00 AM | | | | | AtmAA |
| CV-2337 | 5/6/2026 9:25:00 AM | | | | | AtmAA; [User entered 12.23%] |
| CV-2338 | 5/28/2026 8:46:22 AM | 28.58 | 1316 | 34.4348679 | -118.6504584 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-2338 | 5/20/2026 8:15:49 AM | 28.6 | 1327 | 34.4348565 | -118.6504794 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2338 | 5/12/2026 10:09:33 AM | 28.63 | 1293 | 34.4349470 | -118.6503273 | NSPS/EG CAI,High Temp |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-2338 | 5/12/2026 10:05:03 AM | 28.63 | 1309 | 34.4348593 | -118.6504292 | NSPS/EG CAI,High Temp |
| CV-2338 | 5/11/2026 1:52:50 PM | 28.6 | 1315 | 34.4348633 | -118.6504710 | Valve Adjustment:High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down |
| CV-2338 | 5/11/2026 1:52:06 PM | 28.59 | 1315 | 34.4348630 | -118.6504678 | Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Valve 100% Open,Reduce Sys. Vac. - Flare Down |
| CV-2338 | 5/6/2026 9:15:00 AM | | | | | AtmAA |
| CV-2338 | 5/6/2026 9:15:00 AM | | | | | AtmAA; [User entered 17.41%] |
| CV-2338 | 5/6/2026 9:13:21 AM | 28.7 | 1319 | 34.4348462 | -118.6504661 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2338 | 5/6/2026 9:12:07 AM | 28.7 | 1321 | 34.4348350 | -118.6504678 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-2339 | 5/29/2026 10:41:08 AM | 28.65 | 1309 | 34.4341757 | -118.6502638 | NSPS/EG CAI,High O2 |
| CV-2339 | 5/29/2026 10:39:26 AM | 28.65 | 1309 | 34.4341957 | -118.6502310 | NSPS/EG CAI,High O2 |
| CV-2339 | 5/14/2026 2:06:48 PM | 28.71 | 1302 | 34.4342078 | -118.6502873 | Valve Adjustment:NSPS/EG CAC |
| CV-2339 | 5/14/2026 2:04:49 PM | 28.72 | 1305 | 34.4342002 | -118.6502865 | Valve Comment:pump off;Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed |
| CV-2341 | 5/29/2026 10:30:39 AM | 28.65 | 1319 | 34.4336450 | -118.6501882 | |
| CV-2341 | 5/14/2026 1:47:09 PM | 28.71 | 1312 | 34.4336342 | -118.6501662 | Valve Adjustment:Audible Flow |
| CV-2341 | 5/11/2026 7:50:00 AM | | | | | Air Tech Lab |
| CV-2341 | 5/11/2026 7:50:00 AM | | | | | Air Tech Lab; [User entered 9.4%] |
| CV-2342A-PLR | 5/28/2026 1:15:25 PM | 28.59 | 1300 | 34.4342446 | -118.6508500 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-2342A-PLR | 5/20/2026 9:08:28 AM | 28.65 | 1288 | 34.4342158 | -118.6508593 | Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open |
| CV-2342A-PLR | 5/13/2026 9:52:01 AM | 28.77 | 1288 | 34.4341971 | -118.6508514 | Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open |
| CV-2342A-PLR | 5/6/2026 10:10:00 AM | 28.7 | 1279 | 34.4342109 | -118.6508438 | Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open |
| CV-2343 | 5/26/2026 2:33:45 PM | 28.49 | 1293 | 34.4332428 | -118.6507077 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement |
| CV-2343 | 5/19/2026 2:04:37 PM | 28.67 | 1279 | 34.4332542 | -118.6507110 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-2343 | 5/19/2026 2:03:22 PM | 28.67 | 1276 | 34.4332587 | -118.6507070 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-2343 | 5/6/2026 9:56:02 AM | 28.7 | 1296 | 34.4332304 | -118.6506766 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2344 | 5/20/2026 8:51:25 AM | 28.62 | 1301 | 34.4329875 | -118.6504420 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement |
| CV-2344 | 5/13/2026 9:31:33 AM | 28.73 | 1306 | 34.4329877 | -118.6504541 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2344 | 5/13/2026 9:30:38 AM | 28.73 | 1306 | 34.4329844 | -118.6504537 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-2344 | 5/11/2026 7:35:00 AM | | | | | Air Tech Lab |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-2344 | 5/11/2026 7:35:00 AM | | | | | Air Tech Lab; [User entered 16%] |
| CV-2344 | 5/6/2026 9:52:20 AM | 28.7 | 1303 | 34.4329593 | -118.6504426 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2344 | 5/6/2026 9:50:00 AM | | | | | AtmAA |
| CV-2344 | 5/6/2026 9:50:00 AM | | | | | AtmAA; [User entered 13.94%] |
| CV-2345 | 5/19/2026 2:17:28 PM | 28.63 | 1302 | 34.4327340 | -118.6501765 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-2345 | 5/19/2026 2:15:18 PM | 28.63 | 1297 | 34.4327320 | -118.6501865 | Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum |
| CV-2345 | 5/11/2026 7:30:00 AM | | | | | Air Tech Lab |
| CV-2345 | 5/11/2026 7:30:00 AM | | | | | Air Tech Lab; [User entered 2.8%] |
| CV-2345 | 5/1/2026 10:20:11 AM | 28.62 | 1302 | 34.4327270 | -118.6501633 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-2345 | 5/1/2026 10:19:42 AM | 28.62 | 1297 | 34.4327213 | -118.6501513 | Valve Adjustment:NSPS/EG CAI,High Temp;Well Repairs:Sample Port |
| CV-2346 | 5/28/2026 9:28:07 AM | 28.58 | 1313 | 34.4326182 | -118.6500469 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-2346 | 5/20/2026 8:47:59 AM | 28.61 | 1312 | 34.4326111 | -118.6500938 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2346 | 5/13/2026 9:20:50 AM | 28.73 | 1315 | 34.4325988 | -118.6500877 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2346 | 5/6/2026 9:47:10 AM | 28.7 | 1322 | 34.4325727 | -118.6500511 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2346 | 5/6/2026 9:45:00 AM | | | | | AtmAA |
| CV-2346 | 5/6/2026 9:45:00 AM | | | | | AtmAA; [User entered 11.85%] |
| CV-2346 | 5/6/2026 8:25:00 AM | | | | | Air Tech Lab |
| CV-2346 | 5/6/2026 8:25:00 AM | | | | | Air Tech Lab; [User entered 13%] |
| CV-2346 | 5/4/2026 1:29:13 PM | 28.61 | 1303 | 34.4326202 | -118.6500715 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed |
| CV-2346 | 5/4/2026 1:27:19 PM | 28.6 | 1304 | 34.4326235 | -118.6500738 | Valve Adjustment:NSPS/EG CAC,High Temp;Well Condition:Lorentz Pump Installed |
| CV-2347 | 5/20/2026 8:26:42 AM | 28.59 | 1314 | 34.4323538 | -118.6498270 | Valve Comment:well needs lowering;Valve Adjustment:Audible Flow |
| CV-2347 | 5/6/2026 8:20:00 AM | | | | | Air Tech Lab |
| CV-2347 | 5/6/2026 8:20:00 AM | | | | | Air Tech Lab; [User entered 5.6%] |
| CV-2347 | 5/1/2026 10:09:08 AM | 28.6 | 1314 | 34.4323262 | -118.6498575 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-2348 | 5/20/2026 8:15:56 AM | 28.58 | 1322 | 34.4321423 | -118.6496170 | Valve Comment:Well needs lowering;Valve Adjustment:Audible Flow,Surging Liquid in Header |
| CV-2348 | 5/13/2026 12:35:31 PM | 28.86 | | | | |
| CV-2348 | 5/6/2026 8:15:00 AM | | | | | Air Tech Lab |
| CV-2348 | 5/6/2026 8:15:00 AM | | | | | Air Tech Lab; [User entered 2.7%] |
| CV-2349 | 5/28/2026 10:20:04 AM | 28.62 | 1284 | 34.4331432 | -118.6512616 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-2349 | 5/20/2026 10:27:38 AM | 28.66 | 1261 | 34.4331426 | -118.6512625 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp |
| CV-2349 | 5/13/2026 10:48:12 AM | 28.79 | 1261 | 34.4331521 | -118.6512689 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header;Well Condition:Lorentz Pump Installed |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-2349 | 5/7/2026 11:16:23 AM | 28.66 | 1260 | 34.4331361 | -118.6512844 | Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down |
| CV-2349 | 5/7/2026 11:15:19 AM | 28.66 | 1260 | 34.4331350 | -118.6512776 | Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Increased Flow/Vacuum |
| CV-2349 | 5/7/2026 11:15:00 AM | | | | | AtmAA |
| CV-2349 | 5/7/2026 11:15:00 AM | | | | | AtmAA; [User entered 11.7%] |
| CV-2349 | 5/5/2026 8:25:00 AM | | | | | Air Tech Lab |
| CV-2349 | 5/5/2026 8:25:00 AM | | | | | Air Tech Lab; [User entered 15%] |
| CV-2350 | 5/20/2026 10:03:44 AM | 28.63 | 1270 | 34.4327675 | -118.6508973 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-2350 | 5/13/2026 12:57:10 PM | 28.68 | 1319 | 34.4327625 | -118.6509237 | |
| CV-2350 | 5/13/2026 12:56:01 PM | 28.68 | 1296 | 34.4327222 | -118.6508528 | NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-2350 | 5/11/2026 7:40:00 AM | | | | | Air Tech Lab |
| CV-2350 | 5/11/2026 7:40:00 AM | | | | | Air Tech Lab; [User entered 17%] |
| CV-2351 | 5/28/2026 9:25:03 AM | 28.62 | 1284 | 34.4351297 | -118.6511445 | Valve Adjustment:NSPS/EG CAI,High O2 |
| CV-2351 | 5/28/2026 9:24:00 AM | 28.62 | 1287 | 34.4351405 | -118.6511518 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum |
| CV-2351 | 5/5/2026 7:50:00 AM | | | | | Air Tech Lab |
| CV-2351 | 5/5/2026 7:50:00 AM | | | | | Air Tech Lab; [User entered 0.16%] |
| CV-2351 | 5/1/2026 9:05:14 AM | 28.61 | 1281 | 34.4350955 | -118.6511857 | Valve Adjustment:Valve 100% Closed,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:Valve stuck open |
| CV-2352 | 5/28/2026 9:16:38 AM | 28.6 | 1286 | 34.4348563 | -118.6510468 | Valve Adjustment:NSPS/EG CAI,High O2 |
| CV-2352 | 5/28/2026 9:12:47 AM | 28.6 | 1284 | 34.4348652 | -118.6510425 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum |
| CV-2352 | 5/5/2026 8:00:00 AM | | | | | Air Tech Lab |
| CV-2352 | 5/5/2026 8:00:00 AM | | | | | Air Tech Lab; [User entered 19%] |
| CV-2352 | 5/1/2026 9:13:24 AM | 28.61 | 1284 | 34.4348275 | -118.6510687 | Valve Adjustment:Increased Flow/Vacuum,Barely Open;Well Comment:Possible damaged valve |
| CV-2353-PLR | 5/20/2026 9:13:57 AM | 28.65 | 1296 | 34.4345360 | -118.6509304 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement |
| CV-2353-PLR | 5/20/2026 9:13:10 AM | 28.63 | 1296 | 34.4345359 | -118.6509308 | Valve Adjustment:No Flow Measurement,Decreased Flow/Vacuum |
| CV-2353-PLR | 5/15/2026 8:29:12 AM | 28.63 | 1290 | 34.4345350 | -118.6509228 | Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open |
| CV-2353-PLR | 5/15/2026 8:27:25 AM | 28.62 | 1285 | 34.4345260 | -118.6509185 | Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open |
| CV-2353-PLR | 5/14/2026 8:40:00 AM | | | | | AtmAA |
| CV-2353-PLR | 5/12/2026 7:35:00 AM | | | | | Air Tech Lab |
| CV-2353-PLR | 5/12/2026 7:35:00 AM | | | | | Air Tech Lab; [User entered 21%] |
| CV-2354 | 5/28/2026 10:36:46 AM | 28.66 | 1270 | 34.4336740 | -118.6513429 | Valve Adjustment:NSPS/EG CAI,High Temp |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-2354 | 5/20/2026 10:42:07 AM | 28.66 | 1278 | 34.4336917 | -118.6513670 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header;Well Condition:Lorentz Pump Installed;Well Repairs:Surging |
| CV-2354 | 5/20/2026 10:40:36 AM | 28.66 | 1277 | 34.4336809 | -118.6513640 | Valve Comment:Header watered in;Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Header;Well Condition:Lorentz Pump Installed;Well Repairs:Surging |
| CV-2354 | 5/13/2026 11:03:49 AM | 28.81 | 1253 | 34.4336904 | -118.6513663 | Valve Comment:LORENTZ pump started after last read so cleared some 02;Valve Adjustment:No Flow Measurement,High Temp |
| CV-2354 | 5/13/2026 11:01:08 AM | 28.8 | 1254 | 34.4336905 | -118.6513642 | Valve Adjustment:No Flow Measurement,High Temp,Barely Open |
| CV-2354 | 5/6/2026 10:50:20 AM | 28.74 | 1259 | 34.4336848 | -118.6513483 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2354 | 5/6/2026 10:50:00 AM | | | | | AtmAA |
| CV-2354 | 5/6/2026 10:50:00 AM | | | | | AtmAA; [User entered 14.8%] |
| CV-2354 | 5/5/2026 8:20:00 AM | | | | | Air Tech Lab |
| CV-2354 | 5/5/2026 8:20:00 AM | | | | | Air Tech Lab; [User entered 17%] |
| CV-24001 | 5/19/2026 10:02:44 AM | 28.62 | 1351 | 34.4366327 | -118.6509302 | |
| CV-24001 | 5/12/2026 10:38:27 AM | 28.59 | 1385 | 34.4366077 | -118.6510030 | |
| CV-24002 | 5/19/2026 9:53:36 AM | 28.63 | 1353 | 34.4367335 | -118.6504768 | Valve Adjustment:NSPS/EG CAC,Barely Open;Well Comment:Sample port installed |
| CV-24002 | 5/19/2026 9:51:18 AM | 28.63 | 1344 | 34.4367297 | -118.6504578 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open |
| CV-24002 | 5/1/2026 2:39:31 PM | 28.47 | 1341 | 34.4367492 | -118.6504717 | Well Comment:no system port |
| CV-24003 | 5/19/2026 9:12:06 AM | 28.59 | 1373 | 34.4368667 | -118.6500807 | Valve Adjustment:Barely Open;Well Repairs:Valve |
| CV-24003 | 5/1/2026 2:37:02 PM | 28.45 | 1347 | 34.4368643 | -118.6500682 | |
| CV-24004 | 5/19/2026 9:02:30 AM | 28.59 | 1368 | 34.4370670 | -118.6496833 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open |
| CV-24004 | 5/1/2026 2:33:11 PM | 28.45 | 1361 | 34.4370727 | -118.6496892 | Valve Adjustment:Barely Open |
| CV-24006 | 5/19/2026 10:36:49 AM | 28.59 | 1365 | 34.4363533 | -118.6504565 | Valve Adjustment:Barely Open |
| CV-24006 | 5/1/2026 11:40:45 AM | 28.5 | 1391 | 34.4363850 | -118.6504893 | |
| CV-24007 | 5/29/2026 9:33:56 AM | 28.63 | 1381 | 34.4365195 | -118.6501157 | Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum |
| CV-24007 | 5/26/2026 1:56:22 PM | 28.4 | 1377 | 34.4365219 | -118.6501221 | Valve Adjustment:High Temp |
| CV-24007 | 5/26/2026 1:55:46 PM | 28.4 | 1377 | 34.4365234 | -118.6501195 | Valve Adjustment:High Temp,Increased Flow/Vacuum |
| CV-24007 | 5/19/2026 10:46:37 AM | 28.59 | 1355 | 34.4365007 | -118.6500992 | Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Barely Open |
| CV-24007 | 5/19/2026 10:45:21 AM | 28.59 | 1366 | 34.4365215 | -118.6501223 | Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Increased Flow/Vacuum |
| CV-24007 | 5/15/2026 9:10:41 AM | 28.53 | 1376 | 34.4365388 | -118.6500990 | Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header |
| CV-24007 | 5/15/2026 9:09:54 AM | 28.53 | 1373 | 34.4365295 | -118.6501087 | Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum,Surging Liquid in Header |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24007 | 5/12/2026 8:40:00 AM | | | | | Air Tech Lab |
| CV-24007 | 5/12/2026 8:40:00 AM | | | | | Air Tech Lab; [User entered 17%] |
| CV-24008 | 5/26/2026 1:50:27 PM | 28.4 | 1379 | 34.4366982 | -118.6496973 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24008 | 5/18/2026 2:25:00 PM | | | | | AtmAA |
| CV-24008 | 5/18/2026 2:17:05 PM | 28.51 | 1370 | 34.4366822 | -118.6496978 | Valve Adjustment:High Temp |
| CV-24008 | 5/12/2026 1:41:31 PM | 28.55 | 1381 | 34.4366814 | -118.6497041 | Valve Adjustment:High Temp,Decreased Flow/Vacuum;Well Comment:Valve on well head does nit adjust input a maintance form |
| CV-24008 | 5/12/2026 1:40:00 PM | | | | | AtmAA |
| CV-24008 | 5/5/2026 10:20:00 AM | | | | | AtmAA |
| CV-24008 | 5/5/2026 10:20:00 AM | | | | | AtmAA; [User entered 8.66%] |
| CV-24008 | 5/5/2026 10:14:56 AM | 28.51 | 1374 | 34.4366809 | -118.6496833 | Valve Adjustment:High Temp |
| CV-24009 | 5/26/2026 1:46:14 PM | 28.4 | 1374 | 34.4368956 | -118.6493814 | Valve Adjustment:High Temp |
| CV-24009 | 5/18/2026 2:20:00 PM | | | | | AtmAA |
| CV-24009 | 5/18/2026 2:13:29 PM | 28.51 | 1373 | 34.4368830 | -118.6493610 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24009 | 5/12/2026 1:35:00 PM | | | | | AtmAA |
| CV-24009 | 5/12/2026 1:31:36 PM | 28.54 | 1373 | 34.4368941 | -118.6493668 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24009 | 5/5/2026 10:15:00 AM | | | | | AtmAA |
| CV-24009 | 5/5/2026 10:15:00 AM | | | | | AtmAA; [User entered 13.53%] |
| CV-24009 | 5/5/2026 10:10:10 AM | 28.51 | 1369 | 34.4368615 | -118.6493551 | Valve Adjustment:High Temp |
| CV-24010 | 5/26/2026 9:45:36 AM | 28.43 | 1373 | 34.4370698 | -118.6489448 | Valve Adjustment:High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-24010 | 5/13/2026 1:57:52 PM | 28.63 | 1349 | 34.4370955 | -118.6489555 | |
| CV-24011 | 5/27/2026 8:51:05 AM | 28.4 | 1377 | 34.4362140 | -118.6501631 | Valve Adjustment:High Temp |
| CV-24011 | 5/27/2026 8:49:35 AM | 28.39 | 1378 | 34.4362009 | -118.6501779 | Valve Adjustment:High Temp,Increased Flow/Vacuum |
| CV-24011 | 5/19/2026 10:30:22 AM | 28.59 | 1364 | 34.4361915 | -118.6501875 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24011 | 5/18/2026 2:55:00 PM | | | | | AtmAA |
| CV-24011 | 5/18/2026 2:48:57 PM | 28.51 | 1373 | 34.4362109 | -118.6501841 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24011 | 5/12/2026 2:43:10 PM | 28.57 | 1368 | 34.4362031 | -118.6502022 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24011 | 5/12/2026 2:25:00 PM | | | | | AtmAA |
| CV-24011 | 5/5/2026 1:10:54 PM | 28.51 | 1378 | 34.4361917 | -118.6502091 | Valve Adjustment:High Temp |
| CV-24011 | 5/5/2026 1:10:00 PM | | | | | AtmAA |
| CV-24011 | 5/5/2026 1:10:00 PM | | | | | AtmAA; [User entered 10.77%] |
| CV-24012 | 5/26/2026 2:14:33 PM | 28.42 | 1360 | 34.4361780 | -118.6493885 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24012 | 5/18/2026 2:56:25 PM | 28.51 | 1358 | 34.4361784 | -118.6493749 | Valve Adjustment:High Temp |
| CV-24012 | 5/18/2026 2:50:00 PM | | | | | AtmAA |
| CV-24012 | 5/18/2026 2:41:34 PM | 28.52 | 1348 | 34.4361953 | -118.6493735 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24012 | 5/12/2026 2:38:30 PM | 28.58 | 1375 | 34.4361821 | -118.6493490 | Valve Adjustment:No Flow Measurement,High Temp |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24012 | 5/12/2026 2:20:00 PM | | | | | AtmAA |
| CV-24012 | 5/5/2026 1:30:00 PM | | | | | AtmAA |
| CV-24012 | 5/5/2026 1:30:00 PM | | | | | AtmAA; [User entered 16.47%] |
| CV-24012 | 5/5/2026 1:26:23 PM | 28.51 | 1358 | 34.4361692 | -118.6493705 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24013 | 5/26/2026 9:51:46 AM | 28.43 | 1382 | 34.4366035 | -118.6492483 | Valve Adjustment:High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-24013 | 5/13/2026 10:06:33 AM | 28.67 | 1364 | 34.4366058 | -118.6492207 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-24014 | 5/26/2026 1:42:04 PM | 28.4 | 1383 | 34.4367773 | -118.6489526 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24014 | 5/18/2026 2:15:00 PM | | | | | AtmAA |
| CV-24014 | 5/18/2026 2:07:26 PM | 28.52 | 1375 | 34.4367798 | -118.6489571 | Valve Adjustment:No Flow Measurement,High Temp,Reduce Sys. Vac. - Flare Down |
| CV-24014 | 5/12/2026 1:30:00 PM | | | | | AtmAA |
| CV-24014 | 5/12/2026 1:26:38 PM | 28.55 | 1362 | 34.4367858 | -118.6489631 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24014 | 5/12/2026 1:25:28 PM | 28.55 | 1363 | 34.4367876 | -118.6489603 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-24014 | 5/5/2026 10:10:00 AM | | | | | AtmAA |
| CV-24014 | 5/5/2026 10:10:00 AM | | | | | AtmAA; [User entered 19.01%] |
| CV-24014 | 5/5/2026 10:06:41 AM | 28.51 | 1367 | 34.4367698 | -118.6489586 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24015 | 5/26/2026 9:48:59 AM | 28.44 | 1373 | 34.4368709 | -118.6486048 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed |
| CV-24015 | 5/18/2026 10:08:30 AM | 28.51 | 1358 | 34.4368805 | -118.6486172 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp |
| CV-24015 | 5/18/2026 10:06:48 AM | 28.51 | 1358 | 34.4368807 | -118.6486171 | Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum |
| CV-24015 | 5/18/2026 10:05:03 AM | 28.51 | 1357 | 34.4368852 | -118.6486148 | Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down |
| CV-24015 | 5/18/2026 10:05:00 AM | | | | | AtmAA |
| CV-24015 | 5/12/2026 9:01:20 AM | 28.51 | 1364 | 34.4368432 | -118.6486216 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24015 | 5/12/2026 9:00:00 AM | | | | | AtmAA |
| CV-24015 | 5/12/2026 8:59:57 AM | 28.51 | 1364 | 34.4368432 | -118.6486216 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-24015 | 5/5/2026 9:14:20 AM | 28.5 | 1358 | 34.4368716 | -118.6486138 | Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open |
| CV-24015 | 5/5/2026 9:05:00 AM | | | | | AtmAA |
| CV-24015 | 5/5/2026 9:05:00 AM | | | | | AtmAA; [User entered 20.36%] |
| CV-24016 | 5/29/2026 9:27:07 AM | 28.64 | 1370 | 34.4359133 | -118.6502473 | Valve Adjustment:NSPS/EG CAI,High Temp,Valve 100% Open |
| CV-24016 | 5/27/2026 8:54:06 AM | 28.4 | 1366 | 34.4359104 | -118.6502344 | Valve Adjustment:No Flow Measurement,High Temp |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24016 | 5/19/2026 10:04:01 AM | 28.61 | 1345 | 34.4359238 | -118.6502128 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed |
| CV-24016 | 5/19/2026 10:02:01 AM | 28.6 | 1348 | 34.4359177 | -118.6502413 | Valve Adjustment:NSPS/EG CAI,High Temp;Well Condition:Lorentz Pump Installed |
| CV-24016 | 5/18/2026 3:00:00 PM | | | | | AtmAA |
| CV-24016 | 5/18/2026 2:51:00 PM | 28.51 | 1367 | 34.4359217 | -118.6502495 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24016 | 5/12/2026 2:44:41 PM | 28.56 | 1368 | 34.4359272 | -118.6502615 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24016 | 5/12/2026 2:30:00 PM | | | | | AtmAA |
| CV-24016 | 5/6/2026 1:26:28 PM | 28.63 | 1368 | 34.4359207 | -118.6502510 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24016 | 5/6/2026 1:25:16 PM | 28.63 | 1371 | 34.4359275 | -118.6502513 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24016 | 5/5/2026 1:15:29 PM | 28.51 | 1368 | 34.4359142 | -118.6502632 | Valve Adjustment:Audible Flow,No Flow Measurement,High Temp |
| CV-24016 | 5/5/2026 1:15:00 PM | | | | | AtmAA |
| CV-24016 | 5/5/2026 1:15:00 PM | | | | | AtmAA; [User entered 9.66%] |
| CV-24017 | 5/26/2026 2:08:15 PM | 28.4 | 1368 | 34.4361184 | -118.6498213 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24017 | 5/26/2026 2:07:20 PM | 28.4 | 1368 | 34.4361151 | -118.6498173 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-24017 | 5/18/2026 2:40:00 PM | | | | | AtmAA |
| CV-24017 | 5/18/2026 2:35:18 PM | 28.51 | 1364 | 34.4361053 | -118.6498081 | Valve Adjustment:No Flow Measurement,High Temp;Well Repairs:Surging |
| CV-24017 | 5/12/2026 2:47:32 PM | 28.56 | 1368 | 34.4361035 | -118.6498030 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header |
| CV-24017 | 5/12/2026 2:25:14 PM | 28.59 | 1378 | 34.4361164 | -118.6498165 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-24017 | 5/12/2026 2:10:00 PM | | | | | AtmAA |
| CV-24017 | 5/12/2026 8:35:00 AM | | | | | Air Tech Lab |
| CV-24017 | 5/12/2026 8:35:00 AM | | | | | Air Tech Lab; [User entered 19%] |
| CV-24017 | 5/5/2026 1:20:00 PM | | | | | AtmAA |
| CV-24017 | 5/5/2026 1:20:00 PM | | | | | AtmAA; [User entered 15.55%] |
| CV-24017 | 5/5/2026 1:19:34 PM | 28.51 | 1369 | 34.4361090 | -118.6498195 | Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open |
| CV-24018 | 5/29/2026 11:06:53 AM | 28.61 | 1362 | 34.4358020 | -118.6501282 | No Flow Measurement |
| CV-24018 | 5/13/2026 3:41:42 PM | 28.65 | 1362 | 34.4356148 | -118.6500517 | Valve Adjustment:No Flow Measurement,High Temp,Barely Open |
| CV-24019 | 5/27/2026 8:57:49 AM | 28.4 | 1361 | 34.4357838 | -118.6497704 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed |
| CV-24019 | 5/19/2026 8:35:00 AM | | | | | AtmAA |
| CV-24019 | 5/19/2026 8:31:39 AM | 28.59 | 1376 | 34.4357821 | -118.6497718 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24019 | 5/13/2026 2:09:27 PM | 28.67 | 1371 | 34.4357829 | -118.6497628 | Valve Adjustment:No Flow Measurement,High Temp |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24019 | 5/5/2026 2:30:00 PM | | | | | AtmAA |
| CV-24019 | 5/5/2026 2:30:00 PM | | | | | AtmAA; [User entered 14.18%] |
| CV-24019 | 5/5/2026 2:26:07 PM | 28.51 | 1364 | 34.4357752 | -118.6497640 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24020 | 5/26/2026 10:31:13 AM | 28.45 | 1352 | 34.4359950 | -118.6493380 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-24020 | 5/13/2026 1:39:38 PM | 28.64 | 1337 | 34.4359825 | -118.6493598 | Valve Adjustment:Barely Open |
| CV-24021 | 5/26/2026 10:19:45 AM | 28.43 | 1365 | 34.4361505 | -118.6490217 | Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-24021 | 5/13/2026 10:19:21 AM | 28.67 | 1355 | 34.4361580 | -118.6490435 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:valve possibly damaged |
| CV-24022-PLR | 5/26/2026 1:34:59 PM | 28.4 | 1377 | 34.4365365 | -118.6487855 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24022-PLR | 5/18/2026 2:10:00 PM | | | | | AtmAA |
| CV-24022-PLR | 5/18/2026 2:04:39 PM | 28.51 | 1377 | 34.4365219 | -118.6487899 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header |
| CV-24022-PLR | 5/12/2026 1:25:00 PM | | | | | AtmAA |
| CV-24022-PLR | 5/12/2026 1:18:18 PM | 28.55 | 1367 | 34.4365285 | -118.6487914 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24022-PLR | 5/5/2026 10:05:00 AM | | | | | AtmAA |
| CV-24022-PLR | 5/5/2026 10:05:00 AM | | | | | AtmAA; [User entered 19.92%] |
| CV-24022-PLR | 5/5/2026 10:03:55 AM | 28.51 | 1368 | 34.4365105 | -118.6488020 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24023 | 5/26/2026 10:02:11 AM | 28.47 | 1383 | 34.4365975 | -118.6484405 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp |
| CV-24023 | 5/26/2026 9:58:22 AM | 28.47 | 1377 | 34.4365949 | -118.6484358 | Valve Comment:LORENTZ PUMP ON UPON ARRIVAL;Valve Adjustment:No Flow Measurement,High Temp,High O2,Decreased Flow/Vacuum |
| CV-24023 | 5/18/2026 10:19:04 AM | 28.51 | 1364 | 34.4365803 | -118.6484551 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24023 | 5/18/2026 10:15:00 AM | 28.51 | 1363 | 34.4365788 | -118.6484547 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-24023 | 5/12/2026 8:52:20 AM | 28.51 | 1364 | 34.4365324 | -118.6484561 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24023 | 5/12/2026 8:51:10 AM | 28.51 | 1364 | 34.4365424 | -118.6484653 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-24023 | 5/12/2026 8:50:00 AM | | | | | AtmAA |
| CV-24023 | 5/6/2026 9:28:29 AM | 28.63 | 1372 | 34.4366013 | -118.6484405 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp,Valve 100% Open |
| CV-24023 | 5/6/2026 9:27:29 AM | 28.63 | 1373 | 34.4365940 | -118.6484368 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp,Valve 100% Open |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24023 | 5/5/2026 9:36:54 AM | 28.51 | 1361 | 34.4365952 | -118.6484455 | Valve Comment:Valve open 100 percent due to gas order around well head;Valve Adjustment:No Flow Measurement,Valve 100% Open |
| CV-24023 | 5/5/2026 9:35:20 AM | 28.51 | 1363 | 34.4365944 | -118.6484474 | Valve Comment:Valve open due to string gas order around well;Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum |
| CV-24023 | 5/5/2026 9:27:58 AM | 28.51 | 1362 | 34.4366107 | -118.6484539 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24023 | 5/5/2026 9:25:00 AM | | | | | AtmAA |
| CV-24023 | 5/5/2026 9:25:00 AM | | | | | AtmAA; [User entered 21.575%] |
| CV-24024-PLR | 5/18/2026 9:51:23 AM | 28.54 | 1362 | 34.4367984 | -118.6481306 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement |
| CV-24024-PLR | 5/15/2026 9:22:07 AM | 28.58 | 1346 | 34.4368165 | -118.6481413 | Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open,Surging Liquid in Header |
| CV-24024-PLR | 5/15/2026 9:20:22 AM | 28.58 | 1343 | 34.4368210 | -118.6481447 | Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open,Surging Liquid in Header |
| CV-24025 | 5/28/2026 2:28:43 PM | 28.51 | 1380 | 34.4352795 | -118.6499510 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24025 | 5/19/2026 9:27:53 AM | 28.62 | 1358 | 34.4352678 | -118.6500158 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp |
| CV-24025 | 5/19/2026 9:26:52 AM | 28.62 | 1357 | 34.4352661 | -118.6500248 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24025 | 5/19/2026 9:25:00 AM | | | | | AtmAA |
| CV-24025 | 5/13/2026 2:30:31 PM | 28.66 | 1356 | 34.4352715 | -118.6499506 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24025 | 5/6/2026 8:57:31 AM | 28.63 | 1359 | 34.4352857 | -118.6499268 | Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header |
| CV-24025 | 5/6/2026 8:56:37 AM | 28.63 | 1353 | 34.4352748 | -118.6499408 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum,Surging Liquid in Header |
| CV-24025 | 5/5/2026 2:13:13 PM | 28.51 | 1364 | 34.4352774 | -118.6499214 | Valve Adjustment:Audible Flow,No Flow Measurement,High Temp |
| CV-24025 | 5/5/2026 2:10:00 PM | | | | | AtmAA |
| CV-24025 | 5/5/2026 2:10:00 PM | | | | | AtmAA; [User entered 11.07%] |
| CV-24026 | 5/22/2026 12:25:54 PM | 28.54 | 1346 | 34.4356472 | -118.6492438 | Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Well (Watered In) |
| CV-24026 | 5/13/2026 1:43:47 PM | 28.64 | 1355 | 34.4356627 | -118.6492732 | Valve Adjustment:Barely Open |
| CV-24027 | 5/26/2026 10:11:09 AM | 28.45 | 1355 | 34.4361000 | -118.6487237 | Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-24027 | 5/13/2026 10:15:50 AM | 28.68 | 1354 | 34.4361152 | -118.6487245 | Valve Adjustment:Barely Open;Well Comment:Possible damaged valve |
| CV-24027 | 5/6/2026 9:11:56 AM | 28.63 | 1355 | 34.4361057 | -118.6487228 | Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum |
| CV-24028 | 5/26/2026 1:15:48 PM | 28.39 | 1366 | 34.4363415 | -118.6484647 | Valve Adjustment:High Temp |
| CV-24028 | 5/26/2026 1:13:13 PM | 28.4 | 1363 | 34.4363513 | -118.6484733 | Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24028 | 5/18/2026 2:05:00 PM | | | | | AtmAA |
| CV-24028 | 5/18/2026 2:01:26 PM | 28.52 | 1380 | 34.4363509 | -118.6484771 | Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down |
| CV-24028 | 5/12/2026 1:20:00 PM | | | | | AtmAA |
| CV-24028 | 5/12/2026 1:14:56 PM | 28.55 | 1355 | 34.4363597 | -118.6484690 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24028 | 5/5/2026 10:00:52 AM | 28.51 | 1365 | 34.4363421 | -118.6484743 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24028 | 5/5/2026 10:00:00 AM | | | | | AtmAA |
| CV-24028 | 5/5/2026 10:00:00 AM | | | | | AtmAA; [User entered 18.67%] |
| CV-24029 | 5/29/2026 11:19:30 AM | 28.6 | 1348 | 34.4364658 | -118.6480740 | NSPS/EG CAI,No Flow Measurement,High O2 |
| CV-24029 | 5/29/2026 11:15:41 AM | 28.6 | 1322 | 34.4364502 | -118.6480705 | NSPS/EG CAI,High O2 |
| CV-24029 | 5/13/2026 2:06:48 PM | 28.63 | 1358 | 34.4364448 | -118.6480895 | Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-24030 | 5/26/2026 9:14:08 AM | 28.47 | 1371 | 34.4366543 | -118.6478634 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24030 | 5/26/2026 9:07:52 AM | 28.47 | 1368 | 34.4366572 | -118.6478750 | Valve Comment:Lorentz pump running upon arrival;Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed |
| CV-24030 | 5/18/2026 9:35:03 AM | 28.52 | 1356 | 34.4366520 | -118.6478828 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp |
| CV-24030 | 5/18/2026 9:35:00 AM | | | | | AtmAA |
| CV-24030 | 5/12/2026 9:18:44 AM | 28.55 | 1350 | 34.4366654 | -118.6479217 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24030 | 5/12/2026 9:15:00 AM | | | | | AtmAA |
| CV-24030 | 5/5/2026 8:46:48 AM | 28.51 | 1340 | 34.4366447 | -118.6478811 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header |
| CV-24030 | 5/5/2026 8:45:00 AM | | | | | AtmAA |
| CV-24030 | 5/5/2026 8:45:00 AM | | | | | AtmAA; [User entered 17.26%] |
| CV-24030 | 5/5/2026 8:44:58 AM | 28.51 | 1337 | 34.4366473 | -118.6478843 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-24031 | 5/29/2026 1:15:41 PM | 28.58 | 1347 | 34.4349001 | -118.6498244 | Valve Comment:LORENTZ pump installed 052726;Valve Adjustment:No Flow Measurement,Valve 100% Open |
| CV-24031 | 5/22/2026 12:15:48 PM | 28.55 | 1352 | 34.4349038 | -118.6498248 | |
| CV-24031 | 5/22/2026 12:14:13 PM | 28.55 | 1355 | 34.4349185 | -118.6498527 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum |
| CV-24031 | 5/12/2026 1:32:07 PM | 28.58 | 1336 | 34.4349093 | -118.6498243 | Valve Adjustment:Barely Open |
| CV-24032 | 5/27/2026 9:19:07 AM | 28.43 | 1339 | 34.4351168 | -118.6496457 | Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Header |
| CV-24032 | 5/27/2026 9:17:20 AM | 28.43 | 1340 | 34.4351132 | -118.6496448 | Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Surging Liquid in Header |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24032 | 5/27/2026 9:09:02 AM | 28.43 | 1340 | 34.4351199 | -118.6496367 | Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum,Valve 100% Open,Surging Liquid in Header |
| CV-24032 | 5/24/2026 12:06:03 PM | 28.61 | 1358 | 34.4351178 | -118.6496545 | Valve Adjustment:High Temp,High O2;Well Condition:Lorentz Pump Installed |
| CV-24032 | 5/24/2026 12:02:54 PM | 28.61 | 1346 | 34.4351428 | -118.6496432 | Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed |
| CV-24032 | 5/19/2026 8:41:47 AM | 28.62 | 1339 | 34.4351149 | -118.6496034 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed |
| CV-24032 | 5/14/2026 10:31:39 AM | 28.6 | 1352 | 34.4351008 | -118.6496090 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum |
| CV-24032 | 5/13/2026 2:37:29 PM | 28.66 | 1352 | 34.4351149 | -118.6496664 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24032 | 5/5/2026 2:20:00 PM | | | | | AtmAA |
| CV-24032 | 5/5/2026 2:20:00 PM | | | | | AtmAA; [User entered 12.905%] |
| CV-24032 | 5/5/2026 2:17:41 PM | 28.51 | 1357 | 34.4351042 | -118.6496337 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24033 | 5/28/2026 2:24:12 PM | 28.55 | 1367 | 34.4353491 | -118.6494775 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24033 | 5/19/2026 8:45:00 AM | | | | | AtmAA |
| CV-24033 | 5/19/2026 8:39:24 AM | 28.62 | 1341 | 34.4353456 | -118.6494733 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed;Well Repairs:None |
| CV-24033 | 5/13/2026 2:17:00 PM | 28.69 | 1364 | 34.4353370 | -118.6494871 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24033 | 5/7/2026 1:00:00 PM | | | | | AtmAA; [User entered 17.1%] |
| CV-24033 | 5/7/2026 12:59:49 PM | 28.55 | 1350 | 34.4353420 | -118.6494736 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24033 | 5/7/2026 1:00:00 AM | | | | | AtmAA |
| CV-24034 | 5/18/2026 11:08:37 AM | 28.54 | 1364 | 34.4361225 | -118.6481087 | Valve Adjustment:No Flow Measurement |
| CV-24034 | 5/18/2026 11:06:51 AM | 28.54 | 1365 | 34.4361207 | -118.6481114 | Valve Adjustment:No Flow Measurement,Decreased Flow/Vacuum |
| CV-24034 | 5/12/2026 10:57:45 AM | 28.55 | 1359 | 34.4361182 | -118.6481212 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed |
| CV-24034 | 5/12/2026 10:55:50 AM | 28.55 | 1358 | 34.4361142 | -118.6481226 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-24034 | 5/12/2026 10:55:00 AM | | | | | AtmAA |
| CV-24034 | 5/5/2026 9:57:30 AM | 28.51 | 1358 | 34.4360973 | -118.6481208 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24034 | 5/5/2026 9:56:30 AM | 28.51 | 1358 | 34.4360973 | -118.6481207 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-24034 | 5/5/2026 9:55:00 AM | | | | | AtmAA |
| CV-24034 | 5/5/2026 9:55:00 AM | | | | | AtmAA; [User entered 16.63%] |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24035 | 5/26/2026 8:50:47 AM | 28.46 | 1378 | 34.4363895 | -118.6477156 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header |
| CV-24035 | 5/18/2026 9:10:00 AM | | | | | AtmAA |
| CV-24035 | 5/18/2026 9:05:47 AM | 28.49 | 1379 | 34.4364010 | -118.6477240 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In) |
| CV-24035 | 5/18/2026 9:03:47 AM | 28.47 | 1379 | 34.4363958 | -118.6477166 | Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum,Surging Liquid in Well (Watered In) |
| CV-24035 | 5/12/2026 9:40:00 AM | | | | | AtmAA |
| CV-24035 | 5/12/2026 9:31:35 AM | 28.51 | 1375 | 34.4363782 | -118.6477294 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24035 | 5/5/2026 8:25:00 AM | | | | | AtmAA |
| CV-24035 | 5/5/2026 8:25:00 AM | | | | | AtmAA; [User entered 14.245%] |
| CV-24035 | 5/5/2026 8:24:01 AM | 28.51 | 1366 | 34.4363744 | -118.6477236 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24036 | 5/29/2026 2:20:04 PM | 28.62 | 1345 | 34.4345244 | -118.6496871 | Valve Adjustment:No Flow Measurement |
| CV-24036 | 5/24/2026 11:45:25 AM | 28.64 | 1343 | 34.4344598 | -118.6497053 | Valve Comment:Pump active;Valve Adjustment:Valve 100% Open;Well Comment:loose lorentz fittings;Well Condition:Lorentz Pump Installed |
| CV-24036 | 5/13/2026 10:53:14 AM | 28.7 | 1340 | 34.4344478 | -118.6497045 | Valve Adjustment:Valve 100% Open |
| CV-24036 | 5/6/2026 8:46:55 AM | 28.65 | 1347 | 34.4344562 | -118.6497137 | Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Valve 100% Open |
| CV-24037 | 5/26/2026 9:09:53 AM | 28.45 | 1357 | 34.4347505 | -118.6494295 | Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed |
| CV-24037 | 5/26/2026 9:08:28 AM | 28.45 | 1352 | 34.4347423 | -118.6494345 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In) |
| CV-24037 | 5/12/2026 1:53:15 PM | 28.57 | 1331 | 34.4347705 | -118.6494507 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-24038 | 5/27/2026 9:29:33 AM | 28.44 | 1341 | 34.4350164 | -118.6488705 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24038 | 5/27/2026 9:27:49 AM | 28.43 | 1340 | 34.4350122 | -118.6488679 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-24038 | 5/19/2026 9:05:00 AM | | | | | AtmAA |
| CV-24038 | 5/19/2026 9:04:35 AM | 28.63 | 1337 | 34.4350133 | -118.6488771 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24038 | 5/19/2026 9:04:12 AM | 28.63 | 1337 | 34.4350135 | -118.6488774 | Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed |
| CV-24038 | 5/13/2026 2:51:36 PM | 28.69 | 1340 | 34.4350189 | -118.6488679 | Valve Comment:Lorentz pump disconnected;Valve Adjustment:No Flow Measurement,High Temp,Barely Open |
| CV-24038 | 5/13/2026 2:48:58 PM | 28.68 | 1342 | 34.4350140 | -118.6488769 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24038 | 5/6/2026 3:05:00 PM | | | | | AtmAA |
| CV-24038 | 5/6/2026 3:05:00 PM | | | | | AtmAA; [User entered 17.06%] |
| CV-24038 | 5/6/2026 3:04:57 PM | 28.59 | 1345 | 34.4350175 | -118.6488795 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Surging Liquid in Header |
| CV-24038 | 5/6/2026 3:04:21 PM | 28.59 | 1346 | 34.4350157 | -118.6488745 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header |
| CV-24039 | 5/22/2026 12:04:33 PM | 28.55 | 1352 | 34.4352908 | -118.6486837 | Valve Comment:Noticed temp going down when pump stopped pumping;Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open |
| CV-24039 | 5/22/2026 12:01:47 PM | 28.54 | 1348 | 34.4352890 | -118.6486822 | Valve Adjustment:NSPS/EG CAC,High Temp;Well Condition:Lorentz Pump Installed |
| CV-24039 | 5/22/2026 11:58:20 AM | 28.55 | 1350 | 34.4352938 | -118.6486770 | Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum,Barely Open;Well Comment:Pump is currently running;Well Condition:Lorentz Pump Installed |
| CV-24039 | 5/14/2026 1:31:24 PM | 28.68 | 1356 | 34.4352930 | -118.6486885 | |
| CV-24039 | 5/14/2026 1:29:39 PM | 28.7 | 1356 | 34.4353073 | -118.6486835 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In);Well Comment:no pump |
| CV-24040 | 5/29/2026 9:07:46 AM | 28.66 | 1356 | 34.4356347 | -118.6483737 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24040 | 5/29/2026 9:07:06 AM | 28.65 | 1359 | 34.4356512 | -118.6483928 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24040 | 5/29/2026 9:05:56 AM | 28.63 | 1358 | 34.4356437 | -118.6483768 | Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum |
| CV-24040 | 5/19/2026 10:40:23 AM | 28.71 | 1331 | 34.4356267 | -118.6483830 | |
| CV-24040 | 5/19/2026 10:38:38 AM | 28.69 | 1339 | 34.4356322 | -118.6483722 | Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In) |
| CV-24040 | 5/13/2026 1:35:35 PM | 28.75 | 1353 | 34.4356472 | -118.6483613 | |
| CV-24040 | 5/13/2026 1:32:34 PM | 28.74 | 1368 | 34.4356482 | -118.6483772 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-24041 | 5/26/2026 10:04:46 AM | 28.44 | 1340 | 34.4358410 | -118.6480238 | Valve Adjustment:High O2,Decreased Flow/Vacuum |
| CV-24041 | 5/8/2026 8:06:27 AM | 28.67 | 1378 | 34.4358953 | -118.6480235 | No Flow Measurement |
| CV-24042 | 5/26/2026 11:03:38 AM | 28.47 | 1374 | 34.4362450 | -118.6474583 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24042 | 5/26/2026 11:02:42 AM | 28.47 | 1373 | 34.4362468 | -118.6474609 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed |
| CV-24042 | 5/18/2026 10:55:00 AM | | | | | AtmAA |
| CV-24042 | 5/18/2026 10:47:52 AM | 28.51 | 1377 | 34.4362378 | -118.6474643 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24042 | 5/12/2026 10:15:58 AM | 28.51 | 1375 | 34.4362586 | -118.6474732 | Valve Adjustment:No Flow Measurement,High Temp |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24042 | 5/12/2026 10:15:09 AM | 28.52 | 1373 | 34.4362525 | -118.6474630 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-24042 | 5/12/2026 10:15:00 AM | | | | | AtmAA |
| CV-24042 | 5/7/2026 10:08:18 AM | 28.57 | 1372 | 34.4362599 | -118.6474627 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp |
| CV-24042 | 5/7/2026 10:06:45 AM | 28.55 | 1370 | 34.4362605 | -118.6474585 | Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Positive Static Press. |
| CV-24042 | 5/7/2026 10:05:00 AM | | | | | AtmAA |
| CV-24042 | 5/7/2026 10:05:00 AM | | | | | AtmAA; [User entered 13.94%] |
| CV-24043 | 5/22/2026 2:06:15 PM | 28.41 | 1332 | 34.4341498 | -118.6497102 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-24043 | 5/15/2026 8:55:16 AM | 28.58 | 1335 | 34.4341002 | -118.6497133 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open |
| CV-24044 | 5/26/2026 8:46:58 AM | 28.45 | 1346 | 34.4343868 | -118.6493960 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-24044 | 5/26/2026 8:42:07 AM | 28.45 | 1353 | 34.4343945 | -118.6493898 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-24044 | 5/8/2026 12:36:24 PM | 28.58 | 1355 | 34.4343787 | -118.6494215 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open |
| CV-24045 | 5/27/2026 9:33:35 AM | 28.43 | 1344 | 34.4347487 | -118.6490565 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24045 | 5/27/2026 9:32:48 AM | 28.43 | 1345 | 34.4347501 | -118.6490543 | Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum |
| CV-24045 | 5/19/2026 9:11:34 AM | 28.64 | 1344 | 34.4347503 | -118.6490607 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24045 | 5/19/2026 9:10:36 AM | 28.62 | 1344 | 34.4347378 | -118.6490730 | Valve Comment:Lorentz pump was off upon arrival;Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed |
| CV-24045 | 5/19/2026 9:10:00 AM | | | | | AtmAA |
| CV-24045 | 5/13/2026 2:58:14 PM | 28.66 | 1340 | 34.4347495 | -118.6490602 | Valve Comment:LORENTZ pump disconnected;Valve Adjustment:No Flow Measurement,High Temp |
| CV-24045 | 5/13/2026 2:56:09 PM | 28.69 | 1341 | 34.4347492 | -118.6490622 | Valve Adjustment:No Flow Measurement,Decreased Flow/Vacuum |
| CV-24045 | 5/6/2026 2:55:47 PM | 28.62 | 1348 | 34.4347539 | -118.6490799 | Valve Adjustment:High Temp |
| CV-24045 | 5/6/2026 2:54:58 PM | 28.59 | 1346 | 34.4347537 | -118.6490797 | Valve Adjustment:High Temp,Decreased Flow/Vacuum |
| CV-24045 | 5/6/2026 2:45:00 PM | | | | | AtmAA |
| CV-24045 | 5/6/2026 2:45:00 PM | | | | | AtmAA; [User entered 16.18%] |
| CV-24046 | 5/29/2026 1:33:04 PM | 28.59 | 1354 | 34.4350982 | -118.6483655 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,Undersized Lateral |
| CV-24046 | 5/29/2026 1:30:24 PM | 28.59 | 1352 | 34.4351048 | -118.6483724 | Valve Comment:Lorentz pump reconnect 0;Valve Adjustment:NSPS/EG CAI,No Flow Measurement,Increased Flow/Vacuum,Undersized Lateral;Well Condition:Lorentz Pump Installed |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24046 | 5/28/2026 11:56:16 AM | 28.5 | 1434 | 34.4350508 | -118.6483830 | |
| CV-24046 | 5/28/2026 11:54:22 AM | 28.5 | 1398 | 34.4350515 | -118.6483538 | |
| CV-24046 | 5/13/2026 10:32:28 AM | 28.77 | 1360 | 34.4350777 | -118.6483772 | Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-24048 | 5/20/2026 2:12:35 PM | 28.45 | 1361 | 34.4355523 | -118.6477917 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-24048 | 5/19/2026 10:25:00 AM | | | | | AtmAA |
| CV-24048 | 5/8/2026 8:14:16 AM | 28.61 | 1348 | 34.4355390 | -118.6477927 | Reduced System Vacuum,No Flow Measurement |
| CV-24049 | 5/26/2026 10:45:00 AM | 28.44 | 1380 | 34.4359386 | -118.6471949 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24049 | 5/26/2026 10:43:34 AM | 28.45 | 1380 | 34.4359428 | -118.6471880 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-24049 | 5/18/2026 10:35:00 AM | | | | | AtmAA |
| CV-24049 | 5/18/2026 10:30:56 AM | 28.51 | 1388 | 34.4359384 | -118.6471848 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24049 | 5/13/2026 8:10:00 AM | | | | | Air Tech Lab |
| CV-24049 | 5/13/2026 8:10:00 AM | | | | | Air Tech Lab; [User entered 16%] |
| CV-24049 | 5/11/2026 8:49:25 AM | 28.55 | 1385 | 34.4359557 | -118.6471904 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Valve 100% Open |
| CV-24049 | 5/11/2026 8:47:07 AM | 28.54 | 1383 | 34.4359487 | -118.6471819 | Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum,Valve 100% Open |
| CV-24049 | 5/4/2026 2:40:00 PM | | | | | AtmAA |
| CV-24049 | 5/4/2026 2:40:00 PM | | | | | AtmAA; [User entered 2.59%] |
| CV-24049 | 5/4/2026 2:36:19 PM | 28.51 | 1388 | 34.4359470 | -118.6471999 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24050 | 5/22/2026 2:16:54 PM | 28.45 | 1317 | 34.4337317 | -118.6499540 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-24050 | 5/11/2026 12:53:12 PM | 28.64 | 1302 | 34.4337362 | -118.6499635 | Well Comment:pump is off;Well Condition:Lorentz Pump Installed |
| CV-24051 | 5/26/2026 8:54:30 AM | 28.45 | 1350 | 34.4344503 | -118.6490243 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open |
| CV-24051 | 5/8/2026 12:45:09 PM | 28.56 | 1336 | 34.4344557 | -118.6490413 | Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| CV-24052 | 5/20/2026 2:26:23 PM | 28.45 | 1374 | 34.4350675 | -118.6480750 | Valve Adjustment:Valve 100% Open |
| CV-24052 | 5/13/2026 10:05:26 AM | 28.74 | 1371 | 34.4350958 | -118.6480640 | Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:No pump |
| CV-24053 | 5/20/2026 2:23:25 PM | 28.45 | 1356 | 34.4352577 | -118.6478027 | Valve Adjustment:Valve 100% Open |
| CV-24053 | 5/8/2026 8:18:44 AM | 28.6 | 1352 | 34.4352325 | -118.6477467 | No Flow Measurement |
| CV-24053 | 5/7/2026 8:40:00 AM | | | | | Air Tech Lab |
| CV-24053 | 5/7/2026 8:40:00 AM | | | | | Air Tech Lab; [User entered 0.53%] |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24054 | 5/26/2026 10:39:35 AM | 28.44 | 1392 | 34.4356337 | -118.6471827 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24054 | 5/26/2026 10:39:02 AM | 28.44 | 1392 | 34.4356330 | -118.6471816 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-24054 | 5/18/2026 10:30:00 AM | | | | | AtmAA |
| CV-24054 | 5/18/2026 10:27:38 AM | 28.51 | 1385 | 34.4356310 | -118.6471775 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24054 | 5/18/2026 10:26:19 AM | 28.51 | 1384 | 34.4356370 | -118.6471819 | Valve Adjustment:No Flow Measurement,Decreased Flow/Vacuum |
| CV-24054 | 5/11/2026 8:39:09 AM | 28.52 | 1382 | 34.4356357 | -118.6471822 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp |
| CV-24054 | 5/11/2026 8:36:54 AM | 28.53 | 1382 | 34.4356346 | -118.6471817 | Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum |
| CV-24054 | 5/4/2026 2:35:00 PM | | | | | AtmAA |
| CV-24054 | 5/4/2026 2:35:00 PM | | | | | AtmAA; [User entered 10.58%] |
| CV-24054 | 5/4/2026 2:34:03 PM | 28.51 | 1391 | 34.4356452 | -118.6471699 | Valve Adjustment:High Temp |
| CV-24054 | 5/4/2026 1:54:35 PM | 28.53 | 1378 | 34.4356480 | -118.6471992 | Valve Adjustment:High Temp |
| CV-24054 | 5/4/2026 1:51:53 PM | 28.53 | 1362 | 34.4356435 | -118.6471943 | Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp,Decreased Flow/Vacuum;Well Comment:secured flange |
| CV-24055 | 5/26/2026 9:28:17 AM | 28.41 | 1405 | 34.4358782 | -118.6469018 | Valve Adjustment:NSPS/EG CAI,High Temp,Reduce Sys. Vac. - Flare Down |
| CV-24055 | 5/26/2026 9:27:16 AM | 28.41 | 1410 | 34.4358615 | -118.6469028 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| CV-24055 | 5/13/2026 8:15:00 AM | | | | | Air Tech Lab |
| CV-24055 | 5/13/2026 8:15:00 AM | | | | | Air Tech Lab; [User entered 5.1%] |
| CV-24055 | 5/12/2026 1:49:20 PM | 28.63 | 1392 | 34.4358725 | -118.6469142 | Valve Adjustment:Surging Liquid in Header |
| CV-24055 | 5/12/2026 1:47:04 PM | 28.63 | 1385 | 34.4358793 | -118.6469185 | Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed |
| CV-24056 | 5/19/2026 12:46:55 PM | 28.63 | 1319 | 34.4332672 | -118.6501688 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-24056 | 5/1/2026 10:37:33 AM | 28.59 | 1321 | 34.4332728 | -118.6501477 | |
| CV-24057 | 5/22/2026 2:21:55 PM | 28.41 | 1331 | 34.4334750 | -118.6496503 | Valve Adjustment:High Temp |
| CV-24057 | 5/11/2026 1:01:48 PM | 28.64 | 1312 | 34.4334530 | -118.6496648 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed |
| CV-24057 | 5/11/2026 1:00:44 PM | 28.63 | 1312 | 34.4334618 | -118.6496457 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Comment:pump is off;Well Condition:Lorentz Pump Installed |
| CV-24058 | 5/22/2026 1:59:19 PM | 28.41 | 1349 | 34.4338122 | -118.6494655 | Valve Adjustment:Barely Open |
| CV-24058 | 5/11/2026 12:33:09 PM | 28.61 | 1318 | 34.4338030 | -118.6494458 | Valve Adjustment:Reduce Sys. Vac. - Flare Down;Well Comment:pump is on;Well Condition:Lorentz Pump Installed |
| CV-24059 | 5/22/2026 2:29:34 PM | 28.41 | 1339 | 34.4338205 | -118.6490560 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In) |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24059 | 5/4/2026 9:02:50 AM | 28.55 | 1341 | 34.4337565 | -118.6490662 | Valve Adjustment:NSPS/EG CAC,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed |
| CV-24059 | 5/4/2026 9:01:40 AM | 28.54 | 1341 | 34.4337645 | -118.6490708 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed |
| CV-24060 | 5/20/2026 1:29:27 PM | 28.5 | 1357 | 34.4340282 | -118.6488037 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open |
| CV-24060 | 5/4/2026 9:39:35 AM | 28.56 | 1339 | 34.4340373 | -118.6487870 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-24061 | 5/26/2026 11:38:49 AM | 28.52 | 1354 | 34.4343495 | -118.6486107 | Valve Adjustment:Audible Flow,Increased Flow/Vacuum |
| CV-24061 | 5/8/2026 12:59:31 PM | 28.56 | 1340 | 34.4343577 | -118.6486282 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| CV-24062 | 5/22/2026 11:10:33 AM | 28.47 | 1378 | 34.4345898 | -118.6480770 | High Temp,NSPS/EG CAI |
| CV-24062 | 5/22/2026 11:08:48 AM | 28.47 | 1319 | 34.4346125 | -118.6479535 | NSPS/EG CAI,High Temp |
| CV-24062 | 5/8/2026 1:05:26 PM | 28.53 | 1364 | 34.4345762 | -118.6481078 | Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| CV-24062 | 5/7/2026 8:17:00 AM | | | | | Air Tech Lab |
| CV-24062 | 5/7/2026 8:17:00 AM | | | | | Air Tech Lab; [User entered 8.0%] |
| CV-24062 | 5/4/2026 1:16:07 PM | 28.51 | 1358 | 34.4345824 | -118.6480800 | Valve Adjustment:High Temp |
| CV-24062 | 5/4/2026 1:15:00 PM | | | | | AtmAA |
| CV-24062 | 5/4/2026 1:15:00 PM | | | | | AtmAA; [User entered 5.61%] |
| CV-24063 | 5/28/2026 1:49:33 PM | 28.53 | 1380 | 34.4349771 | -118.6475687 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24063 | 5/20/2026 2:20:53 PM | 28.51 | 1378 | 34.4349368 | -118.6475152 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24063 | 5/14/2026 11:02:15 AM | 28.63 | 1385 | 34.4349507 | -118.6474972 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24063 | 5/14/2026 11:01:37 AM | 28.62 | 1385 | 34.4349488 | -118.6474944 | Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum |
| CV-24063 | 5/14/2026 11:00:00 AM | | | | | AtmAA |
| CV-24063 | 5/12/2026 8:20:00 AM | | | | | Air Tech Lab |
| CV-24063 | 5/12/2026 8:20:00 AM | | | | | Air Tech Lab; [User entered 12%] |
| CV-24063 | 5/4/2026 1:35:00 PM | | | | | AtmAA |
| CV-24063 | 5/4/2026 1:35:00 PM | | | | | AtmAA; [User entered 7.16%] |
| CV-24063 | 5/4/2026 1:34:44 PM | 28.51 | 1366 | 34.4349530 | -118.6475245 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24063 | 5/4/2026 1:33:24 PM | 28.51 | 1367 | 34.4349536 | -118.6475298 | Valve Adjustment:High Temp,Decreased Flow/Vacuum |
| CV-24064 | 5/28/2026 2:15:41 PM | 28.55 | | | | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24064 | 5/27/2026 1:55:09 PM | 28.4 | 1370 | 34.4352364 | -118.6471357 | Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Well (Watered In) |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24064 | 5/19/2026 1:40:00 PM | | | | | AtmAA |
| CV-24064 | 5/19/2026 1:36:22 PM | 28.6 | 1383 | 34.4352506 | -118.6471800 | Valve Comment:Active PLR observed;Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In) |
| CV-24064 | 5/12/2026 8:15:00 AM | | | | | Air Tech Lab; [User entered 13%] |
| CV-24064 | 5/11/2026 10:07:41 AM | 28.55 | 1377 | 34.4352204 | -118.6471643 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24064 | 5/4/2026 9:10:00 AM | | | | | AtmAA |
| CV-24064 | 5/4/2026 9:10:00 AM | | | | | AtmAA; [User entered 11.1%] |
| CV-24064 | 5/4/2026 9:09:33 AM | 28.55 | 1376 | 34.4352502 | -118.6471611 | Valve Adjustment:High Temp,Valve 100% Open |
| CV-24065-TP1 | 5/22/2026 10:27:26 AM | 28.37 | 1384 | 34.4356133 | -118.6467967 | Valve Adjustment:Barely Open |
| CV-24065-TP1 | 5/12/2026 8:15:00 AM | | | | | Air Tech Lab |
| CV-24065-TP1 | 5/11/2026 1:07:25 PM | 28.52 | 1384 | 34.4356297 | -118.6468193 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| CV-24065-TP1 | 5/7/2026 8:35:00 AM | | | | | Air Tech Lab |
| CV-24065-TP1 | 5/7/2026 8:35:00 AM | | | | | Air Tech Lab; [User entered 0.98%] |
| CV-24066 | 5/19/2026 12:41:10 PM | 28.6 | 1317 | 34.4330187 | -118.6498118 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-24066 | 5/11/2026 7:45:00 AM | | | | | Air Tech Lab |
| CV-24066 | 5/11/2026 7:45:00 AM | | | | | Air Tech Lab; [User entered 3.2%] |
| CV-24066 | 5/1/2026 10:40:05 AM | 28.59 | 1331 | 34.4330032 | -118.6498153 | Valve Adjustment:Audible Flow;Well Condition:Good |
| CV-24067 | 5/26/2026 2:27:02 PM | 28.43 | 1343 | 34.4332042 | -118.6497463 | Valve Adjustment:High Temp |
| CV-24067 | 5/26/2026 2:26:30 PM | 28.43 | 1342 | 34.4332086 | -118.6497617 | Valve Adjustment:High Temp,Decreased Flow/Vacuum |
| CV-24067 | 5/19/2026 8:57:43 AM | 28.64 | 1327 | 34.4331898 | -118.6497188 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed |
| CV-24067 | 5/19/2026 8:55:05 AM | 28.63 | 1332 | 34.4331923 | -118.6497198 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Comment:Lorentz deactivated;Well Condition:Pnumatic Pump Installed |
| CV-24067 | 5/14/2026 11:37:11 AM | 28.54 | 1257 | 34.4332052 | -118.6499145 | |
| CV-24067 | 5/14/2026 11:35:44 AM | 28.54 | 1296 | 34.4331593 | -118.6496722 | High Temp,Positive Static Press. |
| CV-24068 | 5/26/2026 12:08:57 PM | 28.44 | 1369 | 34.4332578 | -118.6493013 | Valve Adjustment:NSPS/EG CAC,Reduce Sys. Vac. - Flare Down |
| CV-24068 | 5/26/2026 12:06:40 PM | 28.44 | 1368 | 34.4332655 | -118.6493125 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down |
| CV-24068 | 5/1/2026 11:18:00 AM | 28.57 | 1334 | 34.4332443 | -118.6493508 | Valve Adjustment:Audible Flow,Decreased Flow/Vacuum |
| CV-24069 | 5/28/2026 9:36:45 AM | 28.53 | 1354 | 34.4334167 | -118.6489192 | |
| CV-24069 | 5/28/2026 9:35:46 AM | 28.53 | 1352 | 34.4334167 | -118.6489207 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-24069 | 5/28/2026 9:30:09 AM | 28.53 | 1347 | 34.4334175 | -118.6489218 | Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum;Well Comment:Needs silicone for lorentz fittings;Well Condition:Lorentz Pump Installed;Well Repairs:Sample Port |
| CV-24069 | 5/13/2026 8:20:00 AM | | | | | Air Tech Lab |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24069 | 5/13/2026 8:20:00 AM | | | | | Air Tech Lab; [User entered 4.0%] |
| CV-24069 | 5/4/2026 8:56:06 AM | 28.56 | 1355 | 34.4334273 | -118.6489272 | Valve Comment:No system port;Valve Adjustment:Barely Open |
| CV-24070 | 5/20/2026 2:35:15 PM | 28.48 | 1350 | 34.4337308 | -118.6486893 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24070 | 5/20/2026 2:34:29 PM | 28.48 | 1350 | 34.4337250 | -118.6486983 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24070 | 5/20/2026 2:33:43 PM | 28.49 | 1349 | 34.4337250 | -118.6486995 | Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum,Decreased Flow/Vacuum |
| CV-24070 | 5/7/2026 8:20:00 AM | | | | | Air Tech Lab |
| CV-24070 | 5/7/2026 8:20:00 AM | | | | | Air Tech Lab; [User entered 11%] |
| CV-24070 | 5/4/2026 9:12:35 AM | 28.53 | 1349 | 34.4337133 | -118.6487107 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed |
| CV-24070 | 5/4/2026 9:11:52 AM | 28.55 | 1339 | 34.4337148 | -118.6486890 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum |
| CV-24071 | 5/20/2026 1:35:21 PM | 28.5 | 1355 | 34.4340125 | -118.6484803 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-24071 | 5/7/2026 8:10:00 AM | | | | | Air Tech Lab |
| CV-24071 | 5/7/2026 8:10:00 AM | | | | | Air Tech Lab; [User entered 2.4%] |
| CV-24071 | 5/4/2026 9:43:04 AM | 28.55 | 1335 | 34.4340043 | -118.6484677 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-24072 | 5/22/2026 2:05:23 PM | 28.37 | 1358 | 34.4341827 | -118.6480535 | |
| CV-24072 | 5/4/2026 2:18:34 PM | 28.51 | 1365 | 34.4342068 | -118.6480500 | Valve Adjustment:NSPS/EG CAC,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed |
| CV-24072 | 5/4/2026 2:17:08 PM | 28.51 | 1372 | 34.4342030 | -118.6480527 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed |
| CV-24073-TP1 | 5/26/2026 8:45:28 AM | 28.41 | 1368 | 34.4346367 | -118.6477108 | Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| CV-24073-TP1 | 5/26/2026 8:40:41 AM | 28.41 | 1377 | 34.4346343 | -118.6476967 | Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| CV-24073-TP1 | 5/8/2026 1:15:17 PM | 28.52 | 1365 | 34.4346693 | -118.6477383 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| CV-24073-TP1 | 5/6/2026 2:09:30 PM | 28.57 | 1381 | 34.4346688 | -118.6476972 | Valve Adjustment:Barely Open,Surging Liquid in Header |
| CV-24074 | 5/22/2026 11:17:05 AM | 28.41 | 1377 | 34.4347428 | -118.6473987 | Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-24074 | 5/6/2026 2:14:23 PM | 28.59 | 1395 | 34.4347680 | -118.6474127 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-24075-TP1 | 5/29/2026 4:03:35 PM | 28.6 | 1366 | 34.4350455 | -118.6471355 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24075-TP1 | 5/29/2026 4:02:17 PM | 28.59 | 1377 | 34.4350263 | -118.6471377 | Valve Adjustment:NSPS/EG CAI,High Temp |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24075-TP1 | 5/11/2026 10:25:13 AM | 28.55 | 1381 | 34.4350370 | -118.6471396 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24075-TP1 | 5/4/2026 9:21:41 AM | 28.53 | 1378 | 34.4350223 | -118.6471194 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24075-TP1 | 5/4/2026 9:20:10 AM | 28.54 | 1377 | 34.4350236 | -118.6471164 | Valve Comment:Updated photo on etools;Valve Adjustment:Audible Flow,High Temp |
| CV-24075-TP1 | 5/4/2026 9:20:00 AM | | | | | AtmAA |
| CV-24075-TP1 | 5/4/2026 9:20:00 AM | | | | | AtmAA; [User entered 11.47%] |
| CV-24076 | 5/27/2026 2:11:24 PM | 28.39 | 1380 | 34.4353005 | -118.6468888 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24076 | 5/19/2026 1:30:00 PM | | | | | AtmAA |
| CV-24076 | 5/19/2026 1:22:53 PM | 28.58 | 1390 | 34.4353297 | -118.6468739 | Valve Adjustment:High Temp |
| CV-24076 | 5/14/2026 10:30:00 AM | | | | | AtmAA |
| CV-24076 | 5/14/2026 10:29:35 AM | 28.61 | 1388 | 34.4353232 | -118.6468753 | Valve Adjustment:High Temp |
| CV-24076 | 5/4/2026 9:06:09 AM | 28.5 | 1388 | 34.4353236 | -118.6468707 | Valve Adjustment:High Temp |
| CV-24076 | 5/4/2026 9:05:00 AM | | | | | AtmAA |
| CV-24076 | 5/4/2026 9:05:00 AM | | | | | AtmAA; [User entered 6.27%] |
| CV-24077 | 5/28/2026 9:18:10 AM | 28.55 | 1332 | 34.4326474 | -118.6493044 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24077 | 5/28/2026 9:16:41 AM | 28.55 | 1328 | 34.4326327 | -118.6493094 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24077 | 5/20/2026 8:03:01 AM | 28.55 | 1334 | 34.4326904 | -118.6493079 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24077 | 5/11/2026 1:38:12 PM | 28.56 | 1342 | 34.4327189 | -118.6493015 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24077 | 5/7/2026 10:50:33 AM | 28.6 | 1335 | 34.4327056 | -118.6493251 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24077 | 5/7/2026 10:50:00 AM | | | | | AtmAA |
| CV-24077 | 5/7/2026 10:50:00 AM | | | | | AtmAA; [User entered 7.22%] |
| CV-24077 | 5/1/2026 10:03:08 AM | 28.59 | 1345 | 34.4326660 | -118.6493097 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24077 | 5/1/2026 10:01:59 AM | 28.59 | 1339 | 34.4326713 | -118.6492955 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum |
| CV-24078 | 5/19/2026 8:40:05 AM | 28.62 | 1328 | 34.4328908 | -118.6494320 | Well Condition:Pnumatic Pump Installed |
| CV-24078 | 5/19/2026 8:35:10 AM | 28.64 | 1330 | 34.4329108 | -118.6494308 | |
| CV-24078 | 5/19/2026 8:34:05 AM | 28.61 | 1331 | 34.4329042 | -118.6494297 | Valve Adjustment:Increased Flow/Vacuum |
| CV-24078 | 5/19/2026 8:31:45 AM | 28.62 | 1340 | 34.4328927 | -118.6494255 | Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp,Decreased Flow/Vacuum |
| CV-24078 | 5/1/2026 10:43:48 AM | 28.59 | 1324 | 34.4328913 | -118.6494548 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-24079-TP8 | 5/26/2026 12:13:32 PM | 28.42 | 1355 | 34.4329835 | -118.6491168 | Valve Adjustment:NSPS/EG CAI,High Temp,Reduce Sys. Vac. - Flare Down |
| CV-24079-TP8 | 5/26/2026 12:12:54 PM | 28.43 | 1359 | 34.4329778 | -118.6491177 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down;Well Comment:no system port |
| CV-24079-TP8 | 5/11/2026 1:15:47 PM | 28.55 | 1356 | 34.4329902 | -118.6491389 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24079-TP8 | 5/7/2026 10:41:06 AM | 28.59 | 1358 | 34.4329826 | -118.6491345 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24079-TP8 | 5/7/2026 10:40:00 AM | | | | | AtmAA |
| CV-24079-TP8 | 5/7/2026 10:40:00 AM | | | | | AtmAA; [User entered 11.17%] |
| CV-24079-TP8 | 5/7/2026 10:38:33 AM | 28.59 | 1355 | 34.4329762 | -118.6491333 | Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum |
| CV-24079-TP8 | 5/1/2026 11:22:57 AM | 28.58 | 1344 | 34.4329862 | -118.6491275 | Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open;Well Comment:no system port;Well Repairs:Sample Port |
| CV-24079-TP8 | 5/1/2026 11:22:12 AM | 28.59 | 1347 | 34.4329890 | -118.6491312 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum |
| CV-24080 | 5/21/2026 9:36:06 AM | 28.5 | 1362 | 34.4331173 | -118.6488748 | Valve Adjustment:Reduce Sys. Vac. - Flare Down |
| CV-24080 | 5/1/2026 11:09:29 AM | 28.56 | 1348 | 34.4331390 | -118.6488647 | Valve Adjustment:Barely Open |
| CV-24081-TP1 | 5/20/2026 2:26:51 PM | 28.48 | 1356 | 34.4334105 | -118.6485840 | Valve Adjustment:NSPS/EG CAC,Barely Open |
| CV-24081-TP1 | 5/20/2026 2:25:55 PM | 28.48 | 1363 | 34.4334093 | -118.6485960 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum |
| CV-24081-TP1 | 5/14/2026 10:40:33 AM | 28.71 | 1371 | 34.4334155 | -118.6485893 | Valve Adjustment:Audible Flow |
| CV-24082 | 5/20/2026 11:24:26 AM | 28.49 | 1368 | 34.4334317 | -118.6483515 | Valve Adjustment:Barely Open |
| CV-24082 | 5/4/2026 10:11:50 AM | 28.52 | 1365 | 34.4334228 | -118.6483313 | Valve Adjustment:Barely Open |
| CV-24083 | 5/20/2026 1:53:17 PM | 28.48 | 1353 | 34.4337110 | -118.6483582 | Valve Adjustment:Barely Open |
| CV-24083 | 5/4/2026 9:58:27 AM | 28.54 | 1346 | 34.4337138 | -118.6483420 | Valve Adjustment:NSPS/EG CAC,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed |
| CV-24083 | 5/4/2026 9:56:08 AM | 28.52 | 1345 | 34.4337090 | -118.6483427 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed |
| CV-24084-TP1 | 5/27/2026 10:49:57 AM | 28.41 | 1368 | 34.4338457 | -118.6480631 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed |
| CV-24084-TP1 | 5/19/2026 10:24:00 AM | 28.62 | 1364 | 34.4338432 | -118.6480344 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed |
| CV-24084-TP1 | 5/11/2026 1:05:39 PM | 28.55 | 1373 | 34.4338529 | -118.6480455 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24084-TP1 | 5/4/2026 2:08:40 PM | 28.52 | 1368 | 34.4338595 | -118.6480247 | Valve Adjustment:Audible Flow,High Temp |
| CV-24084-TP1 | 5/4/2026 2:05:00 PM | | | | | AtmAA |
| CV-24084-TP1 | 5/4/2026 2:05:00 PM | | | | | [User entered 7.74%] |
| CV-24085 | 5/20/2026 10:07:30 AM | 28.5 | 1355 | 34.4323445 | -118.6490410 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-24085 | 5/1/2026 10:47:32 AM | 28.58 | 1342 | 34.4323853 | -118.6490165 | Valve Adjustment:Audible Flow,Barely Open |
| CV-24086 | 5/21/2026 9:49:26 AM | 28.48 | 1364 | 34.4328970 | -118.6486888 | Valve Adjustment:Barely Open,Reduce Sys. Vac. - Flare Down |
| CV-24086 | 5/1/2026 11:00:38 AM | 28.52 | 1368 | 34.4328965 | -118.6486832 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-24087 | 5/20/2026 1:36:05 PM | 28.49 | 1376 | 34.4329980 | -118.6481118 | Valve Adjustment:Reduce Sys. Vac. - Flare Down;Well Repairs:Sample Port |
| CV-24087 | 5/5/2026 10:43:05 AM | 28.53 | 1382 | 34.4329827 | -118.6481162 | Valve Adjustment:Increased Flow/Vacuum;Well Comment:Pump powered off;Well Condition:Lorentz Pump Installed |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24088 | 5/28/2026 9:04:04 AM | 28.49 | 1375 | 34.4335852 | -118.6476383 | |
| CV-24088 | 5/4/2026 1:51:55 PM | 28.49 | 1378 | 34.4335923 | -118.6476597 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-24089 | 5/20/2026 11:52:44 AM | 28.47 | 1352 | 34.4324820 | -118.6480715 | |
| CV-24089 | 5/20/2026 11:51:37 AM | 28.47 | 1362 | 34.4323997 | -118.6480543 | |
| CV-24089 | 5/4/2026 11:15:57 AM | 28.5 | 1302 | 34.4323563 | -118.6481493 | |
| CV-24089 | 5/4/2026 11:14:40 AM | 28.5 | 1332 | 34.4323818 | -118.6481067 | |
| CV-24090 | 5/20/2026 11:45:41 AM | 28.47 | 1322 | 34.4326190 | -118.6475223 | |
| CV-24090 | 5/11/2026 1:42:21 PM | 28.6 | 1374 | 34.4327105 | -118.6475508 | Valve Adjustment:Reduce Sys. Vac. - Flare Down;Well Comment:Pump is off;Well Condition:Lorentz Pump Installed |
| CV-24090 | 5/6/2026 1:52:09 PM | 28.63 | 1370 | 34.4326720 | -118.6475278 | Valve Adjustment:Increased Flow/Vacuum,Barely Open |
| CV-24091 | 5/21/2026 9:33:38 AM | 28.43 | 1382 | 34.4329842 | -118.6469030 | Valve Adjustment:Barely Open,Surging Liquid in Header |
| CV-24091 | 5/4/2026 2:15:54 PM | 28.47 | 1371 | 34.4330193 | -118.6468302 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-24092 | 5/6/2026 10:10:24 AM | 28.55 | 1424 | 34.4332727 | -118.6460750 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-24093 | 5/22/2026 12:11:17 PM | 28.37 | 1417 | 34.4340752 | -118.6463935 | |
| CV-24093 | 5/1/2026 3:13:57 PM | 28.4 | 1388 | 34.4340903 | -118.6463495 | |
| CV-24094 | 5/22/2026 11:49:38 AM | 28.38 | 1421 | 34.4346182 | -118.6461232 | |
| CV-24094 | 5/22/2026 11:48:00 AM | 28.38 | 1470 | 34.4345230 | -118.6460360 | NSPS/EG CAI,High O2 |
| CV-24094 | 5/1/2026 2:32:48 PM | 28.48 | 1391 | 34.4346042 | -118.6461873 | |
| CV-24095 | 5/28/2026 10:32:51 AM | 28.66 | 1272 | 34.4334012 | -118.6513128 | Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Surging Liquid in Header |
| CV-24095 | 5/28/2026 10:30:18 AM | 28.66 | 1269 | 34.4334028 | -118.6513053 | Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press. |
| CV-24095 | 5/20/2026 10:30:33 AM | 28.66 | 1266 | 34.4333957 | -118.6513129 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24095 | 5/14/2026 1:28:11 PM | 28.67 | 1252 | 34.4334130 | -118.6512927 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Header |
| CV-24095 | 5/13/2026 10:56:02 AM | 28.8 | 1255 | 34.4334041 | -118.6512937 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header;Well Condition:Lorentz Pump Installed |
| CV-24095 | 5/13/2026 10:53:04 AM | 28.8 | 1255 | 34.4334028 | -118.6512965 | Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Positive Static Press.,Surging Liquid in Header |
| CV-24095 | 5/6/2026 10:46:15 AM | 28.74 | 1258 | 34.4334102 | -118.6512981 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header |
| CV-24095 | 5/6/2026 10:45:00 AM | | | | | AtmAA |
| CV-24095 | 5/6/2026 10:45:00 AM | | | | | AtmAA; [User entered 10.84%] |
| CV-24095 | 5/6/2026 8:05:00 AM | | | | | Air Tech Lab |
| CV-24095 | 5/6/2026 8:05:00 AM | | | | | Air Tech Lab; [User entered 16%] |
| CV-24096 | 5/20/2026 10:19:24 AM | 28.67 | 1246 | 34.4332235 | -118.6515798 | Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24096 | 5/12/2026 9:25:00 AM | 28.66 | 1253 | 34.4332257 | -118.6515815 | NSPS/EG CAI,High O2 |
| CV-24096 | 5/12/2026 9:22:51 AM | 28.66 | 1253 | 34.4331845 | -118.6515720 | NSPS/EG CAI,High O2 |
| CV-24097 | 5/20/2026 10:29:27 AM | 28.66 | 1248 | 34.4327990 | -118.6515542 | Valve Adjustment:Barely Open |
| CV-24097 | 5/20/2026 10:28:10 AM | 28.64 | 1250 | 34.4327950 | -118.6515487 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-24097 | 5/12/2026 9:16:39 AM | 28.65 | 1257 | 34.4327837 | -118.6516297 | NSPS/EG CAC,No Adjustment Made |
| CV-24097 | 5/12/2026 9:13:02 AM | 28.65 | 1253 | 34.4327735 | -118.6515830 | NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 to 1 Turn |
| CV-24098 | 5/20/2026 10:43:25 AM | 28.66 | 1253 | 34.4325087 | -118.6513128 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-24098 | 5/3/2026 11:01:16 AM | 28.67 | 1254 | 34.4325280 | -118.6512995 | Valve Adjustment:Surging Liquid in Header;Well Condition:Pnumatic Pump Installed |
| CV-24098 | 5/3/2026 11:00:24 AM | 28.65 | 1266 | 34.4324950 | -118.6513277 | Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header;Well Comment:pump fitting needs silicone to cover hole;Well Condition:Pnumatic Pump Installed |
| CV-24098 | 5/1/2026 10:01:03 AM | 28.67 | 1248 | 34.4325082 | -118.6513058 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header;Well Comment:valve stuck open |
| CV-24099 | 5/20/2026 10:48:09 AM | 28.65 | 1256 | 34.4323452 | -118.6509390 | |
| CV-24099 | 5/3/2026 10:28:51 AM | 28.67 | 1255 | 34.4323340 | -118.6509515 | Well Condition:Lorentz Pump Installed |
| CV-24099 | 5/3/2026 10:28:19 AM | 28.68 | 1249 | 34.4323572 | -118.6509205 | Valve Adjustment:Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed |
| CV-24099 | 5/3/2026 10:27:26 AM | 28.65 | 1250 | 34.4323625 | -118.6509200 | Valve Adjustment:NSPS/EG CAC,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed |
| CV-24099 | 5/1/2026 10:08:04 AM | 28.64 | 1263 | 34.4323107 | -118.6509303 | Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:valve stuck open |
| CV-24100 | 5/28/2026 10:02:06 AM | 28.66 | 1264 | 34.4320513 | -118.6504732 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24100 | 5/20/2026 10:01:19 AM | 28.66 | 1264 | 34.4320458 | -118.6504860 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp |
| CV-24100 | 5/20/2026 10:00:42 AM | 28.67 | 1264 | 34.4320402 | -118.6504845 | Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum |
| CV-24100 | 5/20/2026 9:37:52 AM | 28.64 | 1268 | 34.4320515 | -118.6504765 | Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header |
| CV-24100 | 5/20/2026 9:36:36 AM | 28.63 | 1265 | 34.4320508 | -118.6504777 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header |
| CV-24100 | 5/13/2026 10:42:49 AM | 28.8 | 1266 | 34.4320420 | -118.6504906 | Valve Adjustment:No Flow Measurement;Well Condition:Lorentz Pump Installed |
| CV-24100 | 5/13/2026 10:41:16 AM | 28.8 | 1264 | 34.4320422 | -118.6505012 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-24100 | 5/13/2026 8:25:00 AM | | | | | Air Tech Lab |
| CV-24100 | 5/13/2026 8:25:00 AM | | | | | Air Tech Lab; [User entered 0.88%] |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24100 | 5/7/2026 11:06:06 AM | 28.66 | 1272 | 34.4320301 | -118.6504915 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp |
| CV-24100 | 5/7/2026 11:05:00 AM | | | | | AtmAA |
| CV-24100 | 5/7/2026 11:05:00 AM | | | | | AtmAA; [User entered 0.85%] |
| CV-24100 | 5/7/2026 11:04:29 AM | 28.66 | 1273 | 34.4320234 | -118.6504902 | Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum |
| CV-24100 | 5/1/2026 10:25:18 AM | 28.64 | 1261 | 34.4320483 | -118.6504928 | Valve Adjustment:High Temp,Barely Open |
| CV-24101 | 5/20/2026 9:41:50 AM | 28.64 | 1261 | 34.4318263 | -118.6502997 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-24101 | 5/12/2026 8:51:03 AM | 28.65 | 1270 | 34.4318035 | -118.6502830 | No Flow Measurement |
| CV-24101 | 5/6/2026 7:40:00 AM | | | | | Air Tech Lab |
| CV-24101 | 5/6/2026 7:40:00 AM | | | | | Air Tech Lab; [User entered 0.094%] |
| CV-24101 | 5/1/2026 10:20:22 AM | 28.64 | 1261 | 34.4318222 | -118.6502932 | Valve Adjustment:Valve 100% Open |
| CV-24102 | 5/19/2026 10:30:38 AM | 28.69 | 1269 | 34.4316293 | -118.6497903 | |
| CV-24102 | 5/4/2026 9:42:22 AM | 28.64 | 1267 | 34.4316275 | -118.6497782 | Valve Adjustment:Barely Open |
| CV-24103 | 5/20/2026 9:42:52 AM | 28.6 | 1234 | 34.4316590 | -118.6488628 | |
| CV-24103 | 5/4/2026 9:28:18 AM | 28.53 | 1322 | 34.4316217 | -118.6488557 | |
| CV-24104 | 5/20/2026 12:16:58 PM | 28.47 | 1325 | 34.4318087 | -118.6479883 | |
| CV-24104 | 5/4/2026 9:39:11 AM | 28.5 | 1283 | 34.4318737 | -118.6481208 | |
| CV-24105 | 5/20/2026 11:35:42 AM | 28.48 | 1368 | 34.4318890 | -118.6476013 | |
| CV-24105 | 5/4/2026 9:49:47 AM | 28.51 | 1319 | 34.4318910 | -118.6475968 | |
| CV-24106 | 5/28/2026 12:51:23 PM | 28.56 | 1335 | 34.4321138 | -118.6467300 | Valve Comment:RES SEM;Well Comment:Cover compaction |
| CV-24106 | 5/20/2026 2:33:03 PM | 28.42 | 1352 | 34.4320953 | -118.6465760 | |
| CV-24106 | 5/8/2026 11:07:42 AM | 28.64 | 1388 | 34.4322112 | -118.6467370 | Reduced System Vacuum |
| CV-24107 | 5/4/2026 11:30:05 AM | 28.59 | 1322 | 34.4325508 | -118.6461547 | Valve Adjustment:Audible Flow,Decreased Flow/Vacuum |
| CV-24108 | 5/28/2026 12:33:54 PM | 28.52 | 1359 | 34.4331548 | -118.6454345 | Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum |
| CV-24108 | 5/4/2026 1:40:16 PM | 28.56 | 1363 | 34.4331720 | -118.6454428 | Valve Adjustment:Orifice Plate Changed (See OP Log),Audible Flow,Barely Open |
| CV-24109 | 5/4/2026 11:58:26 AM | 28.52 | 1380 | 34.4340122 | -118.6448770 | Valve Adjustment:Audible Flow,Decreased Flow/Vacuum |
| CV-24110 | 5/1/2026 10:54:33 AM | 28.46 | 1378 | 34.4345913 | -118.6446387 | |
| CV-24111 | 5/1/2026 11:14:00 AM | 28.45 | 1391 | 34.4352950 | -118.6450367 | |
| CV-24112 | 5/1/2026 11:04:34 AM | 28.46 | 1362 | 34.4351683 | -118.6441708 | |
| CV-24114 | 5/5/2026 2:47:36 PM | 28.55 | 1234 | 34.4308157 | -118.6485657 | |
| CV-24116 | 5/11/2026 9:58:53 AM | 28.62 | 1266 | 34.4317012 | -118.6458438 | |
| CV-24117 | 5/28/2026 12:44:53 PM | 28.59 | 1298 | 34.4323422 | -118.6449403 | Valve Comment:RES SEM;Valve Adjustment:Audible Flow;Well Comment:Cover compaction |
| CV-24117 | 5/4/2026 10:48:48 AM | 28.64 | 1294 | 34.4323543 | -118.6449448 | Valve Adjustment:Audible Flow,Barely Open;Well Condition:Good |
| CV-24118 | 5/11/2026 1:37:44 PM | 28.6 | 1309 | 34.4333127 | -118.6438447 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24119 | 5/8/2026 2:33:20 PM | 28.64 | 1253 | 34.4337265 | -118.6423345 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open |
| CV-24119 | 5/8/2026 2:32:34 PM | 28.64 | 1253 | 34.4337367 | -118.6423297 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum |
| CV-24119 | 5/7/2026 10:38:27 AM | 28.73 | 1253 | 34.4337712 | -118.6422773 | NSPS/EG CAI,High Temp |
| CV-24119 | 5/7/2026 10:35:25 AM | 28.73 | 1266 | 34.4337382 | -118.6423242 | High Temp,NSPS/EG CAI |
| CV-24120 | 5/26/2026 2:15:09 PM | 28.41 | 1343 | 34.4369008 | -118.6472950 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-24120 | 5/11/2026 10:28:50 AM | 28.6 | 1325 | 34.4368377 | -118.6472678 | Valve Adjustment:Reduce Sys. Vac. - Flare Down;Well Comment:Pump is off;Well Condition:Lorentz Pump Installed |
| CV-24120 | 5/4/2026 8:00:00 AM | | | | | Air Tech Lab; [User entered 11%] |
| CV-24121 | 5/26/2026 2:08:29 PM | 28.4 | 1321 | 34.4369917 | -118.6470098 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open |
| CV-24121 | 5/11/2026 10:33:56 AM | 28.61 | 1326 | 34.4369493 | -118.6470013 | Valve Adjustment:High O2,Barely Open |
| CV-24121 | 5/11/2026 10:33:18 AM | 28.61 | 1334 | 34.4369455 | -118.6470150 | Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Reduce Sys. Vac. - Flare Down |
| CV-24121 | 5/4/2026 7:55:00 AM | | | | | Air Tech Lab; [User entered 0.27%] |
| CV-24122 | 5/29/2026 9:40:41 AM | 28.67 | 1348 | 34.4371873 | -118.6466763 | NSPS/EG CAC,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-24122 | 5/29/2026 9:33:20 AM | 28.7 | 1280 | 34.4372067 | -118.6465517 | NSPS/EG CAI,High O2 |
| CV-24122 | 5/6/2026 10:31:06 AM | 28.68 | 1317 | 34.4371738 | -118.6465920 | Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Surging Liquid in Header |
| CV-24122 | 5/4/2026 8:20:00 AM | | | | | Air Tech Lab; [User entered 0.91%] |
| CV-24123 | 5/28/2026 11:46:50 AM | 28.59 | 1307 | 34.4373075 | -118.6462547 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Well (Watered In) |
| CV-24123 | 5/28/2026 11:46:25 AM | 28.59 | 1309 | 34.4373132 | -118.6462478 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Well (Watered In) |
| CV-24123 | 5/15/2026 11:28:22 AM | 28.69 | 1296 | 34.4373435 | -118.6463497 | |
| CV-24123 | 5/15/2026 11:24:46 AM | 28.69 | 1289 | 34.4372963 | -118.6462287 | NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 to 1 Turn |
| CV-24123 | 5/14/2026 10:54:34 AM | 28.67 | 1296 | 34.4373023 | -118.6462322 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Valve 100% Open |
| CV-24123 | 5/14/2026 10:53:53 AM | 28.66 | 1313 | 34.4373012 | -118.6462247 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Valve 100% Open,Reduce Sys. Vac. - Flare Down |
| CV-24124 | 5/29/2026 11:28:31 AM | 28.61 | 1325 | 34.4366833 | -118.6470370 | No Flow Measurement |
| CV-24125-TP2 | 5/26/2026 1:56:27 PM | 28.41 | 1297 | 34.4369842 | -118.6463480 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24125-TP2 | 5/13/2026 7:55:00 AM | | | | | Air Tech Lab |
| CV-24125-TP2 | 5/13/2026 7:55:00 AM | | | | | Air Tech Lab; [User entered 0.13%] |
| CV-24126 | 5/26/2026 10:58:38 AM | 28.44 | 1378 | 34.4363846 | -118.6471352 | Valve Adjustment:High Temp |
| CV-24126 | 5/22/2026 12:29:20 PM | 28.43 | 1378 | 34.4363843 | -118.6471382 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24126 | 5/22/2026 12:28:40 PM | 28.41 | 1369 | 34.4363798 | -118.6471328 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24126 | 5/18/2026 10:50:00 AM | | | | | AtmAA |
| CV-24126 | 5/18/2026 10:44:28 AM | 28.5 | 1382 | 34.4363798 | -118.6471235 | Valve Adjustment:High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down |
| CV-24126 | 5/18/2026 10:43:37 AM | 28.51 | 1382 | 34.4363799 | -118.6471235 | Valve Adjustment:High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down |
| CV-24126 | 5/12/2026 10:30:00 AM | | | | | AtmAA |
| CV-24126 | 5/12/2026 10:28:41 AM | 28.51 | 1372 | 34.4363758 | -118.6471297 | Valve Adjustment:High Temp |
| CV-24126 | 5/4/2026 2:50:00 PM | | | | | AtmAA |
| CV-24126 | 5/4/2026 2:50:00 PM | | | | | AtmAA; [User entered 13.58%] |
| CV-24126 | 5/4/2026 2:40:40 PM | 28.48 | 1380 | 34.4363804 | -118.6471332 | Valve Adjustment:High Temp |
| CV-24127 | 5/7/2026 10:22:55 AM | 28.56 | 1376 | 34.4364671 | -118.6468331 | Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open |
| CV-24127 | 5/7/2026 10:21:43 AM | 28.57 | 1376 | 34.4364622 | -118.6468224 | Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum,Valve 100% Open |
| CV-24127 | 5/7/2026 10:20:00 AM | | | | | AtmAA |
| CV-24127 | 5/7/2026 10:20:00 AM | | | | | AtmAA; [User entered 15.26%] |
| CV-24127 | 5/4/2026 8:15:00 AM | | | | | Air Tech Lab; [User entered 16%] |
| CV-24128 | 5/26/2026 2:25:15 PM | 28.37 | 1342 | 34.4367235 | -118.6464333 | Valve Adjustment:Barely Open |
| CV-24128 | 5/13/2026 7:50:00 AM | | | | | Air Tech Lab |
| CV-24128 | 5/13/2026 7:50:00 AM | | | | | Air Tech Lab; [User entered 1.1%] |
| CV-24128 | 5/8/2026 9:33:23 AM | 28.61 | 1342 | 34.4367072 | -118.6465008 | Reduced System Vacuum |
| CV-24129 | 5/26/2026 1:33:50 PM | 28.37 | 1361 | 34.4367435 | -118.6461525 | Valve Adjustment:Barely Open |
| CV-24129 | 5/8/2026 9:24:27 AM | 28.62 | 1355 | 34.4368125 | -118.6461097 | Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-24130 | 5/26/2026 1:42:41 PM | 28.41 | 1321 | 34.4368173 | -118.6457212 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-24131 | 5/29/2026 1:47:07 PM | 28.69 | 1417 | 34.4368227 | -118.6450578 | |
| CV-24132 | 5/6/2026 10:15:34 AM | 28.71 | 1282 | 34.4372393 | -118.6440080 | Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Barely Open |
| CV-24133 | 5/7/2026 9:28:04 AM | 28.7 | 1266 | 34.4374198 | -118.6427065 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-24134-TP1 | 5/26/2026 10:55:47 AM | 28.47 | 1369 | 34.4363655 | -118.6465137 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24134-TP1 | 5/18/2026 10:45:00 AM | | | | | AtmAA |
| CV-24134-TP1 | 5/18/2026 10:39:38 AM | 28.51 | 1389 | 34.4363597 | -118.6465047 | Valve Adjustment:No Flow Measurement,High Temp,Reduce Sys. Vac. - Flare Down |
| CV-24134-TP1 | 5/12/2026 10:35:00 AM | | | | | AtmAA |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24134-TP1 | 5/12/2026 10:33:32 AM | 28.52 | 1364 | 34.4363682 | -118.6465123 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp |
| CV-24134-TP1 | 5/12/2026 10:32:12 AM | 28.51 | 1363 | 34.4363686 | -118.6465143 | Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High O2,Increased Flow/Vacuum |
| CV-24134-TP1 | 5/11/2026 2:33:48 PM | 28.5 | 1463 | 34.4358975 | -118.6469445 | |
| CV-24134-TP1 | 5/11/2026 2:29:03 PM | 28.5 | 1306 | 34.4364227 | -118.6465933 | NSPS/EG CAI,High Temp |
| CV-24134-TP1 | 5/7/2026 1:15:00 PM | | | | | AtmAA |
| CV-24134-TP1 | 5/7/2026 1:14:04 PM | 28.52 | 1365 | 34.4363836 | -118.6465279 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24135 | 5/11/2026 2:17:55 PM | 28.5 | 1437 | 34.4365893 | -118.6460023 | |
| CV-24135 | 5/11/2026 2:15:34 PM | 28.5 | 1476 | 34.4366117 | -118.6459615 | NSPS/EG CAI,NSPS/EG CAC,High Temp,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-24136 | 5/11/2026 11:29:51 AM | 28.56 | 1312 | 34.4366663 | -118.6442622 | |
| CV-24137 | 5/4/2026 1:08:31 PM | 28.53 | 1364 | 34.4361537 | -118.6434742 | Valve Adjustment:NSPS/EG CAC,Barely Open |
| CV-24137 | 5/4/2026 1:07:02 PM | 28.52 | 1366 | 34.4361527 | -118.6434890 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum |
| CV-24138 | 5/28/2026 9:03:38 AM | 28.63 | 1259 | 34.4342632 | -118.6512275 | Valve Adjustment:NSPS/EG CAI,High O2,Surging Liquid in Header |
| CV-24138 | 5/28/2026 9:02:31 AM | 28.63 | 1259 | 34.4342632 | -118.6512275 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum |
| CV-24138 | 5/13/2026 1:14:42 PM | 28.77 | 1269 | 34.4342657 | -118.6512554 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header;Well Condition:Pnumatic Pump Installed |
| CV-24138 | 5/6/2026 11:00:00 AM | | | | | AtmAA |
| CV-24138 | 5/6/2026 11:00:00 AM | | | | | AtmAA; [User entered 17.18%] |
| CV-24138 | 5/6/2026 10:58:19 AM | 28.71 | 1267 | 34.4342542 | -118.6512505 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24138 | 5/5/2026 8:15:00 AM | | | | | Air Tech Lab |
| CV-24138 | 5/5/2026 8:15:00 AM | | | | | Air Tech Lab; [User entered 21%] |
| CV-24139 | 5/28/2026 9:08:34 AM | 28.62 | 1271 | 34.4344895 | -118.6511280 | Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum |
| CV-24139 | 5/15/2026 8:22:50 AM | 28.63 | 1277 | 34.4344970 | -118.6511408 | Valve Adjustment:NSPS/EG CAI,High Temp,High O2;Well Comment:sensitive valve;Well Repairs:Valve |
| CV-24139 | 5/15/2026 8:12:50 AM | 28.63 | 1269 | 34.4344985 | -118.6511383 | Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Positive Static Press.,Increased Flow/Vacuum |
| CV-24139 | 5/5/2026 8:10:00 AM | | | | | Air Tech Lab |
| CV-24139 | 5/5/2026 8:10:00 AM | | | | | Air Tech Lab; [User entered 18%] |
| CV-24140 | 5/28/2026 10:52:29 AM | 28.63 | 1290 | 34.4346606 | -118.6511161 | Valve Adjustment:High Temp |
| CV-24140 | 5/28/2026 10:50:34 AM | 28.62 | 1289 | 34.4346622 | -118.6511122 | Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum |
| CV-24140 | 5/20/2026 1:28:20 PM | 28.61 | 1281 | 34.4346751 | -118.6511126 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24140 | 5/20/2026 1:26:41 PM | 28.62 | 1283 | 34.4346784 | -118.6511216 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-24140 | 5/13/2026 1:18:30 PM | 28.76 | 1277 | 34.4346840 | -118.6511326 | Valve Adjustment:No Flow Measurement,High Temp |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24140 | 5/6/2026 11:05:00 AM | | | | | AtmAA |
| CV-24140 | 5/6/2026 11:05:00 AM | | | | | AtmAA; [User entered 20.3%] |
| CV-24140 | 5/6/2026 11:04:58 AM | 28.71 | 1273 | 34.4346804 | -118.6511081 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24140 | 5/5/2026 8:05:00 AM | | | | | Air Tech Lab |
| CV-24140 | 5/5/2026 8:05:00 AM | | | | | Air Tech Lab; [User entered 21%] |
| CV-24141 | 5/28/2026 9:31:07 AM | 28.59 | 1299 | 34.4354908 | -118.6513087 | Valve Adjustment:NSPS/EG CAI,High O2 |
| CV-24141 | 5/28/2026 9:30:26 AM | 28.59 | 1296 | 34.4354957 | -118.6513018 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum;Well Comment:no pump installed |
| CV-24141 | 5/5/2026 7:45:00 AM | | | | | Air Tech Lab |
| CV-24141 | 5/5/2026 7:45:00 AM | | | | | Air Tech Lab; [User entered 0.12%] |
| CV-24141 | 5/1/2026 8:57:18 AM | 28.6 | 1281 | 34.4354885 | -118.6512937 | Valve Adjustment:Increased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| CV-24142 | 5/28/2026 10:41:54 AM | 28.65 | 1270 | 34.4339722 | -118.6513273 | |
| CV-24142 | 5/28/2026 10:40:43 AM | 28.66 | 1270 | 34.4339743 | -118.6513278 | Valve Adjustment:NSPS/EG CAI |
| CV-24142 | 5/20/2026 1:14:55 PM | 28.62 | 1271 | 34.4339962 | -118.6513468 | Valve Comment:Pneumatic pump not working;Valve Adjustment:No Flow Measurement,High Temp |
| CV-24142 | 5/20/2026 1:02:37 PM | 28.64 | 1270 | 34.4339787 | -118.6513463 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed |
| CV-24142 | 5/15/2026 8:03:40 AM | 28.63 | 1259 | 34.4339805 | -118.6513398 | Valve Adjustment:NSPS/EG CAI,High Temp,Valve 100% Open,Surging Liquid in Header |
| CV-24142 | 5/15/2026 7:59:13 AM | 28.63 | 1255 | 34.4339758 | -118.6513298 | Valve Adjustment:NSPS/EG CAI,High Temp,Valve 100% Open,Surging Liquid in Header |
| CV-24142 | 5/14/2026 8:35:00 AM | | | | | AtmAA |
| CV-24142 | 5/6/2026 8:10:00 AM | | | | | Air Tech Lab |
| CV-24142 | 5/6/2026 8:10:00 AM | | | | | Air Tech Lab; [User entered 12%] |
| CV-24143 | 5/28/2026 9:20:03 AM | 28.6 | 1286 | 34.4349775 | -118.6512110 | Valve Adjustment:NSPS/EG CAI,High O2,Barely Open |
| CV-24143 | 5/28/2026 9:19:15 AM | 28.6 | 1285 | 34.4349643 | -118.6511857 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum |
| CV-24143 | 5/5/2026 7:55:00 AM | | | | | Air Tech Lab |
| CV-24143 | 5/5/2026 7:55:00 AM | | | | | Air Tech Lab; [User entered 6.1%] |
| CV-24143 | 5/1/2026 2:16:44 PM | 28.52 | 1296 | 34.4350570 | -118.6513283 | |
| CV-24143 | 5/1/2026 2:15:01 PM | 28.52 | 1289 | 34.4349098 | -118.6512402 | NSPS/EG CAI,High O2 |
| CV-24144 | 5/20/2026 10:35:16 AM | 28.66 | 1250 | 34.4325475 | -118.6515890 | Valve Adjustment:Valve 100% Open |
| CV-24144 | 5/12/2026 9:03:44 AM | 28.67 | 1257 | 34.4324108 | -118.6519563 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,No Flow Measurement |
| CV-24145 | 5/26/2026 2:12:30 PM | 28.4 | 1362 | 34.4362272 | -118.6496586 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement |
| CV-24145 | 5/18/2026 2:54:25 PM | 28.51 | 1365 | 34.4362193 | -118.6496297 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24145 | 5/18/2026 2:45:00 PM | | | | | AtmAA |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24145 | 5/18/2026 2:38:58 PM | 28.53 | 1356 | 34.4362236 | -118.6496363 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24145 | 5/12/2026 2:40:29 PM | 28.58 | 1374 | 34.4362303 | -118.6496176 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24145 | 5/12/2026 2:34:47 PM | 28.58 | 1373 | 34.4362229 | -118.6496211 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24145 | 5/12/2026 2:32:19 PM | 28.58 | 1371 | 34.4362174 | -118.6496221 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-24145 | 5/12/2026 2:15:00 PM | | | | | AtmAA |
| CV-24145 | 5/5/2026 1:25:00 PM | | | | | AtmAA |
| CV-24145 | 5/5/2026 1:25:00 PM | | | | | AtmAA; [User entered 16.59%] |
| CV-24145 | 5/5/2026 1:22:41 PM | 28.51 | 1363 | 34.4362207 | -118.6496456 | Valve Adjustment:High Temp |
| CV-24146 | 5/28/2026 10:15:05 AM | 28.59 | 1314 | 34.4374078 | -118.6463857 | Valve Adjustment:Positive Static Press.,Undersized Lateral |
| CV-24146 | 5/28/2026 10:14:14 AM | 28.59 | 1305 | 34.4374012 | -118.6463870 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Valve 100% Open |
| CV-24146 | 5/11/2026 9:52:43 AM | 28.64 | 1284 | 34.4374268 | -118.6463657 | Valve Adjustment:Valve 100% Open |
| CV-24147 | 5/28/2026 11:28:34 AM | 28.63 | 1280 | 34.4375317 | -118.6459378 | Valve Comment:RES SEM;Well Comment:No system pressure |
| CV-24147 | 5/26/2026 9:21:12 AM | 28.58 | 1287 | 34.4375215 | -118.6459190 | Valve Adjustment:Reduce Sys. Vac. - Flare Down |
| CV-24147 | 5/14/2026 2:08:02 PM | 28.64 | 1266 | 34.4375410 | -118.6459490 | Valve Comment:RES SEM;Valve Adjustment:Valve 100% Open |
| CV-24147 | 5/11/2026 10:06:39 AM | 28.64 | 1265 | 34.4375288 | -118.6459283 | |
| CV-24147 | 5/11/2026 10:05:05 AM | 28.65 | 1287 | 34.4375157 | -118.6459288 | Valve Adjustment:Increased Flow/Vacuum,Valve 100% Open |
| CV-24147 | 5/11/2026 10:02:23 AM | 28.64 | 1289 | 34.4375118 | -118.6459487 | Valve Comment:Valve closed upon arrival;Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Plugged/Pinched Suspected |
| CV-24148 | 5/27/2026 1:49:59 PM | 28.4 | 1377 | 34.4350742 | -118.6466626 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24148 | 5/19/2026 1:50:00 PM | | | | | AtmAA |
| CV-24148 | 5/19/2026 1:44:57 PM | 28.58 | 1382 | 34.4350894 | -118.6466738 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24148 | 5/19/2026 1:43:50 PM | 28.58 | 1381 | 34.4350896 | -118.6466740 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-24148 | 5/11/2026 10:02:23 AM | 28.52 | 1394 | 34.4350592 | -118.6466624 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24148 | 5/4/2026 9:31:25 AM | 28.56 | 1381 | 34.4350509 | -118.6466784 | Valve Adjustment:High Temp |
| CV-24148 | 5/4/2026 9:30:00 AM | | | | | AtmAA |
| CV-24148 | 5/4/2026 9:30:00 AM | | | | | AtmAA; [User entered 10.62%] |
| CV-24149 | 5/28/2026 12:48:18 PM | 28.47 | 1434 | 34.4347898 | -118.6469502 | |
| CV-24149 | 5/6/2026 2:58:21 PM | 28.56 | 1376 | 34.4347945 | -118.6469973 | Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header |
| CV-24150 | 5/22/2026 11:53:52 AM | 28.37 | 1375 | 34.4346357 | -118.6456373 | |
| CV-24150 | 5/1/2026 10:15:37 AM | 28.61 | 1414 | 34.4346062 | -118.6455488 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24151 | 5/21/2026 1:59:13 PM | 28.41 | 1367 | 34.4344122 | -118.6476300 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-24151 | 5/6/2026 2:05:59 PM | 28.6 | 1386 | 34.4344128 | -118.6476310 | Valve Adjustment:Surging Liquid in Header |
| CV-24152 | 5/26/2026 8:32:21 AM | 28.41 | 1387 | 34.4344520 | -118.6471523 | Valve Adjustment:NSPS/EG CAC,Reduce Sys. Vac. - Flare Down |
| CV-24152 | 5/26/2026 8:31:06 AM | 28.41 | 1387 | 34.4344575 | -118.6471328 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down |
| CV-24152 | 5/6/2026 2:21:42 PM | 28.56 | 1411 | 34.4344763 | -118.6471860 | Valve Adjustment:NSPS/EG CAC,High Temp,Barely Open,Surging Liquid in Header |
| CV-24152 | 5/6/2026 2:21:09 PM | 28.56 | 1391 | 34.4344915 | -118.6471960 | Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum,Surging Liquid in Header |
| CV-24153 | 5/22/2026 11:40:23 AM | 28.41 | 1407 | 34.4344045 | -118.6463667 | |
| CV-24153 | 5/1/2026 3:03:06 PM | 28.41 | 1365 | 34.4344288 | -118.6465135 | |
| CV-24153 | 5/1/2026 3:02:03 PM | 28.41 | 1398 | 34.4344655 | -118.6464518 | NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-24154 | 5/22/2026 11:58:09 AM | 28.37 | 1440 | 34.4343248 | -118.6460817 | |
| CV-24154 | 5/1/2026 3:20:22 PM | 28.4 | 1339 | 34.4343657 | -118.6460868 | |
| CV-24155 | 5/26/2026 8:18:02 AM | 28.41 | 1389 | 34.4342782 | -118.6467312 | Valve Adjustment:Audible Flow,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| CV-24155 | 5/1/2026 3:09:53 PM | 28.41 | 1424 | 34.4343630 | -118.6468045 | |
| CV-24155 | 5/1/2026 3:08:32 PM | 28.41 | 1388 | 34.4343065 | -118.6467873 | NSPS/EG CAI,NSPS/EG CAC,Audible Flow,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-24156 | 5/22/2026 2:00:28 PM | 28.38 | 1427 | 34.4341015 | -118.6477328 | |
| CV-24156 | 5/4/2026 2:11:53 PM | 28.51 | 1364 | 34.4340843 | -118.6476997 | Valve Adjustment:Barely Open |
| CV-24157 | 5/21/2026 2:09:04 PM | 28.41 | 1393 | 34.4338020 | -118.6473238 | Valve Adjustment:NSPS/EG CAC,Barely Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| CV-24157 | 5/21/2026 2:08:15 PM | 28.41 | 1389 | 34.4338040 | -118.6473370 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Barely Open,Surging Liquid in Header |
| CV-24157 | 5/4/2026 2:00:15 PM | 28.45 | 1387 | 34.4338397 | -118.6473362 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-24158 | 5/21/2026 10:58:26 AM | 28.41 | 1393 | 34.4339078 | -118.6470818 | Valve Adjustment:NSPS/EG CAI,Barely Open |
| CV-24158 | 5/6/2026 10:59:56 AM | 28.6 | 1396 | 34.4338992 | -118.6470452 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-24159 | 5/21/2026 9:02:31 AM | 28.41 | 1401 | 34.4337822 | -118.6466368 | Valve Adjustment:High Temp,Surging Liquid in Header |
| CV-24159 | 5/21/2026 9:01:50 AM | 28.41 | 1403 | 34.4337750 | -118.6466390 | Valve Adjustment:NSPS/EG CAI,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header |
| CV-24159 | 5/6/2026 10:49:41 AM | 28.38 | 1371 | 34.4337905 | -118.6465662 | |
| CV-24160 | 5/22/2026 12:06:28 PM | 28.37 | 1460 | 34.4337483 | -118.6462070 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24160 | 5/6/2026 12:39:52 PM | 28.63 | 1399 | 34.4338072 | -118.6462550 | Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum |
| CV-24160 | 5/6/2026 10:29:54 AM | 28.56 | 1388 | 34.4338240 | -118.6461872 | |
| CV-24161 | 5/6/2026 10:20:39 AM | 28.56 | 1381 | 34.4338940 | -118.6454970 | |
| CV-24161 | 5/6/2026 10:19:18 AM | 28.56 | 1362 | 34.4338600 | -118.6455383 | NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-24162 | 5/4/2026 12:02:44 PM | 28.52 | 1365 | 34.4335793 | -118.6451230 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-24163 | 5/1/2026 2:33:25 PM | 28.52 | 1338 | 34.4334712 | -118.6444877 | Valve Adjustment:NSPS/EG CAC,Barely Open;Well Condition:Lorentz Pump Installed |
| CV-24163 | 5/1/2026 2:32:24 PM | 28.53 | 1336 | 34.4334823 | -118.6444873 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed |
| CV-24164 | 5/20/2026 2:08:15 PM | 28.48 | 1374 | 34.4334770 | -118.6479875 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24164 | 5/20/2026 2:06:56 PM | 28.48 | 1379 | 34.4334703 | -118.6479778 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24164 | 5/20/2026 11:14:31 AM | 28.49 | 1369 | 34.4334945 | -118.6479757 | Valve Adjustment:Barely Open |
| CV-24164 | 5/4/2026 10:23:58 AM | 28.52 | 1361 | 34.4334943 | -118.6479645 | Valve Adjustment:Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed |
| CV-24165 | 5/20/2026 11:18:42 AM | 28.49 | 1374 | 34.4335912 | -118.6476822 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-24165 | 5/14/2026 11:24:07 AM | 28.67 | 1371 | 34.4334927 | -118.6473035 | |
| CV-24165 | 5/14/2026 11:22:03 AM | 28.67 | 1440 | 34.4335542 | -118.6473277 | NSPS/EG CAI,NSPS/EG CAC,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,High Temp,Positive Static Press. |
| CV-24166 | 5/21/2026 9:08:04 AM | 28.42 | 1405 | 34.4335958 | -118.6468947 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-24166 | 5/20/2026 11:21:55 AM | 28.51 | 1355 | 34.4337010 | -118.6483662 | Valve Adjustment:Barely Open |
| CV-24166 | 5/6/2026 10:54:07 AM | 28.55 | 1289 | 34.4337443 | -118.6468000 | |
| CV-24167 | 5/28/2026 8:45:13 AM | 28.47 | 1386 | 34.4334667 | -118.6464515 | Well Condition:Lorentz Pump Installed |
| CV-24167 | 5/6/2026 9:59:13 AM | 28.76 | 1453 | 34.4334527 | -118.6464858 | |
| CV-24168 | 5/28/2026 8:59:25 AM | 28.49 | 1389 | 34.4332990 | -118.6472985 | Well Condition:Lorentz Pump Installed |
| CV-24168 | 5/6/2026 10:55:15 AM | 28.61 | 1406 | 34.4333458 | -118.6473238 | Valve Adjustment:Barely Open,Surging Liquid in Header |
| CV-24169 | 5/20/2026 11:11:16 AM | 28.49 | 1383 | 34.4332078 | -118.6477205 | Valve Adjustment:Barely Open |
| CV-24169 | 5/4/2026 10:19:18 AM | 28.52 | 1375 | 34.4331917 | -118.6477157 | Valve Adjustment:Barely Open |
| CV-24170 | 5/21/2026 9:20:08 AM | 28.48 | 1368 | 34.4331183 | -118.6485037 | Valve Adjustment:Barely Open |
| CV-24170 | 5/6/2026 8:37:17 AM | 28.63 | 1372 | 34.4331162 | -118.6485155 | Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum,Barely Open |
| CV-24170 | 5/1/2026 10:56:54 AM | 28.56 | 1363 | 34.4331005 | -118.6484957 | Valve Adjustment:Barely Open |
| CV-24171 | 5/21/2026 9:23:58 AM | 28.45 | 1406 | 34.4331897 | -118.6466525 | Valve Comment:well too tall |
| CV-24171 | 5/6/2026 10:03:52 AM | 28.55 | 1411 | 34.4332255 | -118.6466338 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-24172 | 5/21/2026 10:00:21 AM | 28.41 | 1377 | 34.4329367 | -118.6473203 | Valve Adjustment:Barely Open |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24172 | 5/4/2026 2:28:48 PM | 28.46 | 1404 | 34.4330085 | -118.6473612 | |
| CV-24173 | 5/21/2026 10:06:44 AM | 28.45 | 1383 | 34.4328933 | -118.6476563 | Valve Comment:well too tall for system read |
| CV-24173 | 5/6/2026 1:00:35 PM | 28.63 | 1387 | 34.4328932 | -118.6476568 | Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum |
| CV-24174 | 5/21/2026 10:15:48 AM | 28.44 | 1379 | 34.4327447 | -118.6480342 | Valve Adjustment:Barely Open |
| CV-24174 | 5/11/2026 1:20:08 PM | 28.63 | 1375 | 34.4327227 | -118.6480538 | Valve Adjustment:Reduce Sys. Vac. - Flare Down;Well Comment:pump is off;Well Condition:Lorentz Pump Installed |
| CV-24175 | 5/21/2026 10:19:57 AM | 28.45 | 1362 | 34.4326887 | -118.6484998 | Valve Adjustment:Barely Open |
| CV-24175 | 5/5/2026 1:28:08 PM | 28.53 | 1382 | 34.4326552 | -118.6484768 | Well Comment:pump is active;Well Condition:Lorentz Pump Installed |
| CV-24175 | 5/5/2026 1:26:42 PM | 28.52 | 1382 | 34.4326533 | -118.6484855 | Valve Comment:secured lorentz fitting;Valve Adjustment:Increased Flow/Vacuum;Well Comment:pump is active.;Well Condition:Lorentz Pump Installed |
| CV-24175 | 5/5/2026 1:21:04 PM | 28.53 | 1382 | 34.4326548 | -118.6484853 | Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum;Well Comment:pump is active;Well Condition:Lorentz Pump Installed |
| CV-24175 | 5/5/2026 1:13:21 PM | 28.53 | 1362 | 34.4326723 | -118.6484765 | Valve Adjustment:Increased Flow/Vacuum;Well Comment:Pump is active;Well Condition:Lorentz Pump Installed |
| CV-24176 | 5/20/2026 10:16:41 AM | 28.5 | 1391 | 34.4326228 | -118.6489318 | |
| CV-24176 | 5/20/2026 10:14:10 AM | 28.5 | 1404 | 34.4326493 | -118.6489970 | NSPS/EG CAI,NSPS/EG CAC,High Temp |
| CV-24176 | 5/8/2026 11:05:11 AM | 28.54 | 1322 | 34.4326280 | -118.6489067 | |
| CV-24176 | 5/8/2026 11:03:01 AM | 28.54 | 1352 | 34.4325257 | -118.6489255 | NSPS/EG CAI,NSPS/EG CAC,Audible Flow,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 to 1 Turn |
| CV-24177 | 5/20/2026 8:06:52 AM | 28.56 | 1306 | 34.4322462 | -118.6494580 | Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open |
| CV-24177 | 5/20/2026 7:56:33 AM | 28.57 | 1320 | 34.4322548 | -118.6494448 | Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Decreased Flow/Vacuum |
| CV-24177 | 5/8/2026 11:20:50 AM | 28.57 | 1332 | 34.4322813 | -118.6494228 | |
| CV-24177 | 5/8/2026 11:19:26 AM | 28.57 | 1355 | 34.4322503 | -118.6493363 | Reduced System Vacuum,NSPS/EG CAI,NSPS/EG CAC,High O2 |
| CV-24178 | 5/20/2026 12:02:57 PM | 28.48 | 1385 | 34.4323280 | -118.6486115 | |
| CV-24178 | 5/20/2026 12:01:45 PM | 28.48 | 1417 | 34.4323233 | -118.6486002 | NSPS/EG CAI,NSPS/EG CAC,High Temp |
| CV-24178 | 5/8/2026 10:58:25 AM | 28.55 | 1430 | 34.4324165 | -118.6486865 | Reduced System Vacuum |
| CV-24179 | 5/20/2026 9:55:47 AM | 28.51 | 1286 | 34.4320667 | -118.6492728 | |
| CV-24179 | 5/4/2026 1:09:48 PM | 28.57 | 1340 | 34.4321117 | -118.6492078 | |
| CV-24179 | 5/4/2026 1:08:00 PM | 28.6 | 1330 | 34.4321170 | -118.6492072 | Valve Adjustment:Increased Flow/Vacuum |
| CV-24179 | 5/4/2026 1:03:56 PM | 28.58 | 1341 | 34.4321288 | -118.6492127 | Valve Adjustment:Barely Open |
| CV-24180 | 5/20/2026 10:03:08 AM | 28.53 | 1348 | 34.4321713 | -118.6488025 | |
| CV-24180 | 5/8/2026 10:53:15 AM | 28.65 | 1335 | 34.4321552 | -118.6487778 | Reduced System Vacuum |
| CV-24181 | 5/20/2026 12:05:54 PM | 28.48 | 1421 | 34.4321825 | -118.6483900 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24181 | 5/4/2026 11:08:54 AM | 28.53 | 1276 | 34.4321710 | -118.6484342 | |
| CV-24182 | 5/22/2026 10:34:25 AM | 28.4 | 1358 | 34.4323000 | -118.6481662 | |
| CV-24182 | 5/4/2026 11:12:00 AM | 28.5 | 1299 | 34.4322548 | -118.6480292 | |
| CV-24183 | 5/20/2026 11:42:38 AM | 28.48 | 1375 | 34.4323228 | -118.6476718 | |
| CV-24183 | 5/4/2026 11:26:46 AM | 28.51 | 1362 | 34.4324333 | -118.6476603 | |
| CV-24184 | 5/28/2026 1:18:12 PM | 28.52 | 1378 | 34.4325162 | -118.6472783 | Valve Adjustment:NSPS/EG CAI,High Temp,High O2 |
| CV-24184 | 5/28/2026 1:16:04 PM | 28.52 | 1373 | 34.4325148 | -118.6472750 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Decreased Flow/Vacuum |
| CV-24184 | 5/20/2026 11:25:50 AM | 28.48 | 1362 | 34.4325758 | -118.6472723 | |
| CV-24184 | 5/20/2026 11:24:32 AM | 28.48 | 1417 | 34.4325943 | -118.6472117 | High Temp |
| CV-24184 | 5/20/2026 11:22:55 AM | 28.48 | 1250 | 34.4325003 | -118.6471720 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,NSPS/EG CAI,NSPS/EG CAC,Positive Static Press. |
| CV-24184 | 5/4/2026 1:19:41 PM | 28.65 | 1309 | 34.4325610 | -118.6473778 | |
| CV-24184 | 5/4/2026 1:18:22 PM | 28.65 | 1322 | 34.4325152 | -118.6473015 | NSPS/EG CAI,High Temp |
| CV-24185 | 5/20/2026 2:14:16 PM | 28.43 | 1385 | 34.4327108 | -118.6468708 | |
| CV-24185 | 5/20/2026 2:12:58 PM | 28.43 | 1368 | 34.4323010 | -118.6466718 | NSPS/EG CAI,NSPS/EG CAC,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,Positive Static Press. |
| CV-24185 | 5/4/2026 1:26:49 PM | 28.49 | 1371 | 34.4326090 | -118.6469768 | |
| CV-24186 | 5/20/2026 2:18:02 PM | 28.42 | 1398 | 34.4327695 | -118.6464922 | |
| CV-24186 | 5/4/2026 2:56:41 PM | 28.47 | 1385 | 34.4328797 | -118.6466523 | |
| CV-24187 | 5/19/2026 10:36:55 AM | 28.65 | 1311 | 34.4318815 | -118.6495770 | |
| CV-24187 | 5/4/2026 10:28:37 AM | 28.63 | 1302 | 34.4318867 | -118.6495672 | |
| CV-24187 | 5/4/2026 10:27:50 AM | 28.62 | 1302 | 34.4318867 | -118.6495672 | Valve Adjustment:Increased Flow/Vacuum |
| CV-24187 | 5/4/2026 10:19:29 AM | 28.61 | 1297 | 34.4318708 | -118.6495668 | Valve Adjustment:Barely Open |
| CV-24188 | 5/20/2026 12:45:56 PM | 28.61 | 1242 | 34.4315378 | -118.6501282 | Well Repairs:Sample Port |
| CV-24188 | 5/20/2026 8:59:37 AM | 28.64 | 1239 | 34.4315653 | -118.6500917 | Valve Adjustment:Increased Flow/Vacuum |
| CV-24188 | 5/4/2026 9:36:30 AM | 28.66 | 1241 | 34.4315288 | -118.6501175 | |
| CV-24188 | 5/4/2026 9:34:45 AM | 28.64 | 1241 | 34.4315468 | -118.6501070 | Valve Adjustment:Increased Flow/Vacuum |
| CV-24189 | 5/20/2026 8:49:58 AM | 28.64 | 1252 | 34.4313387 | -118.6499855 | |
| CV-24189 | 5/4/2026 9:28:20 AM | 28.64 | 1253 | 34.4312907 | -118.6500002 | |
| CV-24190 | 5/19/2026 10:21:44 AM | 28.68 | 1294 | 34.4316022 | -118.6494635 | |
| CV-24190 | 5/4/2026 10:10:47 AM | 28.61 | 1295 | 34.4316097 | -118.6494683 | |
| CV-24192 | 5/22/2026 10:15:13 AM | 28.29 | 1388 | 34.4312343 | -118.6494792 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-24192 | 5/4/2026 10:02:40 AM | 28.62 | 1280 | 34.4313497 | -118.6494815 | |
| CV-24192 | 5/4/2026 10:01:48 AM | 28.62 | 1291 | 34.4313327 | -118.6494998 | Valve Comment:Reduced system vacuum;Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum |
| CV-24192 | 5/4/2026 9:58:01 AM | 28.62 | 1288 | 34.4313643 | -118.6494618 | Valve Adjustment:Increased Flow/Vacuum |
| CV-24193 | 5/19/2026 2:15:47 PM | 28.63 | 1301 | 34.4315485 | -118.6490550 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24193 | 5/4/2026 9:13:38 AM | 28.63 | | | | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-24194 | 5/20/2026 12:10:04 PM | 28.47 | 1358 | 34.4317543 | -118.6484903 | Orifice Plate Changed (See OP Log) |
| CV-24194 | 5/5/2026 1:47:55 PM | 28.55 | 1349 | 34.4318795 | -118.6485242 | Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum |
| CV-24194 | 5/4/2026 9:33:10 AM | 28.51 | 1348 | 34.4318285 | -118.6484785 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-24195 | 5/28/2026 1:01:56 PM | 28.54 | 1335 | 34.4318083 | -118.6478583 | Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum |
| CV-24195 | 5/20/2026 12:23:03 PM | 28.47 | 1427 | 34.4318705 | -118.6479115 | |
| CV-24195 | 5/4/2026 9:46:22 AM | 28.5 | 1339 | 34.4318115 | -118.6479018 | |
| CV-24196 | 5/28/2026 12:55:54 PM | 28.55 | 1341 | 34.4320625 | -118.6471805 | Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum |
| CV-24196 | 5/20/2026 11:31:51 AM | 28.49 | 1325 | 34.4320827 | -118.6471262 | |
| CV-24196 | 5/4/2026 11:32:25 AM | 28.52 | 1348 | 34.4320408 | -118.6471408 | |
| CV-24197 | 5/22/2026 10:52:22 AM | 28.49 | 1345 | 34.4323348 | -118.6465855 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-24197 | 5/8/2026 11:18:02 AM | 28.64 | 1362 | 34.4325160 | -118.6463473 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-24198 | 5/22/2026 10:50:58 AM | 28.43 | 1362 | 34.4318115 | -118.6472943 | |
| CV-24198 | 5/8/2026 10:50:53 AM | 28.66 | 1332 | 34.4315565 | -118.6475795 | Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-24199 | 5/22/2026 10:41:08 AM | 28.41 | 1355 | 34.4317905 | -118.6472448 | |
| CV-24199 | 5/8/2026 10:55:45 AM | 28.65 | 1296 | 34.4317453 | -118.6473035 | Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,Audible Flow |
| CV-24200 | 5/22/2026 9:57:47 AM | 28.55 | 1283 | 34.4314867 | -118.6471573 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-24200 | 5/6/2026 2:43:38 PM | 28.72 | 1368 | 34.4314878 | -118.6471517 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-24201 | 5/22/2026 10:05:48 AM | 28.56 | 1247 | 34.4317160 | -118.6466007 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-24201 | 5/6/2026 3:11:02 PM | 28.63 | 1280 | 34.4318032 | -118.6466470 | |
| CV-24202 | 5/22/2026 10:29:59 AM | 28.55 | 1247 | 34.4319450 | -118.6462482 | No Flow Measurement |
| CV-24202 | 5/6/2026 3:17:39 PM | 28.62 | 1309 | 34.4319817 | -118.6462840 | |
| CV-24203 | 5/22/2026 9:36:46 AM | 28.63 | 1250 | 34.4315252 | -118.6460367 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-24203 | 5/11/2026 10:07:30 AM | 28.62 | 1217 | 34.4314643 | -118.6462402 | |
| CV-24204 | 5/22/2026 9:39:46 AM | 28.61 | 1227 | 34.4314417 | -118.6462805 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-24204 | 5/11/2026 10:10:41 AM | 28.63 | 1270 | 34.4314382 | -118.6462517 | |
| CV-24205 | 5/22/2026 9:45:39 AM | 28.61 | 1237 | 34.4312217 | -118.6464452 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-24205 | 5/6/2026 12:13:07 PM | 28.63 | 1198 | 34.4313107 | -118.6465557 | |
| CV-24206 | 5/22/2026 10:00:36 AM | 28.55 | 1302 | 34.4314912 | -118.6467710 | No Flow Measurement,No Adjustment Made |
| CV-24206 | 5/6/2026 3:04:18 PM | 28.6 | 1299 | 34.4315113 | -118.6467672 | |
| CV-24207 | 5/21/2026 9:17:20 AM | 28.45 | 1412 | 34.4332568 | -118.6469433 | Valve Adjustment:NSPS/EG CAC,Surging Liquid in Header |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24207 | 5/21/2026 9:15:43 AM | 28.44 | 1392 | 34.4332723 | -118.6469215 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-24207 | 5/4/2026 2:35:22 PM | 28.45 | 1421 | 34.4333115 | -118.6469225 | |
| CV-24208 | 5/4/2026 10:58:55 AM | 28.67 | 1246 | 34.4319048 | -118.6451103 | Valve Adjustment:Audible Flow,Decreased Flow/Vacuum |
| CV-24209 | 5/4/2026 11:15:06 AM | 28.63 | 1300 | 34.4321958 | -118.6456132 | Valve Adjustment:Audible Flow,Barely Open |
| CV-24210 | 5/5/2026 1:26:15 PM | 28.56 | 1334 | 34.4326427 | -118.6455938 | Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum |
| CV-24210 | 5/4/2026 11:34:40 AM | 28.59 | 1334 | 34.4326327 | -118.6455760 | Valve Adjustment:Barely Open |
| CV-24211 | 5/7/2026 10:23:15 AM | 28.73 | 1260 | 34.4327410 | -118.6437678 | |
| CV-24212 | 5/11/2026 9:45:09 AM | 28.6 | 1273 | 34.4331760 | -118.6431025 | |
| CV-24212 | 5/11/2026 9:43:52 AM | 28.6 | 1224 | 34.4331448 | -118.6431658 | High Temp |
| CV-24213 | 5/1/2026 1:55:50 PM | 28.56 | 1319 | 34.4366047 | -118.6429695 | Valve Comment:belly was cleared;Valve Adjustment:NSPS/EG CAC |
| CV-24213 | 5/1/2026 1:54:28 PM | 28.56 | 1322 | 34.4366003 | -118.6429628 | Valve Adjustment:NSPS/EG CAC |
| CV-24213 | 5/1/2026 1:34:20 PM | 28.67 | 1321 | 34.4365922 | -118.6429718 | |
| CV-24213 | 5/1/2026 1:32:27 PM | 28.65 | 1321 | 34.4366045 | -118.6429675 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Header;Well Comment:Lateral is bellied and watered in. Created a maintenance form for well. |
| CV-24214 | 5/26/2026 12:44:02 PM | 28.45 | 1305 | 34.4367725 | -118.6434542 | |
| CV-24214 | 5/26/2026 12:41:30 PM | 28.45 | 1322 | 34.4367697 | -118.6434888 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-24215 | 5/29/2026 9:58:57 AM | 28.67 | 1302 | 34.4368545 | -118.6448328 | No Adjustment Made |
| CV-24216 | 5/1/2026 1:59:49 PM | 28.66 | 1303 | 34.4368142 | -118.6423178 | Valve Adjustment:Audible Flow,No Flow Measurement |
| CV-24217 | 5/11/2026 1:45:32 PM | 28.48 | 1381 | 34.4359698 | -118.6446735 | |
| CV-24217 | 5/11/2026 1:25:59 PM | 28.52 | 1388 | 34.4359297 | -118.6444033 | Valve Adjustment:Barely Open |
| CV-24217 | 5/11/2026 10:19:12 AM | 28.63 | 1387 | 34.4359400 | -118.6443795 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-24218 | 5/8/2026 8:42:59 AM | 28.6 | 1385 | 34.4358460 | -118.6457933 | Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,No Flow Measurement |
| CV-24219 | 5/27/2026 2:44:32 PM | 28.39 | 1386 | 34.4350911 | -118.6462439 | Valve Comment:Lorentz pump on upon arrival;Valve Adjustment:No Flow Measurement,High Temp,Barely Open;Well Condition:Lorentz Pump Installed |
| CV-24219 | 5/19/2026 1:10:00 PM | | | | | AtmAA |
| CV-24219 | 5/19/2026 1:07:47 PM | 28.58 | 1398 | 34.4350971 | -118.6462268 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Valve 100% Open |
| CV-24219 | 5/19/2026 1:07:21 PM | 28.59 | 1397 | 34.4350970 | -118.6462269 | Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Increased Flow/Vacuum,Valve 100% Open |
| CV-24219 | 5/11/2026 9:27:37 AM | 28.53 | 1397 | 34.4351058 | -118.6462183 | Valve Adjustment:No Flow Measurement,High Temp |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-24219 | 5/11/2026 9:26:02 AM | 28.52 | 1396 | 34.4351090 | -118.6462179 | Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum |
| CV-24219 | 5/4/2026 8:40:00 AM | | | | | AtmAA |
| CV-24219 | 5/4/2026 8:40:00 AM | | | | | AtmAA; [User entered 10.57%] |
| CV-24219 | 5/4/2026 8:37:52 AM | 28.5 | 1386 | 34.4351322 | -118.6462394 | Valve Adjustment:Audible Flow,High Temp |
| CV-24220 | 5/1/2026 2:28:38 PM | 28.52 | 1350 | 34.4339808 | -118.6439567 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24220 | 5/1/2026 2:26:20 PM | 28.52 | 1347 | 34.4339868 | -118.6439660 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed |
| CV-24221 | 5/7/2026 10:47:53 AM | 28.73 | 1270 | 34.4341442 | -118.6420920 | Reduced System Vacuum,No Adjustment Made |
| CV-24222 | 5/11/2026 9:28:59 AM | 28.69 | 1263 | 34.4336818 | -118.6419815 | Increased Flow/Vacuum,Opened Valve 1/2 to 1 Turn |
| CV-24223 | 5/11/2026 9:35:14 AM | 28.6 | 1224 | 34.4334745 | -118.6425050 | |
| CV-24224 | 5/1/2026 2:36:53 PM | 28.54 | 1337 | 34.4331895 | -118.6448165 | Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Good,Lorentz Pump Installed |
| CV-24225 | 5/4/2026 10:44:54 AM | 28.66 | 1283 | 34.4327052 | -118.6444193 | Valve Adjustment:Audible Flow;Well Condition:Fair |
| CV-24226 | 5/7/2026 10:18:42 AM | 28.74 | 1247 | 34.4325075 | -118.6443080 | No Adjustment Made |
| CV-24227 | 5/8/2026 11:27:46 AM | 28.59 | 1224 | 34.4308177 | -118.6498410 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-24231 | 5/5/2026 2:20:38 PM | 28.68 | 1260 | 34.4302390 | -118.6496235 | |
| CV-24236 | 5/7/2026 9:58:34 AM | 28.7 | 1273 | 34.4300488 | -118.6503772 | |
| CV-24237 | 5/7/2026 10:03:50 AM | 28.68 | 1270 | 34.4307407 | -118.6503562 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-24243 | 5/8/2026 10:05:46 AM | 28.7 | 1201 | 34.4287652 | -118.6506448 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-24244 | 5/7/2026 11:23:42 AM | 28.67 | 1194 | 34.4290022 | -118.6513967 | Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-24245 | 5/7/2026 2:21:55 PM | 28.69 | 1148 | 34.4284755 | -118.6500290 | Reduced System Vacuum |
| CV-24246 | 5/7/2026 2:17:13 PM | 28.69 | 1178 | 34.4287440 | -118.6494585 | Reduced System Vacuum |
| CV-24253 | 5/7/2026 2:35:07 PM | 28.72 | 1227 | 34.4283225 | -118.6499175 | Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-25 | 5/13/2026 1:44:59 PM | 28.76 | 1266 | 34.4370112 | -118.6420990 | Valve Comment:Tighten valve;Well Repairs:Sample Port |
| CV-2501 | 5/4/2026 9:55:50 AM | 28.51 | 1355 | 34.4313038 | -118.6484687 | |
| CV-2502 | 5/4/2026 10:08:04 AM | 28.54 | 1375 | 34.4308270 | -118.6490368 | |
| CV-2503 | 5/6/2026 2:52:46 PM | 28.61 | 1339 | 34.4312688 | -118.6476768 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-2504 | 5/5/2026 2:41:25 PM | 28.58 | 1152 | 34.4303907 | -118.6489443 | |
| CV-2505 | 5/5/2026 2:55:39 PM | 28.59 | 1240 | 34.4308042 | -118.6471923 | |
| CV-2506 | 5/5/2026 3:55:25 PM | 28.6 | 1152 | 34.4305400 | -118.6475997 | |
| CV-2507 | 5/8/2026 1:37:11 PM | 28.72 | 1188 | 34.4301410 | -118.6481617 | Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum |
| CV-2507 | 5/5/2026 3:50:55 PM | 28.59 | 1198 | 34.4301758 | -118.6481212 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-2508 | 5/5/2026 3:46:09 PM | 28.63 | 1188 | 34.4297138 | -118.6487778 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-2509 | 5/8/2026 1:42:52 PM | 28.74 | 1164 | 34.4292580 | -118.6491703 | Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum |
| CV-2509 | 5/5/2026 3:31:32 PM | 28.6 | 1148 | 34.4293525 | -118.6491663 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-2510 | 5/8/2026 1:46:50 PM | 28.74 | 1180 | 34.4290760 | -118.6498257 | Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum |
| CV-2510 | 5/5/2026 2:25:18 PM | 28.71 | 1185 | 34.4290762 | -118.6498040 | Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum;Well Condition:Good |
| CV-25100D | 5/18/2026 10:35:31 AM | 28.51 | 1385 | 34.4361625 | -118.6471403 | Valve Adjustment:No Flow Measurement |
| CV-25100D | 5/12/2026 10:22:21 AM | 28.52 | 1373 | 34.4361728 | -118.6471453 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-25100D | 5/12/2026 10:20:00 AM | | | | | AtmAA |
| CV-25100D | 5/8/2026 9:54:19 AM | 28.6 | 1381 | 34.4361410 | -118.6471367 | |
| CV-25100D | 5/8/2026 9:52:49 AM | 28.6 | 1398 | 34.4361082 | -118.6470927 | |
| CV-25100S | 5/26/2026 10:48:42 AM | 28.47 | 1375 | 34.4361484 | -118.6471281 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-25100S | 5/26/2026 10:48:08 AM | 28.47 | 1376 | 34.4361512 | -118.6471268 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-25100S | 5/18/2026 10:40:00 AM | | | | | AtmAA |
| CV-25100S | 5/18/2026 10:33:27 AM | 28.51 | 1384 | 34.4361428 | -118.6471385 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-25100S | 5/12/2026 10:25:18 AM | 28.52 | 1375 | 34.4361666 | -118.6471482 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-25100S | 5/12/2026 10:25:00 AM | | | | | AtmAA |
| CV-25100S | 5/8/2026 10:01:43 AM | 28.6 | 1362 | 34.4362412 | -118.6471998 | |
| CV-25100S | 5/8/2026 10:00:14 AM | 28.6 | 1371 | 34.4361457 | -118.6471048 | |
| CV-25100S | 5/4/2026 2:45:00 PM | | | | | AtmAA |
| CV-25100S | 5/4/2026 2:45:00 PM | | | | | AtmAA; [User entered 13.82%] |
| CV-25100S | 5/4/2026 2:38:27 PM | 28.51 | 1384 | 34.4361628 | -118.6471271 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-25101D | 5/22/2026 10:43:56 AM | 28.37 | 1394 | 34.4359927 | -118.6467905 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-25101D | 5/12/2026 1:33:31 PM | 28.63 | 1392 | 34.4359830 | -118.6467840 | Valve Comment:Well is suspected to be watered in;Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Well (Watered In);Well Comment:No pump installed |
| CV-25101S | 5/22/2026 10:46:24 AM | 28.37 | 1398 | 34.4359848 | -118.6467945 | Valve Adjustment:Barely Open |
| CV-25101S | 5/12/2026 1:23:51 PM | 28.63 | 1391 | 34.4359960 | -118.6467880 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-25102_ | 5/20/2026 2:05:47 PM | 28.44 | 1375 | 34.4357913 | -118.6471962 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-25102_ | 5/8/2026 10:11:54 AM | 28.6 | 1375 | 34.4357355 | -118.6472145 | |
| CV-25102_ | 5/8/2026 10:09:29 AM | 28.6 | 1394 | 34.4357597 | -118.6471285 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-25103 | 5/22/2026 11:13:05 AM | 28.41 | 1367 | 34.4346380 | -118.6477068 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-25103 | 5/20/2026 1:53:20 PM | 28.41 | 1396 | 34.4356702 | -118.6466980 | Valve Adjustment:Increased Flow/Vacuum,Barely Open |
| CV-25103 | 5/12/2026 10:47:21 AM | 28.61 | 1385 | 34.4356583 | -118.6467003 | Valve Adjustment:NSPS/EG CAC |
| CV-25103 | 5/12/2026 10:45:57 AM | 28.59 | 1382 | 34.4356737 | -118.6466958 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum |
| CV-25104D | 5/20/2026 2:32:23 PM | 28.44 | 1380 | 34.4353553 | -118.6472522 | |
| CV-25104D | 5/13/2026 9:49:44 AM | 28.71 | 1379 | 34.4353555 | -118.6472503 | Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:No pump |
| CV-25104S | 5/20/2026 2:35:06 PM | 28.44 | 1380 | 34.4353553 | -118.6472522 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-25104S | 5/13/2026 9:54:31 AM | 28.71 | 1372 | 34.4353733 | -118.6472362 | Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:No pump |
| CV-25105D | 5/22/2026 10:19:59 AM | 28.37 | 1404 | 34.4353722 | -118.6466995 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-25105D | 5/8/2026 8:27:56 AM | 28.58 | 1371 | 34.4352940 | -118.6467577 | |
| CV-25105S | 5/20/2026 1:43:43 PM | 28.41 | 1392 | 34.4353708 | -118.6467107 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-25105S | 5/8/2026 8:30:20 AM | 28.5 | 1378 | 34.4353882 | -118.6467118 | |
| CV-25106D | 5/26/2026 9:05:29 AM | 28.43 | 1379 | 34.4350615 | -118.6473708 | Valve Adjustment:NSPS/EG CAI,High O2,Reduce Sys. Vac. - Flare Down |
| CV-25106D | 5/26/2026 9:03:18 AM | 28.43 | 1384 | 34.4350633 | -118.6473718 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down |
| CV-25106D | 5/12/2026 2:19:11 PM | 28.67 | 1359 | 34.4350400 | -118.6473762 | |
| CV-25106D | 5/12/2026 2:18:07 PM | 28.67 | 1357 | 34.4350470 | -118.6473775 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In);Well Comment:No pump installed |
| CV-25106S | 5/26/2026 9:12:30 AM | 28.42 | 1375 | 34.4350495 | -118.6473688 | Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Reduce Sys. Vac. - Flare Down |
| CV-25106S | 5/26/2026 9:11:40 AM | 28.42 | 1379 | 34.4350568 | -118.6473650 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down |
| CV-25106S | 5/12/2026 2:25:06 PM | 28.67 | 1366 | 34.4350378 | -118.6473582 | |
| CV-25106S | 5/12/2026 2:23:49 PM | 28.67 | 1367 | 34.4350492 | -118.6473735 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In);Well Comment:No pump installed |
| CV-25107D | 5/1/2026 2:47:38 PM | 28.4 | 1375 | 34.4351265 | -118.6459852 | |
| CV-25107S | 5/1/2026 2:50:28 PM | 28.4 | 1358 | 34.4350663 | -118.6458963 | |
| CV-2511 | 5/5/2026 2:33:06 PM | 28.59 | 1230 | 34.4296735 | -118.6501605 | |
| CV-2512 | 5/5/2026 2:28:36 PM | 28.59 | 1250 | 34.4292710 | -118.6506313 | |
| CV-2513 | 5/7/2026 3:05:57 PM | 28.69 | 1125 | 34.4288815 | -118.6487923 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-2514 | 5/8/2026 2:58:55 PM | 28.71 | 1129 | 34.4296507 | -118.6479342 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-2515 | 5/7/2026 9:16:53 AM | 28.7 | 1266 | 34.4379218 | -118.6432498 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-2516 | 5/11/2026 11:15:10 AM | 28.63 | 1306 | 34.4374927 | -118.6432372 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-2517 | 5/7/2026 9:40:45 AM | 28.72 | 1273 | 34.4369217 | -118.6420542 | No Adjustment Made |
| CV-2518 | 5/7/2026 10:00:08 AM | 28.75 | 1234 | 34.4363728 | -118.6414252 | NSPS/EG CAC,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-2518 | 5/7/2026 9:57:35 AM | 28.75 | 1243 | 34.4363833 | -118.6414300 | NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 to 1 Turn |
| CV-2519 | 5/1/2026 1:11:22 PM | 28.67 | 1299 | 34.4361448 | -118.6420415 | Valve Adjustment:Audible Flow,Increased Flow/Vacuum |
| CV-2520 | 5/1/2026 1:26:15 PM | 28.67 | 1309 | 34.4358838 | -118.6428112 | Valve Adjustment:NSPS/EG CAC,High Temp |
| CV-2520 | 5/1/2026 1:25:06 PM | 28.65 | 1318 | 34.4358822 | -118.6427960 | Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum |
| CV-2521 | 5/26/2026 12:24:46 PM | 28.45 | 1320 | 34.4354940 | -118.6430322 | |
| CV-2522 | 5/5/2026 12:53:32 PM | 28.63 | 1293 | 34.4355363 | -118.6424013 | Valve Adjustment:Audible Flow,Increased Flow/Vacuum |
| CV-2522 | 5/1/2026 10:59:06 AM | 28.71 | 1293 | 34.4355315 | -118.6423892 | Valve Adjustment:NSPS/EG CAC,High Temp |
| CV-2522 | 5/1/2026 10:57:27 AM | 28.71 | 1283 | 34.4355267 | -118.6423915 | Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum |
| CV-2523 | 5/4/2026 2:07:42 PM | 28.63 | 1278 | 34.4357013 | -118.6416728 | Valve Adjustment:Audible Flow,Increased Flow/Vacuum;Well Condition:Good |
| CV-2524 | 5/1/2026 10:45:46 AM | 28.71 | 1282 | 34.4348065 | -118.6425145 | Valve Adjustment:NSPS/EG CAC,High Temp |
| CV-2524 | 5/1/2026 10:44:23 AM | 28.71 | 1277 | 34.4348058 | -118.6425205 | Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum |
| CV-2525 | 5/4/2026 2:13:54 PM | 28.64 | 1276 | 34.4350133 | -118.6417385 | Valve Adjustment:NSPS/EG CAC,Barely Open |
| CV-2525 | 5/4/2026 2:13:24 PM | 28.64 | 1272 | 34.4350155 | -118.6417368 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum |
| CV-2526 | 5/4/2026 2:18:08 PM | 28.65 | 1269 | 34.4345572 | -118.6415907 | Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Barely Open |
| CV-2527 | 5/15/2026 11:27:42 AM | 28.64 | 1325 | 34.4341018 | -118.6428870 | |
| CV-2528 | 5/11/2026 8:25:29 AM | 28.69 | 1243 | 34.4338085 | -118.6412588 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-2529 | 5/8/2026 12:47:59 PM | 28.71 | 1222 | 34.4331330 | -118.6423445 | Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum |
| CV-2530 | 5/12/2026 7:58:10 AM | 28.68 | 1260 | 34.4327550 | -118.6429390 | No Flow Measurement |
| CV-2531 | 5/8/2026 12:35:03 PM | 28.71 | 1207 | 34.4325265 | -118.6433380 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAC,Audible Flow,Barely Open,Surging Liquid in Header |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-2531 | 5/8/2026 12:34:13 PM | 28.71 | 1219 | 34.4325375 | -118.6433560 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum |
| CV-2532 | 5/12/2026 7:54:00 AM | 28.68 | 1247 | 34.4322183 | -118.6437638 | No Flow Measurement |
| CV-2533 | 5/12/2026 7:48:32 AM | 28.69 | 1230 | 34.4319207 | -118.6441120 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-2534 | 5/11/2026 2:17:18 PM | 28.84 | 1221 | 34.4317063 | -118.6444812 | Valve Adjustment:Audible Flow,Increased Flow/Vacuum |
| CV-2535 | 5/5/2026 2:52:23 PM | 28.56 | 1201 | 34.4310167 | -118.6469827 | |
| CV-2536 | 5/14/2026 10:27:30 AM | 28.81 | 1125 | 34.4309465 | -118.6458117 | |
| CV-2537 | 5/6/2026 12:17:48 PM | 28.71 | 1270 | 34.4310645 | -118.6466235 | |
| CV-2538 | 5/6/2026 12:25:17 PM | 28.71 | 1184 | 34.4308127 | -118.6467563 | |
| CV-2539 | 5/20/2026 9:49:24 AM | 28.51 | 1339 | 34.4317478 | -118.6491623 | |
| CV-2539 | 5/4/2026 9:17:28 AM | 28.53 | | | | |
| CV-2540 | 5/20/2026 2:18:42 PM | 28.46 | 1370 | 34.4332802 | -118.6480973 | Valve Adjustment:NSPS/EG CAI,Barely Open |
| CV-2540 | 5/20/2026 2:15:08 PM | 28.48 | 1373 | 34.4332657 | -118.6480898 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open |
| CV-2540 | 5/14/2026 1:17:10 PM | 28.67 | 1370 | 34.4332643 | -118.6481005 | Valve Adjustment:NSPS/EG CAC |
| CV-2540 | 5/14/2026 1:13:24 PM | 28.67 | 1373 | 34.4332743 | -118.6481005 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Well (Watered In) |
| CV-2541 | 5/19/2026 9:38:49 AM | 28.63 | 1346 | 34.4332705 | -118.6490412 | Well Repairs:Sample Port |
| CV-2541 | 5/19/2026 9:36:57 AM | 28.62 | 1350 | 34.4332710 | -118.6490418 | Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp,Decreased Flow/Vacuum |
| CV-2541 | 5/1/2026 11:15:47 AM | 28.58 | 1333 | 34.4332740 | -118.6490530 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Well (Watered In) |
| CV-2541 | 5/1/2026 11:15:26 AM | 28.59 | 1335 | 34.4332715 | -118.6490500 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Well (Watered In) |
| CV-2542 | 5/21/2026 2:04:28 PM | 28.4 | 1393 | 34.4337050 | -118.6471915 | Valve Adjustment:Barely Open,Surging Liquid in Header |
| CV-2542 | 5/4/2026 1:56:22 PM | 28.48 | 1381 | 34.4337153 | -118.6471642 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-2543-PLR | 5/20/2026 1:43:43 PM | 28.5 | 1351 | 34.4338193 | -118.6484695 | Valve Comment:sensitive valve;Valve Adjustment:Decreased Flow/Vacuum |
| CV-2543-PLR | 5/4/2026 9:50:49 AM | 28.56 | 1337 | 34.4338390 | -118.6484637 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:Possible damaged valve |
| CV-2544 | 5/21/2026 1:52:17 PM | 28.41 | 1387 | 34.4340332 | -118.6472325 | Valve Adjustment:NSPS/EG CAC,Surging Liquid in Header |
| CV-2544 | 5/21/2026 1:51:00 PM | 28.41 | 1378 | 34.4340130 | -118.6472433 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Header |
| CV-2544 | 5/6/2026 11:06:39 AM | 28.6 | 1406 | 34.4340442 | -118.6472338 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-2545 | 5/22/2026 12:19:27 PM | 28.36 | 1404 | 34.4339908 | -118.6466957 | |
| CV-2545 | 5/22/2026 12:15:46 PM | 28.36 | 1407 | 34.4340295 | -118.6467170 | NSPS/EG CAI,NSPS/EG CAC,High Temp |
| CV-2545 | 5/6/2026 2:44:01 PM | 28.54 | 1393 | 34.4340488 | -118.6467080 | Valve Adjustment:NSPS/EG CAC,Barely Open,Surging Liquid in Header |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-2545 | 5/6/2026 2:43:10 PM | 28.54 | 1404 | 34.4340650 | -118.6467367 | Valve Adjustment:Increased Flow/Vacuum,Reduce Sys. Vac. - Flare Down |
| CV-2546 | 5/22/2026 12:25:12 PM | 28.37 | 1358 | 34.4341263 | -118.6470320 | |
| CV-2546 | 5/22/2026 12:24:00 PM | 28.37 | 1391 | 34.4341160 | -118.6470045 | NSPS/EG CAI,NSPS/EG CAC,High Temp |
| CV-2546 | 5/6/2026 2:35:53 PM | 28.56 | 1388 | 34.4341570 | -118.6469667 | Valve Adjustment:Barely Open |
| CV-2547 | 5/28/2026 12:23:14 PM | 28.48 | 1390 | 34.4339535 | -118.6459753 | Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum |
| CV-2547 | 5/22/2026 12:03:11 PM | 28.37 | 1385 | 34.4338917 | -118.6459037 | |
| CV-2547 | 5/6/2026 10:25:52 AM | 28.56 | 1381 | 34.4338955 | -118.6459930 | |
| CV-2548 | 5/13/2026 9:58:56 AM | 28.65 | 1397 | 34.4343410 | -118.6455860 | Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum,Barely Open |
| CV-2548 | 5/1/2026 10:34:59 AM | 28.46 | 1404 | 34.4344290 | -118.6456162 | |
| CV-2549 | 5/28/2026 12:13:13 PM | 28.48 | 1396 | 34.4343867 | -118.6452610 | Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum |
| CV-2549 | 5/13/2026 9:51:28 AM | 28.63 | 1395 | 34.4343673 | -118.6452592 | Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum,Barely Open;Well Condition:Good |
| CV-2549 | 5/6/2026 12:31:15 PM | 28.62 | 1395 | 34.4343742 | -118.6452492 | Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Barely Open;Well Condition:Good |
| CV-2549 | 5/1/2026 10:30:41 AM | 28.45 | 1424 | 34.4344408 | -118.6452425 | |
| CV-2550 | 5/27/2026 1:19:05 PM | 28.36 | 1388 | 34.4348365 | -118.6462116 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header |
| CV-2550 | 5/21/2026 10:06:57 AM | 28.5 | 1388 | 34.4348114 | -118.6461624 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Surging Liquid in Well (Watered In) |
| CV-2550 | 5/21/2026 10:04:40 AM | 28.5 | 1389 | 34.4348143 | -118.6461615 | Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum |
| CV-2550 | 5/11/2026 9:52:55 AM | 28.53 | 1390 | 34.4347874 | -118.6461669 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2550 | 5/4/2026 9:00:00 AM | | | | | AtmAA |
| CV-2550 | 5/4/2026 8:59:59 AM | 28.52 | 1386 | 34.4348107 | -118.6461652 | Valve Adjustment:Audible Flow,No Flow Measurement,High Temp |
| CV-2551 | 5/1/2026 2:40:59 PM | 28.29 | 1411 | 34.4349613 | -118.6458458 | |
| CV-2551 | 5/1/2026 2:39:32 PM | 28.29 | 1417 | 34.4349245 | -118.6458108 | High Temp,Audible Flow |
| CV-2552 | 5/19/2026 1:50:38 PM | 28.58 | 1391 | 34.4348880 | -118.6465470 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement |
| CV-2552 | 5/19/2026 1:49:24 PM | 28.58 | 1387 | 34.4348881 | -118.6465428 | Valve Adjustment:NSPS/EG CAI,No Flow Measurement,Increased Flow/Vacuum |
| CV-2552 | 5/11/2026 9:58:44 AM | 28.52 | 1402 | 34.4348833 | -118.6465278 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2552 | 5/4/2026 9:36:17 AM | 28.55 | 1388 | 34.4348703 | -118.6465369 | Valve Adjustment:High Temp |
| CV-2552 | 5/4/2026 9:35:00 AM | | | | | AtmAA |
| CV-2552 | 5/4/2026 9:35:00 AM | | | | | AtmAA; [User entered 6.71%] |
| CV-2553 | 5/20/2026 1:24:17 PM | 28.52 | 1343 | 34.4341850 | -118.6489165 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-2553 | 5/4/2026 9:36:18 AM | 28.56 | 1340 | 34.4341713 | -118.6489133 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-2554 | 5/28/2026 1:40:06 PM | 28.54 | 1370 | 34.4344472 | -118.6482645 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-2554 | 5/20/2026 2:11:24 PM | 28.53 | 1372 | 34.4344643 | -118.6482583 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2554 | 5/14/2026 11:13:27 AM | 28.62 | 1362 | 34.4344647 | -118.6482595 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2554 | 5/14/2026 11:12:34 AM | 28.65 | 1362 | 34.4344691 | -118.6482616 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-2554 | 5/14/2026 11:10:00 AM | | | | | AtmAA |
| CV-2554 | 5/4/2026 1:13:35 PM | 28.54 | 1358 | 34.4344623 | -118.6482596 | Valve Adjustment:High Temp |
| CV-2554 | 5/4/2026 1:12:59 PM | 28.53 | 1358 | 34.4344687 | -118.6482578 | Valve Adjustment:High Temp,Decreased Flow/Vacuum |
| CV-2554 | 5/4/2026 1:10:00 PM | | | | | AtmAA |
| CV-2554 | 5/4/2026 1:10:00 PM | | | | | AtmAA; [User entered 7.08%] |
| CV-2555 | 5/22/2026 11:41:33 AM | 28.47 | 1352 | 34.4348518 | -118.6476733 | NSPS/EG CAI,High O2 |
| CV-2555 | 5/22/2026 11:39:04 AM | 28.47 | 1388 | 34.4348375 | -118.6476383 | NSPS/EG CAI,High O2 |
| CV-2555 | 5/8/2026 1:12:17 PM | 28.52 | 1351 | 34.4348410 | -118.6477207 | Valve Adjustment:High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| CV-2556 | 5/27/2026 2:02:24 PM | 28.41 | 1368 | 34.4351675 | -118.6472263 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2556 | 5/19/2026 1:45:00 PM | | | | | AtmAA |
| CV-2556 | 5/19/2026 1:38:41 PM | 28.6 | 1386 | 34.4351709 | -118.6472403 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2556 | 5/11/2026 10:20:58 AM | 28.55 | 1383 | 34.4351541 | -118.6472084 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2556 | 5/4/2026 9:15:00 AM | | | | | AtmAA |
| CV-2556 | 5/4/2026 9:15:00 AM | | | | | AtmAA; [User entered 11.08%] |
| CV-2556 | 5/4/2026 9:13:52 AM | 28.54 | 1375 | 34.4351796 | -118.6472120 | Valve Adjustment:High Temp |
| CV-2557 | 5/20/2026 1:47:47 PM | 28.41 | 1380 | 34.4354737 | -118.6464625 | Valve Adjustment:Surging Liquid in Header |
| CV-2557 | 5/8/2026 8:36:19 AM | 28.57 | 1319 | 34.4354630 | -118.6466022 | No Flow Measurement,Reduced System Vacuum |
| CV-2558 | 5/27/2026 2:34:42 PM | 28.37 | 1390 | 34.4353057 | -118.6463321 | Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-2558 | 5/27/2026 2:33:21 PM | 28.38 | 1390 | 34.4353058 | -118.6463320 | Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Well (Watered In) |
| CV-2558 | 5/19/2026 1:15:50 PM | 28.58 | 1393 | 34.4353069 | -118.6463261 | Valve Comment:ACTIVE PLR;Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Well (Watered In) |
| CV-2558 | 5/19/2026 1:15:00 PM | | | | | AtmAA |
| CV-2558 | 5/14/2026 10:19:35 AM | 28.58 | 1396 | 34.4353019 | -118.6463204 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In) |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-2558 | 5/14/2026 10:18:44 AM | 28.58 | 1395 | 34.4352979 | -118.6463215 | Valve Comment:Active plr;Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In) |
| CV-2558 | 5/14/2026 10:15:00 AM | | | | | AtmAA |
| CV-2558 | 5/4/2026 8:47:30 AM | 28.49 | 1388 | 34.4353080 | -118.6463220 | Valve Comment:Active PLR;Valve Adjustment:Audible Flow,High Temp,Positive Static Press. |
| CV-2558 | 5/4/2026 8:45:31 AM | 28.49 | 1388 | 34.4353098 | -118.6463183 | Valve Comment:Active plr;Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press. |
| CV-2558 | 5/4/2026 8:45:00 AM | | | | | AtmAA |
| CV-2559 | 5/8/2026 8:53:26 AM | 28.57 | 1391 | 34.4357650 | -118.6454850 | NSPS/EG CAC,No Flow Measurement,Reduced System Vacuum |
| CV-2559 | 5/8/2026 8:49:36 AM | 28.57 | 1388 | 34.4357823 | -118.6454995 | Positive Static Press.,Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,NSPS/EG CAI |
| CV-2560 | 5/22/2026 10:39:45 AM | 28.37 | 1405 | 34.4359152 | -118.6466632 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-2560 | 5/12/2026 1:09:28 PM | 28.63 | 1390 | 34.4359102 | -118.6466652 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-2561 | 5/11/2026 2:38:47 PM | 28.47 | 1381 | 34.4360695 | -118.6467007 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-2562 | 5/11/2026 2:10:20 PM | 28.49 | 1414 | 34.4360810 | -118.6459618 | |
| CV-2563 | 5/28/2026 11:37:21 AM | 28.59 | 1299 | 34.4372952 | -118.6457702 | Valve Adjustment:NSPS/EG CAC |
| CV-2563 | 5/28/2026 11:36:57 AM | 28.59 | 1292 | 34.4373098 | -118.6457650 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum |
| CV-2563 | 5/15/2026 11:37:25 AM | 28.58 | 1224 | 34.4373225 | -118.6458008 | |
| CV-2563 | 5/15/2026 11:35:25 AM | 28.58 | 1280 | 34.4373478 | -118.6457748 | Reduced System Vacuum,Opened Valve 1/2 to 1 Turn,Positive Static Press.,NSPS/EG CAI,NSPS/EG CAC |
| CV-2564 | 5/21/2026 9:30:21 AM | 28.48 | 1361 | 34.4331228 | -118.6487310 | Valve Adjustment:NSPS/EG CAC,Barely Open |
| CV-2564 | 5/21/2026 9:29:15 AM | 28.48 | 1365 | 34.4331245 | -118.6487238 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum |
| CV-2564 | 5/1/2026 11:06:39 AM | 28.55 | 1356 | 34.4331307 | -118.6487373 | Valve Adjustment:Audible Flow,Barely Open |
| CV-2565 | 5/20/2026 9:51:50 AM | 28.52 | 1339 | 34.4319638 | -118.6490453 | |
| CV-2565 | 5/4/2026 9:20:17 AM | 28.52 | | | | |
| CV-2566 | 5/20/2026 9:46:01 AM | 28.51 | 1358 | 34.4317583 | -118.6487145 | |
| CV-2566 | 5/4/2026 9:24:42 AM | 28.52 | 1371 | 34.4317735 | -118.6487802 | |
| CV-2567 | 5/20/2026 12:20:18 PM | 28.47 | 1306 | 34.4318887 | -118.6480480 | |
| CV-2567 | 5/4/2026 9:43:22 AM | 28.51 | 1339 | 34.4319670 | -118.6480845 | |
| CV-2568 | 5/20/2026 11:39:12 AM | 28.48 | 1339 | 34.4322255 | -118.6478610 | |
| CV-2568 | 5/4/2026 11:23:44 AM | 28.51 | 1325 | 34.4321435 | -118.6477993 | |
| CV-2569 | 5/20/2026 11:29:23 AM | 28.48 | 1398 | 34.4322323 | -118.6472882 | |
| CV-2569 | 5/4/2026 11:29:19 AM | 28.51 | 1365 | 34.4322860 | -118.6473918 | |
| CV-2570 | 5/20/2026 11:15:26 AM | 28.5 | 1440 | 34.4325052 | -118.6471118 | |
| CV-2570 | 5/4/2026 11:34:49 AM | 28.51 | 1329 | 34.4324603 | -118.6470415 | |
| CV-2571 | 5/7/2026 1:00:36 PM | 28.75 | 1125 | 34.4299732 | -118.6457783 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| CV-2572 | 5/7/2026 1:32:16 PM | 28.73 | 1211 | 34.4298968 | -118.6470793 | |
| CV-48R | 5/28/2026 11:41:20 AM | 28.59 | 1304 | 34.4373368 | -118.6458555 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Well (Watered In) |
| CV-48R | 5/28/2026 11:40:34 AM | 28.59 | 1287 | 34.4373452 | -118.6458597 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Well (Watered In) |
| CV-48R | 5/15/2026 11:44:42 AM | 28.58 | 1312 | 34.4373598 | -118.6459028 | |
| CV-48R | 5/6/2026 10:23:03 AM | 28.7 | 1310 | 34.4373213 | -118.6458787 | Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum |
| CV-52D | 5/1/2026 1:17:29 PM | 28.66 | 1318 | 34.4359397 | -118.6424802 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In) |
| CV-55R | 5/27/2026 3:07:28 PM | 28.47 | 1316 | 34.4343666 | -118.6427811 | Valve Comment:Lorentz disconnected due to liner expansion;Valve Adjustment:High Temp |
| CV-55R | 5/21/2026 9:11:16 AM | 28.58 | 1324 | 34.4343888 | -118.6427691 | Valve Adjustment:NSPS/EG CAC |
| CV-55R | 5/21/2026 9:10:09 AM | 28.55 | 1306 | 34.4343699 | -118.6427853 | Valve Adjustment:NSPS/EG CAI,Increased Flow/Vacuum |
| CV-55R | 5/11/2026 11:02:29 AM | 28.61 | 1314 | 34.4343506 | -118.6427855 | Valve Adjustment:High Temp |
| CV-55R | 5/4/2026 8:05:00 AM | | | | | AtmAA |
| CV-55R | 5/4/2026 8:05:00 AM | | | | | AtmAA; [User entered 14.055%] |
| CV-55R | 5/4/2026 8:04:21 AM | 28.61 | 1319 | 34.4343259 | -118.6428242 | Valve Adjustment:High Temp |
| CV-56D | 5/7/2026 11:25:28 AM | 28.67 | 1286 | 34.4337902 | -118.6431927 | Reduced System Vacuum,NSPS/EG CAI,High O2 |
| CV-56D | 5/7/2026 11:22:51 AM | 28.67 | 1270 | 34.4338063 | -118.6432998 | NSPS/EG CAI,High O2,Reduced System Vacuum |
| CV-56S | 5/7/2026 11:32:33 AM | 28.67 | 1299 | 34.4337373 | -118.6431910 | Reduced System Vacuum,NSPS/EG CAI,High O2 |
| CV-56S | 5/7/2026 11:29:21 AM | 28.67 | 1329 | 34.4339453 | -118.6432662 | Reduced System Vacuum,NSPS/EG CAI,High O2 |
| CV-57R | 5/1/2026 2:21:40 PM | 28.52 | 1350 | 34.4343442 | -118.6435822 | Valve Adjustment:Increased Flow/Vacuum;Well Condition:Fair |
| CV-79R | 5/1/2026 2:41:23 PM | 28.54 | 1329 | 34.4332500 | -118.6448550 | Valve Adjustment:Audible Flow;Well Condition:Fair |
| CV-94 | 5/11/2026 3:29:38 PM | 28.52 | 1342 | 34.4349648 | -118.6436033 | |
| CV-94 | 5/11/2026 3:28:29 PM | 28.52 | 1332 | 34.4349903 | -118.6436197 | NSPS/EG CAI,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| CV-95 | 5/1/2026 2:19:24 PM | 28.52 | 1358 | 34.4343250 | -118.6436185 | Valve Adjustment:NSPS/EG CAC,Barely Open |
| CV-95 | 5/1/2026 2:18:38 PM | 28.52 | 1353 | 34.4343223 | -118.6436080 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open;Well Condition:Fair |
| CV-99 | 5/26/2026 1:51:48 PM | 28.43 | 1318 | 34.4370692 | -118.6463438 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-99 | 5/4/2026 7:45:00 AM | | | | | Air Tech Lab; [User entered 0.26%] |
| D-02 | 5/28/2026 3:29:22 PM | 28.68 | 1190 | 34.4311713 | -118.6443112 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| D-03 | 5/28/2026 3:32:52 PM | 28.67 | 1189 | 34.4311658 | -118.6443082 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| D-04 | 5/28/2026 3:41:09 PM | 28.68 | 1180 | 34.4311697 | -118.6443112 | Valve Adjustment:Valve 100% Open,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| D-09 | 5/7/2026 1:18:48 PM | 28.73 | 1168 | 34.4301310 | -118.6463358 | Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| D-10 | 5/7/2026 1:08:35 PM | 28.72 | 1109 | 34.4303733 | -118.6456953 | |
| FP-001 | 5/8/2026 9:19:36 AM | 28.62 | 1345 | 34.4366018 | -118.6458813 | Reduced System Vacuum,Audible Flow |
| FP-002 | 5/8/2026 9:28:39 AM | 28.61 | 1385 | 34.4366048 | -118.6462237 | Reduced System Vacuum |
| FP-003 | 5/8/2026 9:39:47 AM | 28.61 | 1381 | 34.4366380 | -118.6466182 | NSPS/EG CAI,High O2,Reduced System Vacuum |
| FP-003 | 5/8/2026 9:36:36 AM | 28.61 | 1355 | 34.4366733 | -118.6464832 | NSPS/EG CAI,High O2,Reduced System Vacuum |
| FP-005 | 5/15/2026 2:55:43 PM | 28.49 | 1385 | 34.4365253 | -118.6472332 | |
| FP-006 | 5/15/2026 2:51:55 PM | 28.5 | 1365 | 34.4364152 | -118.6476607 | |
| FP-008 | 5/15/2026 3:10:45 PM | 28.48 | 1391 | 34.4362947 | -118.6481520 | |
| FP-008 | 5/6/2026 9:22:39 AM | 28.63 | 1366 | 34.4363213 | -118.6481603 | Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum;Well Comment:Possibly watered in no system pressure |
| FP-009 | 5/13/2026 10:12:04 AM | 28.67 | 1370 | 34.4366912 | -118.6489365 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| FP-010 | 5/13/2026 10:03:04 AM | 28.66 | 1359 | 34.4365998 | -118.6492362 | Valve Adjustment:Decreased Flow/Vacuum |
| FP-011 | 5/13/2026 10:00:11 AM | 28.67 | 1354 | 34.4365362 | -118.6495148 | |
| FP-012 | 5/19/2026 8:39:03 AM | 28.58 | 1394 | 34.4366645 | -118.6499508 | |
| FP-012 | 5/1/2026 11:49:02 AM | 28.49 | 1420 | 34.4366962 | -118.6499643 | |
| FP-013 | 5/19/2026 9:34:22 AM | 28.59 | 1375 | 34.4365733 | -118.6502487 | Valve Adjustment:Increased Flow/Vacuum |
| FP-013 | 5/13/2026 9:55:27 AM | 28.67 | 1370 | 34.4365755 | -118.6502437 | Valve Adjustment:Barely Open |
| FP-014 | 5/13/2026 2:03:06 PM | 28.63 | 1359 | 34.4364897 | -118.6482270 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| FP-015 | 5/15/2026 2:35:16 PM | 28.53 | 1368 | 34.4364350 | -118.6478748 | |
| FP-015 | 5/14/2026 2:08:49 PM | 28.61 | 1345 | 34.4364805 | -118.6479392 | Valve Adjustment:Decreased Flow/Vacuum,Valve 100% Closed |
| FP-015 | 5/13/2026 2:12:26 PM | 28.63 | 1349 | 34.4364387 | -118.6479168 | Valve Adjustment:High Temp |
| FP-016 | 5/15/2026 2:43:10 PM | 28.5 | 1335 | 34.4365703 | -118.6476573 | |
| FP-016 | 5/13/2026 2:15:57 PM | 28.64 | 1360 | 34.4364905 | -118.6477060 | Valve Adjustment:Barely Open |
| FP-017 | 5/8/2026 12:57:34 PM | 28.57 | 1336 | 34.4344060 | -118.6486553 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| FP-018 | 5/8/2026 12:40:54 PM | 28.57 | 1355 | 34.4344607 | -118.6490808 | |
| FP-019 | 5/12/2026 1:48:27 PM | 28.58 | 1324 | 34.4346590 | -118.6491418 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| FP-020 | 5/12/2026 1:57:00 PM | 28.6 | 1328 | 34.4349558 | -118.6492892 | Valve Adjustment:Barely Open |
| FP-021 | 5/13/2026 10:41:14 AM | 28.7 | 1341 | 34.4352002 | -118.6491838 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| FP-021 | 5/12/2026 1:59:43 PM | 28.57 | 1331 | 34.4351600 | -118.6495498 | Valve Adjustment:Decreased Flow/Vacuum |
| FP-022 | 5/13/2026 10:32:37 AM | 28.7 | 1358 | 34.4352390 | -118.6491458 | Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum |
| FP-023 | 5/13/2026 1:46:18 PM | 28.64 | 1345 | 34.4355123 | -118.6494168 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| FP-024 | 5/20/2026 2:16:33 PM | 28.45 | 1362 | 34.4354970 | -118.6477955 | Valve Adjustment:Barely Open |
| FP-025 | 5/20/2026 2:19:20 PM | 28.45 | 1361 | 34.4353510 | -118.6477598 | Valve Adjustment:Decreased Flow/Vacuum |
| FP-026 | 5/29/2026 4:20:14 PM | 28.63 | 1352 | 34.4350803 | -118.6481360 | |
| FP-027 | 5/29/2026 4:24:24 PM | 28.63 | 1359 | 34.4348312 | -118.6482373 | |
| FP-028 | 5/28/2026 11:39:27 AM | 28.5 | 1371 | 34.4346913 | -118.6483355 | |
| FP-029 | 5/28/2026 11:31:57 AM | 28.51 | 1296 | 34.4343368 | -118.6488995 | |
| FP-030 | 5/12/2026 1:41:15 PM | 28.59 | 1307 | 34.4345017 | -118.6496773 | Valve Adjustment:Barely Open |
| FP-031 | 5/29/2026 9:22:16 AM | 28.66 | 1347 | 34.4348340 | -118.6497520 | |
| FP-031 | 5/12/2026 1:37:06 PM | 28.59 | 1320 | 34.4348330 | -118.6497772 | Valve Adjustment:Decreased Flow/Vacuum |
| FP-032 | 5/12/2026 1:28:30 PM | 28.58 | 1334 | 34.4351075 | -118.6498378 | Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum |
| FP-033 | 5/12/2026 1:23:05 PM | 28.58 | 1346 | 34.4353872 | -118.6499523 | Valve Adjustment:Decreased Flow/Vacuum |
| FP-034 | 5/12/2026 1:19:44 PM | 28.55 | 1357 | 34.4356307 | -118.6500237 | Valve Adjustment:Barely Open |
| FP-035 | 5/12/2026 1:16:01 PM | 28.56 | 1362 | 34.4358548 | -118.6501185 | Valve Adjustment:Decreased Flow/Vacuum |
| FP-036 | 5/1/2026 11:36:11 AM | 28.52 | 1401 | 34.4361558 | -118.6502323 | Valve Adjustment:Barely Open |
| FP-037 | 5/19/2026 10:33:25 AM | 28.61 | 1366 | 34.4362913 | -118.6502602 | |
| FP-037 | 5/1/2026 11:38:38 AM | 28.49 | 1388 | 34.4362773 | -118.6503153 | Valve Adjustment:Barely Open |
| FP-038 | 5/14/2026 2:24:47 PM | 28.55 | 1348 | 34.4342242 | -118.6499053 | |
| FP-039 | 5/14/2026 2:15:09 PM | 28.57 | 1306 | 34.4341813 | -118.6498180 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| FP-040 | 5/29/2026 2:30:36 PM | 28.58 | 1325 | 34.4353275 | -118.6510755 | |
| FP-041 | 5/13/2026 1:16:55 PM | 28.66 | 1237 | 34.4339895 | -118.6506525 | |
| FP-042 | 5/20/2026 10:11:54 AM | 28.63 | 1251 | 34.4332757 | -118.6512885 | |
| FP-043 | 5/13/2026 1:22:06 PM | 28.66 | 1211 | 34.4342865 | -118.6506492 | |
| FP-044 | 5/13/2026 1:25:38 PM | 28.66 | 1224 | 34.4346217 | -118.6507967 | |
| FP-045 | 5/11/2026 1:04:40 PM | 28.63 | 1322 | 34.4334380 | -118.6496432 | |
| FP-046 | 5/15/2026 3:02:41 PM | 28.49 | 1329 | 34.4365908 | -118.6471652 | |
| FP-047 | 5/29/2026 11:36:35 AM | 28.62 | 1312 | 34.4366965 | -118.6469575 | |
| FP-050 | 5/6/2026 2:53:31 PM | 28.57 | 1364 | 34.4348978 | -118.6472845 | Valve Adjustment:Decreased Flow/Vacuum |
| FP-051 | 5/6/2026 2:48:25 PM | 28.56 | 1380 | 34.4347007 | -118.6470228 | Valve Adjustment:Decreased Flow/Vacuum |
| FP-052 | 5/22/2026 2:09:54 PM | 28.37 | 1335 | 34.4343828 | -118.6481260 | |
| FP-052 | 5/4/2026 2:20:50 PM | 28.52 | 1366 | 34.4342270 | -118.6481385 | |
| FP-053 | 5/21/2026 2:19:03 PM | 28.41 | 1382 | 34.4340420 | -118.6477340 | Valve Adjustment:Increased Flow/Vacuum,Valve 100% Open |
| FP-053 | 5/4/2026 2:08:41 PM | 28.5 | 1380 | 34.4340587 | -118.6477530 | Valve Adjustment:Barely Open |
| FP-054 | 5/1/2026 11:30:37 AM | 28.45 | 1394 | 34.4349998 | -118.6457865 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| FP-055 | 5/20/2026 2:00:54 PM | 28.48 | 1364 | 34.4336087 | -118.6481788 | Valve Adjustment:Increased Flow/Vacuum |
| FP-055 | 5/4/2026 10:03:30 AM | 28.53 | 1350 | 34.4336195 | -118.6481682 | |
| FP-056 | 5/4/2026 9:15:22 AM | 28.52 | 1356 | 34.4334657 | -118.6486362 | |
| FP-057 | 5/4/2026 9:17:47 AM | 28.52 | 1353 | 34.4333977 | -118.6485917 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:no system port |
| FP-057 | 5/1/2026 11:34:44 AM | 28.45 | 1358 | 34.4347868 | -118.6454630 | |
| FP-058 | 5/29/2026 3:51:49 PM | 28.51 | 1427 | 34.4350023 | -118.6458712 | |
| FP-059 | 5/1/2026 2:35:49 PM | 28.41 | 1322 | 34.4345693 | -118.6459352 | |
| FP-060 | 5/1/2026 2:53:38 PM | 28.4 | 1371 | 34.4349418 | -118.6461343 | |
| FP-061 | 5/15/2026 2:38:19 PM | 28.5 | 1375 | 34.4364535 | -118.6480250 | |
| FP-061 | 5/14/2026 2:22:44 PM | 28.61 | 1347 | 34.4364610 | -118.6479475 | Valve Adjustment:Orifice Plate Changed (See OP Log) |
| FP-061 | 5/14/2026 2:19:38 PM | 28.61 | 1343 | 34.4364735 | -118.6479645 | Valve Adjustment:Decreased Flow/Vacuum |
| H-01 (EXP-01) | 5/26/2026 8:45:19 AM | 28.63 | 1238 | 34.4376920 | -118.6441722 | Valve Adjustment:Audible Flow,Barely Open |
| H-01 (EXP-01) | 5/12/2026 1:49:58 PM | 28.72 | 1218 | 34.4376842 | -118.6441523 | |
| H-02 (EXP-02) | 5/26/2026 8:27:48 AM | 28.62 | 1250 | 34.4377123 | -118.6445873 | Valve Adjustment:Barely Open,Surging Liquid in Well (Watered In) |
| H-02 (EXP-02) | 5/12/2026 1:55:38 PM | 28.72 | 1226 | 34.4376910 | -118.6445842 | |
| H-03 (EXP-03) | 5/26/2026 8:31:53 AM | 28.59 | 1250 | 34.4377153 | -118.6446182 | Valve Adjustment:Audible Flow |
| H-03 (EXP-03) | 5/12/2026 2:02:02 PM | 28.73 | 1231 | 34.4377085 | -118.6446410 | |
| H-04 (EXP-04) | 5/26/2026 8:34:46 AM | 28.61 | 1250 | 34.4377263 | -118.6446790 | Valve Adjustment:Barely Open |
| H-04 (EXP-04) | 5/14/2026 10:16:02 AM | 28.8 | 1272 | 34.4376853 | -118.6447197 | Valve Adjustment:NSPS/EG CAI,High Temp |
| H-04 (EXP-04) | 5/14/2026 10:14:56 AM | 28.82 | 1273 | 34.4376952 | -118.6446813 | Valve Adjustment:NSPS/EG CAC,High Temp |
| H-04 (EXP-04) | 5/14/2026 10:13:50 AM | 28.82 | 1242 | 34.4377102 | -118.6447060 | Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum |
| H-08 (EXP-08) | 5/26/2026 8:55:13 AM | 28.59 | 1294 | 34.4378447 | -118.6465338 | Valve Adjustment:Audible Flow |
| H-08 (EXP-08) | 5/11/2026 9:46:50 AM | 28.64 | 1271 | 34.4378388 | -118.6465160 | |
| H-10 (EXP-10) | 5/26/2026 9:06:45 AM | 28.56 | 1307 | 34.4374403 | -118.6470750 | Valve Adjustment:Audible Flow,Decreased Flow/Vacuum |
| H-10 (EXP-10) | 5/11/2026 9:40:46 AM | 28.64 | 1297 | 34.4374428 | -118.6470835 | Valve Adjustment:Barely Open |
| H-10 (EXP-10) | 5/11/2026 9:40:06 AM | 28.64 | 1291 | 34.4374607 | -118.6470725 | Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum |
| H-101W | 5/13/2026 8:32:50 AM | 28.82 | 1199 | 34.4310828 | -118.6505710 | Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In);Well Repairs:Valve |
| H-101W | 5/13/2026 8:24:13 AM | 28.82 | 1204 | 34.4310752 | -118.6505745 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum |
| H-102A | 5/13/2026 8:17:41 AM | 28.81 | 1210 | 34.4310967 | -118.6505652 | Valve Adjustment:Increased Flow/Vacuum;Well Repairs:Sample Port |
| H-1401W | 5/13/2026 8:48:53 AM | 28.82 | 1200 | 34.4310877 | -118.6505600 | Valve Adjustment:Increased Flow/Vacuum,Surging Liquid in Header |
| H-1404C | 5/20/2026 11:55:54 AM | 28.48 | 1394 | 34.4323593 | -118.6482932 | |
| H-1404C | 5/4/2026 11:20:18 AM | 28.51 | 1407 | 34.4324288 | -118.6483063 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| H-1405C | 5/20/2026 8:39:42 AM | 28.58 | 1312 | 34.4325898 | -118.6497317 | Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header |
| H-1405C | 5/1/2026 10:13:01 AM | 28.6 | 1301 | 34.4325790 | -118.6497293 | Valve Adjustment:Audible Flow,Decreased Flow/Vacuum,Surging Liquid in Header |
| H-1406W | 5/20/2026 9:30:46 AM | 28.63 | 1256 | 34.4321807 | -118.6507710 | Valve Adjustment:Decreased Flow/Vacuum |
| H-1406W | 5/1/2026 10:30:28 AM | 28.65 | 1255 | 34.4321702 | -118.6507820 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:Valve damaged |
| H-1408CR | 5/6/2026 2:48:15 PM | 28.62 | 1260 | 34.4314735 | -118.6473962 | |
| H-1408CR | 5/6/2026 2:46:51 PM | 28.62 | 1263 | 34.4314803 | -118.6473372 | NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-1408E | 5/20/2026 2:13:20 PM | 28.49 | 1396 | 34.4333353 | -118.6471580 | Valve Adjustment:Surging Liquid in Header |
| H-1408E | 5/4/2026 2:44:00 PM | 28.45 | 1417 | 34.4334305 | -118.6473195 | |
| H-1408E | 5/4/2026 2:42:19 PM | 28.45 | 1407 | 34.4334643 | -118.6471968 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,NSPS/EG CAI,NSPS/EG CAC,Positive Static Press. |
| H-1408W | 5/7/2026 10:26:18 AM | 28.64 | 1257 | 34.4311628 | -118.6500330 | Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-1409N | 5/20/2026 2:26:47 PM | 28.41 | 1434 | 34.4327785 | -118.6468967 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-1409N | 5/4/2026 2:02:48 PM | 28.48 | 1434 | 34.4328577 | -118.6469445 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-1410S | 5/6/2026 12:22:14 PM | 28.71 | 1158 | 34.4310043 | -118.6467432 | |
| H-1563N | 5/22/2026 2:12:17 PM | 28.44 | 1318 | 34.4338717 | -118.6498188 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| H-1563N | 5/11/2026 12:47:48 PM | 28.63 | 1320 | 34.4338583 | -118.6498358 | Valve Adjustment:Reduce Sys. Vac. - Flare Down |
| H-1563S | 5/20/2026 8:43:45 AM | 28.58 | 1309 | 34.4323993 | -118.6496597 | |
| H-1563S | 5/1/2026 10:06:27 AM | 28.59 | 1317 | 34.4323920 | -118.6496645 | Valve Adjustment:Barely Open |
| H-1565E | 5/21/2026 10:26:51 AM | 28.41 | 1403 | 34.4335533 | -118.6472303 | Valve Adjustment:Barely Open,Surging Liquid in Header |
| H-1565E | 5/6/2026 10:50:58 AM | 28.6 | 1387 | 34.4335490 | -118.6471893 | Valve Adjustment:Barely Open,Surging Liquid in Header |
| H-1568N | 5/21/2026 10:57:34 AM | 28.44 | 1387 | 34.4339032 | -118.6470792 | Valve Adjustment:Barely Open |
| H-1568N | 5/20/2026 2:05:18 PM | 28.49 | 1388 | 34.4333292 | -118.6471738 | |
| H-1568N | 5/4/2026 2:46:50 PM | 28.42 | 1381 | 34.4333778 | -118.6471675 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-1571S | 5/4/2026 11:05:46 AM | 28.63 | 1273 | 34.4321600 | -118.6452273 | Valve Adjustment:Decreased Flow/Vacuum |
| H-1572N | 5/1/2026 2:47:42 PM | 28.48 | 1358 | 34.4336958 | -118.6447368 | Valve Adjustment:Increased Flow/Vacuum |
| H-1572S | 5/4/2026 10:51:40 AM | 28.67 | 1263 | 34.4321853 | -118.6447270 | Valve Adjustment:Decreased Flow/Vacuum |
| H-1574N | 5/20/2026 10:38:18 AM | 28.67 | 1224 | 34.4325223 | -118.6517647 | Valve Adjustment:Barely Open |
| H-1574N | 5/13/2026 9:52:29 AM | 28.65 | 1369 | 34.4365228 | -118.6501082 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| H-1574N | 5/12/2026 8:59:40 AM | 28.68 | 1270 | 34.4324318 | -118.6518578 | |
| H-1753N | 5/26/2026 9:00:32 AM | 28.45 | 1347 | 34.4347247 | -118.6493153 | Valve Adjustment:Barely Open |
| H-1753N | 5/12/2026 1:45:21 PM | 28.58 | 1327 | 34.4347443 | -118.6493200 | Valve Adjustment:Barely Open |
| H-1753S | 5/22/2026 2:02:07 PM | 28.41 | 1343 | 34.4339337 | -118.6495725 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| H-1753S | 5/11/2026 12:40:59 PM | 28.61 | 1325 | 34.4339465 | -118.6495767 | Valve Adjustment:Reduce Sys. Vac. - Flare Down |
| H-1756S | 5/19/2026 1:28:24 PM | 28.65 | 1289 | 34.4325650 | -118.6502857 | Valve Adjustment:NSPS/EG CAI,Barely Open |
| H-1756S | 5/19/2026 1:25:39 PM | 28.66 | 1295 | 34.4325747 | -118.6502920 | Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum |
| H-1756S | 5/13/2026 12:47:50 PM | 28.67 | 1247 | 34.4325943 | -118.6502308 | |
| H-1757S | 5/20/2026 8:35:55 AM | 28.59 | 1313 | 34.4327182 | -118.6497730 | |
| H-1757S | 5/1/2026 10:14:46 AM | 28.61 | 1308 | 34.4327065 | -118.6497760 | Valve Adjustment:Audible Flow;Well Condition:Fair |
| H-1760S | 5/21/2026 10:10:39 AM | 28.44 | 1388 | 34.4327248 | -118.6479115 | Valve Adjustment:Barely Open |
| H-1760S | 5/11/2026 1:37:59 PM | 28.57 | 1387 | 34.4327687 | -118.6479202 | Valve Adjustment:Reduce Sys. Vac. - Flare Down |
| H-1762N | 5/20/2026 1:57:03 PM | 28.49 | 1387 | 34.4334418 | -118.6468622 | |
| H-1762N | 5/20/2026 1:55:17 PM | 28.47 | 1390 | 34.4334503 | -118.6468817 | Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Increased Flow/Vacuum |
| H-1762N | 5/4/2026 2:38:51 PM | 28.45 | 1421 | 34.4335587 | -118.6469227 | |
| H-1763N | 5/6/2026 10:36:14 AM | 28.56 | 1375 | 34.4335967 | -118.6461747 | |
| H-1763N | 5/6/2026 10:34:51 AM | 28.56 | 1339 | 34.4336130 | -118.6461267 | NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-1763S | 5/4/2026 11:26:50 AM | 28.61 | 1319 | 34.4323963 | -118.6460432 | Valve Adjustment:Decreased Flow/Vacuum |
| H-1764N | 5/28/2026 12:39:39 PM | 28.52 | 1367 | 34.4331603 | -118.6456347 | Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum |
| H-1764N | 5/5/2026 1:16:30 PM | 28.52 | 1369 | 34.4331572 | -118.6456352 | Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum |
| H-1764N | 5/4/2026 11:45:03 AM | 28.55 | 1357 | 34.4331618 | -118.6456243 | Valve Adjustment:Audible Flow,Increased Flow/Vacuum |
| H-1764S | 5/4/2026 11:08:05 AM | 28.63 | 1295 | 34.4321740 | -118.6454062 | |
| H-1767N | 5/11/2026 9:51:22 AM | 28.62 | 1224 | 34.4326290 | -118.6435573 | |
| H-1769N | 5/19/2026 8:53:05 AM | 28.59 | 1365 | 34.4370255 | -118.6494768 | Valve Adjustment:Audible Flow,Barely Open |
| H-1769N | 5/1/2026 2:30:15 PM | 28.46 | 1358 | 34.4370625 | -118.6495027 | |
| H-1770N | 5/19/2026 9:18:49 AM | 28.59 | 1368 | 34.4368203 | -118.6500283 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open |
| H-1770N | 5/4/2026 8:50:00 AM | | | | | Air Tech Lab; [User entered 1.2%] |
| H-1770N | 5/1/2026 2:42:44 PM | 28.45 | 1342 | 34.4368195 | -118.6500292 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| H-1770S | 5/19/2026 12:50:46 PM | 28.63 | 1315 | 34.4331262 | -118.6501585 | Valve Adjustment:Barely Open |
| H-1770S | 5/1/2026 10:34:30 AM | 28.6 | 1320 | 34.4331097 | -118.6501593 | Valve Adjustment:Decreased Flow/Vacuum |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| H-1771A | 5/11/2026 2:21:58 PM | 28.5 | 1381 | 34.4363332 | -118.6463698 | |
| H-1771B | 5/13/2026 11:22:20 AM | 28.67 | 1392 | 34.4355247 | -118.6466602 | Valve Adjustment:NSPS/EG CAI,High Temp |
| H-1771B | 5/13/2026 11:19:01 AM | 30 | 1397 | 34.4355318 | -118.6466588 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum |
| H-1771B | 5/11/2026 1:05:25 PM | 28.52 | 1379 | 34.4355532 | -118.6466608 | Valve Adjustment:Positive Static Press.,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| H-1771B | 5/11/2026 1:04:43 PM | 28.52 | 1380 | 34.4355432 | -118.6466587 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| H-1774N | 5/19/2026 9:58:15 AM | 28.62 | 1352 | 34.4367243 | -118.6508037 | Valve Adjustment:Barely Open |
| H-1774N | 5/12/2026 10:34:14 AM | 28.59 | 1355 | 34.4366473 | -118.6509118 | |
| H-1801S | 5/11/2026 11:15:54 AM | 28.66 | 1299 | 34.4338058 | -118.6441812 | No Adjustment Made |
| H-1802S | 5/1/2026 2:44:17 PM | 28.51 | 1350 | 34.4335672 | -118.6447667 | Valve Adjustment:Increased Flow/Vacuum |
| H-1803N | 5/26/2026 9:42:57 AM | 28.47 | 1373 | 34.4370350 | -118.6485700 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In) |
| H-1803N | 5/18/2026 10:00:00 AM | | | | | AtmAA |
| H-1803N | 5/18/2026 9:58:45 AM | 28.52 | 1354 | 34.4370325 | -118.6485770 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In) |
| H-1803N | 5/12/2026 9:08:34 AM | 28.55 | 1345 | 34.4370158 | -118.6486076 | Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open |
| H-1803N | 5/12/2026 9:05:00 AM | | | | | AtmAA |
| H-1803N | 5/5/2026 9:07:24 AM | 28.51 | 1349 | 34.4370299 | -118.6486000 | Valve Comment:ACTIVE PLR;Valve Adjustment:No Flow Measurement,High Temp |
| H-1803N | 5/5/2026 9:00:00 AM | | | | | AtmAA |
| H-1803N | 5/5/2026 9:00:00 AM | | | | | AtmAA; [User entered 17.07%] |
| H-1804B | 5/1/2026 10:39:08 AM | 28.46 | 1391 | 34.4342722 | -118.6456027 | |
| H-1804N | 5/8/2026 9:11:50 AM | 28.61 | 1348 | 34.4363567 | -118.6457242 | Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-1804S | 5/4/2026 11:47:34 AM | 28.56 | 1365 | 34.4330883 | -118.6456972 | Valve Adjustment:Increased Flow/Vacuum,Surging Liquid in Header |
| H-1805A | 5/1/2026 11:19:57 AM | 28.46 | 1368 | 34.4351310 | -118.6450843 | |
| H-1805B | 5/4/2026 11:52:01 AM | 28.53 | 1379 | 34.4337287 | -118.6451562 | |
| H-1805S | 5/4/2026 11:39:55 AM | 28.59 | 1326 | 34.4329170 | -118.6451598 | Valve Adjustment:Audible Flow |
| H-1806A | 5/1/2026 11:08:54 AM | 28.46 | 1385 | 34.4353900 | -118.6442890 | |
| H-1806B | 5/1/2026 2:52:26 PM | 28.48 | 1365 | 34.4339000 | -118.6444555 | |
| H-1806N | 5/11/2026 11:37:48 AM | 28.52 | 1398 | 34.4364753 | -118.6449213 | |
| H-1806S | 5/4/2026 10:39:51 AM | 28.64 | 1285 | 34.4328797 | -118.6444580 | Valve Adjustment:Audible Flow,Decreased Flow/Vacuum |
| H-1807A | 5/4/2026 1:18:09 PM | 28.58 | 1344 | 34.4353387 | -118.6436233 | Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Surging Liquid in Header |
| H-1807N | 5/29/2026 10:10:34 AM | 28.63 | 1325 | 34.4364860 | -118.6435677 | No Adjustment Made |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| H-1807S | 5/7/2026 11:08:13 AM | 28.67 | 1266 | 34.4337920 | -118.6433665 | Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-1952S | 5/21/2026 2:14:50 PM | 28.41 | 1387 | 34.4338018 | -118.6476160 | Valve Adjustment:NSPS/EG CAC,Barely Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| H-1952S | 5/21/2026 2:13:14 PM | 28.41 | 1386 | 34.4338123 | -118.6476157 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| H-1952S | 5/4/2026 2:04:02 PM | 28.49 | 1364 | 34.4338018 | -118.6476148 | Valve Adjustment:Increased Flow/Vacuum |
| H-1955C | 5/1/2026 11:26:41 AM | 28.44 | 1388 | 34.4350727 | -118.6454042 | |
| H-1955N | 5/8/2026 9:07:44 AM | 28.62 | 1339 | 34.4364617 | -118.6455018 | Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-1956B | 5/1/2026 10:44:44 AM | 28.46 | 1391 | 34.4342613 | -118.6447408 | |
| H-1956N | 5/11/2026 11:40:47 AM | 28.53 | 1329 | 34.4365163 | -118.6449683 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-1956S | 5/1/2026 2:39:31 PM | 28.54 | 1338 | 34.4332363 | -118.6448778 | Valve Adjustment:Audible Flow,Decreased Flow/Vacuum |
| H-1957B | 5/6/2026 2:10:22 PM | 28.61 | 1381 | 34.4345577 | -118.6440863 | |
| H-1957B | 5/1/2026 2:13:12 PM | 28.48 | 1374 | 34.4345740 | -118.6440963 | |
| H-1957N | 5/11/2026 11:33:03 AM | 28.54 | 1342 | 34.4364202 | -118.6443038 | |
| H-1957S | 5/11/2026 11:18:08 AM | 28.61 | 1339 | 34.4338067 | -118.6441572 | |
| H-1958C | 5/4/2026 1:20:33 PM | 28.59 | 1333 | 34.4353942 | -118.6434847 | Valve Adjustment:Audible Flow |
| H-1958N | 5/28/2026 1:56:37 PM | 28.52 | 1354 | 34.4364505 | -118.6435238 | Valve Adjustment:Barely Open |
| H-1958S | 5/7/2026 11:03:31 AM | 28.67 | 1299 | 34.4339642 | -118.6433052 | Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-1962N | 5/19/2026 9:28:05 AM | 28.59 | 1369 | 34.4366552 | -118.6501363 | Valve Adjustment:Decreased Flow/Vacuum |
| H-1962N | 5/19/2026 9:26:00 AM | 28.6 | 1364 | 34.4366772 | -118.6501218 | Valve Adjustment:Decreased Flow/Vacuum |
| H-1962N | 5/1/2026 2:46:00 PM | 28.45 | 1347 | 34.4366583 | -118.6501298 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| H-1963N | 5/19/2026 8:46:36 AM | 28.59 | 1378 | 34.4369248 | -118.6495362 | Valve Adjustment:NSPS/EG CAI,High Temp |
| H-1963N | 5/19/2026 8:44:46 AM | 28.59 | 1379 | 34.4369250 | -118.6495370 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum |
| H-1963N | 5/1/2026 12:06:22 PM | 28.49 | 1383 | 34.4369102 | -118.6495877 | Valve Adjustment:NSPS/EG CAC,High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| H-1963N | 5/1/2026 12:04:32 PM | 28.51 | 1362 | 34.4368882 | -118.6495335 | Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| H-1966N | 5/19/2026 10:06:37 AM | 28.62 | 1344 | 34.4365543 | -118.6507988 | |
| H-1966N | 5/12/2026 10:42:28 AM | 28.59 | 1339 | 34.4365167 | -118.6507485 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-1967E | 5/7/2026 1:04:55 PM | 28.72 | 1152 | 34.4302350 | -118.6459632 | Reduced System Vacuum |
| H-1967W | 5/7/2026 9:49:11 AM | 28.71 | 1257 | 34.4298232 | -118.6507763 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| H-1967W | 5/7/2026 9:47:56 AM | 28.71 | 1201 | 34.4298152 | -118.6507190 | Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-2050E | 5/14/2026 9:38:59 AM | 28.8 | 1119 | 34.4291773 | -118.6475780 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-2050W | 5/5/2026 3:39:36 PM | 28.63 | 1188 | 34.4291558 | -118.6491385 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-2051W | 5/7/2026 9:44:33 AM | 28.61 | 1204 | 34.4299358 | -118.6507733 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-2053E | 5/7/2026 1:13:15 PM | 28.73 | 1115 | 34.4302400 | -118.6459330 | Reduced System Vacuum |
| H-2053W | 5/13/2026 8:39:25 AM | 28.81 | 1205 | 34.4310888 | -118.6505722 | Valve Adjustment:Increased Flow/Vacuum |
| H-2055E | 5/22/2026 10:10:19 AM | 28.55 | 1276 | 34.4318162 | -118.6465767 | |
| H-2055E | 5/6/2026 3:07:33 PM | 28.63 | 1322 | 34.4319158 | -118.6466957 | |
| H-2056B | 5/8/2026 3:07:26 PM | 28.68 | 1119 | 34.4297018 | -118.6474618 | |
| H-2056W | 5/7/2026 9:41:29 AM | 28.66 | 1201 | 34.4299912 | -118.6505983 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-2057E | 5/7/2026 1:10:46 PM | 28.72 | 1125 | 34.4302735 | -118.6459342 | Reduced System Vacuum |
| H-2057W | 5/28/2026 8:44:04 AM | 28.7 | 1195 | 34.4306532 | -118.6506315 | Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum |
| H-2057W | 5/13/2026 8:09:16 AM | 28.82 | 1194 | 34.4306418 | -118.6506340 | Valve Adjustment:Barely Open;Well Repairs:Sample Port |
| H-2057W | 5/13/2026 8:05:12 AM | 28.82 | 1193 | 34.4306693 | -118.6506338 | Valve Adjustment:NSPS/EG CAI,Decreased Flow/Vacuum;Well Repairs:Sample Port |
| H-2058E | 5/7/2026 1:22:33 PM | 28.72 | 1096 | 34.4300088 | -118.6465828 | Reduced System Vacuum |
| H-2058W | 5/7/2026 9:34:28 AM | 28.77 | 1211 | 34.4299087 | -118.6508643 | |
| H-2058W | 5/7/2026 9:33:03 AM | 28.77 | 1181 | 34.4299318 | -118.6509787 | NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-2059E | 5/6/2026 12:36:07 PM | 28.75 | 1142 | 34.4306302 | -118.6462412 | |
| H-2059W | 5/7/2026 10:12:44 AM | 28.67 | 1184 | 34.4311415 | -118.6502280 | |
| H-2161E | 5/6/2026 12:32:34 PM | 28.73 | 1181 | 34.4308358 | -118.6463493 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-2161W | 5/7/2026 10:08:23 AM | 28.67 | 1283 | 34.4309113 | -118.6502148 | |
| H-2163C | 5/22/2026 10:05:49 AM | 28.44 | 1296 | 34.4310082 | -118.6486600 | |
| H-2163C | 5/4/2026 10:05:22 AM | 28.54 | 1293 | 34.4311252 | -118.6486480 | |
| H-2163W | 5/7/2026 10:22:23 AM | 28.66 | 1240 | 34.4311995 | -118.6498642 | Reduced System Vacuum |
| H-2164E | 5/22/2026 10:41:07 AM | 28.55 | 1280 | 34.4318698 | -118.6460668 | No Adjustment Made |
| H-2164E | 5/6/2026 3:22:38 PM | 28.62 | 1276 | 34.4319407 | -118.6460057 | |
| H-2164E | 5/6/2026 3:21:24 PM | 28.62 | 1296 | 34.4319637 | -118.6460188 | NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-2165E | 5/4/2026 10:55:10 AM | 28.67 | 1243 | 34.4318965 | -118.6451208 | Valve Adjustment:Audible Flow,Decreased Flow/Vacuum |
| H-2165W | 5/20/2026 9:46:57 AM | 28.63 | 1288 | 34.4321328 | -118.6504533 | Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header |
| H-2165W | 5/12/2026 7:45:00 AM | | | | | Air Tech Lab |
| H-2165W | 5/12/2026 7:45:00 AM | | | | | Air Tech Lab; [User entered 4.8%] |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| H-2165W | 5/1/2026 10:16:24 AM | 28.64 | 1271 | 34.4321427 | -118.6504262 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| H-2166E | 5/4/2026 1:12:58 PM | 28.55 | 1371 | 34.4356305 | -118.6438722 | |
| H-2168C | 5/1/2026 10:48:38 AM | 28.47 | 1375 | 34.4344292 | -118.6448553 | |
| H-2168E | 5/28/2026 12:08:16 PM | 28.52 | 1377 | 34.4345323 | -118.6439110 | Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum |
| H-2168E | 5/6/2026 2:36:05 PM | 28.63 | 1372 | 34.4345347 | -118.6439215 | Valve Adjustment:Audible Flow;Well Condition:Fair |
| H-2168E | 5/5/2026 10:39:26 AM | 28.51 | 1370 | 34.4345318 | -118.6439165 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAC |
| H-2168E | 5/5/2026 10:37:49 AM | 28.51 | 1375 | 34.4345350 | -118.6438788 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Surging Liquid in Well (Watered In) |
| H-2168E | 5/1/2026 2:15:28 PM | 28.48 | 1373 | 34.4345518 | -118.6439033 | |
| H-2169C | 5/4/2026 11:55:39 AM | 28.52 | 1394 | 34.4340773 | -118.6450443 | Valve Adjustment:Audible Flow,Increased Flow/Vacuum |
| H-2169E | 5/1/2026 2:05:32 PM | 28.49 | 1376 | 34.4342528 | -118.6442070 | Valve Adjustment:Audible Flow;Well Condition:Fair |
| H-2170N | 5/4/2026 2:04:41 PM | 28.63 | 1269 | 34.4358222 | -118.6414655 | Valve Adjustment:Audible Flow |
| H-2170S | 5/11/2026 8:29:12 AM | 28.69 | 1273 | 34.4336432 | -118.6414673 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-2171A | 5/14/2026 8:58:08 AM | 28.7 | 1280 | 34.4373700 | -118.6425202 | Valve Adjustment:Barely Open |
| H-2171A | 5/14/2026 8:54:11 AM | 28.69 | 1274 | 34.4373835 | -118.6425463 | Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum |
| H-2171A | 5/13/2026 10:13:53 AM | 28.78 | 1255 | 34.4374078 | -118.6425213 | |
| H-2171A | 5/13/2026 10:08:18 AM | 28.79 | 1248 | 34.4373908 | -118.6425195 | Valve Adjustment:Decreased Flow/Vacuum |
| H-2171A | 5/7/2026 9:32:22 AM | 28.72 | 1250 | 34.4373920 | -118.6425143 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-2171B | 5/13/2026 2:00:46 PM | 28.76 | 1274 | 34.4364970 | -118.6416663 | |
| H-2171N | 5/7/2026 9:22:04 AM | 28.71 | 1214 | 34.4380093 | -118.6432513 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-2171S | 5/4/2026 2:02:33 PM | 28.64 | 1271 | 34.4358292 | -118.6414683 | Valve Adjustment:Decreased Flow/Vacuum |
| H-2272W | 5/19/2026 10:27:12 AM | 28.68 | 1287 | 34.4317278 | -118.6497595 | |
| H-2272W | 5/4/2026 9:50:05 AM | 28.63 | 1277 | 34.4317415 | -118.6497550 | |
| H-2272W | 5/4/2026 9:47:59 AM | 28.63 | 1279 | 34.4317347 | -118.6497605 | Valve Adjustment:Increased Flow/Vacuum,Barely Open |
| H-2273W | 5/20/2026 8:21:56 AM | 28.59 | 1306 | 34.4321578 | -118.6499555 | Valve Adjustment:Audible Flow,Decreased Flow/Vacuum |
| H-2273W | 5/13/2026 12:42:00 PM | 28.65 | 1322 | 34.4321628 | -118.6499317 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-2273W | 5/12/2026 7:50:00 AM | | | | | Air Tech Lab |
| H-2273W | 5/12/2026 7:50:00 AM | | | | | Air Tech Lab; [User entered 0.59%] |
| H-2274B | 5/20/2026 2:09:49 PM | 28.58 | 1362 | 34.4327818 | -118.6469517 | |
| H-2274B | 5/4/2026 1:23:52 PM | 28.49 | 1322 | 34.4326350 | -118.6469175 | |
| H-2274W | 5/19/2026 1:17:54 PM | 28.63 | 1294 | 34.4327928 | -118.6503735 | Valve Adjustment:Barely Open |
| H-2274W | 5/1/2026 10:22:35 AM | 28.63 | 1298 | 34.4327832 | -118.6503647 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open |
| H-2275E | 5/4/2026 11:24:01 AM | 28.59 | 1322 | 34.4324075 | -118.6461940 | Valve Adjustment:Decreased Flow/Vacuum |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| H-2275W | 5/20/2026 7:50:11 AM | 28.55 | 1325 | 34.4322360 | -118.6493985 | Valve Adjustment:Audible Flow,Decreased Flow/Vacuum |
| H-2275W | 5/8/2026 11:15:19 AM | 28.55 | 1329 | 34.4321810 | -118.6493895 | |
| H-2275W | 5/8/2026 11:13:59 AM | 28.55 | 1306 | 34.4322273 | -118.6494392 | NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 to 1 Turn |
| H-2276A | 5/20/2026 1:13:04 PM | 28.5 | 1377 | 34.4328658 | -118.6483068 | Valve Adjustment:Reduce Sys. Vac. - Flare Down |
| H-2276A | 5/11/2026 1:32:34 PM | 28.57 | 1380 | 34.4328820 | -118.6482900 | Valve Adjustment:Reduce Sys. Vac. - Flare Down |
| H-2276B | 5/20/2026 2:22:12 PM | 28.41 | 1316 | 34.4329953 | -118.6468977 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-2276B | 5/4/2026 2:06:44 PM | 28.46 | 1407 | 34.4328373 | -118.6468900 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-2276E | 5/4/2026 11:37:57 AM | 28.59 | 1341 | 34.4328007 | -118.6453388 | Valve Adjustment:Barely Open |
| H-2276W | 5/20/2026 8:32:50 AM | 28.58 | 1320 | 34.4326735 | -118.6499695 | Valve Adjustment:Decreased Flow/Vacuum |
| H-2276W | 5/1/2026 10:16:43 AM | 28.59 | 1305 | 34.4326583 | -118.6499853 | Valve Adjustment:Decreased Flow/Vacuum |
| H-2277A | 5/21/2026 9:41:03 AM | 28.48 | 1362 | 34.4330293 | -118.6487417 | Valve Adjustment:Barely Open,Reduce Sys. Vac. - Flare Down |
| H-2277A | 5/1/2026 11:04:15 AM | 28.55 | 1351 | 34.4330352 | -118.6487232 | Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum;Well Condition:Good |
| H-2277B | 5/21/2026 9:35:16 AM | 28.44 | 1389 | 34.4330752 | -118.6469062 | Valve Adjustment:Surging Liquid in Header |
| H-2277B | 5/4/2026 2:19:04 PM | 28.46 | 1473 | 34.4331148 | -118.6469048 | |
| H-23 (EXP-23) | 5/13/2026 1:17:40 PM | 28.76 | 1263 | 34.4370082 | -118.6420873 | Valve Adjustment:High O2,Plugged/Pinched Suspected |
| H-23 (EXP-23) | 5/13/2026 1:13:21 PM | 28.76 | 1252 | 34.4370062 | -118.6420955 | Valve Comment:Clear liquid from flex hose;Valve Adjustment:Orifice Plate Changed (See OP Log),High O2 |
| H-23 (EXP-23) | 5/13/2026 10:53:27 AM | 28.79 | 1301 | 34.4370460 | -118.6421150 | Valve Adjustment:NSPS/EG CAI,Orifice Plate Changed (See OP Log),High O2,Decreased Flow/Vacuum |
| H-23 (EXP-23) | 5/13/2026 10:40:54 AM | 28.79 | 1251 | 34.4370065 | -118.6421048 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Valve 100% Closed |
| H-2301E | 5/13/2026 9:05:55 AM | 29.02 | 1035 | 34.4270647 | -118.6479965 | |
| H-2301W | 5/15/2026 10:14:58 AM | 28.76 | 1165 | 34.4282912 | -118.6508605 | |
| H-2301W | 5/15/2026 10:13:21 AM | 28.76 | 1181 | 34.4283080 | -118.6508505 | High O2 |
| H-2302C | 5/7/2026 2:47:12 PM | 28.72 | 1178 | 34.4284913 | -118.6490545 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-2302E | 5/8/2026 12:55:32 PM | 28.77 | 1010 | 34.4275620 | -118.6473168 | |
| H-2303E | 5/8/2026 1:01:15 PM | 28.79 | 1086 | 34.4279038 | -118.6470848 | |
| H-2303N | 5/7/2026 2:55:44 PM | 28.71 | 1270 | 34.4290517 | -118.6485457 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-2304E | 5/8/2026 1:05:45 PM | 28.79 | 1066 | 34.4282910 | -118.6469717 | |
| H-2304S | 5/8/2026 1:30:30 PM | 28.77 | 1102 | 34.4275005 | -118.6489317 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-2305N | 5/7/2026 3:01:47 PM | 28.69 | 1234 | 34.4290775 | -118.6486402 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-2305S | 5/8/2026 1:14:11 PM | 28.78 | 1040 | 34.4274637 | -118.6484590 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| H-2306N | 5/15/2026 10:33:03 AM | 28.74 | 1171 | 34.4294673 | -118.6475270 | |
| H-2307S | 5/22/2026 11:53:04 AM | 28.67 | 1127 | 34.4282258 | -118.6498862 | Valve Adjustment:Audible Flow |
| H-2307S | 5/7/2026 2:41:47 PM | 28.72 | 1184 | 34.4283230 | -118.6499335 | |
| H-2307S | 5/7/2026 2:40:20 PM | 28.72 | 1214 | 34.4282598 | -118.6498622 | NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 to 1 Turn |
| H-2308S | 5/7/2026 2:29:52 PM | 28.72 | 1109 | 34.4283483 | -118.6498983 | Reduced System Vacuum |
| H-2309N | 5/4/2026 10:13:40 AM | 28.55 | 1312 | 34.4316015 | -118.6489425 | |
| H-2309S | 5/8/2026 1:53:32 PM | 28.74 | 1099 | 34.4281668 | -118.6488530 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-2310N | 5/8/2026 3:03:25 PM | 28.68 | 1115 | 34.4299800 | -118.6478832 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-2310S | 5/22/2026 12:06:57 PM | 28.71 | 1120 | 34.4291798 | -118.6475352 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open |
| H-2310S | 5/14/2026 9:47:40 AM | 28.8 | 1102 | 34.4291448 | -118.6476128 | |
| H-2401S | 5/7/2026 11:32:52 AM | 28.68 | 1178 | 34.4289090 | -118.6512467 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-2402N | 5/8/2026 9:47:00 AM | 28.71 | 1237 | 34.4290415 | -118.6501617 | |
| H-2402S | 5/8/2026 9:58:19 AM | 28.7 | 1184 | 34.4287787 | -118.6504880 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-2403N | 5/8/2026 9:51:09 AM | 28.68 | 1178 | 34.4293443 | -118.6502303 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-2403S | 5/8/2026 9:35:34 AM | 28.74 | 1191 | 34.4287068 | -118.6498640 | |
| H-2404N | 5/5/2026 3:35:40 PM | 28.63 | 1217 | 34.4292643 | -118.6494898 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-2404S | 5/8/2026 8:59:38 AM | 28.77 | 1191 | 34.4287530 | -118.6493000 | |
| H-2405N | 5/5/2026 2:23:59 PM | 28.56 | 1247 | 34.4299727 | -118.6495100 | |
| H-29 | 5/29/2026 12:05:20 PM | 28.67 | 1283 | 34.4354267 | -118.6417648 | Valve Adjustment:NSPS/EG CAC |
| H-29 | 5/29/2026 12:00:31 PM | 28.7 | 1281 | 34.4354368 | -118.6417790 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum |
| H-29 | 5/4/2026 1:58:42 PM | 28.63 | 1273 | 34.4354442 | -118.6417735 | Valve Adjustment:NSPS/EG CAC |
| H-29 | 5/4/2026 1:55:50 PM | 28.63 | 1278 | 34.4354300 | -118.6417690 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum |
| H-72 | 5/29/2026 9:51:57 AM | 28.67 | 1325 | 34.4368798 | -118.6448662 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| H-74 | 5/11/2026 11:20:34 AM | 28.57 | 1257 | 34.4370635 | -118.6431107 | |
| H-75 | 5/14/2026 11:59:28 AM | 28.59 | 1345 | 34.4363457 | -118.6420747 | |
| H-79 | 5/15/2026 11:24:44 AM | 28.65 | 1325 | 34.4340572 | -118.6428650 | No Adjustment Made,Audible Flow |
| P-02R | 5/13/2026 8:15:30 AM | 28.87 | 1157 | 34.4297442 | -118.6439258 | |
| P-03R | 5/13/2026 8:26:58 AM | 28.87 | 1173 | 34.4298598 | -118.6442158 | |
| P-04 | 5/5/2026 7:38:51 AM | 28.71 | 1176 | 34.4294557 | -118.6445353 | |
| P-05 | 5/5/2026 7:46:02 AM | 28.73 | 1146 | 34.4291723 | -118.6447730 | Well Condition:Fair;Well Repairs:Flex Hose |
| P-06R | 5/5/2026 7:49:46 AM | 28.72 | 1139 | 34.4288705 | -118.6450635 | Well Condition:Fair |
| P-07R | 5/12/2026 8:59:48 AM | 28.72 | 1169 | 34.4298372 | -118.6432867 | |
| P-08R | 5/11/2026 10:46:01 AM | 28.86 | 1153 | 34.4294120 | -118.6437068 | Valve Adjustment:Audible Flow |
| P-09 | 5/5/2026 8:01:21 AM | 28.71 | 1162 | 34.4290035 | -118.6442565 | Valve Adjustment:Audible Flow;Well Condition:Fair;Well Repairs:Flex Hose |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| P-10 | 5/5/2026 7:56:04 AM | 28.71 | 1145 | 34.4287117 | -118.6446435 | Well Condition:Good |
| P-11 | 5/12/2026 9:25:09 AM | 28.76 | 1134 | 34.4285110 | -118.6449670 | |
| P-12 | 5/15/2026 7:59:36 AM | 28.82 | 1115 | 34.4288363 | -118.6456393 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| P-13 | 5/15/2026 8:05:44 AM | 28.83 | 1135 | 34.4285183 | -118.6457337 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| P-14 | 5/5/2026 8:13:25 AM | 28.78 | 1106 | 34.4280348 | -118.6460672 | Valve Adjustment:Decreased Flow/Vacuum |
| P-15R | 5/5/2026 8:17:20 AM | 28.77 | 1107 | 34.4277893 | -118.6459260 | |
| P-16 | 5/5/2026 8:25:52 AM | 28.78 | 1103 | 34.4275337 | -118.6456078 | |
| P-17 | 5/5/2026 8:30:43 AM | 28.77 | 1096 | 34.4273773 | -118.6453377 | |
| P-18RD | 5/5/2026 8:41:50 AM | 28.78 | 1103 | 34.4271108 | -118.6450018 | |
| P-18RS | 5/5/2026 8:36:36 AM | 28.78 | 1099 | 34.4271123 | -118.6450190 | |
| P-19 | 5/4/2026 11:16:30 AM | 28.84 | 1089 | 34.4268377 | -118.6451812 | |
| P-20R | 5/5/2026 8:45:27 AM | 28.78 | 1101 | 34.4268247 | -118.6448280 | |
| P-21 | 5/5/2026 8:49:59 AM | 28.78 | 1110 | 34.4265067 | -118.6447967 | |
| P-21RD | 5/4/2026 10:03:26 AM | 28.81 | 1142 | 34.4263675 | -118.6443280 | No Adjustment Made |
| P-21RS | 5/4/2026 10:00:38 AM | 28.83 | 1138 | 34.4264085 | -118.6443853 | |
| P-22RD | 5/4/2026 10:32:00 AM | 28.77 | 1171 | 34.4269110 | -118.6438215 | Increased Flow/Vacuum |
| P-22RS | 5/4/2026 10:28:52 AM | 28.76 | 1178 | 34.4269142 | -118.6437452 | |
| P-23 | 5/5/2026 8:59:25 AM | 28.78 | 1110 | 34.4261428 | -118.6447117 | Valve Adjustment:Orifice Plate Changed (See OP Log) |
| P-24 | 5/6/2026 8:17:07 AM | 28.91 | 1109 | 34.4260808 | -118.6442818 | |
| P-26 | 5/6/2026 8:34:09 AM | 28.89 | 1148 | 34.4265393 | -118.6431935 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| P-27 | 5/6/2026 8:43:29 AM | 28.89 | 1155 | 34.4268782 | -118.6427508 | |
| P-28 | 5/6/2026 8:51:00 AM | 28.88 | 1148 | 34.4270348 | -118.6422415 | |
| P-29R | 5/6/2026 8:57:44 AM | 28.87 | 1171 | 34.4271623 | -118.6418718 | |
| P-30R | 5/6/2026 9:04:44 AM | 28.87 | 1184 | 34.4274230 | -118.6415790 | |
| P-32R1 | 5/6/2026 9:10:45 AM | 28.85 | 1161 | 34.4282355 | -118.6410790 | |
| P-32R2 | 5/6/2026 9:14:09 AM | 28.85 | 1175 | 34.4284572 | -118.6410243 | |
| P-33 | 5/6/2026 9:19:40 AM | 28.84 | 1211 | 34.4287705 | -118.6407780 | No Flow Measurement |
| P-36 | 5/6/2026 9:31:05 AM | 28.83 | 1217 | 34.4302865 | -118.6400428 | No Adjustment Made |
| P-37 | 5/6/2026 9:35:20 AM | 28.81 | 1243 | 34.4305062 | -118.6404012 | |
| P-38RD | 5/6/2026 9:48:07 AM | 28.8 | 1207 | 34.4299953 | -118.6406215 | No Adjustment Made |
| P-38RS | 5/6/2026 9:44:32 AM | 28.81 | 1217 | 34.4299980 | -118.6406513 | |
| P-39 | 5/6/2026 9:55:17 AM | 28.81 | 1220 | 34.4294320 | -118.6409958 | No Adjustment Made |
| P-41 | 5/6/2026 10:07:48 AM | 28.81 | 1214 | 34.4288583 | -118.6413945 | NSPS/EG CAI,High O2 |
| P-41 | 5/6/2026 10:06:10 AM | 28.81 | 1240 | 34.4288862 | -118.6414418 | NSPS/EG CAI,High O2 |
| P-42R | 5/6/2026 10:15:47 AM | 28.81 | 1194 | 34.4284612 | -118.6417320 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| P-43 | 5/6/2026 10:22:56 AM | 28.82 | 1224 | 34.4282822 | -118.6418015 | |
| P-44RD | 5/6/2026 10:37:00 AM | 28.81 | 1155 | 34.4280457 | -118.6421608 | Increased Flow/Vacuum |
| P-44RS | 5/6/2026 10:33:49 AM | 28.82 | 1188 | 34.4281768 | -118.6418202 | |
| P-45RD | 5/6/2026 10:50:26 AM | 28.82 | 1204 | 34.4276827 | -118.6424397 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| P-45RS | 5/6/2026 10:47:34 AM | 28.81 | 1184 | 34.4277275 | -118.6424702 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| P-46RD | 5/6/2026 11:02:37 AM | 28.81 | 1201 | 34.4277323 | -118.6427357 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| P-46RS | 5/6/2026 10:55:16 AM | 28.82 | 1211 | 34.4276638 | -118.6426433 | |
| P-47 | 5/4/2026 10:21:39 AM | 28.73 | 1214 | 34.4274452 | -118.6432183 | No Flow Measurement |
| P-48 | 5/4/2026 10:38:03 AM | 28.74 | 1204 | 34.4275840 | -118.6435617 | |
| P-49RD | 5/4/2026 10:58:34 AM | 28.74 | 1201 | 34.4279272 | -118.6438430 | Increased Flow/Vacuum |
| P-49RS | 5/4/2026 10:55:41 AM | 28.74 | 1194 | 34.4279627 | -118.6438450 | |
| P-52 | 5/28/2026 2:38:45 PM | 28.64 | 1219 | 34.4287193 | -118.6432857 | Valve Adjustment:Barely Open |
| P-53 | 5/15/2026 8:37:53 AM | 28.73 | 1234 | 34.4291410 | -118.6431228 | Audible Flow |
| P-54 | 5/15/2026 8:35:38 AM | 28.72 | 1220 | 34.4292002 | -118.6431255 | |
| P-55 | 5/15/2026 8:24:48 AM | 28.71 | 1234 | 34.4297752 | -118.6426818 | Audible Flow,No Flow Measurement |
| P-56 | 5/26/2026 9:15:49 AM | 28.57 | 1220 | 34.4300997 | -118.6428133 | |
| P-57 | 5/13/2026 9:14:04 AM | 28.8 | 1253 | 34.4299728 | -118.6424557 | |
| P-60R | 5/7/2026 8:52:45 AM | 28.74 | 1263 | 34.4307783 | -118.6415790 | NSPS/EG CAI,High O2 |
| P-60R | 5/7/2026 8:48:07 AM | 28.74 | 1207 | 34.4307893 | -118.6415645 | NSPS/EG CAI,High O2 |
| P-61 | 5/7/2026 8:30:07 AM | 28.72 | 1289 | 34.4311355 | -118.6411517 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less |
| P-65 | 5/7/2026 8:25:21 AM | 28.76 | 1263 | 34.4304160 | -118.6409915 | |
| P-71 | 5/4/2026 10:47:48 AM | 28.73 | 1220 | 34.4279280 | -118.6431523 | No Adjustment Made |
| P-75 | 5/6/2026 11:19:49 AM | 28.8 | 1217 | 34.4302853 | -118.6415073 | No Adjustment Made,Increased Flow/Vacuum |
| P-76 | 5/6/2026 9:41:27 AM | 28.8 | 1230 | 34.4300573 | -118.6406000 | |
| P-79 | 5/4/2026 11:21:51 AM | 28.92 | 1004 | 34.4271028 | -118.6460305 | No Flow Measurement |
| SC-2000E | 5/6/2026 12:28:45 PM | 28.72 | 1204 | 34.4307167 | -118.6467057 | |
| SC-2501E | 5/26/2026 9:21:31 AM | 28.47 | 1367 | 34.4366668 | -118.6478788 | Valve Adjustment:High Temp,Valve 100% Open;Well Repairs:Valve |
| SC-2501E | 5/18/2026 9:40:35 AM | 28.51 | 1360 | 34.4366875 | -118.6478968 | Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open;Well Repairs:Valve |
| SC-2501E | 5/18/2026 9:40:00 AM | | | | | AtmAA |
| SC-2501E | 5/18/2026 9:38:11 AM | 28.52 | 1358 | 34.4366869 | -118.6478978 | Valve Adjustment:High Temp,Reduce Sys. Vac. - Flare Down |
| SC-2501E | 5/18/2026 9:29:29 AM | 28.53 | 1357 | 34.4366436 | -118.6478826 | Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down |
| SC-2501E | 5/12/2026 9:13:45 AM | 28.55 | 1341 | 34.4367005 | -118.6479329 | Valve Adjustment:High Temp |
| SC-2501E | 5/12/2026 9:10:00 AM | | | | | AtmAA |
| SC-2501E | 5/5/2026 8:56:40 AM | 28.52 | 1344 | 34.4366786 | -118.6479108 | Valve Adjustment:High Temp |
| SC-2501E | 5/5/2026 8:51:59 AM | 28.51 | 1341 | 34.4366711 | -118.6479123 | Valve Adjustment:Orifice Plate Changed (See OP Log),High Temp |
| SC-2501E | 5/5/2026 8:50:00 AM | | | | | AtmAA |
| SC-2501E | 5/5/2026 8:50:00 AM | | | | | AtmAA; [User entered 17.77%] |
| SC-2501W | 5/5/2026 9:19:42 AM | 28.51 | 1358 | 34.4367915 | -118.6485240 | Valve Comment:Bad well heat valve does not open;Valve Adjustment:NSPS/EG CAC,Increased Flow/Vacuum,Valve 100% Open |
| SW-10 | 5/28/2026 9:37:50 AM | 28.57 | 1343 | 34.4370242 | -118.6503695 | |
| SW-115 | 5/11/2026 8:59:04 AM | 28.73 | 1214 | 34.4348128 | -118.6412347 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| SW-1445 | 5/22/2026 7:39:28 AM | 28.59 | 1228 | 34.4325033 | -118.6519762 | |
| SW-1445 | 5/4/2026 7:53:57 AM | 28.7 | 1216 | 34.4325060 | -118.6520183 | |
| SW-1455 | 5/22/2026 7:44:18 AM | 28.59 | 1204 | 34.4323960 | -118.6519070 | |
| SW-1455 | 5/4/2026 7:57:56 AM | 28.7 | 1199 | 34.4324083 | -118.6519080 | |
| SW-154 | 5/15/2026 9:34:29 AM | 28.7 | 1243 | 34.4379895 | -118.6456350 | NSPS/EG CAI,No Flow Measurement,High O2 |
| SW-154 | 5/15/2026 9:31:56 AM | 28.7 | 1289 | 34.4379950 | -118.6456550 | NSPS/EG CAI,No Flow Measurement,High O2 |
| SW-17-135 | 5/22/2026 7:41:29 AM | 28.59 | 1195 | 34.4324443 | -118.6519940 | |
| SW-17-135 | 5/4/2026 7:56:03 AM | 28.7 | 1216 | 34.4324535 | -118.6520098 | |
| SW-187 | 5/4/2026 9:31:29 AM | 28.6 | 1319 | 34.4372602 | -118.6473498 | |
| SW-1930 | 5/1/2026 7:51:05 AM | 28.6 | 1265 | 34.4353082 | -118.6516128 | Valve Adjustment:Audible Flow |
| SW-20 | 5/12/2026 9:06:57 AM | 28.72 | 1168 | 34.4302393 | -118.6436463 | |
| SW-25 | 5/1/2026 7:53:15 AM | 28.63 | 1253 | 34.4351710 | -118.6516867 | Valve Adjustment:Valve 100% Closed |
| SW-2501D | 5/29/2026 7:21:12 AM | 28.77 | 1208 | 34.4335080 | -118.6519720 | Valve Adjustment:Valve 100% Open |
| SW-2501D | 5/28/2026 6:16:27 AM | 28.63 | 1212 | 34.4335467 | -118.6519558 | |
| SW-2501D | 5/27/2026 6:04:20 AM | 28.52 | 1214 | 34.4334993 | -118.6519592 | Valve Adjustment:Reduce Sys. Vac. - Flare Down |
| SW-2501D | 5/26/2026 6:11:29 AM | 28.59 | 1194 | 34.4335195 | -118.6519752 | |
| SW-2501D | 5/22/2026 6:19:43 AM | 28.56 | 1198 | 34.4335292 | -118.6519572 | |
| SW-2501D | 5/21/2026 6:35:47 AM | 28.61 | 1204 | 34.4335218 | -118.6519610 | |
| SW-2501D | 5/20/2026 8:30:45 AM | 28.67 | 1199 | 34.4334947 | -118.6519580 | Valve Adjustment:Valve 100% Open |
| SW-2501D | 5/19/2026 9:01:29 AM | 28.75 | 1209 | 34.4334962 | -118.6519523 | Valve Adjustment:Valve 100% Open |
| SW-2501D | 5/18/2026 8:44:45 AM | 28.66 | 1207 | 34.4335105 | -118.6519608 | |
| SW-2501D | 5/15/2026 9:25:43 AM | 28.71 | 1211 | 34.4335195 | -118.6519642 | |
| SW-2501D | 5/14/2026 8:19:05 AM | 28.75 | 1202 | 34.4335260 | -118.6519660 | Valve Adjustment:Valve 100% Open |
| SW-2501D | 5/13/2026 8:08:49 AM | 28.82 | 1202 | 34.4334913 | -118.6519685 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| SW-2501D | 5/12/2026 9:15:23 AM | 28.67 | 1208 | 34.4335090 | -118.6519602 | Valve Adjustment:Valve 100% Open,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| SW-2501D | 5/11/2026 8:24:00 AM | 28.71 | 1220 | 34.4335182 | -118.6519562 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| SW-2501D | 5/8/2026 9:35:42 AM | 28.71 | 1209 | 34.4334960 | -118.6519422 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| SW-2501D | 5/7/2026 8:55:20 AM | 28.75 | 1202 | 34.4335105 | -118.6519538 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| SW-2501D | 5/6/2026 8:47:06 AM | 28.78 | 1230 | 34.4335140 | -118.6519823 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header |
| SW-2501D | 5/5/2026 8:31:57 AM | 28.67 | 1209 | 34.4335015 | -118.6519653 | Valve Adjustment:Barely Open,Surging Liquid in Header |
| SW-2501D | 5/4/2026 8:20:15 AM | 28.7 | 1188 | 34.4335058 | -118.6519633 | Valve Adjustment:Audible Flow |
| SW-2501D | 5/1/2026 8:28:56 AM | 28.68 | 1206 | 34.4335202 | -118.6519598 | Valve Adjustment:Audible Flow;Well Condition:Good |
| SW-2501M | 5/29/2026 7:24:25 AM | 28.78 | 1212 | 34.4335182 | -118.6519538 | Valve Adjustment:Valve 100% Open |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| SW-2501M | 5/28/2026 6:12:29 AM | 28.63 | 1209 | 34.4335263 | -118.6519477 | |
| SW-2501M | 5/27/2026 5:59:22 AM | 28.52 | 1221 | 34.4335113 | -118.6519733 | Valve Adjustment:Reduce Sys. Vac. - Flare Down |
| SW-2501M | 5/26/2026 6:01:33 AM | 28.59 | 1209 | 34.4335222 | -118.6519473 | |
| SW-2501M | 5/22/2026 6:14:16 AM | 28.56 | 1206 | 34.4335062 | -118.6519473 | |
| SW-2501M | 5/21/2026 6:30:13 AM | 28.63 | 1202 | 34.4335080 | -118.6519493 | |
| SW-2501M | 5/20/2026 8:25:51 AM | 28.7 | 1205 | 34.4335122 | -118.6519752 | Valve Adjustment:Valve 100% Open |
| SW-2501M | 5/19/2026 8:55:12 AM | 28.75 | 1216 | 34.4335108 | -118.6519538 | Valve Adjustment:Valve 100% Open |
| SW-2501M | 5/18/2026 8:38:11 AM | 28.63 | 1208 | 34.4335058 | -118.6519498 | |
| SW-2501M | 5/15/2026 9:19:11 AM | 28.72 | 1216 | 34.4335352 | -118.6519838 | |
| SW-2501M | 5/14/2026 8:13:12 AM | 28.75 | 1232 | 34.4335345 | -118.6519475 | |
| SW-2501M | 5/13/2026 8:03:42 AM | 28.79 | 1202 | 34.4335012 | -118.6519710 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| SW-2501M | 5/12/2026 9:11:04 AM | 28.67 | 1208 | 34.4335005 | -118.6519717 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| SW-2501M | 5/11/2026 8:20:03 AM | 28.71 | 1241 | 34.4335292 | -118.6519752 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| SW-2501M | 5/8/2026 9:30:13 AM | 28.71 | 1205 | 34.4334985 | -118.6519497 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| SW-2501M | 5/7/2026 8:50:28 AM | 28.75 | 1205 | 34.4335083 | -118.6519487 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| SW-2501M | 5/6/2026 8:42:31 AM | 28.78 | 1236 | 34.4335165 | -118.6519673 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header |
| SW-2501M | 5/5/2026 8:23:44 AM | 28.67 | 1213 | 34.4335072 | -118.6519787 | Valve Adjustment:Barely Open,Surging Liquid in Header |
| SW-2501M | 5/4/2026 8:14:55 AM | 28.7 | 1195 | 34.4335072 | -118.6519662 | Valve Adjustment:Audible Flow |
| SW-2501M | 5/1/2026 8:25:32 AM | 28.7 | 1213 | 34.4335257 | -118.6519562 | Valve Adjustment:Audible Flow;Well Condition:Good |
| SW-2501MD | 5/29/2026 7:15:49 AM | 28.76 | 1214 | 34.4335063 | -118.6519613 | Valve Adjustment:Valve 100% Open |
| SW-2501MD | 5/28/2026 6:14:16 AM | 28.63 | 1216 | 34.4335208 | -118.6519582 | |
| SW-2501MD | 5/27/2026 6:02:25 AM | 28.52 | 1210 | 34.4335200 | -118.6519492 | Valve Adjustment:Reduce Sys. Vac. - Flare Down |
| SW-2501MD | 5/26/2026 6:05:27 AM | 28.59 | 1216 | 34.4335238 | -118.6519560 | |
| SW-2501MD | 5/22/2026 6:16:46 AM | 28.56 | 1204 | 34.4335067 | -118.6519538 | |
| SW-2501MD | 5/21/2026 6:32:26 AM | 28.6 | 1215 | 34.4335160 | -118.6519452 | |
| SW-2501MD | 5/20/2026 8:28:56 AM | 28.7 | 1197 | 34.4335013 | -118.6519777 | Valve Adjustment:Valve 100% Open |
| SW-2501MD | 5/19/2026 8:58:19 AM | 28.75 | 1205 | 34.4335145 | -118.6519443 | Valve Adjustment:Valve 100% Open |
| SW-2501MD | 5/18/2026 8:41:43 AM | 28.65 | 1211 | 34.4335008 | -118.6519532 | |
| SW-2501MD | 5/14/2026 8:16:25 AM | 28.75 | 1220 | 34.4335148 | -118.6519580 | Valve Adjustment:High O2,Valve 100% Open |
| SW-2501MD | 5/13/2026 8:06:36 AM | 28.82 | 1209 | 34.4335015 | -118.6519472 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| SW-2501MD | 5/12/2026 9:12:49 AM | 28.67 | 1208 | 34.4335060 | -118.6519697 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| SW-2501MD | 5/11/2026 8:21:50 AM | 28.71 | 1233 | 34.4335238 | -118.6519727 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| SW-2501MD | 5/8/2026 9:32:28 AM | 28.75 | 1204 | 34.4334947 | -118.6519282 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| SW-2501MD | 5/7/2026 8:53:13 AM | 28.75 | 1206 | 34.4335125 | -118.6519475 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| SW-2501MD | 5/6/2026 8:45:13 AM | 28.78 | 1238 | 34.4335165 | -118.6519718 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header |
| SW-2501MD | 5/5/2026 8:27:56 AM | 28.67 | 1203 | 34.4335097 | -118.6519517 | Valve Adjustment:Valve 100% Closed,Surging Liquid in Header |
| SW-2501MD | 5/4/2026 8:17:07 AM | 28.67 | 1207 | 34.4335143 | -118.6519833 | Valve Adjustment:Audible Flow |
| SW-2501MD | 5/1/2026 8:27:27 AM | 28.67 | 1204 | 34.4335243 | -118.6519692 | Valve Adjustment:Audible Flow;Well Condition:Good |
| SW-2501S | 5/29/2026 7:18:48 AM | 28.78 | 1202 | 34.4335062 | -118.6519753 | Valve Adjustment:Valve 100% Open |
| SW-2501S | 5/28/2026 6:18:35 AM | 28.63 | 1207 | 34.4335115 | -118.6519555 | |
| SW-2501S | 5/27/2026 6:06:12 AM | 28.52 | 1202 | 34.4335105 | -118.6519705 | Valve Adjustment:Reduce Sys. Vac. - Flare Down |
| SW-2501S | 5/26/2026 6:14:28 AM | 28.59 | 1210 | 34.4335415 | -118.6519715 | |
| SW-2501S | 5/22/2026 6:22:20 AM | 28.56 | 1203 | 34.4335172 | -118.6519550 | |
| SW-2501S | 5/21/2026 6:38:09 AM | 28.61 | 1201 | 34.4334975 | -118.6519645 | |
| SW-2501S | 5/20/2026 8:33:18 AM | 28.67 | 1201 | 34.4335063 | -118.6519662 | Valve Adjustment:Valve 100% Open |
| SW-2501S | 5/19/2026 9:04:28 AM | 28.75 | 1210 | 34.4335102 | -118.6519533 | Valve Adjustment:Valve 100% Open |
| SW-2501S | 5/18/2026 8:47:27 AM | 28.66 | 1210 | 34.4335008 | -118.6519640 | |
| SW-2501S | 5/15/2026 9:27:58 AM | 28.71 | 1209 | 34.4335302 | -118.6519562 | |
| SW-2501S | 5/15/2026 9:22:25 AM | 28.71 | 1201 | 34.4335372 | -118.6519382 | |
| SW-2501S | 5/14/2026 8:22:49 AM | 28.75 | 1213 | 34.4335095 | -118.6519472 | Valve Adjustment:High O2,Valve 100% Open |
| SW-2501S | 5/13/2026 8:12:06 AM | 28.81 | 1205 | 34.4335047 | -118.6519632 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| SW-2501S | 5/12/2026 9:17:43 AM | 28.67 | 1205 | 34.4334968 | -118.6519437 | Valve Adjustment:Valve 100% Open,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| SW-2501S | 5/11/2026 8:26:36 AM | 28.71 | 1223 | 34.4335232 | -118.6519632 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| SW-2501S | 5/8/2026 9:39:11 AM | 28.73 | 1208 | 34.4334922 | -118.6519465 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| SW-2501S | 5/7/2026 9:00:17 AM | 28.75 | 1206 | 34.4335225 | -118.6519500 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| SW-2501S | 5/6/2026 8:51:41 AM | 28.78 | 1227 | 34.4335092 | -118.6519708 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header |
| SW-2501S | 5/5/2026 8:36:07 AM | 28.67 | 1212 | 34.4335002 | -118.6519537 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header |
| SW-2501S | 5/4/2026 8:22:18 AM | 28.68 | 1205 | 34.4335283 | -118.6519558 | Valve Adjustment:Audible Flow |
| SW-2501S | 5/1/2026 8:30:42 AM | 28.69 | 1206 | 34.4335170 | -118.6519717 | Valve Adjustment:Audible Flow;Well Condition:Good |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| SW-2502D | 5/29/2026 7:02:56 AM | 28.78 | 1203 | 34.4337180 | -118.6518868 | Valve Adjustment:Valve 100% Open |
| SW-2502D | 5/28/2026 6:27:56 AM | 28.63 | 1217 | 34.4337380 | -118.6518905 | |
| SW-2502D | 5/27/2026 6:15:12 AM | 28.51 | 1217 | 34.4337258 | -118.6518730 | Valve Adjustment:Reduce Sys. Vac. - Flare Down |
| SW-2502D | 5/26/2026 6:28:54 AM | 28.59 | 1212 | 34.4337275 | -118.6518903 | |
| SW-2502D | 5/22/2026 6:34:30 AM | 28.59 | 1214 | 34.4337385 | -118.6518817 | |
| SW-2502D | 5/21/2026 6:50:59 AM | 28.62 | 1207 | 34.4337337 | -118.6518865 | |
| SW-2502D | 5/20/2026 8:15:28 AM | 28.69 | 1206 | 34.4337277 | -118.6518858 | Valve Adjustment:Valve 100% Open |
| SW-2502D | 5/19/2026 9:17:49 AM | 28.75 | 1216 | 34.4337280 | -118.6518860 | Valve Adjustment:Valve 100% Open |
| SW-2502D | 5/18/2026 8:59:18 AM | 28.63 | 1216 | 34.4337255 | -118.6518978 | |
| SW-2502D | 5/15/2026 9:08:52 AM | 28.71 | 1216 | 34.4337363 | -118.6518468 | |
| SW-2502D | 5/14/2026 8:37:14 AM | 28.75 | 1214 | 34.4337347 | -118.6518788 | Valve Adjustment:Valve 100% Open |
| SW-2502D | 5/13/2026 8:21:57 AM | 28.82 | 1219 | 34.4337202 | -118.6519083 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| SW-2502D | 5/12/2026 9:27:18 AM | 28.67 | 1213 | 34.4337305 | -118.6518858 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| SW-2502D | 5/11/2026 8:36:30 AM | 28.71 | 1210 | 34.4337307 | -118.6518923 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| SW-2502D | 5/8/2026 9:49:11 AM | 28.72 | 1214 | 34.4337170 | -118.6518773 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| SW-2502D | 5/7/2026 9:13:11 AM | 28.75 | 1212 | 34.4337435 | -118.6519035 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| SW-2502D | 5/6/2026 9:03:29 AM | 28.79 | 1223 | 34.4337280 | -118.6518957 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header |
| SW-2502D | 5/5/2026 8:48:17 AM | 28.67 | 1230 | 34.4337398 | -118.6518983 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header |
| SW-2502D | 5/4/2026 8:29:47 AM | 28.67 | 1205 | 34.4337345 | -118.6518757 | Valve Adjustment:Audible Flow |
| SW-2502D | 5/1/2026 8:39:01 AM | 28.67 | 1214 | 34.4337297 | -118.6518810 | Valve Adjustment:Audible Flow;Well Condition:Good |
| SW-2502M | 5/29/2026 6:58:21 AM | 28.77 | 1216 | 34.4337387 | -118.6518822 | Valve Adjustment:Valve 100% Open |
| SW-2502M | 5/28/2026 6:26:04 AM | 28.63 | 1218 | 34.4337358 | -118.6518773 | |
| SW-2502M | 5/27/2026 6:13:20 AM | 28.52 | 1205 | 34.4337292 | -118.6518858 | Valve Adjustment:Reduce Sys. Vac. - Flare Down |
| SW-2502M | 5/26/2026 6:25:59 AM | 28.59 | 1213 | 34.4337368 | -118.6518747 | |
| SW-2502M | 5/22/2026 6:31:26 AM | 28.56 | 1203 | 34.4337455 | -118.6518742 | |
| SW-2502M | 5/21/2026 6:48:59 AM | 28.61 | 1210 | 34.4337555 | -118.6518850 | |
| SW-2502M | 5/20/2026 8:13:58 AM | 28.68 | 1214 | 34.4337308 | -118.6519055 | Valve Adjustment:Valve 100% Open |
| SW-2502M | 5/19/2026 9:14:46 AM | 28.75 | 1220 | 34.4337343 | -118.6518632 | Valve Adjustment:Valve 100% Open |
| SW-2502M | 5/18/2026 8:56:28 AM | 28.63 | 1209 | 34.4337413 | -118.6518853 | |
| SW-2502M | 5/15/2026 9:04:47 AM | 28.71 | 1217 | 34.4337558 | -118.6518752 | |
| SW-2502M | 5/14/2026 8:34:30 AM | 28.75 | 1219 | 34.4337393 | -118.6518742 | Valve Adjustment:Valve 100% Open |
| SW-2502M | 5/13/2026 8:19:53 AM | 28.81 | 1213 | 34.4337283 | -118.6518945 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| SW-2502M | 5/12/2026 9:25:33 AM | 28.67 | 1214 | 34.4337280 | -118.6518818 | Valve Adjustment:Valve 100% Open,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| SW-2502M | 5/11/2026 8:34:43 AM | 28.71 | 1220 | 34.4337318 | -118.6518887 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| SW-2502M | 5/8/2026 9:47:15 AM | 28.73 | 1211 | 34.4337167 | -118.6518817 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| SW-2502M | 5/7/2026 9:10:36 AM | 28.75 | 1215 | 34.4337353 | -118.6519033 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| SW-2502M | 5/6/2026 9:01:23 AM | 28.79 | 1220 | 34.4337372 | -118.6518923 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header |
| SW-2502M | 5/5/2026 8:46:24 AM | 28.67 | 1228 | 34.4337390 | -118.6518992 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header |
| SW-2502M | 5/4/2026 8:28:19 AM | 28.69 | 1203 | 34.4337417 | -118.6518647 | Valve Adjustment:Audible Flow |
| SW-2502M | 5/1/2026 8:36:49 AM | 28.67 | 1203 | 34.4337415 | -118.6518992 | Valve Adjustment:Audible Flow;Well Condition:Good |
| SW-2502MD | 5/29/2026 7:08:57 AM | 28.75 | 1204 | 34.4337250 | -118.6518942 | Valve Adjustment:Valve 100% Open |
| SW-2502MD | 5/28/2026 6:29:56 AM | 28.63 | 1219 | 34.4337292 | -118.6518797 | |
| SW-2502MD | 5/27/2026 6:16:47 AM | 28.49 | 1215 | 34.4337263 | -118.6518863 | Valve Adjustment:Reduce Sys. Vac. - Flare Down |
| SW-2502MD | 5/26/2026 6:31:21 AM | 28.59 | 1210 | 34.4337317 | -118.6518855 | |
| SW-2502MD | 5/22/2026 6:36:17 AM | 28.59 | 1209 | 34.4337372 | -118.6518950 | |
| SW-2502MD | 5/21/2026 6:52:38 AM | 28.61 | 1206 | 34.4337335 | -118.6518958 | |
| SW-2502MD | 5/20/2026 8:17:46 AM | 28.68 | 1214 | 34.4337253 | -118.6518992 | Valve Adjustment:Valve 100% Open |
| SW-2502MD | 5/19/2026 9:20:34 AM | 28.75 | 1211 | 34.4337235 | -118.6518815 | Valve Adjustment:Valve 100% Open |
| SW-2502MD | 5/18/2026 9:02:05 AM | 28.63 | 1206 | 34.4337208 | -118.6518838 | |
| SW-2502MD | 5/15/2026 9:12:10 AM | 28.71 | 1204 | 34.4337573 | -118.6518592 | |
| SW-2502MD | 5/14/2026 8:39:47 AM | 28.75 | 1210 | 34.4337373 | -118.6518768 | Valve Adjustment:Valve 100% Open |
| SW-2502MD | 5/13/2026 8:24:00 AM | 28.81 | 1219 | 34.4337222 | -118.6518988 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| SW-2502MD | 5/12/2026 9:28:53 AM | 28.67 | 1206 | 34.4337260 | -118.6518780 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| SW-2502MD | 5/11/2026 8:38:07 AM | 28.71 | 1215 | 34.4337275 | -118.6518900 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| SW-2502MD | 5/8/2026 9:51:10 AM | 28.73 | 1209 | 34.4337140 | -118.6518795 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| SW-2502MD | 5/7/2026 9:14:39 AM | 28.75 | 1214 | 34.4337330 | -118.6518933 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| SW-2502MD | 5/6/2026 9:05:22 AM | 28.8 | 1218 | 34.4337258 | -118.6518817 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header |
| SW-2502MD | 5/5/2026 8:50:15 AM | 28.67 | 1215 | 34.4337330 | -118.6519118 | |
| SW-2502MD | 5/4/2026 8:31:32 AM | 28.68 | 1207 | 34.4337338 | -118.6518708 | Valve Adjustment:Audible Flow |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| SW-2502MD | 5/1/2026 8:41:00 AM | 28.68 | 1208 | 34.4337288 | -118.6518977 | Valve Adjustment:Audible Flow;Well Condition:Good |
| SW-2502S | 5/29/2026 6:54:54 AM | 28.74 | 1212 | 34.4337433 | -118.6518830 | Valve Adjustment:Valve 100% Open |
| SW-2502S | 5/28/2026 6:24:10 AM | 28.61 | 1248 | 34.4337530 | -118.6518642 | |
| SW-2502S | 5/27/2026 6:11:24 AM | 28.52 | 1207 | 34.4337375 | -118.6518813 | Valve Adjustment:Reduce Sys. Vac. - Flare Down |
| SW-2502S | 5/26/2026 6:23:43 AM | 28.59 | 1210 | 34.4337423 | -118.6518857 | |
| SW-2502S | 5/22/2026 6:29:06 AM | 28.56 | 1208 | 34.4337463 | -118.6518768 | |
| SW-2502S | 5/21/2026 6:47:21 AM | 28.6 | 1216 | 34.4337362 | -118.6518680 | |
| SW-2502S | 5/20/2026 8:12:10 AM | 28.67 | 1206 | 34.4337157 | -118.6519175 | Valve Adjustment:Valve 100% Open |
| SW-2502S | 5/19/2026 9:11:46 AM | 28.75 | 1211 | 34.4337440 | -118.6518923 | Valve Adjustment:Valve 100% Open |
| SW-2502S | 5/18/2026 8:53:31 AM | 28.64 | 1216 | 34.4337287 | -118.6518823 | |
| SW-2502S | 5/15/2026 9:00:33 AM | 28.71 | 1219 | 34.4337487 | -118.6518757 | |
| SW-2502S | 5/14/2026 8:31:19 AM | 28.75 | 1209 | 34.4337353 | -118.6518602 | Valve Adjustment:Valve 100% Open |
| SW-2502S | 5/13/2026 8:17:54 AM | 28.81 | 1207 | 34.4337320 | -118.6519045 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| SW-2502S | 5/12/2026 9:23:35 AM | 28.67 | 1211 | 34.4337322 | -118.6518982 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| SW-2502S | 5/11/2026 8:32:32 AM | 28.71 | 1220 | 34.4337297 | -118.6518908 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| SW-2502S | 5/8/2026 9:44:33 AM | 28.72 | 1221 | 34.4337133 | -118.6518933 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| SW-2502S | 5/7/2026 9:08:55 AM | 28.75 | 1215 | 34.4337305 | -118.6518963 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| SW-2502S | 5/6/2026 8:59:15 AM | 28.79 | 1224 | 34.4337393 | -118.6518947 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header |
| SW-2502S | 5/5/2026 8:44:34 AM | 28.67 | 1233 | 34.4337382 | -118.6519108 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header |
| SW-2502S | 5/4/2026 8:26:37 AM | 28.67 | 1210 | 34.4337507 | -118.6518850 | Valve Adjustment:Audible Flow |
| SW-2502S | 5/1/2026 8:35:09 AM | 28.68 | 1219 | 34.4337523 | -118.6518728 | Valve Adjustment:Audible Flow;Well Condition:Good |
| SW-2503D | 5/12/2026 8:21:40 AM | 28.64 | 1264 | 34.4351480 | -118.6516022 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| SW-2503D | 5/4/2026 8:56:42 AM | 28.64 | 1255 | 34.4351298 | -118.6516002 | |
| SW-2503M | 5/12/2026 8:27:21 AM | 28.64 | 1281 | 34.4351567 | -118.6516085 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| SW-2503M | 5/4/2026 9:01:03 AM | 28.65 | 1252 | 34.4351233 | -118.6516122 | |
| SW-2503MD | 5/12/2026 8:24:48 AM | 28.64 | 1288 | 34.4351615 | -118.6515915 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| SW-2503MD | 5/4/2026 8:58:22 AM | 28.64 | 1250 | 34.4351277 | -118.6516077 | |
| SW-2503S | 5/12/2026 8:35:33 AM | 28.64 | 1268 | 34.4351488 | -118.6516155 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| SW-2503S | 5/4/2026 9:03:12 AM | 28.66 | 1253 | 34.4351183 | -118.6515878 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| SW-2504D | 5/12/2026 8:47:37 AM | 28.63 | 1258 | 34.4353063 | -118.6516675 | Valve Adjustment:Valve 100% Open,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| SW-2504D | 5/4/2026 9:08:28 AM | 28.64 | 1273 | 34.4353260 | -118.6516635 | |
| SW-2504M | 5/12/2026 8:49:55 AM | 28.64 | 1254 | 34.4353062 | -118.6516587 | Valve Adjustment:Valve 100% Open,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| SW-2504M | 5/4/2026 9:18:12 AM | 28.66 | 1261 | 34.4353227 | -118.6516630 | |
| SW-2504MD | 5/20/2026 1:56:54 PM | 28.41 | 1395 | 34.4358698 | -118.6469320 | Valve Adjustment:High Temp,Barely Open |
| SW-2504MD | 5/12/2026 8:55:07 AM | 28.63 | 1260 | 34.4353003 | -118.6516498 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| SW-2504MD | 5/4/2026 9:22:21 AM | 28.63 | 1266 | 34.4353153 | -118.6516580 | |
| SW-2504S | 5/12/2026 8:51:59 AM | 28.63 | 1252 | 34.4353105 | -118.6516642 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| SW-2504S | 5/4/2026 9:20:08 AM | 28.66 | 1262 | 34.4353177 | -118.6516593 | |
| SW-30 | 5/22/2026 6:43:04 AM | 28.56 | 1216 | 34.4336823 | -118.6519708 | |
| SW-30 | 5/21/2026 7:02:29 AM | 28.62 | 1207 | 34.4336915 | -118.6519930 | |
| SW-30 | 5/20/2026 8:03:41 AM | 28.67 | 1212 | 34.4336927 | -118.6519757 | Valve Comment:no system vacuum |
| SW-30 | 5/19/2026 9:31:23 AM | 28.75 | 1208 | 34.4336892 | -118.6519593 | Valve Adjustment:Valve 100% Open |
| SW-30 | 5/18/2026 9:09:16 AM | 28.63 | 1220 | 34.4336838 | -118.6519710 | |
| SW-30 | 5/15/2026 8:48:17 AM | 28.71 | 1225 | 34.4336832 | -118.6519693 | |
| SW-30 | 5/14/2026 8:48:35 AM | 28.75 | 1214 | 34.4336768 | -118.6519695 | Valve Adjustment:High O2,Valve 100% Open |
| SW-30 | 5/13/2026 8:34:30 AM | 28.82 | 1212 | 34.4336890 | -118.6519803 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| SW-30 | 5/12/2026 9:39:11 AM | 28.67 | 1214 | 34.4336703 | -118.6519803 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| SW-30 | 5/11/2026 8:48:10 AM | 28.71 | 1211 | 34.4336732 | -118.6519857 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| SW-30 | 5/8/2026 10:07:17 AM | 28.72 | 1197 | 34.4336805 | -118.6519480 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| SW-30 | 5/7/2026 9:27:26 AM | 28.75 | 1209 | 34.4336878 | -118.6519507 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| SW-30 | 5/6/2026 9:14:39 AM | 28.8 | 1212 | 34.4336675 | -118.6519720 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header |
| SW-30 | 5/5/2026 9:02:34 AM | 28.67 | 1228 | 34.4336890 | -118.6519735 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header |
| SW-30 | 5/4/2026 8:36:47 AM | 28.67 | 1208 | 34.4336903 | -118.6519523 | Valve Adjustment:Audible Flow |
| SW-30 | 5/1/2026 8:52:33 AM | 28.69 | 1202 | 34.4336797 | -118.6519770 | |
| SW-32 | 5/22/2026 6:47:07 AM | 28.56 | 1214 | 34.4335298 | -118.6520503 | |
| SW-32 | 5/21/2026 7:10:28 AM | 28.63 | 1217 | 34.4335582 | -118.6520647 | |
| SW-32 | 5/20/2026 7:45:31 AM | 28.67 | 1212 | 34.4335388 | -118.6520643 | Valve Comment:no system vacuum |
| SW-32 | 5/19/2026 9:36:21 AM | 28.77 | 1212 | 34.4335622 | -118.6520468 | |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| SW-32 | 5/18/2026 9:14:33 AM | 28.67 | 1213 | 34.4335360 | -118.6520607 | |
| SW-32 | 5/15/2026 8:38:38 AM | 28.71 | 1223 | 34.4335537 | -118.6520568 | |
| SW-32 | 5/14/2026 8:53:16 AM | 28.75 | 1197 | 34.4335608 | -118.6520255 | Valve Adjustment:High O2,Valve 100% Open |
| SW-32 | 5/13/2026 8:29:37 AM | 28.82 | 1210 | 34.4335567 | -118.6520807 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| SW-32 | 5/12/2026 9:35:51 AM | 28.67 | 1207 | 34.4335182 | -118.6520840 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| SW-32 | 5/11/2026 8:43:32 AM | 28.71 | 1215 | 34.4335192 | -118.6520655 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| SW-32 | 5/8/2026 10:02:48 AM | 28.74 | 1204 | 34.4335547 | -118.6520470 | |
| SW-32 | 5/7/2026 9:20:49 AM | 28.75 | 1211 | 34.4335408 | -118.6520157 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| SW-32 | 5/6/2026 9:10:33 AM | 28.78 | 1212 | 34.4335333 | -118.6520437 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header |
| SW-32 | 5/5/2026 8:56:30 AM | 28.67 | 1242 | 34.4335462 | -118.6520752 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header |
| SW-32 | 5/4/2026 8:41:26 AM | 28.7 | 1210 | 34.4335462 | -118.6520488 | Valve Adjustment:Audible Flow |
| SW-32 | 5/1/2026 8:45:18 AM | 28.7 | 1213 | 34.4335513 | -118.6520683 | |
| SW-64 | 5/22/2026 6:40:52 AM | 28.56 | 1213 | 34.4336812 | -118.6519742 | |
| SW-64 | 5/21/2026 6:58:46 AM | 28.63 | 1212 | 34.4336817 | -118.6519637 | |
| SW-64 | 5/20/2026 8:05:22 AM | 28.68 | 1211 | 34.4336778 | -118.6519713 | Valve Comment:no system vacuum |
| SW-64 | 5/19/2026 9:28:23 AM | 28.75 | 1215 | 34.4336788 | -118.6519550 | Valve Adjustment:Valve 100% Open |
| SW-64 | 5/18/2026 9:06:40 AM | 28.64 | 1217 | 34.4336830 | -118.6519823 | |
| SW-64 | 5/15/2026 8:53:43 AM | 28.72 | 1221 | 34.4336715 | -118.6519645 | |
| SW-64 | 5/15/2026 8:43:20 AM | 28.71 | 1211 | 34.4336890 | -118.6519610 | |
| SW-64 | 5/14/2026 8:44:43 AM | 28.75 | 1215 | 34.4336845 | -118.6519588 | Valve Adjustment:Valve 100% Open |
| SW-64 | 5/13/2026 8:36:34 AM | 28.82 | 1224 | 34.4336830 | -118.6519827 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| SW-64 | 5/12/2026 9:41:18 AM | 28.67 | 1222 | 34.4336523 | -118.6520035 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| SW-64 | 5/11/2026 8:51:06 AM | 28.71 | 1209 | 34.4336463 | -118.6519725 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| SW-64 | 5/8/2026 10:09:00 AM | 28.73 | 1200 | 34.4336888 | -118.6519588 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| SW-64 | 5/7/2026 9:29:18 AM | 28.75 | 1211 | 34.4336797 | -118.6519615 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| SW-64 | 5/6/2026 9:16:27 AM | 28.78 | 1212 | 34.4336663 | -118.6519708 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header |
| SW-64 | 5/5/2026 9:04:48 AM | 28.67 | 1217 | 34.4336845 | -118.6519618 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| SW-64 | 5/4/2026 8:34:50 AM | 28.7 | 1205 | 34.4337058 | -118.6519478 | |
| SW-64 | 5/1/2026 8:47:28 AM | 28.7 | 1208 | 34.4336820 | -118.6519668 | |
| SW-65 | 5/11/2026 9:04:20 AM | 28.72 | 1230 | 34.4348140 | -118.6412388 | |
| SW-66 | 5/15/2026 9:29:15 AM | 28.7 | 1224 | 34.4380090 | -118.6456853 | NSPS/EG CAI,No Flow Measurement,High O2 |
| SW-66 | 5/15/2026 9:27:52 AM | 28.7 | 1224 | 34.4379907 | -118.6456665 | NSPS/EG CAI,No Flow Measurement,High O2 |
| SW-68 | 5/22/2026 6:45:28 AM | 28.56 | 1208 | 34.4335205 | -118.6520510 | |
| SW-68 | 5/21/2026 7:08:10 AM | 28.63 | 1220 | 34.4335510 | -118.6520482 | |
| SW-68 | 5/20/2026 7:47:12 AM | 28.67 | 1219 | 34.4335522 | -118.6520465 | Valve Comment:no system vacuum |
| SW-68 | 5/19/2026 9:34:10 AM | 28.76 | 1204 | 34.4335455 | -118.6520410 | |
| SW-68 | 5/18/2026 9:11:53 AM | 28.67 | 1214 | 34.4335280 | -118.6520707 | |
| SW-68 | 5/15/2026 8:34:05 AM | 28.71 | 1222 | 34.4335485 | -118.6520492 | |
| SW-68 | 5/14/2026 8:50:57 AM | 28.75 | 1219 | 34.4335452 | -118.6520222 | Valve Adjustment:Valve 100% Open |
| SW-68 | 5/13/2026 8:31:50 AM | 28.82 | 1214 | 34.4335455 | -118.6520567 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| SW-68 | 5/12/2026 9:37:18 AM | 28.67 | 1206 | 34.4335397 | -118.6520948 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| SW-68 | 5/11/2026 8:45:53 AM | 28.71 | 1207 | 34.4335247 | -118.6520480 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| SW-68 | 5/8/2026 10:04:26 AM | 28.72 | 1199 | 34.4335387 | -118.6520443 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| SW-68 | 5/7/2026 9:24:55 AM | 28.75 | 1209 | 34.4335365 | -118.6520248 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| SW-68 | 5/6/2026 9:12:20 AM | 28.8 | 1210 | 34.4335297 | -118.6520338 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header |
| SW-68 | 5/5/2026 8:59:48 AM | 28.67 | 1264 | 34.4335412 | -118.6520715 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header |
| SW-68 | 5/4/2026 8:39:10 AM | 28.7 | 1217 | 34.4335490 | -118.6520633 | Valve Adjustment:Audible Flow |
| SW-68 | 5/1/2026 8:43:53 AM | 28.67 | 1199 | 34.4335320 | -118.6520537 | |
| SW-7 | 5/1/2026 7:54:58 AM | 28.63 | 1260 | 34.4352020 | -118.6517087 | Valve Adjustment:Valve 100% Closed |
| SW-70 | 5/4/2026 9:33:46 AM | 28.59 | 1305 | 34.4372625 | -118.6473485 | |
| SW-71 | 5/6/2026 8:31:08 AM | 28.89 | 1148 | 34.4264685 | -118.6431520 | NSPS/EG CAI,High O2 |
| SW-71 | 5/6/2026 8:23:03 AM | 28.89 | 1161 | 34.4260092 | -118.6437895 | NSPS/EG CAI,High O2 |
| SW-72 | 5/6/2026 9:25:28 AM | 28.82 | 1207 | 34.4296255 | -118.6402233 | |
| SW-80 | 5/12/2026 1:23:15 PM | 28.72 | 1200 | 34.4383478 | -118.6433552 | |
| SW-9 | 5/4/2026 9:35:40 AM | 28.59 | 1301 | 34.4372647 | -118.6473453 | |
| TC-1961C | 5/4/2026 11:11:27 AM | 28.63 | 1293 | 34.4321622 | -118.6454215 | Valve Adjustment:Decreased Flow/Vacuum |
| TC-1961E | 5/4/2026 10:42:18 AM | 28.65 | 1279 | 34.4328602 | -118.6444918 | Valve Adjustment:Audible Flow;Well Condition:Good |
| TC-2174 | 5/26/2026 9:02:15 AM | 28.47 | 1361 | 34.4367612 | -118.6476127 | Valve Adjustment:High Temp |
| TC-2174 | 5/18/2026 9:25:30 AM | 28.52 | 1358 | 34.4367364 | -118.6476178 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Valve 100% Open,Reduce Sys. Vac. - Flare Down |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press ["Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| TC-2174 | 5/18/2026 9:25:00 AM | | | | | AtmAA |
| TC-2174 | 5/18/2026 9:24:46 AM | 28.53 | 1359 | 34.4367335 | -118.6476142 | Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down |
| TC-2174 | 5/12/2026 9:30:00 AM | | | | | AtmAA |
| TC-2174 | 5/12/2026 9:24:37 AM | 28.55 | 1375 | 34.4367281 | -118.6476308 | Valve Adjustment:High Temp |
| TC-2174 | 5/5/2026 8:40:00 AM | | | | | AtmAA |
| TC-2174 | 5/5/2026 8:40:00 AM | | | | | AtmAA; [User entered 15.9%] |
| TC-2174 | 5/5/2026 8:34:39 AM | 28.55 | 1331 | 34.4367353 | -118.6476258 | Valve Adjustment:High Temp |
| VL-02 | 5/28/2026 3:26:30 PM | 28.67 | 1199 | 34.4311807 | -118.6442960 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| WTD-01 | 5/21/2026 5:51:51 AM | 28.52 | 1245 | 34.4350053 | -118.6514630 | Valve Adjustment:NSPS/EG CAI,High Temp,High O2 |
| WTD-01 | 5/21/2026 5:51:17 AM | 28.52 | 1247 | 34.4350058 | -118.6514597 | Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,High O2 |
| WTD-01 | 5/1/2026 7:48:21 AM | 28.62 | 1262 | 34.4350075 | -118.6514362 | Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,High O2,Surging Liquid in Header |
| WTD-01 | 5/1/2026 7:47:42 AM | 28.62 | 1255 | 34.4350090 | -118.6514338 | Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Surging Liquid in Header |
| WTD-02 | 5/21/2026 5:58:44 AM | 28.56 | 1256 | 34.4346255 | -118.6513182 | Valve Adjustment:NSPS/EG CAI,High Temp,High O2 |
| WTD-02 | 5/21/2026 5:58:19 AM | 28.56 | 1238 | 34.4346337 | -118.6512968 | Valve Comment:Enhanced Monitoring;Valve Adjustment:NSPS/EG CAI,High Temp,High O2 |
| WTD-02 | 5/13/2026 1:51:34 PM | 28.77 | 1318 | 34.4345837 | -118.6513707 | Valve Adjustment:No Flow Measurement,High Temp |
| WTD-02 | 5/13/2026 1:50:30 PM | 28.77 | 1320 | 34.4345898 | -118.6513641 | Valve Adjustment:No Flow Measurement,High Temp |
| WTD-02 | 5/6/2026 1:50:52 PM | 28.7 | 1248 | 34.4346817 | -118.6513428 | Valve Adjustment:High Temp,High O2,Valve 100% Open |
| WTD-02 | 5/6/2026 1:50:00 PM | | | | | AtmAA |
| WTD-02 | 5/6/2026 1:50:00 PM | | | | | AtmAA; [User entered 7.68%] |
| WTD-02 | 5/6/2026 1:49:41 PM | 28.7 | 1247 | 34.4346819 | -118.6513428 | Valve Adjustment:High Temp,High O2 |
| WTD-03 | 5/21/2026 6:07:17 AM | 28.56 | 1239 | 34.4344147 | -118.6514263 | Valve Adjustment:NSPS/EG CAI,High O2 |
| WTD-03 | 5/21/2026 6:06:19 AM | 28.56 | 1243 | 34.4344167 | -118.6514338 | Valve Adjustment:NSPS/EG CAI,High O2 |
| WTD-03 | 5/1/2026 8:09:37 AM | 28.63 | 1245 | 34.4344027 | -118.6514297 | Valve Adjustment:NSPS/EG CAI,High O2 |
| WTD-03 | 5/1/2026 8:08:56 AM | 28.63 | 1245 | 34.4343962 | -118.6514357 | Valve Adjustment:NSPS/EG CAI,High O2,Surging Liquid in Header |
| WTD-04 | 5/21/2026 6:19:17 AM | 28.59 | 1223 | 34.4340143 | -118.6516873 | Valve Adjustment:NSPS/EG CAI,High O2 |
| WTD-04 | 5/21/2026 6:16:55 AM | 28.59 | 1217 | 34.4340173 | -118.6516852 | Valve Adjustment:NSPS/EG CAI,High O2 |
| WTD-04 | 5/1/2026 8:15:02 AM | 28.67 | 1215 | 34.4340045 | -118.6516995 | Valve Adjustment:NSPS/EG CAI,High O2 |
| WTD-04 | 5/1/2026 8:14:32 AM | 28.66 | 1215 | 34.4340052 | -118.6517005 | Valve Adjustment:NSPS/EG CAI,High O2 |
| WTD-05 | 5/21/2026 6:13:19 AM | 28.59 | 1222 | 34.4339415 | -118.6517192 | Valve Adjustment:NSPS/EG CAI,High O2 |
| WTD-05 | 5/21/2026 6:12:45 AM | 28.59 | 1233 | 34.4339420 | -118.6517235 | Valve Adjustment:NSPS/EG CAI,High O2 |
| WTD-05 | 5/1/2026 8:12:57 AM | 28.66 | 1199 | 34.4339320 | -118.6517167 | Valve Adjustment:NSPS/EG CAI,High O2 |
| WTD-05 | 5/1/2026 8:12:16 AM | 28.63 | 1216 | 34.4339352 | -118.6517073 | Valve Adjustment:NSPS/EG CAI,High O2 |
| WTD-06 | 5/21/2026 6:21:19 AM | 28.6 | 1214 | 34.4335052 | -118.6519012 | Valve Adjustment:NSPS/EG CAI,High O2 |
| WTD-06 | 5/21/2026 6:20:59 AM | 28.6 | 1215 | 34.4334972 | -118.6518953 | Valve Adjustment:NSPS/EG CAI,High O2 |

# All LFG Extraction Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | Baro Press [”Hg] | Elev [ft] | Latitude | Longitude | Comments |
|---|---|---|---|---|---|---|
| WTD-06 | 5/1/2026 8:20:07 AM | 28.67 | 1196 | 34.4334278 | -118.6518478 | Valve Adjustment:NSPS/EG CAI,High O2 |
| WTD-06 | 5/1/2026 8:17:56 AM | 28.67 | 1202 | 34.4335033 | -118.6518977 | Valve Adjustment:NSPS/EG CAI,High O2 |
| WTD-07 | 5/21/2026 6:25:15 AM | 28.59 | 1215 | 34.4334962 | -118.6519032 | Valve Adjustment:NSPS/EG CAI,High O2 |
| WTD-07 | 5/21/2026 6:24:46 AM | 28.6 | 1210 | 34.4334957 | -118.6518975 | Valve Adjustment:NSPS/EG CAI,High O2 |
| WTD-07 | 5/1/2026 8:22:32 AM | 28.67 | 1207 | 34.4334967 | -118.6518982 | Valve Adjustment:NSPS/EG CAI,High O2 |
| WTD-07 | 5/1/2026 8:21:58 AM | 28.67 | 1207 | 34.4334967 | -118.6518982 | Valve Adjustment:NSPS/EG CAI,High O2 |
| WTD-10 | 5/21/2026 7:17:44 AM | 28.63 | 1203 | 34.4324603 | -118.6518485 | Valve Adjustment:NSPS/EG CAI,High O2 |
| WTD-10 | 5/21/2026 7:17:13 AM | 28.63 | 1211 | 34.4324672 | -118.6518500 | Valve Adjustment:NSPS/EG CAI,High O2 |
| WTD-10 | 5/4/2026 8:01:28 AM | 28.69 | 1224 | 34.4324627 | -118.6518968 | Valve Adjustment:NSPS/EG CAI,High O2 |
| WTD-10 | 5/4/2026 8:00:56 AM | 28.7 | 1210 | 34.4324545 | -118.6518852 | Valve Adjustment:NSPS/EG CAI,High O2 |

# Table 2. Monthly LEA Selected Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | Init Temp [°R] | Adj Temp [°R] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Sys Pressure ["H2O] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CV-108-52 | 5/1/2026 10:29:07 AM | 47.7 | 51.3 | 0.0 | 1.0 | | | 98.6 | 99.7 | -6.51 | -6.42 | -7.71 | Valve Adjustment:Barely Open |
| CV-108-52 | 5/6/2026 8:30:00 AM | | | | | 100 | 6600 | | | | | | Air Tech Lab |
| CV-108-52 | 5/19/2026 1:02:47 PM | 50.4 | 48.9 | 0.0 | 0.7 | | | 101.2 | 101.6 | -2.70 | -2.78 | -2.90 | Valve Adjustment:Barely Open,Surging Liquid in Header |
| CV-113 | 5/4/2026 7:50:00 AM | | | | | | 24000 | | | | | | Air Tech Lab; [User entered 2.4%] |
| CV-113 | 5/15/2026 9:28:02 AM | 9.6 | 85.1 | 0.0 | 5.3 | | | 65.9 | 66.6 | -0.24 | -0.23 | -3.12 | |
| CV-113 | 5/26/2026 2:01:29 PM | 9.9 | 88.1 | 0.0 | 2.0 | | | 72.8 | 72.9 | -0.39 | -0.35 | -3.32 | Valve Adjustment:Barely Open |
| CV-114 | 5/4/2026 8:05:00 AM | | | | | | 2800 | | | | | | Air Tech Lab; [User entered 0.28%] |
| CV-114 | 5/5/2026 8:32:18 AM | 2.2 | 80.1 | 0.0 | 17.7 | | | 174.3 | 173.1 | -2.04 | -2.13 | -5.67 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-114 | 5/5/2026 8:35:00 AM | | | | | | 161800 | | | | | | AtmAA; [User entered 16.18%] |
| CV-114 | 5/5/2026 8:35:00 AM | | | | | 3350 | | | | | | | AtmAA |
| CV-114 | 5/12/2026 9:22:16 AM | 18.6 | 81.4 | 0.0 | 0.0 | | | 173.1 | 174.3 | -1.52 | -1.56 | -5.10 | Valve Adjustment:High Temp |
| CV-114 | 5/12/2026 9:25:00 AM | | | | | 1750 | | | | | | | AtmAA |
| CV-114 | 5/18/2026 9:17:57 AM | 14.0 | 75.7 | 0.0 | 10.3 | | | 160.9 | 163.8 | 1.57 | 1.59 | -1.83 | Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum,Valve 100% Open,Reduce Sys. Vac. - Flare Down |
| CV-114 | 5/18/2026 9:20:00 AM | | | | | 4380 | | | | | | | AtmAA |
| CV-114 | 5/18/2026 9:20:17 AM | 14.4 | 78.4 | 0.0 | 7.2 | | | 164.5 | 164.4 | 1.25 | 1.34 | -1.86 | Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down |
| CV-114 | 5/26/2026 8:58:28 AM | 1.0 | 78.6 | 0.0 | 20.4 | | | 170.5 | 170.7 | -0.17 | -0.65 | 0.23 | Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-1532A | 5/11/2026 8:15:00 AM | | | | | | 61000 | | | | | | Air Tech Lab; [User entered 6.1%] |
| CV-1532A | 5/11/2026 8:15:00 AM | | | | | 580 | | | | | | | Air Tech Lab |
| CV-1532A | 5/13/2026 1:07:32 PM | 11.9 | 58.0 | 6.5 | 23.6 | | | 81.9 | 81.9 | -3.42 | -3.87 | -5.11 | Comments:,,,,,,, |
| CV-1532A | 5/13/2026 1:09:52 PM | 8.2 | 38.6 | 11.4 | 41.8 | | | 81.8 | 81.7 | -4.01 | -5.13 | -5.14 | Comments:,,,,,,, |
| CV-1532A | 5/28/2026 8:54:46 AM | 6.7 | 68.0 | 4.2 | 21.1 | | | 66.9 | 66.6 | -6.50 | -6.24 | -5.83 | Valve Adjustment:Barely Open;Well Comment:System surging |
| CV-1535 | 5/1/2026 10:31:55 AM | 45.2 | 51.2 | 0.0 | 3.6 | | | 120.4 | 120.4 | -0.90 | -0.82 | -8.20 | Valve Adjustment:Audible Flow;Well Condition:Good |
| CV-1535 | 5/11/2026 8:25:00 AM | | | | | | 9800 | | | | | | Air Tech Lab; [User entered 0.98%] |
| CV-1535 | 5/11/2026 8:25:00 AM | | | | | 100 | | | | | | | Air Tech Lab |
| CV-1535 | 5/19/2026 12:55:31 PM | 44.5 | 49.2 | 0.0 | 6.3 | | | 119.7 | 119.5 | -0.23 | -0.22 | -3.25 | Valve Adjustment:Barely Open |
| CV-1902A | 5/6/2026 9:05:00 AM | | | | | | 161050 | | | | | | AtmAA; [User entered 16.105%] |
| CV-1902A | 5/6/2026 9:05:00 AM | | | | | 1130 | | | | | | | AtmAA |
| CV-1902A | 5/6/2026 9:06:28 AM | 10.5 | 78.0 | 0.0 | 11.5 | | | 160.9 | 159.6 | -6.78 | -6.73 | -6.80 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-1902A | 5/11/2026 7:55:00 AM | | | | | | 190000 | | | | | | Air Tech Lab; [User entered 19%] |
| CV-1902A | 5/11/2026 7:55:00 AM | | | | | 930 | | | | | | | Air Tech Lab |
| CV-1902A | 5/11/2026 1:48:31 PM | 9.5 | 80.8 | 0.0 | 9.7 | | | 149.5 | 152.7 | -3.48 | -3.32 | 9.42 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-1902A | 5/14/2026 1:48:17 PM | 2.1 | 79.7 | 0.0 | 18.2 | | | 167.2 | 168.6 | -5.46 | -5.64 | -5.50 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum |
| CV-1902A | 5/20/2026 8:10:11 AM | 8.0 | 77.7 | 0.0 | 14.3 | | | 156.7 | 157.4 | -5.28 | -5.26 | -5.00 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-1902A | 5/28/2026 8:49:43 AM | 1.8 | 79.3 | 0.0 | 18.9 | | | 174.2 | 172.3 | -7.63 | -7.66 | -7.45 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-2001 | 5/1/2026 10:12:38 AM | 10.4 | 78.3 | 2.1 | 9.2 | | | 85.8 | 86.2 | -6.24 | -5.48 | -6.26 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-2001 | 5/6/2026 7:50:00 AM | | | | | | 82000 | | | | | | Air Tech Lab; [User entered 8.2%] |
| CV-2001 | 5/6/2026 7:50:00 AM | | | | | 780 | | | | | | | Air Tech Lab |
| CV-2001 | 5/12/2026 8:45:06 AM | 12.0 | 76.2 | 1.0 | 10.8 | | | 76.1 | 76.2 | -2.86 | -3.81 | -4.37 | Comments:No Adjustment Made,,,,,,, |
| CV-2001 | 5/20/2026 9:55:23 AM | 11.8 | 79.2 | 0.0 | 9.0 | | | 103.2 | 103.3 | -4.03 | -4.05 | -4.19 | Valve Adjustment:Barely Open |

# Table 2. Monthly LEA Selected Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | Init Temp [°F] | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Sys Pressure ["H2O] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CV-2002 | 5/6/2026 1:02:03 PM | 35.3 | 64.7 | 0.0 | 0.0 | | | 181.7 | 181.8 | -1.14 | -1.31 | -4.81 | Valve Adjustment:High Temp,Surging Liquid in Well (Watered In) |
| CV-2002 | 5/6/2026 1:05:00 PM | | | | | | 137200 | | | | | | AtmAA; [User entered 13.72%] |
| CV-2002 | 5/6/2026 1:05:00 PM | | | | | 3900 | | | | | | | AtmAA |
| CV-2002 | 5/11/2026 8:10:00 AM | | | | | | 83000 | | | | | | Air Tech Lab; [User entered 8.3%] |
| CV-2002 | 5/11/2026 8:10:00 AM | | | | | 860 | | | | | | | Air Tech Lab |
| CV-2002 | 5/13/2026 10:09:19 AM | 9.0 | 64.5 | 2.4 | 24.1 | | | 181.6 | 181.8 | -0.82 | -1.05 | 0.23 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2002 | 5/20/2026 9:41:05 AM | 42.1 | 55.6 | 2.3 | 0.0 | | | 177.9 | 178.0 | -3.15 | -2.83 | -4.07 | Valve Adjustment:High Temp,Decreased Flow/Vacuum |
| CV-2002 | 5/20/2026 9:42:31 AM | 43.3 | 54.7 | 2.0 | 0.0 | | | 178.6 | 178.6 | -2.21 | -2.02 | -3.82 | Valve Adjustment:High Temp |
| CV-2002 | 5/28/2026 10:12:21 AM | 9.3 | 74.6 | 0.0 | 16.1 | | | 183.5 | 183.6 | 0.35 | -0.67 | -2.10 | Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum,Plugged/Pinched Suspected;Well Comment:Pinched in the vacuum line |
| CV-2002 | 5/28/2026 10:15:53 AM | 9.6 | 74.7 | 0.0 | 15.7 | | | 183.5 | 182.2 | -0.75 | -0.81 | -0.97 | Valve Adjustment:NSPS/EG CAC,High Temp |
| CV-2007 | 5/4/2026 8:10:00 AM | | | | | | 59000 | | | | | | Air Tech Lab; [User entered 5.9%] |
| CV-2007 | 5/8/2026 9:48:29 AM | 20.5 | 75.0 | 0.0 | 4.5 | | | 93.2 | 93.8 | -0.01 | -0.03 | -3.18 | Comments:Reduced System Vacuum,,,,,,, |
| CV-2007 | 5/20/2026 2:00:34 PM | 19.9 | 75.6 | 0.0 | 4.5 | | | 111.1 | 112.8 | -0.10 | -0.11 | -7.42 | Valve Adjustment:Barely Open |
| CV-2301 | 5/7/2026 7:55:00 AM | | | | | | 150000 | | | | | | Air Tech Lab; [User entered 15%] |
| CV-2301 | 5/7/2026 7:55:00 AM | | | | | 2200 | | | | | | | Air Tech Lab |
| CV-2301 | 5/14/2026 10:52:08 AM | 30.7 | 61.8 | 0.0 | 7.5 | | | 182.0 | 182.0 | -7.30 | -7.24 | -7.47 | Valve Comment:Valve too high to adjust;Valve Adjustment:NSPS/EG CAI,High Temp;Well Comment:No Pump |
| CV-2301 | 5/14/2026 10:53:50 AM | 31.1 | 62.4 | 0.0 | 6.5 | | | 182.0 | 182.0 | -7.32 | -7.34 | -7.59 | |
| CV-2301 | 5/14/2026 11:20:00 AM | | | | | 1170 | | | | | | | AtmAA |
| CV-2301 | 5/19/2026 10:15:00 AM | | | | | 990 | | | | | | | AtmAA |
| CV-2301 | 5/19/2026 10:15:36 AM | 48.3 | 51.4 | 0.3 | 0.0 | | | 165.0 | 165.0 | -7.06 | -5.74 | -6.74 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-2301 | 5/19/2026 10:16:23 AM | 47.8 | 52.2 | 0.0 | 0.0 | | | 164.0 | | -5.72 | | -6.88 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2301 | 5/27/2026 10:36:57 AM | 21.7 | 65.2 | 0.1 | 13.0 | | | 160.0 | 158.0 | -4.82 | -1.81 | -6.24 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-2301 | 5/27/2026 10:38:04 AM | 13.5 | 69.3 | 0.0 | 17.2 | | | 158.0 | 158.0 | -2.47 | -2.44 | -6.22 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2302 | 5/4/2026 9:06:38 AM | 42.4 | 51.8 | 0.1 | 5.7 | | | 121.6 | 121.6 | -9.44 | -9.45 | -9.66 | Valve Adjustment:Valve 100% Open;Well Comment:valve stuck open |
| CV-2302 | 5/7/2026 8:05:00 AM | | | | | | 53000 | | | | | | Air Tech Lab; [User entered 5.3%] |
| CV-2302 | 5/7/2026 8:05:00 AM | | | | | 320 | | | | | | | Air Tech Lab |
| CV-2302 | 5/22/2026 3:57:06 PM | 42.2 | 50.6 | 0.7 | 6.5 | | | 120.2 | 121.0 | -5.04 | -5.07 | -5.32 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-2303 | 5/5/2026 2:21:44 PM | 14.0 | 80.9 | 0.0 | 5.1 | | | 189.5 | 187.7 | -3.85 | -3.77 | 0.27 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2303 | 5/5/2026 2:25:00 PM | | | | | | 165800 | | | | | | AtmAA; [User entered 16.58%] |
| CV-2303 | 5/5/2026 2:25:00 PM | | | | | 2170 | | | | | | | AtmAA |
| CV-2303 | 5/12/2026 8:30:00 AM | | | | | | 190000 | | | | | | Air Tech Lab; [User entered 19%] |
| CV-2303 | 5/12/2026 8:30:00 AM | | | | | 2000 | | | | | | | Air Tech Lab |
| CV-2303 | 5/13/2026 2:13:55 PM | 2.0 | 75.5 | 0.0 | 22.5 | | | 188.9 | 190.0 | -4.70 | -4.13 | -4.68 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2303 | 5/19/2026 8:36:23 AM | 14.0 | 79.4 | 0.0 | 6.6 | | | 187.2 | 187.5 | -4.52 | -4.52 | -4.26 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2303 | 5/19/2026 8:40:00 AM | | | | | 2480 | | | | | | | AtmAA |
| CV-2303 | 5/27/2026 9:02:45 AM | 1.3 | 77.6 | 0.0 | 21.1 | | | 181.2 | 179.8 | -2.09 | -2.13 | 0.01 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2305 | 5/4/2026 8:50:00 AM | 16.1 | 73.3 | 0.0 | 10.6 | | | 149.9 | 149.9 | -1.66 | -1.01 | -1.61 | Valve Adjustment:High Temp |
| CV-2305 | 5/12/2026 8:10:00 AM | | | | | | 82000 | | | | | | Air Tech Lab; [User entered 8.2%] |
| CV-2305 | 5/12/2026 8:10:00 AM | | | | | 1700 | | | | | | | Air Tech Lab |

# Table 2. Monthly LEA Selected Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | Init Well Temp [ °F ] | Adj Well Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Sys Pressure ["H2O] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CV-2305 | 5/14/2026 10:09:35 AM | 31.0 | 69.0 | 0.0 | 0.0 | | | 150.0 | 150.3 | -1.47 | -1.47 | -1.89 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed |
| CV-2305 | 5/14/2026 10:11:00 AM | | | | | 2380 | | | | | | | AtmAA |
| CV-2305 | 5/19/2026 1:19:18 PM | 38.8 | 61.2 | 0.0 | 0.0 | | | 148.9 | 149.2 | -0.17 | -0.60 | -0.74 | Valve Adjustment:High Temp,Valve 100% Open,Surging Liquid in Header |
| CV-2305 | 5/19/2026 1:20:00 PM | | | | | 2420 | | | | | | | AtmAA |
| CV-2305 | 5/27/2026 2:23:44 PM | 16.2 | 77.8 | 0.0 | 6.0 | | | 149.1 | 149.3 | 2.27 | 1.95 | 2.18 | Valve Adjustment:High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Header |
| CV-2305 | 5/27/2026 2:24:19 PM | 17.7 | 79.8 | 0.0 | 2.5 | | | 149.7 | 149.4 | 2.23 | 2.20 | 2.14 | Valve Adjustment:High Temp,Positive Static Press.,Surging Liquid in Header |
| CV-2312 | 5/4/2026 10:15:00 AM | | | | | | 120300 | | | | | | AtmAA; [User entered 12.03%] |
| CV-2312 | 5/4/2026 10:15:00 AM | | | | | 3840 | | | | | | | AtmAA |
| CV-2312 | 5/4/2026 10:27:12 AM | 1.5 | 62.9 | 3.1 | 32.5 | | | 168.1 | 168.1 | 23.02 | 25.84 | -9.17 | Valve Comment:Active plr;Valve Adjustment:No Flow Measurement |
| CV-2312 | 5/4/2026 10:29:04 AM | 1.8 | 78.3 | 0.0 | 19.9 | | | 167.9 | 168.0 | 27.20 | 23.82 | -8.85 | Valve Comment:Active PLR;Valve Adjustment:No Flow Measurement,High Temp |
| CV-2312 | 5/13/2026 8:30:00 AM | | | | | | 90000 | | | | | | Air Tech Lab; [User entered 9.0%] |
| CV-2312 | 5/13/2026 8:30:00 AM | | | | | 1800 | | | | | | | Air Tech Lab |
| CV-2312 | 5/13/2026 9:06:06 AM | 7.7 | 81.8 | 0.2 | 10.3 | | | 168.2 | 168.2 | -6.54 | -4.12 | -8.03 | Valve Comment:ACTIVE PLR;Valve Adjustment:No Flow Measurement,High Temp;Well Comment:Installed sample ports on now hard pipe well |
| CV-2312 | 5/13/2026 11:08:10 AM | 2.5 | 78.9 | 0.4 | 18.2 | | | 169.2 | 169.3 | -16.73 | -16.28 | -7.70 | Valve Adjustment:NSPS/EG CAI,Audible Flow,No Flow Measurement,High Temp |
| CV-2312 | 5/19/2026 10:35:00 AM | | | | | 3070 | | | | | | | AtmAA |
| CV-2312 | 5/19/2026 10:35:25 AM | 16.8 | 78.0 | 0.0 | 5.2 | | | 168.5 | 168.5 | -2.64 | -1.13 | -5.08 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In) |
| CV-2312 | 5/27/2026 11:01:39 AM | 3.5 | 80.0 | 0.1 | 16.4 | | | 167.9 | 167.7 | -3.07 | -5.30 | -3.98 | Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Well (Watered In) |
| CV-2314 | 5/4/2026 9:40:00 AM | | | | | | 110000 | | | | | | AtmAA; [User entered 11%] |
| CV-2314 | 5/4/2026 9:40:00 AM | | | | | 4010 | | | | | | | AtmAA |
| CV-2314 | 5/4/2026 9:40:25 AM | 7.3 | 77.6 | 0.0 | 15.1 | | | 177.9 | 178.1 | -2.93 | -2.18 | -13.31 | Valve Adjustment:High Temp |
| CV-2314 | 5/11/2026 10:32:15 AM | 8.2 | 88.6 | 0.0 | 3.2 | | | 180.2 | 180.2 | -2.16 | -1.11 | -13.13 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header |
| CV-2314 | 5/12/2026 8:05:00 AM | | | | | | 140000 | | | | | | Air Tech Lab; [User entered 14%] |
| CV-2314 | 5/12/2026 8:05:00 AM | | | | | 3400 | | | | | | | Air Tech Lab |
| CV-2314 | 5/14/2026 1:49:32 PM | 0.9 | 90.5 | 0.1 | 8.5 | | | 177.6 | 178.0 | -8.65 | -2.73 | -11.53 | Comments:NSPS/EG CAI,High Temp,,,,,, |
| CV-2314 | 5/14/2026 1:50:56 PM | 0.7 | 90.4 | 0.0 | 8.9 | | | 178.0 | 178.0 | -2.53 | -2.89 | -11.70 | Comments:,,,,,,, |
| CV-2314 | 5/19/2026 1:53:23 PM | 23.9 | 76.1 | 0.0 | 0.0 | | | 179.3 | 180.1 | -3.30 | -3.03 | 0.00 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2314 | 5/19/2026 2:00:00 PM | | | | | 3840 | | | | | | | AtmAA |
| CV-2314 | 5/27/2026 1:45:46 PM | 1.3 | 84.1 | 0.0 | 14.6 | | | 179.8 | 179.5 | -0.26 | -3.78 | -7.67 | Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum |
| CV-2314 | 5/27/2026 1:46:16 PM | 1.4 | 85.2 | 0.0 | 13.4 | | | 179.7 | 179.8 | -3.66 | -3.61 | -7.85 | Valve Adjustment:High Temp |
| CV-2315 | 5/6/2026 3:25:58 PM | 3.1 | 92.1 | 0.0 | 4.8 | | | 183.6 | 183.9 | -0.26 | -1.85 | -5.72 | Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum |
| CV-2315 | 5/6/2026 3:27:40 PM | 4.6 | 80.6 | 0.6 | 14.2 | | | 183.9 | 183.9 | -2.69 | -2.61 | -4.69 | Valve Comment:LORENTZ PUMP DISCONECTED;Valve Adjustment:No Flow Measurement,High Temp |
| CV-2315 | 5/6/2026 3:30:00 PM | | | | | | 83300 | | | | | | AtmAA; [User entered 8.33%] |
| CV-2315 | 5/6/2026 3:30:00 PM | | | | | 2530 | | | | | | | AtmAA |
| CV-2315 | 5/7/2026 8:30:00 AM | | | | | | 140000 | | | | | | Air Tech Lab; [User entered 14%] |
| CV-2315 | 5/7/2026 8:30:00 AM | | | | | 3900 | | | | | | | Air Tech Lab |

# Table 2. Monthly LEA Selected Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | Init Temp [ °F ] | Adj Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Sys Pressure ["H2O] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CV-2315 | 5/11/2026 8:41:37 AM | 2.8 | 85.7 | 0.0 | 11.5 | | | 158.8 | 156.4 | 0.34 | 0.79 | 1.38 | Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open |
| CV-2315 | 5/13/2026 1:42:47 PM | 5.1 | 79.0 | 0.1 | 15.8 | | | 177.4 | 177.7 | -2.57 | -3.27 | -3.13 | Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header |
| CV-2315 | 5/13/2026 1:43:34 PM | 5.2 | 78.4 | 0.0 | 16.4 | | | 177.6 | 178.3 | -2.68 | -2.67 | -3.16 | |
| CV-2315 | 5/19/2026 1:31:37 PM | 22.0 | 75.5 | 0.0 | 2.5 | | | 184.8 | 184.8 | -1.16 | -1.16 | 0.00 | Valve Comment:Lorentz pump disconnected;Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open;Well Condition:Lorentz Pump Installed |
| CV-2315 | 5/19/2026 1:35:00 PM | | | | | 4320 | | | | | | | AtmAA |
| CV-2315 | 5/26/2026 10:35:23 AM | 10.0 | 79.9 | 0.1 | 10.0 | | | 182.5 | 182.5 | -5.71 | -5.70 | 0.34 | Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open |
| CV-2328 | 5/4/2026 1:05:00 PM | | | | | | 53600 | | | | | | AtmAA; [User entered 5.36%] |
| CV-2328 | 5/4/2026 1:05:00 PM | | | | | 661 | | | | | | | AtmAA |
| CV-2328 | 5/4/2026 1:06:42 PM | 5.8 | 82.6 | 0.0 | 11.6 | | | 171.5 | 172.4 | 8.45 | -2.28 | -11.61 | Valve Adjustment:NSPS/EG CAI,Audible Flow,Increased Flow/Vacuum |
| CV-2328 | 5/4/2026 1:07:16 PM | 5.4 | 87.3 | 0.0 | 7.3 | | | 172.5 | 172.4 | -2.16 | -2.13 | -10.37 | Valve Adjustment:NSPS/EG CAC,Audible Flow,High Temp |
| CV-2328 | 5/7/2026 8:15:00 AM | | | | | | 110000 | | | | | | Air Tech Lab; [User entered 11%] |
| CV-2328 | 5/7/2026 8:15:00 AM | | | | | 980 | | | | | | | Air Tech Lab |
| CV-2328 | 5/11/2026 1:26:04 PM | 34.7 | 65.3 | 0.0 | 0.0 | | | 144.6 | 146.7 | -0.54 | -0.53 | -1.24 | Valve Adjustment:High Temp,Reduce Sys. Vac. - Flare Down |
| CV-2328 | 5/20/2026 2:05:13 PM | 13.2 | 74.3 | 0.0 | 12.5 | | | 167.2 | 167.4 | -0.64 | -1.43 | -7.41 | Valve Adjustment:High Temp,Increased Flow/Vacuum |
| CV-2328 | 5/20/2026 2:06:30 PM | 13.2 | 72.4 | 0.0 | 14.4 | | | 167.3 | 167.3 | -1.36 | -1.29 | -6.96 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed |
| CV-2328 | 5/28/2026 1:37:05 PM | 13.1 | 76.8 | 0.0 | 10.1 | | | 164.9 | 164.9 | -3.56 | -3.67 | -8.49 | Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header |
| CV-2333 | 5/5/2026 8:26:49 AM | 1.3 | 85.7 | 0.0 | 13.0 | | | 165.9 | 165.9 | -6.44 | -6.41 | -5.79 | Valve Adjustment:Audible Flow,High Temp |
| CV-2333 | 5/5/2026 8:30:00 AM | | | | | | 160100 | | | | | | AtmAA; [User entered 16.01%] |
| CV-2333 | 5/5/2026 8:30:00 AM | | | | | 4590 | | | | | | | AtmAA |
| CV-2333 | 5/6/2026 9:44:40 AM | 0.6 | 82.8 | 0.0 | 16.6 | | | 191.2 | 191.2 | -3.78 | -3.83 | -2.94 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-2333 | 5/6/2026 9:45:24 AM | 0.6 | 82.4 | 0.0 | 17.0 | | | 191.3 | 191.3 | -3.95 | -3.93 | -3.32 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-2333 | 5/12/2026 9:28:21 AM | 13.6 | 81.1 | 0.0 | 5.3 | | | 177.0 | 178.1 | -5.29 | -4.99 | -4.80 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2333 | 5/12/2026 9:35:00 AM | | | | | 2400 | | | | | | | AtmAA |
| CV-2333 | 5/13/2026 7:40:00 AM | | | | | | 160000 | | | | | | Air Tech Lab; [User entered 16%] |
| CV-2333 | 5/13/2026 7:40:00 AM | | | | | 3600 | | | | | | | Air Tech Lab |
| CV-2333 | 5/18/2026 9:12:06 AM | 8.1 | 75.1 | 0.0 | 16.8 | | | 157.9 | 158.1 | -1.10 | -0.47 | -1.03 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2333 | 5/18/2026 9:15:00 AM | | | | | 4360 | | | | | | | AtmAA |
| CV-2333 | 5/26/2026 8:54:11 AM | 0.7 | 76.3 | 0.0 | 23.0 | | | 163.1 | 170.3 | -2.38 | -2.72 | -2.18 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2333 | 5/29/2026 9:43:07 AM | 0.9 | 77.1 | 0.0 | 22.0 | | | 188.6 | 188.5 | -3.29 | -3.45 | -3.28 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-2334 | 5/13/2026 7:45:00 AM | | | | | | 11000 | | | | | | Air Tech Lab; [User entered 1.1%] |
| CV-2334 | 5/13/2026 7:45:00 AM | | | | | 660 | | | | | | | Air Tech Lab |
| CV-2334 | 5/26/2026 2:23:32 PM | 7.2 | 92.8 | 0.0 | 0.0 | | | 127.6 | 127.2 | -1.36 | -1.68 | -1.14 | Valve Adjustment:Barely Open |
| CV-2337 | 5/6/2026 9:25:00 AM | | | | | | 122300 | | | | | | AtmAA; [User entered 12.23%] |
| CV-2337 | 5/6/2026 9:25:00 AM | | | | | 5500 | | | | | | | AtmAA |
| CV-2337 | 5/6/2026 9:26:13 AM | 18.7 | 81.3 | 0.0 | 0.0 | | | 149.3 | 149.9 | -2.47 | -2.48 | -3.11 | Valve Adjustment:High Temp,Valve 100% Open |
| CV-2337 | 5/11/2026 8:05:00 AM | | | | | | 130000 | | | | | | Air Tech Lab; [User entered 13%] |
| CV-2337 | 5/11/2026 8:05:00 AM | | | | | 3500 | | | | | | | Air Tech Lab |
| CV-2337 | 5/11/2026 2:00:37 PM | 33.1 | 66.9 | 0.0 | 0.0 | | | 149.0 | 149.4 | -0.74 | -0.82 | 6.97 | Valve Adjustment:No Flow Measurement,High Temp,Reduce Sys. Vac. - Flare Down |

# Table 2. Monthly LEA Selected Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | Init Temp [°R] | Adj Temp [°R] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Sys Pressure ["H2O] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CV-2337 | 5/20/2026 8:23:36 AM | 18.5 | 80.9 | 0.0 | 0.6 | | | 150.2 | 150.2 | -3.45 | -3.45 | 0.25 | Valve Adjustment:High Temp |
| CV-2341 | 5/11/2026 7:50:00 AM | | | | | | 94000 | | | | | | Air Tech Lab; [User entered 9.4%] |
| CV-2341 | 5/11/2026 7:50:00 AM | | | | | 850 | | | | | | | Air Tech Lab |
| CV-2341 | 5/14/2026 1:47:09 PM | 8.8 | 69.3 | 1.1 | 20.8 | | | 92.2 | 92.1 | -0.94 | -0.93 | -5.13 | Valve Adjustment:Audible Flow |
| CV-2341 | 5/29/2026 10:30:39 AM | 9.1 | 67.8 | 1.3 | 21.8 | | | 86.6 | 86.4 | -1.16 | -1.13 | -6.04 | Comments:,,,,,,, |
| CV-2344 | 5/6/2026 9:50:00 AM | | | | | | 139400 | | | | | | AtmAA; [User entered 13.94%] |
| CV-2344 | 5/6/2026 9:50:00 AM | | | | | 4020 | | | | | | | AtmAA |
| CV-2344 | 5/6/2026 9:52:20 AM | 10.9 | 84.8 | 0.5 | 3.8 | | | 157.7 | 157.4 | -8.39 | -8.35 | 0.30 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2344 | 5/11/2026 7:35:00 AM | | | | | | 160000 | | | | | | Air Tech Lab; [User entered 16%] |
| CV-2344 | 5/11/2026 7:35:00 AM | | | | | 2900 | | | | | | | Air Tech Lab |
| CV-2344 | 5/13/2026 9:30:38 AM | 6.7 | 80.2 | 0.6 | 12.5 | | | 147.1 | 147.2 | -8.12 | -5.43 | -7.90 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-2344 | 5/13/2026 9:31:33 AM | 7.3 | 81.0 | 0.5 | 11.2 | | | 146.2 | 146.1 | -5.39 | -5.33 | -7.71 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2344 | 5/20/2026 8:51:25 AM | 12.2 | 77.4 | 0.6 | 9.8 | | | 141.7 | 141.9 | -6.82 | -6.73 | -7.55 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement |
| CV-2345 | 5/1/2026 10:19:42 AM | 14.6 | 78.8 | 0.1 | 6.5 | | | 137.8 | 138.2 | -0.71 | -0.68 | 0.50 | Valve Adjustment:NSPS/EG CAI,High Temp;Well Repairs:Sample Port |
| CV-2345 | 5/1/2026 10:20:11 AM | 14.2 | 79.3 | 0.1 | 6.4 | | | 138.1 | 138.4 | -0.71 | -0.71 | 0.36 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-2345 | 5/11/2026 7:30:00 AM | | | | | | 28000 | | | | | | Air Tech Lab; [User entered 2.8%] |
| CV-2345 | 5/11/2026 7:30:00 AM | | | | | 580 | | | | | | | Air Tech Lab |
| CV-2345 | 5/19/2026 2:15:18 PM | 12.4 | 83.4 | 0.0 | 4.2 | | | 143.3 | 143.5 | 0.40 | -0.05 | -4.66 | Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum |
| CV-2345 | 5/19/2026 2:17:28 PM | 14.6 | 77.6 | 0.0 | 7.8 | | | 142.7 | 142.7 | -0.14 | -0.12 | -4.50 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-2346 | 5/4/2026 1:27:19 PM | 3.8 | 76.4 | 0.0 | 19.9 | | | 179.5 | 179.2 | -2.10 | -2.04 | -5.67 | Valve Adjustment:NSPS/EG CAC,High Temp;Well Condition:Lorentz Pump Installed |
| CV-2346 | 5/4/2026 1:29:13 PM | 3.5 | 77.6 | 0.0 | 19.0 | | | 178.9 | 178.7 | -2.59 | -2.58 | -5.77 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed |
| CV-2346 | 5/6/2026 8:25:00 AM | | | | | | 130000 | | | | | | Air Tech Lab; [User entered 13%] |
| CV-2346 | 5/6/2026 8:25:00 AM | | | | | 2200 | | | | | | | Air Tech Lab |
| CV-2346 | 5/6/2026 9:45:00 AM | | | | | | 118500 | | | | | | AtmAA; [User entered 11.85%] |
| CV-2346 | 5/6/2026 9:45:00 AM | | | | | 3400 | | | | | | | AtmAA |
| CV-2346 | 5/6/2026 9:47:10 AM | 17.2 | 82.8 | 0.0 | 0.0 | | | 182.1 | 182.2 | -3.78 | -3.77 | -6.82 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2346 | 5/13/2026 9:20:50 AM | 10.9 | 84.3 | 0.0 | 4.8 | | | 182.1 | 182.1 | -1.84 | -1.95 | -7.41 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2346 | 5/20/2026 8:47:59 AM | 17.4 | 80.5 | 0.0 | 2.1 | | | 183.1 | 184.4 | -5.63 | -5.72 | -7.17 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2346 | 5/28/2026 9:28:07 AM | 1.3 | 78.6 | 0.9 | 19.2 | | | 187.1 | 186.9 | -8.63 | -8.69 | -9.37 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-2347 | 5/1/2026 10:09:08 AM | 10.7 | 68.3 | 0.1 | 20.9 | | | 116.7 | 116.7 | -2.15 | -2.07 | -6.86 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-2347 | 5/6/2026 8:20:00 AM | | | | | | 56000 | | | | | | Air Tech Lab; [User entered 5.6%] |
| CV-2347 | 5/6/2026 8:20:00 AM | | | | | 1100 | | | | | | | Air Tech Lab |
| CV-2347 | 5/20/2026 8:26:42 AM | 15.0 | 64.8 | 0.0 | 20.2 | | | 121.6 | 124.3 | -2.67 | -2.69 | -7.58 | Valve Comment:well needs lowering;Valve Adjustment:Audible Flow |
| CV-2348 | 5/6/2026 8:15:00 AM | | | | | | 27000 | | | | | | Air Tech Lab; [User entered 2.7%] |
| CV-2348 | 5/6/2026 8:15:00 AM | | | | | 460 | | | | | | | Air Tech Lab |
| CV-2348 | 5/13/2026 12:35:31 PM | 19.8 | 56.6 | 0.3 | 23.3 | | | 128.7 | 128.8 | -3.81 | -3.82 | -5.97 | Comments:,,,,,,, |
| CV-2348 | 5/20/2026 8:15:56 AM | 20.4 | 54.1 | 0.0 | 25.5 | | | 107.8 | 108.3 | -7.53 | -7.47 | 0.03 | Valve Comment:Well needs lowering;Valve Adjustment:Audible Flow,Surging Liquid in Header |
| CV-2349 | 5/5/2026 8:25:00 AM | | | | | | 150000 | | | | | | Air Tech Lab; [User entered 15%] |
| CV-2349 | 5/5/2026 8:25:00 AM | | | | | 2600 | | | | | | | Air Tech Lab |
| CV-2349 | 5/7/2026 11:15:00 AM | | | | | | 117000 | | | | | | AtmAA; [User entered 11.7%] |

# Table 2. Monthly LEA Selected Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | Init Well Temp [°F] | Adj Well Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Sys Pressure ["H2O] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CV-2349 | 5/7/2026 11:15:00 AM | | | | | 3350 | | | | | | | AtmAA |
| CV-2349 | 5/7/2026 11:15:19 AM | 5.4 | 87.4 | 0.0 | 7.2 | | | 148.3 | 147.8 | 0.27 | 0.59 | 0.33 | Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Increased Flow/Vacuum |
| CV-2349 | 5/7/2026 11:16:23 AM | 5.3 | 87.9 | 0.0 | 6.8 | | | 147.6 | 147.7 | 0.29 | 0.40 | 0.33 | Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down |
| CV-2349 | 5/13/2026 10:48:12 AM | 4.1 | 77.3 | 0.0 | 18.6 | | | 152.3 | 150.2 | -0.05 | -0.13 | 0.13 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header;Well Condition:Lorentz Pump Installed |
| CV-2349 | 5/20/2026 10:27:38 AM | 14.1 | 75.3 | 0.0 | 10.6 | | | 162.7 | 163.1 | -2.00 | -2.00 | -0.29 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp |
| CV-2349 | 5/28/2026 10:20:04 AM | 2.3 | 79.8 | 0.0 | 17.9 | | | 172.2 | 172.5 | -1.12 | -0.52 | -1.79 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-2350 | 5/11/2026 7:40:00 AM | | | | | | 170000 | | | | | | Air Tech Lab; [User entered 17%] |
| CV-2350 | 5/11/2026 7:40:00 AM | | | | | 3700 | | | | | | | Air Tech Lab |
| CV-2350 | 5/13/2026 12:56:01 PM | 4.7 | 77.8 | 0.0 | 17.5 | | | 121.4 | 116.6 | 8.91 | -3.00 | -3.98 | Comments:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,,, |
| CV-2350 | 5/13/2026 12:57:10 PM | 4.5 | 85.3 | 0.0 | 10.2 | | | 116.3 | 116.4 | -0.49 | -1.29 | -3.38 | Comments:,,,,,,, |
| CV-2350 | 5/20/2026 10:03:44 AM | 4.0 | 79.6 | 0.0 | 16.4 | | | 110.9 | 112.1 | -4.09 | -4.05 | -4.09 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-2351 | 5/1/2026 9:05:14 AM | 0.0 | 1.8 | 21.2 | 77.0 | | | 83.8 | 77.5 | -6.60 | -6.39 | -6.56 | Valve Adjustment:Valve 100% Closed,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:Valve stuck open |
| CV-2351 | 5/5/2026 7:50:00 AM | | | | | | 1600 | | | | | | Air Tech Lab; [User entered 0.16%] |
| CV-2351 | 5/5/2026 7:50:00 AM | | | | | 0 | | | | | | | Air Tech Lab |
| CV-2351 | 5/28/2026 9:24:00 AM | 2.8 | 0.1 | 21.2 | 75.9 | | | 62.3 | 65.4 | -6.82 | -6.66 | -6.76 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum |
| CV-2351 | 5/28/2026 9:25:03 AM | 2.8 | 0.1 | 21.1 | 76.0 | | | 68.1 | 77.5 | -6.12 | -6.08 | -5.97 | Valve Adjustment:NSPS/EG CAI,High O2 |
| CV-2352 | 5/1/2026 9:13:24 AM | 0.0 | 0.5 | 21.4 | 78.1 | | | 115.6 | 116.7 | -0.02 | -5.72 | -6.40 | Valve Adjustment:Increased Flow/Vacuum,Barely Open;Well Comment:Possible damaged valve |
| CV-2352 | 5/5/2026 8:00:00 AM | | | | | | 190000 | | | | | | Air Tech Lab; [User entered 19%] |
| CV-2352 | 5/5/2026 8:00:00 AM | | | | | 1100 | | | | | | | Air Tech Lab |
| CV-2352 | 5/28/2026 9:12:47 AM | 2.6 | 25.4 | 15.5 | 56.5 | | | 99.0 | 97.8 | -5.81 | -2.75 | -6.36 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum |
| CV-2352 | 5/28/2026 9:16:38 AM | 5.7 | 29.9 | 13.0 | 51.4 | | | 108.7 | 108.9 | -0.77 | -0.76 | -6.25 | Valve Adjustment:NSPS/EG CAI,High O2 |
| CV-2353-PLR | 5/12/2026 7:35:00 AM | | | | | | 210000 | | | | | | Air Tech Lab; [User entered 21%] |
| CV-2353-PLR | 5/12/2026 7:35:00 AM | | | | | 760 | | | | | | | Air Tech Lab |
| CV-2353-PLR | 5/14/2026 8:40:00 AM | | | | | 924 | | | | | | | AtmAA |
| CV-2353-PLR | 5/15/2026 8:27:25 AM | 2.6 | 77.8 | 0.0 | 19.6 | | | 147.9 | 149.2 | -7.01 | -6.99 | -6.87 | Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open |
| CV-2353-PLR | 5/15/2026 8:29:12 AM | 2.7 | 78.1 | 0.0 | 19.2 | | | 147.6 | 147.9 | -6.86 | -6.79 | -7.01 | Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open |
| CV-2353-PLR | 5/20/2026 9:13:10 AM | 25.8 | 66.6 | 1.1 | 6.5 | | | 129.5 | 131.4 | -5.82 | -5.04 | -5.65 | Valve Adjustment:No Flow Measurement,Decreased Flow/Vacuum |
| CV-2353-PLR | 5/20/2026 9:13:57 AM | 26.1 | 68.8 | 0.5 | 4.6 | | | 131.8 | 131.5 | -5.36 | -5.36 | -5.45 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement |
| CV-2354 | 5/5/2026 8:20:00 AM | | | | | | 170000 | | | | | | Air Tech Lab; [User entered 17%] |
| CV-2354 | 5/5/2026 8:20:00 AM | | | | | 2500 | | | | | | | Air Tech Lab |
| CV-2354 | 5/6/2026 10:50:00 AM | | | | | | 148000 | | | | | | AtmAA; [User entered 14.8%] |
| CV-2354 | 5/6/2026 10:50:00 AM | | | | | 3190 | | | | | | | AtmAA |
| CV-2354 | 5/6/2026 10:50:20 AM | 24.8 | 75.2 | 0.0 | 0.0 | | | 174.0 | 175.3 | -3.33 | -3.39 | 0.34 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-2354 | 5/13/2026 11:01:08 AM | 4.5 | 77.9 | 1.4 | 16.2 | | | 166.8 | 166.8 | -0.98 | -0.98 | -2.75 | Valve Adjustment:No Flow Measurement,High Temp,Barely Open |
| CV-2354 | 5/13/2026 11:03:49 AM | 4.8 | 81.5 | 0.4 | 13.3 | | | 166.6 | 167.4 | -1.06 | -1.11 | -2.62 | Valve Comment:LORENTZ pump started after last read so cleared some 02;Valve Adjustment:No Flow Measurement,High Temp |

# Table 2. Monthly LEA Selected Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | Init Well Temp [°R] | Adj Well Temp [°R] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Sys Pressure ["H2O] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CV-2354 | 5/20/2026 10:40:36 AM | 35.6 | 64.4 | 0.0 | 0.0 | | | 179.4 | 178.6 | 1.82 | 1.87 | 0.29 | Valve Comment:Header watered in;Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Header;Well Condition:Lorentz Pump Installed;Well Repairs:Surging |
| CV-2354 | 5/20/2026 10:42:07 AM | 35.4 | 64.6 | 0.0 | 0.0 | | | 179.6 | 180.2 | 1.88 | 1.91 | -0.10 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header;Well Condition:Lorentz Pump Installed;Well Repairs:Surging |
| CV-2354 | 5/28/2026 10:36:46 AM | 4.2 | 78.4 | 0.0 | 17.4 | | | 183.8 | 183.9 | -0.52 | -0.52 | -2.81 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24002 | 5/1/2026 2:39:31 PM | 44.4 | 53.9 | 0.0 | 1.7 | | | 92.4 | 93.2 | -0.06 | -0.01 | 0.28 | Well Comment:no system port |
| CV-24002 | 5/19/2026 9:51:18 AM | 47.3 | 51.9 | 0.0 | 0.8 | | | 87.8 | 88.6 | 0.11 | -0.04 | -5.90 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open |
| CV-24002 | 5/19/2026 9:53:36 AM | 45.8 | 53.6 | 0.0 | 0.6 | | | 89.2 | 89.1 | -0.13 | -0.15 | -5.87 | Valve Adjustment:NSPS/EG CAC,Barely Open;Well Comment:Sample port installed |
| CV-24003 | 5/1/2026 2:37:02 PM | 39.9 | 57.4 | 0.0 | 2.7 | | | 101.6 | 101.6 | -0.76 | -0.63 | -6.86 | |
| CV-24003 | 5/19/2026 9:12:06 AM | 45.8 | 52.7 | 0.0 | 1.5 | | | 107.1 | 101.3 | -0.41 | -0.43 | -5.97 | Valve Adjustment:Barely Open;Well Repairs:Valve |
| CV-24007 | 5/12/2026 8:40:00 AM | | | | | | 170000 | | | | | | Air Tech Lab; [User entered 17%] |
| CV-24007 | 5/12/2026 8:40:00 AM | | | | | 1800 | | | | | | | Air Tech Lab |
| CV-24007 | 5/15/2026 9:09:54 AM | 5.6 | 77.6 | 0.0 | 16.8 | | | 132.2 | 132.4 | 0.04 | -0.02 | -0.36 | Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum,Surging Liquid in Header |
| CV-24007 | 5/15/2026 9:10:41 AM | 4.8 | 66.5 | 0.0 | 28.7 | | | 138.6 | 138.7 | -0.12 | -0.14 | -0.21 | Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header |
| CV-24007 | 5/19/2026 10:45:21 AM | 19.9 | 70.8 | 0.0 | 9.3 | | | 150.9 | 150.7 | -0.31 | -0.18 | -3.87 | Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Increased Flow/Vacuum |
| CV-24007 | 5/19/2026 10:46:37 AM | 18.2 | 71.0 | 0.0 | 10.8 | | | 150.9 | 150.7 | -0.16 | -0.16 | -3.26 | Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Barely Open |
| CV-24007 | 5/26/2026 1:55:46 PM | 28.1 | 71.9 | 0.0 | 0.0 | | | 150.2 | 150.9 | -0.79 | -1.05 | 1.01 | Valve Adjustment:High Temp,Increased Flow/Vacuum |
| CV-24007 | 5/26/2026 1:56:22 PM | 33.7 | 66.3 | 0.0 | 0.0 | | | 150.7 | 150.8 | -1.44 | -1.44 | 0.88 | Valve Adjustment:High Temp |
| CV-24007 | 5/29/2026 9:33:56 AM | 27.8 | 66.3 | 0.0 | 5.9 | | | 148.0 | 148.2 | -1.32 | -1.34 | -6.72 | Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum |
| CV-24017 | 5/5/2026 1:19:34 PM | 10.8 | 78.7 | 0.6 | 9.9 | | | 159.0 | 159.6 | -3.14 | -3.12 | 0.00 | Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open |
| CV-24017 | 5/5/2026 1:20:00 PM | | | | | | 155500 | | | | | | AtmAA; [User entered 15.55%] |
| CV-24017 | 5/5/2026 1:20:00 PM | | | | | 2760 | | | | | | | AtmAA |
| CV-24017 | 5/12/2026 8:35:00 AM | | | | | | 190000 | | | | | | Air Tech Lab; [User entered 19%] |
| CV-24017 | 5/12/2026 8:35:00 AM | | | | | 2100 | | | | | | | Air Tech Lab |
| CV-24017 | 5/12/2026 2:10:00 PM | | | | | 1230 | | | | | | | AtmAA |
| CV-24017 | 5/12/2026 2:25:14 PM | 18.0 | 72.7 | 0.6 | 8.7 | | | 181.0 | 180.5 | -4.81 | -1.21 | -0.05 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-24017 | 5/12/2026 2:47:32 PM | 25.5 | 74.5 | 0.0 | 0.0 | | | 172.2 | 174.6 | -2.11 | -2.05 | 0.00 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header |
| CV-24017 | 5/18/2026 2:35:18 PM | 25.5 | 74.5 | 0.0 | 0.0 | | | 171.6 | 170.6 | -2.24 | -2.10 | 0.34 | Valve Adjustment:No Flow Measurement,High Temp;Well Repairs:Surging |
| CV-24017 | 5/18/2026 2:40:00 PM | | | | | 2520 | | | | | | | AtmAA |
| CV-24017 | 5/26/2026 2:07:20 PM | 17.6 | 76.3 | 0.8 | 5.3 | | | 172.4 | 172.6 | -7.16 | -5.22 | 0.21 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-24017 | 5/26/2026 2:08:15 PM | 19.6 | 76.0 | 0.6 | 3.8 | | | 170.4 | 171.5 | -3.75 | -3.69 | 0.21 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24049 | 5/4/2026 2:36:19 PM | 2.0 | 88.0 | 0.0 | 10.0 | | | 188.6 | 189.2 | -4.01 | -3.94 | -10.48 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24049 | 5/4/2026 2:40:00 PM | | | | | | 25900 | | | | | | AtmAA; [User entered 2.59%] |
| CV-24049 | 5/4/2026 2:40:00 PM | | | | | 705 | | | | | | | AtmAA |
| CV-24049 | 5/11/2026 8:47:07 AM | 2.8 | 83.6 | 0.0 | 13.6 | | | 186.2 | 186.6 | 3.00 | -0.64 | -0.87 | Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum,Valve 100% Open |

# Table 2. Monthly LEA Selected Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | Init Temp [°F] | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Sys Pressure ["H2O] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CV-24049 | 5/11/2026 8:49:25 AM | 2.9 | 84.8 | 0.0 | 12.3 | | | 186.0 | 185.0 | -1.84 | -1.69 | -0.36 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Valve 100% Open |
| CV-24049 | 5/13/2026 8:10:00 AM | | | | | | 160000 | | | | | | Air Tech Lab; [User entered 16%] |
| CV-24049 | 5/13/2026 8:10:00 AM | | | | | 2800 | | | | | | | Air Tech Lab |
| CV-24049 | 5/18/2026 10:30:56 AM | 18.5 | 77.4 | 0.0 | 4.1 | | | 179.6 | 180.2 | -4.87 | -4.90 | -4.97 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24049 | 5/18/2026 10:35:00 AM | | | | | 3260 | | | | | | | AtmAA |
| CV-24049 | 5/26/2026 10:43:34 AM | 4.4 | 78.6 | 0.0 | 17.0 | | | 179.9 | 179.2 | -11.36 | -5.97 | -11.24 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-24049 | 5/26/2026 10:45:00 AM | 3.5 | 81.4 | 0.0 | 15.1 | | | 179.0 | 179.6 | -5.95 | -5.74 | -11.49 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24053 | 5/7/2026 8:40:00 AM | | | | | | 5300 | | | | | | Air Tech Lab; [User entered 0.53%] |
| CV-24053 | 5/7/2026 8:40:00 AM | | | | | 88 | | | | | | | Air Tech Lab |
| CV-24053 | 5/8/2026 8:18:44 AM | 39.3 | 43.1 | 2.5 | 15.1 | | | 75.4 | 75.5 | -3.03 | -3.04 | -3.36 | Comments:No Flow Measurement,,,,,,, |
| CV-24053 | 5/20/2026 2:23:25 PM | 50.4 | 48.4 | 0.0 | 1.2 | | | 100.2 | 100.5 | -4.32 | -4.99 | -4.39 | Valve Adjustment:Valve 100% Open |
| CV-24055 | 5/12/2026 1:47:04 PM | 9.0 | 65.6 | 2.2 | 23.2 | | | 136.9 | 137.9 | -0.52 | -0.62 | -11.04 | Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed |
| CV-24055 | 5/12/2026 1:49:20 PM | 9.1 | 62.3 | 1.6 | 27.0 | | | 137.8 | 137.3 | -0.58 | -0.57 | -9.05 | Valve Adjustment:Surging Liquid in Header |
| CV-24055 | 5/13/2026 8:15:00 AM | | | | | | 51000 | | | | | | Air Tech Lab; [User entered 5.1%] |
| CV-24055 | 5/13/2026 8:15:00 AM | | | | | 930 | | | | | | | Air Tech Lab |
| CV-24055 | 5/26/2026 9:27:16 AM | 14.3 | 66.2 | 1.1 | 18.4 | | | 137.4 | 137.2 | -0.44 | -0.34 | -8.47 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down |
| CV-24055 | 5/26/2026 9:28:17 AM | 14.4 | 66.0 | 1.1 | 18.5 | | | 137.4 | 136.8 | -0.35 | -0.35 | -7.59 | Valve Adjustment:NSPS/EG CAI,High Temp,Reduce Sys. Vac. - Flare Down |
| CV-24062 | 5/4/2026 1:15:00 PM | | | | | | 56100 | | | | | | AtmAA; [User entered 5.61%] |
| CV-24062 | 5/4/2026 1:15:00 PM | | | | | 1080 | | | | | | | AtmAA |
| CV-24062 | 5/4/2026 1:16:07 PM | 28.3 | 66.3 | 0.0 | 5.4 | | | 145.5 | 148.7 | -6.22 | -6.38 | -10.23 | Valve Adjustment:High Temp |
| CV-24062 | 5/7/2026 8:17:00 AM | | | | | | 80000 | | | | | | Air Tech Lab; [User entered 8.0%] |
| CV-24062 | 5/7/2026 8:17:00 AM | | | | | 890 | | | | | | | Air Tech Lab |
| CV-24062 | 5/8/2026 1:05:26 PM | 28.8 | 63.9 | 0.0 | 7.3 | | | 133.9 | 134.2 | -2.10 | -2.02 | -6.46 | Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| CV-24062 | 5/22/2026 11:08:48 AM | 28.1 | 59.3 | 1.3 | 11.3 | | | 140.5 | 140.3 | -3.49 | -3.46 | -8.26 | Comments:NSPS/EG CAI,High Temp,,,,,, |
| CV-24062 | 5/22/2026 11:10:33 AM | 29.1 | 63.7 | 0.4 | 6.8 | | | 144.9 | 143.7 | -1.88 | -1.78 | -8.22 | Comments:High Temp,NSPS/EG CAI,,,,,, |
| CV-24063 | 5/4/2026 1:33:24 PM | 3.7 | 84.4 | 0.6 | 11.3 | | | 182.4 | 181.7 | -7.10 | -3.43 | -11.01 | Valve Adjustment:High Temp,Decreased Flow/Vacuum |
| CV-24063 | 5/4/2026 1:34:44 PM | 3.7 | 86.5 | 0.0 | 9.8 | | | 183.9 | 182.5 | -3.44 | -3.34 | -11.05 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24063 | 5/4/2026 1:35:00 PM | | | | | | 71600 | | | | | | AtmAA; [User entered 7.16%] |
| CV-24063 | 5/4/2026 1:35:00 PM | | | | | 2470 | | | | | | | AtmAA |
| CV-24063 | 5/12/2026 8:20:00 AM | | | | | | 120000 | | | | | | Air Tech Lab; [User entered 12%] |
| CV-24063 | 5/12/2026 8:20:00 AM | | | | | 2400 | | | | | | | Air Tech Lab |
| CV-24063 | 5/14/2026 11:00:00 AM | | | | | 3230 | | | | | | | AtmAA |
| CV-24063 | 5/14/2026 11:01:37 AM | 10.7 | 83.6 | 0.0 | 5.7 | | | 174.9 | 173.4 | 0.65 | -3.17 | 0.34 | Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum |
| CV-24063 | 5/14/2026 11:02:15 AM | 11.4 | 83.8 | 0.0 | 4.8 | | | 172.8 | 171.9 | -3.36 | -3.31 | -8.44 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24063 | 5/20/2026 2:20:53 PM | 5.1 | 80.1 | 0.0 | 14.8 | | | 171.8 | 173.7 | -2.92 | -2.92 | 0.00 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24063 | 5/28/2026 1:49:33 PM | 6.8 | 84.2 | 0.0 | 9.0 | | | 184.1 | 183.7 | -2.47 | -2.43 | -7.15 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24064 | 5/4/2026 9:09:33 AM | 2.9 | 78.6 | 0.0 | 18.5 | | | 191.9 | 191.8 | -11.35 | -10.47 | -12.85 | Valve Adjustment:High Temp,Valve 100% Open |
| CV-24064 | 5/4/2026 9:10:00 AM | | | | | | 111000 | | | | | | AtmAA; [User entered 11.1%] |
| CV-24064 | 5/4/2026 9:10:00 AM | | | | | 2680 | | | | | | | AtmAA |

# Table 2. Monthly LEA Selected Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | Init Well Temp [°F] | Adj Well Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Sys Pressure ["H2O] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CV-24064 | 5/11/2026 10:07:41 AM | 9.0 | 87.1 | 0.6 | 3.3 | | | 192.5 | 192.5 | -10.46 | -10.56 | -13.49 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24064 | 5/12/2026 8:15:00 AM | | | | | | 130000 | | | | | | Air Tech Lab; [User entered 13%] |
| CV-24064 | 5/19/2026 1:36:22 PM | 14.8 | 76.2 | 0.0 | 9.0 | | | 192.0 | 192.5 | -5.48 | -4.27 | -9.16 | Valve Comment:Active PLR observed;Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In) |
| CV-24064 | 5/19/2026 1:40:00 PM | | | | | 2470 | | | | | | | AtmAA |
| CV-24064 | 5/27/2026 1:55:09 PM | 3.2 | 80.3 | 0.0 | 16.5 | | | 191.7 | 192.0 | -6.74 | -6.78 | -6.68 | Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Well (Watered In) |
| CV-24064 | 5/28/2026 2:15:41 PM | 1.9 | 79.7 | 0.0 | 18.4 | | | 165.5 | 165.7 | -7.85 | -7.85 | -8.16 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24065-TP1 | 5/7/2026 8:35:00 AM | | | | | | 9800 | | | | | | Air Tech Lab; [User entered 0.98%] |
| CV-24065-TP1 | 5/7/2026 8:35:00 AM | | | | | 530 | | | | | | | Air Tech Lab |
| CV-24065-TP1 | 5/11/2026 1:07:25 PM | 21.6 | 73.3 | 0.0 | 5.1 | | | 100.0 | 100.2 | -0.10 | -0.03 | 0.48 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| CV-24065-TP1 | 5/12/2026 8:15:00 AM | | | | | 2000 | | | | | | | Air Tech Lab |
| CV-24065-TP1 | 5/22/2026 10:27:26 AM | 15.0 | 83.3 | 0.4 | 1.3 | | | 82.9 | 83.8 | -0.33 | -0.32 | -10.19 | Valve Adjustment:Barely Open |
| CV-24066 | 5/1/2026 10:40:05 AM | 23.9 | 49.4 | 0.0 | 26.7 | | | 116.8 | 117.5 | -1.19 | -1.18 | -8.39 | Valve Adjustment:Audible Flow;Well Condition:Good |
| CV-24066 | 5/11/2026 7:45:00 AM | | | | | | 32000 | | | | | | Air Tech Lab; [User entered 3.2%] |
| CV-24066 | 5/11/2026 7:45:00 AM | | | | | 390 | | | | | | | Air Tech Lab |
| CV-24066 | 5/19/2026 12:41:10 PM | 25.0 | 45.2 | 0.0 | 29.8 | | | 109.2 | 110.5 | -0.94 | -0.93 | -6.12 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-24069 | 5/4/2026 8:56:06 AM | 40.8 | 48.8 | 0.0 | 10.4 | | | 93.2 | 93.4 | -1.42 | -1.43 | 0.01 | Valve Comment:No system port;Valve Adjustment:Barely Open |
| CV-24069 | 5/13/2026 8:20:00 AM | | | | | | 40000 | | | | | | Air Tech Lab; [User entered 4.0%] |
| CV-24069 | 5/13/2026 8:20:00 AM | | | | | 470 | | | | | | | Air Tech Lab |
| CV-24069 | 5/28/2026 9:30:09 AM | 35.8 | 42.0 | 0.3 | 21.9 | | | 96.1 | 96.2 | -2.80 | -2.08 | -9.63 | Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum;Well Comment:Needs silicone for lorentz fittings;Well Condition:Lorentz Pump Installed;Well Repairs:Sample Port |
| CV-24069 | 5/28/2026 9:35:46 AM | 31.9 | 43.5 | 0.4 | 24.2 | | | 94.5 | 93.7 | -1.98 | -1.68 | -8.97 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-24069 | 5/28/2026 9:36:45 AM | 31.0 | 44.0 | 0.3 | 24.7 | | | 93.4 | 93.4 | -1.66 | -1.65 | -9.09 | |
| CV-24070 | 5/4/2026 9:11:52 AM | 23.2 | 65.8 | 1.9 | 9.1 | | | 131.6 | 130.3 | -1.65 | -1.07 | -10.01 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum |
| CV-24070 | 5/4/2026 9:12:35 AM | 22.4 | 63.4 | 0.0 | 14.2 | | | 130.4 | 130.3 | -1.21 | -1.13 | -10.00 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed |
| CV-24070 | 5/7/2026 8:20:00 AM | | | | | | 110000 | | | | | | Air Tech Lab; [User entered 11%] |
| CV-24070 | 5/7/2026 8:20:00 AM | | | | | 1300 | | | | | | | Air Tech Lab |
| CV-24070 | 5/20/2026 2:33:43 PM | 10.2 | 74.7 | 0.0 | 15.1 | | | 133.9 | 135.6 | 0.95 | -0.10 | -3.46 | Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum,Decreased Flow/Vacuum |
| CV-24070 | 5/20/2026 2:34:29 PM | 10.7 | 77.6 | 0.0 | 11.7 | | | 136.2 | 136.1 | -0.13 | -0.15 | -3.49 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24070 | 5/20/2026 2:35:15 PM | 11.4 | 77.9 | 0.0 | 10.7 | | | 136.2 | 136.2 | -0.15 | -0.10 | -3.35 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24071 | 5/4/2026 9:43:04 AM | 43.3 | 55.1 | 0.0 | 1.6 | | | 121.6 | 121.4 | -5.57 | -5.24 | -9.94 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-24071 | 5/7/2026 8:10:00 AM | | | | | | 24000 | | | | | | Air Tech Lab; [User entered 2.4%] |
| CV-24071 | 5/7/2026 8:10:00 AM | | | | | 190 | | | | | | | Air Tech Lab |
| CV-24071 | 5/20/2026 1:35:21 PM | 42.5 | 52.0 | 0.0 | 5.5 | | | 123.3 | 123.2 | -3.74 | -3.33 | -6.65 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-24075-TP1 | 5/4/2026 9:20:00 AM | | | | | | 114700 | | | | | | AtmAA; [User entered 11.47%] |
| CV-24075-TP1 | 5/4/2026 9:20:00 AM | | | | | 2260 | | | | | | | AtmAA |
| CV-24075-TP1 | 5/4/2026 9:20:10 AM | 1.0 | 81.8 | 0.8 | 16.4 | | | 61.7 | 60.6 | -13.32 | -13.51 | 0.07 | Valve Comment:Updated photo on etools;Valve Adjustment:Audible Flow,High Temp |
| CV-24075-TP1 | 5/4/2026 9:21:41 AM | 1.0 | 82.0 | 0.8 | 16.2 | | | 187.2 | 187.2 | -13.08 | -13.16 | 0.04 | Valve Adjustment:No Flow Measurement,High Temp |

# Table 2. Monthly LEA Selected Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | Init Temp [°F] | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Sys Pressure ["H2O] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CV-24075-TP1 | 5/11/2026 10:25:13 AM | 10.2 | 84.1 | 0.8 | 4.9 | | | 109.5 | 99.5 | -11.66 | -11.98 | 0.04 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24075-TP1 | 5/29/2026 4:02:17 PM | 0.9 | 72.9 | 2.6 | 23.6 | | | 186.7 | 186.7 | -14.48 | -14.48 | -15.16 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24075-TP1 | 5/29/2026 4:03:35 PM | 1.0 | 76.4 | 2.8 | 19.8 | | | 186.8 | 187.0 | -13.96 | -14.01 | -14.15 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24077 | 5/1/2026 10:01:59 AM | 5.0 | 82.0 | 0.0 | 13.0 | | | 150.8 | 151.0 | -1.95 | -1.20 | -5.89 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum |
| CV-24077 | 5/1/2026 10:03:08 AM | 4.6 | 87.3 | 0.0 | 8.1 | | | 151.0 | 151.0 | -1.23 | -1.24 | -6.62 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24077 | 5/7/2026 10:50:00 AM | | | | | | 72200 | | | | | | AtmAA; [User entered 7.22%] |
| CV-24077 | 5/7/2026 10:50:00 AM | | | | | 2820 | | | | | | | AtmAA |
| CV-24077 | 5/7/2026 10:50:33 AM | 7.9 | 86.4 | 0.1 | 5.6 | | | 149.0 | 148.8 | -0.95 | -0.98 | -2.92 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24077 | 5/11/2026 1:38:12 PM | 18.6 | 77.2 | 0.0 | 4.2 | | | 146.5 | 146.1 | -2.00 | -2.00 | 5.79 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24077 | 5/20/2026 8:03:01 AM | 19.8 | 53.5 | 0.0 | 26.7 | | | 142.7 | 142.4 | -4.52 | -4.48 | -6.99 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24077 | 5/28/2026 9:16:41 AM | 12.2 | 59.5 | 0.0 | 28.3 | | | 143.6 | 144.5 | -4.76 | -4.77 | -9.14 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24077 | 5/28/2026 9:18:10 AM | 10.1 | 65.9 | 0.0 | 24.0 | | | 146.7 | 147.0 | -2.62 | -2.61 | -9.05 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24079-TP8 | 5/1/2026 11:22:12 AM | 18.3 | 65.8 | 0.0 | 15.9 | | | 156.5 | 154.7 | -0.62 | -0.25 | 0.66 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum |
| CV-24079-TP8 | 5/1/2026 11:22:57 AM | 18.3 | 70.1 | 0.0 | 11.6 | | | 152.4 | 152.4 | -0.16 | -0.16 | 0.68 | Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open;Well Comment:no system port;Well Repairs:Sample Port |
| CV-24079-TP8 | 5/7/2026 10:38:33 AM | 2.0 | 89.4 | 0.0 | 8.6 | | | 153.6 | 168.1 | 0.98 | -1.80 | 0.33 | Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum |
| CV-24079-TP8 | 5/7/2026 10:40:00 AM | | | | | | 111700 | | | | | | AtmAA; [User entered 11.17%] |
| CV-24079-TP8 | 5/7/2026 10:40:00 AM | | | | | 2450 | | | | | | | AtmAA |
| CV-24079-TP8 | 5/7/2026 10:41:06 AM | 2.3 | 87.0 | 0.0 | 10.7 | | | 170.5 | 172.6 | -1.59 | -1.63 | 0.33 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp |
| CV-24079-TP8 | 5/11/2026 1:15:47 PM | 52.0 | 48.0 | 0.0 | 0.0 | | | 140.1 | 141.7 | -5.34 | -5.34 | 0.02 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24079-TP8 | 5/26/2026 12:12:54 PM | 37.0 | 50.4 | 0.1 | 12.5 | | | 137.8 | 137.0 | -7.80 | -5.70 | -0.06 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down;Well Comment:no system port |
| CV-24079-TP8 | 5/26/2026 12:13:32 PM | 37.3 | 49.5 | 0.0 | 13.2 | | | 137.7 | 135.9 | -5.41 | -5.41 | -0.27 | Valve Adjustment:NSPS/EG CAI,High Temp,Reduce Sys. Vac. - Flare Down |
| CV-24082 | 5/4/2026 10:11:50 AM | 28.2 | 68.8 | 0.0 | 3.0 | | | 110.9 | 111.4 | -0.42 | -0.44 | -8.93 | Valve Adjustment:Barely Open |
| CV-24082 | 5/20/2026 11:24:26 AM | 30.9 | 69.1 | 0.0 | 0.0 | | | 124.3 | 124.4 | -0.20 | -0.13 | -6.11 | Valve Adjustment:Barely Open |
| CV-24083 | 5/4/2026 9:56:08 AM | 40.4 | 57.1 | 0.0 | 2.5 | | | 104.4 | 105.9 | 0.60 | -0.69 | -10.39 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed |
| CV-24083 | 5/4/2026 9:58:27 AM | 41.5 | 56.2 | 0.0 | 2.3 | | | 108.0 | 108.4 | -0.80 | -0.81 | -10.17 | Valve Adjustment:NSPS/EG CAC,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed |
| CV-24083 | 5/20/2026 1:53:17 PM | 42.6 | 55.2 | 0.0 | 2.2 | | | 126.8 | 125.0 | -0.17 | -0.17 | -6.95 | Valve Adjustment:Barely Open |
| CV-24084-TP1 | 5/4/2026 2:05:00 PM | | | | | | 77400 | | | | | | [User entered 7.74%] |
| CV-24084-TP1 | 5/4/2026 2:05:00 PM | | | | | 2420 | | | | | | | AtmAA |
| CV-24084-TP1 | 5/4/2026 2:08:40 PM | 3.7 | 91.0 | 0.0 | 5.3 | | | 180.6 | 180.8 | -1.49 | -1.39 | -8.12 | Valve Adjustment:Audible Flow,High Temp |
| CV-24084-TP1 | 5/11/2026 1:05:39 PM | 11.7 | 61.3 | 0.0 | 27.0 | | | 179.6 | 181.3 | -1.83 | -1.69 | -4.96 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24084-TP1 | 5/19/2026 10:24:00 AM | 18.9 | 81.1 | 0.0 | 0.0 | | | 180.6 | 180.9 | -3.47 | -3.40 | -6.08 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed |
| CV-24084-TP1 | 5/27/2026 10:49:57 AM | 2.9 | 76.5 | 0.0 | 20.6 | | | 180.2 | 180.7 | -2.12 | -2.36 | -5.06 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed |
| CV-24088 | 5/4/2026 1:51:55 PM | 38.8 | 59.1 | 0.0 | 2.1 | | | 100.0 | 100.1 | -2.03 | -1.98 | -7.61 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-24088 | 5/28/2026 9:04:04 AM | 41.7 | 53.9 | 0.0 | 4.4 | | | 99.1 | 99.2 | -1.94 | -1.94 | -8.79 | |
| CV-24095 | 5/6/2026 8:05:00 AM | | | | | | 160000 | | | | | | Air Tech Lab; [User entered 16%] |

# Table 2. Monthly LEA Selected Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | Init Well Temp [ °F ] | Adj Well Temp [ °F ] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Sys Pressure ["H2O] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CV-24095 | 5/6/2026 8:05:00 AM | | | | | 2800 | | | | | | | Air Tech Lab |
| CV-24095 | 5/6/2026 10:45:00 AM | | | | | | 108400 | | | | | | AtmAA; [User entered 10.84%] |
| CV-24095 | 5/6/2026 10:45:00 AM | | | | | 2700 | | | | | | | AtmAA |
| CV-24095 | 5/6/2026 10:46:15 AM | 19.2 | 80.8 | 0.0 | 0.0 | | | 176.2 | 176.2 | -1.28 | -1.30 | 0.34 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header |
| CV-24095 | 5/13/2026 10:53:04 AM | 3.2 | 82.3 | 0.0 | 14.5 | | | 177.8 | 177.9 | 0.91 | 1.66 | 0.65 | Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Positive Static Press.,Surging Liquid in Header |
| CV-24095 | 5/13/2026 10:56:02 AM | 2.2 | 71.8 | 2.8 | 23.2 | | | 178.3 | 178.3 | 0.59 | 0.95 | 0.62 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header;Well Condition:Lorentz Pump Installed |
| CV-24095 | 5/14/2026 1:28:11 PM | 3.5 | 81.5 | 0.0 | 15.0 | | | 178.8 | 178.7 | 1.35 | 0.75 | 0.24 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Header |
| CV-24095 | 5/20/2026 10:30:33 AM | 27.6 | 72.4 | 0.0 | 0.0 | | | 178.6 | 178.7 | -2.17 | -2.41 | -4.22 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24095 | 5/28/2026 10:30:18 AM | 2.3 | 83.9 | 0.3 | 13.5 | | | 179.6 | 179.3 | 0.50 | 0.47 | -0.54 | Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press. |
| CV-24095 | 5/28/2026 10:32:51 AM | 2.9 | 83.5 | 0.0 | 13.6 | | | 179.1 | 179.1 | 0.32 | 0.14 | 0.16 | Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Surging Liquid in Header |
| CV-24096 | 5/12/2026 9:22:51 AM | 23.5 | 34.9 | 8.4 | 33.2 | | | 74.1 | 81.8 | -2.99 | -1.86 | -3.62 | Comments:NSPS/EG CAI,High O2,,,,,, |
| CV-24096 | 5/12/2026 9:25:00 AM | 25.3 | 37.4 | 7.2 | 30.1 | | | 82.9 | 81.9 | -2.06 | -2.02 | -3.71 | Comments:NSPS/EG CAI,High O2,,,,,, |
| CV-24096 | 5/20/2026 10:19:24 AM | 37.6 | 55.4 | 0.3 | 6.7 | | | 95.9 | 98.5 | -2.34 | -1.97 | -3.33 | Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum |
| CV-24097 | 5/12/2026 9:13:02 AM | 48.0 | 51.4 | 0.0 | 0.6 | | | 78.9 | 87.4 | 0.02 | -0.04 | -5.38 | Comments:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 to 1 Turn,,,, |
| CV-24097 | 5/12/2026 9:16:39 AM | 44.2 | 50.8 | 0.4 | 4.6 | | | 81.1 | 81.2 | -0.10 | -0.10 | -5.64 | Comments:NSPS/EG CAC,No Adjustment Made,,,,,, |
| CV-24097 | 5/20/2026 10:28:10 AM | 42.7 | 45.7 | 2.3 | 9.3 | | | 88.4 | 91.2 | -3.87 | -1.12 | -4.95 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-24097 | 5/20/2026 10:29:27 AM | 46.8 | 46.8 | 1.3 | 5.1 | | | 86.7 | 86.8 | -1.19 | -1.19 | -4.94 | Valve Adjustment:Barely Open |
| CV-24098 | 5/1/2026 10:01:03 AM | 42.9 | 39.3 | 3.2 | 14.6 | | | 92.6 | 93.8 | -4.22 | -4.01 | -4.30 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header;Well Comment:valve stuck open |
| CV-24098 | 5/3/2026 11:00:24 AM | 48.8 | 41.9 | 0.8 | 8.5 | | | 69.0 | 69.7 | -7.60 | -7.39 | -7.81 | Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header;Well Comment:pump fitting needs silicone to cover hole;Well Condition:Pnumatic Pump Installed |
| CV-24098 | 5/3/2026 11:01:16 AM | 48.9 | 43.0 | 0.4 | 7.8 | | | 70.4 | 70.5 | -6.65 | -6.20 | -6.53 | Valve Adjustment:Surging Liquid in Header;Well Condition:Pnumatic Pump Installed |
| CV-24098 | 5/20/2026 10:43:25 AM | 42.4 | 38.2 | 4.4 | 15.0 | | | 95.4 | 95.9 | -4.18 | -4.01 | -3.80 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-24099 | 5/1/2026 10:08:04 AM | 9.4 | 35.2 | 8.1 | 47.3 | | | 83.2 | 83.2 | -4.81 | -4.58 | -4.91 | Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:valve stuck open |
| CV-24099 | 5/3/2026 10:27:26 AM | 11.8 | 76.1 | 0.0 | 12.1 | | | 61.8 | 61.4 | -0.01 | -1.06 | -7.32 | Valve Adjustment:NSPS/EG CAC,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed |
| CV-24099 | 5/3/2026 10:28:19 AM | 11.4 | 75.4 | 0.0 | 13.2 | | | 61.2 | 61.4 | -0.90 | -1.00 | -7.63 | Valve Adjustment:Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed |
| CV-24099 | 5/3/2026 10:28:51 AM | 12.3 | 75.2 | 0.0 | 12.5 | | | 61.5 | 61.5 | -1.09 | -1.03 | -6.43 | Well Condition:Lorentz Pump Installed |
| CV-24099 | 5/20/2026 10:48:09 AM | 24.4 | 66.0 | 0.0 | 9.6 | | | 97.5 | 97.6 | -0.54 | -0.48 | -3.60 | |
| CV-24100 | 5/1/2026 10:25:18 AM | 19.0 | 80.8 | 0.1 | 0.1 | | | 143.7 | 147.6 | -0.61 | -0.60 | -8.60 | Valve Adjustment:High Temp,Barely Open |
| CV-24100 | 5/7/2026 11:04:29 AM | 25.0 | 75.0 | 0.0 | 0.0 | | | 144.3 | 146.0 | 2.22 | -2.88 | -3.06 | Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum |
| CV-24100 | 5/7/2026 11:05:00 AM | | | | | | 8500 | | | | | | AtmAA; [User entered 0.85%] |
| CV-24100 | 5/7/2026 11:05:00 AM | | | | | 228 | | | | | | | AtmAA |
| CV-24100 | 5/7/2026 11:06:06 AM | 25.4 | 74.4 | 0.2 | 0.0 | | | 146.0 | 146.9 | -3.18 | -3.18 | -3.06 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp |
| CV-24100 | 5/13/2026 8:25:00 AM | | | | | | 8800 | | | | | | Air Tech Lab; [User entered 0.88%] |
| CV-24100 | 5/13/2026 8:25:00 AM | | | | | 83 | | | | | | | Air Tech Lab |

# Table 2. Monthly LEA Selected Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | Init Well Temp [°F] | Adj Well Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Sys Pressure ["H2O] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CV-24100 | 5/13/2026 10:41:16 AM | 21.9 | 77.3 | 0.2 | 0.6 | | | 143.4 | 141.9 | -7.76 | -2.95 | -7.76 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-24100 | 5/13/2026 10:42:49 AM | 21.8 | 78.0 | 0.1 | 0.1 | | | 143.5 | 143.8 | -2.64 | -2.64 | -7.80 | Valve Adjustment:No Flow Measurement;Well Condition:Lorentz Pump Installed |
| CV-24100 | 5/20/2026 9:36:36 AM | 21.3 | 73.8 | 0.0 | 4.9 | | | 150.8 | 150.9 | -1.42 | -0.31 | -7.43 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header |
| CV-24100 | 5/20/2026 9:37:52 AM | 21.4 | 75.4 | 0.0 | 3.2 | | | 151.2 | 151.5 | -0.21 | -0.23 | -7.51 | Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header |
| CV-24100 | 5/20/2026 10:00:42 AM | 46.9 | 53.1 | 0.0 | 0.0 | | | 149.8 | 150.4 | 0.10 | -2.39 | -6.84 | Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum |
| CV-24100 | 5/20/2026 10:01:19 AM | 46.0 | 54.0 | 0.0 | 0.0 | | | 150.0 | 149.5 | -2.99 | -2.99 | -6.69 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp |
| CV-24100 | 5/28/2026 10:02:06 AM | 21.1 | 74.5 | 0.0 | 4.4 | | | 147.5 | 148.5 | -0.47 | -0.51 | -4.78 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24101 | 5/1/2026 10:20:22 AM | 42.6 | 57.1 | 0.3 | 0.0 | | | 106.9 | | -7.56 | | -7.94 | Valve Adjustment:Valve 100% Open |
| CV-24101 | 5/6/2026 7:40:00 AM | | | | | | 940 | | | | | | Air Tech Lab; [User entered 0.094%] |
| CV-24101 | 5/6/2026 7:40:00 AM | | | | | 0 | | | | | | | Air Tech Lab |
| CV-24101 | 5/12/2026 8:51:03 AM | 38.8 | 53.6 | 1.3 | 6.3 | | | 112.6 | 112.4 | -7.47 | -7.36 | -7.01 | Comments:No Flow Measurement,,,,,,, |
| CV-24101 | 5/20/2026 9:41:50 AM | 41.4 | 54.8 | 0.0 | 3.8 | | | 112.0 | 115.3 | -7.37 | -7.22 | -7.34 | Valve Adjustment:Decreased Flow/Vacuum |
| CV-24102 | 5/4/2026 9:42:22 AM | 46.9 | 48.6 | 0.0 | 4.5 | | | 89.0 | 89.0 | -0.59 | -0.59 | -8.51 | Valve Adjustment:Barely Open |
| CV-24102 | 5/19/2026 10:30:38 AM | 47.8 | 50.6 | 0.0 | 1.6 | | | 103.0 | 103.0 | -0.48 | -0.48 | -6.89 | |
| CV-24120 | 5/4/2026 8:00:00 AM | | | | | | 110000 | | | | | | Air Tech Lab; [User entered 11%] |
| CV-24120 | 5/11/2026 10:28:50 AM | 4.7 | 71.6 | 0.4 | 23.4 | | | 98.1 | 98.1 | -1.16 | -1.18 | -1.37 | Valve Adjustment:Reduce Sys. Vac. - Flare Down;Well Comment:Pump is off;Well Condition:Lorentz Pump Installed |
| CV-24120 | 5/26/2026 2:15:09 PM | 4.8 | 80.5 | 0.6 | 14.1 | | | 88.0 | 89.0 | -8.11 | -7.69 | -7.45 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| CV-24121 | 5/4/2026 7:55:00 AM | | | | | | 2700 | | | | | | Air Tech Lab; [User entered 0.27%] |
| CV-24121 | 5/11/2026 10:33:18 AM | 2.7 | 15.3 | 16.4 | 65.6 | | | 101.3 | 101.3 | -0.80 | -0.82 | -0.89 | Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Reduce Sys. Vac. - Flare Down |
| CV-24121 | 5/11/2026 10:33:56 AM | 2.8 | 15.0 | 16.1 | 66.2 | | | 101.4 | 101.4 | -1.05 | -0.86 | -1.27 | Valve Adjustment:High O2,Barely Open |
| CV-24121 | 5/26/2026 2:08:29 PM | 0.6 | 5.5 | 20.0 | 73.9 | | | 75.9 | 78.2 | -8.13 | -0.55 | -8.06 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open |
| CV-24122 | 5/4/2026 8:20:00 AM | | | | | | 9100 | | | | | | Air Tech Lab; [User entered 0.91%] |
| CV-24122 | 5/6/2026 10:31:06 AM | 42.7 | 42.2 | 3.2 | 11.9 | | | 84.9 | 85.9 | -2.43 | -2.92 | -0.81 | Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Surging Liquid in Header |
| CV-24122 | 5/29/2026 9:33:20 AM | 27.0 | 31.6 | 7.9 | 33.5 | | | 76.1 | 76.9 | -4.68 | -2.41 | -5.20 | Comments:NSPS/EG CAI,High O2,,,,,, |
| CV-24122 | 5/29/2026 9:40:41 AM | 35.0 | 40.3 | 4.3 | 20.4 | | | 81.1 | 81.5 | -2.22 | -2.27 | -4.97 | Comments:NSPS/EG CAC,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,,,,, |
| CV-24123 | 5/14/2026 10:53:53 AM | 30.9 | 69.1 | 0.0 | 0.0 | | | 116.7 | 117.1 | 0.40 | 0.33 | 0.34 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Valve 100% Open,Reduce Sys. Vac. - Flare Down |
| CV-24123 | 5/14/2026 10:54:34 AM | 32.0 | 67.3 | 0.0 | 0.7 | | | 117.2 | 117.3 | 0.18 | 0.18 | 0.29 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Valve 100% Open |
| CV-24123 | 5/15/2026 11:24:46 AM | 26.4 | 69.8 | 0.0 | 3.8 | | | 84.7 | 112.5 | 3.24 | -0.20 | -2.56 | Comments:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 to 1 Turn,, |
| CV-24123 | 5/15/2026 11:28:22 AM | 31.9 | 66.2 | 0.0 | 1.9 | | | 113.9 | 113.9 | -0.16 | -0.16 | -0.44 | Comments:,,,,,,, |
| CV-24123 | 5/28/2026 11:46:25 AM | 38.4 | 57.2 | 0.0 | 4.4 | | | 116.1 | 116.6 | 0.65 | 0.67 | 0.42 | Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Well (Watered In) |
| CV-24123 | 5/28/2026 11:46:50 AM | 37.2 | 57.7 | 0.0 | 5.1 | | | 116.6 | 116.7 | 0.63 | 0.60 | 0.47 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Well (Watered In) |
| CV-24125-TP2( | 5/13/2026 7:55:00 AM | | | | | | 1300 | | | | | | Air Tech Lab; [User entered 0.13%] |
| CV-24125-TP2( | 5/13/2026 7:55:00 AM | | | | | 30 | | | | | | | Air Tech Lab |
| CV-24125-TP2( | 5/26/2026 1:56:27 PM | 28.5 | 67.0 | 1.1 | 3.4 | | | 99.9 | 99.8 | -1.35 | -1.41 | -3.85 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |

# Table 2. Monthly LEA Selected Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | Init Temp [°F] | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Sys Pressure ["H2O] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CV-24126 | 5/4/2026 2:40:40 PM | 1.9 | 85.1 | 0.0 | 13.0 | | | 186.0 | 187.1 | -2.12 | -2.63 | -2.27 | Valve Adjustment:High Temp |
| CV-24126 | 5/4/2026 2:50:00 PM | | | | | | 135800 | | | | | | AtmAA; [User entered 13.58%] |
| CV-24126 | 5/4/2026 2:50:00 PM | | | | | 3200 | | | | | | | AtmAA |
| CV-24126 | 5/12/2026 10:28:41 AM | 20.1 | 79.9 | 0.0 | 0.0 | | | 188.0 | 188.4 | -2.83 | -2.62 | -2.72 | Valve Adjustment:High Temp |
| CV-24126 | 5/12/2026 10:30:00 AM | | | | | 2330 | | | | | | | AtmAA |
| CV-24126 | 5/18/2026 10:43:37 AM | 21.8 | 71.7 | 0.0 | 6.5 | | | 186.3 | 187.2 | 1.28 | 1.80 | 1.52 | Valve Adjustment:High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down |
| CV-24126 | 5/18/2026 10:44:28 AM | 14.0 | 77.0 | 0.0 | 9.0 | | | 186.7 | 186.3 | 1.42 | 1.36 | 1.78 | Valve Adjustment:High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down |
| CV-24126 | 5/18/2026 10:50:00 AM | | | | | 4310 | | | | | | | AtmAA |
| CV-24126 | 5/22/2026 12:28:40 PM | 1.3 | 75.6 | 0.0 | 23.1 | | | 188.3 | 188.5 | -0.20 | -0.22 | -1.11 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24126 | 5/22/2026 12:29:20 PM | 1.6 | 76.9 | 0.0 | 21.5 | | | 188.7 | 188.6 | -0.30 | -0.38 | -1.18 | Valve Adjustment:NSPS/EG CAI,High Temp |
| CV-24126 | 5/26/2026 10:58:38 AM | 4.1 | 73.0 | 0.0 | 22.9 | | | 186.7 | 187.1 | -2.02 | -1.91 | -2.13 | Valve Adjustment:High Temp |
| CV-24127 | 5/4/2026 8:15:00 AM | | | | | | 160000 | | | | | | Air Tech Lab; [User entered 16%] |
| CV-24127 | 5/7/2026 10:20:00 AM | | | | | | 152600 | | | | | | AtmAA; [User entered 15.26%] |
| CV-24127 | 5/7/2026 10:20:00 AM | | | | | 5180 | | | | | | | AtmAA |
| CV-24127 | 5/7/2026 10:21:43 AM | 2.7 | 82.2 | 0.0 | 15.1 | | | 141.6 | 141.1 | 5.40 | 2.26 | 0.32 | Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum,Valve 100% Open |
| CV-24127 | 5/7/2026 10:22:55 AM | 2.9 | 83.5 | 0.0 | 13.6 | | | 141.8 | 141.2 | 2.20 | 2.31 | 0.32 | Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open |
| CV-24128 | 5/8/2026 9:33:23 AM | 34.4 | 43.9 | 1.2 | 20.5 | | | 99.5 | 99.5 | -0.86 | -0.77 | -3.16 | Comments:Reduced System Vacuum,,,,,,, |
| CV-24128 | 5/13/2026 7:50:00 AM | | | | | | 11000 | | | | | | Air Tech Lab; [User entered 1.1%] |
| CV-24128 | 5/13/2026 7:50:00 AM | | | | | 210 | | | | | | | Air Tech Lab |
| CV-24128 | 5/26/2026 2:25:15 PM | 33.4 | 51.7 | 1.2 | 13.7 | | | 91.8 | 91.7 | -1.98 | -1.98 | -10.24 | Valve Adjustment:Barely Open |
| CV-24134-TP1 | 5/7/2026 1:14:04 PM | 22.6 | 74.7 | 0.0 | 2.7 | | | 150.0 | 149.5 | -0.65 | -0.62 | -0.30 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24134-TP1 | 5/7/2026 1:15:00 PM | | | | | 1220 | | | | | | | AtmAA |
| CV-24134-TP1 | 5/11/2026 2:29:03 PM | 18.3 | 65.8 | 0.0 | 15.9 | | | 146.2 | 146.4 | -4.14 | -1.81 | -5.22 | Comments:NSPS/EG CAI,High Temp,,,,,, |
| CV-24134-TP1 | 5/11/2026 2:33:48 PM | 16.6 | 73.9 | 0.0 | 9.5 | | | 146.9 | 146.9 | -1.74 | -1.76 | -5.30 | Comments:,,,,,,, |
| CV-24134-TP1 | 5/12/2026 10:32:12 AM | 36.7 | 63.3 | 0.0 | 0.0 | | | 150.1 | 150.8 | 0.95 | -2.25 | -4.10 | Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High O2,Increased Flow/Vacuum |
| CV-24134-TP1 | 5/12/2026 10:33:32 AM | 38.2 | 61.8 | 0.0 | 0.0 | | | 150.6 | 150.9 | -2.75 | -2.74 | -4.05 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp |
| CV-24134-TP1 | 5/12/2026 10:35:00 AM | | | | | 2470 | | | | | | | AtmAA |
| CV-24134-TP1 | 5/18/2026 10:39:38 AM | 33.1 | 64.1 | 0.0 | 2.8 | | | 151.5 | 151.6 | -0.11 | -0.08 | -1.01 | Valve Adjustment:No Flow Measurement,High Temp,Reduce Sys. Vac. - Flare Down |
| CV-24134-TP1 | 5/18/2026 10:45:00 AM | | | | | 3300 | | | | | | | AtmAA |
| CV-24134-TP1 | 5/26/2026 10:55:47 AM | 23.2 | 68.7 | 0.0 | 8.1 | | | 151.0 | 151.4 | -3.84 | -3.90 | -5.03 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24138 | 5/5/2026 8:15:00 AM | | | | | | 210000 | | | | | | Air Tech Lab; [User entered 21%] |
| CV-24138 | 5/5/2026 8:15:00 AM | | | | | 820 | | | | | | | Air Tech Lab |
| CV-24138 | 5/6/2026 10:58:19 AM | 17.2 | 74.8 | 0.0 | 8.0 | | | 158.7 | 160.2 | -3.80 | -3.60 | 0.32 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24138 | 5/6/2026 11:00:00 AM | | | | | | 171800 | | | | | | AtmAA; [User entered 17.18%] |
| CV-24138 | 5/6/2026 11:00:00 AM | | | | | 1010 | | | | | | | AtmAA |
| CV-24138 | 5/13/2026 1:14:42 PM | 2.4 | 68.4 | 0.0 | 29.2 | | | 131.5 | 131.6 | -0.58 | -0.38 | -0.52 | Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header;Well Condition:Pnumatic Pump Installed |
| CV-24138 | 5/28/2026 9:02:31 AM | 0.3 | 0.2 | 21.6 | 77.9 | | | 96.3 | 95.5 | -2.69 | -2.09 | -2.20 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum |
| CV-24138 | 5/28/2026 9:03:38 AM | 0.3 | 0.2 | 21.5 | 78.0 | | | 95.8 | 96.9 | -2.02 | -1.80 | -1.85 | Valve Adjustment:NSPS/EG CAI,High O2,Surging Liquid in Header |
| CV-24139 | 5/5/2026 8:10:00 AM | | | | | | 180000 | | | | | | Air Tech Lab; [User entered 18%] |

# Table 2. Monthly LEA Selected Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | Init Temp [°F] | Adj Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Sys Pressure ["H2O] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CV-24139 | 5/5/2026 8:10:00 AM | | | | | 630 | | | | | | | Air Tech Lab |
| CV-24139 | 5/15/2026 8:12:50 AM | 0.1 | 3.3 | 20.8 | 75.8 | | | 111.7 | 136.1 | 25.00 | -0.23 | -6.42 | Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Positive Static Press.,Increased Flow/Vacuum |
| CV-24139 | 5/15/2026 8:22:50 AM | 0.7 | 30.7 | 13.2 | 55.4 | | | 144.2 | 139.8 | -0.21 | -0.20 | -6.72 | Valve Adjustment:NSPS/EG CAI,High Temp,High O2;Well Comment:sensitive valve;Well Repairs:Valve |
| CV-24139 | 5/28/2026 9:08:34 AM | 4.1 | 58.6 | 4.7 | 32.6 | | | 127.4 | 125.5 | -6.44 | -6.10 | -6.76 | Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum |
| CV-24140 | 5/5/2026 8:05:00 AM | | | | | | 210000 | | | | | | Air Tech Lab; [User entered 21%] |
| CV-24140 | 5/5/2026 8:05:00 AM | | | | | 1000 | | | | | | | Air Tech Lab |
| CV-24140 | 5/6/2026 11:04:58 AM | 14.4 | 78.6 | 0.0 | 7.0 | | | 163.7 | 164.9 | -5.03 | -5.03 | -5.22 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24140 | 5/6/2026 11:05:00 AM | | | | | | 203000 | | | | | | AtmAA; [User entered 20.3%] |
| CV-24140 | 5/6/2026 11:05:00 AM | | | | | 1350 | | | | | | | AtmAA |
| CV-24140 | 5/13/2026 1:18:30 PM | 2.2 | 69.8 | 0.0 | 28.0 | | | 156.3 | 157.7 | -2.58 | -2.53 | -4.54 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24140 | 5/20/2026 1:26:41 PM | 3.6 | 73.1 | 0.3 | 23.0 | | | 146.3 | 148.5 | -3.62 | -2.56 | -3.60 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum |
| CV-24140 | 5/20/2026 1:28:20 PM | 5.1 | 71.3 | 0.2 | 23.4 | | | 148.6 | 148.4 | -2.42 | -2.47 | -3.40 | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24140 | 5/28/2026 10:50:34 AM | 1.9 | 75.0 | 0.0 | 23.1 | | | 168.4 | 170.8 | 5.74 | -1.38 | -4.68 | Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum |
| CV-24140 | 5/28/2026 10:52:29 AM | 1.9 | 72.1 | 0.4 | 25.6 | | | 171.1 | 170.8 | -1.75 | -1.97 | -5.22 | Valve Adjustment:High Temp |
| CV-24141 | 5/1/2026 8:57:18 AM | 20.8 | 33.2 | 5.1 | 40.9 | | | 79.1 | 76.3 | -0.08 | -0.95 | -6.86 | Valve Adjustment:Increased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down |
| CV-24141 | 5/5/2026 7:45:00 AM | | | | | | 1200 | | | | | | Air Tech Lab; [User entered 0.12%] |
| CV-24141 | 5/5/2026 7:45:00 AM | | | | | 94 | | | | | | | Air Tech Lab |
| CV-24141 | 5/28/2026 9:30:26 AM | 10.7 | 6.5 | 18.4 | 64.4 | | | 65.6 | 65.7 | -6.76 | -5.94 | -7.11 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum;Well Comment:no pump installed |
| CV-24141 | 5/28/2026 9:31:07 AM | 10.8 | 6.8 | 18.3 | 64.1 | | | 66.1 | 65.9 | -5.95 | -5.76 | -5.94 | Valve Adjustment:NSPS/EG CAI,High O2 |
| CV-24142 | 5/6/2026 8:10:00 AM | | | | | | 120000 | | | | | | Air Tech Lab; [User entered 12%] |
| CV-24142 | 5/6/2026 8:10:00 AM | | | | | 1500 | | | | | | | Air Tech Lab |
| CV-24142 | 5/14/2026 8:35:00 AM | | | | | 2300 | | | | | | | AtmAA |
| CV-24142 | 5/15/2026 7:59:13 AM | 0.0 | 1.3 | 21.7 | 77.0 | | | 174.3 | 174.0 | -4.10 | -4.10 | -4.96 | Valve Adjustment:NSPS/EG CAI,High Temp,Valve 100% Open,Surging Liquid in Header |
| CV-24142 | 5/15/2026 8:03:40 AM | 0.0 | 0.2 | 21.9 | 77.9 | | | 174.7 | 174.7 | -3.95 | -3.94 | -4.77 | Valve Adjustment:NSPS/EG CAI,High Temp,Valve 100% Open,Surging Liquid in Header |
| CV-24142 | 5/20/2026 1:02:37 PM | 3.8 | 58.4 | 2.6 | 35.2 | | | 153.3 | 151.5 | -3.36 | -2.50 | -3.07 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed |
| CV-24142 | 5/20/2026 1:14:55 PM | 2.6 | 59.0 | 3.6 | 34.8 | | | 152.3 | 151.1 | -2.68 | -2.87 | 0.00 | Valve Comment:Pneumatic pump not working;Valve Adjustment:No Flow Measurement,High Temp |
| CV-24142 | 5/28/2026 10:40:43 AM | 2.3 | 72.4 | 0.6 | 24.7 | | | 100.2 | 100.7 | -1.92 | -1.91 | -1.66 | Valve Adjustment:NSPS/EG CAI |
| CV-24142 | 5/28/2026 10:41:54 AM | 2.3 | 72.2 | 0.6 | 24.9 | | | 100.6 | 100.8 | -1.89 | -1.89 | -1.58 | |
| CV-24143 | 5/1/2026 2:15:01 PM | 0.7 | 23.9 | 14.4 | 61.0 | | | 95.5 | 97.6 | -4.24 | -2.26 | -4.36 | Comments:NSPS/EG CAI,High O2,,,,,, |
| CV-24143 | 5/1/2026 2:16:44 PM | 0.7 | 23.5 | 14.9 | 60.9 | | | 96.9 | 96.8 | -2.80 | -2.85 | -4.29 | Comments:,,,,,,, |
| CV-24143 | 5/5/2026 7:55:00 AM | | | | | | 61000 | | | | | | Air Tech Lab; [User entered 6.1%] |
| CV-24143 | 5/5/2026 7:55:00 AM | | | | | 460 | | | | | | | Air Tech Lab |
| CV-24143 | 5/28/2026 9:19:15 AM | 4.2 | 23.6 | 15.2 | 57.0 | | | 73.4 | 72.9 | -7.01 | -6.42 | -6.80 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum |
| CV-24143 | 5/28/2026 9:20:03 AM | 4.3 | 24.2 | 15.2 | 56.3 | | | 72.5 | 72.4 | -6.42 | -6.44 | -6.31 | Valve Adjustment:NSPS/EG CAI,High O2,Barely Open |
| CV-24144 | 5/12/2026 9:03:44 AM | 58.5 | 40.0 | 0.0 | 1.5 | | | 79.1 | 88.3 | -4.85 | -4.84 | -4.77 | Comments:Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,No Flow Measurement,,,,, |
| CV-24144 | 5/20/2026 10:35:16 AM | 56.8 | 40.5 | 0.0 | 2.7 | | | 103.0 | 100.3 | -4.49 | -4.52 | -4.27 | Valve Adjustment:Valve 100% Open |

# Table 2. Monthly LEA Selected Wells - May 2026
# Chiquita Canyon Landfill

| Point Name | Record Date | CH4 [%] | CO2 [%] | O2 [%] | Bal Gas [%] | CO Reading [ppmv] | H2 Reading [ppmv] | Init Well Temp [°F] | Adj Well Temp [°F] | Init Stat Press ["H2O] | Adj Stat Press ["H2O] | Sys Pressure ["H2O] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CV-99 | 5/4/2026 7:45:00 AM | | | | | | 2600 | | | | | | Air Tech Lab; [User entered 0.26%] |
| CV-99 | 5/26/2026 1:51:48 PM | 26.1 | 73.9 | 0.0 | 0.0 | | | 77.4 | 77.4 | -3.43 | -2.93 | -3.44 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| H-1770N | 5/1/2026 2:42:44 PM | 35.3 | 62.8 | 0.0 | 1.9 | | | 100.2 | 100.2 | -0.68 | -0.60 | -6.48 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| H-1770N | 5/4/2026 8:50:00 AM | | | | | | 12000 | | | | | | Air Tech Lab; [User entered 1.2%] |
| H-1770N | 5/19/2026 9:18:49 AM | 36.3 | 61.0 | 0.0 | 2.7 | | | 99.2 | 98.4 | -0.44 | -0.37 | -6.73 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open |
| H-2165W | 5/1/2026 10:16:24 AM | 10.9 | 86.4 | 0.0 | 2.7 | | | 118.0 | 117.5 | -0.09 | -0.05 | -8.60 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |
| H-2165W | 5/12/2026 7:45:00 AM | | | | | | 48000 | | | | | | Air Tech Lab; [User entered 4.8%] |
| H-2165W | 5/12/2026 7:45:00 AM | | | | | 720 | | | | | | | Air Tech Lab |
| H-2165W | 5/20/2026 9:46:57 AM | 12.9 | 79.8 | 0.0 | 7.3 | | | 119.8 | 120.0 | -0.68 | -0.55 | -7.28 | Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header |
| H-2273W | 5/12/2026 7:50:00 AM | | | | | | 5900 | | | | | | Air Tech Lab; [User entered 0.59%] |
| H-2273W | 5/12/2026 7:50:00 AM | | | | | 76 | | | | | | | Air Tech Lab |
| H-2273W | 5/13/2026 12:42:00 PM | 17.2 | 42.0 | 0.1 | 40.7 | | | 125.4 | 127.0 | -0.53 | -0.64 | -7.48 | Comments:Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,,,,,, |
| H-2273W | 5/20/2026 8:21:56 AM | 25.2 | 50.1 | 0.0 | 24.7 | | | 129.9 | 129.3 | -0.77 | -0.67 | -8.30 | Valve Adjustment:Audible Flow,Decreased Flow/Vacuum |

# Attachment B


# Down Well Temperatures


# And

# List of Wells for Monitoring


# LEA Selected Wells for Down Hole Temperature Monitoring
## April 2026


| Well Number | Down Well Temp Monitoring Monthly | Last Date Monitored for Downwell Temperatures - 2025 | 2026 Downwell Temperature Monitoring Date | Comments |
|---|---|---|---|---|
| CV-100 | NA | NA | NA | Abandoned Well |
| CV-103 | NA | 3/3/2025 | NA | Abandoned Well |
| CV-108-52 | Yes | 3/4/2025 | 3/2/2026 | |
| CV-113 | Yes | 3/10/2025 | 3/2/2026 | |
| CV-1532 | NA | NA | NA | Abandoned Well |
| CV-1532A | Yes | 3/10/2025 | 2/6/2026 and 3/25/2026 | |
| CV-1535 | Yes | 3/4/2025 | 3/2/2026 | |
| CV-1902A | Yes | 3/18/2025 | 2/6/2026 and 3/2/2026 | |
| CV-2001 | Yes | 3/4/2025 | 3/3/2026 | |
| CV-2002 | Yes | 6/2/2025 | 3/4/2026 | |
| CV-2007 | Yes | 3/5/2025 | 3/4/2026 | |
| CV-2202 | NA | NA | NA | Abandoned Well |
| CV-2301 | Yes | 3/11/2025 | 2/6/2026 and 3/5/2026 | Pump Offline |
| CV-2302 | Yes | 3/11/2025 | TBD - Pump Installed | Graph Attached 5-1 to 5-31-2026 |
| CV-2303 | Yes | 3/11/2025 | TBD - Pump Installed | Pump/Sensor Offline in May |
| CV-2312 | Yes | 3/5/2025 | TBD - Pump Installed | |
| CV-2315 | Yes | 3/19/2025 | TBD - Pump Installed | Graph Attached 5-1 to 5-31-2026 |
| CV-2341 | Yes | 3/5/2025 | TBD - Pump Installed | |
| CV-2350 | Yes | 3/12/2025 | TBD - Pump Installed | Pump/Sensor Offline in May |
| CV-2351 | Yes | 3/12/2025 | 3/10/2026 | Now a Pnuematic Pump no sensors |
| CV-2352 | Yes | 3/12/2025 | 4/24/2026 and 4/30/2026 | Now a Pnuematic Pump no sensors |
| CV-2353 | Yes | 5/30/2025 | 3/10/2026 and 4/30/2026 | |
| CV-24007 | Yes | 3/6/2025 | 3/10/2026 | |
| CV-24017 | Yes | 3/6/2025 | TBD - Pump Installed | Graph attached 5-1 to 5-31-2026 |
| CV-24053 | Yes | 3/6/2025 | TBD - Pump Installed | |
| CV-24065 | Yes | 3/6/2025 | TBD - Pump Installed | Graph Attached 5-1 to 5-31-2026 |
| CV-24095 | Yes | 3/7/2025 | TBD - Pump Installed | Graph Attached 5-1 to 5-31-2026 |
| CV-24101 | Yes | 3/7/2025 | TBD - Pump Installed | |
| CV-24122 | Yes | 3/7/2025 | 3/10/2026 | |
| CV-24127 | Yes | 3/7/2025 | 3/10/2027 | |
| CV-24138 | Yes | 4/1/2025 | TBD - Pump Installed | |
| CV-23139 | Yes | 8/18/2025 | TBD - Pump Installed | |
| CV-24143 | Yes | 3/10/2025 | TBD - Pump Installed | |
| TC-2385A | NA | NA | NA | Abandoned Well |



CV-2302
18 May 2026 10:25 (UTC -7)
Temp. Sensor [Analog 1]: 164.2 °F
May 2, 2026
May 4, 2026
May 6, 2026
May 8, 2026
May 10, 2026
May 12, 2026
May 14, 2026
May 16, 2026
May 18, 2026
May 20, 2026
May 22, 2026
May 24, 2026
May 26, 2026
May 28, 2026
May 30, 2026


15 May 2026 10:12 (UTC -7)
Lorentz Temp. Sensor [Analog 1]: 150.7 °F
May 2, 2026
May 4, 2026
May 6, 2026
May 8, 2026
May 10, 2026
May 12, 2026
May 14, 2026
May 16, 2026
May 18, 2026
May 20, 2026
May 22, 2026
May 24, 2026
May 26, 2026
May 28, 2026
May 30, 2026
June

CV-2315



13 May 2026 19:18 (UTC -7)
Temperature sensor [Analog 1]: 225.6 °F
CV-24017
May 2, 2026
May 4, 2026
May 6, 2026
May 8, 2026
May 10, 2026
May 12, 2026
May 14, 2026
May 16, 2026
May 18, 2026
May 20, 2026
May 22, 2026
May 24, 2026
May 26, 2026
May 28, 2026
May 30, 2026
June 1


17 May 2026 13:06 (UTC -7)
Lorentz Temp. Sensor [Analog 1]: 150.5 °F
CV-24065
May 2, 2026
May 4, 2026
May 6, 2026
May 8, 2026
May 10, 2026
May 12, 2026
May 14, 2026
May 16, 2026
May 18, 2026
May 20, 2026
May 22, 2026
May 24, 2026
May 26, 2026
May 28, 2026
May 30, 2026
June


12 May 2026 00:45 (UTC -7)
Lorentz Temp. Sensor [Analog 1]: 175.1 °F
CV-2495
May 2, 2026
May 4, 2026
May 6, 2026
May 8, 2026
May 10, 2026
May 12, 2026
May 14, 2026
May 16, 2026
May 18, 2026
May 20, 2026
May 22, 2026
May 24, 2026
May 26, 2026
May 28, 2026
May 30, 2026
June 1

Attachment C

Item 7 – Well Location Map




N

GRAPHIC SCALE

150 75 0 150 300 150

SCALE: 1"=150'

**LEGEND**

- 1150 — TOPOGRAPHIC CONTOUR
- EXISTING CELL LIMITS (APPROXIMATE)
- CV-XX — EXISTING VERTICAL LFG EXTRACTION WELL
- H-XX — EXISTING HORIZONTAL COLLECTOR
- EXISTING HORIZONTAL COLLECTOR PERFORATED PIPE
- REACTION AREA BOUNDARY (APPROXIMATE) - BASED ON DATA REVIEW
- REACTION AREA BOUNDARY - CONDITION 9A

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLOR. AERIAL PHOTOGRAPHY DATED JUNE 02, 2026.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.
3. THE LOCATION OF ANY EXISTING GCCS COMPONENTS AND OTHER FEATURES ARE APPROXIMATE AND SHOULD BE USED FOR INFORMATION PURPOSES ONLY.

DATE | REVISION | NO.

SHEET TITLE: EXISTING VERTICAL & HORIZONTAL LFG EXTRACTION WELL MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

**SCS ENGINEERS**
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544


PROJ. NO. 01204123.45 | DSN. BY: - | DWN. BY: RR | CHK. BY: - | ACAD FILE: FIELD SERVICES | APP. BY: -

DATE: 06/11/2026

SCALE: AS SHOWN

SHEET: 1

N:\CAD\ASBUILT – MASTERS\CHIQUITA\GCCS\2026 ACAD\2026 CCLF_Existing Well Map For LEA Response_2026-06-11.dwg Jun 15, 2026 5:04pm By: raulramirez




GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLOR. AERIAL PHOTOGRAPHY DATED MAY 06, 2026.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.
3. THE LOCATION OF ANY EXISTING PIPING, VALVES, TIE-IN LOCATIONS AND OTHER FEATURES ARE APPROXIMATE AND SHOULD BE USED FOR INFORMATION PURPOSES ONLY. ACTUAL FIELD CONDITIONS MAY VARY AND SUBJECT TO CHANGE BASED ON TOPOGRAPHIC FEATURES AND OTHER SITE-SPECIFIC FACTORS.
4. EXISTING GCCS AS-BUILT DATED JUNE 3, 2026.

DATE | REVISION | NO.

SHEET TITLE: EXISTING GCCS MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3711 LONG BEACH BLVD., THIRD FLOOR
LONG BEACH, CA 90807
PH. (562) 426-9544

PROJ. NO. - | DWN. BY: SRM | ACAD. FILE: N:\CAD\ASBUILT-MASTERS\CHIQUITA\GCCS\CCLF MASTER EXISTING GCCS MAP_2026-06-03.dwg
DSN. BY: - | CHK. BY: - | APP. BY: -

DATE: 06/03/2026


SCALE: AS SHOWN

1 of 1

N:\CAD\ASBUILT - MASTERS\CHIQUITA\GCCS\CCLF MASTER EXISTING GCCS MAP_2026-06-03.dwg Jun 03, 2026 - 2:01pm By: raulramirez

# Attachment D

# Milestone 5 Compliance Data




## Ranges Mapped

| | | | | | | # Points |
|---|---|---|---|---|---|---|
| | >= | 0 | and | < | 25 | 53 |
| | >= | 25 | and | < | 48 | 26 |
| | >= | 48 | and | < | 52 | 2 |
| | >= | 52 | and | < | 58 | 1 |
| | >= | 58 | and | < | 101 | |
| | | N/A | | | N/A | |

## Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

**Chiquita Canyon Landfill**


**Range Map**

**Parameter: CH4 (mid range)**

**Analysis Method: MostRecent**

Date Range: 05/01/2026 - 05/31/2026

Map generation date : 06/11/2026




## Ranges Mapped

| | | | | | | # Points |
|---|---|---|---|---|---|---|
| | >= | 0 | and | < | 25 | 5 |
| | >= | 25 | and | < | 45 | 5 |
| | >= | 45 | and | < | 55 | 16 |
| | >= | 55 | and | < | 65 | 7 |
| | >= | 65 | and | < | 101 | 49 |
| | | N/A | | | N/A | |

## Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

**Chiquita Canyon Landfill**


**Range Map**

**Parameter: CO2 (mid range)**

**Analysis Method: MostRecent**

Date Range: 05/01/2026 - 05/31/2026

Map generation date : 06/11/2026




## Ranges Mapped

| | | | | | | # Points |
|---|---|---|---|---|---|---|
| | >= | 0 | and | < | 0.5 | |
| | >= | 0.5 | and | < | 2 | |
| | >= | 2 | and | < | 3.5 | |
| | >= | 3.5 | and | < | 5 | |
| | >= | 5 | and | < | 101 | |
| | | N/A | | | N/A | |

## Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

**Chiquita Canyon Landfill**


**Range Map**

**Parameter: O2 (mid range)**

**Analysis Method: MostRecent**

Date Range: 05/01/2026 - 05/31/2026

Map generation date : 06/11/2026




## Ranges Mapped

| | | | | | | # Points |
|---|---|---|---|---|---|---|
| | >= | -50 | and | < | 131 | 46 |
| | >= | 131 | and | < | 150 | 12 |
| | >= | 150 | and | < | 165 | 4 |
| | >= | 165 | and | < | 180 | 11 |
| | >= | 180 | and | < | 999 | 9 |
| | | N/A | | | N/A | |

## Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

**Chiquita Canyon Landfill**


**Range Map**

**Parameter: Adj Temp (high range)**

**Analysis Method: MostRecent**

Date Range: 05/01/2026 - 05/31/2026

Map generation date : 06/11/2026




## Ranges Mapped

| | | | | | | # Points |
|---|---|---|---|---|---|---|
| | >= | 0 | and | < | 0.5 | 56 |
| | >= | 0.5 | and | < | 0.9 | 16 |
| | >= | 0.9 | and | < | 1.1 | 5 |
| | >= | 1.1 | and | < | 1.5 | 2 |
| | >= | 1.5 | and | < | 101 | 3 |
| | | N/A | | | N/A | |

## Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

**Chiquita Canyon Landfill**


**Range Map**

**Parameter: CH4/CO2 Ratio (high range)**

**Analysis Method: MostRecent**

Date Range: 05/01/2026 - 05/31/2026

Map generation date : 06/11/2026




## Ranges Mapped

| | | | | | | # Points |
|---|---|---|---|---|---|---|
| | >= | 0 | and | < | 500 | 18 |
| | >= | 500 | and | < | 1000 | 15 |
| | >= | 1000 | and | < | 1500 | 6 |
| | >= | 1500 | and | < | 2000 | 3 |
| | >= | 2000 | and | < | 10000 | 21 |

## Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

**Chiquita Canyon Landfill**


**Range Map**

**Parameter: CO LAB (mid range)**

**Analysis Method: MostRecent**

Date Range: 05/01/2026 - 05/31/2026

Map generation date : 06/11/2026




## Ranges Mapped

| | | | | | # Points |
|---|---|---|---|---|---|
| | >= 0 | and | < | 2000 | 4 |
| | >= 2000 | and | < | 5000 | 2 |
| | >= 5000 | and | < | 10000 | 6 |
| | >= 10000 | and | < | 50000 | 10 |
| | >= 50000 | and | < | 100000 | 14 |
| | >= 100000 | and | < | 150000 | 16 |
| | >= 150000 | and | < | 1000000 | 16 |

## Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

**Chiquita Canyon Landfill**


**Range Map**


**Parameter: H2 LAB (mid range)**

**Analysis Method: MostRecent**

Date Range: 05/01/2026 - 05/31/2026

Map generation date : 06/11/2026




Point ID / Name


CHIWCV99 / CV-99

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-99 / CV-99

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-99 / CV-99


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHWCV103 / CV-103

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name

CV-103 / CV-103

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-103 / CV-103


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV108-52 / CV-108-52

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-108-52 / CV-108-52

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-108-52 / CV-108-52

Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-1902A / CV-1902A

Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-2001 / CV-2001

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-2001 / CV-2001


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHWCV113 / CV-113

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-113 / CV-113

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-113 / CV-113


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHWCV114 / CV-114

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-114 / CV-114

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-114 / CV-114


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name

CHCV1423 / CV-1423

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name

CV-1423 / CV-1423

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-1423 / CV-1423


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CCV1532A / CV-1532A

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-1532A / CV-1532A

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-1532A / CV-1532A


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHCV1535 / CV-1535

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-1535 / CV-1535

Parameter / Unit

Carbon Monoxide

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-1535 / CV-1535


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV1902A / CV-1902A

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-1902A / CV-1902A


Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHCV2001 / CV-2001

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CHCV2002 / CV-2002

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-2002 / CV-2002

Parameter / Unit

Carbon Monoxide

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-2002 / CV-2002


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHCV2007 / CV-2007

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-2007 / CV-2007

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-2007 / CV-2007


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHCV2301 / CV-2301

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-2301 / CV-2301

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-2301 / CV-2301


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHCV2302 / CV-2302

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-2302 / CV-2302

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name

CV-2302 / CV-2302

Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHCV2303 / CV-2303

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-2303 / CV-2303

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-2303 / CV-2303

Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHCV2305 / CV-2305

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-2305 / CV-2305

Parameter / Unit

Carbon Monoxide

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-2305 / CV-2305

Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHCV2312 / CV-2312

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-2312 / CV-2312

Parameter / Unit

Carbon Monoxide

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-2312 / CV-2312


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHCV2314 / CV-2314

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-2314 / CV-2314

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-2314 / CV-2314


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHCV2315 / CV-2315

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-2315 / CV-2315

Parameter / Unit

Carbon Monoxide

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-2315 / CV-2315


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHCV2328 / CV-2328

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-2328 / CV-2328

Parameter / Unit

Carbon Monoxide

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-2328 / CV-2328


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHCV2333 / CV-2333

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-2333 / CV-2333

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-2333 / CV-2333


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHCV2334 / CV-2334

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-2334 / CV-2334

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-2334 / CV-2334


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHCV2337 / CV-2337

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-2337 / CV-2337

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-2337 / CV-2337


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHCV2341 / CV-2341

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-2341 / CV-2341

Parameter / Unit

Carbon Monoxide

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-2341 / CV-2341


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHCV2344 / CV-2344

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-2344 / CV-2344

Parameter / Unit

Carbon Monoxide

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-2344 / CV-2344


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHCV2345 / CV-2345

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-2345 / CV-2345

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-2345 / CV-2345


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHCV2346 / CV-2346

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-2346 / CV-2346

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-2346 / CV-2346


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHCV2347 / CV-2347

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-2347 / CV-2347

Parameter / Unit

Carbon Monoxide

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-2347 / CV-2347


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHCV2348 / CV-2348

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-2348 / CV-2348

Parameter / Unit

Carbon Monoxide

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-2348 / CV-2348

Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHCV2349 / CV-2349

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-2349 / CV-2349

Parameter / Unit

Carbon Monoxide

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-2349 / CV-2349


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHCV2350 / CV-2350

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-2350 / CV-2350

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-2350 / CV-2350


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHCV2351 / CV-2351

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-2351 / CV-2351

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-2351 / CV-2351


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHCV2352 / CV-2352

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-2352 / CV-2352

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-2352 / CV-2352


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHCV2353 / CV-2353-PLR

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-2353 / CV-2353

Parameter / Unit

Carbon Monoxide

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CV-2353 / CV-2353

Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26




Point ID / Name


CHCV2354 / CV-2354

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-2354 / CV-2354

Parameter / Unit

Carbon Monoxide

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-2354 / CV-2354

Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24002 / CV-24002


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CCV24003 / CV-24003


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CCV24007 / CV-24007

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24007 / CV-24007

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24007 / CV-24007


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24017 / CV-24017

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24017 / CV-24017

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24017 / CV-24017


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24049 / CV-24049

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24049 / CV-24049

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24049 / CV-24049

Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24053 / CV-24053

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24053 / CV-24053

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24053 / CV-24053


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24055 / CV-24055

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24055 / CV-24055

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24055 / CV-24055


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24062 / CV-24062

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24062 / CV-24062

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24062 / CV-24062


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24063 / CV-24063

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24063 / CV-24063

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24063 / CV-24063


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24064 / CV-24064

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24064 / CV-24064

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24064 / CV-24064

Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24065 / CV-24065-TP17

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24065 / CV-24065

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24065 / CV-24065


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24066 / CV-24066

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24066 / CV-24066

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24066 / CV-24066

Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24069 / CV-24069

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24069 / CV-24069

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24069 / CV-24069


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24070 / CV-24070

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24070 / CV-24070

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24070 / CV-24070

Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24071 / CV-24071

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24071 / CV-24071

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24071 / CV-24071


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24075 / CV-24075-TP15

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24075 / CV-24075

Parameter / Unit

Carbon Monoxide

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24075 / CV-24075


Parameter / Unit

Hydrogen /%,v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24077 / CV-24077

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name

CV-24079 / CV-24079

Parameter / Unit

Carbon Monoxide

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24079 / CV-24079


Parameter / Unit

Hydrogen /%,v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24079 / CV-24079-TP8

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CCV24082 / CV-24082


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CCV24083 / CV-24083

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name

CV-24083 / CV-24083

Parameter / Unit

Carbon Monoxide

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24083 / CV-24083

Parameter / Unit

Hydrogen /%,v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CCV24084 / CV-24084-TP11

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24084-TP11 / CV-24084-TP11

Parameter / Unit

Carbon Monoxide

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24084-TP11 / CV-24084-TP11


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24088 / CV-24088


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CCV24095 / CV-24095

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24095 / CV-24095

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24095 / CV-24095


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24096 / CV-24096

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CCV24097 / CV-24097


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CCV24098 / CV-24098


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CCV24099 / CV-24099


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CCV24100 / CV-24100

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24100 / CV-24100

Parameter / Unit

Carbon Monoxide

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24100 / CV-24100


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24101 / CV-24101

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24101 / CV-24101

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24101 / CV-24101


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24102 / CV-24102

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CCV24120 / CV-24120

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24120 / CV-24120

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24120 / CV-24120


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24121 / CV-24121

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24121 / CV-24121

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24121 / CV-24121


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24122 / CV-24122

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24122 / CV-24122

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24122 / CV-24122


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CCV24123 / CV-24123


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CCV24125 / CV-24125-TP20

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24125 / CV-24125

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24125 / CV-24125


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24126 / CV-24126

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24126 / CV-24126

Parameter / Unit

Carbon Monoxide

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name

CV-24126 / CV-24126

Parameter / Unit

Hydrogen /% v/v


**Chiquita Canyon Landfill - LAB DATA**


Parameter Chart: Uniscale

Date Range: 06/01/2025 - 05/31/2026

Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24127 / CV-24127

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24127 / CV-24127

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24127 / CV-24127


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24128 / CV-24128

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24128 / CV-24128

Parameter / Unit

Carbon Monoxide

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24128 / CV-24128

Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24134 / CV-24134-TP19

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name

CV-24134 / CV-24134

Parameter / Unit

Carbon Monoxide

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24134 / CV-24134


Parameter / Unit

Hydrogen /%,v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24138 / CV-24138

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24138 / CV-24138

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24138 / CV-24138


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24139 / CV-24139

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24139 / CV-24139

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24139 / CV-24139


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24140 / CV-24140

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24140 / CV-24140

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24140 / CV-24140


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24141 / CV-24141

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24141 / CV-24141

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24141 / CV-24141


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24142 / CV-24142

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24142 / CV-24142

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24142 / CV-24142


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24143 / CV-24143

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CV-24143 / CV-24143

Parameter / Unit

Carbon Monoxide

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-24143 / CV-24143


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CCV24144 / CV-24144


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


CHH1770N / H-1770N

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


H-1770N / H-1770N

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


H-1770N / H-1770N


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHH2165W / H-2165W

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


H-2165W / H-2165W

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


H-2165W / H-2165W

Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CHH2273W / H-2273W

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools




Point ID / Name


H-2273W / H-2273W

Parameter / Unit

Carbon Monoxide /ppmv

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


H-2273W / H-2273W


Parameter / Unit

Hydrogen /% v/v

**Chiquita Canyon Landfill - LAB DATA**
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name

CTC2383S / TC-2383S


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

**Chiquita Canyon Landfill**
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools

# Thirty Day Maximum Vertical Temperature Map from the Temperature Probes at the Chiquita Canyon Landfill -May 2026




Max Temps - 20:55:42 05-31-2026

Current | 7 Day | 30 Day

| BOREHOLE | MAX TEMP (°F) | @ DEPTH (FT) |
|---|---|---|
| TP01 | 151 | 100 |
| TP02 | 158 | 60 |
| TP03 | 234 | 45 |
| TP04 | 158 | 30 |
| TP05 | 167 | 45 |
| TP06 | 139 | 100 |
| TP07 | 154 | 100 |
| TP08 | 177 | 45 |
| TP09 | 208 | 125 |
| TP10 | 156 | 125 |
| TP11 | 210 | 125 |
| TP12 | 150 | 125 |
| TP13 | 174 | 140 |
| TP14 | 2,508 | 150 |
| TP15 | 203 | 100 |
| TP16 | 181 | 30 |
| TP17 | 161 | 125 |
| TP18 | 208 | 45 |
| TP19 | 232 | 150 |
| TP20 | 141 | 45 |
| TP21 | 258 | 110 |
| TP22 | 197 | 15 |
| TP23 | 2,508 | 30 |
| TP24 | 210 | 265 |
| TP25 | 210 | 130 |
| TP26 | 177 | 150 |
| TP27 | 157 | 100 |
| TP28 | 144 | 170 |
| TP29 | 194 | 240 |
| TP30 | 174 | 190 |
| TP31 | 192 | 180 |
| TP32 | 170 | 130 |
| TP33 | 198 | 45 |
| TP34 | 151 | 120 |
| TP35 | 175 | 140 |
| TP36 | 172 | 165 |
| TP37 | 184 | 180 |
| TP38 | 172 | 165 |
| TP39 | 159 | 160 |
| TP40 | 149 | 185 |

**TP-14- The 150 foot thermocouple reported a maximum temperature of 2305 o May 10th, which was anomalous and likely associated with a potential thermocouple malfunction. As a result the report temperatures from May 11 to 15th are considered anomalous also. The 150 foot thermocouple was replaced on May 16thand temperature were consistent with previously recorded values.**

**TP -23 The reported maximum temperature reading of 2508 at the 30 foot thermocouple is considered anomolous and is believed to associated with a potential thermocouple sensor malfunction. The 30-foot thermocouple temperatures remained consistent with previously recorded values with the thermocouple functioning as normal.**

# Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 3/26/2026 12:00 AM to 5/6/2026 11:59 PM

SCS ENGINEERS

07224053.00 | May 7, 2026

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

From April 30, 2026, through May 6, 2026, there were three recorded temperature increases and one recorded temperature decrease that triggered the notification limits set forth in the LEA's October 4, 2024 letter.

Chiquita provides the following updates:


- TP-08
  - The 125-foot thermocouple went offline on March 3rd and TP-8 was offline between March 6th and March 9th for evaluation and maintenance. Upon removing the thermocouples, the casing for TP-08 was found to be damaged due to differential settlement beyond 45-feet, thus preventing the installation of the 100-foot, 125-foot, and 150-foot thermocouples. The 15-foot, 30-foot, and 45-foot thermocouples are active and reporting data.
  - The 30-foot thermocouple showed an increase in maximum temperature of 14°F from 159°F to 173°F from April 30th to May 6th.
  - The 45-foot thermocouple showed an increase in maximum temperature of 12°F from 166°F to 178°F from April 30th to May 6th.

- TP-19
  - The 150-foot thermocouple remained consistent with previous recorded temperatures.

- TP-23
  - TP-23 reported maximum values of 2508°F on March 31st, due to being taken offline for pumping liquids from the probe casing prior to thermocouples being re-installed, causing the single day erroneous readings.
  - The 15-foot thermocouple showed a decrease in maximum temperature of 26°F from 214°F to 188°F from April 30th to May 3rd and then an increase in maximum temperature of 26°F from 188°F to 214°F from May 3rd to May 6th.

- TP-36
  - The 250-foot thermocouple was evaluated due to low temperatures on April 6th and wiring that had come loose was corrected. After fixing the wiring issues temperatures returned to 136°F as previously recorded prior to March 21st.


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3






SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5


Maximum data for 3/26/2026 12:00 AM to 5/6/2026 11:59 PM






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16






SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18


Maximum data for 3/26/2026 12:00 AM to 5/6/2026 11:59 PM






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20






SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22


Maximum data for 3/26/2026 12:00 AM to 5/6/2026 11:59 PM






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39






SCS ENGINEERS


# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40






SCS ENGINEERS


# Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill




Max Temps - 04:58:45 05-07-2026

Current | 7 Day | 30 Day

| BOREHOLE | MAX TEMP (°F) | @ DEPTH (FT) |
|---|---|---|
| TP01 | 151 | 100 |
| TP02 | 158 | 60 |
| TP03 | 233 | 45 |
| TP04 | 158 | 30 |
| TP05 | 167 | 45 |
| TP06 | 138 | 120 |
| TP07 | 154 | 100 |
| TP08 | 177 | 45 |
| TP09 | 208 | 125 |
| TP10 | 155 | 125 |
| TP11 | 207 | 125 |
| TP12 | 149 | 125 |
| TP13 | 173 | 140 |
| TP14 | 172 | 150 |
| TP15 | 202 | 100 |
| TP16 | 181 | 30 |
| TP17 | 161 | 125 |
| TP18 | 204 | 45 |
| TP19 | 217 | 150 |
| TP20 | 140 | 45 |
| TP21 | 258 | 110 |
| TP22 | 196 | 15 |
| TP23 | 260 | 75 |
| TP24 | 207 | 265 |
| TP25 | 209 | 130 |
| TP26 | 177 | 150 |
| TP27 | 157 | 100 |
| TP28 | 143 | 170 |
| TP29 | 189 | 240 |
| TP30 | 174 | 190 |
| TP31 | 192 | 180 |
| TP32 | 169 | 130 |
| TP33 | 198 | 45 |
| TP34 | 151 | 120 |
| TP35 | 174 | 140 |
| TP36 | 172 | 165 |
| TP37 | 184 | 180 |
| TP38 | 171 | 165 |
| TP39 | 158 | 160 |
| TP40 | 149 | 185 |




N

GRAPHIC SCALE

130 65 0 130 260 390

SCALE: 1"=130'

**LEGEND**

| | |
|---|---|
| 1150 | EXISTING TOPOGRAPHIC CONTOUR |
| | EXISTING CELL LIMITS (APPROXIMATE) |
| TP-XX | INSTALLED TEMPERATURE PROBES - STANDALONE |
| TP-XX | INSTALLED TEMPERATURE PROBES - INSTALLED WITHIN WELL CASING |
| | REACTION AREA BOUNDARY (APPROXIMATE) - BASED ON DATA REVIEW |
| | REACTION AREA BOUNDARY - CONDITION 9A |

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER. AERIAL PHOTOGRAPHY DATED JANUARY 28, 2026.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

DATE

REVISION

NO.

SHEET TITLE: EXISTING TEMPERATURE PROBE MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

**SCS ENGINEERS**
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544

ACAD FILE: -
DWN: BY: -
CHK: BY: -
APP: BY: -
PROJ. NO. 01204123.41
DSN: BY: -

DATE: 02/10/2026

SCALE: AS SHOWN

SHEET: 1

# Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM

SCS ENGINEERS

07224053.00 | May 14, 2026

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

From May 7, 2026, through May 13, 2026, there were three recorded temperature decreases that triggered the notification limits set forth in the LEA's October 4, 2024 letter.

Chiquita provides the following updates:


- TP-08
  - The 125-foot thermocouple went offline on March 3rd and TP-8 was offline between March 6th and March 9th for evaluation and maintenance. Upon removing the thermocouples, the casing for TP-08 was found to be damaged due to differential settlement beyond 45-feet, thus preventing the installation of the 100-foot, 125-foot, and 150-foot thermocouples. The 15-foot, 30-foot, and 45-foot thermocouples are active and reporting data.
  - The 15-foot thermocouple showed a decrease in maximum temperature of 19°F from 156°F to 137°F from May 7th to May 13th.
  - The 30-foot thermocouple showed a decrease in maximum temperature of 35°F from 175°F to 140°F from May 7th to May 13th.
  - The 45-foot thermocouple showed a decrease in maximum temperature of 36°F from 177°F to 141°F from May 7th to May 13th.

- TP-14
  - The 150-foot thermocouple showed a single hour anomalous temperature increase on May 10th.
  - The reported maximum temperature reading of 2508°F is considered anomalous and is believed to be associated with a potential thermocouple sensor malfunction. The sensor remains under evaluation and investigation.

- TP-23
  - The 15-foot thermocouple remained consistent with previous recorded temperatures.
  - The reported maximum temperature reading of 2508°F is considered anomalous and is believed to be associated with a potential thermocouple sensor malfunction. The sensor remains under evaluation and investigation.
- TP-36
  - The 250-foot thermocouple was evaluated due to low temperatures on April 6th and wiring that had come loose was corrected. After fixing the wiring issues, temperatures returned to 136°F as previously recorded prior to March 21st.

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM






SCS ENGINEERS

# Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill





Max Temps - 04:58:43 05-14-2026

Current | 7 Day | 30 Day

| BOREHOLE | MAX TEMP (°F) | @ DEPTH (FT) |
|---|---|---|
| TP01 | 151 | 100 |
| TP02 | 158 | 60 |
| TP03 | 234 | 45 |
| TP04 | 158 | 30 |
| TP05 | 167 | 45 |
| TP06 | 139 | 100 |
| TP07 | 154 | 100 |
| TP08 | 176 | 45 |
| TP09 | 208 | 125 |
| TP10 | 156 | 125 |
| TP11 | 209 | 100 |
| TP12 | 150 | 125 |
| TP13 | 174 | 140 |
| TP14 | 2,508 | 150 |
| TP15 | 202 | 100 |
| TP16 | 181 | 30 |
| TP17 | 161 | 125 |
| TP18 | 206 | 45 |
| TP19 | 231 | 150 |
| TP20 | 140 | 45 |
| TP21 | 258 | 110 |
| TP22 | 197 | 15 |
| TP23 | 2,508 | 30 |
| TP24 | 208 | 265 |
| TP25 | 209 | 130 |
| TP26 | 177 | 150 |
| TP27 | 157 | 100 |
| TP28 | 143 | 170 |
| TP29 | 188 | 240 |
| TP30 | 174 | 190 |
| TP31 | 192 | 180 |
| TP32 | 169 | 130 |
| TP33 | 198 | 45 |
| TP34 | 151 | 120 |
| TP35 | 174 | 140 |
| TP36 | 172 | 165 |
| TP37 | 184 | 180 |
| TP38 | 171 | 165 |
| TP39 | 159 | 160 |
| TP40 | 149 | 185 |

*The reported maximum temperature reading of 2508°F for TP-14 and TP-23 is considered anomalous and is believed to be associated with a potential thermocouple sensor malfunction. The sensors remain under evaluation and investigation.




N

GRAPHIC SCALE

130 65 0 130 260 390

SCALE: 1"=130'

**LEGEND**

- 1150 — EXISTING TOPOGRAPHIC CONTOUR
- EXISTING CELL LIMITS (APPROXIMATE)
- TP-XX — INSTALLED TEMPERATURE PROBES - STANDALONE
- TP-XX — INSTALLED TEMPERATURE PROBES - INSTALLED WITHIN WELL CASING
- REACTION AREA BOUNDARY (APPROXIMATE) - BASED ON DATA REVIEW
- REACTION AREA BOUNDARY - CONDITION 9A

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER. AERIAL PHOTOGRAPHY DATED APRIL 30, 2026.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

| NO. | REVISION | DATE |
|---|---|---|

SHEET TITLE: EXISTING TEMPERATURE PROBE MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA


**SCS ENGINEERS**
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544


PROJ. NO. 01204123.41 | DWN. BY: - | CHK. BY: - | ACAD FILE: - | APP. BY: - | DSN. BY: -

DATE: 05/07/2026

SCALE: AS SHOWN

SHEET: 1

# Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM

SCS ENGINEERS

07224053.00 | May 21, 2026

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

From May 14, 2026, through May 20, 2026, there were one recorded temperature increase and three recorded temperature decreases that triggered the notification limits set forth in the LEA's October 4, 2024 letter.

Chiquita provides the following updates:

- TP-08
  - The 125-foot thermocouple went offline on March 3rd and TP-8 was offline between March 6th and March 9th for evaluation and maintenance. Upon removing the thermocouples, the casing for TP-08 was found to be damaged due to differential settlement beyond 45-feet, thus preventing the installation of the 100-foot, 125-foot, and 150-foot thermocouples. The 15-foot, 30-foot, and 45-foot thermocouples are active and reporting data.
  - The 15-foot thermocouple remained consistent with previous recorded temperatures..
  - The 30-foot thermocouple remained consistent with previous recorded temperatures. The 45-foot thermocouple maximum temperature increased by 15°F from 141°F to 156°F between May 14th and May 16th, and then decreased by 18°F from 156°F to 138°F between May 16th and May 20th.
- TP-14
  - The 150-foot thermocouple reported a maximum temperature of 249°F on May 10th, which was anomalous and likely associated with a potential thermocouple sensor malfunction. As a result, the reported temperatures of 0°F from May 11th to May 15th are also considered anomalous. The 150-foot thermocouple maximum temperature decreased by 77°F from 249°F to 172°F between May 10th and May 16th Temperatures remained consistent with previous recorded values from May 16th through May 20th with the thermocouple under evaluation and investigation.
  - The reported maximum temperature reading of 2508°F at the 150-foot thermocouple is considered anomalous and is believed to be associated with a potential thermocouple sensor malfunction. The sensor remains under evaluation and investigation.


- TP-23
  - The 15-foot thermocouple reported temperatures of 0°F from May 13th to May 18th, which were anomalous and likely associated with a potential thermocouple sensor malfunction. On May 19th, a temperature of 189°F was reported, with temperatures remaining consistent with previous recorded values through May 20th with the thermocouple functioning as normal.
  - The 30-foot thermocouple reported temperatures of 0°F from May 13th to May 18th, which were anomalous and likely associated with a potential thermocouple sensor malfunction. On May 19th, a

temperature of 221°F was reported, with temperatures remaining consistent with previous recorded values through May 20th with the thermocouple under evaluation and investigation.

- The reported maximum temperature reading of 2508°F at the 30-foot thermocouple is considered anomalous and is believed to be associated with a potential thermocouple sensor malfunction. The sensor remains under evaluation and investigation.

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM






SCS ENGINEERS

# Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill





Max Temps - 04:58:44 05-21-2026

Current | 7 Day | 30 Day

| BOREHOLE | MAX TEMP (°F) | @ DEPTH (FT) |
|---|---|---|
| TP01 | 151 | 100 |
| TP02 | 158 | 60 |
| TP03 | 233 | 45 |
| TP04 | 158 | 30 |
| TP05 | 166 | 45 |
| TP06 | 139 | 100 |
| TP07 | 154 | 100 |
| TP08 | 156 | 45 |
| TP09 | 208 | 125 |
| TP10 | 154 | 125 |
| TP11 | 209 | 125 |
| TP12 | 150 | 125 |
| TP13 | 174 | 140 |
| TP14 | 2,508 | 150 |
| TP15 | 203 | 100 |
| TP16 | 181 | 30 |
| TP17 | 161 | 125 |
| TP18 | 206 | 45 |
| TP19 | 228 | 150 |
| TP20 | 140 | 45 |
| TP21 | 258 | 110 |
| TP22 | 197 | 15 |
| TP23 | 2,508 | 30 |
| TP24 | 209 | 265 |
| TP25 | 209 | 130 |
| TP26 | 177 | 150 |
| TP27 | 157 | 100 |
| TP28 | 144 | 170 |
| TP29 | 194 | 240 |
| TP30 | 174 | 190 |
| TP31 | 192 | 180 |
| TP32 | 169 | 130 |
| TP33 | 198 | 45 |
| TP34 | 151 | 120 |
| TP35 | 174 | 140 |
| TP36 | 172 | 165 |
| TP37 | 184 | 180 |
| TP38 | 172 | 165 |
| TP39 | 159 | 160 |
| TP40 | 149 | 185 |

*The reported maximum temperature readings of 2508°F for TP-14 and TP-23 are considered anomalous and are believed to be associated with potential thermocouple sensor malfunctions. The sensors remain under evaluation and investigation.




N

GRAPHIC SCALE

130 65 0 130 260 390

SCALE: 1"=130'

**LEGEND**

- 1150 — EXISTING TOPOGRAPHIC CONTOUR
- EXISTING CELL LIMITS (APPROXIMATE)
- TP-XX — INSTALLED TEMPERATURE PROBES - STANDALONE
- TP-XX — INSTALLED TEMPERATURE PROBES - INSTALLED WITHIN WELL CASING
- REACTION AREA BOUNDARY (APPROXIMATE) - BASED ON DATA REVIEW
- REACTION AREA BOUNDARY - CONDITION 9A

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER. AERIAL PHOTOGRAPHY DATED APRIL 30, 2026.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

| NO. | REVISION | DATE |
|---|---|---|

SHEET TITLE: EXISTING TEMPERATURE PROBE MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA


**SCS ENGINEERS**
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544


PROJ. NO. 01204123.41 | DWN. BY: - | CHK. BY: - | ACAD FILE: - | APP. BY: - | DSN. BY: -

DATE: 05/07/2026

SCALE: AS SHOWN

SHEET: 1

# Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM

SCS ENGINEERS

07224053.00 | May 28, 2026

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330


From May 21, 2026, through May 27, 2026, there were no recorded temperature increases or decreases that triggered the notification limits set forth in the LEA's October 4, 2024 letter.

Chiquita provides the following updates:

- TP-08
  - The 125-foot thermocouple went offline on March 3rd and TP-8 was offline between March 6th and March 9th for evaluation and maintenance. Upon removing the thermocouples, the casing for TP-08 was found to be damaged due to differential settlement beyond 45-feet, thus preventing the installation of the 100-foot, 125-foot, and 150-foot thermocouples. The 15-foot, 30-foot, and 45-foot thermocouples are active and reporting data.
  - The 45-foot thermocouple remained consistent with previous recoded temperatures.
- TP-14
  - The 150-foot thermocouple reported a maximum temperature of 249°F on May 10th, which was anomalous and likely associated with a potential thermocouple sensor malfunction. As a result, the reported temperatures of 0°F from May 11th to May 15th are also considered anomalous. The 150-foot thermocouple was replaced on May 16th and temperatures were consistent with previous recorded values.
- TP-23
  - The 15-foot thermocouple reported temperatures of 0°F from May 13th to May 18th, which were anomalous and likely associated with a potential thermocouple sensor malfunction. On May 19th, a temperature of 189°F was reported, with temperatures remaining consistent with previous recorded values through May 27th with the thermocouple functioning as normal.
  - The 30-foot thermocouple reported temperatures of 0°F from May 13th to May 18th, which were anomalous and likely associated with a potential thermocouple sensor malfunction. On May 19th, a temperature of 221°F was reported, with temperatures remaining consistent with previous recorded values through May 27th with the thermocouple functioning as normal.
  - The reported maximum temperature reading of 2508°F at the 30-foot thermocouple is considered anomalous and is believed to be associated with a potential thermocouple sensor malfunction. The 30-foot thermocouple temperatures remained consistent with previous recorded values with the thermocouple functioning as normal.

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM






SCS ENGINEERS


# Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill




Max Temps - 04:58:38 05-28-2026

Current | 7 Day | 30 Day

| BOREHOLE | MAX TEMP (°F) | @ DEPTH (FT) |
|---|---|---|
| TP01 | 151 | 100 |
| TP02 | 157 | 60 |
| TP03 | 233 | 45 |
| TP04 | 158 | 30 |
| TP05 | 166 | 45 |
| TP06 | 139 | 100 |
| TP07 | 154 | 100 |
| TP08 | 146 | 30 |
| TP09 | 208 | 125 |
| TP10 | 155 | 125 |
| TP11 | 210 | 100 |
| TP12 | 150 | 125 |
| TP13 | 174 | 140 |
| TP14 | 172 | 150 |
| TP15 | 203 | 100 |
| TP16 | 179 | 30 |
| TP17 | 161 | 125 |
| TP18 | 207 | 45 |
| TP19 | 232 | 150 |
| TP20 | 140 | 45 |
| TP21 | 257 | 110 |
| TP22 | 197 | 15 |
| TP23 | 260 | 75 |
| TP24 | 209 | 265 |
| TP25 | 210 | 130 |
| TP26 | 177 | 150 |
| TP27 | 156 | 100 |
| TP28 | 143 | 170 |
| TP29 | 190 | 240 |
| TP30 | 174 | 190 |
| TP31 | 192 | 180 |
| TP32 | 169 | 130 |
| TP33 | 198 | 45 |
| TP34 | 151 | 120 |
| TP35 | 175 | 140 |
| TP36 | 172 | 165 |
| TP37 | 184 | 180 |
| TP38 | 171 | 165 |
| TP39 | 159 | 160 |
| TP40 | 149 | 185 |




N

GRAPHIC SCALE

130 65 0 130 260 390

SCALE: 1"=130'

**LEGEND**

- 1150 — EXISTING TOPOGRAPHIC CONTOUR
- EXISTING CELL LIMITS (APPROXIMATE)
- TP-XX — INSTALLED TEMPERATURE PROBES - STANDALONE
- TP-XX — INSTALLED TEMPERATURE PROBES - INSTALLED WITHIN WELL CASING
- REACTION AREA BOUNDARY (APPROXIMATE) - BASED ON DATA REVIEW
- REACTION AREA BOUNDARY - CONDITION 9A

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER. AERIAL PHOTOGRAPHY DATED APRIL 30, 2026.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

| NO. | REVISION | DATE |
|---|---|---|

SHEET TITLE: EXISTING TEMPERATURE PROBE MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA


**SCS ENGINEERS**
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544


PROJ. NO. 01204123.41 | DWN. BY: - | CHK. BY: - | ACAD FILE: - | APP. BY: - | DSN. BY: -

DATE: 05/07/2026

SCALE: AS SHOWN

SHEET: 1

# Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM

SCS ENGINEERS

07224053.00 | June 4, 2026

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

From May 28, 2026, through June 3, 2026, there were three recorded temperature increases and one recorded temperature decrease that triggered the notification limits set forth in the LEA's October 4, 2024 letter.

Chiquita provides the following updates:

- TP-08
  - The 125-foot thermocouple went offline on March 3rd and TP-8 was offline between March 6th and March 9th for evaluation and maintenance. Upon removing the thermocouples, the casing for TP-08 was found to be damaged due to differential settlement beyond 45-feet, thus preventing the installation of the 100-foot, 125-foot, and 150-foot thermocouples. The 15-foot, 30-foot, and 45-foot thermocouples are active and reporting data.
  - The 45-foot thermocouple showed an increasein maximum temperature of 18°F from 139°F to 157°F from May 31st to June 3rd.


- TP-14
  - The 150-foot thermocouple reported a maximum temperature of 249°F on May 10th, which was anomalous and likely associated with a potential thermocouple sensor malfunction. As a result, the reported temperatures of 0°F from May 11th to May 15th are also considered anomalous. The 150-foot thermocouple was replaced on May 16th and temperatures were consistent with previous recorded values.

- TP-23
  - The 15-foot thermocouple reported temperatures of 0°F from May 13th to May 18th, which were anomalous and likely associated with a potential thermocouple sensor malfunction. On May 19th, a temperature of 189°F was reported, with temperatures remaining consistent with previous recorded values through May 27th with the thermocouple functioning as normal.
  - The 30-foot thermocouple reported temperatures of 0°F from May 13th to May 18th, which were anomalous and likely associated with a potential thermocouple sensor malfunction. On May 19th, a temperature of 221°F was reported, with temperatures remaining consistent with previously recorded values through May 27th with the thermocouple functioning as normal.
  - The reported maximum temperature reading of 2508°F at the 30-foot thermocouple is considered anomalous and is believed to be associated with a potential thermocouple sensor malfunction. The 30-foot thermocouple temperatures remained consistent with previous recorded values with the thermocouple functioning as normal.
  - The 15-foot thermocouple showed an increasein maximum temperature of 22°F from 188°F to 210°F from June 1st to June 3rd.

- TP-29
  - The 240-foot thermocouple showed an increasein maximum temperature of 22°F from 186°F to 203°F from May 26th to June 2nd and then a decrease in maximum temperature of 22°F from 203°F to 188°F from June 2nd to June 3rd.

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM






SCS ENGINEERS


# Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill




Max Temps - 04:58:39 06-04-2026

Current | 7 Day | 30 Day

| BOREHOLE | MAX TEMP (°F) | @ DEPTH (FT) |
|---|---|---|
| TP01 | 151 | 100 |
| TP02 | 157 | 60 |
| TP03 | 233 | 45 |
| TP04 | 158 | 30 |
| TP05 | 166 | 45 |
| TP06 | 139 | 100 |
| TP07 | 154 | 100 |
| TP08 | 157 | 45 |
| TP09 | 208 | 125 |
| TP10 | 155 | 125 |
| TP11 | 210 | 125 |
| TP12 | 150 | 125 |
| TP13 | 174 | 140 |
| TP14 | 172 | 150 |
| TP15 | 202 | 100 |
| TP16 | 179 | 30 |
| TP17 | 161 | 125 |
| TP18 | 208 | 45 |
| TP19 | 233 | 150 |
| TP20 | 141 | 45 |
| TP21 | 256 | 110 |
| TP22 | 197 | 15 |
| TP23 | 260 | 75 |
| TP24 | 210 | 265 |
| TP25 | 209 | 130 |
| TP26 | 177 | 150 |
| TP27 | 156 | 100 |
| TP28 | 144 | 170 |
| TP29 | 203 | 240 |
| TP30 | 174 | 190 |
| TP31 | 192 | 180 |
| TP32 | 170 | 130 |
| TP33 | 198 | 45 |
| TP34 | 151 | 120 |
| TP35 | 175 | 140 |
| TP36 | 172 | 165 |
| TP37 | 184 | 180 |
| TP38 | 172 | 165 |
| TP39 | 159 | 160 |
| TP40 | 149 | 185 |




N

GRAPHIC SCALE

130 65 0 130 260 390

SCALE: 1"=130'

**LEGEND**

- 1150 — EXISTING TOPOGRAPHIC CONTOUR
- EXISTING CELL LIMITS (APPROXIMATE)
- TP-XX — INSTALLED TEMPERATURE PROBES - STANDALONE
- TP-XX — INSTALLED TEMPERATURE PROBES - INSTALLED WITHIN WELL CASING
- REACTION AREA BOUNDARY (APPROXIMATE) - BASED ON DATA REVIEW
- REACTION AREA BOUNDARY - CONDITION 9A

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER. AERIAL PHOTOGRAPHY DATED APRIL 30, 2026.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

| NO. | REVISION | DATE |
|---|---|---|

SHEET TITLE: EXISTING TEMPERATURE PROBE MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA


**SCS ENGINEERS**
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544


PROJ. NO. 01204123.41 | DWN. BY: - | CHK. BY: - | ACAD FILE: - | APP. BY: - | DSN. BY: -

DATE: 05/07/2026

SCALE: AS SHOWN

SHEET: 1

Attachment E

June 10, 2026

Reaction Committee Report

June 10, 2026
File No. 01204123.21-13

Mr. Baitong Chen
South Coast Air Quality Management District
21865 Copley Drive
Diamond Bar, California 91765

Subject: Monthly Reaction Mitigation Area Boundary Determination
Chiquita Canyon Landfill – Castaic, California

Dear Mr. Chen:

In accordance with Condition Nos. 9a and 9b of the Modified Stipulated Order for Abatement (SOFA) pertaining to the Chiquita Canyon Landfill (Landfill or Facility) (Case No. 6177-4), SCS Engineers (SCS), on behalf of Chiquita Canyon, LLC (Chiquita) has prepared the data-determined Reaction Mitigation Area boundary for May 2026 considering the following criteria:

- Vertical landfill gas (LFG) wellhead temperatures (greater than 160 degrees Fahrenheit).
- Temperature monitoring probe (TMP) measurements (greater than 170 degrees Fahrenheit for more than 3-weeks at any depth).
- Landfill gas quality and methane to CO2 ratio ($CH_4$:$CO_2$) (methane concentrations of less than 30 percent in conjunction with $CH_4$:$CO_2$ ratios less than 1.0).
- Landfill gas concentration of carbon monoxide (CO) (greater than 1,500 ppm) to the extent measured.
- Landfill gas concentration of hydrogen ($H_2$) (greater than 2 percent by volume), to the extent measured.
- Landfill settlement (18 inches or greater within a 60-day period).
- Pressurized leachate releases.

These parameters have been subjected to a cumulative evaluation within each individual landfill surface grid within the Main Canyon (i.e., excluding grids 1 through 29 as well as grids 105 through 144), including all landfill gas wells, temperature probes, and other characteristics within that grid's area. For each individual landfill grid that is contiguous to the prior month's Reaction Mitigation Area, where any three or more parameters listed above indicating reaction conditions are present at the time of evaluation, including any combination of wells, temperature probes, or areas within the grid, the data-determined Reaction Mitigation Area boundary depicted on the Reaction Mitigation Area map will be adjusted to include such landfill grid(s).

For each individual landfill grid that is not contiguous to the prior month's Reaction Mitigation Area, if the three parameters present include a temperature parameter, then the grid will be added to the Reaction Mitigation Area.

In addition to the listed parameters, the following have been considered for the determination of the Reaction Mitigation Area boundary, also using an individual landfill grid-based evaluation:

- Leachate seeps;
- Odor characteristics;
- Wellheads experiencing conditions which would be expected to result in a PLR (e.g. elevated pressure, elevated temperature, liquid flow through wellhead); and
- Waste cuttings according to borehole drilling logs.

Supporting evidence, including documentation of which parameters were met or exceeded for each individual landfill grid, field testing and laboratory results (if applicable), explanation for the determination, revised Reaction Mitigation Area boundary, Reaction Mitigation Area map (if applicable), isothermal gradient range map consisting of wellhead temperature measurements, wellhead carbon monoxide range map, wellhead hydrogen range map, wellhead CH4:CO2 ratio range map, monthly landfill settlement isopach maps and 60-day isopach map, wellhead and temperature probe map with surface grids displayed, and vertical temperature profiles for temperature probes is being hereby submitted to the South Coast Air Quality Management District.

Attachment A presents the Drawing, titled "Reaction Mitigation Area Map", which depicts the Reaction Mitigation Area boundary as prescribed in Condition No. 9a, which corresponds to the limits of Cells 1/2A, 2B/3, 4, and Module 2B/3/4 P2, as a solid black line. The Drawing also depicts the Condition No. 9b data-determined Reaction Mitigation Area as a dashed magenta line.

## CONCLUSION

As presented on the Drawing included as Attachment A, the extent of the data-determined Reaction Mitigation Area (dashed magenta line) is fully contained within the Reaction Mitigation Area boundary decreed in the SOFA (solid black line), except for Grid Nos. 38, 41, 53, 76, 77, 82n and 145 through 149, of which all or a portion protrudes east beyond the Cell 1/2A boundary. Because the data-driven Reaction Mitigation Area is not fully contained within the Reaction Mitigation Area boundary, the Reaction Mitigation Area boundary as prescribed in Condition No. 9a is modified to include portions of these Grids that extend beyond the Cell 1/2A boundary.

- Grid No. 38 is being incorporated based on the poor LFG quality criterium;
- Grid No. 41 is being incorporated based on the poor LFG quality and hydrogen criteria;
- Grid No. 53 is being incorporated based on the TMP temperature and poor LFG quality criteria;
- Grid No. 77 is being incorporated based on the TMP temperature, poor LFG quality, and CO concentration criteria;
- Grid No. 82 is being incorporated based on the poor LFG quality, hydrogen, and CO criteria.

The maximum temperature measurements recorded at the 40 in-situ waste temperature monitoring probes (both 7-Day and 30-Day values) during May 2026 are presented in **Attachment B** in graphical format. The LFG wellhead temperatures recorded at the extraction wells for the entire Landfill footprint are reflected on the isothermal gradient range map presented as **Attachment C**. The $CH_4$:$CO_2$ ratios measured at the LFG wellheads in the vicinity of the data-driven Reaction Mitigation Area boundary are depicted on the range map presented as **Attachment D**. The $H_2$ concentrations measured at the LFG wellheads in the vicinity of the data-driven Reaction Mitigation Area boundary are depicted on the range map presented as **Attachment E**. The CO concentrations measured at the LFG wellheads in the vicinity of the data-driven Reaction Mitigation Area boundary are depicted on the range map presented as **Attachment F**. The landfill surface settlement isopach values measured on a monthly basis and 60-day basis in the vicinity of the data-driven Reaction Mitigation Area boundary are depicted on the range map presented as **Attachment G**.
Please contact either of the undersigned if you have questions or require additional information.

Sincerely,

Robert E. Dick, PE, BCEE
Senior Vice President
SCS Engineers


Patrick S. Sullivan, BCES, CCP
Senior Vice President
SCS Engineers

RED/PSS

cc: Nathaniel Dickel, SCAQMD
Christina Ojeda, SCAQMD

Enclosures:

Attachment A – Reaction Mitigation Area Map
Attachment B – In-Situ Waste Temperature Monitoring Probe Data
Attachment C – Isothermal Gradient Range Map
Attachment D – Wellhead Methane-to-Carbon Dioxide Range Map
Attachment E – Wellhead Hydrogen Range Map
Attachment F – Wellhead Carbon Monoxide Range Map
Attachment G – Settlement Isopach Range Map




GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLOR. AERIAL PHOTOGRAPHY DATED MAY 27, 2026.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

DATE | REVISION | NO.

REACTION MITIGATION AREA

CHIQUITA CANYON LANDFILL
CASTAIC, CALIFORNIA

SHEET TITLE:

PROJECT TITLE:

CLIENT:

CHIQUITA CANYON LANDFILL
CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544

PROJ. NO: 01234123.45
DSN. BY: -
DWN. BY: HA
CHK. BY: -
APP. BY: -
ACAD: N:\CAD\ASBUILT-MASTERS\

DATE: 06/10/2026

SCALE: AS SHOWN

1 of 1

\\SAN-FS02\Data\Files\Engineers\Waste Connections\Chiquita Canyon LF\2026 Reaction Area Maps\05-May\Grid Map\CCLF MASTER EXISTING GCCS MAP_2026-06-05_(PLR Map).dwg Jun 11, 2026 - 12:04am By: holl

# Solid Waste Borehole Maximum Temperature Profiles Over 10 Weeks

for 3/16/202612:00AM to 5/31/202612:00AM


SCS ENGINEERS

07224053.00 | June 10, 2026

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM







SCS ENGINEERS

# Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM






SCS ENGINEERS


# Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill




Max Temps - 04:58:39 06-04-2026

Current | 7 Day | 30 Day

| BOREHOLE | MAX TEMP (°F) | @ DEPTH (FT) |
|---|---|---|
| TP01 | 151 | 100 |
| TP02 | 157 | 60 |
| TP03 | 233 | 45 |
| TP04 | 158 | 30 |
| TP05 | 166 | 45 |
| TP06 | 139 | 100 |
| TP07 | 154 | 100 |
| TP08 | 157 | 45 |
| TP09 | 208 | 125 |
| TP10 | 155 | 125 |
| TP11 | 210 | 125 |
| TP12 | 150 | 125 |
| TP13 | 174 | 140 |
| TP14 | 172 | 150 |
| TP15 | 202 | 100 |
| TP16 | 179 | 30 |
| TP17 | 161 | 125 |
| TP18 | 208 | 45 |
| TP19 | 233 | 150 |
| TP20 | 141 | 45 |
| TP21 | 256 | 110 |
| TP22 | 197 | 15 |
| TP23 | 260 | 75 |
| TP24 | 210 | 265 |
| TP25 | 209 | 130 |
| TP26 | 177 | 150 |
| TP27 | 156 | 100 |
| TP28 | 144 | 170 |
| TP29 | 203 | 240 |
| TP30 | 174 | 190 |
| TP31 | 192 | 180 |
| TP32 | 170 | 130 |
| TP33 | 198 | 45 |
| TP34 | 151 | 120 |
| TP35 | 175 | 140 |
| TP36 | 172 | 165 |
| TP37 | 184 | 180 |
| TP38 | 172 | 165 |
| TP39 | 159 | 160 |
| TP40 | 149 | 185 |




GENERAL DRAWING NOTES:

1. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

DATE
REVISION
NO.

SHEET TITLE: ISOTHERMAL GRADIENT MAP APRIL 2026

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3800 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH. (562) 426-9544


PROJ. NO. 01204123.41
DSN. BY: -
DWN. BY: HA
CHK. BY:
APP. BY: -
ACAD FILE: ENGINEERS

DATE: 06/10/2026

SCALE: AS SHOWN

SHEET: 1

\\SAN-FS02\Data\Files\Engineers\Waste Connections\Chiquita Canyon LF\2026 Temp Probe Data\Isothermal Gradient Maps\04-April 2026\CCLF Isothermal Map-April 2026_V1.0_2026-05-08.dwg Jun 10, 2026 8:57pm By: hali




**Ranges Mapped**

| | | | | | | # Points |
|---|---|---|---|---|---|---|
| | >= | 0 | and | < | 0.5 | 316 |
| | >= | 0.5 | and | < | 0.9 | 166 |
| | >= | 0.9 | and | < | 1.1 | 98 |
| | >= | 1.1 | and | < | 1.5 | 259 |
| | >= | 1.5 | and | < | 101 | 19 |

**Point Type Legend**

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

# Chiquita Canyon Landfill


## Range Map

## Parameter: CH4/CO2 Ratio (high range)

## Analysis Method: MostRecent

Date Range: 05/01/2026 - 05/31/2026

Map generation date : 06/10/2026




## Ranges Mapped

| | | | | | | # Points |
|---|---|---|---|---|---|---|
| | >= | 0 | and | < | 20000 | 18 |
| | >= | 20000 | and | < | 50000 | 8 |
| | >= | 50000 | and | < | 100000 | 20 |
| | >= | 100000 | and | < | 999999 | 69 |

## Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

**Chiquita Canyon Landfill**


**Range Map**

**Parameter: H2 (mid range)**

**Analysis Method: MostRecent**

Date Range: 05/01/2026 - 05/31/2026

Map generation date : 06/10/2026




## Ranges Mapped

| | | | | | | # Points |
|---|---|---|---|---|---|---|
| | >= | 0 | and | < | 500 | 21 |
| | >= | 500 | and | < | 1000 | 23 |
| | >= | 1000 | and | < | 1500 | 12 |
| | >= | 1500 | and | < | 2000 | 15 |
| | >= | 2000 | and | < | 5000 | 42 |
| | >= | 5000 | and | < | 100000 | 1 |

## Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

**Chiquita Canyon Landfill**

**Range Map**


**Parameter: CO LAB (mid range)**


**Analysis Method: MostRecent**

Date Range: 05/01/2026 - 05/31/2026

Map generation date : 06/10/2026

# Chiquita Canyon Landfill -Isopach






May 27, 2026 Survey Image. April 1, 2026 vs May 27, 2026


Attachment F

Monthly Isopach Map June

9, 2026

# Chiquita Canyon Landfill -Isopach






May 27, 2026 Survey Image. May 6, 2026 vs May 27, 2026