SCS ENGINEERS

July 15, 2026

Karen Gork
Chief Environmental Health Specialist
Los Angeles County Local Enforcement Agency
5050 Commerce Drive
Baldwin Park, California 91706

Subject: **June 2026 Monthly Report Pursuant to Milestones 1A-3 and 5 of the LEA June 6, 2024 Compliance Order and July 30, 2024 Letter, Chiquita Canyon Landfill, Castaic, California**

Dear Ms. Gork:

SCS Engineers (SCS), on behalf of Chiquita Canyon, LLC (Chiquita), hereby provides the Los Angeles County Department of Public Health, Solid Waste Management Program, acting as the Local Enforcement Agency (LEA) with a monthly report pursuant to Milestones 1A-3 and 5 of the LEA Compliance Order dated June 6, 2024 (Compliance Order) and subsequent related correspondence received from the LEA. This report covers the monthly period for June 2026.

Chiquita Canyon Landfill (CCL or Landfill) is a landfill/solid waste disposal facility located at 29201 Henry Mayo Drive in Castaic, California. In connection with the Landfill, Chiquita operates a landfill gas collection and control system. SCS prepared and submitted the Carbon Monoxide and Hydrogen Reading Summary Report (Summary Report) to the LEA on June 6, 2024, on behalf of Chiquita, in response to the directives in the LEA letters dated April 5, 2024 and May 28, 2024 regarding collection of landfill gas data and in accordance with Milestone 1A-2 of the Compliance Order. The LEA, in collaboration with the California Department of Resources, Recycling, and Recovery (CalRecycle), reviewed the Summary Report and determined that it complied with Milestone 1A-2. The LEA set forth several new requirements for Chiquita to comply with Milestone 1A-3 in follow-up correspondence dated July 30, 2024.

This report was prepared in accordance with Milestones 1A-3 and 5 of the Compliance Order, the LEA's follow-up correspondence dated July 30, 2024, Chiquita's letter dated September 3, 2024, the September 12, 2024, meeting with the LEA, and follow-up correspondence from the LEA dated November 19 and 27 and December 3, 2024.

Milestone 1A-3 Compliance Items

1. Submit the laboratory test results for monthly sampling of carbon monoxide (CO) and hydrogen (H2) from a set of landfill gas (LFG) wells selected by the LEA. Please see Table 1, columns labeled "CO" and "H2".

Results for wells monitored are shown in **Attachment A**.[1] The data is being submitted to the LEA in a standalone report signed by a licensed engineer, in accordance with Milestone 1A-3 of the Compliance Order. As noted in Chiquita's prior correspondence and monthly reports, this report does not include data from wells CV-100, CV-103, CV-1420, CV-1423, CV-1532, CV-2202, H-1403W, H-1560S, H-1774S, SC-2001W, TC-2383S, TC-2385A, and TC-2385S, as those wells have been abandoned, or from well CV-2332, as that well was never installed. All remaining wells were tested during the month of June 2026.

As discussed during the September 12, 2024 meeting, and as previously reported, graphics showing CO and H2 trends are provided in **Attachment D** and are discussed further below.

2. Provide data from readings for fixed gases (CH4, O2, and CO2) from a set of LFG wells selected by the LEA. See Table 1, column labeled "Fixed Gas CH4, O2, CO2."

The results for wells monitored are provided in **Attachment A**.

3. Collect down well temperatures at 34 wells to confirm the gas wellhead temperature readings per the requirement of the New Source Performance Standards (NSPS). See Table 1, column labeled "Down Well Temp Monitoring."

It is Chiquita's understanding from the LEA's November 27, 2024 correspondence, and as noted in prior monthly reports, that, at this time, Chiquita is only required to sample the wells at the annual frequency provided in the NSPS protocols, but that the LEA may require more frequent monitoring for up to ten (10) wells selected by the LEA. Chiquita is awaiting the LEA's selection of those wells.

Chiquita nevertheless provides in **Attachment B** the down-hole temperature graphs[2] concerning the following wells from fixed locations which contain the Lorentz Pumping System with integral temperature sensors while they were in operation during June 2026: CV-2302, CV-2303, CV-2315, CV-24017, CV-24065 and CV-24095.

Please note that the following locations, CV-2301, CV-2350 and CV-2352, no longer have graphs available due to various equipment-related issues, including damaged casings. (See **Attachment B** Monitoring List).

---

[1] The lab(s) reported data from additional LFG wells outside of those selected for sampling by the LEA; the additional data is related to separate South Coast Air Quality Management District (South Coast AQMD) reporting requirements and therefore can be disregarded for purposes of this report.

[2] Each graph notes a single temperature data point due to changes in the software.

SCS will continue to collect down-hole temperatures for wells on an annual basis and will report the results as the data is obtained at each location. SCS has performed annual down-hole temperature monitoring at 18 locations as of the end of June 2026, (Results are shown in **Attachment B**). The remaining eleven (11) wells will be monitored in accordance with the annual requirements and as pumps are repaired or replaced (See **Attachment B** for well monitoring dates and remaining locations).

4. Sample the selected 40 wells for VOCs by method TO-15. See Table 1, column labeled "VOC (TO-15)."

The results for wells monitored are provided in **Attachment A**.[3] Please note that 31 locations for VOC sampling were tested during June 2026. Nine locations (CV-100, CV-103, CV-1532, CV-2202, H-1403W, H-1560S, H-1758N, H-1774S, and TC-2385A) were not sampled as they have been abandoned.

5. Continue to sample and monitor 6 horizontal wells as indicated in Attachment 1, well numbers highlighted in yellow. At this time, 42 horizontal wells may be released from continued sampling, however, wells may be included later depending on future data submissions. See Table 1, well numbers highlighted in blue.

As noted in the September 3, 2024 letter and reported in prior monthly reports, two (2) of the six (6) horizontal wells (H-1774S and H-1560S) were abandoned when the new vertical extraction wells were installed. Additionally, H-1403W has since been abandoned. Thus, data from those wells are not included. Data from the three (3) other horizontal wells are in **Attachment A**.

6. Add 20 vertical wells to the monthly wellhead temperature and LFG sampling protocols. See Table 1.

As conveyed by the LEA during our September 12, 2024 meeting, and restated in our prior monthly reports, we understand the LEA is requiring laboratory analytical data for fixed gases, CO, and H2, as well as field data. Laboratory results are in **Attachment A**. Field data with wellhead gas temperatures are shown on Table 2 in **Attachment A**.

We understand from the LEA's November 27, 2024 correspondence that laboratory analytical data will be required for the specified fixed gases.

As noted in prior monthly reports, sampling was not conducted at the following wells in June 2026 for the reasons identified below:

CV-1420 – Abandoned during 2024 GCCS Expansion due to declining gas flows.

[3] Well CV-24142 is listed twice in Table 1 of the LEA's July 30, 2024 letter – one requires VOC sampling, and the other does not. Chiquita sampled this well for VOCs.

CV-2202 – Abandoned during 2024 GCCS Expansion due to declining gas flows.
CV-2332 – This well does not exist. This well was proposed for installation in Fall 2023, but other wells were installed in the area in lieu of CV-2332 when the number of wells increased pursuant to the Stipulated Order for Abatement (Stipulated Order) with the South Coast Air Quality Management District (South Coast AQMD).

7. Plot to show the locations of the following 19 wells on the site map titled "Existing GCCS Map – LFG Vertical Extraction Wells" dated 06/06/2024: CV-24002, CV-24003, CV-24007, CV-24017, CV-24053, CV-24055, CV-24065, CV-24071, CV-24075, CV-24077, CV-24079, CV-24082, CV-24083, CV-24088, CV-24095, CV-24096, CV-24097, CV-24098 and H-1403W. For well H-1403W, provide the horizontal location of piping and an estimate where the high temperature (195°F) is most likely occurring. See Table 1, well numbers highlighted in red and H-1403W (highlighted in yellow).

The locations of the above-identified wells are shown on the Map in **Attachment C**.[4]

8. Include in the monthly report, a settlement/heat map as shown below, beginning with the earliest heat map data available for each month to present. The topographic maps should show 2-foot contour intervals if possible.

The LEA directed Chiquita on June 2, 2025 to submit isopach maps on a monthly basis to comply with this request. For ease of reference, we are submitting as **Attachment F** a copy of the June 2026 isopach map, which was initially submitted to the LEA with the weekly cover logs on July 14, 2026.

9. Provide the sampling results in a standalone report with the appropriate discussion, tables, QA/QC, methods and signed by a registered professional, etc., as described in the Compliance Order Milestone 1A-2 and 1A-3.

CCL has provided the above-requested information and the raw data in **Attachment A**, as well as a figure with the data-driven reaction area which incorporates settlement data (see **Attachment F**). Temperature graphs are provided for wells with Lorentz pumps (4 locations).

Please note that in addition to the wells listed in response to the request dated July 30, 2024 (in Table 1) that could not be tested, the following wells that only required analytical data could also not be tested, as previously reported, because they were abandoned during the 2024 and 2025 GCCS expansion due to declining gas flows in accordance with the requirements of the NSPS: CV-100, CV-103, CV-1420, CV-1423, CV-1532, CV-2202, H-1403W, H-1560S, H-1774S, SC-2001W, TC-2383S, TC-2385A, and TC-2385S. Finally, as also previously reported, CV-2332 was never installed.

[4] The LEA acknowledged in its November 20, 2024 correspondence that a high temperature is not occurring in well H-1403W. We therefore did not map the maximum temperature at well H-1403W.

Sampling Procedures

Gas samples were collected using Tedlar or Mylar bags, as described in Chiquita's September 3, 2024 letter and the prior monthly reports, and then delivered to certified laboratories for testing. All permanent gas (CH4, CO2, O2, N2, CO, and H2) data were analyzed within the requested 24 hours of sampling. SCS continues to believe that use of the EPA-approved 72-hour holding time for these samples would be appropriate and accurate. Nevertheless, in response to the LEA's March 17, 2025 correspondence, SCS will continue to request 24-hour holding times for all fixed gases, including CO, H2, and VOCs, collected using Mylar or Tedlar bags. However, if additional sampling is required or if the laboratories have a change in workload, this holding time may change, in which case the LEA will be notified accordingly. During June 2026, all wells were tested for VOCs (EPA method TO-15) and permanent gases (EPA methods 1946 and Alt-144) within 24 hours by providing the laboratory with duplicate bag samples as needed for VOC testing.

Additional gas and pressure data were collected using either an Envision Irwin Gas Meter or Landtec GEM 5000 Gas monitoring device. These instruments measure combustible gas concentrations in air directly on either of two scales, the first as a percent by volume of the lower explosive limit (LEL) of methane gas in air (0 to 5 percent) and the other as a percent by volume (0 to 100 percent) in the gas sampled. The detection limit for these instruments is approximately 0.10 percent by volume.

Gas monitoring testing procedures were as follows:

- Connect sample tubing, open test valve, observe pressure, and record data.
- Turn on sample pump, purge a minimum of one probe volume, and observe and record methane, oxygen, and carbon dioxide gas concentrations when readings have stabilized.
- Close test valve, disconnect sample instruments, and secure sample location.

Milestone 1A-3 Conclusions

June 2026 was the twenty-third monitoring performed pursuant to Milestone 1A-3 of the Compliance Order. The data collected in June 2026 and evaluated for this report are consistent with the data collected in the previous months of August 2024 through May 2026 as well as the data collected and evaluated by Chiquita's technical experts in accordance with the Stipulated Order to assess the Reaction Mitigation Area, including the June 2026 data most recently evaluated on July 10, 2026, as required by Conditions 9(a) and 9(b) of the Stipulated Order, most recently modified on June 3, 2026. (See **Attachment E**.)

For the reasons described in the attached revised Reaction Mitigation Area boundary determination, initially submitted on July 10, 2026 and revised on July 15, 2026, the Reaction Mitigation Area has been adjusted to include the following changes:

- Grid No. 81 is positioned immediately east of and adjacent to Grid No. 149, south of and adjacent to Grid No. 53, and north of and adjacent to Grid No. 82, all three of which were included in last month's Reaction Mitigation Area boundary. Accordingly, Grid No. 81 is being incorporated in the Reaction Mitigation Area boundary for this month as a contiguous surface grid based on the temperature, poor LFG quality, CO concentration, and H_2 concentration at well CV-2551.

- Grid No. 182 is positioned immediately northwest of and adjacent to Grid No. 181, and southwest and adjacent to Grid No. 183, both of which were included in last month's Reaction Area boundary. Accordingly, Grid No. 182 is being incorporated in the Reaction Mitigation Area boundary for this month as a contiguous surface grid based on the poor LFG quality at wells CV-1901, CV-2336, and CV-24141.

- In addition, Grid No. 41 was included in last month's Reaction Area boundary as a non-contiguous grid. Although the grid contains one well that exhibited the poor LFG quality criterium and the H_2 criterium, there was no third parameter as required by Condition No. 9b. Accordingly, Grid No. 41 is being removed from the Reaction Mitigation Area boundary for the month of June as a non-contiguous surface grid.

As liquid levels decrease due to current restart and installation of multiple Lorentz Electric and Pneumatic Pumps, we have seen the percentages of Permanent Gases, Carbon Monoxide, and Hydrogen and temperatures change as these gases move towards the extraction wells for removal. This continues to be demonstrated by the multiscale well graphics included in **Attachment D**, which includes graphics on permanent gases, temperature, and other trends over a twelve (12)-month period. Note that these graphs were created using standard landfill gas monitoring equipment and the results do not contain laboratory data. SCS has also included separate Hydrogen and Carbon Monoxide graphs using laboratory results for your use and review for each well.

Additionally, the installation of larger diameter piping has improved the collection of additional gases throughout the Landfill. Since March 2025, the flow rates of landfill gas being combusted by the abatement devices have ranged from 13,500 cfm to 17,500 cfm. During June 2026, the overall gas extraction from the Landfill was approximately 701,308,800 cubic feet. June's daily landfill gas extraction rate was the highest to date due to the gas collection and control system upgrades, increased liquid removal and start-up of the additional thermal oxidizers. Future increases of this extraction rate may occur, however, the Landfill is approaching the theoretical maximum gas generation rates. SCS will continue to maximize gas and heat extraction as the collection systems continue to expand and as the gas composition of the wells in the Reaction Mitigation Area changes as more vacuum, liquid removal, and resulting movement of gas allows more reaction and normal landfill gas to be extracted.

Chiquita will continue to evaluate the data in future monthly reports as additional data is collected.

Milestone 5 Compliance Items

This report includes in **Attachment D** individual maps overlayed with the following data for June 2026 in an easily understood format, in accordance with Milestone 5 of the Compliance Order:

- Defined Reaction Mitigation Area;
- Expansion of Reaction Mitigation Area, if any;
- Weekly TMP data; and
- LFG data including, but not limited to, CH4, CO2, O2, Temperature, CO, and H2 data.

Milestone 5 also requires "settlement with heat maps," but as discussed earlier in this report and in accordance with LEA correspondence dated November 27 and December 3, 2024, this requirement is satisfied by Chiquita's submittal of its monthly isopach maps to the LEA, which was done on July 14, 2026. For the LEA's convenience, the June 2026 isopach map is included herein as **Attachment F**.

The signatories below are a licensed professional/senior VP, the site project manager, and a Regional Manager VP of SCS Engineers.

Sincerely,

Rachelle Huber
Project Manager
SCS Engineers

Arthur E Jones Jr
Vice President
SCS Engineers

Jenny Kim, P.E.
Project Manager
SCS Engineers

Attachments:

Attachment A – Laboratory Analysis and LFG Extraction Well Instrument and Temperature Data

Attachment B – Down Well Temperatures and List of Wells for Monitoring
Attachment C – Item 7 - Well Location Map
Attachment D – Milestone 5 Compliance Data
Attachment E – July 15, 2026 Revised Reaction Mitigation Area Report
Attachment F – June 2026 Isopach Map

Electronic Data of Laboratory Results and Extraction Well data are in Excel format, with additional PDFs for gas well data.

cc: John Perkey, Chiquita Canyon
Kevin Green, Chiquita Canyon
William Haley, Chiquita Canyon
Dylan Smith, Chiquita Canyon
Sarah Phillips, Chiquita Canyon
Pat Sullivan, SCS Engineers
Liza Frias, Los Angeles County Department of Public Health
Nichole Quick, M.D., Los Angeles County Department of Public Health
Beverly Tway, Los Angeles County LEA
Eric Morofuji, Los Angeles County LEA
Renee Jensen, LEA Counsel
Blaine McPhillips, Senior Deputy County Counsel
Emiko Thompson, Los Angeles County Department of Public Works
Alex Garcia, Los Angeles County Department of Regional Planning
Phillip Chen, Los Angeles County Department of Regional Planning
Steven Jareb, Los Angeles County Department of Regional Planning
Wes Mindermann, CalRecycle
Todd Thalhamer, CalRecycle
Emel Wadhwani, CalRecycle
Jeff Linberg, California Air Recourses Board
Nancy Fletcher, California Air Recourses Board
Jack Cheng, South Coast Air Quality Management Board
Larry Israel, South Coast Air Quality Management Board
Enrique Casas, Los Angeles Regional Water Quality Control Board
Joshua Wirtschafter, United States Environmental Protection Agency
Laura Friedli, United States Environmental Protection Agency
Tyler Holybee, United States Environmental Protection Agency
Mark Anthony Relon, United States Environmental Protection Agency
Gregory Schaffer, Department of Toxic Substances Control
Natasha DiPietro, Department of Toxic Substances Control
Gregory Gentile, Department of Toxic Substances Control

Attachment A

Laboratory Analysis

And

LFG Extraction Well Instrument and Temperature Data

SGS

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175

TX Cert T104704450-14-6
EPA Methods TO14A, TO15

ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

June 10, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T060110-01/10

Enclosed are the results for sample(s) received 6/1/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐ No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐ No ☐
Other:				Level 4	☐	Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:

Bill to: 07FSAccountspayable@scsengineers.com
3900 Kilroy Airport Way, Suite 300
Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T060110-01	CV-2351	06/01/26	9:00AM	2-1L	Gas	N	X	X	X	X		
-02	CV-24143	06/01/26	9:05AM	2-1L	Gas	N	X	X	X	X		
-03	CV-2352	06/01/26	9:10AM	1L	Gas	N	X	X	X			
-04	CV-24140	06/01/26	9:15AM	2-1L	Gas	N	X	X	X	X		
-05	CV-24139	06/01/26	9:20AM	2-1L	Gas	N	X	X	X	X		
-06	CV-24138	06/01/26	9:25AM	2-1L	Gas	N	X	X	X	X		
-07	CV-24144	06/01/26	9:30AM	1L	Gas	N	X					
-08	CV-24099	06/01/26	9:35AM	1L	Gas	N	X					
-09	CV-24100	06/01/26	9:40AM	1L	Gas	N	X	X	X			
-10	CV-24102	06/01/26	9:50AM	1L	Gas	N	X					

AUTHORIZATION TO PERFORM WORK	COMPANY SCS	DATE/TIME	
SAMPLED BY Victor Amaya	COMPANY SCS	DATE/TIME 6/1/26	
RELINQUISHED BY	DATE/TIME 6/1/26 11:25 AM	RECEIVED BY Fedex 6	DATE/TIME 6/1/26 11:26 AM
RELINQUISHED BY Fedex 6	DATE/TIME 6/1/26 12:45 PM	RECEIVED BY	DATE/TIME 6/1/26 12:45
RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

*TO15 cancelled HO 6/10/26

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/01/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T060110-01		T060110-02		T060110-03		T060110-04	
Client Sample I.D.:	CV-2351		CV-24143		CV-2352		CV-24140	
Date/Time Sampled:	6/1/26 9:00		6/1/26 9:05		6/1/26 9:10		6/1/26 9:15	
Date/Time Analyzed:	6/1/26 16:41		6/1/26 16:56		6/1/26 17:10		6/1/26 17:25	
QC Batch No.:	260601GC8A1		260601GC8A1		260601GC8A1		260601GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	17	10	690	10	630	10	1,100	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 6-10-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com

Member of the SGS Group (SGS SA)

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/01/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T060110-05		T060110-06		T060110-09			
Client Sample I.D.:	CV-24139		CV-24138		CV-24100			
Date/Time Sampled:	6/1/26 9:20		6/1/26 9:25		6/1/26 9:40			
Date/Time Analyzed:	6/1/26 17:39		6/1/26 17:54		6/1/26 18:38			
QC Batch No.:	260601GC8A1		260601GC8A1		260601GC8A1			
Analyst Initials:	KD		KD		KD			
Dilution Factor:	1.0		1.0		1.0			
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv		
Carbon Monoxide	ND	10	740	10	42	10		

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 6-10-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com
* Member of the SGS Group (SGS SA)

QC Batch No: 260601GC8A1
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	6/1/26 16:26			6/1/26 14:05		6/1/26 14:20					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,210	120	1,200	119	0.7	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 6-10-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/01/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T060110-01			T060110-02			T060110-03			T060110-04		
Client Sample I.D.:	CV-2351			CV-24143			CV-2352			CV-24140		
Date/Time Sampled:	6/1/26 9:00			6/1/26 9:05			6/1/26 9:10			6/1/26 9:15		
Date/Time Analyzed:	6/1/26 16:41			6/1/26 16:56			6/1/26 17:10			6/1/26 17:25		
QC Batch No.:	260601GC8A1			260601GC8A1			260601GC8A1			260601GC8A1		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	0.17 J	1.0	0.059	8.8	1.0	0.059	10	1.0	0.059	22	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 6-10-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/01/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T060110-05			T060110-06			T060110-09					
Client Sample I.D.:	CV-24139			CV-24138			CV-24100					
Date/Time Sampled:	6/1/26 9:20			6/1/26 9:25			6/1/26 9:40					
Date/Time Analyzed:	6/1/26 17:39			6/1/26 17:54			6/1/26 18:38					
QC Batch No.:	260601GC8A1			260601GC8A1			260601GC8A1					
Analyst Initials:	KD			KD			KD					
Dilution Factor:	1.0			1.0			1.0					
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v			
Hydrogen	0.96 J	1.0	0.059	18	1.0	0.059	0.67 J	1.0	0.059			

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 6-10-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260601GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	6/1/26 16:26				6/1/26 14:05		6/1/26 14:20					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	5.17	104	5.11	103	1.1	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 6-10-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/01/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T060110-01		T060110-02		T060110-03		T060110-04	
Client Sample I.D.:	CV-2351		CV-24143		CV-2352		CV-24140	
Date/Time Sampled:	6/1/26 9:00		6/1/26 9:05		6/1/26 9:10		6/1/26 9:15	
Date/Time Analyzed:	6/1/26 16:41		6/1/26 16:56		6/1/26 17:10		6/1/26 17:25	
QC Batch No.:	260601GC8A1		260601GC8A1		260601GC8A1		260601GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	0.24	0.010	31	0.010	40	0.010	65	0.010
Oxygen/Argon	21	0.50	12	0.50	9.0	0.50	2.0	0.50
Nitrogen	78	1.0	46	1.0	36	1.0	7.4	1.0
Methane	0.0042	0.0010	0.85	0.0010	0.90	0.0010	1.9	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6-10-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/01/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T060110-05		T060110-06		T060110-07		T060110-08	
Client Sample I.D.:	CV-24139		CV-24138		CV-24144		CV-24099	
Date/Time Sampled:	6/1/26 9:20		6/1/26 9:25		6/1/26 9:30		6/1/26 9:35	
Date/Time Analyzed:	6/1/26 17:39		6/1/26 17:54		6/1/26 18:08		6/1/26 18:23	
QC Batch No.:	260601GC8A1		260601GC8A1		260601GC8A1		260601GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	2.3	0.010	48	0.010	7.7	0.010	76	0.010
Oxygen/Argon	20	0.50	6.5	0.50	17	0.50	0.71	0.50
Nitrogen	75	1.0	24	1.0	64	1.0	2.7	1.0
Methane	0.12	0.0010	1.6	0.0010	11	0.0010	20	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 6-10-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/01/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T060110-09		T060110-10					
Client Sample I.D.:	CV-24100		CV-24102					
Date/Time Sampled:	6/1/26 9:40		6/1/26 9:50					
Date/Time Analyzed:	6/1/26 18:38		6/1/26 18:52					
QC Batch No.:	260601GC8A1		260601GC8A1					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**				
Carbon Dioxide	73	0.010	50	0.010				
Oxygen/Argon	1.2	0.50	1.7	0.50				
Nitrogen	4.5	1.0	6.4	1.0				
Methane	20	0.0010	41	0.0010				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 6-10-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260601GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	6/1/26 16:26			6/1/26 14:05		6/1/26 14:20					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	9.49	95	9.51	95	0.2	70	130	30
Oxygen/Argon	ND	0.50	15	14.4	96	14.5	96	0.0	70	130	30
Nitrogen	ND	1.0	70	69.3	99	69.4	99	0.2	70	130	30
Methane	ND	0.0010	0.10	0.111	109	0.110	109	0.7	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 6-10-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175

TX Cert T104704450-14-6
EPA Methods TO14A, TO15

ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

June 16, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T060204-01/10

Enclosed are the results for sample(s) received 6/2/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags. Acetone required quadratic regression calibration.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME
Standard ■ 48 hours ☐
Same Day ☐ 72 hours ☐
24 hours ☐ 96 hours ☐
Other:

DELIVERABLES
EDD ■
EDF ☐
Level 3 ☐
Level 4 ☐

PAGE: 1 **OF**

Condition upon receipt:
Sealed Yes ☐ No ☐
Intact Yes ☐ No ☐
Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING
P.O. No.:
Bill to: 07FSAccountspayable@scsengineers.com
3900 Kilroy Airport Way, Suite 300
Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T060204-01	CV-2348	06/02/26	7:30AM	1L	Gas	N	X	X	X			
-02	CV-2347	06/02/26	7:40AM	1L	Gas	N	X	X	X			
-03	H-2273W	06/02/26	7:45AM	2-1L	Gas	N	X	X	X	X		
-04	CV-2346	06/02/26	7:50AM	1L	Gas	N	X	X	X			
-05	CV-2345	06/02/26	7:55AM	1L	Gas	N	X	X	X			
-06	CV-2344	06/02/26	8:00AM	1L	Gas	N	X	X	X			
-07	CV-108-52	06/02/26	8:10AM	2-1L	Gas	N	X	X	X	X		
-08	CV-2350	06/02/26	8:15AM	2-1L	Gas	N	X	X	X	X		
-09	CV-2002	06/02/26	8:20AM	2-1L	Gas	N	X	X	X	X		
-10	CV-2349	06/02/26	8:30AM	1L	Gas	N	X	X	X			

AUTHORIZATION TO PERFORM WORK [signature] COMPANY SCS DATE/TIME 6-2-26
SAMPLED BY Erik Navarro COMPANY scs DATE/TIME 6/2/26

RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME
[signature]	6-2-26 9:05a	Ruben G	6/2/26 9:05am
Ruben G	6/2/26 11:35		
		[signature]	6/2/26 11:34

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/02/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T060204-03		T060204-07		T060204-08		T060204-09	
Client Sample I.D.:	H-2273W		CV-108-52		CV-2350		CV-2002	
Date/Time Sampled:	6/2/26 7:45		6/2/26 8:10		6/2/26 8:15		6/2/26 8:20	
Date/Time Analyzed:	6/2/26 20:54		6/2/26 21:31		6/2/26 22:09		6/2/26 22:46	
QC Batch No.:	260602MS2A1		260602MS2A1		260602MS2A1		260602MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	3,000		2,500		15,000		10,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	3,000	ND	2,500	ND	15,000	ND	10,000
Chloromethane	ND	3,000	ND	2,500	ND	15,000	ND	10,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	3,000	ND	2,500	ND	15,000	ND	10,000
Vinyl Chloride	ND	3,000	ND	2,500	ND	15,000	ND	10,000
Bromomethane	ND	3,000	ND	2,500	ND	15,000	ND	10,000
Chloroethane	ND	3,000	ND	2,500	ND	15,000	ND	10,000
Trichlorofluoromethane (11)	ND	3,000	ND	2,500	ND	15,000	ND	10,000
1,1-Dichloroethene	ND	3,000	ND	2,500	ND	15,000	ND	10,000
Carbon Disulfide	3,900	3,000	ND	2,500	ND	15,000	ND	10,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	3,000	ND	2,500	ND	15,000	ND	10,000
Acetone	130,000	3,000	90,000	2,500	190,000	15,000	760,000	10,000
Methylene Chloride	ND	3,000	ND	2,500	ND	15,000	ND	10,000
t-1,2-Dichloroethene	ND	3,000	ND	2,500	ND	15,000	ND	10,000
1,1-Dichloroethane	ND	3,000	ND	2,500	ND	15,000	ND	10,000
Vinyl Acetate	ND	3,000	ND	2,500	ND	15,000	ND	10,000
c-1,2-Dichloroethene	ND	3,000	ND	2,500	ND	15,000	ND	10,000
2-Butanone	110,000	6,000	63,000	5,000	130,000	30,000	520,000	20,000
t-Butyl Methyl Ether (MTBE)	ND	3,000	ND	2,500	ND	15,000	ND	10,000
Chloroform	ND	3,000	ND	2,500	ND	15,000	ND	10,000
1,1,1-Trichloroethane	ND	3,000	ND	2,500	ND	15,000	ND	10,000
Carbon Tetrachloride	ND	3,000	ND	2,500	ND	15,000	ND	10,000
Benzene	77,000	3,000	40,000	2,500	150,000	15,000	190,000	10,000
1,2-Dichloroethane	ND	3,000	ND	2,500	ND	15,000	ND	10,000
Trichloroethene	ND	3,000	ND	2,500	ND	15,000	ND	10,000
1,2-Dichloropropane	ND	3,000	ND	2,500	ND	15,000	ND	10,000
Bromodichloromethane	ND	3,000	ND	2,500	ND	15,000	ND	10,000
c-1,3-Dichloropropene	ND	3,000	ND	2,500	ND	15,000	ND	10,000
4-Methyl-2-Pentanone	ND	3,000	ND	2,500	ND	15,000	ND	10,000
Toluene	4,800	3,000	4,100	2,500	ND	15,000	10,000	10,000
t-1,3-Dichloropropene	ND	3,000	ND	2,500	ND	15,000	ND	10,000
1,1,2-Trichloroethane	ND	3,000	ND	2,500	ND	15,000	ND	10,000
Tetrachloroethene	ND	3,000	ND	2,500	ND	15,000	ND	10,000
2-Hexanone	ND	3,000	ND	2,500	ND	15,000	ND	10,000
Dibromochloromethane	ND	3,000	ND	2,500	ND	15,000	ND	10,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/02/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T060204-03		T060204-07		T060204-08		T060204-09	
Client Sample I.D.:	H-2273W		CV-108-52		CV-2350		CV-2002	
Date/Time Sampled:	6/2/26 7:45		6/2/26 8:10		6/2/26 8:15		6/2/26 8:20	
Date/Time Analyzed:	6/2/26 20:54		6/2/26 21:31		6/2/26 22:09		6/2/26 22:46	
QC Batch No.:	260602MS2A1		260602MS2A1		260602MS2A1		260602MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	3,000		2,500		15,000		10,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	3,000	ND	2,500	ND	15,000	ND	10,000
Chlorobenzene	ND	3,000	ND	2,500	ND	15,000	ND	10,000
Ethylbenzene	ND	3,000	ND	2,500	ND	15,000	ND	10,000
p,&m-Xylene	ND	3,000	ND	2,500	ND	15,000	ND	10,000
o-Xylene	ND	3,000	ND	2,500	ND	15,000	ND	10,000
Styrene	ND	3,000	ND	2,500	ND	15,000	ND	10,000
Bromoform	ND	3,000	ND	2,500	ND	15,000	ND	10,000
1,1,2,2-Tetrachloroethane	ND	3,000	ND	2,500	ND	15,000	ND	10,000
Benzyl Chloride	ND	3,000	ND	2,500	ND	15,000	ND	10,000
4-Ethyl Toluene	ND	3,000	ND	2,500	ND	15,000	ND	10,000
1,3,5-Trimethylbenzene	ND	3,000	ND	2,500	ND	15,000	ND	10,000
1,2,4-Trimethylbenzene	ND	3,000	ND	2,500	ND	15,000	ND	10,000
1,3-Dichlorobenzene	ND	3,000	ND	2,500	ND	15,000	ND	10,000
1,4-Dichlorobenzene	ND	3,000	ND	2,500	ND	15,000	ND	10,000
1,2-Dichlorobenzene	ND	3,000	ND	2,500	ND	15,000	ND	10,000
1,2,4-Trichlorobenzene	ND	3,000	ND	2,500	ND	15,000	ND	10,000
Hexachlorobutadiene	ND	3,000	ND	2,500	ND	15,000	ND	10,000
1,3-Butadiene	ND	15,000	ND	13,000	ND	75,000	ND	50,000
Isopropanol	100,000	15,000	70,000	13,000	160,000	75,000	300,000	50,000
n-Hexane	ND	15,000	18,000	13,000	ND	75,000	ND	50,000
Ethyl Acetate	19,000	15,000	ND	13,000	ND	75,000	66,000	50,000
Tetrahydrofuran	88,000	15,000	58,000	13,000	160,000	75,000	430,000	50,000
Cyclohexane	ND	15,000	ND	13,000	ND	75,000	ND	50,000
Heptane	ND	15,000	ND	13,000	ND	75,000	ND	50,000
1,4-Dioxane	ND	15,000	ND	13,000	ND	75,000	ND	50,000

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ **Date** 6/16/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/02/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK
Client Sample I.D.:	--
Date/Time Sampled:	--
Date/Time Analyzed:	6/2/26 15:08
QC Batch No.:	260602MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	0.20
Chloromethane	ND	0.20
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20
Vinyl Chloride	ND	0.20
Bromomethane	ND	0.20
Chloroethane	ND	0.20
Trichlorofluoromethane (11)	ND	0.20
1,1-Dichloroethene	ND	0.20
Carbon Disulfide	ND	0.20
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20
Acetone	ND	0.20
Methylene Chloride	ND	0.20
t-1,2-Dichloroethene	ND	0.20
1,1-Dichloroethane	ND	0.20
Vinyl Acetate	ND	0.20
c-1,2-Dichloroethene	ND	0.20
2-Butanone	ND	0.40
t-Butyl Methyl Ether (MTBE)	ND	0.20
Chloroform	ND	0.20
1,1,1-Trichloroethane	ND	0.20
Carbon Tetrachloride	ND	0.20
Benzene	ND	0.20
1,2-Dichloroethane	ND	0.20
Trichloroethene	ND	0.20
1,2-Dichloropropane	ND	0.20
Bromodichloromethane	ND	0.20
c-1,3-Dichloropropene	ND	0.20
4-Methyl-2-Pentanone	ND	0.20
Toluene	ND	0.20
t-1,3-Dichloropropene	ND	0.20
1,1,2-Trichloroethane	ND	0.20
Tetrachloroethene	ND	0.20
2-Hexanone	ND	0.20
Dibromochloromethane	ND	0.20

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/02/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK							
Client Sample I.D.:	--							
Date/Time Sampled:	--							
Date/Time Analyzed:	6/2/26 15:08							
QC Batch No.:	260602MS2A1							
Analyst Initials:	VM/GD							
Dilution Factor:	0.20							
ANALYTE	**Result ppbv**	**RL ppbv**						
1,2-Dibromoethane	ND	0.20						
Chlorobenzene	ND	0.20						
Ethylbenzene	ND	0.20						
p,&m-Xylene	ND	0.20						
o-Xylene	ND	0.20						
Styrene	ND	0.20						
Bromoform	ND	0.20						
1,1,2,2-Tetrachloroethane	ND	0.20						
Benzyl Chloride	ND	0.20						
4-Ethyl Toluene	ND	0.20						
1,3,5-Trimethylbenzene	ND	0.20						
1,2,4-Trimethylbenzene	ND	0.20						
1,3-Dichlorobenzene	ND	0.20						
1,4-Dichlorobenzene	ND	0.20						
1,2-Dichlorobenzene	ND	0.20						
1,2,4-Trichlorobenzene	ND	0.20						
Hexachlorobutadiene	ND	0.20						
1,3-Butadiene	ND	1.0						
Isopropanol	ND	1.0						
n-Hexane	ND	1.0						
Ethyl Acetate	ND	1.0						
Tetrahydrofuran	ND	1.0						
Cyclohexane	ND	1.0						
Heptane	ND	1.0						
1,4-Dioxane	ND	1.0						

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ **Date** 06/16/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 260602MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	6/2/26 15:08			6/2/26 13:54		6/2/26 14:31					
Analyst Initials:	VM/GD			VM/GD		VM/GD					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	0.20	10	9.16	92	9.33	93	1.8	70	130	30
Methylene Chloride	ND	0.20	10	8.18	82	8.36	84	2.1	70	130	30
Trichloroethene	ND	0.20	10	9.16	92	9.17	92	0.0	70	130	30
Toluene	ND	0.20	10	8.90	89	8.91	89	0.2	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	7.91	79	8.34	83	5.3	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date: 6/16/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/02/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T060204-01		T060204-02		T060204-03		T060204-04	
Client Sample I.D.:	CV-2348		CV-2347		H-2273W		CV-2346	
Date/Time Sampled:	6/2/26 7:30		6/2/26 7:40		6/2/26 7:45		6/2/26 7:50	
Date/Time Analyzed:	6/2/26 15:55		6/2/26 16:09		6/2/26 16:24		6/2/26 16:38	
QC Batch No.:	260602GC8A1		260602GC8A1		260602GC8A1		260602GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	130	10	1,000	10	240	10	2,700	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 6-10-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com

Member of the SGS Group (SGS SA)

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/02/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T060204-05		T060204-06		T060204-07		T060204-08	
Client Sample I.D.:	CV-2345		CV-2344		CV-108-52		CV-2350	
Date/Time Sampled:	6/2/26 7:55		6/2/26 8:00		6/2/26 8:10		6/2/26 8:15	
Date/Time Analyzed:	6/2/26 16:53		6/2/26 17:07		6/2/26 17:22		6/2/26 17:36	
QC Batch No.:	260602GC8A1		260602GC8A1		260602GC8A1		260602GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	660	10	3,200	10	35	10	3,800	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 6-10-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com

Member of the SGS Group (SGS SA)

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/02/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T060204-09		T060204-10					
Client Sample I.D.:	CV-2002		CV-2349					
Date/Time Sampled:	6/2/26 8:20		6/2/26 8:30					
Date/Time Analyzed:	6/2/26 17:51		6/2/26 18:05					
QC Batch No.:	260602GC8A1		260602GC8A1					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv				
Carbon Monoxide	3,200	10	2,900	10				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6-10-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com
Member of the SGS Group (SGS SA)

QC Batch No: 260602GC8A1
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	6/2/26 14:56			6/2/26 15:25		6/2/26 15:40					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,180	117	1,180	117	0.0	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 6-10-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/02/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T060204-01			T060204-02			T060204-03			T060204-04		
Client Sample I.D.:	CV-2348			CV-2347			H-2273W			CV-2346		
Date/Time Sampled:	6/2/26 7:30			6/2/26 7:40			6/2/26 7:45			6/2/26 7:50		
Date/Time Analyzed:	6/2/26 15:55			6/2/26 16:09			6/2/26 16:24			6/2/26 16:38		
QC Batch No.:	260602GC8A1			260602GC8A1			260602GC8A1			260602GC8A1		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	0.90 J	1.0	0.059	5.5	1.0	0.059	1.6	1.0	0.059	16	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 6-10-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/02/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T060204-05			T060204-06			T060204-07			T060204-08		
Client Sample I.D.:	CV-2345			CV-2344			CV-108-52			CV-2350		
Date/Time Sampled:	6/2/26 7:55			6/2/26 8:00			6/2/26 8:10			6/2/26 8:15		
Date/Time Analyzed:	6/2/26 16:53			6/2/26 17:07			6/2/26 17:22			6/2/26 17:36		
QC Batch No.:	260602GC8A1			260602GC8A1			260602GC8A1			260602GC8A1		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	3.3	1.0	0.059	16	1.0	0.059	0.26 J	1.0	0.059	17	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 6-10-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com
Member of the SGS Group (SGS SA)

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/02/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T060204-09			T060204-10								
Client Sample I.D.:	CV-2002			CV-2349								
Date/Time Sampled:	6/2/26 8:20			6/2/26 8:30								
Date/Time Analyzed:	6/2/26 17:51			6/2/26 18:05								
QC Batch No.:	260602GC8A1			260602GC8A1								
Analyst Initials:	KD			KD								
Dilution Factor:	1.0			1.0								
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v						
Hydrogen	15	1.0	0.059	15	1.0	0.059						

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____
Mark Johnson
Operations Manager

Date 6-10-26

The cover letter is an integral part of this analytical report

SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com
Member of the SGS Group (SGS SA)

QC Batch No: 260602GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	6/2/26 14:56				6/2/26 15:25		6/2/26 15:40					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	4.73	95	4.66	94	1.7	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 6-10-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/02/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T060204-01		T060204-02		T060204-03		T060204-04	
Client Sample I.D.:	CV-2348		CV-2347		H-2273W		CV-2346	
Date/Time Sampled:	6/2/26 7:30		6/2/26 7:40		6/2/26 7:45		6/2/26 7:50	
Date/Time Analyzed:	6/2/26 15:55		6/2/26 16:09		6/2/26 16:24		6/2/26 16:38	
QC Batch No.:	260602GC8A1		260602GC8A1		260602GC8A1		260602GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	35	0.010	57	0.010	51	0.010	72	0.010
Oxygen/Argon	2.0	0.50	1.7	0.50	1.0	0.50	1.5	0.50
Nitrogen	40	1.0	21	1.0	26	1.0	6.4	1.0
Methane	22	0.0010	14	0.0010	20	0.0010	2.0	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 6-10-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/02/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T060204-05		T060204-06		T060204-07		T060204-08	
Client Sample I.D.:	CV-2345		CV-2344		CV-108-52		CV-2350	
Date/Time Sampled:	6/2/26 7:55		6/2/26 8:00		6/2/26 8:10		6/2/26 8:15	
Date/Time Analyzed:	6/2/26 16:53		6/2/26 17:07		6/2/26 17:22		6/2/26 17:36	
QC Batch No.:	260602GC8A1		260602GC8A1		260602GC8A1		260602GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	73	0.010	73	0.010	43	0.010	72	0.010
Oxygen/Argon	1.3	0.50	2.0	0.50	0.96	0.50	1.0	0.50
Nitrogen	7.1	1.0	7.3	1.0	3.6	1.0	3.7	1.0
Methane	15	0.0010	1.0	0.0010	51	0.0010	5.0	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 6-10-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com

Member of the SGS Group (SGS SA)

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/02/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T060204-09		T060204-10					
Client Sample I.D.:	CV-2002		CV-2349					
Date/Time Sampled:	6/2/26 8:20		6/2/26 8:30					
Date/Time Analyzed:	6/2/26 17:51		6/2/26 18:05					
QC Batch No.:	260602GC8A1		260602GC8A1					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**				
Carbon Dioxide	69	0.010	72	0.010				
Oxygen/Argon	0.76	0.50	1.8	0.50				
Nitrogen	2.8	1.0	6.6	1.0				
Methane	9.7	0.0010	1.9	0.0010				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 6-10-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com

Member of the SGS Group (SGS SA)

QC Batch No: 260602GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	6/2/26 14:56			6/2/26 15:25		6/2/26 15:40					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	9.31	93	9.28	93	0.3	70	130	30
Oxygen/Argon	ND	0.50	15	14.7	98	14.7	98	0.1	70	130	30
Nitrogen	ND	1.0	70	70.0	100	70.1	100	0.0	70	130	30
Methane	ND	0.0010	0.10	0.108	107	0.108	107	0.0	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6-10-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175
TX Cert T104704450-14-6
EPA Methods TO14A, TO15
ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

June 29, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T060307-01/10

Enclosed are the results for sample(s) received 6/3/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags. Acetone, 2-butanone, p&m-xylene, and dichlorofluoromethane required quadratic regression calibration.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Zain Khan, Art Jones and Ali Ferrara on 6/26/26.

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐ No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐ No ☐
Other:				Level 4	☐	Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:	
Bill to:	
	07FSAccountspayable@scsengineers.com
	3900 Kilroy Airport Way, Suite 300
	Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T060357-01	CV-2301	06/03/26	7:00AM	2-1L	Gas	N	X	X	X	X		
-02	CV-2302	06/03/26	7:10AM	2-1L	Gas	N	X	X	X	X		
-03	CV-2303	06/03/26	7:15AM	2-1L	Gas	N	X	X	X	X		
-04	CV-2315	06/03/26	7:25AM	2-1L	Gas	N	X	X	X	X		
-05	CV-24053	06/03/26	7:40AM	2-1L	Gas	N	X	X	X	X		
-06	CV-2333	06/03/26	8:00AM	1L	Gas	N	X	X	X			
-07	CV-2334	06/03/26	8:05AM	1L	Gas	N	X	X	X			
-08	CV-24128	06/03/26	8:10AM	1L	Gas	N	X	X	X			
-09	CV-24125	06/03/26	8:20AM	1L	Gas	N	X	X	X			
-10	CV-24123	06/03/26	8:30AM	1L	Gas	N	X					

AUTHORIZATION TO PERFORM WORK	COMPANY SCS			DATE/TIME 6-3-26 8:52a
SAMPLED BY	COMPANY SCS			DATE/TIME 6-3-26 8:52a
RELINQUISHED BY	DATE/TIME 6-3-26 8:52a	RECEIVED BY Rubcon 6		DATE/TIME 6/3/26 9:05
RELINQUISHED BY Rubcon 6	DATE/TIME 6-3-26 12:40	RECEIVED BY		DATE/TIME 6/3/26
RELINQUISHED BY	DATE/TIME	RECEIVED BY		DATE/TIME

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/03/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T060307-01		T060307-02		T060307-03		T060307-04	
Client Sample I.D.:	CV-2301		CV-2302		CV-2303		CV-2315	
Date/Time Sampled:	6/3/26 7:00		6/3/26 7:10		6/3/26 7:15		6/3/26 7:25	
Date/Time Analyzed:	6/3/26 18:16		6/3/26 18:54		6/3/26 19:33		6/3/26 20:12	
QC Batch No.:	260603MS2A1		260603MS2A1		260603MS2A1		260603MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	15,000		2,500		14,000		14,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	15,000	ND	2,500	ND	14,000	ND	14,000
Chloromethane	ND	15,000	ND	2,500	ND	14,000	ND	14,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	15,000	ND	2,500	ND	14,000	ND	14,000
Vinyl Chloride	ND	15,000	ND	2,500	ND	14,000	ND	14,000
Bromomethane	ND	15,000	ND	2,500	ND	14,000	ND	14,000
Chloroethane	ND	15,000	ND	2,500	ND	14,000	ND	14,000
Trichlorofluoromethane (11)	ND	15,000	ND	2,500	ND	14,000	ND	14,000
1,1-Dichloroethene	ND	15,000	ND	2,500	ND	14,000	ND	14,000
Carbon Disulfide	ND	15,000	ND	2,500	ND	14,000	ND	14,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	15,000	ND	2,500	ND	14,000	ND	14,000
Acetone	690,000	15,000	230,000	2,500	1,300,000	14,000	660,000	14,000
Methylene Chloride	ND	15,000	ND	2,500	ND	14,000	ND	14,000
t-1,2-Dichloroethene	ND	15,000	ND	2,500	ND	14,000	ND	14,000
1,1-Dichloroethane	ND	15,000	ND	2,500	ND	14,000	ND	14,000
Vinyl Acetate	ND	15,000	ND	2,500	ND	14,000	ND	14,000
c-1,2-Dichloroethene	ND	15,000	ND	2,500	ND	14,000	ND	14,000
2-Butanone	480,000	30,000	200,000	5,000	820,000	28,000	310,000	28,000
t-Butyl Methyl Ether (MTBE)	ND	15,000	ND	2,500	ND	14,000	ND	14,000
Chloroform	ND	15,000	ND	2,500	ND	14,000	ND	14,000
1,1,1-Trichloroethane	ND	15,000	ND	2,500	ND	14,000	ND	14,000
Carbon Tetrachloride	ND	15,000	ND	2,500	ND	14,000	ND	14,000
Benzene	150,000	15,000	61,000	2,500	140,000	14,000	140,000	14,000
1,2-Dichloroethane	ND	15,000	ND	2,500	ND	14,000	ND	14,000
Trichloroethene	ND	15,000	ND	2,500	ND	14,000	ND	14,000
1,2-Dichloropropane	ND	15,000	ND	2,500	ND	14,000	ND	14,000
Bromodichloromethane	ND	15,000	ND	2,500	ND	14,000	ND	14,000
c-1,3-Dichloropropene	ND	15,000	ND	2,500	ND	14,000	ND	14,000
4-Methyl-2-Pentanone	ND	15,000	2,900	2,500	ND	14,000	ND	14,000
Toluene	18,000	15,000	3,400	2,500	ND	14,000	ND	14,000
t-1,3-Dichloropropene	ND	15,000	ND	2,500	ND	14,000	ND	14,000
1,1,2-Trichloroethane	ND	15,000	ND	2,500	ND	14,000	ND	14,000
Tetrachloroethene	ND	15,000	ND	2,500	ND	14,000	ND	14,000
2-Hexanone	ND	15,000	ND	2,500	ND	14,000	ND	14,000
Dibromochloromethane	ND	15,000	ND	2,500	ND	14,000	ND	14,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/03/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T060307-01		T060307-02		T060307-03		T060307-04	
Client Sample I.D.:	CV-2301		CV-2302		CV-2303		CV-2315	
Date/Time Sampled:	6/3/26 7:00		6/3/26 7:10		6/3/26 7:15		6/3/26 7:25	
Date/Time Analyzed:	6/3/26 18:16		6/3/26 18:54		6/3/26 19:33		6/3/26 20:12	
QC Batch No.:	260603MS2A1		260603MS2A1		260603MS2A1		260603MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	15,000		2,500		14,000		14,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	15,000	ND	2,500	ND	14,000	ND	14,000
Chlorobenzene	ND	15,000	ND	2,500	ND	14,000	ND	14,000
Ethylbenzene	ND	15,000	ND	2,500	ND	14,000	ND	14,000
p,&m-Xylene	ND	15,000	ND	2,500	ND	14,000	ND	14,000
o-Xylene	ND	15,000	ND	2,500	ND	14,000	ND	14,000
Styrene	ND	15,000	ND	2,500	ND	14,000	ND	14,000
Bromoform	ND	15,000	ND	2,500	ND	14,000	ND	14,000
1,1,2,2-Tetrachloroethane	ND	15,000	ND	2,500	ND	14,000	ND	14,000
Benzyl Chloride	ND	15,000	ND	2,500	ND	14,000	ND	14,000
4-Ethyl Toluene	ND	15,000	ND	2,500	ND	14,000	ND	14,000
1,3,5-Trimethylbenzene	ND	15,000	ND	2,500	ND	14,000	ND	14,000
1,2,4-Trimethylbenzene	ND	15,000	ND	2,500	ND	14,000	ND	14,000
1,3-Dichlorobenzene	ND	15,000	ND	2,500	ND	14,000	ND	14,000
1,4-Dichlorobenzene	ND	15,000	ND	2,500	ND	14,000	ND	14,000
1,2-Dichlorobenzene	ND	15,000	ND	2,500	ND	14,000	ND	14,000
1,2,4-Trichlorobenzene	ND	15,000	ND	2,500	ND	14,000	ND	14,000
Hexachlorobutadiene	ND	15,000	ND	2,500	ND	14,000	ND	14,000
1,3-Butadiene	ND	75,000	ND	13,000	ND	70,000	ND	70,000
Isopropanol	140,000	75,000	130,000	13,000	110,000	70,000	71,000	70,000
n-Hexane	ND	75,000	ND	13,000	ND	70,000	ND	70,000
Ethyl Acetate	ND	75,000	14,000	13,000	ND	70,000	ND	70,000
Tetrahydrofuran	330,000	75,000	120,000	13,000	450,000	70,000	210,000	70,000
Cyclohexane	ND	75,000	ND	13,000	ND	70,000	ND	70,000
Heptane	ND	75,000	ND	13,000	ND	70,000	ND	70,000
1,4-Dioxane	ND	75,000	ND	13,000	ND	70,000	ND	70,000

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 6/17/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/03/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T060307-05
Client Sample I.D.:	CV-24053
Date/Time Sampled:	6/3/26 7:40
Date/Time Analyzed:	6/3/26 20:50
QC Batch No.:	260603MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	1,500

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	1,500
Chloromethane	ND	1,500
1,2-Cl-1,1,2,2-F ethane (114)	ND	1,500
Vinyl Chloride	ND	1,500
Bromomethane	ND	1,500
Chloroethane	ND	1,500
Trichlorofluoromethane (11)	ND	1,500
1,1-Dichloroethene	ND	1,500
Carbon Disulfide	2,400	1,500
1,1,2-Cl 1,2,2-F ethane (113)	ND	1,500
Acetone	230,000	1,500
Methylene Chloride	ND	1,500
t-1,2-Dichloroethene	ND	1,500
1,1-Dichloroethane	ND	1,500
Vinyl Acetate	ND	1,500
c-1,2-Dichloroethene	ND	1,500
2-Butanone	230,000	3,000
t-Butyl Methyl Ether (MTBE)	ND	1,500
Chloroform	ND	1,500
1,1,1-Trichloroethane	ND	1,500
Carbon Tetrachloride	ND	1,500
Benzene	44,000	1,500
1,2-Dichloroethane	ND	1,500
Trichloroethene	ND	1,500
1,2-Dichloropropane	ND	1,500
Bromodichloromethane	ND	1,500
c-1,3-Dichloropropene	ND	1,500
4-Methyl-2-Pentanone	3,000	1,500
Toluene	3,700	1,500
t-1,3-Dichloropropene	ND	1,500
1,1,2-Trichloroethane	ND	1,500
Tetrachloroethene	ND	1,500
2-Hexanone	ND	1,500
Dibromochloromethane	ND	1,500

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/03/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T060307-05							
Client Sample I.D.:	CV-24053							
Date/Time Sampled:	6/3/26 7:40							
Date/Time Analyzed:	6/3/26 20:50							
QC Batch No.:	260603MS2A1							
Analyst Initials:	VM/GD							
Dilution Factor:	1,500							
ANALYTE	**Result ppbv**	**RL ppbv**						
1,2-Dibromoethane	ND	1,500						
Chlorobenzene	ND	1,500						
Ethylbenzene	ND	1,500						
p,&m-Xylene	ND	1,500						
o-Xylene	ND	1,500						
Styrene	ND	1,500						
Bromoform	ND	1,500						
1,1,2,2-Tetrachloroethane	ND	1,500						
Benzyl Chloride	ND	1,500						
4-Ethyl Toluene	ND	1,500						
1,3,5-Trimethylbenzene	ND	1,500						
1,2,4-Trimethylbenzene	ND	1,500						
1,3-Dichlorobenzene	ND	1,500						
1,4-Dichlorobenzene	ND	1,500						
1,2-Dichlorobenzene	ND	1,500						
1,2,4-Trichlorobenzene	ND	1,500						
Hexachlorobutadiene	ND	1,500						
1,3-Butadiene	ND	7,500						
Isopropanol	120,000	7,500						
n-Hexane	ND	7,500						
Ethyl Acetate	ND	7,500						
Tetrahydrofuran	120,000	7,500						
Cyclohexane	ND	7,500						
Heptane	ND	7,500						
1,4-Dioxane	ND	7,500						

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 6/17/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/03/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK							
Client Sample I.D.:	--							
Date/Time Sampled:	--							
Date/Time Analyzed:	6/3/26 14:08							
QC Batch No.:	260603MS2A1							
Analyst Initials:	VM/GD							
Dilution Factor:	0.20							

ANALYTE	Result ppbv	RL ppbv						
Dichlorodifluoromethane (12)	ND	0.20						
Chloromethane	ND	0.20						
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20						
Vinyl Chloride	ND	0.20						
Bromomethane	ND	0.20						
Chloroethane	ND	0.20						
Trichlorofluoromethane (11)	ND	0.20						
1,1-Dichloroethene	ND	0.20						
Carbon Disulfide	ND	0.20						
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20						
Acetone	ND	0.20						
Methylene Chloride	ND	0.20						
t-1,2-Dichloroethene	ND	0.20						
1,1-Dichloroethane	ND	0.20						
Vinyl Acetate	ND	0.20						
c-1,2-Dichloroethene	ND	0.20						
2-Butanone	ND	0.40						
t-Butyl Methyl Ether (MTBE)	ND	0.20						
Chloroform	ND	0.20						
1,1,1-Trichloroethane	ND	0.20						
Carbon Tetrachloride	ND	0.20						
Benzene	ND	0.20						
1,2-Dichloroethane	ND	0.20						
Trichloroethene	ND	0.20						
1,2-Dichloropropane	ND	0.20						
Bromodichloromethane	ND	0.20						
c-1,3-Dichloropropene	ND	0.20						
4-Methyl-2-Pentanone	ND	0.20						
Toluene	ND	0.20						
t-1,3-Dichloropropene	ND	0.20						
1,1,2-Trichloroethane	ND	0.20						
Tetrachloroethene	ND	0.20						
2-Hexanone	ND	0.20						
Dibromochloromethane	ND	0.20						

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/03/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK							
Client Sample I.D.:	--							
Date/Time Sampled:	--							
Date/Time Analyzed:	6/3/26 14:08							
QC Batch No.:	260603MS2A1							
Analyst Initials:	VM/GD							
Dilution Factor:	0.20							
ANALYTE	**Result ppbv**	**RL ppbv**						
1,2-Dibromoethane	ND	0.20						
Chlorobenzene	ND	0.20						
Ethylbenzene	ND	0.20						
p,&m-Xylene	ND	0.20						
o-Xylene	ND	0.20						
Styrene	ND	0.20						
Bromoform	ND	0.20						
1,1,2,2-Tetrachloroethane	ND	0.20						
Benzyl Chloride	ND	0.20						
4-Ethyl Toluene	ND	0.20						
1,3,5-Trimethylbenzene	ND	0.20						
1,2,4-Trimethylbenzene	ND	0.20						
1,3-Dichlorobenzene	ND	0.20						
1,4-Dichlorobenzene	ND	0.20						
1,2-Dichlorobenzene	ND	0.20						
1,2,4-Trichlorobenzene	ND	0.20						
Hexachlorobutadiene	ND	0.20						
1,3-Butadiene	ND	1.0						
Isopropanol	ND	1.0						
n-Hexane	ND	1.0						
Ethyl Acetate	ND	1.0						
Tetrahydrofuran	ND	1.0						
Cyclohexane	ND	1.0						
Heptane	ND	1.0						
1,4-Dioxane	ND	1.0						

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 6/17/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 260603MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	6/3/26 14:08			6/3/26 12:16		6/3/26 12:54					
Analyst Initials:	VM/GD			VM/GD		VM/GD					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	0.20	10	11.3	113	11.6	116	3.0	70	130	30
Methylene Chloride	ND	0.20	10	11.5	115	11.7	117	1.6	70	130	30
Trichloroethene	ND	0.20	10	11.5	115	11.6	116	0.9	70	130	30
Toluene	ND	0.20	10	11.7	117	11.6	116	1.1	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	11.7	117	11.6	116	0.4	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date:** 6/17/26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/03/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T060307-01		T060307-02		T060307-03		T060307-04	
Client Sample I.D.:	CV-2301		CV-2302		CV-2303		CV-2315	
Date/Time Sampled:	6/3/26 7:00		6/3/26 7:10		6/3/26 7:15		6/3/26 7:25	
Date/Time Analyzed:	6/3/26 16:55		6/3/26 17:10		6/3/26 17:24		6/3/26 17:39	
QC Batch No.:	260603GC8A1		260603GC8A1		260603GC8A1		260603GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	1,400	10	260	10	2,300	10	2,700	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/03/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T060307-05		T060307-06		T060307-07		T060307-08	
Client Sample I.D.:	CV-24053		CV-2333		CV-2334		CV-24128	
Date/Time Sampled:	6/3/26 7:40		6/3/26 8:00		6/3/26 8:05		6/3/26 8:10	
Date/Time Analyzed:	6/3/26 17:53		6/3/26 18:08		6/3/26 18:22		6/3/26 18:37	
QC Batch No.:	260603GC8A1		260603GC8A1		260603GC8A1		260603GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	110	10	4,200	10	1,200	10	180	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6/6/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/03/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T060307-09							
Client Sample I.D.:	CV-24125							
Date/Time Sampled:	6/3/26 8:20							
Date/Time Analyzed:	6/3/26 18:51							
QC Batch No.:	260603GC8A1							
Analyst Initials:	KD							
Dilution Factor:	1.0							
ANALYTE	Result ppmv	RL ppmv						
Carbon Monoxide	12	10						

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6/26/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260603GC8A1
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	6/3/26 9:26			6/3/26 10:10		6/3/26 10:24					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,170	116	1,170	116	0.1	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 6/6/26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/03/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T060307-01			T060307-02			T060307-03			T060307-04		
Client Sample I.D.:	CV-2301			CV-2302			CV-2303			CV-2315		
Date/Time Sampled:	6/3/26 7:00			6/3/26 7:10			6/3/26 7:15			6/3/26 7:25		
Date/Time Analyzed:	6/3/26 16:55			6/3/26 17:10			6/3/26 17:24			6/3/26 17:39		
QC Batch No.:	260603GC8A1			260603GC8A1			260603GC8A1			260603GC8A1		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	11	1.0	0.059	4.2	1.0	0.059	19	1.0	0.059	12	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 6/26/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/03/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T060307-05			T060307-06			T060307-07			T060307-08		
Client Sample I.D.:	CV-24053			CV-2333			CV-2334			CV-24128		
Date/Time Sampled:	6/3/26 7:40			6/3/26 8:00			6/3/26 8:05			6/3/26 8:10		
Date/Time Analyzed:	6/3/26 17:53			6/3/26 18:08			6/3/26 18:22			6/3/26 18:37		
QC Batch No.:	260603GC8A1			260603GC8A1			260603GC8A1			260603GC8A1		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	0.85 J	1.0	0.059	20	1.0	0.059	3.0	1.0	0.059	1.0	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 6/26/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/03/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T060307-09		
Client Sample I.D.:	CV-24125		
Date/Time Sampled:	6/3/26 8:20		
Date/Time Analyzed:	6/3/26 18:51		
QC Batch No.:	260603GC8A1		
Analyst Initials:	KD		
Dilution Factor:	1.0		

ANALYTE	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	0.10 J	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____
Mark Johnson
Operations Manager

Date 6/26/26

The cover letter is an integral part of this analytical report

QC Batch No: 260603GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	6/3/26 9:26				6/3/26 10:10		6/3/26 10:24					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	4.28	86	4.36	88	1.7	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 6/26/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/03/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T060307-01		T060307-02		T060307-03		T060307-04	
Client Sample I.D.:	CV-2301		CV-2302		CV-2303		CV-2315	
Date/Time Sampled:	6/3/26 7:00		6/3/26 7:10		6/3/26 7:15		6/3/26 7:25	
Date/Time Analyzed:	6/3/26 16:55		6/3/26 17:10		6/3/26 17:24		6/3/26 17:39	
QC Batch No.:	260603GC8A1		260603GC8A1		260603GC8A1		260603GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	60	0.010	46	0.010	66	0.010	73	0.010
Oxygen/Argon	1.3	0.50	1.3	0.50	2.2	0.50	1.8	0.50
Nitrogen	6.2	1.0	6.0	1.0	8.0	1.0	7.1	1.0
Methane	19	0.0010	42	0.0010	2.3	0.0010	5.3	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6/16/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/03/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T060307-05		T060307-06		T060307-07		T060307-08	
Client Sample I.D.:	CV-24053		CV-2333		CV-2334		CV-24128	
Date/Time Sampled:	6/3/26 7:40		6/3/26 8:00		6/3/26 8:05		6/3/26 8:10	
Date/Time Analyzed:	6/3/26 17:53		6/3/26 18:08		6/3/26 18:22		6/3/26 18:37	
QC Batch No.:	260603GC8A1		260603GC8A1		260603GC8A1		260603GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	46	0.010	73	0.010	82	0.010	43	0.010
Oxygen/Argon	1.1	0.50	0.67	0.50	1.8	0.50	2.3	0.50
Nitrogen	16	1.0	2.7	1.0	6.7	1.0	21	1.0
Methane	36	0.0010	1.6	0.0010	5.7	0.0010	33	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6/10/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/03/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T060307-09		T060307-10					
Client Sample I.D.:	CV-24125		CV-24123					
Date/Time Sampled:	6/3/26 8:20		6/3/26 8:30					
Date/Time Analyzed:	6/3/26 18:51		6/3/26 19:06					
QC Batch No.:	260603GC8A1		260603GC8A1					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**				
Carbon Dioxide	52	0.010	59	0.010				
Oxygen/Argon	4.4	0.50	0.52	0.50				
Nitrogen	16	1.0	2.2	1.0				
Methane	27	0.0010	38	0.0010				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6/4/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260603GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	6/3/26 9:26			6/3/26 10:10		6/3/26 10:24					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	9.04	90	9.05	90	0.1	70	130	30
Oxygen/Argon	ND	0.50	15	14.7	98	14.8	98	0.4	70	130	30
Nitrogen	ND	1.0	70	70.0	100	70.3	101	0.5	70	130	30
Methane	ND	0.0010	0.10	0.107	106	0.107	106	0.1	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 6/26/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

June 30, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175

TX Cert T104704450-14-6
EPA Methods TO14A, TO15

ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T060404-01/09

Enclosed are the results for sample(s) received 6/4/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags. Acetone required quadratic regression calibration. Quadratic regression calibration was required for dichlorofluoromethane, acetone, 2-butanone, ethyl acetate, and p,&m-Xylene.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Jenny Kim, Art Jones and Ali Ferrara on 6/29/26.

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐ No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐ No ☐
Other:				Level 4	☐	Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:	
Bill to:	
	07FSAccountspayable@scsengineers.com
	3900 Kilroy Airport Way, Suite 300
	Long Beach, CA 90806-6816

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	ANALYSIS REQUEST: CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T060404-01	CV-99	06/04/26	7:30AM	1L	Gas	N	X	X	X			
-02	CV-113	06/04/26	7:45AM	2-1L	Gas	N	X	X	X	X		
-03	CV-24121	06/04/26	8:00AM	1L	Gas	N	X	X	X			
-04	CV-24122	06/04/26	8:20AM	2-1L	Gas	N	X	X	X	X		
-05	CV-24126	06/04/26	8:50AM	1L	Gas	N	X					
-06	CV-2007	06/04/26	8:55AM	2-1L	Gas	N	X	X	X	X		
-07	CV-24049	06/04/26	9:00AM	1L	Gas	N	X	X	X			
-08	CV-24142	06/04/26	9:05AM	2-1L	Gas	N	X	X	X	X		
-09	CV-24127	06/04/26	9:10AM	2-1L	Gas	N	X	X	X	X		
					Gas	N						

AUTHORIZATION TO PERFORM WORK	COMPANY SCS	DATE/TIME 6-4-26 9:42	
SAMPLED BY	COMPANY SCS	DATE/TIME 6-4-26 9:42	
RELINQUISHED BY	DATE/TIME 6-4-26	RECEIVED BY Ruben G	DATE/TIME 6-4-26 9:43
RELINQUISHED BY Ruben G	DATE/TIME 6/4/26 12:02	RECEIVED BY	DATE/TIME 6/4/26 12:02
RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/04/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T060404-02		T060404-04		T060404-06		T060404-08	
Client Sample I.D.:	CV-113		CV-24122		CV-2007		CV-24142	
Date/Time Sampled:	6/4/26 7:45		6/4/26 8:20		6/4/26 8:55		6/4/26 9:05	
Date/Time Analyzed:	6/4/26 18:15		6/4/26 18:53		6/4/26 19:31		6/4/26 20:10	
QC Batch No.:	260604MS2A1		260604MS2A1		260604MS2A1		260604MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	600		470		7,000		10,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	600	ND	470	ND	7,000	ND	10,000
Chloromethane	ND	600	ND	470	ND	7,000	ND	10,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	600	ND	470	ND	7,000	ND	10,000
Vinyl Chloride	ND	600	ND	470	ND	7,000	ND	10,000
Bromomethane	ND	600	ND	470	ND	7,000	ND	10,000
Chloroethane	ND	600	ND	470	ND	7,000	ND	10,000
Trichlorofluoromethane (11)	ND	600	ND	470	ND	7,000	ND	10,000
1,1-Dichloroethene	ND	600	ND	470	ND	7,000	ND	10,000
Carbon Disulfide	1,600	600	600	470	ND	7,000	ND	10,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	600	ND	470	ND	7,000	ND	10,000
Acetone	54,000	600	38,000	470	400,000	7,000	1,400,000 E	10,000
Methylene Chloride	ND	600	ND	470	ND	7,000	ND	10,000
t-1,2-Dichloroethene	ND	600	ND	470	ND	7,000	ND	10,000
1,1-Dichloroethane	ND	600	ND	470	ND	7,000	ND	10,000
Vinyl Acetate	ND	600	ND	470	ND	7,000	ND	10,000
c-1,2-Dichloroethene	ND	600	ND	470	ND	7,000	ND	10,000
2-Butanone	53,000	1,200	86,000	940	400,000	14,000	1,600,000	20,000
t-Butyl Methyl Ether (MTBE)	ND	600	ND	470	ND	7,000	ND	10,000
Chloroform	ND	600	ND	470	ND	7,000	ND	10,000
1,1,1-Trichloroethane	ND	600	ND	470	ND	7,000	ND	10,000
Carbon Tetrachloride	ND	600	ND	470	ND	7,000	ND	10,000
Benzene	62,000	600	12,000	470	450,000	7,000	320,000	10,000
1,2-Dichloroethane	ND	600	ND	470	ND	7,000	ND	10,000
Trichloroethene	ND	600	ND	470	ND	7,000	ND	10,000
1,2-Dichloropropane	ND	600	ND	470	ND	7,000	ND	10,000
Bromodichloromethane	ND	600	ND	470	ND	7,000	ND	10,000
c-1,3-Dichloropropene	ND	600	ND	470	ND	7,000	ND	10,000
4-Methyl-2-Pentanone	1,700	600	2,500	470	11,000	7,000	16,000	10,000
Toluene	3,000	600	2,300	470	27,000	7,000	23,000	10,000
t-1,3-Dichloropropene	ND	600	ND	470	ND	7,000	ND	10,000
1,1,2-Trichloroethane	ND	600	ND	470	ND	7,000	ND	10,000
Tetrachloroethene	ND	600	ND	470	ND	7,000	ND	10,000
2-Hexanone	ND	600	630	470	ND	7,000	ND	10,000
Dibromochloromethane	ND	600	ND	470	ND	7,000	ND	10,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/04/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T060404-02		T060404-04		T060404-06		T060404-08	
Client Sample I.D.:	CV-113		CV-24122		CV-2007		CV-24142	
Date/Time Sampled:	6/4/26 7:45		6/4/26 8:20		6/4/26 8:55		6/4/26 9:05	
Date/Time Analyzed:	6/4/26 18:15		6/4/26 18:53		6/4/26 19:31		6/4/26 20:10	
QC Batch No.:	260604MS2A1		260604MS2A1		260604MS2A1		260604MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	600		470		7,000		10,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	600	ND	470	ND	7,000	ND	10,000
Chlorobenzene	ND	600	ND	470	ND	7,000	ND	10,000
Ethylbenzene	ND	600	490	470	ND	7,000	ND	10,000
p,&m-Xylene	ND	600	520	470	ND	7,000	ND	10,000
o-Xylene	ND	600	ND	470	ND	7,000	ND	10,000
Styrene	ND	600	ND	470	ND	7,000	ND	10,000
Bromoform	ND	600	ND	470	ND	7,000	ND	10,000
1,1,2,2-Tetrachloroethane	ND	600	ND	470	ND	7,000	ND	10,000
Benzyl Chloride	ND	600	ND	470	ND	7,000	ND	10,000
4-Ethyl Toluene	ND	600	ND	470	ND	7,000	ND	10,000
1,3,5-Trimethylbenzene	ND	600	ND	470	ND	7,000	ND	10,000
1,2,4-Trimethylbenzene	ND	600	ND	470	ND	7,000	ND	10,000
1,3-Dichlorobenzene	ND	600	ND	470	ND	7,000	ND	10,000
1,4-Dichlorobenzene	ND	600	ND	470	ND	7,000	ND	10,000
1,2-Dichlorobenzene	ND	600	ND	470	ND	7,000	ND	10,000
1,2,4-Trichlorobenzene	ND	600	ND	470	ND	7,000	ND	10,000
Hexachlorobutadiene	ND	600	ND	470	ND	7,000	ND	10,000
1,3-Butadiene	7,600	3,000	2,800	2,300	ND	35,000	ND	50,000
Isopropanol	120,000	3,000	57,000	2,300	150,000	35,000	210,000	50,000
n-Hexane	ND	3,000	ND	2,300	ND	35,000	ND	50,000
Ethyl Acetate	8,700	3,000	ND	2,300	ND	35,000	ND	50,000
Tetrahydrofuran	54,000	3,000	35,000	2,300	250,000	35,000	250,000	50,000
Cyclohexane	ND	3,000	ND	2,300	ND	35,000	ND	50,000
Heptane	ND	3,000	ND	2,300	ND	35,000	ND	50,000
1,4-Dioxane	ND	3,000	ND	2,300	ND	35,000	ND	50,000

RL = Reporting Limit
ND = Not Detected (below RL)
E = Estimated. Analyte concentration exceeds upper calibration range.

Reviewed/Approved By: _____ Date 6/25/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/04/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T060404-09
Client Sample I.D.:	CV-24127
Date/Time Sampled:	6/4/26 9:10
Date/Time Analyzed:	6/4/26 20:48
QC Batch No.:	260604MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	10,000

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	10,000
Chloromethane	41,000	10,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	10,000
Vinyl Chloride	ND	10,000
Bromomethane	ND	10,000
Chloroethane	ND	10,000
Trichlorofluoromethane (11)	ND	10,000
1,1-Dichloroethene	ND	10,000
Carbon Disulfide	ND	10,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	10,000
Acetone	1,400,000 E	10,000
Methylene Chloride	ND	10,000
t-1,2-Dichloroethene	ND	10,000
1,1-Dichloroethane	ND	10,000
Vinyl Acetate	ND	10,000
c-1,2-Dichloroethene	ND	10,000
2-Butanone	1,500,000	20,000
t-Butyl Methyl Ether (MTBE)	ND	10,000
Chloroform	ND	10,000
1,1,1-Trichloroethane	ND	10,000
Carbon Tetrachloride	ND	10,000
Benzene	310,000	10,000
1,2-Dichloroethane	ND	10,000
Trichloroethene	ND	10,000
1,2-Dichloropropane	ND	10,000
Bromodichloromethane	ND	10,000
c-1,3-Dichloropropene	ND	10,000
4-Methyl-2-Pentanone	12,000	10,000
Toluene	20,000	10,000
t-1,3-Dichloropropene	ND	10,000
1,1,2-Trichloroethane	ND	10,000
Tetrachloroethene	ND	10,000
2-Hexanone	ND	10,000
Dibromochloromethane	ND	10,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/04/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T060404-09
Client Sample I.D.:	CV-24127
Date/Time Sampled:	6/4/26 9:10
Date/Time Analyzed:	6/4/26 20:48
QC Batch No.:	260604MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	10,000

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	10,000
Chlorobenzene	ND	10,000
Ethylbenzene	ND	10,000
p,&m-Xylene	ND	10,000
o-Xylene	ND	10,000
Styrene	ND	10,000
Bromoform	ND	10,000
1,1,2,2-Tetrachloroethane	ND	10,000
Benzyl Chloride	ND	10,000
4-Ethyl Toluene	ND	10,000
1,3,5-Trimethylbenzene	ND	10,000
1,2,4-Trimethylbenzene	ND	10,000
1,3-Dichlorobenzene	ND	10,000
1,4-Dichlorobenzene	ND	10,000
1,2-Dichlorobenzene	ND	10,000
1,2,4-Trichlorobenzene	ND	10,000
Hexachlorobutadiene	ND	10,000
1,3-Butadiene	ND	50,000
Isopropanol	200,000	50,000
n-Hexane	ND	50,000
Ethyl Acetate	83,000	50,000
Tetrahydrofuran	520,000	50,000
Cyclohexane	ND	50,000
Heptane	ND	50,000
1,4-Dioxane	ND	50,000

RL = Reporting Limit
ND = Not Detected (below RL)
E = Estimated. Analyte concentration exceeds upper calibration range.

Reviewed/Approved By: _____ **Date** 6/25/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/04/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK						
Client Sample I.D.:	--						
Date/Time Sampled:	--						
Date/Time Analyzed:	6/4/26 5:43						
QC Batch No.:	260604MS2A1						
Analyst Initials:	VM/GD						
Dilution Factor:	0.20						

ANALYTE	Result ppbv	RL ppbv						
Dichlorodifluoromethane (12)	ND	0.20						
Chloromethane	ND	0.20						
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20						
Vinyl Chloride	ND	0.20						
Bromomethane	ND	0.20						
Chloroethane	ND	0.20						
Trichlorofluoromethane (11)	ND	0.20						
1,1-Dichloroethene	ND	0.20						
Carbon Disulfide	ND	0.20						
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20						
Acetone	ND	0.20						
Methylene Chloride	ND	0.20						
t-1,2-Dichloroethene	ND	0.20						
1,1-Dichloroethane	ND	0.20						
Vinyl Acetate	ND	0.20						
c-1,2-Dichloroethene	ND	0.20						
2-Butanone	ND	0.40						
t-Butyl Methyl Ether (MTBE)	ND	0.20						
Chloroform	ND	0.20						
1,1,1-Trichloroethane	ND	0.20						
Carbon Tetrachloride	ND	0.20						
Benzene	ND	0.20						
1,2-Dichloroethane	ND	0.20						
Trichloroethene	ND	0.20						
1,2-Dichloropropane	ND	0.20						
Bromodichloromethane	ND	0.20						
c-1,3-Dichloropropene	ND	0.20						
4-Methyl-2-Pentanone	ND	0.20						
Toluene	ND	0.20						
t-1,3-Dichloropropene	ND	0.20						
1,1,2-Trichloroethane	ND	0.20						
Tetrachloroethene	ND	0.20						
2-Hexanone	ND	0.20						
Dibromochloromethane	ND	0.20						

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/04/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK
Client Sample I.D.:	--
Date/Time Sampled:	--
Date/Time Analyzed:	6/4/26 5:43
QC Batch No.:	260604MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	0.20
Chlorobenzene	ND	0.20
Ethylbenzene	ND	0.20
p,&m-Xylene	ND	0.20
o-Xylene	ND	0.20
Styrene	ND	0.20
Bromoform	ND	0.20
1,1,2,2-Tetrachloroethane	ND	0.20
Benzyl Chloride	ND	0.20
4-Ethyl Toluene	ND	0.20
1,3,5-Trimethylbenzene	ND	0.20
1,2,4-Trimethylbenzene	ND	0.20
1,3-Dichlorobenzene	ND	0.20
1,4-Dichlorobenzene	ND	0.20
1,2-Dichlorobenzene	ND	0.20
1,2,4-Trichlorobenzene	ND	0.20
Hexachlorobutadiene	ND	0.20
1,3-Butadiene	ND	1.0
Isopropanol	ND	1.0
n-Hexane	ND	1.0
Ethyl Acetate	ND	1.0
Tetrahydrofuran	ND	1.0
Cyclohexane	ND	1.0
Heptane	ND	1.0
1,4-Dioxane	ND	1.0

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ **Date** 6/5/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 260604MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	6/4/26 5:43			6/4/26 4:27		6/4/26 5:05					
Analyst Initials:	VM/GD			VM/GD		VM/GD					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	0.20	10	11.2	112	11.1	111	1.2	70	130	30
Methylene Chloride	ND	0.20	10	10.9	109	10.3	103	5.9	70	130	30
Trichloroethene	ND	0.20	10	11.3	113	10.9	109	4.0	70	130	30
Toluene	ND	0.20	10	10.5	105	10.3	103	1.8	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	10.5	105	10.5	105	0.0	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date:** 6/5/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/04/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T060404-01		T060404-02		T060404-03		T060404-04	
Client Sample I.D.:	CV-99		CV-113		CV-24121		CV-24122	
Date/Time Sampled:	6/4/26 7:30		6/4/26 7:45		6/4/26 8:00		6/4/26 8:20	
Date/Time Analyzed:	6/4/26 18:05		6/4/26 18:20		6/4/26 18:34		6/4/26 18:49	
QC Batch No.:	260604GC8A2		260604GC8A2		260604GC8A2		260604GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	ND	10	160	10	22	10	ND	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/04/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T060404-06		T060404-07		T060404-08		T060404-09	
Client Sample I.D.:	CV-2007		CV-24049		CV-24142		CV-24127	
Date/Time Sampled:	6/4/26 8:55		6/4/26 9:00		6/4/26 9:05		6/4/26 9:10	
Date/Time Analyzed:	6/4/26 19:18		6/4/26 19:32		6/4/26 19:47		6/4/26 20:02	
QC Batch No.:	260604GC8A2		260604GC8A2		260604GC8A2		260604GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	1,100	10	2,800	10	1,700	10	3,700	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260604GC8A2
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	6/4/26 17:50			6/4/26 16:23		6/4/26 16:38					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,140	113	1,140	113	0.2	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 6/9/26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/04/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T060404-01			T060404-02			T060404-03			T060404-04		
Client Sample I.D.:	CV-99			CV-113			CV-24121			CV-24122		
Date/Time Sampled:	6/4/26 7:30			6/4/26 7:45			6/4/26 8:00			6/4/26 8:20		
Date/Time Analyzed:	6/4/26 18:05			6/4/26 18:20			6/4/26 18:34			6/4/26 18:49		
QC Batch No.:	260604GC8A2			260604GC8A2			260604GC8A2			260604GC8A2		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	0.15 J	1.0	0.059	3.2	1.0	0.059	0.26 J	1.0	0.059	ND	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 6/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/04/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T060404-06			T060404-07			T060404-08			T060404-09		
Client Sample I.D.:	CV-2007			CV-24049			CV-24142			CV-24127		
Date/Time Sampled:	6/4/26 8:55			6/4/26 9:00			6/4/26 9:05			6/4/26 9:10		
Date/Time Analyzed:	6/4/26 19:18			6/4/26 19:32			6/4/26 19:47			6/4/26 20:02		
QC Batch No.:	260604GC8A2			260604GC8A2			260604GC8A2			260604GC8A2		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	6.5	1.0	0.059	16	1.0	0.059	15	1.0	0.059	17	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____
Mark Johnson
Operations Manager

Date 6/9/26

The cover letter is an integral part of this analytical report

QC Batch No: 260604GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	6/4/26 17:50				6/4/26 16:23		6/4/26 16:38					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	3.70	74	3.64	73	1.6	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL

Reviewed/Approved By: _____ **Date** 6/9/26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/04/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T060404-01		T060404-02		T060404-03		T060404-04	
Client Sample I.D.:	CV-99		CV-113		CV-24121		CV-24122	
Date/Time Sampled:	6/4/26 7:30		6/4/26 7:45		6/4/26 8:00		6/4/26 8:20	
Date/Time Analyzed:	6/4/26 18:05		6/4/26 18:20		6/4/26 18:34		6/4/26 18:49	
QC Batch No.:	260604GC8A2		260604GC8A2		260604GC8A2		260604GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	38	0.010	73	0.010	36	0.010	27	0.010
Oxygen/Argon	9.5	0.50	1.4	0.50	9.0	0.50	10	0.50
Nitrogen	35	1.0	5.4	1.0	42	1.0	38	1.0
Methane	17	0.0010	17	0.0010	13	0.0010	25	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6/29/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/04/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T060404-05		T060404-06		T060404-07		T060404-08	
Client Sample I.D.:	CV-24126		CV-2007		CV-24049		CV-24142	
Date/Time Sampled:	6/4/26 8:50		6/4/26 8:55		6/4/26 9:00		6/4/26 9:05	
Date/Time Analyzed:	6/4/26 19:03		6/4/26 19:18		6/4/26 19:32		6/4/26 19:47	
QC Batch No.:	260604GC8A2		260604GC8A2		260604GC8A2		260604GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	72	0.010	73	0.010	75	0.010	72	0.010
Oxygen/Argon	1.2	0.50	0.67	0.50	1.1	0.50	0.93	0.50
Nitrogen	4.4	1.0	2.5	1.0	4.0	1.0	4.0	1.0
Methane	1.8	0.0010	17	0.0010	1.6	0.0010	6.7	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/04/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T060404-09							
Client Sample I.D.:	CV-24127							
Date/Time Sampled:	6/4/26 9:10							
Date/Time Analyzed:	6/4/26 20:02							
QC Batch No.:	260604GC8A2							
Analyst Initials:	KD							
Dilution Factor:	1.0							
ANALYTE	**Result % v/v**	**RL % v/v**						
Carbon Dioxide	74	0.010						
Oxygen/Argon	1.2	0.50						
Nitrogen	4.3	1.0						
Methane	1.5	0.0010						

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260604GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	6/4/26 17:50			6/4/26 16:23		6/4/26 16:38					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	8.60	86	8.62	86	0.2	70	130	30
Oxygen/Argon	ND	0.50	15	15.0	100	15.1	100	0.4	70	130	30
Nitrogen	ND	1.0	70	70.5	101	70.8	101	0.4	70	130	30
Methane	ND	0.0010	0.10	0.105	104	0.105	104	0.3	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 6/9/26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

June 23, 2026

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175

TX Cert T104704450-14-6
EPA Methods TO14A, TO15

ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T060803-01/10

Enclosed are the results for sample(s) received 6/8/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Zain Khan, Art Jones and Ali Ferrara on 6/22/26.

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME: Standard ■ 48 hours ☐ | Same Day ☐ 72 hours ☐ | 24 hours ☐ 96 hours ☐ | Other:

DELIVERABLES: EDD ■ | EDF ☐ | Level 3 ☐ | Level 4 ☐

PAGE: 1 OF

Condition upon receipt: Sealed Yes ☐ No ☐ | Intact Yes ☐ No ☐ | Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:	
Bill to:	07FSAccountspayable@scsengineers.com
	3900 Kilroy Airport Way, Suite 300
	Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T060803-01	CV-24138	06/08/26	7:55aM	2-1L	Gas	N	X	X	X	X		
-02	CV-24139	06/08/26	8:00AM	2-1L	Gas	N	X	X	X	X		
-03	CV-24140	06/08/26	8:05AM	2-1L	Gas	N	X	X	X	X		
-04	CV-24143	06/08/26	8:15AM	2-1L	Gas	N	X	X	X	X		
-05	CV-2351	06/08/26	8:25AM	2-1L	Gas	N	X	X	X	X		
-06	CV-2354	06/08/26	8:45AM	1L	Gas	N	X	X	X			
-07	CV-24066	06/08/26	8:55AM	1L	Gas	N	X	X	X			
-08	CV-2341	06/08/26	9:00AM	1L	Gas	N	X	X	X			
-09	CV-2337	06/08/26	9:10AM	1L	Gas	N	X	X	X			
-10	CV-114	06/08/26	9:20AM	1L	Gas	N	X	X	X			

AUTHORIZATION TO PERFORM WORK	COMPANY	DATE/TIME	
SAMPLED BY: Antonio Ambriz	COMPANY: SCS	DATE/TIME: 6-8-26	
RELINQUISHED BY: Antonio Ambriz DATE/TIME: 6-8-26 9:50am	RECEIVED BY: Ruben G	DATE/TIME: 6/8/26 9:50	
RELINQUISHED BY: Ruben G DATE/TIME: 6-8-26 12:00	RECEIVED BY: DMT	DATE/TIME: 6/8/26 1100	
RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/08/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T060803-01		T060803-02		T060803-03		T060803-04	
Client Sample I.D.:	CV-24138		CV-24139		CV-24140		CV-24143	
Date/Time Sampled:	6/8/26 7:55		6/8/26 8:00		6/8/26 8:05		6/8/26 8:15	
Date/Time Analyzed:	6/9/26 2:10		6/9/26 2:48		6/9/26 3:26		6/9/26 4:04	
QC Batch No.:	260608MS2A1		260608MS2A1		260608MS2A1		260608MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	5,000		1,300		13,000		13,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	5,000	ND	1,300	ND	13,000	ND	13,000
Chloromethane	ND	5,000	ND	1,300	ND	13,000	ND	13,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	5,000	ND	1,300	ND	13,000	ND	13,000
Vinyl Chloride	7,400	5,000	ND	1,300	ND	13,000	ND	13,000
Bromomethane	ND	5,000	ND	1,300	ND	13,000	ND	13,000
Chloroethane	ND	5,000	ND	1,300	ND	13,000	ND	13,000
Trichlorofluoromethane (11)	ND	5,000	ND	1,300	ND	13,000	ND	13,000
1,1-Dichloroethene	ND	5,000	ND	1,300	ND	13,000	ND	13,000
Carbon Disulfide	6,700	5,000	ND	1,300	ND	13,000	ND	13,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	5,000	ND	1,300	ND	13,000	ND	13,000
Acetone	200,000	5,000	210,000 E	1,300	300,000	13,000	660,000	13,000
Methylene Chloride	ND	5,000	ND	1,300	ND	13,000	ND	13,000
t-1,2-Dichloroethene	ND	5,000	ND	1,300	ND	13,000	ND	13,000
1,1-Dichloroethane	ND	5,000	ND	1,300	ND	13,000	ND	13,000
Vinyl Acetate	ND	5,000	ND	1,300	ND	13,000	ND	13,000
c-1,2-Dichloroethene	ND	5,000	ND	1,300	ND	13,000	ND	13,000
2-Butanone	91,000	10,000	180,000	2,600	160,000	26,000	360,000	26,000
t-Butyl Methyl Ether (MTBE)	ND	5,000	ND	1,300	ND	13,000	ND	13,000
Chloroform	ND	5,000	ND	1,300	ND	13,000	ND	13,000
1,1,1-Trichloroethane	ND	5,000	ND	1,300	ND	13,000	ND	13,000
Carbon Tetrachloride	ND	5,000	ND	1,300	ND	13,000	ND	13,000
Benzene	32,000	5,000	21,000	1,300	66,000	13,000	77,000	13,000
1,2-Dichloroethane	ND	5,000	ND	1,300	ND	13,000	ND	13,000
Trichloroethene	ND	5,000	ND	1,300	ND	13,000	ND	13,000
1,2-Dichloropropane	ND	5,000	ND	1,300	ND	13,000	ND	13,000
Bromodichloromethane	ND	5,000	ND	1,300	ND	13,000	ND	13,000
c-1,3-Dichloropropene	ND	5,000	ND	1,300	ND	13,000	ND	13,000
4-Methyl-2-Pentanone	ND	5,000	2,200	1,300	ND	13,000	ND	13,000
Toluene	ND	5,000	2,000	1,300	ND	13,000	ND	13,000
t-1,3-Dichloropropene	ND	5,000	ND	1,300	ND	13,000	ND	13,000
1,1,2-Trichloroethane	ND	5,000	ND	1,300	ND	13,000	ND	13,000
Tetrachloroethene	ND	5,000	ND	1,300	ND	13,000	ND	13,000
2-Hexanone	ND	5,000	ND	1,300	ND	13,000	ND	13,000
Dibromochloromethane	ND	5,000	ND	1,300	ND	13,000	ND	13,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/08/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T060803-01		T060803-02		T060803-03		T060803-04	
Client Sample I.D.:	CV-24138		CV-24139		CV-24140		CV-24143	
Date/Time Sampled:	6/8/26 7:55		6/8/26 8:00		6/8/26 8:05		6/8/26 8:15	
Date/Time Analyzed:	6/9/26 2:10		6/9/26 2:48		6/9/26 3:26		6/9/26 4:04	
QC Batch No.:	260608MS2A1		260608MS2A1		260608MS2A1		260608MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	5,000		1,300		13,000		13,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	5,000	ND	1,300	ND	13,000	ND	13,000
Chlorobenzene	ND	5,000	ND	1,300	ND	13,000	ND	13,000
Ethylbenzene	ND	5,000	ND	1,300	ND	13,000	ND	13,000
p,&m-Xylene	ND	5,000	ND	1,300	ND	13,000	ND	13,000
o-Xylene	ND	5,000	ND	1,300	ND	13,000	ND	13,000
Styrene	ND	5,000	ND	1,300	ND	13,000	ND	13,000
Bromoform	ND	5,000	ND	1,300	ND	13,000	ND	13,000
1,1,2,2-Tetrachloroethane	ND	5,000	ND	1,300	ND	13,000	ND	13,000
Benzyl Chloride	ND	5,000	ND	1,300	ND	13,000	ND	13,000
4-Ethyl Toluene	ND	5,000	ND	1,300	ND	13,000	ND	13,000
1,3,5-Trimethylbenzene	ND	5,000	ND	1,300	ND	13,000	ND	13,000
1,2,4-Trimethylbenzene	ND	5,000	ND	1,300	ND	13,000	ND	13,000
1,3-Dichlorobenzene	ND	5,000	ND	1,300	ND	13,000	ND	13,000
1,4-Dichlorobenzene	ND	5,000	ND	1,300	ND	13,000	ND	13,000
1,2-Dichlorobenzene	ND	5,000	ND	1,300	ND	13,000	ND	13,000
1,2,4-Trichlorobenzene	ND	5,000	ND	1,300	ND	13,000	ND	13,000
Hexachlorobutadiene	ND	5,000	ND	1,300	ND	13,000	ND	13,000
1,3-Butadiene	ND	25,000	ND	6,500	ND	65,000	ND	65,000
Isopropanol	86,000	25,000	71,000	6,500	99,000	65,000	110,000	65,000
n-Hexane	ND	25,000	ND	6,500	ND	65,000	ND	65,000
Ethyl Acetate	ND	25,000	7,700	6,500	ND	65,000	ND	65,000
Tetrahydrofuran	65,000	25,000	100,000	6,500	100,000	65,000	290,000	65,000
Cyclohexane	ND	25,000	ND	6,500	ND	65,000	ND	65,000
Heptane	ND	25,000	ND	6,500	ND	65,000	ND	65,000
1,4-Dioxane	ND	25,000	ND	6,500	ND	65,000	ND	65,000

RL = Reporting Limit
ND = Not Detected (below RL)
E = Estimated. Analyte concentration exceeded upper calibration range.

Reviewed/Approved By: _____ Date 6/22/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/08/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T060803-05
Client Sample I.D.:	CV-2351
Date/Time Sampled:	6/8/26 8:25
Date/Time Analyzed:	6/9/26 4:43
QC Batch No.:	260608MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	3,500

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	3,500
Chloromethane	ND	3,500
1,2-Cl-1,1,2,2-F ethane (114)	ND	3,500
Vinyl Chloride	ND	3,500
Bromomethane	ND	3,500
Chloroethane	ND	3,500
Trichlorofluoromethane (11)	ND	3,500
1,1-Dichloroethene	ND	3,500
Carbon Disulfide	ND	3,500
1,1,2-Cl 1,2,2-F ethane (113)	ND	3,500
Acetone	300,000	3,500
Methylene Chloride	ND	3,500
t-1,2-Dichloroethene	ND	3,500
1,1-Dichloroethane	ND	3,500
Vinyl Acetate	ND	3,500
c-1,2-Dichloroethene	ND	3,500
2-Butanone	210,000	7,000
t-Butyl Methyl Ether (MTBE)	ND	3,500
Chloroform	ND	3,500
1,1,1-Trichloroethane	ND	3,500
Carbon Tetrachloride	ND	3,500
Benzene	29,000	3,500
1,2-Dichloroethane	ND	3,500
Trichloroethene	ND	3,500
1,2-Dichloropropane	ND	3,500
Bromodichloromethane	ND	3,500
c-1,3-Dichloropropene	ND	3,500
4-Methyl-2-Pentanone	ND	3,500
Toluene	ND	3,500
t-1,3-Dichloropropene	ND	3,500
1,1,2-Trichloroethane	ND	3,500
Tetrachloroethene	ND	3,500
2-Hexanone	ND	3,500
Dibromochloromethane	ND	3,500

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/08/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T060803-05
Client Sample I.D.:	CV-2351
Date/Time Sampled:	6/8/26 8:25
Date/Time Analyzed:	6/9/26 4:43
QC Batch No.:	260608MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	3,500

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	3,500
Chlorobenzene	ND	3,500
Ethylbenzene	ND	3,500
p,&m-Xylene	ND	3,500
o-Xylene	ND	3,500
Styrene	ND	3,500
Bromoform	ND	3,500
1,1,2,2-Tetrachloroethane	ND	3,500
Benzyl Chloride	ND	3,500
4-Ethyl Toluene	ND	3,500
1,3,5-Trimethylbenzene	ND	3,500
1,2,4-Trimethylbenzene	ND	3,500
1,3-Dichlorobenzene	ND	3,500
1,4-Dichlorobenzene	ND	3,500
1,2-Dichlorobenzene	ND	3,500
1,2,4-Trichlorobenzene	ND	3,500
Hexachlorobutadiene	ND	3,500
1,3-Butadiene	ND	18,000
Isopropanol	95,000	18,000
n-Hexane	ND	18,000
Ethyl Acetate	ND	18,000
Tetrahydrofuran	160,000	18,000
Cyclohexane	ND	18,000
Heptane	ND	18,000
1,4-Dioxane	ND	18,000

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 6/12/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/08/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK							
Client Sample I.D.:	--							
Date/Time Sampled:	--							
Date/Time Analyzed:	6/9/26 1:32							
QC Batch No.:	260608MS2A1							
Analyst Initials:	VM/GD							
Dilution Factor:	0.20							

ANALYTE	Result ppbv	RL ppbv						
Dichlorodifluoromethane (12)	ND	0.20						
Chloromethane	ND	0.20						
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20						
Vinyl Chloride	ND	0.20						
Bromomethane	ND	0.20						
Chloroethane	ND	0.20						
Trichlorofluoromethane (11)	ND	0.20						
1,1-Dichloroethene	ND	0.20						
Carbon Disulfide	ND	0.20						
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20						
Acetone	ND	0.20						
Methylene Chloride	ND	0.20						
t-1,2-Dichloroethene	ND	0.20						
1,1-Dichloroethane	ND	0.20						
Vinyl Acetate	ND	0.20						
c-1,2-Dichloroethene	ND	0.20						
2-Butanone	ND	0.40						
t-Butyl Methyl Ether (MTBE)	ND	0.20						
Chloroform	ND	0.20						
1,1,1-Trichloroethane	ND	0.20						
Carbon Tetrachloride	ND	0.20						
Benzene	ND	0.20						
1,2-Dichloroethane	ND	0.20						
Trichloroethene	ND	0.20						
1,2-Dichloropropane	ND	0.20						
Bromodichloromethane	ND	0.20						
c-1,3-Dichloropropene	ND	0.20						
4-Methyl-2-Pentanone	ND	0.20						
Toluene	ND	0.20						
t-1,3-Dichloropropene	ND	0.20						
1,1,2-Trichloroethane	ND	0.20						
Tetrachloroethene	ND	0.20						
2-Hexanone	ND	0.20						
Dibromochloromethane	ND	0.20						

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/08/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK
Client Sample I.D.:	--
Date/Time Sampled:	--
Date/Time Analyzed:	6/9/26 1:32
QC Batch No.:	260608MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	0.20
Chlorobenzene	ND	0.20
Ethylbenzene	ND	0.20
p,&m-Xylene	ND	0.20
o-Xylene	ND	0.20
Styrene	ND	0.20
Bromoform	ND	0.20
1,1,2,2-Tetrachloroethane	ND	0.20
Benzyl Chloride	ND	0.20
4-Ethyl Toluene	ND	0.20
1,3,5-Trimethylbenzene	ND	0.20
1,2,4-Trimethylbenzene	ND	0.20
1,3-Dichlorobenzene	ND	0.20
1,4-Dichlorobenzene	ND	0.20
1,2-Dichlorobenzene	ND	0.20
1,2,4-Trichlorobenzene	ND	0.20
Hexachlorobutadiene	ND	0.20
1,3-Butadiene	ND	1.0
Isopropanol	ND	1.0
n-Hexane	ND	1.0
Ethyl Acetate	ND	1.0
Tetrahydrofuran	ND	1.0
Cyclohexane	ND	1.0
Heptane	ND	1.0
1,4-Dioxane	ND	1.0

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 6/22/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 260608MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	6/9/26 1:32			6/8/26 23:37		6/9/26 0:15					
Analyst Initials:	VM/GD			VM/GD		VM/GD					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	0.20	10	11.5	115	11.5	115	0.1	70	130	30
Methylene Chloride	ND	0.20	10	11.5	115	11.3	113	1.2	70	130	30
Trichloroethene	ND	0.20	10	11.4	114	10.9	109	4.1	70	130	30
Toluene	ND	0.20	10	11.2	112	11.2	112	0.7	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	10.4	104	10.6	106	1.8	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date: 6/10/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

June 23, 2026

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175

TX Cert T104704450-14-6
EPA Methods TO14A, TO15

ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T060903-01/07

Enclosed are the results for sample(s) received 6/9/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Jenny Kim, Art Jones and Ali Ferrara on 6/22/26.

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME: Standard ■ 48 hours ☐ | Same Day ☐ 72 hours ☐ | 24 hours ☐ 96 hours ☐ | Other:

DELIVERABLES: EDD ■ | EDF ☐ | Level 3 ☐ | Level 4 ☐

PAGE: 1 **OF**

Condition upon receipt: Sealed Yes ☐ No ☐ | Intact Yes ☐ No ☐ | Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:	
Bill to:	07FSAccountspayable@scsengineers.com
	3900 Kilroy Airport Way, Suite 300
	Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T060903-01	CV-1902A 6/9/26	06/08/26	7:45AM	2-1L	Gas	N	X	X	X	X		
-02	CV-1532A	06/09/26	8:05AM	2-1L	Gas	N	X	X	X	X		
-03	CV-2001	06/08/26	8:15AM	2-1L	Gas	N	X	X	X	X		
-04	CV-2353	06/09/26	8:20AM	1L	Gas	N	X	X	X			
-05	CV-24095	06/08/26	8:40AM	2-1L	Gas	N	X	X	X	X		
-06	CV-24069	06/09/26	9:00AM	1L	Gas	N	X	X	X			
-07	CV-24101	06/10/26	8:25AM	2-1L	Gas	N	X	X	X	X		
	HW 6/11/26				Gas	N						
					Gas	N						
					Gas	N						

AUTHORIZATION TO PERFORM WORK	COMPANY SCS	DATE/TIME 9:45 6-9-26	
SAMPLED BY	COMPANY SCS	DATE/TIME 9:45 6-9-26	
RELINQUISHED BY	DATE/TIME 6-9-26 9:45	RECEIVED BY Ruben G	DATE/TIME 6-9-26 9:45
RELINQUISHED BY Ruben G	DATE/TIME 6-9-26 12:20	RECEIVED BY [signature]	DATE/TIME 6/9/26 12:20
RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/09/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T060903-01		T060903-02		T060903-03		T060903-05	
Client Sample I.D.:	CV-1902A		CV-1532A		CV-2001		CV-24095	
Date/Time Sampled:	6/9/26 7:45		6/9/26 8:05		6/9/26 8:15		6/9/26 8:40	
Date/Time Analyzed:	6/9/26 19:09		6/9/26 19:47		6/9/26 20:26		6/9/26 21:05	
QC Batch No.:	260609MS2A1		260609MS2A1		260609MS2A1		260609MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	25,000		5,000		6,000		10,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	25,000	ND	5,000	ND	6,000	ND	10,000
Chloromethane	ND	25,000	ND	5,000	ND	6,000	12,000	10,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	25,000	ND	5,000	ND	6,000	ND	10,000
Vinyl Chloride	180,000	25,000	ND	5,000	ND	6,000	ND	10,000
Bromomethane	ND	25,000	ND	5,000	ND	6,000	ND	10,000
Chloroethane	ND	25,000	ND	5,000	ND	6,000	ND	10,000
Trichlorofluoromethane (11)	ND	25,000	ND	5,000	ND	6,000	ND	10,000
1,1-Dichloroethene	28,000	25,000	ND	5,000	ND	6,000	ND	10,000
Carbon Disulfide	ND	25,000	ND	5,000	ND	6,000	ND	10,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	25,000	ND	5,000	ND	6,000	ND	10,000
Acetone	950,000	25,000	440,000	5,000	110,000	6,000	750,000	10,000
Methylene Chloride	ND	25,000	ND	5,000	ND	6,000	ND	10,000
t-1,2-Dichloroethene	26,000	25,000	ND	5,000	ND	6,000	ND	10,000
1,1-Dichloroethane	60,000	25,000	ND	5,000	ND	6,000	ND	10,000
Vinyl Acetate	ND	25,000	ND	5,000	ND	6,000	ND	10,000
c-1,2-Dichloroethene	ND	25,000	ND	5,000	ND	6,000	ND	10,000
2-Butanone	530,000	50,000	380,000	10,000	86,000	12,000	440,000	20,000
t-Butyl Methyl Ether (MTBE)	ND	25,000	ND	5,000	ND	6,000	ND	10,000
Chloroform	ND	25,000	ND	5,000	ND	6,000	ND	10,000
1,1,1-Trichloroethane	ND	25,000	ND	5,000	ND	6,000	ND	10,000
Carbon Tetrachloride	ND	25,000	ND	5,000	ND	6,000	ND	10,000
Benzene	190,000	25,000	110,000	5,000	47,000	6,000	160,000	10,000
1,2-Dichloroethane	ND	25,000	ND	5,000	ND	6,000	ND	10,000
Trichloroethene	60,000	25,000	ND	5,000	ND	6,000	ND	10,000
1,2-Dichloropropane	ND	25,000	ND	5,000	ND	6,000	ND	10,000
Bromodichloromethane	ND	25,000	ND	5,000	ND	6,000	ND	10,000
c-1,3-Dichloropropene	ND	25,000	ND	5,000	ND	6,000	ND	10,000
4-Methyl-2-Pentanone	ND	25,000	6,900	5,000	ND	6,000	ND	10,000
Toluene	ND	25,000	40,000	5,000	20,000	6,000	ND	10,000
t-1,3-Dichloropropene	ND	25,000	ND	5,000	ND	6,000	ND	10,000
1,1,2-Trichloroethane	ND	25,000	ND	5,000	ND	6,000	ND	10,000
Tetrachloroethene	86,000	25,000	ND	5,000	ND	6,000	ND	10,000
2-Hexanone	ND	25,000	ND	5,000	ND	6,000	ND	10,000
Dibromochloromethane	ND	25,000	ND	5,000	ND	6,000	ND	10,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/09/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T060903-01		T060903-02		T060903-03		T060903-05	
Client Sample I.D.:	CV-1902A		CV-1532A		CV-2001		CV-24095	
Date/Time Sampled:	6/9/26 7:45		6/9/26 8:05		6/9/26 8:15		6/9/26 8:40	
Date/Time Analyzed:	6/9/26 19:09		6/9/26 19:47		6/9/26 20:26		6/9/26 21:05	
QC Batch No.:	260609MS2A1		260609MS2A1		260609MS2A1		260609MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	25,000		5,000		6,000		10,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	25,000	ND	5,000	ND	6,000	ND	10,000
Chlorobenzene	34,000	25,000	ND	5,000	ND	6,000	ND	10,000
Ethylbenzene	ND	25,000	12,000	5,000	ND	6,000	ND	10,000
p,&m-Xylene	ND	25,000	23,000	5,000	7,900	6,000	ND	10,000
o-Xylene	ND	25,000	9,300	5,000	ND	6,000	ND	10,000
Styrene	ND	25,000	ND	5,000	ND	6,000	ND	10,000
Bromoform	ND	25,000	ND	5,000	ND	6,000	ND	10,000
1,1,2,2-Tetrachloroethane	ND	25,000	ND	5,000	ND	6,000	ND	10,000
Benzyl Chloride	ND	25,000	ND	5,000	ND	6,000	ND	10,000
4-Ethyl Toluene	ND	25,000	ND	5,000	ND	6,000	ND	10,000
1,3,5-Trimethylbenzene	ND	25,000	ND	5,000	ND	6,000	ND	10,000
1,2,4-Trimethylbenzene	ND	25,000	ND	5,000	ND	6,000	ND	10,000
1,3-Dichlorobenzene	ND	25,000	ND	5,000	ND	6,000	ND	10,000
1,4-Dichlorobenzene	ND	25,000	ND	5,000	ND	6,000	ND	10,000
1,2-Dichlorobenzene	ND	25,000	ND	5,000	ND	6,000	ND	10,000
1,2,4-Trichlorobenzene	ND	25,000	ND	5,000	ND	6,000	ND	10,000
Hexachlorobutadiene	ND	25,000	ND	5,000	ND	6,000	ND	10,000
1,3-Butadiene	ND	130,000	ND	25,000	ND	30,000	ND	50,000
Isopropanol	130,000	130,000	140,000	25,000	100,000	30,000	150,000	50,000
n-Hexane	ND	130,000	ND	25,000	ND	30,000	ND	50,000
Ethyl Acetate	ND	130,000	ND	25,000	ND	30,000	ND	50,000
Tetrahydrofuran	310,000	130,000	210,000	25,000	41,000	30,000	320,000	50,000
Cyclohexane	ND	130,000	ND	25,000	ND	30,000	ND	50,000
Heptane	ND	130,000	ND	25,000	ND	30,000	ND	50,000
1,4-Dioxane	ND	130,000	ND	25,000	ND	30,000	ND	50,000

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 6/17/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/09/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T060903-07
Client Sample I.D.:	CV-24101
Date/Time Sampled:	6/9/26 8:25
Date/Time Analyzed:	6/9/26 21:44
QC Batch No.:	260609MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	3,600

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	3,600
Chloromethane	ND	3,600
1,2-Cl-1,1,2,2-F ethane (114)	ND	3,600
Vinyl Chloride	ND	3,600
Bromomethane	ND	3,600
Chloroethane	ND	3,600
Trichlorofluoromethane (11)	ND	3,600
1,1-Dichloroethene	ND	3,600
Carbon Disulfide	ND	3,600
1,1,2-Cl 1,2,2-F ethane (113)	ND	3,600
Acetone	180,000	3,600
Methylene Chloride	ND	3,600
t-1,2-Dichloroethene	ND	3,600
1,1-Dichloroethane	ND	3,600
Vinyl Acetate	ND	3,600
c-1,2-Dichloroethene	ND	3,600
2-Butanone	130,000	7,200
t-Butyl Methyl Ether (MTBE)	ND	3,600
Chloroform	ND	3,600
1,1,1-Trichloroethane	ND	3,600
Carbon Tetrachloride	ND	3,600
Benzene	14,000	3,600
1,2-Dichloroethane	ND	3,600
Trichloroethene	ND	3,600
1,2-Dichloropropane	ND	3,600
Bromodichloromethane	ND	3,600
c-1,3-Dichloropropene	ND	3,600
4-Methyl-2-Pentanone	ND	3,600
Toluene	17,000	3,600
t-1,3-Dichloropropene	ND	3,600
1,1,2-Trichloroethane	ND	3,600
Tetrachloroethene	ND	3,600
2-Hexanone	ND	3,600
Dibromochloromethane	ND	3,600

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/09/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T060903-07
Client Sample I.D.:	CV-24101
Date/Time Sampled:	6/9/26 8:25
Date/Time Analyzed:	6/9/26 21:44
QC Batch No.:	260609MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	3,600

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	3,600
Chlorobenzene	ND	3,600
Ethylbenzene	4,000	3,600
p,&m-Xylene	7,400	3,600
o-Xylene	3,800	3,600
Styrene	ND	3,600
Bromoform	ND	3,600
1,1,2,2-Tetrachloroethane	ND	3,600
Benzyl Chloride	ND	3,600
4-Ethyl Toluene	ND	3,600
1,3,5-Trimethylbenzene	ND	3,600
1,2,4-Trimethylbenzene	ND	3,600
1,3-Dichlorobenzene	ND	3,600
1,4-Dichlorobenzene	ND	3,600
1,2-Dichlorobenzene	ND	3,600
1,2,4-Trichlorobenzene	ND	3,600
Hexachlorobutadiene	ND	3,600
1,3-Butadiene	ND	18,000
Isopropanol	60,000	18,000
n-Hexane	ND	18,000
Ethyl Acetate	ND	18,000
Tetrahydrofuran	54,000	18,000
Cyclohexane	ND	18,000
Heptane	ND	18,000
1,4-Dioxane	ND	18,000

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 6/17/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/09/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK
Client Sample I.D.:	--
Date/Time Sampled:	--
Date/Time Analyzed:	6/9/26 18:30
QC Batch No.:	260609MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	0.20
Chloromethane	ND	0.20
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20
Vinyl Chloride	ND	0.20
Bromomethane	ND	0.20
Chloroethane	ND	0.20
Trichlorofluoromethane (11)	ND	0.20
1,1-Dichloroethene	ND	0.20
Carbon Disulfide	ND	0.20
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20
Acetone	ND	0.20
Methylene Chloride	ND	0.20
t-1,2-Dichloroethene	ND	0.20
1,1-Dichloroethane	ND	0.20
Vinyl Acetate	ND	0.20
c-1,2-Dichloroethene	ND	0.20
2-Butanone	ND	0.40
t-Butyl Methyl Ether (MTBE)	ND	0.20
Chloroform	ND	0.20
1,1,1-Trichloroethane	ND	0.20
Carbon Tetrachloride	ND	0.20
Benzene	ND	0.20
1,2-Dichloroethane	ND	0.20
Trichloroethene	ND	0.20
1,2-Dichloropropane	ND	0.20
Bromodichloromethane	ND	0.20
c-1,3-Dichloropropene	ND	0.20
4-Methyl-2-Pentanone	ND	0.20
Toluene	ND	0.20
t-1,3-Dichloropropene	ND	0.20
1,1,2-Trichloroethane	ND	0.20
Tetrachloroethene	ND	0.20
2-Hexanone	ND	0.20
Dibromochloromethane	ND	0.20

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/09/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK							
Client Sample I.D.:	--							
Date/Time Sampled:	--							
Date/Time Analyzed:	6/9/26 18:30							
QC Batch No.:	260609MS2A1							
Analyst Initials:	VM/GD							
Dilution Factor:	0.20							

ANALYTE	Result ppbv	RL ppbv						
1,2-Dibromoethane	ND	0.20						
Chlorobenzene	ND	0.20						
Ethylbenzene	ND	0.20						
p,&m-Xylene	ND	0.20						
o-Xylene	ND	0.20						
Styrene	ND	0.20						
Bromoform	ND	0.20						
1,1,2,2-Tetrachloroethane	ND	0.20						
Benzyl Chloride	ND	0.20						
4-Ethyl Toluene	ND	0.20						
1,3,5-Trimethylbenzene	ND	0.20						
1,2,4-Trimethylbenzene	ND	0.20						
1,3-Dichlorobenzene	ND	0.20						
1,4-Dichlorobenzene	ND	0.20						
1,2-Dichlorobenzene	ND	0.20						
1,2,4-Trichlorobenzene	ND	0.20						
Hexachlorobutadiene	ND	0.20						
1,3-Butadiene	ND	1.0						
Isopropanol	ND	1.0						
n-Hexane	ND	1.0						
Ethyl Acetate	ND	1.0						
Tetrahydrofuran	ND	1.0						
Cyclohexane	ND	1.0						
Heptane	ND	1.0						
1,4-Dioxane	ND	1.0						

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 6/17/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 260609MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	6/9/26 18:30			6/9/26 16:36		6/9/26 17:14					
Analyst Initials:	VM/GD			VM/GD		VM/GD					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	**Result ppbv**	**RL ppbv**	**AMT. ppbv**	**Result ppbv**	**% Rec.**	**Result ppbv**	**% Rec.**	**RPD**	**Low %Rec**	**High %Rec**	**Max. RPD**
1,1-Dichloroethene	ND	0.20	10	12.1	121	12.1	121	0.6	70	130	30
Methylene Chloride	ND	0.20	10	11.9	119	11.7	117	1.3	70	130	30
Trichloroethene	ND	0.20	10	11.1	111	11.2	112	1.3	70	130	30
Toluene	ND	0.20	10	11.4	114	11.5	115	0.5	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	10.8	108	11.1	111	2.5	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date:** 6/17/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175
TX Cert T104704450-14-6
EPA Methods TO14A, TO15
ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

June 26, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T061004-01/05

Enclosed are the results for sample(s) received 6/10/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Zain Khan, Art Jones and Ali Ferrara on 6/25/26.

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

CHAIN OF CUSTODY RECORD

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

TURNAROUND TIME

Standard	■	48 hours	☐
Same Day	☐	72 hours	☐
24 hours	☐	96 hours	☐
Other:			

DELIVERABLES

EDD	■
EDF	☐
Level 3	☐
Level 4	☐

PAGE: 1 **OF**

Condition upon receipt:
Sealed Yes ☐ No ☐
Intact Yes ☐ No ☐
Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:	
Bill to:	
	07FSAccountspayable@scsengineers.com
	3900 Kilroy Airport Way, Suite 300
	Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T061004-01	CV-1535	06/10/26	8:20AM	2-1L	Gas	N	X	X	X	X		
-02	H-1770N	06/10/26	8:30AM	2-1L	Gas	N	X	X	X	X		
-03	CV-24007	06/10/26	8:35AM	2-1L	Gas	N	X	X	X	X		
-04	CV-24017	06/10/26	8:40AM	2-1L	Gas	N	X	X	X	X		
-05	H-2165W	06/10/26	9:00AM	2-1L	Gas	N	X	X	X	X		
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						

AUTHORIZATION TO PERFORM WORK		COMPANY SCS	DATE/TIME 6-10-26 9:26
SAMPLED BY		COMPANY SCS	DATE/TIME 6-10-26 9:26
RELINQUISHED BY	DATE/TIME 6-10-26 9:26	RECEIVED BY	DATE/TIME 6-10-26 9:35
RELINQUISHED BY	DATE/TIME 6/10/26 11:35	RECEIVED BY	DATE/TIME 6/10/26 1133
RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/10/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T061004-01		T061004-02		T061004-03		T061004-04	
Client Sample I.D.:	CV-1535		H-1770N		CV-24007		CV-24017	
Date/Time Sampled:	6/10/26 8:20		6/10/26 8:30		6/10/26 8:35		6/10/26 8:40	
Date/Time Analyzed:	6/10/26 16:17		6/10/26 16:55		6/10/26 17:33		6/10/26 18:11	
QC Batch No.:	260610MS2A1		260610MS2A1		260610MS2A1		260610MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	5,000		2,000		10,000		15,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	5,000	ND	2,000	ND	10,000	ND	15,000
Chloromethane	ND	5,000	ND	2,000	ND	10,000	ND	15,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	5,000	ND	2,000	ND	10,000	ND	15,000
Vinyl Chloride	ND	5,000	ND	2,000	ND	10,000	ND	15,000
Bromomethane	ND	5,000	ND	2,000	ND	10,000	ND	15,000
Chloroethane	ND	5,000	ND	2,000	ND	10,000	ND	15,000
Trichlorofluoromethane (11)	ND	5,000	ND	2,000	ND	10,000	ND	15,000
1,1-Dichloroethene	ND	5,000	ND	2,000	ND	10,000	ND	15,000
Carbon Disulfide	ND	5,000	ND	2,000	ND	10,000	ND	15,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	5,000	ND	2,000	ND	10,000	ND	15,000
Acetone	100,000	5,000	65,000	2,000	340,000	10,000	1,000,000	15,000
Methylene Chloride	ND	5,000	ND	2,000	ND	10,000	ND	15,000
t-1,2-Dichloroethene	ND	5,000	ND	2,000	ND	10,000	ND	15,000
1,1-Dichloroethane	ND	5,000	ND	2,000	ND	10,000	ND	15,000
Vinyl Acetate	ND	5,000	ND	2,000	ND	10,000	ND	15,000
c-1,2-Dichloroethene	ND	5,000	ND	2,000	ND	10,000	ND	15,000
2-Butanone	73,000	10,000	69,000	4,000	260,000	20,000	690,000	30,000
t-Butyl Methyl Ether (MTBE)	ND	5,000	ND	2,000	ND	10,000	ND	15,000
Chloroform	ND	5,000	ND	2,000	ND	10,000	ND	15,000
1,1,1-Trichloroethane	ND	5,000	ND	2,000	ND	10,000	ND	15,000
Carbon Tetrachloride	ND	5,000	ND	2,000	ND	10,000	ND	15,000
Benzene	56,000	5,000	130,000	2,000	140,000	10,000	190,000	15,000
1,2-Dichloroethane	ND	5,000	ND	2,000	ND	10,000	ND	15,000
Trichloroethene	ND	5,000	ND	2,000	ND	10,000	ND	15,000
1,2-Dichloropropane	ND	5,000	ND	2,000	ND	10,000	ND	15,000
Bromodichloromethane	ND	5,000	ND	2,000	ND	10,000	ND	15,000
c-1,3-Dichloropropene	ND	5,000	ND	2,000	ND	10,000	ND	15,000
4-Methyl-2-Pentanone	ND	5,000	ND	2,000	ND	10,000	ND	15,000
Toluene	98,000	5,000	4,600	2,000	ND	10,000	ND	15,000
t-1,3-Dichloropropene	ND	5,000	ND	2,000	ND	10,000	ND	15,000
1,1,2-Trichloroethane	ND	5,000	ND	2,000	ND	10,000	ND	15,000
Tetrachloroethene	ND	5,000	ND	2,000	ND	10,000	ND	15,000
2-Hexanone	ND	5,000	ND	2,000	ND	10,000	ND	15,000
Dibromochloromethane	ND	5,000	ND	2,000	ND	10,000	ND	15,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/10/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T061004-01		T061004-02		T061004-03		T061004-04	
Client Sample I.D.:	CV-1535		H-1770N		CV-24007		CV-24017	
Date/Time Sampled:	6/10/26 8:20		6/10/26 8:30		6/10/26 8:35		6/10/26 8:40	
Date/Time Analyzed:	6/10/26 16:17		6/10/26 16:55		6/10/26 17:33		6/10/26 18:11	
QC Batch No.:	260610MS2A1		260610MS2A1		260610MS2A1		260610MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	5,000		2,000		10,000		15,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	5,000	ND	2,000	ND	10,000	ND	15,000
Chlorobenzene	ND	5,000	ND	2,000	ND	10,000	ND	15,000
Ethylbenzene	5,500	5,000	ND	2,000	ND	10,000	ND	15,000
p,&m-Xylene	19,000	5,000	ND	2,000	ND	10,000	ND	15,000
o-Xylene	9,600	5,000	ND	2,000	ND	10,000	ND	15,000
Styrene	ND	5,000	ND	2,000	ND	10,000	ND	15,000
Bromoform	ND	5,000	ND	2,000	ND	10,000	ND	15,000
1,1,2,2-Tetrachloroethane	ND	5,000	ND	2,000	ND	10,000	ND	15,000
Benzyl Chloride	ND	5,000	ND	2,000	ND	10,000	ND	15,000
4-Ethyl Toluene	ND	5,000	ND	2,000	ND	10,000	ND	15,000
1,3,5-Trimethylbenzene	ND	5,000	ND	2,000	ND	10,000	ND	15,000
1,2,4-Trimethylbenzene	ND	5,000	ND	2,000	ND	10,000	ND	15,000
1,3-Dichlorobenzene	ND	5,000	ND	2,000	ND	10,000	ND	15,000
1,4-Dichlorobenzene	ND	5,000	ND	2,000	ND	10,000	ND	15,000
1,2-Dichlorobenzene	ND	5,000	ND	2,000	ND	10,000	ND	15,000
1,2,4-Trichlorobenzene	ND	5,000	ND	2,000	ND	10,000	ND	15,000
Hexachlorobutadiene	ND	5,000	ND	2,000	ND	10,000	ND	15,000
1,3-Butadiene	ND	25,000	ND	10,000	ND	50,000	ND	75,000
Isopropanol	55,000	25,000	100,000	10,000	260,000	50,000	280,000	75,000
n-Hexane	ND	25,000	ND	10,000	ND	50,000	ND	75,000
Ethyl Acetate	ND	25,000	ND	10,000	ND	50,000	ND	75,000
Tetrahydrofuran	55,000	25,000	110,000	10,000	ND	50,000	520,000	75,000
Cyclohexane	ND	25,000	ND	10,000	ND	50,000	ND	75,000
Heptane	ND	25,000	ND	10,000	ND	50,000	ND	75,000
1,4-Dioxane	ND	25,000	ND	10,000	ND	50,000	ND	75,000

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 6/12/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/10/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T061004-05
Client Sample I.D.:	H-2165W
Date/Time Sampled:	6/10/26 9:00
Date/Time Analyzed:	6/10/26 18:50
QC Batch No.:	260610MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	20,000

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	20,000
Chloromethane	ND	20,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	20,000
Vinyl Chloride	ND	20,000
Bromomethane	ND	20,000
Chloroethane	ND	20,000
Trichlorofluoromethane (11)	ND	20,000
1,1-Dichloroethene	ND	20,000
Carbon Disulfide	ND	20,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	20,000
Acetone	300,000	20,000
Methylene Chloride	ND	20,000
t-1,2-Dichloroethene	ND	20,000
1,1-Dichloroethane	ND	20,000
Vinyl Acetate	ND	20,000
c-1,2-Dichloroethene	ND	20,000
2-Butanone	180,000	40,000
t-Butyl Methyl Ether (MTBE)	ND	20,000
Chloroform	ND	20,000
1,1,1-Trichloroethane	ND	20,000
Carbon Tetrachloride	ND	20,000
Benzene	110,000	20,000
1,2-Dichloroethane	ND	20,000
Trichloroethene	ND	20,000
1,2-Dichloropropane	ND	20,000
Bromodichloromethane	ND	20,000
c-1,3-Dichloropropene	ND	20,000
4-Methyl-2-Pentanone	ND	20,000
Toluene	22,000	20,000
t-1,3-Dichloropropene	ND	20,000
1,1,2-Trichloroethane	ND	20,000
Tetrachloroethene	ND	20,000
2-Hexanone	ND	20,000
Dibromochloromethane	ND	20,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/10/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T061004-05
Client Sample I.D.:	H-2165W
Date/Time Sampled:	6/10/26 9:00
Date/Time Analyzed:	6/10/26 18:50
QC Batch No.:	260610MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	20,000

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	20,000
Chlorobenzene	ND	20,000
Ethylbenzene	ND	20,000
p.&m-Xylene	ND	20,000
o-Xylene	ND	20,000
Styrene	ND	20,000
Bromoform	ND	20,000
1,1,2,2-Tetrachloroethane	ND	20,000
Benzyl Chloride	ND	20,000
4-Ethyl Toluene	ND	20,000
1,3,5-Trimethylbenzene	ND	20,000
1,2,4-Trimethylbenzene	ND	20,000
1,3-Dichlorobenzene	ND	20,000
1,4-Dichlorobenzene	ND	20,000
1,2-Dichlorobenzene	ND	20,000
1,2,4-Trichlorobenzene	ND	20,000
Hexachlorobutadiene	ND	20,000
1,3-Butadiene	ND	100,000
Isopropanol	ND	100,000
n-Hexane	ND	100,000
Ethyl Acetate	ND	100,000
Tetrahydrofuran	130,000	100,000
Cyclohexane	ND	100,000
Heptane	ND	100,000
1,4-Dioxane	ND	100,000

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 6/22/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/10/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK
Client Sample I.D.:	--
Date/Time Sampled:	--
Date/Time Analyzed:	6/10/26 15:38
QC Batch No.:	260610MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	0.20
Chloromethane	ND	0.20
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20
Vinyl Chloride	ND	0.20
Bromomethane	ND	0.20
Chloroethane	ND	0.20
Trichlorofluoromethane (11)	ND	0.20
1,1-Dichloroethene	ND	0.20
Carbon Disulfide	ND	0.20
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20
Acetone	ND	0.20
Methylene Chloride	ND	0.20
t-1,2-Dichloroethene	ND	0.20
1,1-Dichloroethane	ND	0.20
Vinyl Acetate	ND	0.20
c-1,2-Dichloroethene	ND	0.20
2-Butanone	ND	0.40
t-Butyl Methyl Ether (MTBE)	ND	0.20
Chloroform	ND	0.20
1,1,1-Trichloroethane	ND	0.20
Carbon Tetrachloride	ND	0.20
Benzene	ND	0.20
1,2-Dichloroethane	ND	0.20
Trichloroethene	ND	0.20
1,2-Dichloropropane	ND	0.20
Bromodichloromethane	ND	0.20
c-1,3-Dichloropropene	ND	0.20
4-Methyl-2-Pentanone	ND	0.20
Toluene	ND	0.20
t-1,3-Dichloropropene	ND	0.20
1,1,2-Trichloroethane	ND	0.20
Tetrachloroethene	ND	0.20
2-Hexanone	ND	0.20
Dibromochloromethane	ND	0.20

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/10/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK							
Client Sample I.D.:	--							
Date/Time Sampled:	--							
Date/Time Analyzed:	6/10/26 15:38							
QC Batch No.:	260610MS2A1							
Analyst Initials:	VM/GD							
Dilution Factor:	0.20							

ANALYTE	Result ppbv	RL ppbv						
1,2-Dibromoethane	ND	0.20						
Chlorobenzene	ND	0.20						
Ethylbenzene	ND	0.20						
p,&m-Xylene	ND	0.20						
o-Xylene	ND	0.20						
Styrene	ND	0.20						
Bromoform	ND	0.20						
1,1,2,2-Tetrachloroethane	ND	0.20						
Benzyl Chloride	ND	0.20						
4-Ethyl Toluene	ND	0.20						
1,3,5-Trimethylbenzene	ND	0.20						
1,2,4-Trimethylbenzene	ND	0.20						
1,3-Dichlorobenzene	ND	0.20						
1,4-Dichlorobenzene	ND	0.20						
1,2-Dichlorobenzene	ND	0.20						
1,2,4-Trichlorobenzene	ND	0.20						
Hexachlorobutadiene	ND	0.20						
1,3-Butadiene	ND	1.0						
Isopropanol	ND	1.0						
n-Hexane	ND	1.0						
Ethyl Acetate	ND	1.0						
Tetrahydrofuran	ND	1.0						
Cyclohexane	ND	1.0						
Heptane	ND	1.0						
1,4-Dioxane	ND	1.0						

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 6/10/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 260610MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	6/10/26 15:38			6/10/26 14:21		6/10/26 14:59					
Analyst Initials:	VM/GD			VM/GD		VM/GD					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	0.20	10	12.2	122	12.0	120	2.2	70	130	30
Methylene Chloride	ND	0.20	10	11.8	118	12.1	121	2.6	70	130	30
Trichloroethene	ND	0.20	10	11.4	114	11.2	112	1.0	70	130	30
Toluene	ND	0.20	10	11.2	112	11.5	115	2.6	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	11.4	114	11.5	115	1.5	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date: 6/22/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

June 30, 2026

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C,
ASTM D1946, RSK-175

TX Cert T104704450-14-6
EPA Methods TO14A, TO15

ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T061104-01/02

Enclosed are the results for sample(s) received 6/11/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Zain Khan, Art Jones and Ali Ferrara on 6/29/26.

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

CHAIN OF CUSTODY RECORD

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐ No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐ No ☐
Other:				Level 4	☐	Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:	
Bill to:	
	07FSAccountspayable@scsengineers.com
	3900 Kilroy Airport Way, Suite 300
	Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T061104-01	CV-2312	06/11/26	7:30AM	2-1L	Gas	N	X	X	X	X		
↓ -02	CV-24065	06/11/26	7:40AM	2-1L	Gas	N	X	X	X	X		
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						

AUTHORIZATION TO PERFORM WORK		COMPANY SCS	DATE/TIME 6-11-26 8:00	
SAMPLED BY		COMPANY SCS	DATE/TIME 6-11-26 8:00	
RELINQUISHED BY	DATE/TIME 6-11-26 8:20	RECEIVED BY	DATE/TIME 6-11-26 8:30	
RELINQUISHED BY	DATE/TIME 6-11-26 8:30	RECEIVED BY Ruben G	DATE/TIME 6-11-26 9:00	
RELINQUISHED BY Ruben G	DATE/TIME 6-11-26 11:36	RECEIVED BY	DATE/TIME 6/11/26 11:37	

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/11/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T061104-01		T061104-02					
Client Sample I.D.:	CV-2312		CV-24065					
Date/Time Sampled:	6/11/26 7:30		6/11/26 7:40					
Date/Time Analyzed:	6/11/26 14:41		6/11/26 15:19					
QC Batch No.:	260611MS2A1		260611MS2A1					
Analyst Initials:	VM/GD		VM/GD					
Dilution Factor:	9,000		4,000					
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv				
Dichlorodifluoromethane (12)	ND	9,000	ND	4,000				
Chloromethane	ND	9,000	ND	4,000				
1,2-Cl-1,1,2,2-F ethane (114)	ND	9,000	ND	4,000				
Vinyl Chloride	ND	9,000	ND	4,000				
Bromomethane	ND	9,000	ND	4,000				
Chloroethane	ND	9,000	ND	4,000				
Trichlorofluoromethane (11)	ND	9,000	ND	4,000				
1,1-Dichloroethene	ND	9,000	ND	4,000				
Carbon Disulfide	ND	9,000	ND	4,000				
1,1,2-Cl 1,2,2-F ethane (113)	ND	9,000	ND	4,000				
Acetone	450,000	9,000	230,000	4,000				
Methylene Chloride	ND	9,000	ND	4,000				
t-1,2-Dichloroethene	ND	9,000	ND	4,000				
1,1-Dichloroethane	ND	9,000	ND	4,000				
Vinyl Acetate	ND	9,000	ND	4,000				
c-1,2-Dichloroethene	ND	9,000	ND	4,000				
2-Butanone	280,000	18,000	220,000	8,000				
t-Butyl Methyl Ether (MTBE)	ND	9,000	ND	4,000				
Chloroform	ND	9,000	ND	4,000				
1,1,1-Trichloroethane	ND	9,000	ND	4,000				
Carbon Tetrachloride	ND	9,000	ND	4,000				
Benzene	99,000	9,000	170,000	4,000				
1,2-Dichloroethane	ND	9,000	ND	4,000				
Trichloroethene	ND	9,000	ND	4,000				
1,2-Dichloropropane	ND	9,000	ND	4,000				
Bromodichloromethane	ND	9,000	ND	4,000				
c-1,3-Dichloropropene	ND	9,000	ND	4,000				
4-Methyl-2-Pentanone	ND	9,000	4,100 Q	4,000				
Toluene	ND	9,000	8,000	4,000				
t-1,3-Dichloropropene	ND	9,000	ND	4,000				
1,1,2-Trichloroethane	ND	9,000	ND	4,000				
Tetrachloroethene	ND	9,000	ND	4,000				
2-Hexanone	ND	9,000	ND	4,000				
Dibromochloromethane	ND	9,000	ND	4,000				

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/11/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T061104-01		T061104-02					
Client Sample I.D.:	CV-2312		CV-24065					
Date/Time Sampled:	6/11/26 7:30		6/11/26 7:40					
Date/Time Analyzed:	6/11/26 14:41		6/11/26 15:19					
QC Batch No.:	260611MS2A1		260611MS2A1					
Analyst Initials:	VM/GD		VM/GD					
Dilution Factor:	9,000		4,000					
ANALYTE	**Result ppbv**	**RL ppbv**	**Result ppbv**	**RL ppbv**				
1,2-Dibromoethane	ND	9,000	ND	4,000				
Chlorobenzene	ND	9,000	ND	4,000				
Ethylbenzene	ND	9,000	ND	4,000				
p,&m-Xylene	ND	9,000	ND	4,000				
o-Xylene	ND	9,000	ND	4,000				
Styrene	ND	9,000	ND	4,000				
Bromoform	ND	9,000	ND	4,000				
1,1,2,2-Tetrachloroethane	ND	9,000	ND	4,000				
Benzyl Chloride	ND	9,000	ND	4,000				
4-Ethyl Toluene	ND	9,000	ND	4,000				
1,3,5-Trimethylbenzene	ND	9,000	ND	4,000				
1,2,4-Trimethylbenzene	ND	9,000	ND	4,000				
1,3-Dichlorobenzene	ND	9,000	ND	4,000				
1,4-Dichlorobenzene	ND	9,000	ND	4,000				
1,2-Dichlorobenzene	ND	9,000	ND	4,000				
1,2,4-Trichlorobenzene	ND	9,000	ND	4,000				
Hexachlorobutadiene	ND	9,000	ND	4,000				
1,3-Butadiene	ND	45,000	ND	20,000				
Isopropanol	93,000	45,000	110,000	20,000				
n-Hexane	ND	45,000	ND	20,000				
Ethyl Acetate	ND	45,000	ND	20,000				
Tetrahydrofuran	200,000	45,000	120,000	20,000				
Cyclohexane	ND	45,000	ND	20,000				
Heptane	ND	45,000	ND	20,000				
1,4-Dioxane	ND	45,000	ND	20,000				

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited high recovery in the continuing calibration verification indicating possible high bias

Reviewed/Approved By: _____ Date 6/22/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/11/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK
Client Sample I.D.:	--
Date/Time Sampled:	--
Date/Time Analyzed:	6/11/26 5:45
QC Batch No.:	260611MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	0.20
Chloromethane	ND	0.20
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20
Vinyl Chloride	ND	0.20
Bromomethane	ND	0.20
Chloroethane	ND	0.20
Trichlorofluoromethane (11)	ND	0.20
1,1-Dichloroethene	ND	0.20
Carbon Disulfide	ND	0.20
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20
Acetone	ND	0.20
Methylene Chloride	ND	0.20
t-1,2-Dichloroethene	ND	0.20
1,1-Dichloroethane	ND	0.20
Vinyl Acetate	ND	0.20
c-1,2-Dichloroethene	ND	0.20
2-Butanone	ND	0.40
t-Butyl Methyl Ether (MTBE)	ND	0.20
Chloroform	ND	0.20
1,1,1-Trichloroethane	ND	0.20
Carbon Tetrachloride	ND	0.20
Benzene	ND	0.20
1,2-Dichloroethane	ND	0.20
Trichloroethene	ND	0.20
1,2-Dichloropropane	ND	0.20
Bromodichloromethane	ND	0.20
c-1,3-Dichloropropene	ND	0.20
4-Methyl-2-Pentanone	ND	0.20
Toluene	ND	0.20
t-1,3-Dichloropropene	ND	0.20
1,1,2-Trichloroethane	ND	0.20
Tetrachloroethene	ND	0.20
2-Hexanone	ND	0.20
Dibromochloromethane	ND	0.20

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/11/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK
Client Sample I.D.:	--
Date/Time Sampled:	--
Date/Time Analyzed:	6/11/26 5:45
QC Batch No.:	260611MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	0.20
Chlorobenzene	ND	0.20
Ethylbenzene	ND	0.20
p,&m-Xylene	ND	0.20
o-Xylene	ND	0.20
Styrene	ND	0.20
Bromoform	ND	0.20
1,1,2,2-Tetrachloroethane	ND	0.20
Benzyl Chloride	ND	0.20
4-Ethyl Toluene	ND	0.20
1,3,5-Trimethylbenzene	ND	0.20
1,2,4-Trimethylbenzene	ND	0.20
1,3-Dichlorobenzene	ND	0.20
1,4-Dichlorobenzene	ND	0.20
1,2-Dichlorobenzene	ND	0.20
1,2,4-Trichlorobenzene	ND	0.20
Hexachlorobutadiene	ND	0.20
1,3-Butadiene	ND	1.0
Isopropanol	ND	1.0
n-Hexane	ND	1.0
Ethyl Acetate	ND	1.0
Tetrahydrofuran	ND	1.0
Cyclohexane	ND	1.0
Heptane	ND	1.0
1,4-Dioxane	ND	1.0

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ **Date** 6/22/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 260611MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	6/11/26 5:45			6/11/26 4:28		6/11/26 5:06					
Analyst Initials:	VM/GD			VM/GD		VM/GD					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	0.20	10	12.7	127	12.3	123	3.4	70	130	30
Methylene Chloride	ND	0.20	10	12.6	126	11.9	119	5.6	70	130	30
Trichloroethene	ND	0.20	10	11.5	115	11.4	114	0.8	70	130	30
Toluene	ND	0.20	10	12.0	120	12.2	122	1.7	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	12.0	120	12.0	120	0.3	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date:** 6/22/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/11/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T061104-01		T061104-02					
Client Sample I.D.:	CV-2312		CV-24065					
Date/Time Sampled:	6/11/26 7:30		6/11/26 7:40					
Date/Time Analyzed:	6/11/26 19:31		6/11/26 19:46					
QC Batch No.:	260611GC8A2		260611GC8A2					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv				
Carbon Monoxide	2,700	10	250	10				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6/29/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260611GC8A2
Matrix: Air
Reporting Units: ppmv

EPA ATL-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	6/11/26 16:36			6/11/26 14:59		6/11/26 15:13					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,030	102	1,020	101	1.4	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** _____
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/11/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T061104-01			T061104-02						
Client Sample I.D.:	CV-2312			CV-24065						
Date/Time Sampled:	6/11/26 7:30			6/11/26 7:40						
Date/Time Analyzed:	6/11/26 19:31			6/11/26 19:46						
QC Batch No.:	260611GC8A2			260611GC8A2						
Analyst Initials:	KD			KD						
Dilution Factor:	1.0			1.0						
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v				
Hydrogen	15	1.0	0.059	0.71 J	1.0	0.059				

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 6/19/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260611GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	6/11/26 16:36				6/11/26 14:59		6/11/26 15:13					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	3.63	73	3.67	74	1.1	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 6/29/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/11/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T061104-01		T061104-02					
Client Sample I.D.:	CV-2312		CV-24065					
Date/Time Sampled:	6/11/26 7:30		6/11/26 7:40					
Date/Time Analyzed:	6/11/26 19:31		6/11/26 19:46					
QC Batch No.:	260611GC8A2		260611GC8A2					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**				
Carbon Dioxide	76	0.010	76	0.010				
Oxygen/Argon	1.6	0.50	1.4	0.50				
Nitrogen	5.7	1.0	7.1	1.0				
Methane	1.1	0.0010	14	0.0010				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260611GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	6/11/26 16:36			6/11/26 14:59		6/11/26 15:13					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	8.86	88	8.87	89	0.1	70	130	30
Oxygen/Argon	ND	0.50	15	15.1	100	15.1	100	0.1	70	130	30
Nitrogen	ND	1.0	70	71.1	102	71.2	102	0.2	70	130	30
Methane	ND	0.0010	0.10	0.0939	93	0.0930	92	1.0	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 6/9/26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175
TX Cert T104704450-14-6
EPA Methods TO14A, TO15
ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

June 30, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T061207-01/13

Enclosed are the results for sample(s) received 6/12/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Zain Khan, Art Jones and Ali Ferrara on 6/29/26.

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐ No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐ No ☐
Other:				Level 4	☐	Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:	
Bill to:	
	07FSAccountspayable@scsengineers.com
	3900 Kilroy Airport Way, Suite 300
	Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T061207-01	CV-24055	06/12/26	8:00AM	1L	Gas	N	X	X	X			
-02	CV-24134	06/12/26	8:10AM	1L	Gas	N	X					
-03	CV-2305	06/12/26	8:25AM	1L	Gas	N	X	X	X			
-04	CV-2314	06/12/26	8:30AM	1L	Gas	N	X	X	X			
-05	CV-24064	06/12/26	8:35AM	1L	Gas	N	X	X	X			
-06	CV-2328	06/12/26	8:45AM	1L	Gas	N	X	X	X			
-07	CV-24062	06/12/26	8:50AM	1L	Gas	N	X	X	X			
-08	CV-24071	06/12/26	9:00AM	1L	Gas	N	X	X	X			
-09	CV-24070	06/12/26	9:10AM	1L	Gas	N	X	X	X			
-10	CV-24084	06/12/26	9:15AM	1L	Gas	N	X					

AUTHORIZATION TO PERFORM WORK	COMPANY SCS	DATE/TIME 6/12/26	
SAMPLED BY	COMPANY SCS	DATE/TIME	
RELINQUISHED BY	DATE/TIME 6/12/26 10:55	RECEIVED BY Ruben G	DATE/TIME 6-12-26 10:55am
RELINQUISHED BY Ruben G	DATE/TIME 6-12-26 12:30	RECEIVED BY	DATE/TIME 6/12/26 1230
RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 2 OF	
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:	
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐	No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐	No ☐
Other:				Level 4	☐	Chilled _____	deg C

		BILLING	
Project No.:	07224200.24 Task 1		
Project Name:	Chiquita Canyon Landfill		
Report To:	Cornelius Fong		
Company:	SCS Engineers	*P.O. No.:*	
Street:	3900 Kilroy Airport Way, Suite 300	*Bill to:*	
City/State/Zip:	Long Beach, CA 90806-6816	07FSAccountspayable@scsengineers.com	
Phone& Fax:	562-743-7895	3900 Kilroy Airport Way, Suite 300	
e-mail:	cfong@scsengineers.com	Long Beach, CA 90806-6816	

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	ANALYSIS REQUEST: CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T061207-11	CV-24141	06/12/26	9:30AM	1L	Gas	N	X	X	X			
-12	CV-24120	06/12/26	9:55AM	1L	Gas	N	X	X	X			
-13	CV-24063	06/12/26	10:10AM	1L	Gas	N	X	X	X			

AUTHORIZATION TO PERFORM WORK		COMPANY		DATE/TIME
SAMPLED BY		COMPANY SCS		DATE/TIME 6/12/26
RELINQUISHED BY		DATE/TIME 6/12/26 10:55	RECEIVED BY Ruben G	DATE/TIME 6-12-26 10:55
RELINQUISHED BY Ruben G		DATE/TIME 6/12/26 12:30	RECEIVED BY	DATE/TIME 6/12/26 1023
RELINQUISHED BY		DATE/TIME	RECEIVED BY	DATE/TIME

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/12/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T061207-01		T061207-03		T061207-04		T061207-05	
Client Sample I.D.:	CV-24055		CV-2305		CV-2314		CV-24064	
Date/Time Sampled:	6/12/26 8:00		6/12/26 8:25		6/12/26 8:30		6/12/26 8:35	
Date/Time Analyzed:	6/12/26 16:32		6/12/26 17:01		6/12/26 17:15		6/12/26 17:30	
QC Batch No.:	260612GC8A3		260612GC8A3		260612GC8A3		260612GC8A3	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	720	10	500	10	1,700	10	140	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6-29-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/12/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T061207-06		T061207-07		T061207-08		T061207-09	
Client Sample I.D.:	CV-2328		CV-24062		CV-24071		CV-24070	
Date/Time Sampled:	6/12/26 8:45		6/12/26 8:50		6/12/26 9:00		6/12/26 9:10	
Date/Time Analyzed:	6/12/26 17:44		6/12/26 17:59		6/12/26 18:13		6/12/26 18:28	
QC Batch No.:	260612GC8A3		260612GC8A3		260612GC8A3		260612GC8A3	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	200	10	33	10	290	10	600	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6-29-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/12/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T061207-11		T061207-12		T061207-13			
Client Sample I.D.:	CV-24141		CV-24120		CV-24063			
Date/Time Sampled:	6/12/26 9:30		6/12/26 9:55		6/12/26 10:10			
Date/Time Analyzed:	6/12/26 18:57		6/12/26 19:11		6/12/26 19:26			
QC Batch No.:	260612GC8A3		260612GC8A3		260612GC8A3			
Analyst Initials:	KD		KD		KD			
Dilution Factor:	1.0		1.0		1.0			
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv		
Carbon Monoxide	190	10	360	10	190	10		

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____
Mark Johnson
Operations Manager

Date 6-29-26

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/12/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T061207-01			T061207-03			T061207-04			T061207-05		
Client Sample I.D.:	CV-24055			CV-2305			CV-2314			CV-24064		
Date/Time Sampled:	6/12/26 8:00			6/12/26 8:25			6/12/26 8:30			6/12/26 8:35		
Date/Time Analyzed:	6/12/26 16:32			6/12/26 17:01			6/12/26 17:15			6/12/26 17:30		
QC Batch No.:	260612GC8A3			260612GC8A3			260612GC8A3			260612GC8A3		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	4.5	1.0	0.059	2.8	1.0	0.059	7.4	1.0	0.059	1.1	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 6-29-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/12/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T061207-06			T061207-07			T061207-08			T061207-09		
Client Sample I.D.:	CV-2328			CV-24062			CV-24071			CV-24070		
Date/Time Sampled:	6/12/26 8:45			6/12/26 8:50			6/12/26 9:00			6/12/26 9:10		
Date/Time Analyzed:	6/12/26 17:44			6/12/26 17:59			6/12/26 18:13			6/12/26 18:28		
QC Batch No.:	260612GC8A3			260612GC8A3			260612GC8A3			260612GC8A3		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	2.2	1.0	0.059	0.45 J	1.0	0.059	3.6	1.0	0.059	5.5	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 6-29-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/12/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T061207-11			T061207-12			T061207-13					
Client Sample I.D.:	CV-24141			CV-24120			CV-24063					
Date/Time Sampled:	6/12/26 9:30			6/12/26 9:55			6/12/26 10:10					
Date/Time Analyzed:	6/12/26 18:57			6/12/26 19:11			6/12/26 19:26					
QC Batch No.:	260612GC8A3			260612GC8A3			260612GC8A3					
Analyst Initials:	KD			KD			KD					
Dilution Factor:	1.0			1.0			1.0					
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v			
Hydrogen	1.2	1.0	0.059	3.0	1.0	0.059	1.1	1.0	0.059			

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____
Mark Johnson
Operations Manager

Date 6-29-26

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/12/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T061207-01		T061207-02		T061207-03		T061207-04	
Client Sample I.D.:	CV-24055		CV-24134		CV-2305		CV-2314	
Date/Time Sampled:	6/12/26 8:00		6/12/26 8:10		6/12/26 8:25		6/12/26 8:30	
Date/Time Analyzed:	6/12/26 16:32		6/12/26 16:46		6/12/26 17:01		6/12/26 17:15	
QC Batch No.:	260612GC8A3		260612GC8A3		260612GC8A3		260612GC8A3	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	44	0.010	17	0.010	26	0.010	42	0.010
Oxygen/Argon	7.0	0.50	16	0.50	11	0.50	10	0.50
Nitrogen	37	1.0	59	1.0	50	1.0	39	1.0
Methane	6.5	0.0010	3.3	0.0010	9.2	0.0010	1.3	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____
Mark Johnson
Operations Manager

Date 6-29-26

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/12/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T061207-05		T061207-06		T061207-07		T061207-08	
Client Sample I.D.:	CV-24064		CV-2328		CV-24062		CV-24071	
Date/Time Sampled:	6/12/26 8:35		6/12/26 8:45		6/12/26 8:50		6/12/26 9:00	
Date/Time Analyzed:	6/12/26 17:30		6/12/26 17:44		6/12/26 17:59		6/12/26 18:13	
QC Batch No.:	260612GC8A3		260612GC8A3		260612GC8A3		260612GC8A3	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	4.9	0.010	17	0.010	1.7	0.010	30	0.010
Oxygen/Argon	20	0.50	16	0.50	21	0.50	11	0.50
Nitrogen	74	1.0	60	1.0	77	1.0	41	1.0
Methane	0.085	0.0010	4.5	0.0010	0.36	0.0010	14	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6-29-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/12/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T061207-09		T061207-10		T061207-11		T061207-12	
Client Sample I.D.:	CV-24070		CV-24084		CV-24141		CV-24120	
Date/Time Sampled:	6/12/26 9:10		6/12/26 9:15		6/12/26 9:30		6/12/26 9:55	
Date/Time Analyzed:	6/12/26 18:28		6/12/26 18:42		6/12/26 18:57		6/12/26 19:11	
QC Batch No.:	260612GC8A3		260612GC8A3		260612GC8A3		260612GC8A3	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	35	0.010	65	0.010	14	0.010	17	0.010
Oxygen/Argon	11	0.50	4.7	0.50	16	0.50	16	0.50
Nitrogen	41	1.0	17	1.0	65	1.0	62	1.0
Methane	7.6	0.0010	2.5	0.0010	3.6	0.0010	1.5	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6-29-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/12/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	**T061207-13**							
Client Sample I.D.:	**CV-24063**							
Date/Time Sampled:	**6/12/26 10:10**							
Date/Time Analyzed:	**6/12/26 19:26**							
QC Batch No.:	**260612GC8A3**							
Analyst Initials:	**KD**							
Dilution Factor:	**1.0**							
ANALYTE	**Result % v/v**	**RL % v/v**						
Carbon Dioxide	**6.3**	0.010						
Oxygen/Argon	**20**	0.50						
Nitrogen	**73**	1.0						
Methane	**0.25**	0.0010						

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 6-29-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260612GC8A3
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	6/12/26 16:02			6/12/26 15:33		6/12/26 15:47					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,070	106	1,060	105	0.5	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 6-29-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260612GC8A3
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	6/12/26 16:16				6/12/26 15:33		6/12/26 15:47					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	5.02	101	5.01	101	0.2	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 6-29-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260612GC8A3
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	6/12/26 16:16			6/12/26 15:33		6/12/26 15:47					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	9.40	94	9.40	94	0.0	70	130	30
Oxygen/Argon	ND	0.50	15	14.8	98	14.8	98	0.0	70	130	30
Nitrogen	ND	1.0	70	70.6	101	70.6	101	0.0	70	130	30
Methane	ND	0.0010	0.10	0.0970	96	0.0967	96	0.3	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 6-29-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS

June 30, 2026

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175

TX Cert T104704450-14-6
EPA Methods TO14A, TO15

ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T061501-01/10

Enclosed are the results for sample(s) received 6/15/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Zain Khan, Art Jones and Ali Ferrara on 6/29/26.

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 2 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐ No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐ No ☐
Other:				Level 4	☐	Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:	
Bill to:	07FSAccountspayable@scsengineers.com
	3900 Kilroy Airport Way, Suite 300
	Long Beach, CA 90806-6816

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	ANALYSIS REQUEST: CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T061501-01	CV-24066	06/15/26	7:50AM	1L	Gas	N	X	X	X			
-02	CV-2354	06/15/26	8:10AM	1L	Gas	N	X	X	X			
-03	CV-24069	06/15/26	8:00AM	1L	Gas	N	X	X	X			
-04	CV-2353	06/15/26	8:25AM	1L	Gas	N	X	X	X			
-05	CV-114	06/15/26	8:40AM	1L	Gas	N	X	X	X			
-06	H-1770N	06/15/26	9:30AM	1L	Gas	N	X	X	X			
-07	CV-24007	06/15/26	9:35AM	1L	Gas	N	X	X	X			
-08	CV-24017	06/15/26	9:45AM	1L	Gas	N	X	X	X			
-09	CV-1535	06/15/26	10:05AM	1L	Gas	N	X	X	X			
-10	CV-2341	06/15/26	10:15AM	1L	Gas	N	X	X	X			

AUTHORIZATION TO PERFORM WORK	COMPANY SCS	DATE/TIME 10:45a 6-15-26	
SAMPLED BY	COMPANY SCS	DATE/TIME 10:45a 6-15-26	
RELINQUISHED BY	DATE/TIME 6-15-26 10:45a	RECEIVED BY Ruben G	DATE/TIME 6-15-26 10:57
RELINQUISHED BY Ruben G	DATE/TIME 6-15-26 12:13	RECEIVED BY	DATE/TIME 6/15/26 1213
RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/15/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T061501-01		T061501-02		T061501-03		T061501-04	
Client Sample I.D.:	CV-24066		CV-2354		CV-24069		CV-2353	
Date/Time Sampled:	6/15/26 7:50		6/15/26 8:10		6/15/26 8:00		6/15/26 8:25	
Date/Time Analyzed:	6/15/26 16:22		6/15/26 16:36		6/15/26 16:51		6/15/26 17:05	
QC Batch No.:	260615GC8A2		260615GC8A2		260615GC8A2		260615GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	280	10	2,200	10	1,100	10	710	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6-29-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/15/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T061501-05		T061501-06		T061501-07		T061501-08	
Client Sample I.D.:	CV-114		H-1770N		CV-24007		CV-24017	
Date/Time Sampled:	6/15/26 8:40		6/15/26 9:30		6/15/26 9:35		6/15/26 9:45	
Date/Time Analyzed:	6/15/26 17:19		6/15/26 17:34		6/15/26 17:48		6/15/26 18:03	
QC Batch No.:	260615GC8A2		260615GC8A2		260615GC8A2		260615GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	400	10	79	10	470	10	1,500	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6-29-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/15/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T061501-09		T061501-10					
Client Sample I.D.:	CV-1535		CV-2341					
Date/Time Sampled:	6/15/26 10:05		6/15/26 10:15					
Date/Time Analyzed:	6/15/26 18:17		6/15/26 18:32					
QC Batch No.:	260615GC8A2		260615GC8A2					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv				
Carbon Monoxide	91	10	860	10				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6-29-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/15/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T061501-01			T061501-02			T061501-03			T061501-04		
Client Sample I.D.:	CV-24066			CV-2354			CV-24069			CV-2353		
Date/Time Sampled:	6/15/26 7:50			6/15/26 8:10			6/15/26 8:00			6/15/26 8:25		
Date/Time Analyzed:	6/15/26 16:22			6/15/26 16:36			6/15/26 16:51			6/15/26 17:05		
QC Batch No.:	260615GC8A2			260615GC8A2			260615GC8A2			260615GC8A2		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	3.0	1.0	0.059	18	1.0	0.059	12	1.0	0.059	20	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 6-29-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/15/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T061501-05			T061501-06			T061501-07			T061501-08		
Client Sample I.D.:	CV-114			H-1770N			CV-24007			CV-24017		
Date/Time Sampled:	6/15/26 8:40			6/15/26 9:30			6/15/26 9:35			6/15/26 9:45		
Date/Time Analyzed:	6/15/26 17:19			6/15/26 17:34			6/15/26 17:48			6/15/26 18:03		
QC Batch No.:	260615GC8A2			260615GC8A2			260615GC8A2			260615GC8A2		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	ND	1.0	0.059	1.2	1.0	0.059	6.3	1.0	0.059	16	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 6-29-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/15/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T061501-09			T061501-10								
Client Sample I.D.:	CV-1535			CV-2341								
Date/Time Sampled:	6/15/26 10:05			6/15/26 10:15								
Date/Time Analyzed:	6/15/26 18:17			6/15/26 18:32								
QC Batch No.:	260615GC8A2			260615GC8A2								
Analyst Initials:	KD			KD								
Dilution Factor:	1.0			1.0								
ANALYTE	**Result % v/v**	**RL % v/v**	**MDL % v/v**	**Result % v/v**	**RL % v/v**	**MDL % v/v**						
Hydrogen	0.89 J	1.0	0.059	15	1.0	0.059						

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 6-29-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/15/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T061501-01		T061501-02		T061501-03		T061501-04	
Client Sample I.D.:	CV-24066		CV-2354		CV-24069		CV-2353	
Date/Time Sampled:	6/15/26 7:50		6/15/26 8:10		6/15/26 8:00		6/15/26 8:25	
Date/Time Analyzed:	6/15/26 16:22		6/15/26 16:36		6/15/26 16:51		6/15/26 17:05	
QC Batch No.:	260615GC8A2		260615GC8A2		260615GC8A2		260615GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	46	0.010	73	0.010	70	0.010	61	0.010
Oxygen/Argon	1.4	0.50	ND	0.50	1.4	0.50	3.0	0.50
Nitrogen	25	1.0	1.7	1.0	5.4	1.0	11	1.0
Methane	25	0.0010	5.0	0.0010	10	0.0010	2.1	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____
Mark Johnson
Operations Manager

Date 6-29-26

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/15/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T061501-05		T061501-06		T061501-07		T061501-08	
Client Sample I.D.:	CV-114		H-1770N		CV-24007		CV-24017	
Date/Time Sampled:	6/15/26 8:40		6/15/26 9:30		6/15/26 9:35		6/15/26 9:45	
Date/Time Analyzed:	6/15/26 17:19		6/15/26 17:34		6/15/26 17:48		6/15/26 18:03	
QC Batch No.:	260615GC8A2		260615GC8A2		260615GC8A2		260615GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	0.056	0.010	58	0.010	48	0.010	69	0.010
Oxygen/Argon	21	0.50	0.79	0.50	3.2	0.50	1.3	0.50
Nitrogen	79	1.0	3.1	1.0	16	1.0	4.9	1.0
Methane	0.0020	0.0010	36	0.0010	26	0.0010	6.9	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____
Mark Johnson
Operations Manager

Date 6-29-26

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/15/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T061501-09		T061501-10					
Client Sample I.D.:	CV-1535		CV-2341					
Date/Time Sampled:	6/15/26 10:05		6/15/26 10:15					
Date/Time Analyzed:	6/15/26 18:17		6/15/26 18:32					
QC Batch No.:	260615GC8A2		260615GC8A2					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**				
Carbon Dioxide	50	0.010	52	0.010				
Oxygen/Argon	0.84	0.50	4.2	0.50				
Nitrogen	3.2	1.0	16	1.0				
Methane	44	0.0010	12	0.0010				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6-29-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260615GC8A2
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	6/15/26 16:07			6/15/26 15:09		6/15/26 15:23					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,060	105	1,060	105	0.4	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6-29-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260615GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	6/15/26 16:07				6/15/26 15:09		6/15/26 15:23					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	5.55	112	5.59	112	0.7	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 6-29-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260615GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	6/15/26 16:07			6/15/26 15:09		6/15/26 15:23					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	9.73	97	9.74	97	0.1	70	130	30
Oxygen/Argon	ND	0.50	15	14.8	98	14.8	99	0.3	70	130	30
Nitrogen	ND	1.0	70	71.9	103	72.1	103	0.3	70	130	30
Methane	ND	0.0010	0.10	0.0979	97	0.0977	97	0.2	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 6-29-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175
TX Cert T104704450-14-6
EPA Methods TO14A, TO15
ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

June 30, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T061605-01/12

Enclosed are the results for sample(s) received 6/16/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Zain Khan, Art Jones and Ali Ferrara on 6/29/26.

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 2 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐ No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐ No ☐
Other:				Level 4	☐	Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:	
Bill to:	
	07FSAccountspayable@scsengineers.com
	3900 Kilroy Airport Way, Suite 300
	Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T061605-01	H-2165W	06/16/26	8:05AM	1L	Gas	N	X	X	X			
-02	CV-2001	06/16/26	8:10AM	1L	Gas	N	X	X	X			
-03	CV-24095	06/16/26	8:20AM	1L	Gas	N	X	X	X			
-04	CV-24138	06/16/26	8:25AM	1L	Gas	N	X	X	X			
-05	CV-24139	06/16/26	8:30AM	1L	Gas	N	X	X	X			
-06	CV-24140	06/16/26	8:35AM	1L	Gas	N	X	X	X			
-07	CV-24143	06/16/26	8:40AM	1L	Gas	N	X	X	X			
-08	CV-2351	06/16/26	8:45AM	1L	Gas	N	X	X	X			
-09	CV-1532A	06/16/26	8:55AM	1L	Gas	N	X	X	X			
-10	CV-2337	06/16/26	9:15AM	1L	Gas	N	X	X	X			

AUTHORIZATION TO PERFORM WORK	COMPANY	DATE/TIME
SAMPLED BY: Erik Navarro	COMPANY: SCS	DATE/TIME: 6-16-26
RELINQUISHED BY: Antonio Ramos	DATE/TIME: 6-16-26 9:50	RECEIVED BY: Ruben G	DATE/TIME: 6/16/26 9:50
RELINQUISHED BY: Ruben G	DATE/TIME: 6-16-26 12:25	RECEIVED BY: [signature]	DATE/TIME: 6/16/26 12:25
RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 2 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐ No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐ No ☐
Other:				Level 4	☐	Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:	
Bill to:	
	07FSAccountspayable@scsengineers.com
	3900 Kilroy Airport Way, Suite 300
	Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946			
T061605-11	CV-1902A	06/16/26	9:20AM	1L	Gas	N	X	X	X			
↓ -12	CV-24101	06/16/26	9:30AM	1L	Gas	N	X	X	X			

AUTHORIZATION TO PERFORM WORK	COMPANY	DATE/TIME
SAMPLED BY: Erik Navarro	COMPANY: SCS	DATE/TIME: 6-16-26
RELINQUISHED BY: Antonio Ambriz	DATE/TIME: 6-16-26 9:50am	RECEIVED BY: Ruben G	DATE/TIME: 6/16/26 9:50AM
RELINQUISHED BY: Ruben G	DATE/TIME: 6-16-26 12:25	RECEIVED BY: [signature]	DATE/TIME: 6/16/26 12:25
RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/16/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T061605-01		T061605-02		T061605-03		T061605-04	
Client Sample I.D.:	H-2165W		CV-2001		CV-24095		CV-24138	
Date/Time Sampled:	6/16/26 8:05		6/16/26 8:10		6/16/26 8:20		6/16/26 8:25	
Date/Time Analyzed:	6/16/26 17:00		6/16/26 17:15		6/16/26 17:29		6/16/26 17:43	
QC Batch No.:	260616GC8A2		260616GC8A2		260616GC8A2		260616GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	890	10	990	10	2,500	10	780	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6-29-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/16/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T061605-05		T061605-06		T061605-07		T061605-08	
Client Sample I.D.:	CV-24139		CV-24140		CV-24143		CV-2351	
Date/Time Sampled:	6/16/26 8:30		6/16/26 8:35		6/16/26 8:40		6/16/26 8:45	
Date/Time Analyzed:	6/16/26 17:58		6/16/26 18:12		6/16/26 18:27		6/16/26 18:41	
QC Batch No.:	260616GC8A2		260616GC8A2		260616GC8A2		260616GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	ND	10	850	10	1,400	10	13	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6-29-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/16/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T061605-09		T061605-10		T061605-11		T061605-12	
Client Sample I.D.:	CV-1532A		CV-2337		CV-1902A		CV-24101	
Date/Time Sampled:	6/16/26 8:55		6/16/26 9:15		6/16/26 9:20		6/16/26 9:30	
Date/Time Analyzed:	6/16/26 18:56		6/16/26 19:10		6/16/26 19:25		6/16/26 19:39	
QC Batch No.:	260616GC8A2		260616GC8A2		260616GC8A2		260616GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	59	10	3,500	10	810	10	110	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____
Mark Johnson
Operations Manager

Date 6-29-26

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/16/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T061605-01			T061605-02			T061605-03			T061605-04		
Client Sample I.D.:	H-2165W			CV-2001			CV-24095			CV-24138		
Date/Time Sampled:	6/16/26 8:05			6/16/26 8:10			6/16/26 8:20			6/16/26 8:25		
Date/Time Analyzed:	6/16/26 17:00			6/16/26 17:15			6/16/26 17:29			6/16/26 17:43		
QC Batch No.:	260616GC8A2			260616GC8A2			260616GC8A2			260616GC8A2		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	6.0	1.0	0.059	7.9	1.0	0.059	17	1.0	0.059	20	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 6-29-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/16/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T061605-05			T061605-06			T061605-07			T061605-08		
Client Sample I.D.:	CV-24139			CV-24140			CV-24143			CV-2351		
Date/Time Sampled:	6/16/26 8:30			6/16/26 8:35			6/16/26 8:40			6/16/26 8:45		
Date/Time Analyzed:	6/16/26 17:58			6/16/26 18:12			6/16/26 18:27			6/16/26 18:41		
QC Batch No.:	260616GC8A2			260616GC8A2			260616GC8A2			260616GC8A2		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	0.49 J	1.0	0.059	19	1.0	0.059	19	1.0	0.059	0.41 J	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 6-29-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/16/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T061605-09			T061605-10			T061605-11			T061605-12		
Client Sample I.D.:	CV-1532A			CV-2337			CV-1902A			CV-24101		
Date/Time Sampled:	6/16/26 8:55			6/16/26 9:15			6/16/26 9:20			6/16/26 9:30		
Date/Time Analyzed:	6/16/26 18:56			6/16/26 19:10			6/16/26 19:25			6/16/26 19:39		
QC Batch No.:	260616GC8A2			260616GC8A2			260616GC8A2			260616GC8A2		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	1.1	1.0	0.059	12	1.0	0.059	19	1.0	0.059	ND	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____
Mark Johnson
Operations Manager

Date 6-29-26

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/16/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T061605-01		T061605-02		T061605-03		T061605-04	
Client Sample I.D.:	H-2165W		CV-2001		CV-24095		CV-24138	
Date/Time Sampled:	6/16/26 8:05		6/16/26 8:10		6/16/26 8:20		6/16/26 8:25	
Date/Time Analyzed:	6/16/26 17:00		6/16/26 17:15		6/16/26 17:29		6/16/26 17:43	
QC Batch No.:	260616GC8A2		260616GC8A2		260616GC8A2		260616GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	ND	0.010	ND	0.010	ND	0.010	ND	0.010
Oxygen/Argon	1.3	0.50	1.4	0.50	0.95	0.50	1.7	0.50
Nitrogen	4.9	1.0	5.3	1.0	3.4	1.0	19	1.0
Methane	8.8	0.0010	9.7	0.0010	3.3	0.0010	1.9	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6-29-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/16/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T061605-05		T061605-06		T061605-07		T061605-08	
Client Sample I.D.:	CV-24139		CV-24140		CV-24143		CV-2351	
Date/Time Sampled:	6/16/26 8:30		6/16/26 8:35		6/16/26 8:40		6/16/26 8:45	
Date/Time Analyzed:	6/16/26 17:58		6/16/26 18:12		6/16/26 18:27		6/16/26 18:41	
QC Batch No.:	260616GC8A2		260616GC8A2		260616GC8A2		260616GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	1.1	0.010	ND	0.010	ND	0.010	ND	0.010
Oxygen/Argon	20	0.50	4.7	0.50	0.61	0.50	21	0.50
Nitrogen	78	1.0	17	1.0	2.4	1.0	78	1.0
Methane	0.035	0.0010	1.7	0.0010	1.8	0.0010	0.022	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6-29-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 06/16/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T061605-09		T061605-10		T061605-11		T061605-12	
Client Sample I.D.:	CV-1532A		CV-2337		CV-1902A		CV-24101	
Date/Time Sampled:	6/16/26 8:55		6/16/26 9:15		6/16/26 9:20		6/16/26 9:30	
Date/Time Analyzed:	6/16/26 18:56		6/16/26 19:10		6/16/26 19:25		6/16/26 19:39	
QC Batch No.:	260616GC8A2		260616GC8A2		260616GC8A2		260616GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	ND	0.010	ND	0.010	ND	0.010	ND	0.010
Oxygen/Argon	2.5	0.50	2.9	0.50	1.3	0.50	8.0	0.50
Nitrogen	11	1.0	11	1.0	5.1	1.0	30	1.0
Methane	19	0.0010	4.3	0.0010	2.0	0.0010	28	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 6-29-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260616GC8A2
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	6/16/26 16:45			6/16/26 15:47		6/16/26 16:02					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,040	103	1,040	103	0.6	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 6-29-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260616GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	6/16/26 16:45				6/16/26 15:47		6/16/26 16:02					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	4.73	95	4.77	96	0.8	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 6-29-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260616GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	6/16/26 16:45			6/16/26 15:47		6/16/26 16:02					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	9.36	93	9.35	93	0.2	70	130	30
Oxygen/Argon	ND	0.50	15	15.1	100	15.1	100	0.1	70	130	30
Nitrogen	ND	1.0	70	72.6	104	72.6	104	0.1	70	130	30
Methane	ND	0.0010	0.10	0.0990	98	0.0987	98	0.3	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 6-29-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
A-01	6/12/2026 11:15:57 AM	59.1	40.8	0.1	0.0			1.4	0.0	100.0	100.0
A-02	6/12/2026 11:23:56 AM	61.4	38.0	0.7				1.6		101.4	101.4
A-03	6/12/2026 11:26:57 AM	61.5	38.1	0.4	0.0			1.6	0.0	103.0	103.6
A-04	6/12/2026 11:30:07 AM	60.6	39.3	0.2				1.5		98.4	98.4
A-05	6/12/2026 11:32:50 AM	60.5	39.3	0.2	0.0			1.5	0.0	101.3	101.5
B-01	6/15/2026 10:15:16 AM	24.1	23.7	0.0	52.2			1.0	0.0	95.8	96.1
B-02R	6/15/2026 10:12:05 AM	43.3	29.5	0.8	26.4			1.5	33.0	97.6	99.9
B-03R	6/15/2026 10:20:53 AM	36.1	29.5	0.0	34.4			1.2	0.0	91.2	91.4
B-05	6/17/2026 1:59:31 PM	30.0	30.1	0.0	39.9			1.0	0.0	89.9	89.9
B-06	6/15/2026 2:05:25 PM	30.0	26.8	0.0	43.2			1.1	0.0	87.8	87.7
B-07R	6/15/2026 1:36:53 PM	50.7	33.1	0.0	16.2			1.5	0.0	96.3	97.0
B-08	6/17/2026 1:50:41 PM	26.4	27.6	0.0	46.0			1.0	0.0	90.3	90.3
B-09	6/15/2026 1:42:59 PM	46.6	33.8	0.0	19.6			1.4	0.0	99.5	99.5
B-10	6/15/2026 1:50:23 PM	34.7	31.6	0.0	33.7			1.1	0.0	96.4	96.3
B-11	6/15/2026 2:15:52 PM	42.2	33.8	0.0	24.0			1.2	0.0	101.4	101.5
B-12	6/15/2026 10:25:47 AM	27.8	28.5	0.0	43.7			1.0	0.0	96.8	96.8
B-13	6/15/2026 10:31:45 AM	45.2	33.0	0.0	21.8			1.4	0.0	90.6	90.6
B-14	6/17/2026 2:14:38 PM	38.8	32.5	0.0	28.7			1.2	0.0	103.4	104.2
C-03	6/12/2026 11:19:19 AM	58.9	36.7	1.5	2.9			1.6	1.9	109.3	103.1
C-07	6/29/2026 8:47:04 AM	49.9	34.7	1.5	13.9			1.4	9.3	90.7	90.7
C-08	6/17/2026 3:11:40 PM	57.0	40.4	0.0	2.6			1.4	0.0	108.9	108.9
C-10	6/1/2026 10:50:14 AM	56.1	42.2	0.0	1.7			1.3	0.0	98.0	99.6
C-11	6/1/2026 10:25:20 AM	55.5	38.2	0.0	6.3			1.5	0.0	89.5	89.4
C-12	6/1/2026 11:10:05 AM	62.7	37.3	0.0	0.0			1.7	0.0	92.6	93.4
C-15	6/1/2026 11:00:26 AM	34.6	18.2	11.7	35.5			1.9	3.0	93.9	94.6
C-15	6/1/2026 11:01:35 AM	29.2	14.7	13.4	42.7			2.0	3.2	94.9	94.9
C-17B	6/15/2026 10:20:29 AM	54.8	38.0	0.1	7.1			1.4	71.0	109.7	109.7
C-18	6/15/2026 10:33:37 AM	53.8	39.5	0.0	6.7			1.4	0.0	105.8	110.2

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
C-19	6/15/2026 10:26:35 AM	54.2	39.3	0.0	6.5			1.4	0.0	99.3	100.4
C-20	6/15/2026 10:30:07 AM	52.2	38.7	0.0	9.1			1.3	0.0	107.1	107.8
C-24	6/15/2026 10:23:39 AM	37.6	30.6	4.2	27.6			1.2	6.6	102.3	102.7
C-25	6/15/2026 10:14:32 AM	43.5	39.0	0.0	17.5			1.1	0.0	127.3	127.3
C-26	6/15/2026 10:11:03 AM	38.2	43.8	0.0	18.0			0.9	0.0	108.1	108.2
C-27	6/1/2026 11:07:13 AM	62.7	37.3	0.0	0.0			1.7	0.0	95.8	95.9
C-28	6/1/2026 10:21:01 AM	53.5	42.0	0.0	4.5			1.3	0.0	101.0	101.0
C-29	6/1/2026 10:34:31 AM	44.3	49.6	0.0	6.1			0.9	0.0	106.7	106.9
C-30	6/17/2026 2:55:29 PM	53.5	42.0	0.0	4.5			1.3	0.0	129.3	129.2
CV-02	6/12/2026 11:43:37 AM	43.3	34.7	0.1	21.9			1.2	219.0	123.6	123.6
CV-03	6/12/2026 11:40:58 AM	55.7	37.7	0.0	6.6			1.5	0.0	119.7	119.7
CV-04	6/12/2026 11:38:00 AM	54.3	36.8	0.4	8.5			1.5	21.3	111.2	111.3
CV-05	6/15/2026 12:39:47 PM	57.2	39.9	0.0	2.9			1.4	0.0	106.1	106.7
CV-06	6/10/2026 2:24:10 PM	55.9	44.0	0.1	0.0			1.3	0.0	98.5	98.6
CV-108-52	6/2/2026 8:10:00 AM					35					
CV-108-52	6/2/2026 8:10:00 AM						2600				
CV-108-52	6/2/2026 8:18:48 AM	49.7	46.1	0.5	3.7			1.1	7.4	76.5	76.9
CV-108-52	6/16/2026 7:54:36 AM	54.7	41.3	0.8	3.2			1.3	4.0	81.2	81.1
CV-113	6/4/2026 7:45:00 AM						32000				
CV-113	6/4/2026 7:45:00 AM					160					
CV-113	6/5/2026 10:19:11 AM	18.5	78.3	0.0	3.2			0.2	0.0	92.3	92.4
CV-113	6/17/2026 12:35:29 PM	30.7	62.5	0.0	6.9			0.5	0.0	95.7	96.1
CV-113	6/19/2026 12:51:33 PM	31.1	62.1	0.2	6.5			0.5	27.0	81.6	80.6
CV-114	6/1/2026 9:43:10 AM	11.6	74.4	0.0	14.0			0.2	0.0	188.6	110.8

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-114	6/1/2026 9:44:20 AM	11.8	77.2	0.0	11.0			0.2	0.0	188.6	188.6
CV-114	6/1/2026 9:50:00 AM						162000				
CV-114	6/1/2026 9:50:00 AM					3760					
CV-114	6/8/2026 9:22:28 AM	1.8	76.3	0.0	21.9			0.0	0.0	188.7	189.9
CV-114	6/15/2026 8:40:00 AM						0				
CV-114	6/15/2026 8:40:00 AM					400					
CV-114	6/15/2026 8:49:54 AM	8.0	79.0	0.0	13.0			0.1	0.0	190.5	190.6
CV-114	6/22/2026 8:59:44 AM	4.6	77.1	0.0	18.3			0.1	0.0	189.1	189.8
CV-114	6/29/2026 9:16:56 AM	3.4	71.9	0.0	24.7			0.0	0.0	189.6	190.3
CV-1424	6/3/2026 12:24:43 PM	51.5	40.6	0.0	7.9			1.3	0.0	106.3	106.6
CV-1424	6/19/2026 10:08:12 AM	50.4	42.1	0.0	7.5			1.2	0.0	106.9	106.9
CV-1532A	6/11/2026 10:55:34 AM	25.9	45.7	4.6	23.8			0.6	5.2	95.8	95.9
CV-1532A	6/12/2026 10:00:41 AM	22.5	47.1	4.0	26.4			0.5	6.6	96.8	96.8
CV-1532A	6/16/2026 8:55:00 AM						11000				
CV-1532A	6/16/2026 8:55:00 AM					59					
CV-1532A	6/17/2026 10:11:24 AM	39.3	52.9	5.7	2.1			0.7	0.4	87.9	87.8
CV-1532A	6/17/2026 10:11:46 AM	39.3	53.4	5.6	1.7			0.7	0.3	87.8	87.7
CV-1532A	6/17/2026 1:12:53 PM										
CV-1534A-P	6/3/2026 10:00:00 AM						136900				
CV-1534A-P	6/3/2026 10:01:37 AM	15.8	68.8	2.2	13.2			0.2	6.0	188.4	188.9
CV-1534A-P	6/3/2026 10:04:58 AM	15.3	70.8	1.8	12.1			0.2	6.7	186.0	186.4
CV-1534A-P	6/10/2026 10:19:33 AM	18.3	70.4	0.0	11.3			0.3	0.0	150.8	156.6
CV-1534A-P	6/17/2026 9:37:43 AM	1.7	79.4	0.0	18.9			0.0	0.0	139.2	132.5

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-1535	6/2/2026 8:13:51 AM	46.7	51.9	0.0	1.4			0.9	0.0	121.5	120.2
CV-1535	6/15/2026 10:05:00 AM					91					
CV-1535	6/15/2026 10:05:00 AM						8900				
CV-1535	6/16/2026 7:47:10 AM	47.4	51.8	0.0	0.8			0.9	0.0	116.6	116.9
CV-1601D	6/1/2026 10:26:12 AM	46.3	45.1	0.3	8.3			1.0	27.7	113.9	113.9
CV-1601D	6/17/2026 11:48:50 AM	52.8	42.9	0.7	3.6			1.2	5.1	116.2	116.0
CV-1601S	6/1/2026 10:23:27 AM	48.2	45.6	0.0	6.2			1.1	0.0	110.7	108.2
CV-1601S	6/17/2026 11:45:15 AM	53.9	44.6	0.0	1.5			1.2	0.0	110.1	113.5
CV-1604	6/3/2026 11:55:24 AM	52.4	41.6	0.0	6.0			1.3	0.0	128.1	127.9
CV-1701D	6/3/2026 9:34:02 AM	9.0	64.8	0.0	26.2			0.1	0.0	86.9	90.2
CV-1701S	6/3/2026 9:28:58 AM	27.2	64.9	0.0	7.9			0.4	0.0	142.0	138.4
CV-1701S	6/3/2026 9:29:59 AM	27.5	65.1	0.0	7.4			0.4	0.0	136.6	136.2
CV-1901	6/1/2026 2:11:40 PM	15.0	72.5	0.0	12.5			0.2	0.0	109.7	109.8
CV-1901	6/17/2026 9:45:56 AM	17.6	71.8	0.0	10.6			0.2	0.0	107.9	107.3
CV-1902A	6/3/2026 9:06:07 AM	13.6	77.6	0.2	8.6			0.2	43.0	164.2	162.4
CV-1902A	6/3/2026 9:06:48 AM	11.7	75.8	0.0	12.5			0.2	0.0	161.4	162.4
CV-1902A	6/3/2026 9:10:00 AM						158400				
CV-1902A	6/10/2026 9:19:44 AM	18.9	76.2	0.0	4.9			0.2	0.0	168.7	169.5
CV-1902A	6/12/2026 8:25:30 AM										
CV-1902A	6/16/2026 9:20:00 AM					810					
CV-1902A	6/16/2026 9:20:00 AM						190000				
CV-1902A	6/17/2026 8:55:02 AM	2.0	76.6	0.0	21.4			0.0	0.0	162.8	162.9
CV-1902A	6/24/2026 1:28:33 PM	10.2	73.7	0.0	16.1			0.1	0.0	169.5	167.2
CV-1905	6/4/2026 8:18:33 AM	54.4	40.3	0.0	5.3			1.3	0.0	112.7	112.7
CV-1905	6/8/2026 12:30:27 PM										
CV-1905	6/9/2026 12:51:17 PM	54.3	42.1	0.0	3.6			1.3	0.0	113.7	113.9
CV-1905	6/16/2026 11:18:39 AM										
CV-1905	6/16/2026 11:19:38 AM										
CV-1905	6/16/2026 11:21:07 AM										
CV-1905	6/16/2026 12:30:54 PM										
CV-2001	6/6/2026 7:44:37 AM										
CV-2001	6/10/2026 8:24:20 AM	11.6	73.3	0.2	14.9			0.2	74.5	88.8	89.2

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2001	6/10/2026 3:52:07 PM										
CV-2001	6/10/2026 3:52:18 PM										
CV-2001	6/16/2026 8:10:00 AM					990					
CV-2001	6/16/2026 8:10:00 AM						79000				
CV-2001	6/17/2026 8:30:39 AM	10.8	76.4	0.9	11.9			0.1	13.2	90.5	90.5
CV-2001	6/18/2026 2:34:40 PM										
CV-2001	6/18/2026 2:34:54 PM										
CV-2001	6/19/2026 12:17:40 PM										
CV-2001	6/24/2026 1:53:55 PM										
CV-2001	6/30/2026 1:20:37 PM										
CV-2001	6/30/2026 1:20:54 PM										
CV-2002	6/2/2026 8:20:00 AM					3200					
CV-2002	6/2/2026 8:20:00 AM						150000				
CV-2002	6/3/2026 9:45:00 AM						136000				
CV-2002	6/3/2026 9:49:56 AM	30.2	69.6	0.2	0.0			0.4	0.0	183.4	183.8
CV-2002	6/3/2026 9:50:58 AM	30.0	70.0	0.0	0.0			0.4	0.0	183.9	183.9
CV-2002	6/10/2026 1:36:51 PM	30.4	69.5	0.1	0.0			0.4	0.0	183.8	184.0
CV-2002	6/19/2026 3:46:32 PM	13.8	75.1	0.1	11.0			0.2	110.0	184.5	184.5
CV-2002	6/19/2026 3:47:45 PM	13.6	78.7	0.0	7.7			0.2	0.0	183.8	183.8
CV-2003	6/2/2026 8:25:55 AM	9.6	41.8	10.5	38.1			0.2	3.6	103.6	103.3
CV-2003	6/2/2026 8:27:03 AM	8.9	40.3	10.4	40.4			0.2	3.9	103.9	103.3
CV-2003	6/16/2026 7:56:51 AM	18.7	69.7	0.0	11.6			0.3	0.0	114.6	115.9
CV-2006	6/3/2026 9:12:33 AM	14.6	77.5	0.0	7.9			0.2	0.0	188.0	188.0
CV-2006	6/3/2026 9:20:00 AM						179800				
CV-2006	6/10/2026 9:32:53 AM	16.6	66.9	0.0	16.5			0.2	0.0	186.2	187.5
CV-2006	6/17/2026 8:49:42 AM	1.1	76.3	0.0	22.6			0.0	0.0	187.6	187.7
CV-2006	6/24/2026 1:42:38 PM	9.0	76.5	0.0	14.5			0.1	0.0	188.3	188.3
CV-2007	6/4/2026 8:55:00 AM						65000				
CV-2007	6/4/2026 8:55:00 AM					1100					
CV-2007	6/4/2026 10:45:16 AM	16.0	78.3	0.0	5.7			0.2	0.0	102.0	102.0
CV-2007	6/5/2026 10:16:34 AM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2007	6/23/2026 10:08:32 AM	12.5	39.5	10.0	38.0			0.3	3.8	125.9	125.6
CV-2008	6/4/2026 1:53:28 PM	28.9	67.6	0.8	2.7			0.4	3.4	105.9	106.4
CV-2008	6/5/2026 1:00:43 PM										
CV-2008	6/23/2026 9:59:12 AM	30.6	69.4	0.0	0.0			0.4	0.0	103.5	101.8
CV-2009	6/23/2026 10:05:54 AM										
CV-2009	6/25/2026 9:27:32 AM	45.2	51.6	0.0	3.2			0.9	0.0	135.2	134.3
CV-2009	6/25/2026 9:43:11 AM	42.9	53.7	0.0	3.4			0.8	0.0	133.4	133.4
CV-2009	6/25/2026 9:45:41 AM	42.8	54.8	0.0	2.4			0.8	0.0	131.6	129.8
CV-2009A	6/4/2026 7:11:53 AM										
CV-2009A	6/4/2026 7:37:11 AM										
CV-2009A	6/4/2026 8:22:33 AM										
CV-2009A	6/8/2026 11:36:43 AM	43.1	56.8	0.0	0.1			0.8	0.0	117.8	117.4
CV-2010	6/2/2026 11:42:01 AM	41.9	52.9	0.0	5.2			0.8	0.0	84.8	87.4
CV-2010	6/16/2026 1:15:18 PM										
CV-2010A	6/2/2026 11:38:03 AM	46.4	45.6	0.0	8.0			1.0	0.0	138.7	82.9
CV-2010A	6/2/2026 11:38:57 AM	47.0	46.7	0.0	6.3			1.0	0.0	138.7	138.7
CV-2011	6/2/2026 12:12:48 PM	51.1	43.4	0.0	5.5			1.2	0.0	128.9	128.9
CV-2011A	6/4/2026 8:34:54 AM	24.2	54.5	0.0	21.3			0.4	0.0	147.5	149.2
CV-2011A	6/8/2026 2:38:46 PM	37.9	60.7	0.0	1.4			0.6	0.0	148.8	148.9
CV-2011A	6/17/2026 2:55:43 PM	28.6	55.3	0.0	16.1			0.5	0.0	153.4	153.4
CV-2011A	6/29/2026 1:24:17 PM	19.9	53.9	0.0	26.2			0.4	0.0	153.3	152.6
CV-2011A	6/29/2026 1:35:03 PM	19.9	54.0	0.0	26.1			0.4	0.0	152.1	152.4
CV-2011A	6/29/2026 1:37:30 PM	20.1	54.1	0.0	25.8			0.4	0.0	152.4	152.4
CV-2011A	6/29/2026 3:02:00 PM	32.0	53.4	0.0	14.6			0.6	0.0	152.5	153.1
CV-2011A	6/29/2026 3:04:06 PM	31.9	55.2	0.0	12.9			0.6	0.0	153.2	153.1

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2012	6/15/2026 11:50:00 AM	41.1	52.8	0.0	6.1			0.8	0.0	138.7	134.7
CV-2012	6/15/2026 11:51:03 AM	40.5	52.3	0.0	7.2			0.8	0.0	134.7	134.5
CV-2012	6/18/2026 1:09:41 PM										
CV-2201-PLF	6/2/2026 7:48:50 AM	3.8	78.5	0.4	17.3			0.0	43.3	124.9	124.3
CV-2201-PLF	6/17/2026 8:46:18 AM	3.3	79.1	0.2	17.4			0.0	87.0	128.8	129.6
CV-2204-PLF	6/1/2026 1:17:53 PM	21.5	75.6	0.1	2.8			0.3	28.0	151.5	150.7
CV-2204-PLF	6/1/2026 1:25:00 PM						135900				
CV-2204-PLF	6/1/2026 1:25:00 PM					2500					
CV-2204-PLF	6/8/2026 1:18:27 PM	8.2	78.1	0.1	13.6			0.1	136.0	189.2	189.2
CV-2204-PLF	6/15/2026 9:45:45 AM	23.4	73.3	0.0	3.3			0.3	0.0	192.5	192.5
CV-2204-PLF	6/22/2026 10:24:57 AM	15.0	76.4	0.0	8.6			0.2	0.0	190.8	191.1
CV-2204-PLF	6/30/2026 8:26:20 AM	7.0	74.2	0.0	18.8			0.1	0.0	190.4	190.5
CV-2205	6/2/2026 1:19:30 PM	37.8	53.2	0.0	9.0			0.7	0.0	124.1	114.0
CV-2205	6/26/2026 10:37:39 AM										
CV-2207	6/8/2026 11:43:16 AM	39.5	59.0	0.0	1.5			0.7	0.0	120.9	121.0
CV-2208A	6/8/2026 10:08:38 AM	33.7	66.3	0.0	0.0			0.5	0.0	129.4	129.5
CV-2301	6/2/2026 2:24:23 PM	39.8	60.0	0.2	0.0			0.7	0.0	170.0	168.0
CV-2301	6/2/2026 2:25:00 PM						107800				
CV-2301	6/2/2026 2:25:00 PM					1710					
CV-2301	6/3/2026 7:00:00 AM						110000				
CV-2301	6/3/2026 7:00:00 AM					1400					
CV-2301	6/9/2026 1:50:33 PM	39.9	60.1	0.0	0.0			0.7	0.0	167.4	167.5
CV-2301	6/12/2026 9:50:08 AM										
CV-2301	6/16/2026 1:36:56 PM	45.7	54.2	0.1	0.0			0.8	0.0	169.2	169.1
CV-2301	6/16/2026 1:39:12 PM	42.2	57.4	0.4	0.0			0.7	0.0	169.0	88.3
CV-2301	6/23/2026 2:37:21 PM	21.2	72.0	1.3	5.5			0.3	4.2	172.0	172.4
CV-2301	6/23/2026 2:39:33 PM	19.5	47.7	8.6	24.2			0.4	2.8	175.2	169.0
CV-2301	6/23/2026 3:00:42 PM	30.1	69.9	0.0	0.0			0.4	0.0	172.4	173.2
CV-2301	6/24/2026 1:34:16 PM	3.2	82.9	0.0	13.9			0.0	0.0	124.4	153.3

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2301	6/24/2026 1:35:48 PM	3.0	82.7	0.0	14.3			0.0	0.0	164.1	163.4
CV-2301	6/30/2026 10:24:56 AM	5.4	2.1	19.3	73.2			2.6	3.8	176.6	165.8
CV-2301	6/30/2026 10:28:52 AM	39.7	47.8	2.4	10.1			0.8	4.2	157.8	160.0
CV-2301	6/30/2026 10:30:41 AM	28.9	60.2	1.7	9.2			0.5	5.4	158.2	158.0
CV-2302	6/3/2026 7:10:00 AM						42000				
CV-2302	6/3/2026 7:10:00 AM					260					
CV-2302	6/3/2026 9:51:38 AM	42.0	53.4	0.3	4.3			0.8	14.3	117.3	117.3
CV-2302	6/16/2026 9:54:51 AM	45.0	49.7	0.8	4.5			0.9	5.6	117.4	118.2
CV-2302	6/25/2026 1:56:10 PM										
CV-2303	6/2/2026 10:35:06 AM	20.6	73.5	0.0	5.9			0.3	0.0	188.1	186.7
CV-2303	6/2/2026 10:40:00 AM						174400				
CV-2303	6/2/2026 10:40:00 AM					2790					
CV-2303	6/3/2026 7:15:00 AM					2300					
CV-2303	6/3/2026 7:15:00 AM						190000				
CV-2303	6/5/2026 9:12:02 AM										
CV-2303	6/9/2026 9:49:45 AM	16.3	78.0	0.0	5.7			0.2	0.0	195.9	196.1
CV-2303	6/9/2026 9:50:35 AM	18.1	78.3	0.0	3.6			0.2	0.0	196.4	196.5
CV-2303	6/16/2026 9:48:16 AM	14.2	74.2	0.0	11.6			0.2	0.0	200.5	200.6
CV-2303	6/16/2026 9:50:23 AM	14.3	69.5	0.0	16.2			0.2	0.0	199.2	199.2
CV-2303	6/23/2026 10:25:28 AM	8.4	73.7	0.0	17.9			0.1	0.0	169.8	166.6
CV-2303	6/29/2026 9:39:04 AM	1.4	79.6	0.2	18.8			0.0	94.0	191.2	191.6
CV-2304	6/2/2026 2:13:16 PM	17.0	75.2	0.0	7.8			0.2	0.0	168.3	169.1
CV-2304	6/2/2026 2:15:00 PM						183900				
CV-2304	6/2/2026 2:15:00 PM					1680					
CV-2304	6/9/2026 1:09:40 PM	10.7	66.4	0.0	22.9			0.2	0.0	167.0	164.4

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2304	6/16/2026 1:08:11 PM	19.8	75.5	0.0	4.7			0.3	0.0	165.5	165.5
CV-2304	6/16/2026 2:57:49 PM	1.0	72.3	0.0	26.8			0.0	0.0	166.0	165.7
CV-2304	6/16/2026 2:58:50 PM	0.8	73.3	0.0	25.8			0.0	0.0	166.1	166.2
CV-2304	6/23/2026 2:09:03 PM	15.6	70.7	0.0	13.7			0.2	0.0	164.4	164.6
CV-2304	6/29/2026 12:19:53 PM	2.2	78.9	0.0	18.9			0.0	0.0	165.8	166.5
CV-2305	6/2/2026 2:54:55 PM	24.2	63.4	0.0	12.4			0.4	0.0	150.6	150.7
CV-2305	6/2/2026 3:00:00 PM						60700				
CV-2305	6/2/2026 3:00:00 PM					1870					
CV-2305	6/11/2026 9:25:45 AM	38.0	61.2	0.0	0.8			0.6	0.0	160.3	160.3
CV-2305	6/12/2026 8:25:00 AM						28000				
CV-2305	6/12/2026 8:25:00 AM					500					
CV-2305	6/17/2026 1:34:44 PM	21.3	56.2	0.0	22.5			0.4	0.0	159.3	159.4
CV-2305	6/24/2026 8:18:10 AM	43.8	51.2	0.0	5.0			0.9	0.0	158.7	158.8
CV-2306	6/1/2026 10:56:19 AM	24.7	75.3	0.0	0.0			0.3	0.0	152.2	153.4
CV-2306	6/1/2026 11:00:00 AM					1370					
CV-2306	6/1/2026 11:00:00 AM						163300				
CV-2306	6/8/2026 10:21:46 AM	5.4	76.5	0.0	18.1			0.1	0.0	139.6	137.3
CV-2306	6/22/2026 10:15:40 AM	17.3	74.2	0.0	8.5			0.2	0.0	160.2	161.4
CV-2306	6/30/2026 8:15:59 AM	8.3	77.5	0.2	14.0			0.1	70.0	155.5	151.7
CV-2306	6/30/2026 8:18:07 AM	7.4	76.5	0.0	16.1			0.1	0.0	151.0	150.9
CV-2308-PLF	6/2/2026 7:55:47 AM	5.7	77.9	0.2	16.2			0.1	81.0	143.3	142.2
CV-2308-PLF	6/2/2026 7:57:50 AM	6.3	78.4	0.0	15.3			0.1	0.0	143.4	144.4
CV-2308-PLF	6/17/2026 8:50:24 AM	5.2	78.7	0.1	16.0			0.1	160.0	142.5	142.2
CV-2308-PLF	6/17/2026 8:51:38 AM	5.5	78.7	0.0	15.8			0.1	0.0	142.4	142.9

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2310-PLF	6/2/2026 1:53:08 PM	23.2	73.4	0.2	3.2			0.3	16.0	196.3	196.4
CV-2310-PLF	6/2/2026 2:00:00 PM						162900				
CV-2310-PLF	6/2/2026 2:00:00 PM					2050					
CV-2310-PLF	6/9/2026 10:24:42 AM	18.5	75.9	0.2	5.4			0.2	27.0	197.3	197.4
CV-2310-PLF	6/16/2026 10:11:01 AM	19.2	72.7	0.4	7.7			0.3	19.3	195.7	195.7
CV-2310-PLF	6/23/2026 10:49:46 AM	14.7	74.0	0.0	11.3			0.2	0.0	193.9	194.2
CV-2310-PLF	6/29/2026 10:01:07 AM	2.2	81.2	0.0	16.6			0.0	0.0	195.7	196.0
CV-2311	6/2/2026 9:00:00 AM					1810					
CV-2311	6/2/2026 9:18:43 AM	26.0	67.7	0.0	6.3			0.4	0.0	156.1	155.6
CV-2311	6/2/2026 9:20:00 AM						94700				
CV-2311	6/9/2026 9:07:08 AM	23.1	68.2	0.0	8.7			0.3	0.0	168.1	166.4
CV-2311	6/16/2026 9:00:16 AM	20.9	67.7	0.0	11.4			0.3	0.0	172.9	171.6
CV-2311	6/23/2026 9:40:13 AM	13.9	68.8	0.0	17.3			0.2	0.0	171.3	171.0
CV-2311	6/30/2026 9:24:01 AM	3.8	73.8	0.0	22.4			0.1	0.0	157.1	155.9
CV-2311	6/30/2026 9:25:40 AM	20.9	65.4	0.0	13.7			0.3	0.0	157.2	157.0
CV-2312	6/2/2026 2:45:00 PM						121700				
CV-2312	6/2/2026 2:45:00 PM					2900					
CV-2312	6/2/2026 2:47:24 PM	14.7	75.5	0.2	9.6			0.2	48.0	169.2	169.2
CV-2312	6/10/2026 2:01:28 PM	9.7	79.1	0.0	11.2			0.1	0.0	167.1	167.3
CV-2312	6/11/2026 7:30:00 AM						150000				
CV-2312	6/11/2026 7:30:00 AM					2700					
CV-2312	6/24/2026 10:00:40 AM	11.8	75.8	12.4	0.0			0.2	0.0	165.6	166.2
CV-2312	6/30/2026 1:42:08 PM	30.0	70.0	0.0	0.0			0.4	0.0	166.5	166.6
CV-2312	6/30/2026 1:48:19 PM	26.8	69.7	0.0	3.5			0.4	0.0	166.4	166.8

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2312	6/30/2026 1:49:32 PM	14.0	76.6	0.0	9.4			0.2	0.0	167.0	166.7
CV-2314	6/3/2026 1:41:34 PM	18.6	79.4	0.0	2.0			0.2	0.0	178.5	178.9
CV-2314	6/3/2026 1:55:00 PM						110800				
CV-2314	6/10/2026 2:47:57 PM	12.9	80.4	0.2	6.5			0.2	32.5	177.5	178.4
CV-2314	6/10/2026 2:50:12 PM	12.9	81.2	0.0	5.9			0.2	0.0	180.9	179.9
CV-2314	6/12/2026 8:30:00 AM					1700					
CV-2314	6/12/2026 8:30:00 AM						74000				
CV-2314	6/17/2026 2:43:32 PM	1.0	75.4	2.0	21.6			0.0	10.8	180.0	182.3
CV-2314	6/17/2026 2:44:23 PM	0.9	77.0	0.5	21.6			0.0	43.2	181.9	181.6
CV-2314	6/19/2026 11:52:39 AM	0.5	85.1	0.8	13.6			0.0	17.0	177.3	181.1
CV-2314	6/19/2026 11:54:02 AM	0.5	85.4	0.2	13.9			0.0	69.5	180.9	180.9
CV-2314	6/24/2026 9:02:40 AM	7.4	80.6	0.1	11.9			0.1	119.0	181.1	181.1
CV-2314	6/30/2026 2:06:51 PM	38.7	61.3	0.0	0.0			0.6	0.0	180.0	181.5
CV-2314	6/30/2026 2:08:30 PM	10.3	76.1	0.0	13.6			0.1	0.0	181.6	181.5
CV-2315	6/1/2026 1:23:23 PM	26.1	73.9	0.0	0.0			0.4	0.0	183.4	183.4
CV-2315	6/1/2026 1:30:00 PM					2310					
CV-2315	6/1/2026 1:30:00 PM						92400				
CV-2315	6/3/2026 7:25:00 AM						120000				
CV-2315	6/3/2026 7:25:00 AM					2700					
CV-2315	6/8/2026 1:23:19 PM	15.2	80.1	0.1	4.6			0.2	46.0	183.8	183.8
CV-2315	6/15/2026 9:49:34 AM	28.2	71.7	0.0	0.1			0.4	0.0	171.0	172.9
CV-2315	6/22/2026 1:34:17 PM	16.4	74.5	0.0	9.1			0.2	0.0	188.1	188.2
CV-2315	6/25/2026 2:43:59 PM										
CV-2315	6/30/2026 2:44:21 PM	16.4	76.2	0.0	7.4			0.2	0.0	185.1	185.0
CV-2316	6/4/2026 10:21:45 AM	19.4	65.9	0.0	14.7			0.3	0.0	140.9	140.0
CV-2316	6/4/2026 11:20:47 AM										
CV-2316	6/4/2026 12:46:18 PM										
CV-2316	6/17/2026 8:51:12 AM										
CV-2316	6/23/2026 9:53:03 AM	6.0	80.0	0.0	14.0			0.1	0.0	147.3	147.3

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2316	6/23/2026 9:54:14 AM	9.7	79.1	0.0	11.2			0.1	0.0	147.4	147.5
CV-2316	6/23/2026 3:11:49 PM	22.5	68.4	0.0	9.1			0.3	0.0	148.1	148.1
CV-2316	6/23/2026 3:12:16 PM	23.6	71.6	0.0	4.8			0.3	0.0	148.1	148.2
CV-2319	6/12/2026 1:24:57 PM	27.4	68.6	0.1	3.9			0.4	39.0	145.1	145.7
CV-2319	6/12/2026 1:27:27 PM	20.6	71.1	0.0	8.3			0.3	0.0	145.5	145.4
CV-2319	6/15/2026 1:14:28 PM	18.6	71.7	0.2	9.5			0.3	47.5	145.1	144.9
CV-2319	6/15/2026 1:16:00 PM	21.1	67.6	0.2	11.1			0.3	55.5	144.9	144.9
CV-2319	6/21/2026 2:21:21 PM	31.7	68.3	0.0	0.0			0.5	0.0	144.3	144.6
CV-2321	6/3/2026 9:02:48 AM	23.6	66.6	0.5	9.3			0.4	18.6	144.4	144.6
CV-2321	6/3/2026 9:04:13 AM	19.1	69.2	0.3	11.4			0.3	38.0	144.7	144.7
CV-2321	6/22/2026 8:15:36 AM	16.1	74.6	0.2	9.1			0.2	45.5	146.3	146.6
CV-2321	6/22/2026 8:17:15 AM	8.8	79.0	0.1	12.1			0.1	121.0	146.8	146.8
CV-2322	6/4/2026 8:16:40 AM	1.6	84.6	0.0	13.8			0.0	0.0	81.1	81.4
CV-2322	6/29/2026 10:13:50 AM	0.0	1.0	20.4	78.6			0.0	3.9	74.0	74.9
CV-2322	6/29/2026 10:17:01 AM	0.0	1.0	20.2	78.8			0.0	3.9	74.5	74.4
CV-2324	6/2/2026 12:01:10 PM	49.7	45.8	0.0	4.5			1.1	0.0	122.8	122.9
CV-2326	6/4/2026 12:14:04 PM	3.5	76.6	0.0	19.9			0.0	0.0	163.1	163.4
CV-2326	6/4/2026 12:15:55 PM	3.4	78.0	0.0	18.6			0.0	0.0	163.8	163.9
CV-2326	6/11/2026 10:04:53 AM	18.3	77.3	0.0	4.4			0.2	0.0	167.6	167.6
CV-2326	6/16/2026 9:13:00 AM	17.7	72.0	0.0	10.3			0.2	0.0	161.1	161.1
CV-2326	6/23/2026 10:15:57 AM	17.8	72.8	1.0	8.4			0.2	8.4	168.3	168.3
CV-2326	6/30/2026 9:30:30 AM	20.8	64.8	0.0	14.4			0.3	0.0	170.0	169.9
CV-2327	6/3/2026 1:18:30 PM	19.4	79.8	0.0	0.8			0.2	0.0	183.1	183.3

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2327	6/3/2026 1:20:00 PM						119800				
CV-2327	6/9/2026 2:30:10 PM	9.3	74.6	0.0	16.1			0.1	0.0	179.8	180.3
CV-2327	6/16/2026 2:36:43 PM	9.4	76.0	0.0	14.6			0.1	0.0	184.7	184.8
CV-2327	6/24/2026 9:35:33 AM	11.9	78.8	0.0	9.3			0.2	0.0	185.2	185.3
CV-2327	6/29/2026 1:11:01 PM	6.8	80.6	0.0	12.6			0.1	0.0	186.6	186.7
CV-2328	6/2/2026 2:33:14 PM	40.6	59.4	0.0	0.0			0.7	0.0	156.8	157.2
CV-2328	6/2/2026 2:35:00 PM					1010					
CV-2328	6/2/2026 2:35:00 PM						75000				
CV-2328	6/9/2026 2:20:39 PM	33.0	67.0	0.0	0.0			0.5	0.0	157.7	158.2
CV-2328	6/12/2026 8:45:00 AM					200					
CV-2328	6/12/2026 8:45:00 AM						22000				
CV-2328	6/16/2026 2:19:24 PM	30.8	69.2	0.0	0.0			0.4	0.0	173.3	173.3
CV-2328	6/24/2026 9:52:31 AM	35.8	64.2	0.0	0.0			0.6	0.0	167.2	167.2
CV-2328	6/30/2026 1:37:04 PM	7.5	80.9	0.0	11.6			0.1	0.0	163.1	165.2
CV-2328	6/30/2026 1:38:00 PM	19.1	78.1	0.0	2.8			0.2	0.0	165.6	165.6
CV-2333	6/1/2026 9:34:06 AM	7.3	77.2	0.0	15.5			0.1	0.0	186.9	186.9
CV-2333	6/1/2026 9:45:00 AM						181900				
CV-2333	6/1/2026 9:45:00 AM					4810					
CV-2333	6/3/2026 8:00:00 AM						200000				
CV-2333	6/3/2026 8:00:00 AM					4200					
CV-2333	6/8/2026 9:19:09 AM	1.1	76.7	0.0	22.2			0.0	0.0	187.2	187.4
CV-2333	6/15/2026 8:45:46 AM	4.5	79.6	0.0	15.9			0.1	0.0	190.7	190.8
CV-2333	6/15/2026 8:46:36 AM	4.4	77.9	0.0	17.7			0.1	0.0	190.8	190.5
CV-2333	6/16/2026 8:27:48 AM	1.8	70.9	1.0	26.3			0.0	26.3	158.3	161.2
CV-2333	6/16/2026 8:29:05 AM	1.6	78.1	0.4	19.9			0.0	49.8	162.6	162.5
CV-2333	6/22/2026 8:54:06 AM	3.7	74.1	0.0	22.2			0.0	0.0	162.4	162.5
CV-2333	6/24/2026 10:41:33 AM										
CV-2333	6/29/2026 9:12:38 AM	5.8	77.7	0.0	16.5			0.1	0.0	191.0	191.1

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2334	6/2/2026 8:24:06 AM										
CV-2334	6/3/2026 8:05:00 AM					1200					
CV-2334	6/3/2026 8:05:00 AM						30000				
CV-2334	6/4/2026 2:15:28 PM	0.1	0.8	20.7	78.4			0.1	3.8	128.7	128.8
CV-2334	6/11/2026 9:30:32 AM										
CV-2334	6/17/2026 1:21:10 PM	9.4	75.7	0.0	14.8			0.1	741.5	133.3	133.4
CV-2334	6/17/2026 1:22:09 PM	9.5	74.7	0.0	15.8			0.1	0.0	133.3	133.2
CV-2334	6/18/2026 3:46:54 PM										
CV-2334	6/18/2026 3:47:04 PM										
CV-2334	6/19/2026 10:47:23 AM										
CV-2334	6/19/2026 12:10:06 PM	11.5	82.4	0.5	5.6			0.1	11.2	128.5	125.9
CV-2334	6/23/2026 12:31:40 PM										
CV-2334	6/26/2026 11:23:08 AM										
CV-2334	6/26/2026 11:23:21 AM										
CV-2334	6/30/2026 11:19:30 AM										
CV-2334	6/30/2026 11:19:42 AM										
CV-2335	6/1/2026 2:02:30 PM	48.3	49.9	0.2	1.6			1.0	8.0	100.5	100.7
CV-2335	6/17/2026 9:29:31 AM	49.8	46.0	0.0	4.2			1.1	0.0	99.0	98.9
CV-2335	6/24/2026 7:34:08 AM										
CV-2336	6/1/2026 2:07:58 PM	45.3	53.7	0.0	1.0			0.8	0.0	88.9	89.0
CV-2336	6/10/2026 3:30:15 PM										
CV-2336	6/10/2026 3:30:26 PM										
CV-2336	6/11/2026 1:32:50 PM	25.4	62.1	0.0	12.5			0.4	0.0	95.0	94.9
CV-2336	6/11/2026 1:33:49 PM	25.6	62.1	0.0	12.3			0.4	0.0	95.0	95.0
CV-2336	6/11/2026 2:58:42 PM										
CV-2336	6/11/2026 3:00:37 PM										
CV-2336	6/17/2026 9:40:23 AM	16.0	58.8	4.5	20.7			0.3	4.6	74.6	73.6
CV-2336	6/18/2026 1:52:32 PM										
CV-2336	6/18/2026 1:52:47 PM										
CV-2336	6/18/2026 1:53:26 PM										
CV-2336	6/24/2026 6:58:14 AM										
CV-2336	6/24/2026 1:36:33 PM										
CV-2336	6/24/2026 1:36:43 PM										
CV-2336	6/26/2026 2:08:07 PM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2336	6/26/2026 2:08:18 PM										
CV-2337	6/1/2026 2:16:10 PM	4.7	81.3	0.1	13.9			0.1	139.0	150.7	150.8
CV-2337	6/3/2026 9:16:44 AM	23.0	77.0	0.0	0.0			0.3	0.0	151.0	151.1
CV-2337	6/3/2026 9:25:00 AM						92900				
CV-2337	6/10/2026 9:39:16 AM	25.4	74.6	0.0	0.0			0.3	0.0	151.6	151.9
CV-2337	6/16/2026 9:15:00 AM						120000				
CV-2337	6/16/2026 9:15:00 AM					3500					
CV-2337	6/17/2026 8:43:10 AM	5.3	81.5	0.0	13.2			0.1	0.0	152.5	152.5
CV-2337	6/24/2026 1:53:56 PM	21.1	74.5	0.0	4.4			0.3	0.0	151.7	151.6
CV-2338	6/3/2026 9:09:28 AM	13.8	75.5	0.0	10.7			0.2	0.0	166.2	168.8
CV-2338	6/3/2026 9:15:00 AM						182000				
CV-2338	6/10/2026 9:25:38 AM	20.9	76.2	0.0	2.9			0.3	0.0	186.4	186.3
CV-2338	6/17/2026 8:52:13 AM	1.7	77.7	0.0	20.6			0.0	0.0	168.8	170.2
CV-2338	6/24/2026 1:31:30 PM	9.0	74.1	0.0	16.9			0.1	0.0	183.6	184.2
CV-2338	6/24/2026 1:32:33 PM	10.5	73.8	0.0	15.7			0.1	0.0	183.4	183.3
CV-2339	6/11/2026 9:42:14 AM	0.5	21.2	14.7	63.6			0.0	4.3	96.4	96.5
CV-2339	6/11/2026 9:45:19 AM	0.5	18.6	15.2	65.7			0.0	4.3	98.4	98.4
CV-2339	6/12/2026 8:58:58 AM	2.5	28.5	12.5	56.5			0.1	4.5	91.6	94.0
CV-2339	6/12/2026 9:04:45 AM	13.6	38.8	9.9	37.7			0.4	3.8	97.1	97.6
CV-2339	6/12/2026 9:10:50 AM	25.3	39.6	9.4	25.7			0.6	2.7	99.7	99.7
CV-2339	6/18/2026 1:42:24 PM										
CV-2339	6/18/2026 1:42:35 PM										
CV-2339	6/19/2026 1:58:28 PM	0.6	40.3	10.4	48.7			0.0	4.7	142.3	146.2
CV-2339	6/19/2026 2:03:58 PM	0.5	37.6	11.2	50.7			0.0	4.5	151.8	147.2
CV-2339	6/22/2026 2:45:17 PM	8.8	23.1	15.3	52.8			0.4	3.5	152.5	154.3
CV-2339	6/22/2026 2:47:20 PM	7.6	48.1	7.4	36.9			0.2	5.0	158.8	160.9
CV-2339	6/23/2026 12:28:36 PM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2339	6/24/2026 1:48:55 PM										
CV-2339	6/24/2026 1:49:06 PM										
CV-2339	6/26/2026 3:51:11 PM										
CV-2339	6/26/2026 3:51:22 PM										
CV-2341	6/6/2026 1:00:12 PM										
CV-2341	6/11/2026 9:35:24 AM	11.9	62.1	2.3	23.7			0.2	10.3	99.6	101.1
CV-2341	6/11/2026 3:32:00 PM	7.9	72.0	1.7	18.4			0.1	10.8	107.1	107.1
CV-2341	6/15/2026 10:15:00 AM					860					
CV-2341	6/15/2026 10:15:00 AM						150000				
CV-2341	6/22/2026 11:40:09 AM	13.6	67.0	1.1	18.3			0.2	16.6	107.2	106.5
CV-2341	6/24/2026 1:54:00 PM										
CV-2341	6/24/2026 1:54:47 PM										
CV-2341	6/25/2026 1:45:13 PM	1.6	70.3	0.6	27.5			0.0	45.8	96.2	96.2
CV-2341	6/26/2026 3:49:24 PM										
CV-2341	6/26/2026 3:49:37 PM										
CV-2342A-P	6/3/2026 12:53:12 PM	31.9	68.1	0.0	0.0			0.5	0.0	168.1	166.8
CV-2342A-P	6/3/2026 1:00:00 PM						203800				
CV-2342A-P	6/10/2026 10:44:45 AM	21.4	64.1	0.0	14.5			0.3	0.0	155.8	158.1
CV-2342A-P	6/17/2026 9:53:50 AM	23.9	73.3	0.6	2.2			0.3	3.7	184.2	183.4
CV-2342A-P	6/17/2026 9:54:24 AM	21.5	70.0	0.9	7.6			0.3	8.4	185.0	184.8
CV-2343	6/15/2026 9:19:39 AM	0.7	79.3	0.0	20.0			0.0	0.0	165.1	166.0
CV-2343	6/15/2026 9:20:00 AM	0.7	79.5	0.0	19.8			0.0	0.0	167.7	168.2
CV-2343	6/17/2026 2:09:17 PM	1.3	79.6	0.0	19.1			0.0	0.0	162.9	162.2
CV-2343	6/17/2026 2:11:09 PM	1.4	77.0	0.0	21.6			0.0	0.0	163.9	164.2
CV-2343	6/19/2026 11:11:56 AM	1.5	84.3	0.0	14.2			0.0	0.0	164.4	164.6
CV-2343	6/19/2026 11:16:28 AM	1.8	83.3	0.0	14.9			0.0	0.0	168.1	167.0
CV-2344	6/2/2026 8:00:00 AM						160000				
CV-2344	6/2/2026 8:00:00 AM					3200					
CV-2344	6/2/2026 8:40:05 AM	2.2	75.5	1.0	21.3			0.0	21.3	139.8	140.0
CV-2344	6/2/2026 8:41:11 AM	0.4	78.2	1.0	20.4			0.0	20.4	140.6	140.7
CV-2344	6/10/2026 10:48:47 AM	5.7	76.2	0.1	18.0			0.1	180.0	169.5	169.8

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2344	6/10/2026 10:51:49 AM	4.1	81.1	0.0	14.8			0.1	0.0	170.5	170.1
CV-2344	6/11/2026 10:41:23 AM	12.2	67.5	0.0	20.3			0.2	0.0	165.6	166.7
CV-2344	6/11/2026 10:42:42 AM	16.8	77.2	0.0	6.0			0.2	0.0	165.7	165.4
CV-2344	6/17/2026 9:22:23 AM	4.5	75.1	0.0	20.4			0.1	0.0	157.4	157.6
CV-2345	6/2/2026 7:55:00 AM					660					
CV-2345	6/2/2026 7:55:00 AM						33000				
CV-2345	6/2/2026 8:44:21 AM	14.6	78.4	0.2	6.8			0.2	34.0	126.3	126.5
CV-2345	6/16/2026 8:05:13 AM	18.4	76.5	0.2	4.9			0.2	24.5	126.1	126.5
CV-2346	6/2/2026 7:50:00 AM						160000				
CV-2346	6/2/2026 7:50:00 AM					2700					
CV-2346	6/3/2026 9:35:01 AM	13.3	75.5	0.9	10.3			0.2	11.4	186.1	186.4
CV-2346	6/3/2026 9:39:13 AM	13.4	74.4	0.8	11.4			0.2	14.3	186.5	186.6
CV-2346	6/3/2026 9:40:00 AM						147600				
CV-2346	6/10/2026 9:54:27 AM	17.2	75.4	0.5	6.9			0.2	13.8	186.8	186.9
CV-2346	6/17/2026 9:17:36 AM	1.4	78.1	0.5	20.0			0.0	40.0	189.8	189.6
CV-2346	6/17/2026 9:19:04 AM	1.3	77.2	0.4	21.1			0.0	52.8	188.9	189.0
CV-2347	6/2/2026 7:40:00 AM					1000					
CV-2347	6/2/2026 7:40:00 AM						55000				
CV-2347	6/2/2026 9:01:41 AM	15.5	63.6	0.0	20.9			0.2	0.0	108.0	107.8
CV-2347	6/16/2026 8:17:59 AM	15.3	67.9	0.2	16.6			0.2	83.0	114.6	115.7
CV-2348	6/2/2026 7:30:00 AM						9000				
CV-2348	6/2/2026 7:30:00 AM					130					
CV-2348	6/2/2026 9:24:08 AM	23.8	38.9	0.0	37.3			0.6	0.0	124.7	124.8
CV-2348	6/10/2026 1:32:39 PM	19.6	53.1	0.0	27.3			0.4	0.0	131.8	131.8
CV-2348	6/10/2026 1:34:08 PM	19.8	50.7	0.0	29.5			0.4	0.0	132.2	132.2
CV-2348	6/16/2026 8:24:15 AM	21.6	54.1	0.0	24.3			0.4	0.0	134.3	134.4
CV-2348	6/16/2026 8:24:47 AM	22.0	54.7	0.0	23.3			0.4	0.0	134.4	134.4
CV-2349	6/2/2026 8:30:00 AM					2900					
CV-2349	6/2/2026 8:30:00 AM						150000				
CV-2349	6/3/2026 10:34:57 AM	9.8	76.6	0.0	13.6			0.1	0.0	159.0	161.1

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2349	6/3/2026 10:35:45 AM	11.2	79.8	0.0	9.0			0.1	0.0	161.6	161.3
CV-2349	6/3/2026 10:40:00 AM						129950				
CV-2349	6/10/2026 1:32:14 PM	17.2	76.0	0.9	5.9			0.2	6.6	158.4	159.9
CV-2349	6/10/2026 1:33:11 PM	21.0	76.8	0.1	2.1			0.3	21.0	160.5	160.7
CV-2349	6/17/2026 10:35:04 AM	3.3	79.0	0.0	17.7			0.0	0.0	161.8	161.6
CV-2349	6/17/2026 10:35:26 AM	2.9	74.7	0.0	22.4			0.0	0.0	160.6	160.5
CV-2350	6/2/2026 8:15:00 AM						170000				
CV-2350	6/2/2026 8:15:00 AM					3800					
CV-2350	6/2/2026 8:32:01 AM	4.2	78.7	0.0	17.1			0.1	0.0	104.3	104.6
CV-2350	6/17/2026 8:33:21 AM	4.9	75.2	0.0	19.9			0.1	0.0	90.5	90.5
CV-2351	6/1/2026 9:00:00 AM					17					
CV-2351	6/1/2026 9:00:00 AM						1700				
CV-2351	6/1/2026 12:22:24 PM	0.0	1.4	20.6	78.0			0.0	3.8	97.0	97.6
CV-2351	6/1/2026 12:24:29 PM	0.0	0.6	20.7	78.7			0.0	3.8	99.2	99.5
CV-2351	6/2/2026 7:47:05 AM										
CV-2351	6/3/2026 7:58:36 AM										
CV-2351	6/4/2026 3:09:45 PM										
CV-2351	6/5/2026 10:57:36 AM										
CV-2351	6/6/2026 8:19:20 AM										
CV-2351	6/9/2026 3:12:34 PM										
CV-2351	6/9/2026 3:12:48 PM										
CV-2351	6/16/2026 8:45:00 AM						4100				
CV-2351	6/16/2026 8:45:00 AM					13					
CV-2351	6/17/2026 9:15:56 AM	0.1	1.6	20.6	77.7			0.1	3.8	90.5	90.5
CV-2351	6/17/2026 9:16:22 AM	0.1	1.5	20.5	77.9			0.1	3.8	90.5	90.5
CV-2351	6/18/2026 2:20:44 PM										
CV-2351	6/18/2026 2:20:55 PM										
CV-2351	6/19/2026 12:43:31 PM										
CV-2351	6/26/2026 3:52:05 PM										
CV-2351	6/26/2026 3:52:20 PM										
CV-2351	6/30/2026 2:51:00 PM										
CV-2351	6/30/2026 2:52:10 PM										
CV-2352	6/1/2026 9:10:00 AM					630					

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2352	6/1/2026 9:10:00 AM						100000				
CV-2352	6/1/2026 12:43:45 PM	1.2	44.3	9.9	44.6			0.0	4.5	130.4	130.4
CV-2352	6/1/2026 12:44:54 PM	1.3	43.6	9.9	45.2			0.0	4.6	129.0	128.7
CV-2352	6/2/2026 7:48:09 AM										
CV-2352	6/3/2026 7:57:58 AM										
CV-2352	6/4/2026 3:08:51 PM										
CV-2352	6/5/2026 10:58:49 AM										
CV-2352	6/6/2026 8:19:50 AM										
CV-2352	6/9/2026 3:03:03 PM										
CV-2352	6/9/2026 3:03:33 PM										
CV-2352	6/17/2026 9:28:04 AM	3.1	76.9	1.1	18.9			0.0	17.2	90.5	90.5
CV-2352	6/18/2026 2:15:09 PM										
CV-2352	6/18/2026 2:15:24 PM										
CV-2352	6/26/2026 3:52:52 PM										
CV-2352	6/26/2026 3:53:01 PM										
CV-2352	6/30/2026 2:51:05 PM										
CV-2352	6/30/2026 2:51:18 PM										
CV-2353-PLF	6/11/2026 10:42:44 AM	3.6	63.3	3.1	30.0			0.1	9.7	134.1	135.1
CV-2353-PLF	6/11/2026 10:46:22 AM	4.5	58.9	4.3	32.3			0.1	7.5	138.7	138.7
CV-2353-PLF	6/12/2026 10:14:03 AM	3.4	73.8	0.7	22.1			0.0	31.6	183.0	183.4
CV-2353-PLF	6/12/2026 10:16:08 AM	2.8	74.8	0.5	21.9			0.0	43.8	182.5	182.1
CV-2353-PLF	6/12/2026 10:38:13 AM										
CV-2353-PLF	6/15/2026 8:25:00 AM					710					
CV-2353-PLF	6/15/2026 8:25:00 AM						200000				
CV-2353-PLF	6/15/2026 2:58:08 PM	3.6	74.5	0.3	21.6			0.0	72.0	132.9	132.4
CV-2353-PLF	6/15/2026 2:59:49 PM	4.1	63.7	2.4	29.8			0.1	12.4	132.1	132.1
CV-2353-PLF	6/17/2026 9:38:30 AM	11.7	76.3	0.0	12.0			0.2	0.0	187.5	188.4
CV-2353-PLF	6/17/2026 9:38:59 AM	12.8	76.6	0.0	10.6			0.2	0.0	188.5	189.5
CV-2354	6/3/2026 10:45:40 AM	23.8	73.8	0.0	2.4			0.3	0.0	176.0	176.5

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2354	6/3/2026 10:47:46 AM	26.2	73.8	0.0	0.0			0.4	0.0	177.2	177.2
CV-2354	6/3/2026 10:50:00 AM						143400				
CV-2354	6/8/2026 1:27:32 PM	6.0	75.0	0.0	19.0			0.1	0.0	179.6	180.4
CV-2354	6/8/2026 1:28:00 PM	5.3	77.2	0.0	17.5			0.1	0.0	181.0	181.2
CV-2354	6/10/2026 1:14:12 PM	21.5	74.9	0.0	3.6			0.3	0.0	179.8	180.0
CV-2354	6/15/2026 8:10:00 AM						180000				
CV-2354	6/15/2026 8:10:00 AM					2200					
CV-2354	6/17/2026 10:43:17 AM	4.7	74.0	0.0	21.3			0.1	0.0	183.1	183.6
CV-24001	6/1/2026 1:48:34 PM	43.5	56.5	0.0	0.0			0.8	0.0	97.2	97.3
CV-24001	6/17/2026 9:25:42 AM	51.2	46.8	0.0	2.0			1.1	0.0	104.5	104.6
CV-24002	6/1/2026 1:41:05 PM	45.0	53.1	0.1	1.8			0.8	18.0	100.0	100.1
CV-24002	6/17/2026 9:17:33 AM	46.5	50.2	0.0	3.3			0.9	0.0	101.8	107.7
CV-24002	6/24/2026 8:07:06 AM										
CV-24003	6/1/2026 9:47:33 AM	19.0	26.2	11.5	43.3			0.7	3.8	89.0	89.5
CV-24003	6/5/2026 9:17:13 AM	1.3	1.0	19.9	77.8			1.3	3.9	87.1	89.2
CV-24003	6/17/2026 9:05:11 AM	43.5	47.7	0.8	8.0			0.9	10.0	81.6	82.4
CV-24003	6/24/2026 8:19:54 AM										
CV-24004	6/1/2026 9:44:08 AM	41.2	58.8	0.0	0.0			0.7	0.0	110.3	110.5
CV-24004	6/17/2026 9:00:41 AM	43.0	50.4	0.0	6.6			0.9	0.0	108.2	111.0
CV-24004	6/24/2026 8:46:57 AM										
CV-24006	6/1/2026 2:36:17 PM	38.4	54.9	0.0	6.7			0.7	0.0	127.3	127.2
CV-24006	6/2/2026 8:32:06 AM										
CV-24006	6/11/2026 2:54:50 PM	33.0	61.8	0.5	4.7			0.5	9.4	129.1	128.7
CV-24006	6/17/2026 9:50:26 AM	36.7	53.4	0.4	9.5			0.7	23.8	129.3	129.0
CV-24006	6/18/2026 3:15:55 PM										
CV-24006	6/18/2026 3:16:08 PM										
CV-24006	6/19/2026 11:31:36 AM										
CV-24006	6/24/2026 1:27:43 PM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24006	6/24/2026 1:28:01 PM										
CV-24006	6/24/2026 1:28:36 PM										
CV-24006	6/26/2026 1:33:12 PM										
CV-24006	6/26/2026 1:33:26 PM										
CV-24007	6/1/2026 2:43:27 PM	23.6	58.5	1.2	16.7			0.4	13.9	147.5	147.4
CV-24007	6/2/2026 8:31:29 AM										
CV-24007	6/2/2026 9:10:01 AM	48.1	47.0	2.8	2.1			1.0	0.8	143.5	144.0
CV-24007	6/2/2026 9:14:26 AM	35.7	49.9	2.3	12.1			0.7	5.3	138.2	138.2
CV-24007	6/12/2026 8:23:32 AM										
CV-24007	6/15/2026 9:35:00 AM					470					
CV-24007	6/15/2026 9:35:00 AM						63000				
CV-24007	6/17/2026 9:53:11 AM	24.8	52.7	2.4	20.1			0.5	8.4	142.8	142.8
CV-24008	6/1/2026 9:00:00 AM						197800				
CV-24008	6/2/2026 8:30:57 AM										
CV-24008	6/2/2026 8:58:36 AM	8.4	74.9	0.6	16.1			0.1	26.8	168.3	167.8
CV-24008	6/2/2026 9:00:00 AM					2820					
CV-24008	6/9/2026 9:03:09 AM	7.2	75.9	0.4	16.5			0.1	41.3	170.6	170.4
CV-24008	6/16/2026 8:56:04 AM	5.4	72.2	0.3	22.1			0.1	73.7	173.8	173.9
CV-24008	6/16/2026 8:57:09 AM	5.8	69.9	1.0	23.3			0.1	23.3	174.1	174.2
CV-24008	6/23/2026 9:36:51 AM	4.6	71.5	0.0	23.9			0.1	0.0	172.6	172.4
CV-24008	6/24/2026 3:50:29 PM										
CV-24008	6/30/2026 9:05:50 AM	9.3	75.7	0.0	15.0			0.1	0.0	173.3	172.3
CV-24008	6/30/2026 9:07:16 AM	3.6	71.1	0.0	25.3			0.1	0.0	172.3	172.2
CV-24009	6/1/2026 8:55:00 AM						135100				
CV-24009	6/2/2026 8:30:31 AM										
CV-24009	6/2/2026 8:52:31 AM	16.8	77.2	0.0	6.0			0.2	0.0	156.0	156.1
CV-24009	6/2/2026 8:55:00 AM					1080					
CV-24009	6/9/2026 8:57:30 AM	15.7	76.6	0.0	7.7			0.2	0.0	156.7	156.7
CV-24009	6/16/2026 8:46:33 AM	12.1	74.5	0.0	13.4			0.2	0.0	162.5	162.7
CV-24009	6/19/2026 11:27:55 AM										
CV-24009	6/23/2026 9:31:14 AM	18.3	68.3	2.2	11.2			0.3	5.1	158.3	
CV-24009	6/23/2026 9:34:10 AM	12.3	61.6	3.8	22.3			0.2	5.9	153.6	153.6
CV-24009	6/25/2026 9:25:26 AM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24009	6/25/2026 9:26:16 AM										
CV-24009	6/26/2026 1:24:49 PM										
CV-24009	6/26/2026 1:25:02 PM										
CV-24009	6/30/2026 8:56:02 AM	10.3	72.8	0.0	16.9			0.1	0.0	160.8	162.5
CV-24009	6/30/2026 8:57:08 AM	8.9	69.0	0.0	22.1			0.1	0.0	162.5	162.6
CV-24009	6/30/2026 9:31:37 AM	3.5	78.8	0.1	17.6			0.0	176.0	162.6	162.8
CV-24010	6/8/2026 2:10:41 PM	17.5	65.8	1.6	15.2			0.3	9.8	91.2	91.1
CV-24010	6/8/2026 2:11:53 PM	16.6	66.2	1.3	15.9			0.2	12.0	91.4	91.4
CV-24010	6/23/2026 1:51:29 PM	14.4	59.1	4.4	22.1			0.2	5.0	100.5	99.7
CV-24010	6/24/2026 9:13:10 AM										
CV-24011	6/2/2026 9:35:00 AM						143700				
CV-24011	6/2/2026 9:35:00 AM					2130					
CV-24011	6/2/2026 9:37:40 AM	37.0	62.6	0.4	0.0			0.6	0.0	183.6	184.1
CV-24011	6/2/2026 9:38:42 AM	35.4	64.3	0.3	0.0			0.6	0.0	184.2	184.1
CV-24011	6/4/2026 1:01:49 PM	7.2	69.7	0.1	23.0			0.1	230.0	188.4	187.8
CV-24011	6/4/2026 1:03:39 PM	12.0	68.9	0.2	18.9			0.2	94.5	187.7	187.9
CV-24011	6/9/2026 9:12:23 AM	37.4	62.2	0.3	0.1			0.6	0.3	181.6	182.0
CV-24011	6/9/2026 9:13:37 AM	35.8	63.9	0.3	0.0			0.6	0.0	182.6	182.4
CV-24011	6/16/2026 9:07:19 AM	31.1	62.4	0.5	6.0			0.5	12.0	184.5	184.6
CV-24011	6/16/2026 9:08:16 AM	30.7	64.7	0.3	4.3			0.5	14.3	184.8	184.7
CV-24011	6/23/2026 10:12:30 AM	16.8	71.7	0.1	11.4			0.2	114.0	189.2	189.1
CV-24011	6/29/2026 9:18:00 AM	12.9	69.3	0.5	17.3			0.2	34.6	186.0	185.8
CV-24011	6/29/2026 9:18:40 AM	12.3	69.3	0.4	18.0			0.2	45.0	186.1	
CV-24012	6/2/2026 9:28:01 AM	10.3	77.4	0.0	12.3			0.1	0.0	165.3	166.3
CV-24012	6/2/2026 9:30:00 AM						168700				
CV-24012	6/2/2026 9:30:00 AM					2180					

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24012	6/9/2026 9:34:04 AM	11.7	79.3	0.0	9.0			0.1	0.0	159.9	160.9
CV-24012	6/16/2026 9:25:50 AM	10.3	73.8	0.0	15.9			0.1	0.0	179.2	178.8
CV-24012	6/23/2026 10:03:04 AM	8.3	78.7	0.2	12.8			0.1	64.0	176.4	172.2
CV-24012	6/23/2026 10:04:25 AM	10.1	77.3	0.1	12.5			0.1	125.0	173.9	174.6
CV-24012	6/24/2026 1:16:51 PM										
CV-24012	6/29/2026 10:10:08 AM	1.7	81.1	0.0	17.2			0.0	0.0	180.7	181.4
CV-24013	6/11/2026 9:49:00 AM	11.5	22.4	13.9	52.2			0.5	3.8	120.5	118.2
CV-24013	6/22/2026 10:46:47 AM	3.3	47.4	8.8	40.5			0.1	4.6	117.4	115.7
CV-24013	6/22/2026 10:51:54 AM	4.2	47.2	9.1	39.5			0.1	4.3	115.9	118.0
CV-24014	6/2/2026 8:48:10 AM	9.8	75.3	0.0	14.9			0.1	0.0	178.5	178.4
CV-24014	6/2/2026 8:50:00 AM						167950				
CV-24014	6/2/2026 8:50:00 AM					1100					
CV-24014	6/9/2026 8:53:51 AM	10.7	74.8	0.0	14.5			0.1	0.0	178.4	178.8
CV-24014	6/16/2026 8:43:10 AM	8.0	73.2	0.0	18.8			0.1	0.0	178.7	178.8
CV-24014	6/19/2026 11:50:57 AM	5.6	70.3	0.0	24.2			0.1	0.0	178.6	178.4
CV-24014	6/22/2026 9:40:26 AM	14.2	72.7	0.0	13.1			0.2	0.0	179.2	179.2
CV-24014	6/25/2026 10:35:18 AM										
CV-24014	6/29/2026 1:41:00 PM										
CV-24014	6/30/2026 8:45:06 AM	7.9	72.4	0.0	19.7			0.1	0.0	178.4	178.7
CV-24014	6/30/2026 8:47:14 AM	8.6	69.7	0.0	21.7			0.1	0.0	178.7	178.7
CV-24015	6/1/2026 10:43:39 AM	15.1	73.1	0.0	11.8			0.2	0.0	179.5	178.9
CV-24015	6/1/2026 10:45:00 AM						210300				
CV-24015	6/1/2026 10:45:00 AM					1910					
CV-24015	6/8/2026 9:52:47 AM	4.1	74.8	0.0	21.1			0.1	0.0	172.4	172.1
CV-24015	6/15/2026 9:17:48 AM	23.8	71.0	0.0	5.2			0.3	0.0	182.3	182.8

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24015	6/22/2026 9:33:15 AM	10.7	69.1	0.5	19.7			0.2	39.4	184.6	187.5
CV-24015	6/22/2026 9:34:57 AM	11.2	71.2	0.2	17.4			0.2	87.0	187.9	187.7
CV-24015	6/29/2026 9:56:20 AM	8.1	54.5	0.0	37.4			0.1	0.0	173.9	173.7
CV-24016	6/2/2026 9:42:45 AM	34.1	62.1	0.0	3.8			0.5	0.0	169.3	169.1
CV-24016	6/2/2026 9:45:00 AM					1440					
CV-24016	6/2/2026 9:45:00 AM						94000				
CV-24016	6/9/2026 9:16:20 AM	30.8	58.3	0.0	10.9			0.5	0.0	169.3	169.7
CV-24016	6/16/2026 9:15:50 AM	28.1	60.6	0.0	11.3			0.5	0.0	174.4	174.3
CV-24016	6/23/2026 10:09:50 AM	33.3	65.8	0.0	0.9			0.5	0.0	173.7	173.8
CV-24016	6/29/2026 9:22:30 AM	13.8	64.7	0.0	21.5			0.2	0.0	178.9	179.0
CV-24017	6/2/2026 9:23:32 AM	16.0	76.4	0.1	7.5			0.2	75.0	180.9	181.1
CV-24017	6/2/2026 9:24:13 AM	15.4	76.1	0.0	8.5			0.2	0.0	181.1	180.9
CV-24017	6/2/2026 9:25:00 AM					2630					
CV-24017	6/2/2026 9:25:00 AM						160300				
CV-24017	6/9/2026 9:22:05 AM	16.6	76.9	0.0	6.5			0.2	0.0	177.0	179.4
CV-24017	6/15/2026 9:45:00 AM					1500					
CV-24017	6/15/2026 9:45:00 AM						160000				
CV-24017	6/16/2026 9:21:32 AM	19.9	69.7	0.7	9.7			0.3	13.9	180.4	181.6
CV-24017	6/16/2026 9:23:09 AM	17.9	69.8	0.6	11.7			0.3	19.5	181.5	181.4
CV-24017	6/23/2026 9:49:36 AM	11.0	73.3	0.2	15.5			0.2	77.5	183.3	183.5
CV-24017	6/29/2026 10:14:31 AM	6.4	76.0	0.6	17.0			0.1	28.3	188.0	188.4
CV-24017	6/30/2026 8:53:30 AM										
CV-24018	6/1/2026 2:20:40 PM	11.0	32.4	8.8	47.8			0.3	5.4	87.9	88.0
CV-24018	6/22/2026 8:06:29 AM	12.1	72.3	0.2	15.4			0.2	77.0	135.5	134.9
CV-24018	6/22/2026 8:07:35 AM	11.8	72.8	0.8	14.6			0.2	18.3	134.1	133.6
CV-24018	6/23/2026 4:42:31 PM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24018	6/25/2026 3:34:56 PM	13.2	69.2	0.1	17.5			0.2	175.0	126.9	127.0
CV-24019	6/2/2026 9:48:57 AM	15.8	75.8	0.2	8.2			0.2	41.0	173.0	174.2
CV-24019	6/2/2026 9:50:00 AM						150500				
CV-24019	6/2/2026 9:50:00 AM					1745					
CV-24019	6/2/2026 9:50:36 AM	18.5	75.5	0.0	6.0			0.2	0.0	175.0	175.3
CV-24019	6/16/2026 9:37:35 AM	13.3	69.6	1.7	15.4			0.2	9.1	181.3	181.6
CV-24019	6/16/2026 9:40:14 AM	15.5	69.9	1.1	13.5			0.2	12.3	181.5	181.9
CV-24019	6/23/2026 10:07:07 AM	13.1	73.3	0.0	13.6			0.2	0.0	185.2	185.1
CV-24019	6/26/2026 8:44:17 AM										
CV-24019	6/29/2026 9:28:09 AM	2.5	79.4	0.0	18.1			0.0	0.0	187.7	188.2
CV-24020	6/2/2026 8:30:02 AM	2.5	70.4	1.4	25.7			0.0	18.4	64.9	65.0
CV-24020	6/23/2026 1:30:27 PM	1.6	14.5	17.0	66.9			0.1	3.9	95.0	95.2
CV-24020	6/25/2026 11:24:16 AM										
CV-24021	6/2/2026 8:09:06 AM	2.3	63.3	0.0	34.4			0.0	0.0	71.5	70.7
CV-24021	6/2/2026 8:10:40 AM	2.1	57.1	1.4	39.4			0.0	28.1	71.9	72.0
CV-24021	6/2/2026 8:32:46 AM										
CV-24021	6/23/2026 1:23:38 PM	2.2	16.4	14.8	66.6			0.1	4.5	95.2	95.3
CV-24021	6/23/2026 1:25:06 PM	2.3	17.0	14.6	66.1			0.1	4.5	95.5	95.6
CV-24021	6/25/2026 11:24:59 AM										
CV-24022-PI	6/1/2026 1:58:30 PM	23.3	71.0	0.2	5.5			0.3	27.5	195.8	195.7
CV-24022-PI	6/1/2026 2:10:00 PM						155000				
CV-24022-PI	6/1/2026 2:10:00 PM					1470					
CV-24022-PI	6/8/2026 10:03:23 AM	3.2	73.7	0.2	22.9			0.0	114.5	195.1	195.2

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24022-PI	6/15/2026 9:24:32 AM	20.6	70.9	0.0	8.5			0.3	0.0	195.4	195.7
CV-24022-PI	6/22/2026 9:43:50 AM	10.5	72.4	0.0	17.1			0.1	0.0	195.5	195.4
CV-24022-PI	6/29/2026 10:18:07 AM	10.6	68.9	0.0	20.5			0.2	0.0	187.3	187.8
CV-24023	6/1/2026 10:49:06 AM	17.9	71.2	0.0	10.9			0.3	0.0	184.0	183.0
CV-24023	6/1/2026 10:50:00 AM					1315					
CV-24023	6/1/2026 10:50:00 AM						205150				
CV-24023	6/2/2026 7:16:22 AM										
CV-24023	6/8/2026 9:57:42 AM	1.7	36.8	0.6	60.9			0.0	101.5	204.2	204.3
CV-24023	6/8/2026 9:58:50 AM	3.4	75.0	0.0	21.6			0.0	0.0	203.8	203.6
CV-24023	6/11/2026 4:02:00 PM	2.7	80.1	0.0	17.2			0.0	0.0	197.8	197.8
CV-24023	6/11/2026 4:03:26 PM	3.6	83.0	0.0	13.4			0.0	0.0	197.0	197.0
CV-24023	6/15/2026 9:20:16 AM	21.5	72.1	0.0	6.4			0.3	0.0	197.4	197.6
CV-24023	6/22/2026 9:37:30 AM	10.4	71.0	0.0	18.6			0.1	0.0	197.3	197.3
CV-24023	6/29/2026 10:12:19 AM	11.7	68.9	0.0	19.4			0.2	0.0	197.2	197.3
CV-24024-PI	6/8/2026 1:57:26 PM	9.0	69.2	0.0	21.9			0.1	0.0	139.0	139.2
CV-24024-PI	6/8/2026 1:57:56 PM	9.1	68.9	0.0	22.1			0.1	0.0	139.3	139.2
CV-24024-PI	6/24/2026 10:27:50 AM	4.4	69.3	0.9	25.4			0.1	28.2	163.3	163.5
CV-24024-PI	6/29/2026 9:47:30 AM	10.8	71.6	0.0	17.6			0.2	0.0	140.0	139.5
CV-24025	6/2/2026 10:41:15 AM	19.5	77.7	0.0	2.8			0.3	0.0	184.2	184.4
CV-24025	6/2/2026 10:45:00 AM					3690					
CV-24025	6/2/2026 10:45:00 AM						156700				
CV-24025	6/9/2026 9:40:42 AM	19.6	75.4	0.0	5.0			0.3	0.0	181.6	182.3
CV-24025	6/11/2026 10:08:18 AM										
CV-24025	6/16/2026 10:19:07 AM	14.3	75.3	0.0	10.4			0.2	0.0	186.8	186.3
CV-24025	6/16/2026 10:19:54 AM	17.6	74.5	0.0	7.9			0.2	0.0	186.5	186.8
CV-24025	6/23/2026 10:21:26 AM	8.8	75.3	0.0	15.9			0.1	0.0	185.6	185.6

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24025	6/29/2026 9:34:06 AM	4.1	77.7	0.1	18.1			0.1	181.0	188.3	188.4
CV-24026	6/2/2026 8:38:21 AM	3.5	76.4	1.1	19.0			0.0	17.3	77.2	76.6
CV-24026	6/9/2026 9:54:29 AM	16.3	74.1	0.0	9.6			0.2	0.0	84.1	84.5
CV-24026	6/9/2026 9:56:19 AM	15.8	75.7	0.5	8.0			0.2	16.0	85.0	84.9
CV-24026	6/10/2026 11:09:42 AM	0.2	70.3	3.1	26.4			0.0	8.5	134.0	133.5
CV-24026	6/10/2026 11:11:56 AM	0.0	67.3	4.3	28.4			0.0	6.6	129.5	129.9
CV-24026	6/23/2026 11:28:16 AM	4.4	82.8	0.0	12.8			0.1	0.0	188.3	199.8
CV-24026	6/23/2026 11:35:40 AM	2.7	85.7	0.0	11.6			0.0	0.0	199.2	197.4
CV-24026	6/23/2026 11:39:23 AM	3.5	88.0	0.0	8.5			0.0	0.0	196.8	196.1
CV-24026	6/29/2026 10:05:21 AM	1.2	67.3	2.6	28.9			0.0	11.1	175.0	173.5
CV-24027	6/2/2026 8:19:11 AM	3.9	72.2	0.0	23.9			0.1	0.0	72.3	72.2
CV-24027	6/2/2026 8:21:11 AM	3.1	72.3	0.0	24.6			0.0	0.0	71.2	71.8
CV-24027	6/23/2026 11:10:25 AM	4.5	76.2	0.7	18.6			0.1	26.6	94.4	90.2
CV-24027	6/23/2026 2:49:58 PM										
CV-24028	6/1/2026 1:53:07 PM	21.8	72.1	0.0	6.1			0.3	0.0	190.9	190.3
CV-24028	6/1/2026 2:05:00 PM					894					
CV-24028	6/1/2026 2:05:00 PM						186800				
CV-24028	6/8/2026 10:09:22 AM	4.4	72.9	0.0	22.7			0.1	0.0	192.4	192.5
CV-24028	6/15/2026 9:29:30 AM	24.2	70.0	0.0	5.8			0.3	0.0	194.5	194.7
CV-24028	6/22/2026 9:46:03 AM	13.3	67.7	0.0	19.0			0.2	0.0	194.6	195.0
CV-24028	6/23/2026 1:24:03 PM										
CV-24028	6/29/2026 10:41:12 AM	10.4	74.6	0.0	15.0			0.1	0.0	191.7	191.1
CV-24029	6/5/2026 2:13:50 PM	0.4	13.1	18.3	68.2			0.0	3.7	95.5	95.8
CV-24029	6/9/2026 1:11:23 PM	0.4	22.5	15.2	61.9			0.0	4.1	93.9	94.1
CV-24029	6/9/2026 1:24:01 PM	0.4	25.7	14.7	59.2			0.0	4.0	93.5	90.4

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24029	6/17/2026 2:05:10 PM	1.9	71.0	0.0	27.2			0.0	0.0	97.3	96.5
CV-24029	6/17/2026 2:06:03 PM	1.9	73.5	0.0	24.6			0.0	0.0	97.1	97.0
CV-24029	6/19/2026 12:12:46 PM	1.2	34.4	12.4	52.0			0.0	4.2	73.4	73.0
CV-24030	6/1/2026 10:00:00 AM						172600				
CV-24030	6/1/2026 10:00:00 AM					1970					
CV-24030	6/1/2026 10:01:10 AM	11.2	71.3	1.0	16.5			0.2	16.5	192.5	192.9
CV-24030	6/1/2026 10:03:17 AM	10.5	73.5	0.5	15.5			0.1	31.0	192.8	192.4
CV-24030	6/8/2026 9:33:25 AM	2.5	72.8	1.2	23.5			0.0	19.6	190.9	190.8
CV-24030	6/8/2026 9:38:38 AM	2.5	75.2	0.3	22.0			0.0	73.3	192.1	191.9
CV-24030	6/15/2026 8:58:22 AM	11.2	69.5	3.3	16.0			0.2	4.8	189.5	185.8
CV-24030	6/15/2026 9:05:40 AM	10.9	59.6	4.0	25.5			0.2	6.4	185.6	186.0
CV-24030	6/22/2026 9:04:13 AM	4.6	52.9	6.8	35.7			0.1	5.3	189.5	191.7
CV-24030	6/22/2026 9:06:13 AM	5.5	61.6	3.9	29.0			0.1	7.4	190.0	190.9
CV-24030	6/22/2026 9:10:22 AM	9.2	74.9	0.0	15.9			0.1	0.0	190.3	190.3
CV-24030	6/29/2026 9:22:58 AM	6.5	75.9	0.0	17.6			0.1	0.0	187.5	187.6
CV-24031	6/2/2026 9:09:14 AM	26.6	67.0	0.0	6.4			0.4	0.0	138.8	139.2
CV-24031	6/2/2026 9:16:24 AM	12.1	78.7	0.0	9.2			0.2	0.0	127.6	128.0
CV-24031	6/22/2026 8:17:15 AM	10.7	79.2	0.0	10.1			0.1	0.0	163.0	164.3
CV-24031	6/22/2026 8:17:55 AM	10.0	80.3	0.0	9.7			0.1	0.0	163.6	163.7
CV-24031	6/22/2026 8:18:11 AM	9.9	78.6	0.0	11.5			0.1	0.0	164.3	164.1
CV-24032	6/2/2026 1:40:47 PM	18.4	74.6	0.0	7.0			0.2	0.0	189.1	189.8

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24032	6/2/2026 1:41:54 PM	21.1	77.6	0.0	1.3			0.3	0.0	190.1	190.0
CV-24032	6/2/2026 1:45:00 PM					1700					
CV-24032	6/2/2026 1:45:00 PM						136400				
CV-24032	6/9/2026 10:16:37 AM	17.2	75.2	0.0	7.6			0.2	0.0	186.5	187.0
CV-24032	6/9/2026 10:17:50 AM	16.9	78.9	0.0	4.2			0.2	0.0	187.1	186.7
CV-24032	6/16/2026 10:01:42 AM	5.0	7.5	18.4	69.1			0.7	3.8	101.1	113.5
CV-24032	6/16/2026 10:03:21 AM	5.3	18.0	16.3	60.4			0.3	3.7	98.7	98.3
CV-24032	6/23/2026 10:42:53 AM	16.1	41.7	7.9	34.3			0.4	4.3	148.2	169.7
CV-24032	6/23/2026 10:43:53 AM	16.3	63.2	3.0	17.5			0.3	5.8	168.4	172.2
CV-24032	6/25/2026 8:17:52 AM										
CV-24032	6/29/2026 9:46:20 AM	0.8	74.8	2.6	21.8			0.0	8.4	185.2	180.2
CV-24032	6/30/2026 8:30:37 AM	5.5	70.8	0.7	23.0			0.1	32.9	192.2	192.2
CV-24033	6/2/2026 1:44:33 PM	16.6	73.1	0.0	10.3			0.2	0.0	184.6	184.8
CV-24033	6/2/2026 1:55:00 PM						170000				
CV-24033	6/2/2026 1:55:00 PM					2580					
CV-24033	6/9/2026 10:10:59 AM	17.3	73.6	0.0	9.1			0.2	0.0	188.6	189.0
CV-24033	6/9/2026 10:11:43 AM	16.7	75.8	0.0	7.5			0.2	0.0	189.1	189.2
CV-24033	6/16/2026 9:54:12 AM	12.1	85.6	2.3	0.0			0.1	0.0	193.0	196.2
CV-24033	6/16/2026 9:54:43 AM	11.6	75.7	0.0	12.7			0.2	0.0	196.4	196.5
CV-24033	6/16/2026 3:10:13 PM	0.7	72.1	0.0	27.2			0.0	0.0	187.4	187.7

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24033	6/16/2026 3:11:47 PM	0.6	73.1	0.0	26.3			0.0	0.0	188.0	188.3
CV-24033	6/23/2026 10:34:05 AM	8.4	74.2	0.0	17.4			0.1	0.0	184.1	184.2
CV-24033	6/23/2026 10:36:00 AM	9.5	74.9	0.0	15.6			0.1	0.0	185.3	185.2
CV-24033	6/29/2026 9:54:36 AM	0.5	63.4	6.1	30.0			0.0	4.9	116.0	119.0
CV-24033	6/29/2026 9:57:22 AM	0.6	63.3	5.8	30.3			0.0	5.2	118.4	117.3
CV-24034	6/8/2026 10:37:49 AM										
CV-24034	6/10/2026 11:03:35 AM	5.9	83.7	0.0	10.4			0.1	0.0	188.3	187.8
CV-24034	6/10/2026 1:01:10 PM	2.5	85.3	0.0	12.2			0.0	0.0	188.8	188.8
CV-24034	6/10/2026 1:03:05 PM	1.7	87.5	0.0	10.8			0.0	0.0	188.1	188.4
CV-24034	6/15/2026 9:36:46 AM	19.9	76.5	0.0	3.6			0.3	0.0	188.3	187.1
CV-24034	6/22/2026 9:50:57 AM	10.8	76.8	0.0	12.4			0.1	0.0	195.9	196.4
CV-24034	6/22/2026 9:51:32 AM	12.9	76.8	0.0	10.3			0.2	0.0	196.4	196.2
CV-24034	6/30/2026 8:05:38 AM	4.7	81.4	0.0	13.9			0.1	0.0	176.3	173.6
CV-24034	6/30/2026 8:08:12 AM	5.4	79.6	0.0	15.0			0.1	0.0	173.8	174.2
CV-24035	6/1/2026 9:31:45 AM	8.3	75.4	0.0	16.3			0.1	0.0	187.6	187.5
CV-24035	6/1/2026 9:40:00 AM					2220					
CV-24035	6/1/2026 9:40:00 AM						154050				
CV-24035	6/8/2026 9:15:31 AM	2.0	82.9	0.0	15.1			0.0	0.0	184.5	184.4
CV-24035	6/15/2026 8:40:23 AM	6.2	78.5	0.0	15.3			0.1	0.0	185.8	186.2
CV-24035	6/22/2026 8:50:48 AM	8.1	76.7	0.0	15.2			0.1	0.0	184.3	184.5
CV-24035	6/29/2026 9:07:04 AM	7.6	81.4	0.0	11.0			0.1	0.0	186.7	187.8
CV-24036	6/2/2026 9:30:31 AM	50.5	40.9	1.2	7.4			1.2	6.2	74.0	72.3
CV-24036	6/22/2026 8:28:46 AM	50.6	44.3	0.0	5.1			1.1	0.0	92.4	93.5
CV-24037	6/2/2026 9:49:59 AM	0.8	22.8	15.0	61.4			0.0	4.1	74.3	75.2
CV-24037	6/22/2026 8:23:58 AM	11.7	77.7	0.0	10.6			0.2	0.0	156.9	155.7

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24037	6/22/2026 8:24:48 AM	11.2	78.0	0.2	10.6			0.1	53.0	155.6	156.8
CV-24037	6/29/2026 12:33:39 PM	16.9	68.9	0.9	13.3			0.2	14.8	155.7	154.7
CV-24037	6/29/2026 12:34:30 PM	15.9	70.0	0.9	13.2			0.2	14.7	155.5	154.1
CV-24038	6/2/2026 2:01:48 PM	24.1	62.1	2.9	10.9			0.4	3.8	166.9	169.6
CV-24038	6/2/2026 2:03:03 PM	27.9	66.8	2.0	3.3			0.4	1.7	167.5	167.8
CV-24038	6/2/2026 2:05:00 PM					1400					
CV-24038	6/2/2026 2:05:00 PM						155700				
CV-24038	6/3/2026 3:29:21 PM										
CV-24038	6/9/2026 12:58:07 PM	29.0	67.7	0.9	2.4			0.4	2.7	181.3	182.7
CV-24038	6/9/2026 12:59:45 PM	24.0	71.5	0.3	4.2			0.3	14.0	183.1	182.1
CV-24038	6/9/2026 1:14:37 PM	19.4	71.1	0.0	9.5			0.3	0.0	184.8	186.4
CV-24038	6/16/2026 1:02:05 PM	18.7	74.2	0.6	6.5			0.3	10.8	179.1	179.0
CV-24038	6/16/2026 1:03:03 PM	20.7	73.0	0.3	6.0			0.3	20.0	180.1	179.1
CV-24038	6/23/2026 2:03:54 PM	11.6	63.4	4.6	20.4			0.2	4.4	183.2	184.2
CV-24038	6/23/2026 2:04:41 PM	14.3	69.3	1.1	15.3			0.2	13.9	183.4	183.3
CV-24038	6/29/2026 12:43:07 PM	5.8	76.9	0.1	17.2			0.1	172.0	192.1	192.6
CV-24039	6/10/2026 10:33:51 AM	1.1	77.4	0.3	21.2			0.0	70.7	158.8	159.0
CV-24039	6/15/2026 1:30:09 PM	1.2	68.7	0.5	29.6			0.0	59.2	165.2	163.8
CV-24039	6/15/2026 1:31:35 PM	1.0	71.0	0.2	27.8			0.0	139.0	163.1	163.1
CV-24039	6/23/2026 1:50:27 PM	10.8	68.2	0.2	20.8			0.2	104.0	167.3	168.4
CV-24039	6/23/2026 1:51:13 PM	10.3	68.8	0.0	20.9			0.1	0.0	169.2	170.5
CV-24039	6/29/2026 12:51:38 PM	4.0	71.7	0.6	23.7			0.1	39.5	175.3	175.1

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24040	6/1/2026 2:28:59 PM	14.7	75.6	0.0	9.7			0.2	0.0	150.2	150.4
CV-24040	6/1/2026 2:30:00 PM						146200				
CV-24040	6/1/2026 2:30:00 PM					1780					
CV-24040	6/1/2026 2:30:55 PM	17.9	74.1	0.1	7.9			0.2	79.0	150.5	150.2
CV-24040	6/11/2026 10:25:08 AM	9.5	71.2	1.0	18.3			0.1	18.3	166.3	164.3
CV-24040	6/11/2026 10:31:45 AM	15.7	67.0	0.0	17.3			0.2	0.0	166.6	165.9
CV-24040	6/15/2026 9:40:41 AM	16.2	71.7	1.1	11.0			0.2	10.0	161.3	161.4
CV-24040	6/22/2026 10:31:23 AM	10.2	66.9	1.4	21.5			0.2	15.4	160.4	160.8
CV-24040	6/22/2026 10:32:22 AM	11.1	70.4	0.9	17.6			0.2	19.6	160.7	
CV-24040	6/22/2026 1:40:55 PM	0.8	75.0	0.3	23.9			0.0	79.7	160.2	159.7
CV-24040	6/29/2026 1:04:55 PM	6.0	73.5	1.3	19.2			0.1	14.8	174.7	173.0
CV-24041	6/10/2026 10:56:45 AM	3.6	80.7	0.0	15.7			0.0	0.0	99.1	96.2
CV-24041	6/10/2026 10:58:05 AM	1.1	62.4	4.7	31.8			0.0	6.8	98.1	98.1
CV-24041	6/22/2026 1:36:11 PM	8.7	35.4	9.9	46.0			0.2	4.6	95.5	95.4
CV-24041	6/22/2026 1:36:46 PM	8.8	35.4	10.0	45.8			0.2	4.6	95.3	95.3
CV-24042	6/1/2026 1:43:32 PM	28.8	71.2	0.0	0.0			0.4	0.0	185.6	187.6
CV-24042	6/1/2026 2:00:00 PM						131800				
CV-24042	6/1/2026 2:00:00 PM					1440					
CV-24042	6/8/2026 10:25:47 AM	11.7	73.1	0.0	15.2			0.2	0.0	183.0	181.2
CV-24042	6/15/2026 10:17:58 AM	42.0	58.0	0.0	0.0			0.7	0.0	181.9	182.9

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24042	6/22/2026 10:19:11 AM	26.9	72.4	0.0	0.7			0.4	0.0	183.6	183.6
CV-24042	6/30/2026 8:22:39 AM	11.4	81.9	0.0	6.7			0.1	0.0	184.3	180.1
CV-24043	6/2/2026 3:43:36 PM	39.2	55.6	0.3	4.9			0.7	16.3	116.7	117.4
CV-24043	6/3/2026 9:39:34 AM	35.5	62.0	0.0	2.5			0.6	0.0	106.3	107.0
CV-24043	6/25/2026 8:57:04 AM	37.2	56.9	0.1	5.8			0.7	58.0	95.5	95.6
CV-24044	6/2/2026 9:35:24 AM	19.8	73.4	0.0	6.8			0.3	0.0	124.6	106.2
CV-24044	6/22/2026 8:35:31 AM	21.9	73.3	0.0	4.8			0.3	0.0	151.0	151.0
CV-24044	6/22/2026 8:36:18 AM	20.7	74.3	0.0	5.0			0.3	0.0	150.8	150.7
CV-24044	6/29/2026 12:27:05 PM	23.3	73.1	0.0	3.6			0.3	0.0	149.3	149.6
CV-24045	6/2/2026 2:06:38 PM	24.1	73.4	0.0	2.5			0.3	0.0	168.7	169.1
CV-24045	6/2/2026 2:10:00 PM						165700				
CV-24045	6/2/2026 2:10:00 PM					2220					
CV-24045	6/9/2026 1:04:35 PM	19.3	75.1	0.2	5.4			0.3	27.0	166.9	165.2
CV-24045	6/9/2026 1:05:54 PM	19.4	73.5	0.2	6.9			0.3	34.5	164.2	164.1
CV-24045	6/9/2026 1:12:32 PM	12.5	71.9	0.0	15.6			0.2	0.0	156.7	156.1
CV-24045	6/16/2026 1:06:05 PM	22.6	73.7	0.0	3.7			0.3	0.0	163.7	163.3
CV-24045	6/23/2026 2:07:06 PM	17.9	73.0	0.0	9.1			0.2	0.0	163.5	163.1
CV-24045	6/29/2026 12:38:59 PM	5.0	78.8	0.0	16.2			0.1	0.0	172.6	173.9
CV-24046	6/10/2026 10:01:39 AM	0.4	70.9	1.7	27.0			0.0	15.9	179.5	178.7
CV-24046	6/10/2026 10:02:29 AM	0.6	76.0	0.8	22.6			0.0	28.3	178.7	178.4
CV-24046	6/15/2026 1:34:47 PM	0.2	67.8	0.4	31.6			0.0	79.0	176.3	176.4
CV-24046	6/15/2026 1:37:16 PM	0.2	71.9	0.4	27.5			0.0	68.8	176.4	176.4
CV-24046	6/23/2026 1:41:24 PM	13.7	70.3	0.0	16.0			0.2	0.0	136.2	131.4
CV-24046	6/29/2026 12:57:50 PM	3.1	71.6	1.2	24.1			0.0	20.1	186.6	186.8

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24046	6/29/2026 12:59:14 PM	4.5	73.0	0.9	21.6			0.1	24.0	186.1	187.7
CV-24048	6/10/2026 10:44:37 AM	2.3	72.5	1.4	23.8			0.0	17.0	100.8	98.2
CV-24048	6/22/2026 1:27:42 PM	6.1	61.2	3.0	29.7			0.1	9.9	96.9	97.3
CV-24049	6/1/2026 1:29:08 PM	16.4	76.2	0.0	7.4			0.2	0.0	188.9	188.9
CV-24049	6/1/2026 1:40:00 PM					2550					
CV-24049	6/1/2026 1:40:00 PM						151200				
CV-24049	6/4/2026 9:00:00 AM						160000				
CV-24049	6/4/2026 9:00:00 AM					2800					
CV-24049	6/8/2026 1:38:10 PM	8.5	80.2	0.0	11.3			0.1	0.0	177.7	177.5
CV-24049	6/15/2026 9:57:07 AM	19.5	72.7	0.0	7.8			0.3	0.0	189.0	189.3
CV-24049	6/22/2026 1:22:35 PM	13.0	75.3	0.0	11.7			0.2	0.0	183.7	184.4
CV-24049	6/26/2026 2:42:38 PM										
CV-24049	6/29/2026 2:11:03 PM	8.8	75.0	0.0	16.2			0.1	0.0	185.9	186.0
CV-24050	6/3/2026 9:17:29 AM	40.9	54.8	0.0	4.3			0.7	0.0	104.2	104.2
CV-24050	6/22/2026 11:57:01 AM	52.2	47.8	0.0	0.0			1.1	0.0	117.3	116.9
CV-24051	6/4/2026 12:43:06 PM	23.3	71.8	0.0	4.9			0.3	0.0	127.1	127.6
CV-24051	6/4/2026 12:44:46 PM	21.4	68.9	2.1	7.6			0.3	3.6	127.6	127.3
CV-24051	6/25/2026 11:34:01 AM	13.3	46.3	7.6	32.8			0.3	4.3	100.2	98.8
CV-24051	6/25/2026 11:40:21 AM	13.3	47.9	7.4	31.4			0.3	4.2	98.1	100.5
CV-24051	6/25/2026 2:20:14 PM	13.2	51.7	6.1	29.0			0.3	4.8	101.1	100.9
CV-24052	6/4/2026 9:09:09 AM	29.9	49.7	1.0	19.4			0.6	19.4	89.8	90.0
CV-24052	6/22/2026 1:46:11 PM	17.9	58.7	3.2	20.2			0.3	6.3	91.4	91.0
CV-24053	6/3/2026 7:40:00 AM					110					

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24053	6/3/2026 7:40:00 AM						8500				
CV-24053	6/3/2026 1:28:17 PM										
CV-24053	6/4/2026 8:58:29 AM	38.5	46.3	1.1	14.1			0.8	12.8	102.6	100.1
CV-24053	6/22/2026 2:17:18 PM	35.4	59.7	0.2	4.7			0.6	23.5	95.8	95.8
CV-24054	6/1/2026 1:25:36 PM	18.6	75.8	0.0	5.6			0.2	0.0	175.0	175.3
CV-24054	6/1/2026 1:35:00 PM						130800				
CV-24054	6/1/2026 1:35:00 PM					2400					
CV-24054	6/3/2026 1:18:32 PM										
CV-24054	6/8/2026 1:28:03 PM	12.0	81.2	0.0	6.8			0.1	0.0	151.1	151.4
CV-24054	6/15/2026 9:53:03 AM	27.1	72.5	0.0	0.4			0.4	0.0	173.2	173.4
CV-24054	6/22/2026 1:30:09 PM	15.9	73.6	0.0	10.5			0.2	0.0	160.6	162.1
CV-24054	6/29/2026 2:13:59 PM	8.8	78.7	0.0	12.5			0.1	0.0	169.6	170.0
CV-24055	6/4/2026 10:40:08 AM	9.0	68.6	1.0	21.4			0.1	21.4	132.7	132.2
CV-24055	6/4/2026 10:41:12 AM	9.0	68.8	1.0	21.2			0.1	21.2	132.1	132.1
CV-24055	6/12/2026 8:00:00 AM					720					
CV-24055	6/12/2026 8:00:00 AM						45000				
CV-24055	6/23/2026 9:47:37 AM	13.6	65.9	1.1	19.4			0.2	17.6	127.6	127.6
CV-24056	6/2/2026 8:05:04 AM	39.5	57.3	0.0	3.2			0.7	0.0	112.0	112.1
CV-24056	6/6/2026 12:58:24 PM										
CV-24056	6/11/2026 1:07:15 PM	18.5	63.9	0.0	17.7			0.3	0.0	101.9	102.3
CV-24056	6/11/2026 1:09:23 PM	18.3	65.6	0.0	16.1			0.3	0.0	103.5	104.6
CV-24056	6/16/2026 7:44:37 AM	15.5	73.7	0.0	10.8			0.2	0.0	140.5	140.3
CV-24056	6/16/2026 7:45:01 AM	15.5	73.7	0.0	10.8			0.2	0.0	139.8	139.5
CV-24056	6/18/2026 1:25:18 PM										
CV-24056	6/18/2026 1:25:33 PM										
CV-24056	6/19/2026 11:47:34 AM										
CV-24056	6/19/2026 11:55:12 AM										
CV-24056	6/24/2026 1:59:57 PM										
CV-24056	6/24/2026 2:00:11 PM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24056	6/25/2026 2:06:44 PM	27.1	64.2	0.1	8.6			0.4	86.0	111.8	120.3
CV-24057	6/3/2026 9:12:06 AM	21.3	72.8	0.0	5.9			0.3	0.0	144.9	144.9
CV-24057	6/24/2026 12:59:18 PM	17.8	74.1	0.0	8.1			0.2	0.0	146.8	147.3
CV-24057	6/24/2026 12:59:44 PM	17.8	73.7	0.0	8.5			0.2	0.0	147.4	147.4
CV-24058	6/3/2026 9:45:49 AM	31.7	38.5	0.0	29.8			0.8	0.0	105.1	104.3
CV-24058	6/22/2026 12:12:11 PM	40.1	42.4	0.0	17.5			0.9	0.0	114.6	116.1
CV-24059	6/11/2026 10:22:41 AM	27.5	63.9	0.1	8.5			0.4	85.0	160.8	159.4
CV-24059	6/11/2026 10:25:26 AM	24.2	65.1	0.0	10.7			0.4	0.0	160.1	160.1
CV-24059	6/11/2026 2:12:14 PM	18.7	64.2	0.1	17.0			0.3	170.0	116.9	118.5
CV-24059	6/24/2026 1:16:18 PM	17.5	71.1	0.0	11.4			0.2	0.0	162.0	162.0
CV-24059	6/24/2026 1:17:14 PM	17.4	71.8	0.0	10.8			0.2	0.0	162.1	162.1
CV-24060	6/3/2026 2:26:17 PM	24.0	64.5	0.4	11.1			0.4	27.8	109.0	99.3
CV-24060	6/10/2026 3:04:20 PM	28.4	71.1	0.5	0.0			0.4	0.0	108.5	109.3
CV-24060	6/16/2026 9:58:14 AM	12.5	72.7	0.7	14.1			0.2	20.1	103.8	104.0
CV-24060	6/16/2026 9:59:06 AM	13.1	74.9	0.4	11.6			0.2	29.0	102.9	102.8
CV-24061	6/2/2026 4:14:18 PM	34.0	60.5	0.0	5.5			0.6	0.0	121.7	121.9
CV-24061	6/16/2026 10:06:15 AM	16.0	50.6	5.8	27.6			0.3	4.8	131.0	131.0
CV-24061	6/16/2026 10:07:30 AM	22.7	66.3	0.0	11.0			0.3	0.0	131.1	131.1
CV-24061	6/16/2026 10:08:55 AM	24.3	69.2	0.0	6.5			0.4	0.0	129.8	129.7
CV-24062	6/10/2026 10:20:42 AM	20.6	73.4	0.0	6.0			0.3	0.0	165.2	164.6
CV-24062	6/10/2026 10:21:48 AM	20.1	73.6	0.0	6.3			0.3	0.0	164.4	164.3
CV-24062	6/12/2026 8:50:00 AM						4500				
CV-24062	6/12/2026 8:50:00 AM					33					
CV-24062	6/16/2026 2:32:33 PM	42.8	56.9	0.3	0.0			0.8	0.0	149.0	147.7
CV-24062	6/16/2026 2:33:39 PM	41.3	58.6	0.0	0.1			0.7	0.0	146.0	146.3

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24062	6/24/2026 9:42:09 AM	47.5	52.5	0.0	0.0			0.9	0.0	145.3	143.8
CV-24062	6/24/2026 9:44:44 AM	46.2	53.8	0.0	0.0			0.9	0.0	143.6	143.3
CV-24062	6/30/2026 8:52:28 AM	23.6	65.6	0.2	10.6			0.4	53.0	164.8	161.4
CV-24063	6/3/2026 1:21:07 PM	28.6	71.4	0.0	0.0			0.4	0.0	176.3	175.8
CV-24063	6/3/2026 1:25:00 PM						80200				
CV-24063	6/10/2026 2:12:26 PM	16.6	79.9	0.0	3.5			0.2	0.0	174.8	174.7
CV-24063	6/12/2026 10:10:00 AM					190					
CV-24063	6/12/2026 10:10:00 AM						11000				
CV-24063	6/17/2026 2:30:04 PM	3.6	61.5	4.7	30.2			0.1	6.4	177.0	174.6
CV-24063	6/17/2026 2:32:22 PM	3.9	67.4	3.7	25.0			0.1	6.8	176.4	177.7
CV-24063	6/24/2026 9:23:23 AM	10.5	58.2	4.8	26.5			0.2	5.5	182.1	185.5
CV-24063	6/24/2026 9:25:59 AM	12.3	73.4	4.8	9.5			0.2	2.0	184.6	184.8
CV-24063	6/29/2026 10:05:04 AM										
CV-24063	6/29/2026 1:17:06 PM	12.9	82.3	0.0	4.8			0.2	0.0	186.8	188.2
CV-24064	6/3/2026 1:28:32 PM	21.6	78.4	0.0	0.0			0.3	0.0	187.2	187.5
CV-24064	6/3/2026 1:40:00 PM						74600				
CV-24064	6/10/2026 2:23:47 PM	19.9	75.4	0.0	4.7			0.3	0.0	191.0	191.4
CV-24064	6/12/2026 8:35:00 AM					140					
CV-24064	6/12/2026 8:35:00 AM						11000				
CV-24064	6/24/2026 9:09:36 AM	11.0	79.3	0.0	9.7			0.1	0.0	189.3	188.5
CV-24064	6/30/2026 2:26:34 PM	9.7	80.2	0.0	10.1			0.1	0.0	192.7	191.9
CV-24065-TI	6/4/2026 10:11:00 AM	13.4	76.0	1.4	9.2			0.2	6.6	85.5	85.6
CV-24065-TI	6/11/2026 7:40:00 AM						7100				
CV-24065-TI	6/11/2026 7:40:00 AM					250					
CV-24065-TI	6/17/2026 2:10:47 PM	14.9	68.7	2.5	13.9			0.2	5.6	92.0	92.0

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24066	6/2/2026 7:57:31 AM	20.7	50.9	0.0	28.4			0.4	0.0	103.0	103.8
CV-24066	6/15/2026 7:50:00 AM					280					
CV-24066	6/15/2026 7:50:00 AM						30000				
CV-24066	6/16/2026 7:41:54 AM	25.7	49.2	0.0	25.1			0.5	0.0	104.1	105.3
CV-24067	6/4/2026 10:06:31 AM	27.0	62.4	0.0	10.6			0.4	0.0	152.7	152.7
CV-24067	6/10/2026 9:00:37 AM	43.9	56.1	0.0	0.0			0.8	0.0	157.8	157.8
CV-24067	6/16/2026 9:09:08 AM	30.8	59.5	0.0	9.7			0.5	0.0	157.1	157.1
CV-24067	6/16/2026 9:09:40 AM	30.9	60.7	0.0	8.4			0.5	0.0	156.8	156.6
CV-24067	6/17/2026 9:02:41 AM	3.0	80.9	0.0	16.1			0.0	0.0	150.6	151.0
CV-24067	6/17/2026 9:03:28 AM	3.0	80.2	0.0	16.8			0.0	0.0	151.4	151.6
CV-24067	6/24/2026 1:17:20 PM	47.2	52.8	0.0	0.0			0.9	0.0	156.3	156.2
CV-24068	6/4/2026 11:50:22 AM	27.2	56.2	0.0	16.6			0.5	0.0	151.9	152.0
CV-24068	6/4/2026 11:51:40 AM	26.4	56.1	0.0	17.5			0.5	0.0	152.4	152.5
CV-24068	6/9/2026 1:53:32 PM	48.6	43.3	0.0	8.1			1.1	0.0	136.2	138.3
CV-24068	6/9/2026 1:54:04 PM	50.0	45.7	0.0	4.3			1.1	0.0	139.0	139.0
CV-24068	6/24/2026 1:04:40 PM	31.2	42.8	0.0	26.0			0.7	0.0	140.3	140.3
CV-24068	6/24/2026 1:05:09 PM	32.1	42.9	0.0	25.0			0.7	0.0	140.1	140.3
CV-24068	6/30/2026 4:27:59 PM										
CV-24069	6/3/2026 9:58:36 AM	12.0	74.8	0.0	13.2			0.2	0.0	124.7	125.1
CV-24069	6/3/2026 9:59:30 AM	11.4	79.4	0.0	9.2			0.1	0.0	125.4	125.4
CV-24069	6/11/2026 9:28:47 AM	13.1	69.3	0.0	17.6			0.2	0.0	131.4	131.9
CV-24069	6/11/2026 12:10:39 PM	11.7	57.3	1.9	29.1			0.2	15.6	124.2	125.1
CV-24069	6/11/2026 12:19:47 PM	11.7	66.3	0.4	21.6			0.2	56.9	125.7	125.4
CV-24069	6/15/2026 8:00:00 AM						120000				
CV-24069	6/15/2026 8:00:00 AM					1100					

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]
CV-24069	6/16/2026 9:36:41 AM	11.3	71.9	0.0	16.8			0.2	0.0	137.4	140.4
CV-24069	6/16/2026 9:37:03 AM	12.0	76.2	0.0	11.8			0.2	0.0	140.3	140.6
CV-24069	6/16/2026 9:37:50 AM	12.2	76.5	0.0	11.3			0.2	0.0	140.4	140.1
CV-24070	6/3/2026 10:03:54 AM	25.5	68.2	0.0	6.3			0.4	0.0	135.9	135.6
CV-24070	6/3/2026 10:04:21 AM	26.7	68.2	0.4	4.7			0.4	11.8	135.4	135.3
CV-24070	6/12/2026 9:10:00 AM						55000				
CV-24070	6/12/2026 9:10:00 AM					600					
CV-24070	6/24/2026 1:12:10 PM	7.3	77.7	0.0	15.0			0.1	0.0	140.8	140.9
CV-24070	6/24/2026 1:12:40 PM	7.0	82.3	0.0	10.7			0.1	0.0	141.1	141.1
CV-24071	6/3/2026 2:29:39 PM	44.3	53.3	0.4	2.0			0.8	5.0	120.5	120.7
CV-24071	6/12/2026 9:00:00 AM					290					
CV-24071	6/12/2026 9:00:00 AM						36000				
CV-24071	6/22/2026 10:12:46 AM	33.2	62.8	0.0	4.0			0.5	0.0	134.3	134.7
CV-24071	6/22/2026 10:13:06 AM	32.3	64.9	0.0	2.8			0.5	0.0	134.6	134.6
CV-24072	6/2/2026 4:06:57 PM	29.3	70.7	0.0	0.0			0.4	0.0	117.7	118.6
CV-24072	6/2/2026 4:09:25 PM	39.2	60.8	0.0	0.0			0.6	0.0	117.7	117.9
CV-24072	6/22/2026 10:08:42 AM	38.4	61.4	0.0	0.2			0.6	0.0	123.1	123.9
CV-24073-TI	6/4/2026 8:59:38 AM	18.6	70.4	0.0	11.0			0.3	0.0	160.3	162.6
CV-24073-TI	6/4/2026 9:05:52 AM	14.0	73.5	0.0	12.5			0.2	0.0	162.6	161.8
CV-24073-TI	6/10/2026 2:06:19 PM	34.2	65.4	0.0	0.4			0.5	0.0	155.1	156.6
CV-24073-TI	6/10/2026 2:07:26 PM	39.8	60.2	0.0	0.0			0.7	0.0	157.0	156.8
CV-24073-TI	6/26/2026 8:59:10 AM	35.8	62.6	0.0	1.6			0.6	0.0	155.0	155.0
CV-24073-TI	6/26/2026 9:00:11 AM	30.4	65.0	0.0	4.6			0.5	0.0	154.9	155.3

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]
CV-24073-TI	6/30/2026 1:58:39 PM	14.2	85.8	0.0	0.0			0.2	0.0	151.5	152.3
CV-24073-TI	6/30/2026 1:59:55 PM	34.4	65.6	0.0	0.0			0.5	0.0	151.8	151.9
CV-24074	6/4/2026 9:11:06 AM	2.2	80.0	0.0	17.8			0.0	0.0	123.1	124.1
CV-24074	6/16/2026 9:24:52 AM										
CV-24074	6/24/2026 1:10:15 PM	11.1	74.8	0.3	13.8			0.1	46.0	129.1	129.8
CV-24075-TI	6/1/2026 2:36:56 PM	18.3	75.8	1.1	4.8			0.2	4.4	186.8	186.7
CV-24075-TI	6/1/2026 2:40:00 PM						112600				
CV-24075-TI	6/1/2026 2:40:00 PM					2500					
CV-24075-TI	6/10/2026 2:18:34 PM	16.0	75.4	1.2	7.4			0.2	6.2	186.5	186.6
CV-24075-TI	6/24/2026 9:17:11 AM	8.9	73.6	2.3	15.2			0.1	6.6	186.9	186.8
CV-24075-TI	6/30/2026 2:19:22 PM	9.6	79.6	0.8	10.0			0.1	12.5	186.1	185.9
CV-24076	6/4/2026 9:16:55 AM	14.7	73.9	0.0	11.4			0.2	0.0	175.8	176.0
CV-24076	6/10/2026 2:27:37 PM	35.9	64.1	0.0	0.0			0.6	0.0	172.6	172.6
CV-24076	6/22/2026 1:41:43 PM	34.9	65.1	0.0	0.0			0.5	0.0	175.1	175.7
CV-24076	6/30/2026 2:39:35 PM	23.0	76.6	0.0	0.4			0.3	0.0	171.6	173.5
CV-24077	6/1/2026 2:47:35 PM	34.8	46.9	0.0	18.3			0.7	0.0	139.3	138.9
CV-24077	6/2/2026 7:49:32 AM	12.4	67.4	0.0	20.2			0.2	0.0	144.6	144.7
CV-24077	6/2/2026 7:52:34 AM	5.8	84.4	0.0	9.8			0.1	0.0	142.7	137.0
CV-24077	6/6/2026 12:27:22 PM										
CV-24077	6/11/2026 3:08:29 PM	16.3	58.0	0.3	25.4			0.3	84.7	144.0	148.3
CV-24077	6/11/2026 3:10:14 PM	10.1	79.0	0.2	10.7			0.1	53.5	149.1	149.0
CV-24077	6/15/2026 2:24:46 PM	7.5	77.6	0.0	14.9			0.1	0.0	152.1	152.1
CV-24077	6/16/2026 7:33:30 AM	16.3	42.8	0.0	40.9			0.4	0.0	144.4	143.9
CV-24077	6/16/2026 7:35:27 AM	15.8	49.1	0.0	35.1			0.3	0.0	143.7	144.1
CV-24077	6/19/2026 10:22:28 AM	12.7	68.2	0.1	19.0			0.2	190.0	150.4	150.1
CV-24077	6/19/2026 10:23:54 AM	12.6	68.8	0.0	18.6			0.2	0.0	151.0	151.2
CV-24077	6/24/2026 1:14:10 PM	37.6	61.9	0.0	0.5			0.6	0.0	151.4	151.2
CV-24077	6/30/2026 11:17:02 AM	13.9	59.7	0.4	26.0			0.2	65.0	147.3	149.1
CV-24077	6/30/2026 11:19:14 AM	11.9	69.5	0.1	18.5			0.2	185.0	149.0	149.0

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24078	6/2/2026 7:45:28 AM	30.5	42.6	0.4	26.5			0.7	66.3	126.6	124.3
CV-24078	6/6/2026 12:33:36 PM										
CV-24078	6/16/2026 7:39:27 AM	20.0	65.4	1.8	12.8			0.3	7.1	102.4	102.8
CV-24078	6/19/2026 11:42:01 AM										
CV-24078	6/25/2026 3:22:02 PM										
CV-24078	6/25/2026 3:22:24 PM										
CV-24078	6/25/2026 3:23:34 PM										
CV-24078	6/26/2026 1:44:33 PM										
CV-24078	6/26/2026 1:44:44 PM										
CV-24079-TI	6/4/2026 12:07:14 PM	34.8	54.8	0.0	10.4			0.6	0.0	150.1	147.9
CV-24079-TI	6/4/2026 12:09:00 PM	27.2	61.4	0.0	11.4			0.4	0.0	147.5	148.2
CV-24079-TI	6/9/2026 1:56:55 PM	51.6	48.4	0.0	0.0			1.1	0.0	153.6	154.2
CV-24079-TI	6/9/2026 1:57:28 PM	50.6	49.4	0.0	0.0			1.0	0.0	153.2	153.7
CV-24079-TI	6/16/2026 1:51:51 PM	58.8	41.2	0.0	0.0			1.4	0.0	145.5	145.8
CV-24079-TI	6/23/2026 2:42:01 PM	56.2	43.7	0.0	0.1			1.3	0.0	149.5	150.2
CV-24079-TI	6/30/2026 10:39:33 AM	37.7	51.7	0.0	10.6			0.7	0.0	143.3	142.7
CV-24080	6/3/2026 8:57:08 AM	29.8	67.1	0.0	3.1			0.4	0.0	120.8	120.6
CV-24080	6/16/2026 9:30:00 AM	40.2	56.5	0.0	3.3			0.7	0.0	121.1	121.4
CV-24081-TI	6/3/2026 10:09:44 AM	45.2	54.8	0.0	0.0			0.8	0.0	113.7	114.3
CV-24081-TI	6/16/2026 9:43:47 AM	49.1	47.3	0.0	3.6			1.0	0.0	118.3	118.4
CV-24081-TI	6/23/2026 12:39:08 PM										
CV-24081-TI	6/25/2026 3:13:31 PM										
CV-24081-TI	6/25/2026 3:13:41 PM										
CV-24082	6/3/2026 2:39:26 PM	30.1	63.4	0.0	6.5			0.5	0.0	115.8	115.7
CV-24082	6/16/2026 10:19:49 AM	36.5	61.4	0.0	2.1			0.6	0.0	122.0	122.5
CV-24083	6/3/2026 2:36:38 PM	42.9	54.0	0.0	3.1			0.8	0.0	115.5	116.1
CV-24083	6/15/2026 10:42:17 AM										
CV-24083	6/22/2026 10:20:18 AM	20.3	72.6	0.0	7.1			0.3	0.0	148.5	149.8
CV-24083	6/22/2026 10:20:37 AM	19.5	73.4	0.0	7.1			0.3	0.0	148.3	149.8
CV-24084-TI	6/2/2026 2:30:00 PM					2240					
CV-24084-TI	6/2/2026 2:30:05 PM	14.9	80.1	0.0	5.0			0.2	0.0	181.3	181.6

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24084-TI	6/11/2026 9:56:54 AM	16.4	75.9	0.0	7.7			0.2	0.0	182.6	182.7
CV-24084-TI	6/16/2026 2:12:06 PM	11.3	79.7	0.0	9.0			0.1	0.0	183.4	183.4
CV-24084-TI	6/24/2026 9:57:44 AM	14.5	77.8	0.0	7.7			0.2	0.0	183.1	183.1
CV-24084-TI	6/30/2026 1:30:00 PM	7.7	78.4	0.0	13.9			0.1	0.0	183.1	183.1
CV-24085	6/1/2026 11:07:12 AM	27.1	38.7	0.0	34.2			0.7	0.0	129.0	128.9
CV-24085	6/22/2026 10:40:32 AM	35.5	44.2	0.0	20.2			0.8	0.0	129.5	129.6
CV-24086	6/3/2026 8:44:16 AM	48.8	49.3	0.0	1.9			1.0	0.0	116.0	116.0
CV-24086	6/16/2026 9:26:38 AM	49.7	47.4	0.0	2.9			1.0	0.0	118.7	118.2
CV-24087	6/2/2026 2:23:52 PM	39.4	43.5	0.4	16.7			0.9	41.8	119.6	119.7
CV-24087	6/19/2026 2:08:39 PM	43.4	43.0	0.1	13.5			1.0	135.0	119.4	119.4
CV-24088	6/3/2026 2:54:01 PM	37.3	58.0	0.0	4.7			0.6	0.0	115.0	115.6
CV-24088	6/22/2026 1:23:31 PM	47.0	48.3	0.0	4.7			1.0	0.0	110.7	110.5
CV-24089	6/1/2026 3:18:19 PM	5.5	14.1	15.1	65.3			0.4	4.3	92.7	92.7
CV-24089	6/1/2026 3:20:14 PM	1.2	3.0	20.1	75.7			0.4	3.8	90.9	91.0
CV-24089	6/17/2026 1:05:18 PM	36.7	41.2	2.9	19.2			0.9	6.6	89.3	91.4
CV-24090	6/1/2026 3:34:26 PM	35.3	54.1	0.0	10.6			0.7	0.0	113.5	113.8
CV-24090	6/17/2026 12:58:09 PM	39.1	45.2	0.0	15.7			0.9	0.0	118.8	117.7
CV-24091	6/2/2026 1:20:08 PM	54.4	44.9	0.0	0.7			1.2	0.0	98.8	98.6
CV-24091	6/19/2026 1:33:24 PM	54.9	43.6	0.0	1.5			1.3	0.0	93.1	92.4
CV-24092	6/4/2026 8:13:48 AM	53.7	40.9	0.0	5.4			1.3	0.0	122.1	122.1
CV-24093	6/4/2026 9:21:34 AM	46.6	51.5	0.0	1.9			0.9	0.0	118.5	118.6
CV-24093	6/16/2026 5:45:55 AM	48.6	49.5	0.0	1.9			1.0	0.0	115.6	115.6
CV-24094	6/8/2026 12:10:53 PM	15.0	77.6	0.0	7.4			0.2	0.0	89.2	90.7
CV-24094	6/8/2026 12:13:02 PM	11.9	74.2	2.7	11.2			0.2	4.1	87.0	87.5
CV-24094	6/22/2026 8:57:15 AM	18.6	53.0	6.6	21.8			0.4	3.3	90.9	91.0
CV-24094	6/22/2026 8:58:14 AM	18.2	52.2	6.1	23.5			0.3	3.9	91.1	91.2
CV-24095	6/3/2026 10:39:26 AM	18.6	76.9	0.2	4.3			0.2	21.5	179.3	179.5

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24095	6/3/2026 10:40:36 AM	18.3	77.3	0.0	4.4			0.2	0.0	179.7	179.8
CV-24095	6/3/2026 10:45:00 AM						148300				
CV-24095	6/8/2026 1:35:18 PM	3.2	77.2	0.0	19.6			0.0	0.0	181.0	181.2
CV-24095	6/8/2026 1:36:04 PM	3.0	79.7	0.0	17.3			0.0	0.0	181.5	181.6
CV-24095	6/10/2026 1:17:22 PM	22.2	76.4	0.0	1.4			0.3	0.0	180.5	180.5
CV-24095	6/16/2026 8:20:00 AM						170000				
CV-24095	6/16/2026 8:20:00 AM					2500					
CV-24095	6/17/2026 10:38:51 AM	3.1	82.6	0.0	14.3			0.0	0.0	182.2	182.1
CV-24096	6/11/2026 10:32:09 AM	23.4	31.7	8.7	36.2			0.7	4.2	98.7	98.7
CV-24096	6/11/2026 10:33:45 AM	26.9	36.4	7.0	29.7			0.7	4.2	98.8	98.7
CV-24096	6/12/2026 9:48:27 AM	29.1	43.7	4.5	22.7			0.7	5.0	97.3	97.7
CV-24096	6/25/2026 11:07:44 AM	43.4	54.4	0.0	2.2			0.8	0.0	88.3	88.8
CV-24096	6/25/2026 11:09:58 AM	38.7	53.0	1.3	7.0			0.7	5.4	89.3	89.3
CV-24097	6/10/2026 10:19:39 AM	38.6	37.7	3.9	19.8			1.0	5.1	85.8	86.9
CV-24097	6/16/2026 7:47:31 AM	50.4	46.2	0.1	3.3			1.1	33.0	104.3	105.2
CV-24098	6/1/2026 9:10:16 AM										
CV-24098	6/2/2026 7:53:08 AM										
CV-24098	6/5/2026 10:47:49 AM										
CV-24098	6/6/2026 8:15:18 AM										
CV-24098	6/9/2026 4:08:34 PM										
CV-24098	6/9/2026 4:08:44 PM										
CV-24098	6/10/2026 8:26:44 AM	44.7	41.8	2.2	11.3			1.1	5.1	83.3	83.6
CV-24098	6/19/2026 12:22:19 PM										
CV-24098	6/25/2026 10:59:13 AM	41.9	40.9	3.0	14.2			1.0	4.7	83.7	83.7
CV-24098	6/30/2026 1:29:44 PM										
CV-24098	6/30/2026 1:30:02 PM										
CV-24099	6/10/2026 11:59:36 AM										
CV-24099	6/10/2026 11:59:36 AM										
CV-24099	6/11/2026 10:15:38 AM	14.2	47.5	6.5	31.8			0.3	4.9	96.4	96.5
CV-24099	6/11/2026 10:19:14 AM	4.1	16.1	15.9	63.9			0.3	4.0	96.2	96.3
CV-24099	6/12/2026 9:26:51 AM	19.2	70.6	1.3	8.9			0.3	6.8	91.4	91.5

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24099	6/17/2026 10:19:03 AM	34.7	65.3	0.0	0.0			0.5	0.0	87.1	88.1
CV-24099	6/17/2026 10:22:36 AM	33.8	66.2	0.0	0.0			0.5	0.0	88.2	88.3
CV-24100	6/1/2026 9:40:00 AM						6700				
CV-24100	6/1/2026 9:40:00 AM					42					
CV-24100	6/3/2026 10:14:54 AM	35.0	65.0	0.0	0.0			0.5	0.0	151.0	150.7
CV-24100	6/3/2026 10:15:00 AM						15000				
CV-24100	6/10/2026 1:48:21 PM	32.7	67.1	0.2	0.0			0.5	0.0	152.5	152.1
CV-24100	6/10/2026 1:50:08 PM	34.9	65.0	0.1	0.0			0.5	0.0	152.6	152.9
CV-24100	6/17/2026 8:28:06 AM	20.5	76.2	0.0	3.3			0.3	0.0	90.5	90.5
CV-24100	6/17/2026 10:27:26 AM	21.8	70.5	0.0	7.7			0.3	0.0	152.9	153.2
CV-24100	6/17/2026 10:27:54 AM	20.6	73.5	0.0	5.9			0.3	0.0	152.9	153.6
CV-24101	6/2/2026 7:53:37 AM										
CV-24101	6/4/2026 7:59:12 AM										
CV-24101	6/6/2026 8:14:26 AM										
CV-24101	6/9/2026 2:32:46 PM										
CV-24101	6/9/2026 2:32:58 PM										
CV-24101	6/10/2026 8:31:01 AM	43.9	50.4	0.0	5.7			0.9	0.0	107.6	111.3
CV-24101	6/16/2026 9:30:00 AM					110					
CV-24101	6/16/2026 9:30:00 AM						0				
CV-24101	6/17/2026 8:21:54 AM	44.4	52.0	0.0	3.6			0.9	0.0	90.5	90.5
CV-24101	6/19/2026 12:10:06 PM										
CV-24101	6/30/2026 2:47:24 PM										
CV-24101	6/30/2026 2:47:36 PM										
CV-24102	6/2/2026 7:38:32 AM										
CV-24102	6/6/2026 8:13:53 AM										
CV-24102	6/8/2026 1:06:02 PM	42.1	53.6	0.0	4.3			0.8	0.0	95.3	95.3
CV-24102	6/16/2026 8:47:00 AM	42.6	53.8	0.0	3.6			0.8	0.0	96.8	97.0
CV-24102	6/29/2026 1:05:13 PM										
CV-24103	6/1/2026 10:11:29 AM	40.2	42.5	0.3	17.0			0.9	56.7	90.5	92.1
CV-24103	6/17/2026 12:16:15 PM	44.3	45.2	0.0	10.5			1.0	0.0	96.5	96.5
CV-24104	6/1/2026 3:09:05 PM	41.7	53.8	0.2	4.3			0.8	21.5	98.0	96.4
CV-24104	6/3/2026 2:45:25 PM										
CV-24104	6/19/2026 2:53:53 PM	44.2	55.6	0.0	0.2			0.8	0.0	92.4	92.5
CV-24105	6/1/2026 2:59:30 PM	44.2	41.2	0.9	13.7			1.1	15.2	108.3	108.2
CV-24105	6/3/2026 2:50:39 PM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24105	6/17/2026 1:20:46 PM	47.3	43.0	0.0	9.7			1.1	0.0	113.3	113.2
CV-24106	6/1/2026 3:40:10 PM	39.6	43.0	0.0	17.4			0.9	0.0	128.8	128.7
CV-24106	6/19/2026 11:21:28 AM	45.2	40.4	0.0	14.4			1.1	0.0	122.7	124.6
CV-24106	6/19/2026 2:40:04 PM	46.8	41.0	0.1	12.1			1.1	121.0	123.2	123.2
CV-24107	6/11/2026 11:00:24 AM	48.8	44.0	0.0	7.2			1.1	0.0	118.7	118.7
CV-24108	6/1/2026 1:18:43 PM										
CV-24108	6/2/2026 9:11:29 AM										
CV-24108	6/3/2026 8:42:03 AM	53.1	40.6	0.0	6.3			1.3	0.0	128.8	128.9
CV-24108	6/3/2026 9:24:44 AM										
CV-24108	6/4/2026 8:13:47 AM										
CV-24108	6/5/2026 1:40:27 PM										
CV-24108	6/6/2026 8:22:48 AM										
CV-24108	6/8/2026 3:30:54 PM										
CV-24108	6/8/2026 3:37:11 PM										
CV-24108	6/18/2026 2:02:43 PM										
CV-24108	6/19/2026 11:47:53 AM										
CV-24108	6/24/2026 11:07:23 AM										
CV-24108	6/24/2026 11:07:33 AM										
CV-24108	6/24/2026 11:08:01 AM										
CV-24108	6/24/2026 11:09:51 AM										
CV-24108	6/25/2026 2:12:26 PM										
CV-24108	6/25/2026 2:12:49 PM										
CV-24108	6/29/2026 2:23:43 PM										
CV-24108	6/29/2026 2:23:58 PM										
CV-24109	6/1/2026 1:15:50 PM										
CV-24109	6/2/2026 9:05:54 AM										
CV-24109	6/3/2026 8:29:21 AM	26.1	37.6	1.3	35.0			0.7	26.9	99.9	101.3
CV-24109	6/3/2026 9:19:32 AM										
CV-24109	6/4/2026 8:18:15 AM										
CV-24109	6/5/2026 1:36:04 PM										
CV-24109	6/6/2026 8:36:42 AM										
CV-24109	6/8/2026 3:20:24 PM										
CV-24109	6/8/2026 3:20:49 PM										
CV-24109	6/19/2026 11:42:44 AM										
CV-24109	6/24/2026 11:00:46 AM										
CV-24109	6/24/2026 11:00:54 AM										
CV-24109	6/25/2026 2:01:59 PM										
CV-24109	6/25/2026 2:02:09 PM										
CV-24109	6/29/2026 2:15:54 PM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24109	6/29/2026 2:16:04 PM										
CV-24109	6/29/2026 4:07:05 PM										
CV-24109	6/30/2026 11:41:30 AM	30.7	43.2	0.1	26.0			0.7	260.0	106.4	106.2
CV-24110	6/8/2026 11:54:29 AM	43.1	48.7	0.0	8.2			0.9	0.0	124.0	123.9
CV-24110	6/19/2026 9:53:23 AM	45.0	52.2	0.0	2.8			0.9	0.0	125.5	125.4
CV-24111	6/3/2026 12:34:12 PM	47.4	47.6	0.0	5.0			1.0	0.0	118.3	117.6
CV-24111	6/19/2026 10:04:31 AM	48.8	47.3	0.0	3.9			1.0	0.0	105.5	105.2
CV-24112	6/8/2026 11:49:51 AM	50.0	42.6	0.1	7.3			1.2	73.0	127.4	127.5
CV-24114	6/10/2026 9:27:53 AM	56.3	42.0	0.0	1.7			1.3	0.0	122.7	122.9
CV-24114	6/29/2026 10:36:19 AM										
CV-24116	6/8/2026 3:48:25 PM	49.1	47.5	0.1	3.3			1.0	33.0	121.0	120.1
CV-24117	6/3/2026 11:49:43 AM	48.6	40.2	0.0	11.2			1.2	0.0	101.2	101.7
CV-24118	6/3/2026 9:22:48 AM	26.3	67.9	0.0	5.8			0.4	0.0	128.6	128.1
CV-24119	6/15/2026 10:17:22 AM	48.2	44.8	0.0	7.0			1.1	0.0	106.9	120.9
CV-24119	6/15/2026 10:18:25 AM	49.0	45.2	0.0	5.8			1.1	0.0	119.4	119.2
CV-24120	6/5/2026 1:09:53 PM	4.4	63.5	4.9	27.2			0.1	5.6	97.3	97.3
CV-24120	6/10/2026 12:49:09 PM	11.2	78.3	1.4	9.1			0.1	6.5	122.4	123.2
CV-24120	6/12/2026 9:55:00 AM					360					
CV-24120	6/12/2026 9:55:00 AM						30000				
CV-24120	6/17/2026 1:11:35 PM	1.5	20.6	16.2	61.7			0.1	3.8	89.1	90.0
CV-24120	6/17/2026 1:13:40 PM	0.7	8.3	18.3	72.6			0.1	4.0	90.4	90.4
CV-24121	6/4/2026 8:00:00 AM						2600				
CV-24121	6/4/2026 8:00:00 AM					22					
CV-24121	6/8/2026 1:33:03 PM	12.3	32.3	10.7	44.7			0.4	4.2	89.5	89.6
CV-24121	6/8/2026 1:35:33 PM	12.1	32.2	10.7	45.1			0.4	4.2	89.2	88.4
CV-24121	6/8/2026 1:37:57 PM	10.6	30.8	11.7	46.9			0.3	4.0	90.0	90.0
CV-24121	6/17/2026 1:02:38 PM	33.0	61.3	0.0	5.7			0.5	0.0	95.1	

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24121	6/17/2026 1:03:08 PM	32.3	61.1	0.0	6.6			0.5	0.0	94.5	94.5
CV-24121	6/29/2026 11:25:28 AM										
CV-24121	6/29/2026 1:04:01 PM										
CV-24121	6/29/2026 1:04:44 PM										
CV-24122	6/4/2026 8:20:00 AM					0					
CV-24122	6/4/2026 8:20:00 AM						0				
CV-24122	6/5/2026 10:41:55 AM	25.3	32.0	9.2	33.5			0.8	3.6	94.1	100.6
CV-24122	6/5/2026 10:43:09 AM	11.1	14.0	15.9	59.0			0.8	3.7	101.0	101.0
CV-24122	6/17/2026 12:45:58 PM	49.2	47.2	0.0	3.6			1.0	0.0	92.9	95.3
CV-24122	6/17/2026 12:55:28 PM	41.5	39.9	3.9	14.7			1.0	3.7	95.7	95.7
CV-24123	6/9/2026 2:05:21 PM	39.6	55.5	0.0	4.9			0.7	0.0	118.5	118.7
CV-24123	6/19/2026 1:07:56 PM	44.9	50.5	0.0	4.6			0.9	0.0	116.4	117.8
CV-24123	6/24/2026 7:30:31 AM	42.9	53.6	0.0	3.5			0.8	0.0	117.6	117.6
CV-24124	6/5/2026 1:18:36 PM	5.1	80.3	0.0	14.6			0.1	0.0	132.5	132.2
CV-24124	6/5/2026 1:19:19 PM	5.0	81.5	0.0	13.5			0.1	0.0	132.2	132.4
CV-24124	6/26/2026 8:04:01 AM	6.1	80.9	0.0	13.0			0.1	0.0	130.8	131.2
CV-24124	6/26/2026 8:04:44 AM	5.6	81.0	0.0	13.4			0.1	0.0	130.9	132.3
CV-24125-TF	6/3/2026 8:20:00 AM						1000				
CV-24125-TF	6/3/2026 8:20:00 AM					12					
CV-24125-TF	6/5/2026 10:14:30 AM	32.0	64.9	0.4	2.7			0.5	6.8	120.4	119.6
CV-24125-TF	6/5/2026 1:26:59 PM	19.3	74.0	0.9	5.8			0.3	6.4	88.5	88.7
CV-24125-TF	6/11/2026 3:48:37 PM	34.4	65.0	0.5	0.1			0.5	0.2	115.3	116.6
CV-24125-TF	6/17/2026 12:29:31 PM	38.8	56.6	0.0	4.6			0.7	0.0	106.3	106.7

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]
CV-24125-TI	6/17/2026 12:38:33 PM	39.3	56.6	0.0	4.1			0.7	0.0	108.9	108.9
CV-24125-TI	6/23/2026 1:29:02 PM										
CV-24125-TI	6/23/2026 1:29:17 PM										
CV-24125-TI	6/26/2026 11:28:57 AM										
CV-24125-TI	6/26/2026 11:29:08 AM										
CV-24125-TI	6/30/2026 11:22:53 AM										
CV-24126	6/1/2026 1:39:04 PM	12.4	71.2	0.0	16.4			0.2	0.0	187.5	187.5
CV-24126	6/1/2026 1:55:00 PM						172800				
CV-24126	6/1/2026 1:55:00 PM					3345					
CV-24126	6/8/2026 1:09:09 PM	4.0	80.1	0.0	15.9			0.0	0.0	187.9	187.1
CV-24126	6/15/2026 10:13:34 AM	14.3	71.3	0.0	14.4			0.2	0.0	189.9	190.2
CV-24126	6/22/2026 1:18:00 PM	16.6	74.7	0.0	8.7			0.2	0.0	188.8	188.7
CV-24126	6/26/2026 1:10:44 PM										
CV-24126	6/29/2026 1:46:26 PM	11.0	78.5	0.0	10.5			0.1	0.0	189.1	188.8
CV-24127	6/1/2026 2:39:12 PM										
CV-24127	6/2/2026 8:17:51 AM										
CV-24127	6/3/2026 8:44:10 AM										
CV-24127	6/4/2026 9:00:33 AM										
CV-24127	6/4/2026 9:10:00 AM						170000				
CV-24127	6/4/2026 9:10:00 AM					3700					
CV-24127	6/5/2026 12:14:23 PM										
CV-24127	6/10/2026 2:32:41 PM										
CV-24127	6/10/2026 2:33:22 PM										
CV-24127	6/12/2026 7:25:49 AM										
CV-24127	6/12/2026 8:12:32 AM	6.9	71.1	0.0	22.0			0.1	0.0	172.7	171.3
CV-24127	6/12/2026 8:14:13 AM	3.6	78.0	0.0	18.4			0.0	0.0	171.5	171.8
CV-24127	6/15/2026 10:05:15 AM	28.7	69.0	0.0	2.3			0.4	0.0	161.0	162.3
CV-24127	6/19/2026 10:42:55 AM										
CV-24127	6/22/2026 1:16:07 PM	18.9	73.6	0.0	7.5			0.3	0.0	160.9	160.0
CV-24127	6/23/2026 12:34:42 PM										
CV-24127	6/26/2026 10:26:04 AM	5.3	80.4	0.0	14.3			0.1	0.0	172.4	172.5
CV-24127	6/26/2026 10:26:28 AM	5.2	82.1	0.0	12.7			0.1	0.0	172.4	172.9
CV-24127	6/26/2026 11:18:15 AM										
CV-24127	6/26/2026 11:18:25 AM										
CV-24127	6/29/2026 1:43:55 PM	12.5	77.6	0.0	9.9			0.2	0.0	163.6	161.7

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]
CV-24128	6/3/2026 8:10:00 AM						10000				
CV-24128	6/3/2026 8:10:00 AM					180					
CV-24128	6/4/2026 2:19:54 PM	37.2	43.2	1.3	18.3			0.9	14.1	108.0	108.3
CV-24128	6/10/2026 12:54:14 PM	20.8	65.0	0.7	13.5			0.3	19.3	124.6	124.6
CV-24128	6/17/2026 1:41:36 PM	21.7	64.2	0.0	14.1			0.3	0.0	110.2	109.8
CV-24129	6/2/2026 8:22:22 AM										
CV-24129	6/4/2026 2:23:16 PM	41.6	55.8	0.2	2.4			0.7	12.0	123.5	122.8
CV-24129	6/17/2026 12:18:08 PM	42.8	53.3	0.0	3.9			0.8	0.0	121.9	123.0
CV-24129	6/17/2026 12:19:01 PM	42.1	53.2	0.0	4.8			0.8	0.0	122.8	122.7
CV-24130	6/5/2026 9:53:23 AM	18.6	69.5	0.3	11.6			0.3	38.7	123.4	123.3
CV-24131	6/5/2026 9:45:53 AM	44.2	55.1	0.0	0.7			0.8	0.0	124.0	124.0
CV-24132	6/1/2026 8:49:59 AM	50.8	42.3	0.0	6.9			1.2	0.0	128.8	128.8
CV-24133	6/1/2026 9:23:18 AM	50.4	41.7	0.0	7.9			1.2	0.0	123.3	123.3
CV-24134-TI	6/1/2026 1:35:53 PM	36.3	63.7	0.0	0.0			0.6	0.0	151.4	151.6
CV-24134-TI	6/1/2026 1:50:00 PM						115900				
CV-24134-TI	6/1/2026 1:50:00 PM					2930					
CV-24134-TI	6/8/2026 1:05:55 PM	24.6	71.4	0.0	4.0			0.3	0.0	152.0	152.5
CV-24134-TI	6/15/2026 10:02:38 AM	41.5	58.5	0.0	0.0			0.7	0.0	151.6	151.9
CV-24134-TI	6/22/2026 1:13:16 PM	40.9	59.1	0.0	0.0			0.7	0.0	152.4	152.1
CV-24134-TI	6/29/2026 1:36:41 PM	33.3	66.7	0.0	0.0			0.5	0.0	153.8	153.9
CV-24135	6/4/2026 1:50:11 PM	21.8	68.2	0.0	10.0			0.3	0.0	137.1	120.1
CV-24135	6/16/2026 9:51:38 AM										
CV-24135	6/17/2026 12:00:10 PM	27.6	58.8	0.0	13.6			0.5	0.0	136.0	135.2
CV-24135	6/17/2026 12:02:54 PM	26.7	59.4	0.0	13.9			0.4	0.0	136.2	135.3
CV-24135	6/17/2026 12:07:10 PM	25.0	60.2	0.0	14.9			0.4	0.0	135.7	134.4

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24135	6/17/2026 12:12:01 PM	23.1	64.0	0.0	12.9			0.4	0.0	134.9	135.3
CV-24135	6/17/2026 12:13:45 PM	24.8	61.8	0.0	13.5			0.4	0.0	135.6	135.8
CV-24135	6/26/2026 9:05:20 AM										
CV-24135	6/30/2026 12:03:49 PM	24.1	69.8	0.0	6.1			0.3	0.0	133.2	130.5
CV-24135	6/30/2026 12:05:26 PM	14.1	80.2	0.0	5.7			0.2	0.0	130.9	130.8
CV-24136	6/4/2026 12:45:38 PM	34.6	49.9	0.0	15.5			0.7	0.0	145.7	144.0
CV-24136	6/4/2026 12:48:47 PM	34.4	49.2	0.0	16.4			0.7	0.0	143.8	142.1
CV-24137	6/15/2026 9:10:06 AM	42.4	47.9	0.0	9.7			0.9	0.0	124.0	123.0
CV-24138	6/1/2026 9:23:15 AM										
CV-24138	6/1/2026 9:25:00 AM					740					
CV-24138	6/1/2026 9:25:00 AM						180000				
CV-24138	6/2/2026 7:36:39 AM										
CV-24138	6/3/2026 7:54:50 AM										
CV-24138	6/4/2026 3:06:11 PM										
CV-24138	6/6/2026 8:16:09 AM										
CV-24138	6/9/2026 3:28:51 PM										
CV-24138	6/9/2026 3:29:09 PM										
CV-24138	6/10/2026 8:38:31 AM	1.5	69.6	0.5	28.4			0.0	56.8	170.1	169.1
CV-24138	6/10/2026 8:42:15 AM	2.5	72.3	0.5	24.7			0.0	49.4	171.7	169.1
CV-24138	6/11/2026 10:55:56 AM	15.2	68.2	0.0	16.6			0.2	0.0	160.2	160.8
CV-24138	6/16/2026 8:25:00 AM					780					
CV-24138	6/16/2026 8:25:00 AM						200000				
CV-24138	6/17/2026 8:54:02 AM	0.4	6.2	18.4	75.0			0.1	4.1	90.5	90.5
CV-24138	6/17/2026 8:54:25 AM	0.5	6.8	18.2	74.5			0.1	4.1	90.5	90.5
CV-24138	6/17/2026 1:42:39 PM	3.7	70.1	0.0	26.2			0.1	0.0	136.4	136.0
CV-24138	6/18/2026 9:36:58 AM										
CV-24138	6/19/2026 12:31:39 PM										
CV-24138	6/26/2026 9:57:18 AM	1.5	31.6	11.7	55.2			0.0	4.7	95.5	96.1
CV-24138	6/26/2026 9:57:58 AM	1.5	32.1	11.6	54.8			0.0	4.7	96.4	96.7
CV-24138	6/26/2026 3:55:26 PM										
CV-24138	6/26/2026 3:55:54 PM										
CV-24138	6/30/2026 1:41:18 PM										
CV-24138	6/30/2026 1:41:29 PM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24139	6/1/2026 9:20:00 AM					0					
CV-24139	6/1/2026 9:20:00 AM						9600				
CV-24139	6/1/2026 9:26:24 AM										
CV-24139	6/1/2026 12:37:56 PM										
CV-24139	6/2/2026 7:37:33 AM										
CV-24139	6/3/2026 7:55:49 AM										
CV-24139	6/4/2026 3:07:26 PM										
CV-24139	6/5/2026 10:54:02 AM										
CV-24139	6/6/2026 7:54:14 AM										
CV-24139	6/9/2026 3:23:00 PM										
CV-24139	6/9/2026 3:23:50 PM										
CV-24139	6/10/2026 8:49:20 AM	0.4	10.5	18.2	70.9			0.0	3.9	115.8	117.4
CV-24139	6/10/2026 8:51:40 AM	0.5	9.9	18.2	71.4			0.1	3.9	119.9	112.6
CV-24139	6/16/2026 8:30:00 AM						4900				
CV-24139	6/16/2026 8:30:00 AM					0					
CV-24139	6/17/2026 9:00:45 AM	0.0	0.1	21.1	78.8			0.0	3.7	90.5	90.5
CV-24139	6/17/2026 9:01:29 AM	0.0	0.1	21.1	78.8			0.0	3.7	90.5	90.5
CV-24139	6/18/2026 9:24:33 AM										
CV-24139	6/18/2026 9:33:37 AM										
CV-24139	6/19/2026 12:36:43 PM										
CV-24139	6/26/2026 10:05:15 AM	3.3	70.8	1.3	24.6			0.0	18.9	183.7	184.2
CV-24139	6/26/2026 10:05:49 AM	3.8	71.8	0.8	23.6			0.1	29.5	184.1	184.1
CV-24139	6/26/2026 3:54:38 PM										
CV-24139	6/26/2026 3:54:47 PM										
CV-24139	6/30/2026 1:47:54 PM										
CV-24139	6/30/2026 1:48:05 PM										
CV-24140	6/1/2026 9:15:00 AM						220000				
CV-24140	6/1/2026 9:15:00 AM					1100					
CV-24140	6/1/2026 9:32:55 AM										
CV-24140	6/2/2026 7:51:34 AM										
CV-24140	6/3/2026 7:56:51 AM										
CV-24140	6/3/2026 12:47:00 PM	16.3	70.3	0.0	13.4			0.2	0.0	162.2	162.6
CV-24140	6/3/2026 12:55:00 PM						185700				
CV-24140	6/4/2026 3:08:04 PM										
CV-24140	6/5/2026 10:55:44 AM										
CV-24140	6/6/2026 8:16:54 AM										
CV-24140	6/9/2026 3:19:36 PM										
CV-24140	6/9/2026 3:19:52 PM										
CV-24140	6/10/2026 8:58:38 AM	2.7	73.1	0.3	23.9			0.0	79.7	172.6	178.2

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24140	6/10/2026 9:02:51 AM	2.6	75.9	0.1	21.4			0.0	214.0	178.2	172.1
CV-24140	6/10/2026 1:06:06 PM	26.7	66.4	0.0	6.9			0.4	0.0	166.6	168.3
CV-24140	6/16/2026 8:35:00 AM					850					
CV-24140	6/16/2026 8:35:00 AM						190000				
CV-24140	6/17/2026 1:29:57 PM	3.2	70.8	0.0	26.0			0.0	0.0	170.0	169.3
CV-24140	6/17/2026 1:30:23 PM	3.5	71.7	0.0	24.8			0.0	0.0	169.3	169.4
CV-24140	6/18/2026 9:34:12 AM										
CV-24140	6/18/2026 9:34:21 AM										
CV-24140	6/19/2026 12:38:35 PM										
CV-24140	6/26/2026 10:09:15 AM	3.1	81.3	0.0	15.6			0.0	0.0	182.1	182.1
CV-24140	6/26/2026 10:09:34 AM	3.0	80.0	0.0	17.0			0.0	0.0	181.5	181.7
CV-24140	6/26/2026 3:53:37 PM										
CV-24140	6/26/2026 3:53:50 PM										
CV-24140	6/30/2026 2:49:55 PM										
CV-24140	6/30/2026 2:50:16 PM										
CV-24141	6/11/2026 11:16:59 AM	5.9	10.3	17.0	66.8			0.6	3.9	102.0	102.2
CV-24141	6/11/2026 11:18:59 AM	3.7	6.4	18.6	71.3			0.6	3.8	102.0	102.2
CV-24141	6/12/2026 9:30:00 AM						12000				
CV-24141	6/12/2026 9:30:00 AM					190					
CV-24141	6/12/2026 10:41:06 AM	6.0	16.1	15.1	62.8			0.4	4.2	105.5	106.7
CV-24141	6/12/2026 10:43:21 AM	5.4	13.6	15.7	65.3			0.4	4.2	106.9	106.9
CV-24141	6/17/2026 9:19:34 AM	17.3	29.0	8.2	45.5			0.6	5.5	90.5	90.5
CV-24141	6/17/2026 9:20:54 AM	16.3	28.9	8.7	46.1			0.6	5.3	90.5	90.5
CV-24142	6/1/2026 9:19:23 AM										
CV-24142	6/2/2026 7:52:39 AM										
CV-24142	6/3/2026 7:53:09 AM										
CV-24142	6/4/2026 9:05:00 AM						150000				
CV-24142	6/4/2026 9:05:00 AM					1700					
CV-24142	6/4/2026 3:04:27 PM										
CV-24142	6/5/2026 10:52:26 AM										
CV-24142	6/6/2026 7:49:57 AM										
CV-24142	6/11/2026 1:39:28 PM	3.0	64.4	2.3	30.3			0.0	13.2	112.7	113.1
CV-24142	6/17/2026 8:43:53 AM	6.0	68.0	2.1	23.9			0.1	11.4	90.5	90.5
CV-24142	6/18/2026 9:43:28 AM										
CV-24142	6/18/2026 9:43:58 AM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24142	6/19/2026 12:27:49 PM										
CV-24142	6/26/2026 9:52:53 AM	3.8	64.3	4.3	27.6			0.1	6.4	141.1	141.7
CV-24142	6/26/2026 9:53:35 AM	3.9	64.2	4.2	27.7			0.1	6.6	139.9	139.2
CV-24142	6/26/2026 3:56:35 PM										
CV-24142	6/26/2026 3:56:49 PM										
CV-24142	6/30/2026 2:48:45 PM										
CV-24142	6/30/2026 2:48:56 PM										
CV-24143	6/1/2026 9:05:00 AM					690					
CV-24143	6/1/2026 9:05:00 AM						88000				
CV-24143	6/1/2026 12:34:41 PM	0.8	39.6	11.7	47.9			0.0	4.1	104.3	104.0
CV-24143	6/1/2026 12:36:01 PM	0.9	39.6	11.8	47.7			0.0	4.0	103.7	103.8
CV-24143	6/2/2026 7:50:48 AM										
CV-24143	6/6/2026 8:18:45 AM										
CV-24143	6/11/2026 1:51:00 PM	0.7	80.0	0.0	19.3			0.0	0.0	161.3	161.7
CV-24143	6/12/2026 7:36:10 AM										
CV-24143	6/15/2026 2:49:28 PM	1.1	41.1	10.3	47.5			0.0	4.6	106.2	107.8
CV-24143	6/15/2026 2:50:17 PM	1.2	39.7	10.0	49.1			0.0	4.9	108.1	108.1
CV-24143	6/16/2026 8:40:00 AM						190000				
CV-24143	6/16/2026 8:40:00 AM					1400					
CV-24143	6/17/2026 9:12:04 AM	3.2	73.4	0.0	23.4			0.0	0.0	90.5	90.5
CV-24143	6/19/2026 2:17:30 PM	2.9	82.1	0.2	14.8			0.0	74.0	181.5	181.9
CV-24143	6/19/2026 2:20:36 PM	3.5	80.3	0.8	15.4			0.0	19.3	179.6	180.2
CV-24143	6/23/2026 12:37:57 PM										
CV-24143	6/26/2026 2:23:39 PM										
CV-24143	6/26/2026 2:23:48 PM										
CV-24144	6/10/2026 10:15:37 AM	54.0	39.1	0.6	6.3			1.4	10.5	99.4	99.1
CV-24144	6/16/2026 7:55:40 AM	57.9	39.6	0.0	2.5			1.5	0.0	85.3	85.1
CV-24144	6/30/2026 1:46:16 PM	57.7	40.1	0.3	1.9			1.4	6.3	87.2	87.3
CV-24145	6/9/2026 9:28:49 AM	3.4	0.7	18.4	77.5			4.9	4.2	133.8	135.0
CV-24145	6/25/2026 9:07:34 AM	1.1	57.0	5.7	36.2			0.0	6.4	151.4	150.5
CV-24145	6/25/2026 9:10:07 AM	0.6	53.6	6.9	38.9			0.0	5.6	137.0	128.5
CV-24145	6/25/2026 9:15:45 AM	0.6	62.4	4.5	32.5			0.0	7.2	128.5	130.3

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]
CV-24146	6/8/2026 12:31:18 PM	48.3	47.2	0.0	4.5			1.0	0.0	104.1	109.7
CV-24146	6/8/2026 12:36:09 PM	49.5	46.0	0.0	4.5			1.1	0.0	112.0	112.1
CV-24146	6/8/2026 12:36:53 PM	49.5	45.7	0.0	4.8			1.1	0.0	112.2	112.1
CV-24146	6/19/2026 1:14:29 PM	45.8	50.9	0.0	3.3			0.9	0.0	79.1	80.4
CV-24146	6/19/2026 1:16:24 PM	47.1	49.9	0.0	3.0			0.9	0.0	80.6	80.5
CV-24146	6/24/2026 7:32:54 AM	53.4	43.7	0.0	2.9			1.2	0.0	114.1	114.5
CV-24147	6/1/2026 7:56:42 AM	46.1	38.7	2.6	12.6			1.2	4.8	104.1	104.1
CV-24147	6/17/2026 9:42:16 AM	48.1	37.0	2.8	12.1			1.3	4.3	109.8	109.8
CV-24147	6/19/2026 1:22:48 PM	48.0	39.7	2.4	9.8			1.2	4.1	109.0	108.6
CV-24148	6/3/2026 1:36:29 PM	16.9	76.0	0.8	6.3			0.2	7.9	172.6	173.1
CV-24148	6/3/2026 1:37:51 PM	22.3	77.2	0.5	0.0			0.3	0.0	173.2	172.9
CV-24148	6/3/2026 1:50:00 PM						106400				
CV-24148	6/8/2026 2:26:31 PM	7.2	83.3	0.0	9.5			0.1	0.0	183.0	181.9
CV-24148	6/24/2026 9:05:55 AM	25.1	74.9	0.0	0.0			0.3	0.0	181.4	181.5
CV-24148	6/30/2026 2:31:22 PM	25.5	74.5	0.0	0.0			0.3	0.0	180.8	180.9
CV-24149	6/3/2026 8:58:20 AM										
CV-24149	6/8/2026 2:11:13 PM	3.3	72.0	4.2	20.5			0.0	4.9	98.0	98.3
CV-24149	6/24/2026 12:42:45 PM	10.8	80.2	0.0	9.0			0.1	0.0	122.4	127.7
CV-24149	6/24/2026 12:44:13 PM	17.0	72.4	0.0	10.6			0.2	0.0	128.9	128.8
CV-24149	6/24/2026 1:06:46 PM	29.7	64.2	0.0	6.1			0.5	0.0	125.2	115.3
CV-24150	6/8/2026 12:03:23 PM	41.6	56.1	0.0	2.3			0.7	0.0	105.4	105.9
CV-24150	6/19/2026 10:24:05 AM	44.8	52.5	0.0	2.7			0.9	0.0	97.8	96.9
CV-24151	6/11/2026 9:19:01 AM	41.2	56.9	0.3	1.6			0.7	5.3	106.6	106.7
CV-24151	6/12/2026 11:02:29 AM	47.2	52.6	0.2	0.0			0.9	0.0	116.3	115.8
CV-24151	6/22/2026 9:49:24 AM	45.2	53.2	0.0	1.6			0.8	0.0	111.9	112.5
CV-24152	6/4/2026 8:50:55 AM	19.2	69.2	0.0	11.6			0.3	0.0	134.0	133.9
CV-24152	6/4/2026 8:52:46 AM	19.8	69.1	0.0	11.1			0.3	0.0	133.8	133.8

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24152	6/22/2026 9:16:13 AM	15.6	77.6	0.0	6.8			0.2	0.0	137.5	138.7
CV-24152	6/22/2026 9:16:43 AM	14.7	81.3	0.0	4.0			0.2	0.0	138.8	138.8
CV-24152	6/22/2026 9:17:01 AM	14.7	81.1	0.0	4.2			0.2	0.0	138.8	138.8
CV-24153	6/8/2026 2:34:56 PM	37.5	62.5	0.0	0.0			0.6	0.0	105.2	109.2
CV-24153	6/8/2026 2:36:19 PM	37.7	62.3	0.0	0.0			0.6	0.0	110.3	110.6
CV-24153	6/16/2026 12:58:16 PM	34.9	57.8	0.0	7.3			0.6	0.0	115.9	116.7
CV-24154	6/4/2026 9:27:01 AM	45.8	50.2	0.0	4.0			0.9	0.0	112.2	113.3
CV-24154	6/16/2026 5:48:54 AM	45.6	51.5	0.0	2.9			0.9	0.0	100.3	100.3
CV-24154	6/24/2026 8:27:55 AM	38.6	60.9	0.0	0.5			0.6	0.0	108.0	108.7
CV-24155	6/4/2026 9:16:47 AM	35.2	63.1	0.0	1.7			0.6	0.0	123.8	123.0
CV-24155	6/16/2026 1:01:24 PM	11.4	74.9	0.0	13.7			0.2	0.0	136.2	140.6
CV-24155	6/16/2026 1:01:57 PM	11.0	78.5	0.0	10.5			0.1	0.0	141.2	141.7
CV-24155	6/16/2026 1:02:49 PM	11.3	77.2	0.0	11.5			0.1	0.0	141.5	141.8
CV-24156	6/2/2026 3:57:37 PM	40.0	58.8	0.0	1.2			0.7	0.0	133.9	133.9
CV-24156	6/2/2026 4:00:44 PM	35.7	58.2	1.3	4.8			0.6	3.7	133.7	133.7
CV-24156	6/22/2026 10:04:13 AM	26.0	71.0	0.0	3.0			0.4	0.0	134.9	135.0
CV-24156	6/22/2026 10:04:37 AM	25.9	72.7	0.0	1.4			0.4	0.0	135.1	135.1
CV-24157	6/2/2026 3:51:09 PM	44.4	53.4	0.0	2.2			0.8	0.0	117.4	116.6
CV-24157	6/16/2026 6:16:54 AM	46.4	49.9	0.0	3.7			0.9	0.0	98.2	101.0
CV-24158	6/4/2026 12:34:30 PM	35.2	61.7	0.0	3.1			0.6	0.0	129.1	129.1
CV-24158	6/22/2026 9:54:22 AM	33.8	56.3	0.0	9.9			0.6	0.0	128.4	128.7
CV-24159	6/4/2026 8:31:58 AM	43.4	51.1	0.0	5.5			0.8	0.0	129.9	129.9
CV-24159	6/16/2026 5:43:15 AM	45.1	51.3	0.0	3.6			0.9	0.0	125.1	125.3
CV-24160	6/4/2026 8:28:00 AM	44.6	49.6	0.0	5.8			0.9	0.0	126.0	126.0
CV-24160	6/16/2026 5:53:37 AM	42.6	55.1	0.0	2.3			0.8	0.0	126.5	126.6
CV-24160	6/24/2026 8:22:58 AM	44.7	53.4	0.0	1.9			0.8	0.0	126.4	126.4
CV-24161	6/8/2026 2:46:05 PM	26.3	69.5	0.1	4.1			0.4	41.0	109.6	109.9
CV-24161	6/9/2026 12:29:35 PM	24.8	67.1	0.0	8.1			0.4	0.0	107.1	107.5

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]
CV-24162	6/1/2026 1:17:47 PM										
CV-24162	6/2/2026 9:08:14 AM										
CV-24162	6/2/2026 9:08:14 AM										
CV-24162	6/2/2026 9:08:14 AM										
CV-24162	6/3/2026 8:33:29 AM	31.5	34.4	0.8	33.3			0.9	41.6	97.4	97.3
CV-24162	6/3/2026 9:23:01 AM										
CV-24162	6/4/2026 8:15:24 AM										
CV-24162	6/5/2026 1:38:35 PM										
CV-24162	6/6/2026 8:26:15 AM										
CV-24162	6/8/2026 3:24:54 PM										
CV-24162	6/8/2026 3:27:01 PM										
CV-24162	6/8/2026 3:28:04 PM										
CV-24162	6/19/2026 11:45:45 AM										
CV-24162	6/23/2026 2:28:37 PM										
CV-24162	6/23/2026 2:28:46 PM										
CV-24163	6/2/2026 1:04:07 PM	25.6	70.0	0.0	4.4			0.4	0.0	128.5	129.3
CV-24163	6/2/2026 1:04:55 PM	25.6	69.9	0.0	4.5			0.4	0.0	128.6	129.2
CV-24164	6/3/2026 2:50:38 PM	33.0	64.6	0.0	2.4			0.5	0.0	130.6	130.2
CV-24164	6/16/2026 10:15:41 AM	27.1	67.7	0.0	5.2			0.4	0.0	135.2	135.6
CV-24164	6/16/2026 10:16:45 AM	28.3	70.3	0.0	1.4			0.4	0.0	135.8	136.0
CV-24165	6/2/2026 2:39:55 PM	23.1	74.8	0.0	2.1			0.3	0.0	125.0	125.2
CV-24165	6/22/2026 1:17:09 PM	25.5	63.3	0.0	11.2			0.4	0.0	122.7	122.8
CV-24166	6/2/2026 10:42:56 AM	51.6	46.4	0.2	1.8			1.1	9.0	96.2	96.1
CV-24166	6/16/2026 5:40:44 AM	52.3	44.9	0.3	2.5			1.2	8.3	103.8	105.9
CV-24167	6/11/2026 8:37:37 AM	48.1	41.3	0.0	10.6			1.2	0.0	114.9	115.0
CV-24167	6/22/2026 1:02:56 PM	46.7	38.6	0.0	14.7			1.2	0.0	114.1	113.7
CV-24168	6/2/2026 2:31:57 PM	31.6	47.4	0.6	20.4			0.7	34.0	106.8	91.4
CV-24168	6/16/2026 6:07:33 AM	35.8	42.3	0.0	21.9			0.8	0.0	103.3	105.6
CV-24169	6/2/2026 2:27:55 PM	32.7	57.3	0.0	10.0			0.6	0.0	123.2	123.5
CV-24169	6/3/2026 10:21:30 AM										
CV-24169	6/16/2026 10:26:18 AM	39.8	52.1	0.0	8.1			0.8	0.0	117.6	118.0
CV-24170	6/3/2026 8:39:31 AM	6.7	92.2	0.0	1.1			0.1	0.0	131.3	134.7

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24170	6/3/2026 8:40:16 AM	6.5	91.9	0.0	1.6			0.1	0.0	135.1	135.1
CV-24170	6/16/2026 9:47:43 AM	19.5	76.0	0.0	4.5			0.3	0.0	135.3	135.3
CV-24170	6/16/2026 9:48:20 AM	19.8	76.8	0.0	3.4			0.3	0.0	135.3	135.3
CV-24171	6/2/2026 1:07:59 PM	54.8	45.2	0.0	0.0			1.2	0.0	127.2	127.3
CV-24171	6/19/2026 1:15:27 PM	53.8	44.5	0.0	1.7			1.2	0.0	126.5	126.7
CV-24172	6/2/2026 2:04:51 PM	33.7	34.6	4.2	27.5			1.0	6.5	117.5	117.5
CV-24172	6/19/2026 1:40:24 PM	37.5	39.0	3.0	20.5			1.0	6.8	121.6	121.6
CV-24173	6/2/2026 2:09:46 PM	41.9	38.2	0.9	19.0			1.1	21.1	115.6	115.7
CV-24173	6/19/2026 1:42:31 PM	31.6	62.0	0.0	6.4			0.5	0.0	125.2	125.1
CV-24174	6/11/2026 8:53:10 AM	23.1	41.8	0.0	35.1			0.6	0.0	114.2	114.2
CV-24174	6/22/2026 8:34:05 AM	25.9	39.6	0.0	34.5			0.7	0.0	108.5	108.5
CV-24175	6/2/2026 2:16:56 PM	21.6	55.2	0.0	23.2			0.4	0.0	121.3	121.3
CV-24175	6/19/2026 1:53:40 PM	23.3	51.5	0.0	25.2			0.5	0.0	120.8	120.8
CV-24175	6/22/2026 8:43:24 AM	24.5	47.2	0.0	28.3			0.5	0.0	121.5	121.0
CV-24175	6/22/2026 9:19:56 AM	23.6	50.2	0.0	26.2			0.5	0.0	122.1	122.2
CV-24176	6/1/2026 11:10:13 AM	20.6	71.3	0.1	8.0			0.3	80.0	134.8	134.9
CV-24176	6/1/2026 11:12:09 AM	20.7	73.9	0.0	5.4			0.3	0.0	134.6	134.6
CV-24176	6/24/2026 12:52:18 PM	32.7	65.6	0.0	1.7			0.5	0.0	108.8	110.7
CV-24177	6/2/2026 9:39:48 AM	10.4	21.6	9.8	58.2			0.5	5.9	110.9	111.3
CV-24177	6/2/2026 9:40:38 AM	10.3	21.8	9.8	58.1			0.5	5.9	108.5	108.1
CV-24177	6/16/2026 8:58:44 AM	13.5	26.8	7.7	52.0			0.5	6.8	127.7	127.7
CV-24177	6/16/2026 9:02:31 AM	15.3	22.4	8.7	53.6			0.7	6.2	126.1	125.8
CV-24177	6/25/2026 2:15:12 PM	8.8	77.7	0.0	13.5			0.1	0.0	114.8	118.8
CV-24177	6/25/2026 2:18:20 PM	8.2	81.9	0.0	9.9			0.1	0.0	120.6	122.0
CV-24178	6/1/2026 11:20:23 AM	26.7	57.9	0.0	15.4			0.5	0.0	124.5	125.4

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24178	6/22/2026 9:49:05 AM	9.9	23.7	14.0	52.5			0.4	3.7	85.7	86.0
CV-24178	6/22/2026 9:57:54 AM	29.7	62.7	0.1	7.5			0.5	68.3	127.1	122.9
CV-24178	6/22/2026 9:59:40 AM	30.6	62.0	0.1	7.4			0.5	82.1	124.3	124.4
CV-24179	6/1/2026 11:02:27 AM	23.4	50.5	0.0	26.1			0.5	0.0	129.4	129.4
CV-24179	6/22/2026 10:33:02 AM	33.4	50.5	0.0	16.1			0.7	0.0	132.0	132.5
CV-24179	6/22/2026 10:34:07 AM	32.6	50.5	0.0	16.9			0.6	0.0	132.3	132.3
CV-24180	6/9/2026 2:18:49 PM										
CV-24180	6/9/2026 2:19:23 PM										
CV-24180	6/15/2026 2:02:30 PM	19.4	41.9	0.9	37.8			0.5	42.0	122.6	122.7
CV-24180	6/18/2026 2:51:11 PM										
CV-24180	6/18/2026 2:51:21 PM										
CV-24180	6/22/2026 10:24:27 AM	26.1	48.5	0.0	25.3			0.5	0.0	123.9	124.1
CV-24180	6/30/2026 2:57:39 PM										
CV-24180	6/30/2026 2:57:51 PM										
CV-24181	6/1/2026 3:15:10 PM	35.3	59.7	0.0	5.0			0.6	0.0	108.0	108.2
CV-24181	6/17/2026 1:10:56 PM	24.7	70.7	0.2	4.4			0.3	22.0	95.2	95.3
CV-24182	6/1/2026 3:27:50 PM	37.7	54.9	0.3	7.1			0.7	23.7	109.2	109.0
CV-24182	6/17/2026 1:26:50 PM	41.5	48.6	0.4	9.5			0.9	23.8	112.8	114.4
CV-24183	6/1/2026 3:31:15 PM	46.1	50.9	0.0	3.0			0.9	0.0	100.6	100.6
CV-24183	6/17/2026 1:29:18 PM	47.4	47.8	0.0	4.8			1.0	0.0	104.5	104.8
CV-24184	6/1/2026 12:51:50 PM	27.3	37.9	3.2	31.6			0.7	9.9	124.5	124.5
CV-24184	6/17/2026 1:31:52 PM	43.1	55.5	0.0	1.4			0.8	0.0	110.3	110.5
CV-24185	6/8/2026 3:06:30 PM	47.4	50.1	0.0	2.5			0.9	0.0	124.2	124.0
CV-24185	6/8/2026 3:09:02 PM	54.3	44.9	0.0	0.8			1.2	0.0	96.7	96.8
CV-24185	6/17/2026 12:50:10 PM	47.8	45.4	0.0	6.8			1.1	0.0	122.5	122.5
CV-24186	6/8/2026 2:54:43 PM	44.7	43.0	0.7	11.6			1.0	16.6	129.8	129.7
CV-24186	6/22/2026 12:55:19 PM	44.8	41.6	0.7	13.0			1.1	19.7	129.9	130.0
CV-24187	6/8/2026 1:08:58 PM	43.7	47.8	0.0	8.5			0.9	0.0	126.0	126.0
CV-24187	6/16/2026 8:29:13 AM	50.5	49.5	0.0	0.0			1.0	0.0	126.3	126.4
CV-24188	6/8/2026 12:56:31 PM	44.5	41.1	0.0	14.4			1.1	0.0	118.4	117.6
CV-24188	6/16/2026 8:43:18 AM	52.9	45.1	0.0	2.0			1.2	0.0	116.2	117.2
CV-24189	6/8/2026 12:53:01 PM	38.0	35.8	0.5	25.7			1.1	51.4	118.0	117.8

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24189	6/16/2026 8:39:57 AM	46.9	41.3	0.5	11.3			1.1	22.6	116.6	115.8
CV-24190	6/8/2026 1:11:34 PM	51.6	45.3	0.0	3.1			1.1	0.0	123.0	123.0
CV-24190	6/16/2026 8:31:35 AM	54.0	44.9	0.0	1.1			1.2	0.0	123.2	123.2
CV-24192	6/8/2026 1:14:16 PM	53.1	42.3	0.0	4.6			1.3	0.0	119.1	119.3
CV-24192	6/16/2026 8:33:52 AM	54.8	41.9	0.0	3.3			1.3	0.0	118.8	118.8
CV-24193	6/1/2026 10:14:52 AM	51.1	42.9	0.1	5.9			1.2	59.0	114.6	114.6
CV-24193	6/17/2026 11:31:31 AM	53.5	44.0	0.0	2.5			1.2	0.0	118.3	118.3
CV-24194	6/1/2026 3:11:56 PM	50.2	44.5	0.0	5.3			1.1	0.0	98.2	98.2
CV-24194	6/17/2026 1:13:48 PM	49.6	45.4	0.0	5.0			1.1	0.0	100.6	100.6
CV-24195	6/1/2026 3:04:18 PM	46.5	44.9	1.1	7.5			1.0	6.8	118.1	118.0
CV-24195	6/17/2026 1:18:31 PM	52.1	44.3	0.0	3.6			1.2	0.0	120.1	120.0
CV-24196	6/1/2026 2:55:48 PM	48.4	45.9	0.3	5.4			1.1	18.0	123.2	124.3
CV-24196	6/17/2026 12:42:15 PM	48.8	46.5	0.0	4.7			1.0	0.0	127.5	127.1
CV-24197	6/11/2026 8:52:25 AM	47.6	42.2	0.0	10.2			1.1	0.0	126.8	126.8
CV-24197	6/11/2026 11:07:01 AM	39.8	36.6	0.0	23.6			1.1	0.0	128.5	128.5
CV-24197	6/22/2026 12:45:39 PM	48.8	41.3	0.0	10.0			1.2	0.0	127.4	127.3
CV-24198	6/1/2026 3:50:01 PM	39.9	40.7	0.0	19.4			1.0	0.0	122.2	122.4
CV-24198	6/19/2026 2:48:23 PM	48.1	42.2	0.0	9.7			1.1	0.0	120.9	121.2
CV-24199	6/1/2026 3:48:00 PM	39.3	38.0	2.1	20.6			1.0	9.8	127.5	127.3
CV-24199	6/19/2026 2:44:55 PM	54.6	45.3	0.1	0.0			1.2	0.0	127.1	127.3
CV-24200	6/11/2026 8:43:17 AM	47.4	39.2	0.1	13.3			1.2	133.0	118.8	118.8
CV-24200	6/11/2026 10:41:55 AM	46.4	39.5	0.0	14.1			1.2	0.0	118.7	118.7
CV-24200	6/25/2026 8:22:40 AM	47.7	43.6	0.0	8.7			1.1	0.0	117.8	118.0
CV-24201	6/2/2026 9:25:14 AM										
CV-24201	6/3/2026 9:35:53 AM										
CV-24201	6/3/2026 12:17:20 PM	50.7	39.9	0.0	9.4			1.3	0.0	122.0	122.1
CV-24201	6/4/2026 7:58:40 AM										
CV-24201	6/5/2026 1:51:11 PM										
CV-24201	6/8/2026 3:58:23 PM										
CV-24201	6/8/2026 3:58:35 PM										
CV-24201	6/19/2026 12:17:46 PM										
CV-24201	6/19/2026 3:58:50 PM	50.8	43.3	0.0	5.9			1.2	0.0	121.3	121.3
CV-24201	6/25/2026 1:06:00 PM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24201	6/25/2026 1:07:09 PM										
CV-24201	6/30/2026 11:53:07 AM										
CV-24201	6/30/2026 11:53:19 AM										
CV-24202	6/1/2026 1:30:01 PM										
CV-24202	6/2/2026 9:22:52 AM										
CV-24202	6/3/2026 9:33:49 AM										
CV-24202	6/3/2026 12:11:54 PM	43.3	43.6	0.0	13.1			1.0	0.0	119.4	119.6
CV-24202	6/4/2026 8:00:54 AM										
CV-24202	6/5/2026 1:49:56 PM										
CV-24202	6/6/2026 9:00:38 AM										
CV-24202	6/8/2026 3:53:11 PM										
CV-24202	6/8/2026 3:53:58 PM										
CV-24202	6/19/2026 12:15:01 PM										
CV-24202	6/19/2026 4:05:22 PM	38.1	61.7	0.2	0.0			0.6	0.0	125.7	125.7
CV-24202	6/23/2026 2:02:54 PM										
CV-24202	6/23/2026 2:03:14 PM										
CV-24202	6/25/2026 1:11:49 PM										
CV-24202	6/25/2026 1:12:25 PM										
CV-24202	6/30/2026 11:49:07 AM										
CV-24202	6/30/2026 11:49:41 AM										
CV-24203	6/8/2026 3:43:07 PM	49.0	47.4	0.0	3.6			1.0	0.0	125.5	125.7
CV-24203	6/25/2026 8:03:43 AM	50.3	42.4	0.0	7.3			1.2	0.0	122.5	122.6
CV-24204	6/8/2026 3:40:01 PM	49.1	49.3	0.0	1.6			1.0	0.0	125.3	125.3
CV-24204	6/21/2026 3:11:11 PM	53.5	46.5	0.0	0.0			1.2	0.0	126.2	126.4
CV-24204	6/21/2026 3:14:13 PM	53.7	46.3	0.0	0.0			1.2	0.0	126.6	126.6
CV-24204	6/30/2026 2:20:08 PM	50.6	46.1	0.0	3.3			1.1	0.0	128.0	128.6
CV-24205	6/8/2026 3:36:44 PM	51.9	43.3	0.0	4.8			1.2	0.0	121.8	121.8
CV-24205	6/25/2026 8:09:37 AM	49.4	43.0	0.0	7.6			1.1	0.0	121.9	121.9
CV-24206	6/2/2026 9:26:41 AM										
CV-24206	6/3/2026 12:20:11 PM	43.2	38.1	0.0	18.7			1.1	0.0	100.0	100.9
CV-24206	6/22/2026 1:51:33 PM	48.4	46.4	0.0	5.2			1.0	0.0	94.4	94.4
CV-24206	6/26/2026 8:44:38 AM	45.5	40.4	0.0	14.1			1.1	0.0	68.3	68.8
CV-24207	6/2/2026 10:50:32 AM	45.5	54.5	0.0	0.0			0.8	0.0	133.5	133.3
CV-24207	6/2/2026 10:51:16 AM	44.8	55.2	0.0	0.0			0.8	0.0	133.0	133.0
CV-24207	6/16/2026 6:00:05 AM	44.8	54.3	0.0	0.9			0.8	0.0	127.8	127.8

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24208	6/10/2026 1:52:08 PM	49.8	50.2	0.0	0.0			1.0	0.0	130.3	130.1
CV-24209	6/1/2026 1:25:40 PM										
CV-24209	6/2/2026 9:17:37 AM										
CV-24209	6/3/2026 9:31:39 AM										
CV-24209	6/3/2026 12:05:12 PM	15.6	69.9	0.0	14.5			0.2	0.0	122.8	122.1
CV-24209	6/4/2026 8:06:47 AM										
CV-24209	6/5/2026 1:48:24 PM										
CV-24209	6/6/2026 8:57:15 AM										
CV-24209	6/8/2026 3:47:47 PM										
CV-24209	6/8/2026 3:48:01 PM										
CV-24209	6/19/2026 12:11:29 PM										
CV-24209	6/25/2026 1:20:57 PM										
CV-24209	6/25/2026 1:21:08 PM										
CV-24209	6/30/2026 11:43:59 AM										
CV-24209	6/30/2026 11:44:09 AM										
CV-24210	6/1/2026 1:12:24 PM										
CV-24210	6/2/2026 9:13:48 AM										
CV-24210	6/3/2026 8:51:28 AM	48.2	43.5	0.0	8.3			1.1	0.0	108.0	108.5
CV-24210	6/3/2026 9:26:21 AM										
CV-24210	6/4/2026 8:10:19 AM										
CV-24210	6/5/2026 1:43:34 PM										
CV-24210	6/6/2026 8:15:32 AM										
CV-24210	6/6/2026 8:17:27 AM										
CV-24210	6/8/2026 3:40:45 PM										
CV-24210	6/8/2026 3:41:19 PM										
CV-24210	6/9/2026 12:38:28 PM	44.6	43.4	0.0	12.0			1.0	0.0	105.3	105.3
CV-24210	6/19/2026 11:49:20 AM										
CV-24210	6/24/2026 11:15:44 AM										
CV-24210	6/24/2026 11:15:53 AM										
CV-24210	6/25/2026 2:20:19 PM										
CV-24210	6/25/2026 2:20:28 PM										
CV-24210	6/29/2026 2:30:23 PM										
CV-24210	6/29/2026 2:30:33 PM										
CV-24211	6/15/2026 9:54:59 AM	21.7	75.5	0.0	2.8			0.3	0.0	126.7	126.8
CV-24212	6/15/2026 9:59:21 AM	9.3	69.5	0.7	20.5			0.1	29.3	138.0	137.7
CV-24212	6/15/2026 10:00:53 AM	9.3	69.9	0.0	20.8			0.1	0.0	137.7	136.1
CV-24212	6/15/2026 10:02:09 AM	9.6	70.8	0.0	19.6			0.1	0.0	135.5	135.2
CV-24213	6/8/2026 10:52:13 AM	55.8	44.2	0.0	0.0			1.3	0.0	128.2	127.7

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24214	6/8/2026 10:30:06 AM	42.7	42.0	0.0	15.3			1.0	0.0	116.9	117.2
CV-24214	6/8/2026 11:01:06 AM	42.4	38.8	0.1	18.7			1.1	187.0	105.1	103.7
CV-24214	6/10/2026 2:15:31 PM										
CV-24214	6/10/2026 2:15:46 PM										
CV-24214	6/23/2026 11:17:53 AM										
CV-24214	6/23/2026 11:18:07 AM										
CV-24214	6/26/2026 11:12:16 AM										
CV-24214	6/26/2026 11:12:27 AM										
CV-24214	6/30/2026 11:31:15 AM										
CV-24214	6/30/2026 11:34:01 AM										
CV-24214	6/30/2026 11:34:35 AM										
CV-24215	6/24/2026 10:13:40 AM	52.3	47.7	0.0	0.0			1.1	0.0	120.1	120.1
CV-24216	6/17/2026 10:42:13 AM	38.9	37.2	0.2	23.7			1.0	118.5	105.1	98.4
CV-24217	6/8/2026 11:40:15 AM	43.2	52.7	0.2	3.9			0.8	19.5	109.1	109.1
CV-24218	6/4/2026 7:51:47 AM										
CV-24218	6/8/2026 11:18:36 AM	51.5	45.9	0.3	2.3			1.1	7.7	123.3	124.0
CV-24219	6/4/2026 8:54:21 AM	3.5	84.2	0.0	12.3			0.0	0.0	181.2	181.1
CV-24219	6/11/2026 9:18:18 AM	15.0	84.0	0.0	1.0			0.2	0.0	185.0	184.9
CV-24219	6/24/2026 8:15:38 AM	11.7	81.6	0.0	6.7			0.1	0.0	186.4	186.3
CV-24220	6/2/2026 12:24:43 PM	18.3	52.2	0.6	28.9			0.4	48.2	107.4	109.3
CV-24220	6/30/2026 1:30:24 PM	15.8	40.2	3.0	41.0			0.4	13.7	124.4	124.4
CV-24221	6/15/2026 2:27:47 PM	48.7	44.7	0.0	6.6			1.1	0.0	127.2	127.3
CV-24222	6/15/2026 2:17:31 PM	51.8	41.8	0.0	6.5			1.2	0.0	123.6	123.6
CV-24223	6/1/2026 1:47:28 PM										
CV-24223	6/15/2026 10:08:41 AM	39.5	52.7	0.0	7.8			0.7	0.0	132.1	129.8
CV-24223	6/15/2026 10:09:21 AM	39.5	53.9	0.0	6.6			0.7	0.0	129.3	129.1
CV-24224	6/2/2026 12:37:29 PM	47.3	43.1	0.0	9.6			1.1	0.0	104.7	105.0
CV-24225	6/3/2026 9:18:42 AM	52.8	41.1	0.3	5.8			1.3	19.3	111.0	111.9
CV-24226	6/15/2026 9:49:42 AM	53.6	44.2	0.0	2.2			1.2	0.0	126.4	125.6
CV-24227	6/8/2026 1:16:48 PM	50.5	42.6	0.0	6.9			1.2	0.0	117.2	117.5
CV-24231	6/10/2026 9:02:36 AM	45.7	42.3	0.0	12.0			1.1	0.0	125.4	125.4
CV-24236	6/1/2026 3:14:40 PM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]
CV-24236	6/8/2026 12:27:00 PM	37.4	35.3	0.0	27.3			1.1	0.0	106.3	106.2
CV-24237	6/1/2026 3:15:07 PM										
CV-24237	6/8/2026 12:31:50 PM	37.4	34.9	0.0	27.7			1.1	0.0	113.5	113.6
CV-24243	6/8/2026 10:28:32 AM	12.1	12.5	14.4	61.0			1.0	4.2	104.1	103.8
CV-24243	6/8/2026 10:33:20 AM	19.8	16.0	11.3	52.9			1.2	4.7	106.1	106.1
CV-24243	6/12/2026 10:56:52 AM	18.3	15.5	12.5	53.7			1.2	4.3	109.4	109.6
CV-24243	6/12/2026 10:58:41 AM	13.7	11.7	14.0	60.6			1.2	4.3	109.3	109.3
CV-24244	6/8/2026 10:22:29 AM	39.8	37.4	0.4	22.4			1.1	56.0	113.9	114.1
CV-24244	6/12/2026 10:35:49 AM	35.9	35.5	0.5	28.1			1.0	56.2	113.7	113.5
CV-24244	6/12/2026 10:44:49 AM	36.2	36.0	0.1	27.7			1.0	277.0	112.9	112.9
CV-24244	6/30/2026 1:45:09 PM	48.3	43.0	0.2	8.5			1.1	42.5	112.3	112.3
CV-24245	6/8/2026 9:34:29 AM	57.1	42.4	0.0	0.5			1.3	0.0	78.3	95.8
CV-24245	6/8/2026 9:34:50 AM	56.6	42.6	0.0	0.8			1.3	0.0	99.6	100.2
CV-24245	6/12/2026 1:14:59 PM	52.3	42.4	0.1	5.2			1.2	52.0	114.9	115.2
CV-24246	6/8/2026 9:15:06 AM	29.9	29.2	5.7	35.2			1.0	6.2	107.1	107.2
CV-24246	6/8/2026 9:30:23 AM	30.9	29.3	5.3	34.5			1.1	6.5	108.6	108.6
CV-24246	6/12/2026 1:04:39 PM	29.4	26.0	5.4	39.2			1.1	7.3	109.1	108.7
CV-24246	6/12/2026 1:06:33 PM	23.0	21.5	7.6	47.9			1.1	6.3	107.8	107.8
CV-24253	6/12/2026 1:29:16 PM	52.2	45.4	0.0	2.4			1.1	0.0	117.7	117.9
CV-25	6/1/2026 9:45:46 AM	42.8	35.1	3.4	18.7			1.2	5.5	86.1	86.7
CV-2501	6/1/2026 10:19:00 AM	50.1	44.6	0.0	5.3			1.1	0.0	121.7	121.7
CV-2502	6/1/2026 10:33:03 AM	46.6	43.1	0.0	10.3			1.1	0.0	120.3	120.4
CV-2503	6/12/2026 3:19:21 PM	41.1	40.3	0.1	18.5			1.0	185.0	126.7	126.3
CV-2503	6/19/2026 11:08:35 AM	53.6	41.1	0.0	5.4			1.3	0.0	126.6	126.9
CV-2504	6/10/2026 9:15:49 AM	51.4	42.7	0.0	5.9			1.2	0.0	128.2	128.2
CV-2505	6/3/2026 12:41:55 PM	52.2	40.2	0.0	7.6			1.3	0.0	119.0	119.1
CV-2506	6/3/2026 12:48:33 PM	49.4	39.8	0.0	10.8			1.2	0.0	121.3	121.3
CV-2507	6/3/2026 12:52:12 PM	55.8	41.3	0.0	2.9			1.4	0.0	122.7	122.7
CV-2508	6/3/2026 12:55:44 PM	55.1	40.8	0.0	4.1			1.4	0.0	120.0	120.1
CV-2509	6/3/2026 1:00:33 PM	50.6	39.0	0.0	10.4			1.3	0.0	115.5	115.6
CV-2510	6/3/2026 1:06:45 PM	56.6	39.6	0.0	3.8			1.4	0.0	114.2	114.2

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-25100D	6/4/2026 10:51:32 AM	0.0	72.6	0.0	27.4			0.0	0.0	138.1	141.3
CV-25100D	6/23/2026 10:16:56 AM	17.1	74.6	0.0	8.3			0.2	0.0	123.1	126.6
CV-25100D	6/26/2026 1:29:54 PM										
CV-25100S	6/1/2026 1:32:02 PM	17.2	73.7	0.0	9.1			0.2	0.0	170.5	170.1
CV-25100S	6/1/2026 1:45:00 PM						48200				
CV-25100S	6/1/2026 1:45:00 PM					2160					
CV-25100S	6/8/2026 1:43:02 PM	9.1	79.8	0.0	11.1			0.1	0.0	156.7	158.6
CV-25100S	6/15/2026 9:59:15 AM	20.6	73.0	0.0	6.4			0.3	0.0	178.5	179.3
CV-25100S	6/22/2026 1:20:12 PM	12.5	77.0	0.0	10.5			0.2	0.0	169.1	169.9
CV-25100S	6/26/2026 2:41:55 PM										
CV-25100S	6/29/2026 2:07:27 PM	8.5	75.7	0.0	15.8			0.1	0.0	165.4	166.0
CV-25101D	6/4/2026 10:35:59 AM	5.4	68.7	3.6	22.3			0.1	6.2	85.6	85.9
CV-25101D	6/17/2026 2:26:12 PM	4.5	60.6	4.9	30.0			0.1	6.1	90.4	90.4
CV-25101D	6/19/2026 9:33:33 AM	46.4	51.3	0.0	2.3			0.9	0.0	95.2	95.4
CV-25101S	6/4/2026 10:31:12 AM	20.5	66.5	0.0	13.0			0.3	0.0	108.1	108.2
CV-25101S	6/17/2026 2:23:12 PM	19.9	53.2	0.2	26.7			0.4	133.5	110.1	110.2
CV-25102_	6/2/2026 3:16:43 PM	17.3	71.0	0.6	11.2			0.2	19.9	91.9	91.3
CV-25102_	6/4/2026 10:57:28 AM	9.2	53.8	7.2	29.8			0.2	4.1	90.2	90.2
CV-25102_	6/23/2026 10:22:01 AM	15.0	66.8	2.2	16.0			0.2	7.3	87.1	87.7
CV-25102_	6/26/2026 2:44:49 PM										
CV-25103	6/4/2026 10:14:00 AM	27.2	44.6	0.0	28.2			0.6	0.0	113.7	113.7
CV-25103	6/4/2026 12:49:09 PM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-25103	6/17/2026 2:13:33 PM	25.5	38.5	0.0	36.0			0.7	0.0	118.7	118.8
CV-25104D	6/4/2026 8:21:00 AM	4.5	77.1	1.1	17.3			0.1	15.7	93.8	94.1
CV-25104D	6/22/2026 2:05:56 PM	4.2	71.6	2.2	22.0			0.1	10.0	90.2	90.4
CV-25104S	6/4/2026 8:24:31 AM	4.6	81.4	0.0	14.0			0.1	0.0	131.7	131.7
CV-25104S	6/4/2026 8:25:26 AM	4.7	82.3	0.0	13.0			0.1	0.0	131.5	131.8
CV-25104S	6/26/2026 9:08:11 AM	3.0	81.7	0.0	15.3			0.0	0.0	152.3	152.3
CV-25104S	6/26/2026 9:09:21 AM	3.2	85.0	0.0	11.8			0.0	0.0	152.3	79.6
CV-25105D	6/17/2026 1:52:34 PM	21.9	40.4	4.3	33.4			0.5	7.8	90.1	87.1
CV-25105S	6/2/2026 3:34:50 PM	30.9	55.9	1.8	11.4			0.6	6.3	93.8	93.8
CV-25105S	6/2/2026 3:42:33 PM	12.5	25.2	7.7	54.6			0.5	7.1	130.3	127.8
CV-25105S	6/2/2026 3:49:22 PM	13.7	26.9	7.3	52.1			0.5	7.1	130.6	130.5
CV-25105S	6/17/2026 1:58:16 PM	9.1	27.4	3.8	59.7			0.3	15.7	125.0	125.1
CV-25105S	6/22/2026 2:11:08 PM	4.1	79.3	0.2	16.4			0.1	82.0	105.0	106.1
CV-25106D	6/4/2026 8:29:59 AM	0.5	5.6	18.3	75.6			0.1	4.1	85.0	85.2
CV-25106D	6/4/2026 8:31:27 AM	0.5	4.1	18.5	76.9			0.1	4.2	85.8	
CV-25106D	6/22/2026 2:02:06 PM	10.0	63.2	2.0	24.8			0.2	12.4	95.5	95.5
CV-25106S	6/4/2026 8:34:37 AM	27.4	43.5	6.3	22.8			0.6	3.6	89.9	89.7
CV-25106S	6/4/2026 8:36:09 AM	27.7	43.9	6.1	22.3			0.6	3.7	89.9	90.4
CV-25106S	6/22/2026 1:59:24 PM	26.0	47.3	4.2	22.5			0.5	5.4	96.3	96.3
CV-25107D	6/3/2026 12:08:08 PM	4.1	80.3	0.0	15.6			0.1	0.0	91.0	91.0

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-25107D	6/19/2026 9:28:30 AM	3.4	76.2	0.6	19.8			0.0	33.0	73.9	73.9
CV-25107D	6/22/2026 8:39:22 AM	4.2	81.4	0.0	14.4			0.1	0.0	93.3	93.3
CV-25107D	6/22/2026 8:43:08 AM	3.9	74.7	1.6	19.8			0.1	12.4	93.3	93.3
CV-25107S	6/3/2026 12:02:43 PM	49.9	47.0	0.0	3.1			1.1	0.0	107.7	107.7
CV-25107S	6/22/2026 8:32:45 AM	50.3	49.7	0.0	0.0			1.0	0.0	113.4	113.9
CV-2511	6/10/2026 9:06:43 AM	50.3	42.2	0.0	7.5			1.2	0.0	127.1	127.1
CV-2512	6/10/2026 9:10:28 AM	44.3	39.3	0.0	16.4			1.1	0.0	124.9	124.5
CV-2513	6/8/2026 10:06:59 AM	46.6	40.2	0.0	13.2			1.2	0.0	119.3	119.4
CV-2514	6/10/2026 3:40:54 PM	13.0	12.0	15.8	59.2			1.1	3.7	121.9	118.6
CV-2514	6/10/2026 3:43:08 PM	53.9	44.0	0.0	2.1			1.2	0.0	119.7	119.8
CV-2515	6/1/2026 9:02:06 AM	44.2	38.5	0.0	17.3			1.1	0.0	115.2	115.2
CV-2516	6/17/2026 10:36:20 AM	57.6	41.9	0.0	0.5			1.4	0.0	127.2	127.9
CV-2517	6/1/2026 9:39:20 AM	37.3	36.4	0.0	26.3			1.0	0.0	116.4	116.7
CV-2518	6/1/2026 10:08:10 AM	47.9	39.3	0.0	12.8			1.2	0.0	110.9	110.9
CV-2519	6/15/2026 1:21:52 PM	45.7	40.5	0.0	13.8			1.1	0.0	123.2	123.2
CV-2520	6/17/2026 11:04:36 AM	45.4	49.5	0.0	5.1			0.9	0.0	142.8	141.0
CV-2520	6/17/2026 11:05:44 AM	43.2	48.8	0.0	8.0			0.9	0.0	140.9	140.8
CV-2521	6/25/2026 10:08:06 AM	31.7	53.5	0.1	14.7			0.6	147.0	104.8	107.4
CV-2522	6/15/2026 1:15:28 PM	45.7	44.9	0.0	9.4			1.0	0.0	137.0	128.9
CV-2522	6/15/2026 1:16:43 PM	46.0	43.5	0.0	10.5			1.1	0.0	128.6	128.9
CV-2523	6/15/2026 1:00:57 PM	58.4	41.3	0.0	0.3			1.4	0.0	115.6	120.9
CV-2523	6/30/2026 2:32:51 PM										
CV-2524	6/25/2026 9:48:48 AM	2.8	41.5	0.0	55.7			0.1	0.0	76.9	110.5
CV-2524	6/25/2026 9:50:06 AM	4.5	45.3	0.0	50.2			0.1	0.0	113.8	114.7
CV-2525	6/15/2026 12:52:47 PM	45.2	38.5	0.0	16.3			1.2	0.0	117.0	117.0
CV-2526	6/15/2026 12:48:53 PM	53.8	41.6	0.0	4.6			1.3	0.0	121.2	121.7

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2527	6/22/2026 2:39:55 PM	43.9	47.1	0.0	9.0			0.9	0.0	130.5	131.0
CV-2528	6/15/2026 10:47:39 AM	46.6	38.2	0.0	15.2			1.2	0.0	110.5	110.6
CV-2528	6/30/2026 9:56:37 AM										
CV-2529	6/1/2026 10:23:26 AM										
CV-2529	6/2/2026 9:42:05 AM										
CV-2529	6/3/2026 9:44:04 AM										
CV-2529	6/4/2026 7:16:01 AM										
CV-2529	6/5/2026 11:28:41 AM										
CV-2529	6/6/2026 9:54:57 AM										
CV-2529	6/8/2026 3:03:59 PM										
CV-2529	6/8/2026 3:04:24 PM										
CV-2529	6/10/2026 2:08:49 PM	1.4	0.7	20.3	77.6			2.0	3.8	100.6	99.5
CV-2529	6/10/2026 2:10:02 PM	1.2	0.5	20.4	77.9			2.4	3.8	100.3	100.3
CV-2529	6/16/2026 11:08:28 AM										
CV-2529	6/16/2026 11:09:00 AM										
CV-2529	6/16/2026 11:09:14 AM										
CV-2529	6/16/2026 11:15:07 AM										
CV-2529	6/16/2026 11:15:57 AM										
CV-2529	6/16/2026 11:24:10 AM										
CV-2529	6/16/2026 11:24:20 AM										
CV-2529	6/24/2026 12:57:34 PM										
CV-2529	6/24/2026 12:57:52 PM										
CV-2529	6/25/2026 11:45:10 AM										
CV-2529	6/25/2026 11:45:18 AM										
CV-2529	6/25/2026 2:48:45 PM										
CV-2529	6/25/2026 3:48:38 PM	44.5	33.8	4.3	17.4			1.3	4.0	102.4	102.5
CV-2529	6/29/2026 1:17:01 PM										
CV-2530	6/10/2026 2:29:19 PM	46.2	52.5	0.0	1.3			0.9	0.0	127.3	127.4
CV-2531	6/10/2026 2:33:42 PM	33.9	58.6	0.0	7.5			0.6	0.0	118.6	119.5
CV-2532	6/1/2026 10:20:21 AM										
CV-2532	6/3/2026 9:46:27 AM										
CV-2532	6/4/2026 7:12:04 AM										
CV-2532	6/4/2026 7:13:21 AM										
CV-2532	6/5/2026 11:31:43 AM										
CV-2532	6/5/2026 11:34:11 AM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2532	6/10/2026 2:36:45 PM	56.0	43.8	0.2	0.0			1.3	0.0	106.3	106.8
CV-2533	6/1/2026 10:18:28 AM										
CV-2533	6/3/2026 9:48:15 AM										
CV-2533	6/4/2026 7:10:54 AM										
CV-2533	6/5/2026 11:35:17 AM										
CV-2533	6/10/2026 1:57:41 PM										
CV-2533	6/10/2026 1:57:54 PM										
CV-2533	6/10/2026 2:39:59 PM	55.8	43.9	0.3	0.0			1.3	0.0	130.3	130.3
CV-2533	6/16/2026 11:22:47 AM										
CV-2533	6/16/2026 11:22:56 AM										
CV-2533	6/25/2026 11:36:10 AM										
CV-2533	6/25/2026 11:36:22 AM										
CV-2533	6/25/2026 3:53:17 PM										
CV-2533	6/29/2026 1:23:58 PM										
CV-2533	6/29/2026 1:24:21 PM										
CV-2534	6/10/2026 1:02:08 PM	56.6	42.1	0.0	1.3			1.3	0.0	122.2	122.2
CV-2534	6/10/2026 2:43:52 PM	56.4	43.5	0.1	0.0			1.3	0.0	121.9	121.9
CV-2534	6/30/2026 2:28:25 PM	53.6	43.9	0.0	2.5			1.2	0.0	107.7	109.2
CV-2535	6/3/2026 12:25:06 PM	41.5	36.3	0.0	22.2			1.1	0.0	112.5	112.5
CV-2536	6/10/2026 3:50:56 PM	51.6	48.4	0.0	0.0			1.1	0.0	104.3	104.5
CV-2536	6/30/2026 2:11:01 PM										
CV-2537	6/3/2026 12:36:58 PM	55.8	37.8	0.0	6.4			1.5	0.0	106.7	108.5
CV-2537	6/30/2026 2:13:52 PM	45.7	36.2	0.0	18.1			1.3	0.0	113.5	100.3
CV-2538	6/3/2026 12:28:52 PM	51.7	40.0	0.0	8.3			1.3	0.0	123.7	123.6
CV-2538	6/30/2026 1:21:17 PM										
CV-2539	6/1/2026 10:50:13 AM	35.5	41.6	0.0	22.9			0.9	0.0	121.0	121.1
CV-2539	6/17/2026 11:59:27 AM	40.8	41.3	0.0	17.9			1.0	0.0	124.2	118.6
CV-2540	6/15/2026 8:30:48 AM	2.2	84.2	0.0	13.6			0.0	0.0	127.7	127.5
CV-2540	6/16/2026 10:23:27 AM	3.8	84.1	0.0	12.1			0.0	0.0	127.7	127.6
CV-2540	6/25/2026 2:27:35 PM	2.6	81.9	0.3	15.2			0.0	50.7	138.5	138.8

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2540	6/25/2026 2:29:35 PM	2.6	83.1	0.2	14.1			0.0	70.5	139.1	139.1
CV-2541	6/3/2026 9:02:39 AM	31.0	47.8	0.0	21.2			0.6	0.0	131.5	131.9
CV-2541	6/16/2026 9:33:45 AM	26.6	51.3	0.0	22.1			0.5	0.0	132.3	132.0
CV-2541	6/16/2026 9:34:05 AM	26.7	51.3	0.0	22.0			0.5	0.0	131.8	131.7
CV-2542	6/3/2026 2:04:32 PM	49.4	50.6	0.0	0.0			1.0	0.0	90.6	90.6
CV-2542	6/16/2026 6:19:26 AM	48.9	49.2	0.0	1.9			1.0	0.0	114.8	89.2
CV-2543-PLF	6/3/2026 2:32:39 PM	1.9	83.6	0.0	14.5			0.0	0.0	101.2	102.7
CV-2543-PLF	6/3/2026 2:33:15 PM	2.1	85.1	0.0	12.8			0.0	0.0	102.7	102.6
CV-2543-PLF	6/22/2026 10:17:04 AM	29.2	64.4	0.5	5.9			0.5	11.8	116.9	117.4
CV-2543-PLF	6/30/2026 11:16:12 AM										
CV-2544	6/11/2026 9:06:29 AM	9.2	81.7	0.0	9.1			0.1	0.0	149.8	149.8
CV-2544	6/11/2026 9:09:46 AM	7.8	83.5	0.0	8.7			0.1	0.0	147.9	147.6
CV-2544	6/15/2026 2:05:00 PM	7.9	76.0	0.0	16.1			0.1	0.0	95.3	95.3
CV-2544	6/15/2026 2:06:46 PM	10.0	73.5	0.0	16.5			0.1	0.0	96.3	96.3
CV-2544	6/22/2026 9:59:02 AM	15.3	79.0	0.0	5.7			0.2	0.0	138.0	138.0
CV-2544	6/22/2026 9:59:57 AM	14.6	82.7	0.0	2.7			0.2	0.0	138.0	138.0
CV-2545	6/4/2026 8:37:41 AM	35.1	57.5	0.0	7.4			0.6	0.0	129.4	128.2
CV-2545	6/16/2026 2:36:50 PM										
CV-2545	6/22/2026 9:10:21 AM	32.8	61.0	0.5	5.7			0.5	11.4	127.1	127.5
CV-2546	6/4/2026 8:42:51 AM	17.2	70.6	0.0	12.2			0.2	0.0	131.1	129.6
CV-2546	6/4/2026 8:44:06 AM	17.4	71.3	0.0	11.3			0.2	0.0	129.0	129.1
CV-2546	6/16/2026 1:12:07 PM	29.7	60.8	0.0	9.5			0.5	0.0	128.0	131.7
CV-2546	6/16/2026 1:12:57 PM	27.9	63.7	0.0	8.4			0.4	0.0	131.9	132.2
CV-2546	6/16/2026 1:13:54 PM	25.6	66.5	0.0	7.9			0.4	0.0	131.8	131.6

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2546	6/18/2026 8:47:47 AM										
CV-2547	6/4/2026 9:30:40 AM	48.2	48.8	0.0	3.0			1.0	0.0	104.4	104.7
CV-2547	6/16/2026 5:51:22 AM	47.5	49.7	0.0	2.8			1.0	0.0	93.1	95.7
CV-2547	6/16/2026 2:07:20 PM										
CV-2547	6/24/2026 8:12:57 AM	49.8	49.0	0.0	1.2			1.0	0.0	109.9	110.0
CV-2548	6/2/2026 9:12:35 AM	38.9	61.1	0.0	0.0			0.6	0.0	128.3	118.9
CV-2548	6/2/2026 9:15:21 AM	26.7	73.3	0.0	0.0			0.4	0.0	121.6	121.6
CV-2548	6/16/2026 12:50:07 PM	7.6	75.3	0.0	17.1			0.1	0.0	125.5	125.2
CV-2548	6/26/2026 12:39:55 PM	6.2	83.1	0.0	10.7			0.1	0.0	128.3	128.2
CV-2549	6/2/2026 8:57:57 AM	58.8	41.2	0.0	0.0			1.4	0.0	111.0	113.0
CV-2549	6/2/2026 9:04:56 AM	61.3	38.7	0.0	0.0			1.6	0.0	113.5	113.5
CV-2549	6/9/2026 12:21:15 PM	47.2	44.5	0.0	8.3			1.1	0.0	114.2	114.3
CV-2549	6/16/2026 12:47:49 PM	49.0	40.8	0.0	10.2			1.2	0.0	114.8	114.7
CV-2550	6/1/2026 8:25:41 AM										
CV-2550	6/4/2026 9:26:24 AM	2.6	82.0	0.0	15.4			0.0	0.0	172.0	172.2
CV-2550	6/10/2026 2:34:19 PM	23.1	76.9	0.0	0.0			0.3	0.0	176.4	176.5
CV-2550	6/24/2026 8:52:00 AM	13.6	74.4	0.0	12.0			0.2	0.0	179.5	180.0
CV-2550	6/30/2026 2:56:33 PM	8.0	78.4	0.1	13.5			0.1	135.0	171.6	171.4
CV-2551	6/1/2026 3:18:11 PM										
CV-2551	6/2/2026 8:54:03 AM										
CV-2551	6/3/2026 9:17:33 AM	17.5	71.8	0.0	10.7			0.2	0.0	164.8	165.2
CV-2551	6/3/2026 9:19:09 AM	4.8	80.7	0.0	14.5			0.1	0.0	165.2	165.6
CV-2551	6/3/2026 1:49:46 PM	21.0	79.0	0.0	0.0			0.3	0.0	150.4	151.6
CV-2551	6/3/2026 1:50:17 PM	20.6	79.4	0.0	0.0			0.3	0.0	150.8	150.9
CV-2551	6/3/2026 2:00:00 PM						78000				
CV-2551	6/6/2026 8:46:46 AM										
CV-2551	6/10/2026 12:12:00 PM										
CV-2551	6/10/2026 12:15:52 PM										
CV-2551	6/11/2026 9:12:16 AM	34.1	65.9	0.0	0.0			0.5	0.0	152.8	152.3

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2551	6/19/2026 9:39:01 AM	27.9	62.9	0.0	9.2			0.4	0.0	148.4	149.3
CV-2551	6/24/2026 8:07:19 AM	9.2	82.6	0.0	8.2			0.1	0.0	161.3	162.4
CV-2551	6/24/2026 8:08:01 AM	8.8	85.0	0.0	6.2			0.1	0.0	162.9	162.9
CV-2551	6/25/2026 2:42:00 PM										
CV-2551	6/25/2026 2:42:47 PM										
CV-2551	6/30/2026 2:36:17 PM										
CV-2551	6/30/2026 2:36:35 PM										
CV-2552	6/8/2026 2:06:27 PM	30.2	64.3	0.0	5.5			0.5	0.0	87.3	82.8
CV-2552	6/19/2026 9:47:25 AM	25.2	65.3	0.2	9.3			0.4	46.5	143.4	143.9
CV-2552	6/25/2026 7:28:45 AM										
CV-2553	6/3/2026 2:22:58 PM	52.4	44.1	0.0	3.5			1.2	0.0	98.9	99.2
CV-2553	6/16/2026 10:11:11 AM	53.7	44.1	0.0	2.2			1.2	0.0	82.2	83.0
CV-2553	6/17/2026 7:56:00 AM										
CV-2553	6/19/2026 11:27:02 AM	42.5	48.2	1.0	8.3			0.9	8.3	108.2	106.9
CV-2554	6/3/2026 1:14:29 PM	49.4	50.6	0.0	0.0			1.0	0.0	148.1	148.1
CV-2554	6/3/2026 1:15:00 PM						80500				
CV-2554	6/9/2026 2:23:37 PM	42.4	57.6	0.0	0.0			0.7	0.0	146.6	146.5
CV-2554	6/16/2026 2:24:38 PM	44.4	55.3	0.3	0.0			0.8	0.0	151.5	151.9
CV-2554	6/24/2026 9:50:14 AM	47.7	52.2	0.0	0.1			0.9	0.0	153.2	151.8
CV-2555	6/10/2026 10:09:34 AM	0.7	3.7	19.9	75.7			0.2	3.8	94.8	96.7
CV-2555	6/22/2026 1:53:55 PM	1.8	5.7	18.9	73.6			0.3	3.9	89.0	89.1
CV-2556	6/1/2026 3:24:57 PM										
CV-2556	6/3/2026 1:25:38 PM	21.8	77.3	0.0	0.9			0.3	0.0	179.1	179.3
CV-2556	6/3/2026 1:35:00 PM						110750				

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2556	6/10/2026 2:21:23 PM	20.2	79.8	0.0	0.0			0.3	0.0	179.5	179.5
CV-2556	6/24/2026 9:12:42 AM	10.1	77.6	0.0	12.3			0.1	0.0	184.5	184.5
CV-2556	6/30/2026 2:15:00 PM	6.9	81.8	0.0	11.3			0.1	0.0	182.5	182.5
CV-2557	6/4/2026 9:59:27 AM	25.2	50.6	0.0	24.2			0.5	0.0	128.4	128.6
CV-2557	6/4/2026 12:47:58 PM										
CV-2557	6/17/2026 2:02:18 PM	19.3	46.5	0.0	34.2			0.4	0.0	130.5	130.8
CV-2557	6/25/2026 2:51:14 PM										
CV-2557	6/25/2026 2:52:24 PM										
CV-2558	6/4/2026 9:08:41 AM	3.9	79.3	0.2	16.6			0.0	83.0	184.5	184.8
CV-2558	6/4/2026 9:11:08 AM	3.9	80.4	0.0	15.7			0.0	0.0	183.4	183.4
CV-2558	6/6/2026 8:51:55 AM										
CV-2558	6/11/2026 9:40:44 AM	18.5	78.8	0.0	2.7			0.2	0.0	193.9	194.2
CV-2558	6/24/2026 8:24:46 AM	43.3	55.1	0.0	1.6			0.8	0.0	184.4	184.8
CV-2559	6/8/2026 11:29:55 AM	36.6	60.7	0.1	2.6			0.6	26.0	123.2	121.9
CV-2559	6/26/2026 9:21:49 AM	7.2	86.3	0.0	6.5			0.1	0.0	129.9	130.6
CV-2559	6/26/2026 9:22:21 AM	7.3	86.3	0.0	6.4			0.1	0.0	131.4	131.6
CV-2560	6/4/2026 10:17:20 AM	17.2	38.4	0.7	43.7			0.4	62.4	116.8	117.3
CV-2560	6/4/2026 12:55:13 PM										
CV-2560	6/17/2026 2:19:08 PM	15.3	35.9	1.1	47.7			0.4	43.4	113.0	113.1
CV-2561	6/1/2026 10:07:37 AM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2561	6/4/2026 10:27:07 AM	10.6	40.1	0.7	48.6			0.3	69.4	127.2	127.4
CV-2561	6/25/2026 9:03:33 AM	13.8	32.0	1.5	52.7			0.4	35.1	127.6	127.5
CV-2561	6/25/2026 9:59:59 AM	13.5	32.7	1.4	52.4			0.4	37.4	125.0	125.0
CV-2562	6/8/2026 11:24:32 AM	36.8	59.8	0.2	3.2			0.6	16.0	115.6	113.9
CV-2563	6/9/2026 2:01:53 PM	36.6	55.2	0.0	8.2			0.7	0.0	125.3	125.3
CV-2564	6/16/2026 9:20:39 AM	39.9	54.5	0.0	5.6			0.7	0.0	120.6	122.1
CV-2565	6/1/2026 10:58:19 AM	29.4	35.9	0.0	34.7			0.8	0.0	112.3	112.9
CV-2565	6/17/2026 12:11:54 PM	37.0	38.7	0.0	24.3			1.0	0.0	118.0	115.4
CV-2566	6/1/2026 11:25:15 AM	46.3	48.4	0.0	5.3			1.0	0.0	105.9	105.5
CV-2566	6/17/2026 12:05:33 PM	56.1	43.9	0.0	0.0			1.3	0.0	111.4	115.1
CV-2567	6/1/2026 10:36:31 AM										
CV-2567	6/10/2026 9:37:59 AM	52.0	46.2	0.0	1.8			1.1	0.0	108.8	109.0
CV-2567	6/17/2026 1:15:59 PM	50.1	45.3	0.0	4.6			1.1	0.0	108.6	110.2
CV-2568	6/1/2026 1:04:25 PM	38.7	46.1	0.0	15.2			0.8	0.0	105.7	107.5
CV-2568	6/1/2026 1:06:59 PM	39.4	48.5	0.0	12.1			0.8	0.0	106.5	106.4
CV-2568	6/17/2026 12:38:03 PM	46.7	40.6	0.0	12.7			1.2	0.0	106.6	106.5
CV-2569	6/1/2026 1:00:40 PM	43.8	50.6	0.0	5.6			0.9	0.0	105.4	105.5
CV-2569	6/17/2026 12:39:56 PM	47.1	45.6	0.0	7.3			1.0	0.0	110.7	111.2
CV-2570	6/1/2026 12:56:09 PM	48.4	47.0	0.0	4.6			1.0	0.0	109.2	109.1
CV-2570	6/17/2026 12:44:47 PM	50.0	45.2	0.0	4.8			1.1	0.0	111.9	112.1
CV-2571	6/10/2026 2:50:35 PM	56.1	40.0	0.1	3.8			1.4	38.0	97.2	97.0
CV-2571	6/12/2026 2:05:39 PM	57.9	39.7	0.0	2.4			1.5	0.0	97.5	97.6
CV-2572	6/10/2026 3:23:03 PM	48.7	40.1	0.0	11.2			1.2	0.0	121.3	121.4
CV-2572	6/30/2026 9:25:51 AM										
CV-48R	6/9/2026 1:59:40 PM	54.3	42.8	0.0	2.9			1.3	0.0	122.6	122.5
CV-48R	6/19/2026 1:26:30 PM	52.5	45.0	0.0	2.5			1.2	0.0	120.9	121.0
CV-52D	6/17/2026 10:56:39 AM	22.8	30.9	9.6	36.7			0.7	3.8	91.4	89.2
CV-52D	6/17/2026 10:58:21 AM	10.7	13.0	15.9	60.4			0.8	3.8	88.9	88.9
CV-55R	6/22/2026 2:49:14 PM	35.9	47.6	0.0	16.5			0.8	0.0	152.3	153.0
CV-55R	6/22/2026 2:51:17 PM	35.7	47.3	0.0	17.0			0.8	0.0	153.1	153.0

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-56D	6/3/2026 9:46:56 AM	16.9	12.7	14.3	56.1			1.3	3.9	82.3	82.3
CV-56D	6/3/2026 9:48:21 AM	18.8	14.4	13.7	53.1			1.3	3.9	82.2	82.2
CV-56D	6/4/2026 11:45:39 AM	21.4	23.8	10.6	44.2			0.9	4.2	90.3	90.2
CV-56D	6/4/2026 11:48:11 AM	20.8	22.3	10.9	46.0			0.9	4.2	90.3	90.5
CV-56S	6/3/2026 9:50:43 AM	4.6	36.6	4.8	54.0			0.1	11.3	76.7	77.3
CV-56S	6/4/2026 11:53:51 AM	39.3	42.1	0.5	18.1			0.9	36.2	96.2	94.0
CV-57R	6/2/2026 12:09:58 PM	55.3	40.9	0.0	3.8			1.4	0.0	96.6	98.6
CV-79R	6/2/2026 12:42:00 PM	51.2	45.8	0.0	3.0			1.1	0.0	124.4	124.7
CV-94	6/2/2026 11:52:13 AM	36.6	35.9	0.0	27.5			1.0	0.0	119.7	119.8
CV-95	6/2/2026 12:07:10 PM	44.4	37.4	0.0	18.2			1.2	0.0	92.4	92.6
CV-99	6/4/2026 7:30:00 AM						1500				
CV-99	6/4/2026 7:30:00 AM					0					
CV-99	6/5/2026 10:07:36 AM	3.5	7.1	18.4	71.0			0.5	3.9	101.4	102.5
CV-99	6/5/2026 10:08:38 AM	3.6	8.0	18.0	70.4			0.5	3.9	103.2	103.5
D-02	6/23/2026 1:53:57 PM	52.1	39.8	1.4	6.7			1.3	4.8	96.9	
D-02	6/23/2026 2:03:28 PM	57.2	41.4	0.0	1.4			1.4	0.0	96.6	96.6
D-03	6/26/2026 1:32:24 PM	59.2	35.8	0.2	4.8			1.7	24.0	90.4	91.0
D-04	6/10/2026 1:27:08 PM	59.8	39.2	0.0	1.0			1.5	0.0	100.6	100.9
D-09	6/10/2026 3:15:14 PM	56.9	40.8	0.1	2.2			1.4	22.0	114.6	114.8
D-10	6/10/2026 3:05:32 PM	32.0	20.2	8.6	39.2			1.6	4.6	113.5	113.5
D-10	6/10/2026 3:09:00 PM	21.0	13.1	13.3	52.6			1.6	4.0	112.5	112.4
FP-001	6/4/2026 1:35:55 PM	5.3	19.6	5.8	69.3			0.3	11.9	90.4	90.2
FP-002	6/4/2026 2:04:37 PM	42.4	47.7	0.7	9.2			0.9	13.1	87.9	87.9
FP-003	6/4/2026 2:07:37 PM	31.3	38.3	5.4	25.0			0.8	4.6	90.2	90.3
FP-005	6/5/2026 1:33:01 PM	5.5	23.5	11.6	59.4			0.2	5.1	95.3	95.3
FP-006	6/5/2026 1:48:45 PM	14.4	76.1	0.0	9.5			0.2	0.0	91.1	92.6
FP-008	6/5/2026 2:33:38 PM	16.7	73.2	1.4	8.7			0.2	6.2	97.3	98.7
FP-009	6/2/2026 8:40:09 AM	11.8	74.6	0.5	13.1			0.2	26.2	94.9	95.4

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
FP-010	6/2/2026 8:28:42 AM	15.6	78.0	0.1	6.3			0.2	63.0	106.4	106.5
FP-011	6/2/2026 8:25:31 AM	25.0	58.6	3.2	13.2			0.4	4.1	73.2	73.1
FP-012	6/1/2026 9:55:47 AM	1.6	3.1	20.2	75.1			0.5	3.7	86.5	86.9
FP-013	6/1/2026 1:37:28 PM	13.3	16.4	10.5	59.8			0.8	5.7	92.6	92.8
FP-014	6/2/2026 8:35:12 AM	0.6	25.7	15.0	58.7			0.0	3.9	93.5	94.3
FP-014	6/5/2026 2:19:15 PM	14.2	67.3	2.6	15.9			0.2	6.1	99.8	99.9
FP-015	6/5/2026 2:05:04 PM	0.1	4.2	21.4	74.3			0.0	3.5	95.4	96.7
FP-016	6/5/2026 1:58:04 PM	18.6	61.7	3.8	15.9			0.3	4.2	99.0	99.4
FP-017	6/10/2026 9:55:02 AM	11.5	6.6	15.3	66.6			1.7	4.4	90.4	90.5
FP-018	6/10/2026 9:47:19 AM	38.2	28.9	4.0	28.9			1.3	7.2	85.7	86.1
FP-019	6/2/2026 9:42:15 AM	55.6	44.4	0.0	0.0			1.3	0.0	76.6	76.8
FP-020	6/10/2026 11:16:39 AM	43.3	49.2	1.8	5.7			0.9	3.2	93.6	94.1
FP-021	6/2/2026 9:52:46 AM	17.9	44.9	5.1	32.1			0.4	6.3	97.9	97.8
FP-022	6/10/2026 11:08:45 AM	26.8	52.6	3.8	16.8			0.5	4.4	94.9	96.5
FP-023	6/22/2026 8:10:36 AM	33.7	64.0	0.0	2.3			0.5	0.0	82.7	82.9
FP-024	6/10/2026 10:40:56 AM	18.2	45.6	6.8	29.4			0.4	4.3	93.2	93.7
FP-025	6/4/2026 9:05:18 AM	21.1	43.7	3.2	32.0			0.5	10.0	84.4	84.9
FP-026	6/4/2026 9:14:18 AM	15.6	38.9	7.8	37.7			0.4	4.8	84.4	81.9
FP-027	6/8/2026 10:54:42 AM	12.7	25.8	10.3	51.2			0.5	5.0	93.7	93.7
FP-028	6/8/2026 10:49:31 AM	0.5	1.8	20.2	77.4			0.3	3.8	94.8	95.4
FP-029	6/10/2026 9:50:32 AM	50.7	36.8	2.6	9.9			1.4	3.8	99.5	99.9
FP-030	6/2/2026 9:25:15 AM	42.3	39.2	3.2	15.3			1.1	4.8	78.2	78.2
FP-031	6/2/2026 9:20:31 AM	30.6	53.1	1.8	14.5			0.6	8.1	75.8	75.5
FP-032	6/2/2026 9:00:20 AM	12.8	40.6	6.8	39.8			0.3	5.9	68.3	71.2
FP-033	6/2/2026 8:55:46 AM	0.2	5.8	20.1	73.9			0.0	3.7	65.5	65.7
FP-034	6/22/2026 8:03:52 AM	9.1	20.1	9.7	61.1			0.5	6.3	88.6	88.7
FP-035	6/1/2026 2:23:38 PM	32.5	54.8	2.3	10.4			0.6	4.5	79.7	80.5
FP-036	6/1/2026 2:26:56 PM	24.3	43.4	3.5	28.8			0.6	8.2	83.8	83.9
FP-037	6/1/2026 2:33:31 PM	0.1	3.1	20.9	75.9			0.0	3.6	87.4	87.4

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
FP-038	6/3/2026 9:29:51 AM	23.7	24.6	9.1	42.6			1.0	4.7	75.7	76.4
FP-038	6/17/2026 9:30:17 AM	18.7	67.4	0.5	13.4			0.3	26.8	90.5	90.5
FP-039	6/3/2026 9:26:27 AM	48.8	42.1	0.8	8.3			1.2	10.4	78.0	78.2
FP-040	6/17/2026 9:23:16 AM	19.6	72.6	0.0	7.8			0.3	0.0	90.5	90.5
FP-041	6/11/2026 10:59:42 AM	17.5	24.2	5.6	52.7			0.7	9.4	91.1	91.1
FP-041	6/11/2026 11:01:38 AM	18.1	24.3	5.5	52.1			0.7	9.5	91.9	92.1
FP-042	6/8/2026 1:38:09 PM	14.1	42.8	6.4	36.7			0.3	5.7	94.0	94.3
FP-043	6/17/2026 9:47:23 AM	28.0	28.6	7.5	35.9			1.0	4.8	90.5	90.3
FP-044	6/17/2026 9:43:00 AM	8.8	19.5	14.9	56.8			0.5	3.8	89.6	89.7
FP-045	6/3/2026 9:07:49 AM	2.8	4.2	18.1	74.9			0.7	4.1	99.2	99.4
FP-046	6/23/2026 10:33:42 AM	23.8	70.7	1.6	3.9			0.3	2.4	104.9	104.9
FP-047	6/5/2026 1:13:13 PM	27.5	42.5	3.6	26.4			0.6	7.3	96.7	96.7
FP-050	6/8/2026 2:03:54 PM	14.7	32.3	7.6	45.4			0.5	6.0	95.7	95.2
FP-051	6/8/2026 2:16:12 PM	32.2	44.3	3.1	20.4			0.7	6.6	95.8	95.0
FP-052	6/3/2026 2:16:47 PM	18.4	20.9	7.3	53.4			0.9	7.3	92.4	92.5
FP-053	6/3/2026 2:13:47 PM	27.8	25.9	7.6	38.7			1.1	5.1	106.6	108.0
FP-054	6/8/2026 2:29:07 PM	28.3	45.8	3.7	22.2			0.6	6.0	94.0	93.9
FP-055	6/3/2026 2:41:46 PM	44.2	37.8	0.7	17.3			1.2	24.7	105.4	105.8
FP-056	6/3/2026 10:06:38 AM	31.6	31.7	2.9	33.8			1.0	11.7	89.3	89.5
FP-056	6/16/2026 9:41:00 AM	40.9	34.7	1.7	22.7			1.2	13.4	92.5	93.0
FP-057	6/3/2026 9:08:41 AM	40.9	37.2	3.0	18.9			1.1	6.3	83.3	83.3
FP-058	6/3/2026 9:22:51 AM	35.7	39.3	2.5	22.5			0.9	9.0	82.9	82.9
FP-059	6/8/2026 12:07:12 PM	47.1	35.0	2.2	15.7			1.3	7.1	92.2	92.3
FP-060	6/26/2026 1:06:52 PM	6.8	14.4	7.0	71.8			0.5	10.3	100.0	100.1
FP-061	6/5/2026 2:08:36 PM	6.1	73.1	1.6	19.2			0.1	12.0	148.0	147.7
H-01 (EXP-0	6/12/2026 7:44:07 AM	14.5	46.7	0.0	38.8			0.3	0.0	85.8	86.5
H-01 (EXP-0	6/22/2026 8:10:49 AM	13.4	45.7	0.0	40.9			0.3	0.0	75.0	75.1
H-02 (EXP-0	6/1/2026 11:41:57 AM	11.9	48.6	0.0	39.5			0.2	0.0	116.5	116.5
H-02 (EXP-0	6/22/2026 8:05:43 AM	13.0	47.7	0.0	39.3			0.3	0.0	103.5	103.5
H-03 (EXP-0	6/1/2026 11:45:13 AM	50.5	46.0	0.0	3.5			1.1	0.0	121.8	121.9
H-03 (EXP-0	6/22/2026 7:55:26 AM	49.3	47.5	0.0	3.2			1.0	0.0	118.3	118.3
H-04 (EXP-0	6/1/2026 11:51:21 AM	2.0	55.3	0.0	42.7			0.0	0.0	133.9	133.4
H-04 (EXP-0	6/1/2026 11:52:14 AM	1.9	56.0	0.0	42.1			0.0	0.0	133.4	133.4
H-04 (EXP-0	6/22/2026 7:48:41 AM	1.7	51.7	0.0	46.6			0.0	0.0	133.1	133.2

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
H-04 (EXP-0	6/22/2026 7:51:00 AM	1.6	51.5	0.0	46.9			0.0	0.0	133.3	133.6
H-04 (EXP-0	6/22/2026 7:52:34 AM	1.6	52.1	0.0	46.3			0.0	0.0	133.7	133.7
H-08 (EXP-0	6/8/2026 1:06:17 PM	49.8	45.6	0.0	4.6			1.1	0.0	123.1	123.2
H-08 (EXP-0	6/17/2026 9:51:09 AM	51.2	44.4	0.0	4.4			1.2	0.0	123.1	123.7
H-08 (EXP-0	6/17/2026 9:51:47 AM	50.9	44.1	0.0	5.0			1.2	0.0	123.8	123.8
H-10 (EXP-1	6/8/2026 12:48:24 PM	10.0	66.9	0.0	23.1			0.1	0.0	131.2	131.0
H-10 (EXP-1	6/8/2026 12:51:23 PM	9.6	66.5	0.0	23.9			0.1	0.0	131.5	131.6
H-10 (EXP-1	6/17/2026 9:56:40 AM	11.8	64.1	0.0	24.1			0.2	0.0	129.6	129.5
H-10 (EXP-1	6/17/2026 9:57:40 AM	11.2	64.8	0.0	24.0			0.2	0.0	129.6	129.6
H-101W	6/8/2026 12:22:40 PM	57.6	39.1	0.0	3.3			1.5	0.0	85.9	88.3
H-102A	6/8/2026 12:13:39 PM	57.5	34.4	0.5	7.6			1.7	15.2	82.8	81.6
H-102A	6/19/2026 10:48:54 AM	29.9	19.6	12.8	37.7			1.5	2.9	69.6	69.0
H-1401W	6/8/2026 12:09:07 PM	41.3	26.7	6.0	26.0			1.5	4.3	91.8	91.7
H-1401W	6/8/2026 12:11:06 PM	43.7	29.2	3.7	23.4			1.5	6.3	92.3	92.7
H-1404C	6/15/2026 1:54:09 PM	24.2	28.9	0.4	46.5			0.8	116.3	129.8	129.8
H-1404C	6/26/2026 12:54:36 PM	21.1	27.8	0.3	50.8			0.8	169.3	133.7	127.9
H-1404C	6/26/2026 12:55:41 PM	22.0	27.5	0.3	50.2			0.8	167.3	123.1	122.8
H-1405C	6/2/2026 9:16:38 AM	12.3	28.4	1.4	57.9			0.4	41.4	107.9	107.6
H-1405C	6/16/2026 8:12:58 AM	38.1	51.4	0.8	9.7			0.7	12.1	77.8	78.7
H-1406W	6/10/2026 8:42:28 AM	45.6	51.4	0.1	2.9			0.9	29.0	85.9	86.5
H-1406W	6/17/2026 8:18:32 AM	44.1	42.8	1.4	11.7			1.0	8.4	90.5	90.5
H-1408CR	6/12/2026 3:10:27 PM	11.4	23.0	1.1	64.5			0.5	58.6	139.8	139.9
H-1408CR	6/12/2026 3:12:01 PM	10.8	22.5	1.2	65.5			0.5	54.6	141.5	141.6
H-1408E	6/2/2026 2:36:46 PM	15.6	22.4	2.9	59.1			0.7	20.4	115.2	115.5
H-1408E	6/16/2026 6:05:06 AM	30.7	32.6	1.2	35.5			0.9	29.6	104.7	104.4
H-1408W	6/8/2026 12:44:22 PM	9.7	12.6	13.4	64.3			0.8	4.8	107.7	110.2
H-1408W	6/8/2026 12:50:22 PM	13.7	13.6	11.9	60.8			1.0	5.1	111.3	110.8
H-1409N	6/8/2026 3:03:33 PM	40.4	35.1	0.0	24.5			1.2	0.0	116.7	116.3
H-1409N	6/17/2026 12:54:53 PM	38.0	33.7	0.0	28.3			1.1	0.0	118.5	118.2
H-1410S	6/3/2026 12:33:58 PM	53.4	38.2	0.9	7.5			1.4	8.3	98.1	98.3
H-1563N	6/3/2026 9:21:39 AM	38.7	41.0	0.0	20.3			0.9	0.0	113.8	115.3
H-1563N	6/22/2026 11:47:58 AM	54.0	42.6	0.0	3.4			1.3	0.0	117.3	118.0

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
H-1563S	6/2/2026 9:21:26 AM	22.1	32.2	0.0	45.7			0.7	0.0	83.4	83.5
H-1563S	6/16/2026 8:15:23 AM	20.8	29.6	0.0	49.6			0.7	0.0	88.7	88.4
H-1565E	6/2/2026 2:42:34 PM	38.2	38.1	0.1	23.6			1.0	236.0	116.2	116.3
H-1565E	6/16/2026 6:10:30 AM	44.2	38.0	0.0	17.8			1.2	0.0	107.6	107.9
H-1568N	6/2/2026 2:34:10 PM	30.8	34.2	0.0	35.0			0.9	0.0	114.8	115.0
H-1568N	6/16/2026 6:03:23 AM	33.9	36.1	0.0	30.0			0.9	0.0	113.8	113.4
H-1571S	6/3/2026 11:57:36 AM	49.0	41.4	0.0	9.6			1.2	0.0	96.4	96.7
H-1572N	6/2/2026 12:49:04 PM	28.0	33.1	0.0	38.9			0.8	0.0	143.6	132.0
H-1572N	6/2/2026 12:49:47 PM	28.1	33.3	0.0	38.6			0.8	0.0	128.7	128.3
H-1572S	6/3/2026 11:52:57 AM	46.9	39.3	0.0	13.8			1.2	0.0	103.6	103.7
H-1574N	6/10/2026 10:08:46 AM	32.7	28.3	5.9	33.1			1.2	5.6	101.1	101.1
H-1574N	6/10/2026 10:11:13 AM	32.8	29.5	5.8	31.9			1.1	5.5	101.8	101.9
H-1574N	6/25/2026 10:52:47 AM	49.7	42.6	0.2	7.5			1.2	37.5	100.3	100.3
H-1753N	6/2/2026 9:45:07 AM	40.9	35.4	4.5	19.2			1.2	4.3	78.7	78.7
H-1753N	6/26/2026 8:26:29 AM	28.7	25.4	9.3	36.6			1.1	3.9	60.1	60.6
H-1753N	6/26/2026 8:31:04 AM	28.8	25.7	9.2	36.3			1.1	3.9	64.4	65.8
H-1753N	6/26/2026 8:34:36 AM	35.3	30.7	6.6	27.4			1.1	4.2	66.9	67.9
H-1753S	6/3/2026 9:43:25 AM	39.0	40.3	0.0	20.7			1.0	0.0	112.2	111.0
H-1753S	6/22/2026 12:16:51 PM	58.5	40.9	0.0	0.6			1.4	0.0	110.1	109.5
H-1756S	6/2/2026 8:48:21 AM	33.0	65.0	0.0	2.0			0.5	0.0	126.5	125.0
H-1756S	6/16/2026 8:02:34 AM	40.1	58.6	0.0	1.3			0.7	0.0	121.3	121.3
H-1757S	6/2/2026 9:11:24 AM	30.1	43.2	0.0	26.7			0.7	0.0	77.0	76.9
H-1757S	6/16/2026 8:10:28 AM	44.8	45.1	0.0	10.1			1.0	0.0	85.8	84.6
H-1760S	6/2/2026 2:13:24 PM	33.4	45.7	0.0	20.9			0.7	0.0	117.6	117.4
H-1760S	6/17/2026 1:01:37 PM	32.4	43.0	0.0	24.6			0.8	0.0	117.8	117.4
H-1762N	6/2/2026 10:45:08 AM	43.1	40.6	0.0	16.3			1.1	0.0	104.9	106.1
H-1762N	6/16/2026 5:57:38 AM	45.0	38.7	0.0	16.3			1.2	0.0	106.0	106.0
H-1763N	6/4/2026 8:24:17 AM	46.8	43.0	0.0	10.2			1.1	0.0	113.3	113.4
H-1763S	6/3/2026 9:06:43 AM	41.2	36.3	0.0	22.5			1.1	0.0	104.0	104.2
H-1764N	6/3/2026 8:45:22 AM	56.4	40.9	0.0	2.7			1.4	0.0	118.4	119.3
H-1764S	6/3/2026 12:02:54 PM	43.2	41.2	0.0	15.6			1.0	0.0	104.7	104.0

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
H-1767N	6/10/2026 1:57:55 PM	45.8	54.2	0.0	0.0			0.8	0.0	104.0	104.4
H-1769N	6/1/2026 9:37:42 AM	16.7	63.3	0.7	19.3			0.3	27.6	104.7	104.2
H-1769N	6/17/2026 8:57:31 AM	30.6	64.3	0.0	5.1			0.5	0.0	98.2	98.4
H-1770N	6/1/2026 9:51:21 AM	34.2	65.7	0.0	0.1			0.5	0.0	101.9	102.0
H-1770N	6/15/2026 9:30:00 AM						12000				
H-1770N	6/15/2026 9:30:00 AM					79					
H-1770N	6/17/2026 9:09:18 AM	34.8	62.2	0.0	3.0			0.6	0.0	107.3	107.4
H-1770S	6/2/2026 8:08:25 AM	21.7	48.8	0.1	29.4			0.4	294.0	86.9	86.7
H-1770S	6/16/2026 7:49:23 AM	38.9	58.5	0.0	2.6			0.7	0.0	93.3	93.8
H-1771A	6/4/2026 2:01:14 PM	37.5	42.6	0.0	19.9			0.9	0.0	112.4	112.2
H-1771B	6/4/2026 10:07:06 AM	24.0	40.6	1.3	34.1			0.6	26.2	92.0	93.1
H-1771B	6/17/2026 2:04:52 PM	41.0	53.0	0.0	6.0			0.8	0.0	107.6	107.6
H-1774N	6/1/2026 1:44:46 PM	28.8	68.8	0.0	2.4			0.4	0.0	117.3	117.3
H-1774N	6/17/2026 9:23:18 AM	39.6	56.3	0.0	4.1			0.7	0.0	117.0	117.1
H-1801S	6/2/2026 12:28:57 PM	45.0	36.7	2.9	15.4			1.2	5.3	81.4	81.5
H-1802S	6/2/2026 12:44:59 PM	54.0	40.9	0.0	5.1			1.3	0.0	108.6	118.7
H-1803N	6/1/2026 10:35:00 AM						145700				
H-1803N	6/1/2026 10:35:00 AM					1410					
H-1803N	6/1/2026 10:35:20 AM	14.9	73.0	0.5	11.6			0.2	23.2	197.7	198.0
H-1803N	6/8/2026 9:49:51 AM	3.8	77.9	0.0	18.3			0.0	0.0	197.3	197.3
H-1803N	6/15/2026 9:16:07 AM	25.8	70.4	0.0	3.8			0.4	0.0	197.8	197.5
H-1803N	6/22/2026 9:30:13 AM	8.6	74.8	0.0	16.6			0.1	0.0	198.1	197.8
H-1803N	6/29/2026 9:51:07 AM	9.6	71.0	0.0	19.4			0.1	0.0	197.1	197.2
H-1804B	6/8/2026 11:58:30 AM	52.5	43.2	0.0	4.3			1.2	0.0	108.0	108.1

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
H-1804B	6/16/2026 12:52:32 PM	51.2	47.1	0.0	1.7			1.1	0.0	109.8	109.7
H-1804N	6/4/2026 1:46:12 PM	54.7	40.1	0.0	5.2			1.4	0.0	102.9	103.0
H-1804S	6/3/2026 8:47:55 AM	56.7	39.2	0.0	4.1			1.4	0.0	108.3	109.9
H-1805A	6/3/2026 12:28:07 PM	44.7	49.5	0.0	5.8			0.9	0.0	104.1	104.2
H-1805A	6/19/2026 10:10:27 AM	46.9	46.3	0.0	6.8			1.0	0.0	106.6	106.7
H-1805B	6/3/2026 8:35:39 AM	51.3	43.6	0.0	5.1			1.2	0.0	75.3	76.6
H-1805S	6/3/2026 8:58:45 AM	55.8	43.9	0.0	0.3			1.3	0.0	129.5	129.8
H-1806A	6/8/2026 11:47:40 AM	50.1	43.5	0.1	6.3			1.2	63.0	104.0	104.1
H-1806B	6/2/2026 12:54:05 PM	13.6	27.0	0.0	59.4			0.5	0.0	136.3	128.3
H-1806B	6/2/2026 12:56:02 PM	13.7	27.3	0.0	59.0			0.5	0.0	120.4	119.7
H-1806N	6/8/2026 10:18:36 AM	47.7	52.3	0.0	0.0			0.9	0.0	129.3	129.0
H-1806S	6/3/2026 9:15:06 AM	44.6	53.7	0.0	1.7			0.8	0.0	121.8	120.3
H-1807A	6/2/2026 11:48:10 AM	56.1	41.2	0.0	2.7			1.4	0.0	112.2	113.5
H-1807N	6/8/2026 10:40:50 AM	15.1	20.2	3.0	61.7			0.7	20.6	86.7	86.7
H-1807S	6/2/2026 12:21:01 PM	44.8	37.5	0.1	17.6			1.2	176.0	85.9	85.9
H-1952S	6/3/2026 2:08:31 PM	53.5	46.3	0.0	0.2			1.2	0.0	97.7	109.6
H-1952S	6/3/2026 2:09:49 PM	53.6	45.1	0.0	1.3			1.2	0.0	113.4	113.8
H-1952S	6/16/2026 6:13:44 AM	56.5	42.4	0.0	1.1			1.3	0.0	119.0	119.0
H-1955C	6/3/2026 12:19:34 PM	36.7	33.7	2.4	27.2			1.1	11.3	90.2	87.1
H-1955C	6/19/2026 10:16:23 AM	41.0	34.2	2.4	22.4			1.2	9.3	73.1	73.1
H-1955N	6/4/2026 1:43:34 PM	41.4	37.8	0.2	20.6			1.1	103.0	94.7	95.6
H-1956B	6/3/2026 8:18:31 AM	30.7	57.6	0.0	11.7			0.5	0.0	119.1	119.7
H-1956B	6/9/2026 11:39:37 AM	28.0	57.2	0.0	14.8			0.5	0.0	120.9	121.0
H-1956N	6/8/2026 10:12:46 AM	54.5	45.5	0.0	0.0			1.2	0.0	100.5	100.4
H-1956S	6/2/2026 12:40:22 PM	35.6	37.2	0.0	27.2			1.0	0.0	103.5	103.9
H-1957B	6/2/2026 11:59:17 AM	49.7	38.8	0.0	11.5			1.3	0.0	111.7	111.9
H-1957N	6/8/2026 10:21:49 AM	54.7	45.3	0.0	0.0			1.2	0.0	121.1	121.6

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
H-1957S	6/2/2026 12:31:09 PM	44.1	52.2	0.0	3.7			0.8	0.0	94.2	96.1
H-1958C	6/2/2026 11:45:15 AM	58.5	39.4	0.0	2.1			1.5	0.0	102.0	105.3
H-1958C	6/9/2026 11:32:42 AM	47.7	38.9	0.0	13.4			1.2	0.0	122.6	124.3
H-1958N	6/8/2026 10:36:31 AM	40.5	37.0	0.1	22.4			1.1	224.0	120.6	119.2
H-1958S	6/18/2026 2:13:22 PM	30.3	32.0	1.9	35.8			0.9	18.8	91.1	90.9
H-1958S	6/18/2026 2:17:07 PM	29.8	31.2	2.1	36.9			1.0	17.6	92.7	92.8
H-1962N	6/1/2026 1:28:34 PM	13.5	13.5	13.2	59.8			1.0	4.5	95.1	94.0
H-1962N	6/1/2026 1:34:46 PM	0.0	0.1	21.0	78.9			0.0	3.8	91.8	91.9
H-1962N	6/5/2026 9:09:10 AM	0.1	2.5	20.2	77.2			0.0	3.8	81.5	84.8
H-1962N	6/17/2026 9:12:30 AM	0.1	4.6	19.7	75.6			0.0	3.8	77.9	78.2
H-1963N	6/1/2026 9:34:55 AM	22.7	70.7	0.1	6.5			0.3	65.0	141.0	140.9
H-1963N	6/17/2026 8:54:38 AM	23.8	66.7	0.0	9.5			0.4	0.0	143.7	143.6
H-1963N	6/17/2026 12:20:47 PM	49.3	50.7	0.0	0.0			1.0	0.0	143.2	143.7
H-1963N	6/17/2026 12:21:03 PM	48.0	52.0	0.0	0.0			0.9	0.0	143.8	143.8
H-1966N	6/1/2026 1:55:09 PM	34.8	46.8	0.0	18.4			0.7	0.0	108.1	108.2
H-1966N	6/22/2026 10:30:50 AM	44.6	51.1	0.0	4.3			0.9	0.0	106.7	106.9
H-1967E	6/10/2026 2:54:38 PM	29.7	22.9	8.4	39.0			1.3	4.6	103.9	104.4
H-1967E	6/10/2026 2:55:55 PM	28.9	21.6	8.9	40.6			1.3	4.6	106.6	106.6
H-1967W	6/8/2026 11:55:13 AM	57.2	39.3	0.0	3.5			1.5	0.0	97.3	97.5
H-2050E	6/11/2026 12:37:27 PM	55.5	42.5	0.0	2.0			1.3	0.0	108.6	109.0
H-2050W	6/3/2026 12:58:46 PM	34.7	35.9	0.0	29.4			1.0	0.0	103.9	103.9
H-2051W	6/8/2026 11:47:12 AM	55.7	38.1	0.0	6.2			1.5	0.0	91.8	91.9
H-2053E	6/10/2026 3:02:37 PM	36.9	33.4	0.1	29.6			1.1	296.0	121.3	121.4
H-2053W	6/8/2026 12:17:00 PM	57.7	38.4	0.0	3.9			1.5	0.0	96.9	97.5
H-2055E	6/3/2026 12:15:20 PM	32.2	34.0	0.0	33.8			0.9	0.0	109.9	108.9
H-2055E	6/19/2026 4:01:38 PM	40.8	36.9	0.0	22.3			1.1	0.0	103.4	103.5
H-2056B	6/10/2026 3:26:06 PM	12.7	21.6	0.0	65.7			0.6	0.0	98.4	98.4
H-2056W	6/8/2026 11:51:53 AM	56.6	38.3	0.0	5.1			1.5	0.0	103.1	103.8
H-2057E	6/10/2026 2:59:49 PM	54.8	41.0	0.5	3.7			1.3	7.4	126.9	127.0
H-2057W	6/8/2026 11:59:37 AM	48.9	35.5	2.0	13.6			1.4	6.8	88.5	88.8

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
H-2057W	6/8/2026 12:01:57 PM	50.3	36.9	1.0	11.8			1.4	11.8	88.8	88.7
H-2058E	6/10/2026 3:18:13 PM	48.9	40.2	0.0	10.9			1.2	0.0	111.0	111.0
H-2058W	6/8/2026 11:49:40 AM	45.1	36.4	0.0	18.5			1.2	0.0	99.7	99.6
H-2059E	6/25/2026 7:45:33 AM	54.3	43.6	0.1	2.0			1.2	20.0	121.3	121.7
H-2059W	6/8/2026 12:39:30 PM	43.0	41.7	0.0	15.3			1.0	0.0	123.1	123.3
H-2161E	6/25/2026 7:39:50 AM	53.0	40.6	0.1	6.3			1.3	63.0	123.3	123.4
H-2161W	6/8/2026 12:36:22 PM	39.8	35.2	0.0	25.0			1.1	0.0	105.9	106.0
H-2163C	6/1/2026 10:28:26 AM	35.8	40.0	0.0	24.2			0.9	0.0	94.8	94.9
H-2163C	6/17/2026 11:36:55 AM	43.3	40.9	0.0	15.8			1.1	0.0	98.5	98.5
H-2163W	6/8/2026 1:21:45 PM	31.1	63.1	0.0	5.8			0.5	0.0	131.4	129.9
H-2163W	6/8/2026 1:22:03 PM	31.1	65.9	0.0	3.0			0.5	0.0	129.7	129.8
H-2164E	6/3/2026 12:08:19 PM	38.2	54.5	0.0	7.3			0.7	0.0	128.0	128.1
H-2164E	6/19/2026 4:09:03 PM	45.6	50.1	0.1	4.2			0.9	42.0	124.2	124.2
H-2165E	6/10/2026 1:48:13 PM	54.9	45.1	0.0	0.0			1.2	0.0	121.5	121.4
H-2165W	6/10/2026 8:33:57 AM	9.9	79.5	0.0	10.6			0.1	0.0	115.5	115.2
H-2165W	6/16/2026 8:05:00 AM						60000				
H-2165W	6/16/2026 8:05:00 AM					890					
H-2165W	6/17/2026 8:24:58 AM	12.5	78.7	0.0	8.8			0.2	0.0	90.5	90.5
H-2166E	6/2/2026 11:55:24 AM	56.3	41.2	0.3	2.2			1.4	7.3	109.8	109.9
H-2168C	6/3/2026 8:16:01 AM	44.0	31.3	4.1	20.6			1.4	5.0	76.9	76.9
H-2168E	6/2/2026 12:04:16 PM	34.3	36.1	0.0	29.6			1.0	0.0	121.1	120.7
H-2169C	6/3/2026 8:21:40 AM	51.0	38.8	0.0	10.2			1.3	0.0	109.4	109.5
H-2169E	6/2/2026 1:13:50 PM	40.5	41.3	0.0	18.2			1.0	0.0	114.3	114.3
H-2170N	6/15/2026 1:03:30 PM	44.5	36.2	0.0	19.3			1.2	0.0	120.4	120.5
H-2170S	6/12/2026 11:45:52 AM	56.6	37.5	0.2	5.7			1.5	28.5	103.2	103.2
H-2171A	6/1/2026 9:28:09 AM	40.3	36.4	0.0	23.3			1.1	0.0	94.0	94.0
H-2171B	6/1/2026 10:04:39 AM	45.5	37.0	0.1	17.4			1.2	174.0	119.5	119.5
H-2171N	6/1/2026 8:58:16 AM	15.1	24.1	2.2	58.6			0.6	26.6	121.3	121.4
H-2171S	6/15/2026 1:06:14 PM	51.7	40.1	0.0	8.2			1.3	0.0	122.0	122.1
H-2272W	6/8/2026 1:02:54 PM	27.5	44.4	0.0	28.1			0.6	0.0	125.4	125.0
H-2272W	6/16/2026 8:49:15 AM	33.6	48.8	0.0	17.6			0.7	0.0	124.7	124.8
H-2273W	6/2/2026 7:45:00 AM						16000				
H-2273W	6/2/2026 7:45:00 AM					240					

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
H-2273W	6/2/2026 8:54:53 AM	21.0	55.4	0.0	23.6			0.4	0.0	128.1	126.9
H-2273W	6/16/2026 8:21:18 AM	28.2	57.6	0.0	14.2			0.5	0.0	126.2	125.6
H-2274B	6/11/2026 10:34:51 AM	52.0	45.3	0.0	2.7			1.1	0.0	97.7	97.6
H-2274B	6/17/2026 12:47:21 PM	51.9	43.7	0.0	4.4			1.2	0.0	102.8	103.0
H-2274W	6/2/2026 8:36:16 AM	22.2	65.9	0.0	11.9			0.3	0.0	125.1	124.0
H-2274W	6/16/2026 8:00:20 AM	29.1	57.6	0.0	13.3			0.5	0.0	123.0	121.9
H-2275E	6/3/2026 9:04:41 AM	35.5	46.4	0.0	18.1			0.8	0.0	122.5	122.4
H-2275W	6/2/2026 9:27:59 AM	1.8	12.7	9.2	76.3			0.1	8.3	117.9	110.3
H-2275W	6/16/2026 8:53:25 AM	3.7	16.5	2.9	76.9			0.2	26.5	124.4	126.0
H-2276A	6/2/2026 2:20:31 PM	28.7	36.7	0.5	34.1			0.8	68.2	110.4	110.5
H-2276A	6/22/2026 9:30:29 AM	36.1	35.3	0.5	28.1			1.0	58.5	113.0	113.2
H-2276A	6/22/2026 9:31:52 AM	35.6	35.8	0.5	28.1			1.0	62.5	113.2	113.2
H-2276B	6/8/2026 2:59:25 PM	54.3	41.7	0.0	4.0			1.3	0.0	117.8	118.0
H-2276B	6/17/2026 12:52:46 PM	51.2	41.6	0.0	7.2			1.2	0.0	118.5	118.9
H-2276E	6/3/2026 8:54:18 AM	44.7	38.9	0.0	16.4			1.1	0.0	119.7	119.4
H-2276W	6/2/2026 9:06:49 AM	21.9	56.6	0.0	21.5			0.4	0.0	87.9	89.4
H-2276W	6/16/2026 8:07:54 AM	25.4	58.6	0.0	16.0			0.4	0.0	91.5	92.1
H-2277A	6/3/2026 8:51:39 AM	45.1	51.1	0.4	3.4			0.9	8.5	77.3	78.2
H-2277A	6/16/2026 9:24:22 AM	45.0	47.4	1.2	6.4			0.9	5.3	88.3	88.4
H-2277B	6/2/2026 1:12:56 PM	49.0	40.6	0.0	10.4			1.2	0.0	117.6	117.4
H-2277B	6/3/2026 8:54:09 AM	32.6	65.2	0.0	2.2			0.5	0.0	117.9	117.8
H-2277B	6/19/2026 1:21:11 PM	49.9	41.8	0.0	8.3			1.2	0.0	117.1	117.0
H-23 (EXP-2	6/1/2026 9:52:09 AM	0.8	4.9	19.4	74.9			0.2	3.9	88.8	89.1
H-23 (EXP-2	6/1/2026 9:54:19 AM	0.1	1.7	20.2	78.0			0.1	3.9	90.0	90.1
H-2301E	6/14/2026 2:18:45 PM	36.0	35.3	0.3	28.5			1.0	105.6	115.4	115.4
H-2301E	6/14/2026 2:24:14 PM	34.9	35.3	0.3	29.5			1.0	105.4	114.9	114.8
H-2301E	6/14/2026 2:26:21 PM	35.1	35.4	0.3	29.3			1.0	100.9	114.5	114.6
H-2301W	6/25/2026 1:05:18 PM	36.3	25.5	7.7	30.5			1.4	4.0	88.3	88.3
H-2301W	6/25/2026 1:09:52 PM	23.4	15.2	12.9	48.5			1.5	3.8	87.9	87.9

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
H-2301W	6/30/2026 8:35:25 AM	54.2	37.2	1.1	7.5			1.5	6.8	73.2	73.7
H-2302C	6/8/2026 9:52:30 AM	37.5	34.6	1.0	26.9			1.1	26.9	125.4	125.4
H-2302C	6/12/2026 2:48:52 PM	36.2	33.7	1.0	29.1			1.1	29.1	124.9	124.3
H-2302E	6/11/2026 10:52:08 AM	56.3	41.3	0.0	2.4			1.4	0.0	101.1	101.2
H-2303E	6/11/2026 10:55:35 AM	55.3	39.5	0.0	5.2			1.4	0.0	95.3	95.2
H-2303N	6/8/2026 9:57:28 AM	30.8	34.5	0.0	34.7			0.9	0.0	102.8	102.9
H-2303S	6/25/2026 12:20:01 PM	58.4	41.5	0.1	0.0			1.4	0.0	91.1	90.2
H-2303S	6/25/2026 12:23:24 PM	56.9	42.9	0.0	0.2			1.3	0.0	95.9	96.4
H-2304E	6/11/2026 10:58:48 AM	56.3	41.3	0.0	2.4			1.4	0.0	97.1	97.1
H-2304S	6/11/2026 11:10:09 AM	47.5	40.4	0.0	12.1			1.2	0.0	124.9	125.2
H-2305N	6/8/2026 10:04:24 AM	17.6	29.1	0.0	53.3			0.6	0.0	92.7	93.2
H-2305S	6/11/2026 1:24:17 PM	48.6	42.9	0.0	8.5			1.1	0.0	127.3	127.4
H-2306N	6/11/2026 12:47:49 PM	38.0	35.3	0.0	26.7			1.1	0.0	117.7	117.9
H-2307S	6/8/2026 9:41:48 AM	56.8	39.1	0.0	4.1			1.5	0.0	93.0	93.6
H-2307S	6/8/2026 9:42:18 AM	57.8	41.6	0.0	0.6			1.4	0.0	93.8	93.9
H-2307S	6/8/2026 11:07:20 AM	55.1	44.7	0.0	0.2			1.2	0.0	127.6	127.4
H-2307S	6/12/2026 1:35:06 PM	53.0	45.3	0.0	1.7			1.2	0.0	126.2	127.8
H-2308S	6/8/2026 9:47:16 AM	54.8	41.6	0.0	3.6			1.3	0.0	99.6	100.0
H-2308S	6/12/2026 1:23:49 PM	52.3	43.2	0.0	4.5			1.2	0.0	118.3	121.1
H-2309N	6/1/2026 10:38:59 AM	43.6	42.0	0.0	14.4			1.0	0.0	94.6	94.6
H-2309S	6/11/2026 1:19:20 PM	54.9	42.3	0.0	2.8			1.3	0.0	114.4	114.7
H-2310N	6/10/2026 3:31:54 PM	7.1	6.1	18.0	68.8			1.2	3.8	111.5	110.5
H-2310N	6/10/2026 3:33:41 PM	27.5	22.9	7.6	42.0			1.2	5.5	110.7	110.7
H-2310S	6/11/2026 12:41:51 PM	38.7	31.8	0.0	29.5			1.2	0.0	106.1	106.0
H-2401S	6/8/2026 10:24:48 AM	56.4	39.3	0.0	4.3			1.4	0.0	110.2	110.5
H-2401S	6/12/2026 10:50:55 AM	53.4	42.3	0.0	4.3			1.3	0.0	110.1	110.1
H-2401S	6/30/2026 1:49:46 PM	55.0	45.0	0.0	0.0			1.2	0.0	110.0	109.9
H-2402N	6/8/2026 10:17:02 AM	37.9	38.9	0.0	23.2			1.0	0.0	114.0	113.5
H-2402S	6/8/2026 10:36:11 AM	33.2	33.1	0.3	33.4			1.0	111.3	111.7	111.7

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
H-2402S	6/12/2026 11:01:51 AM	32.5	31.5	0.4	35.6			1.0	89.0	111.4	111.5
H-2403N	6/8/2026 10:13:34 AM	35.3	36.2	1.1	27.4			1.0	24.9	115.9	115.9
H-2403S	6/8/2026 10:10:36 AM	55.9	41.6	0.0	2.5			1.3	0.0	81.3	82.3
H-2403S	6/12/2026 1:10:46 PM	38.6	30.9	3.7	26.8			1.2	7.2	99.5	99.5
H-2404N	6/3/2026 1:04:10 PM	54.7	41.8	0.0	3.5			1.3	0.0	115.3	115.3
H-2404S	6/8/2026 9:10:41 AM	57.7	40.7	0.0	1.6			1.4	0.0	113.7	113.8
H-2405N	6/10/2026 9:20:55 AM	23.0	34.3	0.0	42.7			0.7	0.0	118.0	118.2
H-29	6/15/2026 12:56:44 PM	21.2	46.6	0.0	32.2			0.5	0.0	95.5	100.4
H-72	6/24/2026 10:05:28 AM	44.3	55.7	0.0	0.0			0.8	0.0	94.8	96.1
H-74	6/15/2026 11:34:23 AM	54.5	40.7	0.0	4.8			1.3	0.0	104.2	104.3
H-75	6/15/2026 1:24:56 PM	36.6	39.2	0.0	24.2			0.9	0.0	97.5	97.7
H-79	6/3/2026 9:53:50 AM	47.8	48.1	0.0	4.1			1.0	0.0	120.6	121.3
P-02R	6/1/2026 10:04:56 AM	27.3	32.0	0.0	40.8			0.9	0.0	85.9	86.1
P-03R	6/1/2026 10:14:48 AM	40.4	33.8	0.0	25.8			1.2	0.0	97.2	97.3
P-04	6/1/2026 10:26:15 AM	45.0	38.1	0.0	16.9			1.2	0.0	100.3	100.3
P-05	6/1/2026 10:44:04 AM	34.0	35.9	0.0	30.1			0.9	0.0	103.3	104.2
P-06R	6/1/2026 10:55:26 AM	41.4	36.2	0.0	22.4			1.1	0.0	110.5	110.8
P-07R	6/3/2026 10:13:11 AM	32.2	31.7	0.0	36.1			1.0	0.0	86.7	86.6
P-08R	6/1/2026 9:35:18 AM	53.6	36.7	0.0	9.7			1.5	0.0	99.6	99.9
P-08R	6/1/2026 9:45:12 AM	52.9	37.1	0.0	10.0			1.4	0.0	99.4	99.5
P-08R	6/1/2026 9:48:41 AM	52.3	37.9	0.0	9.8			1.4	0.0	99.6	99.7
P-09	6/1/2026 1:04:32 PM	47.3	36.5	0.0	16.2			1.3	0.0	98.8	98.8
P-10	6/1/2026 1:16:13 PM	43.7	34.4	0.0	22.0			1.3	0.0	93.0	93.2
P-11	6/1/2026 1:24:13 PM	47.2	36.3	0.0	16.5			1.3	0.0	106.1	106.0
P-12	6/1/2026 2:05:59 PM	55.3	40.1	0.0	4.6			1.4	0.0	86.7	86.6
P-12	6/1/2026 2:07:33 PM	55.1	40.2	0.0	4.6			1.4	0.0	86.7	86.7
P-13	6/1/2026 1:44:03 PM	48.0	35.9	0.0	16.1			1.3	0.0	85.5	85.5
P-13	6/1/2026 1:53:17 PM	55.5	40.0	0.0	4.5			1.4	0.0	88.9	88.2
P-14	6/1/2026 2:21:50 PM	24.5	29.8	0.4	45.3			0.8	105.4	89.9	89.6
P-14	6/2/2026 10:41:03 AM	23.4	30.3	0.9	45.4			0.8	52.8	79.8	79.8
P-15R	6/2/2026 10:52:46 AM	42.5	35.5	0.0	22.1			1.2	0.0	83.6	84.3
P-16	6/9/2026 10:06:22 AM	50.3	37.4	0.0	12.3			1.3	0.0	94.3	94.8
P-16	6/9/2026 10:12:29 AM	49.9	38.0	0.0	12.1			1.3	0.0	94.4	94.7

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
P-17	6/9/2026 9:53:57 AM	35.9	34.7	0.1	29.3			1.0	209.0	111.4	111.4
P-18RD	6/9/2026 10:45:27 AM	48.4	38.4	0.0	13.2			1.3	0.0	90.5	90.7
P-18RS	6/9/2026 10:54:04 AM	39.8	35.5	0.0	24.7			1.1	0.0	94.9	94.8
P-19	6/9/2026 1:21:14 PM	35.2	33.4	0.0	31.4			1.1	0.0	88.8	89.0
P-20R	6/9/2026 1:01:59 PM	48.4	36.8	0.0	14.9			1.3	0.0	99.3	99.4
P-20R	6/9/2026 1:10:19 PM	46.6	36.5	0.0	16.9			1.3	0.0	100.0	100.0
P-20R	6/9/2026 1:12:39 PM	48.3	37.3	0.0	14.5			1.3	0.0	100.0	100.0
P-21	6/9/2026 1:31:50 PM	35.7	34.2	0.0	30.2			1.0	0.0	94.0	94.1
P-21RD	6/9/2026 1:39:47 PM	40.6	36.4	0.0	23.0			1.1	0.0	100.8	100.8
P-21RS	6/9/2026 1:46:57 PM	45.7	38.5	0.0	15.8			1.2	0.0	108.5	108.5
P-22RD	6/15/2026 1:51:06 PM	50.0	41.8	0.0	8.2			1.2	0.0	117.6	118.1
P-22RS	6/15/2026 1:46:59 PM	0.0	33.0	0.0	67.0			0.0	0.0	121.2	121.4
P-23	6/9/2026 2:24:44 PM	3.4	20.1	0.6	75.9			0.2	138.1	96.1	95.8
P-24	6/10/2026 10:21:41 AM	21.2	31.7	0.0	47.1			0.7	0.0	94.1	94.7
P-26	6/10/2026 10:43:44 AM	43.5	37.4	0.0	19.1			1.2	0.0	86.6	86.6
P-27	6/10/2026 1:24:51 PM	4.6	18.6	1.2	75.6			0.2	61.9	102.1	102.1
P-28	6/10/2026 1:37:21 PM	35.7	34.7	0.0	29.6			1.0	0.0	99.2	
P-29R	6/15/2026 7:50:21 AM	22.5	24.3	0.3	52.9			0.9	176.3	86.4	86.4
P-30R	6/15/2026 7:53:58 AM	18.1	24.5	0.1	57.3			0.7	573.0	86.5	86.5
P-32R1	6/15/2026 7:59:37 AM	21.5	28.0	0.6	49.9			0.8	83.2	111.7	111.7
P-32R2	6/15/2026 8:02:27 AM	24.4	27.9	0.4	47.3			0.9	118.3	110.5	110.5
P-33	6/15/2026 8:06:14 AM	30.9	30.9	1.8	36.4			1.0	20.2	96.0	96.0
P-36	6/15/2026 8:14:41 AM	17.2	23.8	0.2	58.8			0.7	294.0	82.0	82.2
P-37	6/15/2026 8:18:30 AM	7.4	21.2	1.0	70.4			0.3	70.4	93.6	93.8
P-38RD	6/15/2026 8:30:24 AM	37.9	32.0	0.0	30.1			1.2	0.0	107.3	107.3
P-38RS	6/15/2026 8:28:11 AM	27.1	28.0	0.0	44.9			1.0	0.0	105.5	105.6
P-39	6/15/2026 8:36:42 AM	37.6	34.7	0.8	26.9			1.1	33.6	88.4	88.7
P-41	6/15/2026 8:48:14 AM	15.2	17.0	8.3	59.5			0.9	7.2	111.3	111.3
P-41	6/15/2026 8:50:24 AM	15.1	16.8	8.3	59.8			0.9	7.2	110.0	111.2
P-42R	6/15/2026 8:58:53 AM	48.6	40.0	0.0	11.4			1.2	0.0	113.7	113.7
P-43	6/15/2026 9:08:50 AM	20.0	24.7	0.8	54.5			0.8	68.1	117.1	117.2
P-44RD	6/15/2026 9:11:45 AM	46.2	32.0	0.0	21.8			1.4	0.0	100.0	100.5
P-44RS	6/15/2026 9:18:50 AM	19.2	26.6	0.0	54.2			0.7	0.0	122.2	122.5
P-45RD	6/15/2026 9:31:24 AM	38.6	34.2	0.0	27.2			1.1	0.0	116.1	116.2
P-45RS	6/15/2026 9:29:22 AM	1.8	16.9	0.0	81.3			0.1	0.0	103.0	103.4

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
P-46RD	6/15/2026 9:42:33 AM	43.6	33.9	0.0	22.5			1.3	0.0	108.7	108.8
P-46RS	6/15/2026 9:40:21 AM	15.5	22.2	0.0	62.3			0.7	0.0	121.4	121.4
P-47	6/15/2026 10:35:42 AM	8.8	23.9	1.1	66.3			0.4	60.8	103.3	103.3
P-48	6/15/2026 10:47:00 AM	22.5	27.3	0.0	50.2			0.8	0.0	124.7	124.9
P-49RD	6/15/2026 1:10:23 PM	50.2	38.5	0.0	11.3			1.3	0.0	115.2	115.2
P-49RS	6/15/2026 12:57:56 PM	38.0	34.0	0.1	28.0			1.1	559.2	115.5	115.6
P-49RS	6/15/2026 1:06:47 PM	37.8	34.0	0.0	28.2			1.1	0.0	115.6	115.6
P-52	6/15/2026 12:36:30 PM	32.1	33.0	0.0	34.9			1.0	0.0	118.1	118.1
P-52	6/15/2026 12:37:24 PM	31.6	33.3	0.0	35.2			0.9	0.0	118.1	118.2
P-53	6/3/2026 2:24:03 PM	24.1	32.3	0.0	43.6			0.7	0.0	116.8	
P-53	6/3/2026 2:32:15 PM	24.0	33.0	0.0	43.0			0.7	0.0	116.1	115.7
P-53	6/3/2026 2:35:13 PM	24.8	33.3	0.0	41.9			0.7	0.0	115.4	115.4
P-54	6/3/2026 1:49:46 PM	34.5	35.8	0.0	29.7			1.0	0.0	104.0	104.0
P-54	6/16/2026 2:27:41 PM	34.2	32.7	0.0	33.1			1.0	0.0	104.7	104.6
P-55	6/3/2026 1:33:10 PM	32.2	34.9	0.0	32.9			0.9	0.0	100.4	100.4
P-56	6/3/2026 1:00:08 PM	19.2	28.5	0.4	51.9			0.7	129.7	103.9	103.9
P-56	6/3/2026 1:18:05 PM	19.8	30.6	0.0	49.6			0.6	0.0	103.8	103.8
P-57	6/3/2026 12:32:14 PM	28.6	27.6	2.8	41.0			1.0	14.9	86.3	
P-60R	6/10/2026 2:07:25 PM	51.0	37.5	0.0	11.5			1.4	0.0	100.9	101.1
P-61	6/10/2026 2:14:41 PM	43.2	37.0	0.0	19.9			1.2	0.0	91.4	91.4
P-65	6/10/2026 2:29:10 PM	32.9	32.9	0.0	34.2			1.0	0.0	92.9	93.8
P-71	6/15/2026 1:16:48 PM	42.8	33.9	0.0	23.3			1.3	0.0	97.5	98.0
P-71	6/15/2026 1:17:31 PM	42.2	34.5	0.0	23.4			1.2	0.0	98.4	98.5
P-75	6/10/2026 2:44:34 PM	50.8	38.6	0.0	10.5			1.3	0.0	95.0	95.1
P-76	6/15/2026 8:24:20 AM	17.2	25.1	0.5	57.2			0.7	114.4	105.0	105.7
P-79	6/9/2026 10:24:04 AM	20.7	30.9	0.9	47.5			0.7	55.9	90.8	91.0
SC-2000E	6/3/2026 12:31:16 PM	49.2	39.0	0.0	11.8			1.3	0.0	122.0	121.8
SC-2501E	6/1/2026 10:05:00 AM					1370					
SC-2501E	6/1/2026 10:05:00 AM						179800				
SC-2501E	6/1/2026 10:05:41 AM	13.4	74.8	0.0	11.8			0.2	0.0	189.5	189.4
SC-2501E	6/8/2026 9:41:04 AM	3.3	72.5	0.0	24.2			0.0	0.0	188.5	188.8
SC-2501E	6/15/2026 9:12:25 AM	25.2	71.0	0.0	3.8			0.4	0.0	189.9	183.6
SC-2501E	6/29/2026 9:32:13 AM	10.4	64.4	3.7	21.5			0.2	5.8	187.0	188.9
SC-2501E	6/29/2026 9:37:36 AM	13.8	74.6	0.2	11.4			0.2	57.0	188.9	188.9

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
SC-2501W	6/11/2026 9:57:09 AM	24.1	75.9	0.0	0.0			0.3	0.0	186.3	186.4
SC-2501W	6/12/2026 9:03:41 AM	3.1	74.3	2.4	20.2			0.0	8.4	185.5	185.5
SC-2501W	6/16/2026 8:35:07 AM	3.4	61.7	4.3	30.6			0.1	7.1	183.9	184.2
SC-2501W	6/16/2026 8:37:36 AM	3.4	59.2	4.8	32.6			0.1	6.8	184.2	183.5
SC-2501W	6/16/2026 8:39:56 AM	5.1	60.2	4.0	30.7			0.1	7.7	183.3	183.2
SC-2501W	6/22/2026 10:01:39 AM	15.3	70.7	0.0	14.0			0.2	0.0	188.5	188.5
SC-2501W	6/29/2026 10:05:06 AM	13.4	54.8	5.8	26.0			0.2	4.5	183.5	172.3
SC-2501W	6/29/2026 10:07:43 AM	13.0	56.5	4.9	25.6			0.2	5.2	157.4	156.6
SW-10	6/25/2026 12:49:30 PM	22.6	33.5	1.0	42.9			0.7	42.9	86.7	86.7
SW-115	6/1/2026 10:41:10 AM	48.3	38.3	0.0	13.4			1.3	0.0	90.1	90.1
SW-154	6/26/2026 11:08:16 AM	0.1	0.9	19.9	79.1			0.1	4.0	92.6	92.7
SW-187	6/8/2026 12:55:51 PM	19.0	35.9	3.2	41.9			0.5	12.9	89.3	89.6
SW-1930	6/2/2026 5:58:06 AM	26.1	52.0	2.4	19.5			0.5	8.1	82.8	83.0
SW-20	6/3/2026 10:03:24 AM	0.0	5.7	14.7	79.6			0.0	5.4	87.7	88.6
SW-2503D	6/29/2026 5:49:38 AM	7.3	10.3	18.5	63.9			0.7	3.5	55.7	55.4
SW-2503M	6/29/2026 5:56:58 AM	0.5	0.1	22.3	77.1			5.0	3.5	53.1	53.0
SW-2503MD	6/29/2026 5:53:43 AM	8.5	19.9	14.1	57.5			0.4	4.1	72.2	72.3
SW-2503S	6/29/2026 5:59:37 AM	12.2	12.0	16.6	59.2			1.0	3.6	55.9	56.0
SW-2504D	6/29/2026 6:04:51 AM	3.3	3.0	15.9	77.8			1.1	4.9	53.4	53.2
SW-2504M	6/29/2026 6:08:59 AM	0.4	0.0	22.2	77.4				3.5	52.3	52.3
SW-2504MD	6/29/2026 6:15:30 AM	16.7	26.1	8.3	48.9			0.6	5.9	62.1	62.3
SW-2504S	6/29/2026 6:12:14 AM	15.3	18.9	11.6	54.2			0.8	4.7	67.5	67.7
SW-65	6/1/2026 10:45:05 AM	47.7	38.2	0.0	14.1			1.2	0.0	88.4	88.5
SW-66	6/26/2026 11:06:07 AM	11.2	14.6	10.9	63.3			0.8	5.8	89.4	89.4
SW-70	6/8/2026 12:58:00 PM	17.8	62.9	0.0	19.3			0.3	0.0	87.1	87.3
SW-71	6/10/2026 10:30:25 AM	12.5	17.7	7.0	62.8			0.7	9.0	97.0	97.0
SW-72	6/15/2026 8:11:58 AM	5.6	15.8	3.5	75.1			0.4	21.5	81.6	81.7
SW-80	6/1/2026 11:35:52 AM	33.2	28.5	0.3	38.0			1.2	126.7	95.5	95.7

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
SW-9	6/8/2026 1:00:58 PM	1.7	25.3	11.0	62.0			0.1	5.6	87.7	87.8
TC-1961C	6/3/2026 12:00:23 PM	31.1	35.2	0.0	33.7			0.9	0.0	89.9	90.9
TC-1961E	6/3/2026 9:11:02 AM	55.7	44.3	0.0	0.0			1.3	0.0	117.8	118.4
TC-2174	6/1/2026 6:25:00 AM						167500				
TC-2174	6/1/2026 9:52:38 AM	15.4	74.8	0.0	9.8			0.2	0.0	165.4	165.4
TC-2174	6/1/2026 6:25:00 PM					1970					
TC-2174	6/8/2026 9:26:15 AM	4.1	75.2	0.0	20.7			0.1	0.0	183.2	183.2
TC-2174	6/15/2026 8:52:15 AM	9.7	71.9	0.0	18.4			0.1	0.0	184.0	184.0
TC-2174	6/22/2026 8:57:50 AM	7.5	79.7	0.0	12.8			0.1	0.0	184.1	184.1
TC-2174	6/29/2026 9:19:30 AM	4.6	74.9	0.0	20.5			0.1	0.0	184.2	184.3
VL-02	6/26/2026 12:25:21 PM	58.3	33.7	1.4	6.6			1.7	4.7	95.2	96.0
WTD-02	6/14/2026 8:45:26 AM	10.9	43.1	7.9	38.1			0.3	4.8	151.8	151.9
WTD-02	6/17/2026 1:24:35 PM	13.5	40.5	7.7	38.3			0.3	5.0	143.0	141.1
WTD-02	6/17/2026 1:26:01 PM	11.9	40.2	8.1	39.8			0.3	4.9	140.7	
WTD-03	6/14/2026 8:49:13 AM	0.8	7.1	18.6	73.5			0.1	3.9	83.5	82.0
WTD-06	6/14/2026 9:11:46 AM	3.2	9.6	16.2	71.1			0.3	4.4	123.1	123.4
WTD-07	6/14/2026 9:07:02 AM	2.0	5.4	17.7	74.9			0.4	4.2	88.9	89.1
WTD-10	6/14/2026 9:00:26 AM	12.2	19.3	12.0	56.6			0.6	4.7	119.5	119.5

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
A-01	6/12/2026 11:15:57 AM	-19.94	-20.33	0.0	0.0					28.71	1161
A-02	6/12/2026 11:23:56 AM	-18.82	-19.48	0.0	0.0					28.7	1184
A-03	6/12/2026 11:26:57 AM	-20.30	-18.37	0.0	0.0					28.7	1178
A-04	6/12/2026 11:30:07 AM	-10.73	-10.75	0.0	0.0					28.7	1201
A-05	6/12/2026 11:32:50 AM	-17.54	-16.99	0.0	0.0					28.7	1096
B-01	6/15/2026 10:15:16 AM	-0.20	-0.19	0.4	0.5	0.046	0.064	-17.04	-16.89	28.73	1232
B-02R	6/15/2026 10:12:05 AM	-0.11	-0.12	0.1	0.2	0.001	0.005	-16.11	-15.92	28.73	1223
B-03R	6/15/2026 10:20:53 AM	-0.68	-0.68	2.3	2.3	0.537	0.537	-15.11	-15.22	28.76	1221
B-05	6/17/2026 1:59:31 PM	-0.18	-0.16	5.2	5.3	0.166	0.167	-15.39	-15.40	28.64	1233
B-06	6/15/2026 2:05:25 PM	-0.31	-0.32	17.5	17.3	0.249	0.245	-14.88	-14.89	28.77	1220
B-07R	6/15/2026 1:36:53 PM	-0.36	-0.41	7.1	6.9	5.227	4.929	-13.65	-12.79	28.77	1209
B-08	6/17/2026 1:50:41 PM	-0.14	-0.13			0.093	0.096	-15.54	-15.54	28.65	1223
B-09	6/15/2026 1:42:59 PM	-0.18	-0.17			0.183	0.178	-15.25	-15.29	28.77	1210
B-10	6/15/2026 1:50:23 PM	-0.20	-0.15			0.176	0.134	-15.20	-15.04	28.78	1222
B-11	6/15/2026 2:15:52 PM	-0.27	-0.25	5.4	5.1	0.593	0.528	-15.20	-15.05	28.84	1165
B-12	6/15/2026 10:25:47 AM	-0.23	-0.24	0.0	0.0	0.000	0.000	-15.20	-15.48	28.74	1209
B-13	6/15/2026 10:31:45 AM	-0.23	-0.21	32.2	30.1	0.209	0.182	-15.75	-16.15	28.77	1207
B-14	6/17/2026 2:14:38 PM	-0.09	-0.09	1.6	1.6	0.280	0.283	-15.70	-15.71	28.74	1128
C-03	6/12/2026 11:19:19 AM	-18.42	-19.05	0.0	0.0					28.71	1201
C-07	6/29/2026 8:47:04 AM	-16.17	-16.29			16.366	16.490	-16.15	-16.32	28.69	1190
C-08	6/17/2026 3:11:40 PM	-16.24	-16.22			16.166	16.169	-16.11	-16.13	28.67	1208
C-10	6/1/2026 10:50:14 AM	-14.56	-14.65	0.0	0.0					28.7	1207
C-11	6/1/2026 10:25:20 AM	-13.53	-13.41	0.0	0.0	-0.008	0.030			28.7	1194
C-12	6/1/2026 11:10:05 AM	-10.24	-10.24	8.4	7.8	0.434	0.380	-11.05	-11.30	28.76	1224
C-15	6/1/2026 11:00:26 AM	-10.92	-6.20	13.9	11.5	0.437	0.295	-10.83	-10.85	28.75	1232
C-15	6/1/2026 11:01:35 AM	-4.88	-4.83	10.4	10.1	0.243	0.230	-10.84	-10.83	28.76	1226
C-17B	6/15/2026 10:20:29 AM	-10.16	-10.19	0.0	0.0					28.78	1207
C-18	6/15/2026 10:33:37 AM	-11.41	-10.95	0.0	0.0					28.77	1230

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
C-19	6/15/2026 10:26:35 AM	-11.04	-11.12	0.0	0.0					28.77	1220
C-20	6/15/2026 10:30:07 AM	-11.25	-11.24	0.0	0.0					28.77	1201
C-24	6/15/2026 10:23:39 AM	-1.96	-1.86	0.0	0.0	1.760	1.758			28.77	1220
C-25	6/15/2026 10:14:32 AM	-5.49	-5.36	0.0	0.0	5.387	5.046			28.78	1247
C-26	6/15/2026 10:11:03 AM	-10.06	-10.00	0.0	0.0		9.922			28.78	1194
C-27	6/1/2026 11:07:13 AM	-3.87	-4.66			0.196	0.233	-10.83	-10.92	28.75	1230
C-28	6/1/2026 10:21:01 AM	-13.25	-13.22	0.0	0.0	-0.045	-0.041			28.68	1234
C-29	6/1/2026 10:34:31 AM	-10.27	-10.22	0.0	0.0					28.71	1191
C-30	6/17/2026 2:55:29 PM	-4.90	-4.90	6.4	6.5	0.270	0.276	-15.80	-15.73	28.63	1243
CV-02	6/12/2026 11:43:37 AM	-0.37	-0.38	0.0	0.0	-0.088	-0.076	-10.78		28.64	1240
CV-03	6/12/2026 11:40:58 AM	-6.36	-6.32	15.4	16.0	1.389	1.506	-11.31		28.65	1198
CV-04	6/12/2026 11:38:00 AM	-1.93	-1.98	18.8	18.1	0.095	0.088			28.66	1204
CV-05	6/15/2026 12:39:47 PM	-17.55	-18.18	9.0	8.9	1.757	1.717	-17.43	-18.05	28.77	1213
CV-06	6/10/2026 2:24:10 PM	-11.66	-11.69	3.6	3.6	0.082	0.081	-13.82	-13.77	28.54	1217
CV-108-52	6/2/2026 8:10:00 AM										
CV-108-52	6/2/2026 8:10:00 AM										
CV-108-52	6/2/2026 8:18:48 AM	-10.49	-10.56			1.142	1.214	-10.43	-10.64	28.67	1281
CV-108-52	6/16/2026 7:54:36 AM	-1.15	-1.24			0.077	0.182	-1.00	-0.68	28.66	1280
CV-113	6/4/2026 7:45:00 AM										
CV-113	6/4/2026 7:45:00 AM										
CV-113	6/5/2026 10:19:11 AM	-0.91	-0.89	0.8	0.6	0.004	0.002	-7.82	-7.76	28.45	1328
CV-113	6/17/2026 12:35:29 PM	-0.81	-0.77	2.4	1.9	0.035	0.023	-8.26	-8.27	28.56	1335
CV-113	6/19/2026 12:51:33 PM	-1.75	-2.15	0.5	1.9	0.002	0.022	-8.22	-7.84	28.64	1325
CV-114	6/1/2026 9:43:10 AM	-3.88	-3.93			3.931	3.936	0.34	0.34	28.57	1356

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-114	6/1/2026 9:44:20 AM	-4.20	-3.98			4.269	3.965	0.34	0.34	28.58	1357
CV-114	6/1/2026 9:50:00 AM										
CV-114	6/1/2026 9:50:00 AM										
CV-114	6/8/2026 9:22:28 AM	-5.45	-5.56			5.400	5.568	-5.21	-5.38	28.5	1342
CV-114	6/15/2026 8:40:00 AM										
CV-114	6/15/2026 8:40:00 AM										
CV-114	6/15/2026 8:49:54 AM	-1.31	-1.24			1.335	1.235	-3.55	-3.92	28.64	1367
CV-114	6/22/2026 8:59:44 AM	-3.55	-3.49			3.544	3.537	-3.54	-3.63	28.56	1351
CV-114	6/29/2026 9:16:56 AM	-4.45	-4.51			4.526	4.500	0.04	0.06	28.52	1349
CV-1424	6/3/2026 12:24:43 PM	-2.83	-3.48	18.6	22.8	2.184	3.290	-13.08	-13.00	28.6	1398
CV-1424	6/19/2026 10:08:12 AM	-4.90	-4.92	31.6	32.3	6.347	6.655	-24.15	-24.42	28.58	1405
CV-1532A	6/11/2026 10:55:34 AM	-2.99	-2.97	0.0	0.0	5.563	2.519	-5.86		28.57	1316
CV-1532A	6/12/2026 10:00:41 AM	-3.78	-3.68	0.0	0.0	3.571	3.478	-5.97		28.63	1257
CV-1532A	6/16/2026 8:55:00 AM										
CV-1532A	6/16/2026 8:55:00 AM										
CV-1532A	6/17/2026 10:11:24 AM	-5.04	-5.03			5.254	5.174	-5.22	-4.80	28.59	1278
CV-1532A	6/17/2026 10:11:46 AM	-5.03	-5.03			5.223	5.151	-2.53	-3.72	28.59	1284
CV-1532A	6/17/2026 1:12:53 PM										
CV-1534A-P	6/3/2026 10:00:00 AM										
CV-1534A-P	6/3/2026 10:01:37 AM	1.86	3.60			0.000	0.000	0.23	0.25	28.66	1288
CV-1534A-P	6/3/2026 10:04:58 AM	2.34	2.81			0.000	0.000	0.22	0.20	28.66	1287
CV-1534A-P	6/10/2026 10:19:33 AM	-3.09	-3.25			2.664	2.893	0.67	0.67	28.55	1307
CV-1534A-P	6/17/2026 9:37:43 AM	-4.24	-3.91			4.133	3.788	0.34	0.34	28.6	1285

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-1535	6/2/2026 8:13:51 AM	-1.49	-1.22			0.240	0.191	-11.75	-11.57	28.62	1314
CV-1535	6/15/2026 10:05:00 AM										
CV-1535	6/15/2026 10:05:00 AM										
CV-1535	6/16/2026 7:47:10 AM	-0.51	-0.50			0.051	0.053	-8.42	-8.21	28.63	1300
CV-1601D	6/1/2026 10:26:12 AM	-0.87	-0.80	11.2	10.4	2.628	2.237	-13.38		28.51	1316
CV-1601D	6/17/2026 11:48:50 AM	-1.05	-1.05	10.8	10.8	2.486	2.486	-16.06	-16.05	28.63	1318
CV-1601S	6/1/2026 10:23:27 AM	-0.90	-0.81	3.1	2.7	0.192	0.148	-13.65		28.51	1296
CV-1601S	6/17/2026 11:45:15 AM	-0.72	-1.00	3.5	7.5	0.253	1.181	-16.06	-16.27	28.65	1323
CV-1604	6/3/2026 11:55:24 AM	-1.21	-1.07	2.9	3.2	0.181	0.218	-15.37	-15.31	28.64	1290
CV-1701D	6/3/2026 9:34:02 AM	-1.05	-0.45	0.4	0.3	0.035	0.030	-3.79	-5.01	28.63	1297
CV-1701S	6/3/2026 9:28:58 AM	-2.53	-1.51	6.3	5.6	0.263	0.205	-15.43	-15.40	28.64	1289
CV-1701S	6/3/2026 9:29:59 AM	-1.17	-1.17	4.9	4.9	0.159	0.158	-15.50	-15.45	28.63	1291
CV-1901	6/1/2026 2:11:40 PM	-0.71	-0.70	1.0	1.4	0.022	0.039	-7.74	-7.56	28.52	1332
CV-1901	6/17/2026 9:45:56 AM	-2.52	-0.71	0.9	0.9	0.016	0.018	-7.42	-7.85	28.58	1333
CV-1902A	6/3/2026 9:06:07 AM	-5.62	-2.24			5.703	2.251	0.01	0.08	28.6	1325
CV-1902A	6/3/2026 9:06:48 AM	-2.25	-2.09			2.318	2.113	0.04	0.00	28.61	1326
CV-1902A	6/3/2026 9:10:00 AM										
CV-1902A	6/10/2026 9:19:44 AM	-4.17	-4.32			4.166	4.223	-8.19	-8.46	28.51	1329
CV-1902A	6/12/2026 8:25:30 AM										
CV-1902A	6/16/2026 9:20:00 AM										
CV-1902A	6/16/2026 9:20:00 AM										
CV-1902A	6/17/2026 8:55:02 AM	-2.97	-2.99			2.966	2.999	-6.51	-6.65	28.57	1330
CV-1902A	6/24/2026 1:28:33 PM	-3.27	-3.23			3.281	3.247	-5.52	-5.63	28.6	1323
CV-1905	6/4/2026 8:18:33 AM	-4.29	-4.49	11.8	13.3	0.887	1.126	-15.51	-15.63	28.43	1389
CV-1905	6/8/2026 12:30:27 PM										
CV-1905	6/9/2026 12:51:17 PM	-4.50	-5.11	13.9	15.7	1.232	1.593	-15.32	-14.78	28.45	1397
CV-1905	6/16/2026 11:18:39 AM										
CV-1905	6/16/2026 11:19:38 AM										
CV-1905	6/16/2026 11:21:07 AM										
CV-1905	6/16/2026 12:30:54 PM										
CV-2001	6/6/2026 7:44:37 AM										
CV-2001	6/10/2026 8:24:20 AM	-10.14	-9.42	18.5	16.4	0.432	0.340	-10.88	-11.03	28.53	1262

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-2001	6/10/2026 3:52:07 PM										
CV-2001	6/10/2026 3:52:18 PM										
CV-2001	6/16/2026 8:10:00 AM										
CV-2001	6/16/2026 8:10:00 AM										
CV-2001	6/17/2026 8:30:39 AM	-6.99	-6.71	24.5	23.4	0.757	0.686	-7.54	-6.76	28.59	1275
CV-2001	6/18/2026 2:34:40 PM										
CV-2001	6/18/2026 2:34:54 PM										
CV-2001	6/19/2026 12:17:40 PM										
CV-2001	6/24/2026 1:53:55 PM										
CV-2001	6/30/2026 1:20:37 PM										
CV-2001	6/30/2026 1:20:54 PM										
CV-2002	6/2/2026 8:20:00 AM										
CV-2002	6/2/2026 8:20:00 AM										
CV-2002	6/3/2026 9:45:00 AM										
CV-2002	6/3/2026 9:49:56 AM	0.21	-1.44	10.1	20.1	0.303	1.219	-2.91	-4.77	28.67	1275
CV-2002	6/3/2026 9:50:58 AM	-2.01	-1.81	29.4	24.8	2.616	1.865	-4.70	-2.86	28.66	1276
CV-2002	6/10/2026 1:36:51 PM	-7.54	-8.29	49.6	51.8	7.660	8.372	-8.99	-9.38	28.56	1273
CV-2002	6/19/2026 3:46:32 PM	-6.21	-3.27	0.0	0.0	-5.975	-2.955	-6.80		28.57	1207
CV-2002	6/19/2026 3:47:45 PM	-2.80	-2.02	0.0	0.0	-2.608	-1.629	-6.61		28.57	1194
CV-2003	6/2/2026 8:25:55 AM	-0.71	-0.71	2.0	2.0	0.421	0.426	-10.87	-10.94	28.66	1279
CV-2003	6/2/2026 8:27:03 AM	-0.59	-0.59	1.9	1.9	0.400	0.385	-10.12	-9.88	28.65	1283
CV-2003	6/16/2026 7:56:51 AM	-0.20	-0.23	2.6	2.3	0.708	0.546	-1.31	-1.08	28.67	1281
CV-2006	6/3/2026 9:12:33 AM	-4.40	-4.52	11.1	9.1	0.180	0.121	-7.30	-7.39	28.58	1319
CV-2006	6/3/2026 9:20:00 AM										
CV-2006	6/10/2026 9:32:53 AM	-5.77	-4.95	11.8	10.3	0.207	0.156	-9.65	-9.41	28.51	1330
CV-2006	6/17/2026 8:49:42 AM	-3.70	-3.71	25.2	24.9	0.930	0.910	-7.75	-7.75	28.57	1330
CV-2006	6/24/2026 1:42:38 PM	-1.89	-1.77	4.7	9.5	0.032	0.133	-6.91	-7.47	28.6	1329
CV-2007	6/4/2026 8:55:00 AM										
CV-2007	6/4/2026 8:55:00 AM										
CV-2007	6/4/2026 10:45:16 AM	-0.14	-0.12	5.2	3.7	0.071	0.037	-8.35	-8.90	28.42	1383
CV-2007	6/5/2026 10:16:34 AM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-2007	6/23/2026 10:08:32 AM	-1.20	-1.00	9.6	8.3	0.252	0.188	-10.13	-9.10	28.62	1394
CV-2008	6/4/2026 1:53:28 PM	-1.44	-1.48	8.5	5.9	0.453	0.219	-4.86	-4.93	28.41	1373
CV-2008	6/5/2026 1:00:43 PM										
CV-2008	6/23/2026 9:59:12 AM	-4.80	-3.53	10.1	15.1	0.639	1.412	-5.61	-5.35	28.62	1383
CV-2009	6/23/2026 10:05:54 AM										
CV-2009	6/25/2026 9:27:32 AM	-5.16	-3.78	27.2	19.0	1.004	0.486	-8.26	-8.42	28.51	1381
CV-2009	6/25/2026 9:43:11 AM	-3.10	-2.71	17.5	14.7	0.411	0.289	-8.22		28.54	1385
CV-2009	6/25/2026 9:45:41 AM	-1.62	-0.97	5.0	13.5	0.034	0.244	-8.43		28.54	1371
CV-2009A	6/4/2026 7:11:53 AM										
CV-2009A	6/4/2026 7:37:11 AM										
CV-2009A	6/4/2026 8:22:33 AM										
CV-2009A	6/8/2026 11:36:43 AM	-0.98	-0.78	6.7	5.0	1.006	0.565	-7.11		28.39	1486
CV-2010	6/2/2026 11:42:01 AM	-15.21	-14.86	43.6	42.6	2.426	2.327	-15.26	-13.88	28.63	1362
CV-2010	6/16/2026 1:15:18 PM										
CV-2010A	6/2/2026 11:38:03 AM	-14.20	-14.19	9.5	14.1	0.263	0.526	-16.05	-15.57	28.63	1363
CV-2010A	6/2/2026 11:38:57 AM	-14.19	-14.09	12.6	6.3	0.459	0.116	-15.86	-16.09	28.63	1366
CV-2011	6/2/2026 12:12:48 PM	-10.59	-10.60	22.4	22.8	0.681	0.707	-15.25	-16.32	28.64	1348
CV-2011A	6/4/2026 8:34:54 AM	-6.73	-6.77	17.3	28.2	0.084	0.222	-9.41	-9.51	28.51	1332
CV-2011A	6/8/2026 2:38:46 PM	-4.00	-4.02	43.2	23.0	0.518	0.146	-5.08	-5.12	28.55	1323
CV-2011A	6/17/2026 2:55:43 PM	-6.30	-6.32	41.8	49.7	0.491	0.693	-12.86	-12.88	28.53	1330
CV-2011A	6/29/2026 1:24:17 PM	-4.78	-0.64	28.6	20.4	0.560	0.283	-13.08	-13.26	28.54	1341
CV-2011A	6/29/2026 1:35:03 PM	-0.10	-0.60	20.2	20.3	1.176	1.189	-13.05	-13.02	28.54	1343
CV-2011A	6/29/2026 1:37:30 PM	-0.49	-0.51	20.3	20.5	1.190	1.205	-13.01	-13.08	28.54	1332
CV-2011A	6/29/2026 3:02:00 PM	-0.39	-3.15	37.7	76.7	0.394	1.646	-1.81	-13.45	28.49	1337
CV-2011A	6/29/2026 3:04:06 PM	-3.76	-3.79	81.9	78.2	1.879	1.714	-13.45	-13.39	28.49	1337

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-2012	6/15/2026 11:50:00 AM	-10.10	-3.37	11.2	8.3	0.173	0.091	-11.19	-13.18	28.71	1330
CV-2012	6/15/2026 11:51:03 AM	-2.88	-2.86	9.5	11.9	0.121	0.191	-11.47	-10.16	28.74	1346
CV-2012	6/18/2026 1:09:41 PM										
CV-2201-PLF	6/2/2026 7:48:50 AM	-7.81	-7.81			7.769	7.870	-9.90	-9.14	28.63	1352
CV-2201-PLF	6/17/2026 8:46:18 AM	-3.11	-3.25			3.050	3.191	-4.40	-4.66	28.6	1360
CV-2204-PLF	6/1/2026 1:17:53 PM	-5.58	-5.75			5.686	5.873	-0.13	-0.13	28.56	1352
CV-2204-PLF	6/1/2026 1:25:00 PM										
CV-2204-PLF	6/1/2026 1:25:00 PM										
CV-2204-PLF	6/8/2026 1:18:27 PM	-7.93	-7.91			8.020	7.994	0.26	0.27	28.51	1359
CV-2204-PLF	6/15/2026 9:45:45 AM	-1.15	-1.22			1.143	1.216	0.34	0.34	28.64	1365
CV-2204-PLF	6/22/2026 10:24:57 AM	-4.28	-4.94			4.236	4.990	0.36	0.38	28.55	1361
CV-2204-PLF	6/30/2026 8:26:20 AM	-8.22	-6.47			8.449	6.583	0.00	0.07	28.55	1355
CV-2205	6/2/2026 1:19:30 PM	-1.41	-1.14	33.6	28.6	0.291	0.207	-16.10	-16.25	28.59	1373
CV-2205	6/26/2026 10:37:39 AM										
CV-2207	6/8/2026 11:43:16 AM	-0.66	-0.64	7.9	7.6	0.017	0.015	-12.14		28.4	1378
CV-2208A	6/8/2026 10:08:38 AM	-2.70	-2.69	2.8	6.5	0.002	0.011	-7.71	-7.79	28.49	1335
CV-2301	6/2/2026 2:24:23 PM	-3.74	-3.69			3.722	3.665	-11.07	-11.02	28.62	1339
CV-2301	6/2/2026 2:25:00 PM										
CV-2301	6/2/2026 2:25:00 PM										
CV-2301	6/3/2026 7:00:00 AM										
CV-2301	6/3/2026 7:00:00 AM										
CV-2301	6/9/2026 1:50:33 PM	-3.60	-3.60			3.571	3.516	-10.21	-10.54	28.53	1348
CV-2301	6/12/2026 9:50:08 AM										
CV-2301	6/16/2026 1:36:56 PM	-7.42	-5.57			7.417	5.527	-8.02	-8.30	28.57	1342
CV-2301	6/16/2026 1:39:12 PM	-2.78	-2.73			2.731	2.687	-7.78	-7.79	28.54	1344
CV-2301	6/23/2026 2:37:21 PM	-0.03	-1.40			0.000	1.388	-4.91	-4.79	28.6	1345
CV-2301	6/23/2026 2:39:33 PM	-2.23	-2.18			2.171	2.129	-6.13	-6.23	28.6	1344
CV-2301	6/23/2026 3:00:42 PM	-3.17	-3.20			3.130	3.095	0.13	0.00	28.6	1349
CV-2301	6/24/2026 1:34:16 PM	3.95	-0.10			0.000	0.128	0.20	-7.61	28.59	1348

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-2301	6/24/2026 1:35:48 PM	-0.06	-0.04			0.004	0.006	-7.81	-7.85	28.59	1347
CV-2301	6/30/2026 10:24:56 AM	-9.73	-2.36			10.174	2.363	-13.28	-13.17	28.56	1350
CV-2301	6/30/2026 10:28:52 AM	-0.33	-1.26			0.319	1.288	-12.85	-13.01	28.57	1351
CV-2301	6/30/2026 10:30:41 AM	-1.07	-1.06			1.077	1.083	-13.16	-11.81	28.56	1350
CV-2302	6/3/2026 7:10:00 AM										
CV-2302	6/3/2026 7:10:00 AM										
CV-2302	6/3/2026 9:51:38 AM	-7.77	-7.81			8.093	8.117	-7.71	-7.67	28.56	1340
CV-2302	6/16/2026 9:54:51 AM	-6.81	-5.57			7.113	5.805	-6.42	-5.46	28.62	1339
CV-2302	6/25/2026 1:56:10 PM										
CV-2303	6/2/2026 10:35:06 AM	-3.48	-3.72			3.380	3.719	-2.92	-3.15	28.63	1361
CV-2303	6/2/2026 10:40:00 AM										
CV-2303	6/2/2026 10:40:00 AM										
CV-2303	6/3/2026 7:15:00 AM										
CV-2303	6/3/2026 7:15:00 AM										
CV-2303	6/5/2026 9:12:02 AM										
CV-2303	6/9/2026 9:49:45 AM	6.05	6.41			0.000	0.000	5.24	5.22	28.51	1388
CV-2303	6/9/2026 9:50:35 AM	6.01	6.36			0.000	0.000	5.50	5.33	28.5	1388
CV-2303	6/16/2026 9:48:16 AM	4.31	4.32			0.000	0.000	6.55	6.54	28.6	1350
CV-2303	6/16/2026 9:50:23 AM	2.87	2.74			0.000	0.000	6.02	5.81	28.6	1350
CV-2303	6/23/2026 10:25:28 AM	-0.66	-0.66			0.618	0.606	-1.62	-1.60	28.64	1357
CV-2303	6/29/2026 9:39:04 AM	-3.73	-3.75			3.652	3.677	-4.25	-4.28	28.58	1359
CV-2304	6/2/2026 2:13:16 PM	-9.71	-9.73			0.000	0.000	-9.62	-9.58	28.65	1340
CV-2304	6/2/2026 2:15:00 PM										
CV-2304	6/2/2026 2:15:00 PM										
CV-2304	6/9/2026 1:09:40 PM	-8.97	-8.75			9.148	8.972	-9.03	-9.07	28.54	1365

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-2304	6/16/2026 1:08:11 PM	-7.67	-7.83			7.745	7.800	-8.20	-8.17	28.58	1346
CV-2304	6/16/2026 2:57:49 PM	-8.13	-8.36			8.189	8.348	-8.58	-8.65	28.57	1362
CV-2304	6/16/2026 2:58:50 PM	-8.59	-8.55			8.647	8.617	-9.03	-9.00	28.57	1359
CV-2304	6/23/2026 2:09:03 PM	-6.50	-6.76			6.736	7.093	-7.23	-7.41	28.6	1340
CV-2304	6/29/2026 12:19:53 PM	-9.61	-9.45			9.569	9.458	-9.53	-9.14	28.58	1344
CV-2305	6/2/2026 2:54:55 PM	-10.68	-10.74			10.635	10.691	-11.54	-11.60	28.58	1371
CV-2305	6/2/2026 3:00:00 PM										
CV-2305	6/2/2026 3:00:00 PM										
CV-2305	6/11/2026 9:25:45 AM	-8.55	-8.50			8.861	8.760	-8.91	-8.81	28.47	1412
CV-2305	6/12/2026 8:25:00 AM										
CV-2305	6/12/2026 8:25:00 AM										
CV-2305	6/17/2026 1:34:44 PM	-10.50	-10.32			10.399	10.254	-10.94	-10.81	28.52	1394
CV-2305	6/24/2026 8:18:10 AM	-11.16	-11.15			11.556	11.481	-11.79	-11.79	28.57	1393
CV-2306	6/1/2026 10:56:19 AM	-6.80	-6.44			6.868	6.727	0.67	0.67	28.57	1363
CV-2306	6/1/2026 11:00:00 AM										
CV-2306	6/1/2026 11:00:00 AM										
CV-2306	6/8/2026 10:21:46 AM	-8.02	-7.92			7.949	7.947	0.34	0.36	28.51	1363
CV-2306	6/22/2026 10:15:40 AM	-6.12	-6.07			6.597	6.585	0.36	0.34	28.53	1357
CV-2306	6/30/2026 8:15:59 AM	-10.07	-4.54			10.283	4.395	0.00	0.00	28.55	1354
CV-2306	6/30/2026 8:18:07 AM	-3.72	-3.54			3.586	3.645	0.00	0.00	28.53	1355
CV-2308-PLF	6/2/2026 7:55:47 AM	-8.82	-8.82			8.872	8.836	-11.38	-10.79	28.63	1362
CV-2308-PLF	6/2/2026 7:57:50 AM	-8.84	-8.84			8.887	8.879	-11.06	-11.03	28.63	1367
CV-2308-PLF	6/17/2026 8:50:24 AM	-7.87	-7.85			7.971	7.861	-9.36	-9.48	28.59	1367
CV-2308-PLF	6/17/2026 8:51:38 AM	-7.83	-7.85			7.819	7.866	-9.32	-9.42	28.59	1363

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-2310-PLF	6/2/2026 1:53:08 PM	-7.03	-7.58			7.039	7.569	0.04	0.13	28.62	1354
CV-2310-PLF	6/2/2026 2:00:00 PM										
CV-2310-PLF	6/2/2026 2:00:00 PM										
CV-2310-PLF	6/9/2026 10:24:42 AM	-7.07	-7.11			7.325	7.325	0.34	0.34	28.51	1367
CV-2310-PLF	6/16/2026 10:11:01 AM	-5.38	-5.30			5.997	5.918	0.35	0.35	28.6	1356
CV-2310-PLF	6/23/2026 10:49:46 AM	-7.25	-7.25			7.673	7.723	0.38	0.36	28.66	1356
CV-2310-PLF	6/29/2026 10:01:07 AM	-8.35	-8.37			8.571	8.592	0.08	0.10	28.56	1369
CV-2311	6/2/2026 9:00:00 AM										
CV-2311	6/2/2026 9:18:43 AM	-6.43	-6.40			6.498	6.446	-10.32	-10.63	28.58	1378
CV-2311	6/2/2026 9:20:00 AM										
CV-2311	6/9/2026 9:07:08 AM	-4.56	-4.69			4.549	4.725	-10.42	-9.74	28.48	1373
CV-2311	6/16/2026 9:00:16 AM	-2.97	-3.08			2.976	3.021	-8.11	-8.00	28.6	1372
CV-2311	6/23/2026 9:40:13 AM	-2.01	-2.16			2.002	2.161	0.34	0.34	28.63	1368
CV-2311	6/30/2026 9:24:01 AM	-7.08	-3.38			7.465	3.354	-13.31	-9.89	28.53	1378
CV-2311	6/30/2026 9:25:40 AM	-2.53	-2.45			2.513	2.461	-9.45	-9.68	28.56	1379
CV-2312	6/2/2026 2:45:00 PM										
CV-2312	6/2/2026 2:45:00 PM										
CV-2312	6/2/2026 2:47:24 PM	-4.82	-5.56	38.9	44.0	4.532	5.831	-8.21	-8.32	28.6	1374
CV-2312	6/10/2026 2:01:28 PM	-6.29	-6.86	46.0	47.2	6.403	6.781	-7.52	-8.06	28.44	1384
CV-2312	6/11/2026 7:30:00 AM										
CV-2312	6/11/2026 7:30:00 AM										
CV-2312	6/24/2026 10:00:40 AM	-8.66	-8.76	55.2	55.4	9.264	9.333	-9.04	-9.09	28.59	1379
CV-2312	6/30/2026 1:42:08 PM	-23.00	-19.65	84.7	79.3	23.320	20.121	-11.08	-11.22	28.5	1373
CV-2312	6/30/2026 1:48:19 PM	-10.55	-4.78	59.3	39.7	10.824	4.736	-10.99	-11.24	28.49	1374

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-2312	6/30/2026 1:49:32 PM	-6.21	-6.32	46.2	46.3	6.466	6.485	-11.73	-11.83	28.49	1374
CV-2314	6/3/2026 1:41:34 PM	-7.67	-7.61			7.581	7.549	-11.47	-11.47	28.57	1384
CV-2314	6/3/2026 1:55:00 PM										
CV-2314	6/10/2026 2:47:57 PM	-12.32	-8.98			12.413	9.185	-12.97	-12.69	28.43	1382
CV-2314	6/10/2026 2:50:12 PM	-5.99	-5.93			6.142	6.220	-12.53	-14.15	28.43	1380
CV-2314	6/12/2026 8:30:00 AM										
CV-2314	6/12/2026 8:30:00 AM										
CV-2314	6/17/2026 2:43:32 PM	-4.99	-2.47			5.050	2.478	-12.37	-12.36	28.46	1373
CV-2314	6/17/2026 2:44:23 PM	-3.43	-3.11			3.452	3.335	-12.29	-12.38	28.46	1373
CV-2314	6/19/2026 11:52:39 AM	-9.71	-11.07	0.0	0.0	9.371		-14.22		28.53	1450
CV-2314	6/19/2026 11:54:02 AM	-10.77	-10.79	0.0	0.0			-14.71		28.53	1427
CV-2314	6/24/2026 9:02:40 AM	-9.70	-9.77			10.255	10.449	-13.33	-13.14	28.6	1378
CV-2314	6/30/2026 2:06:51 PM	-11.21	-5.39			11.524	5.615	-15.36	-15.30	28.49	1385
CV-2314	6/30/2026 2:08:30 PM	-5.17	-5.05			5.472	5.329	-15.56	-15.31	28.49	1385
CV-2315	6/1/2026 1:23:23 PM	-3.28	-3.25			3.255	3.223	-4.45	-4.39	28.55	1370
CV-2315	6/1/2026 1:30:00 PM										
CV-2315	6/1/2026 1:30:00 PM										
CV-2315	6/3/2026 7:25:00 AM										
CV-2315	6/3/2026 7:25:00 AM										
CV-2315	6/8/2026 1:23:19 PM	-4.39	-4.39			4.413	4.413	-5.51	-5.51	28.47	1382
CV-2315	6/15/2026 9:49:34 AM	-3.46	-3.25			3.442	3.284	-5.05	-4.76	28.6	1380
CV-2315	6/22/2026 1:34:17 PM	-1.42	-1.91			1.396	1.962	0.29	0.32	28.49	1373
CV-2315	6/25/2026 2:43:59 PM										
CV-2315	6/30/2026 2:44:21 PM	-6.45	-6.66			6.790	7.041	-7.93	-8.04	28.49	1378
CV-2316	6/4/2026 10:21:45 AM	-1.36	-0.80	7.6	5.6	0.038	0.021	-5.18	-5.39	28.41	1402
CV-2316	6/4/2026 11:20:47 AM										
CV-2316	6/4/2026 12:46:18 PM										
CV-2316	6/17/2026 8:51:12 AM										
CV-2316	6/23/2026 9:53:03 AM	-0.48	-0.49	27.0	27.2	0.486	0.493	-6.45	-6.31	28.58	1402

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-2316	6/23/2026 9:54:14 AM	-0.65	-0.64	31.5	31.5	0.660	0.664	-6.50	-6.61	28.59	1413
CV-2316	6/23/2026 3:11:49 PM	-0.26	-1.83	19.9	52.2	0.265	1.829	-4.04	-3.70	28.53	1395
CV-2316	6/23/2026 3:12:16 PM	-1.82	-1.83	51.9	51.9	1.809	1.810	-3.73	-3.71	28.53	1396
CV-2319	6/12/2026 1:24:57 PM	-5.12	-2.25			0.000	0.000	-16.84	-18.82	28.41	1399
CV-2319	6/12/2026 1:27:27 PM	-1.92	-1.97	110.8	110.6	3.331	3.323	-18.85	-18.36	28.41	1401
CV-2319	6/15/2026 1:14:28 PM	-1.50	-2.29			0.000	0.000	-17.75	-18.09	28.54	1409
CV-2319	6/15/2026 1:16:00 PM	-2.66	-2.72			0.184	0.000	-17.65	-18.23	28.55	1410
CV-2319	6/21/2026 2:21:21 PM	-6.61	-6.59	115.4	115.8	3.728	3.757	-16.05	-15.75	28.42	1396
CV-2321	6/3/2026 9:02:48 AM	-6.98	-5.63	25.2	18.6	0.431	0.234	-14.13	-15.58	28.59	1416
CV-2321	6/3/2026 9:04:13 AM	-5.75	-5.71	22.2	23.4	0.333	0.371	-16.17	-15.40	28.59	1398
CV-2321	6/22/2026 8:15:36 AM	-2.75	-1.62	14.8	11.8	0.148	0.094	-15.14	-16.64	28.54	1399
CV-2321	6/22/2026 8:17:15 AM	-1.54	-1.48	12.0	11.4	0.097	0.087	-16.80	-15.83	28.55	1393
CV-2322	6/4/2026 8:16:40 AM	-7.42	-7.43			7.522	7.644	-7.43	-7.45	28.51	1381
CV-2322	6/29/2026 10:13:50 AM	-9.40	-9.40			9.369	9.387	-9.40	-9.40	28.49	1368
CV-2322	6/29/2026 10:17:01 AM	-9.44	-9.74			9.435	9.739	-9.38	-9.73	28.51	1359
CV-2324	6/2/2026 12:01:10 PM	-1.74	-1.74	18.9	18.6	0.230	0.222	-17.88	-17.88	28.59	1381
CV-2326	6/4/2026 12:14:04 PM	-7.07	-7.15			7.016	7.073	0.00	0.00	28.48	1381
CV-2326	6/4/2026 12:15:55 PM	-7.10	-7.05			7.042	7.086	0.00	0.00	28.48	1377
CV-2326	6/11/2026 10:04:53 AM	-7.48	-7.05			7.757	7.198	0.62	0.63	28.47	1362
CV-2326	6/16/2026 9:13:00 AM	-7.09	-7.22			7.596	7.688	0.34	0.34	28.6	1396
CV-2326	6/23/2026 10:15:57 AM	-6.98	-7.41			7.531	7.873	0.34	0.29	28.62	1372
CV-2326	6/30/2026 9:30:30 AM	-9.79	-10.05			10.199	10.435	0.30	0.27	28.53	1378
CV-2327	6/3/2026 1:18:30 PM	-3.93	-3.76			3.696	3.777	-6.82	-6.72	28.59	1361

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-2327	6/3/2026 1:20:00 PM										
CV-2327	6/9/2026 2:30:10 PM	-4.03	-4.16			3.822	3.979	-6.13	-6.24	28.51	1398
CV-2327	6/16/2026 2:36:43 PM	-4.64	-4.24			4.653	4.429	-7.38	-7.03	28.53	1355
CV-2327	6/24/2026 9:35:33 AM	-5.14	-5.12			5.645	5.617	-8.42	-8.42	28.62	1355
CV-2327	6/29/2026 1:11:01 PM	-5.58	-5.57			5.676	5.665	-8.25	-8.25	28.57	1373
CV-2328	6/2/2026 2:33:14 PM	-5.72	-5.72	39.8	39.6	3.992	3.958	-9.83	-9.74	28.62	1362
CV-2328	6/2/2026 2:35:00 PM										
CV-2328	6/2/2026 2:35:00 PM										
CV-2328	6/9/2026 2:20:39 PM	-5.68	-5.68	25.7	25.7	1.674	1.674	-7.50	-7.50	28.51	1365
CV-2328	6/12/2026 8:45:00 AM										
CV-2328	6/12/2026 8:45:00 AM										
CV-2328	6/16/2026 2:19:24 PM	-3.33	-3.41	37.5	38.3	3.627	3.778	-7.60	-7.83	28.53	1370
CV-2328	6/24/2026 9:52:31 AM	-4.74	-4.72	27.6	28.5	1.941	2.069	-8.42	-8.42	28.62	1361
CV-2328	6/30/2026 1:37:04 PM	-8.11	-5.39	26.7	19.3	1.827	0.952	-11.62	-12.78	28.53	1350
CV-2328	6/30/2026 1:38:00 PM	-5.32	-5.39	19.2	21.9	0.937	1.225	-12.70	-12.67	28.52	1355
CV-2333	6/1/2026 9:34:06 AM	-4.00	-4.15			3.605	3.705	-3.40	-3.36	28.55	1367
CV-2333	6/1/2026 9:45:00 AM										
CV-2333	6/1/2026 9:45:00 AM										
CV-2333	6/3/2026 8:00:00 AM										
CV-2333	6/3/2026 8:00:00 AM										
CV-2333	6/8/2026 9:19:09 AM	-5.39	-5.72			5.360	5.595	-5.33	-5.46	28.47	1364
CV-2333	6/15/2026 8:45:46 AM	0.59	0.61			0.000	0.000	2.93	3.16	28.61	1375
CV-2333	6/15/2026 8:46:36 AM	0.53	0.48			0.000	0.000	2.98	2.69	28.6	1375
CV-2333	6/16/2026 8:27:48 AM	-3.54	-2.59			3.530	2.651	-4.88	-4.79	28.58	1356
CV-2333	6/16/2026 8:29:05 AM	-1.88	-1.91			1.843	1.582	-4.84	-4.88	28.6	1356
CV-2333	6/22/2026 8:54:06 AM	-3.36	-3.33			3.363	3.337	0.20	0.19	28.53	1364
CV-2333	6/24/2026 10:41:33 AM										
CV-2333	6/29/2026 9:12:38 AM	-4.10	-4.18			4.083	4.093	-5.20	-5.38	28.49	1364

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-2334	6/2/2026 8:24:06 AM										
CV-2334	6/3/2026 8:05:00 AM										
CV-2334	6/3/2026 8:05:00 AM										
CV-2334	6/4/2026 2:15:28 PM	-6.68	-6.66	5.2	5.2	0.076	0.075	-7.13	-7.09	28.45	1358
CV-2334	6/11/2026 9:30:32 AM										
CV-2334	6/17/2026 1:21:10 PM	-6.76	-7.05	10.4	13.7	0.305	0.532	-7.98	-8.49	28.53	1384
CV-2334	6/17/2026 1:22:09 PM	-6.38	-6.38	7.7	6.7	0.166	0.129	-7.17	-6.86	28.53	1376
CV-2334	6/18/2026 3:46:54 PM										
CV-2334	6/18/2026 3:47:04 PM										
CV-2334	6/19/2026 10:47:23 AM										
CV-2334	6/19/2026 12:10:06 PM	-7.92	-4.80	0.0	4.7	-0.027	0.082	-8.78		28.57	1289
CV-2334	6/23/2026 12:31:40 PM										
CV-2334	6/26/2026 11:23:08 AM										
CV-2334	6/26/2026 11:23:21 AM										
CV-2334	6/30/2026 11:19:30 AM										
CV-2334	6/30/2026 11:19:42 AM										
CV-2335	6/1/2026 2:02:30 PM	-3.06	-3.06			2.936	2.911	-5.84	-6.05	28.52	1344
CV-2335	6/17/2026 9:29:31 AM	-1.55	-1.56			1.539	1.557	-5.00	-5.59	28.57	1347
CV-2335	6/24/2026 7:34:08 AM										
CV-2336	6/1/2026 2:07:58 PM	-0.29	-0.27			0.198	0.169	-7.43	-7.65	28.52	1336
CV-2336	6/10/2026 3:30:15 PM										
CV-2336	6/10/2026 3:30:26 PM										
CV-2336	6/11/2026 1:32:50 PM	-6.76	-3.05			6.778	3.081	-7.21	-7.18	28.52	1330
CV-2336	6/11/2026 1:33:49 PM	-3.55	-3.46			3.564	3.485	-7.60	-7.46	28.52	1321
CV-2336	6/11/2026 2:58:42 PM										
CV-2336	6/11/2026 3:00:37 PM										
CV-2336	6/17/2026 9:40:23 AM	-6.48	-5.89			6.516	6.026	-7.54	-6.75	28.55	1342
CV-2336	6/18/2026 1:52:32 PM										
CV-2336	6/18/2026 1:52:47 PM										
CV-2336	6/18/2026 1:53:26 PM										
CV-2336	6/24/2026 6:58:14 AM										
CV-2336	6/24/2026 1:36:33 PM										
CV-2336	6/24/2026 1:36:43 PM										
CV-2336	6/26/2026 2:08:07 PM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-2336	6/26/2026 2:08:18 PM										
CV-2337	6/1/2026 2:16:10 PM	-3.99	-2.68	27.9	24.8	2.258	1.779	-6.61	-7.31	28.52	1326
CV-2337	6/3/2026 9:16:44 AM	-2.84	-2.85	30.4	30.2	2.676	2.627	-7.73	-7.73	28.58	1326
CV-2337	6/3/2026 9:25:00 AM										
CV-2337	6/10/2026 9:39:16 AM	-4.05	-4.19	28.8	32.8	2.418	3.131	-9.07	-9.07	28.48	1336
CV-2337	6/16/2026 9:15:00 AM										
CV-2337	6/16/2026 9:15:00 AM										
CV-2337	6/17/2026 8:43:10 AM	-2.51	-2.50	33.1	33.7	3.171	3.282	-9.10	-9.09	28.56	1338
CV-2337	6/24/2026 1:53:56 PM	-4.15	-4.08	27.5	25.1	2.193	1.828	-8.48	-7.81	28.6	1340
CV-2338	6/3/2026 9:09:28 AM	-2.26	-2.87			2.260	2.876	0.32	0.34	28.61	1318
CV-2338	6/3/2026 9:15:00 AM										
CV-2338	6/10/2026 9:25:38 AM	-4.96	-4.61			4.964	4.635	-4.55	-4.16	28.51	1326
CV-2338	6/17/2026 8:52:13 AM	-1.73	-1.76			1.759	1.794	-2.46	-2.49	28.57	1326
CV-2338	6/24/2026 1:31:30 PM	-0.67	-0.78			0.697	0.857	-1.14	-1.47	28.63	1317
CV-2338	6/24/2026 1:32:33 PM	-0.29	-0.70			0.278	0.674	-0.61	-1.14	28.63	1317
CV-2339	6/11/2026 9:42:14 AM	-0.88	-0.87	0.0	0.0	0.958	0.886	-6.99		28.54	1325
CV-2339	6/11/2026 9:45:19 AM	-0.58	-0.64	0.0	0.0	0.700	0.836	-6.94		28.54	1289
CV-2339	6/12/2026 8:58:58 AM	-0.52	-0.14	0.0	0.0	0.574	0.226	-5.50		28.57	1322
CV-2339	6/12/2026 9:04:45 AM	-0.30	-0.17	0.0	0.0	0.414	0.010	-5.85		28.57	1293
CV-2339	6/12/2026 9:10:50 AM	-0.19	-0.12	0.0	0.0	-0.018	0.100	-6.43		28.57	1293
CV-2339	6/18/2026 1:42:24 PM										
CV-2339	6/18/2026 1:42:35 PM										
CV-2339	6/19/2026 1:58:28 PM	-6.16	-3.45	0.0	0.0	6.459	3.635	-5.95		28.7	1237
CV-2339	6/19/2026 2:03:58 PM	-2.47	-3.66	0.0	0.0	2.836	3.791	-6.40		28.7	1283
CV-2339	6/22/2026 2:45:17 PM	-2.33	-1.22			2.400	1.219	-3.86	-4.72	28.53	1295
CV-2339	6/22/2026 2:47:20 PM	-2.50	-2.54			2.528	2.555	-4.71	-5.09	28.55	1294
CV-2339	6/23/2026 12:28:36 PM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-2339	6/24/2026 1:48:55 PM										
CV-2339	6/24/2026 1:49:06 PM										
CV-2339	6/26/2026 3:51:11 PM										
CV-2339	6/26/2026 3:51:22 PM										
CV-2341	6/6/2026 1:00:12 PM										
CV-2341	6/11/2026 9:35:24 AM	-1.12	-1.38	0.0	0.0	1.336	1.625	-6.55		28.53	1339
CV-2341	6/11/2026 3:32:00 PM	-3.06	-1.67	0.0	0.0	2.948	1.892	-7.36		28.41	1296
CV-2341	6/15/2026 10:15:00 AM										
CV-2341	6/15/2026 10:15:00 AM										
CV-2341	6/22/2026 11:40:09 AM	-1.61	-0.49			1.561	0.478	-4.35	-3.14	28.67	1317
CV-2341	6/24/2026 1:54:00 PM										
CV-2341	6/24/2026 1:54:47 PM										
CV-2341	6/25/2026 1:45:13 PM	-1.49	-1.49			1.507	1.516	-7.64	-7.87	28.62	1315
CV-2341	6/26/2026 3:49:24 PM										
CV-2341	6/26/2026 3:49:37 PM										
CV-2342A-P	6/3/2026 12:53:12 PM	-6.56	-6.69			6.422	6.428	-6.20	-6.13	28.66	1285
CV-2342A-P	6/3/2026 1:00:00 PM										
CV-2342A-P	6/10/2026 10:44:45 AM	-8.94	-9.51			9.211	9.842	0.67	0.67	28.56	1292
CV-2342A-P	6/17/2026 9:53:50 AM	-6.82	-6.38			6.946	6.511	0.06	0.08	28.59	1281
CV-2342A-P	6/17/2026 9:54:24 AM	-7.02	-6.71			7.223	6.862	0.10	0.08	28.59	1280
CV-2343	6/15/2026 9:19:39 AM	-7.81	-7.16			8.208	7.475	-8.46	-8.47	28.68	1287
CV-2343	6/15/2026 9:20:00 AM	-6.71	-6.71			7.023	7.023	-7.93	-7.74	28.68	1288
CV-2343	6/17/2026 2:09:17 PM	1.07	-1.93			0.000	1.992	0.06	-0.02	28.57	1293
CV-2343	6/17/2026 2:11:09 PM	-2.82	-2.58			2.873	2.630	0.03	0.03	28.57	1292
CV-2343	6/19/2026 11:11:56 AM	-0.53	-1.29	0.0	0.0	1.506	1.520	-5.92		28.63	1302
CV-2343	6/19/2026 11:16:28 AM	-0.87	-0.89	0.0	0.0	1.097	0.936	-5.77		28.63	1299
CV-2344	6/2/2026 8:00:00 AM										
CV-2344	6/2/2026 8:00:00 AM										
CV-2344	6/2/2026 8:40:05 AM	-10.20	-9.84			10.445	10.199	-11.35	-11.36	28.66	1289
CV-2344	6/2/2026 8:41:11 AM	-9.65	-9.46			10.081	9.873	-11.44	-11.49	28.63	1291
CV-2344	6/10/2026 10:48:47 AM	-4.99	-4.96	0.0	0.0	5.006	4.990	-10.40		28.56	1276

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-2344	6/10/2026 10:51:49 AM	-4.51	-1.72	0.0	0.0	4.383	1.764	-10.61		28.56	1276
CV-2344	6/11/2026 10:41:23 AM	3.24	-2.15			0.000	2.140	-7.35	-6.96	28.55	1289
CV-2344	6/11/2026 10:42:42 AM	-2.80	-2.59			2.798	2.575	-7.08	-7.06	28.55	1289
CV-2344	6/17/2026 9:22:23 AM	-1.47	-1.20			1.488	1.213	-7.58	-7.54	28.6	1295
CV-2345	6/2/2026 7:55:00 AM										
CV-2345	6/2/2026 7:55:00 AM										
CV-2345	6/2/2026 8:44:21 AM	-2.96	-2.96			2.932	2.931	-11.58	-11.67	28.63	1305
CV-2345	6/16/2026 8:05:13 AM	-2.06	-2.05			2.036	2.026	-8.19	-8.08	28.63	1291
CV-2346	6/2/2026 7:50:00 AM										
CV-2346	6/2/2026 7:50:00 AM										
CV-2346	6/3/2026 9:35:01 AM	-7.29	-6.28			7.366	6.377	-7.46	-7.37	28.62	1302
CV-2346	6/3/2026 9:39:13 AM	-4.58	-4.61			4.473	4.473	-7.62	-7.63	28.62	1302
CV-2346	6/3/2026 9:40:00 AM										
CV-2346	6/10/2026 9:54:27 AM	-9.26	-9.47			9.452	9.724	-10.46	-10.42	28.51	1356
CV-2346	6/17/2026 9:17:36 AM	-5.02	-3.13			5.324	3.070	-7.74	-7.42	28.6	1311
CV-2346	6/17/2026 9:19:04 AM	-1.27	-1.24			1.269	0.920	-7.12	-7.66	28.6	1311
CV-2347	6/2/2026 7:40:00 AM										
CV-2347	6/2/2026 7:40:00 AM										
CV-2347	6/2/2026 9:01:41 AM	-3.93	-3.92			3.895	3.882	-11.08	-10.87	28.63	1306
CV-2347	6/16/2026 8:17:59 AM	-2.33	-2.31			2.273	2.317	-6.90	-6.76	28.63	1300
CV-2348	6/2/2026 7:30:00 AM										
CV-2348	6/2/2026 7:30:00 AM										
CV-2348	6/2/2026 9:24:08 AM	-10.77	-10.79			11.241	11.288	0.34	0.34	28.63	1314
CV-2348	6/10/2026 1:32:39 PM	-5.84	-5.84	0.0	0.0	5.579	5.669	-9.89		28.39	1266
CV-2348	6/10/2026 1:34:08 PM	-6.11	-6.09	0.0	0.0	5.780	5.783	-10.03		28.39	1270
CV-2348	6/16/2026 8:24:15 AM	-7.90	-7.05			8.154	7.267	0.33	0.33	28.63	1301
CV-2348	6/16/2026 8:24:47 AM	-7.09	-7.05			7.240	7.303	0.33	0.33	28.63	1310
CV-2349	6/2/2026 8:30:00 AM										
CV-2349	6/2/2026 8:30:00 AM										
CV-2349	6/3/2026 10:34:57 AM	0.44	-0.19			0.000	0.104	-1.01	-1.29	28.69	1262

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-2349	6/3/2026 10:35:45 AM	-0.20	-0.59			0.000	0.502	-0.97	-1.22	28.69	1265
CV-2349	6/3/2026 10:40:00 AM										
CV-2349	6/10/2026 1:32:14 PM	-5.53	-4.35			5.593	4.449	-5.91	-5.08	28.57	1264
CV-2349	6/10/2026 1:33:11 PM	-5.11	-5.15			5.140	5.191	-6.72	-6.66	28.56	1267
CV-2349	6/17/2026 10:35:04 AM	-0.96	-1.56			0.987	1.577	-2.43	-2.28	28.62	1259
CV-2349	6/17/2026 10:35:26 AM	-2.04	-1.95			2.053	1.941	-2.82	-2.80	28.62	1261
CV-2350	6/2/2026 8:15:00 AM										
CV-2350	6/2/2026 8:15:00 AM										
CV-2350	6/2/2026 8:32:01 AM	-9.98	-8.20			10.381	8.568	-10.39	-8.60	28.67	1275
CV-2350	6/17/2026 8:33:21 AM	-7.19	-6.04			7.305	6.132	-8.13	-6.00	28.59	1285
CV-2351	6/1/2026 9:00:00 AM										
CV-2351	6/1/2026 9:00:00 AM										
CV-2351	6/1/2026 12:22:24 PM	-4.58	-4.57			4.504	4.494	-4.26	-4.25	28.7	1286
CV-2351	6/1/2026 12:24:29 PM	-4.59	-4.47			4.540	4.478	-4.61	-4.48	28.71	1284
CV-2351	6/2/2026 7:47:05 AM										
CV-2351	6/3/2026 7:58:36 AM										
CV-2351	6/4/2026 3:09:45 PM										
CV-2351	6/5/2026 10:57:36 AM										
CV-2351	6/6/2026 8:19:20 AM										
CV-2351	6/9/2026 3:12:34 PM										
CV-2351	6/9/2026 3:12:48 PM										
CV-2351	6/16/2026 8:45:00 AM										
CV-2351	6/16/2026 8:45:00 AM										
CV-2351	6/17/2026 9:15:56 AM	-1.35	-1.33			1.399	1.421	-1.24	-1.25	28.59	1291
CV-2351	6/17/2026 9:16:22 AM	-1.34	-1.37			1.234	1.236	-1.11	-1.15	28.59	1294
CV-2351	6/18/2026 2:20:44 PM										
CV-2351	6/18/2026 2:20:55 PM										
CV-2351	6/19/2026 12:43:31 PM										
CV-2351	6/26/2026 3:52:05 PM										
CV-2351	6/26/2026 3:52:20 PM										
CV-2351	6/30/2026 2:51:00 PM										
CV-2351	6/30/2026 2:52:10 PM										
CV-2352	6/1/2026 9:10:00 AM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-2352	6/1/2026 9:10:00 AM										
CV-2352	6/1/2026 12:43:45 PM	-4.04	-1.53			3.970	1.544	-4.68	-4.51	28.71	1281
CV-2352	6/1/2026 12:44:54 PM	-1.90	-1.91			1.898	1.908	-4.77	-5.01	28.71	1292
CV-2352	6/2/2026 7:48:09 AM										
CV-2352	6/3/2026 7:57:58 AM										
CV-2352	6/4/2026 3:08:51 PM										
CV-2352	6/5/2026 10:58:49 AM										
CV-2352	6/6/2026 8:19:50 AM										
CV-2352	6/9/2026 3:03:03 PM										
CV-2352	6/9/2026 3:03:33 PM										
CV-2352	6/17/2026 9:28:04 AM	-2.67	-2.52			2.647	2.508	-2.51	-2.28	28.59	1305
CV-2352	6/18/2026 2:15:09 PM										
CV-2352	6/18/2026 2:15:24 PM										
CV-2352	6/26/2026 3:52:52 PM										
CV-2352	6/26/2026 3:53:01 PM										
CV-2352	6/30/2026 2:51:05 PM										
CV-2352	6/30/2026 2:51:18 PM										
CV-2353-PLF	6/11/2026 10:42:44 AM	-5.79	-5.65	0.0	0.0	5.731	5.576	-6.41		28.56	1263
CV-2353-PLF	6/11/2026 10:46:22 AM	-5.09	-3.67	0.0	0.0	4.757	3.461	-6.39		28.56	1289
CV-2353-PLF	6/12/2026 10:14:03 AM	0.28	-0.34	0.0	0.0	0.174	0.457	-5.37		28.61	1243
CV-2353-PLF	6/12/2026 10:16:08 AM	-0.55	-0.43	0.0	0.0	0.584	0.513	-5.52		28.61	1335
CV-2353-PLF	6/12/2026 10:38:13 AM										
CV-2353-PLF	6/15/2026 8:25:00 AM										
CV-2353-PLF	6/15/2026 8:25:00 AM										
CV-2353-PLF	6/15/2026 2:58:08 PM	-6.61	-4.68			6.653	4.633	-7.20	-7.10	28.68	1297
CV-2353-PLF	6/15/2026 2:59:49 PM	-2.62	-2.67			2.375	2.527	-7.23	-7.75	28.68	1301
CV-2353-PLF	6/17/2026 9:38:30 AM	-7.05	-6.71			7.348	6.781	-7.18	-6.80	28.59	1298
CV-2353-PLF	6/17/2026 9:38:59 AM	-6.71	-6.71			6.997	6.997	-6.76	-7.09	28.59	1294
CV-2354	6/3/2026 10:45:40 AM	0.51	0.33			0.000	0.000	-2.46	-2.93	28.68	1262

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-2354	6/3/2026 10:47:46 AM	1.19	1.36			0.000	0.000	-2.01	-1.62	28.69	1260
CV-2354	6/3/2026 10:50:00 AM										
CV-2354	6/8/2026 1:27:32 PM	-3.05	-2.96			3.017	3.024	-5.59	-5.88	28.59	1257
CV-2354	6/8/2026 1:28:00 PM	-3.07	-2.95			3.110	2.917	-5.32	-5.59	28.59	1256
CV-2354	6/10/2026 1:14:12 PM	-2.72	-2.51			2.717	2.543	-5.29	-5.04	28.58	1258
CV-2354	6/15/2026 8:10:00 AM										
CV-2354	6/15/2026 8:10:00 AM										
CV-2354	6/17/2026 10:43:17 AM	-0.56	-0.53			0.563	0.551	-3.03	-2.99	28.65	1260
CV-24001	6/1/2026 1:48:34 PM	-4.08	-4.05			3.897	3.857	-5.73	-5.58	28.52	1335
CV-24001	6/17/2026 9:25:42 AM	-1.05	-1.06			1.043	1.035	-5.90	-6.39	28.54	1351
CV-24002	6/1/2026 1:41:05 PM	-0.56	-0.52			0.548	0.503	-7.30	-7.39	28.52	1349
CV-24002	6/17/2026 9:17:33 AM	-1.62	-1.62			1.617	1.622	-8.32	-8.32	28.55	1354
CV-24002	6/24/2026 8:07:06 AM										
CV-24003	6/1/2026 9:47:33 AM	-0.80	-0.80	0.9	4.2	0.000	0.010	-7.50	-7.54	28.52	1369
CV-24003	6/5/2026 9:17:13 AM	-1.35	-1.35	0.9	0.7	0.002	0.001	-8.27	-8.32	28.43	1335
CV-24003	6/17/2026 9:05:11 AM	-0.14	-0.14	2.8	2.6	0.019	0.018	-8.61	-8.57	28.54	1367
CV-24003	6/24/2026 8:19:54 AM										
CV-24004	6/1/2026 9:44:08 AM	-0.83	-0.84	2.0	3.8	0.010	0.039	-7.46	-8.44	28.52	1368
CV-24004	6/17/2026 9:00:41 AM	-0.25	-0.25	6.9	5.8	0.126	0.091	-8.75	-8.66	28.53	1369
CV-24004	6/24/2026 8:46:57 AM										
CV-24006	6/1/2026 2:36:17 PM	-1.14	-1.00	12.5	10.9	0.433	0.329	-3.94	-3.96	28.48	1362
CV-24006	6/2/2026 8:32:06 AM										
CV-24006	6/11/2026 2:54:50 PM	-0.70	-0.71	0.0	0.0	0.016	-0.389	-4.69		28.38	1342
CV-24006	6/17/2026 9:50:26 AM	-0.97	-0.99	12.9	13.5	0.463	0.504	-3.99	-4.09	28.53	1380
CV-24006	6/18/2026 3:15:55 PM										
CV-24006	6/18/2026 3:16:08 PM										
CV-24006	6/19/2026 11:31:36 AM										
CV-24006	6/24/2026 1:27:43 PM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24006	6/24/2026 1:28:01 PM										
CV-24006	6/24/2026 1:28:36 PM										
CV-24006	6/26/2026 1:33:12 PM										
CV-24006	6/26/2026 1:33:26 PM										
CV-24007	6/1/2026 2:43:27 PM	-1.09	-1.24	34.7	32.0	3.118	2.941	-5.03	-7.43	28.48	1380
CV-24007	6/2/2026 8:31:29 AM										
CV-24007	6/2/2026 9:10:01 AM	-3.52	-1.95	27.5	32.1	2.168	2.930	-9.74	-5.37	28.58	1373
CV-24007	6/2/2026 9:14:26 AM	-1.65	-1.65	33.4	33.4	3.145	3.148	-2.69	-2.69	28.58	1375
CV-24007	6/12/2026 8:23:32 AM										
CV-24007	6/15/2026 9:35:00 AM										
CV-24007	6/15/2026 9:35:00 AM										
CV-24007	6/17/2026 9:53:11 AM	-0.82	-0.82	31.6	30.7	2.846	2.679	-7.86	-7.51	28.51	1377
CV-24008	6/1/2026 9:00:00 AM										
CV-24008	6/2/2026 8:30:57 AM										
CV-24008	6/2/2026 8:58:36 AM	-10.36	-10.25	28.1	21.3	0.559	0.321	-10.26	-10.08	28.58	1369
CV-24008	6/2/2026 9:00:00 AM										
CV-24008	6/9/2026 9:03:09 AM	-11.20	-10.99	3.8	2.1	0.010	0.003	-10.97	-10.55	28.48	1375
CV-24008	6/16/2026 8:56:04 AM	-8.05	-6.32	108.2	96.5	8.407	6.644	-8.60	-8.17	28.6	1370
CV-24008	6/16/2026 8:57:09 AM	-5.07	-5.10	87.8	88.1	5.471	5.506	-8.17	-8.42	28.6	1371
CV-24008	6/23/2026 9:36:51 AM	-7.86	-7.75	107.1	106.1	8.213	8.054	-8.19	-8.08	28.61	1376
CV-24008	6/24/2026 3:50:29 PM										
CV-24008	6/30/2026 9:05:50 AM	-11.45	-7.32	127.0	103.4	11.785	7.657	-13.57	-13.53	28.52	1382
CV-24008	6/30/2026 9:07:16 AM	-7.31	-7.41	103.3	104.1	7.646	7.758	-13.55	-13.67	28.55	1382
CV-24009	6/1/2026 8:55:00 AM										
CV-24009	6/2/2026 8:30:31 AM										
CV-24009	6/2/2026 8:52:31 AM	-6.60	-6.73			0.000	0.000	-7.39	-7.39	28.58	1373
CV-24009	6/2/2026 8:55:00 AM										
CV-24009	6/9/2026 8:57:30 AM	-6.36	-6.06			0.001	0.000	-10.84	-10.42	28.47	1373
CV-24009	6/16/2026 8:46:33 AM	-3.72	-3.63			0.048	0.059	-7.75	-7.75	28.57	1380
CV-24009	6/19/2026 11:27:55 AM										
CV-24009	6/23/2026 9:31:14 AM	-4.66				0.121		-8.82		28.61	1385
CV-24009	6/23/2026 9:34:10 AM	-1.97	-1.97			0.138	0.122	-8.13	-8.13	28.6	1383
CV-24009	6/25/2026 9:25:26 AM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24009	6/25/2026 9:26:16 AM										
CV-24009	6/26/2026 1:24:49 PM										
CV-24009	6/26/2026 1:25:02 PM										
CV-24009	6/30/2026 8:56:02 AM	-0.61	-1.24			0.000	0.000	-14.35	-14.50	28.52	1384
CV-24009	6/30/2026 8:57:08 AM	-1.28	-1.29			0.000	0.000	-15.16	-15.16	28.52	1384
CV-24009	6/30/2026 9:31:37 AM	-1.09	-0.82	6.4	1.9	0.118	0.010	-12.81	-13.18	28.54	1381
CV-24010	6/8/2026 2:10:41 PM	-6.49	-6.34			6.501	6.371	-6.61	-6.59	28.49	1348
CV-24010	6/8/2026 2:11:53 PM	-6.71	-7.22			6.655	7.227	-7.38	-7.55	28.49	1360
CV-24010	6/23/2026 1:51:29 PM	-4.38	-4.60			4.311	4.299	-4.06	-4.05	28.62	1372
CV-24010	6/24/2026 9:13:10 AM										
CV-24011	6/2/2026 9:35:00 AM										
CV-24011	6/2/2026 9:35:00 AM										
CV-24011	6/2/2026 9:37:40 AM	-4.40	-3.06	41.2	34.0	5.209	3.534	-9.82	-9.56	28.61	1367
CV-24011	6/2/2026 9:38:42 AM	-3.05	-3.05	33.4	33.4	3.407	3.407	-9.40	-9.40	28.61	1368
CV-24011	6/4/2026 1:01:49 PM	-0.86	-2.07	30.3	36.6	2.819	4.129	-6.85	-6.73	28.47	1374
CV-24011	6/4/2026 1:03:39 PM	-2.15	-2.15	35.6	35.6	3.891	3.891	-6.51	-6.51	28.48	1367
CV-24011	6/9/2026 9:12:23 AM	-4.87	-3.79	40.6	34.7	5.073	3.679	-9.50	-9.23	28.49	1379
CV-24011	6/9/2026 9:13:37 AM	-3.74	-3.76	36.7	35.2	4.120	3.784	-9.83	-9.37	28.49	1381
CV-24011	6/16/2026 9:07:19 AM	-2.40	-2.27	26.2	24.5	2.089	1.823	-6.06	-6.06	28.6	1372
CV-24011	6/16/2026 9:08:16 AM	-2.12	-2.09	23.2	22.4	1.633	1.523	-6.40	-6.40	28.6	1372
CV-24011	6/23/2026 10:12:30 AM	-1.23	-1.33	28.7	29.0	2.513	2.564	-7.35	-7.41	28.64	1364
CV-24011	6/29/2026 9:18:00 AM	-2.22	-1.93	30.7	28.5	2.885	2.477	-9.03	-9.16	28.55	1376
CV-24011	6/29/2026 9:18:40 AM									28.55	1362
CV-24012	6/2/2026 9:28:01 AM	-8.52	-8.50			8.674	8.506	0.31	0.34	28.62	1369
CV-24012	6/2/2026 9:30:00 AM										
CV-24012	6/2/2026 9:30:00 AM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24012	6/9/2026 9:34:04 AM	-10.80	-10.94			10.934	10.982	-10.70	-10.58	28.51	1371
CV-24012	6/16/2026 9:25:50 AM	-8.10	-8.09			8.543	8.426	-8.77	-8.76	28.6	1357
CV-24012	6/23/2026 10:03:04 AM	-8.38	-4.98			8.981	5.479	-8.89	-8.01	28.64	1355
CV-24012	6/23/2026 10:04:25 AM	-5.05	-5.05			5.475	5.442	-8.65	-8.42	28.64	1356
CV-24012	6/24/2026 1:16:51 PM										
CV-24012	6/29/2026 10:10:08 AM	-10.93	-11.05			11.173	11.294	-11.00	-11.07	28.59	1344
CV-24013	6/11/2026 9:49:00 AM	-0.13	-0.18			0.102	0.157	-7.28	-7.53	28.41	1391
CV-24013	6/22/2026 10:46:47 AM	-0.28	-0.25			0.276	0.243	-6.49	-6.31	28.54	1372
CV-24013	6/22/2026 10:51:54 AM	-4.49	-4.39			4.486	4.385	-6.45	-6.18	28.55	1372
CV-24014	6/2/2026 8:48:10 AM	-5.59	-5.68	43.3	43.4	5.718	5.758	-7.17	-7.94	28.58	1375
CV-24014	6/2/2026 8:50:00 AM										
CV-24014	6/2/2026 8:50:00 AM										
CV-24014	6/9/2026 8:53:51 AM	-6.23	-6.78	45.5	47.6	6.374	6.990	-7.41	-8.65	28.47	1365
CV-24014	6/16/2026 8:43:10 AM	-4.66	-4.64	39.1	39.0	4.641	4.629	-7.96	-7.86	28.6	1379
CV-24014	6/19/2026 11:50:57 AM	-4.48	-4.90			4.460	5.062	-6.70	-7.00	28.61	1361
CV-24014	6/22/2026 9:40:26 AM	-2.56	-2.56	29.0	29.0	2.546	2.546	-3.50	-3.50	28.53	1376
CV-24014	6/25/2026 10:35:18 AM										
CV-24014	6/29/2026 1:41:00 PM										
CV-24014	6/30/2026 8:45:06 AM	-9.74	-4.87	56.6	39.9	9.997	4.850	-10.38	-9.40	28.53	1376
CV-24014	6/30/2026 8:47:14 AM	-4.44	-5.05	38.1	41.4	4.411	5.229	-9.66	-10.86	28.53	1376
CV-24015	6/1/2026 10:43:39 AM	-2.42	-2.30			2.428	2.291	-4.70	-4.37	28.57	1369
CV-24015	6/1/2026 10:45:00 AM										
CV-24015	6/1/2026 10:45:00 AM										
CV-24015	6/8/2026 9:52:47 AM	-3.77	-3.69			3.741	3.654	-6.53	-6.76	28.48	1370
CV-24015	6/15/2026 9:17:48 AM	-2.46	-2.46			2.465	2.465	-6.13	-6.13	28.62	1363

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24015	6/22/2026 9:33:15 AM	-1.83	-1.04			1.830	1.033	-4.67	-4.29	28.53	1362
CV-24015	6/22/2026 9:34:57 AM	-1.38	-1.38			1.350	1.350	-6.34	-6.34	28.53	1362
CV-24015	6/29/2026 9:56:20 AM	-3.95	-3.76			3.924	3.740	-7.21	-6.49	28.51	1359
CV-24016	6/2/2026 9:42:45 AM	-5.43	-5.56			5.531	5.586	-6.93	-6.76	28.62	1361
CV-24016	6/2/2026 9:45:00 AM										
CV-24016	6/2/2026 9:45:00 AM										
CV-24016	6/9/2026 9:16:20 AM	-5.72	-5.72			5.755	5.785	-7.07	-7.35	28.51	1379
CV-24016	6/16/2026 9:15:50 AM	-4.49	-4.53			4.484	4.520	-5.75	-5.68	28.6	1373
CV-24016	6/23/2026 10:09:50 AM	-3.83	-3.93			3.815	3.894	-4.88	-5.14	28.64	1364
CV-24016	6/29/2026 9:22:30 AM	-5.42	-5.42			5.656	5.681	-6.79	-6.77	28.56	1367
CV-24017	6/2/2026 9:23:32 AM	-3.74	-2.31			3.819	2.358	0.34	0.33	28.59	1372
CV-24017	6/2/2026 9:24:13 AM	-2.23	-2.39			2.100	2.318	0.34	0.34	28.59	1373
CV-24017	6/2/2026 9:25:00 AM										
CV-24017	6/2/2026 9:25:00 AM										
CV-24017	6/9/2026 9:22:05 AM	-1.69	-1.87			1.622	1.898	-1.34	-1.68	28.5	1387
CV-24017	6/15/2026 9:45:00 AM										
CV-24017	6/15/2026 9:45:00 AM										
CV-24017	6/16/2026 9:21:32 AM	-7.71	-5.24			8.210	5.673	-8.17	-8.44	28.6	1371
CV-24017	6/16/2026 9:23:09 AM	-3.84	-4.02			3.845	3.900	-8.74	-8.00	28.6	1374
CV-24017	6/23/2026 9:49:36 AM	-2.11	-2.29			2.193	2.380	-8.65	-8.76	28.6	1362
CV-24017	6/29/2026 10:14:31 AM	-3.88	-3.78			3.926	3.708	-11.08	-10.96	28.56	1370
CV-24017	6/30/2026 8:53:30 AM										
CV-24018	6/1/2026 2:20:40 PM	-0.10	-0.09			0.000	0.000	-5.47	-5.73	28.49	1379
CV-24018	6/22/2026 8:06:29 AM	-1.36	-0.91			1.352	0.910	-7.65	-7.97	28.5	1375
CV-24018	6/22/2026 8:07:35 AM	-0.78	-0.78			0.775	0.778	-7.82	-7.93	28.51	1392
CV-24018	6/23/2026 4:42:31 PM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24018	6/25/2026 3:34:56 PM	-2.29	-2.28			2.348	2.266	-8.67	-8.22	28.53	1355
CV-24019	6/2/2026 9:48:57 AM	-8.54	-4.04			8.637	3.939	-8.54	-6.28	28.6	1355
CV-24019	6/2/2026 9:50:00 AM										
CV-24019	6/2/2026 9:50:00 AM										
CV-24019	6/2/2026 9:50:36 AM	-4.68	-4.81			4.440	4.498	-7.19	-7.32	28.61	1355
CV-24019	6/16/2026 9:37:35 AM	-6.81	-4.63			7.333	4.582	-7.54	-5.80	28.6	1365
CV-24019	6/16/2026 9:40:14 AM	-4.04	-4.98			4.734	4.649	-6.91	-6.93	28.6	1366
CV-24019	6/23/2026 10:07:07 AM	-4.07	-4.24			3.924	3.841	-8.80	-8.46	28.61	1358
CV-24019	6/26/2026 8:44:17 AM										
CV-24019	6/29/2026 9:28:09 AM	-5.02	-5.08			5.183	5.230	-9.85	-9.86	28.56	1362
CV-24020	6/2/2026 8:30:02 AM	-6.47	-6.44	8.4	9.6	0.176	0.228	-6.51	-6.43	28.64	1360
CV-24020	6/23/2026 1:30:27 PM	-7.69	-7.48	2.5	1.4	0.017	0.005	-7.43	-7.29	28.62	1324
CV-24020	6/25/2026 11:24:16 AM										
CV-24021	6/2/2026 8:09:06 AM	0.04	-7.34			0.000	7.356	-6.29	-7.56	28.63	1359
CV-24021	6/2/2026 8:10:40 AM	-7.80	-7.80			7.801	7.801	-7.92	-7.97	28.63	1359
CV-24021	6/2/2026 8:32:46 AM										
CV-24021	6/23/2026 1:23:38 PM	-7.93	-7.79			8.034	7.859	-7.73	-7.73	28.65	1351
CV-24021	6/23/2026 1:25:06 PM	-7.53	-7.58			7.718	7.734	-7.40	-7.48	28.62	1349
CV-24021	6/25/2026 11:24:59 AM										
CV-24022-PI	6/1/2026 1:58:30 PM	-7.25	-7.58			7.343	7.641	-0.05	-0.04	28.55	1352
CV-24022-PI	6/1/2026 2:10:00 PM										
CV-24022-PI	6/1/2026 2:10:00 PM										
CV-24022-PI	6/8/2026 10:03:23 AM	-10.73	-10.44			10.729	10.430	0.34	0.34	28.48	1379

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24022-PI	6/15/2026 9:24:32 AM	-3.33	-3.42			3.395	3.404	0.34	0.34	28.61	1372
CV-24022-PI	6/22/2026 9:43:50 AM	-5.95	-5.66			6.367	6.116	0.34	0.34	28.53	1382
CV-24022-PI	6/29/2026 10:18:07 AM	-8.03	-8.99			8.345	9.270	0.29	0.29	28.49	1374
CV-24023	6/1/2026 10:49:06 AM	-5.81	-5.81			5.846	5.846	0.67	0.67	28.56	1358
CV-24023	6/1/2026 10:50:00 AM										
CV-24023	6/1/2026 10:50:00 AM										
CV-24023	6/2/2026 7:16:22 AM										
CV-24023	6/8/2026 9:57:42 AM	69.49	-0.51			0.000	0.496	0.34	0.34	28.47	1373
CV-24023	6/8/2026 9:58:50 AM	-3.96	-4.10			3.914	4.024	0.34	0.34	28.48	1373
CV-24023	6/11/2026 4:02:00 PM	-0.88	-0.92	0.0	0.0	0.877	1.056	-5.97		28.4	1358
CV-24023	6/11/2026 4:03:26 PM	-1.12	-1.13	0.0	0.0	0.932	1.150	-6.12		28.4	1375
CV-24023	6/15/2026 9:20:16 AM	-1.82	-1.71			1.819	1.685	0.34	0.34	28.6	1365
CV-24023	6/22/2026 9:37:30 AM	-1.64	-1.60			1.629	1.608	0.34	0.34	28.53	1367
CV-24023	6/29/2026 10:12:19 AM	-3.29	-3.26			3.248	3.214	0.29	0.32	28.5	1367
CV-24024-PI	6/8/2026 1:57:26 PM	-7.75	-7.72			7.769	7.742	-7.81	-7.86	28.51	1340
CV-24024-PI	6/8/2026 1:57:56 PM	-6.67	-6.68			6.649	6.688	-6.40	-6.56	28.54	1334
CV-24024-PI	6/24/2026 10:27:50 AM	-8.33	-8.13			8.271	8.059	-8.04	-7.79	28.63	1326
CV-24024-PI	6/29/2026 9:47:30 AM	-8.17	-7.98			8.515	8.342	-8.70	-8.41	28.52	1349
CV-24025	6/2/2026 10:41:15 AM	-6.40	-6.06			6.474	6.202	-10.04	-9.74	28.63	1353
CV-24025	6/2/2026 10:45:00 AM										
CV-24025	6/2/2026 10:45:00 AM										
CV-24025	6/9/2026 9:40:42 AM	-1.54	-1.31			1.542	1.313	0.34	0.34	28.51	1365
CV-24025	6/11/2026 10:08:18 AM										
CV-24025	6/16/2026 10:19:07 AM	-0.05	-0.51			0.039	0.482	0.36	0.34	28.59	1348
CV-24025	6/16/2026 10:19:54 AM	-0.61	-0.61			0.577	0.577	0.34	0.34	28.6	1345
CV-24025	6/23/2026 10:21:26 AM	-0.88	-0.85			0.843	0.833	0.34	0.34	28.64	1355

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24025	6/29/2026 9:34:06 AM	-1.79	-1.62			1.796	1.604	0.01	0.00	28.56	1367
CV-24026	6/2/2026 8:38:21 AM	-1.14	-1.04			1.131	1.038	-10.19	-10.41	28.64	1367
CV-24026	6/9/2026 9:54:29 AM	-0.16	-8.27			0.096	8.410	-9.01	-7.95	28.51	1354
CV-24026	6/9/2026 9:56:19 AM	-9.02	-8.65			9.143	8.855	-9.07	-7.03	28.51	1355
CV-24026	6/10/2026 11:09:42 AM	-5.15	-4.39	0.0	0.0	5.203	4.442	-8.92		28.49	1355
CV-24026	6/10/2026 11:11:56 AM	-5.25	-2.07	0.0	0.0	5.444	2.155	-9.48		28.49	1322
CV-24026	6/23/2026 11:28:16 AM	105.51	-0.73			0.000	0.751	-7.83	-5.39	28.63	1355
CV-24026	6/23/2026 11:35:40 AM	-2.64	-0.95			2.672	0.966	-5.80	-6.67	28.63	1355
CV-24026	6/23/2026 11:39:23 AM	-1.89	-1.90			1.885	1.892	-6.85	-6.87	28.63	1352
CV-24026	6/29/2026 10:05:21 AM	-9.79	-9.79			10.013	10.014	-10.48	-10.49	28.59	1346
CV-24027	6/2/2026 8:19:11 AM	57.78	-10.98			0.000	11.047	-11.40	-11.23	28.63	1359
CV-24027	6/2/2026 8:21:11 AM	-11.19	-11.17			11.336	11.282	-11.27	-11.51	28.63	1359
CV-24027	6/23/2026 11:10:25 AM	-8.43	-8.53			8.777	8.762	-8.10	-8.34	28.63	1362
CV-24027	6/23/2026 2:49:58 PM										
CV-24028	6/1/2026 1:53:07 PM	-7.09	-7.13			7.203	7.180	-7.40	-7.60	28.56	1355
CV-24028	6/1/2026 2:05:00 PM										
CV-24028	6/1/2026 2:05:00 PM										
CV-24028	6/8/2026 10:09:22 AM	-9.67	-9.81			9.812	9.986	-9.82	-10.12	28.51	1372
CV-24028	6/15/2026 9:29:30 AM	-4.79	-4.27			4.783	4.101	-7.85	-7.45	28.61	1352
CV-24028	6/22/2026 9:46:03 AM	-6.23	-6.66			6.785	7.138	-7.40	-7.16	28.53	1380
CV-24028	6/23/2026 1:24:03 PM										
CV-24028	6/29/2026 10:41:12 AM	-5.64	-5.56			6.014	5.828	-6.52	-6.55	28.49	1362
CV-24029	6/5/2026 2:13:50 PM	-8.12	-8.17			8.217	8.278	-8.42	-8.36	28.41	1355
CV-24029	6/9/2026 1:11:23 PM	-7.77	-1.47			7.881	1.480	-9.07	-8.38	28.48	1367
CV-24029	6/9/2026 1:24:01 PM	-0.59	-0.54			0.528	0.513	-9.50	-8.42	28.48	1363

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24029	6/17/2026 2:05:10 PM	9.37	-8.06			0.000	8.021	-8.12	-8.45	28.54	1372
CV-24029	6/17/2026 2:06:03 PM	-8.25	-8.06			8.290	8.260	-8.35	-8.33	28.53	1385
CV-24029	6/19/2026 12:12:46 PM	-8.33	-8.00			8.567	8.316	-8.47	-8.19	28.61	1341
CV-24030	6/1/2026 10:00:00 AM										
CV-24030	6/1/2026 10:00:00 AM										
CV-24030	6/1/2026 10:01:10 AM	-2.39	-1.19			2.423	1.176	-3.77	-3.86	28.58	1355
CV-24030	6/1/2026 10:03:17 AM	-1.11	-1.14			1.205	1.274	-3.44	-3.51	28.58	1356
CV-24030	6/8/2026 9:33:25 AM	-3.35	-1.28			3.405	1.376	-5.66	-5.50	28.51	1348
CV-24030	6/8/2026 9:38:38 AM	-2.77	-2.93			2.817	2.933	-5.42	-5.54	28.5	1347
CV-24030	6/15/2026 8:58:22 AM	-2.23	-1.32			2.225	1.333	-4.81	-4.86	28.63	1362
CV-24030	6/15/2026 9:05:40 AM	-2.31	-2.01			2.303	2.165	0.30	0.29	28.63	1365
CV-24030	6/22/2026 9:04:13 AM	-2.55	-0.64			2.547	0.623	-3.96	-3.93	28.56	1345
CV-24030	6/22/2026 9:06:13 AM	-0.63	-0.79			0.745	0.753	-4.02	-4.38	28.56	1351
CV-24030	6/22/2026 9:10:22 AM	-0.03	-0.06			0.027	0.051	-4.29	-3.96	28.55	1353
CV-24030	6/29/2026 9:22:58 AM	-2.29	-2.23			2.386	2.308	-6.06	-6.05	28.53	1350
CV-24031	6/2/2026 9:09:14 AM	-10.14	-0.64			10.059	0.642	-10.29	-10.37	28.59	1356
CV-24031	6/2/2026 9:16:24 AM	-0.12	-0.10			0.126	0.119	-9.97	-10.09	28.6	1367
CV-24031	6/22/2026 8:17:15 AM	0.56	-0.25			0.000	0.250	-8.17	-7.96	28.51	1358
CV-24031	6/22/2026 8:17:55 AM	-0.28	-0.25			0.269	0.240	-8.27	-8.10	28.51	1361
CV-24031	6/22/2026 8:18:11 AM	-0.25	-0.24			0.247	0.240	-7.02	-7.13	28.51	1365
CV-24032	6/2/2026 1:40:47 PM	0.22	0.26			0.000	0.000	-0.38	-0.33	28.65	1351

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24032	6/2/2026 1:41:54 PM	0.14	0.14			0.000	0.000	-0.57	-0.59	28.64	1351
CV-24032	6/2/2026 1:45:00 PM										
CV-24032	6/2/2026 1:45:00 PM										
CV-24032	6/9/2026 10:16:37 AM	0.36	0.69			0.000	0.000	1.91	2.02	28.52	1352
CV-24032	6/9/2026 10:17:50 AM	0.60	0.74			0.000	0.000	1.80	1.76	28.51	1352
CV-24032	6/16/2026 10:01:42 AM	-1.64	-0.91			1.657	0.927	-2.23	-2.37	28.6	1340
CV-24032	6/16/2026 10:03:21 AM	-0.71	-0.64			0.738	0.671	-2.38	-2.36	28.6	1340
CV-24032	6/23/2026 10:42:53 AM	-2.26	-0.34			2.202	0.328	-5.50	-4.71	28.67	1354
CV-24032	6/23/2026 10:43:53 AM	-0.44	-0.45			0.465	0.463	-5.73	-5.73	28.67	1356
CV-24032	6/25/2026 8:17:52 AM										
CV-24032	6/29/2026 9:46:20 AM	-6.19	-5.95			6.444	6.184	-8.19	-8.62	28.59	1357
CV-24032	6/30/2026 8:30:37 AM	-4.27	-3.50			4.254	3.506	-9.11	-8.95	28.58	1343
CV-24033	6/2/2026 1:44:33 PM	-3.06	-3.05			3.043	3.070	-3.43	-3.36	28.64	1353
CV-24033	6/2/2026 1:55:00 PM										
CV-24033	6/2/2026 1:55:00 PM										
CV-24033	6/9/2026 10:10:59 AM	1.28	1.30			0.000	0.000	1.89	1.89	28.52	1352
CV-24033	6/9/2026 10:11:43 AM	1.17	1.21			0.000	0.000	2.03	2.03	28.52	1352
CV-24033	6/16/2026 9:54:12 AM	4.18	1.66			0.000	0.000	0.99	4.55	28.61	1335
CV-24033	6/16/2026 9:54:43 AM	1.02	1.04			0.000	0.000	3.05	3.03	28.6	1335
CV-24033	6/16/2026 3:10:13 PM	-0.59	-0.61			0.624	0.614	-1.00	-0.96	28.56	1352

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24033	6/16/2026 3:11:47 PM	-0.57	-0.58			0.578	0.590	-0.96	-1.04	28.57	1366
CV-24033	6/23/2026 10:34:05 AM	-0.08	-2.17			0.041	2.136	-3.02	-2.74	28.68	1355
CV-24033	6/23/2026 10:36:00 AM	-2.70	-2.71			2.682	2.687	-3.19	-3.12	28.68	1355
CV-24033	6/29/2026 9:54:36 AM	-6.76	-6.74			7.001	6.927	-6.79	-6.92	28.59	1337
CV-24033	6/29/2026 9:57:22 AM	-7.09	-7.09			7.335	7.329	-7.34	-7.45	28.59	1342
CV-24034	6/8/2026 10:37:49 AM										
CV-24034	6/10/2026 11:03:35 AM	-6.28	-1.64			6.581	1.643	-7.72	-7.97	28.41	1357
CV-24034	6/10/2026 1:01:10 PM	-0.67	-0.70	0.0	0.0	0.849	0.845	-9.03		28.35	1365
CV-24034	6/10/2026 1:03:05 PM	-0.65	-0.71	0.0	0.0	0.455	0.744	-9.19		28.35	1309
CV-24034	6/15/2026 9:36:46 AM	-5.27	-6.07			5.719	6.512	-7.94	-8.42	28.64	1367
CV-24034	6/22/2026 9:50:57 AM	2.43	-2.92			0.000	2.899	-6.69	-6.28	28.53	1367
CV-24034	6/22/2026 9:51:32 AM	-3.43	-3.38			3.401	3.358	-6.13	-6.01	28.53	1368
CV-24034	6/30/2026 8:05:38 AM	-10.55	-5.36			10.714	5.404	-14.05	-14.49	28.54	1353
CV-24034	6/30/2026 8:08:12 AM	-4.33	-4.35			4.314	4.320	-14.67	-14.82	28.57	1353
CV-24035	6/1/2026 9:31:45 AM	-4.03	-3.87			4.148	3.611	0.34	0.34	28.54	1362
CV-24035	6/1/2026 9:40:00 AM										
CV-24035	6/1/2026 9:40:00 AM										
CV-24035	6/8/2026 9:15:31 AM	-5.33	-5.43			5.384	5.523	-4.93	-5.71	28.47	1368
CV-24035	6/15/2026 8:40:23 AM	-2.59	-2.41			2.561	1.989	-3.92	-3.41	28.6	1372
CV-24035	6/22/2026 8:50:48 AM	-3.27	-3.11			3.179	2.977	-3.27	-2.78	28.51	1363
CV-24035	6/29/2026 9:07:04 AM	-3.77	-3.86			3.753	3.811	-5.38	-5.29	28.49	1366
CV-24036	6/2/2026 9:30:31 AM	-7.43	-3.49			7.549	3.389	-9.95	-10.04	28.6	1344
CV-24036	6/22/2026 8:28:46 AM	-8.39	-8.05			8.591	8.176	-8.41	-8.12	28.51	1348
CV-24037	6/2/2026 9:49:59 AM	-5.49	-1.29			5.673	1.287	-9.65	-9.50	28.6	1340
CV-24037	6/22/2026 8:23:58 AM	-4.43	-3.66			4.306	3.631	-5.94	-6.55	28.52	1347

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24037	6/22/2026 8:24:48 AM	-3.74	-3.76			3.672	3.693	-5.84	-6.10	28.52	1348
CV-24037	6/29/2026 12:33:39 PM	-5.58	-3.66			5.652	3.598	-8.85	-8.97	28.58	1341
CV-24037	6/29/2026 12:34:30 PM	-3.70	-3.72			3.627	3.722	-9.01	-8.84	28.59	1345
CV-24038	6/2/2026 2:01:48 PM	-5.71	-2.54			5.771	2.507	-10.01	-10.44	28.65	1345
CV-24038	6/2/2026 2:03:03 PM	-2.57	-2.91			2.709	3.225	-10.09	-10.58	28.65	1346
CV-24038	6/2/2026 2:05:00 PM										
CV-24038	6/2/2026 2:05:00 PM										
CV-24038	6/3/2026 3:29:21 PM										
CV-24038	6/9/2026 12:58:07 PM	-12.33	-2.81			11.676	2.342	-12.47	-12.89	28.52	1354
CV-24038	6/9/2026 12:59:45 PM	-4.48	-4.75			3.939	4.088	-12.56	-13.46	28.54	1357
CV-24038	6/9/2026 1:14:37 PM	-3.53	-2.84			3.707	2.804	-8.90	-9.49	28.53	1343
CV-24038	6/16/2026 1:02:05 PM	-6.71	-4.66			6.815	4.581	-8.75	-8.77	28.57	1338
CV-24038	6/16/2026 1:03:03 PM	-3.55	-3.10			3.455	3.214	-8.73	-8.63	28.57	
CV-24038	6/23/2026 2:03:54 PM	-7.02	-1.24			7.327	1.263	-7.51	-7.07	28.61	1346
CV-24038	6/23/2026 2:04:41 PM	-0.36	-0.71			0.391	0.661	-6.44	-6.47	28.6	1346
CV-24038	6/29/2026 12:43:07 PM	-8.80	-8.94			8.804	8.962	-9.48	-9.48	28.59	1348
CV-24039	6/10/2026 10:33:51 AM	-5.84	-5.81			6.205	6.176	-9.07	-9.22	28.42	1353
CV-24039	6/15/2026 1:30:09 PM	-6.85	-2.45			6.879	2.460	-8.06	-8.14	28.6	1368
CV-24039	6/15/2026 1:31:35 PM	-3.29	-3.31			3.314	3.321	-8.07	-8.21	28.61	1370
CV-24039	6/23/2026 1:50:27 PM	-0.73	-3.86			0.716	3.906	-5.28	-5.82	28.61	1358
CV-24039	6/23/2026 1:51:13 PM	-2.80	-2.83			2.896	2.906	-5.70	-5.99	28.6	1361
CV-24039	6/29/2026 12:51:38 PM	-7.73	-7.75			7.861	7.798	-8.02	-8.57	28.58	1359

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24040	6/1/2026 2:28:59 PM	1.13	-2.97			0.000	2.958	-8.06	-8.21	28.56	1355
CV-24040	6/1/2026 2:30:00 PM										
CV-24040	6/1/2026 2:30:00 PM										
CV-24040	6/1/2026 2:30:55 PM	-2.98	-2.92			2.951	2.912	-8.41	-7.96	28.56	1355
CV-24040	6/11/2026 10:25:08 AM	-7.12	-4.31			7.435	4.303	-7.04	-6.95	28.5	1355
CV-24040	6/11/2026 10:31:45 AM	-2.61	-2.59			2.569	2.547	-6.77	-6.73	28.51	1359
CV-24040	6/15/2026 9:40:41 AM	-2.39	-2.58			2.379	2.552	-7.00	-8.67	28.65	1357
CV-24040	6/22/2026 10:31:23 AM	-2.78	-1.65			2.757	1.619	-6.90	-6.45	28.57	1360
CV-24040	6/22/2026 10:32:22 AM	-2.29				2.240		-7.23		28.53	1361
CV-24040	6/22/2026 1:40:55 PM	-0.79	-0.84			0.755	0.828	-6.27	-6.34	28.57	1348
CV-24040	6/29/2026 1:04:55 PM	-4.76	-1.31			4.684	1.263	-9.63	-9.47	28.58	1369
CV-24041	6/10/2026 10:56:45 AM	11.86	-7.06			0.000	7.480	-4.10	-9.96	28.41	1353
CV-24041	6/10/2026 10:58:05 AM	-8.89	-8.83			9.300	9.282	-9.80	-9.77	28.43	1356
CV-24041	6/22/2026 1:36:11 PM	-6.73	-6.63			6.682	6.577	-6.49	-6.49	28.58	1345
CV-24041	6/22/2026 1:36:46 PM	-6.40	-6.40			6.368	6.338	-6.79	-6.07	28.58	1346
CV-24042	6/1/2026 1:43:32 PM	-3.74	-4.57			3.699	4.100	-8.50	-11.21	28.55	1372
CV-24042	6/1/2026 2:00:00 PM										
CV-24042	6/1/2026 2:00:00 PM										
CV-24042	6/8/2026 10:25:47 AM	-4.11	-4.00			4.113	3.653	-9.10	-8.92	28.47	1372
CV-24042	6/15/2026 10:17:58 AM	-6.23	-6.07			6.834	6.661	-10.25	-9.64	28.61	1367

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24042	6/22/2026 10:19:11 AM	-2.53	-2.61			2.491	2.546	-7.10	-8.25	28.51	1372
CV-24042	6/30/2026 8:22:39 AM	-7.82	-7.35			8.037	7.489	-15.15	-15.35	28.53	1370
CV-24043	6/2/2026 3:43:36 PM	-5.04	-4.39	0.0	0.0	5.061	4.512	-6.67		28.67	1224
CV-24043	6/3/2026 9:39:34 AM	-1.41	-1.59			1.381	1.535	-2.60	-4.22	28.58	1326
CV-24043	6/25/2026 8:57:04 AM	-4.03	-4.03	60.9	67.2	3.560	4.310			28.57	1309
CV-24044	6/2/2026 9:35:24 AM	-5.74	-3.28			5.718	3.178	-10.14	-10.27	28.6	1361
CV-24044	6/22/2026 8:35:31 AM	-1.42	-0.53			1.402	0.527	-8.08	-7.89	28.55	1352
CV-24044	6/22/2026 8:36:18 AM	-0.63	-0.54			0.621	0.540	-8.41	-7.40	28.52	1354
CV-24044	6/29/2026 12:27:05 PM	-0.85	-0.83			0.879	0.854	-9.37	-9.35	28.58	1350
CV-24045	6/2/2026 2:06:38 PM	-8.84	-8.63			9.036	8.904	-9.77	-9.41	28.62	1346
CV-24045	6/2/2026 2:10:00 PM										
CV-24045	6/2/2026 2:10:00 PM										
CV-24045	6/9/2026 1:04:35 PM	-8.11	-4.85			8.253	4.823	-8.79	-9.04	28.55	1359
CV-24045	6/9/2026 1:05:54 PM	-3.86	-3.49			3.869	3.512	-8.69	-8.32	28.54	1359
CV-24045	6/9/2026 1:12:32 PM	-1.75	-1.97			1.726	1.867	-9.20	-8.53	28.55	1353
CV-24045	6/16/2026 1:06:05 PM	-1.64	-1.78			1.612	1.791	-8.34	-8.59	28.58	1350
CV-24045	6/23/2026 2:07:06 PM	-2.37	-2.42			2.336	2.388	-6.81	-6.84	28.61	1341
CV-24045	6/29/2026 12:38:59 PM	-5.85	-5.58			5.800	5.749	-9.46	-9.56	28.59	1352
CV-24046	6/10/2026 10:01:39 AM	-3.04	-3.16			2.744	3.176	-2.87	-3.06	28.44	1356
CV-24046	6/10/2026 10:02:29 AM	-3.95	-4.34			3.592	3.818	-2.81	-2.95	28.43	1349
CV-24046	6/15/2026 1:34:47 PM	-2.26	-1.19			2.375	1.222	-2.76	-1.50	28.61	1370
CV-24046	6/15/2026 1:37:16 PM	-2.03	-2.74			2.105	2.758	-2.77	-3.37	28.6	1371
CV-24046	6/23/2026 1:41:24 PM	-1.05	-0.80			1.097	0.776	-1.20	-0.91	28.61	1342
CV-24046	6/29/2026 12:57:50 PM	-5.69	-2.48			5.725	2.399	-5.62	-6.08	28.59	1369

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24046	6/29/2026 12:59:14 PM	-2.88	-2.88			2.775	2.775	-6.33	-6.33	28.59	1364
CV-24048	6/10/2026 10:44:37 AM	-10.46	-9.86			10.629	10.119	-10.13	-9.51	28.42	1366
CV-24048	6/22/2026 1:27:42 PM	-7.00	-4.83			6.987	4.794	-6.93	-6.67	28.58	1356
CV-24049	6/1/2026 1:29:08 PM	-2.84	-2.51			2.961	2.539	-8.74	-8.28	28.55	1379
CV-24049	6/1/2026 1:40:00 PM										
CV-24049	6/1/2026 1:40:00 PM										
CV-24049	6/4/2026 9:00:00 AM										
CV-24049	6/4/2026 9:00:00 AM										
CV-24049	6/8/2026 1:38:10 PM	-3.39	-3.24			3.421	4.053	-9.15	-9.49	28.51	1383
CV-24049	6/15/2026 9:57:07 AM	-2.45	-2.46			2.808	2.864	-7.88	-9.39	28.61	1373
CV-24049	6/22/2026 1:22:35 PM	-1.11	-1.26			0.989	1.436	-6.85	-7.35	28.51	1370
CV-24049	6/26/2026 2:42:38 PM										
CV-24049	6/29/2026 2:11:03 PM	-8.56	-8.34			8.828	8.558	-9.62	-10.06	28.47	1383
CV-24050	6/3/2026 9:17:29 AM	-2.19	-2.20			2.138	2.145	-7.85	-7.82	28.6	1341
CV-24050	6/22/2026 11:57:01 AM	-1.68	-1.65			1.633	1.616	-5.60	-5.14	28.67	1326
CV-24051	6/4/2026 12:43:06 PM	0.57	-5.68			0.000	5.696	-7.45	-7.41	28.6	1350
CV-24051	6/4/2026 12:44:46 PM	-5.71	-5.71			5.790	5.788	-7.26	-7.30	28.59	1357
CV-24051	6/25/2026 11:34:01 AM	-8.56	-8.05	0.0	0.0	8.368	8.249	-9.98		28.59	1348
CV-24051	6/25/2026 11:40:21 AM	-8.01	-7.85	0.0	0.0	8.266	7.602	-9.86		28.59	1325
CV-24051	6/25/2026 2:20:14 PM	-7.22	-7.13			7.489	7.391	-8.96	-8.46	28.52	1343
CV-24052	6/4/2026 9:09:09 AM	-6.90	-6.89			7.089	7.034	-6.84	-6.86	28.54	1358
CV-24052	6/22/2026 1:46:11 PM	-5.39	-5.04			5.251	4.983	-5.04	-4.87	28.56	1370
CV-24053	6/3/2026 7:40:00 AM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24053	6/3/2026 7:40:00 AM										
CV-24053	6/3/2026 1:28:17 PM										
CV-24053	6/4/2026 8:58:29 AM	-7.12	-1.63			7.235	1.602	-7.12	-6.96	28.53	1368
CV-24053	6/22/2026 2:17:18 PM	-1.08	-1.07			1.035	1.038	-4.61	-4.49	28.55	1362
CV-24054	6/1/2026 1:25:36 PM	-2.90	-2.90			2.875	2.875	-9.93	-9.93	28.54	1382
CV-24054	6/1/2026 1:35:00 PM										
CV-24054	6/1/2026 1:35:00 PM										
CV-24054	6/3/2026 1:18:32 PM										
CV-24054	6/8/2026 1:28:03 PM	-7.70	-7.74			7.806	7.931	0.08	0.04	28.49	1384
CV-24054	6/15/2026 9:53:03 AM	-6.04	-6.23			6.575	6.757	-9.35	-10.48	28.6	1380
CV-24054	6/22/2026 1:30:09 PM	-5.06	-5.05			5.345	5.351	-7.31	-7.07	28.49	1370
CV-24054	6/29/2026 2:13:59 PM	-7.54	-7.54			7.717	7.778	-10.53	-10.46	28.46	1381
CV-24055	6/4/2026 10:40:08 AM	-0.53	-0.46			0.511	0.459	-8.82	-8.52	28.41	1390
CV-24055	6/4/2026 10:41:12 AM	-0.53	-0.59			0.513	0.544	-8.17	-8.31	28.41	1391
CV-24055	6/12/2026 8:00:00 AM										
CV-24055	6/12/2026 8:00:00 AM										
CV-24055	6/23/2026 9:47:37 AM	-0.46	-0.46			0.449	0.431	-10.40	-10.31	28.58	1403
CV-24056	6/2/2026 8:05:04 AM	-1.33	-0.98			1.307	0.971	-9.30	-9.48	28.6	1330
CV-24056	6/6/2026 12:58:24 PM										
CV-24056	6/11/2026 1:07:15 PM	0.04	-0.18			0.000	0.196	-7.72	-6.49	28.53	1316
CV-24056	6/11/2026 1:09:23 PM	-0.16	-0.15			0.182	0.183	-5.81	-6.37	28.53	1322
CV-24056	6/16/2026 7:44:37 AM	-0.13	-0.14			0.136	0.144	-6.54	-6.40	28.6	1315
CV-24056	6/16/2026 7:45:01 AM	-0.13	-0.11			0.127	0.108	-6.61	-5.47	28.6	1312
CV-24056	6/18/2026 1:25:18 PM										
CV-24056	6/18/2026 1:25:33 PM										
CV-24056	6/19/2026 11:47:34 AM										
CV-24056	6/19/2026 11:55:12 AM										
CV-24056	6/24/2026 1:59:57 PM										
CV-24056	6/24/2026 2:00:11 PM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24056	6/25/2026 2:06:44 PM	-0.46	-0.45			0.419	0.442	-6.80	-7.10	28.58	1311
CV-24057	6/3/2026 9:12:06 AM	-0.37	-0.35	17.3	17.8	0.851	0.894	-7.13	-6.96	28.58	1372
CV-24057	6/24/2026 12:59:18 PM	0.61	-0.05	13.0	16.6	0.481	0.787	-3.43	-3.12	28.59	1329
CV-24057	6/24/2026 12:59:44 PM	-0.12	-0.12	16.7	16.5	0.792	0.773	-3.21	-3.26	28.59	1333
CV-24058	6/3/2026 9:45:49 AM	-2.93	-2.66			2.818	2.573	-3.23	-3.93	28.56	1351
CV-24058	6/22/2026 12:12:11 PM	-2.25	-2.19			2.165	2.121	-3.11	-2.48	28.64	1349
CV-24059	6/11/2026 10:22:41 AM	-4.52	-1.12	10.2	5.5	0.358	0.104	-7.75		28.56	1362
CV-24059	6/11/2026 10:25:26 AM	-0.94	-0.94	6.2	6.2	0.130	0.131	-8.55		28.56	1339
CV-24059	6/11/2026 2:12:14 PM	-0.48	-0.10	8.4	14.1	0.206	0.544	-7.98	-8.37	28.45	1339
CV-24059	6/24/2026 1:16:18 PM	-0.15	-0.15	5.4	5.6	0.085	0.091	-7.05	-7.08	28.58	1350
CV-24059	6/24/2026 1:17:14 PM	-0.09	-0.09	5.7	5.7	0.095	0.096	-6.64	-6.64	28.58	1357
CV-24060	6/3/2026 2:26:17 PM	-5.73	-3.92			5.759	3.834	-6.99	-6.90	28.52	1350
CV-24060	6/10/2026 3:04:20 PM	-6.27	-6.27			6.530	6.528	-10.73	-10.75	28.47	1358
CV-24060	6/16/2026 9:58:14 AM	-4.37	-3.59			4.343	3.577	-6.72	-7.57	28.59	1339
CV-24060	6/16/2026 9:59:06 AM	-3.36	-3.36			3.344	3.341	-7.33	-7.42	28.59	1339
CV-24061	6/2/2026 4:14:18 PM	-2.57	-1.38	0.0	0.0	2.552	1.392	-10.71		28.5	1289
CV-24061	6/16/2026 10:06:15 AM	-0.06	-0.05			0.081	0.058	-8.50	-8.44	28.59	1339
CV-24061	6/16/2026 10:07:30 AM	-0.15	-0.15			0.163	0.160	-8.47	-8.47	28.59	1343
CV-24061	6/16/2026 10:08:55 AM	-0.13	-0.16			0.165	0.186	-8.25	-8.37	28.6	1343
CV-24062	6/10/2026 10:20:42 AM	-0.40	-0.46			0.372	0.419	-9.24	-9.48	28.41	1364
CV-24062	6/10/2026 10:21:48 AM	-1.32	-1.28			1.264	1.227	-9.66	-9.29	28.41	1363
CV-24062	6/12/2026 8:50:00 AM										
CV-24062	6/12/2026 8:50:00 AM										
CV-24062	6/16/2026 2:32:33 PM	-7.92	-3.82			8.063	3.704	-8.14	-8.46	28.53	1342
CV-24062	6/16/2026 2:33:39 PM	-2.16	-2.17			2.097	2.116	-8.39	-8.51	28.53	1343

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24062	6/24/2026 9:42:09 AM	-5.74	-4.49			6.369	4.464	-6.42	-6.11	28.61	1354
CV-24062	6/24/2026 9:44:44 AM	-4.22	-4.19			4.204	4.180	-6.08	-6.06	28.63	1354
CV-24062	6/30/2026 8:52:28 AM	-12.81	-11.79			13.073	11.990	-13.57	-13.00	28.55	1361
CV-24063	6/3/2026 1:21:07 PM	-3.77	-3.83			3.621	3.828	-8.26	-8.19	28.58	1368
CV-24063	6/3/2026 1:25:00 PM										
CV-24063	6/10/2026 2:12:26 PM	-4.63	-4.31			4.558	4.485	-8.76	-9.26	28.47	1376
CV-24063	6/12/2026 10:10:00 AM										
CV-24063	6/12/2026 10:10:00 AM										
CV-24063	6/17/2026 2:30:04 PM	-8.34	-3.87			8.381	3.945	-9.16	-9.06	28.49	1357
CV-24063	6/17/2026 2:32:22 PM	-2.14	-1.92			2.186	2.028	-9.07	-9.01	28.49	1357
CV-24063	6/24/2026 9:23:23 AM	-3.69	-0.61			3.609	0.601	-10.44	-10.14	28.6	1360
CV-24063	6/24/2026 9:25:59 AM	-0.93	-0.57			1.001	0.848	0.36	0.34	28.6	1366
CV-24063	6/29/2026 10:05:04 AM										
CV-24063	6/29/2026 1:17:06 PM	-10.29	-10.12			10.334	10.167	-10.83	-10.16	28.57	1390
CV-24064	6/3/2026 1:28:32 PM	-10.45	-10.73			10.259	10.675	-10.96	-11.59	28.57	1381
CV-24064	6/3/2026 1:40:00 PM										
CV-24064	6/10/2026 2:23:47 PM	-10.84	-12.25			10.995	12.187	-12.13	-13.02	28.45	1372
CV-24064	6/12/2026 8:35:00 AM										
CV-24064	6/12/2026 8:35:00 AM										
CV-24064	6/24/2026 9:09:36 AM	-11.67	-11.46			12.193	11.979	-12.68	-12.60	28.6	1365
CV-24064	6/30/2026 2:26:34 PM	-11.35	-11.46			11.649	11.882	-14.84	-15.16	28.49	1369
CV-24065-TF	6/4/2026 10:11:00 AM	-0.55	-0.48			0.467	0.440	-8.35	-6.96	28.42	1389
CV-24065-TF	6/11/2026 7:40:00 AM										
CV-24065-TF	6/11/2026 7:40:00 AM										
CV-24065-TF	6/17/2026 2:10:47 PM	-0.42	-0.44			0.389	0.398	-10.29	-10.33	28.51	1409

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24066	6/2/2026 7:57:31 AM	-2.06	-1.87			2.037	1.843	-11.84	-11.86	28.6	1328
CV-24066	6/15/2026 7:50:00 AM										
CV-24066	6/15/2026 7:50:00 AM										
CV-24066	6/16/2026 7:41:54 AM	-1.15	-1.16			1.136	1.145	-8.47	-8.92	28.61	1329
CV-24067	6/4/2026 10:06:31 AM	-2.73	-2.77			0.000	0.000	-3.39	-3.51	28.55	1362
CV-24067	6/10/2026 9:00:37 AM	-7.10	-6.40			0.000	0.000	-9.70	-8.06	28.47	1340
CV-24067	6/16/2026 9:09:08 AM	-3.86	-2.97			0.240	0.209	-4.84	-5.65	28.63	1326
CV-24067	6/16/2026 9:09:40 AM	-2.73	-2.76			0.211	0.239	-4.91	-5.05	28.63	1321
CV-24067	6/17/2026 9:02:41 AM	-0.13	-0.44			0.000	0.000	-0.98	-0.68	28.57	1324
CV-24067	6/17/2026 9:03:28 AM	-0.74	-0.77			0.000	0.000	-0.65	-0.66	28.57	1325
CV-24067	6/24/2026 1:17:20 PM	-4.18	-4.94			0.084	0.348	-5.62	-5.94	28.6	1342
CV-24068	6/4/2026 11:50:22 AM	-0.55	-0.55			0.525	0.507	-4.04	-3.94	28.59	1356
CV-24068	6/4/2026 11:51:40 AM	-0.56	-0.56			0.521	0.530	-3.92	-4.36	28.59	1365
CV-24068	6/9/2026 1:53:32 PM	-1.45	-2.44			1.432	2.419	-9.21	-8.38	28.54	1343
CV-24068	6/9/2026 1:54:04 PM	-2.70	-2.74			2.658	2.637	-8.99	-9.09	28.54	1343
CV-24068	6/24/2026 1:04:40 PM	-3.30	-3.25			3.271	3.250	-3.42	-3.54	28.59	1341
CV-24068	6/24/2026 1:05:09 PM	-3.33	-3.26			3.326	3.284	-3.46	-3.38	28.59	1339
CV-24068	6/30/2026 4:27:59 PM										
CV-24069	6/3/2026 9:58:36 AM	0.14	-0.06			0.000	0.044	-7.24	-7.57	28.56	1347
CV-24069	6/3/2026 9:59:30 AM	-0.09	-0.09			0.074	0.076	-6.92	-7.21	28.56	1344
CV-24069	6/11/2026 9:28:47 AM	-0.02	-0.63			0.016	0.635	-8.94	-7.74	28.49	1366
CV-24069	6/11/2026 12:10:39 PM	-0.56	-0.50			0.564	0.495	-7.50	-7.21	28.52	1348
CV-24069	6/11/2026 12:19:47 PM	-0.15	-0.13			0.161	0.124	-7.96	-7.37	28.52	1343
CV-24069	6/15/2026 8:00:00 AM										
CV-24069	6/15/2026 8:00:00 AM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24069	6/16/2026 9:36:41 AM	0.13	-0.10			0.000	0.102	-7.16	-3.89	28.62	1340
CV-24069	6/16/2026 9:37:03 AM	-0.25	-0.26			0.255	0.269	-5.83	-7.70	28.62	1342
CV-24069	6/16/2026 9:37:50 AM	-0.23	-0.23			0.225	0.240	-6.15	-5.68	28.61	1342
CV-24070	6/3/2026 10:03:54 AM	-2.40	-1.57	8.7	7.2	1.655	1.126	-7.68	-7.85	28.55	1339
CV-24070	6/3/2026 10:04:21 AM	-1.34	-1.34	7.1	7.2	1.115	1.119	-7.47	-7.50	28.56	1345
CV-24070	6/12/2026 9:10:00 AM										
CV-24070	6/12/2026 9:10:00 AM										
CV-24070	6/24/2026 1:12:10 PM	-0.39	-0.39	6.2	6.3	0.845	0.858	-6.84	-6.86	28.58	1355
CV-24070	6/24/2026 1:12:40 PM	-0.41	-0.40	6.2	6.1	0.835	0.812	-6.86	-6.87	28.59	1359
CV-24071	6/3/2026 2:29:39 PM	-4.29	-4.30	9.2	9.7	0.548	0.609	-6.60	-6.85	28.52	1340
CV-24071	6/12/2026 9:00:00 AM										
CV-24071	6/12/2026 9:00:00 AM										
CV-24071	6/22/2026 10:12:46 AM	-1.95	-1.83	9.6	7.2	0.601	0.335	-7.23	-6.60	28.51	1365
CV-24071	6/22/2026 10:13:06 AM	-1.82	-1.82	11.9	11.5	0.931	0.873	-7.84	-7.83	28.51	1363
CV-24072	6/2/2026 4:06:57 PM	4.07	-0.58	0.0		-4.061	0.579	-10.51		28.5	1414
CV-24072	6/2/2026 4:09:25 PM	-0.81	-0.78	0.0	0.0	0.711	0.707	-10.79		28.49	1362
CV-24072	6/22/2026 10:08:42 AM	-2.64	-2.17			2.620	2.166	-7.55	-7.58	28.51	1381
CV-24073-TF	6/4/2026 8:59:38 AM	8.97	-0.14			0.000	0.148	-7.76	-7.66	28.45	1357
CV-24073-TF	6/4/2026 9:05:52 AM	-0.16	-0.17			0.158	0.188	-7.55	-7.71	28.45	1375
CV-24073-TF	6/10/2026 2:06:19 PM	1.85	-4.98			0.000	5.063	-8.57	-8.41	28.45	1377
CV-24073-TF	6/10/2026 2:07:26 PM	-5.18	-5.56			5.229	5.568	-8.41	-8.65	28.45	1377
CV-24073-TF	6/26/2026 8:59:10 AM	-5.89	-5.70			5.903	5.781	-8.49	-8.72	28.52	1372
CV-24073-TF	6/26/2026 9:00:11 AM	-6.07	-6.07			6.237	6.240	-9.49	-9.51	28.52	1364

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24073-TF	6/30/2026 1:58:39 PM	-7.42	-4.12			7.758	4.131	-11.22	-11.26	28.5	1367
CV-24073-TF	6/30/2026 1:59:55 PM	-3.89	-3.92			3.916	3.917	-11.14	-11.24	28.5	1366
CV-24074	6/4/2026 9:11:06 AM	-2.99	-2.51			3.006	2.548	-7.41	-7.36	28.45	1375
CV-24074	6/16/2026 9:24:52 AM										
CV-24074	6/24/2026 1:10:15 PM	-3.15	-1.43			3.157	1.461	-4.71	-4.85	28.59	1381
CV-24075-TF	6/1/2026 2:36:56 PM	-10.73	-10.62			10.948	10.824	-0.01	0.00	28.55	1372
CV-24075-TF	6/1/2026 2:40:00 PM										
CV-24075-TF	6/1/2026 2:40:00 PM										
CV-24075-TF	6/10/2026 2:18:34 PM	-12.43	-12.33			12.481	12.431	0.00	0.00	28.43	1372
CV-24075-TF	6/24/2026 9:17:11 AM	-12.03	-12.13			12.585	12.635	0.34	0.36	28.6	1368
CV-24075-TF	6/30/2026 2:19:22 PM	-14.16	-14.49			14.552	14.703	0.02	0.08	28.49	1370
CV-24076	6/4/2026 9:16:55 AM	-5.01	-4.99			5.027	5.023	-7.57	-7.94	28.47	1393
CV-24076	6/10/2026 2:27:37 PM	-4.86	-4.92			4.817	4.898	-8.06	-8.48	28.43	1384
CV-24076	6/22/2026 1:41:43 PM	-3.44	-3.36			3.306	3.151	-5.54	-5.60	28.49	1384
CV-24076	6/30/2026 2:39:35 PM	-6.98	-7.08			7.249	7.256	-11.38	-11.41	28.49	1377
CV-24077	6/1/2026 2:47:35 PM	-5.75	-5.77			6.073	6.057	-8.94	-8.86	28.57	1342
CV-24077	6/2/2026 7:49:32 AM	-2.92	-0.93			2.888	0.933	-11.27	-11.62	28.59	1335
CV-24077	6/2/2026 7:52:34 AM	-2.48	-1.75			2.441	1.735	-11.71	-11.84	28.59	1344
CV-24077	6/6/2026 12:27:22 PM										
CV-24077	6/11/2026 3:08:29 PM	-7.77	-4.90	0.0	0.0	7.798	4.490	-8.14		28.39	1365
CV-24077	6/11/2026 3:10:14 PM	-3.96	-3.96	0.0	0.0	3.899	3.754	-8.14		28.39	1375
CV-24077	6/15/2026 2:24:46 PM	-2.86	-2.90			2.872	2.947	-7.30	-7.41	28.61	1336
CV-24077	6/16/2026 7:33:30 AM	-7.05	-5.41			6.950	5.397	-8.42	-7.90	28.59	1339
CV-24077	6/16/2026 7:35:27 AM	-3.15	-3.27			3.129	3.236	-7.98	-8.29	28.59	1343
CV-24077	6/19/2026 10:22:28 AM	-3.94	-3.82	0.0	0.0	3.875	4.155	-5.16		28.75	1319
CV-24077	6/19/2026 10:23:54 AM	-3.48	-3.79	0.0	0.0	3.503	3.625	-4.91		28.75	1394
CV-24077	6/24/2026 1:14:10 PM	-4.93	-4.93			4.925	4.920	-6.07	-6.08	28.6	1360
CV-24077	6/30/2026 11:17:02 AM	-9.33	-5.61	0.0	0.0	9.374	5.583	-11.08		28.66	1388
CV-24077	6/30/2026 11:19:14 AM	-5.96	-5.96	0.0	0.0	5.938	5.935	-11.41		28.66	1381

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24078	6/2/2026 7:45:28 AM	-4.09	-3.02	6.0	9.1	0.098	0.228	-11.06	-11.28	28.59	1335
CV-24078	6/6/2026 12:33:36 PM										
CV-24078	6/16/2026 7:39:27 AM	-0.70	-0.66	4.9	4.9	0.064	0.063	-4.04	-4.71	28.59	1333
CV-24078	6/19/2026 11:42:01 AM										
CV-24078	6/25/2026 3:22:02 PM										
CV-24078	6/25/2026 3:22:24 PM										
CV-24078	6/25/2026 3:23:34 PM										
CV-24078	6/26/2026 1:44:33 PM										
CV-24078	6/26/2026 1:44:44 PM										
CV-24079-TP	6/4/2026 12:07:14 PM	-2.22	-1.24			2.181	1.224	-4.01	-4.25	28.59	1343
CV-24079-TP	6/4/2026 12:09:00 PM	-1.10	-1.11			1.105	1.085	-4.06	-4.02	28.59	1318
CV-24079-TP	6/9/2026 1:56:55 PM	-2.17	-3.60			2.124	3.576	-8.73	-8.32	28.52	1349
CV-24079-TP	6/9/2026 1:57:28 PM	-3.78	-3.78			3.735	3.686	-8.72	-8.69	28.52	1349
CV-24079-TP	6/16/2026 1:51:51 PM	-4.38	-4.40			4.351	4.352	-7.00	-7.24	28.57	1360
CV-24079-TP	6/23/2026 2:42:01 PM	-3.13	-3.07			3.114	3.048	-5.42	-5.05	28.6	1354
CV-24079-TP	6/30/2026 10:39:33 AM	-5.81	-5.89			6.300	6.308	-10.70	-10.03	28.57	1354
CV-24080	6/3/2026 8:57:08 AM	-1.06	-1.06	7.0	8.0	0.134	0.173	-6.14	-6.74	28.55	1361
CV-24080	6/16/2026 9:30:00 AM	-1.40	-1.41	3.3	4.3	0.029	0.051	-5.30	-3.70	28.59	1354
CV-24081-TP	6/3/2026 10:09:44 AM	-2.34	-1.88			2.269	1.830	-7.52	-7.40	28.54	1356
CV-24081-TP	6/16/2026 9:43:47 AM	-2.06	-2.06			2.023	2.025	-7.28	-7.32	28.61	1359
CV-24081-TP	6/23/2026 12:39:08 PM										
CV-24081-TP	6/25/2026 3:13:31 PM										
CV-24081-TP	6/25/2026 3:13:41 PM										
CV-24082	6/3/2026 2:39:26 PM	-0.24	-0.23			0.228	0.215	-6.86	-6.79	28.49	1361
CV-24082	6/16/2026 10:19:49 AM	-0.93	-0.73			0.928	0.745	-7.41	-8.20	28.59	1362
CV-24083	6/3/2026 2:36:38 PM	-0.84	-0.82			0.793	0.787	-6.71	-6.64	28.52	1342
CV-24083	6/15/2026 10:42:17 AM										
CV-24083	6/22/2026 10:20:18 AM	-0.16	-0.16			0.152	0.153	-7.02	-7.04	28.51	1362
CV-24083	6/22/2026 10:20:37 AM	-0.18	-0.18			0.179	0.181	-7.36	-7.34	28.51	1355
CV-24084-TP	6/2/2026 2:30:00 PM										
CV-24084-TP	6/2/2026 2:30:05 PM	-5.74	-5.05			5.896	5.287	-9.00	-9.11	28.62	1375

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24084-TF	6/11/2026 9:56:54 AM	-3.92	-3.06			3.943	3.048	-6.81	-6.48	28.47	1369
CV-24084-TF	6/16/2026 2:12:06 PM	-1.28	-1.04			1.260	0.991	-5.36	-4.76	28.53	1361
CV-24084-TF	6/24/2026 9:57:44 AM	-4.72	-4.72			5.309	5.370	-8.29	-8.08	28.6	1365
CV-24084-TF	6/30/2026 1:30:00 PM	-6.02	-5.94			6.265	6.161	-9.83	-9.51	28.52	1334
CV-24085	6/1/2026 11:07:12 AM	-0.85	-0.81	16.4	16.5	0.765	0.774	-7.93		28.5	1293
CV-24085	6/22/2026 10:40:32 AM	-0.57	-0.53	15.5	16.1	0.668	0.717	-7.10	-6.90	28.57	1349
CV-24086	6/3/2026 8:44:16 AM	-0.37	-0.38	8.6	8.5	0.199	0.196	-5.61	-5.59	28.53	1363
CV-24086	6/16/2026 9:26:38 AM	-0.76	-0.75	6.7	7.1	0.120	0.137	-5.96	-6.65	28.59	1363
CV-24087	6/2/2026 2:23:52 PM	-2.07	-1.97	50.3	46.7	6.980	6.011	-9.93	-10.15	28.55	1370
CV-24087	6/19/2026 2:08:39 PM	-1.24	-1.25	33.5	33.8	3.068	3.120	-5.44	-5.01	28.59	1374
CV-24088	6/3/2026 2:54:01 PM	-0.56	-0.56			0.533	0.530	-5.36	-5.19	28.47	1380
CV-24088	6/22/2026 1:23:31 PM	-1.17	-1.17			1.149	1.137	-4.34	-4.66	28.53	1353
CV-24089	6/1/2026 3:18:19 PM	-9.20	-9.21	0.0	0.0	-0.019	-0.018	-8.97		28.47	1309
CV-24089	6/1/2026 3:20:14 PM	-9.23	-9.25	0.0	0.0	-0.016	-0.013	-9.06		28.47	1319
CV-24089	6/17/2026 1:05:18 PM	-12.73	-12.56	17.5	17.4	0.816	0.814	-12.73	-12.72	28.51	1361
CV-24090	6/1/2026 3:34:26 PM	-1.02	-0.96	0.0	0.0	0.973	0.950	-9.34		28.45	1322
CV-24090	6/17/2026 12:58:09 PM	-1.47	-1.30			1.462	1.291	-12.56	-12.62	28.51	1380
CV-24091	6/2/2026 1:20:08 PM	-0.99	-0.99	1.7	1.7	0.007	0.007	-12.22	-12.22	28.56	1377
CV-24091	6/19/2026 1:33:24 PM	-1.45	-1.63	12.9	13.3	0.429	0.457	-11.95	-12.06	28.58	1396
CV-24092	6/4/2026 8:13:48 AM	-3.87	-3.95	28.5	30.2	2.256	2.536	-10.47	-10.44	28.41	1410
CV-24093	6/4/2026 9:21:34 AM	-0.58	-0.57	16.3	16.7	0.619	0.654	-15.28	-14.98	28.44	1405
CV-24093	6/16/2026 5:45:55 AM	-0.58	-0.58	16.8	16.7	0.657	0.650	-17.39	-17.40	28.48	1388
CV-24094	6/8/2026 12:10:53 PM	3.58	-3.80	0.1	1.5	0.003	0.321	-14.82		28.4	1424
CV-24094	6/8/2026 12:13:02 PM	-3.29	-3.76	1.6	1.6	0.362	0.361	-14.73		28.4	1381
CV-24094	6/22/2026 8:57:15 AM	-3.59	-3.64	1.8	2.0	0.338	0.425	-13.39	-15.04	28.56	1387
CV-24094	6/22/2026 8:58:14 AM	-3.64	-3.57	1.6	2.1	0.260	0.459	-13.69	-13.46	28.56	1387
CV-24095	6/3/2026 10:39:26 AM	0.58	0.78			0.000	0.000	-0.36	-0.63	28.69	1258

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24095	6/3/2026 10:40:36 AM	0.98	1.64			0.000	0.000	-0.22	0.71	28.69	1259
CV-24095	6/3/2026 10:45:00 AM										
CV-24095	6/8/2026 1:35:18 PM	-4.34	-4.30			4.303	4.285	-6.46	-6.45	28.59	1252
CV-24095	6/8/2026 1:36:04 PM	-3.80	-3.83			3.931	3.920	-6.80	-6.76	28.59	1258
CV-24095	6/10/2026 1:17:22 PM	-5.03	-4.58			5.077	4.629	-5.89	-5.50	28.58	1260
CV-24095	6/16/2026 8:20:00 AM										
CV-24095	6/16/2026 8:20:00 AM										
CV-24095	6/17/2026 10:38:51 AM	-0.43	-0.38			0.469	0.481	-1.32	-1.35	28.61	1259
CV-24096	6/11/2026 10:32:09 AM	-1.54	-1.47	0.0	0.0	1.523	1.238	-3.95		28.61	1234
CV-24096	6/11/2026 10:33:45 AM	-1.27	-1.19	0.0	0.0	1.582	0.961	-4.00		28.61	1230
CV-24096	6/12/2026 9:48:27 AM	-0.40	-0.13	0.0	0.0	0.466	0.138	-2.14		28.65	1257
CV-24096	6/25/2026 11:07:44 AM	0.17	-0.02	0.0	0.0	-0.115	0.129	-0.11		28.68	1260
CV-24096	6/25/2026 11:09:58 AM	-0.17	-0.14	0.0	0.0	0.123	0.117	-0.09		28.68	1286
CV-24097	6/10/2026 10:19:39 AM	-5.97	-4.71	0.0	0.0	5.889	5.032	-8.55		28.59	1220
CV-24097	6/16/2026 7:47:31 AM	-3.58	-5.52			3.511	5.539	-5.68	-6.13	28.73	1259
CV-24098	6/1/2026 9:10:16 AM										
CV-24098	6/2/2026 7:53:08 AM										
CV-24098	6/5/2026 10:47:49 AM										
CV-24098	6/6/2026 8:15:18 AM										
CV-24098	6/9/2026 4:08:34 PM										
CV-24098	6/9/2026 4:08:44 PM										
CV-24098	6/10/2026 8:26:44 AM	-10.77	-11.78	0.0	0.0			-10.30		28.59	1312
CV-24098	6/19/2026 12:22:19 PM										
CV-24098	6/25/2026 10:59:13 AM	-9.94	-9.56	0.0	0.0		9.555	-10.08		28.69	1240
CV-24098	6/30/2026 1:29:44 PM										
CV-24098	6/30/2026 1:30:02 PM										
CV-24099	6/10/2026 11:59:36 AM										
CV-24099	6/10/2026 11:59:36 AM										
CV-24099	6/11/2026 10:15:38 AM	-5.28	-5.17	0.0	0.0	4.795	5.240	-7.98		28.6	1234
CV-24099	6/11/2026 10:19:14 AM	-4.76	-4.21	0.0	0.0	4.810	4.207	-7.57		28.6	1250
CV-24099	6/12/2026 9:26:51 AM	-0.66	-0.55	0.0	0.0	0.592	0.529	-6.86		28.63	1243

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24099	6/17/2026 10:19:03 AM	1.48	-0.58			0.000	0.558	-7.84	-6.97	28.62	1258
CV-24099	6/17/2026 10:22:36 AM	-0.61	-0.59			0.599	0.580	-7.27	-7.32	28.62	1266
CV-24100	6/1/2026 9:40:00 AM										
CV-24100	6/1/2026 9:40:00 AM										
CV-24100	6/3/2026 10:14:54 AM	-1.55	-1.56			1.560	1.575	-7.36	-7.73	28.69	1264
CV-24100	6/3/2026 10:15:00 AM										
CV-24100	6/10/2026 1:48:21 PM	-6.93	-3.39			6.990	3.351	-10.66	-10.24	28.55	1257
CV-24100	6/10/2026 1:50:08 PM	-4.58	-4.58			4.575	4.579	-10.77	-10.76	28.57	1256
CV-24100	6/17/2026 8:28:06 AM	-1.25	-0.28			1.229	0.274	-8.04	-8.10	28.62	1264
CV-24100	6/17/2026 10:27:26 AM	-0.17	-1.28			0.152	1.263	-8.30	-8.16	28.62	1287
CV-24100	6/17/2026 10:27:54 AM	-1.34	-1.33			1.347	1.340	-7.44	-7.52	28.64	1286
CV-24101	6/2/2026 7:53:37 AM										
CV-24101	6/4/2026 7:59:12 AM										
CV-24101	6/6/2026 8:14:26 AM										
CV-24101	6/9/2026 2:32:46 PM										
CV-24101	6/9/2026 2:32:58 PM										
CV-24101	6/10/2026 8:31:01 AM	-11.50	-10.58			11.670	10.717	-11.55	-10.53	28.56	1252
CV-24101	6/16/2026 9:30:00 AM										
CV-24101	6/16/2026 9:30:00 AM										
CV-24101	6/17/2026 8:21:54 AM	-7.23	-6.63			7.224	6.605	-7.53	-7.11	28.62	1266
CV-24101	6/19/2026 12:10:06 PM										
CV-24101	6/30/2026 2:47:24 PM										
CV-24101	6/30/2026 2:47:36 PM										
CV-24102	6/2/2026 7:38:32 AM										
CV-24102	6/6/2026 8:13:53 AM										
CV-24102	6/8/2026 1:06:02 PM	-0.76	-0.54			0.764	0.525	-10.95	-10.84	28.59	1273
CV-24102	6/16/2026 8:47:00 AM	-0.15	-0.16			0.162	0.162	-10.88	-10.69	28.67	1281
CV-24102	6/29/2026 1:05:13 PM										
CV-24103	6/1/2026 10:11:29 AM	-1.02	-1.04	3.0	2.5	0.178	0.131	-8.70		28.51	1306
CV-24103	6/17/2026 12:16:15 PM	-0.68	-0.68	1.5	1.5	0.045	0.046	-11.22	-11.25	28.63	1326
CV-24104	6/1/2026 3:09:05 PM	-1.41	-0.34	1.3	1.7	0.183	0.314	-8.80		28.49	1352
CV-24104	6/3/2026 2:45:25 PM										
CV-24104	6/19/2026 2:53:53 PM	-0.29	-0.28	11.2	13.6	1.039	1.171	-11.11		28.53	1381
CV-24105	6/1/2026 2:59:30 PM	-0.20	-0.21	8.1	7.8	0.398	0.372	-9.07		28.47	1312
CV-24105	6/3/2026 2:50:39 PM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24105	6/17/2026 1:20:46 PM	-0.35	-0.35	9.5	9.6	0.568	0.579	-11.98	-11.92	28.51	1363
CV-24106	6/1/2026 3:40:10 PM	-1.10	-0.91	0.0	0.0	-0.048	-0.175	-12.53		28.46	1293
CV-24106	6/19/2026 11:21:28 AM	-0.83	-1.01	7.4	13.7	0.147	0.511	-15.86	-17.32	28.64	1333
CV-24106	6/19/2026 2:40:04 PM	-0.36	-0.36	4.1	4.3	0.045	0.049	-15.23		28.56	1345
CV-24107	6/11/2026 11:00:24 AM	-4.25	-3.87			4.185	3.765	-7.99	-8.16	28.45	1331
CV-24108	6/1/2026 1:18:43 PM										
CV-24108	6/2/2026 9:11:29 AM										
CV-24108	6/3/2026 8:42:03 AM	-12.54	-12.67	46.9	46.7	1.473	1.459	-13.67	-13.72	28.57	1360
CV-24108	6/3/2026 9:24:44 AM										
CV-24108	6/4/2026 8:13:47 AM										
CV-24108	6/5/2026 1:40:27 PM										
CV-24108	6/6/2026 8:22:48 AM										
CV-24108	6/8/2026 3:30:54 PM										
CV-24108	6/8/2026 3:37:11 PM										
CV-24108	6/18/2026 2:02:43 PM										
CV-24108	6/19/2026 11:47:53 AM										
CV-24108	6/24/2026 11:07:23 AM										
CV-24108	6/24/2026 11:07:33 AM										
CV-24108	6/24/2026 11:08:01 AM										
CV-24108	6/24/2026 11:09:51 AM										
CV-24108	6/25/2026 2:12:26 PM										
CV-24108	6/25/2026 2:12:49 PM										
CV-24108	6/29/2026 2:23:43 PM										
CV-24108	6/29/2026 2:23:58 PM										
CV-24109	6/1/2026 1:15:50 PM										
CV-24109	6/2/2026 9:05:54 AM										
CV-24109	6/3/2026 8:29:21 AM	-7.14	-5.35			7.584	5.665	-16.15	-15.47	28.54	1381
CV-24109	6/3/2026 9:19:32 AM										
CV-24109	6/4/2026 8:18:15 AM										
CV-24109	6/5/2026 1:36:04 PM										
CV-24109	6/6/2026 8:36:42 AM										
CV-24109	6/8/2026 3:20:24 PM										
CV-24109	6/8/2026 3:20:49 PM										
CV-24109	6/19/2026 11:42:44 AM										
CV-24109	6/24/2026 11:00:46 AM										
CV-24109	6/24/2026 11:00:54 AM										
CV-24109	6/25/2026 2:01:59 PM										
CV-24109	6/25/2026 2:02:09 PM										
CV-24109	6/29/2026 2:15:54 PM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24109	6/29/2026 2:16:04 PM										
CV-24109	6/29/2026 4:07:05 PM										
CV-24109	6/30/2026 11:41:30 AM	-14.45	-6.03	0.0	0.0		6.007	-18.31		28.38	1339
CV-24110	6/8/2026 11:54:29 AM	-1.32	-1.14	15.9	12.8	0.706	0.458	-16.17		28.4	1394
CV-24110	6/19/2026 9:53:23 AM	-1.55	-1.55	32.2	31.7	0.667	0.646	-21.85	-21.23	28.58	1389
CV-24111	6/3/2026 12:34:12 PM	-6.33	-4.01			6.266	3.912	-12.80	-14.23	28.61	1411
CV-24111	6/19/2026 10:04:31 AM	-3.56	-2.81			3.564	2.808	-20.76	-21.17	28.56	1411
CV-24112	6/8/2026 11:49:51 AM	-0.78	-0.77	11.3	11.3	0.341	0.340	-13.73		28.41	1398
CV-24114	6/10/2026 9:27:53 AM	-14.34	-14.40	14.1	13.7	0.563	0.535	-15.25	-15.20	28.52	1284
CV-24114	6/29/2026 10:36:19 AM										
CV-24116	6/8/2026 3:48:25 PM	-4.93	-2.64	0.0	0.0	4.874	2.718	-13.96		28.54	1289
CV-24117	6/3/2026 11:49:43 AM	-1.28	-1.28			1.245	1.247	-15.42	-15.41	28.63	1295
CV-24118	6/3/2026 9:22:48 AM	-2.15	-2.00			2.137	1.978	-15.68	-15.66	28.63	1298
CV-24119	6/15/2026 10:17:22 AM	4.03	-0.09			0.000	0.108	-16.32	-15.27	28.71	1262
CV-24119	6/15/2026 10:18:25 AM	-0.13	-0.13			0.132	0.134	-15.69	-15.83	28.71	1271
CV-24120	6/5/2026 1:09:53 PM	-7.77	-8.04			7.955	8.148	-7.58	-8.13	28.41	1322
CV-24120	6/10/2026 12:49:09 PM	-9.00	-6.28	0.0	0.0	8.843	6.113	-8.30		28.53	1329
CV-24120	6/12/2026 9:55:00 AM										
CV-24120	6/12/2026 9:55:00 AM										
CV-24120	6/17/2026 1:11:35 PM	-8.24	-8.06			8.311	8.114	-8.16	-8.14	28.56	1356
CV-24120	6/17/2026 1:13:40 PM	-8.06	-8.06			8.188	8.025	-7.99	-8.16	28.56	1359
CV-24121	6/4/2026 8:00:00 AM										
CV-24121	6/4/2026 8:00:00 AM										
CV-24121	6/8/2026 1:33:03 PM	-0.72	-0.69			0.706	0.661	-8.07	-8.35	28.53	1344
CV-24121	6/8/2026 1:35:33 PM	-0.40	-0.39			0.293	0.291	-8.31	-8.32	28.53	1357
CV-24121	6/8/2026 1:37:57 PM	-0.26	-0.27			0.284	0.287	-8.31	-8.14	28.55	1332
CV-24121	6/17/2026 1:02:38 PM	-0.28				0.321		-8.38		28.57	1342

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24121	6/17/2026 1:03:08 PM	-3.46	-3.47			3.473	3.489	-8.38	-8.44	28.6	1343
CV-24121	6/29/2026 11:25:28 AM										
CV-24121	6/29/2026 1:04:01 PM										
CV-24121	6/29/2026 1:04:44 PM										
CV-24122	6/4/2026 8:20:00 AM										
CV-24122	6/4/2026 8:20:00 AM										
CV-24122	6/5/2026 10:41:55 AM	-7.77	-1.84	0.4	0.2	0.007	0.002	-7.76	-7.99	28.46	1305
CV-24122	6/5/2026 10:43:09 AM	-0.31	-0.25	0.3	0.3	0.005	0.003	-8.45	-8.38	28.49	1300
CV-24122	6/17/2026 12:45:58 PM	5.71	-1.07	1.3	0.5	0.036	0.006	-8.00	-8.08	28.58	1345
CV-24122	6/17/2026 12:55:28 PM	-2.47	-2.50	0.5	0.5	0.006	0.005	-7.83	-7.79	28.57	1330
CV-24123	6/9/2026 2:05:21 PM	-3.59	-3.37	10.6	10.1	0.307	0.278	-4.32	-4.64	28.53	1292
CV-24123	6/19/2026 1:07:56 PM	-0.63	-0.72	2.5	2.8	0.017	0.022	-2.75	-2.68	28.68	1268
CV-24123	6/24/2026 7:30:31 AM	-3.72	-3.79	10.2	10.8	0.281	0.318	-6.18	-6.27	28.65	1312
CV-24124	6/5/2026 1:18:36 PM	-2.05	-2.05			1.960	1.948	-7.62	-7.60	28.41	1358
CV-24124	6/5/2026 1:19:19 PM	-2.10	-2.05			1.976	1.972	-7.54	-7.92	28.41	1355
CV-24124	6/26/2026 8:04:01 AM	-3.97	-3.96			3.921	3.916	-10.53	-10.61	28.51	1364
CV-24124	6/26/2026 8:04:44 AM	-4.11	-4.09			4.079	4.068	-10.75	-10.15	28.51	1367
CV-24125-TF	6/3/2026 8:20:00 AM										
CV-24125-TF	6/3/2026 8:20:00 AM										
CV-24125-TF	6/5/2026 10:14:30 AM	-5.39	-2.55			5.425	2.507	-7.82	-7.89	28.46	1334
CV-24125-TF	6/5/2026 1:26:59 PM	-0.23	-0.23			0.000	0.000	-3.99	-3.96	28.41	1363
CV-24125-TF	6/11/2026 3:48:37 PM	-1.94	-1.14	0.0	0.0	2.228	1.084	-1.91		28.42	1260
CV-24125-TF	6/17/2026 12:29:31 PM	-2.09	-2.08			2.111	2.115	-2.87	-2.83	28.57	1339

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24125-TF	6/17/2026 12:38:33 PM	-2.12	-2.13			2.123	2.135	-2.75	-2.80	28.57	1351
CV-24125-TF	6/23/2026 1:29:02 PM										
CV-24125-TF	6/23/2026 1:29:17 PM										
CV-24125-TF	6/26/2026 11:28:57 AM										
CV-24125-TF	6/26/2026 11:29:08 AM										
CV-24125-TF	6/30/2026 11:22:53 AM										
CV-24126	6/1/2026 1:39:04 PM	-2.91	-2.43			2.653	2.431	-3.08	-3.02	28.54	1377
CV-24126	6/1/2026 1:55:00 PM										
CV-24126	6/1/2026 1:55:00 PM										
CV-24126	6/8/2026 1:09:09 PM	-7.06	-8.08			7.137	8.212	-7.13	-8.27	28.48	1376
CV-24126	6/15/2026 10:13:34 AM	-4.91	-4.93			4.852	5.469	-5.42	-5.81	28.61	1362
CV-24126	6/22/2026 1:18:00 PM	-4.26	-4.25			4.233	4.165	-5.09	-5.20	28.53	1375
CV-24126	6/26/2026 1:10:44 PM										
CV-24126	6/29/2026 1:46:26 PM	-6.40	-7.05			6.703	7.220	-8.51	-8.76	28.46	1381
CV-24127	6/1/2026 2:39:12 PM										
CV-24127	6/2/2026 8:17:51 AM										
CV-24127	6/3/2026 8:44:10 AM										
CV-24127	6/4/2026 9:00:33 AM										
CV-24127	6/4/2026 9:10:00 AM										
CV-24127	6/4/2026 9:10:00 AM										
CV-24127	6/5/2026 12:14:23 PM										
CV-24127	6/10/2026 2:32:41 PM										
CV-24127	6/10/2026 2:33:22 PM										
CV-24127	6/12/2026 7:25:49 AM										
CV-24127	6/12/2026 8:12:32 AM	-5.54	-1.27			5.486	1.234	-6.98	-7.10	28.55	1377
CV-24127	6/12/2026 8:14:13 AM	-1.06	-1.06			1.049	1.048	-7.14	-7.16	28.56	1372
CV-24127	6/15/2026 10:05:15 AM	-0.63	-0.65			0.615	0.654	0.36	0.34	28.61	1379
CV-24127	6/19/2026 10:42:55 AM										
CV-24127	6/22/2026 1:16:07 PM	-5.07	-5.43			5.281	5.673	0.01	0.06	28.49	1378
CV-24127	6/23/2026 12:34:42 PM										
CV-24127	6/26/2026 10:26:04 AM	-2.29	-2.00			2.355	2.010	-8.24	-8.54	28.51	1380
CV-24127	6/26/2026 10:26:28 AM	-2.19	-2.23			2.198	2.293	-8.77	-8.63	28.51	1381
CV-24127	6/26/2026 11:18:15 AM										
CV-24127	6/26/2026 11:18:25 AM										
CV-24127	6/29/2026 1:43:55 PM	-7.25	-6.99			7.374	7.107	0.00	0.00	28.46	1380

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24128	6/3/2026 8:10:00 AM										
CV-24128	6/3/2026 8:10:00 AM										
CV-24128	6/4/2026 2:19:54 PM	-1.44	-1.40			1.370	1.347	-6.17	-6.29	28.45	1350
CV-24128	6/10/2026 12:54:14 PM	-0.62	-0.62	0.0	0.0	0.642	0.642	-8.84		28.23	1368
CV-24128	6/17/2026 1:41:36 PM	-0.36	-0.34			0.205	0.227	-6.14	-6.20	28.53	1378
CV-24129	6/2/2026 8:22:22 AM										
CV-24129	6/4/2026 2:23:16 PM	-3.27	-2.89			3.168	2.825	-6.39	-6.60	28.45	1348
CV-24129	6/17/2026 12:18:08 PM	-3.34	-3.60			3.357	3.632	-8.89	-8.86	28.53	1362
CV-24129	6/17/2026 12:19:01 PM	-3.69	-3.68			3.729	3.727	-8.99	-9.10	28.54	1358
CV-24130	6/5/2026 9:53:23 AM	-4.00	-4.22			3.919	4.119	-8.17	-8.40	28.45	1343
CV-24131	6/5/2026 9:45:53 AM	-1.15	-1.14	13.6	13.3	0.510	0.490	-8.81	-8.62	28.45	1336
CV-24132	6/1/2026 8:49:59 AM	-6.70	-6.60	0.0	0.0	0.067	-0.009	-10.20		28.64	1257
CV-24133	6/1/2026 9:23:18 AM	-6.76	-6.74	19.6	22.4	1.041	1.337	-10.21		28.64	1289
CV-24134-TF	6/1/2026 1:35:53 PM	-2.22	-2.33			2.230	2.323	-3.71	-3.95	28.55	1370
CV-24134-TF	6/1/2026 1:50:00 PM										
CV-24134-TF	6/1/2026 1:50:00 PM										
CV-24134-TF	6/8/2026 1:05:55 PM	-4.77	-4.80			4.785	4.801	-6.06	-6.05	28.51	1371
CV-24134-TF	6/15/2026 10:02:38 AM	-5.05	-5.05			5.596	5.594	-7.41	-7.41	28.61	1370
CV-24134-TF	6/22/2026 1:13:16 PM	-4.27	-4.27			4.274	4.272	-5.38	-5.38	28.53	1375
CV-24134-TF	6/29/2026 1:36:41 PM	-2.72	-2.71			2.711	2.684	-3.95	-4.04	28.47	1362
CV-24135	6/4/2026 1:50:11 PM	-1.79	-0.20			1.671	0.149	-5.73	-5.81	28.45	1358
CV-24135	6/16/2026 9:51:38 AM										
CV-24135	6/17/2026 12:00:10 PM	-8.14	-8.25			8.176	8.201	-8.22	-8.32	28.53	1352
CV-24135	6/17/2026 12:02:54 PM	-8.15	-7.01			8.198	7.001	-8.15	-8.20	28.53	1354
CV-24135	6/17/2026 12:07:10 PM	-6.99	-1.07			6.939	1.069	-8.09	-8.39	28.53	1357

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24135	6/17/2026 12:12:01 PM	-5.41	-5.50			5.504	5.528	-7.97	-8.00	28.54	1360
CV-24135	6/17/2026 12:13:45 PM	-7.68	-7.68			7.764	7.737	-8.08	-7.88	28.53	1353
CV-24135	6/26/2026 9:05:20 AM										
CV-24135	6/30/2026 12:03:49 PM	-6.31	-0.85	0.0	0.0	6.260	0.867	-6.87		28.47	1332
CV-24135	6/30/2026 12:05:26 PM	-0.84	-0.83	0.0	0.0	0.828	0.822	-6.82		28.47	1414
CV-24136	6/4/2026 12:45:38 PM	-3.39	-3.00			3.358	2.948	-8.70	-9.23	28.52	1326
CV-24136	6/4/2026 12:48:47 PM	-2.97	-2.97			2.876	2.924	-9.15	-9.13	28.52	1329
CV-24137	6/15/2026 9:10:06 AM	-2.20	-2.19			2.150	2.142	0.02	0.00	28.67	1374
CV-24138	6/1/2026 9:23:15 AM										
CV-24138	6/1/2026 9:25:00 AM										
CV-24138	6/1/2026 9:25:00 AM										
CV-24138	6/2/2026 7:36:39 AM										
CV-24138	6/3/2026 7:54:50 AM										
CV-24138	6/4/2026 3:06:11 PM										
CV-24138	6/6/2026 8:16:09 AM										
CV-24138	6/9/2026 3:28:51 PM										
CV-24138	6/9/2026 3:29:09 PM										
CV-24138	6/10/2026 8:38:31 AM	-1.71	-8.11	0.0	0.0	1.958	5.529	-6.10		28.56	1260
CV-24138	6/10/2026 8:42:15 AM	-3.35	-2.97	0.0	0.6	3.458	3.907	-3.25		28.56	1257
CV-24138	6/11/2026 10:55:56 AM	-3.18	-3.61			3.122	3.561	-2.67	-3.33	28.58	1261
CV-24138	6/16/2026 8:25:00 AM										
CV-24138	6/16/2026 8:25:00 AM										
CV-24138	6/17/2026 8:54:02 AM	-2.51	-2.52			2.479	2.571	-2.60	-2.20	28.63	1274
CV-24138	6/17/2026 8:54:25 AM	-2.38	-2.34			2.354	2.409	-2.55	-1.94	28.63	1271
CV-24138	6/17/2026 1:42:39 PM	-2.01	-1.91			2.030	1.856	-2.65	-2.41	28.62	1313
CV-24138	6/18/2026 9:36:58 AM										
CV-24138	6/19/2026 12:31:39 PM										
CV-24138	6/26/2026 9:57:18 AM	-4.64	-3.81			4.604	4.013	-4.33	-3.95	28.63	1283
CV-24138	6/26/2026 9:57:58 AM	-3.71	-3.75			3.462	3.715	-3.75	-3.45	28.63	1277
CV-24138	6/26/2026 3:55:26 PM										
CV-24138	6/26/2026 3:55:54 PM										
CV-24138	6/30/2026 1:41:18 PM										
CV-24138	6/30/2026 1:41:29 PM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24139	6/1/2026 9:20:00 AM										
CV-24139	6/1/2026 9:20:00 AM										
CV-24139	6/1/2026 9:26:24 AM										
CV-24139	6/1/2026 12:37:56 PM										
CV-24139	6/2/2026 7:37:33 AM										
CV-24139	6/3/2026 7:55:49 AM										
CV-24139	6/4/2026 3:07:26 PM										
CV-24139	6/5/2026 10:54:02 AM										
CV-24139	6/6/2026 7:54:14 AM										
CV-24139	6/9/2026 3:23:00 PM										
CV-24139	6/9/2026 3:23:50 PM										
CV-24139	6/10/2026 8:49:20 AM	-6.96	-3.36	0.0	0.0	7.630	3.337	-7.52		28.48	1214
CV-24139	6/10/2026 8:51:40 AM	-2.75	-1.31	0.0	0.0	2.724	1.682	-7.56		28.48	1250
CV-24139	6/16/2026 8:30:00 AM										
CV-24139	6/16/2026 8:30:00 AM										
CV-24139	6/17/2026 9:00:45 AM	-5.68	-2.12			5.797	2.121	-5.71	-5.41	28.63	1271
CV-24139	6/17/2026 9:01:29 AM	-0.25	-0.27			0.256	0.265	-4.92	-3.97	28.61	1270
CV-24139	6/18/2026 9:24:33 AM										
CV-24139	6/18/2026 9:33:37 AM										
CV-24139	6/19/2026 12:36:43 PM										
CV-24139	6/26/2026 10:05:15 AM	-5.09	-4.90			5.258	5.086	-5.46	-5.32	28.63	1274
CV-24139	6/26/2026 10:05:49 AM	-4.71	-4.72			4.670	4.679	-5.47	-5.78	28.63	1274
CV-24139	6/26/2026 3:54:38 PM										
CV-24139	6/26/2026 3:54:47 PM										
CV-24139	6/30/2026 1:47:54 PM										
CV-24139	6/30/2026 1:48:05 PM										
CV-24140	6/1/2026 9:15:00 AM										
CV-24140	6/1/2026 9:15:00 AM										
CV-24140	6/1/2026 9:32:55 AM										
CV-24140	6/2/2026 7:51:34 AM										
CV-24140	6/3/2026 7:56:51 AM										
CV-24140	6/3/2026 12:47:00 PM	-1.41	-1.69			1.403	1.670	-4.73	-5.38	28.66	1274
CV-24140	6/3/2026 12:55:00 PM										
CV-24140	6/4/2026 3:08:04 PM										
CV-24140	6/5/2026 10:55:44 AM										
CV-24140	6/6/2026 8:16:54 AM										
CV-24140	6/9/2026 3:19:36 PM										
CV-24140	6/9/2026 3:19:52 PM										
CV-24140	6/10/2026 8:58:38 AM	-4.24	-3.59	0.0	0.0	4.142	3.879	-7.30		28.56	1247

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24140	6/10/2026 9:02:51 AM	-3.53	-2.40	0.0	0.0	3.640	2.469	-7.28		28.56	1273
CV-24140	6/10/2026 1:06:06 PM	-1.86	-1.86			1.881	1.883	-6.35	-6.38	28.55	1300
CV-24140	6/16/2026 8:35:00 AM										
CV-24140	6/16/2026 8:35:00 AM										
CV-24140	6/17/2026 1:29:57 PM	0.97	-1.59			0.000	1.588	-2.80	-3.16	28.6	1294
CV-24140	6/17/2026 1:30:23 PM	-1.54	-1.18			1.590	1.188	-2.61	-2.15	28.6	1296
CV-24140	6/18/2026 9:34:12 AM										
CV-24140	6/18/2026 9:34:21 AM										
CV-24140	6/19/2026 12:38:35 PM										
CV-24140	6/26/2026 10:09:15 AM	-2.54	-2.52			2.533	2.495	-3.61	-3.77	28.63	1288
CV-24140	6/26/2026 10:09:34 AM	-2.46	-2.46			2.423	2.423	-3.57	-3.57	28.63	1285
CV-24140	6/26/2026 3:53:37 PM										
CV-24140	6/26/2026 3:53:50 PM										
CV-24140	6/30/2026 2:49:55 PM										
CV-24140	6/30/2026 2:50:16 PM										
CV-24141	6/11/2026 11:16:59 AM	-5.05	-4.97	0.0	0.0	4.864	4.861	-4.76		28.56	1329
CV-24141	6/11/2026 11:18:59 AM	-5.05	-4.81	0.0	0.0	4.847	4.690	-4.52		28.56	1322
CV-24141	6/12/2026 9:30:00 AM										
CV-24141	6/12/2026 9:30:00 AM										
CV-24141	6/12/2026 10:41:06 AM	-0.85	-0.23	0.0	0.0	0.915	0.358	-2.87		28.58	1296
CV-24141	6/12/2026 10:43:21 AM	-0.59	-0.44	0.0	0.0	0.520	0.467	-2.72		28.58	1299
CV-24141	6/17/2026 9:19:34 AM	-0.92	-0.54			0.817	0.857	-1.06	-0.13	28.58	1299
CV-24141	6/17/2026 9:20:54 AM	-0.92	-0.88			0.916	0.883	-0.73	-1.11	28.59	1298
CV-24142	6/1/2026 9:19:23 AM										
CV-24142	6/2/2026 7:52:39 AM										
CV-24142	6/3/2026 7:53:09 AM										
CV-24142	6/4/2026 9:05:00 AM										
CV-24142	6/4/2026 9:05:00 AM										
CV-24142	6/4/2026 3:04:27 PM										
CV-24142	6/5/2026 10:52:26 AM										
CV-24142	6/6/2026 7:49:57 AM										
CV-24142	6/11/2026 1:39:28 PM	-5.90	-5.74			6.024	5.851	-5.81	-5.63	28.53	1255
CV-24142	6/17/2026 8:43:53 AM	-1.65	-1.57			1.652	1.574	-1.59	-1.50	28.61	1264
CV-24142	6/18/2026 9:43:28 AM										
CV-24142	6/18/2026 9:43:58 AM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24142	6/19/2026 12:27:49 PM										
CV-24142	6/26/2026 9:52:53 AM	-2.16	-2.15			2.109	2.126	-2.04	-2.04	28.63	1264
CV-24142	6/26/2026 9:53:35 AM	-1.96	-1.92			2.017	1.953	-1.81	-1.69	28.63	1267
CV-24142	6/26/2026 3:56:35 PM										
CV-24142	6/26/2026 3:56:49 PM										
CV-24142	6/30/2026 2:48:45 PM										
CV-24142	6/30/2026 2:48:56 PM										
CV-24143	6/1/2026 9:05:00 AM										
CV-24143	6/1/2026 9:05:00 AM										
CV-24143	6/1/2026 12:34:41 PM	-7.32	-7.01			7.076	6.828	-7.08	-7.08	28.7	1290
CV-24143	6/1/2026 12:36:01 PM	-7.01	-6.82			6.818	6.656	-7.08	-7.08	28.71	1287
CV-24143	6/2/2026 7:50:48 AM										
CV-24143	6/6/2026 8:18:45 AM										
CV-24143	6/11/2026 1:51:00 PM	-7.15	-6.76			7.305	6.898	-7.95	-7.78	28.52	1279
CV-24143	6/12/2026 7:36:10 AM										
CV-24143	6/15/2026 2:49:28 PM	-2.88	-1.36			2.912	1.370	-3.28	-3.16	28.68	1289
CV-24143	6/15/2026 2:50:17 PM	-1.38	-1.37			1.405	1.380	-3.33	-2.91	28.68	1296
CV-24143	6/16/2026 8:40:00 AM										
CV-24143	6/16/2026 8:40:00 AM										
CV-24143	6/17/2026 9:12:04 AM	-0.47	-0.48			0.466	0.472	0.00	0.00	28.59	1287
CV-24143	6/19/2026 2:17:30 PM	-0.86	-0.88	0.0	0.0	0.963	0.958	-1.04		28.58	1220
CV-24143	6/19/2026 2:20:36 PM	-0.90	-0.87	0.0	0.0	0.954	0.871	-0.99		28.58	1289
CV-24143	6/23/2026 12:37:57 PM										
CV-24143	6/26/2026 2:23:39 PM										
CV-24143	6/26/2026 2:23:48 PM										
CV-24144	6/10/2026 10:15:37 AM	-7.75	-7.73	0.0	0.0	7.446	7.729	-7.31		28.6	1204
CV-24144	6/16/2026 7:55:40 AM	-3.54	-3.53			3.486	3.452	-3.56	-3.60	28.74	1251
CV-24144	6/30/2026 1:46:16 PM	-4.48	-4.63			4.472	4.596	-4.36	-4.47	28.69	1255
CV-24145	6/9/2026 9:28:49 AM	-9.12	-9.15			0.034	0.009	-10.94	-10.94	28.51	1380
CV-24145	6/25/2026 9:07:34 AM	-9.39	-9.23	3.3	0.0	0.019	-0.005	-10.71		28.55	1378
CV-24145	6/25/2026 9:10:07 AM	-4.87	-0.89	5.1	0.0	0.042	-0.011	-10.68		28.55	1358
CV-24145	6/25/2026 9:15:45 AM	-0.07	-0.08	0.0	0.0	-0.016	-0.017	-10.96		28.55	1339

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24146	6/8/2026 12:31:18 PM	1.89	-0.11	7.9	15.9	0.079	0.322	-3.93	-3.45	28.54	1284
CV-24146	6/8/2026 12:36:09 PM	-0.18	-0.19	14.8	15.2	0.503	0.529	-3.16	-3.09	28.53	1278
CV-24146	6/8/2026 12:36:53 PM	-0.18	-0.16	14.9	14.8	0.508	0.501	-3.36	-3.65	28.53	1269
CV-24146	6/19/2026 1:14:29 PM	2.74	2.75	1.4	1.0	0.004	0.002	2.99	3.00	28.68	1297
CV-24146	6/19/2026 1:16:24 PM	2.74	2.74	2.1	2.0	0.009	0.009	2.98	2.98	28.69	1301
CV-24146	6/24/2026 7:32:54 AM	-4.66	-4.64	24.9	26.3	0.805	0.902	-6.09	-6.12	28.64	1297
CV-24147	6/1/2026 7:56:42 AM	-1.87	-1.86	0.0	0.0	-0.033	-0.005	-1.63		28.61	1280
CV-24147	6/17/2026 9:42:16 AM	-3.19	-3.14	5.6	5.5	0.008	0.008	-3.21	-3.17	28.58	1273
CV-24147	6/19/2026 1:22:48 PM	-2.87	-3.06	10.3	7.3	0.027	0.014	-2.72	-3.14	28.68	1283
CV-24148	6/3/2026 1:36:29 PM	-7.53	-3.33			7.506	3.368	-13.10	-11.14	28.58	1381
CV-24148	6/3/2026 1:37:51 PM	-3.40	-3.45			3.341	3.448	-11.09	-11.09	28.57	1383
CV-24148	6/3/2026 1:50:00 PM										
CV-24148	6/8/2026 2:26:31 PM	-6.65	-0.08			6.646	0.071	-10.86	-11.29	28.44	1378
CV-24148	6/24/2026 9:05:55 AM	-4.02	-4.01			4.017	4.011	-11.71	-12.00	28.6	1378
CV-24148	6/30/2026 2:31:22 PM	-5.04	-5.04			5.311	5.316	-13.87	-13.61	28.49	1372
CV-24149	6/3/2026 8:58:20 AM										
CV-24149	6/8/2026 2:11:13 PM	-8.39	-8.33	0.0	0.0	-0.051	-0.044			28.4	1388
CV-24149	6/24/2026 12:42:45 PM	1.22	-0.13	22.7	5.6	0.132	0.008	-3.87	-3.77	28.55	1366
CV-24149	6/24/2026 12:44:13 PM	-0.20	-0.22	4.8	9.8	0.006	0.025	-3.63	-3.59	28.55	1369
CV-24149	6/24/2026 1:06:46 PM	-0.63	-0.65	8.9	12.9	0.021	0.043	-4.46	-4.60	28.59	1382
CV-24150	6/8/2026 12:03:23 PM	-1.10	-0.98	0.0	0.0	0.986	0.926	-16.74		28.4	1394
CV-24150	6/19/2026 10:24:05 AM	-1.62	-1.63			1.623	1.623	-21.56	-23.92	28.58	1387
CV-24151	6/11/2026 9:19:01 AM	-3.82	-3.74	0.0	0.0	3.772	3.714	-6.66		28.47	1378
CV-24151	6/12/2026 11:02:29 AM	-0.94	-0.82	0.0	0.0	0.991	0.764	-6.40		28.5	1365
CV-24151	6/22/2026 9:49:24 AM	-1.03	-1.04			1.025	1.033	-7.58	-7.70	28.48	1390
CV-24152	6/4/2026 8:50:55 AM	-0.44	-0.24	19.8	17.8	0.937	0.758	-4.68	-4.81	28.44	1379
CV-24152	6/4/2026 8:52:46 AM	-0.24	-0.24	17.8	18.1	0.757	0.785	-4.85	-4.82	28.44	1385

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24152	6/22/2026 9:16:13 AM	0.84	-0.10	18.1	28.3	0.784	1.938	-5.18	-4.99	28.49	1377
CV-24152	6/22/2026 9:16:43 AM	-0.15	-0.14	28.5	28.5	1.959	1.961	-5.03	-4.93	28.49	1385
CV-24152	6/22/2026 9:17:01 AM	-0.15	-0.16	28.7	28.6	1.996	1.982	-4.99	-4.99	28.49	1386
CV-24153	6/8/2026 2:34:56 PM	0.60	-0.03			0.000	0.043	-13.18	-13.44	28.41	1392
CV-24153	6/8/2026 2:36:19 PM	-0.17	-0.16			0.123	0.122	-13.12	-13.54	28.41	1395
CV-24153	6/16/2026 12:58:16 PM	-0.17	-0.17			0.161	0.162	-13.54	-12.78	28.55	1388
CV-24154	6/4/2026 9:27:01 AM	-2.01	-1.92			2.002	1.904	-8.22	-7.08	28.44	1390
CV-24154	6/16/2026 5:48:54 AM	-2.63	-2.15			2.616	2.133	-11.51	-14.71	28.5	1389
CV-24154	6/24/2026 8:27:55 AM	-0.58	-0.57			0.571	0.563	-4.26	-4.05	28.56	1387
CV-24155	6/4/2026 9:16:47 AM	-0.51	-0.31			0.511	0.317	-8.45	-8.59	28.44	1385
CV-24155	6/16/2026 1:01:24 PM	1.13	-0.10			0.000	0.090	-9.41	-8.23	28.55	1381
CV-24155	6/16/2026 1:01:57 PM	-0.20	-0.20			0.177	0.177	-8.46	-8.44	28.55	1386
CV-24155	6/16/2026 1:02:49 PM	-0.18	-0.18			0.151	0.152	-8.77	-8.83	28.55	1386
CV-24156	6/2/2026 3:57:37 PM	-0.35	-0.38	76.6	73.0	1.607	1.462	-9.64		28.49	1398
CV-24156	6/2/2026 4:00:44 PM	-0.32	-0.33	66.8	66.7	1.239	1.236	-10.19		28.49	1365
CV-24156	6/22/2026 10:04:13 AM	-0.29	-0.29	50.9	49.7	0.686	0.654	-5.11	-5.05	28.49	1387
CV-24156	6/22/2026 10:04:37 AM	-0.23	-0.24	49.2	45.7	0.641	0.552	-4.61	-4.57	28.49	1390
CV-24157	6/2/2026 3:51:09 PM	-2.28	-1.64	0.0	0.0	2.068	1.370	-9.72		28.51	1457
CV-24157	6/16/2026 6:16:54 AM	-1.03	-0.72			1.019	0.715	-6.74	-6.71	28.52	1392
CV-24158	6/4/2026 12:34:30 PM	-1.91	-1.86	37.1	35.4	3.841	3.501	-6.01	-6.07	28.45	1393
CV-24158	6/22/2026 9:54:22 AM	-2.40	-2.39	29.3	28.0	2.400	2.190	-5.50	-5.20	28.48	1402
CV-24159	6/4/2026 8:31:58 AM	-0.66	-0.65	23.2	23.6	1.286	1.333	-15.21	-15.82	28.41	1390
CV-24159	6/16/2026 5:43:15 AM	-1.12	-1.00	24.9	20.0	1.471	0.948	-17.54	-17.39	28.48	1396
CV-24160	6/4/2026 8:28:00 AM	-3.95	-3.95	26.1	25.8	1.625	1.588	-15.59	-15.56	28.41	1391
CV-24160	6/16/2026 5:53:37 AM	-4.32	-3.91	27.2	21.5	1.768	1.106	-17.60	-17.51	28.49	1399
CV-24160	6/24/2026 8:22:58 AM	-3.21	-3.36	22.7	23.4	1.222	1.307	-16.26	-16.17	28.55	1404
CV-24161	6/8/2026 2:46:05 PM	-0.48	-0.48			0.461	0.458	-17.83	-15.47	28.41	1418
CV-24161	6/9/2026 12:29:35 PM	-0.64	-0.61			0.535	0.551	-15.75	-17.01	28.45	1396

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24162	6/1/2026 1:17:47 PM										
CV-24162	6/2/2026 9:08:14 AM										
CV-24162	6/2/2026 9:08:14 AM										
CV-24162	6/2/2026 9:08:14 AM										
CV-24162	6/3/2026 8:33:29 AM	-0.75	-0.76			0.759	0.756	-15.16	-14.90	28.55	1379
CV-24162	6/3/2026 9:23:01 AM										
CV-24162	6/4/2026 8:15:24 AM										
CV-24162	6/5/2026 1:38:35 PM										
CV-24162	6/6/2026 8:26:15 AM										
CV-24162	6/8/2026 3:24:54 PM										
CV-24162	6/8/2026 3:27:01 PM										
CV-24162	6/8/2026 3:28:04 PM										
CV-24162	6/19/2026 11:45:45 AM										
CV-24162	6/23/2026 2:28:37 PM										
CV-24162	6/23/2026 2:28:46 PM										
CV-24163	6/2/2026 1:04:07 PM	0.63	-0.03			0.000	0.036	-16.31	-16.24	28.63	1328
CV-24163	6/2/2026 1:04:55 PM	-0.03	-0.03			0.060	0.052	-16.12	-16.58	28.63	1337
CV-24164	6/3/2026 2:50:38 PM	-0.55	-0.53			0.457	0.413	-6.68	-6.71	28.47	1356
CV-24164	6/16/2026 10:15:41 AM	-0.13	-0.13			0.129	0.116	-7.21	-6.79	28.58	1355
CV-24164	6/16/2026 10:16:45 AM	-0.08	-0.08			0.093	0.081	-7.62	-7.00	28.58	1362
CV-24165	6/2/2026 2:39:55 PM	-6.42	-6.42			6.429	6.438	-8.17	-8.20	28.52	1375
CV-24165	6/22/2026 1:17:09 PM	-6.28	-6.29			6.267	6.291	-7.70	-7.75	28.53	1386
CV-24166	6/2/2026 10:42:56 AM	-7.88	-6.56			8.135	6.857	-9.73	-9.94	28.55	1394
CV-24166	6/16/2026 5:40:44 AM	-7.07	-7.18			7.011	7.036	-11.46	-12.08	28.48	1390
CV-24167	6/11/2026 8:37:37 AM	-2.97	-2.95			2.892	2.882	-7.80	-7.78	28.41	1410
CV-24167	6/22/2026 1:02:56 PM	-3.06	-3.07			3.089	3.091	-8.21	-8.97	28.5	1407
CV-24168	6/2/2026 2:31:57 PM	-2.72	-1.86			2.631	1.803	-8.61	-8.79	28.52	1386
CV-24168	6/16/2026 6:07:33 AM	-2.78	-2.46			2.765	2.454	-12.15	-12.18	28.5	1390
CV-24169	6/2/2026 2:27:55 PM	-0.49	-0.49			0.493	0.492	-11.53	-11.60	28.55	1380
CV-24169	6/3/2026 10:21:30 AM										
CV-24169	6/16/2026 10:26:18 AM	-0.33	-0.33			0.342	0.338	-6.04	-5.89	28.56	1371
CV-24170	6/3/2026 8:39:31 AM	1.95	-0.23	6.3	49.5	0.025	1.601	-5.40	-5.14	28.52	1367

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24170	6/3/2026 8:40:16 AM	-0.46	-0.53	46.9	48.1	1.439	1.515	-4.46	-5.32	28.53	1368
CV-24170	6/16/2026 9:47:43 AM	-1.84	-1.00	71.1	61.3	1.291	0.958	-6.82	-7.41	28.59	1357
CV-24170	6/16/2026 9:48:20 AM	-0.92	-0.92	53.2	53.7	0.721	0.732	-6.25	-6.41	28.59	1354
CV-24171	6/2/2026 1:07:59 PM	-1.76	-1.75	18.5	18.6	0.456	0.459	0.04	0.04	28.56	1388
CV-24171	6/19/2026 1:15:27 PM	-1.66	-1.64	19.7	17.3	0.514	0.397	0.07	0.07	28.58	1383
CV-24172	6/2/2026 2:04:51 PM	-0.54	-0.51	13.2	13.1	0.470	0.468	-11.92	-11.92	28.52	1380
CV-24172	6/19/2026 1:40:24 PM	-0.26	-0.26	9.8	9.7	0.262	0.257	-11.89	-11.89	28.58	1378
CV-24173	6/2/2026 2:09:46 PM	-2.09	-2.08	29.5	30.1	2.023	2.119	0.04	0.04	28.53	1384
CV-24173	6/19/2026 1:42:31 PM	-1.30	-1.31	31.5	31.5	2.340	2.349	0.11	0.07	28.58	1386
CV-24174	6/11/2026 8:53:10 AM	-3.03	-3.03			2.954	2.958	0.22	0.22	28.41	1429
CV-24174	6/22/2026 8:34:05 AM	-3.64	-3.52			3.660	3.548	-12.31	-12.09	28.48	1392
CV-24175	6/2/2026 2:16:56 PM	-1.36	-1.32	18.2	17.3	0.908	0.822	-11.33	-10.49	28.56	1374
CV-24175	6/19/2026 1:53:40 PM	-1.32	-1.33	17.9	18.8	0.879	0.965	-11.51	-11.75	28.59	1360
CV-24175	6/22/2026 8:43:24 AM	-1.52	-1.19	38.3	28.7	0.949	0.530	-12.16	-12.29	28.5	1400
CV-24175	6/22/2026 9:19:56 AM	-1.05	-1.06	30.2	31.9	0.586	0.656	-12.05	-12.90	28.53	1376
CV-24176	6/1/2026 11:10:13 AM	-0.59	-0.58	9.0	9.1	0.279	0.284	-8.03		28.48	1430
CV-24176	6/1/2026 11:12:09 AM	-0.59	-0.59	9.2	9.3	0.297	0.298	-8.21		28.48	1388
CV-24176	6/24/2026 12:52:18 PM	-0.12	-0.13	0.5	2.6	0.001	0.018	-3.38	-3.21	28.59	1348
CV-24177	6/2/2026 9:39:48 AM	-2.82	-0.74			2.783	0.746	-11.23	-11.14	28.64	1322
CV-24177	6/2/2026 9:40:38 AM	-0.55	-0.55			0.572	0.571	-11.27	-11.33	28.63	1318
CV-24177	6/16/2026 8:58:44 AM	-0.47	-0.46			0.495	0.483	-9.27	-9.29	28.65	1313
CV-24177	6/16/2026 9:02:31 AM	-0.09	-0.09			0.106	0.104	-9.02	-8.87	28.63	1310
CV-24177	6/25/2026 2:15:12 PM	0.04	-0.08			0.000	0.002	-11.51	-11.74	28.58	1312
CV-24177	6/25/2026 2:18:20 PM	-0.05	-0.05			0.003	0.023	-11.42	-11.51	28.58	1320
CV-24178	6/1/2026 11:20:23 AM	-1.01	-0.91	9.3	7.5	0.267	0.177	-7.77		28.49	1378

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24178	6/22/2026 9:49:05 AM	-0.12	-0.13	1.8	2.3	0.008	0.013	-6.56	-7.54	28.53	1358
CV-24178	6/22/2026 9:57:54 AM	-1.08	-1.10	13.5	13.1	0.503	0.473	-7.34	-7.63	28.53	1363
CV-24178	6/22/2026 9:59:40 AM	-0.99	-0.98	14.9	14.4	0.606	0.572	-8.24	-8.31	28.53	1360
CV-24179	6/1/2026 11:02:27 AM	-1.06	-1.02	7.2	7.3	0.160	0.165	-7.90		28.5	1325
CV-24179	6/22/2026 10:33:02 AM	-0.47	-0.46	8.5	7.7	0.200	0.166	-8.91	-7.90	28.57	1347
CV-24179	6/22/2026 10:34:07 AM	-0.51	-0.51	7.4	7.3	0.153	0.148	-8.21	-7.91	28.57	1351
CV-24180	6/9/2026 2:18:49 PM										
CV-24180	6/9/2026 2:19:23 PM										
CV-24180	6/15/2026 2:02:30 PM	-4.76	-3.53	33.2	34.7	0.749	0.819	-8.82		28.54	1309
CV-24180	6/18/2026 2:51:11 PM										
CV-24180	6/18/2026 2:51:21 PM										
CV-24180	6/22/2026 10:24:27 AM	-2.15	-1.90	14.1	14.1	0.550	0.549	-6.72	-7.38	28.54	1365
CV-24180	6/30/2026 2:57:39 PM										
CV-24180	6/30/2026 2:57:51 PM										
CV-24181	6/1/2026 3:15:10 PM	-0.57	-0.55	3.9	2.3	1.854	0.659	-9.16		28.47	1342
CV-24181	6/17/2026 1:10:56 PM	-0.81	-0.56	4.9	2.5	2.537	0.674	-8.63	-8.49	28.51	1358
CV-24182	6/1/2026 3:27:50 PM	-0.49	-0.50	0.0	0.0	0.521	0.518	-9.40		28.46	1339
CV-24182	6/17/2026 1:26:50 PM	-0.61	-0.57			0.588	0.563	-11.62	-11.24	28.5	1358
CV-24183	6/1/2026 3:31:15 PM	-0.73	-0.73	0.0	0.0	0.767	0.763	-8.60		28.46	1352
CV-24183	6/17/2026 1:29:18 PM	-0.91	-0.90			0.903	0.888	-11.41	-11.33	28.51	1359
CV-24184	6/1/2026 12:51:50 PM	-0.06	-0.06	0.0	0.2	0.000	0.001	-8.90		28.5	1407
CV-24184	6/17/2026 1:31:52 PM	-0.04	-0.04	1.0	1.0	0.022	0.022	-11.62	-11.62	28.51	1357
CV-24185	6/8/2026 3:06:30 PM	-0.74	-0.73	23.5	23.3	1.526	1.501	-11.59	-11.35	28.45	1362
CV-24185	6/8/2026 3:09:02 PM	-2.36	-2.34	4.7	5.0	0.057	0.067	-11.28	-11.09	28.45	1357
CV-24185	6/17/2026 12:50:10 PM	-0.85	-0.80	23.6	20.9	1.522	1.195	-12.30	-12.47	28.51	1367
CV-24186	6/8/2026 2:54:43 PM	-0.84	-0.85	42.0	41.7	1.149	1.135	-11.41	-11.44	28.44	1374
CV-24186	6/22/2026 12:55:19 PM	-0.73	-0.72	19.2	20.3	1.019	1.144	-10.17	-10.29	28.53	1376
CV-24187	6/8/2026 1:08:58 PM	-0.66	-0.59	8.2	7.3	0.183	0.146	-10.44	-10.28	28.55	1306
CV-24187	6/16/2026 8:29:13 AM	-0.15	-0.18	9.7	9.4	0.260	0.242	-9.34	-9.51	28.64	1304
CV-24188	6/8/2026 12:56:31 PM	-3.86	-3.40	9.5	10.2	0.248	0.281	-11.26	-13.96	28.59	1251
CV-24188	6/16/2026 8:43:18 AM	-1.76	-2.19	3.5	6.5	0.033	0.113	-9.71	-11.34	28.7	1255
CV-24189	6/8/2026 12:53:01 PM	-2.45	-2.18	8.4	6.3	1.504	0.852	-10.83	-11.54	28.59	1253

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24189	6/16/2026 8:39:57 AM	-1.21	-0.99	5.8	4.1	0.703	0.357	-10.02	-9.84	28.69	1243
CV-24190	6/8/2026 1:11:34 PM	-5.28	-5.32	14.0	15.2	0.539	0.639	-10.68	-11.35	28.55	1305
CV-24190	6/16/2026 8:31:35 AM	-4.63	-4.71	13.6	14.5	0.512	0.582	-8.97	-7.81	28.65	1319
CV-24192	6/8/2026 1:14:16 PM	-9.84	-9.91	12.2	11.1	0.354	0.295	-11.01	-11.14	28.55	1295
CV-24192	6/16/2026 8:33:52 AM	-9.93	-10.18	15.9	16.2	0.598	0.625	-9.97	-12.04	28.67	1298
CV-24193	6/1/2026 10:14:52 AM	-8.10	-8.09	0.0	0.0	-0.120	-0.123	-8.89		28.5	1299
CV-24193	6/17/2026 11:31:31 AM	-10.24	-9.95	13.7	16.2	0.326	0.452	-11.65	-11.72	28.63	1330
CV-24194	6/1/2026 3:11:56 PM	-2.00	-1.98	3.1	3.1	0.987	0.987	-9.08		28.47	1253
CV-24194	6/17/2026 1:13:48 PM	-2.73	-2.63	21.6	15.9	1.063	0.572	-11.91	-11.68	28.51	1348
CV-24195	6/1/2026 3:04:18 PM	-0.84	-0.72	14.2	10.8	4.211	2.417	-9.26		28.47	1368
CV-24195	6/17/2026 1:18:31 PM	-0.75	-0.75	12.8	12.7	3.485	3.422	-12.13	-12.04	28.51	1338
CV-24196	6/1/2026 2:55:48 PM	-1.43	-1.46	7.4	0.0	0.068	-0.155	-9.50		28.63	1348
CV-24196	6/17/2026 12:42:15 PM	-1.87	-1.56			1.061	1.388	-12.27	-12.29	28.51	1348
CV-24197	6/11/2026 8:52:25 AM	-1.99	-1.98	33.8	33.9	3.055	3.071	-9.88		28.49	1490
CV-24197	6/11/2026 11:07:01 AM	-1.75	-1.76	31.4	31.1	2.754	2.697	0.55	0.55	28.45	1339
CV-24197	6/22/2026 12:45:39 PM	-1.88	-1.84	33.9	33.5	3.200	3.120	-10.37	-10.21	28.56	1339
CV-24198	6/1/2026 3:50:01 PM	-1.03	-0.81	14.1	11.1	4.207	2.579			28.49	1247
CV-24198	6/19/2026 2:48:23 PM	-0.62	-0.58	12.4	12.4	3.167	3.163	-3.12		28.55	1273
CV-24199	6/1/2026 3:48:00 PM	-1.29	-0.36	35.4	22.0	1.553	0.599	-12.00		28.48	1375
CV-24199	6/19/2026 2:44:55 PM	-0.15	-0.25	23.6	27.4	0.671	0.906	-15.04		28.55	1345
CV-24200	6/11/2026 8:43:17 AM	-1.19	-1.15	18.1	18.7	1.989	2.110	-11.75		28.54	1247
CV-24200	6/11/2026 10:41:55 AM	-1.01	-0.76	17.6	11.7	1.885	0.836	-10.28		28.43	1296
CV-24200	6/25/2026 8:22:40 AM	-0.89	-0.86	15.5	16.1	1.491	1.603	-18.05		28.62	1286
CV-24201	6/2/2026 9:25:14 AM										
CV-24201	6/3/2026 9:35:53 AM										
CV-24201	6/3/2026 12:17:20 PM	-1.62	-1.62	3.9	4.0	0.041	0.044	-0.01	-0.01	28.67	1278
CV-24201	6/4/2026 7:58:40 AM										
CV-24201	6/5/2026 1:51:11 PM										
CV-24201	6/8/2026 3:58:23 PM										
CV-24201	6/8/2026 3:58:35 PM										
CV-24201	6/19/2026 12:17:46 PM										
CV-24201	6/19/2026 3:58:50 PM	-1.66	-1.66	12.4	12.4	0.406	0.407			28.6	1345
CV-24201	6/25/2026 1:06:00 PM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24201	6/25/2026 1:07:09 PM										
CV-24201	6/30/2026 11:53:07 AM										
CV-24201	6/30/2026 11:53:19 AM										
CV-24202	6/1/2026 1:30:01 PM										
CV-24202	6/2/2026 9:22:52 AM										
CV-24202	6/3/2026 9:33:49 AM										
CV-24202	6/3/2026 12:11:54 PM	-3.69	-2.89			3.673	2.874	-13.63	-13.82	28.63	1288
CV-24202	6/4/2026 8:00:54 AM										
CV-24202	6/5/2026 1:49:56 PM										
CV-24202	6/6/2026 9:00:38 AM										
CV-24202	6/8/2026 3:53:11 PM										
CV-24202	6/8/2026 3:53:58 PM										
CV-24202	6/19/2026 12:15:01 PM										
CV-24202	6/19/2026 4:05:22 PM	-5.35	-4.25	0.0	0.0	5.314	4.310	-14.97		28.59	1329
CV-24202	6/23/2026 2:02:54 PM										
CV-24202	6/23/2026 2:03:14 PM										
CV-24202	6/25/2026 1:11:49 PM										
CV-24202	6/25/2026 1:12:25 PM										
CV-24202	6/30/2026 11:49:07 AM										
CV-24202	6/30/2026 11:49:41 AM										
CV-24203	6/8/2026 3:43:07 PM	-1.97	-1.87	23.7	22.6	3.565	3.249			28.54	1214
CV-24203	6/25/2026 8:03:43 AM	-3.06	-3.11	25.6	28.0	4.013	4.825	-17.54		28.67	1312
CV-24204	6/8/2026 3:40:01 PM	-2.00	-1.89	15.0	14.3	0.513	0.471	-13.91		28.55	1243
CV-24204	6/21/2026 3:11:11 PM	-3.35	-3.58	13.7	15.0	0.443	0.534	-15.14	-14.90	28.59	1238
CV-24204	6/21/2026 3:14:13 PM	-3.43	-3.42	15.2	15.5	0.545	0.568	-14.90	-15.00	28.62	1237
CV-24204	6/30/2026 2:20:08 PM	-3.69	-5.11	21.1	32.7	0.593	1.426	-18.71	-19.70	28.68	1236
CV-24205	6/8/2026 3:36:44 PM	-3.87	-4.24	29.8	34.1	1.074	1.408	-13.18		28.47	1280
CV-24205	6/25/2026 8:09:37 AM	-5.72	-5.78	36.7	43.5	1.648	2.139	-18.70		28.68	1260
CV-24206	6/2/2026 9:26:41 AM										
CV-24206	6/3/2026 12:20:11 PM	-1.40	-0.41			1.380	0.407	-10.05	-10.29	28.66	1270
CV-24206	6/22/2026 1:51:33 PM	0.04	0.06			0.000	0.000	-10.70	-10.47	28.59	1284
CV-24206	6/26/2026 8:44:38 AM	-0.29	-0.29			0.301	0.302	-9.60	-9.44	28.62	1279
CV-24207	6/2/2026 10:50:32 AM	-1.09	-0.56	16.8	14.2	0.377	0.269	-10.50	-10.77	28.56	1382
CV-24207	6/2/2026 10:51:16 AM	-0.38	-0.35	16.4	15.8	0.357	0.332	-10.69	-10.61	28.56	1386
CV-24207	6/16/2026 6:00:05 AM	-0.15	-0.15	16.4	15.5	0.358	0.317	-12.25	-12.96	28.51	1393

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24208	6/10/2026 1:52:08 PM	-1.21	-0.48	17.1	11.9	1.918	0.922	-11.39	-11.55	28.49	1260
CV-24209	6/1/2026 1:25:40 PM										
CV-24209	6/2/2026 9:17:37 AM										
CV-24209	6/3/2026 9:31:39 AM										
CV-24209	6/3/2026 12:05:12 PM	-0.36	-0.36			0.337	0.337	-15.43	-15.43	28.63	1298
CV-24209	6/4/2026 8:06:47 AM										
CV-24209	6/5/2026 1:48:24 PM										
CV-24209	6/6/2026 8:57:15 AM										
CV-24209	6/8/2026 3:47:47 PM										
CV-24209	6/8/2026 3:48:01 PM										
CV-24209	6/19/2026 12:11:29 PM										
CV-24209	6/25/2026 1:20:57 PM										
CV-24209	6/25/2026 1:21:08 PM										
CV-24209	6/30/2026 11:43:59 AM										
CV-24209	6/30/2026 11:44:09 AM										
CV-24210	6/1/2026 1:12:24 PM										
CV-24210	6/2/2026 9:13:48 AM										
CV-24210	6/3/2026 8:51:28 AM	-1.13	-1.11			1.131	1.100	-8.62	-8.41	28.59	1336
CV-24210	6/3/2026 9:26:21 AM										
CV-24210	6/4/2026 8:10:19 AM										
CV-24210	6/5/2026 1:43:34 PM										
CV-24210	6/6/2026 8:15:32 AM										
CV-24210	6/6/2026 8:17:27 AM										
CV-24210	6/8/2026 3:40:45 PM										
CV-24210	6/8/2026 3:41:19 PM										
CV-24210	6/9/2026 12:38:28 PM	-1.48	-1.48			1.368	1.360	-11.37	-11.29	28.52	1338
CV-24210	6/19/2026 11:49:20 AM										
CV-24210	6/24/2026 11:15:44 AM										
CV-24210	6/24/2026 11:15:53 AM										
CV-24210	6/25/2026 2:20:19 PM										
CV-24210	6/25/2026 2:20:28 PM										
CV-24210	6/29/2026 2:30:23 PM										
CV-24210	6/29/2026 2:30:33 PM										
CV-24211	6/15/2026 9:54:59 AM	-12.12	-11.02			12.593	11.303	-18.03	-16.62	28.72	1253
CV-24212	6/15/2026 9:59:21 AM	-3.78	-1.04			3.761	1.037	-16.69	-16.38	28.74	1252
CV-24212	6/15/2026 10:00:53 AM	-1.00	-1.02			0.998	1.022	-16.48	-16.39	28.74	1249
CV-24212	6/15/2026 10:02:09 AM	-0.47	-0.47			0.478	0.479	-16.49	-16.28	28.74	1252
CV-24213	6/8/2026 10:52:13 AM	-6.30	-6.12			6.496	6.372	-6.37	-6.17	28.48	1306

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24214	6/8/2026 10:30:06 AM	-3.83	-3.83			3.723	3.729	-4.33	-4.33	28.5	1308
CV-24214	6/8/2026 11:01:06 AM	-4.69	-4.35			4.553	4.250	-10.53	-10.69	28.52	1289
CV-24214	6/10/2026 2:15:31 PM										
CV-24214	6/10/2026 2:15:46 PM										
CV-24214	6/23/2026 11:17:53 AM										
CV-24214	6/23/2026 11:18:07 AM										
CV-24214	6/26/2026 11:12:16 AM										
CV-24214	6/26/2026 11:12:27 AM										
CV-24214	6/30/2026 11:31:15 AM										
CV-24214	6/30/2026 11:34:01 AM										
CV-24214	6/30/2026 11:34:35 AM										
CV-24215	6/24/2026 10:13:40 AM	-1.80	-1.80	14.1	15.1	0.126	0.144	-10.14	-10.04	28.66	1311
CV-24216	6/17/2026 10:42:13 AM	-3.93	-3.25			3.879	3.200	-11.11	-11.73	28.63	1302
CV-24217	6/8/2026 11:40:15 AM	-0.73	-0.71	0.0	0.0	0.609	0.608			28.42	1378
CV-24218	6/4/2026 7:51:47 AM										
CV-24218	6/8/2026 11:18:36 AM	-3.33	-3.27	0.0	0.0	3.194	3.180			28.57	1378
CV-24219	6/4/2026 8:54:21 AM	-11.55	-11.54			11.596	11.610	-12.36	-12.45	28.47	1399
CV-24219	6/11/2026 9:18:18 AM	-8.01	-7.56			8.249	7.732	-8.20	-7.58	28.44	1394
CV-24219	6/24/2026 8:15:38 AM	-11.89	-11.91			12.239	12.256	-13.09	-13.10	28.59	1387
CV-24220	6/2/2026 12:24:43 PM	-6.08	-5.09			6.127	4.897	-16.40	-16.06	28.63	1343
CV-24220	6/30/2026 1:30:24 PM	-17.60	-6.13		77.3		6.043			28.47	1342
CV-24221	6/15/2026 2:27:47 PM	-2.84	-2.82	3.5	3.7	0.034	0.037	-15.30	-15.26	28.69	1267
CV-24222	6/15/2026 2:17:31 PM	-13.85	-13.87	24.1	24.5	1.645	1.692	-15.36	-15.44	28.72	1243
CV-24223	6/1/2026 1:47:28 PM										
CV-24223	6/15/2026 10:08:41 AM	-2.43	-0.97			2.422	0.965	-15.69	-16.40	28.74	1259
CV-24223	6/15/2026 10:09:21 AM	-0.78	-0.77			0.787	0.783	-15.94	-16.00	28.73	1253
CV-24224	6/2/2026 12:37:29 PM	-3.80	-2.86			3.763	2.884	-16.72	-16.84	28.67	1329
CV-24225	6/3/2026 9:18:42 AM	-0.12	-0.12			0.119	0.125	-15.15	-17.50	28.63	1292
CV-24226	6/15/2026 9:49:42 AM	-5.39	-5.65	55.0	53.2	0.763	0.715	-19.00	-18.03	28.71	1260
CV-24227	6/8/2026 1:16:48 PM	-5.74	-5.74	27.3	27.1	1.748	1.722	-12.36	-11.94	28.59	1257
CV-24231	6/10/2026 9:02:36 AM	-0.88	-0.76	2.3	2.1	0.586	0.480	-14.24	-14.26	28.54	1278
CV-24236	6/1/2026 3:14:40 PM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-24236	6/8/2026 12:27:00 PM	-3.82	-3.54	26.6	22.7	0.904	0.659	-10.39	-11.18	28.64	1202
CV-24237	6/1/2026 3:15:07 PM										
CV-24237	6/8/2026 12:31:50 PM	-1.98	-1.76	28.9	23.2	1.082	0.694	-11.73	-11.50	28.63	1230
CV-24243	6/8/2026 10:28:32 AM	-0.46	-0.14	33.5	12.8	2.979	0.432	-16.30	-15.62	28.64	1190
CV-24243	6/8/2026 10:33:20 AM	-0.11	-0.11	10.8	10.9	0.307	0.312	-20.09	-20.33	28.65	1194
CV-24243	6/12/2026 10:56:52 AM	-0.27	-0.26	73.9	69.8	0.998	1.128	-26.97		28.6	1204
CV-24243	6/12/2026 10:58:41 AM	-0.29	-0.28	81.7	81.8	1.549	1.553	-26.37		28.6	1181
CV-24244	6/8/2026 10:22:29 AM	-6.29	-5.93	33.1	29.6	0.283	0.225	-20.93	-21.12	28.63	1206
CV-24244	6/12/2026 10:35:49 AM	-7.09	-4.19	55.4	25.3	0.744	0.154	-19.70		28.5	1240
CV-24244	6/12/2026 10:44:49 AM	-2.91	-2.87	20.7	24.3	1.141	1.572	-19.50		28.59	1168
CV-24244	6/30/2026 1:45:09 PM	-2.66	-2.46	82.8	73.5	1.622	1.278	-24.78		28.53	1158
CV-24245	6/8/2026 9:34:29 AM	0.33	-0.10	1.5	8.1	0.013	0.401	-17.52	-17.91	28.67	1152
CV-24245	6/8/2026 9:34:50 AM	-0.20	-0.20	8.3	8.3	0.423	0.425	-20.03	-20.05	28.67	1159
CV-24245	6/12/2026 1:14:59 PM	-0.27	-0.37	9.6	15.3	0.548	1.394	-17.19		28.6	1152
CV-24246	6/8/2026 9:15:06 AM	-3.04	-2.60	58.1	48.0	9.124	6.200	-14.03	-14.53	28.67	1167
CV-24246	6/8/2026 9:30:23 AM	-2.63	-2.63	12.0	12.0	0.384	0.385	-14.37	-14.39	28.67	1170
CV-24246	6/12/2026 1:04:39 PM	-2.17	-0.62	57.1	5.7	8.404	0.082	-19.38		28.63	1132
CV-24246	6/12/2026 1:06:33 PM	-0.38	-0.38	8.7	8.9	0.196	0.205	-21.17		28.63	1115
CV-24253	6/12/2026 1:29:16 PM	-0.11	-0.28	19.2	22.3	0.804	1.080	-25.88		28.63	1175
CV-25	6/1/2026 9:45:46 AM	-10.66	-10.58	6.7	6.0	0.052	0.042	-10.30		28.65	1243
CV-2501	6/1/2026 10:19:00 AM	-1.11	-1.12	21.2	21.2	0.108	0.108	-12.74		28.51	1302
CV-2502	6/1/2026 10:33:03 AM	-1.02	-0.93	33.0	26.2	0.263	0.166	-12.73		28.52	1306
CV-2503	6/12/2026 3:19:21 PM	-1.56	-0.41	50.4	22.7	0.624	0.126	-16.80		28.45	1224
CV-2503	6/19/2026 11:08:35 AM	-0.38	-0.55	12.7	14.4	0.053	0.069	-16.79	-16.51	28.67	1294
CV-2504	6/10/2026 9:15:49 AM	-1.10	-1.10	41.9	41.7	4.873	4.848	-13.98	-14.33	28.56	1274
CV-2505	6/3/2026 12:41:55 PM	-4.05	-4.05	27.0	27.2	0.188	0.191	-14.54	-14.46	28.7	1244
CV-2506	6/3/2026 12:48:33 PM	-2.81	-2.81	46.0	46.3	1.356	1.372	-13.48	-13.46	28.71	1224
CV-2507	6/3/2026 12:52:12 PM	-5.47	-5.64	55.0	54.8	3.918	3.893	-12.85	-13.08	28.71	1202
CV-2508	6/3/2026 12:55:44 PM	-9.84	-9.94	18.2	23.7	0.087	0.148	-13.75	-13.75	28.73	1195
CV-2509	6/3/2026 1:00:33 PM	-8.83	-8.83	48.0	46.5	1.483	1.387	-13.20	-13.12	28.74	1165
CV-2510	6/3/2026 1:06:45 PM	-5.46	-5.62	27.4	28.7	2.041	2.245	-13.76	-13.60	28.74	1157

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-25100D	6/4/2026 10:51:32 AM	-3.80	-1.33			3.732	1.298	-7.66	-8.62	28.42	1373
CV-25100D	6/23/2026 10:16:56 AM	-1.98	-1.94			1.974	1.942	-10.17	-10.03	28.62	1371
CV-25100D	6/26/2026 1:29:54 PM										
CV-25100S	6/1/2026 1:32:02 PM	-4.10	-4.55			3.728	4.517	-8.59	-9.51	28.55	1381
CV-25100S	6/1/2026 1:45:00 PM										
CV-25100S	6/1/2026 1:45:00 PM										
CV-25100S	6/8/2026 1:43:02 PM	-4.64	-4.98			4.306	5.505	-8.56	-8.78	28.5	1367
CV-25100S	6/15/2026 9:59:15 AM	-2.97	-2.59			2.764	2.856	-7.41	-6.19	28.62	1372
CV-25100S	6/22/2026 1:20:12 PM	-2.29	-2.30			2.207	2.078	-7.07	-7.03	28.51	1374
CV-25100S	6/26/2026 2:41:55 PM										
CV-25100S	6/29/2026 2:07:27 PM	-5.62	-5.41			5.870	5.675	-9.52	-9.71	28.46	1383
CV-25101D	6/4/2026 10:35:59 AM	-8.29	-8.00			8.491	8.291	-8.19	-7.92	28.41	1400
CV-25101D	6/17/2026 2:26:12 PM	-8.92	-9.09			8.837	9.000	-8.80	-8.74	28.51	1402
CV-25101D	6/19/2026 9:33:33 AM	-2.24	-2.24			2.241	2.239	-19.54	-18.03	28.57	1385
CV-25101S	6/4/2026 10:31:12 AM	-2.43	-1.46			2.349	1.362	-7.83	-7.96	28.41	1392
CV-25101S	6/17/2026 2:23:12 PM	-1.82	-2.08			1.796	2.095	-8.83	-8.74	28.51	1399
CV-25102_	6/2/2026 3:16:43 PM	-11.43	-11.45			11.537	11.512	-11.87	-11.78	28.58	1341
CV-25102_	6/4/2026 10:57:28 AM	-9.05	-8.78			9.334	9.129	-8.82	-9.06	28.44	1388
CV-25102_	6/23/2026 10:22:01 AM	-10.91	-10.10			11.142	10.276	-11.10	-11.37	28.62	1361
CV-25102_	6/26/2026 2:44:49 PM										
CV-25103	6/4/2026 10:14:00 AM	-0.55	-0.54			0.525	0.527	-8.21	-8.33	28.41	1391
CV-25103	6/4/2026 12:49:09 PM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-25103	6/17/2026 2:13:33 PM	-0.49	-0.49			0.483	0.479	-10.11	-10.16	28.51	1408
CV-25104D	6/4/2026 8:21:00 AM	-9.27	-8.92			9.328	9.006	-9.27	-8.98	28.52	1369
CV-25104D	6/22/2026 2:05:56 PM	-6.23	-6.99	7.7	8.1	6.256	6.971	-6.19	-6.93	28.55	1365
CV-25104S	6/4/2026 8:24:31 AM	-8.83	-8.76			8.890	8.926	-9.12	-9.25	28.52	1371
CV-25104S	6/4/2026 8:25:26 AM	-8.68	-8.77			8.849	8.944	-9.05	-9.14	28.52	1372
CV-25104S	6/26/2026 9:08:11 AM	-6.04	-5.81			6.002	5.838	-12.18	-11.46	28.51	1378
CV-25104S	6/26/2026 9:09:21 AM	-6.23	-6.08			6.263	6.339	-10.11	-11.63	28.51	1380
CV-25105D	6/17/2026 1:52:34 PM	-11.30	-10.93			11.206	10.847	-11.22	-11.29	28.51	1390
CV-25105S	6/2/2026 3:34:50 PM	-11.96	-11.73			11.925	11.773	-11.87	-11.67	28.57	1369
CV-25105S	6/2/2026 3:42:33 PM	-1.12	-0.71			1.082	0.642	-11.67	-12.10	28.56	1365
CV-25105S	6/2/2026 3:49:22 PM	-1.18	-1.14			1.110	1.096	-11.24	-11.74	28.56	1378
CV-25105S	6/17/2026 1:58:16 PM	-1.08	-1.08			1.052	1.056	-11.14	-11.04	28.51	1390
CV-25105S	6/22/2026 2:11:08 PM	-6.40	-2.28			6.338	2.287	-6.43	-6.13	28.55	1378
CV-25106D	6/4/2026 8:29:59 AM	-0.84	-0.82			0.825	0.804	-9.10	-8.93	28.54	1366
CV-25106D	6/4/2026 8:31:27 AM									28.52	1366
CV-25106D	6/22/2026 2:02:06 PM	-2.37	-2.39			2.285	2.333	-6.71	-6.50	28.55	1373
CV-25106S	6/4/2026 8:34:37 AM	-8.77	-8.77			8.969	9.025	-9.30	-9.44	28.52	1368
CV-25106S	6/4/2026 8:36:09 AM	-9.08	-8.77			9.255	9.088	-9.58	-9.16	28.52	1371
CV-25106S	6/22/2026 1:59:24 PM	-6.41	-6.76			6.480	6.754	-6.86	-6.93	28.55	1375
CV-25107D	6/3/2026 12:08:08 PM	-11.98	-12.05			12.020	12.122	-11.89	-12.00	28.59	1400

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-25107D	6/19/2026 9:28:30 AM	-18.49	-9.68			18.660	9.735	-18.45	-19.80	28.55	1393
CV-25107D	6/22/2026 8:39:22 AM	0.65	-11.00			0.000	11.246	-13.00	-13.03	28.55	1402
CV-25107D	6/22/2026 8:43:08 AM	-11.20	-11.34			11.429	11.551	-12.25	-13.59	28.55	1388
CV-25107S	6/3/2026 12:02:43 PM	-0.79	-0.79			0.753	0.763	-12.08	-12.00	28.61	1396
CV-25107S	6/22/2026 8:32:45 AM	-1.01	-1.01			0.982	0.982	-13.39	-13.31	28.55	1400
CV-2511	6/10/2026 9:06:43 AM	-0.90	-0.90	18.6	18.6	0.090	0.090	-14.39	-14.39	28.59	1254
CV-2512	6/10/2026 9:10:28 AM	-0.90	-0.72	34.5	35.5	0.309	0.327	-13.86	-14.54	28.59	1235
CV-2513	6/8/2026 10:06:59 AM	-4.34	-3.82	46.9	35.5	5.200	2.960	-19.87	-14.49	28.68	1159
CV-2514	6/10/2026 3:40:54 PM	-4.14	-1.09	48.1	2.7	2.824	0.009	-10.04		28.55	1207
CV-2514	6/10/2026 3:43:08 PM	-0.88	-0.89	6.8	7.0	0.054	0.059	-10.42		28.55	1280
CV-2515	6/1/2026 9:02:06 AM	-2.78	-2.68	21.3	20.0	0.541	0.478	-10.50		28.64	1243
CV-2516	6/17/2026 10:36:20 AM	-3.69	-3.98	15.2	18.9	1.512	2.330	-10.49	-10.42	28.63	1300
CV-2517	6/1/2026 9:39:20 AM	-2.92	-2.91	0.0	0.0	-0.026	-0.036	-11.18		28.65	1306
CV-2518	6/1/2026 10:08:10 AM	-3.59	-3.57	0.0	0.0	-0.093	-0.082	-10.81		28.66	1217
CV-2519	6/15/2026 1:21:52 PM	-1.68	-1.53	26.6	20.1	1.659	0.945	-14.22	-13.78	28.67	1305
CV-2520	6/17/2026 11:04:36 AM	-8.26	-6.26	14.9	7.8	0.638	0.174	-14.39	-14.59	28.63	1308
CV-2520	6/17/2026 11:05:44 AM	-5.91	-5.92	8.8	7.6	0.221	0.164	-14.63	-14.68	28.66	1311
CV-2521	6/25/2026 10:08:06 AM	-1.22	-1.22			1.176	1.181	-4.06	-4.05	28.55	1328
CV-2522	6/15/2026 1:15:28 PM	-7.05	-2.81	14.0	12.1	0.474	0.348	-13.12	-13.59	28.71	1284
CV-2522	6/15/2026 1:16:43 PM	-2.81	-2.73	11.9	11.7	0.338	0.323	-13.51	-14.10	28.71	1289
CV-2523	6/15/2026 1:00:57 PM	-0.06	-0.32	26.0	29.5	4.301	5.602	-13.87	-14.62	28.7	1280
CV-2523	6/30/2026 2:32:51 PM										
CV-2524	6/25/2026 9:48:48 AM	1.33	-0.16	1.5	7.1	0.006	0.134	-17.80	-16.95	28.62	1290
CV-2524	6/25/2026 9:50:06 AM	-0.38	-0.38	6.6	6.6	0.116	0.115	-16.94	-16.51	28.62	1295
CV-2525	6/15/2026 12:52:47 PM	-1.16	-1.00	24.1	18.9	1.339	0.824	-14.52	-14.80	28.73	1271
CV-2526	6/15/2026 12:48:53 PM	-1.19	-1.23	7.0	8.5	0.012	0.018	-13.93	-15.32	28.72	1262

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-2527	6/22/2026 2:39:55 PM	-3.60	-3.58			3.573	3.548	-13.50	-13.51	28.58	1309
CV-2528	6/15/2026 10:47:39 AM	-3.94	-3.93	15.1	15.5	0.134	0.141	-16.38		28.74	1253
CV-2528	6/30/2026 9:56:37 AM										
CV-2529	6/1/2026 10:23:26 AM										
CV-2529	6/2/2026 9:42:05 AM										
CV-2529	6/3/2026 9:44:04 AM										
CV-2529	6/4/2026 7:16:01 AM										
CV-2529	6/5/2026 11:28:41 AM										
CV-2529	6/6/2026 9:54:57 AM										
CV-2529	6/8/2026 3:03:59 PM										
CV-2529	6/8/2026 3:04:24 PM										
CV-2529	6/10/2026 2:08:49 PM	-13.80	-11.67	1.2	1.0	0.159	0.100	-13.65	-13.86	28.52	1232
CV-2529	6/10/2026 2:10:02 PM	-11.84	-11.82	0.7	0.9	0.048	0.092	-13.81	-13.81	28.52	1235
CV-2529	6/16/2026 11:08:28 AM										
CV-2529	6/16/2026 11:09:00 AM										
CV-2529	6/16/2026 11:09:14 AM										
CV-2529	6/16/2026 11:15:07 AM										
CV-2529	6/16/2026 11:15:57 AM										
CV-2529	6/16/2026 11:24:10 AM										
CV-2529	6/16/2026 11:24:20 AM										
CV-2529	6/24/2026 12:57:34 PM										
CV-2529	6/24/2026 12:57:52 PM										
CV-2529	6/25/2026 11:45:10 AM										
CV-2529	6/25/2026 11:45:18 AM										
CV-2529	6/25/2026 2:48:45 PM										
CV-2529	6/25/2026 3:48:38 PM	-9.63	-9.60	2.6	2.6	0.715	0.726	-16.63	-16.67	28.66	1227
CV-2529	6/29/2026 1:17:01 PM										
CV-2530	6/10/2026 2:29:19 PM	-2.15	-2.12			2.042	2.017	-13.02	-13.18	28.53	1210
CV-2531	6/10/2026 2:33:42 PM	-9.88	-7.44			10.033	7.568	-14.00	-14.21	28.52	1211
CV-2532	6/1/2026 10:20:21 AM										
CV-2532	6/3/2026 9:46:27 AM										
CV-2532	6/4/2026 7:12:04 AM										
CV-2532	6/4/2026 7:13:21 AM										
CV-2532	6/5/2026 11:31:43 AM										
CV-2532	6/5/2026 11:34:11 AM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-2532	6/10/2026 2:36:45 PM	-14.53	-14.53			14.573	14.492	-14.48	-14.48	28.52	1201
CV-2533	6/1/2026 10:18:28 AM										
CV-2533	6/3/2026 9:48:15 AM										
CV-2533	6/4/2026 7:10:54 AM										
CV-2533	6/5/2026 11:35:17 AM										
CV-2533	6/10/2026 1:57:41 PM										
CV-2533	6/10/2026 1:57:54 PM										
CV-2533	6/10/2026 2:39:59 PM	-12.76	-12.51	18.8	19.6	1.017	1.097	-14.23	-14.18	28.52	1192
CV-2533	6/16/2026 11:22:47 AM										
CV-2533	6/16/2026 11:22:56 AM										
CV-2533	6/25/2026 11:36:10 AM										
CV-2533	6/25/2026 11:36:22 AM										
CV-2533	6/25/2026 3:53:17 PM										
CV-2533	6/29/2026 1:23:58 PM										
CV-2533	6/29/2026 1:24:21 PM										
CV-2534	6/10/2026 1:02:08 PM	-4.90	-5.10	39.7	41.2	2.090	2.254	-17.02	-17.59	28.59	1227
CV-2534	6/10/2026 2:43:52 PM	-5.07	-5.07	45.5	45.5	2.757	2.759	-17.91	-18.06	28.52	1198
CV-2534	6/30/2026 2:28:25 PM	-7.72	-8.09	50.5	54.1	3.318	3.829	-22.97	-23.44	28.69	1216
CV-2535	6/3/2026 12:25:06 PM	-0.58	-0.53	29.3	23.5	1.100	0.709	-9.88	-9.74	28.7	1245
CV-2536	6/10/2026 3:50:56 PM	-1.61	-1.52	2.6	2.9	0.744	0.897	-9.91		28.54	1132
CV-2536	6/30/2026 2:11:01 PM										
CV-2537	6/3/2026 12:36:58 PM	-0.35	-0.77			0.335	0.759	0.00	0.01	28.71	1224
CV-2537	6/30/2026 2:13:52 PM	-2.97	-2.35			2.912	2.318	-14.84	-14.93	28.69	1229
CV-2538	6/3/2026 12:28:52 PM	-0.95	-0.95	10.6	10.7	2.416	2.429	-10.16	-10.24	28.71	1222
CV-2538	6/30/2026 1:21:17 PM										
CV-2539	6/1/2026 10:50:13 AM	-2.83	-2.83	0.0	0.0	2.813	2.809	-7.47		28.53	1355
CV-2539	6/17/2026 11:59:27 AM	-3.19	-1.56			3.116	1.533	-8.73	-8.73	28.63	1327
CV-2540	6/15/2026 8:30:48 AM	-0.47	-0.49			0.457	0.479	-7.57	-7.40	28.59	1388
CV-2540	6/16/2026 10:23:27 AM	-0.46	-0.47			0.511	0.474	-7.53	-7.56	28.59	1363
CV-2540	6/25/2026 2:27:35 PM	-9.41	-8.85			9.418	8.739	-9.41	-9.05	28.52	1366

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-2540	6/25/2026 2:29:35 PM	-8.84	-8.92			8.762	8.832	-9.17	-9.24	28.53	1369
CV-2541	6/3/2026 9:02:39 AM	-3.06	-1.84			2.996	1.789	-6.68	-6.82	28.56	1344
CV-2541	6/16/2026 9:33:45 AM	-1.98	-0.83			1.971	0.833	-6.70	-6.29	28.62	1348
CV-2541	6/16/2026 9:34:05 AM	-0.78	-0.78			0.791	0.790	-6.41	-6.39	28.62	1348
CV-2542	6/3/2026 2:04:32 PM	-1.70	-1.69			1.648	1.618	-6.03	-6.26	28.46	1380
CV-2542	6/16/2026 6:19:26 AM	-3.12	-3.11			3.089	3.081	-7.43	-8.27	28.52	1398
CV-2543-PLF	6/3/2026 2:32:39 PM	5.57	-6.38			0.000	6.359	-6.77	-6.64	28.52	1339
CV-2543-PLF	6/3/2026 2:33:15 PM	-5.75	-5.76			5.813	5.802	-6.76	-6.79	28.52	1349
CV-2543-PLF	6/22/2026 10:17:04 AM	-7.28	-6.30			7.491	6.487	-7.29	-6.57	28.51	1361
CV-2543-PLF	6/30/2026 11:16:12 AM										
CV-2544	6/11/2026 9:06:29 AM	-1.86	-1.71	0.0	0.0	1.718	1.688	-7.13		28.46	1404
CV-2544	6/11/2026 9:09:46 AM	-1.76	-1.68	0.0	0.0	2.006	1.453	-6.73		28.46	1394
CV-2544	6/15/2026 2:05:00 PM	0.37	-1.12			0.000	1.134	-7.99	-7.58	28.59	1392
CV-2544	6/15/2026 2:06:46 PM	-1.34	-1.34			1.348	1.361	-7.66	-7.84	28.59	1395
CV-2544	6/22/2026 9:59:02 AM	-7.05	-6.22			7.231	6.435	0.37	0.36	28.48	1398
CV-2544	6/22/2026 9:59:57 AM	-6.02	-6.10			6.182	6.301	0.37	0.35	28.48	1391
CV-2545	6/4/2026 8:37:41 AM	-0.48	-0.32			0.484	0.319	-4.12	-4.31	28.44	1388
CV-2545	6/16/2026 2:36:50 PM										
CV-2545	6/22/2026 9:10:21 AM	-0.36	-0.36			0.353	0.354	-3.56	-3.43	28.48	1383
CV-2546	6/4/2026 8:42:51 AM	-0.47	-0.27			0.470	0.272	-4.33	-4.29	28.44	1387
CV-2546	6/4/2026 8:44:06 AM	-0.24	-0.24			0.245	0.246	-4.16	-4.41	28.44	1383
CV-2546	6/16/2026 1:12:07 PM	0.36	-0.08			0.000	0.090	-6.59	-4.78	28.55	1379
CV-2546	6/16/2026 1:12:57 PM	-0.18	-0.17			0.165	0.158	-5.56	-5.65	28.55	1387
CV-2546	6/16/2026 1:13:54 PM	-0.14	-0.14			0.148	0.145	-5.88	-6.02	28.55	1389

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-2546	6/18/2026 8:47:47 AM										
CV-2547	6/4/2026 9:30:40 AM	-2.46	-2.46			2.433	2.431	-14.60	-14.56	28.44	1392
CV-2547	6/16/2026 5:51:22 AM	-2.88	-2.66			2.851	2.637	-17.50	-17.45	28.48	1389
CV-2547	6/16/2026 2:07:20 PM										
CV-2547	6/24/2026 8:12:57 AM	-1.79	-1.80			1.781	1.783	-16.48	-16.87	28.55	1391
CV-2548	6/2/2026 9:12:35 AM	-2.37	-1.87	12.4	13.3	3.313	3.764	-13.49	-13.15	28.63	1393
CV-2548	6/2/2026 9:15:21 AM	-1.93	-1.93	5.9	6.0	3.907	3.944	-12.83	-13.00	28.63	1391
CV-2548	6/16/2026 12:50:07 PM	-0.71	-0.71	2.5	2.4	0.129	0.119	-17.31	-17.02	28.55	1395
CV-2548	6/26/2026 12:39:55 PM	-0.10	-0.09	14.1	15.0	4.316	4.878	-15.25	-15.91	28.51	1390
CV-2549	6/2/2026 8:57:57 AM	-2.45	-2.90	16.5	14.3	5.756	4.334	-15.44	-15.59	28.63	1410
CV-2549	6/2/2026 9:04:56 AM	-2.99	-2.98	26.3	26.6	4.424	4.503	-14.42	-14.61	28.63	1409
CV-2549	6/9/2026 12:21:15 PM	-2.09	-2.10	41.0	40.9	4.592	4.566	-14.52	-14.27	28.45	1402
CV-2549	6/16/2026 12:47:49 PM	-2.19	-2.20	1.8	2.0	0.008	0.011	-17.79	-17.76	28.55	1396
CV-2550	6/1/2026 8:25:41 AM										
CV-2550	6/4/2026 9:26:24 AM	-12.16	-12.35			12.320	12.397	-13.12	-13.98	28.47	1377
CV-2550	6/10/2026 2:34:19 PM	-7.95	-8.29			8.118	8.411	-12.64	-13.44	28.43	1387
CV-2550	6/24/2026 8:52:00 AM	-12.13	-12.93			12.701	13.542	-12.83	-12.80	28.6	1377
CV-2550	6/30/2026 2:56:33 PM	-13.67	-13.73			14.030	13.968	-16.52	-16.21	28.49	1388
CV-2551	6/1/2026 3:18:11 PM										
CV-2551	6/2/2026 8:54:03 AM										
CV-2551	6/3/2026 9:17:33 AM	-3.37	-1.13			3.322	1.106	-12.42	-12.88	28.58	1401
CV-2551	6/3/2026 9:19:09 AM	-1.00	-1.04			0.986	0.988	-12.36	-12.43	28.59	1405
CV-2551	6/3/2026 1:49:46 PM	0.18	-2.13			0.000	2.020	-11.61	-11.17	28.54	1390
CV-2551	6/3/2026 1:50:17 PM	-2.62	-2.62			2.591	2.560	-11.10	-10.29	28.54	1390
CV-2551	6/3/2026 2:00:00 PM										
CV-2551	6/6/2026 8:46:46 AM										
CV-2551	6/10/2026 12:12:00 PM										
CV-2551	6/10/2026 12:15:52 PM										
CV-2551	6/11/2026 9:12:16 AM	-3.21	-3.16			3.201	3.152	-9.53	-9.65	28.43	1391

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-2551	6/19/2026 9:39:01 AM	-7.15	-3.74			7.258	3.741	-18.52	-19.88	28.58	1405
CV-2551	6/24/2026 8:07:19 AM	-0.16	-2.02			0.160	2.019	-13.85	-13.16	28.58	1404
CV-2551	6/24/2026 8:08:01 AM	-1.99	-2.03			1.954	2.017	-13.09	-13.05	28.57	1405
CV-2551	6/25/2026 2:42:00 PM										
CV-2551	6/25/2026 2:42:47 PM										
CV-2551	6/30/2026 2:36:17 PM										
CV-2551	6/30/2026 2:36:35 PM										
CV-2552	6/8/2026 2:06:27 PM	-10.27	-10.26			10.268	10.330	-12.26	-12.37	28.41	1383
CV-2552	6/19/2026 9:47:25 AM	-9.44	-5.92			0.102	0.078	-24.84	-23.59	28.58	1395
CV-2552	6/25/2026 7:28:45 AM										
CV-2553	6/3/2026 2:22:58 PM	-6.27	-6.38			6.348	6.302	-7.04	-7.13	28.51	1347
CV-2553	6/16/2026 10:11:11 AM	-6.46	-6.69			6.837	7.015	-7.28	-7.55	28.6	1343
CV-2553	6/17/2026 7:56:00 AM										
CV-2553	6/19/2026 11:27:02 AM	-4.64	-3.80	0.0	0.0	4.537	3.511	-7.59		28.35	1362
CV-2554	6/3/2026 1:14:29 PM	-2.40	-2.42			2.406	2.425	-5.12	-5.11	28.59	1350
CV-2554	6/3/2026 1:15:00 PM										
CV-2554	6/9/2026 2:23:37 PM	-2.99	-3.00			3.001	2.984	-7.18	-7.45	28.51	1358
CV-2554	6/16/2026 2:24:38 PM	-2.91	-2.95			2.926	2.980	-8.02	-7.79	28.53	1363
CV-2554	6/24/2026 9:50:14 AM	-3.81	-3.82			3.803	3.806	0.38	0.38	28.62	1353
CV-2555	6/10/2026 10:09:34 AM	-8.65	-8.15			9.007	8.542	-8.46	-7.92	28.41	1353
CV-2555	6/22/2026 1:53:55 PM	-4.71	-5.22			4.619	5.242	-4.62	-5.29	28.55	1368
CV-2556	6/1/2026 3:24:57 PM										
CV-2556	6/3/2026 1:25:38 PM	-11.69	-11.74			11.503	11.444	0.00	0.00	28.58	1381
CV-2556	6/3/2026 1:35:00 PM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-2556	6/10/2026 2:21:23 PM	-12.18	-12.16			12.354	12.344	0.04	0.06	28.47	1372
CV-2556	6/24/2026 9:12:42 AM	-12.47	-12.47			12.987	13.206	0.34	0.34	28.6	1365
CV-2556	6/30/2026 2:15:00 PM	-14.53	-14.66			14.880	14.934	0.04	0.02	28.49	1374
CV-2557	6/4/2026 9:59:27 AM	-6.55	-6.42			6.808	6.682	-10.67	-10.58	28.41	1394
CV-2557	6/4/2026 12:47:58 PM										
CV-2557	6/17/2026 2:02:18 PM	-3.42	-3.42			3.411	3.390	-11.18	-10.85	28.51	1410
CV-2557	6/25/2026 2:51:14 PM										
CV-2557	6/25/2026 2:52:24 PM										
CV-2558	6/4/2026 9:08:41 AM	4.79	3.20			0.000	0.000	0.00	0.00	28.47	1398
CV-2558	6/4/2026 9:11:08 AM	3.35	2.48			0.000	0.000	0.00	0.00	28.47	1397
CV-2558	6/6/2026 8:51:55 AM										
CV-2558	6/11/2026 9:40:44 AM	79.71	77.54			0.000	0.000	0.38	0.52	28.46	1420
CV-2558	6/24/2026 8:24:46 AM	-1.20	-1.07			1.211	1.316	0.10	0.21	28.57	1396
CV-2559	6/8/2026 11:29:55 AM	-3.88	-1.59	0.0	0.0	3.766	1.402	-6.67		28.4	1506
CV-2559	6/26/2026 9:21:49 AM	0.41	-0.04			0.000	0.053	-9.90	-10.05	28.51	1395
CV-2559	6/26/2026 9:22:21 AM	-0.04	-0.05			0.048	0.058	-10.13	-9.98	28.51	1390
CV-2560	6/4/2026 10:17:20 AM	-4.99	-4.57			4.884	4.449	-6.97	-6.94	28.41	1397
CV-2560	6/4/2026 12:55:13 PM										
CV-2560	6/17/2026 2:19:08 PM	-5.39	-5.31			5.227	5.112	-8.69	-8.75	28.5	1397
CV-2561	6/1/2026 10:07:37 AM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-2561	6/4/2026 10:27:07 AM	-1.42	-1.25			1.389	1.230	-5.19	-5.62	28.41	1392
CV-2561	6/25/2026 9:03:33 AM	-1.62	-1.63			1.622	1.627	-6.59	-6.54	28.5	1407
CV-2561	6/25/2026 9:59:59 AM	-1.51	-1.42	0.0	0.0	1.354	1.347	-6.88		28.52	1385
CV-2562	6/8/2026 11:24:32 AM	-1.69	-0.84	0.0	0.0	1.577	0.713	-6.39		28.4	1417
CV-2563	6/9/2026 2:01:53 PM	-4.30	-4.34	3.1	3.5	0.213	0.262	-4.68	-4.58	28.55	1297
CV-2564	6/16/2026 9:20:39 AM	-2.28	-2.12			2.241	2.103	-3.93	-7.20	28.59	1357
CV-2565	6/1/2026 10:58:19 AM	-4.00	-3.97	0.0	0.0	3.982	3.990	-6.96		28.5	1394
CV-2565	6/17/2026 12:11:54 PM	-4.41	-2.06			4.347	2.030	-8.05	-9.75	28.63	1333
CV-2566	6/1/2026 11:25:15 AM	-1.90	-1.58	0.0	0.0	1.782	1.562	-9.14		28.5	1309
CV-2566	6/17/2026 12:05:33 PM	-1.48	-2.10			1.408	2.052	-11.31	-11.36	28.63	1321
CV-2567	6/1/2026 10:36:31 AM										
CV-2567	6/10/2026 9:37:59 AM	-1.25	-1.25			1.237	1.241	-11.80	-11.64	28.45	1358
CV-2567	6/17/2026 1:15:59 PM	-1.05	-1.05			1.032	1.032	-11.55	-11.58	28.51	1354
CV-2568	6/1/2026 1:04:25 PM	0.03	-0.07	0.0	0.0	-0.043	0.108	-8.75		28.49	1293
CV-2568	6/1/2026 1:06:59 PM	-0.53	-0.52	0.0	0.0	0.485	0.480	-8.91		28.49	1319
CV-2568	6/17/2026 12:38:03 PM	-0.54	-0.55			0.536	0.536	-12.91	-12.93	28.51	1357
CV-2569	6/1/2026 1:00:40 PM	-0.54	-0.53	0.0	0.0	0.481	0.476	-8.67		28.49	1368
CV-2569	6/17/2026 12:39:56 PM	-0.69	-0.60			0.657	0.566	-12.63	-12.87	28.51	1356
CV-2570	6/1/2026 12:56:09 PM	-1.05	-0.92	0.0	0.0	0.969	0.901	-8.92		28.49	1424
CV-2570	6/17/2026 12:44:47 PM	-0.86	-0.85			0.861	0.860	-12.34	-12.34	28.51	1349
CV-2571	6/10/2026 2:50:35 PM	-6.72	-6.92	52.8	58.0	1.572	1.897	-6.93		28.55	1050
CV-2571	6/12/2026 2:05:39 PM	-8.95	-10.50	63.1	74.5	2.490	3.497	-18.69	-18.29	28.66	1137
CV-2572	6/10/2026 3:23:03 PM	-3.89	-3.78	38.7	36.9	3.926	3.563	-8.16		28.56	1115
CV-2572	6/30/2026 9:25:51 AM										
CV-48R	6/9/2026 1:59:40 PM	-4.43	-4.50	3.3	4.0	0.071	0.103	-4.68	-4.58	28.53	1296
CV-48R	6/19/2026 1:26:30 PM	-2.71	-2.88	6.0	10.0	0.227	0.638	-2.81	-3.35	28.68	1262
CV-52D	6/17/2026 10:56:39 AM	-13.90	-10.96	6.6	6.5	0.275	0.261	-14.48	-14.37	28.63	1295
CV-52D	6/17/2026 10:58:21 AM	-10.63	-10.63	4.6	4.6	0.131	0.130	-14.43	-14.45	28.64	1296
CV-55R	6/22/2026 2:49:14 PM	-9.12	-9.67	2.5	11.1	0.044	0.850	-13.90	-13.53	28.59	1314
CV-55R	6/22/2026 2:51:17 PM	-10.48	-10.48	11.7	6.6	0.947	0.306	-13.95	-13.66	28.58	1301

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
CV-56D	6/3/2026 9:46:56 AM	-2.36	-2.14	4.6	3.9	0.419	0.299	-15.38	-15.31	28.63	1306
CV-56D	6/3/2026 9:48:21 AM	-1.89	-1.87	3.7	3.6	0.268	0.254	-15.51	-15.33	28.63	1306
CV-56D	6/4/2026 11:45:39 AM	-2.33	-1.83	3.9	3.4	0.305	0.232	-16.07	-15.32	28.56	1311
CV-56D	6/4/2026 11:48:11 AM	-0.04	-0.02	1.6	0.7	0.050	0.009	-15.40	-15.82	28.55	1314
CV-56S	6/3/2026 9:50:43 AM	-1.27	-1.16	1.0	0.8	0.243	0.168	-15.85	-15.50	28.63	1306
CV-56S	6/4/2026 11:53:51 AM	-0.97	-0.96	0.7	0.7	0.136	0.134	-15.49	-15.47	28.56	1310
CV-57R	6/2/2026 12:09:58 PM	-3.47	-3.66	1.8	2.6	0.069	0.138	-15.65	-16.13	28.63	1355
CV-79R	6/2/2026 12:42:00 PM	-1.02	-1.02	11.7	10.9	0.319	0.280	-16.47	-16.81	28.67	1326
CV-94	6/2/2026 11:52:13 AM	-14.86	-13.51	18.2	17.4	2.207	1.994	-16.45	-16.41	28.63	1352
CV-95	6/2/2026 12:07:10 PM	-0.30	-0.30	2.0	1.9	0.081	0.076	-16.27	-16.25	28.63	1353
CV-99	6/4/2026 7:30:00 AM										
CV-99	6/4/2026 7:30:00 AM										
CV-99	6/5/2026 10:07:36 AM	-8.05	-7.77	1.1	0.2	0.024	0.001	-7.86	-7.75	28.46	1341
CV-99	6/5/2026 10:08:38 AM	-7.88	-7.90	0.5	0.5	0.005	0.004	-8.05	-8.22	28.45	1343
D-02	6/23/2026 1:53:57 PM	-1.62		5.3		0.023		-1.51		28.78	1191
D-02	6/23/2026 2:03:28 PM	-13.14	-13.09	6.1	5.8	0.032	0.029	-12.88	-12.87	28.78	1177
D-03	6/26/2026 1:32:24 PM	-18.87	-19.32	12.2	13.6	0.192	0.240	-0.01	0.00	28.7	1162
D-04	6/10/2026 1:27:08 PM	-15.61	-15.76	107.2	107.7	15.507	15.651	-15.18	-15.39	28.63	1179
D-09	6/10/2026 3:15:14 PM	-11.71	-11.68	12.9	12.1	0.991	0.869	-12.03		28.56	1119
D-10	6/10/2026 3:05:32 PM	-6.40	-6.42	0.0	0.0	0.049	0.035	-14.41		28.56	1142
D-10	6/10/2026 3:09:00 PM	-6.74	-7.27	0.0	0.0	-0.033	-0.027	-14.54		28.56	1145
FP-001	6/4/2026 1:35:55 PM	-0.19	-0.21	6.3	6.3	0.244	0.243	-7.39	-7.56	28.45	1353
FP-002	6/4/2026 2:04:37 PM	-0.04	-0.04	4.9	4.9	0.489	0.473	-6.88	-6.72	28.45	1363
FP-003	6/4/2026 2:07:37 PM	-0.07	-0.07	0.7	0.4	0.045	0.015	-7.12	-6.93	28.45	1357
FP-005	6/5/2026 1:33:01 PM	-0.10	-0.09	5.3	5.2	2.919	2.878	-8.36	-8.27	28.41	1358
FP-006	6/5/2026 1:48:45 PM	-0.79	-0.78	1.5	1.5	0.046	0.045	-4.02	-3.99	28.41	1369
FP-008	6/5/2026 2:33:38 PM	-0.96	-0.90	1.1	1.1	0.308	0.296	-9.38	-8.93	28.41	1357
FP-009	6/2/2026 8:40:09 AM	-1.21	-1.21	5.3	5.3	0.571	0.567	-10.61	-10.46	28.56	1367

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
FP-010	6/2/2026 8:28:42 AM	-0.66	-0.66	10.0	9.9	2.068	2.043	-11.40	-11.24	28.54	1367
FP-011	6/2/2026 8:25:31 AM	-1.71	-1.42	4.8	4.1	0.449	0.326	-11.50	-11.07	28.56	1379
FP-012	6/1/2026 9:55:47 AM	-0.36	-0.36	0.2	0.5	0.001	0.005	-7.61	-7.50	28.49	1377
FP-013	6/1/2026 1:37:28 PM	-0.51	-0.51	11.3	11.3	2.614	2.583	-7.37	-7.33	28.48	1371
FP-014	6/2/2026 8:35:12 AM	-0.36	-0.55	1.8	2.3	0.353	0.532	-10.28	-10.84	28.55	1379
FP-014	6/5/2026 2:19:15 PM	-0.30	-0.30	1.1	1.0	0.134	0.114	-0.34	-0.67	28.41	1361
FP-015	6/5/2026 2:05:04 PM	-0.28	-0.28	0.8	0.9	0.013	0.018	-2.92	-2.82	28.41	1343
FP-016	6/5/2026 1:58:04 PM	-0.75	-0.76	0.6	0.6	0.089	0.099	-2.69	-2.91	28.41	1372
FP-017	6/10/2026 9:55:02 AM	-0.36	-0.35	0.2	0.3	0.001	0.001	0.67	0.33	28.41	1342
FP-018	6/10/2026 9:47:19 AM	-2.23	-1.78	6.0	4.7	0.714	0.441	-9.69	-9.81	28.45	1343
FP-019	6/2/2026 9:42:15 AM	-0.20	-0.19	1.9	1.8	0.071	0.065	-10.55	-10.27	28.6	1355
FP-020	6/10/2026 11:16:39 AM	-0.89	-0.89			0.000	0.000	-9.16	-9.46	28.44	1333
FP-021	6/2/2026 9:52:46 AM	-3.24	-2.01			0.008	0.024	-4.89	-5.62	28.6	1350
FP-022	6/10/2026 11:08:45 AM	-3.08	-2.33			0.000	0.000	-8.82	-9.17	28.43	1353
FP-023	6/22/2026 8:10:36 AM	-1.05	-1.13	9.3	10.7	1.729	2.298	-8.41	-7.40	28.51	1368
FP-024	6/10/2026 10:40:56 AM	-0.42	-0.43	0.5	0.6	0.006	0.007	-9.44	-9.22	28.41	1355
FP-025	6/4/2026 9:05:18 AM	-3.03	-3.03	3.4	3.4	0.071	0.071	-8.83	-8.81	28.55	1361
FP-026	6/4/2026 9:14:18 AM	-6.43	-6.68			6.615	6.787	-6.51	-6.64	28.55	1356
FP-027	6/8/2026 10:54:42 AM	-7.97	-8.22			8.004	8.310	-8.01	-8.41	28.49	1341
FP-028	6/8/2026 10:49:31 AM	-0.62	-0.59	5.9	5.9	0.707	0.714	-9.51	-9.48	28.52	1326
FP-029	6/10/2026 9:50:32 AM	-0.14	-0.10	15.4	13.7	0.298	0.237	0.33	0.33	28.45	1347
FP-030	6/2/2026 9:25:15 AM	-0.69	-0.69	16.0	16.2	5.093	5.192	-10.33	-10.45	28.6	1371
FP-031	6/2/2026 9:20:31 AM	-2.44	-1.03	2.9	1.1	2.112	0.294	-10.32	-9.99	28.6	1356
FP-032	6/2/2026 9:00:20 AM	-3.92	-2.49	4.7	1.7	2.223	0.300	-10.30	-10.78	28.6	1348
FP-033	6/2/2026 8:55:46 AM	-0.14	-0.15	1.0	1.0	0.020	0.021	-2.01	-2.40	28.57	1360
FP-034	6/22/2026 8:03:52 AM	-0.29	-0.29	3.9	4.3	0.308	0.368	-8.29	-8.31	28.51	1361
FP-035	6/1/2026 2:23:38 PM	-2.57	-1.87	4.7	4.1	0.447	0.331	-5.99	-5.76	28.49	1369
FP-036	6/1/2026 2:26:56 PM	-1.25	-1.00	2.9	2.5	2.088	1.553	-6.20	-6.28	28.49	1380
FP-037	6/1/2026 2:33:31 PM	-0.30	-0.31			0.000	0.000	-6.76	-6.74	28.48	1366

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
FP-038	6/3/2026 9:29:51 AM	-0.18	-0.23	6.5	8.0	0.828	1.248	-2.94	-4.39	28.57	1322
FP-038	6/17/2026 9:30:17 AM	-0.11	-0.27	0.7	1.0	0.009	0.022	-2.35	-2.26	28.59	1294
FP-039	6/3/2026 9:26:27 AM	-0.45	-0.43	16.9	16.7	5.686	5.553	-4.69	-4.65	28.6	1321
FP-040	6/17/2026 9:23:16 AM	-0.10	-0.08	3.3	7.8	0.023	0.135	0.17	0.25	28.57	1301
FP-041	6/11/2026 10:59:42 AM	-0.43	-0.35	22.6	21.7	3.074	2.846	-3.01		28.56	1296
FP-041	6/11/2026 11:01:38 AM	-0.33	-0.21	19.8	15.9	2.352	1.520	-6.63		28.56	1243
FP-042	6/8/2026 1:38:09 PM	-0.23	-0.21	17.1	15.6	5.946	4.978	-7.19	-6.09	28.59	1258
FP-043	6/17/2026 9:47:23 AM	-0.01	-0.20	12.5	14.7	3.155	4.353	-7.11	-6.78	28.59	1283
FP-044	6/17/2026 9:43:00 AM	-0.08	-0.08	5.1	5.0	0.524	0.509	-6.50	-6.67	28.57	1283
FP-045	6/3/2026 9:07:49 AM	-0.32	-0.29	12.6	12.6	3.238	3.241	-7.07	-7.05	28.6	1325
FP-046	6/23/2026 10:33:42 AM	-0.26	-0.26	1.5	2.3	0.048	0.110	-4.39	-4.83	28.63	1361
FP-047	6/5/2026 1:13:13 PM	-0.04	-0.04	1.3	1.5	0.032	0.043	0.00	0.00	28.41	1342
FP-050	6/8/2026 2:03:54 PM	-1.26	-0.79	0.0	0.0	-1.502	-1.466	-9.67		28.57	1365
FP-051	6/8/2026 2:16:12 PM	-3.32	-0.98	0.0	0.0	-0.011	-0.031	-9.14		28.4	1345
FP-052	6/3/2026 2:16:47 PM	-0.15	-0.14	16.2	16.2	1.598	1.605	-6.98	-7.03	28.49	1349
FP-053	6/3/2026 2:13:47 PM	-1.68	-1.26	2.4	1.4	0.118	0.039	-5.07	-5.86	28.47	1370
FP-054	6/8/2026 2:29:07 PM	-1.78	-0.92	45.4	26.9	4.768	1.672	-7.88		28.4	1424
FP-055	6/3/2026 2:41:46 PM	-0.21	-0.14	12.6	12.5	3.317	3.260	-7.13	-7.04	28.49	1358
FP-056	6/3/2026 10:06:38 AM	-0.24	-0.24	3.6	3.6	3.233	3.266	-7.75	-7.61	28.54	1348
FP-056	6/16/2026 9:41:00 AM	-0.26	-0.34	3.4	4.9	2.944	6.181	-7.74	-7.79	28.59	1343
FP-057	6/3/2026 9:08:41 AM	-0.56	-0.56	22.4	22.4	3.023	3.022	-12.81	-12.80	28.59	1404
FP-058	6/3/2026 9:22:51 AM	-0.75	-0.75	27.6	28.3	1.664	1.751	-13.11	-13.75	28.59	1393
FP-059	6/8/2026 12:07:12 PM	-0.24	-0.25	7.6	7.6	0.326	0.327	-14.54		28.4	1424
FP-060	6/26/2026 1:06:52 PM	-0.23	-0.22	9.4	9.5	1.804	1.859	-8.55	-8.40	28.55	1338
FP-061	6/5/2026 2:08:36 PM	-0.46	-0.45	2.4	2.5	0.124	0.136	-2.96	-2.92	28.41	1350
H-01 (EXP-01	6/12/2026 7:44:07 AM	-5.54	-5.54			5.406	5.406	0.00	0.00	28.67	1239
H-01 (EXP-01	6/22/2026 8:10:49 AM	-4.15	-4.09			4.192	4.133	-9.86	-9.44	28.64	1237
H-02 (EXP-01	6/1/2026 11:41:57 AM	-1.29	-1.29			1.285	1.278	-8.72	-8.80	28.74	1237
H-02 (EXP-01	6/22/2026 8:05:43 AM	-1.90	-1.89			1.915	1.901	-9.82	-9.57	28.64	1243
H-03 (EXP-01	6/1/2026 11:45:13 AM	-8.25	-8.23			8.566	8.439	-8.89	-8.76	28.74	1237
H-03 (EXP-01	6/22/2026 7:55:26 AM	-9.11	-9.23			9.367	9.450	-9.51	-9.51	28.61	1272
H-04 (EXP-04	6/1/2026 11:51:21 AM	-1.70	-0.98			1.678	0.969	-8.93	-9.09	28.74	1244
H-04 (EXP-04	6/1/2026 11:52:14 AM	-0.79	-0.79			0.795	0.795	-8.95	-8.98	28.74	1212
H-04 (EXP-04	6/22/2026 7:48:41 AM	-0.60	-0.59			0.609	0.589	-9.83	-9.45	28.6	1247

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
H-04 (EXP-0	6/22/2026 7:51:00 AM	-0.73	-0.90			0.731	0.900	-9.49	-9.66	28.62	1229
H-04 (EXP-0	6/22/2026 7:52:34 AM	-1.11	-1.11			1.110	1.115	-9.88	-9.59	28.62	1235
H-08 (EXP-0	6/8/2026 1:06:17 PM	-7.06	-7.05			7.031	7.072	-9.01	-9.02	28.57	1266
H-08 (EXP-0	6/17/2026 9:51:09 AM	-7.43	-7.96			7.559	8.178	-9.24	-9.31	28.58	1276
H-08 (EXP-0	6/17/2026 9:51:47 AM	-8.10	-8.10			8.287	8.280	-9.41	-9.41	28.6	1283
H-10 (EXP-1	6/8/2026 12:48:24 PM	-3.48	-0.31			3.590	0.387	-8.79	-8.85	28.55	1275
H-10 (EXP-1	6/8/2026 12:51:23 PM	-0.66	-0.68			0.762	0.803	-8.93	-8.93	28.57	1291
H-10 (EXP-1	6/17/2026 9:56:40 AM	-4.93	-4.88			4.945	4.921	-8.93	-9.04	28.57	1295
H-10 (EXP-1	6/17/2026 9:57:40 AM	-4.91	-4.90			4.956	4.948	-9.30	-9.19	28.57	1314
H-101W	6/8/2026 12:22:40 PM	-4.21	-4.44	19.7	19.7	0.478	0.482	-10.93	-10.61	28.64	1203
H-102A	6/8/2026 12:13:39 PM	-10.41	-10.85	13.3	13.5	1.081	1.109	-10.49	-11.06	28.67	1195
H-102A	6/19/2026 10:48:54 AM	-8.00	-8.05	37.2	37.4	8.272	8.376	0.00	0.00	28.76	1195
H-1401W	6/8/2026 12:09:07 PM	-10.37	-10.15	13.1	13.0	1.074	1.050	-10.81	-10.51	28.67	1203
H-1401W	6/8/2026 12:11:06 PM	-10.14	-9.46	12.6	12.0	0.986	0.899	-10.34	-9.80	28.67	1208
H-1404C	6/15/2026 1:54:09 PM	-0.70	-0.69	5.7	5.4	0.685	0.618	-12.37		28.68	1332
H-1404C	6/26/2026 12:54:36 PM	-0.84	-0.55	7.9	1.4	1.374	0.043	-15.03	-14.21	28.54	1357
H-1404C	6/26/2026 12:55:41 PM	-0.48	-0.49	1.2	2.0	0.033	0.086	-14.09	-14.11	28.51	1351
H-1405C	6/2/2026 9:16:38 AM	-2.03	-1.56	6.6	5.7	0.271	0.200	-3.58	-3.33	28.63	1309
H-1405C	6/16/2026 8:12:58 AM	-0.04	-0.04	1.0	1.2	0.006	0.009	0.33	0.33	28.63	1320
H-1406W	6/10/2026 8:42:28 AM	-1.59	-0.91	9.6	7.1	0.549	0.307	-11.01	-11.08	28.58	1260
H-1406W	6/17/2026 8:18:32 AM	-1.24	-1.26	5.2	5.2	0.164	0.166	-7.47	-7.66	28.62	1257
H-1408CR	6/12/2026 3:10:27 PM	-0.17	-0.15	7.4	7.4	6.258	6.256	-16.77		28.55	1270
H-1408CR	6/12/2026 3:12:01 PM	-0.16	-0.15	7.4	7.4	6.320	6.317	-16.67		28.55	1175
H-1408E	6/2/2026 2:36:46 PM	-0.11	-0.11	3.2	3.7	0.066	0.087	-8.88	-8.92	28.52	1384
H-1408E	6/16/2026 6:05:06 AM	-0.07	-0.07	3.3	3.3	0.067	0.066	-12.36	-12.38	28.51	1390
H-1408W	6/8/2026 12:44:22 PM	-4.81	-2.61	17.0	13.1	0.370	0.219	-10.47	-10.32	28.59	1244
H-1408W	6/8/2026 12:50:22 PM	-2.17	-1.03	14.7	10.0	0.277	0.129	-11.40	-11.16	28.59	1249
H-1409N	6/8/2026 3:03:33 PM	-1.19	-1.02	0.8	0.8	0.190	0.170	-11.05	-11.18	28.43	1372
H-1409N	6/17/2026 12:54:53 PM	-1.17	-0.48	0.4	0.5	0.051	0.069	-13.20	-13.10	28.48	1379
H-1410S	6/3/2026 12:33:58 PM	-9.80	-9.80	33.6	33.7	1.447	1.452	-10.39	-10.24	28.71	1238
H-1563N	6/3/2026 9:21:39 AM	-2.53	-1.98	7.4	4.9	0.345	0.155	-3.88	-4.63	28.6	1327
H-1563N	6/22/2026 11:47:58 AM	-1.34	-2.35	3.8	5.0	0.091	0.158	-3.28	-2.63	28.67	1317

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
H-1563S	6/2/2026 9:21:26 AM	-0.73	-0.70	1.0	0.8	0.109	0.072	-11.44	-11.59	28.63	1309
H-1563S	6/16/2026 8:15:23 AM	-0.29	-0.29	0.4	0.4	0.014	0.012	-7.61	-7.76	28.63	1312
H-1565E	6/2/2026 2:42:34 PM	-1.89	-1.81	1.8	4.5	0.020	0.131	-7.70	-7.70	28.52	1378
H-1565E	6/16/2026 6:10:30 AM	-3.41	-3.06	5.9	5.7	0.216	0.201	-11.82	-9.62	28.52	1387
H-1568N	6/2/2026 2:34:10 PM	-1.97	-1.99	8.4	7.9	1.486	1.307	-7.87	-8.46	28.53	1379
H-1568N	6/16/2026 6:03:23 AM	-2.28	-1.84	8.0	6.6	1.351	0.924	-11.24	-11.78	28.52	1386
H-1571S	6/3/2026 11:57:36 AM	-0.25	-0.24	4.5	4.5	0.045	0.046	-15.23	-15.22	28.67	1294
H-1572N	6/2/2026 12:49:04 PM	-0.97	-0.48	3.6	1.9	0.283	0.075	-15.64	-15.90	28.63	1357
H-1572N	6/2/2026 12:49:47 PM	-0.48	-0.47	2.0	2.0	0.083	0.082	-15.82	-15.83	28.63	1353
H-1572S	6/3/2026 11:52:57 AM	-0.85	-0.86	7.4	7.4	0.125	0.125	-14.94	-14.96	28.67	1282
H-1574N	6/10/2026 10:08:46 AM	-0.29	-0.26	10.3	10.2	0.122	0.120	-9.04		28.62	1220
H-1574N	6/10/2026 10:11:13 AM	-0.19	-0.16	7.4	1.2	0.063	0.002	-8.68		28.62	1211
H-1574N	6/25/2026 10:52:47 AM	-0.29	-0.14	2.9	7.9	0.009	0.073	-6.51		28.68	1194
H-1753N	6/2/2026 9:45:07 AM	-0.43	-0.44	4.3	4.1	0.040	0.037	-10.56	-10.47	28.6	1357
H-1753N	6/26/2026 8:26:29 AM	0.26	-0.26	2.3	2.5	0.011	0.013	-10.86	-11.70	28.55	1338
H-1753N	6/26/2026 8:31:04 AM	-0.16	-0.16	2.1	2.1	0.009	0.010	-11.25	-11.47	28.55	1349
H-1753N	6/26/2026 8:34:36 AM	-0.16	-0.15	2.7	2.7	0.015	0.015	-7.13	-7.13	28.55	1350
H-1753S	6/3/2026 9:43:25 AM	-4.59	-2.17	5.5	2.0	0.650	0.085	-4.71	-2.41	28.56	1344
H-1753S	6/22/2026 12:16:51 PM	-1.16	-1.01	1.8	1.2	0.068	0.027	-1.83	-1.34	28.64	1350
H-1756S	6/2/2026 8:48:21 AM	-0.77	-0.60	7.0	3.3	0.065	0.015	-10.15	-6.73	28.64	1299
H-1756S	6/16/2026 8:02:34 AM	-0.32	-0.25	5.0	3.5	0.033	0.016	-8.73	-7.27	28.63	1299
H-1757S	6/2/2026 9:11:24 AM	-0.83	-0.75	7.9	7.3	0.135	0.114	-11.53	-11.49	28.63	1314
H-1757S	6/16/2026 8:10:28 AM	-0.61	-0.60	6.2	5.9	0.083	0.077	-8.25	-8.25	28.63	1304
H-1760S	6/2/2026 2:13:24 PM	-2.49	-2.21	5.4	4.8	0.188	0.146	-10.87	-10.78	28.56	1376
H-1760S	6/17/2026 1:01:37 PM	-2.41	-2.07	3.8	3.4	0.093	0.076	-12.72	-12.57	28.48	1391
H-1762N	6/2/2026 10:45:08 AM	-0.33	-0.31	13.9	14.0	4.005	4.055	-10.28	-10.48	28.56	1387
H-1762N	6/16/2026 5:57:38 AM	-0.33	-0.33	13.5	14.5	3.815	4.362	-11.24	-12.08	28.5	1391
H-1763N	6/4/2026 8:24:17 AM	-0.06	-0.06	0.7	0.7	0.003	0.003	-16.12	-15.95	28.42	1398
H-1763S	6/3/2026 9:06:43 AM	-0.19	-0.19	5.6	5.5	0.039	0.038	-10.16	-10.15	28.62	1328
H-1764N	6/3/2026 8:45:22 AM	-4.46	-4.84	1.4	3.1	0.042	0.201	-13.76	-13.29	28.56	1373
H-1764S	6/3/2026 12:02:54 PM	-1.29	-0.80	6.5	4.7	0.266	0.138	-15.68	-15.45	28.64	1305

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
H-1767N	6/10/2026 1:57:55 PM	-1.25	-1.22	16.9	16.6	0.649	0.624	-13.98	-13.80	28.52	1242
H-1769N	6/1/2026 9:37:42 AM	-0.53	-0.32	13.6	13.8	0.493	0.505	-9.06	-8.17	28.49	1366
H-1769N	6/17/2026 8:57:31 AM	-0.16	-0.26	37.5	39.2	3.702	4.048	-8.24	-8.63	28.52	1379
H-1770N	6/1/2026 9:51:21 AM	-0.84	-0.81	6.5	7.2	0.869	1.063	-7.54	-7.61	28.52	1368
H-1770N	6/15/2026 9:30:00 AM										
H-1770N	6/15/2026 9:30:00 AM										
H-1770N	6/17/2026 9:09:18 AM	-0.17	-0.17	5.1	5.1	0.538	0.542	-8.59	-8.64	28.53	1361
H-1770S	6/2/2026 8:08:25 AM	-0.72	-0.68	1.6	2.2	0.053	0.095	-10.42	-10.48	28.62	1320
H-1770S	6/16/2026 7:49:23 AM	-0.28	-0.28	1.3	1.2	0.033	0.030	-7.74	-7.74	28.63	1303
H-1771A	6/4/2026 2:01:14 PM	-0.70	-0.73	9.9	11.1	0.621	0.778	-5.58	-5.71	28.44	1354
H-1771B	6/4/2026 10:07:06 AM	-8.47	-7.28	0.2	0.4	0.001	0.003	-8.63	-8.69	28.41	1387
H-1771B	6/17/2026 2:04:52 PM	-0.35	-0.35	2.4	2.5	0.119	0.133	-10.04	-10.53	28.51	1417
H-1774N	6/1/2026 1:44:46 PM	-0.84	-0.79	9.1	9.2	1.760	1.811	-7.43	-7.62	28.52	1343
H-1774N	6/17/2026 9:23:18 AM	-0.48	-0.48	10.6	10.5	2.364	2.346	-8.49	-8.49	28.55	1354
H-1801S	6/2/2026 12:28:57 PM	-0.28	-0.27	1.8	1.7	0.061	0.054	-16.32	-16.20	28.65	1334
H-1802S	6/2/2026 12:44:59 PM	-0.10	-0.50	10.1	8.7	0.129	0.098	-16.41	-16.18	28.63	1359
H-1803N	6/1/2026 10:35:00 AM										
H-1803N	6/1/2026 10:35:00 AM										
H-1803N	6/1/2026 10:35:20 AM	-4.88	-4.81	56.0	57.6	4.716	4.998	0.58	0.38	28.59	1374
H-1803N	6/8/2026 9:49:51 AM	-6.38	-7.07	65.0	68.3	6.416	7.103	0.34	0.34	28.51	1354
H-1803N	6/15/2026 9:16:07 AM	-3.29	-3.05	47.6	45.5	3.391	3.087	0.33	0.34	28.64	1365
H-1803N	6/22/2026 9:30:13 AM	-3.78	-4.25	51.1	53.4	3.927	4.288	0.33	0.32	28.54	1351
H-1803N	6/29/2026 9:51:07 AM	-5.52	-5.05	62.1	59.9	5.837	5.424	0.32	0.29	28.49	1354
H-1804B	6/8/2026 11:58:30 AM	-12.58	-11.77	4.7	12.4	0.133	0.941	-12.24		28.4	1345

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
H-1804B	6/16/2026 12:52:32 PM	-13.09	-13.15	43.1	43.2	12.290	12.380	-12.86	-14.46	28.55	1389
H-1804N	6/4/2026 1:46:12 PM	-3.59	-3.58	1.6	1.9	0.055	0.079	-6.21	-6.22	28.45	1361
H-1804S	6/3/2026 8:47:55 AM	-6.08	-7.14	11.4	12.2	0.827	0.947	-11.83	-12.41	28.56	1369
H-1805A	6/3/2026 12:28:07 PM	-2.51	-2.51	2.8	2.7	0.852	0.797	-13.69	-13.29	28.59	1400
H-1805A	6/19/2026 10:10:27 AM	-3.17	-3.40	34.0	37.6	1.484	1.817	-20.73	-25.91	28.58	1409
H-1805B	6/3/2026 8:35:39 AM	-0.52	-0.52	2.3	2.3	0.101	0.101	-14.39	-14.35	28.55	1384
H-1805S	6/3/2026 8:58:45 AM	-4.92	-5.07	23.5	29.6	1.318	2.105	-15.18	-14.85	28.59	1336
H-1806A	6/8/2026 11:47:40 AM	-0.29	-0.29	2.0	2.0	0.079	0.079	-13.73		28.4	1358
H-1806B	6/2/2026 12:54:05 PM	-1.53	-1.37	34.1	32.5	1.564	1.402	-16.43	-16.32	28.63	1364
H-1806B	6/2/2026 12:56:02 PM	-1.36	-1.36	7.9	7.9	1.338	1.335	-16.41	-16.33	28.63	1364
H-1806N	6/8/2026 10:18:36 AM	-1.93	-1.76	9.0	6.3	0.108	0.053	-11.43	-11.41	28.45	1350
H-1806S	6/3/2026 9:15:06 AM	-1.24	-0.85	5.4	3.5	0.068	0.029	-15.71	-16.14	28.63	1284
H-1807A	6/2/2026 11:48:10 AM	-11.72	-11.92	8.9	13.3	0.104	0.233	-16.37	-16.11	28.64	1353
H-1807N	6/8/2026 10:40:50 AM	-0.98	-0.96	0.4	0.5	0.001	0.001	-6.68	-6.51	28.45	1323
H-1807S	6/2/2026 12:21:01 PM	-15.59	-14.19	39.4	39.6	1.981	1.992	-15.55	-15.42	28.67	1308
H-1952S	6/3/2026 2:08:31 PM	0.56	-0.15	1.3	6.3	0.036	0.823	-6.03	-6.09	28.49	1363
H-1952S	6/3/2026 2:09:49 PM	-0.11	-0.11	6.2	6.2	0.811	0.801	-6.17	-6.10	28.49	1368
H-1952S	6/16/2026 6:13:44 AM	-0.47	-0.69	5.6	7.1	0.666	1.058	-6.63	-7.79	28.52	1377
H-1955C	6/3/2026 12:19:34 PM	-0.51	-0.45	9.4	8.2	1.792	1.355	-13.50	-13.10	28.59	1383
H-1955C	6/19/2026 10:16:23 AM	-0.59	-0.57	10.3	9.6	2.081	1.789	-22.14	-18.75	28.56	1412
H-1955N	6/4/2026 1:43:34 PM	-1.53	-1.53	4.9	5.0	0.147	0.153	-6.26	-6.59	28.47	1349
H-1956B	6/3/2026 8:18:31 AM	-1.54	-1.54	10.4	9.7	0.251	0.220	-14.03	-14.04	28.53	1397
H-1956B	6/9/2026 11:39:37 AM	-1.18	-1.13	6.4	4.0	0.096	0.038	-14.99	-14.56	28.45	1383
H-1956N	6/8/2026 10:12:46 AM	-0.57	-0.57	1.8	2.5	0.019	0.039	-7.96	-6.67	28.45	1346
H-1956S	6/2/2026 12:40:22 PM	-13.77	-13.22	3.6	4.0	1.426	1.716	-16.70	-16.74	28.66	1328
H-1957B	6/2/2026 11:59:17 AM	-1.41	-1.33	26.6	25.2	4.479	4.030	-17.45	-18.34	28.63	1358
H-1957N	6/8/2026 10:21:49 AM	-2.20	-2.32	2.9	2.6	0.055	0.042	-10.80	-10.81	28.45	1337

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
H-1957S	6/2/2026 12:31:09 PM	-0.46	-0.46	3.0	2.6	0.180	0.134	-16.53	-16.47	28.67	1330
H-1958C	6/2/2026 11:45:15 AM	-1.25	-1.44	3.5	6.7	0.075	0.277	-16.34	-16.08	28.64	1347
H-1958C	6/9/2026 11:32:42 AM	-1.74	-2.03	5.9	5.6	0.225	0.202	-14.44	-14.49	28.52	1334
H-1958N	6/8/2026 10:36:31 AM	-2.30	-2.10	48.3	4.2	3.079	0.023	-5.95	-6.55	28.47	1346
H-1958S	6/18/2026 2:13:22 PM	-0.13	-0.13	0.4	0.3	0.001	0.001	-9.21	-9.20	28.59	1319
H-1958S	6/18/2026 2:17:07 PM	-0.24	-0.16	4.3	1.9	0.110	0.023	-9.09	-9.14	28.59	1324
H-1962N	6/1/2026 1:28:34 PM	-1.39	-1.16			0.058	0.004	-7.09	-7.25	28.49	1364
H-1962N	6/1/2026 1:34:46 PM	-1.11	-1.08			0.041	0.000	-7.38	-7.25	28.49	1369
H-1962N	6/5/2026 9:09:10 AM	-1.29	-1.19			0.023	0.000	-8.22	-8.33	28.43	1363
H-1962N	6/17/2026 9:12:30 AM	-0.75	-0.74			0.000	0.000	-8.17	-8.05	28.55	1375
H-1963N	6/1/2026 9:34:55 AM	-0.50	-0.49	5.4	4.5	0.083	0.058	-8.89	-8.70	28.49	1385
H-1963N	6/17/2026 8:54:38 AM	-0.12	-0.12	6.2	6.5	0.107	0.119	-8.15	-8.74	28.51	1382
H-1963N	6/17/2026 12:20:47 PM	-0.09	-0.09	5.2	5.3	0.077	0.078	-8.63	-8.60	28.48	1367
H-1963N	6/17/2026 12:21:03 PM	-0.08	-0.08	5.4	5.3	0.083	0.079	-8.83	-8.55	28.48	1376
H-1966N	6/1/2026 1:55:09 PM	-0.59	-0.44	4.3	4.4	1.943	2.073	-5.77	-5.71	28.5	1355
H-1966N	6/22/2026 10:30:50 AM	-0.18	-0.18	4.1	4.0	1.770	1.683	-4.39	-3.91	28.55	1355
H-1967E	6/10/2026 2:54:38 PM	-10.26	-10.31	0.0	0.0	-0.019	-0.002	-14.21		28.56	1043
H-1967E	6/10/2026 2:55:55 PM	-9.74	-9.76	0.0	0.0	-0.030	-0.026	-14.60		28.56	1079
H-1967W	6/8/2026 11:55:13 AM	-8.46	-8.61	29.8	30.6	1.136	1.196	-11.07	-11.40	28.67	1195
H-2050E	6/11/2026 12:37:27 PM	-11.27	-11.32	3.4	3.2	1.185	1.047	-12.29		28.71	1096
H-2050W	6/3/2026 12:58:46 PM	-1.06	-1.00	4.3	3.6	0.374	0.266	-4.71	-4.62	28.74	1185
H-2051W	6/8/2026 11:47:12 AM	-9.64	-10.01	25.5	26.7	0.826	0.905	-12.63	-12.66	28.67	1196
H-2053E	6/10/2026 3:02:37 PM	-5.70	-4.30	43.5	33.8	2.311	1.390	-14.43		28.56	1093
H-2053W	6/8/2026 12:17:00 PM	-10.47	-10.52	28.9	29.9	1.073	1.144	-10.72	-10.68	28.67	1201
H-2055E	6/3/2026 12:15:20 PM	-1.45	-0.40	16.3	5.0	1.664	0.158	-14.05	-13.85	28.67	1275
H-2055E	6/19/2026 4:01:38 PM	-0.23	-0.24	9.7	9.7	0.556	0.559	-14.96		28.6	1316
H-2056B	6/10/2026 3:26:06 PM	-1.68	-1.67	0.7	0.7	0.052	0.059	-7.35		28.56	1119
H-2056W	6/8/2026 11:51:53 AM	-5.97	-6.10	59.5	66.0	4.563	5.643	-10.86	-11.69	28.67	1198
H-2057E	6/10/2026 2:59:49 PM	-9.05	-10.98	6.5	3.8	0.862	0.302	-10.98		28.56	1050
H-2057W	6/8/2026 11:59:37 AM	-1.98	-1.26			2.019	1.323	-9.42	-9.17	28.67	1195

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
H-2057W	6/8/2026 12:01:57 PM	-1.20	-0.87			1.320	0.862	-11.31	-10.31	28.67	1196
H-2058E	6/10/2026 3:18:13 PM	-6.64	-6.62	50.7	50.5	3.045	3.024	-9.94		28.56	1056
H-2058W	6/8/2026 11:49:40 AM	-5.09	-4.88	24.4	17.2	0.757	0.373	-12.00	-10.57	28.67	1199
H-2059E	6/25/2026 7:45:33 AM	-17.26	-17.09	5.6	3.1	0.670	0.205	-17.87		28.72	1138
H-2059W	6/8/2026 12:39:30 PM	-4.10	-3.00	38.7	33.7	3.554	2.675	-9.02	-7.40	28.62	1231
H-2161E	6/25/2026 7:39:50 AM	-5.92	-5.88	54.5	54.7	3.439	3.574	-17.84		28.7	1181
H-2161W	6/8/2026 12:36:22 PM	-6.74	-6.42	38.8	32.8	1.952	1.389	-9.77	-9.84	28.63	1224
H-2163C	6/1/2026 10:28:26 AM	-0.67	-0.65	0.9	0.9	0.093	0.095	-13.52		28.52	1250
H-2163C	6/17/2026 11:36:55 AM	-0.60	-0.61	1.3	1.4	0.182	0.191	-16.51	-16.50	28.64	1320
H-2163W	6/8/2026 1:21:45 PM	-1.75	-0.44	30.2	7.4	5.989	0.354	-11.38	-11.70	28.59	1253
H-2163W	6/8/2026 1:22:03 PM	-0.39	-0.39	6.5	6.3	0.276	0.259	-11.53	-11.18	28.59	1257
H-2164E	6/3/2026 12:08:19 PM	-0.31	-0.31	7.3	7.3	0.343	0.341	-13.77	-13.84	28.67	1276
H-2164E	6/19/2026 4:09:03 PM	-0.42	-0.40	0.0	0.0	-0.386	-0.384	-14.94		28.59	1296
H-2165E	6/10/2026 1:48:13 PM	-1.34	-1.34	8.3	8.1	0.441	0.425	-10.76	-10.65	28.5	1254
H-2165W	6/10/2026 8:33:57 AM	-0.06	-0.06	3.3	3.3	0.068	0.069	-11.13	-11.26	28.55	1267
H-2165W	6/16/2026 8:05:00 AM										
H-2165W	6/16/2026 8:05:00 AM										
H-2165W	6/17/2026 8:24:58 AM	-0.09	-0.09	12.4	12.4	0.930	0.930	-7.35	-8.28	28.59	1278
H-2166E	6/2/2026 11:55:24 AM	-0.68	-0.68	3.0	2.6	0.056	0.042	-5.07	-5.48	28.61	1357
H-2168C	6/3/2026 8:16:01 AM	-13.38	-13.12	38.9	39.6	1.897	1.961	-13.93	-13.88	28.52	1393
H-2168E	6/2/2026 12:04:16 PM	-1.64	-1.53	5.6	5.2	0.202	0.171	-16.53	-15.94	28.61	1363
H-2169C	6/3/2026 8:21:40 AM	-2.51	-2.52	6.4	4.9	0.053	0.031	-13.40	-13.56	28.54	1381
H-2169E	6/2/2026 1:13:50 PM	-0.44	-0.40	19.2	12.1	0.474	0.188	-16.31	-15.82	28.59	1378
H-2170N	6/15/2026 1:03:30 PM	-2.12	-1.78	18.7	12.2	2.243	0.946	-12.79	-13.51	28.71	1263
H-2170S	6/12/2026 11:45:52 AM	-1.72	-1.70	1.7	1.9	0.017	0.020	-11.44		28.64	1224
H-2171A	6/1/2026 9:28:09 AM	-0.91	-0.84	0.0	0.0	-0.032	-0.013	-2.15		28.66	1207
H-2171B	6/1/2026 10:04:39 AM	-1.96	-1.90	17.8	17.8	1.915	1.908	-3.36		28.65	1234
H-2171N	6/1/2026 8:58:16 AM	-1.10	-1.01	3.7	3.6	0.090	0.081	-10.24		28.65	1260
H-2171S	6/15/2026 1:06:14 PM	-1.38	-1.38	20.0	20.0	2.567	2.556	-13.72	-13.68	28.72	1262
H-2272W	6/8/2026 1:02:54 PM	-0.71	-0.65	11.3	7.3	0.823	0.346	-9.92	-10.85	28.56	1274
H-2272W	6/16/2026 8:49:15 AM	-0.47	-0.48	5.2	5.3	0.176	0.182	-10.35	-10.23	28.67	1292
H-2273W	6/2/2026 7:45:00 AM										
H-2273W	6/2/2026 7:45:00 AM										

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
H-2273W	6/2/2026 8:54:53 AM	-1.13	-1.00	1.9	4.6	0.022	0.134	-11.87	-11.71	28.63	1297
H-2273W	6/16/2026 8:21:18 AM	-0.52	-0.51	5.0	4.9	0.161	0.156	-9.05	-8.96	28.66	1302
H-2274B	6/11/2026 10:34:51 AM	-2.09	-2.19	2.9	3.6	0.021	0.033	-8.82		28.42	1286
H-2274B	6/17/2026 12:47:21 PM	-2.98	-3.34	8.7	8.1	0.202	0.177	-12.65	-12.64	28.5	1369
H-2274W	6/2/2026 8:36:16 AM	-1.02	-0.93	12.0	11.0	0.931	0.777	-8.50	-7.71	28.63	1303
H-2274W	6/16/2026 8:00:20 AM	-0.53	-0.45	4.7	3.7	0.139	0.088	-7.09	-7.20	28.66	1301
H-2275E	6/3/2026 9:04:41 AM	-0.62	-0.54	3.1	2.1	0.062	0.028	-10.31	-9.94	28.6	1340
H-2275W	6/2/2026 9:27:59 AM	-1.11	-1.08	4.1	5.0	0.106	0.158	-11.49	-11.38	28.63	1328
H-2275W	6/16/2026 8:53:25 AM	-1.21	-1.06	28.1	18.2	5.131	2.134	-8.37	-8.75	28.63	1329
H-2276A	6/2/2026 2:20:31 PM	-8.08	-7.42	20.7	19.1	1.005	0.852	-9.58	-9.29	28.56	1368
H-2276A	6/22/2026 9:30:29 AM	-4.82	-5.10	18.2	18.6	0.432	0.454	-5.74	-5.51	28.5	1387
H-2276A	6/22/2026 9:31:52 AM	-4.97	-4.83	18.5	18.4	0.448	0.443	-5.33	-5.28	28.53	1365
H-2276B	6/8/2026 2:59:25 PM	-4.03	-4.08	21.7	21.8	1.110	1.118	-10.88	-11.12	28.43	1374
H-2276B	6/17/2026 12:52:46 PM	-4.73	-4.72	22.5	22.1	1.192	1.158	-12.66	-12.60	28.48	1384
H-2276E	6/3/2026 8:54:18 AM	-0.64	-0.60	3.7	2.9	0.018	0.011	-14.26	-14.41	28.59	1347
H-2276W	6/2/2026 9:06:49 AM	-7.12	-5.87	12.3	11.1	0.926	0.755	-11.54	-11.65	28.63	1313
H-2276W	6/16/2026 8:07:54 AM	-4.88	-4.54	8.6	8.2	0.451	0.412	-8.39	-8.14	28.63	1307
H-2277A	6/3/2026 8:51:39 AM	-0.45	-0.45	0.9	1.1	0.004	0.007	-4.77	-4.52	28.56	1363
H-2277A	6/16/2026 9:24:22 AM	-1.63	-1.60	5.1	5.4	0.155	0.179	-6.33	-8.21	28.59	1353
H-2277B	6/2/2026 1:12:56 PM	-3.59	-2.29	2.7	1.9	2.020	1.008	-10.60	-10.99	28.56	1388
H-2277B	6/3/2026 8:54:09 AM	-1.23	-1.18	2.1	2.1	1.187	1.145	-3.32	-3.12	28.52	1360
H-2277B	6/19/2026 1:21:11 PM	-2.06	-2.07	0.6	0.7	0.107	0.113	-11.96	-11.81	28.58	1377
H-23 (EXP-2	6/1/2026 9:52:09 AM	-1.07	-0.91	1.9	1.6	0.071	0.048	-11.07		28.65	1286
H-23 (EXP-2	6/1/2026 9:54:19 AM	-0.90	-0.79	1.3	1.3	0.035	0.035	-11.01		28.65	1260
H-2301E	6/14/2026 2:18:45 PM	-2.97	-2.58	26.0	19.9	0.869	0.511	-14.71	-16.31	28.94	999
H-2301E	6/14/2026 2:24:14 PM	-2.25	-1.99	20.5	15.2	0.966	0.527	-14.93	-14.78	28.94	1008
H-2301E	6/14/2026 2:26:21 PM	-1.83	-1.85	15.2	16.0	0.527	0.588	-15.06	-16.01	28.94	1021
H-2301W	6/25/2026 1:05:18 PM	-12.14	-11.66	0.7	0.0	0.051	-0.002	-11.94		28.77	1076
H-2301W	6/25/2026 1:09:52 PM	-4.13	-3.99	0.0	4.3	-0.007	1.830	-11.92		28.77	1148

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
H-2301W	6/30/2026 8:35:25 AM	-14.71	-14.78	1.8	1.8	0.320	0.321	-18.35	-18.62	28.82	1143
H-2302C	6/8/2026 9:52:30 AM	-2.82	-2.33	27.5	23.9	1.787	1.339	-13.67	-15.49	28.72	1133
H-2302C	6/12/2026 2:48:52 PM	-1.83	-0.62	14.2	5.8	1.252	0.205	-21.05		28.62	1109
H-2302E	6/11/2026 10:52:08 AM	-8.42	-8.45	7.2	7.7	0.060	0.068	-9.53		28.57	1070
H-2303E	6/11/2026 10:55:35 AM	-7.66	-7.72	0.0	0.0	-0.031	-0.023	-8.06		28.69	1017
H-2303N	6/8/2026 9:57:28 AM	-3.58	-3.40	14.2	13.1	4.165	3.549	-15.34	-17.07	28.71	1136
H-2303S	6/25/2026 12:20:01 PM	0.71	-0.18	0.0	19.9	-0.064	0.430	-11.63		28.81	1076
H-2303S	6/25/2026 12:23:24 PM	-0.58	-0.49	21.5	22.2	0.518	0.552	-12.08		28.81	1093
H-2304E	6/11/2026 10:58:48 AM	-5.84	-5.97	0.0	0.0	-0.016	-0.009	-7.16		28.69	1020
H-2304S	6/11/2026 11:10:09 AM	-2.70	-1.90	31.1	24.7	5.955	3.760			28.68	1122
H-2305N	6/8/2026 10:04:24 AM	-11.81	-10.52	7.1	5.7	1.047	0.672	-14.98	-14.95	28.69	1150
H-2305S	6/11/2026 1:24:17 PM	-3.74	-3.16	35.3	25.6	2.783	1.461	-18.48		28.67	1063
H-2306N	6/11/2026 12:47:49 PM	-3.08	-2.41	47.0	33.6	4.869	2.479	-13.90		28.64	1158
H-2307S	6/8/2026 9:41:48 AM	0.29	-0.07	12.4	22.2	0.340	1.095	-21.13	-17.15	28.7	1140
H-2307S	6/8/2026 9:42:18 AM	-0.11	-0.11	21.3	21.4	1.001	1.018	-16.53	-17.00	28.7	1146
H-2307S	6/8/2026 11:07:20 AM	-3.94	-3.97	19.6	19.9	0.918	0.947	-9.71	-9.98	28.52	1274
H-2307S	6/12/2026 1:35:06 PM	-0.17	-0.38	24.7	29.5	1.343	1.917	-26.61		28.61	1201
H-2308S	6/8/2026 9:47:16 AM	-0.36	-0.39	11.3	12.7	0.160	0.202	-15.34	-16.18	28.7	1144
H-2308S	6/12/2026 1:23:49 PM	-0.32	-0.35	17.0	23.3	0.343	0.649	-28.94		28.48	1211
H-2309N	6/1/2026 10:38:59 AM	-10.77	-10.79	3.9	3.8	0.092	0.087	-12.81		28.53	1309
H-2309S	6/11/2026 1:19:20 PM	-1.89	-2.08	24.4	28.1	0.695	0.921	-18.32		28.65	1109
H-2310N	6/10/2026 3:31:54 PM	-1.50	-0.66	18.6	2.0	2.088	0.025	-7.63		28.53	1188
H-2310N	6/10/2026 3:33:41 PM	-0.57	-0.56	1.4	1.4	0.011	0.012	-7.67		28.53	1325
H-2310S	6/11/2026 12:41:51 PM	-0.17	-0.17	0.7	0.7	0.057	0.057	-13.00		28.66	1125
H-2401S	6/8/2026 10:24:48 AM	-7.98	-8.12	4.4	6.2	0.416	0.803	-15.61	-17.63	28.65	1196
H-2401S	6/12/2026 10:50:55 AM	-11.98	-12.51	46.2	48.2	2.546	2.773	-24.74		28.59	1198
H-2401S	6/30/2026 1:49:46 PM	-10.86	-13.85	9.8	10.3	1.986	2.184	-19.01		28.61	1158
H-2402N	6/8/2026 10:17:02 AM	-1.47	-0.67	9.1	5.1	1.745	0.537	-14.58	-14.84	28.63	1207
H-2402S	6/8/2026 10:36:11 AM	-2.48	-2.09	46.3	40.8	2.771	2.149	-17.71	-18.32	28.66	1194

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
H-2402S	6/12/2026 11:01:51 AM	-2.06	-0.78	41.2	17.6	3.695	0.671	-24.19		28.6	1178
H-2403N	6/8/2026 10:13:34 AM	-1.05	-0.94	9.8	9.1	2.031	1.743	-13.24	-13.93	28.64	1200
H-2403S	6/8/2026 10:10:36 AM	-0.11	-0.25	2.3	4.2	0.101	0.353	-15.84	-20.52	28.67	1172
H-2403S	6/12/2026 1:10:46 PM	-10.88	-10.89	0.0	1.0	-0.009	0.107	-20.74		28.6	1165
H-2404N	6/3/2026 1:04:10 PM	-3.38	-3.79	10.7	12.3	2.413	3.198	-13.48	-13.59	28.73	1175
H-2404S	6/8/2026 9:10:41 AM	-11.70	-11.95	18.9	20.0	0.471	0.529	-12.05	-12.27	28.67	1163
H-2405N	6/10/2026 9:20:55 AM	-0.73	-0.66	17.5	15.6	6.529	5.217	-13.60	-13.95	28.55	1258
H-29	6/15/2026 12:56:44 PM	-0.17	-0.18	4.8	4.8	0.470	0.472	-13.97	-13.93	28.71	1283
H-72	6/24/2026 10:05:28 AM	-1.28	-1.28	3.8	3.8	0.018	0.018	-9.98	-10.08	28.66	1301
H-74	6/15/2026 11:34:23 AM	-5.37	-5.32	7.1	7.1	1.057	1.045	-6.05	-6.06	28.75	1300
H-75	6/15/2026 1:24:56 PM	-1.94	-1.49	2.5	2.0	1.662	1.005	-6.19	-6.54	28.67	1301
H-79	6/3/2026 9:53:50 AM	-0.13	-0.14	4.2	5.5	0.023	0.039	-13.29	-13.13	28.63	1296
P-02R	6/1/2026 10:04:56 AM	-0.49	-0.48	9.3	9.3	0.520	0.520	-20.25	-20.42	28.75	1182
P-03R	6/1/2026 10:14:48 AM	-1.30	-1.28	3.0	3.0	0.940	0.935	-19.66	-19.87	28.76	1172
P-04	6/1/2026 10:26:15 AM	-0.69	-0.69			0.677	0.684	-18.13	-18.16	28.76	1160
P-05	6/1/2026 10:44:04 AM	-0.22	-0.23			0.223	0.235	-16.55	-16.65	28.76	1160
P-06R	6/1/2026 10:55:26 AM	-0.58	-0.59	4.2	4.2	0.108	0.111	-15.56	-15.64	28.78	1139
P-07R	6/3/2026 10:13:11 AM	-0.67	-0.67	4.7	4.6	2.290	2.181	-19.33	-19.23	28.76	1172
P-08R	6/1/2026 9:35:18 AM	-16.76	-16.70	5.4	6.3	0.188	0.254	-17.63	-17.44	28.76	1159
P-08R	6/1/2026 9:45:12 AM	-16.69	-16.77	15.1	14.3	0.295	0.266	-17.99	-17.10	28.74	1161
P-08R	6/1/2026 9:48:41 AM	-17.00	-17.23	14.1	17.4	0.260	0.397	-17.56	-17.88	28.75	1169
P-09	6/1/2026 1:04:32 PM	-0.49	-0.49			0.502	0.496	-11.60	-11.83	28.76	1147
P-10	6/1/2026 1:16:13 PM	-0.21	-0.20	3.7	3.9	1.446	1.549	-11.77	-12.79	28.77	1158
P-11	6/1/2026 1:24:13 PM	-0.50	-0.49	7.3	7.0	5.635	5.301	-12.61	-12.09	28.79	1149
P-12	6/1/2026 2:05:59 PM	-10.54	-11.03	1.8	1.8	0.020	0.021	-13.12	-13.52	28.8	1128
P-12	6/1/2026 2:07:33 PM	-10.18	-10.18	1.9	0.6	0.021	0.002	-12.68	-12.60	28.79	1133
P-13	6/1/2026 1:44:03 PM	-1.36	-1.40	9.0	9.0	1.618	1.622	-14.08	-14.43	28.82	1112
P-13	6/1/2026 1:53:17 PM	-13.44	-13.08	2.2	1.8	0.095	0.070	-14.29	-13.84	28.8	1120
P-14	6/1/2026 2:21:50 PM	-0.23	-0.20			0.226	0.163	-12.32	-10.79	28.83	1117
P-14	6/2/2026 10:41:03 AM	-0.45	-0.44			0.424	0.423	-13.99	-14.28	28.87	1100
P-15R	6/2/2026 10:52:46 AM	-1.36	-1.34	1.6	1.5	0.268	0.220	-13.48	-13.57	28.88	1106
P-16	6/9/2026 10:06:22 AM	-2.29	-2.28	4.6	4.5	5.383	5.292	-12.09	-11.95	28.76	1095
P-16	6/9/2026 10:12:29 AM	-2.58	-2.59	5.6	5.6	3.250	3.244	-12.03	-11.98	28.77	1083

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
P-17	6/9/2026 9:53:57 AM	-0.96	-0.95			0.944	0.940	-11.27	-11.37	28.74	1101
P-18RD	6/9/2026 10:45:27 AM	-9.37	-9.36	3.0	3.1	0.054	0.057	-11.01	-10.59	28.75	1100
P-18RS	6/9/2026 10:54:04 AM	-1.23	-1.22	5.8	5.8	3.505	3.515	-10.91	-10.86	28.76	1094
P-19	6/9/2026 1:21:14 PM	-0.71	-0.69	9.6	9.6	0.549	0.548	-8.62	-8.39	28.79	1084
P-20R	6/9/2026 1:01:59 PM	-1.03	-1.05	8.5	8.4	7.578	7.461	-9.13	-9.07	28.75	1117
P-20R	6/9/2026 1:10:19 PM	-1.81	-1.28	16.2	9.7	1.612	0.580	-8.52	-8.85	28.76	1106
P-20R	6/9/2026 1:12:39 PM	-1.24	-1.23	9.4	9.0	0.545	0.497	-8.42	-8.02	28.75	1102
P-21	6/9/2026 1:31:50 PM	-0.36	-0.34			0.348	0.343	-7.47	-8.08	28.75	1120
P-21RD	6/9/2026 1:39:47 PM	-3.38	-3.36	10.3	9.3	2.176	1.796	-7.14	-6.51	28.74	1129
P-21RS	6/9/2026 1:46:57 PM	-3.10	-3.14	16.0	15.9	0.586	0.579	-7.16	-7.60	28.73	1123
P-22RD	6/15/2026 1:51:06 PM	-3.73	-3.70	3.8	3.7	3.812	3.725	-7.23	-7.17	28.8	1180
P-22RS	6/15/2026 1:46:59 PM	-1.06	-1.05	26.0	25.7	1.565	1.528	-7.61	-7.52	28.81	1183
P-23	6/9/2026 2:24:44 PM	-0.25	-0.26	0.1	0.7	0.000	0.003	-7.00	-7.32	28.75	1107
P-24	6/10/2026 10:21:41 AM	-1.87	-1.89	11.5	11.6	2.708	2.722	-8.74	-8.77	28.72	1106
P-26	6/10/2026 10:43:44 AM	-5.79	-5.79			5.960	5.973	-8.12	-8.00	28.71	1123
P-27	6/10/2026 1:24:51 PM	-0.22	-0.22			0.220	0.213	-6.61	-6.56	28.66	1140
P-28	6/10/2026 1:37:21 PM	-3.46	-3.46			3.487	3.487	-6.16	-6.16	28.68	1146
P-29R	6/15/2026 7:50:21 AM	-1.40	-1.35	6.2	6.3	0.224	0.230	-10.34		28.84	1152
P-30R	6/15/2026 7:53:58 AM	-7.30	-7.23	11.6	11.6	2.729	2.695	-9.72		28.82	1165
P-32R1	6/15/2026 7:59:37 AM	-2.12	-2.07	2.9	2.7	9.297	7.577	-8.59		28.82	1188
P-32R2	6/15/2026 8:02:27 AM	-2.52	-2.43	11.3	11.2	2.621	2.583	-8.82		28.8	1220
P-33	6/15/2026 8:06:14 AM	-3.14	-3.08	0.0	0.0	2.955	2.942			28.78	1198
P-36	6/15/2026 8:14:41 AM	-0.83	-0.78	0.0	0.0	0.643	0.644			28.77	1211
P-37	6/15/2026 8:18:30 AM	-0.70	-0.63	0.9	0.9	0.205	0.198	-0.63		28.77	1230
P-38RD	6/15/2026 8:30:24 AM	-5.41	-5.37	18.0	16.6	0.388	0.323	-6.07		28.75	1243
P-38RS	6/15/2026 8:28:11 AM	-1.82	-1.75	13.5	14.4	1.109	1.251	-6.21		28.75	1201
P-39	6/15/2026 8:36:42 AM	-8.95	-8.69	1.0	1.3	0.021	0.032	-8.68		28.76	1283
P-41	6/15/2026 8:48:14 AM	-2.80	-2.70	0.0	0.0	0.080	0.031			28.77	1273
P-41	6/15/2026 8:50:24 AM	-1.74	-1.69	0.0	0.0	-0.096	-0.079			28.77	1207
P-42R	6/15/2026 8:58:53 AM	-7.78	-7.74	3.1	3.9	1.035	1.581	-8.82		28.77	1217
P-43	6/15/2026 9:08:50 AM	-4.65	-4.59	0.0	0.0	-4.618	-4.612	-9.24		28.78	1230
P-44RD	6/15/2026 9:11:45 AM	-8.95	-8.90	0.6	0.0	0.035	-0.057	-9.35		28.72	1191
P-44RS	6/15/2026 9:18:50 AM	-6.14	-6.04	4.8	4.0	2.563	1.797	-9.40		28.77	1188
P-45RD	6/15/2026 9:31:24 AM	-8.21	-8.17	7.7	6.8	0.369	0.287	-8.89		28.78	1234
P-45RS	6/15/2026 9:29:22 AM	-0.78	-0.68	1.8	2.7	0.019	0.046	-8.97		28.78	1211

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
P-46RD	6/15/2026 9:42:33 AM	-9.10	-9.06	0.0	1.7	0.216	0.018	-8.96		28.78	1194
P-46RS	6/15/2026 9:40:21 AM	-2.56	-2.52	23.8	23.1	3.596	3.389	-8.93		28.78	1230
P-47	6/15/2026 10:35:42 AM	-0.12	-0.11			0.109	0.100	-10.06	-9.34	28.77	1210
P-48	6/15/2026 10:47:00 AM	-0.13	-0.13	3.8	0.8	0.094	0.004	-11.15	-11.28	28.76	1194
P-49RD	6/15/2026 1:10:23 PM	-9.62	-9.61	14.7	14.8	1.396	1.409	-11.11	-11.12	28.79	1200
P-49RS	6/15/2026 12:57:56 PM	-1.02	-1.02	17.6	17.7	0.712	0.720	-11.46	-11.70	28.77	1182
P-49RS	6/15/2026 1:06:47 PM	-0.97	-0.96	17.8	17.9	0.730	0.732	-11.91	-10.49	28.79	1209
P-52	6/15/2026 12:36:30 PM	-0.57	-0.55	13.3	12.7	3.746	3.428	-16.23	-16.61	28.76	1213
P-52	6/15/2026 12:37:24 PM	-0.56	-0.54	12.9	13.0	3.518	3.582	-16.69	-16.99	28.79	1211
P-53	6/3/2026 2:24:03 PM	-1.39		16.1		0.336		-14.83		28.7	1220
P-53	6/3/2026 2:32:15 PM	-1.11	-0.49	14.5	8.4	4.459	1.469	-14.60	-15.18	28.68	1217
P-53	6/3/2026 2:35:13 PM	-0.43	-0.45	8.3	8.4	1.453	1.483	-15.18	-15.52	28.68	1218
P-54	6/3/2026 1:49:46 PM	-0.38	-0.34			0.376	0.337	-17.76	-17.80	28.72	1226
P-54	6/16/2026 2:27:41 PM	-0.80	-0.79	5.4	5.4	0.591	0.597	-16.36	-16.39	28.68	1233
P-55	6/3/2026 1:33:10 PM	-0.18	-0.18			0.137	0.135	-18.12	-17.90	28.69	1215
P-56	6/3/2026 1:00:08 PM	-0.28	-0.30			0.295	0.308	-18.39	-18.41	28.68	1209
P-56	6/3/2026 1:18:05 PM	-0.32	-0.30			0.343	0.309	-18.52	-17.45	28.71	1212
P-57	6/3/2026 12:32:14 PM	-0.32		2.8		0.009		-18.19		28.71	1254
P-60R	6/10/2026 2:07:25 PM	-1.74	-1.82	1.8	0.1	0.065	0.000	-3.64	-3.84	28.57	1225
P-61	6/10/2026 2:14:41 PM	-0.15	-0.17	6.0	6.0	3.818	3.817	-3.72	-3.71	28.57	1208
P-65	6/10/2026 2:29:10 PM	-0.62	-0.65	1.6	1.7	0.677	0.738	-3.72	-4.02	28.57	1215
P-71	6/15/2026 1:16:48 PM	-0.49	-0.65			0.478	0.657	-11.80	-11.70	28.77	1212
P-71	6/15/2026 1:17:31 PM	-0.67	-0.68			0.689	0.682	-10.96	-12.40	28.77	1212
P-75	6/10/2026 2:44:34 PM	-2.90	-2.92	13.1	13.7	1.058	1.159	-3.98	-4.12	28.57	1230
P-76	6/15/2026 8:24:20 AM	-2.20	-2.19	0.0	0.0	-2.327	-2.296	-6.26		28.74	1181
P-79	6/9/2026 10:24:04 AM	-0.20	-0.20			0.191	0.194	-10.60	-10.86	28.83	1034
SC-2000E	6/3/2026 12:31:16 PM	-4.09	-3.70	2.6	0.1	0.143	0.000	-9.96	-9.67	28.71	1216
SC-2501E	6/1/2026 10:05:00 AM										
SC-2501E	6/1/2026 10:05:00 AM										
SC-2501E	6/1/2026 10:05:41 AM	-1.58	-1.51	10.3	10.8	0.279	0.304	-5.88	-5.29	28.58	1357
SC-2501E	6/8/2026 9:41:04 AM	-2.79	-2.40	11.5	9.1	0.346	0.219	-7.73	-7.98	28.51	1350
SC-2501E	6/15/2026 9:12:25 AM	-0.04	-0.12	3.0	6.7	0.023	0.116	-4.72	-4.83	28.64	1368
SC-2501E	6/29/2026 9:32:13 AM	-3.70	-2.77	37.5	32.1	3.719	2.719	-9.38	-9.85	28.5	1355
SC-2501E	6/29/2026 9:37:36 AM	-2.28	-2.28	29.2	29.3	2.241	2.251	-10.08	-10.11	28.53	1355

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
SC-2501W	6/11/2026 9:57:09 AM	-0.04	-0.03	1.7	0.9	0.020	0.006	-4.90	-4.88	28.44	1360
SC-2501W	6/12/2026 9:03:41 AM	-0.20	-0.23	1.8	1.6	0.022	0.018	-5.01	-5.46	28.49	1352
SC-2501W	6/16/2026 8:35:07 AM	-0.55	-1.25	1.1	7.6	0.008	0.411	-7.60	-7.34	28.6	1360
SC-2501W	6/16/2026 8:37:36 AM	-1.03	-0.47	7.8	4.6	0.435	0.148	-7.16	-7.72	28.6	1362
SC-2501W	6/16/2026 8:39:56 AM	-0.42	-0.42	2.7	2.4	0.051	0.039	-8.13	-8.00	28.6	1363
SC-2501W	6/22/2026 10:01:39 AM	-0.23	-0.27	3.5	3.7	0.086	0.100	-1.01	-1.01	28.54	1358
SC-2501W	6/29/2026 10:05:06 AM	-2.07	-1.26	16.8	13.3	2.027	1.229	-4.75	-8.81	28.49	1365
SC-2501W	6/29/2026 10:07:43 AM	-1.15	-1.14	12.8	12.9	1.122	1.128	-9.52	-8.52	28.52	1365
SW-10	6/25/2026 12:49:30 PM	-9.73	-9.70	1.6	0.7	0.017	0.003	-9.68	-9.55	28.58	1331
SW-115	6/1/2026 10:41:10 AM	-8.90	-8.90	15.8	15.3	1.441	1.356	-14.42		28.71	1201
SW-154	6/26/2026 11:08:16 AM	-10.00	-10.01			0.115	0.103	-10.10	-10.10	28.63	1273
SW-187	6/8/2026 12:55:51 PM	-8.98	-8.99	13.7	13.2	0.045	0.042	-8.91	-8.93	28.56	1317
SW-1930	6/2/2026 5:58:06 AM	-9.80	-9.80	30.9	30.8	1.195	1.181	-9.80	-9.89	28.63	1259
SW-20	6/3/2026 10:03:24 AM	-0.03	-0.03	3.5	3.5	0.015	0.015	-19.75	-19.55	28.76	1169
SW-2503D	6/29/2026 5:49:38 AM	-10.27	-10.27	0.1	0.1	0.001	0.001	-10.24	-10.22	28.55	1266
SW-2503M	6/29/2026 5:56:58 AM	-7.47	-7.47	0.1	0.1	0.000	0.000	-9.76	-9.76	28.55	1268
SW-2503MD	6/29/2026 5:53:43 AM	-10.74	-10.74	0.4	0.3	0.014	0.010	-10.68	-10.69	28.55	1268
SW-2503S	6/29/2026 5:59:37 AM	-10.21	-10.23	0.3	0.3	0.009	0.011	-10.25	-10.26	28.55	1274
SW-2504D	6/29/2026 6:04:51 AM	-10.32	-10.27	0.4	0.4	0.003	0.003	-10.52	-10.46	28.55	1281
SW-2504M	6/29/2026 6:08:59 AM	-2.78	-2.70			0.002	0.000	-10.40	-10.10	28.55	1276
SW-2504MD	6/29/2026 6:15:30 AM	-10.44	-10.40	1.0	0.3	0.019	0.001	-10.47	-10.47	28.55	1281
SW-2504S	6/29/2026 6:12:14 AM	-10.19	-10.07	0.8	1.8	0.014	0.065	-10.15	-10.14	28.55	1276
SW-65	6/1/2026 10:45:05 AM	-12.92	-12.86	0.2	0.0	0.000	0.000	-14.49		28.7	1207
SW-66	6/26/2026 11:06:07 AM	-9.68	-9.73			0.074	0.134	-9.82	-9.77	28.63	1267
SW-70	6/8/2026 12:58:00 PM	-8.56	-8.73	20.6	6.7	0.101	0.011	-8.54	-8.79	28.54	1303
SW-71	6/10/2026 10:30:25 AM	-4.94	-4.94	1.8	1.8	0.334	0.334	-8.50	-8.46	28.71	1119
SW-72	6/15/2026 8:11:58 AM	-1.96	-1.89	0.0	0.0	0.203	0.024	-6.26		28.78	1224
SW-80	6/1/2026 11:35:52 AM	-6.24	-6.22	6.2	6.2	0.234	0.233	-9.54	-9.55	28.76	1230

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]
SW-9	6/8/2026 1:00:58 PM	-8.39	-8.73	17.7	6.7	0.075	0.011	-8.38	-8.70	28.55	1310
TC-1961C	6/3/2026 12:00:23 PM	-0.13	-0.15	2.3	2.5	0.012	0.014	-15.22	-15.39	28.63	1298
TC-1961E	6/3/2026 9:11:02 AM	-1.83	-2.19	6.2	8.9	0.090	0.186	-15.64	-16.39	28.63	1295
TC-2174	6/1/2026 6:25:00 AM										
TC-2174	6/1/2026 9:52:38 AM	-1.45	-1.36			1.455	1.340	0.35	0.34	28.58	1357
TC-2174	6/1/2026 6:25:00 PM										
TC-2174	6/8/2026 9:26:15 AM	-2.69	-2.59			2.705	2.583	0.30	0.15	28.51	1341
TC-2174	6/15/2026 8:52:15 AM	-0.43	-0.45			0.481	0.434	0.27	0.29	28.64	1366
TC-2174	6/22/2026 8:57:50 AM	-0.73	-0.81			0.741	0.817	0.18	0.19	28.56	1349
TC-2174	6/29/2026 9:19:30 AM	-1.99	-2.02			1.986	2.046	0.07	0.08	28.53	1347
VL-02	6/26/2026 12:25:21 PM	-18.84	-18.79	12.5	11.1	0.196	0.155	-19.04	-18.92	28.73	1174
WTD-02	6/14/2026 8:45:26 AM	-3.72	-3.68			3.758	3.727	-3.81	-3.73	28.65	1254
WTD-02	6/17/2026 1:24:35 PM	-1.07	-0.42			1.069	0.446	-1.74	-2.67	28.6	1283
WTD-02	6/17/2026 1:26:01 PM	-0.43				0.450		-2.84		28.6	1284
WTD-03	6/14/2026 8:49:13 AM	-4.38	-4.29			4.419	4.317	-4.56	-4.40	28.68	1232
WTD-06	6/14/2026 9:11:46 AM	-3.57	-3.58			3.596	3.619	-6.23	-6.35	28.72	1214
WTD-07	6/14/2026 9:07:02 AM	-6.35	-6.17			6.449	6.285	-6.32	-6.12	28.72	1200
WTD-10	6/14/2026 9:00:26 AM	-3.82	-3.80			3.854	3.800	-7.96	-7.72	28.72	1193

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
A-01	6/12/2026 11:15:57 AM	34.4312122	-118.6437863	No Flow Measurement,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
A-02	6/12/2026 11:23:56 AM	34.4316222	-118.6432602	No Adjustment Made,No Flow Measurement,
A-03	6/12/2026 11:26:57 AM	34.4319842	-118.6428288	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,No Flow Measurement
A-04	6/12/2026 11:30:07 AM	34.4322240	-118.6421968	No Flow Measurement,No Adjustment Made,
A-05	6/12/2026 11:32:50 AM	34.4324172	-118.6417282	No Flow Measurement
B-01	6/15/2026 10:15:16 AM	34.4338572	-118.6396358	Valve Adjustment:Barely Open
B-02R	6/15/2026 10:12:05 AM	34.4335452	-118.6395473	Valve Adjustment:Barely Open
B-03R	6/15/2026 10:20:53 AM	34.4337765	-118.6388308	Valve Adjustment:Barely Open
B-05	6/17/2026 1:59:31 PM	34.4336348	-118.6382588	
B-06	6/15/2026 2:05:25 PM	34.4340830	-118.6377663	Valve Adjustment:Barely Open
B-07R	6/15/2026 1:36:53 PM	34.4343085	-118.6374512	Valve Adjustment:Barely Open
B-08	6/17/2026 1:50:41 PM	34.4337605	-118.6373363	
B-09	6/15/2026 1:42:59 PM	34.4342537	-118.6370633	Valve Adjustment:Barely Open
B-10	6/15/2026 1:50:23 PM	34.4340287	-118.6365438	Valve Adjustment:Barely Open
B-11	6/15/2026 2:15:52 PM	34.4348295	-118.6369002	
B-12	6/15/2026 10:25:47 AM	34.4340680	-118.6385487	Valve Adjustment:Barely Open
B-13	6/15/2026 10:31:45 AM	34.4344347	-118.6379487	Valve Adjustment:Barely Open
B-14	6/17/2026 2:14:38 PM	34.4349215	-118.6370573	
C-03	6/12/2026 11:19:19 AM	34.4313662	-118.6434908	No Flow Measurement,No Adjustment Made,
C-07	6/29/2026 8:47:04 AM	34.4326463	-118.6414363	Valve Adjustment:Valve 100% Open
C-08	6/17/2026 3:11:40 PM	34.4336343	-118.6408742	
C-10	6/1/2026 10:50:14 AM	34.4347345	-118.6411170	No Adjustment Made
C-11	6/1/2026 10:25:20 AM	34.4352508	-118.6412927	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,
C-12	6/1/2026 11:10:05 AM	34.4359710	-118.6409023	Valve Adjustment:Audible Flow
C-15	6/1/2026 11:00:26 AM	34.4362475	-118.6410317	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
C-15	6/1/2026 11:01:35 AM	34.4362462	-118.6410415	
C-17B	6/15/2026 10:20:29 AM	34.4373342	-118.6419228	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,No Flow Measurement
C-18	6/15/2026 10:33:37 AM	34.4379835	-118.6425433	No Flow Measurement,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
C-19	6/15/2026 10:26:35 AM	34.4375732	-118.6421277	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,No Flow Measurement
C-20	6/15/2026 10:30:07 AM	34.4377448	-118.6424238	No Flow Measurement,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
C-24	6/15/2026 10:23:39 AM	34.4375802	-118.6421620	No Flow Measurement
C-25	6/15/2026 10:14:32 AM	34.4371003	-118.6416787	No Flow Measurement
C-26	6/15/2026 10:11:03 AM	34.4365818	-118.6412612	No Flow Measurement
C-27	6/1/2026 11:07:13 AM	34.4361735	-118.6409790	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
C-28	6/1/2026 10:21:01 AM	34.4354503	-118.6414445	No Adjustment Made
C-29	6/1/2026 10:34:31 AM	34.4348812	-118.6411995	No Adjustment Made
C-30	6/17/2026 2:55:29 PM	34.4342617	-118.6412690	
CV-02	6/12/2026 11:43:37 AM	34.4335613	-118.6414020	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,
CV-03	6/12/2026 11:40:58 AM	34.4333830	-118.6414835	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,
CV-04	6/12/2026 11:38:00 AM	34.4331313	-118.6416967	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,
CV-05	6/15/2026 12:39:47 PM	34.4328273	-118.6422080	Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Valve 100% Open
CV-06	6/10/2026 2:24:10 PM	34.4326848	-118.6428472	Valve Adjustment:Surging Liquid in Header
CV-108-52	6/2/2026 8:10:00 AM			AirTech Lab
CV-108-52	6/2/2026 8:10:00 AM			AirTech Lab; [User entered 0.26%]
CV-108-52	6/2/2026 8:18:48 AM	34.4334033	-118.6506887	Valve Adjustment:Barely Open,Surging Liquid in Header
CV-108-52	6/16/2026 7:54:36 AM	34.4334198	-118.6506927	Valve Adjustment:Increased Flow/Vacuum,Surging Liquid in Header
CV-113	6/4/2026 7:45:00 AM			Air Tech Lab; [User entered 3.2%]
CV-113	6/4/2026 7:45:00 AM			AirTech Lab
CV-113	6/5/2026 10:19:11 AM	34.4369675	-118.6467385	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-113	6/17/2026 12:35:29 PM	34.4369502	-118.6467418	Valve Adjustment:Barely Open
CV-113	6/19/2026 12:51:33 PM	34.4369747	-118.6467112	Valve Adjustment:Increased Flow/Vacuum
CV-114	6/1/2026 9:43:10 AM	34.4367351	-118.6476329	Valve Comment:Well head notified hard piped with stainless;Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open;Well Condition:Good

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-114	6/1/2026 9:44:20 AM	34.4367358	-118.6476348	Valve Comment:Well was hard piped;Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-114	6/1/2026 9:50:00 AM			AtmAA; [User entered 16.2%]
CV-114	6/1/2026 9:50:00 AM			AtmAA
CV-114	6/8/2026 9:22:28 AM	34.4367217	-118.6476358	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-114	6/15/2026 8:40:00 AM			Air Tech Lab; [User entered 0%]
CV-114	6/15/2026 8:40:00 AM			Air Tech Lab
CV-114	6/15/2026 8:49:54 AM	34.4367368	-118.6476286	Valve Adjustment:No Flow Measurement,High Temp
CV-114	6/22/2026 8:59:44 AM	34.4367495	-118.6476333	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-114	6/29/2026 9:16:56 AM	34.4367411	-118.6476295	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-1424	6/3/2026 12:24:43 PM	34.4351313	-118.6450950	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-1424	6/19/2026 10:08:12 AM	34.4351007	-118.6450502	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-1532A	6/11/2026 10:55:34 AM	34.4338953	-118.6507965	
CV-1532A	6/12/2026 10:00:41 AM	34.4338742	-118.6508142	No Flow Measurement,Reduced System Vacuum,
CV-1532A	6/16/2026 8:55:00 AM			Air Tech Lab; [User entered 1.1%]
CV-1532A	6/16/2026 8:55:00 AM			Air Tech Lab
CV-1532A	6/17/2026 10:11:24 AM	34.4338770	-118.6508417	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open
CV-1532A	6/17/2026 10:11:46 AM	34.4338757	-118.6508293	Valve Adjustment:NSPS/EG CAI,High O2
CV-1532A	6/17/2026 1:12:53 PM			
CV-1534A-P	6/3/2026 10:00:00 AM			AtmAA; [User entered 13.69%]
CV-1534A-P	6/3/2026 10:01:37 AM	34.4336236	-118.6508030	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-1534A-P	6/3/2026 10:04:58 AM	34.4336244	-118.6508028	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Well (Watered In)
CV-1534A-P	6/10/2026 10:19:33 AM	34.4335967	-118.6508119	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Well (Watered In)
CV-1534A-P	6/17/2026 9:37:43 AM	34.4336174	-118.6507981	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,Valve 100% Open

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-1535	6/2/2026 8:13:51 AM	34.4333142	-118.6503422	Valve Adjustment:Decreased Flow/Vacuum,Barely Open;Well Condition:Good
CV-1535	6/15/2026 10:05:00 AM			Air Tech Lab
CV-1535	6/15/2026 10:05:00 AM			Air Tech Lab; [User entered 0.89%]
CV-1535	6/16/2026 7:47:10 AM	34.4333457	-118.6503130	Valve Adjustment:Barely Open
CV-1601D	6/1/2026 10:26:12 AM	34.4311218	-118.6486580	
CV-1601D	6/17/2026 11:48:50 AM	34.4311047	-118.6486723	Valve Adjustment:Audible Flow
CV-1601S	6/1/2026 10:23:27 AM	34.4311295	-118.6487252	
CV-1601S	6/17/2026 11:45:15 AM	34.4311063	-118.6486693	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-1604	6/3/2026 11:55:24 AM	34.4321867	-118.6450257	Valve Adjustment:Decreased Flow/Vacuum
CV-1701D	6/3/2026 9:34:02 AM	34.4335862	-118.6433250	Valve Adjustment:Decreased Flow/Vacuum
CV-1701S	6/3/2026 9:28:58 AM	34.4335875	-118.6433288	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-1701S	6/3/2026 9:29:59 AM	34.4335855	-118.6433303	Valve Adjustment:NSPS/EG CAI,High Temp
CV-1901	6/1/2026 2:11:40 PM	34.4356955	-118.6508015	Valve Adjustment:Barely Open
CV-1901	6/17/2026 9:45:56 AM	34.4357108	-118.6508282	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-1902A	6/3/2026 9:06:07 AM	34.4345990	-118.6503238	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum,Barely Open
CV-1902A	6/3/2026 9:06:48 AM	34.4345983	-118.6503061	Valve Adjustment:No Flow Measurement,High Temp
CV-1902A	6/3/2026 9:10:00 AM			AtmAA; [User entered 15.84%]
CV-1902A	6/10/2026 9:19:44 AM	34.4346248	-118.6502866	Valve Comment:Install sample port on system side;Valve Adjustment:No Flow Measurement,High Temp
CV-1902A	6/12/2026 8:25:30 AM			
CV-1902A	6/16/2026 9:20:00 AM			Air Tech Lab
CV-1902A	6/16/2026 9:20:00 AM			Air Tech Lab; [User entered 19%]
CV-1902A	6/17/2026 8:55:02 AM	34.4346099	-118.6503193	Valve Adjustment:No Flow Measurement,High Temp
CV-1902A	6/24/2026 1:28:33 PM	34.4345962	-118.6503122	Valve Adjustment:No Flow Measurement,High Temp
CV-1905	6/4/2026 8:18:33 AM	34.4334977	-118.6459860	Valve Adjustment:Increased Flow/Vacuum
CV-1905	6/8/2026 12:30:27 PM			
CV-1905	6/9/2026 12:51:17 PM	34.4335038	-118.6459933	Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum
CV-1905	6/16/2026 11:18:39 AM			
CV-1905	6/16/2026 11:19:38 AM			
CV-1905	6/16/2026 11:21:07 AM			
CV-1905	6/16/2026 12:30:54 PM			
CV-2001	6/6/2026 7:44:37 AM			
CV-2001	6/10/2026 8:24:20 AM	34.4322795	-118.6505758	Valve Adjustment:Decreased Flow/Vacuum

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-2001	6/10/2026 3:52:07 PM			
CV-2001	6/10/2026 3:52:18 PM			
CV-2001	6/16/2026 8:10:00 AM			Air Tech Lab
CV-2001	6/16/2026 8:10:00 AM			Air Tech Lab; [User entered 7.9%]
CV-2001	6/17/2026 8:30:39 AM	34.4322735	-118.6505840	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
CV-2001	6/18/2026 2:34:40 PM			
CV-2001	6/18/2026 2:34:54 PM			
CV-2001	6/19/2026 12:17:40 PM			
CV-2001	6/24/2026 1:53:55 PM			
CV-2001	6/30/2026 1:20:37 PM			
CV-2001	6/30/2026 1:20:54 PM			
CV-2002	6/2/2026 8:20:00 AM			AirTech Lab
CV-2002	6/2/2026 8:20:00 AM			AirTech Lab; [User entered 15%]
CV-2002	6/3/2026 9:45:00 AM			AtmAA; [User entered 13.6%]
CV-2002	6/3/2026 9:49:56 AM	34.4328043	-118.6511557	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum,Surging Liquid in Well (Watered In);Well Condition:Poor;Well Repairs:Flex Hose,Valve,Surging
CV-2002	6/3/2026 9:50:58 AM	34.4328125	-118.6511588	Valve Adjustment:NSPS/EG CAC,High Temp,Surging Liquid in Well (Watered In);Well Condition:Poor;Well Repairs:Flex Hose,Valve,Surging
CV-2002	6/10/2026 1:36:51 PM	34.4328039	-118.6511658	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	6/19/2026 3:46:32 PM	34.4328625	-118.6511985	High Temp
CV-2002	6/19/2026 3:47:45 PM	34.4328573	-118.6511515	
CV-2003	6/2/2026 8:25:55 AM	34.4334122	-118.6507297	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open
CV-2003	6/2/2026 8:27:03 AM	34.4334138	-118.6507287	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open
CV-2003	6/16/2026 7:56:51 AM	34.4334228	-118.6507073	Valve Adjustment:NSPS/EG CAC,Barely Open,Surging Liquid in Header
CV-2006	6/3/2026 9:12:33 AM	34.4352376	-118.6506274	Valve Adjustment:Audible Flow,High Temp
CV-2006	6/3/2026 9:20:00 AM			AtmAA; [User entered 17.98%]
CV-2006	6/10/2026 9:32:53 AM	34.4352423	-118.6506459	Valve Adjustment:High Temp
CV-2006	6/17/2026 8:49:42 AM	34.4352427	-118.6506437	Valve Adjustment:No Flow Measurement,High Temp
CV-2006	6/24/2026 1:42:38 PM	34.4352210	-118.6506450	Valve Adjustment:High Temp
CV-2007	6/4/2026 8:55:00 AM			Air Tech Lab; [User entered 6.5%]
CV-2007	6/4/2026 8:55:00 AM			AirTech Lab
CV-2007	6/4/2026 10:45:16 AM	34.4361798	-118.6469965	Valve Adjustment:Barely Open
CV-2007	6/5/2026 10:16:34 AM			

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-2007	6/23/2026 10:08:32 AM	34.4361685	-118.6470103	Valve Adjustment:Decreased Flow/Vacuum,Valve 100% Closed,Surging Liquid in Header
CV-2008	6/4/2026 1:53:28 PM	34.4361997	-118.6462408	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2008	6/5/2026 1:00:43 PM			
CV-2008	6/23/2026 9:59:12 AM	34.4362092	-118.6462383	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2009	6/23/2026 10:05:54 AM			
CV-2009	6/25/2026 9:27:32 AM	34.4362753	-118.6452817	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2009	6/25/2026 9:43:11 AM	34.4362735	-118.6452127	NSPS/EG CAI,High Temp,
CV-2009	6/25/2026 9:45:41 AM	34.4362663	-118.6452618	NSPS/EG CAC,Audible Flow,
CV-2009A	6/4/2026 7:11:53 AM			
CV-2009A	6/4/2026 7:37:11 AM			
CV-2009A	6/4/2026 8:22:33 AM			
CV-2009A	6/8/2026 11:36:43 AM	34.4359533	-118.6452952	
CV-2010	6/2/2026 11:42:01 AM	34.4356313	-118.6435783	Valve Adjustment:Decreased Flow/Vacuum
CV-2010	6/16/2026 1:15:18 PM			
CV-2010A	6/2/2026 11:38:03 AM	34.4357057	-118.6436815	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2010A	6/2/2026 11:38:57 AM	34.4356867	-118.6436675	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-2011	6/2/2026 12:12:48 PM	34.4342040	-118.6434595	Valve Adjustment:Audible Flow
CV-2011A	6/4/2026 8:34:54 AM	34.4345502	-118.6431863	Valve Comment:Lorenz pump disconnected;Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2011A	6/8/2026 2:38:46 PM	34.4345161	-118.6431961	Valve Adjustment:High Temp
CV-2011A	6/17/2026 2:55:43 PM	34.4345440	-118.6431587	Valve Adjustment:High Temp
CV-2011A	6/29/2026 1:24:17 PM	34.4345537	-118.6431650	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Comment:pump active;Well Condition:Lorentz Pump Installed;Well Repairs:Flex Hose
CV-2011A	6/29/2026 1:35:03 PM	34.4345405	-118.6431583	Valve Adjustment:Orifice Plate Changed (See OP Log),High Temp;Well Condition:Lorentz Pump Installed
CV-2011A	6/29/2026 1:37:30 PM	34.4345478	-118.6431615	Valve Adjustment:High Temp
CV-2011A	6/29/2026 3:02:00 PM	34.4345682	-118.6431624	Valve Adjustment:High Temp,Increased Flow/Vacuum
CV-2011A	6/29/2026 3:04:06 PM	34.4345678	-118.6431625	Valve Adjustment:High Temp

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-2012	6/15/2026 11:50:00 AM	34.4350172	-118.6433010	Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Decreased Flow/Vacuum
CV-2012	6/15/2026 11:51:03 AM	34.4350417	-118.6433293	
CV-2012	6/18/2026 1:09:41 PM			
CV-2201-PLF	6/2/2026 7:48:50 AM	34.4355522	-118.6488568	Valve Adjustment:Barely Open,Surging Liquid in Header
CV-2201-PLF	6/17/2026 8:46:18 AM	34.4355643	-118.6488510	Valve Adjustment:Barely Open,Reduce Sys. Vac. - Flare Down
CV-2204-PLF	6/1/2026 1:17:53 PM	34.4357699	-118.6474661	Valve Adjustment:No Flow Measurement,High Temp
CV-2204-PLF	6/1/2026 1:25:00 PM			AtmAA; [User entered 13.59%]
CV-2204-PLF	6/1/2026 1:25:00 PM			AtmAA
CV-2204-PLF	6/8/2026 1:18:27 PM	34.4357659	-118.6474778	Valve Adjustment:High Temp,Valve 100% Open
CV-2204-PLF	6/15/2026 9:45:45 AM	34.4357679	-118.6474702	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2204-PLF	6/22/2026 10:24:57 AM	34.4357702	-118.6474803	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2204-PLF	6/30/2026 8:26:20 AM	34.4357805	-118.6474742	Valve Adjustment:No Flow Measurement,High Temp
CV-2205	6/2/2026 1:19:30 PM	34.4342378	-118.6440963	Valve Adjustment:Decreased Flow/Vacuum
CV-2205	6/26/2026 10:37:39 AM			
CV-2207	6/8/2026 11:43:16 AM	34.4359782	-118.6442932	
CV-2208A	6/8/2026 10:08:38 AM	34.4365707	-118.6449623	Valve Adjustment:Surging Liquid in Header
CV-2301	6/2/2026 2:24:23 PM	34.4334813	-118.6492226	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	6/2/2026 2:25:00 PM			AtmAA; [User entered 10.78%]
CV-2301	6/2/2026 2:25:00 PM			AtmAA
CV-2301	6/3/2026 7:00:00 AM			Air Tech Lab; [User entered 11%]
CV-2301	6/3/2026 7:00:00 AM			AirTech Lab
CV-2301	6/9/2026 1:50:33 PM	34.4334549	-118.6492024	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	6/12/2026 9:50:08 AM			
CV-2301	6/16/2026 1:36:56 PM	34.4335103	-118.6492402	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2301	6/16/2026 1:39:12 PM	34.4335104	-118.6492486	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	6/23/2026 2:37:21 PM	34.4334892	-118.6492275	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-2301	6/23/2026 2:39:33 PM	34.4334934	-118.6492324	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	6/23/2026 3:00:42 PM	34.4334909	-118.6492370	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	6/24/2026 1:34:16 PM	34.4334968	-118.6492222	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-2301	6/24/2026 1:35:48 PM	34.4335165	-118.6492477	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2301	6/30/2026 10:24:56 AM	34.4334944	-118.6492370	Valve Adjustment:No Flow Measurement,High Temp,High O2,Decreased Flow/Vacuum
CV-2301	6/30/2026 10:28:52 AM	34.4334944	-118.6492369	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-2301	6/30/2026 10:30:41 AM	34.4334946	-118.6492366	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-2302	6/3/2026 7:10:00 AM			Air Tech Lab; [User entered 4.2%]
CV-2302	6/3/2026 7:10:00 AM			AirTech Lab
CV-2302	6/3/2026 9:51:38 AM	34.4340118	-118.6491845	Valve Adjustment:Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2302	6/16/2026 9:54:51 AM	34.4340530	-118.6492060	Valve Adjustment:Decreased Flow/Vacuum
CV-2302	6/25/2026 1:56:10 PM			
CV-2303	6/2/2026 10:35:06 AM	34.4353655	-118.6497137	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2303	6/2/2026 10:40:00 AM			AtmAA; [User entered 17.44%]
CV-2303	6/2/2026 10:40:00 AM			AtmAA
CV-2303	6/3/2026 7:15:00 AM			AirTech Lab
CV-2303	6/3/2026 7:15:00 AM			Air Tech Lab; [User entered 19%]
CV-2303	6/5/2026 9:12:02 AM			
CV-2303	6/9/2026 9:49:45 AM	34.4353918	-118.6496832	Valve Comment:Lorentz pump running;Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2303	6/9/2026 9:50:35 AM	34.4353868	-118.6496812	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2303	6/16/2026 9:48:16 AM	34.4353803	-118.6496976	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open
CV-2303	6/16/2026 9:50:23 AM	34.4353804	-118.6496981	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open
CV-2303	6/23/2026 10:25:28 AM	34.4353745	-118.6496999	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Valve 100% Open
CV-2303	6/29/2026 9:39:04 AM	34.4354037	-118.6496778	Valve Adjustment:High Temp,Valve 100% Open
CV-2304	6/2/2026 2:13:16 PM	34.4345607	-118.6487378	Valve Adjustment:No Flow Measurement,High Temp
CV-2304	6/2/2026 2:15:00 PM			AtmAA; [User entered 18.39%]
CV-2304	6/2/2026 2:15:00 PM			AtmAA
CV-2304	6/9/2026 1:09:40 PM	34.4345739	-118.6487381	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-2304	6/16/2026 1:08:11 PM	34.4345669	-118.6487422	Valve Adjustment:No Flow Measurement,High Temp
CV-2304	6/16/2026 2:57:49 PM	34.4345798	-118.6487617	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp,Barely Open
CV-2304	6/16/2026 2:58:50 PM	34.4345697	-118.6487578	Valve Adjustment:High Temp
CV-2304	6/23/2026 2:09:03 PM	34.4345642	-118.6487562	Valve Adjustment:No Flow Measurement,High Temp
CV-2304	6/29/2026 12:19:53 PM	34.4345337	-118.6487512	Valve Adjustment:High Temp
CV-2305	6/2/2026 2:54:55 PM	34.4352430	-118.6464830	Valve Adjustment:NSPS/EG CAC;Well Comment:pump active;Well Condition:Lorentz Pump Installed
CV-2305	6/2/2026 3:00:00 PM			AtmAA; [User entered 6.07%]
CV-2305	6/2/2026 3:00:00 PM			AtmAA
CV-2305	6/11/2026 9:25:45 AM	34.4352019	-118.6465182	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2305	6/12/2026 8:25:00 AM			Air Tech Lab; [User entered 2.8%]
CV-2305	6/12/2026 8:25:00 AM			Air Tech Lab
CV-2305	6/17/2026 1:34:44 PM	34.4352087	-118.6465458	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-2305	6/24/2026 8:18:10 AM	34.4352187	-118.6465321	Valve Adjustment:No Flow Measurement,High Temp
CV-2306	6/1/2026 10:56:19 AM	34.4360982	-118.6478259	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Well (Watered In)
CV-2306	6/1/2026 11:00:00 AM			AtmAA
CV-2306	6/1/2026 11:00:00 AM			AtmAA; [User entered 16.33%]
CV-2306	6/8/2026 10:21:46 AM	34.4360804	-118.6478269	Valve Adjustment:No Flow Measurement
CV-2306	6/22/2026 10:15:40 AM	34.4360906	-118.6478296	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2306	6/30/2026 8:15:59 AM	34.4360945	-118.6478307	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2306	6/30/2026 8:18:07 AM	34.4360932	-118.6478337	Valve Adjustment:No Flow Measurement,High Temp
CV-2308-PLF	6/2/2026 7:55:47 AM	34.4358747	-118.6489098	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In)
CV-2308-PLF	6/2/2026 7:57:50 AM	34.4358537	-118.6489235	
CV-2308-PLF	6/17/2026 8:50:24 AM	34.4358965	-118.6489193	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open,Surging Liquid in Well (Watered In);Well Comment:No pump
CV-2308-PLF	6/17/2026 8:51:38 AM	34.4358957	-118.6489072	

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-2310-PLF	6/2/2026 1:53:08 PM	34.4353235	-118.6491384	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2310-PLF	6/2/2026 2:00:00 PM			AtmAA; [User entered 16.29%]
CV-2310-PLF	6/2/2026 2:00:00 PM			AtmAA
CV-2310-PLF	6/9/2026 10:24:42 AM	34.4353212	-118.6491391	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2310-PLF	6/16/2026 10:11:01 AM	34.4353398	-118.6491419	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2310-PLF	6/23/2026 10:49:46 AM	34.4353279	-118.6491223	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2310-PLF	6/29/2026 10:01:07 AM	34.4353292	-118.6491532	Valve Adjustment:High Temp,Valve 100% Open
CV-2311	6/2/2026 9:00:00 AM			AtmAA
CV-2311	6/2/2026 9:18:43 AM	34.4363217	-118.6498938	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2311	6/2/2026 9:20:00 AM			AtmAA; [User entered 9.47%]
CV-2311	6/9/2026 9:07:08 AM	34.4363188	-118.6499137	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2311	6/16/2026 9:00:16 AM	34.4363067	-118.6498878	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2311	6/23/2026 9:40:13 AM	34.4363044	-118.6498916	Valve Adjustment:No Flow Measurement,High Temp
CV-2311	6/30/2026 9:24:01 AM	34.4363082	-118.6498708	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2311	6/30/2026 9:25:40 AM	34.4363054	-118.6498711	Valve Adjustment:No Flow Measurement,High Temp
CV-2312	6/2/2026 2:45:00 PM			AtmAA; [User entered 12.17%]
CV-2312	6/2/2026 2:45:00 PM			AtmAA
CV-2312	6/2/2026 2:47:24 PM	34.4342214	-118.6473521	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In)
CV-2312	6/10/2026 2:01:28 PM	34.4342424	-118.6473767	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2312	6/11/2026 7:30:00 AM			Air Tech Lab; [User entered 15%]
CV-2312	6/11/2026 7:30:00 AM			Air Tech Lab
CV-2312	6/24/2026 10:00:40 AM	34.4342126	-118.6473627	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2312	6/30/2026 1:42:08 PM	34.4342456	-118.6473539	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2312	6/30/2026 1:48:19 PM	34.4342484	-118.6473508	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-2312	6/30/2026 1:49:32 PM	34.4342450	-118.6473490	Valve Adjustment:No Flow Measurement,High Temp
CV-2314	6/3/2026 1:41:34 PM	34.4346962	-118.6467064	Valve Adjustment:High Temp
CV-2314	6/3/2026 1:55:00 PM			AtmAA; [User entered 11.08%]
CV-2314	6/10/2026 2:47:57 PM	34.4346963	-118.6467144	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2314	6/10/2026 2:50:12 PM	34.4346929	-118.6467160	Valve Adjustment:High Temp
CV-2314	6/12/2026 8:30:00 AM			Air Tech Lab
CV-2314	6/12/2026 8:30:00 AM			Air Tech Lab; [User entered 7.4%]
CV-2314	6/17/2026 2:43:32 PM	34.4346536	-118.6467484	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-2314	6/17/2026 2:44:23 PM	34.4346539	-118.6467478	Valve Adjustment:High Temp
CV-2314	6/19/2026 11:52:39 AM	34.4348445	-118.6468047	High Temp
CV-2314	6/19/2026 11:54:02 AM	34.4347295	-118.6467332	
CV-2314	6/24/2026 9:02:40 AM	34.4346978	-118.6467227	Valve Adjustment:No Flow Measurement,High Temp
CV-2314	6/30/2026 2:06:51 PM	34.4347105	-118.6467209	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2314	6/30/2026 2:08:30 PM	34.4347112	-118.6467196	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-2315	6/1/2026 1:23:23 PM	34.4355063	-118.6471956	Valve Comment:Lorentz pump disconnected;Valve Adjustment:No Flow Measurement,High Temp
CV-2315	6/1/2026 1:30:00 PM			AtmAA
CV-2315	6/1/2026 1:30:00 PM			AtmAA; [User entered 9.24%]
CV-2315	6/3/2026 7:25:00 AM			Air Tech Lab; [User entered 12%]
CV-2315	6/3/2026 7:25:00 AM			AirTech Lab
CV-2315	6/8/2026 1:23:19 PM	34.4355094	-118.6472078	Valve Adjustment:No Flow Measurement,High Temp
CV-2315	6/15/2026 9:49:34 AM	34.4354982	-118.6472094	Valve Comment:Pump disconnected;Valve Adjustment:No Flow Measurement,High Temp
CV-2315	6/22/2026 1:34:17 PM	34.4355285	-118.6471785	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Header
CV-2315	6/25/2026 2:43:59 PM			
CV-2315	6/30/2026 2:44:21 PM	34.4355189	-118.6472097	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2316	6/4/2026 10:21:45 AM	34.4360360	-118.6463610	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open
CV-2316	6/4/2026 11:20:47 AM			
CV-2316	6/4/2026 12:46:18 PM			
CV-2316	6/17/2026 8:51:12 AM			
CV-2316	6/23/2026 9:53:03 AM	34.4359872	-118.6463565	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-2316	6/23/2026 9:54:14 AM	34.4360057	-118.6463780	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-2316	6/23/2026 3:11:49 PM	34.4360257	-118.6463761	Valve Comment:Lorentz pump installed;Valve Adjustment:High Temp,Increased Flow/Vacuum
CV-2316	6/23/2026 3:12:16 PM	34.4360242	-118.6463872	Valve Adjustment:High Temp
CV-2319	6/12/2026 1:24:57 PM	34.4352988	-118.6457972	Valve Adjustment:NSPS/EG CAI,Orifice Plate Changed (See OP Log),High Temp,Decreased Flow/Vacuum
CV-2319	6/12/2026 1:27:27 PM	34.4352965	-118.6458012	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2319	6/15/2026 1:14:28 PM	34.4353137	-118.6458095	Valve Comment:Pump on;Valve Adjustment:Audible Flow,High Temp;Well Condition:Lorentz Pump Installed
CV-2319	6/15/2026 1:16:00 PM	34.4353159	-118.6458124	Valve Adjustment:Audible Flow
CV-2319	6/21/2026 2:21:21 PM	34.4353052	-118.6457973	
CV-2321	6/3/2026 9:02:48 AM	34.4346123	-118.6453467	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-2321	6/3/2026 9:04:13 AM	34.4346045	-118.6453583	
CV-2321	6/22/2026 8:15:36 AM	34.4346560	-118.6453542	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2321	6/22/2026 8:17:15 AM	34.4346462	-118.6453735	
CV-2322	6/4/2026 8:16:40 AM	34.4352867	-118.6475305	Valve Adjustment:Valve 100% Open
CV-2322	6/29/2026 10:13:50 AM	34.4352818	-118.6475067	Valve Adjustment:NSPS/EG CAI,High O2,Valve 100% Open,Decreased Flow/Vacuum;Well Comment:No pump;Well Repairs:Sample Port
CV-2322	6/29/2026 10:17:01 AM	34.4352648	-118.6475135	Valve Adjustment:High O2
CV-2324	6/2/2026 12:01:10 PM	34.4344770	-118.6442302	Valve Adjustment:Audible Flow,Barely Open
CV-2326	6/4/2026 12:14:04 PM	34.4361617	-118.6504877	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header
CV-2326	6/4/2026 12:15:55 PM	34.4361535	-118.6505013	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header
CV-2326	6/11/2026 10:04:53 AM	34.4361252	-118.6504642	Valve Adjustment:No Flow Measurement,High Temp
CV-2326	6/16/2026 9:13:00 AM	34.4361422	-118.6504705	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2326	6/23/2026 10:15:57 AM	34.4361378	-118.6504825	Valve Comment:Cant adjust well bad valve placement;Valve Adjustment:No Flow Measurement,High Temp
CV-2326	6/30/2026 9:30:30 AM	34.4361402	-118.6504587	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2327	6/3/2026 1:18:30 PM	34.4348876	-118.6479353	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-2327	6/3/2026 1:20:00 PM			AtmAA; [User entered 11.98%]
CV-2327	6/9/2026 2:30:10 PM	34.4349146	-118.6479253	Valve Adjustment:No Flow Measurement,High Temp
CV-2327	6/16/2026 2:36:43 PM	34.4349074	-118.6479301	Valve Adjustment:No Flow Measurement,High Temp
CV-2327	6/24/2026 9:35:33 AM	34.4348990	-118.6479393	Valve Adjustment:No Flow Measurement,High Temp
CV-2327	6/29/2026 1:11:01 PM	34.4348943	-118.6479412	Valve Adjustment:High Temp
CV-2328	6/2/2026 2:33:14 PM	34.4343148	-118.6483493	Valve Comment:Lorentz pump on while taking reading;Valve Adjustment:No Flow Measurement,High Temp
CV-2328	6/2/2026 2:35:00 PM			AtmAA
CV-2328	6/2/2026 2:35:00 PM			AtmAA; [User entered 7.5%]
CV-2328	6/9/2026 2:20:39 PM	34.4343307	-118.6483277	Valve Comment:Pump on;Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2328	6/12/2026 8:45:00 AM			Air Tech Lab
CV-2328	6/12/2026 8:45:00 AM			Air Tech Lab; [User entered 2.2%]
CV-2328	6/16/2026 2:19:24 PM	34.4343505	-118.6483578	Valve Comment:Pump running;Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2328	6/24/2026 9:52:31 AM	34.4343195	-118.6483430	Valve Adjustment:No Flow Measurement,High Temp
CV-2328	6/30/2026 1:37:04 PM	34.4343034	-118.6483421	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-2328	6/30/2026 1:38:00 PM	34.4343262	-118.6483390	Valve Adjustment:High Temp
CV-2333	6/1/2026 9:34:06 AM	34.4365142	-118.6473617	Valve Adjustment:No Flow Measurement,High Temp
CV-2333	6/1/2026 9:45:00 AM			AtmAA; [User entered 18.19%]
CV-2333	6/1/2026 9:45:00 AM			AtmAA
CV-2333	6/3/2026 8:00:00 AM			Air Tech Lab; [User entered 20%]
CV-2333	6/3/2026 8:00:00 AM			AirTech Lab
CV-2333	6/8/2026 9:19:09 AM	34.4365313	-118.6473675	Valve Adjustment:No Flow Measurement,High Temp
CV-2333	6/15/2026 8:45:46 AM	34.4365187	-118.6473836	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.
CV-2333	6/15/2026 8:46:36 AM	34.4365193	-118.6473844	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open
CV-2333	6/16/2026 8:27:48 AM	34.4365031	-118.6473813	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2333	6/16/2026 8:29:05 AM	34.4365031	-118.6473809	Valve Adjustment:No Flow Measurement,High Temp
CV-2333	6/22/2026 8:54:06 AM	34.4365313	-118.6473611	Valve Comment:Well head raised;Valve Adjustment:No Flow Measurement,High Temp
CV-2333	6/24/2026 10:41:33 AM			
CV-2333	6/29/2026 9:12:38 AM	34.4365231	-118.6473656	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-2334	6/2/2026 8:24:06 AM			
CV-2334	6/3/2026 8:05:00 AM			AirTech Lab
CV-2334	6/3/2026 8:05:00 AM			Air Tech Lab; [User entered 3.0%]
CV-2334	6/4/2026 2:15:28 PM	34.4366833	-118.6467055	
CV-2334	6/11/2026 9:30:32 AM			
CV-2334	6/17/2026 1:21:10 PM	34.4366727	-118.6466930	Valve Adjustment:NSPS/EG CAI,High Temp,Reduce Sys. Vac. - Flare Down;Well Comment:pump is active;Well Condition:Pnumatic Pump Installed
CV-2334	6/17/2026 1:22:09 PM	34.4366828	-118.6466727	Valve Adjustment:High Temp,Reduce Sys. Vac. - Flare Down;Well Comment:pump is active;Well Condition:Pnumatic Pump Installed
CV-2334	6/18/2026 3:46:54 PM			
CV-2334	6/18/2026 3:47:04 PM			
CV-2334	6/19/2026 10:47:23 AM			
CV-2334	6/19/2026 12:10:06 PM	34.4366328	-118.6467202	
CV-2334	6/23/2026 12:31:40 PM			
CV-2334	6/26/2026 11:23:08 AM			
CV-2334	6/26/2026 11:23:21 AM			
CV-2334	6/30/2026 11:19:30 AM			
CV-2334	6/30/2026 11:19:42 AM			
CV-2335	6/1/2026 2:02:30 PM	34.4363812	-118.6509693	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2335	6/17/2026 9:29:31 AM	34.4363578	-118.6509685	Valve Adjustment:Barely Open,Surging Liquid in Header
CV-2335	6/24/2026 7:34:08 AM			
CV-2336	6/1/2026 2:07:58 PM	34.4359830	-118.6508800	Valve Adjustment:Barely Open
CV-2336	6/10/2026 3:30:15 PM			
CV-2336	6/10/2026 3:30:26 PM			
CV-2336	6/11/2026 1:32:50 PM	34.4360117	-118.6509060	Valve Adjustment:Decreased Flow/Vacuum
CV-2336	6/11/2026 1:33:49 PM	34.4360290	-118.6508962	
CV-2336	6/11/2026 2:58:42 PM			
CV-2336	6/11/2026 3:00:37 PM			
CV-2336	6/17/2026 9:40:23 AM	34.4359895	-118.6508955	Valve Adjustment:Barely Open,Surging Liquid in Well (Watered In)
CV-2336	6/18/2026 1:52:32 PM			
CV-2336	6/18/2026 1:52:47 PM			
CV-2336	6/18/2026 1:53:26 PM			
CV-2336	6/24/2026 6:58:14 AM			
CV-2336	6/24/2026 1:36:33 PM			
CV-2336	6/24/2026 1:36:43 PM			
CV-2336	6/26/2026 2:08:07 PM			

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-2336	6/26/2026 2:08:18 PM			
CV-2337	6/1/2026 2:16:10 PM	34.4354705	-118.6507777	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-2337	6/3/2026 9:16:44 AM	34.4354690	-118.6507191	Valve Adjustment:High Temp
CV-2337	6/3/2026 9:25:00 AM			AtmAA; [User entered 9.29%]
CV-2337	6/10/2026 9:39:16 AM	34.4354593	-118.6507546	Valve Adjustment:No Flow Measurement,High Temp
CV-2337	6/16/2026 9:15:00 AM			Air Tech Lab; [User entered 12%]
CV-2337	6/16/2026 9:15:00 AM			Air Tech Lab
CV-2337	6/17/2026 8:43:10 AM	34.4354737	-118.6507678	Valve Adjustment:No Flow Measurement,High Temp
CV-2337	6/24/2026 1:53:56 PM	34.4354603	-118.6507594	Valve Comment:Pump on;Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2338	6/3/2026 9:09:28 AM	34.4348425	-118.6504637	Valve Comment:Lorenz pump pumping while taking reading;Valve Adjustment:No Flow Measurement,High Temp
CV-2338	6/3/2026 9:15:00 AM			AtmAA; [User entered 18.2%]
CV-2338	6/10/2026 9:25:38 AM	34.4348668	-118.6504960	Valve Comment:Install sample port on system side;Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2338	6/17/2026 8:52:13 AM	34.4348641	-118.6504927	Valve Adjustment:No Flow Measurement,High Temp
CV-2338	6/24/2026 1:31:30 PM	34.4348470	-118.6504823	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-2338	6/24/2026 1:32:33 PM	34.4348499	-118.6504731	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Header
CV-2339	6/11/2026 9:42:14 AM	34.4342158	-118.6502660	NSPS/EG CAI,High O2,
CV-2339	6/11/2026 9:45:19 AM	34.4342033	-118.6502535	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,NSPS/EG CAI,High O2
CV-2339	6/12/2026 8:58:58 AM	34.4341698	-118.6502953	NSPS/EG CAI,High O2,
CV-2339	6/12/2026 9:04:45 AM	34.4341300	-118.6502578	NSPS/EG CAI,High O2,
CV-2339	6/12/2026 9:10:50 AM	34.4342253	-118.6502107	High O2,NSPS/EG CAI,No Flow Measurement
CV-2339	6/18/2026 1:42:24 PM			
CV-2339	6/18/2026 1:42:35 PM			
CV-2339	6/19/2026 1:58:28 PM	34.4341808	-118.6503920	
CV-2339	6/19/2026 2:03:58 PM	34.4342948	-118.6503165	
CV-2339	6/22/2026 2:45:17 PM	34.4342071	-118.6502717	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2339	6/22/2026 2:47:20 PM	34.4342044	-118.6502779	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-2339	6/23/2026 12:28:36 PM			

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-2339	6/24/2026 1:48:55 PM			
CV-2339	6/24/2026 1:49:06 PM			
CV-2339	6/26/2026 3:51:11 PM			
CV-2339	6/26/2026 3:51:22 PM			
CV-2341	6/6/2026 1:00:12 PM			
CV-2341	6/11/2026 9:35:24 AM	34.4336597	-118.6502768	
CV-2341	6/11/2026 3:32:00 PM	34.4336890	-118.6501883	
CV-2341	6/15/2026 10:15:00 AM			Air Tech Lab
CV-2341	6/15/2026 10:15:00 AM			Air Tech Lab; [User entered 15%]
CV-2341	6/22/2026 11:40:09 AM	34.4336168	-118.6501682	Valve Adjustment:Decreased Flow/Vacuum
CV-2341	6/24/2026 1:54:00 PM			
CV-2341	6/24/2026 1:54:47 PM			
CV-2341	6/25/2026 1:45:13 PM	34.4336123	-118.6501760	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed
CV-2341	6/26/2026 3:49:24 PM			
CV-2341	6/26/2026 3:49:37 PM			
CV-2342A-P	6/3/2026 12:53:12 PM	34.4342280	-118.6508713	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open;Well Condition:Fair;Well Repairs:Valve
CV-2342A-P	6/3/2026 1:00:00 PM			AtmAA; [User entered 20.38%]
CV-2342A-P	6/10/2026 10:44:45 AM	34.4342045	-118.6508399	Valve Adjustment:No Flow Measurement,High Temp
CV-2342A-P	6/17/2026 9:53:50 AM	34.4342117	-118.6508387	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2342A-P	6/17/2026 9:54:24 AM	34.4342165	-118.6508475	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2343	6/15/2026 9:19:39 AM	34.4332507	-118.6506840	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2343	6/15/2026 9:20:00 AM	34.4332408	-118.6506890	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2343	6/17/2026 2:09:17 PM	34.4332378	-118.6506757	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-2343	6/17/2026 2:11:09 PM	34.4332357	-118.6506936	Valve Comment:Lorentz pump repaired today;Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-2343	6/19/2026 11:11:56 AM	34.4332958	-118.6507028	High Temp
CV-2343	6/19/2026 11:16:28 AM	34.4333268	-118.6507517	
CV-2344	6/2/2026 8:00:00 AM			AirTech Lab; [User entered 16%]
CV-2344	6/2/2026 8:00:00 AM			AirTech Lab
CV-2344	6/2/2026 8:40:05 AM	34.4329882	-118.6504447	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-2344	6/2/2026 8:41:11 AM	34.4329910	-118.6504377	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2344	6/10/2026 10:48:47 AM	34.4329595	-118.6504565	High Temp,NSPS/EG CAI,

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-2344	6/10/2026 10:51:49 AM	34.4329653	-118.6504173	NSPS/EG CAI,High Temp,
CV-2344	6/11/2026 10:41:23 AM	34.4329840	-118.6504826	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-2344	6/11/2026 10:42:42 AM	34.4329834	-118.6504812	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-2344	6/17/2026 9:22:23 AM	34.4329767	-118.6504440	Valve Adjustment:No Flow Measurement,High Temp
CV-2345	6/2/2026 7:55:00 AM			AirTech Lab
CV-2345	6/2/2026 7:55:00 AM			AirTech Lab; [User entered 3.3%]
CV-2345	6/2/2026 8:44:21 AM	34.4327437	-118.6501822	Valve Adjustment:Audible Flow
CV-2345	6/16/2026 8:05:13 AM	34.4327325	-118.6501682	Well Comment:Unable to adjust safely
CV-2346	6/2/2026 7:50:00 AM			AirTech Lab; [User entered 16%]
CV-2346	6/2/2026 7:50:00 AM			AirTech Lab
CV-2346	6/3/2026 9:35:01 AM	34.4326088	-118.6500918	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2346	6/3/2026 9:39:13 AM	34.4325928	-118.6500843	Valve Comment:Lorenz pump disconnected;Valve Adjustment:No Flow Measurement,High Temp
CV-2346	6/3/2026 9:40:00 AM			AtmAA; [User entered 14.76%]
CV-2346	6/10/2026 9:54:27 AM	34.4325997	-118.6500577	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2346	6/17/2026 9:17:36 AM	34.4326007	-118.6500843	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2346	6/17/2026 9:19:04 AM	34.4325895	-118.6500658	Valve Adjustment:No Flow Measurement,High Temp
CV-2347	6/2/2026 7:40:00 AM			AirTech Lab
CV-2347	6/2/2026 7:40:00 AM			AirTech Lab; [User entered 5.5%]
CV-2347	6/2/2026 9:01:41 AM	34.4323507	-118.6498297	
CV-2347	6/16/2026 8:17:59 AM	34.4323628	-118.6498315	
CV-2348	6/2/2026 7:30:00 AM			AirTech Lab; [User entered 0.90%]
CV-2348	6/2/2026 7:30:00 AM			AirTech Lab
CV-2348	6/2/2026 9:24:08 AM	34.4321620	-118.6496185	
CV-2348	6/10/2026 1:32:39 PM	34.4322467	-118.6495160	
CV-2348	6/10/2026 1:34:08 PM	34.4319753	-118.6496522	
CV-2348	6/16/2026 8:24:15 AM	34.4321570	-118.6496285	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-2348	6/16/2026 8:24:47 AM	34.4321523	-118.6496235	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header
CV-2349	6/2/2026 8:30:00 AM			AirTech Lab
CV-2349	6/2/2026 8:30:00 AM			AirTech Lab; [User entered 15%]
CV-2349	6/3/2026 10:34:57 AM	34.4331362	-118.6512616	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-2349	6/3/2026 10:35:45 AM	34.4331206	-118.6512639	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header;Well Condition:Lorentz Pump Installed;Well Repairs:Surging
CV-2349	6/3/2026 10:40:00 AM			AtmAA; [User entered 12.995%]
CV-2349	6/10/2026 1:32:14 PM	34.4331480	-118.6512492	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2349	6/10/2026 1:33:11 PM	34.4331489	-118.6512479	Valve Adjustment:No Flow Measurement,High Temp
CV-2349	6/17/2026 10:35:04 AM	34.4331427	-118.6512651	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-2349	6/17/2026 10:35:26 AM	34.4331433	-118.6512552	Valve Adjustment:No Flow Measurement,High Temp
CV-2350	6/2/2026 8:15:00 AM			AirTech Lab; [User entered 17%]
CV-2350	6/2/2026 8:15:00 AM			AirTech Lab
CV-2350	6/2/2026 8:32:01 AM	34.4327560	-118.6509093	Valve Adjustment:Decreased Flow/Vacuum
CV-2350	6/17/2026 8:33:21 AM	34.4327745	-118.6509127	Valve Adjustment:Decreased Flow/Vacuum
CV-2351	6/1/2026 9:00:00 AM			AirTech Lab
CV-2351	6/1/2026 9:00:00 AM			AirTech Lab; [User entered 0.17%]
CV-2351	6/1/2026 12:22:24 PM	34.4351375	-118.6511430	Valve Adjustment:NSPS/EG CAI,Surging Liquid in Well (Watered In);Well Comment:Pump is not pumping
CV-2351	6/1/2026 12:24:29 PM	34.4351385	-118.6511455	
CV-2351	6/2/2026 7:47:05 AM			
CV-2351	6/3/2026 7:58:36 AM			
CV-2351	6/4/2026 3:09:45 PM			
CV-2351	6/5/2026 10:57:36 AM			
CV-2351	6/6/2026 8:19:20 AM			
CV-2351	6/9/2026 3:12:34 PM			
CV-2351	6/9/2026 3:12:48 PM			
CV-2351	6/16/2026 8:45:00 AM			Air Tech Lab; [User entered 0.41%]
CV-2351	6/16/2026 8:45:00 AM			Air Tech Lab
CV-2351	6/17/2026 9:15:56 AM	34.4351398	-118.6511742	Valve Adjustment:NSPS/EG CAI,High O2
CV-2351	6/17/2026 9:16:22 AM	34.4351382	-118.6511728	Valve Adjustment:NSPS/EG CAI,High O2
CV-2351	6/18/2026 2:20:44 PM			
CV-2351	6/18/2026 2:20:55 PM			
CV-2351	6/19/2026 12:43:31 PM			
CV-2351	6/26/2026 3:52:05 PM			
CV-2351	6/26/2026 3:52:20 PM			
CV-2351	6/30/2026 2:51:00 PM			
CV-2351	6/30/2026 2:52:10 PM			
CV-2352	6/1/2026 9:10:00 AM			AirTech Lab

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-2352	6/1/2026 9:10:00 AM			AirTech Lab; [User entered 10%]
CV-2352	6/1/2026 12:43:45 PM	34.4348653	-118.6510463	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-2352	6/1/2026 12:44:54 PM	34.4348667	-118.6510580	
CV-2352	6/2/2026 7:48:09 AM			
CV-2352	6/3/2026 7:57:58 AM			
CV-2352	6/4/2026 3:08:51 PM			
CV-2352	6/5/2026 10:58:49 AM			
CV-2352	6/6/2026 8:19:50 AM			
CV-2352	6/9/2026 3:03:03 PM			
CV-2352	6/9/2026 3:03:33 PM			
CV-2352	6/17/2026 9:28:04 AM	34.4348530	-118.6510517	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum
CV-2352	6/18/2026 2:15:09 PM			
CV-2352	6/18/2026 2:15:24 PM			
CV-2352	6/26/2026 3:52:52 PM			
CV-2352	6/26/2026 3:53:01 PM			
CV-2352	6/30/2026 2:51:05 PM			
CV-2352	6/30/2026 2:51:18 PM			
CV-2353-PLF	6/11/2026 10:42:44 AM	34.4345632	-118.6509253	NSPS/EG CAI,High Temp,
CV-2353-PLF	6/11/2026 10:46:22 AM	34.4345323	-118.6509255	NSPS/EG CAI,High Temp,
CV-2353-PLF	6/12/2026 10:14:03 AM	34.4345627	-118.6508595	NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-2353-PLF	6/12/2026 10:16:08 AM	34.4345773	-118.6508267	NSPS/EG CAI,High Temp,
CV-2353-PLF	6/12/2026 10:38:13 AM			
CV-2353-PLF	6/15/2026 8:25:00 AM			Air Tech Lab
CV-2353-PLF	6/15/2026 8:25:00 AM			Air Tech Lab; [User entered 20%]
CV-2353-PLF	6/15/2026 2:58:08 PM	34.4345339	-118.6509306	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,Decreased Flow/Vacuum
CV-2353-PLF	6/15/2026 2:59:49 PM	34.4345319	-118.6509287	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-2353-PLF	6/17/2026 9:38:30 AM	34.4345232	-118.6509138	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-2353-PLF	6/17/2026 9:38:59 AM	34.4345212	-118.6509185	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2354	6/3/2026 10:45:40 AM	34.4336751	-118.6513689	Valve Comment:Lorentz pump on;Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Increased Flow/Vacuum,Valve 100% Open;Well Condition:Lorentz Pump Installed;Well Repairs:Valve

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-2354	6/3/2026 10:47:46 AM	34.4336747	-118.6513641	Valve Comment:Bad valve in well;Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open;Well Condition:Lorentz Pump Installed;Well Repairs:Valve
CV-2354	6/3/2026 10:50:00 AM			AtmAA; [User entered 14.34%]
CV-2354	6/8/2026 1:27:32 PM	34.4336887	-118.6513753	Valve Adjustment:NSPS/EG CAI,High Temp;Well Comment:Vacuum fluctuating
CV-2354	6/8/2026 1:28:00 PM	34.4336853	-118.6513687	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2354	6/10/2026 1:14:12 PM	34.4336928	-118.6513820	Valve Adjustment:No Flow Measurement,High Temp
CV-2354	6/15/2026 8:10:00 AM			Air Tech Lab; [User entered 18%]
CV-2354	6/15/2026 8:10:00 AM			Air Tech Lab
CV-2354	6/17/2026 10:43:17 AM	34.4336783	-118.6513634	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-24001	6/1/2026 1:48:34 PM	34.4366513	-118.6509243	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24001	6/17/2026 9:25:42 AM	34.4366442	-118.6509378	Valve Adjustment:Barely Open,Surging Liquid in Header
CV-24002	6/1/2026 1:41:05 PM	34.4367267	-118.6504768	Valve Adjustment:Barely Open
CV-24002	6/17/2026 9:17:33 AM	34.4367325	-118.6504843	Valve Adjustment:Barely Open,Surging Liquid in Well (Watered In)
CV-24002	6/24/2026 8:07:06 AM			
CV-24003	6/1/2026 9:47:33 AM	34.4368775	-118.6500817	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24003	6/5/2026 9:17:13 AM	34.4368500	-118.6500632	Valve Adjustment:Orifice Plate Changed (See OP Log),High O2
CV-24003	6/17/2026 9:05:11 AM	34.4368710	-118.6500860	Valve Adjustment:Barely Open,Surging Liquid in Header
CV-24003	6/24/2026 8:19:54 AM			
CV-24004	6/1/2026 9:44:08 AM	34.4370350	-118.6497083	Valve Adjustment:Barely Open
CV-24004	6/17/2026 9:00:41 AM	34.4370378	-118.6497040	Valve Adjustment:Barely Open
CV-24004	6/24/2026 8:46:57 AM			
CV-24006	6/1/2026 2:36:17 PM	34.4363353	-118.6504468	Valve Adjustment:Decreased Flow/Vacuum
CV-24006	6/2/2026 8:32:06 AM			
CV-24006	6/11/2026 2:54:50 PM	34.4362177	-118.6503045	
CV-24006	6/17/2026 9:50:26 AM	34.4363432	-118.6504682	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24006	6/18/2026 3:15:55 PM			
CV-24006	6/18/2026 3:16:08 PM			
CV-24006	6/19/2026 11:31:36 AM			
CV-24006	6/24/2026 1:27:43 PM			

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24006	6/24/2026 1:28:01 PM			
CV-24006	6/24/2026 1:28:36 PM			
CV-24006	6/26/2026 1:33:12 PM			
CV-24006	6/26/2026 1:33:26 PM			
CV-24007	6/1/2026 2:43:27 PM	34.4365032	-118.6501288	Valve Adjustment:High Temp
CV-24007	6/2/2026 8:31:29 AM			
CV-24007	6/2/2026 9:10:01 AM	34.4365276	-118.6501233	Valve Adjustment:Decreased Flow/Vacuum
CV-24007	6/2/2026 9:14:26 AM	34.4365376	-118.6501290	Valve Adjustment:Barely Open
CV-24007	6/12/2026 8:23:32 AM			
CV-24007	6/15/2026 9:35:00 AM			Air Tech Lab
CV-24007	6/15/2026 9:35:00 AM			Air Tech Lab; [User entered 6.3%]
CV-24007	6/17/2026 9:53:11 AM	34.4365000	-118.6501355	
CV-24008	6/1/2026 9:00:00 AM			AtmAA; [User entered 19.78%]
CV-24008	6/2/2026 8:30:57 AM			
CV-24008	6/2/2026 8:58:36 AM	34.4366797	-118.6496910	Valve Adjustment:High Temp;Well Repairs:Valve
CV-24008	6/2/2026 9:00:00 AM			AtmAA
CV-24008	6/9/2026 9:03:09 AM	34.4366621	-118.6497324	Valve Comment:Cant adjust well broken valve;Valve Adjustment:High Temp;Well Condition:Poor;Well Repairs:Valve
CV-24008	6/16/2026 8:56:04 AM	34.4366708	-118.6496972	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24008	6/16/2026 8:57:09 AM	34.4366704	-118.6496970	Valve Adjustment:No Flow Measurement,High Temp
CV-24008	6/23/2026 9:36:51 AM	34.4366724	-118.6496938	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-24008	6/24/2026 3:50:29 PM			
CV-24008	6/30/2026 9:05:50 AM	34.4366744	-118.6496864	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24008	6/30/2026 9:07:16 AM	34.4366745	-118.6496869	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-24009	6/1/2026 8:55:00 AM			AtmAA; [User entered 13.51%]
CV-24009	6/2/2026 8:30:31 AM			
CV-24009	6/2/2026 8:52:31 AM	34.4368720	-118.6493593	Valve Adjustment:High Temp
CV-24009	6/2/2026 8:55:00 AM			AtmAA
CV-24009	6/9/2026 8:57:30 AM	34.4368454	-118.6493665	Valve Adjustment:High Temp
CV-24009	6/16/2026 8:46:33 AM	34.4368713	-118.6493678	Valve Adjustment:High Temp
CV-24009	6/19/2026 11:27:55 AM			
CV-24009	6/23/2026 9:31:14 AM	34.4368697	-118.6493474	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-24009	6/23/2026 9:34:10 AM	34.4368765	-118.6493431	Valve Comment:Pump not operating pneumatic pump installed;Valve Adjustment:High Temp,Barely Open
CV-24009	6/25/2026 9:25:26 AM			

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24009	6/25/2026 9:26:16 AM			
CV-24009	6/26/2026 1:24:49 PM			
CV-24009	6/26/2026 1:25:02 PM			
CV-24009	6/30/2026 8:56:02 AM	34.4368731	-118.6493443	Valve Adjustment:High Temp,Increased Flow/Vacuum,Barely Open
CV-24009	6/30/2026 8:57:08 AM	34.4368707	-118.6493469	Valve Adjustment:High Temp,Barely Open
CV-24009	6/30/2026 9:31:37 AM	34.4368575	-118.6493393	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed
CV-24010	6/8/2026 2:10:41 PM	34.4371102	-118.6489845	Valve Adjustment:NSPS/EG CAC
CV-24010	6/8/2026 2:11:53 PM	34.4371047	-118.6489670	
CV-24010	6/23/2026 1:51:29 PM	34.4370972	-118.6489505	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24010	6/24/2026 9:13:10 AM			
CV-24011	6/2/2026 9:35:00 AM			AtmAA; [User entered 14.37%]
CV-24011	6/2/2026 9:35:00 AM			AtmAA
CV-24011	6/2/2026 9:37:40 AM	34.4361991	-118.6501811	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-24011	6/2/2026 9:38:42 AM	34.4361996	-118.6501837	Valve Adjustment:High Temp
CV-24011	6/4/2026 1:01:49 PM	34.4362205	-118.6502108	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum
CV-24011	6/4/2026 1:03:39 PM	34.4362217	-118.6501878	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24011	6/9/2026 9:12:23 AM	34.4361998	-118.6502131	Valve Comment:Pump disconnected;Valve Adjustment:High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24011	6/9/2026 9:13:37 AM	34.4361947	-118.6502078	Valve Adjustment:Audible Flow,High Temp
CV-24011	6/16/2026 9:07:19 AM	34.4361913	-118.6501942	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24011	6/16/2026 9:08:16 AM	34.4361913	-118.6501942	Valve Adjustment:No Flow Measurement,High Temp
CV-24011	6/23/2026 10:12:30 AM	34.4361945	-118.6501971	Valve Comment:Pump offline;Valve Adjustment:No Flow Measurement,High Temp
CV-24011	6/29/2026 9:18:00 AM	34.4362227	-118.6501652	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header
CV-24011	6/29/2026 9:18:40 AM	34.4362210	-118.6501695	
CV-24012	6/2/2026 9:28:01 AM	34.4361826	-118.6493767	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-24012	6/2/2026 9:30:00 AM			AtmAA; [User entered 16.87%]
CV-24012	6/2/2026 9:30:00 AM			AtmAA

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24012	6/9/2026 9:34:04 AM	34.4361733	-118.6493899	Valve Adjustment:No Flow Measurement,High Temp
CV-24012	6/16/2026 9:25:50 AM	34.4361649	-118.6493663	Valve Adjustment:No Flow Measurement,High Temp
CV-24012	6/23/2026 10:03:04 AM	34.4361614	-118.6493744	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24012	6/23/2026 10:04:25 AM	34.4361630	-118.6493754	Valve Adjustment:No Flow Measurement,High Temp
CV-24012	6/24/2026 1:16:51 PM			
CV-24012	6/29/2026 10:10:08 AM	34.4361668	-118.6493485	Valve Adjustment:High Temp
CV-24013	6/11/2026 9:49:00 AM	34.4366133	-118.6492508	Valve Adjustment:High O2,Barely Open
CV-24013	6/22/2026 10:46:47 AM	34.4366022	-118.6492540	Valve Adjustment:NSPS/EG CAI,High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24013	6/22/2026 10:51:54 AM	34.4365968	-118.6492473	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24014	6/2/2026 8:48:10 AM	34.4367857	-118.6489493	Valve Adjustment:No Flow Measurement,High Temp
CV-24014	6/2/2026 8:50:00 AM			AtmAA; [User entered 16.795%]
CV-24014	6/2/2026 8:50:00 AM			AtmAA
CV-24014	6/9/2026 8:53:51 AM	34.4367873	-118.6489728	Valve Adjustment:No Flow Measurement,High Temp
CV-24014	6/16/2026 8:43:10 AM	34.4367654	-118.6489355	Valve Adjustment:No Flow Measurement,High Temp
CV-24014	6/19/2026 11:50:57 AM	34.4367973	-118.6489305	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum
CV-24014	6/22/2026 9:40:26 AM	34.4367703	-118.6489532	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-24014	6/25/2026 10:35:18 AM			
CV-24014	6/29/2026 1:41:00 PM			
CV-24014	6/30/2026 8:45:06 AM	34.4367963	-118.6489461	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24014	6/30/2026 8:47:14 AM	34.4367959	-118.6489490	Valve Adjustment:No Flow Measurement,High Temp
CV-24015	6/1/2026 10:43:39 AM	34.4368837	-118.6486289	Valve Comment:LORENTZ pump turned in while taking reading;Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24015	6/1/2026 10:45:00 AM			AtmAA; [User entered 21.03%]
CV-24015	6/1/2026 10:45:00 AM			AtmAA
CV-24015	6/8/2026 9:52:47 AM	34.4368637	-118.6486234	Valve Comment:Pump on while taking reading;Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24015	6/15/2026 9:17:48 AM	34.4368808	-118.6486228	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24015	6/22/2026 9:33:15 AM	34.4368883	-118.6486108	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24015	6/22/2026 9:34:57 AM	34.4368878	-118.6486113	Valve Comment:Lorentz pump turned on;Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-24015	6/29/2026 9:56:20 AM	34.4368828	-118.6486388	Valve Adjustment:No Flow Measurement,High Temp
CV-24016	6/2/2026 9:42:45 AM	34.4359413	-118.6502519	Valve Adjustment:No Flow Measurement,High Temp
CV-24016	6/2/2026 9:45:00 AM			AtmAA
CV-24016	6/2/2026 9:45:00 AM			AtmAA; [User entered 9.4%]
CV-24016	6/9/2026 9:16:20 AM	34.4359147	-118.6502662	Valve Comment:Pump on;Valve Adjustment:Audible Flow,No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed;Well Repairs:None
CV-24016	6/16/2026 9:15:50 AM	34.4359230	-118.6502516	Valve Adjustment:No Flow Measurement,High Temp
CV-24016	6/23/2026 10:09:50 AM	34.4359053	-118.6502515	Valve Adjustment:No Flow Measurement,High Temp
CV-24016	6/29/2026 9:22:30 AM	34.4359302	-118.6502547	Valve Adjustment:High Temp
CV-24017	6/2/2026 9:23:32 AM	34.4361109	-118.6498161	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24017	6/2/2026 9:24:13 AM	34.4361117	-118.6498161	Valve Adjustment:No Flow Measurement,High Temp
CV-24017	6/2/2026 9:25:00 AM			AtmAA
CV-24017	6/2/2026 9:25:00 AM			AtmAA; [User entered 16.03%]
CV-24017	6/9/2026 9:22:05 AM	34.4361123	-118.6498237	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	6/15/2026 9:45:00 AM			Air Tech Lab
CV-24017	6/15/2026 9:45:00 AM			Air Tech Lab; [User entered 16%]
CV-24017	6/16/2026 9:21:32 AM	34.4360973	-118.6498129	Valve Comment:Upon arrival fount pump removed from well;Valve Adjustment:No Flow Measurement,High Temp
CV-24017	6/16/2026 9:23:09 AM	34.4360923	-118.6498055	Valve Adjustment:No Flow Measurement,High Temp
CV-24017	6/23/2026 9:49:36 AM	34.4361138	-118.6498234	Valve Comment:Pump removed;Valve Adjustment:No Flow Measurement,High Temp
CV-24017	6/29/2026 10:14:31 AM	34.4361213	-118.6498108	Valve Adjustment:High Temp
CV-24017	6/30/2026 8:53:30 AM			
CV-24018	6/1/2026 2:20:40 PM	34.4355852	-118.6500065	Valve Adjustment:Barely Open
CV-24018	6/22/2026 8:06:29 AM	34.4355968	-118.6500488	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24018	6/22/2026 8:07:35 AM	34.4356178	-118.6500678	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-24018	6/23/2026 4:42:31 PM			

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24018	6/25/2026 3:34:56 PM	34.4355980	-118.6500565	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24019	6/2/2026 9:48:57 AM	34.4357856	-118.6497700	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24019	6/2/2026 9:50:00 AM			AtmAA; [User entered 15.05%]
CV-24019	6/2/2026 9:50:00 AM			AtmAA
CV-24019	6/2/2026 9:50:36 AM	34.4357836	-118.6497754	Valve Adjustment:No Flow Measurement,High Temp
CV-24019	6/16/2026 9:37:35 AM	34.4357626	-118.6497652	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24019	6/16/2026 9:40:14 AM	34.4357703	-118.6497679	Valve Comment:Well head replaced;Valve Adjustment:No Flow Measurement,High Temp
CV-24019	6/23/2026 10:07:07 AM	34.4357639	-118.6497773	Valve Adjustment:No Flow Measurement,High Temp
CV-24019	6/26/2026 8:44:17 AM			
CV-24019	6/29/2026 9:28:09 AM	34.4357850	-118.6497675	Valve Adjustment:High Temp
CV-24020	6/2/2026 8:30:02 AM	34.4359927	-118.6493607	Valve Adjustment:Barely Open,Surging Liquid in Well (Watered In)
CV-24020	6/23/2026 1:30:27 PM	34.4360370	-118.6494023	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24020	6/25/2026 11:24:16 AM			
CV-24021	6/2/2026 8:09:06 AM	34.4361440	-118.6490455	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In);Well Comment:No pump
CV-24021	6/2/2026 8:10:40 AM	34.4361480	-118.6490515	Valve Adjustment:NSPS/EG CAC
CV-24021	6/2/2026 8:32:46 AM			
CV-24021	6/23/2026 1:23:38 PM	34.4361960	-118.6490412	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24021	6/23/2026 1:25:06 PM	34.4361688	-118.6490378	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24021	6/25/2026 11:24:59 AM			
CV-24022-PI	6/1/2026 1:58:30 PM	34.4365223	-118.6487878	Valve Comment:Surging in header;Valve Adjustment:No Flow Measurement,High Temp;Well Repairs:Surging
CV-24022-PI	6/1/2026 2:10:00 PM			AtmAA; [User entered 15.5%]
CV-24022-PI	6/1/2026 2:10:00 PM			AtmAA
CV-24022-PI	6/8/2026 10:03:23 AM	34.4365038	-118.6488104	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24022-PI	6/15/2026 9:24:32 AM	34.4365086	-118.6488018	Valve Adjustment:No Flow Measurement,High Temp
CV-24022-PI	6/22/2026 9:43:50 AM	34.4365035	-118.6488008	Valve Adjustment:No Flow Measurement,High Temp
CV-24022-PI	6/29/2026 10:18:07 AM	34.4365146	-118.6487884	Valve Adjustment:No Flow Measurement,High Temp
CV-24023	6/1/2026 10:49:06 AM	34.4365783	-118.6484430	Valve Adjustment:No Flow Measurement,High Temp
CV-24023	6/1/2026 10:50:00 AM			AtmAA
CV-24023	6/1/2026 10:50:00 AM			AtmAA; [User entered 20.515%]
CV-24023	6/2/2026 7:16:22 AM			
CV-24023	6/8/2026 9:57:42 AM	34.4365814	-118.6484524	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum,Valve 100% Open
CV-24023	6/8/2026 9:58:50 AM	34.4365808	-118.6484480	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Valve 100% Open
CV-24023	6/11/2026 4:02:00 PM	34.4365303	-118.6483507	
CV-24023	6/11/2026 4:03:26 PM	34.4367115	-118.6483238	
CV-24023	6/15/2026 9:20:16 AM	34.4365826	-118.6484393	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24023	6/22/2026 9:37:30 AM	34.4365853	-118.6484415	Valve Adjustment:No Flow Measurement,High Temp
CV-24023	6/29/2026 10:12:19 AM	34.4365891	-118.6484319	Valve Adjustment:No Flow Measurement,High Temp
CV-24024-PI	6/8/2026 1:57:26 PM	34.4368003	-118.6481652	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Comment:pump active;Well Condition:Lorentz Pump Installed
CV-24024-PI	6/8/2026 1:57:56 PM	34.4368090	-118.6481592	Valve Adjustment:High Temp;Well Repairs:Sample Port
CV-24024-PI	6/24/2026 10:27:50 AM	34.4368405	-118.6481675	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24024-PI	6/29/2026 9:47:30 AM	34.4368041	-118.6481724	Valve Adjustment:No Flow Measurement,High Temp
CV-24025	6/2/2026 10:41:15 AM	34.4352784	-118.6499385	Valve Adjustment:No Flow Measurement,High Temp
CV-24025	6/2/2026 10:45:00 AM			AtmAA
CV-24025	6/2/2026 10:45:00 AM			AtmAA; [User entered 15.67%]
CV-24025	6/9/2026 9:40:42 AM	34.4352779	-118.6499597	Valve Adjustment:No Flow Measurement,High Temp
CV-24025	6/11/2026 10:08:18 AM			
CV-24025	6/16/2026 10:19:07 AM	34.4352867	-118.6499403	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum,Valve 100% Open
CV-24025	6/16/2026 10:19:54 AM	34.4352824	-118.6499353	Valve Adjustment:No Flow Measurement,High Temp
CV-24025	6/23/2026 10:21:26 AM	34.4352787	-118.6499453	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24025	6/29/2026 9:34:06 AM	34.4352952	-118.6499518	Valve Adjustment:High Temp,Valve 100% Open;Well Comment:No system sample port;Well Condition:Lorentz Pump Installed
CV-24026	6/2/2026 8:38:21 AM	34.4356617	-118.6492370	Valve Adjustment:Barely Open,Surging Liquid in Header
CV-24026	6/9/2026 9:54:29 AM	34.4356646	-118.6492858	Valve Adjustment:No Flow Measurement;Well Condition:Lorentz Pump Installed
CV-24026	6/9/2026 9:56:19 AM	34.4356631	-118.6492832	Valve Adjustment:No Flow Measurement
CV-24026	6/10/2026 11:09:42 AM	34.4356862	-118.6493055	NSPS/EG CAI,High Temp,
CV-24026	6/10/2026 11:11:56 AM	34.4355963	-118.6491862	NSPS/EG CAI,High Temp,
CV-24026	6/23/2026 11:28:16 AM	34.4356680	-118.6492678	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-24026	6/23/2026 11:35:40 AM	34.4356653	-118.6492547	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum
CV-24026	6/23/2026 11:39:23 AM	34.4356593	-118.6492602	Valve Adjustment:High Temp
CV-24026	6/29/2026 10:05:21 AM	34.4356745	-118.6492725	Valve Adjustment:High Temp
CV-24027	6/2/2026 8:19:11 AM	34.4360997	-118.6487198	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In);Well Comment:No pump
CV-24027	6/2/2026 8:21:11 AM	34.4361108	-118.6487198	Valve Adjustment:NSPS/EG CAC
CV-24027	6/23/2026 11:10:25 AM	34.4361148	-118.6487223	Valve Comment:Faulty value
CV-24027	6/23/2026 2:49:58 PM			
CV-24028	6/1/2026 1:53:07 PM	34.4363527	-118.6484753	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-24028	6/1/2026 2:05:00 PM			AtmAA
CV-24028	6/1/2026 2:05:00 PM			AtmAA; [User entered 18.68%]
CV-24028	6/8/2026 10:09:22 AM	34.4363443	-118.6484737	Valve Adjustment:No Flow Measurement,High Temp
CV-24028	6/15/2026 9:29:30 AM	34.4363515	-118.6484711	Valve Adjustment:No Flow Measurement,High Temp
CV-24028	6/22/2026 9:46:03 AM	34.4363246	-118.6484669	Valve Adjustment:No Flow Measurement,High Temp
CV-24028	6/23/2026 1:24:03 PM			
CV-24028	6/29/2026 10:41:12 AM	34.4363432	-118.6484566	Valve Adjustment:No Flow Measurement,High Temp
CV-24029	6/5/2026 2:13:50 PM	34.4364645	-118.6480485	Valve Adjustment:High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24029	6/9/2026 1:11:23 PM	34.4364480	-118.6480613	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-24029	6/9/2026 1:24:01 PM	34.4364482	-118.6480477	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24029	6/17/2026 2:05:10 PM	34.4364573	-118.6480287	Valve Comment:valve closed upon arrival;Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Barely Open,Plugged/Pinched Suspected;Well Comment:no pump
CV-24029	6/17/2026 2:06:03 PM	34.4364380	-118.6480128	
CV-24029	6/19/2026 12:12:46 PM	34.4364623	-118.6480585	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-24030	6/1/2026 10:00:00 AM			AtmAA; [User entered 17.26%]
CV-24030	6/1/2026 10:00:00 AM			AtmAA
CV-24030	6/1/2026 10:01:10 AM	34.4366659	-118.6478685	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24030	6/1/2026 10:03:17 AM	34.4366651	-118.6478667	Valve Adjustment:No Flow Measurement,High Temp
CV-24030	6/8/2026 9:33:25 AM	34.4366397	-118.6478812	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24030	6/8/2026 9:38:38 AM	34.4366450	-118.6478888	Valve Adjustment:No Flow Measurement,High Temp
CV-24030	6/15/2026 8:58:22 AM	34.4366576	-118.6478850	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24030	6/15/2026 9:05:40 AM	34.4366453	-118.6478827	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-24030	6/22/2026 9:04:13 AM	34.4366599	-118.6478687	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum,Barely Open
CV-24030	6/22/2026 9:06:13 AM	34.4366745	-118.6478881	Valve Adjustment:High Temp,Barely Open
CV-24030	6/22/2026 9:10:22 AM	34.4366995	-118.6479243	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-24030	6/29/2026 9:22:58 AM	34.4366732	-118.6478921	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-24031	6/2/2026 9:09:14 AM	34.4348707	-118.6498260	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24031	6/2/2026 9:16:24 AM	34.4348845	-118.6498233	Valve Adjustment:Surging Liquid in Header
CV-24031	6/22/2026 8:17:15 AM	34.4348912	-118.6498233	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-24031	6/22/2026 8:17:55 AM	34.4348835	-118.6498182	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24031	6/22/2026 8:18:11 AM	34.4348893	-118.6498130	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24032	6/2/2026 1:40:47 PM	34.4351096	-118.6496210	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Positive Static Press.,Increased Flow/Vacuum

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24032	6/2/2026 1:41:54 PM	34.4351130	-118.6496189	Valve Comment:Lorentz pump pumping;Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open
CV-24032	6/2/2026 1:45:00 PM			AtmAA
CV-24032	6/2/2026 1:45:00 PM			AtmAA; [User entered 13.64%]
CV-24032	6/9/2026 10:16:37 AM	34.4351229	-118.6496185	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open
CV-24032	6/9/2026 10:17:50 AM	34.4351232	-118.6496186	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open
CV-24032	6/16/2026 10:01:42 AM	34.4351142	-118.6496256	Valve Comment:Pump disconnected;Valve Adjustment:No Flow Measurement,High Temp,High O2,Decreased Flow/Vacuum
CV-24032	6/16/2026 10:03:21 AM	34.4351137	-118.6496242	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-24032	6/23/2026 10:42:53 AM	34.4351021	-118.6496158	Valve Comment:Pump disconnected;Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum,Barely Open
CV-24032	6/23/2026 10:43:53 AM	34.4350988	-118.6496145	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-24032	6/25/2026 8:17:52 AM			
CV-24032	6/29/2026 9:46:20 AM	34.4351067	-118.6496315	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header
CV-24032	6/30/2026 8:30:37 AM	34.4351140	-118.6496373	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24033	6/2/2026 1:44:33 PM	34.4353348	-118.6494458	Valve Adjustment:No Flow Measurement,High Temp
CV-24033	6/2/2026 1:55:00 PM			AtmAA; [User entered 17%]
CV-24033	6/2/2026 1:55:00 PM			AtmAA
CV-24033	6/9/2026 10:10:59 AM	34.4353534	-118.6494719	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Increased Flow/Vacuum,Valve 100% Open
CV-24033	6/9/2026 10:11:43 AM	34.4353533	-118.6494719	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open
CV-24033	6/16/2026 9:54:12 AM	34.4353294	-118.6494838	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Increased Flow/Vacuum,Valve 100% Open
CV-24033	6/16/2026 9:54:43 AM	34.4353295	-118.6494839	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-24033	6/16/2026 3:10:13 PM	34.4353493	-118.6494538	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp;Well Comment:Active;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24033	6/16/2026 3:11:47 PM	34.4353538	-118.6494512	Valve Adjustment:High Temp;Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24033	6/23/2026 10:34:05 AM	34.4353474	-118.6494596	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24033	6/23/2026 10:36:00 AM	34.4353438	-118.6494579	Valve Adjustment:No Flow Measurement,High Temp
CV-24033	6/29/2026 9:54:36 AM	34.4353462	-118.6494618	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24033	6/29/2026 9:57:22 AM	34.4353393	-118.6494633	
CV-24034	6/8/2026 10:37:49 AM			
CV-24034	6/10/2026 11:03:35 AM	34.4360937	-118.6481260	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-24034	6/10/2026 1:01:10 PM	34.4361563	-118.6482120	
CV-24034	6/10/2026 1:03:05 PM	34.4361955	-118.6480740	
CV-24034	6/15/2026 9:36:46 AM	34.4361108	-118.6481200	Valve Comment:Lorentz pump installed;Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24034	6/22/2026 9:50:57 AM	34.4361153	-118.6481073	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24034	6/22/2026 9:51:32 AM	34.4361185	-118.6481119	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-24034	6/30/2026 8:05:38 AM	34.4360900	-118.6481245	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24034	6/30/2026 8:08:12 AM	34.4360928	-118.6481237	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24035	6/1/2026 9:31:45 AM	34.4363657	-118.6477204	Valve Adjustment:No Flow Measurement,High Temp
CV-24035	6/1/2026 9:40:00 AM			AtmAA
CV-24035	6/1/2026 9:40:00 AM			AtmAA; [User entered 15.405%]
CV-24035	6/8/2026 9:15:31 AM	34.4363706	-118.6477249	Valve Adjustment:No Flow Measurement,High Temp
CV-24035	6/15/2026 8:40:23 AM	34.4364009	-118.6477273	Valve Adjustment:No Flow Measurement,High Temp
CV-24035	6/22/2026 8:50:48 AM	34.4363905	-118.6477207	Valve Adjustment:No Flow Measurement,High Temp
CV-24035	6/29/2026 9:07:04 AM	34.4363878	-118.6477239	Valve Adjustment:No Flow Measurement,High Temp
CV-24036	6/2/2026 9:30:31 AM	34.4344428	-118.6497188	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header
CV-24036	6/22/2026 8:28:46 AM	34.4344583	-118.6497150	Well Comment:Vacuum surging
CV-24037	6/2/2026 9:49:59 AM	34.4347280	-118.6494597	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header
CV-24037	6/22/2026 8:23:58 AM	34.4347422	-118.6494380	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24037	6/22/2026 8:24:48 AM	34.4347488	-118.6494370	Valve Adjustment:NSPS/EG CAI,High Temp;Well Comment:Surging
CV-24037	6/29/2026 12:33:39 PM	34.4347513	-118.6494463	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24037	6/29/2026 12:34:30 PM	34.4347562	-118.6494413	
CV-24038	6/2/2026 2:01:48 PM	34.4350182	-118.6488774	Valve Comment:Lorentz pump on;Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24038	6/2/2026 2:03:03 PM	34.4350196	-118.6488781	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-24038	6/2/2026 2:05:00 PM			AtmAA
CV-24038	6/2/2026 2:05:00 PM			AtmAA; [User entered 15.57%]
CV-24038	6/3/2026 3:29:21 PM			
CV-24038	6/9/2026 12:58:07 PM	34.4350286	-118.6488692	Valve Comment:No pump installed;Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24038	6/9/2026 12:59:45 PM	34.4350185	-118.6488519	Valve Adjustment:No Flow Measurement,High Temp
CV-24038	6/9/2026 1:14:37 PM	34.4350047	-118.6488601	Valve Adjustment:No Flow Measurement,High Temp
CV-24038	6/16/2026 1:02:05 PM	34.4350208	-118.6488700	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24038	6/16/2026 1:03:03 PM			Valve Comment:Pump on;Valve Adjustment:No Flow Measurement,High Temp
CV-24038	6/23/2026 2:03:54 PM	34.4350183	-118.6488752	Valve Comment:Pump offline;Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24038	6/23/2026 2:04:41 PM	34.4350189	-118.6488791	Valve Adjustment:No Flow Measurement,High Temp
CV-24038	6/29/2026 12:43:07 PM	34.4350083	-118.6488735	Valve Adjustment:High Temp
CV-24039	6/10/2026 10:33:51 AM	34.4352772	-118.6486883	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24039	6/15/2026 1:30:09 PM	34.4353108	-118.6487217	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24039	6/15/2026 1:31:35 PM	34.4353081	-118.6487195	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-24039	6/23/2026 1:50:27 PM	34.4352824	-118.6486896	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24039	6/23/2026 1:51:13 PM	34.4352876	-118.6486919	Valve Adjustment:No Flow Measurement,High Temp
CV-24039	6/29/2026 12:51:38 PM	34.4352912	-118.6486785	Valve Adjustment:High Temp

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24040	6/1/2026 2:28:59 PM	34.4356362	-118.6483835	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-24040	6/1/2026 2:30:00 PM			AtmAA; [User entered 14.62%]
CV-24040	6/1/2026 2:30:00 PM			AtmAA
CV-24040	6/1/2026 2:30:55 PM	34.4356346	-118.6483843	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24040	6/11/2026 10:25:08 AM	34.4356275	-118.6483761	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24040	6/11/2026 10:31:45 AM	34.4356284	-118.6483778	Valve Comment:Pump on;Valve Adjustment:No Flow Measurement,High Temp
CV-24040	6/15/2026 9:40:41 AM	34.4356439	-118.6483785	Valve Comment:Pump on;Valve Adjustment:No Flow Measurement,High Temp
CV-24040	6/22/2026 10:31:23 AM	34.4356504	-118.6483880	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24040	6/22/2026 10:32:22 AM	34.4356562	-118.6483853	Valve Adjustment:No Flow Measurement,High Temp
CV-24040	6/22/2026 1:40:55 PM	34.4356587	-118.6483748	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-24040	6/29/2026 1:04:55 PM	34.4356432	-118.6483973	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-24041	6/10/2026 10:56:45 AM	34.4358500	-118.6480412	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24041	6/10/2026 10:58:05 AM	34.4358430	-118.6480527	Valve Adjustment:NSPS/EG CAC,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24041	6/22/2026 1:36:11 PM	34.4358803	-118.6480308	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In)
CV-24041	6/22/2026 1:36:46 PM	34.4358838	-118.6480362	Valve Adjustment:High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24042	6/1/2026 1:43:32 PM	34.4362527	-118.6474337	Valve Comment:Surging in header;Valve Adjustment:No Flow Measurement,High Temp
CV-24042	6/1/2026 2:00:00 PM			AtmAA; [User entered 13.18%]
CV-24042	6/1/2026 2:00:00 PM			AtmAA
CV-24042	6/8/2026 10:25:47 AM	34.4362438	-118.6474745	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header;Well Condition:Lorentz Pump Installed;Well Repairs:Surging
CV-24042	6/15/2026 10:17:58 AM	34.4362532	-118.6474662	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24042	6/22/2026 10:19:11 AM	34.4362321	-118.6474675	Valve Adjustment:No Flow Measurement,High Temp
CV-24042	6/30/2026 8:22:39 AM	34.4362460	-118.6474870	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24043	6/2/2026 3:43:36 PM	34.4340700	-118.6497628	
CV-24043	6/3/2026 9:39:34 AM	34.4340682	-118.6497043	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24043	6/25/2026 8:57:04 AM	34.4341405	-118.6496740	No Flow Measurement,No Adjustment Made,
CV-24044	6/2/2026 9:35:24 AM	34.4343820	-118.6494257	Valve Adjustment:Decreased Flow/Vacuum
CV-24044	6/22/2026 8:35:31 AM	34.4343782	-118.6493795	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header
CV-24044	6/22/2026 8:36:18 AM	34.4343860	-118.6493900	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24044	6/29/2026 12:27:05 PM	34.4343748	-118.6494023	Valve Adjustment:High Temp,Barely Open
CV-24045	6/2/2026 2:06:38 PM	34.4347441	-118.6490743	Valve Adjustment:No Flow Measurement,High Temp
CV-24045	6/2/2026 2:10:00 PM			AtmAA; [User entered 16.57%]
CV-24045	6/2/2026 2:10:00 PM			AtmAA
CV-24045	6/9/2026 1:04:35 PM	34.4347553	-118.6490487	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24045	6/9/2026 1:05:54 PM	34.4347532	-118.6490443	Valve Adjustment:No Flow Measurement,High Temp
CV-24045	6/9/2026 1:12:32 PM	34.4347379	-118.6490511	Valve Adjustment:No Flow Measurement,High Temp
CV-24045	6/16/2026 1:06:05 PM	34.4347589	-118.6490714	Valve Adjustment:No Flow Measurement,High Temp
CV-24045	6/23/2026 2:07:06 PM	34.4347494	-118.6490788	Valve Adjustment:No Flow Measurement,High Temp
CV-24045	6/29/2026 12:38:59 PM	34.4347298	-118.6490572	Valve Adjustment:High Temp,Barely Open
CV-24046	6/10/2026 10:01:39 AM	34.4350653	-118.6483730	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24046	6/10/2026 10:02:29 AM	34.4350748	-118.6483678	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24046	6/15/2026 1:34:47 PM	34.4350885	-118.6483787	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24046	6/15/2026 1:37:16 PM	34.4350900	-118.6483770	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24046	6/23/2026 1:41:24 PM	34.4350963	-118.6483875	Valve Adjustment:No Flow Measurement,High Temp
CV-24046	6/29/2026 12:57:50 PM	34.4350675	-118.6483720	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24046	6/29/2026 12:59:14 PM	34.4350655	-118.6483665	
CV-24048	6/10/2026 10:44:37 AM	34.4355430	-118.6477990	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24048	6/22/2026 1:27:42 PM	34.4355758	-118.6478090	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24049	6/1/2026 1:29:08 PM	34.4359505	-118.6471838	Valve Comment:Surging in header;Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header;Well Repairs:Surging
CV-24049	6/1/2026 1:40:00 PM			AtmAA
CV-24049	6/1/2026 1:40:00 PM			AtmAA; [User entered 15.12%]
CV-24049	6/4/2026 9:00:00 AM			Air Tech Lab; [User entered 16%]
CV-24049	6/4/2026 9:00:00 AM			AirTech Lab
CV-24049	6/8/2026 1:38:10 PM	34.4359399	-118.6471833	Valve Adjustment:No Flow Measurement,High Temp
CV-24049	6/15/2026 9:57:07 AM	34.4359338	-118.6471854	Valve Comment:Surging in header;Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header;Well Repairs:Surging
CV-24049	6/22/2026 1:22:35 PM	34.4359581	-118.6471830	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header
CV-24049	6/26/2026 2:42:38 PM			
CV-24049	6/29/2026 2:11:03 PM	34.4359550	-118.6471934	Valve Adjustment:No Flow Measurement,High Temp
CV-24050	6/3/2026 9:17:29 AM	34.4337275	-118.6499478	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24050	6/22/2026 11:57:01 AM	34.4337012	-118.6499888	Valve Adjustment:Surging Liquid in Header
CV-24051	6/4/2026 12:43:06 PM	34.4344868	-118.6490445	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24051	6/4/2026 12:44:46 PM	34.4345037	-118.6490423	Valve Adjustment:NSPS/EG CAC
CV-24051	6/25/2026 11:34:01 AM	34.4345050	-118.6489953	NSPS/EG CAI,No Flow Measurement,High O2
CV-24051	6/25/2026 11:40:21 AM	34.4345342	-118.6489993	NSPS/EG CAI,No Flow Measurement,High O2
CV-24051	6/25/2026 2:20:14 PM	34.4344612	-118.6490310	
CV-24052	6/4/2026 9:09:09 AM	34.4350773	-118.6480745	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Well (Watered In)
CV-24052	6/22/2026 1:46:11 PM	34.4350842	-118.6480623	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24053	6/3/2026 7:40:00 AM			AirTech Lab

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24053	6/3/2026 7:40:00 AM			Air Tech Lab; [User entered 0.85%]
CV-24053	6/3/2026 1:28:17 PM			
CV-24053	6/4/2026 8:58:29 AM	34.4352537	-118.6477925	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24053	6/22/2026 2:17:18 PM	34.4352915	-118.6477817	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24054	6/1/2026 1:25:36 PM	34.4356277	-118.6471832	Valve Adjustment:No Flow Measurement,High Temp
CV-24054	6/1/2026 1:35:00 PM			AtmAA; [User entered 13.08%]
CV-24054	6/1/2026 1:35:00 PM			AtmAA
CV-24054	6/3/2026 1:18:32 PM			
CV-24054	6/8/2026 1:28:03 PM	34.4356418	-118.6471762	Valve Adjustment:No Flow Measurement,High Temp
CV-24054	6/15/2026 9:53:03 AM	34.4356347	-118.6471734	Valve Adjustment:No Flow Measurement,High Temp
CV-24054	6/22/2026 1:30:09 PM	34.4356486	-118.6471754	Valve Adjustment:No Flow Measurement,High Temp
CV-24054	6/29/2026 2:13:59 PM	34.4356416	-118.6471795	Valve Adjustment:No Flow Measurement,High Temp
CV-24055	6/4/2026 10:40:08 AM	34.4358633	-118.6469398	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-24055	6/4/2026 10:41:12 AM	34.4358642	-118.6469320	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24055	6/12/2026 8:00:00 AM			Air Tech Lab
CV-24055	6/12/2026 8:00:00 AM			Air Tech Lab; [User entered 4.5%]
CV-24055	6/23/2026 9:47:37 AM	34.4358742	-118.6469395	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24056	6/2/2026 8:05:04 AM	34.4332623	-118.6501777	Valve Adjustment:Decreased Flow/Vacuum
CV-24056	6/6/2026 12:58:24 PM			
CV-24056	6/11/2026 1:07:15 PM	34.4332970	-118.6501617	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-24056	6/11/2026 1:09:23 PM	34.4332982	-118.6501577	Valve Adjustment:Barely Open;Well Condition:Pnumatic Pump Installed
CV-24056	6/16/2026 7:44:37 AM	34.4332810	-118.6501572	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-24056	6/16/2026 7:45:01 AM	34.4332852	-118.6501577	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24056	6/18/2026 1:25:18 PM			
CV-24056	6/18/2026 1:25:33 PM			
CV-24056	6/19/2026 11:47:34 AM			
CV-24056	6/19/2026 11:55:12 AM			
CV-24056	6/24/2026 1:59:57 PM			
CV-24056	6/24/2026 2:00:11 PM			

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24056	6/25/2026 2:06:44 PM	34.4332772	-118.6501343	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed
CV-24057	6/3/2026 9:12:06 AM	34.4334878	-118.6496717	Valve Adjustment:High Temp,Barely Open
CV-24057	6/24/2026 12:59:18 PM	34.4334615	-118.6496620	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-24057	6/24/2026 12:59:44 PM	34.4334633	-118.6496727	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-24058	6/3/2026 9:45:49 AM	34.4338097	-118.6494545	Valve Adjustment:Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
CV-24058	6/22/2026 12:12:11 PM	34.4337512	-118.6494347	Valve Adjustment:Audible Flow;Well Condition:Lorentz Pump Installed
CV-24059	6/11/2026 10:22:41 AM	34.4337032	-118.6490878	NSPS/EG CAI,High Temp,
CV-24059	6/11/2026 10:25:26 AM	34.4337730	-118.6492068	
CV-24059	6/11/2026 2:12:14 PM	34.4337653	-118.6490818	
CV-24059	6/24/2026 1:16:18 PM	34.4337552	-118.6490820	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-24059	6/24/2026 1:17:14 PM	34.4337610	-118.6490915	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-24060	6/3/2026 2:26:17 PM	34.4340517	-118.6487920	Valve Adjustment:Decreased Flow/Vacuum
CV-24060	6/10/2026 3:04:20 PM	34.4340161	-118.6488091	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24060	6/16/2026 9:58:14 AM	34.4340197	-118.6488033	Valve Adjustment:Decreased Flow/Vacuum
CV-24060	6/16/2026 9:59:06 AM	34.4340197	-118.6488033	
CV-24061	6/2/2026 4:14:18 PM	34.4343118	-118.6486610	
CV-24061	6/16/2026 10:06:15 AM	34.4343488	-118.6486332	Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Barely Open
CV-24061	6/16/2026 10:07:30 AM	34.4343537	-118.6486290	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24061	6/16/2026 10:08:55 AM	34.4343530	-118.6486318	Valve Adjustment:NSPS/EG CAC
CV-24062	6/10/2026 10:20:42 AM	34.4345780	-118.6480917	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-24062	6/10/2026 10:21:48 AM	34.4345792	-118.6480952	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24062	6/12/2026 8:50:00 AM			Air Tech Lab; [User entered 0.45%]
CV-24062	6/12/2026 8:50:00 AM			Air Tech Lab
CV-24062	6/16/2026 2:32:33 PM	34.4345750	-118.6481089	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24062	6/16/2026 2:33:39 PM	34.4345716	-118.6481064	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24062	6/24/2026 9:42:09 AM	34.4346007	-118.6480922	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24062	6/24/2026 9:44:44 AM	34.4345965	-118.6480964	Valve Adjustment:No Flow Measurement,High Temp
CV-24062	6/30/2026 8:52:28 AM	34.4345777	-118.6480797	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24063	6/3/2026 1:21:07 PM	34.4349533	-118.6475421	Valve Adjustment:No Flow Measurement,High Temp
CV-24063	6/3/2026 1:25:00 PM			AtmAA; [User entered 8.02%]
CV-24063	6/10/2026 2:12:26 PM	34.4349505	-118.6475214	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24063	6/12/2026 10:10:00 AM			Air Tech Lab
CV-24063	6/12/2026 10:10:00 AM			Air Tech Lab; [User entered 1.1%]
CV-24063	6/17/2026 2:30:04 PM	34.4349531	-118.6475565	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24063	6/17/2026 2:32:22 PM	34.4349559	-118.6475555	Valve Comment:Lorenz pump disconnected;Valve Adjustment:No Flow Measurement,High Temp
CV-24063	6/24/2026 9:23:23 AM	34.4349516	-118.6475176	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24063	6/24/2026 9:25:59 AM	34.4349540	-118.6475195	Valve Comment:Pump disconnected;Valve Adjustment:No Flow Measurement,High Temp
CV-24063	6/29/2026 10:05:04 AM			
CV-24063	6/29/2026 1:17:06 PM	34.4349045	-118.6475053	Valve Adjustment:High Temp
CV-24064	6/3/2026 1:28:32 PM	34.4352178	-118.6471627	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24064	6/3/2026 1:40:00 PM			AtmAA; [User entered 7.46%]
CV-24064	6/10/2026 2:23:47 PM	34.4352179	-118.6471791	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In)
CV-24064	6/12/2026 8:35:00 AM			Air Tech Lab
CV-24064	6/12/2026 8:35:00 AM			Air Tech Lab; [User entered 1.1%]
CV-24064	6/24/2026 9:09:36 AM	34.4352296	-118.6471518	Valve Adjustment:No Flow Measurement,High Temp
CV-24064	6/30/2026 2:26:34 PM	34.4352509	-118.6471830	Valve Adjustment:No Flow Measurement,High Temp
CV-24065-TP	6/4/2026 10:11:00 AM	34.4356068	-118.6468122	Valve Adjustment:Barely Open
CV-24065-TP	6/11/2026 7:40:00 AM			Air Tech Lab; [User entered 0.71%]
CV-24065-TP	6/11/2026 7:40:00 AM			Air Tech Lab
CV-24065-TP	6/17/2026 2:10:47 PM	34.4356613	-118.6467935	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24066	6/2/2026 7:57:31 AM	34.4330018	-118.6498085	Valve Adjustment:Decreased Flow/Vacuum
CV-24066	6/15/2026 7:50:00 AM			Air Tech Lab
CV-24066	6/15/2026 7:50:00 AM			Air Tech Lab; [User entered 3.0%]
CV-24066	6/16/2026 7:41:54 AM	34.4330190	-118.6497983	
CV-24067	6/4/2026 10:06:31 AM	34.4331814	-118.6497228	Valve Adjustment:High Temp
CV-24067	6/10/2026 9:00:37 AM	34.4331893	-118.6496853	Valve Adjustment:High Temp
CV-24067	6/16/2026 9:09:08 AM	34.4331897	-118.6497388	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24067	6/16/2026 9:09:40 AM	34.4331943	-118.6497343	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24067	6/17/2026 9:02:41 AM	34.4331864	-118.6497379	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24067	6/17/2026 9:03:28 AM	34.4331883	-118.6497375	Valve Adjustment:No Flow Measurement,High Temp
CV-24067	6/24/2026 1:17:20 PM	34.4331918	-118.6497178	Valve Adjustment:High Temp
CV-24068	6/4/2026 11:50:22 AM	34.4332740	-118.6493508	Valve Adjustment:NSPS/EG CAI,High Temp;Well Condition:Lorentz Pump Installed
CV-24068	6/4/2026 11:51:40 AM	34.4332947	-118.6493547	
CV-24068	6/9/2026 1:53:32 PM	34.4332434	-118.6493468	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24068	6/9/2026 1:54:04 PM	34.4332433	-118.6493469	Valve Adjustment:NSPS/EG CAC,No Flow Measurement
CV-24068	6/24/2026 1:04:40 PM	34.4332333	-118.6493445	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24068	6/24/2026 1:05:09 PM	34.4332302	-118.6493390	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24068	6/30/2026 4:27:59 PM			
CV-24069	6/3/2026 9:58:36 AM	34.4334232	-118.6489040	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open,Surging Liquid in Header
CV-24069	6/3/2026 9:59:30 AM	34.4334173	-118.6489017	Valve Adjustment:NSPS/EG CAC,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24069	6/11/2026 9:28:47 AM	34.4334352	-118.6489083	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum;Well Comment:pump active;Well Condition:Lorentz Pump Installed
CV-24069	6/11/2026 12:10:39 PM	34.4334270	-118.6489245	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-24069	6/11/2026 12:19:47 PM	34.4334247	-118.6489040	Valve Comment:Secured lorentz fitting;Well Condition:Lorentz Pump Installed
CV-24069	6/15/2026 8:00:00 AM			Air Tech Lab; [User entered 12%]
CV-24069	6/15/2026 8:00:00 AM			Air Tech Lab

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24069	6/16/2026 9:36:41 AM	34.4334240	-118.6489310	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-24069	6/16/2026 9:37:03 AM	34.4334262	-118.6489313	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24069	6/16/2026 9:37:50 AM	34.4334262	-118.6489313	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-24070	6/3/2026 10:03:54 AM	34.4337060	-118.6486787	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24070	6/3/2026 10:04:21 AM	34.4337128	-118.6486812	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24070	6/12/2026 9:10:00 AM			Air Tech Lab; [User entered 5.5%]
CV-24070	6/12/2026 9:10:00 AM			Air Tech Lab
CV-24070	6/24/2026 1:12:10 PM	34.4337165	-118.6487175	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-24070	6/24/2026 1:12:40 PM	34.4337145	-118.6487105	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24071	6/3/2026 2:29:39 PM	34.4340187	-118.6484767	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24071	6/12/2026 9:00:00 AM			Air Tech Lab
CV-24071	6/12/2026 9:00:00 AM			Air Tech Lab; [User entered 3.6%]
CV-24071	6/22/2026 10:12:46 AM	34.4340100	-118.6484518	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header
CV-24071	6/22/2026 10:13:06 AM	34.4340047	-118.6484575	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24072	6/2/2026 4:06:57 PM	34.4342100	-118.6480280	NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.
CV-24072	6/2/2026 4:09:25 PM	34.4342037	-118.6480705	
CV-24072	6/22/2026 10:08:42 AM	34.4341953	-118.6480268	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum,Surging Liquid in Header
CV-24073-TF	6/4/2026 8:59:38 AM	34.4346395	-118.6476870	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-24073-TF	6/4/2026 9:05:52 AM	34.4346385	-118.6477008	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-24073-TF	6/10/2026 2:06:19 PM	34.4346325	-118.6477036	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24073-TF	6/10/2026 2:07:26 PM	34.4346330	-118.6477022	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-24073-TF	6/26/2026 8:59:10 AM	34.4346287	-118.6477027	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header
CV-24073-TF	6/26/2026 9:00:11 AM	34.4346402	-118.6477055	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24073-TF	6/30/2026 1:58:39 PM	34.4346130	-118.6477199	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24073-TF	6/30/2026 1:59:55 PM	34.4346247	-118.6477164	Valve Adjustment:No Flow Measurement,High Temp
CV-24074	6/4/2026 9:11:06 AM	34.4347322	-118.6473997	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24074	6/16/2026 9:24:52 AM			
CV-24074	6/24/2026 1:10:15 PM	34.4347197	-118.6474445	Valve Adjustment:Decreased Flow/Vacuum
CV-24075-TF	6/1/2026 2:36:56 PM	34.4349818	-118.6471339	Valve Comment:Cant adjust well side;Valve Adjustment:No Flow Measurement,High Temp
CV-24075-TF	6/1/2026 2:40:00 PM			AtmAA; [User entered 11.26%]
CV-24075-TF	6/1/2026 2:40:00 PM			AtmAA
CV-24075-TF	6/10/2026 2:18:34 PM	34.4350143	-118.6471440	Valve Comment:Cant adjust valve;Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24075-TF	6/24/2026 9:17:11 AM	34.4350126	-118.6471384	Valve Adjustment:No Flow Measurement,High Temp
CV-24075-TF	6/30/2026 2:19:22 PM	34.4350591	-118.6471216	Valve Adjustment:No Flow Measurement,High Temp
CV-24076	6/4/2026 9:16:55 AM	34.4353187	-118.6468739	Valve Adjustment:High Temp
CV-24076	6/10/2026 2:27:37 PM	34.4353024	-118.6468985	Valve Adjustment:High Temp
CV-24076	6/22/2026 1:41:43 PM	34.4353272	-118.6468827	Valve Adjustment:High Temp
CV-24076	6/30/2026 2:39:35 PM	34.4353432	-118.6468844	Valve Adjustment:No Flow Measurement,High Temp
CV-24077	6/1/2026 2:47:35 PM	34.4326799	-118.6493048	Valve Adjustment:NSPS/EG CAC,No Flow Measurement
CV-24077	6/2/2026 7:49:32 AM	34.4326788	-118.6493198	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24077	6/2/2026 7:52:34 AM	34.4326718	-118.6493153	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24077	6/6/2026 12:27:22 PM			
CV-24077	6/11/2026 3:08:29 PM	34.4326597	-118.6493213	
CV-24077	6/11/2026 3:10:14 PM	34.4326670	-118.6491867	
CV-24077	6/15/2026 2:24:46 PM	34.4327026	-118.6493354	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24077	6/16/2026 7:33:30 AM	34.4326982	-118.6493068	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24077	6/16/2026 7:35:27 AM	34.4326973	-118.6492852	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24077	6/19/2026 10:22:28 AM	34.4326345	-118.6492710	High Temp
CV-24077	6/19/2026 10:23:54 AM	34.4326547	-118.6491832	
CV-24077	6/24/2026 1:14:10 PM	34.4326897	-118.6493042	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24077	6/30/2026 11:17:02 AM	34.4326602	-118.6493477	NSPS/EG CAI,High Temp,
CV-24077	6/30/2026 11:19:14 AM	34.4326847	-118.6491662	

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24078	6/2/2026 7:45:28 AM	34.4328965	-118.6494448	Valve Adjustment:Decreased Flow/Vacuum
CV-24078	6/6/2026 12:33:36 PM			
CV-24078	6/16/2026 7:39:27 AM	34.4329107	-118.6494393	Valve Adjustment:Barely Open
CV-24078	6/19/2026 11:42:01 AM			
CV-24078	6/25/2026 3:22:02 PM			
CV-24078	6/25/2026 3:22:24 PM			
CV-24078	6/25/2026 3:23:34 PM			
CV-24078	6/26/2026 1:44:33 PM			
CV-24078	6/26/2026 1:44:44 PM			
CV-24079-TP	6/4/2026 12:07:14 PM	34.4329940	-118.6491258	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24079-TP	6/4/2026 12:09:00 PM	34.4330202	-118.6491273	Well Condition:Lorentz Pump Installed
CV-24079-TP	6/9/2026 1:56:55 PM	34.4329777	-118.6491261	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24079-TP	6/9/2026 1:57:28 PM	34.4329748	-118.6491248	Valve Adjustment:No Flow Measurement,High Temp
CV-24079-TP	6/16/2026 1:51:51 PM	34.4329783	-118.6491363	Valve Adjustment:No Flow Measurement,High Temp
CV-24079-TP	6/23/2026 2:42:01 PM	34.4329712	-118.6491228	Valve Adjustment:No Flow Measurement,High Temp
CV-24079-TP	6/30/2026 10:39:33 AM	34.4329729	-118.6491204	Valve Adjustment:No Flow Measurement,High Temp
CV-24080	6/3/2026 8:57:08 AM	34.4331143	-118.6488743	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24080	6/16/2026 9:30:00 AM	34.4331415	-118.6488650	Valve Adjustment:Barely Open
CV-24081-TP	6/3/2026 10:09:44 AM	34.4334002	-118.6485803	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24081-TP	6/16/2026 9:43:47 AM	34.4334167	-118.6485983	Valve Adjustment:Audible Flow
CV-24081-TP	6/23/2026 12:39:08 PM			
CV-24081-TP	6/25/2026 3:13:31 PM			
CV-24081-TP	6/25/2026 3:13:41 PM			
CV-24082	6/3/2026 2:39:26 PM	34.4334467	-118.6483345	Valve Adjustment:Barely Open
CV-24082	6/16/2026 10:19:49 AM	34.4334273	-118.6483408	Valve Adjustment:Decreased Flow/Vacuum
CV-24083	6/3/2026 2:36:38 PM	34.4337233	-118.6483382	Valve Adjustment:Barely Open
CV-24083	6/15/2026 10:42:17 AM			
CV-24083	6/22/2026 10:20:18 AM	34.4336942	-118.6483327	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header
CV-24083	6/22/2026 10:20:37 AM	34.4336870	-118.6483275	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24084-TP	6/2/2026 2:30:00 PM			AtmAA
CV-24084-TP	6/2/2026 2:30:05 PM	34.4338549	-118.6480617	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24084-TF	6/11/2026 9:56:54 AM	34.4338282	-118.6480441	Valve Adjustment:No Flow Measurement,High Temp
CV-24084-TF	6/16/2026 2:12:06 PM	34.4338586	-118.6480707	Valve Adjustment:No Flow Measurement,High Temp
CV-24084-TF	6/24/2026 9:57:44 AM	34.4338721	-118.6480335	Valve Adjustment:No Flow Measurement,High Temp
CV-24084-TF	6/30/2026 1:30:00 PM	34.4338408	-118.6480360	Valve Adjustment:No Flow Measurement,High Temp
CV-24085	6/1/2026 11:07:12 AM	34.4322690	-118.6490038	
CV-24085	6/22/2026 10:40:32 AM	34.4323957	-118.6490183	Valve Adjustment:Barely Open;Well Comment:Pump active;Well Condition:Pnumatic Pump Installed
CV-24086	6/3/2026 8:44:16 AM	34.4328902	-118.6486960	Valve Adjustment:Barely Open
CV-24086	6/16/2026 9:26:38 AM	34.4328928	-118.6487085	Valve Adjustment:Barely Open
CV-24087	6/2/2026 2:23:52 PM	34.4330137	-118.6481202	Valve Adjustment:Decreased Flow/Vacuum
CV-24087	6/19/2026 2:08:39 PM	34.4329938	-118.6481118	
CV-24088	6/3/2026 2:54:01 PM	34.4335945	-118.6476668	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24088	6/22/2026 1:23:31 PM	34.4335898	-118.6476667	
CV-24089	6/1/2026 3:18:19 PM	34.4324498	-118.6481375	
CV-24089	6/1/2026 3:20:14 PM	34.4324212	-118.6481305	
CV-24089	6/17/2026 1:05:18 PM	34.4324512	-118.6480668	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum
CV-24090	6/1/2026 3:34:26 PM	34.4326015	-118.6476292	
CV-24090	6/17/2026 12:58:09 PM	34.4326782	-118.6475147	Valve Adjustment:Decreased Flow/Vacuum
CV-24091	6/2/2026 1:20:08 PM	34.4329878	-118.6468848	
CV-24091	6/19/2026 1:33:24 PM	34.4330032	-118.6468858	
CV-24092	6/4/2026 8:13:48 AM	34.4332848	-118.6461230	Valve Adjustment:Increased Flow/Vacuum
CV-24093	6/4/2026 9:21:34 AM	34.4340462	-118.6463562	Valve Adjustment:Audible Flow,Barely Open
CV-24093	6/16/2026 5:45:55 AM	34.4340412	-118.6463685	
CV-24094	6/8/2026 12:10:53 PM	34.4345903	-118.6460937	NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24094	6/8/2026 12:13:02 PM	34.4344450	-118.6459697	
CV-24094	6/22/2026 8:57:15 AM	34.4345792	-118.6460738	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In);Well Comment:no pump
CV-24094	6/22/2026 8:58:14 AM	34.4345833	-118.6460788	
CV-24095	6/3/2026 10:39:26 AM	34.4333990	-118.6512978	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Header;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24095	6/3/2026 10:40:36 AM	34.4333980	-118.6512977	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.
CV-24095	6/3/2026 10:45:00 AM			AtmAA; [User entered 14.83%]
CV-24095	6/8/2026 1:35:18 PM	34.4334017	-118.6513088	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24095	6/8/2026 1:36:04 PM	34.4333928	-118.6513093	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24095	6/10/2026 1:17:22 PM	34.4334129	-118.6513093	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24095	6/16/2026 8:20:00 AM			Air Tech Lab; [User entered 17%]
CV-24095	6/16/2026 8:20:00 AM			Air Tech Lab
CV-24095	6/17/2026 10:38:51 AM	34.4333970	-118.6513147	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-24096	6/11/2026 10:32:09 AM	34.4332060	-118.6515783	NSPS/EG CAI,High O2,
CV-24096	6/11/2026 10:33:45 AM	34.4331642	-118.6515252	NSPS/EG CAI,High O2,
CV-24096	6/12/2026 9:48:27 AM	34.4332497	-118.6515838	No Flow Measurement
CV-24096	6/25/2026 11:07:44 AM	34.4332437	-118.6515792	NSPS/EG CAI,No Flow Measurement,Positive Static Press.,Reduced System Vacuum
CV-24096	6/25/2026 11:09:58 AM	34.4332990	-118.6516228	NSPS/EG CAC,No Flow Measurement,Reduced System Vacuum
CV-24097	6/10/2026 10:19:39 AM	34.4328475	-118.6515712	
CV-24097	6/16/2026 7:47:31 AM	34.4328092	-118.6515418	Valve Adjustment:Increased Flow/Vacuum,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-24098	6/1/2026 9:10:16 AM			
CV-24098	6/2/2026 7:53:08 AM			
CV-24098	6/5/2026 10:47:49 AM			
CV-24098	6/6/2026 8:15:18 AM			
CV-24098	6/9/2026 4:08:34 PM			
CV-24098	6/9/2026 4:08:44 PM			
CV-24098	6/10/2026 8:26:44 AM	34.4325223	-118.6512998	No Adjustment Made
CV-24098	6/19/2026 12:22:19 PM			
CV-24098	6/25/2026 10:59:13 AM	34.4325210	-118.6513013	No Flow Measurement
CV-24098	6/30/2026 1:29:44 PM			
CV-24098	6/30/2026 1:30:02 PM			
CV-24099	6/10/2026 11:59:36 AM			
CV-24099	6/10/2026 11:59:36 AM			
CV-24099	6/11/2026 10:15:38 AM	34.4323407	-118.6509457	NSPS/EG CAI,High O2,
CV-24099	6/11/2026 10:19:14 AM	34.4323113	-118.6508862	NSPS/EG CAI,High O2,
CV-24099	6/12/2026 9:26:51 AM	34.4322675	-118.6509528	

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24099	6/17/2026 10:19:03 AM	34.4323370	-118.6509377	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
CV-24099	6/17/2026 10:22:36 AM	34.4323443	-118.6509363	Valve Adjustment:NSPS/EG CAC
CV-24100	6/1/2026 9:40:00 AM			AirTech Lab; [User entered 0.67%]
CV-24100	6/1/2026 9:40:00 AM			AirTech Lab
CV-24100	6/3/2026 10:14:54 AM	34.4320474	-118.6505043	Valve Adjustment:No Flow Measurement,High Temp
CV-24100	6/3/2026 10:15:00 AM			AtmAA; [User entered 1.5%]
CV-24100	6/10/2026 1:48:21 PM	34.4320436	-118.6504832	Valve Adjustment:No Flow Measurement,High Temp
CV-24100	6/10/2026 1:50:08 PM	34.4320467	-118.6504786	Valve Adjustment:No Flow Measurement,High Temp
CV-24100	6/17/2026 8:28:06 AM	34.4320543	-118.6504893	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header
CV-24100	6/17/2026 10:27:26 AM	34.4320466	-118.6504882	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24100	6/17/2026 10:27:54 AM	34.4320355	-118.6504905	Valve Adjustment:No Flow Measurement,High Temp
CV-24101	6/2/2026 7:53:37 AM			
CV-24101	6/4/2026 7:59:12 AM			
CV-24101	6/6/2026 8:14:26 AM			
CV-24101	6/9/2026 2:32:46 PM			
CV-24101	6/9/2026 2:32:58 PM			
CV-24101	6/10/2026 8:31:01 AM	34.4318208	-118.6502775	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-24101	6/16/2026 9:30:00 AM			Air Tech Lab
CV-24101	6/16/2026 9:30:00 AM			Air Tech Lab; [User entered 0%]
CV-24101	6/17/2026 8:21:54 AM	34.4318240	-118.6502962	Valve Adjustment:Decreased Flow/Vacuum
CV-24101	6/19/2026 12:10:06 PM			
CV-24101	6/30/2026 2:47:24 PM			
CV-24101	6/30/2026 2:47:36 PM			
CV-24102	6/2/2026 7:38:32 AM			
CV-24102	6/6/2026 8:13:53 AM			
CV-24102	6/8/2026 1:06:02 PM	34.4316422	-118.6497878	Valve Adjustment:Decreased Flow/Vacuum
CV-24102	6/16/2026 8:47:00 AM	34.4316163	-118.6497802	
CV-24102	6/29/2026 1:05:13 PM			
CV-24103	6/1/2026 10:11:29 AM	34.4316017	-118.6487902	
CV-24103	6/17/2026 12:16:15 PM	34.4316318	-118.6488400	Valve Adjustment:Barely Open
CV-24104	6/1/2026 3:09:05 PM	34.4319683	-118.6479882	
CV-24104	6/3/2026 2:45:25 PM			
CV-24104	6/19/2026 2:53:53 PM	34.4319050	-118.6480503	
CV-24105	6/1/2026 2:59:30 PM	34.4319415	-118.6477437	
CV-24105	6/3/2026 2:50:39 PM			

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24105	6/17/2026 1:20:46 PM	34.4318885	-118.6476410	Valve Adjustment:Audible Flow,Barely Open
CV-24106	6/1/2026 3:40:10 PM	34.4320828	-118.6467583	
CV-24106	6/19/2026 11:21:28 AM	34.4321213	-118.6467398	Valve Adjustment:Increased Flow/Vacuum
CV-24106	6/19/2026 2:40:04 PM	34.4321282	-118.6466740	
CV-24107	6/11/2026 11:00:24 AM	34.4325363	-118.6461658	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24108	6/1/2026 1:18:43 PM			
CV-24108	6/2/2026 9:11:29 AM			
CV-24108	6/3/2026 8:42:03 AM	34.4331490	-118.6454477	
CV-24108	6/3/2026 9:24:44 AM			
CV-24108	6/4/2026 8:13:47 AM			
CV-24108	6/5/2026 1:40:27 PM			
CV-24108	6/6/2026 8:22:48 AM			
CV-24108	6/8/2026 3:30:54 PM			
CV-24108	6/8/2026 3:37:11 PM			
CV-24108	6/18/2026 2:02:43 PM			
CV-24108	6/19/2026 11:47:53 AM			
CV-24108	6/24/2026 11:07:23 AM			
CV-24108	6/24/2026 11:07:33 AM			
CV-24108	6/24/2026 11:08:01 AM			
CV-24108	6/24/2026 11:09:51 AM			
CV-24108	6/25/2026 2:12:26 PM			
CV-24108	6/25/2026 2:12:49 PM			
CV-24108	6/29/2026 2:23:43 PM			
CV-24108	6/29/2026 2:23:58 PM			
CV-24109	6/1/2026 1:15:50 PM			
CV-24109	6/2/2026 9:05:54 AM			
CV-24109	6/3/2026 8:29:21 AM	34.4340033	-118.6448685	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Comment:System port installed
CV-24109	6/3/2026 9:19:32 AM			
CV-24109	6/4/2026 8:18:15 AM			
CV-24109	6/5/2026 1:36:04 PM			
CV-24109	6/6/2026 8:36:42 AM			
CV-24109	6/8/2026 3:20:24 PM			
CV-24109	6/8/2026 3:20:49 PM			
CV-24109	6/19/2026 11:42:44 AM			
CV-24109	6/24/2026 11:00:46 AM			
CV-24109	6/24/2026 11:00:54 AM			
CV-24109	6/25/2026 2:01:59 PM			
CV-24109	6/25/2026 2:02:09 PM			
CV-24109	6/29/2026 2:15:54 PM			

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24109	6/29/2026 2:16:04 PM			
CV-24109	6/29/2026 4:07:05 PM			
CV-24109	6/30/2026 11:41:30 AM	34.4339852	-118.6448147	
CV-24110	6/8/2026 11:54:29 AM	34.4346005	-118.6446852	
CV-24110	6/19/2026 9:53:23 AM	34.4346015	-118.6446638	Valve Adjustment:Barely Open,Valve 100% Closed,Surging Liquid in Header
CV-24111	6/3/2026 12:34:12 PM	34.4353238	-118.6449737	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-24111	6/19/2026 10:04:31 AM	34.4352955	-118.6449187	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24112	6/8/2026 11:49:51 AM	34.4352720	-118.6443580	
CV-24114	6/10/2026 9:27:53 AM	34.4307898	-118.6485372	Valve Adjustment:Audible Flow,Valve 100% Open
CV-24114	6/29/2026 10:36:19 AM			
CV-24116	6/8/2026 3:48:25 PM	34.4315330	-118.6456875	
CV-24117	6/3/2026 11:49:43 AM	34.4323500	-118.6449558	
CV-24118	6/3/2026 9:22:48 AM	34.4332848	-118.6438262	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-24119	6/15/2026 10:17:22 AM	34.4337285	-118.6423290	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
CV-24119	6/15/2026 10:18:25 AM	34.4337302	-118.6423225	Valve Adjustment:NSPS/EG CAC
CV-24120	6/5/2026 1:09:53 PM	34.4368428	-118.6472760	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24120	6/10/2026 12:49:09 PM	34.4367935	-118.6473203	
CV-24120	6/12/2026 9:55:00 AM			Air Tech Lab
CV-24120	6/12/2026 9:55:00 AM			Air Tech Lab; [User entered 3.0%]
CV-24120	6/17/2026 1:11:35 PM	34.4368367	-118.6472905	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Plugged/Pinched Suspected;Well Comment:pump is not active;Well Condition:Lorentz Pump Installed
CV-24120	6/17/2026 1:13:40 PM	34.4368845	-118.6472888	Valve Adjustment:High O2,Plugged/Pinched Suspected;Well Comment:Pump not active;Well Condition:Lorentz Pump Installed
CV-24121	6/4/2026 8:00:00 AM			Air Tech Lab; [User entered 0.26%]
CV-24121	6/4/2026 8:00:00 AM			AirTech Lab
CV-24121	6/8/2026 1:33:03 PM	34.4369418	-118.6470040	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-24121	6/8/2026 1:35:33 PM	34.4369320	-118.6469857	Valve Adjustment:High O2,Increased Flow/Vacuum
CV-24121	6/8/2026 1:37:57 PM	34.4369540	-118.6470330	Valve Adjustment:High O2,Barely Open
CV-24121	6/17/2026 1:02:38 PM	34.4369523	-118.6470227	Valve Adjustment:Increased Flow/Vacuum;Well Comment:No pump

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24121	6/17/2026 1:03:08 PM	34.4369353	-118.6470213	
CV-24121	6/29/2026 11:25:28 AM			
CV-24121	6/29/2026 1:04:01 PM			
CV-24121	6/29/2026 1:04:44 PM			
CV-24122	6/4/2026 8:20:00 AM			AirTech Lab
CV-24122	6/4/2026 8:20:00 AM			Air Tech Lab; [User entered 0%]
CV-24122	6/5/2026 10:41:55 AM	34.4371637	-118.6466288	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24122	6/5/2026 10:43:09 AM	34.4371737	-118.6466385	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24122	6/17/2026 12:45:58 PM	34.4371492	-118.6466177	Valve Comment:valve closed upon arrival;Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum;Well Comment:No pump
CV-24122	6/17/2026 12:55:28 PM	34.4371638	-118.6466027	Valve Adjustment:NSPS/EG CAC,Barely Open,Plugged/Pinched Suspected
CV-24123	6/9/2026 2:05:21 PM	34.4373113	-118.6462235	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum
CV-24123	6/19/2026 1:07:56 PM	34.4373372	-118.6462438	Valve Adjustment:Increased Flow/Vacuum
CV-24123	6/24/2026 7:30:31 AM	34.4373087	-118.6462438	Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum
CV-24124	6/5/2026 1:18:36 PM	34.4366573	-118.6470470	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24124	6/5/2026 1:19:19 PM	34.4366553	-118.6470358	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24124	6/26/2026 8:04:01 AM	34.4366333	-118.6470297	Valve Adjustment:NSPS/EG CAI,High Temp;Well Comment:Unable to adjust safely
CV-24124	6/26/2026 8:04:44 AM	34.4366307	-118.6470372	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24125-TF	6/3/2026 8:20:00 AM			Air Tech Lab; [User entered 0.10%]
CV-24125-TF	6/3/2026 8:20:00 AM			AirTech Lab
CV-24125-TF	6/5/2026 10:14:30 AM	34.4369438	-118.6463788	Valve Adjustment:Decreased Flow/Vacuum
CV-24125-TF	6/5/2026 1:26:59 PM	34.4365852	-118.6473168	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24125-TF	6/11/2026 3:48:37 PM	34.4370960	-118.6462392	
CV-24125-TF	6/17/2026 12:29:31 PM	34.4369490	-118.6463212	Well Comment:pump is off;Well Condition:Pnumatic Pump Installed

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24125-TF	6/17/2026 12:38:33 PM	34.4369643	-118.6463417	Valve Comment:Belly in vacuum lateral;Valve Adjustment:Surging Liquid in Header;Well Comment:pump is off;Well Condition:Pnumatic Pump Installed
CV-24125-TF	6/23/2026 1:29:02 PM			
CV-24125-TF	6/23/2026 1:29:17 PM			
CV-24125-TF	6/26/2026 11:28:57 AM			
CV-24125-TF	6/26/2026 11:29:08 AM			
CV-24125-TF	6/30/2026 11:22:53 AM			
CV-24126	6/1/2026 1:39:04 PM	34.4363967	-118.6471331	Valve Adjustment:High Temp
CV-24126	6/1/2026 1:55:00 PM			AtmAA; [User entered 17.28%]
CV-24126	6/1/2026 1:55:00 PM			AtmAA
CV-24126	6/8/2026 1:09:09 PM	34.4363865	-118.6471206	Valve Adjustment:High Temp
CV-24126	6/15/2026 10:13:34 AM	34.4363949	-118.6471442	Valve Adjustment:High Temp
CV-24126	6/22/2026 1:18:00 PM	34.4363907	-118.6471342	Valve Adjustment:High Temp
CV-24126	6/26/2026 1:10:44 PM			
CV-24126	6/29/2026 1:46:26 PM	34.4363982	-118.6471295	Valve Adjustment:No Flow Measurement,High Temp
CV-24127	6/1/2026 2:39:12 PM			
CV-24127	6/2/2026 8:17:51 AM			
CV-24127	6/3/2026 8:44:10 AM			
CV-24127	6/4/2026 9:00:33 AM			
CV-24127	6/4/2026 9:10:00 AM			Air Tech Lab; [User entered 17%]
CV-24127	6/4/2026 9:10:00 AM			AirTech Lab
CV-24127	6/5/2026 12:14:23 PM			
CV-24127	6/10/2026 2:32:41 PM			
CV-24127	6/10/2026 2:33:22 PM			
CV-24127	6/12/2026 7:25:49 AM			
CV-24127	6/12/2026 8:12:32 AM	34.4364588	-118.6468187	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24127	6/12/2026 8:14:13 AM	34.4364600	-118.6468293	
CV-24127	6/15/2026 10:05:15 AM	34.4364568	-118.6468276	Valve Adjustment:No Flow Measurement,High Temp
CV-24127	6/19/2026 10:42:55 AM			
CV-24127	6/22/2026 1:16:07 PM	34.4364473	-118.6468243	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24127	6/23/2026 12:34:42 PM			
CV-24127	6/26/2026 10:26:04 AM	34.4364545	-118.6468103	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24127	6/26/2026 10:26:28 AM	34.4364572	-118.6468143	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24127	6/26/2026 11:18:15 AM			
CV-24127	6/26/2026 11:18:25 AM			
CV-24127	6/29/2026 1:43:55 PM	34.4364761	-118.6468268	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24128	6/3/2026 8:10:00 AM			Air Tech Lab; [User entered 1.0%]
CV-24128	6/3/2026 8:10:00 AM			AirTech Lab
CV-24128	6/4/2026 2:19:54 PM	34.4366888	-118.6464288	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24128	6/10/2026 12:54:14 PM	34.4367830	-118.6465117	
CV-24128	6/17/2026 1:41:36 PM	34.4366985	-118.6464300	Valve Adjustment:Reduce Sys. Vac. - Flare Down;Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24129	6/2/2026 8:22:22 AM			
CV-24129	6/4/2026 2:23:16 PM	34.4366985	-118.6461613	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24129	6/17/2026 12:18:08 PM	34.4367155	-118.6461623	Valve Adjustment:Increased Flow/Vacuum
CV-24129	6/17/2026 12:19:01 PM	34.4367157	-118.6461593	Well Comment:No pump
CV-24130	6/5/2026 9:53:23 AM	34.4368018	-118.6457102	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24131	6/5/2026 9:45:53 AM	34.4367387	-118.6450678	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24132	6/1/2026 8:49:59 AM	34.4371850	-118.6439987	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,
CV-24133	6/1/2026 9:23:18 AM	34.4374862	-118.6427522	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,
CV-24134-TF	6/1/2026 1:35:53 PM	34.4363621	-118.6465062	Valve Comment:Lorentz Pump pumping upon arrival;Valve Adjustment:No Flow Measurement,High Temp
CV-24134-TF	6/1/2026 1:50:00 PM			AtmAA; [User entered 11.59%]
CV-24134-TF	6/1/2026 1:50:00 PM			AtmAA
CV-24134-TF	6/8/2026 1:05:55 PM	34.4363625	-118.6464988	Valve Comment:Pump on;Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24134-TF	6/15/2026 10:02:38 AM	34.4363652	-118.6465103	Valve Comment:Upon arrival found pump on;Valve Adjustment:No Flow Measurement,High Temp
CV-24134-TF	6/22/2026 1:13:16 PM	34.4363666	-118.6465116	Valve Adjustment:No Flow Measurement,High Temp
CV-24134-TF	6/29/2026 1:36:41 PM	34.4363744	-118.6465005	Valve Adjustment:No Flow Measurement,High Temp
CV-24135	6/4/2026 1:50:11 PM	34.4363832	-118.6459583	Valve Adjustment:Barely Open
CV-24135	6/16/2026 9:51:38 AM			
CV-24135	6/17/2026 12:00:10 PM	34.4363788	-118.6459667	Valve Adjustment:NSPS/EG CAI,High Temp;Well Comment:No pump
CV-24135	6/17/2026 12:02:54 PM	34.4363735	-118.6459603	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-24135	6/17/2026 12:07:10 PM	34.4363823	-118.6459605	Valve Adjustment:High Temp,Decreased Flow/Vacuum

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24135	6/17/2026 12:12:01 PM	34.4363702	-118.6459597	Valve Adjustment:Increased Flow/Vacuum
CV-24135	6/17/2026 12:13:45 PM	34.4363593	-118.6459512	Valve Adjustment:High Temp
CV-24135	6/26/2026 9:05:20 AM			
CV-24135	6/30/2026 12:03:49 PM	34.4363082	-118.6459352	NSPS/EG CAI,NSPS/EG CAC,High Temp
CV-24135	6/30/2026 12:05:26 PM	34.4363965	-118.6459837	
CV-24136	6/4/2026 12:45:38 PM	34.4366523	-118.6442817	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header
CV-24136	6/4/2026 12:48:47 PM	34.4366535	-118.6442823	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24137	6/15/2026 9:10:06 AM	34.4361525	-118.6434523	Valve Adjustment:Barely Open;Well Condition:Lorentz Pump Installed
CV-24138	6/1/2026 9:23:15 AM			
CV-24138	6/1/2026 9:25:00 AM			AirTech Lab
CV-24138	6/1/2026 9:25:00 AM			AirTech Lab; [User entered 18%]
CV-24138	6/2/2026 7:36:39 AM			
CV-24138	6/3/2026 7:54:50 AM			
CV-24138	6/4/2026 3:06:11 PM			
CV-24138	6/6/2026 8:16:09 AM			
CV-24138	6/9/2026 3:28:51 PM			
CV-24138	6/9/2026 3:29:09 PM			
CV-24138	6/10/2026 8:38:31 AM	34.4342525	-118.6512742	NSPS/EG CAI,High Temp,
CV-24138	6/10/2026 8:42:15 AM	34.4342485	-118.6512347	NSPS/EG CAI,High Temp,
CV-24138	6/11/2026 10:55:56 AM	34.4342792	-118.6512456	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24138	6/16/2026 8:25:00 AM			Air Tech Lab
CV-24138	6/16/2026 8:25:00 AM			Air Tech Lab; [User entered 20%]
CV-24138	6/17/2026 8:54:02 AM	34.4342567	-118.6512508	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In)
CV-24138	6/17/2026 8:54:25 AM	34.4342618	-118.6512523	Valve Adjustment:NSPS/EG CAI,High O2,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
CV-24138	6/17/2026 1:42:39 PM	34.4342320	-118.6512521	Valve Adjustment:No Flow Measurement,High Temp
CV-24138	6/18/2026 9:36:58 AM			
CV-24138	6/19/2026 12:31:39 PM			
CV-24138	6/26/2026 9:57:18 AM	34.4342548	-118.6512585	Valve Adjustment:NSPS/EG CAI,High O2
CV-24138	6/26/2026 9:57:58 AM	34.4342480	-118.6512467	Valve Adjustment:NSPS/EG CAI,High O2
CV-24138	6/26/2026 3:55:26 PM			
CV-24138	6/26/2026 3:55:54 PM			
CV-24138	6/30/2026 1:41:18 PM			
CV-24138	6/30/2026 1:41:29 PM			

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24139	6/1/2026 9:20:00 AM			AirTech Lab
CV-24139	6/1/2026 9:20:00 AM			AirTech Lab; [User entered 0.96%]
CV-24139	6/1/2026 9:26:24 AM			
CV-24139	6/1/2026 12:37:56 PM			
CV-24139	6/2/2026 7:37:33 AM			
CV-24139	6/3/2026 7:55:49 AM			
CV-24139	6/4/2026 3:07:26 PM			
CV-24139	6/5/2026 10:54:02 AM			
CV-24139	6/6/2026 7:54:14 AM			
CV-24139	6/9/2026 3:23:00 PM			
CV-24139	6/9/2026 3:23:50 PM			
CV-24139	6/10/2026 8:49:20 AM	34.4345065	-118.6511823	NSPS/EG CAI,High O2,
CV-24139	6/10/2026 8:51:40 AM	34.4345218	-118.6511122	NSPS/EG CAI,High O2,
CV-24139	6/16/2026 8:30:00 AM			Air Tech Lab; [User entered 0.49%]
CV-24139	6/16/2026 8:30:00 AM			Air Tech Lab
CV-24139	6/17/2026 9:00:45 AM	34.4345027	-118.6511467	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-24139	6/17/2026 9:01:29 AM	34.4345030	-118.6511263	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open
CV-24139	6/18/2026 9:24:33 AM			
CV-24139	6/18/2026 9:33:37 AM			
CV-24139	6/19/2026 12:36:43 PM			
CV-24139	6/26/2026 10:05:15 AM	34.4344930	-118.6511438	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24139	6/26/2026 10:05:49 AM	34.4344930	-118.6511438	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24139	6/26/2026 3:54:38 PM			
CV-24139	6/26/2026 3:54:47 PM			
CV-24139	6/30/2026 1:47:54 PM			
CV-24139	6/30/2026 1:48:05 PM			
CV-24140	6/1/2026 9:15:00 AM			AirTech Lab; [User entered 22%]
CV-24140	6/1/2026 9:15:00 AM			AirTech Lab
CV-24140	6/1/2026 9:32:55 AM			
CV-24140	6/2/2026 7:51:34 AM			
CV-24140	6/3/2026 7:56:51 AM			
CV-24140	6/3/2026 12:47:00 PM	34.4346986	-118.6511191	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24140	6/3/2026 12:55:00 PM			AtmAA; [User entered 18.57%]
CV-24140	6/4/2026 3:08:04 PM			
CV-24140	6/5/2026 10:55:44 AM			
CV-24140	6/6/2026 8:16:54 AM			
CV-24140	6/9/2026 3:19:36 PM			
CV-24140	6/9/2026 3:19:52 PM			
CV-24140	6/10/2026 8:58:38 AM	34.4346278	-118.6510683	High Temp,NSPS/EG CAI,

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24140	6/10/2026 9:02:51 AM	34.4346242	-118.6510010	NSPS/EG CAI,High Temp,
CV-24140	6/10/2026 1:06:06 PM	34.4347046	-118.6511358	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24140	6/16/2026 8:35:00 AM			Air Tech Lab
CV-24140	6/16/2026 8:35:00 AM			Air Tech Lab; [User entered 19%]
CV-24140	6/17/2026 1:29:57 PM	34.4346741	-118.6511278	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24140	6/17/2026 1:30:23 PM	34.4346751	-118.6511257	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-24140	6/18/2026 9:34:12 AM			
CV-24140	6/18/2026 9:34:21 AM			
CV-24140	6/19/2026 12:38:35 PM			
CV-24140	6/26/2026 10:09:15 AM	34.4346572	-118.6511210	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24140	6/26/2026 10:09:34 AM	34.4346607	-118.6511180	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24140	6/26/2026 3:53:37 PM			
CV-24140	6/26/2026 3:53:50 PM			
CV-24140	6/30/2026 2:49:55 PM			
CV-24140	6/30/2026 2:50:16 PM			
CV-24141	6/11/2026 11:16:59 AM	34.4355253	-118.6513442	NSPS/EG CAI,High O2,
CV-24141	6/11/2026 11:18:59 AM	34.4354837	-118.6512965	NSPS/EG CAI,High O2,
CV-24141	6/12/2026 9:30:00 AM			Air Tech Lab; [User entered 1.2%]
CV-24141	6/12/2026 9:30:00 AM			Air Tech Lab
CV-24141	6/12/2026 10:41:06 AM	34.4354565	-118.6513000	NSPS/EG CAI,High O2,
CV-24141	6/12/2026 10:43:21 AM	34.4355305	-118.6513205	NSPS/EG CAI,High O2,
CV-24141	6/17/2026 9:19:34 AM	34.4354963	-118.6513100	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open
CV-24141	6/17/2026 9:20:54 AM	34.4355098	-118.6513263	Valve Adjustment:NSPS/EG CAI,High O2
CV-24142	6/1/2026 9:19:23 AM			
CV-24142	6/2/2026 7:52:39 AM			
CV-24142	6/3/2026 7:53:09 AM			
CV-24142	6/4/2026 9:05:00 AM			Air Tech Lab; [User entered 15%]
CV-24142	6/4/2026 9:05:00 AM			AirTech Lab
CV-24142	6/4/2026 3:04:27 PM			
CV-24142	6/5/2026 10:52:26 AM			
CV-24142	6/6/2026 7:49:57 AM			
CV-24142	6/11/2026 1:39:28 PM	34.4339890	-118.6513610	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24142	6/17/2026 8:43:53 AM	34.4339800	-118.6513618	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-24142	6/18/2026 9:43:28 AM			
CV-24142	6/18/2026 9:43:58 AM			

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24142	6/19/2026 12:27:49 PM			
CV-24142	6/26/2026 9:52:53 AM	34.4339830	-118.6513435	Valve Adjustment:NSPS/EG CAI,High Temp,Valve 100% Open
CV-24142	6/26/2026 9:53:35 AM	34.4339790	-118.6513468	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24142	6/26/2026 3:56:35 PM			
CV-24142	6/26/2026 3:56:49 PM			
CV-24142	6/30/2026 2:48:45 PM			
CV-24142	6/30/2026 2:48:56 PM			
CV-24143	6/1/2026 9:05:00 AM			AirTech Lab
CV-24143	6/1/2026 9:05:00 AM			AirTech Lab; [User entered 8.8%]
CV-24143	6/1/2026 12:34:41 PM	34.4349793	-118.6512168	Valve Adjustment:NSPS/EG CAI,High O2,Surging Liquid in Well (Watered In)
CV-24143	6/1/2026 12:36:01 PM	34.4349803	-118.6512132	
CV-24143	6/2/2026 7:50:48 AM			
CV-24143	6/6/2026 8:18:45 AM			
CV-24143	6/11/2026 1:51:00 PM	34.4332577	-118.6506863	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24143	6/12/2026 7:36:10 AM			
CV-24143	6/15/2026 2:49:28 PM	34.4350050	-118.6512238	Valve Comment:No pump in well;Valve Adjustment:No Flow Measurement,High Temp,High O2,Decreased Flow/Vacuum
CV-24143	6/15/2026 2:50:17 PM	34.4349836	-118.6512208	Valve Adjustment:No Flow Measurement,High Temp,High O2,Barely Open
CV-24143	6/16/2026 8:40:00 AM			Air Tech Lab; [User entered 19%]
CV-24143	6/16/2026 8:40:00 AM			Air Tech Lab
CV-24143	6/17/2026 9:12:04 AM	34.4349880	-118.6512123	Valve Adjustment:NSPS/EG CAC;Well Comment:No system port
CV-24143	6/19/2026 2:17:30 PM	34.4349332	-118.6511467	
CV-24143	6/19/2026 2:20:36 PM	34.4349928	-118.6512078	
CV-24143	6/23/2026 12:37:57 PM			
CV-24143	6/26/2026 2:23:39 PM			
CV-24143	6/26/2026 2:23:48 PM			
CV-24144	6/10/2026 10:15:37 AM	34.4326258	-118.6517078	No Adjustment Made
CV-24144	6/16/2026 7:55:40 AM	34.4325667	-118.6515860	Valve Adjustment:Audible Flow,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-24144	6/30/2026 1:46:16 PM	34.4325740	-118.6515727	Valve Adjustment:Valve 100% Open
CV-24145	6/9/2026 9:28:49 AM	34.4362293	-118.6496587	Valve Adjustment:Barely Open
CV-24145	6/25/2026 9:07:34 AM	34.4361908	-118.6496125	NSPS/EG CAI,High Temp,High O2
CV-24145	6/25/2026 9:10:07 AM	34.4362350	-118.6496225	NSPS/EG CAI,High O2,
CV-24145	6/25/2026 9:15:45 AM	34.4362435	-118.6496233	NSPS/EG CAC

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24146	6/8/2026 12:31:18 PM	34.4374157	-118.6463655	Valve Adjustment:NSPS/EG CAC,Orifice Plate Changed (See OP Log),Increased Flow/Vacuum
CV-24146	6/8/2026 12:36:09 PM	34.4374613	-118.6463940	Valve Adjustment:Decreased Flow/Vacuum
CV-24146	6/8/2026 12:36:53 PM	34.4374597	-118.6463870	
CV-24146	6/19/2026 1:14:29 PM	34.4374305	-118.6463823	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Valve 100% Open
CV-24146	6/19/2026 1:16:24 PM	34.4374288	-118.6463900	Valve Adjustment:Positive Static Press.
CV-24146	6/24/2026 7:32:54 AM	34.4373962	-118.6463872	Valve Comment:RES SEM;Valve Adjustment:Valve 100% Open
CV-24147	6/1/2026 7:56:42 AM	34.4375013	-118.6459423	
CV-24147	6/17/2026 9:42:16 AM	34.4375025	-118.6459685	
CV-24147	6/19/2026 1:22:48 PM	34.4375418	-118.6459713	Valve Adjustment:Increased Flow/Vacuum
CV-24148	6/3/2026 1:36:29 PM	34.4350652	-118.6466631	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24148	6/3/2026 1:37:51 PM	34.4350643	-118.6466639	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24148	6/3/2026 1:50:00 PM			AtmAA; [User entered 10.64%]
CV-24148	6/8/2026 2:26:31 PM	34.4350763	-118.6466638	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24148	6/24/2026 9:05:55 AM	34.4350554	-118.6466588	Valve Adjustment:No Flow Measurement,High Temp
CV-24148	6/30/2026 2:31:22 PM	34.4350905	-118.6466662	Valve Adjustment:No Flow Measurement,High Temp
CV-24149	6/3/2026 8:58:20 AM			
CV-24149	6/8/2026 2:11:13 PM	34.4347907	-118.6469763	
CV-24149	6/24/2026 12:42:45 PM	34.4347595	-118.6470155	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
CV-24149	6/24/2026 12:44:13 PM	34.4347677	-118.6469858	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-24149	6/24/2026 1:06:46 PM	34.4347840	-118.6470015	Valve Adjustment:Barely Open
CV-24150	6/8/2026 12:03:23 PM	34.4346228	-118.6457538	
CV-24150	6/19/2026 10:24:05 AM	34.4345848	-118.6457468	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24151	6/11/2026 9:19:01 AM	34.4344455	-118.6476570	No Flow Measurement
CV-24151	6/12/2026 11:02:29 AM	34.4344358	-118.6476032	No Flow Measurement
CV-24151	6/22/2026 9:49:24 AM	34.4344000	-118.6476017	
CV-24152	6/4/2026 8:50:55 AM	34.4344515	-118.6471620	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24152	6/4/2026 8:52:46 AM	34.4344473	-118.6471602	Valve Adjustment:NSPS/EG CAI,High Temp

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24152	6/22/2026 9:16:13 AM	34.4344580	-118.6471603	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-24152	6/22/2026 9:16:43 AM	34.4344647	-118.6471683	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24152	6/22/2026 9:17:01 AM	34.4344528	-118.6471427	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24153	6/8/2026 2:34:56 PM	34.4343820	-118.6464180	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open
CV-24153	6/8/2026 2:36:19 PM	34.4343762	-118.6463788	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-24153	6/16/2026 12:58:16 PM	34.4343948	-118.6464118	Valve Adjustment:Barely Open
CV-24154	6/4/2026 9:27:01 AM	34.4342570	-118.6460805	Valve Adjustment:Audible Flow
CV-24154	6/16/2026 5:48:54 AM	34.4342565	-118.6460773	Valve Adjustment:Decreased Flow/Vacuum
CV-24154	6/24/2026 8:27:55 AM	34.4342545	-118.6460667	Valve Comment:RES SEM
CV-24155	6/4/2026 9:16:47 AM	34.4342820	-118.6467162	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24155	6/16/2026 1:01:24 PM	34.4343055	-118.6467233	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum,Surging Liquid in Header
CV-24155	6/16/2026 1:01:57 PM	34.4343127	-118.6467268	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header
CV-24155	6/16/2026 1:02:49 PM	34.4343200	-118.6467257	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header
CV-24156	6/2/2026 3:57:37 PM	34.4340667	-118.6477213	NSPS/EG CAI,High Temp,
CV-24156	6/2/2026 4:00:44 PM	34.4340503	-118.6477538	
CV-24156	6/22/2026 10:04:13 AM	34.4340697	-118.6476973	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24156	6/22/2026 10:04:37 AM	34.4340637	-118.6476998	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24157	6/2/2026 3:51:09 PM	34.4338917	-118.6473490	
CV-24157	6/16/2026 6:16:54 AM	34.4338013	-118.6473155	Valve Adjustment:Decreased Flow/Vacuum
CV-24158	6/4/2026 12:34:30 PM	34.4338967	-118.6470798	Valve Adjustment:Decreased Flow/Vacuum
CV-24158	6/22/2026 9:54:22 AM	34.4338863	-118.6470627	Well Comment:Unable to tune safely
CV-24159	6/4/2026 8:31:58 AM	34.4337828	-118.6466325	Valve Adjustment:Audible Flow
CV-24159	6/16/2026 5:43:15 AM	34.4337795	-118.6466257	Valve Adjustment:Decreased Flow/Vacuum
CV-24160	6/4/2026 8:28:00 AM	34.4337982	-118.6462435	
CV-24160	6/16/2026 5:53:37 AM	34.4338025	-118.6462727	Valve Adjustment:Decreased Flow/Vacuum
CV-24160	6/24/2026 8:22:58 AM	34.4338108	-118.6462623	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-24161	6/8/2026 2:46:05 PM	34.4338498	-118.6456120	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24161	6/9/2026 12:29:35 PM	34.4338405	-118.6455895	Valve Comment:RES SEM

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24162	6/1/2026 1:17:47 PM			
CV-24162	6/2/2026 9:08:14 AM			
CV-24162	6/2/2026 9:08:14 AM			
CV-24162	6/2/2026 9:08:14 AM			
CV-24162	6/3/2026 8:33:29 AM	34.4335602	-118.6451087	Valve Adjustment:Barely Open
CV-24162	6/3/2026 9:23:01 AM			
CV-24162	6/4/2026 8:15:24 AM			
CV-24162	6/5/2026 1:38:35 PM			
CV-24162	6/6/2026 8:26:15 AM			
CV-24162	6/8/2026 3:24:54 PM			
CV-24162	6/8/2026 3:27:01 PM			
CV-24162	6/8/2026 3:28:04 PM			
CV-24162	6/19/2026 11:45:45 AM			
CV-24162	6/23/2026 2:28:37 PM			
CV-24162	6/23/2026 2:28:46 PM			
CV-24163	6/2/2026 1:04:07 PM	34.4334395	-118.6444847	Valve Adjustment:NSPS/EG CAC,Increased Flow/Vacuum,Barely Open
CV-24163	6/2/2026 1:04:55 PM	34.4334468	-118.6444965	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-24164	6/3/2026 2:50:38 PM	34.4334905	-118.6479643	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24164	6/16/2026 10:15:41 AM	34.4334915	-118.6479637	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-24164	6/16/2026 10:16:45 AM	34.4334887	-118.6479697	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24165	6/2/2026 2:39:55 PM	34.4335533	-118.6472235	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24165	6/22/2026 1:17:09 PM	34.4335452	-118.6472483	Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24166	6/2/2026 10:42:56 AM	34.4336010	-118.6468883	Valve Adjustment:Decreased Flow/Vacuum
CV-24166	6/16/2026 5:40:44 AM	34.4335838	-118.6468792	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-24167	6/11/2026 8:37:37 AM	34.4334533	-118.6465137	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24167	6/22/2026 1:02:56 PM	34.4335382	-118.6464898	Well Condition:Lorentz Pump Installed
CV-24168	6/2/2026 2:31:57 PM	34.4333267	-118.6473263	Valve Adjustment:Decreased Flow/Vacuum
CV-24168	6/16/2026 6:07:33 AM	34.4333068	-118.6473412	Valve Adjustment:Decreased Flow/Vacuum
CV-24169	6/2/2026 2:27:55 PM	34.4332422	-118.6476995	Valve Adjustment:Barely Open
CV-24169	6/3/2026 10:21:30 AM			
CV-24169	6/16/2026 10:26:18 AM	34.4332150	-118.6477280	
CV-24170	6/3/2026 8:39:31 AM	34.4331015	-118.6485038	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24170	6/3/2026 8:40:16 AM	34.4331200	-118.6485172	Valve Adjustment:NSPS/EG CAC,High Temp,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-24170	6/16/2026 9:47:43 AM	34.4331198	-118.6485007	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24170	6/16/2026 9:48:20 AM	34.4331212	-118.6485183	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24171	6/2/2026 1:07:59 PM	34.4331530	-118.6466352	Valve Comment:Well too tall for system read
CV-24171	6/19/2026 1:15:27 PM	34.4331722	-118.6466507	
CV-24172	6/2/2026 2:04:51 PM	34.4329878	-118.6472978	Valve Adjustment:Barely Open
CV-24172	6/19/2026 1:40:24 PM	34.4330062	-118.6472963	
CV-24173	6/2/2026 2:09:46 PM	34.4329072	-118.6476532	Well Comment:well too tall for system read
CV-24173	6/19/2026 1:42:31 PM	34.4328973	-118.6476687	Well Condition:Fair
CV-24174	6/11/2026 8:53:10 AM	34.4327227	-118.6480513	Valve Adjustment:Surging Liquid in Header
CV-24174	6/22/2026 8:34:05 AM	34.4327362	-118.6480590	Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24175	6/2/2026 2:16:56 PM	34.4326493	-118.6484578	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24175	6/19/2026 1:53:40 PM	34.4326857	-118.6484703	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24175	6/22/2026 8:43:24 AM	34.4326508	-118.6484873	Valve Adjustment:Decreased Flow/Vacuum;Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24175	6/22/2026 9:19:56 AM	34.4326660	-118.6484700	Well Condition:Lorentz Pump Installed
CV-24176	6/1/2026 11:10:13 AM	34.4326050	-118.6488437	
CV-24176	6/1/2026 11:12:09 AM	34.4326222	-118.6488967	
CV-24176	6/24/2026 12:52:18 PM	34.4325988	-118.6488930	Valve Adjustment:Barely Open,Reduce Sys. Vac. - Flare Down
CV-24177	6/2/2026 9:39:48 AM	34.4322630	-118.6494507	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-24177	6/2/2026 9:40:38 AM	34.4322570	-118.6494473	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open
CV-24177	6/16/2026 8:58:44 AM	34.4322465	-118.6494458	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open
CV-24177	6/16/2026 9:02:31 AM	34.4322580	-118.6494413	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open
CV-24177	6/25/2026 2:15:12 PM	34.4322617	-118.6494185	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Valve 100% Open,Barely Open;Well Condition:Lorentz Pump Installed
CV-24177	6/25/2026 2:18:20 PM	34.4322655	-118.6494430	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24178	6/1/2026 11:20:23 AM	34.4323615	-118.6486043	

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24178	6/22/2026 9:49:05 AM	34.4323770	-118.6485917	Valve Adjustment:NSPS/EG CAI,High O2;Well Comment:no pump
CV-24178	6/22/2026 9:57:54 AM	34.4323810	-118.6485877	Valve Comment:valve closed upon arrival;Valve Adjustment:NSPS/EG CAC,Increased Flow/Vacuum;Well Comment:Corrected air intrusion through lorentz fittings
CV-24178	6/22/2026 9:59:40 AM	34.4323815	-118.6485618	
CV-24179	6/1/2026 11:02:27 AM	34.4321008	-118.6492408	
CV-24179	6/22/2026 10:33:02 AM	34.4320857	-118.6491982	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24179	6/22/2026 10:34:07 AM	34.4320723	-118.6491747	
CV-24180	6/9/2026 2:18:49 PM			
CV-24180	6/9/2026 2:19:23 PM			
CV-24180	6/15/2026 2:02:30 PM	34.4322918	-118.6489225	
CV-24180	6/18/2026 2:51:11 PM			
CV-24180	6/18/2026 2:51:21 PM			
CV-24180	6/22/2026 10:24:27 AM	34.4321468	-118.6487817	Well Condition:Pnumatic Pump Installed
CV-24180	6/30/2026 2:57:39 PM			
CV-24180	6/30/2026 2:57:51 PM			
CV-24181	6/1/2026 3:15:10 PM	34.4321657	-118.6483575	
CV-24181	6/17/2026 1:10:56 PM	34.4321813	-118.6483902	Valve Adjustment:Decreased Flow/Vacuum
CV-24182	6/1/2026 3:27:50 PM	34.4322557	-118.6481187	
CV-24182	6/17/2026 1:26:50 PM	34.4322612	-118.6480637	
CV-24183	6/1/2026 3:31:15 PM	34.4323135	-118.6476143	
CV-24183	6/17/2026 1:29:18 PM	34.4323540	-118.6476618	Valve Adjustment:Barely Open
CV-24184	6/1/2026 12:51:50 PM	34.4325875	-118.6472833	
CV-24184	6/17/2026 1:31:52 PM	34.4325203	-118.6472775	Valve Adjustment:Barely Open
CV-24185	6/8/2026 3:06:30 PM	34.4326822	-118.6469627	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24185	6/8/2026 3:09:02 PM	34.4326678	-118.6469265	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24185	6/17/2026 12:50:10 PM	34.4326743	-118.6469343	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24186	6/8/2026 2:54:43 PM	34.4328317	-118.6465560	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24186	6/22/2026 12:55:19 PM	34.4328548	-118.6465293	
CV-24187	6/8/2026 1:08:58 PM	34.4318713	-118.6495793	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24187	6/16/2026 8:29:13 AM	34.4318660	-118.6495827	Valve Adjustment:Audible Flow,Barely Open
CV-24188	6/8/2026 12:56:31 PM	34.4315128	-118.6501158	Valve Adjustment:Decreased Flow/Vacuum
CV-24188	6/16/2026 8:43:18 AM	34.4315295	-118.6501023	Valve Adjustment:Increased Flow/Vacuum
CV-24189	6/8/2026 12:53:01 PM	34.4313270	-118.6500097	Valve Adjustment:Decreased Flow/Vacuum

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24189	6/16/2026 8:39:57 AM	34.4313103	-118.6500127	Valve Adjustment:Decreased Flow/Vacuum
CV-24190	6/8/2026 1:11:34 PM	34.4315927	-118.6494833	
CV-24190	6/16/2026 8:31:35 AM	34.4316120	-118.6494705	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-24192	6/8/2026 1:14:16 PM	34.4313392	-118.6495003	Valve Adjustment:Increased Flow/Vacuum
CV-24192	6/16/2026 8:33:52 AM	34.4313405	-118.6494997	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-24193	6/1/2026 10:14:52 AM	34.4314303	-118.6490102	
CV-24193	6/17/2026 11:31:31 AM	34.4315130	-118.6490653	Valve Adjustment:Audible Flow
CV-24194	6/1/2026 3:11:56 PM	34.4317485	-118.6484263	
CV-24194	6/17/2026 1:13:48 PM	34.4318612	-118.6485138	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24195	6/1/2026 3:04:18 PM	34.4317660	-118.6478908	
CV-24195	6/17/2026 1:18:31 PM	34.4318335	-118.6478872	
CV-24196	6/1/2026 2:55:48 PM	34.4320615	-118.6470943	
CV-24196	6/17/2026 12:42:15 PM	34.4320698	-118.6471782	Valve Adjustment:Decreased Flow/Vacuum
CV-24197	6/11/2026 8:52:25 AM	34.4324500	-118.6465275	No Adjustment Made
CV-24197	6/11/2026 11:07:01 AM	34.4323522	-118.6465947	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:well too tall for system read ground in unstable
CV-24197	6/22/2026 12:45:39 PM	34.4323963	-118.6465783	Well Condition:Lorentz Pump Installed
CV-24198	6/1/2026 3:50:01 PM	34.4315727	-118.6476963	
CV-24198	6/19/2026 2:48:23 PM	34.4315915	-118.6476735	
CV-24199	6/1/2026 3:48:00 PM	34.4316553	-118.6475325	
CV-24199	6/19/2026 2:44:55 PM	34.4316948	-118.6472970	
CV-24200	6/11/2026 8:43:17 AM	34.4314460	-118.6471643	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,
CV-24200	6/11/2026 10:41:55 AM	34.4314110	-118.6471887	
CV-24200	6/25/2026 8:22:40 AM	34.4314438	-118.6472675	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,
CV-24201	6/2/2026 9:25:14 AM			
CV-24201	6/3/2026 9:35:53 AM			
CV-24201	6/3/2026 12:17:20 PM	34.4317762	-118.6466285	Valve Adjustment:Barely Open
CV-24201	6/4/2026 7:58:40 AM			
CV-24201	6/5/2026 1:51:11 PM			
CV-24201	6/8/2026 3:58:23 PM			
CV-24201	6/8/2026 3:58:35 PM			
CV-24201	6/19/2026 12:17:46 PM			
CV-24201	6/19/2026 3:58:50 PM	34.4316585	-118.6465790	
CV-24201	6/25/2026 1:06:00 PM			

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24201	6/25/2026 1:07:09 PM			
CV-24201	6/30/2026 11:53:07 AM			
CV-24201	6/30/2026 11:53:19 AM			
CV-24202	6/1/2026 1:30:01 PM			
CV-24202	6/2/2026 9:22:52 AM			
CV-24202	6/3/2026 9:33:49 AM			
CV-24202	6/3/2026 12:11:54 PM	34.4319632	-118.6462513	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-24202	6/4/2026 8:00:54 AM			
CV-24202	6/5/2026 1:49:56 PM			
CV-24202	6/6/2026 9:00:38 AM			
CV-24202	6/8/2026 3:53:11 PM			
CV-24202	6/8/2026 3:53:58 PM			
CV-24202	6/19/2026 12:15:01 PM			
CV-24202	6/19/2026 4:05:22 PM	34.4321850	-118.6462783	
CV-24202	6/23/2026 2:02:54 PM			
CV-24202	6/23/2026 2:03:14 PM			
CV-24202	6/25/2026 1:11:49 PM			
CV-24202	6/25/2026 1:12:25 PM			
CV-24202	6/30/2026 11:49:07 AM			
CV-24202	6/30/2026 11:49:41 AM			
CV-24203	6/8/2026 3:43:07 PM	34.4314868	-118.6460148	
CV-24203	6/25/2026 8:03:43 AM	34.4315810	-118.6459780	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,Audible Flow
CV-24204	6/8/2026 3:40:01 PM	34.4314963	-118.6462910	
CV-24204	6/21/2026 3:11:11 PM	34.4314258	-118.6462503	Valve Adjustment:Increased Flow/Vacuum
CV-24204	6/21/2026 3:14:13 PM	34.4314372	-118.6462527	
CV-24204	6/30/2026 2:20:08 PM	34.4314280	-118.6462613	Valve Adjustment:Increased Flow/Vacuum
CV-24205	6/8/2026 3:36:44 PM	34.4312705	-118.6464633	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,
CV-24205	6/25/2026 8:09:37 AM	34.4312617	-118.6464823	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,
CV-24206	6/2/2026 9:26:41 AM			
CV-24206	6/3/2026 12:20:11 PM	34.4315283	-118.6467882	Valve Adjustment:Decreased Flow/Vacuum
CV-24206	6/22/2026 1:51:33 PM	34.4315640	-118.6467893	
CV-24206	6/26/2026 8:44:38 AM	34.4315217	-118.6467762	
CV-24207	6/2/2026 10:50:32 AM	34.4332587	-118.6469503	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24207	6/2/2026 10:51:16 AM	34.4332673	-118.6469275	Valve Adjustment:High Temp,Barely Open;Well Condition:Lorentz Pump Installed
CV-24207	6/16/2026 6:00:05 AM	34.4332858	-118.6469203	Valve Adjustment:Barely Open

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24208	6/10/2026 1:52:08 PM	34.4319157	-118.6451237	Valve Adjustment:Decreased Flow/Vacuum
CV-24209	6/1/2026 1:25:40 PM			
CV-24209	6/2/2026 9:17:37 AM			
CV-24209	6/3/2026 9:31:39 AM			
CV-24209	6/3/2026 12:05:12 PM	34.4321940	-118.6456063	Valve Adjustment:Barely Open
CV-24209	6/4/2026 8:06:47 AM			
CV-24209	6/5/2026 1:48:24 PM			
CV-24209	6/6/2026 8:57:15 AM			
CV-24209	6/8/2026 3:47:47 PM			
CV-24209	6/8/2026 3:48:01 PM			
CV-24209	6/19/2026 12:11:29 PM			
CV-24209	6/25/2026 1:20:57 PM			
CV-24209	6/25/2026 1:21:08 PM			
CV-24209	6/30/2026 11:43:59 AM			
CV-24209	6/30/2026 11:44:09 AM			
CV-24210	6/1/2026 1:12:24 PM			
CV-24210	6/2/2026 9:13:48 AM			
CV-24210	6/3/2026 8:51:28 AM	34.4326357	-118.6455838	Valve Adjustment:Barely Open
CV-24210	6/3/2026 9:26:21 AM			
CV-24210	6/4/2026 8:10:19 AM			
CV-24210	6/5/2026 1:43:34 PM			
CV-24210	6/6/2026 8:15:32 AM			
CV-24210	6/6/2026 8:17:27 AM			
CV-24210	6/8/2026 3:40:45 PM			
CV-24210	6/8/2026 3:41:19 PM			
CV-24210	6/9/2026 12:38:28 PM	34.4326440	-118.6455903	Valve Comment:RES SEM
CV-24210	6/19/2026 11:49:20 AM			
CV-24210	6/24/2026 11:15:44 AM			
CV-24210	6/24/2026 11:15:53 AM			
CV-24210	6/25/2026 2:20:19 PM			
CV-24210	6/25/2026 2:20:28 PM			
CV-24210	6/29/2026 2:30:23 PM			
CV-24210	6/29/2026 2:30:33 PM			
CV-24211	6/15/2026 9:54:59 AM	34.4327185	-118.6438507	Valve Adjustment:Decreased Flow/Vacuum
CV-24212	6/15/2026 9:59:21 AM	34.4331592	-118.6430762	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24212	6/15/2026 10:00:53 AM	34.4331638	-118.6430642	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24212	6/15/2026 10:02:09 AM	34.4331560	-118.6430717	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24213	6/8/2026 10:52:13 AM	34.4366122	-118.6430052	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24214	6/8/2026 10:30:06 AM	34.4367597	-118.6435057	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24214	6/8/2026 11:01:06 AM	34.4368327	-118.6423643	Valve Adjustment:Decreased Flow/Vacuum
CV-24214	6/10/2026 2:15:31 PM			
CV-24214	6/10/2026 2:15:46 PM			
CV-24214	6/23/2026 11:17:53 AM			
CV-24214	6/23/2026 11:18:07 AM			
CV-24214	6/26/2026 11:12:16 AM			
CV-24214	6/26/2026 11:12:27 AM			
CV-24214	6/30/2026 11:31:15 AM			
CV-24214	6/30/2026 11:34:01 AM			
CV-24214	6/30/2026 11:34:35 AM			
CV-24215	6/24/2026 10:13:40 AM	34.4369637	-118.6448390	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24216	6/17/2026 10:42:13 AM	34.4368317	-118.6423257	Valve Adjustment:Decreased Flow/Vacuum
CV-24217	6/8/2026 11:40:15 AM	34.4359328	-118.6444812	
CV-24218	6/4/2026 7:51:47 AM			
CV-24218	6/8/2026 11:18:36 AM	34.4358917	-118.6459347	
CV-24219	6/4/2026 8:54:21 AM	34.4350943	-118.6462029	Valve Adjustment:No Flow Measurement,High Temp
CV-24219	6/11/2026 9:18:18 AM	34.4350859	-118.6462172	Valve Adjustment:No Flow Measurement,High Temp
CV-24219	6/24/2026 8:15:38 AM	34.4350868	-118.6462330	Valve Adjustment:No Flow Measurement,High Temp
CV-24220	6/2/2026 12:24:43 PM	34.4339463	-118.6439877	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-24220	6/30/2026 1:30:24 PM	34.4339545	-118.6440135	
CV-24221	6/15/2026 2:27:47 PM	34.4341207	-118.6421335	Valve Adjustment:Barely Open
CV-24222	6/15/2026 2:17:31 PM	34.4336045	-118.6420118	Well Condition:Lorentz Pump Installed
CV-24223	6/1/2026 1:47:28 PM			
CV-24223	6/15/2026 10:08:41 AM	34.4334227	-118.6425325	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24223	6/15/2026 10:09:21 AM	34.4334187	-118.6425370	Valve Adjustment:NSPS/EG CAC
CV-24224	6/2/2026 12:37:29 PM	34.4331287	-118.6448253	Valve Adjustment:Decreased Flow/Vacuum
CV-24225	6/3/2026 9:18:42 AM	34.4327108	-118.6444502	Valve Adjustment:Valve 100% Open;Well Comment:unable to apply vacuum.;Well Repairs:Valve
CV-24226	6/15/2026 9:49:42 AM	34.4325147	-118.6442788	Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Barely Open
CV-24227	6/8/2026 1:16:48 PM	34.4309713	-118.6497878	
CV-24231	6/10/2026 9:02:36 AM	34.4302737	-118.6496657	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-24236	6/1/2026 3:14:40 PM			

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-24236	6/8/2026 12:27:00 PM	34.4301113	-118.6504963	Valve Adjustment:Decreased Flow/Vacuum
CV-24237	6/1/2026 3:15:07 PM			
CV-24237	6/8/2026 12:31:50 PM	34.4306368	-118.6502345	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-24243	6/8/2026 10:28:32 AM	34.4287930	-118.6506822	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-24243	6/8/2026 10:33:20 AM	34.4287715	-118.6506692	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open
CV-24243	6/12/2026 10:56:52 AM	34.4287002	-118.6505582	
CV-24243	6/12/2026 10:58:41 AM	34.4287015	-118.6506877	
CV-24244	6/8/2026 10:22:29 AM	34.4290012	-118.6513360	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-24244	6/12/2026 10:35:49 AM	34.4289950	-118.6512900	
CV-24244	6/12/2026 10:44:49 AM	34.4289100	-118.6513880	Orifice Plate Changed (See OP Log)
CV-24244	6/30/2026 1:45:09 PM	34.4289023	-118.6513192	
CV-24245	6/8/2026 9:34:29 AM	34.4284810	-118.6501050	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
CV-24245	6/8/2026 9:34:50 AM	34.4284857	-118.6500933	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-24245	6/12/2026 1:14:59 PM	34.4284937	-118.6499892	
CV-24246	6/8/2026 9:15:06 AM	34.4287027	-118.6494593	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-24246	6/8/2026 9:30:23 AM	34.4286848	-118.6494662	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open
CV-24246	6/12/2026 1:04:39 PM	34.4286990	-118.6495418	High O2
CV-24246	6/12/2026 1:06:33 PM	34.4287122	-118.6495220	
CV-24253	6/12/2026 1:29:16 PM	34.4283907	-118.6497702	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,
CV-25	6/1/2026 9:45:46 AM	34.4370368	-118.6420642	
CV-2501	6/1/2026 10:19:00 AM	34.4313340	-118.6484443	
CV-2502	6/1/2026 10:33:03 AM	34.4308718	-118.6490885	
CV-2503	6/12/2026 3:19:21 PM	34.4312322	-118.6478012	
CV-2503	6/19/2026 11:08:35 AM	34.4312287	-118.6477458	Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Barely Open
CV-2504	6/10/2026 9:15:49 AM	34.4303962	-118.6489372	Valve Adjustment:Audible Flow,Barely Open
CV-2505	6/3/2026 12:41:55 PM	34.4308125	-118.6471905	Valve Adjustment:Barely Open
CV-2506	6/3/2026 12:48:33 PM	34.4304693	-118.6475800	Valve Adjustment:Audible Flow
CV-2507	6/3/2026 12:52:12 PM	34.4301488	-118.6481603	Valve Adjustment:Increased Flow/Vacuum
CV-2508	6/3/2026 12:55:44 PM	34.4297177	-118.6487610	Valve Adjustment:Increased Flow/Vacuum
CV-2509	6/3/2026 1:00:33 PM	34.4292738	-118.6491402	Valve Adjustment:Audible Flow
CV-2510	6/3/2026 1:06:45 PM	34.4290873	-118.6498232	Valve Adjustment:Audible Flow,Increased Flow/Vacuum

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-25100D	6/4/2026 10:51:32 AM	34.4361832	-118.6471370	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25100D	6/23/2026 10:16:56 AM	34.4361612	-118.6471332	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25100D	6/26/2026 1:29:54 PM			
CV-25100S	6/1/2026 1:32:02 PM	34.4361522	-118.6471315	Valve Adjustment:No Flow Measurement,High Temp
CV-25100S	6/1/2026 1:45:00 PM			AtmAA; [User entered 4.82%]
CV-25100S	6/1/2026 1:45:00 PM			AtmAA
CV-25100S	6/8/2026 1:43:02 PM	34.4361570	-118.6471229	Valve Adjustment:No Flow Measurement,High Temp
CV-25100S	6/15/2026 9:59:15 AM	34.4361555	-118.6471360	Valve Adjustment:No Flow Measurement,High Temp
CV-25100S	6/22/2026 1:20:12 PM	34.4361547	-118.6471343	Valve Adjustment:No Flow Measurement,High Temp
CV-25100S	6/26/2026 2:41:55 PM			
CV-25100S	6/29/2026 2:07:27 PM	34.4361660	-118.6471436	Valve Adjustment:No Flow Measurement,High Temp
CV-25101D	6/4/2026 10:35:59 AM	34.4359758	-118.6467900	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25101D	6/17/2026 2:26:12 PM	34.4359878	-118.6467552	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25101D	6/19/2026 9:33:33 AM	34.4350602	-118.6459438	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25101S	6/4/2026 10:31:12 AM	34.4359733	-118.6468128	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25101S	6/17/2026 2:23:12 PM	34.4359922	-118.6467783	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25102_	6/2/2026 3:16:43 PM	34.4358023	-118.6472003	
CV-25102_	6/4/2026 10:57:28 AM	34.4357855	-118.6472237	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25102_	6/23/2026 10:22:01 AM	34.4357803	-118.6472067	Valve Adjustment:Decreased Flow/Vacuum,Valve 100% Closed,Surging Liquid in Header
CV-25102_	6/26/2026 2:44:49 PM			
CV-25103	6/4/2026 10:14:00 AM	34.4356575	-118.6466977	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25103	6/4/2026 12:49:09 PM			

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-25103	6/17/2026 2:13:33 PM	34.4356972	-118.6466522	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25104D	6/4/2026 8:21:00 AM	34.4353787	-118.6472372	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25104D	6/22/2026 2:05:56 PM	34.4353990	-118.6472398	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25104S	6/4/2026 8:24:31 AM	34.4353695	-118.6472500	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In)
CV-25104S	6/4/2026 8:25:26 AM	34.4353710	-118.6472508	
CV-25104S	6/26/2026 9:08:11 AM	34.4353600	-118.6472262	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header
CV-25104S	6/26/2026 9:09:21 AM	34.4353537	-118.6472255	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header
CV-25105D	6/17/2026 1:52:34 PM	34.4353668	-118.6467188	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25105S	6/2/2026 3:34:50 PM	34.4353773	-118.6466957	Valve Adjustment:Barely Open
CV-25105S	6/2/2026 3:42:33 PM	34.4353677	-118.6466725	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-25105S	6/2/2026 3:49:22 PM	34.4353712	-118.6467042	Valve Adjustment:High O2
CV-25105S	6/17/2026 1:58:16 PM	34.4353660	-118.6467042	Valve Adjustment:Barely Open
CV-25105S	6/22/2026 2:11:08 PM	34.4353800	-118.6472277	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25106D	6/4/2026 8:29:59 AM	34.4350408	-118.6473947	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In)
CV-25106D	6/4/2026 8:31:27 AM	34.4350527	-118.6473742	
CV-25106D	6/22/2026 2:02:06 PM	34.4350805	-118.6473950	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25106S	6/4/2026 8:34:37 AM	34.4350480	-118.6473697	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In)
CV-25106S	6/4/2026 8:36:09 AM	34.4350445	-118.6473615	
CV-25106S	6/22/2026 1:59:24 PM	34.4350587	-118.6473867	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25107D	6/3/2026 12:08:08 PM	34.4350777	-118.6459497	Valve Adjustment:Barely Open,Surging Liquid in Well (Watered In)

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-25107D	6/19/2026 9:28:30 AM	34.4350575	-118.6459595	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25107D	6/22/2026 8:39:22 AM	34.4350775	-118.6459787	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In);Well Comment:No pump
CV-25107D	6/22/2026 8:43:08 AM	34.4350547	-118.6459773	Valve Adjustment:NSPS/EG CAC
CV-25107S	6/3/2026 12:02:43 PM	34.4350597	-118.6459593	Valve Adjustment:Audible Flow
CV-25107S	6/22/2026 8:32:45 AM	34.4350578	-118.6459508	Valve Adjustment:Audible Flow
CV-2511	6/10/2026 9:06:43 AM	34.4296597	-118.6501887	Valve Adjustment:Barely Open
CV-2512	6/10/2026 9:10:28 AM	34.4292032	-118.6506253	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-2513	6/8/2026 10:06:59 AM	34.4288165	-118.6488122	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-2514	6/10/2026 3:40:54 PM	34.4297745	-118.6475517	NSPS/EG CAI,Orifice Plate Changed (See OP Log),High O2
CV-2514	6/10/2026 3:43:08 PM	34.4296025	-118.6476597	
CV-2515	6/1/2026 9:02:06 AM	34.4378080	-118.6431737	
CV-2516	6/17/2026 10:36:20 AM	34.4373958	-118.6431878	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-2517	6/1/2026 9:39:20 AM	34.4369933	-118.6420630	No Adjustment Made
CV-2518	6/1/2026 10:08:10 AM	34.4364013	-118.6414668	No Adjustment Made
CV-2519	6/15/2026 1:21:52 PM	34.4361670	-118.6420445	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-2520	6/17/2026 11:04:36 AM	34.4358662	-118.6427995	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open
CV-2520	6/17/2026 11:05:44 AM	34.4358733	-118.6427977	
CV-2521	6/25/2026 10:08:06 AM	34.4354805	-118.6430713	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2522	6/15/2026 1:15:28 PM	34.4355517	-118.6423863	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-2522	6/15/2026 1:16:43 PM	34.4355525	-118.6424037	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-2523	6/15/2026 1:00:57 PM	34.4357000	-118.6416858	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-2523	6/30/2026 2:32:51 PM			
CV-2524	6/25/2026 9:48:48 AM	34.4348150	-118.6425150	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open
CV-2524	6/25/2026 9:50:06 AM	34.4348060	-118.6425250	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-2525	6/15/2026 12:52:47 PM	34.4349995	-118.6417528	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-2526	6/15/2026 12:48:53 PM	34.4345318	-118.6415965	Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Barely Open

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-2527	6/22/2026 2:39:55 PM	34.4340993	-118.6428662	Valve Adjustment:High Temp
CV-2528	6/15/2026 10:47:39 AM	34.4337903	-118.6412642	No Adjustment Made
CV-2528	6/30/2026 9:56:37 AM			
CV-2529	6/1/2026 10:23:26 AM			
CV-2529	6/2/2026 9:42:05 AM			
CV-2529	6/3/2026 9:44:04 AM			
CV-2529	6/4/2026 7:16:01 AM			
CV-2529	6/5/2026 11:28:41 AM			
CV-2529	6/6/2026 9:54:57 AM			
CV-2529	6/8/2026 3:03:59 PM			
CV-2529	6/8/2026 3:04:24 PM			
CV-2529	6/10/2026 2:08:49 PM	34.4331375	-118.6423385	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In)
CV-2529	6/10/2026 2:10:02 PM	34.4331300	-118.6423263	Valve Adjustment:High O2,Surging Liquid in Well (Watered In);Well Comment:pump down;Well Condition:Pnumatic Pump Installed
CV-2529	6/16/2026 11:08:28 AM			
CV-2529	6/16/2026 11:09:00 AM			
CV-2529	6/16/2026 11:09:14 AM			
CV-2529	6/16/2026 11:15:07 AM			
CV-2529	6/16/2026 11:15:57 AM			
CV-2529	6/16/2026 11:24:10 AM			
CV-2529	6/16/2026 11:24:20 AM			
CV-2529	6/24/2026 12:57:34 PM			
CV-2529	6/24/2026 12:57:52 PM			
CV-2529	6/25/2026 11:45:10 AM			
CV-2529	6/25/2026 11:45:18 AM			
CV-2529	6/25/2026 2:48:45 PM			
CV-2529	6/25/2026 3:48:38 PM	34.4331285	-118.6423317	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2529	6/29/2026 1:17:01 PM			
CV-2530	6/10/2026 2:29:19 PM	34.4327585	-118.6429370	
CV-2531	6/10/2026 2:33:42 PM	34.4325685	-118.6433377	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2532	6/1/2026 10:20:21 AM			
CV-2532	6/3/2026 9:46:27 AM			
CV-2532	6/4/2026 7:12:04 AM			
CV-2532	6/4/2026 7:13:21 AM			
CV-2532	6/5/2026 11:31:43 AM			
CV-2532	6/5/2026 11:34:11 AM			

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-2532	6/10/2026 2:36:45 PM	34.4322927	-118.6437275	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2533	6/1/2026 10:18:28 AM			
CV-2533	6/3/2026 9:48:15 AM			
CV-2533	6/4/2026 7:10:54 AM			
CV-2533	6/5/2026 11:35:17 AM			
CV-2533	6/10/2026 1:57:41 PM			
CV-2533	6/10/2026 1:57:54 PM			
CV-2533	6/10/2026 2:39:59 PM	34.4319102	-118.6441375	Valve Adjustment:Surging Liquid in Header
CV-2533	6/16/2026 11:22:47 AM			
CV-2533	6/16/2026 11:22:56 AM			
CV-2533	6/25/2026 11:36:10 AM			
CV-2533	6/25/2026 11:36:22 AM			
CV-2533	6/25/2026 3:53:17 PM			
CV-2533	6/29/2026 1:23:58 PM			
CV-2533	6/29/2026 1:24:21 PM			
CV-2534	6/10/2026 1:02:08 PM	34.4316937	-118.6444795	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-2534	6/10/2026 2:43:52 PM	34.4317013	-118.6444772	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2534	6/30/2026 2:28:25 PM	34.4316873	-118.6444790	Valve Adjustment:Increased Flow/Vacuum
CV-2535	6/3/2026 12:25:06 PM	34.4309645	-118.6469260	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-2536	6/10/2026 3:50:56 PM	34.4309225	-118.6458370	
CV-2536	6/30/2026 2:11:01 PM			
CV-2537	6/3/2026 12:36:58 PM	34.4310542	-118.6466678	Valve Adjustment:Audible Flow,Increased Flow/Vacuum;Well Comment:no system port;Well Repairs:Sample Port
CV-2537	6/30/2026 2:13:52 PM	34.4310537	-118.6466597	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-2538	6/3/2026 12:28:52 PM	34.4308308	-118.6467385	Valve Adjustment:Audible Flow
CV-2538	6/30/2026 1:21:17 PM			
CV-2539	6/1/2026 10:50:13 AM	34.4317010	-118.6491700	
CV-2539	6/17/2026 11:59:27 AM	34.4317257	-118.6492060	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-2540	6/15/2026 8:30:48 AM	34.4332857	-118.6481060	Valve Adjustment:Barely Open
CV-2540	6/16/2026 10:23:27 AM	34.4332743	-118.6481150	Valve Adjustment:Barely Open
CV-2540	6/25/2026 2:27:35 PM	34.4332610	-118.6480917	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-2540	6/25/2026 2:29:35 PM	34.4332888	-118.6481060	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-2541	6/3/2026 9:02:39 AM	34.4332573	-118.6490540	Valve Adjustment:Decreased Flow/Vacuum
CV-2541	6/16/2026 9:33:45 AM	34.4332653	-118.6490642	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open
CV-2541	6/16/2026 9:34:05 AM	34.4332657	-118.6490595	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-2542	6/3/2026 2:04:32 PM	34.4337378	-118.6471630	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2542	6/16/2026 6:19:26 AM	34.4337102	-118.6471703	
CV-2543-PLF	6/3/2026 2:32:39 PM	34.4338342	-118.6484718	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Surging Liquid in Well (Watered In)
CV-2543-PLF	6/3/2026 2:33:15 PM	34.4338362	-118.6484812	Valve Adjustment:Barely Open,Surging Liquid in Well (Watered In)
CV-2543-PLF	6/22/2026 10:17:04 AM	34.4338292	-118.6484720	Valve Adjustment:Decreased Flow/Vacuum
CV-2543-PLF	6/30/2026 11:16:12 AM			
CV-2544	6/11/2026 9:06:29 AM	34.4340107	-118.6472453	NSPS/EG CAI,High Temp,
CV-2544	6/11/2026 9:09:46 AM	34.4340363	-118.6472300	NSPS/EG CAI,High Temp,
CV-2544	6/15/2026 2:05:00 PM	34.4340249	-118.6472317	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,Increased Flow/Vacuum
CV-2544	6/15/2026 2:06:46 PM	34.4340327	-118.6472205	Valve Adjustment:No Flow Measurement
CV-2544	6/22/2026 9:59:02 AM	34.4340280	-118.6472173	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Repairs:Sample Port
CV-2544	6/22/2026 9:59:57 AM	34.4340293	-118.6472127	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2545	6/4/2026 8:37:41 AM	34.4340348	-118.6467323	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-2545	6/16/2026 2:36:50 PM			
CV-2545	6/22/2026 9:10:21 AM	34.4340225	-118.6467335	Valve Adjustment:Barely Open
CV-2546	6/4/2026 8:42:51 AM	34.4341330	-118.6469673	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open
CV-2546	6/4/2026 8:44:06 AM	34.4341365	-118.6469627	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-2546	6/16/2026 1:12:07 PM	34.4341353	-118.6469983	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-2546	6/16/2026 1:12:57 PM	34.4341370	-118.6469972	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-2546	6/16/2026 1:13:54 PM	34.4341320	-118.6469948	Valve Adjustment:NSPS/EG CAI,High Temp

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-2546	6/18/2026 8:47:47 AM			
CV-2547	6/4/2026 9:30:40 AM	34.4339212	-118.6459883	Valve Adjustment:Audible Flow
CV-2547	6/16/2026 5:51:22 AM	34.4339417	-118.6459822	Valve Adjustment:Decreased Flow/Vacuum
CV-2547	6/16/2026 2:07:20 PM			
CV-2547	6/24/2026 8:12:57 AM	34.4339077	-118.6459840	Valve Comment:RES SEM
CV-2548	6/2/2026 9:12:35 AM	34.4343422	-118.6455922	Valve Comment:Changed OP from 0.75 to 0.50;Valve Adjustment:Orifice Plate Changed (See OP Log),Audible Flow,Decreased Flow/Vacuum,Surging Liquid in Header
CV-2548	6/2/2026 9:15:21 AM	34.4343358	-118.6455822	Valve Adjustment:Audible Flow,Surging Liquid in Header
CV-2548	6/16/2026 12:50:07 PM	34.4343292	-118.6455938	Valve Adjustment:Barely Open
CV-2548	6/26/2026 12:39:55 PM	34.4343705	-118.6455743	Valve Adjustment:Audible Flow,Barely Open
CV-2549	6/2/2026 8:57:57 AM	34.4343643	-118.6452738	Valve Comment:Changed OP from 0.75 to 1.00;Valve Adjustment:Orifice Plate Changed (See OP Log),Audible Flow,Increased Flow/Vacuum
CV-2549	6/2/2026 9:04:56 AM	34.4343843	-118.6452677	Valve Adjustment:Audible Flow
CV-2549	6/9/2026 12:21:15 PM	34.4343658	-118.6452627	Valve Comment:RES SEM
CV-2549	6/16/2026 12:47:49 PM	34.4343623	-118.6452773	Valve Adjustment:Audible Flow,Barely Open
CV-2550	6/1/2026 8:25:41 AM			
CV-2550	6/4/2026 9:26:24 AM	34.4348194	-118.6461789	Valve Adjustment:No Flow Measurement,High Temp
CV-2550	6/10/2026 2:34:19 PM	34.4348288	-118.6461683	Valve Adjustment:No Flow Measurement,High Temp
CV-2550	6/24/2026 8:52:00 AM	34.4348090	-118.6461531	Valve Adjustment:No Flow Measurement,High Temp
CV-2550	6/30/2026 2:56:33 PM	34.4348286	-118.6461747	Valve Adjustment:No Flow Measurement,High Temp
CV-2551	6/1/2026 3:18:11 PM			
CV-2551	6/2/2026 8:54:03 AM			
CV-2551	6/3/2026 9:17:33 AM	34.4349340	-118.6458155	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-2551	6/3/2026 9:19:09 AM	34.4349360	-118.6458037	Well Condition:Pnumatic Pump Installed
CV-2551	6/3/2026 1:49:46 PM	34.4349249	-118.6458237	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-2551	6/3/2026 1:50:17 PM	34.4349184	-118.6458177	Valve Adjustment:No Flow Measurement,High Temp
CV-2551	6/3/2026 2:00:00 PM			AtmAA; [User entered 7.8%]
CV-2551	6/6/2026 8:46:46 AM			
CV-2551	6/10/2026 12:12:00 PM			
CV-2551	6/10/2026 12:15:52 PM			
CV-2551	6/11/2026 9:12:16 AM	34.4349240	-118.6458371	Valve Adjustment:Audible Flow,No Flow Measurement,High Temp

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-2551	6/19/2026 9:39:01 AM	34.4349125	-118.6458052	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed
CV-2551	6/24/2026 8:07:19 AM	34.4349177	-118.6458386	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-2551	6/24/2026 8:08:01 AM	34.4349167	-118.6458370	Valve Adjustment:No Flow Measurement,High Temp
CV-2551	6/25/2026 2:42:00 PM			
CV-2551	6/25/2026 2:42:47 PM			
CV-2551	6/30/2026 2:36:17 PM			
CV-2551	6/30/2026 2:36:35 PM			
CV-2552	6/8/2026 2:06:27 PM	34.4348772	-118.6465343	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:no hands for turning
CV-2552	6/19/2026 9:47:25 AM	34.4346203	-118.6453553	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2552	6/25/2026 7:28:45 AM			
CV-2553	6/3/2026 2:22:58 PM	34.4341757	-118.6489205	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2553	6/16/2026 10:11:11 AM	34.4341747	-118.6489242	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-2553	6/17/2026 7:56:00 AM			
CV-2553	6/19/2026 11:27:02 AM	34.4340778	-118.6489307	
CV-2554	6/3/2026 1:14:29 PM	34.4344720	-118.6482482	Valve Adjustment:No Flow Measurement,High Temp
CV-2554	6/3/2026 1:15:00 PM			AtmAA; [User entered 8.05%]
CV-2554	6/9/2026 2:23:37 PM	34.4344569	-118.6482466	Valve Adjustment:No Flow Measurement,High Temp
CV-2554	6/16/2026 2:24:38 PM	34.4344802	-118.6482734	Valve Adjustment:No Flow Measurement,High Temp
CV-2554	6/24/2026 9:50:14 AM	34.4344859	-118.6482612	Valve Adjustment:No Flow Measurement,High Temp
CV-2555	6/10/2026 10:09:34 AM	34.4348213	-118.6477250	Valve Adjustment:Barely Open,Surging Liquid in Well (Watered In)
CV-2555	6/22/2026 1:53:55 PM	34.4348378	-118.6476952	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-2556	6/1/2026 3:24:57 PM			
CV-2556	6/3/2026 1:25:38 PM	34.4351547	-118.6472269	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2556	6/3/2026 1:35:00 PM			AtmAA; [User entered 11.075%]

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-2556	6/10/2026 2:21:23 PM	34.4351563	-118.6472295	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2556	6/24/2026 9:12:42 AM	34.4351568	-118.6472233	Valve Adjustment:No Flow Measurement,High Temp
CV-2556	6/30/2026 2:15:00 PM	34.4351811	-118.6472230	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2557	6/4/2026 9:59:27 AM	34.4354943	-118.6464610	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:Valve damaged
CV-2557	6/4/2026 12:47:58 PM			
CV-2557	6/17/2026 2:02:18 PM	34.4354805	-118.6464452	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed
CV-2557	6/25/2026 2:51:14 PM			
CV-2557	6/25/2026 2:52:24 PM			
CV-2558	6/4/2026 9:08:41 AM	34.4353128	-118.6463170	Valve Comment:Active PLR;Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Closed,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2558	6/4/2026 9:11:08 AM	34.4353033	-118.6463239	Valve Adjustment:High Temp,Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2558	6/6/2026 8:51:55 AM			
CV-2558	6/11/2026 9:40:44 AM	34.4353011	-118.6463176	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Well (Watered In)
CV-2558	6/24/2026 8:24:46 AM	34.4352692	-118.6463037	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2559	6/8/2026 11:29:55 AM	34.4357670	-118.6455798	
CV-2559	6/26/2026 9:21:49 AM	34.4357507	-118.6454865	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-2559	6/26/2026 9:22:21 AM	34.4357403	-118.6454877	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2560	6/4/2026 10:17:20 AM	34.4359138	-118.6466375	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2560	6/4/2026 12:55:13 PM			
CV-2560	6/17/2026 2:19:08 PM	34.4359152	-118.6466342	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2561	6/1/2026 10:07:37 AM			

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-2561	6/4/2026 10:27:07 AM	34.4360773	-118.6466010	Valve Adjustment:Decreased Flow/Vacuum
CV-2561	6/25/2026 9:03:33 AM	34.4360688	-118.6466065	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2561	6/25/2026 9:59:59 AM	34.4360850	-118.6465058	No Flow Measurement
CV-2562	6/8/2026 11:24:32 AM	34.4361130	-118.6459428	
CV-2563	6/9/2026 2:01:53 PM	34.4372948	-118.6457938	Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum
CV-2564	6/16/2026 9:20:39 AM	34.4331313	-118.6487492	Valve Adjustment:Decreased Flow/Vacuum
CV-2565	6/1/2026 10:58:19 AM	34.4319547	-118.6491082	
CV-2565	6/17/2026 12:11:54 PM	34.4319657	-118.6489773	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum,Surging Liquid in Header
CV-2566	6/1/2026 11:25:15 AM	34.4318658	-118.6487857	
CV-2566	6/17/2026 12:05:33 PM	34.4318008	-118.6487697	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-2567	6/1/2026 10:36:31 AM			
CV-2567	6/10/2026 9:37:59 AM	34.4319695	-118.6480807	Valve Adjustment:Barely Open
CV-2567	6/17/2026 1:15:59 PM	34.4319695	-118.6480847	Valve Adjustment:Audible Flow,Barely Open
CV-2568	6/1/2026 1:04:25 PM	34.4321857	-118.6477713	
CV-2568	6/1/2026 1:06:59 PM	34.4322033	-118.6478973	
CV-2568	6/17/2026 12:38:03 PM	34.4321768	-118.6477332	Valve Adjustment:Audible Flow,Barely Open
CV-2569	6/1/2026 1:00:40 PM	34.4322742	-118.6473852	
CV-2569	6/17/2026 12:39:56 PM	34.4322255	-118.6473820	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-2570	6/1/2026 12:56:09 PM	34.4324520	-118.6471465	
CV-2570	6/17/2026 12:44:47 PM	34.4324163	-118.6469745	Valve Adjustment:Audible Flow,Barely Open
CV-2571	6/10/2026 2:50:35 PM	34.4300047	-118.6457025	
CV-2571	6/12/2026 2:05:39 PM	34.4299048	-118.6458418	Valve Adjustment:Increased Flow/Vacuum
CV-2572	6/10/2026 3:23:03 PM	34.4297995	-118.6471115	
CV-2572	6/30/2026 9:25:51 AM			
CV-48R	6/9/2026 1:59:40 PM	34.4373418	-118.6458525	Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum
CV-48R	6/19/2026 1:26:30 PM	34.4373483	-118.6458862	Valve Adjustment:Increased Flow/Vacuum
CV-52D	6/17/2026 10:56:39 AM	34.4359517	-118.6424705	Valve Comment:Valve needs to be replaced;Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-52D	6/17/2026 10:58:21 AM	34.4359470	-118.6424730	
CV-55R	6/22/2026 2:49:14 PM	34.4343863	-118.6427715	Valve Adjustment:High Temp,Increased Flow/Vacuum
CV-55R	6/22/2026 2:51:17 PM	34.4343987	-118.6427758	Valve Adjustment:High Temp

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
CV-56D	6/3/2026 9:46:56 AM	34.4337872	-118.6431808	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-56D	6/3/2026 9:48:21 AM	34.4337812	-118.6431752	Valve Adjustment:NSPS/EG CAI,High O2
CV-56D	6/4/2026 11:45:39 AM	34.4338092	-118.6432033	Valve Adjustment:NSPS/EG CAI,High O2,Valve 100% Closed
CV-56D	6/4/2026 11:48:11 AM	34.4338167	-118.6431887	Valve Adjustment:NSPS/EG CAI,High Temp,Valve 100% Closed
CV-56S	6/3/2026 9:50:43 AM	34.4337787	-118.6431772	Valve Adjustment:Decreased Flow/Vacuum
CV-56S	6/4/2026 11:53:51 AM	34.4337903	-118.6431762	Valve Adjustment:Barely Open
CV-57R	6/2/2026 12:09:58 PM	34.4343045	-118.6435875	Valve Adjustment:Increased Flow/Vacuum
CV-79R	6/2/2026 12:42:00 PM	34.4332237	-118.6448578	Valve Adjustment:Audible Flow
CV-94	6/2/2026 11:52:13 AM	34.4348615	-118.6436622	Valve Adjustment:Decreased Flow/Vacuum
CV-95	6/2/2026 12:07:10 PM	34.4342883	-118.6436078	
CV-99	6/4/2026 7:30:00 AM			Air Tech Lab; [User entered 0.15%]
CV-99	6/4/2026 7:30:00 AM			AirTech Lab
CV-99	6/5/2026 10:07:36 AM	34.4370535	-118.6463437	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-99	6/5/2026 10:08:38 AM	34.4370447	-118.6463555	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:Vale stuck open
D-02	6/23/2026 1:53:57 PM	34.4311680	-118.6442913	
D-02	6/23/2026 2:03:28 PM	34.4311655	-118.6443062	
D-03	6/26/2026 1:32:24 PM	34.4311750	-118.6443160	Valve Adjustment:Audible Flow,Increased Flow/Vacuum;Well Comment:no system port
D-04	6/10/2026 1:27:08 PM	34.4311648	-118.6443147	Valve Adjustment:Increased Flow/Vacuum
D-09	6/10/2026 3:15:14 PM	34.4301835	-118.6462578	
D-10	6/10/2026 3:05:32 PM	34.4301027	-118.6459688	High O2
D-10	6/10/2026 3:09:00 PM	34.4301777	-118.6459403	
FP-001	6/4/2026 1:35:55 PM	34.4365842	-118.6458542	Valve Adjustment:Barely Open
FP-002	6/4/2026 2:04:37 PM	34.4366198	-118.6462027	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
FP-003	6/4/2026 2:07:37 PM	34.4366250	-118.6465255	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
FP-005	6/5/2026 1:33:01 PM	34.4365007	-118.6472768	Valve Adjustment:Barely Open
FP-006	6/5/2026 1:48:45 PM	34.4363955	-118.6476483	Valve Adjustment:Barely Open
FP-008	6/5/2026 2:33:38 PM	34.4363457	-118.6481565	Valve Adjustment:Barely Open,Surging Liquid in Header
FP-009	6/2/2026 8:40:09 AM	34.4366717	-118.6489432	Valve Adjustment:Surging Liquid in Header

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
FP-010	6/2/2026 8:28:42 AM	34.4366002	-118.6492547	Valve Adjustment:Barely Open
FP-011	6/2/2026 8:25:31 AM	34.4365553	-118.6495198	Valve Adjustment:Decreased Flow/Vacuum
FP-012	6/1/2026 9:55:47 AM	34.4366680	-118.6499277	Valve Adjustment:Barely Open
FP-013	6/1/2026 1:37:28 PM	34.4365488	-118.6502717	
FP-014	6/2/2026 8:35:12 AM	34.4366022	-118.6492465	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
FP-014	6/5/2026 2:19:15 PM	34.4364903	-118.6482480	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
FP-015	6/5/2026 2:05:04 PM	34.4364515	-118.6479423	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
FP-016	6/5/2026 1:58:04 PM	34.4364900	-118.6477062	Valve Adjustment:Barely Open
FP-017	6/10/2026 9:55:02 AM	34.4343930	-118.6486595	Valve Adjustment:Surging Liquid in Header
FP-018	6/10/2026 9:47:19 AM	34.4344308	-118.6490848	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header
FP-019	6/2/2026 9:42:15 AM	34.4346530	-118.6491720	Valve Adjustment:Barely Open,Surging Liquid in Header
FP-020	6/10/2026 11:16:39 AM	34.4349208	-118.6492642	Valve Adjustment:Barely Open
FP-021	6/2/2026 9:52:46 AM	34.4351502	-118.6495818	Valve Adjustment:Decreased Flow/Vacuum
FP-022	6/10/2026 11:08:45 AM	34.4352303	-118.6491570	Valve Adjustment:Decreased Flow/Vacuum
FP-023	6/22/2026 8:10:36 AM	34.4357293	-118.6494862	Valve Adjustment:Increased Flow/Vacuum
FP-024	6/10/2026 10:40:56 AM	34.4355053	-118.6477815	Valve Adjustment:Surging Liquid in Header
FP-025	6/4/2026 9:05:18 AM	34.4353300	-118.6477797	
FP-026	6/4/2026 9:14:18 AM	34.4350572	-118.6481683	
FP-027	6/8/2026 10:54:42 AM	34.4348298	-118.6482603	
FP-028	6/8/2026 10:49:31 AM	34.4347505	-118.6484173	
FP-029	6/10/2026 9:50:32 AM	34.4343860	-118.6489108	Valve Adjustment:Surging Liquid in Header
FP-030	6/2/2026 9:25:15 AM	34.4345137	-118.6496898	Valve Adjustment:Barely Open
FP-031	6/2/2026 9:20:31 AM	34.4348065	-118.6497823	Valve Adjustment:Decreased Flow/Vacuum
FP-032	6/2/2026 9:00:20 AM	34.4350990	-118.6498585	Valve Adjustment:Decreased Flow/Vacuum
FP-033	6/2/2026 8:55:46 AM	34.4353635	-118.6499630	Valve Adjustment:Surging Liquid in Header
FP-034	6/22/2026 8:03:52 AM	34.4356033	-118.6500105	
FP-035	6/1/2026 2:23:38 PM	34.4358470	-118.6500948	Valve Adjustment:Decreased Flow/Vacuum
FP-036	6/1/2026 2:26:56 PM	34.4360745	-118.6502252	Valve Adjustment:Decreased Flow/Vacuum
FP-037	6/1/2026 2:33:31 PM	34.4362572	-118.6502877	Valve Adjustment:Barely Open

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
FP-038	6/3/2026 9:29:51 AM	34.4340505	-118.6497955	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
FP-038	6/17/2026 9:30:17 AM	34.4348370	-118.6509397	Valve Adjustment:Increased Flow/Vacuum
FP-039	6/3/2026 9:26:27 AM	34.4341548	-118.6498393	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
FP-040	6/17/2026 9:23:16 AM	34.4352990	-118.6510435	Valve Adjustment:Valve 100% Open
FP-041	6/11/2026 10:59:42 AM	34.4340398	-118.6506520	
FP-041	6/11/2026 11:01:38 AM	34.4340885	-118.6507210	NSPS/EG CAI,High O2,
FP-042	6/8/2026 1:38:09 PM	34.4332893	-118.6512872	
FP-043	6/17/2026 9:47:23 AM	34.4342380	-118.6508030	Valve Adjustment:Increased Flow/Vacuum
FP-044	6/17/2026 9:43:00 AM	34.4345305	-118.6507832	
FP-045	6/3/2026 9:07:49 AM	34.4334487	-118.6496345	Valve Adjustment:Barely Open
FP-046	6/23/2026 10:33:42 AM	34.4365688	-118.6473168	
FP-047	6/5/2026 1:13:13 PM	34.4367517	-118.6469555	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
FP-050	6/8/2026 2:03:54 PM	34.4349323	-118.6472757	
FP-051	6/8/2026 2:16:12 PM	34.4346855	-118.6469998	
FP-052	6/3/2026 2:16:47 PM	34.4342427	-118.6481205	Valve Adjustment:Barely Open
FP-053	6/3/2026 2:13:47 PM	34.4340802	-118.6477433	Valve Adjustment:Decreased Flow/Vacuum
FP-054	6/8/2026 2:29:07 PM	34.4343880	-118.6471560	
FP-055	6/3/2026 2:41:46 PM	34.4336130	-118.6481848	Valve Adjustment:Barely Open
FP-056	6/3/2026 10:06:38 AM	34.4334577	-118.6486137	Valve Adjustment:Barely Open
FP-056	6/16/2026 9:41:00 AM	34.4334600	-118.6486443	
FP-057	6/3/2026 9:08:41 AM	34.4347725	-118.6455972	
FP-058	6/3/2026 9:22:51 AM	34.4349485	-118.6458705	
FP-059	6/8/2026 12:07:12 PM	34.4346277	-118.6457993	
FP-060	6/26/2026 1:06:52 PM	34.4332223	-118.6493610	
FP-061	6/5/2026 2:08:36 PM	34.4364535	-118.6479488	Valve Adjustment:Barely Open
H-01 (EXP-0	6/12/2026 7:44:07 AM	34.4377177	-118.6441565	Valve Adjustment:Audible Flow;Well Comment:System could not be read due to open trench
H-01 (EXP-0	6/22/2026 8:10:49 AM	34.4376975	-118.6441673	
H-02 (EXP-0	6/1/2026 11:41:57 AM	34.4376937	-118.6446038	Valve Adjustment:Audible Flow
H-02 (EXP-0	6/22/2026 8:05:43 AM	34.4376915	-118.6446213	Well Repairs:Sample Port
H-03 (EXP-0	6/1/2026 11:45:13 AM	34.4377140	-118.6446577	Valve Adjustment:Audible Flow
H-03 (EXP-0	6/22/2026 7:55:26 AM	34.4377172	-118.6446292	
H-04 (EXP-0	6/1/2026 11:51:21 AM	34.4377192	-118.6447022	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
H-04 (EXP-0	6/1/2026 11:52:14 AM	34.4377338	-118.6446827	
H-04 (EXP-0	6/22/2026 7:48:41 AM	34.4376955	-118.6447483	Valve Adjustment:NSPS/EG CAI,High Temp

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
H-04 (EXP-04	6/22/2026 7:51:00 AM	34.4377152	-118.6446643	Valve Adjustment:High Temp,Increased Flow/Vacuum,Barely Open
H-04 (EXP-04	6/22/2026 7:52:34 AM	34.4377222	-118.6446890	Valve Adjustment:High Temp
H-08 (EXP-08	6/8/2026 1:06:17 PM	34.4378468	-118.6465585	
H-08 (EXP-08	6/17/2026 9:51:09 AM	34.4378288	-118.6465563	Valve Adjustment:Increased Flow/Vacuum
H-08 (EXP-08	6/17/2026 9:51:47 AM	34.4378222	-118.6465663	
H-10 (EXP-10	6/8/2026 12:48:24 PM	34.4374672	-118.6470992	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
H-10 (EXP-10	6/8/2026 12:51:23 PM	34.4374847	-118.6471120	Valve Adjustment:High Temp,Barely Open
H-10 (EXP-10	6/17/2026 9:56:40 AM	34.4374438	-118.6471210	Valve Adjustment:NSPS/EG CAC
H-10 (EXP-10	6/17/2026 9:57:40 AM	34.4374355	-118.6471355	
H-101W	6/8/2026 12:22:40 PM	34.4310860	-118.6505848	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
H-102A	6/8/2026 12:13:39 PM	34.4310950	-118.6505813	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
H-102A	6/19/2026 10:48:54 AM	34.4311035	-118.6505445	
H-1401W	6/8/2026 12:09:07 PM	34.4311073	-118.6505723	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
H-1401W	6/8/2026 12:11:06 PM	34.4311045	-118.6505897	Valve Adjustment:NSPS/EG CAC
H-1404C	6/15/2026 1:54:09 PM	34.4323582	-118.6482723	
H-1404C	6/26/2026 12:54:36 PM	34.4324322	-118.6483137	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
H-1404C	6/26/2026 12:55:41 PM	34.4324392	-118.6483178	Valve Adjustment:NSPS/EG CAC
H-1405C	6/2/2026 9:16:38 AM	34.4325853	-118.6497397	Valve Adjustment:Decreased Flow/Vacuum
H-1405C	6/16/2026 8:12:58 AM	34.4325903	-118.6497385	Valve Adjustment:Surging Liquid in Well (Watered In)
H-1406W	6/10/2026 8:42:28 AM	34.4321693	-118.6507803	Valve Adjustment:Decreased Flow/Vacuum
H-1406W	6/17/2026 8:18:32 AM	34.4321703	-118.6507767	
H-1408CR	6/12/2026 3:10:27 PM	34.4314102	-118.6475050	High Temp
H-1408CR	6/12/2026 3:12:01 PM	34.4314962	-118.6474982	
H-1408E	6/2/2026 2:36:46 PM	34.4333617	-118.6471572	Valve Adjustment:Barely Open
H-1408E	6/16/2026 6:05:06 AM	34.4333487	-118.6471588	Valve Adjustment:Barely Open
H-1408W	6/8/2026 12:44:22 PM	34.4311995	-118.6500005	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
H-1408W	6/8/2026 12:50:22 PM	34.4311948	-118.6500077	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
H-1409N	6/8/2026 3:03:33 PM	34.4328663	-118.6469530	Valve Adjustment:Decreased Flow/Vacuum
H-1409N	6/17/2026 12:54:53 PM	34.4328577	-118.6469408	Valve Adjustment:Decreased Flow/Vacuum
H-1410S	6/3/2026 12:33:58 PM	34.4309923	-118.6467047	
H-1563N	6/3/2026 9:21:39 AM	34.4338360	-118.6498255	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1563N	6/22/2026 11:47:58 AM	34.4338388	-118.6498188	Valve Adjustment:Increased Flow/Vacuum,Surging Liquid in Header

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
H-1563S	6/2/2026 9:21:26 AM	34.4323855	-118.6496568	Valve Adjustment:Barely Open
H-1563S	6/16/2026 8:15:23 AM	34.4324007	-118.6496563	Valve Adjustment:Barely Open
H-1565E	6/2/2026 2:42:34 PM	34.4335555	-118.6472340	
H-1565E	6/16/2026 6:10:30 AM	34.4335445	-118.6472323	Valve Adjustment:Decreased Flow/Vacuum
H-1568N	6/2/2026 2:34:10 PM	34.4333617	-118.6471663	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1568N	6/16/2026 6:03:23 AM	34.4333508	-118.6471688	Valve Adjustment:Decreased Flow/Vacuum
H-1571S	6/3/2026 11:57:36 AM	34.4321577	-118.6452418	
H-1572N	6/2/2026 12:49:04 PM	34.4337050	-118.6447363	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
H-1572N	6/2/2026 12:49:47 PM	34.4337015	-118.6447383	Valve Adjustment:NSPS/EG CAC
H-1572S	6/3/2026 11:52:57 AM	34.4321663	-118.6447105	Valve Adjustment:Audible Flow
H-1574N	6/10/2026 10:08:46 AM	34.4325190	-118.6517613	NSPS/EG CAI,High O2,
H-1574N	6/10/2026 10:11:13 AM	34.4325062	-118.6517108	NSPS/EG CAI,High O2,
H-1574N	6/25/2026 10:52:47 AM	34.4324777	-118.6517273	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,
H-1753N	6/2/2026 9:45:07 AM	34.4346962	-118.6493442	Valve Adjustment:Barely Open
H-1753N	6/26/2026 8:26:29 AM	34.4347222	-118.6493248	Valve Adjustment:NSPS/EG CAI,High O2,Positive Static Press.,Increased Flow/Vacuum
H-1753N	6/26/2026 8:31:04 AM	34.4347167	-118.6493258	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open
H-1753N	6/26/2026 8:34:36 AM	34.4347152	-118.6493267	Valve Adjustment:NSPS/EG CAI,High O2
H-1753S	6/3/2026 9:43:25 AM	34.4339295	-118.6495670	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1753S	6/22/2026 12:16:51 PM	34.4339270	-118.6495660	Valve Adjustment:Audible Flow,Surging Liquid in Header
H-1756S	6/2/2026 8:48:21 AM	34.4325557	-118.6503063	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
H-1756S	6/16/2026 8:02:34 AM	34.4325698	-118.6502887	Valve Adjustment:Decreased Flow/Vacuum
H-1757S	6/2/2026 9:11:24 AM	34.4327048	-118.6497748	
H-1757S	6/16/2026 8:10:28 AM	34.4327073	-118.6497830	
H-1760S	6/2/2026 2:13:24 PM	34.4327192	-118.6478835	Valve Adjustment:Decreased Flow/Vacuum
H-1760S	6/17/2026 1:01:37 PM	34.4327388	-118.6479068	Valve Adjustment:Decreased Flow/Vacuum
H-1762N	6/2/2026 10:45:08 AM	34.4334582	-118.6468805	Valve Adjustment:Barely Open
H-1762N	6/16/2026 5:57:38 AM	34.4334597	-118.6468795	Valve Adjustment:Barely Open
H-1763N	6/4/2026 8:24:17 AM	34.4335097	-118.6461837	Valve Adjustment:Barely Open
H-1763S	6/3/2026 9:06:43 AM	34.4324213	-118.6460260	
H-1764N	6/3/2026 8:45:22 AM	34.4331578	-118.6456558	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
H-1764S	6/3/2026 12:02:54 PM	34.4321883	-118.6454030	Valve Adjustment:Decreased Flow/Vacuum

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
H-1767N	6/10/2026 1:57:55 PM	34.4327118	-118.6435785	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1769N	6/1/2026 9:37:42 AM	34.4369923	-118.6494972	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1769N	6/17/2026 8:57:31 AM	34.4370118	-118.6495055	Valve Adjustment:Barely Open
H-1770N	6/1/2026 9:51:21 AM	34.4368088	-118.6500157	Valve Adjustment:Barely Open
H-1770N	6/15/2026 9:30:00 AM			Air Tech Lab; [User entered 1.2%]
H-1770N	6/15/2026 9:30:00 AM			Air Tech Lab
H-1770N	6/17/2026 9:09:18 AM	34.4367938	-118.6500443	Valve Adjustment:Barely Open,Surging Liquid in Header
H-1770S	6/2/2026 8:08:25 AM	34.4330962	-118.6501857	
H-1770S	6/16/2026 7:49:23 AM	34.4331428	-118.6501603	Valve Adjustment:Barely Open
H-1771A	6/4/2026 2:01:14 PM	34.4363370	-118.6464088	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1771B	6/4/2026 10:07:06 AM	34.4355332	-118.6466520	Valve Adjustment:Decreased Flow/Vacuum
H-1771B	6/17/2026 2:04:52 PM	34.4355365	-118.6466210	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1774N	6/1/2026 1:44:46 PM	34.4367298	-118.6507842	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1774N	6/17/2026 9:23:18 AM	34.4367108	-118.6508082	Valve Adjustment:Barely Open,Surging Liquid in Header
H-1801S	6/2/2026 12:28:57 PM	34.4337533	-118.6440943	
H-1802S	6/2/2026 12:44:59 PM	34.4335447	-118.6447300	Valve Adjustment:Increased Flow/Vacuum
H-1803N	6/1/2026 10:35:00 AM			AtmAA; [User entered 14.57%]
H-1803N	6/1/2026 10:35:00 AM			AtmAA
H-1803N	6/1/2026 10:35:20 AM	34.4370426	-118.6485870	Valve Comment:Well hard piped;Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
H-1803N	6/8/2026 9:49:51 AM	34.4370039	-118.6485968	Valve Adjustment:No Flow Measurement,High Temp
H-1803N	6/15/2026 9:16:07 AM	34.4370399	-118.6485961	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Well (Watered In)
H-1803N	6/22/2026 9:30:13 AM	34.4370360	-118.6485922	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Well (Watered In)
H-1803N	6/29/2026 9:51:07 AM	34.4370391	-118.6485918	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
H-1804B	6/8/2026 11:58:30 AM	34.4343000	-118.6456510	

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
H-1804B	6/16/2026 12:52:32 PM	34.4342613	-118.6456565	Valve Adjustment:Audible Flow
H-1804N	6/4/2026 1:46:12 PM	34.4363850	-118.6456632	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1804S	6/3/2026 8:47:55 AM	34.4330862	-118.6457153	Valve Adjustment:Increased Flow/Vacuum
H-1805A	6/3/2026 12:28:07 PM	34.4351298	-118.6450955	Valve Adjustment:Audible Flow,Barely Open
H-1805A	6/19/2026 10:10:27 AM	34.4350937	-118.6450498	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1805B	6/3/2026 8:35:39 AM	34.4337098	-118.6451627	
H-1805S	6/3/2026 8:58:45 AM	34.4329100	-118.6451633	Valve Adjustment:Increased Flow/Vacuum
H-1806A	6/8/2026 11:47:40 AM	34.4354063	-118.6441673	
H-1806B	6/2/2026 12:54:05 PM	34.4338955	-118.6444688	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
H-1806B	6/2/2026 12:56:02 PM	34.4338927	-118.6444607	Valve Adjustment:NSPS/EG CAC
H-1806N	6/8/2026 10:18:36 AM	34.4363763	-118.6443083	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header
H-1806S	6/3/2026 9:15:06 AM	34.4328805	-118.6444572	Valve Adjustment:Decreased Flow/Vacuum
H-1807A	6/2/2026 11:48:10 AM	34.4353215	-118.6436223	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
H-1807N	6/8/2026 10:40:50 AM	34.4364665	-118.6435342	Valve Adjustment:Barely Open,Surging Liquid in Header
H-1807S	6/2/2026 12:21:01 PM	34.4338048	-118.6434823	Valve Adjustment:Decreased Flow/Vacuum
H-1952S	6/3/2026 2:08:31 PM	34.4338345	-118.6476128	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1952S	6/3/2026 2:09:49 PM	34.4338217	-118.6476033	Valve Adjustment:Barely Open
H-1952S	6/16/2026 6:13:44 AM	34.4338242	-118.6476208	Valve Adjustment:Increased Flow/Vacuum,Barely Open
H-1955C	6/3/2026 12:19:34 PM	34.4350373	-118.6453853	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
H-1955C	6/19/2026 10:16:23 AM	34.4350237	-118.6453875	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1955N	6/4/2026 1:43:34 PM	34.4364875	-118.6454982	Valve Adjustment:Barely Open
H-1956B	6/3/2026 8:18:31 AM	34.4342647	-118.6447690	
H-1956B	6/9/2026 11:39:37 AM	34.4342860	-118.6447797	Valve Comment:RES SEM
H-1956N	6/8/2026 10:12:46 AM	34.4364690	-118.6449217	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1956S	6/2/2026 12:40:22 PM	34.4331795	-118.6448830	Valve Adjustment:Decreased Flow/Vacuum
H-1957B	6/2/2026 11:59:17 AM	34.4345300	-118.6441160	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
H-1957N	6/8/2026 10:21:49 AM	34.4364485	-118.6442205	Valve Adjustment:Increased Flow/Vacuum,Surging Liquid in Header

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
H-1957S	6/2/2026 12:31:09 PM	34.4337598	-118.6441098	
H-1958C	6/2/2026 11:45:15 AM	34.4353527	-118.6434690	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
H-1958C	6/9/2026 11:32:42 AM	34.4353815	-118.6434612	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum
H-1958N	6/8/2026 10:36:31 AM	34.4364587	-118.6435038	Valve Adjustment:Decreased Flow/Vacuum
H-1958S	6/18/2026 2:13:22 PM	34.4339973	-118.6433297	Valve Adjustment:No Flow Measurement
H-1958S	6/18/2026 2:17:07 PM	34.4340147	-118.6433340	Valve Adjustment:Increased Flow/Vacuum
H-1962N	6/1/2026 1:28:34 PM	34.4366965	-118.6501433	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Surging Liquid in Well (Watered In)
H-1962N	6/1/2026 1:34:46 PM	34.4366580	-118.6501517	Valve Adjustment:High O2,Surging Liquid in Well (Watered In)
H-1962N	6/5/2026 9:09:10 AM	34.4366652	-118.6501348	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
H-1962N	6/17/2026 9:12:30 AM	34.4366623	-118.6501525	Valve Adjustment:Barely Open,Surging Liquid in Well (Watered In)
H-1963N	6/1/2026 9:34:55 AM	34.4369280	-118.6495560	Valve Adjustment:High Temp,Barely Open
H-1963N	6/17/2026 8:54:38 AM	34.4368882	-118.6495542	Valve Adjustment:Barely Open
H-1963N	6/17/2026 12:20:47 PM	34.4369225	-118.6495585	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
H-1963N	6/17/2026 12:21:03 PM	34.4369225	-118.6495600	Valve Adjustment:NSPS/EG CAI,High Temp
H-1966N	6/1/2026 1:55:09 PM	34.4365423	-118.6508223	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1966N	6/22/2026 10:30:50 AM	34.4365412	-118.6507863	Valve Adjustment:Barely Open
H-1967E	6/10/2026 2:54:38 PM	34.4302248	-118.6459358	High O2
H-1967E	6/10/2026 2:55:55 PM	34.4302100	-118.6458487	
H-1967W	6/8/2026 11:55:13 AM	34.4299310	-118.6508508	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
H-2050E	6/11/2026 12:37:27 PM	34.4293080	-118.6475545	
H-2050W	6/3/2026 12:58:46 PM	34.4291302	-118.6491028	Valve Adjustment:Barely Open
H-2051W	6/8/2026 11:47:12 AM	34.4299247	-118.6508250	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
H-2053E	6/10/2026 3:02:37 PM	34.4302470	-118.6459112	
H-2053W	6/8/2026 12:17:00 PM	34.4310888	-118.6505747	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
H-2055E	6/3/2026 12:15:20 PM	34.4317788	-118.6465987	Valve Adjustment:Decreased Flow/Vacuum
H-2055E	6/19/2026 4:01:38 PM	34.4316842	-118.6466263	
H-2056B	6/10/2026 3:26:06 PM	34.4297165	-118.6475258	
H-2056W	6/8/2026 11:51:53 AM	34.4299305	-118.6508232	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
H-2057E	6/10/2026 2:59:49 PM	34.4301902	-118.6459405	
H-2057W	6/8/2026 11:59:37 AM	34.4306720	-118.6506528	Valve Adjustment:Decreased Flow/Vacuum

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
H-2057W	6/8/2026 12:01:57 PM	34.4306642	-118.6506393	
H-2058E	6/10/2026 3:18:13 PM	34.4300308	-118.6465095	
H-2058W	6/8/2026 11:49:40 AM	34.4299213	-118.6508190	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
H-2059E	6/25/2026 7:45:33 AM	34.4306708	-118.6462720	No Adjustment Made
H-2059W	6/8/2026 12:39:30 PM	34.4310882	-118.6502345	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
H-2161E	6/25/2026 7:39:50 AM	34.4308177	-118.6465570	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,Audible Flow
H-2161W	6/8/2026 12:36:22 PM	34.4309475	-118.6502245	Valve Adjustment:Decreased Flow/Vacuum
H-2163C	6/1/2026 10:28:26 AM	34.4311125	-118.6486170	
H-2163C	6/17/2026 11:36:55 AM	34.4311023	-118.6486750	Valve Adjustment:Audible Flow,Barely Open
H-2163W	6/8/2026 1:21:45 PM	34.4311728	-118.6498803	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
H-2163W	6/8/2026 1:22:03 PM	34.4311643	-118.6498752	Valve Adjustment:NSPS/EG CAC
H-2164E	6/3/2026 12:08:19 PM	34.4319202	-118.6460728	
H-2164E	6/19/2026 4:09:03 PM	34.4318832	-118.6459737	
H-2165E	6/10/2026 1:48:13 PM	34.4319173	-118.6451298	Valve Adjustment:Surging Liquid in Header
H-2165W	6/10/2026 8:33:57 AM	34.4321470	-118.6504022	Valve Adjustment:Barely Open
H-2165W	6/16/2026 8:05:00 AM			Air Tech Lab; [User entered 6.0%]
H-2165W	6/16/2026 8:05:00 AM			Air Tech Lab
H-2165W	6/17/2026 8:24:58 AM	34.4321428	-118.6504385	Valve Adjustment:Audible Flow,Barely Open,Surging Liquid in Header
H-2166E	6/2/2026 11:55:24 AM	34.4356273	-118.6438535	
H-2168C	6/3/2026 8:16:01 AM	34.4344087	-118.6448142	Valve Adjustment:Decreased Flow/Vacuum
H-2168E	6/2/2026 12:04:16 PM	34.4345052	-118.6439162	Valve Adjustment:Decreased Flow/Vacuum
H-2169C	6/3/2026 8:21:40 AM	34.4340572	-118.6450553	Valve Adjustment:Audible Flow
H-2169E	6/2/2026 1:13:50 PM	34.4342317	-118.6441932	
H-2170N	6/15/2026 1:03:30 PM	34.4358232	-118.6414425	Valve Adjustment:Decreased Flow/Vacuum
H-2170S	6/12/2026 11:45:52 AM	34.4335308	-118.6414522	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,
H-2171A	6/1/2026 9:28:09 AM	34.4373990	-118.6425532	
H-2171B	6/1/2026 10:04:39 AM	34.4364495	-118.6417222	No Adjustment Made
H-2171N	6/1/2026 8:58:16 AM	34.4379485	-118.6433193	
H-2171S	6/15/2026 1:06:14 PM	34.4358193	-118.6414683	
H-2272W	6/8/2026 1:02:54 PM	34.4317325	-118.6497772	Valve Adjustment:Decreased Flow/Vacuum
H-2272W	6/16/2026 8:49:15 AM	34.4317248	-118.6497512	Valve Adjustment:Audible Flow
H-2273W	6/2/2026 7:45:00 AM			AirTech Lab; [User entered 1.6%]
H-2273W	6/2/2026 7:45:00 AM			AirTech Lab

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
H-2273W	6/2/2026 8:54:53 AM	34.4321422	-118.6499718	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
H-2273W	6/16/2026 8:21:18 AM	34.4321380	-118.6499585	
H-2274B	6/11/2026 10:34:51 AM	34.4326528	-118.6469318	
H-2274B	6/17/2026 12:47:21 PM	34.4326542	-118.6469293	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
H-2274W	6/2/2026 8:36:16 AM	34.4327812	-118.6503697	Valve Adjustment:Decreased Flow/Vacuum
H-2274W	6/16/2026 8:00:20 AM	34.4327805	-118.6503817	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
H-2275E	6/3/2026 9:04:41 AM	34.4324085	-118.6462170	Valve Adjustment:Decreased Flow/Vacuum
H-2275W	6/2/2026 9:27:59 AM	34.4322293	-118.6493888	
H-2275W	6/16/2026 8:53:25 AM	34.4322365	-118.6493837	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum
H-2276A	6/2/2026 2:20:31 PM	34.4328835	-118.6482712	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-2276A	6/22/2026 9:30:29 AM	34.4328703	-118.6483107	Valve Adjustment:Increased Flow/Vacuum,Valve 100% Open,Surging Liquid in Header
H-2276A	6/22/2026 9:31:52 AM	34.4328690	-118.6483013	Valve Adjustment:Plugged/Pinched Suspected
H-2276B	6/8/2026 2:59:25 PM	34.4328773	-118.6469142	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-2276B	6/17/2026 12:52:46 PM	34.4328758	-118.6469078	Valve Adjustment:Audible Flow
H-2276E	6/3/2026 8:54:18 AM	34.4327925	-118.6453587	Valve Adjustment:Decreased Flow/Vacuum
H-2276W	6/2/2026 9:06:49 AM	34.4326590	-118.6499802	Valve Adjustment:Decreased Flow/Vacuum
H-2276W	6/16/2026 8:07:54 AM	34.4326682	-118.6499745	Valve Adjustment:Decreased Flow/Vacuum
H-2277A	6/3/2026 8:51:39 AM	34.4330222	-118.6487383	Valve Adjustment:Barely Open
H-2277A	6/16/2026 9:24:22 AM	34.4330263	-118.6487375	Valve Adjustment:Barely Open
H-2277B	6/2/2026 1:12:56 PM	34.4330450	-118.6469120	Valve Adjustment:Decreased Flow/Vacuum
H-2277B	6/3/2026 8:54:09 AM	34.4331148	-118.6487335	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-2277B	6/19/2026 1:21:11 PM	34.4330850	-118.6469260	Valve Adjustment:Barely Open,Surging Liquid in Well (Watered In)
H-23 (EXP-2	6/1/2026 9:52:09 AM	34.4370208	-118.6421618	NSPS/EG CAI,High O2,
H-23 (EXP-2	6/1/2026 9:54:19 AM	34.4369565	-118.6421417	NSPS/EG CAI,High O2,
H-2301E	6/14/2026 2:18:45 PM	34.4270478	-118.6479833	Valve Adjustment:Decreased Flow/Vacuum
H-2301E	6/14/2026 2:24:14 PM	34.4270888	-118.6479957	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum
H-2301E	6/14/2026 2:26:21 PM	34.4270888	-118.6480135	
H-2301W	6/25/2026 1:05:18 PM	34.4274470	-118.6506732	NSPS/EG CAI,High O2,
H-2301W	6/25/2026 1:09:52 PM	34.4275225	-118.6506208	NSPS/EG CAI,High O2,

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
H-2301W	6/30/2026 8:35:25 AM	34.4274873	-118.6506533	Valve Adjustment:Audible Flow
H-2302C	6/8/2026 9:52:30 AM	34.4283963	-118.6490043	Valve Adjustment:Decreased Flow/Vacuum
H-2302C	6/12/2026 2:48:52 PM	34.4282857	-118.6489373	
H-2302E	6/11/2026 10:52:08 AM	34.4275458	-118.6472818	
H-2303E	6/11/2026 10:55:35 AM	34.4279488	-118.6472737	
H-2303N	6/8/2026 9:57:28 AM	34.4290598	-118.6484410	Valve Adjustment:Decreased Flow/Vacuum
H-2303S	6/25/2026 12:20:01 PM	34.4272997	-118.6495263	NSPS/EG CAI,Audible Flow,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 to 1 Turn
H-2303S	6/25/2026 12:23:24 PM	34.4272363	-118.6495360	NSPS/EG CAC,Audible Flow,No Adjustment Made
H-2304E	6/11/2026 10:58:48 AM	34.4282220	-118.6468428	
H-2304S	6/11/2026 11:10:09 AM	34.4274982	-118.6490862	
H-2305N	6/8/2026 10:04:24 AM	34.4290162	-118.6486258	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
H-2305S	6/11/2026 1:24:17 PM	34.4274167	-118.6484962	
H-2306N	6/11/2026 12:47:49 PM	34.4294525	-118.6475215	
H-2307S	6/8/2026 9:41:48 AM	34.4284645	-118.6498403	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
H-2307S	6/8/2026 9:42:18 AM	34.4284502	-118.6498363	Valve Adjustment:NSPS/EG CAC,Barely Open
H-2307S	6/8/2026 11:07:20 AM	34.4374007	-118.6432410	Valve Adjustment:Surging Liquid in Header
H-2307S	6/12/2026 1:35:06 PM	34.4283438	-118.6498197	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,
H-2308S	6/8/2026 9:47:16 AM	34.4284670	-118.6498415	Valve Adjustment:Increased Flow/Vacuum
H-2308S	6/12/2026 1:23:49 PM	34.4284348	-118.6498917	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,
H-2309N	6/1/2026 10:38:59 AM	34.4308417	-118.6488850	
H-2309S	6/11/2026 1:19:20 PM	34.4282125	-118.6486905	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,
H-2310N	6/10/2026 3:31:54 PM	34.4298677	-118.6477922	High O2,NSPS/EG CAI,
H-2310N	6/10/2026 3:33:41 PM	34.4298433	-118.6478842	
H-2310S	6/11/2026 12:41:51 PM	34.4290653	-118.6476762	
H-2401S	6/8/2026 10:24:48 AM	34.4288705	-118.6512223	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
H-2401S	6/12/2026 10:50:55 AM	34.4288547	-118.6512233	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,
H-2401S	6/30/2026 1:49:46 PM	34.4288585	-118.6511777	Increased Flow/Vacuum,Opened Valve 1/2 to 1 Turn,
H-2402N	6/8/2026 10:17:02 AM	34.4291383	-118.6502977	Valve Adjustment:Decreased Flow/Vacuum
H-2402S	6/8/2026 10:36:11 AM	34.4287662	-118.6504887	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
H-2402S	6/12/2026 11:01:51 AM	34.4287263	-118.6505212	
H-2403N	6/8/2026 10:13:34 AM	34.4293228	-118.6501693	Valve Adjustment:Decreased Flow/Vacuum;Well Repairs:Flex Hose
H-2403S	6/8/2026 10:10:36 AM	34.4287683	-118.6499180	Valve Adjustment:Increased Flow/Vacuum,Barely Open
H-2403S	6/12/2026 1:10:46 PM	34.4287735	-118.6498722	
H-2404N	6/3/2026 1:04:10 PM	34.4293482	-118.6495548	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
H-2404S	6/8/2026 9:10:41 AM	34.4287640	-118.6493233	Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Valve 100% Open;Well Condition:Good
H-2405N	6/10/2026 9:20:55 AM	34.4299970	-118.6495107	Valve Adjustment:Decreased Flow/Vacuum
H-29	6/15/2026 12:56:44 PM	34.4354395	-118.6417838	Valve Adjustment:Barely Open
H-72	6/24/2026 10:05:28 AM	34.4369297	-118.6448290	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-74	6/15/2026 11:34:23 AM	34.4371895	-118.6433188	Valve Adjustment:Audible Flow
H-75	6/15/2026 1:24:56 PM	34.4363965	-118.6420930	Valve Adjustment:Decreased Flow/Vacuum
H-79	6/3/2026 9:53:50 AM	34.4339208	-118.6427747	
P-02R	6/1/2026 10:04:56 AM	34.4297278	-118.6439512	
P-03R	6/1/2026 10:14:48 AM	34.4298483	-118.6442013	
P-04	6/1/2026 10:26:15 AM	34.4294800	-118.6445812	
P-05	6/1/2026 10:44:04 AM	34.4291763	-118.6447810	
P-06R	6/1/2026 10:55:26 AM	34.4288645	-118.6450783	
P-07R	6/3/2026 10:13:11 AM	34.4298230	-118.6432683	
P-08R	6/1/2026 9:35:18 AM	34.4294067	-118.6437355	
P-08R	6/1/2026 9:45:12 AM	34.4294115	-118.6437360	Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum,Valve 100% Open
P-08R	6/1/2026 9:48:41 AM	34.4294080	-118.6437577	Valve Adjustment:Valve 100% Open
P-09	6/1/2026 1:04:32 PM	34.4290163	-118.6442227	
P-10	6/1/2026 1:16:13 PM	34.4287042	-118.6446415	
P-11	6/1/2026 1:24:13 PM	34.4284863	-118.6449740	
P-12	6/1/2026 2:05:59 PM	34.4288397	-118.6456100	Valve Adjustment:Orifice Plate Changed (See OP Log),Surging Liquid in Header
P-12	6/1/2026 2:07:33 PM	34.4288468	-118.6455825	Valve Adjustment:Orifice Plate Changed (See OP Log),Surging Liquid in Header
P-13	6/1/2026 1:44:03 PM	34.4284857	-118.6457970	
P-13	6/1/2026 1:53:17 PM	34.4288383	-118.6456222	
P-14	6/1/2026 2:21:50 PM	34.4280078	-118.6460472	
P-14	6/2/2026 10:41:03 AM	34.4280417	-118.6460760	Well Comment:Install sample port;Well Repairs:Sample Port
P-15R	6/2/2026 10:52:46 AM	34.4277795	-118.6459347	
P-16	6/9/2026 10:06:22 AM	34.4275327	-118.6456395	Valve Adjustment:Orifice Plate Changed (See OP Log)
P-16	6/9/2026 10:12:29 AM	34.4275477	-118.6456267	

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
P-17	6/9/2026 9:53:57 AM	34.4273895	-118.6453485	
P-18RD	6/9/2026 10:45:27 AM	34.4271240	-118.6450187	
P-18RS	6/9/2026 10:54:04 AM	34.4271263	-118.6450482	
P-19	6/9/2026 1:21:14 PM	34.4268887	-118.6452073	
P-20R	6/9/2026 1:01:59 PM	34.4268110	-118.6448160	
P-20R	6/9/2026 1:10:19 PM	34.4268410	-118.6448185	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum
P-20R	6/9/2026 1:12:39 PM	34.4268142	-118.6448403	
P-21	6/9/2026 1:31:50 PM	34.4264885	-118.6447847	
P-21RD	6/9/2026 1:39:47 PM	34.4263950	-118.6443838	
P-21RS	6/9/2026 1:46:57 PM	34.4263950	-118.6443980	
P-22RD	6/15/2026 1:51:06 PM	34.4269258	-118.6437990	
P-22RS	6/15/2026 1:46:59 PM	34.4269215	-118.6438097	
P-23	6/9/2026 2:24:44 PM	34.4261398	-118.6446867	
P-24	6/10/2026 10:21:41 AM	34.4260872	-118.6442908	
P-26	6/10/2026 10:43:44 AM	34.4265168	-118.6432042	
P-27	6/10/2026 1:24:51 PM	34.4268168	-118.6427740	
P-28	6/10/2026 1:37:21 PM	34.4270695	-118.6422750	
P-29R	6/15/2026 7:50:21 AM	34.4271872	-118.6418557	Audible Flow
P-30R	6/15/2026 7:53:58 AM	34.4274190	-118.6415992	
P-32R1	6/15/2026 7:59:37 AM	34.4282387	-118.6410060	
P-32R2	6/15/2026 8:02:27 AM	34.4284188	-118.6409730	
P-33	6/15/2026 8:06:14 AM	34.4288673	-118.6408357	No Flow Measurement
P-36	6/15/2026 8:14:41 AM	34.4301888	-118.6400693	No Flow Measurement
P-37	6/15/2026 8:18:30 AM	34.4305197	-118.6403898	
P-38RD	6/15/2026 8:30:24 AM	34.4299832	-118.6406530	Audible Flow,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
P-38RS	6/15/2026 8:28:11 AM	34.4300188	-118.6406482	
P-39	6/15/2026 8:36:42 AM	34.4295075	-118.6410102	No Adjustment Made
P-41	6/15/2026 8:48:14 AM	34.4289283	-118.6413903	NSPS/EG CAI,High O2,
P-41	6/15/2026 8:50:24 AM	34.4289398	-118.6413633	NSPS/EG CAI,High O2,
P-42R	6/15/2026 8:58:53 AM	34.4284130	-118.6416545	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,
P-43	6/15/2026 9:08:50 AM	34.4283032	-118.6418292	No Flow Measurement
P-44RD	6/15/2026 9:11:45 AM	34.4281708	-118.6419392	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,
P-44RS	6/15/2026 9:18:50 AM	34.4281790	-118.6418487	
P-45RD	6/15/2026 9:31:24 AM	34.4277203	-118.6424453	No Adjustment Made
P-45RS	6/15/2026 9:29:22 AM	34.4277448	-118.6424552	

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
P-46RD	6/15/2026 9:42:33 AM	34.4276685	-118.6426833	No Adjustment Made
P-46RS	6/15/2026 9:40:21 AM	34.4276388	-118.6426390	Audible Flow
P-47	6/15/2026 10:35:42 AM	34.4274350	-118.6432535	Valve Adjustment:Barely Open
P-48	6/15/2026 10:47:00 AM	34.4275800	-118.6436013	
P-49RD	6/15/2026 1:10:23 PM	34.4279945	-118.6438408	
P-49RS	6/15/2026 12:57:56 PM	34.4279775	-118.6437515	Well Repairs:Flex Hose
P-49RS	6/15/2026 1:06:47 PM	34.4279913	-118.6438558	Well Repairs:Sample Port
P-52	6/15/2026 12:36:30 PM	34.4287637	-118.6432890	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum
P-52	6/15/2026 12:37:24 PM	34.4287503	-118.6433103	
P-53	6/3/2026 2:24:03 PM	34.4291195	-118.6430563	
P-53	6/3/2026 2:32:15 PM	34.4291195	-118.6430615	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum
P-53	6/3/2026 2:35:13 PM	34.4291415	-118.6430492	
P-54	6/3/2026 1:49:46 PM	34.4294142	-118.6428592	
P-54	6/16/2026 2:27:41 PM	34.4294105	-118.6428837	
P-55	6/3/2026 1:33:10 PM	34.4297463	-118.6427158	
P-56	6/3/2026 1:00:08 PM	34.4301403	-118.6428037	
P-56	6/3/2026 1:18:05 PM	34.4301222	-118.6428115	Well Comment:corrected O2 issue
P-57	6/3/2026 12:32:14 PM	34.4300145	-118.6424637	
P-60R	6/10/2026 2:07:25 PM	34.4308107	-118.6415242	
P-61	6/10/2026 2:14:41 PM	34.4311480	-118.6411405	
P-65	6/10/2026 2:29:10 PM	34.4303907	-118.6409533	
P-71	6/15/2026 1:16:48 PM	34.4279830	-118.6432182	Valve Adjustment:Increased Flow/Vacuum
P-71	6/15/2026 1:17:31 PM	34.4279773	-118.6432070	
P-75	6/10/2026 2:44:34 PM	34.4303395	-118.6414960	
P-76	6/15/2026 8:24:20 AM	34.4301655	-118.6404450	Audible Flow
P-79	6/9/2026 10:24:04 AM	34.4270492	-118.6460978	
SC-2000E	6/3/2026 12:31:16 PM	34.4307367	-118.6467727	Valve Adjustment:Decreased Flow/Vacuum
SC-2501E	6/1/2026 10:05:00 AM			AtmAA
SC-2501E	6/1/2026 10:05:00 AM			AtmAA; [User entered 17.98%]
SC-2501E	6/1/2026 10:05:41 AM	34.4366790	-118.6478947	Valve Adjustment:High Temp,Barely Open
SC-2501E	6/8/2026 9:41:04 AM	34.4366954	-118.6479033	Valve Adjustment:Audible Flow,High Temp
SC-2501E	6/15/2026 9:12:25 AM	34.4366657	-118.6478893	Valve Adjustment:Audible Flow,No Flow Measurement,High Temp,Valve 100% Open
SC-2501E	6/29/2026 9:32:13 AM	34.4366926	-118.6479158	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
SC-2501E	6/29/2026 9:37:36 AM	34.4366920	-118.6479223	Valve Adjustment:No Flow Measurement,High Temp,Barely Open

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
SC-2501W	6/11/2026 9:57:09 AM	34.4367938	-118.6485273	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
SC-2501W	6/12/2026 9:03:41 AM	34.4367842	-118.6485150	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
SC-2501W	6/16/2026 8:35:07 AM	34.4367752	-118.6485322	Valve Adjustment:High Temp,Decreased Flow/Vacuum
SC-2501W	6/16/2026 8:37:36 AM	34.4367753	-118.6485336	Valve Adjustment:Audible Flow,High Temp,Decreased Flow/Vacuum
SC-2501W	6/16/2026 8:39:56 AM	34.4367718	-118.6485272	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum,Barely Open
SC-2501W	6/22/2026 10:01:39 AM	34.4367813	-118.6485276	Valve Adjustment:High Temp,Valve 100% Open
SC-2501W	6/29/2026 10:05:06 AM	34.4367806	-118.6485298	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
SC-2501W	6/29/2026 10:07:43 AM	34.4367782	-118.6485416	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
SW-10	6/25/2026 12:49:30 PM	34.4370207	-118.6503705	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
SW-115	6/1/2026 10:41:10 AM	34.4348468	-118.6412618	No Adjustment Made
SW-154	6/26/2026 11:08:16 AM	34.4379710	-118.6456283	
SW-187	6/8/2026 12:55:51 PM	34.4372553	-118.6473688	Valve Adjustment:Valve 100% Open
SW-1930	6/2/2026 5:58:06 AM	34.4353152	-118.6516182	Valve Adjustment:Valve 100% Open
SW-20	6/3/2026 10:03:24 AM	34.4302288	-118.6436502	Valve Adjustment:Orifice Plate Changed (See OP Log)
SW-2503D	6/29/2026 5:49:38 AM	34.4351190	-118.6516125	
SW-2503M	6/29/2026 5:56:58 AM	34.4351242	-118.6516007	
SW-2503MD	6/29/2026 5:53:43 AM	34.4350995	-118.6516247	
SW-2503S	6/29/2026 5:59:37 AM	34.4351203	-118.6515980	
SW-2504D	6/29/2026 6:04:51 AM	34.4353097	-118.6516770	Valve Adjustment:Reduce Sys. Vac. - Flare Down
SW-2504M	6/29/2026 6:08:59 AM	34.4353123	-118.6516887	Valve Adjustment:Reduce Sys. Vac. - Flare Down
SW-2504MD	6/29/2026 6:15:30 AM	34.4352992	-118.6516880	Valve Adjustment:Reduce Sys. Vac. - Flare Down
SW-2504S	6/29/2026 6:12:14 AM	34.4353140	-118.6516872	Valve Adjustment:Reduce Sys. Vac. - Flare Down
SW-65	6/1/2026 10:45:05 AM	34.4348150	-118.6411980	No Adjustment Made
SW-66	6/26/2026 11:06:07 AM	34.4379635	-118.6456250	
SW-70	6/8/2026 12:58:00 PM	34.4372472	-118.6473583	Valve Adjustment:Valve 100% Open
SW-71	6/10/2026 10:30:25 AM	34.4259783	-118.6438028	
SW-72	6/15/2026 8:11:58 AM	34.4296157	-118.6402300	
SW-80	6/1/2026 11:35:52 AM	34.4383055	-118.6433533	Valve Adjustment:Audible Flow

All LFG Extraction Wells - June 2026
Chiquita Canyon Landfill

Point Name	Record Date	Latitude	Longitude	Comments
SW-9	6/8/2026 1:00:58 PM	34.4372488	-118.6473773	Valve Adjustment:Valve 100% Open
TC-1961C	6/3/2026 12:00:23 PM	34.4321797	-118.6454193	
TC-1961E	6/3/2026 9:11:02 AM	34.4328558	-118.6444938	Valve Adjustment:Increased Flow/Vacuum
TC-2174	6/1/2026 6:25:00 AM			AtmAA; [User entered 16.75%]
TC-2174	6/1/2026 9:52:38 AM	34.4367608	-118.6476263	Valve Adjustment:No Flow Measurement,High Temp
TC-2174	6/1/2026 6:25:00 PM			AtmAA
TC-2174	6/8/2026 9:26:15 AM	34.4367295	-118.6476359	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
TC-2174	6/15/2026 8:52:15 AM	34.4367466	-118.6476386	Valve Adjustment:No Flow Measurement,High Temp
TC-2174	6/22/2026 8:57:50 AM	34.4367378	-118.6476103	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
TC-2174	6/29/2026 9:19:30 AM	34.4367560	-118.6476266	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
VL-02	6/26/2026 12:25:21 PM	34.4311838	-118.6443143	Valve Adjustment:Surging Liquid in Header
WTD-02	6/14/2026 8:45:26 AM	34.4346313	-118.6513202	
WTD-02	6/17/2026 1:24:35 PM	34.4345368	-118.6512037	Valve Adjustment:No Flow Measurement,Decreased Flow/Vacuum,Barely Open
WTD-02	6/17/2026 1:26:01 PM	34.4345310	-118.6512097	Valve Adjustment:No Flow Measurement,Reconnected this Date,Barely Open
WTD-03	6/14/2026 8:49:13 AM	34.4344013	-118.6514280	
WTD-06	6/14/2026 9:11:46 AM	34.4335080	-118.6519005	
WTD-07	6/14/2026 9:07:02 AM	34.4334887	-118.6519045	
WTD-10	6/14/2026 9:00:26 AM	34.4324687	-118.6518503	

Table 2. Monthly LEA Selected Wells - June 2026
Chiquita Canyon Landfill

Point Name	Status	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-108-52	Active	6/2/2026 8:10:00 AM					35						AirTech Lab
CV-108-52	Active	6/2/2026 8:10:00 AM						2600					AirTech Lab; [User entered 0.26%]
CV-108-52	Active	6/2/2026 8:18:48 AM	49.7	46.1	0.5	3.7			76.5	76.9	-10.49	-10.56	Valve Adjustment:Barely Open,Surging Liquid in Header
CV-108-52	Active	6/16/2026 7:54:36 AM	54.7	41.3	0.8	3.2			81.2	81.1	-1.15	-1.24	Valve Adjustment:Increased Flow/Vacuum,Surging Liquid in Header
CV-113	Active	6/4/2026 7:45:00 AM					160						AirTech Lab
CV-113	Active	6/4/2026 7:45:00 AM						32000					Air Tech Lab; [User entered 3.2%]
CV-113	Active	6/5/2026 10:19:11 AM	18.5	78.3	0.0	3.2			92.3	92.4	-0.91	-0.89	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-113	Active	6/17/2026 12:35:29 PM	30.7	62.5	0.0	6.9			95.7	96.1	-0.81	-0.77	Valve Adjustment:Barely Open
CV-113	Active	6/19/2026 12:51:33 PM	31.1	62.1	0.2	6.5			81.6	80.6	-1.75	-2.15	Valve Adjustment:Increased Flow/Vacuum
CV-114	Active	6/1/2026 9:43:10 AM	11.6	74.4	0.0	14.0			188.6	110.8	-3.88	-3.93	Valve Comment:Well head notified hard piped with stainless;Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open;Well Condition:Good
CV-114	Active	6/1/2026 9:44:20 AM	11.8	77.2	0.0	11.0			188.6	188.6	-4.20	-3.98	Valve Comment:Well was hard piped;Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-114	Active	6/1/2026 9:50:00 AM					3760						AtmAA
CV-114	Active	6/1/2026 9:50:00 AM						162000					AtmAA; [User entered 16.2%]
CV-114	Active	6/8/2026 9:22:28 AM	1.8	76.3	0.0	21.9			188.7	189.9	-5.45	-5.56	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-114	Active	6/15/2026 8:40:00 AM					400						Air Tech Lab
CV-114	Active	6/15/2026 8:40:00 AM						0					Air Tech Lab; [User entered 0%]
CV-114	Active	6/15/2026 8:49:54 AM	8.0	79.0	0.0	13.0			190.5	190.6	-1.31	-1.24	Valve Adjustment:No Flow Measurement,High Temp
CV-114	Active	6/22/2026 8:59:44 AM	4.6	77.1	0.0	18.3			189.1	189.8	-3.55	-3.49	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-114	Active	6/29/2026 9:16:56 AM	3.4	71.9	0.0	24.7			189.6	190.3	-4.45	-4.51	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-1532A	Active	6/11/2026 10:55:34 AM	25.9	45.7	4.6	23.8			95.8	95.9	-2.99	-2.97	,
CV-1532A	Active	6/12/2026 10:00:41 AM	22.5	47.1	4.0	26.4			96.8	96.8	-3.78	-3.68	No Flow Measurement,Reduced System Vacuum
CV-1532A	Active	6/16/2026 8:55:00 AM					59						Air Tech Lab
CV-1532A	Active	6/16/2026 8:55:00 AM						11000					Air Tech Lab; [User entered 1.1%]

Table 2. Monthly LEA Selected Wells - June 2026
Chiquita Canyon Landfill

Point Name	Status	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-1532A	Active	6/17/2026 10:11:24 AM	39.3	52.9	5.7	2.1			87.9	87.8	-5.04	-5.03	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open
CV-1532A	Active	6/17/2026 10:11:46 AM	39.3	53.4	5.6	1.7			87.8	87.7	-5.03	-5.03	Valve Adjustment:NSPS/EG CAI,High O2
CV-1535	Active	6/2/2026 8:13:51 AM	46.7	51.9	0.0	1.4			121.5	120.2	-1.49	-1.22	Valve Adjustment:Decreased Flow/Vacuum,Barely Open;Well Condition:Good
CV-1535	Active	6/15/2026 10:05:00 AM					91						Air Tech Lab
CV-1535	Active	6/15/2026 10:05:00 AM						8900					Air Tech Lab; [User entered 0.89%]
CV-1535	Active	6/16/2026 7:47:10 AM	47.4	51.8	0.0	0.8			116.6	116.9	-0.51	-0.50	Valve Adjustment:Barely Open
CV-1902A	Active	6/3/2026 9:06:07 AM	13.6	77.6	0.2	8.6			164.2	162.4	-5.62	-2.24	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum,Barely Open
CV-1902A	Active	6/3/2026 9:06:48 AM	11.7	75.8	0.0	12.5			161.4	162.4	-2.25	-2.09	Valve Adjustment:No Flow Measurement,High Temp
CV-1902A	Active	6/3/2026 9:10:00 AM						158400					AtmAA; [User entered 15.84%]
CV-1902A	Active	6/10/2026 9:19:44 AM	18.9	76.2	0.0	4.9			168.7	169.5	-4.17	-4.32	Valve Comment:Install sample port on system side;Valve Adjustment:No Flow Measurement,High Temp
CV-1902A	Active	6/16/2026 9:20:00 AM					810						Air Tech Lab
CV-1902A	Active	6/16/2026 9:20:00 AM						190000					Air Tech Lab; [User entered 19%]
CV-1902A	Active	6/17/2026 8:55:02 AM	2.0	76.6	0.0	21.4			162.8	162.9	-2.97	-2.99	Valve Adjustment:No Flow Measurement,High Temp
CV-1902A	Active	6/24/2026 1:28:33 PM	10.2	73.7	0.0	16.1			169.5	167.2	-3.27	-3.23	Valve Adjustment:No Flow Measurement,High Temp
CV-2001	Active	6/10/2026 8:24:20 AM	11.6	73.3	0.2	14.9			88.8	89.2	-10.14	-9.42	Valve Adjustment:Decreased Flow/Vacuum
CV-2001	Active	6/16/2026 8:10:00 AM					990						Air Tech Lab
CV-2001	Active	6/16/2026 8:10:00 AM						79000					Air Tech Lab; [User entered 7.9%]
CV-2001	Active	6/17/2026 8:30:39 AM	10.8	76.4	0.9	11.9			90.5	90.5	-6.99	-6.71	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
CV-2002	Active	6/2/2026 8:20:00 AM					3200						AirTech Lab
CV-2002	Active	6/2/2026 8:20:00 AM						150000					AirTech Lab; [User entered 15%]
CV-2002	Active	6/3/2026 9:45:00 AM						136000					AtmAA; [User entered 13.6%]
CV-2002	Active	6/3/2026 9:49:56 AM	30.2	69.6	0.2	0.0			183.4	183.8	0.21	-1.44	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum,Surging Liquid in Well (Watered In);Well Condition:Poor;Well Repairs:Flex Hose,Valve,Surging
CV-2002	Active	6/3/2026 9:50:58 AM	30.0	70.0	0.0	0.0			183.9	183.9	-2.01	-1.81	Valve Adjustment:NSPS/EG CAC,High Temp,Surging Liquid in Well (Watered In);Well Condition:Poor;Well Repairs:Flex Hose,Valve,Surging

Table 2. Monthly LEA Selected Wells - June 2026
Chiquita Canyon Landfill

Point Name	Status	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2002	Active	6/10/2026 1:36:51 PM	30.4	69.5	0.1	0.0			183.8	184.0	-7.54	-8.29	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	Active	6/19/2026 3:46:32 PM	13.8	75.1	0.1	11.0			184.5	184.5	-6.21	-3.27	High Temp,
CV-2002	Active	6/19/2026 3:47:45 PM	13.6	78.7	0.0	7.7			183.8	183.8	-2.80	-2.02	,
CV-2007	Active	6/4/2026 8:55:00 AM					1100						AirTech Lab
CV-2007	Active	6/4/2026 8:55:00 AM						65000					Air Tech Lab; [User entered 6.5%]
CV-2007	Active	6/4/2026 10:45:16 AM	16.0	78.3	0.0	5.7			102.0	102.0	-0.14	-0.12	Valve Adjustment:Barely Open
CV-2007	Active	6/23/2026 10:08:32 AM	12.5	39.5	10.0	38.0			125.9	125.6	-1.20	-1.00	Valve Adjustment:Decreased Flow/Vacuum,Valve 100% Closed,Surging Liquid in Header
CV-2301	Active	6/2/2026 2:24:23 PM	39.8	60.0	0.2	0.0			170.0	168.0	-3.74	-3.69	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	Active	6/2/2026 2:25:00 PM					1710						AtmAA
CV-2301	Active	6/2/2026 2:25:00 PM						107800					AtmAA; [User entered 10.78%]
CV-2301	Active	6/3/2026 7:00:00 AM					1400						AirTech Lab
CV-2301	Active	6/3/2026 7:00:00 AM						110000					Air Tech Lab; [User entered 11%]
CV-2301	Active	6/9/2026 1:50:33 PM	39.9	60.1	0.0	0.0			167.4	167.5	-3.60	-3.60	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	Active	6/16/2026 1:36:56 PM	45.7	54.2	0.1	0.0			169.2	169.1	-7.42	-5.57	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2301	Active	6/16/2026 1:39:12 PM	42.2	57.4	0.4	0.0			169.0	88.3	-2.78	-2.73	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	Active	6/23/2026 2:37:21 PM	21.2	72.0	1.3	5.5			172.0	172.4	-0.03	-1.40	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-2301	Active	6/23/2026 2:39:33 PM	19.5	47.7	8.6	24.2			175.2	169.0	-2.23	-2.18	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	Active	6/23/2026 3:00:42 PM	30.1	69.9	0.0	0.0			172.4	173.2	-3.17	-3.20	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	Active	6/24/2026 1:34:16 PM	3.2	82.9	0.0	13.9			124.4	153.3	3.95	-0.10	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-2301	Active	6/24/2026 1:35:48 PM	3.0	82.7	0.0	14.3			164.1	163.4	-0.06	-0.04	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2301	Active	6/30/2026 10:24:56 AM	5.4	2.1	19.3	73.2			176.6	165.8	-9.73	-2.36	Valve Adjustment:No Flow Measurement,High Temp,High O2,Decreased Flow/Vacuum
CV-2301	Active	6/30/2026 10:28:52 AM	39.7	47.8	2.4	10.1			157.8	160.0	-0.33	-1.26	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-2301	Active	6/30/2026 10:30:41 AM	28.9	60.2	1.7	9.2			158.2	158.0	-1.07	-1.06	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-2302	Active	6/3/2026 7:10:00 AM					260						AirTech Lab

Table 2. Monthly LEA Selected Wells - June 2026
Chiquita Canyon Landfill

Point Name	Status	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2302	Active	6/3/2026 7:10:00 AM						42000					Air Tech Lab; [User entered 4.2%]
CV-2302	Active	6/3/2026 9:51:38 AM	42.0	53.4	0.3	4.3			117.3	117.3	-7.77	-7.81	Valve Adjustment:Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2302	Active	6/16/2026 9:54:51 AM	45.0	49.7	0.8	4.5			117.4	118.2	-6.81	-5.57	Valve Adjustment:Decreased Flow/Vacuum
CV-2303	Active	6/2/2026 10:35:06 AM	20.6	73.5	0.0	5.9			188.1	186.7	-3.48	-3.72	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2303	Active	6/2/2026 10:40:00 AM					2790						AtmAA
CV-2303	Active	6/2/2026 10:40:00 AM						174400					AtmAA; [User entered 17.44%]
CV-2303	Active	6/3/2026 7:15:00 AM					2300						AirTech Lab
CV-2303	Active	6/3/2026 7:15:00 AM						190000					Air Tech Lab; [User entered 19%]
CV-2303	Active	6/9/2026 9:49:45 AM	16.3	78.0	0.0	5.7			195.9	196.1	6.05	6.41	Valve Comment:Lorentz pump running;Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2303	Active	6/9/2026 9:50:35 AM	18.1	78.3	0.0	3.6			196.4	196.5	6.01	6.36	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2303	Active	6/16/2026 9:48:16 AM	14.2	74.2	0.0	11.6			200.5	200.6	4.31	4.32	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open
CV-2303	Active	6/16/2026 9:50:23 AM	14.3	69.5	0.0	16.2			199.2	199.2	2.87	2.74	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open
CV-2303	Active	6/23/2026 10:25:28 AM	8.4	73.7	0.0	17.9			169.8	166.6	-0.66	-0.66	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Valve 100% Open
CV-2303	Active	6/29/2026 9:39:04 AM	1.4	79.6	0.2	18.8			191.2	191.6	-3.73	-3.75	Valve Adjustment:High Temp,Valve 100% Open
CV-2305	Active	6/2/2026 2:54:55 PM	24.2	63.4	0.0	12.4			150.6	150.7	-10.68	-10.74	Valve Adjustment:NSPS/EG CAC;Well Comment:pump active;Well Condition:Lorentz Pump Installed
CV-2305	Active	6/2/2026 3:00:00 PM					1870						AtmAA
CV-2305	Active	6/2/2026 3:00:00 PM						60700					AtmAA; [User entered 6.07%]
CV-2305	Active	6/11/2026 9:25:45 AM	38.0	61.2	0.0	0.8			160.3	160.3	-8.55	-8.50	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2305	Active	6/12/2026 8:25:00 AM					500						Air Tech Lab
CV-2305	Active	6/12/2026 8:25:00 AM						28000					Air Tech Lab; [User entered 2.8%]

Table 2. Monthly LEA Selected Wells - June 2026
Chiquita Canyon Landfill

Point Name	Status	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2305	Active	6/17/2026 1:34:44 PM	21.3	56.2	0.0	22.5			159.3	159.4	-10.50	-10.32	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-2305	Active	6/24/2026 8:18:10 AM	43.8	51.2	0.0	5.0			158.7	158.8	-11.16	-11.15	Valve Adjustment:No Flow Measurement,High Temp
CV-2312	Active	6/2/2026 2:45:00 PM					2900						AtmAA
CV-2312	Active	6/2/2026 2:45:00 PM						121700					AtmAA; [User entered 12.17%]
CV-2312	Active	6/2/2026 2:47:24 PM	14.7	75.5	0.2	9.6			169.2	169.2	-4.82	-5.56	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In)
CV-2312	Active	6/10/2026 2:01:28 PM	9.7	79.1	0.0	11.2			167.1	167.3	-6.29	-6.86	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2312	Active	6/11/2026 7:30:00 AM					2700						Air Tech Lab
CV-2312	Active	6/11/2026 7:30:00 AM						150000					Air Tech Lab; [User entered 15%]
CV-2312	Active	6/24/2026 10:00:40 AM	11.8	75.8	12.4	0.0			165.6	166.2	-8.66	-8.76	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2312	Active	6/30/2026 1:42:08 PM	30.0	70.0	0.0	0.0			166.5	166.6	-23.00	-19.65	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2312	Active	6/30/2026 1:48:19 PM	26.8	69.7	0.0	3.5			166.4	166.8	-10.55	-4.78	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2312	Active	6/30/2026 1:49:32 PM	14.0	76.6	0.0	9.4			167.0	166.7	-6.21	-6.32	Valve Adjustment:No Flow Measurement,High Temp
CV-2314	Active	6/3/2026 1:41:34 PM	18.6	79.4	0.0	2.0			178.5	178.9	-7.67	-7.61	Valve Adjustment:High Temp
CV-2314	Active	6/3/2026 1:55:00 PM						110800					AtmAA; [User entered 11.08%]
CV-2314	Active	6/10/2026 2:47:57 PM	12.9	80.4	0.2	6.5			177.5	178.4	-12.32	-8.98	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2314	Active	6/10/2026 2:50:12 PM	12.9	81.2	0.0	5.9			180.9	179.9	-5.99	-5.93	Valve Adjustment:High Temp
CV-2314	Active	6/12/2026 8:30:00 AM					1700						Air Tech Lab
CV-2314	Active	6/12/2026 8:30:00 AM						74000					Air Tech Lab; [User entered 7.4%]
CV-2314	Active	6/17/2026 2:43:32 PM	1.0	75.4	2.0	21.6			180.0	182.3	-4.99	-2.47	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-2314	Active	6/17/2026 2:44:23 PM	0.9	77.0	0.5	21.6			181.9	181.6	-3.43	-3.11	Valve Adjustment:High Temp
CV-2314	Active	6/19/2026 11:52:39 AM	0.5	85.1	0.8	13.6			177.3	181.1	-9.71	-11.07	High Temp,
CV-2314	Active	6/19/2026 11:54:02 AM	0.5	85.4	0.2	13.9			180.9	180.9	-10.77	-10.79	,
CV-2314	Active	6/24/2026 9:02:40 AM	7.4	80.6	0.1	11.9			181.1	181.1	-9.70	-9.77	Valve Adjustment:No Flow Measurement,High Temp

Table 2. Monthly LEA Selected Wells - June 2026
Chiquita Canyon Landfill

Point Name	Status	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2314	Active	6/30/2026 2:06:51 PM	38.7	61.3	0.0	0.0			180.0	181.5	-11.21	-5.39	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2314	Active	6/30/2026 2:08:30 PM	10.3	76.1	0.0	13.6			181.6	181.5	-5.17	-5.05	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-2315	Active	6/1/2026 1:23:23 PM	26.1	73.9	0.0	0.0			183.4	183.4	-3.28	-3.25	Valve Comment:Lorentz pump disconnected;Valve Adjustment:No Flow Measurement,High Temp
CV-2315	Active	6/1/2026 1:30:00 PM					2310						AtmAA
CV-2315	Active	6/1/2026 1:30:00 PM						92400					AtmAA; [User entered 9.24%]
CV-2315	Active	6/3/2026 7:25:00 AM					2700						AirTech Lab
CV-2315	Active	6/3/2026 7:25:00 AM						120000					Air Tech Lab; [User entered 12%]
CV-2315	Active	6/8/2026 1:23:19 PM	15.2	80.1	0.1	4.6			183.8	183.8	-4.39	-4.39	Valve Adjustment:No Flow Measurement,High Temp
CV-2315	Active	6/15/2026 9:49:34 AM	28.2	71.7	0.0	0.1			171.0	172.9	-3.46	-3.25	Valve Comment:Pump disconnected;Valve Adjustment:No Flow Measurement,High Temp
CV-2315	Active	6/22/2026 1:34:17 PM	16.4	74.5	0.0	9.1			188.1	188.2	-1.42	-1.91	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Header
CV-2315	Active	6/30/2026 2:44:21 PM	16.4	76.2	0.0	7.4			185.1	185.0	-6.45	-6.66	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2328	Active	6/2/2026 2:33:14 PM	40.6	59.4	0.0	0.0			156.8	157.2	-5.72	-5.72	Valve Comment:Lorentz pump on while taking reading;Valve Adjustment:No Flow Measurement,High Temp
CV-2328	Active	6/2/2026 2:35:00 PM					1010						AtmAA
CV-2328	Active	6/2/2026 2:35:00 PM						75000					AtmAA; [User entered 7.5%]
CV-2328	Active	6/9/2026 2:20:39 PM	33.0	67.0	0.0	0.0			157.7	158.2	-5.68	-5.68	Valve Comment:Pump on;Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2328	Active	6/12/2026 8:45:00 AM					200						Air Tech Lab
CV-2328	Active	6/12/2026 8:45:00 AM						22000					Air Tech Lab; [User entered 2.2%]
CV-2328	Active	6/16/2026 2:19:24 PM	30.8	69.2	0.0	0.0			173.3	173.3	-3.33	-3.41	Valve Comment:Pump running;Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2328	Active	6/24/2026 9:52:31 AM	35.8	64.2	0.0	0.0			167.2	167.2	-4.74	-4.72	Valve Adjustment:No Flow Measurement,High Temp
CV-2328	Active	6/30/2026 1:37:04 PM	7.5	80.9	0.0	11.6			163.1	165.2	-8.11	-5.39	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-2328	Active	6/30/2026 1:38:00 PM	19.1	78.1	0.0	2.8			165.6	165.6	-5.32	-5.39	Valve Adjustment:High Temp
CV-2333	Active	6/1/2026 9:34:06 AM	7.3	77.2	0.0	15.5			186.9	186.9	-4.00	-4.15	Valve Adjustment:No Flow Measurement,High Temp

Table 2. Monthly LEA Selected Wells - June 2026
Chiquita Canyon Landfill

Point Name	Status	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2333	Active	6/1/2026 9:45:00 AM					4810						AtmAA
CV-2333	Active	6/1/2026 9:45:00 AM						181900					AtmAA; [User entered 18.19%]
CV-2333	Active	6/3/2026 8:00:00 AM					4200						AirTech Lab
CV-2333	Active	6/3/2026 8:00:00 AM						200000					Air Tech Lab; [User entered 20%]
CV-2333	Active	6/8/2026 9:19:09 AM	1.1	76.7	0.0	22.2			187.2	187.4	-5.39	-5.72	Valve Adjustment:No Flow Measurement,High Temp
CV-2333	Active	6/15/2026 8:45:46 AM	4.5	79.6	0.0	15.9			190.7	190.8	0.59	0.61	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.
CV-2333	Active	6/15/2026 8:46:36 AM	4.4	77.9	0.0	17.7			190.8	190.5	0.53	0.48	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open
CV-2333	Active	6/16/2026 8:27:48 AM	1.8	70.9	1.0	26.3			158.3	161.2	-3.54	-2.59	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2333	Active	6/16/2026 8:29:05 AM	1.6	78.1	0.4	19.9			162.6	162.5	-1.88	-1.91	Valve Adjustment:No Flow Measurement,High Temp
CV-2333	Active	6/22/2026 8:54:06 AM	3.7	74.1	0.0	22.2			162.4	162.5	-3.36	-3.33	Valve Comment:Well head raised;Valve Adjustment:No Flow Measurement,High Temp
CV-2333	Active	6/29/2026 9:12:38 AM	5.8	77.7	0.0	16.5			191.0	191.1	-4.10	-4.18	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2334	Active	6/3/2026 8:05:00 AM					1200						AirTech Lab
CV-2334	Active	6/3/2026 8:05:00 AM						30000					Air Tech Lab; [User entered 3.0%]
CV-2334	Active	6/4/2026 2:15:28 PM	0.1	0.8	20.7	78.4			128.7	128.8	-6.68	-6.66	
CV-2334	Active	6/17/2026 1:21:10 PM	9.4	75.7	0.0	14.8			133.3	133.4	-6.76	-7.05	Valve Adjustment:NSPS/EG CAI,High Temp,Reduce Sys. Vac. - Flare Down;Well Comment:pump is active;Well Condition:Pnumatic Pump Installed
CV-2334	Active	6/17/2026 1:22:09 PM	9.5	74.7	0.0	15.8			133.3	133.2	-6.38	-6.38	Valve Adjustment:High Temp,Reduce Sys. Vac. - Flare Down;Well Comment:pump is active;Well Condition:Pnumatic Pump Installed
CV-2334	Active	6/19/2026 12:10:06 PM	11.5	82.4	0.5	5.6			128.5	125.9	-7.92	-4.80	,
CV-2337	Active	6/1/2026 2:16:10 PM	4.7	81.3	0.1	13.9			150.7	150.8	-3.99	-2.68	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-2337	Active	6/3/2026 9:16:44 AM	23.0	77.0	0.0	0.0			151.0	151.1	-2.84	-2.85	Valve Adjustment:High Temp
CV-2337	Active	6/3/2026 9:25:00 AM						92900					AtmAA; [User entered 9.29%]
CV-2337	Active	6/10/2026 9:39:16 AM	25.4	74.6	0.0	0.0			151.6	151.9	-4.05	-4.19	Valve Adjustment:No Flow Measurement,High Temp
CV-2337	Active	6/16/2026 9:15:00 AM					3500						Air Tech Lab
CV-2337	Active	6/16/2026 9:15:00 AM						120000					Air Tech Lab; [User entered 12%]

Table 2. Monthly LEA Selected Wells - June 2026
Chiquita Canyon Landfill

Point Name	Status	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2337	Active	6/17/2026 8:43:10 AM	5.3	81.5	0.0	13.2			152.5	152.5	-2.51	-2.50	Valve Adjustment:No Flow Measurement,High Temp
CV-2337	Active	6/24/2026 1:53:56 PM	21.1	74.5	0.0	4.4			151.7	151.6	-4.15	-4.08	Valve Comment:Pump on;Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2341	Active	6/11/2026 9:35:24 AM	11.9	62.1	2.3	23.7			99.6	101.1	-1.12	-1.38	,
CV-2341	Active	6/11/2026 3:32:00 PM	7.9	72.0	1.7	18.4			107.1	107.1	-3.06	-1.67	,
CV-2341	Active	6/15/2026 10:15:00 AM					860						Air Tech Lab
CV-2341	Active	6/15/2026 10:15:00 AM						150000					Air Tech Lab; [User entered 15%]
CV-2341	Active	6/22/2026 11:40:09 AM	13.6	67.0	1.1	18.3			107.2	106.5	-1.61	-0.49	Valve Adjustment:Decreased Flow/Vacuum
CV-2341	Active	6/25/2026 1:45:13 PM	1.6	70.3	0.6	27.5			96.2	96.2	-1.49	-1.49	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed
CV-2344	Active	6/2/2026 8:00:00 AM					3200						AirTech Lab
CV-2344	Active	6/2/2026 8:00:00 AM						160000					AirTech Lab; [User entered 16%]
CV-2344	Active	6/2/2026 8:40:05 AM	2.2	75.5	1.0	21.3			139.8	140.0	-10.20	-9.84	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-2344	Active	6/2/2026 8:41:11 AM	0.4	78.2	1.0	20.4			140.6	140.7	-9.65	-9.46	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2344	Active	6/10/2026 10:48:47 AM	5.7	76.2	0.1	18.0			169.5	169.8	-4.99	-4.96	High Temp,NSPS/EG CAI
CV-2344	Active	6/10/2026 10:51:49 AM	4.1	81.1	0.0	14.8			170.5	170.1	-4.51	-1.72	NSPS/EG CAI,High Temp
CV-2344	Active	6/11/2026 10:41:23 AM	12.2	67.5	0.0	20.3			165.6	166.7	3.24	-2.15	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-2344	Active	6/11/2026 10:42:42 AM	16.8	77.2	0.0	6.0			165.7	165.4	-2.80	-2.59	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-2344	Active	6/17/2026 9:22:23 AM	4.5	75.1	0.0	20.4			157.4	157.6	-1.47	-1.20	Valve Adjustment:No Flow Measurement,High Temp
CV-2345	Active	6/2/2026 7:55:00 AM					660						AirTech Lab
CV-2345	Active	6/2/2026 7:55:00 AM						33000					AirTech Lab; [User entered 3.3%]
CV-2345	Active	6/2/2026 8:44:21 AM	14.6	78.4	0.2	6.8			126.3	126.5	-2.96	-2.96	Valve Adjustment:Audible Flow
CV-2345	Active	6/16/2026 8:05:13 AM	18.4	76.5	0.2	4.9			126.1	126.5	-2.06	-2.05	Well Comment:Unable to adjust safely
CV-2346	Active	6/2/2026 7:50:00 AM					2700						AirTech Lab
CV-2346	Active	6/2/2026 7:50:00 AM						160000					AirTech Lab; [User entered 16%]
CV-2346	Active	6/3/2026 9:35:01 AM	13.3	75.5	0.9	10.3			186.1	186.4	-7.29	-6.28	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum

Table 2. Monthly LEA Selected Wells - June 2026
Chiquita Canyon Landfill

Point Name	Status	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2346	Active	6/3/2026 9:39:13 AM	13.4	74.4	0.8	11.4			186.5	186.6	-4.58	-4.61	Valve Comment:Lorenz pump disconnected;Valve Adjustment:No Flow Measurement,High Temp
CV-2346	Active	6/3/2026 9:40:00 AM						147600					AtmAA; [User entered 14.76%]
CV-2346	Active	6/10/2026 9:54:27 AM	17.2	75.4	0.5	6.9			186.8	186.9	-9.26	-9.47	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2346	Active	6/17/2026 9:17:36 AM	1.4	78.1	0.5	20.0			189.8	189.6	-5.02	-3.13	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2346	Active	6/17/2026 9:19:04 AM	1.3	77.2	0.4	21.1			188.9	189.0	-1.27	-1.24	Valve Adjustment:No Flow Measurement,High Temp
CV-2347	Active	6/2/2026 7:40:00 AM					1000						AirTech Lab
CV-2347	Active	6/2/2026 7:40:00 AM						55000					AirTech Lab; [User entered 5.5%]
CV-2347	Active	6/2/2026 9:01:41 AM	15.5	63.6	0.0	20.9			108.0	107.8	-3.93	-3.92	
CV-2347	Active	6/16/2026 8:17:59 AM	15.3	67.9	0.2	16.6			114.6	115.7	-2.33	-2.31	
CV-2348	Active	6/2/2026 7:30:00 AM					130						AirTech Lab
CV-2348	Active	6/2/2026 7:30:00 AM						9000					AirTech Lab; [User entered 0.90%]
CV-2348	Active	6/2/2026 9:24:08 AM	23.8	38.9	0.0	37.3			124.7	124.8	-10.77	-10.79	
CV-2348	Active	6/10/2026 1:32:39 PM	19.6	53.1	0.0	27.3			131.8	131.8	-5.84	-5.84	,
CV-2348	Active	6/10/2026 1:34:08 PM	19.8	50.7	0.0	29.5			132.2	132.2	-6.11	-6.09	,
CV-2348	Active	6/16/2026 8:24:15 AM	21.6	54.1	0.0	24.3			134.3	134.4	-7.90	-7.05	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-2348	Active	6/16/2026 8:24:47 AM	22.0	54.7	0.0	23.3			134.4	134.4	-7.09	-7.05	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header
CV-2349	Active	6/2/2026 8:30:00 AM					2900						AirTech Lab
CV-2349	Active	6/2/2026 8:30:00 AM						150000					AirTech Lab; [User entered 15%]
CV-2349	Active	6/3/2026 10:34:57 AM	9.8	76.6	0.0	13.6			159.0	161.1	0.44	-0.19	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-2349	Active	6/3/2026 10:35:45 AM	11.2	79.8	0.0	9.0			161.6	161.3	-0.20	-0.59	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header;Well Condition:Lorentz Pump Installed;Well Repairs:Surging
CV-2349	Active	6/3/2026 10:40:00 AM						129950					AtmAA; [User entered 12.995%]
CV-2349	Active	6/10/2026 1:32:14 PM	17.2	76.0	0.9	5.9			158.4	159.9	-5.53	-4.35	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2349	Active	6/10/2026 1:33:11 PM	21.0	76.8	0.1	2.1			160.5	160.7	-5.11	-5.15	Valve Adjustment:No Flow Measurement,High Temp
CV-2349	Active	6/17/2026 10:35:04 AM	3.3	79.0	0.0	17.7			161.8	161.6	-0.96	-1.56	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum

Table 2. Monthly LEA Selected Wells - June 2026
Chiquita Canyon Landfill

Point Name	Status	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Well Temp [°F]	Adj Well Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2349	Active	6/17/2026 10:35:26 AM	2.9	74.7	0.0	22.4			160.6	160.5	-2.04	-1.95	Valve Adjustment:No Flow Measurement,High Temp
CV-2350	Active	6/2/2026 8:15:00 AM					3800						AirTech Lab
CV-2350	Active	6/2/2026 8:15:00 AM						170000					AirTech Lab; [User entered 17%]
CV-2350	Active	6/2/2026 8:32:01 AM	4.2	78.7	0.0	17.1			104.3	104.6	-9.98	-8.20	Valve Adjustment:Decreased Flow/Vacuum
CV-2350	Active	6/17/2026 8:33:21 AM	4.9	75.2	0.0	19.9			90.5	90.5	-7.19	-6.04	Valve Adjustment:Decreased Flow/Vacuum
CV-2351	Active	6/1/2026 9:00:00 AM					17						AirTech Lab
CV-2351	Active	6/1/2026 9:00:00 AM						1700					AirTech Lab; [User entered 0.17%]
CV-2351	Active	6/1/2026 12:22:24 PM	0.0	1.4	20.6	78.0			97.0	97.6	-4.58	-4.57	Valve Adjustment:NSPS/EG CAI,Surging Liquid in Well (Watered In);Well Comment:Pump is not pumping
CV-2351	Active	6/1/2026 12:24:29 PM	0.0	0.6	20.7	78.7			99.2	99.5	-4.59	-4.47	
CV-2351	Active	6/16/2026 8:45:00 AM					13						Air Tech Lab
CV-2351	Active	6/16/2026 8:45:00 AM						4100					Air Tech Lab; [User entered 0.41%]
CV-2351	Active	6/17/2026 9:15:56 AM	0.1	1.6	20.6	77.7			90.5	90.5	-1.35	-1.33	Valve Adjustment:NSPS/EG CAI,High O2
CV-2351	Active	6/17/2026 9:16:22 AM	0.1	1.5	20.5	77.9			90.5	90.5	-1.34	-1.37	Valve Adjustment:NSPS/EG CAI,High O2
CV-2352	Active	6/1/2026 9:10:00 AM					630						AirTech Lab
CV-2352	Active	6/1/2026 9:10:00 AM						100000					AirTech Lab; [User entered 10%]
CV-2352	Active	6/1/2026 12:43:45 PM	1.2	44.3	9.9	44.6			130.4	130.4	-4.04	-1.53	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-2352	Active	6/1/2026 12:44:54 PM	1.3	43.6	9.9	45.2			129.0	128.7	-1.90	-1.91	
CV-2352	Active	6/17/2026 9:28:04 AM	3.1	76.9	1.1	18.9			90.5	90.5	-2.67	-2.52	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum
CV-2353-PLR	Active	6/11/2026 10:42:44 AM	3.6	63.3	3.1	30.0			134.1	135.1	-5.79	-5.65	NSPS/EG CAI,High Temp
CV-2353-PLR	Active	6/11/2026 10:46:22 AM	4.5	58.9	4.3	32.3			138.7	138.7	-5.09	-3.67	NSPS/EG CAI,High Temp
CV-2353-PLR	Active	6/12/2026 10:14:03 AM	3.4	73.8	0.7	22.1			183.0	183.4	0.28	-0.34	NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-2353-PLR	Active	6/12/2026 10:16:08 AM	2.8	74.8	0.5	21.9			182.5	182.1	-0.55	-0.43	NSPS/EG CAI,High Temp
CV-2353-PLR	Active	6/15/2026 8:25:00 AM					710						Air Tech Lab
CV-2353-PLR	Active	6/15/2026 8:25:00 AM						200000					Air Tech Lab; [User entered 20%]
CV-2353-PLR	Active	6/15/2026 2:58:08 PM	3.6	74.5	0.3	21.6			132.9	132.4	-6.61	-4.68	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,Decreased Flow/Vacuum
CV-2353-PLR	Active	6/15/2026 2:59:49 PM	4.1	63.7	2.4	29.8			132.1	132.1	-2.62	-2.67	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-2353-PLR	Active	6/17/2026 9:38:30 AM	11.7	76.3	0.0	12.0			187.5	188.4	-7.05	-6.71	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-2353-PLR	Active	6/17/2026 9:38:59 AM	12.8	76.6	0.0	10.6			188.5	189.5	-6.71	-6.71	Valve Adjustment:NSPS/EG CAI,High Temp

Table 2. Monthly LEA Selected Wells - June 2026
Chiquita Canyon Landfill

Point Name	Status	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Well Temp [°F]	Adj Well Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2354	Active	6/3/2026 10:45:40 AM	23.8	73.8	0.0	2.4			176.0	176.5	0.51	0.33	Valve Comment:Lorentz pump on;Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Increased Flow/Vacuum,Valve 100% Open;Well Condition:Lorentz Pump Installed;Well Repairs:Valve
CV-2354	Active	6/3/2026 10:47:46 AM	26.2	73.8	0.0	0.0			177.2	177.2	1.19	1.36	Valve Comment:Bad valve in well;Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open;Well Condition:Lorentz Pump Installed;Well Repairs:Valve
CV-2354	Active	6/3/2026 10:50:00 AM						143400					AtmAA; [User entered 14.34%]
CV-2354	Active	6/8/2026 1:27:32 PM	6.0	75.0	0.0	19.0			179.6	180.4	-3.05	-2.96	Valve Adjustment:NSPS/EG CAI,High Temp;Well Comment:Vacuum fluctuating
CV-2354	Active	6/8/2026 1:28:00 PM	5.3	77.2	0.0	17.5			181.0	181.2	-3.07	-2.95	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2354	Active	6/10/2026 1:14:12 PM	21.5	74.9	0.0	3.6			179.8	180.0	-2.72	-2.51	Valve Adjustment:No Flow Measurement,High Temp
CV-2354	Active	6/15/2026 8:10:00 AM					2200						Air Tech Lab
CV-2354	Active	6/15/2026 8:10:00 AM						180000					Air Tech Lab; [User entered 18%]
CV-2354	Active	6/17/2026 10:43:17 AM	4.7	74.0	0.0	21.3			183.1	183.6	-0.56	-0.53	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-24002	Active	6/1/2026 1:41:05 PM	45.0	53.1	0.1	1.8			100.0	100.1	-0.56	-0.52	Valve Adjustment:Barely Open
CV-24002	Active	6/17/2026 9:17:33 AM	46.5	50.2	0.0	3.3			101.8	107.7	-1.62	-1.62	Valve Adjustment:Barely Open,Surging Liquid in Well (Watered In)
CV-24003	Active	6/1/2026 9:47:33 AM	19.0	26.2	11.5	43.3			89.0	89.5	-0.80	-0.80	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24003	Active	6/5/2026 9:17:13 AM	1.3	1.0	19.9	77.8			87.1	89.2	-1.35	-1.35	Valve Adjustment:Orifice Plate Changed (See OP Log),High O2
CV-24003	Active	6/17/2026 9:05:11 AM	43.5	47.7	0.8	8.0			81.6	82.4	-0.14	-0.14	Valve Adjustment:Barely Open,Surging Liquid in Header
CV-24007	Active	6/1/2026 2:43:27 PM	23.6	58.5	1.2	16.7			147.5	147.4	-1.09	-1.24	Valve Adjustment:High Temp
CV-24007	Active	6/2/2026 9:10:01 AM	48.1	47.0	2.8	2.1			143.5	144.0	-3.52	-1.95	Valve Adjustment:Decreased Flow/Vacuum
CV-24007	Active	6/2/2026 9:14:26 AM	35.7	49.9	2.3	12.1			138.2	138.2	-1.65	-1.65	Valve Adjustment:Barely Open
CV-24007	Active	6/15/2026 9:35:00 AM					470						Air Tech Lab
CV-24007	Active	6/15/2026 9:35:00 AM						63000					Air Tech Lab; [User entered 6.3%]
CV-24007	Active	6/17/2026 9:53:11 AM	24.8	52.7	2.4	20.1			142.8	142.8	-0.82	-0.82	
CV-24017	Active	6/2/2026 9:23:32 AM	16.0	76.4	0.1	7.5			180.9	181.1	-3.74	-2.31	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum

Table 2. Monthly LEA Selected Wells - June 2026
Chiquita Canyon Landfill

Point Name	Status	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24017	Active	6/2/2026 9:24:13 AM	15.4	76.1	0.0	8.5			181.1	180.9	-2.23	-2.39	Valve Adjustment:No Flow Measurement,High Temp
CV-24017	Active	6/2/2026 9:25:00 AM					2630						AtmAA
CV-24017	Active	6/2/2026 9:25:00 AM						160300					AtmAA; [User entered 16.03%]
CV-24017	Active	6/9/2026 9:22:05 AM	16.6	76.9	0.0	6.5			177.0	179.4	-1.69	-1.87	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	Active	6/15/2026 9:45:00 AM					1500						Air Tech Lab
CV-24017	Active	6/15/2026 9:45:00 AM						160000					Air Tech Lab; [User entered 16%]
CV-24017	Active	6/16/2026 9:21:32 AM	19.9	69.7	0.7	9.7			180.4	181.6	-7.71	-5.24	Valve Comment:Upon arrival fount pump removed from well;Valve Adjustment:No Flow Measurement,High Temp
CV-24017	Active	6/16/2026 9:23:09 AM	17.9	69.8	0.6	11.7			181.5	181.4	-3.84	-4.02	Valve Adjustment:No Flow Measurement,High Temp
CV-24017	Active	6/23/2026 9:49:36 AM	11.0	73.3	0.2	15.5			183.3	183.5	-2.11	-2.29	Valve Comment:Pump removed;Valve Adjustment:No Flow Measurement,High Temp
CV-24017	Active	6/29/2026 10:14:31 AM	6.4	76.0	0.6	17.0			188.0	188.4	-3.88	-3.78	Valve Adjustment:High Temp
CV-24049	Active	6/1/2026 1:29:08 PM	16.4	76.2	0.0	7.4			188.9	188.9	-2.84	-2.51	Valve Comment:Surging in header;Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header;Well Repairs:Surging
CV-24049	Active	6/1/2026 1:40:00 PM					2550						AtmAA
CV-24049	Active	6/1/2026 1:40:00 PM						151200					AtmAA; [User entered 15.12%]
CV-24049	Active	6/4/2026 9:00:00 AM					2800						AirTech Lab
CV-24049	Active	6/4/2026 9:00:00 AM						160000					Air Tech Lab; [User entered 16%]
CV-24049	Active	6/8/2026 1:38:10 PM	8.5	80.2	0.0	11.3			177.7	177.5	-3.39	-3.24	Valve Adjustment:No Flow Measurement,High Temp
CV-24049	Active	6/15/2026 9:57:07 AM	19.5	72.7	0.0	7.8			189.0	189.3	-2.45	-2.46	Valve Comment:Surging in header;Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header;Well Repairs:Surging
CV-24049	Active	6/22/2026 1:22:35 PM	13.0	75.3	0.0	11.7			183.7	184.4	-1.11	-1.26	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header
CV-24049	Active	6/29/2026 2:11:03 PM	8.8	75.0	0.0	16.2			185.9	186.0	-8.56	-8.34	Valve Adjustment:No Flow Measurement,High Temp
CV-24053	Active	6/3/2026 7:40:00 AM					110						AirTech Lab
CV-24053	Active	6/3/2026 7:40:00 AM						8500					Air Tech Lab; [User entered 0.85%]
CV-24053	Active	6/4/2026 8:58:29 AM	38.5	46.3	1.1	14.1			102.6	100.1	-7.12	-1.63	Valve Adjustment:Decreased Flow/Vacuum,Barely Open

Table 2. Monthly LEA Selected Wells - June 2026
Chiquita Canyon Landfill

Point Name	Status	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24053	Active	6/22/2026 2:17:18 PM	35.4	59.7	0.2	4.7			95.8	95.8	-1.08	-1.07	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24055	Active	6/4/2026 10:40:08 AM	9.0	68.6	1.0	21.4			132.7	132.2	-0.53	-0.46	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-24055	Active	6/4/2026 10:41:12 AM	9.0	68.8	1.0	21.2			132.1	132.1	-0.53	-0.59	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24055	Active	6/12/2026 8:00:00 AM					720						Air Tech Lab
CV-24055	Active	6/12/2026 8:00:00 AM						45000					Air Tech Lab; [User entered 4.5%]
CV-24055	Active	6/23/2026 9:47:37 AM	13.6	65.9	1.1	19.4			127.6	127.6	-0.46	-0.46	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24062	Active	6/10/2026 10:20:42 AM	20.6	73.4	0.0	6.0			165.2	164.6	-0.40	-0.46	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-24062	Active	6/10/2026 10:21:48 AM	20.1	73.6	0.0	6.3			164.4	164.3	-1.32	-1.28	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24062	Active	6/12/2026 8:50:00 AM					33						Air Tech Lab
CV-24062	Active	6/12/2026 8:50:00 AM						4500					Air Tech Lab; [User entered 0.45%]
CV-24062	Active	6/16/2026 2:32:33 PM	42.8	56.9	0.3	0.0			149.0	147.7	-7.92	-3.82	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24062	Active	6/16/2026 2:33:39 PM	41.3	58.6	0.0	0.1			146.0	146.3	-2.16	-2.17	Valve Adjustment:No Flow Measurement,High Temp
CV-24062	Active	6/24/2026 9:42:09 AM	47.5	52.5	0.0	0.0			145.3	143.8	-5.74	-4.49	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24062	Active	6/24/2026 9:44:44 AM	46.2	53.8	0.0	0.0			143.6	143.3	-4.22	-4.19	Valve Adjustment:No Flow Measurement,High Temp
CV-24062	Active	6/30/2026 8:52:28 AM	23.6	65.6	0.2	10.6			164.8	161.4	-12.81	-11.79	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24063	Active	6/3/2026 1:21:07 PM	28.6	71.4	0.0	0.0			176.3	175.8	-3.77	-3.83	Valve Adjustment:No Flow Measurement,High Temp
CV-24063	Active	6/3/2026 1:25:00 PM						80200					AtmAA; [User entered 8.02%]
CV-24063	Active	6/10/2026 2:12:26 PM	16.6	79.9	0.0	3.5			174.8	174.7	-4.63	-4.31	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24063	Active	6/12/2026 10:10:00 AM					190						Air Tech Lab

Table 2. Monthly LEA Selected Wells - June 2026
Chiquita Canyon Landfill

Point Name	Status	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24063	Active	6/12/2026 10:10:00 AM						11000					Air Tech Lab; [User entered 1.1%]
CV-24063	Active	6/17/2026 2:30:04 PM	3.6	61.5	4.7	30.2			177.0	174.6	-8.34	-3.87	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24063	Active	6/17/2026 2:32:22 PM	3.9	67.4	3.7	25.0			176.4	177.7	-2.14	-1.92	Valve Comment:Lorenz pump disconnected;Valve Adjustment:No Flow Measurement,High Temp
CV-24063	Active	6/24/2026 9:23:23 AM	10.5	58.2	4.8	26.5			182.1	185.5	-3.69	-0.61	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24063	Active	6/24/2026 9:25:59 AM	12.3	73.4	4.8	9.5			184.6	184.8	-0.93	-0.57	Valve Comment:Pump disconnected;Valve Adjustment:No Flow Measurement,High Temp
CV-24063	Active	6/29/2026 1:17:06 PM	12.9	82.3	0.0	4.8			186.8	188.2	-10.29	-10.12	Valve Adjustment:High Temp
CV-24064	Active	6/3/2026 1:28:32 PM	21.6	78.4	0.0	0.0			187.2	187.5	-10.45	-10.73	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24064	Active	6/3/2026 1:40:00 PM						74600					AtmAA; [User entered 7.46%]
CV-24064	Active	6/10/2026 2:23:47 PM	19.9	75.4	0.0	4.7			191.0	191.4	-10.84	-12.25	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In)
CV-24064	Active	6/12/2026 8:35:00 AM					140						Air Tech Lab
CV-24064	Active	6/12/2026 8:35:00 AM						11000					Air Tech Lab; [User entered 1.1%]
CV-24064	Active	6/24/2026 9:09:36 AM	11.0	79.3	0.0	9.7			189.3	188.5	-11.67	-11.46	Valve Adjustment:No Flow Measurement,High Temp
CV-24064	Active	6/30/2026 2:26:34 PM	9.7	80.2	0.0	10.1			192.7	191.9	-11.35	-11.46	Valve Adjustment:No Flow Measurement,High Temp
CV-24065-TP1	Active	6/4/2026 10:11:00 AM	13.4	76.0	1.4	9.2			85.5	85.6	-0.55	-0.48	Valve Adjustment:Barely Open
CV-24065-TP1	Active	6/11/2026 7:40:00 AM					250						Air Tech Lab
CV-24065-TP1	Active	6/11/2026 7:40:00 AM						7100					Air Tech Lab; [User entered 0.71%]
CV-24065-TP1	Active	6/17/2026 2:10:47 PM	14.9	68.7	2.5	13.9			92.0	92.0	-0.42	-0.44	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24066	Active	6/2/2026 7:57:31 AM	20.7	50.9	0.0	28.4			103.0	103.8	-2.06	-1.87	Valve Adjustment:Decreased Flow/Vacuum
CV-24066	Active	6/15/2026 7:50:00 AM					280						Air Tech Lab
CV-24066	Active	6/15/2026 7:50:00 AM						30000					Air Tech Lab; [User entered 3.0%]
CV-24066	Active	6/16/2026 7:41:54 AM	25.7	49.2	0.0	25.1			104.1	105.3	-1.15	-1.16	
CV-24069	Active	6/3/2026 9:58:36 AM	12.0	74.8	0.0	13.2			124.7	125.1	0.14	-0.06	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open,Surging Liquid in Header

Table 2. Monthly LEA Selected Wells - June 2026
Chiquita Canyon Landfill

Point Name	Status	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24069	Active	6/3/2026 9:59:30 AM	11.4	79.4	0.0	9.2			125.4	125.4	-0.09	-0.09	Valve Adjustment:NSPS/EG CAC,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24069	Active	6/11/2026 9:28:47 AM	13.1	69.3	0.0	17.6			131.4	131.9	-0.02	-0.63	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum;Well Comment:pump active;Well Condition:Lorentz Pump Installed
CV-24069	Active	6/11/2026 12:10:39 PM	11.7	57.3	1.9	29.1			124.2	125.1	-0.56	-0.50	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-24069	Active	6/11/2026 12:19:47 PM	11.7	66.3	0.4	21.6			125.7	125.4	-0.15	-0.13	Valve Comment:Secured lorentz fitting;Well Condition:Lorentz Pump Installed
CV-24069	Active	6/15/2026 8:00:00 AM					1100						Air Tech Lab
CV-24069	Active	6/15/2026 8:00:00 AM						120000					Air Tech Lab; [User entered 12%]
CV-24069	Active	6/16/2026 9:36:41 AM	11.3	71.9	0.0	16.8			137.4	140.4	0.13	-0.10	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-24069	Active	6/16/2026 9:37:03 AM	12.0	76.2	0.0	11.8			140.3	140.6	-0.25	-0.26	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24069	Active	6/16/2026 9:37:50 AM	12.2	76.5	0.0	11.3			140.4	140.1	-0.23	-0.23	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-24070	Active	6/3/2026 10:03:54 AM	25.5	68.2	0.0	6.3			135.9	135.6	-2.40	-1.57	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24070	Active	6/3/2026 10:04:21 AM	26.7	68.2	0.4	4.7			135.4	135.3	-1.34	-1.34	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24070	Active	6/12/2026 9:10:00 AM					600						Air Tech Lab
CV-24070	Active	6/12/2026 9:10:00 AM						55000					Air Tech Lab; [User entered 5.5%]
CV-24070	Active	6/24/2026 1:12:10 PM	7.3	77.7	0.0	15.0			140.8	140.9	-0.39	-0.39	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-24070	Active	6/24/2026 1:12:40 PM	7.0	82.3	0.0	10.7			141.1	141.1	-0.41	-0.40	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24071	Active	6/3/2026 2:29:39 PM	44.3	53.3	0.4	2.0			120.5	120.7	-4.29	-4.30	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24071	Active	6/12/2026 9:00:00 AM					290						Air Tech Lab
CV-24071	Active	6/12/2026 9:00:00 AM						36000					Air Tech Lab; [User entered 3.6%]
CV-24071	Active	6/22/2026 10:12:46 AM	33.2	62.8	0.0	4.0			134.3	134.7	-1.95	-1.83	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header

Table 2. Monthly LEA Selected Wells - June 2026
Chiquita Canyon Landfill

Point Name	Status	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24071	Active	6/22/2026 10:13:06 AM	32.3	64.9	0.0	2.8			134.6	134.6	-1.82	-1.82	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24075-TP1	Active	6/1/2026 2:36:56 PM	18.3	75.8	1.1	4.8			186.8	186.7	-10.73	-10.62	Valve Comment:Cant adjust well side;Valve Adjustment:No Flow Measurement,High Temp
CV-24075-TP1	Active	6/1/2026 2:40:00 PM					2500						AtmAA
CV-24075-TP1	Active	6/1/2026 2:40:00 PM						112600					AtmAA; [User entered 11.26%]
CV-24075-TP1	Active	6/10/2026 2:18:34 PM	16.0	75.4	1.2	7.4			186.5	186.6	-12.43	-12.33	Valve Comment:Cant adjust valve;Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24075-TP1	Active	6/24/2026 9:17:11 AM	8.9	73.6	2.3	15.2			186.9	186.8	-12.03	-12.13	Valve Adjustment:No Flow Measurement,High Temp
CV-24075-TP1	Active	6/30/2026 2:19:22 PM	9.6	79.6	0.8	10.0			186.1	185.9	-14.16	-14.49	Valve Adjustment:No Flow Measurement,High Temp
CV-24077	Active	6/1/2026 2:47:35 PM	34.8	46.9	0.0	18.3			139.3	138.9	-5.75	-5.77	Valve Adjustment:NSPS/EG CAC,No Flow Measurement
CV-24077	Active	6/2/2026 7:49:32 AM	12.4	67.4	0.0	20.2			144.6	144.7	-2.92	-0.93	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24077	Active	6/2/2026 7:52:34 AM	5.8	84.4	0.0	9.8			142.7	137.0	-2.48	-1.75	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24077	Active	6/11/2026 3:08:29 PM	16.3	58.0	0.3	25.4			144.0	148.3	-7.77	-4.90	,
CV-24077	Active	6/11/2026 3:10:14 PM	10.1	79.0	0.2	10.7			149.1	149.0	-3.96	-3.96	,
CV-24077	Active	6/15/2026 2:24:46 PM	7.5	77.6	0.0	14.9			152.1	152.1	-2.86	-2.90	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24077	Active	6/16/2026 7:33:30 AM	16.3	42.8	0.0	40.9			144.4	143.9	-7.05	-5.41	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24077	Active	6/16/2026 7:35:27 AM	15.8	49.1	0.0	35.1			143.7	144.1	-3.15	-3.27	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24077	Active	6/19/2026 10:22:28 AM	12.7	68.2	0.1	19.0			150.4	150.1	-3.94	-3.82	High Temp,
CV-24077	Active	6/19/2026 10:23:54 AM	12.6	68.8	0.0	18.6			151.0	151.2	-3.48	-3.79	,
CV-24077	Active	6/24/2026 1:14:10 PM	37.6	61.9	0.0	0.5			151.4	151.2	-4.93	-4.93	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24077	Active	6/30/2026 11:17:02 AM	13.9	59.7	0.4	26.0			147.3	149.1	-9.33	-5.61	NSPS/EG CAI,High Temp
CV-24077	Active	6/30/2026 11:19:14 AM	11.9	69.5	0.1	18.5			149.0	149.0	-5.96	-5.96	,
CV-24079-TP8	Active	6/4/2026 12:07:14 PM	34.8	54.8	0.0	10.4			150.1	147.9	-2.22	-1.24	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24079-TP8	Active	6/4/2026 12:09:00 PM	27.2	61.4	0.0	11.4			147.5	148.2	-1.10	-1.11	Well Condition:Lorentz Pump Installed
CV-24079-TP8	Active	6/9/2026 1:56:55 PM	51.6	48.4	0.0	0.0			153.6	154.2	-2.17	-3.60	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum

Table 2. Monthly LEA Selected Wells - June 2026
Chiquita Canyon Landfill

Point Name	Status	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24079-TP8	Active	6/9/2026 1:57:28 PM	50.6	49.4	0.0	0.0			153.2	153.7	-3.78	-3.78	Valve Adjustment:No Flow Measurement,High Temp
CV-24079-TP8	Active	6/16/2026 1:51:51 PM	58.8	41.2	0.0	0.0			145.5	145.8	-4.38	-4.40	Valve Adjustment:No Flow Measurement,High Temp
CV-24079-TP8	Active	6/23/2026 2:42:01 PM	56.2	43.7	0.0	0.1			149.5	150.2	-3.13	-3.07	Valve Adjustment:No Flow Measurement,High Temp
CV-24079-TP8	Active	6/30/2026 10:39:33 AM	37.7	51.7	0.0	10.6			143.3	142.7	-5.81	-5.89	Valve Adjustment:No Flow Measurement,High Temp
CV-24082	Active	6/3/2026 2:39:26 PM	30.1	63.4	0.0	6.5			115.8	115.7	-0.24	-0.23	Valve Adjustment:Barely Open
CV-24082	Active	6/16/2026 10:19:49 AM	36.5	61.4	0.0	2.1			122.0	122.5	-0.93	-0.73	Valve Adjustment:Decreased Flow/Vacuum
CV-24083	Active	6/3/2026 2:36:38 PM	42.9	54.0	0.0	3.1			115.5	116.1	-0.84	-0.82	Valve Adjustment:Barely Open
CV-24083	Active	6/22/2026 10:20:18 AM	20.3	72.6	0.0	7.1			148.5	149.8	-0.16	-0.16	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header
CV-24083	Active	6/22/2026 10:20:37 AM	19.5	73.4	0.0	7.1			148.3	149.8	-0.18	-0.18	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24084-TP1	Active	6/2/2026 2:30:00 PM					2240						AtmAA
CV-24084-TP1	Active	6/2/2026 2:30:05 PM	14.9	80.1	0.0	5.0			181.3	181.6	-5.74	-5.05	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24084-TP1	Active	6/11/2026 9:56:54 AM	16.4	75.9	0.0	7.7			182.6	182.7	-3.92	-3.06	Valve Adjustment:No Flow Measurement,High Temp
CV-24084-TP1	Active	6/16/2026 2:12:06 PM	11.3	79.7	0.0	9.0			183.4	183.4	-1.28	-1.04	Valve Adjustment:No Flow Measurement,High Temp
CV-24084-TP1	Active	6/24/2026 9:57:44 AM	14.5	77.8	0.0	7.7			183.1	183.1	-4.72	-4.72	Valve Adjustment:No Flow Measurement,High Temp
CV-24084-TP1	Active	6/30/2026 1:30:00 PM	7.7	78.4	0.0	13.9			183.1	183.1	-6.02	-5.94	Valve Adjustment:No Flow Measurement,High Temp
CV-24088	Active	6/3/2026 2:54:01 PM	37.3	58.0	0.0	4.7			115.0	115.6	-0.56	-0.56	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24088	Active	6/22/2026 1:23:31 PM	47.0	48.3	0.0	4.7			110.7	110.5	-1.17	-1.17	
CV-24095	Active	6/3/2026 10:39:26 AM	18.6	76.9	0.2	4.3			179.3	179.5	0.58	0.78	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-24095	Active	6/3/2026 10:40:36 AM	18.3	77.3	0.0	4.4			179.7	179.8	0.98	1.64	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.
CV-24095	Active	6/3/2026 10:45:00 AM						148300					AtmAA; [User entered 14.83%]
CV-24095	Active	6/8/2026 1:35:18 PM	3.2	77.2	0.0	19.6			181.0	181.2	-4.34	-4.30	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24095	Active	6/8/2026 1:36:04 PM	3.0	79.7	0.0	17.3			181.5	181.6	-3.80	-3.83	Valve Adjustment:NSPS/EG CAI,High Temp

Table 2. Monthly LEA Selected Wells - June 2026
Chiquita Canyon Landfill

Point Name	Status	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24095	Active	6/10/2026 1:17:22 PM	22.2	76.4	0.0	1.4			180.5	180.5	-5.03	-4.58	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24095	Active	6/16/2026 8:20:00 AM					2500						Air Tech Lab
CV-24095	Active	6/16/2026 8:20:00 AM						170000					Air Tech Lab; [User entered 17%]
CV-24095	Active	6/17/2026 10:38:51 AM	3.1	82.6	0.0	14.3			182.2	182.1	-0.43	-0.38	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-24096	Active	6/11/2026 10:32:09 AM	23.4	31.7	8.7	36.2			98.7	98.7	-1.54	-1.47	NSPS/EG CAI,High O2
CV-24096	Active	6/11/2026 10:33:45 AM	26.9	36.4	7.0	29.7			98.8	98.7	-1.27	-1.19	NSPS/EG CAI,High O2
CV-24096	Active	6/12/2026 9:48:27 AM	29.1	43.7	4.5	22.7			97.3	97.7	-0.40	-0.13	No Flow Measurement,
CV-24096	Active	6/25/2026 11:07:44 AM	43.4	54.4	0.0	2.2			88.3	88.8	0.17	-0.02	NSPS/EG CAI,No Flow Measurement,Positive Static Press.,Reduced System Vacuum
CV-24096	Active	6/25/2026 11:09:58 AM	38.7	53.0	1.3	7.0			89.3	89.3	-0.17	-0.14	NSPS/EG CAC,No Flow Measurement,Reduced System Vacuum
CV-24097	Active	6/10/2026 10:19:39 AM	38.6	37.7	3.9	19.8			85.8	86.9	-5.97	-4.71	,
CV-24097	Active	6/16/2026 7:47:31 AM	50.4	46.2	0.1	3.3			104.3	105.2	-3.58	-5.52	Valve Adjustment:Increased Flow/Vacuum,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-24098	Active	6/10/2026 8:26:44 AM	44.7	41.8	2.2	11.3			83.3	83.6	-10.77	-11.78	No Adjustment Made,
CV-24098	Active	6/25/2026 10:59:13 AM	41.9	40.9	3.0	14.2			83.7	83.7	-9.94	-9.56	No Flow Measurement,
CV-24099	Active	6/11/2026 10:15:38 AM	14.2	47.5	6.5	31.8			96.4	96.5	-5.28	-5.17	NSPS/EG CAI,High O2
CV-24099	Active	6/11/2026 10:19:14 AM	4.1	16.1	15.9	63.9			96.2	96.3	-4.76	-4.21	NSPS/EG CAI,High O2
CV-24099	Active	6/12/2026 9:26:51 AM	19.2	70.6	1.3	8.9			91.4	91.5	-0.66	-0.55	,
CV-24099	Active	6/17/2026 10:19:03 AM	34.7	65.3	0.0	0.0			87.1	88.1	1.48	-0.58	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
CV-24099	Active	6/17/2026 10:22:36 AM	33.8	66.2	0.0	0.0			88.2	88.3	-0.61	-0.59	Valve Adjustment:NSPS/EG CAC
CV-24100	Active	6/1/2026 9:40:00 AM					42						AirTech Lab
CV-24100	Active	6/1/2026 9:40:00 AM						6700					AirTech Lab; [User entered 0.67%]
CV-24100	Active	6/3/2026 10:14:54 AM	35.0	65.0	0.0	0.0			151.0	150.7	-1.55	-1.56	Valve Adjustment:No Flow Measurement,High Temp
CV-24100	Active	6/3/2026 10:15:00 AM						15000					AtmAA; [User entered 1.5%]
CV-24100	Active	6/10/2026 1:48:21 PM	32.7	67.1	0.2	0.0			152.5	152.1	-6.93	-3.39	Valve Adjustment:No Flow Measurement,High Temp
CV-24100	Active	6/10/2026 1:50:08 PM	34.9	65.0	0.1	0.0			152.6	152.9	-4.58	-4.58	Valve Adjustment:No Flow Measurement,High Temp
CV-24100	Active	6/17/2026 8:28:06 AM	20.5	76.2	0.0	3.3			90.5	90.5	-1.25	-0.28	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header

Table 2. Monthly LEA Selected Wells - June 2026
Chiquita Canyon Landfill

Point Name	Status	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24100	Active	6/17/2026 10:27:26 AM	21.8	70.5	0.0	7.7			152.9	153.2	-0.17	-1.28	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24100	Active	6/17/2026 10:27:54 AM	20.6	73.5	0.0	5.9			152.9	153.6	-1.34	-1.33	Valve Adjustment:No Flow Measurement,High Temp
CV-24101	Active	6/10/2026 8:31:01 AM	43.9	50.4	0.0	5.7			107.6	111.3	-11.50	-10.58	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-24101	Active	6/16/2026 9:30:00 AM					110						Air Tech Lab
CV-24101	Active	6/16/2026 9:30:00 AM						0					Air Tech Lab; [User entered 0%]
CV-24101	Active	6/17/2026 8:21:54 AM	44.4	52.0	0.0	3.6			90.5	90.5	-7.23	-6.63	Valve Adjustment:Decreased Flow/Vacuum
CV-24102	Active	6/8/2026 1:06:02 PM	42.1	53.6	0.0	4.3			95.3	95.3	-0.76	-0.54	Valve Adjustment:Decreased Flow/Vacuum
CV-24102	Active	6/16/2026 8:47:00 AM	42.6	53.8	0.0	3.6			96.8	97.0	-0.15	-0.16	
CV-24120	Active	6/5/2026 1:09:53 PM	4.4	63.5	4.9	27.2			97.3	97.3	-7.77	-8.04	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24120	Active	6/10/2026 12:49:09 PM	11.2	78.3	1.4	9.1			122.4	123.2	-9.00	-6.28	,
CV-24120	Active	6/12/2026 9:55:00 AM					360						Air Tech Lab
CV-24120	Active	6/12/2026 9:55:00 AM						30000					Air Tech Lab; [User entered 3.0%]
CV-24120	Active	6/17/2026 1:11:35 PM	1.5	20.6	16.2	61.7			89.1	90.0	-8.24	-8.06	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Plugged/Pinched Suspected;Well Comment:pump is not active;Well Condition:Lorentz Pump Installed
CV-24120	Active	6/17/2026 1:13:40 PM	0.7	8.3	18.3	72.6			90.4	90.4	-8.06	-8.06	Valve Adjustment:High O2,Plugged/Pinched Suspected;Well Comment:Pump not active;Well Condition:Lorentz Pump Installed
CV-24121	Active	6/4/2026 8:00:00 AM					22						AirTech Lab
CV-24121	Active	6/4/2026 8:00:00 AM						2600					Air Tech Lab; [User entered 0.26%]
CV-24121	Active	6/8/2026 1:33:03 PM	12.3	32.3	10.7	44.7			89.5	89.6	-0.72	-0.69	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-24121	Active	6/8/2026 1:35:33 PM	12.1	32.2	10.7	45.1			89.2	88.4	-0.40	-0.39	Valve Adjustment:High O2,Increased Flow/Vacuum
CV-24121	Active	6/8/2026 1:37:57 PM	10.6	30.8	11.7	46.9			90.0	90.0	-0.26	-0.27	Valve Adjustment:High O2,Barely Open
CV-24121	Active	6/17/2026 1:02:38 PM	33.0	61.3	0.0	5.7			95.1		-0.28		Valve Adjustment:Increased Flow/Vacuum;Well Comment:No pump
CV-24121	Active	6/17/2026 1:03:08 PM	32.3	61.1	0.0	6.6			94.5	94.5	-3.46	-3.47	
CV-24122	Active	6/4/2026 8:20:00 AM					0						AirTech Lab
CV-24122	Active	6/4/2026 8:20:00 AM						0					Air Tech Lab; [User entered 0%]

Table 2. Monthly LEA Selected Wells - June 2026
Chiquita Canyon Landfill

Point Name	Status	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24122	Active	6/5/2026 10:41:55 AM	25.3	32.0	9.2	33.5			94.1	100.6	-7.77	-1.84	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24122	Active	6/5/2026 10:43:09 AM	11.1	14.0	15.9	59.0			101.0	101.0	-0.31	-0.25	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24122	Active	6/17/2026 12:45:58 PM	49.2	47.2	0.0	3.6			92.9	95.3	5.71	-1.07	Valve Comment:valve closed upon arrival;Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum;Well Comment:No pump
CV-24122	Active	6/17/2026 12:55:28 PM	41.5	39.9	3.9	14.7			95.7	95.7	-2.47	-2.50	Valve Adjustment:NSPS/EG CAC,Barely Open,Plugged/Pinched Suspected
CV-24123	Active	6/9/2026 2:05:21 PM	39.6	55.5	0.0	4.9			118.5	118.7	-3.59	-3.37	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum
CV-24123	Active	6/19/2026 1:07:56 PM	44.9	50.5	0.0	4.6			116.4	117.8	-0.63	-0.72	Valve Adjustment:Increased Flow/Vacuum
CV-24123	Active	6/24/2026 7:30:31 AM	42.9	53.6	0.0	3.5			117.6	117.6	-3.72	-3.79	Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum
CV-24125-TP2(	Active	6/3/2026 8:20:00 AM					12						AirTech Lab
CV-24125-TP2(	Active	6/3/2026 8:20:00 AM						1000					Air Tech Lab; [User entered 0.10%]
CV-24125-TP2(	Active	6/5/2026 10:14:30 AM	32.0	64.9	0.4	2.7			120.4	119.6	-5.39	-2.55	Valve Adjustment:Decreased Flow/Vacuum
CV-24125-TP2(	Active	6/5/2026 1:26:59 PM	19.3	74.0	0.9	5.8			88.5	88.7	-0.23	-0.23	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24125-TP2(	Active	6/11/2026 3:48:37 PM	34.4	65.0	0.5	0.1			115.3	116.6	-1.94	-1.14	,
CV-24125-TP2(	Active	6/17/2026 12:29:31 PM	38.8	56.6	0.0	4.6			106.3	106.7	-2.09	-2.08	Well Comment:pump is off;Well Condition:Pnumatic Pump Installed
CV-24125-TP2(	Active	6/17/2026 12:38:33 PM	39.3	56.6	0.0	4.1			108.9	108.9	-2.12	-2.13	Valve Comment:Belly in vacuum lateral;Valve Adjustment:Surging Liquid in Header;Well Comment:pump is off;Well Condition:Pnumatic Pump Installed
CV-24126	Active	6/1/2026 1:39:04 PM	12.4	71.2	0.0	16.4			187.5	187.5	-2.91	-2.43	Valve Adjustment:High Temp
CV-24126	Active	6/1/2026 1:55:00 PM					3345						AtmAA
CV-24126	Active	6/1/2026 1:55:00 PM						172800					AtmAA; [User entered 17.28%]
CV-24126	Active	6/8/2026 1:09:09 PM	4.0	80.1	0.0	15.9			187.9	187.1	-7.06	-8.08	Valve Adjustment:High Temp
CV-24126	Active	6/15/2026 10:13:34 AM	14.3	71.3	0.0	14.4			189.9	190.2	-4.91	-4.93	Valve Adjustment:High Temp
CV-24126	Active	6/22/2026 1:18:00 PM	16.6	74.7	0.0	8.7			188.8	188.7	-4.26	-4.25	Valve Adjustment:High Temp
CV-24126	Active	6/29/2026 1:46:26 PM	11.0	78.5	0.0	10.5			189.1	188.8	-6.40	-7.05	Valve Adjustment:No Flow Measurement,High Temp
CV-24127	Active	6/4/2026 9:10:00 AM					3700						AirTech Lab

Table 2. Monthly LEA Selected Wells - June 2026
Chiquita Canyon Landfill

Point Name	Status	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24127	Active	6/4/2026 9:10:00 AM						170000					Air Tech Lab; [User entered 17%]
CV-24127	Active	6/12/2026 8:12:32 AM	6.9	71.1	0.0	22.0			172.7	171.3	-5.54	-1.27	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24127	Active	6/12/2026 8:14:13 AM	3.6	78.0	0.0	18.4			171.5	171.8	-1.06	-1.06	
CV-24127	Active	6/15/2026 10:05:15 AM	28.7	69.0	0.0	2.3			161.0	162.3	-0.63	-0.65	Valve Adjustment:No Flow Measurement,High Temp
CV-24127	Active	6/22/2026 1:16:07 PM	18.9	73.6	0.0	7.5			160.9	160.0	-5.07	-5.43	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24127	Active	6/26/2026 10:26:04 AM	5.3	80.4	0.0	14.3			172.4	172.5	-2.29	-2.00	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24127	Active	6/26/2026 10:26:28 AM	5.2	82.1	0.0	12.7			172.4	172.9	-2.19	-2.23	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24127	Active	6/29/2026 1:43:55 PM	12.5	77.6	0.0	9.9			163.6	161.7	-7.25	-6.99	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24128	Active	6/3/2026 8:10:00 AM					180						AirTech Lab
CV-24128	Active	6/3/2026 8:10:00 AM						10000					Air Tech Lab; [User entered 1.0%]
CV-24128	Active	6/4/2026 2:19:54 PM	37.2	43.2	1.3	18.3			108.0	108.3	-1.44	-1.40	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24128	Active	6/10/2026 12:54:14 PM	20.8	65.0	0.7	13.5			124.6	124.6	-0.62	-0.62	,
CV-24128	Active	6/17/2026 1:41:36 PM	21.7	64.2	0.0	14.1			110.2	109.8	-0.36	-0.34	Valve Adjustment:Reduce Sys. Vac. - Flare Down;Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24134-TP1	Active	6/1/2026 1:35:53 PM	36.3	63.7	0.0	0.0			151.4	151.6	-2.22	-2.33	Valve Comment:Lorentz Pump pumping upon arrival;Valve Adjustment:No Flow Measurement,High Temp
CV-24134-TP1	Active	6/1/2026 1:50:00 PM					2930						AtmAA
CV-24134-TP1	Active	6/1/2026 1:50:00 PM						115900					AtmAA; [User entered 11.59%]
CV-24134-TP1	Active	6/8/2026 1:05:55 PM	24.6	71.4	0.0	4.0			152.0	152.5	-4.77	-4.80	Valve Comment:Pump on;Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24134-TP1	Active	6/15/2026 10:02:38 AM	41.5	58.5	0.0	0.0			151.6	151.9	-5.05	-5.05	Valve Comment:Upon arrival found pump on;Valve Adjustment:No Flow Measurement,High Temp
CV-24134-TP1	Active	6/22/2026 1:13:16 PM	40.9	59.1	0.0	0.0			152.4	152.1	-4.27	-4.27	Valve Adjustment:No Flow Measurement,High Temp
CV-24134-TP1	Active	6/29/2026 1:36:41 PM	33.3	66.7	0.0	0.0			153.8	153.9	-2.72	-2.71	Valve Adjustment:No Flow Measurement,High Temp
CV-24138	Active	6/1/2026 9:25:00 AM					740						AirTech Lab
CV-24138	Active	6/1/2026 9:25:00 AM						180000					AirTech Lab; [User entered 18%]

Table 2. Monthly LEA Selected Wells - June 2026
Chiquita Canyon Landfill

Point Name	Status	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24138	Active	6/10/2026 8:38:31 AM	1.5	69.6	0.5	28.4			170.1	169.1	-1.71	-8.11	NSPS/EG CAI,High Temp
CV-24138	Active	6/10/2026 8:42:15 AM	2.5	72.3	0.5	24.7			171.7	169.1	-3.35	-2.97	NSPS/EG CAI,High Temp
CV-24138	Active	6/11/2026 10:55:56 AM	15.2	68.2	0.0	16.6			160.2	160.8	-3.18	-3.61	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24138	Active	6/16/2026 8:25:00 AM					780						Air Tech Lab
CV-24138	Active	6/16/2026 8:25:00 AM						200000					Air Tech Lab; [User entered 20%]
CV-24138	Active	6/17/2026 8:54:02 AM	0.4	6.2	18.4	75.0			90.5	90.5	-2.51	-2.52	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In)
CV-24138	Active	6/17/2026 8:54:25 AM	0.5	6.8	18.2	74.5			90.5	90.5	-2.38	-2.34	Valve Adjustment:NSPS/EG CAI,High O2,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
CV-24138	Active	6/17/2026 1:42:39 PM	3.7	70.1	0.0	26.2			136.4	136.0	-2.01	-1.91	Valve Adjustment:No Flow Measurement,High Temp
CV-24138	Active	6/26/2026 9:57:18 AM	1.5	31.6	11.7	55.2			95.5	96.1	-4.64	-3.81	Valve Adjustment:NSPS/EG CAI,High O2
CV-24138	Active	6/26/2026 9:57:58 AM	1.5	32.1	11.6	54.8			96.4	96.7	-3.71	-3.75	Valve Adjustment:NSPS/EG CAI,High O2
CV-24139	Active	6/1/2026 9:20:00 AM					0						AirTech Lab
CV-24139	Active	6/1/2026 9:20:00 AM						9600					AirTech Lab; [User entered 0.96%]
CV-24139	Active	6/10/2026 8:49:20 AM	0.4	10.5	18.2	70.9			115.8	117.4	-6.96	-3.36	NSPS/EG CAI,High O2
CV-24139	Active	6/10/2026 8:51:40 AM	0.5	9.9	18.2	71.4			119.9	112.6	-2.75	-1.31	NSPS/EG CAI,High O2
CV-24139	Active	6/16/2026 8:30:00 AM					0						Air Tech Lab
CV-24139	Active	6/16/2026 8:30:00 AM						4900					Air Tech Lab; [User entered 0.49%]
CV-24139	Active	6/17/2026 9:00:45 AM	0.0	0.1	21.1	78.8			90.5	90.5	-5.68	-2.12	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-24139	Active	6/17/2026 9:01:29 AM	0.0	0.1	21.1	78.8			90.5	90.5	-0.25	-0.27	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open
CV-24139	Active	6/26/2026 10:05:15 AM	3.3	70.8	1.3	24.6			183.7	184.2	-5.09	-4.90	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24139	Active	6/26/2026 10:05:49 AM	3.8	71.8	0.8	23.6			184.1	184.1	-4.71	-4.72	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24140	Active	6/1/2026 9:15:00 AM					1100						AirTech Lab
CV-24140	Active	6/1/2026 9:15:00 AM						220000					AirTech Lab; [User entered 22%]
CV-24140	Active	6/3/2026 12:47:00 PM	16.3	70.3	0.0	13.4			162.2	162.6	-1.41	-1.69	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24140	Active	6/3/2026 12:55:00 PM						185700					AtmAA; [User entered 18.57%]
CV-24140	Active	6/10/2026 8:58:38 AM	2.7	73.1	0.3	23.9			172.6	178.2	-4.24	-3.59	High Temp,NSPS/EG CAI
CV-24140	Active	6/10/2026 9:02:51 AM	2.6	75.9	0.1	21.4			178.2	172.1	-3.53	-2.40	NSPS/EG CAI,High Temp

Table 2. Monthly LEA Selected Wells - June 2026
Chiquita Canyon Landfill

Point Name	Status	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24140	Active	6/10/2026 1:06:06 PM	26.7	66.4	0.0	6.9			166.6	168.3	-1.86	-1.86	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24140	Active	6/16/2026 8:35:00 AM					850						Air Tech Lab
CV-24140	Active	6/16/2026 8:35:00 AM						190000					Air Tech Lab; [User entered 19%]
CV-24140	Active	6/17/2026 1:29:57 PM	3.2	70.8	0.0	26.0			170.0	169.3	0.97	-1.59	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24140	Active	6/17/2026 1:30:23 PM	3.5	71.7	0.0	24.8			169.3	169.4	-1.54	-1.18	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-24140	Active	6/26/2026 10:09:15 AM	3.1	81.3	0.0	15.6			182.1	182.1	-2.54	-2.52	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24140	Active	6/26/2026 10:09:34 AM	3.0	80.0	0.0	17.0			181.5	181.7	-2.46	-2.46	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24141	Active	6/11/2026 11:16:59 AM	5.9	10.3	17.0	66.8			102.0	102.2	-5.05	-4.97	NSPS/EG CAI,High O2
CV-24141	Active	6/11/2026 11:18:59 AM	3.7	6.4	18.6	71.3			102.0	102.2	-5.05	-4.81	NSPS/EG CAI,High O2
CV-24141	Active	6/12/2026 9:30:00 AM					190						Air Tech Lab
CV-24141	Active	6/12/2026 9:30:00 AM						12000					Air Tech Lab; [User entered 1.2%]
CV-24141	Active	6/12/2026 10:41:06 AM	6.0	16.1	15.1	62.8			105.5	106.7	-0.85	-0.23	NSPS/EG CAI,High O2
CV-24141	Active	6/12/2026 10:43:21 AM	5.4	13.6	15.7	65.3			106.9	106.9	-0.59	-0.44	NSPS/EG CAI,High O2
CV-24141	Active	6/17/2026 9:19:34 AM	17.3	29.0	8.2	45.5			90.5	90.5	-0.92	-0.54	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open
CV-24141	Active	6/17/2026 9:20:54 AM	16.3	28.9	8.7	46.1			90.5	90.5	-0.92	-0.88	Valve Adjustment:NSPS/EG CAI,High O2
CV-24142	Active	6/4/2026 9:05:00 AM					1700						AirTech Lab
CV-24142	Active	6/4/2026 9:05:00 AM						150000					Air Tech Lab; [User entered 15%]
CV-24142	Active	6/11/2026 1:39:28 PM	3.0	64.4	2.3	30.3			112.7	113.1	-5.90	-5.74	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24142	Active	6/17/2026 8:43:53 AM	6.0	68.0	2.1	23.9			90.5	90.5	-1.65	-1.57	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-24142	Active	6/26/2026 9:52:53 AM	3.8	64.3	4.3	27.6			141.1	141.7	-2.16	-2.15	Valve Adjustment:NSPS/EG CAI,High Temp,Valve 100% Open
CV-24142	Active	6/26/2026 9:53:35 AM	3.9	64.2	4.2	27.7			139.9	139.2	-1.96	-1.92	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24143	Active	6/1/2026 9:05:00 AM					690						AirTech Lab
CV-24143	Active	6/1/2026 9:05:00 AM						88000					AirTech Lab; [User entered 8.8%]
CV-24143	Active	6/1/2026 12:34:41 PM	0.8	39.6	11.7	47.9			104.3	104.0	-7.32	-7.01	Valve Adjustment:NSPS/EG CAI,High O2,Surging Liquid in Well (Watered In)
CV-24143	Active	6/1/2026 12:36:01 PM	0.9	39.6	11.8	47.7			103.7	103.8	-7.01	-6.82	
CV-24143	Active	6/11/2026 1:51:00 PM	0.7	80.0	0.0	19.3			161.3	161.7	-7.15	-6.76	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)

Table 2. Monthly LEA Selected Wells - June 2026
Chiquita Canyon Landfill

Point Name	Status	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24143	Active	6/15/2026 2:49:28 PM	1.1	41.1	10.3	47.5			106.2	107.8	-2.88	-1.36	Valve Comment:No pump in well;Valve Adjustment:No Flow Measurement,High Temp,High O2,Decreased Flow/Vacuum
CV-24143	Active	6/15/2026 2:50:17 PM	1.2	39.7	10.0	49.1			108.1	108.1	-1.38	-1.37	Valve Adjustment:No Flow Measurement,High Temp,High O2,Barely Open
CV-24143	Active	6/16/2026 8:40:00 AM					1400						Air Tech Lab
CV-24143	Active	6/16/2026 8:40:00 AM						190000					Air Tech Lab; [User entered 19%]
CV-24143	Active	6/17/2026 9:12:04 AM	3.2	73.4	0.0	23.4			90.5	90.5	-0.47	-0.48	Valve Adjustment:NSPS/EG CAC;Well Comment:No system port
CV-24143	Active	6/19/2026 2:17:30 PM	2.9	82.1	0.2	14.8			181.5	181.9	-0.86	-0.88	,
CV-24143	Active	6/19/2026 2:20:36 PM	3.5	80.3	0.8	15.4			179.6	180.2	-0.90	-0.87	,
CV-24144	Active	6/10/2026 10:15:37 AM	54.0	39.1	0.6	6.3			99.4	99.1	-7.75	-7.73	No Adjustment Made,
CV-24144	Active	6/16/2026 7:55:40 AM	57.9	39.6	0.0	2.5			85.3	85.1	-3.54	-3.53	Valve Adjustment:Audible Flow,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-24144	Active	6/30/2026 1:46:16 PM	57.7	40.1	0.3	1.9			87.2	87.3	-4.48	-4.63	Valve Adjustment:Valve 100% Open
CV-99	Active	6/4/2026 7:30:00 AM					0						AirTech Lab
CV-99	Active	6/4/2026 7:30:00 AM						1500					Air Tech Lab; [User entered 0.15%]
CV-99	Active	6/5/2026 10:07:36 AM	3.5	7.1	18.4	71.0			101.4	102.5	-8.05	-7.77	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-99	Active	6/5/2026 10:08:38 AM	3.6	8.0	18.0	70.4			103.2	103.5	-7.88	-7.90	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:Vale stuck open
H-1770N	Active	6/1/2026 9:51:21 AM	34.2	65.7	0.0	0.1			101.9	102.0	-0.84	-0.81	Valve Adjustment:Barely Open
H-1770N	Active	6/15/2026 9:30:00 AM					79						Air Tech Lab
H-1770N	Active	6/15/2026 9:30:00 AM						12000					Air Tech Lab; [User entered 1.2%]
H-1770N	Active	6/17/2026 9:09:18 AM	34.8	62.2	0.0	3.0			107.3	107.4	-0.17	-0.17	Valve Adjustment:Barely Open,Surging Liquid in Header
H-2165W	Active	6/10/2026 8:33:57 AM	9.9	79.5	0.0	10.6			115.5	115.2	-0.06	-0.06	Valve Adjustment:Barely Open
H-2165W	Active	6/16/2026 8:05:00 AM					890						Air Tech Lab
H-2165W	Active	6/16/2026 8:05:00 AM						60000					Air Tech Lab; [User entered 6.0%]
H-2165W	Active	6/17/2026 8:24:58 AM	12.5	78.7	0.0	8.8			90.5	90.5	-0.09	-0.09	Valve Adjustment:Audible Flow,Barely Open,Surging Liquid in Header
H-2273W	Active	6/2/2026 7:45:00 AM					240						AirTech Lab
H-2273W	Active	6/2/2026 7:45:00 AM						16000					AirTech Lab; [User entered 1.6%]
H-2273W	Active	6/2/2026 8:54:53 AM	21.0	55.4	0.0	23.6			128.1	126.9	-1.13	-1.00	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum

Table 2. Monthly LEA Selected Wells - June 2026
Chiquita Canyon Landfill

Point Name	Status	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
H-2273W	Active	6/16/2026 8:21:18 AM	28.2	57.6	0.0	14.2			126.2	125.6	-0.52	-0.51	

Attachment B

Down Well Temperatures

And

List of Wells for Monitoring

LEA Selected Wells for Down Hole Temperature Monitoring
June 2026

Well Number	Down Well Temp Monitoring Monthly	Last Date Monitored for Downwell Temperatures - 2025	2026 Downwell Temperature Monitoring Date	Comments
CV-100	NA	NA	NA	Abandoned Well
CV-103	NA	3/3/2025	NA	Abandoned Well
CV-108-52	Yes	3/4/2025	3/2/2026	
CV-113	Yes	3/10/2025	3/2/2026	
CV-1532	NA	NA	NA	Abandoned Well
CV-1532A	Yes	3/10/2025	2/6/2026 , 3/25/2026 and 6/17/2026	
CV-1535	Yes	3/4/2025	3/2/2026	
CV-1902A	Yes	3/18/2025	2/6/2026, 3/2/2026 and 6/12/2026	
CV-2001	Yes	3/4/2025	3/3/2026 and 6/24/2026	
CV-2002	Yes	6/2/2025	3/4/2026	
CV-2007	Yes	3/5/2025	3/4/2026	
CV-2202	NA	NA	NA	Abandoned Well
CV-2301	Yes	3/11/2025	2/6/2026, 3/5/2026 and 6/12/2026	Lorentz pump removed, no graph possible
CV-2302	Yes	3/11/2025	6/25/2026	Graph Attached 6-1 to 6-30-2026
CV-2303	Yes	3/11/2025	TBD - Pump Installed	Graph Attached 6-1 to 6-30-2026
CV-2312	Yes	3/5/2025	TBD - Pump Installed	
CV-2315	Yes	3/19/2025	6/25/2026	Graph Attached 6-1 to 6-30-2026
CV-2341	Yes	3/5/2025	TBD - Pump Installed	
CV-2350	Yes	3/12/2025	TBD - Pump Installed	Lorentz pump is damaged and unable to be removed for repairs, no graphing possible.
CV-2351	Yes	3/12/2025	3/10/2026	
CV-2352	Yes	3/12/2025	4/24/2026 and 4/30/2026	Lorentz pump removed, no graph possible
CV-2353	Yes	5/30/2025	3/10/2026, 4/30/2026 and 6/12/2026	
CV-24007	Yes	3/6/2025	3/10/2026 and 6/12/2026	
CV-24017	Yes	3/6/2025	TBD - Pump Installed	Sensor for temp repaired. June chart attached for reference. Operating as of June 30
CV-24053	Yes	3/6/2025	TBD - Pump Installed	
CV-24065	Yes	3/6/2025	TBD - Pump Installed	Graph Attached 6-1 to 6-30-2026
CV-24095	Yes	3/7/2025	TBD - Pump Installed	Graph Attached 6-1 to 6-30-2026
CV-24101	Yes	3/7/2025	TBD - Pump Installed	

LEA Selected Wells for Down Hole Temperature Monitoring

June 2026

CV-24122	Yes	3/7/2025	3/10/2026	
CV-24127	Yes	3/7/2025	3/10/2027	
CV-24138	Yes	4/1/2025	TBD - Pump Installed	
CV-23139	Yes	8/18/2025	TBD - Pump Installed	
CV-24143	Yes	3/10/2025	6/12/2026	
TC-2385A	NA	NA	NA	Abandoned Well


Liquid Data Report
Date Range: 06/01/2026 to 06/30/2026

Report Date: 07/06/2026
Site Name: Chiquita Canyon Landfill


Point Name	Record Date	Pump Installed	Pump Status	Liquid Comments	Temp (F) @ 0 FT from BOW	Temp (F) @ 10 FT from BOW	Temp (F) @ 20 FT from BOW	Temp (F) @ 30 FT from BOW	Temp (F) @ 40 FT from BOW	Temp (F) @ 50 FT from BOW	Temp (F) @ 60 FT from BOW	Temp (F) @ 70 FT from BOW	Temp (F) @ 80 FT from BOW	Temp (F) @ 90 FT from BOW	Temp (F) @ 100 FT from BOW	Temp (F) @ 110 FT from BOW	Temp (F) @ 120 FT from BOW	Temp (F) @ 130 FT from BOW	Temp (F) @ 140 FT from BOW	Temp (F) @ 150 FT from BOW	Temp (F) @ 160 FT from BOW	Temp (F) @ 170 FT from BOW	Temp (F) @ 180 FT from BOW	Temp (F) @ 190 FT from BOW
CV-1532A	6/17/2026 1:12:53 PM	N		91.49°C:BOW;92.23°C:10ft;92.25°C:20ft;91.23°C:30ft;86.85°C:40ft	196.68	198.01	198.05	196.21	188.33															
CV-1902A	6/12/2026 8:25:30 AM	N		90.28°C:BOW;90.53°C:10ft;89.93°C:20ft;89.53°C:30ft;88.73°C:40ft	194.50	194.95	193.87	193.15	191.71															
CV-24007	6/12/2026 8:23:32 AM	Y	Online	74.99°C:BOW;76.87°C:10ft;74.88°C:20ft;74.53°C:30ft;73.89°C:40ft;72.55°C:50ft;67.73°C:60ft;67.00°C:70ft;66.18°C:80ft	166.98	170.37	166.78	166.15	165.00	162.59	153.91	152.60	151.12											
CV-24143	6/12/2026 7:36:10 AM	Y	Online	88.55°C:BOW;90.24°C:10ft;89.50°C:20ft;82.60°C:30ft	191.39	194.43	193.10	180.68																
CV-2001	6/24/2026 1:53:55 PM	Y	Online		154.40	154.40	154.30	155.20	147.00	128.80														
CV-2301	6/12/2026 9:50:08 AM	Y	Online	94.77°C:BOW;95.21°C:10ft;95.28°C:20ft;95.46°C:30ft;95.57°C:40ft;95.90°C:50ft;96.01°C:60ft;96.03°C:70ft;95.73°C:80ft;95.63°C:90ft;95.62°C:100ft;94.43°C:110ft;92.93°C:120ft;91.84°C:130ft;91.40°C:140ft;91.03°C:150ft;89.92°C:160ft;89.70°C:170ft;88.42°C:180ft;87.94°C:190ft	202.59	203.38	203.50	203.83	204.03	204.62	204.82	204.85	204.31	204.13	204.12	201.97	199.27	197.31	196.52	195.85	193.86	193.46	191.16	190.29
CV-2302	6/25/2026 1:56:10 PM	Y	Online		168.00	169.00	169.20	146.40	147.60	148.00	149.70	152.00	150.80	151.20	145.00	118.00								
CV-2315	6/25/2026 2:43:59 PM	Y	Online		209.00	210.40	209.70	206.90	206.70	205.00	204.00	204.00												
CV-2353-PLR	6/12/2026 10:38:13 AM	N		97.33°C:BOW;99.11°C:10ft;99.27°C:20ft;96.96°C:30ft;95.43°C:40ft;94.61°C:50ft	207.19	210.40	210.69	206.53	203.77	202.30														




CV-2302


12 Jun 2026 19:39 (UTC -7)
Temp. Sensor [Analog 1]: 165 °F
June 2, 2026
June 4, 2026
June 6, 2026
June 8, 2026
June 10, 2026
June 12, 2026
June 14, 2026
June 16, 2026
June 18, 2026
June 20, 2026
June 22, 2026
June 24, 2026
June 26, 2026
June 28, 2026
June 30, 2026


CV-2303


13 Jun 2026 20:11 (UTC -7)
Temperature sensor [Analog 1]: 213.5 °F
June 2, 2026
June 4, 2026
June 6, 2026
June 8, 2026
June 10, 2026
June 12, 2026
June 14, 2026
June 16, 2026
June 18, 2026
June 20, 2026
June 22, 2026
June 24, 2026
June 26, 2026
June 28, 2026
June 30, 2026

CV-2315



09 Jun 2026 23:08 (UTC -7)
Lorentz Temp. Sensor [Analog 1]: 151.7 °F
June 2, 2026
June 4, 2026
June 6, 2026
June 8, 2026
June 10, 2026
June 12, 2026
June 14, 2026
June 16, 2026
June 18, 2026
June 20, 2026
June 22, 2026
June 24, 2026
June 26, 2026
June 28, 2026
June 30, 2026

CV-24017




Note that sensor was not working properly for most of June, but has been repaired

CV-24065



09 Jun 2026 09:16 (UTC -7)
Lorentz Temp. Sensor [Analog 1]: 151.7 °F
June 2, 2026
June 4, 2026
June 6, 2026
June 8, 2026
June 10, 2026
June 12, 2026
June 14, 2026
June 16, 2026
June 18, 2026
June 20, 2026
June 22, 2026
June 24, 2026
June 26, 2026
June 28, 2026
June 30, 2026

CV-24095


07 Jun 2026 18:48 (UTC -7)
Lorentz Temp. Sensor [Analog 1]: 178.3 °F
June 2, 2026
June 4, 2026
June 6, 2026
June 8, 2026
June 10, 2026
June 12, 2026
June 14, 2026
June 16, 2026
June 18, 2026
June 20, 2026
June 22, 2026
June 24, 2026
June 26, 2026
June 28, 2026
June 30, 2026

Attachment C

Item 7 – Well Location Map



N

GRAPHIC SCALE

150 75 0 150 300 150

SCALE: 1"=150'

LEGEND

- 1150 — TOPOGRAPHIC CONTOUR
- EXISTING CELL LIMITS (APPROXIMATE)
- CV-XX — EXISTING VERTICAL LFG EXTRACTION WELL
- H-XX — EXISTING HORIZONTAL COLLECTOR
- EXISTING HORIZONTAL COLLECTOR PERFORATED PIPE
- REACTION MITIGATION AREA BOUNDARY
- REACTION AREA BOUNDARY - CONDITION 9A

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLOR. AERIAL PHOTOGRAPHY DATED JUNE 02, 2026.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.
3. THE LOCATION OF ANY EXISTING GCCS COMPONENTS AND OTHER FEATURES ARE APPROXIMATE AND SHOULD BE USED FOR INFORMATION PURPOSES ONLY.

DATE | REVISION | NO.

SHEET TITLE: EXISTING VERTICAL & HORIZONTAL LFG EXTRACTION WELL MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544


PROJ. NO. 01204123.45 | DSN. BY: - | DWN. BY: RR | CHK. BY: - | APP. BY: - | ACAD FILE: FIELD SERVICES

DATE: 07/10/2026

SCALE: AS SHOWN

SHEET: 1

N:\CAD\ASBUILT – MASTERS\CHIQUITA\GCCS\2026 ACAD\2026 CCLF_Existing Well Map_For LEA Response_2026-07-10.dwg Jul 10, 2026 2:26pm By: raulramirez


CELL 2 PHASE 2A
CELL 2 PHASE 2B
MODULE 2B/3/PZ
CELL II, PHASE 1
CELL 2A
CANYON C CELL I
MODULE 2A
MODULE 4
CANYON A
CANYON B
MODULE 5
CANYON D
A-D RIDGE
CELL 6
PRIMARY CANYON
CELL 8
WESTERN STABILITY BUTRESS IN CONSTRUCTION
18" BLIND FLANGE TO CORRUGATED LINER PIPING
18" BLIND FLANGE TO CORRUGATED LINER PIPING
CLEANCAP (HERO) TOX
ZEECO TOX
ZEECO TOX STATION
NEW LEACHATE TANK FARM TOX
GABIONS TOXICS STOCKPILE
GP-10
GP-25
GP-A
GP-11
GP-12
GP-24
GP-9
GP-8
GP-23
GP-22
GP-21
GP-7
GP-6
GP-20
GP-19
GP-5
GP-2
GP-18
GP-17
GP-16
GP-13
SW-80
SW-154
SW-66
SW-9
SW-70
SW-187
SW-10
SW-1930
SW-2500
SW-2504
SW-25
SW-1445
SW-1455
SW-2502
SW-2503
SW-2501
SW-20
SW-65
SW-115
SW-72
SW-71
LC-2100S
LC-2100N
LC-2100C
LC-2001C
LC-2001S
LC-6A
LC-6B
LC-6C
TP-1
TP-2
TP-3
TP-4
TP-5
TP-6
TP-7
TP-8
TP-9
TP-10
TP-11
TP-12
TP-13
TP-14
TP-15
TP-16
TP-17
TP-18
TP-19
TP-20
TP-21
TP-22
TP-23
TP-24
TP-25
TP-26
TP-27
TP-28
TP-29
TP-30
TP-31
TP-32
TP-33
TP-34
TP-35
TP-36
TP-37
TP-38
TP-39
TP-40
TP-41
TP-42
TP-43
TP-44
TP-45
TP-46
TP-47
TP-48
TP-49
FP-1
FP-2
FP-3
FP-4
FP-5
FP-6
FP-7
FP-8
FP-9
FP-10
FP-11
FP-12
FP-13
FP-14
FP-15
FP-16
FP-17
FP-18
FP-19
FP-20
FP-21
FP-22
FP-23
FP-24
FP-25
FP-26
FP-27
FP-28
FP-29
FP-30
FP-31
FP-32
FP-33
FP-34
FP-35
FP-36
FP-37
FP-38
FP-39
FP-40
FP-41
FP-42
FP-43
FP-44
FP-45
FP-46
FP-47
FP-48
FP-49
BH-GB-1
CV-2001 PLR
CV-2201 PLR
CV-2308 PLR
CV-2310 PLR
CV-2342A PLR
CV-1534A PLR
CV-2204 PLR
CV-2501E PLR
CV-2422 PLR
CV-2424 PLR
CV-2423 PLR
CV-2413 PLR
CV-2414 PLR
CV-2415 PLR
CV-2416 PLR
CV-2417 PLR
CV-2418 PLR
CV-2419 PLR
CV-2420 PLR
CV-2421 PLR
CV-2426 PLR
CV-2427 PLR
CV-2428 PLR
CV-2429 PLR
CV-2430 PLR
CV-2431 PLR
CV-2432 PLR
CV-2433 PLR
CV-2434 PLR
CV-2435 PLR
CV-2436 PLR
CV-2437 PLR
CV-2438 PLR
CV-2439 PLR
CV-2440 PLR
CV-2441 PLR
CV-2442 PLR
CV-2443 PLR
CV-2444 PLR
CV-2445 PLR

Attachment D

Milestone 5 Compliance Data



Ranges Mapped

						# Points
	>=	0	and	<	0.5	54
	>=	0.5	and	<	0.9	18
	>=	0.9	and	<	1.1	8
	>=	1.1	and	<	1.5	2
	>=	1.5	and	<	101	
		N/A			N/A	

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill

Range Map

Parameter: CH4/CO2 Ratio (high range)

Analysis Method: MostRecent

Date Range: 06/01/2026 - 06/30/2026

Map generation date : 07/11/2026



Ranges Mapped

						# Points
	>=	0	and	<	500	28
	>=	500	and	<	1000	11
	>=	1000	and	<	1500	8
	>=	1500	and	<	2000	4
	>=	2000	and	<	10000	20

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill

Range Map

Parameter: CO LAB (mid range)

Analysis Method: MostRecent

Date Range: 06/01/2026 - 06/30/2026

Map generation date : 07/11/2026



Ranges Mapped

					# Points
>=	0	and	<	2000	5
>=	2000	and	<	5000	5
>=	5000	and	<	10000	4
>=	10000	and	<	50000	18
>=	50000	and	<	100000	8
>=	100000	and	<	150000	10
>=	150000	and	<	1000000	18

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill


Range Map

Parameter: H2 LAB (mid range)

Analysis Method: MostRecent

Date Range: 06/01/2026 - 06/30/2026

Map generation date : 07/11/2026



Ranges Mapped

						# Points
	>=	0	and	<	25	53
	>=	25	and	<	48	26
	>=	48	and	<	52	1
	>=	52	and	<	58	2
	>=	58	and	<	101	
		N/A			N/A	

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill

Range Map

Parameter: CH4 (mid range)

Analysis Method: MostRecent

Date Range: 06/01/2026 - 06/30/2026

Map generation date : 07/11/2026



Ranges Mapped

						# Points
	>=	0	and	<	25	3
	>=	25	and	<	45	7
	>=	45	and	<	55	16
	>=	55	and	<	65	11
	>=	65	and	<	101	45
		N/A			N/A	

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill

Range Map

Parameter: CO2 (mid range)

Analysis Method: MostRecent

Date Range: 06/01/2026 - 06/30/2026

Map generation date : 07/11/2026



Ranges Mapped

						# Points
	>=	0	and	<	0.5	56
	>=	0.5	and	<	2	14
	>=	2	and	<	3.5	3
	>=	3.5	and	<	5	2
	>=	5	and	<	101	7
		N/A			N/A	

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill


Range Map

Parameter: O2 (mid range)

Analysis Method: MostRecent

Date Range: 06/01/2026 - 06/30/2026

Map generation date : 07/11/2026



Ranges Mapped

						# Points
	>=	-50	and	<	131	41
	>=	131	and	<	150	9
	>=	150	and	<	165	9
	>=	165	and	<	180	3
	>=	180	and	<	999	20
		N/A			N/A	

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill


Range Map

Parameter: Adj Temp (high range)

Analysis Method: MostRecent

Date Range: 06/01/2026 - 06/30/2026

Map generation date : 07/11/2026



Point ID / Name


CHIWCV99 / CV-99

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-99 / CV-99

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-99 / CV-99


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CV108-52 / CV-108-52

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-108-52 / CV-108-52

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-108-52 / CV-108-52


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CHWCV113 / CV-113

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-113 / CV-113

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-113 / CV-113


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CHWCV114 / CV-114

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-114 / CV-114

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-114 / CV-114


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CHCV1423 / CV-1423


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools





Point ID / Name


CCV1532A / CV-1532A

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-1532A / CV-1532A

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-1532A / CV-1532A


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CHCV1535 / CV-1535

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-1535 / CV-1535

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-1535 / CV-1535


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CCV1902A / CV-1902A

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-1902A / CV-1902A

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-1902A / CV-1902A


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CHCV2001 / CV-2001

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-2001 / CV-2001

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-2001 / CV-2001


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CHCV2002 / CV-2002

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-2002 / CV-2002

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-2002 / CV-2002


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CHCV2007 / CV-2007

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-2007 / CV-2007

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-2007 / CV-2007


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name

CHCV2301 / CV-2301

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F


Chiquita Canyon Landfill

Parameter Chart: Multiscale

Date Range: 07/01/2025 - 06/30/2026

Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-2301 / CV-2301

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-2301 / CV-2301


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CHCV2302 / CV-2302

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-2302 / CV-2302

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools



Point ID / Name


CV-2302 / CV-2302


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CHCV2303 / CV-2303

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-2303 / CV-2303

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-2303 / CV-2303

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CHCV2305 / CV-2305

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-2305 / CV-2305

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-2305 / CV-2305

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CHCV2312 / CV-2312

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-2312 / CV-2312

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-2312 / CV-2312


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CHCV2314 / CV-2314

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-2314 / CV-2314

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-2314 / CV-2314

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CHCV2315 / CV-2315

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-2315 / CV-2315

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-2315 / CV-2315


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CHCV2328 / CV-2328

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-2328 / CV-2328

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-2328 / CV-2328

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CHCV2333 / CV-2333

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-2333 / CV-2333

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-2333 / CV-2333


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CHCV2334 / CV-2334

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-2334 / CV-2334

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-2334 / CV-2334


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CHCV2337 / CV-2337

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-2337 / CV-2337

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-2337 / CV-2337


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CHCV2341 / CV-2341

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-2341 / CV-2341

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-2341 / CV-2341


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CHCV2344 / CV-2344

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-2344 / CV-2344

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-2344 / CV-2344


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CHCV2345 / CV-2345

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-2345 / CV-2345

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-2345 / CV-2345


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CHCV2346 / CV-2346

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-2346 / CV-2346

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-2346 / CV-2346


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CHCV2347 / CV-2347

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-2347 / CV-2347

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-2347 / CV-2347


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CHCV2348 / CV-2348

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-2348 / CV-2348

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-2348 / CV-2348


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CHCV2349 / CV-2349

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-2349 / CV-2349

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-2349 / CV-2349


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CHCV2350 / CV-2350

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-2350 / CV-2350

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-2350 / CV-2350


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CHCV2351 / CV-2351

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-2351 / CV-2351

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-2351 / CV-2351


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CHCV2352 / CV-2352

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-2352 / CV-2352

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-2352 / CV-2352


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CHCV2353 / CV-2353-PLR

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-2353 / CV-2353

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-2353 / CV-2353

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CHCV2354 / CV-2354

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-2354 / CV-2354

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-2354 / CV-2354

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CCV24002 / CV-24002


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools





Point ID / Name


CCV24003 / CV-24003


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools





Point ID / Name


CCV24007 / CV-24007

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24007 / CV-24007

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-24007 / CV-24007

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CCV24017 / CV-24017

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24017 / CV-24017

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-24017 / CV-24017


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CCV24049 / CV-24049

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24049 / CV-24049

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-24049 / CV-24049


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CCV24053 / CV-24053

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24053 / CV-24053

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-24053 / CV-24053


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CCV24055 / CV-24055

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24055 / CV-24055

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-24055 / CV-24055


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CCV24062 / CV-24062

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24062 / CV-24062

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-24062 / CV-24062


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CCV24063 / CV-24063

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24063 / CV-24063

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-24063 / CV-24063


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CCV24064 / CV-24064

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24064 / CV-24064

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-24064 / CV-24064

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CCV24065 / CV-24065-TP17

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24065 / CV-24065

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-24065 / CV-24065


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CCV24066 / CV-24066

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24066 / CV-24066

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-24066 / CV-24066


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CCV24069 / CV-24069

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24069 / CV-24069

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-24069 / CV-24069


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CCV24070 / CV-24070

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24070 / CV-24070

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-24070 / CV-24070


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CCV24071 / CV-24071

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24071 / CV-24071

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-24071 / CV-24071


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CCV24075 / CV-24075-TP15

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24075 / CV-24075

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-24075 / CV-24075


Parameter / Unit

Hydrogen /%,v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CCV24077 / CV-24077


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools





Point ID / Name


CCV24079 / CV-24079-TP8

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24079 / CV-24079

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-24079 / CV-24079


Parameter / Unit

Hydrogen /%,v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CCV24082 / CV-24082


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools





Point ID / Name


CCV24083 / CV-24083


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools





Point ID / Name


CCV24084 / CV-24084-TP11

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24084-TP11 / CV-24084-TP11

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-24084-TP11 / CV-24084-TP11


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CCV24088 / CV-24088


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools





Point ID / Name


CCV24095 / CV-24095

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24095 / CV-24095

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools



Point ID / Name


CV-24095 / CV-24095


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/6/26

SCSeTools





Point ID / Name


CCV24096 / CV-24096


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools





Point ID / Name


CCV24097 / CV-24097


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools





Point ID / Name


CCV24098 / CV-24098


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools





Point ID / Name


CCV24099 / CV-24099


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools





Point ID / Name


CCV24100 / CV-24100

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24100 / CV-24100

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools



Point ID / Name


CV-24100 / CV-24100


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools





Point ID / Name


CCV24101 / CV-24101

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24101 / CV-24101

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools



Point ID / Name


CV-24101 / CV-24101


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools





Point ID / Name


CCV24102 / CV-24102


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools





Point ID / Name


CCV24120 / CV-24120

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24120 / CV-24120

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools



Point ID / Name


CV-24120 / CV-24120


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools





Point ID / Name


CCV24121 / CV-24121

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24121 / CV-24121

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools



Point ID / Name


CV-24121 / CV-24121


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools





Point ID / Name


CCV24122 / CV-24122

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24122 / CV-24122

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools



Point ID / Name


CV-24122 / CV-24122


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools





Point ID / Name


CCV24123 / CV-24123


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools





Point ID / Name


CCV24125 / CV-24125-TP20

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24125 / CV-24125

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools



Point ID / Name


CV-24125 / CV-24125

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools



Point ID / Name


CCV24126 / CV-24126

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24126 / CV-24126

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools



Point ID / Name


CV-24126 / CV-24126


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools





Point ID / Name


CCV24127 / CV-24127

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24127 / CV-24127

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools



Point ID / Name


CV-24127 / CV-24127


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools





Point ID / Name


CCV24128 / CV-24128

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24128 / CV-24128

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools



Point ID / Name


CV-24128 / CV-24128

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools



Point ID / Name


CCV24134 / CV-24134-TP19

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name

CV-24134 / CV-24134

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools



Point ID / Name


CV-24134 / CV-24134


Parameter / Unit

Hydrogen /%,v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools





Point ID / Name


CCV24138 / CV-24138

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24138 / CV-24138

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools



Point ID / Name


CV-24138 / CV-24138

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools



Point ID / Name


CCV24139 / CV-24139

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24139 / CV-24139

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools



Point ID / Name


CV-24139 / CV-24139


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools





Point ID / Name


CCV24140 / CV-24140

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24140 / CV-24140

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools



Point ID / Name


CV-24140 / CV-24140


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools





Point ID / Name


CCV24141 / CV-24141

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24141 / CV-24141

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools



Point ID / Name


CV-24141 / CV-24141


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools





Point ID / Name


CCV24142 / CV-24142

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24142 / CV-24142

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools



Point ID / Name


CV-24142 / CV-24142


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools





Point ID / Name


CCV24143 / CV-24143

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


CV-24143 / CV-24143

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools



Point ID / Name

CV-24143 / CV-24143

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools



Point ID / Name


CCV24144 / CV-24144


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools





Point ID / Name


CHH1770N / H-1770N

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


H-1770N / H-1770N

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools



Point ID / Name


H-1770N / H-1770N


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools





Point ID / Name


CHH2165W / H-2165W

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


H-2165W / H-2165W

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools



Point ID / Name


H-2165W / H-2165W


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools





Point ID / Name


CHH2273W / H-2273W

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/2/26

SCSeTools



Point ID / Name


H-2273W / H-2273W

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools



Point ID / Name

H-2273W / H-2273W


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 07/01/2025 - 06/30/2026
Chart generation date: 7/7/26

SCSeTools

Thirty Day Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill



Max Temps - 20:55:42 06-30-2026

Current | 7 Day | 30 Day

BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	159	15
TP02	158	60
TP03	233	45
TP04	158	60
TP05	167	45
TP06	139	100
TP07	154	100
TP08	168	45
TP09	209	125
TP10	156	125
TP11	210	125
TP12	150	125
TP13	174	140
TP14	172	150
TP15	203	100
TP16	179	30
TP17	162	125
TP18	210	45
TP19	237	150
TP20	142	45
TP21	256	110
TP22	198	15
TP23	260	75
TP24	211	265
TP25	215	130
TP26	178	150
TP27	157	100
TP28	144	170
TP29	203	240
TP30	175	190
TP31	193	180
TP32	170	130
TP33	197	45
TP34	152	120
TP35	175	140
TP36	172	165
TP37	184	180
TP38	172	165
TP39	159	160
TP40	149	185

Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM

SCS ENGINEERS

07224053.00 | June 4, 2026

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

From May 28, 2026, through June 3, 2026, there were three recorded temperature increases and one recorded temperature decrease that triggered the notification limits set forth in the LEA's October 4, 2024 letter.

Chiquita provides the following updates:

- TP-08
  - The 125-foot thermocouple went offline on March 3rd and TP-8 was offline between March 6th and March 9th for evaluation and maintenance. Upon removing the thermocouples, the casing for TP-08 was found to be damaged due to differential settlement beyond 45-feet, thus preventing the installation of the 100-foot, 125-foot, and 150-foot thermocouples. The 15-foot, 30-foot, and 45-foot thermocouples are active and reporting data.
  - The 45-foot thermocouple showed an increasein maximum temperature of 18°F from 139°F to 157°F from May 31st to June 3rd.


- TP-14
  - The 150-foot thermocouple reported a maximum temperature of 249°F on May 10th, which was anomalous and likely associated with a potential thermocouple sensor malfunction. As a result, the reported temperatures of 0°F from May 11th to May 15th are also considered anomalous. The 150-foot thermocouple was replaced on May 16th and temperatures were consistent with previous recorded values.

- TP-23
  - The 15-foot thermocouple reported temperatures of 0°F from May 13th to May 18th, which were anomalous and likely associated with a potential thermocouple sensor malfunction. On May 19th, a temperature of 189°F was reported, with temperatures remaining consistent with previous recorded values through May 27th with the thermocouple functioning as normal.
  - The 30-foot thermocouple reported temperatures of 0°F from May 13th to May 18th, which were anomalous and likely associated with a potential thermocouple sensor malfunction. On May 19th, a temperature of 221°F was reported, with temperatures remaining consistent with previously recorded values through May 27th with the thermocouple functioning as normal.
  - The reported maximum temperature reading of 2508°F at the 30-foot thermocouple is considered anomalous and is believed to be associated with a potential thermocouple sensor malfunction. The 30-foot thermocouple temperatures remained consistent with previous recorded values with the thermocouple functioning as normal.
  - The 15-foot thermocouple showed an increasein maximum temperature of 22°F from 188°F to 210°F from June 1st to June 3rd.

- TP-29
  - The 240-foot thermocouple showed an increasein maximum temperature of 22°F from 186°F to 203°F from May 26th to June 2nd and then a decrease in maximum temperature of 22°F from 203°F to 188°F from June 2nd to June 3rd.

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS


Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS


Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill



Max Temps - 04:58:39 06-04-2026

Current | 7 Day | 30 Day

BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	151	100
TP02	157	60
TP03	233	45
TP04	158	30
TP05	166	45
TP06	139	100
TP07	154	100
TP08	157	45
TP09	208	125
TP10	155	125
TP11	210	125
TP12	150	125
TP13	174	140
TP14	172	150
TP15	202	100
TP16	179	30
TP17	161	125
TP18	208	45
TP19	233	150
TP20	141	45
TP21	256	110
TP22	197	15
TP23	260	75
TP24	210	265
TP25	209	130
TP26	177	150
TP27	156	100
TP28	144	170
TP29	203	240
TP30	174	190
TP31	192	180
TP32	170	130
TP33	198	45
TP34	151	120
TP35	175	140
TP36	172	165
TP37	184	180
TP38	172	165
TP39	159	160
TP40	149	185



N

GRAPHIC SCALE

130 65 0 130 260 390

SCALE: 1"=130'

LEGEND

- 1150 — EXISTING TOPOGRAPHIC CONTOUR
- EXISTING CELL LIMITS (APPROXIMATE)
- TP-XX — INSTALLED TEMPERATURE PROBES - STANDALONE
- TP-XX — INSTALLED TEMPERATURE PROBES - INSTALLED WITHIN WELL CASING
- REACTION AREA BOUNDARY (APPROXIMATE) - BASED ON DATA REVIEW
- REACTION AREA BOUNDARY - CONDITION 9A

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER. AERIAL PHOTOGRAPHY DATED APRIL 30, 2026.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

NO.	REVISION	DATE

SHEET TITLE: EXISTING TEMPERATURE PROBE MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544

PROJ. NO. 01204123.41 | DWN. BY: - | CHK. BY: - | ACAD FILE: - | APP. BY: - | DSN. BY: -

DATE: 05/07/2026

SCALE: AS SHOWN

SHEET: 1

Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM

SCS ENGINEERS

07224053.00 | June 11, 2026

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

From June 4, 2026, through June 10, 2026, there were no recorded temperature increases and two recorded temperature decreases that triggered the notification limits set forth in the LEA's October 4, 2024 letter.

Chiquita provides the following updates:

- TP-08
  - The 45-foot thermocouple showed a decrease in maximum temperature of 19°F from 157°F to 138°F from June 4th to June 10th.


- TP-14
  - The 150-foot thermocouple reported a maximum temperature of 249°F on May 10th, which was anomalous and likely associated with a potential thermocouple sensor malfunction. As a result, the reported temperatures of 0°F from May 11th to May 15th are also considered anomalous. The 150-foot thermocouple was replaced on May 16th and temperatures were consistent with previous recorded values.

- TP-23
  - The 15-foot thermocouple reported temperatures of 0°F from May 13th to May 18th, which were anomalous and likely associated with a potential thermocouple sensor malfunction. On May 19th, a temperature of 189°F was reported, with temperatures remaining consistent with previous recorded values through May 27th with the thermocouple functioning as normal.
  - The 30-foot thermocouple reported temperatures of 0°F from May 13th to May 18th, which were anomalous and likely associated with a potential thermocouple sensor malfunction. On May 19th, a temperature of 221°F was reported, with temperatures remaining consistent with previously recorded values through May 27th with the thermocouple functioning as normal.
  - The reported maximum temperature readings of 2508°F at the 30-foot thermocouple on May 13th to May 18th, are considered anomalous and are believed to be associated with a potential thermocouple sensor malfunction. The 30-foot thermocouple temperatures remained consistent with previous recorded values with the thermocouple functioning as normal.
  - The 15-foot thermocouple showed a decrease in maximum temperature of 13°F from 208°F to 195°F from June 4th to June 5th.

- TP-29
  - The 240-foot thermocouple remained consistent with previous recorded temperatures.

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39


Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS


Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40

Maximum data for 4/30/2026 12:00 AM to 6/10/2026 12:00 AM



SCS ENGINEERS

Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill



BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	152	100
TP02	158	60
TP03	233	45
TP04	158	30
TP05	167	45
TP06	139	100
TP07	154	100
TP08	154	45
TP09	208	125
TP10	155	125
TP11	205	100
TP12	150	125
TP13	173	140
TP14	172	150
TP15	203	100
TP16	178	30
TP17	161	125
TP18	208	45
TP19	231	150
TP20	141	45
TP21	256	110
TP22	198	15
TP23	260	75
TP24	211	265
TP25	209	130
TP26	178	150
TP27	157	100
TP28	143	170
TP29	194	240
TP30	175	190
TP31	192	180
TP32	170	130
TP33	196	45
TP34	151	120
TP35	175	140
TP36	172	165
TP37	184	180
TP38	172	165
TP39	159	160
TP40	149	185

Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM

SCS ENGINEERS

07224053.00 | June 18, 2026

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

From June 11, 2026, through June 17, 2026, there was one recorded temperature increase and one recorded temperature decrease that triggered the notification limits set forth in the LEA's October 4, 2024 letter.

Chiquita provides the following updates:

- TP-08
  - The 45-foot thermocouple remained consistent with previous recorded temperatures.

- TP-13
  - The 45-foot thermocouple showed a decrease in maximum temperature of 15°F from 161°F to 146°F from June 11th to June 13th and then an increase in maximum temperature of 19°F from 144°F to 163°F from June 16th to June 17th.


- TP-14
  - The 150-foot thermocouple reported a maximum temperature of 249°F on May 10th, which was anomalous and likely associated with a potential thermocouple sensor malfunction. As a result, the reported temperatures of 0°F from May 11th to May 15th are also considered anomalous. The 150-foot thermocouple was replaced on May 16th and temperatures were consistent with previous recorded values.

- TP-23
  - The 15-foot thermocouple reported temperatures of 0°F from May 13th to May 18th, which were anomalous and likely associated with a potential thermocouple sensor malfunction. On May 19th, a temperature of 189°F was reported, with temperatures remaining consistent with previous recorded values through May 27th with the thermocouple functioning as normal.
  - The 30-foot thermocouple reported temperatures of 0°F from May 13th to May 18th, which were anomalous and likely associated with a potential thermocouple sensor malfunction. On May 19th, a temperature of 221°F was reported, with temperatures remaining consistent with previously recorded values through May 27th with the thermocouple functioning as normal.
  - The reported maximum temperature reading of 2508°F at the 30-foot thermocouple is considered anomalous and is believed to be associated with a potential thermocouple sensor malfunction. The 30-foot thermocouple temperatures remained consistent with previous recorded values with the thermocouple functioning as normal.
  - The 15-foot thermocouple remained consistent with previous recorded temperatures.

- TP-24
    - The 210-foot thermocouple showed an increase in maximum temperature of 10°F from 189°F to 199°F from June 11th to June 17th.

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39


Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS


Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40

Maximum data for 5/7/2026 12:00 AM to 6/17/2026 12:00 AM



SCS ENGINEERS

Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill



Max Temps - 04:58:45 06-18-2026

Current | 7 Day | 30 Day

BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	154	15
TP02	157	60
TP03	233	45
TP04	158	60
TP05	167	45
TP06	139	100
TP07	154	100
TP08	147	30
TP09	209	125
TP10	155	125
TP11	207	125
TP12	150	125
TP13	172	140
TP14	172	150
TP15	203	100
TP16	174	30
TP17	162	125
TP18	209	45
TP19	235	150
TP20	140	45
TP21	255	110
TP22	198	15
TP23	260	75
TP24	211	265
TP25	209	130
TP26	178	150
TP27	156	100
TP28	143	170
TP29	193	240
TP30	175	190
TP31	192	180
TP32	170	130
TP33	195	45
TP34	152	120
TP35	175	140
TP36	172	165
TP37	184	180
TP38	172	165
TP39	159	160
TP40	149	185

Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM

SCS ENGINEERS

07224053.00 | June 25, 2026

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

From June 18, 2026, through June 24, 2026, there were nine recorded temperature increases and five recorded temperature decreases that triggered the notification limits set forth in the LEA's October 4, 2024 letter.

Chiquita provides the following updates:

- TP-08
  - The 30-foot thermocouple showed an increase in maximum temperature of 11°F from 146°F to 157°F from June 18th to June 23rd.
  - The 45-foot thermocouple showed an increase in maximum temperature of 31°F from 138°F to 168°F from June 10th to June 19th.
  - The 45-foot thermocouple showed an increase in maximum temperature of 29°F from 139°F to 168°F from June 18th to June 19th, then a decrease in maximum temperature of 28°F from 168°F to 141°F from June 19th to June 20th, then an increase in maximum temperature of 24°F from 142°F to 166°F from June 21st to June 22nd, and then a decrease in maximum temperature of 25°F from 167°F to 142°F from June 23rd to June 24th.

- TP-13
  - The 30-foot thermocouple remained consistent with previous recorded temperatures.
  - The 45-foot thermocouple showed a decrease in maximum temperature of 17°F from 163°F to 146°F from June 17th to June 18th, then an increase in maximum temperature of 15°F from 144°F to 159°F from June 21st to June 22nd, and then a decrease in maximum temperature of 15°F from 159°F to 143°F from June 23rd to June 24th.

- TP-14
  - The 150-foot thermocouple reported a maximum temperature of 249°F on May 10th, which was anomalous and likely associated with a potential thermocouple sensor malfunction. As a result, the reported temperatures of 0°F from May 11th to May 15th are also considered anomalous. The 150-foot thermocouple was replaced on May 16th and temperatures were consistent with previous recorded values.

- TP-23
  - The 15-foot thermocouple reported temperatures of 0°F from May 13th to May 18th, which were anomalous and likely associated with a potential thermocouple sensor malfunction. On May 19th, a temperature of 189°F was reported, with temperatures remaining consistent with previous recorded values through May 27th with the thermocouple functioning as normal. The 15-foot thermocouple wiring


was repaired and temperatures were consistent with previous recorded values.
    - The 30-foot thermocouple reported temperatures of 0°F from May 13th to May 18th, which were anomalous and likely associated with a potential thermocouple sensor malfunction. On May 19th, a temperature of 221°F was reported, with temperatures remaining consistent with previously recorded values through May 27th with the thermocouple functioning as normal.
    - The reported maximum temperature reading of 2508°F at the 30-foot thermocouple is considered anomalous and is believed to be associated with a potential thermocouple sensor malfunction. On May 19th, the 30-foot thermocouple, a temperature of 221°F was reported, with temperatures remaining consistent with previously recorded values through June 25th with the thermocouple functioning as normal. The 30-foot thermocouple wiring was repaired and temperatures were consistent with previous recorded values.

- TP-24
    - The 155-foot thermocouple showed an increase in maximum temperature of 13°F from 167°F to 181°F from June 22nd to June 24th.
    - The 210-foot thermocouple showed a decrease in maximum temperature of 13°F from 202°F to 190°F from June 19th to June 20th, and then an increase in maximum temperature of 12°F from 190°F to 202°F from June 20th to June 23rd.

- TP-25
    - The 90-foot thermocouple showed an increase in maximum temperature of 41°F from 147°F to 189°F from June 4th to June 23rd.
    - The 90-foot thermocouple showed an increase in maximum temperature of 38°F from 151°F to 189°F from June 18th to June 23rd, and then an increase in maximum temperature of 36°F from 153°F to 189°F from June 22nd to June 23rd.

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39


Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS


Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40

Maximum data for 5/14/2026 12:00 AM to 6/24/2026 12:00 AM



SCS ENGINEERS

Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill



Max Temps - 04:58:44 06-25-2026

Current | 7 Day | 30 Day

BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	157	15
TP02	157	60
TP03	233	45
TP04	158	60
TP05	166	45
TP06	139	100
TP07	154	100
TP08	168	45
TP09	208	125
TP10	156	125
TP11	209	125
TP12	150	125
TP13	172	140
TP14	172	150
TP15	203	100
TP16	170	30
TP17	161	125
TP18	209	45
TP19	237	150
TP20	140	45
TP21	252	110
TP22	198	15
TP23	260	75
TP24	211	265
TP25	210	130
TP26	178	150
TP27	157	100
TP28	144	170
TP29	196	240
TP30	175	190
TP31	193	180
TP32	170	130
TP33	194	45
TP34	152	120
TP35	175	140
TP36	172	165
TP37	184	180
TP38	172	165
TP39	159	160
TP40	149	185

Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM

SCS ENGINEERS

07224053.00 | July 2, 2026

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

From June 25, 2026, through July 1, 2026, there were three recorded temperature increases and five recorded temperature decreases that triggered the notification limits set forth in the LEA's October 4, 2024 letter.

Chiquita provides the following updates:

- TP-08
  - The 30-foot thermocouple showed a decrease in maximum temperature of 12°F from 157°F to 145°F from June 23rd to June 25th.
  - The 45-foot thermocouple showed a decrease in maximum temperature of 30°F from 167°F to 137°F from June 23rd to July 1st.


- TP-13
  - The 45-foot thermocouple remained consistent with previous recorded temperatures.

- TP-24
  - The 155-foot thermocouple showed a decrease in maximum temperature of 15°F from 183°F to 168°F from June 27th to June 28th, and then an increase in maximum temperature of 9°F from 168°F to 177°F from June 28th to June 29th.
  - The 210-foot thermocouple showed a decrease in maximum temperature of 13°F from 204°F to 191°F from June 27th to June 28th, then an increase in maximum temperature of 12°F from 191°F to 203°F from June 28th to June 29th, and then a decrease in maximum temperature of 10°F from 200°F to 190°F from June 30th to July 1st.

- TP-25
  - The 90-foot thermocouple showed an increase in maximum temperature of 10°F from 193°F to 203°F from June 25th to June 27th.

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS


Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40

Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill



Max Temps - 04:58:46 07-02-2026

Current | 7 Day | 30 Day

BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	160	15
TP02	157	60
TP03	233	45
TP04	158	60
TP05	165	75
TP06	139	100
TP07	154	100
TP08	145	30
TP09	208	125
TP10	156	125
TP11	209	125
TP12	150	125
TP13	172	140
TP14	172	150
TP15	202	100
TP16	168	30
TP17	161	125
TP18	210	45
TP19	237	150
TP20	142	45
TP21	249	110
TP22	198	15
TP23	259	75
TP24	211	265
TP25	216	130
TP26	178	150
TP27	156	100
TP28	143	170
TP29	193	240
TP30	175	190
TP31	193	180
TP32	170	130
TP33	194	45
TP34	152	120
TP35	175	140
TP36	172	165
TP37	184	180
TP38	172	165
TP39	159	160
TP40	149	185

Attachment E

July 15, 2026

Reaction Mitigation Area Boundary Determination

July 10, 2026
Revised July 15, 2026
File No. 01204123.21-13

Mr. Baitong Chen
South Coast Air Quality Management District
21865 Copley Drive
Diamond Bar, California 91765

Subject: Revised Monthly Reaction Mitigation Area Boundary Determination
Chiquita Canyon Landfill – Castaic, California

Dear Mr. Chen:

In accordance with Condition Nos. 9(a) and 9(b) of the Modified Stipulated Order for Abatement (SOFA) pertaining to the Chiquita Canyon Landfill (Landfill or Facility) (Case No. 6177-4), as last modified on June 3, 2026, SCS Engineers (SCS), on behalf of Chiquita Canyon, LLC (Chiquita), has prepared this revised data-determined Reaction Mitigation Area boundary determination for June 2026.

This revised Reaction Mitigation Area boundary determination has been developed to incorporate the temperature probe data and is intended to supersede the boundary determination that was submitted on July 10, 2026. This revision includes this data in **Attachment B** and the determination considers the following criteria:

- Vertical landfill gas (LFG) wellhead temperatures (greater than 160 degrees Fahrenheit).
- Temperature monitoring probe (TMP) measurements (greater than 170 degrees Fahrenheit for more than 3-weeks at any depth).
- Landfill gas quality and methane to CO_2 ratio (CH_4:CO_2) (methane concentrations of less than 30 percent in conjunction with CH_4:CO_2 ratios less than 1.0).
- Landfill gas concentration of carbon monoxide (CO) (greater than 1,500 ppm) to the extent measured.
- Landfill gas concentration of hydrogen (H_2) (greater than 2 percent by volume), to the extent measured.
- Landfill settlement (18 inches or greater within a 60-day period).
- Pressurized leachate releases.

These parameters have been subjected to a cumulative evaluation within each individual landfill surface grid within the Main Canyon (i.e., excluding grids 1 through 29 as well as grids 105 through 144), including all landfill gas wells, temperature probes, and other characteristics within that grid's area. Under the recently modified Condition No. 9(b), for each individual landfill grid that is contiguous to the prior month's Reaction Mitigation Area, where any three or more parameters listed

above are present at the time of evaluation, including any combination of wells, temperature probes, or areas within the grid, the Reaction Mitigation Area boundary depicted on the Reaction Mitigation Area map (**Attachment A**) will include such landfill grid(s).

For each individual landfill grid that is not contiguous to the prior month's Reaction Mitigation Area, if the three parameters present include a temperature parameter (the first or second parameter listed above), then the grid will be added to the Reaction Mitigation Area. For each individual landfill grid that is not contiguous to the prior month's Reaction Mitigation Area, if the three parameters present do not include a temperature parameter, then Chiquita will conduct field testing for CO using colorimetric tubes and for H_2 using field instrumentation. If field testing confirms the presence of either CO or H_2 at concentrations in excess of the lower limits of the instrumentation, then a sample of the LFG will be obtained from the wellhead and subjected to lab analytical testing using U.S. EPA Method ALT-144 for CO and ASTM Method D-1946 for H_2. If the lab testing confirms that either of these parameters exceed the values listed above, then the grid will be added to the Reaction Mitigation Area.

In addition to the parameters listed above, the following factors were also considered in determining the Reaction Mitigation Area boundary, applying the same individual landfill grid-based methodology described above:

- Leachate seeps;
- Odor characteristics;
- Wellheads experiencing conditions which would be expected to result in a PLR (e.g. elevated pressure, elevated temperature, liquid flow through wellhead); and
- Waste cuttings according to borehole drilling logs.

Supporting evidence, including documentation of which parameters were met or exceeded for each individual landfill grid, field testing and laboratory results (if applicable), explanation for the determination, Reaction Mitigation Area boundary, Reaction Mitigation Area map (if applicable), isothermal gradient range map consisting of wellhead temperature measurements, wellhead carbon monoxide range map, wellhead hydrogen range map, wellhead CH_4:CO_2 ratio range map, monthly landfill settlement isopach maps and 60-day isopach map, wellhead and temperature probe map with surface grids displayed, and vertical temperature profiles for temperature probes is being hereby submitted to the South Coast Air Quality Management District.

Attachment A presents the Drawing, titled "Reaction Mitigation Area Map", which depicts the Reaction Mitigation Area boundary as prescribed in Condition No. 9(a), which corresponds to the limits of Cells 1/2A, 2B/3, 4, and Module 2B/3/4 P2, as a solid black line. The Drawing also depicts the Condition No. 9(b) data-determined Reaction Mitigation Area as a dashed magenta line.

REACTION MITIGATION AREA BOUNDARY

Based on the parameters and considerations above, the Reaction Mitigation Area boundary includes those grids corresponding to the area encompassed by last month's data-driven Reaction Mitigation Area boundary determination, excluding Grid No. 41 and including Grid Nos. 81 and 182.

Based on input from Chiquita, the change in landfill surface elevations in select grids positioned in the northeastern portion of Cell 1/2A and Module 2B/3/4 P2, as well as to the south of Cell 2B/3 and Module 4, was affiliated with earthwork, grading, and stripping of intermediate cover in preparation for ethylene vinyl alcohol (EVOH) geomembrane cover deployment. While it is recognized that some settlement in these areas may have occurred, the earthwork and cover removal activities are believed to be the predominant contributor to the elevation change experienced over the past month or so. Accordingly, the landfill surface elevation change in these grids was not considered to exhibit the settlement criteria during this monthly exercise.

Parameters in Contiguous Grids

- Grid No. 81 is positioned immediately east of and adjacent to Grid No. 149, south of and adjacent to Grid No. 53, and north of and adjacent to Grid No. 82, all three of which were included in last month's Reaction Mitigation Area boundary. Accordingly, Grid No. 81 is being incorporated in the Reaction Mitigation Area boundary for this month as a contiguous surface grid based on the temperature, poor LFG quality, CO concentration, and H_2 concentration at well CV-2551.

- Grid No. 182 is positioned immediately northwest of and adjacent to Grid No. 181, and southwest of and adjacent to Grid No. 183, both of which were included in last month's Reaction Mitigation Area boundary. Accordingly, Grid No. 182 is being incorporated in the Reaction Mitigation Area boundary for this month as a contiguous surface grid based on the poor LFG quality at wells CV-1901, CV-2336, and CV-24141.

Parameters in Non-Contiguous Grids

- Grid No. 41 was included in last month's Reaction Mitigation Area boundary as a non-contiguous grid. Although the grid contains one well that exhibits the poor LFG quality and H_2 concentration criteria, a third parameter was not present within this grid this month. Accordingly, Grid No. 41 is being removed from the Reaction Mitigation Area boundary for this month as a non-contiguous surface grid.

CONCLUSION

As presented on the Drawing included as **Attachment A**, and for the reasons described above, the extent of the data-determined Reaction Mitigation Area (dashed magenta line) includes Cells 1/2A, 2B/3, 4, and Module 2B/3/4 P2 as decreed in the SOFA (solid black line), and Grid Nos. 53, 76, 77, 81, 82, and 145 through 149.

The maximum temperature measurements recorded at the 40 in-situ waste temperature monitoring probes presented in **Attachment B** in graphical format were excluded from the original submission because of technical difficulties extracting the measurements from the electronic database. This TMP data has been included in this revised submission now that the issue has been resolved. The LFG wellhead temperatures recorded at the extraction wells for the entire Landfill footprint are reflected on the isothermal gradient range map presented as **Attachment C**. The CH_4:CO_2 ratios measured at the LFG wellheads in the vicinity of the data-driven Reaction Mitigation Area boundary are depicted on the range map presented as **Attachment D**. The H_2 concentrations measured at the LFG wellheads in the vicinity of the data-driven Reaction Mitigation Area boundary are depicted on the range map presented as **Attachment E**. The CO concentrations measured at the LFG wellheads in

the vicinity of the data-driven Reaction Mitigation Area boundary are depicted on the range map presented as **Attachment F**. The landfill surface settlement isopach values measured on a monthly basis and 60-day basis in the vicinity of the data-driven Reaction Mitigation Area boundary are depicted on the range map presented as **Attachment G**.

Please contact either of the undersigned if you have questions or require additional information.

Sincerely,

Robert E. Dick, PE, BCEE
Senior Vice President
SCS Engineers

Patrick S. Sullivan, BCES, CCP
Senior Vice President
SCS Engineers

RED/PSS


cc: Nathaniel Dickel, SCAQMD
Christina Ojeda, SCAQMD

Enclosures:

Attachment A – Reaction Mitigation Area Map
Attachment B – In-Situ Waste Temperature Monitoring Probe Data
Attachment C – Isothermal Gradient Range Map
Attachment D – Wellhead Methane-to-Carbon Dioxide Ratio Range Map
Attachment E – Wellhead Hydrogen Range Map
Attachment F – Wellhead Carbon Monoxide Range Map
Attachment G – Settlement Isopach Range Maps

Attachment A

Reaction Mitigation Area Map



GENERAL DRAWING NOTES:

1. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

DATE | REVISION | NO.

SHEET TITLE: REACTION MITIGATION AREA - JUNE 2026

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 100
LONG BEACH, CA 90806
PH. (562) 426-9544

PROJ. NO. 01204123.45 | DSN. BY: - | DWN. BY: HA | CHK. BY: - | APP. BY: - | ACAD: N:\CAD\ASBUILT-MASTERS

DATE: 07/09/2026

SCALE: AS SHOWN

1 of 1


\\SAN-FS02\Data\Files\Engineers\Waste Connections\Chiquita Canyon LF\2026 Reaction Area Maps\06-June\DWG\CCLF June 2026 Reaction Area with Settlement Area & Data Analysis_2026-07-07.dwg Jul 10, 2026 - 5:41pm By: hali

Attachment B

In-Situ Waste Temperature Monitoring Probe Data

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Apr 15, 2024 Apr 22, 2024 Apr 29, 2024 May 6, 2024 May 5, 2026 May 12, 2026 May 19, 2026
May 26, 2026 Jun 2, 2026 Jun 9, 2026 Jun 16, 2026 Jun 23, 2026 Jun 30, 2026
Jul 7, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Apr 15, 2024
Apr 22, 2024
Apr 29, 2024
May 6, 2024
May 5, 2026
May 12, 2026
May 19, 2026
May 26, 2026
Jun 2, 2026
Jun 9, 2026
Jun 16, 2026
Jun 23, 2026
Jun 30, 2026
Jul 7, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Apr 15, 2024 Apr 22, 2024 Apr 29, 2024 May 6, 2024 May 5, 2026 May 12, 2026 May 19, 2026
May 26, 2026 Jun 2, 2026 Jun 9, 2026 Jun 16, 2026 Jun 23, 2026 Jun 30, 2026
Jul 7, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Apr 7, 2025 Apr 14, 2025 Apr 21, 2025 Apr 28, 2025 May 5, 2026 May 12, 2026 May 19, 2026
May 26, 2026 Jun 2, 2026 Jun 9, 2026 Jun 16, 2026 Jun 23, 2026 Jun 30, 2026
Jul 7, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Feb 16, 2026 Feb 23, 2026 Mar 2, 2026 Mar 9, 2026 May 5, 2026 May 12, 2026 May 19, 2026
May 26, 2026 Jun 2, 2026 Jun 9, 2026 Jun 16, 2026 Jun 23, 2026 Jun 30, 2026
Jul 7, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Feb 10, 2025
Feb 17, 2025
Feb 24, 2025
Mar 3, 2025
May 5, 2026
May 12, 2026
May 19, 2026
May 26, 2026
Jun 2, 2026
Jun 9, 2026
Jun 16, 2026
Jun 23, 2026
Jun 30, 2026
Jul 7, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Attachment C

Isothermal Gradient Range Map



GENERAL DRAWING NOTES:

1. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

DATE
REVISION
NO.

SHEET TITLE: ISOTHERMAL GRADIENT MAP JUNE 2026

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3800 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH. (562) 426-9544

DRWN. BY: SRM
CHK. BY:
APP. BY: -
ACAD FILE:
PROJ. NO. 01204123.41
DSN. BY: -

DATE: 07/10/2026


SCALE: AS SHOWN

SHEET: 1

J:\SAN-FS02\Data\Files\Engineers\Waste Connections\Chiquita Canyon LF\2026 Temp Probe Data\Isothermal Gradient Maps\06-June 2026\05-08.dwg Jul 10, 2026 4:16pm By: hall
06-June 2026 CCLF Isothermal Map-April 2026_V1.0_2026

Attachment D

Wellhead Methane-to-Carbon Dioxide Ratio Range Map



Ranges Mapped

						# Points
	>=	0	and	<	0.5	173
	>=	0.5	and	<	0.9	74
	>=	0.9	and	<	1.1	54
	>=	1.1	and	<	1.5	77
	>=	1.5	and	<	101	

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill

Range Map

Parameter: CH4/CO2 Ratio (high range)


Analysis Method: MostRecent

Date Range: 06/01/2026 - 06/30/2026

Map generation date : 07/10/2026

Attachment E

Wellhead Hydrogen Range Map



Ranges Mapped

						# Points
	>=	0	and	<	20000	20
	>=	20000	and	<	50000	11
	>=	50000	and	<	100000	16
	>=	100000	and	<	999999	62

The range values noted above are in units of parts per million (ppm). Divide by 10,000 to convert these values to units of percent by volume.

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill

Range Map

Parameter: H2 (mid range)


Analysis Method: MostRecent

Date Range: 06/01/2026 - 06/30/2026

Map generation date : 07/10/2026

Attachment F

Wellhead Carbon Monoxide Range Map



Ranges Mapped

						# Points
	>=	0	and	<	500	30
	>=	500	and	<	1000	22
	>=	1000	and	<	1500	21
	>=	1500	and	<	2000	14
	>=	2000	and	<	5000	38
	>=	5000	and	<	100000	1

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill

Range Map

Parameter: CO LAB (mid range)


Analysis Method: MostRecent

Date Range: 06/01/2026 - 06/30/2026

Map generation date : 07/10/2026

Attachment G

Settlement Isopach Range Maps


April 30, 2026
vs July 1, 2026
-10 ft
-1.5 ft
1.5 ft
10 ft


May 27, 2026
vs July 1, 2026
-10 ft
-1.5 ft
1.5 ft
10 ft

July 10, 2026
File No. 01204123.21-13

Mr. Baitong Chen
South Coast Air Quality Management District
21865 Copley Drive
Diamond Bar, California 91765

Subject: Monthly Reaction Mitigation Area Boundary Determination
Chiquita Canyon Landfill – Castaic, California

Dear Mr. Chen:

In accordance with Condition Nos. 9(a) and 9(b) of the Modified Stipulated Order for Abatement (SOFA) pertaining to the Chiquita Canyon Landfill (Landfill or Facility) (Case No. 6177-4), as last modified on June 3, 2026, SCS Engineers (SCS), on behalf of Chiquita Canyon, LLC (Chiquita), has prepared this data-determined Reaction Mitigation Area boundary determination for June 2026 considering the following criteria:

- Vertical landfill gas (LFG) wellhead temperatures (greater than 160 degrees Fahrenheit).
- Temperature monitoring probe (TMP) measurements (greater than 170 degrees Fahrenheit for more than 3-weeks at any depth).
- Landfill gas quality and methane to CO_2 ratio (CH_4:CO_2) (methane concentrations of less than 30 percent in conjunction with CH_4:CO_2 ratios less than 1.0).
- Landfill gas concentration of carbon monoxide (CO) (greater than 1,500 ppm) to the extent measured.
- Landfill gas concentration of hydrogen (H_2) (greater than 2 percent by volume), to the extent measured.
- Landfill settlement (18 inches or greater within a 60-day period).
- Pressurized leachate releases.

These parameters have been subjected to a cumulative evaluation within each individual landfill surface grid within the Main Canyon (i.e., excluding grids 1 through 29 as well as grids 105 through 144), including all landfill gas wells, temperature probes, and other characteristics within that grid's area. Under the recently modified Condition No. 9(b), for each individual landfill grid that is contiguous to the prior month's Reaction Mitigation Area, where any three or more parameters listed above are present at the time of evaluation, including any combination of wells, temperature probes, or areas within the grid, the Reaction Mitigation Area boundary depicted on the Reaction Mitigation Area map (**Attachment A**) will include such landfill grid(s).

For each individual landfill grid that is not contiguous to the prior month's Reaction Mitigation Area, if the three parameters present include a temperature parameter (the first or second parameter listed

above), then the grid will be added to the Reaction Mitigation Area. For each individual landfill grid that is not contiguous to the prior month's Reaction Mitigation Area, if the three parameters present do not include a temperature parameter, then Chiquita will conduct field testing for CO using colorimetric tubes and for H_2 using field instrumentation. If field testing confirms the presence of either CO or H_2 at concentrations in excess of the lower limits of the instrumentation, then a sample of the LFG will be obtained from the wellhead and subjected to lab analytical testing using U.S. EPA Method ALT-144 for CO and ASTM Method D-1946 for H_2. If the lab testing confirms that either of these parameters exceed the values listed above, then the grid will be added to the Reaction Mitigation Area.

In addition to the parameters listed above, the following factors were also considered in determining the Reaction Mitigation Area boundary, applying the same individual landfill grid-based methodology described above:

- Leachate seeps;
- Odor characteristics;
- Wellheads experiencing conditions which would be expected to result in a PLR (e.g. elevated pressure, elevated temperature, liquid flow through wellhead); and
- Waste cuttings according to borehole drilling logs.

Supporting evidence, including documentation of which parameters were met or exceeded for each individual landfill grid, field testing and laboratory results (if applicable), explanation for the determination, Reaction Mitigation Area boundary, Reaction Mitigation Area map (if applicable), isothermal gradient range map consisting of wellhead temperature measurements, wellhead carbon monoxide range map, wellhead hydrogen range map, wellhead CH_4:CO_2 ratio range map, monthly landfill settlement isopach maps and 60-day isopach map, wellhead and temperature probe map with surface grids displayed, and vertical temperature profiles for temperature probes is being hereby submitted to the South Coast Air Quality Management District.

Attachment A presents the Drawing, titled "Reaction Mitigation Area Map", which depicts the Reaction Mitigation Area boundary as prescribed in Condition No. 9(a), which corresponds to the limits of Cells 1/2A, 2B/3, 4, and Module 2B/3/4 P2, as a solid black line. The Drawing also depicts the Condition No. 9(b) data-determined Reaction Mitigation Area as a dashed magenta line.

REACTION MITIGATION AREA BOUNDARY

Based on the parameters and considerations above, the Reaction Mitigation Area boundary includes those grids corresponding to the area encompassed by last month's data-driven Reaction Mitigation Area boundary determination, excluding Grid No. 41 and including Grid Nos. 81 and 182.

Based on input from Chiquita, the change in landfill surface elevations in select grids positioned in the northeastern portion of Cell 1/2A and Module 2B/3/4 P2, as well as to the south of Cell 2B/3 and Module 4, was affiliated with earthwork, grading, and stripping of intermediate cover in preparation for ethylene vinyl alcohol (EVOH) geomembrane cover deployment. While it is recognized that some settlement in these areas may have occurred, the earthwork and cover removal activities are believed to be the predominant contributor to the elevation change experienced over the past

month or so. Accordingly, the landfill surface elevation change in these grids was not considered to exhibit the settlement criteria during this monthly exercise.

Parameters in Contiguous Grids

- Grid No. 81 is positioned immediately east of and adjacent to Grid No. 149, south of and adjacent to Grid No. 53, and north of and adjacent to Grid No. 82, all three of which were included in last month's Reaction Mitigation Area boundary. Accordingly, Grid No. 81 is being incorporated in the Reaction Mitigation Area boundary for this month as a contiguous surface grid based on the temperature, poor LFG quality, CO concentration, and H_2 concentration at well CV-2551.

- Grid No. 182 is positioned immediately northwest of and adjacent to Grid No. 181, and southwest of and adjacent to Grid No. 183, both of which were included in last month's Reaction Mitigation Area boundary. Accordingly, Grid No. 182 is being incorporated in the Reaction Mitigation Area boundary for this month as a contiguous surface grid based on the poor LFG quality at wells CV-1901, CV-2336, and CV-24141.

Parameters in Non-Contiguous Grids

- Grid No. 41 was included in last month's Reaction Mitigation Area boundary as a non-contiguous grid. Although the grid contains one well that exhibits the poor LFG quality and H_2 concentration criteria, a third parameter was not present within this grid this month. Accordingly, Grid No. 41 is being removed from the Reaction Mitigation Area boundary for this month as a non-contiguous surface grid.

CONCLUSION

As presented on the Drawing included as **Attachment A**, and for the reasons described above, the extent of the data-determined Reaction Mitigation Area (dashed magenta line) includes Cells 1/2A, 2B/3, 4, and Module 2B/3/4 P2 as decreed in the SOFA (solid black line), and Grid Nos. 53, 76, 77, 81, 82, and 145 through 149.

The maximum temperature measurements recorded at the 40 in-situ waste temperature monitoring probes (both 7-Day and 30-Day values) during the month that is typically presented in **Attachment B** in graphical format has been excluded from this submission because of technical difficulties extracting the measurements from the electronic database. This TMP data will be submitted as soon as this issue has been resolved. The LFG wellhead temperatures recorded at the extraction wells for the entire Landfill footprint are reflected on the isothermal gradient range map presented as **Attachment C**. The CH_4:CO_2 ratios measured at the LFG wellheads in the vicinity of the data-driven Reaction Mitigation Area boundary are depicted on the range map presented as **Attachment D**. The H_2 concentrations measured at the LFG wellheads in the vicinity of the data-driven Reaction Mitigation Area boundary are depicted on the range map presented as **Attachment E**. The CO concentrations measured at the LFG wellheads in the vicinity of the data-driven Reaction Mitigation Area boundary are depicted on the range map presented as **Attachment F**. The landfill surface settlement isopach values measured on a monthly basis and 60-day basis in the vicinity of the data-driven Reaction Mitigation Area boundary are depicted on the range map presented as **Attachment G**.

Please contact either of the undersigned if you have questions or require additional information.

Sincerely,

Robert E. Dick, PE, BCEE
Senior Vice President
SCS Engineers

Patrick S. Sullivan, BCES, CCP
Senior Vice President
SCS Engineers

RED/PSS


cc: Nathaniel Dickel, SCAQMD
Christina Ojeda, SCAQMD

Enclosures:

Attachment A – Reaction Mitigation Area Map
Attachment B – In-Situ Waste Temperature Monitoring Probe Data
Attachment C – Isothermal Gradient Range Map
Attachment D – Wellhead Methane-to-Carbon Dioxide Ratio Range Map
Attachment E – Wellhead Hydrogen Range Map
Attachment F – Wellhead Carbon Monoxide Range Map
Attachment G – Settlement Isopach Range Maps

Attachment A

Reaction Mitigation Area Map



GENERAL DRAWING NOTES:

1. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

DATE | REVISION | NO.

SHEET TITLE: REACTION MITIGATION AREA - JUNE 2026

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 100
LONG BEACH, CA 90806
PH. (562) 426-9544

PROJ. NO. 01204123.45 | DSN. BY: - | CHK. BY: - | DWN. BY: HA | APP. BY: - | ACAD: N:\CAD\ASBUILT-MASTERS

DATE: 07/09/2026

SCALE: AS SHOWN

1 of 1

\\SAN-FS02\Data\Files\Engineers\Waste Connections\Chiquita Canyon LF\2026 Reaction Area Maps\06-June\DWG\CCLF June 2026 Reaction Area with Settlement Area & Data Analysis_2026-07-07.dwg Jul 10, 2026 - 5:41pm By: hali


Attachment B

In-Situ Waste Temperature Monitoring Probe Data

The maximum temperature measurements recorded at the 40 in-situ waste temperature monitoring probes that is typically presented in **Attachment B** in graphical format has been excluded from this submission because of technical difficulties extracting the measurements from the electronic database. This TMP data will be submitted as soon as this issue has been resolved.

Attachment C

Isothermal Gradient Range Map



GENERAL DRAWING NOTES:

1. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

DATE

REVISION

NO.

SHEET TITLE: ISOTHERMAL GRADIENT MAP JUNE 2026

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3800 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH. (562) 426-9544

PROJ. NO. 01204123.41
DSN. BY: -
DWN. BY: SRM
CHK. BY:
AUTO. REF.
APP. BY: -
ENGINEERS

DATE: 07/10/2026


SCALE: AS SHOWN

SHEET: 1

J:\SAN-FS02\Data\Files\Engineers\Waste Connections\Chiquita Canyon LF\2026 Temp Probe Data\Isothermal Gradient Maps\06-June 2026\05-08.dwg Jul 10, 2026 4:16pm By: hall
June 2026 CCLF Isothermal Map - April 2026_V1.0_2026

Attachment D

Wellhead Methane-to-Carbon Dioxide Ratio Range Map



Ranges Mapped

						# Points
	>=	0	and	<	0.5	173
	>=	0.5	and	<	0.9	74
	>=	0.9	and	<	1.1	54
	>=	1.1	and	<	1.5	77
	>=	1.5	and	<	101	

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill

Range Map

Parameter: CH4/CO2 Ratio (high range)


Analysis Method: MostRecent

Date Range: 06/01/2026 - 06/30/2026

Map generation date : 07/10/2026

Attachment E

Wellhead Hydrogen Range Map



Ranges Mapped

						# Points
	>=	0	and	<	20000	20
	>=	20000	and	<	50000	11
	>=	50000	and	<	100000	16
	>=	100000	and	<	999999	62

The range values noted above are in units of parts per million (ppm). Divide by 10,000 to convert these values to units of percent by volume.

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill

Range Map

Parameter: H2 (mid range)


Analysis Method: MostRecent

Date Range: 06/01/2026 - 06/30/2026

Map generation date : 07/10/2026

Attachment F

Wellhead Carbon Monoxide Range Map



Ranges Mapped

						# Points
	>=	0	and	<	500	30
	>=	500	and	<	1000	22
	>=	1000	and	<	1500	21
	>=	1500	and	<	2000	14
	>=	2000	and	<	5000	38
	>=	5000	and	<	100000	1

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill

Range Map

Parameter: CO LAB (mid range)


Analysis Method: MostRecent

Date Range: 06/01/2026 - 06/30/2026

Map generation date : 07/10/2026

Attachment G

Settlement Isopach Range Maps



April 30, 2026
vs July 1, 2026
-10 ft
-1.5 ft
1.5 ft
10 ft



May 27, 2026
vs July 1, 2026
-10 ft
-1.5 ft
1.5 ft
10 ft

Attachment F

June 2026 Isopach Map

Chiquita Canyon Landfill -Isopach





June 24, 2026 Survey Image. June 2, 2026 vs June 24, 2026