SCS ENGINEERS

14 de agosto de 2026

Karen Gork
Jefa Especialista en Salud Ambiental
Agencia de Aplicación Local del Condado de Los Ángeles
5050 Commerce Drive
Baldwin Park, California 91706

Asunto: **Informe Mensual de julio de 2026 Conforme a los Objetivos 1A-3 y 5 de la Orden de Cumplimiento de la LEA del 6 de junio de 2024 y a la Carta del 30 de julio de 2024, Vertedero de Chiquita Canyon, Castaic, California**

Estimada Sra. Gork:

SCS Engineers (SCS), en nombre de Chiquita Canyon, LLC (Chiquita), mediante el presente le proporciona al Programa de Gestión de Desechos Sólidos del Departamento de Salud Pública del Condado de Los Ángeles, que actúa como Agencia de Cumplimiento Local (LEA), un informe mensual, en cumplimiento con los Objetivos 1A-3 y 5 de la Orden de Cumplimiento de la LEA con fecha 6 de junio de 2024 (Orden de Cumplimiento) y la correspondencia posterior relacionada recibida de la LEA. Este informe abarca el período mensual de julio de 2026.

Chiquita Canyon Landfill (CCL o el Vertedero) es un vertedero/centro de disposición de desechos sólidos, ubicado en 29201 Henry Mayo Drive en Castaic, California. Con relación al Vertedero, Chiquita opera un sistema de recolección y control de biogás. SCS elaboró y presentó el Informe Resumido sobre las Lecturas de Monóxido de carbono e Hidrógeno (Informe Resumido) a la LEA el 6 de junio de 2024 en nombre de Chiquita, en respuesta a las directivas indicadas en las cartas de la LEA con fecha 5 de abril de 2024 y 28 de mayo de 2024, sobre la toma de datos de biogás y conforme al Objetivo 1A-2 de la Orden de Cumplimiento. La LEA, en colaboración con el Departamento de Recursos, Reciclaje y Recuperación de California (CalRecycle), revisó el Informe Resumido y determinó que cumplía con el Objetivo 1A-2. La LEA estableció varios requerimientos nuevos para que Chiquita cumpla con el Objetivo 1A-3 en la correspondencia de seguimiento con fecha 30 de julio de 2024.

Este informe fue elaborado según los Objetivos 1A-3 y 5 de la Orden de Cumplimiento, la correspondencia de seguimiento de la LEA con fecha 30 de julio de 2024, la carta de Chiquita con fecha 3 de septiembre de 2024, la reunión del 12 de septiembre de 2024 con la LEA y la correspondencia de seguimiento de la LEA con fecha 19 y 27 de noviembre y 3 de diciembre de 2024.

Puntos de Cumplimiento con el Objetivo 1A-3

1. Presentar los resultados de los análisis de laboratorio de las muestras mensuales de monóxido de carbono (CO) e hidrógeno (H2) tomadas de un conjunto de pozos de biogás (LFG) seleccionados por la LEA. Consulte en la Tabla 1, las columnas rotuladas "CO" y "H2".

Los resultados de los pozos monitoreados se muestran en el **Adjunto A**.[1] Los datos se están presentando a la LEA en un informe independiente firmado por un ingeniero matriculado, conforme al Objetivo 1A-3 de la Orden de Cumplimiento. Como se indicó en correspondencias previas de Chiquita y en los informes mensuales, este informe no incluye datos de los pozos CV-100, CV-103, CV-1420, CV-1423, CV-1532, CV-2202, H-1403W, H-1560S, H-1774S, SC-2001W, TC-2383S, TC-2385A y TC-2385S, ya que esos pozos fueron abandonados, ni tampoco del pozo CV-2332, ya que no se instaló nunca. Todos los demás pozos se evaluaron durante el mes de julio de 2026.

Como se trató en la reunión del 12 de septiembre de 2024 y como se informó previamente, los gráficos que muestran las tendencias de CO y H2 se proporcionan en el **Adjunto D** y se tratan en mayor detalle a continuación.

2. Proporcionar datos de lecturas de gases fijos (CH4, O2 y CO2) entre un conjunto de pozos de LFG seleccionado por la LEA. Consulte en la Tabla 1 la columna rotulada "Gas Fijo CH4, O2, CO2".

Los resultados de los pozos monitoreados se proporcionan en el **Adjunto A**.

3. Tomar temperaturas pozo abajo en 34 pozos, para confirmar las lecturas de las temperaturas de los cabezales de los pozos de gas según el requerimiento de los Estándares de Rendimiento de Fuentes Nuevas (NSPS). Consulte en la Tabla 1 en la columna rotulada "Monitoreo de Temperatura Pozo Abajo".

Chiquita entiende de la correspondencia de la LEA del 27 de noviembre de 2024 y como se indica en los informes mensuales previos, que en este momento solo debe tomar muestras de los pozos a la frecuencia anual indicada en los protocolos NSPS, pero que la LEA podrá requerir monitoreos más frecuentes de hasta diez (10) pozos seleccionados por la LEA. Chiquita está a la espera de la selección de la LEA de esos pozos.

Chiquita proporciona de todos modos en el **Adjunto B** los gráficos de las temperaturas pozo abajo[2] relacionados con los siguientes pozos, desde lugares fijos, que contienen el Sistema de Bombeo Lorentz con los sensores de temperatura integrales mientras estaban en operación durante julio de 2026: CV-2302, CV-2303, CV-24017, CV-24065 y CV-24095

Se debe tener en cuenta que las siguientes ubicaciones, CV-2301, CV-2350 y CV-2352, ya no tienen gráficos disponibles debido a varios problemas relacionados con los equipos, que incluyen revestimientos dañados. (Consulte la Lista de Monitoreos del **Adjunto B**).

---

[1] Los laboratorios informaron datos de otros pozos de LFG fuera de los seleccionados para que la LEA tome muestras; los datos adicionales están relacionados con requerimientos de informes separados del Distrito de Gestión de la Calidad del Aire de la Costa Sur (AQMD de la Costa Sur) y por lo tanto pueden desestimarse para los propósitos de este informe.

[2] Cada gráfico indica un punto de datos de temperatura único debido a cambios en el software.

SCS continuará tomando las temperaturas pozo abajo todos los años e informará los resultados a medida que vaya obteniendo datos de cada lugar. SCS ha realizado el monitoreo anual de las temperaturas pozo abajo en 21 ubicaciones hasta fines de julio de 2026 (Los resultados se muestran en el **Adjunto B**). El resto de los ocho (8) pozos se va a monitorear según los requerimientos anuales y a medida que se vayan reparando o cambiando las bombas (Consulte en el **Adjunto B** las fechas y los lugares restantes de los monitoreos de los pozos).

4. Tomar muestras de los 40 pozos seleccionados para analizar VOCs utilizando el método TO-15. Consulte en la Tabla 1, la columna rotulada "VOC (TO-15)".

Los resultados de los pozos monitoreados se proporcionan en el **Adjunto A**.[3]. Se debe tener en cuenta que las 31 ubicaciones de toma de muestras de VOC se testearon durante julio de 2026. No se tomaron muestras en nueve ubicaciones (CV-100, CV-103, CV-1532, CV-2202, H-1403W, H-1560S, H-1758N, H-1774S y TC-2385A) ya que fueron abandonadas.

5. Continuar tomando muestras y monitoreando los 6 pozos horizontales indicados en el Adjunto 1 donde los números de los pozos están resaltados en amarillo. En este momento podrán liberarse 42 pozos horizontales de las tomas de muestras continuas, pero estos pozos podrán ser incluidos más adelante, dependiendo de las futuras presentaciones de datos. Consulte en la Tabla 1 los números de pozo resaltados en azul.

Como se indicó en la carta del 3 de septiembre de 2024 y se informó en los informes mensuales previos, dos (2) de los seis (6) pozos horizontales (H-1774S y H-1560S) fueron abandonados cuando se instalaron los nuevos pozos de extracción vertical. Además, desde ese momento se abandonó H-1403W. Por lo tanto, no están incluidos los datos de esos pozos. Los datos de los otros tres (3) pozos horizontales están en el **Adjunto A**.

6. Agregar 20 pozos verticales a los protocolos de toma de muestras mensuales de temperatura en el cabezal y de LFG. Consulte la Tabla 1.

Como lo transmitió la LEA durante nuestra reunión del 12 de septiembre de 2024 y se volvió a indicar en nuestro informe mensual, comprendemos que la LEA está requiriendo datos analíticos de laboratorio para gases fijos, CO y H2, como también datos de campo. Los resultados del laboratorio están en el **Adjunto A**. Los datos de campo con las temperaturas del gas en el cabezal del pozo se muestran en la Tabla 2 en el **Adjunto A**.

Comprendemos de la correspondencia de la LEA del 27 de noviembre de 2024 que se requerirán datos analíticos del laboratorio para los gases fijos especificados.

Como se indicó en los informes de los meses previos, no se tomaron muestras en los siguientes pozos en julio de 2026 por los motivos identificados a continuación:

CV-1420 – Abandonado durante la Expansión del GCCS en 2024 debido a la reducción de los flujos de gas.

[3] El Pozo CV-24142 aparece dos veces en la Tabla 1 de la carta de la LEA del 30 de julio de 2024 - uno requiere tomas de muestras de VOC y el otro no. Chiquita tomó muestras de este pozo para analizar los VOCs.

CV-2202 – Abandonado durante la Expansión del GCCS en 2024 debido a la reducción de los flujos de gas.
CV-2332 – Este pozo no existe. Este pozo fue propuesto para instalación en otoño de 2023, pero se instalaron otros pozos en la zona en lugar del CV-2332 cuando la cantidad de pozos aumentó según la Orden de Depuración Estipulada (la Orden Estipulada) del Distrito de Gestión de la Calidad del Aire de la Costa Sur (AQMD de la Costa Sur)

7. Trazar en el mapa del sitio denominado "Mapa de GCCS Existentes - Pozos de Extracción Vertical de LFG" con fecha 06/06/2024 las ubicaciones de los siguientes 19 pozos: CV-24002, CV-24003, CV-24007, CV-24017, CV-24053, CV-24055, CV-24065, CV-24071, CV-24075, CV-24077, CV-24079, CV-24082, CV-24083, CV-24088, CV-24095, CV-24096, CV-24097, CV-24098 y H-1403W. Para el pozo H-1403W, proporcionar la ubicación horizontal de las tuberías y un estimativo sobre dónde es más probable que ocurran temperaturas elevadas (195 °F). Consultar en la Tabla 1 los números de pozo resaltados en rojo y H-1403W (resaltado en amarillo).

Las ubicaciones de los pozos arriba identificados se muestran en el Mapa en el **Adjunto C**.[4]

8. Incluir en el informe mensual un mapa del asentamiento/calor como se muestra a continuación, comenzando con los datos del mapa de calor más antiguo disponible para cada mes hasta el presente. Si es posible, los mapas topográficos deberán mostrar intervalos de contornos de 2 pies.

La LEA le indicó a Chiquita el 2 de junio de 2025 que presente mapas isopáquicos mensualmente para cumplir con esta solicitud. Para facilidad de referencia, estamos presentando el 10 de agosto de 2026 como **Adjunto F** una copia del mapa isopáquico de julio de 2026, que se presentó inicialmente a la LEA con los registros de cubiertas semanales.

9. Proporcionar los resultados de las tomas de muestras en un informe independiente apropiado con el análisis, tablas, AQ/QC y métodos, firmado por un profesional registrado, etc., como se describe en los Objetivos 1A-2 y 1A-3 de la Orden de Cumplimiento.

CCL ha proporcionado la información arriba solicitada y los datos crudos en el **Adjunto A**, como también una figura con los datos de asentamientos (consulte el **Adjunto F**). Se proporcionan los gráficos de las temperaturas de los pozos con bombas Lorentz (4 lugares).

Se debe tener en cuenta que además de los pozos indicados en respuesta a la solicitud con fecha 30 de julio de 2024 (en la Tabla 1) que no pudieron ser testeados, tampoco pudieron testearse los siguientes pozos que solo requerían datos analíticos, como se informó previamente, porque fueron abandonados durante la expansión del GCCS de 2024 y 2025 debido a la reducción de flujos de gas, conforme a los requerimientos del NSPS: CV-100, CV-103, CV-1420, CV-1423, CV-1532, CV-2202, H-1403W, H-1560S, H-1774S, SC-2001W, TC-2383S, TC-2385A y TC-2385S. Finalmente, como también se informó previamente, nunca se instaló el CV-2332.

[4] La LEA reconoció en su correspondencia del 20 de noviembre de 2024 que no están ocurriendo temperaturas altas en el pozo H-1403W. Por lo tanto, no trazamos la temperatura máxima en el pozo H-1403W.

Procedimientos para la Toma de Muestras

Se tomaron muestras de gas utilizando bolsas Tedlar o Mylar, como se describe en la carta de Chiquita del 3 de septiembre de 2024 y en los informes mensuales que se entregaron a laboratorios certificados para su análisis. Todos los datos de gases permanentes (CH4, CO2, O2, N2, CO y H2) fueron analizados dentro de las 24 horas solicitadas desde la toma de las muestras. SCS continúa creyendo que el uso del tiempo de retención de 72 horas aprobado por EPA para estas muestras sería apropiado y correcto. Sin embargo, en respuesta a la correspondencia de la LEA del 17 de marzo de 2025, SCS continuará solicitando tiempos de retención de 24 horas para todos los gases fijos, que incluyen CO, H2 y VOCs tomados utilizando bolsas Mylar o Tedlar. No obstante, si se requieren más muestras o si los laboratorios tienen un cambio en la carga de trabajo, este tiempo de retención podrá cambiar, caso en el que se le informará a la LEA como corresponda. Durante julio de 2026, se testearon los VOCs de todos los pozos (método TO-15 de la EPA) y los gases permanentes (métodos 1946 y Alt-144 de la EPA) dentro de las 24 horas, proporcionándole al laboratorio muestras en bolsas duplicadas como se requiere para análisis VOCs.

Se tomaron otros datos de los gases y las presiones utilizando un Medidor de Gas Envision Irwin o un dispositivo de monitoreo de Gases Landtec GEM 5000. Estos instrumentos miden las concentraciones de gas combustible en el aire, directamente en una de dos escalas: la primera, como un porcentaje por volumen del límite explosivo inferior (LEL) de gas metano en el aire (0 a 5 por ciento) y la otra como un porcentaje por volumen (0 a 100 por ciento) en el gas tomado como muestra. El límite de detección de estos instrumentos es de aproximadamente 0.10 por ciento por volumen.

Los procedimientos para testear el monitoreo de gases fueron los siguientes:

- Conectar la tubería de toma de muestras, abrir la válvula de prueba, observar la presión y registrar los datos.
- Encender la bomba de las muestras, purgar un mínimo de un volumen de la sonda y observar y registrar las concentraciones de metano, oxígeno y dióxido de carbono en el gas cuando se hayan estabilizado las lecturas.
- Cerrar la válvula de prueba, desconectar los instrumentos de toma de muestras y resguardar la ubicación de la muestra.

Conclusiones del Objetivo 1A-3

En julio de 2026 se realizó el vigésimo cuarto monitoreo en cumplimiento con el Objetivo 1A-3 de la Orden de Cumplimiento. Los datos tomados en julio de 2026 y evaluados para este informe son consistentes con los datos tomados los meses anteriores desde agosto de 2024 hasta junio de 2026, como también los datos tomados y evaluados por peritos técnicos de Chiquita en cumplimiento con la Orden Estipulada para evaluar el Área de Mitigación de Reacciones, que incluyen los datos de julio de 2026 más recientemente evaluados el 10 de agosto de 2026 como lo requieren las Condiciones 9(a) y 9(b) de la Orden Estipulada, modificada más recientemente el 3 de junio de 2026. (Consulte el **Adjunto E**.)

Por los motivos descritos en la determinación del límite de la Zona de Mitigación de Reacciones adjunta, presentada inicialmente el 10 de agosto de 2026 y en cumplimiento con la Condición No. 9(b) de la Orden Estipulada, la Zona de Mitigación de Reacciones fue ajustada para incluir los siguientes cambios:

- La Cuadrícula No. 211 está posicionada inmediatamente al este y contigua a la Cuadrícula No. 212 y al sur y contigua a la Cuadrícula No. 208 y las dos fueron incluidas en el límite de la Zona de Mitigación de Reacciones del mes pasado. Por lo tanto, la Cuadrícula No. 211 se está incorporando al límite de la Zona de Mitigación de Reacciones para este mes como cuadrícula de superficie contigua en base a concentraciones de metano de menos del 30 por ciento junto con relaciones de metano y dióxido de carbono (CH4:CO2) de menos de 1.0 en los pozos CV-24100, H2165W, H-2272W y H-2273W, como también la concentración de H2 en el pozo H-2165W.

- La Cuadrícula No. 34 está rodeada por las Cuadrículas No. 30, 33, 35 y 38 y ninguna de ellas fue incluida en el límite de la Zona de Mitigación de Reacciones del mes pasado, por lo tanto es una cuadrícula no contigua. La cuadrícula contiene tres pozos (CV-24163, H-1572N y H-1802S) que exhibieron concentraciones de metano de menos del 30 por ciento junto con relaciones de CH_4:CO_2 menores a 1.0. La cuadrícula No. 34 también contiene TP-38 que exhibió una temperatura mayor a 170 grados Fahrenheit por más de tres semanas. Por lo tanto, la Cuadrícula No. 38 se está incluyendo al límite de la Zona de Mitigación de Reacciones para este mes como cuadrícula de superficie no contigua. No se realizó ninguna prueba de campo ni muestreos de laboratorio para CO o para H2 en ninguna boca de pozo dentro de la cuadrícula porque TP-38 excedió un criterio de temperatura.

- La Cuadrícula No. 38 está rodeada por las Cuadrículas No. 34, 37, 39, 42 y 43 y ninguna de ellas fue incluida en el límite de la Zona de Mitigación de Reacciones del mes pasado, por lo tanto es una cuadrícula no contigua. La cuadrícula contiene tres pozos (CV-56S/D, CV-1701S/D y CV-24118) que exhibieron concentraciones de metano de menos del 30 por ciento junto con relaciones de CH_4:CO_2 menores a 1.0. En base a los muestreos de laboratorio para concentraciones de CO y H2 conducidos en estas bocas de pozos, los mismos tres pozos exhibieron concentraciones de H2 mayores al 2 por ciento por volumen y el pozo CV-1701D exhibió una concentración de CO mayor a 1,500 ppm. Por lo tanto, la Cuadrícula No. 38 se está incluyendo al límite de la Zona de Mitigación de Reacciones para este mes como cuadrícula de superficie no contigua.

- La Cuadrícula No. 41 está rodeada por las Cuadrículas No. 36, 37, 40, 42, 45 y 46 y ninguna de ellas fue incluida en el límite de la Zona de Mitigación de Reacciones del mes pasado, por lo tanto es una cuadrícula no contigua. La cuadrícula contiene dos pozos (CV-55R y CV-2011A) que exhibieron concentraciones de metano de menos del 30 por ciento junto con relaciones de CH_4:CO_2 menores a 1.0. El pozo CV-55R también exhibió una concentración de H2 mayor al 2 por ciento por volumen. En base a las muestras de laboratorio para concentraciones de CO y H2 conducidas en estas dos bocas de pozos, el pozo CV-55R exhibió una concentración de H2 mayor al 2 por ciento por volumen. Por lo tanto, la Cuadrícula No. 41 se está incluyendo al límite de la Zona de Mitigación de Reacciones para este mes como cuadrícula de superficie no contigua.

Como los niveles de líquido se reducen debido al reinicio e instalación actual de varias Bombas Eléctricas y Neumáticas Lorentz, que aumentó la remoción de líquido en general, hemos observado los porcentajes de los Gases Permanentes, del Monóxido de Carbono y de Hidrógeno y el cambio de temperatura a medida que estos gases van moviéndose hacia los pozos de extracción para su remoción. Esto se continúa

demostrando en los gráficos de los pozos a varias escalas en el **Adjunto D**, que incluyen gráficos de los gases permanentes, temperatura y otras tendencias en un período de doce (12) meses. Se debe tener en cuenta que los gráficos fueron creados utilizando resultados de equipos de monitoreo de biogás estándar y los resultados no contienen datos de laboratorio. SCS también incluyó gráficos de Hidrógeno y Monóxido de Carbono separados utilizando los resultados del laboratorio, para su uso y revisión de cada pozo.

Además, la instalación de tuberías de mayor diámetro ha mejorado la recolección de otros gases de todo el Vertedero. Desde marzo de 2025, los índices de flujo de biogás que queman los dispositivos de depuración variaron de 13,500 cfm a 17,500 cfm. Durante julio de 2026, la extracción de gas general del Vertedero fue de aproximadamente 731,828,160 pies cúbicos. El índice de extracción de biogás diario de julio fue el más alto hasta la fecha debido a mejoras en el sistema de recolección y control de gases, a un aumento en la remoción de líquidos y al funcionamiento de 8 dispositivos de reducción (3 antorchas y 5 oxidantes térmicos). Podrán ocurrir futuros aumentos en el índice de extracción; sin embargo, el Vertedero se está acercando a los índices de generación de gas máximos teóricos. SCS continuará maximizando la extracción de gas y calor a medida que los sistemas de recolección continúan expandiéndose y a medida que va cambiando la composición del gas de los pozos en la Zona de Mitigación de Reacciones, ya que más vacío, la remoción del líquido y el movimiento de gas resultante permiten que haya más reacción y que se extraiga biogás normal.

Chiquita continuará evaluando los datos en futuros informes mensuales, a medida que se vayan tomando más datos.

<u>Puntos de Cumplimiento con el Objetivo 5</u>

Este informe incluye en el **Adjunto D** mapas individuales superpuestos con los siguientes datos para julio de 2026, en un formato fácil de comprender, conforme al Objetivo 5 de la Orden de Cumplimiento.

- Zona de Mitigación de Reacciones Definida;
- Expansión de la Zona de Mitigación de Reacciones, si hubiera;
- Datos semanales de TMP; y
- Datos de LFG que incluyen, de forma enunciativa más no limitativa, datos de CH4, CO2, O2, Temperatura CO y de H2.

El Objetivo 5 además requiere "asentamiento con mapas de calor", pero como se analizó al principio de este informe y conforme a la correspondencia de la LEA con fecha 27 de noviembre y 3 de diciembre de 2024, este requerimiento se cumple con la presentación de Chiquita de sus mapas isopáquicos mensuales, presentados a la LEA, que se realizaron el 10 de agosto de 2026. Para practicidad de la LEA, el mapa isopáquico de julio de 2026 se incluye aquí como **Adjunto F**.

Los abajo firmantes son profesionales matriculados, el gerente de proyectos del sitio y un Gerente Regional, Vicepresidente de SCS Engineers.

Atentamente,

Rachelle Huber
Administrador del Proyecto
SCS Engineers

Arthur E Jones Jr.
Vicepresidente
SCS Engineers

Jenny Kim, P.E.
Gerente de
Proyectos de SCS
Engineers

Adjuntos:

Adjunto A - Análisis de Laboratorio y Datos de los Instrumentos de Extracción de LFG de los Pozos y de los Datos de las Temperaturas
Adjunto B – Temperaturas Pozo Abajo y Lista de Pozos para Monitoreo
Adjunto C – Punto 7 - Mapa de Ubicación de Pozos
Adjunto D - Datos de Cumplimiento con el Objetivo 5
Adjunto E - Informe del Área de Mitigación de Reacciones del 10 de Agosto de 2026
Adjunto F - Mapa Isopáquico de julio de 2026

Los Datos Electrónicos de los Resultados del Laboratorio y los datos de los Pozos de Extracción están en formato Excel, con PDFs adicionales para los datos de los pozos de gas.

cc: John Perkey, Chiquita Canyon
Kevin Green, Chiquita Canyon
William Haley, Chiquita Canyon
Dylan Smith, Chiquita Canyon
Sarah Phillips, Chiquita Canyon
Pat Sullivan, SCS Engineers
Liza Frías, Departamento de Salud Pública del Condado de Los Ángeles
Nichole Quick, M.D., Departamento de Salud Pública del Condado de Los Ángeles

Beverly Tway, LEA del Condado de Los Ángeles
Eric Morofuji, LEA del Condado de Los Ángeles
Renee Jensen, Asesor de LEA
Blaine McPhillips, Asesor Suplente Sénior del Condado
Emiko Thompson, Departamento de Obras Públicas del Condado de Los Ángeles
Alex Garcia, Departamento de Planificación Regional del Condado de Los Ángeles
Phillip Chen, Departamento de Planificación Regional del Condado de Los Ángeles
Steven Jareb, Departamento de Planificación Regional del Condado de Los Ángeles
Wes Mindermann, CalRecycle
Todd Thalhamer, CalRecycle
Emel Wadhwani, CalRecycle
Jeff Linberg, Junta de Recursos de Aire de California
Nancy Fletcher, Junta de Recursos de Aire de California
Jack Cheng, Consejo de Gestión de la Calidad del Aire de la Costa Sur
Larry Israel, Consejo de Gestión de la Calidad del Aire de la Costa Sur
Enrique Casas, Junta Regional de Control de Calidad del Agua de Los Ángeles
Joshua Wirtschafter, Agencia de Protección Ambiental de Estados Unidos
Laura Friedli, Agencia de Protección Ambiental de Estados Unidos
Tyler Holybee, Agencia de Protección Ambiental de Estados Unidos
Mark Anthony Relon, Agencia de Protección Ambiental de Estados Unidos
Gregory Schaffer, Departamento de Control de Sustancias Tóxicas
Natasha DiPietro, Departamento de Control de Sustancias Tóxicas
Gregory Gentile, Departamento de Control de Sustancias Tóxicas

Attachment A

Laboratory Analysis

And

LFG Extraction Well Instrument and Temperature Data

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175
TX Cert T104704450-14-6
EPA Methods TO14A, TO15
ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

July 9, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T070109-01/10

Enclosed are the results for sample(s) received 7/1/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags. Quadratic regression calibration was required for isopropanol, n-hexane, tetrahydrofuran, cyclohexane, MTBE, 2-hexanone, styrene, and 1,2,4-trichlorobenzene.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Zain Khan, Art Jones and Ali Ferrara on 7/8/26.

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐ No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐ No ☐
Other:				Level 4	☐	Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:
Bill to:
07FSAccountspayable@scsengineers.com
3900 Kilroy Airport Way, Suite 300
Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T070109-01	CV-2348	07/01/26	8:00AM	1L	Gas	N	X	X	X			
-02	CV-2347	07/01/26	8:05AM	1L	Gas	N	X	X	X			
-03	CV-2346	07/01/26	8:10AM	1L	Gas	N	X	X	X			
-04	CV-2345	07/01/26	8:15AM	1L	Gas	N	X	X	X			
-05	CV-2344	07/01/26	8:20AM	1L	Gas	N	X	X	X			
-06	CV-108-52	07/01/26	8:25AM	2-1L	Gas	N	X	X	X	X		
-07	CV-1532A	07/01/26	8:30AM	2-1L	Gas	N	X	X	X	X		
-08	CV-24143	07/01/26	8:35AM	2-1L	Gas	N	X	X	X	X		
-09	CV-2351	07/01/26	8:40AM	2-1L	Gas	N	X	X	X	X		
-10	CV-24140	07/01/26	8:50AM	2-1L	Gas	N	X	X	X	X		

AUTHORIZATION TO PERFORM WORK	COMPANY		DATE/TIME
SAMPLED BY	COMPANY SCS		DATE/TIME 7-1-26
RELINQUISHED BY	DATE/TIME 7-1-26 9:10a	RECEIVED BY	DATE/TIME 7-1-26 9:20am
RELINQUISHED BY	DATE/TIME 7-1-26 11:47	RECEIVED BY	DATE/TIME 7/1/26 1147
RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: H=HCl N=None / Container: B=Bag C=Can V=VOA O=Other *Rev. 03 - 5/7/09*

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/01/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T070109-06		T070109-07		T070109-08		T070109-09	
Client Sample I.D.:	CV-108-52		CV-1532A		CV-241423		CV-2351	
Date/Time Sampled:	7/1/26 8:25		7/1/26 8:30		7/1/26 8:35		7/1/26 8:40	
Date/Time Analyzed:	7/1/26 17:33		7/1/26 18:10		7/1/26 18:49		7/1/26 19:27	
QC Batch No.:	260701MS2A1		260701MS2A1		260701MS2A1		260701MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	500		1,000		1,000		100	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	500	ND	1,000	ND	1,000	ND	100
Chloromethane	ND	500	ND	1,000	ND	1,000	ND	100
1,2-Cl-1,1,2,2-F ethane (114)	ND	500	ND	1,000	ND	1,000	ND	100
Vinyl Chloride	ND	500	ND	1,000	ND	1,000	ND	100
Bromomethane	ND	500	ND	1,000	ND	1,000	ND	100
Chloroethane	ND	500	ND	1,000	ND	1,000	ND	100
Trichlorofluoromethane (11)	ND	500	ND	1,000	ND	1,000	ND	100
1,1-Dichloroethene	ND	500	ND	1,000	ND	1,000	ND	100
Carbon Disulfide	620	500	ND	1,000	ND	1,000	ND	100
1,1,2-Cl 1,2,2-F ethane (113)	ND	500	ND	1,000	ND	1,000	ND	100
Acetone	24,000	500	16,000	1,000	130,000 E	1,000	790	100
Methylene Chloride	ND	500	ND	1,000	ND	1,000	ND	100
t-1,2-Dichloroethene	ND	500	ND	1,000	ND	1,000	ND	100
1,1-Dichloroethane	ND	500	ND	1,000	ND	1,000	ND	100
Vinyl Acetate	ND	500	ND	1,000	ND	1,000	ND	100
c-1,2-Dichloroethene	ND	500	ND	1,000	ND	1,000	ND	100
2-Butanone	31,000	1,000	18,000	2,000	98,000	2,000	480	200
t-Butyl Methyl Ether (MTBE)	ND	500	ND	1,000	ND	1,000	ND	100
Chloroform	ND	500	ND	1,000	ND	1,000	ND	100
1,1,1-Trichloroethane	ND	500	ND	1,000	ND	1,000	ND	100
Carbon Tetrachloride	ND	500	ND	1,000	ND	1,000	ND	100
Benzene	18,000	500	8,300	1,000	29,000	1,000	210	100
1,2-Dichloroethane	ND	500	ND	1,000	ND	1,000	ND	100
Trichloroethene	ND	500	ND	1,000	ND	1,000	ND	100
1,2-Dichloropropane	ND	500	ND	1,000	ND	1,000	ND	100
Bromodichloromethane	ND	500	ND	1,000	ND	1,000	ND	100
c-1,3-Dichloropropene	ND	500	ND	1,000	ND	1,000	ND	100
4-Methyl-2-Pentanone	860	500	ND	1,000	1,000	1,000	ND	100
Toluene	1,500	500	ND	1,000	ND	1,000	ND	100
t-1,3-Dichloropropene	ND	500	ND	1,000	ND	1,000	ND	100
1,1,2-Trichloroethane	ND	500	ND	1,000	ND	1,000	ND	100
Tetrachloroethene	ND	500	ND	1,000	ND	1,000	ND	100
2-Hexanone	ND	500	ND	1,000	ND	1,000	ND	100
Dibromochloromethane	ND	500	ND	1,000	ND	1,000	ND	100

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/01/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T070109-06		T070109-07		T070109-08		T070109-09	
Client Sample I.D.:	CV-108-52		CV-1532A		CV-241423		CV-2351	
Date/Time Sampled:	7/1/26 8:25		7/1/26 8:30		7/1/26 8:35		7/1/26 8:40	
Date/Time Analyzed:	7/1/26 17:33		7/1/26 18:10		7/1/26 18:49		7/1/26 19:27	
QC Batch No.:	260701MS2A1		260701MS2A1		260701MS2A1		260701MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	500		1,000		1,000		100	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	500	ND	1,000	ND	1,000	ND	100
Chlorobenzene	ND	500	ND	1,000	ND	1,000	ND	100
Ethylbenzene	ND	500	ND	1,000	ND	1,000	ND	100
p,&m-Xylene	ND	500	ND	1,000	ND	1,000	ND	100
o-Xylene	ND	500	ND	1,000	ND	1,000	ND	100
Styrene	ND	500	ND	1,000	ND	1,000	ND	100
Bromoform	ND	500	ND	1,000	ND	1,000	ND	100
1,1,2,2-Tetrachloroethane	ND	500	ND	1,000	ND	1,000	ND	100
Benzyl Chloride	ND	500	ND	1,000	ND	1,000	ND	100
4-Ethyl Toluene	ND	500	ND	1,000	ND	1,000	ND	100
1,3,5-Trimethylbenzene	ND	500	ND	1,000	ND	1,000	ND	100
1,2,4-Trimethylbenzene	ND	500	ND	1,000	ND	1,000	ND	100
1,3-Dichlorobenzene	ND	500	ND	1,000	ND	1,000	ND	100
1,4-Dichlorobenzene	ND	500	ND	1,000	ND	1,000	ND	100
1,2-Dichlorobenzene	ND	500	ND	1,000	ND	1,000	ND	100
1,2,4-Trichlorobenzene	ND	500	ND	1,000	ND	1,000	ND	100
Hexachlorobutadiene	ND	500	ND	1,000	ND	1,000	ND	100
1,3-Butadiene	ND	2,500	ND	5,000	ND	5,000	ND	500
Isopropanol	23,000	2,500	8,700	5,000	12,000	5,000	ND	500
n-Hexane	ND	2,500	ND	5,000	ND	5,000	ND	500
Ethyl Acetate	ND	2,500	ND	5,000	5,100 Q	5,000	ND	500
Tetrahydrofuran	24,000	2,500	11,000	5,000	110,000	5,000	ND	500
Cyclohexane	ND	2,500	ND	5,000	ND	5,000	ND	500
Heptane	ND	2,500	ND	5,000	ND	5,000	ND	500
1,4-Dioxane	ND	2,500	ND	5,000	ND	5,000	ND	500

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited high recovery in the continuing calibration verification indicating possible high bias
E = Estimated. Analyte result exceeded the upper calibration range

Reviewed/Approved By: _____ Date 7/7/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/01/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T070109-10							
Client Sample I.D.:	CV-24140							
Date/Time Sampled:	7/1/26 8:50							
Date/Time Analyzed:	7/1/26 20:06							
QC Batch No.:	260701MS2A1							
Analyst Initials:	VM/GD							
Dilution Factor:	100							
ANALYTE	Result ppbv	RL ppbv						
Dichlorodifluoromethane (12)	ND	100						
Chloromethane	ND	100						
1,2-Cl-1,1,2,2-F ethane (114)	ND	100						
Vinyl Chloride	ND	100						
Bromomethane	ND	100						
Chloroethane	ND	100						
Trichlorofluoromethane (11)	ND	100						
1,1-Dichloroethene	ND	100						
Carbon Disulfide	ND	100						
1,1,2-Cl 1,2,2-F ethane (113)	ND	100						
Acetone	160	100						
Methylene Chloride	ND	100						
t-1,2-Dichloroethene	ND	100						
1,1-Dichloroethane	ND	100						
Vinyl Acetate	ND	100						
c-1,2-Dichloroethene	ND	100						
2-Butanone	ND	200						
t-Butyl Methyl Ether (MTBE)	ND	100						
Chloroform	ND	100						
1,1,1-Trichloroethane	ND	100						
Carbon Tetrachloride	ND	100						
Benzene	ND	100						
1,2-Dichloroethane	ND	100						
Trichloroethene	ND	100						
1,2-Dichloropropane	ND	100						
Bromodichloromethane	ND	100						
c-1,3-Dichloropropene	ND	100						
4-Methyl-2-Pentanone	ND	100						
Toluene	ND	100						
t-1,3-Dichloropropene	ND	100						
1,1,2-Trichloroethane	ND	100						
Tetrachloroethene	ND	100						
2-Hexanone	ND	100						
Dibromochloromethane	ND	100						

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/01/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T070109-10
Client Sample I.D.:	CV-24140
Date/Time Sampled:	7/1/26 8:50
Date/Time Analyzed:	7/1/26 20:06
QC Batch No.:	260701MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	100

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	100
Chlorobenzene	ND	100
Ethylbenzene	ND	100
p,&m-Xylene	ND	100
o-Xylene	ND	100
Styrene	ND	100
Bromoform	ND	100
1,1,2,2-Tetrachloroethane	ND	100
Benzyl Chloride	ND	100
4-Ethyl Toluene	ND	100
1,3,5-Trimethylbenzene	ND	100
1,2,4-Trimethylbenzene	ND	100
1,3-Dichlorobenzene	ND	100
1,4-Dichlorobenzene	ND	100
1,2-Dichlorobenzene	ND	100
1,2,4-Trichlorobenzene	ND	100
Hexachlorobutadiene	ND	100
1,3-Butadiene	ND	500
Isopropanol	ND	500
n-Hexane	ND	500
Ethyl Acetate	ND	500
Tetrahydrofuran	ND	500
Cyclohexane	ND	500
Heptane	ND	500
1,4-Dioxane	ND	500

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 7/7/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/01/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK
Client Sample I.D.:	--
Date/Time Sampled:	--
Date/Time Analyzed:	7/1/26 13:58
QC Batch No.:	260701MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	0.20
Chloromethane	ND	0.20
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20
Vinyl Chloride	ND	0.20
Bromomethane	ND	0.20
Chloroethane	ND	0.20
Trichlorofluoromethane (11)	ND	0.20
1,1-Dichloroethene	ND	0.20
Carbon Disulfide	ND	0.20
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20
Acetone	0.28	0.20
Methylene Chloride	ND	0.20
t-1,2-Dichloroethene	ND	0.20
1,1-Dichloroethane	ND	0.20
Vinyl Acetate	ND	0.20
c-1,2-Dichloroethene	ND	0.20
2-Butanone	ND	0.40
t-Butyl Methyl Ether (MTBE)	ND	0.20
Chloroform	ND	0.20
1,1,1-Trichloroethane	ND	0.20
Carbon Tetrachloride	ND	0.20
Benzene	ND	0.20
1,2-Dichloroethane	ND	0.20
Trichloroethene	ND	0.20
1,2-Dichloropropane	ND	0.20
Bromodichloromethane	ND	0.20
c-1,3-Dichloropropene	ND	0.20
4-Methyl-2-Pentanone	ND	0.20
Toluene	ND	0.20
t-1,3-Dichloropropene	ND	0.20
1,1,2-Trichloroethane	ND	0.20
Tetrachloroethene	ND	0.20
2-Hexanone	ND	0.20
Dibromochloromethane	ND	0.20

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/01/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK
Client Sample I.D.:	--
Date/Time Sampled:	--
Date/Time Analyzed:	7/1/26 13:58
QC Batch No.:	260701MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	0.20
Chlorobenzene	ND	0.20
Ethylbenzene	ND	0.20
p,&m-Xylene	ND	0.20
o-Xylene	ND	0.20
Styrene	ND	0.20
Bromoform	ND	0.20
1,1,2,2-Tetrachloroethane	ND	0.20
Benzyl Chloride	ND	0.20
4-Ethyl Toluene	ND	0.20
1,3,5-Trimethylbenzene	ND	0.20
1,2,4-Trimethylbenzene	ND	0.20
1,3-Dichlorobenzene	ND	0.20
1,4-Dichlorobenzene	ND	0.20
1,2-Dichlorobenzene	ND	0.20
1,2,4-Trichlorobenzene	ND	0.20
Hexachlorobutadiene	ND	0.20
1,3-Butadiene	ND	1.0
Isopropanol	ND	1.0
n-Hexane	ND	1.0
Ethyl Acetate	ND	1.0
Tetrahydrofuran	ND	1.0
Cyclohexane	ND	1.0
Heptane	ND	1.0
1,4-Dioxane	ND	1.0

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 7/7/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 260701MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	7/1/26 13:58			7/1/26 12:39		7/1/26 13:17					
Analyst Initials:	VM/GD			VM/GD		VM/GD					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	0.20	10	**10.1**	101	**10.5**	105	3.9	**70**	**130**	30
Methylene Chloride	ND	0.20	10	**11.0**	110	**11.4**	114	4.0	**70**	**130**	30
Trichloroethene	ND	0.20	10	**10.9**	109	**10.6**	106	2.9	**70**	**130**	30
Toluene	ND	0.20	10	**10.8**	108	**10.7**	107	0.3	**70**	**130**	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	**9.90**	99	**10.1**	101	1.8	**70**	**130**	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date:** 7/1/26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/01/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T070109-01		T070109-02		T070109-03		T070109-04	
Client Sample I.D.:	CV-2348		CV-2347		CV-2346		CV-2345	
Date/Time Sampled:	7/1/26 8:00		7/1/26 8:05		7/1/26 8:10		7/1/26 8:51	
Date/Time Analyzed:	7/1/26 16:16		7/1/26 16:30		7/1/26 16:45		7/1/26 16:59	
QC Batch No.:	260701GC8A2		260701GC8A2		260701GC8A2		260701GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	400	10	790	10	2,300	10	430	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7/7/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/01/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T070109-05		T070109-06		T070109-07		T070109-08	
Client Sample I.D.:	CV-2344		CV-108-52		CV-1532A		CV-241423	
Date/Time Sampled:	7/1/26 8:20		7/1/26 8:25		7/1/26 8:30		7/1/26 8:35	
Date/Time Analyzed:	7/1/26 17:14		7/1/26 17:28		7/1/26 17:43		7/1/26 17:57	
QC Batch No.:	260701GC8A2		260701GC8A2		260701GC8A2		260701GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	ND	10	ND	10	ND	10	230	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7/7/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/01/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T070109-09		T070109-10					
Client Sample I.D.:	CV-2351		CV-24140					
Date/Time Sampled:	7/1/26 8:40		7/1/26 8:50					
Date/Time Analyzed:	7/1/26 18:12		7/1/26 18:26					
QC Batch No.:	260701GC8A2		260701GC8A2					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv				
Carbon Monoxide	ND	10	ND	10				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7/7/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260701GC8A2
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	7/1/26 16:01			7/1/26 15:17		7/1/26 15:32					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,020	101	1,020	101	0.2	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 7/7/26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/01/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070109-01			T070109-02			T070109-03			T070109-04		
Client Sample I.D.:	CV-2348			CV-2347			CV-2346			CV-2345		
Date/Time Sampled:	7/1/26 8:00			7/1/26 8:05			7/1/26 8:10			7/1/26 8:51		
Date/Time Analyzed:	7/1/26 16:16			7/1/26 16:30			7/1/26 16:45			7/1/26 16:59		
QC Batch No.:	260701GC8A2			260701GC8A2			260701GC8A2			260701GC8A2		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	2.8	1.0	0.059	5.0	1.0	0.059	17	1.0	0.059	2.7	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 7/7/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/01/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070109-05			T070109-06			T070109-07			T070109-08		
Client Sample I.D.:	CV-2344			CV-108-52			CV-1532A			CV-241423		
Date/Time Sampled:	7/1/26 8:20			7/1/26 8:25			7/1/26 8:30			7/1/26 8:35		
Date/Time Analyzed:	7/1/26 17:14			7/1/26 17:28			7/1/26 17:43			7/1/26 17:57		
QC Batch No.:	260701GC8A2			260701GC8A2			260701GC8A2			260701GC8A2		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	ND	1.0	0.059	ND	1.0	0.059	ND	1.0	0.059	3.3	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 7/7/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/01/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070109-09			T070109-10								
Client Sample I.D.:	CV-2351			CV-24140								
Date/Time Sampled:	7/1/26 8:40			7/1/26 8:50								
Date/Time Analyzed:	7/1/26 18:12			7/1/26 18:26								
QC Batch No.:	260701GC8A2			260701GC8A2								
Analyst Initials:	KD			KD								
Dilution Factor:	1.0			1.0								
ANALYTE	**Result % v/v**	**RL % v/v**	**MDL % v/v**	**Result % v/v**	**RL % v/v**	**MDL % v/v**						
Hydrogen	0.060 J	1.0	0.059	ND	1.0	0.059						

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 7/7/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260701GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	7/1/26 16:01				7/1/26 15:17		7/1/26 15:32					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	4.20	84	4.23	85	0.8	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 7/7/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/01/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070109-01		T070109-02		T070109-03		T070109-04	
Client Sample I.D.:	CV-2348		CV-2347		CV-2346		CV-2345	
Date/Time Sampled:	7/1/26 8:00		7/1/26 8:05		7/1/26 8:10		7/1/26 8:51	
Date/Time Analyzed:	7/1/26 16:16		7/1/26 16:30		7/1/26 16:45		7/1/26 16:59	
QC Batch No.:	260701GC8A2		260701GC8A2		260701GC8A2		260701GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	48	0.010	57	0.010	74	0.010	57	0.010
Oxygen/Argon	1.8	0.50	1.4	0.50	1.2	0.50	4.3	0.50
Nitrogen	26	1.0	20	1.0	4.9	1.0	20	1.0
Methane	21	0.0010	16	0.0010	2.0	0.0010	15	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7/6/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/01/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070109-05		T070109-06		T070109-07		T070109-08	
Client Sample I.D.:	CV-2344		CV-108-52		CV-1532A		CV-241423	
Date/Time Sampled:	7/1/26 8:20		7/1/26 8:25		7/1/26 8:30		7/1/26 8:35	
Date/Time Analyzed:	7/1/26 17:14		7/1/26 17:28		7/1/26 17:43		7/1/26 17:57	
QC Batch No.:	260701GC8A2		260701GC8A2		260701GC8A2		260701GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	0.049	0.010	18	0.010	0.41	0.010	11	0.010
Oxygen/Argon	21	0.50	12	0.50	21	0.50	18	0.50
Nitrogen	79	1.0	45	1.0	78	1.0	68	1.0
Methane	0.0038	0.0010	25	0.0010	0.27	0.0010	0.32	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7/7/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/01/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070109-09		T070109-10					
Client Sample I.D.:	CV-2351		CV-24140					
Date/Time Sampled:	7/1/26 8:40		7/1/26 8:50					
Date/Time Analyzed:	7/1/26 18:12		7/1/26 18:26					
QC Batch No.:	260701GC8A2		260701GC8A2					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**				
Carbon Dioxide	0.064	0.010	0.059	0.010				
Oxygen/Argon	21	0.50	21	0.50				
Nitrogen	79	1.0	79	1.0				
Methane	0.0030	0.0010	0.0021	0.0010				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7/7/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260701GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	7/1/26 16:01			7/1/26 15:17		7/1/26 15:32					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	9.13	91	9.10	91	0.3	70	130	30
Oxygen/Argon	ND	0.50	15	15.3	102	15.4	102	0.1	70	130	30
Nitrogen	ND	1.0	70	73.2	105	73.2	105	0.0	70	130	30
Methane	ND	0.0010	0.10	0.0947	94	0.0947	94	0.1	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 7/1/26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

July 13, 2026

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175

TX Cert T104704450-14-6
EPA Methods TO14A, TO15

ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T070202-01/10

Enclosed are the results for sample(s) received 7/2/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags. Quadratic regression calibration was required for IPA, n-hexane, ethyl acetate, tetrahydrofuran, MTBE, 2-hexanone, styrene, and 1,2,4-trichlorobenzene.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Zain Khan, Art Jones and Ali Ferrara on 7/9/26

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF	
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:	
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐	No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐	No ☐
Other:				Level 4	☐	Chilled _____	deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING	
P.O. No.:	
Bill to:	
	[redacted]
	3900 Kilroy Airport Way, Suite 300
	Long Beach, CA 90806-6816

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T070202-01	CV-2352	07/02/26	7:50AM	1L	Gas	N	X	X	X			
-02	CV-24141	07/02/26	7:55AM	1L	Gas	N	X	X	X			
-03	CV-24101	07/02/26	8:00AM	2-1L	Gas	N	X	X	X	X		
-04	CV-24100	07/02/26	8:05AM	1L	Gas	N	X	X	X			
-05	CV-2001	07/02/26	8:10AM	2-1L	Gas	N	X	X	X	X		
-06	CV-24144	07/02/26	8:15AM	1L	Gas	N	X					
-07	CV-2349	07/02/26	8:20AM	1L	Gas	N	X	X	X			
-08	CV-24095	07/02/26	8:25AM	2-1L	Gas	N	X	X	X	X		
-09	CV-24142	07/02/26	8:30AM	2-1L	Gas	N	X	X	X	X		
-10	CV-24138	07/02/26	8:35AM	2-1L	Gas	N	X	X	X	X		

AUTHORIZATION TO PERFORM WORK	COMPANY SCS	DATE/TIME 7-2-26 9:17	
SAMPLED BY	COMPANY SCS	DATE/TIME 7-2-26 9:17	
RELINQUISHED BY	DATE/TIME 7-2-26 9:17	RECEIVED BY Ruben G	DATE/TIME 7.2.26 9:17
RELINQUISHED BY Ruben G	DATE/TIME 7.2.26 11:47	RECEIVED BY	DATE/TIME
RELINQUISHED BY	DATE/TIME	RECEIVED BY 7/2/26	DATE/TIME 1147

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/02/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T070202-03		T070202-05		T070202-08		T070202-09	
Client Sample I.D.:	CV-24101		CV-2001		CV-24095		CV-24142	
Date/Time Sampled:	7/2/26 8:00		7/2/26 8:10		7/2/26 8:25		7/2/26 8:30	
Date/Time Analyzed:	7/2/26 21:23		7/2/26 22:02		7/2/26 22:41		7/2/26 23:21	
QC Batch No.:	260702MS2A1		260702MS2A1		260702MS2A1		260702MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	20		40		10,000		5,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	20	ND	40	ND	10,000	ND	5,000
Chloromethane	ND	20	ND	40	ND	10,000	ND	5,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	20	ND	40	ND	10,000	ND	5,000
Vinyl Chloride	ND	20	ND	40	ND	10,000	ND	5,000
Bromomethane	ND	20	ND	40	ND	10,000	ND	5,000
Chloroethane	ND	20	ND	40	ND	10,000	ND	5,000
Trichlorofluoromethane (11)	ND	20	ND	40	ND	10,000	ND	5,000
1,1-Dichloroethene	ND	20	ND	40	ND	10,000	ND	5,000
Carbon Disulfide	29	20	110	40	12,000	10,000	ND	5,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	20	ND	40	ND	10,000	ND	5,000
Acetone	610	20	4,400 E	40	670,000	10,000	330,000	5,000
Methylene Chloride	ND	20	ND	40	ND	10,000	ND	5,000
t-1,2-Dichloroethene	ND	20	ND	40	ND	10,000	ND	5,000
1,1-Dichloroethane	ND	20	ND	40	ND	10,000	ND	5,000
Vinyl Acetate	ND	20	89	40	ND	10,000	ND	5,000
c-1,2-Dichloroethene	ND	20	ND	40	ND	10,000	ND	5,000
2-Butanone	790 Q	40	6,700 Q	80	490,000 Q	20,000	230,000 Q	10,000
t-Butyl Methyl Ether (MTBE)	ND	20	270	40	ND	10,000	ND	5,000
Chloroform	ND	20	ND	40	ND	10,000	ND	5,000
1,1,1-Trichloroethane	ND	20	ND	40	ND	10,000	ND	5,000
Carbon Tetrachloride	ND	20	ND	40	ND	10,000	ND	5,000
Benzene	190	20	8,100	40	180,000	10,000	60,000	5,000
1,2-Dichloroethane	ND	20	ND	40	ND	10,000	ND	5,000
Trichloroethene	ND	20	ND	40	ND	10,000	ND	5,000
1,2-Dichloropropane	ND	20	ND	40	ND	10,000	ND	5,000
Bromodichloromethane	ND	20	ND	40	ND	10,000	ND	5,000
c-1,3-Dichloropropene	ND	20	ND	40	ND	10,000	ND	5,000
4-Methyl-2-Pentanone	ND	20	300	40	ND	10,000	ND	5,000
Toluene	22	20	320	40	ND	10,000	ND	5,000
t-1,3-Dichloropropene	ND	20	ND	40	ND	10,000	ND	5,000
1,1,2-Trichloroethane	ND	20	ND	40	ND	10,000	ND	5,000
Tetrachloroethene	ND	20	ND	40	ND	10,000	ND	5,000
2-Hexanone	ND	20	40	40	ND	10,000	ND	5,000
Dibromochloromethane	ND	20	ND	40	ND	10,000	ND	5,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/02/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T070202-03		T070202-05		T070202-08		T070202-09	
Client Sample I.D.:	CV-24101		CV-2001		CV-24095		CV-24142	
Date/Time Sampled:	7/2/26 8:00		7/2/26 8:10		7/2/26 8:25		7/2/26 8:30	
Date/Time Analyzed:	7/2/26 21:23		7/2/26 22:02		7/2/26 22:41		7/2/26 23:21	
QC Batch No.:	260702MS2A1		260702MS2A1		260702MS2A1		260702MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	20		40		10,000		5,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	20	ND	40	ND	10,000	ND	5,000
Chlorobenzene	ND	20	ND	40	ND	10,000	ND	5,000
Ethylbenzene	ND	20	ND	40	ND	10,000	ND	5,000
p,&m-Xylene	ND	20	ND	40	ND	10,000	ND	5,000
o-Xylene	ND	20	ND	40	ND	10,000	ND	5,000
Styrene	ND	20	ND	40	ND	10,000	ND	5,000
Bromoform	ND	20	ND	40	ND	10,000	ND	5,000
1,1,2,2-Tetrachloroethane	ND	20	ND	40	ND	10,000	ND	5,000
Benzyl Chloride	ND	20	ND	40	ND	10,000	ND	5,000
4-Ethyl Toluene	ND	20	ND	40	ND	10,000	ND	5,000
1,3,5-Trimethylbenzene	ND	20	ND	40	ND	10,000	ND	5,000
1,2,4-Trimethylbenzene	ND	20	ND	40	ND	10,000	ND	5,000
1,3-Dichlorobenzene	ND	20	ND	40	ND	10,000	ND	5,000
1,4-Dichlorobenzene	ND	20	ND	40	ND	10,000	ND	5,000
1,2-Dichlorobenzene	ND	20	ND	40	ND	10,000	ND	5,000
1,2,4-Trichlorobenzene	ND	20	ND	40	ND	10,000	ND	5,000
Hexachlorobutadiene	ND	20	ND	40	ND	10,000	ND	5,000
1,3-Butadiene	120	100	2,000	200	ND	50,000	ND	25,000
Isopropanol	470	100	12,000 E	200	130,000	50,000	110,000	25,000
n-Hexane	ND	100	680	200	ND	50,000	ND	25,000
Ethyl Acetate	ND	100	1,700 Q	200	54,000 Q	50,000	ND	25,000
Tetrahydrofuran	340	100	7,900	200	390,000	50,000	190,000	25,000
Cyclohexane	ND	100	290 Q	200	ND	50,000	ND	25,000
Heptane	ND	100	670	200	ND	50,000	ND	25,000
1,4-Dioxane	ND	100	ND	200	ND	50,000	ND	25,000

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited high recovery in the continuing calibration verification indicating possible high bias
E = Estimated. Analyte result exceeds upper calibration range

Reviewed/Approved By: _____ Date 7/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/02/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T070202-10							
Client Sample I.D.:	CV-24138							
Date/Time Sampled:	7/2/26 8:35							
Date/Time Analyzed:	7/3/26 0:00							
QC Batch No.:	260702MS2A1							
Analyst Initials:	VM/GD							
Dilution Factor:	5,000							
ANALYTE	Result ppbv	RL ppbv						
Dichlorodifluoromethane (12)	ND	5,000						
Chloromethane	ND	5,000						
1,2-Cl-1,1,2,2-F ethane (114)	ND	5,000						
Vinyl Chloride	ND	5,000						
Bromomethane	ND	5,000						
Chloroethane	ND	5,000						
Trichlorofluoromethane (11)	ND	5,000						
1,1-Dichloroethene	ND	5,000						
Carbon Disulfide	ND	5,000						
1,1,2-Cl 1,2,2-F ethane (113)	ND	5,000						
Acetone	120,000	5,000						
Methylene Chloride	ND	5,000						
t-1,2-Dichloroethene	ND	5,000						
1,1-Dichloroethane	ND	5,000						
Vinyl Acetate	ND	5,000						
c-1,2-Dichloroethene	ND	5,000						
2-Butanone	89,000 Q	10,000						
t-Butyl Methyl Ether (MTBE)	ND	5,000						
Chloroform	ND	5,000						
1,1,1-Trichloroethane	ND	5,000						
Carbon Tetrachloride	ND	5,000						
Benzene	13,000	5,000						
1,2-Dichloroethane	ND	5,000						
Trichloroethene	ND	5,000						
1,2-Dichloropropane	ND	5,000						
Bromodichloromethane	ND	5,000						
c-1,3-Dichloropropene	ND	5,000						
4-Methyl-2-Pentanone	ND	5,000						
Toluene	ND	5,000						
t-1,3-Dichloropropene	ND	5,000						
1,1,2-Trichloroethane	ND	5,000						
Tetrachloroethene	ND	5,000						
2-Hexanone	ND	5,000						
Dibromochloromethane	ND	5,000						

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/02/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T070202-10							
Client Sample I.D.:	CV-24138							
Date/Time Sampled:	7/2/26 8:35							
Date/Time Analyzed:	7/3/26 0:00							
QC Batch No.:	260702MS2A1							
Analyst Initials:	VM/GD							
Dilution Factor:	5,000							
ANALYTE	Result ppbv	RL ppbv						
1,2-Dibromoethane	ND	5,000						
Chlorobenzene	ND	5,000						
Ethylbenzene	ND	5,000						
p,&m-Xylene	ND	5,000						
o-Xylene	ND	5,000						
Styrene	ND	5,000						
Bromoform	ND	5,000						
1,1,2,2-Tetrachloroethane	ND	5,000						
Benzyl Chloride	ND	5,000						
4-Ethyl Toluene	ND	5,000						
1,3,5-Trimethylbenzene	ND	5,000						
1,2,4-Trimethylbenzene	ND	5,000						
1,3-Dichlorobenzene	ND	5,000						
1,4-Dichlorobenzene	ND	5,000						
1,2-Dichlorobenzene	ND	5,000						
1,2,4-Trichlorobenzene	ND	5,000						
Hexachlorobutadiene	ND	5,000						
1,3-Butadiene	ND	25,000						
Isopropanol	74,000	25,000						
n-Hexane	ND	25,000						
Ethyl Acetate	ND	25,000						
Tetrahydrofuran	52,000	25,000						
Cyclohexane	ND	25,000						
Heptane	ND	25,000						
1,4-Dioxane	ND	25,000						

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited high recovery in the continuing calibration verification indicating possible high bias

Reviewed/Approved By: _____ Date 7/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/02/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK							
Client Sample I.D.:	-							
Date/Time Sampled:	-							
Date/Time Analyzed:	7/2/26 8:30							
QC Batch No.:	260702MS2A1							
Analyst Initials:	VM/GD							
Dilution Factor:	0.20							

ANALYTE	Result ppbv	RL ppbv						
Dichlorodifluoromethane (12)	ND	0.20						
Chloromethane	ND	0.20						
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20						
Vinyl Chloride	ND	0.20						
Bromomethane	ND	0.20						
Chloroethane	ND	0.20						
Trichlorofluoromethane (11)	ND	0.20						
1,1-Dichloroethene	ND	0.20						
Carbon Disulfide	ND	0.20						
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20						
Acetone	ND	0.20						
Methylene Chloride	ND	0.20						
t-1,2-Dichloroethene	ND	0.20						
1,1-Dichloroethane	ND	0.20						
Vinyl Acetate	ND	0.20						
c-1,2-Dichloroethene	ND	0.20						
2-Butanone	ND	0.40						
t-Butyl Methyl Ether (MTBE)	ND	0.20						
Chloroform	ND	0.20						
1,1,1-Trichloroethane	ND	0.20						
Carbon Tetrachloride	ND	0.20						
Benzene	ND	0.20						
1,2-Dichloroethane	ND	0.20						
Trichloroethene	ND	0.20						
1,2-Dichloropropane	ND	0.20						
Bromodichloromethane	ND	0.20						
c-1,3-Dichloropropene	ND	0.20						
4-Methyl-2-Pentanone	ND	0.20						
Toluene	ND	0.20						
t-1,3-Dichloropropene	ND	0.20						
1,1,2-Trichloroethane	ND	0.20						
Tetrachloroethene	ND	0.20						
2-Hexanone	ND	0.20						
Dibromochloromethane	ND	0.20						

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/02/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK							
Client Sample I.D.:	-							
Date/Time Sampled:	-							
Date/Time Analyzed:	7/2/26 8:30							
QC Batch No.:	260702MS2A1							
Analyst Initials:	VM/GD							
Dilution Factor:	0.20							

ANALYTE	Result ppbv	RL ppbv						
1,2-Dibromoethane	ND	0.20						
Chlorobenzene	ND	0.20						
Ethylbenzene	ND	0.20						
p,&m-Xylene	ND	0.20						
o-Xylene	ND	0.20						
Styrene	ND	0.20						
Bromoform	ND	0.20						
1,1,2,2-Tetrachloroethane	ND	0.20						
Benzyl Chloride	ND	0.20						
4-Ethyl Toluene	ND	0.20						
1,3,5-Trimethylbenzene	ND	0.20						
1,2,4-Trimethylbenzene	ND	0.20						
1,3-Dichlorobenzene	ND	0.20						
1,4-Dichlorobenzene	ND	0.20						
1,2-Dichlorobenzene	ND	0.20						
1,2,4-Trichlorobenzene	ND	0.20						
Hexachlorobutadiene	ND	0.20						
1,3-Butadiene	ND	1.0						
Isopropanol	ND	1.0						
n-Hexane	ND	1.0						
Ethyl Acetate	ND	1.0						
Tetrahydrofuran	ND	1.0						
Cyclohexane	ND	1.0						
Heptane	ND	1.0						
1,4-Dioxane	ND	1.0						

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 7/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/02/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T070202-01		T070202-02		T070202-03		T070202-04	
Client Sample I.D.:	CV-2352		CV-24141		CV-24101		CV-24100	
Date/Time Sampled:	7/2/26 7:50		7/2/26 7:55		7/2/26 8:00		7/2/26 8:05	
Date/Time Analyzed:	7/2/26 14:24		7/2/26 14:38		7/2/26 14:53		7/2/26 15:07	
QC Batch No.:	260702GC8A2		260702GC8A2		260702GC8A2		260702GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	ND	10	ND	10	ND	10	12	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 7/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/02/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T070202-05		T070202-07		T070202-08		T070202-09	
Client Sample I.D.:	CV-2001		CV-2349		CV-24095		CV-24142	
Date/Time Sampled:	7/2/26 8:10		7/2/26 8:20		7/2/26 8:25		7/2/26 8:30	
Date/Time Analyzed:	7/2/26 15:22		7/2/26 15:51		7/2/26 16:05		7/2/26 16:20	
QC Batch No.:	260702GC8A2		260702GC8A2		260702GC8A2		260702GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	300	10	1,200	10	1,700	10	570	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 7/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/02/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T070202-10							
Client Sample I.D.:	CV-24138							
Date/Time Sampled:	7/2/26 8:35							
Date/Time Analyzed:	7/2/26 16:34							
QC Batch No.:	260702GC8A2							
Analyst Initials:	KD							
Dilution Factor:	1.0							
ANALYTE	Result ppmv	RL ppmv						
Carbon Monoxide	ND	10						

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260702GC8A2
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	7/2/26 14:09			7/2/26 13:11		7/2/26 13:26					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,070	106	1,070	105	0.7	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 7/9/26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/02/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070202-01			T070202-02			T070202-03			T070202-04		
Client Sample I.D.:	CV-2352			CV-24141			CV-24101			CV-24100		
Date/Time Sampled:	7/2/26 7:50			7/2/26 7:55			7/2/26 8:00			7/2/26 8:05		
Date/Time Analyzed:	7/2/26 14:24			7/2/26 14:38			7/2/26 14:53			7/2/26 15:07		
QC Batch No.:	260702GC8A2			260702GC8A2			260702GC8A2			260702GC8A2		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	ND	1.0	0.059	0.082 J	1.0	0.059	ND	1.0	0.059	0.33 J	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 7/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/02/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070202-05			T070202-07			T070202-08			T070202-09		
Client Sample I.D.:	CV-2001			CV-2349			CV-24095			CV-24142		
Date/Time Sampled:	7/2/26 8:10			7/2/26 8:20			7/2/26 8:25			7/2/26 8:30		
Date/Time Analyzed:	7/2/26 15:22			7/2/26 15:51			7/2/26 16:05			7/2/26 16:20		
QC Batch No.:	260702GC8A2			260702GC8A2			260702GC8A2			260702GC8A2		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	2.4	1.0	0.059	8.5	1.0	0.059	12	1.0	0.059	8.8	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 7/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/02/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070202-10		
Client Sample I.D.:	CV-24138		
Date/Time Sampled:	7/2/26 8:35		
Date/Time Analyzed:	7/2/26 16:34		
QC Batch No.:	260702GC8A2		
Analyst Initials:	KD		
Dilution Factor:	1.0		

ANALYTE	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	0.24 J	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 7/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260702GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	7/2/26 14:09				7/2/26 13:11		7/2/26 13:26					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	5.72	115	5.69	114	0.7	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 7/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/02/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070202-01		T070202-02		T070202-03		T070202-04	
Client Sample I.D.:	CV-2352		CV-24141		CV-24101		CV-24100	
Date/Time Sampled:	7/2/26 7:50		7/2/26 7:55		7/2/26 8:00		7/2/26 8:05	
Date/Time Analyzed:	7/2/26 14:24		7/2/26 14:38		7/2/26 14:53		7/2/26 15:07	
QC Batch No.:	260702GC8A2		260702GC8A2		260702GC8A2		260702GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	0.057	0.010	0.064	0.010	3.2	0.010	20	0.010
Oxygen/Argon	21	0.50	21	0.50	20	0.50	16	0.50
Nitrogen	79	1.0	79	1.0	74	1.0	58	1.0
Methane	0.0031	0.0010	0.0045	0.0010	3.0	0.0010	5.4	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 7/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/02/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070202-05		T070202-06		T070202-07		T070202-08	
Client Sample I.D.:	CV-2001		CV-24144		CV-2349		CV-24095	
Date/Time Sampled:	7/2/26 8:10		7/2/26 8:15		7/2/26 8:20		7/2/26 8:25	
Date/Time Analyzed:	7/2/26 15:22		7/2/26 15:36		7/2/26 15:51		7/2/26 16:05	
QC Batch No.:	260702GC8A2		260702GC8A2		260702GC8A2		260702GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	18	0.010	0.051	0.010	33	0.010	52	0.010
Oxygen/Argon	16	0.50	21	0.50	12	0.50	6.9	0.50
Nitrogen	61	1.0	79	1.0	45	1.0	26	1.0
Methane	2.1	0.0010	0.0055	0.0010	0.77	0.0010	2.2	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/02/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070202-09		T070202-10					
Client Sample I.D.:	CV-24142		CV-24138					
Date/Time Sampled:	7/2/26 8:30		7/2/26 8:35					
Date/Time Analyzed:	7/2/26 16:20		7/2/26 16:34					
QC Batch No.:	260702GC8A2		260702GC8A2					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**				
Carbon Dioxide	31	0.010	0.83	0.010				
Oxygen/Argon	12	0.50	21	0.50				
Nitrogen	45	1.0	78	1.0				
Methane	2.5	0.0010	0.0083	0.0010				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260702GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	7/2/26 14:09			7/2/26 13:11		7/2/26 13:26					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	9.89	99	9.88	99	0.1	70	130	30
Oxygen/Argon	ND	0.50	15	14.8	99	14.8	99	0.1	70	130	30
Nitrogen	ND	1.0	70	72.1	103	72.2	103	0.2	70	130	30
Methane	ND	0.0010	0.10	0.0981	97	0.0976	97	0.5	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 7/9/26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175
TX Cert T104704450-14-6
EPA Methods TO14A, TO15
ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

July 14, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T070609-01/10

Enclosed are the results for sample(s) received 7/6/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Zain Khan, Art Jones and Ali Ferrara on 7/13/26

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐ No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐ No ☐
Other:				Level 4	☐	Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:	
Bill to:	
	07FSAccountspayable@scsengineers.com
	3900 Kilroy Airport Way, Suite 300
	Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T070609-01	CV-2301	07/06/26	7:20AM	2-1L	Gas	N	X	X	X	X		
-02	CV-2302	07/06/26	7:25AM	2-1L	Gas	N	X	X	X	X		
-03	CV-2303	07/06/26	7:35AM	2-1L	Gas	N	X	X	X	X		
-04	CV-2312	07/06/26	7:45AM	2-1L	Gas	N	X	X	X	X		
-05	CV-2315	07/06/26	8:00AM	2-1L	Gas	N	X	X	X	X		
-06	CV-24064	07/06/26	8:10AM	1L	Gas	N	X	X	X			
-07	CV-24063	07/06/26	8:15AM	1L	Gas	N	X	X	X			
-08	CV-24062	07/06/26	8:20AM	1L	Gas	N	X	X	X			
-09	CV-24069	07/06/26	8:30AM	1L	Gas	N	X	X	X			
-10	CV-24070	7/6/2026	8:35AM	1L	Gas	N	X	X	X			

AUTHORIZATION TO PERFORM WORK		COMPANY: SCS	DATE/TIME: 7-6-26 9:40
SAMPLED BY		COMPANY: SCS	DATE/TIME: 7-6-26 9:40
RELINQUISHED BY	DATE/TIME: 7-6-26 9:40	RECEIVED BY: Ruben G	DATE/TIME: 7-6-26 9:41 AM
RELINQUISHED BY: Ruben G	DATE/TIME: 7-6-26 12:00	RECEIVED BY	DATE/TIME: 7/6/26 1200
RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/06/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T070609-01		T070609-02		T070609-03		T070609-04	
Client Sample I.D.:	CV-2301		CV-2302		CV-2303		CV-2312	
Date/Time Sampled:	7/6/26 7:20		7/6/26 7:25		7/6/26 7:35		7/6/26 7:45	
Date/Time Analyzed:	7/6/26 22:46		7/6/26 23:26		7/7/26 0:07		7/7/26 0:48	
QC Batch No.:	260706MS2A1		260706MS2A1		260706MS2A1		260706MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	10		10		10		100	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	10	ND	10	ND	10	ND	100
Chloromethane	ND	10	ND	10	ND	10	730	100
1,2-Cl-1,1,2,2-F ethane (114)	ND	10	ND	10	ND	10	ND	100
Vinyl Chloride	ND	10	ND	10	ND	10	ND	100
Bromomethane	ND	10	ND	10	ND	10	ND	100
Chloroethane	ND	10	ND	10	ND	10	ND	100
Trichlorofluoromethane (11)	ND	10	ND	10	ND	10	ND	100
1,1-Dichloroethene	ND	10	ND	10	ND	10	ND	100
Carbon Disulfide	ND	10	18	10	ND	10	740	100
1,1,2-Cl 1,2,2-F ethane (113)	ND	10	ND	10	ND	10	ND	100
Acetone	57	10	48	10	32	10	32,000 E	100
Methylene Chloride	ND	10	ND	10	ND	10	ND	100
t-1,2-Dichloroethene	ND	10	ND	10	ND	10	ND	100
1,1-Dichloroethane	ND	10	ND	10	ND	10	ND	100
Vinyl Acetate	ND	10	ND	10	ND	10	ND	100
c-1,2-Dichloroethene	ND	10	ND	10	ND	10	ND	100
2-Butanone	59	20	51	20	25	20	49,000 E	200
t-Butyl Methyl Ether (MTBE)	ND	10	ND	10	ND	10	230	100
Chloroform	ND	10	ND	10	ND	10	ND	100
1,1,1-Trichloroethane	ND	10	ND	10	ND	10	ND	100
Carbon Tetrachloride	ND	10	ND	10	ND	10	ND	100
Benzene	24	10	19	10	12	10	14,000	100
1,2-Dichloroethane	ND	10	ND	10	ND	10	ND	100
Trichloroethene	ND	10	ND	10	ND	10	ND	100
1,2-Dichloropropane	ND	10	ND	10	ND	10	ND	100
Bromodichloromethane	ND	10	ND	10	ND	10	ND	100
c-1,3-Dichloropropene	ND	10	ND	10	ND	10	ND	100
4-Methyl-2-Pentanone	ND	10	ND	10	ND	10	530	100
Toluene	10	10	ND	10	ND	10	430	100
t-1,3-Dichloropropene	ND	10	ND	10	ND	10	ND	100
1,1,2-Trichloroethane	ND	10	ND	10	ND	10	ND	100
Tetrachloroethene	ND	10	ND	10	ND	10	ND	100
2-Hexanone	ND	10	ND	10	ND	10	ND	100
Dibromochloromethane	ND	10	ND	10	ND	10	ND	100

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/06/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T070609-01		T070609-02		T070609-03		T070609-04	
Client Sample I.D.:	CV-2301		CV-2302		CV-2303		CV-2312	
Date/Time Sampled:	7/6/26 7:20		7/6/26 7:25		7/6/26 7:35		7/6/26 7:45	
Date/Time Analyzed:	7/6/26 22:46		7/6/26 23:26		7/7/26 0:07		7/7/26 0:48	
QC Batch No.:	260706MS2A1		260706MS2A1		260706MS2A1		260706MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	10		10		10		100	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	10	ND	10	ND	10	ND	100
Chlorobenzene	ND	10	ND	10	ND	10	ND	100
Ethylbenzene	ND	10	ND	10	ND	10	ND	100
p,&m-Xylene	ND	10	ND	10	ND	10	ND	100
o-Xylene	ND	10	ND	10	ND	10	ND	100
Styrene	ND	10	ND	10	ND	10	ND	100
Bromoform	ND	10	ND	10	ND	10	ND	100
1,1,2,2-Tetrachloroethane	ND	10	ND	10	ND	10	ND	100
Benzyl Chloride	ND	10	ND	10	ND	10	ND	100
4-Ethyl Toluene	ND	10	ND	10	ND	10	ND	100
1,3,5-Trimethylbenzene	ND	10	ND	10	ND	10	ND	100
1,2,4-Trimethylbenzene	ND	10	ND	10	ND	10	ND	100
1,3-Dichlorobenzene	ND	10	ND	10	ND	10	ND	100
1,4-Dichlorobenzene	ND	10	ND	10	ND	10	ND	100
1,2-Dichlorobenzene	ND	10	ND	10	ND	10	ND	100
1,2,4-Trichlorobenzene	ND	10	ND	10	ND	10	ND	100
Hexachlorobutadiene	ND	10	ND	10	ND	10	ND	100
1,3-Butadiene	ND	50	ND	50	ND	50	1,500	500
Isopropanol	ND	50	ND	50	ND	50	29,000 E	500
n-Hexane	ND	50	ND	50	ND	50	640	500
Ethyl Acetate	ND	50	ND	50	ND	50	3,600	500
Tetrahydrofuran	ND	50	ND	50	ND	50	ND	500
Cyclohexane	ND	50	ND	50	ND	50	ND	500
Heptane	ND	50	ND	50	ND	50	1,200	500
1,4-Dioxane	ND	50	ND	50	ND	50	500	500

RL = Reporting Limit
ND = Not Detected (below RL)
E = Estimated. Analyte result exceeds upper calibration range

Reviewed/Approved By: _____ Date 7/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/06/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T070609-05
Client Sample I.D.:	CV-2315
Date/Time Sampled:	7/6/26 8:00
Date/Time Analyzed:	7/7/26 1:28
QC Batch No.:	260706MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	1,000

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	1,000
Chloromethane	1,100	1,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	1,000
Vinyl Chloride	ND	1,000
Bromomethane	ND	1,000
Chloroethane	ND	1,000
Trichlorofluoromethane (11)	ND	1,000
1,1-Dichloroethene	ND	1,000
Carbon Disulfide	2,000	1,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	1,000
Acetone	130,000 E	1,000
Methylene Chloride	ND	1,000
t-1,2-Dichloroethene	ND	1,000
1,1-Dichloroethane	ND	1,000
Vinyl Acetate	ND	1,000
c-1,2-Dichloroethene	ND	1,000
2-Butanone	100,000	2,000
t-Butyl Methyl Ether (MTBE)	ND	1,000
Chloroform	ND	1,000
1,1,1-Trichloroethane	ND	1,000
Carbon Tetrachloride	ND	1,000
Benzene	34,000	1,000
1,2-Dichloroethane	ND	1,000
Trichloroethene	ND	1,000
1,2-Dichloropropane	ND	1,000
Bromodichloromethane	ND	1,000
c-1,3-Dichloropropene	ND	1,000
4-Methyl-2-Pentanone	ND	1,000
Toluene	ND	1,000
t-1,3-Dichloropropene	ND	1,000
1,1,2-Trichloroethane	ND	1,000
Tetrachloroethene	ND	1,000
2-Hexanone	ND	1,000
Dibromochloromethane	ND	1,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/06/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T070609-05
Client Sample I.D.:	CV-2315
Date/Time Sampled:	7/6/26 8:00
Date/Time Analyzed:	7/7/26 1:28
QC Batch No.:	260706MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	1,000

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	1,000
Chlorobenzene	ND	1,000
Ethylbenzene	ND	1,000
p,&m-Xylene	ND	1,000
o-Xylene	ND	1,000
Styrene	ND	1,000
Bromoform	ND	1,000
1,1,2,2-Tetrachloroethane	ND	1,000
Benzyl Chloride	ND	1,000
4-Ethyl Toluene	ND	1,000
1,3,5-Trimethylbenzene	ND	1,000
1,2,4-Trimethylbenzene	ND	1,000
1,3-Dichlorobenzene	ND	1,000
1,4-Dichlorobenzene	ND	1,000
1,2-Dichlorobenzene	ND	1,000
1,2,4-Trichlorobenzene	ND	1,000
Hexachlorobutadiene	ND	1,000
1,3-Butadiene	ND	5,000
Isopropanol	35,000	5,000
n-Hexane	ND	5,000
Ethyl Acetate	7,600	5,000
Tetrahydrofuran	120,000	5,000
Cyclohexane	ND	5,000
Heptane	ND	5,000
1,4-Dioxane	ND	5,000

RL = Reporting Limit
ND = Not Detected (below RL)
E = Estimated. Analyte result exceeds upper calibration range

Reviewed/Approved By: _____ Date 7/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/06/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK							
Client Sample I.D.:	-							
Date/Time Sampled:	-							
Date/Time Analyzed:	7/6/26 14:47							
QC Batch No.:	260706MS2A1							
Analyst Initials:	VM							
Dilution Factor:	0.20							

ANALYTE	Result ppbv	RL ppbv						
Dichlorodifluoromethane (12)	ND	0.20						
Chloromethane	ND	0.20						
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20						
Vinyl Chloride	ND	0.20						
Bromomethane	ND	0.20						
Chloroethane	ND	0.20						
Trichlorofluoromethane (11)	ND	0.20						
1,1-Dichloroethene	ND	0.20						
Carbon Disulfide	ND	0.20						
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20						
Acetone	0.35	0.20						
Methylene Chloride	ND	0.20						
t-1,2-Dichloroethene	ND	0.20						
1,1-Dichloroethane	ND	0.20						
Vinyl Acetate	ND	0.20						
c-1,2-Dichloroethene	ND	0.20						
2-Butanone	ND	0.40						
t-Butyl Methyl Ether (MTBE)	ND	0.20						
Chloroform	ND	0.20						
1,1,1-Trichloroethane	ND	0.20						
Carbon Tetrachloride	ND	0.20						
Benzene	ND	0.20						
1,2-Dichloroethane	ND	0.20						
Trichloroethene	ND	0.20						
1,2-Dichloropropane	ND	0.20						
Bromodichloromethane	ND	0.20						
c-1,3-Dichloropropene	ND	0.20						
4-Methyl-2-Pentanone	ND	0.20						
Toluene	ND	0.20						
t-1,3-Dichloropropene	ND	0.20						
1,1,2-Trichloroethane	ND	0.20						
Tetrachloroethene	ND	0.20						
2-Hexanone	ND	0.20						
Dibromochloromethane	ND	0.20						

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/06/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK
Client Sample I.D.:	-
Date/Time Sampled:	-
Date/Time Analyzed:	7/6/26 14:47
QC Batch No.:	260706MS2A1
Analyst Initials:	VM
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	0.20
Chlorobenzene	ND	0.20
Ethylbenzene	ND	0.20
p,&m-Xylene	ND	0.20
o-Xylene	ND	0.20
Styrene	ND	0.20
Bromoform	ND	0.20
1,1,2,2-Tetrachloroethane	ND	0.20
Benzyl Chloride	ND	0.20
4-Ethyl Toluene	ND	0.20
1,3,5-Trimethylbenzene	ND	0.20
1,2,4-Trimethylbenzene	ND	0.20
1,3-Dichlorobenzene	ND	0.20
1,4-Dichlorobenzene	ND	0.20
1,2-Dichlorobenzene	ND	0.20
1,2,4-Trichlorobenzene	ND	0.20
Hexachlorobutadiene	ND	0.20
1,3-Butadiene	ND	1.0
Isopropanol	ND	1.0
n-Hexane	ND	1.0
Ethyl Acetate	ND	1.0
Tetrahydrofuran	ND	1.0
Cyclohexane	ND	1.0
Heptane	ND	1.0
1,4-Dioxane	ND	1.0

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 7/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 260706MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	7/6/26 14:47			7/6/26 13:30		7/6/26 14:09					
Analyst Initials:	VM/GD			VM/GD		VM/GD					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	0.20	10	9.06	91	9.23	92	1.9	70	130	30
Methylene Chloride	ND	0.20	10	10.2	102	10.0	100	1.4	70	130	30
Trichloroethene	ND	0.20	10	9.63	96	9.39	94	2.5	70	130	30
Toluene	ND	0.20	10	9.47	95	9.35	94	1.3	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	9.13	91	9.20	92	0.7	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date:** 7/9/26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/06/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T070609-01		T070609-02		T070609-03		T070609-04	
Client Sample I.D.:	CV-2301		CV-2302		CV-2303		CV-2312	
Date/Time Sampled:	7/6/26 7:20		7/6/26 7:25		7/6/26 7:35		7/6/26 7:45	
Date/Time Analyzed:	7/6/26 17:23		7/6/26 17:37		7/6/26 17:52		7/6/26 18:06	
QC Batch No.:	260706GC8A1		260706GC8A1		260706GC8A1		260706GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	ND	10	ND	10	ND	10	520	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/06/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T070609-05		T070609-06		T070609-07		T070609-08	
Client Sample I.D.:	CV-2315		CV-24064		CV-24063		CV-24062	
Date/Time Sampled:	7/6/26 8:00		7/6/26 8:10		7/6/26 8:15		7/6/26 8:20	
Date/Time Analyzed:	7/6/26 18:20		7/6/26 18:35		7/6/26 18:50		7/6/26 19:04	
QC Batch No.:	260706GC8A1		260706GC8A1		260706GC8A1		260706GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	370	10	410	10	420	10	190	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/06/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T070609-09		T070609-10					
Client Sample I.D.:	CV-24069		CV-24070					
Date/Time Sampled:	7/6/26 8:30		7/6/26 8:35					
Date/Time Analyzed:	7/6/26 19:19		7/6/26 19:33					
QC Batch No.:	260706GC8A1		260706GC8A1					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv				
Carbon Monoxide	58	10	1,000	10				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260706GC8A1
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	7/6/26 17:05			7/6/26 16:22		7/6/26 16:36					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,030	102	1,020	101	1.5	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 7/9/26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/06/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070609-01			T070609-02			T070609-03			T070609-04		
Client Sample I.D.:	CV-2301			CV-2302			CV-2303			CV-2312		
Date/Time Sampled:	7/6/26 7:20			7/6/26 7:25			7/6/26 7:35			7/6/26 7:45		
Date/Time Analyzed:	7/6/26 17:23			7/6/26 17:37			7/6/26 17:52			7/6/26 18:06		
QC Batch No.:	260706GC8A1			260706GC8A1			260706GC8A1			260706GC8A1		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	ND	1.0	0.059	ND	1.0	0.059	0.079 J	1.0	0.059	3.3	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 7/9/26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/06/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070609-05			T070609-06			T070609-07			T070609-08		
Client Sample I.D.:	CV-2315			CV-24064			CV-24063			CV-24062		
Date/Time Sampled:	7/6/26 8:00			7/6/26 8:10			7/6/26 8:15			7/6/26 8:20		
Date/Time Analyzed:	7/6/26 18:20			7/6/26 18:35			7/6/26 18:50			7/6/26 19:04		
QC Batch No.:	260706GC8A1			260706GC8A1			260706GC8A1			260706GC8A1		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	2.7	1.0	0.059	3.4	1.0	0.059	3.7	1.0	0.059	2.7	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 7/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/06/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070609-09			T070609-10								
Client Sample I.D.:	CV-24069			CV-24070								
Date/Time Sampled:	7/6/26 8:30			7/6/26 8:35								
Date/Time Analyzed:	7/6/26 19:19			7/6/26 19:33								
QC Batch No.:	260706GC8A1			260706GC8A1								
Analyst Initials:	KD			KD								
Dilution Factor:	1.0			1.0								
ANALYTE	**Result % v/v**	**RL % v/v**	**MDL % v/v**	**Result % v/v**	**RL % v/v**	**MDL % v/v**						
Hydrogen	0.86 J	1.0	0.059	8.6	1.0	0.059						

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 7/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260706GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	7/6/26 17:05				7/6/26 16:22		7/6/26 16:36					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	5.76	116	5.68	114	1.3	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 7/9/26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/06/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070609-01		T070609-02		T070609-03		T070609-04	
Client Sample I.D.:	CV-2301		CV-2302		CV-2303		CV-2312	
Date/Time Sampled:	7/6/26 7:20		7/6/26 7:25		7/6/26 7:35		7/6/26 7:45	
Date/Time Analyzed:	7/6/26 17:23		7/6/26 17:37		7/6/26 17:52		7/6/26 18:06	
QC Batch No.:	260706GC8A1		260706GC8A1		260706GC8A1		260706GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	0.044	0.010	0.045	0.010	0.045	0.010	15	0.010
Oxygen/Argon	21	0.50	21	0.50	21	0.50	17	0.50
Nitrogen	79	1.0	79	1.0	79	1.0	64	1.0
Methane	ND	0.0010	ND	0.0010	0.0010	0.0010	0.14	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/06/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070609-05		T070609-06		T070609-07		T070609-08	
Client Sample I.D.:	CV-2315		CV-24064		CV-24063		CV-24062	
Date/Time Sampled:	7/6/26 8:00		7/6/26 8:10		7/6/26 8:15		7/6/26 8:20	
Date/Time Analyzed:	7/6/26 18:20		7/6/26 18:35		7/6/26 18:50		7/6/26 19:04	
QC Batch No.:	260706GC8A1		260706GC8A1		260706GC8A1		260706GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	14	0.010	19	0.010	26	0.010	17	0.010
Oxygen/Argon	17	0.50	16	0.50	14	0.50	16	0.50
Nitrogen	65	1.0	61	1.0	53	1.0	60	1.0
Methane	1.00	0.0010	0.30	0.0010	2.9	0.0010	4.1	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/06/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070609-09		T070609-10					
Client Sample I.D.:	CV-24069		CV-24070					
Date/Time Sampled:	7/6/26 8:30		7/6/26 8:35					
Date/Time Analyzed:	7/6/26 19:19		7/6/26 19:33					
QC Batch No.:	260706GC8A1		260706GC8A1					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**				
Carbon Dioxide	3.8	0.010	71	0.010				
Oxygen/Argon	20	0.50	2.5	0.50				
Nitrogen	75	1.0	9.3	1.0				
Methane	0.98	0.0010	7.9	0.0010				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260706GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	7/6/26 17:05			7/6/26 16:22		7/6/26 16:36					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	10.0	100	9.98	100	0.6	70	130	30
Oxygen/Argon	ND	0.50	15	14.8	99	14.8	98	0.2	70	130	30
Nitrogen	ND	1.0	70	72.3	104	72.2	103	0.3	70	130	30
Methane	ND	0.0010	0.10	0.0972	96	0.0956	95	1.7	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 7/9/26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

July 20, 2026

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175
TX Cert T104704450-14-6
EPA Methods TO14A, TO15
ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T070705-01/10

Enclosed are the results for sample(s) received 7/7/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags. Quadratic regression calibration was required for IPA, n-hexane, ethyl acetate, tetrahydrofuran, MTBE, 2-hexanone, styrene, and 1,2,4-trichlorobenzene.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Zain Khan, Art Jones and Ali Ferrara on 7/17/26.

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐ No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐ No ☐
Other:				Level 4	☐	Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:	
Bill to:	07FSAccountspayable@scsengineers.com
	3900 Kilroy Airport Way, Suite 300
	Long Beach, CA 90806-6816

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	ANALYSIS REQUEST: CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T070705-01	CV-2341	07/07/26	6:40AM	1L	Gas	N	X	X	X			
-02	CV-1902A	07/07/26	6:50AM	2-1L	Gas	N	X	X	X	X		
-03	CV-2337	07/07/26	7:00AM	1L	Gas	N	X	X	X			
-04	H-1770N	07/07/26	7:10AM	2-1L	Gas	N	X	X	X	X		
-05	CV-24007	07/07/26	7:20AM	2-1L	Gas	N	X	X	X	X		
-06	CV-24127	07/07/26	7:40AM	2-1L	Gas	N	X	X	X	X		
-07	CV-24126	07/07/26	7:48AM	1L	Gas	N	X					
-08	CV-2007	07/07/26	8:00AM	2-1L	Gas	N	X	X	X	X		
-09	CV-24055	07/07/26	8:15AM	1L	Gas	N	X	X	X			
-A	CV-24134	07/07/26	8:25AM	1L	Gas	N	X					

AUTHORIZATION TO PERFORM WORK	COMPANY SCS	DATE/TIME 7-7-26 9:26		
SAMPLED BY	COMPANY SCS	DATE/TIME 7-7-26 9:26		
RELINQUISHED BY	DATE/TIME 7-7-26 9:26	RECEIVED BY Ruben G	DATE/TIME 7-7-26 9:26 AM	
RELINQUISHED BY Ruben G	DATE/TIME 7-7-26 11:45	RECEIVED BY	DATE/TIME 7/7/26 11:45	
RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME	

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/07/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T070705-02		T070705-04		T070705-05		T070705-06	
Client Sample I.D.:	CV-1902A		H-1770N		CV-24007		CV-24127	
Date/Time Sampled:	7/7/26 6:50		7/7/26 7:10		7/7/26 7:20		7/7/26 7:40	
Date/Time Analyzed:	7/7/26 18:27		7/7/26 17:12		7/7/26 17:49		7/7/26 19:05	
QC Batch No.:	260707MS2A1		260707MS2A1		260707MS2A1		260707MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	6,600		2,000		4,600		10,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	6,600	ND	2,000	ND	4,600	ND	10,000
Chloromethane	ND	6,600	ND	2,000	ND	4,600	38,000	10,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	6,600	ND	2,000	ND	4,600	ND	10,000
Vinyl Chloride	ND	6,600	ND	2,000	ND	4,600	ND	10,000
Bromomethane	ND	6,600	ND	2,000	ND	4,600	ND	10,000
Chloroethane	ND	6,600	ND	2,000	ND	4,600	ND	10,000
Trichlorofluoromethane (11)	ND	6,600	ND	2,000	ND	4,600	ND	10,000
1,1-Dichloroethene	ND	6,600	ND	2,000	ND	4,600	ND	10,000
Carbon Disulfide	8,700	6,600	ND	2,000	ND	4,600	ND	10,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	6,600	ND	2,000	ND	4,600	ND	10,000
Acetone	560,000	6,600	130,000	2,000	360,000	4,600	730,000	10,000
Methylene Chloride	ND	6,600	ND	2,000	ND	4,600	ND	10,000
t-1,2-Dichloroethene	ND	6,600	ND	2,000	ND	4,600	ND	10,000
1,1-Dichloroethane	ND	6,600	ND	2,000	ND	4,600	ND	10,000
Vinyl Acetate	ND	6,600	ND	2,000	ND	4,600	ND	10,000
c-1,2-Dichloroethene	ND	6,600	ND	2,000	ND	4,600	ND	10,000
2-Butanone	450,000	13,000	130,000	4,000	330,000	9,200	610,000	20,000
t-Butyl Methyl Ether (MTBE)	ND	6,600	ND	2,000	ND	4,600	ND	10,000
Chloroform	ND	6,600	ND	2,000	ND	4,600	ND	10,000
1,1,1-Trichloroethane	ND	6,600	ND	2,000	ND	4,600	ND	10,000
Carbon Tetrachloride	ND	6,600	ND	2,000	ND	4,600	ND	10,000
Benzene	100,000	6,600	130,000	2,000	180,000	4,600	170,000	10,000
1,2-Dichloroethane	ND	6,600	ND	2,000	ND	4,600	ND	10,000
Trichloroethene	ND	6,600	ND	2,000	ND	4,600	ND	10,000
1,2-Dichloropropane	ND	6,600	ND	2,000	ND	4,600	ND	10,000
Bromodichloromethane	ND	6,600	ND	2,000	ND	4,600	ND	10,000
c-1,3-Dichloropropene	ND	6,600	ND	2,000	ND	4,600	ND	10,000
4-Methyl-2-Pentanone	ND	6,600	4,100	2,000	6,700	4,600	ND	10,000
Toluene	ND	6,600	6,800	2,000	8,700	4,600	ND	10,000
t-1,3-Dichloropropene	ND	6,600	ND	2,000	ND	4,600	ND	10,000
1,1,2-Trichloroethane	ND	6,600	ND	2,000	ND	4,600	ND	10,000
Tetrachloroethene	ND	6,600	ND	2,000	ND	4,600	ND	10,000
2-Hexanone	ND	6,600	ND	2,000	ND	4,600	ND	10,000
Dibromochloromethane	ND	6,600	ND	2,000	ND	4,600	ND	10,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/07/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T070705-02		T070705-04		T070705-05		T070705-06	
Client Sample I.D.:	CV-1902A		H-1770N		CV-24007		CV-24127	
Date/Time Sampled:	7/7/26 6:50		7/7/26 7:10		7/7/26 7:20		7/7/26 7:40	
Date/Time Analyzed:	7/7/26 18:27		7/7/26 17:12		7/7/26 17:49		7/7/26 19:05	
QC Batch No.:	260707MS2A1		260707MS2A1		260707MS2A1		260707MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	6,600		2,000		4,600		10,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	6,600	ND	2,000	ND	4,600	ND	10,000
Chlorobenzene	ND	6,600	ND	2,000	ND	4,600	ND	10,000
Ethylbenzene	ND	6,600	ND	2,000	ND	4,600	ND	10,000
p,&m-Xylene	ND	6,600	ND	2,000	ND	4,600	ND	10,000
o-Xylene	ND	6,600	ND	2,000	ND	4,600	ND	10,000
Styrene	ND	6,600	ND	2,000	ND	4,600	ND	10,000
Bromoform	ND	6,600	ND	2,000	ND	4,600	ND	10,000
1,1,2,2-Tetrachloroethane	ND	6,600	ND	2,000	ND	4,600	ND	10,000
Benzyl Chloride	ND	6,600	ND	2,000	ND	4,600	ND	10,000
4-Ethyl Toluene	ND	6,600	ND	2,000	ND	4,600	ND	10,000
1,3,5-Trimethylbenzene	ND	6,600	ND	2,000	ND	4,600	ND	10,000
1,2,4-Trimethylbenzene	ND	6,600	ND	2,000	ND	4,600	ND	10,000
1,3-Dichlorobenzene	ND	6,600	ND	2,000	ND	4,600	ND	10,000
1,4-Dichlorobenzene	ND	6,600	ND	2,000	ND	4,600	ND	10,000
1,2-Dichlorobenzene	ND	6,600	ND	2,000	ND	4,600	ND	10,000
1,2,4-Trichlorobenzene	ND Q	6,600	ND Q	2,000	ND Q	4,600	ND Q	10,000
Hexachlorobutadiene	ND	6,600	ND	2,000	ND	4,600	ND	10,000
1,3-Butadiene	ND	33,000	ND	10,000	ND	23,000	ND	50,000
Isopropanol	82,000	33,000	100,000	10,000	260,000	23,000	250,000	50,000
n-Hexane	ND	33,000	ND	10,000	ND	23,000	ND	50,000
Ethyl Acetate	ND	33,000	ND	10,000	ND	23,000	54,000	50,000
Tetrahydrofuran	270,000	33,000	190,000	10,000	550,000	23,000	360,000	50,000
Cyclohexane	ND	33,000	ND	10,000	ND	23,000	ND	50,000
Heptane	ND	33,000	ND	10,000	ND	23,000	ND	50,000
1,4-Dioxane	ND	33,000	ND	10,000	ND	23,000	ND	50,000

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited low recovery in the continuing calibration verification indicating possible low bias

Reviewed/Approved By: _____ Date 7/10/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/07/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T070705-08
Client Sample I.D.:	CV-2007
Date/Time Sampled:	7/7/26 8:00
Date/Time Analyzed:	7/7/26 19:44
QC Batch No.:	260707MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	20,000

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	20,000
Chloromethane	ND	20,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	20,000
Vinyl Chloride	ND	20,000
Bromomethane	ND	20,000
Chloroethane	ND	20,000
Trichlorofluoromethane (11)	ND	20,000
1,1-Dichloroethene	ND	20,000
Carbon Disulfide	ND	20,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	20,000
Acetone	520,000	20,000
Methylene Chloride	ND	20,000
t-1,2-Dichloroethene	ND	20,000
1,1-Dichloroethane	ND	20,000
Vinyl Acetate	ND	20,000
c-1,2-Dichloroethene	ND	20,000
2-Butanone	350,000	40,000
t-Butyl Methyl Ether (MTBE)	ND	20,000
Chloroform	ND	20,000
1,1,1-Trichloroethane	ND	20,000
Carbon Tetrachloride	ND	20,000
Benzene	190,000	20,000
1,2-Dichloroethane	ND	20,000
Trichloroethene	ND	20,000
1,2-Dichloropropane	ND	20,000
Bromodichloromethane	ND	20,000
c-1,3-Dichloropropene	ND	20,000
4-Methyl-2-Pentanone	ND	20,000
Toluene	ND	20,000
t-1,3-Dichloropropene	ND	20,000
1,1,2-Trichloroethane	ND	20,000
Tetrachloroethene	ND	20,000
2-Hexanone	ND	20,000
Dibromochloromethane	ND	20,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/07/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T070705-08
Client Sample I.D.:	CV-2007
Date/Time Sampled:	7/7/26 8:00
Date/Time Analyzed:	7/7/26 19:44
QC Batch No.:	260707MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	20,000

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	20,000
Chlorobenzene	ND	20,000
Ethylbenzene	ND	20,000
p,&m-Xylene	ND	20,000
o-Xylene	ND	20,000
Styrene	ND	20,000
Bromoform	ND	20,000
1,1,2,2-Tetrachloroethane	ND	20,000
Benzyl Chloride	ND	20,000
4-Ethyl Toluene	ND	20,000
1,3,5-Trimethylbenzene	ND	20,000
1,2,4-Trimethylbenzene	ND	20,000
1,3-Dichlorobenzene	ND	20,000
1,4-Dichlorobenzene	ND	20,000
1,2-Dichlorobenzene	ND	20,000
1,2,4-Trichlorobenzene	ND Q	20,000
Hexachlorobutadiene	ND	20,000
1,3-Butadiene	ND	100,000
Isopropanol	220,000	100,000
n-Hexane	ND	100,000
Ethyl Acetate	ND	100,000
Tetrahydrofuran	220,000	100,000
Cyclohexane	ND	100,000
Heptane	ND	100,000
1,4-Dioxane	ND	100,000

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited low recovery in the continuing calibration verification indicating possible low bias

Reviewed/Approved By: _____ Date 7/17/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/07/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK
Client Sample I.D.:	-
Date/Time Sampled:	-
Date/Time Analyzed:	7/7/26 10:09
QC Batch No.:	260707MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	0.20
Chloromethane	ND	0.20
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20
Vinyl Chloride	ND	0.20
Bromomethane	ND	0.20
Chloroethane	ND	0.20
Trichlorofluoromethane (11)	ND	0.20
1,1-Dichloroethene	ND	0.20
Carbon Disulfide	ND	0.20
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20
Acetone	0.39	0.20
Methylene Chloride	ND	0.20
t-1,2-Dichloroethene	ND	0.20
1,1-Dichloroethane	ND	0.20
Vinyl Acetate	ND	0.20
c-1,2-Dichloroethene	ND	0.20
2-Butanone	ND	0.40
t-Butyl Methyl Ether (MTBE)	ND	0.20
Chloroform	ND	0.20
1,1,1-Trichloroethane	ND	0.20
Carbon Tetrachloride	ND	0.20
Benzene	ND	0.20
1,2-Dichloroethane	ND	0.20
Trichloroethene	ND	0.20
1,2-Dichloropropane	ND	0.20
Bromodichloromethane	ND	0.20
c-1,3-Dichloropropene	ND	0.20
4-Methyl-2-Pentanone	ND	0.20
Toluene	ND	0.20
t-1,3-Dichloropropene	ND	0.20
1,1,2-Trichloroethane	ND	0.20
Tetrachloroethene	ND	0.20
2-Hexanone	ND	0.20
Dibromochloromethane	ND	0.20

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/07/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK							
Client Sample I.D.:	-							
Date/Time Sampled:	-							
Date/Time Analyzed:	7/7/26 10:09							
QC Batch No.:	260707MS2A1							
Analyst Initials:	VM/GD							
Dilution Factor:	0.20							

ANALYTE	Result ppbv	RL ppbv						
1,2-Dibromoethane	ND	0.20						
Chlorobenzene	ND	0.20						
Ethylbenzene	ND	0.20						
p,&m-Xylene	ND	0.20						
o-Xylene	ND	0.20						
Styrene	ND	0.20						
Bromoform	ND	0.20						
1,1,2,2-Tetrachloroethane	ND	0.20						
Benzyl Chloride	ND	0.20						
4-Ethyl Toluene	ND	0.20						
1,3,5-Trimethylbenzene	ND	0.20						
1,2,4-Trimethylbenzene	ND	0.20						
1,3-Dichlorobenzene	ND	0.20						
1,4-Dichlorobenzene	ND	0.20						
1,2-Dichlorobenzene	ND	0.20						
1,2,4-Trichlorobenzene	ND Q	0.20						
Hexachlorobutadiene	ND	0.20						
1,3-Butadiene	ND	1.0						
Isopropanol	ND	1.0						
n-Hexane	ND	1.0						
Ethyl Acetate	ND	1.0						
Tetrahydrofuran	ND	1.0						
Cyclohexane	ND	1.0						
Heptane	ND	1.0						
1,4-Dioxane	ND	1.0						

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited low recovery in the continuing calibration verification indicating possible low bias

Reviewed/Approved By: _____ **Date** 7/17/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 260707MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	7/7/26 10:09			7/7/26 8:54		7/7/26 9:31					
Analyst Initials:	VM/GD			VM/GD		VM/GD					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	0.20	10	9.14	91	9.04	90	1.1	70	130	30
Methylene Chloride	ND	0.20	10	10.0	100	9.82	98	2.1	70	130	30
Trichloroethene	ND	0.20	10	9.53	95	9.08	91	4.8	70	130	30
Toluene	ND	0.20	10	9.14	91	9.14	91	0.1	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	8.46	85	8.99	90	6.0	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date: 7/17/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/07/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T070705-01		T070705-02		T070705-03		T070705-04	
Client Sample I.D.:	CV-2341		CV-1902A		CV-2337		H-1770N	
Date/Time Sampled:	7/7/26 6:40		7/7/26 6:50		7/7/26 7:00		7/7/26 7:10	
Date/Time Analyzed:	7/7/26 19:58		7/7/26 20:12		7/7/26 20:27		7/7/26 20:41	
QC Batch No.:	260707GC8A2		260707GC8A2		260707GC8A2		260707GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	990	10	400	10	1,000	10	180	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7-17-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/07/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T070705-05		T070705-06		T070705-08		T070705-09	
Client Sample I.D.:	CV-24007		CV-24127		CV-2007		CV-24055	
Date/Time Sampled:	7/7/26 7:20		7/7/26 7:40		7/7/26 8:00		7/7/26 8:15	
Date/Time Analyzed:	7/7/26 20:56		7/7/26 21:11		7/7/26 21:41		7/7/26 21:55	
QC Batch No.:	260707GC8A2		260707GC8A2		260707GC8A2		260707GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	750	10	2,000	10	570	10	820	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7-17-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260707GC8A2
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	7/7/26 19:29			7/7/26 18:45		7/7/26 19:00					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,040	103	1,040	103	0.4	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 7-17-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/07/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070705-01			T070705-02			T070705-03			T070705-04		
Client Sample I.D.:	CV-2341			CV-1902A			CV-2337			H-1770N		
Date/Time Sampled:	7/7/26 6:40			7/7/26 6:50			7/7/26 7:00			7/7/26 7:10		
Date/Time Analyzed:	7/7/26 19:58			7/7/26 20:12			7/7/26 20:27			7/7/26 20:41		
QC Batch No.:	260707GC8A2			260707GC8A2			260707GC8A2			260707GC8A2		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	17	1.0	0.059	10	1.0	0.059	4.3	1.0	0.059	1.7	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 7-17-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/07/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070705-05			T070705-06			T070705-08			T070705-09		
Client Sample I.D.:	CV-24007			CV-24127			CV-2007			CV-24055		
Date/Time Sampled:	7/7/26 7:20			7/7/26 7:40			7/7/26 8:00			7/7/26 8:15		
Date/Time Analyzed:	7/7/26 20:56			7/7/26 21:11			7/7/26 21:41			7/7/26 21:55		
QC Batch No.:	260707GC8A2			260707GC8A2			260707GC8A2			260707GC8A2		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	9.3	1.0	0.059	12	1.0	0.059	4.0	1.0	0.059	5.1	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 7-17-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260707GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	7/7/26 19:29				7/7/26 18:45		7/7/26 19:00					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	5.12	103	5.05	102	1.4	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 7-17-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/07/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070705-01		T070705-02		T070705-03		T070705-04	
Client Sample I.D.:	CV-2341		CV-1902A		CV-2337		H-1770N	
Date/Time Sampled:	7/7/26 6:40		7/7/26 6:50		7/7/26 7:00		7/7/26 7:10	
Date/Time Analyzed:	7/7/26 19:58		7/7/26 20:12		7/7/26 20:27		7/7/26 20:41	
QC Batch No.:	260707GC8A2		260707GC8A2		260707GC8A2		260707GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	56	0.010	35	0.010	18	0.010	41	0.010
Oxygen/Argon	3.6	0.50	11	0.50	16	0.50	6.6	0.50
Nitrogen	14	1.0	42	1.0	61	1.0	26	1.0
Methane	8.5	0.0010	0.95	0.0010	0.76	0.0010	24	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7-17-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/07/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070705-05		T070705-06		T070705-07		T070705-08	
Client Sample I.D.:	CV-24007		CV-24127		CV-24126		CV-2007	
Date/Time Sampled:	7/7/26 7:20		7/7/26 7:40		7/7/26 7:48		7/7/26 8:00	
Date/Time Analyzed:	7/7/26 20:56		7/7/26 21:11		7/7/26 21:25		7/7/26 21:41	
QC Batch No.:	260707GC8A2		260707GC8A2		260707GC8A2		260707GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	45	0.010	49	0.010	43	0.010	48	0.010
Oxygen/Argon	8.1	0.50	7.6	0.50	9.2	0.50	6.5	0.50
Nitrogen	31	1.0	29	1.0	35	1.0	29	1.0
Methane	6.5	0.0010	0.71	0.0010	0.37	0.0010	12	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7-17-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/07/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070705-09		T070705-10					
Client Sample I.D.:	CV-24055		CV-24134					
Date/Time Sampled:	7/7/26 8:15		7/7/26 8:25					
Date/Time Analyzed:	7/7/26 21:55		7/7/26 22:10					
QC Batch No.:	260707GC8A2		260707GC8A2					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**				
Carbon Dioxide	47	0.010	52	0.010				
Oxygen/Argon	5.7	0.50	5.2	0.50				
Nitrogen	34	1.0	20	1.0				
Methane	7.1	0.0010	11	0.0010				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7-7-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260707GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	7/7/26 19:29			7/7/26 18:45		7/7/26 19:00					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	9.65	96	9.67	96	0.2	70	130	30
Oxygen/Argon	ND	0.50	15	15.0	99	15.0	99	0.0	70	130	30
Nitrogen	ND	1.0	70	72.4	104	72.5	104	0.1	70	130	30
Methane	ND	0.0010	0.10	0.0952	94	0.0950	94	0.3	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7-17-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175
TX Cert T104704450-14-6
EPA Methods TO14A, TO15
ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

July 20, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T070806-01/10

Enclosed are the results for sample(s) received 7/8/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags. Quadratic regression calibration was required for IPA, n-hexane, ethyl acetate, tetrahydrofuran, MTBE, 2-hexanone, styrene, and 1,2,4-trichlorobenzene.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Zain Khan, Art Jones and Ali Ferrara on 7/17/26.

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐ No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐ No ☐
Other:				Level 4	☐	Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:	
Bill to:	
	07FSAccountspayable@scsengineers.com
	3900 Kilroy Airport Way, Suite 300
	Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T070806-01	CV-24102	07/08/26	7:00AM	1L	Gas	N	X					
-02	CV-2001	07/08/26	7:10AM	2-1L	Gas	N	X	X	X	X		
-03	H-2165W	07/08/26	7:15AM	2-1L	Gas	N	X	X	X	X		
-04	CV-24099	07/08/26	7:20AM	1L	Gas	N	X					
-05	H-2273W	07/08/26	7:30AM	2-1L	Gas	N	X	X	X	X		
-06	CV-2350	07/08/26	7:40AM	2-1L	Gas	N	X	X	X	X		
-07	CV-2002	07/08/26	7:50AM	2-1L	Gas	N	X	X	X	X		
-08	CV-2354	07/08/26	8:00AM	1L	Gas	N	X	X	X			
-09	CV-2353	07/08/26	8:10AM	1L	Gas	N	X	X	X			
-10	CV-24071	07/08/26	8:25AM	1L	Gas	N	X	X	X			

SAMPLED BY	SCS			DATE/TIME 7-8-26 9:24
SAMPLED BY	SCS			DATE/TIME 7-8-26 9:24
RELINQUISHED BY	DATE/TIME 7-8-26 9:24	RECEIVED BY Ruben G	DATE/TIME 7-8-26 9:26	
RELINQUISHED BY Ruben G	DATE/TIME 7-8-26 11:45	RECEIVED BY	DATE/TIME 7/8/26 11:45	
RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME	

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/08/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T070806-02		T070806-03		T070806-05		T070806-06	
Client Sample I.D.:	CV-2001		H-2165W		H-2273W		CV-2350	
Date/Time Sampled:	7/8/26 7:10		7/8/26 7:15		7/8/26 7:30		7/8/26 7:40	
Date/Time Analyzed:	7/8/26 17:05		7/8/26 17:42		7/8/26 18:20		7/8/26 18:59	
QC Batch No.:	260708MS2A1		260708MS2A1		260708MS2A1		260708MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	6,000		20,000		1,000		20,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	6,000	ND	20,000	ND	1,000	ND	20,000
Chloromethane	ND	6,000	ND	20,000	ND	1,000	ND	20,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	6,000	ND	20,000	ND	1,000	ND	20,000
Vinyl Chloride	ND	6,000	ND	20,000	ND	1,000	ND	20,000
Bromomethane	ND	6,000	ND	20,000	ND	1,000	ND	20,000
Chloroethane	ND	6,000	ND	20,000	ND	1,000	ND	20,000
Trichlorofluoromethane (11)	ND	6,000	ND	20,000	ND	1,000	ND	20,000
1,1-Dichloroethene	ND	6,000	ND	20,000	ND	1,000	ND	20,000
Carbon Disulfide	ND	6,000	ND	20,000	ND	1,000	ND	20,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	6,000	ND	20,000	ND	1,000	ND	20,000
Acetone	34,000	6,000	280,000	20,000	48,000	1,000	230,000	20,000
Methylene Chloride	ND	6,000	ND	20,000	ND	1,000	ND	20,000
t-1,2-Dichloroethene	ND	6,000	ND	20,000	ND	1,000	ND	20,000
1,1-Dichloroethane	ND	6,000	ND	20,000	ND	1,000	ND	20,000
Vinyl Acetate	ND	6,000	ND	20,000	ND	1,000	ND	20,000
c-1,2-Dichloroethene	ND	6,000	ND	20,000	ND	1,000	ND	20,000
2-Butanone	28,000	12,000	180,000	40,000	39,000	2,000	150,000	40,000
t-Butyl Methyl Ether (MTBE)	ND	6,000	ND	20,000	ND	1,000	ND	20,000
Chloroform	ND	6,000	ND	20,000	ND	1,000	ND	20,000
1,1,1-Trichloroethane	ND	6,000	ND	20,000	ND	1,000	ND	20,000
Carbon Tetrachloride	ND	6,000	ND	20,000	ND	1,000	ND	20,000
Benzene	61,000	6,000	150,000	20,000	9,000	1,000	180,000	20,000
1,2-Dichloroethane	ND	6,000	ND	20,000	ND	1,000	ND	20,000
Trichloroethene	ND	6,000	ND	20,000	ND	1,000	ND	20,000
1,2-Dichloropropane	ND	6,000	ND	20,000	ND	1,000	ND	20,000
Bromodichloromethane	ND	6,000	ND	20,000	ND	1,000	ND	20,000
c-1,3-Dichloropropene	ND	6,000	ND	20,000	ND	1,000	ND	20,000
4-Methyl-2-Pentanone	ND	6,000	ND	20,000	ND	1,000	ND	20,000
Toluene	ND	6,000	ND	20,000	ND	1,000	ND	20,000
t-1,3-Dichloropropene	ND	6,000	ND	20,000	ND	1,000	ND	20,000
1,1,2-Trichloroethane	ND	6,000	ND	20,000	ND	1,000	ND	20,000
Tetrachloroethene	ND	6,000	ND	20,000	ND	1,000	ND	20,000
2-Hexanone	ND	6,000	ND	20,000	ND	1,000	ND	20,000
Dibromochloromethane	ND	6,000	ND	20,000	ND	1,000	ND	20,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/08/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T070806-02		T070806-03		T070806-05		T070806-06	
Client Sample I.D.:	CV-2001		H-2165W		H-2273W		CV-2350	
Date/Time Sampled:	7/8/26 7:10		7/8/26 7:15		7/8/26 7:30		7/8/26 7:40	
Date/Time Analyzed:	7/8/26 17:05		7/8/26 17:42		7/8/26 18:20		7/8/26 18:59	
QC Batch No.:	260708MS2A1		260708MS2A1		260708MS2A1		260708MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	6,000		20,000		1,000		20,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	6,000	ND	20,000	ND	1,000	ND	20,000
Chlorobenzene	ND	6,000	ND	20,000	ND	1,000	ND	20,000
Ethylbenzene	ND	6,000	ND	20,000	ND	1,000	ND	20,000
p,&m-Xylene	ND	6,000	ND	20,000	ND	1,000	ND	20,000
o-Xylene	ND	6,000	ND	20,000	ND	1,000	ND	20,000
Styrene	ND	6,000	ND	20,000	ND	1,000	ND	20,000
Bromoform	ND	6,000	ND	20,000	ND	1,000	ND	20,000
1,1,2,2-Tetrachloroethane	ND	6,000	ND	20,000	ND	1,000	ND	20,000
Benzyl Chloride	ND	6,000	ND	20,000	ND	1,000	ND	20,000
4-Ethyl Toluene	ND	6,000	ND	20,000	ND	1,000	ND	20,000
1,3,5-Trimethylbenzene	ND	6,000	ND	20,000	ND	1,000	ND	20,000
1,2,4-Trimethylbenzene	ND	6,000	ND	20,000	1,200	1,000	ND	20,000
1,3-Dichlorobenzene	ND	6,000	ND	20,000	ND	1,000	ND	20,000
1,4-Dichlorobenzene	ND	6,000	ND	20,000	ND	1,000	ND	20,000
1,2-Dichlorobenzene	ND	6,000	ND	20,000	ND	1,000	ND	20,000
1,2,4-Trichlorobenzene	ND Q	6,000	ND Q	20,000	ND Q	1,000	ND Q	20,000
Hexachlorobutadiene	ND	6,000	ND	20,000	ND	1,000	ND	20,000
1,3-Butadiene	ND	30,000	ND	100,000	ND	5,000	ND	100,000
Isopropanol	130,000	30,000	160,000	100,000	90,000	5,000	260,000	100,000
n-Hexane	ND	30,000	ND	100,000	ND	5,000	ND	100,000
Ethyl Acetate	ND	30,000	ND	100,000	ND	5,000	ND	100,000
Tetrahydrofuran	ND	30,000	130,000	100,000	25,000	5,000	170,000	100,000
Cyclohexane	ND	30,000	ND	100,000	ND	5,000	ND	100,000
Heptane	ND	30,000	ND	100,000	ND	5,000	ND	100,000
1,4-Dioxane	ND	30,000	ND	100,000	ND	5,000	ND	100,000

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited low recovery in the continuing calibration verification indicating possible low bias.

Reviewed/Approved By: _____ Date 7/17/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/08/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T070806-07							
Client Sample I.D.:	CV-2002							
Date/Time Sampled:	7/8/26 7:50							
Date/Time Analyzed:	7/8/26 19:38							
QC Batch No.:	260708MS2A1							
Analyst Initials:	VM/GD							
Dilution Factor:	10,000							
ANALYTE	Result ppbv	RL ppbv						
Dichlorodifluoromethane (12)	ND	10,000						
Chloromethane	ND	10,000						
1,2-Cl-1,1,2,2-F ethane (114)	ND	10,000						
Vinyl Chloride	ND	10,000						
Bromomethane	ND	10,000						
Chloroethane	ND	10,000						
Trichlorofluoromethane (11)	ND	10,000						
1,1-Dichloroethene	ND	10,000						
Carbon Disulfide	ND	10,000						
1,1,2-Cl 1,2,2-F ethane (113)	ND	10,000						
Acetone	750,000	10,000						
Methylene Chloride	ND	10,000						
t-1,2-Dichloroethene	ND	10,000						
1,1-Dichloroethane	ND	10,000						
Vinyl Acetate	ND	10,000						
c-1,2-Dichloroethene	ND	10,000						
2-Butanone	610,000	20,000						
t-Butyl Methyl Ether (MTBE)	ND	10,000						
Chloroform	ND	10,000						
1,1,1-Trichloroethane	ND	10,000						
Carbon Tetrachloride	ND	10,000						
Benzene	210,000	10,000						
1,2-Dichloroethane	ND	10,000						
Trichloroethene	ND	10,000						
1,2-Dichloropropane	ND	10,000						
Bromodichloromethane	ND	10,000						
c-1,3-Dichloropropene	ND	10,000						
4-Methyl-2-Pentanone	ND	10,000						
Toluene	ND	10,000						
t-1,3-Dichloropropene	ND	10,000						
1,1,2-Trichloroethane	ND	10,000						
Tetrachloroethene	ND	10,000						
2-Hexanone	ND	10,000						
Dibromochloromethane	ND	10,000						

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/08/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T070806-07
Client Sample I.D.:	CV-2002
Date/Time Sampled:	7/8/26 7:50
Date/Time Analyzed:	7/8/26 19:38
QC Batch No.:	260708MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	10,000

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	10,000
Chlorobenzene	ND	10,000
Ethylbenzene	ND	10,000
p,&m-Xylene	ND	10,000
o-Xylene	ND	10,000
Styrene	ND	10,000
Bromoform	ND	10,000
1,1,2,2-Tetrachloroethane	ND	10,000
Benzyl Chloride	ND	10,000
4-Ethyl Toluene	ND	10,000
1,3,5-Trimethylbenzene	ND	10,000
1,2,4-Trimethylbenzene	ND	10,000
1,3-Dichlorobenzene	ND	10,000
1,4-Dichlorobenzene	ND	10,000
1,2-Dichlorobenzene	ND	10,000
1,2,4-Trichlorobenzene	ND Q	10,000
Hexachlorobutadiene	ND	10,000
1,3-Butadiene	ND	50,000
Isopropanol	670,000	50,000
n-Hexane	ND	50,000
Ethyl Acetate	61,000	50,000
Tetrahydrofuran	560,000	50,000
Cyclohexane	ND	50,000
Heptane	ND	50,000
1,4-Dioxane	ND	50,000

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited low recovery in the continuing calibration verification indicating possible low bias.

Reviewed/Approved By: _____ Date 7/7/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/08/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK
Client Sample I.D.:	-
Date/Time Sampled:	-
Date/Time Analyzed:	7/8/26 9:42
QC Batch No.:	260708MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	0.20
Chloromethane	ND	0.20
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20
Vinyl Chloride	ND	0.20
Bromomethane	ND	0.20
Chloroethane	ND	0.20
Trichlorofluoromethane (11)	ND	0.20
1,1-Dichloroethene	ND	0.20
Carbon Disulfide	ND	0.20
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20
Acetone	ND	0.20
Methylene Chloride	ND	0.20
t-1,2-Dichloroethene	ND	0.20
1,1-Dichloroethane	ND	0.20
Vinyl Acetate	ND	0.20
c-1,2-Dichloroethene	ND	0.20
2-Butanone	ND	0.40
t-Butyl Methyl Ether (MTBE)	ND	0.20
Chloroform	ND	0.20
1,1,1-Trichloroethane	ND	0.20
Carbon Tetrachloride	ND	0.20
Benzene	ND	0.20
1,2-Dichloroethane	ND	0.20
Trichloroethene	ND	0.20
1,2-Dichloropropane	ND	0.20
Bromodichloromethane	ND	0.20
c-1,3-Dichloropropene	ND	0.20
4-Methyl-2-Pentanone	ND	0.20
Toluene	ND	0.20
t-1,3-Dichloropropene	ND	0.20
1,1,2-Trichloroethane	ND	0.20
Tetrachloroethene	ND	0.20
2-Hexanone	ND	0.20
Dibromochloromethane	ND	0.20

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/08/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK							
Client Sample I.D.:	-							
Date/Time Sampled:	-							
Date/Time Analyzed:	7/8/26 9:42							
QC Batch No.:	260708MS2A1							
Analyst Initials:	VM/GD							
Dilution Factor:	0.20							
ANALYTE	**Result ppbv**	**RL ppbv**						
1,2-Dibromoethane	ND	0.20						
Chlorobenzene	ND	0.20						
Ethylbenzene	ND	0.20						
p,&m-Xylene	ND	0.20						
o-Xylene	ND	0.20						
Styrene	ND	0.20						
Bromoform	ND	0.20						
1,1,2,2-Tetrachloroethane	ND	0.20						
Benzyl Chloride	ND	0.20						
4-Ethyl Toluene	ND	0.20						
1,3,5-Trimethylbenzene	ND	0.20						
1,2,4-Trimethylbenzene	ND	0.20						
1,3-Dichlorobenzene	ND	0.20						
1,4-Dichlorobenzene	ND	0.20						
1,2-Dichlorobenzene	ND	0.20						
1,2,4-Trichlorobenzene	ND Q	0.20						
Hexachlorobutadiene	ND	0.20						
1,3-Butadiene	ND	1.0						
Isopropanol	ND	1.0						
n-Hexane	ND	1.0						
Ethyl Acetate	ND	1.0						
Tetrahydrofuran	ND	1.0						
Cyclohexane	ND	1.0						
Heptane	ND	1.0						
1,4-Dioxane	ND	1.0						

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited low recovery in the continuing calibration verification indicating possible low bias.

Reviewed/Approved By: _____ **Date** 7/17/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 260708MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	7/8/26 9:42			7/8/26 8:27		7/8/26 9:04					
Analyst Initials:	VM/GD			VM/GD		VM/GD					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	0.20	10	8.89	89	8.86	89	0.3	70	130	30
Methylene Chloride	ND	0.20	10	9.47	95	9.47	95	0.0	70	130	30
Trichloroethene	ND	0.20	10	8.74	87	8.96	90	2.5	70	130	30
Toluene	ND	0.20	10	8.82	88	8.85	88	0.3	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	8.17	82	8.57	86	4.9	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date:** 7/17/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/08/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T070806-03		T070806-05		T070806-06		T070806-07	
Client Sample I.D.:	H-2165W		H-2273W		CV-2350		CV-2002	
Date/Time Sampled:	7/8/26 7:15		7/8/26 7:30		7/8/26 7:40		7/8/26 7:50	
Date/Time Analyzed:	7/8/26 15:05		7/8/26 15:34		7/8/26 15:49		7/8/26 16:03	
QC Batch No.:	260708GC8A1		260708GC8A1		260708GC8A1		260708GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	670	10	48	10	3,200	10	2,200	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7-17-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/08/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T070806-08		T070806-09		T070806-10			
Client Sample I.D.:	CV-2354		CV-2353		CV-24071			
Date/Time Sampled:	7/8/26 8:00		7/8/26 8:10		7/8/26 8:25			
Date/Time Analyzed:	7/8/26 16:17		7/8/26 16:32		7/8/26 16:46			
QC Batch No.:	260708GC8A1		260708GC8A1		260708GC8A1			
Analyst Initials:	KD		KD		KD			
Dilution Factor:	1.0		1.0		1.0			
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv		
Carbon Monoxide	2,000	10	710	10	570	10		

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7-17-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260708GC8A1
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	7/8/26 14:22			7/8/26 13:24		7/8/26 13:38					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,040	103	1,040	103	0.4	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 7-17-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/08/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070806-03			T070806-05			T070806-06			T070806-07		
Client Sample I.D.:	H-2165W			H-2273W			CV-2350			CV-2002		
Date/Time Sampled:	7/8/26 7:15			7/8/26 7:30			7/8/26 7:40			7/8/26 7:50		
Date/Time Analyzed:	7/8/26 15:05			7/8/26 15:34			7/8/26 15:49			7/8/26 16:03		
QC Batch No.:	260708GC8A1			260708GC8A1			260708GC8A1			260708GC8A1		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	5.3	1.0	0.059	0.54 J	1.0	0.059	17	1.0	0.059	12	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 7-17-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com
Member of the SGS Group (SGS SA)

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/08/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070806-08			T070806-09			T070806-10					
Client Sample I.D.:	CV-2354			CV-2353			CV-24071					
Date/Time Sampled:	7/8/26 8:00			7/8/26 8:10			7/8/26 8:25					
Date/Time Analyzed:	7/8/26 16:17			7/8/26 16:32			7/8/26 16:46					
QC Batch No.:	260708GC8A1			260708GC8A1			260708GC8A1					
Analyst Initials:	KD			KD			KD					
Dilution Factor:	1.0			1.0			1.0					
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v			
Hydrogen	17	1.0	0.059	22	1.0	0.059	8.3	1.0	0.059			

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 7-17-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260708GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	7/8/26 14:22				7/8/26 13:24		7/8/26 13:38					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	4.66	94	4.62	93	0.9	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 7-17-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/08/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070806-01		T070806-03		T070806-04		T070806-05	
Client Sample I.D.:	CV-24102		H-2165W		CV-24099		H-2273W	
Date/Time Sampled:	7/8/26 7:00		7/8/26 7:15		7/8/26 7:20		7/8/26 7:30	
Date/Time Analyzed:	7/8/26 14:36		7/8/26 15:05		7/8/26 15:20		7/8/26 15:34	
QC Batch No.:	260708GC8A1		260708GC8A1		260708GC8A1		260708GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	26	0.010	42	0.010	65	0.010	4.5	0.010
Oxygen/Argon	11	0.50	9.9	0.50	2.1	0.50	19	0.50
Nitrogen	42	1.0	37	1.0	11	1.0	75	1.0
Methane	21	0.0010	5.4	0.0010	21	0.0010	0.68	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7-17-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/08/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070806-06		T070806-07		T070806-08		T070806-09	
Client Sample I.D.:	CV-2350		CV-2002		CV-2354		CV-2353	
Date/Time Sampled:	7/8/26 7:40		7/8/26 7:50		7/8/26 8:00		7/8/26 8:10	
Date/Time Analyzed:	7/8/26 15:49		7/8/26 16:03		7/8/26 16:17		7/8/26 16:32	
QC Batch No.:	260708GC8A1		260708GC8A1		260708GC8A1		260708GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**
Carbon Dioxide	72	0.010	61	0.010	71	0.010	69	0.010
Oxygen/Argon	1.3	0.50	1.1	0.50	0.98	0.50	0.81	0.50
Nitrogen	5.1	1.0	4.9	1.0	3.6	1.0	2.9	1.0
Methane	4.2	0.0010	19	0.0010	5.3	0.0010	2.5	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7-17-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/08/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070806-10						
Client Sample I.D.:	CV-24071						
Date/Time Sampled:	7/8/26 8:25						
Date/Time Analyzed:	7/8/26 16:46						
QC Batch No.:	260708GC8A1						
Analyst Initials:	KD						
Dilution Factor:	1.0						

ANALYTE	Result % v/v	RL % v/v						
Carbon Dioxide	56	0.010						
Oxygen/Argon	0.53	0.50						
Nitrogen	2.0	1.0						
Methane	32	0.0010						

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7-17-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260708GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	7/8/26 14:22			7/8/26 13:24		7/8/26 13:38					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	9.38	94	9.38	94	0.1	70	130	30
Oxygen/Argon	ND	0.50	15	15.1	100	15.2	101	0.4	70	130	30
Nitrogen	ND	1.0	70	72.5	104	72.8	104	0.5	70	130	30
Methane	ND	0.0010	0.10	0.0954	94	0.0952	94	0.3	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 7-17-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175

TX Cert T104704450-14-6
EPA Methods TO14A, TO15

ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

July 28, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T070904-01/10

Enclosed are the results for sample(s) received 7/9/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags.
- Results for TO-15 could not be reported. An error occurred during analysis. Re-analysis could not be performed due to the expiration of the 24-hour holding-time.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results for fixed gases, CO, and hydrogen were e-mailed to Cornelius Fong, Art Jones, Antonio Ambriz, and Jenny Kim on 7/23/26

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐ No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐ No ☐
Other:				Level 4	☐	Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING	
P.O. No.:	
Bill to:	
	07FSAccountspayable@scsengineers.com
	3900 Kilroy Airport Way, Suite 300
	Long Beach, CA 90806-6816

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T070904-01	CV-24084	07/09/26	~~7:00~~ 7:10 AM	1L	Gas	N	X					
-02	CV-2333	07/09/26	7:15AM	1L	Gas	N	X	X	X			
-03	CV-114	07/09/26	7:20AM	1L	Gas	N	X	X	X			
-04	CV-113	07/09/26	7:25AM	2-1L	Gas	N	X	X	X	X		
-05	CV-2334	07/09/26	7:30AM	1L	Gas	N	X	X	X			
-06	CV-24128	07/09/26	7:35AM	1L	Gas	N	X	X	X			
-07	CV-24123	07/09/26	7:40AM	1L	Gas	N	X					
-08	CV-99	07/09/26	7:45AM	1L	Gas	N	X	X	X			
-09	CV-24121	07/09/26	7:50AM	1L	Gas	N	X	X	X			
-10	CV-24122	07/09/26	7:55AM	2-1L	Gas	N	X	X	X	X		

AUTHORIZATION TO PERFORM WORK	COMPANY SCS			DATE/TIME 7-9-26 9:00
SAMPLED BY	COMPANY SCS			DATE/TIME 7-9-26 9:00
RELINQUISHED BY	DATE/TIME 7-9-26 9:00	RECEIVED BY Ruben G		DATE/TIME 7-9-26 9:00
RELINQUISHED BY Ruben G	DATE/TIME 7-9-26 11:34	RECEIVED BY		DATE/TIME 7/9/26 1134
RELINQUISHED BY	DATE/TIME	RECEIVED BY		DATE/TIME

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: H=HCl N=None / Container: B=Bag C=Can V=VOA O=Other

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/09/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070904-01		T070904-02		T070904-03		T070904-04	
Client Sample I.D.:	CV-24084		CV-2333		CV-114		CV-113	
Date/Time Sampled:	7/9/26 7:10		7/9/26 7:15		7/9/26 7:20		7/9/26 7:25	
Date/Time Analyzed:	7/9/26 14:19		7/9/26 14:34		7/9/26 14:48		7/9/26 15:02	
QC Batch No.:	260709GC8A1		260709GC8A1		260709GC8A1		260709GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	78	0.010	74	0.010	66	0.010	5.7	0.010
Oxygen/Argon	1.4	0.50	0.64	0.50	3.3	0.50	19	0.50
Nitrogen	5.3	1.0	2.3	1.0	12	1.0	72	1.0
Methane	1.1	0.0010	0.51	0.0010	0.75	0.0010	2.5	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7/23/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com
Member of the SGS Group (SGS SA)

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/09/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070904-05		T070904-06		T070904-07		T070904-08	
Client Sample I.D.:	CV-2334		CV-24128		CV-24123		CV-99	
Date/Time Sampled:	7/9/26 7:30		7/9/26 7:35		7/9/26 7:40		7/9/26 7:45	
Date/Time Analyzed:	7/9/26 15:17		7/9/26 15:31		7/9/26 15:46		7/9/26 16:00	
QC Batch No.:	260709GC8A1		260709GC8A1		260709GC8A1		260709GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	81	0.010	57	0.010	51	0.010	56	0.010
Oxygen/Argon	0.54	0.50	1.7	0.50	0.67	0.50	0.86	0.50
Nitrogen	2.1	1.0	11	1.0	2.7	1.0	4.2	1.0
Methane	3.3	0.0010	22	0.0010	45	0.0010	39	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7/31/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/09/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070904-09		T070904-10					
Client Sample I.D.:	CV-24121		CV-24122					
Date/Time Sampled:	7/9/26 7:50		7/9/26 7:55					
Date/Time Analyzed:	7/9/26 16:15		7/9/26 16:29					
QC Batch No.:	260709GC8A1		260709GC8A1					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**				
Carbon Dioxide	74	0.010	51	0.010				
Oxygen/Argon	0.72	0.50	1.1	0.50				
Nitrogen	2.7	1.0	6.6	1.0				
Methane	6.0	0.0010	41	0.0010				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7/23/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260709GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	7/9/26 9:54			7/9/26 9:11		7/9/26 9:25					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	9.09	91	9.09	91	0.0	70	130	30
Oxygen/Argon	ND	0.50	15	15.3	102	15.3	102	0.2	70	130	30
Nitrogen	ND	1.0	70	73.1	105	73.1	105	0.1	70	130	30
Methane	ND	0.0010	0.10	0.0932	92	0.0930	92	0.2	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7/23/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/09/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070904-02			T070904-03			T070904-04			T070904-05		
Client Sample I.D.:	CV-2333			CV-114			CV-113			CV-2334		
Date/Time Sampled:	7/9/26 7:15			7/9/26 7:20			7/9/26 7:25			7/9/26 7:30		
Date/Time Analyzed:	7/9/26 14:34			7/9/26 14:48			7/9/26 15:02			7/9/26 15:17		
QC Batch No.:	260709GC8A1			260709GC8A1			260709GC8A1			260709GC8A1		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	20	1.0	0.059	17	1.0	0.059	0.064 J	1.0	0.059	11	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 7/23/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/09/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T070904-06			T070904-08			T070904-09			T070904-10		
Client Sample I.D.:	CV-24128			CV-99			CV-24121			CV-24122		
Date/Time Sampled:	7/9/26 7:35			7/9/26 7:45			7/9/26 7:50			7/9/26 7:55		
Date/Time Analyzed:	7/9/26 15:31			7/9/26 16:00			7/9/26 16:15			7/9/26 16:29		
QC Batch No.:	260709GC8A1			260709GC8A1			260709GC8A1			260709GC8A1		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	7.2	1.0	0.059	ND	1.0	0.059	16	1.0	0.059	0.17 J	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 7/23/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260709GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	7/9/26 9:54				7/9/26 9:11		7/9/26 9:25					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	4.21	85	4.25	85	1.0	70	130	30

MDL = Method Detection Limit
ND = Not Detected (below RL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 7/23/26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/09/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T070904-02		T070904-03		T070904-04		T070904-05	
Client Sample I.D.:	CV-2333		CV-114		CV-113		CV-2334	
Date/Time Sampled:	7/9/26 7:15		7/9/26 7:20		7/9/26 7:25		7/9/26 7:30	
Date/Time Analyzed:	7/9/26 14:34		7/9/26 14:48		7/9/26 15:02		7/9/26 15:17	
QC Batch No.:	260709GC8A1		260709GC8A1		260709GC8A1		260709GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	3,500	10	2,200	10	ND	10	1,900	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7/23/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/09/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T070904-06		T070904-08		T070904-09		T070904-10	
Client Sample I.D.:	CV-24128		CV-99		CV-24121		CV-24122	
Date/Time Sampled:	7/9/26 7:35		7/9/26 7:45		7/9/26 7:50		7/9/26 7:55	
Date/Time Analyzed:	7/9/26 15:31		7/9/26 16:00		7/9/26 16:15		7/9/26 16:29	
QC Batch No.:	260709GC8A1		260709GC8A1		260709GC8A1		260709GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	1,600	10	ND	10	2,100	10	ND	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7/23/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260709GC8A1
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	7/9/26 9:54			7/9/26 9:11		7/9/26 9:25					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,010	100	1,010	100	0.2	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7/23/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175
TX Cert T104704450-14-6
EPA Methods TO14A, TO15
ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

July 28, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T071303-01/12

Enclosed are the results for sample(s) received 7/13/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags. Quadratic regression calibration was required for MTBE, 2-hexanone, styrene, and 1,2,4-trichlorobenzene.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Art Jones, Zain Khan, and Jenny Kim on 7/25/26.

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Annika Sotelo-Sanchez
Lab Manager
annika.sotelo-sanchez@sgs.com

Note: The cover letter is an integral part of this analytical report.

CHAIN OF CUSTODY RECORD

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐ No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐ No ☐
Other:				Level 4	☐	Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:	
Bill to:	07FSAccountspayable@scsengineers.com
	3900 Kilroy Airport Way, Suite 300
	Long Beach, CA 90806-6816

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T071303-01	CV-2328	07/13/26	7:10AM	1L	Gas	N	X	X	X			
-02	CV-24053	07/13/26	7:15AM	2-1L	Gas	N	X	X	X	X		
-03	CV-2314	07/13/26	7:30AM	1L	Gas	N	X	X	X			
-04	CV-2305	07/13/26	8:40AM	1L	Gas	N	X	X	X			
-05	CV-24065	07/13/26	8:45AM	2-1L	Gas	N	X	X	X	X		
-06	CV-24017	07/13/26	9:00AM	2-1L	Gas	N	X	X	X	X		
-07	CV-24049	07/13/26	9:10AM	1L	Gas	N	X	X	X			
-08	CV-24066	07/13/26	9:20AM	1L	Gas	N	X	X	X			
-09	CV-1535	07/13/26	9:30AM	2-1L	Gas	N	X	X	X	X		
-10	CV-24134 thu 7/13/26 * Cancelled	07/13/26	9:40AM	1L	Gas	N	X	X	X	X		

ANALYSIS REQUEST

AUTHORIZATION TO PERFORM WORK	COMPANY SCS	DATE/TIME 7-13-26 1105	
SAMPLED BY	COMPANY SCS	DATE/TIME 7-13-26 1105	
RELINQUISHED BY	DATE/TIME 7-13-26 1105	RECEIVED BY Ruben G	DATE/TIME 7-13-26 11:05
RELINQUISHED BY Ruben G	DATE/TIME 7-13-26 12:17	RECEIVED BY	DATE/TIME 7/13/26 1217
RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

* Cancelled per Antonio A. thu 7/13/26

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: H=HCl N=None / Container: B=Bag C=Can V=VOA O=Other

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐ No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐ No ☐
Other:				Level 4	☐	Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING	
P.O. No.:	
Bill to:	
	07FSAccountspayable@scsengineers.com
	3900 Kilroy Airport Way, Suite 300
	Long Beach, CA 90806-6816

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	ANALYSIS REQUEST: CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T071303-11	CV-24120	07/13/26	10:05AM	1L	Gas	N	X	X	X			
-12	CV-24125	07/13/26	10:25AM	1L	Gas	N	X	X	X			
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						

	COMPANY	DATE/TIME
AUTHORIZATION TO PERFORM WORK	SCS	7-13-26 11:05
SAMPLED BY	SCS	7-13-26 11:05
RELINQUISHED BY	DATE/TIME 7-13-26 11:05	RECEIVED BY / DATE/TIME 7-13-26 11:05
RELINQUISHED BY	DATE/TIME 7-13-26 12:17	RECEIVED BY / DATE/TIME 7/13/26 12:17
RELINQUISHED BY	DATE/TIME	RECEIVED BY / DATE/TIME

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/13/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T071303-02		T071303-05		T071303-06		T071303-09	
Client Sample I.D.:	CV-24053		CV-24065		CV-24017		CV-1535	
Date/Time Sampled:	7/13/26 7:15		7/13/26 8:45		7/13/26 9:00		7/13/26 9:30	
Date/Time Analyzed:	7/13/26 15:14		7/13/26 15:53		7/13/26 16:30		7/13/26 17:09	
QC Batch No.:	260713MS2A1		260713MS2A1		260713MS2A1		260713MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	1,500		3,600		12,000		1,500	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	1,500	ND	3,600	ND	12,000	ND	1,500
Chloromethane	ND	1,500	ND	3,600	ND	12,000	ND	1,500
1,2-Cl-1,1,2,2-F ethane (114)	ND	1,500	ND	3,600	ND	12,000	ND	1,500
Vinyl Chloride	ND	1,500	ND	3,600	ND	12,000	ND	1,500
Bromomethane	ND	1,500	ND	3,600	ND	12,000	ND	1,500
Chloroethane	ND	7,500	ND	18,000	ND	60,000	ND	7,500
Trichlorofluoromethane (11)	ND	1,500	ND	3,600	ND	12,000	ND	1,500
1,1-Dichloroethene	ND	1,500	ND	3,600	ND	12,000	ND	1,500
Carbon Disulfide	6,600	1,500	ND	3,600	ND	12,000	ND	1,500
1,1,2-Cl 1,2,2-F ethane (113)	ND	1,500	ND	3,600	ND	12,000	ND	1,500
Acetone	100,000	7,500	230,000	18,000	750,000	60,000	120,000	7,500
Methylene Chloride	ND	1,500	ND	3,600	ND	12,000	ND	1,500
t-1,2-Dichloroethene	ND	1,500	ND	3,600	ND	12,000	ND	1,500
1,1-Dichloroethane	ND	1,500	ND	3,600	ND	12,000	ND	1,500
Vinyl Acetate	ND	1,500	ND	3,600	ND	12,000	ND	1,500
c-1,2-Dichloroethene	ND	1,500	ND	3,600	ND	12,000	ND	1,500
2-Butanone	100,000	7,500	140,000	18,000	450,000	60,000	120,000	7,500
t-Butyl Methyl Ether (MTBE)	ND	1,500	ND	3,600	ND	12,000	ND	1,500
Chloroform	ND	1,500	ND	3,600	ND	12,000	ND	1,500
1,1,1-Trichloroethane	ND	1,500	ND	3,600	ND	12,000	ND	1,500
Carbon Tetrachloride	ND	1,500	ND	3,600	ND	12,000	ND	1,500
Benzene	38,000	1,500	44,000	3,600	120,000	12,000	60,000	1,500
1,2-Dichloroethane	ND	1,500	ND	3,600	ND	12,000	ND	1,500
Trichloroethene	ND	1,500	ND	3,600	ND	12,000	ND	1,500
1,2-Dichloropropane	ND	1,500	ND	3,600	ND	12,000	ND	1,500
Bromodichloromethane	ND	1,500	ND	3,600	ND	12,000	ND	1,500
c-1,3-Dichloropropene	ND	1,500	ND	3,600	ND	12,000	ND	1,500
4-Methyl-2-Pentanone	1,900	1,500	ND	3,600	ND	12,000	3,000	1,500
Toluene	2,300	1,500	ND	3,600	ND	12,000	8,300	1,500
t-1,3-Dichloropropene	ND	3,000	ND	7,200	ND	24,000	ND	3,000
1,1,2-Trichloroethane	ND	1,500	ND	3,600	ND	12,000	ND	1,500
Tetrachloroethene	ND	1,500	ND	3,600	ND	12,000	ND	1,500
2-Hexanone	ND	1,500	ND	3,600	ND	12,000	ND	1,500
Dibromochloromethane	ND	1,500	ND	3,600	ND	12,000	ND	1,500

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/13/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T071303-02		T071303-05		T071303-06		T071303-09	
Client Sample I.D.:	CV-24053		CV-24065		CV-24017		CV-1535	
Date/Time Sampled:	7/13/26 7:15		7/13/26 8:45		7/13/26 9:00		7/13/26 9:30	
Date/Time Analyzed:	7/13/26 15:14		7/13/26 15:53		7/13/26 16:30		7/13/26 17:09	
QC Batch No.:	260713MS2A1		260713MS2A1		260713MS2A1		260713MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	1,500		3,600		12,000		1,500	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	1,500	ND	3,600	ND	12,000	ND	1,500
Chlorobenzene	ND	1,500	ND	3,600	ND	12,000	ND	1,500
Ethylbenzene	ND	1,500	ND	3,600	ND	12,000	ND	1,500
p,&m-Xylene	ND	3,000	ND	7,200	ND	24,000	ND	3,000
o-Xylene	ND	1,500	ND	3,600	ND	12,000	ND	1,500
Styrene	ND	1,500	ND	3,600	ND	12,000	ND	1,500
Bromoform	ND	1,500	ND	3,600	ND	12,000	ND	1,500
1,1,2,2-Tetrachloroethane	ND	1,500	ND	3,600	ND	12,000	ND	1,500
Benzyl Chloride	ND	1,500	ND	3,600	ND	12,000	ND	1,500
4-Ethyl Toluene	ND	1,500	ND	3,600	ND	12,000	ND	1,500
1,3,5-Trimethylbenzene	ND	1,500	ND	3,600	ND	12,000	ND	1,500
1,2,4-Trimethylbenzene	ND	1,500	ND	3,600	ND	12,000	ND	1,500
1,3-Dichlorobenzene	ND	1,500	ND	3,600	ND	12,000	ND	1,500
1,4-Dichlorobenzene	ND	1,500	ND	3,600	ND	12,000	ND	1,500
1,2-Dichlorobenzene	ND	1,500	ND	3,600	ND	12,000	ND	1,500
1,2,4-Trichlorobenzene	ND Q	1,500	ND Q	3,600	ND Q	12,000	ND Q	1,500
Hexachlorobutadiene	ND	1,500	ND	3,600	ND	12,000	ND	1,500
1,3-Butadiene	ND	7,500	ND	18,000	ND	60,000	ND	7,500
Isopropanol	130,000	7,500	140,000	18,000	380,000	60,000	170,000	7,500
n-Hexane	ND	7,500	ND	18,000	ND	60,000	ND	7,500
Ethyl Acetate	9,100	7,500	ND	18,000	85,000	60,000	9,300	7,500
Tetrahydrofuran	100,000	7,500	78,000	18,000	310,000	60,000	100,000	7,500
Cyclohexane	ND	7,500	ND	18,000	ND	60,000	ND	7,500
Heptane	ND	7,500	ND	18,000	ND	60,000	ND	7,500
1,4-Dioxane	ND	7,500	ND	18,000	ND	60,000	ND	7,500

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited low recovery in the continuing calibration verification indicating possible low bias

Reviewed/Approved By: _____ **Date** 7/25/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/13/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK
Client Sample I.D.:	-
Date/Time Sampled:	-
Date/Time Analyzed:	7/13/26 13:58
QC Batch No.:	260713MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	0.20
Chloromethane	ND	0.20
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20
Vinyl Chloride	ND	0.20
Bromomethane	ND	0.20
Chloroethane	ND	1.0
Trichlorofluoromethane (11)	ND	0.20
1,1-Dichloroethene	ND	0.20
Carbon Disulfide	ND	0.20
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20
Acetone	ND	1.0
Methylene Chloride	ND	0.20
t-1,2-Dichloroethene	ND	0.20
1,1-Dichloroethane	ND	0.20
Vinyl Acetate	ND	0.20
c-1,2-Dichloroethene	ND	0.20
2-Butanone	ND	1.0
t-Butyl Methyl Ether (MTBE)	ND	0.20
Chloroform	ND	0.20
1,1,1-Trichloroethane	ND	0.20
Carbon Tetrachloride	ND	0.20
Benzene	ND	0.20
1,2-Dichloroethane	ND	0.20
Trichloroethene	ND	0.20
1,2-Dichloropropane	ND	0.20
Bromodichloromethane	ND	0.20
c-1,3-Dichloropropene	ND	0.20
4-Methyl-2-Pentanone	ND	0.20
Toluene	ND	0.20
t-1,3-Dichloropropene	ND	0.40
1,1,2-Trichloroethane	ND	0.20
Tetrachloroethene	ND	0.20
2-Hexanone	ND	0.20
Dibromochloromethane	ND	0.20

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/13/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK							
Client Sample I.D.:	-							
Date/Time Sampled:	-							
Date/Time Analyzed:	7/13/26 13:58							
QC Batch No.:	260713MS2A1							
Analyst Initials:	VM/GD							
Dilution Factor:	0.20							

ANALYTE	Result ppbv	RL ppbv						
1,2-Dibromoethane	ND	0.20						
Chlorobenzene	ND	0.20						
Ethylbenzene	ND	0.20						
p,&m-Xylene	ND	0.40						
o-Xylene	ND	0.20						
Styrene	ND	0.20						
Bromoform	ND	0.20						
1,1,2,2-Tetrachloroethane	ND	0.20						
Benzyl Chloride	ND	0.20						
4-Ethyl Toluene	ND	0.20						
1,3,5-Trimethylbenzene	ND	0.20						
1,2,4-Trimethylbenzene	ND	0.20						
1,3-Dichlorobenzene	ND	0.20						
1,4-Dichlorobenzene	ND	0.20						
1,2-Dichlorobenzene	ND	0.20						
1,2,4-Trichlorobenzene	ND Q	0.20						
Hexachlorobutadiene	ND	0.20						
1,3-Butadiene	ND	1.0						
Isopropanol	ND	1.0						
n-Hexane	ND	1.0						
Ethyl Acetate	ND	1.0						
Tetrahydrofuran	ND	1.0						
Cyclohexane	ND	1.0						
Heptane	ND	1.0						
1,4-Dioxane	ND	1.0						

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited low recovery in the continuing calibration verification indicating possible low bias

Reviewed/Approved By: _____ **Date** 7/25/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 260713MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	7/13/26 13:58			7/13/26 12:42		7/13/26 13:20					
Analyst Initials:	VM/GD			VM/GD		VM/GD					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	0.20	10	8.33	83	8.42	84	1.0	70	130	30
Methylene Chloride	ND	0.20	10	8.66	87	9.15	92	5.5	70	130	30
Trichloroethene	ND	0.20	10	8.08	81	7.94	79	1.7	70	130	30
Toluene	ND	0.20	10	8.43	84	8.17	82	3.1	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	7.83	78	7.60	76	3.0	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date:** 7/25/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/13/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T071303-01		T071303-02		T071303-03		T071303-04	
Client Sample I.D.:	CV-2328		CV-24053		CV-2314		CV-2305	
Date/Time Sampled:	7/13/26 7:10		7/13/26 7:15		7/13/26 7:30		7/13/26 8:40	
Date/Time Analyzed:	7/13/26 14:24		7/13/26 14:38		7/13/26 14:53		7/13/26 15:07	
QC Batch No.:	260713GC8A2		260713GC8A2		260713GC8A2		260713GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	350	10	110	10	3,200	10	2,000	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7-23-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/13/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T071303-05		T071303-06		T071303-07		T071303-08	
Client Sample I.D.:	CV-24065		CV-24017		CV-24049		CV-24066	
Date/Time Sampled:	7/13/26 8:45		7/13/26 9:00		7/13/26 9:10		7/13/26 9:20	
Date/Time Analyzed:	7/13/26 15:22		7/13/26 15:36		7/13/26 15:51		7/13/26 16:05	
QC Batch No.:	260713GC8A2		260713GC8A2		260713GC8A2		260713GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	100	10	1,600	10	1,700	10	170	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7-23-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/13/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T071303-09		T071303-11		T071303-12			
Client Sample I.D.:	CV-1535		CV-24120		CV-24125			
Date/Time Sampled:	7/13/26 9:30		7/13/26 10:05		7/13/26 10:25			
Date/Time Analyzed:	7/13/26 16:20		7/13/26 16:34		7/13/26 16:49			
QC Batch No.:	260713GC8A2		260713GC8A2		260713GC8A2			
Analyst Initials:	KD		KD		KD			
Dilution Factor:	1.0		1.0		1.0			
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv		
Carbon Monoxide	44	10	150	10	ND	10		

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7-23-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260713GC8A2
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	7/13/26 13:55			7/13/26 13:11		7/13/26 13:26					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	987	98	979	97	0.7	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 7-23-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/13/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T071303-01			T071303-02			T071303-03			T071303-04		
Client Sample I.D.:	CV-2328			CV-24053			CV-2314			CV-2305		
Date/Time Sampled:	7/13/26 7:10			7/13/26 7:15			7/13/26 7:30			7/13/26 8:40		
Date/Time Analyzed:	7/13/26 14:24			7/13/26 14:38			7/13/26 14:53			7/13/26 15:07		
QC Batch No.:	260713GC8A2			260713GC8A2			260713GC8A2			260713GC8A2		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	4.2	1.0	0.059	1.5	1.0	0.059	14	1.0	0.059	8.6	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____
Mark Johnson
Operations Manager

Date 7-23-26

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/13/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T071303-05			T071303-06			T071303-07			T071303-08		
Client Sample I.D.:	CV-24065			CV-24017			CV-24049			CV-24066		
Date/Time Sampled:	7/13/26 8:45			7/13/26 9:00			7/13/26 9:10			7/13/26 9:20		
Date/Time Analyzed:	7/13/26 15:22			7/13/26 15:36			7/13/26 15:51			7/13/26 16:05		
QC Batch No.:	260713GC8A2			260713GC8A2			260713GC8A2			260713GC8A2		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	0.33 J	1.0	0.059	18	1.0	0.059	13	1.0	0.059	2.3	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____
Mark Johnson
Operations Manager

Date 7-23-26

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/13/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T071303-09			T071303-11			T071303-12					
Client Sample I.D.:	CV-1535			CV-24120			CV-24125					
Date/Time Sampled:	7/13/26 9:30			7/13/26 10:05			7/13/26 10:25					
Date/Time Analyzed:	7/13/26 16:20			7/13/26 16:34			7/13/26 16:49					
QC Batch No.:	260713GC8A2			260713GC8A2			260713GC8A2					
Analyst Initials:	KD			KD			KD					
Dilution Factor:	1.0			1.0			1.0					
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v			
Hydrogen	0.50 J	1.0	0.059	1.1	1.0	0.059	0.27 J	1.0	0.059			

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 7-23-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260713GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	7/13/26 13:55				7/13/26 13:11		7/13/26 13:26					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	3.86	78	4.00	81	3.7	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 7-23-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/13/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T071303-01		T071303-02		T071303-03		T071303-04	
Client Sample I.D.:	CV-2328		CV-24053		CV-2314		CV-2305	
Date/Time Sampled:	7/13/26 7:10		7/13/26 7:15		7/13/26 7:30		7/13/26 8:40	
Date/Time Analyzed:	7/13/26 14:24		7/13/26 14:38		7/13/26 14:53		7/13/26 15:07	
QC Batch No.:	260713GC8A2		260713GC8A2		260713GC8A2		260713GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	52	0.010	40	0.010	78	0.010	68	0.010
Oxygen/Argon	0.72	0.50	3.4	0.50	0.76	0.50	0.74	0.50
Nitrogen	2.7	1.0	20	1.0	3.4	1.0	5.1	1.0
Methane	40	0.0010	34	0.0010	1.9	0.0010	17	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7-23-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/13/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T071303-05		T071303-06		T071303-07		T071303-08	
Client Sample I.D.:	CV-24065		CV-24017		CV-24049		CV-24066	
Date/Time Sampled:	7/13/26 8:45		7/13/26 9:00		7/13/26 9:10		7/13/26 9:20	
Date/Time Analyzed:	7/13/26 15:22		7/13/26 15:36		7/13/26 15:51		7/13/26 16:05	
QC Batch No.:	260713GC8A2		260713GC8A2		260713GC8A2		260713GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	31	0.010	71	0.010	56	0.010	34	0.010
Oxygen/Argon	3.3	0.50	1.0	0.50	6.0	0.50	4.9	0.50
Nitrogen	49	1.0	3.8	1.0	23	1.0	41	1.0
Methane	15	0.0010	5.2	0.0010	0.73	0.0010	17	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7-23-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/13/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T071303-09		T071303-11		T071303-12			
Client Sample I.D.:	CV-1535		CV-24120		CV-24125			
Date/Time Sampled:	7/13/26 9:30		7/13/26 10:05		7/13/26 10:25			
Date/Time Analyzed:	7/13/26 16:20		7/13/26 16:34		7/13/26 16:49			
QC Batch No.:	260713GC8A2		260713GC8A2		260713GC8A2			
Analyst Initials:	KD		KD		KD			
Dilution Factor:	1.0		1.0		1.0			
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**		
Carbon Dioxide	49	0.010	10	0.010	45	0.010		
Oxygen/Argon	0.63	0.50	18	0.50	2.7	0.50		
Nitrogen	3.2	1.0	69	1.0	13	1.0		
Methane	47	0.0010	1.5	0.0010	38	0.0010		

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7-23-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260713GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	7/13/26 13:55			7/13/26 13:11		7/13/26 13:26					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	9.00	90	9.02	90	0.1	70	130	30
Oxygen/Argon	ND	0.50	15	15.4	102	15.5	103	0.4	70	130	30
Nitrogen	ND	1.0	70	73.5	105	73.9	106	0.5	70	130	30
Methane	ND	0.0010	0.10	0.0924	92	0.0920	91	0.4	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7-23-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

July 28, 2026

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C,
ASTM D1946, RSK-175

TX Cert T104704450-14-6
EPA Methods TO14A, TO15

ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T071403-01

Enclosed are the results for sample(s) received 7/14/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags. Quadratic regression calibration was required for MTBE, 2-hexanone, styrene, and 1,2,4-trichlorobenzene.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Art Jones, Zain Khan, and Jenny Kim on 7/25/26.

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Annika Sotelo-Sanchez
Lab Manager
annika.sotelo-sanchez@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐ No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐ No ☐
Other:				Level 4	☐	Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:	
Bill to:	07FSAccountspayable@scsengineers.com
	3900 Kilroy Airport Way, Suite 300
	Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T071403-01	CV-24139	07/14/26	7:15AM	2-1L	Gas	N	X	X	X	X		
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						

	COMPANY	DATE/TIME
AUTHORIZATION TO PERFORM WORK		
SAMPLED BY	SCS	7/14/26

	DATE/TIME		DATE/TIME
RELINQUISHED BY: Antonio H	7/14/26 9:35am	RECEIVED BY: Karandra Sanson	7/14/26 9:15AM
RELINQUISHED BY: Karandra Sanson	7/14/26 9:15AM	RECEIVED BY: Ruben G	7/14/26 9:35
RELINQUISHED BY: Ruben G	7/14/26 12:21	RECEIVED BY:	7/14/26 1221

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/14/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T071403-01							
Client Sample I.D.:	CV-24139							
Date/Time Sampled:	7/14/26 7:15							
Date/Time Analyzed:	7/14/26 18:15							
QC Batch No.:	260714MS2A1							
Analyst Initials:	VM/GD							
Dilution Factor:	10,000							
ANALYTE	Result ppbv	RL ppbv						
Dichlorodifluoromethane (12)	ND	10,000						
Chloromethane	ND	10,000						
1,2-Cl-1,1,2,2-F ethane (114)	ND	10,000						
Vinyl Chloride	ND	10,000						
Bromomethane	ND	10,000						
Chloroethane	ND	10,000						
Trichlorofluoromethane (11)	ND	10,000						
1,1-Dichloroethene	ND	10,000						
Carbon Disulfide	ND	10,000						
1,1,2-Cl 1,2,2-F ethane (113)	ND	10,000						
Acetone	410,000	10,000						
Methylene Chloride	ND	10,000						
t-1,2-Dichloroethene	ND	10,000						
1,1-Dichloroethane	ND	10,000						
Vinyl Acetate	ND	10,000						
c-1,2-Dichloroethene	ND	10,000						
2-Butanone	360,000	20,000						
t-Butyl Methyl Ether (MTBE)	ND	10,000						
Chloroform	ND	10,000						
1,1,1-Trichloroethane	ND	10,000						
Carbon Tetrachloride	ND	10,000						
Benzene	86,000	10,000						
1,2-Dichloroethane	ND	10,000						
Trichloroethene	ND	10,000						
1,2-Dichloropropane	ND	10,000						
Bromodichloromethane	ND	10,000						
c-1,3-Dichloropropene	ND	10,000						
4-Methyl-2-Pentanone	ND	10,000						
Toluene	ND	10,000						
t-1,3-Dichloropropene	ND	10,000						
1,1,2-Trichloroethane	ND	10,000						
Tetrachloroethene	ND	10,000						
2-Hexanone	ND	10,000						
Dibromochloromethane	ND	10,000						

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/14/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T071403-01
Client Sample I.D.:	CV-24139
Date/Time Sampled:	7/14/26 7:15
Date/Time Analyzed:	7/14/26 18:15
QC Batch No.:	260714MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	10,000

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	10,000
Chlorobenzene	ND	10,000
Ethylbenzene	ND	10,000
p,&m-Xylene	ND	10,000
o-Xylene	ND	10,000
Styrene	ND	10,000
Bromoform	ND	10,000
1,1,2,2-Tetrachloroethane	ND	10,000
Benzyl Chloride	ND	10,000
4-Ethyl Toluene	ND	10,000
1,3,5-Trimethylbenzene	ND	10,000
1,2,4-Trimethylbenzene	ND	10,000
1,3-Dichlorobenzene	ND	10,000
1,4-Dichlorobenzene	ND	10,000
1,2-Dichlorobenzene	ND	10,000
1,2,4-Trichlorobenzene	ND Q	10,000
Hexachlorobutadiene	ND	10,000
1,3-Butadiene	ND	50,000
Isopropanol	52,000	50,000
n-Hexane	ND	50,000
Ethyl Acetate	ND	50,000
Tetrahydrofuran	210,000	50,000
Cyclohexane	ND	50,000
Heptane	ND	50,000
1,4-Dioxane	ND	50,000

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited low recovery in the continuing calibration verification indicating possible low bias

Reviewed/Approved By: _____ Date 7/25/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/14/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK							
Client Sample I.D.:	-							
Date/Time Sampled:	-							
Date/Time Analyzed:	7/14/26 13:11							
QC Batch No.:	260714MS2A1							
Analyst Initials:	VM/GD							
Dilution Factor:	0.20							

ANALYTE	Result ppbv	RL ppbv						
Dichlorodifluoromethane (12)	ND	0.20						
Chloromethane	ND	0.20						
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20						
Vinyl Chloride	ND	0.20						
Bromomethane	ND	0.20						
Chloroethane	ND	0.20						
Trichlorofluoromethane (11)	ND	0.20						
1,1-Dichloroethene	ND	0.20						
Carbon Disulfide	ND	0.20						
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20						
Acetone	ND	0.20						
Methylene Chloride	ND	0.20						
t-1,2-Dichloroethene	ND	0.20						
1,1-Dichloroethane	ND	0.20						
Vinyl Acetate	ND	0.20						
c-1,2-Dichloroethene	ND	0.20						
2-Butanone	ND	0.40						
t-Butyl Methyl Ether (MTBE)	ND	0.20						
Chloroform	ND	0.20						
1,1,1-Trichloroethane	ND	0.20						
Carbon Tetrachloride	ND	0.20						
Benzene	ND	0.20						
1,2-Dichloroethane	ND	0.20						
Trichloroethene	ND	0.20						
1,2-Dichloropropane	ND	0.20						
Bromodichloromethane	ND	0.20						
c-1,3-Dichloropropene	ND	0.20						
4-Methyl-2-Pentanone	ND	0.20						
Toluene	ND	0.20						
t-1,3-Dichloropropene	ND	0.20						
1,1,2-Trichloroethane	ND	0.20						
Tetrachloroethene	ND	0.20						
2-Hexanone	ND	0.20						
Dibromochloromethane	ND	0.20						

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/14/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK
Client Sample I.D.:	-
Date/Time Sampled:	-
Date/Time Analyzed:	7/14/26 13:11
QC Batch No.:	260714MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	0.20
Chlorobenzene	ND	0.20
Ethylbenzene	ND	0.20
p,&m-Xylene	ND	0.20
o-Xylene	ND	0.20
Styrene	ND	0.20
Bromoform	ND	0.20
1,1,2,2-Tetrachloroethane	ND	0.20
Benzyl Chloride	ND	0.20
4-Ethyl Toluene	ND	0.20
1,3,5-Trimethylbenzene	ND	0.20
1,2,4-Trimethylbenzene	ND	0.20
1,3-Dichlorobenzene	ND	0.20
1,4-Dichlorobenzene	ND	0.20
1,2-Dichlorobenzene	ND	0.20
1,2,4-Trichlorobenzene	ND Q	0.20
Hexachlorobutadiene	ND	0.20
1,3-Butadiene	ND	1.0
Isopropanol	ND	1.0
n-Hexane	ND	1.0
Ethyl Acetate	ND	1.0
Tetrahydrofuran	ND	1.0
Cyclohexane	ND	1.0
Heptane	ND	1.0
1,4-Dioxane	ND	1.0

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited low recovery in the continuing calibration verification indicating possible low bias

Reviewed/Approved By: _____ **Date** 7/25/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 260714MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	7/14/26 13:11			7/14/26 11:56		7/14/26 12:33					
Analyst Initials:	VM/GD			VM/GD		VM/GD					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	0.20	10	11.4	114	11.5	115	0.3	70	130	30
Methylene Chloride	ND	0.20	10	11.5	115	11.4	114	0.2	70	130	30
Trichloroethene	ND	0.20	10	10.1	101	10.2	102	1.4	70	130	30
Toluene	ND	0.20	10	9.74	97	9.77	98	0.3	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	6.81	68 *	7.18	72	5.3	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit
* Outside of QC Criteria

Reviewed/Approved By: _____ **Date:** 7/25/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/14/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	**T071403-01**							
Client Sample I.D.:	**CV-24139**							
Date/Time Sampled:	**7/14/26 7:15**							
Date/Time Analyzed:	**7/14/26 18:48**							
QC Batch No.:	**260714GC8A1**							
Analyst Initials:	**KD**							
Dilution Factor:	**1.0**							
ANALYTE	**Result ppmv**	**RL ppmv**						
Carbon Monoxide	300	10						

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 7-24-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260714GC8A1
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	7/14/26 10:49			7/14/26 21:29		7/14/26 21:43					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,040	103	1,030	102	0.7	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 7-24-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/14/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T071403-01											
Client Sample I.D.:	CV-24139											
Date/Time Sampled:	7/14/26 7:15											
Date/Time Analyzed:	7/14/26 18:48											
QC Batch No.:	260714GC8A1											
Analyst Initials:	KD											
Dilution Factor:	1.0											
ANALYTE	Result % v/v	RL % v/v	MDL % v/v									
Hydrogen	9.4	1.0	0.059									

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 7-24-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260714GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	7/14/26 10:49				7/14/26 21:29		7/14/26 21:43					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	5.67	114	5.65	114	0.4	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 7-24-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/14/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T071403-01
Client Sample I.D.:	CV-24139
Date/Time Sampled:	7/14/26 7:15
Date/Time Analyzed:	7/14/26 18:48
QC Batch No.:	260714GC8A1
Analyst Initials:	KD
Dilution Factor:	1.0

ANALYTE	Result % v/v	RL % v/v
Carbon Dioxide	24	0.010
Oxygen/Argon	14	0.50
Nitrogen	51	1.0
Methane	0.83	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7-24-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260714GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	7/14/26 10:49			7/14/26 21:29		7/14/26 21:43					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	10.0	100	9.96	99	0.5	70	130	30
Oxygen/Argon	ND	0.50	15	14.8	99	14.8	99	0.1	70	130	30
Nitrogen	ND	1.0	70	73.0	105	72.8	104	0.3	70	130	30
Methane	ND	0.0010	0.10	0.0948	94	0.0944	93	0.4	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 7-24-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175
TX Cert T104704450-14-6
EPA Methods TO14A, TO15
ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

July 31, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T072405-01/02

Enclosed are the results for sample(s) received 7/24/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Zain Khan, Art Jones and Ali Ferrara on 7/27/26

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐ No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐ No ☐
Other:				Level 4	☐	Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:	
Bill to:	
	07FSAccountspayable@scsengineers.com
	3900 Kilroy Airport Way, Suite 300
	Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T072405-01	CV-113	07/24/26	9:55AM	2-1L	Gas	N	X	X	X	X		
↓ -02	CV-24122	07/24/26	9:45AM	2-1L	Gas	N	X	X	X	X		
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						

AUTHORIZATION TO PERFORM WORK	COMPANY	DATE/TIME
SAMPLED BY: Jaime Cervel	COMPANY: SCS Engineers	DATE/TIME: 7/24/26

RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME
Jaime Cervel	7/24/26 11am	Antonio	7/24/26 11am
Antonio Ambriz	7/24/26 11:15am	Rubcen G	7/24/26 11:00 AM
Rubcen G	7/24/26 12:40	[signature]	7/24/26 1240

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATL! Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/24/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T072405-01		T072405-02					
Client Sample I.D.:	CV-113		CV-24122					
Date/Time Sampled:	7/24/26 9:55		7/24/26 9:45					
Date/Time Analyzed:	7/24/26 16:55		7/24/26 17:34					
QC Batch No.:	260724MS2A1		260724MS2A1					
Analyst Initials:	VM/GD		VM/GD					
Dilution Factor:	16,000		1,000					
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv				
Dichlorodifluoromethane (12)	ND	16,000	ND	1,000				
Chloromethane	ND	16,000	ND	1,000				
1,2-Cl-1,1,2,2-F ethane (114)	ND	16,000	ND	1,000				
Vinyl Chloride	ND	16,000	ND	1,000				
Bromomethane	ND	16,000	ND	1,000				
Chloroethane	ND	16,000	ND	1,000				
Trichlorofluoromethane (11)	ND	16,000	ND	1,000				
1,1-Dichloroethene	ND	16,000	ND	1,000				
Carbon Disulfide	26,000	16,000	ND	1,000				
1,1,2-Cl 1,2,2-F ethane (113)	ND	16,000	ND	1,000				
Acetone	910,000	16,000	47,000	1,000				
Methylene Chloride	ND	16,000	ND	1,000				
t-1,2-Dichloroethene	ND	16,000	ND	1,000				
1,1-Dichloroethane	ND	16,000	ND	1,000				
Vinyl Acetate	ND	16,000	ND	1,000				
c-1,2-Dichloroethene	ND	16,000	ND	1,000				
2-Butanone	600,000	32,000	45,000	2,000				
t-Butyl Methyl Ether (MTBE)	ND	16,000	ND	1,000				
Chloroform	ND	16,000	ND	1,000				
1,1,1-Trichloroethane	ND	16,000	ND	1,000				
Carbon Tetrachloride	ND	16,000	ND	1,000				
Benzene	130,000	16,000	8,300	1,000				
1,2-Dichloroethane	ND	16,000	ND	1,000				
Trichloroethene	ND	16,000	ND	1,000				
1,2-Dichloropropane	ND	16,000	ND	1,000				
Bromodichloromethane	ND	16,000	ND	1,000				
c-1,3-Dichloropropene	ND	16,000	ND	1,000				
4-Methyl-2-Pentanone	ND	16,000	ND	1,000				
Toluene	ND	16,000	ND	1,000				
t-1,3-Dichloropropene	ND	16,000	ND	1,000				
1,1,2-Trichloroethane	ND	16,000	ND	1,000				
Tetrachloroethene	ND	16,000	ND	1,000				
2-Hexanone	ND	16,000	ND	1,000				
Dibromochloromethane	ND	16,000	ND	1,000				

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/24/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T072405-01		T072405-02					
Client Sample I.D.:	CV-113		CV-24122					
Date/Time Sampled:	7/24/26 9:55		7/24/26 9:45					
Date/Time Analyzed:	7/24/26 16:55		7/24/26 17:34					
QC Batch No.:	260724MS2A1		260724MS2A1					
Analyst Initials:	VM/GD		VM/GD					
Dilution Factor:	16,000		1,000					
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv				
1,2-Dibromoethane	ND	16,000	ND	1,000				
Chlorobenzene	ND	16,000	ND	1,000				
Ethylbenzene	ND	16,000	ND	1,000				
p,&m-Xylene	ND	16,000	ND	1,000				
o-Xylene	ND	16,000	ND	1,000				
Styrene	ND	16,000	ND	1,000				
Bromoform	ND	16,000	ND	1,000				
1,1,2,2-Tetrachloroethane	ND	16,000	ND	1,000				
Benzyl Chloride	ND	16,000	ND	1,000				
4-Ethyl Toluene	ND	16,000	ND	1,000				
1,3,5-Trimethylbenzene	ND	16,000	ND	1,000				
1,2,4-Trimethylbenzene	ND	16,000	ND	1,000				
1,3-Dichlorobenzene	ND	16,000	ND	1,000				
1,4-Dichlorobenzene	ND	16,000	ND	1,000				
1,2-Dichlorobenzene	ND	16,000	ND	1,000				
1,2,4-Trichlorobenzene	ND	16,000	ND	1,000				
Hexachlorobutadiene	ND	16,000	ND	1,000				
1,3-Butadiene	ND	80,000	ND	5,000				
Isopropanol	190,000	80,000	11,000	5,000				
n-Hexane	ND	80,000	ND	5,000				
Ethyl Acetate	ND	80,000	ND	5,000				
Tetrahydrofuran	430,000	80,000	12,000	5,000				
Cyclohexane	ND	80,000	ND	5,000				
Heptane	ND	80,000	ND	5,000				
1,4-Dioxane	ND	80,000	ND	5,000				

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ **Date** 7/27/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/24/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK							
Client Sample I.D.:	--							
Date/Time Sampled:	-							
Date/Time Analyzed:	7/24/26 7:39							
QC Batch No.:	260724MS2A1							
Analyst Initials:	VM/GD							
Dilution Factor:	0.20							
ANALYTE	Result ppbv	RL ppbv						
Dichlorodifluoromethane (12)	ND	0.20						
Chloromethane	ND	0.20						
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20						
Vinyl Chloride	ND	0.20						
Bromomethane	ND	0.20						
Chloroethane	ND	0.20						
Trichlorofluoromethane (11)	ND	0.20						
1,1-Dichloroethene	ND	0.20						
Carbon Disulfide	ND	0.20						
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20						
Acetone	ND	0.20						
Methylene Chloride	ND	0.20						
t-1,2-Dichloroethene	ND	0.20						
1,1-Dichloroethane	ND	0.20						
Vinyl Acetate	ND	0.20						
c-1,2-Dichloroethene	ND	0.20						
2-Butanone	ND	0.40						
t-Butyl Methyl Ether (MTBE)	ND	0.20						
Chloroform	ND	0.20						
1,1,1-Trichloroethane	ND	0.20						
Carbon Tetrachloride	ND	0.20						
Benzene	ND	0.20						
1,2-Dichloroethane	ND	0.20						
Trichloroethene	ND	0.20						
1,2-Dichloropropane	ND	0.20						
Bromodichloromethane	ND	0.20						
c-1,3-Dichloropropene	ND	0.20						
4-Methyl-2-Pentanone	ND	0.20						
Toluene	ND	0.20						
t-1,3-Dichloropropene	ND	0.20						
1,1,2-Trichloroethane	ND	0.20						
Tetrachloroethene	ND	0.20						
2-Hexanone	ND	0.20						
Dibromochloromethane	ND	0.20						

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/24/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK
Client Sample I.D.:	--
Date/Time Sampled:	-
Date/Time Analyzed:	7/24/26 7:39
QC Batch No.:	260724MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	0.20
Chlorobenzene	ND	0.20
Ethylbenzene	ND	0.20
p,&m-Xylene	ND	0.20
o-Xylene	ND	0.20
Styrene	ND	0.20
Bromoform	ND	0.20
1,1,2,2-Tetrachloroethane	ND	0.20
Benzyl Chloride	ND	0.20
4-Ethyl Toluene	ND	0.20
1,3,5-Trimethylbenzene	ND	0.20
1,2,4-Trimethylbenzene	ND	0.20
1,3-Dichlorobenzene	ND	0.20
1,4-Dichlorobenzene	ND	0.20
1,2-Dichlorobenzene	ND	0.20
1,2,4-Trichlorobenzene	ND	0.20
Hexachlorobutadiene	ND	0.20
1,3-Butadiene	ND	1.0
Isopropanol	ND	1.0
n-Hexane	ND	1.0
Ethyl Acetate	ND	1.0
Tetrahydrofuran	ND	1.0
Cyclohexane	ND	1.0
Heptane	ND	1.0
1,4-Dioxane	ND	1.0

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ **Date** 7/27/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 260724MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	7/24/26 7:39			7/24/26 6:22		7/24/26 7:01					
Analyst Initials:	VM/GD			VM/GD		VM/GD					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	**Result ppbv**	**RL ppbv**	**AMT. ppbv**	**Result ppbv**	**% Rec.**	**Result ppbv**	**% Rec.**	**RPD**	**Low %Rec**	**High %Rec**	**Max. RPD**
1,1-Dichloroethene	ND	0.20	10	10.8	108	10.6	106	1.4	70	130	30
Methylene Chloride	ND	0.20	10	10.2	102	10.0	100	2.0	70	130	30
Trichloroethene	ND	0.20	10	10.4	104	10.6	106	1.7	70	130	30
Toluene	ND	0.20	10	9.85	98	9.85	98	0.0	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	8.47	85	8.69	87	2.6	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date:** 7/27/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/24/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T072405-01		T072405-02					
Client Sample I.D.:	CV-113		CV-24122					
Date/Time Sampled:	7/24/26 9:55		7/24/26 9:45					
Date/Time Analyzed:	7/24/26 13:45		7/24/26 14:00					
QC Batch No.:	260724GC8A1		260724GC8A1					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**				
Carbon Dioxide	73	0.010	48	0.010				
Oxygen/Argon	1.3	0.50	0.53	0.50				
Nitrogen	4.9	1.0	2.0	1.0				
Methane	0.88	0.0010	50	0.0010				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7/27/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260724GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	7/24/26 12:47			7/24/26 13:16		7/24/26 13:31					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	10.2	102	9.62	96	5.8	70	130	30
Oxygen/Argon	ND	0.50	15	15.0	100	15.1	100	0.2	70	130	30
Nitrogen	ND	1.0	70	73.5	105	73.1	105	0.5	70	130	30
Methane	ND	0.0010	0.10	0.0973	96	0.0963	95	1.0	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 7/27/26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/24/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T072405-01			T072405-02								
Client Sample I.D.:	CV-113			CV-24122								
Date/Time Sampled:	7/24/26 9:55			7/24/26 9:45								
Date/Time Analyzed:	7/24/26 13:45			7/24/26 14:00								
QC Batch No.:	260724GC8A1			260724GC8A1								
Analyst Initials:	KD			KD								
Dilution Factor:	1.0			1.0								
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v						
Hydrogen	18	1.0	0.059	ND	1.0	0.059						

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 7/27/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260724GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	7/24/26 12:47				7/24/26 13:16		7/24/26 13:31					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	5.11	103	5.13	103	0.3	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 7/27/26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 07/24/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T072405-01		T072405-02					
Client Sample I.D.:	CV-113		CV-24122					
Date/Time Sampled:	7/24/26 9:55		7/24/26 9:45					
Date/Time Analyzed:	7/24/26 13:45		7/24/26 14:00					
QC Batch No.:	260724GC8A1		260724GC8A1					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv				
Carbon Monoxide	2,300	10	ND	10				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 7/31/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260724GC8A1
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	7/24/26 12:47			7/24/26 13:16		7/24/26 13:31					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,050	104	1,040	103	1.0	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 7/27/26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Table 2. Monthly LEA Selected Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Well Temp [°F]	Adj Well Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-108-52	7/1/2026 8:25:00 AM					0						AirTech Lab
CV-108-52	7/1/2026 8:25:00 AM						0					AirTech Lab; [User entered 0%]
CV-108-52	7/3/2026 7:30:23 AM	52.3	39.3	0.0	8.4			66.6	70.4	1.08	1.11	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Well (Watered In)
CV-108-52	7/3/2026 7:30:59 AM	56.2	41.0	0.0	2.8			70.7	71.4	1.00	0.66	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Well (Watered In)
CV-108-52	7/7/2026 10:18:34 AM	50.8	48.4	0.0	0.8			101.8	102.1	-2.55	-2.55	Valve Adjustment:NSPS/EG CAC,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
CV-108-52	7/28/2026 1:43:12 PM	48.9	47.9	0.1	3.1			106.9	107.0	0.94	0.38	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Valve 100% Open,Surging Liquid in Header
CV-108-52	7/28/2026 1:45:22 PM	49.5	47.9	0.2	2.4			107.2	107.2	1.39	1.51	Valve Adjustment:Positive Static Press.,Valve 100% Open
CV-113	7/8/2026 1:51:43 PM	0.1	2.0	20.9	77.0			100.5	102.7	-2.65	-0.68	Valve Adjustment:High O2,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-113	7/9/2026 7:25:00 AM					0						AirTech Lab
CV-113	7/9/2026 7:25:00 AM						640					AirTech Lab; [User entered 0.064%]
CV-113	7/24/2026 9:55:00 AM					2300						Air Tech Lab
CV-113	7/24/2026 9:55:00 AM						180000					Air Tech Lab; [User entered 18%]
CV-113	7/29/2026 2:25:40 PM	25.9	54.1	5.4	14.6			99.2	99.2	-1.16	-1.15	Valve Adjustment:High O2,Barely Open
CV-114	7/6/2026 9:16:05 AM	4.0	74.6	0.0	21.4			189.8	190.1	-4.30	-4.13	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-114	7/6/2026 9:20:00 AM					3180						AtmAA
CV-114	7/6/2026 9:20:00 AM						144400					AtmAA; [User entered 14.44%]
CV-114	7/9/2026 7:20:00 AM					2200						AirTech Lab
CV-114	7/9/2026 7:20:00 AM						170000					AirTech Lab; [User entered 17%]
CV-114	7/13/2026 9:10:49 AM	0.8	78.3	0.0	20.9			191.1	191.1	-1.31	-1.17	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-114	7/15/2026 2:14:50 PM	17.2	71.4	0.0	11.4			184.5	184.5	-0.25	-0.28	Valve Adjustment:No Flow Measurement,High Temp
CV-114	7/20/2026 9:07:38 AM	3.1	73.7	0.0	23.2			190.4	190.8	-5.25	-5.28	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-114	7/27/2026 8:59:32 AM	5.2	78.1	0.0	16.7			190.6	190.7	-5.45	-5.73	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open

Table 2. Monthly LEA Selected Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Well Temp [°F]	Adj Well Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-1532A	7/1/2026 8:30:00 AM					0						AirTech Lab
CV-1532A	7/1/2026 8:30:00 AM						0					AirTech Lab; [User entered 0%]
CV-1532A	7/13/2026 9:37:04 AM	0.4	8.8	18.5	72.3			84.6	84.6	-6.19	-5.06	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-1532A	7/13/2026 9:39:23 AM	0.5	8.5	18.6	72.4			84.5	84.5	-3.37	-3.37	Valve Adjustment:NSPS/EG CAI,High O2
CV-1532A	7/28/2026 1:50:16 PM	0.3	41.7	7.8	50.2			102.5	102.3	-5.40	-6.08	Valve Adjustment:High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-1535	7/3/2026 7:26:47 AM	48.2	48.4	0.0	3.4			109.7	110.3	-0.94	-0.83	Valve Adjustment:Decreased Flow/Vacuum
CV-1535	7/13/2026 9:30:00 AM					44						AirTech Lab
CV-1535	7/13/2026 9:30:00 AM						5000					AirTech Lab; [User entered 0.50%]
CV-1535	7/20/2026 10:25:32 AM	47.2	49.5	0.0	3.3			122.3	122.5	-1.21	-1.23	Valve Adjustment:Barely Open
CV-1902A	7/1/2026 9:35:00 AM					37.3						AtmAA
CV-1902A	7/1/2026 9:37:01 AM	5.4	73.0	0.0	21.6			172.3	159.9	-4.42	-4.46	Valve Adjustment:No Flow Measurement,High Temp
CV-1902A	7/8/2026 8:49:36 AM	17.2	72.3	0.0	10.5			175.0	174.8	-5.73	-5.39	Valve Adjustment:No Flow Measurement,High Temp
CV-1902A	7/15/2026 8:30:50 AM	11.7	75.3	0.0	13.0			176.1	176.4	-5.05	-5.05	Valve Adjustment:No Flow Measurement,High Temp
CV-1902A	7/22/2026 9:15:53 AM	14.3	71.3	0.0	14.4			177.9	178.7	-4.72	-4.72	Valve Adjustment:No Flow Measurement,High Temp
CV-1902A	7/29/2026 8:19:09 AM	8.3	76.7	0.0	15.0			185.5	185.6	-2.33	-2.24	Valve Adjustment:No Flow Measurement,High Temp
CV-2001	7/2/2026 8:10:00 AM					300						AirTech Lab
CV-2001	7/2/2026 8:10:00 AM						24000					AirTech Lab; [User entered 2.4%]
CV-2001	7/3/2026 7:59:18 AM	6.7	57.0	7.6	28.7			80.2	81.3	-9.40	-9.06	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Surging Liquid in Header
CV-2001	7/3/2026 8:00:50 AM	6.1	54.6	7.5	31.8			81.3	81.6	-9.06	-9.06	Valve Adjustment:NSPS/EG CAI,High O2,Surging Liquid in Header;Well Comment:Unable to adjust safely
CV-2001	7/20/2026 12:55:49 PM	7.5	67.7	3.4	21.4			116.5	116.5	-0.90	-0.82	Valve Adjustment:Barely Open
CV-2002	7/1/2026 1:41:30 PM	42.0	58.0	0.0	0.0			183.3	183.2	-5.73	-5.19	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	7/1/2026 1:42:00 PM					248						AtmAA

Table 2. Monthly LEA Selected Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Well Temp [°F]	Adj Well Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2002	7/8/2026 7:50:00 AM					2200						AirTech Lab
CV-2002	7/8/2026 7:50:00 AM						120000					AirTech Lab; [User entered 12%]
CV-2002	7/8/2026 10:23:36 AM	45.4	54.6	0.0	0.0			184.2	184.3	-4.83	-4.97	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	7/15/2026 9:58:01 AM	34.4	65.4	0.1	0.1			186.8	186.8	-4.56	-4.38	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	7/20/2026 1:06:48 PM	11.7	69.7	0.1	18.5			186.8	186.8	-4.41	-3.96	Valve Adjustment:High Temp,Barely Open
CV-2002	7/22/2026 1:55:59 PM	35.8	64.1	0.0	0.1			186.5	186.5	-5.52	-5.56	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	7/22/2026 1:56:42 PM	33.9	66.1	0.0	0.0			186.6	186.6	-4.31	-4.28	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	7/29/2026 9:25:08 AM	20.0	74.9	0.0	5.1			186.7	186.9	-0.57	-0.61	Valve Adjustment:No Flow Measurement,High O2
CV-2007	7/6/2026 1:47:52 PM	8.9	33.5	10.1	47.5			130.2	130.4	-0.66	-0.66	Valve Adjustment:High O2
CV-2007	7/23/2026 9:41:53 AM	15.9	49.3	2.3	32.5			158.0	156.5	-2.33	-1.05	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open
CV-2007	7/23/2026 9:42:37 AM	16.3	48.1	2.4	33.2			156.2	156.1	-0.95	-0.94	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2007	7/27/2026 1:17:09 PM	20.6	67.9	0.0	11.5			144.1	144.8	-1.43	-1.38	Valve Adjustment:High Temp
CV-2301	7/6/2026 7:20:00 AM					0						AirTech Lab
CV-2301	7/6/2026 7:20:00 AM						0					AirTech Lab; [User entered 0%]
CV-2301	7/8/2026 1:12:10 PM	9.0	75.4	0.0	15.6			174.0	186.5	1.72	-1.55	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-2301	7/8/2026 1:12:44 PM	8.4	79.8	0.0	11.8			186.3	187.2	-1.76	-1.82	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	7/16/2026 10:42:12 AM	21.9	52.5	5.1	20.5			186.5	185.5	-3.52	-2.48	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2301	7/16/2026 10:43:49 AM	20.3	63.8	2.7	13.2			185.9	185.8	-1.86	-1.85	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	7/22/2026 2:20:36 PM	8.6	73.6	1.2	16.6			187.1	188.1	-0.76	-3.36	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2301	7/22/2026 2:22:28 PM	10.9	63.2	5.5	20.4			187.6	188.1	-2.82	-2.75	Valve Adjustment:No Flow Measurement,High Temp,High O2
CV-2301	7/22/2026 2:22:54 PM	11.1	62.8	5.0	21.1			188.1	188.4	-2.81	-2.81	Valve Adjustment:No Flow Measurement,High Temp,High O2

Table 2. Monthly LEA Selected Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Well Temp [°F]	Adj Well Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2301	7/30/2026 9:33:34 AM	24.4	41.9	7.7	26.0			185.1	178.4	-4.96	-1.27	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,High O2,Decreased Flow/Vacuum
CV-2301	7/30/2026 9:37:13 AM	14.7	74.1	1.3	9.9			179.9	179.6	-0.91	-0.89	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-2302	7/6/2026 7:25:00 AM					0						AirTech Lab
CV-2302	7/6/2026 7:25:00 AM						0					AirTech Lab; [User entered 0%]
CV-2302	7/6/2026 3:38:27 PM	42.7	48.0	0.9	8.4			114.6	114.9	-11.44	-11.40	
CV-2302	7/16/2026 2:45:08 PM	43.8	44.5	0.7	11.0			126.7	127.1	-12.38	-11.78	Valve Adjustment:Valve 100% Open
CV-2303	7/6/2026 7:25:00 AM					0						AirTech Lab
CV-2303	7/6/2026 7:35:00 AM						790					AirTech Lab; [User entered 0.079%]
CV-2303	7/7/2026 9:55:00 AM					2500						AtmAA
CV-2303	7/7/2026 9:55:00 AM						153100					AtmAA; [User entered 15.31%]
CV-2303	7/7/2026 10:01:32 AM	15.9	75.0	0.0	9.1			192.4	192.6	1.10	0.83	Valve Adjustment:No Flow Measurement,High Temp,High O2,Valve 100% Open
CV-2303	7/7/2026 10:02:07 AM	17.3	74.6	0.0	8.1			192.1	192.5	1.01	0.96	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open
CV-2303	7/14/2026 9:45:01 AM	12.8	70.1	0.0	17.1			190.9	191.3	-1.40	-1.43	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Valve 100% Open
CV-2303	7/21/2026 8:52:07 AM	14.9	72.3	0.0	12.8			187.9	188.2	-2.24	-2.63	Valve Adjustment:No Flow Measurement,High Temp
CV-2303	7/28/2026 9:21:10 AM	11.6	73.3	0.2	14.9			191.2	191.2	-1.28	-1.42	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2305	7/2/2026 8:53:00 AM					1580						AtmAA
CV-2305	7/2/2026 8:57:50 AM	21.5	60.7	0.0	17.8			156.7	156.1	-12.13	-6.74	Valve Adjustment:High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2305	7/2/2026 8:59:04 AM	22.1	45.6	0.0	32.3			156.4	156.5	-6.54	-6.50	Valve Adjustment:High Temp
CV-2305	7/9/2026 9:46:08 AM	32.9	64.8	0.0	2.3			153.9	154.1	-2.00	-1.99	Valve Comment:Pump was on while reading was taken;Valve Adjustment:High Temp
CV-2305	7/13/2026 8:40:00 AM					2000						AirTech Lab
CV-2305	7/13/2026 8:40:00 AM						86000					AirTech Lab; [User entered 8.6%]
CV-2305	7/16/2026 9:44:14 AM	34.1	65.9	0.0	0.0			155.5	155.5	-2.03	-3.90	Valve Comment:Pump on;Valve Adjustment:High Temp,Increased Flow/Vacuum

Table 2. Monthly LEA Selected Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Gas Temp [°F]	Adj Gas Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2305	7/16/2026 9:44:37 AM	33.7	66.2	0.0	0.1			155.5	155.5	-4.32	-4.33	Valve Adjustment:High Temp
CV-2305	7/30/2026 8:45:53 AM	18.2	74.7	0.0	7.1			155.8	155.8	-4.56	-4.57	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2312	7/6/2026 7:45:00 AM					520						AirTech Lab
CV-2312	7/6/2026 7:45:00 AM						33000					AirTech Lab; [User entered 3.3%]
CV-2312	7/8/2026 1:43:27 PM	8.4	76.6	0.0	15.0			168.0	167.9	-4.67	-4.26	Valve Adjustment:No Flow Measurement,High Temp
CV-2312	7/16/2026 10:16:27 AM	7.9	78.3	0.0	13.8			168.1	168.0	-3.17	-3.76	Valve Adjustment:No Flow Measurement,High Temp
CV-2312	7/17/2026 10:06:51 AM	49.6	43.2	0.1	7.1			111.0	111.8	-0.48	-0.48	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2312	7/21/2026 1:16:32 PM	12.4	75.7	0.0	11.9			167.4	167.9	-1.62	-0.30	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In)
CV-2312	7/22/2026 2:54:17 PM	11.8	68.9	0.0	19.3			167.2	167.4	-2.57	-2.51	Valve Adjustment:No Flow Measurement,High Temp
CV-2312	7/29/2026 1:17:39 PM	40.0	60.0	0.0	0.0			167.5	167.6	-40.15	-38.84	Valve Adjustment:No Flow Measurement,High Temp
CV-2314	7/6/2026 2:20:01 PM	12.0	74.6	1.5	11.9			180.6	182.4	-11.86	-5.61	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-2314	7/6/2026 2:21:36 PM	12.7	78.9	0.5	7.9			182.5	182.6	-5.53	-5.56	Valve Adjustment:High Temp
CV-2314	7/6/2026 2:40:00 PM					4400						AtmAA
CV-2314	7/6/2026 2:40:00 PM						117700					AtmAA; [User entered 11.77%]
CV-2314	7/13/2026 7:30:00 AM					3200						AirTech Lab
CV-2314	7/13/2026 7:30:00 AM						140000					AirTech Lab; [User entered 14%]
CV-2314	7/15/2026 1:37:00 PM	11.4	80.6	0.0	8.0			186.1	185.1	0.88	-8.23	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum
CV-2314	7/15/2026 1:37:27 PM	11.9	81.0	0.0	7.1			185.2	185.1	-7.75	-7.93	Valve Adjustment:High Temp
CV-2315	7/6/2026 8:00:00 AM					370						AirTech Lab
CV-2315	7/6/2026 8:00:00 AM						27000					AirTech Lab; [User entered 2.7%]
CV-2315	7/6/2026 1:44:39 PM	23.6	71.8	0.0	4.6			174.5	175.0	-5.90	-5.94	Valve Adjustment:No Flow Measurement,High Temp
CV-2315	7/6/2026 2:05:00 PM					2800						AtmAA
CV-2315	7/6/2026 2:05:00 PM						105600					AtmAA; [User entered 10.56%]
CV-2315	7/13/2026 1:19:42 PM	9.7	71.4	0.0	18.9			186.1	186.0	-3.81	-3.87	Valve Adjustment:No Flow Measurement,High Temp

Table 2. Monthly LEA Selected Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2315	7/20/2026 10:06:54 AM	27.9	68.3	0.0	3.8			185.4	185.6	-4.86	-4.68	Valve Adjustment:No Flow Measurement,High Temp
CV-2315	7/27/2026 1:32:19 PM	24.7	69.5	0.0	5.8			188.0	188.0	-2.80	-2.47	Valve Adjustment:No Flow Measurement,High Temp
CV-2328	7/8/2026 1:55:59 PM	51.5	48.5	0.0	0.0			142.8	142.7	-7.92	-7.90	Valve Adjustment:High Temp
CV-2328	7/13/2026 7:10:00 AM					350						AirTech Lab
CV-2328	7/13/2026 7:10:00 AM						42000					AirTech Lab; [User entered 4.2%]
CV-2328	7/29/2026 9:48:41 AM	39.2	57.5	0.0	3.3			146.7	146.3	-7.09	-6.75	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-2328	7/29/2026 9:49:48 AM	39.1	58.1	0.0	2.8			146.5	146.3	-6.75	-6.75	Valve Adjustment:High Temp
CV-2328	7/29/2026 12:49:23 PM	54.1	45.9	0.0	0.0			147.3	147.3	-5.05	-5.05	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2333	7/6/2026 9:09:15 AM	3.5	75.3	0.0	21.2			186.6	186.7	-5.47	-5.92	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2333	7/6/2026 9:15:00 AM					3760						AtmAA
CV-2333	7/6/2026 9:15:00 AM						164200					AtmAA; [User entered 16.42%]
CV-2333	7/9/2026 7:15:00 AM					3500						AirTech Lab
CV-2333	7/9/2026 7:15:00 AM						200000					AirTech Lab; [User entered 20%]
CV-2333	7/13/2026 9:03:07 AM	0.3	77.6	0.0	22.1			198.7	198.6	1.55	1.54	Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Increased Flow/Vacuum,Valve 100% Open
CV-2333	7/13/2026 9:04:45 AM	0.4	80.2	0.0	19.4			198.7	198.7	1.48	1.48	Valve Comment:Pneumatic pump installed;Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open;Well Condition:Pnumatic Pump Installed
CV-2333	7/15/2026 2:28:17 PM	14.7	69.4	0.0	15.9			193.1	193.0	0.76	0.85	Valve Adjustment:No Flow Measurement,High Temp
CV-2333	7/16/2026 4:31:46 PM	0.9	85.2	0.1	13.8			182.8	182.3	-6.51	-5.76	
CV-2333	7/16/2026 4:33:26 PM	0.8	86.5	0.1	12.6			185.2	185.2	-3.19	-5.47	
CV-2333	7/20/2026 9:04:08 AM	1.9	76.7	0.6	20.8			195.8	196.0	-1.42	-1.13	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2333	7/27/2026 8:55:36 AM	2.3	77.3	0.0	20.4			186.7	186.8	-7.08	-7.41	Valve Adjustment:No Flow Measurement,High Temp
CV-2334	7/9/2026 7:30:00 AM					1900						AirTech Lab

Table 2. Monthly LEA Selected Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Well Temp [°F]	Adj Well Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2334	7/9/2026 7:30:00 AM						110000					AirTech Lab; [User entered 11%]
CV-2334	7/13/2026 8:41:10 AM	7.5	84.8	0.0	7.7			128.6	128.6	-9.18	-8.93	Valve Adjustment:Audible Flow,Reduce Sys. Vac. - Flare Down
CV-2334	7/23/2026 1:50:21 PM	5.3	79.1	0.0	15.6			136.8	137.0	-2.35	-1.83	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2334	7/23/2026 1:52:54 PM	4.8	80.7	0.0	14.5			137.0	137.0	-1.72	-1.72	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2337	7/1/2026 9:53:55 AM	10.8	73.3	0.0	15.9			151.5	151.4	-4.03	-4.05	Valve Comment:Pump pumping upon arrival;Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2337	7/1/2026 9:57:00 AM					86.5						AtmAA
CV-2337	7/8/2026 8:58:06 AM	29.8	70.2	0.0	0.0			146.5	146.7	-7.41	-7.75	Valve Adjustment:No Flow Measurement,High Temp
CV-2337	7/15/2026 8:40:46 AM	19.2	48.0	7.8	25.0			153.0	153.0	-6.07	-4.68	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2337	7/15/2026 8:42:31 AM	22.3	61.5	4.2	12.0			152.9	152.9	-3.54	-3.49	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Barely Open
CV-2337	7/22/2026 9:26:17 AM	23.0	77.0	0.0	0.0			153.8	153.5	0.34	-2.18	Valve Adjustment:High Temp,Increased Flow/Vacuum
CV-2337	7/22/2026 9:26:54 AM	21.2	77.3	0.0	1.5			153.4	153.4	-2.23	-2.25	Valve Adjustment:High Temp
CV-2337	7/29/2026 8:26:34 AM	17.0	73.8	0.0	9.2			152.6	152.7	-5.36	-5.39	Valve Adjustment:High Temp
CV-2341	7/7/2026 9:50:03 AM	10.8	70.2	0.5	18.5			102.1	102.4	-2.71	-2.70	Valve Adjustment:Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
CV-2341	7/16/2026 2:21:29 PM	11.8	62.9	0.6	24.7			111.7	111.1	-2.84	-1.28	Valve Adjustment:Decreased Flow/Vacuum
CV-2344	7/1/2026 8:20:00 AM					0						AirTech Lab
CV-2344	7/1/2026 8:20:00 AM						0					AirTech Lab; [User entered 0%]
CV-2344	7/1/2026 10:08:37 AM	11.1	78.6	0.0	10.3			154.7	155.3	-3.75	-3.80	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2344	7/1/2026 10:17:00 AM					1830						AtmAA
CV-2344	7/8/2026 9:24:38 AM	30.5	69.5	0.0	0.0			161.0	161.1	-4.13	-4.13	Valve Adjustment:No Flow Measurement,High Temp
CV-2344	7/15/2026 9:07:22 AM	26.5	73.1	0.0	0.4			160.8	161.3	-2.79	-2.80	Valve Adjustment:No Flow Measurement,High Temp
CV-2344	7/22/2026 10:47:52 AM	23.9	71.6	0.0	4.5			156.8	157.2	-1.20	-1.16	Valve Adjustment:No Flow Measurement,High Temp

Table 2. Monthly LEA Selected Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Well Temp [°F]	Adj Well Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2344	7/29/2026 8:48:14 AM	20.4	74.2	0.0	5.4			153.2	153.6	-5.06	-5.05	Valve Adjustment:No Flow Measurement,High O2
CV-2345	7/1/2026 8:51:00 AM					430						AirTech Lab
CV-2345	7/1/2026 8:51:00 AM						27000					AirTech Lab; [User entered 2.7%]
CV-2345	7/3/2026 9:09:08 AM	18.3	74.5	0.0	7.2			127.1	127.2	-3.86	-3.85	Valve Adjustment:Audible Flow;Well Condition:Lorentz Pump Installed
CV-2345	7/28/2026 1:17:28 PM	19.6	65.7	0.4	14.3			132.8	133.1	-4.44	-4.44	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-2345	7/28/2026 1:18:30 PM	19.4	66.5	0.4	13.7			133.2	133.0	-4.44	-4.43	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-2346	7/1/2026 8:10:00 AM					2300						AirTech Lab
CV-2346	7/1/2026 8:10:00 AM						170000					AirTech Lab; [User entered 17%]
CV-2346	7/1/2026 10:04:09 AM	7.9	74.2	0.0	17.9			189.0	189.0	-6.39	-6.07	Valve Adjustment:No Flow Measurement,High Temp
CV-2346	7/1/2026 10:10:00 AM					954						AtmAA
CV-2346	7/8/2026 9:18:20 AM	21.9	74.5	0.0	3.6			186.5	186.0	-7.32	-7.56	Valve Adjustment:No Flow Measurement,High Temp
CV-2346	7/15/2026 9:03:00 AM	20.0	72.3	0.0	7.7			185.4	185.7	-3.54	-3.82	Valve Adjustment:No Flow Measurement,High Temp
CV-2346	7/22/2026 10:45:05 AM	18.9	72.2	0.0	8.9			186.3	186.6	-4.89	-4.98	Valve Adjustment:No Flow Measurement,High Temp
CV-2346	7/29/2026 8:44:01 AM	12.4	76.6	0.0	11.0			185.4	185.3	-11.07	-10.87	Valve Adjustment:No Flow Measurement,High Temp
CV-2347	7/1/2026 8:05:00 AM					790						AirTech Lab
CV-2347	7/1/2026 8:05:00 AM						50000					AirTech Lab; [User entered 5.0%]
CV-2347	7/3/2026 8:56:09 AM	15.6	66.4	0.0	18.0			119.7	120.3	-3.65	-3.63	
CV-2347	7/28/2026 9:44:36 AM	18.3	50.5	0.3	30.9			123.2	123.6	-5.40	-5.40	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2348	7/1/2026 8:00:00 AM					400						AirTech Lab
CV-2348	7/1/2026 8:00:00 AM						28000					AirTech Lab; [User entered 2.8%]
CV-2348	7/3/2026 8:54:05 AM	19.6	55.1	0.0	25.3			81.6	81.9	-9.27	-9.27	Well Comment:unable to adjust safely
CV-2348	7/30/2026 12:27:31 PM	20.6	48.5	0.5	30.4			132.3	132.3	-11.35	-11.38	Valve Adjustment:NSPS/EG CAI,High Temp;Well Comment:Unable to reach system

Table 2. Monthly LEA Selected Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2348	7/30/2026 12:28:19 PM	19.7	49.3	0.5	30.5			132.3	132.3	-11.34	-11.36	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2349	7/1/2026 1:45:13 PM	41.0	58.9	0.1	0.0			178.9	179.6	-4.98	-5.52	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2349	7/1/2026 1:50:00 PM					178						AtmAA
CV-2349	7/2/2026 8:20:00 AM					1200						AirTech Lab
CV-2349	7/2/2026 8:20:00 AM						85000					AirTech Lab; [User entered 8.5%]
CV-2349	7/8/2026 10:21:09 AM	24.4	69.6	0.0	6.0			176.5	176.5	-4.38	-4.72	Valve Adjustment:No Flow Measurement,High Temp
CV-2349	7/15/2026 10:06:40 AM	16.1	65.6	2.1	16.2			181.3	181.3	-5.40	-5.77	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2349	7/22/2026 1:58:42 PM	26.9	58.8	14.3	0.0			166.1	170.4	-4.33	-4.93	Valve Adjustment:No Flow Measurement,High Temp
CV-2349	7/29/2026 9:20:49 AM	19.0	75.6	0.0	5.4			180.0	180.4	-6.46	-6.07	Valve Adjustment:No Flow Measurement,High Temp
CV-2350	7/3/2026 7:38:14 AM	4.9	78.1	0.0	17.0			110.9	111.2	-12.71	-11.72	Valve Adjustment:Decreased Flow/Vacuum
CV-2350	7/8/2026 7:40:00 AM					3200						AirTech Lab
CV-2350	7/20/2026 1:03:58 PM	4.1	72.8	0.1	23.0			118.8	118.8	-8.64	-9.01	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2351	7/1/2026 8:40:00 AM					0						AirTech Lab
CV-2351	7/1/2026 8:40:00 AM						600					AirTech Lab; [User entered 0.060%]
CV-2351	7/7/2026 10:34:21 AM	0.2	1.0	21.0	77.8			99.8	100.0	-1.37	-1.21	Valve Adjustment:NSPS/EG CAI,High O2,Reduce Sys. Vac. - Flare Down
CV-2351	7/7/2026 10:35:02 AM	0.2	1.2	20.7	77.9			100.3	100.4	-1.21	-0.96	Valve Adjustment:NSPS/EG CAI,High O2,Reduce Sys. Vac. - Flare Down
CV-2351	7/28/2026 2:17:08 PM	1.6	1.1	20.9	76.4			103.0	103.3	-1.42	-1.16	Valve Adjustment:Plugged/Pinched Suspected
CV-2352	7/2/2026 7:50:00 AM					0						AirTech Lab
CV-2352	7/2/2026 7:50:00 AM						0					AirTech Lab; [User entered 0%]
CV-2352	7/2/2026 1:09:51 PM	1.4	42.0	11.1	45.5			166.4	166.8	9.52	-0.48	Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Positive Static Press.
CV-2352	7/2/2026 1:12:12 PM	1.3	39.9	11.5	47.3			168.4	166.2	-0.50	-0.68	Valve Adjustment:NSPS/EG CAI,High Temp,High O2
CV-2352	7/2/2026 2:00:00 PM					1380						AtmAA
CV-2352	7/2/2026 2:16:24 PM	12.9	70.0	1.2	15.9			162.1	168.7	-0.48	-0.47	Valve Comment:O2 in well due to pump pushing air;Valve Adjustment:No Flow Measurement,High Temp

Table 2. Monthly LEA Selected Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Well Temp [°F]	Adj Well Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2352	7/9/2026 10:28:26 AM	9.8	43.7	7.7	38.8			182.9	182.7	-1.54	-1.69	Valve Comment:Found pump pushing air;Valve Adjustment:No Flow Measurement,High Temp,High O2,Surging Liquid in Well (Watered In)
CV-2352	7/9/2026 10:30:58 AM	12.8	65.6	1.5	20.1			180.1	180.8	-1.45	-1.34	Valve Adjustment:No Flow Measurement,High Temp
CV-2352	7/15/2026 9:35:39 AM	19.8	70.7	1.0	8.5			146.1	146.6	-1.72	-1.95	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2352	7/22/2026 10:59:08 AM	21.0	67.4	0.0	11.6			187.7	187.7	-1.61	-1.26	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2352	7/29/2026 9:05:16 AM	13.3	68.6	0.0	18.1			141.5	141.7	-2.78	-2.61	Valve Adjustment:No Flow Measurement,High Temp
CV-2353-PLR	7/1/2026 10:24:09 AM	12.8	68.5	0.0	18.7			122.9	123.5	-0.23	-0.17	Valve Adjustment:No Flow Measurement,High Temp
CV-2353-PLR	7/8/2026 8:10:00 AM					710						AirTech Lab
CV-2353-PLR	7/8/2026 8:10:00 AM						220000					AirTech Lab; [User entered 22%]
CV-2353-PLR	7/28/2026 2:07:19 PM	3.2	75.8	0.2	20.8			133.4	132.5	-7.60	-7.64	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2353-PLR	7/28/2026 2:11:24 PM	6.4	65.9	2.5	25.2			131.3	131.5	-7.43	-7.45	Valve Adjustment:High Temp
CV-2354	7/1/2026 1:52:06 PM	23.4	76.6	0.0	0.0			181.6	181.7	-1.56	-2.09	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2354	7/1/2026 2:04:00 PM					774						AtmAA
CV-2354	7/8/2026 8:00:00 AM					2000						AirTech Lab
CV-2354	7/8/2026 8:00:00 AM						170000					AirTech Lab; [User entered 17%]
CV-2354	7/8/2026 10:02:59 AM	28.1	71.9	0.0	0.0			186.6	186.6	-1.64	-1.62	Valve Adjustment:No Flow Measurement,High Temp
CV-2354	7/15/2026 10:23:28 AM	20.7	70.3	0.0	9.0			177.1	177.0	-4.18	-4.59	Valve Adjustment:No Flow Measurement,High Temp
CV-2354	7/22/2026 2:04:50 PM	19.4	68.6	0.0	12.0			172.2	172.5	-4.62	-4.53	Valve Adjustment:No Flow Measurement,High Temp
CV-2354	7/29/2026 9:14:57 AM	21.0	71.2	0.0	7.8			185.8	185.9	-3.52	-3.52	Valve Adjustment:No Flow Measurement,High Temp
CV-24002	7/1/2026 9:27:49 AM	41.7	43.7	0.3	14.3			108.8	109.8	-3.26	-3.26	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24002	7/16/2026 10:43:22 AM	41.8	51.9	0.0	6.3			114.3	114.4	-2.97	-2.97	

Table 2. Monthly LEA Selected Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Well Temp [°F]	Adj Well Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24003	7/1/2026 9:12:42 AM	35.0	49.2	0.0	15.8			122.5	121.8	-1.86	-1.56	Valve Adjustment:Decreased Flow/Vacuum
CV-24003	7/16/2026 10:34:14 AM	38.6	53.6	0.0	7.8			124.9	124.9	-1.04	-1.03	Valve Adjustment:Barely Open
CV-24007	7/1/2026 10:24:33 AM	25.6	43.2	2.9	28.3			139.2	139.3	-1.76	-1.42	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24007	7/16/2026 10:21:13 AM	21.1	50.5	3.3	25.1			140.7	140.7	-1.00	-0.99	Valve Adjustment:High O2,Barely Open
CV-24017	7/2/2026 9:54:07 AM	6.0	74.8	0.1	19.1			187.2	188.1	-9.38	-4.79	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24017	7/7/2026 9:07:06 AM	17.6	70.8	0.0	11.6			193.3	193.5	-1.83	-1.93	Valve Adjustment:No Flow Measurement,High Temp
CV-24017	7/7/2026 9:10:00 AM					2050						AtmAA
CV-24017	7/7/2026 9:10:00 AM						136100					AtmAA; [User entered 13.61%]
CV-24017	7/13/2026 9:00:00 AM					1600						AirTech Lab
CV-24017	7/13/2026 9:00:00 AM						180000					AirTech Lab; [User entered 18%]
CV-24017	7/14/2026 9:01:41 AM	10.6	73.6	0.0	15.8			191.4	190.2	-1.39	-3.17	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24017	7/14/2026 9:02:10 AM	9.7	69.2	0.0	21.1			189.9	189.7	-3.44	-3.42	Valve Adjustment:No Flow Measurement,High Temp
CV-24017	7/21/2026 8:34:08 AM	16.3	73.0	0.2	10.5			186.0	186.1	-4.43	-4.37	Valve Comment:Lorentz pump on while collecting reading;Valve Adjustment:No Flow Measurement,High Temp
CV-24017	7/28/2026 8:09:09 AM	22.6	68.8	0.4	8.2			185.9	185.7	-6.22	-6.23	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24049	7/6/2026 1:38:16 PM	13.3	74.1	0.0	12.6			185.1	185.3	-10.56	-10.60	Valve Adjustment:No Flow Measurement,High Temp
CV-24049	7/6/2026 4:50:00 PM					3480						AtmAA
CV-24049	7/6/2026 4:50:00 PM						118800					AtmAA; [User entered 11.88%]
CV-24049	7/13/2026 9:10:00 AM					1700						AirTech Lab
CV-24049	7/13/2026 9:10:00 AM						130000					AirTech Lab; [User entered 13%]
CV-24049	7/13/2026 1:14:21 PM	3.9	76.5	0.0	19.6			190.5	190.6	-8.90	-8.09	Valve Adjustment:No Flow Measurement,High Temp
CV-24049	7/20/2026 10:13:54 AM	18.2	70.1	0.0	11.7			187.5	187.4	-9.48	-8.26	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-24049	7/27/2026 1:26:59 PM	15.3	73.1	0.0	11.6			192.8	192.9	-5.39	-5.04	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed

Table 2. Monthly LEA Selected Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Well Temp [°F]	Adj Well Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24049	7/27/2026 1:30:09 PM	27.5	72.1	0.0	0.4			164.9	165.1	-7.96	-7.79	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24053	7/2/2026 2:21:41 PM	33.4	45.4	0.1	21.1			96.7	97.4	-5.68	-5.35	Valve Adjustment:Decreased Flow/Vacuum
CV-24053	7/10/2026 10:33:54 AM	33.5	45.1	0.2	21.2			102.7	102.7	-5.19	-4.55	Valve Adjustment:Decreased Flow/Vacuum
CV-24053	7/13/2026 7:15:00 AM					110						AirTech Lab
CV-24053	7/13/2026 7:15:00 AM						15000					AirTech Lab; [User entered 1.5%]
CV-24053	7/21/2026 1:39:10 PM	35.0	45.7	0.1	19.2			105.0	105.4	-8.22	-8.33	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24055	7/9/2026 3:17:18 PM	8.2	55.5	3.4	32.9			134.4	134.0	-0.64	-0.61	High Temp
CV-24055	7/9/2026 3:18:58 PM	8.1	56.5	3.4	32.0			134.0	134.1	-0.66	-0.66	
CV-24055	7/23/2026 9:27:41 AM	7.7	50.5	2.8	39.0			141.2	141.3	-0.89	-0.80	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24062	7/6/2026 8:20:00 AM					190						AirTech Lab
CV-24062	7/6/2026 8:20:00 AM						27000					AirTech Lab; [User entered 2.7%]
CV-24062	7/8/2026 2:06:55 PM	36.4	63.6	0.0	0.0			180.0	179.3	1.42	-5.21	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24062	7/8/2026 2:08:53 PM	40.5	59.5	0.0	0.0			179.4	180.0	-6.37	-6.34	Valve Adjustment:No Flow Measurement,High Temp
CV-24062	7/14/2026 1:31:33 PM	42.7	57.3	0.0	0.0			181.4	180.9	-4.58	-4.55	Valve Adjustment:No Flow Measurement,High Temp
CV-24062	7/21/2026 1:00:32 PM	43.6	56.4	0.0	0.0			181.2	181.1	-6.36	-6.36	Valve Adjustment:No Flow Measurement,High Temp
CV-24062	7/29/2026 12:56:17 PM	38.3	61.7	0.0	0.0			177.2	176.6	-6.82	-7.08	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24063	7/6/2026 8:15:00 AM					420						AirTech Lab
CV-24063	7/6/2026 8:15:00 AM						37000					AirTech Lab; [User entered 3.7%]
CV-24063	7/8/2026 2:23:32 PM	27.6	72.4	0.0	0.0			185.2	185.2	-9.44	-9.56	Valve Adjustment:No Flow Measurement,High Temp
CV-24063	7/14/2026 1:24:44 PM	26.1	69.6	0.0	4.3			184.8	184.6	-7.05	-6.87	Valve Adjustment:No Flow Measurement,High Temp
CV-24063	7/21/2026 12:54:42 PM	40.5	59.4	0.0	0.1			183.9	184.0	-5.63	-5.69	Valve Adjustment:No Flow Measurement,High Temp

Table 2. Monthly LEA Selected Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Well Temp [°F]	Adj Well Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24063	7/29/2026 1:02:30 PM	37.3	62.7	0.0	0.0			181.3	181.6	-7.08	-6.78	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24064	7/6/2026 8:10:00 AM					410						AirTech Lab
CV-24064	7/6/2026 8:10:00 AM						34000					AirTech Lab; [User entered 3.4%]
CV-24064	7/6/2026 2:33:01 PM	13.2	78.0	0.0	8.8			190.6	190.6	-13.35	-12.47	Valve Adjustment:No Flow Measurement,High Temp
CV-24064	7/6/2026 2:50:00 PM					1780						AtmAA
CV-24064	7/6/2026 2:50:00 PM						114300					AtmAA; [User entered 11.43%]
CV-24064	7/15/2026 1:24:20 PM	10.9	80.1	0.0	9.0			190.6	190.5	-11.21	-11.23	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-24064	7/28/2026 1:23:22 PM	19.2	75.9	0.0	4.9			191.1	191.2	-9.35	-10.34	Valve Adjustment:No Flow Measurement,High Temp
CV-24065-TP1	7/6/2026 9:55:14 AM	29.3	69.8	0.9	0.0			101.7	101.7	-0.53	-0.53	Valve Adjustment:Barely Open
CV-24065-TP1	7/13/2026 8:45:00 AM					100						AirTech Lab
CV-24065-TP1	7/13/2026 8:45:00 AM						3300					AirTech Lab; [User entered 0.33%]
CV-24065-TP1	7/20/2026 9:11:35 AM	11.6	35.1	3.8	49.5			122.8	123.3	-8.02	-7.96	
CV-24066	7/3/2026 7:16:42 AM	19.9	44.8	0.0	35.3			95.1	96.3	-1.86	-1.85	
CV-24066	7/13/2026 9:20:00 AM					170						AirTech Lab
CV-24066	7/13/2026 9:20:00 AM						23000					AirTech Lab; [User entered 2.3%]
CV-24066	7/30/2026 12:31:20 PM	19.9	44.4	0.0	35.7			108.3	108.4	-1.84	-1.84	
CV-24069	7/6/2026 8:30:00 AM					58						AirTech Lab
CV-24069	7/6/2026 8:30:00 AM						8600					AirTech Lab; [User entered 0.86%]
CV-24069	7/8/2026 10:32:20 AM	18.4	65.3	0.6	15.7			126.8	127.0	-1.36	-1.35	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-24069	7/16/2026 2:59:51 PM	20.6	43.5	1.6	34.3			120.0	120.1	-2.08	-2.20	Valve Adjustment:Barely Open
CV-24070	7/6/2026 8:35:00 AM					1000						AirTech Lab
CV-24070	7/6/2026 8:35:00 AM						86000					AirTech Lab; [User entered 8.6%]
CV-24070	7/6/2026 3:45:09 PM	10.1	81.1	0.0	8.8			147.9	147.9	-0.21	-0.22	High Temp
CV-24070	7/6/2026 3:46:17 PM	10.5	83.3	0.0	6.2			147.9	147.9	-0.31	-0.30	
CV-24070	7/13/2026 2:59:42 PM	22.8	75.3	0.0	1.9			150.0	150.8	0.89	-2.66	Valve Adjustment:High Temp,Increased Flow/Vacuum
CV-24070	7/13/2026 3:00:43 PM	21.6	74.2	0.0	4.2			151.1		-3.02		Valve Adjustment:High Temp

Table 2. Monthly LEA Selected Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Well Temp [°F]	Adj Well Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24070	7/16/2026 3:03:30 PM	22.7	69.8	0.0	7.5			148.4	148.5	-6.03	-5.39	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24070	7/30/2026 9:51:32 AM	44.7	55.3	0.0	0.0			146.3	146.2	-6.40	-6.40	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24071	7/6/2026 3:18:36 PM	33.1	61.2	0.0	5.7			131.8	131.4	-3.83	-2.20	High Temp
CV-24071	7/6/2026 3:19:46 PM	32.6	64.7	0.0	2.7			131.3	131.3	-2.09	-2.09	
CV-24071	7/8/2026 8:25:00 AM					570						AirTech Lab
CV-24071	7/8/2026 8:25:00 AM						83000					AirTech Lab; [User entered 8.3%]
CV-24071	7/17/2026 7:53:19 AM	31.4	63.1	0.0	5.5			132.9	132.4	-3.03	-2.07	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24071	7/17/2026 7:54:08 AM	31.5	60.1	0.0	8.4			132.2	132.3	-1.89	-1.88	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24075-TP1	7/2/2026 9:39:29 AM	0.8	74.7	2.0	22.5			185.6	185.7	-15.39	-15.41	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:Hard pipped
CV-24075-TP1	7/6/2026 3:01:23 PM	20.1	75.2	0.4	4.3			185.0	185.1	-12.25	-4.09	Valve Adjustment:No Flow Measurement,High Temp
CV-24075-TP1	7/6/2026 3:02:24 PM	18.8	76.0	0.2	5.0			185.2	185.3	-4.54	-4.54	Valve Adjustment:No Flow Measurement,High Temp
CV-24075-TP1	7/6/2026 3:05:00 PM					2100						AtmAA
CV-24075-TP1	7/6/2026 3:05:00 PM						109900					AtmAA; [User entered 10.99%]
CV-24075-TP1	7/15/2026 1:29:30 PM	22.1	73.0	0.0	4.9			188.6	188.6	4.36	-2.71	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24075-TP1	7/15/2026 1:30:02 PM	24.1	75.9	0.0	0.0			188.7	188.7	-2.91	-2.95	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-24075-TP1	7/28/2026 1:27:30 PM	29.3	70.6	0.1	0.0			187.0	187.0	-6.67	-6.53	Valve Adjustment:No Flow Measurement,High Temp
CV-24077	7/1/2026 8:48:35 AM	17.2	63.7	0.0	19.1			150.5	150.7	-4.91	-4.96	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24077	7/1/2026 8:50:00 AM					1.89						AtmAA
CV-24077	7/8/2026 8:28:44 AM	20.8	60.8	0.0	18.4			150.6	150.6	-5.39	-5.39	Valve Adjustment:No Flow Measurement,High Temp

Table 2. Monthly LEA Selected Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Well Temp [°F]	Adj Well Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24077	7/15/2026 8:09:17 AM	26.5	61.1	0.0	12.4			150.6	150.6	-4.91	-5.03	Valve Adjustment:No Flow Measurement,High Temp
CV-24077	7/20/2026 9:49:45 AM	15.8	61.7	0.0	22.5			151.2	152.0	-5.81	-2.02	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open
CV-24077	7/22/2026 8:54:23 AM	18.4	76.5	0.0	5.1			159.4	159.2	-0.35	-1.89	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24077	7/22/2026 8:54:59 AM	17.4	80.5	0.0	2.1			159.1	158.9	-2.28	-2.29	Valve Adjustment:No Flow Measurement,High Temp
CV-24077	7/29/2026 8:07:00 AM	19.9	65.6	0.0	14.5			152.4	152.4	-3.92	-3.81	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24079-TP8	7/7/2026 9:15:40 AM	32.1	44.9	0.0	23.0			146.8	144.6	-3.33	-3.12	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down
CV-24079-TP8	7/7/2026 9:16:34 AM	31.6	46.5	0.0	21.9			144.7	143.6	-2.57	-2.50	Valve Adjustment:NSPS/EG CAI,High Temp,Reduce Sys. Vac. - Flare Down
CV-24079-TP8	7/13/2026 7:31:55 AM	36.7	43.0	0.0	20.3			121.3	102.5	-3.01	-1.24	Valve Adjustment:Decreased Flow/Vacuum;Well Comment:pump deactivated.;Well Condition:Lorentz Pump Installed
CV-24079-TP8	7/13/2026 7:42:05 AM	32.0	46.8	0.0	21.2			100.1	94.4	-1.45	-1.44	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Plugged/Pinched Suspected;Well Condition:Lorentz Pump Installed
CV-24079-TP8	7/29/2026 9:09:16 AM	5.5	50.4	9.1	35.0			86.9	88.1	-0.58	-0.54	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24079-TP8	7/29/2026 9:15:45 AM	2.4	81.3	2.1	14.2			91.6	92.7	-0.72	-0.71	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24082	7/6/2026 3:07:02 PM	42.4	55.3	0.0	2.3			125.3	125.3	-9.24	-8.14	
CV-24082	7/17/2026 8:13:54 AM	40.6	55.8	0.0	3.6			127.6	127.2	-8.46	-6.72	Valve Adjustment:Decreased Flow/Vacuum
CV-24083	7/2/2026 1:14:35 PM	14.9	77.1	0.0	8.0			154.4	153.8	1.03	1.03	Valve Adjustment:No Flow Measurement,High Temp
CV-24083	7/2/2026 1:15:00 PM					1750						AtmAA
CV-24083	7/6/2026 3:15:00 PM					1540						AtmAA
CV-24083	7/6/2026 3:15:00 PM						96000					AtmAA; [User entered 9.6%]

Table 2. Monthly LEA Selected Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Well Temp [°F]	Adj Well Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24083	7/6/2026 3:17:19 PM	16.4	72.3	0.0	11.3			152.6	154.3	1.21	-2.86	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24083	7/6/2026 3:18:50 PM	19.1	77.3	0.0	3.6			155.3	155.6	-3.62	-3.74	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-24083	7/6/2026 3:19:25 PM	21.0	77.5	0.0	1.5			155.7	155.7	-3.74	-3.74	Valve Adjustment:No Flow Measurement,High Temp
CV-24083	7/16/2026 10:27:18 AM	37.4	61.7	0.0	0.9			162.0	161.9	-3.85	-3.87	Valve Adjustment:No Flow Measurement,High Temp
CV-24083	7/17/2026 8:09:38 AM	26.8	64.4	0.0	8.8			155.0	150.6	-5.12	-0.42	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24083	7/21/2026 1:36:33 PM	24.4	73.4	0.0	2.2			158.8	163.3	1.61	-1.94	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24083	7/21/2026 1:37:02 PM	23.2	76.8	0.0	0.0			162.8	162.7	-1.89	-2.10	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24083	7/30/2026 10:16:56 AM	41.8	58.2	0.0	0.0			156.3	156.4	-4.62	-4.68	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24084-TP1	7/8/2026 1:30:26 PM	12.7	76.8	0.0	10.5			183.4	183.7	-7.16	-8.02	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24084-TP1	7/16/2026 10:24:02 AM	7.3	76.5	0.0	16.2			183.7	183.9	-5.16	-5.52	Valve Adjustment:No Flow Measurement,High Temp
CV-24084-TP1	7/21/2026 1:27:39 PM	8.9	74.7	0.0	16.4			184.6	184.4	-5.59	-6.02	Valve Adjustment:No Flow Measurement,High Temp
CV-24084-TP1	7/29/2026 1:25:41 PM	10.0	81.0	0.0	9.0			184.4	184.6	-8.46	-8.13	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24088	7/6/2026 12:48:09 PM	45.8	52.5	0.0	1.7			120.4	120.2	-5.86	-5.56	
CV-24088	7/17/2026 8:32:34 AM	46.5	47.1	0.0	6.4			123.6	124.4	-4.38	-3.97	Valve Adjustment:Decreased Flow/Vacuum
CV-24095	7/1/2026 1:48:38 PM	25.8	74.2	0.0	0.0			184.1	184.1	-4.94	-4.75	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-24095	7/1/2026 1:56:00 PM					27.6						AtmAA
CV-24095	7/2/2026 8:25:00 AM					1700						AirTech Lab
CV-24095	7/2/2026 8:25:00 AM						120000					AirTech Lab; [User entered 12%]
CV-24095	7/8/2026 10:05:22 AM	25.3	68.7	0.0	6.0			182.1	182.2	-5.30	-5.88	Valve Adjustment:No Flow Measurement,High Temp

Table 2. Monthly LEA Selected Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Well Temp [°F]	Adj Well Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24095	7/15/2026 10:11:43 AM	13.7	33.3	10.5	42.5			182.7	182.7	-5.79	-4.77	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24095	7/15/2026 10:16:56 AM	12.8	67.6	0.1	19.5			182.1	182.5	-6.40	-6.74	Valve Adjustment:No Flow Measurement,High Temp
CV-24095	7/22/2026 2:01:45 PM	14.0	74.3	0.0	11.7			189.7	189.7	-0.51	-2.28	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24095	7/22/2026 2:02:24 PM	14.3	76.2	0.0	9.5			189.7	189.7	-2.15	-2.14	Valve Adjustment:No Flow Measurement,High Temp
CV-24095	7/29/2026 9:17:33 AM	21.8	73.4	0.0	4.8			188.7	188.7	-3.49	-3.61	Valve Adjustment:No Flow Measurement,High Temp
CV-24096	7/9/2026 8:45:58 AM	1.0	9.6	16.7	72.7			82.7	83.3	0.00	-0.01	Valve Adjustment:NSPS/EG CAI,High O2,Positive Static Press.;Well Comment:No system vacuum
CV-24096	7/9/2026 8:47:11 AM	1.1	9.8	16.4	72.7			83.6	83.7	0.00	0.00	
CV-24096	7/20/2026 1:13:02 PM	4.8	10.6	17.7	66.9			106.1	106.1	-0.01	-0.02	Valve Adjustment:Barely Open
CV-24097	7/8/2026 10:34:37 AM	64.7	35.0	0.3	0.0			97.0	97.2	-5.39	-4.85	Valve Adjustment:No Flow Measurement,Decreased Flow/Vacuum
CV-24097	7/8/2026 10:35:24 AM	64.8	35.1	0.1	0.0			97.4	97.4	-4.82	-4.86	Valve Adjustment:No Flow Measurement
CV-24097	7/20/2026 1:16:13 PM	45.1	42.5	1.2	11.2			112.7	112.8	-6.73	-6.73	Valve Adjustment:Barely Open
CV-24098	7/3/2026 7:42:01 AM	39.9	45.2	2.6	12.3			69.3	70.1	-11.95	-9.88	Valve Adjustment:Decreased Flow/Vacuum
CV-24098	7/30/2026 10:47:53 AM	0.1	2.4	19.0	78.5			93.4	93.5	-0.06	-0.05	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open
CV-24098	7/30/2026 10:48:29 AM	0.1	1.9	18.9	79.1			94.0	94.4	-0.02	-0.02	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open
CV-24099	7/3/2026 7:45:50 AM	20.3	63.2	2.0	14.5			70.5	72.1	-1.76	-0.69	Valve Adjustment:Decreased Flow/Vacuum
CV-24099	7/20/2026 12:59:25 PM	16.9	64.5	2.2	16.4			108.2	108.2	-0.74	-0.73	Valve Adjustment:Barely Open
CV-24100	7/1/2026 1:28:47 PM	40.4	59.5	0.1	0.0			149.9	151.4	-8.43	-8.47	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24100	7/1/2026 1:30:00 PM					42.7						AtmAA
CV-24100	7/2/2026 8:05:00 AM					12						AirTech Lab
CV-24100	7/2/2026 8:05:00 AM						3300					AirTech Lab; [User entered 0.33%]
CV-24100	7/3/2026 8:08:58 AM	21.2	75.8	0.0	3.0			148.9	143.2	-9.06	-1.11	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24100	7/3/2026 8:10:35 AM	20.3	77.5	0.0	2.2			143.5	142.5	-1.22	-1.29	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header
CV-24100	7/20/2026 12:53:13 PM	21.3	68.4	0.0	10.3			153.1	154.1	-0.55	-0.47	Valve Adjustment:High Temp,Barely Open

Table 2. Monthly LEA Selected Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24100	7/29/2026 9:35:55 AM	28.3	71.7	0.0	0.0			155.7	155.9	-1.01	-0.99	Valve Adjustment:No Flow Measurement,High Temp
CV-24101	7/2/2026 8:00:00 AM					0						AirTech Lab
CV-24101	7/2/2026 8:00:00 AM						0					AirTech Lab; [User entered 0%]
CV-24101	7/3/2026 8:15:20 AM	47.0	50.2	0.3	2.5			102.5	99.2	-12.42	-11.41	Valve Adjustment:Decreased Flow/Vacuum
CV-24101	7/20/2026 10:36:02 AM	44.5	48.1	1.1	6.3			107.7	108.1	-11.96	-11.29	
CV-24102	7/3/2026 8:37:34 AM	42.3	55.5	0.0	2.2			95.7	96.1	-0.90	-0.80	
CV-24102	7/28/2026 10:17:39 AM	42.9	54.8	0.3	2.0			105.1	105.2	-0.28	-0.28	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24120	7/8/2026 1:58:27 PM	2.2	20.1	15.7	62.0			100.8	100.8	-7.10	-7.06	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24120	7/13/2026 10:05:00 AM					150						AirTech Lab
CV-24120	7/13/2026 10:05:00 AM						11000					AirTech Lab; [User entered 1.1%]
CV-24120	7/31/2026 9:43:24 AM	6.5	29.7	13.8	50.0			106.6	106.6	-0.02	-0.02	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-24120	7/31/2026 10:24:29 AM	9.4	58.3	4.4	27.9			130.2	130.3	-12.32	-11.29	Valve Adjustment:No Flow Measurement,Surging Liquid in Header
CV-24121	7/8/2026 1:56:01 PM	0.7	1.6	20.3	77.4			102.6	102.4	-7.12	-7.06	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24121	7/9/2026 7:50:00 AM					2100						AirTech Lab
CV-24121	7/9/2026 7:50:00 AM						160000					AirTech Lab; [User entered 16%]
CV-24121	7/27/2026 1:27:57 PM	0.5	2.9	20.3	76.3			104.2	104.2	-6.13	-6.13	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-24122	7/6/2026 9:28:47 AM	0.0	0.2	20.6	79.2			97.0	97.6	-0.04	-0.05	
CV-24122	7/6/2026 9:40:00 AM	20.3	25.4	11.7	42.6			100.2	101.9	-8.02	-4.71	Valve Adjustment:NSPS/EG CAI
CV-24122	7/9/2026 7:55:00 AM					0						AirTech Lab
CV-24122	7/9/2026 7:55:00 AM						1700					AirTech Lab; [User entered 0.17%]
CV-24122	7/23/2026 2:13:49 PM	46.0	54.0	0.0	0.0			109.3	109.4	3.69	3.61	Valve Comment:line watered in;Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Header,Surging Liquid in Well (Watered In)

Table 2. Monthly LEA Selected Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Well Temp [°F]	Adj Well Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24122	7/23/2026 2:14:07 PM	46.9	51.6	0.0	1.5			109.3	109.5	4.18	4.02	Valve Adjustment:Positive Static Press.
CV-24122	7/24/2026 9:45:00 AM						0					AirTech Lab; [User entered 0%]
CV-24123	7/8/2026 3:18:05 PM	45.4	54.6	0.0	0.0			116.7	117.2	-4.98	-4.69	
CV-24123	7/22/2026 10:18:09 AM	43.9	51.0	0.0	5.1			118.4	118.5	-3.03	-3.02	
CV-24125-TP2	7/13/2026 10:25:00 AM					0						AirTech Lab
CV-24125-TP2	7/13/2026 10:25:00 AM						2700					AirTech Lab; [User entered 0.27%]
CV-24125-TP2	7/13/2026 12:00:38 PM	39.0	57.7	0.5	2.8			119.8	121.2	-13.82	-13.53	Valve Adjustment:Audible Flow,Valve 100% Open,Decreased Flow/Vacuum
CV-24125-TP2	7/23/2026 2:22:19 PM	38.3	56.0	0.3	5.4			121.5	121.3	-5.98	-5.35	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24126	7/2/2026 10:44:12 AM	5.7	53.0	0.9	40.4			195.1	195.2	-3.76	-3.73	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24126	7/6/2026 1:33:35 PM	11.8	74.8	0.0	13.4			187.6	188.1	-6.17	-6.17	Valve Adjustment:High Temp
CV-24126	7/6/2026 1:40:00 PM					4470						AtmAA
CV-24126	7/6/2026 1:40:00 PM						165200					AtmAA; [User entered 16.52%]
CV-24126	7/13/2026 1:44:32 PM	2.9	72.0	1.0	24.1			189.7	189.6	-5.43	-5.05	Valve Adjustment:No Flow Measurement,High Temp
CV-24126	7/13/2026 1:45:04 PM	3.1	73.7	0.3	22.9			189.9	190.0	-5.73	-5.40	Valve Adjustment:No Flow Measurement,High Temp
CV-24126	7/20/2026 10:21:14 AM	29.2	65.3	0.0	5.5			189.6	189.4	-3.60	-3.22	Valve Adjustment:High Temp
CV-24126	7/27/2026 1:12:06 PM	22.1	68.6	0.0	9.3			193.7	193.9	-0.24	-0.20	Valve Adjustment:High Temp
CV-24127	7/6/2026 1:30:07 PM	14.2	72.9	0.0	12.9			168.3	169.3	-5.54	-5.77	Valve Adjustment:No Flow Measurement,High Temp
CV-24127	7/6/2026 1:35:00 PM					4520						AtmAA
CV-24127	7/6/2026 1:35:00 PM						154300					AtmAA; [User entered 15.43%]
CV-24127	7/13/2026 1:04:22 PM	8.2	73.0	0.0	18.8			172.5	173.2	-5.10	-5.10	Valve Adjustment:No Flow Measurement,High Temp
CV-24127	7/20/2026 10:25:41 AM	29.0	66.8	0.0	4.2			171.9	172.0	-1.49	-1.48	Valve Adjustment:No Flow Measurement,High Temp
CV-24127	7/27/2026 1:06:12 PM	32.9	64.1	0.0	3.0			166.0	167.1	-2.42	-2.53	Valve Adjustment:No Flow Measurement,High Temp
CV-24128	7/9/2026 7:35:00 AM					1600						AirTech Lab
CV-24128	7/9/2026 7:35:00 AM						72000					AirTech Lab; [User entered 7.2%]

Table 2. Monthly LEA Selected Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Gas Temp [°F]	Adj Gas Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24128	7/9/2026 8:21:11 AM	21.7	61.4	0.2	16.7			123.0	123.1	-0.73	-0.74	Valve Adjustment:Barely Open
CV-24128	7/9/2026 3:03:21 PM	23.3	64.4	0.6	11.7			125.2	125.3	-0.88	-0.88	
CV-24128	7/23/2026 1:56:14 PM	17.8	68.6	0.0	13.6			123.7	123.8	-0.57	-0.52	Valve Adjustment:Barely Open
CV-24134-TP1	7/6/2026 1:27:42 PM	40.5	59.5	0.0	0.0			154.9	154.8	-3.04	-3.01	Valve Adjustment:No Flow Measurement,High Temp
CV-24134-TP1	7/6/2026 1:30:00 PM					2770						AtmAA
CV-24134-TP1	7/6/2026 1:30:00 PM						108000					AtmAA; [User entered 10.8%]
CV-24134-TP1	7/13/2026 1:01:45 PM	39.8	54.6	0.0	5.6			149.3	148.9	-5.62	-5.48	Valve Adjustment:No Flow Measurement,High Temp
CV-24134-TP1	7/20/2026 10:29:58 AM	37.7	62.3	0.0	0.0			155.2	155.2	-2.61	-2.01	Valve Adjustment:No Flow Measurement,High Temp
CV-24134-TP1	7/27/2026 1:04:09 PM	39.4	60.6	0.0	0.0			153.4	154.1	-1.16	-1.18	Valve Adjustment:No Flow Measurement,High Temp
CV-24138	7/2/2026 8:35:00 AM					0						AirTech Lab
CV-24138	7/2/2026 8:35:00 AM						2400					AirTech Lab; [User entered 0.24%]
CV-24138	7/9/2026 9:09:04 AM	1.5	0.7	18.2	79.6			103.1	102.8	-3.98	-4.28	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed
CV-24138	7/9/2026 9:10:39 AM	1.5	0.9	18.1	79.5			102.0	101.6	-4.06	-4.38	
CV-24138	7/30/2026 10:59:43 AM	2.5	66.1	2.2	29.2			120.0	120.0	-2.85	-2.62	
CV-24138	7/30/2026 11:01:03 AM	2.5	65.7	2.1	29.7			119.4	119.2	-1.77	-1.52	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-24139	7/1/2026 1:59:05 PM	20.5	74.1	0.1	5.3			158.3	158.7	-4.83	-5.45	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24139	7/1/2026 2:10:00 PM					466						AtmAA
CV-24139	7/8/2026 9:55:13 AM	22.6	65.2	0.8	11.4			168.8	169.3	-5.03	-3.65	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24139	7/8/2026 9:56:32 AM	24.2	66.0	0.6	9.2			169.1	169.0	-3.75	-3.77	Valve Adjustment:No Flow Measurement,High Temp
CV-24139	7/14/2026 7:15:00 AM					300						AirTech Lab
CV-24139	7/14/2026 7:15:00 AM						94000					AirTech Lab; [User entered 9.4%]
CV-24139	7/15/2026 9:45:13 AM	13.7	2.2	19.4	64.7			114.7	113.4	-5.22	-2.81	Valve Comment:Pump not working;Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum,Barely Open

Table 2. Monthly LEA Selected Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24139	7/15/2026 9:46:47 AM	11.9	0.9	19.7	67.5			111.8	111.3	-2.63	-2.74	Valve Adjustment:No Flow Measurement,High Temp
CV-24139	7/30/2026 11:03:32 AM	3.3	68.4	0.6	27.7			156.3	156.6	-5.58	-5.29	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24139	7/30/2026 11:04:14 AM	3.3	79.7	0.8	16.2			156.7	157.0	-5.67	-5.67	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24140	7/1/2026 8:50:00 AM					0						AirTech Lab
CV-24140	7/1/2026 8:50:00 AM						0					AirTech Lab; [User entered 0%]
CV-24140	7/1/2026 2:08:43 PM	16.5	72.4	0.1	11.0			147.5	146.8	-3.82	-4.25	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24140	7/1/2026 2:17:00 PM					1190						AtmAA
CV-24140	7/8/2026 9:47:46 AM	16.9	66.2	0.7	16.2			147.2	147.9	-4.30	-3.70	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24140	7/8/2026 9:49:23 AM	16.5	68.9	0.3	14.3			148.2	148.3	-3.64	-3.80	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24140	7/15/2026 9:39:54 AM	21.6	68.1	0.4	9.9			161.2	161.4	-3.36	-3.34	Valve Adjustment:No Flow Measurement,High Temp
CV-24140	7/22/2026 11:04:15 AM	18.8	69.3	0.6	11.3			137.4	138.0	-2.59	-2.98	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24140	7/22/2026 11:04:39 AM	18.6	69.0	0.4	12.0			139.7	139.9	-2.62	-2.36	Valve Adjustment:No Flow Measurement,High Temp
CV-24141	7/2/2026 7:55:00 AM					0						AirTech Lab
CV-24141	7/2/2026 7:55:00 AM						820					AirTech Lab; [User entered 0.082%]
CV-24141	7/2/2026 12:59:12 PM	24.3	37.1	3.4	35.2			90.7	90.7	-0.24	-0.50	Valve Adjustment:Increased Flow/Vacuum,Valve 100% Open
CV-24141	7/14/2026 8:50:53 AM	0.7	1.4	19.4	78.5			91.2	91.2	-0.64	-0.62	Valve Adjustment:NSPS/EG CAI,High O2,Surging Liquid in Well (Watered In)
CV-24141	7/14/2026 8:51:58 AM	0.7	1.4	19.3	78.6			91.1	91.1	-0.55	-0.51	Valve Adjustment:NSPS/EG CAI,High O2,Valve 100% Closed,Surging Liquid in Well (Watered In)
CV-24141	7/28/2026 2:19:35 PM	31.5	31.7	4.9	31.9			107.2	107.2	-0.92	-0.59	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24142	7/2/2026 8:30:00 AM					570						AirTech Lab
CV-24142	7/2/2026 8:30:00 AM						88000					AirTech Lab; [User entered 8.8%]
CV-24142	7/9/2026 8:59:51 AM	8.3	43.9	8.7	39.1			133.8	132.7	-1.53	-1.54	Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Decreased Flow/Vacuum,Surging Liquid in Well (Watered In)

Table 2. Monthly LEA Selected Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Gas Temp [°F]	Adj Gas Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24142	7/9/2026 9:01:16 AM	5.6	36.4	11.2	46.8			133.7	133.9	-1.66	-1.68	
CV-24142	7/30/2026 10:56:47 AM	2.3	59.9	3.2	34.6			151.7	151.9	-1.42	-1.36	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24142	7/30/2026 10:57:39 AM	2.6	61.7	2.6	33.1			152.9	153.4	-1.17	-1.07	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24143	7/1/2026 8:35:00 AM					230						AirTech Lab
CV-24143	7/1/2026 8:35:00 AM						33000					AirTech Lab; [User entered 3.3%]
CV-24143	7/1/2026 10:34:22 AM	10.5	57.8	5.7	26.0			81.1	81.3	-0.47	-0.17	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High O2,Decreased Flow/Vacuum,Barely Open;Well Condition:Pnumatic Pump Installed
CV-24143	7/1/2026 10:37:17 AM	11.4	56.1	5.4	27.1			81.4	81.4	-0.34	-0.36	Valve Adjustment:No Flow Measurement,High O2
CV-24144	7/8/2026 10:38:46 AM	70.5	29.5	0.0	0.0			112.0	111.7	-3.66	-3.73	Valve Adjustment:No Flow Measurement
CV-24144	7/20/2026 1:19:01 PM	51.7	41.7	0.1	6.5			110.0	110.0	-4.36	-4.36	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-99	7/9/2026 7:45:00 AM					0						AirTech Lab
CV-99	7/9/2026 7:45:00 AM						0					AirTech Lab; [User entered 0%]
CV-99	7/14/2026 1:09:14 PM	43.2	52.0	0.1	4.7			102.3	103.7	-11.63	-11.55	Valve Adjustment:Barely Open
CV-99	7/23/2026 2:19:12 PM	20.1	31.0	11.1	37.8			108.9	109.2	-6.40	-5.56	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-99	7/23/2026 2:19:57 PM	19.1	30.9	11.7	38.3			109.4	109.4	-5.89	-6.14	Valve Adjustment:NSPS/EG CAI,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1770N	7/1/2026 9:15:45 AM	32.9	60.4	0.0	6.7			99.9	100.0	-0.97	-0.94	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1770N	7/16/2026 10:37:30 AM	32.4	61.3	0.0	6.3			111.3	111.3	-0.78	-0.77	Valve Adjustment:Barely Open
H-2165W	7/3/2026 8:04:21 AM	19.3	77.9	0.0	2.8			139.7	135.2	-1.05	-0.52	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header
H-2165W	7/3/2026 8:04:45 AM	19.3	78.4	0.0	2.3			134.7	134.4	-0.47	-0.49	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open,Surging Liquid in Header
H-2165W	7/8/2026 7:15:00 AM					670						AirTech Lab
H-2165W	7/8/2026 7:15:00 AM						53000					AirTech Lab; [User entered 5.3%]
H-2165W	7/20/2026 10:29:00 AM	12.5	71.1	0.2	16.2			132.6	132.6	-0.34	-0.14	NSPS/EG CAI,High Temp,

Table 2. Monthly LEA Selected Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
H-2165W	7/20/2026 10:31:25 AM	10.5	85.3	0.0	4.2			132.3	132.4	-0.15	-0.10	High Temp,NSPS/EG CAI,
H-2273W	7/3/2026 8:59:47 AM	20.9	53.8	0.0	25.3			124.5	120.2	-0.71	-0.58	Valve Adjustment:Decreased Flow/Vacuum
H-2273W	7/8/2026 7:30:00 AM					48						AirTech Lab
H-2273W	7/8/2026 7:30:00 AM						5400					AirTech Lab; [User entered 0.54%]
H-2273W	7/28/2026 9:48:03 AM	0.8	8.3	19.6	71.3			91.7	91.9	-0.51	-0.51	Valve Adjustment:High O2,Barely Open,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down,Plugged/Pinched Suspected

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
A-01	7/6/2026 7:46:40 AM	57.7	38.2	0.4	3.7			1.5	9.3
A-02	7/6/2026 7:57:43 AM	58.3	39.0	0.1	2.6			1.5	26.0
A-03	7/6/2026 8:00:34 AM	55.8	41.8	0.0	2.4			1.3	0.0
A-04	7/6/2026 8:05:04 AM	56.4	40.7	0.1	2.8			1.4	28.0
A-05	7/6/2026 8:09:36 AM	57.6	39.4	0.1	2.9			1.5	29.0
B-01	7/6/2026 9:13:17 AM	21.7	21.4	0.1	56.8			1.0	568.0
B-02R	7/6/2026 9:02:40 AM	27.6	21.9	0.2	50.3			1.3	251.5
B-02R	7/6/2026 9:18:34 AM	39.2	29.7	0.1	31.0			1.3	310.0
B-03R	7/6/2026 8:43:02 AM	29.9	26.1	0.1	43.9			1.1	439.0
B-05	7/6/2026 9:09:04 AM	27.3	27.3	0.2	45.2			1.0	226.0
B-06	7/28/2026 1:24:16 PM	30.5	26.4	0.0	43.1			1.2	0.0
B-07R	7/6/2026 8:24:41 AM	41.8	30.3	0.1	27.8			1.4	278.0
B-08	7/22/2026 1:56:26 PM	18.5	19.2	8.4	53.9			1.0	6.4
B-08	7/22/2026 3:13:28 PM	5.2	2.6	17.3	74.9			2.0	4.3
B-08	7/22/2026 3:16:37 PM	5.8	4.0	16.8	73.4			1.5	4.4
B-08	7/22/2026 3:19:24 PM	5.3	3.7	17.1	73.9			1.4	4.3
B-08	7/28/2026 1:11:23 PM	24.0	23.5	0.0	52.5			1.0	0.0
B-09	7/6/2026 8:21:46 AM	38.4	31.1	0.0	30.5			1.2	0.0
B-10	7/6/2026 8:16:35 AM	29.5	27.1	0.3	43.1			1.1	143.7
B-11	7/22/2026 1:36:25 PM	42.0	34.7	0.0	23.3			1.2	0.0
B-12	7/6/2026 8:37:40 AM	24.5	25.4	0.2	49.9			1.0	249.5
B-13	7/6/2026 8:28:38 AM	38.3	30.3	0.1	31.3			1.3	313.0
B-14	7/22/2026 1:41:43 PM	38.2	32.3	0.0	29.5			1.2	0.0
C-03	7/30/2026 9:18:29 AM	41.9	31.6	4.8	21.7			1.3	4.5
C-07	7/30/2026 9:46:54 AM	50.0	37.7	0.9	11.4			1.3	12.7
C-08	7/15/2026 1:59:25 PM	54.4	42.7	0.0	2.9			1.3	0.0
C-08	7/16/2026 1:29:17 PM	44.1	34.9	4.1	16.9			1.3	4.1
C-10	7/7/2026 11:57:57 AM	55.1	40.2	0.0	4.7			1.4	0.0
C-11	7/9/2026 11:58:12 AM	53.9	40.1	0.0	6.0			1.3	0.0
C-12	7/31/2026 9:52:23 AM	53.6	44.8	0.3	1.3			1.2	4.3
C-15	7/29/2026 2:09:12 PM	56.0	40.3	0.0	3.7			1.4	0.0
C-15	7/29/2026 2:11:26 PM	42.1	31.0	4.9	22.0			1.4	4.5
C-15	7/29/2026 3:08:37 PM	55.5	40.0	0.0	4.5			1.4	0.0
C-17B	7/22/2026 9:17:59 AM	53.7	37.2	0.1	9.0			1.4	90.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
C-17B	7/30/2026 10:53:56 AM	56.2	39.2	0.1	4.5			1.4	45.0
C-18	7/22/2026 9:31:11 AM	55.6	39.9	0.0	4.5			1.4	0.0
C-19	7/22/2026 9:28:11 AM	53.7	38.9	0.0	7.4			1.4	0.0
C-19	7/30/2026 10:37:45 AM	58.2	36.8	0.2	4.8			1.6	24.0
C-20	7/22/2026 9:25:28 AM	57.8	38.9	0.0	3.3			1.5	0.0
C-24	7/22/2026 9:23:30 AM	29.9	25.4	5.9	38.8			1.2	6.6
C-24	7/22/2026 9:25:48 AM	32.8	27.6	4.9	34.7			1.2	7.1
C-24	7/30/2026 10:47:49 AM	1.0	2.8	19.3	76.9			0.4	4.0
C-24	7/30/2026 10:48:42 AM	0.1	1.0	19.6	79.3			0.1	4.0
C-25	7/22/2026 9:07:22 AM	20.4	9.6	13.6	56.4			2.1	4.1
C-25	7/22/2026 9:07:58 AM	20.2	9.3	13.8	56.7			2.2	4.1
C-25	7/22/2026 9:12:41 AM	51.7	35.4	0.3	12.6			1.5	42.0
C-25	7/30/2026 10:57:08 AM	36.4	38.0	0.1	25.5			1.0	255.0
C-26	7/22/2026 9:06:07 AM	54.1	32.6	2.3	11.0			1.7	4.8
C-27	7/31/2026 8:10:51 AM	18.1	7.7	15.1	59.1			2.4	3.9
C-27	7/31/2026 8:11:55 AM	20.9	9.3	14.7	55.1			2.2	3.7
C-28	7/9/2026 11:53:17 AM	51.5	40.1	0.0	8.4			1.3	0.0
C-28	7/9/2026 11:54:12 AM	52.3	41.4	0.0	6.3			1.3	0.0
C-29	7/7/2026 11:54:36 AM	46.0	47.4	0.0	6.6			1.0	0.0
C-30	7/15/2026 2:11:09 PM	50.9	42.5	0.0	6.6			1.2	0.0
CV-02	7/6/2026 9:42:55 AM	27.9	27.9	0.0	44.2			1.0	0.0
CV-03	7/6/2026 9:37:03 AM	43.4	37.0	0.0	19.6			1.2	0.0
CV-04	7/6/2026 9:33:10 AM	42.0	38.2	0.1	19.7			1.1	197.0
CV-05	7/9/2026 10:12:25 AM	54.0	41.9	0.0	4.1			1.3	0.0
CV-05	7/16/2026 1:41:39 PM	42.1	35.8	4.3	17.8			1.2	4.1
CV-06	7/7/2026 12:17:10 PM	50.2	45.5	0.0	4.3			1.1	0.0
CV-108-52	7/1/2026 8:25:00 AM					0			
CV-108-52	7/1/2026 8:25:00 AM						0		
CV-108-52	7/3/2026 7:30:23 AM	52.3	39.3	0.0	8.4			1.3	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-108-52	7/3/2026 7:30:59 AM	56.2	41.0	0.0	2.8			1.4	0.0
CV-108-52	7/7/2026 10:18:34 AM	50.8	48.4	0.0	0.8			1.0	0.0
CV-108-52	7/28/2026 1:43:12 PM	48.9	47.9	0.1	3.1			1.0	31.0
CV-108-52	7/28/2026 1:45:22 PM	49.5	47.9	0.2	2.4			1.0	12.0
CV-113	7/8/2026 1:51:43 PM	0.1	2.0	20.9	77.0			0.1	3.7
CV-113	7/9/2026 7:25:00 AM					0			
CV-113	7/9/2026 7:25:00 AM						640		
CV-113	7/24/2026 9:55:00 AM					2300			
CV-113	7/24/2026 9:55:00 AM						180000		
CV-113	7/29/2026 2:25:40 PM	25.9	54.1	5.4	14.6			0.5	2.7
CV-114	7/6/2026 9:16:05 AM	4.0	74.6	0.0	21.4			0.1	0.0
CV-114	7/6/2026 9:20:00 AM					3180			
CV-114	7/6/2026 9:20:00 AM						144400		
CV-114	7/9/2026 7:20:00 AM					2200			
CV-114	7/9/2026 7:20:00 AM						170000		
CV-114	7/13/2026 9:10:49 AM	0.8	78.3	0.0	20.9			0.0	0.0
CV-114	7/13/2026 9:20:00 AM					3260			
CV-114	7/15/2026 2:14:50 PM	17.2	71.4	0.0	11.4			0.2	0.0
CV-114	7/20/2026 9:07:38 AM	3.1	73.7	0.0	23.2			0.0	0.0
CV-114	7/20/2026 9:10:00 AM					3070			
CV-114	7/27/2026 8:59:32 AM	5.2	78.1	0.0	16.7			0.1	0.0
CV-1424	7/2/2026 11:04:56 AM	52.0	41.6	0.0	6.4			1.3	0.0
CV-1424	7/21/2026 10:15:43 AM	49.9	39.4	0.0	10.7			1.3	0.0
CV-1532A	7/1/2026 8:30:00 AM					0			
CV-1532A	7/1/2026 8:30:00 AM						0		
CV-1532A	7/13/2026 9:37:04 AM	0.4	8.8	18.5	72.3			0.0	3.9
CV-1532A	7/13/2026 9:39:23 AM	0.5	8.5	18.6	72.4			0.1	3.9

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-1532A	7/28/2026 1:50:16 PM	0.3	41.7	7.8	50.2			0.0	6.4
CV-1534A-PL	7/13/2026 9:24:22 AM	2.2	80.0	0.3	17.5			0.0	58.3
CV-1534A-PL	7/28/2026 1:57:13 PM	3.0	65.6	3.8	27.6			0.0	7.3
CV-1535	7/3/2026 7:26:47 AM	48.2	48.4	0.0	3.4			1.0	0.0
CV-1535	7/13/2026 9:30:00 AM					44			
CV-1535	7/13/2026 9:30:00 AM						5000		
CV-1535	7/20/2026 10:25:32 AM	47.2	49.5	0.0	3.3			1.0	0.0
CV-1601D	7/1/2026 3:18:41 PM	45.1	46.4	0.2	8.3			1.0	41.5
CV-1601D	7/16/2026 2:02:26 PM	45.1	45.9	0.2	8.8			1.0	44.0
CV-1601S	7/1/2026 3:14:58 PM	45.3	48.0	0.0	6.7			0.9	0.0
CV-1601S	7/16/2026 2:00:37 PM	43.2	45.2	0.3	11.3			1.0	37.7
CV-1604	7/1/2026 10:22:08 AM	50.8	46.8	0.0	2.4			1.1	0.0
CV-1701D	7/6/2026 10:05:30 AM	8.0	69.6	0.0	22.4			0.1	0.0
CV-1701D	7/29/2026 10:38:22 AM						192000		
CV-1701D	7/29/2026 10:47:20 AM	8.8	55.5	2.3	7.8		25.6	0.2	3.4
CV-1701D	7/29/2026 10:50:04 AM	9.5	54.5	2.3	8.4		25.3	0.2	3.7
CV-1701D	7/29/2026 1:45:00 PM					3060			
CV-1701D	7/29/2026 2:13:12 PM	9.7	64.4	0.1	0.0		25.8	0.2	0.0
CV-1701D	7/29/2026 2:14:44 PM	9.3	63.2	0.9	1.1		25.5	0.1	1.2
CV-1701S	7/6/2026 9:59:53 AM	24.1	70.8	0.0	5.1			0.3	0.0
CV-1701S	7/6/2026 10:00:19 AM	24.7	69.4	0.0	5.9			0.4	0.0
CV-1701S	7/29/2026 11:07:45 AM						42000		
CV-1701S	7/29/2026 11:09:01 AM	25.2	66.8	0.0	0.4		7.6	0.4	0.0
CV-1701S	7/29/2026 11:10:07 AM	25.9	64.2	0.0	2.4		7.5	0.4	0.0
CV-1701S	7/29/2026 1:50:00 PM					338			
CV-1701S	7/29/2026 1:50:00 PM						55700		
CV-1901	7/1/2026 10:06:33 AM	19.8	68.3	0.1	11.8			0.3	118.0
CV-1901	7/16/2026 10:59:07 AM	16.0	69.1	0.0	14.9			0.2	0.0
CV-1902A	7/1/2026 9:35:00 AM					37.3			
CV-1902A	7/1/2026 9:37:01 AM	5.4	73.0	0.0	21.6			0.1	0.0
CV-1902A	7/8/2026 8:45:00 AM					901			
CV-1902A	7/8/2026 8:45:00 AM						158900		

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-1902A	7/8/2026 8:49:36 AM	17.2	72.3	0.0	10.5			0.2	0.0
CV-1902A	7/15/2026 8:30:00 AM					1030			
CV-1902A	7/15/2026 8:30:50 AM	11.7	75.3	0.0	13.0			0.2	0.0
CV-1902A	7/22/2026 9:15:53 AM	14.3	71.3	0.0	14.4			0.2	0.0
CV-1902A	7/29/2026 8:19:09 AM	8.3	76.7	0.0	15.0			0.1	0.0
CV-1905	7/7/2026 2:26:39 PM	54.1	44.8	0.0	1.1			1.2	0.0
CV-2001	7/2/2026 8:10:00 AM					300			
CV-2001	7/2/2026 8:10:00 AM						24000		
CV-2001	7/3/2026 7:59:18 AM	6.7	57.0	7.6	28.7			0.1	3.8
CV-2001	7/3/2026 8:00:50 AM	6.1	54.6	7.5	31.8			0.1	4.2
CV-2001	7/20/2026 12:55:49 PM	7.5	67.7	3.4	21.4			0.1	6.3
CV-2002	7/1/2026 1:41:30 PM	42.0	58.0	0.0	0.0			0.7	0.0
CV-2002	7/1/2026 1:42:00 PM					248			
CV-2002	7/8/2026 7:50:00 AM					2200			
CV-2002	7/8/2026 7:50:00 AM						120000		
CV-2002	7/8/2026 10:23:36 AM	45.4	54.6	0.0	0.0			0.8	0.0
CV-2002	7/8/2026 10:35:00 AM					3130			
CV-2002	7/8/2026 10:35:00 AM						103200		
CV-2002	7/15/2026 9:58:01 AM	34.4	65.4	0.1	0.1			0.5	1.0
CV-2002	7/15/2026 10:00:00 AM					3480			
CV-2002	7/20/2026 1:06:48 PM	11.7	69.7	0.1	18.5			0.2	185.0
CV-2002	7/22/2026 1:55:59 PM	35.8	64.1	0.0	0.1			0.6	0.0
CV-2002	7/22/2026 1:56:42 PM	33.9	66.1	0.0	0.0			0.5	0.0
CV-2002	7/29/2026 9:25:08 AM	20.0	74.9	0.0	5.1			0.3	0.0
CV-2003	7/3/2026 7:32:47 AM	23.2	63.6	0.0	13.2			0.4	0.0
CV-2003	7/3/2026 7:33:04 AM	20.9	68.6	0.0	10.5			0.3	0.0
CV-2003	7/7/2026 10:15:47 AM	18.5	73.4	0.0	8.1			0.3	0.0
CV-2003	7/28/2026 1:39:31 PM	48.0	50.6	0.3	1.1			0.9	3.7
CV-2003	7/28/2026 1:41:40 PM	49.1	48.7	0.1	2.1			1.0	21.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-2006	7/1/2026 9:44:51 AM	4.9	73.9	0.0	21.2			0.1	0.0
CV-2006	7/1/2026 9:50:00 AM					1970			
CV-2006	7/8/2026 8:55:00 AM					3360			
CV-2006	7/8/2026 8:55:00 AM						170100		
CV-2006	7/8/2026 8:55:07 AM	17.8	71.7	0.0	10.5			0.2	0.0
CV-2006	7/15/2026 8:37:09 AM	12.0	73.5	0.0	14.5			0.2	0.0
CV-2006	7/15/2026 8:40:00 AM					2820			
CV-2006	7/22/2026 9:20:15 AM	15.1	74.0	0.0	10.9			0.2	0.0
CV-2006	7/29/2026 8:24:09 AM	10.9	74.9	0.0	14.2			0.1	0.0
CV-2007	7/6/2026 1:47:52 PM	8.9	33.5	10.1	47.5			0.3	4.7
CV-2007	7/23/2026 9:41:53 AM	15.9	49.3	2.3	32.5			0.3	14.1
CV-2007	7/23/2026 9:42:37 AM	16.3	48.1	2.4	33.2			0.3	13.8
CV-2007	7/27/2026 1:17:09 PM	20.6	67.9	0.0	11.5			0.3	0.0
CV-2008	7/6/2026 2:08:20 PM	23.6	71.5	0.0	4.9			0.3	0.0
CV-2008	7/23/2026 9:23:46 AM	26.6	71.7	0.0	1.7			0.4	0.0
CV-2009	7/7/2026 10:02:25 AM	39.3	55.8	0.0	4.9			0.7	0.0
CV-2009	7/7/2026 10:03:44 AM	39.4	56.6	0.0	4.0			0.7	0.0
CV-2009A	7/14/2026 8:47:52 AM	18.6	65.7	0.0	15.7			0.3	0.0
CV-2009A	7/14/2026 8:48:35 AM	18.0	66.5	0.0	15.5			0.3	0.0
CV-2009A	7/14/2026 2:08:33 PM	43.0	57.0	0.0	0.0			0.8	0.0
CV-2009A	7/14/2026 2:10:00 PM					1210			
CV-2009A	7/20/2026 2:40:00 PM					993			
CV-2009A	7/20/2026 2:41:25 PM	32.9	62.7	0.0	4.4			0.5	0.0
CV-2009A	7/20/2026 2:41:51 PM	34.1	65.3	0.0	0.6			0.5	0.0
CV-2009A	7/29/2026 10:20:52 AM	35.7	61.7	0.0	2.6			0.6	0.0
CV-2010	7/6/2026 9:15:47 AM	45.8	49.6	0.0	4.6			0.9	0.0
CV-2010A	7/6/2026 8:59:57 AM	45.7	47.7	0.0	6.6			1.0	0.0
CV-2010A	7/6/2026 9:01:10 AM	45.2	48.4	0.0	6.4			0.9	0.0
CV-2010A	7/6/2026 9:03:59 AM	46.3	47.7	0.0	6.0			1.0	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-2011	7/6/2026 9:30:09 AM	51.5	42.5	0.0	6.0			1.2	0.0
CV-2011A	7/2/2026 11:29:15 AM	19.6	44.9	4.3	31.2			0.4	7.3
CV-2011A	7/9/2026 8:54:58 AM	25.5	57.1	0.0	17.4			0.4	0.0
CV-2011A	7/9/2026 8:55:33 AM	24.2	51.8	0.0	24.0			0.5	0.0
CV-2011A	7/9/2026 9:00:00 AM					380			
CV-2011A	7/9/2026 9:00:00 AM						201800		
CV-2011A	7/16/2026 9:11:56 AM	41.7	48.0	0.0	10.3			0.9	0.0
CV-2011A	7/16/2026 9:15:00 AM					799			
CV-2011A	7/22/2026 2:38:29 PM	46.7	49.0	0.0	4.3			1.0	0.0
CV-2011A	7/30/2026 1:03:33 PM	47.2	52.8	0.0	0.0			0.9	0.0
CV-2012	7/8/2026 2:55:41 PM	38.9	57.8	0.0	3.3			0.7	0.0
CV-2012	7/8/2026 2:56:37 PM	39.3	55.5	0.0	5.2			0.7	0.0
CV-2201-PLR	7/8/2026 11:29:35 AM	3.0	78.3	0.0	18.7			0.0	0.0
CV-2201-PLR	7/8/2026 11:30:39 AM	3.2	82.3	0.0	14.5			0.0	0.0
CV-2201-PLR	7/29/2026 1:40:18 PM	3.3	73.4	2.0	21.3			0.0	10.7
CV-2201-PLR	7/29/2026 1:41:27 PM	3.3	74.8	1.7	20.2			0.0	11.9
CV-2204-PLR	7/6/2026 10:47:15 AM	28.3	69.8	0.0	1.9			0.4	0.0
CV-2204-PLR	7/6/2026 11:05:00 AM					1875			
CV-2204-PLR	7/6/2026 11:05:00 AM						139050		
CV-2204-PLR	7/13/2026 10:28:00 AM	3.1	73.3	0.0	23.6			0.0	0.0
CV-2204-PLR	7/13/2026 10:30:00 AM					1650			
CV-2204-PLR	7/20/2026 10:02:50 AM	19.5	70.8	0.0	9.7			0.3	0.0
CV-2204-PLR	7/20/2026 10:15:00 AM					2220			
CV-2204-PLR	7/27/2026 10:47:10 AM	28.3	69.9	0.0	1.8			0.4	0.0
CV-2205	7/6/2026 11:03:21 AM	14.2	72.7	0.0	13.1			0.2	0.0
CV-2205	7/6/2026 11:04:01 AM	13.6	75.4	0.0	11.0			0.2	0.0
CV-2207	7/2/2026 11:24:38 AM	43.0	57.0	0.0	0.0			0.8	0.0
CV-2208A	7/7/2026 9:14:02 AM	22.9	64.2	0.1	12.8			0.4	128.0
CV-2208A	7/7/2026 9:14:44 AM	22.7	64.3	0.0	13.0			0.4	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-2208A	7/7/2026 2:37:56 PM	48.0	52.0	0.0	0.0			0.9	0.0
CV-2208A	7/7/2026 2:38:55 PM	47.1	52.9	0.0	0.0			0.9	0.0
CV-2208A	7/7/2026 2:40:00 PM					500			
CV-2208A	7/7/2026 2:40:00 PM						68600		
CV-2208A	7/16/2026 11:12:34 AM	46.1	53.9	0.0	0.0			0.9	0.0
CV-2208A	7/16/2026 11:15:00 AM					674			
CV-2208A	7/20/2026 1:44:53 PM	52.2	47.8	0.0	0.0			1.1	0.0
CV-2208A	7/20/2026 1:50:00 PM					455			
CV-2208A	7/27/2026 12:57:55 PM	48.9	51.1	0.0	0.0			1.0	0.0
CV-2301	7/6/2026 7:20:00 AM					0			
CV-2301	7/6/2026 7:20:00 AM						0		
CV-2301	7/8/2026 1:12:10 PM	9.0	75.4	0.0	15.6			0.1	0.0
CV-2301	7/8/2026 1:12:44 PM	8.4	79.8	0.0	11.8			0.1	0.0
CV-2301	7/8/2026 1:15:00 PM					2830			
CV-2301	7/8/2026 1:15:00 PM						113600		
CV-2301	7/16/2026 10:42:12 AM	21.9	52.5	5.1	20.5			0.4	4.0
CV-2301	7/16/2026 10:43:49 AM	20.3	63.8	2.7	13.2			0.3	4.9
CV-2301	7/16/2026 10:45:00 AM					2360			
CV-2301	7/22/2026 2:20:36 PM	8.6	73.6	1.2	16.6			0.1	13.8
CV-2301	7/22/2026 2:22:28 PM	10.9	63.2	5.5	20.4			0.2	3.7
CV-2301	7/22/2026 2:22:54 PM	11.1	62.8	5.0	21.1			0.2	4.2
CV-2301	7/30/2026 9:33:34 AM	24.4	41.9	7.7	26.0			0.6	3.4
CV-2301	7/30/2026 9:37:13 AM	14.7	74.1	1.3	9.9			0.2	7.6
CV-2302	7/6/2026 7:25:00 AM					0			
CV-2302	7/6/2026 7:25:00 AM						0		
CV-2302	7/6/2026 3:38:27 PM	42.7	48.0	0.9	8.4			0.9	9.3
CV-2302	7/16/2026 2:45:08 PM	43.8	44.5	0.7	11.0			1.0	15.7
CV-2303	7/6/2026 7:25:00 AM					0			
CV-2303	7/6/2026 7:35:00 AM						790		
CV-2303	7/7/2026 9:55:00 AM					2500			
CV-2303	7/7/2026 9:55:00 AM						153100		
CV-2303	7/7/2026 10:01:32 AM	15.9	75.0	0.0	9.1			0.2	0.0
CV-2303	7/7/2026 10:02:07 AM	17.3	74.6	0.0	8.1			0.2	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-2303	7/14/2026 9:45:01 AM	12.8	70.1	0.0	17.1			0.2	0.0
CV-2303	7/14/2026 9:55:00 AM					2480			
CV-2303	7/21/2026 8:52:07 AM	14.9	72.3	0.0	12.8			0.2	0.0
CV-2303	7/28/2026 9:21:10 AM	11.6	73.3	0.2	14.9			0.2	74.5
CV-2304-PLR	7/2/2026 12:29:34 PM	0.7	69.4	4.5	25.4			0.0	5.6
CV-2304-PLR	7/7/2026 1:45:00 PM					1440			
CV-2304-PLR	7/7/2026 1:45:00 PM						108500		
CV-2304-PLR	7/7/2026 1:47:24 PM	19.0	75.1	0.0	5.9			0.3	0.0
CV-2304-PLR	7/14/2026 10:20:56 AM	12.3	73.3	0.0	14.4			0.2	0.0
CV-2304-PLR	7/14/2026 10:25:00 AM					1950			
CV-2304-PLR	7/14/2026 1:03:47 PM	12.0	68.6	0.0	19.4			0.2	0.0
CV-2304-PLR	7/21/2026 10:16:28 AM	19.3	70.4	0.0	10.3			0.3	0.0
CV-2304-PLR	7/28/2026 9:49:36 AM	16.7	73.8	0.0	9.5			0.2	0.0
CV-2305	7/2/2026 8:53:00 AM					1580			
CV-2305	7/2/2026 8:57:50 AM	21.5	60.7	0.0	17.8			0.4	0.0
CV-2305	7/2/2026 8:59:04 AM	22.1	45.6	0.0	32.3			0.5	0.0
CV-2305	7/9/2026 9:46:08 AM	32.9	64.8	0.0	2.3			0.5	0.0
CV-2305	7/9/2026 9:50:00 AM					2310			
CV-2305	7/9/2026 9:50:00 AM						62300		
CV-2305	7/13/2026 8:40:00 AM					2000			
CV-2305	7/13/2026 8:40:00 AM						86000		
CV-2305	7/16/2026 9:44:14 AM	34.1	65.9	0.0	0.0			0.5	0.0
CV-2305	7/16/2026 9:44:37 AM	33.7	66.2	0.0	0.1			0.5	0.0
CV-2305	7/16/2026 9:50:00 AM					1700			
CV-2305	7/30/2026 8:45:53 AM	18.2	74.7	0.0	7.1			0.2	0.0
CV-2306-PLR	7/6/2026 10:35:36 AM	27.8	72.2	0.0	0.0			0.4	0.0
CV-2306-PLR	7/6/2026 10:36:14 AM	25.2	72.3	0.0	2.5			0.3	0.0
CV-2306-PLR	7/6/2026 10:50:00 AM					910			
CV-2306-PLR	7/6/2026 10:50:00 AM						131300		
CV-2306-PLR	7/13/2026 10:20:00 AM					1110			

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-2306-PLR	7/13/2026 10:21:22 AM	2.4	71.1	0.4	26.1			0.0	65.3
CV-2306-PLR	7/13/2026 10:22:02 AM	2.4	74.6	0.4	22.6			0.0	56.5
CV-2306-PLR	7/20/2026 9:55:42 AM	18.4	71.3	0.0	10.3			0.3	0.0
CV-2306-PLR	7/20/2026 10:05:00 AM					1360			
CV-2306-PLR	7/27/2026 10:38:00 AM	24.4	68.8	0.0	6.8			0.4	0.0
CV-2308-PLR	7/8/2026 11:34:43 AM	6.0	75.4	0.4	18.2			0.1	45.5
CV-2308-PLR	7/8/2026 11:36:02 AM	8.0	75.6	0.2	16.2			0.1	81.0
CV-2308-PLR	7/29/2026 1:44:36 PM	4.6	68.7	3.1	23.6			0.1	7.6
CV-2310-PLR	7/7/2026 9:40:00 AM					1390			
CV-2310-PLR	7/7/2026 9:40:00 AM						113800		
CV-2310-PLR	7/7/2026 9:50:54 AM	15.5	72.6	0.0	11.9			0.2	0.0
CV-2310-PLR	7/14/2026 9:32:34 AM	20.4	69.1	0.0	10.5			0.3	0.0
CV-2310-PLR	7/14/2026 9:35:00 AM					1600			
CV-2310-PLR	7/21/2026 8:57:27 AM	15.8	69.0	0.0	15.2			0.2	0.0
CV-2310-PLR	7/28/2026 9:16:24 AM	15.5	66.8	0.0	17.7			0.2	0.0
CV-2311	7/7/2026 8:43:40 AM	34.6	63.7	0.0	1.7			0.5	0.0
CV-2311	7/7/2026 8:50:00 AM					1100			
CV-2311	7/7/2026 8:50:00 AM						86100		
CV-2311	7/13/2026 2:40:00 PM					1990			
CV-2311	7/13/2026 2:45:21 PM	4.8	79.3	0.0	15.9			0.1	0.0
CV-2311	7/13/2026 2:46:49 PM	7.1	70.9	0.0	22.0			0.1	0.0
CV-2311	7/20/2026 2:20:00 AM					2210			
CV-2311	7/20/2026 2:18:54 PM	35.3	62.6	0.0	2.1			0.6	0.0
CV-2311	7/28/2026 8:05:28 AM	29.4	60.5	0.0	10.1			0.5	0.0
CV-2312-PLR	7/6/2026 7:45:00 AM					520			
CV-2312-PLR	7/6/2026 7:45:00 AM						33000		
CV-2312-PLR	7/8/2026 1:40:00 PM					4010			
CV-2312-PLR	7/8/2026 1:40:00 PM						131400		
CV-2312-PLR	7/8/2026 1:43:27 PM	8.4	76.6	0.0	15.0			0.1	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-2312-PLR	7/16/2026 10:16:27 AM	7.9	78.3	0.0	13.8			0.1	0.0
CV-2312-PLR	7/16/2026 10:20:00 AM					3850			
CV-2312-PLR	7/17/2026 10:06:51 AM	49.6	43.2	0.1	7.1			1.1	71.0
CV-2312-PLR	7/21/2026 1:16:32 PM	12.4	75.7	0.0	11.9			0.2	0.0
CV-2312-PLR	7/22/2026 2:54:17 PM	11.8	68.9	0.0	19.3			0.2	0.0
CV-2312-PLR	7/29/2026 1:17:39 PM	40.0	60.0	0.0	0.0			0.7	0.0
CV-2314-PLR	7/6/2026 2:20:01 PM	12.0	74.6	1.5	11.9			0.2	7.9
CV-2314-PLR	7/6/2026 2:21:36 PM	12.7	78.9	0.5	7.9			0.2	15.8
CV-2314-PLR	7/6/2026 2:40:00 PM					4400			
CV-2314-PLR	7/6/2026 2:40:00 PM						117700		
CV-2314-PLR	7/13/2026 7:30:00 AM					3200			
CV-2314-PLR	7/13/2026 7:30:00 AM						140000		
CV-2314-PLR	7/15/2026 1:37:00 PM	11.4	80.6	0.0	8.0			0.1	0.0
CV-2314-PLR	7/15/2026 1:37:27 PM	11.9	81.0	0.0	7.1			0.1	0.0
CV-2314-PLR	7/15/2026 1:45:00 PM					4250			
CV-2315	7/6/2026 8:00:00 AM					370			
CV-2315	7/6/2026 8:00:00 AM						27000		
CV-2315	7/6/2026 1:44:39 PM	23.6	71.8	0.0	4.6			0.3	0.0
CV-2315	7/6/2026 2:05:00 PM					2800			
CV-2315	7/6/2026 2:05:00 PM						105600		
CV-2315	7/13/2026 1:19:42 PM	9.7	71.4	0.0	18.9			0.1	0.0
CV-2315	7/13/2026 1:30:00 PM					2190			
CV-2315	7/20/2026 10:06:54 AM	27.9	68.3	0.0	3.8			0.4	0.0
CV-2315	7/20/2026 10:20:00 AM					1455			
CV-2315	7/27/2026 1:32:19 PM	24.7	69.5	0.0	5.8			0.4	0.0
CV-2316	7/2/2026 8:44:17 AM	19.0	67.7	0.0	13.3			0.3	0.0
CV-2316	7/2/2026 8:45:00 AM					1940			
CV-2316	7/6/2026 10:15:04 AM	13.8	74.3	0.0	11.9			0.2	0.0
CV-2316	7/9/2026 9:11:41 AM	17.9	70.4	0.0	11.7			0.3	0.0
CV-2316	7/9/2026 9:15:00 AM					2540			
CV-2316	7/9/2026 9:15:00 AM						108300		
CV-2316	7/13/2026 1:31:38 PM	19.6	67.5	0.0	12.9			0.3	0.0
CV-2316	7/13/2026 1:32:10 PM	20.6	70.6	0.0	8.8			0.3	0.0
CV-2316	7/13/2026 1:50:00 PM					2810			

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-2316	7/20/2026 2:48:22 PM	23.9	69.5	0.0	6.6			0.3	0.0
CV-2316	7/20/2026 2:48:45 PM	23.1	72.9	0.0	4.0			0.3	0.0
CV-2316	7/20/2026 2:50:00 PM					3410			
CV-2316	7/29/2026 10:28:36 AM	34.2	65.8	0.0	0.0			0.5	0.0
CV-2319	7/9/2026 1:47:48 PM	22.3	76.5	0.0	1.2			0.3	0.0
CV-2319	7/9/2026 1:48:57 PM	18.3	79.8	0.0	1.9			0.2	0.0
CV-2319	7/21/2026 10:28:30 AM	11.8	74.2	0.0	14.0			0.2	0.0
CV-2321	7/2/2026 10:04:18 AM	24.7	75.3	0.0	0.0			0.3	0.0
CV-2321	7/2/2026 10:05:00 AM					4540			
CV-2321	7/9/2026 9:24:29 AM	25.3	72.3	0.2	2.2			0.3	11.0
CV-2321	7/9/2026 9:25:00 AM					4570			
CV-2321	7/9/2026 9:25:00 AM						71200		
CV-2321	7/16/2026 9:35:00 AM					4010			
CV-2321	7/16/2026 9:35:42 AM	26.9	71.9	0.1	1.1			0.4	11.0
CV-2321	7/30/2026 8:24:57 AM	21.7	74.6	0.2	3.5			0.3	17.5
CV-2322	7/10/2026 10:37:17 AM	0.2	10.4	17.3	72.1			0.0	4.2
CV-2322	7/29/2026 10:48:15 AM	1.9	86.9	0.0	11.2			0.0	0.0
CV-2322	7/29/2026 10:50:11 AM	1.5	82.6	0.6	15.3			0.0	25.5
CV-2324	7/2/2026 11:30:10 AM	49.0	46.3	0.0	4.7			1.1	0.0
CV-2326	7/1/2026 10:11:42 AM	4.2	74.7	0.9	20.2			0.1	22.4
CV-2326	7/7/2026 8:55:47 AM	25.2	69.6	0.0	5.2			0.4	0.0
CV-2326	7/7/2026 8:56:20 AM	24.6	74.0	0.0	1.4			0.3	0.0
CV-2326	7/7/2026 9:00:00 AM					378			
CV-2326	7/7/2026 9:00:00 AM						16000		
CV-2326	7/14/2026 8:52:10 AM	22.7	68.0	0.0	9.3			0.3	0.0
CV-2326	7/14/2026 9:05:00 AM					2890			
CV-2326	7/21/2026 8:27:42 AM	23.2	62.8	0.0	14.0			0.4	0.0
CV-2326	7/28/2026 8:24:36 AM	41.3	58.7	0.0	0.0			0.7	0.0
CV-2326	7/28/2026 8:25:04 AM	39.7	58.2	0.0	2.1			0.7	0.0
CV-2327	7/8/2026 2:20:50 PM	9.3	75.7	0.0	15.0			0.1	0.0
CV-2327	7/8/2026 2:25:00 PM					3290			

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-2327	7/14/2026 1:28:40 PM	15.8	74.5	0.0	9.7			0.2	0.0
CV-2327	7/14/2026 1:35:00 PM					2630			
CV-2327	7/21/2026 12:57:58 PM	21.7	77.6	0.0	0.7			0.3	0.0
CV-2327	7/29/2026 12:59:11 PM	37.0	63.0	0.0	0.0			0.6	0.0
CV-2328	7/8/2026 1:55:59 PM	51.5	48.5	0.0	0.0			1.1	0.0
CV-2328	7/13/2026 7:10:00 AM					350			
CV-2328	7/13/2026 7:10:00 AM						42000		
CV-2328	7/29/2026 9:48:41 AM	39.2	57.5	0.0	3.3			0.7	0.0
CV-2328	7/29/2026 9:49:48 AM	39.1	58.1	0.0	2.8			0.7	0.0
CV-2328	7/29/2026 12:49:23 PM	54.1	45.9	0.0	0.0			1.2	0.0
CV-2333	7/6/2026 9:09:15 AM	3.5	75.3	0.0	21.2			0.0	0.0
CV-2333	7/6/2026 9:15:00 AM					3760			
CV-2333	7/6/2026 9:15:00 AM						164200		
CV-2333	7/9/2026 7:15:00 AM					3500			
CV-2333	7/9/2026 7:15:00 AM						200000		
CV-2333	7/9/2026 9:15:00 AM					3360			
CV-2333	7/13/2026 9:03:07 AM	0.3	77.6	0.0	22.1			0.0	0.0
CV-2333	7/13/2026 9:04:45 AM	0.4	80.2	0.0	19.4			0.0	0.0
CV-2333	7/15/2026 2:28:17 PM	14.7	69.4	0.0	15.9			0.2	0.0
CV-2333	7/16/2026 4:31:46 PM	0.9	85.2	0.1	13.8			0.0	138.0
CV-2333	7/16/2026 4:33:26 PM	0.8	86.5	0.1	12.6			0.0	126.0
CV-2333	7/20/2026 9:04:08 AM	1.9	76.7	0.6	20.8			0.0	34.7
CV-2333	7/20/2026 9:05:00 AM					3680			
CV-2333	7/27/2026 8:55:36 AM	2.3	77.3	0.0	20.4			0.0	0.0
CV-2334	7/9/2026 7:30:00 AM					1900			
CV-2334	7/9/2026 7:30:00 AM						110000		
CV-2334	7/13/2026 8:41:10 AM	7.5	84.8	0.0	7.7			0.1	0.0
CV-2334	7/23/2026 1:50:21 PM	5.3	79.1	0.0	15.6			0.1	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-2334	7/23/2026 1:52:54 PM	4.8	80.7	0.0	14.5			0.1	0.0
CV-2335	7/1/2026 9:46:36 AM	51.7	44.3	0.1	3.9			1.2	39.0
CV-2335	7/16/2026 10:52:46 AM	45.2	41.1	0.1	13.6			1.1	136.0
CV-2336	7/1/2026 9:53:36 AM	4.6	10.3	17.6	67.5			0.4	3.8
CV-2336	7/16/2026 10:55:43 AM	14.6	23.8	11.2	50.4			0.6	4.5
CV-2337	7/1/2026 9:53:55 AM	10.8	73.3	0.0	15.9			0.1	0.0
CV-2337	7/1/2026 9:57:00 AM					86.5			
CV-2337	7/8/2026 8:58:06 AM	29.8	70.2	0.0	0.0			0.4	0.0
CV-2337	7/8/2026 9:00:00 AM					3480			
CV-2337	7/8/2026 9:00:00 AM						69900		
CV-2337	7/15/2026 8:40:46 AM	19.2	48.0	7.8	25.0			0.4	3.2
CV-2337	7/15/2026 8:42:31 AM	22.3	61.5	4.2	12.0			0.4	2.9
CV-2337	7/15/2026 8:45:00 AM					482			
CV-2337	7/22/2026 9:26:17 AM	23.0	77.0	0.0	0.0			0.3	0.0
CV-2337	7/22/2026 9:26:54 AM	21.2	77.3	0.0	1.5			0.3	0.0
CV-2337	7/29/2026 8:26:34 AM	17.0	73.8	0.0	9.2			0.2	0.0
CV-2338	7/1/2026 9:40:30 AM	6.2	74.9	0.0	18.9			0.1	0.0
CV-2338	7/1/2026 9:42:00 AM					755			
CV-2338	7/8/2026 8:45:00 AM					1310			
CV-2338	7/8/2026 8:45:00 AM						165700		
CV-2338	7/8/2026 8:53:18 AM	21.1	74.4	0.0	4.5			0.3	0.0
CV-2338	7/15/2026 8:33:54 AM	11.8	71.3	0.0	16.9			0.2	0.0
CV-2338	7/15/2026 8:35:00 AM					1190			
CV-2338	7/22/2026 9:17:45 AM	15.3	72.1	0.0	12.6			0.2	0.0
CV-2338	7/29/2026 8:21:59 AM	11.0	75.0	0.0	14.0			0.1	0.0
CV-2339	7/1/2026 9:20:00 AM					541			

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-2339	7/1/2026 9:24:19 AM	3.4	73.9	0.3	22.4			0.0	74.7
CV-2339	7/1/2026 9:26:06 AM	3.0	74.4	0.0	22.6			0.0	0.0
CV-2339	7/8/2026 8:40:52 AM	14.0	68.0	0.5	17.5			0.2	35.0
CV-2339	7/8/2026 8:44:33 AM	16.5	66.8	0.4	16.3			0.2	40.8
CV-2339	7/15/2026 8:23:25 AM	5.6	60.7	3.6	30.1			0.1	8.4
CV-2339	7/15/2026 8:25:00 AM					958			
CV-2339	7/22/2026 9:08:40 AM	8.4	66.7	1.2	23.7			0.1	19.8
CV-2339	7/22/2026 9:11:54 AM	8.8	63.8	1.0	26.4			0.1	26.4
CV-2339	7/22/2026 9:12:58 AM	9.6	62.1	3.2	25.1			0.2	7.8
CV-2341	7/7/2026 9:50:03 AM	10.8	70.2	0.5	18.5			0.2	37.0
CV-2341	7/16/2026 2:21:29 PM	11.8	62.9	0.6	24.7			0.2	41.2
CV-2342A-PL	7/1/2026 10:16:44 AM	11.9	73.3	0.0	14.8			0.2	0.0
CV-2342A-PL	7/1/2026 10:25:00 AM					519			
CV-2342A-PL	7/8/2026 9:35:00 AM					889.5			
CV-2342A-PL	7/8/2026 9:35:00 AM						205000		
CV-2342A-PL	7/8/2026 9:37:26 AM	21.2	68.2	0.0	10.6			0.3	0.0
CV-2342A-PL	7/8/2026 9:37:47 AM	21.6	69.8	0.0	8.6			0.3	0.0
CV-2342A-PL	7/15/2026 9:30:00 AM					420			
CV-2342A-PL	7/15/2026 9:31:03 AM	16.9	68.5	0.0	14.6			0.2	0.0
CV-2342A-PL	7/22/2026 10:55:19 AM	17.1	65.4	0.0	17.5			0.3	0.0
CV-2342A-PL	7/29/2026 8:59:38 AM	15.0	83.4	0.0	1.6			0.2	0.0
CV-2343-PLR	7/2/2026 1:25:00 AM					3255			
CV-2343-PLR	7/2/2026 1:27:10 PM	14.7	75.4	0.0	9.9			0.2	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-2343-PLR	7/8/2026 9:27:42 AM	16.2	73.0	0.0	10.8			0.2	0.0
CV-2343-PLR	7/8/2026 9:30:00 AM					3750			
CV-2343-PLR	7/8/2026 9:30:00 AM						159500		
CV-2343-PLR	7/15/2026 9:20:00 AM					3145			
CV-2343-PLR	7/15/2026 9:20:56 AM	12.2	73.2	0.0	14.6			0.2	0.0
CV-2343-PLR	7/22/2026 10:51:24 AM	16.4	76.3	0.0	7.3			0.2	0.0
CV-2343-PLR	7/29/2026 8:52:02 AM	23.3	73.3	0.0	3.4			0.3	0.0
CV-2344	7/1/2026 8:20:00 AM					0			
CV-2344	7/1/2026 8:20:00 AM						0		
CV-2344	7/1/2026 10:08:37 AM	11.1	78.6	0.0	10.3			0.1	0.0
CV-2344	7/1/2026 10:17:00 AM					1830			
CV-2344	7/8/2026 9:24:38 AM	30.5	69.5	0.0	0.0			0.4	0.0
CV-2344	7/8/2026 9:25:00 AM					2550			
CV-2344	7/8/2026 9:25:00 AM						102000		
CV-2344	7/15/2026 9:07:22 AM	26.5	73.1	0.0	0.4			0.4	0.0
CV-2344	7/15/2026 9:15:00 AM					2560			
CV-2344	7/22/2026 10:47:52 AM	23.9	71.6	0.0	4.5			0.3	0.0
CV-2344	7/29/2026 8:48:14 AM	20.4	74.2	0.0	5.4			0.3	0.0
CV-2345	7/1/2026 8:51:00 AM					430			
CV-2345	7/1/2026 8:51:00 AM						27000		
CV-2345	7/3/2026 9:09:08 AM	18.3	74.5	0.0	7.2			0.2	0.0
CV-2345	7/28/2026 1:17:28 PM	19.6	65.7	0.4	14.3			0.3	35.8
CV-2345	7/28/2026 1:18:30 PM	19.4	66.5	0.4	13.7			0.3	34.3
CV-2346	7/1/2026 8:10:00 AM					2300			
CV-2346	7/1/2026 8:10:00 AM						170000		
CV-2346	7/1/2026 10:04:09 AM	7.9	74.2	0.0	17.9			0.1	0.0
CV-2346	7/1/2026 10:10:00 AM					954			
CV-2346	7/8/2026 9:18:20 AM	21.9	74.5	0.0	3.6			0.3	0.0
CV-2346	7/8/2026 9:20:00 AM					3200			
CV-2346	7/8/2026 9:20:00 AM						153500		
CV-2346	7/15/2026 9:03:00 AM	20.0	72.3	0.0	7.7			0.3	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-2346	7/15/2026 9:05:00 AM					2600			
CV-2346	7/22/2026 10:45:05 AM	18.9	72.2	0.0	8.9			0.3	0.0
CV-2346	7/29/2026 8:44:01 AM	12.4	76.6	0.0	11.0			0.2	0.0
CV-2347	7/1/2026 8:05:00 AM					790			
CV-2347	7/1/2026 8:05:00 AM						50000		
CV-2347	7/3/2026 8:56:09 AM	15.6	66.4	0.0	18.0			0.2	0.0
CV-2347	7/28/2026 9:44:36 AM	18.3	50.5	0.3	30.9			0.4	103.0
CV-2348	7/1/2026 8:00:00 AM					400			
CV-2348	7/1/2026 8:00:00 AM						28000		
CV-2348	7/3/2026 8:54:05 AM	19.6	55.1	0.0	25.3			0.4	0.0
CV-2348	7/30/2026 12:27:31 PM	20.6	48.5	0.5	30.4			0.4	60.8
CV-2348	7/30/2026 12:28:19 PM	19.7	49.3	0.5	30.5			0.4	61.0
CV-2349	7/1/2026 1:45:13 PM	41.0	58.9	0.1	0.0			0.7	0.0
CV-2349	7/1/2026 1:50:00 PM					178			
CV-2349	7/2/2026 8:20:00 AM					1200			
CV-2349	7/2/2026 8:20:00 AM						85000		
CV-2349	7/8/2026 10:21:09 AM	24.4	69.6	0.0	6.0			0.4	0.0
CV-2349	7/8/2026 10:30:00 AM					3500			
CV-2349	7/8/2026 10:30:00 AM						144500		
CV-2349	7/15/2026 10:06:40 AM	16.1	65.6	2.1	16.2			0.2	7.7
CV-2349	7/15/2026 10:10:00 AM					3960			
CV-2349	7/22/2026 1:58:42 PM	26.9	58.8	14.3	0.0			0.5	0.0
CV-2349	7/29/2026 9:20:49 AM	19.0	75.6	0.0	5.4			0.3	0.0
CV-2350	7/3/2026 7:38:14 AM	4.9	78.1	0.0	17.0			0.1	0.0
CV-2350	7/8/2026 7:40:00 AM					3200			
CV-2350	7/20/2026 1:03:58 PM	4.1	72.8	0.1	23.0			0.1	230.0
CV-2351	7/1/2026 8:40:00 AM					0			
CV-2351	7/1/2026 8:40:00 AM						600		
CV-2351	7/7/2026 10:34:21 AM	0.2	1.0	21.0	77.8			0.2	3.7
CV-2351	7/7/2026 10:35:02 AM	0.2	1.2	20.7	77.9			0.2	3.8
CV-2351	7/28/2026 2:17:08 PM	1.6	1.1	20.9	76.4			1.5	3.7
CV-2352	7/2/2026 7:50:00 AM					0			
CV-2352	7/2/2026 7:50:00 AM						0		

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-2352	7/2/2026 1:09:51 PM	1.4	42.0	11.1	45.5			0.0	4.1
CV-2352	7/2/2026 1:12:12 PM	1.3	39.9	11.5	47.3			0.0	4.1
CV-2352	7/2/2026 2:00:00 PM					1380			
CV-2352	7/2/2026 2:16:24 PM	12.9	70.0	1.2	15.9			0.2	13.3
CV-2352	7/9/2026 10:20:00 AM					1040			
CV-2352	7/9/2026 10:20:00 AM						101400		
CV-2352	7/9/2026 10:28:26 AM	9.8	43.7	7.7	38.8			0.2	5.0
CV-2352	7/9/2026 10:30:58 AM	12.8	65.6	1.5	20.1			0.2	13.4
CV-2352	7/15/2026 9:35:00 AM					180			
CV-2352	7/15/2026 9:35:39 AM	19.8	70.7	1.0	8.5			0.3	8.5
CV-2352	7/22/2026 10:59:08 AM	21.0	67.4	0.0	11.6			0.3	0.0
CV-2352	7/29/2026 9:05:16 AM	13.3	68.6	0.0	18.1			0.2	0.0
CV-2353-PLR	7/1/2026 10:24:09 AM	12.8	68.5	0.0	18.7			0.2	0.0
CV-2353-PLR	7/8/2026 8:10:00 AM					710			
CV-2353-PLR	7/8/2026 8:10:00 AM						220000		
CV-2353-PLR	7/28/2026 2:07:19 PM	3.2	75.8	0.2	20.8			0.0	104.0
CV-2353-PLR	7/28/2026 2:11:24 PM	6.4	65.9	2.5	25.2			0.1	10.1
CV-2354	7/1/2026 1:52:06 PM	23.4	76.6	0.0	0.0			0.3	0.0
CV-2354	7/1/2026 2:04:00 PM					774			
CV-2354	7/8/2026 8:00:00 AM					2000			
CV-2354	7/8/2026 8:00:00 AM						170000		
CV-2354	7/8/2026 10:02:59 AM	28.1	71.9	0.0	0.0			0.4	0.0
CV-2354	7/8/2026 10:20:00 AM					2670			
CV-2354	7/8/2026 10:20:00 AM						150300		
CV-2354	7/15/2026 10:23:28 AM	20.7	70.3	0.0	9.0			0.3	0.0
CV-2354	7/15/2026 10:25:00 AM					3080			
CV-2354	7/22/2026 2:04:50 PM	19.4	68.6	0.0	12.0			0.3	0.0
CV-2354	7/29/2026 9:14:57 AM	21.0	71.2	0.0	7.8			0.3	0.0
CV-24001	7/1/2026 9:35:32 AM	54.3	43.9	0.0	1.8			1.2	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24001	7/16/2026 10:48:16 AM	53.2	44.2	0.0	2.6			1.2	0.0
CV-24002	7/1/2026 9:27:49 AM	41.7	43.7	0.3	14.3			1.0	47.7
CV-24002	7/16/2026 10:43:22 AM	41.8	51.9	0.0	6.3			0.8	0.0
CV-24003	7/1/2026 9:12:42 AM	35.0	49.2	0.0	15.8			0.7	0.0
CV-24003	7/16/2026 10:34:14 AM	38.6	53.6	0.0	7.8			0.7	0.0
CV-24004	7/1/2026 9:08:53 AM	35.7	59.0	0.0	5.3			0.6	0.0
CV-24004	7/16/2026 10:31:15 AM	34.3	56.4	0.0	9.3			0.6	0.0
CV-24006	7/1/2026 10:20:36 AM	39.7	48.4	0.5	11.4			0.8	22.8
CV-24006	7/16/2026 10:18:58 AM	9.6	53.0	6.5	30.9			0.2	4.8
CV-24007	7/1/2026 10:24:33 AM	25.6	43.2	2.9	28.3			0.6	9.8
CV-24007	7/16/2026 10:21:13 AM	21.1	50.5	3.3	25.1			0.4	7.6
CV-24008	7/7/2026 8:38:49 AM	4.8	76.3	0.0	18.9			0.1	0.0
CV-24008	7/7/2026 8:39:31 AM	4.8	74.5	0.0	20.7			0.1	0.0
CV-24008	7/7/2026 8:45:00 AM					1300			
CV-24008	7/7/2026 8:45:00 AM						97300		
CV-24008	7/13/2026 2:30:36 PM	5.5	70.8	0.0	23.7			0.1	0.0
CV-24008	7/13/2026 2:35:00 PM					1940			
CV-24008	7/20/2026 2:10:19 PM	9.5	70.2	0.2	20.1			0.1	100.5
CV-24008	7/20/2026 2:11:02 PM	10.7	73.4	0.1	15.8			0.1	158.0
CV-24008	7/20/2026 2:15:00 PM					2390			
CV-24008	7/28/2026 7:59:01 AM	4.0	76.3	0.0	19.7			0.1	0.0
CV-24008	7/28/2026 7:59:41 AM	4.3	73.6	0.0	22.1			0.1	0.0
CV-24009	7/7/2026 8:34:34 AM	12.1	79.6	0.0	8.3			0.2	0.0
CV-24009	7/7/2026 8:35:11 AM	11.6	77.1	0.0	11.3			0.2	0.0
CV-24009	7/7/2026 8:40:00 AM					833.5			
CV-24009	7/7/2026 8:40:00 AM						100150		
CV-24009	7/13/2026 2:26:43 PM	11.1	74.5	0.0	14.4			0.1	0.0
CV-24009	7/13/2026 2:27:24 PM	12.6	73.6	0.0	13.8			0.2	0.0
CV-24009	7/13/2026 2:27:53 PM	12.5	74.4	0.0	13.1			0.2	0.0
CV-24009	7/13/2026 2:30:00 PM					1370			

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24009	7/20/2026 2:07:05 PM	16.9	72.0	0.4	10.7			0.2	26.8
CV-24009	7/20/2026 2:10:00 PM					959.5			
CV-24009	7/28/2026 7:52:05 AM	12.7	73.3	0.7	13.3			0.2	19.0
CV-24009	7/28/2026 7:53:03 AM	12.2	71.5	0.6	15.7			0.2	26.2
CV-24010	7/8/2026 1:33:01 PM	6.8	39.9	10.3	43.0			0.2	4.2
CV-24010	7/8/2026 1:34:33 PM	1.2	8.5	18.9	71.4			0.1	3.8
CV-24010	7/21/2026 8:23:59 AM	22.8	66.1	0.2	10.9			0.3	54.5
CV-24011	7/7/2026 8:50:42 AM	22.7	68.4	0.0	8.9			0.3	0.0
CV-24011	7/7/2026 8:55:00 AM					2160			
CV-24011	7/7/2026 8:55:00 AM						124800		
CV-24011	7/14/2026 8:49:11 AM	15.4	69.8	0.2	14.6			0.2	73.0
CV-24011	7/14/2026 8:50:04 AM	15.1	68.3	0.2	16.4			0.2	82.0
CV-24011	7/14/2026 9:00:00 AM					1530			
CV-24011	7/21/2026 8:30:40 AM	23.6	65.9	0.2	10.3			0.4	51.5
CV-24011	7/28/2026 8:27:29 AM	38.7	60.3	0.3	0.7			0.6	2.3
CV-24012	7/7/2026 9:19:39 AM	11.9	74.9	0.0	13.2			0.2	0.0
CV-24012	7/7/2026 9:20:00 AM					1115			
CV-24012	7/7/2026 9:20:00 AM						78500		
CV-24012	7/14/2026 9:08:24 AM	9.0	76.7	0.0	14.3			0.1	0.0
CV-24012	7/14/2026 9:25:00 AM					2010			
CV-24012	7/21/2026 8:39:29 AM	6.2	76.8	0.0	17.0			0.1	0.0
CV-24012	7/28/2026 8:13:47 AM	7.6	74.3	0.0	18.1			0.1	0.0
CV-24013	7/2/2026 1:36:18 PM	0.8	23.8	15.1	60.3			0.0	4.0
CV-24013	7/21/2026 7:52:29 AM	0.3	14.0	17.5	68.2			0.0	3.9
CV-24014	7/6/2026 10:04:48 AM	17.8	72.0	0.0	10.2			0.2	0.0
CV-24014	7/6/2026 10:25:00 AM					1670			
CV-24014	7/6/2026 10:25:00 AM						174800		
CV-24014	7/13/2026 9:47:14 AM	3.0	73.2	0.0	23.8			0.0	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24014	7/13/2026 10:00:00 AM					1580			
CV-24014	7/20/2026 9:37:23 AM	15.9	68.9	0.0	15.2			0.2	0.0
CV-24014	7/20/2026 9:40:00 AM					1495			
CV-24014	7/27/2026 9:37:20 AM	20.0	70.1	0.0	9.9			0.3	0.0
CV-24015	7/6/2026 9:45:00 AM					1590			
CV-24015	7/6/2026 9:45:00 AM						175000		
CV-24015	7/6/2026 9:55:39 AM	11.5	62.1	3.2	23.2			0.2	7.3
CV-24015	7/6/2026 9:57:45 AM	13.0	67.9	0.9	18.2			0.2	20.2
CV-24015	7/13/2026 9:34:45 AM	1.4	69.2	0.7	28.7			0.0	41.0
CV-24015	7/13/2026 9:45:00 AM					1700			
CV-24015	7/20/2026 9:34:26 AM	13.2	69.0	0.0	17.8			0.2	0.0
CV-24015	7/20/2026 9:35:00 AM					1650			
CV-24015	7/27/2026 9:28:10 AM	15.6	69.3	0.8	14.3			0.2	17.9
CV-24016	7/7/2026 8:59:53 AM	33.3	55.3	0.0	11.4			0.6	0.0
CV-24016	7/7/2026 9:05:00 AM					935			
CV-24016	7/7/2026 9:05:00 AM						53300		
CV-24016	7/14/2026 8:54:39 AM	18.8	55.9	0.0	25.3			0.3	0.0
CV-24016	7/14/2026 9:10:00 AM					1560			
CV-24016	7/21/2026 8:25:11 AM	16.2	55.7	0.0	28.1			0.3	0.0
CV-24016	7/28/2026 8:19:06 AM	27.1	47.4	0.0	25.5			0.6	0.0
CV-24017	7/2/2026 9:54:07 AM	6.0	74.8	0.1	19.1			0.1	191.0
CV-24017	7/7/2026 9:07:06 AM	17.6	70.8	0.0	11.6			0.2	0.0
CV-24017	7/7/2026 9:10:00 AM					2050			
CV-24017	7/7/2026 9:10:00 AM						136100		
CV-24017	7/13/2026 9:00:00 AM					1600			
CV-24017	7/13/2026 9:00:00 AM						180000		
CV-24017	7/14/2026 9:01:41 AM	10.6	73.6	0.0	15.8			0.1	0.0
CV-24017	7/14/2026 9:02:10 AM	9.7	69.2	0.0	21.1			0.1	0.0
CV-24017	7/14/2026 9:15:00 AM					1920			
CV-24017	7/21/2026 8:34:08 AM	16.3	73.0	0.2	10.5			0.2	52.5

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24017	7/28/2026 8:09:09 AM	22.6	68.8	0.4	8.2			0.3	20.5
CV-24018	7/1/2026 1:40:12 PM	0.7	6.5	15.5	77.3			0.1	5.0
CV-24018	7/29/2026 2:10:56 PM	18.3	60.1	0.2	21.4			0.3	107.0
CV-24018	7/29/2026 2:11:44 PM	17.7	61.5	0.1	20.7			0.3	207.0
CV-24019	7/7/2026 9:25:00 AM					1370			
CV-24019	7/7/2026 9:25:00 AM						105700		
CV-24019	7/7/2026 9:29:12 AM	14.6	77.3	0.0	8.1			0.2	0.0
CV-24019	7/7/2026 9:29:55 AM	17.0	77.6	0.0	5.4			0.2	0.0
CV-24019	7/14/2026 9:15:49 AM	14.8	75.3	0.0	9.9			0.2	0.0
CV-24019	7/14/2026 9:30:00 AM					2010			
CV-24019	7/21/2026 8:48:47 AM	16.7	76.9	0.0	6.4			0.2	0.0
CV-24019	7/28/2026 8:16:19 AM	11.6	74.3	0.0	14.1			0.2	0.0
CV-24020	7/2/2026 1:45:52 PM	0.0	7.2	19.0	73.8			0.0	3.9
CV-24020	7/21/2026 7:57:54 AM	0.0	9.8	18.6	71.6			0.0	3.8
CV-24021	7/2/2026 1:50:07 PM	0.0	3.1	19.4	77.5			0.0	4.0
CV-24021	7/21/2026 8:09:32 AM	0.0	6.7	19.3	74.0			0.0	3.8
CV-24022-PL	7/6/2026 10:15:31 AM	17.7	72.0	0.0	10.3			0.2	0.0
CV-24022-PL	7/6/2026 10:30:00 AM					1950			
CV-24022-PL	7/6/2026 10:30:00 AM						192400		
CV-24022-PL	7/13/2026 9:55:02 AM	1.5	70.0	0.0	28.5			0.0	0.0
CV-24022-PL	7/13/2026 10:05:00 AM					1740			
CV-24022-PL	7/20/2026 9:40:24 AM	9.5	68.0	0.0	22.5			0.1	0.0
CV-24022-PL	7/20/2026 9:45:00 AM					2450			

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24022-PLI	7/27/2026 9:40:43 AM	11.8	66.8	0.0	21.4			0.2	0.0
CV-24023	7/3/2026 9:30:00 AM					1940			
CV-24023	7/3/2026 10:41:33 AM	4.0	73.0	0.0	23.0			0.1	0.0
CV-24023	7/6/2026 9:50:00 AM					1275			
CV-24023	7/6/2026 9:50:00 AM						180450		
CV-24023	7/6/2026 10:00:42 AM	13.4	69.3	0.0	17.3			0.2	0.0
CV-24023	7/13/2026 9:42:44 AM	1.7	72.0	0.0	26.3			0.0	0.0
CV-24023	7/13/2026 9:55:00 AM					1045			
CV-24023	7/20/2026 9:42:39 AM	10.3	68.3	0.0	21.4			0.2	0.0
CV-24023	7/20/2026 9:50:00 AM					1680			
CV-24023	7/27/2026 9:30:57 AM	15.2	68.4	0.0	16.4			0.2	0.0
CV-24024-PLI	7/13/2026 9:00:47 AM	1.5	77.1	1.1	20.3			0.0	18.5
CV-24024-PLI	7/13/2026 9:01:05 AM	1.4	77.3	1.0	20.3			0.0	20.3
CV-24024-PLI	7/23/2026 8:16:11 AM	1.5	70.1	0.8	27.6			0.0	34.5
CV-24024-PLI	7/27/2026 9:18:50 AM	14.9	68.5	0.0	16.6			0.2	0.0
CV-24025	7/7/2026 10:05:00 AM					2340			
CV-24025	7/7/2026 10:05:00 AM						103200		
CV-24025	7/7/2026 10:09:55 AM	18.4	72.7	0.0	8.9			0.3	0.0
CV-24025	7/14/2026 9:41:47 AM	19.4	64.9	0.0	15.7			0.3	0.0
CV-24025	7/14/2026 9:50:00 AM					2880			
CV-24025	7/21/2026 9:11:03 AM	19.1	65.6	0.0	15.3			0.3	0.0
CV-24025	7/28/2026 9:23:57 AM	16.2	61.6	0.0	22.2			0.3	0.0
CV-24026	7/7/2026 9:35:00 AM					691			
CV-24026	7/7/2026 9:35:00 AM						68000		
CV-24026	7/7/2026 9:41:18 AM	11.5	64.9	2.9	20.7			0.2	7.1
CV-24026	7/7/2026 9:49:00 AM	10.8	65.4	1.9	21.9			0.2	11.5

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24026	7/14/2026 9:25:45 AM	8.4	56.0	5.7	29.9			0.2	5.2
CV-24026	7/14/2026 9:27:42 AM	14.5	60.4	4.1	21.0			0.2	5.1
CV-24026	7/14/2026 9:28:29 AM	15.5	66.6	2.7	15.2			0.2	5.6
CV-24026	7/21/2026 8:03:12 AM	0.1	61.9	4.3	33.7			0.0	7.8
CV-24027	7/2/2026 1:59:27 PM	3.9	51.8	5.7	38.6			0.1	6.8
CV-24027	7/21/2026 8:11:59 AM	0.0	3.5	20.1	76.4			0.0	3.8
CV-24028	7/6/2026 10:19:46 AM	25.3	74.7	0.0	0.0			0.3	0.0
CV-24028	7/6/2026 10:35:00 AM					1020			
CV-24028	7/6/2026 10:35:00 AM						170300		
CV-24028	7/13/2026 10:06:15 AM	2.2	71.4	0.0	26.4			0.0	0.0
CV-24028	7/13/2026 10:10:00 AM					915			
CV-24028	7/20/2026 9:45:58 AM	13.6	69.2	0.0	17.2			0.2	0.0
CV-24028	7/20/2026 9:55:00 AM					1090			
CV-24028	7/27/2026 9:44:15 AM	16.5	69.2	0.0	14.3			0.2	0.0
CV-24029	7/6/2026 7:47:53 AM	2.0	49.5	7.7	40.8			0.0	5.3
CV-24029	7/6/2026 7:49:23 AM	3.3	71.4	1.7	23.6			0.0	13.9
CV-24029	7/23/2026 8:08:33 AM	0.7	35.9	11.0	52.4			0.0	4.8
CV-24029	7/23/2026 8:09:38 AM	0.6	31.6	13.0	54.8			0.0	4.2
CV-24030	7/6/2026 9:27:02 AM	4.4	52.9	6.8	35.9			0.1	5.3
CV-24030	7/6/2026 9:28:14 AM	5.9	60.5	4.9	28.7			0.1	5.9
CV-24030	7/6/2026 9:30:00 AM					1420			
CV-24030	7/6/2026 9:30:00 AM						140800		

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24030	7/6/2026 9:39:05 AM	10.4	74.9	0.0	14.7			0.1	0.0
CV-24030	7/13/2026 9:18:53 AM	1.3	77.2	0.0	21.5			0.0	0.0
CV-24030	7/13/2026 9:21:12 AM	0.9	66.6	4.3	28.2			0.0	6.6
CV-24030	7/13/2026 9:22:29 AM	1.0	65.7	3.3	30.0			0.0	9.1
CV-24030	7/13/2026 9:30:00 AM					1560			
CV-24030	7/20/2026 9:13:06 AM	5.3	61.5	3.9	29.3			0.1	7.5
CV-24030	7/20/2026 9:14:05 AM	5.9	63.1	3.7	27.3			0.1	7.4
CV-24030	7/20/2026 9:20:00 AM					1520			
CV-24030	7/27/2026 9:09:52 AM	4.8	28.5	13.6	53.1			0.2	3.9
CV-24030	7/27/2026 9:12:05 AM	6.9	42.2	8.6	42.3			0.2	4.9
CV-24031	7/1/2026 1:57:55 PM	2.4	3.8	18.9	74.9			0.6	4.0
CV-24031	7/2/2026 10:12:38 AM	32.1	63.1	0.1	4.7			0.5	47.0
CV-24031	7/2/2026 10:20:00 AM					1340			
CV-24031	7/7/2026 10:23:01 AM	33.7	65.8	0.0	0.5			0.5	0.0
CV-24031	7/7/2026 10:23:43 AM	33.9	66.1	0.0	0.0			0.5	0.0
CV-24031	7/7/2026 10:25:00 AM					120			
CV-24031	7/7/2026 10:25:00 AM						12800		
CV-24031	7/14/2026 9:38:15 AM	43.7	56.3	0.0	0.0			0.8	0.0
CV-24031	7/14/2026 9:45:00 AM					563			
CV-24031	7/21/2026 9:07:39 AM	47.4	52.6	0.0	0.0			0.9	0.0
CV-24031	7/28/2026 9:26:57 AM	46.8	53.2	0.0	0.0			0.9	0.0
CV-24032	7/7/2026 10:05:00 AM						103200		
CV-24032	7/7/2026 10:14:38 AM	44.9	55.0	0.0	0.1			0.8	0.0
CV-24032	7/7/2026 10:15:00 AM					671			
CV-24032	7/7/2026 10:15:00 AM						102200		
CV-24032	7/14/2026 9:35:53 AM	50.4	49.6	0.0	0.0			1.0	0.0
CV-24032	7/14/2026 9:40:00 AM					266			

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24032	7/21/2026 9:04:20 AM	51.3	48.7	0.0	0.0			1.1	0.0
CV-24032	7/28/2026 9:12:58 AM	49.3	50.7	0.0	0.0			1.0	0.0
CV-24033	7/7/2026 9:57:36 AM	11.4	54.5	6.1	28.0			0.2	4.6
CV-24033	7/7/2026 9:59:21 AM	13.5	58.3	4.8	23.4			0.2	4.9
CV-24033	7/29/2026 2:05:34 PM	1.0	5.1	19.9	74.0			0.2	3.7
CV-24033	7/29/2026 2:05:59 PM	1.4	5.7	19.5	73.4			0.2	3.8
CV-24034	7/6/2026 10:26:57 AM	19.6	78.7	0.0	1.7			0.2	0.0
CV-24034	7/6/2026 10:28:02 AM	24.2	75.5	0.0	0.3			0.3	0.0
CV-24034	7/6/2026 10:45:00 AM					1970			
CV-24034	7/6/2026 10:45:00 AM						156800		
CV-24034	7/13/2026 10:15:00 AM					1250			
CV-24034	7/13/2026 10:15:08 AM	1.8	76.7	0.4	21.1			0.0	52.8
CV-24034	7/13/2026 10:16:16 AM	1.6	72.2	2.7	23.5			0.0	8.7
CV-24034	7/20/2026 9:53:07 AM	14.0	73.6	0.0	12.4			0.2	0.0
CV-24034	7/20/2026 9:53:35 AM	14.0	72.8	0.0	13.2			0.2	0.0
CV-24034	7/20/2026 10:00:00 AM					1150			
CV-24034	7/27/2026 10:35:43 AM	15.8	64.0	3.4	16.8			0.2	4.9
CV-24034	7/27/2026 10:36:13 AM	14.9	65.0	3.2	16.9			0.2	5.3
CV-24035-PLI	7/6/2026 9:05:37 AM	6.0	77.7	0.0	16.3			0.1	0.0
CV-24035-PLI	7/6/2026 9:10:00 AM					1855			
CV-24035-PLI	7/6/2026 9:10:00 AM						134450		
CV-24035-PLI	7/13/2026 8:51:05 AM	1.3	77.2	0.0	21.5			0.0	0.0
CV-24035-PLI	7/13/2026 9:10:00 AM					1825			
CV-24035-PLI	7/20/2026 8:57:32 AM	2.5	77.3	0.0	20.2			0.0	0.0
CV-24035-PLI	7/20/2026 9:00:00 AM					1490			

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24035-PLI	7/27/2026 8:46:51 AM	2.7	81.0	0.0	16.3			0.0	0.0
CV-24036	7/1/2026 2:03:29 PM	54.7	40.1	0.3	4.9			1.4	16.3
CV-24036	7/2/2026 12:42:35 PM	50.5	42.2	0.1	7.2			1.2	72.0
CV-24036	7/29/2026 1:56:07 PM	53.9	45.9	0.2	0.0			1.2	0.0
CV-24037	7/1/2026 2:18:36 PM	16.0	68.3	0.5	15.2			0.2	30.4
CV-24037	7/1/2026 2:19:56 PM	15.1	69.7	0.1	15.1			0.2	151.0
CV-24037	7/29/2026 1:50:59 PM	13.2	78.0	0.2	8.6			0.2	43.0
CV-24038	7/7/2026 1:32:14 PM	27.8	72.0	0.2	0.0			0.4	0.0
CV-24038	7/7/2026 1:33:35 PM	23.4	73.0	0.0	3.6			0.3	0.0
CV-24038	7/7/2026 1:35:00 PM					820			
CV-24038	7/7/2026 1:35:00 PM						101550		
CV-24038	7/14/2026 10:14:43 AM	25.8	70.5	0.0	3.7			0.4	0.0
CV-24038	7/14/2026 10:15:00 AM					1840			
CV-24038	7/14/2026 10:15:17 AM	25.2	71.6	0.0	3.2			0.4	0.0
CV-24038	7/21/2026 10:10:15 AM	13.1	72.5	0.0	14.4			0.2	0.0
CV-24038	7/21/2026 10:11:14 AM	14.6	74.5	0.0	10.9			0.2	0.0
CV-24038	7/28/2026 9:31:51 AM	17.5	68.9	0.7	12.9			0.3	18.4
CV-24039	7/7/2026 2:00:00 PM					957			
CV-24039	7/7/2026 2:00:00 PM						116200		
CV-24039	7/7/2026 2:04:06 PM	16.9	68.4	0.6	14.1			0.2	23.5
CV-24039	7/7/2026 2:04:59 PM	17.8	68.1	0.0	14.1			0.3	0.0
CV-24039	7/14/2026 1:04:46 PM	11.3	70.6	0.0	18.1			0.2	0.0
CV-24039	7/14/2026 1:09:42 PM	11.2	67.6	0.0	21.2			0.2	0.0
CV-24039	7/14/2026 1:10:00 PM					1660			
CV-24039	7/21/2026 10:31:01 AM	17.5	68.0	0.0	14.5			0.3	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24039	7/28/2026 10:01:04 AM	16.7	66.5	0.0	16.8			0.3	0.0
CV-24040	7/2/2026 2:03:23 PM	0.9	76.8	0.4	21.9			0.0	54.8
CV-24040	7/7/2026 2:10:03 PM	18.5	70.5	0.0	11.0			0.3	0.0
CV-24040	7/7/2026 2:11:41 PM	18.0	71.9	0.8	9.3			0.3	11.6
CV-24040	7/7/2026 2:15:00 PM					1590			
CV-24040	7/7/2026 2:15:00 PM						152400		
CV-24040	7/13/2026 10:32:47 AM	1.3	68.9	1.5	28.3			0.0	18.9
CV-24040	7/13/2026 10:34:01 AM	1.9	71.6	0.6	25.9			0.0	43.2
CV-24040	7/13/2026 10:40:00 AM					1200			
CV-24040	7/21/2026 10:28:33 AM	14.8	69.3	0.3	15.6			0.2	52.0
CV-24040	7/28/2026 10:07:52 AM	11.6	67.8	0.5	20.1			0.2	40.2
CV-24041	7/2/2026 2:06:37 PM	3.6	39.1	10.5	46.8			0.1	4.5
CV-24041	7/21/2026 8:16:04 AM	0.0	3.4	19.9	76.7			0.0	3.9
CV-24042	7/6/2026 10:39:05 AM	33.1	66.9	0.0	0.0			0.5	0.0
CV-24042	7/6/2026 10:40:03 AM	25.7	73.9	0.0	0.4			0.3	0.0
CV-24042	7/6/2026 10:55:00 AM					1960			
CV-24042	7/6/2026 10:55:00 AM						124800		
CV-24042	7/13/2026 10:25:00 AM					819			
CV-24042	7/13/2026 10:25:01 AM	7.8	71.3	0.0	20.9			0.1	0.0
CV-24042	7/20/2026 9:58:34 AM	29.6	68.2	0.0	2.2			0.4	0.0
CV-24042	7/20/2026 10:10:00 AM					1500			
CV-24042	7/27/2026 10:43:38 AM	42.9	55.7	0.0	1.4			0.8	0.0
CV-24043	7/10/2026 10:12:45 AM	38.2	54.1	0.0	7.7			0.7	0.0
CV-24043	7/16/2026 2:32:38 PM	38.9	54.3	0.0	6.8			0.7	0.0
CV-24044	7/1/2026 2:08:53 PM	21.8	70.4	0.0	7.8			0.3	0.0
CV-24044	7/22/2026 1:39:48 PM	19.5	71.2	0.0	9.3			0.3	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24044	7/30/2026 9:59:51 AM	43.1	56.9	0.0	0.0			0.8	0.0
CV-24045	7/7/2026 1:38:11 PM	19.3	74.3	0.0	6.4			0.3	0.0
CV-24045	7/7/2026 1:40:00 PM					1650			
CV-24045	7/7/2026 1:40:00 PM						131200		
CV-24045	7/14/2026 10:17:58 AM	19.8	68.3	0.0	11.9			0.3	0.0
CV-24045	7/14/2026 10:20:00 AM					1640			
CV-24045	7/21/2026 10:14:16 AM	23.4	68.9	0.0	7.7			0.3	0.0
CV-24045	7/28/2026 9:44:32 AM	19.4	54.1	5.4	21.1			0.4	3.9
CV-24045	7/28/2026 9:46:42 AM	22.6	63.4	2.0	12.0			0.4	6.0
CV-24046	7/7/2026 1:54:14 PM	11.1	70.0	1.2	17.7			0.2	14.8
CV-24046	7/7/2026 1:55:00 PM					1720			
CV-24046	7/7/2026 1:55:00 PM						155600		
CV-24046	7/7/2026 1:56:03 PM	10.6	72.2	0.5	16.7			0.1	33.4
CV-24046	7/14/2026 1:13:28 PM	11.7	70.4	0.5	17.4			0.2	34.8
CV-24046	7/14/2026 1:14:02 PM	11.8	69.7	0.5	18.0			0.2	36.0
CV-24046	7/21/2026 10:33:20 AM	11.1	68.7	0.0	20.2			0.2	0.0
CV-24046	7/28/2026 10:18:26 AM	8.4	67.0	0.4	24.2			0.1	60.5
CV-24048	7/2/2026 2:12:30 PM	1.9	65.5	1.5	31.1			0.0	20.7
CV-24048	7/21/2026 8:18:43 AM	2.1	69.3	1.0	27.6			0.0	27.6
CV-24049	7/6/2026 1:38:16 PM	13.3	74.1	0.0	12.6			0.2	0.0
CV-24049	7/6/2026 4:50:00 PM					3480			
CV-24049	7/6/2026 4:50:00 PM						118800		
CV-24049	7/13/2026 9:10:00 AM					1700			
CV-24049	7/13/2026 9:10:00 AM						130000		
CV-24049	7/13/2026 1:14:21 PM	3.9	76.5	0.0	19.6			0.1	0.0
CV-24049	7/13/2026 1:20:00 PM					2960			
CV-24049	7/20/2026 10:13:54 AM	18.2	70.1	0.0	11.7			0.3	0.0
CV-24049	7/20/2026 10:30:00 AM					1440			

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24049	7/27/2026 1:26:59 PM	15.3	73.1	0.0	11.6			0.2	0.0
CV-24049	7/27/2026 1:30:09 PM	27.5	72.1	0.0	0.4			0.4	0.0
CV-24050	7/7/2026 9:56:00 AM	41.3	48.4	0.0	10.3			0.9	0.0
CV-24050	7/16/2026 2:26:11 PM	29.5	45.8	0.4	24.3			0.6	60.8
CV-24051	7/8/2026 10:40:27 AM	13.1	52.4	6.9	27.6			0.3	4.0
CV-24051	7/8/2026 10:41:15 AM	15.6	59.7	4.1	20.6			0.3	5.0
CV-24051	7/22/2026 1:46:52 PM	16.5	63.1	2.7	17.7			0.3	6.6
CV-24052	7/2/2026 2:24:37 PM	25.1	41.4	3.3	30.2			0.6	9.2
CV-24052	7/21/2026 1:52:36 PM	27.1	58.2	0.1	14.6			0.5	146.0
CV-24053	7/2/2026 2:21:41 PM	33.4	45.4	0.1	21.1			0.7	211.0
CV-24053	7/10/2026 10:33:54 AM	33.5	45.1	0.2	21.2			0.7	106.0
CV-24053	7/13/2026 7:15:00 AM					110			
CV-24053	7/13/2026 7:15:00 AM						15000		
CV-24053	7/21/2026 1:39:10 PM	35.0	45.7	0.1	19.2			0.8	192.0
CV-24054	7/6/2026 1:41:08 PM	20.0	74.6	0.0	5.4			0.3	0.0
CV-24054	7/6/2026 2:00:00 PM					1970			
CV-24054	7/6/2026 2:00:00 PM						115100		
CV-24054	7/13/2026 1:16:50 PM	8.2	73.9	0.0	17.9			0.1	0.0
CV-24054	7/13/2026 1:25:00 PM					1830			
CV-24054	7/20/2026 10:09:45 AM	27.8	72.2	0.0	0.0			0.4	0.0
CV-24054	7/20/2026 10:10:46 AM	27.1	72.9	0.0	0.0			0.4	0.0
CV-24054	7/20/2026 10:25:00 AM					1750			
CV-24055	7/9/2026 3:17:18 PM	8.2	55.5	3.4	32.9			0.1	9.7
CV-24055	7/9/2026 3:18:58 PM	8.1	56.5	3.4	32.0			0.1	9.4
CV-24055	7/23/2026 9:27:41 AM	7.7	50.5	2.8	39.0			0.2	13.9
CV-24056	7/3/2026 7:21:57 AM	32.4	63.3	0.0	4.3			0.5	0.0
CV-24056	7/20/2026 10:21:42 AM	22.0	61.7	0.7	15.6			0.4	22.3

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24057	7/1/2026 9:08:14 AM	1.0	0.1	20.9	78.0			10.0	3.7
CV-24057	7/1/2026 9:09:49 AM	27.9	65.6	0.0	6.5			0.4	0.0
CV-24057	7/16/2026 2:15:14 PM	18.3	67.6	0.0	14.1			0.3	0.0
CV-24058	7/7/2026 9:36:58 AM	24.1	35.5	0.0	40.4			0.7	0.0
CV-24058	7/16/2026 2:42:08 PM	25.4	33.9	0.0	40.7			0.7	0.0
CV-24059	7/2/2026 10:50:00 AM					453			
CV-24059	7/2/2026 10:56:24 AM	38.7	61.2	0.1	0.0			0.6	0.0
CV-24059	7/8/2026 1:16:56 PM	37.0	63.0	0.0	0.0			0.6	0.0
CV-24059	7/8/2026 1:20:00 PM					558			
CV-24059	7/8/2026 1:20:00 PM						110250		
CV-24059	7/16/2026 2:16:47 PM	37.1	60.7	0.1	2.1			0.6	21.0
CV-24059	7/16/2026 2:54:28 PM	25.5	61.7	0.0	12.8			0.4	0.0
CV-24059	7/22/2026 2:25:32 PM	46.0	54.0	0.0	0.0			0.9	0.0
CV-24059	7/30/2026 9:45:59 AM	38.6	61.4	0.0	0.0			0.6	0.0
CV-24060	7/6/2026 3:24:50 PM	5.8	90.8	0.0	3.4			0.1	0.0
CV-24060	7/17/2026 7:49:21 AM	7.3	73.7	1.1	17.9			0.1	16.3
CV-24061	7/8/2026 2:27:26 PM	29.8	65.5	0.2	4.5			0.5	22.5
CV-24061	7/8/2026 2:28:35 PM	25.4	69.8	0.1	4.7			0.4	47.0
CV-24061	7/29/2026 9:43:44 AM	47.9	49.5	0.0	2.6			1.0	0.0
CV-24062	7/6/2026 8:20:00 AM					190			
CV-24062	7/6/2026 8:20:00 AM						27000		
CV-24062	7/8/2026 2:06:55 PM	36.4	63.6	0.0	0.0			0.6	0.0
CV-24062	7/8/2026 2:08:53 PM	40.5	59.5	0.0	0.0			0.7	0.0
CV-24062	7/8/2026 2:10:00 PM					1260			
CV-24062	7/8/2026 2:10:00 PM						65400		
CV-24062	7/14/2026 1:31:33 PM	42.7	57.3	0.0	0.0			0.7	0.0
CV-24062	7/14/2026 1:40:00 PM					1060			
CV-24062	7/21/2026 1:00:32 PM	43.6	56.4	0.0	0.0			0.8	0.0
CV-24062	7/29/2026 12:56:17 PM	38.3	61.7	0.0	0.0			0.6	0.0
CV-24063	7/6/2026 8:15:00 AM					420			

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24063	7/6/2026 8:15:00 AM						37000		
CV-24063	7/8/2026 2:23:32 PM	27.6	72.4	0.0	0.0			0.4	0.0
CV-24063	7/8/2026 2:30:00 PM					1940			
CV-24063	7/8/2026 2:30:00 PM						86000		
CV-24063	7/14/2026 1:24:44 PM	26.1	69.6	0.0	4.3			0.4	0.0
CV-24063	7/14/2026 1:30:00 PM					1320			
CV-24063	7/21/2026 12:54:42 PM	40.5	59.4	0.0	0.1			0.7	0.0
CV-24063	7/29/2026 1:02:30 PM	37.3	62.7	0.0	0.0			0.6	0.0
CV-24064-PL	7/6/2026 8:10:00 AM					410			
CV-24064-PL	7/6/2026 8:10:00 AM						34000		
CV-24064-PL	7/6/2026 2:33:01 PM	13.2	78.0	0.0	8.8			0.2	0.0
CV-24064-PL	7/6/2026 2:50:00 PM					1780			
CV-24064-PL	7/6/2026 2:50:00 PM						114300		
CV-24064-PL	7/15/2026 1:24:20 PM	10.9	80.1	0.0	9.0			0.1	0.0
CV-24064-PL	7/15/2026 1:25:00 PM					2440			
CV-24064-PL	7/28/2026 1:23:22 PM	19.2	75.9	0.0	4.9			0.3	0.0
V-24065-TP1	7/6/2026 9:55:14 AM	29.3	69.8	0.9	0.0			0.4	0.0
V-24065-TP1	7/13/2026 8:45:00 AM					100			
V-24065-TP1	7/13/2026 8:45:00 AM						3300		
V-24065-TP1	7/20/2026 9:11:35 AM	11.6	35.1	3.8	49.5			0.3	13.0
CV-24066	7/3/2026 7:16:42 AM	19.9	44.8	0.0	35.3			0.4	0.0
CV-24066	7/13/2026 9:20:00 AM					170			
CV-24066	7/13/2026 9:20:00 AM						23000		
CV-24066	7/30/2026 12:31:20 PM	19.9	44.4	0.0	35.7			0.4	0.0
CV-24067	7/1/2026 8:55:09 AM	31.9	51.7	0.0	16.4			0.6	0.0
CV-24067	7/1/2026 9:00:00 AM					295			
CV-24067	7/3/2026 7:13:48 AM	27.5	50.3	0.0	22.2			0.5	0.0
CV-24067	7/3/2026 7:14:32 AM	27.1	49.9	0.0	23.0			0.5	0.0
CV-24067	7/20/2026 9:54:51 AM	1.1	82.1	0.0	16.8			0.0	0.0
CV-24067	7/22/2026 8:59:39 AM	5.3	77.6	0.0	17.1			0.1	0.0
CV-24067	7/22/2026 9:00:05 AM	4.4	81.5	0.0	14.1			0.1	0.0
CV-24067	7/29/2026 8:12:32 AM	25.5	50.6	0.0	23.9			0.5	0.0
CV-24068	7/7/2026 9:20:23 AM	23.5	39.4	0.0	37.1			0.6	0.0
CV-24068	7/20/2026 9:57:51 AM	20.3	49.8	0.0	29.9			0.4	0.0
CV-24069	7/6/2026 8:30:00 AM					58			
CV-24069	7/6/2026 8:30:00 AM						8600		

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24069	7/8/2026 10:32:20 AM	18.4	65.3	0.6	15.7			0.3	26.2
CV-24069	7/16/2026 2:59:51 PM	20.6	43.5	1.6	34.3			0.5	21.4
CV-24070	7/6/2026 8:35:00 AM					1000			
CV-24070	7/6/2026 8:35:00 AM						86000		
CV-24070	7/6/2026 3:45:09 PM	10.1	81.1	0.0	8.8			0.1	0.0
CV-24070	7/6/2026 3:46:17 PM	10.5	83.3	0.0	6.2			0.1	0.0
CV-24070	7/13/2026 2:59:42 PM	22.8	75.3	0.0	1.9			0.3	0.0
CV-24070	7/13/2026 3:00:00 PM					1310			
CV-24070	7/13/2026 3:00:43 PM	21.6	74.2	0.0	4.2			0.3	0.0
CV-24070	7/16/2026 3:03:30 PM	22.7	69.8	0.0	7.5			0.3	0.0
CV-24070	7/30/2026 9:51:32 AM	44.7	55.3	0.0	0.0			0.8	0.0
CV-24071	7/6/2026 3:18:36 PM	33.1	61.2	0.0	5.7			0.5	0.0
CV-24071	7/6/2026 3:19:46 PM	32.6	64.7	0.0	2.7			0.5	0.0
CV-24071	7/8/2026 8:25:00 AM					570			
CV-24071	7/8/2026 8:25:00 AM						83000		
CV-24071	7/17/2026 7:53:19 AM	31.4	63.1	0.0	5.5			0.5	0.0
CV-24071	7/17/2026 7:54:08 AM	31.5	60.1	0.0	8.4			0.5	0.0
CV-24072	7/6/2026 1:06:35 PM	33.7	66.3	0.0	0.0			0.5	0.0
CV-24072	7/17/2026 8:54:50 AM	39.0	57.7	0.0	3.3			0.7	0.0
V-24073-TP1	7/2/2026 3:17:49 PM	26.7	73.3	0.0	0.0			0.4	0.0
V-24073-TP1	7/2/2026 3:20:38 PM	23.1	76.9	0.0	0.0			0.3	0.0
V-24073-TP1	7/8/2026 2:14:44 PM	39.2	60.8	0.0	0.0			0.6	0.0
V-24073-TP1	7/8/2026 2:20:00 PM						48400		
V-24073-TP1	7/16/2026 10:10:00 AM					1150			
V-24073-TP1	7/16/2026 10:10:07 AM	38.5	61.5	0.0	0.0			0.6	0.0
V-24073-TP1	7/16/2026 10:10:25 AM	39.4	60.6	0.0	0.0			0.7	0.0
V-24073-TP1	7/21/2026 1:03:11 PM	47.5	52.5	0.0	0.0			0.9	0.0
V-24073-TP1	7/29/2026 1:08:41 PM	31.8	68.2	0.0	0.0			0.5	0.0
CV-24074	7/2/2026 3:13:30 PM	12.3	81.4	0.4	5.9			0.2	14.8
CV-24074	7/22/2026 2:20:45 PM	11.5	75.5	0.1	12.9			0.2	129.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
V-24075-TP1	7/2/2026 9:39:29 AM	0.8	74.7	2.0	22.5			0.0	11.3
V-24075-TP1	7/6/2026 3:01:23 PM	20.1	75.2	0.4	4.3			0.3	10.8
V-24075-TP1	7/6/2026 3:02:24 PM	18.8	76.0	0.2	5.0			0.2	25.0
V-24075-TP1	7/6/2026 3:05:00 PM					2100			
V-24075-TP1	7/6/2026 3:05:00 PM						109900		
V-24075-TP1	7/15/2026 1:29:30 PM	22.1	73.0	0.0	4.9			0.3	0.0
V-24075-TP1	7/15/2026 1:30:02 PM	24.1	75.9	0.0	0.0			0.3	0.0
V-24075-TP1	7/15/2026 1:35:00 PM					1870			
V-24075-TP1	7/28/2026 1:27:30 PM	29.3	70.6	0.1	0.0			0.4	0.0
CV-24076	7/6/2026 2:07:53 PM	41.5	58.5	0.0	0.0			0.7	0.0
CV-24076	7/6/2026 2:10:00 PM					757.5			
CV-24076	7/6/2026 2:10:00 PM						51950		
CV-24076	7/13/2026 1:23:31 PM	22.4	60.8	0.2	16.6			0.4	83.0
CV-24076	7/13/2026 1:35:00 PM					858			
CV-24076	7/20/2026 2:30:00 PM					1030			
CV-24076	7/20/2026 2:31:50 PM	29.7	55.3	0.7	14.3			0.5	20.4
CV-24076	7/27/2026 1:40:02 PM	38.4	52.9	0.7	8.0			0.7	11.4
CV-24077	7/1/2026 8:48:35 AM	17.2	63.7	0.0	19.1			0.3	0.0
CV-24077	7/1/2026 8:50:00 AM					1.89			
CV-24077	7/8/2026 8:28:44 AM	20.8	60.8	0.0	18.4			0.3	0.0
CV-24077	7/8/2026 8:30:00 AM					1200			
CV-24077	7/8/2026 8:30:00 AM						35150		
CV-24077	7/15/2026 8:09:17 AM	26.5	61.1	0.0	12.4			0.4	0.0
CV-24077	7/15/2026 8:10:00 AM					891			
CV-24077	7/20/2026 9:49:45 AM	15.8	61.7	0.0	22.5			0.3	0.0
CV-24077	7/22/2026 8:54:23 AM	18.4	76.5	0.0	5.1			0.2	0.0
CV-24077	7/22/2026 8:54:59 AM	17.4	80.5	0.0	2.1			0.2	0.0
CV-24077	7/29/2026 8:07:00 AM	19.9	65.6	0.0	14.5			0.3	0.0
CV-24078	7/3/2026 7:09:44 AM	31.0	49.7	2.6	16.7			0.6	6.4
CV-24078	7/20/2026 9:52:27 AM	18.4	54.0	4.2	23.4			0.3	5.6

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24079-TP	7/7/2026 9:15:40 AM	32.1	44.9	0.0	23.0			0.7	0.0
CV-24079-TP	7/7/2026 9:16:34 AM	31.6	46.5	0.0	21.9			0.7	0.0
CV-24079-TP	7/13/2026 7:31:55 AM	36.7	43.0	0.0	20.3			0.9	507.3
CV-24079-TP	7/13/2026 7:42:05 AM	32.0	46.8	0.0	21.2			0.7	707.0
CV-24079-TP	7/29/2026 9:09:16 AM	5.5	50.4	9.1	35.0			0.1	3.8
CV-24079-TP	7/29/2026 9:15:45 AM	2.4	81.3	2.1	14.2			0.0	6.8
CV-24080	7/7/2026 9:11:34 AM	39.6	55.5	0.0	4.9			0.7	0.0
CV-24080	7/29/2026 9:05:55 AM	43.8	56.2	0.0	0.0			0.8	0.0
V-24081-TP1	7/6/2026 3:54:09 PM	46.0	51.2	0.1	2.7			0.9	27.0
V-24081-TP1	7/16/2026 3:11:01 PM	32.1	63.0	0.0	4.9			0.5	0.0
CV-24082	7/6/2026 3:07:02 PM	42.4	55.3	0.0	2.3			0.8	0.0
CV-24082	7/17/2026 8:13:54 AM	40.6	55.8	0.0	3.6			0.7	0.0
CV-24083	7/2/2026 1:14:35 PM	14.9	77.1	0.0	8.0			0.2	0.0
CV-24083	7/2/2026 1:15:00 PM					1750			
CV-24083	7/6/2026 3:15:00 PM					1540			
CV-24083	7/6/2026 3:15:00 PM						96000		
CV-24083	7/6/2026 3:17:19 PM	16.4	72.3	0.0	11.3			0.2	0.0
CV-24083	7/6/2026 3:18:50 PM	19.1	77.3	0.0	3.6			0.2	0.0
CV-24083	7/6/2026 3:19:25 PM	21.0	77.5	0.0	1.5			0.3	0.0
CV-24083	7/16/2026 10:27:18 AM	37.4	61.7	0.0	0.9			0.6	0.0
CV-24083	7/16/2026 10:30:00 AM					1070			
CV-24083	7/17/2026 8:09:38 AM	26.8	64.4	0.0	8.8			0.4	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24083	7/21/2026 1:36:33 PM	24.4	73.4	0.0	2.2			0.3	0.0
CV-24083	7/21/2026 1:37:02 PM	23.2	76.8	0.0	0.0			0.3	0.0
CV-24083	7/30/2026 10:16:56 AM	41.8	58.2	0.0	0.0			0.7	0.0
V-24084-TP1	7/8/2026 1:30:00 PM					2760			
V-24084-TP1	7/8/2026 1:30:00 PM						101400		
V-24084-TP1	7/8/2026 1:30:26 PM	12.7	76.8	0.0	10.5			0.2	0.0
V-24084-TP1	7/16/2026 10:24:02 AM	7.3	76.5	0.0	16.2			0.1	0.0
V-24084-TP1	7/16/2026 10:25:00 AM					2790			
V-24084-TP1	7/21/2026 1:27:39 PM	8.9	74.7	0.0	16.4			0.1	0.0
V-24084-TP1	7/29/2026 1:25:41 PM	10.0	81.0	0.0	9.0			0.1	0.0
CV-24085	7/7/2026 12:01:16 PM	26.8	39.2	0.0	34.0			0.7	0.0
CV-24085	7/16/2026 9:52:28 AM	28.9	38.5	0.1	32.5			0.8	325.0
CV-24085	7/16/2026 9:54:37 AM	29.0	40.1	0.0	30.9			0.7	0.0
CV-24086	7/7/2026 8:58:12 AM	47.5	51.1	0.0	1.4			0.9	0.0
CV-24086	7/16/2026 1:59:18 PM	46.3	46.4	0.0	7.3			1.0	0.0
CV-24087	7/2/2026 2:17:41 PM	37.2	36.5	1.2	25.2			1.0	21.9
CV-24087	7/2/2026 2:19:33 PM	35.6	35.9	1.2	27.2			1.0	22.0
CV-24087	7/13/2026 7:57:48 AM	38.7	36.8	1.2	23.3			1.1	20.3
CV-24087	7/19/2026 1:06:40 PM	48.4	44.3	0.0	7.3			1.1	0.0
CV-24087	7/19/2026 1:07:48 PM	47.7	44.7	0.0	7.7			1.1	0.0
CV-24088	7/6/2026 12:48:09 PM	45.8	52.5	0.0	1.7			0.9	0.0
CV-24088	7/17/2026 8:32:34 AM	46.5	47.1	0.0	6.4			1.0	0.0
CV-24089	7/13/2026 11:29:35 AM	41.8	43.9	1.6	12.7			1.0	7.9
CV-24089	7/17/2026 8:41:49 AM	40.5	52.1	0.0	7.4			0.8	0.0
CV-24090	7/7/2026 12:20:30 PM	35.3	48.0	0.0	16.7			0.7	0.0
CV-24090	7/28/2026 8:57:02 AM	36.5	59.1	0.0	4.4			0.6	0.0
CV-24091	7/2/2026 1:55:15 PM	53.7	43.0	0.0	3.3			1.2	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24091	7/2/2026 1:58:33 PM	53.7	43.0	0.0	3.3			1.2	0.0
CV-24091	7/6/2026 10:46:17 AM	28.1	47.6	5.1	19.2			0.6	3.8
CV-24091	7/6/2026 10:48:07 AM	27.7	46.3	5.4	20.6			0.6	3.8
CV-24091	7/22/2026 9:43:27 AM	12.6	21.3	13.9	52.2			0.6	3.8
CV-24092	7/7/2026 2:35:45 PM	48.2	47.7	0.0	4.1			1.0	0.0
CV-24093	7/1/2026 11:46:07 AM	50.8	44.8	0.0	4.4			1.1	0.0
CV-24093	7/1/2026 11:49:48 AM	49.9	44.7	0.0	5.3			1.1	0.0
CV-24093	7/1/2026 11:50:23 AM	49.8	45.2	0.0	5.0			1.1	504.0
CV-24093	7/16/2026 2:34:31 PM	50.4	45.7	0.0	3.8			1.1	0.0
CV-24093	7/16/2026 2:37:29 PM	49.9	45.9	0.0	4.2			1.1	0.0
CV-24093	7/16/2026 2:39:05 PM	49.8	45.4	0.0	4.8			1.1	0.0
CV-24094	7/2/2026 1:06:27 PM	17.1	57.5	4.8	20.6			0.3	4.3
CV-24094	7/2/2026 1:07:29 PM	18.4	59.2	4.1	18.3			0.3	4.5
CV-24094	7/24/2026 10:59:08 AM	10.5	45.8	9.2	34.5			0.2	3.8
CV-24094	7/24/2026 11:02:10 AM	16.3	66.4	1.7	15.6			0.2	9.2
CV-24095	7/1/2026 1:48:38 PM	25.8	74.2	0.0	0.0			0.3	0.0
CV-24095	7/1/2026 1:56:00 PM					27.6			
CV-24095	7/2/2026 8:25:00 AM					1700			
CV-24095	7/2/2026 8:25:00 AM						120000		
CV-24095	7/8/2026 10:05:22 AM	25.3	68.7	0.0	6.0			0.4	0.0
CV-24095	7/8/2026 10:25:00 AM					3240			
CV-24095	7/8/2026 10:25:00 AM						14.81		
CV-24095	7/15/2026 10:11:43 AM	13.7	33.3	10.5	42.5			0.4	4.0
CV-24095	7/15/2026 10:16:56 AM	12.8	67.6	0.1	19.5			0.2	195.0
CV-24095	7/15/2026 10:20:00 AM					3410			
CV-24095	7/22/2026 2:01:45 PM	14.0	74.3	0.0	11.7			0.2	0.0
CV-24095	7/22/2026 2:02:24 PM	14.3	76.2	0.0	9.5			0.2	0.0
CV-24095	7/29/2026 9:17:33 AM	21.8	73.4	0.0	4.8			0.3	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24096	7/9/2026 8:45:58 AM	1.0	9.6	16.7	72.7			0.1	4.4
CV-24096	7/9/2026 8:47:11 AM	1.1	9.8	16.4	72.7			0.1	4.4
CV-24096	7/20/2026 1:13:02 PM	4.8	10.6	17.7	66.9			0.5	3.8
CV-24097	7/8/2026 10:34:37 AM	64.7	35.0	0.3	0.0			1.8	0.0
CV-24097	7/8/2026 10:35:24 AM	64.8	35.1	0.1	0.0			1.8	0.0
CV-24097	7/20/2026 1:16:13 PM	45.1	42.5	1.2	11.2			1.1	9.3
CV-24098	7/3/2026 7:42:01 AM	39.9	45.2	2.6	12.3			0.9	4.7
CV-24098	7/30/2026 10:47:53 AM	0.1	2.4	19.0	78.5			0.0	4.1
CV-24098	7/30/2026 10:48:29 AM	0.1	1.9	18.9	79.1			0.1	4.2
CV-24099	7/3/2026 7:45:50 AM	20.3	63.2	2.0	14.5			0.3	7.3
CV-24099	7/20/2026 12:59:25 PM	16.9	64.5	2.2	16.4			0.3	7.5
CV-24100	7/1/2026 1:28:47 PM	40.4	59.5	0.1	0.0			0.7	0.0
CV-24100	7/1/2026 1:30:00 PM					42.7			
CV-24100	7/2/2026 8:05:00 AM					12			
CV-24100	7/2/2026 8:05:00 AM						3300		
CV-24100	7/3/2026 8:08:58 AM	21.2	75.8	0.0	3.0			0.3	0.0
CV-24100	7/3/2026 8:10:35 AM	20.3	77.5	0.0	2.2			0.3	0.0
CV-24100	7/20/2026 12:53:13 PM	21.3	68.4	0.0	10.3			0.3	0.0
CV-24100	7/29/2026 9:35:55 AM	28.3	71.7	0.0	0.0			0.4	0.0
CV-24101	7/2/2026 8:00:00 AM					0			
CV-24101	7/2/2026 8:00:00 AM						0		
CV-24101	7/3/2026 8:15:20 AM	47.0	50.2	0.3	2.5			0.9	8.3
CV-24101	7/20/2026 10:36:02 AM	44.5	48.1	1.1	6.3			0.9	5.7
CV-24102	7/3/2026 8:37:34 AM	42.3	55.5	0.0	2.2			0.8	0.0
CV-24102	7/28/2026 10:17:39 AM	42.9	54.8	0.3	2.0			0.8	6.7
CV-24103	7/1/2026 3:29:48 PM	44.0	45.2	0.0	10.8			1.0	0.0
CV-24103	7/16/2026 9:38:27 AM	44.0	43.2	0.2	12.6			1.0	63.0
CV-24104	7/1/2026 10:59:23 AM	41.3	53.4	0.0	5.3			0.8	0.0
CV-24104	7/16/2026 2:10:22 PM	40.9	58.5	0.1	0.5			0.7	5.0
CV-24105	7/1/2026 11:06:55 AM	32.4	34.4	1.4	31.8			0.9	22.7
CV-24105	7/16/2026 2:27:11 PM	36.0	38.9	1.3	23.8			0.9	18.3
CV-24106	7/7/2026 3:07:31 PM	40.0	41.5	0.1	18.4			1.0	184.0
CV-24106	7/16/2026 3:02:43 PM	38.5	40.8	0.0	20.7			0.9	0.0
CV-24107	7/6/2026 12:36:03 PM	44.3	40.8	0.0	14.9			1.1	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24108	7/6/2026 12:25:36 PM	50.0	39.5	0.0	10.5			1.3	0.0
CV-24109	7/6/2026 12:00:44 PM	38.3	44.2	0.0	17.5			0.9	0.0
CV-24110	7/7/2026 1:04:20 PM	29.2	63.9	0.0	6.9			0.5	0.0
CV-24110	7/7/2026 1:05:17 PM	30.7	64.0	0.0	5.3			0.5	0.0
CV-24111	7/2/2026 11:09:11 AM	47.8	50.5	0.0	1.7			0.9	0.0
CV-24112	7/2/2026 11:13:05 AM	54.2	42.8	0.0	3.0			1.3	0.0
CV-24114	7/8/2026 10:21:07 AM	52.6	41.7	0.0	5.7			1.3	0.0
CV-24116	7/1/2026 7:41:28 AM	49.3	47.3	0.3	3.1			1.0	10.3
CV-24117	7/8/2026 10:03:59 AM	35.2	36.4	0.0	28.4			1.0	0.0
CV-24118	7/7/2026 1:25:13 PM	18.4	61.1	0.4	20.1			0.3	50.3
CV-24118	7/7/2026 1:25:56 PM	18.7	65.0	0.4	15.9			0.3	39.8
CV-24118	7/29/2026 9:13:45 AM						148000		
CV-24118	7/29/2026 9:19:19 AM	4.5	76.6	0.0	4.0		14.9	0.1	0.0
CV-24118	7/29/2026 9:21:46 AM	4.7	78.1	0.0	2.9		14.3	0.1	0.0
CV-24118	7/29/2026 9:25:00 AM					2650			
CV-24118	7/29/2026 9:25:00 AM						127800		
CV-24119	7/15/2026 10:31:25 AM	43.9	43.1	0.0	13.0			1.0	0.0
CV-24119	7/15/2026 10:32:21 AM	43.2	43.1	0.0	13.7			1.0	0.0
CV-24120	7/8/2026 1:58:27 PM	2.2	20.1	15.7	62.0			0.1	3.9
CV-24120	7/13/2026 10:05:00 AM					150			
CV-24120	7/13/2026 10:05:00 AM						11000		
CV-24120	7/31/2026 9:43:24 AM	6.5	29.7	13.8	50.0			0.2	3.6
CV-24120	7/31/2026 10:24:29 AM	9.4	58.3	4.4	27.9			0.2	6.3

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24121	7/8/2026 1:56:01 PM	0.7	1.6	20.3	77.4			0.4	3.8
CV-24121	7/9/2026 7:50:00 AM					2100			
CV-24121	7/9/2026 7:50:00 AM						160000		
CV-24121	7/27/2026 1:27:57 PM	0.5	2.9	20.3	76.3			0.2	3.8
CV-24122	7/6/2026 9:28:47 AM	0.0	0.2	20.6	79.2			0.0	3.8
CV-24122	7/6/2026 9:40:00 AM	20.3	25.4	11.7	42.6			0.8	3.6
CV-24122	7/9/2026 7:55:00 AM					0			
CV-24122	7/9/2026 7:55:00 AM						1700		
CV-24122	7/23/2026 2:13:49 PM	46.0	54.0	0.0	0.0			0.9	0.0
CV-24122	7/23/2026 2:14:07 PM	46.9	51.6	0.0	1.5			0.9	0.0
CV-24122	7/24/2026 9:45:00 AM						0		
CV-24123	7/8/2026 3:18:05 PM	45.4	54.6	0.0	0.0			0.8	0.0
CV-24123	7/22/2026 10:18:09 AM	43.9	51.0	0.0	5.1			0.9	0.0
CV-24124	7/13/2026 9:07:33 AM	4.9	82.4	0.0	12.7			0.1	0.0
CV-24124	7/13/2026 9:07:55 AM	4.9	84.5	0.0	10.6			0.1	0.0
CV-24124	7/31/2026 9:35:59 AM	6.0	72.8	1.1	20.1			0.1	18.3
V-24125-TP2	7/13/2026 10:25:00 AM					0			
V-24125-TP2	7/13/2026 10:25:00 AM						2700		
V-24125-TP2	7/13/2026 12:00:38 PM	39.0	57.7	0.5	2.8			0.7	5.6
V-24125-TP2	7/23/2026 2:22:19 PM	38.3	56.0	0.3	5.4			0.7	18.0
CV-24126	7/2/2026 10:44:12 AM	5.7	53.0	0.9	40.4			0.1	44.9
CV-24126	7/6/2026 1:33:35 PM	11.8	74.8	0.0	13.4			0.2	0.0
CV-24126	7/6/2026 1:40:00 PM					4470			
CV-24126	7/6/2026 1:40:00 PM						165200		
CV-24126	7/13/2026 1:44:32 PM	2.9	72.0	1.0	24.1			0.0	24.1
CV-24126	7/13/2026 1:45:00 PM					2125			
CV-24126	7/13/2026 1:45:04 PM	3.1	73.7	0.3	22.9			0.0	76.3

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24126	7/20/2026 10:21:14 AM	29.2	65.3	0.0	5.5			0.4	0.0
CV-24126	7/20/2026 10:40:00 AM					3300			
CV-24126	7/27/2026 1:12:06 PM	22.1	68.6	0.0	9.3			0.3	0.0
CV-24127	7/6/2026 1:30:07 PM	14.2	72.9	0.0	12.9			0.2	0.0
CV-24127	7/6/2026 1:35:00 PM					4520			
CV-24127	7/6/2026 1:35:00 PM						154300		
CV-24127	7/13/2026 1:04:22 PM	8.2	73.0	0.0	18.8			0.1	0.0
CV-24127	7/13/2026 1:10:00 PM					4730			
CV-24127	7/20/2026 10:25:41 AM	29.0	66.8	0.0	4.2			0.4	0.0
CV-24127	7/20/2026 10:45:00 AM					3200			
CV-24127	7/27/2026 1:06:12 PM	32.9	64.1	0.0	3.0			0.5	0.0
CV-24128	7/9/2026 7:35:00 AM					1600			
CV-24128	7/9/2026 7:35:00 AM						72000		
CV-24128	7/9/2026 8:21:11 AM	21.7	61.4	0.2	16.7			0.4	83.5
CV-24128	7/9/2026 3:03:21 PM	23.3	64.4	0.6	11.7			0.4	19.5
CV-24128	7/23/2026 1:56:14 PM	17.8	68.6	0.0	13.6			0.3	0.0
CV-24129	7/9/2026 8:18:18 AM	39.7	60.3	0.0	0.0			0.7	0.0
CV-24129	7/23/2026 2:00:53 PM	44.3	55.7	0.0	0.0			0.8	0.0
CV-24130	7/9/2026 8:15:12 AM	20.7	65.8	0.0	13.5			0.3	0.0
CV-24130	7/23/2026 2:05:27 PM	22.9	63.5	0.0	13.6			0.4	0.0
CV-24131	7/8/2026 3:31:54 PM	45.2	53.1	0.0	1.7			0.9	0.0
CV-24132	7/8/2026 3:36:10 PM	52.3	43.8	0.0	3.9			1.2	0.0
CV-24133	7/22/2026 10:30:37 AM	55.1	37.6	0.2	7.1			1.5	35.5
V-24134-TP1	7/6/2026 1:27:42 PM	40.5	59.5	0.0	0.0			0.7	0.0
V-24134-TP1	7/6/2026 1:30:00 PM					2770			
V-24134-TP1	7/6/2026 1:30:00 PM						108000		
V-24134-TP1	7/13/2026 1:01:45 PM	39.8	54.6	0.0	5.6			0.7	0.0
V-24134-TP1	7/13/2026 1:05:00 PM					2340			
V-24134-TP1	7/20/2026 10:29:58 AM	37.7	62.3	0.0	0.0			0.6	0.0
V-24134-TP1	7/20/2026 10:50:00 AM					3440			
V-24134-TP1	7/27/2026 1:04:09 PM	39.4	60.6	0.0	0.0			0.7	0.0
CV-24135	7/6/2026 2:20:09 PM	14.1	70.5	0.0	15.4			0.2	0.0
CV-24135	7/27/2026 1:02:21 PM	6.3	64.4	1.9	27.4			0.1	14.4

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24135	7/27/2026 1:23:42 PM	11.8	77.4	0.0	10.8			0.2	0.0
CV-24136	7/7/2026 9:55:59 AM	33.2	51.7	0.0	15.1			0.6	0.0
CV-24137	7/6/2026 11:54:10 AM	46.1	43.3	0.0	10.6			1.1	0.0
CV-24138	7/2/2026 8:35:00 AM					0			
CV-24138	7/2/2026 8:35:00 AM						2400		
CV-24138	7/9/2026 9:09:04 AM	1.5	0.7	18.2	79.6			2.1	4.4
CV-24138	7/9/2026 9:10:39 AM	1.5	0.9	18.1	79.5			1.7	4.4
CV-24138	7/30/2026 10:59:43 AM	2.5	66.1	2.2	29.2			0.0	13.3
CV-24138	7/30/2026 11:01:03 AM	2.5	65.7	2.1	29.7			0.0	14.1
CV-24139	7/1/2026 1:59:05 PM	20.5	74.1	0.1	5.3			0.3	53.0
CV-24139	7/1/2026 2:10:00 PM					466			
CV-24139	7/8/2026 9:55:00 AM					1150			
CV-24139	7/8/2026 9:55:00 AM						181600		
CV-24139	7/8/2026 9:55:13 AM	22.6	65.2	0.8	11.4			0.3	14.3
CV-24139	7/8/2026 9:56:32 AM	24.2	66.0	0.6	9.2			0.4	15.3
CV-24139	7/14/2026 7:15:00 AM					300			
CV-24139	7/14/2026 7:15:00 AM						94000		
CV-24139	7/15/2026 9:45:13 AM	13.7	2.2	19.4	64.7			6.2	3.3
CV-24139	7/15/2026 9:46:47 AM	11.9	0.9	19.7	67.5			13.2	3.4
CV-24139	7/30/2026 11:03:32 AM	3.3	68.4	0.6	27.7			0.0	46.2
CV-24139	7/30/2026 11:04:14 AM	3.3	79.7	0.8	16.2			0.0	20.3
CV-24140	7/1/2026 8:50:00 AM					0			
CV-24140	7/1/2026 8:50:00 AM						0		
CV-24140	7/1/2026 2:08:43 PM	16.5	72.4	0.1	11.0			0.2	110.0
CV-24140	7/1/2026 2:17:00 PM					1190			
CV-24140	7/8/2026 9:45:00 AM					1010			
CV-24140	7/8/2026 9:45:00 AM						119800		
CV-24140	7/8/2026 9:47:46 AM	16.9	66.2	0.7	16.2			0.3	23.1

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24140	7/8/2026 9:49:23 AM	16.5	68.9	0.3	14.3			0.2	47.7
CV-24140	7/15/2026 9:39:54 AM	21.6	68.1	0.4	9.9			0.3	24.8
CV-24140	7/15/2026 9:40:00 AM					666			
CV-24140	7/22/2026 11:04:15 AM	18.8	69.3	0.6	11.3			0.3	18.8
CV-24140	7/22/2026 11:04:39 AM	18.6	69.0	0.4	12.0			0.3	30.0
CV-24141	7/2/2026 7:55:00 AM					0			
CV-24141	7/2/2026 7:55:00 AM						820		
CV-24141	7/2/2026 12:59:12 PM	24.3	37.1	3.4	35.2			0.7	10.4
CV-24141	7/14/2026 8:50:53 AM	0.7	1.4	19.4	78.5			0.5	4.0
CV-24141	7/14/2026 8:51:58 AM	0.7	1.4	19.3	78.6			0.5	4.1
CV-24141	7/28/2026 2:19:35 PM	31.5	31.7	4.9	31.9			1.0	6.5
CV-24142	7/2/2026 8:30:00 AM					570			
CV-24142	7/2/2026 8:30:00 AM						88000		
CV-24142	7/9/2026 8:59:51 AM	8.3	43.9	8.7	39.1			0.2	4.5
CV-24142	7/9/2026 9:01:16 AM	5.6	36.4	11.2	46.8			0.2	4.2
CV-24142	7/30/2026 10:56:47 AM	2.3	59.9	3.2	34.6			0.0	10.8
CV-24142	7/30/2026 10:57:39 AM	2.6	61.7	2.6	33.1			0.0	12.7
CV-24143	7/1/2026 8:35:00 AM					230			
CV-24143	7/1/2026 8:35:00 AM						33000		
CV-24143	7/1/2026 10:34:22 AM	10.5	57.8	5.7	26.0			0.2	4.6
CV-24143	7/1/2026 10:37:17 AM	11.4	56.1	5.4	27.1			0.2	5.0
CV-24144	7/8/2026 10:38:46 AM	70.5	29.5	0.0	0.0			2.4	0.0
CV-24144	7/20/2026 1:19:01 PM	51.7	41.7	0.1	6.5			1.2	65.0
CV-24145	7/7/2026 9:15:00 AM					709			
CV-24145	7/7/2026 9:15:00 AM						68600		
CV-24145	7/7/2026 9:15:42 AM	11.3	70.5	0.0	18.2			0.2	0.0
CV-24145	7/7/2026 9:16:13 AM	9.4	67.5	0.0	23.1			0.1	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24145	7/14/2026 9:05:26 AM	6.9	72.8	0.0	20.3			0.1	0.0
CV-24145	7/14/2026 9:05:51 AM	5.8	61.1	0.0	33.1			0.1	0.0
CV-24145	7/14/2026 9:20:00 AM					1840			
CV-24145	7/21/2026 8:36:45 AM	11.9	62.1	0.0	26.0			0.2	0.0
CV-24145	7/28/2026 8:11:20 AM	8.9	70.3	0.0	20.8			0.1	0.0
CV-24146	7/1/2026 9:26:27 AM	53.8	40.0	0.0	6.2			1.3	0.0
CV-24146	7/1/2026 9:28:20 AM	52.8	40.5	0.0	6.7			1.3	0.0
CV-24146	7/22/2026 10:17:09 AM	55.8	40.6	0.1	3.5			1.4	35.0
CV-24146	7/27/2026 2:11:52 PM	51.2	44.7	0.0	4.1			1.1	0.0
CV-24147	7/1/2026 9:36:36 AM	44.5	36.0	3.2	16.4			1.2	5.2
CV-24147	7/1/2026 9:46:01 AM	51.0	40.0	0.3	8.7			1.3	29.9
CV-24147	7/22/2026 10:21:45 AM	49.7	44.6	0.0	5.7			1.1	0.0
CV-24148	7/6/2026 2:26:20 PM	34.5	65.5	0.0	0.0			0.5	0.0
CV-24148	7/6/2026 2:45:00 PM					1800			
CV-24148	7/6/2026 2:45:00 PM						66700		
CV-24148	7/15/2026 1:20:00 PM					2060			
CV-24148	7/15/2026 1:21:10 PM	26.2	72.3	0.0	1.5			0.4	0.0
CV-24148	7/28/2026 1:21:09 PM	45.6	54.4	0.0	0.0			0.8	0.0
CV-24149	7/2/2026 3:03:27 PM	39.2	59.0	0.0	1.8			0.7	0.0
CV-24149	7/29/2026 10:38:37 AM	34.5	61.7	0.0	3.8			0.6	0.0
CV-24150	7/2/2026 1:19:01 PM	44.7	54.9	0.1	0.3			0.8	3.0
CV-24150	7/24/2026 10:54:45 AM	51.8	42.7	0.0	5.5			1.2	0.0
CV-24151	7/2/2026 4:27:58 PM	46.9	53.0	0.0	0.1			0.9	0.0
CV-24151	7/29/2026 10:06:40 AM	45.9	52.4	0.2	1.5			0.9	7.5
CV-24152	7/2/2026 3:30:10 PM	20.3	79.7	0.0	0.0			0.3	0.0
CV-24152	7/2/2026 3:31:51 PM	19.5	80.5	0.0	0.0			0.2	0.0
CV-24152	7/22/2026 2:16:41 PM	17.7	74.4	0.0	7.9			0.2	0.0
CV-24153	7/2/2026 1:30:09 PM	43.4	55.2	0.0	1.4			0.8	0.0
CV-24153	7/29/2026 10:41:39 AM	37.7	59.5	0.0	2.8			0.6	0.0
CV-24154	7/2/2026 12:04:43 PM	35.3	56.7	1.4	6.6			0.6	4.7
CV-24154	7/2/2026 1:26:44 PM	44.2	54.0	0.4	1.4			0.8	3.5
CV-24154	7/16/2026 2:44:12 PM	39.2	55.6	0.0	5.3			0.7	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24155	7/2/2026 2:56:00 PM	32.2	61.1	0.3	6.4			0.5	21.3
CV-24155	7/22/2026 2:06:53 PM	23.9	69.6	0.0	6.5			0.3	0.0
CV-24156	7/6/2026 1:00:56 PM	25.4	74.5	0.1	0.0			0.3	0.0
CV-24156	7/6/2026 1:03:01 PM	17.5	82.5	0.0	0.0			0.2	0.0
CV-24156	7/17/2026 10:11:04 AM	25.0	66.5	0.0	8.5			0.4	0.0
CV-24157	7/2/2026 4:31:31 PM	51.2	48.8	0.0	0.0			1.0	0.0
CV-24157	7/17/2026 10:17:57 AM	33.1	59.3	0.0	7.6			0.6	0.0
CV-24158	7/2/2026 4:18:26 PM	33.9	65.0	0.1	1.0			0.5	10.0
CV-24158	7/17/2026 9:52:10 AM	36.2	60.4	0.0	3.4			0.6	0.0
CV-24159	7/1/2026 11:34:49 AM	49.4	45.6	0.0	5.0			1.1	0.0
CV-24159	7/1/2026 11:38:58 AM	48.7	44.7	0.0	6.7			1.1	0.0
CV-24159	7/1/2026 11:39:41 AM	48.6	45.8	0.0	5.6			1.1	0.0
CV-24159	7/16/2026 2:28:59 PM	45.6	49.5	0.0	4.9			0.9	0.0
CV-24159	7/16/2026 2:29:46 PM	45.3	49.4	0.0	5.4			0.9	0.0
CV-24160	7/1/2026 1:08:53 PM	46.4	46.8	0.0	6.8			1.0	0.0
CV-24160	7/16/2026 2:50:10 PM	43.5	51.4	0.0	5.1			0.8	0.0
CV-24160	7/16/2026 2:51:27 PM	44.2	50.8	0.0	5.0			0.9	0.0
CV-24161	7/7/2026 2:17:35 PM	20.8	78.9	0.3	0.0			0.3	0.0
CV-24161	7/7/2026 2:18:47 PM	32.8	66.4	0.0	0.8			0.5	0.0
CV-24161	7/8/2026 2:54:28 PM	53.3	46.7	0.0	0.0			1.1	0.0
CV-24161	7/8/2026 2:55:35 PM	51.6	48.4	0.0	0.0			1.1	0.0
CV-24162	7/6/2026 12:09:43 PM	34.6	34.1	0.8	30.5			1.0	38.1
CV-24163	7/6/2026 10:51:03 AM	27.7	72.0	0.0	0.3			0.4	0.0
CV-24164	7/6/2026 2:59:38 PM	40.7	58.3	0.0	1.0			0.7	0.0
CV-24164	7/17/2026 8:21:20 AM	36.8	58.7	0.0	4.5			0.6	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24165	7/2/2026 10:25:28 AM	25.9	62.8	0.0	11.3			0.4	0.0
CV-24165	7/22/2026 8:18:17 AM	29.5	61.8	0.0	8.7			0.5	0.0
CV-24166	7/1/2026 1:16:33 PM	53.5	40.0	0.1	6.4			1.3	71.2
CV-24166	7/16/2026 2:23:51 PM	49.1	46.0	0.0	5.0			1.1	0.0
CV-24167	7/1/2026 1:36:53 PM	44.8	37.1	0.0	18.2			1.2	0.0
CV-24167	7/28/2026 8:36:37 AM	45.1	40.5	0.0	14.4			1.1	0.0
CV-24168	7/2/2026 12:22:20 PM	35.9	43.8	0.0	20.3			0.8	0.0
CV-24168	7/22/2026 8:22:36 AM	27.3	48.0	0.1	24.6			0.6	246.0
CV-24169	7/6/2026 2:56:17 PM	31.8	39.4	0.0	28.8			0.8	0.0
CV-24169	7/17/2026 8:24:21 AM	35.9	40.4	0.0	23.7			0.9	0.0
CV-24170	7/6/2026 3:57:46 PM	20.7	76.1	0.0	3.2			0.3	0.0
CV-24170	7/6/2026 3:59:49 PM	15.6	80.9	0.0	3.5			0.2	0.0
CV-24170	7/13/2026 10:36:08 AM	11.9	73.2	0.0	15.0			0.2	0.0
CV-24170	7/13/2026 10:37:39 AM	11.3	74.7	0.0	14.0			0.2	0.0
CV-24170	7/29/2026 8:57:26 AM	13.9	86.0	0.1	0.0			0.2	0.0
CV-24171	7/7/2026 2:44:27 PM	50.9	49.1	0.0	0.0			1.0	0.0
CV-24171	7/28/2026 8:48:55 AM	52.2	46.1	0.0	1.7			1.1	0.0
CV-24172	7/7/2026 12:29:38 PM	34.1	37.3	4.5	24.1			0.9	5.4
CV-24172	7/22/2026 9:55:02 AM	37.0	34.3	3.7	25.0			1.1	6.8
CV-24173	7/13/2026 11:49:25 AM	34.4	51.4	0.0	14.2			0.7	0.0
CV-24173	7/19/2026 1:43:48 PM	34.8	52.5	0.0	12.7			0.7	0.0
CV-24173	7/19/2026 1:45:39 PM	34.0	53.3	0.0	12.8			0.6	0.0
CV-24174	7/13/2026 9:26:49 AM	20.6	37.4	0.0	42.0			0.5	0.0
CV-24174	7/13/2026 9:29:10 AM	19.0	33.5	0.0	47.5			0.6	0.0
CV-24174	7/19/2026 1:34:46 PM	18.3	64.7	0.0	17.0			0.3	0.0
CV-24175	7/7/2026 11:47:48 AM	22.0	48.1	0.3	29.6			0.5	98.7

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24175	7/13/2026 7:13:50 AM	22.8	48.6	0.0	28.6			0.5	0.0
CV-24175	7/13/2026 7:16:51 AM	22.8	52.1	0.0	25.1			0.4	0.0
CV-24175	7/19/2026 1:25:17 PM	20.6	70.2	0.0	9.2			0.3	0.0
CV-24176	7/7/2026 11:57:12 AM	31.7	48.2	0.0	20.1			0.7	0.0
CV-24176	7/16/2026 9:57:20 AM	32.9	46.7	0.0	20.4			0.7	0.0
CV-24177	7/3/2026 8:50:27 AM	9.8	81.8	0.6	7.8			0.1	13.0
CV-24177	7/20/2026 1:38:05 PM	8.8	77.1	0.0	14.1			0.1	0.0
CV-24178	7/7/2026 11:52:46 AM	24.9	48.7	0.7	25.7			0.5	36.7
CV-24178	7/7/2026 11:54:03 AM	24.6	46.4	0.9	28.1			0.5	31.2
CV-24178	7/16/2026 10:01:44 AM	23.8	41.9	0.9	33.4			0.6	37.1
CV-24178	7/16/2026 10:02:55 AM	23.3	40.6	0.2	35.9			0.6	179.5
CV-24179	7/7/2026 12:05:35 PM	32.3	51.5	0.1	16.1			0.6	161.0
CV-24179	7/7/2026 12:07:10 PM	32.7	51.8	0.0	15.5			0.6	0.0
CV-24179	7/16/2026 9:47:20 AM	28.4	56.2	0.0	15.4			0.5	0.0
CV-24179	7/16/2026 9:48:41 AM	28.0	57.0	0.0	15.0			0.5	0.0
CV-24180	7/1/2026 3:43:22 PM	22.0	43.0	0.5	34.5			0.5	69.0
CV-24180	7/16/2026 10:10:17 AM	21.4	39.1	0.8	38.7			0.5	48.4
CV-24181	7/1/2026 3:45:28 PM	34.9	56.0	0.0	9.1			0.6	0.0
CV-24181	7/16/2026 10:05:46 AM	29.6	45.6	0.0	24.8			0.6	0.0
CV-24182	7/1/2026 3:56:52 PM	35.6	44.4	0.2	19.8			0.8	99.0
CV-24182	7/28/2026 9:23:56 AM	35.0	45.3	0.0	19.7			0.8	0.0
CV-24183	7/1/2026 4:06:34 PM	48.5	50.6	0.5	0.4			1.0	0.8
CV-24183	7/16/2026 2:54:48 PM	41.5	27.4	0.1	31.0			1.5	310.0
CV-24184	7/6/2026 10:20:25 AM	6.3	6.7	14.8	72.2			0.9	4.9
CV-24184	7/6/2026 10:21:53 AM	6.3	8.1	14.6	71.0			0.8	4.9
CV-24184	7/16/2026 3:19:56 PM	43.6	43.7	0.0	12.7			1.0	0.0
CV-24184	7/16/2026 3:20:01 PM	43.6	43.7	0.0	12.7			1.0	0.0
CV-24184	7/16/2026 3:21:33 PM	45.0	47.5	0.0	7.5			0.9	0.0
CV-24185	7/6/2026 10:33:38 AM	44.3	46.7	0.0	9.0			0.9	0.0
CV-24185	7/16/2026 3:10:44 PM	46.2	52.0	0.0	1.8			0.9	0.0
CV-24186	7/6/2026 10:53:50 AM	41.1	41.4	1.2	16.3			1.0	13.6
CV-24186	7/31/2026 9:06:58 AM	46.1	50.7	0.1	3.1			0.9	31.0
CV-24187	7/3/2026 8:45:32 AM	45.7	47.3	0.0	7.0			1.0	0.0
CV-24187	7/28/2026 10:01:22 AM	49.4	50.5	0.0	0.1			1.0	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24188	7/3/2026 8:18:13 AM	50.1	44.5	0.0	5.4			1.1	0.0
CV-24188	7/20/2026 10:23:42 AM	50.5	44.6	0.0	4.9			1.1	0.0
CV-24189	7/3/2026 8:22:16 AM	43.5	39.6	0.4	16.5			1.1	41.3
CV-24189	7/20/2026 10:19:56 AM	45.8	36.0	2.7	15.5			1.3	5.7
CV-24190	7/3/2026 9:31:48 AM	51.1	44.7	0.1	4.1			1.1	41.0
CV-24190	7/28/2026 10:06:36 AM	49.7	45.8	0.1	4.4			1.1	44.0
CV-24192	7/3/2026 9:29:59 AM	50.5	43.4	0.0	6.1			1.2	0.0
CV-24192	7/28/2026 10:10:00 AM	51.4	45.4	0.0	3.2			1.1	0.0
CV-24193	7/1/2026 3:06:38 PM	50.2	43.6	0.1	6.1			1.2	61.0
CV-24193	7/16/2026 10:16:18 AM	48.2	43.1	0.0	8.7			1.1	0.0
CV-24194	7/1/2026 3:49:34 PM	52.0	47.1	0.0	0.9			1.1	0.0
CV-24194	7/16/2026 2:16:21 PM	49.3	45.9	0.1	4.7			1.1	47.0
CV-24195	7/1/2026 10:55:30 AM	51.9	44.3	0.0	3.8			1.2	0.0
CV-24195	7/16/2026 2:22:23 PM	48.1	47.6	0.0	4.3			1.0	0.0
CV-24196	7/1/2026 10:39:45 AM	47.4	49.1	0.0	3.5			1.0	0.0
CV-24196	7/16/2026 2:59:29 PM	46.8	51.0	0.0	2.2			0.9	0.0
CV-24197	7/7/2026 3:12:35 PM	43.0	44.2	0.0	12.8			1.0	0.0
CV-24197	7/31/2026 9:01:20 AM	51.8	42.7	0.0	5.5			1.2	0.0
CV-24198	7/1/2026 10:51:11 AM	40.2	41.5	0.0	18.3			1.0	0.0
CV-24198	7/31/2026 10:02:49 AM	56.2	41.5	0.0	2.3			1.4	0.0
CV-24199	7/1/2026 10:46:03 AM	45.9	43.9	0.0	10.2			1.0	0.0
CV-24199	7/31/2026 9:58:44 AM	46.9	41.0	0.0	12.1			1.1	0.0
CV-24200	7/1/2026 8:49:29 AM	46.3	40.6	0.0	13.1			1.1	0.0
CV-24200	7/31/2026 9:37:53 AM	47.2	40.0	0.0	12.8			1.2	0.0
CV-24201	7/1/2026 9:13:06 AM	41.2	41.3	0.0	17.5			1.0	0.0
CV-24201	7/31/2026 8:51:59 AM	40.5	37.2	2.4	19.9			1.1	8.3
CV-24202	7/1/2026 9:25:34 AM	37.3	40.2	0.0	22.5			0.9	0.0
CV-24202	7/31/2026 8:34:50 AM	25.1	29.8	0.4	44.7			0.8	111.8
CV-24203	7/1/2026 7:48:19 AM	48.3	42.7	0.0	9.0			1.1	0.0
CV-24203	7/28/2026 1:14:17 PM	45.5	39.5	0.0	15.0			1.2	0.0
CV-24203	7/28/2026 1:19:47 PM	44.7	40.5	0.0	14.8			1.1	739.0
CV-24204	7/1/2026 7:53:18 AM	50.2	47.2	0.0	2.6			1.1	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24204	7/28/2026 1:25:26 PM	47.1	44.4	0.0	8.5			1.1	0.0
CV-24205	7/1/2026 8:20:01 AM	44.7	40.3	0.0	15.0			1.1	0.0
CV-24205	7/28/2026 1:31:58 PM	44.4	39.3	0.0	16.3			1.1	0.0
CV-24205	7/28/2026 1:33:51 PM	44.1	39.4	0.0	16.6			1.1	0.0
CV-24206	7/1/2026 8:55:19 AM	23.4	30.5	0.6	45.5			0.8	75.8
CV-24206	7/31/2026 8:54:17 AM	23.0	28.1	0.6	48.3			0.8	80.5
CV-24207	7/1/2026 1:28:15 PM	45.8	48.4	0.0	5.8			0.9	0.0
CV-24207	7/1/2026 1:31:42 PM	45.2	48.9	0.0	5.9			0.9	0.0
CV-24207	7/16/2026 2:04:54 PM	45.8	49.6	0.0	4.7			0.9	0.0
CV-24207	7/16/2026 2:08:41 PM	45.7	49.0	0.0	5.3			0.9	0.0
CV-24207	7/16/2026 2:09:52 PM	45.2	49.7	0.0	5.0			0.9	0.0
CV-24208	7/9/2026 1:33:32 PM	44.1	50.3	0.0	5.6			0.9	0.0
CV-24209	7/1/2026 10:07:13 AM	15.1	69.2	0.2	15.5			0.2	77.5
CV-24210	7/6/2026 12:13:38 PM	41.8	40.0	0.0	18.2			1.0	0.0
CV-24211	7/15/2026 10:55:22 AM	19.4	72.0	0.0	8.6			0.3	0.0
CV-24212	7/15/2026 10:48:49 AM	16.3	60.3	0.4	23.0			0.3	57.5
CV-24213	7/6/2026 11:00:04 AM	47.8	47.0	0.0	5.2			1.0	0.0
CV-24213	7/6/2026 11:01:11 AM	48.5	45.0	0.0	6.5			1.1	0.0
CV-24214	7/7/2026 9:51:22 AM	31.9	36.0	1.4	30.7			0.9	21.9
CV-24215	7/8/2026 3:28:03 PM	45.4	49.6	0.0	5.0			0.9	0.0
CV-24216	7/6/2026 11:20:47 AM	42.4	42.6	0.0	15.0			1.0	0.0
CV-24217	7/2/2026 11:20:03 AM	46.7	51.4	0.0	1.9			0.9	0.0
CV-24218	7/6/2026 10:27:41 AM	49.8	45.2	0.0	5.0			1.1	0.0
CV-24219	7/2/2026 9:34:00 AM					3240			
CV-24219	7/2/2026 9:51:06 AM	9.9	77.0	0.0	13.1			0.1	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-24219	7/2/2026 9:51:58 AM	14.6	82.3	0.0	3.1			0.2	0.0
CV-24219	7/9/2026 9:40:00 AM					3520			
CV-24219	7/9/2026 9:40:00 AM						84700		
CV-24219	7/9/2026 9:41:25 AM	13.1	79.8	0.0	7.1			0.2	0.0
CV-24219	7/16/2026 9:39:52 AM	19.0	74.6	0.0	6.4			0.3	0.0
CV-24219	7/16/2026 9:45:00 AM					3690			
CV-24219	7/30/2026 8:40:54 AM	28.3	67.2	0.0	4.5			0.4	0.0
CV-24220	7/6/2026 11:00:13 AM	15.2	39.6	1.2	44.0			0.4	36.7
CV-24221	7/15/2026 1:49:24 PM	47.1	44.7	0.2	8.0			1.1	40.0
CV-24222	7/15/2026 10:36:12 AM	50.4	40.6	0.1	8.9			1.2	89.0
CV-24223	7/30/2026 10:04:38 AM	29.7	47.4	4.3	18.6			0.6	4.3
CV-24224	7/6/2026 10:22:07 AM	46.7	46.6	0.3	6.4			1.0	21.3
CV-24225	7/7/2026 1:39:40 PM	50.9	47.3	0.0	1.8			1.1	0.0
CV-24225	7/7/2026 1:42:58 PM	51.8	45.3	0.0	2.9			1.1	0.0
CV-24225	7/8/2026 8:07:51 AM	48.7	38.3	2.2	10.8			1.3	4.9
CV-24226	7/15/2026 10:59:16 AM	19.8	70.9	2.4	6.9			0.3	2.9
CV-24227	7/3/2026 9:35:57 AM	48.1	41.1	0.0	10.8			1.2	0.0
CV-24231	7/8/2026 10:36:56 AM	42.1	41.0	0.0	16.9			1.0	0.0
CV-24236	7/3/2026 10:02:29 AM	35.3	31.8	0.0	32.9			1.1	0.0
CV-24237	7/3/2026 10:06:25 AM	35.4	33.8	0.2	30.6			1.0	153.0
CV-24243	7/7/2026 1:18:13 PM	23.0	18.1	9.5	49.4			1.3	5.2
CV-24243	7/7/2026 1:22:47 PM	19.2	15.4	10.9	54.5			1.2	5.0
CV-24243	7/7/2026 1:34:56 PM	26.4	21.4	8.8	43.4			1.2	4.9
CV-24244	7/7/2026 1:41:19 PM	47.2	38.5	0.5	13.8			1.2	27.6
CV-24245	7/7/2026 12:39:44 PM	53.0	40.9	0.0	6.1			1.3	0.0
CV-24246	7/7/2026 12:36:10 PM	54.1	42.9	0.0	3.0			1.3	0.0
CV-24253	7/7/2026 12:47:31 PM	53.5	42.7	0.0	3.8			1.3	0.0
CV-25	7/9/2026 11:25:13 AM	0.0	0.8	20.1	79.1			0.0	3.9
CV-25	7/9/2026 11:27:02 AM	7.5	3.9	17.6	71.0			1.9	4.0
CV-2501	7/1/2026 3:25:30 PM	50.8	47.9	0.0	1.3			1.1	0.0
CV-2502	7/1/2026 3:10:48 PM	47.3	44.9	0.1	7.7			1.1	77.0
CV-2503	7/1/2026 8:33:56 AM	46.4	42.4	0.0	11.2			1.1	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-2504	7/8/2026 10:32:18 AM	47.1	41.5	0.0	11.4			1.1	0.0
CV-2505	7/7/2026 3:22:12 PM	45.6	43.0	0.1	11.3			1.1	113.0
CV-2506	7/7/2026 3:27:25 PM	42.3	41.0	0.0	16.7			1.0	0.0
CV-2507	7/7/2026 3:30:21 PM	50.3	44.3	0.0	5.4			1.1	0.0
CV-2508	7/8/2026 10:25:00 AM	50.6	42.3	0.0	7.1			1.2	0.0
CV-2509	7/8/2026 10:07:20 AM	49.5	40.7	0.0	9.8			1.2	0.0
CV-2510	7/8/2026 10:20:42 AM	52.5	42.0	0.0	5.5			1.3	0.0
CV-25100D	7/6/2026 1:51:46 PM	11.9	52.0	0.2	35.9			0.2	179.5
CV-25100D	7/23/2026 9:38:21 AM	8.9	64.3	0.0	26.8			0.1	0.0
CV-25100D	7/27/2026 1:20:17 PM	34.3	48.7	0.0	17.0			0.7	0.0
CV-25100S	7/6/2026 1:36:14 PM	11.4	74.7	0.0	13.9			0.2	0.0
CV-25100S	7/6/2026 1:50:00 PM					3490			
CV-25100S	7/13/2026 1:06:47 PM	4.4	77.0	0.0	18.6			0.1	0.0
CV-25100S	7/13/2026 1:15:00 PM					3630			
CV-25100S	7/20/2026 10:16:41 AM	16.6	73.8	0.0	9.6			0.2	0.0
CV-25100S	7/20/2026 10:17:24 AM	17.4	74.6	0.0	8.0			0.2	0.0
CV-25100S	7/20/2026 10:35:00 AM					3170			
CV-25100S	7/27/2026 1:24:21 PM	13.2	70.7	0.0	16.1			0.2	0.0
CV-25101D	7/6/2026 10:26:33 AM	9.2	69.5	2.1	19.2			0.1	9.1
CV-25101D	7/20/2026 9:01:51 AM	6.8	54.5	4.5	34.2			0.1	7.6
CV-25101S	7/6/2026 10:28:38 AM	23.5	57.4	0.1	19.0			0.4	190.0
CV-25101S	7/20/2026 9:03:57 AM	14.9	41.1	0.3	43.7			0.4	145.7
CV-25102	7/6/2026 10:37:26 AM	10.5	56.5	4.4	28.6			0.2	6.5
CV-25102	7/23/2026 9:32:59 AM	3.5	74.9	0.7	20.9			0.0	29.9
CV-25103	7/6/2026 10:03:22 AM	30.5	34.3	0.1	35.1			0.9	351.0
CV-25103	7/27/2026 2:29:26 PM	20.8	30.2	0.6	48.4			0.7	80.7
CV-25104D	7/8/2026 12:30:04 PM	6.4	71.7	2.7	19.2			0.1	7.1
CV-25104D	7/21/2026 1:22:18 PM	3.2	76.6	0.4	19.8			0.0	49.5
CV-25104S	7/2/2026 1:43:30 PM	11.6	81.3	0.0	7.1			0.1	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-25104S	7/8/2026 12:33:30 PM	8.3	78.0	0.4	13.3			0.1	33.3
CV-25104S	7/21/2026 1:17:04 PM	2.3	64.1	3.7	29.9			0.0	8.1
CV-25105D	7/6/2026 9:46:11 AM	31.6	30.4	8.4	29.6			1.0	3.5
CV-25105D	7/6/2026 9:47:55 AM	33.8	32.2	7.2	26.8			1.0	3.7
CV-25105D	7/20/2026 9:15:48 AM	17.0	74.4	0.2	8.4			0.2	42.0
CV-25105S	7/6/2026 9:40:39 AM	11.4	12.9	12.3	63.4			0.9	5.2
CV-25105S	7/6/2026 9:41:26 AM	12.1	12.6	12.6	62.7			1.0	5.0
CV-25105S	7/20/2026 9:18:29 AM	2.0	10.1	17.1	70.8			0.2	4.1
CV-25105S	7/20/2026 9:19:47 AM	1.9	6.5	17.9	73.7			0.3	4.1
CV-25106D	7/8/2026 12:21:49 PM	5.1	38.1	11.0	45.8			0.1	4.2
CV-25106D	7/8/2026 12:22:37 PM	5.5	38.0	11.0	45.5			0.1	4.1
CV-25106D	7/9/2026 3:25:27 PM	1.9	27.9	12.3	57.9			0.1	4.7
CV-25106D	7/9/2026 3:27:08 PM	1.3	18.3	15.2	65.2			0.1	4.3
CV-25106D	7/21/2026 1:33:34 PM	10.2	35.6	9.7	44.5			0.3	4.6
CV-25106S	7/8/2026 12:25:20 PM	19.6	32.8	11.7	35.9			0.6	3.1
CV-25106S	7/8/2026 12:26:22 PM	21.0	34.5	10.9	33.6			0.6	3.1
CV-25106S	7/21/2026 1:25:58 PM	8.8	41.2	8.0	42.0			0.2	5.3
CV-25107D	7/2/2026 10:50:21 AM	2.6	80.6	0.1	16.7			0.0	167.0
CV-25107D	7/21/2026 10:03:10 AM	1.7	80.6	0.0	17.7			0.0	0.0
CV-25107S	7/2/2026 10:46:50 AM	45.5	51.2	0.0	3.3			0.9	0.0
CV-25107S	7/20/2026 8:38:14 AM	57.0	39.5	0.4	3.1			1.4	7.7
CV-25107S	7/21/2026 10:06:29 AM	52.8	45.6	0.0	1.6			1.2	0.0
CV-2511	7/8/2026 10:47:35 AM	46.3	41.7	0.0	12.0			1.1	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-2512	7/8/2026 10:52:13 AM	43.5	40.4	0.0	16.1			1.1	0.0
CV-2513	7/7/2026 1:03:46 PM	48.1	38.8	0.0	13.1			1.2	0.0
CV-2514	7/7/2026 12:27:36 PM	55.7	42.1	0.0	2.2			1.3	0.0
CV-2514	7/7/2026 12:28:19 PM	55.5	41.8	0.0	2.7			1.3	0.0
CV-2514	7/7/2026 12:28:46 PM	55.6	41.5	0.0	2.9			1.3	0.0
CV-2515	7/9/2026 11:04:39 AM	43.2	29.9	0.4	26.5			1.4	66.3
CV-2516	7/6/2026 11:26:24 AM	50.8	43.9	0.0	5.3			1.2	0.0
CV-2516	7/20/2026 9:44:48 AM	46.6	37.0	2.6	13.8			1.3	5.3
CV-2517	7/9/2026 11:37:20 AM	37.0	31.7	0.1	31.2			1.2	312.0
CV-2518	7/9/2026 11:46:28 AM	39.9	34.2	0.3	25.6			1.2	85.3
CV-2519	7/6/2026 10:07:30 AM	44.9	41.2	0.0	13.9			1.1	0.0
CV-2520	7/6/2026 10:18:34 AM	33.0	50.5	0.1	16.4			0.7	164.0
CV-2520	7/6/2026 10:21:32 AM	33.0	51.2	0.0	15.8			0.6	0.0
CV-2521	7/8/2026 2:50:11 PM	39.6	52.1	0.0	8.3			0.8	0.0
CV-2521	7/8/2026 2:51:44 PM	38.6	51.9	0.0	9.5			0.7	0.0
CV-2522	7/8/2026 12:50:04 PM	39.8	46.5	0.0	13.7			0.9	0.0
CV-2522	7/8/2026 12:51:07 PM	39.6	48.6	0.0	11.8			0.8	0.0
CV-2523	7/8/2026 12:35:59 PM	52.2	43.2	0.0	4.6			1.2	0.0
CV-2524	7/15/2026 1:31:35 PM	27.6	46.0	0.0	26.4			0.6	0.0
CV-2524	7/16/2026 1:43:13 PM	53.6	41.9	0.0	4.5			1.3	0.0
CV-2524	7/16/2026 1:45:00 PM					164			
CV-2524	7/16/2026 1:45:33 PM	54.5	45.5	0.0	0.0			1.2	0.0
CV-2524	7/22/2026 3:00:48 PM	53.7	46.3	0.0	0.0			1.2	0.0
CV-2525	7/8/2026 12:22:47 PM	33.7	37.4	0.0	28.9			0.9	0.0
CV-2526	7/8/2026 12:18:22 PM	47.7	42.0	0.0	10.3			1.1	0.0
CV-2527	7/2/2026 11:38:52 AM	36.6	39.8	3.8	19.8			0.9	5.2
CV-2527	7/2/2026 11:42:07 AM	37.8	40.8	3.1	18.3			0.9	5.9
CV-2527	7/6/2026 9:44:55 AM	44.4	48.9	0.0	6.7			0.9	0.0
CV-2527	7/6/2026 9:45:16 AM	45.2	50.2	0.0	4.6			0.9	0.0
CV-2527	7/30/2026 10:09:39 AM	42.4	47.2	0.1	10.3			0.9	103.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-2528	7/6/2026 9:46:49 AM	45.7	35.3	0.2	18.8			1.3	94.0
CV-2529	7/7/2026 12:22:38 PM	46.9	39.0	2.4	11.7			1.2	4.9
CV-2529	7/16/2026 1:49:16 PM	21.3	17.2	13.6	47.9			1.2	3.5
CV-2529	7/16/2026 1:50:34 PM	20.3	15.9	13.9	49.9			1.3	3.6
CV-2530	7/6/2026 12:09:42 PM	31.9	57.0	0.0	11.1			0.6	0.0
CV-2530	7/6/2026 12:10:39 PM	32.9	55.8	0.0	11.3			0.6	0.0
CV-2531	7/6/2026 12:01:36 PM	28.2	60.0	0.0	11.8			0.5	0.0
CV-2531	7/6/2026 12:02:52 PM	28.1	60.1	0.0	11.8			0.5	0.0
CV-2532	7/6/2026 11:55:09 AM	50.2	45.3	0.0	4.5			1.1	0.0
CV-2533	7/6/2026 11:48:36 AM	50.5	45.2	0.1	4.2			1.1	42.0
CV-2534	7/6/2026 11:41:45 AM	52.0	45.2	0.0	2.8			1.2	0.0
CV-2535	7/1/2026 7:30:47 AM	24.3	25.6	0.2	49.9			0.9	249.5
CV-2536	7/9/2026 9:16:39 AM	42.6	39.6	2.3	15.5			1.1	6.7
CV-2537	7/1/2026 8:11:38 AM	45.3	40.8	0.1	13.8			1.1	138.0
CV-2538	7/1/2026 8:03:31 AM	41.9	39.5	0.0	18.6			1.1	0.0
CV-2539	7/1/2026 3:03:38 PM	37.5	40.1	0.3	22.1			0.9	73.7
CV-2539	7/16/2026 10:13:17 AM	37.5	42.4	0.0	20.1			0.9	0.0
CV-2540	7/6/2026 4:05:31 PM	7.9	85.6	0.0	6.5			0.1	0.0
CV-2540	7/6/2026 4:06:42 PM	6.0	84.5	0.0	9.5			0.1	0.0
CV-2540	7/17/2026 8:16:47 AM	5.8	82.9	0.0	11.3			0.1	0.0
CV-2541	7/7/2026 9:23:24 AM	1.4	84.3	0.0	14.3			0.0	0.0
CV-2541	7/29/2026 9:20:26 AM	31.5	55.2	0.1	13.2			0.6	132.0
CV-2542	7/6/2026 12:51:45 PM	42.0	58.0	0.0	0.0			0.7	0.0
CV-2542	7/22/2026 8:26:21 AM	47.0	49.6	0.0	3.4			0.9	0.0
CV-2543-PLR	7/6/2026 3:12:48 PM	31.0	64.8	0.1	4.1			0.5	41.0
CV-2543-PLR	7/17/2026 7:57:38 AM	26.8	54.2	2.0	17.0			0.5	8.5
CV-2544	7/9/2026 1:34:27 PM	10.5	87.9	0.0	1.6			0.1	0.0
CV-2544	7/9/2026 1:36:07 PM	9.8	90.1	0.0	0.1			0.1	0.0
CV-2544	7/17/2026 10:00:41 AM	10.2	78.7	0.0	11.1			0.1	0.0
CV-2544	7/17/2026 10:02:08 AM	9.5	78.4	0.0	12.1			0.1	0.0
CV-2545	7/2/2026 3:43:52 PM	35.2	63.7	0.5	0.6			0.6	1.2
CV-2545	7/22/2026 2:10:43 PM	37.5	62.0	0.0	0.5			0.6	0.0
CV-2546	7/2/2026 3:39:52 PM	23.3	69.2	0.0	7.5			0.3	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-2546	7/2/2026 3:41:04 PM	24.5	71.4	0.0	4.1			0.3	0.0
CV-2546	7/22/2026 2:14:01 PM	24.6	67.9	0.0	7.5			0.4	0.0
CV-2547	7/7/2026 2:22:04 PM	45.8	49.5	0.0	4.7			0.9	0.0
CV-2548	7/2/2026 11:51:45 AM	6.4	85.5	0.0	8.1			0.1	0.0
CV-2548	7/2/2026 11:53:07 AM	6.2	90.4	0.0	3.4			0.1	0.0
CV-2548	7/19/2026 12:37:51 PM	7.2	74.4	0.0	18.3			0.1	0.0
CV-2548	7/19/2026 12:48:14 PM	6.8	75.4	0.0	17.8			0.1	0.0
CV-2548	7/30/2026 9:44:46 AM	7.2	77.0	0.0	15.8			0.1	0.0
CV-2548	7/30/2026 9:55:52 AM	7.2	76.9	0.0	15.9			0.1	0.0
CV-2548	7/30/2026 10:06:07 AM	6.8	76.9	0.0	16.3			0.1	0.0
CV-2549	7/2/2026 11:44:08 AM	35.1	58.7	0.0	6.2			0.6	0.0
CV-2549	7/19/2026 12:24:06 PM	36.9	55.5	0.0	7.7			0.7	0.0
CV-2549	7/19/2026 12:26:54 PM	35.4	56.7	0.0	8.0			0.6	0.0
CV-2549	7/30/2026 10:10:42 AM	36.0	57.1	0.0	7.0			0.6	0.0
CV-2549	7/30/2026 10:12:50 AM	36.6	56.5	0.0	6.9			0.6	0.0
CV-2550	7/6/2026 2:12:46 PM	18.3	75.7	0.0	6.0			0.2	0.0
CV-2550	7/6/2026 2:35:00 PM					2900			
CV-2550	7/6/2026 2:35:00 PM						114600		
CV-2550	7/15/2026 1:10:00 PM					2060			
CV-2550	7/15/2026 1:15:53 PM	14.7	75.4	0.0	9.9			0.2	0.0
CV-2550	7/28/2026 1:16:37 PM	19.8	78.3	0.0	1.9			0.3	0.0
CV-2550	7/28/2026 1:17:15 PM	19.1	78.5	0.0	2.4			0.2	0.0
CV-2551	7/2/2026 9:45:00 AM					2650			
CV-2551	7/2/2026 9:56:40 AM	13.6	81.0	0.0	5.4			0.2	0.0
CV-2551	7/9/2026 9:30:00 AM					4510			
CV-2551	7/9/2026 9:30:00 AM						81100		

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-2551	7/9/2026 9:34:42 AM	17.3	68.5	1.9	12.3			0.3	6.5
CV-2551	7/9/2026 9:35:40 AM	16.7	69.5	1.2	12.6			0.2	10.5
CV-2551	7/16/2026 10:58:39 AM	48.3	50.7	0.9	0.1			1.0	0.1
CV-2551	7/16/2026 10:59:26 AM	48.5	50.8	0.7	0.0			1.0	0.0
CV-2551	7/16/2026 11:00:00 AM					1880			
CV-2551	7/30/2026 8:34:53 AM	32.7	65.4	0.0	1.9			0.5	0.0
CV-2552	7/8/2026 12:12:15 PM	34.5	59.7	0.4	5.4			0.6	13.5
CV-2552	7/27/2026 2:39:02 PM	21.7	69.7	0.3	8.3			0.3	27.7
CV-2553	7/6/2026 3:28:02 PM	27.2	67.7	0.1	5.0			0.4	50.0
CV-2553	7/6/2026 3:29:35 PM	28.4	65.5	0.0	6.1			0.4	0.0
CV-2553	7/16/2026 2:50:41 PM	27.8	57.9	0.0	14.3			0.5	0.0
CV-2554	7/2/2026 10:28:28 AM	51.9	47.1	0.9	0.1			1.1	0.1
CV-2554	7/2/2026 10:30:00 AM					367			
CV-2554	7/29/2026 9:54:52 AM	30.6	62.7	0.3	6.4			0.5	21.3
CV-2554	7/29/2026 9:56:46 AM	26.5	61.9	0.9	10.7			0.4	11.9
CV-2555	7/2/2026 10:29:34 AM	33.3	61.2	0.2	5.3			0.5	26.5
CV-2555	7/21/2026 1:56:49 PM	39.4	60.6	0.0	0.0			0.7	0.0
CV-2555	7/22/2026 12:09:59 PM	37.9	54.4	0.0	7.7			0.7	0.0
CV-2555	7/22/2026 12:14:36 PM	31.7	61.2	0.0	7.1			0.5	0.0
CV-2556-PLR	7/6/2026 2:55:44 PM	12.6	79.3	0.4	7.7			0.2	19.3
CV-2556-PLR	7/6/2026 3:00:00 PM					3580			
CV-2556-PLR	7/6/2026 3:00:00 PM						107200		
CV-2556-PLR	7/15/2026 1:26:18 PM	9.8	76.9	0.0	13.3			0.1	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-2556-PLR	7/15/2026 1:30:00 PM					3220			
CV-2556-PLR	7/28/2026 1:24:55 PM	14.3	79.0	0.0	6.7			0.2	0.0
CV-2557	7/6/2026 9:34:25 AM	31.3	47.0	0.0	21.7			0.7	0.0
CV-2557	7/6/2026 9:35:26 AM	31.1	46.6	0.0	22.3			0.7	0.0
CV-2557	7/31/2026 8:57:06 AM	1.9	79.4	1.4	17.3			0.0	12.4
CV-2558-PLR	7/2/2026 9:22:49 AM	16.3	77.2	0.1	6.4			0.2	64.0
CV-2558-PLR	7/2/2026 9:25:00 AM					2800			
CV-2558-PLR	7/9/2026 9:54:46 AM	16.1	73.4	1.2	9.3			0.2	7.8
CV-2558-PLR	7/9/2026 9:55:00 AM					2200			
CV-2558-PLR	7/9/2026 9:55:00 AM						104400		
CV-2558-PLR	7/16/2026 9:55:00 AM					2520			
CV-2558-PLR	7/16/2026 9:56:07 AM	11.2	62.0	4.4	22.4			0.2	5.1
CV-2558-PLR	7/16/2026 10:01:19 AM	14.4	71.5	1.4	12.7			0.2	9.1
CV-2558-PLR	7/30/2026 10:36:54 AM	16.2	72.7	0.5	10.6			0.2	21.2
CV-2558-PLR	7/30/2026 10:37:41 AM	17.1	75.1	0.0	7.8			0.2	0.0
CV-2559	7/6/2026 10:36:34 AM	9.1	80.2	0.0	10.7			0.1	0.0
CV-2559	7/6/2026 10:38:03 AM	10.4	82.0	0.0	7.6			0.1	0.0
CV-2559	7/27/2026 2:33:18 PM	5.6	78.9	0.0	15.5			0.1	0.0
CV-2560	7/6/2026 10:11:08 AM	22.0	31.9	1.9	44.2			0.7	23.3
CV-2560	7/20/2026 8:57:37 AM	16.4	32.3	2.3	49.0			0.5	21.3

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-2561	7/6/2026 10:17:54 AM	11.0	39.6	1.9	47.5			0.3	25.0
CV-2561	7/20/2026 8:51:55 AM	10.9	37.2	1.5	50.4			0.3	33.6
CV-2562	7/6/2026 2:16:47 PM	41.4	53.1	0.0	5.5			0.8	0.0
CV-2563	7/8/2026 3:11:20 PM	41.2	54.6	0.0	4.2			0.8	0.0
CV-2564	7/7/2026 9:09:14 AM	41.9	54.5	0.0	3.6			0.8	0.0
CV-2564	7/16/2026 2:05:21 PM	26.3	64.4	0.0	9.3			0.4	0.0
CV-2565	7/1/2026 3:35:54 PM	38.5	44.2	0.0	17.3			0.9	0.0
CV-2565	7/16/2026 9:44:21 AM	36.6	40.9	0.0	22.5			0.9	0.0
CV-2566	7/1/2026 3:33:22 PM	48.7	47.8	0.0	3.5			1.0	0.0
CV-2566	7/16/2026 9:42:16 AM	47.9	45.1	0.0	7.0			1.1	0.0
CV-2567	7/1/2026 11:02:22 AM	49.0	47.9	0.0	3.1			1.0	0.0
CV-2567	7/16/2026 2:13:44 PM	47.9	49.1	0.1	2.9			1.0	29.0
CV-2568	7/1/2026 4:00:33 PM	40.1	46.7	0.0	13.2			0.9	0.0
CV-2568	7/16/2026 2:52:06 PM	34.6	42.1	0.0	23.3			0.8	0.0
CV-2569	7/1/2026 4:03:02 PM	44.4	52.1	0.0	3.5			0.9	0.0
CV-2569	7/16/2026 2:56:59 PM	42.3	44.5	0.0	13.2			1.0	0.0
CV-2570	7/6/2026 10:24:58 AM	50.9	44.2	0.1	4.8			1.2	48.0
CV-2570	7/16/2026 3:05:45 PM	50.2	46.6	0.0	3.2			1.1	0.0
CV-2571	7/7/2026 12:00:31 PM	50.4	38.5	0.0	11.1			1.3	0.0
CV-2572	7/7/2026 12:15:50 PM	51.4	38.2	0.0	10.4			1.3	0.0
CV-2610	7/25/2026 11:40:20 AM	56.1	40.8	0.0	3.1			1.4	0.0
CV-2610	7/25/2026 11:42:03 AM	55.0	41.0	0.0	3.9			1.3	0.0
CV-2610	7/25/2026 11:44:49 AM	53.7	42.0	0.0	4.3			1.3	0.0
CV-2610	7/26/2026 10:14:09 AM	53.9	41.2	0.0	4.9			1.3	0.0
CV-2610	7/26/2026 10:14:51 AM	53.6	41.5	0.0	5.0			1.3	0.0
CV-2663	7/22/2026 12:56:38 PM	18.4	43.6	3.8	34.3			0.4	9.1
CV-2663	7/22/2026 12:58:52 PM	3.9	12.8	17.6	65.7			0.3	3.7
CV-2663	7/22/2026 4:04:48 PM	15.4	50.5	0.0	34.1			0.3	3409.0
CV-2663	7/22/2026 4:08:46 PM	15.8	51.5	0.0	32.6			0.3	0.0
CV-2663	7/24/2026 10:42:38 AM	21.4	52.1	0.0	26.5			0.4	0.0
CV-2663	7/24/2026 10:44:41 AM	29.3	53.0	0.0	17.7			0.6	0.0
CV-2663	7/24/2026 10:48:15 AM	29.7	53.3	0.0	17.0			0.6	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-2663	7/24/2026 10:50:52 AM	31.1	53.9	0.0	15.0			0.6	0.0
CV-2663	7/26/2026 11:07:52 AM	31.7	52.5	0.0	15.8			0.6	0.0
CV-2680	7/15/2026 4:49:56 PM	45.3	43.1	0.0	11.7			1.1	0.0
CV-2680	7/15/2026 4:52:34 PM	44.6	43.0	0.0	12.5			1.0	0.0
CV-2680	7/20/2026 9:30:35 AM	42.8	46.7	0.0	10.5			0.9	0.0
CV-2680	7/20/2026 9:34:17 AM	43.3	46.0	0.0	10.8			0.9	0.0
CV-2680	7/20/2026 9:38:37 AM	42.6	45.8	0.0	11.6			0.9	0.0
CV-2680	7/20/2026 9:40:30 AM	42.9	46.5	0.0	10.6			0.9	0.0
CV-2680	7/21/2026 5:32:16 AM	36.2	43.6	0.0	20.2			0.8	0.0
CV-2680	7/22/2026 1:11:09 PM	37.7	46.9	0.0	15.5			0.8	0.0
CV-2680	7/22/2026 4:18:33 PM	38.7	43.8	0.0	17.5			0.9	0.0
CV-2680	7/24/2026 10:20:22 AM	46.0	43.9	0.0	10.1			1.0	0.0
CV-2680	7/24/2026 10:21:10 AM	47.4	43.4	0.0	9.2			1.1	0.0
CV-2687	7/21/2026 5:24:06 AM	51.9	38.9	0.0	9.1			1.3	0.0
CV-2687	7/22/2026 1:19:45 PM	54.8	41.9	0.0	3.4			1.3	0.0
CV-2687	7/22/2026 1:21:56 PM	53.3	42.7	0.0	4.0			1.3	0.0
CV-2687	7/22/2026 1:24:49 PM	52.9	43.0	0.0	4.2			1.2	0.0
CV-2687	7/22/2026 1:26:11 PM	52.7	43.0	0.0	4.3			1.2	0.0
CV-2687	7/22/2026 3:51:57 PM	54.8	40.2	0.0	5.0			1.4	0.0
CV-2687	7/22/2026 3:53:55 PM	54.3	41.1	0.0	4.7			1.3	0.0
CV-2688	7/29/2026 1:13:08 PM	52.6	41.5	0.1	4.3	0	1.5	1.3	43.0
CV-2688	7/29/2026 1:16:09 PM	53.5	42.4	0.1	2.8	0	1.2	1.3	28.0
CV-2688	7/30/2026 8:19:40 AM	56.8	39.8	0.0	3.4			1.4	0.0
CV-2688	7/30/2026 8:20:55 AM	55.5	40.8	0.0	3.7			1.4	0.0
CV-2689	7/20/2026 8:30:00 AM	1.3	60.6	2.2	36.0			0.0	16.7
CV-2689	7/20/2026 8:34:59 AM	1.3	65.1	0.1	33.5			0.0	372.1
CV-2689	7/20/2026 8:50:45 AM	1.3	64.3	0.8	33.7			0.0	42.1
CV-2689	7/20/2026 9:11:16 AM	1.4	65.2	0.0	33.4			0.0	0.0
CV-2689	7/20/2026 10:12:48 AM	1.3	66.4	1.8	30.5			0.0	16.9

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-2689	7/21/2026 5:46:41 AM	0.8	59.6	0.9	38.6			0.0	42.9
CV-2689	7/22/2026 1:43:50 PM	1.3	66.8	0.0	31.9			0.0	0.0
CV-2689	7/22/2026 1:50:59 PM	1.2	69.0	0.0	29.8			0.0	0.0
CV-2689	7/22/2026 4:29:54 PM	1.3	63.3	0.2	35.2			0.0	234.5
CV-2689	7/22/2026 4:34:31 PM	1.2	64.3	0.0	34.5			0.0	0.0
CV-2689	7/23/2026 12:43:00 PM	0.5	50.0	4.7	44.8			0.0	9.5
CV-2689	7/23/2026 12:48:08 PM	0.9	65.7	0.0	33.4			0.0	0.0
CV-2690	7/22/2026 3:28:21 PM	51.9	44.9	0.0	3.2			1.2	0.0
CV-2690	7/22/2026 3:30:50 PM	51.9	44.6	0.0	3.5			1.2	0.0
CV-2690	7/24/2026 10:07:33 AM	59.6	40.4	0.0	0.0			1.5	0.0
CV-2690	7/24/2026 10:09:10 AM	59.4	40.6	0.0	0.0			1.5	0.0
CV-2690	7/25/2026 12:07:22 PM	51.7	44.5	0.0	3.9			1.2	0.0
CV-2690	7/26/2026 10:30:30 AM	52.0	43.6	0.0	4.3			1.2	0.0
CV-2691	7/28/2026 9:40:50 AM	54.1	42.9	0.0	3.0			1.3	0.0
CV-2691	7/28/2026 12:47:38 PM	53.6	41.1	0.0	5.3			1.3	0.0
CV-48R	7/8/2026 3:14:46 PM	49.3	44.2	0.0	6.5			1.1	0.0
CV-52D	7/6/2026 10:15:17 AM	27.8	44.0	3.9	24.3			0.6	6.2
CV-55R	7/1/2026 2:40:00 PM					296			
CV-55R	7/1/2026 2:40:14 PM	53.3	46.6	0.1	0.0			1.1	0.0
CV-55R	7/1/2026 2:42:13 PM	53.6	46.2	0.2	0.0			1.2	0.0
CV-55R	7/2/2026 11:47:37 AM	25.1	43.6	3.5	27.8			0.6	7.9
CV-55R	7/9/2026 8:59:26 AM	41.1	47.0	0.1	11.8			0.9	118.0
CV-55R	7/9/2026 9:05:00 AM					380			
CV-55R	7/9/2026 9:05:00 AM						169200		
CV-55R	7/16/2026 9:15:15 AM	46.0	45.9	0.0	8.1			1.0	0.0
CV-55R	7/16/2026 9:20:00 AM					317			
CV-55R	7/22/2026 2:43:20 PM	53.6	44.5	0.0	1.9			1.2	0.0
CV-55R	7/22/2026 2:44:02 PM	54.3	45.7	0.0	0.0			1.2	0.0
CV-55R	7/30/2026 1:07:16 PM	43.3	50.8	0.0	5.9			0.9	0.0
CV-56D	7/29/2026 9:58:10 AM						29000		
CV-56D	7/29/2026 9:59:59 AM	52.4	45.8	0.0	0.0		1.8	1.1	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
CV-56D	7/29/2026 10:03:44 AM	51.9	42.8	0.0	3.4		1.9	1.2	0.0
CV-56D	7/29/2026 1:40:00 PM					1			
CV-56D	7/29/2026 1:40:00 PM						1000		
CV-56S	7/6/2026 9:52:49 AM	12.7	37.1	6.0	44.2			0.3	7.4
CV-56S	7/6/2026 9:55:21 AM	47.9	40.4	0.0	11.7			1.2	0.0
CV-56S	7/29/2026 10:14:57 AM						34000		
CV-56S	7/29/2026 10:18:52 AM	53.3	44.3	0.0	0.4		2	1.2	0.0
CV-56S	7/29/2026 1:30:00 PM					1			
CV-56S	7/29/2026 1:50:00 PM						1000		
CV-57R	7/6/2026 9:25:36 AM	50.8	41.4	0.0	7.8			1.2	0.0
CV-79R	7/6/2026 10:30:12 AM	48.2	43.5	0.0	8.3			1.1	0.0
CV-79R	7/6/2026 10:30:37 AM	48.0	45.0	0.0	7.0			1.1	0.0
CV-94	7/6/2026 9:22:39 AM	51.9	41.7	0.0	6.4			1.2	0.0
CV-95	7/6/2026 9:27:21 AM	50.4	41.5	0.0	8.1			1.2	0.0
CV-99	7/9/2026 7:45:00 AM					0			
CV-99	7/9/2026 7:45:00 AM						0		
CV-99	7/14/2026 1:09:14 PM	43.2	52.0	0.1	4.7			0.8	47.0
CV-99	7/23/2026 2:19:12 PM	20.1	31.0	11.1	37.8			0.6	3.4
CV-99	7/23/2026 2:19:57 PM	19.1	30.9	11.7	38.3			0.6	3.3
D-02	7/9/2026 10:23:12 AM	54.9	40.7	0.0	4.4			1.3	0.0
D-03	7/9/2026 10:26:06 AM	48.4	38.6	1.4	11.6			1.3	8.3
D-04	7/9/2026 10:28:32 AM	55.8	39.4	0.0	4.8			1.4	0.0
D-09	7/7/2026 12:07:51 PM	53.0	39.7	0.0	7.3			1.3	0.0
D-10	7/7/2026 11:45:01 AM	57.5	38.1	0.5	3.9			1.5	7.8
FP-001	7/6/2026 1:36:18 PM	15.0	20.0	5.1	59.9			0.8	11.7
FP-002	7/6/2026 1:39:31 PM	40.7	42.5	0.3	16.5			1.0	55.0
FP-003	7/6/2026 1:42:36 PM	30.9	38.7	3.4	27.0			0.8	7.9
FP-005	7/8/2026 1:43:07 PM	1.5	7.2	16.5	74.8			0.2	4.5
FP-006	7/6/2026 8:00:51 AM	23.3	74.1	0.0	2.6			0.3	0.0
FP-008	7/6/2026 7:43:30 AM	6.1	36.8	9.3	47.8			0.2	5.1
FP-009	7/2/2026 1:39:59 PM	11.2	74.4	0.0	14.4			0.2	0.0
FP-010	7/14/2026 10:08:14 AM	14.6	74.1	0.0	11.3			0.2	0.0
FP-011	7/8/2026 1:16:44 PM	24.2	60.3	2.4	13.1			0.4	5.5
FP-012	7/1/2026 8:59:25 AM	1.8	1.9	20.0	76.3			0.9	3.8
FP-013	7/1/2026 9:24:19 AM	2.8	5.5	16.5	75.2			0.5	4.6
FP-014	7/14/2026 10:13:32 AM	8.5	58.0	4.2	29.3			0.1	7.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
FP-015	7/14/2026 10:16:00 AM	1.2	13.0	17.0	68.8			0.1	4.0
FP-016	7/6/2026 7:58:28 AM	2.5	4.5	19.7	73.3			0.6	3.7
FP-017	7/8/2026 2:31:56 PM	37.3	26.0	5.7	31.0			1.4	5.4
FP-018	7/8/2026 10:37:14 AM	48.8	44.0	0.6	6.6			1.1	11.0
FP-019	7/1/2026 2:11:35 PM	54.7	43.9	0.0	1.4			1.2	0.0
FP-020	7/1/2026 2:26:14 PM	20.7	39.5	4.7	35.1			0.5	7.5
FP-021	7/1/2026 2:37:18 PM	7.0	22.2	11.6	59.2			0.3	5.1
FP-022	7/1/2026 2:31:49 PM	4.9	32.4	2.4	60.3			0.2	25.1
FP-023	7/1/2026 2:40:21 PM	1.7	8.1	16.8	73.4			0.2	4.4
FP-024	7/2/2026 2:14:20 PM	12.8	47.2	5.9	34.1			0.3	5.8
FP-025	7/2/2026 2:18:43 PM	13.5	38.5	5.3	42.7			0.4	8.1
FP-026	7/2/2026 2:27:09 PM	13.3	32.5	9.2	45.0			0.4	4.9
FP-027	7/14/2026 9:07:07 AM	15.3	29.8	7.7	47.2			0.5	6.1
FP-028	7/14/2026 9:09:50 AM	8.9	11.0	15.2	64.9			0.8	4.3
FP-029	7/8/2026 10:43:57 AM	49.7	45.4	0.0	4.9			1.1	0.0
FP-029	7/8/2026 2:35:22 PM	55.1	40.5	0.0	4.4			1.4	0.0
FP-030	7/1/2026 2:01:04 PM	53.1	40.5	0.7	5.7			1.3	8.1
FP-031	7/14/2026 9:20:58 AM	5.1	6.4	17.8	70.7			0.8	4.0
FP-032	7/1/2026 1:50:54 PM	16.1	26.0	9.2	48.7			0.6	5.3
FP-033	7/1/2026 1:45:21 PM	0.2	2.4	18.1	79.3			0.1	4.4
FP-034	7/14/2026 9:24:45 AM	4.5	6.6	14.7	74.2			0.7	5.0
FP-035	7/1/2026 1:36:10 PM	20.4	34.2	7.5	37.9			0.6	5.1
FP-036	7/1/2026 1:31:08 PM	17.3	26.6	8.1	48.0			0.7	5.9
FP-037	7/1/2026 10:17:41 AM	1.4	2.5	19.1	77.0			0.6	4.0
FP-038	7/7/2026 9:43:23 AM	34.0	32.0	3.6	30.4			1.1	8.4
FP-038	7/7/2026 10:42:42 AM	18.6	70.1	1.3	10.0			0.3	7.7
FP-039	7/7/2026 9:45:39 AM	44.9	38.0	1.7	15.4			1.2	9.1
FP-040	7/7/2026 10:31:45 AM	20.2	72.3	0.0	7.5			0.3	0.0
FP-041	7/7/2026 10:50:30 AM	12.9	26.6	5.2	55.3			0.5	10.6
FP-042	7/30/2026 10:53:26 AM	5.4	11.4	16.4	66.8			0.5	4.1
FP-043	7/7/2026 10:47:36 AM	5.8	18.7	12.8	62.7			0.3	4.9
FP-044	7/7/2026 10:44:58 AM	4.5	18.9	14.9	61.7			0.2	4.1
FP-045	7/16/2026 2:11:52 PM	0.1	4.4	19.8	75.7			0.0	3.8
FP-046	7/8/2026 1:39:49 PM	20.5	70.7	0.7	8.1			0.3	11.6
FP-046	7/16/2026 4:36:27 PM	15.0	53.8	6.2	25.0			0.3	4.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
FP-047	7/8/2026 1:46:52 PM	28.0	39.0	2.6	30.4			0.7	11.7
FP-050	7/2/2026 3:09:30 PM	11.9	25.5	10.8	51.8			0.5	4.8
FP-051	7/2/2026 3:00:23 PM	24.7	33.9	3.7	37.7			0.7	10.2
FP-052	7/6/2026 1:09:00 PM	3.0	9.7	16.5	70.8			0.3	4.3
FP-053	7/6/2026 12:56:22 PM	12.5	22.0	12.2	53.3			0.6	4.4
FP-054	7/2/2026 3:35:07 PM	21.5	33.3	3.3	41.9			0.6	12.7
FP-055	7/6/2026 3:04:30 PM	19.0	24.5	6.7	49.8			0.8	7.4
FP-056	7/6/2026 3:49:54 PM	10.7	18.5	11.0	59.8			0.6	5.4
FP-057	7/2/2026 10:40:18 AM	47.4	36.5	1.1	15.0			1.3	13.6
FP-058	7/2/2026 10:43:14 AM	36.8	31.2	4.0	28.0			1.2	7.0
FP-059	7/2/2026 1:16:15 PM	48.8	35.1	1.5	14.6			1.4	9.7
FP-060	7/2/2026 1:11:41 PM	5.6	5.7	17.3	71.4			1.0	4.1
FP-061	7/6/2026 7:53:11 AM	7.6	63.9	3.4	25.1			0.1	7.4
H-01 (EXP-01	7/13/2026 8:10:30 AM	12.8	48.2	0.0	39.0			0.3	0.0
H-01 (EXP-01	7/22/2026 9:38:27 AM	11.4	46.4	0.0	42.2			0.2	0.0
H-01 (EXP-01	7/27/2026 1:53:35 PM	9.7	42.6	0.1	47.6			0.2	476.0
H-02 (EXP-02	7/13/2026 7:58:53 AM	20.9	47.2	0.0	31.9			0.4	0.0
H-02 (EXP-02	7/22/2026 9:42:16 AM	42.3	47.0	0.0	10.7			0.9	0.0
H-02 (EXP-02	7/27/2026 1:51:19 PM	15.0	45.2	0.0	39.8			0.3	0.0
H-03 (EXP-03	7/13/2026 8:01:45 AM	51.0	48.5	0.0	0.5			1.1	0.0
H-03 (EXP-03	7/22/2026 9:44:31 AM	50.2	46.0	0.0	3.8			1.1	0.0
H-03 (EXP-03	7/27/2026 1:48:20 PM	50.6	43.6	0.1	5.7			1.2	57.0
H-04 (EXP-04	7/13/2026 8:07:00 AM	2.2	57.3	0.0	40.5			0.0	0.0
H-04 (EXP-04	7/13/2026 8:07:32 AM	2.3	55.6	0.0	42.1			0.0	0.0
H-04 (EXP-04	7/22/2026 9:47:27 AM	1.4	55.6	0.0	43.0			0.0	0.0
H-04 (EXP-04	7/22/2026 9:50:13 AM	1.6	56.0	0.0	42.4			0.0	0.0
H-08 (EXP-08	7/1/2026 10:41:09 AM	50.1	45.8	0.0	4.1			1.1	0.0
H-08 (EXP-08	7/22/2026 10:11:44 AM	49.3	44.9	0.0	5.8			1.1	0.0
H-10 (EXP-10	7/1/2026 10:32:28 AM	11.3	63.4	0.0	25.3			0.2	0.0
H-10 (EXP-10	7/31/2026 8:12:39 AM	11.4	73.3	0.0	15.3			0.2	0.0
H-101W-PLR	7/3/2026 10:24:03 AM	35.2	24.4	8.1	32.3			1.4	4.0
H-101W-PLR	7/3/2026 10:25:22 AM	34.0	24.6	8.6	32.8			1.4	3.8
H-102A	7/3/2026 10:16:34 AM	58.4	37.0	0.0	4.6			1.6	0.0
H-1401W	7/3/2026 10:18:08 AM	55.4	34.7	1.0	8.9			1.6	8.9

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
H-1404C	7/13/2026 11:16:46 AM	5.1	18.5	0.4	76.0			0.3	190.0
H-1404C	7/31/2026 9:11:09 AM	12.8	26.7	0.0	60.5			0.5	0.0
H-1405C	7/3/2026 9:19:48 AM	40.8	51.8	0.0	7.4			0.8	0.0
H-1405C	7/20/2026 10:05:45 AM	7.8	11.2	16.7	64.3			0.7	3.9
H-1406W	7/3/2026 7:52:35 AM	41.1	54.8	0.4	3.7			0.8	9.3
H-1406W	7/20/2026 12:49:05 PM	27.4	47.1	3.5	22.0			0.6	6.3
H-1408CR	7/1/2026 8:42:10 AM	5.3	14.5	8.4	71.8			0.4	8.5
H-1408CR	7/1/2026 8:44:56 AM	8.8	17.3	7.1	66.8			0.5	9.4
H-1408E	7/2/2026 12:38:06 PM	40.0	35.9	0.9	23.3			1.1	26.4
H-1408E	7/2/2026 12:40:12 PM	20.3	29.2	2.2	48.3			0.7	21.9
H-1408E	7/2/2026 12:41:18 PM	23.9	30.6	2.0	43.5			0.8	21.4
H-1408E	7/2/2026 1:12:43 PM	26.4	31.2	1.7	40.7			0.8	23.7
H-1408E	7/16/2026 1:43:57 PM	35.1	34.6	1.0	29.3			1.0	30.2
H-1408E	7/16/2026 1:49:15 PM	36.1	36.0	0.9	27.0			1.0	30.3
H-1408E	7/16/2026 1:50:44 PM	27.5	33.2	1.4	37.9			0.8	27.3
H-1408E	7/16/2026 1:51:40 PM	25.6	32.2	1.5	40.7			0.8	28.1
H-1408W	7/3/2026 8:28:12 AM	12.3	13.0	13.3	61.4			0.9	4.6
H-1408W	7/3/2026 8:30:59 AM	14.3	13.9	12.4	59.4			1.0	4.8
H-1409N	7/6/2026 10:40:14 AM	39.4	36.0	0.0	24.6			1.1	0.0
H-1409N	7/16/2026 3:17:34 PM	37.0	33.6	0.0	29.4			1.1	0.0
H-1410S	7/1/2026 8:07:41 AM	48.8	41.2	0.0	10.0			1.2	0.0
H-1563N	7/7/2026 9:58:28 AM	38.0	40.1	0.0	21.9			0.9	0.0
H-1563N	7/16/2026 2:29:54 PM	28.6	34.6	0.0	36.8			0.8	0.0
H-1563S	7/3/2026 9:15:46 AM	20.8	38.2	0.0	41.0			0.5	0.0
H-1563S	7/20/2026 10:01:37 AM	5.7	8.7	15.6	70.0			0.7	4.5
H-1565E	7/2/2026 10:08:57 AM	22.6	31.7	1.2	44.5			0.7	36.8
H-1565E	7/22/2026 8:15:26 AM	55.3	40.2	0.0	4.5			1.4	0.0
H-1568N	7/2/2026 1:23:44 PM	37.7	36.1	0.0	26.2			1.0	0.0
H-1568N	7/2/2026 1:25:23 PM	35.3	35.3	0.0	29.5			1.0	0.0
H-1568N	7/16/2026 1:07:53 PM	44.9	37.8	0.0	17.2			1.2	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
H-1568N	7/16/2026 1:19:13 PM	44.1	38.5	0.0	17.4			1.1	0.0
H-1568N	7/16/2026 1:19:55 PM	45.9	38.5	0.0	15.7			1.2	0.0
H-1571S	7/1/2026 10:25:36 AM	42.5	43.2	0.0	14.3			1.0	0.0
H-1572N	7/6/2026 10:41:59 AM	24.7	29.7	0.0	45.6			0.8	0.0
H-1572N	7/6/2026 10:43:57 AM	24.6	31.6	0.0	43.8			0.8	0.0
H-1572N	7/6/2026 10:44:40 AM	24.4	31.9	0.0	43.7			0.8	0.0
H-1572S	7/15/2026 1:05:33 PM	40.6	37.3	0.0	22.1			1.1	0.0
H-1574N	7/13/2026 9:47:50 AM	49.4	43.9	0.0	6.7			1.1	0.0
H-1753N	7/1/2026 2:14:02 PM	46.9	37.9	2.7	12.5			1.2	4.6
H-1753N	7/22/2026 1:43:28 PM	43.0	41.7	2.3	13.0			1.0	5.7
H-1753S	7/7/2026 9:40:17 AM	41.5	37.6	0.0	20.9			1.1	0.0
H-1753S	7/16/2026 2:36:10 PM	36.3	36.8	0.0	26.9			1.0	0.0
H-1756S	7/3/2026 9:02:07 AM	40.9	54.7	0.0	4.4			0.7	0.0
H-1756S	7/28/2026 1:12:47 PM	41.8	53.0	0.0	5.2			0.8	0.0
H-1757S	7/3/2026 9:22:05 AM	32.5	43.4	0.0	24.1			0.7	0.0
H-1757S	7/20/2026 10:13:09 AM	28.8	32.7	2.0	36.5			0.9	18.3
H-1760S	7/7/2026 12:16:26 PM	27.8	39.2	0.1	32.9			0.7	329.0
H-1760S	7/22/2026 9:58:10 AM	32.8	51.3	0.0	15.9			0.6	0.0
H-1762N	7/1/2026 1:22:19 PM	36.0	34.4	0.0	29.6			1.0	0.0
H-1762N	7/16/2026 2:13:18 PM	40.6	36.9	0.0	22.5			1.1	0.0
H-1762N	7/16/2026 2:16:39 PM	40.5	37.7	0.0	21.8			1.1	0.0
H-1763N	7/7/2026 2:30:01 PM	21.4	74.0	0.0	4.6			0.3	0.0
H-1763N	7/7/2026 2:31:23 PM	27.1	71.1	0.0	1.8			0.4	0.0
H-1763S	7/6/2026 12:41:01 PM	31.9	32.2	0.0	35.9			1.0	0.0
H-1764N	7/6/2026 12:28:11 PM	52.2	39.5	0.0	8.3			1.3	0.0
H-1764S	7/1/2026 10:17:27 AM	34.5	40.1	0.0	25.4			0.9	0.0
H-1767N	7/9/2026 1:46:00 PM	39.1	54.3	0.0	6.6			0.7	0.0
H-1769N	7/1/2026 9:05:19 AM	10.9	35.0	2.1	52.0			0.3	24.8
H-1769N	7/16/2026 10:27:47 AM	7.4	24.8	4.4	63.4			0.3	14.4
H-1770N	7/1/2026 9:15:45 AM	32.9	60.4	0.0	6.7			0.5	0.0
H-1770N	7/16/2026 10:37:30 AM	32.4	61.3	0.0	6.3			0.5	0.0
H-1770S	7/3/2026 7:24:24 AM	39.2	58.3	0.0	2.5			0.7	0.0
H-1770S	7/20/2026 10:19:12 AM	39.9	58.1	0.0	2.0			0.7	0.0
H-1771A	7/6/2026 2:01:03 PM	39.3	39.9	0.0	20.8			1.0	0.0
H-1771B	7/6/2026 9:52:22 AM	53.2	46.8	0.0	0.0			1.1	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
H-1774N	7/1/2026 9:32:28 AM	41.9	55.3	0.0	2.8			0.8	0.0
H-1774N	7/16/2026 10:45:57 AM	40.2	51.2	0.0	8.6			0.8	0.0
H-1801S	7/6/2026 10:55:07 AM	35.3	37.9	0.2	26.6			0.9	133.0
H-1802S	7/6/2026 10:35:07 AM	17.2	25.4	2.6	54.8			0.7	21.1
H-1802S	7/6/2026 10:36:34 AM	17.7	26.5	2.7	53.1			0.7	19.7
H-1802S	7/6/2026 10:38:21 AM	14.7	23.3	3.6	58.4			0.6	16.2
H-1803N-PLF	7/6/2026 9:40:00 AM					1540			
H-1803N-PLF	7/6/2026 9:40:00 AM						152600		
H-1803N-PLF	7/6/2026 9:43:25 AM	11.7	74.2	0.0	14.1			0.2	0.0
H-1803N-PLF	7/13/2026 9:30:31 AM	1.6	80.0	0.0	18.4			0.0	0.0
H-1803N-PLF	7/13/2026 9:40:00 AM					1370			
H-1803N-PLF	7/20/2026 9:30:00 AM					1500			
H-1803N-PLF	7/20/2026 9:31:03 AM	12.8	74.3	0.0	12.9			0.2	0.0
H-1803N-PLF	7/27/2026 9:23:26 AM	15.9	69.8	0.0	14.3			0.2	0.0
H-1804B	7/2/2026 1:22:54 PM	45.8	53.5	0.0	0.7			0.9	0.0
H-1804N	7/7/2026 9:04:56 AM	58.5	39.1	0.1	2.3			1.5	23.0
H-1804S	7/6/2026 12:30:07 PM	48.9	39.9	0.0	11.2			1.2	0.0
H-1805A	7/2/2026 11:02:16 AM	47.6	48.5	0.0	3.9			1.0	0.0
H-1805A	7/21/2026 10:19:00 AM	45.2	43.1	0.0	11.7			1.0	0.0
H-1805B	7/6/2026 12:07:13 PM	39.3	38.4	0.0	22.3			1.0	0.0
H-1805S	7/6/2026 12:19:58 PM	52.2	43.1	0.0	4.7			1.2	0.0
H-1805S	7/6/2026 12:20:18 PM	51.4	43.2	0.0	5.4			1.2	0.0
H-1806A	7/2/2026 11:16:43 AM	56.5	42.2	0.0	1.3			1.3	0.0
H-1806B	7/6/2026 10:48:27 AM	29.7	40.7	0.2	29.4			0.7	147.0
H-1806N	7/7/2026 9:27:30 AM	43.4	52.8	0.0	3.8			0.8	0.0
H-1806S	7/6/2026 10:19:10 AM	35.5	64.5	0.0	0.0			0.6	0.0
H-1807A	7/6/2026 9:20:28 AM	55.6	43.5	0.0	0.9			1.3	0.0
H-1807N	7/7/2026 9:46:22 AM	8.8	15.2	7.4	68.6			0.6	9.3

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
H-1807N	7/7/2026 9:47:04 AM	8.9	15.2	7.4	68.5			0.6	9.3
H-1807S	7/6/2026 9:39:03 AM	43.2	38.2	0.0	18.6			1.1	0.0
H-1952S	7/6/2026 12:43:31 PM	49.8	49.3	0.4	0.5			1.0	1.3
H-1952S	7/29/2026 10:11:32 AM	53.5	46.5	0.0	0.0			1.2	0.0
H-1955C	7/2/2026 10:55:18 AM	33.2	28.6	5.1	33.1			1.2	6.5
H-1955C	7/2/2026 10:57:58 AM	26.3	22.2	8.4	43.1			1.2	5.1
H-1955C	7/21/2026 10:12:36 AM	34.1	32.3	1.1	32.5			1.1	29.5
H-1955N	7/7/2026 9:08:05 AM	49.6	41.7	0.5	8.2			1.2	16.4
H-1956B	7/2/2026 11:38:20 AM	34.4	59.4	0.0	6.2			0.6	0.0
H-1956N	7/7/2026 9:20:39 AM	48.9	47.3	0.0	3.8			1.0	0.0
H-1956S	7/6/2026 10:23:58 AM	55.2	44.8	0.0	0.0			1.2	0.0
H-1956S	7/6/2026 10:24:22 AM	55.1	44.9	0.0	0.0			1.2	0.0
H-1956S	7/23/2026 1:24:17 PM	52.1	45.1	0.0	2.8			1.2	0.0
H-1957B	7/2/2026 11:32:45 AM	49.7	39.7	0.0	10.6			1.3	0.0
H-1957N	7/7/2026 9:33:09 AM	48.2	45.1	0.0	6.7			1.1	0.0
H-1957S	7/6/2026 10:57:07 AM	35.5	55.7	0.0	8.8			0.6	0.0
H-1958C	7/6/2026 9:18:24 AM	34.0	33.5	0.0	32.5			1.0	0.0
H-1958N	7/7/2026 9:38:14 AM	23.9	29.7	0.2	46.2			0.8	231.0
H-1958S	7/6/2026 9:35:13 AM	16.8	14.7	11.0	57.5			1.1	5.2
H-1958S	7/6/2026 9:35:55 AM	17.8	15.8	10.5	55.9			1.1	5.3
H-1962N	7/1/2026 9:18:59 AM	0.1	4.3	20.2	75.4			0.0	3.7
H-1962N	7/16/2026 10:40:44 AM	0.5	8.1	19.3	72.1			0.1	3.7
H-1963N	7/1/2026 9:02:32 AM	22.4	60.8	0.5	16.3			0.4	32.6
H-1963N	7/16/2026 10:24:18 AM	20.3	57.5	0.6	21.6			0.4	36.0
H-1966N	7/1/2026 9:42:22 AM	36.6	45.8	0.0	17.6			0.8	0.0
H-1966N	7/16/2026 10:50:23 AM	37.4	40.8	0.0	21.8			0.9	0.0
H-1967E	7/7/2026 11:48:29 AM	43.2	31.1	3.5	22.2			1.4	6.3

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
H-1967W	7/3/2026 9:51:34 AM	57.1	41.4	0.0	1.5			1.4	0.0
H-2050E	7/8/2026 11:01:21 AM	53.4	45.8	0.0	0.8			1.2	0.0
H-2050W	7/8/2026 10:04:46 AM	30.0	32.0	0.0	38.0			0.9	0.0
H-2051W	7/3/2026 9:48:44 AM	57.4	41.2	0.0	1.4			1.4	0.0
H-2053E	7/9/2026 1:01:15 PM	34.0	32.4	0.0	33.6			1.0	0.0
H-2053W	7/3/2026 10:13:44 AM	57.4	41.4	0.0	1.2			1.4	0.0
H-2055E	7/1/2026 9:16:30 AM	21.0	30.5	0.0	48.5			0.7	0.0
H-2055E	7/31/2026 8:41:21 AM	9.4	17.7	4.0	68.9			0.5	17.2
H-2056B	7/7/2026 12:20:01 PM	20.5	26.0	0.0	53.5			0.8	0.0
H-2056W	7/3/2026 9:46:01 AM	56.1	39.1	0.0	4.8			1.4	0.0
H-2057E	7/7/2026 11:56:18 AM	55.2	40.0	0.5	4.3			1.4	8.6
H-2057W	7/3/2026 10:10:18 AM	55.1	38.7	0.0	6.2			1.4	0.0
H-2058E	7/7/2026 12:10:53 PM	48.2	38.1	0.0	13.7			1.3	0.0
H-2058W	7/3/2026 9:43:34 AM	43.6	36.3	0.0	20.1			1.2	0.0
H-2059E	7/9/2026 9:21:16 AM	53.4	43.0	0.0	3.6			1.2	0.0
H-2059W	7/3/2026 10:28:35 AM	44.0	41.8	0.0	14.2			1.1	0.0
H-2161E	7/9/2026 9:25:57 AM	48.2	42.4	0.0	9.4			1.1	0.0
H-2161W	7/3/2026 10:31:00 AM	39.0	35.1	0.0	25.9			1.1	0.0
H-2163C	7/1/2026 3:20:52 PM	35.1	42.1	0.0	22.8			0.8	0.0
H-2163C	7/16/2026 2:04:14 PM	34.3	41.0	0.1	24.6			0.8	246.0
H-2163W	7/3/2026 8:33:34 AM	35.6	60.3	0.0	4.1			0.6	0.0
H-2164E	7/1/2026 9:35:21 AM	31.6	36.5	0.0	31.9			0.9	0.0
H-2164E	7/31/2026 12:51:18 PM	21.6	30.2	0.3	47.9			0.7	159.7
H-2165E	7/9/2026 1:29:58 PM	48.3	45.8	0.0	5.9			1.1	0.0
H-2165W	7/3/2026 8:04:21 AM	19.3	77.9	0.0	2.8			0.2	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
H-2165W	7/3/2026 8:04:45 AM	19.3	78.4	0.0	2.3			0.2	0.0
H-2165W	7/8/2026 7:15:00 AM					670			
H-2165W	7/8/2026 7:15:00 AM						53000		
H-2165W	7/20/2026 10:29:00 AM	12.5	71.1	0.2	16.2			0.2	81.0
H-2165W	7/20/2026 10:31:25 AM	10.5	85.3	0.0	4.2			0.1	0.0
H-2166E	7/6/2026 9:13:00 AM	55.9	43.9	0.0	0.2			1.3	0.0
H-2168C	7/7/2026 12:56:37 PM	52.7	38.0	0.9	8.4			1.4	9.3
H-2168E	7/6/2026 11:08:12 AM	42.7	54.5	0.0	2.8			0.8	0.0
H-2169C	7/6/2026 12:03:22 PM	49.7	38.9	0.0	11.4			1.3	0.0
H-2169E	7/6/2026 11:05:54 AM	46.9	44.9	0.0	8.2			1.0	0.0
H-2170N	7/8/2026 12:44:54 PM	31.1	34.7	0.0	34.2			0.9	0.0
H-2170S	7/6/2026 9:39:55 AM	40.9	35.1	0.1	23.9			1.2	239.0
H-2171A	7/22/2026 10:35:38 AM	0.3	1.5	21.4	76.8			0.2	3.6
H-2171A	7/22/2026 10:37:21 AM	0.5	1.5	21.3	76.7			0.3	3.6
H-2171A	7/30/2026 10:41:52 AM	9.1	12.3	15.2	63.4			0.7	4.2
H-2171B	7/9/2026 11:42:06 AM	36.0	32.9	0.0	31.1			1.1	0.0
H-2171N	7/9/2026 11:10:50 AM	25.5	27.5	0.7	46.3			0.9	66.1
H-2171S	7/8/2026 12:41:11 PM	36.8	39.1	0.0	24.1			0.9	0.0
H-2272W	7/3/2026 8:41:27 AM	26.8	43.5	0.0	29.7			0.6	0.0
H-2272W	7/28/2026 10:14:33 AM	31.0	41.0	0.0	28.0			0.8	0.0
H-2273W	7/3/2026 8:59:47 AM	20.9	53.8	0.0	25.3			0.4	0.0
H-2273W	7/8/2026 7:30:00 AM					48			
H-2273W	7/8/2026 7:30:00 AM						5400		
H-2273W	7/28/2026 9:48:03 AM	0.8	8.3	19.6	71.3			0.1	3.6
H-2274B	7/6/2026 10:30:01 AM	51.7	44.5	0.0	3.8			1.2	0.0
H-2274B	7/16/2026 3:08:24 PM	50.7	45.6	0.0	3.7			1.1	0.0
H-2274W	7/3/2026 9:05:07 AM	22.7	46.2	0.0	31.1			0.5	0.0
H-2274W	7/28/2026 1:09:51 PM	17.7	30.8	1.7	49.8			0.6	29.3
H-2275E	7/6/2026 12:38:37 PM	30.0	33.0	0.0	37.0			0.9	0.0
H-2275W	7/3/2026 8:48:18 AM	7.2	23.5	1.3	68.0			0.3	52.3
H-2275W	7/3/2026 8:48:42 AM	6.6	23.4	1.3	68.7			0.3	52.8
H-2275W	7/20/2026 1:35:47 PM	10.1	26.1	0.6	63.2			0.4	105.3
H-2276A	7/7/2026 12:12:40 PM	29.2	31.8	0.8	38.2			0.9	47.8

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
H-2276A	7/19/2026 1:13:15 PM	43.1	34.4	0.4	22.1			1.3	55.2
H-2276B	7/6/2026 10:36:34 AM	54.0	41.6	0.0	4.4			1.3	0.0
H-2276B	7/16/2026 3:13:23 PM	52.7	43.2	0.0	4.1			1.2	0.0
H-2276E	7/6/2026 12:16:34 PM	31.2	30.8	0.2	37.8			1.0	189.0
H-2276W	7/3/2026 9:13:09 AM	23.9	53.1	0.0	23.0			0.5	0.0
H-2276W	7/20/2026 10:15:45 AM	20.9	52.9	0.0	26.2			0.4	0.0
H-2277A	7/7/2026 9:06:50 AM	33.1	38.3	4.1	24.5			0.9	6.0
H-2277A	7/16/2026 2:02:32 PM	39.6	43.2	0.8	16.4			0.9	20.5
H-2277B	7/2/2026 1:33:25 PM	49.1	40.0	0.0	10.9			1.2	0.0
H-2277B	7/7/2026 12:32:31 PM	50.1	42.8	0.0	7.1			1.2	0.0
H-2277B	7/22/2026 9:37:54 AM	37.5	35.7	0.0	26.8			1.1	0.0
H-23 (EXP-23	7/9/2026 11:33:58 AM	58.2	28.4	0.8	12.6			2.0	15.8
H-2301E	7/9/2026 9:01:57 AM	39.8	40.0	0.0	20.2			1.0	0.0
H-2301W	7/8/2026 12:56:38 PM	51.9	41.7	1.2	5.2			1.2	4.3
H-2302C	7/7/2026 12:51:29 PM	54.0	40.0	0.0	6.0			1.4	0.0
H-2302E	7/8/2026 10:48:12 AM	56.6	43.3	0.1	0.0			1.3	0.0
H-2303E	7/8/2026 10:51:22 AM	56.8	42.9	0.1	0.2			1.3	2.0
H-2303N	7/7/2026 12:58:06 PM	34.6	32.0	0.0	33.4			1.1	0.0
H-2303S	7/8/2026 12:50:38 PM	54.4	44.6	0.0	1.0			1.2	0.0
H-2304E	7/8/2026 10:53:56 AM	54.8	43.3	0.0	1.9			1.3	0.0
H-2304S	7/8/2026 12:46:00 PM	44.2	41.6	0.0	14.2			1.1	0.0
H-2305N	7/7/2026 12:55:53 PM	33.0	32.3	0.0	34.7			1.0	0.0
H-2305S	7/8/2026 12:38:28 PM	47.7	42.6	0.0	9.7			1.1	0.0
H-2306N	7/8/2026 11:12:08 AM	40.8	38.5	0.0	20.7			1.1	0.0
H-2307S	7/7/2026 12:42:18 PM	54.3	40.5	0.0	5.2			1.3	0.0
H-2308S	7/7/2026 12:44:18 PM	52.8	41.4	0.0	5.8			1.3	0.0
H-2309N	7/8/2026 10:26:32 AM	41.1	37.9	0.0	21.0			1.1	0.0
H-2309S	7/8/2026 11:46:56 AM	52.9	45.5	0.0	1.6			1.2	0.0
H-2310N	7/7/2026 12:23:23 PM	56.2	39.8	0.0	4.0			1.4	0.0
H-2310S	7/8/2026 11:04:10 AM	36.4	39.9	0.2	23.5			0.9	117.5
H-2401S	7/7/2026 1:38:50 PM	55.6	40.6	0.0	3.8			1.4	0.0
H-2402N	7/8/2026 10:18:31 AM	44.7	40.1	0.0	15.2			1.1	0.0
H-2402S	7/7/2026 1:13:43 PM	53.3	41.6	0.0	5.1			1.3	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
H-2403N	7/8/2026 10:13:18 AM	33.2	35.3	2.0	29.5			0.9	14.8
H-2403N	7/8/2026 10:14:45 AM	36.0	36.5	1.7	25.8			1.0	15.2
H-2403S	7/7/2026 1:10:49 PM	46.2	37.8	0.3	15.7			1.2	52.3
H-2404N	7/8/2026 10:09:46 AM	50.6	41.6	0.0	7.8			1.2	0.0
H-2404S	7/7/2026 12:33:55 PM	56.1	41.6	0.0	2.3			1.3	0.0
H-2405N	7/8/2026 10:41:41 AM	20.1	32.9	0.1	46.9			0.6	469.0
H-29	7/8/2026 12:28:55 PM	32.1	44.5	1.0	22.4			0.7	22.4
H-29	7/8/2026 12:33:29 PM	31.5	43.1	1.1	24.3			0.7	22.1
H-72	7/8/2026 3:24:26 PM	36.7	63.3	0.0	0.0			0.6	0.0
H-74	7/8/2026 3:40:26 PM	50.6	42.9	0.0	6.5			1.2	0.0
H-74	7/20/2026 9:52:25 AM	41.2	37.0	3.2	18.6			1.1	5.8
H-75	7/6/2026 10:04:51 AM	37.4	34.6	0.1	27.9			1.1	279.0
H-79	7/6/2026 9:42:54 AM	43.0	56.9	0.0	0.1			0.8	0.0
P-02R	7/8/2026 8:43:54 AM	26.8	32.1	0.0	41.1			0.8	0.0
P-03R	7/8/2026 8:58:45 AM	39.6	34.5	0.0	25.9			1.1	0.0
P-04	7/8/2026 9:07:17 AM	32.7	35.0	0.0	32.3			0.9	0.0
P-05	7/8/2026 9:20:57 AM	32.2	35.3	0.0	32.6			0.9	0.0
P-05	7/8/2026 9:37:13 AM	33.1	34.5	0.0	32.4			1.0	0.0
P-05	7/8/2026 9:39:03 AM	32.7	34.9	0.0	32.4			0.9	0.0
P-05	7/8/2026 1:30:17 PM	38.2	35.8	0.0	25.9			1.1	0.0
P-06R	7/8/2026 9:28:01 AM	42.2	36.6	0.0	21.2			1.2	0.0
P-06R	7/8/2026 9:30:23 AM	41.7	36.7	0.0	21.6			1.1	0.0
P-06R	7/8/2026 9:40:41 AM	32.2	35.1	0.0	32.6			0.9	0.0
P-07R	7/8/2026 10:22:36 AM	32.5	30.8	0.0	36.7			1.1	0.0
P-08R	7/8/2026 8:36:31 AM	52.1	37.3	0.0	10.6			1.4	0.0
P-09	7/1/2026 1:36:56 PM	47.9	35.9	0.0	16.2			1.3	0.0
P-10	7/1/2026 1:47:13 PM	43.1	34.7	0.0	22.2			1.2	0.0
P-11	7/1/2026 1:54:31 PM	48.7	35.9	0.0	15.4			1.4	0.0
P-12	7/8/2026 10:01:31 AM	57.8	40.4	0.0	1.8			1.4	0.0
P-12	7/8/2026 10:03:58 AM	56.6	40.7	0.0	2.7			1.4	0.0
P-13	7/8/2026 9:53:30 AM	45.5	37.5	0.0	17.0			1.2	0.0
P-13	7/8/2026 9:55:58 AM	45.6	37.1	0.0	17.3			1.2	0.0
P-13	7/8/2026 10:07:11 AM	55.7	41.0	0.0	3.3			1.4	0.0
P-14	7/1/2026 2:03:05 PM	24.7	27.6	0.3	47.4			0.9	158.0
P-15R	7/1/2026 2:10:19 PM	46.3	33.8	0.0	19.9			1.4	0.0
P-16	7/20/2026 12:54:22 PM	54.7	34.6	0.0	10.7			1.6	0.0
P-17	7/6/2026 2:12:14 PM	36.4	31.7	0.0	31.9			1.1	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
P-18RD	7/6/2026 1:50:44 PM	52.0	36.2	0.0	11.8			1.4	0.0
P-18RD	7/6/2026 1:52:07 PM	51.3	35.3	0.0	13.4			1.5	0.0
P-18RD	7/6/2026 1:53:33 PM	51.4	36.1	0.0	12.5			1.4	0.0
P-18RS	7/6/2026 1:58:17 PM	39.5	33.5	0.0	27.0			1.2	0.0
P-19	7/6/2026 1:41:07 PM	34.1	28.7	0.0	37.2			1.2	0.0
P-20R	7/2/2026 2:11:06 PM	48.3	32.8	0.1	18.8			1.5	188.0
P-21	7/2/2026 2:05:54 PM	32.1	32.3	0.2	35.4			1.0	177.0
P-21RD	7/2/2026 1:36:40 PM	41.4	34.9	0.0	23.7			1.2	0.0
P-21RS	7/2/2026 1:31:20 PM	45.3	36.7	0.0	18.0			1.2	0.0
P-22RD	7/20/2026 12:48:40 PM	54.1	40.7	0.0	5.2			1.3	0.0
P-22RS	7/20/2026 12:45:58 PM	34.2	31.2	0.0	34.6			1.1	0.0
P-23	7/2/2026 1:50:54 PM	2.9	21.5	0.7	74.9			0.1	107.0
P-24	7/2/2026 1:18:32 PM	19.5	27.7	0.0	52.8			0.7	0.0
P-26	7/20/2026 1:03:55 PM	45.8	34.2	0.0	20.0			1.3	0.0
P-27	7/20/2026 1:12:57 PM	6.8	17.3	0.6	75.3			0.4	125.5
P-28	7/20/2026 1:18:33 PM	37.1	31.4	0.1	31.4			1.2	314.0
P-29R	7/20/2026 1:23:40 PM	27.9	27.1	0.2	44.8			1.0	224.0
P-30R	7/20/2026 1:31:27 PM	24.6	26.4	0.0	49.0			0.9	0.0
P-32R1	7/27/2026 1:09:08 PM	25.9	28.5	0.5	45.1			0.9	90.2
P-32R2	7/27/2026 1:00:31 PM	29.4	29.2	0.0	41.4			1.0	0.0
P-33	7/27/2026 12:53:39 PM	36.1	33.1	1.1	29.7			1.1	27.0
P-36	7/9/2026 1:53:10 PM	22.6	28.6	0.0	48.8			0.8	0.0
P-37	7/9/2026 2:10:42 PM	10.1	22.6	0.0	67.3			0.4	0.0
P-38RD	7/15/2026 1:34:09 PM	45.2	34.8	0.0	20.0			1.3	0.0
P-38RS	7/15/2026 1:37:49 PM	35.0	32.1	0.0	32.9			1.1	0.0
P-39	7/15/2026 1:47:47 PM	54.0	40.4	0.0	5.6			1.3	0.0
P-41	7/17/2026 1:27:10 PM	23.5	23.0	4.7	48.8			1.0	10.4
P-42R	7/17/2026 1:34:26 PM	54.5	38.0	0.0	7.5			1.4	0.0
P-42R	7/17/2026 1:35:31 PM	53.7	38.9	0.0	7.4			1.4	0.0
P-43	7/27/2026 2:02:31 PM	23.1	25.9	0.4	50.6			0.9	126.5
P-44RD	7/27/2026 1:55:00 PM	51.0	34.0	0.0	15.0			1.5	0.0
P-44RS	7/27/2026 1:51:21 PM	21.5	25.0	0.0	53.5			0.9	0.0
P-45RD	7/20/2026 1:08:46 PM	45.3	36.1	0.0	18.6			1.3	0.0
P-45RD	7/30/2026 8:33:40 AM	44.6	34.7	0.0	20.7			1.3	0.0
P-45RS	7/31/2026 8:40:03 AM	2.6	28.2	0.0	69.2			0.1	0.0
P-46RD	7/20/2026 12:58:59 PM	52.9	35.6	0.0	11.5			1.5	0.0
P-46RS	7/20/2026 1:02:00 PM	19.4	27.5	0.0	53.1			0.7	0.0
P-46RS	7/20/2026 1:11:30 PM	2.7	20.1	0.0	77.2			0.1	0.0
P-46RS	7/28/2026 12:43:27 PM	2.2	18.6	0.0	79.2			0.1	0.0
P-46RS	7/30/2026 9:02:21 AM	3.1	19.6	0.0	77.3			0.2	0.0
P-47	7/20/2026 12:34:13 PM	9.5	24.5	0.0	66.0			0.4	0.0
P-47	7/27/2026 9:24:31 AM	4.2	18.4	1.6	75.8			0.2	47.4
P-48	7/17/2026 2:01:45 PM	19.5	24.1	0.1	56.3			0.8	563.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
P-49RD	7/13/2026 12:32:12 PM	52.1	36.9	0.1	10.9			1.4	109.0
P-49RS	7/13/2026 12:27:08 PM	37.0	32.7	0.1	30.2			1.1	302.0
P-52	7/13/2026 1:42:13 PM	31.0	32.1	0.0	36.9			1.0	0.0
P-53	7/13/2026 1:00:47 PM	21.7	26.3	0.0	52.0			0.8	0.0
P-54	7/13/2026 1:15:17 PM	28.1	29.1	0.0	42.8			1.0	0.0
P-55	7/13/2026 1:21:13 PM	31.6	30.6	0.0	37.8			1.0	0.0
P-56	7/13/2026 1:34:27 PM	17.4	25.8	0.1	56.7			0.7	567.0
P-57	7/13/2026 1:27:44 PM	26.2	24.6	2.5	46.7			1.1	18.7
P-60R	7/13/2026 2:12:36 PM	55.0	36.4	0.0	8.6			1.5	0.0
P-61	7/27/2026 1:30:00 PM	43.4	32.8	0.0	23.8			1.3	0.0
P-65	7/16/2026 9:36:59 AM	30.0	32.1	0.0	37.9			0.9	0.0
P-71	7/17/2026 1:54:06 PM	43.5	34.1	0.0	22.4			1.3	0.0
P-75	7/13/2026 2:03:27 PM	53.2	36.1	0.0	10.7			1.5	0.0
P-76	7/20/2026 2:18:46 PM	21.1	27.4	0.5	51.0			0.8	102.0
P-79	7/9/2026 1:00:36 PM	21.6	27.5	0.2	50.7			0.8	253.5
SC-2000E	7/1/2026 7:59:51 AM	33.3	36.5	0.0	30.2			0.9	0.0
SC-2501E	7/6/2026 9:35:00 AM					1350			
SC-2501E	7/6/2026 9:35:00 AM						152400		
SC-2501E	7/6/2026 9:38:29 AM	9.2	74.5	0.0	16.3			0.1	0.0
SC-2501E	7/13/2026 9:26:02 AM	2.3	71.0	1.1	25.6			0.0	23.3
SC-2501E	7/13/2026 9:35:00 AM					1330			
SC-2501E	7/20/2026 9:21:46 AM	13.7	65.9	1.5	18.9			0.2	12.6
SC-2501E	7/20/2026 9:25:00 AM					1270			
SC-2501E	7/27/2026 9:15:01 AM	16.2	69.6	0.8	13.4			0.2	16.8
SC-2501W	7/6/2026 10:10:15 AM	20.3	66.3	1.6	11.8			0.3	7.4
SC-2501W	7/6/2026 10:20:00 AM					816			
SC-2501W	7/6/2026 10:20:00 AM						154500		
SC-2501W	7/13/2026 9:39:51 AM	2.8	64.6	1.8	30.8			0.0	17.1
SC-2501W	7/13/2026 9:40:22 AM	2.3	51.3	1.9	44.5			0.0	23.4
SW-10	7/31/2026 7:58:44 AM	21.4	30.7	2.2	45.7			0.7	20.8
SW-115	7/7/2026 11:50:26 AM	47.1	37.6	0.0	15.3			1.3	0.0
SW-1445	7/9/2026 11:49:56 AM	46.4	30.8	0.0	22.8			1.5	0.0
SW-1455	7/9/2026 11:39:16 AM	63.3	36.7	0.0	0.0			1.7	0.0
SW-154	7/13/2026 8:17:41 AM	7.0	10.3	13.9	68.8			0.7	4.9
SW-154	7/22/2026 10:03:39 AM	5.3	11.4	14.7	68.6			0.5	4.7
SW-17-135	7/9/2026 11:44:32 AM	53.2	33.5	0.0	13.3			1.6	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
SW-187	7/14/2026 1:15:47 PM	18.5	37.2	6.0	38.3			0.5	6.4
SW-187	7/20/2026 10:40:27 AM	13.7	26.7	7.5	52.1			0.5	6.9
SW-20	7/8/2026 10:16:30 AM	0.1	4.4	15.5	80.0			0.0	5.2
SW-2501D	7/30/2026 9:36:03 AM	2.9	10.0	17.2	69.9			0.3	4.1
SW-2501M	7/30/2026 9:30:41 AM	10.4	12.5	12.2	64.9			0.8	5.3
SW-2501MD	7/30/2026 9:33:08 AM	0.0	0.6	19.5	79.9			0.0	4.1
SW-2501S	7/30/2026 9:39:47 AM	1.0	3.4	13.4	82.2			0.3	6.1
SW-2501S	7/30/2026 9:55:04 AM	4.0	14.9	11.3	69.8			0.3	6.2
SW-2502D	7/30/2026 10:03:33 AM	7.5	81.1	0.4	11.0			0.1	27.5
SW-2502M	7/30/2026 9:59:45 AM	0.0	1.4	19.3	79.3			0.0	4.1
SW-2502S	7/30/2026 9:57:10 AM	5.6	14.5	2.3	77.6			0.4	33.7
SW-2503D	7/30/2026 10:09:23 AM	3.2	12.9	16.1	67.8			0.2	4.2
SW-2503M	7/30/2026 10:14:22 AM	0.0	0.8	19.4	79.8			0.0	4.1
SW-2503MD	7/30/2026 10:11:11 AM	6.5	24.1	8.6	60.8			0.3	7.1
SW-2503S	7/30/2026 10:17:02 AM	10.6	15.7	13.5	60.2			0.7	4.5
SW-2504D	7/30/2026 10:20:04 AM	0.1	1.7	19.1	79.1			0.1	4.1
SW-2504M	7/30/2026 10:21:58 AM	0.0	0.2	19.4	80.4			0.0	4.1
SW-2504MD	7/30/2026 10:26:42 AM	12.4	23.9	7.3	56.4			0.5	7.7
SW-2504S	7/30/2026 10:23:56 AM	12.7	16.5	10.0	60.8			0.8	6.1
SW-30	7/30/2026 9:50:01 AM	7.3	36.2	6.6	49.9			0.2	7.6
SW-32	7/30/2026 9:47:03 AM	18.0	60.0	4.3	17.7			0.3	4.1
SW-64	7/30/2026 9:51:59 AM	12.5	66.1	2.8	18.6			0.2	6.6
SW-65	7/7/2026 11:47:53 AM	46.1	37.0	0.2	16.7			1.2	83.5
SW-66	7/13/2026 8:15:49 AM	7.9	14.3	12.1	65.7			0.6	5.4
SW-66	7/22/2026 10:01:37 AM	8.4	14.2	11.1	66.3			0.6	6.0
SW-68	7/30/2026 9:44:08 AM	34.7	43.3	0.5	21.5			0.8	43.0
SW-70	7/14/2026 1:18:03 PM	14.5	66.8	0.0	18.7			0.2	0.0
SW-70	7/20/2026 10:44:08 AM	11.4	56.4	4.6	27.6			0.2	6.0
SW-71	7/2/2026 1:10:31 PM	11.8	17.3	7.5	63.4			0.7	8.5
SW-72	7/9/2026 1:49:05 PM	6.4	18.3	2.1	73.2			0.3	34.9
SW-80	7/22/2026 9:36:13 AM	26.1	29.2	1.3	43.4			0.9	33.4
SW-9	7/14/2026 1:53:02 PM	1.0	26.7	12.2	60.1			0.0	4.9
SW-9	7/20/2026 10:46:40 AM	0.6	16.7	15.4	67.3			0.0	4.4
TC-1961C	7/1/2026 10:14:09 AM	19.7	30.6	0.3	49.4			0.6	164.7
TC-1961E	7/6/2026 10:16:48 AM	51.0	43.0	0.0	6.0			1.2	0.0
TC-2174	7/6/2026 9:22:38 AM	6.4	73.8	0.0	19.8			0.1	0.0
TC-2174	7/6/2026 9:25:00 AM					1960			
TC-2174	7/6/2026 9:25:00 AM						152500		
TC-2174	7/13/2026 9:12:45 AM	1.6	83.0	0.0	15.4			0.0	0.0
TC-2174	7/13/2026 9:14:53 AM	1.9	76.7	0.0	21.4			0.0	0.0

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]
TC-2174	7/13/2026 9:25:00 AM					1940			
TC-2174	7/15/2026 2:14:30 PM	15.9	71.3	0.0	12.8			0.2	0.0
TC-2174	7/15/2026 2:22:26 PM	19.0	70.5	0.0	10.5			0.3	0.0
TC-2174	7/20/2026 9:09:11 AM	6.5	75.4	0.0	18.1			0.1	0.0
TC-2174	7/20/2026 9:15:00 AM					1620			
TC-2174	7/27/2026 9:01:39 AM	8.8	74.1	0.0	17.1			0.1	0.0
VL-02	7/30/2026 9:00:19 AM	53.1	32.2	1.8	12.9			1.6	7.2

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
A-01	7/6/2026 7:46:40 AM	84.9	84.9	-16.55	-16.41	0.0	0.0					28.76
A-02	7/6/2026 7:57:43 AM	96.3	96.3	-17.96	-18.01	0.0	0.0					28.77
A-03	7/6/2026 8:00:34 AM	83.9	84.0	-17.99	-17.99	0.0	0.0					28.74
A-04	7/6/2026 8:05:04 AM	96.2	95.5	-12.09	-12.19	0.0	0.0					28.74
A-05	7/6/2026 8:09:36 AM	87.6	87.7	-20.31	-20.26	0.0	0.0					28.73
B-01	7/6/2026 9:13:17 AM	88.3	88.7	-0.21	-0.19	0.0	0.0	-0.016	-0.020	-11.37		28.69
B-02R	7/6/2026 9:02:40 AM	82.5	82.5	-0.37	-0.39	1.9	1.9	0.342	0.343	-17.53		28.72
B-02R	7/6/2026 9:18:34 AM	92.2	92.4	-0.18	-0.17	0.0	0.0	-0.078	-0.074	-13.97		28.7
B-03R	7/6/2026 8:43:02 AM	82.7	82.7	-0.82	-0.79	2.6	2.6	0.686	0.673	-17.52		28.71
B-05	7/6/2026 9:09:04 AM	89.4	89.4	-0.45	-0.42	6.3	7.3	0.232	0.312	-16.87		28.71
B-06	7/28/2026 1:24:16 PM	89.3	88.8	-0.31	-0.41	1.1	1.6	0.279	0.664	-16.18	-15.91	28.66
B-07R	7/6/2026 8:24:41 AM	93.8	93.8	-0.51	-0.49	4.8	4.8	5.508	5.504	-14.85		28.72
B-08	7/22/2026 1:56:26 PM	96.6	96.9	-17.50	-17.32	0.4	0.4	0.016	0.013	-17.36	-16.86	28.7
B-08	7/22/2026 3:13:28 PM	97.1	97.7	-17.19	-0.74	0.4	0.3	0.014	0.007	-16.92	-16.99	28.67
B-08	7/22/2026 3:16:37 PM	98.2	97.5	-8.52	-0.05	0.6	0.2	0.039	0.005	-16.74	-16.58	28.67
B-08	7/22/2026 3:19:24 PM	97.9	98.0	-5.01	-5.03	0.2	0.2	0.010	0.009	-17.15	-16.68	28.67
B-08	7/28/2026 1:11:23 PM	94.1	95.0	-5.08	-14.11	0.4	0.4	0.048	0.034	-13.72	-14.55	28.67
B-09	7/6/2026 8:21:46 AM	93.4	93.4	-0.43	-0.38	0.0	0.0	0.375	0.359	-17.74		28.72
B-10	7/6/2026 8:16:35 AM	89.3	89.4	-0.37	-0.33	0.0	0.0	0.325	0.247	-18.05		28.72
B-11	7/22/2026 1:36:25 PM	102.2	102.2	-0.20	-0.19			0.000	0.000	-16.95	-16.92	28.78
B-12	7/6/2026 8:37:40 AM	93.8	93.6	-0.34	-0.29	4.9	4.9	2.445	2.497	-17.70		28.71
B-13	7/6/2026 8:28:38 AM	88.9	89.0	-0.48	-0.45	31.8	31.8	0.291	0.291	-17.78		28.72
B-14	7/22/2026 1:41:43 PM	108.5	109.2	-0.15	-0.15	1.4	1.4	0.201	0.206	-17.03	-17.42	28.78
C-03	7/30/2026 9:18:29 AM	91.4	91.6	-19.91	-19.58			20.174	19.792	0.33	0.26	28.72
C-07	7/30/2026 9:46:54 AM	98.7	98.7	-17.77	-17.45			18.172	17.806	0.31	0.34	28.71
C-08	7/15/2026 1:59:25 PM	119.8	120.3	-15.56	-15.53			15.462	15.464	-15.23	-15.12	28.66
C-08	7/16/2026 1:29:17 PM	120.4	120.5	-15.53	-15.71			16.060	16.269	-16.05	-16.30	28.58
C-10	7/7/2026 11:57:57 AM	118.6	119.1	-15.18	-15.11			15.296	15.144	0.08	0.10	28.81
C-11	7/9/2026 11:58:12 AM	107.2	107.8	-16.72	-16.74	0.0	0.0	-0.027	-0.032			28.56
C-12	7/31/2026 9:52:23 AM	102.7	103.0	-15.46	-15.42	1.2	1.6	0.010	0.016	-15.41	-15.39	28.71
C-15	7/29/2026 2:09:12 PM	103.6	101.7	27.70	14.03	2.5	2.6	0.013	0.015	-13.99	-14.04	28.63
C-15	7/29/2026 2:11:26 PM	101.9	101.9	15.18	15.20	4.7	3.1	0.047	0.021	-14.09	-14.01	28.63
C-15	7/29/2026 3:08:37 PM	99.9	99.7	14.52	-2.06	4.3	3.1	0.040	0.022	-14.02	-14.10	28.63
C-17B	7/22/2026 9:17:59 AM	110.4	110.5	-13.80	-14.00			14.075	14.141	-13.03	-13.03	28.73

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
C-17B	7/30/2026 10:53:56 AM	110.7	110.7	-13.19	-13.04			13.529	13.428	-13.76	-13.67	28.67
C-18	7/22/2026 9:31:11 AM	99.5	100.2	-13.62	-13.70			13.943	13.995	0.16	0.10	28.81
C-19	7/22/2026 9:28:11 AM	98.6	98.8	-11.45	-11.45			11.633	11.616	-11.35	-11.32	28.74
C-19	7/30/2026 10:37:45 AM	104.2	104.6	-14.37	-14.21			14.646	14.531	-14.24	-14.24	28.67
C-20	7/22/2026 9:25:28 AM	96.9	96.6	-9.81	-9.96			10.159	10.253	-10.01	-10.11	28.81
C-24	7/22/2026 9:23:30 AM	106.0	105.9	-1.83	-0.90			1.817	0.897	-1.69	-0.81	28.72
C-24	7/22/2026 9:25:48 AM	107.8	106.6	-1.32	-1.31			1.314	1.302	-1.20	-1.17	28.74
C-24	7/30/2026 10:47:49 AM	120.0	109.5	-0.14	-0.14			0.109	0.109	-13.97	-13.94	28.67
C-24	7/30/2026 10:48:42 AM	107.9	107.7	-0.15	-0.15			0.126	0.123	-14.05	-14.18	28.67
C-25	7/22/2026 9:07:22 AM	93.0	91.9	-15.10	-14.81			15.191	15.074	0.19	0.15	28.74
C-25	7/22/2026 9:07:58 AM	90.8	90.8	-14.81	-14.81			14.975	15.146	0.11	0.15	28.74
C-25	7/22/2026 9:12:41 AM	119.7	119.7	-14.47	-14.45			14.597	14.557	0.18	0.19	28.73
C-25	7/30/2026 10:57:08 AM	126.3	126.5	-13.81	-13.80			14.248	14.293	0.34	0.34	28.67
C-26	7/22/2026 9:06:07 AM	96.4	96.6	-14.83	-14.82			15.116	15.108	0.00	0.00	28.79
C-27	7/31/2026 8:10:51 AM	81.2	81.6	-16.71	-16.35	5.1	5.1	0.546	0.546	-16.59	-16.21	28.78
C-27	7/31/2026 8:11:55 AM	81.2	81.3	-16.33	-16.33	5.0	5.2	0.512	0.554	-16.17	-16.12	28.78
C-28	7/9/2026 11:53:17 AM	103.9	106.6	0.67	-4.94	0.0	0.0	-0.016	-0.050			28.56
C-28	7/9/2026 11:54:12 AM	106.7	106.7	-6.71	-6.70	0.0	0.0	-0.027	-0.028			28.56
C-29	7/7/2026 11:54:36 AM	110.0	110.0	-10.08	-8.05			10.125	8.152	-14.13	-14.98	28.8
C-30	7/15/2026 2:11:09 PM	130.1	130.0	-4.59	-4.28	6.1	6.0	0.244	0.235	-14.83	-14.67	28.62
CV-02	7/6/2026 9:42:55 AM	123.8	123.9	-0.71	-0.71	0.2	0.3	0.005	0.007	-17.36		28.68
CV-03	7/6/2026 9:37:03 AM	119.2	119.4	-8.49	-8.49	21.0	20.9	2.722	2.716	-15.58		28.69
CV-04	7/6/2026 9:33:10 AM	118.8	118.8	-2.70	-2.61	26.4	17.1	0.205	0.084			28.7
CV-05	7/9/2026 10:12:25 AM	108.1	108.2	-19.81	-19.87	2.0	1.3	0.088	0.039	-20.13	-20.16	28.66
CV-05	7/16/2026 1:41:39 PM	109.5	109.6	-16.12	-16.32	7.3	7.0	1.157	1.073	-17.31	-17.54	28.55
CV-06	7/7/2026 12:17:10 PM	98.6	99.0	-12.44	-13.45	7.5	7.6	0.349	0.362	-14.91	-14.81	28.81
CV-108-52	7/1/2026 8:25:00 AM											
CV-108-52	7/1/2026 8:25:00 AM											
CV-108-52	7/3/2026 7:30:23 AM	66.6	70.4	1.08	1.11			0.000	0.000	1.07	1.11	28.66

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-108-52	7/3/2026 7:30:59 AM	70.7	71.4	1.00	0.66			0.000	0.000	1.18	0.69	28.66
CV-108-52	7/7/2026 10:18:34 AM	101.8	102.1	-2.55	-2.55			0.081	0.054	-2.22	-2.15	28.63
CV-108-52	7/28/2026 1:43:12 PM	106.9	107.0	0.94	0.38			0.000	0.000	1.21	0.67	28.56
CV-108-52	7/28/2026 1:45:22 PM	107.2	107.2	1.39	1.51			0.022	0.009	1.73	1.77	28.56
CV-113	7/8/2026 1:51:43 PM	100.5	102.7	-2.65	-0.68	2.3	1.0	0.033	0.007	-7.97	-7.94	28.62
CV-113	7/9/2026 7:25:00 AM											
CV-113	7/9/2026 7:25:00 AM											
CV-113	7/24/2026 9:55:00 AM											
CV-113	7/24/2026 9:55:00 AM											
CV-113	7/29/2026 2:25:40 PM	99.2	99.2	-1.16	-1.15	1.2	1.5	0.009	0.014	-4.78	-4.75	28.45
CV-114	7/6/2026 9:16:05 AM	189.8	190.1	-4.30	-4.13			4.296	4.133	1.29	1.01	28.57
CV-114	7/6/2026 9:20:00 AM											
CV-114	7/6/2026 9:20:00 AM											
CV-114	7/9/2026 7:20:00 AM											
CV-114	7/9/2026 7:20:00 AM											
CV-114	7/13/2026 9:10:49 AM	191.1	191.1	-1.31	-1.17			1.301	1.129	0.33	0.34	28.61
CV-114	7/13/2026 9:20:00 AM											
CV-114	7/15/2026 2:14:50 PM	184.5	184.5	-0.25	-0.28			0.315	0.314	0.21	0.21	28.46
CV-114	7/20/2026 9:07:38 AM	190.4	190.8	-5.25	-5.28			5.607	5.633	-5.98	-5.94	28.6
CV-114	7/20/2026 9:10:00 AM											
CV-114	7/27/2026 8:59:32 AM	190.6	190.7	-5.45	-5.73			5.864	6.177	-5.61	-5.98	28.6
CV-1424	7/2/2026 11:04:56 AM	106.4	106.4	-3.85	-3.96	6.5	6.9	4.377	4.928	-16.24		28.5
CV-1424	7/21/2026 10:15:43 AM	106.1	106.1	-3.75	-3.63	24.7	24.0	3.858	3.642	-13.10	-13.71	28.61
CV-1532A	7/1/2026 8:30:00 AM											
CV-1532A	7/1/2026 8:30:00 AM											
CV-1532A	7/13/2026 9:37:04 AM	84.6	84.6	-6.19	-5.06			6.358	5.307	-6.31	-8.39	28.65
CV-1532A	7/13/2026 9:39:23 AM	84.5	84.5	-3.37	-3.37			3.342	3.342	-8.56	-8.53	28.66

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-1532A	7/28/2026 1:50:16 PM	102.5	102.3	-5.40	-6.08			5.571	6.150	-4.82	-6.77	28.56
CV-1534A-PL	7/13/2026 9:24:22 AM	128.9	128.3	-3.93	-3.93			3.298	3.298	0.33	0.33	28.65
CV-1534A-PL	7/28/2026 1:57:13 PM	132.5	133.0	-6.61	-7.11			4.800	7.354	0.33	0.34	28.56
CV-1535	7/3/2026 7:26:47 AM	109.7	110.3	-0.94	-0.83			0.976	0.857	-10.53	-11.21	28.62
CV-1535	7/13/2026 9:30:00 AM											
CV-1535	7/13/2026 9:30:00 AM											
CV-1535	7/20/2026 10:25:32 AM	122.3	122.5	-1.21	-1.23			1.058	1.138	-10.61	-11.21	28.66
CV-1601D	7/1/2026 3:18:41 PM	113.3	113.3	-0.80	-0.75	7.8	6.2	1.292	0.802	-8.81		28.48
CV-1601D	7/16/2026 2:02:26 PM	115.4	115.3	-0.77	-0.76	9.3	9.3	1.803	1.805	-15.59		28.41
CV-1601S	7/1/2026 3:14:58 PM	114.6	114.6	-0.53	-0.52	6.1	6.1	0.780	0.786	-9.21		28.48
CV-1601S	7/16/2026 2:00:37 PM	117.7	117.6	-1.01	-0.90	8.7	5.4	1.604	0.616	-14.55		28.54
CV-1604	7/1/2026 10:22:08 AM	123.0	123.0	-1.39	-1.30	1.5	1.6	0.048	0.052	-20.16		28.62
CV-1701D	7/6/2026 10:05:30 AM	112.2	114.1	-0.50	-0.24	0.4	0.5	0.051	0.055	-14.28	-14.98	28.62
CV-1701D	7/29/2026 10:38:22 AM											
CV-1701D	7/29/2026 10:47:20 AM	108.6	107.9	-2.19	-1.67	0.4	2.5	0.034	1.596	-17.01	-17.35	28.58
CV-1701D	7/29/2026 10:50:04 AM	110.2	110.3	-3.05	-3.06	0.4	0.3	0.037	0.025	-16.92	-16.92	28.57
CV-1701D	7/29/2026 1:45:00 PM											
CV-1701D	7/29/2026 2:13:12 PM	116.6	119.3	1.26	-2.12	0.3	0.7	0.028	0.143	-16.84	-16.54	28.55
CV-1701D	7/29/2026 2:14:44 PM	119.7	119.7	-2.46	-2.42	0.7	0.7	0.118	0.129	-16.49	-16.84	28.55
CV-1701S	7/6/2026 9:59:53 AM	143.7	143.4	-0.11	-0.12	6.2	1.1	0.249	0.008	-18.25	-18.11	28.61
CV-1701S	7/6/2026 10:00:19 AM	143.6	143.5	-0.12	-0.12	3.3	3.3	0.072	0.073	-17.97	-17.97	28.59
CV-1701S	7/29/2026 11:07:45 AM											
CV-1701S	7/29/2026 11:09:01 AM	145.3	132.6	-4.81	-1.55	3.9	1.2	0.103	0.010	-17.04	-16.75	28.57
CV-1701S	7/29/2026 11:10:07 AM	133.0	133.3	-1.53	-1.53	1.9	1.9	0.023	0.022	-16.86	-17.00	28.59
CV-1701S	7/29/2026 1:50:00 PM											
CV-1701S	7/29/2026 1:50:00 PM											
CV-1901	7/1/2026 10:06:33 AM	98.6	98.8	-3.25	-0.83	1.1	1.0	0.026	0.018	-10.98	-11.17	28.58
CV-1901	7/16/2026 10:59:07 AM	116.5	116.6	-8.63	-7.60	1.9	1.3	0.077	0.037	-9.42	-9.46	28.51
CV-1902A	7/1/2026 9:35:00 AM											
CV-1902A	7/1/2026 9:37:01 AM	172.3	159.9	-4.42	-4.46			4.403	4.424	-6.78	-7.07	28.57
CV-1902A	7/8/2026 8:45:00 AM											
CV-1902A	7/8/2026 8:45:00 AM											

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-1902A	7/8/2026 8:49:36 AM	175.0	174.8	-5.73	-5.39			6.083	5.905	-8.80	-8.63	28.64
CV-1902A	7/15/2026 8:30:00 AM											
CV-1902A	7/15/2026 8:30:50 AM	176.1	176.4	-5.05	-5.05			5.506	5.506	-9.02	-9.02	28.57
CV-1902A	7/22/2026 9:15:53 AM	177.9	178.7	-4.72	-4.72			5.098	5.116	-8.29	-8.29	28.67
CV-1902A	7/29/2026 8:19:09 AM	185.5	185.6	-2.33	-2.24			2.325	2.238	-9.26	-9.01	28.56
CV-1905	7/7/2026 2:26:39 PM	114.6	114.6	-4.15	-5.49	17.5	23.0	1.852	3.213	-12.28		28.44
CV-2001	7/2/2026 8:10:00 AM											
CV-2001	7/2/2026 8:10:00 AM											
CV-2001	7/3/2026 7:59:18 AM	80.2	81.3	-9.40	-9.06	17.6	17.2	0.385	0.365	-10.08	-10.08	28.67
CV-2001	7/3/2026 8:00:50 AM	81.3	81.6	-9.06	-9.06	17.5	17.5	0.381	0.379	-11.05	-11.39	28.66
CV-2001	7/20/2026 12:55:49 PM	116.5	116.5	-0.90	-0.82	8.8	8.0	0.100	0.083	-8.29	-8.13	28.66
CV-2002	7/1/2026 1:41:30 PM	183.3	183.2	-5.73	-5.19	44.0	42.1	5.957	5.433	-11.79	-10.21	28.63
CV-2002	7/1/2026 1:42:00 PM											
CV-2002	7/8/2026 7:50:00 AM											
CV-2002	7/8/2026 7:50:00 AM											
CV-2002	7/8/2026 10:23:36 AM	184.2	184.3	-4.83	-4.97	42.2	42.3	5.469	5.497	-10.91	-11.45	28.68
CV-2002	7/8/2026 10:35:00 AM											
CV-2002	7/8/2026 10:35:00 AM											
CV-2002	7/15/2026 9:58:01 AM	186.8	186.8	-4.56	-4.38	40.7	40.3	5.093	5.007	-8.28	-8.84	28.61
CV-2002	7/15/2026 10:00:00 AM											
CV-2002	7/20/2026 1:06:48 PM	186.8	186.8	-4.41	-3.96			4.379	3.952	-8.30	-7.72	28.66
CV-2002	7/22/2026 1:55:59 PM	186.5	186.5	-5.52	-5.56	42.4	42.1	5.560	5.469	-10.91	-10.99	28.64
CV-2002	7/22/2026 1:56:42 PM	186.6	186.6	-4.31	-4.28			4.251	4.202	-10.88	-10.89	28.65
CV-2002	7/29/2026 9:25:08 AM	186.7	186.9	-0.57	-0.61			0.529	0.630	-12.51	-12.93	28.6
CV-2003	7/3/2026 7:32:47 AM	91.8	96.7	1.46	1.50	0.6	0.4	0.034	0.019	1.86	1.62	28.66
CV-2003	7/3/2026 7:33:04 AM	95.8	99.6	1.39	1.39	1.0	1.0	0.113	0.113	1.65	1.65	28.66
CV-2003	7/7/2026 10:15:47 AM	103.2	113.8	-0.08	-0.07	2.9	2.9	0.860	0.888	-2.15	-2.24	28.64
CV-2003	7/28/2026 1:39:31 PM	106.6	107.1	0.03	0.00	0.5	0.4	0.031	0.014	0.47	2.02	28.56
CV-2003	7/28/2026 1:41:40 PM	105.9	106.0	0.00	0.01	0.2	0.2	0.006	0.005	0.61	0.72	28.56

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2006	7/1/2026 9:44:51 AM	188.0	188.0	-2.68	-2.56	18.0	17.6	0.472	0.453	-8.73	-8.70	28.57
CV-2006	7/1/2026 9:50:00 AM											
CV-2006	7/8/2026 8:55:00 AM											
CV-2006	7/8/2026 8:55:00 AM											
CV-2006	7/8/2026 8:55:07 AM	188.4	188.5	-4.57	-4.57	13.2	13.2	0.254	0.254	-12.00	-12.00	28.64
CV-2006	7/15/2026 8:37:09 AM	187.9	188.2	-6.23	-6.07	16.8	13.9	0.418	0.286	-10.17	-10.25	28.57
CV-2006	7/15/2026 8:40:00 AM											
CV-2006	7/22/2026 9:20:15 AM	188.1	188.4	-2.90	-2.91	10.4	10.9	0.158	0.172	-6.44	-6.44	28.67
CV-2006	7/29/2026 8:24:09 AM	187.5	187.6	-5.42	-5.64	13.5	17.6	0.270	0.456	-10.75	-11.16	28.55
CV-2007	7/6/2026 1:47:52 PM	130.2	130.4	-0.66	-0.66	5.5	4.9	0.084	0.068	-10.98	-11.11	28.55
CV-2007	7/23/2026 9:41:53 AM	158.0	156.5	-2.33	-1.05	5.8	2.8	0.099	0.022	-9.57	-10.48	28.51
CV-2007	7/23/2026 9:42:37 AM	156.2	156.1	-0.95	-0.94	2.0	2.8	0.012	0.023	-10.10	-10.31	28.53
CV-2007	7/27/2026 1:17:09 PM	144.1	144.8	-1.43	-1.38	7.5	7.8	0.161	0.173	-6.55	-6.19	28.53
CV-2008	7/6/2026 2:08:20 PM	109.7	108.3	-3.90	-1.36	0.3	0.2	0.024	0.014	-3.73	-3.99	28.55
CV-2008	7/23/2026 9:23:46 AM	113.5	113.7	-0.01	-0.01	0.2	0.2	0.008	0.011	-3.01	-3.03	28.54
CV-2009	7/7/2026 10:02:25 AM	133.9	137.2	1.77	-0.28	10.5	22.4	0.145	0.675	-2.81	-2.40	28.59
CV-2009	7/7/2026 10:03:44 AM	137.4	137.4	-0.46	-0.48	20.5	21.1	0.565	0.596	-2.20	-2.40	28.59
CV-2009A	7/14/2026 8:47:52 AM	157.1	157.1	-0.55	-0.53	19.2	18.5	2.503	2.329	-3.84	-3.67	28.57
CV-2009A	7/14/2026 8:48:35 AM	157.2	157.2	-0.48	-0.58	17.1	18.9	1.987	2.441	-3.00	-3.92	28.57
CV-2009A	7/14/2026 2:08:33 PM	155.5	155.6	-2.46	-2.35	14.9	13.8	1.524	1.298	-0.16	-0.17	28.5
CV-2009A	7/14/2026 2:10:00 PM											
CV-2009A	7/20/2026 2:40:00 PM											
CV-2009A	7/20/2026 2:41:25 PM	153.1	153.8	-0.93	-1.18	13.5	4.3	1.231	0.123	-3.07	-3.04	28.47
CV-2009A	7/20/2026 2:41:51 PM	153.9	153.8	-1.25	-1.26	4.4	5.3	0.129	0.189	-3.03	-3.03	28.49
CV-2009A	7/29/2026 10:20:52 AM	153.7	153.8	-2.20	-2.20	3.3	2.3	0.072	0.035	-3.82	-3.77	28.46
CV-2010	7/6/2026 9:15:47 AM	94.9	97.5	-11.04	-10.93	10.7	10.4	0.147	0.138	-11.00	-10.98	28.55
CV-2010A	7/6/2026 8:59:57 AM	136.4	90.9	-15.70	-15.56	28.1	29.7	2.316	2.379	-17.98	-18.02	28.54
CV-2010A	7/6/2026 9:01:10 AM	136.4	136.4	-15.60	-15.72	27.8	27.0	2.252	2.138	-17.87	-17.88	28.55
CV-2010A	7/6/2026 9:03:59 AM	136.3	136.2	-15.60	-15.60	27.6	27.3	2.228	2.179	-17.76	-17.81	28.55

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2011	7/6/2026 9:30:09 AM	128.8	128.8	-9.48	-9.48	23.8	21.6	0.767	0.633	-14.00	-14.15	28.55
CV-2011A	7/2/2026 11:29:15 AM	152.8	152.7	-4.64	-4.83	86.4	91.5	2.089	2.344	-12.37	-12.02	28.61
CV-2011A	7/9/2026 8:54:58 AM	153.1	153.7	-0.12	-2.04	59.4	69.9	0.977	1.362	-18.50	-18.05	28.53
CV-2011A	7/9/2026 8:55:33 AM	153.7	153.8	-2.27	-2.28	71.0	71.9	1.405	1.439	-17.85	-17.85	28.53
CV-2011A	7/9/2026 9:00:00 AM											
CV-2011A	7/9/2026 9:00:00 AM											
CV-2011A	7/16/2026 9:11:56 AM	153.3	153.4	-3.44	-3.45	58.4	66.0	0.954	1.218	-16.55	-17.89	28.49
CV-2011A	7/16/2026 9:15:00 AM											
CV-2011A	7/22/2026 2:38:29 PM	152.5	152.4	-4.34	-4.28	53.7	57.2	0.803	0.913	-12.81	-12.02	28.57
CV-2011A	7/30/2026 1:03:33 PM	152.4	152.4	-3.95	-3.94	72.8	72.1	1.479	1.450	-14.49	-14.48	28.57
CV-2012	7/8/2026 2:55:41 PM	138.9	138.3	-11.01	-7.94	11.3	0.0	0.182	-0.101	-15.56		28.49
CV-2012	7/8/2026 2:56:37 PM	137.7	137.8	-7.02	-7.02	0.0	0.0	-0.120	-0.115	-15.54		28.49
CV-2201-PLR	7/8/2026 11:29:35 AM	143.0	142.7	1.14	-2.45			0.000	2.394	-5.48	-5.09	28.67
CV-2201-PLR	7/8/2026 11:30:39 AM	142.5	142.4	-3.57	-3.57			3.537	3.537	-4.81	-4.81	28.67
CV-2201-PLR	7/29/2026 1:40:18 PM	146.6	146.5	-5.31	-4.75			5.481	4.802	-5.14	-4.44	28.45
CV-2201-PLR	7/29/2026 1:41:27 PM	145.8	146.0	-5.10	-5.40			5.142	5.418	-5.08	-5.45	28.45
CV-2204-PLR	7/6/2026 10:47:15 AM	190.6	190.4	-6.78	-6.70			7.229	6.884	1.01	1.01	28.54
CV-2204-PLR	7/6/2026 11:05:00 AM											
CV-2204-PLR	7/6/2026 11:05:00 AM											
CV-2204-PLR	7/13/2026 10:28:00 AM	191.2	191.2	-9.10	-9.10			9.678	9.678	0.34	0.34	28.6
CV-2204-PLR	7/13/2026 10:30:00 AM											
CV-2204-PLR	7/20/2026 10:02:50 AM	190.7	190.7	-8.42	-8.42			9.007	8.971	0.34	0.34	28.58
CV-2204-PLR	7/20/2026 10:15:00 AM											
CV-2204-PLR	7/27/2026 10:47:10 AM	190.9	190.9	-4.86	-6.87			4.749	7.438	0.63	0.63	28.58
CV-2205	7/6/2026 11:03:21 AM	144.6	144.9	-0.05	-0.04	13.2	6.8	0.047	0.012	-15.79	-15.69	28.51
CV-2205	7/6/2026 11:04:01 AM	144.9	144.7	-0.07	-0.07	10.0	7.3	0.027	0.014	-15.61	-15.59	28.51
CV-2207	7/2/2026 11:24:38 AM	121.0	121.4	-1.33	-1.26	0.0	3.5	-0.024	0.003	-14.14		28.5
CV-2208A	7/7/2026 9:14:02 AM	149.0	146.2	-3.94	-1.39	12.4	8.8	0.043	0.021	-5.38	-5.04	28.6
CV-2208A	7/7/2026 9:14:44 AM	146.6	146.6	-1.16	-1.14	5.9	7.7	0.009	0.016	-5.10	-5.07	28.61

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2208A	7/7/2026 2:37:56 PM	143.5	147.2	0.36	-2.60	9.3	2.5	0.024	0.002	-0.26	-0.23	28.57
CV-2208A	7/7/2026 2:38:55 PM	147.2	147.6	-2.96	-2.95	19.6	20.2	0.106	0.113	-4.69	-4.72	28.55
CV-2208A	7/7/2026 2:40:00 PM											
CV-2208A	7/7/2026 2:40:00 PM											
CV-2208A	7/16/2026 11:12:34 AM	150.1	150.2	-5.21	-5.18	29.1	27.5	0.236	0.212	-6.78	-6.78	28.49
CV-2208A	7/16/2026 11:15:00 AM											
CV-2208A	7/20/2026 1:44:53 PM	146.7	146.9	-4.60	-4.63	18.5	18.8	0.094	0.097	-5.35	-5.39	28.54
CV-2208A	7/20/2026 1:50:00 PM											
CV-2208A	7/27/2026 12:57:55 PM	143.4	143.3	-4.24	-4.24	7.1	19.2	0.014	0.101	-5.05	-5.05	28.58
CV-2301	7/6/2026 7:20:00 AM											
CV-2301	7/6/2026 7:20:00 AM											
CV-2301	7/8/2026 1:12:10 PM	174.0	186.5	1.72	-1.55			0.000	1.552	-8.31	-10.21	28.55
CV-2301	7/8/2026 1:12:44 PM	186.3	187.2	-1.76	-1.82			1.766	1.798	-11.54	-11.79	28.56
CV-2301	7/8/2026 1:15:00 PM											
CV-2301	7/8/2026 1:15:00 PM											
CV-2301	7/16/2026 10:42:12 AM	186.5	185.5	-3.52	-2.48			3.503	2.477	-10.95	-10.36	28.46
CV-2301	7/16/2026 10:43:49 AM	185.9	185.8	-1.86	-1.85			1.850	1.830	-9.85	-10.48	28.49
CV-2301	7/16/2026 10:45:00 AM											
CV-2301	7/22/2026 2:20:36 PM	187.1	188.1	-0.76	-3.36			0.754	3.355	-11.34	-10.18	28.57
CV-2301	7/22/2026 2:22:28 PM	187.6	188.1	-2.82	-2.75			2.785	2.744	-9.56	-11.54	28.55
CV-2301	7/22/2026 2:22:54 PM	188.1	188.4	-2.81	-2.81			2.841	2.841	-11.58	-11.58	28.57
CV-2301	7/30/2026 9:33:34 AM	185.1	178.4	-4.96	-1.27			5.305	1.268	-14.55	-14.40	28.57
CV-2301	7/30/2026 9:37:13 AM	179.9	179.6	-0.91	-0.89			0.909	0.893	-14.34	-14.34	28.57
CV-2302	7/6/2026 7:25:00 AM											
CV-2302	7/6/2026 7:25:00 AM											
CV-2302	7/6/2026 3:38:27 PM	114.6	114.9	-11.44	-11.40	0.0	0.0			-11.44		28.47
CV-2302	7/16/2026 2:45:08 PM	126.7	127.1	-12.38	-11.78			12.401	11.652	-11.07	-11.09	28.47
CV-2303	7/6/2026 7:25:00 AM											
CV-2303	7/6/2026 7:35:00 AM											
CV-2303	7/7/2026 9:55:00 AM											
CV-2303	7/7/2026 9:55:00 AM											
CV-2303	7/7/2026 10:01:32 AM	192.4	192.6	1.10	0.83			0.000	0.000	1.54	0.86	28.57
CV-2303	7/7/2026 10:02:07 AM	192.1	192.5	1.01	0.96			0.000	0.000	1.54	1.14	28.58

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2303	7/14/2026 9:45:01 AM	190.9	191.3	-1.40	-1.43			1.413	1.425	-2.08	-2.23	28.6
CV-2303	7/14/2026 9:55:00 AM											
CV-2303	7/21/2026 8:52:07 AM	187.9	188.2	-2.24	-2.63			2.215	2.620	-3.06	-3.45	28.62
CV-2303	7/28/2026 9:21:10 AM	191.2	191.2	-1.28	-1.42			1.240	1.382	-2.17	-2.21	28.49
CV-2304-PLR	7/2/2026 12:29:34 PM	169.3	169.2	-9.82	-10.07			0.000	0.000	-10.44	-10.56	28.59
CV-2304-PLR	7/7/2026 1:45:00 PM											
CV-2304-PLR	7/7/2026 1:45:00 PM											
CV-2304-PLR	7/7/2026 1:47:24 PM	172.1	172.2	-9.70	-9.69			9.858	9.769	-9.96	-9.83	28.55
CV-2304-PLR	7/14/2026 10:20:56 AM	175.7	175.8	-8.27	-8.42			8.857	9.007	-8.52	-8.76	28.62
CV-2304-PLR	7/14/2026 10:25:00 AM											
CV-2304-PLR	7/14/2026 1:03:47 PM	189.3	189.3	3.34	-6.99			0.000	7.037	-8.52	-8.53	28.59
CV-2304-PLR	7/21/2026 10:16:28 AM	176.7	176.9	-7.17	-7.48			7.752	8.023	-7.42	-7.75	28.67
CV-2304-PLR	7/28/2026 9:49:36 AM	176.0	175.8	-8.70	-8.11			9.304	8.689	-9.05	-8.46	28.52
CV-2305	7/2/2026 8:53:00 AM											
CV-2305	7/2/2026 8:57:50 AM	156.7	156.1	-12.13	-6.74			12.421	6.962	-14.48	-14.48	28.53
CV-2305	7/2/2026 8:59:04 AM	156.4	156.5	-6.54	-6.50			6.732	6.712	-14.48	-14.47	28.55
CV-2305	7/9/2026 9:46:08 AM	153.9	154.1	-2.00	-1.99			0.279	0.265	-15.16	-15.16	28.49
CV-2305	7/9/2026 9:50:00 AM											
CV-2305	7/9/2026 9:50:00 AM											
CV-2305	7/13/2026 8:40:00 AM											
CV-2305	7/13/2026 8:40:00 AM											
CV-2305	7/16/2026 9:44:14 AM	155.5	155.5	-2.03	-3.90			0.206	0.317	-13.83	-14.01	28.45
CV-2305	7/16/2026 9:44:37 AM	155.5	155.5	-4.32	-4.33			0.361	0.346	-14.19	-14.19	28.45
CV-2305	7/16/2026 9:50:00 AM											
CV-2305	7/30/2026 8:45:53 AM	155.8	155.8	-4.56	-4.57			0.068	0.027	-16.77	-16.95	28.5
CV-2306-PLR	7/6/2026 10:35:36 AM	168.7	170.5	0.70	-5.68			0.000	6.024	0.34	0.34	28.56
CV-2306-PLR	7/6/2026 10:36:14 AM	170.7	171.0	-5.77	-6.07			6.048	6.195	0.00	0.00	28.57
CV-2306-PLR	7/6/2026 10:50:00 AM											
CV-2306-PLR	7/6/2026 10:50:00 AM											
CV-2306-PLR	7/13/2026 10:20:00 AM											

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2306-PLR	7/13/2026 10:21:22 AM	180.5	169.3	-10.52	-6.09			11.057	6.589	0.34	0.34	28.6
CV-2306-PLR	7/13/2026 10:22:02 AM	169.7	169.8	-6.49	-6.39			6.984	6.833	0.34	0.34	28.6
CV-2306-PLR	7/20/2026 9:55:42 AM	148.4	149.9	-2.02	-1.98			1.836	1.345	0.34	0.34	28.6
CV-2306-PLR	7/20/2026 10:05:00 AM											
CV-2306-PLR	7/27/2026 10:38:00 AM	164.7	165.1	-1.34	-1.77			1.473	1.355	0.65	0.67	28.57
CV-2308-PLR	7/8/2026 11:34:43 AM	138.7	140.5	-9.43	-9.40			9.611	9.468	-10.72	-10.82	28.67
CV-2308-PLR	7/8/2026 11:36:02 AM	139.0	138.8	-9.43	-9.40			9.576	9.508	-10.75	-10.65	28.67
CV-2308-PLR	7/29/2026 1:44:36 PM	117.7	117.8	-8.10	-8.10			8.262	8.217	-8.14	-8.82	28.45
CV-2310-PLR	7/7/2026 9:40:00 AM											
CV-2310-PLR	7/7/2026 9:40:00 AM											
CV-2310-PLR	7/7/2026 9:50:54 AM	194.4	194.7	-5.79	-5.56			6.343	6.023	0.34	0.34	28.59
CV-2310-PLR	7/14/2026 9:32:34 AM	191.2	191.3	-8.07	-7.73			8.587	8.159	0.34	0.34	28.61
CV-2310-PLR	7/14/2026 9:35:00 AM											
CV-2310-PLR	7/21/2026 8:57:27 AM	193.7	193.7	-7.37	-7.41			7.646	7.719	0.34	0.34	28.64
CV-2310-PLR	7/28/2026 9:16:24 AM	192.6	193.1	-8.15	-8.76			8.693	9.333	0.31	0.29	28.49
CV-2311	7/7/2026 8:43:40 AM	168.9	167.4	-4.06	-4.07			4.053	4.055	-9.21	-9.43	28.56
CV-2311	7/7/2026 8:50:00 AM											
CV-2311	7/7/2026 8:50:00 AM											
CV-2311	7/13/2026 2:40:00 PM											
CV-2311	7/13/2026 2:45:21 PM	183.2	184.3	1.87	-0.37			0.000	0.398	-5.14	-4.72	28.56
CV-2311	7/13/2026 2:46:49 PM	192.3	192.4	-0.55	-0.52			0.552	0.549	-4.69	-4.63	28.54
CV-2311	7/20/2026 2:20:00 AM											
CV-2311	7/20/2026 2:18:54 PM	185.5	184.6	-2.62	-2.59			2.615	2.607	-7.35	-7.28	28.5
CV-2311	7/28/2026 8:05:28 AM	184.7	185.3	-5.05	-5.05			5.304	5.270	-10.76	-10.86	28.49
CV-2312-PLR	7/6/2026 7:45:00 AM											
CV-2312-PLR	7/6/2026 7:45:00 AM											
CV-2312-PLR	7/8/2026 1:40:00 PM											
CV-2312-PLR	7/8/2026 1:40:00 PM											
CV-2312-PLR	7/8/2026 1:43:27 PM	168.0	167.9	-4.67	-4.26	38.9	38.4	4.549	4.416	-0.33	-0.30	28.53

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2312-PLR	7/16/2026 10:16:27 AM	168.1	168.0	-3.17	-3.76	32.4	33.0	3.145	3.273	-8.88	-8.63	28.43
CV-2312-PLR	7/16/2026 10:20:00 AM											
CV-2312-PLR	7/17/2026 10:06:51 AM	111.0	111.8	-0.48	-0.48	13.2	13.3	0.470	0.476	-9.27	-9.41	28.58
CV-2312-PLR	7/21/2026 1:16:32 PM	167.4	167.9	-1.62	-0.30	21.3	9.8	1.344	0.283	-6.91	-6.23	28.55
CV-2312-PLR	7/22/2026 2:54:17 PM	167.2	167.4	-2.57	-2.51	30.1	30.9	2.703	2.841	-8.91	-8.97	28.52
CV-2312-PLR	7/29/2026 1:17:39 PM	167.5	167.6	-40.15	-38.84	97.8	98.0	33.370	33.370	-6.85	-6.74	28.46
CV-2314-PLR	7/6/2026 2:20:01 PM	180.6	182.4	-11.86	-5.61			12.287	5.975	-13.80	-13.77	28.51
CV-2314-PLR	7/6/2026 2:21:36 PM	182.5	182.6	-5.53	-5.56			5.944	5.887	-13.81	-13.89	28.52
CV-2314-PLR	7/6/2026 2:40:00 PM											
CV-2314-PLR	7/6/2026 2:40:00 PM											
CV-2314-PLR	7/13/2026 7:30:00 AM											
CV-2314-PLR	7/13/2026 7:30:00 AM											
CV-2314-PLR	7/15/2026 1:37:00 PM	186.1	185.1	0.88	-8.23			0.000	8.355	-11.37	-11.36	28.42
CV-2314-PLR	7/15/2026 1:37:27 PM	185.2	185.1	-7.75	-7.93			7.885	8.073	-11.13	-11.16	28.45
CV-2314-PLR	7/15/2026 1:45:00 PM											
CV-2315	7/6/2026 8:00:00 AM											
CV-2315	7/6/2026 8:00:00 AM											
CV-2315	7/6/2026 1:44:39 PM	174.5	175.0	-5.90	-5.94			6.086	6.259	-7.20	-7.41	28.5
CV-2315	7/6/2026 2:05:00 PM											
CV-2315	7/6/2026 2:05:00 PM											
CV-2315	7/13/2026 1:19:42 PM	186.1	186.0	-3.81	-3.87			3.868	3.921	-4.84	-4.90	28.54
CV-2315	7/13/2026 1:30:00 PM											
CV-2315	7/20/2026 10:06:54 AM	185.4	185.6	-4.86	-4.68			4.727	4.588	-5.09	-4.72	28.57
CV-2315	7/20/2026 10:20:00 AM											
CV-2315	7/27/2026 1:32:19 PM	188.0	188.0	-2.80	-2.47			2.766	2.676	-3.64	-2.86	28.53
CV-2316	7/2/2026 8:44:17 AM	147.6	147.5	-2.53	-2.49	61.2	60.8	2.526	2.487	-6.44	-6.44	28.52
CV-2316	7/2/2026 8:45:00 AM											
CV-2316	7/6/2026 10:15:04 AM	149.0	149.0	-1.29	-0.94	43.6	37.3	1.275	0.931	-4.24	-4.30	28.55
CV-2316	7/9/2026 9:11:41 AM	147.8	147.8	-1.35	-1.35	44.8	44.6	1.348	1.337	-5.52	-5.52	28.46
CV-2316	7/9/2026 9:15:00 AM											
CV-2316	7/9/2026 9:15:00 AM											
CV-2316	7/13/2026 1:31:38 PM	149.8	149.9	-1.68	-2.42	50.0	59.7	1.683	2.414	-6.59	-5.98	28.53
CV-2316	7/13/2026 1:32:10 PM	149.9	149.9	-2.48	-2.46	60.5	60.2	2.475	2.451	-5.94	-5.89	28.53
CV-2316	7/13/2026 1:50:00 PM											

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2316	7/20/2026 2:48:22 PM	151.3	151.4	0.10	-0.68	12.7	31.0	0.109	0.650	-2.02	-1.70	28.48
CV-2316	7/20/2026 2:48:45 PM	151.5	151.4	-0.81	-0.79	35.0	34.3	0.828	0.795	-1.68	-1.68	28.47
CV-2316	7/20/2026 2:50:00 PM											
CV-2316	7/29/2026 10:28:36 AM	150.4	150.4	-1.65	-1.69	49.1	49.6	1.631	1.667	-1.54	-1.60	28.46
CV-2319	7/9/2026 1:47:48 PM	141.9	142.6	-2.53	-1.32	0.0	0.0	-3.531	-2.828	-18.22		28.38
CV-2319	7/9/2026 1:48:57 PM	142.3	142.3	-1.52	-1.53	0.0	0.0	-2.802	-2.802	-18.28		28.38
CV-2319	7/21/2026 10:28:30 AM	144.6	144.7	-0.19	-0.19	85.4	88.2	1.950	2.081	-15.13	-14.57	28.6
CV-2321	7/2/2026 10:04:18 AM	147.4	147.4	-2.05	-2.06			0.209	0.124	-17.64	-17.64	28.55
CV-2321	7/2/2026 10:05:00 AM											
CV-2321	7/9/2026 9:24:29 AM	146.8	146.7	-2.22	-2.22			0.314	0.314	-18.53	-18.53	28.49
CV-2321	7/9/2026 9:25:00 AM											
CV-2321	7/9/2026 9:25:00 AM											
CV-2321	7/16/2026 9:35:00 AM											
CV-2321	7/16/2026 9:35:42 AM	147.4	147.3	-2.70	-2.75			0.316	0.323	-19.58	-19.58	28.44
CV-2321	7/30/2026 8:24:57 AM	146.8	146.8	-3.22	-3.13			0.034	0.020	-19.41	-19.41	28.5
CV-2322	7/10/2026 10:37:17 AM	92.8	92.8	-8.85	-8.59			8.834	8.645	0.62	0.62	28.51
CV-2322	7/29/2026 10:48:15 AM	179.2	178.4	-9.51	-9.05			9.917	9.400	-9.34	-8.63	28.45
CV-2322	7/29/2026 10:50:11 AM	185.2	186.1	-9.06	-8.95			9.429	9.336	-8.96	-8.80	28.45
CV-2324	7/2/2026 11:30:10 AM	121.6	121.7	-1.31	-1.21	15.8	7.8	0.154	0.037	-16.14		28.51
CV-2326	7/1/2026 10:11:42 AM	170.1	170.2	-11.69	-11.78			11.906	12.078	0.34	0.34	28.53
CV-2326	7/7/2026 8:55:47 AM	170.5	170.6	-6.24	-5.06			6.617	5.350	-11.26	-11.22	28.58
CV-2326	7/7/2026 8:56:20 AM	170.6	170.6	-4.74	-4.89			5.138	5.224	-10.84	-11.41	28.57
CV-2326	7/7/2026 9:00:00 AM											
CV-2326	7/7/2026 9:00:00 AM											
CV-2326	7/14/2026 8:52:10 AM	160.4	160.5	-5.08	-5.39			5.530	5.596	-8.32	-8.42	28.59
CV-2326	7/14/2026 9:05:00 AM											
CV-2326	7/21/2026 8:27:42 AM	162.5	162.6	-7.15	-7.10			7.452	7.474	-9.48	-9.26	28.57
CV-2326	7/28/2026 8:24:36 AM	163.4	163.0	-8.38	-6.78			8.780	7.253	-10.91	-10.53	28.49
CV-2326	7/28/2026 8:25:04 AM	163.0	163.0	-6.82	-6.74			7.268	7.293	-10.67	-10.69	28.49
CV-2327	7/8/2026 2:20:50 PM	186.5	186.6	-6.28	-6.32			6.324	6.385	-9.60	-9.77	28.53
CV-2327	7/8/2026 2:25:00 PM											

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2327	7/14/2026 1:28:40 PM	186.4	186.4	-3.54	-3.46			3.586	3.404	-7.48	-7.54	28.58
CV-2327	7/14/2026 1:35:00 PM											
CV-2327	7/21/2026 12:57:58 PM	182.2	183.0	-4.17	-4.12			4.126	4.043	-7.57	-7.60	28.6
CV-2327	7/29/2026 12:59:11 PM	182.2	182.5	-4.51	-4.49			4.344	4.362	-7.59	-7.41	28.49
CV-2328	7/8/2026 1:55:59 PM	142.8	142.7	-7.92	-7.90	14.7	12.7	0.534	0.401	-1.29	-1.27	28.53
CV-2328	7/13/2026 7:10:00 AM											
CV-2328	7/13/2026 7:10:00 AM											
CV-2328	7/29/2026 9:48:41 AM	146.7	146.3	-7.09	-6.75	2.9	5.4	0.021	0.072	-9.53	-9.67	28.47
CV-2328	7/29/2026 9:49:48 AM	146.5	146.3	-6.75	-6.75	3.5	5.4	0.030	0.071	-10.17	-9.78	28.49
CV-2328	7/29/2026 12:49:23 PM	147.3	147.3	-5.05	-5.05	7.0	7.3	0.121	0.132	-8.63	-8.63	28.49
CV-2333	7/6/2026 9:09:15 AM	186.6	186.7	-5.47	-5.92			5.743	6.200	5.05	5.05	28.57
CV-2333	7/6/2026 9:15:00 AM											
CV-2333	7/6/2026 9:15:00 AM											
CV-2333	7/9/2026 7:15:00 AM											
CV-2333	7/9/2026 7:15:00 AM											
CV-2333	7/9/2026 9:15:00 AM											
CV-2333	7/13/2026 9:03:07 AM	198.7	198.6	1.55	1.54			0.000	0.000	0.07	0.13	28.6
CV-2333	7/13/2026 9:04:45 AM	198.7	198.7	1.48	1.48			0.000	0.000	0.09	0.27	28.6
CV-2333	7/15/2026 2:28:17 PM	193.1	193.0	0.76	0.85			0.000	0.000	-2.12	-1.98	28.45
CV-2333	7/16/2026 4:31:46 PM	182.8	182.3	-6.51	-5.76	0.0	0.0	-6.693	-6.199	-7.53		28.37
CV-2333	7/16/2026 4:33:26 PM	185.2	185.2	-3.19	-5.47	0.0	0.0	-3.065	-5.368	-7.45		28.37
CV-2333	7/20/2026 9:04:08 AM	195.8	196.0	-1.42	-1.13			1.428	1.074	-5.56	-5.31	28.58
CV-2333	7/20/2026 9:05:00 AM											
CV-2333	7/27/2026 8:55:36 AM	186.7	186.8	-7.08	-7.41			7.392	7.782	-7.75	-7.71	28.57
CV-2334	7/9/2026 7:30:00 AM											
CV-2334	7/9/2026 7:30:00 AM											
CV-2334	7/13/2026 8:41:10 AM	128.6	128.6	-9.18	-8.93	2.2	7.1	0.014	0.141	-9.47	-9.46	28.55
CV-2334	7/23/2026 1:50:21 PM	136.8	137.0	-2.35	-1.83	12.8	10.5	0.459	0.312	0.15	0.16	28.54

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2334	7/23/2026 1:52:54 PM	137.0	137.0	-1.72	-1.72	15.1	15.1	0.640	0.640	-3.70	-3.70	28.52
CV-2335	7/1/2026 9:46:36 AM	86.7	86.4	-0.85	-0.85			0.839	0.837	-6.22	-6.38	28.55
CV-2335	7/16/2026 10:52:46 AM	108.7	108.5	-0.37	-0.37			0.362	0.362	-7.03	-7.03	28.51
CV-2336	7/1/2026 9:53:36 AM	67.6	68.1	-7.45	-7.05			7.648	7.200	-7.98	-7.82	28.55
CV-2336	7/16/2026 10:55:43 AM	96.5	96.5	-0.98	-0.98			0.969	0.934	-8.02	-8.19	28.52
CV-2337	7/1/2026 9:53:55 AM	151.5	151.4	-4.03	-4.05	29.9	29.8	2.591	2.582	-8.76	-8.76	28.56
CV-2337	7/1/2026 9:57:00 AM											
CV-2337	7/8/2026 8:58:06 AM	146.5	146.7	-7.41	-7.75	22.0	26.1	1.400	1.976	-9.28	-9.68	28.61
CV-2337	7/8/2026 9:00:00 AM											
CV-2337	7/8/2026 9:00:00 AM											
CV-2337	7/15/2026 8:40:46 AM	153.0	153.0	-6.07	-4.68	25.7	24.9	1.932	1.801	0.33	0.34	28.53
CV-2337	7/15/2026 8:42:31 AM	152.9	152.9	-3.54	-3.49	25.3	24.9	1.854	1.794	0.34	0.34	28.54
CV-2337	7/15/2026 8:45:00 AM											
CV-2337	7/22/2026 9:26:17 AM	153.8	153.5	0.34	-2.18	24.7	25.4	1.750	1.862	0.34	0.34	28.67
CV-2337	7/22/2026 9:26:54 AM	153.4	153.4	-2.23	-2.25	25.1	25.1	1.812	1.815	0.34	0.34	28.66
CV-2337	7/29/2026 8:26:34 AM	152.6	152.7	-5.36	-5.39	28.8	28.8	2.430	2.428	0.08	0.08	28.51
CV-2338	7/1/2026 9:40:30 AM	184.0	184.9	-1.60	-1.41			1.602	1.398	-1.96	-1.73	28.6
CV-2338	7/1/2026 9:42:00 AM											
CV-2338	7/8/2026 8:45:00 AM											
CV-2338	7/8/2026 8:45:00 AM											
CV-2338	7/8/2026 8:53:18 AM	191.1	191.4	-3.13	-2.80			3.086	2.805	-3.24	-2.69	28.65
CV-2338	7/15/2026 8:33:54 AM	179.2	180.9	-2.18	-2.50			2.118	2.410	-2.36	-2.69	28.57
CV-2338	7/15/2026 8:35:00 AM											
CV-2338	7/22/2026 9:17:45 AM	188.2	190.0	-2.77	-2.27			2.779	2.221	-2.73	-2.27	28.68
CV-2338	7/29/2026 8:21:59 AM	194.7	194.9	-3.22	-3.50			3.203	3.468	-3.89	-4.29	28.56
CV-2339	7/1/2026 9:20:00 AM											

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2339	7/1/2026 9:24:19 AM	175.1	173.4	-7.34	-4.72			0.000	0.000	0.00	0.00	28.59
CV-2339	7/1/2026 9:26:06 AM	173.8	175.1	-5.35	-5.31			5.448	5.442	-10.14	-10.06	28.57
CV-2339	7/8/2026 8:40:52 AM	102.3	101.8	-8.57	-6.41			8.961	6.749	-10.06	-10.44	28.64
CV-2339	7/8/2026 8:44:33 AM	101.9	102.6	-8.44	-8.44			8.880	8.873	-9.80	-9.85	28.64
CV-2339	7/15/2026 8:23:25 AM	162.4	161.9	-2.67	-2.73			2.661	2.701	-9.98	-9.77	28.57
CV-2339	7/15/2026 8:25:00 AM											
CV-2339	7/22/2026 9:08:40 AM	109.9	110.2	-9.10	-8.93			9.403	9.374	-10.19	-9.77	28.68
CV-2339	7/22/2026 9:11:54 AM	110.1	106.7	-10.00	-3.97			10.473	3.953	-10.11	-9.60	28.67
CV-2339	7/22/2026 9:12:58 AM	110.5	110.6	-6.74	-6.74			7.215	7.238	-9.87	-9.81	28.67
CV-2341	7/7/2026 9:50:03 AM	102.1	102.4	-2.71	-2.70			2.692	2.684	-9.85	-9.76	28.59
CV-2341	7/16/2026 2:21:29 PM	111.7	111.1	-2.84	-1.28			2.855	1.261	-8.92	-9.15	28.53
V-2342A-PL	7/1/2026 10:16:44 AM	168.1	170.3	-9.08	-8.75			9.472	9.140	0.17	0.20	28.61
V-2342A-PL	7/1/2026 10:25:00 AM											
V-2342A-PL	7/8/2026 9:35:00 AM											
V-2342A-PL	7/8/2026 9:35:00 AM											
V-2342A-PL	7/8/2026 9:37:26 AM	179.4	181.0	-8.01	-5.93			8.583	6.491	-8.52	-8.77	28.68
V-2342A-PL	7/8/2026 9:37:47 AM	180.6	180.5	-6.36	-6.19			6.869	6.739	-8.87	-8.76	28.68
V-2342A-PL	7/15/2026 9:30:00 AM											
V-2342A-PL	7/15/2026 9:31:03 AM	168.4	170.6	-4.85	-4.76			4.822	4.899	-6.59	-6.74	28.6
V-2342A-PL	7/22/2026 10:55:19 AM	170.6	171.3	-4.72	-4.71			4.722	4.654	-6.67	-6.40	28.68
V-2342A-PL	7/29/2026 8:59:38 AM	170.2	170.6	-6.07	-6.02			6.558	6.363	-9.45	-9.33	28.59
CV-2343-PLR	7/2/2026 1:25:00 AM											
CV-2343-PLR	7/2/2026 1:27:10 PM	152.5	153.7	-4.32	-4.20			4.329	4.246	0.76	0.86	28.68

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2343-PLR	7/8/2026 9:27:42 AM	165.8	166.3	-8.78	-8.55			9.376	9.234	0.34	0.34	28.68
CV-2343-PLR	7/8/2026 9:30:00 AM											
CV-2343-PLR	7/8/2026 9:30:00 AM											
CV-2343-PLR	7/15/2026 9:20:00 AM											
CV-2343-PLR	7/15/2026 9:20:56 AM	177.2	177.2	-1.70	-1.71			1.717	1.732	0.35	0.34	28.6
CV-2343-PLR	7/22/2026 10:51:24 AM	171.0	171.4	-2.23	-2.18			2.152	2.130	0.51	0.51	28.68
CV-2343-PLR	7/29/2026 8:52:02 AM	162.2	162.7	-8.28	-8.26			8.641	8.638	-12.90	-12.88	28.58
CV-2344	7/1/2026 8:20:00 AM											
CV-2344	7/1/2026 8:20:00 AM											
CV-2344	7/1/2026 10:08:37 AM	154.7	155.3	-3.75	-3.80			3.749	3.794	-11.53	-11.58	28.6
CV-2344	7/1/2026 10:17:00 AM											
CV-2344	7/8/2026 9:24:38 AM	161.0	161.1	-4.13	-4.13			4.117	4.115	-10.84	-10.80	28.67
CV-2344	7/8/2026 9:25:00 AM											
CV-2344	7/8/2026 9:25:00 AM											
CV-2344	7/15/2026 9:07:22 AM	160.8	161.3	-2.79	-2.80			2.784	2.785	-9.78	-9.49	28.57
CV-2344	7/15/2026 9:15:00 AM											
CV-2344	7/22/2026 10:47:52 AM	156.8	157.2	-1.20	-1.16			1.185	1.139	0.46	0.42	28.68
CV-2344	7/29/2026 8:48:14 AM	153.2	153.6	-5.06	-5.05			0.000	0.000	0.08	0.08	28.59
CV-2345	7/1/2026 8:51:00 AM											
CV-2345	7/1/2026 8:51:00 AM											
CV-2345	7/3/2026 9:09:08 AM	127.1	127.2	-3.86	-3.85			3.833	3.807	-10.27	-10.29	28.65
CV-2345	7/28/2026 1:17:28 PM	132.8	133.1	-4.44	-4.44			4.442	4.433	-11.77	-11.89	28.54
CV-2345	7/28/2026 1:18:30 PM	133.2	133.0	-4.44	-4.43			4.443	4.439	-11.78	-11.76	28.55
CV-2346	7/1/2026 8:10:00 AM											
CV-2346	7/1/2026 8:10:00 AM											
CV-2346	7/1/2026 10:04:09 AM	189.0	189.0	-6.39	-6.07			6.747	6.390	-11.25	-11.41	28.58
CV-2346	7/1/2026 10:10:00 AM											
CV-2346	7/8/2026 9:18:20 AM	186.5	186.0	-7.32	-7.56			7.869	8.130	-11.55	-11.59	28.67
CV-2346	7/8/2026 9:20:00 AM											
CV-2346	7/8/2026 9:20:00 AM											
CV-2346	7/15/2026 9:03:00 AM	185.4	185.7	-3.54	-3.82			3.799	3.710	-6.25	-6.74	28.57

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2346	7/15/2026 9:05:00 AM											
CV-2346	7/22/2026 10:45:05 AM	186.3	186.6	-4.89	-4.98			5.433	4.920	-7.01	-6.74	28.67
CV-2346	7/29/2026 8:44:01 AM	185.4	185.3	-11.07	-10.87			11.491	11.181	-13.77	-13.77	28.57
CV-2347	7/1/2026 8:05:00 AM											
CV-2347	7/1/2026 8:05:00 AM											
CV-2347	7/3/2026 8:56:09 AM	119.7	120.3	-3.65	-3.63			3.639	3.604	-8.91	-10.67	28.63
CV-2347	7/28/2026 9:44:36 AM	123.2	123.6	-5.40	-5.40			5.616	5.636	-12.00	-11.97	28.54
CV-2348	7/1/2026 8:00:00 AM											
CV-2348	7/1/2026 8:00:00 AM											
CV-2348	7/3/2026 8:54:05 AM	81.6	81.9	-9.27	-9.27			9.401	9.401	0.44	0.44	28.63
CV-2348	7/30/2026 12:27:31 PM	132.3	132.3	-11.35	-11.38			11.434	11.462	0.27	0.11	28.64
CV-2348	7/30/2026 12:28:19 PM	132.3	132.3	-11.34	-11.36			11.399	11.367	0.12	0.10	28.64
CV-2349	7/1/2026 1:45:13 PM	178.9	179.6	-4.98	-5.52			4.900	5.844	-6.18	-6.65	28.64
CV-2349	7/1/2026 1:50:00 PM											
CV-2349	7/2/2026 8:20:00 AM											
CV-2349	7/2/2026 8:20:00 AM											
CV-2349	7/8/2026 10:21:09 AM	176.5	176.5	-4.38	-4.72			4.816	5.161	-6.11	-5.98	28.69
CV-2349	7/8/2026 10:30:00 AM											
CV-2349	7/8/2026 10:30:00 AM											
CV-2349	7/15/2026 10:06:40 AM	181.3	181.3	-5.40	-5.77			5.986	6.323	-6.32	-6.82	28.61
CV-2349	7/15/2026 10:10:00 AM											
CV-2349	7/22/2026 1:58:42 PM	166.1	170.4	-4.33	-4.93			4.506	5.061	-5.35	-6.40	28.67
CV-2349	7/29/2026 9:20:49 AM	180.0	180.4	-6.46	-6.07			6.920	6.497	-7.81	-7.71	28.62
CV-2350	7/3/2026 7:38:14 AM	110.9	111.2	-12.71	-11.72			12.676	11.654	-12.94	-11.87	28.66
CV-2350	7/8/2026 7:40:00 AM											
CV-2350	7/20/2026 1:03:58 PM	118.8	118.8	-8.64	-9.01			8.581	8.918	-8.40	-8.74	28.66
CV-2351	7/1/2026 8:40:00 AM											
CV-2351	7/1/2026 8:40:00 AM											
CV-2351	7/7/2026 10:34:21 AM	99.8	100.0	-1.37	-1.21			1.286	1.030	-0.79	-0.56	28.62
CV-2351	7/7/2026 10:35:02 AM	100.3	100.4	-1.21	-0.96			1.119	0.737	-0.72	-0.38	28.63
CV-2351	7/28/2026 2:17:08 PM	103.0	103.3	-1.42	-1.16			1.021	1.248	-0.95	-1.00	28.52
CV-2352	7/2/2026 7:50:00 AM											
CV-2352	7/2/2026 7:50:00 AM											

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2352	7/2/2026 1:09:51 PM	166.4	166.8	9.52	-0.48			0.000	0.439	-1.48	-1.37	28.63
CV-2352	7/2/2026 1:12:12 PM	168.4	166.2	-0.50	-0.68			0.641	0.788	-1.05	-1.24	28.63
CV-2352	7/2/2026 2:00:00 PM											
CV-2352	7/2/2026 2:16:24 PM	162.1	168.7	-0.48	-0.47			0.494	0.472	-0.55	-0.30	28.66
CV-2352	7/9/2026 10:20:00 AM											
CV-2352	7/9/2026 10:20:00 AM											
CV-2352	7/9/2026 10:28:26 AM	182.9	182.7	-1.54	-1.69			1.447	1.031	-1.57	-1.18	28.59
CV-2352	7/9/2026 10:30:58 AM	180.1	180.8	-1.45	-1.34			1.322	1.375	-1.68	-1.68	28.59
CV-2352	7/15/2026 9:35:00 AM											
CV-2352	7/15/2026 9:35:39 AM	146.1	146.6	-1.72	-1.95			1.708	1.963	-1.52	-1.68	28.59
CV-2352	7/22/2026 10:59:08 AM	187.7	187.7	-1.61	-1.26			1.532	1.352	-1.23	-0.97	28.68
CV-2352	7/29/2026 9:05:16 AM	141.5	141.7	-2.78	-2.61			2.986	2.691	-2.98	-2.76	28.59
CV-2353-PLR	7/1/2026 10:24:09 AM	122.9	123.5	-0.23	-0.17			0.223	0.163	-9.88	-10.44	28.63
CV-2353-PLR	7/8/2026 8:10:00 AM											
CV-2353-PLR	7/8/2026 8:10:00 AM											
CV-2353-PLR	7/28/2026 2:07:19 PM	133.4	132.5	-7.60	-7.64			7.729	7.684	-7.70	-7.52	28.52
CV-2353-PLR	7/28/2026 2:11:24 PM	131.3	131.5	-7.43	-7.45			7.558	7.630	-7.51	-7.63	28.55
CV-2354	7/1/2026 1:52:06 PM	181.6	181.7	-1.56	-2.09			1.562	2.035	-3.76	-4.13	28.63
CV-2354	7/1/2026 2:04:00 PM											
CV-2354	7/8/2026 8:00:00 AM											
CV-2354	7/8/2026 8:00:00 AM											
CV-2354	7/8/2026 10:02:59 AM	186.6	186.6	-1.64	-1.62			1.637	1.581	-3.41	-3.05	28.71
CV-2354	7/8/2026 10:20:00 AM											
CV-2354	7/8/2026 10:20:00 AM											
CV-2354	7/15/2026 10:23:28 AM	177.1	177.0	-4.18	-4.59			3.609	3.984	-4.40	-4.39	28.62
CV-2354	7/15/2026 10:25:00 AM											
CV-2354	7/22/2026 2:04:50 PM	172.2	172.5	-4.62	-4.53			4.696	4.810	-5.47	-5.14	28.65
CV-2354	7/29/2026 9:14:57 AM	185.8	185.9	-3.52	-3.52			3.543	3.619	-5.47	-5.05	28.6
CV-24001	7/1/2026 9:35:32 AM	90.1	90.1	-1.57	-1.57			1.569	1.560	-6.45	-6.31	28.55

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24001	7/16/2026 10:48:16 AM	116.1	116.1	-1.38	-1.37			1.346	1.348	-7.18	-6.97	28.49
CV-24002	7/1/2026 9:27:49 AM	108.8	109.8	-3.26	-3.26			3.258	3.251	-12.73	-12.66	28.53
CV-24002	7/16/2026 10:43:22 AM	114.3	114.4	-2.97	-2.97			2.960	2.962	-10.56	-10.38	28.49
CV-24003	7/1/2026 9:12:42 AM	122.5	121.8	-1.86	-1.56	15.7	12.1	0.680	0.402	-12.91	-12.99	28.53
CV-24003	7/16/2026 10:34:14 AM	124.9	124.9	-1.04	-1.03	8.2	8.8	0.183	0.213	-10.80	-10.27	28.5
CV-24004	7/1/2026 9:08:53 AM	120.9	120.8	-2.54	-2.43	17.1	15.7	0.807	0.676	-13.61	-13.41	28.51
CV-24004	7/16/2026 10:31:15 AM	123.8	123.8	-1.93	-1.80	12.0	9.7	0.396	0.257	-10.41	-9.55	28.47
CV-24006	7/1/2026 10:20:36 AM	129.2	128.8	-1.51	-1.37	15.1	12.3	0.632	0.416	-6.25	-6.33	28.54
CV-24006	7/16/2026 10:18:58 AM	121.7	121.7	-0.66	-0.66	1.9	2.0	0.415	0.420	-5.65	-5.81	28.47
CV-24007	7/1/2026 10:24:33 AM	139.2	139.3	-1.76	-1.42	40.9	32.6	4.745	3.018	-13.56	-13.59	28.53
CV-24007	7/16/2026 10:21:13 AM	140.7	140.7	-1.00	-0.99	28.2	28.2	2.248	2.256	-11.14	-10.94	28.47
CV-24008	7/7/2026 8:38:49 AM	171.3	170.6	1.35	-3.53	44.5	70.8	1.367	3.517	-9.13	-9.10	28.56
CV-24008	7/7/2026 8:39:31 AM	170.9	170.9	-7.48	-7.54	104.5	104.5	7.807	7.810	-10.84	-11.16	28.55
CV-24008	7/7/2026 8:45:00 AM											
CV-24008	7/7/2026 8:45:00 AM											
CV-24008	7/13/2026 2:30:36 PM	175.9	175.8	-4.98	-5.05	86.7	87.0	5.361	5.397	-5.59	-5.64	28.53
CV-24008	7/13/2026 2:35:00 PM											
CV-24008	7/20/2026 2:10:19 PM	176.6	176.6	-7.03	-6.41	99.4	94.8	7.117	6.459	-7.64	-8.25	28.5
CV-24008	7/20/2026 2:11:02 PM	176.6	176.6	-4.42	-4.44	78.9	79.0	4.433	4.450	-8.81	-8.38	28.51
CV-24008	7/20/2026 2:15:00 PM											
CV-24008	7/28/2026 7:59:01 AM	175.6	176.6	0.02	-3.28	5.5	67.9	0.021	3.275	-11.60	-11.52	28.49
CV-24008	7/28/2026 7:59:41 AM	175.0	176.3	-3.27	-3.25	67.5	67.2	3.221	3.207	-11.56	-10.91	28.47
CV-24009	7/7/2026 8:34:34 AM	159.5	159.7	-1.55	-1.55			0.000	0.000	-8.76	-8.76	28.57
CV-24009	7/7/2026 8:35:11 AM	159.7	159.4	-1.57	-1.56			0.000	0.000	-8.55	-8.51	28.55
CV-24009	7/7/2026 8:40:00 AM											
CV-24009	7/7/2026 8:40:00 AM											
CV-24009	7/13/2026 2:26:43 PM	159.4	159.3	-0.45	-0.45			0.390	0.430	-5.98	-5.97	28.53
CV-24009	7/13/2026 2:27:24 PM	159.4	159.9	-0.42	-3.70			0.421	0.669	-5.99	-6.32	28.53
CV-24009	7/13/2026 2:27:53 PM	160.7	160.8	-3.93	-3.93			0.757	0.799	-6.32	-6.32	28.53
CV-24009	7/13/2026 2:30:00 PM											

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24009	7/20/2026 2:07:05 PM	160.3	160.0	-5.71	-5.69			0.000	0.000	-7.93	-8.08	28.49
CV-24009	7/20/2026 2:10:00 PM											
CV-24009	7/28/2026 7:52:05 AM	164.9	164.1	-6.07	-4.88			0.000	0.106	-11.75	-11.51	28.46
CV-24009	7/28/2026 7:53:03 AM	164.0	164.4	-4.60	-4.60			0.116	0.120	-11.34	-10.69	28.46
CV-24010	7/8/2026 1:33:01 PM	105.0	101.9	-9.92	-0.42			9.920	0.384	-9.88	-9.62	28.58
CV-24010	7/8/2026 1:34:33 PM	104.5	104.6	-0.92	-0.87			0.907	0.832	-10.14	-10.02	28.59
CV-24010	7/21/2026 8:23:59 AM	77.8	78.0	-0.70	-0.69			0.701	0.693	-6.69	-6.28	28.61
CV-24011	7/7/2026 8:50:42 AM	187.2	187.2	-1.54	-1.55	30.8	29.0	2.899	2.561	-9.54	-8.74	28.57
CV-24011	7/7/2026 8:55:00 AM											
CV-24011	7/7/2026 8:55:00 AM											
CV-24011	7/14/2026 8:49:11 AM	186.8	186.6	-0.88	-1.47	25.2	28.2	1.932	2.411	-6.74	-6.53	28.6
CV-24011	7/14/2026 8:50:04 AM	186.4	186.4	-1.80	-1.87	29.7	29.9	2.685	2.731	-6.38	-6.40	28.6
CV-24011	7/14/2026 9:00:00 AM											
CV-24011	7/21/2026 8:30:40 AM	183.6	183.5	-3.12	-3.08	33.1	32.1	3.338	3.133	-8.51	-8.25	28.6
CV-24011	7/28/2026 8:27:29 AM	181.9	182.1	-4.34	-4.09	37.3	36.8	4.262	4.148	-10.41	-10.11	28.49
CV-24012	7/7/2026 9:19:39 AM	188.1	187.9	-10.37	-10.45			10.777	10.812	-10.81	-10.79	28.59
CV-24012	7/7/2026 9:20:00 AM											
CV-24012	7/7/2026 9:20:00 AM											
CV-24012	7/14/2026 9:08:24 AM	187.0	187.1	-9.07	-9.10			9.542	9.615	-9.81	-10.11	28.6
CV-24012	7/14/2026 9:25:00 AM											
CV-24012	7/21/2026 8:39:29 AM	181.6	181.6	-9.38	-9.44			9.703	9.741	-9.86	-10.02	28.61
CV-24012	7/28/2026 8:13:47 AM	183.7	183.4	-10.52	-11.12			10.899	11.710	-11.04	-12.00	28.49
CV-24013	7/2/2026 1:36:18 PM	105.7	105.8	-9.19	-9.39			9.084	9.217	-10.32	-10.18	28.58
CV-24013	7/21/2026 7:52:29 AM	124.1	126.5	-9.89	-9.76			9.912	9.851	-9.65	-9.59	28.59
CV-24014	7/6/2026 10:04:48 AM	180.0	180.2	-4.16	-4.09	37.0	36.9	4.185	4.143	-3.08	-3.03	28.53
CV-24014	7/6/2026 10:25:00 AM											
CV-24014	7/6/2026 10:25:00 AM											
CV-24014	7/13/2026 9:47:14 AM	179.6	179.9	-4.80	-5.05	41.3	42.8	5.200	5.587	-9.83	-10.78	28.59

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24014	7/13/2026 10:00:00 AM											
CV-24014	7/20/2026 9:37:23 AM	179.5	179.6	-4.71	-4.94	39.1	40.2	4.669	4.931	-9.35	-10.11	28.57
CV-24014	7/20/2026 9:40:00 AM											
CV-24014	7/27/2026 9:37:20 AM	180.4	180.4	-4.83	-4.61	39.7	38.7	4.804	4.570	-9.77	-8.78	28.57
CV-24015	7/6/2026 9:45:00 AM											
CV-24015	7/6/2026 9:45:00 AM											
CV-24015	7/6/2026 9:55:39 AM	189.5	189.4	-8.56	-3.95			8.801	3.963	-0.13	-0.01	28.57
CV-24015	7/6/2026 9:57:45 AM	189.6	189.6	-4.21	-4.20			4.230	4.216	0.34	0.34	28.57
CV-24015	7/13/2026 9:34:45 AM	189.5	189.6	-2.53	-2.45			2.531	2.435	-7.30	-6.91	28.58
CV-24015	7/13/2026 9:45:00 AM											
CV-24015	7/20/2026 9:34:26 AM	186.9	186.9	-3.35	-3.31			3.290	3.327	-7.27	-6.80	28.58
CV-24015	7/20/2026 9:35:00 AM											
CV-24015	7/27/2026 9:28:10 AM	188.5	188.7	-3.43	-3.42			3.405	3.374	-7.98	-7.75	28.58
CV-24016	7/7/2026 8:59:53 AM	176.0	175.9	-6.07	-6.07			6.449	6.439	-7.92	-7.93	28.59
CV-24016	7/7/2026 9:05:00 AM											
CV-24016	7/7/2026 9:05:00 AM											
CV-24016	7/14/2026 8:54:39 AM	177.4	177.5	-3.70	-3.73			3.696	3.738	-5.09	-5.24	28.6
CV-24016	7/14/2026 9:10:00 AM											
CV-24016	7/21/2026 8:25:11 AM	170.0	170.2	-4.95	-5.05			5.147	5.203	-6.66	-6.75	28.6
CV-24016	7/28/2026 8:19:06 AM	168.4	168.5	-6.26	-6.40			6.652	6.703	-8.06	-8.15	28.49
CV-24017	7/2/2026 9:54:07 AM	187.2	188.1	-9.38	-4.79			9.601	4.756	-10.50	-10.79	28.58
CV-24017	7/7/2026 9:07:06 AM	193.3	193.5	-1.83	-1.93			1.845	1.899	-10.98	-11.24	28.57
CV-24017	7/7/2026 9:10:00 AM											
CV-24017	7/7/2026 9:10:00 AM											
CV-24017	7/13/2026 9:00:00 AM											
CV-24017	7/13/2026 9:00:00 AM											
CV-24017	7/14/2026 9:01:41 AM	191.4	190.2	-1.39	-3.17			1.405	3.122	-7.75	-8.42	28.6
CV-24017	7/14/2026 9:02:10 AM	189.9	189.7	-3.44	-3.42			3.424	3.416	-8.04	-7.81	28.6
CV-24017	7/14/2026 9:15:00 AM											
CV-24017	7/21/2026 8:34:08 AM	186.0	186.1	-4.43	-4.37			4.500	4.424	-7.75	-7.58	28.6

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24017	7/28/2026 8:09:09 AM	185.9	185.7	-6.22	-6.23			6.522	6.481	-10.88	-10.91	28.49
CV-24018	7/1/2026 1:40:12 PM	92.0	92.0	-0.26	-0.25			0.000	0.000	-11.40	-11.08	28.55
CV-24018	7/29/2026 2:10:56 PM	136.7	136.3	-3.18	-2.79			3.016	2.625	-8.70	-8.75	28.45
CV-24018	7/29/2026 2:11:44 PM	136.2	137.1	-2.74	-2.61			2.496	2.431	-8.61	-8.56	28.45
CV-24019	7/7/2026 9:25:00 AM											
CV-24019	7/7/2026 9:25:00 AM											
CV-24019	7/7/2026 9:29:12 AM	187.0	187.5	0.59	-6.25			0.000	6.728	-10.52	-10.31	28.57
CV-24019	7/7/2026 9:29:55 AM	187.4	187.5	-6.30	-6.21			6.772	6.712	-10.23	-9.96	28.58
CV-24019	7/14/2026 9:15:49 AM	185.4	186.4	-6.15	-6.09			6.634	6.667	-9.52	-9.54	28.6
CV-24019	7/14/2026 9:30:00 AM											
CV-24019	7/21/2026 8:48:47 AM	181.8	181.6	-6.02	-6.11			6.351	6.540	-9.27	-9.43	28.63
CV-24019	7/28/2026 8:16:19 AM	180.6	181.1	-7.03	-6.91			7.403	7.401	-10.41	-10.27	28.49
CV-24020	7/2/2026 1:45:52 PM	87.1	89.1	-10.21	-10.17	2.2	1.6	0.013	0.007	-9.99	-9.88	28.58
CV-24020	7/21/2026 7:57:54 AM	74.3	74.4	-10.33	-10.44	1.5	2.4	0.006	0.015	-10.00	-10.20	28.6
CV-24021	7/2/2026 1:50:07 PM	89.6	89.8	-10.97	-11.07			10.798	10.964	-10.71	-10.75	28.59
CV-24021	7/21/2026 8:09:32 AM	77.0	76.7	-10.15	-10.21			10.140	10.177	-10.12	-10.19	28.61
CV-24022-PLI	7/6/2026 10:15:31 AM	195.6	195.7	-7.59	-7.60			7.811	7.836	0.78	0.79	28.53
CV-24022-PLI	7/6/2026 10:30:00 AM											
CV-24022-PLI	7/6/2026 10:30:00 AM											
CV-24022-PLI	7/13/2026 9:55:02 AM	193.2	193.0	-10.30	-10.97			10.902	11.460	-10.63	-11.73	28.6
CV-24022-PLI	7/13/2026 10:05:00 AM											
CV-24022-PLI	7/20/2026 9:40:24 AM	195.1	195.0	-7.91	-8.76			8.260	9.143	-8.70	-9.89	28.59
CV-24022-PLI	7/20/2026 9:45:00 AM											

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24022-PLI	7/27/2026 9:40:43 AM	195.3	195.1	-8.99	-9.12			9.590	9.651	-9.25	-9.26	28.57
CV-24023	7/3/2026 9:30:00 AM											
CV-24023	7/3/2026 10:41:33 AM	196.6	196.8	-6.39	-6.71			6.795	7.051	-8.50	-9.83	28.58
CV-24023	7/6/2026 9:50:00 AM											
CV-24023	7/6/2026 9:50:00 AM											
CV-24023	7/6/2026 10:00:42 AM	196.7	196.8	-7.71	-7.75			7.924	7.855	0.37	0.38	28.57
CV-24023	7/13/2026 9:42:44 AM	195.9	196.0	-5.71	-5.73			6.127	6.145	0.34	0.34	28.59
CV-24023	7/13/2026 9:55:00 AM											
CV-24023	7/20/2026 9:42:39 AM	196.1	196.3	-5.42	-5.39			5.923	5.669	0.32	0.34	28.57
CV-24023	7/20/2026 9:50:00 AM											
CV-24023	7/27/2026 9:30:57 AM	196.4	196.5	-5.39	-5.39			5.910	5.823	0.49	0.34	28.58
CV-24024-PLI	7/13/2026 9:00:47 AM	131.8	131.7	-6.25	-5.70			6.394	5.871	-6.16	-6.09	28.59
CV-24024-PLI	7/13/2026 9:01:05 AM	131.7	131.8	-5.72	-5.74			5.853	5.905	-6.13	-6.19	28.59
CV-24024-PLI	7/23/2026 8:16:11 AM	158.4	157.6	-9.40	-7.30			9.394	7.265	-10.36	-10.11	28.55
CV-24024-PLI	7/27/2026 9:18:50 AM	162.6	163.0	-5.13	-5.05			5.646	5.456	-7.53	-7.31	28.6
CV-24025	7/7/2026 10:05:00 AM											
CV-24025	7/7/2026 10:05:00 AM											
CV-24025	7/7/2026 10:09:55 AM	189.0	188.2	-0.40	-0.40			0.401	0.401	-2.34	-2.33	28.57
CV-24025	7/14/2026 9:41:47 AM	187.4	187.6	-1.03	-1.03			1.017	1.019	-3.35	-3.43	28.6
CV-24025	7/14/2026 9:50:00 AM											
CV-24025	7/21/2026 9:11:03 AM	184.1	184.5	-0.99	-0.95			1.012	0.949	-3.17	-3.20	28.64
CV-24025	7/28/2026 9:23:57 AM	182.2	182.6	-1.90	-1.90			1.890	1.881	-4.50	-4.29	28.49
CV-24026	7/7/2026 9:35:00 AM											
CV-24026	7/7/2026 9:35:00 AM											
CV-24026	7/7/2026 9:41:18 AM	152.7	152.2	-9.66	-8.16			10.244	8.700	-10.00	-9.82	28.6
CV-24026	7/7/2026 9:49:00 AM	150.8	151.7	-2.39	-2.35			2.370	2.295	-10.11	-10.19	28.6

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24026	7/14/2026 9:25:45 AM	133.2	137.0	-6.74	-1.77			7.286	1.770	-8.80	-9.31	28.61
CV-24026	7/14/2026 9:27:42 AM	135.0	135.2	-1.78	-1.73			1.779	1.724	-9.09	-8.25	28.61
CV-24026	7/14/2026 9:28:29 AM	137.2	136.0	-1.66	-1.61			1.652	1.599	-8.36	-9.43	28.61
CV-24026	7/21/2026 8:03:12 AM	109.8	106.4	-3.39	-3.26			3.383	3.242	-8.94	-8.51	28.62
CV-24027	7/2/2026 1:59:27 PM	89.3	89.3	-10.92	-11.07			10.892	11.064	-10.69	-10.84	28.58
CV-24027	7/21/2026 8:11:59 AM	80.6	80.5	-9.86	-10.10			9.793	10.041	-9.86	-10.08	28.61
CV-24028	7/6/2026 10:19:46 AM	194.5	194.1	-3.29	-3.29			3.213	3.213	-2.36	-2.36	26.59
CV-24028	7/6/2026 10:35:00 AM											
CV-24028	7/6/2026 10:35:00 AM											
CV-24028	7/13/2026 10:06:15 AM	193.9	194.6	-11.14	-11.46			11.741	12.014	-12.17	-12.69	28.6
CV-24028	7/13/2026 10:10:00 AM											
CV-24028	7/20/2026 9:45:58 AM	193.7	194.1	-9.10	-9.13			9.588	9.619	-10.80	-10.80	28.57
CV-24028	7/20/2026 9:55:00 AM											
CV-24028	7/27/2026 9:44:15 AM	194.4	194.1	-7.08	-7.27			7.743	7.896	-8.10	-8.25	28.57
CV-24029	7/6/2026 7:47:53 AM	85.3	85.2	-11.41	-11.28			11.174	11.052	-11.16	-11.10	28.55
CV-24029	7/6/2026 7:49:23 AM	90.9	90.6	-11.67	-11.63			11.422	11.338	-11.49	-11.56	28.55
CV-24029	7/23/2026 8:08:33 AM	96.1	89.3	-11.89	-10.99			11.823	10.909	-12.01	-11.30	28.53
CV-24029	7/23/2026 8:09:38 AM	94.3	94.3	-11.56	-11.50			11.441	11.399	-11.54	-12.14	28.55
CV-24030	7/6/2026 9:27:02 AM	186.3	188.2	-4.63	-2.19			4.631	2.226	0.05	0.54	28.57
CV-24030	7/6/2026 9:28:14 AM	188.1	188.0	-2.23	-2.23			2.130	2.130	1.01	1.01	28.57
CV-24030	7/6/2026 9:30:00 AM											
CV-24030	7/6/2026 9:30:00 AM											

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24030	7/6/2026 9:39:05 AM	189.0	189.0	-2.06	-2.06			2.057	2.116	-2.61	-2.65	28.57
CV-24030	7/13/2026 9:18:53 AM	193.3	190.8	0.12	-3.67			0.000	3.674	-3.97	-3.93	28.6
CV-24030	7/13/2026 9:21:12 AM	190.1	191.3	-3.84	-1.72			3.805	1.664	-4.11	-4.14	28.6
CV-24030	7/13/2026 9:22:29 AM	190.5	190.6	-2.32	-2.37			2.554	2.304	-4.70	-4.80	28.6
CV-24030	7/13/2026 9:30:00 AM											
CV-24030	7/20/2026 9:13:06 AM	189.0	189.1	-3.23	-2.40			3.246	2.445	-6.78	-6.91	28.6
CV-24030	7/20/2026 9:14:05 AM	189.4	189.3	-2.62	-2.34			2.650	2.032	-6.53	-6.32	28.6
CV-24030	7/20/2026 9:20:00 AM											
CV-24030	7/27/2026 9:09:52 AM	150.6	149.9	-6.20	-1.03			6.608	1.017	-6.46	-6.84	28.6
CV-24030	7/27/2026 9:12:05 AM	151.7	151.7	-1.01	-0.95			1.017	0.958	-7.09	-7.12	28.6
CV-24031	7/1/2026 1:57:55 PM	85.5	77.9	-7.37	-6.86			0.026	0.000	-11.78	-11.65	28.58
CV-24031	7/2/2026 10:12:38 AM	153.1	153.4	-1.39	-1.41			1.387	1.416	-10.62	-10.44	28.6
CV-24031	7/2/2026 10:20:00 AM											
CV-24031	7/7/2026 10:23:01 AM	154.5	154.6	-0.38	-2.75			0.316	2.733	-6.81	-6.76	28.59
CV-24031	7/7/2026 10:23:43 AM	154.5	154.5	-2.92	-2.91			2.878	2.879	-6.97	-6.98	28.6
CV-24031	7/7/2026 10:25:00 AM											
CV-24031	7/7/2026 10:25:00 AM											
CV-24031	7/14/2026 9:38:15 AM	159.3	159.6	-4.10	-4.06			4.066	4.034	-7.75	-7.75	28.61
CV-24031	7/14/2026 9:45:00 AM											
CV-24031	7/21/2026 9:07:39 AM	149.3	149.3	-5.39	-5.39			5.834	5.887	-9.04	-8.97	28.65
CV-24031	7/28/2026 9:26:57 AM	154.8	154.5	-5.73	-5.73			6.376	6.404	-8.99	-10.15	28.52
CV-24032	7/7/2026 10:05:00 AM											
CV-24032	7/7/2026 10:14:38 AM	182.0	181.8	-0.96	-0.91			0.921	0.914	-0.98	-0.67	28.6
CV-24032	7/7/2026 10:15:00 AM											
CV-24032	7/7/2026 10:15:00 AM											
CV-24032	7/14/2026 9:35:53 AM	176.9	176.9	-4.25	-4.24			4.220	4.211	-6.48	-6.44	28.62
CV-24032	7/14/2026 9:40:00 AM											

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [ ]	Adj Temp [ ]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24032	7/21/2026 9:04:20 AM	169.6	169.6	-5.32	-5.39			5.678	5.732	-6.77	-6.82	28.64
CV-24032	7/28/2026 9:12:58 AM	170.1	170.7	-4.47	-4.71			4.471	4.695	-5.15	-5.64	28.5
CV-24033	7/7/2026 9:57:36 AM	117.0	118.3	-2.80	-0.56			2.791	0.540	-2.27	-2.44	28.6
CV-24033	7/7/2026 9:59:21 AM	117.7	117.0	-1.52	-1.51			1.499	1.494	-1.64	-1.65	28.6
CV-24033	7/29/2026 2:05:34 PM	99.1	99.0	-3.94	-2.70			3.928	2.646	-3.55	-3.15	28.45
CV-24033	7/29/2026 2:05:59 PM	99.6	99.7	-3.54	-3.58			3.519	3.540	-3.55	-3.74	28.45
CV-24034	7/6/2026 10:26:57 AM	185.8	190.2	16.34	-6.86			0.000	7.136	-5.03	-2.92	28.56
CV-24034	7/6/2026 10:28:02 AM	190.9	190.0	-7.44	-7.75			7.758	7.900	-2.72	-2.69	28.56
CV-24034	7/6/2026 10:45:00 AM											
CV-24034	7/6/2026 10:45:00 AM											
CV-24034	7/13/2026 10:15:00 AM											
CV-24034	7/13/2026 10:15:08 AM	183.3	176.3	-11.19	-3.06			11.696	3.045	-11.68	-11.86	28.6
CV-24034	7/13/2026 10:16:16 AM	177.1	176.7	-2.07	-2.17			2.064	2.153	-11.56	-11.79	28.6
CV-24034	7/20/2026 9:53:07 AM	162.5	166.2	0.17	-5.44			0.000	5.867	-10.79	-9.52	28.6
CV-24034	7/20/2026 9:53:35 AM	170.9	169.3	-6.87	-6.87			7.277	7.356	-10.53	-10.44	28.6
CV-24034	7/20/2026 10:00:00 AM											
CV-24034	7/27/2026 10:35:43 AM	151.2	146.3	-8.09	-7.76			8.635	8.350	-8.42	-8.08	28.58
CV-24034	7/27/2026 10:36:13 AM	145.9	145.9	-8.02	-8.06			8.686	8.714	-8.51	-8.65	28.57
CV-24035-PL	7/6/2026 9:05:37 AM	187.6	187.7	-5.56	-5.62			5.834	5.905	5.05	5.05	28.55
CV-24035-PL	7/6/2026 9:10:00 AM											
CV-24035-PL	7/6/2026 9:10:00 AM											
CV-24035-PL	7/13/2026 8:51:05 AM	183.3	182.8	-2.31	-2.22			2.360	2.268	-3.09	-3.03	28.6
CV-24035-PL	7/13/2026 9:10:00 AM											
CV-24035-PL	7/20/2026 8:57:32 AM	179.5	180.2	-5.20	-4.89			5.529	5.156	-6.80	-6.51	28.57
CV-24035-PL	7/20/2026 9:00:00 AM											

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24035-PLI	7/27/2026 8:46:51 AM	188.4	187.7	-7.19	-6.36			7.613	6.630	-7.65	-6.74	28.57
CV-24036	7/1/2026 2:03:29 PM	92.4	92.7	-11.50	-11.54			11.464	11.520	-11.62	-11.67	28.58
CV-24036	7/2/2026 12:42:35 PM	85.1	85.2	-7.91	-8.03			8.222	8.434	-9.99	-10.27	28.58
CV-24036	7/29/2026 1:56:07 PM	104.4	104.2	-8.37	-8.33			8.494	8.464	-8.34	-8.37	28.45
CV-24037	7/1/2026 2:18:36 PM	138.5	137.2	-5.34	-4.73			5.364	4.725	-11.35	-11.54	28.57
CV-24037	7/1/2026 2:19:56 PM	136.9	136.9	-4.50	-4.50			4.557	4.557	-11.15	-11.15	28.55
CV-24037	7/29/2026 1:50:59 PM	136.9	137.2	-0.73	-0.78			0.627	0.674	-7.60	-7.31	28.45
CV-24038	7/7/2026 1:32:14 PM	190.8	189.0	-8.89	-6.75			8.889	6.751	-10.11	-10.17	28.56
CV-24038	7/7/2026 1:33:35 PM	190.0	190.3	-6.74	-6.91			6.785	6.952	-10.44	-10.02	28.55
CV-24038	7/7/2026 1:35:00 PM											
CV-24038	7/7/2026 1:35:00 PM											
CV-24038	7/14/2026 10:14:43 AM	192.0	191.1	-0.58	-4.33			0.668	4.388	-5.99	-5.88	28.64
CV-24038	7/14/2026 10:15:00 AM											
CV-24038	7/14/2026 10:15:17 AM	190.7	190.7	-4.29	-4.26			4.288	4.082	-6.82	-6.91	28.62
CV-24038	7/21/2026 10:10:15 AM	195.1	194.9	2.06	-3.74			0.000	3.818	-9.05	-8.33	28.66
CV-24038	7/21/2026 10:11:14 AM	194.6	194.9	-4.71	-4.38			4.597	4.789	-8.34	-9.22	28.65
CV-24038	7/28/2026 9:31:51 AM	188.8	188.5	-4.73	-4.57			4.629	5.129	-10.15	-10.65	28.53
CV-24039	7/7/2026 2:00:00 PM											
CV-24039	7/7/2026 2:00:00 PM											
CV-24039	7/7/2026 2:04:06 PM	171.1	177.4	-6.74	-3.39			6.737	3.370	-8.35	-9.45	28.53
CV-24039	7/7/2026 2:04:59 PM	177.5	177.5	-5.05	-5.07			5.127	5.157	-8.75	-8.88	28.53
CV-24039	7/14/2026 1:04:46 PM	191.1	191.2	-6.43	-6.36			6.639	6.676	-8.65	-8.55	28.59
CV-24039	7/14/2026 1:09:42 PM	186.0	186.3	-6.99	-6.99			7.111	7.093	-8.65	-8.63	28.56
CV-24039	7/14/2026 1:10:00 PM											
CV-24039	7/21/2026 10:31:01 AM	189.4	189.6	-4.82	-4.90			4.813	4.856	-6.57	-6.15	28.64

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24039	7/28/2026 10:01:04 AM	182.2	182.9	-7.24	-7.08			7.879	7.601	-9.06	-9.01	28.51
CV-24040	7/2/2026 2:03:23 PM	161.7	162.0	-1.79	-1.81			1.745	1.752	-11.21	-11.38	28.58
CV-24040	7/7/2026 2:10:03 PM	165.3	165.3	1.38	-3.65			0.000	3.664	-6.99	-5.97	28.53
CV-24040	7/7/2026 2:11:41 PM	165.6	165.3	-2.80	-2.81			2.828	2.803	-6.11	-6.02	28.54
CV-24040	7/7/2026 2:15:00 PM											
CV-24040	7/7/2026 2:15:00 PM											
CV-24040	7/13/2026 10:32:47 AM	168.9	169.5	-8.77	-5.23			9.286	5.685	-11.55	-11.98	28.6
CV-24040	7/13/2026 10:34:01 AM	168.4	168.6	-4.86	-4.42			4.823	5.007	-10.60	-12.04	28.6
CV-24040	7/13/2026 10:40:00 AM											
CV-24040	7/21/2026 10:28:33 AM	170.3	170.5	-1.52	-1.51			1.510	1.519	-8.40	-7.92	28.63
CV-24040	7/28/2026 10:07:52 AM	161.8	161.7	-3.57	-3.50			3.513	3.459	-10.34	-10.72	28.53
CV-24041	7/2/2026 2:06:37 PM	90.4	90.5	-11.74	-11.74			11.676	11.603	-11.32	-11.42	28.58
CV-24041	7/21/2026 8:16:04 AM	83.3	83.5	-10.44	-10.44			10.394	10.394	-10.42	-10.42	28.62
CV-24042	7/6/2026 10:39:05 AM	183.4		-7.02				7.270		-4.02		28.54
CV-24042	7/6/2026 10:40:03 AM	185.5	182.1	-8.03	-7.78			8.316	8.075	-4.21	-4.11	28.53
CV-24042	7/6/2026 10:55:00 AM											
CV-24042	7/6/2026 10:55:00 AM											
CV-24042	7/13/2026 10:25:00 AM											
CV-24042	7/13/2026 10:25:01 AM	178.9	178.2	-10.90	-10.78			11.486	11.410	-11.90	-12.00	28.6
CV-24042	7/20/2026 9:58:34 AM	177.5	177.6	-9.32	-9.44			9.862	9.887	-9.94	-10.32	28.59
CV-24042	7/20/2026 10:10:00 AM											
CV-24042	7/27/2026 10:43:38 AM	180.4	179.8	-8.84	-8.85			9.515	9.488	-9.18	-9.28	28.54
CV-24043	7/10/2026 10:12:45 AM	114.0	113.9	-5.39	-5.39			5.256	5.260	0.62	0.62	28.55
CV-24043	7/16/2026 2:32:38 PM	120.7	121.1	-5.72	-5.72			5.665	5.718	0.06	0.04	28.5
CV-24044	7/1/2026 2:08:53 PM	137.8	139.0	-3.23	-1.98			3.233	1.971	-12.10	-12.15	28.56
CV-24044	7/22/2026 1:39:48 PM	151.2	150.3	-2.12	-2.15			2.139	2.157	-10.48	-10.73	28.62

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24044	7/30/2026 9:59:51 AM	157.8	158.6	-1.12	-1.15			1.112	1.139	-9.20	-9.22	28.56
CV-24045	7/7/2026 1:38:11 PM	164.7	164.9	-2.91	-2.74			2.937	2.744	-7.03	-7.24	28.56
CV-24045	7/7/2026 1:40:00 PM											
CV-24045	7/7/2026 1:40:00 PM											
CV-24045	7/14/2026 10:17:58 AM	164.6	163.2	-4.69	-4.69			4.644	4.644	-8.42	-8.42	28.62
CV-24045	7/14/2026 10:20:00 AM											
CV-24045	7/21/2026 10:14:16 AM	177.3	177.0	-3.90	-3.91			3.890	3.905	-7.57	-7.89	28.68
CV-24045	7/28/2026 9:44:32 AM	142.4	145.2	-8.61	-3.25			9.212	3.233	-9.51	-9.07	28.53
CV-24045	7/28/2026 9:46:42 AM	147.9	148.0	-0.97	-0.96			0.952	0.947	-8.92	-8.97	28.53
CV-24046	7/7/2026 1:54:14 PM	187.2	186.4	-1.82	-1.61			1.781	1.602	-7.09	-4.99	28.53
CV-24046	7/7/2026 1:55:00 PM											
CV-24046	7/7/2026 1:55:00 PM											
CV-24046	7/7/2026 1:56:03 PM	186.1	187.1	-1.86	-1.53			1.868	1.501	-4.98	-2.74	28.53
CV-24046	7/14/2026 1:13:28 PM	134.6	135.0	-2.88	-1.19			3.058	1.195	-6.65	-6.39	28.57
CV-24046	7/14/2026 1:14:02 PM	135.3	135.4	-1.48	-1.54			1.492	1.504	-6.30	-7.66	28.59
CV-24046	7/21/2026 10:33:20 AM	148.2	149.0	-1.43	-1.38			1.503	1.380	-4.45	-6.69	28.64
CV-24046	7/28/2026 10:18:26 AM	186.5	186.4	-3.18	-3.21			3.151	3.190	-7.51	-8.42	28.52
CV-24048	7/2/2026 2:12:30 PM	89.6	89.8	-9.72	-9.72			9.684	9.679	-11.43	-11.44	28.58
CV-24048	7/21/2026 8:18:43 AM	81.4	81.5	-8.51	-8.47			8.481	8.438	-10.26	-10.16	28.62
CV-24049	7/6/2026 1:38:16 PM	185.1	185.3	-10.56	-10.60			10.607	10.632	-11.65	-11.67	28.52
CV-24049	7/6/2026 4:50:00 PM											
CV-24049	7/6/2026 4:50:00 PM											
CV-24049	7/13/2026 9:10:00 AM											
CV-24049	7/13/2026 9:10:00 AM											
CV-24049	7/13/2026 1:14:21 PM	190.5	190.6	-8.90	-8.09			9.325	8.444	-10.12	-9.64	28.57
CV-24049	7/13/2026 1:20:00 PM											
CV-24049	7/20/2026 10:13:54 AM	187.5	187.4	-9.48	-8.26			10.014	8.707	-10.32	-9.43	28.57
CV-24049	7/20/2026 10:30:00 AM											

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24049	7/27/2026 1:26:59 PM	192.8	192.9	-5.39	-5.04			5.723	5.457	-7.22	-7.10	28.53
CV-24049	7/27/2026 1:30:09 PM	164.9	165.1	-7.96	-7.79			8.395	8.195	-8.40	-7.71	28.53
CV-24050	7/7/2026 9:56:00 AM	112.7	112.7	-2.59	-2.61			2.554	2.570	-7.93	-8.20	28.59
CV-24050	7/16/2026 2:26:11 PM	121.0	116.4	-9.71	-10.10			9.700	10.140	-9.78	-10.08	28.52
CV-24051	7/8/2026 10:40:27 AM	112.9	112.5	-9.80	-2.94			10.255	2.903	-11.18	-11.51	28.59
CV-24051	7/8/2026 10:41:15 AM	112.5	112.4	-3.82	-3.81			3.769	3.769	-11.38	-11.57	28.58
CV-24051	7/22/2026 1:46:52 PM	113.4	112.9	-2.85	-2.86			2.816	2.856	-10.87	-10.86	28.62
CV-24052	7/2/2026 2:24:37 PM	85.9	86.2	-8.71	-8.74			8.782	8.788	-8.40	-8.52	28.58
CV-24052	7/21/2026 1:52:36 PM	121.7	107.0	-3.13	-1.88			3.125	1.877	-5.93	-6.78	28.64
CV-24053	7/2/2026 2:21:41 PM	96.7	97.4	-5.68	-5.35			5.633	5.287	-8.51	-8.71	28.58
CV-24053	7/10/2026 10:33:54 AM	102.7	102.7	-5.19	-4.55			5.144	4.526	-8.36	-8.28	28.51
CV-24053	7/13/2026 7:15:00 AM											
CV-24053	7/13/2026 7:15:00 AM											
CV-24053	7/21/2026 1:39:10 PM	105.0	105.4	-8.22	-8.33			8.224	8.346	-8.11	-8.47	28.62
CV-24054	7/6/2026 1:41:08 PM	165.2	165.6	-9.31	-9.35			9.488	9.560	-12.32	-12.29	28.51
CV-24054	7/6/2026 2:00:00 PM											
CV-24054	7/6/2026 2:00:00 PM											
CV-24054	7/13/2026 1:16:50 PM	172.4	172.2	-6.74	-6.74			7.093	7.091	-10.50	-10.45	28.54
CV-24054	7/13/2026 1:25:00 PM											
CV-24054	7/20/2026 10:09:45 AM	172.7	172.8	-10.57	-10.11			11.111	10.656	-11.31	-10.77	28.57
CV-24054	7/20/2026 10:10:46 AM	173.1	173.6	-10.49	-10.78			11.102	11.241	-11.12	-11.21	28.57
CV-24054	7/20/2026 10:25:00 AM											
CV-24055	7/9/2026 3:17:18 PM	134.4	134.0	-0.64	-0.61	0.0	0.0	0.589	0.564	-12.38		28.38
CV-24055	7/9/2026 3:18:58 PM	134.0	134.1	-0.66	-0.66	0.0	0.0	0.608	0.606	-12.50		28.38
CV-24055	7/23/2026 9:27:41 AM	141.2	141.3	-0.89	-0.80			0.896	0.846	-11.36	-10.25	28.51
CV-24056	7/3/2026 7:21:57 AM	101.3	101.9	-0.98	-0.72			0.963	0.703	-9.26	-9.75	28.6
CV-24056	7/20/2026 10:21:42 AM	117.2	117.0	-0.61	-0.61			0.612	0.604	-8.66	-8.43	28.63

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24057	7/1/2026 9:08:14 AM	141.9	141.7	-4.21	-2.83	31.2	14.4	2.776	0.584	-12.08	-12.24	28.56
CV-24057	7/1/2026 9:09:49 AM	142.8	143.0	-2.27	-2.26	16.9	18.1	0.807	0.931	-12.14	-12.13	28.57
CV-24057	7/16/2026 2:15:14 PM	143.9	143.7	-1.19	-1.16	16.1	15.6	0.738	0.688	-10.14	-9.59	28.49
CV-24058	7/7/2026 9:36:58 AM	107.9	108.7	-4.77	-4.72			4.971	4.658	-6.86	-6.84	28.58
CV-24058	7/16/2026 2:42:08 PM	112.5	112.5	-5.72	-5.72			5.752	5.693	-7.27	-7.30	28.49
CV-24059	7/2/2026 10:50:00 AM											
CV-24059	7/2/2026 10:56:24 AM	158.4	158.1	-3.49	-3.32	2.5	7.6	0.018	0.168	-10.37	-10.59	28.6
CV-24059	7/8/2026 1:16:56 PM	159.7	159.7	-2.94	-2.91	9.2	9.4	0.249	0.257	-12.12	-12.13	28.54
CV-24059	7/8/2026 1:20:00 PM											
CV-24059	7/8/2026 1:20:00 PM											
CV-24059	7/16/2026 2:16:47 PM	122.0	122.0	-2.35	-2.33	5.6	5.9	0.086	0.097	-11.45	-11.45	28.45
CV-24059	7/16/2026 2:54:28 PM	161.1	160.4	-5.90	-4.93	10.0	8.8	0.297	0.226	-10.80	-10.40	28.5
CV-24059	7/22/2026 2:25:32 PM	158.8	158.9	-4.87	-4.93	8.4	12.0	0.206	0.423	-11.77	-11.58	28.56
CV-24059	7/30/2026 9:45:59 AM	158.7	158.7	-6.74	-6.74	4.0	2.7	0.046	0.022	-13.81	-13.81	28.57
CV-24060	7/6/2026 3:24:50 PM	105.8	104.7	-2.12	-1.15	40.9	27.0	2.101	0.925			28.47
CV-24060	7/17/2026 7:49:21 AM	90.7	82.8	-2.13	-1.12			2.134	1.123	-11.55	-12.22	28.54
CV-24061	7/8/2026 2:27:26 PM	134.7	134.7	-0.95	-0.94	0.0	0.0	0.961	0.959	-11.29		28.64
CV-24061	7/8/2026 2:28:35 PM	134.5	134.7	-0.89	-0.88	0.0	0.0	0.876	0.870	-11.33		28.64
CV-24061	7/29/2026 9:43:44 AM	122.0	122.1	-4.68	-4.69			4.687	4.702	-9.98	-10.31	28.48
CV-24062	7/6/2026 8:20:00 AM											
CV-24062	7/6/2026 8:20:00 AM											
CV-24062	7/8/2026 2:06:55 PM	180.0	179.3	1.42	-5.21			0.000	5.058	-1.14	-0.88	28.53
CV-24062	7/8/2026 2:08:53 PM	179.4	180.0	-6.37	-6.34			6.599	6.603	-11.24	-11.07	28.53
CV-24062	7/8/2026 2:10:00 PM											
CV-24062	7/8/2026 2:10:00 PM											
CV-24062	7/14/2026 1:31:33 PM	181.4	180.9	-4.58	-4.55			4.526	4.493	-8.40	-8.46	28.56
CV-24062	7/14/2026 1:40:00 PM											
CV-24062	7/21/2026 1:00:32 PM	181.2	181.1	-6.36	-6.36			6.410	6.422	-8.08	-8.17	28.6
CV-24062	7/29/2026 12:56:17 PM	177.2	176.6	-6.82	-7.08			7.073	7.306	-8.35	-8.93	28.46
CV-24063	7/6/2026 8:15:00 AM											

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24063	7/6/2026 8:15:00 AM											
CV-24063	7/8/2026 2:23:32 PM	185.2	185.2	-9.44	-9.56			9.664	9.751	-10.86	-10.95	28.53
CV-24063	7/8/2026 2:30:00 PM											
CV-24063	7/8/2026 2:30:00 PM											
CV-24063	7/14/2026 1:24:44 PM	184.8	184.6	-7.05	-6.87			7.227	7.007	-8.12	-7.68	28.53
CV-24063	7/14/2026 1:30:00 PM											
CV-24063	7/21/2026 12:54:42 PM	183.9	184.0	-5.63	-5.69			5.657	5.669	-6.40	-6.40	28.59
CV-24063	7/29/2026 1:02:30 PM	181.3	181.6	-7.08	-6.78			7.504	7.184	-8.20	-7.41	28.46
CV-24064-PL	7/6/2026 8:10:00 AM											
CV-24064-PL	7/6/2026 8:10:00 AM											
CV-24064-PL	7/6/2026 2:33:01 PM	190.6	190.6	-13.35	-12.47			13.800	12.816	-13.57	-13.56	28.53
CV-24064-PL	7/6/2026 2:50:00 PM											
CV-24064-PL	7/6/2026 2:50:00 PM											
CV-24064-PL	7/15/2026 1:24:20 PM	190.6	190.5	-11.21	-11.23			11.335	11.352	-11.66	-11.64	28.45
CV-24064-PL	7/15/2026 1:25:00 PM											
CV-24064-PL	7/28/2026 1:23:22 PM	191.1	191.2	-9.35	-10.34			9.524	10.463	-13.43	-13.54	28.49
V-24065-TP1	7/6/2026 9:55:14 AM	101.7	101.7	-0.53	-0.53			0.527	0.527	-12.25	-12.25	28.55
V-24065-TP1	7/13/2026 8:45:00 AM											
V-24065-TP1	7/13/2026 8:45:00 AM											
V-24065-TP1	7/20/2026 9:11:35 AM	122.8	123.3	-8.02	-7.96	87.0	92.2	7.572	8.510			28.55
CV-24066	7/3/2026 7:16:42 AM	95.1	96.3	-1.86	-1.85			1.854	1.847	-12.53	-11.75	28.62
CV-24066	7/13/2026 9:20:00 AM											
CV-24066	7/13/2026 9:20:00 AM											
CV-24066	7/30/2026 12:31:20 PM	108.3	108.4	-1.84	-1.84			1.920	1.921	-11.78	-11.72	28.63
CV-24067	7/1/2026 8:55:09 AM	149.9	149.7	-7.36	-7.75			0.000	0.000	-10.47	-11.79	28.56
CV-24067	7/1/2026 9:00:00 AM											
CV-24067	7/3/2026 7:13:48 AM	134.8	129.4	-9.73	-3.80			0.010	0.163	-11.09	-11.02	28.61
CV-24067	7/3/2026 7:14:32 AM	129.3	129.2	-3.62	-3.61			0.178	0.163	-10.60	-11.24	28.6
CV-24067	7/20/2026 9:54:51 AM	156.4	156.4	-0.52	-0.53			0.018	0.014	-7.78	-7.70	28.62
CV-24067	7/22/2026 8:59:39 AM	155.0	160.5	-0.02	-3.56			0.000	0.078	-7.03	-6.79	28.68
CV-24067	7/22/2026 9:00:05 AM	162.4	162.7	-3.57	-3.65			0.294	0.317	-7.20	-6.74	28.65
CV-24067	7/29/2026 8:12:32 AM	157.0	157.2	-3.63	-3.52			0.000	0.000	-9.40	-9.01	28.53
CV-24068	7/7/2026 9:20:23 AM	120.0	121.5	-8.96	-8.98			9.041	9.005	-10.09	-10.18	28.56
CV-24068	7/20/2026 9:57:51 AM	114.5	114.6	-1.73	-1.73			1.714	1.718	-10.81	-11.16	28.62
CV-24069	7/6/2026 8:30:00 AM											
CV-24069	7/6/2026 8:30:00 AM											

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24069	7/8/2026 10:32:20 AM	126.8	127.0	-1.36	-1.35			1.351	1.341	-10.38	-10.38	28.59
CV-24069	7/16/2026 2:59:51 PM	120.0	120.1	-2.08	-2.20			1.986	2.022	-10.64	-10.12	28.48
CV-24070	7/6/2026 8:35:00 AM											
CV-24070	7/6/2026 8:35:00 AM											
CV-24070	7/6/2026 3:45:09 PM	147.9	147.9	-0.21	-0.22	27.7	27.5	6.736	6.662	-11.50		28.47
CV-24070	7/6/2026 3:46:17 PM	147.9	147.9	-0.31	-0.30	27.6	27.6	6.772	6.772	-11.32		28.47
CV-24070	7/13/2026 2:59:42 PM	150.0	150.8	0.89	-2.66	14.2	14.3	4.509	4.654	-8.36	-7.42	28.58
CV-24070	7/13/2026 3:00:00 PM											
CV-24070	7/13/2026 3:00:43 PM	151.1		-3.02		26.0		4.609		-8.34		28.59
CV-24070	7/16/2026 3:03:30 PM	148.4	148.5	-6.03	-5.39	15.2	14.0	5.264	4.456	-10.82	-11.24	28.48
CV-24070	7/30/2026 9:51:32 AM	146.3	146.2	-6.40	-6.40	26.8	26.7	4.917	4.882	-14.11	-14.36	28.57
CV-24071	7/6/2026 3:18:36 PM	131.8	131.4	-3.83	-2.20	8.3	5.7	1.711	0.785	-11.40		28.47
CV-24071	7/6/2026 3:19:46 PM	131.3	131.3	-2.09	-2.09	5.6	5.6	0.774	0.778	-11.41		28.47
CV-24071	7/8/2026 8:25:00 AM											
CV-24071	7/8/2026 8:25:00 AM											
CV-24071	7/17/2026 7:53:19 AM	132.9	132.4	-3.03	-2.07	10.5	8.9	0.719	0.518	-10.58	-11.51	28.55
CV-24071	7/17/2026 7:54:08 AM	132.2	132.3	-1.89	-1.88	8.6	8.6	0.480	0.486	-11.58	-11.61	28.55
CV-24072	7/6/2026 1:06:35 PM	117.3	116.9	-3.69	-2.16	59.0	42.9	3.674	1.958			28.47
CV-24072	7/17/2026 8:54:50 AM	119.7	119.8	-0.37	-0.32			0.340	0.310	-11.44	-12.01	28.55
V-24073-TP1	7/2/2026 3:17:49 PM	152.8	153.2	-2.80	-1.14	0.0	0.0	2.815	1.094	-9.70		28.48
V-24073-TP1	7/2/2026 3:20:38 PM	153.8	153.8	-1.10	-1.13	0.0	0.0	1.363	1.364	-9.82		28.48
V-24073-TP1	7/8/2026 2:14:44 PM	155.0	155.7	-2.59	-2.53			2.518	2.548	-10.68	-10.61	28.53
V-24073-TP1	7/8/2026 2:20:00 PM											
V-24073-TP1	7/16/2026 10:10:00 AM											
V-24073-TP1	7/16/2026 10:10:07 AM	158.2	158.3	-1.54	-5.47			1.524	5.894	-8.96	-9.21	28.45
V-24073-TP1	7/16/2026 10:10:25 AM	158.5	158.5	-5.52	-5.35			5.787	5.732	-8.17	-8.84	28.46
V-24073-TP1	7/21/2026 1:03:11 PM	156.9	157.1	-4.15	-4.17			4.141	4.142	-7.77	-7.75	28.59
V-24073-TP1	7/29/2026 1:08:41 PM	154.4	154.7	-4.75	-4.94			5.077	4.993	-7.65	-7.47	28.46
CV-24074	7/2/2026 3:13:30 PM	126.2	128.9	-5.61	-1.75	0.0	0.0	5.446	1.840	-9.57		28.48
CV-24074	7/22/2026 2:20:45 PM	123.7	106.1	-5.54	-3.28			5.536	3.222	-9.68	-9.43	28.58

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
V-24075-TP1	7/2/2026 9:39:29 AM	185.6	185.7	-15.39	-15.41			15.595	15.638	0.34	0.34	28.58
V-24075-TP1	7/6/2026 3:01:23 PM	185.0	185.1	-12.25	-4.09			12.703	4.084	-13.06	-13.05	28.51
V-24075-TP1	7/6/2026 3:02:24 PM	185.2	185.3	-4.54	-4.54			4.557	4.535	-13.20	-13.08	28.51
V-24075-TP1	7/6/2026 3:05:00 PM											
V-24075-TP1	7/6/2026 3:05:00 PM											
V-24075-TP1	7/15/2026 1:29:30 PM	188.6	188.6	4.36	-2.71			0.000	2.684	-11.30	-11.01	28.44
V-24075-TP1	7/15/2026 1:30:02 PM	188.7	188.7	-2.91	-2.95			2.960	2.955	-11.15	-11.03	28.45
V-24075-TP1	7/15/2026 1:35:00 PM											
V-24075-TP1	7/28/2026 1:27:30 PM	187.0	187.0	-6.67	-6.53			6.682	6.676	-13.07	-12.78	28.49
CV-24076	7/6/2026 2:07:53 PM	172.5	172.3	-5.42	-5.42			5.722	5.722	-8.13	-8.13	28.5
CV-24076	7/6/2026 2:10:00 PM											
CV-24076	7/6/2026 2:10:00 PM											
CV-24076	7/13/2026 1:23:31 PM	173.3	173.5	-4.72	-4.76			5.129	5.152	-8.46	-8.57	28.53
CV-24076	7/13/2026 1:35:00 PM											
CV-24076	7/20/2026 2:30:00 PM											
CV-24076	7/20/2026 2:31:50 PM	174.3	174.5	-4.80	-4.77			4.767	4.743	-8.36	-8.29	28.49
CV-24076	7/27/2026 1:40:02 PM	169.4	169.6	-4.03	-4.17			3.887	4.065	-7.54	-7.66	28.5
CV-24077	7/1/2026 8:48:35 AM	150.5	150.7	-4.91	-4.96			4.895	4.966	-12.41	-12.48	28.55
CV-24077	7/1/2026 8:50:00 AM											
CV-24077	7/8/2026 8:28:44 AM	150.6	150.6	-5.39	-5.39			5.663	5.660	-11.05	-11.71	28.61
CV-24077	7/8/2026 8:30:00 AM											
CV-24077	7/8/2026 8:30:00 AM											
CV-24077	7/15/2026 8:09:17 AM	150.6	150.6	-4.91	-5.03			5.140	5.179	-11.22	-11.35	28.54
CV-24077	7/15/2026 8:10:00 AM											
CV-24077	7/20/2026 9:49:45 AM	151.2	152.0	-5.81	-2.02			5.695	2.023	-10.46	-10.64	28.62
CV-24077	7/22/2026 8:54:23 AM	159.4	159.2	-0.35	-1.89			0.368	1.881	-11.34	-10.83	28.64
CV-24077	7/22/2026 8:54:59 AM	159.1	158.9	-2.28	-2.29			2.291	2.335	-10.96	-10.82	28.65
CV-24077	7/29/2026 8:07:00 AM	152.4	152.4	-3.92	-3.81			3.920	3.815	-13.85	-13.60	28.52
CV-24078	7/3/2026 7:09:44 AM	100.0	99.6	-1.66	-1.52	8.2	7.0	0.176	0.128	-8.79	-9.13	28.6
CV-24078	7/20/2026 9:52:27 AM	102.8	102.8	-1.03	-1.03	1.1	2.2	0.003	0.013	-8.35	-9.27	28.62

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24079-TP3	7/7/2026 9:15:40 AM	146.8	144.6	-3.33	-3.12			3.295	3.085	-8.09	-7.84	28.57
CV-24079-TP3	7/7/2026 9:16:34 AM	144.7	143.6	-2.57	-2.50			2.552	2.479	-7.69	-7.81	28.56
CV-24079-TP3	7/13/2026 7:31:55 AM	121.3	102.5	-3.01	-1.24			3.037	1.235	-11.82	-12.70	28.57
CV-24079-TP3	7/13/2026 7:42:05 AM	100.1	94.4	-1.45	-1.44			1.451	1.449	-12.68	-13.60	28.6
CV-24079-TP3	7/29/2026 9:09:16 AM	86.9	88.1	-0.58	-0.54			0.569	0.536	-11.00	-12.00	28.5
CV-24079-TP3	7/29/2026 9:15:45 AM	91.6	92.7	-0.72	-0.71			0.712	0.698	-11.05	-10.91	28.49
CV-24080	7/7/2026 9:11:34 AM	124.5	124.6	-2.22	-2.11	6.8	6.1	0.127	0.102	-10.64	-10.64	28.56
CV-24080	7/29/2026 9:05:55 AM	123.4	122.7	-2.52	-2.42	8.0	6.7	0.178	0.124	-13.27	-12.30	28.49
V-24081-TP1	7/6/2026 3:54:09 PM	115.7	115.1	-3.99	-3.69	0.0	0.0	3.975	3.634	-11.53		28.46
V-24081-TP1	7/16/2026 3:11:01 PM	117.4	117.1	-1.04	-1.08			1.032	1.124	-6.87	-6.66	28.47
CV-24082	7/6/2026 3:07:02 PM	125.3	125.3	-9.24	-8.14	94.6	90.5	8.790	8.034			28.46
CV-24082	7/17/2026 8:13:54 AM	127.6	127.2	-8.46	-6.72			8.629	6.873	-11.24	-11.00	28.55
CV-24083	7/2/2026 1:14:35 PM	154.4	153.8	1.03	1.03			0.000	0.000	-6.05	-6.06	28.57
CV-24083	7/2/2026 1:15:00 PM											
CV-24083	7/6/2026 3:15:00 PM											
CV-24083	7/6/2026 3:15:00 PM											
CV-24083	7/6/2026 3:17:19 PM	152.6	154.3	1.21	-2.86			0.000	2.916	0.44	0.52	28.53
CV-24083	7/6/2026 3:18:50 PM	155.3	155.6	-3.62	-3.74			3.654	3.755	-10.44	-10.34	28.53
CV-24083	7/6/2026 3:19:25 PM	155.7	155.7	-3.74	-3.74			3.774	3.771	-9.22	-9.53	28.53
CV-24083	7/16/2026 10:27:18 AM	162.0	161.9	-3.85	-3.87			3.833	3.846	-8.19	-8.93	28.46
CV-24083	7/16/2026 10:30:00 AM											
CV-24083	7/17/2026 8:09:38 AM	155.0	150.6	-5.12	-0.42			5.363	0.420	-10.26	-10.31	28.55

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24083	7/21/2026 1:36:33 PM	158.8	163.3	1.61	-1.94			0.000	1.946	-5.04	-5.59	28.6
CV-24083	7/21/2026 1:37:02 PM	162.8	162.7	-1.89	-2.10			1.849	2.078	-4.74	-6.04	28.6
CV-24083	7/30/2026 10:16:56 AM	156.3	156.4	-4.62	-4.68			4.594	4.635	-5.78	-5.76	28.53
V-24084-TP1	7/8/2026 1:30:00 PM											
V-24084-TP1	7/8/2026 1:30:00 PM											
V-24084-TP1	7/8/2026 1:30:26 PM	183.4	183.7	-7.16	-8.02			7.246	8.111	-10.79	-10.82	28.53
V-24084-TP1	7/16/2026 10:24:02 AM	183.7	183.9	-5.16	-5.52			5.619	6.077	-8.69	-8.80	28.46
V-24084-TP1	7/16/2026 10:25:00 AM											
V-24084-TP1	7/21/2026 1:27:39 PM	184.6	184.4	-5.59	-6.02			5.533	6.050	-8.73	-8.67	28.59
V-24084-TP1	7/29/2026 1:25:41 PM	184.4	184.6	-8.46	-8.13			8.704	8.381	-12.02	-11.87	28.46
CV-24085	7/7/2026 12:01:16 PM	130.7	130.7	-0.72	-0.72	15.3	15.3	0.675	0.674	-11.44		28.5
CV-24085	7/16/2026 9:52:28 AM	131.3	131.4	-0.73	-0.70	17.0	17.4	0.824	0.859	-11.95		28.42
CV-24085	7/16/2026 9:54:37 AM	131.4	131.4	-0.71	-0.71	17.0	17.0	0.829	0.831	-11.18		28.42
CV-24086	7/7/2026 8:58:12 AM	120.3	120.3	-0.71	-0.72	6.8	5.8	0.124	0.092	-9.08	-12.71	28.55
CV-24086	7/16/2026 1:59:18 PM	121.5	121.7	-0.22	-0.21	4.3	3.4	0.051	0.032	-9.52	-11.02	28.47
CV-24087	7/2/2026 2:17:41 PM	119.2	118.9	-2.09	-1.64	43.8	31.3	5.283	2.683	-8.94	-8.62	28.57
CV-24087	7/2/2026 2:19:33 PM	118.7	118.7	-1.66	-1.67	31.4	32.5	2.699	2.892	-8.61	-9.17	28.56
CV-24087	7/13/2026 7:57:48 AM	119.6	117.6	-2.07	-0.87	39.0	16.0	4.171	0.692	-12.89	-9.52	28.57
CV-24087	7/19/2026 1:06:40 PM	119.4	119.5	-0.19	-0.17	12.7	13.6	0.440	0.505	-9.26	-9.64	28.56
CV-24087	7/19/2026 1:07:48 PM	119.7	119.7	-0.24	-0.24	15.2	15.2	0.630	0.628	-10.13	-10.18	28.56
CV-24088	7/6/2026 12:48:09 PM	120.4	120.2	-5.86	-5.56	0.0	0.0	5.688	5.349	-9.42		28.46
CV-24088	7/17/2026 8:32:34 AM	123.6	124.4	-4.38	-3.97			4.370	3.973	-10.83	-10.37	28.55
CV-24089	7/13/2026 11:29:35 AM	98.7	99.0	-13.13	-13.09	6.6	5.0	0.119	0.068	-12.82	-12.82	28.59
CV-24089	7/17/2026 8:41:49 AM	144.3	144.5	-8.11	-7.51	7.6	8.3	0.165	0.199	-10.47	-10.37	28.58
CV-24090	7/7/2026 12:20:30 PM	117.1	116.7	-1.20	-0.96	0.0	0.0	0.979	0.877	-13.03		28.48
CV-24090	7/28/2026 8:57:02 AM	119.9	120.0	-0.94	-0.95			0.930	0.925	-12.54	-12.60	28.46
CV-24091	7/2/2026 1:55:15 PM	98.8	101.3	-1.26	-2.27	2.1	3.3	0.012	0.029	-12.70	-12.77	28.56

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24091	7/2/2026 1:58:33 PM	104.9	105.2	-2.50	-2.50	3.3	3.3	0.029	0.029	-12.70	-12.74	28.57
CV-24091	7/6/2026 10:46:17 AM	93.9	94.0	-11.38	-11.33	2.8	2.9	0.023	0.024	-11.50		28.35
CV-24091	7/6/2026 10:48:07 AM	94.1	94.1	-11.33	-11.34	2.2	2.2	0.013	0.014	-11.49		28.35
CV-24091	7/22/2026 9:43:27 AM	89.8	88.7	-11.85	-11.69	2.2	1.3	0.012	0.005	-11.56	-11.49	28.62
CV-24092	7/7/2026 2:35:45 PM	117.5	117.6	-4.06	-3.86			-2.819	-2.324			28.44
CV-24093	7/1/2026 11:46:07 AM	114.2	114.2	-1.72	-1.70	11.0	10.8	0.767	0.737	-18.59	-18.74	28.53
CV-24093	7/1/2026 11:49:48 AM	114.2	114.6	-1.69	-1.74	11.2	11.5	0.797	0.846	-18.67	-18.69	28.53
CV-24093	7/1/2026 11:50:23 AM	114.8	114.9	-1.68	-1.68	11.3	11.4	0.814	0.824	-18.69	-18.62	28.53
CV-24093	7/16/2026 2:34:31 PM	121.4	121.3	-0.53	-0.53	10.7	10.9	0.742	0.764	-16.03	-16.03	28.42
CV-24093	7/16/2026 2:37:29 PM	121.4	121.9	-0.63	-0.66	13.7	15.0	0.441	0.528	-15.97	-15.89	28.42
CV-24093	7/16/2026 2:39:05 PM	122.1	122.1	-0.68	-0.67	15.5	15.3	0.565	0.550	-15.87	-15.85	28.42
CV-24094	7/2/2026 1:06:27 PM	92.1	91.9	-3.48	-3.38	1.7	1.8	0.378	0.401	-14.59		28.52
CV-24094	7/2/2026 1:07:29 PM	91.5	91.5	-3.28	-3.26	1.9	1.9	0.436	0.470	-14.71		28.52
CV-24094	7/24/2026 10:59:08 AM	101.3	101.6	-7.05	-1.08	2.3	0.3	0.547	0.009	-11.60	-11.99	28.47
CV-24094	7/24/2026 11:02:10 AM	105.0	104.6	-1.18	-1.17	0.8	0.8	0.064	0.064	-12.77	-12.65	28.46
CV-24095	7/1/2026 1:48:38 PM	184.1	184.1	-4.94	-4.75			4.935	4.669	-7.18	-7.54	28.64
CV-24095	7/1/2026 1:56:00 PM											
CV-24095	7/2/2026 8:25:00 AM											
CV-24095	7/2/2026 8:25:00 AM											
CV-24095	7/8/2026 10:05:22 AM	182.1	182.2	-5.30	-5.88			5.825	6.398	-6.26	-6.75	28.71
CV-24095	7/8/2026 10:25:00 AM											
CV-24095	7/8/2026 10:25:00 AM											
CV-24095	7/15/2026 10:11:43 AM	182.7	182.7	-5.79	-4.77			6.404	5.322	-6.20	-6.97	28.6
CV-24095	7/15/2026 10:16:56 AM	182.1	182.5	-6.40	-6.74			6.766	7.256	0.55	0.51	28.62
CV-24095	7/15/2026 10:20:00 AM											
CV-24095	7/22/2026 2:01:45 PM	189.7	189.7	-0.51	-2.28			0.496	2.267	-5.29	-6.73	28.68
CV-24095	7/22/2026 2:02:24 PM	189.7	189.7	-2.15	-2.14			2.032	2.043	-6.65	-6.51	28.66
CV-24095	7/29/2026 9:17:33 AM	188.7	188.7	-3.49	-3.61			3.460	3.576	-7.58	-7.59	28.61

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24096	7/9/2026 8:45:58 AM	82.7	83.3	0.00	-0.01			0.003	0.006	0.00	0.00	28.67
CV-24096	7/9/2026 8:47:11 AM	83.6	83.7	0.00	0.00			0.004	0.000	0.03	0.00	28.67
CV-24096	7/20/2026 1:13:02 PM	106.1	106.1	-0.01	-0.02			0.000	0.000	0.34	0.34	28.69
CV-24097	7/8/2026 10:34:37 AM	97.0	97.2	-5.39	-4.85			6.074	4.812	-6.05	-5.97	28.71
CV-24097	7/8/2026 10:35:24 AM	97.4	97.4	-4.82	-4.86			4.787	4.832	-6.09	-5.60	28.71
CV-24097	7/20/2026 1:16:13 PM	112.7	112.8	-6.73	-6.73			6.760	6.727	-7.38	-7.39	28.66
CV-24098	7/3/2026 7:42:01 AM	69.3	70.1	-11.95	-9.88			11.742	9.775	-11.60	-9.70	28.7
CV-24098	7/30/2026 10:47:53 AM	93.4	93.5	-0.06	-0.05			0.000	0.000	-12.02	-11.82	28.71
CV-24098	7/30/2026 10:48:29 AM	94.0	94.4	-0.02	-0.02			0.000	0.000	-11.89	-10.84	28.71
CV-24099	7/3/2026 7:45:50 AM	70.5	72.1	-1.76	-0.69			1.760	0.686	-10.54	-11.31	28.69
CV-24099	7/20/2026 12:59:25 PM	108.2	108.2	-0.74	-0.73			0.737	0.727	-8.82	-7.91	28.67
CV-24100	7/1/2026 1:28:47 PM	149.9	151.4	-8.43	-8.47			8.791	8.850	-12.47	-12.63	28.64
CV-24100	7/1/2026 1:30:00 PM											
CV-24100	7/2/2026 8:05:00 AM											
CV-24100	7/2/2026 8:05:00 AM											
CV-24100	7/3/2026 8:08:58 AM	148.9	143.2	-9.06	-1.11			8.973	1.107	-12.57	-12.74	28.68
CV-24100	7/3/2026 8:10:35 AM	143.5	142.5	-1.22	-1.29			1.214	1.282	-10.95	-11.80	28.66
CV-24100	7/20/2026 12:53:13 PM	153.1	154.1	-0.55	-0.47			0.550	0.486	-9.09	-10.37	28.66
CV-24100	7/29/2026 9:35:55 AM	155.7	155.9	-1.01	-0.99			0.991	0.979	-13.51	-13.48	28.6
CV-24101	7/2/2026 8:00:00 AM											
CV-24101	7/2/2026 8:00:00 AM											
CV-24101	7/3/2026 8:15:20 AM	102.5	99.2	-12.42	-11.41			12.602	11.445	-12.40	-11.37	28.67
CV-24101	7/20/2026 10:36:02 AM	107.7	108.1	-11.96	-11.29	0.0	0.0			-10.56		28.69
CV-24102	7/3/2026 8:37:34 AM	95.7	96.1	-0.90	-0.80			0.903	0.797	-14.50	-14.69	28.66
CV-24102	7/28/2026 10:17:39 AM	105.1	105.2	-0.28	-0.28			0.257	0.253	-14.27	-13.08	28.56
CV-24103	7/1/2026 3:29:48 PM	92.9	92.9	-0.23	-0.23	1.5	1.5	0.046	0.045	-8.04		28.48
CV-24103	7/16/2026 9:38:27 AM	103.2	103.2	-0.70	-0.68	4.8	4.8	0.476	0.472	-15.70		28.55
CV-24104	7/1/2026 10:59:23 AM	92.2	92.2	-1.82	-1.78	3.5	3.4	1.366	1.301	-15.45		28.56
CV-24104	7/16/2026 2:10:22 PM	103.9	103.6	-1.23	-1.13	2.6	2.3	0.775	0.603	-13.18		28.4
CV-24105	7/1/2026 11:06:55 AM	110.3	110.3	-0.94	-0.95	9.2	8.0	0.667	0.397	-13.78		28.57
CV-24105	7/16/2026 2:27:11 PM	118.6	118.8	-0.59	-0.49	21.2	17.2	2.838	1.869	-14.24		28.39
CV-24106	7/7/2026 3:07:31 PM	128.3	128.4	-0.84	-0.83	4.4	9.0	0.054	0.221	-11.83		28.48
CV-24106	7/16/2026 3:02:43 PM	129.0	128.6	-1.07	-0.81	7.7	0.7	0.165	0.001	-16.35		28.4
CV-24107	7/6/2026 12:36:03 PM	114.9	115.6	-4.67	-4.36			4.622	4.303	-13.19	-13.35	28.55

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24108	7/6/2026 12:25:36 PM	129.4	129.4	-14.09	-13.82	15.0	14.0	0.151	0.132	-15.09	-14.88	28.53
CV-24109	7/6/2026 12:00:44 PM	104.1	104.9	-2.05	-2.05			2.034	2.042	-17.50	-18.08	28.51
CV-24110	7/7/2026 1:04:20 PM	130.1	135.8	0.19	-0.06	34.5	55.4	0.768	2.014	-13.39	-6.09	28.58
CV-24110	7/7/2026 1:05:17 PM	136.1	136.1	-0.14	-0.14	55.6	55.1	2.028	1.993	-13.19	-13.10	28.57
CV-24111	7/2/2026 11:09:11 AM	109.3	109.5	-1.90	-1.69	45.3	41.8	1.891	1.615			28.5
CV-24112	7/2/2026 11:13:05 AM	127.8	128.3	-1.01	-1.11	12.3	15.1	0.392	0.598	-16.49		28.5
CV-24114	7/8/2026 10:21:07 AM	123.3	123.3	-15.94	-15.98	20.8	25.5	1.231	1.847	-17.32	-17.74	28.68
CV-24116	7/1/2026 7:41:28 AM	124.0	124.0	-3.43	-3.41	0.0	0.0	3.486	3.473	-18.57		28.63
CV-24117	7/8/2026 10:03:59 AM	108.2	108.3	-1.67	-1.63			1.651	1.612	-18.27	-18.37	28.66
CV-24118	7/7/2026 1:25:13 PM	137.6	137.4	-4.03	-2.97			4.010	2.973	-7.22	-11.36	28.66
CV-24118	7/7/2026 1:25:56 PM	137.7	137.7	-3.21	-3.20			3.089	3.090	-12.47	-12.52	28.66
CV-24118	7/29/2026 9:13:45 AM											
CV-24118	7/29/2026 9:19:19 AM	153.4	154.0	1.91	-0.22			0.000	0.218	-18.33	-18.25	28.59
CV-24118	7/29/2026 9:21:46 AM	154.5	154.5	-0.88	-0.88			0.884	0.870	-17.99	-17.73	28.59
CV-24118	7/29/2026 9:25:00 AM											
CV-24118	7/29/2026 9:25:00 AM											
CV-24119	7/15/2026 10:31:25 AM	143.0	142.4	-1.54	-1.53			1.520	1.513	-15.84	-15.56	28.62
CV-24119	7/15/2026 10:32:21 AM	143.5	143.4	-1.54	-1.55			1.524	1.517	-15.72	-15.64	28.62
CV-24120	7/8/2026 1:58:27 PM	100.8	100.8	-7.10	-7.06			7.159	7.098	-6.65	-6.67	28.62
CV-24120	7/13/2026 10:05:00 AM											
CV-24120	7/13/2026 10:05:00 AM											
CV-24120	7/31/2026 9:43:24 AM	106.6	106.6	-0.02	-0.02			0.023	0.020	0.04	0.04	28.63
CV-24120	7/31/2026 10:24:29 AM	130.2	130.3	-12.32	-11.29			12.628	11.637	0.04	0.04	28.62

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24121	7/8/2026 1:56:01 PM	102.6	102.4	-7.12	-7.06			7.078	7.104	-6.94	-6.86	28.62
CV-24121	7/9/2026 7:50:00 AM											
CV-24121	7/9/2026 7:50:00 AM											
CV-24121	7/27/2026 1:27:57 PM	104.2	104.2	-6.13	-6.13			6.151	6.231	-5.99	-6.06	28.6
CV-24122	7/6/2026 9:28:47 AM	97.0	97.6	-0.04	-0.05	10.5	10.5	2.269	2.272	-7.71	-7.73	28.6
CV-24122	7/6/2026 9:40:00 AM	100.2	101.9	-8.02	-4.71	0.7	0.6	0.010	0.007	-10.00	-9.93	28.6
CV-24122	7/9/2026 7:55:00 AM											
CV-24122	7/9/2026 7:55:00 AM											
CV-24122	7/23/2026 2:13:49 PM	109.3	109.4	3.69	3.61	0.7	0.2	0.023	0.003	3.94	3.80	28.58
CV-24122	7/23/2026 2:14:07 PM	109.3	109.5	4.18	4.02	1.0	0.6	0.053	0.016	4.42	4.28	28.58
CV-24122	7/24/2026 9:45:00 AM											
CV-24123	7/8/2026 3:18:05 PM	116.7	117.2	-4.98	-4.69	0.0	0.0	0.011	0.008	-7.30		28.52
CV-24123	7/22/2026 10:18:09 AM	118.4	118.5	-3.03	-3.02	2.7	2.4	0.019	0.015	-4.90	-5.08	28.74
CV-24124	7/13/2026 9:07:33 AM	133.9	134.0	-0.39	-0.37			0.394	0.375	-6.13	-6.13	28.57
CV-24124	7/13/2026 9:07:55 AM	133.9	133.8	-0.34	-0.32			0.335	0.332	-6.18	-6.05	28.57
CV-24124	7/31/2026 9:35:59 AM	128.3	128.1	-2.26	-1.14			2.262	1.118	-5.94	-5.74	28.6
V-24125-TP2	7/13/2026 10:25:00 AM											
V-24125-TP2	7/13/2026 10:25:00 AM											
V-24125-TP2	7/13/2026 12:00:38 PM	119.8	121.2	-13.82	-13.53			13.830	13.594	-13.50	-13.62	28.62
V-24125-TP2	7/23/2026 2:22:19 PM	121.5	121.3	-5.98	-5.35			6.068	5.368	-5.76	-5.08	28.55
CV-24126	7/2/2026 10:44:12 AM	195.1	195.2	-3.76	-3.73			3.765	3.715	-5.17	-4.79	28.58
CV-24126	7/6/2026 1:33:35 PM	187.6	188.1	-6.17	-6.17			6.054	6.054	-6.65	-6.65	28.5
CV-24126	7/6/2026 1:40:00 PM											
CV-24126	7/6/2026 1:40:00 PM											
CV-24126	7/13/2026 1:44:32 PM	189.7	189.6	-5.43	-5.05			5.835	5.488	-5.57	-5.68	28.54
CV-24126	7/13/2026 1:45:00 PM											
CV-24126	7/13/2026 1:45:04 PM	189.9	190.0	-5.73	-5.40			6.050	5.746	-6.32	-6.06	28.53

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24126	7/20/2026 10:21:14 AM	189.6	189.4	-3.60	-3.22			3.644	3.809	-3.80	-4.04	28.58
CV-24126	7/20/2026 10:40:00 AM											
CV-24126	7/27/2026 1:12:06 PM	193.7	193.9	-0.24	-0.20			0.256	0.227	-3.33	-3.19	28.53
CV-24127	7/6/2026 1:30:07 PM	168.3	169.3	-5.54	-5.77			5.726	5.841	-6.26	-6.99	28.5
CV-24127	7/6/2026 1:35:00 PM											
CV-24127	7/6/2026 1:35:00 PM											
CV-24127	7/13/2026 1:04:22 PM	172.5	173.2	-5.10	-5.10			5.410	5.488	-6.19	-5.77	28.55
CV-24127	7/13/2026 1:10:00 PM											
CV-24127	7/20/2026 10:25:41 AM	171.9	172.0	-1.49	-1.48			1.276	1.324	-2.83	-3.03	28.58
CV-24127	7/20/2026 10:45:00 AM											
CV-24127	7/27/2026 1:06:12 PM	166.0	167.1	-2.42	-2.53			2.358	2.536	-4.82	-5.09	28.53
CV-24128	7/9/2026 7:35:00 AM											
CV-24128	7/9/2026 7:35:00 AM											
CV-24128	7/9/2026 8:21:11 AM	123.0	123.1	-0.73	-0.74			0.738	0.735	-11.45	-11.30	28.52
CV-24128	7/9/2026 3:03:21 PM	125.2	125.3	-0.88	-0.88	0.0	0.0	0.819	0.823	-12.92		28.42
CV-24128	7/23/2026 1:56:14 PM	123.7	123.8	-0.57	-0.52			0.581	0.495	-10.63	-10.56	28.54
CV-24129	7/9/2026 8:18:18 AM	125.7		-5.54				5.380		-11.49		28.52
CV-24129	7/23/2026 2:00:53 PM	128.0	128.2	-9.36	-8.77			9.468	8.832	-10.90	-10.73	28.54
CV-24130	7/9/2026 8:15:12 AM	125.1	124.5	-9.10	-8.06			9.152	7.926	-11.39	-11.06	28.55
CV-24130	7/23/2026 2:05:27 PM	129.0	128.7	-10.61	-9.87			10.682	9.919	-10.46	-10.11	28.55
CV-24131	7/8/2026 3:31:54 PM	122.6	122.6	-1.56	-1.00	16.4	10.8	0.767	0.328	-11.80		28.5
CV-24132	7/8/2026 3:36:10 PM	129.5	129.6	-7.44	-7.42	0.0	0.0	-0.051	-0.047	-11.69		28.53
CV-24133	7/22/2026 10:30:37 AM	124.8	124.9	-4.85	-4.92	15.7	15.7	0.679	0.685	-7.80	-7.83	28.66
V-24134-TP1	7/6/2026 1:27:42 PM	154.9	154.8	-3.04	-3.01			3.065	3.040	-4.37	-4.38	28.51
V-24134-TP1	7/6/2026 1:30:00 PM											
V-24134-TP1	7/6/2026 1:30:00 PM											
V-24134-TP1	7/13/2026 1:01:45 PM	149.3	148.9	-5.62	-5.48			6.009	5.923	-6.51	-6.32	28.59
V-24134-TP1	7/13/2026 1:05:00 PM											
V-24134-TP1	7/20/2026 10:29:58 AM	155.2	155.2	-2.61	-2.01			2.629	2.019	-3.37	-3.37	28.58
V-24134-TP1	7/20/2026 10:50:00 AM											
V-24134-TP1	7/27/2026 1:04:09 PM	153.4	154.1	-1.16	-1.18			1.195	1.194	-1.77	-1.92	28.53
CV-24135	7/6/2026 2:20:09 PM	144.0	143.4	-3.05	-3.05			3.040	3.026	-4.71	-4.70	28.58
CV-24135	7/27/2026 1:02:21 PM	121.8	121.8	-0.34	-0.33			0.334	0.363	-1.98	-1.98	28.58

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24135	7/27/2026 1:23:42 PM	127.0	127.0	-6.40	-6.59			5.985	6.566	-6.14	-6.48	28.59
CV-24136	7/7/2026 9:55:59 AM	133.8	133.2	-2.24	-2.00			2.222	1.970	-5.75	-5.89	28.62
CV-24137	7/6/2026 11:54:10 AM	99.7	100.6	-6.95	-6.71			6.990	6.671	-18.32	-18.47	28.52
CV-24138	7/2/2026 8:35:00 AM											
CV-24138	7/2/2026 8:35:00 AM											
CV-24138	7/9/2026 9:09:04 AM	103.1	102.8	-3.98	-4.28			3.947	4.265	-3.85	-4.19	28.67
CV-24138	7/9/2026 9:10:39 AM	102.0	101.6	-4.06	-4.38			4.022	4.301	-4.10	-4.27	28.67
CV-24138	7/30/2026 10:59:43 AM	120.0	120.0	-2.85	-2.62			2.541	2.462	-3.26	-2.58	28.71
CV-24138	7/30/2026 11:01:03 AM	119.4	119.2	-1.77	-1.52			1.760	1.572	-0.93	-0.53	28.72
CV-24139	7/1/2026 1:59:05 PM	158.3	158.7	-4.83	-5.45			5.109	5.717	-5.26	-6.32	28.63
CV-24139	7/1/2026 2:10:00 PM											
CV-24139	7/8/2026 9:55:00 AM											
CV-24139	7/8/2026 9:55:00 AM											
CV-24139	7/8/2026 9:55:13 AM	168.8	169.3	-5.03	-3.65			5.562	3.637	-5.34	-5.64	28.68
CV-24139	7/8/2026 9:56:32 AM	169.1	169.0	-3.75	-3.77			3.728	3.741	-5.88	-5.47	28.7
CV-24139	7/14/2026 7:15:00 AM											
CV-24139	7/14/2026 7:15:00 AM											
CV-24139	7/15/2026 9:45:13 AM	114.7	113.4	-5.22	-2.81			5.804	2.801	-6.42	-6.41	28.6
CV-24139	7/15/2026 9:46:47 AM	111.8	111.3	-2.63	-2.74			2.616	2.732	-6.10	-6.06	28.6
CV-24139	7/30/2026 11:03:32 AM	156.3	156.6	-5.58	-5.29			5.627	5.343	-5.50	-5.25	28.7
CV-24139	7/30/2026 11:04:14 AM	156.7	157.0	-5.67	-5.67			5.704	5.699	-5.50	-5.48	28.73
CV-24140	7/1/2026 8:50:00 AM											
CV-24140	7/1/2026 8:50:00 AM											
CV-24140	7/1/2026 2:08:43 PM	147.5	146.8	-3.82	-4.25			3.962	4.212	-4.00	-4.38	28.6
CV-24140	7/1/2026 2:17:00 PM											
CV-24140	7/8/2026 9:45:00 AM											
CV-24140	7/8/2026 9:45:00 AM											
CV-24140	7/8/2026 9:47:46 AM	147.2	147.9	-4.30	-3.70			4.325	3.689	-3.96	-4.31	28.68

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24140	7/8/2026 9:49:23 AM	148.2	148.3	-3.64	-3.80			3.622	3.805	-4.32	-4.06	28.68
CV-24140	7/15/2026 9:39:54 AM	161.2	161.4	-3.36	-3.34			3.383	3.379	-4.08	-3.87	28.6
CV-24140	7/15/2026 9:40:00 AM											
CV-24140	7/22/2026 11:04:15 AM	137.4	138.0	-2.59	-2.98			2.613	2.833	-2.19	-2.76	28.68
CV-24140	7/22/2026 11:04:39 AM	139.7	139.9	-2.62	-2.36			2.702	2.548	-2.19	-2.06	28.68
CV-24141	7/2/2026 7:55:00 AM											
CV-24141	7/2/2026 7:55:00 AM											
CV-24141	7/2/2026 12:59:12 PM	90.7	90.7	-0.24	-0.50			0.238	0.515	0.18	-0.18	28.63
CV-24141	7/14/2026 8:50:53 AM	91.2	91.2	-0.64	-0.62			0.634	0.614	0.52	0.54	28.64
CV-24141	7/14/2026 8:51:58 AM	91.1	91.1	-0.55	-0.51			0.544	0.510	0.53	0.53	28.64
CV-24141	7/28/2026 2:19:35 PM	107.2	107.2	-0.92	-0.59			0.833	0.606	-0.64	0.34	28.52
CV-24142	7/2/2026 8:30:00 AM											
CV-24142	7/2/2026 8:30:00 AM											
CV-24142	7/9/2026 8:59:51 AM	133.8	132.7	-1.53	-1.54			1.554	1.516	-1.48	-1.45	28.67
CV-24142	7/9/2026 9:01:16 AM	133.7	133.9	-1.66	-1.68			1.626	1.646	-1.65	-1.63	28.67
CV-24142	7/30/2026 10:56:47 AM	151.7	151.9	-1.42	-1.36			1.359	1.318	-1.51	-1.41	28.72
CV-24142	7/30/2026 10:57:39 AM	152.9	153.4	-1.17	-1.07			1.376	1.402	-1.36	-1.36	28.72
CV-24143	7/1/2026 8:35:00 AM											
CV-24143	7/1/2026 8:35:00 AM											
CV-24143	7/1/2026 10:34:22 AM	81.1	81.3	-0.47	-0.17			0.464	0.145	0.32	0.23	28.64
CV-24143	7/1/2026 10:37:17 AM	81.4	81.4	-0.34	-0.36			0.325	0.363	0.24	0.34	28.63
CV-24144	7/8/2026 10:38:46 AM	112.0	111.7	-3.66	-3.73			3.620	3.666	-3.26	-3.38	28.7
CV-24144	7/20/2026 1:19:01 PM	110.0	110.0	-4.36	-4.36			4.356	4.393	-3.83	-3.91	28.69
CV-24145	7/7/2026 9:15:00 AM											
CV-24145	7/7/2026 9:15:00 AM											
CV-24145	7/7/2026 9:15:42 AM	192.4	192.6	-7.08	-4.96			0.292	0.248	-8.02	-8.10	28.6
CV-24145	7/7/2026 9:16:13 AM	192.2	192.2	-4.71	-4.72			0.206	0.142	-8.15	-8.46	28.59

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24145	7/14/2026 9:05:26 AM	190.8	190.7	-4.43	-5.39			0.073	0.355	-9.38	-9.46	28.6
CV-24145	7/14/2026 9:05:51 AM	191.0	190.9	-5.73	-5.73			0.490	0.468	-9.52	-9.35	28.6
CV-24145	7/14/2026 9:20:00 AM											
CV-24145	7/21/2026 8:36:45 AM	188.9	188.7	-6.07	-5.81			0.513	0.461	-9.45	-8.88	28.6
CV-24145	7/28/2026 8:11:20 AM	188.6	188.8	-7.13	-7.08			0.000	0.000	-11.66	-11.66	28.49
CV-24146	7/1/2026 9:26:27 AM	114.0	114.0	-6.46	-6.47	26.7	26.8	1.677	1.685	-7.90	-7.91	28.57
CV-24146	7/1/2026 9:28:20 AM	114.1	114.2	-6.92	-6.79	28.4	27.6	1.061	0.997	-8.03	-7.89	28.57
CV-24146	7/22/2026 10:17:09 AM	115.3	115.5	-4.30	-4.30	20.0	21.2	0.522	0.586	-4.81	-4.81	28.65
CV-24146	7/27/2026 2:11:52 PM	115.7	115.8	-5.72	-5.72	25.5	25.1	0.851	0.828	-6.52	-6.67	28.62
CV-24147	7/1/2026 9:36:36 AM	110.1	107.8	-6.68	-6.07	6.6	9.3	0.011	0.022	-6.66	-6.69	28.61
CV-24147	7/1/2026 9:46:01 AM	111.3	111.2	-6.38	-6.38	11.8	9.0	0.036	0.021	-6.45	-6.33	28.6
CV-24147	7/22/2026 10:21:45 AM	116.9	117.0	-4.79	-4.83	10.9	12.2	0.030	0.038	-5.23	-5.06	28.76
CV-24148	7/6/2026 2:26:20 PM	177.4	177.3	-5.56	-5.60			5.934	5.991	-12.58	-12.57	28.52
CV-24148	7/6/2026 2:45:00 PM											
CV-24148	7/6/2026 2:45:00 PM											
CV-24148	7/15/2026 1:20:00 PM											
CV-24148	7/15/2026 1:21:10 PM	183.6	183.5	-4.96	-4.88			4.998	4.876	-11.26	-11.03	28.45
CV-24148	7/28/2026 1:21:09 PM	180.3	180.6	-11.10	-11.25			11.217	11.383	-13.86	-14.36	28.49
CV-24149	7/2/2026 3:03:27 PM	129.0	128.5	-2.11	-1.53	42.0	41.6	0.480	0.470			28.47
CV-24149	7/29/2026 10:38:37 AM	129.0	129.1	-0.97	-0.94	7.9	5.6	0.017	0.008	-9.02	-8.48	28.45
CV-24150	7/2/2026 1:19:01 PM	106.7	106.8	-0.48	-0.48	22.0	21.9	0.471	0.468			28.48
CV-24150	7/24/2026 10:54:45 AM	109.8	109.9	-1.04	-1.04			1.038	1.038	-13.63	-13.63	28.47
CV-24151	7/2/2026 4:27:58 PM	108.6	108.6	-2.36	-1.93	74.0	69.7	5.024	4.469			28.47
CV-24151	7/29/2026 10:06:40 AM	114.5	114.8	-0.45	-0.47			0.436	0.442	-8.54	-9.26	28.45
CV-24152	7/2/2026 3:30:10 PM	137.3	137.2	-0.90	-0.55	0.0	0.0	-3.246	-2.322	-6.57		28.46
CV-24152	7/2/2026 3:31:51 PM	137.3	137.3	-0.72	-0.71	0.0	0.0	0.689	0.680	-6.53		28.46
CV-24152	7/22/2026 2:16:41 PM	140.7	140.8	-0.72	-0.70	33.8	34.6	2.767	2.904	-7.71	-7.79	28.56
CV-24153	7/2/2026 1:30:09 PM	114.4	114.3	-2.15	-1.62	46.5	39.8	2.092	1.542			28.49
CV-24153	7/29/2026 10:41:39 AM	119.0	119.4	-1.12	-1.11			1.084	1.083	-15.49	-15.40	28.45
CV-24154	7/2/2026 12:04:43 PM	103.5	102.5	-0.96	-1.18			0.961	1.175	-7.19	-5.15	28.55
CV-24154	7/2/2026 1:26:44 PM	112.8	112.2	-1.63	-1.05	0.0	0.0	1.706	1.050	-11.48		28.49
CV-24154	7/16/2026 2:44:12 PM	107.7	107.8	-0.15	-0.16			0.151	0.153	-4.33	-4.26	28.42

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24155	7/2/2026 2:56:00 PM	130.3	129.9	-1.94	-1.19	43.2	34.2	1.990	1.260			28.64
CV-24155	7/22/2026 2:06:53 PM	123.9	124.1	-0.33	-0.31			0.308	0.311	-10.53	-10.65	28.56
CV-24156	7/6/2026 1:00:56 PM	133.6	133.7	-3.28	-1.03	50.7	32.5	0.802	0.327	-10.08		28.47
CV-24156	7/6/2026 1:03:01 PM	134.1	134.1	-0.65	-0.65	35.1	35.2	0.408	0.406	-9.99		28.47
CV-24156	7/17/2026 10:11:04 AM	136.1	136.2	0.06	-0.04	43.5	45.1	0.501	0.538	-9.33	0.67	28.55
CV-24157	7/2/2026 4:31:31 PM	106.2	106.2	-0.85	-0.84	63.1	63.0	3.514	3.506			28.46
CV-24157	7/17/2026 10:17:57 AM	113.7	114.2	-0.31	-0.31			0.279	0.281	-9.94	-10.11	28.55
CV-24158	7/2/2026 4:18:26 PM	127.8	125.8	-4.13	-2.24	23.7	0.0	1.790	-2.402	-10.04		28.45
CV-24158	7/17/2026 9:52:10 AM	127.6	128.3	-0.99	-0.98	13.9	13.6	0.530	0.510	-10.13	-9.96	28.54
CV-24159	7/1/2026 11:34:49 AM	119.4	119.1	-2.42	-2.42	13.7	13.7	1.201	1.206	-19.00	-18.79	28.53
CV-24159	7/1/2026 11:38:58 AM	119.6	119.4	-2.41	-2.48	13.7	14.7	0.441	0.504	-19.07	-19.02	28.53
CV-24159	7/1/2026 11:39:41 AM	119.9	119.8	-2.53	-2.53	14.8	14.8	0.511	0.511	-18.95	-19.21	28.51
CV-24159	7/16/2026 2:28:59 PM	121.9	121.8	-1.19	-1.19	13.9	14.7	0.455	0.510	-16.84	-16.39	28.42
CV-24159	7/16/2026 2:29:46 PM	122.0	122.0	-1.18	-1.23	15.0	15.6	0.529	0.576	-16.79	-18.54	28.42
CV-24160	7/1/2026 1:08:53 PM	127.9	127.7	-4.38	-4.35	28.3	29.2	1.919	2.039	-18.23	-17.89	28.53
CV-24160	7/16/2026 2:50:10 PM	129.3	129.1	-3.64	-2.75	27.0	16.2	1.752	0.624	-16.33	-16.26	28.42
CV-24160	7/16/2026 2:51:27 PM	128.7	128.7	-2.50	-2.51	16.3	16.4	0.638	0.640	-16.37	-16.44	28.42
CV-24161	7/7/2026 2:17:35 PM	125.7	129.6	0.43	-0.14	0.0	0.0	-0.417	0.091	-12.41		28.45
CV-24161	7/7/2026 2:18:47 PM	130.1	130.1	-0.18	-0.16	0.0	0.0	0.177	0.179	-12.43		28.45
CV-24161	7/8/2026 2:54:28 PM	127.4	128.5	-0.79	-2.53			0.831	2.575	-14.26	-16.70	28.49
CV-24161	7/8/2026 2:55:35 PM	128.6	128.6	-2.75	-2.74			2.798	2.794	-16.69	-16.72	28.49
CV-24162	7/6/2026 12:09:43 PM	102.6	102.8	-0.62	-0.60			0.622	0.601	-17.92	-17.95	28.52
CV-24163	7/6/2026 10:51:03 AM	119.9	120.1	-0.29	-0.29			0.276	0.276	-16.16	-16.16	28.55
CV-24164	7/6/2026 2:59:38 PM	130.0	129.3	-2.46	-1.67	0.0	0.0	2.398	1.513	-11.39		28.46
CV-24164	7/17/2026 8:21:20 AM	125.1	125.5	-1.39	-1.36			1.381	1.379	-12.04	-11.89	28.54

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24165	7/2/2026 10:25:28 AM	124.3	124.0	-10.72	-10.55			10.684	10.566	-12.07	-11.98	28.56
CV-24165	7/22/2026 8:18:17 AM	128.0	128.7	-8.46	-8.35			8.554	8.495	-9.38	-9.22	28.58
CV-24166	7/1/2026 1:16:33 PM	110.1	110.1	-8.02	-8.63			8.016	8.614	-12.87	-12.52	28.53
CV-24166	7/16/2026 2:23:51 PM	121.8	121.8	-7.07	-7.06			7.201	7.124	-11.43	-11.23	28.42
CV-24167	7/1/2026 1:36:53 PM	115.6	115.6	-5.04	-4.93			4.995	4.966	-12.09	-12.25	28.5
CV-24167	7/28/2026 8:36:37 AM	115.3	115.1	-4.92	-4.91			4.927	4.921	-10.27	-10.15	28.44
CV-24168	7/2/2026 12:22:20 PM	109.6	109.5	-1.17	-1.16			1.136	1.129	-11.62	-11.95	28.57
CV-24168	7/22/2026 8:22:36 AM	129.0	88.6	-8.38	-8.35			8.536	8.514	-9.03	-9.15	28.59
CV-24169	7/6/2026 2:56:17 PM	118.3	118.3	-0.75	-0.75	0.0	0.0	0.789	0.789	-11.14		28.59
CV-24169	7/17/2026 8:24:21 AM	118.8	119.1	-0.76	-0.76			0.756	0.758	-10.98	-11.07	28.55
CV-24170	7/6/2026 3:57:46 PM	136.1	135.2	-2.73	-1.19	40.0	16.9	1.291	0.230	-10.62		28.43
CV-24170	7/6/2026 3:59:49 PM	134.9	134.9	-0.89	-0.89	16.7	17.0	0.230	0.240	-10.69		28.43
CV-24170	7/13/2026 10:36:08 AM	92.3	93.5	-0.60	-0.31	22.3	16.8	0.303	0.173	-12.13	-11.45	28.6
CV-24170	7/13/2026 10:37:39 AM	89.6	89.4	-0.18	-0.18	18.0	18.5	0.195	0.207	-11.75	-10.63	28.61
CV-24170	7/29/2026 8:57:26 AM	129.6	129.7	-1.58	-1.57	8.5	5.9	0.047	0.022	-11.36	-11.39	28.49
CV-24171	7/7/2026 2:44:27 PM	126.2	126.2	-0.85	-0.83	17.2	17.5	0.369	0.383	-8.97		28.46
CV-24171	7/28/2026 8:48:55 AM	128.9	128.9	-1.94	-1.95	19.5	19.3	0.506	0.496	0.25	0.26	28.44
CV-24172	7/7/2026 12:29:38 PM	122.3	122.2	-0.47	-0.41	0.0	0.0	-0.511	-0.460	-12.53		28.48
CV-24172	7/22/2026 9:55:02 AM	122.4	122.3	-0.37	-0.36	11.1	11.0	0.333	0.330	-12.68	-11.51	28.62
CV-24173	7/13/2026 11:49:25 AM	126.6	126.7	-1.77	-1.46	34.7	28.0	2.857	1.858	-15.41	-15.00	28.55
CV-24173	7/19/2026 1:43:48 PM	128.5	128.4	-1.00	-0.96	27.5	27.5	1.800	1.796	-13.83	-13.79	28.53
CV-24173	7/19/2026 1:45:39 PM	128.3	128.3	-0.83	-0.84	24.8	25.5	1.458	1.544	-13.17	-13.72	28.53
CV-24174	7/13/2026 9:26:49 AM	105.3		-3.84				3.883		-13.51		28.57
CV-24174	7/13/2026 9:29:10 AM	112.3	111.8	-0.60	-0.59			0.616	0.612	-11.40	-11.27	28.57
CV-24174	7/19/2026 1:34:46 PM	107.8	107.9	-0.11	-0.11			0.093	0.093	-13.62	-13.61	28.54
CV-24175	7/7/2026 11:47:48 AM	122.0	121.7	-1.25	-1.02	14.3	9.4	0.620	0.267	-13.01		28.64

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24175	7/13/2026 7:13:50 AM	120.3	117.3	-1.14	-0.67	23.4	11.0	0.353	0.077	-17.42	-17.50	28.56
CV-24175	7/13/2026 7:16:51 AM	116.2	115.7	-0.59	-0.58	9.0	8.9	0.052	0.050	-18.11	-16.48	28.53
CV-24175	7/19/2026 1:25:17 PM	121.9	122.0	-0.09	-0.09	6.7	6.7	0.029	0.029	-13.67	-13.67	28.55
CV-24176	7/7/2026 11:57:12 AM	119.1	119.1	-0.60	-0.59	0.0	0.0	-0.004	-0.003	-11.49		28.28
CV-24176	7/16/2026 9:57:20 AM	117.1	117.2	-0.42	-0.42	0.0	1.0	0.000	0.003	-10.94		28.41
CV-24177	7/3/2026 8:50:27 AM	118.5	118.7	-0.30	-0.30			0.304	0.304	-13.97	-14.31	28.63
CV-24177	7/20/2026 1:38:05 PM	128.1	128.2	-0.06	-0.04			0.046	0.023	-11.84	-12.64	28.62
CV-24178	7/7/2026 11:52:46 AM	131.9	130.8	-1.40	-0.96	21.6	11.4	1.428	0.397	-1.32		28.48
CV-24178	7/7/2026 11:54:03 AM	129.8	129.8	-0.96	-0.95	12.8	12.8	0.495	0.494	-1.33		28.48
CV-24178	7/16/2026 10:01:44 AM	131.1	130.8	-1.19	-0.99	13.6	8.2	0.546	0.201	-1.33		28.4
CV-24178	7/16/2026 10:02:55 AM	129.9	130.0	-0.92	-0.92	7.6	9.2	0.169	0.247	-1.62		28.4
CV-24179	7/7/2026 12:05:35 PM	132.7	131.8	-0.66	-0.48	8.4	4.9	0.210	0.073	-13.47		28.52
CV-24179	7/7/2026 12:07:10 PM	131.5	131.5	-0.47	-0.46	4.8	4.8	0.068	0.069	-14.03		28.52
CV-24179	7/16/2026 9:47:20 AM	132.3	132.3	-0.50	-0.49	6.1	6.1	0.117	0.115	-15.08		28.42
CV-24179	7/16/2026 9:48:41 AM	132.3	132.3	-0.53	-0.52	4.8	5.0	0.073	0.079	-15.70		28.42
CV-24180	7/1/2026 3:43:22 PM	122.0	121.9	-2.38	-2.38	15.5	14.5	0.709	0.619	-10.94		28.46
CV-24180	7/16/2026 10:10:17 AM	125.1	125.1	-1.82	-1.43	14.3	9.6	0.600	0.268	-1.49		28.41
CV-24181	7/1/2026 3:45:28 PM	103.9	104.9	-0.96	-0.94	22.1	21.9	0.649	0.635	-9.94		28.45
CV-24181	7/16/2026 10:05:46 AM	121.2	121.2	-1.32	-1.32	43.8	43.8	2.536	2.538	-12.91		28.41
CV-24182	7/1/2026 3:56:52 PM	112.0	109.4	-6.22	-4.74	0.0	0.0	6.130	4.596	-13.46		28.45
CV-24182	7/28/2026 9:23:56 AM	125.9	126.1	-4.11	-4.10			4.110	4.087	-11.44	-11.55	28.49
CV-24183	7/1/2026 4:06:34 PM	97.3	97.7	-1.88	-1.59	0.0	0.0	1.826	1.362	-15.15		28.44
CV-24183	7/16/2026 2:54:48 PM	108.2	108.2	-0.23	-0.23	0.0	0.0	0.268	0.267	-14.53		28.38
CV-24184	7/6/2026 10:20:25 AM	130.5	130.5	-0.10	-0.10	1.0	1.0	0.019	0.021	-13.47		28.49
CV-24184	7/6/2026 10:21:53 AM	130.4	130.4	-0.10	-0.10	0.8	0.9	0.015	0.018	-13.84		28.49
CV-24184	7/16/2026 3:19:56 PM	139.5	139.6	-0.04	-0.05	5.8	5.8	0.739	0.739	-14.00		28.38
CV-24184	7/16/2026 3:20:01 PM	139.5	139.6	-0.04	-0.05	5.8	5.8	0.739	0.739	-14.00		28.38
CV-24184	7/16/2026 3:21:33 PM	140.0	140.0	-0.10	-0.10	5.9	5.9	0.774	0.772	-13.98		28.38
CV-24185	7/6/2026 10:33:38 AM	122.1	122.1	-0.78	-0.61	22.9	17.2	1.442	0.818	-13.18		28.49
CV-24185	7/16/2026 3:10:44 PM	125.0	125.1	-0.18	-0.18	16.8	16.8	0.794	0.798	-13.80		28.37
CV-24186	7/6/2026 10:53:50 AM	130.0	129.7	-1.13	-0.83	22.7	15.3	1.419	0.646	-12.62		28.47
CV-24186	7/31/2026 9:06:58 AM	130.1	129.9	-0.85	-0.85	39.0	39.9	0.984	1.032	-11.39	-11.86	28.6
CV-24187	7/3/2026 8:45:32 AM	126.7	123.6	-0.83	-0.85	17.5	18.0	0.844	0.881	-14.75	-16.16	28.66
CV-24187	7/28/2026 10:01:22 AM	126.3	126.6	-0.33	-0.35	9.7	9.9	0.259	0.268	-14.60	-14.51	28.53

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24188	7/3/2026 8:18:13 AM	117.7	117.8	-3.29	-3.28	8.9	9.0	0.213	0.219	-15.79	-15.65	28.68
CV-24188	7/20/2026 10:23:42 AM	118.5	118.6	-3.12	-3.16	12.2	15.8	0.395	0.660	-15.44		28.68
CV-24189	7/3/2026 8:22:16 AM	115.7	115.4	-1.21	-1.04	5.3	4.1	0.580	0.359	-13.35	-14.60	28.7
CV-24189	7/20/2026 10:19:56 AM	113.9	113.9	-0.83	-0.76	4.1	4.9	0.342	0.476	-14.49		28.69
CV-24190	7/3/2026 9:31:48 AM	123.5	123.5	-6.72	-6.71	24.8	24.4	1.710	1.653	-13.77	-13.12	28.63
CV-24190	7/28/2026 10:06:36 AM	124.2	124.1	-7.10	-6.41	27.3	19.6	2.080	1.074	-14.11	-14.27	28.54
CV-24192	7/3/2026 9:29:59 AM	119.7	119.9	-11.80	-11.74	20.7	11.5	1.029	0.315	-13.22	-12.15	28.63
CV-24192	7/28/2026 10:10:00 AM	119.8	119.8	-11.86	-11.86	21.3	20.5	1.090	1.013	-12.98	-12.92	28.54
CV-24193	7/1/2026 3:06:38 PM	116.1	116.1	-12.59	-12.57	25.2	25.2	0.782	0.782	-14.74		28.47
CV-24193	7/16/2026 10:16:18 AM	117.7	117.9	-12.57	-11.60	29.5	20.8	1.082	0.536	-15.34		28.43
CV-24194	7/1/2026 3:49:34 PM	98.4	98.4	-2.41	-2.51	21.9	25.2	1.025	1.362	-13.63		28.46
CV-24194	7/16/2026 2:16:21 PM	106.6	106.5	-3.56	-3.58	25.1	25.8	1.383	1.454	-13.33		28.19
CV-24195	7/1/2026 10:55:30 AM	118.4	118.7	-1.91	-1.90	14.8	15.9	4.477	5.141	-15.52		28.57
CV-24195	7/16/2026 2:22:23 PM	120.1	120.2	-1.17	-1.03	14.5	8.4	4.443	1.475	-13.96		28.39
CV-24196	7/1/2026 10:39:45 AM	123.1	122.6	-2.11	-2.06	12.6	13.1	0.201	0.217	-16.21		28.56
CV-24196	7/16/2026 2:59:29 PM	125.8	125.8	-1.60	-1.60	6.5	6.8	0.054	0.060	-14.65		28.38
CV-24197	7/7/2026 3:12:35 PM	127.2	126.8	-1.93	-1.50	33.7	17.4	3.128	0.839	-9.93		28.5
CV-24197	7/31/2026 9:01:20 AM	125.4	125.5	-1.14	-1.14	18.4	18.3	0.926	0.917	-12.10	-12.06	28.67
CV-24198	7/1/2026 10:51:11 AM	122.8	122.8	-1.13	-1.13	13.4	13.6	3.813	3.895	-19.98		28.59
CV-24198	7/31/2026 10:02:49 AM	120.0	120.9	-0.02	-0.14	5.5	8.7	0.620	1.584	-17.65	-18.79	28.71
CV-24199	7/1/2026 10:46:03 AM	127.7	127.8	-1.48	-1.37	29.3	29.3	1.069	1.067	-19.61		28.59
CV-24199	7/31/2026 9:58:44 AM	129.3	129.3	-1.39	-1.00	25.2	19.6	0.838	0.505	0.30	0.22	28.71
CV-24200	7/1/2026 8:49:29 AM	118.0	118.0	-1.34	-1.33	17.7	17.8	1.913	1.938	-18.83		28.6
CV-24200	7/31/2026 9:37:53 AM	120.5	120.5	-1.27	-1.07	28.7	23.2	1.923	1.254	-18.78	-18.62	28.74
CV-24201	7/1/2026 9:13:06 AM	119.8	119.8	-2.84	-2.84	12.8	12.9	0.443	0.451			28.61
CV-24201	7/31/2026 8:51:59 AM	120.7	123.2	-1.09	-0.85	15.7	9.4	0.664	0.239	-19.38	-19.69	28.74
CV-24202	7/1/2026 9:25:34 AM	121.7	121.7	-12.88	-12.63	0.0	0.0			-17.43		28.61
CV-24202	7/31/2026 8:34:50 AM	124.2	124.2	-19.26	-18.72			19.287	18.845	-19.42	-19.00	28.71
CV-24203	7/1/2026 7:48:19 AM	122.8	122.8	-4.18	-4.15	27.8	29.5	4.824	5.440	-18.81		28.63
CV-24203	7/28/2026 1:14:17 PM	125.1	125.4	-3.57	-3.34	24.9	23.2	4.036	3.496	-14.81	-15.56	28.67
CV-24203	7/28/2026 1:19:47 PM	125.4	125.4	-3.18	-3.17	21.6	21.5	3.023	2.997	-15.82	-15.81	28.67
CV-24204	7/1/2026 7:53:18 AM	127.3	127.3	-6.16	-6.13	31.3	32.9	1.234	1.364	-19.10		28.64

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24204	7/28/2026 1:25:26 PM	128.0	128.0	-6.06	-6.04	21.0	20.9	1.058	1.039	-16.39	-16.25	28.67
CV-24205	7/1/2026 8:20:01 AM	122.1	122.1	-7.06	-7.04	40.3	40.3	2.002	2.006	-18.10		28.65
CV-24205	7/28/2026 1:31:58 PM	125.2	125.2	-5.71	-5.65	37.2	35.2	1.844	1.647	-16.18	-16.25	28.67
CV-24205	7/28/2026 1:33:51 PM	125.2	125.2	-5.37	-5.36	33.5	33.9	1.496	1.526	-16.14	-16.09	28.66
CV-24206	7/1/2026 8:55:19 AM	112.1	112.6	-9.92	-9.87	0.0	0.0	9.884		-13.84		28.61
CV-24206	7/31/2026 8:54:17 AM	112.1	113.2	-10.29	-8.35			10.409	4.521	-14.88	-15.24	28.75
CV-24207	7/1/2026 1:28:15 PM	132.9	132.8	-0.41	-0.40	15.2	15.8	0.306	0.334	-13.11	-12.88	28.53
CV-24207	7/1/2026 1:31:42 PM	132.9	133.0	-0.39	-0.39	14.7	15.3	0.516	0.561	-13.27	-13.12	28.53
CV-24207	7/16/2026 2:04:54 PM	134.7	134.7	0.21	0.10	14.2	15.7	0.486	0.589	-11.73	-11.68	28.42
CV-24207	7/16/2026 2:08:41 PM	135.0	135.4	-0.45	-0.46	17.4	17.5	0.406	0.413	-11.63	-11.37	28.42
CV-24207	7/16/2026 2:09:52 PM	137.4	137.6	-0.54	-0.60	17.3	17.5	0.403	0.413	-11.67	-11.42	28.42
CV-24208	7/9/2026 1:33:32 PM	130.7	130.8	-0.46	-0.45	22.9	23.6	1.224	1.294	-15.35	-15.54	28.62
CV-24209	7/1/2026 10:07:13 AM	123.9	124.0	-0.71	-0.67	0.0	0.0	0.872	1.043	-17.75		28.62
CV-24210	7/6/2026 12:13:38 PM	109.6	109.9	-1.75	-1.61			1.717	1.579	-14.68	-14.64	28.55
CV-24211	7/15/2026 10:55:22 AM	125.4	126.3	-12.46	-12.46			12.487	12.467	-16.58	-16.67	28.65
CV-24212	7/15/2026 10:48:49 AM	138.4	139.3	-16.28	-15.20			16.242	15.184	-15.80	-15.68	28.65
CV-24213	7/6/2026 11:00:04 AM	132.5	127.6	-7.04	-3.44			7.089	3.384	-7.10	-8.03	28.67
CV-24213	7/6/2026 11:01:11 AM	127.1	127.3	-3.20	-3.19			3.145	3.140	-7.53	-7.58	28.67
CV-24214	7/7/2026 9:51:22 AM	122.7	123.1	-3.44	-3.45			3.433	3.455	-3.97	-4.06	28.64
CV-24215	7/8/2026 3:28:03 PM	119.2	119.5	-2.18	-1.84	15.1	10.6	0.145	0.071			28.51
CV-24216	7/6/2026 11:20:47 AM	111.5	110.6	-7.05	-5.77			7.076	5.847	-11.19	-12.26	28.7
CV-24217	7/2/2026 11:20:03 AM	107.4	107.6	-1.22	-0.87	0.0	0.0	1.140	0.828			28.5
CV-24218	7/6/2026 10:27:41 AM	129.8	129.8	-4.75	-4.76			4.687	4.703	-11.71	-11.66	28.59
CV-24219	7/2/2026 9:34:00 AM											
CV-24219	7/2/2026 9:51:06 AM	186.6	188.1	-12.95	-6.49			13.380	6.846	-14.77	-14.36	28.57

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24219	7/2/2026 9:51:58 AM	188.0	188.1	-7.44	-6.42			7.795	6.717	-14.40	-14.38	28.57
CV-24219	7/9/2026 9:40:00 AM											
CV-24219	7/9/2026 9:40:00 AM											
CV-24219	7/9/2026 9:41:25 AM	186.9	186.9	-11.78	-11.95			11.970	12.104	-13.22	-13.20	28.47
CV-24219	7/16/2026 9:39:52 AM	185.6	185.7	-9.39	-9.90			9.868	10.449	-12.51	-12.51	28.45
CV-24219	7/16/2026 9:45:00 AM											
CV-24219	7/30/2026 8:40:54 AM	183.2	183.3	-9.59	-9.63			10.005	10.104	-13.47	-13.47	28.5
CV-24220	7/6/2026 11:00:13 AM	128.0	128.5	-14.03	-10.38			14.401	10.771	-14.91	-14.77	28.54
CV-24221	7/15/2026 1:49:24 PM	129.1	129.4	-2.55	-2.54	4.1	4.4	0.047	0.053	-13.92	-13.97	28.58
CV-24222	7/15/2026 10:36:12 AM	124.3	124.3	-14.48	-14.48	25.9	27.7	1.909	2.185	-15.83	-16.13	28.62
CV-24223	7/30/2026 10:04:38 AM	127.0	127.0	-0.38	-0.38			0.366	0.364	-14.85	-14.36	28.63
CV-24224	7/6/2026 10:22:07 AM	95.4	95.5	-0.20	-0.22			0.199	0.223	-16.77	-16.82	28.56
CV-24225	7/7/2026 1:39:40 PM	109.9	109.8	0.17	0.34			0.000	0.000	-10.02	-9.25	28.66
CV-24225	7/7/2026 1:42:58 PM	113.2	112.0	0.01	0.04			0.000	0.000	-14.95	-14.87	28.67
CV-24225	7/8/2026 8:07:51 AM	104.9	105.5	-2.05	-2.05			2.044	2.053	-20.78	-21.04	28.65
CV-24226	7/15/2026 10:59:16 AM	127.4	127.5	-4.97	-4.98	11.0	11.2	0.079	0.082	-17.05	-17.14	28.65
CV-24227	7/3/2026 9:35:57 AM	118.2	118.1	-6.40	-4.53	36.2	16.1	3.087	0.605	-14.28	-14.32	28.67
CV-24231	7/8/2026 10:36:56 AM	126.3	126.2	-0.84	-0.85	15.5	14.7	0.655	0.596	-17.58	-17.32	28.68
CV-24236	7/3/2026 10:02:29 AM	107.7	107.8	-2.21	-2.06	17.9	16.2	0.409	0.334	-5.22	-5.11	28.72
CV-24237	7/3/2026 10:06:25 AM	112.7	113.0	-0.86	-0.77	12.4	13.2	0.196	0.224	-3.41	-5.84	28.71
CV-24243	7/7/2026 1:18:13 PM	110.7	113.9	-0.44	-0.15	39.7	19.8	4.215	1.054	-12.11	-10.26	28.69
CV-24243	7/7/2026 1:22:47 PM	116.2	116.4	-0.30	-0.29	25.8	25.8	1.794	1.789	-9.92	-10.01	28.69
CV-24243	7/7/2026 1:34:56 PM	113.0	112.9	-0.05	-0.05	6.4	6.4	0.110	0.110	-18.47	-16.81	28.7
CV-24244	7/7/2026 1:41:19 PM	113.6	113.5	-1.80	-1.65	48.6	41.6	0.602	0.441	-14.90	-15.00	28.69
CV-24245	7/7/2026 12:39:44 PM	117.0	117.1	-0.54	-0.54	9.8	9.1	0.609	0.522	-16.12	-15.41	28.75
CV-24246	7/7/2026 12:36:10 PM	119.5	121.3	-0.08	-0.16	15.0	17.2	0.607	0.798	-13.70	-13.62	28.75
CV-24253	7/7/2026 12:47:31 PM	116.8	117.8	-0.43	-0.43	22.5	22.3	0.655	0.642	-11.25	-11.28	28.74
CV-25	7/9/2026 11:25:13 AM	102.6	103.4	-2.36	-1.77	1.8	0.0	0.004	-0.034	-13.81		28.52
CV-25	7/9/2026 11:27:02 AM	103.4	103.4	-1.72	-1.74	0.0	0.0	-0.009	-0.008	-13.90		28.52
CV-2501	7/1/2026 3:25:30 PM	121.7	121.7	-0.52	-0.52	30.9	31.1	0.233	0.235	-9.02		28.48
CV-2502	7/1/2026 3:10:48 PM	120.6	120.7	-0.97	-0.77	28.1	18.9	0.192	0.087	-18.29		28.48
CV-2503	7/1/2026 8:33:56 AM	126.1	126.1	-0.96	-0.92	17.8	18.0	0.078	0.079	-18.17		28.6

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2504	7/8/2026 10:32:18 AM	129.0	129.2	-1.49	-1.21	155.1	131.1	6.349	4.521	-17.04	-17.06	28.69
CV-2505	7/7/2026 3:22:12 PM	119.1	119.7	-3.80	-3.04	37.5	26.0	0.858	0.415	-12.72		28.53
CV-2506	7/7/2026 3:27:25 PM	121.3	121.4	-2.75	-2.11	56.0	38.4	1.931	0.904	-12.35		28.6
CV-2507	7/7/2026 3:30:21 PM	121.7	121.7	-5.41	-5.38	62.2	63.2	4.737	4.890	-11.66		28.62
CV-2508	7/8/2026 10:25:00 AM	120.5	120.6	-13.80	-13.80	83.0	81.7	1.835	1.775	-17.74	-17.84	28.73
CV-2509	7/8/2026 10:07:20 AM	116.3	116.3	-12.46	-12.12	76.3	73.2	3.800	3.495	-18.52	-18.53	28.74
CV-2510	7/8/2026 10:20:42 AM	114.4	114.5	-9.54	-9.54	43.7	43.7	5.272	5.265	-18.05	-18.22	28.74
CV-25100D	7/6/2026 1:51:46 PM	130.1	128.2	-11.46	-10.76			11.307	10.658	-11.23	-11.39	28.58
CV-25100D	7/23/2026 9:38:21 AM	159.9	160.1	-5.18	-5.11			5.106	5.079	-10.69	-10.38	28.54
CV-25100D	7/27/2026 1:20:17 PM	116.4	118.6	-5.81	-5.67			6.224	6.059	-7.15	-6.69	28.53
CV-25100S	7/6/2026 1:36:14 PM	167.8	167.8	-6.73	-6.87			6.809	6.957	-9.04	-8.99	28.52
CV-25100S	7/6/2026 1:50:00 PM											
CV-25100S	7/13/2026 1:06:47 PM	176.9	177.4	-5.41	-5.73			5.664	5.968	-9.52	-9.68	28.54
CV-25100S	7/13/2026 1:15:00 PM											
CV-25100S	7/20/2026 10:16:41 AM	179.5	180.8	-1.22	-3.32			1.370	3.318	-11.26	-9.63	28.57
CV-25100S	7/20/2026 10:17:24 AM	181.0	180.9	-5.00	-4.60			4.733	4.494	-11.05	-10.86	28.57
CV-25100S	7/20/2026 10:35:00 AM											
CV-25100S	7/27/2026 1:24:21 PM	176.8	177.5	-4.44	-4.10			4.502	3.945	-5.89	-5.77	28.53
CV-25101D	7/6/2026 10:26:33 AM	96.1	96.2	-10.55	-10.25			10.508	10.208	-10.26	-10.11	28.55
CV-25101D	7/20/2026 9:01:51 AM	83.3	83.7	-10.78	-10.07	95.6		9.477				28.54
CV-25101S	7/6/2026 10:28:38 AM	118.1	118.4	-1.40	-1.40			1.380	1.373	-10.93	-10.88	28.54
CV-25101S	7/20/2026 9:03:57 AM	123.3	124.0	-2.98	-2.34	46.9	48.8	2.252	2.433			28.54
CV-25102	7/6/2026 10:37:26 AM	98.6	98.8	-11.54	-11.51	0.0	0.0			-11.17		28.56
CV-25102	7/23/2026 9:32:59 AM	119.0	98.6	-10.70	-12.28			10.704	12.237	-10.63	-12.16	28.55
CV-25103	7/6/2026 10:03:22 AM	126.2	128.2	-0.57	-0.56			0.562	0.558	-12.00	-12.01	28.55
CV-25103	7/27/2026 2:29:26 PM	122.8	123.0	-0.38	-0.38			0.385	0.356	-10.04	-9.72	28.54
CV-25104D	7/8/2026 12:30:04 PM	107.4	107.6	-11.27	-11.27			11.452	11.426	-11.36	-11.50	28.66
CV-25104D	7/21/2026 1:22:18 PM	109.8	110.6	-6.38	-6.39			6.413	6.365	-8.50	-8.24	28.62
CV-25104S	7/2/2026 1:43:30 PM	103.4	103.7	-6.19	-6.08			6.414	6.340	-5.77	-5.54	28.57

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-25104S	7/8/2026 12:33:30 PM	120.2	120.5	-8.12	-8.06			8.279	8.159	-11.63	-12.47	28.66
CV-25104S	7/21/2026 1:17:04 PM	98.2	98.2	-7.92	-8.46			7.928	8.493	-7.66	-8.27	28.62
CV-25105D	7/6/2026 9:46:11 AM	93.5	90.5	-13.43	-12.75			13.486	12.681	-13.48	-13.44	28.55
CV-25105D	7/6/2026 9:47:55 AM	93.0		-10.73				10.627		-13.35		28.54
CV-25105D	7/20/2026 9:15:48 AM	83.1	83.7	-0.69	-0.60	23.0	22.6	0.588	0.572			28.55
CV-25105S	7/6/2026 9:40:39 AM	122.4	121.3	-1.19	-0.60			1.185	0.589	-12.17	-12.48	28.54
CV-25105S	7/6/2026 9:41:26 AM	121.1	121.3	-0.60	-0.59			0.599	0.596	-12.68	-12.83	28.54
CV-25105S	7/20/2026 9:18:29 AM	108.2	106.9	-0.91	-0.74	31.7	28.1	0.935	0.739			28.55
CV-25105S	7/20/2026 9:19:47 AM	105.2	105.5	-0.74	-0.69	27.7	27.8	0.706	0.709			28.55
CV-25106D	7/8/2026 12:21:49 PM	104.2	104.2	-3.84	-3.84			3.680	3.761	-12.17	-12.17	28.66
CV-25106D	7/8/2026 12:22:37 PM	104.1	104.1	-3.91	-3.89			3.837	3.819	-12.00	-12.03	28.66
CV-25106D	7/9/2026 3:25:27 PM	102.3	102.3	-2.58	-2.60	50.9	51.7	2.545	2.629			28.38
CV-25106D	7/9/2026 3:27:08 PM	102.0	102.0	-2.26	-2.29	50.7	50.8	2.433	2.436			28.38
CV-25106D	7/21/2026 1:33:34 PM	102.7	102.8	-8.75	-8.75			8.785	8.797	-8.67	-8.62	28.62
CV-25106S	7/8/2026 12:25:20 PM	104.8	104.8	-11.85	-11.85			11.954	11.954	-11.97	-11.97	28.66
CV-25106S	7/8/2026 12:26:22 PM	104.5	104.6	-11.75	-11.80			11.939	12.013	-11.91	-12.13	28.66
CV-25106S	7/21/2026 1:25:58 PM	102.1	100.3	-9.09	-1.34			8.906	1.286	-8.64	-7.53	28.62
CV-25107D	7/2/2026 10:50:21 AM	95.8	95.9	-11.43	-11.46	0.0	0.0			-13.98		28.48
CV-25107D	7/21/2026 10:03:10 AM	128.6	128.6	-5.28	-5.42			5.278	5.406	-9.30	-9.90	28.62
CV-25107S	7/2/2026 10:46:50 AM	102.8	102.1	-1.62	-1.38	0.0	0.0	1.639	1.341	-14.07		28.49
CV-25107S	7/20/2026 8:38:14 AM	111.0	112.8	-1.57	-1.58	0.0	0.0	1.478	1.668	-10.51		28.62
CV-25107S	7/21/2026 10:06:29 AM	125.7	125.0	-1.07	-1.09			1.073	1.085	-9.02	-9.78	28.62
CV-2511	7/8/2026 10:47:35 AM	128.3	128.2	-1.16	-1.06	22.3	24.6	0.130	0.157	-17.43	-17.56	28.7

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2512	7/8/2026 10:52:13 AM	124.7	124.3	-0.73	-0.72	30.3	29.7	0.237	0.228	-17.30	-17.39	28.7
CV-2513	7/7/2026 1:03:46 PM	120.6	120.7	-3.16	-3.16	39.4	39.7	3.644	3.691	-15.83	-15.92	28.74
CV-2514	7/7/2026 12:27:36 PM	132.0	132.9	0.32	-0.06	23.4	32.1	0.724	1.364	-8.13	-7.78	28.75
CV-2514	7/7/2026 12:28:19 PM	132.8	132.8	-0.09	-0.07	30.6	31.0	1.244	1.274	-7.36	-7.54	28.75
CV-2514	7/7/2026 12:28:46 PM	133.0	133.0	-0.10	-0.10	30.9	31.0	1.266	1.270	-7.68	-7.63	28.75
CV-2515	7/9/2026 11:04:39 AM	116.0	116.8	-2.92	-2.66	23.1	17.6	0.613	0.356	-12.85		28.61
CV-2516	7/6/2026 11:26:24 AM	127.5	127.5	-3.71	-3.76	12.9	14.0	1.080	1.283	-7.03	-7.72	28.7
CV-2516	7/20/2026 9:44:48 AM	127.5	127.3	-4.99	-4.76	18.2	18.0	2.152	2.109	-10.13	-9.96	28.71
CV-2517	7/9/2026 11:37:20 AM	118.5	118.7	-3.66	-3.60	0.0	0.0	-0.015	-0.010	-14.29		28.53
CV-2518	7/9/2026 11:46:28 AM	111.5	109.4	-4.48	-3.75			0.083	0.032	-14.50		28.54
CV-2519	7/6/2026 10:07:30 AM	122.4	122.4	-1.61	-1.58	21.2	22.2	1.242	1.316	-14.70		28.62
CV-2520	7/6/2026 10:18:34 AM	142.5	139.8	-3.06	-2.02	0.0	0.0	-0.114	0.047	-13.83		28.61
CV-2520	7/6/2026 10:21:32 AM	138.1	137.4	-1.23	-0.74	0.0	0.0	0.052	0.052	-13.72		28.61
CV-2521	7/8/2026 2:50:11 PM	135.1	134.5	-4.63	-3.23	0.0	0.0	4.592	3.190	-15.35		28.48
CV-2521	7/8/2026 2:51:44 PM	131.2	131.2	-2.67	-2.65	0.0	0.0	2.650	2.565	-15.37		28.48
CV-2522	7/8/2026 12:50:04 PM	134.3	133.0	-0.51	-0.09	2.3	1.5	0.013	0.005	-15.26	-15.26	28.62
CV-2522	7/8/2026 12:51:07 PM	132.4	131.9	-0.11	-0.11	3.6	3.8	0.031	0.033	-15.24	-15.24	28.62
CV-2523	7/8/2026 12:35:59 PM	125.8	125.8	-2.41	-2.40	16.3	16.6	1.731	1.786	-6.30	-6.43	28.62
CV-2524	7/15/2026 1:31:35 PM	145.7	147.8	-0.16	-0.16	9.2	9.2	0.240	0.239	-14.70	-14.71	28.58
CV-2524	7/16/2026 1:43:13 PM	147.1	148.8	-0.75	-2.28			0.000	0.000	-15.63	-15.12	28.5
CV-2524	7/16/2026 1:45:00 PM											
CV-2524	7/16/2026 1:45:33 PM	149.2	149.3	-3.71	-3.72	26.3	25.1	2.001	1.821	-15.33	-13.85	28.49
CV-2524	7/22/2026 3:00:48 PM	143.8	144.1	-6.22	-6.21	27.3	27.1	2.146	2.116	-15.86	-15.85	28.62
CV-2525	7/8/2026 12:22:47 PM	117.2	117.2	-3.00	-1.83	45.0	18.1	4.753	0.761	-15.07	-15.33	28.62
CV-2526	7/8/2026 12:18:22 PM	121.3	121.3	-2.00	-1.73	11.7	10.4	0.033	0.027	-15.08	-15.00	28.63
CV-2527	7/2/2026 11:38:52 AM	130.3	131.3	-3.63	-3.86			3.599	3.806	-16.04	-16.09	28.63
CV-2527	7/2/2026 11:42:07 AM	130.9	131.1	-3.77	-3.78			3.731	3.742	-16.08	-15.92	28.62
CV-2527	7/6/2026 9:44:55 AM	135.4	135.1	-4.10	-3.97			4.105	3.965	-17.47	-16.52	28.59
CV-2527	7/6/2026 9:45:16 AM	136.0	136.3	-3.93	-3.94			3.940	3.940	-17.47	-17.43	28.59
CV-2527	7/30/2026 10:09:39 AM	134.9	135.2	-3.97	-3.96			3.961	3.958	-13.61	-13.65	28.58

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2528	7/6/2026 9:46:49 AM	110.8	110.7	-4.06	-4.03	10.6	12.0	0.066	0.084	-17.76		28.69
CV-2529	7/7/2026 12:22:38 PM	106.6	106.6	-8.74	-8.74	2.7	2.5	0.794	0.665	-14.42	-14.43	28.8
CV-2529	7/16/2026 1:49:16 PM	116.4	116.5	-7.77	-7.79			0.000	0.000	-15.39	-14.96	28.55
CV-2529	7/16/2026 1:50:34 PM	116.5	116.5	-7.91	-7.93			0.000	0.000	-14.99	-14.84	28.55
CV-2530	7/6/2026 12:09:42 PM	137.5	138.1	-12.76	-3.51			12.762	3.443	-17.64	-17.20	28.78
CV-2530	7/6/2026 12:10:39 PM	136.4	136.4	-3.14	-3.14			3.059	3.060	-17.32	-17.32	28.79
CV-2531	7/6/2026 12:01:36 PM	139.2	137.5	-8.32	-2.28			8.414	2.211	-17.39	-17.30	28.78
CV-2531	7/6/2026 12:02:52 PM	137.6	137.7	-2.11	-2.08			2.025	2.021	-16.93	-17.66	28.78
CV-2532	7/6/2026 11:55:09 AM	116.0	117.1	-17.84	-17.80			17.986	17.897	-17.97	-18.02	28.79
CV-2533	7/6/2026 11:48:36 AM	130.7	130.7	-15.12	-14.07	21.2	18.8	1.283	1.011	-17.85	-17.51	28.78
CV-2534	7/6/2026 11:41:45 AM	117.0	117.0	-7.05	-7.57	46.8	49.2	2.887	3.184	-20.42	-19.55	28.78
CV-2535	7/1/2026 7:30:47 AM	108.5	108.2	-1.22	-1.13	3.5	3.6	1.293	1.348	-15.15		28.65
CV-2536	7/9/2026 9:16:39 AM	99.1	99.2	-11.97	-11.81	7.8	7.2	1.270	1.091	-16.04	-15.77	28.69
CV-2537	7/1/2026 8:11:38 AM	103.9	103.7	-2.14	-2.13	50.1	50.0	2.198	2.183			28.65
CV-2538	7/1/2026 8:03:31 AM	107.8	107.8	-2.23	-2.20	14.6	14.4	4.341	4.194	-15.53		28.66
CV-2539	7/1/2026 3:03:38 PM	113.7	115.6	-0.72	-0.87	0.0	0.0	0.727	0.946	-14.76		28.48
CV-2539	7/16/2026 10:13:17 AM	120.7	120.7	-0.94	-0.93	0.0	0.0	1.409	1.408	-15.68		28.43
CV-2540	7/6/2026 4:05:31 PM	138.5	138.9	-5.35	-1.94	0.0	0.0	5.425	1.835	-10.23		28.44
CV-2540	7/6/2026 4:06:42 PM	138.8	138.8	-1.91	-1.92	0.0	0.0	1.928	1.934	-9.95		28.44
CV-2540	7/17/2026 8:16:47 AM	142.6	142.7	-1.30	-1.09			1.307	1.074	-10.67	-9.92	28.54
CV-2541	7/7/2026 9:23:24 AM	101.4	101.4	-2.37	-2.38			2.354	2.360	-8.70	-10.49	28.56
CV-2541	7/29/2026 9:20:26 AM	128.2	128.3	-3.13	-3.13			3.125	3.128	-11.04	-11.03	28.51
CV-2542	7/6/2026 12:51:45 PM	120.5	119.7	-2.66	-2.25	50.8	44.9	2.566	2.010			28.45
CV-2542	7/22/2026 8:26:21 AM	85.0	85.0	-2.29	-2.30			2.291	2.304	-11.75	-12.21	28.58
CV-2543-PLR	7/6/2026 3:12:48 PM	127.2	126.7	-10.96	-10.34	0.0	0.0			-11.07		28.46
CV-2543-PLR	7/17/2026 7:57:38 AM	121.0	119.9	-10.86	-10.45			11.046	10.620	-10.84	-10.40	28.55
CV-2544	7/9/2026 1:34:27 PM	135.6	135.6	-0.73	-0.73	0.0	0.0	0.724	0.722	-10.65		28.54
CV-2544	7/9/2026 1:36:07 PM	135.4	135.3	-0.53	-0.53	0.0	0.0	0.559	0.550	-11.23		28.54
CV-2544	7/17/2026 10:00:41 AM	112.0	86.1	0.20	-0.37			0.000	0.380	-7.69	-7.67	28.55
CV-2544	7/17/2026 10:02:08 AM	112.0	112.0	-0.60	-0.55			0.524	0.547	-7.75	-7.65	28.55
CV-2545	7/2/2026 3:43:52 PM	121.4	121.4	-0.58	-0.58	56.4	56.4	3.298	3.299			28.46
CV-2545	7/22/2026 2:10:43 PM	118.0	118.3	-0.10	-0.11			0.095	0.098	-7.18	-7.10	28.57
CV-2546	7/2/2026 3:39:52 PM	132.3	132.0	-3.77	-1.61	75.9	61.2	6.488	4.229			28.46

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2546	7/2/2026 3:41:04 PM	131.8	131.9	-1.36	-1.34	59.9	59.9	4.071	4.068			28.46
CV-2546	7/22/2026 2:14:01 PM	126.3	126.3	-0.47	-0.46			0.455	0.504	-7.26	-7.06	28.56
CV-2547	7/7/2026 2:22:04 PM	111.0	111.0	-0.57	-0.57	26.6	26.6	0.667	0.669			28.43
CV-2548	7/2/2026 11:51:45 AM	136.3	139.3	2.07	-0.28	0.0	0.0	-6.632	-1.932			28.5
CV-2548	7/2/2026 11:53:07 AM	139.5	139.4	-0.43	-0.41	0.0	0.0	-1.835	-1.638			28.5
CV-2548	7/19/2026 12:37:51 PM	140.6	140.9	0.30	-0.32	33.4	41.3	1.508	2.312	-16.40	-14.19	28.56
CV-2548	7/19/2026 12:48:14 PM	141.0	141.1	-0.34	-0.33	40.2	40.3	2.193	2.205	-13.49	-13.85	28.53
CV-2548	7/30/2026 9:44:46 AM	131.3	139.1	3.44	-1.08	7.1	43.9	0.067	2.614	-15.13	-15.46	28.53
CV-2548	7/30/2026 9:55:52 AM	139.5	139.7	-1.08	-1.00	43.6	42.2	2.574	2.413	-16.14	-15.31	28.53
CV-2548	7/30/2026 10:06:07 AM	140.5	140.6	-1.16	-1.65	40.7	48.2	2.255	3.169	-14.30	-16.08	28.53
CV-2549	7/2/2026 11:44:08 AM	112.6	110.5	-2.13	-1.26	0.0	0.0	-4.399	-0.440			28.5
CV-2549	7/19/2026 12:24:06 PM	114.9	114.8	-0.87	-0.90	8.0	7.8	0.407	0.385	-16.76	-15.38	28.55
CV-2549	7/19/2026 12:26:54 PM	114.5	114.4	-0.86	-0.85	7.6	7.9	1.219	1.331	-16.02	-17.07	28.54
CV-2549	7/30/2026 10:10:42 AM	116.7	118.3	-1.73	-1.87	7.3	13.7	1.128	3.995	-15.89	-15.16	28.53
CV-2549	7/30/2026 10:12:50 AM	119.4	120.0	-1.97	-2.10	12.4	18.8	0.361	0.826	-11.16	-15.72	28.53
CV-2550	7/6/2026 2:12:46 PM	173.6	173.8	-13.48	-13.47			14.027	13.941	-14.21	-14.23	28.52
CV-2550	7/6/2026 2:35:00 PM											
CV-2550	7/6/2026 2:35:00 PM											
CV-2550	7/15/2026 1:10:00 PM											
CV-2550	7/15/2026 1:15:53 PM	179.0	179.0	-10.78	-11.33			10.898	11.474	-11.21	-11.24	28.42
CV-2550	7/28/2026 1:16:37 PM	182.2	182.1	-14.12	-5.72			14.329	5.829	-14.54	-14.62	28.48
CV-2550	7/28/2026 1:17:15 PM	182.4	183.2	-4.85	-4.21			5.048	3.719	-14.82	-13.89	28.46
CV-2551	7/2/2026 9:45:00 AM											
CV-2551	7/2/2026 9:56:40 AM	152.9	152.9	-3.98	-3.70			3.959	3.679	-14.05	-14.17	28.56
CV-2551	7/9/2026 9:30:00 AM											
CV-2551	7/9/2026 9:30:00 AM											

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2551	7/9/2026 9:34:42 AM	165.5	164.6	-8.80	-5.71			9.273	6.172	-11.31	-12.37	28.49
CV-2551	7/9/2026 9:35:40 AM	164.5	164.6	-5.48	-5.73			5.959	6.204	-12.11	-12.13	28.47
CV-2551	7/16/2026 10:58:39 AM	154.6	154.4	-12.52	-7.78			13.112	8.319	-14.87	-14.85	28.43
CV-2551	7/16/2026 10:59:26 AM	155.2	155.2	-6.44	-6.19			6.900	6.649	-16.22	-13.43	28.44
CV-2551	7/16/2026 11:00:00 AM											
CV-2551	7/30/2026 8:34:53 AM	158.2	158.4	-6.88	-7.14			7.253	7.565	-16.18	-17.07	28.49
CV-2552	7/8/2026 12:12:15 PM	117.0	117.0	-12.92	-9.96			12.993	10.103	-14.18	-14.21	28.63
CV-2552	7/27/2026 2:39:02 PM	106.0		-6.81				6.855		-12.89		28.55
CV-2553	7/6/2026 3:28:02 PM	134.9	135.0	-0.56	-0.56	0.0	0.0	0.527	0.521	-11.79		28.47
CV-2553	7/6/2026 3:29:35 PM	134.1	133.9	-0.52	-0.52	0.0	0.0	0.508	0.503	-11.89		28.47
CV-2553	7/16/2026 2:50:41 PM	123.5	123.5	-0.06	-0.59			0.123	0.632	-11.01	-11.06	28.48
CV-2554	7/2/2026 10:28:28 AM	144.4	144.0	-10.10	-9.95			10.586	10.430	12.40	12.37	28.6
CV-2554	7/2/2026 10:30:00 AM											
CV-2554	7/29/2026 9:54:52 AM	171.3	172.1	-9.25	-9.61			9.616	9.986	-9.36	-9.67	28.47
CV-2554	7/29/2026 9:56:46 AM	171.9	171.9	-9.47	-9.41			9.774	9.705	-9.44	-9.35	28.47
CV-2555	7/2/2026 10:29:34 AM	118.9	121.7	-9.83	-9.55			10.049	9.839	-9.77	-10.02	28.58
CV-2555	7/21/2026 1:56:49 PM	126.3	127.3	-5.51	-5.87			5.506	5.822	-6.23	-6.97	28.62
CV-2555	7/22/2026 12:09:59 PM	131.9	131.5	-2.50	-1.39	11.6	10.1	0.878	0.657	-6.82	-7.09	28.69
CV-2555	7/22/2026 12:14:36 PM	131.6	131.0	-1.28	-1.24	14.2	14.0	1.313	1.270	-6.84	-7.41	28.67
CV-2556-PLR	7/6/2026 2:55:44 PM	179.6	179.8	-11.31	-11.16			11.796	11.528	-13.03	-13.18	28.52
CV-2556-PLR	7/6/2026 3:00:00 PM											
CV-2556-PLR	7/6/2026 3:00:00 PM											
CV-2556-PLR	7/15/2026 1:26:18 PM	185.1	185.1	-3.93	-4.12			3.677	4.183	-11.45	-11.62	28.45

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2556-PLR	7/15/2026 1:30:00 PM											
CV-2556-PLR	7/28/2026 1:24:55 PM	185.3	185.4	-5.00	-4.97			5.049	5.152	-14.58	-14.19	28.49
CV-2557	7/6/2026 9:34:25 AM	134.0	132.8	-7.37	-7.37			7.281	7.279	-11.15	-11.07	28.54
CV-2557	7/6/2026 9:35:26 AM	133.7	132.5	-7.73	-7.73			7.750	7.759	-11.58	-11.54	28.55
CV-2557	7/31/2026 8:57:06 AM	130.5	131.5	-0.47	-0.47			0.460	0.451	-16.63	-15.62	28.54
CV-2558-PLR	7/2/2026 9:22:49 AM	182.5	182.8	0.74	0.35			0.000	0.000	0.03	0.04	28.54
CV-2558-PLR	7/2/2026 9:25:00 AM											
CV-2558-PLR	7/9/2026 9:54:46 AM	186.2	186.0	-3.81	-1.00			3.685	1.307	0.00	0.00	28.46
CV-2558-PLR	7/9/2026 9:55:00 AM											
CV-2558-PLR	7/9/2026 9:55:00 AM											
CV-2558-PLR	7/16/2026 9:55:00 AM											
CV-2558-PLR	7/16/2026 9:56:07 AM	181.0	181.0	0.81	3.01			0.000	0.000	0.35	0.29	28.43
CV-2558-PLR	7/16/2026 10:01:19 AM	180.2	180.4	1.77	3.26			0.000	0.000	0.29	0.29	28.45
CV-2558-PLR	7/30/2026 10:36:54 AM	187.5	187.5	2.38	2.31			0.000	0.000	6.41	6.93	28.52
CV-2558-PLR	7/30/2026 10:37:41 AM	188.1	188.2	2.87	0.55			0.000	0.000	8.68	2.00	28.51
CV-2559	7/6/2026 10:36:34 AM	134.6	136.3	1.20	-0.13			0.000	0.127	-5.48	-5.31	28.6
CV-2559	7/6/2026 10:38:03 AM	137.2	137.7	-0.10	-0.10			0.100	0.104	-5.39	-5.39	28.59
CV-2559	7/27/2026 2:33:18 PM	125.0	125.2	-0.97	-0.97			0.959	0.956	-2.61	-2.78	28.55
CV-2560	7/6/2026 10:11:08 AM	123.1	123.3	-6.02	-5.75			5.934	5.770	-10.48	-10.65	28.54
CV-2560	7/20/2026 8:57:37 AM	123.2	123.2	-5.52	-5.42	0.0	0.0	5.615	5.570			28.53

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2561	7/6/2026 10:17:54 AM	123.5	118.9	-0.85	-0.85			0.851	0.854	-3.79	-3.80	28.55
CV-2561	7/20/2026 8:51:55 AM	117.9	123.2	-1.06	-0.99	0.0	0.0	1.108	1.065	-3.88		28.54
CV-2562	7/6/2026 2:16:47 PM	129.4	129.4	-2.93	-2.47			0.000	0.000	-4.69	-4.65	28.55
CV-2563	7/8/2026 3:11:20 PM	124.7	124.8	-6.63	-6.00	0.0	0.0	-0.004	-0.006	-7.36		28.5
CV-2564	7/7/2026 9:09:14 AM	116.7	117.9	-2.93	-2.69			2.903	2.656	-9.87	-12.08	28.55
CV-2564	7/16/2026 2:05:21 PM	118.8	118.9	-1.41	-1.43			1.393	1.329	-8.48	-9.62	28.47
CV-2565	7/1/2026 3:35:54 PM	102.3	102.2	-0.75	-0.73	0.0	0.0	0.652	0.651	-11.30		28.48
CV-2565	7/16/2026 9:44:21 AM	113.5	113.5	-0.79	-0.79	0.0	0.0	0.766	0.764	-15.47		28.42
CV-2566	7/1/2026 3:33:22 PM	109.9	110.0	-1.60	-1.39	0.0	0.0	1.596	1.355	-10.12		28.48
CV-2566	7/16/2026 9:42:16 AM	111.0	111.5	-1.56	-1.30	0.0	0.0	1.587	1.281	-15.47		28.43
CV-2567	7/1/2026 11:02:22 AM	104.7	105.4	-2.40	-2.44	0.0	0.0	2.506	2.705	-13.37		28.57
CV-2567	7/16/2026 2:13:44 PM	114.1	113.9	-2.84	-2.72	0.0	0.0	2.762	2.587	-14.43		28.39
CV-2568	7/1/2026 4:00:33 PM	108.2	106.9	-2.81	-2.08	0.0	0.0	2.777	1.992	-14.86		28.45
CV-2568	7/16/2026 2:52:06 PM	113.5	112.8	-1.26	-1.03	0.0	0.0	1.198	0.940	-14.73		28.39
CV-2569	7/1/2026 4:03:02 PM	104.1	104.1	-0.96	-0.96	0.0	0.0	0.889	0.885	-15.10		28.45
CV-2569	7/16/2026 2:56:59 PM	114.1	114.2	-0.64	-0.65	0.0	0.0	0.591	0.590	-14.68		28.38
CV-2570	7/6/2026 10:24:58 AM	110.9	110.9	-1.06	-1.06	0.0	0.0	1.077	1.073	-12.60		28.5
CV-2570	7/16/2026 3:05:45 PM	113.3	113.3	-0.58	-0.58	0.0	0.0	0.568	0.566	-12.18		28.39
CV-2571	7/7/2026 12:00:31 PM	97.0	97.0	-10.07	-10.07	98.5	98.9	2.361	2.378	-15.66	-15.66	28.76
CV-2572	7/7/2026 12:15:50 PM	121.9	122.1	-3.68	-3.65	58.8	59.5	4.571	4.679	-9.75	-9.76	28.77
CV-2610	7/25/2026 11:40:20 AM	103.9	104.4	0.43	-0.01	2.0	8.5	0.080	1.490	-16.92	-17.25	28.73
CV-2610	7/25/2026 11:42:03 AM	105.1	105.2	-0.14	-0.09	9.1	8.0	1.710	1.319	-18.68	-17.19	28.75
CV-2610	7/25/2026 11:44:49 AM	105.5	105.5	-0.09	-0.08	6.9	6.8	0.965	0.941	-17.81	-17.37	28.75
CV-2610	7/26/2026 10:14:09 AM	110.6	110.7	-0.50	-0.51	8.1	8.7	1.373	1.554	-18.90	-19.29	28.8
CV-2610	7/26/2026 10:14:51 AM	110.8	110.7	-0.52	-0.52	8.6	8.6	1.523	1.536	-18.65	-18.89	28.82
CV-2663	7/22/2026 12:56:38 PM	130.9	120.9	-5.21	0.32	12.2	0.9	3.287	0.018	-14.16	-15.57	28.6
CV-2663	7/22/2026 12:58:52 PM	117.7	123.0	1.20	1.12	0.4	1.5	0.003	0.046	-15.46	-15.61	28.6
CV-2663	7/22/2026 4:04:48 PM	126.7	119.6	3.49	3.10	9.8	11.5	2.035	2.786	-13.64	-14.84	28.57
CV-2663	7/22/2026 4:08:46 PM	117.0	124.8	3.68	2.54	9.5	12.3	1.908	3.223	-14.72	-14.21	28.57
CV-2663	7/24/2026 10:42:38 AM	104.4	138.6	6.39	-0.31	13.5	12.3	3.719	3.306	-12.25	-11.75	28.54
CV-2663	7/24/2026 10:44:41 AM	138.9	139.0	-0.39	-0.36	12.1	11.2	3.247	2.744	-11.69	-9.98	28.53
CV-2663	7/24/2026 10:48:15 AM	139.0	140.4	-0.49	-1.56	11.9	14.9	3.094	4.934	-11.86	-11.38	28.53

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2663	7/24/2026 10:50:52 AM	140.9	140.5	-1.89	-1.89	12.1	12.1	3.254	3.262	-11.56	-11.57	28.54
CV-2663	7/26/2026 11:07:52 AM	141.7	141.7	-8.82	-8.84	10.1	10.4	2.304	2.432	-15.92	-16.30	28.6
CV-2680	7/15/2026 4:49:56 PM	94.5	94.3	-1.01	-0.41	15.7	12.2	0.547	0.333	-12.80	-12.69	28.53
CV-2680	7/15/2026 4:52:34 PM	94.2	94.2	-0.09	-0.09	12.9	12.8	1.010	1.003	-12.73	-12.66	28.53
CV-2680	7/20/2026 9:30:35 AM	130.3	128.2	-4.21	-3.11	14.8	15.2	1.441	1.499	-16.65	-16.91	28.65
CV-2680	7/20/2026 9:34:17 AM	127.8	124.9	-2.96	-2.11	8.3	4.9	1.487	0.506	-16.26	-16.57	28.66
CV-2680	7/20/2026 9:38:37 AM	122.0	119.1	-1.82	-1.34	4.2	2.2	1.952	0.532	-16.68	-16.08	28.68
CV-2680	7/20/2026 9:40:30 AM	118.6	118.3	-1.28	-1.26	2.0	2.1	0.427	0.469	-16.33	-16.11	28.66
CV-2680	7/21/2026 5:32:16 AM	100.5	103.0	0.67	0.52	1.7	3.2	0.056	0.214	-13.78	-13.98	28.64
CV-2680	7/22/2026 1:11:09 PM	125.6	126.3	0.41	0.29	4.2	5.6	0.378	0.677	-14.68	-16.23	28.65
CV-2680	7/22/2026 4:18:33 PM	128.1	127.1	0.35	0.57	6.0	5.8	0.768	0.717	-16.04	-16.39	28.64
CV-2680	7/24/2026 10:20:22 AM	127.3	127.1	0.20	-0.04	4.4	1.8	0.406	0.066	-13.70	-13.82	28.6
CV-2680	7/24/2026 10:21:10 AM	127.2	127.1	-0.03	-0.03	2.8	1.6	0.168	0.056	-13.77	-13.85	28.61
CV-2687	7/21/2026 5:24:06 AM	115.5	103.3	-4.21	-2.19	12.6	1.0	3.364	0.022	-15.10	-15.77	28.64
CV-2687	7/22/2026 1:19:45 PM	98.1	95.4	-0.08	-0.41	2.1	3.6	0.086	0.257	-18.18	-19.00	28.68
CV-2687	7/22/2026 1:21:56 PM	95.8	95.4	-0.61	-0.72	3.0	5.1	0.186	0.526	-18.07	-18.04	28.68
CV-2687	7/22/2026 1:24:49 PM	96.1	96.5	-0.87	-0.67	4.7	1.0	0.444	0.020	-18.87	-18.29	28.68
CV-2687	7/22/2026 1:26:11 PM	96.9	96.1	-0.62	-0.62	2.9	2.9	0.170	0.168	-18.66	-18.37	28.68
CV-2687	7/22/2026 3:51:57 PM	100.8	100.5	-0.81	-0.50	1.9	1.4	0.077	0.038	-18.22	-18.29	28.67
CV-2687	7/22/2026 3:53:55 PM	100.6	100.5	-0.32	-0.34	1.2	1.2	0.029	0.031	-17.95	-17.94	28.66
CV-2688	7/29/2026 1:13:08 PM	111.4	111.5	0.20	0.00	9.9	10.1	2.044	2.145	-18.06	-18.56	28.63
CV-2688	7/29/2026 1:16:09 PM	111.6	111.5	0.00	0.00	10.1	10.1	2.149	2.126	-17.99	-17.89	28.64
CV-2688	7/30/2026 8:19:40 AM	116.6	116.6	-1.76	-1.84	11.0	11.6	2.555	2.848	-20.95	-20.28	28.67
CV-2688	7/30/2026 8:20:55 AM	116.6	116.6	-2.01	-2.00	11.6	11.7	2.847	2.876	-20.59	-20.15	28.66
CV-2689	7/20/2026 8:30:00 AM	117.5	117.7	-19.51	-2.82			19.751	2.844	-19.64	-19.62	28.68
CV-2689	7/20/2026 8:34:59 AM	119.5	120.5	-0.33	-2.96			0.340	2.992	-19.54	-18.74	28.69
CV-2689	7/20/2026 8:50:45 AM	121.2	120.5	-4.14	21.01			4.171	0.000	-19.49	-19.40	28.68
CV-2689	7/20/2026 9:11:16 AM	120.3	120.6	22.05	0.84			0.000	0.000	-18.57	-18.39	28.69
CV-2689	7/20/2026 10:12:48 AM	134.4	132.3	-2.59	-2.96			2.546	2.913	-18.36	-18.71	28.78

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2689	7/21/2026 5:46:41 AM	77.0	77.9	42.24	23.73			0.000	0.000	-15.12	-15.11	28.68
CV-2689	7/22/2026 1:43:50 PM	117.2	117.2	0.98	-0.09			0.000	0.057	-14.89	-17.32	28.69
CV-2689	7/22/2026 1:50:59 PM	116.5	116.5	0.11	0.09			0.000	0.000	-16.51	-16.15	28.71
CV-2689	7/22/2026 4:29:54 PM	115.6	114.8	-6.58	0.68			6.695	0.000	-17.19	-17.44	28.67
CV-2689	7/22/2026 4:34:31 PM	113.6	113.2	1.63	1.62			0.000	0.000	-17.69	-17.11	28.66
CV-2689	7/23/2026 12:43:00 PM	126.9	124.4	14.74	-0.46			0.000	0.397	-17.55	-16.90	28.65
CV-2689	7/23/2026 12:48:08 PM	124.3	123.1	-0.90	-0.89			0.891	0.877	-17.16	-16.58	28.66
CV-2690	7/22/2026 3:28:21 PM	104.5	102.1	-4.35	1.02	13.4	7.6	3.762	1.178	-16.24	-18.54	28.71
CV-2690	7/22/2026 3:30:50 PM	102.0	102.1	0.96	0.64	7.7	8.6	1.197	1.499	-18.94	-18.78	28.72
CV-2690	7/24/2026 10:07:33 AM	124.8	123.6	-1.10	-0.03	8.6	6.0	1.584	0.763	-16.22	-16.72	28.68
CV-2690	7/24/2026 10:09:10 AM	123.6	123.7	-0.05	-0.05	6.4	6.4	0.877	0.866	-16.16	-16.17	28.66
CV-2690	7/25/2026 12:07:22 PM	125.0	123.8	-6.71	-4.36	5.9	4.9	0.762	0.512	-19.41	-18.98	28.69
CV-2690	7/26/2026 10:30:30 AM	124.9	124.7	-7.01	-7.01	5.6	6.0	0.688	0.782	-20.69	-20.69	28.72
CV-2691	7/28/2026 9:40:50 AM	111.1	111.2	-1.89	-1.90	13.4	13.4	3.750	3.793	-14.84	-15.27	28.68
CV-2691	7/28/2026 12:47:38 PM	115.2	115.3	-1.99	-1.95	13.6	13.6	3.914	3.899	-14.01	-13.87	28.7
CV-48R	7/8/2026 3:14:46 PM	122.2	122.1	-6.91	-5.96	9.0	8.5	0.513	0.457	-7.17		28.52
CV-52D	7/6/2026 10:15:17 AM	98.1	100.8	-7.74	-7.70	0.0	3.2	-0.007	0.067	-13.63		28.61
CV-55R	7/1/2026 2:40:00 PM											
CV-55R	7/1/2026 2:40:14 PM	151.6	147.9	-13.56	-7.42	7.1	17.9	0.348	2.185	-15.64	-18.07	28.6
CV-55R	7/1/2026 2:42:13 PM	147.3	147.3	-6.40	-6.40	20.9	21.0	2.970	3.003	-18.07	-17.52	28.58
CV-55R	7/2/2026 11:47:37 AM	150.6	151.2	-2.19	-2.30	4.1	7.2	0.113	0.346	-16.06	-16.09	28.63
CV-55R	7/9/2026 8:59:26 AM	153.2	153.3	-2.99	-2.99	4.6	5.7	0.144	0.222	-17.18	-17.18	28.57
CV-55R	7/9/2026 9:05:00 AM											
CV-55R	7/9/2026 9:05:00 AM											
CV-55R	7/16/2026 9:15:15 AM	152.7	152.8	-3.50	-3.50	7.3	7.8	0.367	0.417	-16.48	-16.83	28.5
CV-55R	7/16/2026 9:20:00 AM											
CV-55R	7/22/2026 2:43:20 PM	152.3	152.2	-5.50	-5.52	4.1	3.9	0.116	0.101	-15.00	-15.66	28.59
CV-55R	7/22/2026 2:44:02 PM	151.9	152.3	-5.24	-5.24	2.1	4.1	0.029	0.112	-15.01	-15.85	28.59
CV-55R	7/30/2026 1:07:16 PM	152.0	152.1	-5.06	-5.05	6.2	6.9	0.259	0.319	-13.04	-13.56	28.6
CV-56D	7/29/2026 9:58:10 AM											
CV-56D	7/29/2026 9:59:59 AM	96.7	98.5	0.13	-0.01	0.7	1.9	0.010	0.077	-17.59	-17.48	28.57

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-56D	7/29/2026 10:03:44 AM	103.4	103.5	-0.02	-0.03	1.6	1.7	0.054	0.058	-17.48	-17.44	28.57
CV-56D	7/29/2026 1:40:00 PM											
CV-56D	7/29/2026 1:40:00 PM											
CV-56S	7/6/2026 9:52:49 AM	95.6	96.6	-6.88	-1.87	0.8	0.4	0.149	0.041	-18.06	-18.25	28.59
CV-56S	7/6/2026 9:55:21 AM	96.2	96.3	-0.24	-0.23	0.3	0.3	0.025	0.026	-17.30	-17.53	28.59
CV-56S	7/29/2026 10:14:57 AM											
CV-56S	7/29/2026 10:18:52 AM	102.3	102.2	-0.03	-0.03	0.5	0.5	0.031	0.028	-17.48	-17.44	28.56
CV-56S	7/29/2026 1:30:00 PM											
CV-56S	7/29/2026 1:50:00 PM											
CV-57R	7/6/2026 9:25:36 AM	122.1	122.0	-2.96	-2.94	4.0	3.8	0.336	0.304	-11.51	-11.21	28.55
CV-79R	7/6/2026 10:30:12 AM	136.9	125.9	-16.29	-4.92	15.3	15.9	0.589	0.601	-16.32	-17.09	28.55
CV-79R	7/6/2026 10:30:37 AM	124.7	124.3	-4.59	-4.59	16.9	17.9	0.682	0.763	-16.13	-16.41	28.58
CV-94	7/6/2026 9:22:39 AM	118.6	119.0	-12.08	-12.08	5.0	3.7	0.166	0.091	-14.22	-14.20	28.55
CV-95	7/6/2026 9:27:21 AM	99.8	100.7	-0.47	-0.47	1.1	0.8	0.025	0.013	-10.43	-10.29	28.55
CV-99	7/9/2026 7:45:00 AM											
CV-99	7/9/2026 7:45:00 AM											
CV-99	7/14/2026 1:09:14 PM	102.3	103.7	-11.63	-11.55	1.6	1.1	0.057	0.027	-11.42	-11.38	28.62
CV-99	7/23/2026 2:19:12 PM	108.9	109.2	-6.40	-5.56	0.5	2.1	0.004	0.094	-6.31	-5.25	28.55
CV-99	7/23/2026 2:19:57 PM	109.4	109.4	-5.89	-6.14	2.6	2.5	0.147	0.128	-5.75	-5.92	28.55
D-02	7/9/2026 10:23:12 AM	97.1	97.3	-16.21	-16.20	2.3	2.2	0.007	0.006	-16.28	-16.34	28.69
D-03	7/9/2026 10:26:06 AM	97.6	97.8	-4.71	-4.73	11.3	11.3	0.107	0.107	-5.01	-5.03	28.69
D-04	7/9/2026 10:28:32 AM	94.8	95.0	-19.97	-19.87	4.3	3.7	0.024	0.018	-19.90	-19.82	28.69
D-09	7/7/2026 12:07:51 PM	116.5	116.6	-12.49	-12.51	25.2	24.8	0.847	0.816	-12.88	-13.01	28.74
D-10	7/7/2026 11:45:01 AM	106.6	106.7	-15.77	-15.77			0.241	0.243	-16.02	-16.03	28.74
FP-001	7/6/2026 1:36:18 PM	94.0	94.1	-0.10	-0.11	7.6	7.7	0.349	0.361	-10.42	-10.65	28.58
FP-002	7/6/2026 1:39:31 PM	93.7	94.0	-0.09	-0.09	5.3	5.3	0.562	0.568	-7.87	-7.98	28.58
FP-003	7/6/2026 1:42:36 PM	92.2	92.4	-0.13	-0.10	2.3	2.2	0.526	0.519	-8.06	-7.96	28.58
FP-005	7/8/2026 1:43:07 PM	98.6	98.6	-0.09	-0.10	5.0	5.0	2.637	2.686	-8.68	-8.97	28.58
FP-006	7/6/2026 8:00:51 AM	87.8	87.8	-1.48	-1.48	1.4	1.8	0.039	0.062	-6.67	-7.56	28.55
FP-008	7/6/2026 7:43:30 AM	99.5	99.1	-3.47	-2.73	1.1	0.7	0.306	0.120	-9.34	-10.38	28.55
FP-009	7/2/2026 1:39:59 PM	107.0	106.9	-0.59	-0.61	3.0	2.9	0.180	0.174	-5.84	-6.66	28.58
FP-010	7/14/2026 10:08:14 AM	117.1	117.1	-0.28	-0.25	11.5	11.3	2.786	2.678	-8.04	-8.20	28.61
FP-011	7/8/2026 1:16:44 PM	94.6	94.5	-1.20	-1.10	3.5	3.6	0.246	0.256	-11.30	-11.59	28.58
FP-012	7/1/2026 8:59:25 AM	70.4	70.6	-0.36	-0.36	0.4	0.2	0.002	0.001	-12.90	-12.81	28.51
FP-013	7/1/2026 9:24:19 AM	77.6	77.6	-0.58	-0.58	15.4	15.4	4.734	4.707	-12.77	-13.06	28.51
FP-014	7/14/2026 10:13:32 AM	111.0	111.0	-1.98	-1.95	3.9	3.9	1.638	1.624	-3.52	-3.68	28.62

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
FP-015	7/14/2026 10:16:00 AM	98.9	101.8	-1.85	-1.88	1.1	1.1	0.026	0.024	-2.99	-3.05	28.62
FP-016	7/6/2026 7:58:28 AM	80.0	81.5	-1.43	-1.41	0.1	0.1	0.001	0.004	-7.38	-7.22	28.55
FP-017	7/8/2026 2:31:56 PM	103.9	103.7	-0.62	-0.61	0.0	0.0	-0.020	-0.018	-0.43		28.48
FP-018	7/8/2026 10:37:14 AM	92.0	92.5	-2.29	-2.80	5.2	7.3	0.549	1.084	-11.39	-11.43	28.58
FP-019	7/1/2026 2:11:35 PM	84.5	84.8	-0.31	-0.30	2.8	2.9	0.153	0.165	-12.11	-12.31	28.58
FP-020	7/1/2026 2:26:14 PM	87.7	87.7	-5.37	-5.35			0.117	0.000	-11.49	-11.59	28.55
FP-021	7/1/2026 2:37:18 PM	100.3	100.4	-8.71	-8.38			0.000	0.000	-8.79	-8.56	28.56
FP-022	7/1/2026 2:31:49 PM	95.1	95.5	-10.97	-7.66			0.018	0.000	-10.95	-11.04	28.57
FP-023	7/1/2026 2:40:21 PM	89.0	89.9	-0.27	-0.27	1.1	0.7	0.023	0.010	-0.30	-0.34	28.55
FP-024	7/2/2026 2:14:20 PM	97.0	97.0	-0.78	-0.77	1.7	1.8	0.061	0.064	-11.36	-11.40	28.59
FP-025	7/2/2026 2:18:43 PM	85.8	86.0	-3.89	-3.33	1.6	1.3	0.049	0.036	-11.21	-11.14	28.58
FP-026	7/2/2026 2:27:09 PM	99.9	99.8	-8.53	-8.69			8.432	8.443	0.08	0.06	28.58
FP-027	7/14/2026 9:07:07 AM	94.0	94.1	-8.66	-8.63	20.3	20.4	8.610	8.686	0.01	0.01	28.62
FP-028	7/14/2026 9:09:50 AM	105.7	105.9	-1.10	-1.10	2.9	2.8	0.171	0.162	-10.35	-10.07	28.62
FP-029	7/8/2026 10:43:57 AM	112.9	115.6	-0.46	-0.46	19.1	19.1	0.470	0.470	0.21	0.21	28.58
FP-029	7/8/2026 2:35:22 PM	108.9	108.9	-0.15	-0.14	0.0	0.0	-0.162	-0.160	-0.13		28.49
FP-030	7/1/2026 2:01:04 PM	83.5	83.5	-0.56	-0.56	14.2	14.5	4.017	4.195	-11.87	-11.76	28.57
FP-031	7/14/2026 9:20:58 AM	96.0	96.7	-2.53	-2.57	0.2	0.1	0.008	0.002	-9.73	-10.17	28.62
FP-032	7/1/2026 1:50:54 PM	85.8	85.9	-7.23	-7.15	5.8	5.0	3.546	2.624	-11.44	-11.73	28.56
FP-033	7/1/2026 1:45:21 PM	82.5	82.4	-0.07	-0.06	0.3	0.3	0.002	0.002	-0.81	-1.09	28.57
FP-034	7/14/2026 9:24:45 AM	94.6	94.6	-0.19	-0.18	6.4	6.3	0.818	0.811	-10.09	-10.19	28.62
FP-035	7/1/2026 1:36:10 PM	82.1	82.4	-3.75	-3.13	5.7	4.9	0.658	0.487	-11.47	-11.36	28.55
FP-036	7/1/2026 1:31:08 PM	85.6	85.8	-1.65	-1.35	3.0	2.6	2.316	1.725	-10.54	-10.69	28.55
FP-037	7/1/2026 10:17:41 AM	75.0	74.8	-0.57	-0.57			0.013	0.003	-13.31	-13.23	28.54
FP-038	7/7/2026 9:43:23 AM	87.6	87.6	-0.44	-0.55	7.2	8.9	1.038	1.571	-5.72	-7.26	28.59
FP-038	7/7/2026 10:42:42 AM	96.0	96.0	-0.42	-0.41	0.8	0.6	0.014	0.007	-2.26	-2.17	28.62
FP-039	7/7/2026 9:45:39 AM	85.9	86.0	-0.69	-0.66	18.8	18.6	7.099	7.001	-6.63	-6.55	28.58
FP-040	7/7/2026 10:31:45 AM	108.7	109.1	-0.06	-0.04	12.8	16.4	0.374	0.611	-0.10	-0.32	28.62
FP-041	7/7/2026 10:50:30 AM	91.5	91.6	-0.26	-0.24	12.0	11.6	2.888	2.729	-7.50	-7.31	28.63
FP-042	7/30/2026 10:53:26 AM	97.9	99.2	-0.25	-0.25	13.2	13.2	3.554	3.554	-3.39	-3.39	28.73
FP-043	7/7/2026 10:47:36 AM	96.0	96.0	-0.31	-0.31	17.5	17.3	6.270	6.132	-8.32	-8.14	28.62
FP-044	7/7/2026 10:44:58 AM	95.7	95.9	-0.09	-0.09	6.0	5.9	0.738	0.701	-8.12	-8.21	28.63
FP-045	7/16/2026 2:11:52 PM	122.5	122.6	-0.53	-0.57	14.3	14.8	4.411	4.720	-9.91	-10.54	28.51
FP-046	7/8/2026 1:39:49 PM	92.6	92.7	-0.39	-0.26	9.9	10.8	2.001	2.346	-3.13	-3.61	28.58
FP-046	7/16/2026 4:36:27 PM	99.2	99.0	-0.42	-0.43	14.0	14.2	4.676	4.817	-7.02		28.35

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
FP-047	7/8/2026 1:46:52 PM	97.7	97.8	-0.08	-0.04	3.4	3.4	0.236	0.229	0.00	0.00	28.59
FP-050	7/2/2026 3:09:30 PM	92.7	91.9	-0.43	-0.36	8.9	4.0	0.500	0.102	-11.68		28.48
FP-051	7/2/2026 3:00:23 PM	96.1	96.5	-0.49	-0.39	0.0	0.0	-0.614	-0.532	-11.17		28.47
FP-052	7/6/2026 1:09:00 PM	97.3	97.2	-0.14	-0.15	10.5	10.5	2.223	2.233	-10.28		28.47
FP-053	7/6/2026 12:56:22 PM	104.9	103.8	-2.33	-0.40	1.9	0.9	0.076	0.018	-9.60		28.46
FP-054	7/2/2026 3:35:07 PM	95.2	94.8	-0.97	-0.65	0.0	0.0	-1.457	-2.374	-6.58		28.46
FP-055	7/6/2026 3:04:30 PM	106.0	108.9	-0.44	-0.34	15.3	8.5	4.833	1.483	-11.11		28.46
FP-056	7/6/2026 3:49:54 PM	106.8	106.7	-0.60	-0.40	20.9	11.4	9.074	2.699	-11.44		28.46
FP-057	7/2/2026 10:40:18 AM	83.7	83.7	-0.87	-0.86	13.7	13.7	3.531	3.528	-14.94		28.7
FP-058	7/2/2026 10:43:14 AM	81.7	81.8	-1.12	-0.93			-1.901	-1.324			28.49
FP-059	7/2/2026 1:16:15 PM	95.7	95.7	-0.33	-0.45	3.6	16.7	0.238	5.262	-14.37		28.49
FP-060	7/2/2026 1:11:41 PM	86.5	86.0	-0.59	-0.36	9.8	5.2	1.858	0.522	-15.30		28.49
FP-061	7/6/2026 7:53:11 AM	144.8	144.3	-1.35	-1.10	5.9	6.2	0.768	0.840	-6.55	-6.61	28.55
H-01 (EXP-01	7/13/2026 8:10:30 AM	82.3	82.6	-4.28	-4.28			4.238	4.240	-9.81	-9.89	28.69
H-01 (EXP-01	7/22/2026 9:38:27 AM	108.0	108.1	-3.13	-3.13			3.095	3.095	-13.34	-13.42	28.71
H-01 (EXP-01	7/27/2026 1:53:35 PM	112.6	113.1	-2.17	-2.17			2.120	2.116	-12.47	-12.57	28.69
H-02 (EXP-02	7/13/2026 7:58:53 AM	100.0	100.0	-5.04	-5.03			5.056	4.979	-9.88	-9.84	28.66
H-02 (EXP-02	7/22/2026 9:42:16 AM	118.6	118.4	-4.25	-4.25			4.213	4.211	-12.86	-12.90	28.7
H-02 (EXP-02	7/27/2026 1:51:19 PM	120.1	120.0	-3.36	-3.36			3.352	3.342	-13.41	-13.49	28.69
H-03 (EXP-03	7/13/2026 8:01:45 AM	114.2	114.0	-9.73	-9.73			9.631	9.671	-9.85	-9.89	28.66
H-03 (EXP-03	7/22/2026 9:44:31 AM	121.2	121.2	-12.79	-12.79			13.008	13.000	-12.42	-12.41	28.7
H-03 (EXP-03	7/27/2026 1:48:20 PM	120.5	120.7	-11.10	-10.98			11.124	11.046	-11.17	-11.22	28.69
H-04 (EXP-04	7/13/2026 8:07:00 AM	131.7	129.9	-3.03	-0.87			3.014	0.870	-9.69	-9.86	28.67
H-04 (EXP-04	7/13/2026 8:07:32 AM	129.8	129.8	-0.37	-0.38			0.379	0.375	-9.85	-9.89	28.69
H-04 (EXP-04	7/22/2026 9:47:27 AM	134.7	134.0	5.67	-0.06			0.000	0.075	-12.84	-12.90	28.79
H-04 (EXP-04	7/22/2026 9:50:13 AM	132.8	137.1	-0.08	-0.05			0.099	0.067	-12.61	-12.61	28.79
H-08 (EXP-08	7/1/2026 10:41:09 AM	122.9	123.0	-12.76	-12.76			12.698	12.710	-13.99	-13.99	28.61
H-08 (EXP-08	7/22/2026 10:11:44 AM	121.9	122.1	-9.11	-9.11			9.558	9.499	-8.80	-8.68	28.77
H-10 (EXP-10	7/1/2026 10:32:28 AM	129.9	130.0	-9.44	-9.44			9.509	9.522	-14.12	-13.97	28.6
H-10 (EXP-10	7/31/2026 8:12:39 AM	130.7	130.2	-11.14	-1.51			11.263	1.504	-15.14	-14.43	28.63
H-101W-PLR	7/3/2026 10:24:03 AM	94.1	94.1	-9.83	-9.48	15.7	15.6	0.314	0.310	-10.13	-9.98	28.74
H-101W-PLR	7/3/2026 10:25:22 AM	94.4	94.3	-9.48	-9.48	15.8	14.9	0.317	0.281	-9.45	-9.34	28.74
H-102A	7/3/2026 10:16:34 AM	93.4	81.9	-8.72	-9.09	6.4	6.5	0.255	0.256	-8.62	-9.04	28.74
H-1401W	7/3/2026 10:18:08 AM	92.2	92.6	-9.71	-9.40	7.1	6.6	0.315	0.268	-9.68	-9.49	28.74

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
H-1404C	7/13/2026 11:16:46 AM	123.4	122.8	-0.39	-0.38	1.2	1.4	0.031	0.040	-11.03	-11.26	28.58
H-1404C	7/31/2026 9:11:09 AM	114.4	114.6	-0.32	-0.32	3.0	3.4	0.191	0.242	-11.57	-11.34	28.67
H-1405C	7/3/2026 9:19:48 AM	91.0	90.2	-0.89	-0.50	3.3	2.3	0.064	0.032	-1.97	-1.74	28.63
H-1405C	7/20/2026 10:05:45 AM	96.2	97.0	-0.23	-0.30	0.8	0.8	0.004	0.004	0.38	0.14	28.65
H-1406W	7/3/2026 7:52:35 AM	71.9	73.7	-3.67	-1.61	5.8	4.2	0.199	0.103	-12.78	-12.86	28.67
H-1406W	7/20/2026 12:49:05 PM	100.2	100.8	-10.66	-10.10	1.8	2.3	0.020	0.032	-10.13	-9.74	28.68
H-1408CR	7/1/2026 8:42:10 AM	135.0	129.8	-0.18	-0.10	2.4	1.9	0.647	0.400	-18.19		28.6
H-1408CR	7/1/2026 8:44:56 AM	120.8	119.9	-0.08	-0.08	1.9	1.8	0.386	0.373	-18.34		28.6
H-1408E	7/2/2026 12:38:06 PM	107.7	110.8	-0.03	-0.12	1.1	3.2	0.024	0.210	-11.91	-11.96	28.57
H-1408E	7/2/2026 12:40:12 PM	111.0	110.8	-0.06	-0.05	2.2	2.2	0.104	0.104	-11.39	-11.70	28.57
H-1408E	7/2/2026 12:41:18 PM	111.1	111.0	-0.07	-0.08	2.2	2.2	0.099	0.104	-11.98	-12.04	28.57
H-1408E	7/2/2026 1:12:43 PM	113.8	113.8	-0.08	-0.07	2.3	2.3	0.107	0.109	-11.50	-11.39	28.57
H-1408E	7/16/2026 1:43:57 PM	122.7	122.6	-0.04	-0.04	0.9	1.1	0.018	0.026	-10.77	-11.07	28.42
H-1408E	7/16/2026 1:49:15 PM	122.2	123.4	-0.03	-0.13	1.2	2.8	0.170	0.834	-11.09	-11.21	28.43
H-1408E	7/16/2026 1:50:44 PM	123.9	124.0	-0.10	-0.08	2.3	2.1	0.578	0.506	-11.03	-11.09	28.42
H-1408E	7/16/2026 1:51:40 PM	123.8	123.9	-0.08	-0.09	2.2	2.2	0.509	0.531	-11.21	-11.12	28.44
H-1408W	7/3/2026 8:28:12 AM	106.5	103.2	-2.02	-0.08	5.7	3.4	0.042	0.015	-12.85	-12.20	28.7
H-1408W	7/3/2026 8:30:59 AM	108.5	107.3	-0.24	-0.24	4.7	4.6	0.028	0.027	-13.24	-13.29	28.7
H-1409N	7/6/2026 10:40:14 AM	116.1	116.7	-0.38	-0.88	0.0	0.3	-0.127	0.028	-12.31		28.47
H-1409N	7/16/2026 3:17:34 PM	121.3	121.3	-0.50	-0.49	0.0	0.0	-0.084	-0.071	-13.85		28.35
H-1410S	7/1/2026 8:07:41 AM	73.6	73.7	-14.65	-14.64	0.0	0.0	-0.031	-0.037	-15.06		28.65
H-1563N	7/7/2026 9:58:28 AM	119.6	119.6	-3.98	-3.99	5.7	6.1	0.210	0.241	-4.60	-4.59	28.59
H-1563N	7/16/2026 2:29:54 PM	122.8	122.7	-5.46	-4.88	7.8	3.2	0.391	0.065	-6.42	-6.84	28.51
H-1563S	7/3/2026 9:15:46 AM	91.6	91.6	-0.48	-0.40	0.7	0.5	0.047	0.025	-9.74	-10.67	28.63
H-1563S	7/20/2026 10:01:37 AM	94.3	94.4	-0.37	-0.37	0.2	0.3	0.006	0.007	-11.29	-11.29	28.65
H-1565E	7/2/2026 10:08:57 AM	102.3	101.5	-0.43	-0.43	1.0	1.5	0.006	0.013	-12.08	-12.20	28.53
H-1565E	7/22/2026 8:15:26 AM	106.2	107.2	-0.14	-0.32	2.3	0.7	0.031	0.003	-9.21	-8.91	28.59
H-1568N	7/2/2026 1:23:44 PM	112.2	114.0	-0.85	-1.12	3.7	5.0	0.285	0.533	-11.22	-11.63	28.57
H-1568N	7/2/2026 1:25:23 PM	114.3	114.4	-1.16	-1.17	5.1	5.4	0.539	0.605	-11.20	-11.16	28.57
H-1568N	7/16/2026 1:07:53 PM	120.0	120.0	-1.15	-1.24	3.8	4.6	0.309	0.444	-11.20	-11.05	28.43

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
H-1568N	7/16/2026 1:19:13 PM	118.3	120.0	-1.02	-1.40	3.7	5.3	0.296	0.598	-11.23	-11.41	28.42
H-1568N	7/16/2026 1:19:55 PM	120.1	120.1	-1.40	-1.42	5.1	5.2	0.552	0.573	-11.11	-11.45	28.45
H-1571S	7/1/2026 10:25:36 AM	85.8	85.9	-0.65	-0.64	0.0	0.0	-0.044	-0.044	-20.07		28.63
H-1572N	7/6/2026 10:41:59 AM	148.2	139.5	-3.29	-0.94	20.9	1.0	9.923	0.022	-15.38	-15.92	28.55
H-1572N	7/6/2026 10:43:57 AM	134.8	132.1	-0.82	-0.55	2.8	0.8	0.166	0.015	-15.82	-15.89	28.53
H-1572N	7/6/2026 10:44:40 AM	129.8	129.4	-0.48	-0.48	1.0	1.0	0.021	0.020	-15.80	-15.88	28.55
H-1572S	7/15/2026 1:05:33 PM	117.2	117.3	-0.92	-0.90	8.2	8.0	0.155	0.150	-14.57	-14.50	28.58
H-1574N	7/13/2026 9:47:50 AM	101.7	101.9	-0.07	-0.06	6.5	8.6	0.052	0.093	-3.18	-3.26	28.7
H-1753N	7/1/2026 2:14:02 PM	90.2	90.4	-0.16	-0.14	4.1	3.2	0.036	0.023	-12.01	-11.07	28.58
H-1753N	7/22/2026 1:43:28 PM	101.7	101.8	-0.16	-0.17	1.9	1.8	0.008	0.008	-10.45	-10.73	28.61
H-1753S	7/7/2026 9:40:17 AM	115.7	115.9	-3.95	-3.81	3.9	3.9	0.320	0.316	-6.93	-6.66	28.56
H-1753S	7/16/2026 2:36:10 PM	118.2	118.1	-4.35	-3.86	4.6	4.0	0.453	0.347	-7.40	-7.31	28.5
H-1756S	7/3/2026 9:02:07 AM	123.8	124.0	-0.40	-0.39	3.2	3.1	0.013	0.013	-11.67	-10.44	28.65
H-1756S	7/28/2026 1:12:47 PM	125.5	125.5	-0.33	-0.34	2.8	3.9	0.011	0.020	-10.44	-10.82	28.56
H-1757S	7/3/2026 9:22:05 AM	88.7	89.9	-0.77	-0.53	5.9	6.8	0.076	0.101	-7.04	-8.17	28.63
H-1757S	7/20/2026 10:13:09 AM	96.9	96.9	-0.46	-0.47	2.2	2.3	0.011	0.012	-9.83	-9.07	28.65
H-1760S	7/7/2026 12:16:26 PM	117.5	117.7	-2.36	-2.34	3.6	3.6	0.085	0.084	-12.89		28.48
H-1760S	7/22/2026 9:58:10 AM	119.9	119.9	-0.74	-0.76	2.9	3.4	0.055	0.074	-8.43	-9.30	28.62
H-1762N	7/1/2026 1:22:19 PM	111.6	111.3	-0.32	-0.30	5.7	5.7	3.495	3.552	-12.56	-12.53	28.53
H-1762N	7/16/2026 2:13:18 PM	115.6	115.6	-0.23	-0.24	5.4	5.5	3.131	3.266	-11.13	-11.77	28.42
H-1762N	7/16/2026 2:16:39 PM	115.8	115.9	-0.27	-0.26	6.0	6.0	0.755	0.751	-11.47	-11.35	28.42
H-1763N	7/7/2026 2:30:01 PM	110.9	115.3	0.01	-0.16	0.8	8.0	0.005	0.500	-12.23		28.44
H-1763N	7/7/2026 2:31:23 PM	117.4	117.5	-0.29	-0.28	7.9	7.9	0.472	0.474	-12.28		28.44
H-1763S	7/6/2026 12:41:01 PM	112.1	112.2	-0.21	-0.20	1.5	1.1	0.003	0.001	-13.60	-13.49	28.56
H-1764N	7/6/2026 12:28:11 PM	120.7	120.7	-6.05	-6.05	7.2	7.2	1.133	1.130	-14.63	-14.73	28.51
H-1764S	7/1/2026 10:17:27 AM	89.2	89.3	-1.16	-1.13	0.0	0.0	-0.096	-0.086	-20.18		28.62
H-1767N	7/9/2026 1:46:00 PM	105.4	106.1	-1.41	-1.43	20.2	19.2	0.927	0.843	-18.21	-18.40	28.63
H-1769N	7/1/2026 9:05:19 AM	87.3	88.2	-0.52	-0.59	15.9	14.0	0.646	0.507	-13.58	-13.50	28.51
H-1769N	7/16/2026 10:27:47 AM	115.4	115.4	-0.39	-0.38	4.5	4.9	0.055	0.066	-9.60	-9.55	28.47
H-1770N	7/1/2026 9:15:45 AM	99.9	100.0	-0.97	-0.94	8.6	9.4	1.503	1.833	-13.02	-13.08	28.53
H-1770N	7/16/2026 10:37:30 AM	111.3	111.3	-0.78	-0.77	10.8	8.9	2.476	1.661	-10.51	-11.21	28.48
H-1770S	7/3/2026 7:24:24 AM	70.9	72.0	-0.55	-0.54	1.9	1.8	0.069	0.063	-9.90	-10.03	28.61
H-1770S	7/20/2026 10:19:12 AM	100.1	100.2	-0.56	-0.56	0.7	0.7	0.011	0.009	-9.93	-10.18	28.66
H-1771A	7/6/2026 2:01:03 PM	111.8	111.8	-0.46	-0.42	8.5	8.6	0.451	0.462	-3.56	-3.44	28.57
H-1771B	7/6/2026 9:52:22 AM	109.9	111.9	-0.70	-0.98	1.1	1.9	0.024	0.079	-13.40	-12.87	28.55

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
H-1774N	7/1/2026 9:32:28 AM	116.3	116.3	-1.53	-1.38	12.3	11.2	3.196	2.680	-13.00	-13.03	28.54
H-1774N	7/16/2026 10:45:57 AM	119.0	119.0	-0.72	-0.70	10.7	10.3	2.461	2.239	-10.95	-10.50	28.49
H-1801S	7/6/2026 10:55:07 AM	106.8	103.8	-2.33	-1.48	2.6	1.5	0.139	0.047	-16.04	-15.87	28.55
H-1802S	7/6/2026 10:35:07 AM	139.6	133.7	-4.79	-0.69	74.8	3.6	7.731	0.017	-16.29	-16.84	28.55
H-1802S	7/6/2026 10:36:34 AM	132.0	128.4	-0.68	-0.49	10.9	2.9	0.157	0.011	-16.25	-16.31	28.55
H-1802S	7/6/2026 10:38:21 AM	124.1	123.3	-0.41	-0.40	3.0	3.0	0.012	0.012	-15.23	-16.50	28.55
H-1803N-PLF	7/6/2026 9:40:00 AM											
H-1803N-PLF	7/6/2026 9:40:00 AM											
H-1803N-PLF	7/6/2026 9:43:25 AM	198.0	197.6	-8.82	-8.42	76.5	75.1	8.986	8.630	-1.01	-1.01	28.57
H-1803N-PLF	7/13/2026 9:30:31 AM	197.3	197.2	-4.64	-4.89	55.5	56.1	4.630	4.727	0.34	0.32	28.6
H-1803N-PLF	7/13/2026 9:40:00 AM											
H-1803N-PLF	7/20/2026 9:30:00 AM											
H-1803N-PLF	7/20/2026 9:31:03 AM	197.6	197.4	-6.93	-7.08	69.5	70.4	7.337	7.546	0.32	0.34	28.6
H-1803N-PLF	7/27/2026 9:23:26 AM	197.8	197.6	-4.84	-5.05	56.4	59.8	4.780	5.388	0.34	0.34	28.6
H-1804B	7/2/2026 1:22:54 PM	108.2	108.4	-13.51	-15.10	13.5	14.0	1.211	1.303	-15.55		28.48
H-1804N	7/7/2026 9:04:56 AM	100.8	100.9	-2.58	-2.56	1.5	1.6	0.047	0.054	-6.13	-6.21	28.58
H-1804S	7/6/2026 12:30:07 PM	114.6	114.7	-8.03	-7.70	3.2	4.6	0.064	0.136	-12.74	-12.34	28.51
H-1805A	7/2/2026 11:02:16 AM	106.3	106.0	-2.50	-2.42	3.2	2.4	1.084	0.641	-15.91		28.49
H-1805A	7/21/2026 10:19:00 AM	104.7	104.7	-2.46	-2.36	22.7	8.2	0.659	0.086	-13.38	-12.87	28.61
H-1805B	7/6/2026 12:07:13 PM	97.2	97.5	-0.06	-0.06	0.8	0.8	0.012	0.012	-18.00	-18.59	28.52
H-1805S	7/6/2026 12:19:58 PM	132.5	127.5	-6.45	-3.89	10.2	9.5	0.253	0.216	-16.84	-16.99	28.55
H-1805S	7/6/2026 12:20:18 PM	127.1	126.2	-3.55	-3.55	8.7	9.0	0.181	0.192	-17.04	-17.01	28.55
H-1806A	7/2/2026 11:16:43 AM	103.9	107.8	-0.61	-0.81	2.0	4.9	0.073	0.474	-16.70		28.51
H-1806B	7/6/2026 10:48:27 AM	91.5	91.6	-0.24	-0.24	1.8	1.7	0.062	0.058	-15.71	-15.69	28.52
H-1806N	7/7/2026 9:27:30 AM	129.9	129.7	-1.32	-1.31	2.3	5.8	0.007	0.045	-11.81	-11.98	28.59
H-1806S	7/6/2026 10:19:10 AM	124.3	123.7	-0.70	-0.40	16.7	16.2	0.657	0.616	-16.78	-17.04	28.62
H-1807A	7/6/2026 9:20:28 AM	118.0	118.8	-11.60	-11.77	39.1	37.8	2.056	1.916	-14.24	-14.11	28.55
H-1807N	7/7/2026 9:46:22 AM	97.6	97.7	-1.77	-1.78	1.0	1.7	0.006	0.018	-9.02	-8.65	28.62

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
H-1807N	7/7/2026 9:47:04 AM	97.8	97.8	-1.82	-1.81	1.5	1.5	0.013	0.014	-8.58	-8.63	28.62
H-1807S	7/6/2026 9:39:03 AM	95.8	96.4	-14.47	-12.08	12.3	11.5	0.196	0.169	-16.03	-16.10	28.59
H-1952S	7/6/2026 12:43:31 PM	118.1	118.1	-1.03	-0.92	8.7	7.8	1.599	1.288	-9.31		28.51
H-1952S	7/29/2026 10:11:32 AM	119.2	119.1	-1.13	-1.13	9.2	9.1	1.794	1.781	-13.12	-13.29	28.45
H-1955C	7/2/2026 10:55:18 AM	80.5	80.7	-0.70	-0.58	6.5	3.2	0.808	0.196	-16.37		28.49
H-1955C	7/2/2026 10:57:58 AM	80.9	80.9	-0.28	-0.29	3.4	3.4	0.222	0.223	-16.37		28.49
H-1955C	7/21/2026 10:12:36 AM	92.3	92.3	-0.35	-0.35	1.6	1.7	0.054	0.055	-12.92	-12.71	28.62
H-1955N	7/7/2026 9:08:05 AM	97.0	97.2	-1.06	-1.25	6.2	8.4	0.235	0.432	-6.13	-5.92	28.58
H-1956B	7/2/2026 11:38:20 AM	119.4	119.4	-1.14	-1.00	6.2	5.0	0.096	0.064	-16.95		28.51
H-1956N	7/7/2026 9:20:39 AM	114.2	114.2	-3.14	-3.15	24.0	24.2	3.669	3.759	-7.02	-7.11	28.59
H-1956S	7/6/2026 10:23:58 AM	93.8	93.7	0.43	0.45	0.9	0.6	0.079	0.037	0.79	0.82	28.55
H-1956S	7/6/2026 10:24:22 AM	93.6	93.5	0.41	0.49	1.1	1.1	0.132	0.129	0.83	0.78	28.55
H-1956S	7/23/2026 1:24:17 PM	123.4	120.8	-16.20	-15.86	6.2	1.2	4.451	0.152	-16.13	-16.91	28.58
H-1957B	7/2/2026 11:32:45 AM	109.7	110.1	-0.99	-0.90	27.4	24.2	4.437	3.460	-15.90		28.51
H-1957N	7/7/2026 9:33:09 AM	122.9	122.6	-2.50	-2.39	6.1	0.9	0.242	0.005	-11.43	-11.56	28.62
H-1957S	7/6/2026 10:57:07 AM	101.3	103.1	-0.83	-0.73	2.9	2.5	0.178	0.126	-16.02	-15.67	28.56
H-1958C	7/6/2026 9:18:24 AM	126.9	126.9	-5.55	-4.71	20.0	14.1	2.632	1.299	-10.59	-12.94	28.55
H-1958N	7/7/2026 9:38:14 AM	112.5	109.7	-3.76	-3.66	15.4	2.4	0.305	0.008	-7.64	-8.55	28.6
H-1958S	7/6/2026 9:35:13 AM	103.7	103.6	-0.70	-0.58	5.1	2.2	0.159	0.029	-15.47	-15.42	28.58
H-1958S	7/6/2026 9:35:55 AM	103.6	103.6	-0.55	-0.55	0.8	0.8	0.004	0.004	-15.82	-15.82	28.59
H-1962N	7/1/2026 9:18:59 AM	66.3	66.8	-1.62	-1.60			0.000	0.000	-12.88	-12.78	28.51
H-1962N	7/16/2026 10:40:44 AM	101.3	102.1	-0.88	-0.89			0.000	0.000	-10.59	-10.87	28.47
H-1963N	7/1/2026 9:02:32 AM	142.6	142.7	-0.78	-0.77	6.8	7.5	0.132	0.157	-13.42	-13.44	28.51
H-1963N	7/16/2026 10:24:18 AM	140.9	141.0	-0.63	-0.63	6.4	6.5	0.115	0.119	-10.50	-10.47	28.47
H-1966N	7/1/2026 9:42:22 AM	105.6	105.3	-0.44	-0.43	4.4	4.4	2.091	2.089	-5.96	-6.02	28.55
H-1966N	7/16/2026 10:50:23 AM	111.2	111.2	-0.57	-0.56	5.0	4.5	2.754	2.209	-7.20	-5.67	28.51
H-1967E	7/7/2026 11:48:29 AM	102.0	102.9	-15.48	-14.78	18.9	14.9	0.469	0.289	-15.33	-15.89	28.74

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
H-1967W	7/3/2026 9:51:34 AM	95.5	95.6	-7.26	-7.25	4.2	4.3	0.022	0.024	-7.51	-7.47	28.74
H-2050E	7/8/2026 11:01:21 AM	105.3	105.4	-17.19	-17.20	6.3	6.3	0.820	0.819	-17.96		28.77
H-2050W	7/8/2026 10:04:46 AM	107.6	107.6	-2.18	-1.88	6.5	4.9	0.885	0.497	-9.57	-9.68	28.74
H-2051W	7/3/2026 9:48:44 AM	89.5	89.6	-12.42	-13.68	14.5	17.4	0.265	0.383	-13.80	-14.30	28.74
H-2053E	7/9/2026 1:01:15 PM	121.6	121.7	-3.60	-2.32	32.3	22.5	1.276	0.615	-17.65		28.61
H-2053W	7/3/2026 10:13:44 AM	98.4	98.5	-8.05	-8.18	10.4	13.2	0.137	0.223	-8.09	-8.24	28.74
H-2055E	7/1/2026 9:16:30 AM	101.9	101.9	-0.85	-0.81	9.8	10.7	0.602	0.708	-12.63		28.62
H-2055E	7/31/2026 8:41:21 AM	100.3		-3.74		30.1		5.650		-19.86		28.74
H-2056B	7/7/2026 12:20:01 PM	98.2	98.4	-1.39	-1.39	1.9	2.1	0.072	0.089	-9.14	-9.11	28.77
H-2056W	7/3/2026 9:46:01 AM	104.4	104.5	-5.54	-5.70	59.3	61.8	4.533	4.926	-9.21	-9.84	28.74
H-2057E	7/7/2026 11:56:18 AM	128.1	128.0	-12.08	-10.74	31.5	30.3	1.342	1.238	-15.63	-15.03	28.76
H-2057W	7/3/2026 10:10:18 AM	90.2	89.9	-1.35	-1.88			1.179	2.009	-3.34	-2.94	28.74
H-2058E	7/7/2026 12:10:53 PM	112.1	112.1	-7.37	-7.32	49.2	48.6	3.160	3.083	-11.41	-11.29	28.74
H-2058W	7/3/2026 9:43:34 AM	99.6	99.6	-4.78	-4.20	29.4	15.6	1.095	0.305	-12.18	-12.82	28.74
H-2059E	7/9/2026 9:21:16 AM	126.3	126.2	-18.87	-18.91			0.097	0.099	-19.65	-19.61	28.69
H-2059W	7/3/2026 10:28:35 AM	123.4	123.3	-3.58	-3.02	39.7	34.9	3.729	2.869	-9.30	-7.42	28.72
H-2161E	7/9/2026 9:25:57 AM	124.7	125.4	-6.97	-4.79	55.3	41.6	4.102	2.300	-21.22	-12.35	28.66
H-2161W	7/3/2026 10:31:00 AM	105.4	105.5	-5.76	-5.43	45.0	44.7	2.609	2.565	-8.67	-8.61	28.73
H-2163C	7/1/2026 3:20:52 PM	91.2	91.2	-0.46	-0.46	2.1	2.1	0.485	0.490	-8.60		28.49
H-2163C	7/16/2026 2:04:14 PM	105.3	105.2	-0.68	-0.67	1.9	1.9	0.391	0.390	-15.91		28.42
H-2163W	7/3/2026 8:33:34 AM	120.1	120.0	-0.49	-0.49	8.8	8.7	0.487	0.485	-14.19	-14.52	28.68
H-2164E	7/1/2026 9:35:21 AM	121.5	121.4	-1.12	-1.08	0.0	0.0	-0.546	-0.571	-10.95		28.62
H-2164E	7/31/2026 12:51:18 PM	126.0	126.2	-4.77	-3.37	37.4	27.4	9.211	4.883	-13.56	-16.05	28.72
H-2165E	7/9/2026 1:29:58 PM	123.0	123.2	-1.52	-1.51	15.8	14.0	1.604	1.266	-15.56	-15.58	28.62
H-2165W	7/3/2026 8:04:21 AM	139.7	135.2	-1.05	-0.52	14.3	2.6	1.351	0.044	-11.40	-11.67	28.66

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
H-2165W	7/3/2026 8:04:45 AM	134.7	134.4	-0.47	-0.49	3.1	2.6	0.061	0.043	-11.06	-11.96	28.66
H-2165W	7/8/2026 7:15:00 AM											
H-2165W	7/8/2026 7:15:00 AM											
H-2165W	7/20/2026 10:29:00 AM	132.6	132.6	-0.34	-0.14	0.0	0.0	-0.173	-0.083	-10.84		28.68
H-2165W	7/20/2026 10:31:25 AM	132.3	132.4	-0.15	-0.10	0.0	0.0	-0.042	-0.031	-11.46		28.68
H-2166E	7/6/2026 9:13:00 AM	114.5	115.0	-0.32	-0.35	5.1	6.8	0.167	0.296	-7.84	-6.25	28.55
H-2168C	7/7/2026 12:56:37 PM	99.7	99.8	-13.83	-13.80	5.9	6.8	0.046	0.059	-15.22	-15.12	28.58
H-2168E	7/6/2026 11:08:12 AM	119.9	119.9	-0.18	-0.18	5.2	5.2	0.171	0.170	-16.10	-16.14	28.51
H-2169C	7/6/2026 12:03:22 PM	115.1	115.1	-2.58	-2.59	23.6	22.4	0.726	0.651	-17.74	-17.69	28.51
H-2169E	7/6/2026 11:05:54 AM	115.0	115.4	-0.09	-0.09	24.1	24.3	0.749	0.762	-15.78	-15.75	28.51
H-2170N	7/8/2026 12:44:54 PM	120.7	120.9	-4.57	-2.51	40.5	8.2	10.732	0.435	-14.36	-15.88	28.63
H-2170S	7/6/2026 9:39:55 AM	104.3	104.4	-2.57	-2.54	0.0	3.3	-0.010	0.066	-16.42		28.68
H-2171A	7/22/2026 10:35:38 AM	103.6	105.5	-0.49	-0.03	0.1	2.0	0.001	0.442	-0.31	-0.11	28.78
H-2171A	7/22/2026 10:37:21 AM	97.1	100.4	-0.05	-0.07	2.0	2.0	0.423	0.405	-0.01	-0.01	28.79
H-2171A	7/30/2026 10:41:52 AM	103.5	92.9	-0.80	-0.83	3.6	2.7	0.080	0.044	0.34	0.34	28.63
H-2171B	7/9/2026 11:42:06 AM	121.0	121.1	-3.52	-3.10	19.7	9.3	2.404	0.537	-11.73		28.53
H-2171N	7/9/2026 11:10:50 AM	117.7	118.0	-0.95	-0.80	7.1	4.7	0.313	0.135	-12.77		28.5
H-2171S	7/8/2026 12:41:11 PM	120.9	121.3	-3.83	-1.67	37.7	7.2	9.309	0.334	-12.30	-14.98	28.63
H-2272W	7/3/2026 8:41:27 AM	125.3	124.8	-0.68	-0.66	7.5	3.0	0.365	0.057	-13.75	-13.30	28.66
H-2272W	7/28/2026 10:14:33 AM	126.0	125.9	-0.62	-0.62	8.4	8.2	0.458	0.430	-14.49	-13.80	28.56
H-2273W	7/3/2026 8:59:47 AM	124.5	120.2	-0.71	-0.58	6.2	4.0	0.249	0.100	-10.55	-11.24	28.65
H-2273W	7/8/2026 7:30:00 AM											
H-2273W	7/8/2026 7:30:00 AM											
H-2273W	7/28/2026 9:48:03 AM	91.7	91.9	-0.51	-0.51	2.7	2.6	0.043	0.042	-12.61	-13.21	28.53
H-2274B	7/6/2026 10:30:01 AM	104.9	104.9	-4.03	-4.03	7.4	7.5	0.140	0.144	-13.46		28.5
H-2274B	7/16/2026 3:08:24 PM	110.7	110.8	-3.00	-2.99	6.7	6.7	0.117	0.119	-12.94		28.38
H-2274W	7/3/2026 9:05:07 AM	102.2	101.6	-0.57	-0.28	3.2	5.8	0.062	0.206	-10.21	-9.92	28.65
H-2274W	7/28/2026 1:09:51 PM	99.0	98.9	-0.43	-0.43	0.9	0.6	0.005	0.002	-9.18	-9.26	28.56
H-2275E	7/6/2026 12:38:37 PM	124.1	123.3	-1.00	-0.85	2.7	0.7	0.045	0.003	-13.58	-13.31	28.56
H-2275W	7/3/2026 8:48:18 AM	130.6	129.5	-1.46	-1.17	23.4	3.0	3.570	0.060	-15.08	-12.64	28.63
H-2275W	7/3/2026 8:48:42 AM	129.3	129.1	-1.15	-1.14	4.2	4.2	0.112	0.116	-12.95	-14.43	28.63
H-2275W	7/20/2026 1:35:47 PM	129.1	129.2	-0.16	-0.21	6.1	6.2	0.239	0.251	-10.72	-11.19	28.62
H-2276A	7/7/2026 12:12:40 PM	114.6	114.6	-8.44	-5.99	19.5	14.5	0.857	0.472	-9.16		28.51

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
H-2276A	7/19/2026 1:13:15 PM	115.6	115.6	-5.54	-5.62	21.3	19.6	0.596	0.505	-10.19	-10.30	28.56
H-2276B	7/6/2026 10:36:34 AM	118.5	118.8	-4.43	-5.10	25.7	30.0	1.418	1.938	-12.39		28.48
H-2276B	7/16/2026 3:13:23 PM	119.4	119.7	-6.48	-6.93	34.1	36.3	2.541	2.881	-13.43		28.36
H-2276E	7/6/2026 12:16:34 PM	107.4	110.0	-0.57	-0.52	8.7	3.0	0.097	0.011	-16.97	-16.87	28.55
H-2276W	7/3/2026 9:13:09 AM	95.8	93.3	-4.97	-4.22	7.2	5.9	0.318	0.211	-10.67	-10.69	28.63
H-2276W	7/20/2026 10:15:45 AM	103.4	103.8	-5.18	-5.06	1.3	1.1	0.011	0.007	-11.47	-11.38	28.65
H-2277A	7/7/2026 9:06:50 AM	94.8	95.0	-1.57	-1.59	3.0	3.0	0.054	0.055	-8.40	-9.21	28.55
H-2277A	7/16/2026 2:02:32 PM	103.3	103.4	-10.86	-10.44	1.6	2.6	0.017	0.044	-10.42	-10.08	28.48
H-2277B	7/2/2026 1:33:25 PM	118.1	118.1	-2.16	-2.19	4.9	6.7	0.152	0.287	-12.26	-12.96	28.57
H-2277B	7/7/2026 12:32:31 PM	118.0	118.0	-2.09	-2.08	6.6	6.6	0.263	0.262	-12.02		28.47
H-2277B	7/22/2026 9:37:54 AM	112.1	112.0	-4.50	-2.81	0.0	1.0	0.001	0.281	-11.06	-11.00	28.61
H-23 (EXP-23	7/9/2026 11:33:58 AM	103.6	103.4	-9.77	-9.93	0.0	0.0	-0.001	-0.002	-13.61		28.52
H-2301E	7/9/2026 9:01:57 AM	114.5	114.6	-1.23	-1.11	24.1	17.5	0.746	0.394	-19.40	-18.79	28.84
H-2301W	7/8/2026 12:56:38 PM	104.6	104.5	-14.05	-14.06	0.2	0.3	0.007	0.011	-15.10		28.73
H-2302C	7/7/2026 12:51:29 PM	122.2	122.5	-0.25	-0.38	9.6	12.7	0.213	0.376	-10.47	-11.04	28.77
H-2302E	7/8/2026 10:48:12 AM	100.0	100.0	-13.82	-13.84	8.8	8.8	0.091	0.090	-14.95		28.77
H-2303E	7/8/2026 10:51:22 AM	96.8	96.7	-12.26	-13.25	2.4	2.8	0.007	0.009	-13.98		28.79
H-2303N	7/7/2026 12:58:06 PM	103.8	103.9	-2.72	-2.50	13.4	10.7	3.744	2.350	-14.99	-15.02	28.74
H-2303S	7/8/2026 12:50:38 PM	109.3	109.3	-1.12	-1.65	23.5	30.2	0.647	1.069	-16.89		28.74
H-2304E	7/8/2026 10:53:56 AM	98.4	98.5	-8.89	-8.87	0.0	0.0	-0.366	-0.373	-10.33		28.78
H-2304S	7/8/2026 12:46:00 PM	126.9	127.3	-2.87	-1.79	17.7	12.0	6.607	3.012	-3.84		28.75
H-2305N	7/7/2026 12:55:53 PM	99.3	99.4	-9.19	-7.05	5.1	1.3	0.533	0.036	-14.44	-14.82	28.76
H-2305S	7/8/2026 12:38:28 PM	127.4	127.5	-3.26	-2.70	17.3	12.9	1.875	1.040			28.77
H-2306N	7/8/2026 11:12:08 AM	117.9	118.1	-3.16	-1.67	38.5	14.7	3.279	0.479	-17.56		28.75
H-2307S	7/7/2026 12:42:18 PM	114.5	118.5	-0.53	-0.49	22.7	23.6	1.183	1.287	-12.25	-11.95	28.75
H-2308S	7/7/2026 12:44:18 PM	118.9	119.0	-0.34	-0.36	13.8	12.7	0.247	0.208	-12.16	-12.10	28.74
H-2309N	7/8/2026 10:26:32 AM	107.3	107.3	-15.23	-12.86	2.4	0.6	0.036	0.002	-17.57	-17.48	28.66
H-2309S	7/8/2026 11:46:56 AM	117.0	117.1	-3.00	-3.16	31.3	35.7	1.179	1.539	-16.39		28.75
H-2310N	7/7/2026 12:23:23 PM	113.2	114.0	-0.36	-0.39	18.4	22.4	0.434	0.644	-8.90	-8.78	28.73
H-2310S	7/8/2026 11:04:10 AM	103.6	103.7	-0.30	-0.30			-0.131	-0.131			28.75
H-2401S	7/7/2026 1:38:50 PM	111.8	112.3	-9.08	-9.08	7.2	7.3	1.108	1.135	-11.68	-11.74	28.7
H-2402N	7/8/2026 10:18:31 AM	116.5	116.6	-0.68	-0.68	6.4	7.1	0.869	1.055	-18.12	-17.99	28.71
H-2402S	7/7/2026 1:13:43 PM	114.6	114.8	-0.25	-0.58	15.9	13.9	0.326	0.247	-13.79	-19.07	28.7

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [ ]	Adj Temp [ ]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
H-2403N	7/8/2026 10:13:18 AM	117.5	117.6	-1.38	-0.66	10.7	6.8	2.438	0.961	-17.47	-17.74	28.7
H-2403N	7/8/2026 10:14:45 AM	117.5	117.6	-0.66	-0.64	6.8	6.7	0.968	0.958	-17.64	-17.67	28.7
H-2403S	7/7/2026 1:10:49 PM	96.2	96.8	-9.35	-7.72	3.0	2.9	0.187	0.171	-16.36	-15.45	28.72
H-2404N	7/8/2026 10:09:46 AM	116.4	116.4	-5.08	-5.08	16.4	16.4	5.738	5.734	-18.52	-18.55	28.73
H-2404S	7/7/2026 12:33:55 PM	114.3	114.3	-12.93	-13.08	21.3	24.1	0.601	0.769	-13.66	-13.88	28.74
H-2405N	7/8/2026 10:41:41 AM	123.0	123.0	-0.75	-0.65	7.6	6.6	6.455	4.786	-17.18	-16.91	28.69
H-29	7/8/2026 12:28:55 PM	134.2	119.3	-5.76	-2.53	2.8	4.0	0.167	0.341	-14.84	-14.94	28.62
H-29	7/8/2026 12:33:29 PM	128.7	128.7	-2.48	-2.38	3.9	3.5	0.331	0.265	-14.93	-14.97	28.62
H-72	7/8/2026 3:24:26 PM	98.4	97.9	-1.30	-1.27	1.5	2.6	0.003	0.009	-10.82		28.52
H-74	7/8/2026 3:40:26 PM	107.7	107.7	-7.67	-7.65	11.1	10.5	2.498	2.238	-9.71		28.52
H-74	7/20/2026 9:52:25 AM	108.4	108.3	-7.08	-6.90	10.8	10.9	2.449	2.486	-9.55	-9.34	28.71
H-75	7/6/2026 10:04:51 AM	96.9	96.9	-3.19	-3.16	4.0	4.0	4.072	4.071	-12.51		28.62
H-79	7/6/2026 9:42:54 AM	126.9	130.4	-0.11	-0.12	7.7	8.0	0.079	0.085	-15.14	-15.36	28.59
P-02R	7/8/2026 8:43:54 AM	86.4		-0.52		9.3		0.521		-19.10		28.79
P-03R	7/8/2026 8:58:45 AM	94.8		-1.36	-1.36	3.1	3.1	0.998	0.990	-18.20	-18.25	28.79
P-04	7/8/2026 9:07:17 AM	102.5		-1.10				1.104		-16.55		28.79
P-05	7/8/2026 9:20:57 AM	104.0	104.0	-0.24	-0.24			0.237	0.237	-15.00	-15.18	28.79
P-05	7/8/2026 9:37:13 AM	104.3										28.79
P-05	7/8/2026 9:39:03 AM	104.2	104.5	-0.20	-0.22			0.200	0.219	-14.98	-14.94	28.82
P-05	7/8/2026 1:30:17 PM	105.1	105.1	-0.13	-0.13			0.124	0.131	-14.08	-14.00	28.76
P-06R	7/8/2026 9:28:01 AM	112.2	112.4	-0.59	-0.64	4.0	4.7	0.100	0.139	-14.28	-14.28	28.8
P-06R	7/8/2026 9:30:23 AM	112.5	112.4	-0.66	-0.67	4.9	5.2	0.147	0.166	-14.30	-14.53	28.82
P-06R	7/8/2026 9:40:41 AM	104.6	104.6	-0.24	-0.24	6.2	6.2	0.237	0.237	-14.86	-14.82	28.8
P-07R	7/8/2026 10:22:36 AM	89.8		-0.71		4.9		2.476		-17.50		28.77
P-08R	7/8/2026 8:36:31 AM	98.2	98.7	-15.50	-15.76	15.4	15.6	0.306	0.314	-16.04	-16.42	28.79
P-09	7/1/2026 1:36:56 PM	98.0	98.0	-0.51	-0.50			0.504	0.492	-12.41	-12.50	28.71
P-10	7/1/2026 1:47:13 PM	94.1	94.1	-0.19	-0.19	3.2	3.1	1.084	0.990	-12.14	-11.08	28.74
P-11	7/1/2026 1:54:31 PM	105.6	105.7	-0.42	-0.42	7.2	7.2	5.585	5.593	-11.31	-11.54	28.74
P-12	7/8/2026 10:01:31 AM	91.1	91.0	-10.04	-10.06	2.1	0.9	0.028	0.005	-11.81	-11.75	28.83
P-12	7/8/2026 10:03:58 AM	88.9	88.7	-10.12	-10.07	5.0	3.6	0.032	0.016	-11.71	-11.89	28.83
P-13	7/8/2026 9:53:30 AM	86.5	86.3	-1.07	-0.73	13.4	9.7	1.067	0.563	-11.86	-11.78	28.86
P-13	7/8/2026 9:55:58 AM	86.1	86.1	-0.68	-0.69	9.5	9.7	0.543	0.563	-11.75	-12.09	28.86
P-13	7/8/2026 10:07:11 AM	88.6	88.6	-10.10	-10.32	2.1	1.0	0.027	0.006	-11.65	-11.83	28.86
P-14	7/1/2026 2:03:05 PM	84.5	84.5	-0.18	-0.17			0.181	0.174	-12.68	-12.69	28.78
P-15R	7/1/2026 2:10:19 PM	90.4	90.5	-1.28	-1.26	2.1	2.3	0.471	0.548	-12.15	-12.08	28.78
P-16	7/20/2026 12:54:22 PM	123.9	123.9	-2.03	-2.10	4.8	5.1	2.481	2.831	-9.51	-10.16	28.9
P-17	7/6/2026 2:12:14 PM	112.2	112.1	-0.81	-0.79			0.834	0.795	-8.14	-8.94	28.78

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
P-18RD	7/6/2026 1:50:44 PM	99.0	99.1	-7.12	-7.88	0.1	1.0	0.001	0.110	-7.87	-7.63	28.78
P-18RD	7/6/2026 1:52:07 PM	99.6	99.7	-7.88	-7.81	1.4	1.0	0.206	0.116	-7.74	-7.63	28.78
P-18RD	7/6/2026 1:53:33 PM	99.5	99.6	-7.91	-7.43	1.1	1.5	0.128	0.231	-7.80	-7.40	28.78
P-18RS	7/6/2026 1:58:17 PM	98.2	98.2	-0.92	-0.93	4.7	4.7	2.327	2.306	-7.14	-7.25	28.8
P-19	7/6/2026 1:41:07 PM	93.5	93.4	-0.63	-0.61	8.6	8.6	0.448	0.443	-7.98	-7.77	28.8
P-20R	7/2/2026 2:11:06 PM	100.1	100.2	-1.30	-1.28	2.1	2.1	0.477	0.476	-9.47	-9.25	28.82
P-21	7/2/2026 2:05:54 PM	94.2	94.2	-0.41	-0.39			0.422	0.415	-9.07	-9.17	28.82
P-21RD	7/2/2026 1:36:40 PM	100.7	100.8	-3.92	-3.91	19.6	19.6	2.369	2.373	-8.48	-8.46	28.81
P-21RS	7/2/2026 1:31:20 PM	108.7	108.7	-3.60	-3.58	17.4	17.7	0.689	0.716	-8.70	-8.73	28.81
P-22RD	7/20/2026 12:48:40 PM	122.0	122.0	-3.37	-3.38	25.7	25.4	4.270	4.169	-7.19	-7.16	28.74
P-22RS	7/20/2026 12:45:58 PM	122.3	122.3	-0.96	-0.96	3.8	3.9	1.578	1.626	-7.32	-7.57	28.74
P-23	7/2/2026 1:50:54 PM	95.5	95.5	-0.22	-0.21			0.000	0.000	-8.72	-8.48	28.82
P-24	7/2/2026 1:18:32 PM	94.1		-1.82		4.8		2.396		-8.34		28.82
P-26	7/20/2026 1:03:55 PM	87.0	87.1	-4.98	-4.95			4.899	4.865	-7.18	-6.92	28.89
P-27	7/20/2026 1:12:57 PM	101.6	103.7	-0.30	-0.30			0.300	0.300	-6.94	-7.00	28.86
P-28	7/20/2026 1:18:33 PM	105.2	104.9	-3.49	-3.48			3.423	3.413	-6.42	-6.07	28.86
P-29R	7/20/2026 1:23:40 PM	106.3	106.5	-0.52	-0.52	1.2	1.1	0.008	0.007	-6.69	-6.61	28.86
P-30R	7/20/2026 1:31:27 PM	97.4	97.0	-4.67	-4.82	8.8	7.6	1.600	1.181	-6.19	-6.09	28.84
P-32R1	7/27/2026 1:09:08 PM	114.1	114.1	-1.09	-1.10	4.0	4.1	4.211	4.367	-5.03	-5.18	28.73
P-32R2	7/27/2026 1:00:31 PM	111.5	111.5	-1.39	-1.40	8.3	8.8	1.434	1.597	-5.12	-5.39	28.74
P-33	7/27/2026 12:53:39 PM	102.9	102.9	-1.63	-1.69			1.629	1.649	-4.99	-5.55	28.71
P-36	7/9/2026 1:53:10 PM	106.4	106.8	-0.11	-0.10			0.154	0.146	-3.54	-3.13	28.63
P-37	7/9/2026 2:10:42 PM	102.2	102.3	-0.12	-0.12	0.4	0.5	0.040	0.055	-3.12	-3.07	28.63
P-38RD	7/15/2026 1:34:09 PM	108.9	109.0	-2.85	-2.67	11.9	9.5	0.890	0.571	-3.36	-2.95	28.63
P-38RS	7/15/2026 1:37:49 PM	107.5	107.5	-0.66	-0.64	10.4	9.5	0.668	0.567	-3.20	-2.86	28.63
P-39	7/15/2026 1:47:47 PM	110.1	111.2	-5.02	-4.49	1.7	1.3	0.062	0.036	-4.77	-4.25	28.61
P-41	7/17/2026 1:27:10 PM	116.1	116.2	-4.11	-4.17	5.5	5.5	0.639	0.630	-4.47	-4.48	28.7
P-42R	7/17/2026 1:34:26 PM	114.0	114.2	-4.50	-4.45	2.3	1.9	0.559	0.394	-4.70	-4.55	28.71
P-42R	7/17/2026 1:35:31 PM	114.2	114.2	-4.54	-4.46	2.6	2.0	0.739	0.440	-4.91	-4.58	28.7
P-43	7/27/2026 2:02:31 PM	118.8	118.8	-3.03	-3.01			2.991	2.951	-5.70	-5.66	28.67
P-44RD	7/27/2026 1:55:00 PM	111.5	111.7	-5.79	-5.83	1.7	1.3	0.327	0.178	-6.19	-5.95	28.7
P-44RS	7/27/2026 1:51:21 PM	123.3	123.3	-5.24	-5.08	3.7	3.5	1.537	1.341	-6.13	-5.82	28.7
P-45RD	7/20/2026 1:08:46 PM	118.6	118.6	-5.15	-5.46	6.7	8.8	0.290	0.492	-5.68	-6.22	28.7
P-45RD	7/30/2026 8:33:40 AM	116.2	116.5	-7.43	-7.32	8.2	5.2	0.431	0.175	-8.74	-8.10	28.67
P-45RS	7/31/2026 8:40:03 AM	106.4	106.4	-0.68	-0.68	1.5	1.3	0.243	0.177	-8.47	-8.38	28.71
P-46RD	7/20/2026 12:58:59 PM	112.7	112.8	-5.90	-6.49	1.0	3.0	0.006	0.059	-5.80	-6.51	28.7
P-46RS	7/20/2026 1:02:00 PM	122.5	122.5	-1.65	-1.64	18.9	18.7	2.282	2.247	-5.68	-5.93	28.7
P-46RS	7/20/2026 1:11:30 PM	110.6	110.6	-0.28	-0.26	5.6	5.6	0.194	0.197	-5.89	-5.68	28.7
P-46RS	7/28/2026 12:43:27 PM	110.8	110.8	-0.45	-0.50	6.8	6.9	0.288	0.297	-6.06	-6.44	28.67
P-46RS	7/30/2026 9:02:21 AM	106.3	106.5	-0.65	-0.64	7.1	7.0	0.313	0.308	-8.02	-7.89	28.67
P-47	7/20/2026 12:34:13 PM	111.2	111.2	0.02	0.01			0.000	0.000	-7.30	-7.26	28.71
P-47	7/27/2026 9:24:31 AM	101.0	101.4	-0.10	-0.10			0.099	0.103	-8.14	-8.06	28.73
P-48	7/17/2026 2:01:45 PM	123.3	123.3	-0.13	-0.13	1.8	2.2	0.068	0.101	-6.41	-6.42	28.71

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
P-49RD	7/13/2026 12:32:12 PM	115.5	115.6	-8.92	-8.91	13.7	13.8	1.211	1.232	-10.21	-10.17	28.74
P-49RS	7/13/2026 12:27:08 PM	115.9	115.9	-0.81	-0.81	13.3	13.6	0.408	0.427	-10.11	-10.17	28.74
P-52	7/13/2026 1:42:13 PM	118.2	118.2	-0.29	-0.29			0.000	0.000	-12.78	-12.65	28.74
P-53	7/13/2026 1:00:47 PM	116.5	116.5	-0.56	-0.55	8.4	8.5	1.487	1.515	-13.74	-14.11	28.74
P-54	7/13/2026 1:15:17 PM	105.9	105.9	-3.16	-3.14	9.9	10.0	2.040	2.073	-15.44	-15.44	28.71
P-55	7/13/2026 1:21:13 PM	102.2	102.5	-0.35	-0.35			0.347	0.346	-16.28	-16.28	28.73
P-56	7/13/2026 1:34:27 PM	104.4		-0.33	-0.33			0.331	0.331	-16.15	-16.15	28.71
P-57	7/13/2026 1:27:44 PM	99.3	98.9	-0.29	-0.30	2.1	1.9	0.005	0.005	-16.10	-16.10	28.71
P-60R	7/13/2026 2:12:36 PM	107.9	108.4	-2.46	-2.38	1.2	1.6	0.032	0.050	-3.03	-3.46	28.7
P-61	7/27/2026 1:30:00 PM	93.5	93.5	-0.26	-0.26	5.9	6.2	3.655	3.972	-3.43	-3.84	28.67
P-65	7/16/2026 9:36:59 AM	87.6	89.4	-1.31	-1.26	2.1	1.9	1.064	0.944	-5.36	-4.76	28.6
P-71	7/17/2026 1:54:06 PM	110.7	110.7	-1.25	-1.25			1.235	1.240	-8.31	-8.69	28.71
P-75	7/13/2026 2:03:27 PM	96.3	96.3	-3.15	-3.20	13.9	14.0	1.178	1.211	-4.02	-4.13	28.7
P-76	7/20/2026 2:18:46 PM	115.7	115.6	-1.06	-1.07	7.1	7.1	1.056	1.058	-2.79	-3.06	28.67
P-79	7/9/2026 1:00:36 PM	98.1	98.1	-0.12	-0.10			0.141	0.139	-8.39	-8.66	28.81
SC-2000E	7/1/2026 7:59:51 AM	119.3	119.3	-5.75	-5.72	7.5	7.4	1.208	1.165	-15.14		28.66
SC-2501E	7/6/2026 9:35:00 AM											
SC-2501E	7/6/2026 9:35:00 AM											
SC-2501E	7/6/2026 9:38:29 AM	190.2	189.0	-0.41	-1.79	12.4	26.2	0.404	1.796	-1.76	-2.24	28.57
SC-2501E	7/13/2026 9:26:02 AM	188.4	188.4	-3.69	-3.71	37.4	37.4	3.681	3.693	-9.76	-9.85	28.6
SC-2501E	7/13/2026 9:35:00 AM											
SC-2501E	7/20/2026 9:21:46 AM	188.6	188.6	-3.56	-3.55			3.548	3.530	-8.55	-9.12	28.6
SC-2501E	7/20/2026 9:25:00 AM											
SC-2501E	7/27/2026 9:15:01 AM	189.1	189.2	-3.68	-3.68			3.711	3.702	-8.00	-7.99	28.6
SC-2501W	7/6/2026 10:10:15 AM	146.6	146.4	-2.73	-2.73	20.2	20.2	2.749	2.747	-3.16	-3.03	28.57
SC-2501W	7/6/2026 10:20:00 AM											
SC-2501W	7/6/2026 10:20:00 AM											
SC-2501W	7/13/2026 9:39:51 AM	140.0	123.9	-3.19	-3.46	21.8	23.0	3.178	3.445	-7.79	-8.44	28.6
SC-2501W	7/13/2026 9:40:22 AM	121.8	124.4	-3.48	-3.48	23.2	23.1	3.473	3.471	-8.32	-8.34	28.6
SW-10	7/31/2026 7:58:44 AM	83.8	84.6	-14.85	-12.16	1.9	0.9	0.023	0.005	-14.76	-15.08	28.6
SW-115	7/7/2026 11:50:26 AM	96.3	96.3	-8.72	-8.73	13.4	13.3	1.123	1.100	-15.13	-15.09	28.79
SW-1445	7/9/2026 11:49:56 AM	98.3	97.4	-2.30	-2.88	5.9	5.9	0.044	0.043	-2.87	-2.81	28.74
SW-1455	7/9/2026 11:39:16 AM	96.5	94.1	-1.42	-2.90	3.5	6.7	0.015	0.055	-2.95	-3.00	28.74
SW-154	7/13/2026 8:17:41 AM	83.4	83.5	-11.51	-11.70			0.108	0.116	-11.50	-11.50	28.66
SW-154	7/22/2026 10:03:39 AM	104.1	104.7	-10.08	-10.12			0.000	0.000	-10.08	-10.16	28.78
SW-17-135	7/9/2026 11:44:32 AM	100.4	100.1	-2.22	-2.97	6.7	6.9	0.056	0.059	-2.85	-2.97	28.74

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
SW-187	7/14/2026 1:15:47 PM	101.7	101.7	-9.99	-9.89	5.6	6.0	0.008	0.009	-9.76	-9.76	28.66
SW-187	7/20/2026 10:40:27 AM	92.4	92.7	-10.74	-10.74	52.7	52.7	0.671	0.671	-11.52	-11.52	28.71
SW-20	7/8/2026 10:16:30 AM	100.0	100.3	-0.04	-0.04	3.9	3.9	0.019	0.019	-17.62	-17.66	28.79
SW-2501D	7/30/2026 9:36:03 AM	84.5	84.6	-14.40	-14.40	2.3	2.2	0.540	0.491	-14.22	-14.22	28.74
SW-2501M	7/30/2026 9:30:41 AM	85.4	85.5	-29.04	-29.55	11.4	12.0	14.681	16.218	-14.66	-14.18	28.74
SW-2501MD	7/30/2026 9:33:08 AM	85.1	85.2	-6.06	-6.44	6.5	6.2	0.252	0.232	-14.24	-14.15	28.74
SW-2501S	7/30/2026 9:39:47 AM	85.9	86.1	-14.11	-14.08	1.6	1.7	0.275	0.290	-14.22	-14.05	28.73
SW-2501S	7/30/2026 9:55:04 AM	93.5	93.8	-13.39	-13.39	1.8	1.8	0.339	0.332	-13.16	-13.21	28.74
SW-2502D	7/30/2026 10:03:33 AM	99.0	98.7	-13.39	-13.39	2.0	2.0	0.416	0.420	-13.21	-13.08	28.74
SW-2502M	7/30/2026 9:59:45 AM	89.0	88.6	-7.71	-7.71	1.6	1.6	0.260	0.260	-13.14	-13.14	28.74
SW-2502S	7/30/2026 9:57:10 AM	95.2	94.6	-13.50	-13.48	2.2	2.2	0.519	0.519	-13.32	-13.29	28.74
SW-2503D	7/30/2026 10:09:23 AM	89.1	89.3	-13.35	-13.39	1.7	1.7	0.324	0.315	-13.21	-13.21	28.71
SW-2503M	7/30/2026 10:14:22 AM	97.4	97.3	-10.88	-10.88	1.7	1.7	0.303	0.303	-13.20	-13.20	28.71
SW-2503MD	7/30/2026 10:11:11 AM	93.0	93.4	-13.39	-13.39	1.7	1.7	0.317	0.302	-13.38	-13.50	28.71
SW-2503S	7/30/2026 10:17:02 AM	99.0	98.9	-13.56	-13.60	1.8	1.8	0.347	0.356	-13.55	-13.48	28.71
SW-2504D	7/30/2026 10:20:04 AM	86.0	86.1	-13.35	-13.39	3.1	3.0	0.201	0.188	-13.21	-13.21	28.71
SW-2504M	7/30/2026 10:21:58 AM	97.1	97.3	-8.02	-8.02			0.213	0.208	-13.45	-13.39	28.71
SW-2504MD	7/30/2026 10:26:42 AM	94.0	94.0	-13.39	-13.39	3.7	3.6	0.288	0.263	-13.45	-13.21	28.71
SW-2504S	7/30/2026 10:23:56 AM	100.8	100.8	-13.24	-13.24	3.6	3.6	0.270	0.270	-13.10	-13.10	28.71
SW-30	7/30/2026 9:50:01 AM	92.0	92.2	-13.39	-13.35	15.3	14.7	0.297	0.276	-13.19	-13.12	28.74
SW-32	7/30/2026 9:47:03 AM	93.0	93.5	-13.39	-13.41			0.202	0.132	-13.25	-13.50	28.74
SW-64	7/30/2026 9:51:59 AM	94.0	94.5	-13.66	-13.62	15.4	15.5	0.302	0.308	-13.41	-13.38	28.74
SW-65	7/7/2026 11:47:53 AM	97.4	97.5	-12.78	-12.77	7.9	7.9	0.388	0.387	-15.03	-15.04	28.79
SW-66	7/13/2026 8:15:49 AM	89.0	89.0	-9.06	-9.06			0.054	0.086	-9.13	-9.17	28.66
SW-66	7/22/2026 10:01:37 AM	91.9	91.9	-8.77	-8.77			0.057	0.063	-8.93	-8.93	28.7
SW-68	7/30/2026 9:44:08 AM	91.2	91.3	-14.40	-14.32	15.4	15.4	0.303	0.301	-14.14	-14.07	28.74
SW-70	7/14/2026 1:18:03 PM	94.4	92.9	-9.74	-9.93	3.0	4.1	0.002	0.004	-9.69	-9.86	28.66
SW-70	7/20/2026 10:44:08 AM	89.4	89.7	-10.85	-10.84	57.8	57.3	0.802	0.788	-11.85	-11.81	28.71
SW-71	7/2/2026 1:10:31 PM	85.4		-5.28		1.9		0.371		-8.46		28.79
SW-72	7/9/2026 1:49:05 PM	103.5	103.7	-0.32	-0.28			0.042	0.044	-3.21	-3.14	28.63
SW-80	7/22/2026 9:36:13 AM	95.7	95.9	-8.15	-8.16	4.5	4.5	0.125	0.126	-13.53	-13.49	28.81
SW-9	7/14/2026 1:53:02 PM	96.1	96.5	-9.78	-9.78	5.5	6.1	0.007	0.009	-9.90	-9.87	28.66
SW-9	7/20/2026 10:46:40 AM	90.7	90.8	-10.96	-10.98	47.7	47.7	0.547	0.548	-11.70	-11.73	28.71
TC-1961C	7/1/2026 10:14:09 AM	73.0	73.3	-0.29	-0.20	0.0	0.0	-0.052	-0.056	-20.07		28.62
TC-1961E	7/6/2026 10:16:48 AM	123.5	123.4	-3.28	-3.29	5.3	3.0	0.066	0.021	-17.51	-17.14	28.62
TC-2174	7/6/2026 9:22:38 AM	184.3	184.4	-2.09	-2.10			2.098	2.085	0.29	0.25	28.57
TC-2174	7/6/2026 9:25:00 AM											
TC-2174	7/6/2026 9:25:00 AM											
TC-2174	7/13/2026 9:12:45 AM	184.6	184.7	0.23	0.26			0.000	0.000	0.28	0.24	28.62
TC-2174	7/13/2026 9:14:53 AM	184.7	184.7	0.13	0.15			0.000	0.000	0.25	0.25	28.6

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
TC-2174	7/13/2026 9:25:00 AM											
TC-2174	7/15/2026 2:14:30 PM	184.4	184.5	-0.22	-0.29			0.267	0.366	0.21	0.21	28.46
TC-2174	7/15/2026 2:22:26 PM	184.6	184.7	-0.71	-0.64			0.698	0.636	0.21	0.21	28.46
TC-2174	7/20/2026 9:09:11 AM	184.6	184.6	-2.90	-2.87			2.907	2.858	0.14	0.17	28.6
TC-2174	7/20/2026 9:15:00 AM											
TC-2174	7/27/2026 9:01:39 AM	184.7	184.9	-3.62	-3.61			3.609	3.565	0.34	0.34	28.6
VL-02	7/30/2026 9:00:19 AM	78.2	98.3	-20.29	-19.92	29.8	29.6	1.091	1.111	-19.39	-19.34	28.71

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
A-01	7/6/2026 7:46:40 AM	1125	34.4312047	-118.6437952	No Flow Measurement,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
A-02	7/6/2026 7:57:43 AM	1165	34.4316143	-118.6433238	No Flow Measurement,No Adjustment Made
A-03	7/6/2026 8:00:34 AM	1204	34.4320215	-118.6428298	No Flow Measurement,No Adjustment Made
A-04	7/6/2026 8:05:04 AM	1148	34.4322783	-118.6423037	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,No Flow Measurement
A-05	7/6/2026 8:09:36 AM	1191	34.4324975	-118.6416480	No Flow Measurement,No Adjustment Made
B-01	7/6/2026 9:13:17 AM	1211	34.4338755	-118.6395902	,
B-02R	7/6/2026 9:02:40 AM	1204	34.4339748	-118.6377563	No Adjustment Made,
B-02R	7/6/2026 9:18:34 AM	1243	34.4335760	-118.6395035	,
B-03R	7/6/2026 8:43:02 AM	1224	34.4338260	-118.6388312	,
B-05	7/6/2026 9:09:04 AM	1207	34.4336590	-118.6382497	,
B-06	7/28/2026 1:24:16 PM	1213	34.4340062	-118.6377352	
B-07R	7/6/2026 8:24:41 AM	1220	34.4342268	-118.6373580	No Adjustment Made,
B-08	7/22/2026 1:56:26 PM	1214	34.4337837	-118.6373352	Valve Adjustment:NSPS/EG CAI,No Flow Measurement
B-08	7/22/2026 3:13:28 PM	1229	34.4337738	-118.6373457	Valve Adjustment:High O2,Decreased Flow/Vacuum,Barely Open
B-08	7/22/2026 3:16:37 PM	1222	34.4337752	-118.6373477	Valve Adjustment:Orifice Plate Changed (See OP Log),Barely Open
B-08	7/22/2026 3:19:24 PM	1230	34.4337663	-118.6373608	Valve Adjustment:High O2,Barely Open
B-08	7/28/2026 1:11:23 PM	1220	34.4337765	-118.6373478	Valve Adjustment:Barely Open
B-09	7/6/2026 8:21:46 AM	1204	34.4342795	-118.6370965	No Flow Measurement,
B-10	7/6/2026 8:16:35 AM	1201	34.4340842	-118.6366672	No Flow Measurement,No Adjustment Made
B-11	7/22/2026 1:36:25 PM	1142	34.4348172	-118.6368967	
B-12	7/6/2026 8:37:40 AM	1230	34.4340348	-118.6384518	,
B-13	7/6/2026 8:28:38 AM	1234	34.4344195	-118.6378810	No Adjustment Made,Audible Flow
B-14	7/22/2026 1:41:43 PM	1130	34.4349263	-118.6370652	
C-03	7/30/2026 9:18:29 AM	1177	34.4314048	-118.6435548	Well Comment:hard pipped
C-07	7/30/2026 9:46:54 AM	1188	34.4326317	-118.6414102	Valve Adjustment:Valve 100% Open;Well Comment:hard pipped
C-08	7/15/2026 1:59:25 PM	1199	34.4336642	-118.6408568	
C-08	7/16/2026 1:29:17 PM	1209	34.4336658	-118.6408753	Valve Adjustment:Increased Flow/Vacuum
C-10	7/7/2026 11:57:57 AM	1224	34.4347128	-118.6411817	Valve Adjustment:Audible Flow
C-11	7/9/2026 11:58:12 AM	1234	34.4353027	-118.6412533	,
C-12	7/31/2026 9:52:23 AM	1228	34.4359693	-118.6408823	Valve Adjustment:Valve 100% Open
C-15	7/29/2026 2:09:12 PM	1223	34.4362640	-118.6410743	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
C-15	7/29/2026 2:11:26 PM	1233	34.4362795	-118.6410513	Valve Adjustment:Positive Static Press.
C-15	7/29/2026 3:08:37 PM	1222	34.4362598	-118.6410407	Valve Adjustment:NSPS/EG CAC,Increased Flow/Vacuum
C-17B	7/22/2026 9:17:59 AM	1234	34.4373867	-118.6419280	Valve Adjustment:Increased Flow/Vacuum

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
C-17B	7/30/2026 10:53:56 AM	1224	34.4373478	-118.6419387	Valve Adjustment:Valve 100% Open;Well Comment:hard pipped
C-18	7/22/2026 9:31:11 AM	1231	34.4380185	-118.6426348	Valve Adjustment:Increased Flow/Vacuum
C-19	7/22/2026 9:28:11 AM	1232	34.4375810	-118.6421593	
C-19	7/30/2026 10:37:45 AM	1226	34.4375628	-118.6421543	Valve Adjustment:Valve 100% Open;Well Comment:hard pipped
C-20	7/22/2026 9:25:28 AM	1265	34.4378257	-118.6424532	Valve Adjustment:Increased Flow/Vacuum
C-24	7/22/2026 9:23:30 AM	1242	34.4375465	-118.6421347	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
C-24	7/22/2026 9:25:48 AM	1248	34.4375537	-118.6421363	Valve Adjustment:NSPS/EG CAC
C-24	7/30/2026 10:47:49 AM	1224	34.4375010	-118.6421263	Valve Adjustment:High O2,Barely Open
C-24	7/30/2026 10:48:42 AM	1223	34.4375008	-118.6421280	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
C-25	7/22/2026 9:07:22 AM	1234	34.4371678	-118.6417003	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
C-25	7/22/2026 9:07:58 AM	1230	34.4371627	-118.6416972	Valve Adjustment:NSPS/EG CAI,High O2
C-25	7/22/2026 9:12:41 AM	1227	34.4371210	-118.6416588	
C-25	7/30/2026 10:57:08 AM	1208	34.4371533	-118.6417280	Valve Adjustment:Valve 100% Open;Well Comment:hard pipped
C-26	7/22/2026 9:06:07 AM	1227	34.4366653	-118.6412783	Valve Comment:No system port
C-27	7/31/2026 8:10:51 AM	1228	34.4361788	-118.6409688	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum;Well Repairs:Valve
C-27	7/31/2026 8:11:55 AM	1226	34.4361757	-118.6409705	Valve Adjustment:NSPS/EG CAI,High O2;Well Repairs:Valve
C-28	7/9/2026 11:53:17 AM	1243	34.4353933	-118.6413295	Positive Static Press.,NSPS/EG CAI,NSPS/EG CAC,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
C-28	7/9/2026 11:54:12 AM	1293	34.4353438	-118.6412247	,
C-29	7/7/2026 11:54:36 AM	1218	34.4348293	-118.6412663	Valve Adjustment:Decreased Flow/Vacuum
C-30	7/15/2026 2:11:09 PM	1232	34.4342622	-118.6412493	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-02	7/6/2026 9:42:55 AM	1230	34.4335608	-118.6413230	,
CV-03	7/6/2026 9:37:03 AM	1224	34.4333140	-118.6414473	No Adjustment Made,
CV-04	7/6/2026 9:33:10 AM	1204	34.4331582	-118.6416985	No Adjustment Made,
CV-05	7/9/2026 10:12:25 AM	1227	34.4328247	-118.6422235	Valve Adjustment:Valve 100% Open
CV-05	7/16/2026 1:41:39 PM	1220	34.4328363	-118.6422285	Valve Adjustment:Increased Flow/Vacuum
CV-06	7/7/2026 12:17:10 PM	1226	34.4326690	-118.6428577	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-108-52	7/1/2026 8:25:00 AM				AirTech Lab
CV-108-52	7/1/2026 8:25:00 AM				AirTech Lab; [User entered 0%]
CV-108-52	7/3/2026 7:30:23 AM	1269	34.4333962	-118.6507050	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Well (Watered In)

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-108-52	7/3/2026 7:30:59 AM	1274	34.4333982	-118.6506948	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Well (Watered In)
CV-108-52	7/7/2026 10:18:34 AM	1276	34.4334007	-118.6506755	Valve Adjustment:NSPS/EG CAC,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
CV-108-52	7/28/2026 1:43:12 PM	1277	34.4334007	-118.6506922	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Valve 100% Open,Surging Liquid in Header
CV-108-52	7/28/2026 1:45:22 PM	1272	34.4334072	-118.6506763	Valve Adjustment:Positive Static Press.,Valve 100% Open
CV-113	7/8/2026 1:51:43 PM	1335	34.4369973	-118.6467305	Valve Adjustment:High O2,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-113	7/9/2026 7:25:00 AM				AirTech Lab
CV-113	7/9/2026 7:25:00 AM				AirTech Lab; [User entered 0.064%]
CV-113	7/24/2026 9:55:00 AM				Air Tech Lab
CV-113	7/24/2026 9:55:00 AM				Air Tech Lab; [User entered 18%]
CV-113	7/29/2026 2:25:40 PM	1307	34.4369448	-118.6467152	Valve Adjustment:High O2,Barely Open
CV-114	7/6/2026 9:16:05 AM	1345	34.4367486	-118.6476602	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-114	7/6/2026 9:20:00 AM				AtmAA
CV-114	7/6/2026 9:20:00 AM				AtmAA; [User entered 14.44%]
CV-114	7/9/2026 7:20:00 AM				AirTech Lab
CV-114	7/9/2026 7:20:00 AM				AirTech Lab; [User entered 17%]
CV-114	7/13/2026 9:10:49 AM	1358	34.4367308	-118.6476262	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-114	7/13/2026 9:20:00 AM				AtmAA
CV-114	7/15/2026 2:14:50 PM	1349	34.4367605	-118.6476134	Valve Adjustment:No Flow Measurement,High Temp
CV-114	7/20/2026 9:07:38 AM	1360	34.4367318	-118.6476214	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-114	7/20/2026 9:10:00 AM				AtmAA
CV-114	7/27/2026 8:59:32 AM	1346	34.4367146	-118.6476166	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-1424	7/2/2026 11:04:56 AM	1434	34.4352215	-118.6451102	,
CV-1424	7/21/2026 10:15:43 AM	1384	34.4351602	-118.6450825	Valve Adjustment:Decreased Flow/Vacuum
CV-1532A	7/1/2026 8:30:00 AM				AirTech Lab
CV-1532A	7/1/2026 8:30:00 AM				AirTech Lab; [User entered 0%]
CV-1532A	7/13/2026 9:37:04 AM	1281	34.4338532	-118.6508227	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-1532A	7/13/2026 9:39:23 AM	1294	34.4338753	-118.6508400	Valve Adjustment:NSPS/EG CAI,High O2

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-1532A	7/28/2026 1:50:16 PM	1282	34.4338673	-118.6508275	Valve Adjustment:High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-1534A-PL	7/13/2026 9:24:22 AM	1292	34.4336385	-118.6507873	Valve Adjustment:Audible Flow,Surging Liquid in Header
CV-1534A-PL	7/28/2026 1:57:13 PM	1281	34.4336190	-118.6508160	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:Hard pipped
CV-1535	7/3/2026 7:26:47 AM	1317	34.4333180	-118.6503463	Valve Adjustment:Decreased Flow/Vacuum
CV-1535	7/13/2026 9:30:00 AM				AirTech Lab
CV-1535	7/13/2026 9:30:00 AM				AirTech Lab; [User entered 0.50%]
CV-1535	7/20/2026 10:25:32 AM	1310	34.4333348	-118.6503247	Valve Adjustment:Barely Open
CV-1601D	7/1/2026 3:18:41 PM	1306	34.4311097	-118.6486390	,
CV-1601D	7/16/2026 2:02:26 PM				,
CV-1601S	7/1/2026 3:14:58 PM	1270	34.4310767	-118.6487327	,
CV-1601S	7/16/2026 2:00:37 PM				,
CV-1604	7/1/2026 10:22:08 AM	1283	34.4321758	-118.6450640	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-1701D	7/6/2026 10:05:30 AM	1294	34.4336048	-118.6433477	Valve Adjustment:Decreased Flow/Vacuum
CV-1701D	7/29/2026 10:38:22 AM				[User entered 19.2%]
CV-1701D	7/29/2026 10:47:20 AM	1292	34.4335928	-118.6433378	Valve Adjustment:Decreased Flow/Vacuum
CV-1701D	7/29/2026 10:50:04 AM	1295	34.4335947	-118.6433408	Well Comment:secured lorentz nut
CV-1701D	7/29/2026 1:45:00 PM				AtmAA
CV-1701D	7/29/2026 2:13:12 PM	1305	34.4335717	-118.6433293	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum;Well Comment:secured wellhead
CV-1701D	7/29/2026 2:14:44 PM	1298	34.4335935	-118.6433612	
CV-1701S	7/6/2026 9:59:53 AM	1297	34.4336138	-118.6433473	Valve Adjustment:NSPS/EG CAI,High Temp
CV-1701S	7/6/2026 10:00:19 AM	1299	34.4336220	-118.6433520	Valve Adjustment:NSPS/EG CAI,High Temp
CV-1701S	7/29/2026 11:07:45 AM				[User entered 4.2%]
CV-1701S	7/29/2026 11:09:01 AM	1295	34.4335952	-118.6433358	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-1701S	7/29/2026 11:10:07 AM	1291	34.4335973	-118.6433460	Valve Adjustment:High Temp
CV-1701S	7/29/2026 1:50:00 PM				AtmAA
CV-1701S	7/29/2026 1:50:00 PM				AtmAA; [User entered 5.57%]
CV-1901	7/1/2026 10:06:33 AM	1325	34.4356972	-118.6507958	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-1901	7/16/2026 10:59:07 AM	1333	34.4357142	-118.6507965	Valve Adjustment:Barely Open
CV-1902A	7/1/2026 9:35:00 AM				AtmAA
CV-1902A	7/1/2026 9:37:01 AM	1322	34.4346402	-118.6503773	Valve Adjustment:No Flow Measurement,High Temp
CV-1902A	7/8/2026 8:45:00 AM				AtmAA
CV-1902A	7/8/2026 8:45:00 AM				AtmAA; [User entered 15.89%]

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-1902A	7/8/2026 8:49:36 AM	1327	34.4345957	-118.6503186	Valve Adjustment:No Flow Measurement,High Temp
CV-1902A	7/15/2026 8:30:00 AM				AtmAA
CV-1902A	7/15/2026 8:30:50 AM	1321	34.4346192	-118.6503277	Valve Adjustment:No Flow Measurement,High Temp
CV-1902A	7/22/2026 9:15:53 AM	1321	34.4346146	-118.6503184	Valve Adjustment:No Flow Measurement,High Temp
CV-1902A	7/29/2026 8:19:09 AM	1329	34.4345939	-118.6503119	Valve Adjustment:No Flow Measurement,High Temp
CV-1905	7/7/2026 2:26:39 PM				Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-2001	7/2/2026 8:10:00 AM				AirTech Lab
CV-2001	7/2/2026 8:10:00 AM				AirTech Lab; [User entered 2.4%]
CV-2001	7/3/2026 7:59:18 AM	1254	34.4322870	-118.6505707	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Surging Liquid in Header
CV-2001	7/3/2026 8:00:50 AM	1262	34.4322718	-118.6505622	Valve Adjustment:NSPS/EG CAI,High O2,Surging Liquid in Header;Well Comment:Unable to adjust safely
CV-2001	7/20/2026 12:55:49 PM	1262	34.4322958	-118.6505543	Valve Adjustment:Barely Open
CV-2002	7/1/2026 1:41:30 PM	1260	34.4327953	-118.6511391	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	7/1/2026 1:42:00 PM				AtmAA
CV-2002	7/8/2026 7:50:00 AM				AirTech Lab
CV-2002	7/8/2026 7:50:00 AM				AirTech Lab; [User entered 12%]
CV-2002	7/8/2026 10:23:36 AM	1271	34.4327992	-118.6511744	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	7/8/2026 10:35:00 AM				AtmAA
CV-2002	7/8/2026 10:35:00 AM				AtmAA; [User entered 10.32%]
CV-2002	7/15/2026 9:58:01 AM	1263	34.4328166	-118.6511536	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	7/15/2026 10:00:00 AM				AtmAA
CV-2002	7/20/2026 1:06:48 PM	1268	34.4328397	-118.6511598	Valve Adjustment:High Temp,Barely Open
CV-2002	7/22/2026 1:55:59 PM	1264	34.4328083	-118.6511745	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	7/22/2026 1:56:42 PM	1264	34.4328084	-118.6511745	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	7/29/2026 9:25:08 AM	1276	34.4328087	-118.6511556	Valve Adjustment:No Flow Measurement,High O2
CV-2003	7/3/2026 7:32:47 AM	1275	34.4334007	-118.6507417	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Well (Watered In)
CV-2003	7/3/2026 7:33:04 AM	1278	34.4334137	-118.6507353	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Well (Watered In)
CV-2003	7/7/2026 10:15:47 AM	1278	34.4334098	-118.6507203	Valve Adjustment:NSPS/EG CAC,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
CV-2003	7/28/2026 1:39:31 PM	1279	34.4334120	-118.6507123	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Valve 100% Open
CV-2003	7/28/2026 1:41:40 PM	1275	34.4334140	-118.6507123	Valve Adjustment:Positive Static Press.,Valve 100% Open,Surging Liquid in Header

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2006	7/1/2026 9:44:51 AM	1321	34.4352297	-118.6506548	Valve Adjustment:High Temp
CV-2006	7/1/2026 9:50:00 AM				AtmAA
CV-2006	7/8/2026 8:55:00 AM				AtmAA
CV-2006	7/8/2026 8:55:00 AM				AtmAA; [User entered 17.01%]
CV-2006	7/8/2026 8:55:07 AM	1328	34.4352231	-118.6506536	Valve Adjustment:No Flow Measurement,High Temp
CV-2006	7/15/2026 8:37:09 AM	1323	34.4352251	-118.6506595	Valve Adjustment:High O2
CV-2006	7/15/2026 8:40:00 AM				AtmAA
CV-2006	7/22/2026 9:20:15 AM	1330	34.4352402	-118.6506639	Valve Adjustment:High Temp
CV-2006	7/29/2026 8:24:09 AM	1315	34.4352347	-118.6506543	Valve Adjustment:High Temp
CV-2007	7/6/2026 1:47:52 PM	1382	34.4361725	-118.6470030	Valve Adjustment:High O2
CV-2007	7/23/2026 9:41:53 AM	1367	34.4361632	-118.6469945	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open
CV-2007	7/23/2026 9:42:37 AM	1372	34.4361558	-118.6470018	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2007	7/27/2026 1:17:09 PM	1379	34.4361734	-118.6469908	Valve Adjustment:High Temp
CV-2008	7/6/2026 2:08:20 PM	1370	34.4361967	-118.6462565	Valve Adjustment:Decreased Flow/Vacuum
CV-2008	7/23/2026 9:23:46 AM	1375	34.4362055	-118.6462470	Valve Adjustment:Barely Open
CV-2009	7/7/2026 10:02:25 AM	1367	34.4362615	-118.6452675	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Barely Open
CV-2009	7/7/2026 10:03:44 AM	1371	34.4362727	-118.6452877	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-2009A	7/14/2026 8:47:52 AM	1401	34.4359905	-118.6452547	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-2009A	7/14/2026 8:48:35 AM	1400	34.4359857	-118.6452613	Valve Adjustment:High Temp,Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-2009A	7/14/2026 2:08:33 PM	1397	34.4359705	-118.6452433	Valve Adjustment:High Temp,Valve 100% Open
CV-2009A	7/14/2026 2:10:00 PM				AtmAA
CV-2009A	7/20/2026 2:40:00 PM				AtmAA
CV-2009A	7/20/2026 2:41:25 PM	1388	34.4359904	-118.6452741	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum,Valve 100% Open
CV-2009A	7/20/2026 2:41:51 PM	1388	34.4359938	-118.6452735	Valve Adjustment:No Flow Measurement,High Temp
CV-2009A	7/29/2026 10:20:52 AM	1411	34.4359939	-118.6452442	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2010	7/6/2026 9:15:47 AM	1349	34.4356603	-118.6435915	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-2010A	7/6/2026 8:59:57 AM	1352	34.4357187	-118.6436740	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-2010A	7/6/2026 9:01:10 AM	1357	34.4357097	-118.6436670	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2010A	7/6/2026 9:03:59 AM	1365	34.4357168	-118.6436673	Valve Adjustment:NSPS/EG CAI,High Temp

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2011	7/6/2026 9:30:09 AM	1333	34.4342272	-118.6434515	Valve Adjustment:Audible Flow
CV-2011A	7/2/2026 11:29:15 AM	1334	34.4345387	-118.6431572	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum
CV-2011A	7/9/2026 8:54:58 AM	1336	34.4345068	-118.6431718	Valve Adjustment:High Temp,Increased Flow/Vacuum
CV-2011A	7/9/2026 8:55:33 AM	1339	34.4345173	-118.6431899	Valve Adjustment:High Temp
CV-2011A	7/9/2026 9:00:00 AM				AtmAA
CV-2011A	7/9/2026 9:00:00 AM				AtmAA; [User entered 20.18%]
CV-2011A	7/16/2026 9:11:56 AM	1322	34.4345268	-118.6431660	Valve Adjustment:High Temp
CV-2011A	7/16/2026 9:15:00 AM				AtmAA
CV-2011A	7/22/2026 2:38:29 PM	1308	34.4345763	-118.6431566	Valve Adjustment:High Temp
CV-2011A	7/30/2026 1:03:33 PM	1330	34.4345436	-118.6431508	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2012	7/8/2026 2:55:41 PM	1411	34.4351415	-118.6433088	High Temp,
CV-2012	7/8/2026 2:56:37 PM	1404	34.4351548	-118.6433650	,
CV-2201-PLR	7/8/2026 11:29:35 AM	1352	34.4355572	-118.6488465	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum,Barely Open
CV-2201-PLR	7/8/2026 11:30:39 AM	1346	34.4355568	-118.6488430	Valve Adjustment:NSPS/EG CAC,High Temp
CV-2201-PLR	7/29/2026 1:40:18 PM	1353	34.4355522	-118.6488432	Valve Adjustment:High Temp;Well Comment:hard pipped
CV-2201-PLR	7/29/2026 1:41:27 PM	1353	34.4355557	-118.6488432	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2204-PLR	7/6/2026 10:47:15 AM	1372	34.4357806	-118.6474874	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2204-PLR	7/6/2026 11:05:00 AM				AtmAA
CV-2204-PLR	7/6/2026 11:05:00 AM				AtmAA; [User entered 13.905%]
CV-2204-PLR	7/13/2026 10:28:00 AM	1358	34.4357819	-118.6474735	Valve Adjustment:No Flow Measurement,High Temp
CV-2204-PLR	7/13/2026 10:30:00 AM				AtmAA
CV-2204-PLR	7/20/2026 10:02:50 AM	1364	34.4357633	-118.6474581	Valve Adjustment:No Flow Measurement,High Temp
CV-2204-PLR	7/20/2026 10:15:00 AM				AtmAA
CV-2204-PLR	7/27/2026 10:47:10 AM	1363	34.4357685	-118.6474774	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2205	7/6/2026 11:03:21 AM	1363	34.4342562	-118.6441033	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2205	7/6/2026 11:04:01 AM	1363	34.4342637	-118.6441045	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2207	7/2/2026 11:24:38 AM	1417	34.4360042	-118.6443115	,
CV-2208A	7/7/2026 9:14:02 AM	1337	34.4365418	-118.6449503	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2208A	7/7/2026 9:14:44 AM	1339	34.4365445	-118.6449477	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2208A	7/7/2026 2:37:56 PM	1336	34.4365662	-118.6449429	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum
CV-2208A	7/7/2026 2:38:55 PM	1336	34.4365659	-118.6449432	Valve Adjustment:NSPS/EG CAC,High Temp
CV-2208A	7/7/2026 2:40:00 PM				AtmAA
CV-2208A	7/7/2026 2:40:00 PM				AtmAA; [User entered 6.86%]
CV-2208A	7/16/2026 11:12:34 AM	1338	34.4365487	-118.6449527	Valve Adjustment:High Temp
CV-2208A	7/16/2026 11:15:00 AM				AtmAA
CV-2208A	7/20/2026 1:44:53 PM	1337	34.4365610	-118.6449374	Valve Adjustment:No Flow Measurement,High Temp
CV-2208A	7/20/2026 1:50:00 PM				AtmAA
CV-2208A	7/27/2026 12:57:55 PM	1329	34.4365688	-118.6449464	Valve Adjustment:High Temp
CV-2301	7/6/2026 7:20:00 AM				AirTech Lab
CV-2301	7/6/2026 7:20:00 AM				AirTech Lab; [User entered 0%]
CV-2301	7/8/2026 1:12:10 PM	1343	34.4335268	-118.6492362	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-2301	7/8/2026 1:12:44 PM	1343	34.4335243	-118.6492302	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	7/8/2026 1:15:00 PM				AtmAA
CV-2301	7/8/2026 1:15:00 PM				AtmAA; [User entered 11.36%]
CV-2301	7/16/2026 10:42:12 AM	1335	34.4335088	-118.6492296	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2301	7/16/2026 10:43:49 AM	1340	34.4335077	-118.6492367	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	7/16/2026 10:45:00 AM				AtmAA
CV-2301	7/22/2026 2:20:36 PM	1331	34.4335224	-118.6491879	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2301	7/22/2026 2:22:28 PM	1330	34.4335187	-118.6491861	Valve Adjustment:No Flow Measurement,High Temp,High O2
CV-2301	7/22/2026 2:22:54 PM	1331	34.4335201	-118.6491831	Valve Adjustment:No Flow Measurement,High Temp,High O2
CV-2301	7/30/2026 9:33:34 AM	1348	34.4335009	-118.6492532	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,High O2,Decreased Flow/Vacuum
CV-2301	7/30/2026 9:37:13 AM	1348	34.4335010	-118.6492526	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-2302	7/6/2026 7:25:00 AM				AirTech Lab
CV-2302	7/6/2026 7:25:00 AM				AirTech Lab; [User entered 0%]
CV-2302	7/6/2026 3:38:27 PM	1332	34.4340623	-118.6490787	,
CV-2302	7/16/2026 2:45:08 PM	1336	34.4340353	-118.6492193	Valve Adjustment:Valve 100% Open
CV-2303	7/6/2026 7:25:00 AM				AirTech Lab
CV-2303	7/6/2026 7:35:00 AM				AirTech Lab; [User entered 0.079%]
CV-2303	7/7/2026 9:55:00 AM				AtmAA
CV-2303	7/7/2026 9:55:00 AM				AtmAA; [User entered 15.31%]
CV-2303	7/7/2026 10:01:32 AM	1352	34.4353744	-118.6496836	Valve Adjustment:No Flow Measurement,High Temp,High O2,Valve 100% Open
CV-2303	7/7/2026 10:02:07 AM	1352	34.4353745	-118.6496831	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2303	7/14/2026 9:45:01 AM	1367	34.4353819	-118.6496967	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Valve 100% Open
CV-2303	7/14/2026 9:55:00 AM				AtmAA
CV-2303	7/21/2026 8:52:07 AM	1365	34.4353719	-118.6496885	Valve Adjustment:No Flow Measurement,High Temp
CV-2303	7/28/2026 9:21:10 AM	1354	34.4353661	-118.6496773	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2304-PLR	7/2/2026 12:29:34 PM	1338	34.4345472	-118.6487668	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum
CV-2304-PLR	7/7/2026 1:45:00 PM				AtmAA
CV-2304-PLR	7/7/2026 1:45:00 PM				AtmAA; [User entered 10.85%]
CV-2304-PLR	7/7/2026 1:47:24 PM	1336	34.4345545	-118.6487241	Valve Adjustment:No Flow Measurement,High Temp
CV-2304-PLR	7/14/2026 10:20:56 AM	1348	34.4345699	-118.6487487	Valve Adjustment:No Flow Measurement,High Temp
CV-2304-PLR	7/14/2026 10:25:00 AM				AtmAA
CV-2304-PLR	7/14/2026 1:03:47 PM	1355	34.4352849	-118.6486659	Valve Adjustment:NSPS/EG CAI,Other - See Daily Log,High Temp,Increased Flow/Vacuum
CV-2304-PLR	7/21/2026 10:16:28 AM	1340	34.4345732	-118.6487622	Valve Adjustment:No Flow Measurement,High Temp
CV-2304-PLR	7/28/2026 9:49:36 AM	1346	34.4345570	-118.6487486	Valve Adjustment:No Flow Measurement,High Temp
CV-2305	7/2/2026 8:53:00 AM				AtmAA
CV-2305	7/2/2026 8:57:50 AM	1393	34.4352312	-118.6465461	Valve Adjustment:High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2305	7/2/2026 8:59:04 AM	1392	34.4352285	-118.6465445	Valve Adjustment:High Temp
CV-2305	7/9/2026 9:46:08 AM	1396	34.4352020	-118.6465393	Valve Comment:Pump was on while reading was taken;Valve Adjustment:High Temp
CV-2305	7/9/2026 9:50:00 AM				AtmAA
CV-2305	7/9/2026 9:50:00 AM				AtmAA; [User entered 6.23%]
CV-2305	7/13/2026 8:40:00 AM				AirTech Lab
CV-2305	7/13/2026 8:40:00 AM				AirTech Lab; [User entered 8.6%]
CV-2305	7/16/2026 9:44:14 AM	1397	34.4352103	-118.6465274	Valve Comment:Pump on;Valve Adjustment:High Temp,Increased Flow/Vacuum
CV-2305	7/16/2026 9:44:37 AM	1398	34.4352125	-118.6465271	Valve Adjustment:High Temp
CV-2305	7/16/2026 9:50:00 AM				AtmAA
CV-2305	7/30/2026 8:45:53 AM	1390	34.4352171	-118.6465479	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2306-PLR	7/6/2026 10:35:36 AM	1349	34.4360848	-118.6478362	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-2306-PLR	7/6/2026 10:36:14 AM	1348	34.4360876	-118.6478229	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-2306-PLR	7/6/2026 10:50:00 AM				AtmAA
CV-2306-PLR	7/6/2026 10:50:00 AM				AtmAA; [User entered 13.13%]
CV-2306-PLR	7/13/2026 10:20:00 AM				AtmAA

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2306-PLR	7/13/2026 10:21:22 AM	1367	34.4361027	-118.6478321	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2306-PLR	7/13/2026 10:22:02 AM	1367	34.4361033	-118.6478303	Valve Adjustment:No Flow Measurement,High Temp
CV-2306-PLR	7/20/2026 9:55:42 AM	1369	34.4360834	-118.6478191	Valve Adjustment:No Flow Measurement,High Temp
CV-2306-PLR	7/20/2026 10:05:00 AM				AtmAA
CV-2306-PLR	7/27/2026 10:38:00 AM	1365	34.4360827	-118.6478304	Valve Adjustment:No Flow Measurement,High Temp
CV-2308-PLR	7/8/2026 11:34:43 AM	1341	34.4359085	-118.6488990	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open,Surging Liquid in Well (Watered In)
CV-2308-PLR	7/8/2026 11:36:02 AM	1344	34.4359028	-118.6488968	
CV-2308-PLR	7/29/2026 1:44:36 PM	1355	34.4358950	-118.6489160	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2310-PLR	7/7/2026 9:40:00 AM				AtmAA
CV-2310-PLR	7/7/2026 9:40:00 AM				AtmAA; [User entered 11.38%]
CV-2310-PLR	7/7/2026 9:50:54 AM	1350	34.4353270	-118.6491468	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2310-PLR	7/14/2026 9:32:34 AM	1377	34.4353292	-118.6491398	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2310-PLR	7/14/2026 9:35:00 AM				AtmAA
CV-2310-PLR	7/21/2026 8:57:27 AM	1358	34.4353198	-118.6491405	Valve Adjustment:No Flow Measurement,High Temp
CV-2310-PLR	7/28/2026 9:16:24 AM	1371	34.4353319	-118.6491370	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2311	7/7/2026 8:43:40 AM	1361	34.4363335	-118.6499016	Valve Adjustment:No Flow Measurement,High Temp
CV-2311	7/7/2026 8:50:00 AM				AtmAA
CV-2311	7/7/2026 8:50:00 AM				AtmAA; [User entered 8.61%]
CV-2311	7/13/2026 2:40:00 PM				AtmAA
CV-2311	7/13/2026 2:45:21 PM	1390	34.4363054	-118.6498936	Valve Comment:Suspect bad valve;Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum,Valve 100% Open;Well Repairs:Valve
CV-2311	7/13/2026 2:46:49 PM	1397	34.4363062	-118.6498932	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2311	7/20/2026 2:20:00 AM				AtmAA
CV-2311	7/20/2026 2:18:54 PM	1375	34.4363153	-118.6498849	Valve Adjustment:No Flow Measurement,High Temp
CV-2311	7/28/2026 8:05:28 AM	1374	34.4363092	-118.6498855	Valve Adjustment:No Flow Measurement,High Temp
CV-2312-PLR	7/6/2026 7:45:00 AM				AirTech Lab
CV-2312-PLR	7/6/2026 7:45:00 AM				AirTech Lab; [User entered 3.3%]
CV-2312-PLR	7/8/2026 1:40:00 PM				AtmAA
CV-2312-PLR	7/8/2026 1:40:00 PM				AtmAA; [User entered 13.14%]
CV-2312-PLR	7/8/2026 1:43:27 PM	1384	34.4342200	-118.6473697	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2312-PLR	7/16/2026 10:16:27 AM	1383	34.4342104	-118.6473481	Valve Adjustment:No Flow Measurement,High Temp
CV-2312-PLR	7/16/2026 10:20:00 AM				AtmAA
CV-2312-PLR	7/17/2026 10:06:51 AM	1371	34.4344232	-118.6476223	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2312-PLR	7/21/2026 1:16:32 PM	1388	34.4342244	-118.6473407	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In)
CV-2312-PLR	7/22/2026 2:54:17 PM	1378	34.4342250	-118.6473589	Valve Adjustment:No Flow Measurement,High Temp
CV-2312-PLR	7/29/2026 1:17:39 PM	1383	34.4342120	-118.6473635	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PLR	7/6/2026 2:20:01 PM	1376	34.4346772	-118.6467126	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-2314-PLR	7/6/2026 2:21:36 PM	1377	34.4346770	-118.6467164	Valve Adjustment:High Temp
CV-2314-PLR	7/6/2026 2:40:00 PM				AtmAA
CV-2314-PLR	7/6/2026 2:40:00 PM				AtmAA; [User entered 11.77%]
CV-2314-PLR	7/13/2026 7:30:00 AM				AirTech Lab
CV-2314-PLR	7/13/2026 7:30:00 AM				AirTech Lab; [User entered 14%]
CV-2314-PLR	7/15/2026 1:37:00 PM	1374	34.4346771	-118.6467211	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum
CV-2314-PLR	7/15/2026 1:37:27 PM	1375	34.4346816	-118.6467211	Valve Adjustment:High Temp
CV-2314-PLR	7/15/2026 1:45:00 PM				AtmAA
CV-2315	7/6/2026 8:00:00 AM				AirTech Lab
CV-2315	7/6/2026 8:00:00 AM				AirTech Lab; [User entered 2.7%]
CV-2315	7/6/2026 1:44:39 PM	1377	34.4355113	-118.6472071	Valve Adjustment:No Flow Measurement,High Temp
CV-2315	7/6/2026 2:05:00 PM				AtmAA
CV-2315	7/6/2026 2:05:00 PM				AtmAA; [User entered 10.56%]
CV-2315	7/13/2026 1:19:42 PM	1388	34.4355227	-118.6471978	Valve Adjustment:No Flow Measurement,High Temp
CV-2315	7/13/2026 1:30:00 PM				AtmAA
CV-2315	7/20/2026 10:06:54 AM	1381	34.4355230	-118.6472025	Valve Adjustment:No Flow Measurement,High Temp
CV-2315	7/20/2026 10:20:00 AM				AtmAA
CV-2315	7/27/2026 1:32:19 PM	1380	34.4355261	-118.6471962	Valve Adjustment:No Flow Measurement,High Temp
CV-2316	7/2/2026 8:44:17 AM	1413	34.4360032	-118.6463951	Valve Adjustment:High Temp;Well Comment:Pump on;Well Condition:Lorentz Pump Installed
CV-2316	7/2/2026 8:45:00 AM				AtmAA
CV-2316	7/6/2026 10:15:04 AM	1396	34.4360428	-118.6463880	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-2316	7/9/2026 9:11:41 AM	1380	34.4360107	-118.6463790	Valve Adjustment:No Flow Measurement,High Temp
CV-2316	7/9/2026 9:15:00 AM				AtmAA
CV-2316	7/9/2026 9:15:00 AM				AtmAA; [User entered 10.83%]
CV-2316	7/13/2026 1:31:38 PM	1408	34.4360301	-118.6463710	Valve Adjustment:No Flow Measurement,High Temp
CV-2316	7/13/2026 1:32:10 PM	1408	34.4360349	-118.6463686	Valve Adjustment:No Flow Measurement,High Temp
CV-2316	7/13/2026 1:50:00 PM				AtmAA

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2316	7/20/2026 2:48:22 PM				Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum,Valve 100% Open
CV-2316	7/20/2026 2:48:45 PM	1403	34.4360418	-118.6463901	Valve Adjustment:High Temp
CV-2316	7/20/2026 2:50:00 PM				AtmAA
CV-2316	7/29/2026 10:28:36 AM	1412	34.4360602	-118.6463809	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2319	7/9/2026 1:47:48 PM	1385	34.4353020	-118.6457797	High Temp,NSPS/EG CAI
CV-2319	7/9/2026 1:48:57 PM	1414	34.4353400	-118.6458078	,
CV-2319	7/21/2026 10:28:30 AM	1393	34.4353363	-118.6457953	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2321	7/2/2026 10:04:18 AM	1398	34.4346233	-118.6453629	Valve Adjustment:High Temp
CV-2321	7/2/2026 10:05:00 AM				AtmAA
CV-2321	7/9/2026 9:24:29 AM	1388	34.4346145	-118.6453731	Valve Adjustment:High Temp
CV-2321	7/9/2026 9:25:00 AM				AtmAA
CV-2321	7/9/2026 9:25:00 AM				AtmAA; [User entered 7.12%]
CV-2321	7/16/2026 9:35:00 AM				AtmAA
CV-2321	7/16/2026 9:35:42 AM	1394	34.4346367	-118.6453976	Valve Adjustment:Audible Flow,High Temp
CV-2321	7/30/2026 8:24:57 AM	1397	34.4346359	-118.6453792	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2322	7/10/2026 10:37:17 AM	1374	34.4352670	-118.6475363	
CV-2322	7/29/2026 10:48:15 AM	1377	34.4353077	-118.6475445	Valve Adjustment:High Temp,Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:Hard piped
CV-2322	7/29/2026 10:50:11 AM	1367	34.4352945	-118.6475268	Valve Adjustment:High Temp
CV-2324	7/2/2026 11:30:10 AM	1407	34.4345678	-118.6442308	,
CV-2326	7/1/2026 10:11:42 AM	1365	34.4361393	-118.6504792	Valve Comment:Hard piped;Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2326	7/7/2026 8:55:47 AM	1367	34.4361201	-118.6504493	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2326	7/7/2026 8:56:20 AM	1367	34.4361202	-118.6504497	Valve Adjustment:No Flow Measurement,High Temp
CV-2326	7/7/2026 9:00:00 AM				AtmAA
CV-2326	7/7/2026 9:00:00 AM				AtmAA; [User entered 1.6%]
CV-2326	7/14/2026 8:52:10 AM	1371	34.4361042	-118.6504510	Valve Adjustment:No Flow Measurement,High Temp
CV-2326	7/14/2026 9:05:00 AM				AtmAA
CV-2326	7/21/2026 8:27:42 AM	1373	34.4361190	-118.6504443	Valve Adjustment:No Flow Measurement,High Temp
CV-2326	7/28/2026 8:24:36 AM	1365	34.4361033	-118.6504389	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2326	7/28/2026 8:25:04 AM	1366	34.4361058	-118.6504391	Valve Adjustment:No Flow Measurement,High Temp
CV-2327	7/8/2026 2:20:50 PM	1367	34.4348862	-118.6479381	Valve Adjustment:No Flow Measurement,High Temp
CV-2327	7/8/2026 2:25:00 PM				AtmAA

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2327	7/14/2026 1:28:40 PM	1378	34.4349001	-118.6479304	Valve Adjustment:No Flow Measurement,High Temp
CV-2327	7/14/2026 1:35:00 PM				AtmAA
CV-2327	7/21/2026 12:57:58 PM	1366	34.4348935	-118.6479521	Valve Adjustment:No Flow Measurement,High Temp
CV-2327	7/29/2026 12:59:11 PM	1372	34.4348930	-118.6479591	Valve Adjustment:No Flow Measurement,High Temp
CV-2328	7/8/2026 1:55:59 PM	1351	34.4343298	-118.6483477	Valve Adjustment:High Temp
CV-2328	7/13/2026 7:10:00 AM				AirTech Lab
CV-2328	7/13/2026 7:10:00 AM				AirTech Lab; [User entered 4.2%]
CV-2328	7/29/2026 9:48:41 AM	1348	34.4343235	-118.6483410	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-2328	7/29/2026 9:49:48 AM	1348	34.4343317	-118.6483380	Valve Adjustment:High Temp
CV-2328	7/29/2026 12:49:23 PM	1360	34.4343249	-118.6483356	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2333	7/6/2026 9:09:15 AM	1368	34.4365102	-118.6473904	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2333	7/6/2026 9:15:00 AM				AtmAA
CV-2333	7/6/2026 9:15:00 AM				AtmAA; [User entered 16.42%]
CV-2333	7/9/2026 7:15:00 AM				AirTech Lab
CV-2333	7/9/2026 7:15:00 AM				AirTech Lab; [User entered 20%]
CV-2333	7/9/2026 9:15:00 AM				AtmAA
CV-2333	7/13/2026 9:03:07 AM	1375	34.4365126	-118.6473705	Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Increased Flow/Vacuum,Valve 100% Open
CV-2333	7/13/2026 9:04:45 AM	1375	34.4365116	-118.6473674	Valve Comment:Pneumatic pump installed;Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open;Well Condition:Pnumatic Pump Installed
CV-2333	7/15/2026 2:28:17 PM	1352	34.4365321	-118.6473542	Valve Adjustment:No Flow Measurement,High Temp
CV-2333	7/16/2026 4:31:46 PM	1368	34.4364952	-118.6473827	,
CV-2333	7/16/2026 4:33:26 PM	1473	34.4366455	-118.6473287	,
CV-2333	7/20/2026 9:04:08 AM	1378	34.4365021	-118.6473609	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2333	7/20/2026 9:05:00 AM				AtmAA
CV-2333	7/27/2026 8:55:36 AM	1349	34.4365097	-118.6473763	Valve Adjustment:No Flow Measurement,High Temp
CV-2334	7/9/2026 7:30:00 AM				AirTech Lab
CV-2334	7/9/2026 7:30:00 AM				AirTech Lab; [User entered 11%]
CV-2334	7/13/2026 8:41:10 AM	1380	34.4366832	-118.6466417	Valve Adjustment:Audible Flow,Reduce Sys. Vac. - Flare Down
CV-2334	7/23/2026 1:50:21 PM	1355	34.4367012	-118.6466953	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2334	7/23/2026 1:52:54 PM	1361	34.4367495	-118.6466877	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2335	7/1/2026 9:46:36 AM	1345	34.4363668	-118.6509692	Valve Adjustment:Barely Open,Surging Liquid in Well (Watered In)
CV-2335	7/16/2026 10:52:46 AM	1345	34.4363748	-118.6509772	Valve Adjustment:Barely Open
CV-2336	7/1/2026 9:53:36 AM	1316	34.4359737	-118.6509037	Valve Adjustment:High O2,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2336	7/16/2026 10:55:43 AM	1345	34.4359847	-118.6509035	Valve Adjustment:High O2,Barely Open
CV-2337	7/1/2026 9:53:55 AM	1324	34.4354664	-118.6507697	Valve Comment:Pump pumping upon arrival;Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2337	7/1/2026 9:57:00 AM				AtmAA
CV-2337	7/8/2026 8:58:06 AM	1343	34.4354566	-118.6507546	Valve Adjustment:No Flow Measurement,High Temp
CV-2337	7/8/2026 9:00:00 AM				AtmAA
CV-2337	7/8/2026 9:00:00 AM				AtmAA; [User entered 6.99%]
CV-2337	7/15/2026 8:40:46 AM	1340	34.4354767	-118.6507644	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2337	7/15/2026 8:42:31 AM	1341	34.4354788	-118.6507708	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Barely Open
CV-2337	7/15/2026 8:45:00 AM				AtmAA
CV-2337	7/22/2026 9:26:17 AM	1338	34.4354700	-118.6507688	Valve Adjustment:High Temp,Increased Flow/Vacuum
CV-2337	7/22/2026 9:26:54 AM	1339	34.4354706	-118.6507675	Valve Adjustment:High Temp
CV-2337	7/29/2026 8:26:34 AM	1329	34.4354604	-118.6507612	Valve Adjustment:High Temp
CV-2338	7/1/2026 9:40:30 AM	1314	34.4348403	-118.6504816	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2338	7/1/2026 9:42:00 AM				AtmAA
CV-2338	7/8/2026 8:45:00 AM				AtmAA
CV-2338	7/8/2026 8:45:00 AM				AtmAA; [User entered 16.57%]
CV-2338	7/8/2026 8:53:18 AM	1320	34.4348464	-118.6504707	Valve Adjustment:No Flow Measurement,High Temp
CV-2338	7/15/2026 8:33:54 AM	1314	34.4348578	-118.6504821	Valve Adjustment:No Flow Measurement,High Temp
CV-2338	7/15/2026 8:35:00 AM				AtmAA
CV-2338	7/22/2026 9:17:45 AM	1323	34.4348661	-118.6504868	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2338	7/29/2026 8:21:59 AM	1315	34.4348691	-118.6504784	Valve Adjustment:No Flow Measurement,High Temp
CV-2339	7/1/2026 9:20:00 AM				AtmAA

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2339	7/1/2026 9:24:19 AM	1327	34.4341830	-118.6502588	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum,Barely Open;Well Condition:Pnumatic Pump Installed
CV-2339	7/1/2026 9:26:06 AM	1328	34.4341829	-118.6502628	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-2339	7/8/2026 8:40:52 AM	1326	34.4341969	-118.6502717	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2339	7/8/2026 8:44:33 AM	1327	34.4341962	-118.6502705	Valve Comment:Valve is hard to adjust well;Valve Adjustment:No Flow Measurement,High Temp
CV-2339	7/15/2026 8:23:25 AM	1319	34.4342006	-118.6502534	Valve Adjustment:No Flow Measurement,High Temp
CV-2339	7/15/2026 8:25:00 AM				AtmAA
CV-2339	7/22/2026 9:08:40 AM	1330	34.4342019	-118.6502719	Valve Comment:Found pump pushing air;Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2339	7/22/2026 9:11:54 AM	1331	34.4342040	-118.6502747	Valve Comment:Found pump pushing air;Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-2339	7/22/2026 9:12:58 AM	1327	34.4342022	-118.6502781	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2341	7/7/2026 9:50:03 AM	1326	34.4336107	-118.6501785	Valve Adjustment:Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
CV-2341	7/16/2026 2:21:29 PM	1314	34.4336177	-118.6501755	Valve Adjustment:Decreased Flow/Vacuum
V-2342A-PL	7/1/2026 10:16:44 AM	1288	34.4341962	-118.6508243	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
V-2342A-PL	7/1/2026 10:25:00 AM				AtmAA
V-2342A-PL	7/8/2026 9:35:00 AM				AtmAA
V-2342A-PL	7/8/2026 9:35:00 AM				AtmAA; [User entered 20.5%]
V-2342A-PL	7/8/2026 9:37:26 AM	1290	34.4342211	-118.6508435	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
V-2342A-PL	7/8/2026 9:37:47 AM	1291	34.4342244	-118.6508362	Valve Adjustment:No Flow Measurement,High Temp
V-2342A-PL	7/15/2026 9:30:00 AM				AtmAA
V-2342A-PL	7/15/2026 9:31:03 AM	1270	34.4342456	-118.6508300	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
V-2342A-PL	7/22/2026 10:55:19 AM	1290	34.4342186	-118.6508368	Valve Adjustment:No Flow Measurement,High Temp
V-2342A-PL	7/29/2026 8:59:38 AM	1290	34.4342316	-118.6508353	Valve Adjustment:No Flow Measurement,High Temp
CV-2343-PLR	7/2/2026 1:25:00 AM				AtmAA
CV-2343-PLR	7/2/2026 1:27:10 PM	1283	34.4332350	-118.6506985	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2343-PLR	7/8/2026 9:27:42 AM	1293	34.4332384	-118.6506930	Valve Adjustment:No Flow Measurement,High Temp
CV-2343-PLR	7/8/2026 9:30:00 AM				AtmAA
CV-2343-PLR	7/8/2026 9:30:00 AM				AtmAA; [User entered 15.95%]
CV-2343-PLR	7/15/2026 9:20:00 AM				AtmAA
CV-2343-PLR	7/15/2026 9:20:56 AM	1291	34.4332486	-118.6507026	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2343-PLR	7/22/2026 10:51:24 AM	1297	34.4332322	-118.6507017	Valve Adjustment:No Flow Measurement,High Temp
CV-2343-PLR	7/29/2026 8:52:02 AM	1303	34.4332304	-118.6506831	Valve Adjustment:No Flow Measurement,High Temp
CV-2344	7/1/2026 8:20:00 AM				AirTech Lab
CV-2344	7/1/2026 8:20:00 AM				AirTech Lab; [User entered 0%]
CV-2344	7/1/2026 10:08:37 AM	1295	34.4329760	-118.6504286	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2344	7/1/2026 10:17:00 AM				AtmAA
CV-2344	7/8/2026 9:24:38 AM	1307	34.4329691	-118.6504396	Valve Adjustment:No Flow Measurement,High Temp
CV-2344	7/8/2026 9:25:00 AM				AtmAA
CV-2344	7/8/2026 9:25:00 AM				AtmAA; [User entered 10.2%]
CV-2344	7/15/2026 9:07:22 AM	1290	34.4329730	-118.6504615	Valve Adjustment:No Flow Measurement,High Temp
CV-2344	7/15/2026 9:15:00 AM				AtmAA
CV-2344	7/22/2026 10:47:52 AM	1304	34.4329961	-118.6504469	Valve Adjustment:No Flow Measurement,High Temp
CV-2344	7/29/2026 8:48:14 AM	1310	34.4329933	-118.6504472	Valve Adjustment:No Flow Measurement,High O2
CV-2345	7/1/2026 8:51:00 AM				AirTech Lab
CV-2345	7/1/2026 8:51:00 AM				AirTech Lab; [User entered 2.7%]
CV-2345	7/3/2026 9:09:08 AM	1297	34.4327648	-118.6501713	Valve Adjustment:Audible Flow;Well Condition:Lorentz Pump Installed
CV-2345	7/28/2026 1:17:28 PM	1293	34.4327282	-118.6501695	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-2345	7/28/2026 1:18:30 PM	1301	34.4327340	-118.6501577	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-2346	7/1/2026 8:10:00 AM				AirTech Lab
CV-2346	7/1/2026 8:10:00 AM				AirTech Lab; [User entered 17%]
CV-2346	7/1/2026 10:04:09 AM	1314	34.4325678	-118.6500719	Valve Adjustment:No Flow Measurement,High Temp
CV-2346	7/1/2026 10:10:00 AM				AtmAA
CV-2346	7/8/2026 9:18:20 AM	1310	34.4325807	-118.6500778	Valve Adjustment:No Flow Measurement,High Temp
CV-2346	7/8/2026 9:20:00 AM				AtmAA
CV-2346	7/8/2026 9:20:00 AM				AtmAA; [User entered 15.35%]
CV-2346	7/15/2026 9:03:00 AM	1289	34.4326098	-118.6500715	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2346	7/15/2026 9:05:00 AM				AtmAA
CV-2346	7/22/2026 10:45:05 AM	1311	34.4326161	-118.6500857	Valve Adjustment:No Flow Measurement,High Temp
CV-2346	7/29/2026 8:44:01 AM	1321	34.4326121	-118.6500729	Valve Adjustment:No Flow Measurement,High Temp
CV-2347	7/1/2026 8:05:00 AM				AirTech Lab
CV-2347	7/1/2026 8:05:00 AM				AirTech Lab; [User entered 5.0%]
CV-2347	7/3/2026 8:56:09 AM	1308	34.4323663	-118.6498422	
CV-2347	7/28/2026 9:44:36 AM	1316	34.4323610	-118.6498173	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2348	7/1/2026 8:00:00 AM				AirTech Lab
CV-2348	7/1/2026 8:00:00 AM				AirTech Lab; [User entered 2.8%]
CV-2348	7/3/2026 8:54:05 AM	1306	34.4321893	-118.6496372	Well Comment:unable to adjust safely
CV-2348	7/30/2026 12:27:31 PM	1321	34.4321613	-118.6496147	Valve Adjustment:NSPS/EG CAI,High Temp;Well Comment:Unable to reach system
CV-2348	7/30/2026 12:28:19 PM	1321	34.4321588	-118.6496113	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2349	7/1/2026 1:45:13 PM	1255	34.4331406	-118.6512268	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2349	7/1/2026 1:50:00 PM				AtmAA
CV-2349	7/2/2026 8:20:00 AM				AirTech Lab
CV-2349	7/2/2026 8:20:00 AM				AirTech Lab; [User entered 8.5%]
CV-2349	7/8/2026 10:21:09 AM	1265	34.4331391	-118.6512657	Valve Adjustment:No Flow Measurement,High Temp
CV-2349	7/8/2026 10:30:00 AM				AtmAA
CV-2349	7/8/2026 10:30:00 AM				AtmAA; [User entered 14.45%]
CV-2349	7/15/2026 10:06:40 AM	1267	34.4331480	-118.6512566	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2349	7/15/2026 10:10:00 AM				AtmAA
CV-2349	7/22/2026 1:58:42 PM	1262	34.4331597	-118.6512214	Valve Adjustment:No Flow Measurement,High Temp
CV-2349	7/29/2026 9:20:49 AM	1272	34.4331689	-118.6512496	Valve Adjustment:No Flow Measurement,High Temp
CV-2350	7/3/2026 7:38:14 AM	1275	34.4327760	-118.6509028	Valve Adjustment:Decreased Flow/Vacuum
CV-2350	7/8/2026 7:40:00 AM				AirTech Lab
CV-2350	7/20/2026 1:03:58 PM	1263	34.4327823	-118.6508778	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2351	7/1/2026 8:40:00 AM				AirTech Lab
CV-2351	7/1/2026 8:40:00 AM				AirTech Lab; [User entered 0.060%]
CV-2351	7/7/2026 10:34:21 AM	1297	34.4351428	-118.6511577	Valve Adjustment:NSPS/EG CAI,High O2,Reduce Sys. Vac. - Flare Down
CV-2351	7/7/2026 10:35:02 AM	1293	34.4351455	-118.6511548	Valve Adjustment:NSPS/EG CAI,High O2,Reduce Sys. Vac. - Flare Down
CV-2351	7/28/2026 2:17:08 PM	1293	34.4351472	-118.6511533	Valve Adjustment:Plugged/Pinched Suspected
CV-2352	7/2/2026 7:50:00 AM				AirTech Lab
CV-2352	7/2/2026 7:50:00 AM				AirTech Lab; [User entered 0%]

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2352	7/2/2026 1:09:51 PM	1291	34.4348650	-118.6510495	Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Positive Static Press.
CV-2352	7/2/2026 1:12:12 PM	1304	34.4348825	-118.6510598	Valve Adjustment:NSPS/EG CAI,High Temp,High O2
CV-2352	7/2/2026 2:00:00 PM				AtmAA
CV-2352	7/2/2026 2:16:24 PM	1293	34.4348422	-118.6510372	Valve Comment:O2 in well due to pump pushing air;Valve Adjustment:No Flow Measurement,High Temp
CV-2352	7/9/2026 10:20:00 AM				AtmAA
CV-2352	7/9/2026 10:20:00 AM				AtmAA; [User entered 10.14%]
CV-2352	7/9/2026 10:28:26 AM	1296	34.4348833	-118.6510393	Valve Comment:Found pump pushing air;Valve Adjustment:No Flow Measurement,High Temp,High O2,Surging Liquid in Well (Watered In)
CV-2352	7/9/2026 10:30:58 AM	1297	34.4348762	-118.6510438	Valve Adjustment:No Flow Measurement,High Temp
CV-2352	7/15/2026 9:35:00 AM				AtmAA
CV-2352	7/15/2026 9:35:39 AM	1279	34.4348727	-118.6510391	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2352	7/22/2026 10:59:08 AM	1299	34.4348706	-118.6510479	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2352	7/29/2026 9:05:16 AM	1300	34.4348723	-118.6510529	Valve Adjustment:No Flow Measurement,High Temp
CV-2353-PLR	7/1/2026 10:24:09 AM	1289	34.4345258	-118.6509166	Valve Adjustment:No Flow Measurement,High Temp
CV-2353-PLR	7/8/2026 8:10:00 AM				AirTech Lab
CV-2353-PLR	7/8/2026 8:10:00 AM				AirTech Lab; [User entered 22%]
CV-2353-PLR	7/28/2026 2:07:19 PM	1282	34.4345217	-118.6508968	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2353-PLR	7/28/2026 2:11:24 PM	1269	34.4345123	-118.6509055	Valve Adjustment:High Temp
CV-2354	7/1/2026 1:52:06 PM	1249	34.4336873	-118.6513352	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2354	7/1/2026 2:04:00 PM				AtmAA
CV-2354	7/8/2026 8:00:00 AM				AirTech Lab
CV-2354	7/8/2026 8:00:00 AM				AirTech Lab; [User entered 17%]
CV-2354	7/8/2026 10:02:59 AM	1267	34.4336959	-118.6513722	Valve Adjustment:No Flow Measurement,High Temp
CV-2354	7/8/2026 10:20:00 AM				AtmAA
CV-2354	7/8/2026 10:20:00 AM				AtmAA; [User entered 15.03%]
CV-2354	7/15/2026 10:23:28 AM	1258	34.4336814	-118.6513542	Valve Adjustment:No Flow Measurement,High Temp
CV-2354	7/15/2026 10:25:00 AM				AtmAA
CV-2354	7/22/2026 2:04:50 PM	1259	34.4336853	-118.6513424	Valve Adjustment:No Flow Measurement,High Temp
CV-2354	7/29/2026 9:14:57 AM	1262	34.4336979	-118.6513400	Valve Adjustment:No Flow Measurement,High Temp
CV-24001	7/1/2026 9:35:32 AM	1323	34.4366320	-118.6509123	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24001	7/16/2026 10:48:16 AM	1342	34.4366265	-118.6509148	Valve Adjustment:Barely Open
CV-24002	7/1/2026 9:27:49 AM	1343	34.4367422	-118.6504652	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24002	7/16/2026 10:43:22 AM	1363	34.4367417	-118.6504627	
CV-24003	7/1/2026 9:12:42 AM	1360	34.4368507	-118.6500722	Valve Adjustment:Decreased Flow/Vacuum
CV-24003	7/16/2026 10:34:14 AM	1359	34.4368767	-118.6500548	Valve Adjustment:Barely Open
CV-24004	7/1/2026 9:08:53 AM	1348	34.4370410	-118.6496782	Valve Adjustment:Decreased Flow/Vacuum
CV-24004	7/16/2026 10:31:15 AM	1376	34.4370565	-118.6496878	Valve Adjustment:Decreased Flow/Vacuum
CV-24006	7/1/2026 10:20:36 AM	1368	34.4363487	-118.6504465	Valve Adjustment:Decreased Flow/Vacuum
CV-24006	7/16/2026 10:18:58 AM	1376	34.4363443	-118.6504510	Valve Adjustment:Barely Open
CV-24007	7/1/2026 10:24:33 AM	1357	34.4365182	-118.6501175	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24007	7/16/2026 10:21:13 AM	1374	34.4365192	-118.6500972	Valve Adjustment:High O2,Barely Open
CV-24008	7/7/2026 8:38:49 AM	1363	34.4366899	-118.6497286	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24008	7/7/2026 8:39:31 AM	1363	34.4366899	-118.6497286	Valve Adjustment:No Flow Measurement,High Temp
CV-24008	7/7/2026 8:45:00 AM				AtmAA
CV-24008	7/7/2026 8:45:00 AM				AtmAA; [User entered 9.73%]
CV-24008	7/13/2026 2:30:36 PM	1386	34.4366827	-118.6496915	Valve Adjustment:No Flow Measurement,High Temp
CV-24008	7/13/2026 2:35:00 PM				AtmAA
CV-24008	7/20/2026 2:10:19 PM	1372	34.4366770	-118.6497041	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24008	7/20/2026 2:11:02 PM	1373	34.4366782	-118.6497015	Valve Adjustment:No Flow Measurement,High Temp
CV-24008	7/20/2026 2:15:00 PM				AtmAA
CV-24008	7/28/2026 7:59:01 AM	1379	34.4366681	-118.6496912	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24008	7/28/2026 7:59:41 AM	1379	34.4366683	-118.6496921	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-24009	7/7/2026 8:34:34 AM	1382	34.4368701	-118.6493624	Valve Adjustment:No Flow Measurement,High Temp
CV-24009	7/7/2026 8:35:11 AM	1382	34.4368691	-118.6493650	Valve Adjustment:High Temp
CV-24009	7/7/2026 8:40:00 AM				AtmAA
CV-24009	7/7/2026 8:40:00 AM				AtmAA; [User entered 10.015%]
CV-24009	7/13/2026 2:26:43 PM	1381	34.4368888	-118.6493717	Valve Adjustment:No Flow Measurement,High Temp
CV-24009	7/13/2026 2:27:24 PM	1381	34.4368882	-118.6493740	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24009	7/13/2026 2:27:53 PM	1382	34.4368875	-118.6493740	Valve Adjustment:No Flow Measurement,High Temp
CV-24009	7/13/2026 2:30:00 PM				AtmAA

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24009	7/20/2026 2:07:05 PM	1372	34.4368757	-118.6493628	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24009	7/20/2026 2:10:00 PM				AtmAA
CV-24009	7/28/2026 7:52:05 AM	1375	34.4368640	-118.6493538	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24009	7/28/2026 7:53:03 AM	1375	34.4368633	-118.6493529	Valve Adjustment:High Temp
CV-24010	7/8/2026 1:33:01 PM	1355	34.4370972	-118.6489710	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In)
CV-24010	7/8/2026 1:34:33 PM	1356	34.4371813	-118.6489767	Valve Adjustment:High O2
CV-24010	7/21/2026 8:23:59 AM	1375	34.4370792	-118.6489587	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24011	7/7/2026 8:50:42 AM	1369	34.4361974	-118.6502064	Valve Adjustment:High Temp
CV-24011	7/7/2026 8:55:00 AM				AtmAA
CV-24011	7/7/2026 8:55:00 AM				AtmAA; [User entered 12.48%]
CV-24011	7/14/2026 8:49:11 AM	1368	34.4361965	-118.6501891	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24011	7/14/2026 8:50:04 AM	1370	34.4361967	-118.6501851	Valve Comment:Pump offline;Valve Adjustment:High Temp
CV-24011	7/14/2026 9:00:00 AM				AtmAA
CV-24011	7/21/2026 8:30:40 AM	1372	34.4362052	-118.6501822	Valve Comment:Lorentz pump disconnected;Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24011	7/28/2026 8:27:29 AM	1367	34.4361984	-118.6501965	Valve Adjustment:High Temp
CV-24012	7/7/2026 9:19:39 AM	1364	34.4361571	-118.6493766	Valve Adjustment:No Flow Measurement,High Temp
CV-24012	7/7/2026 9:20:00 AM				AtmAA
CV-24012	7/7/2026 9:20:00 AM				AtmAA; [User entered 7.85%]
CV-24012	7/14/2026 9:08:24 AM	1375	34.4361708	-118.6493671	Valve Adjustment:No Flow Measurement,High Temp
CV-24012	7/14/2026 9:25:00 AM				AtmAA
CV-24012	7/21/2026 8:39:29 AM	1362	34.4361703	-118.6493605	Valve Adjustment:No Flow Measurement,High Temp
CV-24012	7/28/2026 8:13:47 AM	1359	34.4361724	-118.6493720	Valve Adjustment:No Flow Measurement,High Temp
CV-24013	7/2/2026 1:36:18 PM	1378	34.4366195	-118.6492495	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24013	7/21/2026 7:52:29 AM	1375	34.4365960	-118.6492295	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24014	7/6/2026 10:04:48 AM	1375	34.4367843	-118.6489557	Valve Adjustment:No Flow Measurement,High Temp
CV-24014	7/6/2026 10:25:00 AM				AtmAA
CV-24014	7/6/2026 10:25:00 AM				AtmAA; [User entered 17.48%]
CV-24014	7/13/2026 9:47:14 AM	1382	34.4367815	-118.6489403	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24014	7/13/2026 10:00:00 AM				AtmAA
CV-24014	7/20/2026 9:37:23 AM	1387	34.4367796	-118.6489433	Valve Adjustment:No Flow Measurement,High Temp
CV-24014	7/20/2026 9:40:00 AM				AtmAA
CV-24014	7/27/2026 9:37:20 AM	1368	34.4367769	-118.6489494	Valve Adjustment:No Flow Measurement,High Temp
CV-24015	7/6/2026 9:45:00 AM				AtmAA
CV-24015	7/6/2026 9:45:00 AM				AtmAA; [User entered 17.5%]
CV-24015	7/6/2026 9:55:39 AM	1352	34.4368783	-118.6486242	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24015	7/6/2026 9:57:45 AM	1355	34.4368670	-118.6486264	Valve Adjustment:No Flow Measurement,High Temp
CV-24015	7/13/2026 9:34:45 AM	1367	34.4368721	-118.6486228	Valve Adjustment:No Flow Measurement,High Temp
CV-24015	7/13/2026 9:45:00 AM				AtmAA
CV-24015	7/20/2026 9:34:26 AM	1381	34.4368679	-118.6486137	Valve Adjustment:No Flow Measurement,High Temp
CV-24015	7/20/2026 9:35:00 AM				AtmAA
CV-24015	7/27/2026 9:28:10 AM	1357	34.4368681	-118.6486179	Valve Adjustment:No Flow Measurement,High Temp
CV-24016	7/7/2026 8:59:53 AM	1365	34.4359146	-118.6502619	Valve Adjustment:No Flow Measurement,High Temp
CV-24016	7/7/2026 9:05:00 AM				AtmAA
CV-24016	7/7/2026 9:05:00 AM				AtmAA; [User entered 5.33%]
CV-24016	7/14/2026 8:54:39 AM	1372	34.4358924	-118.6502670	Valve Adjustment:No Flow Measurement,High Temp
CV-24016	7/14/2026 9:10:00 AM				AtmAA
CV-24016	7/21/2026 8:25:11 AM	1361	34.4359076	-118.6502470	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24016	7/28/2026 8:19:06 AM	1365	34.4359005	-118.6502468	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	7/2/2026 9:54:07 AM	1363	34.4361198	-118.6498347	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24017	7/7/2026 9:07:06 AM	1366	34.4361048	-118.6498200	Valve Adjustment:No Flow Measurement,High Temp
CV-24017	7/7/2026 9:10:00 AM				AtmAA
CV-24017	7/7/2026 9:10:00 AM				AtmAA; [User entered 13.61%]
CV-24017	7/13/2026 9:00:00 AM				AirTech Lab
CV-24017	7/13/2026 9:00:00 AM				AirTech Lab; [User entered 18%]
CV-24017	7/14/2026 9:01:41 AM	1368	34.4361082	-118.6498136	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24017	7/14/2026 9:02:10 AM	1369	34.4361086	-118.6498100	Valve Adjustment:No Flow Measurement,High Temp
CV-24017	7/14/2026 9:15:00 AM				AtmAA
CV-24017	7/21/2026 8:34:08 AM	1371	34.4360986	-118.6498090	Valve Comment:Lorentz pump on while collecting reading;Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24017	7/28/2026 8:09:09 AM	1369	34.4361139	-118.6498252	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24018	7/1/2026 1:40:12 PM	1354	34.4356462	-118.6500065	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24018	7/29/2026 2:10:56 PM	1377	34.4356123	-118.6500632	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24018	7/29/2026 2:11:44 PM	1375	34.4355953	-118.6500647	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24019	7/7/2026 9:25:00 AM				AtmAA
CV-24019	7/7/2026 9:25:00 AM				AtmAA; [User entered 10.57%]
CV-24019	7/7/2026 9:29:12 AM	1360	34.4357666	-118.6497731	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24019	7/7/2026 9:29:55 AM	1364	34.4357719	-118.6497704	Valve Adjustment:No Flow Measurement,High Temp
CV-24019	7/14/2026 9:15:49 AM	1369	34.4357848	-118.6497614	Valve Adjustment:No Flow Measurement,High Temp
CV-24019	7/14/2026 9:30:00 AM				AtmAA
CV-24019	7/21/2026 8:48:47 AM	1357	34.4357777	-118.6497523	Valve Adjustment:No Flow Measurement,High Temp
CV-24019	7/28/2026 8:16:19 AM	1357	34.4357702	-118.6497647	Valve Adjustment:No Flow Measurement,High Temp
CV-24020	7/2/2026 1:45:52 PM	1355	34.4359898	-118.6493785	Valve Adjustment:High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24020	7/21/2026 7:57:54 AM	1366	34.4360005	-118.6493433	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24021	7/2/2026 1:50:07 PM	1360	34.4361602	-118.6490407	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24021	7/21/2026 8:09:32 AM	1366	34.4361587	-118.6490302	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24022-PL	7/6/2026 10:15:31 AM	1369	34.4365193	-118.6488105	Valve Adjustment:No Flow Measurement,High Temp
CV-24022-PL	7/6/2026 10:30:00 AM				AtmAA
CV-24022-PL	7/6/2026 10:30:00 AM				AtmAA; [User entered 19.24%]
CV-24022-PL	7/13/2026 9:55:02 AM	1395	34.4365171	-118.6488132	Valve Adjustment:No Flow Measurement,High Temp
CV-24022-PL	7/13/2026 10:05:00 AM				AtmAA
CV-24022-PL	7/20/2026 9:40:24 AM	1392	34.4365097	-118.6488171	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-24022-PL	7/20/2026 9:45:00 AM				AtmAA

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24022-PLL	7/27/2026 9:40:43 AM	1373	34.4365069	-118.6488038	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-24023	7/3/2026 9:30:00 AM				AtmAA
CV-24023	7/3/2026 10:41:33 AM	1352	34.4365868	-118.6484338	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24023	7/6/2026 9:50:00 AM				AtmAA
CV-24023	7/6/2026 9:50:00 AM				AtmAA; [User entered 18.045%]
CV-24023	7/6/2026 10:00:42 AM	1371	34.4365758	-118.6484454	Valve Adjustment:No Flow Measurement,High Temp
CV-24023	7/13/2026 9:42:44 AM	1374	34.4366131	-118.6484458	Valve Adjustment:No Flow Measurement,High Temp
CV-24023	7/13/2026 9:55:00 AM				AtmAA
CV-24023	7/20/2026 9:42:39 AM	1384	34.4365838	-118.6484337	Valve Adjustment:No Flow Measurement,High Temp
CV-24023	7/20/2026 9:50:00 AM				AtmAA
CV-24023	7/27/2026 9:30:57 AM	1368	34.4365810	-118.6484377	Valve Adjustment:No Flow Measurement,High Temp
CV-24024-PLL	7/13/2026 9:00:47 AM	1356	34.4368068	-118.6481355	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24024-PLL	7/13/2026 9:01:05 AM	1352	34.4368073	-118.6481367	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24024-PLL	7/23/2026 8:16:11 AM	1331	34.4368082	-118.6481540	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24024-PLL	7/27/2026 9:18:50 AM	1364	34.4367969	-118.6481736	Valve Adjustment:No Flow Measurement,High Temp
CV-24025	7/7/2026 10:05:00 AM				AtmAA
CV-24025	7/7/2026 10:05:00 AM				AtmAA; [User entered 10.32%]
CV-24025	7/7/2026 10:09:55 AM	1342	34.4352905	-118.6499311	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-24025	7/14/2026 9:41:47 AM	1361	34.4352886	-118.6499287	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-24025	7/14/2026 9:50:00 AM				AtmAA
CV-24025	7/21/2026 9:11:03 AM	1360	34.4352936	-118.6499327	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-24025	7/28/2026 9:23:57 AM	1358	34.4352737	-118.6499174	Valve Comment:Pump turned on;Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24026	7/7/2026 9:35:00 AM				AtmAA
CV-24026	7/7/2026 9:35:00 AM				AtmAA; [User entered 6.8%]
CV-24026	7/7/2026 9:41:18 AM	1349	34.4356594	-118.6492808	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24026	7/7/2026 9:49:00 AM	1350	34.4356596	-118.6492768	Valve Comment:Suspect lorentz pump not working;Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24026	7/14/2026 9:25:45 AM	1364	34.4356555	-118.6492871	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Decreased Flow/Vacuum,Barely Open
CV-24026	7/14/2026 9:27:42 AM	1364	34.4356548	-118.6492847	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-24026	7/14/2026 9:28:29 AM	1365	34.4356552	-118.6492857	Valve Adjustment:No Flow Measurement,High Temp
CV-24026	7/21/2026 8:03:12 AM	1373	34.4356480	-118.6492505	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24027	7/2/2026 1:59:27 PM	1365	34.4361183	-118.6487285	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24027	7/21/2026 8:11:59 AM	1359	34.4361037	-118.6487132	Valve Adjustment:High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-24028	7/6/2026 10:19:46 AM	1358	34.4363525	-118.6484789	Valve Adjustment:No Flow Measurement,High Temp
CV-24028	7/6/2026 10:35:00 AM				AtmAA
CV-24028	7/6/2026 10:35:00 AM				AtmAA; [User entered 17.03%]
CV-24028	7/13/2026 10:06:15 AM	1383	34.4363603	-118.6484749	Valve Adjustment:No Flow Measurement,High Temp
CV-24028	7/13/2026 10:10:00 AM				AtmAA
CV-24028	7/20/2026 9:45:58 AM	1384	34.4363523	-118.6484741	Valve Adjustment:No Flow Measurement,High Temp
CV-24028	7/20/2026 9:55:00 AM				AtmAA
CV-24028	7/27/2026 9:44:15 AM	1366	34.4363442	-118.6484548	Valve Adjustment:No Flow Measurement,High Temp
CV-24029	7/6/2026 7:47:53 AM	1358	34.4364473	-118.6480978	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24029	7/6/2026 7:49:23 AM	1360	34.4364542	-118.6480875	Valve Adjustment:NSPS/EG CAC,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24029	7/23/2026 8:08:33 AM	1345	34.4364687	-118.6480853	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected;Well Condition:Lorentz Pump Installed
CV-24029	7/23/2026 8:09:38 AM	1345	34.4364693	-118.6480730	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24030	7/6/2026 9:27:02 AM	1345	34.4366521	-118.6479050	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,High O2,Decreased Flow/Vacuum
CV-24030	7/6/2026 9:28:14 AM	1347	34.4366584	-118.6479077	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Barely Open
CV-24030	7/6/2026 9:30:00 AM				AtmAA
CV-24030	7/6/2026 9:30:00 AM				AtmAA; [User entered 14.08%]

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24030	7/6/2026 9:39:05 AM	1349	34.4366790	-118.6479311	Valve Adjustment:No Flow Measurement,High Temp
CV-24030	7/13/2026 9:18:53 AM	1356	34.4366558	-118.6478938	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24030	7/13/2026 9:21:12 AM	1356	34.4366560	-118.6479001	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24030	7/13/2026 9:22:29 AM	1356	34.4366593	-118.6479051	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-24030	7/13/2026 9:30:00 AM				AtmAA
CV-24030	7/20/2026 9:13:06 AM	1355	34.4366596	-118.6478954	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24030	7/20/2026 9:14:05 AM	1355	34.4366623	-118.6478980	Valve Adjustment:No Flow Measurement,High Temp
CV-24030	7/20/2026 9:20:00 AM				AtmAA
CV-24030	7/27/2026 9:09:52 AM	1352	34.4366582	-118.6478919	Valve Adjustment:No Flow Measurement,High Temp,High O2,Decreased Flow/Vacuum,Barely Open
CV-24030	7/27/2026 9:12:05 AM	1355	34.4366666	-118.6478893	Valve Comment:Suspect Lorentz pump not working;Valve Adjustment:No Flow Measurement,High Temp,High O2,Barely Open
CV-24031	7/1/2026 1:57:55 PM	1332	34.4348118	-118.6497717	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24031	7/2/2026 10:12:38 AM	1351	34.4348887	-118.6498193	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24031	7/2/2026 10:20:00 AM				AtmAA
CV-24031	7/7/2026 10:23:01 AM	1344	34.4348781	-118.6498281	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24031	7/7/2026 10:23:43 AM	1342	34.4348777	-118.6498247	Valve Adjustment:No Flow Measurement,High Temp
CV-24031	7/7/2026 10:25:00 AM				AtmAA
CV-24031	7/7/2026 10:25:00 AM				AtmAA; [User entered 1.28%]
CV-24031	7/14/2026 9:38:15 AM	1358	34.4348801	-118.6498065	Valve Adjustment:No Flow Measurement,High Temp
CV-24031	7/14/2026 9:45:00 AM				AtmAA
CV-24031	7/21/2026 9:07:39 AM	1352	34.4348900	-118.6498239	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24031	7/28/2026 9:26:57 AM	1354	34.4348889	-118.6498231	Valve Adjustment:No Flow Measurement,High Temp
CV-24032	7/7/2026 10:05:00 AM				AtmAA; [User entered 10.32%]
CV-24032	7/7/2026 10:14:38 AM	1341	34.4351089	-118.6496386	Valve Adjustment:No Flow Measurement,High Temp
CV-24032	7/7/2026 10:15:00 AM				AtmAA
CV-24032	7/7/2026 10:15:00 AM				AtmAA; [User entered 10.22%]
CV-24032	7/14/2026 9:35:53 AM	1355	34.4351161	-118.6496305	Valve Adjustment:No Flow Measurement,High Temp
CV-24032	7/14/2026 9:40:00 AM				AtmAA

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24032	7/21/2026 9:04:20 AM	1347	34.4351166	-118.6496229	Valve Adjustment:No Flow Measurement,High Temp
CV-24032	7/28/2026 9:12:58 AM	1359	34.4351040	-118.6496307	Valve Adjustment:No Flow Measurement,High Temp
CV-24033	7/7/2026 9:57:36 AM	1345	34.4353438	-118.6494572	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24033	7/7/2026 9:59:21 AM	1346	34.4353462	-118.6494644	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-24033	7/29/2026 2:05:34 PM	1340	34.4353280	-118.6494738	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24033	7/29/2026 2:05:59 PM	1348	34.4353297	-118.6494688	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-24034	7/6/2026 10:26:57 AM	1354	34.4361119	-118.6481287	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24034	7/6/2026 10:28:02 AM	1353	34.4361075	-118.6481263	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Barely Open
CV-24034	7/6/2026 10:45:00 AM				AtmAA
CV-24034	7/6/2026 10:45:00 AM				AtmAA; [User entered 15.68%]
CV-24034	7/13/2026 10:15:00 AM				AtmAA
CV-24034	7/13/2026 10:15:08 AM	1363	34.4361237	-118.6481053	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24034	7/13/2026 10:16:16 AM	1364	34.4361296	-118.6481024	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-24034	7/20/2026 9:53:07 AM	1375	34.4361203	-118.6481204	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum,Barely Open
CV-24034	7/20/2026 9:53:35 AM	1375	34.4361197	-118.6481201	Valve Adjustment:No Flow Measurement,High Temp
CV-24034	7/20/2026 10:00:00 AM				AtmAA
CV-24034	7/27/2026 10:35:43 AM	1354	34.4361128	-118.6481225	Valve Adjustment:Audible Flow,High Temp,Decreased Flow/Vacuum
CV-24034	7/27/2026 10:36:13 AM	1355	34.4361142	-118.6481211	Valve Adjustment:No Flow Measurement,High Temp
CV-24035-PL	7/6/2026 9:05:37 AM	1376	34.4363623	-118.6477466	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-24035-PL	7/6/2026 9:10:00 AM				AtmAA
CV-24035-PL	7/6/2026 9:10:00 AM				AtmAA; [User entered 13.445%]
CV-24035-PL	7/13/2026 8:51:05 AM	1374	34.4363714	-118.6477187	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-24035-PL	7/13/2026 9:10:00 AM				AtmAA
CV-24035-PL	7/20/2026 8:57:32 AM	1376	34.4363515	-118.6477210	Valve Adjustment:No Flow Measurement,High Temp
CV-24035-PL	7/20/2026 9:00:00 AM				AtmAA

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24035-PLI	7/27/2026 8:46:51 AM	1362	34.4363708	-118.6477376	Valve Adjustment:No Flow Measurement,High Temp
CV-24036	7/1/2026 2:03:29 PM	1324	34.4344553	-118.6497217	Valve Adjustment:Barely Open
CV-24036	7/2/2026 12:42:35 PM	1337	34.4344552	-118.6497063	Valve Adjustment:Increased Flow/Vacuum
CV-24036	7/29/2026 1:56:07 PM	1343	34.4344390	-118.6497263	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24037	7/1/2026 2:18:36 PM	1319	34.4347343	-118.6494595	Valve Adjustment:Decreased Flow/Vacuum
CV-24037	7/1/2026 2:19:56 PM	1329	34.4347393	-118.6494505	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24037	7/29/2026 1:50:59 PM	1349	34.4347512	-118.6494475	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24038	7/7/2026 1:32:14 PM	1354	34.4350069	-118.6488301	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24038	7/7/2026 1:33:35 PM	1356	34.4350093	-118.6488244	Valve Adjustment:No Flow Measurement,High Temp
CV-24038	7/7/2026 1:35:00 PM				AtmAA
CV-24038	7/7/2026 1:35:00 PM				AtmAA; [User entered 10.155%]
CV-24038	7/14/2026 10:14:43 AM	1344	34.4350259	-118.6488795	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24038	7/14/2026 10:15:00 AM				AtmAA
CV-24038	7/14/2026 10:15:17 AM	1343	34.4350276	-118.6488716	Valve Adjustment:No Flow Measurement,High Temp
CV-24038	7/21/2026 10:10:15 AM	1342	34.4350237	-118.6488854	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24038	7/21/2026 10:11:14 AM	1343	34.4350216	-118.6488909	Valve Comment:Pump disconnected;Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-24038	7/28/2026 9:31:51 AM	1343	34.4350056	-118.6488763	Valve Comment:Pump is disconnected;Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24039	7/7/2026 2:00:00 PM				AtmAA
CV-24039	7/7/2026 2:00:00 PM				AtmAA; [User entered 11.62%]
CV-24039	7/7/2026 2:04:06 PM	1353	34.4352831	-118.6486713	Valve Adjustment:No Flow Measurement,High Temp
CV-24039	7/7/2026 2:04:59 PM	1352	34.4352831	-118.6486722	Valve Adjustment:No Flow Measurement,High Temp
CV-24039	7/14/2026 1:04:46 PM	1352	34.4352782	-118.6486737	Valve Adjustment:No Flow Measurement,High Temp
CV-24039	7/14/2026 1:09:42 PM	1353	34.4352757	-118.6486730	Valve Adjustment:No Flow Measurement,High Temp
CV-24039	7/14/2026 1:10:00 PM				AtmAA
CV-24039	7/21/2026 10:31:01 AM	1354	34.4352932	-118.6486829	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24039	7/28/2026 10:01:04 AM	1350	34.4352941	-118.6486741	Valve Adjustment:No Flow Measurement,High Temp
CV-24040	7/2/2026 2:03:23 PM	1358	34.4356355	-118.6483863	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24040	7/7/2026 2:10:03 PM	1349	34.4356552	-118.6483903	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24040	7/7/2026 2:11:41 PM	1348	34.4356514	-118.6483939	Valve Adjustment:No Flow Measurement,High Temp
CV-24040	7/7/2026 2:15:00 PM				AtmAA
CV-24040	7/7/2026 2:15:00 PM				AtmAA; [User entered 15.24%]
CV-24040	7/13/2026 10:32:47 AM	1359	34.4356477	-118.6483877	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24040	7/13/2026 10:34:01 AM	1358	34.4356484	-118.6483785	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-24040	7/13/2026 10:40:00 AM				AtmAA
CV-24040	7/21/2026 10:28:33 AM	1353	34.4356491	-118.6483957	Valve Adjustment:No Flow Measurement,High Temp
CV-24040	7/28/2026 10:07:52 AM	1353	34.4356443	-118.6483706	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24041	7/2/2026 2:06:37 PM	1357	34.4358572	-118.6480380	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24041	7/21/2026 8:16:04 AM	1363	34.4358623	-118.6480288	Valve Adjustment:High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-24042	7/6/2026 10:39:05 AM	1374	34.4362656	-118.6474772	Valve Adjustment:No Flow Measurement,High Temp
CV-24042	7/6/2026 10:40:03 AM	1374	34.4362618	-118.6474744	Valve Adjustment:No Flow Measurement,High Temp
CV-24042	7/6/2026 10:55:00 AM				AtmAA
CV-24042	7/6/2026 10:55:00 AM				AtmAA; [User entered 12.48%]
CV-24042	7/13/2026 10:25:00 AM				AtmAA
CV-24042	7/13/2026 10:25:01 AM	1374	34.4362387	-118.6474717	Valve Adjustment:No Flow Measurement,High Temp
CV-24042	7/20/2026 9:58:34 AM	1383	34.4362345	-118.6474679	Valve Adjustment:No Flow Measurement,High Temp
CV-24042	7/20/2026 10:10:00 AM				AtmAA
CV-24042	7/27/2026 10:43:38 AM	1375	34.4362497	-118.6474751	Valve Adjustment:No Flow Measurement,High Temp
CV-24043	7/10/2026 10:12:45 AM	1331	34.4340927	-118.6497150	Valve Comment:well too tall for system read
CV-24043	7/16/2026 2:32:38 PM	1334	34.4341092	-118.6496975	Well Comment:well is too tall
CV-24044	7/1/2026 2:08:53 PM	1325	34.4343792	-118.6494050	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24044	7/22/2026 1:39:48 PM	1342	34.4343777	-118.6493702	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24044	7/30/2026 9:59:51 AM	1355	34.4343948	-118.6494133	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24045	7/7/2026 1:38:11 PM	1344	34.4347454	-118.6490587	Valve Adjustment:No Flow Measurement,High Temp
CV-24045	7/7/2026 1:40:00 PM				AtmAA
CV-24045	7/7/2026 1:40:00 PM				AtmAA; [User entered 13.12%]
CV-24045	7/14/2026 10:17:58 AM	1346	34.4347584	-118.6490619	Valve Adjustment:No Flow Measurement,High Temp
CV-24045	7/14/2026 10:20:00 AM				AtmAA
CV-24045	7/21/2026 10:14:16 AM	1345	34.4347540	-118.6490845	Valve Adjustment:No Flow Measurement,High Temp
CV-24045	7/28/2026 9:44:32 AM	1348	34.4347531	-118.6490348	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24045	7/28/2026 9:46:42 AM	1349	34.4347481	-118.6490474	Valve Comment:Pump disconnected;Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-24046	7/7/2026 1:54:14 PM	1353	34.4350856	-118.6483584	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum,Barely Open
CV-24046	7/7/2026 1:55:00 PM				AtmAA
CV-24046	7/7/2026 1:55:00 PM				AtmAA; [User entered 15.56%]
CV-24046	7/7/2026 1:56:03 PM	1353	34.4350821	-118.6483616	Valve Comment:Pump turned on;Valve Adjustment:No Flow Measurement,High Temp
CV-24046	7/14/2026 1:13:28 PM	1348	34.4350771	-118.6483796	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-24046	7/14/2026 1:14:02 PM	1348	34.4350739	-118.6483760	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-24046	7/21/2026 10:33:20 AM	1352	34.4350851	-118.6483832	Valve Adjustment:No Flow Measurement,High Temp
CV-24046	7/28/2026 10:18:26 AM	1357	34.4350913	-118.6483610	Valve Adjustment:No Flow Measurement,High Temp
CV-24048	7/2/2026 2:12:30 PM	1365	34.4355613	-118.6477880	
CV-24048	7/21/2026 8:18:43 AM	1356	34.4355583	-118.6477967	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24049	7/6/2026 1:38:16 PM	1369	34.4359477	-118.6471866	Valve Adjustment:No Flow Measurement,High Temp
CV-24049	7/6/2026 4:50:00 PM				AtmAA
CV-24049	7/6/2026 4:50:00 PM				AtmAA; [User entered 11.88%]
CV-24049	7/13/2026 9:10:00 AM				AirTech Lab
CV-24049	7/13/2026 9:10:00 AM				AirTech Lab; [User entered 13%]
CV-24049	7/13/2026 1:14:21 PM	1383	34.4359778	-118.6472174	Valve Adjustment:No Flow Measurement,High Temp
CV-24049	7/13/2026 1:20:00 PM				AtmAA
CV-24049	7/20/2026 10:13:54 AM	1382	34.4359477	-118.6471820	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-24049	7/20/2026 10:30:00 AM				AtmAA

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24049	7/27/2026 1:26:59 PM	1368	34.4359625	-118.6471874	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24049	7/27/2026 1:30:09 PM	1377	34.4356495	-118.6471739	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24050	7/7/2026 9:56:00 AM	1328	34.4337087	-118.6499647	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-24050	7/16/2026 2:26:11 PM	1324	34.4337577	-118.6499452	Valve Adjustment:Valve 100% Open
CV-24051	7/8/2026 10:40:27 AM	1345	34.4344580	-118.6490273	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-24051	7/8/2026 10:41:15 AM	1345	34.4344642	-118.6490285	Valve Adjustment:NSPS/EG CAC
CV-24051	7/22/2026 1:46:52 PM	1360	34.4344347	-118.6490423	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24052	7/2/2026 2:24:37 PM	1365	34.4350717	-118.6480408	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24052	7/21/2026 1:52:36 PM	1366	34.4350740	-118.6480718	Valve Adjustment:Decreased Flow/Vacuum
CV-24053	7/2/2026 2:21:41 PM	1378	34.4352437	-118.6478018	Valve Adjustment:Decreased Flow/Vacuum
CV-24053	7/10/2026 10:33:54 AM	1367	34.4352618	-118.6477902	Valve Adjustment:Decreased Flow/Vacuum
CV-24053	7/13/2026 7:15:00 AM				AirTech Lab
CV-24053	7/13/2026 7:15:00 AM				AirTech Lab; [User entered 1.5%]
CV-24053	7/21/2026 1:39:10 PM	1367	34.4352280	-118.6477988	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24054	7/6/2026 1:41:08 PM	1372	34.4356337	-118.6471738	Valve Adjustment:No Flow Measurement,High Temp
CV-24054	7/6/2026 2:00:00 PM				AtmAA
CV-24054	7/6/2026 2:00:00 PM				AtmAA; [User entered 11.51%]
CV-24054	7/13/2026 1:16:50 PM	1387	34.4356518	-118.6471842	Valve Adjustment:No Flow Measurement,High Temp
CV-24054	7/13/2026 1:25:00 PM				AtmAA
CV-24054	7/20/2026 10:09:45 AM	1386	34.4356342	-118.6471754	Valve Adjustment:No Flow Measurement,High Temp
CV-24054	7/20/2026 10:10:46 AM	1386	34.4356348	-118.6471744	Valve Comment:Pneumatic pump installed;Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24054	7/20/2026 10:25:00 AM				AtmAA
CV-24055	7/9/2026 3:17:18 PM	1430	34.4359242	-118.6468808	High Temp,
CV-24055	7/9/2026 3:18:58 PM	1437	34.4358823	-118.6469773	,
CV-24055	7/23/2026 9:27:41 AM	1389	34.4358707	-118.6469348	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24056	7/3/2026 7:21:57 AM	1324	34.4332725	-118.6501695	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Good
CV-24056	7/20/2026 10:21:42 AM	1332	34.4332783	-118.6501608	Valve Adjustment:Barely Open

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24057	7/1/2026 9:08:14 AM	1340	34.4334521	-118.6496523	Valve Comment:Pump turned on;Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open;Well Condition:Lorentz Pump Installed
CV-24057	7/1/2026 9:09:49 AM	1338	34.4334528	-118.6496578	Valve Adjustment:High Temp,Barely Open;Well Condition:Lorentz Pump Installed
CV-24057	7/16/2026 2:15:14 PM	1326	34.4334732	-118.6496440	Valve Adjustment:High Temp,Barely Open;Well Condition:Lorentz Pump Installed
CV-24058	7/7/2026 9:36:58 AM	1360	34.4337900	-118.6494458	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-24058	7/16/2026 2:42:08 PM	1314	34.4337877	-118.6494828	
CV-24059	7/2/2026 10:50:00 AM				AtmAA
CV-24059	7/2/2026 10:56:24 AM	1354	34.4337650	-118.6490832	Valve Adjustment:Audible Flow,High Temp
CV-24059	7/8/2026 1:16:56 PM	1345	34.4337723	-118.6490663	Valve Adjustment:No Flow Measurement,High Temp
CV-24059	7/8/2026 1:20:00 PM				AtmAA
CV-24059	7/8/2026 1:20:00 PM				AtmAA; [User entered 11.025%]
CV-24059	7/16/2026 2:16:47 PM	1354	34.4337637	-118.6491015	Valve Adjustment:High Temp
CV-24059	7/16/2026 2:54:28 PM	1338	34.4337652	-118.6490717	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-24059	7/22/2026 2:25:32 PM	1336	34.4337647	-118.6490215	Valve Adjustment:No Flow Measurement,High Temp
CV-24059	7/30/2026 9:45:59 AM	1343	34.4337625	-118.6490759	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24060	7/6/2026 3:24:50 PM	1365	34.4339267	-118.6487497	,
CV-24060	7/17/2026 7:49:21 AM	1345	34.4340213	-118.6487963	Valve Adjustment:Decreased Flow/Vacuum,Barely Open;Well Condition:Lorentz Pump Installed
CV-24061	7/8/2026 2:27:26 PM	1401	34.4343810	-118.6487068	High Temp,
CV-24061	7/8/2026 2:28:35 PM	1385	34.4343833	-118.6487092	,
CV-24061	7/29/2026 9:43:44 AM	1348	34.4343520	-118.6486267	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24062	7/6/2026 8:20:00 AM				AirTech Lab
CV-24062	7/6/2026 8:20:00 AM				AirTech Lab; [User entered 2.7%]
CV-24062	7/8/2026 2:06:55 PM	1377	34.4345524	-118.6480682	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24062	7/8/2026 2:08:53 PM	1377	34.4345637	-118.6480821	Valve Adjustment:No Flow Measurement,High Temp
CV-24062	7/8/2026 2:10:00 PM				AtmAA
CV-24062	7/8/2026 2:10:00 PM				AtmAA; [User entered 6.54%]
CV-24062	7/14/2026 1:31:33 PM	1378	34.4345961	-118.6480895	Valve Adjustment:No Flow Measurement,High Temp
CV-24062	7/14/2026 1:40:00 PM				AtmAA
CV-24062	7/21/2026 1:00:32 PM	1362	34.4346069	-118.6481031	Valve Adjustment:No Flow Measurement,High Temp
CV-24062	7/29/2026 12:56:17 PM	1364	34.4345842	-118.6481275	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24063	7/6/2026 8:15:00 AM				AirTech Lab

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24063	7/6/2026 8:15:00 AM				AirTech Lab; [User entered 3.7%]
CV-24063	7/8/2026 2:23:32 PM	1365	34.4349511	-118.6475301	Valve Adjustment:No Flow Measurement,High Temp
CV-24063	7/8/2026 2:30:00 PM				AtmAA
CV-24063	7/8/2026 2:30:00 PM				AtmAA; [User entered 8.6%]
CV-24063	7/14/2026 1:24:44 PM	1373	34.4349507	-118.6475255	Valve Adjustment:No Flow Measurement,High Temp
CV-24063	7/14/2026 1:30:00 PM				AtmAA
CV-24063	7/21/2026 12:54:42 PM	1371	34.4349616	-118.6475325	Valve Adjustment:No Flow Measurement,High Temp
CV-24063	7/29/2026 1:02:30 PM	1372	34.4349573	-118.6475250	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24064-PL	7/6/2026 8:10:00 AM				AirTech Lab
CV-24064-PL	7/6/2026 8:10:00 AM				AirTech Lab; [User entered 3.4%]
CV-24064-PL	7/6/2026 2:33:01 PM	1369	34.4352361	-118.6471504	Valve Adjustment:No Flow Measurement,High Temp
CV-24064-PL	7/6/2026 2:50:00 PM				AtmAA
CV-24064-PL	7/6/2026 2:50:00 PM				AtmAA; [User entered 11.43%]
CV-24064-PL	7/15/2026 1:24:20 PM	1384	34.4352498	-118.6471728	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-24064-PL	7/15/2026 1:25:00 PM				AtmAA
CV-24064-PL	7/28/2026 1:23:22 PM	1365	34.4352228	-118.6471381	Valve Adjustment:No Flow Measurement,High Temp
V-24065-TP1	7/6/2026 9:55:14 AM	1398	34.4356180	-118.6468198	Valve Adjustment:Barely Open
V-24065-TP1	7/13/2026 8:45:00 AM				AirTech Lab
V-24065-TP1	7/13/2026 8:45:00 AM				AirTech Lab; [User entered 0.33%]
V-24065-TP1	7/20/2026 9:11:35 AM	1417	34.4356340	-118.6467915	,
CV-24066	7/3/2026 7:16:42 AM	1327	34.4330108	-118.6498035	
CV-24066	7/13/2026 9:20:00 AM				AirTech Lab
CV-24066	7/13/2026 9:20:00 AM				AirTech Lab; [User entered 2.3%]
CV-24066	7/30/2026 12:31:20 PM	1326	34.4330025	-118.6497970	
CV-24067	7/1/2026 8:55:09 AM	1334	34.4331519	-118.6497387	Valve Adjustment:High Temp
CV-24067	7/1/2026 9:00:00 AM				AtmAA
CV-24067	7/3/2026 7:13:48 AM	1320	34.4331795	-118.6497502	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24067	7/3/2026 7:14:32 AM	1321	34.4331953	-118.6497533	Valve Adjustment:NSPS/EG CAC
CV-24067	7/20/2026 9:54:51 AM	1330	34.4332067	-118.6497225	Valve Adjustment:High Temp,Barely Open
CV-24067	7/22/2026 8:59:39 AM	1329	34.4331798	-118.6497389	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24067	7/22/2026 9:00:05 AM	1331	34.4331861	-118.6497347	Valve Adjustment:No Flow Measurement,High Temp
CV-24067	7/29/2026 8:12:32 AM	1339	34.4331759	-118.6497329	Valve Adjustment:High Temp
CV-24068	7/7/2026 9:20:23 AM	1349	34.4332320	-118.6493493	Valve Adjustment:NSPS/EG CAC,Reduce Sys. Vac. - Flare Down
CV-24068	7/20/2026 9:57:51 AM	1324	34.4329892	-118.6497857	Valve Adjustment:Barely Open
CV-24069	7/6/2026 8:30:00 AM				AirTech Lab
CV-24069	7/6/2026 8:30:00 AM				AirTech Lab; [User entered 0.86%]

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24069	7/8/2026 10:32:20 AM	1347	34.4334053	-118.6489165	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-24069	7/16/2026 2:59:51 PM	1346	34.4334268	-118.6489613	Valve Adjustment:Barely Open
CV-24070	7/6/2026 8:35:00 AM				AirTech Lab
CV-24070	7/6/2026 8:35:00 AM				AirTech Lab; [User entered 8.6%]
CV-24070	7/6/2026 3:45:09 PM	1362	34.4336607	-118.6486102	High Temp,
CV-24070	7/6/2026 3:46:17 PM	1362	34.4336500	-118.6486633	,
CV-24070	7/13/2026 2:59:42 PM	1351	34.4337150	-118.6486802	Valve Adjustment:High Temp,Increased Flow/Vacuum
CV-24070	7/13/2026 3:00:00 PM				AtmAA
CV-24070	7/13/2026 3:00:43 PM	1352	34.4337148	-118.6486811	Valve Adjustment:High Temp
CV-24070	7/16/2026 3:03:30 PM	1345	34.4337210	-118.6487043	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24070	7/30/2026 9:51:32 AM	1353	34.4337100	-118.6487093	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24071	7/6/2026 3:18:36 PM	1316	34.4340065	-118.6485530	High Temp,
CV-24071	7/6/2026 3:19:46 PM	1345	34.4338997	-118.6486800	,
CV-24071	7/8/2026 8:25:00 AM				AirTech Lab
CV-24071	7/8/2026 8:25:00 AM				AirTech Lab; [User entered 8.3%]
CV-24071	7/17/2026 7:53:19 AM	1353	34.4340005	-118.6484900	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24071	7/17/2026 7:54:08 AM	1359	34.4339990	-118.6484935	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24072	7/6/2026 1:06:35 PM	1444	34.4343647	-118.6480062	,
CV-24072	7/17/2026 8:54:50 AM	1348	34.4341590	-118.6480438	Valve Adjustment:Barely Open;Well Condition:Lorentz Pump Installed
V-24073-TP1	7/2/2026 3:17:49 PM	1391	34.4345788	-118.6478377	NSPS/EG CAI,High Temp
V-24073-TP1	7/2/2026 3:20:38 PM	1352	34.4346430	-118.6476890	,
V-24073-TP1	7/8/2026 2:14:44 PM	1377	34.4346446	-118.6477192	Valve Adjustment:No Flow Measurement,High Temp
V-24073-TP1	7/8/2026 2:20:00 PM				AtmAA; [User entered 4.84%]
V-24073-TP1	7/16/2026 10:10:00 AM				AtmAA
V-24073-TP1	7/16/2026 10:10:07 AM	1362	34.4346206	-118.6477069	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
V-24073-TP1	7/16/2026 10:10:25 AM	1362	34.4346200	-118.6477045	Valve Adjustment:No Flow Measurement,High Temp
V-24073-TP1	7/21/2026 1:03:11 PM	1377	34.4346540	-118.6477166	Valve Adjustment:No Flow Measurement,High Temp
V-24073-TP1	7/29/2026 1:08:41 PM	1377	34.4346154	-118.6477386	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24074	7/2/2026 3:13:30 PM	1365	34.4348463	-118.6474788	,
CV-24074	7/22/2026 2:20:45 PM	1370	34.4347375	-118.6474002	Valve Adjustment:Decreased Flow/Vacuum,Barely Open

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
V-24075-TP1	7/2/2026 9:39:29 AM	1368	34.4350317	-118.6471367	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:Hard pipped
V-24075-TP1	7/6/2026 3:01:23 PM	1371	34.4350245	-118.6471239	Valve Adjustment:No Flow Measurement,High Temp
V-24075-TP1	7/6/2026 3:02:24 PM	1372	34.4350244	-118.6471295	Valve Adjustment:No Flow Measurement,High Temp
V-24075-TP1	7/6/2026 3:05:00 PM				AtmAA
V-24075-TP1	7/6/2026 3:05:00 PM				AtmAA; [User entered 10.99%]
V-24075-TP1	7/15/2026 1:29:30 PM	1380	34.4350427	-118.6471426	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
V-24075-TP1	7/15/2026 1:30:02 PM	1380	34.4350409	-118.6471436	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
V-24075-TP1	7/15/2026 1:35:00 PM				AtmAA
V-24075-TP1	7/28/2026 1:27:30 PM	1377	34.4350218	-118.6471180	Valve Adjustment:No Flow Measurement,High Temp
CV-24076	7/6/2026 2:07:53 PM	1381	34.4353120	-118.6468943	Valve Adjustment:High Temp
CV-24076	7/6/2026 2:10:00 PM				AtmAA
CV-24076	7/6/2026 2:10:00 PM				AtmAA; [User entered 5.195%]
CV-24076	7/13/2026 1:23:31 PM	1387	34.4353274	-118.6468858	Valve Adjustment:No Flow Measurement,High Temp
CV-24076	7/13/2026 1:35:00 PM				AtmAA
CV-24076	7/20/2026 2:30:00 PM				AtmAA
CV-24076	7/20/2026 2:31:50 PM	1373	34.4352933	-118.6468738	Valve Adjustment:High Temp
CV-24076	7/27/2026 1:40:02 PM	1383	34.4353247	-118.6468944	Valve Adjustment:High Temp
CV-24077	7/1/2026 8:48:35 AM	1343	34.4326588	-118.6492893	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24077	7/1/2026 8:50:00 AM				AtmAA
CV-24077	7/8/2026 8:28:44 AM	1322	34.4327065	-118.6493304	Valve Adjustment:No Flow Measurement,High Temp
CV-24077	7/8/2026 8:30:00 AM				AtmAA
CV-24077	7/8/2026 8:30:00 AM				AtmAA; [User entered 3.515%]
CV-24077	7/15/2026 8:09:17 AM	1334	34.4326849	-118.6493408	Valve Adjustment:No Flow Measurement,High Temp
CV-24077	7/15/2026 8:10:00 AM				AtmAA
CV-24077	7/20/2026 9:49:45 AM	1343	34.4326903	-118.6493107	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open
CV-24077	7/22/2026 8:54:23 AM	1339	34.4327007	-118.6493123	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24077	7/22/2026 8:54:59 AM	1339	34.4326900	-118.6493104	Valve Adjustment:No Flow Measurement,High Temp
CV-24077	7/29/2026 8:07:00 AM	1342	34.4327009	-118.6493174	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24078	7/3/2026 7:09:44 AM	1324	34.4328967	-118.6494352	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24078	7/20/2026 9:52:27 AM	1326	34.4328947	-118.6494310	Valve Adjustment:Barely Open

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24079-TP	7/7/2026 9:15:40 AM	1347	34.4329873	-118.6491468	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down
CV-24079-TP	7/7/2026 9:16:34 AM	1351	34.4329953	-118.6491278	Valve Adjustment:NSPS/EG CAI,High Temp,Reduce Sys. Vac. - Flare Down
CV-24079-TP	7/13/2026 7:31:55 AM	1283	34.4329625	-118.6491792	Valve Adjustment:Decreased Flow/Vacuum;Well Comment:pump deactivated.;Well Condition:Lorentz Pump Installed
CV-24079-TP	7/13/2026 7:42:05 AM	1366	34.4330223	-118.6491248	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Plugged/Pinched Suspected;Well Condition:Lorentz Pump Installed
CV-24079-TP	7/29/2026 9:09:16 AM	1341	34.4329958	-118.6491137	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24079-TP	7/29/2026 9:15:45 AM	1339	34.4330027	-118.6491232	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24080	7/7/2026 9:11:34 AM	1359	34.4331277	-118.6488748	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-24080	7/29/2026 9:05:55 AM	1358	34.4331555	-118.6488735	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
V-24081-TP1	7/6/2026 3:54:09 PM	1391	34.4330450	-118.6484820	,
V-24081-TP1	7/16/2026 3:11:01 PM	1352	34.4334258	-118.6485950	Valve Adjustment:Barely Open
CV-24082	7/6/2026 3:07:02 PM	1286	34.4335568	-118.6483698	,
CV-24082	7/17/2026 8:13:54 AM	1367	34.4334262	-118.6483480	Valve Adjustment:Decreased Flow/Vacuum
CV-24083	7/2/2026 1:14:35 PM	1364	34.4337137	-118.6483364	Valve Adjustment:No Flow Measurement,High Temp
CV-24083	7/2/2026 1:15:00 PM				AtmAA
CV-24083	7/6/2026 3:15:00 PM				AtmAA
CV-24083	7/6/2026 3:15:00 PM				AtmAA; [User entered 9.6%]
CV-24083	7/6/2026 3:17:19 PM	1361	34.4336988	-118.6483361	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24083	7/6/2026 3:18:50 PM	1361	34.4337056	-118.6483377	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-24083	7/6/2026 3:19:25 PM	1361	34.4337054	-118.6483383	Valve Adjustment:No Flow Measurement,High Temp
CV-24083	7/16/2026 10:27:18 AM	1364	34.4336855	-118.6483448	Valve Adjustment:No Flow Measurement,High Temp
CV-24083	7/16/2026 10:30:00 AM				AtmAA
CV-24083	7/17/2026 8:09:38 AM	1364	34.4336923	-118.6483597	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24083	7/21/2026 1:36:33 PM	1349	34.4337164	-118.6483550	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24083	7/21/2026 1:37:02 PM	1350	34.4337156	-118.6483506	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24083	7/30/2026 10:16:56 AM	1366	34.4337088	-118.6483533	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
V-24084-TP1	7/8/2026 1:30:00 PM				AtmAA
V-24084-TP1	7/8/2026 1:30:00 PM				AtmAA; [User entered 10.14%]
V-24084-TP1	7/8/2026 1:30:26 PM	1372	34.4338572	-118.6480412	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
V-24084-TP1	7/16/2026 10:24:02 AM	1366	34.4338449	-118.6480312	Valve Adjustment:No Flow Measurement,High Temp
V-24084-TP1	7/16/2026 10:25:00 AM				AtmAA
V-24084-TP1	7/21/2026 1:27:39 PM	1345	34.4338583	-118.6480623	Valve Adjustment:No Flow Measurement,High Temp
V-24084-TP1	7/29/2026 1:25:41 PM	1367	34.4338471	-118.6480434	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24085	7/7/2026 12:01:16 PM	1362	34.4323937	-118.6490225	,
CV-24085	7/16/2026 9:52:28 AM	1371	34.4324250	-118.6490320	High Temp,
CV-24085	7/16/2026 9:54:37 AM	1398	34.4325903	-118.6490727	,
CV-24086	7/7/2026 8:58:12 AM	1364	34.4328937	-118.6487035	Valve Adjustment:Audible Flow,Barely Open,Reduce Sys. Vac. - Flare Down
CV-24086	7/16/2026 1:59:18 PM	1363	34.4329045	-118.6486848	Valve Adjustment:Barely Open
CV-24087	7/2/2026 2:17:41 PM	1383	34.4329882	-118.6481410	Valve Adjustment:Decreased Flow/Vacuum
CV-24087	7/2/2026 2:19:33 PM	1393	34.4329975	-118.6481217	
CV-24087	7/13/2026 7:57:48 AM	1394	34.4330168	-118.6480972	Valve Adjustment:Decreased Flow/Vacuum;Well Comment:No pump
CV-24087	7/19/2026 1:06:40 PM	1371	34.4330035	-118.6481023	Valve Adjustment:Increased Flow/Vacuum
CV-24087	7/19/2026 1:07:48 PM	1386	34.4329877	-118.6481053	
CV-24088	7/6/2026 12:48:09 PM	1365	34.4337113	-118.6476772	,
CV-24088	7/17/2026 8:32:34 AM	1385	34.4335805	-118.6476650	Valve Adjustment:Decreased Flow/Vacuum
CV-24089	7/13/2026 11:29:35 AM	1351	34.4324502	-118.6481002	Valve Adjustment:Audible Flow,Barely Open,Surging Liquid in Header
CV-24089	7/17/2026 8:41:49 AM	1358	34.4343248	-118.6483405	Valve Adjustment:High O2,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24090	7/7/2026 12:20:30 PM	1355	34.4325860	-118.6474770	,
CV-24090	7/28/2026 8:57:02 AM	1372	34.4326700	-118.6475228	Valve Adjustment:Barely Open
CV-24091	7/2/2026 1:55:15 PM	1392	34.4329835	-118.6468947	Valve Adjustment:Increased Flow/Vacuum;Well Comment:pump not on;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24091	7/2/2026 1:58:33 PM	1408	34.4329738	-118.6468672	Well Condition:Lorentz Pump Installed
CV-24091	7/6/2026 10:46:17 AM	1427	34.4331902	-118.6468278	,
CV-24091	7/6/2026 10:48:07 AM	1430	34.4330322	-118.6468458	,
CV-24091	7/22/2026 9:43:27 AM	1403	34.4329895	-118.6469078	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24092	7/7/2026 2:35:45 PM				,
CV-24093	7/1/2026 11:46:07 AM	1394	34.4340618	-118.6463492	Valve Adjustment:Orifice Plate Changed (See OP Log);Well Condition:Lorentz Pump Installed
CV-24093	7/1/2026 11:49:48 AM	1403	34.4340520	-118.6463425	Valve Adjustment:Increased Flow/Vacuum;Well Comment:pump active;Well Condition:Lorentz Pump Installed
CV-24093	7/1/2026 11:50:23 AM	1397	34.4340568	-118.6463380	Well Condition:Lorentz Pump Installed
CV-24093	7/16/2026 2:34:31 PM	1405	34.4340300	-118.6463665	Valve Adjustment:Orifice Plate Changed (See OP Log);Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24093	7/16/2026 2:37:29 PM	1393	34.4340345	-118.6463542	Valve Adjustment:Increased Flow/Vacuum
CV-24093	7/16/2026 2:39:05 PM	1403	34.4340323	-118.6463582	Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24094	7/2/2026 1:06:27 PM	1444	34.4346487	-118.6460305	,
CV-24094	7/2/2026 1:07:29 PM	1437	34.4346962	-118.6460513	,
CV-24094	7/24/2026 10:59:08 AM	1374	34.4345825	-118.6460723	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-24094	7/24/2026 11:02:10 AM	1381	34.4345945	-118.6460547	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-24095	7/1/2026 1:48:38 PM	1251	34.4333998	-118.6513031	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-24095	7/1/2026 1:56:00 PM				AtmAA
CV-24095	7/2/2026 8:25:00 AM				AirTech Lab
CV-24095	7/2/2026 8:25:00 AM				AirTech Lab; [User entered 12%]
CV-24095	7/8/2026 10:05:22 AM	1257	34.4334018	-118.6513154	Valve Adjustment:No Flow Measurement,High Temp
CV-24095	7/8/2026 10:25:00 AM				AtmAA
CV-24095	7/8/2026 10:25:00 AM				AtmAA
CV-24095	7/15/2026 10:11:43 AM	1262	34.4334030	-118.6512970	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24095	7/15/2026 10:16:56 AM	1263	34.4334087	-118.6512990	Valve Adjustment:No Flow Measurement,High Temp
CV-24095	7/15/2026 10:20:00 AM				AtmAA
CV-24095	7/22/2026 2:01:45 PM	1256	34.4334033	-118.6512801	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24095	7/22/2026 2:02:24 PM	1257	34.4333993	-118.6512912	Valve Adjustment:No Flow Measurement,High Temp
CV-24095	7/29/2026 9:17:33 AM	1268	34.4334062	-118.6513071	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24096	7/9/2026 8:45:58 AM	1249	34.4332247	-118.6515850	Valve Adjustment:NSPS/EG CAI,High O2,Positive Static Press.;Well Comment:No system vacuum
CV-24096	7/9/2026 8:47:11 AM	1253	34.4332217	-118.6515940	
CV-24096	7/20/2026 1:13:02 PM	1236	34.4332313	-118.6515612	Valve Adjustment:Barely Open
CV-24097	7/8/2026 10:34:37 AM	1253	34.4327934	-118.6515527	Valve Adjustment:No Flow Measurement,Decreased Flow/Vacuum
CV-24097	7/8/2026 10:35:24 AM	1253	34.4327936	-118.6515486	Valve Adjustment:No Flow Measurement
CV-24097	7/20/2026 1:16:13 PM	1255	34.4327985	-118.6515693	Valve Adjustment:Barely Open
CV-24098	7/3/2026 7:42:01 AM	1249	34.4324997	-118.6513122	Valve Adjustment:Decreased Flow/Vacuum
CV-24098	7/30/2026 10:47:53 AM	1257	34.4325043	-118.6513205	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open
CV-24098	7/30/2026 10:48:29 AM	1256	34.4324972	-118.6513308	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open
CV-24099	7/3/2026 7:45:50 AM	1253	34.4323365	-118.6509312	Valve Adjustment:Decreased Flow/Vacuum
CV-24099	7/20/2026 12:59:25 PM	1242	34.4323813	-118.6509158	Valve Adjustment:Barely Open
CV-24100	7/1/2026 1:28:47 PM	1271	34.4320569	-118.6504875	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24100	7/1/2026 1:30:00 PM				AtmAA
CV-24100	7/2/2026 8:05:00 AM				AirTech Lab
CV-24100	7/2/2026 8:05:00 AM				AirTech Lab; [User entered 0.33%]
CV-24100	7/3/2026 8:08:58 AM	1264	34.4320408	-118.6504915	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24100	7/3/2026 8:10:35 AM	1267	34.4320322	-118.6505058	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header
CV-24100	7/20/2026 12:53:13 PM	1240	34.4320587	-118.6504735	Valve Adjustment:High Temp,Barely Open
CV-24100	7/29/2026 9:35:55 AM	1261	34.4320477	-118.6504844	Valve Adjustment:No Flow Measurement,High Temp
CV-24101	7/2/2026 8:00:00 AM				AirTech Lab
CV-24101	7/2/2026 8:00:00 AM				AirTech Lab; [User entered 0%]
CV-24101	7/3/2026 8:15:20 AM	1264	34.4318247	-118.6502947	Valve Adjustment:Decreased Flow/Vacuum
CV-24101	7/20/2026 10:36:02 AM	1234	34.4318762	-118.6503052	,
CV-24102	7/3/2026 8:37:34 AM	1279	34.4316252	-118.6497983	
CV-24102	7/28/2026 10:17:39 AM	1283	34.4316390	-118.6497697	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24103	7/1/2026 3:29:48 PM	1293	34.4315652	-118.6488655	,
CV-24103	7/16/2026 9:38:27 AM	1302	34.4315838	-118.6488007	,
CV-24104	7/1/2026 10:59:23 AM	1358	34.4318652	-118.6480703	,
CV-24104	7/16/2026 2:10:22 PM				,
CV-24105	7/1/2026 11:06:55 AM	1365	34.4319457	-118.6476252	,
CV-24105	7/16/2026 2:27:11 PM	1385	34.4319107	-118.6476362	,
CV-24106	7/7/2026 3:07:31 PM	1388	34.4320820	-118.6468097	,
CV-24106	7/16/2026 3:02:43 PM	1378	34.4321145	-118.6466663	,
CV-24107	7/6/2026 12:36:03 PM	1315	34.4325407	-118.6461695	Valve Adjustment:Decreased Flow/Vacuum

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24108	7/6/2026 12:25:36 PM	1355	34.4331565	-118.6454383	Valve Adjustment:Audible Flow
CV-24109	7/6/2026 12:00:44 PM	1383	34.4339828	-118.6448823	
CV-24110	7/7/2026 1:04:20 PM	1401	34.4346113	-118.6446693	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Barely Open
CV-24110	7/7/2026 1:05:17 PM	1391	34.4346142	-118.6446740	Valve Adjustment:NSPS/EG CAC,High Temp,Barely Open;Well Condition:Lorentz Pump Installed
CV-24111	7/2/2026 11:09:11 AM	1483	34.4353100	-118.6450167	,
CV-24112	7/2/2026 11:13:05 AM	1407	34.4352917	-118.6442353	,
CV-24114	7/8/2026 10:21:07 AM	1285	34.4308130	-118.6485397	Valve Adjustment:Valve 100% Open
CV-24116	7/1/2026 7:41:28 AM	1230	34.4316668	-118.6456853	Audible Flow,No Flow Measurement,No Adjustment Made
CV-24117	7/8/2026 10:03:59 AM	1300	34.4323463	-118.6449605	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24118	7/7/2026 1:25:13 PM	1305	34.4333025	-118.6438168	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-24118	7/7/2026 1:25:56 PM	1308	34.4332957	-118.6438150	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24118	7/29/2026 9:13:45 AM				[User entered 14.8%]
CV-24118	7/29/2026 9:19:19 AM	1300	34.4332957	-118.6438402	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp,Positive Static Press.,Increased Flow/Vacuum;Well Comment:Pump is active;Well Condition:Lorentz Pump Installed
CV-24118	7/29/2026 9:21:46 AM	1304	34.4333323	-118.6438628	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24118	7/29/2026 9:25:00 AM				AtmAA
CV-24118	7/29/2026 9:25:00 AM				AtmAA; [User entered 12.78%]
CV-24119	7/15/2026 10:31:25 AM	1274	34.4337223	-118.6423143	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24119	7/15/2026 10:32:21 AM	1276	34.4337160	-118.6423118	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24120	7/8/2026 1:58:27 PM	1330	34.4368615	-118.6472818	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24120	7/13/2026 10:05:00 AM				AirTech Lab
CV-24120	7/13/2026 10:05:00 AM				AirTech Lab; [User entered 1.1%]
CV-24120	7/31/2026 9:43:24 AM	1340	34.4368469	-118.6472991	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-24120	7/31/2026 10:24:29 AM	1348	34.4368570	-118.6472941	Valve Adjustment:No Flow Measurement,Surging Liquid in Header

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24121	7/8/2026 1:56:01 PM	1333	34.4369637	-118.6470187	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24121	7/9/2026 7:50:00 AM				AirTech Lab
CV-24121	7/9/2026 7:50:00 AM				AirTech Lab; [User entered 16%]
CV-24121	7/27/2026 1:27:57 PM	1329	34.4369555	-118.6470020	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-24122	7/6/2026 9:28:47 AM	1311	34.4371790	-118.6466185	
CV-24122	7/6/2026 9:40:00 AM	1307	34.4371767	-118.6466207	Valve Adjustment:NSPS/EG CAI
CV-24122	7/9/2026 7:55:00 AM				AirTech Lab
CV-24122	7/9/2026 7:55:00 AM				AirTech Lab; [User entered 0.17%]
CV-24122	7/23/2026 2:13:49 PM	1294	34.4371975	-118.6465587	Valve Comment:line watered in;Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24122	7/23/2026 2:14:07 PM	1304	34.4372058	-118.6465912	Valve Adjustment:Positive Static Press.
CV-24122	7/24/2026 9:45:00 AM				AirTech Lab; [User entered 0%]
CV-24123	7/8/2026 3:18:05 PM	1329	34.4372298	-118.6463528	,
CV-24123	7/22/2026 10:18:09 AM	1305	34.4372998	-118.6462480	
CV-24124	7/13/2026 9:07:33 AM	1365	34.4366392	-118.6470352	Valve Adjustment:NSPS/EG CAI,High Temp,Reduce Sys. Vac. - Flare Down
CV-24124	7/13/2026 9:07:55 AM	1380	34.4366428	-118.6470387	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24124	7/31/2026 9:35:59 AM	1357	34.4366362	-118.6470272	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
V-24125-TP2	7/13/2026 10:25:00 AM				AirTech Lab
V-24125-TP2	7/13/2026 10:25:00 AM				AirTech Lab; [User entered 0.27%]
V-24125-TP2	7/13/2026 12:00:38 PM	1331	34.4369712	-118.6463468	Valve Adjustment:Audible Flow,Valve 100% Open,Decreased Flow/Vacuum
V-24125-TP2	7/23/2026 2:22:19 PM	1323	34.4369807	-118.6463183	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24126	7/2/2026 10:44:12 AM	1375	34.4363968	-118.6471793	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24126	7/6/2026 1:33:35 PM	1376	34.4363812	-118.6471215	Valve Adjustment:High Temp
CV-24126	7/6/2026 1:40:00 PM				AtmAA
CV-24126	7/6/2026 1:40:00 PM				AtmAA; [User entered 16.52%]
CV-24126	7/13/2026 1:44:32 PM	1380	34.4363716	-118.6471498	Valve Adjustment:No Flow Measurement,High Temp
CV-24126	7/13/2026 1:45:00 PM				AtmAA
CV-24126	7/13/2026 1:45:04 PM	1380	34.4363715	-118.6471501	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24126	7/20/2026 10:21:14 AM	1384	34.4363851	-118.6471276	Valve Adjustment:High Temp
CV-24126	7/20/2026 10:40:00 AM				AtmAA
CV-24126	7/27/2026 1:12:06 PM	1371	34.4363951	-118.6471527	Valve Adjustment:High Temp
CV-24127	7/6/2026 1:30:07 PM	1379	34.4364479	-118.6468452	Valve Adjustment:No Flow Measurement,High Temp
CV-24127	7/6/2026 1:35:00 PM				AtmAA
CV-24127	7/6/2026 1:35:00 PM				AtmAA; [User entered 15.43%]
CV-24127	7/13/2026 1:04:22 PM	1388	34.4364479	-118.6468104	Valve Adjustment:No Flow Measurement,High Temp
CV-24127	7/13/2026 1:10:00 PM				AtmAA
CV-24127	7/20/2026 10:25:41 AM	1384	34.4364612	-118.6468159	Valve Adjustment:No Flow Measurement,High Temp
CV-24127	7/20/2026 10:45:00 AM				AtmAA
CV-24127	7/27/2026 1:06:12 PM	1373	34.4364631	-118.6468279	Valve Adjustment:No Flow Measurement,High Temp
CV-24128	7/9/2026 7:35:00 AM				AirTech Lab
CV-24128	7/9/2026 7:35:00 AM				AirTech Lab; [User entered 7.2%]
CV-24128	7/9/2026 8:21:11 AM	1357	34.4366958	-118.6464383	Valve Adjustment:Barely Open
CV-24128	7/9/2026 3:03:21 PM	1352	34.4365702	-118.6464338	,
CV-24128	7/23/2026 1:56:14 PM	1348	34.4367295	-118.6464133	Valve Adjustment:Barely Open
CV-24129	7/9/2026 8:18:18 AM	1357	34.4366973	-118.6461467	Valve Adjustment:Decreased Flow/Vacuum
CV-24129	7/23/2026 2:00:53 PM	1331	34.4367400	-118.6461598	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24130	7/9/2026 8:15:12 AM	1337	34.4368095	-118.6457255	Valve Adjustment:Decreased Flow/Vacuum
CV-24130	7/23/2026 2:05:27 PM	1315	34.4368152	-118.6456975	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24131	7/8/2026 3:31:54 PM	1296	34.4366400	-118.6451223	,
CV-24132	7/8/2026 3:36:10 PM	1247	34.4372307	-118.6440178	,
CV-24133	7/22/2026 10:30:37 AM	1269	34.4374338	-118.6427213	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
V-24134-TP1	7/6/2026 1:27:42 PM	1370	34.4363674	-118.6464978	Valve Adjustment:No Flow Measurement,High Temp
V-24134-TP1	7/6/2026 1:30:00 PM				AtmAA
V-24134-TP1	7/6/2026 1:30:00 PM				AtmAA; [User entered 10.8%]
V-24134-TP1	7/13/2026 1:01:45 PM	1381	34.4363493	-118.6465096	Valve Adjustment:No Flow Measurement,High Temp
V-24134-TP1	7/13/2026 1:05:00 PM				AtmAA
V-24134-TP1	7/20/2026 10:29:58 AM	1380	34.4363652	-118.6464863	Valve Adjustment:No Flow Measurement,High Temp
V-24134-TP1	7/20/2026 10:50:00 AM				AtmAA
V-24134-TP1	7/27/2026 1:04:09 PM	1363	34.4363834	-118.6465161	Valve Adjustment:No Flow Measurement,High Temp
CV-24135	7/6/2026 2:20:09 PM	1361	34.4363830	-118.6459463	Valve Adjustment:High Temp,Valve 100% Closed,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-24135	7/27/2026 1:02:21 PM	1353	34.4363942	-118.6459530	Valve Adjustment:Barely Open;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24135	7/27/2026 1:23:42 PM	1331	34.4368903	-118.6472607	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24136	7/7/2026 9:55:59 AM	1321	34.4366157	-118.6442708	Valve Adjustment:Decreased Flow/Vacuum
CV-24137	7/6/2026 11:54:10 AM	1363	34.4361332	-118.6434592	Valve Adjustment:Decreased Flow/Vacuum
CV-24138	7/2/2026 8:35:00 AM				AirTech Lab
CV-24138	7/2/2026 8:35:00 AM				AirTech Lab; [User entered 0.24%]
CV-24138	7/9/2026 9:09:04 AM	1270	34.4342427	-118.6512253	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed
CV-24138	7/9/2026 9:10:39 AM	1264	34.4342587	-118.6512517	
CV-24138	7/30/2026 10:59:43 AM	1277	34.4342512	-118.6512368	
CV-24138	7/30/2026 11:01:03 AM	1276	34.4342588	-118.6512358	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-24139	7/1/2026 1:59:05 PM	1255	34.4344980	-118.6511258	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24139	7/1/2026 2:10:00 PM				AtmAA
CV-24139	7/8/2026 9:55:00 AM				AtmAA
CV-24139	7/8/2026 9:55:00 AM				AtmAA; [User entered 18.16%]
CV-24139	7/8/2026 9:55:13 AM	1281	34.4344908	-118.6511461	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24139	7/8/2026 9:56:32 AM	1280	34.4344974	-118.6511398	Valve Adjustment:No Flow Measurement,High Temp
CV-24139	7/14/2026 7:15:00 AM				AirTech Lab
CV-24139	7/14/2026 7:15:00 AM				AirTech Lab; [User entered 9.4%]
CV-24139	7/15/2026 9:45:13 AM	1273	34.4344957	-118.6511289	Valve Comment:Pump not working;Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum,Barely Open
CV-24139	7/15/2026 9:46:47 AM	1273	34.4344997	-118.6511296	Valve Adjustment:No Flow Measurement,High Temp
CV-24139	7/30/2026 11:03:32 AM	1275	34.4344923	-118.6511390	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24139	7/30/2026 11:04:14 AM	1275	34.4344923	-118.6511390	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24140	7/1/2026 8:50:00 AM				AirTech Lab
CV-24140	7/1/2026 8:50:00 AM				AirTech Lab; [User entered 0%]
CV-24140	7/1/2026 2:08:43 PM	1266	34.4346731	-118.6511100	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24140	7/1/2026 2:17:00 PM				AtmAA
CV-24140	7/8/2026 9:45:00 AM				AtmAA
CV-24140	7/8/2026 9:45:00 AM				AtmAA; [User entered 11.98%]
CV-24140	7/8/2026 9:47:46 AM	1283	34.4346638	-118.6511151	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24140	7/8/2026 9:49:23 AM	1284	34.4346657	-118.6511161	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24140	7/15/2026 9:39:54 AM	1272	34.4346841	-118.6511058	Valve Adjustment:No Flow Measurement,High Temp
CV-24140	7/15/2026 9:40:00 AM				AtmAA
CV-24140	7/22/2026 11:04:15 AM	1292	34.4346565	-118.6511413	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24140	7/22/2026 11:04:39 AM	1292	34.4346565	-118.6511409	Valve Adjustment:No Flow Measurement,High Temp
CV-24141	7/2/2026 7:55:00 AM				AirTech Lab
CV-24141	7/2/2026 7:55:00 AM				AirTech Lab; [User entered 0.082%]
CV-24141	7/2/2026 12:59:12 PM	1300	34.4355108	-118.6513107	Valve Adjustment:Increased Flow/Vacuum,Valve 100% Open
CV-24141	7/14/2026 8:50:53 AM	1308	34.4355052	-118.6513052	Valve Adjustment:NSPS/EG CAI,High O2,Surging Liquid in Well (Watered In)
CV-24141	7/14/2026 8:51:58 AM	1311	34.4354920	-118.6512988	Valve Adjustment:NSPS/EG CAI,High O2,Valve 100% Closed,Surging Liquid in Well (Watered In)
CV-24141	7/28/2026 2:19:35 PM	1302	34.4355158	-118.6513105	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24142	7/2/2026 8:30:00 AM				AirTech Lab
CV-24142	7/2/2026 8:30:00 AM				AirTech Lab; [User entered 8.8%]
CV-24142	7/9/2026 8:59:51 AM	1272	34.4339785	-118.6513507	Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Decreased Flow/Vacuum,Surging Liquid in Well (Watered In)
CV-24142	7/9/2026 9:01:16 AM	1265	34.4339813	-118.6513477	
CV-24142	7/30/2026 10:56:47 AM	1271	34.4339858	-118.6513472	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24142	7/30/2026 10:57:39 AM	1274	34.4339852	-118.6513472	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24143	7/1/2026 8:35:00 AM				AirTech Lab
CV-24143	7/1/2026 8:35:00 AM				AirTech Lab; [User entered 3.3%]
CV-24143	7/1/2026 10:34:22 AM	1286	34.4349970	-118.6511821	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High O2,Decreased Flow/Vacuum,Barely Open;Well Condition:Pnumatic Pump Installed
CV-24143	7/1/2026 10:37:17 AM	1289	34.4350008	-118.6511880	Valve Adjustment:No Flow Measurement,High O2
CV-24144	7/8/2026 10:38:46 AM	1251	34.4325683	-118.6515978	Valve Adjustment:No Flow Measurement
CV-24144	7/20/2026 1:19:01 PM	1254	34.4325663	-118.6515793	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24145	7/7/2026 9:15:00 AM				AtmAA
CV-24145	7/7/2026 9:15:00 AM				AtmAA; [User entered 6.86%]
CV-24145	7/7/2026 9:15:42 AM	1369	34.4362020	-118.6496358	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-24145	7/7/2026 9:16:13 AM	1369	34.4362009	-118.6496343	Valve Adjustment:High Temp

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24145	7/14/2026 9:05:26 AM	1373	34.4362212	-118.6496205	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24145	7/14/2026 9:05:51 AM	1373	34.4362209	-118.6496228	Valve Adjustment:No Flow Measurement,High Temp
CV-24145	7/14/2026 9:20:00 AM				AtmAA
CV-24145	7/21/2026 8:36:45 AM	1368	34.4362195	-118.6496232	Valve Adjustment:High Temp
CV-24145	7/28/2026 8:11:20 AM	1360	34.4362091	-118.6496379	Valve Adjustment:High Temp
CV-24146	7/1/2026 9:26:27 AM	1254	34.4373662	-118.6464357	Valve Adjustment:NSPS/EG CAC,Orifice Plate Changed (See OP Log)
CV-24146	7/1/2026 9:28:20 AM	1262	34.4373907	-118.6464038	
CV-24146	7/22/2026 10:17:09 AM	1282	34.4374207	-118.6464175	Valve Adjustment:Valve 100% Open
CV-24146	7/27/2026 2:11:52 PM	1320	34.4374123	-118.6463415	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24147	7/1/2026 9:36:36 AM	1277	34.4375200	-118.6459613	Valve Adjustment:Decreased Flow/Vacuum;Well Comment:Wellhead has air leak;Well Condition:Fair
CV-24147	7/1/2026 9:46:01 AM	1247	34.4375070	-118.6459283	Well Comment:temporary fix applied
CV-24147	7/22/2026 10:21:45 AM	1286	34.4375252	-118.6459410	
CV-24148	7/6/2026 2:26:20 PM	1372	34.4350624	-118.6466529	Valve Comment:Pump on;Valve Adjustment:No Flow Measurement,High Temp
CV-24148	7/6/2026 2:45:00 PM				AtmAA
CV-24148	7/6/2026 2:45:00 PM				AtmAA; [User entered 6.67%]
CV-24148	7/15/2026 1:20:00 PM				AtmAA
CV-24148	7/15/2026 1:21:10 PM	1387	34.4350697	-118.6466623	Valve Adjustment:No Flow Measurement,High Temp
CV-24148	7/28/2026 1:21:09 PM	1375	34.4350600	-118.6466536	Valve Adjustment:No Flow Measurement,High Temp
CV-24149	7/2/2026 3:03:27 PM	1371	34.4348205	-118.6470928	,
CV-24149	7/29/2026 10:38:37 AM	1376	34.4348148	-118.6469752	Valve Adjustment:Barely Open
CV-24150	7/2/2026 1:19:01 PM	1440	34.4346217	-118.6457927	,
CV-24150	7/24/2026 10:54:45 AM	1394	34.4346072	-118.6457193	Valve Adjustment:Audible Flow;Well Condition:Good
CV-24151	7/2/2026 4:27:58 PM	1394	34.4344047	-118.6476500	,
CV-24151	7/29/2026 10:06:40 AM	1365	34.4344480	-118.6476135	Valve Adjustment:Barely Open
CV-24152	7/2/2026 3:30:10 PM	1430	34.4345197	-118.6471548	,
CV-24152	7/2/2026 3:31:51 PM	1385	34.4345188	-118.6470357	,
CV-24152	7/22/2026 2:16:41 PM	1378	34.4344460	-118.6471583	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24153	7/2/2026 1:30:09 PM	1391	34.4343562	-118.6464038	,
CV-24153	7/29/2026 10:41:39 AM	1383	34.4343988	-118.6463903	Valve Adjustment:Barely Open
CV-24154	7/2/2026 12:04:43 PM	1392	34.4342558	-118.6460755	Valve Adjustment:Increased Flow/Vacuum
CV-24154	7/2/2026 1:26:44 PM	1385	34.4343327	-118.6461577	,
CV-24154	7/16/2026 2:44:12 PM	1385	34.4342530	-118.6461038	Valve Adjustment:Barely Open;Well Comment:pump is active;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24155	7/2/2026 2:56:00 PM	1325	34.4342445	-118.6468017	,
CV-24155	7/22/2026 2:06:53 PM	1381	34.4342872	-118.6467103	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24156	7/6/2026 1:00:56 PM	1319	34.4340140	-118.6477623	High Temp,NSPS/EG CAI
CV-24156	7/6/2026 1:03:01 PM	1319	34.4340925	-118.6478032	,
CV-24156	7/17/2026 10:11:04 AM	1361	34.4340740	-118.6477108	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24157	7/2/2026 4:31:31 PM	1427	34.4338227	-118.6473393	,
CV-24157	7/17/2026 10:17:57 AM	1390	34.4338477	-118.6473387	Valve Adjustment:Barely Open
CV-24158	7/2/2026 4:18:26 PM	1381	34.4338900	-118.6471292	,
CV-24158	7/17/2026 9:52:10 AM	1393	34.4338963	-118.6470693	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24159	7/1/2026 11:34:49 AM	1389	34.4337967	-118.6466300	
CV-24159	7/1/2026 11:38:58 AM	1402	34.4337870	-118.6466145	Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24159	7/1/2026 11:39:41 AM	1405	34.4337818	-118.6466140	Well Condition:Lorentz Pump Installed
CV-24159	7/16/2026 2:28:59 PM	1425	34.4337477	-118.6466318	Valve Adjustment:Increased Flow/Vacuum;Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24159	7/16/2026 2:29:46 PM	1423	34.4337698	-118.6466413	
CV-24160	7/1/2026 1:08:53 PM	1384	34.4338200	-118.6462710	Well Comment:pump active;Well Condition:Lorentz Pump Installed
CV-24160	7/16/2026 2:50:10 PM	1411	34.4337973	-118.6462928	Valve Adjustment:Decreased Flow/Vacuum;Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24160	7/16/2026 2:51:27 PM	1383	34.4337785	-118.6462767	Well Comment:Pump is active;Well Condition:Lorentz Pump Installed
CV-24161	7/7/2026 2:17:35 PM				Positive Static Press.,NSPS/EG CAI,NSPS/EG CAC,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24161	7/7/2026 2:18:47 PM				,
CV-24161	7/8/2026 2:54:28 PM	1380	34.4338674	-118.6456097	Valve Adjustment:No Flow Measurement,Increased Flow/Vacuum
CV-24161	7/8/2026 2:55:35 PM	1380	34.4338671	-118.6456096	Valve Adjustment:No Flow Measurement,High Temp
CV-24162	7/6/2026 12:09:43 PM	1374	34.4335620	-118.6451170	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Pnumatic Pump Installed
CV-24163	7/6/2026 10:51:03 AM	1341	34.4334722	-118.6444950	Valve Adjustment:Barely Open;Well Condition:Lorentz Pump Installed
CV-24164	7/6/2026 2:59:38 PM	1427	34.4333640	-118.6478617	,
CV-24164	7/17/2026 8:21:20 AM	1365	34.4334825	-118.6479818	Valve Adjustment:Barely Open

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24165	7/2/2026 10:25:28 AM	1382	34.4335413	-118.6472735	Well Comment:pump active;Well Condition:Lorentz Pump Installed
CV-24165	7/22/2026 8:18:17 AM	1386	34.4335218	-118.6472670	
CV-24166	7/1/2026 1:16:33 PM	1392	34.4336180	-118.6468742	Valve Adjustment:Increased Flow/Vacuum;Well Comment:pump active;Well Condition:Lorentz Pump Installed
CV-24166	7/16/2026 2:23:51 PM	1419	34.4335867	-118.6468905	Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24167	7/1/2026 1:36:53 PM	1402	34.4334738	-118.6464488	Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24167	7/28/2026 8:36:37 AM	1397	34.4334558	-118.6464908	Valve Adjustment:Barely Open
CV-24168	7/2/2026 12:22:20 PM	1390	34.4332737	-118.6473333	Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24168	7/22/2026 8:22:36 AM	1376	34.4333178	-118.6473497	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24169	7/6/2026 2:56:17 PM	1407	34.4332625	-118.6477255	,
CV-24169	7/17/2026 8:24:21 AM	1392	34.4332093	-118.6477078	Valve Adjustment:Barely Open
CV-24170	7/6/2026 3:57:46 PM	1332	34.4333135	-118.6486027	High Temp,NSPS/EG CAI
CV-24170	7/6/2026 3:59:49 PM	1316	34.4331438	-118.6485195	,
CV-24170	7/13/2026 10:36:08 AM	1353	34.4331292	-118.6485273	Valve Adjustment:Decreased Flow/Vacuum;Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24170	7/13/2026 10:37:39 AM	1349	34.4331302	-118.6485175	Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24170	7/29/2026 8:57:26 AM	1363	34.4331380	-118.6484922	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24171	7/7/2026 2:44:27 PM				,
CV-24171	7/28/2026 8:48:55 AM	1396	34.4331727	-118.6466432	Valve Comment:Well too tall for system read
CV-24172	7/7/2026 12:29:38 PM	1348	34.4330108	-118.6472335	,
CV-24172	7/22/2026 9:55:02 AM	1384	34.4329592	-118.6473208	Valve Adjustment:Barely Open
CV-24173	7/13/2026 11:49:25 AM	1391	34.4329055	-118.6476862	Valve Adjustment:Decreased Flow/Vacuum
CV-24173	7/19/2026 1:43:48 PM	1382	34.4328995	-118.6476088	Valve Adjustment:Decreased Flow/Vacuum;Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24173	7/19/2026 1:45:39 PM	1375	34.4329048	-118.6476163	Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24174	7/13/2026 9:26:49 AM	1386	34.4327050	-118.6480113	Valve Adjustment:Decreased Flow/Vacuum;Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24174	7/13/2026 9:29:10 AM	1422	34.4327270	-118.6479697	Well Condition:Lorentz Pump Installed
CV-24174	7/19/2026 1:34:46 PM	1382	34.4327120	-118.6480115	Valve Adjustment:Barely Open;Well Condition:Lorentz Pump Installed
CV-24175	7/7/2026 11:47:48 AM	1434	34.4326872	-118.6484648	,

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24175	7/13/2026 7:13:50 AM	1383	34.4326632	-118.6484857	Valve Adjustment:Decreased Flow/Vacuum;Well Comment:Lorentz pump flange not sealed correctly. Pump is active.;Well Condition:Lorentz Pump Installed;Well Repairs:Sample Port
CV-24175	7/13/2026 7:16:51 AM	1384	34.4326540	-118.6484725	Well Condition:Lorentz Pump Installed
CV-24175	7/19/2026 1:25:17 PM	1361	34.4326553	-118.6484490	Valve Adjustment:Barely Open;Well Condition:Lorentz Pump Installed
CV-24176	7/7/2026 11:57:12 AM	1312	34.4326468	-118.6490007	,
CV-24176	7/16/2026 9:57:20 AM	1332	34.4326058	-118.6488667	,
CV-24177	7/3/2026 8:50:27 AM	1316	34.4322602	-118.6494425	Valve Adjustment:NSPS/EG CAC;Well Condition:Lorentz Pump Installed
CV-24177	7/20/2026 1:38:05 PM	1336	34.4322312	-118.6494338	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24178	7/7/2026 11:52:46 AM	1355	34.4323232	-118.6485155	High Temp,NSPS/EG CAI
CV-24178	7/7/2026 11:54:03 AM	1371	34.4323855	-118.6485975	,
CV-24178	7/16/2026 10:01:44 AM	1319	34.4323945	-118.6486323	High Temp,
CV-24178	7/16/2026 10:02:55 AM	1332	34.4323743	-118.6485255	,
CV-24179	7/7/2026 12:05:35 PM				High Temp,NSPS/EG CAI
CV-24179	7/7/2026 12:07:10 PM	1358	34.4319392	-118.6491422	,
CV-24179	7/16/2026 9:47:20 AM	1404	34.4321910	-118.6492610	High Temp,
CV-24179	7/16/2026 9:48:41 AM	1394	34.4321682	-118.6493210	,
CV-24180	7/1/2026 3:43:22 PM	1339	34.4321497	-118.6484020	,
CV-24180	7/16/2026 10:10:17 AM	1411	34.4322288	-118.6487628	,
CV-24181	7/1/2026 3:45:28 PM	1339	34.4321725	-118.6484523	,
CV-24181	7/16/2026 10:05:46 AM	1381	34.4323885	-118.6485205	,
CV-24182	7/1/2026 3:56:52 PM	1378	34.4322983	-118.6480988	,
CV-24182	7/28/2026 9:23:56 AM	1367	34.4322388	-118.6480605	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24183	7/1/2026 4:06:34 PM	1335	34.4323147	-118.6476795	,
CV-24183	7/16/2026 2:54:48 PM	1348	34.4322843	-118.6477358	,
CV-24184	7/6/2026 10:20:25 AM	1362	34.4325900	-118.6472820	High O2,
CV-24184	7/6/2026 10:21:53 AM	1401	34.4325982	-118.6472687	,
CV-24184	7/16/2026 3:19:56 PM	1371	34.4324563	-118.6474037	High Temp,
CV-24184	7/16/2026 3:20:01 PM	1378	34.4324443	-118.6473498	,
CV-24184	7/16/2026 3:21:33 PM	1322	34.4325878	-118.6471233	,
CV-24185	7/6/2026 10:33:38 AM	1411	34.4327278	-118.6470045	,
CV-24185	7/16/2026 3:10:44 PM	1391	34.4326503	-118.6469152	,
CV-24186	7/6/2026 10:53:50 AM	1352	34.4328685	-118.6465668	,
CV-24186	7/31/2026 9:06:58 AM	1358	34.4328050	-118.6465602	Valve Adjustment:Barely Open
CV-24187	7/3/2026 8:45:32 AM	1301	34.4318742	-118.6495750	Valve Adjustment:Barely Open
CV-24187	7/28/2026 10:01:22 AM	1326	34.4318662	-118.6495952	Valve Adjustment:No Flow Measurement,Other - See Daily Log,Barely Open

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24188	7/3/2026 8:18:13 AM	1256	34.4315335	-118.6501237	Valve Adjustment:Audible Flow;Well Condition:Good
CV-24188	7/20/2026 10:23:42 AM	1250	34.4316198	-118.6500603	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24189	7/3/2026 8:22:16 AM	1261	34.4313085	-118.6499942	Valve Adjustment:Decreased Flow/Vacuum
CV-24189	7/20/2026 10:19:56 AM	1234	34.4313870	-118.6500478	,
CV-24190	7/3/2026 9:31:48 AM	1306	34.4315963	-118.6494665	
CV-24190	7/28/2026 10:06:36 AM	1313	34.4315890	-118.6494827	Valve Adjustment:Decreased Flow/Vacuum
CV-24192	7/3/2026 9:29:59 AM	1300	34.4313485	-118.6495147	
CV-24192	7/28/2026 10:10:00 AM	1303	34.4313282	-118.6494985	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24193	7/1/2026 3:06:38 PM	1342	34.4314883	-118.6490825	,
CV-24193	7/16/2026 10:16:18 AM	1306	34.4316418	-118.6490603	,
CV-24194	7/1/2026 3:49:34 PM	1345	34.4318452	-118.6484877	,
CV-24194	7/16/2026 2:16:21 PM				,
CV-24195	7/1/2026 10:55:30 AM	1368	34.4318750	-118.6479020	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24195	7/16/2026 2:22:23 PM	1362	34.4317347	-118.6478392	,
CV-24196	7/1/2026 10:39:45 AM	1332	34.4320618	-118.6472113	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24196	7/16/2026 2:59:29 PM	1243	34.4321997	-118.6472290	,
CV-24197	7/7/2026 3:12:35 PM	1355	34.4323712	-118.6465828	,
CV-24197	7/31/2026 9:01:20 AM	1346	34.4323733	-118.6465920	Valve Adjustment:Barely Open
CV-24198	7/1/2026 10:51:11 AM	1335	34.4316007	-118.6476128	No Adjustment Made,
CV-24198	7/31/2026 10:02:49 AM	1336	34.4315790	-118.6476033	Valve Adjustment:Increased Flow/Vacuum,Barely Open
CV-24199	7/1/2026 10:46:03 AM	1316	34.4317680	-118.6473202	No Adjustment Made,
CV-24199	7/31/2026 9:58:44 AM	1340	34.4317715	-118.6473058	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Comment:unable to reach system safely
CV-24200	7/1/2026 8:49:29 AM	1302	34.4314357	-118.6471958	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24200	7/31/2026 9:37:53 AM	1284	34.4314428	-118.6472248	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-24201	7/1/2026 9:13:06 AM	1306	34.4317537	-118.6466138	No Adjustment Made,
CV-24201	7/31/2026 8:51:59 AM	1284	34.4317473	-118.6466265	Valve Adjustment:Decreased Flow/Vacuum
CV-24202	7/1/2026 9:25:34 AM	1289	34.4319363	-118.6462450	No Flow Measurement,
CV-24202	7/31/2026 8:34:50 AM	1281	34.4319287	-118.6462825	Valve Adjustment:Audible Flow,Valve 100% Open,Decreased Flow/Vacuum
CV-24203	7/1/2026 7:48:19 AM	1260	34.4315915	-118.6460533	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24203	7/28/2026 1:14:17 PM	1223	34.4315502	-118.6459800	Valve Adjustment:Decreased Flow/Vacuum;Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24203	7/28/2026 1:19:47 PM	1222	34.4315497	-118.6459855	
CV-24204	7/1/2026 7:53:18 AM	1234	34.4313827	-118.6462373	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24204	7/28/2026 1:25:26 PM	1230	34.4314318	-118.6462438	Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24205	7/1/2026 8:20:01 AM	1237	34.4312095	-118.6464842	No Adjustment Made,Audible Flow
CV-24205	7/28/2026 1:31:58 PM	1237	34.4312290	-118.6464637	Valve Adjustment:Decreased Flow/Vacuum;Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24205	7/28/2026 1:33:51 PM	1223	34.4312298	-118.6464583	
CV-24206	7/1/2026 8:55:19 AM	1276	34.4315752	-118.6468373	No Flow Measurement,
CV-24206	7/31/2026 8:54:17 AM	1278	34.4315180	-118.6467678	Valve Adjustment:Decreased Flow/Vacuum
CV-24207	7/1/2026 1:28:15 PM	1397	34.4332873	-118.6469342	Valve Adjustment:NSPS/EG CAI,High Temp;Well Comment:Pump is active.;Well Condition:Lorentz Pump Installed
CV-24207	7/1/2026 1:31:42 PM	1392	34.4332835	-118.6469392	Valve Adjustment:Orifice Plate Changed (See OP Log),High Temp;Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24207	7/16/2026 2:04:54 PM	1402	34.4333023	-118.6469293	Valve Adjustment:NSPS/EG CAI,Orifice Plate Changed (See OP Log),High Temp,Positive Static Press.,Increased Flow/Vacuum;Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24207	7/16/2026 2:08:41 PM	1394	34.4332733	-118.6469205	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp,Increased Flow/Vacuum;Well Comment:Pump is active;Well Condition:Lorentz Pump Installed
CV-24207	7/16/2026 2:09:52 PM	1409	34.4332730	-118.6469230	Valve Adjustment:High Temp;Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24208	7/9/2026 1:33:32 PM	1251	34.4319025	-118.6451138	Valve Adjustment:Barely Open
CV-24209	7/1/2026 10:07:13 AM	1302	34.4322170	-118.6455907	No Flow Measurement,
CV-24210	7/6/2026 12:13:38 PM	1329	34.4326510	-118.6455970	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum,Barely Open
CV-24211	7/15/2026 10:55:22 AM	1256	34.4326872	-118.6438370	Valve Adjustment:Barely Open
CV-24212	7/15/2026 10:48:49 AM	1258	34.4331587	-118.6430852	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-24213	7/6/2026 11:00:04 AM	1313	34.4366120	-118.6429642	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24213	7/6/2026 11:01:11 AM	1325	34.4365988	-118.6429732	Valve Adjustment:NSPS/EG CAC
CV-24214	7/7/2026 9:51:22 AM	1316	34.4367503	-118.6435175	Valve Adjustment:Barely Open
CV-24215	7/8/2026 3:28:03 PM	1352	34.4369235	-118.6449418	,
CV-24216	7/6/2026 11:20:47 AM	1300	34.4368337	-118.6423315	Valve Adjustment:Decreased Flow/Vacuum
CV-24217	7/2/2026 11:20:03 AM	1440	34.4359497	-118.6443048	,
CV-24218	7/6/2026 10:27:41 AM	1379	34.4358470	-118.6458087	Valve Adjustment:Audible Flow
CV-24219	7/2/2026 9:34:00 AM				AtmAA
CV-24219	7/2/2026 9:51:06 AM	1395	34.4350905	-118.6462279	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24219	7/2/2026 9:51:58 AM	1395	34.4350742	-118.6462245	Valve Adjustment:No Flow Measurement,High Temp
CV-24219	7/9/2026 9:40:00 AM				AtmAA
CV-24219	7/9/2026 9:40:00 AM				AtmAA; [User entered 8.47%]
CV-24219	7/9/2026 9:41:25 AM	1388	34.4350742	-118.6462545	Valve Adjustment:No Flow Measurement,High Temp
CV-24219	7/16/2026 9:39:52 AM	1393	34.4350858	-118.6462272	Valve Adjustment:No Flow Measurement,High Temp
CV-24219	7/16/2026 9:45:00 AM				AtmAA
CV-24219	7/30/2026 8:40:54 AM	1384	34.4350650	-118.6462144	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24220	7/6/2026 11:00:13 AM	1350	34.4339627	-118.6439773	Valve Adjustment:Decreased Flow/Vacuum
CV-24221	7/15/2026 1:49:24 PM	1283	34.4341143	-118.6421118	Valve Adjustment:Barely Open
CV-24222	7/15/2026 10:36:12 AM	1261	34.4335948	-118.6419900	Valve Adjustment:Barely Open
CV-24223	7/30/2026 10:04:38 AM	1263	34.4334133	-118.6425488	
CV-24224	7/6/2026 10:22:07 AM	1319	34.4331560	-118.6448383	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Lorentz Pump Installed
CV-24225	7/7/2026 1:39:40 PM	1290	34.4327153	-118.6444395	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Valve 100% Open
CV-24225	7/7/2026 1:42:58 PM	1285	34.4327235	-118.6444533	Valve Adjustment:Positive Static Press.
CV-24225	7/8/2026 8:07:51 AM	1287	34.4327185	-118.6444247	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-24226	7/15/2026 10:59:16 AM	1262	34.4324882	-118.6442877	Valve Adjustment:Barely Open
CV-24227	7/3/2026 9:35:57 AM	1260	34.4309882	-118.6497818	Valve Adjustment:Decreased Flow/Vacuum
CV-24231	7/8/2026 10:36:56 AM	1277	34.4302635	-118.6496413	Valve Adjustment:Barely Open
CV-24236	7/3/2026 10:02:29 AM	1206	34.4301278	-118.6504717	Valve Adjustment:Decreased Flow/Vacuum
CV-24237	7/3/2026 10:06:25 AM	1222	34.4306317	-118.6502075	Valve Adjustment:Decreased Flow/Vacuum
CV-24243	7/7/2026 1:18:13 PM	1207	34.4287737	-118.6506243	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-24243	7/7/2026 1:22:47 PM	1207	34.4287672	-118.6506468	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open
CV-24243	7/7/2026 1:34:56 PM	1205	34.4287618	-118.6506538	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open
CV-24244	7/7/2026 1:41:19 PM	1209	34.4289828	-118.6513240	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24245	7/7/2026 12:39:44 PM	1164	34.4284712	-118.6500772	
CV-24246	7/7/2026 12:36:10 PM	1171	34.4286895	-118.6494357	Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Barely Open
CV-24253	7/7/2026 12:47:31 PM	1157	34.4284778	-118.6498172	
CV-25	7/9/2026 11:25:13 AM	1207	34.4369760	-118.6421815	High O2,
CV-25	7/9/2026 11:27:02 AM	1217	34.4369665	-118.6420382	,
CV-2501	7/1/2026 3:25:30 PM	1329	34.4314055	-118.6485067	,
CV-2502	7/1/2026 3:10:48 PM	1296	34.4309095	-118.6490837	,
CV-2503	7/1/2026 8:33:56 AM	1319	34.4312292	-118.6477382	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2504	7/8/2026 10:32:18 AM	1269	34.4303618	-118.6489203	Valve Adjustment:Decreased Flow/Vacuum
CV-2505	7/7/2026 3:22:12 PM	1250	34.4308210	-118.6471663	,
CV-2506	7/7/2026 3:27:25 PM	1227	34.4304985	-118.6475680	,
CV-2507	7/7/2026 3:30:21 PM	1211	34.4301542	-118.6481397	,
CV-2508	7/8/2026 10:25:00 AM	1200	34.4297030	-118.6487542	Valve Adjustment:Audible Flow
CV-2509	7/8/2026 10:07:20 AM	1183	34.4292437	-118.6491805	Valve Adjustment:Decreased Flow/Vacuum
CV-2510	7/8/2026 10:20:42 AM	1194	34.4290517	-118.6497817	Valve Adjustment:Audible Flow
CV-25100D	7/6/2026 1:51:46 PM	1375	34.4361592	-118.6471412	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-25100D	7/23/2026 9:38:21 AM	1359	34.4361510	-118.6471307	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed
CV-25100D	7/27/2026 1:20:17 PM	1374	34.4361718	-118.6471119	Valve Adjustment:No Flow Measurement;Well Condition:Pnumatic Pump Installed
CV-25100S	7/6/2026 1:36:14 PM	1370	34.4361578	-118.6471252	Valve Adjustment:No Flow Measurement,High Temp
CV-25100S	7/6/2026 1:50:00 PM				AtmAA
CV-25100S	7/13/2026 1:06:47 PM	1384	34.4361533	-118.6471270	Valve Adjustment:No Flow Measurement,High Temp
CV-25100S	7/13/2026 1:15:00 PM				AtmAA
CV-25100S	7/20/2026 10:16:41 AM	1379	34.4361537	-118.6471225	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-25100S	7/20/2026 10:17:24 AM	1380	34.4361568	-118.6471243	Valve Adjustment:No Flow Measurement,High Temp
CV-25100S	7/20/2026 10:35:00 AM				AtmAA
CV-25100S	7/27/2026 1:24:21 PM	1375	34.4361717	-118.6471212	Valve Adjustment:No Flow Measurement,High Temp
CV-25101D	7/6/2026 10:26:33 AM	1391	34.4359760	-118.6467920	Valve Adjustment:Barely Open
CV-25101D	7/20/2026 9:01:51 AM	1427	34.4360173	-118.6468878	,
CV-25101S	7/6/2026 10:28:38 AM	1382	34.4359767	-118.6467783	Valve Adjustment:Barely Open
CV-25101S	7/20/2026 9:03:57 AM	1411	34.4359873	-118.6468357	,
CV-25102	7/6/2026 10:37:26 AM	1407	34.4358853	-118.6472208	,
CV-25102	7/23/2026 9:32:59 AM	1375	34.4357920	-118.6471978	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-25103	7/6/2026 10:03:22 AM	1389	34.4356588	-118.6466993	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25103	7/27/2026 2:29:26 PM	1395	34.4356673	-118.6466962	Valve Adjustment:Barely Open
CV-25104D	7/8/2026 12:30:04 PM	1363	34.4353785	-118.6472320	Valve Adjustment:Barely Open,Surging Liquid in Well (Watered In)
CV-25104D	7/21/2026 1:22:18 PM	1380	34.4353458	-118.6472290	Valve Adjustment:Barely Open
CV-25104S	7/2/2026 1:43:30 PM	1389	34.4353662	-118.6472463	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-25104S	7/8/2026 12:33:30 PM	1348	34.4353707	-118.6472352	Valve Adjustment:Barely Open,Surging Liquid in Well (Watered In)
CV-25104S	7/21/2026 1:17:04 PM	1371	34.4353385	-118.6472495	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-25105D	7/6/2026 9:46:11 AM	1395	34.4353680	-118.6467107	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25105D	7/6/2026 9:47:55 AM	1392	34.4353768	-118.6467153	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25105D	7/20/2026 9:15:48 AM	1411	34.4353942	-118.6467925	,
CV-25105S	7/6/2026 9:40:39 AM	1394	34.4353738	-118.6467143	Valve Adjustment:NSPS/EG CAI,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25105S	7/6/2026 9:41:26 AM	1394	34.4353742	-118.6467212	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25105S	7/20/2026 9:18:29 AM	1430	34.4354838	-118.6467457	,
CV-25105S	7/20/2026 9:19:47 AM	1437	34.4354690	-118.6467537	,
CV-25106D	7/8/2026 12:21:49 PM	1361	34.4350520	-118.6473995	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In)
CV-25106D	7/8/2026 12:22:37 PM	1360	34.4350530	-118.6473818	
CV-25106D	7/9/2026 3:25:27 PM	1280	34.4350305	-118.6473040	,
CV-25106D	7/9/2026 3:27:08 PM	1319	34.4350133	-118.6473288	,
CV-25106D	7/21/2026 1:33:34 PM	1370	34.4350318	-118.6473988	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25106S	7/8/2026 12:25:20 PM	1372	34.4350507	-118.6473733	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In)
CV-25106S	7/8/2026 12:26:22 PM	1364	34.4350570	-118.6473792	
CV-25106S	7/21/2026 1:25:58 PM	1367	34.4350433	-118.6473917	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25107D	7/2/2026 10:50:21 AM	1440	34.4351272	-118.6459417	,
CV-25107D	7/21/2026 10:03:10 AM	1392	34.4350680	-118.6459755	Valve Adjustment:Barely Open
CV-25107S	7/2/2026 10:46:50 AM	1404	34.4350253	-118.6460213	,
CV-25107S	7/20/2026 8:38:14 AM	1417	34.4350580	-118.6459965	,
CV-25107S	7/21/2026 10:06:29 AM	1392	34.4350982	-118.6459735	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2511	7/8/2026 10:47:35 AM	1248	34.4296572	-118.6501635	Valve Adjustment:Decreased Flow/Vacuum

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2512	7/8/2026 10:52:13 AM	1249	34.4292307	-118.6506250	Valve Adjustment:Barely Open
CV-2513	7/7/2026 1:03:46 PM	1156	34.4288247	-118.6488200	Valve Adjustment:Audible Flow
CV-2514	7/7/2026 12:27:36 PM	1150	34.4296027	-118.6477925	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-2514	7/7/2026 12:28:19 PM	1155	34.4296022	-118.6477962	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2514	7/7/2026 12:28:46 PM	1159	34.4296012	-118.6477985	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2515	7/9/2026 11:04:39 AM	1234	34.4379585	-118.6431397	,
CV-2516	7/6/2026 11:26:24 AM	1300	34.4373957	-118.6431928	Valve Adjustment:Audible Flow,Surging Liquid in Header
CV-2516	7/20/2026 9:44:48 AM	1314	34.4373858	-118.6431802	
CV-2517	7/9/2026 11:37:20 AM	1250	34.4370018	-118.6420915	,
CV-2518	7/9/2026 11:46:28 AM	1296	34.4363067	-118.6413437	,
CV-2519	7/6/2026 10:07:30 AM	1339	34.4361073	-118.6420303	,
CV-2520	7/6/2026 10:18:34 AM	1299	34.4359435	-118.6427883	,
CV-2520	7/6/2026 10:21:32 AM	1312	34.4359375	-118.6428430	,
CV-2521	7/8/2026 2:50:11 PM	1329	34.4355252	-118.6430337	,
CV-2521	7/8/2026 2:51:44 PM	1355	34.4354663	-118.6429650	,
CV-2522	7/8/2026 12:50:04 PM	1280	34.4355348	-118.6423983	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open
CV-2522	7/8/2026 12:51:07 PM	1278	34.4355347	-118.6424065	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-2523	7/8/2026 12:35:59 PM	1278	34.4356740	-118.6416662	Valve Adjustment:Audible Flow;Well Condition:Good
CV-2524	7/15/2026 1:31:35 PM	1279	34.4347990	-118.6425182	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2524	7/16/2026 1:43:13 PM	1271	34.4348319	-118.6425338	Valve Adjustment:High Temp,Increased Flow/Vacuum
CV-2524	7/16/2026 1:45:00 PM				AtmAA
CV-2524	7/16/2026 1:45:33 PM	1278	34.4348140	-118.6425278	Valve Adjustment:Audible Flow,No Flow Measurement,High Temp
CV-2524	7/22/2026 3:00:48 PM	1281	34.4347897	-118.6425312	Valve Adjustment:High Temp
CV-2525	7/8/2026 12:22:47 PM	1284	34.4349958	-118.6417298	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-2526	7/8/2026 12:18:22 PM	1277	34.4345575	-118.6415883	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum,Barely Open
CV-2527	7/2/2026 11:38:52 AM	1306	34.4341003	-118.6428788	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum,Barely Open
CV-2527	7/2/2026 11:42:07 AM	1307	34.4341068	-118.6428753	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-2527	7/6/2026 9:44:55 AM	1304	34.4341112	-118.6428858	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-2527	7/6/2026 9:45:16 AM	1300	34.4341098	-118.6428925	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-2527	7/30/2026 10:09:39 AM	1303	34.4341077	-118.6428660	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2528	7/6/2026 9:46:49 AM	1227	34.4337537	-118.6412445	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-2529	7/7/2026 12:22:38 PM	1234	34.4331165	-118.6423533	Valve Adjustment:Audible Flow
CV-2529	7/16/2026 1:49:16 PM	1235	34.4331200	-118.6423355	
CV-2529	7/16/2026 1:50:34 PM	1234	34.4331253	-118.6423530	Valve Adjustment:NSPS/EG CAI,High O2
CV-2530	7/6/2026 12:09:42 PM	1217	34.4327017	-118.6429342	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-2530	7/6/2026 12:10:39 PM	1212	34.4327038	-118.6429370	
CV-2531	7/6/2026 12:01:36 PM	1222	34.4325318	-118.6433477	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-2531	7/6/2026 12:02:52 PM	1215	34.4325288	-118.6433562	
CV-2532	7/6/2026 11:55:09 AM	1220	34.4322338	-118.6437215	Valve Adjustment:Audible Flow
CV-2533	7/6/2026 11:48:36 AM	1211	34.4318975	-118.6441290	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-2534	7/6/2026 11:41:45 AM	1218	34.4316743	-118.6444818	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-2535	7/1/2026 7:30:47 AM	1214	34.4309617	-118.6468960	,
CV-2536	7/9/2026 9:16:39 AM	1180	34.4309762	-118.6458880	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2537	7/1/2026 8:11:38 AM	1191	34.4310443	-118.6467488	,
CV-2538	7/1/2026 8:03:31 AM	1198	34.4307898	-118.6466802	,
CV-2539	7/1/2026 3:03:38 PM	1306	34.4316313	-118.6491078	,
CV-2539	7/16/2026 10:13:17 AM	1335	34.4317843	-118.6492680	,
CV-2540	7/6/2026 4:05:31 PM	1352	34.4332602	-118.6482112	High Temp,NSPS/EG CAI
CV-2540	7/6/2026 4:06:42 PM	1345	34.4331957	-118.6481662	,
CV-2540	7/17/2026 8:16:47 AM	1381	34.4332593	-118.6480973	Valve Adjustment:High Temp,Barely Open
CV-2541	7/7/2026 9:23:24 AM	1348	34.4332738	-118.6490560	Valve Adjustment:NSPS/EG CAC,Reduce Sys. Vac. - Flare Down
CV-2541	7/29/2026 9:20:26 AM	1323	34.4332785	-118.6490442	Valve Adjustment:Barely Open
CV-2542	7/6/2026 12:51:45 PM	1450	34.4338220	-118.6471497	,
CV-2542	7/22/2026 8:26:21 AM	1395	34.4337080	-118.6471885	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2543-PLR	7/6/2026 3:12:48 PM	1302	34.4338092	-118.6484225	,
CV-2543-PLR	7/17/2026 7:57:38 AM	1365	34.4338177	-118.6484885	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2544	7/9/2026 1:34:27 PM	1368	34.4339470	-118.6472208	High Temp,
CV-2544	7/9/2026 1:36:07 PM	1348	34.4338892	-118.6471833	,
CV-2544	7/17/2026 10:00:41 AM	1382	34.4340507	-118.6472480	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open
CV-2544	7/17/2026 10:02:08 AM	1387	34.4340392	-118.6472327	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-2545	7/2/2026 3:43:52 PM	1309	34.4341278	-118.6467348	,
CV-2545	7/22/2026 2:10:43 PM	1375	34.4340507	-118.6467332	Valve Adjustment:Barely Open
CV-2546	7/2/2026 3:39:52 PM	1407	34.4341958	-118.6469635	NSPS/EG CAI,High Temp

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2546	7/2/2026 3:41:04 PM	1391	34.4341975	-118.6469110	,
CV-2546	7/22/2026 2:14:01 PM	1378	34.4341298	-118.6469763	Valve Adjustment:Barely Open
CV-2547	7/7/2026 2:22:04 PM				,
CV-2548	7/2/2026 11:51:45 AM	1404	34.4342967	-118.6455822	,
CV-2548	7/2/2026 11:53:07 AM	1404	34.4344182	-118.6453838	,
CV-2548	7/19/2026 12:37:51 PM	1401	34.4343608	-118.6455858	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp,Positive Static Press.,Increased Flow/Vacuum;Well Comment:pump us active;Well Condition:Lorentz Pump Installed
CV-2548	7/19/2026 12:48:14 PM	1396	34.4343642	-118.6455613	Valve Adjustment:High Temp;Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-2548	7/30/2026 9:44:46 AM	1402	34.4343607	-118.6455820	Valve Comment:valve closed upon arrival;Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp,Positive Static Press.,Increased Flow/Vacuum;Well Comment:Pump is active;Well Condition:Lorentz Pump Installed
CV-2548	7/30/2026 9:55:52 AM	1398	34.4343267	-118.6456053	Valve Adjustment:High Temp,Surging Liquid in Header;Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-2548	7/30/2026 10:06:07 AM	1382	34.4343480	-118.6455957	Valve Adjustment:Increased Flow/Vacuum
CV-2549	7/2/2026 11:44:08 AM	1407	34.4343622	-118.6452728	,
CV-2549	7/19/2026 12:24:06 PM	1408	34.4343733	-118.6452482	Valve Adjustment:Orifice Plate Changed (See OP Log)
CV-2549	7/19/2026 12:26:54 PM	1401	34.4344087	-118.6452087	
CV-2549	7/30/2026 10:10:42 AM	1389	34.4343642	-118.6452837	Valve Adjustment:Increased Flow/Vacuum
CV-2549	7/30/2026 10:12:50 AM	1402	34.4343642	-118.6452642	Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum
CV-2550	7/6/2026 2:12:46 PM	1386	34.4348041	-118.6461671	Valve Adjustment:No Flow Measurement,High Temp
CV-2550	7/6/2026 2:35:00 PM				AtmAA
CV-2550	7/6/2026 2:35:00 PM				AtmAA; [User entered 11.46%]
CV-2550	7/15/2026 1:10:00 PM				AtmAA
CV-2550	7/15/2026 1:15:53 PM	1389	34.4348109	-118.6461330	Valve Adjustment:No Flow Measurement,High Temp
CV-2550	7/28/2026 1:16:37 PM	1366	34.4348469	-118.6461687	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2550	7/28/2026 1:17:15 PM	1368	34.4348405	-118.6461710	Valve Adjustment:No Flow Measurement,High Temp
CV-2551	7/2/2026 9:45:00 AM				AtmAA
CV-2551	7/2/2026 9:56:40 AM	1396	34.4349413	-118.6458142	Valve Adjustment:No Flow Measurement,High Temp
CV-2551	7/9/2026 9:30:00 AM				AtmAA
CV-2551	7/9/2026 9:30:00 AM				AtmAA; [User entered 8.11%]

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2551	7/9/2026 9:34:42 AM	1393	34.4349257	-118.6458681	Valve Comment:Found pump pushing air;Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2551	7/9/2026 9:35:40 AM	1394	34.4349220	-118.6458637	Valve Adjustment:No Flow Measurement,Other - See Daily Log,High Temp
CV-2551	7/16/2026 10:58:39 AM	1396	34.4349143	-118.6458445	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2551	7/16/2026 10:59:26 AM	1397	34.4349138	-118.6458422	Valve Adjustment:No Flow Measurement,High Temp
CV-2551	7/16/2026 11:00:00 AM				AtmAA
CV-2551	7/30/2026 8:34:53 AM	1395	34.4349323	-118.6458206	Valve Adjustment:No Flow Measurement,High Temp
CV-2552	7/8/2026 12:12:15 PM	1374	34.4348800	-118.6465280	Valve Adjustment:Decreased Flow/Vacuum
CV-2552	7/27/2026 2:39:02 PM	1386	34.4348962	-118.6464993	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2553	7/6/2026 3:28:02 PM	1342	34.4341838	-118.6488263	High Temp,
CV-2553	7/6/2026 3:29:35 PM	1322	34.4341660	-118.6489118	,
CV-2553	7/16/2026 2:50:41 PM	1339	34.4341668	-118.6489160	Valve Adjustment:Increased Flow/Vacuum
CV-2554	7/2/2026 10:28:28 AM	1360	34.4344595	-118.6482587	Valve Adjustment:No Flow Measurement,High Temp
CV-2554	7/2/2026 10:30:00 AM				AtmAA
CV-2554	7/29/2026 9:54:52 AM	1345	34.4344660	-118.6482620	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2554	7/29/2026 9:56:46 AM	1335	34.4344863	-118.6482638	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2555	7/2/2026 10:29:34 AM	1366	34.4348318	-118.6477207	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-2555	7/21/2026 1:56:49 PM	1364	34.4348153	-118.6477258	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-2555	7/22/2026 12:09:59 PM	1364	34.4348153	-118.6477243	Valve Adjustment:NSPS/EG CAI,Orifice Plate Changed (See OP Log),High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2555	7/22/2026 12:14:36 PM	1364	34.4348213	-118.6477087	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2556-PLR	7/6/2026 2:55:44 PM	1374	34.4351529	-118.6472008	Valve Adjustment:No Flow Measurement,High Temp
CV-2556-PLR	7/6/2026 3:00:00 PM				AtmAA
CV-2556-PLR	7/6/2026 3:00:00 PM				AtmAA; [User entered 10.72%]
CV-2556-PLR	7/15/2026 1:26:18 PM	1377	34.4351679	-118.6472009	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2556-PLR	7/15/2026 1:30:00 PM				AtmAA
CV-2556-PLR	7/28/2026 1:24:55 PM	1367	34.4351536	-118.6471801	Valve Adjustment:No Flow Measurement,High Temp
CV-2557	7/6/2026 9:34:25 AM	1379	34.4355095	-118.6464673	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2557	7/6/2026 9:35:26 AM	1382	34.4355045	-118.6464778	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2557	7/31/2026 8:57:06 AM	1392	34.4354947	-118.6464943	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2558-PLR	7/2/2026 9:22:49 AM	1395	34.4352776	-118.6463009	Valve Adjustment:High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2558-PLR	7/2/2026 9:25:00 AM				AtmAA
CV-2558-PLR	7/9/2026 9:54:46 AM	1394	34.4352957	-118.6463204	Valve Comment:ACTIVE PLR;Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2558-PLR	7/9/2026 9:55:00 AM				AtmAA
CV-2558-PLR	7/9/2026 9:55:00 AM				AtmAA; [User entered 10.44%]
CV-2558-PLR	7/16/2026 9:55:00 AM				AtmAA
CV-2558-PLR	7/16/2026 9:56:07 AM	1400	34.4352942	-118.6463251	Valve Comment:Active plr;Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Well (Watered In)
CV-2558-PLR	7/16/2026 10:01:19 AM	1401	34.4352951	-118.6463297	Valve Comment:Active PLR;Valve Adjustment:No Flow Measurement,Valve 100% Open
CV-2558-PLR	7/30/2026 10:36:54 AM	1390	34.4352684	-118.6463223	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2558-PLR	7/30/2026 10:37:41 AM	1390	34.4352684	-118.6463223	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2559	7/6/2026 10:36:34 AM	1381	34.4357657	-118.6454977	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-2559	7/6/2026 10:38:03 AM	1392	34.4357578	-118.6454943	Valve Adjustment:NSPS/EG CAC,High Temp
CV-2559	7/27/2026 2:33:18 PM	1393	34.4357635	-118.6454717	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2560	7/6/2026 10:11:08 AM	1399	34.4359170	-118.6466673	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2560	7/20/2026 8:57:37 AM	1424	34.4359730	-118.6466673	No Flow Measurement,

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2561	7/6/2026 10:17:54 AM	1388	34.4360785	-118.6466168	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2561	7/20/2026 8:51:55 AM	1391	34.4360968	-118.6465345	,
CV-2562	7/6/2026 2:16:47 PM	1390	34.4360665	-118.6459582	Valve Adjustment:Barely Open
CV-2563	7/8/2026 3:11:20 PM	1299	34.4371860	-118.6458610	,
CV-2564	7/7/2026 9:09:14 AM	1355	34.4331298	-118.6487688	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down
CV-2564	7/16/2026 2:05:21 PM	1357	34.4331382	-118.6487323	Valve Adjustment:Barely Open
CV-2565	7/1/2026 3:35:54 PM	1286	34.4320550	-118.6490317	,
CV-2565	7/16/2026 9:44:21 AM	1365	34.4320735	-118.6489803	,
CV-2566	7/1/2026 3:33:22 PM	1407	34.4317262	-118.6489208	,
CV-2566	7/16/2026 9:42:16 AM	1398	34.4319060	-118.6487658	,
CV-2567	7/1/2026 11:02:22 AM	1368	34.4319893	-118.6481658	,
CV-2567	7/16/2026 2:13:44 PM	1381	34.4319247	-118.6480070	,
CV-2568	7/1/2026 4:00:33 PM	1358	34.4321572	-118.6477393	,
CV-2568	7/16/2026 2:52:06 PM	1414	34.4320487	-118.6478732	,
CV-2569	7/1/2026 4:03:02 PM	1342	34.4322200	-118.6473623	,
CV-2569	7/16/2026 2:56:59 PM	1401	34.4322098	-118.6473688	,
CV-2570	7/6/2026 10:24:58 AM	1348	34.4324885	-118.6470840	,
CV-2570	7/16/2026 3:05:45 PM	1385	34.4324182	-118.6469643	,
CV-2571	7/7/2026 12:00:31 PM	1136	34.4299467	-118.6457448	Valve Adjustment:Audible Flow;Well Condition:Good
CV-2572	7/7/2026 12:15:50 PM	1148	34.4298112	-118.6470567	
CV-2610	7/25/2026 11:40:20 AM	1118	34.4298393	-118.6465858	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Orifice Plate Changed (See OP Log),Reconnected this Date,Increased Flow/Vacuum
CV-2610	7/25/2026 11:42:03 AM	1137	34.4298410	-118.6465838	Valve Adjustment:Decreased Flow/Vacuum
CV-2610	7/25/2026 11:44:49 AM	1119	34.4298440	-118.6466093	
CV-2610	7/26/2026 10:14:09 AM	1152	34.4298113	-118.6465705	Valve Adjustment:Increased Flow/Vacuum
CV-2610	7/26/2026 10:14:51 AM	1148	34.4298302	-118.6465735	
CV-2663	7/22/2026 12:56:38 PM	1347	34.4350517	-118.6433173	Valve Adjustment:Decreased Flow/Vacuum
CV-2663	7/22/2026 12:58:52 PM	1356	34.4350443	-118.6433288	Valve Adjustment:Increased Flow/Vacuum,Barely Open
CV-2663	7/22/2026 4:04:48 PM	1332	34.4350878	-118.6432972	Valve Adjustment:Decreased Flow/Vacuum
CV-2663	7/22/2026 4:08:46 PM	1341	34.4350735	-118.6433227	Valve Adjustment:Increased Flow/Vacuum
CV-2663	7/24/2026 10:42:38 AM	1342	34.4350536	-118.6433305	Valve Adjustment:NSPS/EG CAI,Increased Flow/Vacuum,Barely Open
CV-2663	7/24/2026 10:44:41 AM	1341	34.4350454	-118.6433214	Valve Adjustment:High Temp,Barely Open
CV-2663	7/24/2026 10:48:15 AM	1341	34.4350439	-118.6433198	Valve Comment:Increase vacuum due to strong odors around casing;Valve Adjustment:High Temp,Increased Flow/Vacuum

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2663	7/24/2026 10:50:52 AM	1340	34.4350434	-118.6433170	Valve Comment:Valve open 10 percent;Valve Adjustment:High Temp
CV-2663	7/26/2026 11:07:52 AM	1337	34.4350577	-118.6433390	
CV-2680	7/15/2026 4:49:56 PM	1259	34.4353835	-118.6421403	Valve Comment:well installed this date;Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Reduce Sys. Vac. - Flare Down
CV-2680	7/15/2026 4:52:34 PM	1267	34.4353687	-118.6421430	
CV-2680	7/20/2026 9:30:35 AM	1306	34.4353945	-118.6421038	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum
CV-2680	7/20/2026 9:34:17 AM	1311	34.4353865	-118.6421070	Valve Adjustment:Barely Open
CV-2680	7/20/2026 9:38:37 AM	1308	34.4353890	-118.6421070	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum
CV-2680	7/20/2026 9:40:30 AM	1295	34.4353723	-118.6421125	
CV-2680	7/21/2026 5:32:16 AM	1285	34.4353793	-118.6421408	Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum
CV-2680	7/22/2026 1:11:09 PM	1284	34.4353622	-118.6421127	Valve Adjustment:Increased Flow/Vacuum
CV-2680	7/22/2026 4:18:33 PM	1275	34.4354030	-118.6421177	Valve Adjustment:Decreased Flow/Vacuum
CV-2680	7/24/2026 10:20:22 AM	1281	34.4353880	-118.6421035	Valve Adjustment:Reconnected this Date,Increased Flow/Vacuum,Barely Open
CV-2680	7/24/2026 10:21:10 AM	1281	34.4353829	-118.6421098	Valve Adjustment:Barely Open
CV-2687	7/21/2026 5:24:06 AM	1254	34.4336038	-118.6415730	Valve Adjustment:Decreased Flow/Vacuum
CV-2687	7/22/2026 1:19:45 PM	1273	34.4335848	-118.6415785	Valve Adjustment:Increased Flow/Vacuum
CV-2687	7/22/2026 1:21:56 PM	1252	34.4335810	-118.6415757	Valve Adjustment:Increased Flow/Vacuum
CV-2687	7/22/2026 1:24:49 PM	1257	34.4335760	-118.6415892	Valve Adjustment:Decreased Flow/Vacuum
CV-2687	7/22/2026 1:26:11 PM	1257	34.4335760	-118.6415887	
CV-2687	7/22/2026 3:51:57 PM	1259	34.4336048	-118.6415670	Valve Adjustment:Decreased Flow/Vacuum
CV-2687	7/22/2026 3:53:55 PM	1256	34.4335822	-118.6415442	Valve Adjustment:Barely Open
CV-2688	7/29/2026 1:13:08 PM	1229	34.4327315	-118.6424188	Valve Adjustment:Reconnected this Date,Decreased Flow/Vacuum
CV-2688	7/29/2026 1:16:09 PM	1242	34.4327115	-118.6424097	
CV-2688	7/30/2026 8:19:40 AM	1213	34.4327447	-118.6424093	Valve Adjustment:Increased Flow/Vacuum
CV-2688	7/30/2026 8:20:55 AM	1226	34.4327372	-118.6424123	
CV-2689	7/20/2026 8:30:00 AM	1254	34.4328373	-118.6433758	Valve Comment:connected this date;Valve Adjustment:Decreased Flow/Vacuum;Well Repairs:Sample Port
CV-2689	7/20/2026 8:34:59 AM	1246	34.4328108	-118.6433387	Valve Adjustment:Increased Flow/Vacuum
CV-2689	7/20/2026 8:50:45 AM	1247	34.4328020	-118.6433570	
CV-2689	7/20/2026 9:11:16 AM	1243	34.4327968	-118.6433533	Valve Adjustment:Positive Static Press.
CV-2689	7/20/2026 10:12:48 AM	1249	34.4328150	-118.6433457	Valve Adjustment:Increased Flow/Vacuum

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2689	7/21/2026 5:46:41 AM	1240	34.4328080	-118.6433570	Valve Adjustment:Increased Flow/Vacuum
CV-2689	7/22/2026 1:43:50 PM	1242	34.4328208	-118.6433585	Valve Adjustment:Increased Flow/Vacuum,Barely Open
CV-2689	7/22/2026 1:50:59 PM	1236	34.4328203	-118.6433578	Valve Adjustment:Increased Flow/Vacuum
CV-2689	7/22/2026 4:29:54 PM	1224	34.4328420	-118.6433678	Valve Adjustment:Decreased Flow/Vacuum
CV-2689	7/22/2026 4:34:31 PM	1226	34.4328493	-118.6433612	
CV-2689	7/23/2026 12:43:00 PM	1239	34.4328468	-118.6433707	Valve Adjustment:NSPS/EG CAI,Reconnected this Date,Positive Static Press.,Increased Flow/Vacuum,Barely Open
CV-2689	7/23/2026 12:48:08 PM	1244	34.4328342	-118.6433685	Valve Adjustment:NSPS/EG CAC,Increased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2690	7/22/2026 3:28:21 PM	1212	34.4323980	-118.6429108	
CV-2690	7/22/2026 3:30:50 PM	1218	34.4323998	-118.6428942	Valve Adjustment:Increased Flow/Vacuum
CV-2690	7/24/2026 10:07:33 AM	1223	34.4323907	-118.6428989	Valve Adjustment:Reconnected this Date,Decreased Flow/Vacuum,Barely Open
CV-2690	7/24/2026 10:09:10 AM	1223	34.4323907	-118.6428989	Valve Adjustment:Barely Open
CV-2690	7/25/2026 12:07:22 PM	1208	34.4323748	-118.6429212	
CV-2690	7/26/2026 10:30:30 AM	1217	34.4323767	-118.6429153	
CV-2691	7/28/2026 9:40:50 AM	1224	34.4321173	-118.6431760	Valve Adjustment:Orifice Plate Changed (See OP Log),Reconnected this Date,Barely Open
CV-2691	7/28/2026 12:47:38 PM	1210	34.4321462	-118.6431960	
CV-48R	7/8/2026 3:14:46 PM	1309	34.4373087	-118.6458817	,
CV-52D	7/6/2026 10:15:17 AM	1306	34.4359532	-118.6424687	,
CV-55R	7/1/2026 2:40:00 PM				AtmAA
CV-55R	7/1/2026 2:40:14 PM	1297	34.4343715	-118.6427790	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-55R	7/1/2026 2:42:13 PM	1297	34.4343709	-118.6427766	Valve Adjustment:High Temp
CV-55R	7/2/2026 11:47:37 AM	1304	34.4343522	-118.6427785	Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Increased Flow/Vacuum
CV-55R	7/9/2026 8:59:26 AM	1320	34.4343633	-118.6427875	Valve Adjustment:High Temp
CV-55R	7/9/2026 9:05:00 AM				AtmAA
CV-55R	7/9/2026 9:05:00 AM				AtmAA; [User entered 16.92%]
CV-55R	7/16/2026 9:15:15 AM	1319	34.4343854	-118.6428110	Valve Adjustment:High Temp
CV-55R	7/16/2026 9:20:00 AM				AtmAA
CV-55R	7/22/2026 2:43:20 PM	1299	34.4343812	-118.6427767	Valve Adjustment:High Temp
CV-55R	7/22/2026 2:44:02 PM	1299	34.4343836	-118.6427780	Valve Adjustment:High Temp
CV-55R	7/30/2026 1:07:16 PM	1312	34.4343779	-118.6427579	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-56D	7/29/2026 9:58:10 AM				[User entered 2.9%]
CV-56D	7/29/2026 9:59:59 AM	1302	34.4338153	-118.6431817	Valve Comment:valve closed upon arrival;Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-56D	7/29/2026 10:03:44 AM	1296	34.4338310	-118.6431942	
CV-56D	7/29/2026 1:40:00 PM				AtmAA <1
CV-56D	7/29/2026 1:40:00 PM				AtmAA <0.10; [User entered 0.10%]
CV-56S	7/6/2026 9:52:49 AM	1298	34.4337795	-118.6431985	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-56S	7/6/2026 9:55:21 AM	1301	34.4337803	-118.6432033	Valve Adjustment:NSPS/EG CAC
CV-56S	7/29/2026 10:14:57 AM				[User entered 3.4%]
CV-56S	7/29/2026 10:18:52 AM	1301	34.4337862	-118.6431945	
CV-56S	7/29/2026 1:30:00 PM				AtmAA <1
CV-56S	7/29/2026 1:50:00 PM				AtmAA <0.10; [User entered 0.10%]
CV-57R	7/6/2026 9:25:36 AM	1350	34.4343092	-118.6435990	
CV-79R	7/6/2026 10:30:12 AM	1325	34.4332523	-118.6448787	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-79R	7/6/2026 10:30:37 AM	1332	34.4332428	-118.6448805	Valve Adjustment:NSPS/EG CAC
CV-94	7/6/2026 9:22:39 AM	1349	34.4348925	-118.6436447	Valve Adjustment:Audible Flow;Well Condition:Good
CV-95	7/6/2026 9:27:21 AM	1357	34.4343207	-118.6436263	
CV-99	7/9/2026 7:45:00 AM				AirTech Lab
CV-99	7/9/2026 7:45:00 AM				AirTech Lab; [User entered 0%]
CV-99	7/14/2026 1:09:14 PM	1321	34.4370498	-118.6463472	Valve Adjustment:Barely Open
CV-99	7/23/2026 2:19:12 PM	1308	34.4370512	-118.6463212	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-99	7/23/2026 2:19:57 PM	1315	34.4370555	-118.6463183	Valve Adjustment:NSPS/EG CAI,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
D-02	7/9/2026 10:23:12 AM	1180	34.4311712	-118.6443032	
D-03	7/9/2026 10:26:06 AM	1178	34.4311753	-118.6442958	
D-04	7/9/2026 10:28:32 AM	1180	34.4311808	-118.6442798	Valve Adjustment:Valve 100% Open
D-09	7/7/2026 12:07:51 PM	1160	34.4301165	-118.6463068	Valve Adjustment:Audible Flow
D-10	7/7/2026 11:45:01 AM	1141	34.4302055	-118.6458210	
FP-001	7/6/2026 1:36:18 PM	1356	34.4365970	-118.6458592	Valve Adjustment:Barely Open
FP-002	7/6/2026 1:39:31 PM	1360	34.4366230	-118.6462073	
FP-003	7/6/2026 1:42:36 PM	1366	34.4366243	-118.6465355	
FP-005	7/8/2026 1:43:07 PM	1364	34.4364732	-118.6472667	Valve Adjustment:Barely Open
FP-006	7/6/2026 8:00:51 AM	1372	34.4363962	-118.6476328	Valve Adjustment:Barely Open
FP-008	7/6/2026 7:43:30 AM	1350	34.4363372	-118.6481742	Valve Adjustment:Decreased Flow/Vacuum
FP-009	7/2/2026 1:39:59 PM	1370	34.4366818	-118.6489330	Valve Adjustment:Barely Open,Surging Liquid in Header
FP-010	7/14/2026 10:08:14 AM	1376	34.4366237	-118.6492652	
FP-011	7/8/2026 1:16:44 PM	1377	34.4365542	-118.6495077	
FP-012	7/1/2026 8:59:25 AM	1358	34.4366915	-118.6499457	
FP-013	7/1/2026 9:24:19 AM	1368	34.4365487	-118.6502413	
FP-014	7/14/2026 10:13:32 AM	1364	34.4364930	-118.6482298	

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
FP-015	7/14/2026 10:16:00 AM	1361	34.4364583	-118.6479283	
FP-016	7/6/2026 7:58:28 AM	1355	34.4364947	-118.6477013	
FP-017	7/8/2026 2:31:56 PM	1283	34.4343308	-118.6487125	,
FP-018	7/8/2026 10:37:14 AM	1340	34.4344250	-118.6490648	
FP-019	7/1/2026 2:11:35 PM	1329	34.4346435	-118.6491418	Valve Adjustment:Barely Open
FP-020	7/1/2026 2:26:14 PM	1332	34.4349315	-118.6492732	
FP-021	7/1/2026 2:37:18 PM	1342	34.4351528	-118.6495722	Valve Adjustment:Decreased Flow/Vacuum
FP-022	7/1/2026 2:31:49 PM	1344	34.4352147	-118.6491795	Valve Adjustment:Decreased Flow/Vacuum
FP-023	7/1/2026 2:40:21 PM	1338	34.4355120	-118.6494252	Valve Adjustment:Barely Open
FP-024	7/2/2026 2:14:20 PM	1365	34.4354958	-118.6477722	Valve Adjustment:Barely Open
FP-025	7/2/2026 2:18:43 PM	1369	34.4353337	-118.6477593	Valve Adjustment:Decreased Flow/Vacuum
FP-026	7/2/2026 2:27:09 PM	1366	34.4350783	-118.6481492	Well Comment:hard pipped
FP-027	7/14/2026 9:07:07 AM	1364	34.4348335	-118.6482585	Valve Comment:Hard pipped
FP-028	7/14/2026 9:09:50 AM	1350	34.4347632	-118.6483862	
FP-029	7/8/2026 10:43:57 AM	1342	34.4343790	-118.6489107	Valve Adjustment:Surging Liquid in Well (Watered In);Well Comment:No system pressure
FP-029	7/8/2026 2:35:22 PM	1358	34.4342783	-118.6489417	,
FP-030	7/1/2026 2:01:04 PM	1326	34.4344957	-118.6497093	Valve Adjustment:Barely Open
FP-031	7/14/2026 9:20:58 AM	1353	34.4348312	-118.6497723	Valve Adjustment:Valve 100% Closed;Well Comment:valve damaged
FP-032	7/1/2026 1:50:54 PM	1336	34.4351002	-118.6498465	Valve Adjustment:Decreased Flow/Vacuum
FP-033	7/1/2026 1:45:21 PM	1346	34.4353680	-118.6499555	Valve Adjustment:Barely Open
FP-034	7/14/2026 9:24:45 AM	1365	34.4356305	-118.6500132	
FP-035	7/1/2026 1:36:10 PM	1365	34.4358560	-118.6501133	Valve Adjustment:Decreased Flow/Vacuum
FP-036	7/1/2026 1:31:08 PM	1380	34.4361425	-118.6501978	Valve Adjustment:Decreased Flow/Vacuum
FP-037	7/1/2026 10:17:41 AM	1375	34.4362707	-118.6502785	Valve Adjustment:Barely Open,Surging Liquid in Header
FP-038	7/7/2026 9:43:23 AM	1332	34.4340682	-118.6497962	Valve Adjustment:Reduce Sys. Vac. - Flare Down
FP-038	7/7/2026 10:42:42 AM	1301	34.4348487	-118.6509373	Valve Adjustment:Reduce Sys. Vac. - Flare Down
FP-039	7/7/2026 9:45:39 AM	1331	34.4341753	-118.6498580	Valve Adjustment:Reduce Sys. Vac. - Flare Down
FP-040	7/7/2026 10:31:45 AM	1283	34.4352990	-118.6510607	Valve Adjustment:Valve 100% Open,Reduce Sys. Vac. - Flare Down
FP-041	7/7/2026 10:50:30 AM	1291	34.4340303	-118.6506422	Valve Adjustment:Reduce Sys. Vac. - Flare Down
FP-042	7/30/2026 10:53:26 AM	1265	34.4332782	-118.6513027	
FP-043	7/7/2026 10:47:36 AM	1278	34.4342468	-118.6507870	Valve Adjustment:Reduce Sys. Vac. - Flare Down
FP-044	7/7/2026 10:44:58 AM	1291	34.4345262	-118.6507642	Valve Adjustment:Reduce Sys. Vac. - Flare Down
FP-045	7/16/2026 2:11:52 PM	1325	34.4334772	-118.6496408	
FP-046	7/8/2026 1:39:49 PM	1366	34.4365908	-118.6473315	
FP-046	7/16/2026 4:36:27 PM	1365	34.4365350	-118.6472280	,

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
FP-047	7/8/2026 1:46:52 PM	1358	34.4367342	-118.6469170	
FP-050	7/2/2026 3:09:30 PM	1362	34.4349020	-118.6473020	,
FP-051	7/2/2026 3:00:23 PM	1342	34.4347985	-118.6470057	,
FP-052	7/6/2026 1:09:00 PM	1266	34.4342403	-118.6481545	,
FP-053	7/6/2026 12:56:22 PM	1270	34.4341498	-118.6477573	,
FP-054	7/2/2026 3:35:07 PM	1391	34.4343320	-118.6471512	,
FP-055	7/6/2026 3:04:30 PM	1385	34.4334540	-118.6483235	,
FP-056	7/6/2026 3:49:54 PM	1286	34.4335265	-118.6486630	,
FP-057	7/2/2026 10:40:18 AM	1450	34.4347613	-118.6455793	,
FP-058	7/2/2026 10:43:14 AM	1421	34.4349547	-118.6458812	,
FP-059	7/2/2026 1:16:15 PM	1342	34.4346392	-118.6458377	,
FP-060	7/2/2026 1:11:41 PM	1385	34.4348850	-118.6460327	,
FP-061	7/6/2026 7:53:11 AM	1351	34.4364357	-118.6479627	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-01 (EXP-01	7/13/2026 8:10:30 AM	1245	34.4376895	-118.6441482	
H-01 (EXP-01	7/22/2026 9:38:27 AM	1237	34.4377282	-118.6441588	
H-01 (EXP-01	7/27/2026 1:53:35 PM	1223	34.4377118	-118.6441473	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-02 (EXP-02	7/13/2026 7:58:53 AM	1266	34.4376857	-118.6445873	Valve Adjustment:Audible Flow;Well Condition:Fair
H-02 (EXP-02	7/22/2026 9:42:16 AM	1246	34.4377285	-118.6446032	
H-02 (EXP-02	7/27/2026 1:51:19 PM	1244	34.4377023	-118.6445958	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-03 (EXP-03	7/13/2026 8:01:45 AM	1269	34.4377113	-118.6446160	Valve Adjustment:Audible Flow;Well Condition:Fair
H-03 (EXP-03	7/22/2026 9:44:31 AM	1238	34.4377343	-118.6446328	
H-03 (EXP-03	7/27/2026 1:48:20 PM	1246	34.4377232	-118.6446257	Valve Adjustment:Valve 100% Open
H-04 (EXP-04	7/13/2026 8:07:00 AM	1267	34.4377275	-118.6446727	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
H-04 (EXP-04	7/13/2026 8:07:32 AM	1249	34.4377238	-118.6446898	Valve Adjustment:NSPS/EG CAC
H-04 (EXP-04	7/22/2026 9:47:27 AM	1247	34.4377412	-118.6447203	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum
H-04 (EXP-04	7/22/2026 9:50:13 AM	1250	34.4377527	-118.6447097	Valve Adjustment:NSPS/EG CAI,High Temp;Well Repairs:Valve
H-08 (EXP-08	7/1/2026 10:41:09 AM	1273	34.4378362	-118.6465773	
H-08 (EXP-08	7/22/2026 10:11:44 AM	1279	34.4378463	-118.6465600	
H-10 (EXP-10	7/1/2026 10:32:28 AM	1288	34.4374310	-118.6470973	
H-10 (EXP-10	7/31/2026 8:12:39 AM	1301	34.4374272	-118.6470822	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
H-101W-PLR	7/3/2026 10:24:03 AM	1193	34.4310792	-118.6505788	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
H-101W-PLR	7/3/2026 10:25:22 AM	1193	34.4310890	-118.6505780	Valve Adjustment:NSPS/EG CAI,High O2
H-102A	7/3/2026 10:16:34 AM	1206	34.4311078	-118.6505750	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
H-1401W	7/3/2026 10:18:08 AM	1205	34.4311327	-118.6505925	

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
H-1404C	7/13/2026 11:16:46 AM	1354	34.4324273	-118.6483073	Valve Adjustment:Barely Open
H-1404C	7/31/2026 9:11:09 AM	1363	34.4324132	-118.6483075	
H-1405C	7/3/2026 9:19:48 AM	1306	34.4326060	-118.6497350	Valve Adjustment:Decreased Flow/Vacuum;Well Comment:Cleared belly
H-1405C	7/20/2026 10:05:45 AM	1314	34.4326042	-118.6497282	Valve Adjustment:High O2,Barely Open
H-1406W	7/3/2026 7:52:35 AM	1258	34.4321737	-118.6507540	Valve Adjustment:Decreased Flow/Vacuum
H-1406W	7/20/2026 12:49:05 PM	1254	34.4321902	-118.6507978	Valve Adjustment:Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
H-1408CR	7/1/2026 8:42:10 AM	1306	34.4314203	-118.6474243	NSPS/EG CAI,High Temp
H-1408CR	7/1/2026 8:44:56 AM	1296	34.4314415	-118.6475325	NSPS/EG CAI,High O2
H-1408E	7/2/2026 12:38:06 PM	1386	34.4333375	-118.6471630	Valve Adjustment:Increased Flow/Vacuum
H-1408E	7/2/2026 12:40:12 PM	1375	34.4333483	-118.6471585	Valve Adjustment:Decreased Flow/Vacuum
H-1408E	7/2/2026 12:41:18 PM	1375	34.4333572	-118.6471640	
H-1408E	7/2/2026 1:12:43 PM	1383	34.4333332	-118.6471577	
H-1408E	7/16/2026 1:43:57 PM	1395	34.4333360	-118.6471748	Valve Adjustment:Barely Open
H-1408E	7/16/2026 1:49:15 PM	1390	34.4333393	-118.6471633	Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum
H-1408E	7/16/2026 1:50:44 PM	1390	34.4333438	-118.6471665	Valve Adjustment:Decreased Flow/Vacuum
H-1408E	7/16/2026 1:51:40 PM	1392	34.4333363	-118.6471627	
H-1408W	7/3/2026 8:28:12 AM	1248	34.4311828	-118.6500193	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
H-1408W	7/3/2026 8:30:59 AM	1251	34.4311883	-118.6499867	Valve Adjustment:NSPS/EG CAI,High O2
H-1409N	7/6/2026 10:40:14 AM	1388	34.4329105	-118.6470152	,
H-1409N	7/16/2026 3:17:34 PM	1375	34.4325392	-118.6473020	,
H-1410S	7/1/2026 8:07:41 AM	1240	34.4310273	-118.6466945	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-1563N	7/7/2026 9:58:28 AM	1329	34.4338670	-118.6498057	Valve Adjustment:Reduce Sys. Vac. - Flare Down
H-1563N	7/16/2026 2:29:54 PM	1333	34.4338700	-118.6498420	Valve Adjustment:Decreased Flow/Vacuum
H-1563S	7/3/2026 9:15:46 AM	1305	34.4324280	-118.6496692	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
H-1563S	7/20/2026 10:01:37 AM	1320	34.4323955	-118.6496487	Valve Adjustment:High O2,Barely Open
H-1565E	7/2/2026 10:08:57 AM	1380	34.4335470	-118.6472407	Valve Adjustment:Plugged/Pinched Suspected;Well Repairs:Sample Port
H-1565E	7/22/2026 8:15:26 AM	1380	34.4335592	-118.6472280	Valve Adjustment:Increased Flow/Vacuum
H-1568N	7/2/2026 1:23:44 PM	1373	34.4333442	-118.6471753	Valve Adjustment:Increased Flow/Vacuum;Well Repairs:Flex Hose
H-1568N	7/2/2026 1:25:23 PM	1375	34.4333505	-118.6471983	
H-1568N	7/16/2026 1:07:53 PM	1378	34.4333562	-118.6471437	Valve Adjustment:Increased Flow/Vacuum;Well Comment:Removed liquid from wellhead;Well Repairs:Flex Hose

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
H-1568N	7/16/2026 1:19:13 PM	1384	34.4333607	-118.6471707	Valve Adjustment:Increased Flow/Vacuum
H-1568N	7/16/2026 1:19:55 PM	1386	34.4333465	-118.6471435	
H-1571S	7/1/2026 10:25:36 AM	1280	34.4321465	-118.6452407	,
H-1572N	7/6/2026 10:41:59 AM	1362	34.4337172	-118.6447347	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
H-1572N	7/6/2026 10:43:57 AM	1359	34.4337077	-118.6447310	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
H-1572N	7/6/2026 10:44:40 AM	1363	34.4337057	-118.6447442	Valve Adjustment:NSPS/EG CAC
H-1572S	7/15/2026 1:05:33 PM	1279	34.4321830	-118.6447252	Valve Adjustment:Barely Open
H-1574N	7/13/2026 9:47:50 AM	1249	34.4325518	-118.6517933	
H-1753N	7/1/2026 2:14:02 PM	1329	34.4347282	-118.6493287	Valve Adjustment:Barely Open
H-1753N	7/22/2026 1:43:28 PM	1346	34.4347252	-118.6493255	Valve Adjustment:Barely Open
H-1753S	7/7/2026 9:40:17 AM	1338	34.4339408	-118.6495755	Valve Adjustment:Reduce Sys. Vac. - Flare Down
H-1753S	7/16/2026 2:36:10 PM	1340	34.4339367	-118.6495902	Valve Adjustment:Decreased Flow/Vacuum
H-1756S	7/3/2026 9:02:07 AM	1287	34.4325838	-118.6502833	Valve Adjustment:Barely Open
H-1756S	7/28/2026 1:12:47 PM	1293	34.4325458	-118.6502853	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1757S	7/3/2026 9:22:05 AM	1315	34.4327415	-118.6497887	Valve Adjustment:Decreased Flow/Vacuum
H-1757S	7/20/2026 10:13:09 AM	1314	34.4327200	-118.6497677	Valve Adjustment:Barely Open
H-1760S	7/7/2026 12:16:26 PM	1302	34.4327327	-118.6478415	,
H-1760S	7/22/2026 9:58:10 AM	1371	34.4327372	-118.6478858	Valve Adjustment:Barely Open
H-1762N	7/1/2026 1:22:19 PM	1383	34.4334748	-118.6468762	Valve Adjustment:Barely Open
H-1762N	7/16/2026 2:13:18 PM	1395	34.4334515	-118.6468860	Valve Adjustment:Orifice Plate Changed (See OP Log)
H-1762N	7/16/2026 2:16:39 PM	1396	34.4334502	-118.6468847	
H-1763N	7/7/2026 2:30:01 PM				Positive Static Press.,NSPS/EG CAI,NSPS/EG CAC,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-1763N	7/7/2026 2:31:23 PM				,
H-1763S	7/6/2026 12:41:01 PM	1316	34.4323892	-118.6460473	
H-1764N	7/6/2026 12:28:11 PM	1368	34.4331490	-118.6456308	Valve Adjustment:Audible Flow
H-1764S	7/1/2026 10:17:27 AM	1280	34.4321602	-118.6454160	,
H-1767N	7/9/2026 1:46:00 PM	1244	34.4326460	-118.6435735	Valve Adjustment:Barely Open
H-1769N	7/1/2026 9:05:19 AM	1364	34.4370120	-118.6495183	Valve Adjustment:Barely Open
H-1769N	7/16/2026 10:27:47 AM	1374	34.4370197	-118.6495073	Valve Adjustment:Barely Open
H-1770N	7/1/2026 9:15:45 AM	1367	34.4368035	-118.6500432	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1770N	7/16/2026 10:37:30 AM	1372	34.4368148	-118.6500348	Valve Adjustment:Barely Open
H-1770S	7/3/2026 7:24:24 AM	1311	34.4331193	-118.6501847	Valve Adjustment:Barely Open;Well Condition:Good
H-1770S	7/20/2026 10:19:12 AM	1317	34.4331205	-118.6501720	Valve Adjustment:Barely Open
H-1771A	7/6/2026 2:01:03 PM	1365	34.4363335	-118.6464113	
H-1771B	7/6/2026 9:52:22 AM	1389	34.4355335	-118.6466578	Valve Adjustment:Increased Flow/Vacuum,Barely Open

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
H-1774N	7/1/2026 9:32:28 AM	1358	34.4367012	-118.6508748	Valve Adjustment:Decreased Flow/Vacuum
H-1774N	7/16/2026 10:45:57 AM	1360	34.4367312	-118.6508098	Valve Adjustment:Barely Open
H-1801S	7/6/2026 10:55:07 AM	1331	34.4337652	-118.6441102	Valve Adjustment:Decreased Flow/Vacuum
H-1802S	7/6/2026 10:35:07 AM	1353	34.4335588	-118.6447492	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
H-1802S	7/6/2026 10:36:34 AM	1356	34.4335673	-118.6447475	Valve Adjustment:NSPS/EG CAI,Barely Open
H-1802S	7/6/2026 10:38:21 AM	1351	34.4335622	-118.6447512	Valve Adjustment:NSPS/EG CAC,Barely Open
H-1803N-PLR	7/6/2026 9:40:00 AM				AtmAA
H-1803N-PLR	7/6/2026 9:40:00 AM				AtmAA; [User entered 15.26%]
H-1803N-PLR	7/6/2026 9:43:25 AM	1338	34.4370247	-118.6486022	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
H-1803N-PLR	7/13/2026 9:30:31 AM	1356	34.4370338	-118.6485987	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Well (Watered In)
H-1803N-PLR	7/13/2026 9:40:00 AM				AtmAA
H-1803N-PLR	7/20/2026 9:30:00 AM				AtmAA
H-1803N-PLR	7/20/2026 9:31:03 AM	1356	34.4370169	-118.6485777	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
H-1803N-PLR	7/27/2026 9:23:26 AM	1354	34.4370061	-118.6485980	Valve Comment:Active PLR;Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
H-1804B	7/2/2026 1:22:54 PM	1293	34.4343172	-118.6456478	,
H-1804N	7/7/2026 9:04:56 AM	1362	34.4363730	-118.6456840	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1804S	7/6/2026 12:30:07 PM	1361	34.4330803	-118.6457030	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
H-1805A	7/2/2026 11:02:16 AM	1434	34.4351668	-118.6450318	,
H-1805A	7/21/2026 10:19:00 AM	1401	34.4351903	-118.6451337	Valve Adjustment:Decreased Flow/Vacuum
H-1805B	7/6/2026 12:07:13 PM	1366	34.4337353	-118.6451902	
H-1805S	7/6/2026 12:19:58 PM	1330	34.4329160	-118.6451818	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
H-1805S	7/6/2026 12:20:18 PM	1330	34.4329252	-118.6451675	Valve Adjustment:NSPS/EG CAC
H-1806A	7/2/2026 11:16:43 AM	1417	34.4354755	-118.6442450	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-1806B	7/6/2026 10:48:27 AM	1353	34.4339150	-118.6444742	
H-1806N	7/7/2026 9:27:30 AM	1356	34.4363655	-118.6443057	Valve Adjustment:Barely Open,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
H-1806S	7/6/2026 10:19:10 AM	1279	34.4328990	-118.6444958	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum,Barely Open
H-1807A	7/6/2026 9:20:28 AM	1352	34.4353512	-118.6436270	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
H-1807N	7/7/2026 9:46:22 AM	1344	34.4364510	-118.6435265	Valve Adjustment:NSPS/EG CAI,High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In)

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
H-1807N	7/7/2026 9:47:04 AM	1349	34.4364482	-118.6435423	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1807S	7/6/2026 9:39:03 AM	1320	34.4338077	-118.6434955	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
H-1952S	7/6/2026 12:43:31 PM	1358	34.4339370	-118.6475053	,
H-1952S	7/29/2026 10:11:32 AM	1366	34.4338512	-118.6475985	Valve Adjustment:Barely Open
H-1955C	7/2/2026 10:55:18 AM	1375	34.4350425	-118.6454540	NSPS/EG CAI,High O2
H-1955C	7/2/2026 10:57:58 AM	1388	34.4350103	-118.6452948	,
H-1955C	7/21/2026 10:12:36 AM	1384	34.4350737	-118.6454140	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1955N	7/7/2026 9:08:05 AM	1347	34.4364875	-118.6455190	Valve Adjustment:Increased Flow/Vacuum
H-1956B	7/2/2026 11:38:20 AM	1401	34.4343693	-118.6447248	,
H-1956N	7/7/2026 9:20:39 AM	1335	34.4364650	-118.6448850	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1956S	7/6/2026 10:23:58 AM	1315	34.4331972	-118.6448798	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Well (Watered In)
H-1956S	7/6/2026 10:24:22 AM	1314	34.4332055	-118.6448792	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Well (Watered In)
H-1956S	7/23/2026 1:24:17 PM	1331	34.4332360	-118.6448587	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
H-1957B	7/2/2026 11:32:45 AM	1355	34.4345510	-118.6440722	,
H-1957N	7/7/2026 9:33:09 AM	1355	34.4364708	-118.6442180	Valve Adjustment:Decreased Flow/Vacuum
H-1957S	7/6/2026 10:57:07 AM	1328	34.4337852	-118.6441372	
H-1958C	7/6/2026 9:18:24 AM	1334	34.4353812	-118.6434822	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
H-1958N	7/7/2026 9:38:14 AM	1344	34.4364557	-118.6435197	Valve Adjustment:Decreased Flow/Vacuum
H-1958S	7/6/2026 9:35:13 AM	1309	34.4340132	-118.6433563	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum;Well Repairs:Valve
H-1958S	7/6/2026 9:35:55 AM	1313	34.4340022	-118.6433495	Valve Adjustment:NSPS/EG CAI,High O2;Well Repairs:Valve
H-1962N	7/1/2026 9:18:59 AM	1362	34.4366573	-118.6501385	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1962N	7/16/2026 10:40:44 AM	1377	34.4366745	-118.6501507	Valve Adjustment:High O2
H-1963N	7/1/2026 9:02:32 AM	1373	34.4369062	-118.6495630	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1963N	7/16/2026 10:24:18 AM	1381	34.4369307	-118.6495488	Valve Adjustment:Barely Open
H-1966N	7/1/2026 9:42:22 AM	1343	34.4365497	-118.6507987	Valve Adjustment:Barely Open
H-1966N	7/16/2026 10:50:23 AM	1351	34.4365668	-118.6507870	Valve Adjustment:Barely Open
H-1967E	7/7/2026 11:48:29 AM	1143	34.4302087	-118.6458087	Valve Adjustment:Decreased Flow/Vacuum

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
H-1967W	7/3/2026 9:51:34 AM	1202	34.4299365	-118.6508120	Valve Adjustment:Audible Flow,Valve 100% Open,Surging Liquid in Header
H-2050E	7/8/2026 11:01:21 AM	1168	34.4291702	-118.6475817	,
H-2050W	7/8/2026 10:04:46 AM	1186	34.4291222	-118.6491060	Valve Adjustment:Decreased Flow/Vacuum
H-2051W	7/3/2026 9:48:44 AM	1201	34.4299308	-118.6508062	Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Surging Liquid in Header
H-2053E	7/9/2026 1:01:15 PM	1066	34.4301910	-118.6459022	,
H-2053W	7/3/2026 10:13:44 AM	1192	34.4311230	-118.6505788	Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Surging Liquid in Header
H-2055E	7/1/2026 9:16:30 AM	1266	34.4317637	-118.6466242	Audible Flow,
H-2055E	7/31/2026 8:41:21 AM	1273	34.4317695	-118.6466057	Valve Adjustment:Decreased Flow/Vacuum
H-2056B	7/7/2026 12:20:01 PM	1149	34.4297125	-118.6474488	Valve Adjustment:Barely Open
H-2056W	7/3/2026 9:46:01 AM	1194	34.4299230	-118.6507755	Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Surging Liquid in Header
H-2057E	7/7/2026 11:56:18 AM	1151	34.4302063	-118.6458185	
H-2057W	7/3/2026 10:10:18 AM	1195	34.4306742	-118.6506427	Valve Adjustment:Increased Flow/Vacuum,Surging Liquid in Header
H-2058E	7/7/2026 12:10:53 PM	1154	34.4300400	-118.6464287	
H-2058W	7/3/2026 9:43:34 AM	1187	34.4299307	-118.6507890	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum,Surging Liquid in Header
H-2059E	7/9/2026 9:21:16 AM	1174	34.4306680	-118.6462493	Valve Adjustment:Valve 100% Open
H-2059W	7/3/2026 10:28:35 AM	1227	34.4311115	-118.6502155	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum,Surging Liquid in Header
H-2161E	7/9/2026 9:25:57 AM	1195	34.4308430	-118.6464568	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-2161W	7/3/2026 10:31:00 AM	1227	34.4309405	-118.6502043	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
H-2163C	7/1/2026 3:20:52 PM	1312	34.4310600	-118.6486802	,
H-2163C	7/16/2026 2:04:14 PM				,
H-2163W	7/3/2026 8:33:34 AM	1250	34.4311783	-118.6498692	
H-2164E	7/1/2026 9:35:21 AM	1270	34.4319060	-118.6461240	Audible Flow,
H-2164E	7/31/2026 12:51:18 PM	1270	34.4319100	-118.6460752	Valve Adjustment:Decreased Flow/Vacuum
H-2165E	7/9/2026 1:29:58 PM	1259	34.4318877	-118.6451215	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-2165W	7/3/2026 8:04:21 AM	1258	34.4321328	-118.6504430	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
H-2165W	7/3/2026 8:04:45 AM	1263	34.4321463	-118.6504193	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open,Surging Liquid in Header
H-2165W	7/8/2026 7:15:00 AM				AirTech Lab
H-2165W	7/8/2026 7:15:00 AM				AirTech Lab; [User entered 5.3%]
H-2165W	7/20/2026 10:29:00 AM	1329	34.4321690	-118.6504197	NSPS/EG CAI,High Temp
H-2165W	7/20/2026 10:31:25 AM	1283	34.4322052	-118.6502968	High Temp,NSPS/EG CAI
H-2166E	7/6/2026 9:13:00 AM	1364	34.4356242	-118.6438712	Valve Adjustment:Increased Flow/Vacuum
H-2168C	7/7/2026 12:56:37 PM	1385	34.4344057	-118.6448168	Valve Adjustment:Valve 100% Open
H-2168E	7/6/2026 11:08:12 AM	1362	34.4345317	-118.6439353	
H-2169C	7/6/2026 12:03:22 PM	1378	34.4340677	-118.6450493	Valve Adjustment:Audible Flow
H-2169E	7/6/2026 11:05:54 AM	1368	34.4342302	-118.6442202	
H-2170N	7/8/2026 12:44:54 PM	1268	34.4357962	-118.6414258	Valve Adjustment:Decreased Flow/Vacuum
H-2170S	7/6/2026 9:39:55 AM	1237	34.4336127	-118.6414653	,
H-2171A	7/22/2026 10:35:38 AM	1264	34.4374260	-118.6425242	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
H-2171A	7/22/2026 10:37:21 AM	1271	34.4374115	-118.6425257	
H-2171A	7/30/2026 10:41:52 AM	1261	34.4374063	-118.6425390	
H-2171B	7/9/2026 11:42:06 AM	1240	34.4365898	-118.6416222	,
H-2171N	7/9/2026 11:10:50 AM	1276	34.4374402	-118.6427223	,
H-2171S	7/8/2026 12:41:11 PM	1260	34.4357905	-118.6414738	Valve Adjustment:Decreased Flow/Vacuum
H-2272W	7/3/2026 8:41:27 AM	1292	34.4317258	-118.6497903	
H-2272W	7/28/2026 10:14:33 AM	1291	34.4317243	-118.6497705	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
H-2273W	7/3/2026 8:59:47 AM	1310	34.4321623	-118.6499658	Valve Adjustment:Decreased Flow/Vacuum
H-2273W	7/8/2026 7:30:00 AM				AirTech Lab
H-2273W	7/8/2026 7:30:00 AM				AirTech Lab; [User entered 0.54%]
H-2273W	7/28/2026 9:48:03 AM	1322	34.4321615	-118.6499543	Valve Adjustment:High O2,Barely Open,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down,Plugged/Pinched Suspected
H-2274B	7/6/2026 10:30:01 AM	1398	34.4326580	-118.6469510	,
H-2274B	7/16/2026 3:08:24 PM	1391	34.4326413	-118.6469227	,
H-2274W	7/3/2026 9:05:07 AM	1294	34.4328010	-118.6503748	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
H-2274W	7/28/2026 1:09:51 PM	1299	34.4327903	-118.6503712	Valve Adjustment:Barely Open
H-2275E	7/6/2026 12:38:37 PM	1309	34.4323967	-118.6462223	Valve Adjustment:Decreased Flow/Vacuum
H-2275W	7/3/2026 8:48:18 AM	1312	34.4322367	-118.6493938	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
H-2275W	7/3/2026 8:48:42 AM	1315	34.4322347	-118.6493898	Valve Adjustment:NSPS/EG CAC
H-2275W	7/20/2026 1:35:47 PM	1325	34.4322138	-118.6493900	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-2276A	7/7/2026 12:12:40 PM	1365	34.4327608	-118.6482248	,

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
H-2276A	7/19/2026 1:13:15 PM	1364	34.4328782	-118.6483002	
H-2276B	7/6/2026 10:36:34 AM	1368	34.4328645	-118.6468532	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-2276B	7/16/2026 3:13:23 PM	1322	34.4328002	-118.6469355	,
H-2276E	7/6/2026 12:16:34 PM	1331	34.4327997	-118.6453655	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
H-2276W	7/3/2026 9:13:09 AM	1303	34.4326793	-118.6499748	Valve Adjustment:Decreased Flow/Vacuum;Well Repairs:Valve
H-2276W	7/20/2026 10:15:45 AM	1307	34.4326792	-118.6499513	Valve Adjustment:Decreased Flow/Vacuum
H-2277A	7/7/2026 9:06:50 AM	1351	34.4330397	-118.6487473	Valve Adjustment:Audible Flow,Barely Open,Reduce Sys. Vac. - Flare Down
H-2277A	7/16/2026 2:02:32 PM	1362	34.4330258	-118.6487273	Valve Adjustment:Barely Open,Surging Liquid in Well (Watered In)
H-2277B	7/2/2026 1:33:25 PM	1394	34.4330608	-118.6469128	
H-2277B	7/7/2026 12:32:31 PM	1322	34.4331075	-118.6470208	,
H-2277B	7/22/2026 9:37:54 AM	1383	34.4330720	-118.6469092	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-23 (EXP-23	7/9/2026 11:33:58 AM	1316	34.4369632	-118.6420008	,
H-2301E	7/9/2026 9:01:57 AM	1030	34.4270680	-118.6479905	Valve Adjustment:Barely Open
H-2301W	7/8/2026 12:56:38 PM	1161	34.4275032	-118.6506025	,
H-2302C	7/7/2026 12:51:29 PM	1126	34.4284123	-118.6489888	Valve Adjustment:Increased Flow/Vacuum
H-2302E	7/8/2026 10:48:12 AM	1109	34.4275437	-118.6472448	,
H-2303E	7/8/2026 10:51:22 AM	1076	34.4279697	-118.6472703	,
H-2303N	7/7/2026 12:58:06 PM	1136	34.4290390	-118.6484312	Valve Adjustment:Decreased Flow/Vacuum
H-2303S	7/8/2026 12:50:38 PM	1109	34.4273838	-118.6496552	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-2304E	7/8/2026 10:53:56 AM	1093	34.4282590	-118.6469293	,
H-2304S	7/8/2026 12:46:00 PM	1001	34.4274465	-118.6488847	,
H-2305N	7/7/2026 12:55:53 PM	1146	34.4289808	-118.6485802	Well Comment:Vacuum surging
H-2305S	7/8/2026 12:38:28 PM	1056	34.4274788	-118.6484690	,
H-2306N	7/8/2026 11:12:08 AM	1079	34.4293425	-118.6476363	,
H-2307S	7/7/2026 12:42:18 PM	1152	34.4284517	-118.6498205	Valve Adjustment:Audible Flow
H-2308S	7/7/2026 12:44:18 PM	1153	34.4284567	-118.6498170	Valve Adjustment:Audible Flow
H-2309N	7/8/2026 10:26:32 AM	1296	34.4307970	-118.6489150	Valve Adjustment:Decreased Flow/Vacuum
H-2309S	7/8/2026 11:46:56 AM	1132	34.4282232	-118.6487612	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-2310N	7/7/2026 12:23:23 PM	1182	34.4298812	-118.6478475	Valve Adjustment:Increased Flow/Vacuum,Barely Open
H-2310S	7/8/2026 11:04:10 AM	1060	34.4292808	-118.6475685	,
H-2401S	7/7/2026 1:38:50 PM	1199	34.4288677	-118.6512170	Valve Adjustment:Increased Flow/Vacuum
H-2402N	7/8/2026 10:18:31 AM	1219	34.4291227	-118.6502543	Valve Adjustment:Audible Flow,Barely Open
H-2402S	7/7/2026 1:13:43 PM	1211	34.4287573	-118.6504715	Valve Adjustment:Audible Flow,Increased Flow/Vacuum

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
H-2403N	7/8/2026 10:13:18 AM	1215	34.4292915	-118.6501588	Valve Adjustment:Decreased Flow/Vacuum
H-2403N	7/8/2026 10:14:45 AM	1217	34.4292865	-118.6501468	
H-2403S	7/7/2026 1:10:49 PM	1195	34.4287573	-118.6498703	Valve Adjustment:Decreased Flow/Vacuum
H-2404N	7/8/2026 10:09:46 AM	1205	34.4293193	-118.6495610	Valve Adjustment:Audible Flow,Barely Open
H-2404S	7/7/2026 12:33:55 PM	1168	34.4287798	-118.6493070	Valve Adjustment:Increased Flow/Vacuum
H-2405N	7/8/2026 10:41:41 AM	1265	34.4299820	-118.6495148	Valve Adjustment:Decreased Flow/Vacuum
H-29	7/8/2026 12:28:55 PM	1261	34.4354182	-118.6417147	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
H-29	7/8/2026 12:33:29 PM	1275	34.4354192	-118.6417525	Valve Adjustment:NSPS/EG CAC
H-72	7/8/2026 3:24:26 PM	1430	34.4370575	-118.6446930	,
H-74	7/8/2026 3:40:26 PM	1243	34.4371170	-118.6433980	,
H-74	7/20/2026 9:52:25 AM	1307	34.4371797	-118.6432975	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header
H-75	7/6/2026 10:04:51 AM	1296	34.4363840	-118.6420927	,
H-79	7/6/2026 9:42:54 AM	1304	34.4339330	-118.6428000	Valve Adjustment:Audible Flow
P-02R	7/8/2026 8:43:54 AM	1115	34.4298427	-118.6439823	
P-03R	7/8/2026 8:58:45 AM	1187	34.4299483	-118.6442137	
P-04	7/8/2026 9:07:17 AM	1155	34.4294902	-118.6445358	
P-05	7/8/2026 9:20:57 AM	1167	34.4291957	-118.6447997	Well Repairs:Flex Hose
P-05	7/8/2026 9:37:13 AM	1161	34.4291498	-118.6447330	
P-05	7/8/2026 9:39:03 AM	1154	34.4291673	-118.6447375	Valve Adjustment:Increased Flow/Vacuum
P-05	7/8/2026 1:30:17 PM	1153	34.4291712	-118.6447682	Well Comment:Flex hose repaired
P-06R	7/8/2026 9:28:01 AM	1145	34.4288558	-118.6450393	Valve Adjustment:Increased Flow/Vacuum
P-06R	7/8/2026 9:30:23 AM	1157	34.4288473	-118.6450375	
P-06R	7/8/2026 9:40:41 AM	1161	34.4291705	-118.6447680	
P-07R	7/8/2026 10:22:36 AM	1199	34.4298415	-118.6432927	
P-08R	7/8/2026 8:36:31 AM	1154	34.4294263	-118.6437413	
P-09	7/1/2026 1:36:56 PM	1160	34.4289770	-118.6442612	
P-10	7/1/2026 1:47:13 PM	1156	34.4287250	-118.6446468	
P-11	7/1/2026 1:54:31 PM	1132	34.4285055	-118.6449697	
P-12	7/8/2026 10:01:31 AM	1123	34.4288442	-118.6456203	
P-12	7/8/2026 10:03:58 AM	1123	34.4288527	-118.6455962	Valve Adjustment:Orifice Plate Changed (See OP Log)
P-13	7/8/2026 9:53:30 AM	1122	34.4284873	-118.6457987	Valve Adjustment:Decreased Flow/Vacuum
P-13	7/8/2026 9:55:58 AM	1131	34.4284925	-118.6458493	
P-13	7/8/2026 10:07:11 AM	1123	34.4288497	-118.6456193	Valve Adjustment:Plugged/Pinched Suspected
P-14	7/1/2026 2:03:05 PM	1105	34.4280250	-118.6460475	
P-15R	7/1/2026 2:10:19 PM	1103	34.4277613	-118.6459382	
P-16	7/20/2026 12:54:22 PM	1105	34.4275455	-118.6456053	Valve Adjustment:Increased Flow/Vacuum
P-17	7/6/2026 2:12:14 PM	1101	34.4273867	-118.6453090	

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
P-18RD	7/6/2026 1:50:44 PM	1105	34.4270842	-118.6450153	Valve Adjustment:NSPS/EG CAI,Increased Flow/Vacuum
P-18RD	7/6/2026 1:52:07 PM	1109	34.4270862	-118.6450148	
P-18RD	7/6/2026 1:53:33 PM	1105	34.4270910	-118.6450005	
P-18RS	7/6/2026 1:58:17 PM	1102	34.4270987	-118.6450102	
P-19	7/6/2026 1:41:07 PM	1072	34.4268712	-118.6451972	
P-20R	7/2/2026 2:11:06 PM	1104	34.4268353	-118.6448477	
P-21	7/2/2026 2:05:54 PM	1114	34.4264977	-118.6447920	
P-21RD	7/2/2026 1:36:40 PM	1129	34.4263902	-118.6444123	
P-21RS	7/2/2026 1:31:20 PM	1131	34.4263878	-118.6443977	
P-22RD	7/20/2026 12:48:40 PM	1176	34.4269167	-118.6438123	
P-22RS	7/20/2026 12:45:58 PM	1175	34.4269222	-118.6437878	
P-23	7/2/2026 1:50:54 PM	1107	34.4261460	-118.6447025	
P-24	7/2/2026 1:18:32 PM	1110	34.4260735	-118.6442848	
P-26	7/20/2026 1:03:55 PM	1131	34.4265358	-118.6432065	
P-27	7/20/2026 1:12:57 PM	1138	34.4268353	-118.6427940	
P-28	7/20/2026 1:18:33 PM	1147	34.4270522	-118.6422750	
P-29R	7/20/2026 1:23:40 PM	1161	34.4271652	-118.6418273	
P-30R	7/20/2026 1:31:27 PM	1163	34.4274122	-118.6415998	Valve Comment:Reduced vacuum flare down
P-32R1	7/27/2026 1:09:08 PM	1171	34.4282392	-118.6410342	
P-32R2	7/27/2026 1:00:31 PM	1177	34.4284335	-118.6409382	
P-33	7/27/2026 12:53:39 PM	1194	34.4288357	-118.6408047	
P-36	7/9/2026 1:53:10 PM	1214	34.4301850	-118.6400610	
P-37	7/9/2026 2:10:42 PM	1228	34.4304737	-118.6403565	
P-38RD	7/15/2026 1:34:09 PM	1246	34.4299995	-118.6406338	
P-38RS	7/15/2026 1:37:49 PM	1244	34.4299745	-118.6406497	
P-39	7/15/2026 1:47:47 PM	1214	34.4294740	-118.6409835	
P-41	7/17/2026 1:27:10 PM	1237	34.4288835	-118.6414333	
P-42R	7/17/2026 1:34:26 PM	1231	34.4284065	-118.6417110	
P-42R	7/17/2026 1:35:31 PM	1230	34.4284087	-118.6416770	
P-43	7/27/2026 2:02:31 PM	1211	34.4282758	-118.6418165	
P-44RD	7/27/2026 1:55:00 PM	1216	34.4281405	-118.6419203	
P-44RS	7/27/2026 1:51:21 PM	1218	34.4281562	-118.6419190	
P-45RD	7/20/2026 1:08:46 PM	1212	34.4277558	-118.6424658	
P-45RD	7/30/2026 8:33:40 AM	1217	34.4277445	-118.6424725	Valve Adjustment:Surging Liquid in Header
P-45RS	7/31/2026 8:40:03 AM	1215	34.4277253	-118.6424617	Valve Adjustment:Barely Open,Surging Liquid in Header
P-46RD	7/20/2026 12:58:59 PM	1208	34.4276597	-118.6426430	
P-46RS	7/20/2026 1:02:00 PM	1215	34.4276583	-118.6426673	
P-46RS	7/20/2026 1:11:30 PM	1213	34.4277588	-118.6424568	
P-46RS	7/28/2026 12:43:27 PM	1209	34.4277523	-118.6424382	
P-46RS	7/30/2026 9:02:21 AM	1217	34.4277527	-118.6424718	Valve Adjustment:Barely Open
P-47	7/20/2026 12:34:13 PM	1212	34.4274488	-118.6432447	
P-47	7/27/2026 9:24:31 AM	1214	34.4274360	-118.6432608	Valve Adjustment:Barely Open
P-48	7/17/2026 2:01:45 PM	1211	34.4275860	-118.6435908	

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
P-49RD	7/13/2026 12:32:12 PM	1205	34.4279793	-118.6438600	
P-49RS	7/13/2026 12:27:08 PM	1209	34.4279868	-118.6438610	
P-52	7/13/2026 1:42:13 PM	1212	34.4287193	-118.6432882	
P-53	7/13/2026 1:00:47 PM	1223	34.4290982	-118.6430453	
P-54	7/13/2026 1:15:17 PM	1228	34.4293833	-118.6428832	
P-55	7/13/2026 1:21:13 PM	1245	34.4297172	-118.6427763	
P-56	7/13/2026 1:34:27 PM	1232	34.4300888	-118.6428363	
P-57	7/13/2026 1:27:44 PM	1231	34.4299822	-118.6424677	
P-60R	7/13/2026 2:12:36 PM	1253	34.4307888	-118.6415470	
P-61	7/27/2026 1:30:00 PM	1225	34.4311343	-118.6411123	
P-65	7/16/2026 9:36:59 AM	1255	34.4303855	-118.6409470	
P-71	7/17/2026 1:54:06 PM	1224	34.4279625	-118.6432283	
P-75	7/13/2026 2:03:27 PM	1247	34.4303180	-118.6415243	
P-76	7/20/2026 2:18:46 PM	1240	34.4301960	-118.6404473	
P-79	7/9/2026 1:00:36 PM	1038	34.4270020	-118.6460538	
SC-2000E	7/1/2026 7:59:51 AM	1201	34.4307053	-118.6467697	Audible Flow,
SC-2501E	7/6/2026 9:35:00 AM				AtmAA
SC-2501E	7/6/2026 9:35:00 AM				AtmAA; [User entered 15.24%]
SC-2501E	7/6/2026 9:38:29 AM	1348	34.4366802	-118.6479324	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
SC-2501E	7/13/2026 9:26:02 AM	1368	34.4366861	-118.6479153	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
SC-2501E	7/13/2026 9:35:00 AM				AtmAA
SC-2501E	7/20/2026 9:21:46 AM	1355	34.4366895	-118.6479141	Valve Adjustment:No Flow Measurement,High Temp
SC-2501E	7/20/2026 9:25:00 AM				AtmAA
SC-2501E	7/27/2026 9:15:01 AM	1359	34.4366853	-118.6479141	Valve Adjustment:No Flow Measurement,High Temp
SC-2501W	7/6/2026 10:10:15 AM	1368	34.4367886	-118.6485435	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
SC-2501W	7/6/2026 10:20:00 AM				AtmAA
SC-2501W	7/6/2026 10:20:00 AM				AtmAA; [User entered 15.45%]
SC-2501W	7/13/2026 9:39:51 AM	1363	34.4368114	-118.6485277	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
SC-2501W	7/13/2026 9:40:22 AM	1365	34.4368112	-118.6485371	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
SW-10	7/31/2026 7:58:44 AM	1335	34.4370395	-118.6503862	Valve Adjustment:Decreased Flow/Vacuum
SW-115	7/7/2026 11:50:26 AM	1219	34.4348213	-118.6412072	Valve Adjustment:Audible Flow
SW-1445	7/9/2026 11:49:56 AM	1222	34.4325408	-118.6519868	Valve Adjustment:Reconnected this Date,Increased Flow/Vacuum
SW-1455	7/9/2026 11:39:16 AM	1199	34.4324252	-118.6518883	Valve Adjustment:Reconnected this Date,Increased Flow/Vacuum
SW-154	7/13/2026 8:17:41 AM	1272	34.4379990	-118.6456553	Valve Adjustment:Audible Flow
SW-154	7/22/2026 10:03:39 AM	1261	34.4379960	-118.6456407	
SW-17-135	7/9/2026 11:44:32 AM	1202	34.4324887	-118.6519533	Valve Adjustment:Reconnected this Date,Increased Flow/Vacuum

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
SW-187	7/14/2026 1:15:47 PM	1319	34.4372507	-118.6473722	
SW-187	7/20/2026 10:40:27 AM	1328	34.4372683	-118.6473400	
SW-20	7/8/2026 10:16:30 AM	1182	34.4302480	-118.6436485	
SW-2501D	7/30/2026 9:36:03 AM	1239	34.4335297	-118.6520038	Valve Adjustment:Valve 100% Open
SW-2501M	7/30/2026 9:30:41 AM	1239	34.4335243	-118.6519803	Valve Adjustment:Valve 100% Open
SW-2501MD	7/30/2026 9:33:08 AM	1241	34.4335363	-118.6519873	
SW-2501S	7/30/2026 9:39:47 AM	1237	34.4335183	-118.6519903	Valve Adjustment:Valve 100% Open
SW-2501S	7/30/2026 9:55:04 AM	1234	34.4337432	-118.6519257	
SW-2502D	7/30/2026 10:03:33 AM	1234	34.4337238	-118.6519335	
SW-2502M	7/30/2026 9:59:45 AM	1231	34.4337413	-118.6519400	
SW-2502S	7/30/2026 9:57:10 AM	1227	34.4337438	-118.6519342	
SW-2503D	7/30/2026 10:09:23 AM	1277	34.4351220	-118.6516003	
SW-2503M	7/30/2026 10:14:22 AM	1270	34.4351220	-118.6515922	
SW-2503MD	7/30/2026 10:11:11 AM	1274	34.4351237	-118.6515963	
SW-2503S	7/30/2026 10:17:02 AM	1261	34.4351245	-118.6515883	
SW-2504D	7/30/2026 10:20:04 AM	1274	34.4352938	-118.6516822	
SW-2504M	7/30/2026 10:21:58 AM	1263	34.4353073	-118.6516800	
SW-2504MD	7/30/2026 10:26:42 AM	1278	34.4353002	-118.6516808	
SW-2504S	7/30/2026 10:23:56 AM	1272	34.4353028	-118.6516860	
SW-30	7/30/2026 9:50:01 AM	1232	34.4336678	-118.6519677	Valve Adjustment:Valve 100% Open
SW-32	7/30/2026 9:47:03 AM	1223	34.4335283	-118.6519997	Valve Adjustment:Valve 100% Open
SW-64	7/30/2026 9:51:59 AM	1232	34.4336710	-118.6519642	Valve Adjustment:Valve 100% Open
SW-65	7/7/2026 11:47:53 AM	1218	34.4348138	-118.6412150	Valve Adjustment:Audible Flow
SW-66	7/13/2026 8:15:49 AM	1267	34.4379932	-118.6456333	Valve Adjustment:Reduce Sys. Vac. - Flare Down
SW-66	7/22/2026 10:01:37 AM	1255	34.4380085	-118.6456595	
SW-68	7/30/2026 9:44:08 AM	1236	34.4335367	-118.6520043	Valve Adjustment:Valve 100% Open
SW-70	7/14/2026 1:18:03 PM	1314	34.4372450	-118.6473505	
SW-70	7/20/2026 10:44:08 AM	1328	34.4372538	-118.6473268	
SW-71	7/2/2026 1:10:31 PM	1126	34.4259885	-118.6438407	
SW-72	7/9/2026 1:49:05 PM	1201	34.4296203	-118.6401832	
SW-80	7/22/2026 9:36:13 AM	1195	34.4383358	-118.6433430	
SW-9	7/14/2026 1:53:02 PM	1315	34.4372413	-118.6473663	
SW-9	7/20/2026 10:46:40 AM	1324	34.4372778	-118.6473323	
TC-1961C	7/1/2026 10:14:09 AM	1283	34.4320958	-118.6454345	,
TC-1961E	7/6/2026 10:16:48 AM	1279	34.4328563	-118.6445150	Valve Adjustment:Audible Flow;Well Condition:Fair
TC-2174	7/6/2026 9:22:38 AM	1339	34.4367419	-118.6476707	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
TC-2174	7/6/2026 9:25:00 AM				AtmAA
TC-2174	7/6/2026 9:25:00 AM				AtmAA; [User entered 15.25%]
TC-2174	7/13/2026 9:12:45 AM	1363	34.4367378	-118.6476192	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum,Valve 100% Open
TC-2174	7/13/2026 9:14:53 AM	1363	34.4367467	-118.6476269	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open

All LFG Extraction Wells - July 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
TC-2174	7/13/2026 9:25:00 AM				AtmAA
TC-2174	7/15/2026 2:14:30 PM	1352	34.4367562	-118.6476240	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum,Valve 100% Open
TC-2174	7/15/2026 2:22:26 PM	1338	34.4367558	-118.6476224	Valve Comment:Moved header to have more fall;Valve Adjustment:No Flow Measurement,High Temp
TC-2174	7/20/2026 9:09:11 AM	1357	34.4367467	-118.6476259	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
TC-2174	7/20/2026 9:15:00 AM				AtmAA
TC-2174	7/27/2026 9:01:39 AM	1345	34.4367451	-118.6476350	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
VL-02	7/30/2026 9:00:19 AM	1187	34.4311863	-118.6443343	Valve Adjustment:Valve 100% Open

Attachment B

Down Well Temperatures

And


List of Wells for Monitoring

LEA Selected Wells for Down Hole Temperature Monitoring
July 2026

Well Number	Down Well Temp Monitoring Monthly	Last Date Monitored for Downwell Temperatures - 2025	2026 Downwell Temperature Monitoring Date	Comments
CV-100	NA	NA	NA	Abandoned Well
CV-103	NA	3/3/2025	NA	Abandoned Well
CV-108-52	Yes	3/4/2025	3/2/2026 and 7/6/2026	
CV-113	Yes	3/10/2025	3/2/2026	
CV-1532	NA	NA	NA	Abandoned Well
CV-1532A	Yes	3/10/2025	2/6/2026 , 3/25/2026 and 6/17/2026	
CV-1535	Yes	3/4/2025	3/2/2026 and 7/6/2026	
CV-1902A	Yes	3/18/2025	2/6/2026, 3/2/2026 and 6/12/2026	
CV-2001	Yes	3/4/2025	3/3/2026 and 6/24/2026	
CV-2002	Yes	6/2/2025	3/4/2026 and 7/6/2026	
CV-2007	Yes	3/5/2025	3/4/2026	
CV-2202	NA	NA	NA	Abandoned Well
CV-2301	Yes	3/11/2025	2/6/2026, 3/5/2026 and 6/12/2026	Lorentz pump removed, no graph possible
CV-2302	Yes	3/11/2025	6/25/2026	Graph Attached 7-1 to 7-31-2026
CV-2303	Yes	3/11/2025	TBD - Pump Installed	Graph Attached 7-1 to 7-31-2026
CV-2312	Yes	3/5/2025	TBD - Pump Installed	
CV-2315	Yes	3/19/2025	6/25/2026	Pump Offline
CV-2341	Yes	3/5/2025	TBD - Pump Installed	
CV-2350	Yes	3/12/2025	TBD - Pump Installed	Lorentz pump is damaged and unable to be removed for repairs, no graphing possible.
CV-2351	Yes	3/12/2025	3/10/2026	
CV-2352	Yes	3/12/2025	4/24/2026 and 4/30/2026	Lorentz pump removed, no graph possible
CV-2353	Yes	5/30/2025	3/10/2026, 4/30/2026 and 6/12/2026	
CV-24007	Yes	3/6/2025	3/10/2026 and 6/12/2026	
CV-24017	Yes	3/6/2025	7/21/2026	Graph Attached 7-1 to 7-31-2026
CV-24053	Yes	3/6/2025	TBD - Pump Installed	
CV-24065	Yes	3/6/2025	7/16/2026	Graph Attached 7-1 to 7-31-2026
CV-24095	Yes	3/7/2025	TBD - Pump Installed	Graph Attached 7-1 to 7-31-2026
CV-24101	Yes	3/7/2025	7/1/2026	
CV-24122	Yes	3/7/2025	3/10/2026	
CV-24127	Yes	3/7/2025	3/10/2026	
CV-24138	Yes	4/1/2025	TBD - Pump Installed	


LEA Selected Wells for Down Hole Temperature Monitoring
July 2026


CV-24139	Yes	8/18/2025	TBD - Pump Installed	
CV-24143	Yes	3/10/2025	6/12/2026	
TC-2385A	NA	NA	NA	Abandoned Well



13 Jul 2026 19:47 (UTC -7)
Temp. Sensor [Analog 1]: 169 °F
CV-2302
July 2, 2026
July 4, 2026
July 6, 2026
July 8, 2026
July 10, 2026
July 12, 2026
July 14, 2026
July 16, 2026
July 18, 2026
July 20, 2026
July 22, 2026
July 24, 2026
July 26, 2026
July 28, 2026
July 30, 2026


12 Jul 2026 13:39 (UTC -7)
Temperature sensor [Analog 1]: 198.3 °F
July 2, 2026
July 4, 2026
July 6, 2026
July 8, 2026
July 10, 2026
July 12, 2026
July 14, 2026
July 16, 2026
July 18, 2026
July 20, 2026
July 22, 2026
July 24, 2026
July 26, 2026
July 28, 2026
July 30, 2026

CV-2303



15 Jul 2026 11:42 (UTC -7)
Temperature sensor [Analog 1]: 201 °F
CV-24017
July 2, 2026
July 4, 2026
July 6, 2026
July 8, 2026
July 10, 2026
July 12, 2026
July 14, 2026
July 16, 2026
July 18, 2026
July 20, 2026
July 22, 2026
July 24, 2026
July 26, 2026
July 28, 2026
July 30, 2026


16 Jul 2026 23:24 (UTC -7)
Lorentz Temp. Sensor [Analog 1]: 143.8 °F
CV-24065
July 2, 2026
July 4, 2026
July 6, 2026
July 8, 2026
July 10, 2026
July 12, 2026
July 14, 2026
July 16, 2026
July 18, 2026
July 20, 2026
July 22, 2026
July 24, 2026
July 26, 2026
July 28, 2026
July 30, 2026


11 Jul 2026 18:10 (UTC -7)
Events:
Analog In 2: Under Current
CV-24095
July 2, 2026
July 4, 2026
July 6, 2026
July 8, 2026
July 10, 2026
July 12, 2026
July 14, 2026
July 16, 2026
July 18, 2026
July 20, 2026
July 22, 2026
July 24, 2026
July 26, 2026
July 28, 2026
July 30, 2026

Attachment C

Item 7 – Well Location Map



N

GRAPHIC SCALE

150 75 0 150 300 150

SCALE: 1"=150'

LEGEND

- 1150 — TOPOGRAPHIC CONTOUR
- EXISTING CELL LIMITS (APPROXIMATE)
- REACTION MITIGATION AREA BOUNDARY (APPOXIMATED BASED ON DATA ANALYSIS)
- REACTION MITIGATION AREA BOUNDARY - CONDITION 9A
- EXISTING HORIZONTAL COLLECTOR PERFORATED PIPE
- H-XX — EXISTING HORIZONTAL COLLECTOR
- CV-XX — EXISTING VERTICAL LFG EXTRACTION WELL

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLOR, DATED AUGUST 5, 2026.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.
3. THE LOCATION OF ANY EXISTING GCCS COMPONENTS AND OTHER FEATURES ARE APPROXIMATE AND SHOULD BE USED FOR INFORMATION PURPOSES ONLY.

DATE | REVISION | NO.

SHEET TITLE: EXISTING VERTICAL & HORIZONTAL LFG EXTRACTION WELL MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544


DSN. BY: - | PROJ. NO. 01204123.45 | DWN. BY: CNW | CHK. BY: - | APP. BY: - | ACAD FILE: FIELD SERVICES

DATE: 08/11/2026

SCALE: AS SHOWN

SHEET: 1

\\scs-fs02\Files\Engineers\Waste Connections\Chiquita Canyon LF\2026 LEA Correspondence\2026 CCL - LEA Appeal Declaration\01-DWG\2026-08-11_CCLF_Existing Well Map-For LEA Response.dwg Aug 11, 2026 2:02pm By: cwoy



LEGEND

- TOPOGRAPHIC CONTOUR
- REACTION MITIGATION AREA BOUNDARY (APPROXIMATE, BASED ON DATA)
- WESTERN BUTRESS FILL LIMITS
- EXISTING CELL LIMITS (APPROXIMATE)
- EXISTING 36" LFG COLLECTION HEADER PIPING
- EXISTING 30" LFG COLLECTION HEADER PIPING
- EXISTING 24" LFG COLLECTION HEADER PIPING
- EXISTING 20" LFG COLLECTION HEADER PIPING
- EXISTING 18" LFG COLLECTION HEADER PIPING
- EXISTING 12" LFG COLLECTION HEADER PIPING
- EXISTING 10" LFG COLLECTION HEADER PIPING
- EXISTING 8" LFG COLLECTION LATERAL PIPING
- EXISTING 4"/6" LFG COLLECTION LATERAL PIPING
- BELOW-GRADE PIPES ARE SHOWN DASHED
- EXISTING FRAC TANKS
- EXISTING ACTIVATED CARBON VESSEL
- EXISTING CONDENSATE SUMP
- EXISTING CORRUGATED LINER RISER
- EXISTING HDPE LINER RISER
- EXISTING LFG VERTICAL EXTRACTION WELL - MAIN CANYON, CANYON A, B, D, PRIMARY
- EXISTING LFG VERTICAL EXTRACTION WELL - PRESSURIZED LEACHATE RELEASE
- EXISTING GABION LFG COLLECTOR WELL
- EXISTING SOIL VAPOR EXTRACTION WELL
- EXISTING SURFACE COLLECTOR WELLHEAD
- EXISTING HORIZONTAL, TRENCH, SLOPE, COLLECTOR WELL
- EXISTING REMOTE VERTICAL WELLHEAD
- EXISTING PERIMETER MIGRATION PROBE
- EXISTING TEMPERATURE PROBE
- EXISTING ISOLATION VALVE
- EXISTING BLIND FLANGE

GENERAL DRAWING NOTES:

1. EXISTING GCCS AS-BUILT DATED AUGUST 10, 2026.
2. EXISTING AERIAL PHOTOGRAPHY REFERENCED AND TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER, DATED AUGUST 5, 2026.
3. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.
4. THE LOCATION OF ANY EXISTING PIPING, VALVES, TIE-IN LOCATIONS AND OTHER FEATURES ARE APPROXIMATE AND SHOULD BE USED FOR INFORMATION PURPOSES ONLY. ACTUAL FIELD CONDITIONS MAY VARY AND SUBJECT TO CHANGE BASED ON TOPOGRAPHIC FEATURES AND OTHER SITE-SPECIFIC FACTORS.

NO.	REVISION	DATE

SHEET TITLE: EXISTING GCCS MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544

PROJ. NO. 01204123.45 | DES. BY: CWW | DRN. BY: CWW | CHK. BY: RNH | APP. BY: - | SGN. BY: SRM / RNH | CAD FILE: ACAD/SBL/LFMASTER5

DATE: 08/12/2026


SCALE: AS SHOWN

1 of 1

\\san-fs02\Data\Files\Engineers\Waste Connections\Chiquita Canyon LF\2026 LEA Corespondence\CCLF Weekly LEA Maps\2026-08-11_CCLF LEA Report Figure.dwg Aug 12, 2026 - 9:37am By: cwoy

Attachment D

Milestone 5 Compliance Data



Ranges Mapped

						# Points
	>=	0	and	<	25	51
	>=	25	and	<	48	27
	>=	48	and	<	52	2
	>=	52	and	<	58	1
	>=	58	and	<	101	
		N/A			N/A	

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill


Range Map

Parameter: CH4 (mid range)

Analysis Method: MostRecent

Date Range: 07/01/2026 - 07/31/2026

Map generation date : 08/11/2026



Ranges Mapped

						# Points
	>=	0	and	<	25	5
	>=	25	and	<	45	9
	>=	45	and	<	55	16
	>=	55	and	<	65	15
	>=	65	and	<	101	36
		N/A			N/A	

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill


Range Map

Parameter: CO2 (mid range)

Analysis Method: MostRecent

Date Range: 07/01/2026 - 07/31/2026

Map generation date : 08/11/2026



Ranges Mapped

						# Points
	>=	0	and	<	0.5	54
	>=	0.5	and	<	2	8
	>=	2	and	<	3.5	8
	>=	3.5	and	<	5	3
	>=	5	and	<	101	8
		N/A			N/A	

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill


Range Map

Parameter: O2 (mid range)

Analysis Method: MostRecent

Date Range: 07/01/2026 - 07/31/2026

Map generation date : 08/11/2026



Ranges Mapped

						# Points
	>=	0	and	<	0.5	53
	>=	0.5	and	<	0.9	17
	>=	0.9	and	<	1.1	8
	>=	1.1	and	<	1.5	3
	>=	1.5	and	<	101	
		N/A			N/A	

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill


Range Map

Parameter: CH4/CO2 Ratio (high range)

Analysis Method: MostRecent

Date Range: 07/01/2026 - 07/31/2026

Map generation date : 08/11/2026



Ranges Mapped

						# Points
	>=	-50	and	<	131	37
	>=	131	and	<	150	13
	>=	150	and	<	165	9
	>=	165	and	<	180	5
	>=	180	and	<	999	17
		N/A			N/A	

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill


Range Map

Parameter: Adj Temp (high range)

Analysis Method: MostRecent

Date Range: 07/01/2026 - 07/31/2026

Map generation date : 08/11/2026



Ranges Mapped

						# Points
	>=	0	and	<	500	25
	>=	500	and	<	1000	7
	>=	1000	and	<	1500	7
	>=	1500	and	<	2000	5
	>=	2000	and	<	10000	20

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill


Range Map

Parameter: CO LAB (mid range)

Analysis Method: MostRecent

Date Range: 07/01/2026 - 07/31/2026

Map generation date : 08/11/2026



Ranges Mapped

						# Points
	>=	0	and	<	2000	9
	>=	2000	and	<	5000	4
	>=	5000	and	<	10000	3
	>=	10000	and	<	50000	8
	>=	50000	and	<	100000	12
	>=	100000	and	<	150000	15
	>=	150000	and	<	1000000	12

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill


Range Map


Parameter: H2 LAB (mid range)

Analysis Method: MostRecent

Date Range: 07/01/2026 - 07/31/2026

Map generation date : 08/11/2026





Point ID / Name


CHIWCV99 / CV-99

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-99 / CV-99

Parameter / Unit

Carbon Monoxide /

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-99 / CV-99


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CV108-52 / CV-108-52

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-108-52 / CV-108-52

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-108-52 / CV-108-52


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CHWCV113 / CV-113

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-113 / CV-113

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-113 / CV-113


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CHWCV114 / CV-114

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-114 / CV-114

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-114 / CV-114


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV1532A / CV-1532A

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-1532A / CV-1532A

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-1532A / CV-1532A


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CHCV1535 / CV-1535

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-1535 / CV-1535

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-1535 / CV-1535


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV1902A / CV-1902A

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-1902A / CV-1902A

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-1902A / CV-1902A


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CHCV2001 / CV-2001

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-2001 / CV-2001

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-2001 / CV-2001


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CHCV2002 / CV-2002

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-2002 / CV-2002

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-2002 / CV-2002


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CHCV2007 / CV-2007

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-2007 / CV-2007

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-2007 / CV-2007

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CHCV2301 / CV-2301

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-2301 / CV-2301

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-2301 / CV-2301


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CHCV2302 / CV-2302

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-2302 / CV-2302

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-2302 / CV-2302


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CHCV2303 / CV-2303

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-2303 / CV-2303

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-2303 / CV-2303

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CHCV2305 / CV-2305

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-2305 / CV-2305

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-2305 / CV-2305


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CHCV2312 / CV-2312

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-2312 / CV-2312

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-2312 / CV-2312


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CHCV2314 / CV-2314

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-2314 / CV-2314

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-2314 / CV-2314


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CHCV2315 / CV-2315

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools




Point ID / Name

CV-2315 / CV-2315

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26



Point ID / Name


CV-2315 / CV-2315


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CHCV2328 / CV-2328

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-2328 / CV-2328

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-2328 / CV-2328


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CHCV2333 / CV-2333

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-2333 / CV-2333

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools




Point ID / Name

CV-2333 / CV-2333

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26



Point ID / Name


CHCV2334 / CV-2334

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-2334 / CV-2334

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-2334 / CV-2334

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CHCV2337 / CV-2337

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-2337 / CV-2337

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-2337 / CV-2337


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CHCV2341 / CV-2341

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-2341 / CV-2341

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-2341 / CV-2341


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CHCV2344 / CV-2344

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-2344 / CV-2344

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-2344 / CV-2344


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CHCV2345 / CV-2345

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-2345 / CV-2345

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-2345 / CV-2345


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CHCV2346 / CV-2346

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-2346 / CV-2346

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-2346 / CV-2346


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CHCV2347 / CV-2347

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-2347 / CV-2347

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-2347 / CV-2347


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CHCV2348 / CV-2348

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-2348 / CV-2348

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-2348 / CV-2348


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CHCV2349 / CV-2349

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-2349 / CV-2349

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-2349 / CV-2349


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CHCV2350 / CV-2350

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-2350 / CV-2350

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-2350 / CV-2350


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CHCV2351 / CV-2351

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-2351 / CV-2351

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-2351 / CV-2351


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CHCV2352 / CV-2352

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-2352 / CV-2352

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-2352 / CV-2352


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CHCV2353 / CV-2353-PLR

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-2353 / CV-2353

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-2353 / CV-2353

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CHCV2354 / CV-2354

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-2354 / CV-2354

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-2354 / CV-2354

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CCV24002 / CV-24002


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools





Point ID / Name


CCV24003 / CV-24003


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools





Point ID / Name


CCV24007 / CV-24007

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24007 / CV-24007

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24007 / CV-24007


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24017 / CV-24017

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24017 / CV-24017

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24017 / CV-24017


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24049 / CV-24049

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24049 / CV-24049

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24049 / CV-24049


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24053 / CV-24053

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24053 / CV-24053

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24053 / CV-24053


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24055 / CV-24055

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24055 / CV-24055

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24055 / CV-24055


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24062 / CV-24062

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24062 / CV-24062

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24062 / CV-24062


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24063 / CV-24063

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24063 / CV-24063

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24063 / CV-24063


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24064 / CV-24064

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24064 / CV-24064

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24064 / CV-24064


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24065 / CV-24065-TP17

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24065 / CV-24065

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24065 / CV-24065


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24066 / CV-24066

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24066 / CV-24066

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24066 / CV-24066


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24069 / CV-24069

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24069 / CV-24069

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24069 / CV-24069


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24070 / CV-24070

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24070 / CV-24070

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24070 / CV-24070


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24071 / CV-24071

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24071 / CV-24071

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24071 / CV-24071


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24075 / CV-24075-TP15


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools





Point ID / Name


CCV24077 / CV-24077


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools





Point ID / Name


CCV24079 / CV-24079-TP8


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools





Point ID / Name


CCV24082 / CV-24082


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools





Point ID / Name


CCV24083 / CV-24083


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools





Point ID / Name


CCV24084 / CV-24084-TP11

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24084-TP11 / CV-24084-TP11

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24084-TP11 / CV-24084-TP11


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24088 / CV-24088


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools





Point ID / Name


CCV24095 / CV-24095

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24095 / CV-24095

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24095 / CV-24095


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24096 / CV-24096


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools





Point ID / Name


CCV24097 / CV-24097


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools





Point ID / Name


CCV24098 / CV-24098


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools





Point ID / Name


CCV24099 / CV-24099


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools





Point ID / Name


CCV24100 / CV-24100

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24100 / CV-24100

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24100 / CV-24100


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24101 / CV-24101

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24101 / CV-24101

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24101 / CV-24101


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24102 / CV-24102


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools





Point ID / Name


CCV24120 / CV-24120

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24120 / CV-24120

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24120 / CV-24120


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24121 / CV-24121

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24121 / CV-24121

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24121 / CV-24121


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24122 / CV-24122

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24122 / CV-24122

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24122 / CV-24122


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24123 / CV-24123


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools





Point ID / Name


CCV24125 / CV-24125-TP20

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24125 / CV-24125

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24125 / CV-24125


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24126 / CV-24126

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24126 / CV-24126

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24126 / CV-24126


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24127 / CV-24127

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24127 / CV-24127

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24127 / CV-24127


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24128 / CV-24128

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24128 / CV-24128

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24128 / CV-24128


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24134 / CV-24134-TP19


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools





Point ID / Name


CCV24138 / CV-24138

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24138 / CV-24138

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24138 / CV-24138


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24139 / CV-24139

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24139 / CV-24139

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24139 / CV-24139


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24140 / CV-24140

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24140 / CV-24140

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24140 / CV-24140


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24141 / CV-24141

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24141 / CV-24141

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24141 / CV-24141


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24142 / CV-24142

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24142 / CV-24142

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24142 / CV-24142

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name

CCV24143 / CV-24143

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


CV-24143 / CV-24143

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


CV-24143 / CV-24143


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CCV24144 / CV-24144


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools





Point ID / Name


CHH1770N / H-1770N

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


H-1770N / H-1770N

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


H-1770N / H-1770N


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CHH2165W / H-2165W

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


H-2165W / H-2165W

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name


H-2165W / H-2165W


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools





Point ID / Name


CHH2273W / H-2273W

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/3/26

SCSeTools



Point ID / Name


H-2273W / H-2273W

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools



Point ID / Name

H-2273W / H-2273W


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 08/01/2025 - 07/31/2026
Chart generation date: 8/5/26

SCSeTools

Thirty Day Maximum Vertical Temperature Map from Temperature Probes at



Max Temps - 20:55:41 07-31-2026

Current | 7 Day | 30 Day

BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	164	15
TP02	157	60
TP03	234	45
TP04	159	60
TP05	167	75
TP06	140	100
TP07	154	100
TP08	186	45
TP09	209	125
TP10	157	125
TP11	212	125
TP12	151	125
TP13	175	140
TP14	173	150
TP15	209	100
TP16	167	30
TP17	163	125
TP18	210	45
TP19	265	150
TP20	143	45
TP21	249	110
TP22	199	15
TP23	260	75
TP24	214	265
TP25	248	130
TP26	178	150
TP27	157	100
TP28	144	170
TP29	190	240
TP30	175	190
TP31	194	180
TP32	171	130
TP33	195	45
TP34	152	120
TP35	175	140
TP36	173	165
TP37	185	180
TP38	172	165
TP39	159	160
TP40	150	185

Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM

SCS ENGINEERS

07224053.00 | July 2, 2026

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

From June 25, 2026, through July 1, 2026, there were three recorded temperature increases and five recorded temperature decreases that triggered the notification limits set forth in the LEA's October 4, 2024 letter.

Chiquita provides the following updates:

- TP-08
  - The 30-foot thermocouple showed a decrease in maximum temperature of 12°F from 157°F to 145°F from June 23rd to June 25th.
  - The 45-foot thermocouple showed a decrease in maximum temperature of 30°F from 167°F to 137°F from June 23rd to July 1st.


- TP-13
  - The 45-foot thermocouple remained consistent with previous recorded temperatures.

- TP-24
  - The 155-foot thermocouple showed a decrease in maximum temperature of 15°F from 183°F to 168°F from June 27th to June 28th, and then an increase in maximum temperature of 9°F from 168°F to 177°F from June 28th to June 29th.
  - The 210-foot thermocouple showed a decrease in maximum temperature of 13°F from 204°F to 191°F from June 27th to June 28th, then an increase in maximum temperature of 12°F from 191°F to 203°F from June 28th to June 29th, and then a decrease in maximum temperature of 10°F from 200°F to 190°F from June 30th to July 1st.

- TP-25
  - The 90-foot thermocouple showed an increase in maximum temperature of 10°F from 193°F to 203°F from June 25th to June 27th.

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39


Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS


Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40

Maximum data for 5/21/2026 12:00 AM to 7/1/2026 12:00 AM



SCS ENGINEERS

Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill



Max Temps - 04:58:46 07-02-2026

Current | 7 Day | 30 Day

BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	160	15
TP02	157	60
TP03	233	45
TP04	158	60
TP05	165	75
TP06	139	100
TP07	154	100
TP08	145	30
TP09	208	125
TP10	156	125
TP11	209	125
TP12	150	125
TP13	172	140
TP14	172	150
TP15	202	100
TP16	168	30
TP17	161	125
TP18	210	45
TP19	237	150
TP20	142	45
TP21	249	110
TP22	198	15
TP23	259	75
TP24	211	265
TP25	216	130
TP26	178	150
TP27	156	100
TP28	143	170
TP29	193	240
TP30	175	190
TP31	193	180
TP32	170	130
TP33	194	45
TP34	152	120
TP35	175	140
TP36	172	165
TP37	184	180
TP38	172	165
TP39	159	160
TP40	149	185

Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM

SCS ENGINEERS

07224053.00 | July 9, 2026

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

From July 2, 2026, through July 8, 2026, there were eleven recorded temperature increases and one recorded temperature decrease that triggered the notification limits set forth in the LEA's October 4, 2024 letter.

Chiquita provides the following updates:

- TP-08
  - The 15-foot thermocouple showed an increase in maximum temperature of 10°F from 138°F to 148°F from July 6th to July 7th.
  - The 30-foot thermocouple showed an increase in maximum temperature of 16°F from 144°F to 160°F from July 6th to July 7th.
  - The 45-foot thermocouple showed an increase in maximum temperature of 34°F from 138°F to 172°F from July 6th to July 7th.

- TP-15
  - The 30-foot thermocouple showed a decrease in maximum temperature of 11°F from 196°F to 185°F from July 2nd to July 4th.


- TP-24
  - The 155-foot thermocouple remained consistent with previous recorded temperatures.
  - The 210-foot thermocouple showed an increase in maximum temperature of 12°F from 190°F to 202°F from July 7th to July 8th.

- TP-25
  - The 30-foot thermocouple showed an increase in maximum temperature of 78°F from 127°F to 205°F from July 7th to July 8th. This temperature increase is likely a result of additional pumping in nearby wells resulting in increased gas movement and extraction in the area.
  - The 45-foot thermocouple showed an increase in maximum temperature of 79°F from 127°F to 206°F from July 7th to July 8th. This temperature increase is likely a result of additional pumping in nearby wells resulting in increased gas movement and extraction in the area.
  - The 60-foot thermocouple showed an increase in maximum temperature of 30°F from 129°F to 159°F from July 5th to July 6th, and then an increase in maximum temperature of 14°F from 159°F to 173°F from July 6th to July 7th, and then an increase in maximum temperature of 34°F from 173°F to 207°F from July 7th to July 8th. This temperature increase is likely a result of additional pumping in nearby wells resulting in increased gas movement and extraction in the area.
  - The 75-foot thermocouple showed an increase in maximum temperature of 69°F from 136°F to 205°F from July 4th to July 5th. This temperature increase is likely a result of additional pumping in nearby wells resulting in increased gas movement and extraction in the area.

- The 90-foot thermocouple showed an increase in maximum temperature of 55°F from 153°F to 208°F from June 22nd to July 8th. This temperature increase is likely a result of additional pumping in nearby wells resulting in increased gas movement and extraction in the area.

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39


Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS


Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40

Maximum data for 5/28/2026 12:00 AM to 7/8/2026 12:00 AM



SCS ENGINEERS


Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill



Max Temps - 04:58:45 07-09-2026

Current | 7 Day | 30 Day

BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	162	15
TP02	157	60
TP03	233	45
TP04	158	60
TP05	166	75
TP06	140	100
TP07	153	100
TP08	171	45
TP09	209	125
TP10	157	125
TP11	211	125
TP12	150	125
TP13	175	140
TP14	173	150
TP15	203	100
TP16	167	30
TP17	161	125
TP18	210	45
TP19	235	150
TP20	141	45
TP21	249	110
TP22	198	15
TP23	260	75
TP24	212	265
TP25	221	130
TP26	178	150
TP27	157	100
TP28	144	170
TP29	187	240
TP30	175	190
TP31	193	180
TP32	170	130
TP33	194	45
TP34	152	120
TP35	175	140
TP36	172	165
TP37	184	180
TP38	172	165
TP39	159	160
TP40	149	185



N

GRAPHIC SCALE

150 75 0 150 300 450

SCALE: 1"=150'

LEGEND

- 1150 — EXISTING TOPOGRAPHIC CONTOUR
- EXISTING CELL LIMITS (APPROXIMATE)
- TP-XX — INSTALLED TEMPERATURE PROBES - STANDALONE
- TP-XX — INSTALLED TEMPERATURE PROBES - INSTALLED WITHIN WELL CASING
- REACTION MITIGATION AREA BOUNDARY (APPROXIMATE) -BASED ON DATA REVIEW
- REACTION MITIGATION AREA BOUNDARY - CONDITION 9A

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER. AERIAL PHOTOGRAPHY DATED JULY 1, 2026.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

NO.	REVISION	DATE

SHEET TITLE: EXISTING TEMPERATURE PROBE MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544

ACAD FILE: -
APP. BY: -
DWN. BY: -
CHK. BY: -
PROJ. NO. 01204123.45
DSN. BY: -

DATE: 07/09/2026

SCALE: AS SHOWN

SHEET: 1

Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM

SCS ENGINEERS

07224053.00 | July 16, 2026

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

From July 9, 2026, through July 15, 2026, there were seven recorded temperature increases and eight recorded temperature decreases that triggered the notification limits set forth in the LEA's October 4, 2024 letter.

Chiquita provides the following updates:

- TP-08
  - The 15-foot thermocouple showed a decrease in maximum temperature of 15°F from 148°F to 133°F from July 7th to July 14th.
  - The 30-foot thermocouple showed a decrease in maximum temperature of 11°F from 169°F to 158°F from July 12th to July 13th.
  - The 45-foot thermocouple showed a decrease in maximum temperature of 21°F from 178°F to 157°F from July 12th to July 13th, then an increase in maximum temperature of 12°F from 157°F to 168°F from July 13th to July 14th.

- TP-10
  - The 45-foot thermocouple showed an increase in maximum temperature of 11°F from 131°F to 142°F from July 9th to July 15th

- TP-15
  - The 30-foot thermocouple remained consistent with previous recorded temperatures.
  - The 45-foot thermocouple showed a decrease in maximum temperature of 12°F from 191°F to 179°F from July 9th to July 14th.

- TP-23
  - The 15-foot thermocouple showed an increase in maximum temperature of 25°F from 192°F to 217°F from July 9th to July 10th, then a decrease in maximum temperature of 18°F from 217°F to 195°F from July 10th to July 15th.

- TP-24
  - The 155-foot thermocouple showed an increase in maximum temperature of 19°F from 167°F to 186°F from July 14th to July 15th.
  - The 210-foot thermocouple showed a decrease in maximum temperature of 12°F from 202°F to 189°F from July 8th to July 12th, then an increase in maximum temperature of 17°F from 189°F to 206°F from July 11th to July 15th.

- TP-25
  - The 15-foot thermocouple recorded an increase in maximum temperature of 96°F from 114°F to 210°F from July 9th to July 10th. This temperature

increase may have resulted from additional pumping at nearby wells, which increased gas movement and extraction in the area. The probe will be removed and evaluated to determine whether any failure or other issue with the probe may have contributed to the elevated reading.


- The 30-foot thermocouple remained consistent with previous recorded temperatures.
- The 45-foot thermocouple remained consistent with previous recorded temperatures.
- The 60-foot thermocouple remained consistent with previous recorded temperatures.
- The 75-foot thermocouple remained consistent with previous recorded temperatures.
- The 90-foot thermocouple remained consistent with previous recorded temperatures.
- The 110-foot thermocouple showed a decrease in maximum temperature of 10°F from 220°F to 210°F from July 14th to July 15th.
- The 130-foot thermocouple showed an increase in maximum temperature of 21°F from 217°F to 238°F from July 2nd to July 14th, then a decrease in maximum temperature of 20°F from 238°F to 218°F from July 14th to July 15th.

We also included an Excel file of the daily maximum temperatures with any high temperatures that triggered the above notification limits highlighted, as requested in the LEA's September 3, 2024 letter.

This report includes recorded temperature increases of greater than 20°F within 24 hours or less, as detailed above, that require a 48-hour notification due to a temperature change.

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39


Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS


Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40

Maximum data for 6/4/2026 12:00 AM to 7/15/2026 12:00 AM



SCS ENGINEERS


Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill



Max Temps - 04:58:45 07-16-2026

Current | 7 Day | 30 Day

BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	162	15
TP02	157	60
TP03	234	45
TP04	159	30
TP05	167	75
TP06	140	100
TP07	153	100
TP08	177	45
TP09	209	125
TP10	157	125
TP11	211	125
TP12	150	125
TP13	175	140
TP14	173	150
TP15	209	100
TP16	167	30
TP17	163	125
TP18	210	45
TP19	235	150
TP20	142	45
TP21	249	110
TP22	199	15
TP23	260	75
TP24	213	265
TP25	238	130
TP26	178	150
TP27	157	100
TP28	144	170
TP29	188	240
TP30	175	190
TP31	193	180
TP32	170	130
TP33	194	45
TP34	152	120
TP35	175	140
TP36	172	165
TP37	185	180
TP38	172	165
TP39	159	160
TP40	149	185



N

GRAPHIC SCALE

150 75 0 150 300 450

SCALE: 1"=150'

LEGEND

- 1150 — EXISTING TOPOGRAPHIC CONTOUR
- EXISTING CELL LIMITS (APPROXIMATE)
- TP-XX — INSTALLED TEMPERATURE PROBES - STANDALONE
- TP-XX — INSTALLED TEMPERATURE PROBES - INSTALLED WITHIN WELL CASING
- REACTION MITIGATION AREA BOUNDARY
- REACTION MITIGATION AREA BOUNDARY - CONDITION 9A

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER. AERIAL PHOTOGRAPHY DATED JULY 8, 2026.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

DATE

REVISION

NO.

SHEET TITLE: EXISTING TEMPERATURE PROBE MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH. (562) 426-9544

ACAD FILE: -
APP. BY: -
DWN. BY: -
CHK. BY: -
PROJ. NO. 01204123.45
DSN. BY: -

DATE: 07/16/2026

SCALE: AS SHOWN

SHEET: 1

Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM

SCS ENGINEERS

07224053.00 | July 23, 2026

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

From July 16, 2026, through July 22, 2026, there were five recorded temperature increases and five recorded temperature decreases that triggered the notification limits set forth in the LEA's October 4, 2024 letter.

Chiquita provides the following updates:

- TP-08
  - The 15-foot thermocouple showed a decrease in maximum temperature of 26°F from 156°F to 130°F from July 12th to July 15th.
  - The 30-foot thermocouple showed an increase in maximum temperature of 27°F from 155°F to 182°F from July 14th to July 22nd.
  - The 45-foot thermocouple showed an increase in maximum temperature of 29°F from 157°F to 186°F from July 13th to July 22nd.

- TP-10
  - The 45-foot thermocouple remained consistent with previously recorded temperatures.

- TP-15
  - The 45-foot thermocouple remained consistent with previously recorded temperatures.

- TP-23
  - The 15-foot thermocouple showed an increase in maximum temperature of 16°F from 194°F to 210°F from July 17th to July 20th.

- TP-24
  - The 100-foot thermocouple showed an increase in maximum temperature of 16°F from 147°F to 163°F from July 13th to July 17th, then a decrease in maximum temperature of 14°F from 163°F to 149°F from July 17th to July 21st.
  - The 155-foot thermocouple showed a decrease in maximum temperature of 15°F from 186°F to 171°F from July 17th to July 18th.
  - The 210-foot thermocouple remained consistent with previously recorded temperatures.

- TP-25

  The atypical temperature profiles observed at each thermocouple for TP-25 were investigated. The exterior temperature of the well casing was measured at 181°F. The area surrounding the temperature probe casing has settled approximately 3 to 4 feet since it was installed, and the inspection confirmed that the probe wiring remained intact. No visible signs of aboveground liquid accumulation were observed.


During thermocouple removal, the first casing section was unthreaded and conditions were allowed to stabilize before work continued. A downhole camera inspection identified approximately 2 to 3 feet of liquid within the temperature probe casing and moisture at several connection points. Following liquid removal by vacuum extraction, observations suggested that the well seals had failed, allowing communication with the casing annulus. The temperature probe is being evaluated to see if it can be repaired or if it needs to be replaced.

- The 15-foot thermocouple remained consistent with previously recorded temperatures.
- The 30-foot thermocouple remained consistent with previously recorded temperatures.
- The 45-foot thermocouple remained consistent with previously recorded temperatures.
- The 60-foot thermocouple remained consistent with previously recorded temperatures.
- The 75-foot thermocouple remained consistent with previously recorded temperatures.
- The 90-foot thermocouple remained consistent with previously recorded temperatures.
- The 110-foot thermocouple showed an increase in maximum temperature of 27°F from 211°F to 238°F from July 19th to July 20th, and then a decrease in maximum temperature of 28°F from 238°F to 210°F from July 20th to July 22nd.
- The 130-foot thermocouple showed an increase in maximum temperature of 27°F from 218°F to 245°F from July 15th to July 20th, and then a decrease of 33°F from 245°F to 212°F from July 20th to July 22nd.

We also included an Excel file of the daily maximum temperatures with any high temperatures that triggered the above notification limits highlighted, as requested in the LEA's September 3, 2024 letter.

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39


Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS


Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40

Maximum data for 6/11/2026 12:00 AM to 7/22/2026 12:00 AM



SCS ENGINEERS


Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill



Max Temps - 04:58:47 07-23-2026

Current | 7 Day | 30 Day

BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	162	15
TP02	157	60
TP03	233	45
TP04	158	60
TP05	167	75
TP06	140	100
TP07	153	100
TP08	185	45
TP09	209	125
TP10	156	125
TP11	212	125
TP12	150	125
TP13	175	140
TP14	173	150
TP15	209	100
TP16	167	30
TP17	158	125
TP18	210	45
TP19	235	150
TP20	142	45
TP21	248	110
TP22	198	15
TP23	258	75
TP24	213	265
TP25	245	130
TP26	178	150
TP27	157	100
TP28	144	170
TP29	190	240
TP30	175	190
TP31	194	180
TP32	171	130
TP33	194	45
TP34	152	120
TP35	175	140
TP36	172	165
TP37	185	180
TP38	172	165
TP39	159	160
TP40	149	185



N

GRAPHIC SCALE

150 75 0 150 300 450

SCALE: 1"=150'

LEGEND

- 1150 — EXISTING TOPOGRAPHIC CONTOUR
- EXISTING CELL LIMITS (APPROXIMATE)
- TP-XX — INSTALLED TEMPERATURE PROBES - STANDALONE
- TP-XX — INSTALLED TEMPERATURE PROBES - INSTALLED WITHIN WELL CASING
- REACTION MITIGATION AREA BOUNDARY
- REACTION MITIGATION AREA BOUNDARY - CONDITION 9A

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER. AERIAL PHOTOGRAPHY DATED JULY 15, 2026.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

DATE

REVISION

NO.

SHEET TITLE: EXISTING TEMPERATURE PROBE MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH. (562) 426-9544

ACAD FILE: -
APP. BY: -
DWN. BY: CNW
CHK. BY: -
PROJ. NO. 01204123.45
DSN. BY: -

DATE: 07/22/2026

SCALE: AS SHOWN

SHEET: 1

Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM

SCS ENGINEERS

07224053.00 | July 30, 2026

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

From July 23, 2026, through July 29, 2026, there were five recorded temperature increases and nine recorded temperature decreases that triggered the notification limits set forth in the LEA's October 4, 2024 letter.

Chiquita provides the following updates:

- TP-08
  - The 30-foot and 45-foot thermocouples exhibited temperature increases of 27°F and 29°F, respectively, between July 12, 2026, and July 22, 2026. The Site observed these temperature changes and conducted an investigation between July 23, 2026, and July 29, 2026. TP-08 is installed within extraction well CV-24079, which is equipped with a liquid extraction pump. The investigation determined that recent pump operations removed liquids from the well over the preceding several weeks, influencing the temperature fluctuations observed within TP-08. As liquid levels declined, temperatures measured at the associated thermocouple depths increased. The subsequent decrease in temperature may be attributable to the removal of heat from the landfill mass as liquids were extracted from the well.
  - The 15-foot thermocouple showed a decrease in maximum temperature of 14°F from 139°F to 125°F from July 23rd to July 28th.
  - The 30-foot thermocouple showed a decrease in maximum temperature of 16°F from 183°F to 167°F from July 23rd to July 29th.
  - The 45-foot thermocouple showed a decrease in maximum temperature of 21°F from 186°F to 165°F from July 23rd to July 29th.

- TP-15
  - The 45-foot thermocouple showed a decrease in maximum temperature of 11°F from 188°F to 177°F from July 22nd to July 23rd.

- TP-19
  - A discrepancy was identified during the review of the weekly data. Upon investigation, the Site determined that the associated battery had failed and subsequently replaced it. During this inspection, the temperature reading from the 125-foot thermocouple was observed to be anomalously low. Further evaluation indicated that the 125-foot thermocouple required replacement. As an interim measure, the Site installed a 120-foot thermocouple that was available onsite and ordered a replacement 125-foot thermocouple. The replacement 125-foot thermocouple will be installed upon receipt.
  - The 45-foot thermocouple showed an increase in maximum temperature of 15°F from 146°F to 161°F from July 23rd to July 24th.

    - The 75-foot thermocouple showed an increase in maximum temperature of 17°F from 145°F to 162°F from July 23rd to July 24th, and then a decrease in maximum temperature of 14°F from 162°F to 148°F from July 24th to July 27th.
    - The 125-foot thermocouple showed a decrease in maximum temperature of 66°F from 167°F to 101°F from July 24th to July 25th, and then an increase in maximum temperature of 68°F from 101°F to 169°F from July 25th to July 28th.
    - The 150-foot thermocouple showed an increase in maximum temperature of 29°F from 236°F to 265°F from July 23rd to July 24th, and then a decrease in maximum temperature of 19°F from 265°F to 246°F from July 24th to July 29th.

- TP-23
    - The 15-foot thermocouple remained consistent with previously recorded temperatures.

- TP-24
    - The 100-foot thermocouple remained consistent with previously recorded temperatures.
    - The 155-foot thermocouple showed a decrease in maximum temperature of 20°F from 187°F to 167°F from July 16th to July 27th.


- TP-25
    - The Site evacuated liquid from the TP-25 probe casing and has been routinely monitoring temperature readings. The Site plans to conduct a follow-up camera inspection of the probe casing to determine whether additional liquid infiltration has occurred within the TP-25 well casing and to assess the condition of the casing interior.
    - The 110-foot thermocouple showed a decrease in maximum temperature of 27°F from 238°F to 210°F from July 20th to July 29th.
    - The 130-foot thermocouple showed an increase in maximum temperature of 36°F from 212°F to 248°F from July 22nd to July 27th.

We also included an Excel file of the daily maximum temperatures with any high temperatures that triggered the above notification limits highlighted, as requested in the LEA's September 3, 2024 letter.

No other sensors showed major sustained increases or decreases in temperature within the landfill per the LEA's reporting limits and no other sensors showed an anomaly, outlier, data gap, or malfunction, as discussed above. In the past week there were no other recorded temperature increases in the TMP field of greater than 10°F within 7 days or less, greater than 20°F within 14 days or less, or greater than 30°F within 21 days or less.

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39


Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS


Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40

Maximum data for 6/18/2026 12:00 AM to 7/29/2026 12:00 AM



SCS ENGINEERS

Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill



Max Temps - 04:58:45 07-30-2026


Current | 7 Day | 30 Day

BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	163	15
TP02	157	60
TP03	233	45
TP04	159	60
TP05	167	75
TP06	140	100
TP07	154	100
TP08	186	45
TP09	209	125
TP10	157	125
TP11	212	125
TP12	151	125
TP13	175	140
TP14	173	150
TP15	206	100
TP16	165	30
TP17	158	125
TP18	210	45
TP19	265	150
TP20	143	45
TP21	248	110
TP22	198	15
TP23	258	75
TP24	213	265
TP25	247	130
TP26	178	150
TP27	157	100
TP28	144	170
TP29	188	240
TP30	175	190
TP31	193	180
TP32	170	130
TP33	195	45
TP34	152	120
TP35	175	140
TP36	173	165
TP37	185	180
TP38	172	165
TP39	159	160
TP40	150	185

TP-08: The 30-foot and 45-foot thermocouples exhibited temperature increases of 27°F and 29°F, respectively, between July 12, 2026, and July 22, 2026. The Site observed these temperature changes and conducted an investigation between July 23, 2026, and July 29, 2026. TP-08 is installed within extraction well CV-24079, which is equipped with a liquid extraction pump. The investigation determined that recent pump operation removed liquids from the well over the preceding several weeks, influencing the temperature fluctuations observed within TP-08. As liquid levels declined, temperatures measured at the associated thermocouple depths increased. The subsequent decrease in temperature may be attributable to the removal of heat from the landfill mass as liquids were extracted from the well.

TP-19: A discrepancy was identified during the review of the weekly data. Upon investigation, the Site determined that the associated battery had failed and subsequently replaced it. During this inspection, the temperature reading from the 125-foot thermocouple was observed to be anomalously low. Further evaluation indicated that the 125-foot thermocouple required replacement. As an interim measure, the Site installed a 120-foot thermocouple that was available on-site and ordered a replacement 125-foot thermocouple. The replacement 125-foot thermocouple will be installed upon receipt.

TP-25: The Site evacuated liquid from the TP-25 probe casing and has been routinely monitoring temperature readings. The Site plans to conduct a follow-up camera inspection of the probe casing to determine whether additional liquid infiltration has occurred within the TP-25 well casing and to assess the condition of the casing interior.



N

GRAPHIC SCALE

150 75 0 150 300 450

SCALE: 1"=150'

LEGEND

- 1150 — EXISTING TOPOGRAPHIC CONTOUR
- EXISTING CELL LIMITS (APPROXIMATE)
- TP-XX — INSTALLED TEMPERATURE PROBES - STANDALONE
- TP-XX — INSTALLED TEMPERATURE PROBES - INSTALLED WITHIN WELL CASING
- REACTION MITIGATION AREA BOUNDARY
- REACTION MITIGATION AREA BOUNDARY - CONDITION 9A

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER. AERIAL PHOTOGRAPHY DATED JULY 22, 2026.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

NO.	REVISION	DATE

SHEET TITLE: EXISTING TEMPERATURE PROBE MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH. (562) 426-9544

DSN. BY: - | DWN. BY: CNW | CHK. BY: - | APP. BY: -

PROJ. NO. 01204123.45 | ACAD FILE: ENGINEERS

DATE: 07/30/2026

SCALE: AS SHOWN

SHEET: 1

Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM

SCS ENGINEERS

07224053.00 | August 6, 2026

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

From July 30, 2026, through August 05, 2026, there were four recorded temperature increases and six recorded temperature decreases that triggered the notification limits set forth in the LEA's October 4, 2024 letter.

Chiquita provides the following updates:

- TP-08
  - The 30-foot and 45-foot thermocouples exhibited temperature increases of 27°F and 29°F, respectively, between July 12, 2026, and July 22, 2026. In response, Site personnel observed the temperature changes and conducted an investigation from July 23, 2026, through July 29, 2026. Following the investigation, temperatures continued to decline from July 30, 2026, through August 5, 2026.
  - TP-08 is installed within extraction well CV-24079, which is equipped with a liquid extraction pump. The investigation determined that the existing pump is experiencing a power-related issue and requires removal. Site personnel have identified the need for a replacement pump and plan to complete the replacement next week.
  - The 15-foot thermocouple showed a decrease in maximum temperature of 21°F from 139°F to 118°F from July 23rd to August 5th.
  - The 30-foot thermocouple showed a decrease in maximum temperature of 33°F from 183°F to 150°F from July 23rd to August 5th.
  - The 45-foot thermocouple showed a decrease in maximum temperature of 20°F from 166°F to 146°F from July 30th to August 5th.

- TP-15
  - The 45-foot thermocouple remained consistent with previously recorded temperatures.
  - The 100-foot thermocouple showed a decrease in maximum temperature of 11°F from 208°F to 197°F from August 1st to August 5th.

- TP-19
  - A discrepancy was identified during the review of last week's data. Upon investigation, the Site determined that the associated battery had failed and subsequently replaced it. During this inspection, the temperature reading from the 125-foot thermocouple was observed to be anomalously low. Further evaluation indicated that the 125-foot thermocouple required replacement. As an interim measure, the Site installed a 120-foot thermocouple that was available onsite and ordered a replacement 125-foot thermocouple. The replacement 125-foot thermocouple will be installed upon receipt.
  - The 45-foot thermocouple remained consistent with previously recorded temperatures.
  - The 75-foot thermocouple remained consistent with previously recorded temperatures.

    - The 125-foot thermocouple remained consistent with previously recorded temperatures.
    - The 150-foot thermocouple showed a decrease in maximum temperature of 28°F from 265°F to 237°F from July 24th to August 2nd.


- TP-23
    - The 15-foot thermocouple showed an increase in maximum temperature of 21°F from 197°F to 218°F from July 29th to July 30th, and then a decrease in maximum temperature of 21°F from 218°F to 197°F from July 30th to July 31st.

- TP-24
    - The 155-foot thermocouple showed an increase in maximum temperature of 10°F from 167°F to 177°F from July 29th to August 4th.
    - The 210-foot thermocouple showed an increase in maximum temperature of 10°F from 193°F to 203°F from July 29th to August 4th.

- TP-25
    - The Site plans to conduct a follow-up camera inspection next week of the probe casing to determine whether additional liquid infiltration has occurred within the TP-25 well casing and to assess the condition of the casing interior.
    - The 110-foot thermocouple remained consistent with previously recorded temperatures.
    - The 130-foot thermocouple showed an increase in maximum temperature of 40°F from 212°F to 252°F from July 22nd to August 4th. As described above, the Site is continuing to assess the condition of this probe equipment.

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39


Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS


Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40

Maximum data for 6/25/2026 12:00 AM to 8/5/2026 12:00 AM



SCS ENGINEERS

Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill




Max Temps - 04:58:43 08-06-2026

Current | 7 Day | 30 Day

BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	166	15
TP02	157	60
TP03	233	45
TP04	159	60
TP05	167	75
TP06	140	100
TP07	154	100
TP08	166	45
TP09	209	125
TP10	157	125
TP11	212	125
TP12	150	125
TP13	175	140
TP14	173	150
TP15	208	100
TP16	164	30
TP17	158	125
TP18	211	45
TP19	244	150
TP20	143	45
TP21	248	110
TP22	198	15
TP23	258	75
TP24	214	265
TP25	251	130
TP26	179	150
TP27	157	100
TP28	144	170
TP29	187	240
TP30	175	190
TP31	192	180
TP32	170	130
TP33	196	45
TP34	152	120
TP35	175	140
TP36	173	165
TP37	185	180
TP38	172	165
TP39	159	160
TP40	150	185

TP-08: The 30-foot and 45-foot thermocouples exhibited temperature increases of 27°F and 29°F, respectively, between July 12, 2026, and July 22, 2026. In response, Site personnel observed the temperature changes and conducted an investigation from July 23, 2026, through July 29, 2026. Following the investigation, temperatures continued to decline from July 30, 2026, through August 5, 2026.
oTP-08 is installed within extraction well CV-24079, which is equipped with a liquid extraction pump. The investigation determined that the existing pump is experiencing a power-related issue and requires removal. Site personnel have identified the need for a replacement pump and plan to complete the replacement next week.
TP-19: A discrepancy was identified during the review of the weekly data. Upon [RH2.1]investigation, the Site determined that the associated battery had failed and subsequently replaced it. During this inspection, the temperature reading from the 125-foot thermocouple was observed to be anomalously low. Further evaluation indicated that the 125-foot thermocouple required replacement. As an interim measure, the Site installed a 120-foot thermocouple that was available onsite and ordered a replacement 125-foot thermocouple. The replacement 125-foot thermocouple will be installed upon receipt.
TP-25: The Site plans to conduct a follow-up camera inspection next week of the probe casing to determine whether additional liquid infiltration has occurred within the TP-25 well casing and to assess the condition of the casing interior.



N

GRAPHIC SCALE

150 75 0 150 300 450

SCALE: 1"=150'

LEGEND

- 1150 — EXISTING TOPOGRAPHIC CONTOUR
- EXISTING CELL LIMITS (APPROXIMATE)
- REACTION MITIGATION AREA BOUNDARY
- REACTION MITIGATION AREA BOUNDARY - CONDITION 9A
- TP-XX — EXISTING TEMPERATURE PROBE - STANDALONE
- TP-XX — EXISTING TEMPERATURE PROBES - INSTALLED WITHIN WELL CASING

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER. AERIAL PHOTOGRAPHY DATED JULY 29, 2026.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

NO.	REVISION	DATE

SHEET TITLE: EXISTING TEMPERATURE PROBE MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544

PROJ. NO. 01204123.45 | DSN. BY: RNH | DWN. BY: CNW | CHK. BY: - | ACAD FILE ENGINEERS | APP. BY: -

DATE: 7/15/2026

SCALE: AS SHOWN

SHEET: 1

N:\CAD\ASBUILT – MASTERS\CHIQUITA\GCCS\2026 ACAD\2026-08-05_CCLF_Existing Temperature Probe Map.dwg Aug 05, 2026 – 4:16pm By: cway

Attachment E

August 10, 2026

Reaction Mitigation Area Boundary Determination

August 10, 2026
File No. 01204123.21-13

Mr. Baitong Chen
South Coast Air Quality Management District
21865 Copley Drive
Diamond Bar, California 91765

Subject: Monthly Reaction Mitigation Area Boundary Determination
Chiquita Canyon Landfill – Castaic, California

Dear Mr. Chen:

In accordance with Condition Nos. 9(a) and 9(b) of the Modified Stipulated Order for Abatement (SOFA) pertaining to the Chiquita Canyon Landfill (Landfill or Facility) (Case No. 6177-4), as last modified on June 3, 2026, SCS Engineers (SCS), on behalf of Chiquita Canyon, LLC (Chiquita), has prepared this data-determined Reaction Mitigation Area boundary determination for July 2026 considering the following criteria:

- Vertical landfill gas (LFG) wellhead temperatures (greater than 160 degrees Fahrenheit).
- Temperature monitoring probe (TMP) measurements (greater than 170 degrees Fahrenheit for more than 3-weeks at any depth).
- Landfill gas quality and methane to CO_2 ratio (CH_4:CO_2) (methane concentrations of less than 30 percent in conjunction with CH_4:CO_2 ratios less than 1.0).
- Landfill gas concentration of carbon monoxide (CO) (greater than 1,500 ppm), to the extent measured.
- Landfill gas concentration of hydrogen (H_2) (greater than 2 percent by volume), to the extent measured.
- Landfill settlement (18 inches or greater within a 60-day period).
- Pressurized leachate releases.

These parameters have been subjected to a cumulative evaluation within each individual landfill surface grid within the Main Canyon (i.e., excluding grids 1 through 29 as well as grids 105 through 144), including all landfill gas wells, temperature probes, and other characteristics within that grid's area. For each individual landfill grid that is contiguous to the prior month's Reaction Mitigation Area, where any three or more parameters listed above are present at the time of evaluation, including any combination of wells, temperature probes, or areas within the grid, the Reaction Mitigation Area boundary depicted on the Reaction Mitigation Area map (**Attachment A**) includes such landfill grid(s).

For each individual landfill grid that is not contiguous to the prior month's Reaction Mitigation Area, if the three parameters present include a temperature parameter (the first or second parameter listed above), then the grid has been added to the Reaction Mitigation Area. For each individual landfill grid

that is not contiguous to the prior month's Reaction Mitigation Area, if the three parameters present do not include a temperature parameter, then Chiquita conducted field testing for CO using colorimetric tubes and for H_2 using field instrumentation. If field testing confirmed the presence of either CO or H_2 at concentrations in excess of the lower limits of the instrumentation (100 ppm for CO and 1 percent by volume for H_2), then a sample of the LFG was obtained from the wellhead and subjected to lab analytical testing using U.S. EPA Method ALT-144 for CO and ASTM Method D-1946 for H_2. If the lab testing confirmed that either of these parameters exceed the values listed above, then the grid has been added to the Reaction Mitigation Area.

In addition to the parameters listed above, the following factors were also considered in determining the Reaction Mitigation Area boundary, applying the same individual landfill grid-based methodology described above:

- Leachate seeps;
- Odor characteristics;
- Wellheads experiencing conditions which would be expected to result in a pressurized leachate release (e.g., elevated pressure, elevated temperature, liquid flow through wellhead); and
- Waste cuttings according to borehole drilling logs.

Supporting evidence, including documentation of which parameters were met or exceeded for each individual landfill grid, field testing and laboratory results (if applicable), explanation for the determination, Reaction Mitigation Area boundary, Reaction Mitigation Area map (if applicable), isothermal gradient range map consisting of wellhead temperature measurements, wellhead carbon monoxide range map, wellhead hydrogen range map, wellhead CH_4:CO_2 ratio range map, monthly landfill settlement isopach maps and 60-day isopach map, wellhead and temperature probe map with surface grids displayed, and vertical temperature profiles for temperature probes is being hereby submitted to the South Coast Air Quality Management District.

Attachment A presents the Drawing, titled "Reaction Mitigation Area Map", which depicts the Reaction Mitigation Area boundary as prescribed in Condition No. 9(a), which corresponds to the limits of Cells 1/2A, 2B/3, 4, and Module 2B/3/4 P2, as a solid black line. The Drawing also depicts the Condition No. 9(b) data-determined Reaction Mitigation Area as a dashed magenta line.

REACTION MITIGATION AREA BOUNDARY

Based on the parameters and considerations above, the Reaction Mitigation Area boundary includes those grids corresponding to the area encompassed by last month's data-driven Reaction Mitigation Area boundary determination and now also includes Grid Nos. 34, 38, 41, and 211.

Based on input from Chiquita, the change in landfill surface elevations in select grids positioned to the south of Cell 2B/3 and Module 4 was affiliated with earthwork, grading, and stripping of intermediate cover in preparation for ethylene vinyl alcohol (EVOH) geomembrane cover deployment. While it is recognized that some settlement in these areas may have occurred, the earthwork and cover removal activities are believed to be the predominant contributor to the elevation change

experienced over the past few months. Accordingly, the landfill surface elevation change in these grids was not considered to exhibit the settlement criteria during this monthly exercise.

Parameters in Contiguous Grids

- Grid No. 211 is positioned immediately east of and adjacent to Grid No. 212 and south of and adjacent to Grid No. 208, both of which were included in last month's Reaction Mitigation Area boundary. Accordingly, Grid No. 211 is being incorporated in the Reaction Mitigation Area boundary for this month as a contiguous surface grid based on methane concentrations of less than 30 percent in conjunction with CH_4:CO_2 ratios less than 1.0 at wells CV-24100, H2165W, H-2272W, and H-2273W, as well as the H_2 concentration at well H-2165W.

Parameters in Non-Contiguous Grids

- Grid No. 34 is surrounded by Grid Nos. 30, 33, 35, and 38, none of which were included in last month's Reaction Mitigation Area boundary, so it is a non-contiguous grid. The grid contains three wells (CV-24163, H-1572N, and H-1802S) that exhibited methane concentrations of less than 30 percent in conjunction with CH_4:CO_2 ratios less than 1.0. Grid No. 34 also contains TP-38, which exhibited a temperature of greater than 170 degrees Fahrenheit for more than three weeks. Accordingly, Grid No. 38 is being included in the Reaction Mitigation Area boundary for this month as a non-contiguous surface grid. No field testing or laboratory sampling for CO and H_2 concentrations was conducted at any wellheads within the grid because TP-38 exceeded a temperature criterion.

- Grid No. 38 is surrounded by Grid Nos. 34, 37, 39, 42, and 43, none of which were included in last month's Reaction Mitigation Area boundary, so it is a non-contiguous grid. The grid contains three wells (CV-56S/D, CV-1701S/D, and CV-24118) that exhibited methane concentrations of less than 30 percent in conjunction with CH_4:CO_2 ratios less than 1.0. Based on laboratory sampling for CO and H_2 concentrations conducted at these wellheads, the same three wells exhibited H_2 concentrations greater than 2 percent by volume and well CV-1701D exhibited CO concentration greater than 1,500 ppm. Accordingly, Grid No. 38 is being included in the Reaction Mitigation Area boundary for this month as a non-contiguous surface grid.

- Grid No. 41 is surrounded by Grid Nos. 36, 37, 40, 42, 45, and 46, none of which were included in last month's Reaction Mitigation Area boundary, so it is a non-contiguous grid. The grid contains two wells (CV-55R and CV-2011A) that exhibited methane concentrations of less than 30 percent in conjunction with CH_4:CO_2 ratios less than 1.0. Well CV-55R also exhibited an H_2 concentration greater than 2 percent by volume. Based on laboratory sampling for CO and H_2 concentrations conducted at these two wellheads, well CV-55R exhibited a H_2 concentration greater than 2 percent by volume. Accordingly, Grid No. 41 is being included in the Reaction Mitigation Area boundary for this month as a non-contiguous surface grid.

CONCLUSION

As presented on the Drawing included as **Attachment A**, and for the reasons described above, the extent of the data-determined Reaction Mitigation Area (dashed magenta line) includes Cells 1/2A, 2B/3, 4, and Module 2B/3/4 P2 as decreed in the SOFA (solid black line), and Grid Nos. 34, 38, 53, 76, 77, 81, 82, and 145 through 149.

The maximum temperature measurements recorded at the 40 in-situ waste temperature monitoring probes during the month are presented in **Attachment B** in graphical format. The LFG wellhead temperatures recorded at the extraction wells for the entire Landfill footprint are reflected on the isothermal gradient range map presented as **Attachment C**. The CH_4:CO_2 ratios measured at the LFG wellheads in the vicinity of the data-driven Reaction Mitigation Area boundary are depicted on the range map presented as **Attachment D**. The H_2 concentrations measured at the LFG wellheads in the vicinity of the data-driven Reaction Mitigation Area boundary are depicted on the range map presented as **Attachment E**. The CO concentrations measured at the LFG wellheads in the vicinity of the data-driven Reaction Mitigation Area boundary are depicted on the range map presented as **Attachment F**. The landfill surface settlement isopach values measured on a monthly basis and 60-day basis in the vicinity of the data-driven Reaction Mitigation Area boundary are depicted on the range map presented as **Attachment G**. The field testing and lab sampling results for H_2 and CO concentrations at wells positioned within non-contiguous surface grids that did not exhibit a temperature criterion, which are included in the Reaction Mitigation Area boundary this month, are included in **Attachment H**, as applicable.

Please contact either of the undersigned if you have questions or require additional information.

Sincerely,

Robert E. Dick, PE, BCEE
Senior Vice President
SCS Engineers

Patrick S. Sullivan, BCES, CCP
Senior Vice President
SCS Engineers

RED/PSS

cc: Nathaniel Dickel, SCAQMD
Christina Ojeda, SCAQMD


Enclosures:

Attachment A – Reaction Mitigation Area Map
Attachment B – In-Situ Waste Temperature Monitoring Probe Data
Attachment C – Isothermal Gradient Range Map
Attachment D – Wellhead Methane-to-Carbon Dioxide Ratio Range Map
Attachment E – Wellhead Hydrogen Range Map
Attachment F – Wellhead Carbon Monoxide Range Map

Attachment G – Settlement Isopach Range Maps
Attachment H – Wellhead Hydrogen and Carbon Monoxide Field Testing / Lab Sampling Data

Attachment A

Reaction Mitigation Area Map



GENERAL DRAWING NOTES:

1. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

DATE | REVISION | NO.

REACTION MITIGATION AREA - JULY 2026

CHIQUITA CANYON LANDFILL
CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 100
LONG BEACH, CA 90806
PH: (562) 426-9544

PROJ. NO. 01204123.45 | DWN. BY: HA | ACAD. NUC-ADASBUILT-MASTERS | APP. BY: -
DSN. BY: - | CHK. BY: -

DATE: 08/10/2026

SCALE: AS SHOWN

CLIENT:

SHEET TITLE:

PROJECT TITLE:

1 of 1


\\san-fs02\Files\Engineers\Waste Connections\Chiquita Canyon_LF\2026 Temp Probe Data\Isothermal Gradient Maps\07-July 2026\2026 Reaction Mitigation Area - July 2026_2026-08-10.dwg Aug 10, 2026 - 5:08pm By: raulramirez

Attachment B

In-Situ Waste Temperature Monitoring Probe Data

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Apr 15, 2024
Apr 22, 2024
Apr 29, 2024
May 6, 2024
Jun 2, 2026
Jun 9, 2026
Jun 16, 2026
Jun 23, 2026
Jun 30, 2026
Jul 7, 2026
Jul 14, 2026
Jul 21, 2026
Jul 28, 2026
Aug 4, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Apr 15, 2024 Apr 22, 2024 Apr 29, 2024 May 6, 2024 Jun 2, 2026 Jun 9, 2026 Jun 16, 2026
Jun 23, 2026 Jun 30, 2026 Jul 7, 2026 Jul 14, 2026 Jul 21, 2026 Jul 28, 2026
Aug 4, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Apr 29, 2024 May 6, 2024 May 13, 2024 May 20, 2024 Jun 2, 2026 Jun 9, 2026 Jun 16, 2026
Jun 23, 2026 Jun 30, 2026 Jul 7, 2026 Jul 14, 2026 Jul 21, 2026 Jul 28, 2026
Aug 4, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Apr 15, 2024
Apr 22, 2024
Apr 29, 2024
May 6, 2024
Jun 2, 2026
Jun 9, 2026
Jun 16, 2026
Jun 23, 2026
Jun 30, 2026
Jul 7, 2026
Jul 14, 2026
Jul 21, 2026
Jul 28, 2026
Aug 4, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Apr 7, 2025
Apr 14, 2025
Apr 21, 2025
Apr 28, 2025
Jun 2, 2026
Jun 9, 2026
Jun 16, 2026
Jun 23, 2026
Jun 30, 2026
Jul 7, 2026
Jul 14, 2026
Jul 21, 2026
Jul 28, 2026
Aug 4, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Feb 16, 2026 Feb 23, 2026 Mar 2, 2026 Mar 9, 2026 Jun 2, 2026 Jun 9, 2026 Jun 16, 2026
Jun 23, 2026 Jun 30, 2026 Jul 7, 2026 Jul 14, 2026 Jul 21, 2026 Jul 28, 2026
Aug 4, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Apr 7, 2025
Apr 14, 2025
Apr 21, 2025
Apr 28, 2025
Jun 2, 2026
Jun 9, 2026
Jun 16, 2026
Jun 23, 2026
Jun 30, 2026
Jul 7, 2026
Jul 14, 2026
Jul 21, 2026
Jul 28, 2026
Aug 4, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Feb 10, 2025
Feb 17, 2025
Feb 24, 2025
Mar 3, 2025
Jun 2, 2026
Jun 9, 2026
Jun 16, 2026
Jun 23, 2026
Jun 30, 2026
Jul 7, 2026
Jul 14, 2026
Jul 21, 2026
Jul 28, 2026
Aug 4, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Feb 10, 2025 Feb 17, 2025 Feb 24, 2025 Mar 3, 2025 Jun 2, 2026 Jun 9, 2026 Jun 16, 2026
Jun 23, 2026 Jun 30, 2026 Jul 7, 2026 Jul 14, 2026 Jul 21, 2026 Jul 28, 2026
Aug 4, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Dec 15, 2025
Dec 22, 2025
Dec 29, 2025
Jan 5, 2026
Jun 2, 2026
Jun 9, 2026
Jun 16, 2026
Jun 23, 2026
Jun 30, 2026
Jul 7, 2026
Jul 14, 2026
Jul 21, 2026
Jul 28, 2026
Aug 4, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Attachment C

Isothermal Gradient Range Map



LEGEND

- EXISTING CELL LIMITS (APPROXIMATE)
- REACTION MITIGATION AREA BOUNDARY (APPROXIMATE) - BASED ON DATA REVIEW
- REACTION MITIGATION AREA BOUNDARY - CONDITION 9A
- GP-XX EXISTING PERIMETER MIGRATION PROBE
- TP-XX EXISTING TEMPERATURE PROBE

GENERAL DRAWING NOTES:

1. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

DATE

REVISION

NO.

SHEET TITLE: ISOTHERMAL GRADIENT MAP JULY 2026

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH. (562) 426-9544

ACAD FILE: -
APP. BY: -
DWN. BY: SRM
CHK. BY: -
PROJ. NO. 01204123.41
DSN. BY: -

DATE: 08/10/2026


SCALE: AS SHOWN

SHEET: 1

J:\san-fs02\Files\Engineers\Waste Connections\Chiquita Canyon LF\2026 Temp Probe Data\Isothermal Gradient Maps\07-July 2026\CCLF Isothermal Map-April 2026_V1.0_2026-08-10.dwg Aug 10, 2026 - 7:56pm By: rhuber

Attachment D

Wellhead Methane-to-Carbon Dioxide Ratio Range Map



Ranges Mapped

						# Points
	>=	0	and	<	0.5	160
	>=	0.5	and	<	0.9	88
	>=	0.9	and	<	1.1	64
	>=	1.1	and	<	1.5	70
	>=	1.5	and	<	101	2

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill

Range Map

Parameter: CH4/CO2 Ratio (mid range)


Analysis Method: MostRecent

Date Range: 07/01/2026 - 07/31/2026

Map generation date : 08/10/2026

Attachment E

Wellhead Hydrogen Range Map



Ranges Mapped

						# Points
	>=	0	and	<	20000	27
	>=	20000	and	<	50000	7
	>=	50000	and	<	100000	25
	>=	100000	and	<	999999	66

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

The range values noted above are in units of parts per million (ppm). Divide by 10,000 to convert these values to units of percent by volume.

N

SCSeTools

Chiquita Canyon Landfill

Range Map

Parameter: H2 (mid range)


Analysis Method: MostRecent

Date Range: 07/01/2026 - 07/31/2026

Map generation date : 08/10/2026

Attachment F

Wellhead Carbon Monoxide Range Map



Ranges Mapped

						# Points
	>=	0	and	<	500	35
	>=	500	and	<	1000	15
	>=	1000	and	<	1500	16
	>=	1500	and	<	2000	22
	>=	2000	and	<	5000	41
	>=	5000	and	<	100000	

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill

Range Map

Parameter: CO LAB (mid range)

Analysis Method: MostRecent

Date Range: 07/01/2026 - 07/31/2026


Map generation date : 08/10/2026

Attachment G

Settlement Isopach Range Maps

July 1, 2026
vs. July 29, 2026




June 2, 2026
vs. July 29, 2026
-10 ft
-1.5 ft
1.5 ft
10 ft

Attachment H

Wellhead Hydrogen and Carbon Monoxide Field Testing / Lab Sampling Data

Landfill Gas Wellhead Hydrogen (H2) and Carbon Monoxide (CO) Concentrations
July 2026 Field Testing & Laboratory Sampling Data for Non-Contiguous Surface Grids
Chiquita Canyon Landfill


Point ID	Point Name	Field H2 Concentration [% by volume]	Lab H2 Concentration (% by volume)	Field CO Concentration [ppmv]	Lab CO Concentration (ppmv)
CHWCV56D	CV-56D		2.9		1
CHWCV56S	CV-56S		3.4		1
CCV1701D	CV-1701D		19.2		3060
CCV1701S	CV-1701S		4.2		338
CCV1701S	CV-1701S		5.6		
CCV24118	CV-24118		14.8		2650
CCV24118	CV-24118		12.8		
CHWCV55R	CV-55R		16.9		296
CHWCV55R	CV-55R				380
CHWCV55R	CV-55R				317
CHCV2011	CV-2011A		20.2		380
CHCV2011	CV-2011A				799

Attachment F

July 2026 Isopach Map

Chiquita Canyon Landfill -Isopach





Jul 29, 2026 Survey Image. Jul 1, 2026 vs Jul 29, 2026