SCS ENGINEERS

October 15, 2026

Karen Gork
Chief Environmental Health Specialist
Los Angeles County Local Enforcement Agency
5050 Commerce Drive
Baldwin Park, California 91706

Subject: **September 2026 Monthly Report Pursuant to Milestones 1A-3 and 5 of the LEA June 6, 2024 Compliance Order and July 30, 2024 Letter, Chiquita Canyon Landfill, Castaic, California**

Dear Ms. Gork:

SCS Engineers (SCS), on behalf of Chiquita Canyon, LLC (Chiquita), hereby provides the Los Angeles County Department of Public Health, Solid Waste Management Program, acting as the Local Enforcement Agency (LEA) with a monthly report pursuant to Milestones 1A-3 and 5 of the LEA Compliance Order dated June 6, 2024 (Compliance Order) and subsequent related correspondence received from the LEA. This report covers the monthly period for September 2026.

Chiquita Canyon Landfill (CCL or Landfill) is a landfill/solid waste disposal facility located at 29201 Henry Mayo Drive in Castaic, California. In connection with the Landfill, Chiquita operates a landfill gas collection and control system. SCS prepared and submitted the Carbon Monoxide and Hydrogen Reading Summary Report (Summary Report) to the LEA on June 6, 2024, on behalf of Chiquita, in response to the directives in the LEA letters dated April 5, 2024 and May 28, 2024 regarding collection of landfill gas data and in accordance with Milestone 1A-2 of the Compliance Order. The LEA, in collaboration with the California Department of Resources, Recycling, and Recovery (CalRecycle), reviewed the Summary Report and determined that it complied with Milestone 1A-2. The LEA set forth several new requirements for Chiquita to comply with Milestone 1A-3 in follow-up correspondence dated July 30, 2024.

This report was prepared in accordance with Milestones 1A-3 and 5 of the Compliance Order, the LEA's follow-up correspondence dated July 30, 2024, Chiquita's letter dated September 3, 2024, the September 12, 2024, meeting with the LEA, and follow-up correspondence from the LEA dated November 19 and 27 and December 3, 2024.

Milestone 1A-3 Compliance Items

1. Submit the laboratory test results for monthly sampling of carbon monoxide (CO) and hydrogen (H2) from a set of landfill gas (LFG) wells selected by the LEA. Please see Table 1, columns labeled "CO" and "H2".

Results for wells monitored are shown in **Attachment A**.[1] The data is being submitted to the LEA in a standalone report signed by a licensed engineer, in accordance with Milestone 1A-3 of the Compliance Order. As noted in Chiquita's prior correspondence and monthly reports, this report does not include data from wells CV-100, CV-103, CV-1420, CV-1423, CV-1532, CV-2202, H-1403W, H-1560S, H-1774S, SC-2001W, TC-2383S, TC-2385A, and TC-2385S, as those wells have been abandoned, or from well CV-2332, as that well was never installed. All remaining wells were tested during the month of September 2026.

As discussed during the September 12, 2024 meeting, and as previously reported, graphics showing CO and H2 trends are provided in **Attachment D** and are discussed further below.

2. Provide data from readings for fixed gases (CH4, O2, and CO2) from a set of LFG wells selected by the LEA. See Table 1, column labeled "Fixed Gas CH4, O2, CO2."

The results for wells monitored are provided in **Attachment A**.

3. Collect down well temperatures at 34 wells to confirm the gas wellhead temperature readings per the requirement of the New Source Performance Standards (NSPS). See Table 1, column labeled "Down Well Temp Monitoring."

It is Chiquita's understanding from the LEA's November 27, 2024 correspondence, and as noted in prior monthly reports, that, at this time, Chiquita is only required to sample the wells at the annual frequency provided in the NSPS protocols, but that the LEA may require more frequent monitoring for up to ten (10) wells selected by the LEA. Chiquita is awaiting the LEA's selection of those wells.

Chiquita nevertheless provides in **Attachment B** the down-hole temperature graphs[2] concerning the following wells from fixed locations which contain the Lorentz Pumping System with integral temperature sensors while they were in operation during September 2026: CV-2302, CV-2303, CV-24017, CV-24065 and CV-24095.

Please note that the following locations, CV-2301, CV-2350 and CV-2352, no longer have graphs available due to various equipment-related issues, including damaged casings. (See **Attachment B** Monitoring List).

---

[1] The lab(s) reported data from additional LFG wells outside of those selected for sampling by the LEA; the additional data is related to separate South Coast Air Quality Management District (South Coast AQMD) reporting requirements and therefore can be disregarded for purposes of this report.

[2] Each graph notes a single temperature data point due to changes in the software.

SCS will continue to collect down-hole temperatures for wells on an annual basis and will report the results as the data is obtained at each location. SCS has performed annual down-hole temperature monitoring at 24 locations as of the end of September 2026, (Results are shown in **Attachment B**). The remaining five (5) wells will be monitored in accordance with the annual requirements and as pumps are repaired or replaced (See **Attachment B** for well monitoring dates and remaining locations).

4. Sample the selected 40 wells for VOCs by method TO-15. See Table 1, column labeled "VOC (TO-15)."

The results for wells monitored are provided in **Attachment A**.[3] Please note that 31 locations for VOC sampling were tested during September 2026. Nine locations (CV-100, CV-103, CV-1532, CV-2202, H-1403W, H-1560S, H-1758N, H-1774S, and TC-2385A) were not sampled as they have been abandoned.

5. Continue to sample and monitor 6 horizontal wells as indicated in Attachment 1, well numbers highlighted in yellow. At this time, 42 horizontal wells may be released from continued sampling, however, wells may be included later depending on future data submissions. See Table 1, well numbers highlighted in blue.

As noted in the September 3, 2024 letter and reported in prior monthly reports, two (2) of the six (6) horizontal wells (H-1774S and H-1560S) were abandoned when the new vertical extraction wells were installed. Additionally, H-1403W has since been abandoned. Thus, data from those wells are not included. Data from the three (3) other horizontal wells are in **Attachment A**.

6. Add 20 vertical wells to the monthly wellhead temperature and LFG sampling protocols. See Table 1.

As conveyed by the LEA during our September 12, 2024 meeting, and restated in our prior monthly reports, we understand the LEA is requiring laboratory analytical data for fixed gases, CO, and H2, as well as field data. Laboratory results are in **Attachment A**. Field data with wellhead gas temperatures are shown on Table 2 in **Attachment A**.

We understand from the LEA's November 27, 2024 correspondence that laboratory analytical data will be required for the specified fixed gases.

As noted in prior monthly reports, sampling was not conducted at the following wells in September 2026 for the reasons identified below:

CV-1420 – Abandoned during 2024 GCCS Expansion due to declining gas flows.
CV-2202 – Abandoned during 2024 GCCS Expansion due to declining gas flows.

[3] Well CV-24142 is listed twice in Table 1 of the LEA's July 30, 2024 letter – one requires VOC sampling, and the other does not. Chiquita sampled this well for VOCs.

CV-2332 – This well does not exist. This well was proposed for installation in Fall 2023, but other wells were installed in the area in lieu of CV-2332 when the number of wells increased pursuant to the Stipulated Order for Abatement (Stipulated Order) with the South Coast Air Quality Management District (South Coast AQMD).

7. Plot to show the locations of the following 19 wells on the site map titled "Existing GCCS Map – LFG Vertical Extraction Wells" dated 06/06/2024: CV-24002, CV-24003, CV-24007, CV-24017, CV-24053, CV-24055, CV-24065, CV-24071, CV-24075, CV-24077, CV-24079, CV-24082, CV-24083, CV-24088, CV-24095, CV-24096, CV-24097, CV-24098 and H-1403W. For well H-1403W, provide the horizontal location of piping and an estimate where the high temperature (195°F) is most likely occurring. See Table 1, well numbers highlighted in red and H-1403W (highlighted in yellow).

The locations of the above-identified wells are shown on the Map in **Attachment C.**[4]

8. Include in the monthly report, a settlement/heat map as shown below, beginning with the earliest heat map data available for each month to present. The topographic maps should show 2-foot contour intervals if possible.

The LEA directed Chiquita on June 2, 2025 to submit isopach maps on a monthly basis to comply with this request. For ease of reference, we are submitting as **Attachment F** a copy of the September 2026 isopach map, which was initially submitted to the LEA with the weekly cover logs on October 13, 2026.

9. Provide the sampling results in a standalone report with the appropriate discussion, tables, QA/QC, methods and signed by a registered professional, etc., as described in the Compliance Order Milestone 1A-2 and 1A-3.

CCL has provided the above-requested information and the raw data in **Attachment A**, as well as a figure with settlement data (see **Attachment F**). Temperature graphs are provided for wells with Lorentz pumps (5 locations).

Please note that in addition to the wells listed in response to the request dated July 30, 2024 (in Table 1) that could not be tested, the following wells that only required analytical data could also not be tested, as previously reported, because they were abandoned during the 2024 and 2025 GCCS expansion due to declining gas flows in accordance with the requirements of the NSPS: CV-100, CV-103, CV-1420, CV-1423, CV-1532, CV-2202, H-1403W, H-1560S, H-1774S, SC-2001W, TC-2383S, TC-2385A, and TC-2385S. Finally, as also previously reported, CV-2332 was never installed.

[4] The LEA acknowledged in its November 20, 2024 correspondence that a high temperature is not occurring in well H-1403W. We therefore did not map the maximum temperature at well H-1403W.

Sampling Procedures

Gas samples were collected using Tedlar or Mylar bags, as described in Chiquita's September 3, 2024 letter and the prior monthly reports, and then delivered to certified laboratories for testing. All permanent gas (CH4, CO2, O2, N2, CO, and H2) data were analyzed within the requested 24 hours of sampling. SCS continues to believe that use of the EPA-approved 72-hour holding time for these samples would be appropriate and accurate. Nevertheless, in response to the LEA's March 17, 2025 correspondence, SCS will continue to request 24-hour holding times for all fixed gases, including CO, H2, and VOCs, collected using Mylar or Tedlar bags. However, if additional sampling is required or if the laboratories have a change in workload, this holding time may change, in which case the LEA will be notified accordingly. During September 2026, all wells were tested for VOCs (EPA method TO-15) and permanent gases (EPA methods 1946 and Alt-144) within 24 hours by providing the laboratory with duplicate bag samples as needed for VOC testing.

Additional gas and pressure data were collected using either an Envision Irwin Gas Meter or Landtec GEM 5000 Gas monitoring device. These instruments measure combustible gas concentrations in air directly on either of two scales, the first as a percent by volume of the lower explosive limit (LEL) of methane gas in air (0 to 5 percent) and the other as a percent by volume (0 to 100 percent) in the gas sampled. The detection limit for these instruments is approximately 0.10 percent by volume.

Gas monitoring testing procedures were as follows:

- Connect sample tubing, open test valve, observe pressure, and record data.
- Turn on sample pump, purge a minimum of one probe volume, and observe and record methane, oxygen, and carbon dioxide gas concentrations when readings have stabilized.
- Close test valve, disconnect sample instruments, and secure sample location.

Milestone 1A-3 Conclusions

September 2026 was the twenty-sixth monitoring performed pursuant to Milestone 1A-3 of the Compliance Order. The data collected in September 2026 and evaluated for this report are consistent with the data collected in the previous months of August 2024 through August 2026 as well as the data collected and evaluated by Chiquita's technical experts in accordance with the Stipulated Order to assess the Reaction Mitigation Area, including the September 2026 data most recently evaluated on October 9, 2026, as required by Conditions 9(a) and 9(b) of the Stipulated Order, most recently modified on June 3, 2026. (See **Attachment E**.)

For the reasons described in the attached Reaction Mitigation Area boundary determination, submitted on October 9, 2026, and in accordance with Condition No. 9(b) of the Stipulated Order, the extent of the data-determined Reaction Mitigation Area (dashed magenta line) was

adjusted to encompass Cells 1/2A, 2B/3, 4, and Module 2B/3/4 P2, as specified in the SOFA (solid black line), and Grid Nos. 37, 38, 39, 41, 53, 76, 77, 79, 81, 82, 145 through 149, and 155. Grid Nos. 39, 155, and 169 were included as contiguous surface grids and Grid Nos. 33, 34, 163, and 170 were excluded as contiguous surface grids.

As liquid levels continue to decrease due to the restarting and installation of multiple Lorentz Electric and Pneumatic Pumps which has increased overall liquid removal, we have seen the percentages of Permanent Gases, Carbon Monoxide, and Hydrogen and temperatures change as these gases move towards the extraction wells for removal. This continues to be demonstrated by the multiscale well graphics included in **Attachment D**, which includes graphics on permanent gases, temperature, and other trends over a twelve (12)-month period. Note that these graphs were created using standard landfill gas monitoring equipment and the results do not contain laboratory data. SCS has also included separate Hydrogen and Carbon Monoxide graphs using laboratory results for your use and review for each well.

Additionally, the installation of larger diameter piping has improved the collection of additional gases throughout the Landfill. Since March 2025, the flow rates of landfill gas being combusted by the abatement devices have ranged from 13,500 cfm to 18,500 cfm. During September 2026, the overall gas extraction from the Landfill was approximately 688,651,200 cubic feet. September's daily landfill gas extraction rate was slightly lower than August due to the gas collection and control system construction activities (i.e. header reconfigurations and system modifications associated with the West Slope project, an unplanned shutdown of the Zeeco #7 thermal oxidizer to accommodate electrical work on overhead power lines and to remove and regrade the thermal oxidizer stack area to address settlement, and a shutdown of the Parnel thermal oxidizer for an extended period of time to install a new liquid handling sump which resulted in additional downtimes of the eight (8) abatement devices (three (3) flares and five (5) thermal oxidizers). Future increases of this extraction rate may occur, however, the Landfill may be approaching the theoretical maximum gas generation rates. SCS will continue to maximize gas and heat extraction as the collection systems continue to expand and as the gas composition of the wells in the Reaction Mitigation Area changes as more vacuum, liquid removal, and resulting movement of gas allows more reaction and normal landfill gas to be extracted.

Chiquita will continue to evaluate the data in future monthly reports as additional data is collected.

Milestone 5 Compliance Items

This report includes in **Attachment D** individual maps overlayed with the following data for September 2026 in an easily understood format, in accordance with Milestone 5 of the Compliance Order:

- Defined Reaction Mitigation Area;
- Expansion of Reaction Mitigation Area, if any;
- Weekly TMP data; and

- LFG data including, but not limited to, CH4, CO2, O2, Temperature, CO, and H2 data.

Milestone 5 also requires "settlement with heat maps," but as discussed earlier in this report and in accordance with LEA correspondence dated November 27 and December 3, 2024, this requirement is satisfied by Chiquita's submittal of its monthly isopach maps to the LEA, which was done on October 13, 2026. For the LEA's convenience, the September 2026 isopach map is included herein as **Attachment F**.

The signatories below are a licensed professional, the site project manager, and a Regional Manager VP of SCS Engineers.

Sincerely,

Rachelle Huber
Project Manager
SCS Engineers

Arthur E Jones Jr
Vice President
SCS Engineers

Jenny Kim, P.E.
Project Manager
SCS Engineers

Attachments:

Attachment A – Laboratory Analysis and LFG Extraction Well Instrument and Temperature Data
Attachment B – Down Well Temperatures and List of Wells for Monitoring
Attachment C – Item 7 - Well Location Map
Attachment D – Milestone 5 Compliance Data
Attachment E – October 9, 2026 Reaction Mitigation Area Report
Attachment F – September 2026 Isopach Map

Electronic Data of Laboratory Results and Extraction Well data are in Excel format, with additional PDFs for gas well data.

cc: John Perkey, Chiquita Canyon

Kevin Green, Chiquita Canyon
William Haley, Chiquita Canyon
Dylan Smith, Chiquita Canyon
Sarah Phillips, Chiquita Canyon
Tessa Lenz, Chiquita Canyon
Pat Sullivan, SCS Engineers
Liza Frias, Los Angeles County Department of Public Health
Nichole Quick, M.D., Los Angeles County Department of Public Health
Beverly Tway, Los Angeles County LEA
Eric Morofuji, Los Angeles County LEA
Renee Jensen, LEA Counsel
Blaine McPhillips, Senior Deputy County Counsel
Emiko Thompson, Los Angeles County Department of Public Works
Alex Garcia, Los Angeles County Department of Regional Planning
Phillip Chen, Los Angeles County Department of Regional Planning
Steven Jareb, Los Angeles County Department of Regional Planning
Wes Mindermann, CalRecycle
Todd Thalhamer, CalRecycle
Emel Wadhwani, CalRecycle
Lor Xiong, CalRecycle
Jeff Linberg, California Air Recourses Board
Nancy Fletcher, California Air Recourses Board
Jack Cheng, South Coast Air Quality Management Board
Larry Israel, South Coast Air Quality Management Board
Enrique Casas, Los Angeles Regional Water Quality Control Board
Joshua Wirtschafter, United States Environmental Protection Agency
Laura Friedli, United States Environmental Protection Agency
Tyler Holybee, United States Environmental Protection Agency
Mark Anthony Relon, United States Environmental Protection Agency
Gregory Schaffer, Department of Toxic Substances Control
Natasha DiPietro, Department of Toxic Substances Control
Gregory Gentile, Department of Toxic Substances Control

Attachment A

Laboratory Analysis

And

LFG Extraction Well Instrument and Temperature Data

SGS

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C,
ASTM D1946, RSK-175

TX Cert T104704450-14-6
EPA Methods TO14A, TO15

ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

September 21, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T090107-01/10

Enclosed are the results for sample(s) received 9/1/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Zain Khan, Art Jones and Ali Ferrara on 9/17/26.

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Annika Sotelo-Sanchez
Lab Manager
Annika.sotelo-sanchez@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐ No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐ No ☐
Other:				Level 4	☐	Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:	
Bill to:	
	07FSAccountspayable@scsengineers.com
	3900 Kilroy Airport Way, Suite 300
	Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T090107-01	CV-2348	09/01/26	6:50AM	1L	Gas	N	X	X	X			
-02	CV-2347	09/01/26	6:55AM	1L	Gas	N	X	X	X			
-03	CV-2346	09/01/26	7:05AM	1L	Gas	N	X	X	X			
-04	CV-2345	09/01/26	7:10AM	1L	Gas	N	X	X	X			
-05	CV-2344	09/01/26	7:15AM	1L	Gas	N	X	X	X			
-06	CV-2350	09/01/26	7:20AM	2-1L	Gas	N	X	X	X	X		
-07	CV-108-52	09/01/26	7:25AM	2-1L	Gas	N	X	X	X	X		
-08	CV-1532A	09/01/26	7:30AM	2-1L	Gas	N	X	X	X	X		
-09	CV-1902A	09/01/26	7:35AM	2-1L	Gas	N	X	X	X	X		
-10	CV-24143	09/01/26	7:40AM	2-1L	Gas	N	X	X	X	X		

AUTHORIZATION TO PERFORM WORK	COMPANY SCS	DATE/TIME 9-1-26 7:58a	
SAMPLED BY	COMPANY SCS	DATE/TIME 9-1-26 7:58a	
RELINQUISHED BY	DATE/TIME 9-1-26 7:58a	RECEIVED BY Antonio Ambriz	DATE/TIME 9/1/26 7:59am
RELINQUISHED BY Antonio Ambriz	DATE/TIME 9/1/26 10:38am	RECEIVED BY John C	DATE/TIME 9/1/26 1038
RELINQUISHED BY John C	DATE/TIME 9/1/26 1150	RECEIVED BY	DATE/TIME 9/1/26 1158

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/01/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T090107-06		T090107-07		T090107-08		T090107-09	
Client Sample I.D.:	CV-2350		CV-108-52		CV-1532A		CV-1902A	
Date/Time Sampled:	9/1/26 7:20		9/1/26 7:25		9/1/26 7:30		9/1/26 7:35	
Date/Time Analyzed:	9/1/26 16:06		9/1/26 16:43		9/1/26 17:20		9/1/26 17:58	
QC Batch No.:	260901MS2A1		260901MS2A1		260901MS2A1		260901MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	2,000		2,000		7,000		5,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	2,000	ND	2,000	ND	7,000	ND	5,000
Chloromethane	ND	2,000	ND	2,000	17,000	7,000	ND	5,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	2,000	ND	2,000	ND	7,000	ND	5,000
Vinyl Chloride	ND	2,000	ND	2,000	ND	7,000	ND	5,000
Bromomethane	ND	2,000	ND	2,000	ND	7,000	ND	5,000
Chloroethane	2,600	2,000	ND	2,000	ND	7,000	ND	5,000
Trichlorofluoromethane (11)	ND	2,000	ND	2,000	ND	7,000	ND	5,000
1,1-Dichloroethene	ND	2,000	ND	2,000	ND	7,000	ND	5,000
Carbon Disulfide	ND	2,000	ND	2,000	ND	7,000	ND	5,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	2,000	ND	2,000	ND	7,000	ND	5,000
Acetone	240,000	2,000	160,000	2,000	500,000	7,000	310,000	5,000
Methylene Chloride	ND	2,000	ND	2,000	ND	7,000	ND	5,000
t-1,2-Dichloroethene	ND	2,000	ND	2,000	ND	7,000	ND	5,000
1,1-Dichloroethane	ND	2,000	ND	2,000	ND	7,000	ND	5,000
Vinyl Acetate	ND	2,000	ND	2,000	ND	7,000	ND	5,000
c-1,2-Dichloroethene	ND	2,000	ND	2,000	ND	7,000	ND	5,000
2-Butanone	220,000	4,000	130,000	4,000	330,000	14,000	170,000	10,000
t-Butyl Methyl Ether (MTBE)	ND	2,000	ND	2,000	ND	7,000	ND	5,000
Chloroform	ND	2,000	ND	2,000	ND	7,000	ND	5,000
1,1,1-Trichloroethane	ND	2,000	ND	2,000	ND	7,000	ND	5,000
Carbon Tetrachloride	ND	2,000	ND	2,000	ND	7,000	ND	5,000
Benzene	170,000	2,000	110,000	2,000	170,000	7,000	33,000	5,000
1,2-Dichloroethane	ND	2,000	ND	2,000	ND	7,000	ND	5,000
Trichloroethene	ND	2,000	ND	2,000	ND	7,000	ND	5,000
1,2-Dichloropropane	ND	2,000	ND	2,000	ND	7,000	ND	5,000
Bromodichloromethane	ND	2,000	ND	2,000	ND	7,000	ND	5,000
c-1,3-Dichloropropene	ND	2,000	ND	2,000	ND	7,000	ND	5,000
4-Methyl-2-Pentanone	3,800	2,000	3,000	2,000	ND	7,000	ND	5,000
Toluene	6,100	2,000	4,900	2,000	ND	7,000	ND	5,000
t-1,3-Dichloropropene	ND	2,000	ND	2,000	ND	7,000	ND	5,000
1,1,2-Trichloroethane	ND	2,000	ND	2,000	ND	7,000	ND	5,000
Tetrachloroethene	ND	2,000	ND	2,000	ND	7,000	ND	5,000
2-Hexanone	ND	2,000	ND	2,000	ND	7,000	ND	5,000
Dibromochloromethane	ND	2,000	ND	2,000	ND	7,000	ND	5,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/01/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T090107-06		T090107-07		T090107-08		T090107-09	
Client Sample I.D.:	CV-2350		CV-108-52		CV-1532A		CV-1902A	
Date/Time Sampled:	9/1/26 7:20		9/1/26 7:25		9/1/26 7:30		9/1/26 7:35	
Date/Time Analyzed:	9/1/26 16:06		9/1/26 16:43		9/1/26 17:20		9/1/26 17:58	
QC Batch No.:	260901MS2A1		260901MS2A1		260901MS2A1		260901MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	2,000		2,000		7,000		5,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	2,000	ND	2,000	ND	7,000	ND	5,000
Chlorobenzene	ND	2,000	ND	2,000	ND	7,000	ND	5,000
Ethylbenzene	ND	2,000	ND	2,000	ND	7,000	ND	5,000
p,&m-Xylene	ND	2,000	ND	2,000	ND	7,000	ND	5,000
o-Xylene	ND	2,000	ND	2,000	ND	7,000	ND	5,000
Styrene	ND	2,000	ND	2,000	ND	7,000	ND	5,000
Bromoform	ND	2,000	ND	2,000	ND	7,000	ND	5,000
1,1,2,2-Tetrachloroethane	ND	2,000	ND	2,000	ND	7,000	ND	5,000
Benzyl Chloride	ND Q	2,000	ND Q	2,000	ND Q	7,000	ND Q	5,000
4-Ethyl Toluene	ND	2,000	ND	2,000	ND	7,000	ND	5,000
1,3,5-Trimethylbenzene	ND	2,000	ND	2,000	ND	7,000	ND	5,000
1,2,4-Trimethylbenzene	ND	2,000	ND	2,000	ND	7,000	ND	5,000
1,3-Dichlorobenzene	ND	2,000	ND	2,000	ND	7,000	ND	5,000
1,4-Dichlorobenzene	ND	2,000	ND	2,000	ND	7,000	ND	5,000
1,2-Dichlorobenzene	ND	2,000	ND	2,000	ND	7,000	ND	5,000
1,2,4-Trichlorobenzene	ND	2,000	ND	2,000	ND	7,000	ND	5,000
Hexachlorobutadiene	ND	2,000	ND	2,000	ND	7,000	ND	5,000
1,3-Butadiene	ND Q	10,000	ND Q	10,000	ND Q	35,000	ND Q	25,000
Isopropanol	120,000	10,000	120,000	10,000	120,000	35,000	140,000	25,000
n-Hexane	ND	10,000	ND	10,000	ND	35,000	ND	25,000
Ethyl Acetate	22,000	10,000	15,000	10,000	41,000	35,000	ND	25,000
Tetrahydrofuran	400,000	10,000	150,000	10,000	220,000	35,000	110,000	25,000
Cyclohexane	ND	10,000	ND	10,000	ND	35,000	ND	25,000
Heptane	11,000	10,000	ND	10,000	ND	35,000	ND	25,000
1,4-Dioxane	ND	10,000	ND	10,000	ND	35,000	ND	25,000

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited low recovery in the continuing calibration verification indicating possible low bias

Reviewed/Approved By: _____ for **Date** 9/10/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/01/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T090107-10							
Client Sample I.D.:	CV-24143							
Date/Time Sampled:	9/1/26 7:40							
Date/Time Analyzed:	9/1/26 18:36							
QC Batch No.:	260901MS2A1							
Analyst Initials:	VM/GD							
Dilution Factor:	8,000							
ANALYTE	**Result ppbv**	**RL ppbv**						
Dichlorodifluoromethane (12)	ND	8,000						
Chloromethane	ND	8,000						
1,2-Cl-1,1,2,2-F ethane (114)	ND	8,000						
Vinyl Chloride	ND	8,000						
Bromomethane	ND	8,000						
Chloroethane	ND	8,000						
Trichlorofluoromethane (11)	ND	8,000						
1,1-Dichloroethene	ND	8,000						
Carbon Disulfide	ND	8,000						
1,1,2-Cl 1,2,2-F ethane (113)	ND	8,000						
Acetone	510,000	8,000						
Methylene Chloride	ND	8,000						
t-1,2-Dichloroethene	ND	8,000						
1,1-Dichloroethane	ND	8,000						
Vinyl Acetate	ND	8,000						
c-1,2-Dichloroethene	ND	8,000						
2-Butanone	290,000	16,000						
t-Butyl Methyl Ether (MTBE)	ND	8,000						
Chloroform	ND	8,000						
1,1,1-Trichloroethane	ND	8,000						
Carbon Tetrachloride	ND	8,000						
Benzene	54,000	8,000						
1,2-Dichloroethane	ND	8,000						
Trichloroethene	ND	8,000						
1,2-Dichloropropane	ND	8,000						
Bromodichloromethane	ND	8,000						
c-1,3-Dichloropropene	ND	8,000						
4-Methyl-2-Pentanone	ND	8,000						
Toluene	ND	8,000						
t-1,3-Dichloropropene	ND	8,000						
1,1,2-Trichloroethane	ND	8,000						
Tetrachloroethene	ND	8,000						
2-Hexanone	ND	8,000						
Dibromochloromethane	ND	8,000						

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/01/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T090107-10							
Client Sample I.D.:	CV-24143							
Date/Time Sampled:	9/1/26 7:40							
Date/Time Analyzed:	9/1/26 18:36							
QC Batch No.:	260901MS2A1							
Analyst Initials:	VM/GD							
Dilution Factor:	8,000							
ANALYTE	**Result ppbv**	**RL ppbv**						
1,2-Dibromoethane	ND	8,000						
Chlorobenzene	ND	8,000						
Ethylbenzene	ND	8,000						
p,&m-Xylene	ND	8,000						
o-Xylene	ND	8,000						
Styrene	ND	8,000						
Bromoform	ND	8,000						
1,1,2,2-Tetrachloroethane	ND	8,000						
Benzyl Chloride	ND Q	8,000						
4-Ethyl Toluene	ND	8,000						
1,3,5-Trimethylbenzene	ND	8,000						
1,2,4-Trimethylbenzene	ND	8,000						
1,3-Dichlorobenzene	ND	8,000						
1,4-Dichlorobenzene	ND	8,000						
1,2-Dichlorobenzene	ND	8,000						
1,2,4-Trichlorobenzene	ND	8,000						
Hexachlorobutadiene	ND	8,000						
1,3-Butadiene	ND Q	40,000						
Isopropanol	140,000	40,000						
n-Hexane	ND	40,000						
Ethyl Acetate	ND	40,000						
Tetrahydrofuran	200,000	40,000						
Cyclohexane	ND	40,000						
Heptane	ND	40,000						
1,4-Dioxane	ND	40,000						

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited low recovery in the continuing calibration verification indicating possible low bias

Reviewed/Approved By: _____ **Date** 9/10/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/01/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK							
Client Sample I.D.:	-							
Date/Time Sampled:	-							
Date/Time Analyzed:	9/1/26 6:04							
QC Batch No.:	260901MS2A1							
Analyst Initials:	VM/GD							
Dilution Factor:	0.20							

ANALYTE	Result ppbv	RL ppbv						
Dichlorodifluoromethane (12)	ND	0.20						
Chloromethane	ND	0.20						
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20						
Vinyl Chloride	ND	0.20						
Bromomethane	ND	0.20						
Chloroethane	ND	0.20						
Trichlorofluoromethane (11)	ND	0.20						
1,1-Dichloroethene	ND	0.20						
Carbon Disulfide	ND	0.20						
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20						
Acetone	0.30	0.20						
Methylene Chloride	ND	0.20						
t-1,2-Dichloroethene	ND	0.20						
1,1-Dichloroethane	ND	0.20						
Vinyl Acetate	ND	0.20						
c-1,2-Dichloroethene	ND	0.20						
2-Butanone	ND	0.40						
t-Butyl Methyl Ether (MTBE)	ND	0.20						
Chloroform	ND	0.20						
1,1,1-Trichloroethane	ND	0.20						
Carbon Tetrachloride	ND	0.20						
Benzene	ND	0.20						
1,2-Dichloroethane	ND	0.20						
Trichloroethene	ND	0.20						
1,2-Dichloropropane	ND	0.20						
Bromodichloromethane	ND	0.20						
c-1,3-Dichloropropene	ND	0.20						
4-Methyl-2-Pentanone	ND	0.20						
Toluene	ND	0.20						
t-1,3-Dichloropropene	ND	0.20						
1,1,2-Trichloroethane	ND	0.20						
Tetrachloroethene	ND	0.20						
2-Hexanone	ND	0.20						
Dibromochloromethane	ND	0.20						

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/01/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK
Client Sample I.D.:	-
Date/Time Sampled:	-
Date/Time Analyzed:	9/1/26 6:04
QC Batch No.:	260901MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	0.20
Chlorobenzene	ND	0.20
Ethylbenzene	ND	0.20
p,&m-Xylene	ND	0.20
o-Xylene	ND	0.20
Styrene	ND	0.20
Bromoform	ND	0.20
1,1,2,2-Tetrachloroethane	ND	0.20
Benzyl Chloride	ND Q	0.20
4-Ethyl Toluene	ND	0.20
1,3,5-Trimethylbenzene	ND	0.20
1,2,4-Trimethylbenzene	ND	0.20
1,3-Dichlorobenzene	ND	0.20
1,4-Dichlorobenzene	ND	0.20
1,2-Dichlorobenzene	ND	0.20
1,2,4-Trichlorobenzene	ND	0.20
Hexachlorobutadiene	ND	0.20
1,3-Butadiene	ND Q	1.0
Isopropanol	ND	1.0
n-Hexane	ND	1.0
Ethyl Acetate	ND	1.0
Tetrahydrofuran	ND	1.0
Cyclohexane	ND	1.0
Heptane	ND	1.0
1,4-Dioxane	ND	1.0

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited low recovery in the continuing calibration verification indicating possible low bias

Reviewed/Approved By: _____ Date 9/10/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 260901MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	9/1/26 6:04			9/1/26 4:41		9/1/26 5:23					
Analyst Initials:	VM/GD			VM/GD		VM/GD					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	0.20	10	11.1	111	11.0	110	1.7	70	130	30
Methylene Chloride	ND	0.20	10	9.84	98	9.38	94	4.8	70	130	30
Trichloroethene	ND	0.20	10	9.93	99	9.94	99	0.1	70	130	30
Toluene	ND	0.20	10	9.34	93	9.42	94	0.8	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	8.92	89	9.03	90	1.3	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date:** 9/10/26

Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/01/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T090107-01		T090107-02		T090107-03		T090107-04	
Client Sample I.D.:	CV-2348		CV-2347		CV-2346		CV-2345	
Date/Time Sampled:	9/1/26 6:50		9/1/26 6:55		9/1/26 7:05		9/1/26 7:10	
Date/Time Analyzed:	9/1/26 19:33		9/1/26 19:48		9/1/26 20:03		9/1/26 20:17	
QC Batch No.:	260901GC8A2		260901GC8A2		260901GC8A2		260901GC8A2	
Analyst Initials:	AS		AS		AS		AS	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	380	10	610	10	540	10	450	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 9/17/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/01/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T090107-05		T090107-06		T090107-07		T090107-08	
Client Sample I.D.:	CV-2344		CV-2350		CV-108-52		CV-1532A	
Date/Time Sampled:	9/1/26 7:15		9/1/26 7:20		9/1/26 7:25		9/1/26 7:30	
Date/Time Analyzed:	9/1/26 20:32		9/1/26 20:46		9/1/26 21:01		9/1/26 21:15	
QC Batch No.:	260901GC8A2		260901GC8A2		260901GC8A2		260901GC8A2	
Analyst Initials:	AS		AS		AS		AS	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	1,500	10	3,400	10	450	10	1,400	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 9/17/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/01/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T090107-09		T090107-10					
Client Sample I.D.:	CV-1902A		CV-24143					
Date/Time Sampled:	9/1/26 7:35		9/1/26 7:40					
Date/Time Analyzed:	9/1/26 21:30		9/1/26 21:44					
QC Batch No.:	260901GC8A2		260901GC8A2					
Analyst Initials:	AS		AS					
Dilution Factor:	1.0		1.0					
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv				
Carbon Monoxide	310	10	660	10				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 9/17/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260901GC8A2
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	9/1/26 19:19			9/1/26 18:21		9/1/26 18:35					
Analyst Initials:	AS			AS		AS					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,010	100	1,000	99	0.6	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 9/17/26

Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/01/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090107-01			T090107-02			T090107-03			T090107-04		
Client Sample I.D.:	CV-2348			CV-2347			CV-2346			CV-2345		
Date/Time Sampled:	9/1/26 6:50			9/1/26 6:55			9/1/26 7:05			9/1/26 7:10		
Date/Time Analyzed:	9/1/26 19:33			9/1/26 19:48			9/1/26 20:03			9/1/26 20:17		
QC Batch No.:	260901GC8A2			260901GC8A2			260901GC8A2			260901GC8A2		
Analyst Initials:	AS			AS			AS			AS		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	2.8	1.0	0.059	4.6	1.0	0.059	5.3	1.0	0.059	3.3	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 9/17/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/01/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090107-05			T090107-06			T090107-07			T090107-08		
Client Sample I.D.:	CV-2344			CV-2350			CV-108-52			CV-1532A		
Date/Time Sampled:	9/1/26 7:15			9/1/26 7:20			9/1/26 7:25			9/1/26 7:30		
Date/Time Analyzed:	9/1/26 20:32			9/1/26 20:46			9/1/26 21:01			9/1/26 21:15		
QC Batch No.:	260901GC8A2			260901GC8A2			260901GC8A2			260901GC8A2		
Analyst Initials:	AS			AS			AS			AS		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	11	1.0	0.059	17	1.0	0.059	13	1.0	0.059	23	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 9/17/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/01/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090107-09			T090107-10								
Client Sample I.D.:	CV-1902A			CV-24143								
Date/Time Sampled:	9/1/26 7:35			9/1/26 7:40								
Date/Time Analyzed:	9/1/26 21:30			9/1/26 21:44								
QC Batch No.:	260901GC8A2			260901GC8A2								
Analyst Initials:	AS			AS								
Dilution Factor:	1.0			1.0								
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v						
Hydrogen	4.3	1.0	0.059	9.4	1.0	0.059						

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____
Annika Sotelo-Sanchez
Lab Manager

Date 9/11/26

The cover letter is an integral part of this analytical report

QC Batch No: 260901GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	9/1/26 19:19				9/1/26 18:21		9/1/26 18:35					
Analyst Initials:	AS				AS		AS					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	4.32	87	4.13	83	4.5	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 9/17/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/01/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090107-01		T090107-02		T090107-03		T090107-04	
Client Sample I.D.:	CV-2348		CV-2347		CV-2346		CV-2345	
Date/Time Sampled:	9/1/26 6:50		9/1/26 6:55		9/1/26 7:05		9/1/26 7:10	
Date/Time Analyzed:	9/1/26 19:33		9/1/26 19:48		9/1/26 20:03		9/1/26 20:17	
QC Batch No.:	260901GC8A2		260901GC8A2		260901GC8A2		260901GC8A2	
Analyst Initials:	AS		AS		AS		AS	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	44	0.010	45	0.010	39	0.010	62	0.010
Oxygen/Argon	2.6	0.50	1.4	0.50	7.1	0.50	1.4	0.50
Nitrogen	31	1.0	34	1.0	37	1.0	14	1.0
Methane	19	0.0010	15	0.0010	11	0.0010	19	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 9/7/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/01/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090107-05		T090107-06		T090107-07		T090107-08	
Client Sample I.D.:	CV-2344		CV-2350		CV-108-52		CV-1532A	
Date/Time Sampled:	9/1/26 7:15		9/1/26 7:20		9/1/26 7:25		9/1/26 7:30	
Date/Time Analyzed:	9/1/26 20:32		9/1/26 20:46		9/1/26 21:01		9/1/26 21:15	
QC Batch No.:	260901GC8A2		260901GC8A2		260901GC8A2		260901GC8A2	
Analyst Initials:	AS		AS		AS		AS	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	70	0.010	72	0.010	70	0.010	72	0.010
Oxygen/Argon	0.83	0.50	1.3	0.50	0.59	0.50	0.55	0.50
Nitrogen	7.6	1.0	4.9	1.0	2.2	1.0	2.1	1.0
Methane	10	0.0010	4.1	0.0010	13	0.0010	1.3	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 9/17/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/01/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090107-09		T090107-10					
Client Sample I.D.:	CV-1902A		CV-24143					
Date/Time Sampled:	9/1/26 7:35		9/1/26 7:40					
Date/Time Analyzed:	9/1/26 21:30		9/1/26 21:44					
QC Batch No.:	260901GC8A2		260901GC8A2					
Analyst Initials:	AS		AS					
Dilution Factor:	1.0		1.0					
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**				
Carbon Dioxide	16	0.010	36	0.010				
Oxygen/Argon	15	0.50	11	0.50				
Nitrogen	61	1.0	41	1.0				
Methane	3.1	0.0010	0.87	0.0010				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 9/17/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260901GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	9/1/26 19:19			9/1/26 18:21		9/1/26 18:35					
Analyst Initials:	AS			AS		AS					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	9.22	92	9.26	92	0.4	70	130	30
Oxygen/Argon	ND	0.50	15	15.5	103	15.5	103	0.1	70	130	30
Nitrogen	ND	1.0	70	73.5	105	73.7	106	0.3	70	130	30
Methane	ND	0.0010	0.10	0.112	111	0.111	110	0.4	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 9/17/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

SGS

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175
TX Cert T104704450-14-6
EPA Methods TO14A, TO15
ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

September 22, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T090207-01/10

Enclosed are the results for sample(s) received 9/2/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were received in Mylar bags. Quadratic regression calibration was required for ethyl acetate, tetrahydrofuran, cyclohexane, and 1,4-dioxane.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Zain Khan, Art Jones and Ali Ferrara on 9/21/26.

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Annika Sotelo-Sanchez
Lab Manager
Annika.sotelo-sanchez@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐ No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐ No ☐
Other:				Level 4	☐	Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:	
Bill to:	07FSAccountspayable@scsengineers.com
	3900 Kilroy Airport Way, Suite 300
	Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T090207-01	CV-24141	09/02/26	7:10AM	1L	Gas	N	X	X	X			
-02	CV-2351	09/02/26	7:15AM	2-1L	Gas	N	X	X	X	X		
-03	CV-2352	09/02/26	7:20AM	1L	Gas	N	X	X	X			
-04	CV-24140	09/02/26	7:25AM	2-1L	Gas	N	X	X	X	X		
-05	CV-24139	09/02/26	7:30AM	2-1L	Gas	N	X	X	X	X		
-06	CV-24138	09/02/26	7:35AM	2-1L	Gas	N	X	X	X	X		
-07	CV-24142	09/02/26	7:40AM	2-1L	Gas	N	X	X	X	X		
-08	CV-2354	09/02/26	7:45AM	1L	Gas	N	X	X	X			
-09	CV-2349	09/02/26	7:50AM	1L	Gas	N	X	X	X			
-10	CV-24144	09/02/26	8:00AM	1L	Gas	N	X					

AUTHORIZATION TO PERFORM WORK	COMPANY SCS	DATE/TIME 9/2/26 0700	
SAMPLED BY Emmanuel Melena	COMPANY SCS	DATE/TIME 9-2-26 0700	
RELINQUISHED BY	DATE/TIME 9/2/26	RECEIVED BY	DATE/TIME 9-2-26
RELINQUISHED BY	DATE/TIME 9/2/26 12:5	RECEIVED BY	DATE/TIME 9/2/26 1251
RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/02/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T090207-02		T090207-04		T090207-05		T090207-06	
Client Sample I.D.:	CV-24141		CV-24140		CV-24139		CV-24138	
Date/Time Sampled:	9/2/26 7:10		9/2/26 7:25		9/2/26 7:30		9/2/26 7:35	
Date/Time Analyzed:	9/2/26 18:29		9/2/26 15:59		9/2/26 16:36		9/2/26 17:14	
QC Batch No.:	260902MS2A1		260902MS2A1		260902MS2A1		260902MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	1,000		10,000		5,000		10,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	1,000	ND	10,000	ND	5,000	ND	10,000
Chloromethane	ND	1,000	ND	10,000	ND	5,000	ND	10,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	1,000	ND	10,000	ND	5,000	ND	10,000
Vinyl Chloride	ND	1,000	ND	10,000	ND	5,000	ND	10,000
Bromomethane	ND	1,000	ND	10,000	ND	5,000	ND	10,000
Chloroethane	ND	1,000	ND	10,000	ND	5,000	ND	10,000
Trichlorofluoromethane (11)	ND	1,000	ND	10,000	ND	5,000	ND	10,000
1,1-Dichloroethene	ND	1,000	ND	10,000	ND	5,000	ND	10,000
Carbon Disulfide	ND	1,000	ND	10,000	ND	5,000	ND	10,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	1,000	ND	10,000	ND	5,000	ND	10,000
Acetone	76,000	1,000	780,000	10,000	490,000	5,000	700,000	10,000
Methylene Chloride	ND	1,000	ND	10,000	ND	5,000	11,000	10,000
t-1,2-Dichloroethene	ND	1,000	ND	10,000	ND	5,000	ND	10,000
1,1-Dichloroethane	ND	1,000	ND	10,000	ND	5,000	ND	10,000
Vinyl Acetate	ND	1,000	ND	10,000	ND	5,000	ND	10,000
c-1,2-Dichloroethene	ND	1,000	ND	10,000	ND	5,000	ND	10,000
2-Butanone	41,000	2,000	420,000	20,000	350,000	10,000	540,000	20,000
t-Butyl Methyl Ether (MTBE)	ND	1,000	ND	10,000	ND	5,000	ND	10,000
Chloroform	ND	1,000	ND	10,000	ND	5,000	ND	10,000
1,1,1-Trichloroethane	ND	1,000	ND	10,000	ND	5,000	ND	10,000
Carbon Tetrachloride	ND	1,000	ND	10,000	ND	5,000	ND	10,000
Benzene	9,700	1,000	72,000	10,000	62,000	5,000	52,000	10,000
1,2-Dichloroethane	ND	1,000	ND	10,000	ND	5,000	ND	10,000
Trichloroethene	ND	1,000	ND	10,000	ND	5,000	ND	10,000
1,2-Dichloropropane	ND	1,000	ND	10,000	ND	5,000	ND	10,000
Bromodichloromethane	ND	1,000	ND	10,000	ND	5,000	ND	10,000
c-1,3-Dichloropropene	ND	1,000	ND	10,000	ND	5,000	ND	10,000
4-Methyl-2-Pentanone	ND	1,000	ND	10,000	ND	5,000	ND	10,000
Toluene	ND	1,000	ND	10,000	ND	5,000	ND	10,000
t-1,3-Dichloropropene	ND	1,000	ND	10,000	ND	5,000	ND	10,000
1,1,2-Trichloroethane	ND	1,000	ND	10,000	ND	5,000	ND	10,000
Tetrachloroethene	ND	1,000	ND	10,000	ND	5,000	ND	10,000
2-Hexanone	ND	1,000	ND	10,000	ND	5,000	ND	10,000
Dibromochloromethane	ND	1,000	ND	10,000	ND	5,000	ND	10,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/02/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T090207-02		T090207-04		T090207-05		T090207-06	
Client Sample I.D.:	CV-24141		CV-24140		CV-24139		CV-24138	
Date/Time Sampled:	9/2/26 7:10		9/2/26 7:25		9/2/26 7:30		9/2/26 7:35	
Date/Time Analyzed:	9/2/26 18:29		9/2/26 15:59		9/2/26 16:36		9/2/26 17:14	
QC Batch No.:	260902MS2A1		260902MS2A1		260902MS2A1		260902MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	1,000		10,000		5,000		10,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	1,000	ND	10,000	ND	5,000	ND	10,000
Chlorobenzene	ND	1,000	ND	10,000	ND	5,000	ND	10,000
Ethylbenzene	ND	1,000	ND	10,000	ND	5,000	ND	10,000
p,&m-Xylene	ND	1,000	ND	10,000	ND	5,000	ND	10,000
o-Xylene	ND	1,000	ND	10,000	ND	5,000	ND	10,000
Styrene	ND	1,000	ND	10,000	ND	5,000	ND	10,000
Bromoform	ND	1,000	ND	10,000	ND	5,000	ND	10,000
1,1,2,2-Tetrachloroethane	ND	1,000	ND	10,000	ND	5,000	ND	10,000
Benzyl Chloride	ND Q	1,000	ND Q	10,000	ND Q	5,000	ND Q	10,000
4-Ethyl Toluene	ND	1,000	ND	10,000	ND	5,000	ND	10,000
1,3,5-Trimethylbenzene	ND	1,000	ND	10,000	ND	5,000	ND	10,000
1,2,4-Trimethylbenzene	ND	1,000	ND	10,000	ND	5,000	ND	10,000
1,3-Dichlorobenzene	ND	1,000	ND	10,000	ND	5,000	ND	10,000
1,4-Dichlorobenzene	ND	1,000	ND	10,000	ND	5,000	ND	10,000
1,2-Dichlorobenzene	ND	1,000	ND	10,000	ND	5,000	ND	10,000
1,2,4-Trichlorobenzene	ND	1,000	ND	10,000	ND	5,000	ND	10,000
Hexachlorobutadiene	ND	1,000	ND	10,000	ND	5,000	ND	10,000
1,3-Butadiene	ND	5,000	ND	50,000	ND	25,000	ND	50,000
Isopropanol	31,000	5,000	55,000	50,000	53,000	25,000	160,000	50,000
n-Hexane	ND	5,000	ND	50,000	ND	25,000	ND	50,000
Ethyl Acetate	ND	5,000	ND	50,000	ND	25,000	ND	50,000
Tetrahydrofuran	31,000	5,000	280,000	50,000	230,000	25,000	320,000	50,000
Cyclohexane	ND	5,000	ND	50,000	ND	25,000	ND	50,000
Heptane	ND	5,000	ND	50,000	ND	25,000	ND	50,000
1,4-Dioxane	ND	5,000	ND	50,000	ND	25,000	ND	50,000

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited low recovery in the continuing calibration verification indicating possible low bias

Reviewed/Approved By: _____ **Date** 9/18/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/02/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T090207-07
Client Sample I.D.:	CV-24142
Date/Time Sampled:	9/2/26 7:40
Date/Time Analyzed:	9/2/26 17:51
QC Batch No.:	260902MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	7,000

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	7,000
Chloromethane	ND	7,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	7,000
Vinyl Chloride	ND	7,000
Bromomethane	ND	7,000
Chloroethane	ND	7,000
Trichlorofluoromethane (11)	ND	7,000
1,1-Dichloroethene	ND	7,000
Carbon Disulfide	ND	7,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	7,000
Acetone	470,000	7,000
Methylene Chloride	ND	7,000
t-1,2-Dichloroethene	ND	7,000
1,1-Dichloroethane	ND	7,000
Vinyl Acetate	ND	7,000
c-1,2-Dichloroethene	ND	7,000
2-Butanone	260,000	14,000
t-Butyl Methyl Ether (MTBE)	ND	7,000
Chloroform	ND	7,000
1,1,1-Trichloroethane	ND	7,000
Carbon Tetrachloride	ND	7,000
Benzene	47,000	7,000
1,2-Dichloroethane	ND	7,000
Trichloroethene	ND	7,000
1,2-Dichloropropane	ND	7,000
Bromodichloromethane	ND	7,000
c-1,3-Dichloropropene	ND	7,000
4-Methyl-2-Pentanone	ND	7,000
Toluene	ND	7,000
t-1,3-Dichloropropene	ND	7,000
1,1,2-Trichloroethane	ND	7,000
Tetrachloroethene	ND	7,000
2-Hexanone	ND	7,000
Dibromochloromethane	ND	7,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/02/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T090207-07
Client Sample I.D.:	CV-24142
Date/Time Sampled:	9/2/26 7:40
Date/Time Analyzed:	9/2/26 17:51
QC Batch No.:	260902MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	7,000

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	7,000
Chlorobenzene	ND	7,000
Ethylbenzene	ND	7,000
p,&m-Xylene	ND	7,000
o-Xylene	ND	7,000
Styrene	ND	7,000
Bromoform	ND	7,000
1,1,2,2-Tetrachloroethane	ND	7,000
Benzyl Chloride	ND Q	7,000
4-Ethyl Toluene	ND	7,000
1,3,5-Trimethylbenzene	ND	7,000
1,2,4-Trimethylbenzene	ND	7,000
1,3-Dichlorobenzene	ND	7,000
1,4-Dichlorobenzene	ND	7,000
1,2-Dichlorobenzene	ND	7,000
1,2,4-Trichlorobenzene	ND	7,000
Hexachlorobutadiene	ND	7,000
1,3-Butadiene	ND	35,000
Isopropanol	55,000	35,000
n-Hexane	ND	35,000
Ethyl Acetate	ND	35,000
Tetrahydrofuran	160,000	35,000
Cyclohexane	ND	35,000
Heptane	ND	35,000
1,4-Dioxane	ND	35,000

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited low recovery in the continuing calibration verification indicating possible low bias

Reviewed/Approved By: _____ Date 9/18/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/02/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK							
Client Sample I.D.:	-							
Date/Time Sampled:	-							
Date/Time Analyzed:	9/2/26 6:27							
QC Batch No.:	260902MS2A1							
Analyst Initials:	VM/GD							
Dilution Factor:	0.20							

ANALYTE	Result ppbv	RL ppbv						
Dichlorodifluoromethane (12)	ND	0.20						
Chloromethane	ND	0.20						
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20						
Vinyl Chloride	ND	0.20						
Bromomethane	ND	0.20						
Chloroethane	ND	0.20						
Trichlorofluoromethane (11)	ND	0.20						
1,1-Dichloroethene	ND	0.20						
Carbon Disulfide	ND	0.20						
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20						
Acetone	ND	0.20						
Methylene Chloride	ND	0.20						
t-1,2-Dichloroethene	ND	0.20						
1,1-Dichloroethane	ND	0.20						
Vinyl Acetate	ND	0.20						
c-1,2-Dichloroethene	ND	0.20						
2-Butanone	ND	0.40						
t-Butyl Methyl Ether (MTBE)	ND	0.20						
Chloroform	ND	0.20						
1,1,1-Trichloroethane	ND	0.20						
Carbon Tetrachloride	ND	0.20						
Benzene	ND	0.20						
1,2-Dichloroethane	ND	0.20						
Trichloroethene	ND	0.20						
1,2-Dichloropropane	ND	0.20						
Bromodichloromethane	ND	0.20						
c-1,3-Dichloropropene	ND	0.20						
4-Methyl-2-Pentanone	ND	0.20						
Toluene	ND	0.20						
t-1,3-Dichloropropene	ND	0.20						
1,1,2-Trichloroethane	ND	0.20						
Tetrachloroethene	ND	0.20						
2-Hexanone	ND	0.20						
Dibromochloromethane	ND	0.20						

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/02/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK
Client Sample I.D.:	-
Date/Time Sampled:	-
Date/Time Analyzed:	9/2/26 6:27
QC Batch No.:	260902MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	0.20
Chlorobenzene	ND	0.20
Ethylbenzene	ND	0.20
p,&m-Xylene	ND	0.20
o-Xylene	ND	0.20
Styrene	ND	0.20
Bromoform	ND	0.20
1,1,2,2-Tetrachloroethane	ND	0.20
Benzyl Chloride	ND Q	0.20
4-Ethyl Toluene	ND	0.20
1,3,5-Trimethylbenzene	ND	0.20
1,2,4-Trimethylbenzene	ND	0.20
1,3-Dichlorobenzene	ND	0.20
1,4-Dichlorobenzene	ND	0.20
1,2-Dichlorobenzene	ND	0.20
1,2,4-Trichlorobenzene	ND	0.20
Hexachlorobutadiene	ND	0.20
1,3-Butadiene	ND	1.0
Isopropanol	ND	1.0
n-Hexane	ND	1.0
Ethyl Acetate	ND	1.0
Tetrahydrofuran	ND	1.0
Cyclohexane	ND	1.0
Heptane	ND	1.0
1,4-Dioxane	ND	1.0

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited low recovery in the continuing calibration verification indicating possible low bias

Reviewed/Approved By: _____ Date 9/8/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 260902MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	9/2/26 6:27			9/2/26 5:09		9/2/26 5:48					
Analyst Initials:	VM/GD			VM/GD		VM/GD					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	0.20	10	10.7	107	10.8	108	1.1	70	130	30
Methylene Chloride	ND	0.20	10	9.48	95	9.60	96	1.3	70	130	30
Trichloroethene	ND	0.20	10	9.43	94	9.20	92	2.5	70	130	30
Toluene	ND	0.20	10	9.03	90	8.70	87	3.7	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	9.24	92	9.10	91	1.5	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date: 9/18/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/02/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T090207-01		T090207-02		T090207-03		T090207-04	
Client Sample I.D.:	CV-24141		CV-2351		CV-2352		CV-24140	
Date/Time Sampled:	9/2/26 7:10		9/2/26 7:15		9/2/26 7:20		9/2/26 7:25	
Date/Time Analyzed:	9/2/26 19:14		9/2/26 19:29		9/2/26 19:43		9/2/26 19:58	
QC Batch No.:	260902GC8A1		260902GC8A1		260902GC8A1		260902GC8A1	
Analyst Initials:	AS		AS		AS		AS	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	26	10	220	10	820	10	1,400	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 9/17/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/02/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T090207-05		T090207-06		T090207-07		T090207-08	
Client Sample I.D.:	CV-24139		CV-24138		CV-24142		CV-2354	
Date/Time Sampled:	9/2/26 7:30		9/2/26 7:35		9/2/26 7:40		9/2/26 7:45	
Date/Time Analyzed:	9/2/26 20:12		9/2/26 20:27		9/2/26 20:41		9/2/26 20:56	
QC Batch No.:	260902GC8A1		260902GC8A1		260902GC8A1		260902GC8A1	
Analyst Initials:	AS		AS		AS		AS	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	720	10	160	10	1,200	10	1,400	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 9/17/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/02/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	**T090207-09**							
Client Sample I.D.:	**CV-2349**							
Date/Time Sampled:	**9/2/26 7:50**							
Date/Time Analyzed:	**9/2/26 21:10**							
QC Batch No.:	**260902GC8A1**							
Analyst Initials:	**AS**							
Dilution Factor:	**1.0**							
ANALYTE	**Result ppmv**	**RL ppmv**						
Carbon Monoxide	2,900	10						

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 9/17/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260902GC8A1
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	9/2/26 15:03			9/2/26 13:50		9/2/26 15:17					
Analyst Initials:	AS			AS		AS					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,080	107	1,080	106	0.9	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 9/17/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/02/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090207-01			T090207-02			T090207-03			T090207-04		
Client Sample I.D.:	CV-24141			CV-2351			CV-2352			CV-24140		
Date/Time Sampled:	9/2/26 7:10			9/2/26 7:15			9/2/26 7:20			9/2/26 7:25		
Date/Time Analyzed:	9/2/26 19:14			9/2/26 19:29			9/2/26 19:43			9/2/26 19:58		
QC Batch No.:	260902GC8A1			260902GC8A1			260902GC8A1			260902GC8A1		
Analyst Initials:	AS			AS			AS			AS		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	**Result % v/v**	**RL % v/v**	**MDL % v/v**	**Result % v/v**	**RL % v/v**	**MDL % v/v**	**Result % v/v**	**RL % v/v**	**MDL % v/v**	**Result % v/v**	**RL % v/v**	**MDL % v/v**
Hydrogen	0.19 J	1.0	0.059	2.7	1.0	0.059	19	1.0	0.059	21	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 9/17/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/02/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090207-05			T090207-06			T090207-07			T090207-08		
Client Sample I.D.:	CV-24139			CV-24138			CV-24142			CV-2354		
Date/Time Sampled:	9/2/26 7:30			9/2/26 7:35			9/2/26 7:40			9/2/26 7:45		
Date/Time Analyzed:	9/2/26 20:12			9/2/26 20:27			9/2/26 20:41			9/2/26 20:56		
QC Batch No.:	260902GC8A1			260902GC8A1			260902GC8A1			260902GC8A1		
Analyst Initials:	AS			AS			AS			AS		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	**Result % v/v**	**RL % v/v**	**MDL % v/v**	**Result % v/v**	**RL % v/v**	**MDL % v/v**	**Result % v/v**	**RL % v/v**	**MDL % v/v**	**Result % v/v**	**RL % v/v**	**MDL % v/v**
Hydrogen	21	1.0	0.059	2.5	1.0	0.059	17	1.0	0.059	15	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 9/17/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/02/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090207-09		
Client Sample I.D.:	CV-2349		
Date/Time Sampled:	9/2/26 7:50		
Date/Time Analyzed:	9/2/26 21:10		
QC Batch No.:	260902GC8A1		
Analyst Initials:	AS		
Dilution Factor:	1.0		

ANALYTE	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	20	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 9/17/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260902GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	9/2/26 15:03				9/2/26 13:50		9/2/26 15:17					
Analyst Initials:	AS				AS		AS					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	0.18 J	1.0	0.059	5.0	5.69	111	5.65	110	0.7	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 9/17/26
Anmika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/02/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090207-01		T090207-02		T090207-03		T090207-04	
Client Sample I.D.:	CV-24141		CV-2351		CV-2352		CV-24140	
Date/Time Sampled:	9/2/26 7:10		9/2/26 7:15		9/2/26 7:20		9/2/26 7:25	
Date/Time Analyzed:	9/2/26 19:14		9/2/26 19:29		9/2/26 19:43		9/2/26 19:58	
QC Batch No.:	260902GC8A1		260902GC8A1		260902GC8A1		260902GC8A1	
Analyst Initials:	AS		AS		AS		AS	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	7.6	0.010	12	0.010	67	0.010	69	0.010
Oxygen/Argon	18	0.50	16	0.50	2.0	0.50	1.4	0.50
Nitrogen	72	1.0	65	1.0	7.7	1.0	5.3	1.0
Methane	2.8	0.0010	3.4	0.0010	2.5	0.0010	2.0	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 9/17/26

Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/02/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090207-05		T090207-06		T090207-07		T090207-08	
Client Sample I.D.:	CV-24139		CV-24138		CV-24142		CV-2354	
Date/Time Sampled:	9/2/26 7:30		9/2/26 7:35		9/2/26 7:40		9/2/26 7:45	
Date/Time Analyzed:	9/2/26 20:12		9/2/26 20:27		9/2/26 20:41		9/2/26 20:56	
QC Batch No.:	260902GC8A1		260902GC8A1		260902GC8A1		260902GC8A1	
Analyst Initials:	AS		AS		AS		AS	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**
Carbon Dioxide	64	0.010	8.5	0.010	56	0.010	56	0.010
Oxygen/Argon	2.1	0.50	17	0.50	4.8	0.50	5.1	0.50
Nitrogen	8.0	1.0	71	1.0	19	1.0	19	1.0
Methane	2.8	0.0010	0.41	0.0010	2.3	0.0010	3.4	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 9/7/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/02/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090207-09		T090207-10					
Client Sample I.D.:	CV-2349		CV-24144					
Date/Time Sampled:	9/2/26 7:50		9/2/26 8:00					
Date/Time Analyzed:	9/2/26 21:10		9/2/26 21:25					
QC Batch No.:	260902GC8A1		260902GC8A1					
Analyst Initials:	AS		AS					
Dilution Factor:	1.0		1.0					
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**				
Carbon Dioxide	72	0.010	42	0.010				
Oxygen/Argon	1.0	0.50	0.82	0.50				
Nitrogen	3.8	1.0	3.1	1.0				
Methane	1.7	0.0010	52	0.0010				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 9/17/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260902GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	9/2/26 15:03			9/2/26 13:50		9/2/26 15:17					
Analyst Initials:	AS			AS		AS					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	10.0	100	10.0	100	0.0	70	130	30
Oxygen/Argon	ND	0.50	15	14.9	99	14.9	99	0.1	70	130	30
Nitrogen	ND	1.0	70	72.5	104	72.4	104	0.1	70	130	30
Methane	ND	0.0010	0.10	0.0993	98	0.0987	98	0.6	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 9/17/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

SGS

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175
TX Cert T104704450-14-6
EPA Methods TO14A, TO15
ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

September 22, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T090301-01/10

Enclosed are the results for sample(s) received 9/3/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were received in Mylar bags. Quadratic regression calibration was required for ethyl acetate, tetrahydrofuran, cyclohexane, and 1,4-dioxane.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Zain Khan, Art Jones and Ali Ferrara on 9/21/26.

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Annika Sotelo-Sanchez
Lab Manager
Annika.sotelo-sanchez@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME
Standard ■ 48 hours ☐
Same Day ☐ 72 hours ☐
24 hours ☐ 96 hours ☐
Other:

DELIVERABLES
EDD ■
EDF ☐
Level 3 ☐
Level 4 ☐

PAGE: 1 OF

Condition upon receipt:
Sealed Yes ☐ No ☐
Intact Yes ☐ No ☐
Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING
P.O. No.:
Bill to:
07FSAccountspayable@scsengineers.com
3900 Kilroy Airport Way, Suite 300
Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T090301-01	CV-2301	09/03/26	6:40AM	2-1L	Gas	N	X	X	X	X		
-02	CV-2302	9/3/2026	6:45AM	2-1L	Gas	N	X	X	X	X		
-03	CV-2303	09/03/26	6:50AM	2-1L	Gas	N	X	X	X	X		
-04	CV-2312	09/03/26	7:00AM	2-1L	Gas	N	X	X	X	X		
-05	CV-24007	09/03/26	7:10AM	2-1L	Gas	N	X	X	X	X		
-06	CV-24062	09/03/26	7:20AM	1L	Gas	N	X	X	X			
-07	CV-24063	09/03/26	7:20AM	1L	Gas	N	X	X	X			
-08	CV-24064	09/03/26	7:30AM	1L	Gas	N	X	X	X			
-09	CV-2333	09/03/26	7:45AM	1L	Gas	N	X	X	X			
-10	CV-2334	09/03/26	7:50AM	1L	Gas	N	X	X	X			

AUTHORIZATION TO PERFORM WORK	COMPANY SCS	DATE/TIME 9-3-26 8:07a	
SAMPLED BY	COMPANY SCS	DATE/TIME 9-3-26 8:07a	
RELINQUISHED BY	DATE/TIME 9-3-26 8:07a	RECEIVED BY Antonio A	DATE/TIME 9-3-26 8:02am
RELINQUISHED BY Antonio A	DATE/TIME 9-3-26 8:34am	RECEIVED BY Nick N.	DATE/TIME 9-3-26 8:30
RELINQUISHED BY Nick N	DATE/TIME 9-3-26 11:00am	RECEIVED BY	DATE/TIME 9/3/26 11:00

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/03/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T090301-01		T090301-02		T090301-03		T090301-04	
Client Sample I.D.:	CV-2301		CV-2302		CV-2303		CV-2312	
Date/Time Sampled:	9/3/26 6:40		9/3/26 6:45		9/3/26 6:50		9/3/26 7:00	
Date/Time Analyzed:	9/3/26 14:15		9/3/26 14:52		9/3/26 15:30		9/3/26 16:07	
QC Batch No.:	260903MS2A1		260903MS2A1		260903MS2A1		260903MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	4,000		3,000		18,000		4,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	4,000	ND	3,000	ND	18,000	ND	4,000
Chloromethane	ND	4,000	ND	3,000	ND	18,000	ND	4,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	4,000	ND	3,000	ND	18,000	ND	4,000
Vinyl Chloride	ND	4,000	ND	3,000	ND	18,000	ND	4,000
Bromomethane	ND	4,000	ND	3,000	ND	18,000	ND	4,000
Chloroethane	ND	4,000	ND	3,000	ND	18,000	ND	4,000
Trichlorofluoromethane (11)	ND	4,000	ND	3,000	ND	18,000	ND	4,000
1,1-Dichloroethene	ND	4,000	ND	3,000	ND	18,000	ND	4,000
Carbon Disulfide	6,700	4,000	3,900	3,000	ND	18,000	ND	4,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	4,000	ND	3,000	ND	18,000	ND	4,000
Acetone	330,000	4,000	210,000	3,000	810,000	18,000	320,000	4,000
Methylene Chloride	ND	4,000	ND	3,000	ND	18,000	ND	4,000
t-1,2-Dichloroethene	ND	4,000	ND	3,000	ND	18,000	ND	4,000
1,1-Dichloroethane	ND	4,000	ND	3,000	ND	18,000	ND	4,000
Vinyl Acetate	ND	4,000	ND	3,000	ND	18,000	ND	4,000
c-1,2-Dichloroethene	ND	4,000	ND	3,000	ND	18,000	ND	4,000
2-Butanone	180,000	8,000	140,000	6,000	460,000	36,000	240,000	8,000
t-Butyl Methyl Ether (MTBE)	ND	4,000	ND	3,000	ND	18,000	ND	4,000
Chloroform	ND	4,000	ND	3,000	ND	18,000	ND	4,000
1,1,1-Trichloroethane	ND	4,000	ND	3,000	ND	18,000	ND	4,000
Carbon Tetrachloride	ND	4,000	ND	3,000	ND	18,000	ND	4,000
Benzene	51,000	4,000	33,000	3,000	140,000	18,000	100,000	4,000
1,2-Dichloroethane	ND	4,000	ND	3,000	ND	18,000	ND	4,000
Trichloroethene	ND	4,000	ND	3,000	ND	18,000	ND	4,000
1,2-Dichloropropane	ND	4,000	ND	3,000	ND	18,000	ND	4,000
Bromodichloromethane	ND	4,000	ND	3,000	ND	18,000	ND	4,000
c-1,3-Dichloropropene	ND	4,000	ND	3,000	ND	18,000	ND	4,000
4-Methyl-2-Pentanone	ND	4,000	ND	3,000	ND	18,000	ND	4,000
Toluene	ND	4,000	ND	3,000	ND	18,000	ND	4,000
t-1,3-Dichloropropene	ND	4,000	ND	3,000	ND	18,000	ND	4,000
1,1,2-Trichloroethane	ND	4,000	ND	3,000	ND	18,000	ND	4,000
Tetrachloroethene	ND	4,000	ND	3,000	ND	18,000	ND	4,000
2-Hexanone	ND	4,000	ND	3,000	ND	18,000	ND	4,000
Dibromochloromethane	ND	4,000	ND	3,000	ND	18,000	ND	4,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/03/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T090301-01		T090301-02		T090301-03		T090301-04	
Client Sample I.D.:	CV-2301		CV-2302		CV-2303		CV-2312	
Date/Time Sampled:	9/3/26 6:40		9/3/26 6:45		9/3/26 6:50		9/3/26 7:00	
Date/Time Analyzed:	9/3/26 14:15		9/3/26 14:52		9/3/26 15:30		9/3/26 16:07	
QC Batch No.:	260903MS2A1		260903MS2A1		260903MS2A1		260903MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	4,000		3,000		18,000		4,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	4,000	ND	3,000	ND	18,000	ND	4,000
Chlorobenzene	ND	4,000	ND	3,000	ND	18,000	ND	4,000
Ethylbenzene	ND	4,000	ND	3,000	ND	18,000	ND	4,000
p,&m-Xylene	ND	4,000	ND	3,000	ND	18,000	ND	4,000
o-Xylene	ND	4,000	ND	3,000	ND	18,000	ND	4,000
Styrene	ND	4,000	ND	3,000	ND	18,000	ND	4,000
Bromoform	ND	4,000	ND	3,000	ND	18,000	ND	4,000
1,1,2,2-Tetrachloroethane	ND	4,000	ND	3,000	ND	18,000	ND	4,000
Benzyl Chloride	ND	4,000	ND	3,000	ND	18,000	ND	4,000
4-Ethyl Toluene	ND	4,000	ND	3,000	ND	18,000	ND	4,000
1,3,5-Trimethylbenzene	ND	4,000	ND	3,000	ND	18,000	ND	4,000
1,2,4-Trimethylbenzene	ND	4,000	ND	3,000	ND	18,000	ND	4,000
1,3-Dichlorobenzene	ND	4,000	ND	3,000	ND	18,000	ND	4,000
1,4-Dichlorobenzene	ND	4,000	ND	3,000	ND	18,000	ND	4,000
1,2-Dichlorobenzene	ND	4,000	ND	3,000	ND	18,000	ND	4,000
1,2,4-Trichlorobenzene	ND	4,000	ND	3,000	ND	18,000	ND	4,000
Hexachlorobutadiene	ND	4,000	ND	3,000	ND	18,000	ND	4,000
1,3-Butadiene	ND	20,000	ND	15,000	ND	90,000	ND	20,000
Isopropanol	86,000	20,000	84,000	15,000	210,000	90,000	70,000	20,000
n-Hexane	ND	20,000	21,000	15,000	150,000	90,000	32,000	20,000
Ethyl Acetate	31,000	20,000	ND	15,000	ND	90,000	ND	20,000
Tetrahydrofuran	130,000	20,000	100,000	15,000	260,000	90,000	200,000	20,000
Cyclohexane	ND	20,000	ND	15,000	ND	90,000	ND	20,000
Heptane	ND	20,000	ND	15,000	ND	90,000	ND	20,000
1,4-Dioxane	ND	20,000	ND	15,000	ND	90,000	ND	20,000

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 9/18/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/03/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T090301-05
Client Sample I.D.:	CV-24007
Date/Time Sampled:	9/3/26 7:10
Date/Time Analyzed:	9/3/26 16:45
QC Batch No.:	260903MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	3,000

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	3,000
Chloromethane	ND	3,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	3,000
Vinyl Chloride	ND	3,000
Bromomethane	ND	3,000
Chloroethane	ND	3,000
Trichlorofluoromethane (11)	ND	3,000
1,1-Dichloroethene	ND	3,000
Carbon Disulfide	3,100	3,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	3,000
Acetone	210,000	3,000
Methylene Chloride	ND	3,000
t-1,2-Dichloroethene	ND	3,000
1,1-Dichloroethane	ND	3,000
Vinyl Acetate	ND	3,000
c-1,2-Dichloroethene	ND	3,000
2-Butanone	160,000	6,000
t-Butyl Methyl Ether (MTBE)	ND	3,000
Chloroform	ND	3,000
1,1,1-Trichloroethane	ND	3,000
Carbon Tetrachloride	ND	3,000
Benzene	70,000	3,000
1,2-Dichloroethane	ND	3,000
Trichloroethene	ND	3,000
1,2-Dichloropropane	ND	3,000
Bromodichloromethane	ND	3,000
c-1,3-Dichloropropene	ND	3,000
4-Methyl-2-Pentanone	ND	3,000
Toluene	3,800	3,000
t-1,3-Dichloropropene	ND	3,000
1,1,2-Trichloroethane	ND	3,000
Tetrachloroethene	ND	3,000
2-Hexanone	ND	3,000
Dibromochloromethane	ND	3,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/03/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T090301-05
Client Sample I.D.:	CV-24007
Date/Time Sampled:	9/3/26 7:10
Date/Time Analyzed:	9/3/26 16:45
QC Batch No.:	260903MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	3,000

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	3,000
Chlorobenzene	ND	3,000
Ethylbenzene	ND	3,000
p,&m-Xylene	ND	3,000
o-Xylene	ND	3,000
Styrene	ND	3,000
Bromoform	ND	3,000
1,1,2,2-Tetrachloroethane	ND	3,000
Benzyl Chloride	ND	3,000
4-Ethyl Toluene	ND	3,000
1,3,5-Trimethylbenzene	ND	3,000
1,2,4-Trimethylbenzene	ND	3,000
1,3-Dichlorobenzene	ND	3,000
1,4-Dichlorobenzene	ND	3,000
1,2-Dichlorobenzene	ND	3,000
1,2,4-Trichlorobenzene	ND	3,000
Hexachlorobutadiene	ND	3,000
1,3-Butadiene	ND	15,000
Isopropanol	74,000	15,000
n-Hexane	21,000	15,000
Ethyl Acetate	ND	15,000
Tetrahydrofuran	130,000	15,000
Cyclohexane	ND	15,000
Heptane	ND	15,000
1,4-Dioxane	ND	15,000

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 9/10/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/03/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD-BLAN
Client Sample I.D.:	-
Date/Time Sampled:	-
Date/Time Analyzed:	9/3/26 13:03
QC Batch No.:	260903MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	0.20
Chloromethane	ND	0.20
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20
Vinyl Chloride	ND	0.20
Bromomethane	ND	0.20
Chloroethane	ND	0.20
Trichlorofluoromethane (11)	ND	0.20
1,1-Dichloroethene	ND	0.20
Carbon Disulfide	ND	0.20
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20
Acetone	ND	0.20
Methylene Chloride	ND	0.20
t-1,2-Dichloroethene	ND	0.20
1,1-Dichloroethane	ND	0.20
Vinyl Acetate	ND	0.20
c-1,2-Dichloroethene	ND	0.20
2-Butanone	ND	0.40
t-Butyl Methyl Ether (MTBE)	ND	0.20
Chloroform	ND	0.20
1,1,1-Trichloroethane	ND	0.20
Carbon Tetrachloride	ND	0.20
Benzene	ND	0.20
1,2-Dichloroethane	ND	0.20
Trichloroethene	ND	0.20
1,2-Dichloropropane	ND	0.20
Bromodichloromethane	ND	0.20
c-1,3-Dichloropropene	ND	0.20
4-Methyl-2-Pentanone	ND	0.20
Toluene	ND	0.20
t-1,3-Dichloropropene	ND	0.20
1,1,2-Trichloroethane	ND	0.20
Tetrachloroethene	ND	0.20
2-Hexanone	ND	0.20
Dibromochloromethane	ND	0.20

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/03/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD-BLAN
Client Sample I.D.:	-
Date/Time Sampled:	-
Date/Time Analyzed:	9/3/26 13:03
QC Batch No.:	260903MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	0.20
Chlorobenzene	ND	0.20
Ethylbenzene	ND	0.20
p,&m-Xylene	ND	0.20
o-Xylene	ND	0.20
Styrene	ND	0.20
Bromoform	ND	0.20
1,1,2,2-Tetrachloroethane	ND	0.20
Benzyl Chloride	ND	0.20
4-Ethyl Toluene	ND	0.20
1,3,5-Trimethylbenzene	ND	0.20
1,2,4-Trimethylbenzene	ND	0.20
1,3-Dichlorobenzene	ND	0.20
1,4-Dichlorobenzene	ND	0.20
1,2-Dichlorobenzene	ND	0.20
1,2,4-Trichlorobenzene	ND	0.20
Hexachlorobutadiene	ND	0.20
1,3-Butadiene	ND	1.0
Isopropanol	ND	1.0
n-Hexane	ND	1.0
Ethyl Acetate	ND	1.0
Tetrahydrofuran	ND	1.0
Cyclohexane	ND	1.0
Heptane	ND	1.0
1,4-Dioxane	ND	1.0

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 9/18/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 260903MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	9/3/26 13:03			9/3/26 11:47		9/3/26 12:25					
Analyst Initials:	VM/GD			VM/GD		VM/GD					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	0.20	10	11.4	114	11.2	112	2.2	70	130	30
Methylene Chloride	ND	0.20	10	9.88	99	9.79	98	0.9	70	130	30
Trichloroethene	ND	0.20	10	9.84	98	9.32	93	5.5	70	130	30
Toluene	ND	0.20	10	9.44	94	9.04	90	4.3	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	9.67	97	9.53	95	1.4	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date: 9/18/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/03/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T090301-01		T090301-02		T090301-03		T090301-04	
Client Sample I.D.:	CV-2301		CV-2302		CV-2303		CV-2312	
Date/Time Sampled:	9/3/26 6:40		9/3/26 6:45		9/3/26 6:50		9/3/26 7:00	
Date/Time Analyzed:	9/3/26 15:26		9/3/26 17:56		9/3/26 18:10		9/3/26 16:10	
QC Batch No.:	260903GC8A2		260903GC8A2		260903GC8A2		260903GC8A2	
Analyst Initials:	AS		AS		AS		AS	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	470	10	ND	10	1,700	10	2,600	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 9/18/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/03/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T090301-05		T090301-06		T090301-07		T090301-08	
Client Sample I.D.:	CV-24007		CV-24062		CV-24063		CV-24064	
Date/Time Sampled:	9/3/26 7:10		9/3/26 7:20		9/3/26 7:20		9/3/26 7:30	
Date/Time Analyzed:	9/3/26 16:24		9/3/26 18:25		9/3/26 16:53		9/3/26 17:08	
QC Batch No.:	260903GC8A2		260903GC8A2		260903GC8A2		260903GC8A2	
Analyst Initials:	AS		AS		AS		AS	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	400	10	840	10	1,400	10	1,600	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 9/8/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/03/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T090301-09		T090301-10					
Client Sample I.D.:	CV-2333		CV-2334					
Date/Time Sampled:	9/3/26 7:45		9/3/26 7:50					
Date/Time Analyzed:	9/3/26 17:22		9/3/26 18:39					
QC Batch No.:	260903GC8A2		260903GC8A2					
Analyst Initials:	AS		AS					
Dilution Factor:	1.0		1.0					
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv				
Carbon Monoxide	2,700	10	2,600	10				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 9/18/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260903GC8A2
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	9/3/26 15:12			9/3/26 14:14		9/3/26 14:28					
Analyst Initials:	MJ			MJ		MJ					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,010	100	1,010	100	0.5	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 9/18/26
Anoika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/03/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090301-01			T090301-02			T090301-03			T090301-04		
Client Sample I.D.:	CV-2301			CV-2302			CV-2303			CV-2312		
Date/Time Sampled:	9/3/26 6:40			9/3/26 6:45			9/3/26 6:50			9/3/26 7:00		
Date/Time Analyzed:	9/3/26 15:26			9/3/26 17:56			9/3/26 18:10			9/3/26 16:10		
QC Batch No.:	260903GC8A2			260903GC8A2			260903GC8A2			260903GC8A2		
Analyst Initials:	AS			AS			AS			AS		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	5.5	1.0	0.059	3.5	1.0	0.059	19	1.0	0.059	16	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 9/8/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/03/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090301-05			T090301-06			T090301-07			T090301-08		
Client Sample I.D.:	CV-24007			CV-24062			CV-24063			CV-24064		
Date/Time Sampled:	9/3/26 7:10			9/3/26 7:20			9/3/26 7:20			9/3/26 7:30		
Date/Time Analyzed:	9/3/26 16:24			9/3/26 18:25			9/3/26 16:53			9/3/26 17:08		
QC Batch No.:	260903GC8A2			260903GC8A2			260903GC8A2			260903GC8A2		
Analyst Initials:	AS			AS			AS			AS		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	5.1	1.0	0.059	11	1.0	0.059	11	1.0	0.059	14	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 9/18/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/03/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090301-09			T090301-10								
Client Sample I.D.:	CV-2333			CV-2334								
Date/Time Sampled:	9/3/26 7:45			9/3/26 7:50								
Date/Time Analyzed:	9/3/26 17:22			9/3/26 18:39								
QC Batch No.:	260903GC8A2			260903GC8A2								
Analyst Initials:	AS			AS								
Dilution Factor:	1.0			1.0								
ANALYTE	**Result % v/v**	**RL % v/v**	**MDL % v/v**	**Result % v/v**	**RL % v/v**	**MDL % v/v**						
Hydrogen	19	1.0	0.059	14	1.0	0.059						

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 9/18/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260903GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	9/3/26 15:12				9/3/26 14:14		9/3/26 14:28					
Analyst Initials:	MJ				MJ		MJ					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	0.23 J	1.0	0.059	5.0	5.06	97	4.98	96	1.5	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 9/18/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/03/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090301-01		T090301-02		T090301-03		T090301-04	
Client Sample I.D.:	CV-2301		CV-2302		CV-2303		CV-2312	
Date/Time Sampled:	9/3/26 6:40		9/3/26 6:45		9/3/26 6:50		9/3/26 7:00	
Date/Time Analyzed:	9/3/26 15:26		9/3/26 17:56		9/3/26 18:10		9/3/26 16:10	
QC Batch No.:	260903GC8A2		260903GC8A2		260903GC8A2		260903GC8A2	
Analyst Initials:	AS		AS		AS		AS	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	43	0.010	43	0.010	74	0.010	78	0.010
Oxygen/Argon	4.1	0.50	1.3	0.50	ND	0.50	ND	0.50
Nitrogen	19	1.0	5.3	1.0	1.6	1.0	2.6	1.0
Methane	28	0.0010	47	0.0010	3.0	0.0010	1.9	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 9/18/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/03/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090301-05		T090301-06		T090301-07		T090301-08	
Client Sample I.D.:	CV-24007		CV-24062		CV-24063		CV-24064	
Date/Time Sampled:	9/3/26 7:10		9/3/26 7:20		9/3/26 7:20		9/3/26 7:30	
Date/Time Analyzed:	9/3/26 16:24		9/3/26 18:25		9/3/26 16:53		9/3/26 17:08	
QC Batch No.:	260903GC8A2		260903GC8A2		260903GC8A2		260903GC8A2	
Analyst Initials:	AS		AS		AS		AS	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	43	0.010	64	0.010	74	0.010	79	0.010
Oxygen/Argon	1.0	0.50	0.74	0.50	0.72	0.50	0.80	0.50
Nitrogen	26	1.0	2.7	1.0	2.7	1.0	3.0	1.0
Methane	24	0.0010	20	0.0010	10.0	0.0010	1.8	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 9/18/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/03/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090301-09		T090301-10					
Client Sample I.D.:	CV-2333		CV-2334					
Date/Time Sampled:	9/3/26 7:45		9/3/26 7:50					
Date/Time Analyzed:	9/3/26 17:22		9/3/26 18:39					
QC Batch No.:	260903GC8A2		260903GC8A2					
Analyst Initials:	AS		AS					
Dilution Factor:	1.0		1.0					
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**				
Carbon Dioxide	73	0.010	77	0.010				
Oxygen/Argon	1.2	0.50	0.83	0.50				
Nitrogen	4.3	1.0	3.1	1.0				
Methane	0.67	0.0010	3.2	0.0010				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 9/18/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260903GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	9/3/26 15:12			9/3/26 14:14		9/3/26 14:28					
Analyst Initials:	MJ			MJ		MJ					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	9.44	94	9.45	94	0.1	70	130	30
Oxygen/Argon	ND	0.50	15	14.6	97	14.6	97	0.1	70	130	30
Nitrogen	ND	1.0	70	70.5	101	70.5	101	0.0	70	130	30
Methane	ND	0.0010	0.10	0.0970	96	0.0966	96	0.4	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 9/18/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175
TX Cert T104704450-14-6
EPA Methods TO14A, TO15
ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

September 29, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T090401-01/09

Enclosed are the results for sample(s) received 9/4/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags. Quadratic regression calibration was required for ethyl acetate, tetrahydrofuran, cyclohexane, and 1,4-dioxane.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Zain Khan, Art Jones and Ali Ferrara on 9/28/26.

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Annika Sotelo-Sanchez
Lab Manager
Annika.sotelo-sanchez@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐ No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐ No ☐
Other:				Level 4	☐	Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:

Bill to:

07FSAccountspayable@scsengineers.com

3900 Kilroy Airport Way, Suite 300

Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T090401-01	CV-113	09/04/26	7:00AM	2-1L	Gas	N	X	X	X	X		
-02	CV-99	09/04/26	7:05AM	1L	Gas	N	X	X	X			
-03	CV-1535	09/04/26	7:22AM	2-1L	Gas	N	X	X	X	X		
-04	CV-2007	09/04/26	7:48AM	2-1L	Gas	N	X	X	X	X		
-05	CV-2314	09/04/26	7:56AM	1L	Gas	N	X	X	X			
-06	CV-2315	09/04/26	8:04AM	2-1L	Gas	N	X	X	X	X		
-07	CV-24084	09/04/26	8:11AM	1L	Gas	N	X					
-08	CV-114	09/04/26	8:22AM	1L	Gas	N	X	X	X			
-09	H-2273W	09/04/26	8:32AM	2-1L	Gas	N	X	X	X	X		
					Gas	N						

AUTHORIZATION TO PERFORM WORK	COMPANY SCS	DATE/TIME 9.4.26 0852	
SAMPLED BY	COMPANY SCS	DATE/TIME 9.4.26 0852	
RELINQUISHED BY	DATE/TIME 9.4.26 0900	RECEIVED BY	DATE/TIME 9.4.26 9:10
RELINQUISHED BY	DATE/TIME 9.4.26 12:02	RECEIVED BY	DATE/TIME 9/4/26 12:02
RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/04/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T090401-01		T090401-03		T090401-04		T090401-06	
Client Sample I.D.:	CV-113		CV-1535		CV-2007		CV-2315	
Date/Time Sampled:	9/4/26 7:00		9/4/26 7:22		9/4/26 7:48		9/4/26 8:04	
Date/Time Analyzed:	9/4/26 14:22		9/4/26 14:59		9/4/26 15:38		9/4/26 16:16	
QC Batch No.:	260904MS2A1		260904MS2A1		260904MS2A1		260904MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	4,000		10,000		5,000		20,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	4,000	ND	10,000	ND	5,000	ND	20,000
Chloromethane	ND	4,000	14,000	10,000	ND	5,000	ND	20,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	4,000	ND	10,000	ND	5,000	ND	20,000
Vinyl Chloride	ND	4,000	ND	10,000	ND	5,000	ND	20,000
Bromomethane	ND	4,000	ND	10,000	ND	5,000	ND	20,000
Chloroethane	ND	4,000	ND	10,000	ND	5,000	ND	20,000
Trichlorofluoromethane (11)	ND	4,000	ND	10,000	ND	5,000	ND	20,000
1,1-Dichloroethene	ND	4,000	ND	10,000	ND	5,000	ND	20,000
Carbon Disulfide	ND	4,000	ND	10,000	ND	5,000	ND	20,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	4,000	ND	10,000	ND	5,000	ND	20,000
Acetone	260,000	4,000	850,000	10,000	350,000	5,000	1,100,000	20,000
Methylene Chloride	ND	4,000	ND	10,000	ND	5,000	ND	20,000
t-1,2-Dichloroethene	ND	4,000	ND	10,000	ND	5,000	ND	20,000
1,1-Dichloroethane	ND	4,000	ND	10,000	ND	5,000	ND	20,000
Vinyl Acetate	ND	4,000	ND	10,000	ND	5,000	ND	20,000
c-1,2-Dichloroethene	ND	4,000	ND	10,000	ND	5,000	ND	20,000
2-Butanone	120,000	8,000	350,000	20,000	220,000	10,000	490,000	40,000
t-Butyl Methyl Ether (MTBE)	ND	4,000	ND	10,000	ND	5,000	ND	20,000
Chloroform	ND	4,000	ND	10,000	ND	5,000	ND	20,000
1,1,1-Trichloroethane	ND	4,000	ND	10,000	ND	5,000	ND	20,000
Carbon Tetrachloride	ND	4,000	ND	10,000	ND	5,000	ND	20,000
Benzene	12,000	4,000	62,000	10,000	85,000	5,000	98,000	20,000
1,2-Dichloroethane	ND	4,000	ND	10,000	ND	5,000	ND	20,000
Trichloroethene	ND	4,000	ND	10,000	ND	5,000	ND	20,000
1,2-Dichloropropane	ND	4,000	ND	10,000	ND	5,000	ND	20,000
Bromodichloromethane	ND	4,000	ND	10,000	ND	5,000	ND	20,000
c-1,3-Dichloropropene	ND	4,000	ND	10,000	ND	5,000	ND	20,000
4-Methyl-2-Pentanone	ND	4,000	ND	10,000	ND	5,000	ND	20,000
Toluene	ND	4,000	ND	10,000	ND	5,000	ND	20,000
t-1,3-Dichloropropene	ND	4,000	ND	10,000	ND	5,000	ND	20,000
1,1,2-Trichloroethane	ND	4,000	ND	10,000	ND	5,000	ND	20,000
Tetrachloroethene	ND	4,000	ND	10,000	ND	5,000	ND	20,000
2-Hexanone	ND	4,000	ND	10,000	ND	5,000	ND	20,000
Dibromochloromethane	ND	4,000	ND	10,000	ND	5,000	ND	20,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/04/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T090401-01		T090401-03		T090401-04		T090401-06	
Client Sample I.D.:	CV-113		CV-1535		CV-2007		CV-2315	
Date/Time Sampled:	9/4/26 7:00		9/4/26 7:22		9/4/26 7:48		9/4/26 8:04	
Date/Time Analyzed:	9/4/26 14:22		9/4/26 14:59		9/4/26 15:38		9/4/26 16:16	
QC Batch No.:	260904MS2A1		260904MS2A1		260904MS2A1		260904MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	4,000		10,000		5,000		20,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	4,000	ND	10,000	ND	5,000	ND	20,000
Chlorobenzene	ND	4,000	ND	10,000	ND	5,000	ND	20,000
Ethylbenzene	ND	4,000	ND	10,000	ND	5,000	ND	20,000
p,&m-Xylene	ND	4,000	ND	10,000	ND	5,000	ND	20,000
o-Xylene	ND	4,000	ND	10,000	ND	5,000	ND	20,000
Styrene	ND	4,000	ND	10,000	ND	5,000	ND	20,000
Bromoform	ND	4,000	ND	10,000	ND	5,000	ND	20,000
1,1,2,2-Tetrachloroethane	ND	4,000	ND	10,000	ND	5,000	ND	20,000
Benzyl Chloride	ND	4,000	ND	10,000	ND	5,000	ND	20,000
4-Ethyl Toluene	ND	4,000	ND	10,000	ND	5,000	ND	20,000
1,3,5-Trimethylbenzene	ND	4,000	ND	10,000	ND	5,000	ND	20,000
1,2,4-Trimethylbenzene	ND	4,000	ND	10,000	ND	5,000	ND	20,000
1,3-Dichlorobenzene	ND	4,000	ND	10,000	ND	5,000	ND	20,000
1,4-Dichlorobenzene	ND	4,000	ND	10,000	ND	5,000	ND	20,000
1,2-Dichlorobenzene	ND	4,000	ND	10,000	ND	5,000	ND	20,000
1,2,4-Trichlorobenzene	ND	4,000	ND	10,000	ND	5,000	ND	20,000
Hexachlorobutadiene	ND	4,000	ND	10,000	ND	5,000	ND	20,000
1,3-Butadiene	ND	20,000	ND	50,000	ND	25,000	ND	100,000
Isopropanol	43,000	20,000	70,000	50,000	130,000	25,000	150,000	100,000
n-Hexane	ND	20,000	ND	50,000	28,000	25,000	ND	100,000
Ethyl Acetate	ND	20,000	ND	50,000	ND	25,000	ND	100,000
Tetrahydrofuran	27,000	20,000	180,000	50,000	220,000	25,000	290,000	100,000
Cyclohexane	ND	20,000	ND	50,000	ND	25,000	ND	100,000
Heptane	ND	20,000	ND	50,000	ND	25,000	ND	100,000
1,4-Dioxane	ND	20,000	ND	50,000	ND	25,000	ND	100,000

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 9/7/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/04/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T090401-09
Client Sample I.D.:	H-2273W
Date/Time Sampled:	9/4/26 8:32
Date/Time Analyzed:	9/4/26 16:53
QC Batch No.:	260904MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	4,000

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	4,000
Chloromethane	ND	4,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	4,000
Vinyl Chloride	ND	4,000
Bromomethane	ND	4,000
Chloroethane	ND	4,000
Trichlorofluoromethane (11)	ND	4,000
1,1-Dichloroethene	ND	4,000
Carbon Disulfide	ND	4,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	4,000
Acetone	320,000	4,000
Methylene Chloride	ND	4,000
t-1,2-Dichloroethene	ND	4,000
1,1-Dichloroethane	ND	4,000
Vinyl Acetate	ND	4,000
c-1,2-Dichloroethene	ND	4,000
2-Butanone	190,000	8,000
t-Butyl Methyl Ether (MTBE)	ND	4,000
Chloroform	ND	4,000
1,1,1-Trichloroethane	ND	4,000
Carbon Tetrachloride	ND	4,000
Benzene	36,000	4,000
1,2-Dichloroethane	ND	4,000
Trichloroethene	ND	4,000
1,2-Dichloropropane	ND	4,000
Bromodichloromethane	ND	4,000
c-1,3-Dichloropropene	ND	4,000
4-Methyl-2-Pentanone	ND	4,000
Toluene	ND	4,000
t-1,3-Dichloropropene	ND	4,000
1,1,2-Trichloroethane	ND	4,000
Tetrachloroethene	ND	4,000
2-Hexanone	ND	4,000
Dibromochloromethane	ND	4,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/04/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T090401-09
Client Sample I.D.:	H-2273W
Date/Time Sampled:	9/4/26 8:32
Date/Time Analyzed:	9/4/26 16:53
QC Batch No.:	260904MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	4,000

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	4,000
Chlorobenzene	ND	4,000
Ethylbenzene	ND	4,000
p,&m-Xylene	ND	4,000
o-Xylene	ND	4,000
Styrene	ND	4,000
Bromoform	ND	4,000
1,1,2,2-Tetrachloroethane	ND	4,000
Benzyl Chloride	ND	4,000
4-Ethyl Toluene	ND	4,000
1,3,5-Trimethylbenzene	ND	4,000
1,2,4-Trimethylbenzene	ND	4,000
1,3-Dichlorobenzene	ND	4,000
1,4-Dichlorobenzene	ND	4,000
1,2-Dichlorobenzene	ND	4,000
1,2,4-Trichlorobenzene	ND	4,000
Hexachlorobutadiene	ND	4,000
1,3-Butadiene	ND	20,000
Isopropanol	95,000	20,000
n-Hexane	22,000	20,000
Ethyl Acetate	ND	20,000
Tetrahydrofuran	110,000	20,000
Cyclohexane	ND	20,000
Heptane	ND	20,000
1,4-Dioxane	ND	20,000

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 9/7/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/04/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD-BLAN							
Client Sample I.D.:	-							
Date/Time Sampled:	-							
Date/Time Analyzed:	9/4/26 8:00							
QC Batch No.:	260904MS2A1							
Analyst Initials:	VM/GD							
Dilution Factor:	0.20							

ANALYTE	Result ppbv	RL ppbv						
Dichlorodifluoromethane (12)	ND	0.20						
Chloromethane	ND	0.20						
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20						
Vinyl Chloride	ND	0.20						
Bromomethane	ND	0.20						
Chloroethane	ND	0.20						
Trichlorofluoromethane (11)	ND	0.20						
1,1-Dichloroethene	ND	0.20						
Carbon Disulfide	ND	0.20						
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20						
Acetone	0.26	0.20						
Methylene Chloride	ND	0.20						
t-1,2-Dichloroethene	ND	0.20						
1,1-Dichloroethane	ND	0.20						
Vinyl Acetate	ND	0.20						
c-1,2-Dichloroethene	ND	0.20						
2-Butanone	ND	0.40						
t-Butyl Methyl Ether (MTBE)	ND	0.20						
Chloroform	ND	0.20						
1,1,1-Trichloroethane	ND	0.20						
Carbon Tetrachloride	ND	0.20						
Benzene	ND	0.20						
1,2-Dichloroethane	ND	0.20						
Trichloroethene	ND	0.20						
1,2-Dichloropropane	ND	0.20						
Bromodichloromethane	ND	0.20						
c-1,3-Dichloropropene	ND	0.20						
4-Methyl-2-Pentanone	ND	0.20						
Toluene	ND	0.20						
t-1,3-Dichloropropene	ND	0.20						
1,1,2-Trichloroethane	ND	0.20						
Tetrachloroethene	ND	0.20						
2-Hexanone	ND	0.20						
Dibromochloromethane	ND	0.20						

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/04/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD-BLAN
Client Sample I.D.:	-
Date/Time Sampled:	-
Date/Time Analyzed:	9/4/26 8:00
QC Batch No.:	260904MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	0.20
Chlorobenzene	ND	0.20
Ethylbenzene	ND	0.20
p,&m-Xylene	ND	0.20
o-Xylene	ND	0.20
Styrene	ND	0.20
Bromoform	ND	0.20
1,1,2,2-Tetrachloroethane	ND	0.20
Benzyl Chloride	ND	0.20
4-Ethyl Toluene	ND	0.20
1,3,5-Trimethylbenzene	ND	0.20
1,2,4-Trimethylbenzene	ND	0.20
1,3-Dichlorobenzene	ND	0.20
1,4-Dichlorobenzene	ND	0.20
1,2-Dichlorobenzene	ND	0.20
1,2,4-Trichlorobenzene	ND	0.20
Hexachlorobutadiene	ND	0.20
1,3-Butadiene	ND	1.0
Isopropanol	ND	1.0
n-Hexane	ND	1.0
Ethyl Acetate	ND	1.0
Tetrahydrofuran	ND	1.0
Cyclohexane	ND	1.0
Heptane	ND	1.0
1,4-Dioxane	ND	1.0

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 9/7/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 260904MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	9/4/26 8:00			9/4/26 6:43		9/4/26 7:21					
Analyst Initials:	VM/GD			VM/GD		VM/GD					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	0.20	10	11.7	117	11.4	114	3.0	70	130	30
Methylene Chloride	ND	0.20	10	9.83	98	9.89	99	0.6	70	130	30
Trichloroethene	ND	0.20	10	9.82	98	9.18	92	6.7	70	130	30
Toluene	ND	0.20	10	9.38	94	8.96	90	4.6	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	9.55	95	9.64	96	0.9	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date:** 9/27/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/04/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T090401-01		T090401-02		T090401-03		T090401-04	
Client Sample I.D.:	CV-113		CV-99		CV-1535		CV-2007	
Date/Time Sampled:	9/4/26 7:00		9/4/26 7:05		9/4/26 7:22		9/4/26 7:48	
Date/Time Analyzed:	9/4/26 18:45		9/4/26 18:59		9/4/26 19:14		9/4/26 19:28	
QC Batch No.:	260904GC8A2		260904GC8A2		260904GC8A2		260904GC8A2	
Analyst Initials:	MJ		MJ		MJ		MJ	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	37	10	900	10	2,800	10	470	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 9/7/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/04/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T090401-05		T090401-06		T090401-08		T090401-09	
Client Sample I.D.:	CV-2314		CV-2315		CV-114		H-2273W	
Date/Time Sampled:	9/4/26 7:56		9/4/26 8:04		9/4/26 8:22		9/4/26 8:32	
Date/Time Analyzed:	9/4/26 19:43		9/4/26 19:58		9/4/26 20:27		9/4/26 20:41	
QC Batch No.:	260904GC8A2		260904GC8A2		260904GC8A2		260904GC8A2	
Analyst Initials:	MJ		MJ		MJ		MJ	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	2,700	10	2,200	10	2,200	10	160	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 09/27/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260904GC8A2
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	9/4/26 13:28			9/4/26 12:30		9/4/26 12:45					
Analyst Initials:	MJ			MJ		MJ					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	980	97	978	97	0.1	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 9/7/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/04/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090401-01			T090401-02			T090401-03			T090401-04		
Client Sample I.D.:	CV-113			CV-99			CV-1535			CV-2007		
Date/Time Sampled:	9/4/26 7:00			9/4/26 7:05			9/4/26 7:22			9/4/26 7:48		
Date/Time Analyzed:	9/4/26 18:45			9/4/26 18:59			9/4/26 19:14			9/4/26 19:28		
QC Batch No.:	260904GC8A2			260904GC8A2			260904GC8A2			260904GC8A2		
Analyst Initials:	MJ			MJ			MJ			MJ		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	**Result % v/v**	**RL % v/v**	**MDL % v/v**	**Result % v/v**	**RL % v/v**	**MDL % v/v**	**Result % v/v**	**RL % v/v**	**MDL % v/v**	**Result % v/v**	**RL % v/v**	**MDL % v/v**
Hydrogen	ND	1.0	0.059	6.4	1.0	0.059	18	1.0	0.059	6.2	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 9/7/26
Yunika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/04/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090401-05			T090401-06			T090401-08			T090401-09		
Client Sample I.D.:	CV-2314			CV-2315			CV-114			H-2273W		
Date/Time Sampled:	9/4/26 7:56			9/4/26 8:04			9/4/26 8:22			9/4/26 8:32		
Date/Time Analyzed:	9/4/26 19:43			9/4/26 19:58			9/4/26 20:27			9/4/26 20:41		
QC Batch No.:	260904GC8A2			260904GC8A2			260904GC8A2			260904GC8A2		
Analyst Initials:	MJ			MJ			MJ			MJ		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	13	1.0	0.059	17	1.0	0.059	18	1.0	0.059	1.8	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 9/27/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260904GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	9/4/26 13:28				9/4/26 12:30		9/4/26 12:45					
Analyst Initials:	MJ				MJ		MJ					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	4.31	87	4.34	87	0.7	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 9/7/26

Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/04/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090401-01		T090401-02		T090401-03		T090401-04	
Client Sample I.D.:	CV-113		CV-99		CV-1535		CV-2007	
Date/Time Sampled:	9/4/26 7:00		9/4/26 7:05		9/4/26 7:22		9/4/26 7:48	
Date/Time Analyzed:	9/4/26 18:45		9/4/26 18:59		9/4/26 19:14		9/4/26 19:28	
QC Batch No.:	260904GC8A2		260904GC8A2		260904GC8A2		260904GC8A2	
Analyst Initials:	MJ		MJ		MJ		MJ	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	40	0.010	43	0.010	74	0.010	47	0.010
Oxygen/Argon	2.9	0.50	6.6	0.50	1.0	0.50	0.78	0.50
Nitrogen	21	1.0	28	1.0	3.9	1.0	20	1.0
Methane	35	0.0010	15	0.0010	1.8	0.0010	25	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 9/7/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/04/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090401-05		T090401-06		T090401-07		T090401-08	
Client Sample I.D.:	CV-2314		CV-2315		CV-24084		CV-114	
Date/Time Sampled:	9/4/26 7:56		9/4/26 8:04		9/4/26 8:11		9/4/26 8:22	
Date/Time Analyzed:	9/4/26 19:43		9/4/26 19:58		9/4/26 20:12		9/4/26 20:27	
QC Batch No.:	260904GC8A2		260904GC8A2		260904GC8A2		260904GC8A2	
Analyst Initials:	MJ		MJ		MJ		MJ	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	78	0.010	76	0.010	81	0.010	76	0.010
Oxygen/Argon	1.00	0.50	0.73	0.50	0.57	0.50	0.69	0.50
Nitrogen	4.6	1.0	2.9	1.0	2.1	1.0	2.6	1.0
Methane	2.1	0.0010	1.7	0.0010	1.2	0.0010	0.92	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 9/7/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/04/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	**T090401-09**							
Client Sample I.D.:	**H-2273W**							
Date/Time Sampled:	**9/4/26 8:32**							
Date/Time Analyzed:	**9/4/26 20:41**							
QC Batch No.:	**260904GC8A2**							
Analyst Initials:	**MJ**							
Dilution Factor:	**1.0**							
ANALYTE	**Result % v/v**	**RL % v/v**						
Carbon Dioxide	**39**	0.010						
Oxygen/Argon	**2.3**	0.50						
Nitrogen	**34**	1.0						
Methane	**23**	0.0010						

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 9/27/26

Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260904GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	9/4/26 13:28			9/4/26 12:30		9/4/26 12:45					
Analyst Initials:	MJ			MJ		MJ					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	8.96	89	8.97	90	0.1	70	130	30
Oxygen/Argon	ND	0.50	15	14.7	98	14.7	98	0.0	70	130	30
Nitrogen	ND	1.0	70	70.2	101	70.2	101	0.0	70	130	30
Methane	ND	0.0010	0.10	0.100	99	0.100	99	0.0	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 9/7/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

SGS

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175
TX Cert T104704450-14-6
EPA Methods TO14A, TO15
ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

September 29, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T090801-01/10

Enclosed are the results for sample(s) received 9/8/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags. Quadratic regression calibration was required for ethyl acetate, tetrahydrofuran, cyclohexane, and 1,4-dioxane.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Zain Khan, Art Jones and Ali Ferrara on 9/28/26.

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Annika Sotelo-Sanchez
Lab Manager
Annika.sotelo-sanchez@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME
Standard ■ 48 hours ☐
Same Day ☐ 72 hours ☐
24 hours ☐ 96 hours ☐
Other:

DELIVERABLES
EDD ■
EDF ☐
Level 3 ☐
Level 4 ☐

PAGE: 1 OF

Condition upon receipt:
Sealed Yes ☐ No ☐
Intact Yes ☐ No ☐
Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING
P.O. No.:
Bill to:
07FSAccountspayable@scsengineers.com
3900 Kilroy Airport Way, Suite 300
Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T090801-01	CV-24069	09/08/26	7:00AM	1L	Gas	N	X	X	X			
-02	CV-24070	09/08/26	7:10AM	1L	Gas	N	X	X	X			
-03	CV-24071	09/08/26	7:15AM	1L	Gas	N	X	X	X			
-04	CV-24102	09/08/26	7:25AM	1L	Gas	N	X					
-05	CV-24101	09/08/26	7:30AM	2-1L	Gas	N	X	X	X	X		
-06	CV-24100	09/08/26	7:35AM	1L	Gas	N	X	X	X			
-07	CV-24053	09/08/26	7:40AM	2-1L	Gas	N	X	X	X	X		
-08	CV-24065	09/08/26	7:50AM	2-1L	Gas	N	X	X	X	X		
-09	CV-24127	09/08/26	8:00AM	2-1L	Gas	N	X	X	X	X		
-10	CV-24122	09/08/26	8:20AM	2-1L	Gas	N	X	X	X	X		

AUTHORIZATION TO PERFORM WORK	COMPANY SCS	DATE/TIME 9-8-26 9:08A	
SAMPLED BY	COMPANY SCS	DATE/TIME 9-8-26 9:08A	
RELINQUISHED BY	DATE/TIME 9-8-26 9:08A	RECEIVED BY	DATE/TIME 9-8-26 9:08am
RELINQUISHED BY	DATE/TIME 9-8-26 9:25am	RECEIVED BY	DATE/TIME 9/8/26 9:25am
RELINQUISHED BY	DATE/TIME 9/8/26 11:47	RECEIVED BY	DATE/TIME 9/8/26 11:47

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: H=HCl N=None / Container: B=Bag C=Can V=VOA O=Other

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T090801-01		T090801-07		T090801-08		T090801-09	
Client Sample I.D.:	CV-24069		CV-24053		CV-24065		CV-24127	
Date/Time Sampled:	9/8/26 7:00		9/8/26 7:40		9/8/26 7:50		9/8/26 8:00	
Date/Time Analyzed:	9/8/26 16:23		9/8/26 17:01		9/8/26 17:39		9/8/26 18:17	
QC Batch No.:	260908MS2A1		260908MS2A1		260908MS2A1		260908MS2A1	
Analyst Initials:	VM		VM		VM		VM	
Dilution Factor:	500		1,000		800		12,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	500	ND	1,000	ND	800	ND	12,000
Chloromethane	ND	500	ND	1,000	ND	800	29,000	12,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	500	ND	1,000	ND	800	ND	12,000
Vinyl Chloride	ND	500	ND	1,000	ND	800	ND	12,000
Bromomethane	ND	500	ND	1,000	ND	800	ND	12,000
Chloroethane	ND	500	ND	1,000	ND	800	ND	12,000
Trichlorofluoromethane (11)	ND	500	ND	1,000	ND	800	ND	12,000
1,1-Dichloroethene	ND	500	ND	1,000	ND	800	ND	12,000
Carbon Disulfide	520	500	1,200	1,000	1,100	800	ND	12,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	500	ND	1,000	ND	800	ND	12,000
Acetone	47,000	500	120,000	1,000	93,000	800	1,200,000	12,000
Methylene Chloride	ND	500	ND	1,000	ND	800	ND	12,000
t-1,2-Dichloroethene	ND	500	ND	1,000	ND	800	ND	12,000
1,1-Dichloroethane	ND	500	ND	1,000	ND	800	ND	12,000
Vinyl Acetate	ND	500	ND	1,000	ND	800	ND	12,000
c-1,2-Dichloroethene	ND	500	ND	1,000	ND	800	ND	12,000
2-Butanone	42,000	1,000	120,000	2,000	87,000	1,600	760,000	24,000
t-Butyl Methyl Ether (MTBE)	ND	500	ND	1,000	ND	800	ND	12,000
Chloroform	ND	500	ND	1,000	ND	800	ND	12,000
1,1,1-Trichloroethane	ND	500	ND	1,000	ND	800	ND	12,000
Carbon Tetrachloride	ND	500	ND	1,000	ND	800	ND	12,000
Benzene	8,900	500	71,000	1,000	67,000	800	220,000	12,000
1,2-Dichloroethane	ND	500	ND	1,000	ND	800	ND	12,000
Trichloroethene	ND	500	ND	1,000	ND	800	ND	12,000
1,2-Dichloropropane	ND	500	ND	1,000	ND	800	ND	12,000
Bromodichloromethane	ND	500	ND	1,000	ND	800	ND	12,000
c-1,3-Dichloropropene	ND	500	ND	1,000	ND	800	ND	12,000
4-Methyl-2-Pentanone	1,100	500	2,400	1,000	2,600	800	ND	12,000
Toluene	880	500	3,600	1,000	3,700	800	ND	12,000
t-1,3-Dichloropropene	ND	500	ND	1,000	ND	800	ND	12,000
1,1,2-Trichloroethane	ND	500	ND	1,000	ND	800	ND	12,000
Tetrachloroethene	ND	500	ND	1,000	ND	800	ND	12,000
2-Hexanone	ND	500	ND	1,000	ND	800	ND	12,000
Dibromochloromethane	ND	500	ND	1,000	ND	800	ND	12,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T090801-01		T090801-07		T090801-08		T090801-09	
Client Sample I.D.:	CV-24069		CV-24053		CV-24065		CV-24127	
Date/Time Sampled:	9/8/26 7:00		9/8/26 7:40		9/8/26 7:50		9/8/26 8:00	
Date/Time Analyzed:	9/8/26 16:23		9/8/26 17:01		9/8/26 17:39		9/8/26 18:17	
QC Batch No.:	260908MS2A1		260908MS2A1		260908MS2A1		260908MS2A1	
Analyst Initials:	VM		VM		VM		VM	
Dilution Factor:	500		1,000		800		12,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	500	ND	1,000	ND	800	ND	12,000
Chlorobenzene	ND	500	ND	1,000	ND	800	ND	12,000
Ethylbenzene	ND	500	ND	1,000	ND	800	ND	12,000
p,&m-Xylene	ND	500	ND	1,000	ND	800	ND	12,000
o-Xylene	ND	500	ND	1,000	ND	800	ND	12,000
Styrene	ND	500	ND	1,000	ND	800	ND	12,000
Bromoform	ND	500	ND	1,000	ND	800	ND	12,000
1,1,2,2-Tetrachloroethane	ND	500	ND	1,000	ND	800	ND	12,000
Benzyl Chloride	ND	500	ND	1,000	ND	800	ND	12,000
4-Ethyl Toluene	ND	500	ND	1,000	ND	800	ND	12,000
1,3,5-Trimethylbenzene	ND	500	ND	1,000	ND	800	ND	12,000
1,2,4-Trimethylbenzene	ND	500	ND	1,000	ND	800	ND	12,000
1,3-Dichlorobenzene	ND	500	ND	1,000	ND	800	ND	12,000
1,4-Dichlorobenzene	ND	500	ND	1,000	ND	800	ND	12,000
1,2-Dichlorobenzene	ND	500	ND	1,000	ND	800	ND	12,000
1,2,4-Trichlorobenzene	ND	500	ND	1,000	ND	800	ND	12,000
Hexachlorobutadiene	ND	500	ND	1,000	ND	800	ND	12,000
1,3-Butadiene	ND	2,500	ND	5,000	ND	4,000	ND	60,000
Isopropanol	90,000	2,500	120,000	5,000	89,000	4,000	210,000	60,000
n-Hexane	4,700	2,500	ND	5,000	4,200	4,000	ND	60,000
Ethyl Acetate	2,700	2,500	5,100	5,000	ND	4,000	ND	60,000
Tetrahydrofuran	19,000	2,500	91,000	5,000	62,000	4,000	360,000	60,000
Cyclohexane	ND	2,500	ND	5,000	ND	4,000	ND	60,000
Heptane	ND	2,500	ND	5,000	ND	4,000	ND	60,000
1,4-Dioxane	ND	2,500	ND	5,000	ND	4,000	ND	60,000

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 9/23/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T090801-10
Client Sample I.D.:	CV-24122
Date/Time Sampled:	9/8/26 8:20
Date/Time Analyzed:	9/8/26 18:56
QC Batch No.:	260908MS2A1
Analyst Initials:	VM
Dilution Factor:	2,500

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	2,500
Chloromethane	ND	2,500
1,2-Cl-1,1,2,2-F ethane (114)	ND	2,500
Vinyl Chloride	ND	2,500
Bromomethane	ND	2,500
Chloroethane	ND	2,500
Trichlorofluoromethane (11)	ND	2,500
1,1-Dichloroethene	ND	2,500
Carbon Disulfide	ND	2,500
1,1,2-Cl 1,2,2-F ethane (113)	ND	2,500
Acetone	230,000	2,500
Methylene Chloride	ND	2,500
t-1,2-Dichloroethene	ND	2,500
1,1-Dichloroethane	ND	2,500
Vinyl Acetate	ND	2,500
c-1,2-Dichloroethene	ND	2,500
2-Butanone	120,000	5,000
t-Butyl Methyl Ether (MTBE)	ND	2,500
Chloroform	ND	2,500
1,1,1-Trichloroethane	ND	2,500
Carbon Tetrachloride	ND	2,500
Benzene	17,000	2,500
1,2-Dichloroethane	ND	2,500
Trichloroethene	ND	2,500
1,2-Dichloropropane	ND	2,500
Bromodichloromethane	ND	2,500
c-1,3-Dichloropropene	ND	2,500
4-Methyl-2-Pentanone	ND	2,500
Toluene	ND	2,500
t-1,3-Dichloropropene	ND	2,500
1,1,2-Trichloroethane	ND	2,500
Tetrachloroethene	ND	2,500
2-Hexanone	ND	2,500
Dibromochloromethane	ND	2,500

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T090801-10
Client Sample I.D.:	CV-24122
Date/Time Sampled:	9/8/26 8:20
Date/Time Analyzed:	9/8/26 18:56
QC Batch No.:	260908MS2A1
Analyst Initials:	VM
Dilution Factor:	2,500

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	2,500
Chlorobenzene	ND	2,500
Ethylbenzene	ND	2,500
p,&m-Xylene	ND	2,500
o-Xylene	ND	2,500
Styrene	ND	2,500
Bromoform	ND	2,500
1,1,2,2-Tetrachloroethane	ND	2,500
Benzyl Chloride	ND	2,500
4-Ethyl Toluene	ND	2,500
1,3,5-Trimethylbenzene	ND	2,500
1,2,4-Trimethylbenzene	ND	2,500
1,3-Dichlorobenzene	ND	2,500
1,4-Dichlorobenzene	ND	2,500
1,2-Dichlorobenzene	ND	2,500
1,2,4-Trichlorobenzene	ND	2,500
Hexachlorobutadiene	ND	2,500
1,3-Butadiene	ND	13,000
Isopropanol	97,000	13,000
n-Hexane	ND	13,000
Ethyl Acetate	ND	13,000
Tetrahydrofuran	40,000	13,000
Cyclohexane	ND	13,000
Heptane	ND	13,000
1,4-Dioxane	ND	13,000

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 9/27/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK							
Client Sample I.D.:	-							
Date/Time Sampled:	-							
Date/Time Analyzed:	9/8/26 15:45							
QC Batch No.:	260908MS2A1							
Analyst Initials:	VM							
Dilution Factor:	0.20							

ANALYTE	Result ppbv	RL ppbv						
Dichlorodifluoromethane (12)	ND	0.20						
Chloromethane	ND	0.20						
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20						
Vinyl Chloride	ND	0.20						
Bromomethane	ND	0.20						
Chloroethane	ND	0.20						
Trichlorofluoromethane (11)	ND	0.20						
1,1-Dichloroethene	ND	0.20						
Carbon Disulfide	ND	0.20						
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20						
Acetone	ND	0.20						
Methylene Chloride	ND	0.20						
t-1,2-Dichloroethene	ND	0.20						
1,1-Dichloroethane	ND	0.20						
Vinyl Acetate	ND	0.20						
c-1,2-Dichloroethene	ND	0.20						
2-Butanone	ND	0.40						
t-Butyl Methyl Ether (MTBE)	ND	0.20						
Chloroform	ND	0.20						
1,1,1-Trichloroethane	ND	0.20						
Carbon Tetrachloride	ND	0.20						
Benzene	ND	0.20						
1,2-Dichloroethane	ND	0.20						
Trichloroethene	ND	0.20						
1,2-Dichloropropane	ND	0.20						
Bromodichloromethane	ND	0.20						
c-1,3-Dichloropropene	ND	0.20						
4-Methyl-2-Pentanone	ND	0.20						
Toluene	ND	0.20						
t-1,3-Dichloropropene	ND	0.20						
1,1,2-Trichloroethane	ND	0.20						
Tetrachloroethene	ND	0.20						
2-Hexanone	ND	0.20						
Dibromochloromethane	ND	0.20						

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK							
Client Sample I.D.:	-							
Date/Time Sampled:	-							
Date/Time Analyzed:	9/8/26 15:45							
QC Batch No.:	260908MS2A1							
Analyst Initials:	VM							
Dilution Factor:	0.20							
ANALYTE	**Result ppbv**	**RL ppbv**						
1,2-Dibromoethane	ND	0.20						
Chlorobenzene	ND	0.20						
Ethylbenzene	ND	0.20						
p,&m-Xylene	ND	0.20						
o-Xylene	ND	0.20						
Styrene	ND	0.20						
Bromoform	ND	0.20						
1,1,2,2-Tetrachloroethane	ND	0.20						
Benzyl Chloride	ND	0.20						
4-Ethyl Toluene	ND	0.20						
1,3,5-Trimethylbenzene	ND	0.20						
1,2,4-Trimethylbenzene	ND	0.20						
1,3-Dichlorobenzene	ND	0.20						
1,4-Dichlorobenzene	ND	0.20						
1,2-Dichlorobenzene	ND	0.20						
1,2,4-Trichlorobenzene	ND	0.20						
Hexachlorobutadiene	ND	0.20						
1,3-Butadiene	ND	1.0						
Isopropanol	ND	1.0						
n-Hexane	ND	1.0						
Ethyl Acetate	ND	1.0						
Tetrahydrofuran	ND	1.0						
Cyclohexane	ND	1.0						
Heptane	ND	1.0						
1,4-Dioxane	ND	1.0						

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 9/27/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 260908MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	9/8/26 15:45			9/8/26 14:28		9/8/26 15:06					
Analyst Initials:	VM			VM		VM					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	**Result ppbv**	**RL ppbv**	**AMT. ppbv**	**Result ppbv**	**% Rec.**	**Result ppbv**	**% Rec.**	**RPD**	**Low %Rec**	**High %Rec**	**Max. RPD**
1,1-Dichloroethene	ND	0.20	10	11.5	115	11.7	117	1.5	70	130	30
Methylene Chloride	ND	0.20	10	10.6	106	10.8	108	2.3	70	130	30
Trichloroethene	ND	0.20	10	9.61	96	9.47	95	1.5	70	130	30
Toluene	ND	0.20	10	9.69	97	9.91	99	2.2	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	10.6	106	9.67	97	8.8	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ for Date: 9/27/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T090801-01		T090801-02		T090801-03		T090801-05	
Client Sample I.D.:	CV-24069		CV-24070		CV-24071		CV-24101	
Date/Time Sampled:	9/8/26 7:00		9/8/26 7:10		9/8/26 7:15		9/8/26 7:30	
Date/Time Analyzed:	9/8/26 19:47		9/8/26 20:01		9/8/26 20:16		9/8/26 20:45	
QC Batch No.:	260908GC8A2		260908GC8A2		260908GC8A2		260908GC8A2	
Analyst Initials:	MJ		MJ		MJ		MJ	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	580	10	1,000	10	550	10	ND	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 9/15/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T090801-06		T090801-07		T090801-08		T090801-09	
Client Sample I.D.:	CV-24100		CV-24053		CV-24065		CV-24127	
Date/Time Sampled:	9/8/26 7:35		9/8/26 7:40		9/8/26 7:50		9/8/26 8:00	
Date/Time Analyzed:	9/8/26 20:59		9/8/26 21:14		9/8/26 21:28		9/8/26 21:43	
QC Batch No.:	260908GC8A2		260908GC8A2		260908GC8A2		260908GC8A2	
Analyst Initials:	MJ		MJ		MJ		MJ	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	38	10	58	10	290	10	2,600	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 9/25/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T090801-10						
Client Sample I.D.:	CV-24122						
Date/Time Sampled:	9/8/26 8:20						
Date/Time Analyzed:	9/8/26 21:57						
QC Batch No.:	260908GC8A2						
Analyst Initials:	MJ						
Dilution Factor:	1.0						
ANALYTE	Result ppmv	RL ppmv					
Carbon Monoxide	200	10					

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 9/10/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260908GC8A2
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	9/8/26 19:32			9/8/26 18:34		9/8/26 18:48					
Analyst Initials:	MJ			MJ		MJ					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,000	99	981	97	2.4	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 9/25/26

Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090801-01			T090801-02			T090801-03			T090801-05		
Client Sample I.D.:	CV-24069			CV-24070			CV-24071			CV-24101		
Date/Time Sampled:	9/8/26 7:00			9/8/26 7:10			9/8/26 7:15			9/8/26 7:30		
Date/Time Analyzed:	9/8/26 19:47			9/8/26 20:01			9/8/26 20:16			9/8/26 20:45		
QC Batch No.:	260908GC8A2			260908GC8A2			260908GC8A2			260908GC8A2		
Analyst Initials:	MJ			MJ			MJ			MJ		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	6.4	1.0	0.059	8.2	1.0	0.059	7.4	1.0	0.059	0.12 J	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 9/15/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090801-06			T090801-07			T090801-08			T090801-09		
Client Sample I.D.:	CV-24100			CV-24053			CV-24065			CV-24127		
Date/Time Sampled:	9/8/26 7:35			9/8/26 7:40			9/8/26 7:50			9/8/26 8:00		
Date/Time Analyzed:	9/8/26 20:59			9/8/26 21:14			9/8/26 21:28			9/8/26 21:43		
QC Batch No.:	260908GC8A2			260908GC8A2			260908GC8A2			260908GC8A2		
Analyst Initials:	MJ			MJ			MJ			MJ		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	0.63 J	1.0	0.059	0.88 J	1.0	0.059	1.5	1.0	0.059	18	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 9/8/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090801-10		
Client Sample I.D.:	CV-24122		
Date/Time Sampled:	9/8/26 8:20		
Date/Time Analyzed:	9/8/26 21:57		
QC Batch No.:	260908GC8A2		
Analyst Initials:	MJ		
Dilution Factor:	1.0		

ANALYTE	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	1.5	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 9/5/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260908GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	9/8/26 19:32				9/8/26 18:34		9/8/26 18:48					
Analyst Initials:	MJ				MJ		MJ					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	5.75	116	5.76	116	0.2	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 9/15/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090801-01		T090801-02		T090801-03		T090801-04	
Client Sample I.D.:	CV-24069		CV-24070		CV-24071		CV-24102	
Date/Time Sampled:	9/8/26 7:00		9/8/26 7:10		9/8/26 7:15		9/8/26 7:25	
Date/Time Analyzed:	9/8/26 19:47		9/8/26 20:01		9/8/26 20:16		9/8/26 20:30	
QC Batch No.:	260908GC8A2		260908GC8A2		260908GC8A2		260908GC8A2	
Analyst Initials:	MJ		MJ		MJ		MJ	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	47	0.010	72	0.010	59	0.010	52	0.010
Oxygen/Argon	2.4	0.50	0.59	0.50	ND	0.50	0.66	0.50
Nitrogen	24	1.0	2.9	1.0	2.0	1.0	3.7	1.0
Methane	20	0.0010	15	0.0010	31	0.0010	43	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 9/15/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090801-05		T090801-06		T090801-07		T090801-08	
Client Sample I.D.:	CV-24101		CV-24100		CV-24053		CV-24065	
Date/Time Sampled:	9/8/26 7:30		9/8/26 7:35		9/8/26 7:40		9/8/26 7:50	
Date/Time Analyzed:	9/8/26 20:45		9/8/26 20:59		9/8/26 21:14		9/8/26 21:28	
QC Batch No.:	260908GC8A2		260908GC8A2		260908GC8A2		260908GC8A2	
Analyst Initials:	MJ		MJ		MJ		MJ	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	43	0.010	75	0.010	46	0.010	44	0.010
Oxygen/Argon	4.6	0.50	0.71	0.50	0.88	0.50	5.1	0.50
Nitrogen	17	1.0	2.6	1.0	20	1.0	36	1.0
Methane	35	0.0010	20	0.0010	32	0.0010	13	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 9/25/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/08/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090801-09		T090801-10					
Client Sample I.D.:	CV-24127		CV-24122					
Date/Time Sampled:	9/8/26 8:00		9/8/26 8:20					
Date/Time Analyzed:	9/8/26 21:43		9/8/26 21:57					
QC Batch No.:	260908GC8A2		260908GC8A2					
Analyst Initials:	MJ		MJ					
Dilution Factor:	1.0		1.0					
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**				
Carbon Dioxide	74	0.010	44	0.010				
Oxygen/Argon	0.82	0.50	1.4	0.50				
Nitrogen	3.7	1.0	5.6	1.0				
Methane	1.4	0.0010	47	0.0010				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 9/25/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260908GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	9/8/26 19:32			9/8/26 18:34		9/8/26 18:48					
Analyst Initials:	MJ			MJ		MJ					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	10.3	103	10.3	103	0.1	70	130	30
Oxygen/Argon	ND	0.50	15	14.5	96	14.5	96	0.1	70	130	30
Nitrogen	ND	1.0	70	70.5	101	70.6	101	0.1	70	130	30
Methane	ND	0.0010	0.10	0.0929	92	0.0910	90	2.2	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 9/5/26

Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

SGS

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175
TX Cert T104704450-14-6
EPA Methods TO14A, TO15
ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

September 29, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T090904-01/10

Enclosed are the results for sample(s) received 9/9/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags. Quadratic regression calibration was required for ethyl acetate, tetrahydrofuran, cyclohexane, and 1,4-dioxane.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Zain Khan, Art Jones and Ali Ferrara on 9/28/26.

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Annika Sotelo-Sanchez
Lab Manager
Annika.sotelo-sanchez@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐ No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐ No ☐
Other:				Level 4	☐	Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:	
Bill to:	
	07FSAccountspayable@scsengineers.com
	3900 Kilroy Airport Way, Suite 300
	Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T090904-01	H-2165W	09/09/26	7:00AM	2-1L	Gas	N	X	X	X	X		
-02	H-2273W	09/09/26	7:10AM	2-1L	Gas	N	X	X	X	X		
-03	CV-2001	09/09/26	7:20AM	2-1L	Gas	N	X	X	X	X		
-04	CV-2002	09/09/26	7:25AM	2-1L	Gas	N	X	X	X	X		
-05	CV-24017	09/09/26	7:35AM	2-1L	Gas	N	X	X	X	X		
-06	CV-2328	09/09/26	7:45AM	1L	Gas	N	X	X	X			
-07	CV-24126	09/09/26	7:55AM	1L	Gas	N	X					
-08	CV-2305	09/09/26	8:05AM	1L	Gas	N	X	X	X			
-09	CV-24120	09/09/26	8:10AM	1L	Gas	N	X	X	X			
-10	CV-24125	09/09/26	8:20AM	1L	Gas	N	X	X	X			

AUTHORIZATION TO PERFORM WORK: EM	COMPANY: SCS	DATE/TIME: 9.9.26 9:20am	
SAMPLED BY: EM	COMPANY: SCS	DATE/TIME: 9.9.26 9:20am	
RELINQUISHED BY: EM	DATE/TIME: 9.9.26 9:28am	RECEIVED BY: Fabian G	DATE/TIME: 9/9/26 9:28Am
RELINQUISHED BY: Fabian G	DATE/TIME: 9/9/26 12:00	RECEIVED BY: [illegible]	DATE/TIME: 9/9/26 12:00
RELINQUISHED BY:	DATE/TIME:	RECEIVED BY:	DATE/TIME:

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/09/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T090904-01		T090904-02		T090904-03		T090904-04	
Client Sample I.D.:	H-2165W		H-2273W		CV-2001		CV-2002	
Date/Time Sampled:	9/9/26 7:00		9/9/26 7:10		9/9/26 7:20		9/9/26 7:25	
Date/Time Analyzed:	9/9/26 14:31		9/9/26 15:15		9/9/26 15:53		9/9/26 16:30	
QC Batch No.:	260909MS2A1		260909MS2A1		260909MS2A1		260909MS2A1	
Analyst Initials:	VM		VM		VM		VM	
Dilution Factor:	4,000		1,800		400		5,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	4,000	ND	1,800	ND	400	ND	5,000
Chloromethane	ND	4,000	ND	1,800	ND	400	ND	5,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	4,000	ND	1,800	ND	400	ND	5,000
Vinyl Chloride	ND	4,000	ND	1,800	ND	400	ND	5,000
Bromomethane	ND	4,000	ND	1,800	ND	400	ND	5,000
Chloroethane	ND	4,000	ND	1,800	ND	400	ND	5,000
Trichlorofluoromethane (11)	ND	4,000	ND	1,800	ND	400	ND	5,000
1,1-Dichloroethene	ND	4,000	ND	1,800	ND	400	ND	5,000
Carbon Disulfide	ND	4,000	ND	1,800	450	400	ND	5,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	4,000	ND	1,800	ND	400	ND	5,000
Acetone	410,000	4,000	280,000	1,800	60,000	400	550,000	5,000
Methylene Chloride	ND	4,000	ND	1,800	ND	400	ND	5,000
t-1,2-Dichloroethene	ND	4,000	ND	1,800	ND	400	ND	5,000
1,1-Dichloroethane	ND	4,000	ND	1,800	ND	400	ND	5,000
Vinyl Acetate	ND	4,000	ND	1,800	520	400	ND	5,000
c-1,2-Dichloroethene	ND	4,000	ND	1,800	ND	400	ND	5,000
2-Butanone	300,000	8,000	200,000	3,600	59,000	800	310,000	10,000
t-Butyl Methyl Ether (MTBE)	ND	4,000	ND	1,800	1,200	400	ND	5,000
Chloroform	ND	4,000	ND	1,800	ND	400	ND	5,000
1,1,1-Trichloroethane	ND	4,000	ND	1,800	ND	400	ND	5,000
Carbon Tetrachloride	ND	4,000	ND	1,800	ND	400	ND	5,000
Benzene	240,000	4,000	64,000	1,800	59,000	400	130,000	5,000
1,2-Dichloroethane	ND	4,000	ND	1,800	ND	400	ND	5,000
Trichloroethene	ND	4,000	ND	1,800	ND	400	ND	5,000
1,2-Dichloropropane	ND	4,000	ND	1,800	ND	400	ND	5,000
Bromodichloromethane	ND	4,000	ND	1,800	ND	400	ND	5,000
c-1,3-Dichloropropene	ND	4,000	ND	1,800	ND	400	ND	5,000
4-Methyl-2-Pentanone	7,700	4,000	4,300	1,800	2,200	400	ND	5,000
Toluene	7,700	4,000	3,500	1,800	2,200	400	ND	5,000
t-1,3-Dichloropropene	ND	4,000	ND	1,800	ND	400	ND	5,000
1,1,2-Trichloroethane	ND	4,000	ND	1,800	ND	400	ND	5,000
Tetrachloroethene	ND	4,000	ND	1,800	ND	400	ND	5,000
2-Hexanone	ND	4,000	ND	1,800	430	400	ND	5,000
Dibromochloromethane	ND	4,000	ND	1,800	ND	400	ND	5,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/09/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T090904-01		T090904-02		T090904-03		T090904-04	
Client Sample I.D.:	H-2165W		H-2273W		CV-2001		CV-2002	
Date/Time Sampled:	9/9/26 7:00		9/9/26 7:10		9/9/26 7:20		9/9/26 7:25	
Date/Time Analyzed:	9/9/26 14:31		9/9/26 15:15		9/9/26 15:53		9/9/26 16:30	
QC Batch No.:	260909MS2A1		260909MS2A1		260909MS2A1		260909MS2A1	
Analyst Initials:	VM		VM		VM		VM	
Dilution Factor:	4,000		1,800		400		5,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	4,000	ND	1,800	ND	400	ND	5,000
Chlorobenzene	ND	4,000	ND	1,800	ND	400	ND	5,000
Ethylbenzene	ND	4,000	ND	1,800	ND	400	ND	5,000
p,&m-Xylene	ND	4,000	ND	1,800	ND	400	ND	5,000
o-Xylene	ND	4,000	ND	1,800	ND	400	ND	5,000
Styrene	ND	4,000	ND	1,800	ND	400	ND	5,000
Bromoform	ND	4,000	ND	1,800	ND	400	ND	5,000
1,1,2,2-Tetrachloroethane	ND	4,000	ND	1,800	ND	400	ND	5,000
Benzyl Chloride	ND	4,000	ND	1,800	ND	400	ND	5,000
4-Ethyl Toluene	ND	4,000	ND	1,800	ND	400	ND	5,000
1,3,5-Trimethylbenzene	ND	4,000	ND	1,800	ND	400	ND	5,000
1,2,4-Trimethylbenzene	ND	4,000	ND	1,800	ND	400	ND	5,000
1,3-Dichlorobenzene	ND	4,000	ND	1,800	ND	400	ND	5,000
1,4-Dichlorobenzene	ND	4,000	ND	1,800	ND	400	ND	5,000
1,2-Dichlorobenzene	ND	4,000	ND	1,800	ND	400	ND	5,000
1,2,4-Trichlorobenzene	ND	4,000	ND	1,800	ND	400	ND	5,000
Hexachlorobutadiene	ND	4,000	ND	1,800	ND	400	ND	5,000
1,3-Butadiene	ND	20,000	ND	9,000	4,600	2,000	ND	25,000
Isopropanol	96,000	20,000	160,000	9,000	100,000	2,000	200,000	25,000
n-Hexane	ND	20,000	ND	9,000	6,300	2,000	ND	25,000
Ethyl Acetate	ND	20,000	16,000	9,000	ND	2,000	ND	25,000
Tetrahydrofuran	270,000	20,000	150,000	9,000	70,000	2,000	240,000	25,000
Cyclohexane	ND	20,000	ND	9,000	ND	2,000	ND	25,000
Heptane	ND	20,000	ND	9,000	3,800	2,000	ND	25,000
1,4-Dioxane	ND	20,000	ND	9,000	ND	2,000	ND	25,000

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 9/27/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/09/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T090904-05
Client Sample I.D.:	CV-24017
Date/Time Sampled:	9/9/26 7:35
Date/Time Analyzed:	9/9/26 17:08
QC Batch No.:	260909MS2A1
Analyst Initials:	VM
Dilution Factor:	10,000

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	10,000
Chloromethane	ND	10,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	10,000
Vinyl Chloride	ND	10,000
Bromomethane	ND	10,000
Chloroethane	ND	10,000
Trichlorofluoromethane (11)	ND	10,000
1,1-Dichloroethene	ND	10,000
Carbon Disulfide	ND	10,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	10,000
Acetone	1,300,000	10,000
Methylene Chloride	ND	10,000
t-1,2-Dichloroethene	ND	10,000
1,1-Dichloroethane	ND	10,000
Vinyl Acetate	ND	10,000
c-1,2-Dichloroethene	ND	10,000
2-Butanone	800,000	20,000
t-Butyl Methyl Ether (MTBE)	ND	10,000
Chloroform	ND	10,000
1,1,1-Trichloroethane	ND	10,000
Carbon Tetrachloride	ND	10,000
Benzene	240,000	10,000
1,2-Dichloroethane	ND	10,000
Trichloroethene	ND	10,000
1,2-Dichloropropane	ND	10,000
Bromodichloromethane	ND	10,000
c-1,3-Dichloropropene	ND	10,000
4-Methyl-2-Pentanone	ND	10,000
Toluene	12,000	10,000
t-1,3-Dichloropropene	ND	10,000
1,1,2-Trichloroethane	ND	10,000
Tetrachloroethene	ND	10,000
2-Hexanone	ND	10,000
Dibromochloromethane	ND	10,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/09/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T090904-05
Client Sample I.D.:	CV-24017
Date/Time Sampled:	9/9/26 7:35
Date/Time Analyzed:	9/9/26 17:08
QC Batch No.:	260909MS2A1
Analyst Initials:	VM
Dilution Factor:	10,000

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	10,000
Chlorobenzene	ND	10,000
Ethylbenzene	ND	10,000
p,&m-Xylene	ND	10,000
o-Xylene	ND	10,000
Styrene	ND	10,000
Bromoform	ND	10,000
1,1,2,2-Tetrachloroethane	ND	10,000
Benzyl Chloride	ND	10,000
4-Ethyl Toluene	ND	10,000
1,3,5-Trimethylbenzene	ND	10,000
1,2,4-Trimethylbenzene	ND	10,000
1,3-Dichlorobenzene	ND	10,000
1,4-Dichlorobenzene	ND	10,000
1,2-Dichlorobenzene	ND	10,000
1,2,4-Trichlorobenzene	ND	10,000
Hexachlorobutadiene	ND	10,000
1,3-Butadiene	ND	50,000
Isopropanol	440,000	50,000
n-Hexane	ND	50,000
Ethyl Acetate	62,000	50,000
Tetrahydrofuran	650,000	50,000
Cyclohexane	ND	50,000
Heptane	ND	50,000
1,4-Dioxane	ND	50,000

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 9/17/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/09/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD-BLAN
Client Sample I.D.:	-
Date/Time Sampled:	-
Date/Time Analyzed:	9/9/26 11:47
QC Batch No.:	260909MS2A1
Analyst Initials:	VM
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	0.20
Chloromethane	ND	0.20
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20
Vinyl Chloride	ND	0.20
Bromomethane	ND	0.20
Chloroethane	ND	0.20
Trichlorofluoromethane (11)	ND	0.20
1,1-Dichloroethene	ND	0.20
Carbon Disulfide	ND	0.20
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20
Acetone	0.30	0.20
Methylene Chloride	ND	0.20
t-1,2-Dichloroethene	ND	0.20
1,1-Dichloroethane	ND	0.20
Vinyl Acetate	ND	0.20
c-1,2-Dichloroethene	ND	0.20
2-Butanone	ND	0.40
t-Butyl Methyl Ether (MTBE)	ND	0.20
Chloroform	ND	0.20
1,1,1-Trichloroethane	ND	0.20
Carbon Tetrachloride	ND	0.20
Benzene	ND	0.20
1,2-Dichloroethane	ND	0.20
Trichloroethene	ND	0.20
1,2-Dichloropropane	ND	0.20
Bromodichloromethane	ND	0.20
c-1,3-Dichloropropene	ND	0.20
4-Methyl-2-Pentanone	ND	0.20
Toluene	ND	0.20
t-1,3-Dichloropropene	ND	0.20
1,1,2-Trichloroethane	ND	0.20
Tetrachloroethene	ND	0.20
2-Hexanone	ND	0.20
Dibromochloromethane	ND	0.20

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/09/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD-BLAN
Client Sample I.D.:	-
Date/Time Sampled:	-
Date/Time Analyzed:	9/9/26 11:47
QC Batch No.:	260909MS2A1
Analyst Initials:	VM
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	0.20
Chlorobenzene	ND	0.20
Ethylbenzene	ND	0.20
p,&m-Xylene	ND	0.20
o-Xylene	ND	0.20
Styrene	ND	0.20
Bromoform	ND	0.20
1,1,2,2-Tetrachloroethane	ND	0.20
Benzyl Chloride	ND	0.20
4-Ethyl Toluene	ND	0.20
1,3,5-Trimethylbenzene	ND	0.20
1,2,4-Trimethylbenzene	ND	0.20
1,3-Dichlorobenzene	ND	0.20
1,4-Dichlorobenzene	ND	0.20
1,2-Dichlorobenzene	ND	0.20
1,2,4-Trichlorobenzene	ND	0.20
Hexachlorobutadiene	ND	0.20
1,3-Butadiene	ND	1.0
Isopropanol	ND	1.0
n-Hexane	ND	1.0
Ethyl Acetate	ND	1.0
Tetrahydrofuran	ND	1.0
Cyclohexane	ND	1.0
Heptane	ND	1.0
1,4-Dioxane	ND	1.0

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 9/26/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 260909MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	9/9/26 11:47			9/9/26 4:52		9/9/26 11:11					
Analyst Initials:	VM			VM		VM					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	**Result ppbv**	**RL ppbv**	**AMT. ppbv**	**Result ppbv**	**% Rec.**	**Result ppbv**	**% Rec.**	**RPD**	**Low %Rec**	**High %Rec**	**Max. RPD**
1,1-Dichloroethene	ND	0.20	10	11.3	113	10.8	108	4.0	70	130	30
Methylene Chloride	ND	0.20	10	10.4	104	10.3	103	1.2	70	130	30
Trichloroethene	ND	0.20	10	9.46	95	9.02	90	4.7	70	130	30
Toluene	ND	0.20	10	9.83	98	9.80	98	0.4	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	9.14	91	9.41	94	2.9	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date: 9/27/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/09/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T090904-01		T090904-02		T090904-03		T090904-04	
Client Sample I.D.:	H-2165W		H-2273W		CV-2001		CV-2002	
Date/Time Sampled:	9/9/26 7:00		9/9/26 7:10		9/9/26 7:20		9/9/26 7:25	
Date/Time Analyzed:	9/9/26 14:00		9/9/26 14:15		9/9/26 14:29		9/9/26 14:44	
QC Batch No.:	260909GC8A1		260909GC8A1		260909GC8A1		260909GC8A1	
Analyst Initials:	MJ		MJ		MJ		MJ	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	680	10	78	10	1,100	10	2,900	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 9/15/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/09/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T090904-05		T090904-06		T090904-08		T090904-09	
Client Sample I.D.:	CV-24017		CV-2328		CV-2305		CV-24120	
Date/Time Sampled:	9/9/26 7:35		9/9/26 7:45		9/9/26 8:05		9/9/26 8:10	
Date/Time Analyzed:	9/9/26 14:58		9/9/26 15:12		9/9/26 15:41		9/9/26 15:56	
QC Batch No.:	260909GC8A1		260909GC8A1		260909GC8A1		260909GC8A1	
Analyst Initials:	MJ		MJ		MJ		MJ	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	1,400	10	630	10	1,200	10	680	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 9/25/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/09/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T090904-10							
Client Sample I.D.:	CV-24125							
Date/Time Sampled:	9/9/26 8:20							
Date/Time Analyzed:	9/9/26 16:10							
QC Batch No.:	260909GC8A1							
Analyst Initials:	MJ							
Dilution Factor:	1.0							
ANALYTE	**Result ppmv**	**RL ppmv**						
Carbon Monoxide	ND	10						

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 9/25/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260909GC8A1
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	9/9/26 7:53			9/9/26 6:56		9/9/26 7:10					
Analyst Initials:	MJ			MJ		MJ					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,040	103	1,040	103	0.3	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 9/9/26

Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/09/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090904-01			T090904-02			T090904-03			T090904-04		
Client Sample I.D.:	H-2165W			H-2273W			CV-2001			CV-2002		
Date/Time Sampled:	9/9/26 7:00			9/9/26 7:10			9/9/26 7:20			9/9/26 7:25		
Date/Time Analyzed:	9/9/26 14:00			9/9/26 14:15			9/9/26 14:29			9/9/26 14:44		
QC Batch No.:	260909GC8A1			260909GC8A1			260909GC8A1			260909GC8A1		
Analyst Initials:	MJ			MJ			MJ			MJ		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	5.1	1.0	0.059	1.0	1.0	0.059	10	1.0	0.059	14	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____
Annika Sotelo-Sanchez
Lab Manager

Date 9/15/26

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/09/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090904-05			T090904-06			T090904-08			T090904-09		
Client Sample I.D.:	CV-24017			CV-2328			CV-2305			CV-24120		
Date/Time Sampled:	9/9/26 7:35			9/9/26 7:45			9/9/26 8:05			9/9/26 8:10		
Date/Time Analyzed:	9/9/26 14:58			9/9/26 15:12			9/9/26 15:41			9/9/26 15:56		
QC Batch No.:	260909GC8A1			260909GC8A1			260909GC8A1			260909GC8A1		
Analyst Initials:	MJ			MJ			MJ			MJ		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	16	1.0	0.059	6.2	1.0	0.059	4.7	1.0	0.059	4.2	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 9/25/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/09/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090904-10											
Client Sample I.D.:	CV-24125											
Date/Time Sampled:	9/9/26 8:20											
Date/Time Analyzed:	9/9/26 16:10											
QC Batch No.:	260909GC8A1											
Analyst Initials:	MJ											
Dilution Factor:	1.0											
ANALYTE	Result % v/v		RL % v/v	MDL % v/v								
Hydrogen	0.14	J	1.0	0.059								

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 9/25/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260909GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	9/9/26 7:53				9/9/26 6:56		9/9/26 7:10					
Analyst Initials:	MJ				MJ		MJ					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	5.42	109	5.36	108	1.1	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 9/9/26

Anjika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/09/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090904-01		T090904-02		T090904-03		T090904-04	
Client Sample I.D.:	H-2165W		H-2273W		CV-2001		CV-2002	
Date/Time Sampled:	9/9/26 7:00		9/9/26 7:10		9/9/26 7:20		9/9/26 7:25	
Date/Time Analyzed:	9/9/26 14:00		9/9/26 14:15		9/9/26 14:29		9/9/26 14:44	
QC Batch No.:	260909GC8A1		260909GC8A1		260909GC8A1		260909GC8A1	
Analyst Initials:	MJ		MJ		MJ		MJ	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	83	0.010	40	0.010	71	0.010	68	0.010
Oxygen/Argon	0.58	0.50	1.4	0.50	2.0	0.50	1.4	0.50
Nitrogen	2.2	1.0	36	1.0	8.4	1.0	5.2	1.0
Methane	7.9	0.0010	21	0.0010	7.0	0.0010	9.8	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 9/25/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/09/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090904-05		T090904-06		T090904-07		T090904-08	
Client Sample I.D.:	CV-24017		CV-2328		CV-24126		CV-2305	
Date/Time Sampled:	9/9/26 7:35		9/9/26 7:45		9/9/26 7:55		9/9/26 8:05	
Date/Time Analyzed:	9/9/26 14:58		9/9/26 15:12		9/9/26 15:27		9/9/26 15:41	
QC Batch No.:	260909GC8A1		260909GC8A1		260909GC8A1		260909GC8A1	
Analyst Initials:	MJ		MJ		MJ		MJ	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	65	0.010	55	0.010	39	0.010	49	0.010
Oxygen/Argon	1.9	0.50	1.2	0.50	3.2	0.50	2.5	0.50
Nitrogen	6.9	1.0	4.3	1.0	41	1.0	29	1.0
Methane	9.1	0.0010	32	0.0010	9.6	0.0010	14	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 9/25/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/09/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T090904-09		T090904-10					
Client Sample I.D.:	CV-24120		CV-24125					
Date/Time Sampled:	9/9/26 8:10		9/9/26 8:20					
Date/Time Analyzed:	9/9/26 15:56		9/9/26 16:10					
QC Batch No.:	260909GC8A1		260909GC8A1					
Analyst Initials:	MJ		MJ					
Dilution Factor:	1.0		1.0					
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**				
Carbon Dioxide	42	0.010	48	0.010				
Oxygen/Argon	10	0.50	2.4	0.50				
Nitrogen	38	1.0	9.2	1.0				
Methane	5.8	0.0010	40	0.0010				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 9/25/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260909GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	9/9/26 7:53			9/9/26 6:56		9/9/26 7:10					
Analyst Initials:	MJ			MJ		MJ					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	9.96	99	9.86	98	1.0	70	130	30
Oxygen/Argon	ND	0.50	15	14.5	96	14.5	97	0.1	70	130	30
Nitrogen	ND	1.0	70	70.1	100	70.0	100	0.2	70	130	30
Methane	ND	0.0010	0.10	0.0945	94	0.0951	94	0.7	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 9/25/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

SGS

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175
TX Cert T104704450-14-6
EPA Methods TO14A, TO15
ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

September 29, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T091005-01/13

Enclosed are the results for sample(s) received 9/10/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags. Quadratic regression calibration was required for ethyl acetate, tetrahydrofuran, cyclohexane, and 1,4-dioxane.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Zain Khan, Art Jones and Ali Ferrara on 9/28/26.

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Annika Sotelo-Sanchez
Lab Manager
Annika.sotelo-sanchez@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME
Standard ■ 48 hours ☐
Same Day ☐ 72 hours ☐
24 hours ☐ 96 hours ☐
Other:

DELIVERABLES
EDD ■
EDF ☐
Level 3 ☐
Level 4 ☐

PAGE: 1 OF 2

Condition upon receipt:
Sealed Yes ☐ No ☐
Intact Yes ☐ No ☐
Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING
P.O. No.:
Bill to: 07FSAccountspayable@scsengineers.com
3900 Kilroy Airport Way, Suite 300
Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
1091005-01	CV-24066	09/10/26	8:15am	1L	Gas	N	X	X	X			
-02	CV-24099	09/10/26	8:25am	1L	Gas	N	X					
-03	CV-24095	09/10/26	8:30am	2-1L	Gas	N	X	X	X	X		
-04	CV-2353	09/10/26	8:40am	1L	Gas	N	X	X	X			
-05	CV-2341	09/10/26	8:45am	1L	Gas	N	X	X	X			
-06	CV-2337	09/10/26	9:00am	1L	Gas	N	X	X	X			
-07	H-1770N	09/10/26	9:10am	2-1L	Gas	N	X	X	X	X		
-08	CV-24049	09/10/26	9:20am	1L	Gas	N	X	X	X			
-09	CV-24055	09/10/26	9:25am	1L	Gas	N	X	X	X			
-10	CV-24134	09/10/26	9:30am	1L	Gas	N	X					

AUTHORIZATION TO PERFORM WORK		COMPANY SCS	DATE/TIME 9.10.26 10:47am
SAMPLED BY		COMPANY SCS	DATE/TIME 9.10.26 10:47am
RELINQUISHED BY	DATE/TIME 9.10.26 10:47am	RECEIVED BY Kasandra Sanson	DATE/TIME 9.10.26 10:48.
RELINQUISHED BY Kasandra Sanson	DATE/TIME 9.10.26 10:48	RECEIVED BY Ruben G	DATE/TIME 9/10/26 11:22
RELINQUISHED BY Ruben G	DATE/TIME 9/10/26 12:33	RECEIVED BY	DATE/TIME 9/10/26 1233

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME: Standard ■ 48 hours ☐ | Same Day ☐ 72 hours ☐ | 24 hours ☐ 96 hours ☐ | Other:

DELIVERABLES: EDD ■ | EDF ☐ | Level 3 ☐ | Level 4 ☐

PAGE: 2 OF 2

Condition upon receipt: Sealed Yes ☐ No ☐ | Intact Yes ☐ No ☐ | Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:	
Bill to:	07FSAccountspayable@scsengineers.com
	3900 Kilroy Airport Way, Suite 300
	Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T091005-11	CV-24128	09/10/26	9:35am	1L	Gas	N	X	X	X			
-12	CV-24123	09/10/26	9:40am	1L	Gas	N	X					
-13	CV-24121	09/10/26	9:45am	1L	Gas	N	X	X	X			
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						
					Gas	N						

AUTHORIZATION TO PERFORM WORK: EM	COMPANY: SCS	DATE/TIME: 9.10.26 10:47am	
SAMPLED BY: EM	COMPANY: SCS	DATE/TIME: 9.10.26 10:47am	
RELINQUISHED BY: EM	DATE/TIME: 9.10.26 10:47am	RECEIVED BY: Kasandra Gonsalves	DATE/TIME: 9.10.26 10:48 AM
RELINQUISHED BY: Kasandra Gonsalves	DATE/TIME: 9.10.26 10:48am	RECEIVED BY: Ruben G	DATE/TIME: 9/10/26 11:22am
RELINQUISHED BY: Ruben G	DATE/TIME: 9/10/26 12:33	RECEIVED BY: [signature] 9/10/26	DATE/TIME: 1233

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/10/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T091005-03		T091005-07					
Client Sample I.D.:	CV-24095		H-1770N					
Date/Time Sampled:	9/10/26 8:30		9/10/26 9:10					
Date/Time Analyzed:	9/10/26 16:16		9/10/26 16:53					
QC Batch No.:	260910MS2A1		260910MS2A1					
Analyst Initials:	VM/GD		VM					
Dilution Factor:	13,000		2,400					
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv				
Dichlorodifluoromethane (12)	ND	13,000	ND	2,400				
Chloromethane	15,000	13,000	ND	2,400				
1,2-Cl-1,1,2,2-F ethane (114)	ND	13,000	ND	2,400				
Vinyl Chloride	ND	13,000	ND	2,400				
Bromomethane	ND	13,000	ND	2,400				
Chloroethane	ND	13,000	ND	2,400				
Trichlorofluoromethane (11)	ND	13,000	ND	2,400				
1,1-Dichloroethene	ND	13,000	ND	2,400				
Carbon Disulfide	23,000	13,000	ND	2,400				
1,1,2-Cl 1,2,2-F ethane (113)	ND	13,000	ND	2,400				
Acetone	1,100,000	13,000	210,000	2,400				
Methylene Chloride	ND	13,000	ND	2,400				
t-1,2-Dichloroethene	ND	13,000	ND	2,400				
1,1-Dichloroethane	ND	13,000	ND	2,400				
Vinyl Acetate	ND	13,000	ND	2,400				
c-1,2-Dichloroethene	ND	13,000	ND	2,400				
2-Butanone	500,000	26,000	130,000	4,800				
t-Butyl Methyl Ether (MTBE)	ND	13,000	ND	2,400				
Chloroform	ND	13,000	ND	2,400				
1,1,1-Trichloroethane	ND	13,000	ND	2,400				
Carbon Tetrachloride	ND	13,000	ND	2,400				
Benzene	120,000	13,000	99,000	2,400				
1,2-Dichloroethane	ND	13,000	ND	2,400				
Trichloroethene	ND	13,000	ND	2,400				
1,2-Dichloropropane	ND	13,000	ND	2,400				
Bromodichloromethane	ND	13,000	ND	2,400				
c-1,3-Dichloropropene	ND	13,000	ND	2,400				
4-Methyl-2-Pentanone	ND	13,000	ND	2,400				
Toluene	ND	13,000	3,500	2,400				
t-1,3-Dichloropropene	ND	13,000	ND	2,400				
1,1,2-Trichloroethane	ND	13,000	ND	2,400				
Tetrachloroethene	ND	13,000	ND	2,400				
2-Hexanone	ND	13,000	ND	2,400				
Dibromochloromethane	ND	13,000	ND	2,400				

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/10/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T091005-03		T091005-07					
Client Sample I.D.:	CV-24095		H-1770N					
Date/Time Sampled:	9/10/26 8:30		9/10/26 9:10					
Date/Time Analyzed:	9/10/26 16:16		9/10/26 16:53					
QC Batch No.:	260910MS2A1		260910MS2A1					
Analyst Initials:	VM/GD		VM					
Dilution Factor:	13,000		2,400					
ANALYTE	**Result ppbv**	**RL ppbv**	**Result ppbv**	**RL ppbv**				
1,2-Dibromoethane	ND	13,000	ND	2,400				
Chlorobenzene	ND	13,000	ND	2,400				
Ethylbenzene	ND	13,000	ND	2,400				
p,&m-Xylene	ND	13,000	ND	2,400				
o-Xylene	ND	13,000	ND	2,400				
Styrene	ND	13,000	ND	2,400				
Bromoform	ND	13,000	ND	2,400				
1,1,2,2-Tetrachloroethane	ND	13,000	ND	2,400				
Benzyl Chloride	ND	13,000	ND	2,400				
4-Ethyl Toluene	ND	13,000	ND	2,400				
1,3,5-Trimethylbenzene	ND	13,000	ND	2,400				
1,2,4-Trimethylbenzene	ND	13,000	ND	2,400				
1,3-Dichlorobenzene	ND	13,000	ND	2,400				
1,4-Dichlorobenzene	ND	13,000	ND	2,400				
1,2-Dichlorobenzene	ND	13,000	ND	2,400				
1,2,4-Trichlorobenzene	ND	13,000	ND	2,400				
Hexachlorobutadiene	ND	13,000	ND	2,400				
1,3-Butadiene	ND	65,000	ND	12,000				
Isopropanol	270,000	65,000	150,000	12,000				
n-Hexane	ND	65,000	12,000	12,000				
Ethyl Acetate	ND	65,000	ND	12,000				
Tetrahydrofuran	310,000	65,000	110,000	12,000				
Cyclohexane	ND	65,000	ND	12,000				
Heptane	ND	65,000	ND	12,000				
1,4-Dioxane	ND	65,000	ND	12,000				

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 9/27/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/10/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD-BLAN
Client Sample I.D.:	-
Date/Time Sampled:	-
Date/Time Analyzed:	9/10/26 13:10
QC Batch No.:	260910MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	0.20
Chloromethane	ND	0.20
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20
Vinyl Chloride	ND	0.20
Bromomethane	ND	0.20
Chloroethane	ND	0.20
Trichlorofluoromethane (11)	ND	0.20
1,1-Dichloroethene	ND	0.20
Carbon Disulfide	ND	0.20
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20
Acetone	0.30	0.20
Methylene Chloride	ND	0.20
t-1,2-Dichloroethene	ND	0.20
1,1-Dichloroethane	ND	0.20
Vinyl Acetate	ND	0.20
c-1,2-Dichloroethene	ND	0.20
2-Butanone	ND	0.40
t-Butyl Methyl Ether (MTBE)	ND	0.20
Chloroform	ND	0.20
1,1,1-Trichloroethane	ND	0.20
Carbon Tetrachloride	ND	0.20
Benzene	ND	0.20
1,2-Dichloroethane	ND	0.20
Trichloroethene	ND	0.20
1,2-Dichloropropane	ND	0.20
Bromodichloromethane	ND	0.20
c-1,3-Dichloropropene	ND	0.20
4-Methyl-2-Pentanone	ND	0.20
Toluene	ND	0.20
t-1,3-Dichloropropene	ND	0.20
1,1,2-Trichloroethane	ND	0.20
Tetrachloroethene	ND	0.20
2-Hexanone	ND	0.20
Dibromochloromethane	ND	0.20

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/10/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD-BLAN
Client Sample I.D.:	-
Date/Time Sampled:	-
Date/Time Analyzed:	9/10/26 13:10
QC Batch No.:	260910MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	0.20
Chlorobenzene	ND	0.20
Ethylbenzene	ND	0.20
p,&m-Xylene	ND	0.20
o-Xylene	ND	0.20
Styrene	ND	0.20
Bromoform	ND	0.20
1,1,2,2-Tetrachloroethane	ND	0.20
Benzyl Chloride	ND	0.20
4-Ethyl Toluene	ND	0.20
1,3,5-Trimethylbenzene	ND	0.20
1,2,4-Trimethylbenzene	ND	0.20
1,3-Dichlorobenzene	ND	0.20
1,4-Dichlorobenzene	ND	0.20
1,2-Dichlorobenzene	ND	0.20
1,2,4-Trichlorobenzene	ND	0.20
Hexachlorobutadiene	ND	0.20
1,3-Butadiene	ND	1.0
Isopropanol	ND	1.0
n-Hexane	ND	1.0
Ethyl Acetate	ND	1.0
Tetrahydrofuran	ND	1.0
Cyclohexane	ND	1.0
Heptane	ND	1.0
1,4-Dioxane	ND	1.0

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 9/26/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 260910MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	9/10/26 13:10			9/10/26 11:56		9/10/26 12:33					
Analyst Initials:	VM/GD			VM/GD		VM/GD					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	0.20	10	10.9	109	10.9	109	0.6	70	130	30
Methylene Chloride	ND	0.20	10	10.3	103	10.3	103	0.4	70	130	30
Trichloroethene	ND	0.20	10	8.75	88	9.49	95	8.0	70	130	30
Toluene	ND	0.20	10	9.48	95	9.73	97	2.6	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	9.41	94	9.38	94	0.3	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date: 9/27/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/10/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T091005-01			T091005-03			T091005-04			T091005-05		
Client Sample I.D.:	CV-24066			CV-24095			CV-2353			CV-2341		
Date/Time Sampled:	9/10/26 8:15			9/10/26 8:30			9/10/26 8:40			9/10/26 8:45		
Date/Time Analyzed:	9/10/26 14:12			9/10/26 14:41			9/10/26 15:16			9/10/26 15:30		
QC Batch No.:	260910GC8A1			260910GC8A1			260910GC8A1			260910GC8A1		
Analyst Initials:	MJ			MJ			MJ			MJ		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result ppmv	RL ppmv	MDL ppmv	Result ppmv	RL ppmv	MDL ppmv	Result ppmv	RL ppmv	MDL ppmv	Result ppmv	RL ppmv	MDL ppmv
Carbon Monoxide	250	10	0.030	2,200	10	0.030	560	10	0.030	1,500	10	0.030

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 9/27/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/10/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T091005-06			T091005-07			T091005-08			T091005-09		
Client Sample I.D.:	CV-2337			H-1770N			CV-24049			CV-24055		
Date/Time Sampled:	9/10/26 9:00			9/10/26 9:10			9/10/26 9:20			9/10/26 9:25		
Date/Time Analyzed:	9/10/26 15:45			9/10/26 15:59			9/10/26 16:13			9/10/26 16:28		
QC Batch No.:	260910GC8A1			260910GC8A1			260910GC8A1			260910GC8A1		
Analyst Initials:	MJ			MJ			MJ			MJ		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result ppmv	RL ppmv	MDL ppmv	Result ppmv	RL ppmv	MDL ppmv	Result ppmv	RL ppmv	MDL ppmv	Result ppmv	RL ppmv	MDL ppmv
Carbon Monoxide	2,000	10	0.030	320	10	0.030	1,700	10	0.030	1,400	10	0.030

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____
Annika Sotelo-Sanchez
Lab Manager

Date 9/27/26

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/10/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T091005-11			T091005-13								
Client Sample I.D.:	CV-24128			CV-24121								
Date/Time Sampled:	9/10/26 9:35			9/10/26 9:45								
Date/Time Analyzed:	9/10/26 16:57			9/10/26 17:26								
QC Batch No.:	260910GC8A1			260910GC8A1								
Analyst Initials:	MJ			MJ								
Dilution Factor:	1.0			1.0								
ANALYTE	Result ppmv	RL ppmv	MDL ppmv	Result ppmv	RL ppmv	MDL ppmv						
Carbon Monoxide	2,700	10	0.030	25	10	0.030						

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 9/27/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260910GC8A1
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	9/10/26 12:45			9/10/26 11:48		9/10/26 12:02					
Analyst Initials:	MJ			MJ		MJ					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,040	103	1,040	103	0.0	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 9/10/26

Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/10/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T091005-01			T091005-03			T091005-04			T091005-05		
Client Sample I.D.:	CV-24066			CV-24095			CV-2353			CV-2341		
Date/Time Sampled:	9/10/26 8:15			9/10/26 8:30			9/10/26 8:40			9/10/26 8:45		
Date/Time Analyzed:	9/10/26 14:12			9/10/26 14:41			9/10/26 15:16			9/10/26 15:30		
QC Batch No.:	260910GC8A1			260910GC8A1			260910GC8A1			260910GC8A1		
Analyst Initials:	MJ			MJ			MJ			MJ		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	2.3	1.0	0.059	18	1.0	0.059	23	1.0	0.059	22	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____
Annika Sotelo-Sanchez
Lab Manager

Date 9/27/26

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/10/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T091005-06			T091005-07			T091005-08			T091005-09		
Client Sample I.D.:	CV-2337			H-1770N			CV-24049			CV-24055		
Date/Time Sampled:	9/10/26 9:00			9/10/26 9:10			9/10/26 9:20			9/10/26 9:25		
Date/Time Analyzed:	9/10/26 15:45			9/10/26 15:59			9/10/26 16:13			9/10/26 16:28		
QC Batch No.:	260910GC8A1			260910GC8A1			260910GC8A1			260910GC8A1		
Analyst Initials:	MJ			MJ			MJ			MJ		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	10	1.0	0.059	2.3	1.0	0.059	15	1.0	0.059	8.5	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 9/26/26
Anjelka Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/10/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T091005-11			T091005-13								
Client Sample I.D.:	CV-24128			CV-24121								
Date/Time Sampled:	9/10/26 9:35			9/10/26 9:45								
Date/Time Analyzed:	9/10/26 16:57			9/10/26 17:26								
QC Batch No.:	260910GC8A1			260910GC8A1								
Analyst Initials:	MJ			MJ								
Dilution Factor:	1.0			1.0								
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v						
Hydrogen	11	1.0	0.059	0.16 J	1.0	0.059						

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 9/27/26
Abnika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260910GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	9/10/26 12:45				9/10/26 11:48		9/10/26 12:02					
Analyst Initials:	MJ				MJ		MJ					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	4.68	94	4.68	94	0.1	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 9/27/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/10/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T091005-01		T091005-02		T091005-03		T091005-04	
Client Sample I.D.:	CV-24066		CV-24099		CV-24095		CV-2353	
Date/Time Sampled:	9/10/26 8:15		9/10/26 8:25		9/10/26 8:30		9/10/26 8:40	
Date/Time Analyzed:	9/10/26 14:12		9/10/26 14:26		9/10/26 14:41		9/10/26 15:16	
QC Batch No.:	260910GC8A1		260910GC8A1		260910GC8A1		260910GC8A1	
Analyst Initials:	MJ		MJ		MJ		MJ	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	27	0.010	44	0.010	72	0.010	70	0.010
Oxygen/Argon	10	0.50	8.4	0.50	0.89	0.50	0.52	0.50
Nitrogen	49	1.0	34	1.0	3.6	1.0	1.9	1.0
Methane	12	0.0010	13	0.0010	3.6	0.0010	2.6	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 9/30/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/10/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T091005-05		T091005-06		T091005-07		T091005-08	
Client Sample I.D.:	CV-2341		CV-2337		H-1770N		CV-24049	
Date/Time Sampled:	9/10/26 8:45		9/10/26 9:00		9/10/26 9:10		9/10/26 9:20	
Date/Time Analyzed:	9/10/26 15:30		9/10/26 15:45		9/10/26 15:59		9/10/26 16:13	
QC Batch No.:	260910GC8A1		260910GC8A1		260910GC8A1		260910GC8A1	
Analyst Initials:	MJ		MJ		MJ		MJ	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	71	0.010	42	0.010	62	0.010	73	0.010
Oxygen/Argon	0.87	0.50	9.5	0.50	0.90	0.50	0.69	0.50
Nitrogen	3.2	1.0	36	1.0	8.6	1.0	4.0	1.0
Methane	1.2	0.0010	1.7	0.0010	25	0.0010	4.8	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 9/27/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/10/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T091005-09		T091005-10		T091005-11		T091005-12	
Client Sample I.D.:	CV-24055		CV-24134		CV-24128		CV-24123	
Date/Time Sampled:	9/10/26 9:25		9/10/26 9:30		9/10/26 9:35		9/10/26 9:40	
Date/Time Analyzed:	9/10/26 16:28		9/10/26 16:42		9/10/26 16:57		9/10/26 17:11	
QC Batch No.:	260910GC8A1		260910GC8A1		260910GC8A1		260910GC8A1	
Analyst Initials:	MJ		MJ		MJ		MJ	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	58	0.010	64	0.010	67	0.010	52	0.010
Oxygen/Argon	1.9	0.50	1.4	0.50	0.85	0.50	0.72	0.50
Nitrogen	26	1.0	8.7	1.0	4.5	1.0	2.8	1.0
Methane	4.4	0.0010	11	0.0010	16	0.0010	42	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 9/27/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 09/10/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	**T091005-13**							
Client Sample I.D.:	**CV-24121**							
Date/Time Sampled:	**9/10/26 9:45**							
Date/Time Analyzed:	**9/10/26 17:26**							
QC Batch No.:	**260910GC8A1**							
Analyst Initials:	**MJ**							
Dilution Factor:	**1.0**							
ANALYTE	**Result % v/v**	**RL % v/v**						
Carbon Dioxide	53	0.010						
Oxygen/Argon	4.2	0.50						
Nitrogen	16	1.0						
Methane	26	0.0010						

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 9/27/26

Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260910GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	9/10/26 12:45			9/10/26 11:48		9/10/26 12:02					
Analyst Initials:	MJ			MJ		MJ					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	9.52	95	9.49	95	0.3	70	130	30
Oxygen/Argon	ND	0.50	15	15.0	100	15.0	100	0.2	70	130	30
Nitrogen	ND	1.0	70	71.7	103	71.4	102	0.4	70	130	30
Methane	ND	0.0010	0.10	0.0976	97	0.0976	97	0.0	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 9/27/26
Annika Sotelo-Sanchez
Lab Manager

The cover letter is an integral part of this analytical report

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
A-01	9/17/2026 7:39:23 AM	57.7	40.3	0.0	2.0			1.4	0.0	84.5	
A-02	9/17/2026 7:48:47 AM	57.5	40.7	0.0	1.8			1.4	0.0	90.9	91.0
A-03	9/17/2026 8:00:42 AM	48.1	38.3	1.9	11.7			1.3	6.2	80.0	80.1
A-04	9/17/2026 8:10:05 AM	56.4	41.2	0.0	2.4			1.4	0.0	95.5	95.5
A-05	9/28/2026 8:50:32 AM	58.5	40.0	0.0	1.5			1.5	0.0	88.1	88.1
B-01	9/17/2026 9:22:43 AM	5.5	20.4	0.0	74.1			0.3	0.0	76.1	76.2
B-02R	9/17/2026 9:16:57 AM	30.3	29.4	0.0	40.3			1.0	0.0	75.0	75.0
B-03R	9/16/2026 1:51:26 PM	21.9	26.7	0.0	51.4			0.8	0.0	87.2	87.1
B-05	9/16/2026 2:03:40 PM	11.9	25.0	0.3	62.8			0.5	209.3	92.5	92.6
B-06	9/17/2026 8:53:22 AM	21.9	27.2	0.0	50.9			0.8	0.0	79.2	79.3
B-07R	9/16/2026 10:45:52 AM	26.7	26.9	1.6	44.8			1.0	28.0	89.0	90.0
B-07R	9/16/2026 10:52:10 AM	32.0	29.4	0.5	38.1			1.1	76.2	94.8	94.9
B-08	9/17/2026 8:39:40 AM	0.4	1.7	20.5	77.4			0.2	3.8	69.6	69.8
B-08	9/17/2026 8:44:20 AM	4.2	6.3	15.3	74.2			0.7	4.8	68.1	68.3
B-09	9/16/2026 9:27:25 AM	34.0	32.8	0.0	33.2			1.0	0.0	93.0	93.0
B-10	9/16/2026 9:20:22 AM	26.4	29.1	0.0	44.5			0.9	0.0	90.5	90.9
B-11	9/16/2026 8:54:56 AM	26.3	30.0	0.3	43.4			0.9	144.7	106.2	106.2
B-12	9/16/2026 1:43:21 PM	15.2	26.0	0.0	58.8			0.6	0.0	96.1	96.3
B-13	9/16/2026 1:37:34 PM	28.6	30.6	0.1	40.7			0.9	407.0	93.8	93.8
B-14	9/16/2026 8:34:59 AM	14.4	27.4	0.0	58.2			0.5	0.0	104.6	105.1
C-03	9/14/2026 1:58:34 PM	54.2	38.4	0.5	6.9			1.4	13.8	97.3	97.3
C-07	9/30/2026 3:03:49 PM	50.5	41.1	0.0	8.4			1.2	419.5	98.0	97.9
C-08	9/17/2026 10:13:25 AM	26.8	25.5	6.9	40.8			1.1	5.9	84.8	85.0
C-08	9/17/2026 10:15:37 AM	30.4	28.3	4.9	36.4			1.1	7.4	84.9	85.1
C-10	9/17/2026 10:44:49 AM	55.6	40.5	0.2	3.7			1.4	18.5	93.0	93.0
C-11	9/3/2026 11:22:35 AM	56.7	40.3	0.0	3.0			1.4	0.0	98.8	98.9
C-12	9/3/2026 11:48:07 AM	55.7	40.6	0.0	3.7			1.4	0.0	95.3	96.2
C-15	9/3/2026 11:44:12 AM	49.1	37.1	2.3	11.5			1.3	5.0	97.8	97.9
C-17B	9/29/2026 9:29:28 AM	54.2	42.1	0.0	3.7			1.3	0.0	110.2	110.2
C-18	9/29/2026 10:05:18 AM	53.0	41.7	0.2	5.1			1.3	28.1	114.8	114.8
C-19	9/29/2026 9:49:37 AM	55.2	41.6	0.0	3.2			1.3	0.0	98.8	98.9
C-20	9/29/2026 9:55:47 AM	55.2	41.5	0.0	3.4			1.3	0.0	110.7	111.0
C-24	9/29/2026 9:39:17 AM	35.6	32.8	5.2	26.4			1.1	5.1	102.3	102.8
C-24	9/29/2026 9:44:02 AM	36.9	33.6	4.5	25.1			1.1	5.6	103.7	103.6
C-25	9/25/2026 12:09:01 PM	0.1	0.6	21.0	78.3			0.2	3.7	124.3	124.5
C-25	9/25/2026 12:10:05 PM	0.2	0.5	20.9	78.4			0.4	3.8	125.1	125.3
C-26	9/25/2026 12:01:24 PM	47.6	44.1	0.0	8.3			1.1	0.0	110.0	110.0

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
C-27	9/3/2026 11:37:39 AM	0.9	2.4	20.3	76.4			0.4	3.8	95.3	95.4
C-27	9/3/2026 11:38:33 AM	0.1	0.8	20.6	78.5			0.1	3.8	95.8	95.8
C-28	9/3/2026 11:18:29 AM	56.3	39.8	0.0	3.9			1.4	0.0	103.6	103.6
C-29	9/21/2026 8:03:56 AM	47.0	49.8	0.0	3.2			0.9	0.0	109.4	109.2
C-30	9/17/2026 10:25:51 AM	0.0	0.1	20.8	79.1			0.0	3.8	82.4	82.4
C-30	9/17/2026 10:32:06 AM	48.9	39.4	1.1	10.6			1.2	9.6	112.3	113.3
CV-02	9/21/2026 10:39:51 AM	25.5	29.4	0.0	45.1			0.9	0.0	120.8	122.4
CV-03	9/21/2026 12:58:06 PM	38.7	36.2	0.0	25.1			1.1	0.0	120.7	120.7
CV-04	9/30/2026 8:15:05 AM	37.2	36.6	0.7	25.6			1.0	39.3	118.1	118.0
CV-05	9/4/2026 8:19:06 AM	55.5	40.8	0.0	3.8			1.4	0.0	106.0	106.0
CV-06	9/28/2026 3:58:30 PM	47.6	46.4	0.0	6.0			1.0	0.0	100.5	100.4
CV-108-52	9/1/2026 7:25:00 AM					450					
CV-108-52	9/1/2026 7:25:00 AM						130000				
CV-108-52	9/2/2026 7:35:40 AM	15.6	69.0	0.0	15.4			0.2	0.0	61.0	60.7
CV-108-52	9/2/2026 7:36:35 AM	15.6	71.2	0.0	13.2			0.2	0.0	59.0	59.0
CV-108-52	9/10/2026 3:44:09 PM	48.6	51.3	0.0	0.1			0.9	0.0	107.3	108.9
CV-108-52	9/10/2026 3:44:53 PM	49.6	50.4	0.0	0.0			1.0	0.0	108.7	108.6
CV-108-52	9/22/2026 11:11:22 AM	40.7	35.6	4.5	19.2			1.1	4.3	97.8	97.9
CV-113	9/4/2026 7:00:00 AM					37					
CV-113	9/4/2026 7:00:00 AM						0				
CV-113	9/14/2026 9:34:21 AM	0.3	1.6	18.7	79.4			0.2	4.2	97.6	97.8
CV-113	9/14/2026 9:35:35 AM	2.4	1.9	18.0	77.7			1.3	4.3	98.9	98.9
CV-113	9/25/2026 10:33:54 AM	12.8	19.1	13.0	55.1			0.7	4.2	106.0	106.1
CV-114	9/4/2026 8:22:00 AM					2200					
CV-114	9/4/2026 8:22:00 AM						180000				
CV-114	9/8/2026 9:33:48 AM	0.8	81.3	0.0	17.9			0.0	0.0	189.9	189.8
CV-114	9/8/2026 9:39:00 AM					3460					
CV-114	9/14/2026 8:28:09 AM	1.5	82.9	0.0	15.6			0.0	0.0	188.9	189.0
CV-114	9/14/2026 8:30:00 AM					3730					
CV-114	9/21/2026 8:22:00 AM	3.0	79.4	0.0	17.6			0.0	0.0	189.0	189.0
CV-114	9/21/2026 8:25:00 AM					3480					
CV-114	9/28/2026 8:16:00 AM	2.6	0.0	0.0	97.4				0.0	188.8	188.8
CV-114	9/28/2026 8:20:00 AM					3070					

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-114	9/28/2026 8:20:00 AM					3070					
CV-1424	9/3/2026 1:47:43 PM	49.0	40.3	0.0	10.7			1.2	0.0	106.5	106.6
CV-1532A	9/1/2026 7:30:00 AM					1400					
CV-1532A	9/1/2026 7:30:00 AM						230000				
CV-1532A	9/1/2026 1:33:46 PM	1.2	70.8	1.1	26.9			0.0	24.5	101.4	102.1
CV-1532A	9/30/2026 3:06:52 PM	0.7	75.5	0.9	22.9			0.0	25.4	167.0	167.2
CV-1534A-PL	9/2/2026 10:23:59 AM	7.9	78.1	0.0	14.0			0.1	0.0	135.3	131.1
CV-1534A-PL	9/30/2026 3:09:20 PM	0.0	16.8	18.6	64.6			0.0	3.5	121.9	121.8
CV-1535	9/1/2026 9:18:24 AM	45.5	48.3	0.0	6.2			0.9	0.0	105.4	105.5
CV-1535	9/4/2026 7:22:00 AM					2800					
CV-1535	9/4/2026 7:22:00 AM						180000				
CV-1535	9/22/2026 11:06:11 AM	28.1	36.2	0.0	35.7			0.8	0.0	125.6	125.5
CV-1535	9/24/2026 2:43:07 PM	29.6	40.2	0.0	30.2			0.7	0.0	126.1	125.8
CV-1601D	9/15/2026 11:02:56 AM	51.2	42.2	0.0	6.6			1.2	0.0	112.2	113.5
CV-1601D	9/21/2026 11:29:39 AM	44.9	43.8	0.0	11.3			1.0	0.0	115.5	115.1
CV-1601S	9/15/2026 11:06:57 AM	50.1	42.8	0.0	7.1			1.2	0.0	113.2	115.2
CV-1601S	9/21/2026 11:25:45 AM	43.0	45.8	0.0	11.2			0.9	0.0	118.7	117.7
CV-1604	9/24/2026 10:50:44 AM	50.8	44.5	0.0	4.7			1.1	0.0	115.0	115.0
CV-1701D	9/1/2026 8:45:21 AM	9.3	69.0	0.0	21.7			0.1	0.0	104.8	104.6
CV-1701S	9/1/2026 8:41:19 AM	22.5	65.0	0.0	12.5			0.3	0.0	130.8	130.5
CV-1901	9/14/2026 9:48:47 AM	23.1	68.2	0.1	8.6			0.3	86.0	117.4	117.2
CV-1901	9/16/2026 2:06:50 PM	16.9	73.8	0.2	9.1			0.2	45.5	109.6	108.1
CV-1902A	9/1/2026 7:35:00 AM					310					
CV-1902A	9/1/2026 7:35:00 AM						43000				
CV-1902A	9/8/2026 10:47:01 AM	2.5	75.0	0.2	22.3			0.0	111.5	158.4	159.4
CV-1902A	9/8/2026 10:50:00 AM					1290					
CV-1902A	9/16/2026 2:31:00 PM					869.5					
CV-1902A	9/16/2026 2:32:50 PM	12.4	72.3	1.3	14.0			0.2	10.8	157.7	157.8
CV-1902A	9/23/2026 2:32:08 PM	10.3	77.5	0.0	12.2			0.1	0.0	182.5	181.6
CV-1902A	9/23/2026 2:37:00 PM					1210					
CV-1902A	9/30/2026 2:35:00 PM					719					

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-1902A	9/30/2026 2:40:44 PM	9.6	64.4	2.6	23.4			0.1	9.0	154.5	155.0
CV-1905	9/14/2026 1:14:41 PM	15.0	11.0	14.8	59.2			1.4	4.0	100.4	89.1
CV-1905	9/22/2026 9:36:40 AM	42.3	33.7	4.1	19.9			1.3	4.9	78.9	89.6
CV-1905	9/24/2026 2:08:39 PM	53.1	45.7	0.0	1.2			1.2	0.0	111.3	111.4
CV-2001	9/2/2026 8:39:57 AM	9.5	69.9	2.0	18.6			0.1	9.3	79.4	79.5
CV-2001	9/9/2026 7:20:00 AM					1100					
CV-2001	9/9/2026 7:20:00 AM						100000				
CV-2001	9/23/2026 8:47:00 AM	4.6	54.5	7.5	33.4			0.1	4.5	85.7	86.5
CV-2002	9/1/2026 2:10:00 PM					3900					
CV-2002	9/1/2026 2:10:00 PM						117100				
CV-2002	9/1/2026 2:10:13 PM	12.4	71.4	0.3	15.9			0.2	53.0	185.8	185.8
CV-2002	9/8/2026 1:42:58 PM	15.2	73.0	0.6	11.2			0.2	18.7	185.6	185.6
CV-2002	9/8/2026 1:45:00 PM					4130					
CV-2002	9/9/2026 7:25:00 AM					2900					
CV-2002	9/9/2026 7:25:00 AM						140000				
CV-2002	9/17/2026 8:11:35 AM	24.9	67.9	0.4	6.8			0.4	17.0	183.5	183.4
CV-2002	9/17/2026 8:13:00 AM					2270					
CV-2002	9/24/2026 9:58:49 AM	9.8	72.3	0.0	17.9			0.1	0.0	184.2	184.3
CV-2002	9/24/2026 10:10:00 AM					2900					
CV-2003	9/2/2026 7:38:27 AM	15.0	69.9	0.0	15.1			0.2	0.0	99.9	101.4
CV-2003	9/2/2026 7:41:22 AM	15.3	71.9	0.0	12.8			0.2	0.0	98.4	98.8
CV-2003	9/10/2026 3:49:41 PM	48.3	51.7	0.0	0.0			0.9	0.0	123.9	123.9
CV-2003	9/10/2026 3:50:31 PM	24.9	68.6	0.0	6.5			0.4	0.0	123.9	123.8
CV-2003	9/22/2026 11:14:52 AM	16.0	73.2	0.0	10.8			0.2	0.0	113.2	113.2
CV-2006	9/8/2026 10:53:00 AM	2.8	76.5	0.0	20.7			0.0	0.0	185.6	185.8
CV-2006	9/8/2026 11:05:00 AM					2560					
CV-2006	9/16/2026 2:22:00 PM					3660					
CV-2006	9/16/2026 2:23:56 PM	12.8	77.6	0.0	9.6			0.2	0.0	186.3	186.2
CV-2006	9/23/2026 2:26:56 PM	12.7	66.8	0.0	20.5			0.2	0.0	185.0	185.0
CV-2006	9/23/2026 2:29:00 PM					3680					
CV-2006	9/30/2026 2:25:00 PM					4140					
CV-2006	9/30/2026 2:27:51 PM	8.5	78.2	0.0	13.3			0.1	0.0	185.9	185.9
CV-2007	9/3/2026 10:00:55 AM	16.8	76.7	0.0	6.5			0.2	0.0	126.2	126.3
CV-2007	9/4/2026 7:48:00 AM					470					
CV-2007	9/4/2026 7:48:00 AM						62000				
CV-2007	9/25/2026 2:05:13 PM	9.6	40.3	2.3	47.8			0.2	20.8	147.0	147.2

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2007	9/28/2026 10:15:15 AM	8.3	37.5	2.7	51.5			0.2	19.1	152.5	152.5
CV-2007	9/30/2026 10:12:39 AM	8.3	36.1	3.0	52.6			0.2	17.5	150.5	148.3
CV-2007	9/30/2026 10:14:47 AM	8.0	36.4	3.3	52.3			0.2	15.8	146.5	146.4
CV-2008	9/3/2026 9:55:07 AM	45.9	54.1	0.0	0.0			0.8	0.0	96.3	96.4
CV-2008	9/25/2026 2:19:23 PM	41.2	57.0	0.0	1.8			0.7	0.0	101.7	101.7
CV-2009	9/10/2026 1:22:30 PM	41.0	58.4	0.6	0.0			0.7	0.0	138.0	138.0
CV-2009A	9/14/2026 1:25:59 PM	35.5	61.1	0.0	3.4			0.6	0.0	149.9	150.4
CV-2009A	9/14/2026 1:27:41 PM	32.5	63.7	0.0	3.8			0.5	0.0	150.2	150.3
CV-2009A	9/14/2026 2:27:00 PM					913					
CV-2009A	9/14/2026 2:28:48 PM	30.1	63.9	0.0	6.0			0.5	0.0	151.4	151.3
CV-2009A	9/21/2026 1:44:33 PM	35.2	64.5	0.0	0.3			0.5	0.0	151.5	151.6
CV-2009A	9/21/2026 1:45:00 PM					1300					
CV-2010	9/22/2026 9:53:51 AM	41.3	51.2	0.1	7.4			0.8	74.0	89.1	89.2
CV-2010A	9/22/2026 9:49:39 AM	43.1	44.1	0.3	12.5			1.0	41.7	85.1	85.4
CV-2011	9/1/2026 10:17:28 AM	47.1	37.6	0.0	15.3			1.3	0.0	128.3	127.6
CV-2011A	9/2/2026 2:08:11 PM	30.8	56.0	0.0	13.2			0.6	0.0	152.0	152.0
CV-2011A	9/2/2026 2:10:00 PM					1005					
CV-2011A	9/2/2026 2:10:00 PM						201200				
CV-2011A	9/10/2026 9:14:08 AM	41.1	51.5	0.0	7.4			0.8	0.0	152.6	152.6
CV-2011A	9/10/2026 9:16:00 AM					719.5					
CV-2011A	9/11/2026 9:29:31 AM	28.1	46.4	0.0	25.5			0.6	0.0	152.7	152.7
CV-2011A	9/17/2026 10:27:00 AM					1250					
CV-2011A	9/17/2026 10:27:38 AM	36.0	50.8	0.0	13.2			0.7	0.0	151.4	151.3
CV-2011A	9/24/2026 2:22:16 PM	39.1	52.3	0.1	8.5			0.7	85.0	151.9	151.9
CV-2011A	9/24/2026 2:25:00 PM					800					
CV-2012	9/28/2026 1:57:34 PM	39.0	55.2	0.0	5.8			0.7	0.0	137.9	134.1
CV-2201-PLR	9/3/2026 7:56:39 AM	2.8	76.4	1.0	19.8			0.0	19.8	139.1	138.6
CV-2201-PLR	9/3/2026 7:57:44 AM	2.8	77.0	0.9	19.3			0.0	21.4	138.5	139.8
CV-2201-PLR	9/21/2026 8:20:29 AM	2.9	77.1	0.9	19.1			0.0	21.2	143.8	143.6
CV-2201-PLR	9/21/2026 8:21:42 AM	3.0	76.6	0.8	19.6			0.0	24.5	144.3	144.8
CV-2204-PLR	9/8/2026 2:13:18 PM	9.4	64.6	0.0	26.0			0.1	0.0	192.2	192.4

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2204-PLR	9/8/2026 2:17:00 PM					1640					
CV-2204-PLR	9/14/2026 10:19:07 AM	11.8	69.4	0.0	18.8			0.2	0.0	191.9	191.9
CV-2204-PLR	9/14/2026 10:26:00 AM					1540					
CV-2204-PLR	9/21/2026 10:25:45 AM	19.2	71.2	0.0	9.6			0.3	0.0	189.8	190.3
CV-2204-PLR	9/21/2026 10:28:00 AM					1330					
CV-2204-PLR	9/28/2026 10:21:59 AM	15.3	72.1	0.0	12.6			0.2	0.0	192.6	193.5
CV-2204-PLR	9/28/2026 10:25:00 AM					1320					
CV-2205	9/22/2026 10:12:14 AM	10.1	71.8	0.0	18.1			0.1	0.0	136.1	136.1
CV-2205	9/22/2026 10:43:00 AM	12.2	66.9	0.0	20.9			0.2	0.0	136.8	148.0
CV-2205	9/22/2026 10:44:32 AM	10.1	72.7	0.0	17.2			0.1	0.0	148.6	148.5
CV-2205	9/22/2026 1:55:00 PM					2840					
CV-2207	9/3/2026 1:27:19 PM	46.3	53.4	0.0	0.3			0.9	0.0	125.7	125.5
CV-2208A	9/10/2026 9:58:00 AM					1150					
CV-2208A	9/11/2026 6:08:06 PM	20.2	61.2	0.0	18.6			0.3	0.0	149.8	152.6
CV-2208A	9/14/2026 1:18:15 PM	34.8	60.1	0.1	5.0			0.6	50.0	156.8	156.9
CV-2208A	9/14/2026 1:19:00 PM					1090					
CV-2208A	9/24/2026 2:05:00 PM					896					
CV-2208A	9/24/2026 2:07:36 PM	27.3	64.5	0.1	8.1			0.4	81.0	156.7	156.9
CV-2301	9/2/2026 9:11:34 AM	20.2	64.6	0.0	15.2			0.3	0.0	179.1	179.0
CV-2301	9/2/2026 9:13:00 AM					775					
CV-2301	9/2/2026 9:13:00 AM						55700				
CV-2301	9/3/2026 6:40:00 AM					470					
CV-2301	9/3/2026 6:40:00 AM						55000				
CV-2301	9/8/2026 9:59:02 AM	22.0	48.9	3.9	25.2			0.4	6.5	167.1	167.3
CV-2301	9/8/2026 10:00:00 AM					1170					
CV-2301	9/16/2026 1:43:00 PM					830					
CV-2301	9/16/2026 1:46:53 PM	25.4	69.6	0.0	5.0			0.4	0.0	179.6	177.6
CV-2301	9/23/2026 1:27:45 PM	44.1	55.9	0.0	0.0			0.8	0.0	175.3	174.9
CV-2301	9/23/2026 1:31:00 PM					552					
CV-2301	9/30/2026 10:14:35 AM	43.3	46.5	10.2	0.0			0.9	0.0	174.4	174.6
CV-2301	9/30/2026 10:15:00 AM					495					
CV-2302	9/2/2026 8:56:46 AM	43.0	45.2	1.1	10.7			1.0	9.7	125.8	125.7
CV-2302	9/3/2026 6:45:00 AM					0					
CV-2302	9/3/2026 6:45:00 AM						35000				
CV-2302	9/17/2026 10:41:57 AM	44.5	45.0	1.1	9.4			1.0	8.5	113.0	113.3
CV-2303	9/3/2026 6:50:00 AM					1700					

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2303	9/3/2026 6:50:00 AM						190000				
CV-2303	9/3/2026 7:49:00 AM					2165					
CV-2303	9/3/2026 7:49:00 AM						187500				
CV-2303	9/3/2026 7:52:16 AM	2.1	73.6	0.0	24.3			0.0	0.0	190.5	
CV-2303	9/3/2026 7:53:05 AM	3.2	79.0	0.0	17.8			0.0	0.0	188.1	189.1
CV-2303	9/9/2026 8:46:47 AM	8.8	39.4	0.2	51.6			0.2	258.0	188.7	188.8
CV-2303	9/9/2026 8:50:00 AM					2470					
CV-2303	9/15/2026 9:24:00 AM	9.7	61.8	0.0	28.5			0.2	0.0	188.5	189.6
CV-2303	9/15/2026 9:25:00 AM					2620					
CV-2303	9/22/2026 9:19:07 AM	6.4	78.9	0.0	14.7			0.1	0.0	192.6	193.1
CV-2303	9/22/2026 9:21:00 AM					275					
CV-2304-PLR	9/3/2026 8:30:11 AM	4.0	74.2	0.1	21.7			0.1	217.0	173.4	173.7
CV-2304-PLR	9/3/2026 8:32:00 AM					1980					
CV-2304-PLR	9/3/2026 8:32:00 AM						190200				
CV-2304-PLR	9/9/2026 9:38:00 AM					1980					
CV-2304-PLR	9/9/2026 9:42:30 AM	8.4	73.1	0.0	18.5			0.1	0.0	177.5	177.4
CV-2304-PLR	9/11/2026 2:24:49 PM	2.6	74.4	0.0	23.0			0.0	0.0	173.4	173.3
CV-2304-PLR	9/11/2026 2:25:38 PM	2.7	72.8	0.0	24.5			0.0	0.0	172.5	172.9
CV-2304-PLR	9/15/2026 10:21:48 AM	15.9	69.0	0.0	15.1			0.2	0.0	176.0	176.8
CV-2304-PLR	9/15/2026 10:22:00 AM					1620					
CV-2304-PLR	9/22/2026 10:45:24 AM	15.0	72.1	0.0	12.9			0.2	0.0	175.7	176.4
CV-2304-PLR	9/22/2026 10:46:00 AM					1470					
CV-2304-PLR	9/29/2026 9:11:59 AM	26.1	60.7	0.0	13.2			0.4	0.0	177.6	178.0
CV-2304-PLR	9/29/2026 9:20:00 AM					1930					
CV-2305	9/1/2026 10:04:00 AM					2310					
CV-2305	9/1/2026 10:04:00 AM						50300				
CV-2305	9/1/2026 10:04:41 AM	36.5	59.2	0.0	4.3			0.6	0.0	158.7	158.8
CV-2305	9/9/2026 8:05:00 AM					1200					
CV-2305	9/9/2026 8:05:00 AM						47000				

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2305	9/9/2026 10:42:39 AM	27.0	71.2	0.0	1.8			0.4	0.0	155.5	155.6
CV-2305	9/9/2026 10:43:11 AM	35.9	57.4	0.0	6.7			0.6	0.0	155.7	155.7
CV-2305	9/9/2026 11:00:00 AM					2760					
CV-2305	9/15/2026 2:00:00 PM					2740					
CV-2305	9/15/2026 2:02:20 PM	26.5	73.5	0.0	0.0			0.4	0.0	163.4	163.8
CV-2305	9/15/2026 2:04:55 PM	26.3	73.7	0.0	0.0			0.4	0.0	163.6	163.7
CV-2305	9/22/2026 2:28:38 PM	16.0	81.6	0.0	2.4			0.2	0.0	157.9	157.9
CV-2305	9/22/2026 2:31:00 PM					1530					
CV-2305	9/29/2026 1:49:58 PM	35.5	60.1	0.0	4.4			0.6	0.0	158.9	159.0
CV-2305	9/30/2026 10:00:00 AM					1380					
CV-2305	9/30/2026 10:01:12 AM	20.9	51.5	0.0	27.6			0.4	0.0	157.5	157.6
CV-2306-PLR	9/8/2026 1:31:32 PM	2.9	76.3	0.4	20.4			0.0	51.0	182.1	182.0
CV-2306-PLR	9/8/2026 1:32:00 PM					1390					
CV-2306-PLR	9/14/2026 10:15:56 AM	13.0	71.2	0.4	15.4			0.2	38.5	144.5	144.9
CV-2306-PLR	9/14/2026 10:16:00 AM					1530					
CV-2306-PLR	9/28/2026 10:16:32 AM	18.1	71.2	0.4	10.3			0.3	25.8	131.7	132.0
CV-2306-PLR	9/28/2026 10:20:00 AM					1080					
CV-2308-PLR	9/3/2026 8:03:28 AM	3.4	77.8	0.5	18.3			0.0	36.6	121.3	120.6
CV-2308-PLR	9/21/2026 8:50:45 AM	4.4	76.6	0.6	18.4			0.1	30.7	118.8	117.4
CV-2310-PLR	9/3/2026 7:36:11 AM	2.1	70.2	0.0	27.7			0.0	0.0	197.6	198.2
CV-2310-PLR	9/3/2026 7:40:00 AM					1770					
CV-2310-PLR	9/3/2026 7:40:00 AM						172000				
CV-2310-PLR	9/9/2026 8:56:24 AM	6.3	84.5	0.0	9.2			0.1	0.0	192.2	192.6
CV-2310-PLR	9/9/2026 8:59:00 AM					1680					
CV-2310-PLR	9/15/2026 9:36:20 AM	6.6	72.7	0.0	20.7			0.1	0.0	190.5	190.6
CV-2310-PLR	9/15/2026 9:38:00 AM					1250					
CV-2310-PLR	9/22/2026 9:28:31 AM	6.7	70.6	0.0	22.7			0.1	0.0	191.6	191.7
CV-2310-PLR	9/22/2026 9:31:00 AM					1060					
CV-2310-PLR	9/29/2026 8:57:01 AM	12.2	76.1	0.0	11.7			0.2	0.0	190.2	147.2
CV-2310-PLR	9/29/2026 9:00:00 AM					1630					

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2311	9/8/2026 3:18:24 PM	17.6	61.0	0.0	21.4			0.3	0.0	164.5	166.2
CV-2311	9/8/2026 3:20:00 PM					1310					
CV-2311	9/15/2026 8:20:03 AM	24.8	66.9	0.0	8.3			0.4	0.0	169.4	169.6
CV-2311	9/15/2026 8:21:00 AM					766					
CV-2311	9/21/2026 2:22:27 PM	28.9	65.5	0.0	5.6			0.4	0.0	164.2	
CV-2311	9/21/2026 2:26:00 PM					1400					
CV-2311	9/28/2026 3:16:00 PM					1380					
CV-2311	9/28/2026 3:16:22 PM	26.6	64.8	0.0	8.6			0.4	0.0	154.6	156.5
CV-2312-PLR	9/2/2026 8:09:16 AM	3.5	83.0	0.0	13.5			0.0	0.0	168.3	168.3
CV-2312-PLR	9/3/2026 7:00:00 AM					2600					
CV-2312-PLR	9/3/2026 7:00:00 AM						160000				
CV-2312-PLR	9/9/2026 1:24:41 PM	17.4	71.0	0.1	11.5			0.2	115.0	169.7	169.6
CV-2312-PLR	9/9/2026 1:35:00 PM					3410					
CV-2312-PLR	9/16/2026 10:30:00 AM					3530					
CV-2312-PLR	9/16/2026 10:44:19 AM	5.0	79.9	0.0	15.1			0.1	0.0	169.6	169.5
CV-2312-PLR	9/23/2026 10:29:16 AM	43.9	53.5	2.6	0.0			0.8	0.0	170.0	170.1
CV-2312-PLR	9/23/2026 10:31:00 AM					2893					
CV-2312-PLR	9/23/2026 1:10:56 PM	6.8	79.1	0.0	14.1			0.1	0.0	169.8	169.8
CV-2312-PLR	9/30/2026 9:44:29 AM	6.4	79.0	0.0	14.6			0.1	0.0	169.9	170.0
CV-2312-PLR	9/30/2026 9:50:00 AM					2700					
CV-2314-PLR	9/1/2026 1:32:37 PM	11.3	76.9	0.0	11.8			0.1	0.0	187.2	187.3
CV-2314-PLR	9/1/2026 1:38:00 PM					4010					
CV-2314-PLR	9/1/2026 1:38:00 PM						120100				
CV-2314-PLR	9/4/2026 7:56:00 AM					2700					
CV-2314-PLR	9/4/2026 7:56:00 AM						130000				
CV-2314-PLR	9/9/2026 1:40:13 PM	23.0	76.3	0.0	0.7			0.3	0.0	188.1	188.1
CV-2314-PLR	9/9/2026 1:46:00 PM					2810					
CV-2314-PLR	9/16/2026 9:36:00 AM					3550					
CV-2314-PLR	9/16/2026 9:39:58 AM	6.1	84.0	0.1	9.8			0.1	98.0	187.9	187.8
CV-2314-PLR	9/23/2026 9:37:50 AM	9.3	79.1	0.6	11.0			0.1	18.3	186.3	186.2
CV-2314-PLR	9/23/2026 9:40:00 AM					2960					
CV-2314-PLR	9/30/2026 8:54:14 AM	5.1	82.0	0.2	12.7			0.1	63.5	185.5	185.5

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2314-PLR	9/30/2026 9:00:00 AM					4010					
CV-2315	9/3/2026 9:13:05 AM	14.8	74.0	0.1	11.1			0.2	111.0	184.9	185.1
CV-2315	9/3/2026 9:17:00 AM					2450					
CV-2315	9/3/2026 9:17:00 AM						123800				
CV-2315	9/4/2026 8:04:00 AM					2200					
CV-2315	9/4/2026 8:04:00 AM						170000				
CV-2315	9/8/2026 1:48:37 PM	4.4	79.7	0.0	15.9			0.1	0.0	179.1	180.6
CV-2315	9/8/2026 1:51:00 PM					2730					
CV-2315	9/14/2026 10:40:35 AM	17.7	69.7	0.0	12.6			0.3	0.0	191.7	191.8
CV-2315	9/14/2026 10:44:00 AM					1710					
CV-2315	9/21/2026 10:37:20 AM	29.6	64.3	0.0	6.1			0.5	0.0	187.2	187.3
CV-2315	9/21/2026 10:41:00 AM					1530					
CV-2315	9/28/2026 10:36:48 AM	23.8	66.4	0.0	9.8			0.4	0.0	187.5	187.5
CV-2315	9/28/2026 10:40:00 AM					1360					
CV-2316	9/2/2026 1:39:54 PM	27.5	68.8	0.0	3.7			0.4	0.0	149.9	150.0
CV-2316	9/2/2026 1:45:00 PM					2030					
CV-2316	9/2/2026 1:45:00 PM						88600				
CV-2316	9/3/2026 9:48:34 AM	20.4	69.4	0.0	10.2			0.3	0.0	149.7	149.8
CV-2316	9/10/2026 10:21:00 AM					2370					
CV-2316	9/10/2026 10:23:35 AM	29.7	67.3	0.0	3.0			0.4	0.0	150.3	150.3
CV-2316	9/14/2026 1:56:00 PM					1625					
CV-2316	9/14/2026 2:22:00 PM	27.0	66.3	0.0	6.7			0.4	0.0	149.9	150.0
CV-2316	9/21/2026 1:35:00 PM					2270					
CV-2316	9/21/2026 1:37:31 PM	34.4	65.5	0.0	0.1			0.5	0.0	150.0	150.1
CV-2319	9/2/2026 1:50:00 PM					4290					
CV-2319	9/2/2026 1:50:00 PM						80200				
CV-2319	9/2/2026 1:58:16 PM	12.6	83.0	0.0	4.4			0.2	0.0	161.1	161.2
CV-2319	9/2/2026 1:59:13 PM	12.9	80.8	0.0	6.3			0.2	0.0	161.2	161.2
CV-2319	9/9/2026 12:48:41 PM	47.6	52.3	0.1	0.0			0.9	0.0	160.6	160.6
CV-2319	9/9/2026 1:00:00 PM					2990					
CV-2319	9/15/2026 2:22:47 PM	36.4	63.6	0.0	0.0			0.6	0.0	167.3	167.3
CV-2319	9/15/2026 2:25:00 PM					3030					

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2319	9/22/2026 9:40:58 AM	10.1	81.4	0.1	8.4			0.1	84.0	172.8	173.6
CV-2319	9/22/2026 2:35:00 PM					48.9					
CV-2319	9/22/2026 2:40:31 PM	26.3	72.7	0.0	1.0			0.4	0.0	174.7	173.3
CV-2319	9/22/2026 2:41:24 PM	19.4	78.4	0.0	2.2			0.2	0.0	173.1	173.1
CV-2319	9/29/2026 1:53:56 PM	35.3	64.7	0.0	0.0			0.5	0.0	171.8	171.8
CV-2319	9/29/2026 2:00:00 PM					4180					
CV-2321	9/1/2026 8:55:00 AM					3590					
CV-2321	9/1/2026 8:55:00 AM						76600				
CV-2321	9/1/2026 8:56:13 AM	18.1	78.9	0.3	2.7			0.2	9.0	148.2	148.2
CV-2321	9/9/2026 10:11:41 AM	33.7	66.3	0.0	0.0			0.5	0.0	145.3	145.3
CV-2321	9/9/2026 10:15:00 AM					3130					
CV-2321	9/15/2026 1:25:04 PM	39.1	60.5	0.4	0.0			0.6	0.0	139.3	139.2
CV-2321	9/22/2026 9:56:29 AM	13.7	77.0	0.4	8.9			0.2	22.3	147.2	147.4
CV-2321	9/29/2026 1:15:00 PM					2840					
CV-2321	9/29/2026 1:21:59 PM	24.4	75.3	0.2	0.1			0.3	0.5	148.4	147.8
CV-2321	9/29/2026 1:22:57 PM	30.9	68.9	0.2	0.0			0.4	0.0	147.7	147.7
CV-2322	9/1/2026 1:56:33 PM	9.6	77.3	0.0	13.1			0.1	0.0	165.0	165.2
CV-2322	9/1/2026 2:00:00 PM					2140					
CV-2322	9/1/2026 2:00:00 PM						109200				
CV-2322	9/10/2026 8:31:00 AM					2640					
CV-2322	9/10/2026 8:31:01 AM	6.2	85.1	0.0	8.7			0.1	0.0	167.5	168.6
CV-2322	9/17/2026 12:50:31 PM	14.1	80.5	0.1	5.3			0.2	53.0	118.6	119.3
CV-2324	9/3/2026 1:08:01 PM	45.8	51.9	0.0	2.3			0.9	0.0	124.9	125.2
CV-2326	9/3/2026 9:35:00 AM					3110					
CV-2326	9/3/2026 9:35:00 AM						153800				
CV-2326	9/3/2026 9:35:50 AM	12.9	69.3	0.3	17.5			0.2	58.3	175.7	84.1
CV-2326	9/3/2026 1:14:03 PM	57.8	40.7	0.0	1.5			1.4	0.0	91.5	95.7
CV-2326	9/8/2026 3:25:00 PM					3480					
CV-2326	9/8/2026 3:25:03 PM	16.6	62.7	0.0	20.7			0.3	0.0	168.8	168.8
CV-2326	9/15/2026 8:24:00 AM					3020					

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2326	9/15/2026 8:25:39 AM	20.9	62.6	0.0	16.5			0.3	0.0	175.6	175.7
CV-2326	9/21/2026 2:28:46 PM	25.7	64.7	0.0	9.6			0.4	0.0	173.1	173.1
CV-2326	9/21/2026 2:31:00 PM					3000					
CV-2326	9/28/2026 3:18:43 PM	26.2	62.1	0.0	11.7			0.4	0.0	169.8	169.8
CV-2326	9/28/2026 3:20:00 PM					2350					
CV-2327	9/14/2026 10:24:05 AM	3.0	81.5	0.0	15.5			0.0	0.0	181.5	181.5
CV-2327	9/14/2026 10:26:47 AM	2.7	81.7	0.0	15.6			0.0	0.0	180.4	180.9
CV-2327	9/14/2026 1:30:00 PM					2360					
CV-2327	9/21/2026 8:50:00 AM					1280					
CV-2327	9/21/2026 8:58:34 AM	1.1	40.8	10.2	47.9			0.0	4.7	181.0	182.4
CV-2327	9/21/2026 9:11:07 AM	1.8	81.4	0.3	16.5			0.0	55.0	179.4	179.7
CV-2327	9/30/2026 9:14:10 AM	24.3	75.7	0.0	0.0			0.3	0.0	128.3	128.0
CV-2328	9/1/2026 2:21:10 PM	43.1	56.9	0.0	0.0			0.8	0.0	152.5	152.9
CV-2328	9/1/2026 2:25:00 PM					1690					
CV-2328	9/1/2026 2:25:00 PM						2600				
CV-2328	9/9/2026 7:45:00 AM					630					
CV-2328	9/9/2026 7:45:00 AM						62000				
CV-2328	9/9/2026 1:45:59 PM	50.5	49.5	0.0	0.0			1.0	0.0	119.1	119.1
CV-2328	9/24/2026 10:56:47 AM	37.6	56.8	0.1	5.5			0.7	55.0	151.3	151.3
CV-2328	9/24/2026 10:58:35 AM	36.2	57.1	0.0	6.7			0.6	0.0	151.1	151.3
CV-2328	9/28/2026 2:24:07 PM	35.2	63.1	0.0	1.7			0.6	0.0	148.1	148.4
CV-2328	9/30/2026 8:52:17 AM	38.1	55.8	0.0	6.1			0.7	0.0	145.4	145.4
CV-2328	9/30/2026 8:55:00 AM					887					
CV-2333	9/3/2026 7:45:00 AM					2700					
CV-2333	9/3/2026 7:45:00 AM						190000				
CV-2333	9/8/2026 9:30:41 AM	1.2	65.8	0.0	33.0			0.0	0.0	184.2	184.4
CV-2333	9/8/2026 9:35:00 AM					4040					
CV-2333	9/14/2026 8:23:05 AM	1.9	84.2	0.0	13.9			0.0	0.0	186.5	186.6
CV-2333	9/14/2026 8:25:00 AM					5050					
CV-2333	9/21/2026 8:18:24 AM	2.4	80.9	0.0	16.7			0.0	0.0	187.9	187.9
CV-2333	9/21/2026 8:21:00 AM					4470					
CV-2333	9/28/2026 8:05:00 AM					4280					

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2333	9/28/2026 8:08:07 AM	1.0	78.3	0.0	20.7			0.0	0.0	189.0	189.0
CV-2334	9/3/2026 7:50:00 AM					2600					
CV-2334	9/3/2026 7:50:00 AM						140000				
CV-2334	9/9/2026 12:10:26 PM	9.0	77.9	0.2	12.9			0.1	64.5	145.6	145.6
CV-2334	9/9/2026 12:10:43 PM	8.5	79.4	0.3	11.8			0.1	39.3	145.6	145.6
CV-2334	9/17/2026 12:59:56 PM	13.2	73.2	0.0	13.6			0.2	0.0	147.7	147.7
CV-2334	9/17/2026 1:03:00 PM					3390					
CV-2334	9/24/2026 1:25:00 PM					3530					
CV-2334	9/24/2026 1:44:17 PM	13.3	77.9	0.0	8.8			0.2	0.0	154.5	154.5
CV-2334	9/24/2026 1:45:33 PM	11.5	74.4	0.0	14.1			0.2	0.0	154.7	154.7
CV-2335	9/14/2026 9:41:03 AM	51.2	45.1	0.4	3.3			1.1	8.3	91.5	91.6
CV-2335	9/16/2026 2:27:40 PM	54.4	45.4	0.1	0.1			1.2	1.0	100.0	100.2
CV-2336	9/14/2026 9:45:07 AM	21.0	55.0	4.2	19.8			0.4	4.7	76.5	76.4
CV-2336	9/16/2026 2:20:41 PM	18.7	63.8	2.5	15.0			0.3	6.0	87.0	87.1
CV-2337	9/8/2026 10:57:52 AM	4.7	79.0	0.1	16.2			0.1	162.0	153.3	153.4
CV-2337	9/8/2026 11:00:00 AM					4780					
CV-2337	9/10/2026 9:00:00 AM					2000					
CV-2337	9/10/2026 9:00:00 AM						100000				
CV-2337	9/16/2026 2:13:00 PM					4360					
CV-2337	9/16/2026 2:19:44 PM	15.3	0.0	0.0	84.7				0.0	153.7	153.8
CV-2337	9/23/2026 2:21:00 PM					3390					
CV-2337	9/23/2026 2:21:55 PM	13.4	75.9	0.0	10.7			0.2	0.0	144.7	144.6
CV-2337	9/30/2026 2:15:00 PM					4335					
CV-2337	9/30/2026 2:20:16 PM	7.9	76.1	0.0	16.0			0.1	0.0	138.8	138.7
CV-2338	9/8/2026 11:13:27 AM	2.7	71.9	0.5	24.9			0.0	49.8	149.9	152.5
CV-2338	9/8/2026 11:15:00 AM					891					
CV-2338	9/16/2026 2:23:00 PM					1140					
CV-2338	9/16/2026 2:28:52 PM	10.7	76.9	0.0	12.4			0.1	0.0	175.6	176.3
CV-2338	9/23/2026 2:29:15 PM	10.2	77.7	0.0	12.1			0.1	0.0	173.6	175.6
CV-2338	9/23/2026 2:34:00 PM					1040					
CV-2338	9/30/2026 2:30:00 PM					616					

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2338	9/30/2026 2:35:34 PM	8.0	77.2	0.0	14.8			0.1	0.0	146.0	149.1
CV-2339	9/14/2026 2:04:24 PM	3.7	17.1	15.3	63.9			0.2	4.2	99.8	99.8
CV-2339	9/14/2026 2:06:28 PM	3.8	13.9	16.1	66.2			0.3	4.1	99.4	99.4
CV-2339	9/30/2026 3:45:57 PM	0.5	35.4	11.2	52.9			0.0	4.7	132.6	130.4
CV-2341	9/10/2026 8:29:15 AM	1.5	75.0	0.1	23.4			0.0	234.0	87.3	87.7
CV-2341	9/10/2026 8:30:27 AM	1.4	75.5	0.0	23.1			0.0	0.0	88.0	88.0
CV-2341	9/10/2026 8:45:00 AM					1500					
CV-2341	9/10/2026 8:45:00 AM						220000				
CV-2341	9/24/2026 2:48:06 PM	5.5	69.3	0.4	24.8			0.1	62.0	102.0	102.0
CV-2342A-PL	9/1/2026 1:37:03 PM	4.0	63.3	0.0	32.7			0.1	0.0	136.7	136.8
CV-2342A-PL	9/8/2026 2:08:22 PM	9.3	74.2	0.0	16.5			0.1	0.0	159.7	158.3
CV-2342A-PL	9/8/2026 2:17:58 PM	11.3	75.3	0.0	13.4			0.2	0.0	156.2	151.2
CV-2342A-PL	9/8/2026 2:20:00 PM					672					
CV-2342A-PL	9/14/2026 1:57:27 PM	6.1	66.8	0.1	27.1			0.1	450.8	189.8	189.9
CV-2342A-PL	9/14/2026 2:10:00 PM					1250					
CV-2342A-PL	9/24/2026 9:32:37 AM	8.8	69.5	0.0	21.7			0.1	0.0	182.3	182.1
CV-2342A-PL	9/24/2026 9:35:00 AM					1070					
CV-2343-PLR	9/1/2026 1:05:42 PM	2.3	75.8	0.0	21.9			0.0	0.0	156.4	156.7
CV-2343-PLR	9/1/2026 1:25:00 PM					3600					
CV-2343-PLR	9/1/2026 1:25:00 PM						157700				
CV-2343-PLR	9/8/2026 1:57:49 PM	4.6	82.2	0.2	13.0			0.1	65.0	160.7	160.7
CV-2343-PLR	9/8/2026 1:59:45 PM	5.0	79.0	0.0	16.0			0.1	0.0	161.7	162.0
CV-2343-PLR	9/8/2026 2:00:00 PM					3810					
CV-2343-PLR	9/14/2026 1:47:19 PM	3.9	66.9	0.1	29.1			0.1	323.0	100.6	99.7
CV-2343-PLR	9/14/2026 1:50:00 PM					4970					
CV-2343-PLR	9/16/2026 12:27:21 PM	0.9	72.6	0.3	26.2			0.0	77.0	180.6	178.9
CV-2343-PLR	9/24/2026 9:22:03 AM	13.7	68.1	0.0	18.2			0.2	0.0	189.4	189.6
CV-2343-PLR	9/24/2026 9:25:00 AM					3890					
CV-2344	9/1/2026 7:15:00 AM					1500					

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2344	9/1/2026 12:55:13 PM	10.7	76.2	0.0	13.1			0.1	0.0	141.6	142.2
CV-2344	9/1/2026 7:15:00 PM						110000				
CV-2344	9/8/2026 1:49:02 PM	12.4	80.3	0.0	7.3			0.2	0.0	150.4	150.5
CV-2344	9/8/2026 1:50:00 PM					2700					
CV-2344	9/8/2026 1:50:10 PM	12.1	80.1	0.0	7.8			0.2	0.0	150.8	150.8
CV-2344	9/14/2026 10:26:52 AM	12.3	67.3	0.0	20.4			0.2	510.8	147.1	147.4
CV-2344	9/14/2026 10:32:00 AM					2050					
CV-2344	9/24/2026 9:12:30 AM	11.1	69.4	0.0	19.5			0.2	0.0	158.7	158.9
CV-2344	9/24/2026 9:15:00 AM					1700					
CV-2345	9/1/2026 7:10:00 AM					450					
CV-2345	9/1/2026 7:10:00 AM						33000				
CV-2345	9/2/2026 7:32:38 AM	19.8	65.4	0.0	14.8			0.3	0.0	93.5	93.6
CV-2345	9/22/2026 11:32:10 AM	17.6	65.8	0.3	16.3			0.3	54.3	109.5	109.5
CV-2346	9/1/2026 7:05:00 AM					540					
CV-2346	9/1/2026 7:05:00 AM						53000				
CV-2346	9/1/2026 10:35:00 AM					532					
CV-2346	9/1/2026 10:35:00 AM						16600				
CV-2346	9/1/2026 10:36:56 AM	2.2	78.3	0.0	19.5			0.0	0.0	180.8	180.2
CV-2346	9/8/2026 2:30:00 PM					2740					
CV-2346	9/8/2026 2:32:55 PM	11.4	81.2	0.1	7.3			0.1	73.0	179.4	179.6
CV-2346	9/14/2026 10:07:15 AM	2.2	74.4	0.0	23.5			0.0	0.0	184.5	184.6
CV-2346	9/14/2026 10:09:25 AM	1.6	76.0	0.0	22.4			0.0	0.0	184.7	184.6
CV-2346	9/14/2026 10:10:00 AM					1720					
CV-2346	9/24/2026 9:05:00 AM					1525					
CV-2346	9/24/2026 9:07:33 AM	4.5	81.8	0.0	13.7			0.1	0.0	187.3	187.2
CV-2347	9/1/2026 6:55:00 AM					610					
CV-2347	9/1/2026 6:55:00 AM						46000				
CV-2347	9/2/2026 7:17:45 AM	14.4	48.6	0.2	36.8			0.3	184.0	91.2	91.0
CV-2347	9/22/2026 12:05:58 PM	14.6	47.0	1.1	37.3			0.3	33.9	117.6	117.7
CV-2348	9/1/2026 6:50:00 AM						28000				
CV-2348	9/1/2026 6:50:00 PM					380					
CV-2348	9/2/2026 7:12:27 AM	19.9	51.5	0.1	28.5			0.4	285.0	131.4	131.4
CV-2348	9/2/2026 7:13:13 AM	19.9	51.7	0.1	28.3			0.4	283.0	131.4	131.5
CV-2348	9/22/2026 12:12:09 PM	19.0	51.4	0.0	29.6			0.4	0.0	137.6	137.6
CV-2348	9/22/2026 12:13:11 PM	18.8	53.3	0.0	27.9			0.4	0.0	137.9	137.9

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2349	9/1/2026 2:05:00 AM						151900				
CV-2349	9/1/2026 2:02:58 PM	3.1	71.2	0.7	25.0			0.0	35.7	162.2	161.7
CV-2349	9/1/2026 2:05:00 PM					2770					
CV-2349	9/2/2026 7:50:00 AM					2900					
CV-2349	9/2/2026 7:50:00 AM						200000				
CV-2349	9/8/2026 1:35:00 PM					3020					
CV-2349	9/8/2026 1:37:23 PM	9.1	77.3	0.7	12.9			0.1	18.4	164.0	163.8
CV-2349	9/8/2026 1:38:01 PM	9.5	80.8	0.3	9.4			0.1	31.3	163.4	163.5
CV-2349	9/17/2026 9:37:56 AM	10.3	75.6	0.0	14.1			0.1	0.0	176.9	178.0
CV-2349	9/17/2026 9:40:00 AM					2410					
CV-2349	9/24/2026 9:55:30 AM	10.2	72.1	0.0	17.7			0.1	0.0	181.6	181.7
CV-2349	9/24/2026 10:05:00 AM					2680					
CV-2350	9/1/2026 7:20:00 AM					3400					
CV-2350	9/1/2026 7:20:00 AM						170000				
CV-2350	9/2/2026 8:27:52 AM	6.2	69.6	1.0	23.2			0.1	23.2	75.8	75.6
CV-2350	9/23/2026 9:06:15 AM	5.1	79.7	0.3	14.9			0.1	49.7	117.3	117.4
CV-2351	9/2/2026 7:15:00 AM					220					
CV-2351	9/2/2026 7:15:00 AM						27000				
CV-2351	9/10/2026 12:26:23 PM	19.0	47.9	5.4	27.7			0.4	5.1	118.4	118.2
CV-2351	9/10/2026 12:27:25 PM	18.2	45.7	5.5	30.6			0.4	5.6	118.0	117.9
CV-2351	9/23/2026 9:53:22 AM	0.0	9.2	19.0	71.8			0.0	3.8	96.7	96.6
CV-2352	9/2/2026 7:20:00 AM					820					
CV-2352	9/2/2026 7:20:00 AM						190000				
CV-2352	9/10/2026 11:57:24 AM	3.8	73.5	0.6	22.1			0.1	36.8	146.1	144.6
CV-2352	9/10/2026 11:59:11 AM	3.7	74.6	0.2	21.5			0.0	107.5	144.6	144.6
CV-2352	9/30/2026 3:26:31 PM	18.1	68.1	0.1	13.7			0.3	137.0	189.3	190.5
CV-2353-PLR	9/2/2026 7:54:07 AM	4.1	68.4	1.0	26.5			0.1	26.5	90.4	91.2
CV-2353-PLR	9/10/2026 8:40:00 AM					560					
CV-2353-PLR	9/10/2026 8:40:00 AM						230000				

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2353-PLR	9/30/2026 4:20:22 PM	1.9	39.9	8.9	49.3			0.0	5.5	140.6	142.2
CV-2354	9/2/2026 7:45:00 AM					1400					
CV-2354	9/2/2026 7:45:00 AM						150000				
CV-2354	9/2/2026 8:05:50 AM	7.2	73.8	0.0	19.0			0.1	0.0	163.2	163.4
CV-2354	9/2/2026 8:06:24 AM	7.4	74.5	0.1	18.0			0.1	180.0	162.5	162.2
CV-2354	9/8/2026 8:08:52 AM	5.4	74.5	0.0	20.1			0.1	0.0	187.3	188.2
CV-2354	9/8/2026 8:10:05 AM	5.3	70.3	0.0	24.4			0.1	0.0	188.7	188.0
CV-2354	9/8/2026 9:08:00 AM					1530					
CV-2354	9/17/2026 9:46:30 AM	11.4	75.6	0.0	13.0			0.2	0.0	187.6	188.0
CV-2354	9/17/2026 9:50:00 AM					2210					
CV-2354	9/24/2026 9:34:17 AM	9.4	72.7	0.0	17.9			0.1	0.0	182.2	182.3
CV-2354	9/24/2026 9:47:15 AM	7.7	71.3	0.3	20.7			0.1	69.0	110.3	110.5
CV-2354	9/24/2026 9:50:00 AM					1210					
CV-24001	9/10/2026 9:02:39 AM	53.4	44.3	0.0	2.3			1.2	0.0	105.6	106.3
CV-24001	9/16/2026 2:35:59 PM	51.9	45.1	0.1	2.9			1.2	29.0	97.2	97.4
CV-24002	9/10/2026 8:53:47 AM	35.4	49.0	0.0	15.6			0.7	0.0	112.6	111.9
CV-24002	9/16/2026 2:44:36 PM	35.4	49.1	0.1	15.4			0.7	154.0	111.0	110.3
CV-24003	9/14/2026 9:33:43 AM	26.1	40.5	0.6	32.8			0.6	54.7	104.8	105.0
CV-24003	9/16/2026 2:48:11 PM	30.2	54.6	0.2	15.0			0.6	75.0	106.5	106.6
CV-24004	9/1/2026 11:16:57 AM	38.7	53.1	0.0	8.2			0.7	0.0	122.3	122.4
CV-24004	9/16/2026 12:39:13 PM	31.8	52.3	0.0	15.9			0.6	0.0	121.3	121.2
CV-24006	9/1/2026 11:38:09 AM	20.5	66.6	1.5	11.4			0.3	7.6	132.3	130.8
CV-24006	9/1/2026 11:38:58 AM	19.2	67.4	1.8	11.6			0.3	6.4	130.2	130.4
CV-24006	9/16/2026 1:53:51 PM	11.4	77.0	1.6	10.0			0.1	6.3	111.5	111.6
CV-24007	9/1/2026 1:41:17 PM	26.5	46.2	0.1	27.2			0.6	272.0	145.5	145.7
CV-24007	9/3/2026 7:10:00 AM					400					
CV-24007	9/3/2026 7:10:00 AM						51000				
CV-24007	9/8/2026 3:13:15 PM	16.2	67.7	0.0	16.1			0.2	0.0	166.8	166.8
CV-24007	9/8/2026 3:15:00 PM					1040					
CV-24007	9/15/2026 8:10:00 AM					283					
CV-24007	9/15/2026 8:12:16 AM	28.1	41.7	0.0	30.2			0.7	0.0	144.4	144.3

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24007	9/29/2026 9:01:50 AM	20.3	40.7	0.1	38.9			0.5	389.0	145.4	145.5
CV-24007	9/29/2026 9:03:57 AM	13.4	65.5	0.0	21.1			0.2	0.0	146.3	146.5
CV-24007	9/29/2026 9:55:00 AM					1690					
CV-24008	9/8/2026 3:07:24 PM	12.6	67.9	0.0	19.5			0.2	0.0	185.4	185.5
CV-24008	9/8/2026 3:09:00 PM					1840					
CV-24008	9/14/2026 2:57:03 PM	17.1	65.8	0.0	17.1			0.3	0.0	185.2	185.4
CV-24008	9/14/2026 2:59:00 PM					1650					
CV-24008	9/21/2026 2:19:31 PM	23.0	70.9	0.0	6.1			0.3	0.0	182.8	182.8
CV-24008	9/21/2026 2:20:00 PM					1250					
CV-24008	9/28/2026 3:12:00 PM					756					
CV-24008	9/28/2026 3:12:04 PM	26.6	63.0	0.0	10.4			0.4	0.0	181.5	181.6
CV-24009	9/8/2026 3:00:41 PM	6.4	77.4	0.0	16.2			0.1	0.0	172.4	172.2
CV-24009	9/8/2026 3:03:00 PM					1480					
CV-24009	9/14/2026 2:51:55 PM	15.3	72.6	0.2	11.9			0.2	59.5	167.3	167.3
CV-24009	9/14/2026 2:52:00 PM					1120					
CV-24009	9/21/2026 2:14:38 PM	15.1	74.0	0.3	10.6			0.2	35.3	173.3	173.0
CV-24009	9/21/2026 2:15:00 PM					1460					
CV-24009	9/28/2026 2:54:10 PM	13.9	74.5	0.0	11.6			0.2	0.0	161.2	161.3
CV-24009	9/28/2026 3:05:00 PM					1280					
CV-24010	9/14/2026 1:20:33 PM	34.8	54.3	0.5	10.4			0.6	20.8	103.5	103.6
CV-24010	9/23/2026 1:13:43 PM	0.0	1.9	20.0	78.1			0.0	3.9	104.5	104.5
CV-24011	9/10/2026 1:14:00 PM					2600					
CV-24011	9/10/2026 1:15:42 PM	18.7	69.7	0.0	11.6			0.3	0.0	189.4	189.5
CV-24011	9/15/2026 8:34:00 AM					2610					
CV-24011	9/15/2026 8:38:24 AM	19.0	67.0	0.0	14.0			0.3	0.0	185.6	185.6
CV-24011	9/22/2026 8:35:45 AM	18.9	68.4	0.0	12.7			0.3	0.0	183.9	183.8
CV-24011	9/22/2026 8:37:00 AM					1880					
CV-24011	9/29/2026 8:04:57 AM	18.1	65.5	0.0	16.4			0.3	0.0	181.9	181.8
CV-24011	9/29/2026 8:10:00 AM					2250					

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24012	9/10/2026 1:34:00 PM					2600					
CV-24012	9/10/2026 1:36:19 PM	8.6	79.7	0.0	11.7			0.1	0.0	182.7	181.8
CV-24012	9/15/2026 8:57:47 AM	5.6	60.0	0.0	34.4			0.1	0.0	187.7	187.7
CV-24012	9/15/2026 8:59:00 AM					1450					
CV-24012	9/22/2026 8:52:16 AM	5.3	78.7	0.0	16.0			0.1	0.0	181.8	183.2
CV-24012	9/22/2026 8:55:00 AM					1740					
CV-24012	9/29/2026 8:25:00 AM					2020					
CV-24012	9/29/2026 8:26:34 AM	3.5	78.5	0.0	18.0			0.0	0.0	175.0	174.6
CV-24012	9/29/2026 8:27:45 AM	4.3	81.9	0.0	13.8			0.1	0.0	175.5	175.2
CV-24013	9/8/2026 2:55:00 PM					2320					
CV-24013	9/8/2026 2:55:38 PM	3.8	75.7	0.2	20.3			0.1	101.5	189.7	190.1
CV-24013	9/14/2026 2:41:00 PM					1700					
CV-24013	9/14/2026 2:45:29 PM	8.9	73.4	0.3	17.4			0.1	58.0	189.6	188.7
CV-24013	9/21/2026 2:06:00 PM					1605					
CV-24013	9/21/2026 2:06:42 PM	9.4	73.9	0.3	16.4			0.1	54.7	189.6	190.6
CV-24013	9/22/2026 9:07:43 AM	7.2	78.3	0.0	14.5			0.1	0.0	185.8	186.0
CV-24013	9/28/2026 2:25:03 PM	6.4	46.3	6.6	40.7			0.1	6.2	190.6	190.2
CV-24013	9/28/2026 2:34:21 PM	6.9	52.6	5.0	35.5			0.1	7.1	190.2	189.5
CV-24013	9/28/2026 2:46:14 PM	7.1	53.1	4.1	35.7			0.1	8.7	190.8	190.0
CV-24013	9/28/2026 3:05:00 PM					105.5					
CV-24014	9/8/2026 10:27:00 AM					1580					
CV-24014	9/8/2026 10:29:18 AM	1.9	73.6	0.0	24.5			0.0	0.0	182.9	182.9
CV-24014	9/14/2026 9:42:29 AM	13.6	71.7	0.4	14.3			0.2	35.8	183.6	183.7
CV-24014	9/14/2026 9:47:00 AM					1560					
CV-24014	9/21/2026 9:59:00 AM					1540					
CV-24014	9/21/2026 10:01:34 AM	14.2	69.3	0.8	15.7			0.2	19.6	183.8	183.8
CV-24014	9/28/2026 9:50:00 AM					1370					

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24014	9/28/2026 9:51:51 AM	12.1	66.5	1.4	20.0			0.2	14.3	183.0	183.0
CV-24015	9/8/2026 10:15:00 AM					1390					
CV-24015	9/8/2026 10:15:01 AM	1.5	66.3	0.0	32.2			0.0	0.0	187.9	188.3
CV-24015	9/14/2026 9:33:41 AM	11.0	73.9	0.0	15.1			0.1	0.0	179.6	179.9
CV-24015	9/14/2026 9:37:00 AM					2390					
CV-24015	9/21/2026 9:43:08 AM	9.4	73.0	0.0	17.6			0.1	0.0	189.6	189.8
CV-24015	9/21/2026 9:47:00 AM					1690					
CV-24015	9/28/2026 9:20:40 AM	10.3	76.3	0.0	13.4			0.1	0.0	163.2	163.3
CV-24015	9/28/2026 9:25:00 AM					1660					
CV-24016	9/10/2026 1:20:58 PM	24.6	49.0	0.2	26.2			0.5	131.0	167.3	167.9
CV-24016	9/10/2026 1:23:00 PM					1270					
CV-24016	9/15/2026 8:42:34 AM	18.1	64.5	0.0	17.4			0.3	0.0	161.4	161.6
CV-24016	9/15/2026 8:46:00 AM					418					
CV-24016	9/22/2026 8:41:38 AM	16.7	54.7	0.0	28.6			0.3	0.0	176.5	176.4
CV-24016	9/22/2026 8:43:00 AM					959					
CV-24016	9/29/2026 8:07:47 AM	14.9	56.7	0.0	28.4			0.3	0.0	167.6	167.5
CV-24016	9/29/2026 8:15:00 AM					1410					
CV-24017	9/9/2026 7:35:00 AM					1400					
CV-24017	9/9/2026 7:35:00 AM						160000				
CV-24017	9/9/2026 8:19:35 AM	20.9	71.3	0.4	7.4			0.3	18.5	176.0	176.4
CV-24017	9/9/2026 8:21:00 AM					1095					
CV-24017	9/15/2026 8:47:21 AM	17.7	52.5	0.0	29.8			0.3	0.0	186.7	186.8
CV-24017	9/15/2026 8:51:00 AM					1110					
CV-24017	9/22/2026 8:31:00 AM					1250					
CV-24017	9/22/2026 8:31:48 AM	19.7	69.8	0.7	9.8			0.3	14.0	174.5	174.0
CV-24017	9/29/2026 8:02:00 AM	19.2	66.5	0.9	13.4			0.3	14.9	167.3	167.1
CV-24017	9/29/2026 8:05:00 AM					1275					
CV-24018	9/1/2026 1:52:46 PM	11.0	65.9	0.2	22.9			0.2	114.5	132.4	131.9
CV-24018	9/1/2026 1:53:33 PM	10.9	66.1	0.2	22.8			0.2	114.0	131.6	131.7

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24018	9/15/2026 9:11:09 AM	5.1	72.5	0.0	22.4			0.1	0.0	133.9	133.8
CV-24018	9/24/2026 8:57:40 AM	11.0	60.8	0.0	28.2			0.2	0.0	140.1	135.3
CV-24018	9/24/2026 8:58:59 AM	9.0	65.8	0.0	25.2			0.1	0.0	134.8	134.6
CV-24019	9/3/2026 7:27:00 AM					2300					
CV-24019	9/3/2026 7:27:00 AM						158000				
CV-24019	9/3/2026 7:27:22 AM	4.0	82.5	0.1	13.4			0.0	134.0	181.6	181.8
CV-24019	9/9/2026 8:36:17 AM	6.5	77.9	0.4	15.2			0.1	38.0	180.7	181.9
CV-24019	9/9/2026 8:39:00 AM					1740					
CV-24019	9/15/2026 9:06:46 AM	4.5	75.6	0.0	19.9			0.1	0.0	184.0	183.7
CV-24019	9/15/2026 9:09:00 AM					1600					
CV-24019	9/22/2026 9:08:00 AM					1980					
CV-24019	9/24/2026 10:45:00 AM					2050					
CV-24019	9/24/2026 10:45:17 AM	9.9	73.1	0.0	17.0			0.1	0.0	190.5	190.8
CV-24019	9/29/2026 8:43:49 AM	8.8	70.1	2.1	19.0			0.1	9.0	175.6	175.3
CV-24019	9/29/2026 8:45:00 AM					1970					
CV-24020	9/3/2026 8:44:20 AM	0.6	8.1	16.6	74.7			0.1	4.5	80.5	81.2
CV-24020	9/3/2026 8:45:27 AM	0.6	10.0	16.1	73.3			0.1	4.6	81.7	81.7
CV-24020	9/21/2026 8:32:06 AM	0.0	9.2	17.2	73.6			0.0	4.3	69.4	69.4
CV-24020	9/21/2026 8:33:17 AM	0.1	10.1	16.5	73.3			0.0	4.4	69.4	69.3
CV-24021	9/3/2026 8:33:42 AM	9.0	66.0	3.5	21.5			0.1	6.1	147.1	147.1
CV-24021	9/3/2026 8:39:22 AM	11.7	64.4	3.3	20.6			0.2	6.2	145.9	146.0
CV-24021	9/3/2026 1:27:00 PM					260					
CV-24021	9/3/2026 1:27:00 PM						83000				
CV-24021	9/10/2026 1:38:53 PM	8.5	76.5	0.0	15.0			0.1	0.0	109.6	109.8
CV-24021	9/21/2026 8:38:36 AM	0.0	1.0	19.2	79.8			0.0	4.2	75.4	76.4
CV-24021	9/21/2026 8:39:59 AM	0.1	0.3	19.3	80.3			0.3	4.2	76.4	76.3
CV-24022-PL	9/8/2026 10:34:00 AM					1860					

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24022-PL	9/8/2026 10:34:57 AM	2.4	71.9	0.0	25.7			0.0	0.0	194.7	194.8
CV-24022-PL	9/14/2026 9:47:06 AM	10.2	70.7	0.4	18.7			0.1	46.8	194.7	194.8
CV-24022-PL	9/17/2026 1:14:16 PM	14.6	74.2	0.0	11.2			0.2	0.0	194.5	194.7
CV-24022-PL	9/17/2026 1:15:00 PM					2220					
CV-24022-PL	9/21/2026 10:04:00 AM					2060					
CV-24022-PL	9/21/2026 10:05:58 AM	11.8	67.0	0.0	21.2			0.2	0.0	194.4	194.4
CV-24022-PL	9/28/2026 9:56:17 AM	9.4	68.2	0.5	21.9			0.1	43.8	194.6	194.7
CV-24022-PL	9/28/2026 10:05:00 AM					1970					
CV-24023	9/8/2026 10:21:52 AM	1.5	66.5	0.0	32.0			0.0	0.0	196.3	196.4
CV-24023	9/8/2026 10:23:00 AM					1530					
CV-24023	9/14/2026 9:37:06 AM	10.5	74.6	0.0	14.9			0.1	0.0	196.1	196.2
CV-24023	9/14/2026 9:41:00 AM					1210					
CV-24023	9/21/2026 9:52:32 AM	11.2	58.9	3.3	26.6			0.2	8.1	185.2	188.3
CV-24023	9/21/2026 9:53:00 AM					1080					
CV-24023	9/28/2026 9:32:30 AM	15.3	63.8	0.0	20.9			0.2	0.0	196.4	196.4
CV-24023	9/28/2026 9:33:25 AM	15.0	70.4	0.0	14.6			0.2	0.0	196.4	196.5
CV-24023	9/28/2026 9:35:00 AM					1570					
CV-24024-PL	9/14/2026 1:05:56 PM	1.5	72.6	0.5	25.4			0.0	50.8	162.8	165.5
CV-24024-PL	9/14/2026 1:07:36 PM	1.4	73.8	0.2	24.6			0.0	123.0	165.6	163.3
CV-24024-PL	9/14/2026 2:45:00 PM					1440					
CV-24024-PL	9/21/2026 9:33:56 AM	10.8	72.7	0.0	16.5			0.1	0.0	139.0	139.0
CV-24025	9/3/2026 7:56:02 AM	3.6	80.6	0.0	15.8			0.0	0.0	174.3	174.4
CV-24025	9/3/2026 8:00:00 AM					2190					
CV-24025	9/3/2026 8:00:00 AM						127300				
CV-24025	9/9/2026 8:43:21 AM	12.2	51.5	0.3	36.0			0.2	120.0	168.6	167.7
CV-24025	9/9/2026 8:45:00 AM					1460					

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24025	9/15/2026 9:18:02 AM	13.0	68.1	0.0	18.9			0.2	0.0	178.2	178.6
CV-24025	9/15/2026 9:19:00 AM					1970					
CV-24025	9/22/2026 9:13:58 AM	8.7	64.0	0.0	27.3			0.1	0.0	184.0	184.1
CV-24025	9/22/2026 9:16:00 AM					2110					
CV-24025	9/29/2026 8:49:38 AM	10.8	60.2	0.0	29.0			0.2	0.0	170.7	171.0
CV-24025	9/29/2026 8:50:00 AM					2010					
CV-24026	9/3/2026 7:33:18 AM	2.7	81.2	0.0	16.1			0.0	0.0	179.6	179.5
CV-24026	9/3/2026 7:34:00 AM					1990					
CV-24026	9/3/2026 7:34:00 AM						196700				
CV-24026	9/9/2026 8:31:27 AM	7.3	70.0	0.0	22.7			0.1	0.0	142.6	142.2
CV-24026	9/21/2026 8:25:41 AM	1.0	79.9	0.0	19.1			0.0	0.0	184.9	184.5
CV-24026	9/21/2026 8:26:47 AM	1.0	79.6	0.0	19.4			0.0	0.0	184.3	184.4
CV-24026	9/28/2026 10:42:46 AM	0.9	87.7	0.0	11.4			0.0	0.0	184.4	184.5
CV-24026	9/29/2026 8:35:00 AM					2320					
CV-24026	9/29/2026 8:35:11 AM	3.7	78.8	0.0	17.5			0.0	0.0	179.6	179.4
CV-24027	9/9/2026 11:08:00 AM	7.9	37.8	7.9	46.4			0.2	5.9	117.6	117.7
CV-24027	9/21/2026 8:45:43 AM	0.2	11.2	16.2	72.4			0.0	4.5	82.3	84.5
CV-24027	9/21/2026 8:46:35 AM	0.2	11.0	16.2	72.6			0.0	4.5	83.2	83.9
CV-24028	9/8/2026 10:39:56 AM	1.8	70.7	0.0	27.5			0.0	0.0	198.6	198.5
CV-24028	9/8/2026 10:45:00 AM					1330					
CV-24028	9/14/2026 9:52:00 AM					1110					
CV-24028	9/14/2026 9:59:11 AM	11.4	69.4	0.0	19.2			0.2	0.0	195.6	195.7
CV-24028	9/21/2026 10:10:45 AM	11.2	70.5	0.0	18.3			0.2	0.0	195.8	195.4
CV-24028	9/21/2026 10:13:00 AM					1110					
CV-24028	9/28/2026 10:02:58 AM	11.8	69.7	0.0	18.5			0.2	0.0	196.6	196.4
CV-24028	9/28/2026 10:10:00 AM					1080					

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24029	9/9/2026 10:30:51 AM	2.3	66.1	3.7	27.9			0.0	7.5	117.9	118.3
CV-24029	9/25/2026 10:15:36 AM	0.1	3.1	19.2	77.6			0.0	4.0	97.0	96.7
CV-24030	9/8/2026 9:51:00 AM					244					
CV-24030	9/8/2026 9:52:46 AM	1.1	66.4	3.6	28.9			0.0	8.0	86.2	91.1
CV-24030	9/14/2026 8:52:00 AM					1680					
CV-24030	9/14/2026 9:02:11 AM	3.8	63.6	4.5	28.1			0.1	6.2	185.0	185.0
CV-24030	9/14/2026 9:08:34 AM	4.3	64.8	3.6	27.3			0.1	7.6	187.0	75.3
CV-24030	9/21/2026 9:12:52 AM	5.2	68.1	3.7	23.0			0.1	6.2	186.0	71.9
CV-24030	9/21/2026 9:15:00 AM					1370					
CV-24030	9/21/2026 9:21:19 AM	10.1	69.8	1.9	18.2			0.1	9.6	186.0	76.3
CV-24030	9/28/2026 8:35:00 AM					1870					
CV-24030	9/28/2026 8:36:53 AM	5.1	68.0	3.2	23.7			0.1	7.4	88.0	75.3
CV-24031	9/1/2026 2:26:16 PM	26.8	62.4	0.2	10.6			0.4	53.0	141.5	141.3
CV-24031	9/3/2026 8:12:54 AM	3.4	80.3	0.0	16.3			0.0	0.0	146.7	147.4
CV-24031	9/3/2026 8:17:00 AM					670.5					
CV-24031	9/3/2026 8:17:00 AM						78250				
CV-24031	9/9/2026 9:07:06 AM	19.1	73.2	0.0	7.7			0.3	0.0	157.9	158.1
CV-24031	9/9/2026 9:10:00 AM					712.5					
CV-24031	9/15/2026 9:52:53 AM	31.2	68.8	0.0	0.0			0.5	0.0	162.0	162.5
CV-24031	9/15/2026 9:57:00 AM					1030					
CV-24031	9/22/2026 9:40:37 AM	24.7	60.7	0.0	14.6			0.4	0.0	157.0	157.6
CV-24031	9/22/2026 9:44:00 AM					818					
CV-24031	9/29/2026 9:04:40 AM	42.3	57.7	0.0	0.0			0.7	0.0	155.9	155.7
CV-24031	9/29/2026 9:10:00 AM					781					

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24032	9/3/2026 7:35:00 AM					2000					
CV-24032	9/3/2026 8:05:00 AM						139400				
CV-24032	9/3/2026 8:05:26 AM	3.4	78.5	0.0	18.1			0.0	0.0	195.9	196.2
CV-24032	9/3/2026 8:06:12 AM	4.1	65.4	0.0	30.5			0.1	0.0	196.4	196.6
CV-24032	9/9/2026 9:02:42 AM	6.3	76.2	0.0	17.5			0.1	0.0	195.4	195.3
CV-24032	9/9/2026 9:04:00 AM					1280					
CV-24032	9/15/2026 9:43:54 AM	7.4	74.8	0.0	17.8			0.1	0.0	195.9	195.9
CV-24032	9/15/2026 9:47:00 AM					1380					
CV-24032	9/22/2026 9:35:52 AM	19.9	69.0	0.0	11.1			0.3	0.0	192.5	192.3
CV-24032	9/22/2026 9:38:00 AM					887					
CV-24032	9/29/2026 9:01:56 AM	39.2	60.8	0.0	0.0			0.6	0.0	181.8	181.4
CV-24032	9/29/2026 9:05:00 AM					887					
CV-24033	9/3/2026 7:35:00 AM					2500					
CV-24033	9/3/2026 7:35:00 AM						191400				
CV-24033	9/3/2026 7:42:08 AM	2.4	79.6	0.0	18.0			0.0	0.0	193.6	194.1
CV-24033	9/9/2026 8:52:55 AM	6.3	69.9	0.0	23.8			0.1	0.0	193.3	193.5
CV-24033	9/9/2026 8:55:00 AM					2210					
CV-24033	9/15/2026 9:28:55 AM	5.1	65.3	0.0	29.6			0.1	0.0	196.9	196.7
CV-24033	9/15/2026 9:32:00 AM					2480					
CV-24033	9/22/2026 9:22:23 AM	5.7	76.4	0.0	17.9			0.1	0.0	194.7	194.4
CV-24033	9/22/2026 9:27:00 AM					2060					
CV-24033	9/29/2026 8:53:18 AM	11.3	74.0	0.0	14.7			0.2	0.0	193.8	193.3
CV-24033	9/29/2026 8:55:00 AM					1675					
CV-24034	9/8/2026 1:21:00 PM					1040					
CV-24034	9/8/2026 1:24:32 PM	2.2	78.9	0.7	18.2			0.0	26.0	153.4	153.9
CV-24034	9/14/2026 10:06:34 AM	10.7	69.9	0.0	19.4			0.2	0.0	163.6	163.2

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24034	9/14/2026 10:09:00 AM					960					
CV-24034	9/21/2026 10:18:00 AM					994					
CV-24034	9/21/2026 10:19:16 AM	13.5	71.4	0.0	15.1			0.2	0.0	182.8	197.3
CV-24034	9/21/2026 10:20:16 AM	12.1	69.9	0.0	18.0			0.2	0.0	196.8	196.4
CV-24034	9/28/2026 10:07:28 AM	12.8	70.6	0.0	16.6			0.2	0.0	177.0	177.6
CV-24034	9/28/2026 10:15:00 AM					1110					
CV-24035-PL	9/8/2026 9:27:31 AM	1.4	75.1	0.0	23.5			0.0	0.0	189.3	190.0
CV-24035-PL	9/8/2026 9:29:00 AM					1980					
CV-24035-PL	9/14/2026 8:17:00 AM					1520					
CV-24035-PL	9/14/2026 8:17:07 AM	2.2	83.6	0.1	14.1			0.0	141.0	176.6	174.6
CV-24035-PL	9/21/2026 8:14:30 AM	3.7	80.9	0.0	15.4			0.0	0.0	187.0	186.7
CV-24035-PL	9/21/2026 8:15:00 AM					1395					
CV-24035-PL	9/28/2026 7:53:30 AM	1.8	80.8	0.0	17.4			0.0	0.0	184.8	183.9
CV-24035-PL	9/28/2026 7:55:00 AM					1915					
CV-24036	9/1/2026 2:33:35 PM	52.4	40.8	0.9	5.9			1.3	6.6	101.4	101.5
CV-24036	9/11/2026 2:07:19 PM	61.3	37.8	0.9	0.0			1.6	0.0	110.0	110.2
CV-24036	9/11/2026 2:08:24 PM	60.7	38.4	0.9	0.0			1.6	0.0	110.0	109.8
CV-24036	9/24/2026 11:11:10 AM	52.3	40.8	0.7	6.2			1.3	8.9	107.8	108.0
CV-24037	9/1/2026 3:35:53 PM	19.6	59.1	2.8	18.5			0.3	6.6	117.9	117.8
CV-24037	9/24/2026 11:22:54 AM	40.6	40.3	3.5	15.6			1.0	4.5	122.1	120.0
CV-24038	9/14/2026 11:13:08 AM	5.0	77.7	0.0	17.3			0.1	0.0	185.2	185.2
CV-24038	9/14/2026 11:14:07 AM	4.6	78.0	0.0	17.4			0.1	0.0	185.6	185.6
CV-24038	9/14/2026 2:15:00 PM					1820					
CV-24038	9/21/2026 10:10:47 AM	3.0	77.7	0.0	19.3			0.0	0.0	194.9	195.1
CV-24038	9/21/2026 10:20:00 AM					1610					
CV-24038	9/22/2026 10:40:33 AM	18.8	68.5	0.0	12.7			0.3	0.0	197.1	197.1
CV-24038	9/29/2026 9:21:20 AM	16.8	72.2	0.0	11.0			0.2	0.0	194.0	194.3
CV-24038	9/29/2026 9:30:00 AM					1690					

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24039	9/3/2026 8:43:35 AM	1.1	6.2	17.9	74.8			0.2	4.2	94.7	94.5
CV-24039	9/3/2026 8:45:09 AM	1.1	6.8	17.8	74.3			0.2	4.2	94.3	94.5
CV-24039	9/29/2026 9:17:59 AM	0.0	1.5	17.8	80.7			0.0	4.5	97.3	95.8
CV-24039	9/29/2026 9:18:59 AM	0.1	1.3	17.5	81.1			0.1	4.6	98.6	97.5
CV-24040	9/3/2026 8:50:25 AM	3.9	72.4	1.1	22.6			0.1	20.5	172.8	172.5
CV-24040	9/3/2026 8:52:00 AM					1960					
CV-24040	9/3/2026 8:52:00 AM						197000				
CV-24040	9/9/2026 9:53:48 AM	15.1	74.3	0.0	10.6			0.2	0.0	176.2	176.6
CV-24040	9/9/2026 9:55:00 AM					2690					
CV-24040	9/15/2026 10:32:00 AM					2370					
CV-24040	9/15/2026 10:35:47 AM	4.0	65.0	2.3	28.7			0.1	12.5	145.3	146.1
CV-24040	9/15/2026 10:38:31 AM	3.5	67.5	1.2	27.8			0.1	23.2	143.0	143.5
CV-24040	9/21/2026 8:14:52 AM	0.5	11.5	16.5	71.5			0.0	4.3	74.6	75.1
CV-24040	9/21/2026 8:16:09 AM	0.5	12.5	16.5	70.5			0.0	4.3	75.5	75.8
CV-24041	9/9/2026 11:11:38 AM	3.3	22.3	15.7	58.7			0.1	3.7	114.6	114.8
CV-24041	9/23/2026 1:19:53 PM	0.0	0.3	20.3	79.4			0.0	3.9	108.2	108.1
CV-24042	9/8/2026 1:36:57 PM	5.4	73.9	0.0	20.7			0.1	0.0	180.9	180.4
CV-24042	9/8/2026 1:37:00 PM					1400					
CV-24042	9/14/2026 10:23:07 AM	12.8	75.5	0.0	11.7			0.2	0.0	181.5	182.9
CV-24042	9/14/2026 10:27:00 AM					1540					
CV-24042	9/21/2026 10:29:12 AM	25.0	65.8	0.0	9.2			0.4	0.0	176.1	175.2
CV-24042	9/21/2026 10:32:00 AM					1040					
CV-24042	9/28/2026 10:28:10 AM	16.0	72.8	0.0	11.2			0.2	0.0	182.3	179.2
CV-24042	9/28/2026 10:30:00 AM					1850					
CV-24043	9/14/2026 2:27:14 PM	42.7	57.3	0.0	0.0			0.7	0.0	104.9	105.0
CV-24043	9/30/2026 4:24:40 PM	37.9	56.9	0.1	5.1			0.7	51.0	122.0	122.0

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24044	9/3/2026 8:17:38 AM	23.0	69.9	0.0	7.1			0.3	0.0	149.0	149.4
CV-24044	9/3/2026 8:23:00 AM					596					
CV-24044	9/3/2026 8:23:00 AM						67000				
CV-24044	9/9/2026 9:15:54 AM	29.2	69.2	0.0	1.6			0.4	0.0	151.3	152.4
CV-24044	9/9/2026 9:17:00 AM					596					
CV-24044	9/14/2026 9:52:00 AM					2440					
CV-24044	9/15/2026 10:10:54 AM	33.3	66.0	0.0	0.7			0.5	0.0	157.9	159.7
CV-24044	9/15/2026 10:12:00 AM					584					
CV-24044	9/22/2026 9:50:00 AM					530					
CV-24044	9/22/2026 9:56:36 AM	36.8	63.1	0.0	0.1			0.6	0.0	158.2	157.7
CV-24044	9/29/2026 9:08:25 AM	36.6	63.4	0.0	0.0			0.6	0.0	154.6	154.9
CV-24044	9/29/2026 9:15:00 AM					577					
CV-24045	9/3/2026 8:23:14 AM	25.5	70.7	0.0	3.8			0.4	0.0	185.3	185.5
CV-24045	9/3/2026 8:27:00 AM					1750					
CV-24045	9/3/2026 8:27:00 AM						161100				
CV-24045	9/9/2026 9:26:00 AM					458					
CV-24045	9/9/2026 9:29:21 AM	15.0	65.6	1.3	18.1			0.2	13.9	188.3	188.6
CV-24045	9/15/2026 10:14:44 AM	33.2	66.7	0.0	0.1			0.5	0.0	187.7	187.9
CV-24045	9/15/2026 10:18:00 AM					1150					
CV-24045	9/22/2026 10:34:00 AM					1600					
CV-24045	9/22/2026 10:37:26 AM	18.9	71.5	0.4	9.2			0.3	23.0	190.1	189.4
CV-24045	9/29/2026 9:16:50 AM	18.4	70.5	0.5	10.6			0.3	21.2	184.9	185.3
CV-24045	9/29/2026 9:17:31 AM	18.2	70.8	0.4	10.6			0.3	26.5	185.8	186.0
CV-24045	9/29/2026 9:25:00 AM					1910					
CV-24046	9/14/2026 10:32:13 AM	1.0	73.1	0.3	25.6			0.0	85.3	180.2	180.4
CV-24046	9/14/2026 10:32:44 AM	1.1	74.5	0.4	24.0			0.0	60.0	182.1	182.3
CV-24046	9/21/2026 9:20:00 AM					1830					
CV-24046	9/21/2026 9:25:30 AM	0.2	72.2	1.1	26.5			0.0	24.1	184.8	185.5

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24046	9/21/2026 9:27:21 AM	0.2	73.0	0.1	26.7			0.0	267.0	184.0	184.7
CV-24046	9/22/2026 1:28:16 PM	8.8	75.2	0.0	16.0			0.1	0.0	147.0	146.9
CV-24046	9/22/2026 1:32:00 PM	8.9	73.2	0.2	17.7			0.1	88.5	147.0	146.8
CV-24046	9/29/2026 9:35:00 AM					1740					
CV-24046	9/29/2026 9:38:38 AM	10.4	71.9	0.0	17.7			0.1	0.0	172.7	173.5
CV-24048	9/9/2026 11:14:18 AM	4.4	29.0	11.7	54.9			0.2	4.7	120.2	120.5
CV-24048	9/23/2026 1:23:23 PM	6.5	76.6	0.1	16.8			0.1	168.0	106.2	107.2
CV-24049	9/10/2026 9:20:00 AM					1700					
CV-24049	9/10/2026 9:20:00 AM						150000				
CV-24049	9/14/2026 9:39:50 AM	4.0	77.2	0.0	18.8			0.1	0.0	183.4	183.4
CV-24049	9/14/2026 9:40:16 AM	4.2	78.7	0.0	17.1			0.1	0.0	183.8	183.8
CV-24049	9/14/2026 10:45:00 AM					2200					
CV-24049	9/21/2026 9:35:00 AM					1820					
CV-24049	9/21/2026 9:40:32 AM	4.5	71.0	0.0	24.5			0.1	0.0	187.6	188.7
CV-24049	9/21/2026 9:41:36 AM	4.5	74.2	0.0	21.3			0.1	0.0	189.2	189.3
CV-24049	9/28/2026 2:11:38 PM	8.0	78.8	0.0	13.2			0.1	0.0	187.9	187.8
CV-24049	9/28/2026 2:40:00 PM					1750					
CV-24050	9/14/2026 2:38:57 PM	47.5	41.7	0.0	10.8			1.1	0.0	121.8	121.8
CV-24050	9/30/2026 2:26:44 PM	27.6	36.5	0.0	35.9			0.8	0.0	119.4	118.7
CV-24051	9/14/2026 11:02:47 AM	28.6	47.6	3.4	20.4			0.6	6.0	107.7	108.0
CV-24051	9/24/2026 11:45:13 AM	25.4	62.0	2.4	10.2			0.4	4.3	111.8	114.0
CV-24052	9/14/2026 10:13:38 AM	21.9	42.1	4.2	31.8			0.5	7.6	126.3	126.3
CV-24052	9/14/2026 10:14:40 AM	26.9	49.8	1.8	21.5			0.5	11.9	127.4	127.5
CV-24052	9/23/2026 1:29:49 PM	32.5	39.7	0.5	27.3			0.8	54.6	113.0	115.7
CV-24053	9/8/2026 7:40:00 AM					58					
CV-24053	9/8/2026 7:40:00 AM						8800				
CV-24053	9/14/2026 10:03:36 AM	31.7	46.1	0.0	22.2			0.7	0.0	106.3	106.7
CV-24053	9/23/2026 1:26:37 PM	28.6	49.0	0.2	22.2			0.6	111.0	118.6	119.2
CV-24054	9/8/2026 1:44:40 PM	8.9	77.3	0.0	13.8			0.1	0.0	171.5	171.4
CV-24054	9/8/2026 1:48:00 PM					894.5					

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24054	9/14/2026 10:33:37 AM	28.0	0.0	0.0	72.0				0.0	167.8	167.9
CV-24054	9/14/2026 10:34:00 AM					1080					
CV-24054	9/21/2026 10:34:28 AM	27.3	59.7	0.0	13.0			0.5	0.0	177.0	177.0
CV-24054	9/21/2026 10:37:00 AM					977					
CV-24054	9/28/2026 10:42:38 AM	22.8	65.3	0.0	11.9			0.3	0.0	161.1	161.9
CV-24054	9/28/2026 10:45:00 AM					1360					
CV-24055	9/10/2026 9:25:00 AM					1400					
CV-24055	9/10/2026 9:25:00 AM						85000				
CV-24055	9/14/2026 9:36:06 AM	4.9	55.9	3.0	36.2			0.1	12.1	122.0	122.3
CV-24055	9/30/2026 8:16:47 AM	4.6	41.3	5.3	48.8			0.1	9.2	151.0	151.0
CV-24055	9/30/2026 8:17:55 AM	4.5	41.9	5.1	48.5			0.1	9.5	151.0	151.0
CV-24055	9/30/2026 10:20:00 AM					322					
CV-24056	9/1/2026 9:14:34 AM	23.1	66.2	0.0	10.7			0.3	0.0	99.1	99.2
CV-24056	9/22/2026 11:03:33 AM	25.0	45.7	0.0	29.3			0.5	0.0	117.8	117.7
CV-24057	9/14/2026 2:15:25 PM	34.7	58.8	0.0	6.5			0.6	0.0	147.4	146.9
CV-24057	9/14/2026 2:16:28 PM	34.2	65.8	0.0	0.0			0.5	0.0	145.7	145.5
CV-24057	9/14/2026 3:00:00 PM					1540					
CV-24057	9/17/2026 10:27:01 AM	14.3	74.9	0.1	10.7			0.2	107.0	148.9	148.6
CV-24057	9/21/2026 10:46:29 AM	19.4	72.3	0.0	8.3			0.3	0.0	149.3	152.4
CV-24057	9/21/2026 10:47:11 AM	19.3	72.3	0.0	8.4			0.3	0.0	152.7	152.8
CV-24057	9/21/2026 10:50:00 AM					1250					
CV-24058	9/11/2026 1:53:52 PM	45.8	37.2	0.1	16.9			1.2	169.0	111.4	112.8
CV-24058	9/11/2026 1:55:09 PM	44.2	35.8	0.0	20.0			1.2	0.0	111.7	112.0
CV-24058	9/17/2026 10:38:59 AM	30.9	36.0	0.3	32.8			0.9	109.3	100.9	101.0
CV-24059	9/2/2026 9:05:00 AM					684					
CV-24059	9/2/2026 9:05:00 AM						150200				
CV-24059	9/2/2026 9:06:09 AM	20.6	65.5	0.0	13.9			0.3	0.0	156.5	156.6
CV-24059	9/8/2026 9:49:40 AM	13.0	66.7	0.3	20.0			0.2	66.7	154.3	155.9
CV-24059	9/8/2026 9:50:00 AM					489.5					
CV-24059	9/8/2026 9:51:20 AM	12.6	69.0	0.1	18.3			0.2	183.0	155.5	155.9
CV-24059	9/16/2026 1:37:00 PM					691					

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24059	9/16/2026 1:42:42 PM	25.8	71.4	0.0	2.8			0.4	0.0	160.2	159.9
CV-24059	9/23/2026 1:24:51 PM	29.7	70.3	0.0	0.0			0.4	0.0	156.7	156.9
CV-24059	9/23/2026 1:27:00 PM					431					
CV-24059	9/30/2026 10:05:00 AM					339					
CV-24059	9/30/2026 10:08:00 AM	45.3	54.7	0.0	0.0			0.8	0.0	155.4	155.4
CV-24060	9/2/2026 9:45:32 AM	31.8	61.7	0.2	6.3			0.5	31.5	133.0	130.7
CV-24060	9/17/2026 11:02:39 AM	29.4	62.2	0.3	8.1			0.5	27.0	126.1	126.7
CV-24061	9/2/2026 9:52:58 AM	44.6	54.6	0.0	0.8			0.8	0.0	102.4	102.5
CV-24061	9/28/2026 10:31:48 AM	7.2	80.4	0.0	12.4			0.1	0.0	147.6	147.3
CV-24062	9/1/2026 2:14:11 PM	35.7	64.2	0.0	0.1			0.6	0.0	175.4	175.7
CV-24062	9/1/2026 2:15:00 PM					942.5					
CV-24062	9/1/2026 2:15:00 PM						102100				
CV-24062	9/3/2026 7:20:00 AM					840					
CV-24062	9/3/2026 7:20:00 AM						110000				
CV-24062	9/10/2026 8:48:00 AM					1200					
CV-24062	9/16/2026 10:09:38 AM	29.5	65.0	0.0	5.5			0.5	0.0	173.3	173.7
CV-24062	9/16/2026 10:13:00 AM					940.5					
CV-24062	9/23/2026 10:16:47 AM	40.6	59.4	0.0	0.0			0.7	0.0	178.3	178.8
CV-24062	9/23/2026 10:19:00 AM					175					
CV-24062	9/30/2026 9:17:26 AM	19.7	75.5	0.0	4.8			0.3	0.0	170.1	170.4
CV-24062	9/30/2026 9:20:00 AM					1800					
CV-24063	9/1/2026 2:00:39 PM	8.4	79.6	0.0	12.0			0.1	0.0	186.3	186.3
CV-24063	9/1/2026 2:05:00 PM					1970					
CV-24063	9/1/2026 2:05:00 PM						96900				
CV-24063	9/3/2026 7:20:00 AM					1400					
CV-24063	9/3/2026 7:20:00 AM						110000				
CV-24063	9/10/2026 8:38:00 AM					1230					
CV-24063	9/10/2026 8:38:14 AM	17.9	79.7	0.0	2.4			0.2	0.0	188.1	185.2
CV-24063	9/10/2026 8:39:09 AM	17.9	76.6	0.0	5.5			0.2	0.0	184.9	184.7

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24063	9/14/2026 2:32:38 PM	11.5	76.5	0.0	12.0			0.2	0.0	183.6	183.7
CV-24063	9/15/2026 10:47:20 AM	11.5	74.0	0.0	14.5			0.2	0.0	183.9	184.0
CV-24063	9/17/2026 12:22:16 PM	9.6	75.9	0.0	14.5			0.1	0.0		
CV-24063	9/17/2026 1:33:24 PM	21.7	70.2	0.0	8.1			0.3	0.0	167.8	167.7
CV-24063	9/17/2026 1:34:00 PM					1190					
CV-24063	9/23/2026 10:11:45 AM	32.2	67.7	0.0	0.1			0.5	0.0	167.4	167.5
CV-24063	9/23/2026 10:13:00 AM					1410					
CV-24063	9/30/2026 9:08:35 AM	24.7	75.3	0.0	0.0			0.3	0.0	133.5	133.1
CV-24063	9/30/2026 9:15:00 AM					731.5					
CV-24064-PL	9/1/2026 1:18:43 PM	37.6	58.3	0.0	4.1			0.6	0.0	191.4	191.5
CV-24064-PL	9/1/2026 1:25:00 PM					2350					
CV-24064-PL	9/1/2026 1:25:00 PM						121100				
CV-24064-PL	9/3/2026 7:30:00 AM					1600					
CV-24064-PL	9/3/2026 7:30:00 AM						140000				
CV-24064-PL	9/9/2026 1:28:11 PM	47.8	52.2	0.0	0.0			0.9	0.0	191.7	192.6
CV-24064-PL	9/9/2026 1:32:00 PM					1940					
CV-24064-PL	9/10/2026 8:45:01 AM	18.7	75.7	0.0	5.6			0.2	0.0	175.2	175.6
CV-24064-PL	9/16/2026 9:05:32 AM	35.8	64.2	0.0	0.0			0.6	0.0	190.2	191.1
CV-24064-PL	9/16/2026 9:14:00 AM					2030					
CV-24064-PL	9/23/2026 9:22:59 AM	46.5	53.5	0.0	0.0			0.9	0.0	188.2	189.7
CV-24064-PL	9/23/2026 9:25:00 AM					1340					
CV-24064-PL	9/30/2026 8:25:00 AM					2020					
CV-24064-PL	9/30/2026 8:38:49 AM	37.9	56.7	0.0	5.4			0.7	0.0	188.1	188.5
CV-24065-TP	9/3/2026 8:57:02 AM	12.8	53.4	2.0	31.8			0.2	15.9	113.3	113.3
CV-24065-TP	9/8/2026 7:50:00 AM					290					
CV-24065-TP	9/8/2026 7:50:00 AM						15000				
CV-24065-TP	9/22/2026 10:39:59 AM	14.0	42.9	0.9	42.2			0.3	46.9	126.3	126.5
CV-24066	9/1/2026 9:11:21 AM	21.0	41.6	0.1	37.3			0.5	373.0	89.1	89.3
CV-24066	9/10/2026 8:15:00 AM					250					
CV-24066	9/10/2026 8:15:00 AM						23000				
CV-24066	9/22/2026 11:00:28 AM	16.9	44.9	0.0	38.2			0.4	0.0	102.6	103.9
CV-24066	9/24/2026 2:36:50 PM	18.0	42.6	0.0	39.4			0.4	0.0	123.0	122.8

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24067	9/29/2026 2:12:24 PM	16.4	47.7	0.0	36.0			0.3	0.0	156.2	156.7
CV-24067	9/29/2026 2:14:48 PM	16.9	45.9	0.0	37.1			0.4	0.0	156.8	156.8
CV-24068	9/3/2026 10:45:39 AM	38.9	49.3	0.2	11.6			0.8	58.0	151.1	151.2
CV-24068	9/3/2026 10:47:00 AM					644					
CV-24068	9/3/2026 10:47:00 AM						42300				
CV-24068	9/8/2026 10:05:00 AM					545					
CV-24068	9/8/2026 10:06:07 AM	25.6	50.6	0.2	23.6			0.5	118.0	145.2	145.3
CV-24068	9/17/2026 1:41:53 PM	24.9	72.0	0.0	3.1			0.3	0.0	140.0	139.9
CV-24069	9/2/2026 8:53:53 AM	21.7	49.7	0.1	28.5			0.4	285.0	117.5	116.7
CV-24069	9/8/2026 7:00:00 AM					580					
CV-24069	9/8/2026 7:00:00 AM						64000				
CV-24069	9/28/2026 10:46:59 AM	11.9	44.8	0.2	43.1			0.3	215.5	126.3	126.4
CV-24070	9/2/2026 8:55:00 AM					1590					
CV-24070	9/2/2026 8:55:00 AM						64200				
CV-24070	9/2/2026 8:55:24 AM	29.3	64.5	0.0	6.2			0.5	0.0	149.4	149.4
CV-24070	9/8/2026 7:10:00 AM					1000					
CV-24070	9/8/2026 7:10:00 AM						82000				
CV-24070	9/9/2026 1:57:00 PM	32.2	67.7	0.1	0.0			0.5	0.0	119.1	119.1
CV-24070	9/9/2026 1:57:46 PM	30.7	69.2	0.1	0.0			0.4	0.0	119.1	119.1
CV-24070	9/10/2026 1:57:00 PM					1370					
CV-24070	9/10/2026 1:59:57 PM	33.6	66.4	0.0	0.0			0.5	0.0	150.7	150.7
CV-24070	9/16/2026 1:23:00 PM					1360					
CV-24070	9/16/2026 1:30:24 PM	42.9	57.1	0.0	0.0			0.8	0.0	144.7	144.7
CV-24071	9/2/2026 9:40:06 AM	24.9	68.0	0.0	7.1			0.4	0.0	138.4	138.3
CV-24071	9/8/2026 7:15:00 AM					550					
CV-24071	9/8/2026 7:15:00 AM						74000				
CV-24071	9/17/2026 2:19:48 PM	33.7	60.4	0.0	5.9			0.6	0.0	134.7	134.0
CV-24072	9/2/2026 1:30:58 PM	42.9	57.1	0.0	0.0			0.8	0.0	111.0	110.0
CV-24072	9/17/2026 2:25:11 PM	25.5	69.4	0.0	5.1			0.4	0.0	110.9	111.6
CV-24073-TP	9/1/2026 2:25:19 PM	47.3	52.7	0.0	0.0			0.9	0.0	157.5	157.6

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24073-TP	9/1/2026 2:30:00 PM					1420					
CV-24073-TP	9/1/2026 2:30:00 PM						47600				
CV-24073-TP	9/9/2026 1:21:38 PM	47.0	52.9	0.1	0.0			0.9	0.0	138.4	138.4
CV-24073-TP	9/21/2026 2:25:32 PM	24.1	71.1	0.2	4.6			0.3	23.0	153.9	154.4
CV-24073-TP	9/30/2026 9:00:28 AM	29.2	65.1	0.0	5.7			0.4	0.0	153.5	153.5
CV-24073-TP	9/30/2026 9:01:24 AM	27.9	64.9	0.0	7.2			0.4	0.0	153.5	153.7
CV-24073-TP	9/30/2026 9:05:00 AM					1170					
CV-24074	9/2/2026 2:20:20 PM	1.5	83.5	0.1	14.9			0.0	149.0	118.3	118.8
CV-24074	9/21/2026 2:20:48 PM	1.1	80.4	0.2	18.3			0.0	91.5	127.9	127.3
CV-24075-TP	9/1/2026 1:27:41 PM	25.5	71.0	1.0	2.5			0.4	2.5	178.5	178.4
CV-24075-TP	9/1/2026 1:34:00 PM					1740					
CV-24075-TP	9/1/2026 1:34:00 PM						67500				
CV-24075-TP	9/9/2026 1:36:18 PM	31.9	66.8	1.3	0.0			0.5	0.0	181.5	181.6
CV-24075-TP	9/9/2026 1:41:00 PM					2030					
CV-24075-TP	9/16/2026 9:26:05 AM	10.8	82.6	0.0	6.6			0.1	0.0	182.3	182.3
CV-24075-TP	9/16/2026 9:28:00 AM					2100					
CV-24075-TP	9/23/2026 9:31:50 AM	37.0	62.2	0.8	0.0			0.6	0.0	181.4	181.5
CV-24075-TP	9/23/2026 9:35:00 AM					770					
CV-24075-TP	9/30/2026 8:50:15 AM	27.7	66.7	1.3	4.3			0.4	3.3	179.1	179.2
CV-24075-TP	9/30/2026 8:55:00 AM					1710					
CV-24076	9/1/2026 1:45:00 PM					1040					
CV-24076	9/1/2026 1:45:00 PM						41400				
CV-24076	9/1/2026 1:45:11 PM	24.0	44.9	3.8	27.3			0.5	7.2	167.6	167.4
CV-24076	9/1/2026 1:49:10 PM	23.4	45.1	3.9	27.6			0.5	7.1	172.5	172.2
CV-24076	9/9/2026 1:57:00 PM					818					
CV-24076	9/9/2026 1:58:23 PM	24.4	43.2	4.1	28.3			0.6	6.9	172.5	174.2
CV-24076	9/16/2026 9:59:57 AM	5.9	82.1	0.0	12.0			0.1	0.0	171.0	171.8
CV-24076	9/16/2026 10:02:00 AM					1010					
CV-24076	9/23/2026 9:57:00 AM	29.0	37.9	2.4	30.7			0.8	12.8	168.5	168.0
CV-24076	9/30/2026 9:00:43 AM	23.1	39.3	2.8	34.8			0.6	12.4	160.5	160.0

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24076	9/30/2026 9:05:00 AM					881					
CV-24077	9/1/2026 9:39:47 AM	22.7	57.4	0.0	19.9			0.4	0.0	143.9	140.9
CV-24077	9/1/2026 11:02:58 AM	21.6	66.2	0.0	12.2			0.3	0.0	136.0	136.1
CV-24077	9/1/2026 2:25:00 PM					1330					
CV-24077	9/1/2026 2:25:00 PM						40000				
CV-24077	9/1/2026 2:29:54 PM	26.5	69.3	0.0	4.2			0.4	0.0	154.1	153.7
CV-24077	9/8/2026 10:33:07 AM	13.8	68.9	0.0	17.3			0.2	0.0	157.3	157.6
CV-24077	9/8/2026 10:35:00 AM					1800					
CV-24077	9/14/2026 9:40:00 AM					1290					
CV-24077	9/14/2026 9:41:46 AM	15.5	60.1	0.0	24.4			0.3	0.0	157.7	157.8
CV-24077	9/14/2026 10:22:00 AM	14.6	65.1	0.0	20.3			0.2	0.0	157.5	157.3
CV-24077	9/22/2026 12:59:33 PM	11.5	75.8	0.0	12.7			0.2	0.0	154.3	154.5
CV-24077	9/22/2026 1:00:24 PM	12.5	78.5	0.0	9.0			0.2	0.0	155.1	155.1
CV-24077	9/23/2026 1:52:00 PM					950					
CV-24077	9/23/2026 1:52:12 PM	25.8	60.5	0.0	13.7			0.4	0.0	156.0	156.2
CV-24077	9/30/2026 1:55:00 PM					1370					
CV-24077	9/30/2026 1:57:09 PM	24.7	63.6	0.0	11.7			0.4	0.0	156.0	156.0
CV-24078	9/1/2026 11:05:35 AM	7.9	63.9	3.2	25.0			0.1	7.8	108.7	108.8
CV-24078	9/22/2026 10:57:51 AM	15.2	62.6	3.2	19.0			0.2	5.9	113.9	113.9
CV-24079-TP	9/1/2026 10:56:25 AM	0.8	83.0	0.0	16.2			0.0	0.0	94.4	94.4
CV-24079-TP	9/21/2026 11:00:53 AM	18.8	68.1	0.1	13.0			0.3	130.0	170.4	169.1
CV-24079-TP	9/21/2026 11:03:19 AM	8.1	76.6	0.1	15.2			0.1	152.0	169.1	170.4
CV-24079-TP	9/28/2026 10:34:01 AM	19.0	75.6	0.0	5.4			0.3	0.0	166.5	166.1
CV-24079-TP	9/30/2026 9:15:00 AM					1100					
CV-24079-TP	9/30/2026 9:17:09 AM	20.2	64.4	0.0	15.4			0.3	0.0	162.3	163.3
CV-24080	9/1/2026 10:50:48 AM	18.9	68.8	0.0	12.3			0.3	0.0	123.5	123.6
CV-24080	9/9/2026 2:19:31 PM	31.2	48.7	0.0	20.1			0.6	0.0	128.3	128.4
CV-24080	9/17/2026 10:09:09 AM	41.2	56.1	0.0	2.7			0.7	0.0	119.7	119.5
CV-24081-TP	9/2/2026 9:06:17 AM	25.0	73.7	0.1	1.2			0.3	12.0	104.7	104.7
CV-24081-TP	9/17/2026 1:48:26 PM	27.7	71.4	0.0	0.9			0.4	0.0	107.8	107.9
CV-24082	9/2/2026 9:30:43 AM	43.2	54.8	0.0	2.0			0.8	0.0	122.8	122.5
CV-24082	9/17/2026 1:53:48 PM	43.3	53.8	0.0	2.9			0.8	0.0	126.1	125.2

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24083	9/2/2026 8:49:34 AM	30.6	66.2	0.0	3.2			0.5	0.0	157.9	158.8
CV-24083	9/2/2026 8:50:00 AM					1430					
CV-24083	9/2/2026 8:50:00 AM						76700				
CV-24083	9/8/2026 10:18:45 AM	19.3	68.8	0.1	11.8			0.3	118.0	152.8	153.8
CV-24083	9/8/2026 10:20:00 AM					1360					
CV-24083	9/17/2026 1:55:13 PM	40.8	59.2	0.0	0.0			0.7	0.0	154.0	152.8
CV-24083	9/17/2026 1:57:00 PM					703.5					
CV-24083	9/23/2026 1:21:00 PM					1060					
CV-24083	9/23/2026 1:23:41 PM	7.6	74.2	0.0	18.2			0.1	0.0	149.5	148.0
CV-24083	9/30/2026 10:01:53 AM	39.9	60.1	0.0	0.0			0.7	0.0	137.8	138.2
CV-24084-TP	9/2/2026 8:41:51 AM	28.3	71.2	0.0	0.5			0.4	0.0	185.2	185.4
CV-24084-TP	9/2/2026 8:45:00 AM					2215					
CV-24084-TP	9/2/2026 8:45:00 AM						106300				
CV-24084-TP	9/8/2026 10:20:41 AM	2.3	80.9	0.0	16.8			0.0	0.0	187.2	187.4
CV-24084-TP	9/8/2026 10:25:00 AM					3620					
CV-24084-TP	9/17/2026 1:59:08 PM	39.8	60.2	0.0	0.0			0.7	0.0	186.2	186.0
CV-24084-TP	9/17/2026 2:02:00 PM					3220					
CV-24084-TP	9/23/2026 1:13:00 PM					2770					
CV-24084-TP	9/23/2026 1:16:20 PM	7.0	79.8	0.0	13.2			0.1	0.0	186.1	186.3
CV-24084-TP	9/30/2026 9:55:00 AM					2810					
CV-24084-TP	9/30/2026 9:57:04 AM	8.2	79.0	0.0	12.8			0.1	0.0	185.3	185.2
CV-24085	9/1/2026 11:10:02 AM	40.6	51.9	0.0	7.5			0.8	0.0	93.7	93.6
CV-24085	9/1/2026 11:10:35 AM	41.7	51.9	0.0	6.4			0.8	0.0	93.6	93.6
CV-24085	9/9/2026 2:14:51 PM	27.6	40.0	0.0	32.4			0.7	0.0	133.8	132.8
CV-24085	9/9/2026 2:15:24 PM	27.8	39.9	0.0	32.3			0.7	0.0	132.6	132.6
CV-24085	9/18/2026 4:38:39 PM	24.4	33.8	0.1	41.7			0.7	417.0	130.9	129.8
CV-24086	9/1/2026 10:18:55 AM	39.1	48.2	0.0	12.7			0.8	0.0	126.2	126.9
CV-24086	9/17/2026 9:56:01 AM	39.7	46.0	0.1	14.2			0.9	142.0	127.3	127.4
CV-24087	9/14/2026 1:57:58 PM	49.2	43.1	0.0	7.7			1.1	0.0	121.5	121.3
CV-24087	9/21/2026 9:41:26 AM	44.1	42.0	0.8	13.1			1.1	16.4	123.4	123.3
CV-24088	9/2/2026 1:21:22 PM	47.4	52.6	0.0	0.0			0.9	0.0	112.6	113.1

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24088	9/17/2026 3:03:53 PM	44.8	51.9	0.1	3.2			0.9	32.0	104.5	104.8
CV-24089	9/1/2026 2:52:55 PM	44.6	46.2	0.0	9.2			1.0	0.0	129.3	129.5
CV-24089	9/22/2026 2:06:04 PM	31.6	40.4	0.1	27.9			0.8	279.0	129.1	129.2
CV-24090	9/3/2026 12:03:50 PM	44.6	51.4	0.0	4.0			0.9	0.0	113.4	113.3
CV-24090	9/14/2026 1:45:37 PM	42.7	49.3	0.0	8.0			0.9	0.0	117.0	116.6
CV-24090	9/21/2026 9:16:50 AM	40.0	49.7	0.0	10.3			0.8	0.0	108.3	108.4
CV-24091	9/14/2026 1:37:49 PM	54.6	42.3	0.0	3.1			1.3	0.0	111.2	111.3
CV-24091	9/21/2026 8:59:41 AM	56.2	40.7	0.0	3.1			1.4	0.0	98.8	100.0
CV-24092	9/14/2026 1:27:47 PM	51.3	45.1	0.0	3.6			1.1	0.0	119.4	119.5
CV-24092	9/24/2026 2:16:45 PM	50.9	46.7	0.0	2.4			1.1	0.0	119.9	119.8
CV-24093	9/13/2026 9:56:20 AM	29.5	22.6	10.3	37.6			1.3	3.6	99.4	98.3
CV-24093	9/13/2026 9:58:10 AM	29.3	21.5	10.2	39.0			1.4	3.8	100.7	100.8
CV-24093	9/28/2026 10:16:44 AM	0.2	3.9	20.0	75.9			0.1	3.8	80.1	80.4
CV-24094	9/14/2026 1:07:34 PM	19.3	70.0	3.0	7.7			0.3	2.6	102.9	102.9
CV-24094	9/22/2026 10:05:46 AM	10.0	73.2	2.2	14.6			0.1	6.6	99.8	99.8
CV-24095	9/1/2026 1:57:31 PM	5.3	71.6	0.0	23.1			0.1	0.0	186.0	186.2
CV-24095	9/1/2026 2:00:00 PM					2620					
CV-24095	9/1/2026 2:00:00 PM						159300				
CV-24095	9/8/2026 1:30:00 PM					2940					
CV-24095	9/8/2026 1:31:41 PM	7.6	78.1	0.1	14.2			0.1	142.0	191.3	191.3
CV-24095	9/10/2026 8:30:00 AM					2200					
CV-24095	9/10/2026 8:30:00 AM						180000				
CV-24095	9/17/2026 9:42:47 AM	11.4	79.9	0.0	8.7			0.1	0.0	192.0	192.1
CV-24095	9/17/2026 9:47:00 AM					3210					
CV-24095	9/24/2026 9:52:08 AM	12.9	68.7	0.0	18.4			0.2	0.0	191.8	191.6
CV-24095	9/24/2026 10:00:00 AM					2670					
CV-24096	9/2/2026 8:14:01 AM	32.6	53.7	2.6	11.1			0.6	4.3	65.8	65.8
CV-24096	9/23/2026 9:26:01 AM	30.5	40.7	4.5	24.3			0.7	5.4	87.7	88.4
CV-24097	9/2/2026 8:18:03 AM	50.5	44.4	0.4	4.7			1.1	11.8	66.2	66.2
CV-24097	9/30/2026 3:17:38 PM	41.6	40.3	0.0	18.1			1.0	0.0	99.3	99.4

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24098	9/2/2026 8:23:38 AM	43.7	51.6	0.3	4.4			0.8	14.7	72.3	72.3
CV-24098	9/23/2026 9:16:20 AM	43.9	48.5	1.3	6.3			0.9	4.8	88.4	89.4
CV-24099	9/2/2026 8:32:12 AM	23.3	50.2	4.6	21.9			0.5	4.8	67.0	66.4
CV-24099	9/23/2026 9:11:30 AM	0.0	4.8	19.5	75.7			0.0	3.9	79.8	80.5
CV-24099	9/23/2026 9:13:00 AM	0.1	2.0	19.9	78.0			0.1	3.9	81.1	81.2
CV-24100	9/2/2026 8:50:27 AM	44.1	52.5	0.3	3.1			0.8	10.3	97.3	97.3
CV-24100	9/2/2026 1:05:00 PM					144					
CV-24100	9/2/2026 1:05:00 PM						5600				
CV-24100	9/2/2026 1:12:10 PM	33.8	66.2	0.0	0.0			0.5	0.0	151.7	153.7
CV-24100	9/2/2026 1:16:31 PM	33.4	66.6	0.0	0.0			0.5	0.0	152.1	152.6
CV-24100	9/8/2026 7:35:00 AM					38					
CV-24100	9/8/2026 7:35:00 AM						6300				
CV-24100	9/8/2026 2:53:01 PM	29.5	70.4	0.1	0.0			0.4	0.0	147.6	148.4
CV-24100	9/8/2026 2:55:00 PM					192					
CV-24100	9/17/2026 2:15:00 PM					348					
CV-24100	9/17/2026 2:19:56 PM	35.9	64.1	0.0	0.0			0.6	0.0	148.6	148.5
CV-24100	9/17/2026 2:21:00 PM	35.6	64.4	0.0	0.0			0.6	0.0	148.7	149.0
CV-24100	9/24/2026 10:19:50 AM	29.3	70.3	0.3	0.1			0.4	0.3	142.1	133.8
CV-24100	9/24/2026 10:25:00 AM					137					
CV-24100	9/28/2026 1:58:23 PM	17.4	80.9	1.1	0.6			0.2	0.5	122.3	125.7
CV-24101	9/8/2026 7:30:00 AM					0					
CV-24101	9/8/2026 7:30:00 AM						1200				
CV-24101	9/28/2026 1:59:13 PM	17.6	80.4	0.5	1.5			0.2	3.0	127.9	128.1
CV-24102	9/2/2026 9:21:46 AM	43.1	47.1	0.0	9.8			0.9	0.0	101.0	101.1
CV-24102	9/22/2026 12:22:15 PM	40.3	52.4	0.0	7.3			0.8	0.0	101.9	101.7
CV-24103	9/1/2026 11:30:43 AM	41.2	42.6	0.0	16.2			1.0	0.0	111.6	111.7
CV-24103	9/21/2026 11:54:27 AM	42.1	41.4	0.0	16.5			1.0	0.0	110.5	110.6
CV-24104	9/1/2026 1:54:55 PM	44.1	49.9	0.0	6.0			0.9	0.0	101.7	101.8
CV-24104	9/3/2026 10:55:10 AM	40.5	53.8	0.0	5.7			0.8	0.0	101.4	101.6

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24104	9/21/2026 12:21:54 PM	41.8	52.5	0.0	5.7			0.8	0.0	102.3	102.2
CV-24105	9/1/2026 2:02:32 PM	45.1	40.6	0.0	14.3			1.1	0.0	118.3	118.3
CV-24105	9/22/2026 3:05:41 PM	41.1	41.4	0.0	17.5			1.0	0.0	118.2	118.3
CV-24106	9/15/2026 12:21:17 PM	42.4	37.3	0.0	20.3			1.1	0.0	129.7	129.1
CV-24106	9/15/2026 12:21:57 PM	41.7	37.7	0.0	20.6			1.1	0.0	129.1	128.8
CV-24107	9/9/2026 1:53:59 PM	38.1	43.2	0.0	18.7			0.9	0.0	126.1	126.9
CV-24108	9/9/2026 1:16:23 PM	44.9	46.7	0.0	8.4			1.0	0.0	136.5	135.0
CV-24108	9/9/2026 1:17:42 PM	45.8	45.8	0.0	8.4			1.0	0.0	135.0	135.0
CV-24109	9/9/2026 12:50:32 PM	30.3	44.7	1.4	23.6			0.7	16.9	124.4	124.6
CV-24110	9/3/2026 1:03:31 PM	26.9	71.4	0.0	1.7			0.4	0.0	131.3	131.5
CV-24111	9/3/2026 1:42:51 PM	41.7	52.5	0.1	5.7			0.8	57.0	117.9	116.7
CV-24112	9/3/2026 1:20:04 PM	46.7	39.5	0.0	13.8			1.2	0.0	130.2	130.2
CV-24114	9/23/2026 9:58:47 AM	54.2	40.5	0.0	5.3			1.3	0.0	121.0	122.0
CV-24116	9/24/2026 1:00:00 PM					20.3					
CV-24116	9/24/2026 1:00:00 PM						3200				
CV-24116	9/24/2026 1:11:51 PM						58000				
CV-24116	9/24/2026 1:12:29 PM	51.0	43.8	0.0	5.2			1.2	0.0	118.7	118.3
CV-24116	9/24/2026 3:03:05 PM					25					
CV-24117	9/24/2026 10:47:16 AM	32.5	38.4	0.0	29.1			0.8	0.0	107.0	107.0
CV-24118	9/1/2026 9:00:54 AM	8.2	79.8	0.0	12.0			0.1	0.0	150.9	150.9
CV-24118	9/2/2026 2:19:21 PM	31.1	52.0	0.0	16.9			0.6	0.0	150.5	151.0
CV-24118	9/2/2026 2:25:00 PM					3750					
CV-24118	9/2/2026 2:25:00 PM						133800				
CV-24118	9/10/2026 9:35:00 AM					3110					
CV-24118	9/10/2026 9:38:23 AM	16.2	73.1	0.0	10.7			0.2	0.0	151.4	151.6
CV-24118	9/17/2026 10:36:18 AM	32.1	62.7	0.0	5.2			0.5	0.0	144.2	144.5
CV-24118	9/17/2026 10:39:00 AM					2010					
CV-24119	9/28/2026 2:35:12 PM	44.0	46.2	0.0	9.8			1.0	0.0	137.1	136.0
CV-24120	9/9/2026 8:10:00 AM					680					
CV-24120	9/9/2026 8:10:00 AM						42000				
CV-24120	9/14/2026 10:25:29 AM	3.3	39.8	10.8	46.1			0.1	4.3	97.7	97.7
CV-24120	9/14/2026 10:27:15 AM	2.5	29.5	12.9	55.1			0.1	4.3	97.7	97.7
CV-24120	9/25/2026 10:26:04 AM	1.7	18.2	15.1	65.0			0.1	4.3	92.2	92.0

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24120	9/28/2026 9:41:44 AM	7.8	92.2	0.0	0.0			0.1	0.0	89.4	84.7
CV-24120	9/28/2026 9:50:35 AM	6.9	89.6	0.9	2.6			0.1	2.9	91.6	91.5
CV-24121	9/3/2026 9:37:51 AM	23.6	52.8	2.6	21.1			0.4	8.0	99.9	125.5
CV-24121	9/3/2026 9:43:25 AM	31.6	51.2	3.6	13.7			0.6	3.8	125.7	125.5
CV-24121	9/10/2026 9:45:00 AM					25					
CV-24121	9/10/2026 9:45:00 AM						1600				
CV-24121	9/25/2026 10:30:06 AM	31.7	67.5	0.0	0.8			0.5	0.0	127.2	127.4
CV-24122	9/8/2026 8:20:00 AM					200					
CV-24122	9/8/2026 8:20:00 AM						15000				
CV-24122	9/15/2026 7:57:25 AM	27.9	24.0	10.3	37.8			1.2	3.7	67.3	67.4
CV-24122	9/15/2026 7:58:33 AM	27.9	24.0	10.3	37.8			1.2	3.7	67.5	67.5
CV-24122	9/25/2026 10:38:50 AM	32.8	27.6	7.3	32.3			1.2	4.4	99.6	100.1
CV-24123	9/3/2026 9:17:50 AM	45.4	50.6	0.0	3.9			0.9	0.0	117.1	117.3
CV-24123	9/11/2026 3:37:45 PM	50.5	49.5	0.0	0.0			1.0	0.0	117.0	
CV-24123	9/11/2026 3:38:20 PM	50.9	49.1	0.0	0.0			1.0	0.0	117.0	
CV-24123	9/23/2026 8:27:33 AM	46.6	49.4	0.0	4.0			0.9	0.0	117.0	116.6
CV-24124	9/15/2026 10:14:34 AM	6.4	67.4	1.3	24.9			0.1	19.2	135.9	136.0
CV-24124	9/15/2026 10:15:20 AM	5.7	71.2	1.3	21.8			0.1	16.8	135.9	135.9
CV-24124	9/29/2026 8:14:35 AM	6.2	60.8	2.3	30.7			0.1	13.1	134.1	133.9
CV-24124	9/29/2026 8:15:27 AM	6.2	61.0	2.3	30.6			0.1	13.2	133.4	133.9
CV-24125-TP	9/9/2026 8:20:00 AM					0					
CV-24125-TP	9/9/2026 8:20:00 AM						1400				
CV-24125-TP	9/14/2026 9:25:49 AM	37.6	48.1	1.5	12.8			0.8	8.5	124.2	121.4
CV-24125-TP	9/29/2026 8:05:16 AM	44.1	51.3	0.0	4.6			0.9	0.0	90.0	89.9
CV-24126	9/8/2026 2:01:24 PM	15.0	63.4	0.0	21.6			0.2	0.0	189.3	189.4
CV-24126	9/8/2026 2:04:00 PM					3490					
CV-24126	9/14/2026 1:36:52 PM	16.3	40.1	2.3	41.3			0.4	18.0	177.6	177.7
CV-24126	9/14/2026 1:40:00 PM					1340					
CV-24126	9/21/2026 1:17:00 PM					1360					
CV-24126	9/21/2026 1:17:21 PM	19.1	34.2	3.2	43.5			0.6	13.6	174.2	174.1

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24126	9/28/2026 1:36:03 PM	13.4	35.4	2.7	48.5			0.4	18.0	174.0	174.2
CV-24126	9/28/2026 1:45:00 PM					1370					
CV-24127	9/8/2026 8:00:00 AM					2600					
CV-24127	9/8/2026 8:00:00 AM						180000				
CV-24127	9/8/2026 2:06:28 PM	8.9	69.4	0.0	21.7			0.1	0.0	177.2	177.2
CV-24127	9/8/2026 2:09:00 PM					3930					
CV-24127	9/14/2026 1:33:01 PM	28.2	67.5	0.0	4.3			0.4	0.0	160.3	160.3
CV-24127	9/14/2026 1:36:00 PM					1620					
CV-24127	9/21/2026 1:12:42 PM	34.5	65.5	0.0	0.0			0.5	0.0	164.0	164.3
CV-24127	9/21/2026 1:13:00 PM					1780					
CV-24127	9/28/2026 1:25:09 PM	26.7	40.6	0.5	32.2			0.7	64.4	151.6	151.4
CV-24127	9/28/2026 1:35:00 PM					1760					
CV-24128	9/9/2026 12:13:22 PM	23.5	70.8	0.3	5.4			0.3	18.0	145.6	123.0
CV-24128	9/9/2026 12:14:49 PM	24.0	69.7	0.3	6.0			0.3	20.0	122.3	122.3
CV-24128	9/10/2026 9:35:00 AM					2700					
CV-24128	9/10/2026 9:35:00 AM						110000				
CV-24128	9/25/2026 9:55:31 AM	23.1	58.8	0.3	17.8			0.4	59.3	127.8	127.8
CV-24129	9/9/2026 12:18:22 PM	43.9	55.4	0.7	0.0			0.8	0.0	130.8	130.8
CV-24129	9/25/2026 9:45:34 AM	45.6	54.4	0.0	0.0			0.8	0.0	130.6	130.0
CV-24130	9/30/2026 2:09:18 PM	18.7	72.0	0.0	9.3			0.3	0.0	126.1	125.6
CV-24131	9/10/2026 1:47:00 PM	40.1	58.5	0.2	1.2			0.7	6.0	127.2	127.3
CV-24132	9/30/2026 10:16:29 AM	50.4	44.1	0.0	5.5			1.1	0.0	129.4	129.7
CV-24133	9/21/2026 8:33:25 AM	48.0	41.7	0.0	10.3			1.2	0.0	123.9	123.7
CV-24134-TP	9/10/2026 1:06:47 PM	21.9	70.2	0.1	7.8			0.3	78.0	153.2	153.0
CV-24134-TP	9/14/2026 1:29:38 PM	25.7	68.2	0.0	6.1			0.4	0.0	152.3	152.0
CV-24134-TP	9/14/2026 1:32:00 PM					2890					
CV-24134-TP	9/21/2026 1:07:00 PM					3140					
CV-24134-TP	9/21/2026 1:09:25 PM	36.4	63.5	0.0	0.1			0.6	0.0	151.7	152.2

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24134-TP	9/28/2026 1:06:51 PM	25.8	69.5	0.0	4.7			0.4	0.0	150.0	150.1
CV-24134-TP	9/28/2026 1:25:00 PM					2760					
CV-24135	9/3/2026 9:48:00 AM					4220					
CV-24135	9/3/2026 9:48:00 AM						141700				
CV-24135	9/3/2026 10:26:41 AM	21.7	71.0	0.0	7.3			0.3	0.0	150.4	150.4
CV-24135	9/10/2026 2:23:00 PM					3960					
CV-24135	9/10/2026 2:26:00 PM	18.0	73.9	0.0	8.1			0.2	0.0	149.4	149.2
CV-24135	9/10/2026 2:27:03 PM	16.8	73.4	0.0	9.8			0.2	0.0	149.3	149.2
CV-24135	9/14/2026 1:23:45 PM	23.7	67.8	0.0	8.5			0.3	0.0	150.1	150.2
CV-24135	9/14/2026 1:27:00 PM					4270					
CV-24135	9/24/2026 1:53:54 PM	20.2	74.8	0.0	5.0			0.3	0.0	150.4	150.4
CV-24135	9/24/2026 1:55:00 PM					4070					
CV-24136	9/10/2026 1:43:56 PM	26.1	64.2	0.2	9.5			0.4	47.5	135.6	135.7
CV-24137	9/28/2026 1:45:23 PM	43.7	44.1	0.0	12.2			1.0	0.0	105.6	104.2
CV-24138	9/2/2026 7:35:00 AM					160					
CV-24138	9/2/2026 7:35:00 AM						25000				
CV-24138	9/2/2026 7:58:13 AM	0.5	10.2	17.4	71.9			0.0	4.1	65.6	65.5
CV-24138	9/2/2026 7:59:07 AM	0.5	10.2	17.3	72.0			0.0	4.2	65.3	65.3
CV-24138	9/30/2026 2:54:56 PM	2.3	72.3	0.2	25.2			0.0	126.0	162.2	161.4
CV-24139	9/1/2026 1:45:00 PM					1070					
CV-24139	9/1/2026 1:45:00 PM						180100				
CV-24139	9/1/2026 1:48:41 PM	5.5	70.8	0.4	23.3			0.1	58.3	145.4	145.4
CV-24139	9/2/2026 7:30:00 AM					720					
CV-24139	9/2/2026 7:30:00 AM						210000				
CV-24139	9/8/2026 1:22:11 PM	8.7	58.3	4.3	28.7			0.1	6.7	110.5	110.5
CV-24139	9/10/2026 2:55:48 PM	1.9	2.1	20.3	75.7			0.9	3.7	132.1	129.5
CV-24139	9/10/2026 3:13:23 PM	9.3	16.2	15.6	58.9			0.6	3.8	127.2	125.3
CV-24139	9/10/2026 3:15:24 PM	8.9	18.3	15.0	57.8			0.5	3.9	125.4	125.4

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24139	9/30/2026 2:51:42 PM	4.2	53.0	7.8	35.0			0.1	4.5	128.4	129.2
CV-24140	9/1/2026 1:40:00 PM					2160					
CV-24140	9/1/2026 1:40:00 PM						182800				
CV-24140	9/1/2026 1:44:48 PM	3.8	74.8	0.0	21.4			0.1	0.0	164.0	164.0
CV-24140	9/2/2026 7:25:00 AM					1400					
CV-24140	9/2/2026 7:25:00 AM						210000				
CV-24140	9/8/2026 1:16:52 PM	3.4	73.7	0.6	22.3			0.0	37.2	165.9	166.0
CV-24140	9/8/2026 1:20:00 PM					2140					
CV-24140	9/17/2026 9:53:55 AM	7.1	72.3	0.3	20.3			0.1	67.7	154.7	153.3
CV-24140	9/17/2026 9:55:00 AM					2120					
CV-24140	9/24/2026 9:42:13 AM	7.8	72.8	0.3	19.1			0.1	63.7	145.3	145.5
CV-24140	9/24/2026 9:45:00 AM					1290					
CV-24141	9/2/2026 7:10:00 AM					26					
CV-24141	9/2/2026 7:10:00 AM						1900				
CV-24141	9/15/2026 9:57:58 AM	2.1	6.4	17.6	73.9			0.3	4.2	90.4	91.6
CV-24141	9/15/2026 9:59:24 AM	2.1	5.6	17.7	74.6			0.4	4.2	92.2	92.1
CV-24141	9/23/2026 9:57:06 AM	0.9	6.1	18.4	74.6			0.1	4.1	95.9	94.6
CV-24142	9/1/2026 1:54:21 PM	4.0	65.9	2.7	27.4			0.1	10.1	128.0	128.2
CV-24142	9/2/2026 7:40:00 AM					1200					
CV-24142	9/2/2026 7:40:00 AM						170000				
CV-24142	9/30/2026 2:58:57 PM	1.6	52.9	7.2	38.3			0.0	5.3	130.5	130.5
CV-24143	9/1/2026 7:40:00 AM					660					
CV-24143	9/1/2026 7:40:00 AM						94000				
CV-24143	9/10/2026 12:19:01 PM	4.8	62.0	5.2	28.0			0.1	5.4	125.2	124.2
CV-24143	9/10/2026 12:20:07 PM	3.9	61.0	5.3	29.8			0.1	5.6	123.9	124.1
CV-24143	9/23/2026 9:50:14 AM	1.7	71.2	2.9	24.2			0.0	8.3	100.3	100.4
CV-24144	9/2/2026 8:20:25 AM	55.9	41.0	0.0	3.1			1.4	0.0	68.7	68.8
CV-24145	9/9/2026 8:26:12 AM	14.9	59.4	0.0	25.7			0.3	0.0	187.7	188.0
CV-24145	9/9/2026 8:28:00 AM					1620					

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24145	9/15/2026 8:52:56 AM	14.4	58.4	0.0	27.2			0.2	0.0	187.1	187.2
CV-24145	9/15/2026 8:55:00 AM					1770					
CV-24145	9/22/2026 8:48:58 AM	12.6	40.1	0.0	47.3			0.3	0.0	187.6	187.6
CV-24145	9/22/2026 8:50:00 AM					1100					
CV-24145	9/29/2026 8:14:25 AM	8.7	72.8	0.0	18.5			0.1	0.0	187.9	187.6
CV-24145	9/29/2026 8:20:00 AM					2250					
CV-24146	9/11/2026 3:43:00 PM	54.5	45.5	0.0	0.0			1.2	0.0	115.0	
CV-24146	9/11/2026 3:43:31 PM	58.8	41.2	0.0	0.0			1.4	0.0		
CV-24146	9/23/2026 8:23:00 AM	54.1	40.1	0.0	5.8			1.3	0.0	113.9	113.9
CV-24146	9/29/2026 7:46:29 AM	52.8	41.6	0.0	5.6			1.3	0.0	113.9	114.1
CV-24146	9/29/2026 7:48:05 AM	52.6	42.0	0.0	5.4			1.3	0.0	114.2	114.2
CV-24147	9/14/2026 8:55:38 AM	52.0	42.3	0.0	5.7			1.2	0.0	115.3	115.3
CV-24147	9/29/2026 7:53:08 AM	49.6	41.1	0.0	9.3			1.2	0.0	113.1	113.2
CV-24148	9/1/2026 1:15:45 PM	32.5	61.0	0.0	6.5			0.5	0.0	167.1	167.2
CV-24148	9/1/2026 1:21:00 PM					983					
CV-24148	9/1/2026 1:21:00 PM						49050				
CV-24148	9/9/2026 1:24:00 PM					1250					
CV-24148	9/9/2026 1:25:02 PM	47.4	52.6	0.0	0.0			0.9	0.0	172.7	172.6
CV-24148	9/16/2026 9:01:24 AM	31.5	67.5	0.0	1.0			0.5	0.0	176.9	177.4
CV-24148	9/16/2026 9:06:00 AM					1580					
CV-24148	9/23/2026 9:17:16 AM	42.1	57.9	0.0	0.0			0.7	0.0	174.7	174.6
CV-24148	9/23/2026 9:21:00 AM					861					
CV-24148	9/30/2026 8:20:00 AM					1060					
CV-24148	9/30/2026 8:33:02 AM	32.0	61.7	0.0	6.3			0.5	0.0	166.2	166.4
CV-24149	9/2/2026 2:26:43 PM	35.9	54.8	0.0	9.3			0.7	0.0	128.5	128.4
CV-24149	9/28/2026 10:08:01 AM	31.9	63.3	0.0	4.8			0.5	0.0	129.0	129.2
CV-24150	9/14/2026 1:00:56 PM	41.8	57.7	0.4	0.1			0.7	0.2	96.0	96.0
CV-24150	9/22/2026 10:00:08 AM	42.7	57.2	0.1	0.0			0.7	0.0	111.8	111.7
CV-24151	9/2/2026 1:38:48 PM	45.9	46.4	0.3	7.4			1.0	24.7	116.4	116.9
CV-24151	9/28/2026 10:24:52 AM	39.9	55.5	0.0	4.6			0.7	0.0	121.9	122.9
CV-24152	9/2/2026 2:13:03 PM	19.3	76.5	0.0	4.2			0.3	0.0	142.5	142.6

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24152	9/2/2026 2:14:21 PM	19.5	76.3	0.0	4.2			0.3	0.0	142.7	142.7
CV-24152	9/21/2026 2:17:53 PM	18.6	72.6	0.2	8.6			0.3	43.0	144.3	144.3
CV-24153	9/2/2026 2:35:08 PM	38.0	61.9	0.0	0.1			0.6	0.0	116.9	116.7
CV-24153	9/28/2026 10:19:05 AM	36.3	63.7	0.0	0.0			0.6	0.0	129.6	129.7
CV-24154	9/3/2026 12:57:36 PM	44.2	52.3	0.0	3.4			0.8	0.0	108.8	109.0
CV-24154	9/24/2026 1:45:55 PM	40.3	58.9	0.0	0.8			0.7	0.0	113.7	113.2
CV-24155	9/2/2026 2:32:05 PM	33.5	61.8	0.0	4.7			0.5	0.0	123.9	124.4
CV-24155	9/28/2026 10:12:48 AM	37.7	56.9	0.0	5.4			0.7	0.0	128.5	128.6
CV-24156	9/2/2026 8:34:18 AM	25.8	69.6	0.0	4.6			0.4	0.0	137.1	137.2
CV-24156	9/2/2026 8:35:16 AM	27.2	71.7	0.0	1.1			0.4	0.0	136.9	137.0
CV-24156	9/17/2026 2:44:43 PM	22.3	70.0	1.1	6.6			0.3	6.0	137.1	137.1
CV-24157	9/2/2026 1:17:03 PM	45.6	54.0	0.4	0.0			0.8	0.0	108.1	108.4
CV-24157	9/17/2026 2:54:47 PM	47.9	51.1	0.0	1.0			0.9	0.0	103.0	103.3
CV-24158	9/2/2026 1:50:00 PM	44.0	56.0	0.0	0.0			0.8	0.0	127.9	127.9
CV-24158	9/18/2026 9:48:59 AM	41.7	58.3	0.0	0.0			0.7	0.0	126.2	126.1
CV-24159	9/13/2026 10:18:12 AM	46.6	49.3	0.0	4.0			0.9	0.0	128.6	128.5
CV-24159	9/13/2026 10:19:02 AM	46.0	49.2	0.0	4.8			0.9	0.0	128.2	128.3
CV-24159	9/25/2026 11:34:39 AM	28.9	68.1	0.0	3.0			0.4	0.0	126.8	130.8
CV-24159	9/25/2026 11:37:32 AM	30.6	66.7	0.0	2.7			0.5	0.0	136.5	135.7
CV-24159	9/25/2026 11:38:14 AM	31.1	65.6	0.0	3.3			0.5	0.0	135.7	135.4
CV-24160	9/13/2026 10:07:13 AM	49.0	47.9	0.0	3.1			1.0	0.0	127.3	127.3
CV-24160	9/13/2026 10:08:00 AM	48.7	47.3	0.0	4.0			1.0	0.0	127.4	127.4
CV-24160	9/24/2026 2:00:04 PM	47.8	52.2	0.0	0.0			0.9	0.0	127.3	127.2
CV-24161	9/14/2026 1:18:54 PM	37.6	49.9	0.0	12.5			0.8	0.0	128.8	128.2
CV-24162	9/9/2026 1:08:06 PM	36.5	38.9	0.3	24.3			0.9	81.0	120.5	120.5
CV-24162	9/14/2026 1:22:08 PM	48.6	48.2	0.0	3.2			1.0	0.0	105.2	105.6
CV-24163	9/1/2026 9:47:08 AM	27.6	69.9	0.0	2.5			0.4	0.0	136.1	136.5
CV-24164	9/2/2026 9:23:46 AM	32.4	67.6	0.0	0.0			0.5	0.0	127.1	126.6
CV-24164	9/2/2026 9:26:17 AM	33.6	66.4	0.0	0.0			0.5	0.0	127.6	83.7

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24164	9/17/2026 2:06:22 PM	32.1	67.9	0.0	0.0			0.5	0.0	132.0	132.4
CV-24164	9/17/2026 2:07:38 PM	34.2	64.2	0.0	1.6			0.5	0.0	132.0	131.3
CV-24165	9/15/2026 1:44:17 PM	26.1	69.3	0.1	4.5			0.4	45.0	122.1	122.1
CV-24165	9/30/2026 1:54:12 PM	21.2	68.0	0.0	10.8			0.3	0.0	130.2	131.3
CV-24165	9/30/2026 2:18:26 PM	40.9	52.0	0.1	7.0			0.8	70.0	122.7	123.1
CV-24166	9/13/2026 10:25:03 AM	52.8	43.4	0.0	3.8			1.2	0.0	113.2	111.9
CV-24166	9/13/2026 10:25:58 AM	52.1	43.6	0.0	4.3			1.2	0.0	112.0	112.1
CV-24166	9/21/2026 8:17:14 AM	57.3	39.8	0.1	2.8			1.4	28.0	107.1	107.4
CV-24167	9/15/2026 9:35:57 AM	38.5	45.4	0.0	16.1			0.8	0.0	113.1	113.1
CV-24167	9/30/2026 1:45:26 PM	53.4	42.6	0.0	4.0			1.3	0.0	120.8	121.4
CV-24167	9/30/2026 1:46:57 PM	52.1	43.2	0.0	4.7			1.2	0.0	122.2	122.0
CV-24168	9/14/2026 2:05:52 PM	32.5	62.4	0.0	5.1			0.5	0.0	135.0	89.3
CV-24168	9/21/2026 9:52:58 AM	37.2	60.1	0.0	2.7			0.6	0.0	131.2	133.4
CV-24169	9/14/2026 2:01:29 PM	41.0	42.0	0.0	17.0			1.0	0.0	119.5	119.2
CV-24169	9/28/2026 10:50:36 AM	33.9	42.5	0.0	23.6			0.8	0.0	119.4	119.4
CV-24170	9/2/2026 9:09:47 AM	6.7	87.4	0.0	5.9			0.1	0.0	125.9	125.9
CV-24170	9/17/2026 1:45:21 PM	7.5	82.5	0.1	9.9			0.1	99.0	129.8	129.8
CV-24171	9/14/2026 1:31:04 PM	53.3	42.5	0.0	4.2			1.3	0.0	125.4	125.5
CV-24171	9/21/2026 8:30:41 AM	53.4	45.4	0.0	1.2			1.2	0.0	123.8	124.4
CV-24172	9/14/2026 1:41:43 PM	50.9	41.7	0.2	7.2			1.2	36.0	127.2	127.2
CV-24172	9/21/2026 9:04:18 AM	49.4	39.7	0.8	10.1			1.2	12.6	125.9	125.8
CV-24173	9/14/2026 1:49:58 PM	9.4	84.7	0.0	5.9			0.1	0.0	136.2	136.1
CV-24173	9/21/2026 9:21:07 AM	8.2	90.2	0.0	1.6			0.1	0.0	134.6	134.7
CV-24174	9/15/2026 1:52:08 PM	32.5	56.0	0.0	11.5			0.6	0.0	111.5	111.5
CV-24174	9/24/2026 8:32:37 AM	32.4	41.9	0.0	25.7			0.8	0.0	128.2	125.5
CV-24175	9/15/2026 9:24:45 AM	41.3	51.1	0.0	7.6			0.8	0.0	110.9	111.0
CV-24175	9/30/2026 8:57:29 AM	14.8	80.4	0.0	4.8			0.2	0.0	114.4	77.5

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24176	9/1/2026 11:15:56 AM	28.1	65.0	0.0	6.9			0.4	0.0	94.8	95.6
CV-24176	9/1/2026 11:16:38 AM	28.0	65.9	0.0	6.1			0.4	0.0	95.9	95.9
CV-24176	9/3/2026 10:17:38 AM	30.3	62.8	0.0	7.0			0.5	0.0	89.4	90.3
CV-24176	9/30/2026 9:16:05 AM	19.0	33.6	2.5	44.9			0.6	18.0	79.0	79.0
CV-24177	9/2/2026 7:09:30 AM	9.2	76.9	0.7	13.2			0.1	18.9	100.1	100.3
CV-24177	9/22/2026 12:56:38 PM	7.7	87.8	1.0	3.5			0.1	3.5	110.4	110.4
CV-24178	9/1/2026 2:59:57 PM	23.4	72.8	0.0	3.8			0.3	0.0	94.2	94.1
CV-24178	9/1/2026 3:02:27 PM	26.6	72.4	0.0	1.0			0.4	0.0	94.5	94.5
CV-24178	9/3/2026 10:29:19 AM	26.6	66.5	0.0	6.9			0.4	0.0	92.0	93.0
CV-24178	9/9/2026 2:38:51 PM	28.2	56.4	0.0	15.4			0.5	0.0	134.4	134.4
CV-24178	9/9/2026 2:41:36 PM	28.3	57.0	0.0	14.7			0.5	0.0	134.4	134.5
CV-24178	9/22/2026 1:58:45 PM	27.2	47.8	0.2	24.8			0.6	124.0	134.0	133.6
CV-24179	9/1/2026 11:22:17 AM	13.5	76.5	0.0	10.0			0.2	0.0	117.2	117.6
CV-24179	9/30/2026 11:41:43 AM	12.0	70.8	1.9	15.3			0.2	8.1	100.3	100.6
CV-24179	9/30/2026 11:42:38 AM	11.8	72.8	1.8	13.6			0.2	7.6	101.8	102.0
CV-24180	9/1/2026 3:04:20 PM	23.8	76.2	0.0	0.0			0.3	0.0	91.6	91.6
CV-24180	9/1/2026 3:05:55 PM	17.2	79.9	0.0	2.9			0.2	0.0	91.8	91.8
CV-24180	9/18/2026 4:27:56 PM	26.9	43.3	0.0	29.8			0.6	0.0	129.4	128.5
CV-24180	9/22/2026 3:35:15 PM	28.6	48.8	0.0	22.6			0.6	0.0	126.2	126.2
CV-24181	9/1/2026 2:56:29 PM	18.4	78.9	0.0	2.7			0.2	0.0	97.8	97.7
CV-24181	9/1/2026 2:57:27 PM	17.1	78.3	0.0	4.6			0.2	0.0	97.4	97.4
CV-24181	9/9/2026 2:02:35 PM	32.6	55.6	0.0	11.8			0.6	0.0	123.6	123.6
CV-24181	9/22/2026 3:27:56 PM	39.9	51.3	0.0	8.8			0.8	0.0	119.2	119.3
CV-24182	9/1/2026 2:49:50 PM	42.7	42.4	0.0	14.9			1.0	0.0	101.6	101.6
CV-24182	9/22/2026 3:17:59 PM	33.4	38.7	1.2	26.7			0.9	22.3	113.5	113.7
CV-24183	9/1/2026 2:44:48 PM	45.4	40.5	0.0	14.1			1.1	0.0	98.2	98.2
CV-24183	9/22/2026 2:15:06 PM	31.4	25.5	0.4	42.7			1.2	106.8	96.2	95.0
CV-24184	9/1/2026 2:29:37 PM	50.0	41.1	0.0	8.9			1.2	0.0	131.1	131.3
CV-24184	9/1/2026 2:34:21 PM	51.8	42.2	0.0	6.0			1.2	0.0	136.3	136.5
CV-24184	9/3/2026 12:22:14 PM	47.8	44.0	1.0	7.3			1.1	7.6	137.6	138.3
CV-24184	9/3/2026 12:23:03 PM	47.4	43.8	1.1	7.7			1.1	7.1	138.4	138.3
CV-24184	9/22/2026 2:21:19 PM	30.8	28.5	4.9	35.8			1.1	7.3	129.7	130.0
CV-24185	9/1/2026 2:19:32 PM	51.2	45.6	0.0	3.2			1.1	0.0	125.9	127.5
CV-24185	9/1/2026 2:20:58 PM	48.4	51.6	0.0	0.0			0.9	0.0	127.6	127.6

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24185	9/3/2026 12:38:20 PM	49.0	48.5	0.0	2.5			1.0	0.0	125.4	125.3
CV-24185	9/22/2026 2:34:09 PM	30.2	27.8	7.9	34.1			1.1	4.3	124.2	124.1
CV-24185	9/22/2026 2:35:54 PM	48.4	42.6	0.1	8.9			1.1	89.0	124.1	124.1
CV-24186	9/15/2026 10:32:27 AM	45.1	34.9	1.7	18.3			1.3	10.8	125.0	124.9
CV-24186	9/22/2026 2:42:35 PM	49.9	39.4	0.5	10.2			1.3	20.4	125.5	126.2
CV-24187	9/2/2026 9:24:10 AM	50.2	45.5	0.0	4.3			1.1	0.0	124.3	124.4
CV-24187	9/22/2026 12:48:46 PM	45.0	53.1	0.0	1.9			0.8	0.0	126.5	126.6
CV-24187	9/22/2026 2:45:38 PM	50.2	40.7	0.1	9.0			1.2	90.0	107.3	107.5
CV-24188	9/2/2026 8:53:02 AM	49.3	45.6	0.0	5.1			1.1	0.0	117.4	117.5
CV-24188	9/22/2026 10:14:23 AM	51.4	44.0	0.0	4.6			1.2	0.0	117.1	117.9
CV-24189	9/2/2026 8:58:47 AM	43.5	34.4	3.5	18.6			1.3	5.3	108.9	108.2
CV-24189	9/22/2026 10:07:55 AM	54.3	41.7	0.0	4.0			1.3	0.0	100.0	104.3
CV-24189	9/22/2026 10:08:53 AM	53.0	41.3	0.3	5.4			1.3	18.0	105.0	105.6
CV-24190	9/2/2026 9:15:42 AM	52.9	42.9	0.0	4.2			1.2	0.0	123.1	123.6
CV-24190	9/22/2026 12:45:58 PM	46.2	53.3	0.5	0.0			0.9	0.0	122.3	119.9
CV-24192	9/2/2026 9:12:33 AM	54.5	41.4	0.0	4.1			1.3	0.0	119.7	119.8
CV-24192	9/4/2026 1:39:12 PM	52.3	41.0	0.0	6.7			1.3	0.0	121.5	121.4
CV-24192	9/22/2026 12:39:10 PM	54.4	44.1	1.5	0.0			1.2	0.0	118.9	119.7
CV-24193	9/1/2026 11:28:13 AM	44.2	42.8	0.0	13.0			1.0	0.0	117.6	117.7
CV-24193	9/21/2026 11:49:20 AM	50.8	42.7	0.0	6.5			1.2	0.0	119.3	119.3
CV-24194	9/1/2026 1:49:41 PM	53.0	38.0	0.3	8.7			1.4	29.0	106.3	106.3
CV-24194	9/3/2026 10:43:30 AM	49.6	47.6	0.0	2.9			1.0	0.0	107.5	107.6
CV-24194	9/21/2026 12:40:02 PM	50.4	44.9	0.0	4.7			1.1	0.0	106.0	106.1
CV-24194	9/21/2026 12:42:15 PM	51.6	44.6	0.0	3.8			1.2	0.0	106.6	106.5
CV-24195	9/1/2026 1:57:58 PM	51.7	44.9	0.0	3.4			1.2	0.0	118.6	118.7
CV-24195	9/3/2026 11:04:13 AM	41.2	42.6	0.1	16.1			1.0	179.3	118.1	118.1
CV-24195	9/21/2026 12:26:17 PM	49.5	46.2	0.0	4.3			1.1	0.0	119.7	119.8
CV-24195	9/22/2026 3:15:01 PM	51.2	44.8	0.0	4.0			1.1	0.0	117.6	118.1
CV-24196	9/1/2026 2:06:39 PM	46.4	48.4	0.2	5.0			1.0	25.0	123.6	123.6
CV-24196	9/22/2026 3:03:17 PM	46.2	52.6	0.0	1.2			0.9	0.0	123.9	123.7
CV-24197	9/1/2026 2:10:01 PM	44.9	42.7	0.0	12.4			1.1	0.0	124.4	124.4
CV-24197	9/22/2026 2:56:45 PM	47.1	45.3	0.0	7.6			1.0	0.0	128.4	126.6
CV-24198	9/15/2026 12:38:31 PM	35.4	36.4	0.0	28.2			1.0	0.0	128.2	128.0
CV-24198	9/15/2026 12:40:21 PM	34.8	36.6	0.0	28.6			1.0	0.0	127.9	127.7

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24198	9/30/2026 1:17:46 PM	47.5	41.0	0.0	11.5			1.2	0.0	125.8	126.1
CV-24199	9/15/2026 12:27:13 PM	46.5	39.6	0.0	13.9			1.2	0.0	128.5	128.4
CV-24199	9/15/2026 12:29:31 PM	46.4	40.6	0.0	13.0			1.1	0.0	128.4	128.4
CV-24199	9/30/2026 1:27:46 PM	51.6	44.8	0.0	3.6			1.2	0.0	127.9	128.8
CV-24200	9/15/2026 9:58:46 AM	45.0	39.2	0.0	15.8			1.1	0.0	120.9	120.9
CV-24200	9/15/2026 9:59:38 AM	45.1	38.6	0.0	16.3			1.2	0.0	120.9	120.9
CV-24200	9/30/2026 1:33:17 PM	51.3	40.6	0.0	8.1			1.3	0.0	121.7	121.8
CV-24201	9/15/2026 10:10:20 AM	48.3	46.4	0.1	5.2			1.0	52.0	109.5	124.0
CV-24201	9/15/2026 10:11:55 AM	49.0	46.3	0.0	4.7			1.1	0.0	125.4	125.4
CV-24201	9/15/2026 10:14:30 AM	48.6	46.7	0.0	4.7			1.0	0.0	126.6	125.0
CV-24201	9/24/2026 1:50:00 PM					24.3					
CV-24201	9/24/2026 1:50:00 PM						1000				
CV-24201	9/24/2026 1:50:04 PM						23000				
CV-24201	9/24/2026 1:50:55 PM	48.7	47.3	0.0	4.0			1.0	0.0	119.2	119.0
CV-24201	9/24/2026 2:48:38 PM					20					
CV-24201	9/28/2026 8:40:33 AM	47.4	47.2	0.0	5.5			1.0	0.0	93.1	124.2
CV-24201	9/28/2026 8:44:14 AM	47.9	47.5	0.0	4.6			1.0	0.0	127.9	128.6
CV-24202	9/15/2026 4:15:49 PM	26.8	32.7	0.0	40.5			0.8	0.0	125.4	121.0
CV-24202	9/15/2026 4:17:09 PM	26.1	32.5	0.0	41.4			0.8	0.0	119.7	119.9
CV-24202	9/23/2026 10:59:35 AM	35.4	39.2	0.0	25.4			0.9	0.0	127.1	127.2
CV-24202	9/24/2026 1:32:57 PM						16000				
CV-24202	9/24/2026 1:35:00 PM					11.8					
CV-24202	9/24/2026 1:35:00 PM						1000				
CV-24202	9/24/2026 1:35:03 PM	36.3	38.6	0.0	25.0			0.9	0.0	118.2	118.4
CV-24202	9/24/2026 3:14:01 PM					10					
CV-24203	9/15/2026 9:25:44 AM	53.3	42.4	0.0	4.3			1.3	0.0	122.8	123.0
CV-24203	9/15/2026 9:28:02 AM	53.1	42.4	0.0	4.5			1.3	0.0	123.3	123.8
CV-24203	9/24/2026 12:50:00 PM					11.9					
CV-24203	9/24/2026 12:50:00 PM						1400				

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24203	9/24/2026 12:53:25 PM						39000				
CV-24203	9/24/2026 12:54:25 PM	51.8	43.9	0.0	4.3			1.2	0.0	124.1	124.2
CV-24203	9/24/2026 2:54:50 PM					25					
CV-24204	9/15/2026 9:12:51 AM	51.7	44.0	0.0	4.3			1.2	0.0	126.9	126.9
CV-24204	9/15/2026 9:15:00 AM	50.7	44.6	0.0	4.7			1.1	0.0	127.0	127.2
CV-24204	9/15/2026 9:15:53 AM	50.2	45.7	0.0	4.1			1.1	0.0	127.2	127.2
CV-24204	9/25/2026 9:17:43 AM	49.5	45.4	0.0	5.1			1.1	0.0	127.3	127.3
CV-24205	9/15/2026 9:07:09 AM	54.0	41.1	0.0	4.9			1.3	0.0	124.0	124.1
CV-24205	9/15/2026 9:08:01 AM	52.9	41.7	0.0	5.4			1.3	0.0	124.2	124.1
CV-24205	9/30/2026 4:14:08 PM	50.3	44.5	0.0	5.2			1.1	0.0	125.0	125.0
CV-24206	9/15/2026 9:41:41 AM	36.4	41.1	3.9	18.6			0.9	4.8	82.1	81.9
CV-24206	9/15/2026 9:45:15 AM	44.2	48.1	0.2	7.5			0.9	37.5	82.3	82.3
CV-24206	9/23/2026 10:43:02 AM	46.1	46.6	0.9	6.4			1.0	7.1	106.7	107.9
CV-24206	9/23/2026 10:44:23 AM	49.0	50.1	0.0	0.9			1.0	0.0	108.9	109.1
CV-24206	9/24/2026 12:30:00 PM					11.1					
CV-24206	9/24/2026 12:30:00 PM						3700				
CV-24206	9/24/2026 12:33:26 PM						35000				
CV-24206	9/24/2026 12:37:06 PM	46.1	41.2	0.0	12.7			1.1	0.0	92.7	93.5
CV-24206	9/24/2026 12:39:33 PM	46.4	39.9	0.0	13.6			1.2	0.0	101.6	101.8
CV-24206	9/24/2026 3:07:10 PM					40					
CV-24207	9/3/2026 12:47:00 PM	40.1	56.1	0.0	3.8			0.7	0.0	127.3	136.1
CV-24207	9/3/2026 12:48:27 PM	39.0	57.9	0.0	3.1			0.7	0.0	136.4	136.5
CV-24207	9/13/2026 1:29:48 PM	47.7	47.2	0.0	5.0			1.0	0.0	135.8	135.7
CV-24207	9/13/2026 1:32:35 PM	48.0	47.2	0.0	4.8			1.0	0.0	135.5	135.3
CV-24207	9/13/2026 1:35:07 PM	48.1	46.8	0.0	5.1			1.0	0.0	135.2	134.6

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24207	9/13/2026 1:35:54 PM	47.9	47.2	0.0	4.9			1.0	0.0	133.9	133.8
CV-24207	9/21/2026 8:26:11 AM	46.1	53.5	0.0	0.4			0.9	0.0	126.8	130.2
CV-24208	9/24/2026 10:14:51 AM	41.7	57.4	0.0	0.9			0.7	0.0	131.8	131.8
CV-24208	9/24/2026 10:16:08 AM	41.4	57.6	0.0	1.0			0.7	0.0	128.4	128.6
CV-24209	9/30/2026 2:11:34 PM	10.0	73.8	0.0	16.2			0.1	0.0	131.6	131.9
CV-24210	9/9/2026 1:42:55 PM	29.9	35.8	0.0	34.3			0.8	0.0	123.7	124.2
CV-24211	9/28/2026 2:53:00 PM	15.8	76.6	0.3	7.3			0.2	24.3	114.4	99.5
CV-24212	9/28/2026 2:46:21 PM	9.3	70.2	0.8	19.7			0.1	24.6	118.1	110.9
CV-24213	9/4/2026 9:21:22 AM	43.1	47.2	0.0	9.8			0.9	0.0	111.4	112.8
CV-24214	9/30/2026 1:49:40 PM	13.7	58.1	0.0	28.2			0.2	0.0	115.4	115.6
CV-24215	9/30/2026 1:28:04 PM	44.4	50.1	0.0	5.5			0.9	0.0	119.7	119.7
CV-24216	9/16/2026 11:46:26 AM	39.1	40.2	0.0	20.7			1.0	0.0	124.0	121.6
CV-24217	9/3/2026 1:30:59 PM	41.0	58.2	0.0	0.8			0.7	0.0	109.0	109.0
CV-24218	9/14/2026 1:37:55 PM	44.4	50.1	0.0	5.5			0.9	0.0	124.9	124.7
CV-24219	9/1/2026 9:17:40 AM	13.9	82.1	0.0	4.0			0.2	0.0	183.9	183.8
CV-24219	9/1/2026 9:23:00 AM					3280					
CV-24219	9/1/2026 9:23:00 AM						110300				
CV-24219	9/9/2026 10:37:30 AM	17.7	74.4	0.0	7.9			0.2	0.0	185.1	185.2
CV-24219	9/9/2026 10:37:57 AM	24.9	75.1	0.0	0.0			0.3	0.0	185.3	185.2
CV-24219	9/9/2026 10:42:00 AM					2315					
CV-24219	9/15/2026 1:45:00 PM					3440					
CV-24219	9/15/2026 1:50:49 PM	12.3	76.9	0.0	10.8			0.2	0.0	189.6	189.5
CV-24219	9/15/2026 1:52:47 PM	15.5	80.2	0.0	4.3			0.2	0.0	189.5	189.5
CV-24219	9/22/2026 2:24:19 PM	16.2	83.1	0.0	0.7			0.2	0.0	187.8	187.7
CV-24219	9/22/2026 2:26:00 PM					1340					

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24219	9/29/2026 1:44:55 PM	22.6	77.1	0.2	0.1			0.3	0.5	185.6	186.1
CV-24219	9/29/2026 1:45:41 PM	22.4	76.6	0.0	1.0			0.3	0.0	187.0	187.5
CV-24219	9/29/2026 1:50:00 PM					2530					
CV-24220	9/1/2026 9:58:34 AM	21.7	50.7	1.2	26.4			0.4	22.0	147.3	147.7
CV-24220	9/8/2026 9:02:20 AM	18.5	43.8	2.2	35.5			0.4	16.1	140.2	130.5
CV-24220	9/8/2026 9:07:51 AM	13.9	58.9	0.8	26.4			0.2	33.0	129.9	129.5
CV-24221	9/28/2026 2:25:52 PM	30.3	35.9	0.1	33.7			0.8	337.0	129.3	125.8
CV-24222	9/30/2026 8:21:47 AM	50.0	40.5	0.0	9.5			1.2	0.0	121.8	121.8
CV-24223	9/28/2026 2:38:35 PM	35.3	54.7	0.2	9.8			0.6	49.0	125.0	125.0
CV-24224	9/30/2026 9:30:13 AM	47.9	47.9	0.0	4.2			1.0	0.0	80.5	81.0
CV-24224	9/30/2026 9:30:54 AM	48.8	47.6	0.0	3.6			1.0	0.0	81.5	81.5
CV-24224	9/30/2026 2:00:06 PM	52.2	42.9	0.0	4.9			1.2	0.0	111.3	111.4
CV-24225	9/1/2026 9:07:25 AM	48.4	49.1	0.5	2.0			1.0	4.0	120.5	120.6
CV-24226	9/28/2026 2:56:01 PM	50.5	48.6	0.2	0.7			1.0	3.5	111.7	111.6
CV-24227	9/2/2026 9:09:03 AM	55.9	42.0	0.0	2.1			1.3	0.0	117.4	117.6
CV-24227	9/4/2026 1:33:49 PM	52.9	40.8	0.0	6.3			1.3	0.0	118.8	118.7
CV-24227	9/22/2026 12:30:13 PM	51.2	48.8	0.0	0.0			1.0	0.0	118.0	118.0
CV-24231	9/30/2026 12:42:54 PM	44.0	44.0	0.0	12.0			1.0	0.0	127.6	127.5
CV-24236	9/2/2026 1:22:24 PM	54.2	37.6	0.0	8.2			1.4	0.0	107.3	107.3
CV-24237	9/2/2026 1:11:47 PM	59.2	35.9	1.4	3.5			1.6	2.5	112.1	112.3
CV-24237	9/4/2026 2:04:02 PM	39.0	40.2	1.3	19.5			1.0	14.8	112.8	112.9
CV-24243	9/17/2026 12:16:52 PM	48.3	37.6	1.6	12.5			1.3	7.8	117.9	120.9
CV-24243	9/17/2026 12:30:09 PM	27.2	23.9	8.6	40.4			1.1	4.7	121.2	120.8
CV-24243	9/17/2026 12:37:43 PM	28.8	25.7	8.5	37.1			1.1	4.4	120.5	120.6
CV-24243	9/22/2026 1:52:57 PM	43.0	34.7	3.6	18.7			1.2	5.2	115.7	115.8
CV-24244	9/16/2026 8:41:03 AM	49.0	38.8	0.3	11.8			1.3	35.8	112.8	112.7
CV-24244	9/16/2026 8:43:19 AM	48.5	39.0	0.5	12.0			1.2	23.9	112.7	112.6

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-24245	9/28/2026 10:15:21 AM	48.2	40.5	0.0	11.3			1.2	0.0	117.2	117.7
CV-24245	9/28/2026 10:17:16 AM	47.7	40.9	0.0	11.4			1.2	0.0	117.8	117.7
CV-24246	9/4/2026 9:59:35 AM	52.5	44.0	0.0	3.5			1.2	0.0	117.9	121.5
CV-24246	9/4/2026 10:00:29 AM	52.0	43.9	0.0	4.1			1.2	0.0	121.7	121.8
CV-24253	9/28/2026 9:37:51 AM	50.0	41.3	0.0	8.7			1.2	0.0	105.9	107.2
CV-24253	9/28/2026 9:39:46 AM	49.4	41.7	0.0	9.0			1.2	0.0	105.9	107.5
CV-25	9/21/2026 8:45:49 AM	54.9	42.2	0.0	2.9			1.3	0.0	89.9	90.2
CV-2501	9/4/2026 1:08:58 PM	51.7	43.0	0.0	5.3			1.2	131.5	128.7	128.6
CV-2502	9/11/2026 10:11:06 AM	56.8	35.9	0.0	7.3			1.6	0.0	114.6	120.3
CV-2502	9/11/2026 10:12:18 AM	56.5	39.0	0.0	4.5			1.4	0.0	122.0	122.0
CV-2503	9/11/2026 10:21:39 AM	45.5	32.1	0.0	22.4			1.4	0.0	130.3	130.4
CV-2503	9/23/2026 12:40:37 PM	43.5	37.7	0.0	18.8			1.2	0.0	130.2	130.2
CV-2504	9/23/2026 10:20:47 AM	48.4	40.8	0.0	10.9			1.2	0.0	129.9	130.1
CV-2504	9/23/2026 10:23:26 AM	47.3	41.2	0.0	11.5			1.1	0.0	130.2	130.1
CV-2505	9/23/2026 12:39:50 PM	50.7	42.5	0.0	6.9			1.2	0.0	127.2	127.3
CV-2506	9/23/2026 12:41:42 PM	49.9	42.3	0.0	7.8			1.2	0.0	127.2	127.2
CV-2506	9/23/2026 1:16:38 PM	46.3	41.5	0.0	12.2			1.1	0.0	123.2	123.2
CV-2507	9/23/2026 1:33:01 PM	52.1	42.8	0.0	5.1			1.2	0.0	126.7	126.6
CV-2507	9/23/2026 1:36:04 PM	52.4	42.6	0.0	5.1			1.2	0.0	126.6	126.6
CV-2508	9/23/2026 2:08:04 PM	49.7	41.7	0.0	8.6			1.2	0.0	121.7	121.7
CV-2509	9/4/2026 10:15:57 AM	49.3	42.7	0.0	8.0			1.2	0.0	117.0	117.0
CV-2510	9/4/2026 10:06:27 AM	52.7	43.2	0.0	4.1			1.2	0.0	116.1	116.1
CV-25100D	9/3/2026 10:05:34 AM	12.4	64.9	0.1	22.6			0.2	226.0	147.9	149.5
CV-25100D	9/3/2026 10:06:21 AM	12.4	64.9	0.3	22.4			0.2	74.7	148.9	151.1
CV-25100D	9/3/2026 10:34:00 AM					771					
CV-25100D	9/3/2026 10:34:00 AM						63000				
CV-25100D	9/8/2026 1:58:00 PM					798					
CV-25100D	9/8/2026 1:58:37 PM	13.7	62.5	0.5	23.3			0.2	46.6	159.4	157.5
CV-25100D	9/14/2026 1:43:20 PM	30.1	47.6	0.1	22.2			0.6	222.0	123.5	123.2
CV-25100D	9/25/2026 2:09:25 PM	11.9	42.0	0.2	45.9			0.3	229.5	120.2	120.4

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-25100S	9/8/2026 1:54:00 PM					2660					
CV-25100S	9/8/2026 1:54:17 PM	3.6	76.2	0.0	20.2			0.0	0.0	189.0	188.5
CV-25100S	9/14/2026 1:46:48 PM	19.1	63.9	0.0	17.0			0.3	0.0	176.4	176.4
CV-25100S	9/14/2026 1:47:00 PM					3330					
CV-25100S	9/21/2026 1:22:46 PM	11.6	72.0	0.0	16.4			0.2	0.0	178.4	178.6
CV-25100S	9/21/2026 1:24:00 PM					2790					
CV-25100S	9/28/2026 1:43:54 PM	8.7	79.9	0.0	11.4			0.1	0.0	164.0	164.2
CV-25100S	9/28/2026 1:55:00 PM					1910					
CV-25101D	9/3/2026 9:32:55 AM	23.2	46.3	0.0	30.5			0.5	0.0	128.9	128.8
CV-25101D	9/22/2026 10:51:18 AM	18.2	37.7	0.1	44.0			0.5	440.0	127.5	127.5
CV-25101S	9/3/2026 9:34:39 AM	5.9	27.5	0.1	66.5			0.2	665.0	108.8	109.1
CV-25101S	9/22/2026 10:53:04 AM	4.5	21.1	1.0	73.4			0.2	73.4	115.4	115.7
CV-25102	9/14/2026 9:45:37 AM	1.6	81.6	0.0	16.8			0.0	0.0	198.1	200.1
CV-25102	9/14/2026 9:46:33 AM	1.6	81.6	0.0	16.8			0.0	0.0	200.4	200.4
CV-25102	9/14/2026 1:20:00 PM					1660					
CV-25102	9/21/2026 9:40:00 AM					1260					
CV-25102	9/21/2026 9:46:14 AM	1.7	77.4	0.3	20.6			0.0	68.7	179.6	179.4
CV-25102	9/21/2026 9:48:39 AM	2.1	76.8	0.3	20.8			0.0	69.3	174.0	174.6
CV-25102	9/28/2026 10:49:11 AM	15.7	71.1	0.0	13.2			0.2	0.0	185.8	185.9
CV-25102	9/28/2026 1:05:00 PM					1810					
CV-25102	9/30/2026 8:30:50 AM	1.9	78.6	0.4	19.1			0.0	47.8	196.3	196.4
CV-25102	9/30/2026 8:32:19 AM	1.8	78.5	0.1	19.6			0.0	196.0	196.5	196.4
CV-25103	9/3/2026 9:09:00 AM	21.7	32.9	2.7	42.7			0.7	15.8	116.8	117.3
CV-25103	9/22/2026 10:46:56 AM	19.1	25.9	4.4	50.6			0.7	11.5	112.5	111.9
CV-25104D	9/15/2026 9:02:09 AM	3.7	79.7	0.0	16.6			0.0	0.0	135.0	129.5
CV-25104D	9/15/2026 9:02:43 AM	3.6	82.7	0.0	13.7			0.0	0.0	128.8	128.7
CV-25104D	9/23/2026 1:35:53 PM	3.6	80.1	0.2	16.1			0.0	80.5	152.5	155.2
CV-25104S	9/14/2026 9:28:09 AM	12.0	71.6	0.0	16.4			0.2	0.0	174.0	174.2
CV-25104S	9/14/2026 9:28:26 AM	11.9	72.7	0.0	15.4			0.2	0.0	174.0	174.2
CV-25104S	9/21/2026 10:03:05 AM	13.6	65.3	0.0	21.1			0.2	0.0	118.0	118.0
CV-25104S	9/30/2026 9:51:41 AM	9.5	71.3	0.0	19.2			0.1	0.0	118.4	118.0

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-25105D	9/3/2026 8:36:30 AM	0.4	2.0	20.3	77.3			0.2	3.8	70.0	70.0
CV-25105D	9/3/2026 8:39:20 AM	4.6	19.5	14.7	61.2			0.2	4.2	69.4	68.9
CV-25105D	9/25/2026 11:09:43 AM	12.0	78.2	0.1	9.7			0.2	97.0	134.0	134.0
CV-25105D	9/25/2026 11:12:40 AM	11.4	78.3	0.0	10.3			0.1	0.0	134.0	134.0
CV-25105S	9/3/2026 8:42:42 AM	0.0	2.5	20.3	77.2			0.0	3.8	83.1	83.1
CV-25105S	9/3/2026 8:43:52 AM	0.0	1.7	20.4	77.9			0.0	3.8	67.3	67.1
CV-25105S	9/25/2026 10:57:59 AM	2.1	2.9	16.9	78.1			0.7	4.6	98.5	98.3
CV-25105S	9/25/2026 10:59:33 AM	2.1	3.0	17.1	77.8			0.7	4.5	98.6	98.6
CV-25106D	9/14/2026 9:16:26 AM	40.0	58.6	0.3	1.1			0.7	3.7	81.3	81.3
CV-25106D	9/21/2026 2:39:29 PM	20.7	62.2	2.8	14.3			0.3	5.1	108.1	108.3
CV-25106S	9/15/2026 9:01:26 AM	19.4	34.1	5.8	40.7			0.6	7.0	77.3	77.3
CV-25106S	9/15/2026 9:02:41 AM	19.1	34.8	5.5	40.6			0.5	7.4	77.3	77.1
CV-25106S	9/21/2026 2:36:58 PM	7.5	14.0	15.8	62.7			0.5	4.0	96.1	96.1
CV-25107D	9/1/2026 9:37:00 AM					4190					
CV-25107D	9/1/2026 9:37:00 AM						110100				
CV-25107D	9/1/2026 9:41:08 AM	2.6	0.0	19.7	77.7				3.9	169.5	168.9
CV-25107D	9/1/2026 9:49:48 AM	10.8	53.7	7.0	28.5			0.2	4.1	168.5	167.7
CV-25107D	9/1/2026 9:52:33 AM	15.3	76.3	1.4	7.0			0.2	5.0	167.4	167.5
CV-25107D	9/1/2026 10:04:00 AM						110100				
CV-25107D	9/9/2026 10:27:10 AM	12.6	80.1	0.0	7.3			0.2	0.0	172.9	172.7
CV-25107D	9/9/2026 10:32:44 AM	12.1	59.9	4.2	23.8			0.2	5.7	173.4	173.3
CV-25107D	9/9/2026 10:33:42 AM	12.2	63.9	0.8	23.1			0.2	28.9	173.5	173.8
CV-25107D	9/9/2026 10:35:00 AM					3410					
CV-25107D	9/15/2026 1:35:00 PM					4090					

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-25107D	9/15/2026 1:35:50 PM	12.2	79.1	0.0	8.7			0.2	0.0	173.5	173.2
CV-25107D	9/15/2026 1:39:57 PM	10.4	76.2	0.0	13.4			0.1	0.0	175.4	175.9
CV-25107D	9/22/2026 2:13:00 PM					108					
CV-25107D	9/22/2026 2:20:08 PM	11.8	49.7	2.8	35.7			0.2	12.8	164.9	165.1
CV-25107D	9/29/2026 1:39:25 PM	11.1	38.8	7.9	42.2			0.3	5.3	163.8	167.1
CV-25107D	9/29/2026 1:40:00 PM					3530					
CV-25107S	9/3/2026 12:53:12 PM	2.4	87.1	0.0	10.5			0.0	0.0	103.2	103.2
CV-25107S	9/22/2026 10:17:17 AM	46.2	50.8	0.1	2.9			0.9	29.0	143.9	142.6
CV-25107S	9/22/2026 10:19:04 AM	49.2	47.0	0.1	3.7			1.0	37.0	144.0	143.0
CV-2511	9/30/2026 1:02:49 PM	51.1	43.8	0.0	5.1			1.2	0.0	127.4	127.3
CV-2512	9/4/2026 10:31:39 AM	44.0	42.6	0.0	13.4			1.0	0.0	125.3	125.4
CV-2513	9/17/2026 1:56:08 PM	53.7	42.1	0.0	4.2			1.3	0.0	121.8	121.7
CV-2513	9/17/2026 1:59:17 PM	52.8	42.0	0.0	5.2			1.3	0.0	121.7	121.7
CV-2514	9/21/2026 10:01:35 AM	53.7	42.0	0.0	4.3			1.3	0.0	127.4	127.5
CV-2514	9/21/2026 10:07:35 AM	53.4	41.8	0.0	4.8			1.3	0.0	127.8	127.8
CV-2515	9/29/2026 10:32:00 AM	43.7	37.5	0.0	18.9			1.2	0.0	115.7	115.1
CV-2515	9/29/2026 10:36:37 AM	43.4	38.0	0.0	18.6			1.1	0.0	114.8	115.2
CV-2515	9/29/2026 10:37:18 AM	43.5	38.2	0.0	18.4			1.1	0.0	115.2	115.2
CV-2515	9/29/2026 10:40:01 AM	43.5	38.2	0.0	18.4			1.1	0.0	115.2	115.3
CV-2516	9/16/2026 11:55:45 AM	50.1	42.2	0.0	7.7			1.2	0.0	128.0	127.9
CV-2517	9/21/2026 9:13:49 AM	40.0	35.3	0.0	24.7			1.1	0.0	115.5	116.0
CV-2518	9/21/2026 9:35:14 AM	52.5	38.3	0.0	9.2			1.4	0.0	109.8	110.3
CV-2519	9/22/2026 2:34:58 PM	46.4	41.4	0.1	12.1			1.1	121.0	122.8	122.7
CV-2520	9/22/2026 2:46:22 PM	34.1	50.4	0.0	15.5			0.7	0.0	135.9	134.9
CV-2520	9/22/2026 2:48:41 PM	34.2	51.3	0.0	14.5			0.7	0.0	134.0	134.0
CV-2521	9/30/2026 8:54:33 AM	45.7	43.6	0.0	10.7			1.0	0.0	105.5	105.4

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2521	9/30/2026 12:10:46 PM	44.0	46.6	0.0	9.4			0.9	0.0	138.9	138.1
CV-2521	9/30/2026 12:11:47 PM	45.0	44.6	0.0	10.4			1.0	0.0	137.8	138.0
CV-2522	9/22/2026 3:06:29 PM	41.8	45.5	0.0	12.7			0.9	0.0	132.8	131.3
CV-2522	9/22/2026 3:07:55 PM	43.6	44.3	0.0	12.1			1.0	0.0	129.3	129.4
CV-2523	9/25/2026 11:36:15 AM	47.8	41.7	0.0	10.5			1.1	0.0	126.8	126.8
CV-2524	9/22/2026 3:14:40 PM	32.2	40.5	1.0	26.3			0.8	26.3	138.1	126.7
CV-2524	9/22/2026 3:18:41 PM	33.0	37.6	0.9	28.5			0.9	31.7	122.1	121.8
CV-2525	9/25/2026 11:17:14 AM	32.3	32.4	0.1	35.2			1.0	352.0	119.3	119.2
CV-2526	9/29/2026 9:14:52 AM	47.4	39.0	0.0	13.5			1.2	0.0	122.5	122.7
CV-2527	9/14/2026 8:36:25 AM	46.4	43.6	0.1	9.9			1.1	99.0	132.5	132.5
CV-2527	9/14/2026 8:37:20 AM	45.8	44.0	0.0	10.2			1.0	0.0	132.6	132.2
CV-2527	9/30/2026 9:05:03 AM	5.7	50.4	0.0	44.0			0.1	0.0	86.7	86.4
CV-2527	9/30/2026 9:07:01 AM	5.4	52.2	0.0	42.4			0.1	0.0	86.1	86.1
CV-2527	9/30/2026 9:11:36 AM	5.0	52.6	0.0	42.4			0.1	0.0	86.4	84.6
CV-2527	9/30/2026 9:12:30 AM	5.1	52.9	0.0	42.1			0.1	0.0	84.6	84.5
CV-2527	9/30/2026 12:24:57 PM	10.0	54.3	0.0	35.7			0.2	0.0	110.5	113.7
CV-2527	9/30/2026 12:26:17 PM	12.2	54.5	0.0	33.3			0.2	0.0	114.6	114.6
CV-2528	9/21/2026 10:33:20 AM	43.4	35.8	0.0	20.8			1.2	0.0	110.6	110.5
CV-2529	9/4/2026 8:05:25 AM	55.1	39.4	0.7	4.7			1.4	6.3	77.4	80.4
CV-2529	9/4/2026 8:07:06 AM	51.6	39.1	1.3	8.0			1.3	6.1	80.6	80.6
CV-2530	9/28/2026 3:53:58 PM	45.3	47.4	0.2	7.1			1.0	35.5	107.9	109.9
CV-2531	9/28/2026 3:43:12 PM	35.2	53.1	0.2	11.5			0.7	57.5	113.6	113.3
CV-2532	9/30/2026 8:40:47 AM	51.5	42.4	0.2	5.9			1.2	34.8	97.1	97.6
CV-2533	9/28/2026 3:24:49 PM	43.0	36.2	3.6	17.2			1.2	4.8	128.2	127.4
CV-2534	9/1/2026 11:25:42 AM	33.8	46.3	0.0	19.9			0.7	0.0	110.6	110.6
CV-2534	9/28/2026 3:16:57 PM	51.6	48.3	0.0	0.1			1.1	0.0	100.4	100.7
CV-2535	9/23/2026 12:53:43 PM	45.5	39.3	0.0	15.3			1.2	0.0	115.5	115.2
CV-2536	9/25/2026 9:51:12 AM	48.1	43.1	1.3	7.5			1.1	5.6	98.2	98.2
CV-2537	9/25/2026 9:09:18 AM	47.0	39.2	0.0	13.8			1.2	0.0	118.6	118.7
CV-2538	9/25/2026 8:54:18 AM	50.2	40.9	0.0	9.0			1.2	0.0	114.5	114.4

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2539	9/15/2026 10:51:41 AM	44.0	42.3	0.0	13.7			1.0	0.0	120.5	120.3
CV-2539	9/21/2026 12:01:09 PM	41.3	43.2	0.0	15.5			1.0	0.0	122.6	122.3
CV-2540	9/2/2026 9:19:21 AM	15.9	80.1	0.0	4.0			0.2	0.0	138.4	138.6
CV-2540	9/17/2026 1:58:14 PM	7.6	81.6	0.0	10.8			0.1	0.0	138.7	138.9
CV-2541	9/1/2026 10:53:11 AM	21.9	63.8	0.0	14.3			0.3	0.0	108.4	108.9
CV-2541	9/17/2026 10:16:55 AM	22.7	63.9	0.1	13.3			0.4	133.0	127.5	128.6
CV-2542	9/2/2026 1:13:18 PM	44.3	54.0	0.6	1.1			0.8	1.8	130.1	130.1
CV-2542	9/17/2026 3:00:18 PM	39.4	56.6	0.4	3.6			0.7	9.0	130.0	130.4
CV-2543-PLR	9/2/2026 9:36:06 AM	6.2	55.2	7.1	31.5			0.1	4.4	95.9	97.9
CV-2543-PLR	9/17/2026 2:16:09 PM	13.5	60.1	4.1	22.3			0.2	5.4	99.7	101.0
CV-2544	9/15/2026 9:11:52 AM	6.9	84.9	0.0	8.2			0.1	0.0	89.8	89.8
CV-2544	9/15/2026 9:14:07 AM	7.0	84.7	0.0	8.3			0.1	0.0	145.2	145.3
CV-2544	9/15/2026 9:33:39 AM	6.8	82.3	0.0	10.9			0.1	0.0	145.4	145.4
CV-2544	9/21/2026 10:26:52 AM	10.7	82.2	0.0	7.1			0.1	0.0	150.1	150.0
CV-2544	9/21/2026 10:35:00 AM					2090					
CV-2545	9/2/2026 1:57:34 PM	27.2	71.1	0.0	1.7			0.4	0.0	126.5	129.4
CV-2545	9/2/2026 2:00:03 PM	29.1	70.9	0.0	0.0			0.4	0.0	129.3	129.7
CV-2545	9/21/2026 1:45:21 PM	33.1	61.0	0.1	5.8			0.5	58.0	127.9	127.5
CV-2546	9/2/2026 2:02:59 PM	22.8	73.0	0.0	4.2			0.3	0.0	129.8	129.6
CV-2546	9/2/2026 2:03:29 PM	22.6	75.0	0.1	2.3			0.3	23.0	129.1	130.6
CV-2546	9/21/2026 2:15:18 PM	18.6	73.6	3.5	4.3			0.3	1.2	124.4	124.5
CV-2547	9/24/2026 1:41:35 PM	51.7	46.6	0.0	1.7			1.1	0.0	99.9	99.7
CV-2548	9/1/2026 12:26:39 PM	6.6	80.2	0.0	13.2			0.1	0.0	139.7	139.7
CV-2548	9/1/2026 12:27:39 PM	6.3	81.7	0.0	12.0			0.1	0.0	139.6	139.6
CV-2548	9/3/2026 1:03:06 PM	7.0	75.8	0.0	17.2			0.1	0.0	86.3	85.5
CV-2548	9/18/2026 2:00:15 PM	7.0	85.6	0.0	7.4			0.1	0.0	137.8	137.9
CV-2548	9/18/2026 2:02:16 PM	6.9	85.9	0.0	7.2			0.1	0.0	137.9	137.8

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2548	9/22/2026 9:25:43 AM	6.0	82.2	0.0	11.8			0.1	0.0	139.0	139.0
CV-2549	9/1/2026 12:15:56 PM	40.7	52.3	0.0	7.0			0.8	0.0	117.2	116.7
CV-2549	9/1/2026 12:17:23 PM	40.1	53.0	0.0	6.9			0.8	0.0	116.9	117.1
CV-2549	9/3/2026 1:08:50 PM	40.9	53.8	0.0	5.3			0.8	0.0	117.0	116.8
CV-2549	9/18/2026 1:52:07 PM	14.7	82.2	0.0	3.1			0.2	0.0	135.7	135.7
CV-2549	9/18/2026 1:53:32 PM	14.7	77.3	0.0	8.0			0.2	0.0	135.9	135.7
CV-2550	9/1/2026 1:08:00 PM					2040					
CV-2550	9/1/2026 1:08:00 PM						113900				
CV-2550	9/1/2026 1:09:01 PM	8.9	78.5	0.0	12.6			0.1	0.0	184.3	184.4
CV-2550	9/9/2026 1:03:44 PM	23.2	76.8	0.0	0.0			0.3	0.0	181.1	180.6
CV-2550	9/9/2026 1:05:00 PM					3000					
CV-2550	9/16/2026 9:45:27 AM	5.5	76.9	0.0	17.6			0.1	0.0	186.2	187.0
CV-2550	9/16/2026 9:48:00 AM					3280					
CV-2550	9/23/2026 9:05:00 AM					347					
CV-2550	9/23/2026 9:06:42 AM	13.0	84.2	0.1	2.7			0.2	27.0	186.4	185.6
CV-2550	9/30/2026 8:10:00 AM					2460					
CV-2550	9/30/2026 8:13:11 AM	5.4	85.7	0.0	8.9			0.1	0.0	179.9	179.3
CV-2551	9/1/2026 9:06:00 AM					2970					
CV-2551	9/1/2026 9:06:00 AM						79300				
CV-2551	9/9/2026 10:15:15 AM	33.5	66.5	0.0	0.0			0.5	0.0	169.4	169.5
CV-2551	9/9/2026 10:25:00 AM					2910					
CV-2551	9/15/2026 1:29:53 PM	35.0	65.0	0.0	0.0			0.5	0.0	166.6	167.9
CV-2551	9/15/2026 1:30:00 PM					1540					
CV-2551	9/22/2026 2:05:45 PM	34.9	64.9	0.1	0.1			0.5	1.0	164.3	163.1
CV-2551	9/22/2026 2:07:00 PM					2190					
CV-2551	9/29/2026 1:30:00 PM					2660					

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2551	9/29/2026 1:30:09 PM	32.1	67.9	0.0	0.0			0.5	0.0	155.0	155.7
CV-2552	9/1/2026 1:12:06 PM	8.3	81.6	0.0	10.1			0.1	0.0	171.3	171.3
CV-2552	9/1/2026 1:16:00 PM					1800					
CV-2552	9/1/2026 1:16:00 PM						74500				
CV-2552	9/9/2026 1:16:00 PM					372					
CV-2552	9/9/2026 1:17:03 PM	40.3	59.4	0.3	0.0			0.7	0.0	165.1	165.1
CV-2552	9/16/2026 8:55:00 AM					1080					
CV-2552	9/16/2026 8:55:21 AM	24.8	75.2	0.0	0.0			0.3	0.0	168.3	168.5
CV-2552	9/23/2026 9:14:44 AM	32.3	67.2	0.5	0.0			0.5	0.0	167.1	167.1
CV-2552	9/23/2026 9:15:00 AM					1290					
CV-2552	9/30/2026 8:15:00 AM					1460					
CV-2552	9/30/2026 8:27:07 AM	23.4	76.2	0.3	0.1			0.3	0.3	167.7	167.7
CV-2553	9/2/2026 9:50:00 AM	34.8	60.4	0.0	4.8			0.6	0.0	110.0	110.0
CV-2553	9/17/2026 10:55:57 AM	36.0	57.8	0.1	6.1			0.6	61.0	89.8	76.5
CV-2554	9/1/2026 2:17:21 PM	35.4	64.6	0.0	0.0			0.5	0.0	160.4	160.5
CV-2554	9/1/2026 2:20:00 PM					779					
CV-2554	9/1/2026 2:20:00 PM						59700				
CV-2554	9/10/2026 8:49:04 AM	36.1	62.6	1.3	0.0			0.6	0.0	168.2	168.6
CV-2554	9/10/2026 8:51:00 AM					816					
CV-2554	9/16/2026 10:15:07 AM	32.3	65.8	0.0	1.9			0.5	0.0	164.5	165.1
CV-2554	9/16/2026 10:17:00 AM					669					
CV-2554	9/23/2026 10:20:05 AM	42.0	57.9	0.0	0.1			0.7	0.0	169.0	169.0
CV-2554	9/23/2026 10:25:00 AM					671					
CV-2554	9/30/2026 9:20:33 AM	33.5	66.5	0.0	0.0			0.5	0.0	164.0	164.4
CV-2554	9/30/2026 9:30:00 AM					582					
CV-2555	9/14/2026 10:19:23 AM	51.2	47.4	0.0	1.4			1.1	0.0	119.4	118.3
CV-2555	9/21/2026 2:31:09 PM	44.1	55.3	0.1	0.5			0.8	5.0	127.3	128.8
CV-2556-PLR	9/1/2026 1:23:16 PM	21.4	68.0	1.1	9.5			0.3	8.6	183.7	183.7
CV-2556-PLR	9/1/2026 1:29:00 PM					2270					

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2556-PLR	9/1/2026 1:29:00 PM						84900				
CV-2556-PLR	9/9/2026 1:31:40 PM	47.0	53.0	0.0	0.0			0.9	0.0	170.7	170.8
CV-2556-PLR	9/9/2026 1:37:00 PM					1980					
CV-2556-PLR	9/16/2026 9:12:40 AM	36.8	63.2	0.0	0.0			0.6	0.0	186.6	187.1
CV-2556-PLR	9/16/2026 9:18:00 AM					2940					
CV-2556-PLR	9/16/2026 9:20:48 AM	10.7	80.8	0.0	8.5			0.1	0.0	186.8	187.7
CV-2556-PLR	9/16/2026 9:21:53 AM	11.6	81.4	0.0	7.0			0.1	0.0	187.6	187.6
CV-2556-PLR	9/23/2026 9:27:28 AM	41.2	46.9	2.3	9.6			0.9	4.2	174.8	174.3
CV-2556-PLR	9/23/2026 9:30:00 AM					687					
CV-2556-PLR	9/30/2026 8:45:00 AM					927					
CV-2556-PLR	9/30/2026 8:45:01 AM	23.6	45.9	2.8	27.7			0.5	9.9	171.8	171.8
CV-2557	9/15/2026 8:51:14 AM	16.8	43.1	0.0	40.1			0.4	0.0	140.6	140.8
CV-2557	9/15/2026 8:52:00 AM	16.8	43.1	0.0	40.1			0.4	0.0	139.6	140.0
CV-2557	9/22/2026 10:25:41 AM	15.6	39.1	2.9	42.4			0.4	14.6	139.7	139.1
CV-2558-PLR	9/1/2026 10:13:00 AM					1150					
CV-2558-PLR	9/1/2026 10:13:00 AM						70000				
CV-2558-PLR	9/1/2026 10:28:32 AM	17.3	75.1	0.3	7.3			0.2	24.3	192.6	193.3
CV-2558-PLR	9/9/2026 1:00:56 PM	14.5	69.1	0.1	16.3			0.2	163.0	189.3	189.3
CV-2558-PLR	9/9/2026 1:10:00 PM					2150					
CV-2558-PLR	9/15/2026 2:10:00 PM					600					
CV-2558-PLR	9/15/2026 2:11:15 PM	15.3	79.8	0.0	4.9			0.2	0.0	191.8	191.4
CV-2558-PLR	9/23/2026 8:35:00 AM					452.5					
CV-2558-PLR	9/23/2026 8:42:47 AM	13.3	81.9	0.0	4.8			0.2	0.0	186.0	186.0
CV-2558-PLR	9/29/2026 2:05:00 PM					1700					

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2558-PLR	9/29/2026 2:07:13 PM	17.2	78.5	0.0	4.3			0.2	0.0	201.2	201.2
CV-2559	9/14/2026 1:31:45 PM	10.3	89.7	0.0	0.0			0.1	0.0	120.2	120.2
CV-2559	9/22/2026 9:49:02 AM	12.3	77.9	0.1	9.7			0.2	97.0	131.4	131.8
CV-2560	9/3/2026 9:21:28 AM	9.1	85.3	0.0	5.6			0.1	0.0	135.0	134.2
CV-2560	9/22/2026 10:49:07 AM	14.0	70.0	0.2	15.8			0.2	79.0	137.3	137.3
CV-2561	9/3/2026 9:41:08 AM	12.9	42.3	0.6	44.2			0.3	73.7	118.0	118.0
CV-2561	9/25/2026 2:14:35 PM	12.9	46.8	0.3	40.0			0.3	133.3	110.0	110.0
CV-2562	9/14/2026 1:42:18 PM	30.2	69.8	0.0	0.0			0.4	0.0	129.2	129.3
CV-2563	9/23/2026 8:42:14 AM	38.8	53.8	0.2	7.2			0.7	36.0	116.3	113.2
CV-2564	9/1/2026 10:33:16 AM	30.6	58.0	0.0	11.4			0.5	0.0	103.9	103.9
CV-2564	9/17/2026 10:06:15 AM	39.7	54.3	0.1	5.9			0.7	59.0	120.1	120.0
CV-2565	9/1/2026 11:35:08 AM	38.3	42.2	0.0	19.5			0.9	0.0	101.4	101.4
CV-2565	9/4/2026 1:22:35 PM	43.9	41.2	0.0	14.9			1.1	0.0	103.7	103.4
CV-2565	9/30/2026 11:33:22 AM	41.8	43.0	0.0	15.2			1.0	0.0	120.4	120.3
CV-2566	9/1/2026 11:33:06 AM	43.7	43.6	0.0	12.7			1.0	0.0	102.1	102.3
CV-2566	9/21/2026 11:57:56 AM	48.5	44.8	0.0	6.7			1.1	0.0	117.0	117.4
CV-2567	9/1/2026 1:52:22 PM	51.1	41.0	0.1	7.8			1.2	78.0	104.3	104.4
CV-2567	9/21/2026 12:33:36 PM	50.0	44.3	0.0	5.7			1.1	0.0	115.9	116.3
CV-2568	9/1/2026 2:47:30 PM	41.4	39.9	0.0	18.7			1.0	0.0	97.3	97.3
CV-2568	9/3/2026 11:10:53 AM	42.5	45.7	0.0	11.8			0.9	0.0	107.7	107.8
CV-2568	9/22/2026 3:09:14 PM	38.7	43.3	0.0	18.0			0.9	0.0	101.7	101.7
CV-2569	9/1/2026 2:37:13 PM	45.7	45.7	0.0	8.6			1.0	0.0	97.2	97.3
CV-2569	9/24/2026 12:16:37 PM	41.5	45.6	0.0	12.9			0.9	0.0	116.7	116.8
CV-2570	9/1/2026 2:13:36 PM	52.1	42.4	0.0	5.5			1.2	0.0	97.1	97.3
CV-2570	9/30/2026 1:55:05 PM	52.7	42.8	0.0	4.5			1.2	0.0	119.5	119.5
CV-2571	9/2/2026 10:53:10 AM	54.1	38.5	0.0	7.4			1.4	0.0	97.3	97.3
CV-2572	9/30/2026 10:38:28 AM	54.6	43.3	0.0	2.1			1.3	0.0	123.0	122.9
CV-2602	9/28/2026 9:13:58 AM	48.4	40.7	0.0	10.9			1.2	0.0	112.1	112.3
CV-2603	9/17/2026 1:31:00 PM	49.0	41.4	0.0	9.6			1.2	0.0	122.3	122.3
CV-2603	9/17/2026 1:35:30 PM	48.4	41.3	0.0	10.3			1.2	0.0	123.0	122.9
CV-2603	9/17/2026 1:37:32 PM	48.4	41.9	0.0	9.7			1.2	0.0	122.9	122.8
CV-2605	9/30/2026 9:04:23 AM	46.1	42.0	0.0	11.9			1.1	0.0	129.1	129.4

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2606	9/17/2026 1:17:22 PM	53.3	41.4	0.0	5.4			1.3	0.0	123.9	123.9
CV-2606	9/17/2026 1:22:30 PM	53.2	41.6	0.0	5.2			1.3	0.0	124.3	124.3
CV-2606	9/17/2026 1:24:50 PM	52.2	42.2	0.0	5.6			1.2	0.0	124.3	124.3
CV-2608	9/21/2026 9:33:42 AM	53.6	41.2	0.0	5.2			1.3	0.0	88.4	114.7
CV-2608	9/21/2026 9:44:28 AM	53.3	41.9	0.0	4.8			1.3	0.0	120.2	123.1
CV-2610	9/9/2026 10:26:51 AM	56.0	40.7	0.0	3.3			1.4	0.0	116.6	116.6
CV-2610	9/9/2026 10:27:56 AM	54.9	40.6	0.0	4.4			1.4	0.0	116.7	116.7
CV-2611	9/25/2026 8:33:59 AM	58.6	39.4	0.0	2.0			1.5	0.0	99.7	101.4
CV-2611	9/25/2026 8:35:07 AM	57.0	39.5	0.0	3.4			1.4	0.0	101.8	101.9
CV-2612	9/23/2026 10:24:54 AM	56.0	42.9	0.0	1.1			1.3	0.0	105.9	106.6
CV-2613	9/23/2026 9:13:04 AM	53.0	41.1	0.0	5.9			1.3	0.0	105.4	
CV-2613	9/23/2026 9:20:54 AM	52.9	41.1	0.0	6.1			1.3	0.0	106.4	108.7
CV-2613	9/23/2026 9:28:02 AM	55.1	40.4	0.0	4.5			1.4	0.0	109.1	109.2
CV-2613	9/23/2026 9:45:38 AM	54.6	40.3	0.0	5.1			1.4	0.0	108.6	109.3
CV-2614	9/21/2026 12:45:34 PM	53.2	42.1	0.0	4.7			1.3	0.0	124.7	124.6
CV-2614	9/21/2026 12:51:30 PM	54.1	41.1	0.0	4.8			1.3	0.0	125.0	125.7
CV-2614	9/21/2026 12:53:19 PM	52.8	42.4	0.0	4.8			1.2	0.0	125.8	125.9
CV-2615	9/21/2026 12:14:18 PM	46.8	44.2	0.0	9.0			1.1	0.0	108.6	108.6
CV-2615	9/21/2026 12:17:00 PM	45.8	45.7	0.0	8.5			1.0	0.0	109.1	108.5
CV-2615	9/21/2026 12:18:55 PM	45.4	45.9	0.0	8.7			1.0	0.0	108.1	108.0
CV-2627	9/11/2026 8:23:45 AM	58.8	38.6	0.0	2.6			1.5	0.0	113.0	113.2
CV-2634	9/4/2026 7:30:48 AM	1.0	2.3	20.8	76.0			0.5	3.7	68.2	68.3
CV-2634	9/11/2026 8:16:30 AM	1.1	5.1	20.5	73.3			0.2	3.6	88.8	89.5
CV-2634	9/23/2026 1:07:00 PM	2.1	7.1	20.4	70.4			0.3	3.5	106.1	107.1

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2634	9/24/2026 2:13:35 PM						1000				
CV-2634	9/24/2026 2:14:26 PM	1.1	2.7	20.1	76.1			0.4	3.8	102.0	102.1
CV-2634	9/24/2026 2:25:00 PM					15.8					
CV-2634	9/24/2026 2:25:00 PM						1000				
CV-2634	9/24/2026 2:58:48 PM					30					
CV-2634	9/24/2026 2:58:48 PM					30					
CV-2634	9/24/2026 2:58:48 PM					30					
CV-2638	9/27/2026 11:47:09 AM	18.0	52.3	0.0	29.7			0.3	0.0	104.4	104.5
CV-2663	9/28/2026 1:50:21 PM	25.6	55.1	0.1	19.2			0.5	192.0	143.1	143.2
CV-2676	9/1/2026 8:50:09 AM	15.0	74.6	0.0	10.4			0.2	0.0	128.4	130.6
CV-2680	9/16/2026 11:27:44 AM	41.8	40.6	0.1	17.5			1.0	175.0	132.4	122.6
CV-2680	9/16/2026 11:30:13 AM	38.5	40.6	0.5	20.4			0.9	40.8	125.8	125.9
CV-2680	9/22/2026 2:55:28 PM	39.9	44.0	0.0	16.1			0.9	0.0	129.1	128.7
CV-2681	9/22/2026 3:00:45 PM	14.0	42.9	0.0	43.1			0.3	0.0	94.2	94.5
CV-2681	9/22/2026 3:01:29 PM	13.0	44.8	0.0	42.2			0.3	0.0	94.6	94.6
CV-2683	9/22/2026 3:21:53 PM	24.6	44.1	0.0	31.3			0.6	0.0	96.9	96.9
CV-2684	9/28/2026 2:31:31 PM	28.8	36.1	0.1	35.0			0.8	350.0	125.7	116.6
CV-2687	9/9/2026 1:20:38 PM	49.4	40.2	0.0	10.4			1.2	0.0	124.6	124.6
CV-2688	9/4/2026 8:25:47 AM	55.7	41.3	0.0	3.0			1.3	0.0	121.1	122.8
CV-2688	9/18/2026 3:17:08 PM	55.3	44.7	0.0	0.0			1.2	0.0	124.3	123.3
CV-2689	9/28/2026 3:05:38 PM	0.9	60.7	1.4	37.0			0.0	26.4	104.8	104.9
CV-2689	9/30/2026 11:55:35 AM						282000				
CV-2689	9/30/2026 11:59:55 AM	0.8	61.1	0.0	38.1			0.0	0.0	121.3	122.7
CV-2689	9/30/2026 12:01:28 PM	0.9	60.8	0.0	38.4			0.0	0.0	122.2	122.2
CV-2690	9/4/2026 8:32:48 AM	54.4	41.4	0.0	4.2			1.3	0.0	120.8	121.0
CV-2691	9/28/2026 7:44:15 AM	55.8	40.2	0.0	4.0			1.4	0.0	125.7	125.8
CV-2692	9/4/2026 7:43:29 AM	55.9	41.0	0.0	3.2			1.4	315.0	127.0	127.0
CV-2692	9/18/2026 3:35:46 PM	54.9	42.2	0.0	2.9			1.3	0.0	127.2	127.3

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
CV-2695	9/16/2026 1:56:22 PM	54.5	41.8	0.0	3.7			1.3	0.0	114.4	114.5
CV-2695	9/16/2026 2:05:21 PM	53.9	42.1	0.0	4.0			1.3	0.0	114.4	114.9
CV-2695	9/16/2026 2:07:07 PM	53.3	42.9	0.0	3.8			1.2	0.0	114.9	114.9
CV-48R	9/23/2026 8:32:14 AM	52.1	43.7	0.0	4.2			1.2	0.0	120.9	121.4
CV-52D	9/22/2026 2:41:30 PM	31.1	51.8	0.0	17.1			0.6	0.0	102.6	99.2
CV-55R	9/2/2026 2:12:41 PM	29.9	55.0	0.0	15.1			0.5	0.0	151.6	151.4
CV-55R	9/2/2026 2:15:00 PM					425					
CV-55R	9/2/2026 2:15:00 PM						169000				
CV-55R	9/10/2026 9:19:10 AM	37.5	49.3	0.1	13.1			0.8	131.0	152.4	152.5
CV-55R	9/10/2026 9:21:00 AM					207					
CV-55R	9/11/2026 9:33:09 AM	30.2	46.9	0.0	22.9			0.6	0.0	152.9	152.8
CV-55R	9/17/2026 10:30:20 AM	35.1	43.8	0.0	21.1			0.8	0.0	150.8	151.0
CV-55R	9/17/2026 10:33:00 AM					440					
CV-55R	9/24/2026 2:26:06 PM	37.9	50.0	0.0	12.1			0.8	0.0	151.8	151.4
CV-55R	9/24/2026 2:30:00 PM					249					
CV-56D	9/1/2026 8:36:44 AM	36.7	36.0	0.9	26.4			1.0	29.3	117.8	117.7
CV-56S	9/1/2026 8:31:46 AM	26.4	17.3	4.5	51.8			1.5	11.5	110.9	110.8
CV-57R	9/1/2026 10:13:04 AM	47.3	38.5	0.0	14.2			1.2	0.0	105.2	105.4
CV-79R	9/1/2026 9:35:58 AM	51.3	45.7	0.0	3.0			1.1	0.0	136.8	136.5
CV-79R	9/1/2026 9:37:09 AM	51.0	45.5	0.0	3.5			1.1	0.0	135.8	135.9
CV-94	9/22/2026 10:04:47 AM	50.1	40.5	0.0	9.4			1.2	0.0	112.3	112.5
CV-95	9/1/2026 10:09:59 AM	35.7	29.3	2.0	33.0			1.2	16.5	91.6	91.7
CV-99	9/4/2026 7:05:00 AM					900					
CV-99	9/4/2026 7:05:00 AM						64000				
CV-99	9/14/2026 9:15:48 AM	3.0	6.5	17.8	72.7			0.5	4.1	85.9	86.7
CV-99	9/14/2026 9:19:46 AM	31.6	48.3	3.5	16.6			0.7	4.7	88.0	88.3
CV-99	9/25/2026 10:42:18 AM	40.9	54.1	0.3	4.7			0.8	15.7	105.0	98.8
D-02	9/25/2026 9:39:15 AM	60.3	38.0	0.0	1.7			1.6	0.0	88.8	89.1

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
D-02	9/28/2026 12:45:58 PM	58.7	38.4	0.0	2.9			1.5	0.0	92.8	92.6
D-02	9/28/2026 12:48:09 PM	56.6	40.4	0.0	3.1			1.4	0.0	92.3	92.3
D-03	9/2/2026 10:11:51 AM	51.6	36.6	1.7	10.1			1.4	5.8	99.5	99.6
D-04	9/25/2026 9:43:51 AM	50.4	38.0	0.7	10.8			1.3	14.6	89.4	89.5
D-09	9/25/2026 8:39:40 AM	55.8	40.0	0.0	4.2			1.4	0.0	115.5	115.6
D-10	9/2/2026 10:47:58 AM	54.5	40.0	0.3	5.2			1.4	17.3	102.9	103.0
FP-001	9/9/2026 11:56:26 AM	27.2	24.2	3.6	45.0			1.1	12.5	114.6	114.6
FP-002	9/9/2026 11:59:58 AM	26.5	24.5	4.4	44.6			1.1	10.1	114.6	114.6
FP-003	9/9/2026 12:04:20 PM	45.5	44.9	1.5	8.1			1.0	5.4	114.6	114.6
FP-005	9/25/2026 10:01:13 AM	0.1	2.7	18.5	78.7			0.0	4.3	89.1	89.2
FP-006	9/9/2026 10:42:38 AM	21.8	65.9	0.4	11.9			0.3	29.8	107.1	107.4
FP-008	9/9/2026 10:51:01 AM	4.6	33.3	9.9	52.2			0.1	5.3	108.4	108.3
FP-009	9/9/2026 10:56:29 AM	15.4	66.8	1.6	16.2			0.2	10.1	114.2	114.2
FP-010	9/9/2026 11:00:51 AM	19.9	76.3	0.6	3.2			0.3	5.3	120.9	120.9
FP-011	9/9/2026 11:03:30 AM	24.9	35.6	6.9	32.6			0.7	4.7	96.1	96.4
FP-012	9/1/2026 11:45:24 AM	0.7	4.7	19.0	75.6			0.1	4.0	95.6	95.8
FP-013	9/1/2026 11:33:24 AM	2.4	6.0	17.1	74.5			0.4	4.4	95.5	95.5
FP-014	9/25/2026 10:20:20 AM	4.5	35.5	10.1	49.9			0.1	4.9	112.4	112.5
FP-015	9/9/2026 10:36:14 AM	0.3	0.7	19.3	79.7			0.4	4.1	114.6	114.7
FP-016	9/9/2026 10:39:37 AM	0.3	0.4	19.3	80.0			0.8	4.1	108.9	109.5
FP-017	9/14/2026 11:00:20 AM	54.4	35.0	2.4	8.2			1.6	3.4	98.8	98.6
FP-018	9/1/2026 2:40:24 PM	50.4	38.9	0.6	10.1			1.3	16.8	96.1	96.1
FP-019	9/1/2026 2:44:17 PM	54.4	43.5	0.1	2.0			1.3	20.0	95.1	95.2
FP-020	9/14/2026 11:24:45 AM	5.1	10.6	13.8	70.5			0.5	5.1	96.0	96.0
FP-021	9/14/2026 11:16:23 AM	14.0	28.1	8.7	49.2			0.5	5.7	106.1	106.1
FP-022	9/14/2026 11:21:00 AM	6.1	26.8	1.1	66.0			0.2	60.0	104.5	104.5
FP-023	9/3/2026 8:54:48 AM	18.4	45.5	5.2	30.9			0.4	5.9	82.0	82.1
FP-024	9/9/2026 11:18:04 AM	18.9	40.3	6.1	34.7			0.5	5.7	103.4	103.7
FP-025	9/14/2026 10:07:38 AM	6.9	14.1	14.5	64.5			0.5	4.4	95.2	95.3
FP-026	9/14/2026 10:10:15 AM	11.5	23.0	10.7	54.8			0.5	5.1	92.6	92.6
FP-027	9/14/2026 10:53:07 AM	11.9	26.7	8.6	52.8			0.4	6.1	98.7	98.8
FP-027	9/14/2026 2:20:08 PM	13.0	24.9	9.5	52.6			0.5	5.5	97.0	96.9
FP-027	9/15/2026 10:17:45 AM	1.0	18.6	15.1	65.3			0.1	4.3	93.6	93.7
FP-028	9/14/2026 10:55:24 AM	9.2	10.1	15.7	65.0			0.9	4.1	101.0	101.1
FP-028	9/15/2026 10:30:36 AM	0.1	2.1	19.7	78.1			0.0	4.0	89.1	89.1
FP-028	9/15/2026 10:31:51 AM	0.0	0.9	20.6	78.5			0.0	3.8	89.5	89.5
FP-029	9/14/2026 11:04:54 AM	52.2	41.3	0.0	6.5			1.3	0.0	110.3	110.9

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
FP-029	9/15/2026 10:38:34 AM	13.5	15.2	11.3	60.0			0.9	5.3	91.1	90.9
FP-030	9/1/2026 2:31:04 PM	50.4	40.1	1.2	8.3			1.3	6.9	94.3	94.3
FP-031	9/1/2026 2:28:03 PM	3.9	18.3	17.7	60.1			0.2	3.4	91.9	92.4
FP-031	9/15/2026 10:39:37 AM	13.0	14.3	11.6	61.1			0.9	5.3	90.6	90.6
FP-032	9/1/2026 2:20:55 PM	6.5	13.6	11.2	68.7			0.5	6.1	94.6	94.9
FP-033	9/1/2026 2:17:52 PM	0.0	1.5	19.5	79.0			0.0	4.1	95.1	95.1
FP-034	9/1/2026 2:13:58 PM	0.4	7.7	11.7	80.2			0.1	6.9	99.7	99.7
FP-035	9/1/2026 1:47:39 PM	19.4	39.8	4.9	35.9			0.5	7.3	91.8	91.8
FP-036	9/14/2026 9:56:48 AM	9.7	15.8	12.5	62.0			0.6	5.0	93.2	93.3
FP-037	9/1/2026 1:35:51 PM	1.1	1.1	19.3	78.5			1.0	4.1	92.9	93.6
FP-038	9/14/2026 1:57:24 PM	25.4	17.9	6.6	50.1			1.4	7.6	98.2	98.7
FP-038	9/23/2026 10:03:41 AM	3.4	20.9	16.4	59.3			0.2	3.6	87.4	87.4
FP-039	9/14/2026 1:59:50 PM	51.1	32.9	2.0	14.0			1.6	7.0	101.6	101.7
FP-040	9/23/2026 10:00:51 AM	12.0	43.2	6.4	38.4			0.3	6.0	103.2	103.2
FP-041	9/2/2026 7:45:38 AM	13.4	33.2	4.3	49.1			0.4	11.4	64.9	65.0
FP-042	9/2/2026 8:11:34 AM	6.2	28.7	12.1	53.0			0.2	4.4	70.4	70.5
FP-043	9/2/2026 7:48:43 AM	8.0	26.0	7.6	58.4			0.3	7.7	82.4	82.5
FP-044	9/2/2026 7:51:27 AM	0.5	6.7	19.2	73.6			0.1	3.8	67.4	67.5
FP-045	9/2/2026 1:12:15 PM	0.0	0.1	21.0	78.9			0.2	3.8	94.1	105.4
FP-046	9/25/2026 10:05:05 AM	9.3	36.2	9.1	45.4			0.3	5.0	93.5	93.4
FP-047	9/29/2026 8:20:44 AM	3.3	6.5	15.4	74.8			0.5	4.9	73.0	73.0
FP-050	9/2/2026 2:22:59 PM	25.8	60.0	0.1	14.1			0.4	141.0	99.9	99.9
FP-051	9/2/2026 2:17:15 PM	35.9	63.4	0.2	0.5			0.6	2.5	98.4	98.4
FP-052	9/2/2026 1:33:27 PM	9.3	14.1	10.5	66.1			0.7	6.3	94.0	94.0
FP-053	9/2/2026 1:27:21 PM	17.1	19.4	8.6	54.9			0.9	6.4	100.3	100.6
FP-054	9/1/2026 9:06:16 AM	27.3	72.6	0.1	0.0			0.4	0.0	164.9	165.1
FP-054	9/2/2026 2:06:03 PM	37.3	55.0	0.0	7.7			0.7	0.0	98.1	98.1
FP-055	9/28/2026 10:39:01 AM	1.3	14.8	13.4	70.5			0.1	5.3	94.1	94.2
FP-056	9/2/2026 9:03:40 AM	13.5	17.2	10.9	58.4			0.8	5.4	82.2	82.2
FP-057	9/3/2026 12:59:26 PM	40.1	35.9	0.8	23.2			1.1	29.0	100.0	100.1
FP-058	9/3/2026 12:56:21 PM	24.4	35.3	3.1	37.2			0.7	12.0	97.5	97.6
FP-059	9/14/2026 1:04:23 PM	35.5	24.2	8.7	31.6			1.5	3.6	108.2	108.2
FP-060	9/28/2026 10:03:13 AM	0.0	0.0	20.8	79.2				3.8	86.5	86.4
FP-061	9/9/2026 10:33:21 AM	1.0	14.4	16.0	68.6			0.1	4.3	112.1	
FP-062	9/10/2026 12:04:52 PM	9.7	74.4	0.0	15.9			0.1	0.0	151.0	151.1
FP-063	9/10/2026 12:09:15 PM	0.5	3.2	19.4	76.9			0.2	4.0	112.6	112.8
FP-064	9/14/2026 12:54:05 PM	52.9	40.5	0.0	6.6			1.3	0.0	100.8	101.7
FP-064	9/14/2026 12:58:32 PM	51.3	39.0	0.0	9.7			1.3	0.0	101.6	101.4

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
FP-064	9/15/2026 9:47:50 AM	28.4	27.1	2.3	42.2			1.0	18.3	92.0	91.9
FP-065	9/14/2026 1:10:28 PM	54.6	40.6	0.1	4.7			1.3	47.0	101.8	103.6
FP-065	9/15/2026 9:51:40 AM	32.6	29.9	2.2	35.3			1.1	16.0	93.0	92.8
FP-066	9/14/2026 1:20:35 PM	39.5	30.5	2.2	27.8			1.3	12.6	103.8	103.8
FP-066	9/15/2026 9:55:34 AM	8.1	15.9	9.9	66.1			0.5	6.7	92.9	92.8
H-01 (EXP-01	9/3/2026 12:08:43 PM	11.3	48.4	0.0	40.3			0.2	0.0	103.7	104.8
H-01 (EXP-01	9/30/2026 2:26:54 PM	10.2	47.0	0.0	42.9			0.2	0.0	110.0	110.3
H-02 (EXP-02	9/3/2026 12:33:02 PM	18.1	49.0	0.0	32.9			0.4	0.0	117.2	117.0
H-02 (EXP-02	9/30/2026 2:29:31 PM	20.5	46.6	0.0	33.0			0.4	0.0	115.0	115.2
H-03 (EXP-03	9/3/2026 12:29:22 PM	47.9	49.6	0.0	2.5			1.0	0.0	119.2	117.0
H-03 (EXP-03	9/30/2026 2:35:08 PM	53.2	42.3	0.0	4.6			1.3	0.0	115.2	115.2
H-04 (EXP-04	9/3/2026 12:23:09 PM	3.4	56.9	0.0	39.7			0.1	0.0	135.4	131.8
H-04 (EXP-04	9/3/2026 12:24:20 PM	2.5	57.9	0.0	39.6			0.0	0.0	131.5	131.5
H-04 (EXP-04	9/30/2026 2:38:36 PM	1.6	52.7	0.0	45.7			0.0	0.0	130.6	132.1
H-04 (EXP-04	9/30/2026 2:40:29 PM	1.5	55.3	0.0	43.2			0.0	0.0	136.6	136.8
H-08 (EXP-08	9/14/2026 8:50:48 AM	50.4	45.3	0.0	4.3			1.1	0.0	123.3	123.3
H-08 (EXP-08	9/29/2026 8:40:38 AM	51.1	45.8	0.0	3.1			1.1	0.0	123.3	123.5
H-08 (EXP-08	9/29/2026 8:42:05 AM	50.0	46.8	0.0	3.2			1.1	0.0	123.5	123.5
H-10 (EXP-10	9/15/2026 8:07:00 AM	11.5	70.4	0.0	18.1			0.2	0.0	131.2	131.2
H-10 (EXP-10	9/15/2026 8:11:28 AM	10.9	69.6	0.0	19.5			0.2	0.0	131.3	131.3
H-10 (EXP-10	9/29/2026 8:30:20 AM	11.1	65.7	0.2	23.0			0.2	95.6	131.0	130.9
H-10 (EXP-10	9/29/2026 8:32:34 AM	11.0	66.3	0.2	22.6			0.2	141.5	130.8	130.8
H-1404C	9/15/2026 9:34:05 AM	12.8	30.3	0.6	56.3			0.4	93.8	153.8	153.6
H-1404C	9/15/2026 9:38:51 AM	12.7	29.9	0.6	56.8			0.4	94.7	153.4	153.9
H-1404C	9/16/2026 10:35:00 AM					201					
H-1404C	9/16/2026 12:54:05 PM	13.9	31.9	0.5	53.7			0.4	116.7	151.7	150.8
H-1404C	9/16/2026 1:34:20 PM	10.5	26.3	0.5	62.7			0.4	118.4	151.1	122.2
H-1404C	9/16/2026 1:40:19 PM	10.5	26.9	0.5	62.1			0.4	124.3	106.2	104.6
H-1405C	9/1/2026 9:32:25 AM	16.0	49.7	2.9	31.4			0.3	10.8	90.9	91.2
H-1405C	9/22/2026 11:58:24 AM	0.0	0.2	22.8	77.0			0.0	3.4	101.0	101.0

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
H-1405C	9/22/2026 11:59:05 AM	0.0	0.2	22.8	77.0			0.0	3.4	100.9	100.8
H-1406W	9/2/2026 8:36:20 AM	28.4	59.3	1.9	10.4			0.5	5.5	71.9	70.8
H-1406W	9/4/2026 1:49:40 PM	31.7	55.6	0.6	12.0			0.6	19.4	93.1	93.5
H-1406W	9/10/2026 10:32:49 AM	29.3	63.1	0.3	7.3			0.5	24.3	93.1	93.2
H-1406W	9/23/2026 8:53:49 AM	0.2	7.4	19.4	73.0			0.0	3.8	83.1	83.1
H-1408CR	9/23/2026 12:53:30 PM	42.7	43.2	0.0	14.1			1.0	0.0	126.1	126.1
H-1408E	9/14/2026 2:12:45 PM	54.4	42.0	0.0	3.6			1.3	0.0	98.1	103.0
H-1408E	9/21/2026 10:04:50 AM	55.3	43.0	0.0	1.7			1.3	0.0	117.6	118.5
H-1408W	9/2/2026 9:01:18 AM	36.9	30.5	4.8	27.8			1.2	5.8	81.6	81.6
H-1409N	9/1/2026 2:27:54 PM	42.2	34.8	0.0	23.0			1.2	0.0	116.8	116.9
H-1409N	9/21/2026 9:11:22 AM	57.1	41.2	0.0	1.7			1.4	0.0	103.6	106.0
H-1410S	9/25/2026 9:05:52 AM	50.4	40.9	0.6	8.1			1.2	14.5	93.3	94.0
H-1563N	9/14/2026 2:12:22 PM	48.5	36.8	0.3	14.4			1.3	48.0	126.0	126.0
H-1563N	9/17/2026 10:33:10 AM	32.6	37.8	0.5	29.1			0.9	58.2	126.1	124.6
H-1563S	9/1/2026 9:35:22 AM	13.8	27.5	0.4	58.3			0.5	145.8	90.1	90.1
H-1563S	9/22/2026 12:03:36 PM	10.9	23.5	0.3	65.3			0.5	217.7	94.4	94.4
H-1565E	9/14/2026 2:16:08 PM	51.5	39.6	0.0	8.9			1.3	0.0	104.6	104.6
H-1565E	9/21/2026 10:11:59 AM	38.7	36.0	0.0	25.3			1.1	0.0	91.1	91.2
H-1568N	9/14/2026 2:10:12 PM	41.7	38.9	1.2	18.2			1.1	15.2	116.5	116.4
H-1568N	9/21/2026 9:57:33 AM	34.2	38.7	1.5	25.6			0.9	17.1	116.0	116.0
H-1571S	9/24/2026 10:55:12 AM	52.9	42.0	0.0	5.1			1.3	0.0	94.1	100.2
H-1572N	9/22/2026 10:24:00 AM	50.5	42.9	0.0	6.6			1.2	0.0	108.1	107.3
H-1572S	9/24/2026 10:40:13 AM	39.8	35.3	4.2	20.7			1.1	4.9	94.1	97.2
H-1753N	9/1/2026 2:48:08 PM	38.5	30.1	4.8	26.6			1.3	5.5	96.3	96.3
H-1753N	9/24/2026 11:34:35 AM	41.2	33.6	5.3	19.9			1.2	3.8	94.9	94.7
H-1753N	9/24/2026 11:36:18 AM	41.7	33.2	4.9	20.2			1.3	4.1	94.8	94.7
H-1753S	9/14/2026 1:54:43 PM	54.6	41.4	0.0	4.0			1.3	0.0	108.8	108.9
H-1753S	9/17/2026 10:36:17 AM	43.6	39.2	0.0	17.2			1.1	0.0	106.9	105.5
H-1756S	9/2/2026 7:25:00 AM	10.8	25.7	3.5	60.0			0.4	17.1	68.9	71.3

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
H-1756S	9/22/2026 11:27:30 AM	30.9	41.6	1.9	25.6			0.7	13.5	111.0	109.4
H-1757S	9/1/2026 9:27:22 AM	38.4	46.9	0.0	14.7			0.8	0.0	93.9	94.1
H-1757S	9/22/2026 11:41:50 AM	31.4	42.3	0.0	26.3			0.7	0.0	109.8	110.1
H-1760S	9/14/2026 1:52:17 PM	40.2	58.6	0.0	1.2			0.7	0.0	122.1	122.1
H-1760S	9/21/2026 9:25:24 AM	39.0	55.9	0.0	5.1			0.7	0.0	117.9	117.9
H-1762N	9/13/2026 1:22:53 PM	51.5	39.8	0.0	8.6			1.3	0.0	115.5	116.1
H-1762N	9/13/2026 1:24:07 PM	50.4	39.8	0.0	9.8			1.3	0.0	116.4	116.5
H-1762N	9/21/2026 8:20:33 AM	49.3	38.1	0.0	12.6			1.3	0.0	113.2	113.4
H-1763N	9/14/2026 1:09:46 PM	29.5	29.6	3.1	37.8			1.0	12.2	121.7	121.5
H-1763N	9/24/2026 2:03:05 PM	29.7	41.8	2.3	26.2			0.7	11.4	124.3	124.3
H-1763S	9/9/2026 1:49:39 PM	18.7	27.9	0.0	53.4			0.7	0.0	127.1	127.1
H-1764N	9/9/2026 1:21:26 PM	44.1	39.6	0.0	16.3			1.1	0.0	122.3	122.1
H-1764S	9/24/2026 11:03:44 AM	40.8	47.1	0.0	12.1			0.9	0.0	124.3	123.7
H-1767N	9/28/2026 3:02:56 PM	39.6	57.4	0.1	2.9			0.7	29.0	106.3	106.3
H-1769N	9/1/2026 11:12:33 AM	9.7	28.4	3.8	58.1			0.3	15.3	124.7	123.6
H-1769N	9/16/2026 12:33:55 PM	4.7	17.8	7.6	69.9			0.3	9.2	118.5	117.7
H-1769N	9/16/2026 12:34:48 PM	4.6	17.1	7.7	70.6			0.3	9.2	117.1	117.0
H-1770N	9/1/2026 11:22:05 AM	29.2	63.7	0.0	7.1			0.5	0.0	105.0	105.2
H-1770N	9/10/2026 9:10:00 AM					320					
H-1770N	9/10/2026 9:10:00 AM						23000				
H-1770N	9/16/2026 2:50:15 PM	27.2	65.6	0.2	7.0			0.4	35.0	97.3	97.4
H-1770S	9/1/2026 9:20:12 AM	40.1	52.8	0.0	7.1			0.8	0.0	103.4	103.6
H-1770S	9/24/2026 2:40:13 PM	27.1	48.3	1.7	22.9			0.6	13.5	105.7	106.3
H-1771A	9/10/2026 1:09:59 PM	33.0	67.0	0.0	0.0			0.5	0.0	106.7	106.7
H-1771B	9/3/2026 8:52:45 AM	13.6	70.2	0.0	16.2			0.2	0.0	98.8	98.6
H-1771B	9/22/2026 10:31:17 AM	25.0	33.2	1.3	40.5			0.8	31.2	104.0	104.0
H-1774N	9/10/2026 8:58:19 AM	38.4	58.6	0.0	3.0			0.7	0.0	118.9	118.5
H-1774N	9/16/2026 2:40:28 PM	37.4	62.4	0.2	0.0			0.6	0.0	118.5	118.4
H-1801S	9/1/2026 9:53:29 AM	0.1	2.6	19.6	77.7			0.0	4.0	90.5	90.7
H-1801S	9/1/2026 9:53:57 AM	0.1	2.3	19.6	78.0			0.0	4.0	91.6	91.8
H-1802S	9/22/2026 10:27:44 AM	53.6	43.7	0.0	2.7			1.2	0.0	108.4	112.1
H-1803N-PLF	9/8/2026 10:07:00 AM					1740					
H-1803N-PLF	9/8/2026 10:10:29 AM	1.7	77.3	0.0	21.0			0.0	0.0	198.6	198.5
H-1803N-PLF	9/14/2026 9:29:28 AM	11.9	72.8	0.0	15.3			0.2	0.0	198.3	198.2
H-1803N-PLF	9/14/2026 9:32:00 AM					1700					

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
H-1803N-PLF	9/21/2026 9:40:35 AM	10.6	74.6	0.0	14.8			0.1	0.0	198.4	198.4
H-1803N-PLF	9/21/2026 9:41:00 AM					1490					
H-1803N-PLF	9/28/2026 9:10:00 AM					1290					
H-1803N-PLF	9/28/2026 9:16:43 AM	10.7	74.1	0.0	15.2			0.1	0.0	198.5	198.7
H-1804B	9/14/2026 1:13:24 PM	45.5	54.5	0.0	0.0			0.8	0.0	112.3	112.3
H-1804N	9/25/2026 2:27:02 PM	26.4	70.1	0.1	3.4			0.4	34.0	130.4	130.4
H-1804S	9/9/2026 1:23:01 PM	44.0	39.2	0.0	16.8			1.1	0.0	120.5	120.5
H-1805A	9/3/2026 1:50:46 PM	45.9	42.9	0.2	11.0			1.1	55.0	90.6	
H-1805B	9/9/2026 1:05:06 PM	24.0	29.0	0.7	46.3			0.8	66.1	111.1	111.5
H-1805S	9/9/2026 1:38:46 PM	44.9	40.8	0.0	14.3			1.1	0.0	130.6	128.9
H-1805S	9/9/2026 1:39:27 PM	45.7	42.3	0.0	12.0			1.1	0.0	127.9	128.0
H-1806A	9/3/2026 1:23:27 PM	49.3	39.0	0.0	11.7			1.3	0.0	118.2	118.3
H-1806B	9/22/2026 10:17:41 AM	41.9	37.6	2.2	18.3			1.1	8.3	89.6	89.6
H-1806B	9/22/2026 10:19:58 AM	46.2	38.6	0.7	14.5			1.2	20.7	90.6	90.4
H-1806N	9/10/2026 1:30:41 PM	42.2	57.7	0.1	0.0			0.7	0.0	126.2	125.9
H-1806S	9/1/2026 9:12:20 AM	17.6	77.3	0.0	5.1			0.2	0.0	123.3	127.4
H-1807A	9/22/2026 10:02:24 AM	52.7	41.7	0.0	5.6			1.3	0.0	113.7	114.1
H-1807N	9/4/2026 9:28:29 AM	29.2	34.3	0.6	35.9			0.9	56.1	93.9	94.4
H-1807N	9/10/2026 1:36:04 PM	47.8	37.2	0.1	14.9			1.3	149.0	113.3	113.9
H-1807S	9/1/2026 10:29:44 AM	45.4	32.9	0.2	21.5			1.4	107.5	98.0	98.5
H-1952S	9/2/2026 1:24:38 PM	52.7	46.5	0.0	0.8			1.1	0.0	119.2	119.2
H-1952S	9/17/2026 2:50:32 PM	53.4	45.1	0.0	1.5			1.2	0.0	118.3	118.3
H-1955C	9/3/2026 1:54:00 PM	24.6	27.2	2.5	45.7			0.9	18.3	91.7	91.7
H-1955N	9/10/2026 1:18:23 PM	40.3	48.4	0.5	10.8			0.8	21.6	103.1	103.4
H-1956B	9/9/2026 12:56:13 PM	14.6	68.6	0.0	16.8			0.2	0.0	126.4	125.1
H-1956B	9/9/2026 12:57:13 PM	17.1	68.7	0.0	14.2			0.2	0.0	128.5	128.6
H-1956N	9/10/2026 1:26:20 PM	54.5	45.4	0.1	0.0			1.2	0.0	115.3	115.3
H-1956S	9/1/2026 9:27:26 AM	44.7	41.2	0.0	14.1			1.1	0.0	104.1	103.9
H-1957B	9/3/2026 1:15:00 PM	57.6	40.4	0.0	2.0			1.4	0.0	97.3	97.4
H-1957N	9/10/2026 1:33:26 PM	52.5	47.4	0.1	0.0			1.1	0.0	121.9	122.0
H-1957S	9/30/2026 9:45:11 AM	45.0	45.2	0.6	9.2			1.0	16.7	142.6	127.3
H-1957S	9/30/2026 9:54:00 AM	44.0	46.0	0.5	9.5			1.0	18.3	130.5	129.5

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
H-1957S	9/30/2026 2:08:10 PM	41.1	48.6	0.6	9.7			0.8	16.2	107.8	107.6
H-1958C	9/22/2026 9:58:48 AM	41.5	37.7	0.0	20.8			1.1	0.0	116.2	116.2
H-1958N	9/10/2026 1:37:51 PM	48.1	38.1	0.4	13.4			1.3	33.5	114.2	114.6
H-1958S	9/1/2026 10:27:20 AM	11.9	16.6	12.1	59.4			0.7	4.9	96.7	97.5
H-1962N	9/1/2026 11:28:27 AM	18.4	33.4	0.9	47.3			0.6	52.6	134.7	134.7
H-1962N	9/1/2026 11:29:39 AM	14.6	27.4	1.7	56.3			0.5	33.1	134.8	134.8
H-1962N	9/16/2026 2:56:18 PM	17.2	36.2	0.9	45.7			0.5	50.8	136.1	136.9
H-1962N	9/16/2026 2:56:46 PM	17.6	33.8	1.5	47.1			0.5	31.4	136.9	136.7
H-1963N	9/1/2026 10:58:20 AM	17.2	60.5	0.8	21.5			0.3	26.9	145.8	144.1
H-1963N	9/1/2026 10:59:34 AM	18.8	66.1	0.2	14.9			0.3	74.5	144.0	143.8
H-1963N	9/16/2026 12:20:55 PM	16.6	65.4	0.9	17.1			0.3	19.0	143.7	143.5
H-1963N	9/16/2026 12:21:46 PM	16.4	66.5	0.9	16.2			0.2	18.0	143.7	143.7
H-1966N	9/10/2026 9:06:20 AM	36.7	41.0	0.0	22.3			0.9	0.0	110.1	110.2
H-1966N	9/16/2026 2:32:58 PM	36.7	43.4	0.1	19.8			0.8	198.0	110.2	110.1
H-1967E	9/2/2026 10:44:57 AM	42.0	35.5	2.0	20.5			1.2	10.3	101.9	101.6
H-1967W	9/2/2026 1:39:12 PM	55.5	37.2	0.0	7.3			1.5	0.0	102.8	102.8
H-2050E	9/30/2026 9:51:30 AM	55.3	42.8	0.2	1.7			1.3	8.5	101.1	101.2
H-2050W	9/21/2026 2:03:14 PM	37.6	37.7	0.0	24.7			1.0	0.0	98.7	98.6
H-2050W	9/21/2026 2:07:51 PM	37.7	37.5	0.0	24.8			1.0	0.0	98.3	99.8
H-2050W	9/21/2026 2:09:57 PM	33.5	36.3	0.0	30.2			0.9	0.0	100.2	100.2
H-2051W	9/2/2026 1:36:38 PM	55.9	39.4	0.0	4.7			1.4	0.0	103.7	103.8
H-2053E	9/2/2026 10:36:42 AM	54.7	39.9	0.0	5.4			1.4	0.0	119.3	119.4
H-2055E	9/15/2026 10:19:32 AM	23.8	33.3	0.0	42.9			0.7	0.0	92.3	92.6
H-2055E	9/24/2026 1:41:22 PM						28000				
H-2055E	9/24/2026 1:42:43 PM	45.1	41.8	0.0	13.1			1.1	0.0	104.7	104.7
H-2055E	9/24/2026 1:45:00 PM					14.1					
H-2055E	9/24/2026 1:45:00 PM						3300				
H-2055E	9/24/2026 2:52:19 PM					20					
H-2055E	9/28/2026 8:24:51 AM	39.2	36.4	0.0	24.3			1.1	0.0	71.0	84.3
H-2055E	9/28/2026 8:27:27 AM	30.7	34.3	0.0	35.0			0.9	0.0	86.3	86.4
H-2056B	9/30/2026 10:41:17 AM	52.5	42.1	0.0	5.4			1.2	0.0	113.3	113.3
H-2056W	9/2/2026 1:33:36 PM	58.0	38.6	0.0	3.4			1.5	0.0	106.7	106.7
H-2057E	9/2/2026 10:33:09 AM	53.5	38.5	1.0	7.0			1.4	7.0	127.8	127.8
H-2058E	9/25/2026 8:43:12 AM	53.5	40.0	0.0	6.5			1.3	0.0	113.6	113.6
H-2058W	9/2/2026 1:31:18 PM	58.3	35.3	0.0	6.4			1.7	0.0	100.3	100.4

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
H-2059E	9/25/2026 8:48:49 AM	54.6	41.5	0.0	3.9			1.3	0.0	117.6	117.8
H-2059W	9/2/2026 1:18:59 PM	57.5	41.1	0.0	1.4			1.4	0.0	123.2	123.4
H-2161E	9/30/2026 4:18:18 PM	51.4	44.4	0.0	4.2			1.2	0.0	126.1	126.2
H-2161W	9/2/2026 1:15:54 PM	56.7	35.7	0.0	7.6			1.6	0.0	106.0	106.2
H-2163C	9/15/2026 10:57:08 AM	47.1	40.4	0.2	12.3			1.2	61.5	83.9	83.9
H-2163C	9/21/2026 11:35:30 AM	37.7	41.5	0.0	20.8			0.9	0.0	87.9	87.9
H-2163W	9/2/2026 9:04:51 AM	28.7	23.0	9.2	39.1			1.2	4.3	90.0	92.8
H-2163W	9/2/2026 9:05:57 AM	56.5	40.9	0.0	2.6			1.4	0.0	98.9	99.0
H-2163W	9/22/2026 12:25:17 PM	41.6	56.0	0.0	2.4			0.7	0.0	121.0	121.0
H-2164E	9/16/2026 3:11:14 PM	25.3	35.8	0.0	38.9			0.7	0.0	127.4	127.4
H-2164E	9/24/2026 1:20:04 PM						6000				
H-2164E	9/24/2026 1:23:09 PM	25.6	33.7	0.0	40.8			0.8	0.0	122.0	122.1
H-2164E	9/24/2026 1:25:00 PM					15					
H-2164E	9/24/2026 1:25:00 PM						1300				
H-2164E	9/24/2026 3:05:04 PM					28					
H-2165E	9/25/2026 9:23:57 AM	47.5	47.6	0.0	4.9			1.0	0.0	125.4	125.4
H-2165W	9/2/2026 8:43:14 AM	31.1	65.0	0.1	3.8			0.5	38.0	139.4	136.6
H-2165W	9/2/2026 8:45:08 AM	14.3	76.0	0.0	9.7			0.2	0.0	135.9	137.6
H-2165W	9/9/2026 7:00:00 AM					680					
H-2165W	9/9/2026 7:00:00 AM						51000				
H-2165W	9/23/2026 8:49:44 AM	8.9	88.0	0.0	3.1			0.1	0.0	147.2	147.2
H-2165W	9/30/2026 10:38:31 AM	10.1	73.5	0.0	16.4			0.1	0.0	148.0	146.0
H-2165W	9/30/2026 10:39:18 AM	19.4	75.3	0.0	5.3			0.3	0.0	144.9	145.2
H-2165W	9/30/2026 11:35:00 AM					218					
H-2166E	9/22/2026 10:33:01 AM	50.1	40.4	0.2	9.3			1.2	46.5	118.0	118.0
H-2168C	9/1/2026 12:08:00 PM	54.9	39.4	0.5	5.2			1.4	10.4	92.8	93.2
H-2168E	9/22/2026 10:07:45 AM	48.1	39.1	0.1	12.7			1.2	127.0	114.3	114.3
H-2169C	9/9/2026 1:00:48 PM	37.0	37.6	1.2	24.2			1.0	20.2	120.5	120.7
H-2169E	9/22/2026 9:11:45 AM	47.9	48.6	0.0	3.5			1.0	0.0	77.7	90.1
H-2169E	9/22/2026 9:12:40 AM	47.6	47.9	0.0	4.5			1.0	0.0	92.8	92.9
H-2169E	9/22/2026 10:14:12 AM	34.9	60.5	0.0	4.6			0.6	0.0	110.8	110.9
H-2170N	9/25/2026 11:43:20 AM	30.9	35.5	0.0	33.6			0.9	0.0	121.5	121.5
H-2170S	9/21/2026 12:50:35 PM	43.6	38.7	0.1	17.6			1.1	176.0	106.8	110.6
H-2171A	9/29/2026 10:23:57 AM	33.0	35.1	0.0	31.9			0.9	0.0	100.3	100.3
H-2171B	9/21/2026 9:19:40 AM	38.8	34.4	0.0	26.8			1.1	0.0	119.9	120.0

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
H-2171N	9/29/2026 10:44:58 AM	20.4	31.5	0.0	48.1			0.6	0.0	113.1	113.1
H-2171S	9/25/2026 11:49:39 AM	25.8	33.4	0.0	40.8			0.8	0.0	121.5	121.7
H-2272W	9/2/2026 9:18:52 AM	29.7	35.1	0.0	35.2			0.8	0.0	123.3	123.3
H-2272W	9/22/2026 12:19:10 PM	31.4	35.0	0.0	33.6			0.9	0.0	122.3	122.1
H-2273W	9/2/2026 7:21:33 AM	21.3	40.8	0.0	37.9			0.5	0.0	120.7	120.7
H-2273W	9/4/2026 8:32:00 AM					160					
H-2273W	9/4/2026 8:32:00 AM						18000				
H-2273W	9/9/2026 7:10:00 AM					78					
H-2273W	9/9/2026 7:10:00 AM						10000				
H-2273W	9/22/2026 12:09:18 PM	31.8	42.0	0.0	26.2			0.8	0.0	123.2	123.0
H-2274B	9/1/2026 2:15:59 PM	54.6	42.3	0.0	3.1			1.3	0.0	103.9	104.1
H-2274B	9/22/2026 2:38:09 PM	53.3	43.6	0.0	3.1			1.2	0.0	107.5	107.6
H-2274W	9/2/2026 7:28:33 AM	19.9	36.3	0.1	43.7			0.5	437.0	62.0	62.0
H-2274W	9/22/2026 11:23:46 AM	13.4	30.2	1.0	55.4			0.4	55.4	99.8	99.7
H-2275E	9/9/2026 1:51:36 PM	46.8	40.9	0.0	12.3			1.1	0.0	116.4	116.4
H-2275W	9/1/2026 11:38:16 AM	10.0	19.6	6.9	63.5			0.5	9.2	122.3	125.3
H-2275W	9/1/2026 11:39:55 AM	27.9	31.8	0.7	39.6			0.9	56.6	128.3	127.1
H-2275W	9/1/2026 11:41:12 AM	34.7	37.5	0.4	27.4			0.9	68.5	124.5	124.5
H-2275W	9/22/2026 12:53:21 PM	8.2	25.1	2.9	63.8			0.3	22.0	131.8	127.9
H-2275W	9/22/2026 12:53:59 PM	8.8	25.7	3.0	62.5			0.3	20.8	122.6	122.3
H-2276A	9/14/2026 1:55:11 PM	48.9	42.1	0.2	8.8			1.2	44.0	113.6	113.7
H-2276A	9/21/2026 9:31:10 AM	47.3	41.4	0.2	11.1			1.1	55.5	112.5	112.3
H-2276B	9/1/2026 2:23:18 PM	53.8	44.3	0.0	1.9			1.2	0.0	116.6	116.9
H-2276B	9/21/2026 9:13:01 AM	56.6	41.5	0.0	1.9			1.4	0.0	119.3	119.4
H-2276E	9/9/2026 1:36:12 PM	35.2	34.7	0.0	30.1			1.0	0.0	120.9	121.0
H-2276W	9/1/2026 9:23:11 AM	24.0	44.6	0.0	31.4			0.5	0.0	101.4	101.6
H-2276W	9/22/2026 11:39:01 AM	20.6	41.0	0.0	38.4			0.5	0.0	100.4	97.7
H-2277A	9/1/2026 10:22:08 AM	32.5	37.0	3.6	26.9			0.9	7.5	91.9	91.9
H-2277A	9/17/2026 10:03:32 AM	42.5	42.3	1.8	13.4			1.0	7.4	79.7	79.9
H-2277B	9/14/2026 1:34:55 PM	53.7	42.8	0.0	3.5			1.3	0.0	95.0	109.9
H-2277B	9/21/2026 8:52:57 AM	53.4	40.8	0.0	5.8			1.3	0.0	110.6	111.4
H-23 (EXP-23	9/21/2026 8:51:57 AM	2.7	80.6	0.0	16.7			0.0	0.0	75.7	75.8
H-2301E	9/24/2026 1:01:31 PM	54.2	40.3	0.0	5.5			1.3	0.0	102.7	102.7
H-2301N	9/16/2026 7:52:01 AM	54.0	35.6	0.0	10.4			1.5	0.0	89.6	91.2
H-2301N	9/23/2026 1:05:15 PM	35.9	32.0	0.0	32.1			1.1	0.0	98.6	98.6
H-2301W	9/28/2026 2:15:49 PM	0.1	0.4	20.8	78.7			0.4	3.8	92.1	92.4
H-2301W	9/28/2026 2:16:39 PM	0.2	0.3	20.8	78.7			0.8	3.8	94.7	94.8

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
H-2302C	9/17/2026 1:44:50 PM	50.0	39.9	0.0	10.1			1.3	0.0	122.8	122.8
H-2302C	9/17/2026 1:47:40 PM	49.7	39.9	0.0	10.4			1.2	0.0	122.8	122.8
H-2302E	9/24/2026 1:21:07 PM	54.4	42.0	0.0	3.6			1.3	0.0	110.8	110.9
H-2303E	9/24/2026 1:28:29 PM	56.3	39.7	0.0	4.0			1.4	0.0	101.5	101.8
H-2303N	9/21/2026 1:25:13 PM	37.3	33.5	3.5	25.8			1.1	7.5	107.7	107.9
H-2303N	9/21/2026 1:31:23 PM	38.4	34.2	3.3	24.1			1.1	7.4	108.2	108.2
H-2303N	9/21/2026 1:36:02 PM	40.6	35.4	2.7	21.3			1.1	8.0	108.1	108.0
H-2303N	9/21/2026 1:42:20 PM	41.8	35.9	2.6	19.7			1.2	7.6	107.9	107.9
H-2303N	9/21/2026 1:46:07 PM	41.7	35.9	2.7	19.8			1.2	7.5	108.1	108.3
H-2303S	9/30/2026 9:07:20 AM	50.2	41.2	0.0	8.6			1.2	0.0	107.2	108.2
H-2303S	9/30/2026 3:11:43 PM	49.0	38.4	0.0	12.6			1.3	0.0	110.8	110.8
H-2304E	9/24/2026 1:38:49 PM	54.4	41.0	0.0	4.6			1.3	0.0	98.9	98.8
H-2304S	9/30/2026 8:57:47 AM	48.5	40.5	0.0	11.0			1.2	0.0	112.7	112.7
H-2305N	9/21/2026 1:56:13 PM	36.5	36.1	0.0	27.5			1.0	0.0	101.1	101.2
H-2305S	9/30/2026 8:54:12 AM	53.6	43.5	0.0	2.9			1.2	0.0	127.3	127.2
H-2306N	9/30/2026 10:03:45 AM	49.7	44.3	0.0	6.0			1.1	0.0	119.2	119.2
H-2307S	9/28/2026 9:57:33 AM	49.1	41.1	0.2	9.6			1.2	48.1	108.0	106.9
H-2307S	9/28/2026 9:59:24 AM	49.2	40.7	0.2	9.9			1.2	52.1	108.5	109.0
H-2308S	9/28/2026 9:25:41 AM	46.3	40.8	0.0	12.8			1.1	0.0	98.0	98.6
H-2309N	9/23/2026 10:09:11 AM	46.9	39.5	0.0	13.6			1.2	0.0	103.0	103.5
H-2309S	9/28/2026 1:47:35 PM	50.4	41.7	0.0	7.8			1.2	0.0	120.4	120.4
H-2309S	9/28/2026 1:50:05 PM	50.1	42.5	0.0	7.5			1.2	0.0	120.5	120.5
H-2310N	9/21/2026 10:17:15 AM	55.4	41.5	0.0	3.2			1.3	0.0	110.4	110.5
H-2310N	9/21/2026 10:23:24 AM	54.9	41.4	0.0	3.8			1.3	0.0	111.4	113.5
H-2310N	9/21/2026 10:25:58 AM	52.0	43.2	0.0	4.8			1.2	0.0	113.6	113.7
H-2310S	9/30/2026 9:54:34 AM	51.8	43.0	0.0	5.2			1.2	0.0	99.6	99.6
H-2401S	9/17/2026 12:53:46 PM	54.0	40.8	0.0	5.1			1.3	0.0	112.3	112.3
H-2401S	9/17/2026 12:55:27 PM	54.0	40.9	0.0	5.1			1.3	0.0	112.2	112.3
H-2402N	9/16/2026 9:29:50 AM	35.7	36.8	0.0	27.5			1.0	0.0	111.0	110.4
H-2402N	9/16/2026 9:38:17 AM	31.8	35.6	0.0	32.6			0.9	0.0	109.6	109.8
H-2402S	9/17/2026 10:29:36 AM	44.0	40.5	0.0	15.6			1.1	0.0	112.8	112.8
H-2402S	9/17/2026 10:36:31 AM	44.2	40.1	0.0	15.8			1.1	0.0	112.8	112.8
H-2403N	9/16/2026 9:07:19 AM	24.1	28.3	4.2	43.5			0.8	10.4	118.4	117.3
H-2403N	9/16/2026 9:15:02 AM	32.5	33.3	3.2	31.1			1.0	9.8	116.6	116.5

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
H-2403S	9/17/2026 9:46:50 AM	48.6	41.3	0.5	9.6			1.2	18.5	77.4	84.4
H-2403S	9/17/2026 9:55:54 AM	53.1	43.0	0.0	3.9			1.2	0.0	88.4	91.0
H-2403S	9/17/2026 10:14:23 AM	53.1	42.7	0.0	4.2			1.2	0.0	95.4	95.8
H-2404N	9/4/2026 10:12:11 AM	50.2	43.7	0.0	6.1			1.1	0.0	116.6	116.6
H-2404N	9/17/2026 10:16:28 AM	53.4	42.5	0.0	4.1			1.3	0.0	96.1	96.2
H-2404S	9/17/2026 9:29:43 AM	53.9	41.4	0.0	4.7			1.3	0.0	114.9	115.0
H-2405N	9/30/2026 12:52:28 PM	26.8	35.9	0.0	37.3			0.7	0.0	125.6	125.5
H-29	9/25/2026 11:24:23 AM	18.4	44.5	1.8	35.3			0.4	19.6	104.8	103.6
H-72	9/30/2026 1:21:04 PM	41.5	55.7	0.0	2.8			0.7	0.0	101.4	101.6
H-74	9/16/2026 11:51:01 AM	49.7	42.2	0.0	8.1			1.2	0.0	113.4	113.4
H-75	9/22/2026 2:37:52 PM	37.6	39.7	0.0	22.7			0.9	0.0	96.3	96.5
H-79	9/4/2026 9:06:09 AM	47.5	44.1	0.0	8.4			1.1	0.0	123.7	123.6
P-02R	9/14/2026 10:11:10 AM	26.5	30.3	0.0	43.2			0.9	0.0	89.7	89.8
P-03R	9/14/2026 1:32:02 PM	40.3	30.0	0.0	29.7			1.3	0.0	102.9	102.8
P-04	9/14/2026 1:26:28 PM	50.2	36.2	0.0	13.6			1.4	0.0	103.6	103.6
P-05	9/14/2026 1:22:06 PM	39.7	33.0	0.0	27.3			1.2	0.0	106.0	106.0
P-06R	9/14/2026 1:14:43 PM	40.7	32.4	0.0	26.9			1.3	0.0	113.9	114.9
P-07R	9/14/2026 9:55:22 AM	30.1	26.8	0.0	43.1			1.1	0.0	89.9	89.8
P-08R	9/14/2026 10:17:08 AM	53.1	37.7	0.0	9.2			1.4	0.0	100.4	100.4
P-09	9/14/2026 10:29:35 AM	48.2	36.0	0.0	15.8			1.3	0.0	98.1	98.2
P-10	9/14/2026 10:34:17 AM	41.5	33.6	0.0	24.9			1.2	0.0	96.1	96.1
P-11	9/14/2026 10:41:27 AM	45.5	35.8	0.0	18.7			1.3	0.0	106.8	107.1
P-12	9/14/2026 1:08:27 PM	57.2	38.9	0.0	3.9			1.5	0.0	90.1	89.9
P-13	9/14/2026 1:02:12 PM	51.6	35.3	0.0	13.1			1.5	0.0	91.5	91.2
P-14	9/14/2026 10:49:55 AM	27.0	27.7	0.4	44.9			1.0	112.3	87.8	88.0
P-15R	9/11/2026 9:23:55 AM	50.1	34.4	0.0	15.5			1.5	0.0	93.3	93.6
P-16	9/11/2026 9:31:08 AM	52.9	35.6	0.0	11.5			1.5	0.0	99.1	99.0
P-17	9/11/2026 1:40:34 PM	37.7	29.5	0.0	32.8			1.3	0.0	114.1	114.1
P-18RD	9/11/2026 1:30:44 PM	50.6	32.8	0.0	16.6			1.5	0.0	100.3	100.7
P-18RS	9/11/2026 1:34:14 PM	39.2	32.8	0.0	28.0			1.2	0.0	99.8	99.8
P-19	9/11/2026 1:55:29 PM	29.6	27.6	0.0	42.8			1.1	0.0	96.5	96.4
P-20R	9/11/2026 1:23:45 PM	46.0	32.8	0.0	21.2			1.4	0.0	101.6	101.7
P-21	9/11/2026 1:17:27 PM	33.6	29.2	0.0	37.2			1.2	0.0	98.9	98.5
P-21RD	9/11/2026 1:06:36 PM	41.4	32.0	0.0	26.6			1.3	0.0	105.3	105.4
P-21RS	9/11/2026 1:09:45 PM	44.4	35.6	0.0	20.0			1.2	0.0	110.0	110.1
P-22RD	9/11/2026 8:08:10 AM	53.5	40.5	0.0	6.0			1.3	0.0	120.4	120.4
P-22RS	9/11/2026 8:04:52 AM	31.5	29.8	0.0	38.7			1.1	0.0	121.9	122.0
P-23	9/11/2026 1:01:52 PM	4.9	19.7	0.1	75.3			0.2	753.0	103.2	106.6
P-24	9/13/2026 1:20:31 PM	20.0	27.3	0.0	52.7			0.7	0.0	101.1	101.2

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
P-26	9/13/2026 1:35:13 PM	44.9	31.8	0.0	23.3			1.4	0.0	90.7	89.4
P-27	9/13/2026 1:42:38 PM	11.1	20.9	0.0	68.0			0.5	0.0	96.8	96.9
P-28	9/13/2026 1:49:04 PM	36.7	30.9	0.0	32.4			1.2	0.0	98.6	98.6
P-28	9/25/2026 2:03:37 PM	37.9	25.5	1.8	34.8			1.5	19.3		
P-29R	9/14/2026 8:03:35 AM	28.6	29.6	0.0	41.8			1.0	0.0	87.8	87.7
P-30R	9/14/2026 8:11:45 AM	24.2	28.5	0.0	47.3			0.8	0.0	86.7	86.7
P-32R1	9/14/2026 8:36:49 AM	27.5	30.8	0.6	41.1			0.9	68.5	113.4	113.4
P-32R2	9/14/2026 8:45:03 AM	32.4	32.8	0.1	34.7			1.0	347.0	110.0	110.0
P-33	9/14/2026 8:50:19 AM	46.3	37.1	0.0	16.6			1.2	0.0	93.2	93.4
P-36	9/14/2026 9:06:39 AM	24.9	30.3	0.0	44.8			0.8	0.0	85.6	99.7
P-36	9/14/2026 9:07:30 AM	24.6	30.6	0.0	44.8			0.8	0.0	100.0	101.6
P-37	9/14/2026 9:26:35 AM	11.3	25.4	0.4	62.9			0.4	157.3	93.5	93.8
P-38RD	9/9/2026 1:02:10 PM	41.9	35.5	0.0	22.6			1.2	0.0	109.1	109.1
P-38RS	9/9/2026 12:58:14 PM	30.6	30.1	0.0	39.3			1.0	0.0	107.9	107.9
P-39	9/9/2026 1:09:03 PM	4.6	5.0	18.3	72.1			0.9	3.9	114.9	115.1
P-39	9/9/2026 1:12:07 PM	5.0	4.6	18.1	72.3			1.1	4.0	116.8	116.7
P-41	9/9/2026 1:35:32 PM	35.3	29.7	2.8	32.2			1.2	11.5	118.7	118.8
P-42R	9/9/2026 1:46:37 PM	48.1	35.2	0.0	16.7			1.4	0.0	117.9	118.0
P-43	9/9/2026 1:51:47 PM	22.7	28.4	0.4	48.5			0.8	121.3	119.1	119.1
P-44RD	9/9/2026 1:59:38 PM	48.3	34.6	0.0	17.1			1.4	0.0	114.8	115.3
P-44RS	9/9/2026 1:56:43 PM	20.7	25.9	0.0	53.4			0.8	0.0	123.8	123.8
P-45RD	9/11/2026 7:34:35 AM	45.5	35.5	0.0	19.0			1.3	0.0	117.2	117.2
P-45RS	9/11/2026 7:38:47 AM	2.6	21.3	0.0	76.1			0.1	0.0	114.0	114.0
P-46RD	9/11/2026 7:48:05 AM	52.4	36.5	0.0	11.1			1.4	0.0	107.4	107.6
P-46RS	9/11/2026 7:50:57 AM	17.6	27.6	0.0	54.8			0.6	0.0	121.9	122.0
P-47	9/11/2026 7:57:45 AM	2.4	18.1	1.1	78.4			0.1	71.3	88.7	89.0
P-48	9/11/2026 8:17:55 AM	15.3	23.0	0.0	61.7			0.7	0.0	123.4	130.5
P-49RD	9/2/2026 12:40:19 PM	56.9	38.3	0.0	4.8			1.5	0.0	114.9	114.9
P-49RS	9/2/2026 12:36:19 PM	38.3	32.4	0.2	29.1			1.2	145.5	115.4	115.4
P-52	9/2/2026 12:48:58 PM	32.8	32.3	0.0	34.9			1.0	0.0	114.9	115.0
P-53	9/2/2026 12:54:52 PM	25.7	28.2	0.0	46.1			0.9	0.0	114.9	114.7
P-54	9/2/2026 1:04:15 PM	37.8	31.7	0.0	30.5			1.2	0.0	101.0	101.9
P-55	9/2/2026 1:11:35 PM	36.3	31.8	0.0	31.9			1.1	0.0	101.6	101.6
P-56	9/2/2026 1:26:56 PM	19.9	26.7	0.0	53.4			0.7	0.0	104.5	104.5
P-57	9/2/2026 1:19:29 PM	32.3	28.9	1.3	37.5			1.1	28.8	89.5	89.5
P-60R	9/2/2026 1:44:59 PM	60.5	38.4	0.0	1.1			1.6	0.0	96.1	95.7
P-61	9/3/2026 10:41:33 AM	42.8	35.8	0.0	21.4			1.2	0.0	88.6	88.7
P-65	9/3/2026 10:49:34 AM	29.7	29.3	0.0	41.0			1.0	0.0	87.2	87.1
P-71	9/11/2026 8:24:58 AM	39.5	32.8	0.0	27.7			1.2	0.0	82.4	82.7
P-75	9/2/2026 1:35:58 PM	55.9	36.6	0.0	7.5			1.5	0.0	94.5	94.8
P-76	9/9/2026 12:51:44 PM	19.2	27.9	0.0	52.9			0.7	0.0	120.2	120.5
P-79	9/11/2026 1:48:37 PM	24.1	27.0	0.0	48.9			0.9	0.0	100.0	99.6

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
P-79	9/14/2026 7:34:29 AM	19.1	25.5	1.3	54.1			0.7	41.6	89.2	89.7
SC-2000E	9/25/2026 8:57:52 AM	45.9	39.7	0.0	14.4			1.2	0.0	120.7	120.7
SC-2501E	9/8/2026 9:59:28 AM	2.6	71.6	0.4	25.4			0.0	63.5	189.2	189.3
SC-2501E	9/8/2026 10:01:00 AM					1240					
SC-2501E	9/14/2026 9:17:00 AM					1190					
SC-2501E	9/14/2026 9:21:21 AM	10.6	69.6	1.3	18.5			0.2	14.2	188.8	189.1
SC-2501E	9/14/2026 9:23:51 AM	14.0	68.9	0.9	16.2			0.2	18.0	189.2	189.1
SC-2501E	9/21/2026 9:24:00 AM					1120					
SC-2501E	9/21/2026 9:24:06 AM	12.2	72.7	0.9	14.2			0.2	15.8	189.9	189.9
SC-2501E	9/28/2026 8:44:16 AM	9.2	72.4	0.9	17.5			0.1	19.4	189.9	189.8
SC-2501E	9/28/2026 8:50:00 AM					1140					
SC-2501W	9/14/2026 1:14:36 PM	2.2	73.5	0.5	23.8			0.0	47.6	190.3	190.3
SC-2501W	9/14/2026 1:16:00 PM	2.5	73.3	0.4	23.8			0.0	59.5	190.3	190.3
SC-2501W	9/21/2026 9:47:01 AM	13.5	67.7	2.1	16.7			0.2	8.0	189.2	189.2
SC-2501W	9/21/2026 9:50:00 AM					722					
SC-2501W	9/28/2026 9:27:48 AM	16.8	64.8	1.8	16.6			0.3	9.2	188.8	188.9
SC-2501W	9/28/2026 9:30:00 AM					741.5					
SW-10	9/28/2026 10:08:23 AM	19.5	35.0	2.2	43.3			0.6	19.7	89.7	89.9
SW-115	9/17/2026 1:39:25 PM	41.5	34.0	1.0	23.5			1.2	23.5	90.2	90.2
SW-1445	9/29/2026 12:27:40 PM	39.0	31.6	0.1	29.3			1.2	293.0	92.5	92.2
SW-1455	9/30/2026 4:06:16 PM	48.4	39.4	0.0	12.2			1.2	0.0	113.7	114.9
SW-154	9/30/2026 2:17:21 PM	0.0	2.9	19.5	77.6			0.0	4.0	105.2	105.4
SW-17-135	9/30/2026 4:01:25 PM	38.3	27.5	0.0	34.2			1.4	0.0	111.1	111.9
SW-187	9/23/2026 9:03:24 AM	19.3	40.9	1.9	37.9			0.5	19.9	83.6	83.9
SW-20	9/14/2026 10:03:19 AM	0.0	4.7	15.9	79.4			0.0	5.0	93.7	94.2
SW-20	9/14/2026 10:04:06 AM	0.0	4.8	16.0	79.2			0.0	5.0	94.7	94.6
SW-2501D	9/28/2026 8:51:48 AM	0.5	5.8	19.5	74.2			0.1	3.8	74.7	74.7
SW-2501M	9/28/2026 8:37:05 AM	14.7	24.8	12.2	48.3			0.6	4.0	67.5	67.5
SW-2501MD	9/28/2026 8:48:27 AM	21.0	52.3	3.5	23.2			0.4	6.6	72.4	72.5
SW-2501S	9/28/2026 8:34:18 AM	4.2	11.6	11.1	73.1			0.4	6.6	65.9	65.9
SW-2502D	9/28/2026 1:31:44 PM	7.0	79.2	0.1	13.7			0.1	137.0	93.8	93.9
SW-2502M	9/28/2026 1:35:12 PM	0.0	3.5	19.6	76.9			0.0	3.9	94.5	94.5
SW-2502MD	9/28/2026 9:07:21 AM	6.6	49.6	9.8	34.0			0.1	3.5	82.3	82.3

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init °F Temp [ ]	Adj °F Temp [ ]
SW-2502S	9/28/2026 9:04:57 AM	5.2	23.9	10.4	60.5			0.2	5.8	82.5	82.5
SW-2503D	9/28/2026 9:31:14 AM	2.9	11.7	17.2	68.2			0.2	4.0	81.0	81.1
SW-2503M	9/28/2026 9:36:56 AM	0.0	1.5	20.0	78.5			0.0	3.9	85.9	86.6
SW-2503MD	9/28/2026 9:43:35 AM	5.2	21.3	12.5	61.0			0.2	4.9	86.2	86.2
SW-2503S	9/28/2026 9:40:46 AM	12.3	22.7	12.3	52.7			0.5	4.3	82.0	82.1
SW-2504D	9/28/2026 9:56:00 AM	0.2	1.6	19.5	78.7			0.1	4.0	81.4	81.5
SW-2504M	9/28/2026 9:49:08 AM	0.1	2.4	19.6	77.9			0.0	4.0	85.0	85.2
SW-2504MD	9/28/2026 9:59:28 AM	12.5	28.8	7.7	51.0			0.4	6.6	82.7	82.9
SW-2504S	9/28/2026 9:52:36 AM	14.4	14.4	10.9	60.3			1.0	5.5	85.6	85.7
SW-30	9/28/2026 8:56:46 AM	5.1	27.6	11.2	56.1			0.2	5.0	73.2	73.5
SW-32	9/28/2026 8:26:06 AM	14.0	53.1	7.6	25.3			0.3	3.3	71.2	71.6
SW-64	9/28/2026 8:59:49 AM	13.0	76.2	1.2	9.6			0.2	8.0	77.6	77.4
SW-65	9/17/2026 10:54:03 AM	36.4	33.5	0.9	29.2			1.1	32.4	87.8	87.8
SW-65	9/17/2026 11:10:21 AM	43.3	55.0	0.0	1.7			0.8	0.0	110.6	110.4
SW-66	9/30/2026 2:19:22 PM	6.0	6.1	13.9	74.0			1.0	5.3	91.8	91.8
SW-68	9/28/2026 8:30:14 AM	13.1	34.5	1.8	50.6			0.4	28.1	66.4	66.4
SW-70	9/23/2026 9:06:01 AM	14.5	66.2	0.9	18.4			0.2	20.4	89.1	89.1
SW-71	9/13/2026 1:27:50 PM	13.5	17.5	7.2	61.8			0.8	8.6	95.2	95.1
SW-71	9/13/2026 1:29:03 PM	13.4	17.6	7.1	61.9			0.8	8.7	95.1	95.1
SW-72	9/14/2026 8:57:13 AM	22.8	22.4	5.0	49.8			1.0	10.0	76.6	76.4
SW-80	9/3/2026 12:03:20 PM	27.1	28.6	1.8	42.5			0.9	23.6	92.6	93.3
SW-9	9/23/2026 9:09:10 AM	0.9	20.8	13.2	65.1			0.0	4.9	86.4	86.4
TC-1961C	9/24/2026 11:07:18 AM	6.0	24.0	0.0	70.0			0.3	0.0	118.5	118.5
TC-1961E	9/1/2026 9:15:54 AM	45.2	48.9	0.0	5.9			0.9	0.0	125.0	124.8
TC-2174	9/8/2026 9:41:41 AM	1.4	78.8	0.0	19.8			0.0	0.0	185.6	185.6
TC-2174	9/8/2026 9:44:00 AM					1880					
TC-2174	9/14/2026 8:44:26 AM	3.3	78.6	0.0	18.1			0.0	0.0	185.7	185.7
TC-2174	9/14/2026 8:47:00 AM					2370					
TC-2174	9/21/2026 9:00:00 AM					2080					
TC-2174	9/21/2026 9:00:43 AM	6.3	77.1	0.0	16.6			0.1	0.0	185.7	185.6
TC-2174	9/28/2026 8:20:43 AM	2.0	77.9	0.0	20.1			0.0	0.0	185.8	185.9
TC-2174	9/28/2026 8:25:00 AM					1710					
VL-02	9/30/2026 10:59:45 AM	59.1	34.6	0.2	6.1			1.7	30.5	99.8	100.2

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
A-01	9/17/2026 7:39:23 AM	-25.51				25.633		-25.01		28.85
A-02	9/17/2026 7:48:47 AM	-13.75	-13.77			13.793	13.865	-13.25	-13.35	28.85
A-03	9/17/2026 8:00:42 AM	-25.28	-25.32			25.399	25.471	-24.40	-24.51	28.85
A-04	9/17/2026 8:10:05 AM	-24.19	-24.30			24.331	24.471	-23.70	-23.43	28.85
A-05	9/28/2026 8:50:32 AM	-21.69	-21.63			21.774	21.670	0.00	0.00	28.59
B-01	9/17/2026 9:22:43 AM	-1.52	-1.51	2.1	2.1	1.119	1.077	-22.12	-21.94	28.81
B-02R	9/17/2026 9:16:57 AM	-3.44	-3.74	2.3	3.0	0.552	0.890	-22.29	-22.18	28.81
B-03R	9/16/2026 1:51:26 PM	-0.92	-0.92	1.7	1.8	0.751	0.846	-20.73	-20.85	28.74
B-05	9/16/2026 2:03:40 PM	-0.40	-0.46	5.6	5.6	0.189	0.186	-20.90	-20.61	28.73
B-06	9/17/2026 8:53:22 AM	-0.71	-0.74	3.8	4.2	0.087	0.103	-21.12	-20.78	28.82
B-07R	9/16/2026 10:45:52 AM	-0.96	-0.87	8.5	7.7	18.741	15.405	-21.67	-21.81	28.78
B-07R	9/16/2026 10:52:10 AM	-1.37	-1.33	3.5	5.3	0.248	0.564	-20.76	-21.96	28.78
B-08	9/17/2026 8:39:40 AM	-20.91	-20.86	1.0	1.2	0.007	0.008	-20.49	-20.46	28.83
B-08	9/17/2026 8:44:20 AM	-21.00	-21.00	0.5	0.7	0.004	0.010	-20.53	-20.50	28.82
B-09	9/16/2026 9:27:25 AM	-0.44	-0.43			0.433	0.428	-18.99	-19.08	28.77
B-10	9/16/2026 9:20:22 AM	-0.27	-0.38			0.266	0.375	-19.00	-19.03	28.74
B-11	9/16/2026 8:54:56 AM	-0.42	-0.41	12.1	15.1	0.332	0.514	-18.82	-18.99	28.81
B-12	9/16/2026 1:43:21 PM	-1.29	-1.28	10.4	10.1	0.655	0.619	-20.77	-20.95	28.74
B-13	9/16/2026 1:37:34 PM	-0.90	-0.87			0.862	0.869	-20.97	-21.27	28.74
B-14	9/16/2026 8:34:59 AM	-0.73	-1.41	2.5	2.7	0.670	0.788	-19.54	-19.53	28.81
C-03	9/14/2026 1:58:34 PM	-28.42	-28.06			28.451	28.061	-28.21	-27.91	28.62
C-07	9/30/2026 3:03:49 PM	-14.02	-14.02			14.179	14.076	-14.09	-14.01	28.59
C-08	9/17/2026 10:13:25 AM	-23.42	-23.61			23.561	23.704	-22.94	-23.11	28.85
C-08	9/17/2026 10:15:37 AM	-23.49	-23.36			23.672	23.569	-23.13	-22.92	28.85
C-10	9/17/2026 10:44:49 AM	-23.70	-23.95			23.989	24.172	-23.27	-23.50	28.86
C-11	9/3/2026 11:22:35 AM	-14.94	-15.07	17.5	15.5	0.705	0.555	-14.87	-14.97	28.76
C-12	9/3/2026 11:48:07 AM	-15.85	-16.02	11.0	10.4	0.762	0.687	-17.11	-17.22	28.77
C-15	9/3/2026 11:44:12 AM	-13.88	-13.86	17.3	16.2	0.690	0.606	-13.96	-13.88	28.78
C-17B	9/29/2026 9:29:28 AM	-16.75	-16.45			16.692	16.465	-17.52	-17.07	28.49
C-18	9/29/2026 10:05:18 AM	-13.09	-12.82			13.039	12.854	-12.96	-12.92	28.49
C-19	9/29/2026 9:49:37 AM	-17.14	-17.12			17.151	17.051	-17.11	-17.11	28.49
C-20	9/29/2026 9:55:47 AM	-17.12	-17.12			17.115	17.169	-17.11	-17.11	28.49
C-24	9/29/2026 9:39:17 AM	-1.73	-1.82			1.721	1.812	-17.23	-17.11	28.5
C-24	9/29/2026 9:44:02 AM	-2.67	-2.62			2.637	2.668	-17.03	-17.20	28.49
C-25	9/25/2026 12:09:01 PM	-14.61	-14.62			15.091	15.132	-14.54	-14.55	28.71
C-25	9/25/2026 12:10:05 PM	-14.82	-14.85			15.259	15.220	-14.56	-14.59	28.72
C-26	9/25/2026 12:01:24 PM	-16.15	-16.25			16.569	16.617	-16.24	-16.25	28.72

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
C-27	9/3/2026 11:37:39 AM	-13.49	-13.43	5.3	5.2	0.587	0.569	-13.98	-14.43	28.78
C-27	9/3/2026 11:38:33 AM	-13.43	-13.43	5.0	5.0	0.522	0.522	-14.04	-13.80	28.76
C-28	9/3/2026 11:18:29 AM	-8.39	-9.07	3.0	3.8	2.450	3.745	-15.77	-15.71	28.77
C-29	9/21/2026 8:03:56 AM	-5.80	-5.83			5.883	5.887	-19.29	-19.01	28.7
C-30	9/17/2026 10:25:51 AM	-0.52	-0.51	0.5	0.8	0.001	0.004	-22.63	-22.74	28.85
C-30	9/17/2026 10:32:06 AM	-2.44	-2.44	5.5	5.6	0.193	0.195	-23.36	-23.34	28.83
CV-02	9/21/2026 10:39:51 AM	-0.81	-1.65	0.7	1.3	0.051	0.186	-25.35	-25.41	28.7
CV-03	9/21/2026 12:58:06 PM	-10.10	-10.00	21.1	20.9	2.920	2.872	-20.99	-20.83	28.7
CV-04	9/30/2026 8:15:05 AM	-1.57	-1.56			1.572	1.573	-21.56	-21.58	28.57
CV-05	9/4/2026 8:19:06 AM	-12.55	-12.66	3.3	3.1	0.228	0.210	-12.75	-12.87	28.68
CV-06	9/28/2026 3:58:30 PM	-18.39	-13.54	4.0	3.7	0.103	0.086	-21.10	-20.75	28.48
CV-108-52	9/1/2026 7:25:00 AM									
CV-108-52	9/1/2026 7:25:00 AM									
CV-108-52	9/2/2026 7:35:40 AM	10.57	12.65	0.0	0.0	-0.009	-0.011	12.63		28.68
CV-108-52	9/2/2026 7:36:35 AM	11.01	11.01	0.0	0.0	-0.014	-0.012	11.02		28.68
CV-108-52	9/10/2026 3:44:09 PM	1.07	-1.86			0.900	0.126	-3.51	-2.80	28.54
CV-108-52	9/10/2026 3:44:53 PM	-2.85	-2.89			0.209	0.209	-3.79	-4.04	28.53
CV-108-52	9/22/2026 11:11:22 AM	-9.72	-9.17			0.004	0.011	-9.88		28.62
CV-113	9/4/2026 7:00:00 AM									
CV-113	9/4/2026 7:00:00 AM									
CV-113	9/14/2026 9:34:21 AM	-0.02	-0.02	0.8	0.8	0.004	0.004	-6.79	-6.79	28.56
CV-113	9/14/2026 9:35:35 AM	-0.03	-0.02	0.9	0.7	0.005	0.003	-6.83	-6.77	28.58
CV-113	9/25/2026 10:33:54 AM	-0.01	-0.01	1.9	1.9	0.022	0.023	-7.89	-7.78	28.57
CV-114	9/4/2026 8:22:00 AM									
CV-114	9/4/2026 8:22:00 AM									
CV-114	9/8/2026 9:33:48 AM	-4.74	-4.61			4.706	4.592	-4.67	-4.76	28.61
CV-114	9/8/2026 9:39:00 AM									
CV-114	9/14/2026 8:28:09 AM	-7.52	-7.31			7.604	7.365	-7.53	-7.39	28.49
CV-114	9/14/2026 8:30:00 AM									
CV-114	9/21/2026 8:22:00 AM	-4.77	-4.56			4.808	4.687	-7.74	-7.12	28.6
CV-114	9/21/2026 8:25:00 AM									
CV-114	9/28/2026 8:16:00 AM	-8.17	-8.17			8.319	8.363	-8.81	-8.46	28.46
CV-114	9/28/2026 8:20:00 AM									

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-114	9/28/2026 8:20:00 AM									
CV-1424	9/3/2026 1:47:43 PM	-4.12	-3.36	29.6	24.8	5.602	3.900	-20.20	-21.13	28.45
CV-1532A	9/1/2026 7:30:00 AM									
CV-1532A	9/1/2026 7:30:00 AM									
CV-1532A	9/1/2026 1:33:46 PM	-3.50	-3.64			3.465	3.487	-3.36	-3.50	28.69
CV-1532A	9/30/2026 3:06:52 PM	-7.59	-7.76			7.849	7.937	-7.69	-7.70	28.45
CV-1534A-PL	9/2/2026 10:23:59 AM	-6.56	-6.40			6.986	6.748	0.53	0.67	28.72
CV-1534A-PL	9/30/2026 3:09:20 PM	-0.09	-0.07			0.070	0.027	-0.07	-0.09	28.44
CV-1535	9/1/2026 9:18:24 AM	-0.58	-0.53	0.0	0.0	0.643	0.554	-1.67		28.63
CV-1535	9/4/2026 7:22:00 AM									
CV-1535	9/4/2026 7:22:00 AM									
CV-1535	9/22/2026 11:06:11 AM	-6.94	-5.60	0.0	0.0	0.012	0.001	-9.75		28.59
CV-1535	9/24/2026 2:43:07 PM	-5.40	-4.58			0.000	0.000	-7.31	-10.52	28.51
CV-1601D	9/15/2026 11:02:56 AM	-0.94	-1.18	7.2	12.8	1.088	3.446	-14.31	-13.96	28.67
CV-1601D	9/21/2026 11:29:39 AM	-1.48	-1.28	13.0	9.6	3.558	1.950	-16.02	-17.73	28.69
CV-1601S	9/15/2026 11:06:57 AM	-1.21	-1.50	5.2	10.9	0.563	2.521	-13.96	-14.29	28.68
CV-1601S	9/21/2026 11:25:45 AM	-1.81	-1.54	11.8	6.5	2.959	0.900	-17.09	-18.80	28.67
CV-1604	9/24/2026 10:50:44 AM	-0.18	-0.07	1.4	2.2	0.040	0.101	-13.70	-13.42	28.6
CV-1701D	9/1/2026 8:45:21 AM	-14.14	-14.14	1.1	1.1	0.342	0.325	-16.83	-16.71	28.64
CV-1701S	9/1/2026 8:41:19 AM	-0.32	-0.31	1.3	1.1	0.011	0.008	-16.75	-16.76	28.65
CV-1901	9/14/2026 9:48:47 AM	-4.42	-1.79	1.6	1.4	0.053	0.040	-7.68	-7.87	28.48
CV-1901	9/16/2026 2:06:50 PM	-0.53	-0.72	2.0	1.9	0.083	0.072	-4.31	-4.69	28.57
CV-1902A	9/1/2026 7:35:00 AM									
CV-1902A	9/1/2026 7:35:00 AM									
CV-1902A	9/8/2026 10:47:01 AM	-5.70	-5.63	0.0	0.0	5.732	5.463	-5.27		28.65
CV-1902A	9/8/2026 10:50:00 AM									
CV-1902A	9/16/2026 2:31:00 PM									
CV-1902A	9/16/2026 2:32:50 PM	-6.63	-6.42			6.857	6.629	-6.80	-6.60	28.61
CV-1902A	9/23/2026 2:32:08 PM	-7.43	-7.12			7.637	7.265	-7.73	-7.37	28.49
CV-1902A	9/23/2026 2:37:00 PM									
CV-1902A	9/30/2026 2:35:00 PM									

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-1902A	9/30/2026 2:40:44 PM	-6.05	-6.02			6.098	5.977	-6.06	-5.89	28.44
CV-1905	9/14/2026 1:14:41 PM	-0.42	-0.42	1.2	1.2	0.008	0.008	-23.43	-23.15	28.37
CV-1905	9/22/2026 9:36:40 AM	-0.30	-1.49	1.1	8.4	0.008	0.429	-14.08	-13.89	28.54
CV-1905	9/24/2026 2:08:39 PM	-0.97	-1.11	10.2	9.1	0.663	0.520	-12.29	-11.71	28.45
CV-2001	9/2/2026 8:39:57 AM	-8.38	-8.03	0.0	1.3	-0.229	0.042	-8.32		28.7
CV-2001	9/9/2026 7:20:00 AM									
CV-2001	9/9/2026 7:20:00 AM									
CV-2001	9/23/2026 8:47:00 AM	-11.67	-11.60	3.8	4.7	0.019	0.028	-11.68	-11.65	28.58
CV-2002	9/1/2026 2:10:00 PM									
CV-2002	9/1/2026 2:10:00 PM									
CV-2002	9/1/2026 2:10:13 PM	-6.92	-6.94			6.991	7.031	-7.08	-7.10	28.71
CV-2002	9/8/2026 1:42:58 PM	-5.92	-5.00	0.0	0.0	-6.163	-5.003	-4.44		28.68
CV-2002	9/8/2026 1:45:00 PM									
CV-2002	9/9/2026 7:25:00 AM									
CV-2002	9/9/2026 7:25:00 AM									
CV-2002	9/17/2026 8:11:35 AM	-6.40	-6.23			6.612	6.322	-10.78	-9.77	28.79
CV-2002	9/17/2026 8:13:00 AM									
CV-2002	9/24/2026 9:58:49 AM	-10.65	-10.45			11.109	10.957	-11.71	-10.76	28.64
CV-2002	9/24/2026 10:10:00 AM									
CV-2003	9/2/2026 7:38:27 AM	10.59	10.61	0.0	1.5	-0.051	0.298	10.62		28.68
CV-2003	9/2/2026 7:41:22 AM	13.76	13.25	2.5	2.3	0.787	0.666	13.25		28.68
CV-2003	9/10/2026 3:49:41 PM	-5.01	-5.03	1.5	1.5	0.234	0.252	-5.46	-5.66	28.55
CV-2003	9/10/2026 3:50:31 PM	-5.16	-5.22	1.3	1.3	0.183	0.178	-5.58	-5.39	28.53
CV-2003	9/22/2026 11:14:52 AM	-9.57	-9.05	0.7	1.0	0.072	0.150	-9.90		28.62
CV-2006	9/8/2026 10:53:00 AM	-3.36	-3.37	0.0	0.0	-0.010	-0.010	-5.67		28.64
CV-2006	9/8/2026 11:05:00 AM									
CV-2006	9/16/2026 2:22:00 PM									
CV-2006	9/16/2026 2:23:56 PM	-4.30	-4.30	17.9	17.1	0.470	0.429	-7.08	-7.20	28.6
CV-2006	9/23/2026 2:26:56 PM	-4.39	-4.34	16.3	12.1	0.392	0.216	-8.24	-7.83	28.49
CV-2006	9/23/2026 2:29:00 PM									
CV-2006	9/30/2026 2:25:00 PM									
CV-2006	9/30/2026 2:27:51 PM	-5.43	-4.67	13.2	17.2	0.257	0.437	-8.43	-8.59	28.44
CV-2007	9/3/2026 10:00:55 AM	-1.12	-1.15	4.3	5.0	0.051	0.068	-5.37	-5.39	28.53
CV-2007	9/4/2026 7:48:00 AM									
CV-2007	9/4/2026 7:48:00 AM									
CV-2007	9/25/2026 2:05:13 PM	-1.11	-1.15	2.5	1.3	0.018	0.005	-9.99	-10.10	28.45

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2007	9/28/2026 10:15:15 AM	-2.02	-2.02	10.2	8.6	0.071	0.050	-11.82	-11.84	28.44
CV-2007	9/30/2026 10:12:39 AM	-1.88	-1.23	3.5	2.5	0.036	0.018	-10.69	-10.76	28.47
CV-2007	9/30/2026 10:14:47 AM	-1.14	-1.13	1.4	1.0	0.006	0.003	-10.28	-10.29	28.47
CV-2008	9/3/2026 9:55:07 AM	-2.31	-2.08	0.0	0.0	0.001	0.000	-2.37	-2.39	28.52
CV-2008	9/25/2026 2:19:23 PM	-0.93	-0.79	0.8	0.4	0.177	0.032	-2.08	-2.06	28.45
CV-2009	9/10/2026 1:22:30 PM	-0.57	-0.59	19.0	18.8	0.484	0.478	-2.08	-2.08	28.49
CV-2009A	9/14/2026 1:25:59 PM	-2.50	-2.29	1.1	1.0	0.009	0.008	-3.95		28.4
CV-2009A	9/14/2026 1:27:41 PM	-2.24	-2.23	1.3	1.3	0.013	0.013	-4.00		28.4
CV-2009A	9/14/2026 2:27:00 PM									
CV-2009A	9/14/2026 2:28:48 PM	-2.86	-2.87	4.9	5.1	0.167	0.176	-4.87	-4.84	28.38
CV-2009A	9/21/2026 1:44:33 PM	-2.27	-2.25	7.5	7.4	0.381	0.366	-3.79	-3.85	28.49
CV-2009A	9/21/2026 1:45:00 PM									
CV-2010	9/22/2026 9:53:51 AM	-19.70	-19.69	1.4	1.8	0.002	0.004	-19.35		28.57
CV-2010A	9/22/2026 9:49:39 AM	-17.16	-17.09	34.1	31.5	3.092	2.638	-19.66		28.57
CV-2011	9/1/2026 10:17:28 AM	-8.44	-6.03	16.8	12.9	0.380	0.222	-14.70	-15.29	28.6
CV-2011A	9/2/2026 2:08:11 PM	-2.29	-2.31	60.1	66.6	1.000	1.231	-10.01	-11.58	28.6
CV-2011A	9/2/2026 2:10:00 PM									
CV-2011A	9/2/2026 2:10:00 PM									
CV-2011A	9/10/2026 9:14:08 AM	-3.35	-3.30	69.0	66.7	1.323	1.238	-11.35	-11.35	28.6
CV-2011A	9/10/2026 9:16:00 AM									
CV-2011A	9/11/2026 9:29:31 AM	-3.59	-3.60	80.0	84.5	1.789	1.996	-12.57	-12.51	28.53
CV-2011A	9/17/2026 10:27:00 AM									
CV-2011A	9/17/2026 10:27:38 AM	-5.86	-5.79	64.1	49.0	1.142	0.666	-16.72	-14.99	28.75
CV-2011A	9/24/2026 2:22:16 PM	-4.17	-4.11	56.2	55.5	0.880	0.859	-12.93	-14.08	28.52
CV-2011A	9/24/2026 2:25:00 PM									
CV-2012	9/28/2026 1:57:34 PM	-3.50	-1.50	6.7	2.8	0.061	0.010	-15.00	-15.00	28.37
CV-2201-PLR	9/3/2026 7:56:39 AM	-9.55	-9.45			9.617	9.531	-9.62	-9.48	28.6
CV-2201-PLR	9/3/2026 7:57:44 AM	-9.56	-9.45			9.608	9.531	-9.60	-9.48	28.6
CV-2201-PLR	9/21/2026 8:20:29 AM	-10.08	-10.03			10.048	10.052	-9.97	-9.99	28.63
CV-2201-PLR	9/21/2026 8:21:42 AM	-9.95	-9.95			9.940	10.045	-9.82	-10.07	28.63
CV-2204-PLR	9/8/2026 2:13:18 PM	-1.24	-0.98			1.312	1.006	0.28	0.27	28.6

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2204-PLR	9/8/2026 2:17:00 PM									
CV-2204-PLR	9/14/2026 10:19:07 AM	-3.03	-2.86			3.154	2.836	0.34	0.34	28.49
CV-2204-PLR	9/14/2026 10:26:00 AM									
CV-2204-PLR	9/21/2026 10:25:45 AM	-7.94	-7.82			8.385	8.256	0.29	0.32	28.58
CV-2204-PLR	9/21/2026 10:28:00 AM									
CV-2204-PLR	9/28/2026 10:21:59 AM	-6.85	-5.24			7.305	5.732	0.34	0.34	28.46
CV-2204-PLR	9/28/2026 10:25:00 AM									
CV-2205	9/22/2026 10:12:14 AM	3.39	3.37	0.0	10.1	-0.034	0.033	3.37		28.54
CV-2205	9/22/2026 10:43:00 AM	3.23	-0.12	0.0	28.3	-0.032	0.257	-21.52		28.53
CV-2205	9/22/2026 10:44:32 AM	-0.28	-0.15	18.6	19.3	0.115	0.123	-21.96		28.53
CV-2205	9/22/2026 1:55:00 PM									
CV-2207	9/3/2026 1:27:19 PM	-0.24	-0.28	7.1	5.4	0.013	0.008	-16.17	-15.48	28.47
CV-2208A	9/10/2026 9:58:00 AM									
CV-2208A	9/11/2026 6:08:06 PM	-4.10	-4.08	4.6	3.4	0.006	0.003	-8.18	-8.22	28.45
CV-2208A	9/14/2026 1:18:15 PM	-2.78	-2.78	18.1	19.4	0.091	0.105	-7.20	-7.24	28.46
CV-2208A	9/14/2026 1:19:00 PM									
CV-2208A	9/24/2026 2:05:00 PM									
CV-2208A	9/24/2026 2:07:36 PM	-2.76	-2.76	18.4	14.9	0.094	0.062	-6.59	-6.48	28.53
CV-2301	9/2/2026 9:11:34 AM	-9.44	-9.27			9.897	9.746	-11.32	-11.00	28.64
CV-2301	9/2/2026 9:13:00 AM									
CV-2301	9/2/2026 9:13:00 AM									
CV-2301	9/3/2026 6:40:00 AM									
CV-2301	9/3/2026 6:40:00 AM									
CV-2301	9/8/2026 9:59:02 AM	-6.41	-6.37	76.3	74.3	6.462	6.133			28.62
CV-2301	9/8/2026 10:00:00 AM									
CV-2301	9/16/2026 1:43:00 PM									
CV-2301	9/16/2026 1:46:53 PM	-5.55	-5.05			5.696	5.152	-5.80	-5.05	28.58
CV-2301	9/23/2026 1:27:45 PM	-6.56	-6.44			6.805	6.812	-6.92	-6.11	28.48
CV-2301	9/23/2026 1:31:00 PM									
CV-2301	9/30/2026 10:14:35 AM	-9.58	-8.80			10.143	9.533	-9.92	-8.63	28.49
CV-2301	9/30/2026 10:15:00 AM									
CV-2302	9/2/2026 8:56:46 AM	-12.16	-12.16			12.202	12.167	-12.30	-12.26	28.62
CV-2302	9/3/2026 6:45:00 AM									
CV-2302	9/3/2026 6:45:00 AM									
CV-2302	9/17/2026 10:41:57 AM	-11.03	-12.03			11.395	12.325	-11.61	-12.93	28.71
CV-2303	9/3/2026 6:50:00 AM									

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2303	9/3/2026 6:50:00 AM									
CV-2303	9/3/2026 7:49:00 AM									
CV-2303	9/3/2026 7:49:00 AM									
CV-2303	9/3/2026 7:52:16 AM	0.45				0.000		0.35		28.57
CV-2303	9/3/2026 7:53:05 AM	0.46	0.41			0.000	0.000	0.47	0.27	28.57
CV-2303	9/9/2026 8:46:47 AM	-0.25	-0.23			0.208	0.215	-0.58	-0.59	28.66
CV-2303	9/9/2026 8:50:00 AM									
CV-2303	9/15/2026 9:24:00 AM	0.43	0.44			0.000	0.000	0.46	0.50	28.57
CV-2303	9/15/2026 9:25:00 AM									
CV-2303	9/22/2026 9:19:07 AM	0.26	0.22			0.000	0.000	0.08	0.00	28.57
CV-2303	9/22/2026 9:21:00 AM									
CV-2304-PLR	9/3/2026 8:30:11 AM	-7.34	-7.39			7.956	8.023	-7.80	-7.94	28.59
CV-2304-PLR	9/3/2026 8:32:00 AM									
CV-2304-PLR	9/3/2026 8:32:00 AM									
CV-2304-PLR	9/9/2026 9:38:00 AM									
CV-2304-PLR	9/9/2026 9:42:30 AM	3.03	3.13			0.000	0.000	7.21	7.23	28.68
CV-2304-PLR	9/11/2026 2:24:49 PM	-4.86	-5.01			5.181	5.285	-5.13	-5.25	28.46
CV-2304-PLR	9/11/2026 2:25:38 PM	-4.98	-5.14			5.259	5.374	-5.23	-5.26	28.47
CV-2304-PLR	9/15/2026 10:21:48 AM	-5.23	-5.05			5.737	5.501	-5.45	-5.14	28.58
CV-2304-PLR	9/15/2026 10:22:00 AM									
CV-2304-PLR	9/22/2026 10:45:24 AM	-8.89	-8.72			0.440	0.527	-9.43	-9.16	28.57
CV-2304-PLR	9/22/2026 10:46:00 AM									
CV-2304-PLR	9/29/2026 9:11:59 AM	-10.65	-10.78			11.139	11.202	-10.92	-10.95	28.39
CV-2304-PLR	9/29/2026 9:20:00 AM									
CV-2305	9/1/2026 10:04:00 AM									
CV-2305	9/1/2026 10:04:00 AM									
CV-2305	9/1/2026 10:04:41 AM	-4.76	-4.73			0.335	0.246	-14.45	-14.72	28.58
CV-2305	9/9/2026 8:05:00 AM									
CV-2305	9/9/2026 8:05:00 AM									

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2305	9/9/2026 10:42:39 AM	-4.99	-3.44			0.000	0.000	-13.18	-13.79	28.66
CV-2305	9/9/2026 10:43:11 AM	-2.38	-2.34			0.025	0.040	-9.22	-9.31	28.64
CV-2305	9/9/2026 11:00:00 AM									
CV-2305	9/15/2026 2:00:00 PM									
CV-2305	9/15/2026 2:02:20 PM	0.86	-1.38			0.575	0.156	-4.09	-3.33	28.49
CV-2305	9/15/2026 2:04:55 PM	-1.56	-1.51			0.144	0.173	-3.41	-3.44	28.5
CV-2305	9/22/2026 2:28:38 PM	-5.10	-5.10			0.196	0.175	-8.03	-7.98	28.44
CV-2305	9/22/2026 2:31:00 PM									
CV-2305	9/29/2026 1:49:58 PM	-6.52	-6.61			0.576	0.465	-9.17	-9.18	28.29
CV-2305	9/30/2026 10:00:00 AM									
CV-2305	9/30/2026 10:01:12 AM	-8.45	-8.56			0.026	0.017	0.41	0.50	28.47
CV-2306-PLR	9/8/2026 1:31:32 PM	-5.62	-5.39			5.810	5.524	0.24	0.25	28.6
CV-2306-PLR	9/8/2026 1:32:00 PM									
CV-2306-PLR	9/14/2026 10:15:56 AM	-7.50	-7.08			7.932	7.460	0.34	0.34	28.49
CV-2306-PLR	9/14/2026 10:16:00 AM									
CV-2306-PLR	9/28/2026 10:16:32 AM	-10.16	-9.98			10.646	10.512	0.34	0.34	28.46
CV-2306-PLR	9/28/2026 10:20:00 AM									
CV-2308-PLR	9/3/2026 8:03:28 AM	-8.78	-8.90			8.964	9.016	-9.90	-9.82	28.6
CV-2308-PLR	9/21/2026 8:50:45 AM	-11.61	-11.63			11.543	11.534	-11.89	-12.19	28.63
CV-2310-PLR	9/3/2026 7:36:11 AM	-4.24	-3.15			4.503	3.049	0.04	0.04	28.53
CV-2310-PLR	9/3/2026 7:40:00 AM									
CV-2310-PLR	9/3/2026 7:40:00 AM									
CV-2310-PLR	9/9/2026 8:56:24 AM	-5.19	-5.05			4.685	5.478	0.08	0.08	28.67
CV-2310-PLR	9/9/2026 8:59:00 AM									
CV-2310-PLR	9/15/2026 9:36:20 AM	-6.34	-5.86			4.980	6.200	0.30	0.34	28.57
CV-2310-PLR	9/15/2026 9:38:00 AM									
CV-2310-PLR	9/22/2026 9:28:31 AM	-7.80	-7.58			8.368	8.181	0.34	0.34	28.57
CV-2310-PLR	9/22/2026 9:31:00 AM									
CV-2310-PLR	9/29/2026 8:57:01 AM	-11.12	-11.27			11.547	11.686	-11.25	-11.41	28.38
CV-2310-PLR	9/29/2026 9:00:00 AM									

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2311	9/8/2026 3:18:24 PM	-2.87	-2.90			2.912	3.027	-6.19	-6.44	28.6
CV-2311	9/8/2026 3:20:00 PM									
CV-2311	9/15/2026 8:20:03 AM	-3.86	-3.85			3.868	3.877	-9.09	-8.88	28.51
CV-2311	9/15/2026 8:21:00 AM									
CV-2311	9/21/2026 2:22:27 PM	-4.57				4.552		-8.15		28.5
CV-2311	9/21/2026 2:26:00 PM									
CV-2311	9/28/2026 3:16:00 PM									
CV-2311	9/28/2026 3:16:22 PM	-6.40	-6.40			6.567	6.567	-10.61	-10.69	28.35
CV-2312-PLR	9/2/2026 8:09:16 AM	-3.87	-3.44	36.1	34.0	3.896	3.450	-5.03	-5.16	28.6
CV-2312-PLR	9/3/2026 7:00:00 AM									
CV-2312-PLR	9/3/2026 7:00:00 AM									
CV-2312-PLR	9/9/2026 1:24:41 PM	-3.71	-3.72	35.4	33.4	3.747	3.340	0.01	0.00	28.63
CV-2312-PLR	9/9/2026 1:35:00 PM									
CV-2312-PLR	9/16/2026 10:30:00 AM									
CV-2312-PLR	9/16/2026 10:44:19 AM	-2.65	-2.15	29.4	27.0	2.568	2.167	-3.08	-2.32	28.6
CV-2312-PLR	9/23/2026 10:29:16 AM	-34.37	-34.04	98.5	98.6	33.361	33.361	-7.12	-8.04	28.49
CV-2312-PLR	9/23/2026 10:31:00 AM									
CV-2312-PLR	9/23/2026 1:10:56 PM	-4.53	-4.39	39.0	37.6	4.586	4.276	-5.21	-5.07	28.45
CV-2312-PLR	9/30/2026 9:44:29 AM	-9.62	-9.44	57.5	57.1	10.190	10.059	-8.33	-8.88	28.46
CV-2312-PLR	9/30/2026 9:50:00 AM									
CV-2314-PLR	9/1/2026 1:32:37 PM	-13.88	-13.98			14.092	14.231	-14.00	-14.19	28.54
CV-2314-PLR	9/1/2026 1:38:00 PM									
CV-2314-PLR	9/1/2026 1:38:00 PM									
CV-2314-PLR	9/4/2026 7:56:00 AM									
CV-2314-PLR	9/4/2026 7:56:00 AM									
CV-2314-PLR	9/9/2026 1:40:13 PM	-7.74	-7.41			7.812	7.556	-8.12	-7.75	28.57
CV-2314-PLR	9/9/2026 1:46:00 PM									
CV-2314-PLR	9/16/2026 9:36:00 AM									
CV-2314-PLR	9/16/2026 9:39:58 AM	-4.97	-5.18			5.213	5.421	-5.38	-5.78	28.6
CV-2314-PLR	9/23/2026 9:37:50 AM	-12.90	-12.87			13.379	13.383	-13.61	-13.85	28.49
CV-2314-PLR	9/23/2026 9:40:00 AM									
CV-2314-PLR	9/30/2026 8:54:14 AM	-11.15	-11.08			11.637	11.483	-11.77	-11.12	28.45

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2314-PLR	9/30/2026 9:00:00 AM									
CV-2315	9/3/2026 9:13:05 AM	-2.07	-2.39			2.064	2.464	-2.51	-3.24	28.56
CV-2315	9/3/2026 9:17:00 AM									
CV-2315	9/3/2026 9:17:00 AM									
CV-2315	9/4/2026 8:04:00 AM									
CV-2315	9/4/2026 8:04:00 AM									
CV-2315	9/8/2026 1:48:37 PM	-0.43	-0.46			0.385	0.438	-0.83	-1.09	28.59
CV-2315	9/8/2026 1:51:00 PM									
CV-2315	9/14/2026 10:40:35 AM	-1.77	-1.67			1.777	1.730	-2.12	-1.87	28.46
CV-2315	9/14/2026 10:44:00 AM									
CV-2315	9/21/2026 10:37:20 AM	-4.79	-4.52			4.776	4.390	-6.84	-6.11	28.57
CV-2315	9/21/2026 10:41:00 AM									
CV-2315	9/28/2026 10:36:48 AM	-5.20	-4.66			5.630	4.804	-6.34	-4.55	28.43
CV-2315	9/28/2026 10:40:00 AM									
CV-2316	9/2/2026 1:39:54 PM	-2.23	-2.22	57.5	57.7	2.233	2.244	-3.12	-3.13	28.57
CV-2316	9/2/2026 1:45:00 PM									
CV-2316	9/2/2026 1:45:00 PM									
CV-2316	9/3/2026 9:48:34 AM	-2.06	-2.06	55.1	55.2	2.049	2.061	-2.46	-2.44	28.51
CV-2316	9/10/2026 10:21:00 AM									
CV-2316	9/10/2026 10:23:35 AM	-1.32	-1.30	44.2	43.8	1.313	1.293	-1.96	-1.94	28.53
CV-2316	9/14/2026 1:56:00 PM									
CV-2316	9/14/2026 2:22:00 PM	-2.80	-2.77	63.3	63.2	2.732	2.717	-3.76	-3.87	28.38
CV-2316	9/21/2026 1:35:00 PM									
CV-2316	9/21/2026 1:37:31 PM	-2.16	-2.15	56.4	56.4	2.154	2.150	-2.87	-2.82	28.49
CV-2319	9/2/2026 1:50:00 PM									
CV-2319	9/2/2026 1:50:00 PM									
CV-2319	9/2/2026 1:58:16 PM	0.89	-1.49			0.000	0.000	-14.57	-14.77	28.55
CV-2319	9/2/2026 1:59:13 PM	-1.75	-1.77			0.000	0.000	-15.04	-14.86	28.53
CV-2319	9/9/2026 12:48:41 PM	-3.58	-3.20			0.000	0.000	-17.22	-17.26	28.62
CV-2319	9/9/2026 1:00:00 PM									
CV-2319	9/15/2026 2:22:47 PM	-2.48	-2.46			0.000	0.000	-19.67	-19.54	28.47
CV-2319	9/15/2026 2:25:00 PM									

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2319	9/22/2026 9:40:58 AM	-2.25	-1.72	153.3	145.2	6.697	5.998	-19.75	-22.01	28.5
CV-2319	9/22/2026 2:35:00 PM									
CV-2319	9/22/2026 2:40:31 PM	-0.08	-1.61			0.000	0.000	-14.14	-16.04	28.42
CV-2319	9/22/2026 2:41:24 PM	-1.84	-1.73			0.000	0.000	-16.53	-17.52	28.42
CV-2319	9/29/2026 1:53:56 PM	-3.83	-3.85			0.000	0.000	-19.96	-19.75	28.27
CV-2319	9/29/2026 2:00:00 PM									
CV-2321	9/1/2026 8:55:00 AM									
CV-2321	9/1/2026 8:55:00 AM									
CV-2321	9/1/2026 8:56:13 AM	-1.67	-1.70			0.031	0.027	-19.14	-19.16	28.56
CV-2321	9/9/2026 10:11:41 AM	-3.13	-3.14	6.5	6.5	0.121	0.120	-20.07	-19.89	28.64
CV-2321	9/9/2026 10:15:00 AM									
CV-2321	9/15/2026 1:25:04 PM	-3.20	-3.17			0.225	0.261	0.03	0.10	28.49
CV-2321	9/22/2026 9:56:29 AM	-2.09	-1.64	3.3	1.4	0.031	0.005	-12.42	-13.27	28.52
CV-2321	9/29/2026 1:15:00 PM									
CV-2321	9/29/2026 1:21:59 PM	-0.74	-4.54			0.049	0.412	-11.63	-11.09	28.31
CV-2321	9/29/2026 1:22:57 PM	-4.65	-4.67			0.471	0.549	-11.40	-11.26	28.31
CV-2322	9/1/2026 1:56:33 PM	-6.34	-6.23			6.496	6.467	-6.48	-6.40	28.54
CV-2322	9/1/2026 2:00:00 PM									
CV-2322	9/1/2026 2:00:00 PM									
CV-2322	9/10/2026 8:31:00 AM									
CV-2322	9/10/2026 8:31:01 AM	-6.33	-6.36			6.587	6.643	-7.12	-7.08	28.56
CV-2322	9/17/2026 12:50:31 PM	-9.21	-8.87			9.436	9.061	-9.22	-8.88	28.68
CV-2324	9/3/2026 1:08:01 PM	-0.56	-0.59	4.1	3.4	0.011	0.008	-19.76	-20.86	28.48
CV-2326	9/3/2026 9:35:00 AM									
CV-2326	9/3/2026 9:35:00 AM									
CV-2326	9/3/2026 9:35:50 AM	-3.31	-3.31			3.309	3.282	-6.91	-6.74	28.56
CV-2326	9/3/2026 1:14:03 PM	0.07	-0.25			0.000	0.000	-19.50	-21.41	28.48
CV-2326	9/8/2026 3:25:00 PM									
CV-2326	9/8/2026 3:25:03 PM	-3.06	-2.86			3.048	2.891	-6.19	-5.68	28.59
CV-2326	9/15/2026 8:24:00 AM									

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2326	9/15/2026 8:25:39 AM	-6.60	-6.40			6.779	6.703	-4.71	-4.51	28.51
CV-2326	9/21/2026 2:28:46 PM	-4.43	-4.30			4.322	4.325	-7.92	-7.68	28.5
CV-2326	9/21/2026 2:31:00 PM									
CV-2326	9/28/2026 3:18:43 PM	-6.40	-6.40			6.561	6.567	-10.74	-10.76	28.35
CV-2326	9/28/2026 3:20:00 PM									
CV-2327	9/14/2026 10:24:05 AM	-4.19	-4.18	0.0	0.0	4.219	3.901			28.48
CV-2327	9/14/2026 10:26:47 AM	-4.59	-4.64	0.0	0.0	4.668	4.640			28.48
CV-2327	9/14/2026 1:30:00 PM									
CV-2327	9/21/2026 8:50:00 AM									
CV-2327	9/21/2026 8:58:34 AM	-12.62	-3.39			12.776	3.372	-11.03	-11.00	28.58
CV-2327	9/21/2026 9:11:07 AM	-2.34	-2.20			2.369	2.228	-10.96	-10.84	28.58
CV-2327	9/30/2026 9:14:10 AM	-0.74	-0.68			0.741	0.671	-10.26	-10.19	28.49
CV-2328	9/1/2026 2:21:10 PM	-3.85	-3.75	18.4	20.1	0.839	1.008	-6.84	-6.53	28.57
CV-2328	9/1/2026 2:25:00 PM									
CV-2328	9/1/2026 2:25:00 PM									
CV-2328	9/9/2026 7:45:00 AM									
CV-2328	9/9/2026 7:45:00 AM									
CV-2328	9/9/2026 1:45:59 PM	-2.47	-2.38	8.5	10.8	0.166	0.274	-4.20	-5.00	28.65
CV-2328	9/24/2026 10:56:47 AM	-7.73	-7.05	11.5	22.7	0.036	0.141	-10.98	-10.99	28.6
CV-2328	9/24/2026 10:58:35 AM	-7.05	-7.05	32.5	36.5	0.289	0.365	-11.29	-11.38	28.63
CV-2328	9/28/2026 2:24:07 PM	-7.55	-7.56	18.2	10.5	0.091	0.030	-10.71	-10.79	28.41
CV-2328	9/30/2026 8:52:17 AM	-8.94	-8.94	10.3	11.3	0.267	0.319	-11.39	-11.57	28.47
CV-2328	9/30/2026 8:55:00 AM									
CV-2333	9/3/2026 7:45:00 AM									
CV-2333	9/3/2026 7:45:00 AM									
CV-2333	9/8/2026 9:30:41 AM	-5.48	-5.22			5.811	5.546	-6.11	-5.64	28.6
CV-2333	9/8/2026 9:35:00 AM									
CV-2333	9/14/2026 8:23:05 AM	-7.65	-7.58			7.717	7.592	-8.39	-8.17	28.46
CV-2333	9/14/2026 8:25:00 AM									
CV-2333	9/21/2026 8:18:24 AM	-5.73	-5.73			5.732	5.687	-8.80	-8.80	28.57
CV-2333	9/21/2026 8:21:00 AM									
CV-2333	9/28/2026 8:05:00 AM									

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2333	9/28/2026 8:08:07 AM	-9.52	-9.10			9.705	9.302	-10.44	-9.96	28.46
CV-2334	9/3/2026 7:50:00 AM									
CV-2334	9/3/2026 7:50:00 AM									
CV-2334	9/9/2026 12:10:26 PM	-1.32	-1.44	33.1	33.8	3.130	3.268	-3.07	-3.37	28.6
CV-2334	9/9/2026 12:10:43 PM	-1.49	-1.49	34.6	34.6	3.426	3.426	-3.70	-3.70	28.59
CV-2334	9/17/2026 12:59:56 PM	-3.43	-3.44	37.0	34.9	3.930	3.489	-7.57	-7.15	28.68
CV-2334	9/17/2026 1:03:00 PM									
CV-2334	9/24/2026 1:25:00 PM									
CV-2334	9/24/2026 1:44:17 PM	0.96	-0.98	33.7	43.8	3.285	5.601	-1.69	-5.78	28.51
CV-2334	9/24/2026 1:45:33 PM	-1.01	-1.00	44.3	44.6	5.726	5.802	-6.04	-5.96	28.49
CV-2335	9/14/2026 9:41:03 AM	-1.00	-0.99			0.992	0.982	-6.48	-6.37	28.46
CV-2335	9/16/2026 2:27:40 PM	-0.08	-0.19			0.029	0.149	-5.16	-5.12	28.56
CV-2336	9/14/2026 9:45:07 AM	-0.91	-0.91			0.896	0.896	-7.65	-7.67	28.48
CV-2336	9/16/2026 2:20:41 PM	-4.34	-4.64			4.165	4.568	-4.49	-4.84	28.56
CV-2337	9/8/2026 10:57:52 AM	-1.73	-1.72	0.0	0.0	-2.247	-2.057			28.63
CV-2337	9/8/2026 11:00:00 AM									
CV-2337	9/10/2026 9:00:00 AM									
CV-2337	9/10/2026 9:00:00 AM									
CV-2337	9/16/2026 2:13:00 PM									
CV-2337	9/16/2026 2:19:44 PM	-1.09	-1.06	24.2	24.2	1.684	1.683	-4.71	-4.59	28.6
CV-2337	9/23/2026 2:21:00 PM									
CV-2337	9/23/2026 2:21:55 PM	-7.37	-7.16	12.5	13.3	0.452	0.514	-8.13	-7.71	28.46
CV-2337	9/30/2026 2:15:00 PM									
CV-2337	9/30/2026 2:20:16 PM	-7.92	-7.71	13.9	11.2	0.555	0.363	-7.94	-7.82	28.42
CV-2338	9/8/2026 11:13:27 AM	-4.27	-4.27	0.0	0.0	4.366	4.503	-4.27		28.64
CV-2338	9/8/2026 11:15:00 AM									
CV-2338	9/16/2026 2:23:00 PM									
CV-2338	9/16/2026 2:28:52 PM	-4.88	-4.84			5.152	5.048	-5.16	-5.05	28.62
CV-2338	9/23/2026 2:29:15 PM	-5.71	-5.64			5.927	5.950	-6.00	-5.98	28.5
CV-2338	9/23/2026 2:34:00 PM									
CV-2338	9/30/2026 2:30:00 PM									

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2338	9/30/2026 2:35:34 PM	0.04	0.00			0.000	0.000	0.11	0.00	28.45
CV-2339	9/14/2026 2:04:24 PM	-7.16	-7.15	0.0	0.0	7.277	7.314	-7.01		28.48
CV-2339	9/14/2026 2:06:28 PM	-7.26	-7.21	0.0	0.0	7.194	6.962	-7.34		28.48
CV-2339	9/30/2026 3:45:57 PM	-9.43	-9.44			9.529	9.570	-9.99	-10.14	28.41
CV-2341	9/10/2026 8:29:15 AM	4.01	-1.90			0.000	1.877	-7.21	-8.26	28.67
CV-2341	9/10/2026 8:30:27 AM	-2.28	-2.26			2.225	2.241	-7.92	-8.08	28.69
CV-2341	9/10/2026 8:45:00 AM									
CV-2341	9/10/2026 8:45:00 AM									
CV-2341	9/24/2026 2:48:06 PM	-8.55	-8.44			8.685	8.598	-10.35	-10.46	28.49
CV-2342A-PL	9/1/2026 1:37:03 PM	-4.06	-4.19			4.043	4.112	-6.30	-6.11	28.69
CV-2342A-PL	9/8/2026 2:08:22 PM	-3.10	-2.97	0.0	0.0	3.125	3.039	-4.83		28.67
CV-2342A-PL	9/8/2026 2:17:58 PM	-2.48	-2.53	0.0	0.0	2.483	2.776	-4.98		28.67
CV-2342A-PL	9/8/2026 2:20:00 PM									
CV-2342A-PL	9/14/2026 1:57:27 PM	-4.77	-4.98			4.765	4.721	-4.65	-4.49	28.53
CV-2342A-PL	9/14/2026 2:10:00 PM									
CV-2342A-PL	9/24/2026 9:32:37 AM	-4.82	-4.80			5.134	4.798	-6.78	-6.63	28.63
CV-2342A-PL	9/24/2026 9:35:00 AM									
CV-2343-PLR	9/1/2026 1:05:42 PM	1.96	1.42			0.000	0.000	-1.59	-7.06	28.72
CV-2343-PLR	9/1/2026 1:25:00 PM									
CV-2343-PLR	9/1/2026 1:25:00 PM									
CV-2343-PLR	9/8/2026 1:57:49 PM	1.97	-0.39	0.0	0.0	-1.849	-1.210	-3.54		28.66
CV-2343-PLR	9/8/2026 1:59:45 PM	-1.53	-1.56	0.0	0.0	0.343	-2.141	-3.88		28.66
CV-2343-PLR	9/8/2026 2:00:00 PM									
CV-2343-PLR	9/14/2026 1:47:19 PM	-7.63	-7.39			7.618	7.619	0.00	0.00	28.53
CV-2343-PLR	9/14/2026 1:50:00 PM									
CV-2343-PLR	9/16/2026 12:27:21 PM	-5.72	-5.23			5.646	5.238	-5.81	-6.13	28.68
CV-2343-PLR	9/24/2026 9:22:03 AM	-7.55	-7.31			7.760	7.429	-8.55	-8.38	28.62
CV-2343-PLR	9/24/2026 9:25:00 AM									
CV-2344	9/1/2026 7:15:00 AM									

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2344	9/1/2026 12:55:13 PM	-3.39	-3.41			3.393	3.400	-9.48	-9.90	28.69
CV-2344	9/1/2026 7:15:00 PM									
CV-2344	9/8/2026 1:49:02 PM	-1.60	-1.56	0.0	0.0	1.465	1.461	-6.09		28.65
CV-2344	9/8/2026 1:50:00 PM									
CV-2344	9/8/2026 1:50:10 PM	-1.50	-1.50	0.0	0.0	1.530	1.532	-6.55		28.65
CV-2344	9/14/2026 10:26:52 AM	-5.64	-5.66			5.925	5.943	-8.18	-8.22	28.53
CV-2344	9/14/2026 10:32:00 AM									
CV-2344	9/24/2026 9:12:30 AM	-6.09	-6.07			6.259	6.219	-8.83	-8.46	28.6
CV-2344	9/24/2026 9:15:00 AM									
CV-2345	9/1/2026 7:10:00 AM									
CV-2345	9/1/2026 7:10:00 AM									
CV-2345	9/2/2026 7:32:38 AM	-3.62	-3.60	57.4	57.4	3.479	3.474			28.65
CV-2345	9/22/2026 11:32:10 AM	-3.85	-3.85	61.1	61.1	4.086	4.086			28.59
CV-2346	9/1/2026 7:05:00 AM									
CV-2346	9/1/2026 7:05:00 AM									
CV-2346	9/1/2026 10:35:00 AM									
CV-2346	9/1/2026 10:35:00 AM									
CV-2346	9/1/2026 10:36:56 AM	-7.84	-7.85			8.121	8.114	-9.55	-9.54	28.66
CV-2346	9/8/2026 2:30:00 PM									
CV-2346	9/8/2026 2:32:55 PM	-4.99	-4.97	0.0	0.0	4.541	4.631	-6.33		28.64
CV-2346	9/14/2026 10:07:15 AM	-6.55	-6.54			6.728	6.802	-8.47	-8.57	28.53
CV-2346	9/14/2026 10:09:25 AM	-7.13	-6.89			7.322	7.112	-9.06	-8.87	28.53
CV-2346	9/14/2026 10:10:00 AM									
CV-2346	9/24/2026 9:05:00 AM									
CV-2346	9/24/2026 9:07:33 AM	-6.30	-6.14			6.318	6.208	-8.17	-7.87	28.6
CV-2347	9/1/2026 6:55:00 AM									
CV-2347	9/1/2026 6:55:00 AM									
CV-2347	9/2/2026 7:17:45 AM	-3.87	-3.88	61.9	61.9	3.812	3.810			28.65
CV-2347	9/22/2026 12:05:58 PM	-3.52	-3.53	60.1	61.0	3.744	3.856			28.56
CV-2348	9/1/2026 6:50:00 AM									
CV-2348	9/1/2026 6:50:00 PM									
CV-2348	9/2/2026 7:12:27 AM	-9.05	-9.02	0.0	0.0	8.966	8.748	-9.01		28.64
CV-2348	9/2/2026 7:13:13 AM	-9.18	-9.11	0.0	0.0	9.160	8.743	-9.06		28.64
CV-2348	9/22/2026 12:12:09 PM	-8.62	-8.65	0.0	0.0	8.890	9.240	-8.66		28.55
CV-2348	9/22/2026 12:13:11 PM	-8.79	-8.76	0.0	0.0	8.916	8.643	-8.72		28.55

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2349	9/1/2026 2:05:00 AM									
CV-2349	9/1/2026 2:02:58 PM	-2.58	-2.59			2.679	2.440	-2.77	-2.61	28.69
CV-2349	9/1/2026 2:05:00 PM									
CV-2349	9/2/2026 7:50:00 AM									
CV-2349	9/2/2026 7:50:00 AM									
CV-2349	9/8/2026 1:35:00 PM									
CV-2349	9/8/2026 1:37:23 PM	2.35	1.83			-2.508	-1.933			28.68
CV-2349	9/8/2026 1:38:01 PM	1.50	1.56			-1.689	-1.730			28.68
CV-2349	9/17/2026 9:37:56 AM	1.36	0.12			0.000	0.000	-2.25	-2.20	28.79
CV-2349	9/17/2026 9:40:00 AM									
CV-2349	9/24/2026 9:55:30 AM	-1.34	-1.31			1.395	1.315	-3.83	-3.54	28.67
CV-2349	9/24/2026 10:05:00 AM									
CV-2350	9/1/2026 7:20:00 AM									
CV-2350	9/1/2026 7:20:00 AM									
CV-2350	9/2/2026 8:27:52 AM	-8.15	-7.24	0.0	0.0	8.283	5.953	-8.24		28.69
CV-2350	9/23/2026 9:06:15 AM	-11.21	-11.98			11.335	12.172	-11.31	-11.77	28.57
CV-2351	9/2/2026 7:15:00 AM									
CV-2351	9/2/2026 7:15:00 AM									
CV-2351	9/10/2026 12:26:23 PM	-4.07	-3.88			4.140	3.752	-4.02	-3.77	28.7
CV-2351	9/10/2026 12:27:25 PM	-3.76	-4.02			3.903	4.001	-3.55	-3.89	28.71
CV-2351	9/23/2026 9:53:22 AM	-7.22	-7.02			7.484	7.428	-7.15	-7.23	28.54
CV-2352	9/2/2026 7:20:00 AM									
CV-2352	9/2/2026 7:20:00 AM									
CV-2352	9/10/2026 11:57:24 AM	-3.85	-2.44			3.838	2.385	-3.76	-3.75	28.71
CV-2352	9/10/2026 11:59:11 AM	-2.47	-2.61			2.413	2.569	-3.99	-3.91	28.71
CV-2352	9/30/2026 3:26:31 PM	-2.82	-2.85			2.809	2.862	-6.73	-6.77	28.43
CV-2353-PLR	9/2/2026 7:54:07 AM	-5.78	-5.73	0.0	0.0	5.867	5.479	-5.68		28.67
CV-2353-PLR	9/10/2026 8:40:00 AM									
CV-2353-PLR	9/10/2026 8:40:00 AM									

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2353-PLR	9/30/2026 4:20:22 PM	-9.79	-9.79			9.905	9.995	-10.06	-10.06	28.44
CV-2354	9/2/2026 7:45:00 AM									
CV-2354	9/2/2026 7:45:00 AM									
CV-2354	9/2/2026 8:05:50 AM	5.27	4.47	0.0	0.0	-3.733	-4.968	0.88		28.71
CV-2354	9/2/2026 8:06:24 AM	2.07	4.58	0.0	0.0	-2.887	-4.318	3.97		28.71
CV-2354	9/8/2026 8:08:52 AM	1.40	-0.48			0.000	0.501	-2.15	-2.78	28.68
CV-2354	9/8/2026 8:10:05 AM	-0.13	-0.10			0.124	0.072	-2.27	-1.98	28.68
CV-2354	9/8/2026 9:08:00 AM									
CV-2354	9/17/2026 9:46:30 AM	-4.82	-4.72			4.787	5.170	-7.31	-7.37	28.82
CV-2354	9/17/2026 9:50:00 AM									
CV-2354	9/24/2026 9:34:17 AM	-9.36	-8.93			9.779	9.333	-12.07	-11.79	28.61
CV-2354	9/24/2026 9:47:15 AM	-10.53	-10.30			11.066	10.776	-10.57	-10.46	28.65
CV-2354	9/24/2026 9:50:00 AM									
CV-24001	9/10/2026 9:02:39 AM	-1.23	-2.04			1.209	2.004	-4.96	-4.87	28.67
CV-24001	9/16/2026 2:35:59 PM	-2.33	-2.30			2.277	2.246	-4.80	-4.92	28.56
CV-24002	9/10/2026 8:53:47 AM	-4.31	-3.21			4.240	3.148	-11.09	-11.06	28.64
CV-24002	9/16/2026 2:44:36 PM	-3.19	-3.18			3.147	3.155	-11.81	-11.83	28.54
CV-24003	9/14/2026 9:33:43 AM	-2.27	-2.27	2.6	2.4	0.018	0.016	-12.96	-12.87	28.45
CV-24003	9/16/2026 2:48:11 PM	-1.52	-1.53	2.8	2.9	0.021	0.022	-11.88	-11.78	28.54
CV-24004	9/1/2026 11:16:57 AM	-1.28	-1.28	3.5	3.6	0.034	0.034	-6.82	-6.77	28.68
CV-24004	9/16/2026 12:39:13 PM	-1.87	-1.83	7.4	6.5	0.147	0.114	-10.30	-10.45	28.69
CV-24006	9/1/2026 11:38:09 AM	-0.80	-0.63	4.7	0.2	0.062	0.000	-3.85	-3.75	28.67
CV-24006	9/1/2026 11:38:58 AM	-0.59	-0.62	2.1	4.9	0.012	0.066	-3.73	-3.75	28.67
CV-24006	9/16/2026 1:53:51 PM	-0.19	-0.20	2.0	4.7	0.011	0.059	-2.22	-2.25	28.55
CV-24007	9/1/2026 1:41:17 PM	-3.05	-2.88	55.8	51.8	9.035	7.765	-10.42	-10.68	28.52
CV-24007	9/3/2026 7:10:00 AM									
CV-24007	9/3/2026 7:10:00 AM									
CV-24007	9/8/2026 3:13:15 PM	-1.82	-1.79	53.3	53.3	8.481	8.463	-10.98	-10.93	28.58
CV-24007	9/8/2026 3:15:00 PM									
CV-24007	9/15/2026 8:10:00 AM									
CV-24007	9/15/2026 8:12:16 AM	-3.30	-3.30	58.9	58.9	10.079	10.079	-14.82	-14.82	28.49

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24007	9/29/2026 9:01:50 AM	-4.55	-2.04	62.2	6.5	11.360	0.122	-16.82	-16.67	28.4
CV-24007	9/29/2026 9:03:57 AM	-1.74	-1.75	6.6	7.0	0.126	0.141	-15.66	-15.57	28.41
CV-24007	9/29/2026 9:55:00 AM									
CV-24008	9/8/2026 3:07:24 PM	-6.14	-6.07	93.3	93.7	6.313	6.367	-6.55	-6.48	28.6
CV-24008	9/8/2026 3:09:00 PM									
CV-24008	9/14/2026 2:57:03 PM	-6.44	-6.36	96.2	94.6	6.776	6.544	-7.03	-6.59	28.41
CV-24008	9/14/2026 2:59:00 PM									
CV-24008	9/21/2026 2:19:31 PM	-7.68	-7.41	104.2	103.2	7.931	7.764	-8.61	-8.29	28.49
CV-24008	9/21/2026 2:20:00 PM									
CV-24008	9/28/2026 3:12:00 PM									
CV-24008	9/28/2026 3:12:04 PM	-10.11	-10.11	119.0	119.0	10.484	10.485	-11.13	-11.03	28.35
CV-24009	9/8/2026 3:00:41 PM	-3.36	-3.39			0.359	0.345	-7.12	-7.20	28.6
CV-24009	9/8/2026 3:03:00 PM									
CV-24009	9/14/2026 2:51:55 PM	-5.98	-5.73			0.423	0.403	-8.24	-7.75	28.4
CV-24009	9/14/2026 2:52:00 PM									
CV-24009	9/21/2026 2:14:38 PM	-5.39	-5.35			0.850	0.858	-9.49	-7.49	28.49
CV-24009	9/21/2026 2:15:00 PM									
CV-24009	9/28/2026 2:54:10 PM	-8.92	-8.78			0.386	0.320	-11.03	-10.72	28.34
CV-24009	9/28/2026 3:05:00 PM									
CV-24010	9/14/2026 1:20:33 PM	-1.05	-1.05			1.027	1.028	-5.64	-5.64	28.54
CV-24010	9/23/2026 1:13:43 PM	-0.15	-0.19			0.055	0.023	-4.79	-6.48	28.44
CV-24011	9/10/2026 1:14:00 PM									
CV-24011	9/10/2026 1:15:42 PM	-0.31	-0.33	33.8	35.1	3.493	3.769	-3.88	-4.04	28.52
CV-24011	9/15/2026 8:34:00 AM									
CV-24011	9/15/2026 8:38:24 AM	-2.89	-3.02	39.7	38.9	4.827	4.639	-7.68	-7.67	28.53
CV-24011	9/22/2026 8:35:45 AM	-3.14	-3.12	45.3	46.3	6.286	6.570	-9.47	-9.59	28.54
CV-24011	9/22/2026 8:37:00 AM									
CV-24011	9/29/2026 8:04:57 AM	-4.65	-4.58	45.1	43.5	6.286	5.838	-11.07	-10.81	28.37
CV-24011	9/29/2026 8:10:00 AM									

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24012	9/10/2026 1:34:00 PM									
CV-24012	9/10/2026 1:36:19 PM	-5.62	-5.05			5.690	5.179	-5.79	-5.39	28.5
CV-24012	9/15/2026 8:57:47 AM	-7.75	-7.79			8.063	8.231	-9.09	-8.86	28.56
CV-24012	9/15/2026 8:59:00 AM									
CV-24012	9/22/2026 8:52:16 AM	-6.37	-6.19			6.672	6.567	-10.64	-10.11	28.57
CV-24012	9/22/2026 8:55:00 AM									
CV-24012	9/29/2026 8:25:00 AM									
CV-24012	9/29/2026 8:26:34 AM	-11.42	-6.19			11.644	6.427	-12.29	-12.18	28.35
CV-24012	9/29/2026 8:27:45 AM	-6.40	-6.40			6.611	6.649	-12.46	-12.46	28.38
CV-24013	9/8/2026 2:55:00 PM									
CV-24013	9/8/2026 2:55:38 PM	-6.23	-6.23			6.420	6.308	-6.58	-6.61	28.6
CV-24013	9/14/2026 2:41:00 PM									
CV-24013	9/14/2026 2:45:29 PM	-7.96	-7.75			8.343	7.973	-8.64	-8.08	28.42
CV-24013	9/21/2026 2:06:00 PM									
CV-24013	9/21/2026 2:06:42 PM	-8.70	-8.42			9.025	8.562	-9.61	-8.46	28.5
CV-24013	9/22/2026 9:07:43 AM	-3.06	-2.86			3.067	2.894	0.34	0.34	28.56
CV-24013	9/28/2026 2:25:03 PM	-35.13	-3.31			33.379	3.271	-10.29	-10.08	28.36
CV-24013	9/28/2026 2:34:21 PM	-40.68	-0.05			33.379	0.000	-10.56	-10.82	28.37
CV-24013	9/28/2026 2:46:14 PM	-15.12	-13.82			15.439	14.005	-10.24	-10.36	28.35
CV-24013	9/28/2026 3:05:00 PM									
CV-24014	9/8/2026 10:27:00 AM									
CV-24014	9/8/2026 10:29:18 AM	-2.29	-2.33	27.3	27.6	2.266	2.315	-5.43	-5.36	28.61
CV-24014	9/14/2026 9:42:29 AM	-6.88	-6.74	48.4	48.3	7.294	7.256	-7.51	-7.66	28.49
CV-24014	9/14/2026 9:47:00 AM									
CV-24014	9/21/2026 9:59:00 AM									
CV-24014	9/21/2026 10:01:34 AM	-8.65	-8.64	54.0	54.0	9.101	9.111	-10.37	-9.98	28.57
CV-24014	9/28/2026 9:50:00 AM									

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24014	9/28/2026 9:51:51 AM	-9.77	-9.77	57.2	57.2	10.313	10.322	-10.78	-10.78	28.44
CV-24015	9/8/2026 10:15:00 AM									
CV-24015	9/8/2026 10:15:01 AM	-2.93	-3.23			2.900	3.181	0.28	0.27	28.6
CV-24015	9/14/2026 9:33:41 AM	-4.58	-4.09			4.549	4.078	-5.89	-4.95	28.49
CV-24015	9/14/2026 9:37:00 AM									
CV-24015	9/21/2026 9:43:08 AM	-4.91	-4.89			5.215	5.261	-8.80	-9.18	28.57
CV-24015	9/21/2026 9:47:00 AM									
CV-24015	9/28/2026 9:20:40 AM	-6.44	-6.23			6.745	6.522	-8.37	-8.13	28.45
CV-24015	9/28/2026 9:25:00 AM									
CV-24016	9/10/2026 1:20:58 PM	-3.95	-3.88			3.934	3.805	-4.36	-4.38	28.52
CV-24016	9/10/2026 1:23:00 PM									
CV-24016	9/15/2026 8:42:34 AM	-6.07	-6.07			6.351	6.413	-7.73	-7.79	28.54
CV-24016	9/15/2026 8:46:00 AM									
CV-24016	9/22/2026 8:41:38 AM	-5.23	-5.22			5.519	5.551	-7.64	-7.54	28.57
CV-24016	9/22/2026 8:43:00 AM									
CV-24016	9/29/2026 8:07:47 AM	-6.74	-6.74			6.681	6.674	-8.45	-8.44	28.38
CV-24016	9/29/2026 8:15:00 AM									
CV-24017	9/9/2026 7:35:00 AM									
CV-24017	9/9/2026 7:35:00 AM									
CV-24017	9/9/2026 8:19:35 AM	-5.05	-4.88			5.057	4.866	-9.71	-10.11	28.64
CV-24017	9/9/2026 8:21:00 AM									
CV-24017	9/15/2026 8:47:21 AM	-4.81	-4.72			5.101	5.134	-8.61	-8.46	28.54
CV-24017	9/15/2026 8:51:00 AM									
CV-24017	9/22/2026 8:31:00 AM									
CV-24017	9/22/2026 8:31:48 AM	-4.46	-4.45			4.461	4.444	-9.22	-10.19	28.54
CV-24017	9/29/2026 8:02:00 AM	-7.79	-7.85			7.846	7.797	-11.62	-11.55	28.38
CV-24017	9/29/2026 8:05:00 AM									
CV-24018	9/1/2026 1:52:46 PM	-1.67	-1.50			1.684	1.453	-6.71	-6.72	28.54
CV-24018	9/1/2026 1:53:33 PM	-1.50	-1.49			1.495	1.494	-6.76	-6.77	28.54

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24018	9/15/2026 9:11:09 AM	-1.70	-1.70			1.705	1.704	-8.30	-8.23	28.56
CV-24018	9/24/2026 8:57:40 AM	-2.33	-1.26			2.287	1.233	-8.98	-9.04	28.59
CV-24018	9/24/2026 8:58:59 AM	-1.16	-1.14			1.137	1.119	-8.83	-8.84	28.59
CV-24019	9/3/2026 7:27:00 AM									
CV-24019	9/3/2026 7:27:00 AM									
CV-24019	9/3/2026 7:27:22 AM	-3.33	-3.14			3.343	3.180	-8.54	-7.20	28.55
CV-24019	9/9/2026 8:36:17 AM	-2.18	-2.00			2.185	2.007	-8.76	-8.72	28.66
CV-24019	9/9/2026 8:39:00 AM									
CV-24019	9/15/2026 9:06:46 AM	-4.11	-4.05			4.100	3.985	-8.34	-8.25	28.55
CV-24019	9/15/2026 9:09:00 AM									
CV-24019	9/22/2026 9:08:00 AM									
CV-24019	9/24/2026 10:45:00 AM									
CV-24019	9/24/2026 10:45:17 AM	-1.71	-1.61			1.676	1.562	-9.80	-8.67	28.55
CV-24019	9/29/2026 8:43:49 AM	-5.22	-5.05			5.530	5.252	-11.14	-11.20	28.38
CV-24019	9/29/2026 8:45:00 AM									
CV-24020	9/3/2026 8:44:20 AM	-8.03	-8.07	10.4	10.4	0.278	0.277	-8.11	-8.13	28.63
CV-24020	9/3/2026 8:45:27 AM	-7.99	-8.10	10.3	9.6	0.274	0.237	-8.07	-8.13	28.63
CV-24020	9/21/2026 8:32:06 AM	-10.62	-10.96	10.5	10.7	0.282	0.290	-10.74	-10.92	28.63
CV-24020	9/21/2026 8:33:17 AM	-11.17	-11.29	10.4	10.6	0.273	0.288	-11.30	-11.30	28.63
CV-24021	9/3/2026 8:33:42 AM	-7.97	-4.67			8.039	4.584	-8.60	-8.37	28.61
CV-24021	9/3/2026 8:39:22 AM	-4.36	-4.34			4.290	4.272	-8.43	-8.13	28.63
CV-24021	9/3/2026 1:27:00 PM									
CV-24021	9/3/2026 1:27:00 PM									
CV-24021	9/10/2026 1:38:53 PM	-5.39	-5.35			5.501	5.347	-5.73	-5.54	28.51
CV-24021	9/21/2026 8:38:36 AM	-12.38	-12.37			12.527	12.516	-12.53	-12.53	28.63
CV-24021	9/21/2026 8:39:59 AM	-12.48	-12.22			12.529	12.234	-12.39	-12.19	28.63
CV-24022-PL	9/8/2026 10:34:00 AM									

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24022-PL	9/8/2026 10:34:57 AM	-4.96	-4.72			5.452	5.324	-5.44	-5.39	28.6
CV-24022-PL	9/14/2026 9:47:06 AM	-7.61	-7.62			8.044	8.057	-7.81	-7.75	28.47
CV-24022-PL	9/17/2026 1:14:16 PM	-7.84	-7.75			8.172	7.900	-8.44	-8.17	28.67
CV-24022-PL	9/17/2026 1:15:00 PM									
CV-24022-PL	9/21/2026 10:04:00 AM									
CV-24022-PL	9/21/2026 10:05:58 AM	-7.83	-7.83			8.299	8.354	-11.16	-10.99	28.59
CV-24022-PL	9/28/2026 9:56:17 AM	-10.34	-10.24			10.672	10.633	-10.44	-10.44	28.46
CV-24022-PL	9/28/2026 10:05:00 AM									
CV-24023	9/8/2026 10:21:52 AM	-3.13	-3.09			3.119	3.085	-4.91	-4.57	28.6
CV-24023	9/8/2026 10:23:00 AM									
CV-24023	9/14/2026 9:37:06 AM	-4.81	-4.69			4.802	4.685	-6.17	-6.23	28.48
CV-24023	9/14/2026 9:41:00 AM									
CV-24023	9/21/2026 9:52:32 AM	-6.44	-6.40			6.782	6.694	-9.27	-9.14	28.57
CV-24023	9/21/2026 9:53:00 AM									
CV-24023	9/28/2026 9:32:30 AM	-6.68	-6.49			0.000	0.000	0.27	0.33	28.46
CV-24023	9/28/2026 9:33:25 AM	-6.67	-6.57			7.023	6.991	-8.72	-8.74	28.46
CV-24023	9/28/2026 9:35:00 AM									
CV-24024-PL	9/14/2026 1:05:56 PM	-4.74	-4.80			4.661	4.715	-6.09	-6.43	28.56
CV-24024-PL	9/14/2026 1:07:36 PM	-4.86	-4.76			4.778	4.671	-6.34	-5.76	28.56
CV-24024-PL	9/14/2026 2:45:00 PM									
CV-24024-PL	9/21/2026 9:33:56 AM	-7.90	-7.96			8.269	8.317	-9.84	-9.73	28.6
CV-24025	9/3/2026 7:56:02 AM	-2.54	-2.53			2.519	2.515	-4.61	-4.61	28.57
CV-24025	9/3/2026 8:00:00 AM									
CV-24025	9/3/2026 8:00:00 AM									
CV-24025	9/9/2026 8:43:21 AM	-4.94	-4.82			4.910	4.770	-6.66	-6.57	28.65
CV-24025	9/9/2026 8:45:00 AM									

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24025	9/15/2026 9:18:02 AM	-2.46	-2.44			2.443	2.439	-4.28	-4.29	28.56
CV-24025	9/15/2026 9:19:00 AM									
CV-24025	9/22/2026 9:13:58 AM	-2.07	-2.06			2.048	2.040	-4.80	-4.80	28.57
CV-24025	9/22/2026 9:16:00 AM									
CV-24025	9/29/2026 8:49:38 AM	-3.24	-3.23			3.233	3.216	-5.86	-5.77	28.38
CV-24025	9/29/2026 8:50:00 AM									
CV-24026	9/3/2026 7:33:18 AM	-4.45	-4.26			4.462	4.245	-7.86	-8.41	28.55
CV-24026	9/3/2026 7:34:00 AM									
CV-24026	9/3/2026 7:34:00 AM									
CV-24026	9/9/2026 8:31:27 AM	-7.70	-7.41			7.976	7.565	-9.11	-8.67	28.67
CV-24026	9/21/2026 8:25:41 AM	-6.46	-6.26			6.380	6.273	-9.89	-9.39	28.63
CV-24026	9/21/2026 8:26:47 AM	-6.50	-6.59			6.543	6.706	-10.48	-9.99	28.63
CV-24026	9/28/2026 10:42:46 AM	-6.75	-6.71			7.171	7.224	-10.20	-10.97	28.48
CV-24026	9/29/2026 8:35:00 AM									
CV-24026	9/29/2026 8:35:11 AM	-6.89	-6.78			7.176	7.117	-10.67	-9.70	28.38
CV-24027	9/9/2026 11:08:00 AM	-5.49	-5.32			5.878	5.686	-4.38	-4.88	28.63
CV-24027	9/21/2026 8:45:43 AM	-11.08	-11.69			11.092	11.758	-10.88	-11.69	28.63
CV-24027	9/21/2026 8:46:35 AM	-12.34	-12.34			12.495	12.515	-12.53	-12.53	28.63
CV-24028	9/8/2026 10:39:56 AM	-5.33	-5.15			5.854	5.669	-6.04	-5.92	28.61
CV-24028	9/8/2026 10:45:00 AM									
CV-24028	9/14/2026 9:52:00 AM									
CV-24028	9/14/2026 9:59:11 AM	-7.35	-7.25			7.846	7.762	-7.65	-7.56	28.49
CV-24028	9/21/2026 10:10:45 AM	-9.53	-9.44			10.008	9.814	-11.81	-11.49	28.58
CV-24028	9/21/2026 10:13:00 AM									
CV-24028	9/28/2026 10:02:58 AM	-11.86	-11.67			12.315	12.259	-12.20	-12.15	28.46
CV-24028	9/28/2026 10:10:00 AM									

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24029	9/9/2026 10:30:51 AM	-4.99	-4.81			4.993	4.972	-4.29	-4.25	28.64
CV-24029	9/25/2026 10:15:36 AM	-9.79	-9.79			10.041	10.284	-9.70	-9.83	28.56
CV-24030	9/8/2026 9:51:00 AM									
CV-24030	9/8/2026 9:52:46 AM	-3.05	-2.53			2.946	2.561	-4.72	-4.76	28.64
CV-24030	9/14/2026 8:52:00 AM									
CV-24030	9/14/2026 9:02:11 AM	-4.98	-2.69			4.560	2.688	-6.90	-6.91	28.49
CV-24030	9/14/2026 9:08:34 AM	-3.04	-2.52			2.955	2.321	-6.54	-6.74	28.49
CV-24030	9/21/2026 9:12:52 AM	-3.34	-0.78			3.371	0.817	0.29	0.29	28.6
CV-24030	9/21/2026 9:15:00 AM									
CV-24030	9/21/2026 9:21:19 AM	-0.69	-0.63			0.620	0.590	0.29	0.29	28.58
CV-24030	9/28/2026 8:35:00 AM									
CV-24030	9/28/2026 8:36:53 AM	-3.34	-3.18			3.343	3.291	0.00	0.00	28.46
CV-24031	9/1/2026 2:26:16 PM	-4.34	-2.24			4.350	2.220	-6.31	-6.56	28.53
CV-24031	9/3/2026 8:12:54 AM	-2.54	-2.51			2.536	2.496	-8.72	-8.61	28.59
CV-24031	9/3/2026 8:17:00 AM									
CV-24031	9/3/2026 8:17:00 AM									
CV-24031	9/9/2026 9:07:06 AM	-1.55	-1.52			1.546	1.525	-6.00	-5.73	28.66
CV-24031	9/9/2026 9:10:00 AM									
CV-24031	9/15/2026 9:52:53 AM	-1.42	-1.36			1.416	1.353	-5.80	-5.54	28.57
CV-24031	9/15/2026 9:57:00 AM									
CV-24031	9/22/2026 9:40:37 AM	-2.46	-2.44			2.445	2.429	-9.89	-9.60	28.57
CV-24031	9/22/2026 9:44:00 AM									
CV-24031	9/29/2026 9:04:40 AM	-3.30	-3.30			3.294	3.287	-11.00	-11.16	28.38
CV-24031	9/29/2026 9:10:00 AM									

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24032	9/3/2026 7:35:00 AM									
CV-24032	9/3/2026 8:05:00 AM									
CV-24032	9/3/2026 8:05:26 AM	0.33	-0.88			0.000	0.887	-2.40	-1.56	28.57
CV-24032	9/3/2026 8:06:12 AM	-0.99	-0.83			0.984	0.867	-1.67	-1.18	28.59
CV-24032	9/9/2026 9:02:42 AM	-0.54	-0.41			0.533	0.345	-0.85	-0.59	28.68
CV-24032	9/9/2026 9:04:00 AM									
CV-24032	9/15/2026 9:43:54 AM	-0.26	-0.23			0.245	0.244	-0.33	-0.17	28.57
CV-24032	9/15/2026 9:47:00 AM									
CV-24032	9/22/2026 9:35:52 AM	-1.84	-1.72			1.812	1.745	-2.69	-2.36	28.57
CV-24032	9/22/2026 9:38:00 AM									
CV-24032	9/29/2026 9:01:56 AM	-4.72	-4.72			5.010	5.034	-5.96	-5.98	28.38
CV-24032	9/29/2026 9:05:00 AM									
CV-24033	9/3/2026 7:35:00 AM									
CV-24033	9/3/2026 7:35:00 AM									
CV-24033	9/3/2026 7:42:08 AM	-1.43	-1.33			1.458	1.345	-2.02	-1.75	28.57
CV-24033	9/9/2026 8:52:55 AM	-0.42	-0.43			0.419	0.436	-0.60	-0.82	28.68
CV-24033	9/9/2026 8:55:00 AM									
CV-24033	9/15/2026 9:28:55 AM	-0.65	-0.44			0.648	0.462	-0.74	-0.63	28.57
CV-24033	9/15/2026 9:32:00 AM									
CV-24033	9/22/2026 9:22:23 AM	-0.90	-0.86			0.902	0.896	-1.89	-1.35	28.57
CV-24033	9/22/2026 9:27:00 AM									
CV-24033	9/29/2026 8:53:18 AM	-6.02	-6.02			6.222	6.204	-6.53	-6.74	28.38
CV-24033	9/29/2026 8:55:00 AM									
CV-24034	9/8/2026 1:21:00 PM									
CV-24034	9/8/2026 1:24:32 PM	-4.06	-3.99			4.045	3.985	-5.81	-5.73	28.6
CV-24034	9/14/2026 10:06:34 AM	-4.72	-4.57			5.134	5.084	0.34	0.34	28.49

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24034	9/14/2026 10:09:00 AM									
CV-24034	9/21/2026 10:18:00 AM									
CV-24034	9/21/2026 10:19:16 AM	16.10	-3.01			0.000	3.004	-12.05	-11.67	28.6
CV-24034	9/21/2026 10:20:16 AM	-5.04	-4.72			5.353	5.052	-11.94	-11.24	28.6
CV-24034	9/28/2026 10:07:28 AM	-11.46	-11.46			12.017	12.063	-12.22	-12.34	28.46
CV-24034	9/28/2026 10:15:00 AM									
CV-24035-PL	9/8/2026 9:27:31 AM	-5.10	-5.05			5.409	5.406	-5.50	-5.56	28.59
CV-24035-PL	9/8/2026 9:29:00 AM									
CV-24035-PL	9/14/2026 8:17:00 AM									
CV-24035-PL	9/14/2026 8:17:07 AM	-6.81	-6.74			6.765	6.612	-8.33	-8.08	28.46
CV-24035-PL	9/21/2026 8:14:30 AM	-5.05	-5.05			5.098	5.170	-8.29	-8.21	28.57
CV-24035-PL	9/21/2026 8:15:00 AM									
CV-24035-PL	9/28/2026 7:53:30 AM	-8.36	-8.09			8.432	8.073	-9.41	-9.09	28.45
CV-24035-PL	9/28/2026 7:55:00 AM									
CV-24036	9/1/2026 2:33:35 PM	-6.51	-6.36			6.537	6.363	-6.78	-6.46	28.56
CV-24036	9/11/2026 2:07:19 PM	-5.72	-5.92	10.5	10.6	5.882	6.043	-5.94	-6.14	28.49
CV-24036	9/11/2026 2:08:24 PM	-5.96	-6.15	10.6	10.8	6.052	6.209	-6.15	-6.23	28.46
CV-24036	9/24/2026 11:11:10 AM	-10.75	-10.75			10.903	10.767	-10.71	-10.75	28.63
CV-24037	9/1/2026 3:35:53 PM	-4.12	-3.84			4.099	3.795	-5.70	-5.09	28.53
CV-24037	9/24/2026 11:22:54 AM	-10.75	-1.82			10.722	1.786	-11.39	-11.56	28.63
CV-24038	9/14/2026 11:13:08 AM	-5.43	-5.40	0.0	0.0	5.622	5.294	-5.99		28.5
CV-24038	9/14/2026 11:14:07 AM	-5.56	-5.56	0.0	0.0	5.630	5.737	-7.05		28.5
CV-24038	9/14/2026 2:15:00 PM									
CV-24038	9/21/2026 10:10:47 AM	-10.23	-10.51			10.502	10.708	-11.40	-11.68	28.62
CV-24038	9/21/2026 10:20:00 AM									
CV-24038	9/22/2026 10:40:33 AM	-7.83	-7.81			8.463	8.444	-9.33	-9.33	28.57
CV-24038	9/29/2026 9:21:20 AM	-8.79	-5.14			9.270	5.540	-10.66	-10.72	28.41
CV-24038	9/29/2026 9:30:00 AM									

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24039	9/3/2026 8:43:35 AM	-7.27	-7.23			7.978	7.875	-7.74	-7.42	28.57
CV-24039	9/3/2026 8:45:09 AM	-7.07	-7.10			7.735	7.764	-7.44	-7.41	28.6
CV-24039	9/29/2026 9:17:59 AM	-11.49	-11.49			11.520	11.500	-11.45	-11.40	28.43
CV-24039	9/29/2026 9:18:59 AM	-11.37	-11.29			11.469	11.483	-11.35	-11.41	28.41
CV-24040	9/3/2026 8:50:25 AM	-4.63	-4.60			4.619	4.595	-7.65	-7.75	28.57
CV-24040	9/3/2026 8:52:00 AM									
CV-24040	9/3/2026 8:52:00 AM									
CV-24040	9/9/2026 9:53:48 AM	-4.42	-4.38			4.342	4.906	-5.59	-6.61	28.68
CV-24040	9/9/2026 9:55:00 AM									
CV-24040	9/15/2026 10:32:00 AM									
CV-24040	9/15/2026 10:35:47 AM	-4.81	-2.70			5.365	2.686	-5.03	-5.49	28.57
CV-24040	9/15/2026 10:38:31 AM	-2.47	-2.47			2.459	2.459	-5.73	-5.73	28.57
CV-24040	9/21/2026 8:14:52 AM	-9.17	-9.28			9.106	9.190	-9.15	-9.19	28.62
CV-24040	9/21/2026 8:16:09 AM	-9.61	-9.61			9.563	9.522	-9.63	-9.82	28.62
CV-24041	9/9/2026 11:11:38 AM	-5.46	-5.36			5.883	5.707	-5.27	-5.05	28.64
CV-24041	9/23/2026 1:19:53 PM	-0.03	-0.02			0.000	0.000	-8.98	-9.04	28.45
CV-24042	9/8/2026 1:36:57 PM	-4.85	-4.69			4.853	4.807	-5.67	-5.47	28.59
CV-24042	9/8/2026 1:37:00 PM									
CV-24042	9/14/2026 10:23:07 AM	-6.87	-6.82			7.363	7.256	-7.54	-7.52	28.46
CV-24042	9/14/2026 10:27:00 AM									
CV-24042	9/21/2026 10:29:12 AM	-10.13	-9.77			10.579	10.322	-12.04	-11.83	28.57
CV-24042	9/21/2026 10:32:00 AM									
CV-24042	9/28/2026 10:28:10 AM	-11.16	-11.12			11.755	11.728	-12.13	-11.92	28.45
CV-24042	9/28/2026 10:30:00 AM									
CV-24043	9/14/2026 2:27:14 PM	-4.93	-4.91	70.8	70.8	4.777	4.779			28.45
CV-24043	9/30/2026 4:24:40 PM	-9.11	-9.09			9.065	9.061	-0.03	-0.11	28.37

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24044	9/3/2026 8:17:38 AM	-4.75	-4.67			4.746	4.665	-8.61	-8.46	28.57
CV-24044	9/3/2026 8:23:00 AM									
CV-24044	9/3/2026 8:23:00 AM									
CV-24044	9/9/2026 9:15:54 AM	-1.83	-1.82			1.831	1.825	-5.23	-5.24	28.67
CV-24044	9/9/2026 9:17:00 AM									
CV-24044	9/14/2026 9:52:00 AM									
CV-24044	9/15/2026 10:10:54 AM	-2.12	-2.07			2.113	2.065	-6.22	-5.81	28.57
CV-24044	9/15/2026 10:12:00 AM									
CV-24044	9/22/2026 9:50:00 AM									
CV-24044	9/22/2026 9:56:36 AM	-4.92	-4.91			4.907	4.887	-10.25	-10.11	28.6
CV-24044	9/29/2026 9:08:25 AM	-4.72	-4.72			5.152	5.134	-10.92	-11.12	28.38
CV-24044	9/29/2026 9:15:00 AM									
CV-24045	9/3/2026 8:23:14 AM	-7.74	-7.46			8.283	8.127	-8.36	-8.08	28.6
CV-24045	9/3/2026 8:27:00 AM									
CV-24045	9/3/2026 8:27:00 AM									
CV-24045	9/9/2026 9:26:00 AM									
CV-24045	9/9/2026 9:29:21 AM	-4.96	-4.88			5.422	4.847	-5.32	-4.82	28.68
CV-24045	9/15/2026 10:14:44 AM	-5.08	-4.75			5.475	5.262	-5.45	-5.15	28.6
CV-24045	9/15/2026 10:18:00 AM									
CV-24045	9/22/2026 10:34:00 AM									
CV-24045	9/22/2026 10:37:26 AM	-8.85	-8.55			9.415	9.315	-9.14	-9.09	28.6
CV-24045	9/29/2026 9:16:50 AM	-10.45	-4.85			10.878	5.322	-10.74	-10.70	28.39
CV-24045	9/29/2026 9:17:31 AM	-4.52	-4.50			4.496	4.483	-10.67	-10.69	28.4
CV-24045	9/29/2026 9:25:00 AM									
CV-24046	9/14/2026 10:32:13 AM	-1.47	-1.45	34.3	32.2	1.601	1.417			28.49
CV-24046	9/14/2026 10:32:44 AM	-1.56	-1.57	33.9	33.4	1.584	1.539			28.49
CV-24046	9/21/2026 9:20:00 AM									
CV-24046	9/21/2026 9:25:30 AM	-5.64	-1.53			5.922	1.526	-9.07	-9.26	28.6

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24046	9/21/2026 9:27:21 AM	-1.65	-1.86			1.625	1.774	-8.97	-10.71	28.59
CV-24046	9/22/2026 1:28:16 PM	-0.09	-3.04			0.092	3.002	-8.00	-7.29	28.49
CV-24046	9/22/2026 1:32:00 PM	-3.69	-3.62			3.615	3.545	-7.25	-8.38	28.49
CV-24046	9/29/2026 9:35:00 AM									
CV-24046	9/29/2026 9:38:38 AM	-1.30	-1.41			1.300	1.374	-4.40	-4.36	28.39
CV-24048	9/9/2026 11:14:18 AM	-4.71	-4.71			5.005	4.701	-5.16	-5.26	28.64
CV-24048	9/23/2026 1:23:23 PM	-7.49	-7.64			7.452	7.639	-9.06	-9.17	28.45
CV-24049	9/10/2026 9:20:00 AM									
CV-24049	9/10/2026 9:20:00 AM									
CV-24049	9/14/2026 9:39:50 AM	-5.97	-5.97	0.0	0.0	5.988	6.116			28.47
CV-24049	9/14/2026 9:40:16 AM	-5.71	-5.78	0.0	0.0	5.869	6.107			28.47
CV-24049	9/14/2026 10:45:00 AM									
CV-24049	9/21/2026 9:35:00 AM									
CV-24049	9/21/2026 9:40:32 AM	-10.06	-4.11			10.352	4.132	-11.45	-12.32	28.57
CV-24049	9/21/2026 9:41:36 AM	-5.33	-5.26			5.582	5.505	-12.14	-12.10	28.57
CV-24049	9/28/2026 2:11:38 PM	-4.47	-4.46			4.481	4.446	-10.12	-9.60	28.38
CV-24049	9/28/2026 2:40:00 PM									
CV-24050	9/14/2026 2:38:57 PM	-9.54	-10.14	0.0	0.0	9.939		-7.98		28.46
CV-24050	9/30/2026 2:26:44 PM	-7.97	-7.99			8.526	8.567	-8.08	-8.18	28.47
CV-24051	9/14/2026 11:02:47 AM	-5.99	-5.40	0.0	0.0	6.008	5.213	-7.05		28.51
CV-24051	9/24/2026 11:45:13 AM	-7.53	-6.38			7.614	6.383	-10.87	-10.67	28.61
CV-24052	9/14/2026 10:13:38 AM	-6.87	-6.42	0.0	0.0	6.941	6.696	-6.88		28.48
CV-24052	9/14/2026 10:14:40 AM	-6.25	-6.25	0.0	0.0	6.316	6.315	-6.79		28.48
CV-24052	9/23/2026 1:29:49 PM	-7.45	-5.33			7.386	5.347	-8.22	-7.48	28.41
CV-24053	9/8/2026 7:40:00 AM									
CV-24053	9/8/2026 7:40:00 AM									
CV-24053	9/14/2026 10:03:36 AM	-7.56	-6.96	0.0	0.0	7.718	7.271	-7.77		28.48
CV-24053	9/23/2026 1:26:37 PM	-8.20	-7.30			8.166	7.337	-8.53	-8.58	28.44
CV-24054	9/8/2026 1:44:40 PM	-5.79	-5.87			6.044	6.077	-6.33	-6.36	28.57
CV-24054	9/8/2026 1:48:00 PM									

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24054	9/14/2026 10:33:37 AM	-6.73	-6.53			7.178	7.039	-7.10	-6.86	28.47
CV-24054	9/14/2026 10:34:00 AM									
CV-24054	9/21/2026 10:34:28 AM	-11.12	-11.12			11.556	11.524	-12.59	-12.53	28.57
CV-24054	9/21/2026 10:37:00 AM									
CV-24054	9/28/2026 10:42:38 AM	-11.40	-11.37			11.810	11.764	-11.89	-11.71	28.43
CV-24054	9/28/2026 10:45:00 AM									
CV-24055	9/10/2026 9:25:00 AM									
CV-24055	9/10/2026 9:25:00 AM									
CV-24055	9/14/2026 9:36:06 AM	-0.89	-0.88	0.0	0.0	0.865	0.856	-8.62		28.45
CV-24055	9/30/2026 8:16:47 AM	-1.29	-1.28			1.262	1.253	-12.27	-12.26	28.44
CV-24055	9/30/2026 8:17:55 AM	-1.27	-1.27			1.249	1.244	-12.22	-12.23	28.44
CV-24055	9/30/2026 10:20:00 AM									
CV-24056	9/1/2026 9:14:34 AM	-0.51	-0.50	0.0	0.0	0.515	0.513			28.62
CV-24056	9/22/2026 11:03:33 AM	-4.96	-4.65	0.0	0.0	4.985	4.728			28.58
CV-24057	9/14/2026 2:15:25 PM	-1.89	-1.23			0.846	0.235	-8.14		28.46
CV-24057	9/14/2026 2:16:28 PM	-0.60	-0.56			0.291	0.279	-8.00		28.46
CV-24057	9/14/2026 3:00:00 PM									
CV-24057	9/17/2026 10:27:01 AM	-1.00	-1.02	15.2	8.0	0.656	0.184	-11.38	-11.52	28.71
CV-24057	9/21/2026 10:46:29 AM	-0.73	-2.26	13.2	19.5	0.494	1.091	-10.63	-9.67	28.62
CV-24057	9/21/2026 10:47:11 AM	-2.36	-2.33	19.5	19.2	1.097	1.067	-9.95	-9.83	28.62
CV-24057	9/21/2026 10:50:00 AM									
CV-24058	9/11/2026 1:53:52 PM	-3.59	-3.84			3.600	3.828	-4.48	-4.52	28.46
CV-24058	9/11/2026 1:55:09 PM	-4.14	-4.13			4.113	4.131	-4.77	-4.82	28.48
CV-24058	9/17/2026 10:38:59 AM	-6.99	-7.00			7.346	7.233	-8.18	-7.92	28.71
CV-24059	9/2/2026 9:05:00 AM									
CV-24059	9/2/2026 9:05:00 AM									
CV-24059	9/2/2026 9:06:09 AM	-0.83	-0.82	1.6	3.2	0.008	0.029	-11.63	-11.45	28.64
CV-24059	9/8/2026 9:49:40 AM	0.53	-1.15	0.0	0.0	-0.004	-0.005	-7.44		28.62
CV-24059	9/8/2026 9:50:00 AM									
CV-24059	9/8/2026 9:51:20 AM	-1.21	-1.23	7.7	7.6	0.213	0.210	-7.80		28.62
CV-24059	9/16/2026 1:37:00 PM									

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24059	9/16/2026 1:42:42 PM	-0.23	-0.19	4.8	5.6	0.068	0.092	-5.85	-6.57	28.6
CV-24059	9/23/2026 1:24:51 PM	-6.78	-6.78	12.1	12.3	0.434	0.447	-9.31	-8.72	28.49
CV-24059	9/23/2026 1:27:00 PM									
CV-24059	9/30/2026 10:05:00 AM									
CV-24059	9/30/2026 10:08:00 AM	-9.77	-9.56	12.5	12.5	0.460	0.462	-12.17	-11.79	28.49
CV-24060	9/2/2026 9:45:32 AM	-8.44	-7.09			8.655	7.417	-11.16	-11.15	28.63
CV-24060	9/17/2026 11:02:39 AM	-7.48	-7.48			7.977	8.015	-12.52	-11.76	28.71
CV-24061	9/2/2026 9:52:58 AM	-1.76	-1.75			1.754	1.745	-6.88	-6.57	28.63
CV-24061	9/28/2026 10:31:48 AM	-0.42	-0.48			0.145	0.454	-11.41	-11.41	28.45
CV-24062	9/1/2026 2:14:11 PM	-4.89	-4.89			5.086	5.016	-6.37	-6.36	28.57
CV-24062	9/1/2026 2:15:00 PM									
CV-24062	9/1/2026 2:15:00 PM									
CV-24062	9/3/2026 7:20:00 AM									
CV-24062	9/3/2026 7:20:00 AM									
CV-24062	9/10/2026 8:48:00 AM									
CV-24062	9/16/2026 10:09:38 AM	-3.86	-3.78			3.856	3.789	-4.72	-4.35	28.61
CV-24062	9/16/2026 10:13:00 AM									
CV-24062	9/23/2026 10:16:47 AM	-9.64	-9.56			10.182	10.141	-11.12	-10.95	28.53
CV-24062	9/23/2026 10:19:00 AM									
CV-24062	9/30/2026 9:17:26 AM	-9.06	-9.06			9.460	9.451	-10.40	-10.40	28.47
CV-24062	9/30/2026 9:20:00 AM									
CV-24063	9/1/2026 2:00:39 PM	-4.86	-4.53			4.965	4.651	-5.61	-4.76	28.54
CV-24063	9/1/2026 2:05:00 PM									
CV-24063	9/1/2026 2:05:00 PM									
CV-24063	9/3/2026 7:20:00 AM									
CV-24063	9/3/2026 7:20:00 AM									
CV-24063	9/10/2026 8:38:00 AM									
CV-24063	9/10/2026 8:38:14 AM	9.05	-3.06			0.000	3.043	-7.14	-6.92	28.57
CV-24063	9/10/2026 8:39:09 AM	-3.25	-3.27			3.225	3.293	-7.28	-6.82	28.57

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24063	9/14/2026 2:32:38 PM	-1.34	-1.21	42.7	43.0	2.665	2.701	-6.00	-5.79	28.47
CV-24063	9/15/2026 10:47:20 AM	-3.66	-3.66	52.6	52.5	4.063	4.044	-1.26	-1.29	28.58
CV-24063	9/17/2026 12:22:16 PM	-4.20	-4.22	41.6	39.6	2.042	1.851	-7.62	-7.33	28.71
CV-24063	9/17/2026 1:33:24 PM	-3.30	-3.27			3.310	3.292	-5.49	-5.43	28.68
CV-24063	9/17/2026 1:34:00 PM									
CV-24063	9/23/2026 10:11:45 AM	-6.71	-6.44			7.172	6.893	-8.53	-8.38	28.49
CV-24063	9/23/2026 10:13:00 AM									
CV-24063	9/30/2026 9:08:35 AM	-5.16	-5.14			5.651	5.518	-7.33	-6.65	28.46
CV-24063	9/30/2026 9:15:00 AM									
CV-24064-PL	9/1/2026 1:18:43 PM	-12.71	-12.97			12.964	13.211	-13.91	-13.92	28.58
CV-24064-PL	9/1/2026 1:25:00 PM									
CV-24064-PL	9/1/2026 1:25:00 PM									
CV-24064-PL	9/3/2026 7:30:00 AM									
CV-24064-PL	9/3/2026 7:30:00 AM									
CV-24064-PL	9/9/2026 1:28:11 PM	-6.37	-5.83			6.327	5.730	-8.01	-7.42	28.57
CV-24064-PL	9/9/2026 1:32:00 PM									
CV-24064-PL	9/10/2026 8:45:01 AM	-5.39	-5.10			5.649	5.605	-6.95	-6.99	28.57
CV-24064-PL	9/16/2026 9:05:32 AM	-3.71	-3.34			4.051	3.533	-5.05	-4.74	28.6
CV-24064-PL	9/16/2026 9:14:00 AM									
CV-24064-PL	9/23/2026 9:22:59 AM	-11.55	-11.46			12.007	11.810	-13.15	-13.07	28.49
CV-24064-PL	9/23/2026 9:25:00 AM									
CV-24064-PL	9/30/2026 8:25:00 AM									
CV-24064-PL	9/30/2026 8:38:49 AM	-9.75	-9.65			10.059	9.946	-11.62	-11.41	28.46
CV-24065-TP	9/3/2026 8:57:02 AM	-4.29	-3.61			4.241	3.596	-7.98	-7.97	28.52
CV-24065-TP	9/8/2026 7:50:00 AM									
CV-24065-TP	9/8/2026 7:50:00 AM									
CV-24065-TP	9/22/2026 10:39:59 AM	-5.40	-4.94			5.700	4.970	-11.02	-10.84	28.5
CV-24066	9/1/2026 9:11:21 AM	-1.60	-1.58	0.0	0.0	1.555	1.551	-10.61		28.62
CV-24066	9/10/2026 8:15:00 AM									
CV-24066	9/10/2026 8:15:00 AM									
CV-24066	9/22/2026 11:00:28 AM	-1.50	-1.52	0.0	0.0	1.549	1.454	-8.18		28.57
CV-24066	9/24/2026 2:36:50 PM	-1.48	-1.48			1.468	1.453	-10.40	-10.78	28.49

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24067	9/29/2026 2:12:24 PM	-6.00	-5.33	44.7	42.4	5.960	5.338	-9.73	-6.38	28.36
CV-24067	9/29/2026 2:14:48 PM	-5.16	-4.99	9.2	10.6	0.248	0.333	-6.71	-6.38	28.36
CV-24068	9/3/2026 10:45:39 AM	-3.79	-3.78			3.751	3.761	-6.45	-6.32	28.57
CV-24068	9/3/2026 10:47:00 AM									
CV-24068	9/3/2026 10:47:00 AM									
CV-24068	9/8/2026 10:05:00 AM									
CV-24068	9/8/2026 10:06:07 AM	-3.84	-3.89	0.0	0.0	3.901	4.108	-6.80		28.62
CV-24068	9/17/2026 1:41:53 PM	-5.74	-5.73			5.989	6.018	-9.18	-9.62	28.68
CV-24069	9/2/2026 8:53:53 AM	-1.22	-1.22			1.230	1.228	-11.78	-12.02	28.62
CV-24069	9/8/2026 7:00:00 AM									
CV-24069	9/8/2026 7:00:00 AM									
CV-24069	9/28/2026 10:46:59 AM	-1.48	-1.49			1.467	1.468	-11.19	-11.63	28.43
CV-24070	9/2/2026 8:55:00 AM									
CV-24070	9/2/2026 8:55:00 AM									
CV-24070	9/2/2026 8:55:24 AM	-2.30	-2.33	22.8	22.9	3.524	3.536	-12.57	-12.82	28.64
CV-24070	9/8/2026 7:10:00 AM									
CV-24070	9/8/2026 7:10:00 AM									
CV-24070	9/9/2026 1:57:00 PM	0.69	-0.97	9.3	11.2	1.837	2.652	-4.35	-3.49	28.65
CV-24070	9/9/2026 1:57:46 PM	-1.05	-1.04	11.0	11.5	2.549	2.817	-3.46	-3.84	28.66
CV-24070	9/10/2026 1:57:00 PM									
CV-24070	9/10/2026 1:59:57 PM	-2.40	-2.47	24.5	25.7	4.084	4.495	-6.30	-6.78	28.49
CV-24070	9/16/2026 1:23:00 PM									
CV-24070	9/16/2026 1:30:24 PM	-3.79	-4.01	19.2	18.8	2.470	2.384	-6.79	-6.88	28.57
CV-24071	9/2/2026 9:40:06 AM	-0.53	-0.72	12.1	13.5	0.955	1.201	-5.87	-7.02	28.62
CV-24071	9/8/2026 7:15:00 AM									
CV-24071	9/8/2026 7:15:00 AM									
CV-24071	9/17/2026 2:19:48 PM	-3.15	-1.97	13.6	9.6	1.214	0.605	-9.94	-9.61	28.64
CV-24072	9/2/2026 1:30:58 PM	-4.26	-3.50			4.283	3.491	-6.15	-6.00	28.58
CV-24072	9/17/2026 2:25:11 PM	-0.27	-0.21			0.215	0.241	-9.18	-9.54	28.63
CV-24073-TP	9/1/2026 2:25:19 PM	-1.98	-1.94			1.966	1.931	-5.96	-5.94	28.55

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24073-TP	9/1/2026 2:30:00 PM									
CV-24073-TP	9/1/2026 2:30:00 PM									
CV-24073-TP	9/9/2026 1:21:38 PM	-2.02	-2.07			2.020	2.059	-5.22	-5.48	28.64
CV-24073-TP	9/21/2026 2:25:32 PM	-3.71	-3.70			3.712	3.722	-7.66	-7.45	28.48
CV-24073-TP	9/30/2026 9:00:28 AM	-6.11	-4.75			6.408	4.737	-10.46	-10.59	28.47
CV-24073-TP	9/30/2026 9:01:24 AM	-4.46	-4.42			4.458	4.476	-10.37	-10.37	28.47
CV-24073-TP	9/30/2026 9:05:00 AM									
CV-24074	9/2/2026 2:20:20 PM	-1.01	-0.91			1.036	0.973	-5.43	-5.70	28.55
CV-24074	9/21/2026 2:20:48 PM	-1.49	-1.42			1.529	1.398	-7.05	-7.20	28.48
CV-24075-TP	9/1/2026 1:27:41 PM	-10.56	-10.32			10.739	10.621	-13.20	-13.05	28.57
CV-24075-TP	9/1/2026 1:34:00 PM									
CV-24075-TP	9/1/2026 1:34:00 PM									
CV-24075-TP	9/9/2026 1:36:18 PM	-6.76	-6.40			6.858	6.349	-7.49	-7.66	28.57
CV-24075-TP	9/9/2026 1:41:00 PM									
CV-24075-TP	9/16/2026 9:26:05 AM	-4.13	-4.11			4.123	4.088	-4.48	-4.36	28.6
CV-24075-TP	9/16/2026 9:28:00 AM									
CV-24075-TP	9/23/2026 9:31:50 AM	-11.74	-11.50			12.167	12.018	-12.52	-12.46	28.49
CV-24075-TP	9/23/2026 9:35:00 AM									
CV-24075-TP	9/30/2026 8:50:15 AM	-10.45	-10.45			10.819	10.830	-11.24	-11.20	28.46
CV-24075-TP	9/30/2026 8:55:00 AM									
CV-24076	9/1/2026 1:45:00 PM									
CV-24076	9/1/2026 1:45:00 PM									
CV-24076	9/1/2026 1:45:11 PM	-4.21	-4.15			4.188	4.143	0.05	0.00	28.53
CV-24076	9/1/2026 1:49:10 PM	-4.17	-4.11			4.148	4.169	-5.94	-6.32	28.53
CV-24076	9/9/2026 1:57:00 PM									
CV-24076	9/9/2026 1:58:23 PM	-3.85	-3.62			3.902	3.634	-5.63	-4.76	28.55
CV-24076	9/16/2026 9:59:57 AM	-4.41	-4.41			4.357	4.393	-6.32	-6.27	28.6
CV-24076	9/16/2026 10:02:00 AM									
CV-24076	9/23/2026 9:57:00 AM	-7.83	-7.75			8.341	8.240	-11.19	-10.93	28.49
CV-24076	9/30/2026 9:00:43 AM	-7.51	-7.51			7.974	7.974	-10.38	-10.38	28.46

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24076	9/30/2026 9:05:00 AM									
CV-24077	9/1/2026 9:39:47 AM	-3.28	-3.34	0.0	0.0	3.410	3.507	-9.94		28.61
CV-24077	9/1/2026 11:02:58 AM	-3.57	-3.57	0.0	0.0	3.474	3.475	-9.56		28.62
CV-24077	9/1/2026 2:25:00 PM									
CV-24077	9/1/2026 2:25:00 PM									
CV-24077	9/1/2026 2:29:54 PM	-3.11	-3.11			3.108	3.115	-8.98	-9.03	28.62
CV-24077	9/8/2026 10:33:07 AM	-1.79	-1.81	0.0	0.0	1.995	1.989	-6.89		28.63
CV-24077	9/8/2026 10:35:00 AM									
CV-24077	9/14/2026 9:40:00 AM									
CV-24077	9/14/2026 9:41:46 AM	-3.28	-3.34			3.289	3.350	-9.05	-8.95	28.53
CV-24077	9/14/2026 10:22:00 AM	-3.03	-2.95			3.054	2.956	-8.15	-7.84	28.5
CV-24077	9/22/2026 12:59:33 PM	-3.37	-3.38	0.0	0.0	2.879	2.881	-9.16		28.51
CV-24077	9/22/2026 1:00:24 PM	-3.33	-3.33	0.0	0.0	2.874	2.669	-9.46		28.51
CV-24077	9/23/2026 1:52:00 PM									
CV-24077	9/23/2026 1:52:12 PM	-3.53	-3.53			3.526	3.516	-9.09	-8.99	28.49
CV-24077	9/30/2026 1:55:00 PM									
CV-24077	9/30/2026 1:57:09 PM	-3.20	-3.15			3.202	3.182	-8.76	-8.76	28.42
CV-24078	9/1/2026 11:05:35 AM	-0.74	-0.75	5.8	7.0	0.010	0.015	-10.34		28.62
CV-24078	9/22/2026 10:57:51 AM	-0.86	-0.88	13.8	12.7	0.056	0.048	-9.68		28.58
CV-24079-TP	9/1/2026 10:56:25 AM	-0.50	-0.48	0.0	0.0	0.424	0.414	-7.39		28.42
CV-24079-TP	9/21/2026 11:00:53 AM	-2.37	-1.20			2.320	1.175	-9.45	-9.04	28.64
CV-24079-TP	9/21/2026 11:03:19 AM	-1.08	-1.10			1.052	1.058	-9.31	-8.46	28.65
CV-24079-TP	9/28/2026 10:34:01 AM	-1.73	-1.75			1.730	1.746	-7.68	-7.54	28.48
CV-24079-TP	9/30/2026 9:15:00 AM									
CV-24079-TP	9/30/2026 9:17:09 AM	-2.12	-2.11			2.114	2.108	-7.41	-7.64	28.47
CV-24080	9/1/2026 10:50:48 AM	-0.68	-0.68	1.5	3.0	0.002	0.007	-8.27		28.6
CV-24080	9/9/2026 2:19:31 PM	-1.81	-1.83	16.1	22.7	0.176	0.350	-6.17		28.57
CV-24080	9/17/2026 10:09:09 AM	-1.96	-1.93	4.6	4.3	0.058	0.050	-8.86	-7.96	28.7
CV-24081-TP	9/2/2026 9:06:17 AM	-0.13	-0.12			0.133	0.124	-11.78	-11.78	28.6
CV-24081-TP	9/17/2026 1:48:26 PM	-1.10	-1.07			1.085	1.056	-9.84	-9.32	28.64
CV-24082	9/2/2026 9:30:43 AM	-6.42	-5.74			6.708	5.972	-11.09	-11.49	28.6
CV-24082	9/17/2026 1:53:48 PM	-4.92	-3.79			4.127	3.805	-7.84	-10.15	28.63

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24083	9/2/2026 8:49:34 AM	-2.59	-2.56			2.569	2.570	-2.84	-2.54	28.64
CV-24083	9/2/2026 8:50:00 AM									
CV-24083	9/2/2026 8:50:00 AM									
CV-24083	9/8/2026 10:18:45 AM	-0.46	-0.44	0.0	0.0	0.777	0.385	-0.93		28.6
CV-24083	9/8/2026 10:20:00 AM									
CV-24083	9/17/2026 1:55:13 PM	-2.29	-2.23			2.342	2.194	-2.38	-2.11	28.68
CV-24083	9/17/2026 1:57:00 PM									
CV-24083	9/23/2026 1:21:00 PM									
CV-24083	9/23/2026 1:23:41 PM	-7.12	-7.08			7.426	7.329	-7.78	-7.71	28.47
CV-24083	9/30/2026 10:01:53 AM	-9.44	-9.38			10.011	9.957	-10.21	-10.04	28.48
CV-24084-TP	9/2/2026 8:41:51 AM	-7.28	-6.82			7.533	7.166	-10.91	-10.78	28.64
CV-24084-TP	9/2/2026 8:45:00 AM									
CV-24084-TP	9/2/2026 8:45:00 AM									
CV-24084-TP	9/8/2026 10:20:41 AM	-4.28	-3.40	54.1	47.2	4.085	3.135			28.6
CV-24084-TP	9/8/2026 10:25:00 AM									
CV-24084-TP	9/17/2026 1:59:08 PM	-5.27	-4.79			5.550	4.942	-8.14	-8.54	28.68
CV-24084-TP	9/17/2026 2:02:00 PM									
CV-24084-TP	9/23/2026 1:13:00 PM									
CV-24084-TP	9/23/2026 1:16:20 PM	-4.81	-4.46			4.962	4.431	-8.14	-7.81	28.46
CV-24084-TP	9/30/2026 9:55:00 AM									
CV-24084-TP	9/30/2026 9:57:04 AM	-8.02	-7.08			8.553	7.438	-11.32	-11.16	28.47
CV-24085	9/1/2026 11:10:02 AM	0.23	0.23	0.0	0.0	0.028	0.025	0.23		28.6
CV-24085	9/1/2026 11:10:35 AM	0.25	0.26	0.0	0.0	0.012	0.013	0.26		28.6
CV-24085	9/9/2026 2:14:51 PM	-0.83	-0.49	0.0	0.0	0.898	-0.099	-0.46		28.57
CV-24085	9/9/2026 2:15:24 PM	-0.51	-0.49	0.0	0.0	-0.085	-0.088	-0.48		28.57
CV-24085	9/18/2026 4:38:39 PM	-1.87	-1.66	18.4	15.6	0.938	0.678	0.66	0.67	28.6
CV-24086	9/1/2026 10:18:55 AM	-1.13	-1.18	49.5	15.5	1.602	0.156	-6.68		28.6
CV-24086	9/17/2026 9:56:01 AM	-1.94	-1.93	13.5	12.7	0.499	0.447	-12.53	-11.71	28.7
CV-24087	9/14/2026 1:57:58 PM	-0.38	-0.38	12.3	12.3	0.413	0.414	-8.47	-8.54	28.37
CV-24087	9/21/2026 9:41:26 AM	-2.49	-2.48	54.1	53.0	8.160	7.810	-9.17	-8.83	28.55
CV-24088	9/2/2026 1:21:22 PM	-2.03	-2.03			2.016	2.010	-9.24	-9.32	28.55

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24088	9/17/2026 3:03:53 PM	-2.43	-2.40			2.432	2.397	-9.18	-8.51	28.6
CV-24089	9/1/2026 2:52:55 PM	-0.48	-0.47	15.4	15.4	0.660	0.661	-5.54		28.56
CV-24089	9/22/2026 2:06:04 PM	-0.81	-0.80	16.4	11.3	0.746	0.357	-9.71	-9.16	28.45
CV-24090	9/3/2026 12:03:50 PM	-0.49	-0.65			0.451	0.626	-8.20	-8.07	28.54
CV-24090	9/14/2026 1:45:37 PM	-1.27	-1.20			1.117	1.083	-9.70	-9.11	28.37
CV-24090	9/21/2026 9:16:50 AM	-1.47	-1.45			1.463	1.451	-11.13	-10.56	28.55
CV-24091	9/14/2026 1:37:49 PM	-6.38	-6.53	18.7	17.0	0.956	0.793	-10.71	-10.07	28.37
CV-24091	9/21/2026 8:59:41 AM	-10.84	-10.82	6.3	1.5	0.107	0.006	-11.24	-10.81	28.53
CV-24092	9/14/2026 1:27:47 PM	-3.65	-3.64	36.0	36.0	3.592	3.588	-9.53	-9.92	28.36
CV-24092	9/24/2026 2:16:45 PM	-3.25	-3.26	34.2	34.4	3.234	3.260	-9.51	-9.58	28.44
CV-24093	9/13/2026 9:56:20 AM	-0.94	-0.94	1.5	1.8	0.005	0.008	-24.54	-24.33	28.47
CV-24093	9/13/2026 9:58:10 AM	-0.95	-0.96	0.0	2.2	0.000	0.011	-24.77	-24.77	28.47
CV-24093	9/28/2026 10:16:44 AM	-0.33	-0.34	2.9	2.6	0.019	0.015	0.40	0.38	28.41
CV-24094	9/14/2026 1:07:34 PM	-1.38	-1.37	0.3	0.3	0.009	0.009	-18.24		28.42
CV-24094	9/22/2026 10:05:46 AM	-0.62	-0.60	0.6	0.7	0.033	0.047	-11.58	-12.14	28.52
CV-24095	9/1/2026 1:57:31 PM	-2.41	-2.42			2.420	2.413	-4.32	-4.44	28.72
CV-24095	9/1/2026 2:00:00 PM									
CV-24095	9/1/2026 2:00:00 PM									
CV-24095	9/8/2026 1:30:00 PM									
CV-24095	9/8/2026 1:31:41 PM	-1.91	-1.95	0.0	0.0	2.020	2.117	-1.96		28.69
CV-24095	9/10/2026 8:30:00 AM									
CV-24095	9/10/2026 8:30:00 AM									
CV-24095	9/17/2026 9:42:47 AM	-5.15	-5.10			5.492	5.527	-8.35	-8.27	28.82
CV-24095	9/17/2026 9:47:00 AM									
CV-24095	9/24/2026 9:52:08 AM	-7.41	-7.41			7.955	7.873	-10.74	-9.89	28.65
CV-24095	9/24/2026 10:00:00 AM									
CV-24096	9/2/2026 8:14:01 AM	-2.39	-2.37	0.0	0.0	2.265	2.262	-2.31		28.71
CV-24096	9/23/2026 9:26:01 AM	-5.61	-5.44			5.875	5.718	-5.65	-5.53	28.6
CV-24097	9/2/2026 8:18:03 AM	-3.21	-3.23	0.0	0.0	3.215	2.977	-3.40		28.71
CV-24097	9/30/2026 3:17:38 PM	2.75	0.67			0.000	0.000	2.87	0.52	28.45

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24098	9/2/2026 8:23:38 AM	-7.95	-7.38	0.0	0.0	7.929	7.186	-7.23		28.71
CV-24098	9/23/2026 9:16:20 AM	-11.66	-11.49			11.813	11.712	-11.54	-11.43	28.61
CV-24099	9/2/2026 8:32:12 AM	-7.76	-7.91	0.0	0.0	7.545	7.790	-7.47		28.71
CV-24099	9/23/2026 9:11:30 AM	-11.20	-11.53			11.426	11.646	-11.24	-11.48	28.6
CV-24099	9/23/2026 9:13:00 AM	-10.68	-11.35			10.871	11.546	-10.75	-11.23	28.6
CV-24100	9/2/2026 8:50:27 AM	-8.85	-8.87	0.0	0.0	9.048	8.889	-8.71		28.7
CV-24100	9/2/2026 1:05:00 PM									
CV-24100	9/2/2026 1:05:00 PM									
CV-24100	9/2/2026 1:12:10 PM	0.52	-2.38			0.000	2.370	-8.44	-8.79	28.72
CV-24100	9/2/2026 1:16:31 PM	-2.41	-2.42			2.415	2.424	-8.81	-8.42	28.71
CV-24100	9/8/2026 7:35:00 AM									
CV-24100	9/8/2026 7:35:00 AM									
CV-24100	9/8/2026 2:53:01 PM	-1.51	-1.48	0.0	0.0	1.379	1.382	-6.92		28.7
CV-24100	9/8/2026 2:55:00 PM									
CV-24100	9/17/2026 2:15:00 PM									
CV-24100	9/17/2026 2:19:56 PM	-8.62	-8.47			8.916	8.943	-9.23	-10.86	28.75
CV-24100	9/17/2026 2:21:00 PM	-9.31	-8.93			9.615	9.179	-10.66	-9.18	28.75
CV-24100	9/24/2026 10:19:50 AM	-12.64	-12.13			13.209	12.517	-13.84	-13.18	28.65
CV-24100	9/24/2026 10:25:00 AM									
CV-24100	9/28/2026 1:58:23 PM	-12.00	-5.25			11.958	5.155	-12.19	-11.26	28.53
CV-24101	9/8/2026 7:30:00 AM									
CV-24101	9/8/2026 7:30:00 AM									
CV-24101	9/28/2026 1:59:13 PM	-6.06	-5.97			5.981	5.915	-11.97	-13.02	28.52
CV-24102	9/2/2026 9:21:46 AM	-2.00	-1.95	0.0	0.0	1.759	1.755	-13.37		28.68
CV-24102	9/22/2026 12:22:15 PM	-0.44	-0.40	0.0	0.0	0.832	0.573	-9.07		28.58
CV-24103	9/1/2026 11:30:43 AM	-0.69	-0.68	5.7	5.7	0.676	0.675	-9.39		28.63
CV-24103	9/21/2026 11:54:27 AM	-0.90	-0.90	5.3	5.3	0.587	0.583	-10.75	-11.06	28.67
CV-24104	9/1/2026 1:54:55 PM	-0.41	-0.24	3.1	3.0	1.072	0.973	-9.52		28.58
CV-24104	9/3/2026 10:55:10 AM	-0.50	-0.65	3.7	3.7	1.428	1.430	-10.36	-10.18	28.58

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24104	9/21/2026 12:21:54 PM	-0.77	-0.76	3.0	2.0	0.932	0.437	-10.51	-10.83	28.67
CV-24105	9/1/2026 2:02:32 PM	-0.45	-0.44	12.1	12.1	0.892	0.894	-8.77		28.58
CV-24105	9/22/2026 3:05:41 PM	-0.41	-0.41	13.5	13.1	1.168	1.101	-9.40	-9.06	28.42
CV-24106	9/15/2026 12:21:17 PM	-1.37	-1.14	7.2	4.8	0.143	0.064	-19.46	-20.45	28.6
CV-24106	9/15/2026 12:21:57 PM	-1.15	-1.15	4.3	4.9	0.051	0.067	-19.90	-20.64	28.58
CV-24107	9/9/2026 1:53:59 PM	-3.96	-3.76	0.0	0.0	4.103	3.766	-5.54		28.61
CV-24108	9/9/2026 1:16:23 PM	-2.96	-0.88	0.0	0.0	-0.067	-0.005	-19.93		28.59
CV-24108	9/9/2026 1:17:42 PM	-0.59	-0.56	0.0	0.0	0.013	0.010	-16.90		28.59
CV-24109	9/9/2026 12:50:32 PM	-3.66	-3.21	0.0	0.0	3.845	3.200	-19.13		28.59
CV-24110	9/3/2026 1:03:31 PM	-0.10	-0.10	18.1	18.4	0.214	0.220	-16.49	-19.18	28.48
CV-24111	9/3/2026 1:42:51 PM	-10.08	-6.65			10.144	6.653	-16.42	-18.16	28.45
CV-24112	9/3/2026 1:20:04 PM	-1.74	-1.73	38.0	37.1	0.942	0.898	-18.84	-18.72	28.48
CV-24114	9/23/2026 9:58:47 AM	-12.19	-15.29	29.6	28.2	0.578	0.531	-12.87	-15.66	28.57
CV-24116	9/24/2026 1:00:00 PM									
CV-24116	9/24/2026 1:00:00 PM									
CV-24116	9/24/2026 1:11:51 PM									
CV-24116	9/24/2026 1:12:29 PM	-1.10	-1.09			1.088	1.079	-7.61	-7.48	28.65
CV-24116	9/24/2026 3:03:05 PM									
CV-24117	9/24/2026 10:47:16 AM	-0.76	-0.68			0.755	0.675	-13.54	-13.86	28.59
CV-24118	9/1/2026 9:00:54 AM	-0.68	-0.68			0.664	0.671	-14.34	-16.65	28.65
CV-24118	9/2/2026 2:19:21 PM	-0.37	-0.38			0.299	0.311	-15.66	-15.65	28.66
CV-24118	9/2/2026 2:25:00 PM									
CV-24118	9/2/2026 2:25:00 PM									
CV-24118	9/10/2026 9:35:00 AM									
CV-24118	9/10/2026 9:38:23 AM	-0.11	-0.10			0.095	0.096	-14.71	-14.72	28.64
CV-24118	9/17/2026 10:36:18 AM	-4.84	-4.84			4.816	4.820	-24.86	-25.05	28.79
CV-24118	9/17/2026 10:39:00 AM									
CV-24119	9/28/2026 2:35:12 PM	-0.70	-0.66			0.633	0.547	-21.11	-21.60	28.41
CV-24120	9/9/2026 8:10:00 AM									
CV-24120	9/9/2026 8:10:00 AM									
CV-24120	9/14/2026 10:25:29 AM	-6.64	-3.05			6.984	3.010	-6.77	-6.57	28.59
CV-24120	9/14/2026 10:27:15 AM	-4.09	-4.04			4.017	3.980	-6.40	-6.51	28.59
CV-24120	9/25/2026 10:26:04 AM	-4.70	-4.28			4.707	4.284	-8.33	-8.39	28.57

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24120	9/28/2026 9:41:44 AM	4.93	-1.78			0.000	1.789	-9.49	-9.55	28.45
CV-24120	9/28/2026 9:50:35 AM	-6.03	-6.00			6.389	6.331	-9.42	-9.20	28.47
CV-24121	9/3/2026 9:37:51 AM	120.52	-1.09			0.000	1.116	-6.33	-5.79	28.58
CV-24121	9/3/2026 9:43:25 AM	-1.67	-1.70			1.654	1.759	-5.39	-4.96	28.57
CV-24121	9/10/2026 9:45:00 AM									
CV-24121	9/10/2026 9:45:00 AM									
CV-24121	9/25/2026 10:30:06 AM	-7.31	-5.47			7.693	5.899	-8.11	-8.11	28.58
CV-24122	9/8/2026 8:20:00 AM									
CV-24122	9/8/2026 8:20:00 AM									
CV-24122	9/15/2026 7:57:25 AM	-7.11	-7.11	47.9	47.9	5.818	5.809	-6.28	-6.27	28.58
CV-24122	9/15/2026 7:58:33 AM	-7.05	-7.39	47.6	48.1	5.742	5.872	-6.25	-6.42	28.58
CV-24122	9/25/2026 10:38:50 AM	-4.96	-5.06	0.4	0.6	0.009	0.016	-4.97	-4.99	28.6
CV-24123	9/3/2026 9:17:50 AM	-3.49	-3.67	2.4	2.9	0.015	0.022	-6.89	-6.62	28.61
CV-24123	9/11/2026 3:37:45 PM	-3.32	-3.47			0.196	0.228	-6.30	-6.28	28.49
CV-24123	9/11/2026 3:38:20 PM	-3.52	-3.53			0.219	0.204	-6.14	-6.32	28.49
CV-24123	9/23/2026 8:27:33 AM	-6.11	-5.29	4.3	3.8	0.051	0.040	-9.26	-9.58	28.59
CV-24124	9/15/2026 10:14:34 AM	-0.77	-0.77	0.0	0.0	0.729	0.725	-4.83		28.56
CV-24124	9/15/2026 10:15:20 AM	-0.74	-0.75	0.0	0.0	0.738	0.732	-4.88		28.56
CV-24124	9/29/2026 8:14:35 AM	-4.21	-4.20			4.239	4.234	-10.00	-9.90	28.35
CV-24124	9/29/2026 8:15:27 AM	-4.22	-4.21			4.287	4.246	-10.05	-9.82	28.36
CV-24125-TP	9/9/2026 8:20:00 AM									
CV-24125-TP	9/9/2026 8:20:00 AM									
CV-24125-TP	9/14/2026 9:25:49 AM	-8.02	-4.23			8.294	4.179	-10.16	-10.19	28.58
CV-24125-TP	9/29/2026 8:05:16 AM	-6.08	-6.08			6.357	6.348	-13.79	-13.88	28.38
CV-24126	9/8/2026 2:01:24 PM	-2.35	-2.34			2.360	2.315	0.28	0.29	28.6
CV-24126	9/8/2026 2:04:00 PM									
CV-24126	9/14/2026 1:36:52 PM	-3.54	-3.14			3.504	3.172	0.18	0.29	28.42
CV-24126	9/14/2026 1:40:00 PM									
CV-24126	9/21/2026 1:17:00 PM									
CV-24126	9/21/2026 1:17:21 PM	-4.85	-4.87			5.079	5.075	-5.64	-5.61	28.51

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24126	9/28/2026 1:36:03 PM	-5.83	-5.39			6.089	5.687	0.00	0.00	28.38
CV-24126	9/28/2026 1:45:00 PM									
CV-24127	9/8/2026 8:00:00 AM									
CV-24127	9/8/2026 8:00:00 AM									
CV-24127	9/8/2026 2:06:28 PM	-2.91	-2.77			2.901	2.783	-3.27	-3.07	28.59
CV-24127	9/8/2026 2:09:00 PM									
CV-24127	9/14/2026 1:33:01 PM	-3.99	-3.92			3.941	3.902	-4.35	-4.21	28.42
CV-24127	9/14/2026 1:36:00 PM									
CV-24127	9/21/2026 1:12:42 PM	-4.83	-4.80			4.805	4.807	-6.15	-6.11	28.52
CV-24127	9/21/2026 1:13:00 PM									
CV-24127	9/28/2026 1:25:09 PM	-6.07	-6.07			6.351	6.385	-6.75	-6.74	28.38
CV-24127	9/28/2026 1:35:00 PM									
CV-24128	9/9/2026 12:13:22 PM	-0.61	-0.59			0.520	0.533	-9.30	-9.01	28.6
CV-24128	9/9/2026 12:14:49 PM	-0.50	-0.51			0.417	0.433	-6.44	-6.72	28.6
CV-24128	9/10/2026 9:35:00 AM									
CV-24128	9/10/2026 9:35:00 AM									
CV-24128	9/25/2026 9:55:31 AM	-1.07	-1.10			1.058	1.094	-11.69	-11.68	28.53
CV-24129	9/9/2026 12:18:22 PM	-6.84	-6.09			7.350	6.513	-6.19	-6.02	28.61
CV-24129	9/25/2026 9:45:34 AM	-9.62	-9.32			9.944	9.542	-11.72	-11.70	28.56
CV-24130	9/30/2026 2:09:18 PM	-0.30	-0.29			0.314	0.297	-3.64	-4.00	28.43
CV-24131	9/10/2026 1:47:00 PM	-0.12	-0.15	13.0	13.6	0.466	0.509	-10.31	-10.45	28.51
CV-24132	9/30/2026 10:16:29 AM	-8.73	-8.78	13.8	12.3	0.052	0.041	-12.67	-12.86	28.54
CV-24133	9/21/2026 8:33:25 AM	-7.50	-7.50	22.1	22.2	1.360	1.378	-13.36	-13.56	28.63
CV-24134-TP	9/10/2026 1:06:47 PM	-1.75	-1.78			1.713	1.738	-1.68	-1.77	28.49
CV-24134-TP	9/14/2026 1:29:38 PM	-2.57	-2.55			2.568	2.549	-3.03	-3.03	28.42
CV-24134-TP	9/14/2026 1:32:00 PM									
CV-24134-TP	9/21/2026 1:07:00 PM									
CV-24134-TP	9/21/2026 1:09:25 PM	-2.66	-2.63			2.661	2.639	-3.07	-3.07	28.53

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24134-TP	9/28/2026 1:06:51 PM	-0.91	-0.89			0.816	0.801	-1.35	-1.35	28.4
CV-24134-TP	9/28/2026 1:25:00 PM									
CV-24135	9/3/2026 9:48:00 AM									
CV-24135	9/3/2026 9:48:00 AM									
CV-24135	9/3/2026 10:26:41 AM	-0.79	-0.81			0.785	0.792	-2.69	-2.64	28.57
CV-24135	9/10/2026 2:23:00 PM									
CV-24135	9/10/2026 2:26:00 PM	0.48	-0.25			0.000	0.268	-1.69	-1.65	28.5
CV-24135	9/10/2026 2:27:03 PM	-0.28	-0.28			0.272	0.282	-1.68	-1.68	28.5
CV-24135	9/14/2026 1:23:45 PM	-1.75	-1.74			1.737	1.747	-3.03	-3.03	28.43
CV-24135	9/14/2026 1:27:00 PM									
CV-24135	9/24/2026 1:53:54 PM	-1.16	-1.15			1.124	1.128	-2.15	-2.16	28.5
CV-24135	9/24/2026 1:55:00 PM									
CV-24136	9/10/2026 1:43:56 PM	-1.32	-1.31			1.266	1.273	-5.92	-6.51	28.52
CV-24137	9/28/2026 1:45:23 PM	-3.65	-3.65			3.667	3.662	-22.65	-22.31	28.37
CV-24138	9/2/2026 7:35:00 AM									
CV-24138	9/2/2026 7:35:00 AM									
CV-24138	9/2/2026 7:58:13 AM	-3.91	-3.90	0.0	0.0	3.625	3.742	-3.85		28.7
CV-24138	9/2/2026 7:59:07 AM	-4.08	-4.07	0.0	0.0	3.919	3.838	-3.96		28.7
CV-24138	9/30/2026 2:54:56 PM	-4.34	-4.38			4.344	4.347	-4.39	-4.45	28.45
CV-24139	9/1/2026 1:45:00 PM									
CV-24139	9/1/2026 1:45:00 PM									
CV-24139	9/1/2026 1:48:41 PM	-5.52	-5.53			5.666	5.590	-5.52	-5.54	28.7
CV-24139	9/2/2026 7:30:00 AM									
CV-24139	9/2/2026 7:30:00 AM									
CV-24139	9/8/2026 1:22:11 PM	-5.34	-4.90	0.0	0.0	5.220	5.065	-4.74		28.66
CV-24139	9/10/2026 2:55:48 PM	-4.74	-2.49			4.735	2.507	-4.88	-5.14	28.58
CV-24139	9/10/2026 3:13:23 PM	-1.12	-1.10			1.157	1.139	-4.86	-5.01	28.57
CV-24139	9/10/2026 3:15:24 PM	-0.67	-0.67			0.688	0.692	-4.94	-4.92	28.57

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24139	9/30/2026 2:51:42 PM	-7.90	-7.71			8.057	7.886	-7.97	-7.89	28.45
CV-24140	9/1/2026 1:40:00 PM									
CV-24140	9/1/2026 1:40:00 PM									
CV-24140	9/1/2026 1:44:48 PM	-4.96	-4.94			5.000	5.075	-5.03	-5.12	28.69
CV-24140	9/2/2026 7:25:00 AM									
CV-24140	9/2/2026 7:25:00 AM									
CV-24140	9/8/2026 1:16:52 PM	-4.55	-4.56	0.0	0.0	4.552	4.684	-4.58		28.53
CV-24140	9/8/2026 1:20:00 PM									
CV-24140	9/17/2026 9:53:55 AM	-8.42	-8.13			8.789	8.635	-9.37	-9.09	28.8
CV-24140	9/17/2026 9:55:00 AM									
CV-24140	9/24/2026 9:42:13 AM	-9.47	-9.32			9.937	9.784	-9.67	-9.46	28.61
CV-24140	9/24/2026 9:45:00 AM									
CV-24141	9/2/2026 7:10:00 AM									
CV-24141	9/2/2026 7:10:00 AM									
CV-24141	9/15/2026 9:57:58 AM	-4.95	-5.12			5.045	5.113	-4.99	-5.10	28.67
CV-24141	9/15/2026 9:59:24 AM	-5.25	-5.27			5.226	5.262	-5.16	-5.10	28.67
CV-24141	9/23/2026 9:57:06 AM	-7.13	-3.58			7.603	3.576	-7.14	-7.24	28.55
CV-24142	9/1/2026 1:54:21 PM	-1.61	-1.61			1.601	1.596	-2.13	-2.18	28.73
CV-24142	9/2/2026 7:40:00 AM									
CV-24142	9/2/2026 7:40:00 AM									
CV-24142	9/30/2026 2:58:57 PM	-3.40	-3.42			3.391	3.421	-3.68	-3.91	28.45
CV-24143	9/1/2026 7:40:00 AM									
CV-24143	9/1/2026 7:40:00 AM									
CV-24143	9/10/2026 12:19:01 PM	-1.95	-2.19			1.914	2.165	-1.86	-2.20	28.71
CV-24143	9/10/2026 12:20:07 PM	-2.23	-1.93			2.169	1.893	-2.18	-1.86	28.71
CV-24143	9/23/2026 9:50:14 AM	-7.99	-4.25			8.342	4.250	-8.18	-8.15	28.56
CV-24144	9/2/2026 8:20:25 AM	-0.90	-0.86	28.9	28.9	0.667	0.665			28.72
CV-24145	9/9/2026 8:26:12 AM	-5.25	-5.06			0.111	0.001	-10.43	-10.35	28.64
CV-24145	9/9/2026 8:28:00 AM									

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24145	9/15/2026 8:52:56 AM	-4.71	-4.73			0.000	0.000	-9.07	-9.09	28.57
CV-24145	9/15/2026 8:55:00 AM									
CV-24145	9/22/2026 8:48:58 AM	-3.76	-3.76			0.000	0.000	-10.15	-10.11	28.56
CV-24145	9/22/2026 8:50:00 AM									
CV-24145	9/29/2026 8:14:25 AM	-6.46	-6.44			0.000	0.000	-12.14	-12.22	28.35
CV-24145	9/29/2026 8:20:00 AM									
CV-24146	9/11/2026 3:43:00 PM	-4.73	-4.92	16.0	18.4	0.334	0.442	-5.89	-6.15	28.49
CV-24146	9/11/2026 3:43:31 PM	-4.92	-4.93	16.7	20.0	0.329	0.476	-6.09	-6.18	28.49
CV-24146	9/23/2026 8:23:00 AM	-7.63	-7.56	24.3	24.0	0.773	0.755	-9.13	-9.12	28.59
CV-24146	9/29/2026 7:46:29 AM	-7.09	-6.76	26.5	28.8	0.926	1.096	-8.82	-8.56	28.42
CV-24146	9/29/2026 7:48:05 AM	-7.17	-7.28	27.8	28.0	1.024	1.034	-8.92	-9.15	28.39
CV-24147	9/14/2026 8:55:38 AM	-8.04	-8.08	21.2	24.7	0.117	0.159	-8.77	-8.51	28.62
CV-24147	9/29/2026 7:53:08 AM	-9.07	-9.11	5.1	25.1	0.007	0.168	-9.69	-10.07	28.42
CV-24148	9/1/2026 1:15:45 PM	-12.50	-12.32			12.640	12.476	-15.12	-14.51	28.57
CV-24148	9/1/2026 1:21:00 PM									
CV-24148	9/1/2026 1:21:00 PM									
CV-24148	9/9/2026 1:24:00 PM									
CV-24148	9/9/2026 1:25:02 PM	-7.07	-6.74			7.146	6.871	-8.73	-8.29	28.57
CV-24148	9/16/2026 9:01:24 AM	-4.09	-4.05			4.094	4.040	-4.66	-4.56	28.57
CV-24148	9/16/2026 9:06:00 AM									
CV-24148	9/23/2026 9:17:16 AM	-11.53	-11.46			11.925	11.896	-13.29	-13.35	28.49
CV-24148	9/23/2026 9:21:00 AM									
CV-24148	9/30/2026 8:20:00 AM									
CV-24148	9/30/2026 8:33:02 AM	-10.27	-10.27			10.492	10.492	-11.87	-11.87	28.45
CV-24149	9/2/2026 2:26:43 PM	-0.19	-0.22	11.4	14.8	0.034	0.057	-6.19	-6.57	28.55
CV-24149	9/28/2026 10:08:01 AM	-1.78	-1.78	13.4	14.3	0.047	0.054	-12.36	-12.55	28.41
CV-24150	9/14/2026 1:00:56 PM	-1.29	-1.29	38.1	38.0	1.388	1.384			28.41
CV-24150	9/22/2026 10:00:08 AM	-0.92	-0.91			0.903	0.903	-12.67	-12.77	28.52
CV-24151	9/2/2026 1:38:48 PM	-3.72	-3.10			3.676	3.030	-5.54	-5.73	28.56
CV-24151	9/28/2026 10:24:52 AM	-6.75	-5.32			6.965	5.598	-10.94	-10.85	28.41
CV-24152	9/2/2026 2:13:03 PM	0.06	-0.09	27.9	28.4	1.886	1.963	-3.52	-3.54	28.53

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24152	9/2/2026 2:14:21 PM	-0.15	-0.15	28.5	27.9	1.975	1.888	-3.56	-3.60	28.56
CV-24152	9/21/2026 2:17:53 PM	-1.01	-0.87	31.0	31.3	2.349	2.401	-5.39	-5.11	28.48
CV-24153	9/2/2026 2:35:08 PM	-0.47	-0.46			0.463	0.439	-14.03	-14.06	28.52
CV-24153	9/28/2026 10:19:05 AM	-0.73	-0.72			0.722	0.706	-12.91	-13.71	28.41
CV-24154	9/3/2026 12:57:36 PM	-4.74	-4.99			5.131	5.307	-13.73	-14.80	28.53
CV-24154	9/24/2026 1:45:55 PM	-2.06	-1.92			2.016	1.941	0.31	0.31	28.45
CV-24155	9/2/2026 2:32:05 PM	-1.02	-1.03			1.001	1.008	-5.95	-6.02	28.52
CV-24155	9/28/2026 10:12:48 AM	-2.25	-2.24			2.246	2.215	-11.61	-11.46	28.41
CV-24156	9/2/2026 8:34:18 AM	0.15	-0.45	43.1	50.3	0.491	0.670	-9.76	-9.72	28.61
CV-24156	9/2/2026 8:35:16 AM	-0.60	-0.58	49.9	52.9	0.659	0.740	-9.86	-9.79	28.6
CV-24156	9/17/2026 2:44:43 PM	-0.44	-0.39	50.0	46.8	0.662	0.579	-8.91	-7.82	28.6
CV-24157	9/2/2026 1:17:03 PM	-0.95	-0.96			0.924	0.959	-9.30	-9.45	28.53
CV-24157	9/17/2026 2:54:47 PM	-1.35	-1.31			1.315	1.303	-8.90	-9.20	28.6
CV-24158	9/2/2026 1:50:00 PM	-0.36	-0.34	13.0	12.9	0.463	0.462	-9.69	-9.77	28.52
CV-24158	9/18/2026 9:48:59 AM	-1.20	-1.17	6.7	6.9	0.123	0.130	-4.98	-4.70	28.63
CV-24159	9/13/2026 10:18:12 AM	-1.37	-1.24	17.2	14.5	0.706	0.503	-19.76	-20.74	28.47
CV-24159	9/13/2026 10:19:02 AM	-1.18	-1.17	14.8	15.1	0.518	0.543	-21.88	-22.23	28.49
CV-24159	9/25/2026 11:34:39 AM	0.32	-0.05	4.9	12.2	0.057	0.353	-1.59	-0.89	28.59
CV-24159	9/25/2026 11:37:32 AM	-1.14	-0.44	29.7	13.9	2.121	0.461	-6.66	-7.40	28.6
CV-24159	9/25/2026 11:38:14 AM	-0.46	-0.42	16.5	16.1	0.651	0.617	-10.43	-9.52	28.61
CV-24160	9/13/2026 10:07:13 AM	-2.22	-2.33	11.5	13.1	0.869	1.122	-24.35	-24.62	28.48
CV-24160	9/13/2026 10:08:00 AM	-2.38	-2.38	13.3	13.3	1.149	1.161	-24.43	-24.73	28.48
CV-24160	9/24/2026 2:00:04 PM	-0.22	-0.14	12.5	15.3	0.370	0.555	-9.53	-11.49	28.45
CV-24161	9/14/2026 1:18:54 PM	-14.85	-7.77			14.871	7.967	0.21	0.21	28.37
CV-24162	9/9/2026 1:08:06 PM	-0.91	-0.84	0.0	0.0	0.778	0.771	-20.29		28.58
CV-24162	9/14/2026 1:22:08 PM	-2.42	-2.40			2.401	2.380	-17.24	-20.61	28.37
CV-24163	9/1/2026 9:47:08 AM	-0.29	-0.29			0.281	0.281	-16.54	-15.59	28.6
CV-24164	9/2/2026 9:23:46 AM	-0.87	-0.87	19.3	19.2	0.877	0.871	-11.01	-11.36	28.6
CV-24164	9/2/2026 9:26:17 AM	-0.17	-0.17	23.7	24.6	1.325	1.315	-10.86	-11.15	28.6

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24164	9/17/2026 2:06:22 PM	-0.76	-0.77	17.6	17.7	0.738	0.741	-10.59	-10.81	28.63
CV-24164	9/17/2026 2:07:38 PM	-0.72	-0.73	16.7	16.9	0.660	0.679	-9.89	-10.32	28.63
CV-24165	9/15/2026 1:44:17 PM	-7.49	-6.77	0.0	0.0	7.480	6.808	-8.32		28.5
CV-24165	9/30/2026 1:54:12 PM	-0.50	-0.53			0.433	0.466	-0.10	-0.10	28.43
CV-24165	9/30/2026 2:18:26 PM	-5.74	-5.77			6.105	6.030	-7.38	-7.43	28.47
CV-24166	9/13/2026 10:25:03 AM	-5.71	-6.34			5.675	6.269	-7.74	-8.78	28.45
CV-24166	9/13/2026 10:25:58 AM	-6.13	-5.71			6.153	5.672	-7.84	-7.30	28.48
CV-24166	9/21/2026 8:17:14 AM	-5.51	-5.74			5.649	5.806	-7.90	-8.16	28.52
CV-24167	9/15/2026 9:35:57 AM	-4.54	-4.54	0.0	0.0	4.304	4.503	-9.19		28.5
CV-24167	9/30/2026 1:45:26 PM	-0.05	-0.51			0.050	0.488	-0.94	-0.69	28.4
CV-24167	9/30/2026 1:46:57 PM	-0.97	-1.25			0.962	1.164	-1.36	-1.30	28.4
CV-24168	9/14/2026 2:05:52 PM	-1.78	-1.67			1.723	1.661	-6.61	-4.21	28.37
CV-24168	9/21/2026 9:52:58 AM	-2.61	-1.00			2.627	0.988	-5.53	-7.50	28.52
CV-24169	9/14/2026 2:01:29 PM	-2.16	-1.65			2.147	1.625	-7.54	-7.73	28.38
CV-24169	9/28/2026 10:50:36 AM	-2.02	-2.02			2.018	1.994	-10.87	-11.08	28.41
CV-24170	9/2/2026 9:09:47 AM	-0.15	-0.13	10.4	11.2	0.070	0.080	-7.92	-8.08	28.6
CV-24170	9/17/2026 1:45:21 PM	-1.04	-1.03	11.6	11.2	0.086	0.081	-10.66	-9.52	28.64
CV-24171	9/14/2026 1:31:04 PM	-1.30	-1.31	23.6	23.7	0.739	0.749	-8.86	-9.23	28.37
CV-24171	9/21/2026 8:30:41 AM	-1.62	-2.00	23.4	31.1	0.724	1.277	-9.63	-9.37	28.52
CV-24172	9/14/2026 1:41:43 PM	-0.11	-0.10	3.0	3.1	0.026	0.027	-9.83	-9.87	28.37
CV-24172	9/21/2026 9:04:18 AM	-0.15	-0.16	7.3	7.3	0.146	0.147	-11.61	-12.32	28.52
CV-24173	9/14/2026 1:49:58 PM	-0.12	-0.12	13.6	13.9	0.448	0.465	-10.72	-10.82	28.37
CV-24173	9/21/2026 9:21:07 AM	-0.35	-0.35	14.1	15.2	0.473	0.555	-12.17	-11.86	28.54
CV-24174	9/15/2026 1:52:08 PM	-0.78	-0.77	0.0	0.0	0.709	0.712	-0.75		28.5
CV-24174	9/24/2026 8:32:37 AM	-2.03	-1.16			2.005	1.146	-12.41	-9.39	28.55
CV-24175	9/15/2026 9:24:45 AM	-1.23	-1.24	12.2	13.1	0.107	0.124	-12.28	-13.39	28.52
CV-24175	9/30/2026 8:57:29 AM	-0.30	-0.30	6.3	10.7	0.025	0.067	-4.58	-4.53	28.52

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24176	9/1/2026 11:15:56 AM	0.22	0.20	0.0	0.0	-0.015	-0.017	0.12		28.6
CV-24176	9/1/2026 11:16:38 AM	0.06	0.14	0.0	0.0	-0.022	-0.012	0.16		28.6
CV-24176	9/3/2026 10:17:38 AM	0.20	0.21	5.3	4.7	0.017	0.013	0.25	0.31	28.59
CV-24176	9/30/2026 9:16:05 AM	-0.28	-0.28	1.6	1.8	0.007	0.008	0.02	0.02	28.54
CV-24177	9/2/2026 7:09:30 AM	-0.25	-0.25	0.0	0.0	0.076	0.075	-11.70		28.73
CV-24177	9/22/2026 12:56:38 PM	-0.60	-0.56	0.0	0.0	-0.060	0.047	-9.38		28.54
CV-24178	9/1/2026 2:59:57 PM	1.00	1.00	0.0	0.0	-0.034	-0.033	1.00		28.55
CV-24178	9/1/2026 3:02:27 PM	0.97	0.97	0.0	0.0	-0.049	-0.046	0.97		28.55
CV-24178	9/3/2026 10:29:19 AM	0.71	0.70	4.1	4.1	0.044	0.044	0.03	0.03	28.58
CV-24178	9/9/2026 2:38:51 PM	-3.03	-2.81	32.3	27.1	3.291	2.313	-6.44		28.57
CV-24178	9/9/2026 2:41:36 PM	-2.68	-2.69	32.9	28.7	3.417	2.599	-6.33		28.57
CV-24178	9/22/2026 1:58:45 PM	-3.98	-3.20	44.9	24.3	5.741	1.658	-9.26	-9.43	28.45
CV-24179	9/1/2026 11:22:17 AM	-0.15	-0.16	4.4	4.4	0.067	0.067	-10.35		28.63
CV-24179	9/30/2026 11:41:43 AM	0.13	0.13	1.5	1.5	0.006	0.006	0.14	0.14	28.56
CV-24179	9/30/2026 11:42:38 AM	0.13	0.13	0.8	0.5	0.002	0.001	0.00	0.00	28.56
CV-24180	9/1/2026 3:04:20 PM	0.47	0.45	0.0	0.0	-0.035	-0.032	0.05		28.56
CV-24180	9/1/2026 3:05:55 PM	0.46	0.45	0.0	0.0	-0.109	-0.038	0.44		28.56
CV-24180	9/18/2026 4:27:56 PM	-7.48	-5.96	22.0	14.2	1.362	0.562	-9.89	-10.55	28.58
CV-24180	9/22/2026 3:35:15 PM	-4.35	-3.97	23.8	12.3	1.588	0.422	-9.23	-8.90	28.44
CV-24181	9/1/2026 2:56:29 PM	0.26	0.30	0.0	0.0	-0.150	-0.141	0.30		28.56
CV-24181	9/1/2026 2:57:27 PM	0.25	0.26	0.0	0.0	-0.148	-0.147	0.27		28.56
CV-24181	9/9/2026 2:02:35 PM	-1.40	-1.39	7.1	7.0	6.116	5.924	-6.86		28.58
CV-24181	9/22/2026 3:27:56 PM	-1.05	-1.08			0.000	0.000	-6.57	-6.91	28.44
CV-24182	9/1/2026 2:49:50 PM	-2.46	-2.42	0.0	0.0	2.294	2.290	-5.13		28.55
CV-24182	9/22/2026 3:17:59 PM	-2.95	-2.98			2.891	2.857	-8.07	-7.98	28.43
CV-24183	9/1/2026 2:44:48 PM	-0.07	-0.11	0.0	0.0	0.339	0.345	-5.28		28.56
CV-24183	9/22/2026 2:15:06 PM	-0.09	-0.10			0.065	0.092	-9.23	-9.28	28.45
CV-24184	9/1/2026 2:29:37 PM	-0.10	-0.05	1.9	2.7	0.072	0.147	-5.65		28.56
CV-24184	9/1/2026 2:34:21 PM	-0.01	-0.01	8.2	8.2	1.382	1.380	-5.58		28.56
CV-24184	9/3/2026 12:22:14 PM	-0.14	-0.24	7.6	9.6	1.272	2.041	-8.41	-8.37	28.57
CV-24184	9/3/2026 12:23:03 PM	-0.24	-0.23	9.2	9.3	1.855	1.902	-7.87	-8.10	28.57
CV-24184	9/22/2026 2:21:19 PM	-0.15	-0.13	5.7	6.0	0.712	0.776	-9.05	-9.52	28.45
CV-24185	9/1/2026 2:19:32 PM	0.17	-0.03	16.7	20.4	0.747	1.118	-5.37		28.56
CV-24185	9/1/2026 2:20:58 PM	-0.16	-0.15	19.5	19.6	1.069	1.075	-5.37		28.56

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24185	9/3/2026 12:38:20 PM	-0.56	-0.59	24.2	24.6	1.613	1.667	-7.52	-7.72	28.57
CV-24185	9/22/2026 2:34:09 PM	-0.79	-0.78	26.3	26.3	1.917	1.912	-9.88	-9.50	28.42
CV-24185	9/22/2026 2:35:54 PM	-0.79	-0.81	26.2	26.4	1.890	1.918	0.00	-0.01	28.45
CV-24186	9/15/2026 10:32:27 AM	-1.34	-1.35	17.1	16.9	0.804	0.783	-8.43	-8.80	28.63
CV-24186	9/22/2026 2:42:35 PM	-0.70	-0.69	37.8	38.2	0.927	0.943	-9.08	-9.29	28.41
CV-24187	9/2/2026 9:24:10 AM	-0.61	-0.55	8.1	8.2	0.174	0.181	-13.51		28.66
CV-24187	9/22/2026 12:48:46 PM	-0.07	-0.07	0.0	0.0	-3.112	-3.024	-8.43		28.55
CV-24187	9/22/2026 2:45:38 PM	-1.05	-1.04	19.7	20.0	1.039	1.070	-9.42	-9.14	28.42
CV-24188	9/2/2026 8:53:02 AM	-2.57	-2.55	11.0	11.0	0.323	0.329	-13.15		28.7
CV-24188	9/22/2026 10:14:23 AM	-0.50	-0.97	6.6	10.1	0.116	0.275	-11.84	-11.74	28.67
CV-24189	9/2/2026 8:58:47 AM	-0.46	-0.31	5.0	0.7	0.499	0.009	-13.60		28.7
CV-24189	9/22/2026 10:07:55 AM	0.22	-0.11	0.5	3.4	0.004	0.233	-12.64	-12.60	28.69
CV-24189	9/22/2026 10:08:53 AM	-0.18	-0.17	3.3	3.2	0.222	0.215	-12.57	-11.98	28.66
CV-24190	9/2/2026 9:15:42 AM	-4.35	-4.31	38.8	45.5	0.902	1.242	-12.92		28.65
CV-24190	9/22/2026 12:45:58 PM	-1.80	-1.26	0.0	0.0	-4.481	-3.938	-8.99		28.57
CV-24192	9/2/2026 9:12:33 AM	-11.72	-11.70	21.6	21.5	0.560	0.557	-12.50		28.66
CV-24192	9/4/2026 1:39:12 PM	-7.94	-8.06	17.4	17.0	0.401	0.383	-8.64	-8.63	28.61
CV-24192	9/22/2026 12:39:10 PM	-8.34	-8.35	0.0	0.0	-10.037	-10.037	-9.12		28.58
CV-24193	9/1/2026 11:28:13 AM	-8.16	-8.17	15.8	15.8	0.310	0.311	-9.80		28.62
CV-24193	9/21/2026 11:49:20 AM	-9.03	-9.03	14.6	15.4	0.367	0.411	-11.09	-11.30	28.67
CV-24194	9/1/2026 1:49:41 PM	-4.31	-4.31	3.6	3.6	1.313	1.322	-9.42		28.6
CV-24194	9/3/2026 10:43:30 AM	-4.77	-4.94	3.6	3.9	1.378	1.627	-9.87	-9.98	28.58
CV-24194	9/21/2026 12:40:02 PM	-1.45	-2.03	5.4	3.3	3.076	1.145	-10.48	-10.35	28.63
CV-24194	9/21/2026 12:42:15 PM	-2.20	-2.22	7.0	7.4	1.031	1.154	-9.73	-10.75	28.63
CV-24195	9/1/2026 1:57:58 PM	-0.25	-0.24	7.1	7.1	1.018	1.018	-9.56		28.58
CV-24195	9/3/2026 11:04:13 AM	-0.53	-0.54	12.4	12.9	0.982	1.057	-8.69	-8.73	28.6
CV-24195	9/21/2026 12:26:17 PM	-0.58	-0.58	7.1	7.7	1.078	1.260	-10.64	-11.89	28.66
CV-24195	9/22/2026 3:15:01 PM	-0.31	-0.32	6.3	5.9	0.840	0.751	-8.59	-8.28	28.45
CV-24196	9/1/2026 2:06:39 PM	-0.73	-0.69	11.6	11.6	0.171	0.171	-8.94		28.58
CV-24196	9/22/2026 3:03:17 PM	-0.14	-0.21			0.000	0.000	-9.27	-9.50	28.45
CV-24197	9/1/2026 2:10:01 PM	-0.46	-0.46	14.2	14.2	0.542	0.543	-5.69		28.58
CV-24197	9/22/2026 2:56:45 PM	-0.82	-0.84	17.8	18.5	0.876	0.946	-9.52	-9.50	28.45
CV-24198	9/15/2026 12:38:31 PM	-3.30	-1.92	29.4	8.9	5.692	0.514	-21.08	-19.95	28.58
CV-24198	9/15/2026 12:40:21 PM	-1.29	-1.28	8.9	9.4	0.514	0.570	-19.61	-19.67	28.57

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24198	9/30/2026 1:17:46 PM	-0.08	-0.14	5.5	6.3	0.654	0.850	-7.23	-10.10	28.41
CV-24199	9/15/2026 12:27:13 PM	-0.63	-0.61	15.0	15.7	0.296	0.325	-19.71	-19.20	28.58
CV-24199	9/15/2026 12:29:31 PM	-0.47	-0.48	14.8	15.4	1.411	1.536	-18.71	-19.55	28.57
CV-24199	9/30/2026 1:27:46 PM	-0.17	-0.12	50.5	48.8	3.401	3.178	0.04	0.04	28.41
CV-24200	9/15/2026 9:58:46 AM	-2.67	-1.92	26.2	17.7	4.446	2.004	-21.82	-21.01	28.64
CV-24200	9/15/2026 9:59:38 AM	-1.90	-1.90	18.2	17.8	2.118	2.040	-21.85	-21.77	28.64
CV-24200	9/30/2026 1:33:17 PM	-0.03	-0.01	19.8	19.8	0.917	0.919	-8.27	-8.20	28.44
CV-24201	9/15/2026 10:10:20 AM	0.97	-0.07	3.8	9.6	0.037	0.252	-22.09	-21.19	28.64
CV-24201	9/15/2026 10:11:55 AM	-0.17	-0.13	9.4	9.0	0.242	0.222	-22.85	-23.30	28.64
CV-24201	9/15/2026 10:14:30 AM	-0.03	-0.07	2.8	3.3	0.022	0.029	-24.24	-24.17	28.64
CV-24201	9/24/2026 1:50:00 PM									
CV-24201	9/24/2026 1:50:00 PM									
CV-24201	9/24/2026 1:50:04 PM									
CV-24201	9/24/2026 1:50:55 PM	1.11	1.11	2.2	2.0	0.013	0.011	-14.15	-14.43	28.63
CV-24201	9/24/2026 2:48:38 PM									
CV-24201	9/28/2026 8:40:33 AM	1.49	-0.19	2.4	14.2	0.015	0.551	-12.01	-12.63	28.53
CV-24201	9/28/2026 8:44:14 AM	-0.44	-0.44	14.5	14.4	0.578	0.573	-13.46	-14.11	28.52
CV-24202	9/15/2026 4:15:49 PM	-13.62	-2.86			13.592	2.879	-19.41	-19.87	28.54
CV-24202	9/15/2026 4:17:09 PM	-2.50	-2.48			2.522	2.486	-20.96	-20.81	28.56
CV-24202	9/23/2026 10:59:35 AM	-0.96	-1.00			0.957	0.988	-14.98	-16.96	28.62
CV-24202	9/24/2026 1:32:57 PM									
CV-24202	9/24/2026 1:35:00 PM									
CV-24202	9/24/2026 1:35:00 PM									
CV-24202	9/24/2026 1:35:03 PM	-1.15	-1.15			1.143	1.099	-6.71	-6.71	28.6
CV-24202	9/24/2026 3:14:01 PM									
CV-24203	9/15/2026 9:25:44 AM	-0.47	-0.57	6.1	9.1	0.239	0.534	-10.23	-10.15	28.68
CV-24203	9/15/2026 9:28:02 AM	-1.21	-1.23	10.4	10.7	0.693	0.731	-20.16	-20.22	28.69
CV-24203	9/24/2026 12:50:00 PM									
CV-24203	9/24/2026 12:50:00 PM									

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24203	9/24/2026 12:53:25 PM									
CV-24203	9/24/2026 12:54:25 PM	-0.33	-0.35	7.6	7.9	0.370	0.403	-8.06	-8.02	28.66
CV-24203	9/24/2026 2:54:50 PM									
CV-24204	9/15/2026 9:12:51 AM	-3.43	-3.32	19.2	18.1	0.871	0.773	-14.43	-10.23	28.67
CV-24204	9/15/2026 9:15:00 AM	-3.92	-4.02	21.3	20.7	0.600	0.569	-14.47	-13.58	28.68
CV-24204	9/15/2026 9:15:53 AM	-3.96	-3.86	22.2	19.9	0.653	0.526	-13.05	-11.74	28.67
CV-24204	9/25/2026 9:17:43 AM	-5.51	-5.48	15.2	14.8	0.550	0.523	-15.93	-15.44	28.68
CV-24205	9/15/2026 9:07:09 AM	-2.75	-2.85	21.6	24.4	0.616	0.783	-10.28	-12.16	28.68
CV-24205	9/15/2026 9:08:01 AM	-2.96	-2.98	24.6	25.5	0.795	0.859	-12.04	-13.33	28.68
CV-24205	9/30/2026 4:14:08 PM	-3.72	-3.62	29.9	28.6	1.187	1.085	-15.30	-14.86	28.56
CV-24206	9/15/2026 9:41:41 AM	0.10	-0.05			0.000	0.052	-13.90	-14.07	28.64
CV-24206	9/15/2026 9:45:15 AM	-1.14	-1.14			1.167	1.158	-13.72	-13.13	28.64
CV-24206	9/23/2026 10:43:02 AM	0.19	-0.60			0.000	0.587	-6.91	-5.77	28.61
CV-24206	9/23/2026 10:44:23 AM	-0.74	-0.74			0.734	0.734	-5.72	-5.84	28.62
CV-24206	9/24/2026 12:30:00 PM									
CV-24206	9/24/2026 12:30:00 PM									
CV-24206	9/24/2026 12:33:26 PM									
CV-24206	9/24/2026 12:37:06 PM	-0.88	-0.84			0.019	0.019	-5.71	-5.47	28.64
CV-24206	9/24/2026 12:39:33 PM	-1.06	-1.05			1.033	1.045	-7.90	-8.02	28.61
CV-24206	9/24/2026 3:07:10 PM									
CV-24207	9/3/2026 12:47:00 PM	9.06	-0.43	3.8	33.9	0.019	1.546	-6.71	-6.49	28.52
CV-24207	9/3/2026 12:48:27 PM	-0.69	-0.62	30.1	29.1	1.215	1.141	-7.52	-7.22	28.53
CV-24207	9/13/2026 1:29:48 PM	-5.71	-4.89	25.7	19.3	0.905	0.509	-9.65	-9.24	28.44
CV-24207	9/13/2026 1:32:35 PM	-3.81	-2.69	20.8	15.9	2.884	1.680	-9.59	-9.32	28.45
CV-24207	9/13/2026 1:35:07 PM	-2.07	-2.13	16.8	17.0	1.858	1.911	-8.58	-8.79	28.45

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24207	9/13/2026 1:35:54 PM	-2.03	-2.14	16.4	18.1	1.779	2.157	-8.32	-9.65	28.45
CV-24207	9/21/2026 8:26:11 AM	-1.22	-0.77	41.6	35.0	2.300	1.635	-9.10	-8.67	28.52
CV-24208	9/24/2026 10:14:51 AM	-0.51	-0.48	13.1	13.4	1.118	1.169	-11.52	-10.81	28.62
CV-24208	9/24/2026 10:16:08 AM	-0.52	-0.42	22.9	23.2	1.210	1.248	-11.73	-12.14	28.63
CV-24209	9/30/2026 2:11:34 PM	-0.02	-0.04			0.064	0.066	-11.17	-11.13	28.56
CV-24210	9/9/2026 1:42:55 PM	-5.12	-4.71	0.0	0.0	5.402	4.651	-5.44		28.61
CV-24211	9/28/2026 2:53:00 PM	-19.56	-13.50			19.712	13.520	-19.84	-20.12	28.45
CV-24212	9/28/2026 2:46:21 PM	-8.73	-5.06			8.849	5.092	-18.73	-19.44	28.45
CV-24213	9/4/2026 9:21:22 AM	-0.03	-0.15			0.029	0.144	-12.00	-11.23	28.6
CV-24214	9/30/2026 1:49:40 PM	0.52	0.51			0.000	0.000	-5.50	-5.53	28.44
CV-24215	9/30/2026 1:28:04 PM	-2.08	-2.22	14.0	16.3	0.126	0.169	-11.20	-11.37	28.47
CV-24216	9/16/2026 11:46:26 AM	-7.38	-5.52			7.421	5.466	-18.92	-19.47	28.74
CV-24217	9/3/2026 1:30:59 PM	-0.12	-0.13			0.049	0.034	-16.64	-16.61	28.46
CV-24218	9/14/2026 1:37:55 PM	-0.12	-0.11	0.0	0.0	0.161	0.066			28.41
CV-24219	9/1/2026 9:17:40 AM	-13.03	-13.08			13.459	13.451	-14.59	-14.71	28.57
CV-24219	9/1/2026 9:23:00 AM									
CV-24219	9/1/2026 9:23:00 AM									
CV-24219	9/9/2026 10:37:30 AM	-12.33	-2.52			12.615	2.514	-12.89	-14.74	28.65
CV-24219	9/9/2026 10:37:57 AM	-2.89	-2.21			2.904	2.221	-14.68	-15.50	28.64
CV-24219	9/9/2026 10:42:00 AM									
CV-24219	9/15/2026 1:45:00 PM									
CV-24219	9/15/2026 1:50:49 PM	5.71	-1.34			0.000	1.378	-3.32	-2.80	28.5
CV-24219	9/15/2026 1:52:47 PM	-1.37	-1.63			1.396	1.672	-2.82	-2.82	28.5
CV-24219	9/22/2026 2:24:19 PM	-7.73	-7.53			8.093	7.843	-8.93	-8.80	28.46
CV-24219	9/22/2026 2:26:00 PM									

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24219	9/29/2026 1:44:55 PM	-4.86	-4.56			4.789	4.525	-9.23	-9.05	28.3
CV-24219	9/29/2026 1:45:41 PM	-4.85	-4.71			4.790	4.743	-9.32	-8.29	28.31
CV-24219	9/29/2026 1:50:00 PM									
CV-24220	9/1/2026 9:58:34 AM	-14.47	-14.14			14.802	14.609	-14.83	-14.51	28.6
CV-24220	9/8/2026 9:02:20 AM	-14.17	-2.47			14.605	2.443	-15.10	-15.92	28.6
CV-24220	9/8/2026 9:07:51 AM	-2.32	-2.32			2.301	2.296	-16.05	-16.15	28.61
CV-24221	9/28/2026 2:25:52 PM	-15.36	-12.48	22.2	38.9	1.428	4.334	-16.57	-17.31	28.42
CV-24222	9/30/2026 8:21:47 AM	-18.74	-18.80	29.7	28.3	2.536	2.306	-21.24	-20.99	28.53
CV-24223	9/28/2026 2:38:35 PM	-1.08	-1.05			1.042	1.034	-18.97	-19.10	28.43
CV-24224	9/30/2026 9:30:13 AM	0.26	-0.47			0.000	0.461	-23.43	-22.82	28.52
CV-24224	9/30/2026 9:30:54 AM	-0.56	-0.56			0.549	0.553	-22.93	-23.49	28.49
CV-24224	9/30/2026 2:00:06 PM	-0.10	-0.10			0.081	0.080	-19.04	-17.91	28.41
CV-24225	9/1/2026 9:07:25 AM	-0.21	-0.21			0.194	0.196	-17.14	-17.25	28.65
CV-24226	9/28/2026 2:56:01 PM	-5.30	-5.32	7.6	7.9	0.037	0.040	-21.53	-21.33	28.42
CV-24227	9/2/2026 9:09:03 AM	-3.39	-3.52	22.0	28.6	1.026	1.738			28.7
CV-24227	9/4/2026 1:33:49 PM	-3.12	-3.38	22.6	26.5	1.194	1.643	-9.16	-11.65	28.64
CV-24227	9/22/2026 12:30:13 PM	-3.22	-3.24	18.9	19.2	0.800	0.827			28.6
CV-24231	9/30/2026 12:42:54 PM	-0.54	-0.54	22.6	24.8	0.330	0.397	0.00	0.00	28.6
CV-24236	9/2/2026 1:22:24 PM	-2.38	-2.36	10.3	11.7	0.611	0.786	-11.59		28.75
CV-24237	9/2/2026 1:11:47 PM	-0.95	-1.05	19.3	24.0	0.743	1.151	-11.43		28.75
CV-24237	9/4/2026 2:04:02 PM	-1.26	-1.37	29.3	32.0	1.102	1.318	-10.86	-11.84	28.68
CV-24243	9/17/2026 12:16:52 PM	0.01	-0.04	1.3	11.8	0.005	0.375	-18.26	-16.48	28.87
CV-24243	9/17/2026 12:30:09 PM	-0.07	-0.04	11.5	8.7	0.357	0.205	-18.98	-17.30	28.86
CV-24243	9/17/2026 12:37:43 PM	-0.06	-0.05	5.2	2.6	0.073	0.018	-19.34	-17.40	28.87
CV-24243	9/22/2026 1:52:57 PM	-0.01	-0.01	5.6	5.3	0.084	0.076	-11.81	-10.85	28.66
CV-24244	9/16/2026 8:41:03 AM	-1.63	-1.68	13.9	14.5	0.516	0.565	-18.26	-17.59	28.74
CV-24244	9/16/2026 8:43:19 AM	-1.68	-1.75	15.0	15.3	0.600	0.631	-18.10	-18.95	28.76

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-24245	9/28/2026 10:15:21 AM	-0.75	-1.15	9.7	15.0	0.592	1.422	-15.65	-15.04	28.67
CV-24245	9/28/2026 10:17:16 AM	-1.18	-1.17	14.6	14.7	1.350	1.368	-14.28	-14.27	28.65
CV-24246	9/4/2026 9:59:35 AM	0.22	-0.07	4.0	16.3	0.043	0.715	-1.24	-0.96	28.76
CV-24246	9/4/2026 10:00:29 AM	-0.08	-0.13	15.6	20.6	0.655	1.147	-0.83	-1.73	28.76
CV-24253	9/28/2026 9:37:51 AM	-1.20	-1.30	20.0	21.9	0.906	1.091	-14.99	-14.52	28.68
CV-24253	9/28/2026 9:39:46 AM	-1.29	-1.28	22.6	21.9	1.156	1.096	-14.40	-14.07	28.68
CV-25	9/21/2026 8:45:49 AM	-17.97	-17.95	4.0	5.3	0.021	0.036	-18.33	-18.62	28.66
CV-2501	9/4/2026 1:08:58 PM	-1.13	-1.25	65.3	68.2	1.117	1.220	-6.69	-6.68	28.6
CV-2502	9/11/2026 10:11:06 AM	0.22	-0.28			0.063	0.000	-15.62	-16.44	28.55
CV-2502	9/11/2026 10:12:18 AM	-0.43	-0.43			0.000	0.000	-16.12	-16.07	28.55
CV-2503	9/11/2026 10:21:39 AM	-1.79	-1.91	53.0	57.8	0.718	0.855	-13.08	-13.31	28.57
CV-2503	9/23/2026 12:40:37 PM	-1.35	-1.43	39.8	46.0	0.416	0.556	-9.09	-10.51	28.62
CV-2504	9/23/2026 10:20:47 AM	-1.06	-1.21	37.3	42.5	3.868	5.045	-15.42	-15.94	28.6
CV-2504	9/23/2026 10:23:26 AM	-1.19	-1.23	41.0	40.6	4.695	4.602	-14.83	-14.61	28.61
CV-2505	9/23/2026 12:39:50 PM	-1.84	-2.02	33.1	35.5	0.708	0.816	-13.13	-13.71	28.61
CV-2506	9/23/2026 12:41:42 PM	-2.03	-2.04	36.3	34.7	0.853	0.779	-14.60	-13.32	28.61
CV-2506	9/23/2026 1:16:38 PM	-1.11	-1.15	31.7	35.1	0.649	0.795	-11.29	-13.56	28.63
CV-2507	9/23/2026 1:33:01 PM	-0.74	-1.04	34.6	38.9	1.581	1.997	-13.48	-13.90	28.64
CV-2507	9/23/2026 1:36:04 PM	-1.14	-1.17	39.4	38.8	2.054	1.985	-13.60	-13.61	28.64
CV-2508	9/23/2026 2:08:04 PM	-10.89	-11.32	80.3	85.6	1.736	1.978	-13.94	-14.81	28.65
CV-2509	9/4/2026 10:15:57 AM	-11.75	-11.91	80.5	80.1	4.258	4.214	-19.44	-18.98	28.75
CV-2510	9/4/2026 10:06:27 AM	-10.74	-10.80	45.5	46.5	5.752	6.020	-18.87	-19.41	28.76
CV-25100D	9/3/2026 10:05:34 AM	-3.40	-3.43			3.391	3.438	-5.22	-5.60	28.53
CV-25100D	9/3/2026 10:06:21 AM	-3.35	-2.60			3.341	2.579	-5.28	-5.33	28.52
CV-25100D	9/3/2026 10:34:00 AM									
CV-25100D	9/3/2026 10:34:00 AM									
CV-25100D	9/8/2026 1:58:00 PM									
CV-25100D	9/8/2026 1:58:37 PM	-1.86	-1.85			1.848	1.848	-4.87	-4.55	28.6
CV-25100D	9/14/2026 1:43:20 PM	-3.86	-3.84			3.876	3.853	-5.83	-5.92	28.42
CV-25100D	9/25/2026 2:09:25 PM	-5.56	-5.36			5.507	5.449	-10.08	-10.10	28.45

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-25100S	9/8/2026 1:54:00 PM									
CV-25100S	9/8/2026 1:54:17 PM	-2.16	-2.04			2.188	1.907	-5.09	-5.01	28.58
CV-25100S	9/14/2026 1:46:48 PM	-5.40	-5.05			5.702	5.234	-6.16	-5.89	28.42
CV-25100S	9/14/2026 1:47:00 PM									
CV-25100S	9/21/2026 1:22:46 PM	-7.15	-7.08			7.370	7.370	-9.33	-9.26	28.53
CV-25100S	9/21/2026 1:24:00 PM									
CV-25100S	9/28/2026 1:43:54 PM	-8.66	-8.42			8.951	8.717	-10.17	-10.11	28.38
CV-25100S	9/28/2026 1:55:00 PM									
CV-25101D	9/3/2026 9:32:55 AM	-2.35	-2.33			2.330	2.319	-6.15	-6.06	28.52
CV-25101D	9/22/2026 10:51:18 AM	-3.65	-3.65			3.644	3.645	-9.61	-9.50	28.49
CV-25101S	9/3/2026 9:34:39 AM	-2.00	-1.98			2.000	1.969	-5.93	-5.60	28.52
CV-25101S	9/22/2026 10:53:04 AM	-3.02	-3.01			3.015	3.002	-9.54	-9.48	28.5
CV-25102	9/14/2026 9:45:37 AM	4.34	-0.10		15.5	-4.377	0.361			28.47
CV-25102	9/14/2026 9:46:33 AM	-0.94	-0.49	41.4	37.9	2.463	2.069			28.47
CV-25102	9/14/2026 1:20:00 PM									
CV-25102	9/21/2026 9:40:00 AM									
CV-25102	9/21/2026 9:46:14 AM	-3.90	-3.91			3.920	3.924	-13.02	-13.06	28.58
CV-25102	9/21/2026 9:48:39 AM	-3.86	-3.84			3.854	3.873	-13.16	-13.27	28.57
CV-25102	9/28/2026 10:49:11 AM	-2.30	-2.30			2.285	2.284	-10.61	-10.60	28.45
CV-25102	9/28/2026 1:05:00 PM									
CV-25102	9/30/2026 8:30:50 AM	-3.80	-1.16			3.725	1.141	-12.41	-12.22	28.48
CV-25102	9/30/2026 8:32:19 AM	-1.23	-1.25			1.226	1.227	-12.23	-12.23	28.49
CV-25103	9/3/2026 9:09:00 AM	-0.29	-0.30			0.287	0.302	-8.02	-8.14	28.52
CV-25103	9/22/2026 10:46:56 AM	-0.61	-0.60			0.611	0.566	-11.13	-11.00	28.49
CV-25104D	9/15/2026 9:02:09 AM	40.95	-0.20		5.7		0.045			28.53
CV-25104D	9/15/2026 9:02:43 AM	-0.36	-0.36	13.4	13.4	0.241	0.241			28.53
CV-25104D	9/23/2026 1:35:53 PM	-2.97	-0.23			2.965	0.224	-8.17	-8.26	28.41
CV-25104S	9/14/2026 9:28:09 AM	-5.89	-5.88	67.9	67.9	5.887	5.882			28.47
CV-25104S	9/14/2026 9:28:26 AM	-5.73	-5.73	67.4	67.3	5.819	5.816			28.47
CV-25104S	9/21/2026 10:03:05 AM	-8.12	-8.13			8.465	8.449	-10.75	-10.83	28.58
CV-25104S	9/30/2026 9:51:41 AM	-8.08	-7.91			8.222	8.221	-11.98	-12.17	28.47

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-25105D	9/3/2026 8:36:30 AM	-15.70	-15.31			15.712	15.393	-15.35	-16.20	28.52
CV-25105D	9/3/2026 8:39:20 AM	-13.84	-13.84			13.984	13.927	-15.79	-15.80	28.49
CV-25105D	9/25/2026 11:09:43 AM	-3.07	-1.57			3.000	1.510	-12.40	-12.35	28.6
CV-25105D	9/25/2026 11:12:40 AM	-1.24	-1.33			1.265	1.341	-11.61	-11.15	28.63
CV-25105S	9/3/2026 8:42:42 AM	-0.30	-0.30			0.297	0.295	-9.61	-16.06	28.52
CV-25105S	9/3/2026 8:43:52 AM	-0.30	-0.30			0.301	0.301	-15.72	-16.29	28.52
CV-25105S	9/25/2026 10:57:59 AM	-0.64	-0.64			0.630	0.632	-10.81	-10.48	28.61
CV-25105S	9/25/2026 10:59:33 AM	-0.64	-0.64			0.629	0.628	-12.26	-12.24	28.59
CV-25106D	9/14/2026 9:16:26 AM	-8.63	-8.58	95.8	95.1	8.512	8.393			28.48
CV-25106D	9/21/2026 2:39:29 PM	-8.64	-8.86			8.746	9.002	-8.55	-8.38	28.48
CV-25106S	9/15/2026 9:01:26 AM	-9.68	-9.66			9.791	9.883	-9.69	-9.82	28.6
CV-25106S	9/15/2026 9:02:41 AM	-9.67	-9.66			9.741	9.810	-9.59	-9.56	28.6
CV-25106S	9/21/2026 2:36:58 PM	-8.44	-8.52			8.578	8.668	-8.23	-8.67	28.48
CV-25107D	9/1/2026 9:37:00 AM									
CV-25107D	9/1/2026 9:37:00 AM									
CV-25107D	9/1/2026 9:41:08 AM	-12.49	-3.48			12.951	3.488	-15.73	-15.78	28.57
CV-25107D	9/1/2026 9:49:48 AM	-3.39	-2.44			3.346	2.366	-16.31	-15.71	28.57
CV-25107D	9/1/2026 9:52:33 AM	-1.37	-1.39			1.342	1.324	-16.18	-14.44	28.57
CV-25107D	9/1/2026 10:04:00 AM									
CV-25107D	9/9/2026 10:27:10 AM	9.76	-4.59			0.000	4.514	-9.45	-9.48	28.66
CV-25107D	9/9/2026 10:32:44 AM	-4.16	-1.42			4.160	1.423	-5.90	-6.70	28.65
CV-25107D	9/9/2026 10:33:42 AM	-2.70	-2.35			2.753	2.169	-6.24	-9.53	28.65
CV-25107D	9/9/2026 10:35:00 AM									
CV-25107D	9/15/2026 1:35:00 PM									

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-25107D	9/15/2026 1:35:50 PM	2.29	2.51			0.000	0.000	1.49	1.28	28.49
CV-25107D	9/15/2026 1:39:57 PM	2.11	2.71			0.000	0.000	-0.23	1.45	28.49
CV-25107D	9/22/2026 2:13:00 PM									
CV-25107D	9/22/2026 2:20:08 PM	-3.12	-2.57			3.071	2.427	-3.12	-2.65	28.46
CV-25107D	9/29/2026 1:39:25 PM	-4.27	-5.45			3.948	4.939	-4.77	-5.85	28.31
CV-25107D	9/29/2026 1:40:00 PM									
CV-25107S	9/3/2026 12:53:12 PM	-0.06	-0.06			0.077	0.070	-12.55	-12.58	28.46
CV-25107S	9/22/2026 10:17:17 AM	-5.45	-3.22			5.743	3.210	-5.40	-7.15	28.49
CV-25107S	9/22/2026 10:19:04 AM	-2.64	-2.66			2.643	2.656	-9.61	-9.34	28.51
CV-2511	9/30/2026 1:02:49 PM	-0.38	-0.42	30.0	33.8	0.237	0.302	-8.87	-9.88	28.62
CV-2512	9/4/2026 10:31:39 AM	-0.90	-0.92	22.2	24.8	0.130	0.162	-18.14	-17.92	28.7
CV-2513	9/17/2026 1:56:08 PM	-2.27	-2.25	31.3	31.2	2.286	2.271	-14.17	-13.67	28.87
CV-2513	9/17/2026 1:59:17 PM	-2.29	-2.28	30.3	30.4	1.193	1.202	-13.72	-13.04	28.88
CV-2514	9/21/2026 10:01:35 AM	-0.19	-0.26	16.5	18.4	0.638	0.790	-3.90	-3.97	28.78
CV-2514	9/21/2026 10:07:35 AM	-0.28	-0.34	17.2	18.3	0.692	0.787	-3.61	-3.88	28.79
CV-2515	9/29/2026 10:32:00 AM	-2.03	-1.28	31.3	25.4	1.276	0.840	-16.05	-12.86	28.44
CV-2515	9/29/2026 10:36:37 AM	-1.21	-1.21	34.0	34.5	2.697	2.783	-15.76	-15.72	28.45
CV-2515	9/29/2026 10:37:18 AM	-1.26	-1.26	28.8	29.0	1.935	1.955	-15.90	-16.07	28.45
CV-2515	9/29/2026 10:40:01 AM	-1.39	-1.40	15.6	15.4	0.565	0.552	-15.89	-15.88	28.43
CV-2516	9/16/2026 11:55:45 AM	-7.35	-7.35	20.4	21.0	2.737	2.909	-15.46	-15.70	28.75
CV-2517	9/21/2026 9:13:49 AM	-3.28	-3.47	6.7	9.3	0.121	0.236	-19.36	-19.23	28.66
CV-2518	9/21/2026 9:35:14 AM	-5.08	-5.08	27.2	27.7	0.189	0.195	-0.34	-0.30	28.7
CV-2519	9/22/2026 2:34:58 PM	-1.01	-0.90	18.4	16.4	0.901	0.718	-18.60		28.49
CV-2520	9/22/2026 2:46:22 PM	-1.60	-1.45	0.0	0.0	0.123	0.165	-19.20		28.49
CV-2520	9/22/2026 2:48:41 PM	-1.12	-1.12	0.0	0.0	0.026	0.032	-19.21		28.49
CV-2521	9/30/2026 8:54:33 AM	-19.50	-19.47			19.745	19.705	-19.75	-19.74	28.48

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2521	9/30/2026 12:10:46 PM	-12.72	-11.07			12.942	11.303	-12.78	-12.39	28.56
CV-2521	9/30/2026 12:11:47 PM	-10.78	-10.87			11.011	11.038	-12.35	-12.23	28.56
CV-2522	9/22/2026 3:06:29 PM	-6.58	-4.60	0.0	0.0	-1.054	0.071	-19.09		28.52
CV-2522	9/22/2026 3:07:55 PM	-3.66	-3.62	0.0	0.0	0.021	-0.057	-19.22		28.52
CV-2523	9/25/2026 11:36:15 AM	-5.94	-5.97	30.4	30.4	6.061	6.050	-19.38	-18.58	28.66
CV-2524	9/22/2026 3:14:40 PM	-4.29	-1.46	0.0	0.0	-0.752	0.928	-16.91		28.52
CV-2524	9/22/2026 3:18:41 PM	-1.18	-1.14	0.0	0.0	1.078	1.071	-17.01		28.52
CV-2525	9/25/2026 11:17:14 AM	-12.87	-12.35	61.1	59.9	10.897	10.418	-19.50	-19.46	28.66
CV-2526	9/29/2026 9:14:52 AM	-1.57	-1.60	13.3	12.9	0.114	0.108	-20.70	-20.74	28.46
CV-2527	9/14/2026 8:36:25 AM	-5.65	-5.67			5.696	5.695	-20.31	-18.71	28.59
CV-2527	9/14/2026 8:37:20 AM	-5.44	-5.42			5.697	5.695	-20.75	-19.64	28.59
CV-2527	9/30/2026 9:05:03 AM	0.67	-0.24			0.000	0.249	-20.30	-19.56	28.53
CV-2527	9/30/2026 9:07:01 AM	-1.20	-1.21			1.203	1.213	-20.18	-19.97	28.5
CV-2527	9/30/2026 9:11:36 AM	-1.23	-0.18			1.229	0.176	-20.41	-19.99	28.53
CV-2527	9/30/2026 9:12:30 AM	-0.08	-0.08			0.076	0.075	-19.38	-20.78	28.53
CV-2527	9/30/2026 12:24:57 PM	-3.12	-3.18			3.075	3.133	-12.80	-12.48	28.56
CV-2527	9/30/2026 12:26:17 PM	-3.63	-3.64			3.584	3.594	-12.30	-13.92	28.59
CV-2528	9/21/2026 10:33:20 AM	-5.40	-5.41	21.1	22.3	0.282	0.315	-25.30	-25.22	28.7
CV-2529	9/4/2026 8:05:25 AM	13.31	-0.88	2.7	2.9	0.696	0.870	-16.78	-10.95	28.65
CV-2529	9/4/2026 8:07:06 AM	-1.61	-1.67	2.7	2.7	0.746	0.750	-10.83	-10.97	28.65
CV-2530	9/28/2026 3:53:58 PM	-21.37	-21.24			21.549	21.367	-21.59	-21.41	28.48
CV-2531	9/28/2026 3:43:12 PM	-9.72	-3.38			9.743	3.377	-21.60	-21.67	28.48
CV-2532	9/30/2026 8:40:47 AM	-22.46	-22.61			22.665	22.816	-23.52	-23.65	28.57
CV-2533	9/28/2026 3:24:49 PM	-5.77	-3.85	18.5	15.6	0.956	0.680	-21.91	-22.09	28.48
CV-2534	9/1/2026 11:25:42 AM	-1.04	-1.04	0.0	0.0	-1.022	-1.022	-10.62		28.63
CV-2534	9/28/2026 3:16:57 PM	-6.71	-3.34	43.6	29.2	2.456	1.086	-15.05	-14.42	28.46
CV-2535	9/23/2026 12:53:43 PM	-0.53	-0.33	12.0	9.7	3.058	1.971	-2.96	-2.67	28.61
CV-2536	9/25/2026 9:51:12 AM	-5.79	-5.73	5.5	5.2	0.628	0.553	-8.04	-7.79	28.76
CV-2537	9/25/2026 9:09:18 AM	-3.10	-3.10			3.125	3.125	-8.98	-9.17	28.7
CV-2538	9/25/2026 8:54:18 AM	-1.21	-1.21	31.4	31.4	2.281	2.268	-9.30	-9.22	28.71

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2539	9/15/2026 10:51:41 AM	-1.41	-1.39			1.382	1.365	-9.43	-9.18	28.67
CV-2539	9/21/2026 12:01:09 PM	-1.23	-1.23			1.210	1.210	-11.25	-11.22	28.67
CV-2540	9/2/2026 9:19:21 AM	-10.01	-3.32			10.241	3.332	-11.57	-11.59	28.6
CV-2540	9/17/2026 1:58:14 PM	-1.23	-1.31			1.219	1.280	-10.11	-10.45	28.63
CV-2541	9/1/2026 10:53:11 AM	-1.13	-1.14	0.0	0.0	1.169	1.168	-7.01		28.61
CV-2541	9/17/2026 10:16:55 AM	-2.34	-2.01			2.336	2.000	-11.10	-10.75	28.7
CV-2542	9/2/2026 1:13:18 PM	-9.73	-9.63			9.763	9.716	0.33	0.32	28.56
CV-2542	9/17/2026 3:00:18 PM	-9.34	-10.82			9.496	10.868	0.28	0.28	28.6
CV-2543-PLR	9/2/2026 9:36:06 AM	-1.92	-1.80			1.929	1.803	-1.48	-1.57	28.63
CV-2543-PLR	9/17/2026 2:16:09 PM	-4.56	-3.40			4.536	3.398	-4.43	-3.30	28.64
CV-2544	9/15/2026 9:11:52 AM	-2.09	-2.09	0.0	0.0	1.844	2.191	-6.81		28.51
CV-2544	9/15/2026 9:14:07 AM	-1.43	-1.45	0.0	0.0	1.383	1.388	-6.55		28.51
CV-2544	9/15/2026 9:33:39 AM	-1.66	-1.63	0.0	0.0	1.483	1.401	-6.54		28.51
CV-2544	9/21/2026 10:26:52 AM	-4.48	-4.33			4.477	4.338	-9.75	-9.28	28.58
CV-2544	9/21/2026 10:35:00 AM									
CV-2545	9/2/2026 1:57:34 PM	0.39	-0.07			0.000	0.064	-3.90	-3.42	28.52
CV-2545	9/2/2026 2:00:03 PM	-0.12	-0.13			0.106	0.114	-3.34	-3.08	28.53
CV-2545	9/21/2026 1:45:21 PM	-1.20	-1.19			1.175	1.164	-5.24	-4.92	28.47
CV-2546	9/2/2026 2:02:59 PM	0.04	-0.05			0.000	0.059	-3.37	-2.78	28.53
CV-2546	9/2/2026 2:03:29 PM	-0.21	-0.20			0.160	0.157	-3.16	-3.16	28.53
CV-2546	9/21/2026 2:15:18 PM	-0.78	-0.78			0.775	0.815	-4.44	-4.36	28.48
CV-2547	9/24/2026 1:41:35 PM	-0.05	-0.02			0.000	0.000	-2.31	-3.71	28.45
CV-2548	9/1/2026 12:26:39 PM	-0.33	-0.38	44.1	46.2	2.624	2.879	-15.14	-16.55	28.66
CV-2548	9/1/2026 12:27:39 PM	-0.45	-0.48	44.7	46.3	2.697	2.887	-15.69	-16.59	28.67
CV-2548	9/3/2026 1:03:06 PM	-1.22	-1.34	51.7	54.6	3.307	3.696	-19.04	-21.86	28.53
CV-2548	9/18/2026 2:00:15 PM	-0.99	-0.35	53.4	47.2	19.272	14.932	-21.05	-20.07	28.56
CV-2548	9/18/2026 2:02:16 PM	-0.34	-0.20	51.8	48.4	18.065	15.715	-21.53	-18.48	28.56

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2548	9/22/2026 9:25:43 AM	-0.08	-0.15			0.000	0.000	-20.23	-17.01	28.55
CV-2549	9/1/2026 12:15:56 PM	-1.17	-1.06	11.2	28.9	0.290	1.940	-15.80	-12.88	28.67
CV-2549	9/1/2026 12:17:23 PM	-1.04	-1.04	10.0	10.0	2.102	2.108	-14.10	-14.09	28.67
CV-2549	9/3/2026 1:08:50 PM	-1.00	-1.02	33.6	37.6	2.634	3.307	-15.52	-18.84	28.53
CV-2549	9/18/2026 1:52:07 PM	-3.32	-1.55	16.8	10.4	6.262	2.354	-25.65	-23.87	28.57
CV-2549	9/18/2026 1:53:32 PM	-1.58	-1.54	10.5	9.9	2.398	2.168	-25.36	-21.05	28.56
CV-2550	9/1/2026 1:08:00 PM									
CV-2550	9/1/2026 1:08:00 PM									
CV-2550	9/1/2026 1:09:01 PM	-13.84	-13.61			14.087	13.760	-14.54	-14.44	28.54
CV-2550	9/9/2026 1:03:44 PM	-12.83	-12.38			13.009	12.414	-13.58	-11.53	28.56
CV-2550	9/9/2026 1:05:00 PM									
CV-2550	9/16/2026 9:45:27 AM	-4.40	-4.22			4.430	4.347	-4.37	-4.36	28.59
CV-2550	9/16/2026 9:48:00 AM									
CV-2550	9/23/2026 9:05:00 AM									
CV-2550	9/23/2026 9:06:42 AM	-13.49	-13.48			13.841	13.705	-14.07	-14.11	28.48
CV-2550	9/30/2026 8:10:00 AM									
CV-2550	9/30/2026 8:13:11 AM	-9.11	-8.55			9.247	8.644	-10.02	-9.64	28.42
CV-2551	9/1/2026 9:06:00 AM									
CV-2551	9/1/2026 9:06:00 AM									
CV-2551	9/9/2026 10:15:15 AM	-4.82	-4.90			0.000	0.000	0.67	0.67	28.63
CV-2551	9/9/2026 10:25:00 AM									
CV-2551	9/15/2026 1:29:53 PM	-5.40	-5.05			5.671	5.234	-8.13	-7.41	28.49
CV-2551	9/15/2026 1:30:00 PM									
CV-2551	9/22/2026 2:05:45 PM	-4.43	-4.33			4.360	4.390	-6.30	-6.23	28.44
CV-2551	9/22/2026 2:07:00 PM									
CV-2551	9/29/2026 1:30:00 PM									

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2551	9/29/2026 1:30:09 PM	-4.57	-4.49			4.665	4.453	-6.15	-7.00	28.28
CV-2552	9/1/2026 1:12:06 PM	-14.89	-14.20			15.020	14.372	0.00	0.00	28.57
CV-2552	9/1/2026 1:16:00 PM									
CV-2552	9/1/2026 1:16:00 PM									
CV-2552	9/9/2026 1:16:00 PM									
CV-2552	9/9/2026 1:17:03 PM	-8.21	-8.42			8.227	8.580	0.00	0.00	28.57
CV-2552	9/16/2026 8:55:00 AM									
CV-2552	9/16/2026 8:55:21 AM	-4.84	-4.77			4.845	4.790	0.00	0.00	28.57
CV-2552	9/23/2026 9:14:44 AM	-13.42	-13.14			13.773	13.624	0.04	0.04	28.49
CV-2552	9/23/2026 9:15:00 AM									
CV-2552	9/30/2026 8:15:00 AM									
CV-2552	9/30/2026 8:27:07 AM	-11.80	-11.79			12.086	12.068	0.08	0.08	28.42
CV-2553	9/2/2026 9:50:00 AM	-3.02	-2.47			3.027	2.471	-11.09	-10.76	28.64
CV-2553	9/17/2026 10:55:57 AM	-3.03	-1.84			3.030	1.822	-10.97	-11.31	28.71
CV-2554	9/1/2026 2:17:21 PM	-6.31	-6.23			0.335	0.262	0.00	0.00	28.58
CV-2554	9/1/2026 2:20:00 PM									
CV-2554	9/1/2026 2:20:00 PM									
CV-2554	9/10/2026 8:49:04 AM	-6.55	-6.45			6.812	6.768	-6.74	-6.76	28.57
CV-2554	9/10/2026 8:51:00 AM									
CV-2554	9/16/2026 10:15:07 AM	-4.73	-4.63			5.146	5.016	-5.06	-4.84	28.64
CV-2554	9/16/2026 10:17:00 AM									
CV-2554	9/23/2026 10:20:05 AM	-10.78	-10.78			11.262	11.311	-10.93	-11.07	28.51
CV-2554	9/23/2026 10:25:00 AM									
CV-2554	9/30/2026 9:20:33 AM	-10.37	-10.13			10.745	10.694	-10.37	-10.36	28.47
CV-2554	9/30/2026 9:30:00 AM									
CV-2555	9/14/2026 10:19:23 AM	-3.92	-3.88	64.8	64.8	3.798	3.791			28.48
CV-2555	9/21/2026 2:31:09 PM	-3.41	-2.69			0.000	0.000	-7.80	-7.69	28.48
CV-2556-PLR	9/1/2026 1:23:16 PM	-0.29	-0.25			0.300	0.269	0.17	0.17	28.58
CV-2556-PLR	9/1/2026 1:29:00 PM									

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2556-PLR	9/1/2026 1:29:00 PM									
CV-2556-PLR	9/9/2026 1:31:40 PM	-0.35	-0.33			0.263	0.308	0.00	0.00	28.6
CV-2556-PLR	9/9/2026 1:37:00 PM									
CV-2556-PLR	9/16/2026 9:12:40 AM	0.26	0.29			0.000	0.000	0.00	0.04	28.6
CV-2556-PLR	9/16/2026 9:18:00 AM									
CV-2556-PLR	9/16/2026 9:20:48 AM	0.31	-1.40			0.000	1.380	-4.55	-4.51	28.6
CV-2556-PLR	9/16/2026 9:21:53 AM	-1.53	-1.53			1.519	1.537	-4.58	-4.63	28.6
CV-2556-PLR	9/23/2026 9:27:28 AM	-5.76	-5.76			6.258	6.258	-12.63	-12.63	28.49
CV-2556-PLR	9/23/2026 9:30:00 AM									
CV-2556-PLR	9/30/2026 8:45:00 AM									
CV-2556-PLR	9/30/2026 8:45:01 AM	-5.44	-5.43			5.872	5.878	-11.09	-11.16	28.46
CV-2557	9/15/2026 8:51:14 AM	-6.73	-6.66	0.0	0.0	6.647	6.574	-10.59		28.51
CV-2557	9/15/2026 8:52:00 AM	-6.55	-6.55	0.0	0.0	6.545	6.549	-10.56		28.51
CV-2557	9/22/2026 10:25:41 AM	-7.09	-5.41			7.429	5.761	-9.47	-10.02	28.52
CV-2558-PLR	9/1/2026 10:13:00 AM									
CV-2558-PLR	9/1/2026 10:13:00 AM									
CV-2558-PLR	9/1/2026 10:28:32 AM	1.35	1.32			0.000	0.000	0.67	0.59	28.58
CV-2558-PLR	9/9/2026 1:00:56 PM	4.91	5.43			0.000	0.000	8.04	6.49	28.62
CV-2558-PLR	9/9/2026 1:10:00 PM									
CV-2558-PLR	9/15/2026 2:10:00 PM									
CV-2558-PLR	9/15/2026 2:11:15 PM	3.61	3.00			0.000	0.000	0.13	0.21	28.49
CV-2558-PLR	9/23/2026 8:35:00 AM									
CV-2558-PLR	9/23/2026 8:42:47 AM	1.80	1.79			0.000	0.000	-0.03	-0.15	28.46
CV-2558-PLR	9/29/2026 2:05:00 PM									

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2558-PLR	9/29/2026 2:07:13 PM	1.00	1.05			0.000	0.000	-0.15	-0.15	28.27
CV-2559	9/14/2026 1:31:45 PM	-1.02	-0.79	0.0	0.0	-0.889	-0.591	-4.34		28.4
CV-2559	9/22/2026 9:49:02 AM	-1.39	-1.34			1.391	1.336	-4.63	-4.48	28.51
CV-2560	9/3/2026 9:21:28 AM	-0.24	-0.21			0.237	0.194	-6.40	-6.34	28.52
CV-2560	9/22/2026 10:49:07 AM	-1.05	-1.05			1.023	1.037	-9.82	-9.57	28.49
CV-2561	9/3/2026 9:41:08 AM	-0.49	-0.48			0.474	0.462	-3.49	-3.51	28.52
CV-2561	9/25/2026 2:14:35 PM	-0.22	-0.22			0.215	0.195	-2.12	-2.10	28.44
CV-2562	9/14/2026 1:42:18 PM	-0.17	-0.19	7.7	7.8	0.089	0.090	-3.07		28.4
CV-2563	9/23/2026 8:42:14 AM	-4.76	-4.11			0.183	0.076	-9.54	-9.74	28.6
CV-2564	9/1/2026 10:33:16 AM	-1.59	-1.00	0.0	0.0	1.561	0.962	-10.05		28.6
CV-2564	9/17/2026 10:06:15 AM	-4.47	-4.28			4.462	4.283	-11.41	-9.61	28.71
CV-2565	9/1/2026 11:35:08 AM	-0.20	-0.20	0.0	0.0	0.228	0.223	-10.53		28.62
CV-2565	9/4/2026 1:22:35 PM	-0.15	-0.28			0.141	0.267	-8.70	-8.70	28.57
CV-2565	9/30/2026 11:33:22 AM	-0.18	-0.18			0.174	0.174	-3.29	-3.31	28.55
CV-2566	9/1/2026 11:33:06 AM	-2.56	-2.56	0.0	0.0	2.656	2.647	-9.58		28.62
CV-2566	9/21/2026 11:57:56 AM	-3.25	-3.04			3.191	2.988	-10.81	-10.81	28.67
CV-2567	9/1/2026 1:52:22 PM	-1.52	-1.52	0.0	0.0	1.548	1.545	-9.22		28.58
CV-2567	9/21/2026 12:33:36 PM	-2.42	-2.41			2.377	2.364	-10.81	-10.60	28.65
CV-2568	9/1/2026 2:47:30 PM	-2.83	-2.84	0.0	0.0	2.876	2.777	-5.30		28.56
CV-2568	9/3/2026 11:10:53 AM	-2.16	-2.36			2.184	2.363	-6.01	-5.97	28.58
CV-2568	9/22/2026 3:09:14 PM	-0.50	-0.51			0.506	0.511	-9.01	-8.88	28.44
CV-2569	9/1/2026 2:37:13 PM	-0.16	-0.16	0.0	0.0	0.227	0.211	-5.30		28.57
CV-2569	9/24/2026 12:16:37 PM	-1.64	-1.64			1.610	1.611	-10.08	-10.07	28.63
CV-2570	9/1/2026 2:13:36 PM	-0.71	-0.69	0.0	0.0	0.618	0.613	-5.46		28.58
CV-2570	9/30/2026 1:55:05 PM	-0.16	-0.15			0.155	0.152	-3.61	-3.24	28.52
CV-2571	9/2/2026 10:53:10 AM	-9.07	-9.31	27.8	29.6	2.037	2.320	-14.26	-14.11	28.93
CV-2572	9/30/2026 10:38:28 AM	-0.31	-0.30	27.6	27.1	0.992	0.961	-1.23	-1.14	28.67
CV-2602	9/28/2026 9:13:58 AM	-4.86	-4.73	57.7	55.2	4.339	3.980	-10.40	-9.74	28.67
CV-2603	9/17/2026 1:31:00 PM	-1.43	-1.38	19.7	19.5	8.291	8.139	-13.26	-13.06	28.91
CV-2603	9/17/2026 1:35:30 PM	-1.99	-1.69	29.0	23.1	1.956	1.238	-13.61	-13.32	28.91
CV-2603	9/17/2026 1:37:32 PM	-1.63	-1.60	22.6	22.1	1.190	1.138	-12.51	-12.51	28.9
CV-2605	9/30/2026 9:04:23 AM	-0.28	-0.28	5.9	6.2	0.753	0.816	-1.36	-1.36	28.71

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2606	9/17/2026 1:17:22 PM	-0.94	-0.92	14.1	14.1	4.252	4.239	-15.62	-15.39	28.91
CV-2606	9/17/2026 1:22:30 PM	-1.05	-1.10	15.3	16.1	0.545	0.605	-15.48	-15.53	28.91
CV-2606	9/17/2026 1:24:50 PM	-1.13	-1.13	15.7	15.9	0.570	0.585	-15.18	-16.15	28.91
CV-2608	9/21/2026 9:33:42 AM	1.08	0.41	1.0	9.0	0.018	1.695	-6.55	-6.59	28.79
CV-2608	9/21/2026 9:44:28 AM	0.25	-0.10	9.1	14.8	0.190	0.509	-6.05	-6.19	28.79
CV-2610	9/9/2026 10:26:51 AM	-0.79	-0.94	16.6	20.5	1.732	2.652	-13.13	-12.99	28.87
CV-2610	9/9/2026 10:27:56 AM	-1.02	-1.02	20.0	20.3	2.525	2.611	-10.93	-12.33	28.86
CV-2611	9/25/2026 8:33:59 AM	0.82	-0.25	4.3	10.2	0.376	2.128	-13.83	-12.67	28.76
CV-2611	9/25/2026 8:35:07 AM	-0.50	-0.51	10.1	10.3	2.094	2.158	-13.24	-13.34	28.79
CV-2612	9/23/2026 10:24:54 AM	0.86	0.88	2.9	2.6	0.023	0.018	1.00	1.00	28.62
CV-2613	9/23/2026 9:13:04 AM	0.05		7.5		1.150		-16.74		28.6
CV-2613	9/23/2026 9:20:54 AM	0.03	-0.16	7.2	14.8	0.117	0.501	-14.92	-11.74	28.6
CV-2613	9/23/2026 9:28:02 AM	-0.19	-0.19	15.4	15.1	0.541	0.521	-11.95	-11.41	28.6
CV-2613	9/23/2026 9:45:38 AM	-0.17	-0.16	15.6	15.4	0.553	0.538	-13.27	-12.92	28.61
CV-2614	9/21/2026 12:45:34 PM	0.57	0.54	9.7	10.8	2.026	2.467	-17.54	-16.66	28.65
CV-2614	9/21/2026 12:51:30 PM	0.51	-0.43	3.2	8.7	0.222	1.608	-15.28	-16.87	28.68
CV-2614	9/21/2026 12:53:19 PM	-0.54	-0.57	8.6	8.7	1.577	1.635	-16.72	-17.33	28.67
CV-2615	9/21/2026 12:14:18 PM	-0.51	-0.51	27.4	27.5	0.962	0.964	-10.71	-10.51	28.61
CV-2615	9/21/2026 12:17:00 PM	-0.51	-0.43	27.5	20.4	0.965	0.531	-10.74	-10.97	28.61
CV-2615	9/21/2026 12:18:55 PM	-0.41	-0.40	19.7	20.0	0.493	0.507	-10.47	-10.68	28.62
CV-2627	9/11/2026 8:23:45 AM	-0.41	-0.85	7.5	9.5	0.350	0.568	-4.52	-4.06	28.69
CV-2634	9/4/2026 7:30:48 AM	-1.74	-1.80	13.9	14.3	3.753	3.965	-1.64	-1.74	28.64
CV-2634	9/11/2026 8:16:30 AM	-3.70	-3.78	16.3	16.4	5.380	5.469	-3.86	-3.92	28.67
CV-2634	9/23/2026 1:07:00 PM	0.33	0.21	3.5	4.4	0.258	0.405	0.64	0.50	28.7

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2634	9/24/2026 2:13:35 PM									
CV-2634	9/24/2026 2:14:26 PM	-6.61	-6.36	0.8	0.8	0.014	0.014	-6.79	-6.56	28.68
CV-2634	9/24/2026 2:25:00 PM									
CV-2634	9/24/2026 2:25:00 PM									
CV-2634	9/24/2026 2:58:48 PM									
CV-2634	9/24/2026 2:58:48 PM									
CV-2634	9/24/2026 2:58:48 PM									
CV-2638	9/27/2026 11:47:09 AM	-12.40	-12.76	1.7	1.3	0.059	0.034	-13.45	-13.33	28.53
CV-2663	9/28/2026 1:50:21 PM	-0.26	-0.27	8.0	11.4	0.086	0.178	-13.37	-16.86	28.37
CV-2676	9/1/2026 8:50:09 AM	-0.17	-0.17			0.157	0.162	-16.48	-16.80	28.63
CV-2680	9/16/2026 11:27:44 AM	-6.00	-4.59	26.3	34.7	4.571	7.828	-24.33	-24.14	28.78
CV-2680	9/16/2026 11:30:13 AM	-4.63	-4.63	8.5	8.4	8.106	7.987	-24.10	-24.04	28.78
CV-2680	9/22/2026 2:55:28 PM	-2.22	-2.02	17.4	16.2	6.627	5.686	-19.10		28.52
CV-2681	9/22/2026 3:00:45 PM	1.01	-0.46		19.6	-0.697	0.391			28.52
CV-2681	9/22/2026 3:01:29 PM	-0.37	-0.36	20.8	20.8	0.443	0.444			28.52
CV-2683	9/22/2026 3:21:53 PM	-6.45	-5.76	5.4	4.7	0.032	0.024			28.52
CV-2684	9/28/2026 2:31:31 PM	-13.86	-8.97	69.0	56.9	13.930	9.115	-19.07	-20.96	28.42
CV-2687	9/9/2026 1:20:38 PM	-2.23	-2.23	0.9	0.9	0.019	0.018	-18.36	-19.13	28.75
CV-2688	9/4/2026 8:25:47 AM	1.22	-0.71	5.6	12.7	0.196	1.030	-13.01	-18.08	28.68
CV-2688	9/18/2026 3:17:08 PM	-4.37	-2.37	13.1	8.2	1.110	0.433	-20.35	-20.61	28.71
CV-2689	9/28/2026 3:05:38 PM	-9.39	-9.38			9.479	9.479	-13.72	-13.80	28.45
CV-2689	9/30/2026 11:55:35 AM									
CV-2689	9/30/2026 11:59:55 AM	-4.98	-9.18			5.093	9.278	-9.56	-9.14	28.56
CV-2689	9/30/2026 12:01:28 PM	-9.55	-9.58			9.630	9.708	-9.54	-9.64	28.57
CV-2690	9/4/2026 8:32:48 AM	-16.79	-17.12	3.6	3.6	0.286	0.292	-21.32	-21.12	28.68
CV-2691	9/28/2026 7:44:15 AM	-3.50	-3.65	17.5	19.1	1.997	2.379	-20.67	-20.81	28.63
CV-2692	9/4/2026 7:43:29 AM	1.05	-0.39	26.7	36.1	0.935	1.715	-16.09	-13.52	28.67
CV-2692	9/18/2026 3:35:46 PM	-2.75	-2.72	35.3	35.5	1.648	1.673	-13.36	-13.59	28.71

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
CV-2695	9/16/2026 1:56:22 PM	-0.71	-0.72	11.9	12.8	0.897	1.028	-20.75	-19.37	28.77
CV-2695	9/16/2026 2:05:21 PM	-0.87	-1.44	6.3	9.3	0.247	0.542	-21.48	-19.94	28.76
CV-2695	9/16/2026 2:07:07 PM	-1.53	-1.49	9.6	9.0	0.575	0.507	-21.66	-19.08	28.77
CV-48R	9/23/2026 8:32:14 AM	-7.38	-8.04	4.8	4.5	0.148	0.133	-9.72	-9.61	28.59
CV-52D	9/22/2026 2:41:30 PM	-6.74	-6.73	1.2	1.2	0.435	0.434	-18.63		28.5
CV-55R	9/2/2026 2:12:41 PM	-4.85	-4.87	4.2	2.9	0.120	0.057	-11.93	-12.04	28.64
CV-55R	9/2/2026 2:15:00 PM									
CV-55R	9/2/2026 2:15:00 PM									
CV-55R	9/10/2026 9:19:10 AM	-5.23	-5.21	4.5	3.8	0.140	0.100	-12.73	-12.97	28.64
CV-55R	9/10/2026 9:21:00 AM									
CV-55R	9/11/2026 9:33:09 AM	-5.63	-5.60	9.7	9.8	0.647	0.662	-14.41	-14.65	28.57
CV-55R	9/17/2026 10:30:20 AM	-7.45	-7.41	1.7	3.6	0.019	0.089	-19.71	-18.40	28.78
CV-55R	9/17/2026 10:33:00 AM									
CV-55R	9/24/2026 2:26:06 PM	-5.73	-5.73	5.5	4.8	0.209	0.158	-15.44	-15.26	28.54
CV-55R	9/24/2026 2:30:00 PM									
CV-56D	9/1/2026 8:36:44 AM	-3.10	-2.92	22.6	21.1	10.985	9.546	-16.72	-16.73	28.63
CV-56S	9/1/2026 8:31:46 AM	-3.53	-3.11	1.7	1.1	0.728	0.302	-16.84	-16.84	28.63
CV-57R	9/1/2026 10:13:04 AM	-0.58	-0.59	0.4	1.3	0.003	0.032	-12.78	-12.85	28.6
CV-79R	9/1/2026 9:35:58 AM	-8.88	-7.05	7.4	5.6	0.134	0.075	-16.74	-16.91	28.63
CV-79R	9/1/2026 9:37:09 AM	-5.28	-5.11	0.8	3.1	0.002	0.023	-16.78	-16.92	28.61
CV-94	9/22/2026 10:04:47 AM	-7.74	-7.74	1.3	1.5	0.011	0.013	-17.85		28.57
CV-95	9/1/2026 10:09:59 AM	-0.19	-0.18	1.0	0.7	0.018	0.011	-15.01	-15.15	28.6
CV-99	9/4/2026 7:05:00 AM									
CV-99	9/4/2026 7:05:00 AM									
CV-99	9/14/2026 9:15:48 AM	-9.69	-10.08	4.2	1.7	0.366	0.062	-9.91	-10.14	28.59
CV-99	9/14/2026 9:19:46 AM	-2.53	-2.53	2.6	2.7	0.139	0.144	-10.25	-10.45	28.58
CV-99	9/25/2026 10:42:18 AM	-0.47	-0.67	5.4	5.3	0.592	0.582	-12.91	-12.90	28.58
D-02	9/25/2026 9:39:15 AM	3.09	3.09	5.5	6.3	0.037	0.047	3.31	3.26	28.75

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
D-02	9/28/2026 12:45:58 PM	3.69	-15.39	3.7	2.9	0.016	0.011	3.78	-15.44	28.61
D-02	9/28/2026 12:48:09 PM	-15.36	-15.37	4.2	5.6	0.023	0.040	-15.41	-15.42	28.61
D-03	9/2/2026 10:11:51 AM	-0.76	-0.75	3.0	2.5	0.011	0.008	-0.78	-0.83	28.82
D-04	9/25/2026 9:43:51 AM	-21.01	-20.65	7.1	6.3	0.064	0.051	-20.28	-20.89	28.76
D-09	9/25/2026 8:39:40 AM	-10.91	-11.08	26.2	28.1	0.910	1.043	-12.04	-11.93	28.78
D-10	9/2/2026 10:47:58 AM	-13.15	-13.13	1.7	1.3	0.018	0.011	-14.52	-14.47	28.91
FP-001	9/9/2026 11:56:26 AM	-0.21	-0.19	8.0	8.0	0.401	0.405	-11.73	-11.30	28.63
FP-002	9/9/2026 11:59:58 AM	-0.14	-0.13	16.7	14.7	5.891	4.564	-6.78	-5.15	28.6
FP-003	9/9/2026 12:04:20 PM	-0.10	-0.09	2.3	2.3	0.572	0.571	-7.68	-7.46	28.63
FP-005	9/25/2026 10:01:13 AM	-0.91	-0.86	5.5	5.4	3.140	3.081	-9.87	-9.43	28.52
FP-006	9/9/2026 10:42:38 AM	-1.08	-1.07	0.6	1.0	0.008	0.019	-3.70	-4.06	28.64
FP-008	9/9/2026 10:51:01 AM	-2.08	-2.04	0.2	0.2	0.012	0.006	-5.55	-5.05	28.64
FP-009	9/9/2026 10:56:29 AM	-0.81	-0.81	3.6	3.4	0.278	0.249	-5.47	-5.51	28.62
FP-010	9/9/2026 11:00:51 AM	-0.57	-0.65	10.5	10.7	2.349	2.422	-5.36	-5.56	28.63
FP-011	9/9/2026 11:03:30 AM	-0.60	-0.67	2.3	2.6	0.107	0.141	-4.04	-5.43	28.63
FP-012	9/1/2026 11:45:24 AM	-0.17	-0.17	0.3	0.3	0.002	0.002	-11.02	-10.66	28.67
FP-013	9/1/2026 11:33:24 AM	-0.38	-0.38	13.5	13.5	3.700	3.698	-10.71	-10.72	28.67
FP-014	9/25/2026 10:20:20 AM	-3.28	-3.23	6.6	6.6	4.697	4.712	-7.83	-7.87	28.56
FP-015	9/9/2026 10:36:14 AM	-1.96	-1.97	0.6	0.7	0.008	0.009	-4.07	-4.38	28.64
FP-016	9/9/2026 10:39:37 AM	-1.03	-1.04	0.2	0.2	0.006	0.011	-4.14	-4.38	28.64
FP-017	9/14/2026 11:00:20 AM	-0.28	-0.27	0.4	0.4	0.003	0.003	-0.23		28.51
FP-018	9/1/2026 2:40:24 PM	-3.53	-3.37	7.4	6.7	1.135	0.928	-6.29	-6.30	28.56
FP-019	9/1/2026 2:44:17 PM	-0.33	-0.28	2.4	2.6	0.117	0.133	-6.46	-6.24	28.56
FP-020	9/14/2026 11:24:45 AM	-4.77	-4.77	2.7	2.7	0.145	0.145	-4.62		28.5
FP-021	9/14/2026 11:16:23 AM	-3.52	-3.54	6.1	6.0	0.790	0.788	-4.49		28.5
FP-022	9/14/2026 11:21:00 AM	-2.76	-2.76	0.8	0.8	0.014	0.014	-4.99		28.5
FP-023	9/3/2026 8:54:48 AM	-0.69	-0.69	5.7	5.7	0.654	0.653	-7.18	-7.15	28.63
FP-024	9/9/2026 11:18:04 AM	-0.32	-0.37	1.3	1.7	0.035	0.057	-4.84	-6.57	28.63
FP-025	9/14/2026 10:07:38 AM	-1.82	-1.81	0.0	0.0	-0.224	-0.224	-7.26		28.49
FP-026	9/14/2026 10:10:15 AM	-6.49	-6.49	0.0	0.0	-6.532	-6.536	-6.49		28.49
FP-027	9/14/2026 10:53:07 AM	-7.18	-7.16	0.0	0.0	-6.995	-7.134	-7.16		28.5
FP-027	9/14/2026 2:20:08 PM	-0.50	-0.50	5.0	5.0	6.377	6.496	-6.80	-6.84	28.47
FP-027	9/15/2026 10:17:45 AM	-0.64	-0.64	4.4	4.4	4.998	4.974	-5.02	-5.29	28.58
FP-028	9/14/2026 10:55:24 AM	-0.81	-0.79	2.5	2.5	0.122	0.122	-7.72		28.5
FP-028	9/15/2026 10:30:36 AM	-0.43	-0.35	7.0	2.1	5.033	0.471	-5.60	-5.17	28.58
FP-028	9/15/2026 10:31:51 AM	-0.34	-0.33	2.1	2.2	0.462	0.482	-5.13	-4.91	28.58
FP-029	9/14/2026 11:04:54 AM	-0.03	-0.06	0.0	0.0	-0.458	-0.648	-0.08		28.51

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
FP-029	9/15/2026 10:38:34 AM	-0.62	-0.52	12.5	11.1	3.155	2.497	-4.51	-5.26	28.58
FP-030	9/1/2026 2:31:04 PM	-0.47	-0.45	10.2	10.4	2.126	2.182	-6.36	-6.50	28.56
FP-031	9/1/2026 2:28:03 PM	-1.14	-1.30	0.2	0.6	0.012	0.089	-6.57	-6.24	28.56
FP-031	9/15/2026 10:39:37 AM	-0.50	-0.50	10.7	11.1	2.310	2.489	-4.95	-5.08	28.58
FP-032	9/1/2026 2:20:55 PM	-1.97	-1.60	3.9	2.1	1.604	0.476	-6.75	-6.50	28.56
FP-033	9/1/2026 2:17:52 PM	-0.57	-0.55	0.7	0.8	0.010	0.014	-3.47	-3.24	28.54
FP-034	9/1/2026 2:13:58 PM	-0.07	-0.06	4.6	4.6	0.436	0.441	-6.50	-6.10	28.53
FP-035	9/1/2026 1:47:39 PM	-1.38	-1.36	4.2	5.1	0.365	0.519	-6.52	-6.64	28.53
FP-036	9/14/2026 9:56:48 AM	-1.05	-1.06	2.0	2.1	1.052	1.115	-6.66	-6.81	28.45
FP-037	9/1/2026 1:35:51 PM	-0.36	-0.36			0.000	0.000	-6.76	-6.66	28.53
FP-038	9/14/2026 1:57:24 PM	-0.59	-0.59	41.7	41.7	1.953	1.957	-5.97		28.46
FP-038	9/23/2026 10:03:41 AM	-1.96	-1.73	1.2	2.7	0.029	0.151	-7.74	-8.52	28.56
FP-039	9/14/2026 1:59:50 PM	-0.63	-0.61	18.6	19.0	6.412	6.751	-5.67		28.47
FP-040	9/23/2026 10:00:51 AM	-1.54	-1.49			0.000	0.000	-7.16	-7.50	28.54
FP-041	9/2/2026 7:45:38 AM	-0.30	-0.29	7.1	7.4	1.022	1.114	-4.78		28.69
FP-042	9/2/2026 8:11:34 AM	-0.17	-0.17	11.5	11.1	2.764	2.557	-3.32		28.71
FP-043	9/2/2026 7:48:43 AM	-0.34	-0.33	26.0	26.0	4.205	4.203	-5.82		28.68
FP-044	9/2/2026 7:51:27 AM	-0.21	-0.21	5.6	5.6	0.590	0.590	-6.15		28.68
FP-045	9/2/2026 1:12:15 PM	-0.37	-0.05	13.4	0.3	3.645	0.001	-8.36	-8.48	28.67
FP-046	9/25/2026 10:05:05 AM	-1.35	-1.34	16.5	16.6	5.589	5.667	-8.96	-9.07	28.54
FP-047	9/29/2026 8:20:44 AM	-0.11	-0.11	1.4	1.5	0.040	0.044	-0.21	-0.21	28.35
FP-050	9/2/2026 2:22:59 PM	-0.03	-0.02	6.2	6.3	0.235	0.242	-6.16	-6.89	28.55
FP-051	9/2/2026 2:17:15 PM	-0.09	-0.10	25.3	25.8	0.802	0.834	-4.55	-4.66	28.56
FP-052	9/2/2026 1:33:27 PM	-0.04	-0.04	14.0	14.1	1.192	1.220	-6.32	-6.38	28.59
FP-053	9/2/2026 1:27:21 PM	-0.15	-0.14	2.5	2.4	0.123	0.118	-9.34	-8.94	28.56
FP-054	9/1/2026 9:06:16 AM	-4.34	-4.33			4.310	4.314	-11.08	-11.22	28.57
FP-054	9/2/2026 2:06:03 PM	-0.09	-0.05			0.000	0.000	-3.55	-3.48	28.53
FP-055	9/28/2026 10:39:01 AM	-0.25	-0.25	8.8	8.6	1.594	1.523	-12.12	-11.82	28.43
FP-056	9/2/2026 9:03:40 AM	-0.14	-0.14	3.5	3.5	3.029	3.078	-11.89	-11.83	28.61
FP-057	9/3/2026 12:59:26 PM	-0.97	-0.89	21.6	20.0	9.728	8.307	-19.92	-17.23	28.46
FP-058	9/3/2026 12:56:21 PM	-0.60	-0.57	9.1	8.4	1.683	1.441	-18.79	-16.02	28.46
FP-059	9/14/2026 1:04:23 PM	-0.75	-0.75	13.2	13.2	3.387	3.387	-21.45		28.42
FP-060	9/28/2026 10:03:13 AM	-0.24	-0.25	4.8	4.8	0.465	0.459	-13.90	-13.92	28.41
FP-061	9/9/2026 10:33:21 AM	-2.08		1.1		0.023		-4.40		28.64
FP-062	9/10/2026 12:04:52 PM	-3.32	-3.16	6.8	4.6	0.063	0.028	-3.30	-3.09	28.71
FP-063	9/10/2026 12:09:15 PM	-3.85	-3.78	1.9	1.5	0.024	0.015	-3.77	-3.85	28.71
FP-064	9/14/2026 12:54:05 PM	0.00	-0.08	2.8	7.5	0.010	0.071	-18.32	-18.16	28.44
FP-064	9/14/2026 12:58:32 PM	-0.07	-0.07	6.2	6.3	0.048	0.049	-18.29	-18.20	28.44

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
FP-064	9/15/2026 9:47:50 AM	-0.43	-0.44	18.6	18.3	0.428	0.415	-20.38	-20.30	28.55
FP-065	9/14/2026 1:10:28 PM	-0.01	-0.08	1.5	9.0	0.015	0.506	-17.75	-17.45	28.46
FP-065	9/15/2026 9:51:40 AM	-0.32	-0.32	7.2	7.1	0.314	0.310	-19.06	-18.87	28.55
FP-066	9/14/2026 1:20:35 PM	-0.06	-0.07	8.2	8.2	1.289	1.291	-15.94		28.41
FP-066	9/15/2026 9:55:34 AM	-0.40	-0.41	4.4	4.4	0.394	0.384	-17.83	-18.25	28.55
H-01 (EXP-01	9/3/2026 12:08:43 PM	-4.17	-4.18			4.099	4.116	-15.20	-14.75	28.74
H-01 (EXP-01	9/30/2026 2:26:54 PM	-3.14	-3.13			3.207	3.234	-14.32	-13.88	28.53
H-02 (EXP-02	9/3/2026 12:33:02 PM	-5.04	-5.04			5.211	5.199	-14.80	-14.98	28.74
H-02 (EXP-02	9/30/2026 2:29:31 PM	-5.79	-5.62			5.834	5.807	-14.20	-14.26	28.53
H-03 (EXP-03	9/3/2026 12:29:22 PM	-13.87	-11.75			14.070	11.859	-14.22	-14.88	28.74
H-03 (EXP-03	9/30/2026 2:35:08 PM	-11.33	-11.33			11.407	11.398	-13.62	-13.80	28.53
H-04 (EXP-04	9/3/2026 12:23:09 PM	-11.81	-5.71			12.043	5.809	-14.70	-14.68	28.74
H-04 (EXP-04	9/3/2026 12:24:20 PM	-4.80	-4.79			4.952	4.937	-14.93	-14.77	28.74
H-04 (EXP-04	9/30/2026 2:38:36 PM	1.37	-0.04			0.000	0.022	-13.23	-13.04	28.53
H-04 (EXP-04	9/30/2026 2:40:29 PM	-8.75	-8.98			8.881	9.017	-11.97	-12.08	28.53
H-08 (EXP-08	9/14/2026 8:50:48 AM	-13.52	-13.46			13.828	13.800	-16.01	-15.87	28.6
H-08 (EXP-08	9/29/2026 8:40:38 AM	-15.14	-15.48			15.290	15.683	-18.22	-18.23	28.45
H-08 (EXP-08	9/29/2026 8:42:05 AM	-15.69	-15.48			15.840	15.798	-18.26	-18.16	28.44
H-10 (EXP-10	9/15/2026 8:07:00 AM	-16.45	-16.49			16.378	16.420	-13.70	-13.73	28.59
H-10 (EXP-10	9/15/2026 8:11:28 AM	-16.28	-16.27			16.313	16.296	-14.50	-14.51	28.59
H-10 (EXP-10	9/29/2026 8:30:20 AM	-16.22	-15.15			16.419	15.280	-15.98	-15.98	28.42
H-10 (EXP-10	9/29/2026 8:32:34 AM	-14.47	-14.31			14.558	14.427	-15.78	-15.65	28.42
H-1404C	9/15/2026 9:34:05 AM	-1.72	-1.76	3.1	3.1	1.105	1.089	-10.62	-11.82	28.54
H-1404C	9/15/2026 9:38:51 AM	-1.69	-1.68	4.1	3.2	1.956	1.155	-10.80	-10.77	28.56
H-1404C	9/16/2026 10:35:00 AM									
H-1404C	9/16/2026 12:54:05 PM	-1.26	-1.24	7.7	6.0	1.315	0.814	-11.40	-11.82	28.6
H-1404C	9/16/2026 1:34:20 PM	-0.95	-0.59	4.5	0.2	2.307	0.003	-10.22	-10.22	28.61
H-1404C	9/16/2026 1:40:19 PM	-0.56	-0.56	0.6	0.7	0.041	0.048	-11.07	-11.36	28.61
H-1405C	9/1/2026 9:32:25 AM	-0.16	-0.16	1.2	1.0	0.010	0.007	-0.04		28.64
H-1405C	9/22/2026 11:58:24 AM	-0.11	-0.10	0.0	0.0	-0.189	-0.189	-0.08		28.58

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
H-1405C	9/22/2026 11:59:05 AM	-0.11	-0.10	0.0	0.0	-0.179	-0.179	-0.09		28.58
H-1406W	9/2/2026 8:36:20 AM	-9.94	-3.86	1.8	2.3	0.022	0.036	-10.45		28.71
H-1406W	9/4/2026 1:49:40 PM	-8.18	-8.33	0.1	0.4	0.000	0.001	-8.40	-8.33	28.64
H-1406W	9/10/2026 10:32:49 AM	-1.56	-1.94	0.5	0.7	0.002	0.003	-1.45	-1.69	28.7
H-1406W	9/23/2026 8:53:49 AM	-5.40	-5.40	2.2	2.5	0.029	0.038	-5.52	-5.71	28.6
H-1408CR	9/23/2026 12:53:30 PM	-0.22	-0.27	6.9	8.3	0.304	0.442	-9.57	-11.95	28.59
H-1408E	9/14/2026 2:12:45 PM	-0.30	-0.30	7.0	7.0	0.305	0.308	-7.49	-7.83	28.37
H-1408E	9/21/2026 10:04:50 AM	-0.59	-1.25	7.0	5.8	0.312	0.218	-9.59	-9.11	28.52
H-1408W	9/2/2026 9:01:18 AM	-0.24	-0.21	0.6	1.1	0.000	0.001	-12.71		28.71
H-1409N	9/1/2026 2:27:54 PM	-0.41	-0.41	0.7	0.7	0.111	0.111	-3.83		28.55
H-1409N	9/21/2026 9:11:22 AM	-1.22	-1.31	1.3	1.2	0.432	0.400	-9.97	-9.36	28.55
H-1410S	9/25/2026 9:05:52 AM	-8.70	-8.69	2.0	2.5	0.005	0.008	-9.29	-9.20	28.7
H-1563N	9/14/2026 2:12:22 PM	-2.51	-2.51	6.6	6.7	0.263	0.267	-6.05		28.46
H-1563N	9/17/2026 10:33:10 AM	-3.61	-2.51	3.5	5.0	0.078	0.161	-8.47	-8.32	28.71
H-1563S	9/1/2026 9:35:22 AM	-0.45	-0.44	0.4	0.4	0.016	0.019	-0.44		28.63
H-1563S	9/22/2026 12:03:36 PM	-0.24	-0.21	0.9	0.3	0.090	0.013	-9.63		28.55
H-1565E	9/14/2026 2:16:08 PM	-0.07	-0.07	2.3	2.4	0.032	0.036	-3.03	-2.96	28.37
H-1565E	9/21/2026 10:11:59 AM	-0.23	-0.24	0.7	1.3	0.003	0.011	-4.00	-4.28	28.52
H-1568N	9/14/2026 2:10:12 PM	-0.90	-0.86	17.4	18.0	6.525	6.939	-8.35	-7.89	28.37
H-1568N	9/21/2026 9:57:33 AM	-1.29	-1.28	19.5	19.4	8.181	8.045	-9.71	-9.50	28.52
H-1571S	9/24/2026 10:55:12 AM	-2.35	-2.37	5.0	4.3	0.055	0.042	-13.67	-13.38	28.59
H-1572N	9/22/2026 10:24:00 AM	-0.22	-0.21	0.7	0.7	0.010	0.009	-22.00		28.55
H-1572S	9/24/2026 10:40:13 AM	-0.03	-0.04	2.2	2.1	0.011	0.010	-13.67	-13.65	28.62
H-1753N	9/1/2026 2:48:08 PM	-1.32	-1.30	2.0	2.0	0.009	0.009	-6.45	-6.37	28.56
H-1753N	9/24/2026 11:34:35 AM	-1.25	-1.06	6.0	11.4	0.079	0.289	-11.98	-11.00	28.63
H-1753N	9/24/2026 11:36:18 AM	-1.03	-1.04	1.0	1.1	0.272	0.281	-10.78	-10.83	28.63
H-1753S	9/14/2026 1:54:43 PM	-1.25	-1.23	8.3	8.3	0.143	0.143	-5.86		28.45
H-1753S	9/17/2026 10:36:17 AM	-2.04	-1.30	2.2	1.0	0.098	0.019	-8.80	-8.31	28.71
H-1756S	9/2/2026 7:25:00 AM	-0.60	-0.46	11.5	5.7	0.155	0.039	-7.97		28.66

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
H-1756S	9/22/2026 11:27:30 AM	-1.76	-0.56	43.8	19.0	2.444	0.456	-8.40		28.61
H-1757S	9/1/2026 9:27:22 AM	-0.64	-0.66	5.8	5.8	0.075	0.074	-10.65		28.63
H-1757S	9/22/2026 11:41:50 AM	-1.66	-1.45	5.3	0.0	0.066	-0.202	-9.30		28.58
H-1760S	9/14/2026 1:52:17 PM	-1.47	-1.42	5.3	4.9	0.179	0.156	-11.15	-10.23	28.38
H-1760S	9/21/2026 9:25:24 AM	-1.84	-1.87	5.2	5.4	0.174	0.184	-11.06	-11.76	28.55
H-1762N	9/13/2026 1:22:53 PM	-0.25	-0.31	5.7	6.9	0.685	1.006	-7.42	-7.85	28.46
H-1762N	9/13/2026 1:24:07 PM	-0.34	-0.31	6.8	6.8	0.992	0.966	-7.88	-7.52	28.45
H-1762N	9/21/2026 8:20:33 AM	-0.40	-0.39	6.6	7.2	0.926	1.077	-8.87	-8.69	28.51
H-1763N	9/14/2026 1:09:46 PM	-1.46	-1.47	28.7	28.9	5.380	5.449	-22.89	-23.34	28.37
H-1763N	9/24/2026 2:03:05 PM	-0.82	-0.75	20.4	20.3	2.693	2.680	-11.22	-10.82	28.45
H-1763S	9/9/2026 1:49:39 PM	-1.62	-1.54	32.1	30.9	1.310	1.567	-7.16		28.62
H-1764N	9/9/2026 1:21:26 PM	-3.89	-2.67	13.4	6.5	1.114	0.261	-22.61		28.58
H-1764S	9/24/2026 11:03:44 AM	-9.00	-8.75	1.6	1.1	0.017	0.008	-13.77	-13.84	28.57
H-1767N	9/28/2026 3:02:56 PM	-1.19	-1.20	20.3	21.3	0.944	1.041	-19.62	-20.48	28.45
H-1769N	9/1/2026 11:12:33 AM	-0.39	-0.37	1.9	1.8	0.386	0.349	-6.95	-6.92	28.67
H-1769N	9/16/2026 12:33:55 PM	-0.39	-0.37	2.4	1.9	0.650	0.383	-7.50	-7.24	28.67
H-1769N	9/16/2026 12:34:48 PM	-0.38	-0.38	1.9	1.8	0.375	0.356	-7.38	-7.66	28.68
H-1770N	9/1/2026 11:22:05 AM	-1.01	-0.93	3.5	3.2	1.314	1.079	-10.45	-10.47	28.69
H-1770N	9/10/2026 9:10:00 AM									
H-1770N	9/10/2026 9:10:00 AM									
H-1770N	9/16/2026 2:50:15 PM	-1.43	-1.44	10.4	12.6	2.239	3.289	-11.97	-12.21	28.53
H-1770S	9/1/2026 9:20:12 AM	-0.40	-0.40	0.2	0.3	0.006	0.007	-9.52		28.63
H-1770S	9/24/2026 2:40:13 PM	-0.68	-0.58	0.3	1.5	0.002	0.045	-9.06	-8.80	28.49
H-1771A	9/10/2026 1:09:59 PM	-0.01	-0.03	9.0	9.4	0.511	0.556	-1.46	-1.34	28.49
H-1771B	9/3/2026 8:52:45 AM	-0.42	-0.42	1.3	1.5	0.036	0.047	-8.11	-7.91	28.52
H-1771B	9/22/2026 10:31:17 AM	-1.03	-1.04	1.4	1.5	0.040	0.044	-11.00	-10.66	28.49
H-1774N	9/10/2026 8:58:19 AM	-1.57	-1.09	40.8	29.4	2.174	1.125	-11.23	-11.24	28.67
H-1774N	9/16/2026 2:40:28 PM	-0.95	-0.94	8.1	8.1	1.380	1.392	-12.02	-12.12	28.56
H-1801S	9/1/2026 9:53:29 AM	-0.15	-0.17	1.0	0.8	0.022	0.012	-15.13	-15.17	28.6
H-1801S	9/1/2026 9:53:57 AM	-0.18	-0.17	0.5	0.5	0.005	0.005	-14.60	-14.85	28.6
H-1802S	9/22/2026 10:27:44 AM	-0.08	-0.21	6.8	20.5	0.054	0.490	-21.86		28.55
H-1803N-PLF	9/8/2026 10:07:00 AM									
H-1803N-PLF	9/8/2026 10:10:29 AM	-3.89	-3.65	50.5	48.8	3.828	3.563	0.24	0.25	28.61
H-1803N-PLF	9/14/2026 9:29:28 AM	-5.11	-5.10	60.5	57.4	5.547	4.990	0.33	0.34	28.49
H-1803N-PLF	9/14/2026 9:32:00 AM									

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
H-1803N-PLF	9/21/2026 9:40:35 AM	-7.19	-6.92	70.5	68.9	7.570	7.226	0.29	0.29	28.6
H-1803N-PLF	9/21/2026 9:41:00 AM									
H-1803N-PLF	9/28/2026 9:10:00 AM									
H-1803N-PLF	9/28/2026 9:16:43 AM	-8.14	-7.98	74.1	73.6	8.456	8.330	0.13	0.13	28.46
H-1804B	9/14/2026 1:13:24 PM	-17.18	-13.00	17.0	6.9	1.953	0.319	-19.67		28.41
H-1804N	9/25/2026 2:27:02 PM	-0.99	-0.66	10.5	10.8	2.394	2.547	-3.03	-3.41	28.47
H-1804S	9/9/2026 1:23:01 PM	-18.66	-14.27	17.9	13.2	2.056	1.112	-16.77		28.58
H-1805A	9/3/2026 1:50:46 PM	-2.14		2.0		0.005		-19.47		28.45
H-1805B	9/9/2026 1:05:06 PM	-0.65	-0.66	0.0	0.0	-0.009	-0.008	-20.25		28.58
H-1805S	9/9/2026 1:38:46 PM	-2.57	-1.89	8.4	1.2	0.159	0.003	-21.53		28.61
H-1805S	9/9/2026 1:39:27 PM	-1.54	-1.54	2.2	1.9	0.011	0.008	-21.21		28.61
H-1806A	9/3/2026 1:23:27 PM	-0.92	-0.84	23.8	18.1	1.326	0.766	-18.43	-18.65	28.48
H-1806B	9/22/2026 10:17:41 AM	-0.94	-0.93	1.2	1.2	0.028	0.027	-21.27		28.55
H-1806B	9/22/2026 10:19:58 AM	-0.92	-0.92	0.7	0.6	0.008	0.008	-21.73		28.55
H-1806N	9/10/2026 1:30:41 PM	-1.02	-1.03	12.5	12.3	0.205	0.200	-9.67	-9.19	28.5
H-1806S	9/1/2026 9:12:20 AM	-0.15	-0.15	12.8	12.3	0.382	0.357	-17.38	-17.04	28.67
H-1807A	9/22/2026 10:02:24 AM	-16.50	-16.50	0.0	0.0	-3.806	-2.827	-19.39		28.57
H-1807N	9/4/2026 9:28:29 AM	-1.07	-1.16	2.5	5.3	0.037	0.172	-11.28	-12.02	28.57
H-1807N	9/10/2026 1:36:04 PM	-0.46	-0.45	2.6	2.6	0.042	0.044	-9.27	-8.35	28.52
H-1807S	9/1/2026 10:29:44 AM	-4.52	-4.51	3.8	2.4	0.018	0.008	-14.95	-15.17	28.64
H-1952S	9/2/2026 1:24:38 PM	-1.66	-1.63	14.0	14.0	4.168	4.172	-9.38	-9.22	28.56
H-1952S	9/17/2026 2:50:32 PM	-1.68	-1.47	14.1	13.2	4.243	3.683	-9.63	-8.25	28.6
H-1955C	9/3/2026 1:54:00 PM	-0.61	-0.58	8.4	8.4	1.441	1.439	-22.84	-22.53	28.45
H-1955N	9/10/2026 1:18:23 PM	-0.38	-0.37	4.0	3.7	0.100	0.083	-2.11	-1.99	28.51
H-1956B	9/9/2026 12:56:13 PM	0.05	-0.57	0.0	8.4	-0.017	0.198	-1.18		28.59
H-1956B	9/9/2026 12:57:13 PM	-0.73	-0.73	7.1	7.3	0.144	0.150	-1.11		28.59
H-1956N	9/10/2026 1:26:20 PM	-1.99	-2.02	21.6	21.7	2.983	3.012	-4.53	-4.63	28.51
H-1956S	9/1/2026 9:27:26 AM	-16.18	-16.16	0.5	0.5	0.027	0.025	-16.94	-16.98	28.6
H-1957B	9/3/2026 1:15:00 PM	-0.31	-0.32	22.2	23.0	3.049	3.268	-19.62	-20.91	28.48
H-1957N	9/10/2026 1:33:26 PM	-0.47	-0.45	5.6	4.9	0.203	0.153	-9.65	-9.70	28.52
H-1957S	9/30/2026 9:45:11 AM	-22.12	-3.68	3.0	0.2	0.216	0.001	-22.84	-22.16	28.48
H-1957S	9/30/2026 9:54:00 AM	-0.24	-0.24	0.8	0.9	0.015	0.016	-21.14	-21.02	28.49

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
H-1957S	9/30/2026 2:08:10 PM	-0.73	-0.92	7.1	7.7	1.058	1.255	-18.27	-17.34	28.4
H-1958C	9/22/2026 9:58:48 AM	-1.10	-1.08	3.6	3.7	0.081	0.086	-20.18		28.59
H-1958N	9/10/2026 1:37:51 PM	-0.61	-0.58	22.0	21.7	0.628	0.608	-9.51	-9.07	28.52
H-1958S	9/1/2026 10:27:20 AM	-0.16	-0.25	4.8	2.9	0.138	0.051	-15.09	-15.15	28.63
H-1962N	9/1/2026 11:28:27 AM	-4.07	-3.19			3.984	3.116	-10.18	-10.79	28.68
H-1962N	9/1/2026 11:29:39 AM	-3.15	-3.14			3.068	3.062	-10.73	-10.62	28.69
H-1962N	9/16/2026 2:56:18 PM	-1.67	-1.51			1.641	1.445	-11.74	-11.84	28.52
H-1962N	9/16/2026 2:56:46 PM	-1.45	-1.45			1.437	1.438	-11.81	-11.81	28.52
H-1963N	9/1/2026 10:58:20 AM	-0.54	-0.24	3.1	3.6	0.013	0.018	-6.98	-6.91	28.65
H-1963N	9/1/2026 10:59:34 AM	-0.23	-0.23	4.3	4.3	0.026	0.025	-6.74	-6.79	28.67
H-1963N	9/16/2026 12:20:55 PM	-0.33	-0.34	2.3	2.8	0.007	0.010	-10.20	-10.16	28.67
H-1963N	9/16/2026 12:21:46 PM	-0.34	-0.34	2.3	2.4	0.007	0.008	-10.33	-10.35	28.68
H-1966N	9/10/2026 9:06:20 AM	-0.46	-0.45	9.0	8.7	1.689	1.572	-5.07	-4.74	28.67
H-1966N	9/16/2026 2:32:58 PM	-0.36	-0.38	4.4	4.4	2.113	2.096	-5.04	-5.39	28.53
H-1967E	9/2/2026 10:44:57 AM	-1.84	-0.93	6.0	4.7	0.046	0.027	-13.82	-13.68	28.89
H-1967W	9/2/2026 1:39:12 PM	-5.36	-5.36	57.2	58.6	3.641	3.819	-10.20		28.75
H-2050E	9/30/2026 9:51:30 AM	-1.45	-1.50	3.3	3.7	0.218	0.286	-1.32	-1.52	28.71
H-2050W	9/21/2026 2:03:14 PM	-0.76	-0.73	2.2	1.9	0.522	0.379	-4.76	-3.61	28.73
H-2050W	9/21/2026 2:07:51 PM	-0.90	-1.22	2.4	5.4	0.115	0.597	-4.87	-4.76	28.73
H-2050W	9/21/2026 2:09:57 PM	-1.20	-1.19	5.0	5.0	0.511	0.512	-4.25	-4.36	28.73
H-2051W	9/2/2026 1:36:38 PM	-11.25	-11.26	6.2	6.1	0.044	0.042	-11.32		28.76
H-2053E	9/2/2026 10:36:42 AM	-0.82	-1.05	12.3	13.9	0.194	0.250	-14.73	-14.87	28.9
H-2055E	9/15/2026 10:19:32 AM	-0.58	-0.55	1.8	0.8	0.020	0.004	-23.64	-23.35	28.64
H-2055E	9/24/2026 1:41:22 PM									
H-2055E	9/24/2026 1:42:43 PM	0.07	0.08	0.2	0.3	0.014	0.017	-13.09	-13.22	28.61
H-2055E	9/24/2026 1:45:00 PM									
H-2055E	9/24/2026 1:45:00 PM									
H-2055E	9/24/2026 2:52:19 PM									
H-2055E	9/28/2026 8:24:51 AM	-0.01	-0.75	0.2	1.5	0.015	0.535	-15.18	-14.70	28.52
H-2055E	9/28/2026 8:27:27 AM	-0.68	-0.68	1.4	1.4	0.513	0.506	-14.01	-13.36	28.53
H-2056B	9/30/2026 10:41:17 AM	-0.09	-0.11	4.6	2.2	0.450	0.098	-0.66	-1.56	28.67
H-2056W	9/2/2026 1:33:36 PM	-4.09	-4.67	81.1	76.9	7.330	6.611	-9.91		28.76
H-2057E	9/2/2026 10:33:09 AM	-9.61	-9.75	8.4	8.4	1.543	1.532	-13.87	-13.91	28.89
H-2058E	9/25/2026 8:43:12 AM	-6.02	-6.16	45.2	46.6	2.666	2.829	-9.56	-9.82	28.79
H-2058W	9/2/2026 1:31:18 PM	-2.90	-3.34	14.4	24.3	0.222	0.638	-10.62		28.77

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
H-2059E	9/25/2026 8:48:49 AM	-13.66	-13.81	4.8	5.6	0.491	0.691	-14.47	-14.84	28.74
H-2059W	9/2/2026 1:18:59 PM	-2.98	-3.50	55.9	57.0	3.637	3.793	-7.80		28.74
H-2161E	9/30/2026 4:18:18 PM	-4.48	-4.46	50.7	51.0	3.446	3.480	-14.70	-14.05	28.57
H-2161W	9/2/2026 1:15:54 PM	-4.88	-5.00	51.2	49.1	2.859	2.663	-6.70		28.75
H-2163C	9/15/2026 10:57:08 AM	-0.81	-0.81	1.1	1.1	0.124	0.134	-13.99	-14.22	28.67
H-2163C	9/21/2026 11:35:30 AM	-0.92	-0.92	0.5	0.5	0.071	0.070	-16.62	-16.82	28.67
H-2163W	9/2/2026 9:04:51 AM	-0.29	-0.16	8.3	8.2	0.393	0.392	-13.09		28.7
H-2163W	9/2/2026 9:05:57 AM	-0.38	-0.36	7.7	7.7	0.339	0.339	-14.04		28.7
H-2163W	9/22/2026 12:25:17 PM	-0.27	-0.27	16.8	17.8	1.905	2.148	-8.99		28.6
H-2164E	9/16/2026 3:11:14 PM	-2.49	-2.37	26.3	26.0	4.526	4.418	-19.17	-18.41	28.66
H-2164E	9/24/2026 1:20:04 PM									
H-2164E	9/24/2026 1:23:09 PM	-0.34	-0.34	1.9	0.9	0.022	0.006	-13.72	-13.48	28.63
H-2164E	9/24/2026 1:25:00 PM									
H-2164E	9/24/2026 1:25:00 PM									
H-2164E	9/24/2026 3:05:04 PM									
H-2165E	9/25/2026 9:23:57 AM	-3.38	-3.21	14.1	13.2	4.319	3.761	-8.61	-8.32	28.68
H-2165W	9/2/2026 8:43:14 AM	-0.88	-0.31	4.4	0.0	2.592	-0.116	-11.41		28.7
H-2165W	9/2/2026 8:45:08 AM	-0.10	-0.09	0.8	0.8	0.101	0.105	-10.85		28.7
H-2165W	9/9/2026 7:00:00 AM									
H-2165W	9/9/2026 7:00:00 AM									
H-2165W	9/23/2026 8:49:44 AM	-0.90	-0.92	6.4	6.3	0.272	0.265	-13.69	-14.55	28.59
H-2165W	9/30/2026 10:38:31 AM	-0.25	-1.32	7.8	40.2	0.407	10.981	-12.05	-13.26	28.58
H-2165W	9/30/2026 10:39:18 AM	-1.47	-1.42	39.2	38.4	10.445	10.005	-13.04	-13.48	28.58
H-2165W	9/30/2026 11:35:00 AM									
H-2166E	9/22/2026 10:33:01 AM	-0.73	-0.73	10.3	12.2	0.643	0.893	-13.80		28.54
H-2168C	9/1/2026 12:08:00 PM	-16.12	-15.55	25.8	24.1	0.857	0.747	-16.06	-15.74	28.67
H-2168E	9/22/2026 10:07:45 AM	-0.29	-0.29	4.4	4.4	0.113	0.113	-17.36		28.54
H-2169C	9/9/2026 1:00:48 PM	-15.93	-12.29	32.7	17.7	1.370	0.396	-19.61		28.58
H-2169E	9/22/2026 9:11:45 AM	0.07	-0.03	11.1	7.4	0.149	0.068	-21.81	-21.34	28.55
H-2169E	9/22/2026 9:12:40 AM	-0.05	-0.06	6.0	5.9	0.045	0.043	-20.67	-21.63	28.55
H-2169E	9/22/2026 10:14:12 AM	-0.11	-0.11	10.7	10.7	0.157	0.157	-21.57		28.54
H-2170N	9/25/2026 11:43:20 AM	-3.46	-3.28	27.6	25.2	4.942	4.121	-16.41	-16.39	28.67
H-2170S	9/21/2026 12:50:35 PM	-1.01	-1.65	0.6	2.8	0.003	0.049	-20.92	-20.97	28.67
H-2171A	9/29/2026 10:23:57 AM	-0.67	-0.68	3.1	3.2	0.996	1.115	-2.24	-2.29	28.46
H-2171B	9/21/2026 9:19:40 AM	-3.39	-3.40	15.4	15.3	1.532	1.502	-10.93	-11.27	28.67

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
H-2171N	9/29/2026 10:44:58 AM	-0.73	-0.76	7.6	6.9	0.363	0.305	-15.04	-14.89	28.45
H-2171S	9/25/2026 11:49:39 AM	-4.77	-4.74	48.0	47.0	15.243	14.601	-16.55	-16.66	28.69
H-2272W	9/2/2026 9:18:52 AM	-0.64	-0.63	24.0	25.9	3.672	4.308	-13.13		28.67
H-2272W	9/22/2026 12:19:10 PM	-0.41	-0.40	4.5	4.6	2.249	2.365	-9.93		28.57
H-2273W	9/2/2026 7:21:33 AM	-0.91	-0.70	5.6	5.5	0.209	0.204	-9.36		28.66
H-2273W	9/4/2026 8:32:00 AM									
H-2273W	9/4/2026 8:32:00 AM									
H-2273W	9/9/2026 7:10:00 AM									
H-2273W	9/9/2026 7:10:00 AM									
H-2273W	9/22/2026 12:09:18 PM	-0.30	-0.26	4.9	4.9	0.160	0.158	-9.85		28.56
H-2274B	9/1/2026 2:15:59 PM	-2.06	-2.15	4.7	6.9	0.055	0.119	-5.31		28.56
H-2274B	9/22/2026 2:38:09 PM	-3.97	-3.97	9.3	9.4	0.233	0.239	-9.02	-9.22	28.45
H-2274W	9/2/2026 7:28:33 AM	-0.58	-0.58	1.0	1.0	0.005	0.005	-7.73		28.66
H-2274W	9/22/2026 11:23:46 AM	-0.44	-0.44	0.0	0.0	-0.135	-0.134	-8.18		28.6
H-2275E	9/9/2026 1:51:36 PM	-0.28	-0.28	0.0	0.0	-0.015	-0.016	-4.39		28.61
H-2275W	9/1/2026 11:38:16 AM	-0.68	-0.63	30.1	30.0	5.825	5.801	-10.56		28.63
H-2275W	9/1/2026 11:39:55 AM	-0.64	-0.63	29.7	29.7	5.629	5.633	-10.55		28.63
H-2275W	9/1/2026 11:41:12 AM	-0.82	-0.78	28.9	28.9	5.330	5.335	-10.77		28.63
H-2275W	9/22/2026 12:53:21 PM	-0.59	-0.54	9.6	3.4	0.637	0.077	-9.28		28.54
H-2275W	9/22/2026 12:53:59 PM	-0.47	-0.48	5.5	5.6	0.204	0.205	-9.19		28.54
H-2276A	9/14/2026 1:55:11 PM	-1.39	-1.44	6.3	6.4	0.093	0.095	-7.74	-8.07	28.38
H-2276A	9/21/2026 9:31:10 AM	-1.79	-1.67	5.4	4.8	0.067	0.053	-9.87	-8.64	28.53
H-2276B	9/1/2026 2:23:18 PM	-4.02	-4.01	16.8	15.3	0.615	0.510	-5.44		28.55
H-2276B	9/21/2026 9:13:01 AM	-6.93	-7.00	28.0	30.5	1.866	2.212	-9.99	-10.26	28.55
H-2276E	9/9/2026 1:36:12 PM	-0.44	-0.43	1.2	1.1	0.002	0.001	-19.66		28.6
H-2276W	9/1/2026 9:23:11 AM	-5.67	-5.69	0.6	0.6	0.002	0.002	-10.72		28.64
H-2276W	9/22/2026 11:39:01 AM	-3.07	-2.62	12.0	9.8	0.950	0.637	-9.80		28.58
H-2277A	9/1/2026 10:22:08 AM	-0.36	-0.35	0.6	0.6	0.002	0.002	-7.34		28.59
H-2277A	9/17/2026 10:03:32 AM	-3.20	-3.13	2.0	1.3	0.023	0.009	-11.34	-11.33	28.67
H-2277B	9/14/2026 1:34:55 PM	-4.19	-2.26	1.7	1.1	0.780	0.320	-9.01	-9.42	28.37
H-2277B	9/21/2026 8:52:57 AM	-2.22	-3.17	1.2	0.6	0.400	0.103	-10.25	-10.99	28.53
H-23 (EXP-23	9/21/2026 8:51:57 AM	-18.76	-18.86	3.1	2.3	0.021	0.012	-18.82	-18.82	28.66
H-2301E	9/24/2026 1:01:31 PM	-0.87	-0.87	5.3	7.0	0.063	0.108	-4.89	-4.89	28.87
H-2301N	9/16/2026 7:52:01 AM	-2.49	-4.84	31.9	38.8	1.257	1.884	-11.54	-12.06	28.74
H-2301N	9/23/2026 1:05:15 PM	-5.39	-5.38	30.3	29.2	1.165	1.079	-8.83	-8.61	28.66
H-2301W	9/28/2026 2:15:49 PM	-3.52	-3.52	0.2	0.2	0.003	0.005	-5.86	-6.17	28.63
H-2301W	9/28/2026 2:16:39 PM	-3.82	-3.81	0.2	0.2	0.002	0.002	-6.26	-6.21	28.64

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
H-2302C	9/17/2026 1:44:50 PM	-0.52	-1.83	8.6	10.3	0.470	0.669	-11.44	-11.49	28.91
H-2302C	9/17/2026 1:47:40 PM	-1.94	-2.12	11.7	12.5	0.866	0.991	-11.49	-11.08	28.91
H-2302E	9/24/2026 1:21:07 PM	-5.58	-5.67	13.1	13.3	0.220	0.228	-5.67	-5.62	28.83
H-2303E	9/24/2026 1:28:29 PM	-0.86	-0.82	5.2	5.9	0.034	0.043	-0.52	-0.54	28.83
H-2303N	9/21/2026 1:25:13 PM	-0.82	-0.81	14.4	14.1	4.298	4.139	-11.74	-11.29	28.77
H-2303N	9/21/2026 1:31:23 PM	-0.92	-1.01	8.6	9.7	1.519	1.951	-10.94	-10.64	28.78
H-2303N	9/21/2026 1:36:02 PM	-1.58	-1.72	14.6	15.3	4.420	4.854	-11.07	-10.50	28.77
H-2303N	9/21/2026 1:42:20 PM	-3.50	-3.51	46.5	46.5	4.985	4.974	-10.25	-10.85	28.76
H-2303N	9/21/2026 1:46:07 PM	-3.98	-4.05	46.9	48.3	2.829	2.997	-10.03	-10.84	28.76
H-2303S	9/30/2026 9:07:20 AM	-0.50	-0.47	0.3	3.4	0.002	0.242	-1.60	-1.43	28.71
H-2303S	9/30/2026 3:11:43 PM	-1.92	-1.92	29.5	28.6	1.121	1.054	-8.18	-8.17	28.66
H-2304E	9/24/2026 1:38:49 PM	-0.17	-0.19	78.8	79.0	3.794	3.817	-3.70	-3.70	28.82
H-2304S	9/30/2026 8:57:47 AM	-0.10	-0.20	8.4	8.2	1.470	1.406	-1.67	-1.47	28.72
H-2305N	9/21/2026 1:56:13 PM	-4.57	-4.47	2.8	3.9	0.017	0.035	-8.91	-8.82	28.77
H-2305S	9/30/2026 8:54:12 AM	-0.87	-0.86	4.3	4.8	0.118	0.147	-1.75	-1.66	28.75
H-2306N	9/30/2026 10:03:45 AM	-0.15	-0.16	10.0	10.5	0.230	0.255	-1.22	-1.14	28.67
H-2307S	9/28/2026 9:57:33 AM	-0.80	-0.81	21.3	22.0	1.032	1.099	-14.85	-14.50	28.67
H-2307S	9/28/2026 9:59:24 AM	-0.83	-0.83	22.6	22.4	1.160	1.144	-15.30	-15.06	28.68
H-2308S	9/28/2026 9:25:41 AM	-1.31	-1.31	14.7	15.7	0.269	0.309	-10.89	-9.97	28.68
H-2309N	9/23/2026 10:09:11 AM	-8.08	-8.73	1.4	0.9	0.013	0.005	-12.63	-17.06	28.57
H-2309S	9/28/2026 1:47:35 PM	-3.16	-3.26	33.3	35.5	1.456	1.656	-7.76	-7.94	28.65
H-2309S	9/28/2026 1:50:05 PM	-3.38	-3.34	37.0	37.0	1.795	1.801	-8.03	-7.93	28.65
H-2310N	9/21/2026 10:17:15 AM	-0.02	-0.03	5.7	6.1	0.669	0.762	-3.48	-3.13	28.76
H-2310N	9/21/2026 10:23:24 AM	-0.05	-0.24	4.0	9.1	0.098	0.518	-3.32	-3.03	28.76
H-2310N	9/21/2026 10:25:58 AM	-0.33	-0.32	9.6	9.9	0.574	0.609	-2.84	-2.95	28.76
H-2310S	9/30/2026 9:54:34 AM	-0.05	-0.04	5.3	4.0	0.035	0.020	-1.33	-1.22	28.71
H-2401S	9/17/2026 12:53:46 PM	-13.75	-14.41	46.4	47.6	2.853	3.010	-19.11	-18.85	28.84
H-2401S	9/17/2026 12:55:27 PM	-13.68	-13.74	44.9	45.3	2.671	2.716	-17.89	-18.15	28.84
H-2402N	9/16/2026 9:29:50 AM	-0.80	-0.29	4.0	3.1	1.688	1.048	-19.97	-21.40	28.76
H-2402N	9/16/2026 9:38:17 AM	-0.32	-0.33	0.7	0.8	0.058	0.060	-20.82	-21.19	28.76
H-2402S	9/17/2026 10:29:36 AM	-0.43	-0.36	16.3	15.0	0.604	0.514	-20.82	-20.74	28.87
H-2402S	9/17/2026 10:36:31 AM	-0.38	-0.36	15.1	15.1	0.522	0.516	-22.14	-20.69	28.87
H-2403N	9/16/2026 9:07:19 AM	-4.48	-0.57	17.6	5.5	6.658	0.624	-20.19	-20.32	28.74
H-2403N	9/16/2026 9:15:02 AM	-0.56	-0.52	5.1	5.7	0.541	0.671	-21.31	-19.67	28.75

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
H-2403S	9/17/2026 9:46:50 AM	-1.32	-1.73	0.3	3.3	0.006	1.142	-19.27	-20.72	28.87
H-2403S	9/17/2026 9:55:54 AM	-1.67	-1.97	3.2	5.2	0.208	0.550	-19.38	-18.17	28.87
H-2403S	9/17/2026 10:14:23 AM	-2.04	-2.11	5.1	5.1	0.517	0.523	-20.13	-18.81	28.87
H-2404N	9/4/2026 10:12:11 AM	-4.64	-4.80	14.3	16.2	4.368	5.588	-17.58	-18.99	28.72
H-2404N	9/17/2026 10:16:28 AM	-2.25	-2.14	4.9	5.2	0.481	0.546	-19.16	-17.75	28.88
H-2404S	9/17/2026 9:29:43 AM	-11.78	-11.76	26.1	25.8	0.899	0.874	-12.80	-12.67	28.9
H-2405N	9/30/2026 12:52:28 PM	-0.06	-0.06	3.1	2.9	0.206	0.174	-10.05	-9.18	28.63
H-29	9/25/2026 11:24:23 AM	-0.76	-0.70	0.1	0.1	0.002	0.001	-18.75	-18.67	28.66
H-72	9/30/2026 1:21:04 PM	-1.35	-1.35	3.6	2.7	0.017	0.009	-11.97	-12.07	28.45
H-74	9/16/2026 11:51:01 AM	-10.85	-11.05	15.2	15.0	4.994	4.866	-15.34	-15.19	28.75
H-75	9/22/2026 2:37:52 PM	-3.14	-2.72	4.0	4.0	4.183	4.201	-18.70		28.51
H-79	9/4/2026 9:06:09 AM	-1.14	-1.13	4.3	5.4	0.025	0.038	-17.47	-17.30	28.58
P-02R	9/14/2026 10:11:10 AM	-0.21	-0.20	12.5	12.5	0.938	0.938	-17.86	-18.05	28.67
P-03R	9/14/2026 1:32:02 PM	-0.70	-0.70	2.9	3.0	0.899	0.926	-17.70	-17.61	28.63
P-04	9/14/2026 1:26:28 PM	-0.77	-0.75			0.762	0.740	-14.84	-14.69	28.66
P-05	9/14/2026 1:22:06 PM	-0.02	-0.01			0.030	0.034	-13.70	-13.71	28.67
P-06R	9/14/2026 1:14:43 PM	-0.45	-0.89	1.0	2.5	0.102	0.689	-13.06	-12.90	28.67
P-07R	9/14/2026 9:55:22 AM	-27.69	-12.16	6.6	6.7	4.814	4.814	-17.52	-17.54	28.67
P-08R	9/14/2026 10:17:08 AM	-13.10	-12.93	12.2	11.9	0.943	0.895	-14.49	-14.13	28.68
P-09	9/14/2026 10:29:35 AM	-0.32	-0.34			0.000	0.000	-8.82	-9.28	28.7
P-10	9/14/2026 10:34:17 AM	-0.10	-0.09	4.3	4.3	1.888	1.911	-9.32	-9.94	28.7
P-11	9/14/2026 10:41:27 AM	-0.31	-0.31	7.3	7.1	5.639	5.418	-9.06	-9.11	28.71
P-12	9/14/2026 1:08:27 PM	-10.76	-10.78	1.2	1.2	0.029	0.029	-10.91	-10.79	28.69
P-13	9/14/2026 1:02:12 PM	-0.20	-0.20	4.6	4.6	0.417	0.424	-10.83	-10.85	28.7
P-14	9/14/2026 10:49:55 AM	-0.06	-0.06			0.000	0.000	-10.23	-10.28	28.74
P-15R	9/11/2026 9:23:55 AM	-1.24	-1.23	1.9	1.9	0.364	0.378	-10.83	-10.38	28.78
P-16	9/11/2026 9:31:08 AM	-2.39	-2.39	5.3	5.3	2.963	2.936	-9.93	-9.84	28.78
P-17	9/11/2026 1:40:34 PM	-0.49	-0.49			0.426	0.381	-8.12	-8.04	28.74
P-18RD	9/11/2026 1:30:44 PM	-7.98	-7.78	2.8	3.2	0.868	1.103	-7.83	-7.69	28.74
P-18RS	9/11/2026 1:34:14 PM	-0.73	-0.74	5.0	5.0	2.617	2.603	-7.96	-7.64	28.74
P-19	9/11/2026 1:55:29 PM	-0.37	-0.35	2.4	4.2	0.035	0.109	-7.35	-7.33	28.75
P-20R	9/11/2026 1:23:45 PM	-0.89	-1.02	2.1	2.9	0.445	0.887	-7.65	-7.51	28.74
P-21	9/11/2026 1:17:27 PM	-0.16	-0.22			0.273	0.208	-7.63	-7.72	28.74
P-21RD	9/11/2026 1:06:36 PM	-2.91	-2.94	9.8	10.1	2.013	2.130	-6.69	-6.95	28.71
P-21RS	9/11/2026 1:09:45 PM	-2.88	-2.89	12.3	13.4	0.346	0.408	-6.76	-6.99	28.74
P-22RD	9/11/2026 8:08:10 AM	-3.84	-3.84	4.4	4.4	5.289	5.295	-8.34	-8.32	28.69
P-22RS	9/11/2026 8:04:52 AM	-1.20	-1.19	26.8	27.2	1.682	1.727	-8.50	-8.41	28.68
P-23	9/11/2026 1:01:52 PM	-0.96	-0.63	0.9	1.6	0.005	0.016	-6.85	-6.78	28.74
P-24	9/13/2026 1:20:31 PM	-1.34	-1.32	8.5	8.3	1.470	1.414	-6.42	-6.24	28.73

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
P-26	9/13/2026 1:35:13 PM	-4.52	-4.48			4.466	4.438	-6.00	-5.83	28.71
P-27	9/13/2026 1:42:38 PM	-0.78	-0.78	1.9	2.0	0.954	1.017	-5.50	-5.81	28.71
P-28	9/13/2026 1:49:04 PM	-3.27	-3.26			3.237	3.216	-5.57	-5.26	28.68
P-28	9/25/2026 2:03:37 PM	-1.00	-0.29			0.090	0.011	-4.91	-4.93	28.74
P-29R	9/14/2026 8:03:35 AM	-0.82	-0.82	10.9	10.9	0.710	0.717	-7.97	-8.45	28.67
P-30R	9/14/2026 8:11:45 AM	-4.67	-4.75	11.0	11.2	2.426	2.541	-7.68	-7.65	28.67
P-32R1	9/14/2026 8:36:49 AM	-1.47	-1.47	4.9	4.8	6.518	6.199	-7.08	-6.88	28.66
P-32R2	9/14/2026 8:45:03 AM	-1.77	-1.77	25.5	25.4	0.834	0.828	-7.19	-7.26	28.65
P-33	9/14/2026 8:50:19 AM	-1.09	-1.12			0.479	0.510	-1.05	-1.05	28.63
P-36	9/14/2026 9:06:39 AM	-0.27	-2.17			0.000	1.558	-4.37	-4.14	28.63
P-36	9/14/2026 9:07:30 AM	-2.14	-2.11			1.516	1.487	-4.43	-4.65	28.63
P-37	9/14/2026 9:26:35 AM	-0.18	-0.27	1.7	1.7	0.704	0.715	-4.18	-4.15	28.61
P-38RD	9/9/2026 1:02:10 PM	-2.87	-2.91	11.0	11.4	0.752	0.819	-3.40	-3.38	28.73
P-38RS	9/9/2026 12:58:14 PM	-0.71	-0.85	10.0	13.6	0.618	1.153	-3.15	-3.31	28.74
P-39	9/9/2026 1:09:03 PM	-4.87	-4.83	0.9	1.1	0.018	0.026	-4.64	-4.61	28.74
P-39	9/9/2026 1:12:07 PM	-4.94	-4.90	1.2	2.4	0.028	0.122	-4.69	-4.85	28.74
P-41	9/9/2026 1:35:32 PM	-5.08	-5.05			0.000	0.000	-5.43	-5.40	28.74
P-42R	9/9/2026 1:46:37 PM	-4.76	-4.84	2.6	3.2	0.754	1.117	-5.38	-5.88	28.74
P-43	9/9/2026 1:51:47 PM	-2.52	-2.52			2.508	2.502	-5.57	-5.50	28.74
P-44RD	9/9/2026 1:59:38 PM	-5.26	-5.16	0.1	0.9	0.001	0.092	-5.20	-5.24	28.74
P-44RS	9/9/2026 1:56:43 PM	-3.54	-3.52	3.2	3.2	1.136	1.107	-5.29	-5.35	28.74
P-45RD	9/11/2026 7:34:35 AM	-7.07	-6.94	6.5	6.8	0.270	0.297	-7.80	-7.76	28.64
P-45RS	9/11/2026 7:38:47 AM	-0.75	-0.74	3.9	3.9	4.008	4.020	0.37	0.37	28.63
P-46RD	9/11/2026 7:48:05 AM	-7.73	-7.76	2.1	3.7	0.028	0.086	-7.49	-7.50	28.64
P-46RS	9/11/2026 7:50:57 AM	-2.23	-2.25	20.7	21.4	2.754	2.951	-7.20	-7.52	28.63
P-47	9/11/2026 7:57:45 AM	-0.15	-0.15			0.156	0.152	-8.12	-8.29	28.67
P-48	9/11/2026 8:17:55 AM	-0.20	-0.62	0.2	3.7	0.001	0.291	-9.28	-9.18	28.67
P-49RD	9/2/2026 12:40:19 PM	-7.79	-7.81	12.7	13.4	1.031	1.147	-11.14	-11.56	28.74
P-49RS	9/2/2026 12:36:19 PM	-1.50	-1.49	23.9	23.8	1.320	1.304	-10.66	-10.94	28.75
P-52	9/2/2026 12:48:58 PM	-0.30	-0.25	11.6	11.7	2.837	2.844	-15.97	-16.41	28.74
P-53	9/2/2026 12:54:52 PM	-0.56	-0.58	9.1	9.4	1.722	1.842	-17.00	-16.81	28.74
P-54	9/2/2026 1:04:15 PM	-0.36	-0.82	24.3	28.7	1.327	1.859	-9.23	-11.09	28.74
P-55	9/2/2026 1:11:35 PM	-0.35	-0.34			0.329	0.324	-0.33	-0.34	28.74
P-56	9/2/2026 1:26:56 PM	-0.30	-0.20			0.240	0.235	-17.69	-17.49	28.74
P-57	9/2/2026 1:19:29 PM	-0.19	-0.18	2.5	2.2	0.008	0.006	-16.96	-16.56	28.72
P-60R	9/2/2026 1:44:59 PM	-2.44	-2.86	0.6	2.1	0.007	0.087	-4.25	-4.43	28.72
P-61	9/3/2026 10:41:33 AM	-0.45	-0.43	6.7	6.3	4.669	4.070	-4.15	-3.56	28.67
P-65	9/3/2026 10:49:34 AM	-0.92	-1.12	7.5	8.8	1.122	1.537	-4.50	-3.46	28.67
P-71	9/11/2026 8:24:58 AM	-1.60	-1.58			0.030	0.027	-8.22	-7.77	28.66
P-75	9/2/2026 1:35:58 PM	-3.36	-3.47	13.4	14.9	1.092	1.352	-4.09	-4.46	28.71
P-76	9/9/2026 12:51:44 PM	-1.06	-1.08			1.058	1.023	-3.17	-3.15	28.74
P-79	9/11/2026 1:48:37 PM	0.03	-0.11			0.014	0.113	-7.38	-7.60	28.78

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
P-79	9/14/2026 7:34:29 AM	-0.52	-0.59			0.000	0.000	-10.98	-10.97	28.78
SC-2000E	9/25/2026 8:57:52 AM	-3.66	-3.40	5.8	5.3	0.726	0.598	-10.12	-9.73	28.72
SC-2501E	9/8/2026 9:59:28 AM	-2.54	-2.55			2.539	2.529	-5.07	-5.15	28.61
SC-2501E	9/8/2026 10:01:00 AM									
SC-2501E	9/14/2026 9:17:00 AM									
SC-2501E	9/14/2026 9:21:21 AM	-4.34	-3.20			4.331	3.188	-7.38	-8.09	28.49
SC-2501E	9/14/2026 9:23:51 AM	-3.07	-3.05			3.060	3.043	-8.09	-7.71	28.49
SC-2501E	9/21/2026 9:24:00 AM									
SC-2501E	9/21/2026 9:24:06 AM	-3.30	-3.30			3.296	3.300	-10.46	-10.78	28.59
SC-2501E	9/28/2026 8:44:16 AM	-3.19	-3.18			3.195	3.188	-10.74	-10.61	28.46
SC-2501E	9/28/2026 8:50:00 AM									
SC-2501W	9/14/2026 1:14:36 PM	-3.26	-2.66			3.210	2.562	-3.78	-4.65	28.55
SC-2501W	9/14/2026 1:16:00 PM	-2.81	-2.83			2.756	2.754	-4.29	-4.15	28.56
SC-2501W	9/21/2026 9:47:01 AM	-2.41	-2.46	18.2	18.4	2.395	2.442	-7.55	-7.52	28.58
SC-2501W	9/21/2026 9:50:00 AM									
SC-2501W	9/28/2026 9:27:48 AM	-3.30	-3.29	21.2	21.2	3.271	3.259	-6.81	-6.99	28.46
SC-2501W	9/28/2026 9:30:00 AM									
SW-10	9/28/2026 10:08:23 AM	-14.78	-14.78	13.7	12.6	0.242	0.204	-17.42	-17.60	28.55
SW-115	9/17/2026 1:39:25 PM	-16.91	-16.96	24.9	24.6	3.907	3.812	-20.62	-20.51	28.81
SW-1445	9/29/2026 12:27:40 PM	-4.39	-5.04	0.9	3.9	0.001	0.019	-5.13	-5.08	28.55
SW-1455	9/30/2026 4:06:16 PM	-3.56	-5.01	2.9	4.8	0.011	0.030	-5.44	-5.22	28.55
SW-154	9/30/2026 2:17:21 PM	-13.68	-13.68			13.760	13.751	-13.59	-13.67	28.53
SW-17-135	9/30/2026 4:01:25 PM	-4.08	-5.46	3.2	0.8	0.013	0.001	-5.43	-5.34	28.55
SW-187	9/23/2026 9:03:24 AM	-15.87	-15.86	9.7	9.7	0.023	0.023	-15.98	-15.96	28.59
SW-20	9/14/2026 10:03:19 AM	-4.02	-3.98	23.8	23.8	0.706	0.709	-17.52	-17.52	28.67
SW-20	9/14/2026 10:04:06 AM	-5.34	-5.35	23.9	23.8	0.718	0.715	-17.66	-17.75	28.67
SW-2501D	9/28/2026 8:51:48 AM	-14.44	-14.27	20.0	20.7	0.500	0.531	-14.40	-14.22	28.63
SW-2501M	9/28/2026 8:37:05 AM	-14.18	-14.17	20.0	20.1	0.493	0.496	-14.22	-14.22	28.62
SW-2501MD	9/28/2026 8:48:27 AM	-12.14	-12.09	6.1	5.6	0.225	0.192	-14.27	-14.22	28.63
SW-2501S	9/28/2026 8:34:18 AM	-14.11	-14.11	18.0	18.0	0.395	0.396	-14.26	-14.26	28.63
SW-2502D	9/28/2026 1:31:44 PM	-14.53	-14.53	1.5	1.5	0.230	0.254	-14.56	-14.52	28.62
SW-2502M	9/28/2026 1:35:12 PM	-7.14	-7.14	0.3	0.3	0.010	0.010	-14.63	-14.62	28.63
SW-2502MD	9/28/2026 9:07:21 AM	-14.15	-14.16	1.7	1.7	0.302	0.308	-14.22	-14.23	28.63

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]
SW-2502S	9/28/2026 9:04:57 AM	-14.11	-14.11	1.7	1.7	0.315	0.315	-14.27	-14.27	28.63
SW-2503D	9/28/2026 9:31:14 AM	-14.11	-14.11	4.8	4.8	0.140	0.140	-14.21	-14.21	28.6
SW-2503M	9/28/2026 9:36:56 AM	-10.41	-10.41	3.8	3.7	0.091	0.086	-14.17	-14.22	28.61
SW-2503MD	9/28/2026 9:43:35 AM	-14.11	-14.11	5.7	5.6	0.202	0.192	-14.31	-14.56	28.62
SW-2503S	9/28/2026 9:40:46 AM	-14.15	-14.20	6.0	6.0	0.221	0.225	-14.35	-14.37	28.6
SW-2504D	9/28/2026 9:56:00 AM	-14.26	-14.11	3.8	2.5	0.087	0.038	-14.36	-14.56	28.61
SW-2504M	9/28/2026 9:49:08 AM	-7.05	-7.05	4.3	4.2	0.111	0.108	-14.32	-14.47	28.63
SW-2504MD	9/28/2026 9:59:28 AM	-16.48	-16.57	6.6	6.4	0.272	0.252	-16.62	-16.73	28.63
SW-2504S	9/28/2026 9:52:36 AM	-14.21	-14.11	4.1	4.9	0.103	0.149	-14.27	-14.18	28.6
SW-30	9/28/2026 8:56:46 AM	-13.98	-13.90	5.8	5.6	0.206	0.191	-14.22	-14.22	28.63
SW-32	9/28/2026 8:26:06 AM	-14.11	-14.11	10.1	10.2	0.613	0.629	-14.44	-14.56	28.63
SW-64	9/28/2026 8:59:49 AM	-14.11	-14.11	6.7	6.8	0.275	0.281	-14.22	-14.22	28.63
SW-65	9/17/2026 10:54:03 AM	-17.60	-17.75	4.6	5.3	0.129	0.173	-23.34	-23.26	28.85
SW-65	9/17/2026 11:10:21 AM	-7.25	-7.24			7.419	7.425	-23.61	-23.63	28.85
SW-66	9/30/2026 2:19:22 PM	-12.34	-12.26			12.402	12.317	-12.36	-12.32	28.53
SW-68	9/28/2026 8:30:14 AM	-14.11	-14.23	13.8	7.6	1.141	0.345	-14.35	-14.47	28.62
SW-70	9/23/2026 9:06:01 AM	-15.79	-15.83	7.5	0.0	0.013	0.000	-16.00	-16.25	28.62
SW-71	9/13/2026 1:27:50 PM	-6.12	-6.08	2.6	2.4	0.715	0.597	-6.25	-6.08	28.71
SW-71	9/13/2026 1:29:03 PM	-6.13	-6.12	2.3	2.4	0.566	0.632	-6.07	-6.16	28.71
SW-72	9/14/2026 8:57:13 AM	-4.82	-4.26	2.7	2.7	0.758	0.760	-4.89	-5.08	28.63
SW-80	9/3/2026 12:03:20 PM	-9.08	-9.08	6.2	6.2	0.234	0.234	-15.23	-15.23	28.75
SW-9	9/23/2026 9:09:10 AM	-15.79	-15.79	31.5	29.8	0.241	0.215	-16.14	-16.21	28.62
TC-1961C	9/24/2026 11:07:18 AM	-1.84	-1.80	5.9	7.1	0.082	0.117	-13.74	-13.83	28.58
TC-1961E	9/1/2026 9:15:54 AM	-3.54	-2.87	5.9	13.6	0.082	0.433	-17.37	-17.52	28.65
TC-2174	9/8/2026 9:41:41 AM	-1.97	-1.94			1.980	1.959	0.04	0.04	28.63
TC-2174	9/8/2026 9:44:00 AM									
TC-2174	9/14/2026 8:44:26 AM	-3.95	-3.94			3.923	3.911	0.00	0.00	28.49
TC-2174	9/14/2026 8:47:00 AM									
TC-2174	9/21/2026 9:00:00 AM									
TC-2174	9/21/2026 9:00:43 AM	-3.90	-3.94			3.884	3.941	0.29	0.29	28.57
TC-2174	9/28/2026 8:20:43 AM	-4.78	-4.76			4.752	4.750	0.00	0.00	28.46
TC-2174	9/28/2026 8:25:00 AM									
VL-02	9/30/2026 10:59:45 AM	-2.01	-2.05	40.5	40.7	2.004	2.023	0.67	0.67	28.69

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
A-01	9/17/2026 7:39:23 AM	1174	34.4312288	-118.6437712	
A-02	9/17/2026 7:48:47 AM	1162	34.4316565	-118.6433610	
A-03	9/17/2026 8:00:42 AM	1193	34.4319923	-118.6428522	
A-04	9/17/2026 8:10:05 AM	1204	34.4322172	-118.6422053	
A-05	9/28/2026 8:50:32 AM	1195	34.4325068	-118.6416402	
B-01	9/17/2026 9:22:43 AM	1238	34.4338618	-118.6396167	
B-02R	9/17/2026 9:16:57 AM	1239	34.4335615	-118.6395132	
B-03R	9/16/2026 1:51:26 PM	1224	34.4337940	-118.6388338	
B-05	9/16/2026 2:03:40 PM	1208	34.4336167	-118.6382465	
B-06	9/17/2026 8:53:22 AM	1220	34.4340185	-118.6377473	
B-07R	9/16/2026 10:45:52 AM	1215	34.4342898	-118.6374210	Valve Adjustment:NSPS/EG CAI
B-07R	9/16/2026 10:52:10 AM	1211	34.4342747	-118.6374130	Valve Adjustment:NSPS/EG CAC,Orifice Plate Changed (See OP Log)
B-08	9/17/2026 8:39:40 AM	1231	34.4337560	-118.6373313	Valve Adjustment:NSPS/EG CAI,High O2,Valve 100% Open
B-08	9/17/2026 8:44:20 AM	1222	34.4337668	-118.6373377	Valve Adjustment:NSPS/EG CAI,Orifice Plate Changed (See OP Log),No Flow Measurement,High O2
B-09	9/16/2026 9:27:25 AM	1200	34.4342120	-118.6370480	
B-10	9/16/2026 9:20:22 AM	1223	34.4340105	-118.6365542	
B-11	9/16/2026 8:54:56 AM	1149	34.4348338	-118.6368885	
B-12	9/16/2026 1:43:21 PM	1218	34.4340710	-118.6385075	
B-13	9/16/2026 1:37:34 PM	1210	34.4344482	-118.6378995	
B-14	9/16/2026 8:34:59 AM	1127	34.4349353	-118.6370485	
C-03	9/14/2026 1:58:34 PM	1174	34.4314085	-118.6435793	
C-07	9/30/2026 3:03:49 PM	1186	34.4326427	-118.6414348	Valve Adjustment:Valve 100% Open,Reduce Sys. Vac. - Flare Down
C-08	9/17/2026 10:13:25 AM	1200	34.4336425	-118.6408665	Valve Adjustment:NSPS/EG CAI,High O2
C-08	9/17/2026 10:15:37 AM	1201	34.4336492	-118.6408757	Valve Adjustment:NSPS/EG CAI
C-10	9/17/2026 10:44:49 AM	1217	34.4347212	-118.6411873	
C-11	9/3/2026 11:22:35 AM	1217	34.4352285	-118.6413333	Valve Adjustment:Audible Flow
C-12	9/3/2026 11:48:07 AM	1224	34.4359657	-118.6408995	Valve Adjustment:Audible Flow
C-15	9/3/2026 11:44:12 AM	1223	34.4362487	-118.6410603	Valve Adjustment:Audible Flow
C-17B	9/29/2026 9:29:28 AM	1229	34.4373565	-118.6419128	
C-18	9/29/2026 10:05:18 AM	1227	34.4379753	-118.6426142	Valve Adjustment:Valve 100% Open
C-19	9/29/2026 9:49:37 AM	1223	34.4375627	-118.6421395	Valve Adjustment:Valve 100% Open
C-20	9/29/2026 9:55:47 AM	1220	34.4377778	-118.6424007	Valve Adjustment:Valve 100% Open
C-24	9/29/2026 9:39:17 AM	1216	34.4375213	-118.6421202	Valve Adjustment:NSPS/EG CAI,High O2,Increased Flow/Vacuum
C-24	9/29/2026 9:44:02 AM	1246	34.4375273	-118.6421290	Valve Adjustment:NSPS/EG CAC
C-25	9/25/2026 12:09:01 PM	1217	34.4371087	-118.6416640	Valve Comment:broken valve;Valve Adjustment:NSPS/EG CAI,Positive Static Press.
C-25	9/25/2026 12:10:05 PM	1220	34.4371008	-118.6416723	Valve Adjustment:NSPS/EG CAI,Positive Static Press.
C-26	9/25/2026 12:01:24 PM	1214	34.4366432	-118.6412978	

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
C-27	9/3/2026 11:37:39 AM	1228	34.4361717	-118.6409792	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In)
C-27	9/3/2026 11:38:33 AM	1231	34.4361723	-118.6409863	
C-28	9/3/2026 11:18:29 AM	1225	34.4354082	-118.6413798	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
C-29	9/21/2026 8:03:56 AM	1223	34.4348462	-118.6412337	
C-30	9/17/2026 10:25:51 AM	1241	34.4342405	-118.6412652	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp
C-30	9/17/2026 10:32:06 AM	1240	34.4342668	-118.6412558	Valve Adjustment:NSPS/EG CAC,Increased Flow/Vacuum
CV-02	9/21/2026 10:39:51 AM	1248	34.4335690	-118.6413535	
CV-03	9/21/2026 12:58:06 PM	1237	34.4333167	-118.6414605	
CV-04	9/30/2026 8:15:05 AM	1229	34.4331157	-118.6416692	
CV-05	9/4/2026 8:19:06 AM	1229	34.4328347	-118.6422322	Valve Adjustment:Increased Flow/Vacuum
CV-06	9/28/2026 3:58:30 PM	1227	34.4326880	-118.6428460	Valve Adjustment:Decreased Flow/Vacuum
CV-108-52	9/1/2026 7:25:00 AM				Air Tech Lab
CV-108-52	9/1/2026 7:25:00 AM				Air Tech Lab; [User entered 13%]
CV-108-52	9/2/2026 7:35:40 AM	1289	34.4333565	-118.6506533	NSPS/EG CAI,Positive Static Press.,Reduced System Vacuum
CV-108-52	9/2/2026 7:36:35 AM	1325	34.4333477	-118.6506358	NSPS/EG CAI,Positive Static Press.,Reduced System Vacuum
CV-108-52	9/10/2026 3:44:09 PM	1288	34.4334013	-118.6507085	Valve Adjustment:NSPS/EG CAC,Increased Flow/Vacuum,Barely Open
CV-108-52	9/10/2026 3:44:53 PM	1290	34.4333983	-118.6507048	
CV-108-52	9/22/2026 11:11:22 AM	1260	34.4334630	-118.6506818	,
CV-113	9/4/2026 7:00:00 AM				AirTech Lab
CV-113	9/4/2026 7:00:00 AM				AirTech Lab; [User entered 0%]
CV-113	9/14/2026 9:34:21 AM	1331	34.4369800	-118.6467277	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In)
CV-113	9/14/2026 9:35:35 AM	1352	34.4369782	-118.6467027	
CV-113	9/25/2026 10:33:54 AM	1328	34.4369592	-118.6467337	Valve Adjustment:High O2,Barely Open
CV-114	9/4/2026 8:22:00 AM				AirTech Lab
CV-114	9/4/2026 8:22:00 AM				AirTech Lab; [User entered 18%]
CV-114	9/8/2026 9:33:48 AM	1347	34.4367228	-118.6476567	Valve Adjustment:No Flow Measurement,High Temp
CV-114	9/8/2026 9:39:00 AM				AtmAA
CV-114	9/14/2026 8:28:09 AM	1341	34.4367189	-118.6476122	Valve Adjustment:No Flow Measurement,High Temp
CV-114	9/14/2026 8:30:00 AM				AtmAA
CV-114	9/21/2026 8:22:00 AM	1321	34.4367257	-118.6476236	Valve Adjustment:No Flow Measurement,High Temp
CV-114	9/21/2026 8:25:00 AM				AtmAA
CV-114	9/28/2026 8:16:00 AM	1353	34.4367287	-118.6476203	Valve Adjustment:No Flow Measurement,High Temp
CV-114	9/28/2026 8:20:00 AM				AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-114	9/28/2026 8:20:00 AM				AtmAA
CV-1424	9/3/2026 1:47:43 PM	1391	34.4351257	-118.6450895	Valve Adjustment:Decreased Flow/Vacuum
CV-1532A	9/1/2026 7:30:00 AM				Air Tech Lab
CV-1532A	9/1/2026 7:30:00 AM				AirTech Lab; [User entered 23%]
CV-1532A	9/1/2026 1:33:46 PM	1277	34.4338658	-118.6508396	Valve Adjustment:No Flow Measurement
CV-1532A	9/30/2026 3:06:52 PM	1281	34.4338700	-118.6508292	
CV-1534A-PL	9/2/2026 10:23:59 AM				Valve Adjustment:No Flow Measurement,High Temp
CV-1534A-PL	9/30/2026 3:09:20 PM	1276	34.4336273	-118.6508055	
CV-1535	9/1/2026 9:18:24 AM	1296	34.4331213	-118.6502692	,
CV-1535	9/4/2026 7:22:00 AM				AirTech Lab
CV-1535	9/4/2026 7:22:00 AM				AirTech Lab; [User entered 18%]
CV-1535	9/22/2026 11:06:11 AM	1286	34.4333205	-118.6503402	,
CV-1535	9/24/2026 2:43:07 PM	1298	34.4333198	-118.6503462	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header
CV-1601D	9/15/2026 11:02:56 AM	1315	34.4311130	-118.6486610	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-1601D	9/21/2026 11:29:39 AM	1328	34.4311047	-118.6486582	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-1601S	9/15/2026 11:06:57 AM	1314	34.4310925	-118.6486713	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-1601S	9/21/2026 11:25:45 AM	1323	34.4310993	-118.6486612	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-1604	9/24/2026 10:50:44 AM	1296	34.4321622	-118.6450182	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-1701D	9/1/2026 8:45:21 AM	1323	34.4335742	-118.6433220	Valve Adjustment:Barely Open,Surging Liquid in Header,Plugged/Pinched Suspected
CV-1701S	9/1/2026 8:41:19 AM	1302	34.4335962	-118.6433337	Valve Adjustment:Barely Open
CV-1901	9/14/2026 9:48:47 AM	1339	34.4356837	-118.6508192	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-1901	9/16/2026 2:06:50 PM	1317	34.4356995	-118.6507963	Valve Adjustment:Barely Open
CV-1902A	9/1/2026 7:35:00 AM				Air Tech Lab
CV-1902A	9/1/2026 7:35:00 AM				Air Tech Lab; [User entered 4.3%]
CV-1902A	9/8/2026 10:47:01 AM	1283	34.4345907	-118.6503337	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-1902A	9/8/2026 10:50:00 AM				AtmAA
CV-1902A	9/16/2026 2:31:00 PM				AtmAA
CV-1902A	9/16/2026 2:32:50 PM	1323	34.4345944	-118.6503040	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-1902A	9/23/2026 2:32:08 PM	1311	34.4345912	-118.6502988	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-1902A	9/23/2026 2:37:00 PM				AtmAA
CV-1902A	9/30/2026 2:35:00 PM				AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-1902A	9/30/2026 2:40:44 PM	1312	34.4345939	-118.6502987	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-1905	9/14/2026 1:14:41 PM	1389	34.4334972	-118.6459933	Valve Adjustment:Barely Open
CV-1905	9/22/2026 9:36:40 AM	1398	34.4335026	-118.6459849	Valve Adjustment:Increased Flow/Vacuum,Barely Open
CV-1905	9/24/2026 2:08:39 PM	1386	34.4334710	-118.6460140	Valve Adjustment:Increased Flow/Vacuum
CV-2001	9/2/2026 8:39:57 AM	1224	34.4322745	-118.6505838	Reduced System Vacuum,
CV-2001	9/9/2026 7:20:00 AM				AirTech Lab
CV-2001	9/9/2026 7:20:00 AM				AirTech Lab; [User entered 10%]
CV-2001	9/23/2026 8:47:00 AM	1262	34.4322705	-118.6505628	Valve Comment:Well too tall
CV-2002	9/1/2026 2:10:00 PM				AtmAA
CV-2002	9/1/2026 2:10:00 PM				AtmAA; [User entered 11.71%]
CV-2002	9/1/2026 2:10:13 PM	1266	34.4328169	-118.6511726	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2002	9/8/2026 1:42:58 PM	1289	34.4326590	-118.6510465	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-2002	9/8/2026 1:45:00 PM				AtmAA
CV-2002	9/9/2026 7:25:00 AM				AirTech Lab
CV-2002	9/9/2026 7:25:00 AM				AirTech Lab; [User entered 14%]
CV-2002	9/17/2026 8:11:35 AM	1274	34.4328224	-118.6511977	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	9/17/2026 8:13:00 AM				AtmAA
CV-2002	9/24/2026 9:58:49 AM	1268	34.4328016	-118.6511557	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	9/24/2026 10:10:00 AM				AtmAA
CV-2003	9/2/2026 7:38:27 AM	1316	34.4332298	-118.6506550	NSPS/EG CAI,Positive Static Press.,Reduced System Vacuum
CV-2003	9/2/2026 7:41:22 AM	1286	34.4335605	-118.6509697	NSPS/EG CAI,Positive Static Press.,Reduced System Vacuum
CV-2003	9/10/2026 3:49:41 PM	1291	34.4333900	-118.6507330	Valve Adjustment:NSPS/EG CAC,Valve 100% Open
CV-2003	9/10/2026 3:50:31 PM	1291	34.4333900	-118.6507330	
CV-2003	9/22/2026 11:14:52 AM	1204	34.4334478	-118.6508902	,
CV-2006	9/8/2026 10:53:00 AM	1362	34.4352133	-118.6507100	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-2006	9/8/2026 11:05:00 AM				AtmAA
CV-2006	9/16/2026 2:22:00 PM				AtmAA
CV-2006	9/16/2026 2:23:56 PM	1328	34.4352240	-118.6506578	Valve Adjustment:High Temp
CV-2006	9/23/2026 2:26:56 PM	1318	34.4352382	-118.6506570	Valve Adjustment:High Temp
CV-2006	9/23/2026 2:29:00 PM				AtmAA
CV-2006	9/30/2026 2:25:00 PM				AtmAA
CV-2006	9/30/2026 2:27:51 PM	1326	34.4352046	-118.6506651	Valve Adjustment:High Temp
CV-2007	9/3/2026 10:00:55 AM	1379	34.4361438	-118.6470322	Valve Adjustment:Barely Open
CV-2007	9/4/2026 7:48:00 AM				AirTech Lab
CV-2007	9/4/2026 7:48:00 AM				AirTech Lab; [User entered 6.2%]
CV-2007	9/25/2026 2:05:13 PM	1367	34.4361393	-118.6469917	Valve Adjustment:High Temp,Barely Open

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2007	9/28/2026 10:15:15 AM	1381	34.4361788	-118.6469867	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2007	9/30/2026 10:12:39 AM	1374	34.4361776	-118.6470183	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-2007	9/30/2026 10:14:47 AM	1374	34.4361770	-118.6470180	Valve Adjustment:High Temp;Well Comment:Bad valve on well head;Well Condition:Fair;Well Repairs:Valve
CV-2008	9/3/2026 9:55:07 AM	1361	34.4361932	-118.6462488	Valve Adjustment:Decreased Flow/Vacuum
CV-2008	9/25/2026 2:19:23 PM	1372	34.4362572	-118.6462565	Valve Adjustment:Barely Open,Surging Liquid in Header
CV-2009	9/10/2026 1:22:30 PM	1355	34.4362693	-118.6452872	Valve Adjustment:Barely Open
CV-2009A	9/14/2026 1:25:59 PM	1348	34.4360450	-118.6453020	NSPS/EG CAI,High Temp
CV-2009A	9/14/2026 1:27:41 PM	1312	34.4358952	-118.6453217	NSPS/EG CAI,High Temp
CV-2009A	9/14/2026 2:27:00 PM				AtmAA
CV-2009A	9/14/2026 2:28:48 PM	1395	34.4359809	-118.6452555	Valve Adjustment:Audible Flow,No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2009A	9/21/2026 1:44:33 PM	1392	34.4359827	-118.6452533	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2009A	9/21/2026 1:45:00 PM				AtmAA
CV-2010	9/22/2026 9:53:51 AM	1394	34.4355675	-118.6435675	,
CV-2010A	9/22/2026 9:49:39 AM	1312	34.4357355	-118.6435607	,
CV-2011	9/1/2026 10:17:28 AM	1336	34.4342182	-118.6434390	Valve Adjustment:Decreased Flow/Vacuum
CV-2011A	9/2/2026 2:08:11 PM	1334	34.4345479	-118.6431825	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2011A	9/2/2026 2:10:00 PM				AtmAA
CV-2011A	9/2/2026 2:10:00 PM				AtmAA; [User entered 20.12%]
CV-2011A	9/10/2026 9:14:08 AM	1327	34.4345323	-118.6431649	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2011A	9/10/2026 9:16:00 AM				AtmAA
CV-2011A	9/11/2026 9:29:31 AM	1331	34.4345648	-118.6431363	Valve Adjustment:High Temp
CV-2011A	9/17/2026 10:27:00 AM				AtmAA
CV-2011A	9/17/2026 10:27:38 AM	1331	34.4345592	-118.6431607	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2011A	9/24/2026 2:22:16 PM	1337	34.4345394	-118.6431843	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2011A	9/24/2026 2:25:00 PM				AtmAA
CV-2012	9/28/2026 1:57:34 PM	1329	34.4350002	-118.6433187	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-2201-PLR	9/3/2026 7:56:39 AM	1349	34.4355665	-118.6488462	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open,Surging Liquid in Well (Watered In)
CV-2201-PLR	9/3/2026 7:57:44 AM	1343	34.4355577	-118.6488687	
CV-2201-PLR	9/21/2026 8:20:29 AM	1356	34.4355463	-118.6488482	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open,Surging Liquid in Well (Watered In)
CV-2201-PLR	9/21/2026 8:21:42 AM	1355	34.4355523	-118.6488412	
CV-2204-PLR	9/8/2026 2:13:18 PM	1379	34.4357913	-118.6474824	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2204-PLR	9/8/2026 2:17:00 PM				AtmAA
CV-2204-PLR	9/14/2026 10:19:07 AM	1361	34.4357541	-118.6474728	Valve Adjustment:No Flow Measurement,High Temp
CV-2204-PLR	9/14/2026 10:26:00 AM				AtmAA
CV-2204-PLR	9/21/2026 10:25:45 AM	1350	34.4357693	-118.6474752	Valve Adjustment:No Flow Measurement,High Temp
CV-2204-PLR	9/21/2026 10:28:00 AM				AtmAA
CV-2204-PLR	9/28/2026 10:21:59 AM	1344	34.4357756	-118.6474776	Valve Adjustment:No Flow Measurement,High Temp
CV-2204-PLR	9/28/2026 10:25:00 AM				AtmAA
CV-2205	9/22/2026 10:12:14 AM	1348	34.4341150	-118.6440615	NSPS/EG CAI,High Temp,Positive Static Press.
CV-2205	9/22/2026 10:43:00 AM	1286	34.4342123	-118.6440915	NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-2205	9/22/2026 10:44:32 AM	1319	34.4342518	-118.6441378	NSPS/EG CAI,High Temp
CV-2205	9/22/2026 1:55:00 PM				AtmAA
CV-2207	9/3/2026 1:27:19 PM	1395	34.4359843	-118.6442125	Valve Adjustment:Barely Open
CV-2208A	9/10/2026 9:58:00 AM				AtmAA
CV-2208A	9/11/2026 6:08:06 PM	1335	34.4365660	-118.6449336	
CV-2208A	9/14/2026 1:18:15 PM	1345	34.4365576	-118.6449547	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2208A	9/14/2026 1:19:00 PM				AtmAA
CV-2208A	9/24/2026 2:05:00 PM				AtmAA
CV-2208A	9/24/2026 2:07:36 PM	1361	34.4365752	-118.6449529	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2301	9/2/2026 9:11:34 AM	1359	34.4335338	-118.6492161	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	9/2/2026 9:13:00 AM				AtmAA
CV-2301	9/2/2026 9:13:00 AM				AtmAA; [User entered 5.57%]
CV-2301	9/3/2026 6:40:00 AM				AirTech Lab
CV-2301	9/3/2026 6:40:00 AM				AirTech Lab; [User entered 5.5%]
CV-2301	9/8/2026 9:59:02 AM	1302	34.4334958	-118.6493157	NSPS/EG CAI,High Temp
CV-2301	9/8/2026 10:00:00 AM				AtmAA
CV-2301	9/16/2026 1:43:00 PM				AtmAA
CV-2301	9/16/2026 1:46:53 PM	1342	34.4335202	-118.6492498	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	9/23/2026 1:27:45 PM	1341	34.4335060	-118.6492387	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	9/23/2026 1:31:00 PM				AtmAA
CV-2301	9/30/2026 10:14:35 AM	1344	34.4335029	-118.6492130	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	9/30/2026 10:15:00 AM				AtmAA
CV-2302	9/2/2026 8:56:46 AM	1350	34.4340338	-118.6492053	Valve Comment:Valve stuck open;Valve Adjustment:Valve 100% Open
CV-2302	9/3/2026 6:45:00 AM				AirTech Lab
CV-2302	9/3/2026 6:45:00 AM				AirTech Lab; [User entered 3.5%]
CV-2302	9/17/2026 10:41:57 AM	1335	34.4340333	-118.6491978	
CV-2303	9/3/2026 6:50:00 AM				AirTech Lab

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2303	9/3/2026 6:50:00 AM				AirTech Lab; [User entered 19%]
CV-2303	9/3/2026 7:49:00 AM				AtmAA
CV-2303	9/3/2026 7:49:00 AM				AtmAA; [User entered 18.75%]
CV-2303	9/3/2026 7:52:16 AM	1353	34.4353804	-118.6496919	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2303	9/3/2026 7:53:05 AM	1353	34.4353804	-118.6496916	Valve Adjustment:No Flow Measurement,High O2;Well Condition:Lorentz Pump Installed
CV-2303	9/9/2026 8:46:47 AM	1367	34.4353876	-118.6496789	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2303	9/9/2026 8:50:00 AM				AtmAA
CV-2303	9/15/2026 9:24:00 AM	1365	34.4353806	-118.6496105	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2303	9/15/2026 9:25:00 AM				AtmAA
CV-2303	9/22/2026 9:19:07 AM	1342	34.4353779	-118.6496979	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2303	9/22/2026 9:21:00 AM				AtmAA
CV-2304-PLR	9/3/2026 8:30:11 AM	1342	34.4345708	-118.6487343	Valve Adjustment:No Flow Measurement,High Temp
CV-2304-PLR	9/3/2026 8:32:00 AM				AtmAA
CV-2304-PLR	9/3/2026 8:32:00 AM				AtmAA; [User entered 19.02%]
CV-2304-PLR	9/9/2026 9:38:00 AM				AtmAA
CV-2304-PLR	9/9/2026 9:42:30 AM	1336	34.4345555	-118.6487491	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.
CV-2304-PLR	9/11/2026 2:24:49 PM	1338	34.4345404	-118.6487454	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-2304-PLR	9/11/2026 2:25:38 PM	1341	34.4345383	-118.6487426	
CV-2304-PLR	9/15/2026 10:21:48 AM	1355	34.4345517	-118.6487781	Valve Adjustment:No Flow Measurement,High Temp
CV-2304-PLR	9/15/2026 10:22:00 AM				AtmAA
CV-2304-PLR	9/22/2026 10:45:24 AM	1338	34.4345606	-118.6487636	Valve Adjustment:No Flow Measurement,High Temp
CV-2304-PLR	9/22/2026 10:46:00 AM				AtmAA
CV-2304-PLR	9/29/2026 9:11:59 AM	1350	34.4345511	-118.6487367	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2304-PLR	9/29/2026 9:20:00 AM				AtmAA
CV-2305	9/1/2026 10:04:00 AM				AtmAA
CV-2305	9/1/2026 10:04:00 AM				AtmAA; [User entered 5.03%]
CV-2305	9/1/2026 10:04:41 AM	1377	34.4352305	-118.6465370	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2305	9/9/2026 8:05:00 AM				AirTech Lab
CV-2305	9/9/2026 8:05:00 AM				AirTech Lab; [User entered 4.7%]

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2305	9/9/2026 10:42:39 AM	1395	34.4352253	-118.6465235	Valve Adjustment:High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2305	9/9/2026 10:43:11 AM	1395	34.4352253	-118.6465245	
CV-2305	9/9/2026 11:00:00 AM				AtmAA
CV-2305	9/15/2026 2:00:00 PM				AtmAA
CV-2305	9/15/2026 2:02:20 PM	1393	34.4352168	-118.6465431	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-2305	9/15/2026 2:04:55 PM	1394	34.4352189	-118.6465414	Valve Adjustment:NSPS/EG CAC,High Temp;Well Condition:Lorentz Pump Installed
CV-2305	9/22/2026 2:28:38 PM	1384	34.4352159	-118.6465303	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2305	9/22/2026 2:31:00 PM				AtmAA
CV-2305	9/29/2026 1:49:58 PM	1385	34.4352313	-118.6465493	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2305	9/30/2026 10:00:00 AM				AtmAA
CV-2305	9/30/2026 10:01:12 AM	1384	34.4352078	-118.6465434	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2306-PLR	9/8/2026 1:31:32 PM	1360	34.4360807	-118.6478155	Valve Adjustment:No Flow Measurement,High Temp
CV-2306-PLR	9/8/2026 1:32:00 PM				AtmAA
CV-2306-PLR	9/14/2026 10:15:56 AM	1351	34.4360801	-118.6478323	Valve Adjustment:No Flow Measurement,High Temp
CV-2306-PLR	9/14/2026 10:16:00 AM				AtmAA
CV-2306-PLR	9/28/2026 10:16:32 AM	1348	34.4360900	-118.6478094	Valve Adjustment:No Flow Measurement,High Temp
CV-2306-PLR	9/28/2026 10:20:00 AM				AtmAA
CV-2308-PLR	9/3/2026 8:03:28 AM	1330	34.4359090	-118.6489253	Barely Open,Surging Liquid in Well (Watered In);Well Comment:No pump
CV-2308-PLR	9/21/2026 8:50:45 AM	1339	34.4359077	-118.6488948	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2310-PLR	9/3/2026 7:36:11 AM	1358	34.4353272	-118.6491432	Valve Adjustment:No Flow Measurement,High Temp
CV-2310-PLR	9/3/2026 7:40:00 AM				AtmAA
CV-2310-PLR	9/3/2026 7:40:00 AM				AtmAA; [User entered 17.2%]
CV-2310-PLR	9/9/2026 8:56:24 AM	1365	34.4353443	-118.6491270	Valve Adjustment:No Flow Measurement,High Temp
CV-2310-PLR	9/9/2026 8:59:00 AM				AtmAA
CV-2310-PLR	9/15/2026 9:36:20 AM	1350	34.4353240	-118.6491389	Valve Adjustment:No Flow Measurement,High Temp
CV-2310-PLR	9/15/2026 9:38:00 AM				AtmAA
CV-2310-PLR	9/22/2026 9:28:31 AM	1347	34.4353372	-118.6491464	Valve Adjustment:No Flow Measurement,High Temp
CV-2310-PLR	9/22/2026 9:31:00 AM				AtmAA
CV-2310-PLR	9/29/2026 8:57:01 AM	1368	34.4353250	-118.6491155	Valve Adjustment:Audible Flow,No Flow Measurement,High Temp,Valve 100% Open
CV-2310-PLR	9/29/2026 9:00:00 AM				AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2311	9/8/2026 3:18:24 PM	1367	34.4362903	-118.6498959	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2311	9/8/2026 3:20:00 PM				AtmAA
CV-2311	9/15/2026 8:20:03 AM	1369	34.4363251	-118.6498674	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2311	9/15/2026 8:21:00 AM				AtmAA
CV-2311	9/21/2026 2:22:27 PM	1368	34.4363155	-118.6498575	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2311	9/21/2026 2:26:00 PM				AtmAA
CV-2311	9/28/2026 3:16:00 PM				AtmAA
CV-2311	9/28/2026 3:16:22 PM	1374	34.4363078	-118.6498885	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2312-PLR	9/2/2026 8:09:16 AM	1380	34.4342335	-118.6473823	Valve Adjustment:No Flow Measurement,High Temp
CV-2312-PLR	9/3/2026 7:00:00 AM				AirTech Lab
CV-2312-PLR	9/3/2026 7:00:00 AM				AirTech Lab; [User entered 16%]
CV-2312-PLR	9/9/2026 1:24:41 PM	1369	34.4342328	-118.6473481	Valve Adjustment:No Flow Measurement,High Temp
CV-2312-PLR	9/9/2026 1:35:00 PM				AtmAA
CV-2312-PLR	9/16/2026 10:30:00 AM				AtmAA
CV-2312-PLR	9/16/2026 10:44:19 AM	1371	34.4342158	-118.6473707	Valve Adjustment:No Flow Measurement,High Temp
CV-2312-PLR	9/23/2026 10:29:16 AM	1353	34.4342124	-118.6473826	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2312-PLR	9/23/2026 10:31:00 AM				AtmAA
CV-2312-PLR	9/23/2026 1:10:56 PM	1393	34.4342099	-118.6473883	Valve Adjustment:No Flow Measurement,High Temp
CV-2312-PLR	9/30/2026 9:44:29 AM	1387	34.4342013	-118.6473798	Valve Adjustment:No Flow Measurement,High Temp
CV-2312-PLR	9/30/2026 9:50:00 AM				AtmAA
CV-2314-PLR	9/1/2026 1:32:37 PM	1382	34.4346889	-118.6467118	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PLR	9/1/2026 1:38:00 PM				AtmAA
CV-2314-PLR	9/1/2026 1:38:00 PM				AtmAA; [User entered 12.01%]
CV-2314-PLR	9/4/2026 7:56:00 AM				AirTech Lab
CV-2314-PLR	9/4/2026 7:56:00 AM				AirTech Lab; [User entered 13%]
CV-2314-PLR	9/9/2026 1:40:13 PM	1369	34.4346946	-118.6466922	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PLR	9/9/2026 1:46:00 PM				AtmAA
CV-2314-PLR	9/16/2026 9:36:00 AM				AtmAA
CV-2314-PLR	9/16/2026 9:39:58 AM	1372	34.4346964	-118.6467225	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PLR	9/23/2026 9:37:50 AM	1375	34.4346966	-118.6466901	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PLR	9/23/2026 9:40:00 AM				AtmAA
CV-2314-PLR	9/30/2026 8:54:14 AM	1372	34.4347186	-118.6467117	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2314-PLR	9/30/2026 9:00:00 AM				AtmAA
CV-2315	9/3/2026 9:13:05 AM	1377	34.4355163	-118.6472132	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2315	9/3/2026 9:17:00 AM				AtmAA
CV-2315	9/3/2026 9:17:00 AM				AtmAA; [User entered 12.38%]
CV-2315	9/4/2026 8:04:00 AM				AirTech Lab
CV-2315	9/4/2026 8:04:00 AM				AirTech Lab; [User entered 17%]
CV-2315	9/8/2026 1:48:37 PM	1393	34.4355047	-118.6471882	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2315	9/8/2026 1:51:00 PM				AtmAA
CV-2315	9/14/2026 10:40:35 AM	1375	34.4355061	-118.6471957	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2315	9/14/2026 10:44:00 AM				AtmAA
CV-2315	9/21/2026 10:37:20 AM	1368	34.4355172	-118.6472012	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2315	9/21/2026 10:41:00 AM				AtmAA
CV-2315	9/28/2026 10:36:48 AM	1371	34.4355098	-118.6471987	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2315	9/28/2026 10:40:00 AM				AtmAA
CV-2316	9/2/2026 1:39:54 PM	1401	34.4360321	-118.6463818	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2316	9/2/2026 1:45:00 PM				AtmAA
CV-2316	9/2/2026 1:45:00 PM				AtmAA; [User entered 8.86%]
CV-2316	9/3/2026 9:48:34 AM	1384	34.4360245	-118.6463840	Valve Adjustment:High Temp
CV-2316	9/10/2026 10:21:00 AM				AtmAA
CV-2316	9/10/2026 10:23:35 AM	1395	34.4360408	-118.6463790	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2316	9/14/2026 1:56:00 PM				AtmAA
CV-2316	9/14/2026 2:22:00 PM	1404	34.4360329	-118.6463813	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2316	9/21/2026 1:35:00 PM				AtmAA
CV-2316	9/21/2026 1:37:31 PM	1394	34.4360366	-118.6463749	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2319	9/2/2026 1:50:00 PM				AtmAA
CV-2319	9/2/2026 1:50:00 PM				AtmAA; [User entered 8.02%]
CV-2319	9/2/2026 1:58:16 PM	1408	34.4353020	-118.6458036	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2319	9/2/2026 1:59:13 PM	1408	34.4353000	-118.6457999	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2319	9/9/2026 12:48:41 PM	1407	34.4352842	-118.6457913	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2319	9/9/2026 1:00:00 PM				AtmAA
CV-2319	9/15/2026 2:22:47 PM	1395	34.4353008	-118.6457986	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2319	9/15/2026 2:25:00 PM				AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2319	9/22/2026 9:40:58 AM	1397	34.4353070	-118.6458138	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-2319	9/22/2026 2:35:00 PM				AtmAA
CV-2319	9/22/2026 2:40:31 PM	1392	34.4352891	-118.6457993	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2319	9/22/2026 2:41:24 PM	1394	34.4352976	-118.6457940	Valve Adjustment:NSPS/EG CAC,High Temp;Well Condition:Lorentz Pump Installed
CV-2319	9/29/2026 1:53:56 PM	1373	34.4352995	-118.6458137	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2319	9/29/2026 2:00:00 PM				AtmAA
CV-2321	9/1/2026 8:55:00 AM				AtmAA
CV-2321	9/1/2026 8:55:00 AM				AtmAA; [User entered 7.66%]
CV-2321	9/1/2026 8:56:13 AM	1406	34.4346429	-118.6453729	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2321	9/9/2026 10:11:41 AM	1396	34.4346090	-118.6453764	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2321	9/9/2026 10:15:00 AM				AtmAA
CV-2321	9/15/2026 1:25:04 PM	1408	34.4346343	-118.6454037	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2321	9/22/2026 9:56:29 AM	1374	34.4346362	-118.6453545	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open
CV-2321	9/29/2026 1:15:00 PM				AtmAA
CV-2321	9/29/2026 1:21:59 PM	1399	34.4346180	-118.6453840	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2321	9/29/2026 1:22:57 PM	1400	34.4346237	-118.6453867	Well Condition:Lorentz Pump Installed
CV-2322	9/1/2026 1:56:33 PM	1371	34.4352744	-118.6475555	Valve Adjustment:No Flow Measurement,High Temp
CV-2322	9/1/2026 2:00:00 PM				AtmAA
CV-2322	9/1/2026 2:00:00 PM				AtmAA; [User entered 10.92%]
CV-2322	9/10/2026 8:31:00 AM				AtmAA
CV-2322	9/10/2026 8:31:01 AM	1378	34.4352672	-118.6475025	Valve Adjustment:No Flow Measurement,High Temp
CV-2322	9/17/2026 12:50:31 PM	1370	34.4352801	-118.6475496	Valve Adjustment:No Flow Measurement
CV-2324	9/3/2026 1:08:01 PM	1390	34.4345000	-118.6442427	Valve Adjustment:Barely Open
CV-2326	9/3/2026 9:35:00 AM				AtmAA
CV-2326	9/3/2026 9:35:00 AM				AtmAA; [User entered 15.38%]
CV-2326	9/3/2026 9:35:50 AM	1373	34.4361365	-118.6504865	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2326	9/3/2026 1:14:03 PM	1380	34.4345763	-118.6441043	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Barely Open,Surging Liquid in Header
CV-2326	9/8/2026 3:25:00 PM				AtmAA
CV-2326	9/8/2026 3:25:03 PM	1369	34.4361090	-118.6504464	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2326	9/15/2026 8:24:00 AM				AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2326	9/15/2026 8:25:39 AM	1372	34.4361394	-118.6504627	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2326	9/21/2026 2:28:46 PM	1366	34.4361214	-118.6504334	Valve Adjustment:Audible Flow,High Temp;Well Condition:Lorentz Pump Installed
CV-2326	9/21/2026 2:31:00 PM				AtmAA
CV-2326	9/28/2026 3:18:43 PM	1375	34.4361087	-118.6504566	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2326	9/28/2026 3:20:00 PM				AtmAA
CV-2327	9/14/2026 10:24:05 AM	1299	34.4349290	-118.6479637	NSPS/EG CAI,High Temp
CV-2327	9/14/2026 10:26:47 AM	1325	34.4349483	-118.6478963	NSPS/EG CAI,High Temp
CV-2327	9/14/2026 1:30:00 PM				AtmAA
CV-2327	9/21/2026 8:50:00 AM				AtmAA
CV-2327	9/21/2026 8:58:34 AM	1361	34.4348928	-118.6479362	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2327	9/21/2026 9:11:07 AM	1366	34.4348934	-118.6479396	Valve Adjustment:No Flow Measurement,High Temp
CV-2327	9/30/2026 9:14:10 AM	1356	34.4348937	-118.6479513	Valve Adjustment:No Flow Measurement,High Temp
CV-2328	9/1/2026 2:21:10 PM	1355	34.4343036	-118.6483598	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2328	9/1/2026 2:25:00 PM				AtmAA
CV-2328	9/1/2026 2:25:00 PM				AtmAA; [User entered 0.26%]
CV-2328	9/9/2026 7:45:00 AM				AirTech Lab
CV-2328	9/9/2026 7:45:00 AM				AirTech Lab; [User entered 6.2%]
CV-2328	9/9/2026 1:45:59 PM	1357	34.4343150	-118.6483458	Well Condition:Lorentz Pump Installed
CV-2328	9/24/2026 10:56:47 AM	1364	34.4343292	-118.6483413	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-2328	9/24/2026 10:58:35 AM	1357	34.4343182	-118.6483530	
CV-2328	9/28/2026 2:24:07 PM	1343	34.4343018	-118.6483585	Valve Adjustment:High Temp
CV-2328	9/30/2026 8:52:17 AM	1357	34.4343249	-118.6483597	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2328	9/30/2026 8:55:00 AM				AtmAA
CV-2333	9/3/2026 7:45:00 AM				AirTech Lab
CV-2333	9/3/2026 7:45:00 AM				AirTech Lab; [User entered 19%]
CV-2333	9/8/2026 9:30:41 AM	1365	34.4365099	-118.6473866	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2333	9/8/2026 9:35:00 AM				AtmAA
CV-2333	9/14/2026 8:23:05 AM	1363	34.4365145	-118.6473733	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2333	9/14/2026 8:25:00 AM				AtmAA
CV-2333	9/21/2026 8:18:24 AM	1348	34.4365245	-118.6473638	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2333	9/21/2026 8:21:00 AM				AtmAA
CV-2333	9/28/2026 8:05:00 AM				AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2333	9/28/2026 8:08:07 AM	1358	34.4365184	-118.6473623	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2334	9/3/2026 7:50:00 AM				AirTech Lab
CV-2334	9/3/2026 7:50:00 AM				AirTech Lab; [User entered 14%]
CV-2334	9/9/2026 12:10:26 PM	1384	34.4366652	-118.6467085	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2334	9/9/2026 12:10:43 PM	1361	34.4366657	-118.6467037	Valve Adjustment:High Temp,Barely Open
CV-2334	9/17/2026 12:59:56 PM	1357	34.4366728	-118.6466527	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2334	9/17/2026 1:03:00 PM				AtmAA
CV-2334	9/24/2026 1:25:00 PM				AtmAA
CV-2334	9/24/2026 1:44:17 PM	1376	34.4366794	-118.6466942	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2334	9/24/2026 1:45:33 PM	1375	34.4366780	-118.6467040	Valve Adjustment:NSPS/EG CAC,High Temp;Well Condition:Lorentz Pump Installed
CV-2335	9/14/2026 9:41:03 AM	1320	34.4364225	-118.6509372	Valve Adjustment:Barely Open
CV-2335	9/16/2026 2:27:40 PM	1325	34.4363800	-118.6509645	Valve Adjustment:Increased Flow/Vacuum,Barely Open
CV-2336	9/14/2026 9:45:07 AM	1346	34.4359667	-118.6508977	Valve Adjustment:Barely Open
CV-2336	9/16/2026 2:20:41 PM	1325	34.4359835	-118.6508803	Valve Adjustment:Barely Open
CV-2337	9/8/2026 10:57:52 AM	1289	34.4354205	-118.6507197	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-2337	9/8/2026 11:00:00 AM				AtmAA
CV-2337	9/10/2026 9:00:00 AM				AirTech Lab
CV-2337	9/10/2026 9:00:00 AM				AirTech Lab; [User entered 10%]
CV-2337	9/16/2026 2:13:00 PM				AtmAA
CV-2337	9/16/2026 2:19:44 PM	1332	34.4354445	-118.6507553	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2337	9/23/2026 2:21:00 PM				AtmAA
CV-2337	9/23/2026 2:21:55 PM	1314	34.4354555	-118.6507592	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2337	9/30/2026 2:15:00 PM				AtmAA
CV-2337	9/30/2026 2:20:16 PM	1330	34.4354513	-118.6507534	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2338	9/8/2026 11:13:27 AM	1385	34.4348540	-118.6505495	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-2338	9/8/2026 11:15:00 AM				AtmAA
CV-2338	9/16/2026 2:23:00 PM				AtmAA
CV-2338	9/16/2026 2:28:52 PM	1313	34.4348596	-118.6504742	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2338	9/23/2026 2:29:15 PM	1308	34.4348637	-118.6504801	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2338	9/23/2026 2:34:00 PM				AtmAA
CV-2338	9/30/2026 2:30:00 PM				AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2338	9/30/2026 2:35:34 PM	1313	34.4348405	-118.6504515	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.;Well Comment:Vacuum line being worked on;Well Condition:Lorentz Pump Installed
CV-2339	9/14/2026 2:04:24 PM	1289	34.4342345	-118.6501797	NSPS/EG CAI,High O2
CV-2339	9/14/2026 2:06:28 PM	1276	34.4342873	-118.6502115	NSPS/EG CAI,High O2
CV-2339	9/30/2026 3:45:57 PM	1299	34.4341737	-118.6502555	Valve Adjustment:NSPS/EG CAI,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2341	9/10/2026 8:29:15 AM	1319	34.4336210	-118.6501692	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open
CV-2341	9/10/2026 8:30:27 AM	1315	34.4336098	-118.6501748	Valve Adjustment:NSPS/EG CAC
CV-2341	9/10/2026 8:45:00 AM				AirTech Lab
CV-2341	9/10/2026 8:45:00 AM				AirTech Lab; [User entered 22.%]
CV-2341	9/24/2026 2:48:06 PM	1298	34.4336428	-118.6502110	Valve Adjustment:Decreased Flow/Vacuum
CV-2342A-PL	9/1/2026 1:37:03 PM	1281	34.4342130	-118.6508421	Valve Adjustment:No Flow Measurement
CV-2342A-PL	9/8/2026 2:08:22 PM	1283	34.4341195	-118.6508555	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-2342A-PL	9/8/2026 2:17:58 PM	1240	34.4342202	-118.6509147	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-2342A-PL	9/8/2026 2:20:00 PM				AtmAA
CV-2342A-PL	9/14/2026 1:57:27 PM	1285	34.4342257	-118.6508585	Valve Adjustment:No Flow Measurement,High Temp
CV-2342A-PL	9/14/2026 2:10:00 PM				AtmAA
CV-2342A-PL	9/24/2026 9:32:37 AM	1295	34.4342028	-118.6508542	Valve Adjustment:No Flow Measurement,High Temp
CV-2342A-PL	9/24/2026 9:35:00 AM				AtmAA
CV-2343-PLR	9/1/2026 1:05:42 PM	1290	34.4332371	-118.6506988	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2343-PLR	9/1/2026 1:25:00 PM				AtmAA
CV-2343-PLR	9/1/2026 1:25:00 PM				AtmAA; [User entered 15.77%]
CV-2343-PLR	9/8/2026 1:57:49 PM	1243	34.4333050	-118.6508090	NSPS/EG CAI,High Temp,Positive Static Press.,Reduced System Vacuum,Increased Flow/Vacuum
CV-2343-PLR	9/8/2026 1:59:45 PM	1280	34.4332792	-118.6507595	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-2343-PLR	9/8/2026 2:00:00 PM				AtmAA
CV-2343-PLR	9/14/2026 1:47:19 PM	1284	34.4332413	-118.6506910	Valve Adjustment:No Flow Measurement,High Temp
CV-2343-PLR	9/14/2026 1:50:00 PM				AtmAA
CV-2343-PLR	9/16/2026 12:27:21 PM	1284	34.4332342	-118.6506825	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Comment:wellhead exchanged
CV-2343-PLR	9/24/2026 9:22:03 AM	1295	34.4332384	-118.6506933	Valve Adjustment:No Flow Measurement,High Temp
CV-2343-PLR	9/24/2026 9:25:00 AM				AtmAA
CV-2344	9/1/2026 7:15:00 AM				Air Tech Lab

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2344	9/1/2026 12:55:13 PM	1303	34.4329697	-118.6504470	Valve Adjustment:No Flow Measurement;Well Condition:Lorentz Pump Installed
CV-2344	9/1/2026 7:15:00 PM				Air Tech Lab; [User entered 11%]
CV-2344	9/8/2026 1:49:02 PM	1312	34.4329567	-118.6504552	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-2344	9/8/2026 1:50:00 PM				AtmAA
CV-2344	9/8/2026 1:50:10 PM	1312	34.4329982	-118.6504473	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-2344	9/14/2026 10:26:52 AM	1261	34.4329687	-118.6504562	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2344	9/14/2026 10:32:00 AM				AtmAA
CV-2344	9/24/2026 9:12:30 AM	1294	34.4329704	-118.6504398	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2344	9/24/2026 9:15:00 AM				AtmAA
CV-2345	9/1/2026 7:10:00 AM				Air Tech Lab
CV-2345	9/1/2026 7:10:00 AM				Air Tech Lab; [User entered 3.3%]
CV-2345	9/2/2026 7:32:38 AM	1250	34.4327250	-118.6502150	Reduced System Vacuum,
CV-2345	9/22/2026 11:32:10 AM	1309	34.4327020	-118.6502423	,
CV-2346	9/1/2026 7:05:00 AM				Air Tech Lab
CV-2346	9/1/2026 7:05:00 AM				Air Tech Lab; [User entered 5.3%]
CV-2346	9/1/2026 10:35:00 AM				AtmAA
CV-2346	9/1/2026 10:35:00 AM				AtmAA; [User entered 1.66%]
CV-2346	9/1/2026 10:36:56 AM	1296	34.4326020	-118.6500622	Valve Adjustment:No Flow Measurement,High Temp
CV-2346	9/8/2026 2:30:00 PM				AtmAA
CV-2346	9/8/2026 2:32:55 PM	1365	34.4325310	-118.6501422	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-2346	9/14/2026 10:07:15 AM	1309	34.4325858	-118.6500830	Valve Adjustment:No Adjustments Made
CV-2346	9/14/2026 10:09:25 AM	1310	34.4325877	-118.6500700	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2346	9/14/2026 10:10:00 AM				AtmAA
CV-2346	9/24/2026 9:05:00 AM				AtmAA
CV-2346	9/24/2026 9:07:33 AM	1297	34.4325957	-118.6500783	Valve Adjustment:No Flow Measurement,High Temp
CV-2347	9/1/2026 6:55:00 AM				Air Tech Lab
CV-2347	9/1/2026 6:55:00 AM				Air Tech Lab; [User entered 4.6%]
CV-2347	9/2/2026 7:17:45 AM	1316	34.4323070	-118.6498862	,
CV-2347	9/22/2026 12:05:58 PM	1302	34.4324020	-118.6497328	,
CV-2348	9/1/2026 6:50:00 AM				Air Tech Lab; [User entered 2.8%]
CV-2348	9/1/2026 6:50:00 PM				Air Tech Lab
CV-2348	9/2/2026 7:12:27 AM	1342	34.4322007	-118.6496217	NSPS/EG CAI,High Temp
CV-2348	9/2/2026 7:13:13 AM	1362	34.4321802	-118.6497023	NSPS/EG CAI,High Temp
CV-2348	9/22/2026 12:12:09 PM	1217	34.4321953	-118.6496317	NSPS/EG CAI,High Temp
CV-2348	9/22/2026 12:13:11 PM	1296	34.4320917	-118.6496172	NSPS/EG CAI,High Temp

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2349	9/1/2026 2:05:00 AM				AtmAA; [User entered 15.19%]
CV-2349	9/1/2026 2:02:58 PM	1270	34.4331388	-118.6512676	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2349	9/1/2026 2:05:00 PM				AtmAA
CV-2349	9/2/2026 7:50:00 AM				AirTech Lab
CV-2349	9/2/2026 7:50:00 AM				AirTech Lab; [User entered 20%]
CV-2349	9/8/2026 1:35:00 PM				AtmAA
CV-2349	9/8/2026 1:37:23 PM	1227	34.4331148	-118.6512575	NSPS/EG CAI,High Temp,Positive Static Press.,Reduced System Vacuum
CV-2349	9/8/2026 1:38:01 PM	1247	34.4330518	-118.6511642	NSPS/EG CAI,High Temp,Positive Static Press.,Reduced System Vacuum
CV-2349	9/17/2026 9:37:56 AM	1265	34.4331102	-118.6512541	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Valve 100% Open,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-2349	9/17/2026 9:40:00 AM				AtmAA
CV-2349	9/24/2026 9:55:30 AM	1252	34.4331430	-118.6512350	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2349	9/24/2026 10:05:00 AM				AtmAA
CV-2350	9/1/2026 7:20:00 AM				Air Tech Lab
CV-2350	9/1/2026 7:20:00 AM				Air Tech Lab; [User entered 17%]
CV-2350	9/2/2026 8:27:52 AM	1247	34.4327690	-118.6508805	Reduced System Vacuum,
CV-2350	9/23/2026 9:06:15 AM	1281	34.4327615	-118.6509092	Well Comment:valve stuck open
CV-2351	9/2/2026 7:15:00 AM				AirTech Lab
CV-2351	9/2/2026 7:15:00 AM				AirTech Lab; [User entered 2.7%]
CV-2351	9/10/2026 12:26:23 PM	1304	34.4351275	-118.6511270	Valve Adjustment:NSPS/EG CAI,High O2,Surging Liquid in Well (Watered In)
CV-2351	9/10/2026 12:27:25 PM	1287	34.4351427	-118.6511517	
CV-2351	9/23/2026 9:53:22 AM	1285	34.4351298	-118.6511233	Valve Adjustment:High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected;Well Comment:valve stuck open
CV-2352	9/2/2026 7:20:00 AM				AirTech Lab
CV-2352	9/2/2026 7:20:00 AM				AirTech Lab; [User entered 19%]
CV-2352	9/10/2026 11:57:24 AM	1280	34.4348732	-118.6510500	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed
CV-2352	9/10/2026 11:59:11 AM	1292	34.4348675	-118.6510410	
CV-2352	9/30/2026 3:26:31 PM	1286	34.4348750	-118.6510445	Valve Adjustment:High Temp
CV-2353-PLR	9/2/2026 7:54:07 AM	1312	34.4345678	-118.6509308	Reduced System Vacuum,
CV-2353-PLR	9/10/2026 8:40:00 AM				AirTech Lab
CV-2353-PLR	9/10/2026 8:40:00 AM				AirTech Lab; [User entered 23%]

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2353-PLR	9/30/2026 4:20:22 PM	1278	34.4345265	-118.6508893	Valve Adjustment:High Temp,High O2
CV-2354	9/2/2026 7:45:00 AM				AirTech Lab
CV-2354	9/2/2026 7:45:00 AM				AirTech Lab; [User entered 15%]
CV-2354	9/2/2026 8:05:50 AM	1263	34.4336987	-118.6514048	NSPS/EG CAI,High Temp,Positive Static Press.
CV-2354	9/2/2026 8:06:24 AM	1240	34.4337187	-118.6514173	NSPS/EG CAI,High Temp,Positive Static Press.
CV-2354	9/8/2026 8:08:52 AM	1266	34.4336934	-118.6513447	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2354	9/8/2026 8:10:05 AM	1266	34.4336935	-118.6513427	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2354	9/8/2026 9:08:00 AM				AtmAA
CV-2354	9/17/2026 9:46:30 AM	1265	34.4337095	-118.6513658	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2354	9/17/2026 9:50:00 AM				AtmAA
CV-2354	9/24/2026 9:34:17 AM	1295	34.4342026	-118.6508543	Valve Adjustment:No Flow Measurement,High Temp
CV-2354	9/24/2026 9:47:15 AM	1254	34.4337008	-118.6513581	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2354	9/24/2026 9:50:00 AM				AtmAA
CV-24001	9/10/2026 9:02:39 AM	1352	34.4366348	-118.6508967	Valve Adjustment:Increased Flow/Vacuum
CV-24001	9/16/2026 2:35:59 PM	1332	34.4366398	-118.6509068	Valve Adjustment:Barely Open
CV-24002	9/10/2026 8:53:47 AM	1361	34.4367377	-118.6504760	Valve Adjustment:Decreased Flow/Vacuum
CV-24002	9/16/2026 2:44:36 PM	1311	34.4366973	-118.6504535	Valve Adjustment:Barely Open
CV-24003	9/14/2026 9:33:43 AM	1333	34.4368852	-118.6500838	Valve Adjustment:Barely Open
CV-24003	9/16/2026 2:48:11 PM	1339	34.4368830	-118.6500785	Valve Adjustment:Barely Open
CV-24004	9/1/2026 11:16:57 AM	1348	34.4370328	-118.6496633	Valve Adjustment:Audible Flow
CV-24004	9/16/2026 12:39:13 PM	1364	34.4370578	-118.6496768	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24006	9/1/2026 11:38:09 AM	1375	34.4363523	-118.6504703	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24006	9/1/2026 11:38:58 AM	1372	34.4363530	-118.6504393	Valve Adjustment:NSPS/EG CAC
CV-24006	9/16/2026 1:53:51 PM	1349	34.4363735	-118.6504443	Valve Adjustment:Barely Open
CV-24007	9/1/2026 1:41:17 PM	1361	34.4365283	-118.6501310	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-24007	9/3/2026 7:10:00 AM				AirTech Lab
CV-24007	9/3/2026 7:10:00 AM				AirTech Lab; [User entered 5.1%]
CV-24007	9/8/2026 3:13:15 PM	1370	34.4364987	-118.6501064	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-24007	9/8/2026 3:15:00 PM				AtmAA
CV-24007	9/15/2026 8:10:00 AM				AtmAA
CV-24007	9/15/2026 8:12:16 AM	1374	34.4365268	-118.6501282	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24007	9/29/2026 9:01:50 AM	1377	34.4365120	-118.6501192	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down;Well Condition:Pnumatic Pump Installed
CV-24007	9/29/2026 9:03:57 AM	1380	34.4365257	-118.6501017	
CV-24007	9/29/2026 9:55:00 AM				AtmAA
CV-24008	9/8/2026 3:07:24 PM	1375	34.4366657	-118.6496974	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24008	9/8/2026 3:09:00 PM				AtmAA
CV-24008	9/14/2026 2:57:03 PM	1373	34.4366238	-118.6497072	Valve Adjustment:No Flow Measurement,High Temp
CV-24008	9/14/2026 2:59:00 PM				AtmAA
CV-24008	9/21/2026 2:19:31 PM	1372	34.4366686	-118.6496892	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-24008	9/21/2026 2:20:00 PM				AtmAA
CV-24008	9/28/2026 3:12:00 PM				AtmAA
CV-24008	9/28/2026 3:12:04 PM	1378	34.4366678	-118.6496964	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24009	9/8/2026 3:00:41 PM	1382	34.4368755	-118.6493586	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-24009	9/8/2026 3:03:00 PM				AtmAA
CV-24009	9/14/2026 2:51:55 PM	1369	34.4368685	-118.6493755	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-24009	9/14/2026 2:52:00 PM				AtmAA
CV-24009	9/21/2026 2:14:38 PM	1370	34.4368672	-118.6493469	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-24009	9/21/2026 2:15:00 PM				AtmAA
CV-24009	9/28/2026 2:54:10 PM	1375	34.4368671	-118.6493531	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-24009	9/28/2026 3:05:00 PM				AtmAA
CV-24010	9/14/2026 1:20:33 PM	1363	34.4371042	-118.6489715	Valve Adjustment:Barely Open
CV-24010	9/23/2026 1:13:43 PM	1350	34.4370870	-118.6489565	Valve Adjustment:Barely Open,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-24011	9/10/2026 1:14:00 PM				AtmAA
CV-24011	9/10/2026 1:15:42 PM	1384	34.4361872	-118.6502029	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24011	9/15/2026 8:34:00 AM				AtmAA
CV-24011	9/15/2026 8:38:24 AM	1384	34.4362010	-118.6501764	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24011	9/22/2026 8:35:45 AM	1341	34.4361923	-118.6501664	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24011	9/22/2026 8:37:00 AM				AtmAA
CV-24011	9/29/2026 8:04:57 AM	1361	34.4362013	-118.6501706	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24011	9/29/2026 8:10:00 AM				AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24012	9/10/2026 1:34:00 PM				AtmAA
CV-24012	9/10/2026 1:36:19 PM	1369	34.4361742	-118.6493643	Valve Adjustment:No Flow Measurement,High Temp
CV-24012	9/15/2026 8:57:47 AM	1369	34.4361759	-118.6493347	Valve Adjustment:No Flow Measurement,High Temp
CV-24012	9/15/2026 8:59:00 AM				AtmAA
CV-24012	9/22/2026 8:52:16 AM	1353	34.4361728	-118.6493825	Valve Adjustment:No Flow Measurement,High Temp
CV-24012	9/22/2026 8:55:00 AM				AtmAA
CV-24012	9/29/2026 8:25:00 AM				AtmAA
CV-24012	9/29/2026 8:26:34 AM	1356	34.4361859	-118.6493574	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum,Barely Open
CV-24012	9/29/2026 8:27:45 AM	1358	34.4361736	-118.6493564	Well Condition:Lorentz Pump Installed
CV-24013	9/8/2026 2:55:00 PM				AtmAA
CV-24013	9/8/2026 2:55:38 PM	1387	34.4365995	-118.6492325	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24013	9/14/2026 2:41:00 PM				AtmAA
CV-24013	9/14/2026 2:45:29 PM	1371	34.4366229	-118.6492451	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24013	9/21/2026 2:06:00 PM				AtmAA
CV-24013	9/21/2026 2:06:42 PM	1367	34.4366246	-118.6492122	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24013	9/22/2026 9:07:43 AM				Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24013	9/28/2026 2:25:03 PM	1376	34.4366042	-118.6492379	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24013	9/28/2026 2:34:21 PM	1376	34.4366053	-118.6492389	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24013	9/28/2026 2:46:14 PM	1377	34.4366090	-118.6492370	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-24013	9/28/2026 3:05:00 PM				AtmAA
CV-24014	9/8/2026 10:27:00 AM				AtmAA
CV-24014	9/8/2026 10:29:18 AM	1361	34.4367643	-118.6489806	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24014	9/14/2026 9:42:29 AM	1363	34.4367784	-118.6489729	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24014	9/14/2026 9:47:00 AM				AtmAA
CV-24014	9/21/2026 9:59:00 AM				AtmAA
CV-24014	9/21/2026 10:01:34 AM	1365	34.4367976	-118.6489447	Valve Adjustment:No Flow Measurement,High Temp
CV-24014	9/28/2026 9:50:00 AM				AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24014	9/28/2026 9:51:51 AM	1347	34.4367763	-118.6489531	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24015	9/8/2026 10:15:00 AM				AtmAA
CV-24015	9/8/2026 10:15:01 AM	1352	34.4368700	-118.6486089	Valve Adjustment:No Flow Measurement,High Temp
CV-24015	9/14/2026 9:33:41 AM	1346	34.4368816	-118.6486166	Valve Adjustment:No Flow Measurement,High Temp
CV-24015	9/14/2026 9:37:00 AM				AtmAA
CV-24015	9/21/2026 9:43:08 AM	1350	34.4368824	-118.6486319	Valve Adjustment:No Flow Measurement,High Temp
CV-24015	9/21/2026 9:47:00 AM				AtmAA
CV-24015	9/28/2026 9:20:40 AM	1343	34.4368759	-118.6486242	Valve Adjustment:No Flow Measurement,High Temp
CV-24015	9/28/2026 9:25:00 AM				AtmAA
CV-24016	9/10/2026 1:20:58 PM	1391	34.4358974	-118.6502815	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24016	9/10/2026 1:23:00 PM				AtmAA
CV-24016	9/15/2026 8:42:34 AM	1383	34.4359138	-118.6502500	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24016	9/15/2026 8:46:00 AM				AtmAA
CV-24016	9/22/2026 8:41:38 AM	1355	34.4359252	-118.6502371	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24016	9/22/2026 8:43:00 AM				AtmAA
CV-24016	9/29/2026 8:07:47 AM	1357	34.4359123	-118.6502410	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24016	9/29/2026 8:15:00 AM				AtmAA
CV-24017	9/9/2026 7:35:00 AM				AirTech Lab
CV-24017	9/9/2026 7:35:00 AM				AirTech Lab; [User entered 16%]
CV-24017	9/9/2026 8:19:35 AM	1355	34.4361280	-118.6497792	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	9/9/2026 8:21:00 AM				AtmAA
CV-24017	9/15/2026 8:47:21 AM	1373	34.4361095	-118.6498125	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	9/15/2026 8:51:00 AM				AtmAA
CV-24017	9/22/2026 8:31:00 AM				AtmAA
CV-24017	9/22/2026 8:31:48 AM	1362	34.4361166	-118.6497614	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	9/29/2026 8:02:00 AM	1359	34.4361115	-118.6497831	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	9/29/2026 8:05:00 AM				AtmAA
CV-24018	9/1/2026 1:52:46 PM	1354	34.4356177	-118.6500745	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open
CV-24018	9/1/2026 1:53:33 PM	1360	34.4356027	-118.6500740	Valve Adjustment:High Temp

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24018	9/15/2026 9:11:09 AM	692	34.4355956	-118.6500720	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24018	9/24/2026 8:57:40 AM	1371	34.4355977	-118.6500652	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24018	9/24/2026 8:58:59 AM	1374	34.4355913	-118.6500765	
CV-24019	9/3/2026 7:27:00 AM				AtmAA
CV-24019	9/3/2026 7:27:00 AM				AtmAA; [User entered 15.8%]
CV-24019	9/3/2026 7:27:22 AM	1379	34.4357832	-118.6497926	Valve Adjustment:No Flow Measurement,High Temp
CV-24019	9/9/2026 8:36:17 AM	1362	34.4357937	-118.6497838	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24019	9/9/2026 8:39:00 AM				AtmAA
CV-24019	9/15/2026 9:06:46 AM	1350	34.4357762	-118.6497832	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24019	9/15/2026 9:09:00 AM				AtmAA
CV-24019	9/22/2026 9:08:00 AM				AtmAA
CV-24019	9/24/2026 10:45:00 AM				AtmAA
CV-24019	9/24/2026 10:45:17 AM	1335	34.4357863	-118.6497607	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24019	9/29/2026 8:43:49 AM	1355	34.4357927	-118.6497724	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24019	9/29/2026 8:45:00 AM				AtmAA
CV-24020	9/3/2026 8:44:20 AM	1370	34.4359895	-118.6493590	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In);Well Comment:No pump
CV-24020	9/3/2026 8:45:27 AM	1348	34.4359842	-118.6493688	
CV-24020	9/21/2026 8:32:06 AM	1351	34.4360042	-118.6493535	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In);Well Comment:No pump
CV-24020	9/21/2026 8:33:17 AM	1353	34.4359973	-118.6493502	
CV-24021	9/3/2026 8:33:42 AM	1358	34.4361612	-118.6490398	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-24021	9/3/2026 8:39:22 AM	1375	34.4361472	-118.6490668	
CV-24021	9/3/2026 1:27:00 PM				AtmAA
CV-24021	9/3/2026 1:27:00 PM				AtmAA; [User entered 8.3%]
CV-24021	9/10/2026 1:38:53 PM	1370	34.4361774	-118.6490491	Valve Adjustment:No Flow Measurement
CV-24021	9/21/2026 8:38:36 AM	1356	34.4361513	-118.6490468	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Surging Liquid in Well (Watered In);Well Comment:NO PUMP
CV-24021	9/21/2026 8:39:59 AM	1357	34.4361525	-118.6490430	
CV-24022-PL	9/8/2026 10:34:00 AM				AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24022-PL	9/8/2026 10:34:57 AM	1365	34.4365224	-118.6488159	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24022-PL	9/14/2026 9:47:06 AM	1373	34.4364986	-118.6488295	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24022-PL	9/17/2026 1:14:16 PM				Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24022-PL	9/17/2026 1:15:00 PM				AtmAA
CV-24022-PL	9/21/2026 10:04:00 AM				AtmAA
CV-24022-PL	9/21/2026 10:05:58 AM	1361	34.4365111	-118.6488035	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24022-PL	9/28/2026 9:56:17 AM	1361	34.4365163	-118.6488077	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24022-PL	9/28/2026 10:05:00 AM				AtmAA
CV-24023	9/8/2026 10:21:52 AM	1362	34.4365840	-118.6484290	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24023	9/8/2026 10:23:00 AM				AtmAA
CV-24023	9/14/2026 9:37:06 AM	1355	34.4366167	-118.6484493	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24023	9/14/2026 9:41:00 AM				AtmAA
CV-24023	9/21/2026 9:52:32 AM	1363	34.4366003	-118.6484342	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24023	9/21/2026 9:53:00 AM				AtmAA
CV-24023	9/28/2026 9:32:30 AM	1360	34.4365946	-118.6484382	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24023	9/28/2026 9:33:25 AM	1360	34.4365945	-118.6484378	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24023	9/28/2026 9:35:00 AM				AtmAA
CV-24024-PL	9/14/2026 1:05:56 PM	1344	34.4368068	-118.6481622	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-24024-PL	9/14/2026 1:07:36 PM	1348	34.4367917	-118.6481548	
CV-24024-PL	9/14/2026 2:45:00 PM				AtmAA
CV-24024-PL	9/21/2026 9:33:56 AM	1338	34.4367904	-118.6481458	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24025	9/3/2026 7:56:02 AM	1348	34.4352944	-118.6499458	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24025	9/3/2026 8:00:00 AM				AtmAA
CV-24025	9/3/2026 8:00:00 AM				AtmAA; [User entered 12.73%]
CV-24025	9/9/2026 8:43:21 AM	1365	34.4353054	-118.6499108	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24025	9/9/2026 8:45:00 AM				AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24025	9/15/2026 9:18:02 AM	1358	34.4352859	-118.6499373	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24025	9/15/2026 9:19:00 AM				AtmAA
CV-24025	9/22/2026 9:13:58 AM	1350	34.4352819	-118.6499411	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24025	9/22/2026 9:16:00 AM				AtmAA
CV-24025	9/29/2026 8:49:38 AM	1351	34.4353089	-118.6499223	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24025	9/29/2026 8:50:00 AM				AtmAA
CV-24026	9/3/2026 7:33:18 AM	1356	34.4356545	-118.6492903	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24026	9/3/2026 7:34:00 AM				AtmAA
CV-24026	9/3/2026 7:34:00 AM				AtmAA; [User entered 19.67%]
CV-24026	9/9/2026 8:31:27 AM	1349	34.4356773	-118.6492750	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24026	9/21/2026 8:25:41 AM	1353	34.4356482	-118.6492617	Valve Adjustment:NSPS/EG CAI,High Temp;Well Condition:Lorentz Pump Installed
CV-24026	9/21/2026 8:26:47 AM	1358	34.4356468	-118.6492583	
CV-24026	9/28/2026 10:42:46 AM	1351	34.4356470	-118.6492477	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24026	9/29/2026 8:35:00 AM				AtmAA
CV-24026	9/29/2026 8:35:11 AM	1346	34.4356668	-118.6492720	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24027	9/9/2026 11:08:00 AM	1351	34.4361385	-118.6487050	Valve Adjustment:High O2,Barely Open
CV-24027	9/21/2026 8:45:43 AM	1354	34.4361070	-118.6487170	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Surging Liquid in Well (Watered In);Well Comment:Pump not working;Well Condition:Pnumatic Pump Installed
CV-24027	9/21/2026 8:46:35 AM	1353	34.4361088	-118.6487290	
CV-24028	9/8/2026 10:39:56 AM	1370	34.4363459	-118.6484646	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24028	9/8/2026 10:45:00 AM				AtmAA
CV-24028	9/14/2026 9:52:00 AM				AtmAA
CV-24028	9/14/2026 9:59:11 AM	1361	34.4363435	-118.6484890	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24028	9/21/2026 10:10:45 AM	1362	34.4363335	-118.6484631	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24028	9/21/2026 10:13:00 AM				AtmAA
CV-24028	9/28/2026 10:02:58 AM	1360	34.4363352	-118.6484677	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24028	9/28/2026 10:10:00 AM				AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24029	9/9/2026 10:30:51 AM	1350	34.4363975	-118.6480672	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24029	9/25/2026 10:15:36 AM	1350	34.4364608	-118.6480642	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24030	9/8/2026 9:51:00 AM				AtmAA
CV-24030	9/8/2026 9:52:46 AM	1351	34.4366496	-118.6478841	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24030	9/14/2026 8:52:00 AM				AtmAA
CV-24030	9/14/2026 9:02:11 AM	1339	34.4366591	-118.6478892	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24030	9/14/2026 9:08:34 AM	1340	34.4366684	-118.6478970	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24030	9/21/2026 9:12:52 AM	1331	34.4366503	-118.6479213	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24030	9/21/2026 9:15:00 AM				AtmAA
CV-24030	9/21/2026 9:21:19 AM	1335	34.4366513	-118.6479062	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24030	9/28/2026 8:35:00 AM				AtmAA
CV-24030	9/28/2026 8:36:53 AM	1347	34.4366413	-118.6478754	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24031	9/1/2026 2:26:16 PM	1352	34.4348793	-118.6498365	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-24031	9/3/2026 8:12:54 AM	1351	34.4348845	-118.6498232	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24031	9/3/2026 8:17:00 AM				AtmAA
CV-24031	9/3/2026 8:17:00 AM				AtmAA; [User entered 7.825%]
CV-24031	9/9/2026 9:07:06 AM	1357	34.4348880	-118.6498336	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24031	9/9/2026 9:10:00 AM				AtmAA
CV-24031	9/15/2026 9:52:53 AM				Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24031	9/15/2026 9:57:00 AM				AtmAA
CV-24031	9/22/2026 9:40:37 AM	1338	34.4348922	-118.6498337	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24031	9/22/2026 9:44:00 AM				AtmAA
CV-24031	9/29/2026 9:04:40 AM	1347	34.4348958	-118.6497962	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24031	9/29/2026 9:10:00 AM				AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24032	9/3/2026 7:35:00 AM				AtmAA
CV-24032	9/3/2026 8:05:00 AM				AtmAA; [User entered 13.94%]
CV-24032	9/3/2026 8:05:26 AM	1339	34.4351164	-118.6496223	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24032	9/3/2026 8:06:12 AM	1352	34.4351307	-118.6496275	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24032	9/9/2026 9:02:42 AM	1356	34.4351317	-118.6496053	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24032	9/9/2026 9:04:00 AM				AtmAA
CV-24032	9/15/2026 9:43:54 AM	1332	34.4350870	-118.6496251	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24032	9/15/2026 9:47:00 AM				AtmAA
CV-24032	9/22/2026 9:35:52 AM	1339	34.4351131	-118.6496149	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24032	9/22/2026 9:38:00 AM				AtmAA
CV-24032	9/29/2026 9:01:56 AM	1362	34.4351013	-118.6495934	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24032	9/29/2026 9:05:00 AM				AtmAA
CV-24033	9/3/2026 7:35:00 AM				AtmAA
CV-24033	9/3/2026 7:35:00 AM				AtmAA; [User entered 19.14%]
CV-24033	9/3/2026 7:42:08 AM	1354	34.4353460	-118.6494719	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24033	9/9/2026 8:52:55 AM	1359	34.4353452	-118.6494492	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24033	9/9/2026 8:55:00 AM				AtmAA
CV-24033	9/15/2026 9:28:55 AM	1356	34.4353369	-118.6494400	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24033	9/15/2026 9:32:00 AM				AtmAA
CV-24033	9/22/2026 9:22:23 AM	1336	34.4353373	-118.6494663	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24033	9/22/2026 9:27:00 AM				AtmAA
CV-24033	9/29/2026 8:53:18 AM	1344	34.4353258	-118.6494611	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24033	9/29/2026 8:55:00 AM				AtmAA
CV-24034	9/8/2026 1:21:00 PM				AtmAA
CV-24034	9/8/2026 1:24:32 PM	1375	34.4361096	-118.6481328	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24034	9/14/2026 10:06:34 AM	1353	34.4360935	-118.6481341	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24034	9/14/2026 10:09:00 AM				AtmAA
CV-24034	9/21/2026 10:18:00 AM				AtmAA
CV-24034	9/21/2026 10:19:16 AM	1357	34.4361107	-118.6481153	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24034	9/21/2026 10:20:16 AM	1357	34.4361086	-118.6481128	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24034	9/28/2026 10:07:28 AM	1351	34.4361086	-118.6481199	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24034	9/28/2026 10:15:00 AM				AtmAA
CV-24035-PL	9/8/2026 9:27:31 AM	1364	34.4363796	-118.6477371	Valve Adjustment:No Flow Measurement,High Temp
CV-24035-PL	9/8/2026 9:29:00 AM				AtmAA
CV-24035-PL	9/14/2026 8:17:00 AM				AtmAA
CV-24035-PL	9/14/2026 8:17:07 AM	1363	34.4363823	-118.6477074	Valve Adjustment:No Flow Measurement,High Temp
CV-24035-PL	9/21/2026 8:14:30 AM	1364	34.4363839	-118.6476987	Valve Adjustment:No Flow Measurement,High Temp
CV-24035-PL	9/21/2026 8:15:00 AM				AtmAA
CV-24035-PL	9/28/2026 7:53:30 AM	1355	34.4363794	-118.6477362	Valve Adjustment:No Flow Measurement,High Temp
CV-24035-PL	9/28/2026 7:55:00 AM				AtmAA
CV-24036	9/1/2026 2:33:35 PM	1338	34.4344730	-118.6497342	Valve Adjustment:Valve 100% Open
CV-24036	9/11/2026 2:07:19 PM	1349	34.4344580	-118.6497194	Valve Adjustment:No Flow Measurement,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24036	9/11/2026 2:08:24 PM	1348	34.4344662	-118.6497157	
CV-24036	9/24/2026 11:11:10 AM	1359	34.4344540	-118.6496910	Valve Adjustment:Audible Flow;Well Condition:Lorentz Pump Installed
CV-24037	9/1/2026 3:35:53 PM	1348	34.4347668	-118.6494520	
CV-24037	9/24/2026 11:22:54 AM	1335	34.4347533	-118.6494378	Valve Adjustment:Decreased Flow/Vacuum
CV-24038	9/14/2026 11:13:08 AM	1286	34.4350472	-118.6490432	NSPS/EG CAI,High Temp
CV-24038	9/14/2026 11:14:07 AM	1302	34.4350743	-118.6489623	NSPS/EG CAI,High Temp
CV-24038	9/14/2026 2:15:00 PM				AtmAA
CV-24038	9/21/2026 10:10:47 AM	1347	34.4350215	-118.6488593	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24038	9/21/2026 10:20:00 AM				AtmAA
CV-24038	9/22/2026 10:40:33 AM	1332	34.4349962	-118.6488891	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24038	9/29/2026 9:21:20 AM	1341	34.4349994	-118.6488610	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24038	9/29/2026 9:30:00 AM				AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24039	9/3/2026 8:43:35 AM	1352	34.4352957	-118.6486971	Valve Adjustment:No Flow Measurement,High O2,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24039	9/3/2026 8:45:09 AM	1352	34.4352968	-118.6486993	Well Condition:Lorentz Pump Installed
CV-24039	9/29/2026 9:17:59 AM	1357	34.4352862	-118.6486928	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In);Well Comment:Pump is off
CV-24039	9/29/2026 9:18:59 AM	1345	34.4352903	-118.6486710	
CV-24040	9/3/2026 8:50:25 AM	1344	34.4356455	-118.6483919	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24040	9/3/2026 8:52:00 AM				AtmAA
CV-24040	9/3/2026 8:52:00 AM				AtmAA; [User entered 19.7%]
CV-24040	9/9/2026 9:53:48 AM	1348	34.4356539	-118.6483790	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24040	9/9/2026 9:55:00 AM				AtmAA
CV-24040	9/15/2026 10:32:00 AM				AtmAA
CV-24040	9/15/2026 10:35:47 AM	1340	34.4356452	-118.6483970	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24040	9/15/2026 10:38:31 AM	1341	34.4356455	-118.6483986	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24040	9/21/2026 8:14:52 AM	1367	34.4356300	-118.6483590	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In);Well Comment:Pump is off
CV-24040	9/21/2026 8:16:09 AM	1363	34.4356305	-118.6483698	
CV-24041	9/9/2026 11:11:38 AM	1344	34.4358672	-118.6480342	Valve Adjustment:High O2,Barely Open
CV-24041	9/23/2026 1:19:53 PM	1346	34.4358730	-118.6480412	Valve Adjustment:High O2,Barely Open,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-24042	9/8/2026 1:36:57 PM	1367	34.4362411	-118.6474634	Valve Adjustment:No Flow Measurement,High Temp
CV-24042	9/8/2026 1:37:00 PM				AtmAA
CV-24042	9/14/2026 10:23:07 AM	1365	34.4362201	-118.6474804	Valve Adjustment:No Flow Measurement,High Temp
CV-24042	9/14/2026 10:27:00 AM				AtmAA
CV-24042	9/21/2026 10:29:12 AM	1367	34.4362388	-118.6474614	Valve Adjustment:No Flow Measurement,High Temp
CV-24042	9/21/2026 10:32:00 AM				AtmAA
CV-24042	9/28/2026 10:28:10 AM	1365	34.4362405	-118.6474694	Valve Adjustment:No Flow Measurement,High Temp
CV-24042	9/28/2026 10:30:00 AM				AtmAA
CV-24043	9/14/2026 2:27:14 PM	1276	34.4340498	-118.6497925	,
CV-24043	9/30/2026 4:24:40 PM	1323	34.4340767	-118.6497155	

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24044	9/3/2026 8:17:38 AM	1344	34.4343905	-118.6494041	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24044	9/3/2026 8:23:00 AM				AtmAA
CV-24044	9/3/2026 8:23:00 AM				AtmAA; [User entered 6.7%]
CV-24044	9/9/2026 9:15:54 AM	1346	34.4343820	-118.6493877	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24044	9/9/2026 9:17:00 AM				AtmAA
CV-24044	9/14/2026 9:52:00 AM				AtmAA
CV-24044	9/15/2026 10:10:54 AM	1348	34.4343821	-118.6494143	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24044	9/15/2026 10:12:00 AM				AtmAA
CV-24044	9/22/2026 9:50:00 AM				AtmAA
CV-24044	9/22/2026 9:56:36 AM	1338	34.4343900	-118.6494035	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24044	9/29/2026 9:08:25 AM	1343	34.4343999	-118.6493894	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24044	9/29/2026 9:15:00 AM				AtmAA
CV-24045	9/3/2026 8:23:14 AM	1338	34.4347424	-118.6490782	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24045	9/3/2026 8:27:00 AM				AtmAA
CV-24045	9/3/2026 8:27:00 AM				AtmAA; [User entered 16.11%]
CV-24045	9/9/2026 9:26:00 AM				AtmAA
CV-24045	9/9/2026 9:29:21 AM	1343	34.4347416	-118.6490725	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24045	9/15/2026 10:14:44 AM	1348	34.4347478	-118.6490696	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24045	9/15/2026 10:18:00 AM				AtmAA
CV-24045	9/22/2026 10:34:00 AM				AtmAA
CV-24045	9/22/2026 10:37:26 AM	1327	34.4347373	-118.6491014	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24045	9/29/2026 9:16:50 AM	1342	34.4347419	-118.6490643	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24045	9/29/2026 9:17:31 AM	1341	34.4347456	-118.6490647	Well Condition:Lorentz Pump Installed
CV-24045	9/29/2026 9:25:00 AM				AtmAA
CV-24046	9/14/2026 10:32:13 AM	1302	34.4350398	-118.6483622	NSPS/EG CAI,High Temp
CV-24046	9/14/2026 10:32:44 AM	1289	34.4350448	-118.6484187	NSPS/EG CAI,High Temp
CV-24046	9/21/2026 9:20:00 AM				AtmAA
CV-24046	9/21/2026 9:25:30 AM	1352	34.4350889	-118.6483739	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24046	9/21/2026 9:27:21 AM	1352	34.4350885	-118.6483742	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24046	9/22/2026 1:28:16 PM	1353	34.4350997	-118.6483721	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24046	9/22/2026 1:32:00 PM	1355	34.4350919	-118.6483670	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24046	9/29/2026 9:35:00 AM				AtmAA
CV-24046	9/29/2026 9:38:38 AM	1347	34.4350592	-118.6483815	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24048	9/9/2026 11:14:18 AM	1346	34.4355710	-118.6477875	Valve Adjustment:High O2,Barely Open
CV-24048	9/23/2026 1:23:23 PM	1351	34.4355672	-118.6477890	Valve Adjustment:Barely Open
CV-24049	9/10/2026 9:20:00 AM				AirTech Lab
CV-24049	9/10/2026 9:20:00 AM				AirTech Lab; [User entered 15%]
CV-24049	9/14/2026 9:39:50 AM	1345	34.4359687	-118.6471783	NSPS/EG CAI,High Temp
CV-24049	9/14/2026 9:40:16 AM	1355	34.4359942	-118.6471752	NSPS/EG CAI,High Temp
CV-24049	9/14/2026 10:45:00 AM				AtmAA
CV-24049	9/21/2026 9:35:00 AM				AtmAA
CV-24049	9/21/2026 9:40:32 AM	1378	34.4359493	-118.6471965	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24049	9/21/2026 9:41:36 AM	1378	34.4359493	-118.6471964	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24049	9/28/2026 2:11:38 PM	1381	34.4359389	-118.6472044	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24049	9/28/2026 2:40:00 PM				AtmAA
CV-24050	9/14/2026 2:38:57 PM	1293	34.4337753	-118.6498962	,
CV-24050	9/30/2026 2:26:44 PM	1332	34.4337245	-118.6499719	Valve Adjustment:No Flow Measurement
CV-24051	9/14/2026 11:02:47 AM	1289	34.4344652	-118.6491165	,
CV-24051	9/24/2026 11:45:13 AM	1356	34.4344693	-118.6490308	Valve Adjustment:Decreased Flow/Vacuum
CV-24052	9/14/2026 10:13:38 AM	1332	34.4351138	-118.6481183	,
CV-24052	9/14/2026 10:14:40 AM	1342	34.4350830	-118.6481057	,
CV-24052	9/23/2026 1:29:49 PM	1348	34.4350733	-118.6480637	Valve Adjustment:Decreased Flow/Vacuum
CV-24053	9/8/2026 7:40:00 AM				AirTech Lab
CV-24053	9/8/2026 7:40:00 AM				AirTech Lab; [User entered 0.88%]
CV-24053	9/14/2026 10:03:36 AM	1329	34.4352268	-118.6478772	,
CV-24053	9/23/2026 1:26:37 PM	1338	34.4352458	-118.6478037	Valve Adjustment:Decreased Flow/Vacuum
CV-24054	9/8/2026 1:44:40 PM	1375	34.4356411	-118.6471945	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24054	9/8/2026 1:48:00 PM				AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24054	9/14/2026 10:33:37 AM	1373	34.4356267	-118.6471907	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24054	9/14/2026 10:34:00 AM				AtmAA
CV-24054	9/21/2026 10:34:28 AM	1371	34.4356359	-118.6471815	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24054	9/21/2026 10:37:00 AM				AtmAA
CV-24054	9/28/2026 10:42:38 AM	1374	34.4356326	-118.6471962	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24054	9/28/2026 10:45:00 AM				AtmAA
CV-24055	9/10/2026 9:25:00 AM				AirTech Lab
CV-24055	9/10/2026 9:25:00 AM				AirTech Lab; [User entered 8.5%]
CV-24055	9/14/2026 9:36:06 AM	1391	34.4358657	-118.6469608	,
CV-24055	9/30/2026 8:16:47 AM	1397	34.4358563	-118.6469278	Valve Adjustment:NSPS/EG CAI,High Temp,High O2;Well Condition:Lorentz Pump Installed
CV-24055	9/30/2026 8:17:55 AM	1393	34.4358568	-118.6469233	
CV-24055	9/30/2026 10:20:00 AM				AtmAA
CV-24056	9/1/2026 9:14:34 AM	1335	34.4332992	-118.6500930	,
CV-24056	9/22/2026 11:03:33 AM	1322	34.4333415	-118.6501477	,
CV-24057	9/14/2026 2:15:25 PM	1316	34.4334453	-118.6496745	NSPS/EG CAI,High Temp
CV-24057	9/14/2026 2:16:28 PM	1339	34.4334505	-118.6496667	NSPS/EG CAI,High Temp
CV-24057	9/14/2026 3:00:00 PM				AtmAA
CV-24057	9/17/2026 10:27:01 AM	1320	34.4334902	-118.6496335	Valve Adjustment:High Temp,Barely Open
CV-24057	9/21/2026 10:46:29 AM	1331	34.4334532	-118.6496669	Valve Adjustment:Audible Flow,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24057	9/21/2026 10:47:11 AM	1331	34.4334530	-118.6496667	Valve Adjustment:Audible Flow,High Temp;Well Condition:Lorentz Pump Installed
CV-24057	9/21/2026 10:50:00 AM				AtmAA
CV-24058	9/11/2026 1:53:52 PM	1363	34.4337995	-118.6494456	Valve Adjustment:No Flow Measurement,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24058	9/11/2026 1:55:09 PM	1355	34.4337894	-118.6494639	
CV-24058	9/17/2026 10:38:59 AM	1336	34.4338113	-118.6494502	Valve Adjustment:Barely Open
CV-24059	9/2/2026 9:05:00 AM				AtmAA
CV-24059	9/2/2026 9:05:00 AM				AtmAA; [User entered 15.02%]
CV-24059	9/2/2026 9:06:09 AM	1362	34.4337805	-118.6490978	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24059	9/8/2026 9:49:40 AM	1319	34.4338325	-118.6489450	NSPS/EG CAI,High Temp,Positive Static Press.,Reduced System Vacuum
CV-24059	9/8/2026 9:50:00 AM				AtmAA
CV-24059	9/8/2026 9:51:20 AM	1329	34.4338568	-118.6489895	NSPS/EG CAI,High Temp
CV-24059	9/16/2026 1:37:00 PM				AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24059	9/16/2026 1:42:42 PM	1345	34.4337596	-118.6490772	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24059	9/23/2026 1:24:51 PM	1351	34.4337572	-118.6490860	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24059	9/23/2026 1:27:00 PM				AtmAA
CV-24059	9/30/2026 10:05:00 AM				AtmAA
CV-24059	9/30/2026 10:08:00 AM	1352	34.4337412	-118.6491124	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24060	9/2/2026 9:45:32 AM	1345	34.4340368	-118.6487882	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Plugged/Pinched Suspected
CV-24060	9/17/2026 11:02:39 AM	1352	34.4340405	-118.6487990	Valve Adjustment:Barely Open
CV-24061	9/2/2026 9:52:58 AM	1343	34.4343435	-118.6486292	Valve Adjustment:Barely Open
CV-24061	9/28/2026 10:31:48 AM	1356	34.4343257	-118.6486043	Valve Adjustment:Barely Open
CV-24062	9/1/2026 2:14:11 PM	1364	34.4345859	-118.6481037	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24062	9/1/2026 2:15:00 PM				AtmAA
CV-24062	9/1/2026 2:15:00 PM				AtmAA; [User entered 10.21%]
CV-24062	9/3/2026 7:20:00 AM				AirTech Lab
CV-24062	9/3/2026 7:20:00 AM				AirTech Lab; [User entered 11%]
CV-24062	9/10/2026 8:48:00 AM				AtmAA
CV-24062	9/16/2026 10:09:38 AM	1359	34.4345857	-118.6480850	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24062	9/16/2026 10:13:00 AM				AtmAA
CV-24062	9/23/2026 10:16:47 AM	1361	34.4345692	-118.6480866	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24062	9/23/2026 10:19:00 AM				AtmAA
CV-24062	9/30/2026 9:17:26 AM	1362	34.4345872	-118.6480768	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24062	9/30/2026 9:20:00 AM				AtmAA
CV-24063	9/1/2026 2:00:39 PM	1366	34.4349637	-118.6475249	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24063	9/1/2026 2:05:00 PM				AtmAA
CV-24063	9/1/2026 2:05:00 PM				AtmAA; [User entered 9.69%]
CV-24063	9/3/2026 7:20:00 AM				AirTech Lab
CV-24063	9/3/2026 7:20:00 AM				AirTech Lab; [User entered 11%]
CV-24063	9/10/2026 8:38:00 AM				AtmAA
CV-24063	9/10/2026 8:38:14 AM	1367	34.4349463	-118.6475114	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24063	9/10/2026 8:39:09 AM	1367	34.4349657	-118.6475070	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24063	9/14/2026 2:32:38 PM	1368	34.4349453	-118.6475110	Valve Comment:Installed new flow device well head;Valve Adjustment:Orifice Plate Changed (See OP Log),Valve 100% Open
CV-24063	9/15/2026 10:47:20 AM	1363	34.4349572	-118.6475364	
CV-24063	9/17/2026 12:22:16 PM	1360	34.4349487	-118.6475366	
CV-24063	9/17/2026 1:33:24 PM	1367	34.4349575	-118.6475331	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24063	9/17/2026 1:34:00 PM				AtmAA
CV-24063	9/23/2026 10:11:45 AM	1364	34.4349518	-118.6475207	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24063	9/23/2026 10:13:00 AM				AtmAA
CV-24063	9/30/2026 9:08:35 AM	1363	34.4349454	-118.6475303	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24063	9/30/2026 9:15:00 AM				AtmAA
CV-24064-PL	9/1/2026 1:18:43 PM	1376	34.4352293	-118.6471673	Valve Adjustment:No Flow Measurement,High Temp
CV-24064-PL	9/1/2026 1:25:00 PM				AtmAA
CV-24064-PL	9/1/2026 1:25:00 PM				AtmAA; [User entered 12.11%]
CV-24064-PL	9/3/2026 7:30:00 AM				AirTech Lab
CV-24064-PL	9/3/2026 7:30:00 AM				AirTech Lab; [User entered 14%]
CV-24064-PL	9/9/2026 1:28:11 PM	1374	34.4352301	-118.6471435	Valve Adjustment:No Flow Measurement,High Temp
CV-24064-PL	9/9/2026 1:32:00 PM				AtmAA
CV-24064-PL	9/10/2026 8:45:01 AM	1362	34.4345767	-118.6480934	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24064-PL	9/16/2026 9:05:32 AM	1364	34.4352208	-118.6471720	Valve Adjustment:No Flow Measurement,High Temp
CV-24064-PL	9/16/2026 9:14:00 AM				AtmAA
CV-24064-PL	9/23/2026 9:22:59 AM	1372	34.4352217	-118.6471656	Valve Adjustment:No Flow Measurement,High Temp
CV-24064-PL	9/23/2026 9:25:00 AM				AtmAA
CV-24064-PL	9/30/2026 8:25:00 AM				AtmAA
CV-24064-PL	9/30/2026 8:38:49 AM	1366	34.4352409	-118.6471663	Valve Adjustment:No Flow Measurement,High Temp
CV-24065-TP	9/3/2026 8:57:02 AM	1365	34.4355762	-118.6468408	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24065-TP	9/8/2026 7:50:00 AM				AirTech Lab
CV-24065-TP	9/8/2026 7:50:00 AM				AirTech Lab; [User entered 1.5%]
CV-24065-TP	9/22/2026 10:39:59 AM	1381	34.4355865	-118.6468232	Valve Adjustment:Decreased Flow/Vacuum
CV-24066	9/1/2026 9:11:21 AM	1296	34.4330013	-118.6498730	,
CV-24066	9/10/2026 8:15:00 AM				AirTech Lab
CV-24066	9/10/2026 8:15:00 AM				AirTech Lab; [User entered 2.3%]
CV-24066	9/22/2026 11:00:28 AM	1319	34.4330323	-118.6498247	,
CV-24066	9/24/2026 2:36:50 PM	1323	34.4330125	-118.6498187	Valve Adjustment:Barely Open

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24067	9/29/2026 2:12:24 PM	1310	34.4331878	-118.6497418	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24067	9/29/2026 2:14:48 PM	1320	34.4331927	-118.6497357	Valve Comment:corrected differential port;Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24068	9/3/2026 10:45:39 AM	1308	34.4332665	-118.6493682	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24068	9/3/2026 10:47:00 AM				AtmAA
CV-24068	9/3/2026 10:47:00 AM				AtmAA; [User entered 4.23%]
CV-24068	9/8/2026 10:05:00 AM				AtmAA
CV-24068	9/8/2026 10:06:07 AM	1283	34.4332867	-118.6493442	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-24068	9/17/2026 1:41:53 PM	1367	34.4332668	-118.6493867	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24069	9/2/2026 8:53:53 AM	1365	34.4334253	-118.6489433	Valve Adjustment:Barely Open
CV-24069	9/8/2026 7:00:00 AM				AirTech Lab
CV-24069	9/8/2026 7:00:00 AM				AirTech Lab; [User entered 6.4%]
CV-24069	9/28/2026 10:46:59 AM	1345	34.4334198	-118.6489247	Valve Adjustment:Barely Open
CV-24070	9/2/2026 8:55:00 AM				AtmAA
CV-24070	9/2/2026 8:55:00 AM				AtmAA; [User entered 6.42%]
CV-24070	9/2/2026 8:55:24 AM	1367	34.4337238	-118.6486983	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24070	9/8/2026 7:10:00 AM				AirTech Lab
CV-24070	9/8/2026 7:10:00 AM				AirTech Lab; [User entered 8.2%]
CV-24070	9/9/2026 1:57:00 PM	1344	34.4337403	-118.6486914	Valve Adjustment:Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24070	9/9/2026 1:57:46 PM	1340	34.4337333	-118.6487074	
CV-24070	9/10/2026 1:57:00 PM				AtmAA
CV-24070	9/10/2026 1:59:57 PM	1362	34.4337177	-118.6487056	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24070	9/16/2026 1:23:00 PM				AtmAA
CV-24070	9/16/2026 1:30:24 PM	1359	34.4337356	-118.6486836	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24071	9/2/2026 9:40:06 AM	1343	34.4340118	-118.6484862	Valve Adjustment:High Temp,Barely Open;Well Condition:Lorentz Pump Installed
CV-24071	9/8/2026 7:15:00 AM				AirTech Lab
CV-24071	9/8/2026 7:15:00 AM				AirTech Lab; [User entered 7.4%]
CV-24071	9/17/2026 2:19:48 PM	1345	34.4340007	-118.6484940	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open
CV-24072	9/2/2026 1:30:58 PM	1358	34.4341643	-118.6480443	Valve Adjustment:Decreased Flow/Vacuum
CV-24072	9/17/2026 2:25:11 PM	1359	34.4341910	-118.6480525	Valve Adjustment:Barely Open
CV-24073-TP	9/1/2026 2:25:19 PM	1367	34.4346323	-118.6477321	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24073-TP	9/1/2026 2:30:00 PM				AtmAA
CV-24073-TP	9/1/2026 2:30:00 PM				AtmAA; [User entered 4.76%]
CV-24073-TP	9/9/2026 1:21:38 PM	1366	34.4346204	-118.6476943	Valve Adjustment:No Flow Measurement;Well Condition:Lorentz Pump Installed
CV-24073-TP	9/21/2026 2:25:32 PM	1370	34.4346508	-118.6477230	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24073-TP	9/30/2026 9:00:28 AM	1365	34.4346349	-118.6477305	Valve Adjustment:No Flow Measurement,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24073-TP	9/30/2026 9:01:24 AM	1365	34.4346352	-118.6477302	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24073-TP	9/30/2026 9:05:00 AM				AtmAA
CV-24074	9/2/2026 2:20:20 PM	1374	34.4347323	-118.6474223	Valve Adjustment:Barely Open
CV-24074	9/21/2026 2:20:48 PM	1366	34.4347475	-118.6474397	Valve Adjustment:Barely Open
CV-24075-TP	9/1/2026 1:27:41 PM	1377	34.4350212	-118.6471203	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24075-TP	9/1/2026 1:34:00 PM				AtmAA
CV-24075-TP	9/1/2026 1:34:00 PM				AtmAA; [User entered 6.75%]
CV-24075-TP	9/9/2026 1:36:18 PM	1365	34.4350383	-118.6471025	Valve Adjustment:Other - See Daily Log,High Temp;Well Condition:Lorentz Pump Installed
CV-24075-TP	9/9/2026 1:41:00 PM				AtmAA
CV-24075-TP	9/16/2026 9:26:05 AM	1357	34.4350257	-118.6471345	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24075-TP	9/16/2026 9:28:00 AM				AtmAA
CV-24075-TP	9/23/2026 9:31:50 AM	1373	34.4350254	-118.6471172	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24075-TP	9/23/2026 9:35:00 AM				AtmAA
CV-24075-TP	9/30/2026 8:50:15 AM				Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24075-TP	9/30/2026 8:55:00 AM				AtmAA
CV-24076	9/1/2026 1:45:00 PM				AtmAA
CV-24076	9/1/2026 1:45:00 PM				AtmAA; [User entered 4.14%]
CV-24076	9/1/2026 1:45:11 PM	1389	34.4353069	-118.6468877	Valve Adjustment:High Temp
CV-24076	9/1/2026 1:49:10 PM	1388	34.4353041	-118.6468846	Valve Adjustment:High Temp
CV-24076	9/9/2026 1:57:00 PM				AtmAA
CV-24076	9/9/2026 1:58:23 PM	1405	34.4353295	-118.6469041	Valve Adjustment:High Temp,Valve 100% Open
CV-24076	9/16/2026 9:59:57 AM	1369	34.4353454	-118.6468883	Valve Adjustment:High Temp
CV-24076	9/16/2026 10:02:00 AM				AtmAA
CV-24076	9/23/2026 9:57:00 AM	1377	34.4353274	-118.6468801	Valve Adjustment:High Temp
CV-24076	9/30/2026 9:00:43 AM	1372	34.4353301	-118.6468726	Valve Adjustment:High Temp

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24076	9/30/2026 9:05:00 AM				AtmAA
CV-24077	9/1/2026 9:39:47 AM	1312	34.4327360	-118.6493397	NSPS/EG CAI,High Temp
CV-24077	9/1/2026 11:02:58 AM	1296	34.4326713	-118.6492630	NSPS/EG CAI,High Temp
CV-24077	9/1/2026 2:25:00 PM				AtmAA
CV-24077	9/1/2026 2:25:00 PM				AtmAA; [User entered 4%]
CV-24077	9/1/2026 2:29:54 PM	1329	34.4326822	-118.6493146	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24077	9/8/2026 10:33:07 AM	1362	34.4326312	-118.6494683	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-24077	9/8/2026 10:35:00 AM				AtmAA
CV-24077	9/14/2026 9:40:00 AM				AtmAA
CV-24077	9/14/2026 9:41:46 AM	1329	34.4326937	-118.6492783	Valve Adjustment:No Adjustments Made;Well Comment:lorentz pump installed
CV-24077	9/14/2026 10:22:00 AM	1324	34.4326883	-118.6493132	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24077	9/22/2026 12:59:33 PM	1329	34.4326130	-118.6493027	NSPS/EG CAI,High Temp
CV-24077	9/22/2026 1:00:24 PM	1312	34.4326507	-118.6492862	NSPS/EG CAI,High Temp
CV-24077	9/23/2026 1:52:00 PM				AtmAA
CV-24077	9/23/2026 1:52:12 PM	1338	34.4326824	-118.6493065	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24077	9/30/2026 1:55:00 PM				AtmAA
CV-24077	9/30/2026 1:57:09 PM	1336	34.4326908	-118.6492945	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24078	9/1/2026 11:05:35 AM	1398	34.4328607	-118.6494877	,
CV-24078	9/22/2026 10:57:51 AM	1329	34.4329245	-118.6494582	,
CV-24079-TP	9/1/2026 10:56:25 AM	1309	34.4330195	-118.6490892	,
CV-24079-TP	9/21/2026 11:00:53 AM	1332	34.4329885	-118.6491078	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24079-TP	9/21/2026 11:03:19 AM	1320	34.4329590	-118.6491037	
CV-24079-TP	9/28/2026 10:34:01 AM	1335	34.4329805	-118.6491157	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24079-TP	9/30/2026 9:15:00 AM				AtmAA
CV-24079-TP	9/30/2026 9:17:09 AM	1343	34.4329769	-118.6491282	Valve Adjustment:No Flow Measurement,High Temp
CV-24080	9/1/2026 10:50:48 AM	1335	34.4331360	-118.6489003	,
CV-24080	9/9/2026 2:19:31 PM	1329	34.4321602	-118.6487012	NSPS/EG CAC,
CV-24080	9/17/2026 10:09:09 AM	1344	34.4331267	-118.6488392	Valve Adjustment:Barely Open
CV-24081-TP	9/2/2026 9:06:17 AM	1349	34.4334087	-118.6485977	Valve Adjustment:Barely Open
CV-24081-TP	9/17/2026 1:48:26 PM	1356	34.4334192	-118.6486353	Valve Adjustment:Barely Open
CV-24082	9/2/2026 9:30:43 AM	1364	34.4334072	-118.6483257	Valve Adjustment:Decreased Flow/Vacuum
CV-24082	9/17/2026 1:53:48 PM	1357	34.4334343	-118.6483500	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24083	9/2/2026 8:49:34 AM	1365	34.4337136	-118.6483451	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24083	9/2/2026 8:50:00 AM				AtmAA
CV-24083	9/2/2026 8:50:00 AM				AtmAA; [User entered 7.67%]
CV-24083	9/8/2026 10:18:45 AM	1391	34.4337317	-118.6483928	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-24083	9/8/2026 10:20:00 AM				AtmAA
CV-24083	9/17/2026 1:55:13 PM	1364	34.4337039	-118.6483548	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24083	9/17/2026 1:57:00 PM				AtmAA
CV-24083	9/23/2026 1:21:00 PM				AtmAA
CV-24083	9/23/2026 1:23:41 PM	1363	34.4337095	-118.6483465	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24083	9/30/2026 10:01:53 AM	1352	34.4337238	-118.6483368	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24084-TP	9/2/2026 8:41:51 AM	1370	34.4338541	-118.6480293	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24084-TP	9/2/2026 8:45:00 AM				AtmAA
CV-24084-TP	9/2/2026 8:45:00 AM				AtmAA; [User entered 10.63%]
CV-24084-TP	9/8/2026 10:20:41 AM	1332	34.4338592	-118.6479802	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-24084-TP	9/8/2026 10:25:00 AM				AtmAA
CV-24084-TP	9/17/2026 1:59:08 PM	1365	34.4338397	-118.6480644	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24084-TP	9/17/2026 2:02:00 PM				AtmAA
CV-24084-TP	9/23/2026 1:13:00 PM				AtmAA
CV-24084-TP	9/23/2026 1:16:20 PM	1373	34.4338474	-118.6480523	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24084-TP	9/30/2026 9:55:00 AM				AtmAA
CV-24084-TP	9/30/2026 9:57:04 AM	1360	34.4338413	-118.6480469	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24085	9/1/2026 11:10:02 AM	1280	34.4323987	-118.6488777	NSPS/EG CAI,Positive Static Press.
CV-24085	9/1/2026 11:10:35 AM	1280	34.4323852	-118.6488888	NSPS/EG CAI,Positive Static Press.
CV-24085	9/9/2026 2:14:51 PM	1299	34.4323227	-118.6490213	NSPS/EG CAI,High Temp
CV-24085	9/9/2026 2:15:24 PM	1322	34.4323160	-118.6490775	NSPS/EG CAI,High Temp
CV-24085	9/18/2026 4:38:39 PM	1344	34.4324113	-118.6490002	Valve Adjustment:Decreased Flow/Vacuum
CV-24086	9/1/2026 10:18:55 AM	1322	34.4328010	-118.6486468	,
CV-24086	9/17/2026 9:56:01 AM	1358	34.4328898	-118.6486847	Valve Adjustment:Barely Open
CV-24087	9/14/2026 1:57:58 PM	1377	34.4330130	-118.6481458	Valve Adjustment:Barely Open
CV-24087	9/21/2026 9:41:26 AM	1373	34.4329927	-118.6481192	Valve Adjustment:Surging Liquid in Header
CV-24088	9/2/2026 1:21:22 PM	1378	34.4335760	-118.6476442	Valve Adjustment:Barely Open

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24088	9/17/2026 3:03:53 PM	1374	34.4335813	-118.6476792	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24089	9/1/2026 2:52:55 PM	1348	34.4324250	-118.6481377	,
CV-24089	9/22/2026 2:06:04 PM	1363	34.4324632	-118.6480998	Valve Adjustment:Barely Open
CV-24090	9/3/2026 12:03:50 PM	1374	34.4326817	-118.6475420	Valve Adjustment:Increased Flow/Vacuum
CV-24090	9/14/2026 1:45:37 PM	1373	34.4326970	-118.6475555	Valve Adjustment:Barely Open
CV-24090	9/21/2026 9:16:50 AM	1371	34.4327005	-118.6475340	
CV-24091	9/14/2026 1:37:49 PM	1393	34.4330008	-118.6469258	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24091	9/21/2026 8:59:41 AM	1381	34.4329872	-118.6468902	Valve Adjustment:Valve 100% Open
CV-24092	9/14/2026 1:27:47 PM	1395	34.4333165	-118.6461510	Valve Adjustment:Barely Open
CV-24092	9/24/2026 2:16:45 PM	1389	34.4333148	-118.6461470	
CV-24093	9/13/2026 9:56:20 AM	1377	34.4340597	-118.6463428	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open;Well Comment:Pump is active;Well Condition:Poor,Lorentz Pump Installed
CV-24093	9/13/2026 9:58:10 AM	1380	34.4340730	-118.6463600	Valve Adjustment:Barely Open;Well Condition:Lorentz Pump Installed
CV-24093	9/28/2026 10:16:44 AM	1395	34.4340735	-118.6463412	
CV-24094	9/14/2026 1:07:34 PM	1411	34.4345155	-118.6460690	,
CV-24094	9/22/2026 10:05:46 AM	1372	34.4345660	-118.6460878	Valve Adjustment:Barely Open
CV-24095	9/1/2026 1:57:31 PM	1267	34.4333949	-118.6513113	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24095	9/1/2026 2:00:00 PM				AtmAA
CV-24095	9/1/2026 2:00:00 PM				AtmAA; [User entered 15.93%]
CV-24095	9/8/2026 1:30:00 PM				AtmAA
CV-24095	9/8/2026 1:31:41 PM	1299	34.4331315	-118.6512473	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-24095	9/10/2026 8:30:00 AM				AirTech Lab
CV-24095	9/10/2026 8:30:00 AM				AirTech Lab; [User entered 18%]
CV-24095	9/17/2026 9:42:47 AM	1260	34.4334194	-118.6512860	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24095	9/17/2026 9:47:00 AM				AtmAA
CV-24095	9/24/2026 9:52:08 AM	1254	34.4334084	-118.6512947	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24095	9/24/2026 10:00:00 AM				AtmAA
CV-24096	9/2/2026 8:14:01 AM	1230	34.4332345	-118.6516627	,
CV-24096	9/23/2026 9:26:01 AM	1251	34.4332217	-118.6515660	Valve Adjustment:Decreased Flow/Vacuum
CV-24097	9/2/2026 8:18:03 AM	1276	34.4327085	-118.6515597	Reduced System Vacuum,
CV-24097	9/30/2026 3:17:38 PM	1238	34.4328117	-118.6515068	Valve Adjustment:Positive Static Press.,Surging Liquid in Header,Surging Liquid in Well (Watered In)

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24098	9/2/2026 8:23:38 AM	1257	34.4324882	-118.6512422	Reduced System Vacuum,
CV-24098	9/23/2026 9:16:20 AM	1247	34.4325072	-118.6512940	Well Comment:Valve stuck open
CV-24099	9/2/2026 8:32:12 AM	1322	34.4323762	-118.6510242	Reduced System Vacuum,
CV-24099	9/23/2026 9:11:30 AM	1259	34.4323088	-118.6509557	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected;Well Comment:Valve stuck open
CV-24099	9/23/2026 9:13:00 AM	1257	34.4323130	-118.6509193	Valve Adjustment:High O2,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected;Well Comment:Valve stuck open
CV-24100	9/2/2026 8:50:27 AM	1250	34.4318308	-118.6502663	,
CV-24100	9/2/2026 1:05:00 PM				AtmAA
CV-24100	9/2/2026 1:05:00 PM				AtmAA; [User entered 0.56%]
CV-24100	9/2/2026 1:12:10 PM	1261	34.4320575	-118.6505007	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24100	9/2/2026 1:16:31 PM	1262	34.4320563	-118.6505004	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24100	9/8/2026 7:35:00 AM				AirTech Lab
CV-24100	9/8/2026 7:35:00 AM				AirTech Lab; [User entered 0.63%]
CV-24100	9/8/2026 2:53:01 PM	1234	34.4320318	-118.6505738	NSPS/EG CAI,High Temp
CV-24100	9/8/2026 2:55:00 PM				AtmAA
CV-24100	9/17/2026 2:15:00 PM				AtmAA
CV-24100	9/17/2026 2:19:56 PM	1263	34.4320557	-118.6504980	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24100	9/17/2026 2:21:00 PM	1263	34.4320598	-118.6504961	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24100	9/24/2026 10:19:50 AM	1268	34.4320480	-118.6504950	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24100	9/24/2026 10:25:00 AM				AtmAA
CV-24100	9/28/2026 1:58:23 PM	1243	34.4320353	-118.6504885	Valve Adjustment:No Flow Measurement,Decreased Flow/Vacuum
CV-24101	9/8/2026 7:30:00 AM				AirTech Lab
CV-24101	9/8/2026 7:30:00 AM				AirTech Lab; [User entered 0.12%]
CV-24101	9/28/2026 1:59:13 PM	1249	34.4320435	-118.6504778	
CV-24102	9/2/2026 9:21:46 AM	1316	34.4315287	-118.6498003	,
CV-24102	9/22/2026 12:22:15 PM	1263	34.4316202	-118.6499008	,
CV-24103	9/1/2026 11:30:43 AM	1309	34.4316838	-118.6489393	,
CV-24103	9/21/2026 11:54:27 AM	1322	34.4316372	-118.6488253	Valve Adjustment:Audible Flow
CV-24104	9/1/2026 1:54:55 PM	1339	34.4319182	-118.6479823	,
CV-24104	9/3/2026 10:55:10 AM	1345	34.4318688	-118.6481022	Valve Adjustment:Increased Flow/Vacuum,Barely Open

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24104	9/21/2026 12:21:54 PM	1340	34.4318703	-118.6480883	Valve Adjustment:Audible Flow,Barely Open
CV-24105	9/1/2026 2:02:32 PM	1280	34.4319265	-118.6477470	,
CV-24105	9/22/2026 3:05:41 PM	1347	34.4319162	-118.6476585	Valve Adjustment:Barely Open
CV-24106	9/15/2026 12:21:17 PM	1342	34.4321198	-118.6467325	Valve Adjustment:Decreased Flow/Vacuum
CV-24106	9/15/2026 12:21:57 PM	1343	34.4321255	-118.6467260	
CV-24107	9/9/2026 1:53:59 PM	1289	34.4327040	-118.6462592	,
CV-24108	9/9/2026 1:16:23 PM	1375	34.4332038	-118.6454417	NSPS/EG CAI,High Temp
CV-24108	9/9/2026 1:17:42 PM	1302	34.4331657	-118.6455800	NSPS/EG CAI,High Temp
CV-24109	9/9/2026 12:50:32 PM	1365	34.4340008	-118.6449610	,
CV-24110	9/3/2026 1:03:31 PM	1381	34.4345965	-118.6446968	Valve Adjustment:High Temp,Barely Open
CV-24111	9/3/2026 1:42:51 PM	1393	34.4353150	-118.6449560	Valve Adjustment:Decreased Flow/Vacuum
CV-24112	9/3/2026 1:20:04 PM	1385	34.4352323	-118.6442025	Valve Adjustment:Barely Open
CV-24114	9/23/2026 9:58:47 AM	1277	34.4308057	-118.6485413	Valve Adjustment:Valve 100% Open
CV-24116	9/24/2026 1:00:00 PM				AtmAA (24 TAT Request)
CV-24116	9/24/2026 1:00:00 PM				AtmAA (24 TAT Request); [User entered 0.32%]
CV-24116	9/24/2026 1:11:51 PM				[User entered 5.8%]
CV-24116	9/24/2026 1:12:29 PM	1239	34.4316483	-118.6457223	Valve Adjustment:Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-24116	9/24/2026 3:03:05 PM				
CV-24117	9/24/2026 10:47:16 AM	1301	34.4323488	-118.6449450	
CV-24118	9/1/2026 9:00:54 AM	1316	34.4332862	-118.6438527	
CV-24118	9/2/2026 2:19:21 PM	1302	34.4332987	-118.6438870	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24118	9/2/2026 2:25:00 PM				AtmAA
CV-24118	9/2/2026 2:25:00 PM				AtmAA; [User entered 13.38%]
CV-24118	9/10/2026 9:35:00 AM				AtmAA
CV-24118	9/10/2026 9:38:23 AM	1304	34.4332950	-118.6438345	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24118	9/17/2026 10:36:18 AM	1291	34.4332868	-118.6438448	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24118	9/17/2026 10:39:00 AM				AtmAA
CV-24119	9/28/2026 2:35:12 PM	1261	34.4337282	-118.6423448	Valve Adjustment:High Temp,Barely Open
CV-24120	9/9/2026 8:10:00 AM				AirTech Lab
CV-24120	9/9/2026 8:10:00 AM				AirTech Lab; [User entered 4.2%]
CV-24120	9/14/2026 10:25:29 AM	1344	34.4368285	-118.6472872	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In)
CV-24120	9/14/2026 10:27:15 AM	1335	34.4368475	-118.6472788	
CV-24120	9/25/2026 10:26:04 AM	1333	34.4368447	-118.6472772	Valve Adjustment:Decreased Flow/Vacuum

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24120	9/28/2026 9:41:44 AM	1352	34.4368405	-118.6472745	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open
CV-24120	9/28/2026 9:50:35 AM	1336	34.4368523	-118.6472812	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-24121	9/3/2026 9:37:51 AM	1333	34.4369440	-118.6470215	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
CV-24121	9/3/2026 9:43:25 AM	1340	34.4369442	-118.6470290	Valve Adjustment:NSPS/EG CAC
CV-24121	9/10/2026 9:45:00 AM				AirTech Lab
CV-24121	9/10/2026 9:45:00 AM				AirTech Lab; [User entered 0.16%]
CV-24121	9/25/2026 10:30:06 AM	1335	34.4369802	-118.6470150	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24122	9/8/2026 8:20:00 AM				AirTech Lab
CV-24122	9/8/2026 8:20:00 AM				AirTech Lab; [User entered 1.5%]
CV-24122	9/15/2026 7:57:25 AM	1304	34.4371792	-118.6466323	Valve Adjustment:NSPS/EG CAI,High O2
CV-24122	9/15/2026 7:58:33 AM	1296	34.4371765	-118.6466377	
CV-24122	9/25/2026 10:38:50 AM	1313	34.4371658	-118.6466385	Valve Adjustment:High O2,Opened for Sample,Increased Flow/Vacuum,Plugged/Pinched Suspected
CV-24123	9/3/2026 9:17:50 AM	1284	34.4373050	-118.6462557	Valve Adjustment:Increased Flow/Vacuum
CV-24123	9/11/2026 3:37:45 PM	1300	34.4372933	-118.6462211	Valve Adjustment:Increased Flow/Vacuum
CV-24123	9/11/2026 3:38:20 PM	1301	34.4372888	-118.6462239	
CV-24123	9/23/2026 8:27:33 AM	1303	34.4372990	-118.6462398	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-24124	9/15/2026 10:14:34 AM	1309	34.4367153	-118.6469675	NSPS/EG CAI,High Temp
CV-24124	9/15/2026 10:15:20 AM	1365	34.4366338	-118.6470908	NSPS/EG CAI,High Temp
CV-24124	9/29/2026 8:14:35 AM	1348	34.4366625	-118.6470088	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24124	9/29/2026 8:15:27 AM	1340	34.4366480	-118.6470102	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24125-TP	9/9/2026 8:20:00 AM				AirTech Lab
CV-24125-TP	9/9/2026 8:20:00 AM				AirTech Lab; [User entered 0.14%]
CV-24125-TP	9/14/2026 9:25:49 AM	1325	34.4369652	-118.6463240	Valve Adjustment:Decreased Flow/Vacuum
CV-24125-TP	9/29/2026 8:05:16 AM	1336	34.4369652	-118.6463265	Well Condition:Pnumatic Pump Installed
CV-24126	9/8/2026 2:01:24 PM	1386	34.4363679	-118.6471270	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24126	9/8/2026 2:04:00 PM				AtmAA
CV-24126	9/14/2026 1:36:52 PM	1389	34.4363864	-118.6471412	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24126	9/14/2026 1:40:00 PM				AtmAA
CV-24126	9/21/2026 1:17:00 PM				AtmAA
CV-24126	9/21/2026 1:17:21 PM	1381	34.4363820	-118.6471044	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24126	9/28/2026 1:36:03 PM	1375	34.4363779	-118.6471433	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24126	9/28/2026 1:45:00 PM				AtmAA
CV-24127	9/8/2026 8:00:00 AM				AirTech Lab
CV-24127	9/8/2026 8:00:00 AM				AirTech Lab; [User entered 18%]
CV-24127	9/8/2026 2:06:28 PM				Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24127	9/8/2026 2:09:00 PM				AtmAA
CV-24127	9/14/2026 1:33:01 PM	1376	34.4364448	-118.6468262	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24127	9/14/2026 1:36:00 PM				AtmAA
CV-24127	9/21/2026 1:12:42 PM	1384	34.4364483	-118.6468392	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24127	9/21/2026 1:13:00 PM				AtmAA
CV-24127	9/28/2026 1:25:09 PM	1376	34.4364689	-118.6468414	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24127	9/28/2026 1:35:00 PM				AtmAA
CV-24128	9/9/2026 12:13:22 PM	1362	34.4366942	-118.6464257	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-24128	9/9/2026 12:14:49 PM	1358	34.4367017	-118.6464352	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-24128	9/10/2026 9:35:00 AM				AirTech Lab
CV-24128	9/10/2026 9:35:00 AM				AirTech Lab; [User entered 11%]
CV-24128	9/25/2026 9:55:31 AM	1363	34.4367142	-118.6464303	Valve Adjustment:Barely Open
CV-24129	9/9/2026 12:18:22 PM	1346	34.4366892	-118.6461563	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-24129	9/25/2026 9:45:34 AM	1345	34.4367117	-118.6461688	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24130	9/30/2026 2:09:18 PM	1327	34.4368120	-118.6456965	
CV-24131	9/10/2026 1:47:00 PM	1325	34.4367267	-118.6450742	Valve Adjustment:Barely Open,Surging Liquid in Header
CV-24132	9/30/2026 10:16:29 AM	1286	34.4372418	-118.6440413	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-24133	9/21/2026 8:33:25 AM	1283	34.4374257	-118.6427150	
CV-24134-TP	9/10/2026 1:06:47 PM	1370	34.4363520	-118.6465075	Valve Adjustment:High Temp,Barely Open
CV-24134-TP	9/14/2026 1:29:38 PM	1369	34.4363697	-118.6464983	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24134-TP	9/14/2026 1:32:00 PM				AtmAA
CV-24134-TP	9/21/2026 1:07:00 PM				AtmAA
CV-24134-TP	9/21/2026 1:09:25 PM	1372	34.4363611	-118.6464995	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24134-TP	9/28/2026 1:06:51 PM	1368	34.4363582	-118.6465083	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24134-TP	9/28/2026 1:25:00 PM				AtmAA
CV-24135	9/3/2026 9:48:00 AM				AtmAA
CV-24135	9/3/2026 9:48:00 AM				AtmAA; [User entered 14.17%]
CV-24135	9/3/2026 10:26:41 AM	1355	34.4363871	-118.6459611	Valve Adjustment:No Flow Measurement,High Temp
CV-24135	9/10/2026 2:23:00 PM				AtmAA
CV-24135	9/10/2026 2:26:00 PM	1374	34.4363958	-118.6459794	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24135	9/10/2026 2:27:03 PM	1377	34.4363965	-118.6459810	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24135	9/14/2026 1:23:45 PM	1362	34.4363989	-118.6459679	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24135	9/14/2026 1:27:00 PM				AtmAA
CV-24135	9/24/2026 1:53:54 PM	1370	34.4364099	-118.6459664	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24135	9/24/2026 1:55:00 PM				AtmAA
CV-24136	9/10/2026 1:43:56 PM	1329	34.4366128	-118.6442960	Valve Adjustment:Barely Open
CV-24137	9/28/2026 1:45:23 PM	1371	34.4361553	-118.6434965	Valve Adjustment:Barely Open
CV-24138	9/2/2026 7:35:00 AM				AirTech Lab
CV-24138	9/2/2026 7:35:00 AM				AirTech Lab; [User entered 2.5%]
CV-24138	9/2/2026 7:58:13 AM	1306	34.4342217	-118.6512640	NSPS/EG CAI,High O2
CV-24138	9/2/2026 7:59:07 AM	1302	34.4342333	-118.6512605	NSPS/EG CAI,High O2
CV-24138	9/30/2026 2:54:56 PM	1267	34.4342628	-118.6512385	Valve Adjustment:High Temp,Barely Open
CV-24139	9/1/2026 1:45:00 PM				AtmAA
CV-24139	9/1/2026 1:45:00 PM				AtmAA; [User entered 18.01%]
CV-24139	9/1/2026 1:48:41 PM	1276	34.4344923	-118.6511560	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24139	9/2/2026 7:30:00 AM				AirTech Lab
CV-24139	9/2/2026 7:30:00 AM				AirTech Lab; [User entered 21%]
CV-24139	9/8/2026 1:22:11 PM	1220	34.4345005	-118.6511732	NSPS/EG CAC,Reduced System Vacuum
CV-24139	9/10/2026 2:55:48 PM	1280	34.4344994	-118.6511353	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-24139	9/10/2026 3:13:23 PM	1280	34.4344991	-118.6511363	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-24139	9/10/2026 3:15:24 PM	1280	34.4344991	-118.6511365	Valve Adjustment:No Flow Measurement;Well Condition:Pnumatic Pump Installed

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24139	9/30/2026 2:51:42 PM	1270	34.4345080	-118.6511198	Valve Adjustment:High O2,Barely Open
CV-24140	9/1/2026 1:40:00 PM				AtmAA
CV-24140	9/1/2026 1:40:00 PM				AtmAA; [User entered 18.28%]
CV-24140	9/1/2026 1:44:48 PM	1283	34.4346600	-118.6511438	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24140	9/2/2026 7:25:00 AM				AirTech Lab
CV-24140	9/2/2026 7:25:00 AM				AirTech Lab; [User entered 21%]
CV-24140	9/8/2026 1:16:52 PM	1234	34.4347035	-118.6511152	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-24140	9/8/2026 1:20:00 PM				AtmAA
CV-24140	9/17/2026 9:53:55 AM	1273	34.4346782	-118.6511147	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24140	9/17/2026 9:55:00 AM				AtmAA
CV-24140	9/24/2026 9:42:13 AM	1280	34.4346749	-118.6511171	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24140	9/24/2026 9:45:00 AM				AtmAA
CV-24141	9/2/2026 7:10:00 AM				AirTech Lab
CV-24141	9/2/2026 7:10:00 AM				AirTech Lab; [User entered 0.19%]
CV-24141	9/15/2026 9:57:58 AM	1295	34.4354872	-118.6513138	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In)
CV-24141	9/15/2026 9:59:24 AM	1299	34.4354905	-118.6513135	
CV-24141	9/23/2026 9:57:06 AM	1304	34.4354748	-118.6513263	Valve Adjustment:High O2,Decreased Flow/Vacuum,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-24142	9/1/2026 1:54:21 PM	1260	34.4339812	-118.6513562	Valve Adjustment:No Flow Measurement;Well Condition:Pnumatic Pump Installed
CV-24142	9/2/2026 7:40:00 AM				AirTech Lab
CV-24142	9/2/2026 7:40:00 AM				AirTech Lab; [User entered 17%]
CV-24142	9/30/2026 2:58:57 PM	1255	34.4339757	-118.6513368	Valve Adjustment:High O2
CV-24143	9/1/2026 7:40:00 AM				Air Tech Lab
CV-24143	9/1/2026 7:40:00 AM				Air Tech Lab; [User entered 9.4%]
CV-24143	9/10/2026 12:19:01 PM	1286	34.4349895	-118.6512217	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:No pump
CV-24143	9/10/2026 12:20:07 PM	1292	34.4350137	-118.6512360	
CV-24143	9/23/2026 9:50:14 AM	1285	34.4349848	-118.6512180	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-24144	9/2/2026 8:20:25 AM	1224	34.4325943	-118.6515392	Reduced System Vacuum,
CV-24145	9/9/2026 8:26:12 AM	1351	34.4362334	-118.6496453	Valve Adjustment:High Temp
CV-24145	9/9/2026 8:28:00 AM				AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24145	9/15/2026 8:52:56 AM	1371	34.4362282	-118.6496228	Valve Adjustment:No Flow Measurement,High Temp
CV-24145	9/15/2026 8:55:00 AM				AtmAA
CV-24145	9/22/2026 8:48:58 AM	1356	34.4362284	-118.6496183	Valve Adjustment:No Flow Measurement,High Temp
CV-24145	9/22/2026 8:50:00 AM				AtmAA
CV-24145	9/29/2026 8:14:25 AM	1359	34.4362275	-118.6496108	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24145	9/29/2026 8:20:00 AM				AtmAA
CV-24146	9/11/2026 3:43:00 PM	1305	34.4374029	-118.6463693	Valve Adjustment:Increased Flow/Vacuum
CV-24146	9/11/2026 3:43:31 PM	1305	34.4374050	-118.6463694	
CV-24146	9/23/2026 8:23:00 AM	1313	34.4374017	-118.6463642	Valve Adjustment:Audible Flow
CV-24146	9/29/2026 7:46:29 AM	1312	34.4374220	-118.6463597	Valve Adjustment:Increased Flow/Vacuum
CV-24146	9/29/2026 7:48:05 AM	1305	34.4374292	-118.6463440	
CV-24147	9/14/2026 8:55:38 AM	1280	34.4375253	-118.6459207	Valve Adjustment:Audible Flow
CV-24147	9/29/2026 7:53:08 AM	1297	34.4375065	-118.6459440	Valve Adjustment:Valve 100% Open
CV-24148	9/1/2026 1:15:45 PM	1388	34.4350570	-118.6466701	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24148	9/1/2026 1:21:00 PM				AtmAA
CV-24148	9/1/2026 1:21:00 PM				AtmAA; [User entered 4.905%]
CV-24148	9/9/2026 1:24:00 PM				AtmAA
CV-24148	9/9/2026 1:25:02 PM	1389	34.4350486	-118.6466625	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24148	9/16/2026 9:01:24 AM	1374	34.4350767	-118.6466515	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24148	9/16/2026 9:06:00 AM				AtmAA
CV-24148	9/23/2026 9:17:16 AM	1373	34.4350471	-118.6466506	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24148	9/23/2026 9:21:00 AM				AtmAA
CV-24148	9/30/2026 8:20:00 AM				AtmAA
CV-24148	9/30/2026 8:33:02 AM	1376	34.4350587	-118.6466532	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24149	9/2/2026 2:26:43 PM	1377	34.4348108	-118.6470007	Valve Adjustment:Barely Open
CV-24149	9/28/2026 10:08:01 AM	1374	34.4347757	-118.6469842	Valve Adjustment:Barely Open
CV-24150	9/14/2026 1:00:56 PM	1375	34.4346792	-118.6458260	,
CV-24150	9/22/2026 10:00:08 AM	1386	34.4345958	-118.6457500	Valve Adjustment:Barely Open
CV-24151	9/2/2026 1:38:48 PM	1366	34.4344155	-118.6476508	Valve Adjustment:Decreased Flow/Vacuum
CV-24151	9/28/2026 10:24:52 AM	1372	34.4344018	-118.6476223	Valve Adjustment:Decreased Flow/Vacuum
CV-24152	9/2/2026 2:13:03 PM	1371	34.4344700	-118.6471673	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum,Barely Open

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24152	9/2/2026 2:14:21 PM	1370	34.4344550	-118.6471763	Valve Adjustment:NSPS/EG CAC,High Temp,Barely Open
CV-24152	9/21/2026 2:17:53 PM	1367	34.4344860	-118.6471603	Valve Adjustment:High Temp,Barely Open
CV-24153	9/2/2026 2:35:08 PM	1389	34.4343767	-118.6464272	
CV-24153	9/28/2026 10:19:05 AM	1373	34.4343738	-118.6463667	Valve Adjustment:Barely Open
CV-24154	9/3/2026 12:57:36 PM	1374	34.4342658	-118.6460745	Valve Adjustment:Increased Flow/Vacuum
CV-24154	9/24/2026 1:45:55 PM	1394	34.4342520	-118.6460977	Valve Adjustment:Barely Open
CV-24155	9/2/2026 2:32:05 PM	1402	34.4342888	-118.6467388	Valve Adjustment:Barely Open
CV-24155	9/28/2026 10:12:48 AM	1388	34.4342855	-118.6466958	Valve Adjustment:Barely Open
CV-24156	9/2/2026 8:34:18 AM	1373	34.4340631	-118.6477078	Valve Adjustment:High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24156	9/2/2026 8:35:16 AM	1373	34.4340622	-118.6477081	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24156	9/17/2026 2:44:43 PM	1360	34.4340402	-118.6477392	
CV-24157	9/2/2026 1:17:03 PM	1383	34.4338150	-118.6473410	Valve Adjustment:Barely Open
CV-24157	9/17/2026 2:54:47 PM	1374	34.4338202	-118.6473437	Valve Adjustment:Barely Open
CV-24158	9/2/2026 1:50:00 PM	1383	34.4339030	-118.6470790	Valve Adjustment:Barely Open
CV-24158	9/18/2026 9:48:59 AM	1386	34.4339055	-118.6470555	Valve Adjustment:Barely Open
CV-24159	9/13/2026 10:18:12 AM	1391	34.4338023	-118.6466167	Valve Adjustment:Decreased Flow/Vacuum
CV-24159	9/13/2026 10:19:02 AM	1394	34.4338112	-118.6466227	
CV-24159	9/25/2026 11:34:39 AM	1397	34.4337948	-118.6466287	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Reduce Sys. Vac. - Flare Down;Well Comment:Parnell down at time of read;Well Condition:Lorentz Pump Installed
CV-24159	9/25/2026 11:37:32 AM	1407	34.4337783	-118.6466275	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header
CV-24159	9/25/2026 11:38:14 AM	1402	34.4337793	-118.6466275	
CV-24160	9/13/2026 10:07:13 AM	1383	34.4337957	-118.6462740	Valve Adjustment:Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24160	9/13/2026 10:08:00 AM	1400	34.4338042	-118.6462428	
CV-24160	9/24/2026 2:00:04 PM	1382	34.4337915	-118.6462653	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24161	9/14/2026 1:18:54 PM	1398	34.4338633	-118.6456153	Valve Adjustment:Decreased Flow/Vacuum
CV-24162	9/9/2026 1:08:06 PM	1296	34.4336587	-118.6451240	,
CV-24162	9/14/2026 1:22:08 PM	1396	34.4339360	-118.6460018	Valve Comment:Valve stuck
CV-24163	9/1/2026 9:47:08 AM	1334	34.4334860	-118.6444818	Valve Adjustment:High Temp,Barely Open
CV-24164	9/2/2026 9:23:46 AM	1365	34.4334837	-118.6479817	
CV-24164	9/2/2026 9:26:17 AM	1348	34.4336052	-118.6481718	

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24164	9/17/2026 2:06:22 PM	1378	34.4334953	-118.6480047	Valve Adjustment:Barely Open
CV-24164	9/17/2026 2:07:38 PM	1375	34.4335048	-118.6480008	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24165	9/15/2026 1:44:17 PM	1378	34.4335865	-118.6472948	,
CV-24165	9/30/2026 1:54:12 PM	1391	34.4335258	-118.6472634	Valve Adjustment:No Flow Measurement;Well Condition:Lorentz Pump Installed
CV-24165	9/30/2026 2:18:26 PM	1347	34.4340783	-118.6497226	Valve Adjustment:No Flow Measurement;Well Condition:Lorentz Pump Installed
CV-24166	9/13/2026 10:25:03 AM	1399	34.4336058	-118.6468815	Valve Adjustment:Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24166	9/13/2026 10:25:58 AM	1398	34.4336128	-118.6468483	Well Condition:Lorentz Pump Installed
CV-24166	9/21/2026 8:17:14 AM	1404	34.4335947	-118.6468810	Valve Adjustment:Surging Liquid in Header
CV-24167	9/15/2026 9:35:57 AM	1385	34.4335018	-118.6465045	,
CV-24167	9/30/2026 1:45:26 PM	1400	34.4334452	-118.6464944	Valve Adjustment:No Flow Measurement,Increased Flow/Vacuum,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-24167	9/30/2026 1:46:57 PM	1401	34.4334461	-118.6464909	Valve Adjustment:No Flow Measurement,Valve 100% Open
CV-24168	9/14/2026 2:05:52 PM	1404	34.4333278	-118.6473092	Valve Adjustment:Barely Open
CV-24168	9/21/2026 9:52:58 AM	1393	34.4333117	-118.6473277	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open
CV-24169	9/14/2026 2:01:29 PM	1378	34.4332180	-118.6477258	Valve Adjustment:Decreased Flow/Vacuum
CV-24169	9/28/2026 10:50:36 AM	1385	34.4332050	-118.6476922	Valve Adjustment:Barely Open
CV-24170	9/2/2026 9:09:47 AM	1369	34.4331175	-118.6485170	Valve Adjustment:Barely Open
CV-24170	9/17/2026 1:45:21 PM	1361	34.4331173	-118.6485125	Valve Adjustment:Barely Open
CV-24171	9/14/2026 1:31:04 PM	1397	34.4331873	-118.6466473	Valve Adjustment:Barely Open
CV-24171	9/21/2026 8:30:41 AM	1412	34.4331668	-118.6466512	Valve Adjustment:Increased Flow/Vacuum
CV-24172	9/14/2026 1:41:43 PM	1381	34.4329850	-118.6473162	Valve Adjustment:Barely Open
CV-24172	9/21/2026 9:04:18 AM	1379	34.4329933	-118.6472900	
CV-24173	9/14/2026 1:49:58 PM	1385	34.4329037	-118.6476818	Valve Adjustment:High Temp,Barely Open;Well Condition:Lorentz Pump Installed
CV-24173	9/21/2026 9:21:07 AM	1379	34.4329252	-118.6476558	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24174	9/15/2026 1:52:08 PM	1365	34.4326532	-118.6480363	,
CV-24174	9/24/2026 8:32:37 AM	1387	34.4327130	-118.6480365	Valve Adjustment:Decreased Flow/Vacuum
CV-24175	9/15/2026 9:24:45 AM	1368	34.4326248	-118.6485050	
CV-24175	9/30/2026 8:57:29 AM	1368	34.4326472	-118.6484672	Valve Adjustment:Audible Flow,Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24176	9/1/2026 11:15:56 AM	1355	34.4325073	-118.6488945	NSPS/EG CAI,Positive Static Press.
CV-24176	9/1/2026 11:16:38 AM	1381	34.4324382	-118.6488618	NSPS/EG CAI,Positive Static Press.
CV-24176	9/3/2026 10:17:38 AM	1334	34.4326087	-118.6488848	Valve Adjustment:Positive Static Press.,Valve 100% Open
CV-24176	9/30/2026 9:16:05 AM	1347	34.4326030	-118.6488967	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-24177	9/2/2026 7:09:30 AM	1355	34.4321960	-118.6495027	,
CV-24177	9/22/2026 12:56:38 PM	1283	34.4322772	-118.6494463	,
CV-24178	9/1/2026 2:59:57 PM	1322	34.4324093	-118.6486228	NSPS/EG CAI,Positive Static Press.
CV-24178	9/1/2026 3:02:27 PM	1319	34.4322302	-118.6489377	NSPS/EG CAI,Positive Static Press.
CV-24178	9/3/2026 10:29:19 AM	1361	34.4323703	-118.6485925	Valve Adjustment:Positive Static Press.,Valve 100% Open
CV-24178	9/9/2026 2:38:51 PM	1260	34.4324900	-118.6485782	NSPS/EG CAI,High Temp
CV-24178	9/9/2026 2:41:36 PM	1345	34.4324700	-118.6485798	NSPS/EG CAI,High Temp
CV-24178	9/22/2026 1:58:45 PM	1374	34.4324362	-118.6485943	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-24179	9/1/2026 11:22:17 AM	1263	34.4321268	-118.6492020	,
CV-24179	9/30/2026 11:41:43 AM	1325	34.4320955	-118.6492285	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Reduce Sys. Vac. - Flare Down;Well Comment:Well too tall to adjust
CV-24179	9/30/2026 11:42:38 AM	1340	34.4320860	-118.6492267	
CV-24180	9/1/2026 3:04:20 PM	1283	34.4321597	-118.6488385	NSPS/EG CAI,Positive Static Press.
CV-24180	9/1/2026 3:05:55 PM	1286	34.4320942	-118.6488652	NSPS/EG CAI,Positive Static Press.
CV-24180	9/18/2026 4:27:56 PM	1348	34.4321503	-118.6487858	Valve Adjustment:Decreased Flow/Vacuum
CV-24180	9/22/2026 3:35:15 PM	1346	34.4321258	-118.6488007	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24181	9/1/2026 2:56:29 PM	1322	34.4320537	-118.6484773	NSPS/EG CAI,Positive Static Press.
CV-24181	9/1/2026 2:57:27 PM	1306	34.4321240	-118.6484930	NSPS/EG CAI,Positive Static Press.
CV-24181	9/9/2026 2:02:35 PM	1421	34.4321305	-118.6483708	NSPS/EG CAC,
CV-24181	9/22/2026 3:27:56 PM	1342	34.4321670	-118.6483968	Valve Adjustment:Barely Open
CV-24182	9/1/2026 2:49:50 PM	1398	34.4322618	-118.6481947	,
CV-24182	9/22/2026 3:17:59 PM	1351	34.4322292	-118.6480608	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24183	9/1/2026 2:44:48 PM	1306	34.4322535	-118.6477808	,
CV-24183	9/22/2026 2:15:06 PM	1354	34.4323915	-118.6476695	Valve Adjustment:Barely Open
CV-24184	9/1/2026 2:29:37 PM	1322	34.4325837	-118.6472167	NSPS/EG CAI,High Temp
CV-24184	9/1/2026 2:34:21 PM	1358	34.4321850	-118.6474008	NSPS/EG CAI,High Temp
CV-24184	9/3/2026 12:22:14 PM	1348	34.4325148	-118.6472710	Valve Adjustment:High Temp,Increased Flow/Vacuum
CV-24184	9/3/2026 12:23:03 PM	1350	34.4325265	-118.6472592	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24184	9/22/2026 2:21:19 PM	1368	34.4325403	-118.6472523	Valve Adjustment:Barely Open
CV-24185	9/1/2026 2:19:32 PM	1299	34.4327203	-118.6470285	NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
CV-24185	9/1/2026 2:20:58 PM	1306	34.4326737	-118.6470057	NSPS/EG CAC,

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24185	9/3/2026 12:38:20 PM	1355	34.4326762	-118.6469485	Valve Adjustment:Increased Flow/Vacuum
CV-24185	9/22/2026 2:34:09 PM	1366	34.4326730	-118.6469535	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open
CV-24185	9/22/2026 2:35:54 PM	1362	34.4326875	-118.6469315	Valve Adjustment:NSPS/EG CAC,Barely Open,Surging Liquid in Header
CV-24186	9/15/2026 10:32:27 AM	1374	34.4328470	-118.6465443	Valve Adjustment:Audible Flow
CV-24186	9/22/2026 2:42:35 PM	1366	34.4328407	-118.6465432	Valve Adjustment:Barely Open
CV-24187	9/2/2026 9:24:10 AM	1260	34.4318558	-118.6495158	,
CV-24187	9/22/2026 12:48:46 PM	1266	34.4319670	-118.6495042	,
CV-24187	9/22/2026 2:45:38 PM	1348	34.4324220	-118.6469768	Valve Adjustment:Barely Open
CV-24188	9/2/2026 8:53:02 AM	1230	34.4315455	-118.6501003	,
CV-24188	9/22/2026 10:14:23 AM	1273	34.4315062	-118.6501235	Valve Adjustment:Increased Flow/Vacuum
CV-24189	9/2/2026 8:58:47 AM	1263	34.4313372	-118.6500550	,
CV-24189	9/22/2026 10:07:55 AM	1275	34.4313030	-118.6500181	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open
CV-24189	9/22/2026 10:08:53 AM	1274	34.4313025	-118.6500153	Valve Adjustment:NSPS/EG CAC
CV-24190	9/2/2026 9:15:42 AM	1312	34.4315488	-118.6494625	,
CV-24190	9/22/2026 12:45:58 PM	1371	34.4315985	-118.6495228	,
CV-24192	9/2/2026 9:12:33 AM	1299	34.4313500	-118.6495168	,
CV-24192	9/4/2026 1:39:12 PM	1303	34.4313397	-118.6494930	
CV-24192	9/22/2026 12:39:10 PM	1276	34.4313383	-118.6495360	,
CV-24193	9/1/2026 11:28:13 AM	1306	34.4314840	-118.6492110	,
CV-24193	9/21/2026 11:49:20 AM	1312	34.4315017	-118.6490660	Valve Adjustment:Audible Flow
CV-24194	9/1/2026 1:49:41 PM	1296	34.4318220	-118.6484657	,
CV-24194	9/3/2026 10:43:30 AM	1345	34.4318613	-118.6485208	Valve Adjustment:Increased Flow/Vacuum
CV-24194	9/21/2026 12:40:02 PM	1338	34.4318595	-118.6485112	Valve Adjustment:Orifice Plate Changed (See OP Log),Audible Flow,Increased Flow/Vacuum;Well Comment:Changed OP from 0.50 to 0.75
CV-24194	9/21/2026 12:42:15 PM	1345	34.4318652	-118.6485092	
CV-24195	9/1/2026 1:57:58 PM	1273	34.4317900	-118.6479335	,
CV-24195	9/3/2026 11:04:13 AM	1342	34.4319197	-118.6476668	Valve Adjustment:Increased Flow/Vacuum
CV-24195	9/21/2026 12:26:17 PM	1345	34.4318237	-118.6478848	Valve Adjustment:Audible Flow
CV-24195	9/22/2026 3:15:01 PM	1343	34.4318195	-118.6478692	Valve Adjustment:Barely Open
CV-24196	9/1/2026 2:06:39 PM	1316	34.4320417	-118.6471583	,
CV-24196	9/22/2026 3:03:17 PM	1344	34.4320508	-118.6471755	Valve Adjustment:Barely Open
CV-24197	9/1/2026 2:10:01 PM	1217	34.4324498	-118.6466075	,
CV-24197	9/22/2026 2:56:45 PM	1334	34.4323683	-118.6465750	Valve Adjustment:Barely Open
CV-24198	9/15/2026 12:38:31 PM	1326	34.4315760	-118.6475880	Valve Adjustment:Decreased Flow/Vacuum
CV-24198	9/15/2026 12:40:21 PM	1330	34.4315603	-118.6475888	

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24198	9/30/2026 1:17:46 PM	1346	34.4316255	-118.6476403	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24199	9/15/2026 12:27:13 PM	1338	34.4318142	-118.6473160	
CV-24199	9/15/2026 12:29:31 PM	1341	34.4318080	-118.6473063	Valve Adjustment:Orifice Plate Changed (See OP Log)
CV-24199	9/30/2026 1:27:46 PM	1348	34.4318227	-118.6473313	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24200	9/15/2026 9:58:46 AM	1292	34.4314395	-118.6472363	Valve Adjustment:Decreased Flow/Vacuum
CV-24200	9/15/2026 9:59:38 AM	1294	34.4314277	-118.6472468	
CV-24200	9/30/2026 1:33:17 PM	1302	34.4314577	-118.6472310	Valve Adjustment:Barely Open
CV-24201	9/15/2026 10:10:20 AM	1266	34.4317253	-118.6466435	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-24201	9/15/2026 10:11:55 AM	1280	34.4317500	-118.6466223	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24201	9/15/2026 10:14:30 AM	1280	34.4317480	-118.6466220	Well Condition:Pnumatic Pump Installed
CV-24201	9/24/2026 1:50:00 PM				AtmAA (24 TAT Request)
CV-24201	9/24/2026 1:50:00 PM				AtmAA (24 TAT Request) <0.10; [User entered 0.10%]
CV-24201	9/24/2026 1:50:04 PM				[User entered 2.3%]
CV-24201	9/24/2026 1:50:55 PM	1275	34.4317503	-118.6466507	Valve Adjustment:Reduce Sys. Vac. - Flare Down;Well Condition:Pnumatic Pump Installed
CV-24201	9/24/2026 2:48:38 PM				
CV-24201	9/28/2026 8:40:33 AM	1275	34.4317528	-118.6466283	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum
CV-24201	9/28/2026 8:44:14 AM	1274	34.4317513	-118.6466318	
CV-24202	9/15/2026 4:15:49 PM	1266	34.4319677	-118.6462730	Valve Adjustment:Decreased Flow/Vacuum
CV-24202	9/15/2026 4:17:09 PM	1270	34.4319193	-118.6462603	
CV-24202	9/23/2026 10:59:35 AM	1279	34.4319198	-118.6462808	Valve Adjustment:Increased Flow/Vacuum
CV-24202	9/24/2026 1:32:57 PM				[User entered 1.6%]
CV-24202	9/24/2026 1:35:00 PM				AtmAA (24 TAT Request)
CV-24202	9/24/2026 1:35:00 PM				AtmAA (24 TAT Request) <0.10; [User entered 0.10%]
CV-24202	9/24/2026 1:35:03 PM	1291	34.4319222	-118.6462708	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-24202	9/24/2026 3:14:01 PM				
CV-24203	9/15/2026 9:25:44 AM	1238	34.4315260	-118.6460085	Valve Adjustment:Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24203	9/15/2026 9:28:02 AM	1244	34.4315300	-118.6460148	Valve Adjustment:Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-24203	9/24/2026 12:50:00 PM				AtmAA (24 TAT Request)
CV-24203	9/24/2026 12:50:00 PM				AtmAA (24 TAT Request); [User entered 0.14%]

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24203	9/24/2026 12:53:25 PM				[User entered 3.9%]
CV-24203	9/24/2026 12:54:25 PM	1234	34.4315647	-118.6459937	Valve Adjustment:Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-24203	9/24/2026 2:54:50 PM				
CV-24204	9/15/2026 9:12:51 AM	1245	34.4314145	-118.6462598	Well Condition:Lorentz Pump Installed
CV-24204	9/15/2026 9:15:00 AM	1240	34.4314125	-118.6462587	Valve Adjustment:Orifice Plate Changed (See OP Log)
CV-24204	9/15/2026 9:15:53 AM	1239	34.4314237	-118.6462580	Well Condition:Lorentz Pump Installed
CV-24204	9/25/2026 9:17:43 AM	1227	34.4314310	-118.6462535	
CV-24205	9/15/2026 9:07:09 AM	1234	34.4312307	-118.6464740	Valve Adjustment:Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24205	9/15/2026 9:08:01 AM	1233	34.4312232	-118.6464747	
CV-24205	9/30/2026 4:14:08 PM	1223	34.4312302	-118.6464650	
CV-24206	9/15/2026 9:41:41 AM	1293	34.4315140	-118.6467670	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-24206	9/15/2026 9:45:15 AM	1279	34.4315107	-118.6467832	Well Condition:Pnumatic Pump Installed
CV-24206	9/23/2026 10:43:02 AM	1284	34.4315375	-118.6467783	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open
CV-24206	9/23/2026 10:44:23 AM	1287	34.4315385	-118.6467843	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-24206	9/24/2026 12:30:00 PM				AtmAA (24 TAT Request)
CV-24206	9/24/2026 12:30:00 PM				AtmAA (24 TAT Request); [User entered 0.37%]
CV-24206	9/24/2026 12:33:26 PM				[User entered 3.5%]
CV-24206	9/24/2026 12:37:06 PM	1270	34.4315065	-118.6467857	Valve Adjustment:Reduce Sys. Vac. - Flare Down;Well Condition:Pnumatic Pump Installed
CV-24206	9/24/2026 12:39:33 PM	1271	34.4315013	-118.6467637	Valve Adjustment:Reduce Sys. Vac. - Flare Down;Well Condition:Pnumatic Pump Installed
CV-24206	9/24/2026 3:07:10 PM				
CV-24207	9/3/2026 12:47:00 PM	1390	34.4332975	-118.6469485	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-24207	9/3/2026 12:48:27 PM	1387	34.4332798	-118.6469378	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24207	9/13/2026 1:29:48 PM	1375	34.4332857	-118.6469355	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24207	9/13/2026 1:32:35 PM	1386	34.4332708	-118.6469427	Valve Adjustment:NSPS/EG CAI,Orifice Plate Changed (See OP Log),High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24207	9/13/2026 1:35:07 PM	1392	34.4332733	-118.6469483	Valve Adjustment:High Temp,Increased Flow/Vacuum

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24207	9/13/2026 1:35:54 PM	1396	34.4332788	-118.6469503	Valve Adjustment:High Temp
CV-24207	9/21/2026 8:26:11 AM	1393	34.4332750	-118.6469535	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24208	9/24/2026 10:14:51 AM	1255	34.4318913	-118.6451020	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24208	9/24/2026 10:16:08 AM	1256	34.4319008	-118.6450930	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24209	9/30/2026 2:11:34 PM	1294	34.4321832	-118.6456147	Valve Adjustment:NSPS/EG CAI,High Temp,Reduce Sys. Vac. - Flare Down
CV-24210	9/9/2026 1:42:55 PM	1312	34.4326083	-118.6456548	,
CV-24211	9/28/2026 2:53:00 PM	1253	34.4327265	-118.6438603	Valve Adjustment:Decreased Flow/Vacuum
CV-24212	9/28/2026 2:46:21 PM	1252	34.4331540	-118.6430773	Valve Adjustment:Decreased Flow/Vacuum
CV-24213	9/4/2026 9:21:22 AM	1322	34.4366015	-118.6429617	Valve Adjustment:Increased Flow/Vacuum
CV-24214	9/30/2026 1:49:40 PM	1321	34.4367497	-118.6435122	
CV-24215	9/30/2026 1:28:04 PM	1307	34.4369473	-118.6448165	
CV-24216	9/16/2026 11:46:26 AM	1306	34.4368255	-118.6422970	Valve Adjustment:Decreased Flow/Vacuum
CV-24217	9/3/2026 1:30:59 PM	1380	34.4359225	-118.6443843	Valve Adjustment:Barely Open
CV-24218	9/14/2026 1:37:55 PM	1266	34.4357750	-118.6459403	,
CV-24219	9/1/2026 9:17:40 AM	1395	34.4350964	-118.6462255	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24219	9/1/2026 9:23:00 AM				AtmAA
CV-24219	9/1/2026 9:23:00 AM				AtmAA; [User entered 11.03%]
CV-24219	9/9/2026 10:37:30 AM	1398	34.4350904	-118.6462286	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24219	9/9/2026 10:37:57 AM	1399	34.4350896	-118.6462289	
CV-24219	9/9/2026 10:42:00 AM				AtmAA
CV-24219	9/15/2026 1:45:00 PM				AtmAA
CV-24219	9/15/2026 1:50:49 PM	1393	34.4350933	-118.6462376	Valve Adjustment:NSPS/EG CAI,Decom Well (Temporary),No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24219	9/15/2026 1:52:47 PM	1395	34.4350976	-118.6462375	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24219	9/22/2026 2:24:19 PM	1379	34.4350910	-118.6462265	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24219	9/22/2026 2:26:00 PM				AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24219	9/29/2026 1:44:55 PM	1393	34.4350993	-118.6462309	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24219	9/29/2026 1:45:41 PM	1388	34.4350982	-118.6462408	Well Condition:Lorentz Pump Installed
CV-24219	9/29/2026 1:50:00 PM				AtmAA
CV-24220	9/1/2026 9:58:34 AM	1339	34.4339702	-118.6439713	Valve Adjustment:Barely Open,Surging Liquid in Header,Plugged/Pinched Suspected
CV-24220	9/8/2026 9:02:20 AM	1379	34.4339354	-118.6439285	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24220	9/8/2026 9:07:51 AM				Valve Adjustment:No Flow Measurement;Well Condition:Lorentz Pump Installed
CV-24221	9/28/2026 2:25:52 PM	1250	34.4341298	-118.6421518	Valve Adjustment:Decreased Flow/Vacuum
CV-24222	9/30/2026 8:21:47 AM	1257	34.4336020	-118.6420043	Valve Adjustment:Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-24223	9/28/2026 2:38:35 PM	1244	34.4334207	-118.6425758	Valve Adjustment:Barely Open
CV-24224	9/30/2026 9:30:13 AM	1321	34.4331493	-118.6448345	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-24224	9/30/2026 9:30:54 AM	1325	34.4331415	-118.6448350	Valve Adjustment:Barely Open,Reduce Sys. Vac. - Flare Down
CV-24224	9/30/2026 2:00:06 PM	1331	34.4331565	-118.6448268	Valve Adjustment:Barely Open
CV-24225	9/1/2026 9:07:25 AM	1295	34.4327197	-118.6444303	Valve Adjustment:Barely Open
CV-24226	9/28/2026 2:56:01 PM	1249	34.4325337	-118.6442788	Valve Adjustment:Barely Open
CV-24227	9/2/2026 9:09:03 AM	1240	34.4309270	-118.6498232	Increased Flow/Vacuum,
CV-24227	9/4/2026 1:33:49 PM	1274	34.4309582	-118.6497832	Valve Adjustment:Increased Flow/Vacuum
CV-24227	9/22/2026 12:30:13 PM	1257	34.4309208	-118.6498442	,
CV-24231	9/30/2026 12:42:54 PM	1273	34.4302777	-118.6496547	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-24236	9/2/2026 1:22:24 PM	1168	34.4300885	-118.6504988	,
CV-24237	9/2/2026 1:11:47 PM	1191	34.4306342	-118.6502053	Increased Flow/Vacuum,
CV-24237	9/4/2026 2:04:02 PM	1213	34.4306128	-118.6502200	Valve Adjustment:Increased Flow/Vacuum
CV-24243	9/17/2026 12:16:52 PM	1205	34.4287647	-118.6506745	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum
CV-24243	9/17/2026 12:30:09 PM	1190	34.4287782	-118.6506690	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-24243	9/17/2026 12:37:43 PM	1201	34.4287717	-118.6506562	Valve Adjustment:High O2
CV-24243	9/22/2026 1:52:57 PM	1206	34.4287828	-118.6506487	Valve Adjustment:NSPS/EG CAC
CV-24244	9/16/2026 8:41:03 AM	1207	34.4289962	-118.6513460	Valve Adjustment:Increased Flow/Vacuum
CV-24244	9/16/2026 8:43:19 AM	1193	34.4290265	-118.6513248	

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-24245	9/28/2026 10:15:21 AM	1163	34.4284875	-118.6500863	Valve Adjustment:Increased Flow/Vacuum
CV-24245	9/28/2026 10:17:16 AM	1163	34.4284883	-118.6500860	
CV-24246	9/4/2026 9:59:35 AM	1177	34.4286630	-118.6494528	Valve Adjustment:Positive Static Press.,Increased Flow/Vacuum
CV-24246	9/4/2026 10:00:29 AM	1181	34.4286648	-118.6494527	
CV-24253	9/28/2026 9:37:51 AM	1153	34.4284638	-118.6498265	Valve Adjustment:Increased Flow/Vacuum
CV-24253	9/28/2026 9:39:46 AM	1150	34.4284662	-118.6498218	
CV-25	9/21/2026 8:45:49 AM	1260	34.4370123	-118.6420942	
CV-2501	9/4/2026 1:08:58 PM	1310	34.4313455	-118.6484332	Valve Adjustment:Increased Flow/Vacuum
CV-2502	9/11/2026 10:11:06 AM	1316	34.4308813	-118.6491094	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Valve 100% Closed
CV-2502	9/11/2026 10:12:18 AM	1316	34.4308814	-118.6491091	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-2503	9/11/2026 10:21:39 AM	1303	34.4312184	-118.6477578	Valve Adjustment:Increased Flow/Vacuum
CV-2503	9/23/2026 12:40:37 PM	1302	34.4312297	-118.6477603	Valve Adjustment:Increased Flow/Vacuum
CV-2504	9/23/2026 10:20:47 AM	1272	34.4303778	-118.6489542	Valve Adjustment:Increased Flow/Vacuum
CV-2504	9/23/2026 10:23:26 AM	1274	34.4303848	-118.6489475	
CV-2505	9/23/2026 12:39:50 PM	1242	34.4308168	-118.6471838	Valve Adjustment:Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2506	9/23/2026 12:41:42 PM	1245	34.4308110	-118.6471653	Well Condition:Lorentz Pump Installed
CV-2506	9/23/2026 1:16:38 PM	1237	34.4304637	-118.6475620	
CV-2507	9/23/2026 1:33:01 PM	1212	34.4301367	-118.6481625	Valve Adjustment:Increased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-2507	9/23/2026 1:36:04 PM	1214	34.4301413	-118.6481570	
CV-2508	9/23/2026 2:08:04 PM	1189	34.4297225	-118.6487580	
CV-2509	9/4/2026 10:15:57 AM	1181	34.4292533	-118.6491843	Valve Adjustment:Increased Flow/Vacuum
CV-2510	9/4/2026 10:06:27 AM	1193	34.4290505	-118.6498313	Valve Adjustment:Increased Flow/Vacuum
CV-25100D	9/3/2026 10:05:34 AM	1365	34.4361387	-118.6471250	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open
CV-25100D	9/3/2026 10:06:21 AM	1371	34.4361427	-118.6471307	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-25100D	9/3/2026 10:34:00 AM				AtmAA
CV-25100D	9/3/2026 10:34:00 AM				AtmAA; [User entered 6.3%]
CV-25100D	9/8/2026 1:58:00 PM				AtmAA
CV-25100D	9/8/2026 1:58:37 PM	1385	34.4361739	-118.6471388	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-25100D	9/14/2026 1:43:20 PM	1383	34.4361723	-118.6471456	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-25100D	9/25/2026 2:09:25 PM	1371	34.4362112	-118.6471577	Valve Adjustment:Barely Open

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-25100S	9/8/2026 1:54:00 PM				AtmAA
CV-25100S	9/8/2026 1:54:17 PM	1382	34.4361660	-118.6471288	Valve Adjustment:No Flow Measurement,High Temp
CV-25100S	9/14/2026 1:46:48 PM	1383	34.4361652	-118.6471451	Valve Adjustment:No Flow Measurement,High Temp
CV-25100S	9/14/2026 1:47:00 PM				AtmAA
CV-25100S	9/21/2026 1:22:46 PM	1371	34.4361619	-118.6471508	Valve Adjustment:No Flow Measurement,High Temp
CV-25100S	9/21/2026 1:24:00 PM				AtmAA
CV-25100S	9/28/2026 1:43:54 PM	1381	34.4361663	-118.6471300	Valve Adjustment:No Flow Measurement,High Temp
CV-25100S	9/28/2026 1:55:00 PM				AtmAA
CV-25101D	9/3/2026 9:32:55 AM	1377	34.4359590	-118.6467967	Valve Adjustment:Barely Open
CV-25101D	9/22/2026 10:51:18 AM	1385	34.4359605	-118.6467978	Valve Adjustment:Barely Open
CV-25101S	9/3/2026 9:34:39 AM	1377	34.4359747	-118.6467778	Valve Adjustment:Barely Open
CV-25101S	9/22/2026 10:53:04 AM	1385	34.4359565	-118.6468050	Valve Adjustment:Barely Open
CV-25102	9/14/2026 9:45:37 AM	1339	34.4358030	-118.6473307	,
CV-25102	9/14/2026 9:46:33 AM	1299	34.4359130	-118.6471542	,
CV-25102	9/14/2026 1:20:00 PM				AtmAA
CV-25102	9/21/2026 9:40:00 AM				AtmAA
CV-25102	9/21/2026 9:46:14 AM	1375	34.4357959	-118.6471970	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-25102	9/21/2026 9:48:39 AM	1375	34.4357955	-118.6471971	Valve Adjustment:Audible Flow,No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-25102	9/28/2026 10:49:11 AM	1372	34.4357783	-118.6471935	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-25102	9/28/2026 1:05:00 PM				AtmAA
CV-25102	9/30/2026 8:30:50 AM	1374	34.4357825	-118.6471932	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-25102	9/30/2026 8:32:19 AM	1374	34.4357815	-118.6471928	
CV-25103	9/3/2026 9:09:00 AM	1374	34.4356168	-118.6467338	Valve Adjustment:Barely Open
CV-25103	9/22/2026 10:46:56 AM	1381	34.4356483	-118.6467095	Valve Adjustment:Barely Open
CV-25104D	9/15/2026 9:02:09 AM	1339	34.4354213	-118.6472855	,
CV-25104D	9/15/2026 9:02:43 AM	1378	34.4353730	-118.6472162	,
CV-25104D	9/23/2026 1:35:53 PM	1368	34.4353770	-118.6472283	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open;Well Condition:Lorentz Pump Installed
CV-25104S	9/14/2026 9:28:09 AM	1329	34.4354580	-118.6471855	,
CV-25104S	9/14/2026 9:28:26 AM	1362	34.4354128	-118.6471958	,
CV-25104S	9/21/2026 10:03:05 AM	1378	34.4353661	-118.6472328	Valve Adjustment:Audible Flow,No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-25104S	9/30/2026 9:51:41 AM	1379	34.4353421	-118.6472406	Valve Adjustment:No Flow Measurement

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-25105D	9/3/2026 8:36:30 AM	1386	34.4353675	-118.6467145	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-25105D	9/3/2026 8:39:20 AM	1397	34.4353710	-118.6466988	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-25105D	9/25/2026 11:09:43 AM	1383	34.4353582	-118.6466908	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-25105D	9/25/2026 11:12:40 AM	1379	34.4353510	-118.6466997	
CV-25105S	9/3/2026 8:42:42 AM	1394	34.4353628	-118.6467072	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25105S	9/3/2026 8:43:52 AM	1396	34.4353677	-118.6467120	Valve Adjustment:High O2,Barely Open
CV-25105S	9/25/2026 10:57:59 AM	1396	34.4353772	-118.6467088	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In);Well Comment:No pump
CV-25105S	9/25/2026 10:59:33 AM	1394	34.4353805	-118.6467123	
CV-25106D	9/14/2026 9:16:26 AM	1371	34.4350583	-118.6474012	,
CV-25106D	9/21/2026 2:39:29 PM	1355	34.4350822	-118.6473845	Valve Adjustment:Barely Open;Well Condition:Pnumatic Pump Installed
CV-25106S	9/15/2026 9:01:26 AM	1366	34.4350408	-118.6473680	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In)
CV-25106S	9/15/2026 9:02:41 AM	1366	34.4350378	-118.6473498	
CV-25106S	9/21/2026 2:36:58 PM	1362	34.4350632	-118.6473828	Valve Adjustment:High O2,Barely Open,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
CV-25107D	9/1/2026 9:37:00 AM				AtmAA
CV-25107D	9/1/2026 9:37:00 AM				AtmAA; [User entered 11.01%]
CV-25107D	9/1/2026 9:41:08 AM	1394	34.4350678	-118.6459510	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-25107D	9/1/2026 9:49:48 AM	1390	34.4350571	-118.6459631	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-25107D	9/1/2026 9:52:33 AM	1391	34.4350530	-118.6459614	Valve Adjustment:No Flow Measurement,High Temp
CV-25107D	9/1/2026 10:04:00 AM				AtmAA; [User entered 11.01%]
CV-25107D	9/9/2026 10:27:10 AM	1404	34.4350433	-118.6459781	Valve Adjustment:No Flow Measurement,High Temp
CV-25107D	9/9/2026 10:32:44 AM	1404	34.4350493	-118.6459781	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-25107D	9/9/2026 10:33:42 AM	1404	34.4350494	-118.6459779	
CV-25107D	9/9/2026 10:35:00 AM				AtmAA
CV-25107D	9/15/2026 1:35:00 PM				AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-25107D	9/15/2026 1:35:50 PM	1402	34.4350638	-118.6459660	Valve Adjustment:No Flow Measurement,High Temp
CV-25107D	9/15/2026 1:39:57 PM	1401	34.4350641	-118.6459709	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Surging Liquid in Header
CV-25107D	9/22/2026 2:13:00 PM				AtmAA
CV-25107D	9/22/2026 2:20:08 PM	1403	34.4350618	-118.6459605	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-25107D	9/29/2026 1:39:25 PM	1394	34.4350416	-118.6459700	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-25107D	9/29/2026 1:40:00 PM				AtmAA
CV-25107S	9/3/2026 12:53:12 PM	1380	34.4350475	-118.6459542	Valve Adjustment:Barely Open
CV-25107S	9/22/2026 10:17:17 AM	1373	34.4350365	-118.6459687	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header
CV-25107S	9/22/2026 10:19:04 AM	1378	34.4350417	-118.6459593	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2511	9/30/2026 1:02:49 PM	1247	34.4296585	-118.6501777	Valve Adjustment:Audible Flow,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
CV-2512	9/4/2026 10:31:39 AM	1247	34.4292485	-118.6506277	Valve Adjustment:Increased Flow/Vacuum
CV-2513	9/17/2026 1:56:08 PM	1156	34.4288257	-118.6488242	
CV-2513	9/17/2026 1:59:17 PM	1154	34.4288262	-118.6488200	Valve Adjustment:Orifice Plate Changed (See OP Log)
CV-2514	9/21/2026 10:01:35 AM	1151	34.4296145	-118.6477938	Valve Adjustment:Increased Flow/Vacuum,Surging Liquid in Header
CV-2514	9/21/2026 10:07:35 AM	1155	34.4296012	-118.6477977	
CV-2515	9/29/2026 10:32:00 AM	1253	34.4378905	-118.6432107	Valve Adjustment:Decreased Flow/Vacuum
CV-2515	9/29/2026 10:36:37 AM	1255	34.4378745	-118.6432197	Valve Adjustment:Orifice Plate Changed (See OP Log)
CV-2515	9/29/2026 10:37:18 AM	1264	34.4379030	-118.6432222	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-2515	9/29/2026 10:40:01 AM	1264	34.4378942	-118.6432200	Valve Comment:Removed differential port blockage
CV-2516	9/16/2026 11:55:45 AM	1297	34.4374025	-118.6431808	Valve Adjustment:Audible Flow
CV-2517	9/21/2026 9:13:49 AM	1267	34.4369505	-118.6420208	
CV-2518	9/21/2026 9:35:14 AM	1247	34.4364008	-118.6414373	
CV-2519	9/22/2026 2:34:58 PM	1381	34.4361342	-118.6419822	,
CV-2520	9/22/2026 2:46:22 PM	1339	34.4358263	-118.6427397	,
CV-2520	9/22/2026 2:48:41 PM	1293	34.4358582	-118.6427438	,
CV-2521	9/30/2026 8:54:33 AM	1331	34.4354747	-118.6430567	Valve Adjustment:Valve 100% Open,Reduce Sys. Vac. - Flare Down

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2521	9/30/2026 12:10:46 PM	1329	34.4354790	-118.6430585	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down;Well Comment:No pump
CV-2521	9/30/2026 12:11:47 PM	1329	34.4354862	-118.6430565	
CV-2522	9/22/2026 3:06:29 PM	1263	34.4355943	-118.6423742	,
CV-2522	9/22/2026 3:07:55 PM	1257	34.4355928	-118.6424520	,
CV-2523	9/25/2026 11:36:15 AM	1286	34.4356635	-118.6416667	
CV-2524	9/22/2026 3:14:40 PM	1332	34.4348030	-118.6424923	NSPS/EG CAI,High Temp
CV-2524	9/22/2026 3:18:41 PM	1260	34.4346678	-118.6425243	NSPS/EG CAC,
CV-2525	9/25/2026 11:17:14 AM	1276	34.4349688	-118.6417315	Valve Adjustment:Decreased Flow/Vacuum
CV-2526	9/29/2026 9:14:52 AM	1270	34.4345157	-118.6415813	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-2527	9/14/2026 8:36:25 AM	1304	34.4340957	-118.6428678	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-2527	9/14/2026 8:37:20 AM	1307	34.4340973	-118.6428842	
CV-2527	9/30/2026 9:05:03 AM	1318	34.4340880	-118.6428660	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Reduce Sys. Vac. - Flare Down
CV-2527	9/30/2026 9:07:01 AM	1305	34.4341018	-118.6428687	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-2527	9/30/2026 9:11:36 AM	1319	34.4340958	-118.6428758	Valve Adjustment:Decreased Flow/Vacuum
CV-2527	9/30/2026 9:12:30 AM	1319	34.4340957	-118.6428798	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-2527	9/30/2026 12:24:57 PM	1309	34.4340902	-118.6428787	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open,Reduce Sys. Vac. - Flare Down
CV-2527	9/30/2026 12:26:17 PM	1307	34.4340925	-118.6428720	Valve Adjustment:NSPS/EG CAC
CV-2528	9/21/2026 10:33:20 AM	1241	34.4337997	-118.6412453	
CV-2529	9/4/2026 8:05:25 AM	1229	34.4331448	-118.6423483	Valve Adjustment:Positive Static Press.,Increased Flow/Vacuum,Barely Open
CV-2529	9/4/2026 8:07:06 AM	1226	34.4331263	-118.6423528	
CV-2530	9/28/2026 3:53:58 PM	1223	34.4327540	-118.6429517	Valve Comment:Valve stuck open
CV-2531	9/28/2026 3:43:12 PM	1225	34.4325842	-118.6433368	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-2532	9/30/2026 8:40:47 AM	1214	34.4322510	-118.6437185	Well Condition:Pnumatic Pump Installed;Well Repairs:Sample Port
CV-2533	9/28/2026 3:24:49 PM	1194	34.4319202	-118.6440960	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-2534	9/1/2026 11:25:42 AM	1302	34.4317317	-118.6491760	,
CV-2534	9/28/2026 3:16:57 PM	1215	34.4316987	-118.6445058	Valve Adjustment:Decreased Flow/Vacuum
CV-2535	9/23/2026 12:53:43 PM	1249	34.4309728	-118.6469200	Valve Adjustment:Decreased Flow/Vacuum
CV-2536	9/25/2026 9:51:12 AM	1182	34.4309900	-118.6458555	
CV-2537	9/25/2026 9:09:18 AM	1223	34.4310497	-118.6466448	
CV-2538	9/25/2026 8:54:18 AM	1216	34.4308187	-118.6467205	

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2539	9/15/2026 10:51:41 AM	1322	34.4317167	-118.6492018	Valve Adjustment:Barely Open
CV-2539	9/21/2026 12:01:09 PM	1320	34.4317142	-118.6491973	Valve Adjustment:Barely Open
CV-2540	9/2/2026 9:19:21 AM	1367	34.4332697	-118.6480940	Valve Adjustment:Decreased Flow/Vacuum
CV-2540	9/17/2026 1:58:14 PM	1373	34.4332718	-118.6481188	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2541	9/1/2026 10:53:11 AM	1309	34.4332297	-118.6491375	,
CV-2541	9/17/2026 10:16:55 AM	1340	34.4332678	-118.6490583	Valve Adjustment:Decreased Flow/Vacuum
CV-2542	9/2/2026 1:13:18 PM	1389	34.4337235	-118.6471813	Valve Adjustment:Valve 100% Open
CV-2542	9/17/2026 3:00:18 PM	1383	34.4337205	-118.6472078	Valve Comment:Hard pipped;Valve Adjustment:Increased Flow/Vacuum
CV-2543-PLR	9/2/2026 9:36:06 AM	1343	34.4338343	-118.6484718	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-2543-PLR	9/17/2026 2:16:09 PM	1348	34.4338625	-118.6485018	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-2544	9/15/2026 9:11:52 AM	1348	34.4339618	-118.6471392	,
CV-2544	9/15/2026 9:14:07 AM	1388	34.4339843	-118.6472425	NSPS/EG CAI,High Temp
CV-2544	9/15/2026 9:33:39 AM	1401	34.4333795	-118.6465553	NSPS/EG CAI,High Temp
CV-2544	9/21/2026 10:26:52 AM	1386	34.4340300	-118.6472290	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2544	9/21/2026 10:35:00 AM				AtmAA
CV-2545	9/2/2026 1:57:34 PM	1385	34.4340253	-118.6467365	Valve Adjustment:Barely Open
CV-2545	9/2/2026 2:00:03 PM	1392	34.4340200	-118.6467337	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-2545	9/21/2026 1:45:21 PM	1403	34.4340103	-118.6467513	Valve Adjustment:Barely Open
CV-2546	9/2/2026 2:02:59 PM	1375	34.4341267	-118.6469773	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum,Barely Open
CV-2546	9/2/2026 2:03:29 PM	1385	34.4341332	-118.6469887	Valve Adjustment:Barely Open
CV-2546	9/21/2026 2:15:18 PM	1381	34.4341222	-118.6469958	Valve Adjustment:Barely Open
CV-2547	9/24/2026 1:41:35 PM	1389	34.4339323	-118.6459912	Valve Adjustment:Barely Open
CV-2548	9/1/2026 12:26:39 PM	1393	34.4343298	-118.6455988	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-2548	9/1/2026 12:27:39 PM	1388	34.4343440	-118.6456083	
CV-2548	9/3/2026 1:03:06 PM	1388	34.4343420	-118.6455865	Valve Adjustment:Increased Flow/Vacuum
CV-2548	9/18/2026 2:00:15 PM	1421	34.4343682	-118.6455775	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open;Well Condition:Lorentz Pump Installed
CV-2548	9/18/2026 2:02:16 PM	1426	34.4343600	-118.6455920	Valve Adjustment:Orifice Plate Changed (See OP Log),High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2548	9/22/2026 9:25:43 AM	1392	34.4343344	-118.6455764	Valve Adjustment:Increased Flow/Vacuum
CV-2549	9/1/2026 12:15:56 PM	1391	34.4343870	-118.6452748	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum,Surging Liquid in Header;Well Comment:Changed OP from 1.25 to 0.75
CV-2549	9/1/2026 12:17:23 PM	1390	34.4343903	-118.6452725	
CV-2549	9/3/2026 1:08:50 PM	1388	34.4343680	-118.6452770	Valve Adjustment:Increased Flow/Vacuum,Barely Open
CV-2549	9/18/2026 1:52:07 PM	1431	34.4344150	-118.6452565	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-2549	9/18/2026 1:53:32 PM	1412	34.4343935	-118.6452855	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-2550	9/1/2026 1:08:00 PM				AtmAA
CV-2550	9/1/2026 1:08:00 PM				AtmAA; [User entered 11.39%]
CV-2550	9/1/2026 1:09:01 PM	1378	34.4348080	-118.6461649	Valve Adjustment:No Flow Measurement,High Temp
CV-2550	9/9/2026 1:03:44 PM	1381	34.4348152	-118.6461675	Valve Adjustment:No Flow Measurement,High Temp
CV-2550	9/9/2026 1:05:00 PM				AtmAA
CV-2550	9/16/2026 9:45:27 AM	1372	34.4348126	-118.6461678	Valve Adjustment:No Flow Measurement,High Temp
CV-2550	9/16/2026 9:48:00 AM				AtmAA
CV-2550	9/23/2026 9:05:00 AM				AtmAA
CV-2550	9/23/2026 9:06:42 AM	1376	34.4348121	-118.6461876	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2550	9/30/2026 8:10:00 AM				AtmAA
CV-2550	9/30/2026 8:13:11 AM	1369	34.4348194	-118.6461580	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2551	9/1/2026 9:06:00 AM				AtmAA
CV-2551	9/1/2026 9:06:00 AM				AtmAA; [User entered 7.93%]
CV-2551	9/9/2026 10:15:15 AM	1394	34.4349336	-118.6458154	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2551	9/9/2026 10:25:00 AM				AtmAA
CV-2551	9/15/2026 1:29:53 PM	1408	34.4349401	-118.6458381	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2551	9/15/2026 1:30:00 PM				AtmAA
CV-2551	9/22/2026 2:05:45 PM	1405	34.4349389	-118.6458271	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2551	9/22/2026 2:07:00 PM				AtmAA
CV-2551	9/29/2026 1:30:00 PM				AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2551	9/29/2026 1:30:09 PM	1398	34.4349211	-118.6458237	Valve Adjustment:High Temp,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-2552	9/1/2026 1:12:06 PM	1392	34.4348684	-118.6465507	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2552	9/1/2026 1:16:00 PM				AtmAA
CV-2552	9/1/2026 1:16:00 PM				AtmAA; [User entered 7.45%]
CV-2552	9/9/2026 1:16:00 PM				AtmAA
CV-2552	9/9/2026 1:17:03 PM	1385	34.4348737	-118.6465371	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2552	9/16/2026 8:55:00 AM				AtmAA
CV-2552	9/16/2026 8:55:21 AM	1378	34.4348783	-118.6465171	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2552	9/23/2026 9:14:44 AM	1376	34.4348846	-118.6465267	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2552	9/23/2026 9:15:00 AM				AtmAA
CV-2552	9/30/2026 8:15:00 AM				AtmAA
CV-2552	9/30/2026 8:27:07 AM	1374	34.4348794	-118.6465258	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2553	9/2/2026 9:50:00 AM	1339	34.4341628	-118.6489138	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-2553	9/17/2026 10:55:57 AM	1342	34.4341562	-118.6489118	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-2554	9/1/2026 2:17:21 PM	1360	34.4344608	-118.6482734	Valve Adjustment:No Flow Measurement,High Temp
CV-2554	9/1/2026 2:20:00 PM				AtmAA
CV-2554	9/1/2026 2:20:00 PM				AtmAA; [User entered 5.97%]
CV-2554	9/10/2026 8:49:04 AM	1358	34.4344607	-118.6482651	Valve Adjustment:No Flow Measurement,High Temp
CV-2554	9/10/2026 8:51:00 AM				AtmAA
CV-2554	9/16/2026 10:15:07 AM	1354	34.4344641	-118.6482674	Valve Adjustment:No Flow Measurement,High Temp
CV-2554	9/16/2026 10:17:00 AM				AtmAA
CV-2554	9/23/2026 10:20:05 AM	1353	34.4344504	-118.6482660	Valve Adjustment:No Flow Measurement,High Temp
CV-2554	9/23/2026 10:25:00 AM				AtmAA
CV-2554	9/30/2026 9:20:33 AM	1356	34.4344741	-118.6482482	Valve Adjustment:No Flow Measurement,High Temp
CV-2554	9/30/2026 9:30:00 AM				AtmAA
CV-2555	9/14/2026 10:19:23 AM	1339	34.4347467	-118.6477035	,
CV-2555	9/21/2026 2:31:09 PM	1355	34.4348352	-118.6477542	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2556-PLR	9/1/2026 1:23:16 PM	1371	34.4351565	-118.6472239	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2556-PLR	9/1/2026 1:29:00 PM				AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2556-PLR	9/1/2026 1:29:00 PM				AtmAA; [User entered 8.49%]
CV-2556-PLR	9/9/2026 1:31:40 PM	1367	34.4351636	-118.6471996	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2556-PLR	9/9/2026 1:37:00 PM				AtmAA
CV-2556-PLR	9/16/2026 9:12:40 AM	1363	34.4351583	-118.6472166	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.;Well Condition:Lorentz Pump Installed
CV-2556-PLR	9/16/2026 9:18:00 AM				AtmAA
CV-2556-PLR	9/16/2026 9:20:48 AM	1360	34.4351579	-118.6471987	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2556-PLR	9/16/2026 9:21:53 AM	1359	34.4351558	-118.6472029	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2556-PLR	9/23/2026 9:27:28 AM	1366	34.4351569	-118.6471918	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2556-PLR	9/23/2026 9:30:00 AM				AtmAA
CV-2556-PLR	9/30/2026 8:45:00 AM				AtmAA
CV-2556-PLR	9/30/2026 8:45:01 AM	1362	34.4351535	-118.6471946	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2557	9/15/2026 8:51:14 AM	1352	34.4355248	-118.6465558	NSPS/EG CAI,High Temp
CV-2557	9/15/2026 8:52:00 AM	1348	34.4355342	-118.6464980	NSPS/EG CAI,High Temp
CV-2557	9/22/2026 10:25:41 AM	1390	34.4354872	-118.6464842	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-2558-PLR	9/1/2026 10:13:00 AM				AtmAA
CV-2558-PLR	9/1/2026 10:13:00 AM				AtmAA; [User entered 7%]
CV-2558-PLR	9/1/2026 10:28:32 AM				Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2558-PLR	9/9/2026 1:00:56 PM	1388	34.4352914	-118.6463292	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2558-PLR	9/9/2026 1:10:00 PM				AtmAA
CV-2558-PLR	9/15/2026 2:10:00 PM				AtmAA
CV-2558-PLR	9/15/2026 2:11:15 PM	1391	34.4352955	-118.6463191	Valve Adjustment:High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2558-PLR	9/23/2026 8:35:00 AM				AtmAA
CV-2558-PLR	9/23/2026 8:42:47 AM	1386	34.4352957	-118.6463184	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open;Well Condition:Pnumatic Pump Installed
CV-2558-PLR	9/29/2026 2:05:00 PM				AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2558-PLR	9/29/2026 2:07:13 PM	1390	34.4352908	-118.6463089	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-2559	9/14/2026 1:31:45 PM	1355	34.4357713	-118.6455095	,
CV-2559	9/22/2026 9:49:02 AM	1388	34.4357428	-118.6454868	Valve Adjustment:High Temp,Barely Open
CV-2560	9/3/2026 9:21:28 AM	1391	34.4358958	-118.6466598	Valve Adjustment:High Temp,Barely Open
CV-2560	9/22/2026 10:49:07 AM	1394	34.4359138	-118.6466578	Valve Adjustment:High Temp,Barely Open
CV-2561	9/3/2026 9:41:08 AM	1376	34.4360748	-118.6466135	Valve Adjustment:Barely Open
CV-2561	9/25/2026 2:14:35 PM	1394	34.4360888	-118.6466068	Valve Adjustment:Barely Open
CV-2562	9/14/2026 1:42:18 PM	1306	34.4361413	-118.6459982	,
CV-2563	9/23/2026 8:42:14 AM	1313	34.4373045	-118.6457717	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Comment:No OP
CV-2564	9/1/2026 10:33:16 AM	1289	34.4331910	-118.6487370	,
CV-2564	9/17/2026 10:06:15 AM	1347	34.4331303	-118.6487315	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-2565	9/1/2026 11:35:08 AM	1293	34.4320288	-118.6489437	,
CV-2565	9/4/2026 1:22:35 PM	1326	34.4319940	-118.6489847	Valve Adjustment:Increased Flow/Vacuum
CV-2565	9/30/2026 11:33:22 AM	1338	34.4319660	-118.6489923	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-2566	9/1/2026 11:33:06 AM	1342	34.4318257	-118.6487872	,
CV-2566	9/21/2026 11:57:56 AM	1331	34.4317940	-118.6487693	Valve Adjustment:Decreased Flow/Vacuum
CV-2567	9/1/2026 1:52:22 PM	1319	34.4319495	-118.6479698	,
CV-2567	9/21/2026 12:33:36 PM	1350	34.4319712	-118.6481002	Valve Adjustment:Audible Flow
CV-2568	9/1/2026 2:47:30 PM	1371	34.4322285	-118.6477988	,
CV-2568	9/3/2026 11:10:53 AM	1358	34.4321577	-118.6477598	Valve Adjustment:Increased Flow/Vacuum,Barely Open
CV-2568	9/22/2026 3:09:14 PM	1348	34.4321603	-118.6477297	Valve Adjustment:Barely Open
CV-2569	9/1/2026 2:37:13 PM	1322	34.4322047	-118.6474113	,
CV-2569	9/24/2026 12:16:37 PM	1344	34.4322192	-118.6473983	Valve Adjustment:Audible Flow
CV-2570	9/1/2026 2:13:36 PM	1296	34.4326718	-118.6471275	,
CV-2570	9/30/2026 1:55:05 PM	1357	34.4324270	-118.6469898	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-2571	9/2/2026 10:53:10 AM	1140	34.4299500	-118.6457250	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-2572	9/30/2026 10:38:28 AM	1135	34.4297853	-118.6470640	Valve Adjustment:Barely Open
CV-2602	9/28/2026 9:13:58 AM	1148	34.4284570	-118.6497975	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-2603	9/17/2026 1:31:00 PM	1128	34.4283382	-118.6487775	Valve Adjustment:Orifice Plate Changed (See OP Log)
CV-2603	9/17/2026 1:35:30 PM	1130	34.4283543	-118.6487698	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum
CV-2603	9/17/2026 1:37:32 PM	1123	34.4283613	-118.6487997	
CV-2605	9/30/2026 9:04:23 AM	1103	34.4275312	-118.6489412	Valve Adjustment:Barely Open

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2606	9/17/2026 1:17:22 PM	1143	34.4288927	-118.6484607	Valve Adjustment:Orifice Plate Changed (See OP Log)
CV-2606	9/17/2026 1:22:30 PM	1150	34.4289073	-118.6484578	Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum
CV-2606	9/17/2026 1:24:50 PM	1145	34.4289225	-118.6484590	
CV-2608	9/21/2026 9:33:42 AM	1146	34.4293738	-118.6480595	Valve Adjustment:NSPS/EG CAI,Increased Flow/Vacuum
CV-2608	9/21/2026 9:44:28 AM	1141	34.4293493	-118.6480658	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Orifice Plate Changed (See OP Log),Positive Static Press.,Increased Flow/Vacuum
CV-2610	9/9/2026 10:26:51 AM	1132	34.4298355	-118.6465565	Valve Adjustment:Increased Flow/Vacuum
CV-2610	9/9/2026 10:27:56 AM	1133	34.4298245	-118.6465593	
CV-2611	9/25/2026 8:33:59 AM	1154	34.4303475	-118.6459120	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Surging Liquid in Header
CV-2611	9/25/2026 8:35:07 AM	1163	34.4303600	-118.6459287	Valve Adjustment:NSPS/EG CAC
CV-2612	9/23/2026 10:24:54 AM	1258	34.4311688	-118.6470948	
CV-2613	9/23/2026 9:13:04 AM	1266	34.4306163	-118.6480082	Valve Adjustment:NSPS/EG CAI,Increased Flow/Vacuum
CV-2613	9/23/2026 9:20:54 AM	1265	34.4306058	-118.6479975	Valve Adjustment:NSPS/EG CAC,Orifice Plate Changed (See OP Log),Increased Flow/Vacuum
CV-2613	9/23/2026 9:28:02 AM	1270	34.4306265	-118.6480000	
CV-2613	9/23/2026 9:45:38 AM	1264	34.4306175	-118.6480067	
CV-2614	9/21/2026 12:45:34 PM	1267	34.4305132	-118.6484738	Valve Adjustment:NSPS/EG CAI,Orifice Plate Changed (See OP Log),Reconnected this Date,Positive Static Press.,Increased Flow/Vacuum
CV-2614	9/21/2026 12:51:30 PM	1269	34.4305338	-118.6484800	Valve Adjustment:NSPS/EG CAC,Orifice Plate Changed (See OP Log),Positive Static Press.,Increased Flow/Vacuum
CV-2614	9/21/2026 12:53:19 PM	1262	34.4305240	-118.6484760	
CV-2615	9/21/2026 12:14:18 PM	1300	34.4312343	-118.6492985	Valve Adjustment:Orifice Plate Changed (See OP Log),Reconnected this Date
CV-2615	9/21/2026 12:17:00 PM	1307	34.4312255	-118.6492823	Valve Adjustment:Decreased Flow/Vacuum
CV-2615	9/21/2026 12:18:55 PM	1312	34.4312255	-118.6492940	
CV-2627	9/11/2026 8:23:45 AM	1188	34.4310297	-118.6461986	Valve Adjustment:Increased Flow/Vacuum
CV-2634	9/4/2026 7:30:48 AM	1215	34.4313887	-118.6454587	Valve Adjustment:Increased Flow/Vacuum
CV-2634	9/11/2026 8:16:30 AM	1209	34.4313936	-118.6454759	Valve Adjustment:NSPS/EG CAI,High O2,Increased Flow/Vacuum,Valve 100% Open
CV-2634	9/23/2026 1:07:00 PM	1212	34.4313947	-118.6454755	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Valve 100% Open

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2634	9/24/2026 2:13:35 PM				[User entered 0.1%]
CV-2634	9/24/2026 2:14:26 PM	1205	34.4313813	-118.6454902	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-2634	9/24/2026 2:25:00 PM				AtmAA (24 TAT Request)
CV-2634	9/24/2026 2:25:00 PM				AtmAA (24 TAT Request) <0.10; [User entered 0.10%]
CV-2634	9/24/2026 2:58:48 PM				
CV-2634	9/24/2026 2:58:48 PM				
CV-2634	9/24/2026 2:58:48 PM				
CV-2638	9/27/2026 11:47:09 AM	1361	34.4363957	-118.6436468	Valve Adjustment:Orifice Plate Changed (See OP Log),Reconnected this Date,Surging Liquid in Well (Watered In);Well Comment:Wellhead remoted up slope
CV-2663	9/28/2026 1:50:21 PM	1323	34.4350605	-118.6433293	Valve Adjustment:Barely Open
CV-2676	9/1/2026 8:50:09 AM	1319	34.4336153	-118.6434693	Valve Adjustment:Barely Open
CV-2680	9/16/2026 11:27:44 AM	1288	34.4353972	-118.6421087	Valve Adjustment:NSPS/EG CAI,Orifice Plate Changed (See OP Log),High Temp,Decreased Flow/Vacuum,Barely Open;Well Comment:Changed OP from 0.75 to 0.50;Well Condition:Pnumatic Pump Installed
CV-2680	9/16/2026 11:30:13 AM	1282	34.4353872	-118.6421277	Valve Adjustment:NSPS/EG CAC
CV-2680	9/22/2026 2:55:28 PM	1257	34.4354220	-118.6420105	,
CV-2681	9/22/2026 3:00:45 PM	1253	34.4353228	-118.6426775	,
CV-2681	9/22/2026 3:01:29 PM	1289	34.4352577	-118.6426147	,
CV-2683	9/22/2026 3:21:53 PM	1332	34.4346575	-118.6423535	,
CV-2684	9/28/2026 2:31:31 PM	1256	34.4342220	-118.6422342	Valve Adjustment:Decreased Flow/Vacuum
CV-2687	9/9/2026 1:20:38 PM	1251	34.4335957	-118.6415808	
CV-2688	9/4/2026 8:25:47 AM	1217	34.4327100	-118.6424180	Valve Adjustment:Increased Flow/Vacuum
CV-2688	9/18/2026 3:17:08 PM	1229	34.4327417	-118.6423970	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum
CV-2689	9/28/2026 3:05:38 PM	1223	34.4328413	-118.6433908	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2689	9/30/2026 11:55:35 AM				[User entered 28.2%]
CV-2689	9/30/2026 11:59:55 AM	1218	34.4328272	-118.6433742	Valve Adjustment:Increased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-2689	9/30/2026 12:01:28 PM	1249	34.4328153	-118.6433878	
CV-2690	9/4/2026 8:32:48 AM	1257	34.4323567	-118.6428787	Valve Adjustment:Increased Flow/Vacuum
CV-2691	9/28/2026 7:44:15 AM	1214	34.4321097	-118.6431822	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-2692	9/4/2026 7:43:29 AM	1213	34.4316470	-118.6444830	Valve Adjustment:Increased Flow/Vacuum
CV-2692	9/18/2026 3:35:46 PM	1218	34.4316240	-118.6444675	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
CV-2695	9/16/2026 1:56:22 PM	1181	34.4288608	-118.6501575	Valve Adjustment:Increased Flow/Vacuum
CV-2695	9/16/2026 2:05:21 PM	1170	34.4288637	-118.6501745	Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum
CV-2695	9/16/2026 2:07:07 PM	1196	34.4288828	-118.6501817	
CV-48R	9/23/2026 8:32:14 AM	1307	34.4373335	-118.6458563	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-52D	9/22/2026 2:41:30 PM	1270	34.4359503	-118.6424648	,
CV-55R	9/2/2026 2:12:41 PM	1320	34.4343831	-118.6427878	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-55R	9/2/2026 2:15:00 PM				AtmAA
CV-55R	9/2/2026 2:15:00 PM				AtmAA; [User entered 16.9%]
CV-55R	9/10/2026 9:19:10 AM	1317	34.4343693	-118.6427642	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-55R	9/10/2026 9:21:00 AM				AtmAA
CV-55R	9/11/2026 9:33:09 AM	1302	34.4343857	-118.6427807	
CV-55R	9/17/2026 10:30:20 AM	1302	34.4343810	-118.6427784	Valve Adjustment:High O2;Well Condition:Lorentz Pump Installed
CV-55R	9/17/2026 10:33:00 AM				AtmAA
CV-55R	9/24/2026 2:26:06 PM	1322	34.4343653	-118.6427891	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-55R	9/24/2026 2:30:00 PM				AtmAA
CV-56D	9/1/2026 8:36:44 AM	1311	34.4337917	-118.6431812	Valve Adjustment:Decreased Flow/Vacuum
CV-56S	9/1/2026 8:31:46 AM	1320	34.4337888	-118.6431718	Valve Adjustment:Decreased Flow/Vacuum
CV-57R	9/1/2026 10:13:04 AM	1336	34.4343207	-118.6435575	Valve Adjustment:Barely Open
CV-79R	9/1/2026 9:35:58 AM	1336	34.4332422	-118.6448520	Valve Adjustment:Decreased Flow/Vacuum
CV-79R	9/1/2026 9:37:09 AM	1341	34.4332420	-118.6448542	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-94	9/22/2026 10:04:47 AM	1322	34.4348150	-118.6437323	,
CV-95	9/1/2026 10:09:59 AM	1344	34.4343058	-118.6436020	Valve Adjustment:Barely Open
CV-99	9/4/2026 7:05:00 AM				AirTech Lab
CV-99	9/4/2026 7:05:00 AM				AirTech Lab; [User entered 6.4%]
CV-99	9/14/2026 9:15:48 AM	1323	34.4370603	-118.6463192	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In)
CV-99	9/14/2026 9:19:46 AM	1304	34.4370568	-118.6463197	Valve Adjustment:NSPS/EG CAC
CV-99	9/25/2026 10:42:18 AM	1311	34.4370470	-118.6463417	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
D-02	9/25/2026 9:39:15 AM	1175	34.4311670	-118.6442888	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Header

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
D-02	9/28/2026 12:45:58 PM	1174	34.4311728	-118.6442900	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Reduce Sys. Vac. - Flare Down
D-02	9/28/2026 12:48:09 PM	1175	34.4311653	-118.6443002	Valve Adjustment:Valve 100% Open,Reduce Sys. Vac. - Flare Down
D-03	9/2/2026 10:11:51 AM	1164	34.4311717	-118.6442877	Valve Adjustment:NSPS/EG CAC
D-04	9/25/2026 9:43:51 AM	1173	34.4311817	-118.6442882	
D-09	9/25/2026 8:39:40 AM	1147	34.4301047	-118.6463198	Valve Adjustment:Increased Flow/Vacuum
D-10	9/2/2026 10:47:58 AM	1144	34.4302038	-118.6458290	Valve Adjustment:Audible Flow
FP-001	9/9/2026 11:56:26 AM	1348	34.4365950	-118.6458458	
FP-002	9/9/2026 11:59:58 AM	1343	34.4366248	-118.6462108	
FP-003	9/9/2026 12:04:20 PM	1348	34.4366082	-118.6465073	
FP-005	9/25/2026 10:01:13 AM	1354	34.4364653	-118.6472745	
FP-006	9/9/2026 10:42:38 AM	1360	34.4363740	-118.6476428	
FP-008	9/9/2026 10:51:01 AM	1351	34.4363288	-118.6481510	
FP-009	9/9/2026 10:56:29 AM	1363	34.4366898	-118.6489068	Valve Adjustment:Barely Open
FP-010	9/9/2026 11:00:51 AM	1370	34.4366332	-118.6492395	Valve Adjustment:Barely Open
FP-011	9/9/2026 11:03:30 AM	1360	34.4365443	-118.6494752	Valve Adjustment:Barely Open
FP-012	9/1/2026 11:45:24 AM	1375	34.4366542	-118.6498983	
FP-013	9/1/2026 11:33:24 AM	1376	34.4365747	-118.6502460	
FP-014	9/25/2026 10:20:20 AM	1358	34.4364813	-118.6482293	Valve Adjustment:Barely Open
FP-015	9/9/2026 10:36:14 AM	1358	34.4363940	-118.6479208	Valve Adjustment:Barely Open
FP-016	9/9/2026 10:39:37 AM	1350	34.4364775	-118.6476588	
FP-017	9/14/2026 11:00:20 AM	1339	34.4343250	-118.6486857	Increased Flow/Vacuum,
FP-018	9/1/2026 2:40:24 PM	1324	34.4344613	-118.6491045	
FP-019	9/1/2026 2:44:17 PM	1332	34.4346722	-118.6491785	
FP-020	9/14/2026 11:24:45 AM	1309	34.4350263	-118.6491820	,
FP-021	9/14/2026 11:16:23 AM	1345	34.4352887	-118.6491603	,
FP-022	9/14/2026 11:21:00 AM	1362	34.4352097	-118.6491552	,
FP-023	9/3/2026 8:54:48 AM	1346	34.4359968	-118.6496160	
FP-024	9/9/2026 11:18:04 AM	1337	34.4355083	-118.6477695	
FP-025	9/14/2026 10:07:38 AM	1388	34.4353428	-118.6477610	,
FP-026	9/14/2026 10:10:15 AM	1348	34.4350197	-118.6480687	,
FP-027	9/14/2026 10:53:07 AM	1283	34.4349642	-118.6480655	,
FP-027	9/14/2026 2:20:08 PM	1364	34.4348765	-118.6482155	Valve Comment:Riser modified to adapt the well head
FP-027	9/15/2026 10:17:45 AM	1357	34.4348620	-118.6482127	
FP-028	9/14/2026 10:55:24 AM	1319	34.4346473	-118.6483827	,
FP-028	9/15/2026 10:30:36 AM	1357	34.4346723	-118.6482621	Valve Adjustment:NSPS/EG CAI,Reconnected this Date,Decreased Flow/Vacuum
FP-028	9/15/2026 10:31:51 AM	1357	34.4346753	-118.6482583	Valve Adjustment:NSPS/EG CAC
FP-029	9/14/2026 11:04:54 AM	1345	34.4342698	-118.6489275	,

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
FP-029	9/15/2026 10:38:34 AM	1361	34.4345653	-118.6482952	Valve Adjustment:NSPS/EG CAI,Reconnected this Date,Decreased Flow/Vacuum
FP-030	9/1/2026 2:31:04 PM	1336	34.4345195	-118.6497283	
FP-031	9/1/2026 2:28:03 PM	1341	34.4348335	-118.6497830	
FP-031	9/15/2026 10:39:37 AM	1361	34.4345654	-118.6482961	Valve Adjustment:NSPS/EG CAC
FP-032	9/1/2026 2:20:55 PM	1340	34.4350925	-118.6498458	Valve Adjustment:Decreased Flow/Vacuum
FP-033	9/1/2026 2:17:52 PM	1355	34.4353645	-118.6499232	
FP-034	9/1/2026 2:13:58 PM	1352	34.4356143	-118.6500065	Valve Adjustment:Barely Open
FP-035	9/1/2026 1:47:39 PM	1347	34.4358578	-118.6501190	Valve Adjustment:Barely Open
FP-036	9/14/2026 9:56:48 AM	1366	34.4361263	-118.6502075	
FP-037	9/1/2026 1:35:51 PM	1362	34.4362712	-118.6502867	
FP-038	9/14/2026 1:57:24 PM	1339	34.4341347	-118.6497993	,
FP-038	9/23/2026 10:03:41 AM	1284	34.4348375	-118.6509298	
FP-039	9/14/2026 1:59:50 PM	1312	34.4341353	-118.6498533	,
FP-040	9/23/2026 10:00:51 AM	1307	34.4352800	-118.6510477	
FP-041	9/2/2026 7:45:38 AM	1273	34.4340772	-118.6507097	Reduced System Vacuum,
FP-042	9/2/2026 8:11:34 AM	1230	34.4333060	-118.6512125	Reduced System Vacuum,
FP-043	9/2/2026 7:48:43 AM	1247	34.4342878	-118.6507950	Reduced System Vacuum,
FP-044	9/2/2026 7:51:27 AM	1250	34.4346070	-118.6508722	Reduced System Vacuum,
FP-045	9/2/2026 1:12:15 PM	1321	34.4334673	-118.6496613	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
FP-046	9/25/2026 10:05:05 AM	1353	34.4365698	-118.6473025	
FP-047	9/29/2026 8:20:44 AM	1351	34.4367228	-118.6469347	
FP-050	9/2/2026 2:22:59 PM	1362	34.4349092	-118.6472822	
FP-051	9/2/2026 2:17:15 PM	1372	34.4345688	-118.6473497	
FP-052	9/2/2026 1:33:27 PM	1321	34.4342273	-118.6481287	Valve Adjustment:Barely Open
FP-053	9/2/2026 1:27:21 PM	1372	34.4340435	-118.6477683	
FP-054	9/1/2026 9:06:16 AM	1397	34.4349500	-118.6458056	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
FP-054	9/2/2026 2:06:03 PM	1370	34.4343572	-118.6471028	
FP-055	9/28/2026 10:39:01 AM	1365	34.4336285	-118.6481653	
FP-056	9/2/2026 9:03:40 AM	1359	34.4334652	-118.6486602	
FP-057	9/3/2026 12:59:26 PM	1382	34.4347557	-118.6455632	
FP-058	9/3/2026 12:56:21 PM	1403	34.4349677	-118.6458427	Valve Adjustment:Barely Open
FP-059	9/14/2026 1:04:23 PM	1322	34.4346710	-118.6459353	,
FP-060	9/28/2026 10:03:13 AM	1366	34.4348340	-118.6461072	
FP-061	9/9/2026 10:33:21 AM	1354	34.4364122	-118.6479115	
FP-062	9/10/2026 12:04:52 PM	1287	34.4349482	-118.6512123	
FP-063	9/10/2026 12:09:15 PM	1290	34.4349755	-118.6511665	
FP-064	9/14/2026 12:54:05 PM	1368	34.4352088	-118.6442336	Valve Adjustment:NSPS/EG CAI,Reconnected this Date,Positive Static Press.,Increased Flow/Vacuum,Barely Open
FP-064	9/14/2026 12:58:32 PM	1376	34.4351995	-118.6442335	Valve Adjustment:NSPS/EG CAC

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
FP-064	9/15/2026 9:47:50 AM	1386	34.4351913	-118.6442349	
FP-065	9/14/2026 1:10:28 PM	1383	34.4354977	-118.6441162	Valve Adjustment:NSPS/EG CAI,Reconnected this Date,Increased Flow/Vacuum,Barely Open
FP-065	9/15/2026 9:51:40 AM	1384	34.4354990	-118.6441080	
FP-066	9/14/2026 1:20:35 PM	1345	34.4357498	-118.6441913	,
FP-066	9/15/2026 9:55:34 AM	1386	34.4357176	-118.6442139	
H-01 (EXP-01	9/3/2026 12:08:43 PM	1241	34.4376952	-118.6441568	Valve Adjustment:Barely Open
H-01 (EXP-01	9/30/2026 2:26:54 PM	1236	34.4377082	-118.6441205	Valve Adjustment:Reduce Sys. Vac. - Flare Down
H-02 (EXP-02	9/3/2026 12:33:02 PM	1239	34.4376965	-118.6446027	Valve Adjustment:Surging Liquid in Header
H-02 (EXP-02	9/30/2026 2:29:31 PM	1232	34.4376975	-118.6445695	Valve Adjustment:Reduce Sys. Vac. - Flare Down
H-03 (EXP-03	9/3/2026 12:29:22 PM	1249	34.4377235	-118.6446417	Valve Adjustment:Decreased Flow/Vacuum
H-03 (EXP-03	9/30/2026 2:35:08 PM	1240	34.4377113	-118.6446432	Valve Adjustment:Reduce Sys. Vac. - Flare Down
H-04 (EXP-04	9/3/2026 12:23:09 PM	1256	34.4377615	-118.6447062	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
H-04 (EXP-04	9/3/2026 12:24:20 PM	1259	34.4377445	-118.6447087	
H-04 (EXP-04	9/30/2026 2:38:36 PM	1249	34.4377160	-118.6447213	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp,Positive Static Press.,Increased Flow/Vacuum
H-04 (EXP-04	9/30/2026 2:40:29 PM	1237	34.4377133	-118.6446953	Valve Adjustment:NSPS/EG CAI,High Temp,Reduce Sys. Vac. - Flare Down
H-08 (EXP-08	9/14/2026 8:50:48 AM	1259	34.4378665	-118.6465762	Valve Adjustment:Audible Flow
H-08 (EXP-08	9/29/2026 8:40:38 AM	1278	34.4378133	-118.6465330	Valve Adjustment:Increased Flow/Vacuum
H-08 (EXP-08	9/29/2026 8:42:05 AM	1283	34.4378187	-118.6465455	
H-10 (EXP-10	9/15/2026 8:07:00 AM	1307	34.4374417	-118.6471038	Valve Adjustment:NSPS/EG CAI,High Temp
H-10 (EXP-10	9/15/2026 8:11:28 AM	1322	34.4374557	-118.6470822	Valve Adjustment:High Temp
H-10 (EXP-10	9/29/2026 8:30:20 AM	1312	34.4374495	-118.6471103	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp,Decreased Flow/Vacuum
H-10 (EXP-10	9/29/2026 8:32:34 AM	1312	34.4374272	-118.6470828	
H-1404C	9/15/2026 9:34:05 AM	1357	34.4324138	-118.6483060	Valve Adjustment:NSPS/EG CAI,High Temp
H-1404C	9/15/2026 9:38:51 AM	1354	34.4323960	-118.6483453	Valve Adjustment:High Temp
H-1404C	9/16/2026 10:35:00 AM				AtmAA
H-1404C	9/16/2026 12:54:05 PM	1340	34.4324263	-118.6483047	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
H-1404C	9/16/2026 1:34:20 PM	1357	34.4324153	-118.6482913	Valve Adjustment:NSPS/EG CAC,Orifice Plate Changed (See OP Log),High Temp,Decreased Flow/Vacuum
H-1404C	9/16/2026 1:40:19 PM	1348	34.4324238	-118.6482973	
H-1405C	9/1/2026 9:32:25 AM	1224	34.4326442	-118.6498927	,
H-1405C	9/22/2026 11:58:24 AM	1345	34.4325665	-118.6496640	NSPS/EG CAI,

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
H-1405C	9/22/2026 11:59:05 AM	1316	34.4325772	-118.6496620	NSPS/EG CAI,High O2
H-1406W	9/2/2026 8:36:20 AM	1227	34.4321592	-118.6507752	Reduced System Vacuum,
H-1406W	9/4/2026 1:49:40 PM	1263	34.4321802	-118.6508002	Valve Adjustment:Increased Flow/Vacuum
H-1406W	9/10/2026 10:32:49 AM	1244	34.4321732	-118.6507816	Valve Adjustment:Increased Flow/Vacuum
H-1406W	9/23/2026 8:53:49 AM	1260	34.4321605	-118.6507730	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
H-1408CR	9/23/2026 12:53:30 PM	1326	34.4315698	-118.6475928	Valve Adjustment:Increased Flow/Vacuum,Barely Open
H-1408E	9/14/2026 2:12:45 PM	1394	34.4333870	-118.6471932	Valve Adjustment:Barely Open
H-1408E	9/21/2026 10:04:50 AM	1381	34.4333585	-118.6471537	Valve Adjustment:Increased Flow/Vacuum
H-1408W	9/2/2026 9:01:18 AM	1220	34.4311535	-118.6499650	,
H-1409N	9/1/2026 2:27:54 PM	1325	34.4324990	-118.6472582	,
H-1409N	9/21/2026 9:11:22 AM	1354	34.4328685	-118.6469350	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1410S	9/25/2026 9:05:52 AM	1220	34.4310030	-118.6466878	
H-1563N	9/14/2026 2:12:22 PM	1332	34.4338745	-118.6498027	,
H-1563N	9/17/2026 10:33:10 AM	1322	34.4338623	-118.6497998	Valve Adjustment:Decreased Flow/Vacuum
H-1563S	9/1/2026 9:35:22 AM	1270	34.4323257	-118.6496260	,
H-1563S	9/22/2026 12:03:36 PM	1286	34.4323790	-118.6495912	,
H-1565E	9/14/2026 2:16:08 PM	1408	34.4335807	-118.6472417	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1565E	9/21/2026 10:11:59 AM	1380	34.4335487	-118.6472173	Valve Adjustment:Barely Open
H-1568N	9/14/2026 2:10:12 PM	1387	34.4333623	-118.6471542	Valve Adjustment:Barely Open
H-1568N	9/21/2026 9:57:33 AM	1381	34.4333530	-118.6471417	Valve Adjustment:Barely Open
H-1571S	9/24/2026 10:55:12 AM	1285	34.4321542	-118.6452327	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1572N	9/22/2026 10:24:00 AM	1362	34.4338670	-118.6447982	,
H-1572S	9/24/2026 10:40:13 AM	1275	34.4321608	-118.6447210	Valve Adjustment:Barely Open
H-1753N	9/1/2026 2:48:08 PM	1338	34.4347308	-118.6493502	
H-1753N	9/24/2026 11:34:35 AM	1346	34.4347177	-118.6493162	Valve Adjustment:NSPS/EG CAI,Orifice Plate Changed (See OP Log),High O2,Decreased Flow/Vacuum;Well Comment:Changed OP from 1.25 to 0.40
H-1753N	9/24/2026 11:36:18 AM	1341	34.4347147	-118.6493143	Valve Adjustment:NSPS/EG CAC
H-1753S	9/14/2026 1:54:43 PM	1332	34.4339740	-118.6496573	,
H-1753S	9/17/2026 10:36:17 AM	1336	34.4339248	-118.6495635	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
H-1756S	9/2/2026 7:25:00 AM	1289	34.4324973	-118.6502938	Reduced System Vacuum,

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
H-1756S	9/22/2026 11:27:30 AM	1293	34.4325735	-118.6502503	,
H-1757S	9/1/2026 9:27:22 AM	1348	34.4327692	-118.6497163	,
H-1757S	9/22/2026 11:41:50 AM	1253	34.4327528	-118.6497990	,
H-1760S	9/14/2026 1:52:17 PM	1384	34.4327338	-118.6479463	
H-1760S	9/21/2026 9:25:24 AM	1357	34.4327312	-118.6478820	Valve Adjustment:Surging Liquid in Header
H-1762N	9/13/2026 1:22:53 PM	1381	34.4334488	-118.6468737	Valve Adjustment:Increased Flow/Vacuum;Well Repairs:Flex Hose
H-1762N	9/13/2026 1:24:07 PM	1385	34.4334498	-118.6468985	
H-1762N	9/21/2026 8:20:33 AM	1393	34.4334683	-118.6468832	Valve Adjustment:Surging Liquid in Header
H-1763N	9/14/2026 1:09:46 PM	1400	34.4335408	-118.6462090	Valve Adjustment:Barely Open
H-1763N	9/24/2026 2:03:05 PM	1385	34.4335343	-118.6461888	Valve Adjustment:Barely Open
H-1763S	9/9/2026 1:49:39 PM	1322	34.4323707	-118.6462738	,
H-1764N	9/9/2026 1:21:26 PM	1339	34.4331267	-118.6455518	,
H-1764S	9/24/2026 11:03:44 AM	1302	34.4321818	-118.6454058	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
H-1767N	9/28/2026 3:02:56 PM	1233	34.4326733	-118.6436082	Valve Adjustment:Barely Open
H-1769N	9/1/2026 11:12:33 AM	1358	34.4370417	-118.6494878	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
H-1769N	9/16/2026 12:33:55 PM	1377	34.4370138	-118.6494922	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Surging Liquid in Well (Watered In)
H-1769N	9/16/2026 12:34:48 PM	1378	34.4370137	-118.6494940	
H-1770N	9/1/2026 11:22:05 AM	1357	34.4368300	-118.6500212	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
H-1770N	9/10/2026 9:10:00 AM				AirTech Lab
H-1770N	9/10/2026 9:10:00 AM				AirTech Lab; [User entered 2.3%]
H-1770N	9/16/2026 2:50:15 PM	1330	34.4367707	-118.6500187	Valve Adjustment:Barely Open
H-1770S	9/1/2026 9:20:12 AM	1283	34.4331502	-118.6501687	,
H-1770S	9/24/2026 2:40:13 PM	1307	34.4331515	-118.6501883	Valve Adjustment:Barely Open
H-1771A	9/10/2026 1:09:59 PM	1368	34.4363303	-118.6464000	Valve Adjustment:Barely Open
H-1771B	9/3/2026 8:52:45 AM	1380	34.4355145	-118.6466442	Valve Adjustment:Barely Open
H-1771B	9/22/2026 10:31:17 AM	1389	34.4355065	-118.6466522	Valve Adjustment:Barely Open
H-1774N	9/10/2026 8:58:19 AM	1356	34.4367360	-118.6508087	Valve Adjustment:Decreased Flow/Vacuum
H-1774N	9/16/2026 2:40:28 PM	1292	34.4366750	-118.6507832	Valve Adjustment:Barely Open
H-1801S	9/1/2026 9:53:29 AM	1334	34.4337665	-118.6440815	Valve Adjustment:High O2,Barely Open
H-1801S	9/1/2026 9:53:57 AM	1334	34.4337655	-118.6440868	Valve Adjustment:High O2,Barely Open
H-1802S	9/22/2026 10:27:44 AM	1358	34.4334885	-118.6447217	,
H-1803N-PLF	9/8/2026 10:07:00 AM				AtmAA
H-1803N-PLF	9/8/2026 10:10:29 AM	1351	34.4370384	-118.6485862	Valve Adjustment:No Flow Measurement,High Temp
H-1803N-PLF	9/14/2026 9:29:28 AM	1339	34.4370404	-118.6486030	Valve Adjustment:No Flow Measurement,High Temp
H-1803N-PLF	9/14/2026 9:32:00 AM				AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
H-1803N-PLF	9/21/2026 9:40:35 AM	1346	34.4370364	-118.6486014	Valve Adjustment:No Flow Measurement,High Temp
H-1803N-PLF	9/21/2026 9:41:00 AM				AtmAA
H-1803N-PLF	9/28/2026 9:10:00 AM				AtmAA
H-1803N-PLF	9/28/2026 9:16:43 AM				Valve Adjustment:No Flow Measurement,High Temp
H-1804B	9/14/2026 1:13:24 PM	1306	34.4342583	-118.6457412	,
H-1804N	9/25/2026 2:27:02 PM	1344	34.4363942	-118.6457030	Valve Adjustment:Barely Open
H-1804S	9/9/2026 1:23:01 PM	1325	34.4331813	-118.6457637	,
H-1805A	9/3/2026 1:50:46 PM	1389	34.4351325	-118.6450940	Valve Adjustment:Barely Open
H-1805B	9/9/2026 1:05:06 PM	1355	34.4337667	-118.6451923	,
H-1805S	9/9/2026 1:38:46 PM	1335	34.4328877	-118.6451552	NSPS/EG CAI,High Temp
H-1805S	9/9/2026 1:39:27 PM	1358	34.4328317	-118.6450868	NSPS/EG CAC,
H-1806A	9/3/2026 1:23:27 PM	1384	34.4354598	-118.6442113	Valve Adjustment:Barely Open
H-1806B	9/22/2026 10:17:41 AM	1368	34.4338525	-118.6444215	,
H-1806B	9/22/2026 10:19:58 AM	1339	34.4339752	-118.6444817	,
H-1806N	9/10/2026 1:30:41 PM	1356	34.4363658	-118.6443012	Valve Adjustment:Barely Open
H-1806S	9/1/2026 9:12:20 AM	1285	34.4328808	-118.6444572	Valve Adjustment:Barely Open
H-1807A	9/22/2026 10:02:24 AM	1309	34.4352938	-118.6436250	,
H-1807N	9/4/2026 9:28:29 AM	1350	34.4364542	-118.6435158	Valve Adjustment:Increased Flow/Vacuum
H-1807N	9/10/2026 1:36:04 PM	1352	34.4364475	-118.6435195	Valve Adjustment:Barely Open
H-1807S	9/1/2026 10:29:44 AM	1297	34.4338257	-118.6434557	
H-1952S	9/2/2026 1:24:38 PM	1358	34.4338043	-118.6476345	Valve Adjustment:Barely Open
H-1952S	9/17/2026 2:50:32 PM	1329	34.4337640	-118.6476647	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1955C	9/3/2026 1:54:00 PM	1380	34.4350433	-118.6454357	Valve Adjustment:Barely Open
H-1955N	9/10/2026 1:18:23 PM	1346	34.4364757	-118.6455270	Valve Adjustment:Barely Open
H-1956B	9/9/2026 12:56:13 PM	1430	34.4342482	-118.6447508	NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
H-1956B	9/9/2026 12:57:13 PM	1365	34.4342145	-118.6447100	NSPS/EG CAC,
H-1956N	9/10/2026 1:26:20 PM	1320	34.4364623	-118.6448830	
H-1956S	9/1/2026 9:27:26 AM	1335	34.4331990	-118.6448652	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
H-1957B	9/3/2026 1:15:00 PM	1377	34.4345480	-118.6441168	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1957N	9/10/2026 1:33:26 PM	1342	34.4364512	-118.6441942	Valve Adjustment:Barely Open
H-1957S	9/30/2026 9:45:11 AM	1327	34.4337623	-118.6441242	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down
H-1957S	9/30/2026 9:54:00 AM	1327	34.4337590	-118.6441348	Valve Adjustment:Barely Open,Reduce Sys. Vac. - Flare Down

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
H-1957S	9/30/2026 2:08:10 PM	1326	34.4337655	-118.6441103	Valve Adjustment:Barely Open
H-1958C	9/22/2026 9:58:48 AM	1375	34.4352407	-118.6434030	,
H-1958N	9/10/2026 1:37:51 PM	1354	34.4364260	-118.6434973	Valve Adjustment:Barely Open
H-1958S	9/1/2026 10:27:20 AM	1301	34.4340163	-118.6433158	Valve Adjustment:High O2,Barely Open
H-1962N	9/1/2026 11:28:27 AM	1361	34.4366952	-118.6501143	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
H-1962N	9/1/2026 11:29:39 AM	1371	34.4366880	-118.6501150	
H-1962N	9/16/2026 2:56:18 PM	1349	34.4366487	-118.6501228	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
H-1962N	9/16/2026 2:56:46 PM	1349	34.4366513	-118.6501238	Valve Adjustment:High Temp
H-1963N	9/1/2026 10:58:20 AM	1371	34.4369235	-118.6495610	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
H-1963N	9/1/2026 10:59:34 AM	1371	34.4369235	-118.6495435	
H-1963N	9/16/2026 12:20:55 PM	1373	34.4369177	-118.6495743	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
H-1963N	9/16/2026 12:21:46 PM	1372	34.4369202	-118.6495612	
H-1966N	9/10/2026 9:06:20 AM	1349	34.4365540	-118.6508080	Valve Adjustment:Audible Flow
H-1966N	9/16/2026 2:32:58 PM	1305	34.4365103	-118.6507695	Valve Adjustment:Barely Open
H-1967E	9/2/2026 10:44:57 AM	1144	34.4302150	-118.6458270	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
H-1967W	9/2/2026 1:39:12 PM	1194	34.4300793	-118.6509698	,
H-2050E	9/30/2026 9:51:30 AM	1095	34.4291283	-118.6475085	Valve Adjustment:Barely Open
H-2050W	9/21/2026 2:03:14 PM	1184	34.4291275	-118.6491238	
H-2050W	9/21/2026 2:07:51 PM	1182	34.4291217	-118.6491375	Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum
H-2050W	9/21/2026 2:09:57 PM	1194	34.4291248	-118.6491200	
H-2051W	9/2/2026 1:36:38 PM	1201	34.4298638	-118.6508128	,
H-2053E	9/2/2026 10:36:42 AM	1142	34.4302028	-118.6458253	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
H-2055E	9/15/2026 10:19:32 AM	1282	34.4317688	-118.6465997	Valve Adjustment:Barely Open
H-2055E	9/24/2026 1:41:22 PM				[User entered 2.8%]
H-2055E	9/24/2026 1:42:43 PM	1283	34.4317447	-118.6466117	Valve Adjustment:Reduce Sys. Vac. - Flare Down
H-2055E	9/24/2026 1:45:00 PM				AtmAA (24 TAT Request)
H-2055E	9/24/2026 1:45:00 PM				AtmAA (24 TAT Request); [User entered 0.33%]
H-2055E	9/24/2026 2:52:19 PM				
H-2055E	9/28/2026 8:24:51 AM	1289	34.4317570	-118.6466127	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Increased Flow/Vacuum
H-2055E	9/28/2026 8:27:27 AM	1269	34.4317760	-118.6466288	
H-2056B	9/30/2026 10:41:17 AM	1145	34.4297317	-118.6474723	Valve Adjustment:Barely Open
H-2056W	9/2/2026 1:33:36 PM	1122	34.4299845	-118.6507983	Increased Flow/Vacuum,
H-2057E	9/2/2026 10:33:09 AM	1151	34.4302000	-118.6458073	Valve Adjustment:Audible Flow,Surging Liquid in Header
H-2058E	9/25/2026 8:43:12 AM	1144	34.4300565	-118.6464293	Valve Adjustment:Increased Flow/Vacuum
H-2058W	9/2/2026 1:31:18 PM	1237	34.4299820	-118.6506997	Increased Flow/Vacuum,

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
H-2059E	9/25/2026 8:48:49 AM	1180	34.4306673	-118.6462665	Valve Adjustment:Increased Flow/Vacuum
H-2059W	9/2/2026 1:18:59 PM	1211	34.4311237	-118.6503147	Increased Flow/Vacuum,
H-2161E	9/30/2026 4:18:18 PM	1189	34.4308518	-118.6464575	
H-2161W	9/2/2026 1:15:54 PM	1207	34.4310272	-118.6501297	Increased Flow/Vacuum,
H-2163C	9/15/2026 10:57:08 AM	1320	34.4310977	-118.6486693	Valve Adjustment:Audible Flow
H-2163C	9/21/2026 11:35:30 AM	1322	34.4310947	-118.6486623	Valve Adjustment:Audible Flow
H-2163W	9/2/2026 9:04:51 AM	1220	34.4311025	-118.6498775	NSPS/EG CAI,High O2
H-2163W	9/2/2026 9:05:57 AM	1266	34.4311833	-118.6498500	NSPS/EG CAC,
H-2163W	9/22/2026 12:25:17 PM	1276	34.4312177	-118.6499042	,
H-2164E	9/16/2026 3:11:14 PM	1271	34.4318938	-118.6460627	
H-2164E	9/24/2026 1:20:04 PM				[User entered 0.6%]
H-2164E	9/24/2026 1:23:09 PM	1268	34.4318975	-118.6460642	Valve Adjustment:Reduce Sys. Vac. - Flare Down
H-2164E	9/24/2026 1:25:00 PM				AtmAA (24 TAT Request)
H-2164E	9/24/2026 1:25:00 PM				AtmAA (24 TAT Request); [User entered 0.13%]
H-2164E	9/24/2026 3:05:04 PM				
H-2165E	9/25/2026 9:23:57 AM	1251	34.4319015	-118.6451075	Valve Adjustment:Decreased Flow/Vacuum
H-2165W	9/2/2026 8:43:14 AM	1112	34.4322225	-118.6505600	Reduced System Vacuum,
H-2165W	9/2/2026 8:45:08 AM	1309	34.4320863	-118.6504058	NSPS/EG CAI,High Temp,Reduced System Vacuum
H-2165W	9/9/2026 7:00:00 AM				AirTech Lab
H-2165W	9/9/2026 7:00:00 AM				AirTech Lab; [User entered 5.1%]
H-2165W	9/23/2026 8:49:44 AM	1275	34.4321350	-118.6504333	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-2165W	9/30/2026 10:38:31 AM	1274	34.4321374	-118.6504127	Valve Adjustment:High Temp,Increased Flow/Vacuum
H-2165W	9/30/2026 10:39:18 AM	1276	34.4321404	-118.6504166	Valve Adjustment:High Temp
H-2165W	9/30/2026 11:35:00 AM				AtmAA
H-2166E	9/22/2026 10:33:01 AM	1348	34.4355840	-118.6438355	,
H-2168C	9/1/2026 12:08:00 PM	1386	34.4344342	-118.6448075	Valve Adjustment:Audible Flow,Surging Liquid in Header
H-2168E	9/22/2026 10:07:45 AM	1381	34.4345267	-118.6438742	,
H-2169C	9/9/2026 1:00:48 PM	1398	34.4340938	-118.6451000	,
H-2169E	9/22/2026 9:11:45 AM	1370	34.4342221	-118.6442052	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Barely Open
H-2169E	9/22/2026 9:12:40 AM	1374	34.4342334	-118.6442060	Valve Adjustment:NSPS/EG CAC,Barely Open
H-2169E	9/22/2026 10:14:12 AM	1385	34.4341422	-118.6442120	,
H-2170N	9/25/2026 11:43:20 AM	1265	34.4357882	-118.6414450	Valve Adjustment:Decreased Flow/Vacuum
H-2170S	9/21/2026 12:50:35 PM	1240	34.4335887	-118.6414913	
H-2171A	9/29/2026 10:23:57 AM	1256	34.4374322	-118.6425240	
H-2171B	9/21/2026 9:19:40 AM	1259	34.4365148	-118.6416428	

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
H-2171N	9/29/2026 10:44:58 AM	1252	34.4379790	-118.6432537	
H-2171S	9/25/2026 11:49:39 AM	1275	34.4357843	-118.6414638	Valve Adjustment:Decreased Flow/Vacuum
H-2272W	9/2/2026 9:18:52 AM	1283	34.4318203	-118.6497095	,
H-2272W	9/22/2026 12:19:10 PM	1247	34.4317167	-118.6497675	,
H-2273W	9/2/2026 7:21:33 AM	1309	34.4322882	-118.6499358	Reduced System Vacuum,
H-2273W	9/4/2026 8:32:00 AM				AirTech Lab
H-2273W	9/4/2026 8:32:00 AM				AirTech Lab; [User entered 1.8%]
H-2273W	9/9/2026 7:10:00 AM				AirTech Lab
H-2273W	9/9/2026 7:10:00 AM				AirTech Lab; [User entered 1.0%]
H-2273W	9/22/2026 12:09:18 PM	1270	34.4321787	-118.6498992	,
H-2274B	9/1/2026 2:15:59 PM	1365	34.4325842	-118.6470083	Increased Flow/Vacuum,
H-2274B	9/22/2026 2:38:09 PM	1352	34.4326725	-118.6469342	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-2274W	9/2/2026 7:28:33 AM	1312	34.4327643	-118.6504502	Reduced System Vacuum,
H-2274W	9/22/2026 11:23:46 AM	1335	34.4327530	-118.6503850	,
H-2275E	9/9/2026 1:51:36 PM	1312	34.4324457	-118.6463502	,
H-2275W	9/1/2026 11:38:16 AM	1257	34.4321895	-118.6494103	NSPS/EG CAI,High O2
H-2275W	9/1/2026 11:39:55 AM	1266	34.4321568	-118.6493250	NSPS/EG CAC,
H-2275W	9/1/2026 11:41:12 AM	1312	34.4321390	-118.6493208	,
H-2275W	9/22/2026 12:53:21 PM	1306	34.4322370	-118.6493817	NSPS/EG CAI,High Temp
H-2275W	9/22/2026 12:53:59 PM	1306	34.4323017	-118.6493957	NSPS/EG CAC,
H-2276A	9/14/2026 1:55:11 PM	1376	34.4328953	-118.6483110	
H-2276A	9/21/2026 9:31:10 AM	1358	34.4328922	-118.6482798	Valve Adjustment:Surging Liquid in Header
H-2276B	9/1/2026 2:23:18 PM	1335	34.4329073	-118.6469532	,
H-2276B	9/21/2026 9:13:01 AM	1371	34.4329035	-118.6469237	Valve Adjustment:Surging Liquid in Header
H-2276E	9/9/2026 1:36:12 PM	1329	34.4328458	-118.6454408	,
H-2276W	9/1/2026 9:23:11 AM	1293	34.4326493	-118.6499660	,
H-2276W	9/22/2026 11:39:01 AM	1266	34.4326307	-118.6499450	,
H-2277A	9/1/2026 10:22:08 AM	1358	34.4330067	-118.6487560	,
H-2277A	9/17/2026 10:03:32 AM	1344	34.4330428	-118.6487440	Valve Adjustment:Barely Open
H-2277B	9/14/2026 1:34:55 PM	1392	34.4330985	-118.6469388	Valve Adjustment:Decreased Flow/Vacuum
H-2277B	9/21/2026 8:52:57 AM	1378	34.4330735	-118.6469053	Valve Adjustment:Increased Flow/Vacuum
H-23 (EXP-23	9/21/2026 8:51:57 AM	1262	34.4370247	-118.6420965	
H-2301E	9/24/2026 1:01:31 PM	1007	34.4270662	-118.6479868	
H-2301N	9/16/2026 7:52:01 AM	1199	34.4296310	-118.6512658	
H-2301N	9/23/2026 1:05:15 PM	1197	34.4296325	-118.6512267	
H-2301W	9/28/2026 2:15:49 PM	1127	34.4274735	-118.6506552	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Plugged/Pinched Suspected
H-2301W	9/28/2026 2:16:39 PM	1118	34.4274762	-118.6506483	Valve Adjustment:High O2,Plugged/Pinched Suspected

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
H-2302C	9/17/2026 1:44:50 PM	1123	34.4283940	-118.6490058	Valve Adjustment:Increased Flow/Vacuum
H-2302C	9/17/2026 1:47:40 PM	1133	34.4283882	-118.6490128	
H-2302E	9/24/2026 1:21:07 PM	1057	34.4275162	-118.6472432	
H-2303E	9/24/2026 1:28:29 PM	1071	34.4279082	-118.6471928	Valve Adjustment:Valve 100% Open
H-2303N	9/21/2026 1:25:13 PM	1132	34.4290423	-118.6484448	
H-2303N	9/21/2026 1:31:23 PM	1139	34.4290435	-118.6484375	Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum
H-2303N	9/21/2026 1:36:02 PM	1140	34.4290385	-118.6484447	Valve Adjustment:Increased Flow/Vacuum
H-2303N	9/21/2026 1:42:20 PM	1140	34.4290545	-118.6484497	Valve Adjustment:Orifice Plate Changed (See OP Log)
H-2303N	9/21/2026 1:46:07 PM	1142	34.4290322	-118.6484323	Valve Adjustment:Orifice Plate Changed (See OP Log)
H-2303S	9/30/2026 9:07:20 AM	1123	34.4272932	-118.6495713	Valve Adjustment:Barely Open
H-2303S	9/30/2026 3:11:43 PM	1125	34.4272693	-118.6495643	
H-2304E	9/24/2026 1:38:49 PM	1088	34.4282307	-118.6468948	
H-2304S	9/30/2026 8:57:47 AM	1090	34.4274785	-118.6489233	Valve Adjustment:Barely Open
H-2305N	9/21/2026 1:56:13 PM	1155	34.4289977	-118.6486237	
H-2305S	9/30/2026 8:54:12 AM	1064	34.4274495	-118.6485145	Valve Adjustment:Barely Open
H-2306N	9/30/2026 10:03:45 AM	1121	34.4294033	-118.6475793	Valve Adjustment:Barely Open
H-2307S	9/28/2026 9:57:33 AM	1147	34.4284633	-118.6498320	Valve Adjustment:Increased Flow/Vacuum
H-2307S	9/28/2026 9:59:24 AM	1143	34.4284515	-118.6498218	
H-2308S	9/28/2026 9:25:41 AM	1146	34.4284533	-118.6498070	
H-2309N	9/23/2026 10:09:11 AM	1293	34.4308103	-118.6489333	Valve Adjustment:Plugged/Pinched Suspected
H-2309S	9/28/2026 1:47:35 PM	1102	34.4281662	-118.6487472	Valve Adjustment:Increased Flow/Vacuum
H-2309S	9/28/2026 1:50:05 PM	1109	34.4281502	-118.6487540	
H-2310N	9/21/2026 10:17:15 AM	1197	34.4298735	-118.6478407	
H-2310N	9/21/2026 10:23:24 AM	1172	34.4298905	-118.6478558	Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum
H-2310N	9/21/2026 10:25:58 AM	1183	34.4298712	-118.6478453	
H-2310S	9/30/2026 9:54:34 AM	1105	34.4291867	-118.6475135	Valve Adjustment:Barely Open
H-2401S	9/17/2026 12:53:46 PM	1187	34.4288763	-118.6512315	Valve Adjustment:Increased Flow/Vacuum;Well Comment:Recommend bigger wellhead
H-2401S	9/17/2026 12:55:27 PM	1195	34.4288703	-118.6512107	
H-2402N	9/16/2026 9:29:50 AM	1218	34.4291228	-118.6502807	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
H-2402N	9/16/2026 9:38:17 AM	1209	34.4291292	-118.6502657	
H-2402S	9/17/2026 10:29:36 AM	1203	34.4287675	-118.6504800	Valve Adjustment:Decreased Flow/Vacuum
H-2402S	9/17/2026 10:36:31 AM	1209	34.4287543	-118.6504988	
H-2403N	9/16/2026 9:07:19 AM	1216	34.4293012	-118.6501653	Valve Adjustment:Decreased Flow/Vacuum
H-2403N	9/16/2026 9:15:02 AM	1228	34.4292928	-118.6501797	

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
H-2403S	9/17/2026 9:46:50 AM	1186	34.4287493	-118.6498800	Valve Adjustment:Increased Flow/Vacuum,Barely Open
H-2403S	9/17/2026 9:55:54 AM	1182	34.4287562	-118.6498785	Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum
H-2403S	9/17/2026 10:14:23 AM	1185	34.4287595	-118.6498838	Valve Adjustment:Increased Flow/Vacuum
H-2404N	9/4/2026 10:12:11 AM	1214	34.4293013	-118.6495623	Valve Adjustment:Increased Flow/Vacuum
H-2404N	9/17/2026 10:16:28 AM	1178	34.4287662	-118.6498930	
H-2404S	9/17/2026 9:29:43 AM	1170	34.4287540	-118.6493110	Valve Adjustment:Valve 100% Open
H-2405N	9/30/2026 12:52:28 PM	1260	34.4300043	-118.6495265	Valve Adjustment:Audible Flow,Barely Open,Reduce Sys. Vac. - Flare Down
H-29	9/25/2026 11:24:23 AM	1273	34.4354158	-118.6417870	Valve Adjustment:Decreased Flow/Vacuum,Valve 100% Closed
H-72	9/30/2026 1:21:04 PM	1331	34.4369380	-118.6448205	
H-74	9/16/2026 11:51:01 AM	1306	34.4371967	-118.6433037	Valve Adjustment:Audible Flow
H-75	9/22/2026 2:37:52 PM	1348	34.4364338	-118.6419792	,
H-79	9/4/2026 9:06:09 AM	1304	34.4339352	-118.6427842	
P-02R	9/14/2026 10:11:10 AM	1161	34.4297070	-118.6439315	
P-03R	9/14/2026 1:32:02 PM	1165	34.4298962	-118.6441943	
P-04	9/14/2026 1:26:28 PM	1175	34.4295005	-118.6445293	
P-05	9/14/2026 1:22:06 PM	1152	34.4291833	-118.6447825	
P-06R	9/14/2026 1:14:43 PM	1148	34.4288800	-118.6450652	
P-07R	9/14/2026 9:55:22 AM	1182	34.4298193	-118.6433152	
P-08R	9/14/2026 10:17:08 AM	1165	34.4294058	-118.6437460	
P-09	9/14/2026 10:29:35 AM	1159	34.4289947	-118.6443200	
P-10	9/14/2026 10:34:17 AM	1143	34.4287177	-118.6446367	
P-11	9/14/2026 10:41:27 AM	1127	34.4284882	-118.6449703	
P-12	9/14/2026 1:08:27 PM	1118	34.4288657	-118.6456145	
P-13	9/14/2026 1:02:12 PM	1105	34.4285188	-118.6458233	
P-14	9/14/2026 10:49:55 AM	1092	34.4280243	-118.6460637	
P-15R	9/11/2026 9:23:55 AM	1100	34.4277942	-118.6459262	
P-16	9/11/2026 9:31:08 AM	1092	34.4275302	-118.6455993	
P-17	9/11/2026 1:40:34 PM	1099	34.4273787	-118.6453100	
P-18RD	9/11/2026 1:30:44 PM	1110	34.4271017	-118.6449838	
P-18RS	9/11/2026 1:34:14 PM	1096	34.4271037	-118.6450097	
P-19	9/11/2026 1:55:29 PM	1070	34.4268768	-118.6451973	
P-20R	9/11/2026 1:23:45 PM	1101	34.4268375	-118.6448275	
P-21	9/11/2026 1:17:27 PM	1111	34.4264870	-118.6448013	
P-21RD	9/11/2026 1:06:36 PM	1116	34.4263808	-118.6443692	
P-21RS	9/11/2026 1:09:45 PM	1119	34.4263870	-118.6443767	
P-22RD	9/11/2026 8:08:10 AM	1175	34.4269042	-118.6437940	
P-22RS	9/11/2026 8:04:52 AM	1180	34.4269258	-118.6438105	
P-23	9/11/2026 1:01:52 PM	1087	34.4261307	-118.6446950	
P-24	9/13/2026 1:20:31 PM	1101	34.4260803	-118.6443095	

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
P-26	9/13/2026 1:35:13 PM	1129	34.4265215	-118.6432322	
P-27	9/13/2026 1:42:38 PM	1134	34.4268305	-118.6427857	
P-28	9/13/2026 1:49:04 PM	1149	34.4270482	-118.6422927	
P-28	9/25/2026 2:03:37 PM	1151	34.4270463	-118.6422782	Valve Adjustment:Barely Open
P-29R	9/14/2026 8:03:35 AM	1142	34.4271838	-118.6418537	
P-30R	9/14/2026 8:11:45 AM	1163	34.4274317	-118.6416140	
P-32R1	9/14/2026 8:36:49 AM	1184	34.4282325	-118.6410458	
P-32R2	9/14/2026 8:45:03 AM	1181	34.4284388	-118.6409368	
P-33	9/14/2026 8:50:19 AM	1185	34.4288372	-118.6408297	
P-36	9/14/2026 9:06:39 AM	1215	34.4301798	-118.6400528	
P-36	9/14/2026 9:07:30 AM	1223	34.4301893	-118.6400587	
P-37	9/14/2026 9:26:35 AM	1225	34.4305073	-118.6403603	
P-38RD	9/9/2026 1:02:10 PM	1222	34.4299695	-118.6406322	
P-38RS	9/9/2026 12:58:14 PM	1231	34.4299758	-118.6406440	
P-39	9/9/2026 1:09:03 PM	1222	34.4294767	-118.6409795	Valve Adjustment:NSPS/EG CAI,High O2
P-39	9/9/2026 1:12:07 PM	1221	34.4294888	-118.6409893	Valve Adjustment:NSPS/EG CAI,High O2
P-41	9/9/2026 1:35:32 PM	1221	34.4288968	-118.6414145	
P-42R	9/9/2026 1:46:37 PM	1217	34.4284240	-118.6416973	
P-43	9/9/2026 1:51:47 PM	1222	34.4282688	-118.6418300	
P-44RD	9/9/2026 1:59:38 PM	1219	34.4281448	-118.6419440	
P-44RS	9/9/2026 1:56:43 PM	1219	34.4281342	-118.6419397	
P-45RD	9/11/2026 7:34:35 AM	1224	34.4277337	-118.6424752	
P-45RS	9/11/2026 7:38:47 AM	1218	34.4277402	-118.6424682	
P-46RD	9/11/2026 7:48:05 AM	1219	34.4276617	-118.6426650	
P-46RS	9/11/2026 7:50:57 AM	1217	34.4276562	-118.6426663	
P-47	9/11/2026 7:57:45 AM	1210	34.4274432	-118.6432615	
P-48	9/11/2026 8:17:55 AM	1198	34.4275945	-118.6435923	
P-49RD	9/2/2026 12:40:19 PM	1211	34.4279963	-118.6438657	
P-49RS	9/2/2026 12:36:19 PM	1218	34.4279638	-118.6438263	
P-52	9/2/2026 12:48:58 PM	1223	34.4287322	-118.6432828	
P-53	9/2/2026 12:54:52 PM	1225	34.4291075	-118.6430702	
P-54	9/2/2026 1:04:15 PM	1235	34.4294205	-118.6428818	
P-55	9/2/2026 1:11:35 PM	1228	34.4297295	-118.6427393	
P-56	9/2/2026 1:26:56 PM	1241	34.4301117	-118.6428300	
P-57	9/2/2026 1:19:29 PM	1232	34.4299682	-118.6424433	
P-60R	9/2/2026 1:44:59 PM	1240	34.4307882	-118.6415505	
P-61	9/3/2026 10:41:33 AM	1243	34.4311500	-118.6411538	
P-65	9/3/2026 10:49:34 AM	1260	34.4304112	-118.6409530	
P-71	9/11/2026 8:24:58 AM	1216	34.4279690	-118.6432200	
P-75	9/2/2026 1:35:58 PM	1259	34.4302885	-118.6415238	
P-76	9/9/2026 12:51:44 PM	1232	34.4302210	-118.6404325	
P-79	9/11/2026 1:48:37 PM	1053	34.4270263	-118.6460497	

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
P-79	9/14/2026 7:34:29 AM	1039	34.4270218	-118.6460565	
SC-2000E	9/25/2026 8:57:52 AM	1208	34.4307137	-118.6467738	Valve Adjustment:Decreased Flow/Vacuum
SC-2501E	9/8/2026 9:59:28 AM				Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
SC-2501E	9/8/2026 10:01:00 AM				AtmAA
SC-2501E	9/14/2026 9:17:00 AM				AtmAA
SC-2501E	9/14/2026 9:21:21 AM	1334	34.4366658	-118.6479245	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
SC-2501E	9/14/2026 9:23:51 AM	1338	34.4366885	-118.6479270	Valve Adjustment:No Flow Measurement,High Temp
SC-2501E	9/21/2026 9:24:00 AM				AtmAA
SC-2501E	9/21/2026 9:24:06 AM	1338	34.4367003	-118.6479188	Valve Adjustment:No Flow Measurement,High Temp
SC-2501E	9/28/2026 8:44:16 AM	1345	34.4366886	-118.6478967	Valve Adjustment:No Flow Measurement,High Temp
SC-2501E	9/28/2026 8:50:00 AM				AtmAA
SC-2501W	9/14/2026 1:14:36 PM	1363	34.4367787	-118.6485455	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
SC-2501W	9/14/2026 1:16:00 PM	1356	34.4367882	-118.6485310	
SC-2501W	9/21/2026 9:47:01 AM	1353	34.4367967	-118.6485404	Valve Adjustment:No Flow Measurement,High Temp
SC-2501W	9/21/2026 9:50:00 AM				AtmAA
SC-2501W	9/28/2026 9:27:48 AM	1350	34.4367775	-118.6485433	Valve Adjustment:No Flow Measurement,High Temp
SC-2501W	9/28/2026 9:30:00 AM				AtmAA
SW-10	9/28/2026 10:08:23 AM	1330	34.4370338	-118.6503715	
SW-115	9/17/2026 1:39:25 PM	1202	34.4348293	-118.6412152	
SW-1445	9/29/2026 12:27:40 PM	1228	34.4324977	-118.6520037	Valve Adjustment:Reconnected this Date
SW-1455	9/30/2026 4:06:16 PM	1217	34.4325137	-118.6519597	Valve Adjustment:Reconnected this Date,Increased Flow/Vacuum
SW-154	9/30/2026 2:17:21 PM	1267	34.4379645	-118.6456497	Valve Adjustment:Reduce Sys. Vac. - Flare Down
SW-17-135	9/30/2026 4:01:25 PM	1216	34.4325153	-118.6519583	Valve Adjustment:Reconnected this Date,Increased Flow/Vacuum
SW-187	9/23/2026 9:03:24 AM	1310	34.4372337	-118.6473478	
SW-20	9/14/2026 10:03:19 AM	1170	34.4302225	-118.6436447	Valve Adjustment:NSPS/EG CAI,High O2
SW-20	9/14/2026 10:04:06 AM	1170	34.4302227	-118.6436470	Valve Adjustment:NSPS/EG CAI,High O2
SW-2501D	9/28/2026 8:51:48 AM	1236	34.4335223	-118.6519685	
SW-2501M	9/28/2026 8:37:05 AM	1234	34.4335150	-118.6520013	
SW-2501MD	9/28/2026 8:48:27 AM	1240	34.4335137	-118.6519903	
SW-2501S	9/28/2026 8:34:18 AM	1237	34.4335185	-118.6519930	
SW-2502D	9/28/2026 1:31:44 PM	1233	34.4337208	-118.6519175	Valve Adjustment:Reduce Sys. Vac. - Flare Down
SW-2502M	9/28/2026 1:35:12 PM	1223	34.4337085	-118.6519090	Valve Adjustment:Reduce Sys. Vac. - Flare Down
SW-2502MD	9/28/2026 9:07:21 AM	1232	34.4337310	-118.6519317	

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	Elev [ft]	Latitude	Longitude	Comments
SW-2502S	9/28/2026 9:04:57 AM	1236	34.4337335	-118.6519282	
SW-2503D	9/28/2026 9:31:14 AM	1267	34.4351315	-118.6516038	
SW-2503M	9/28/2026 9:36:56 AM	1280	34.4351258	-118.6515968	
SW-2503MD	9/28/2026 9:43:35 AM	1264	34.4351190	-118.6515960	
SW-2503S	9/28/2026 9:40:46 AM	1276	34.4351215	-118.6515818	
SW-2504D	9/28/2026 9:56:00 AM	1274	34.4353063	-118.6516703	
SW-2504M	9/28/2026 9:49:08 AM	1271	34.4353008	-118.6516693	
SW-2504MD	9/28/2026 9:59:28 AM	1272	34.4353142	-118.6516715	
SW-2504S	9/28/2026 9:52:36 AM	1264	34.4353082	-118.6516607	
SW-30	9/28/2026 8:56:46 AM	1233	34.4336635	-118.6519505	
SW-32	9/28/2026 8:26:06 AM	1234	34.4335182	-118.6520110	
SW-64	9/28/2026 8:59:49 AM	1232	34.4336715	-118.6519532	
SW-65	9/17/2026 10:54:03 AM	1208	34.4348230	-118.6412032	
SW-65	9/17/2026 11:10:21 AM	1213	34.4348453	-118.6412638	
SW-66	9/30/2026 2:19:22 PM	1280	34.4379620	-118.6456293	Valve Adjustment:Reduce Sys. Vac. - Flare Down
SW-68	9/28/2026 8:30:14 AM	1238	34.4335178	-118.6519883	
SW-70	9/23/2026 9:06:01 AM	1320	34.4372307	-118.6473725	
SW-71	9/13/2026 1:27:50 PM	1126	34.4259810	-118.6438412	Valve Adjustment:NSPS/EG CAI,High O2
SW-71	9/13/2026 1:29:03 PM	1123	34.4259863	-118.6438483	Valve Adjustment:NSPS/EG CAI,High O2
SW-72	9/14/2026 8:57:13 AM	1207	34.4296373	-118.6401932	
SW-80	9/3/2026 12:03:20 PM	1231	34.4383017	-118.6433473	
SW-9	9/23/2026 9:09:10 AM	1317	34.4372213	-118.6473733	
TC-1961C	9/24/2026 11:07:18 AM	1302	34.4321850	-118.6454320	Valve Adjustment:Surging Liquid in Header
TC-1961E	9/1/2026 9:15:54 AM	1296	34.4328613	-118.6444795	Valve Adjustment:Decreased Flow/Vacuum
TC-2174	9/8/2026 9:41:41 AM	1348	34.4367493	-118.6476344	Valve Adjustment:No Flow Measurement,High Temp
TC-2174	9/8/2026 9:44:00 AM				AtmAA
TC-2174	9/14/2026 8:44:26 AM	1337	34.4367498	-118.6476372	Valve Adjustment:No Flow Measurement,High Temp
TC-2174	9/14/2026 8:47:00 AM				AtmAA
TC-2174	9/21/2026 9:00:00 AM				AtmAA
TC-2174	9/21/2026 9:00:43 AM	1338	34.4367669	-118.6476533	Valve Adjustment:No Flow Measurement,High Temp
TC-2174	9/28/2026 8:20:43 AM	1348	34.4367395	-118.6476302	Valve Adjustment:No Flow Measurement,High Temp
TC-2174	9/28/2026 8:25:00 AM				AtmAA
VL-02	9/30/2026 10:59:45 AM	1167	34.4311722	-118.6443214	Valve Adjustment:Valve 100% Open

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-108-52	9/1/2026 7:25:00 AM					450						Air Tech Lab
CV-108-52	9/1/2026 7:25:00 AM						130000					Air Tech Lab; [User entered 13%]
CV-108-52	9/2/2026 7:35:40 AM	15.6	69.0	0.0	15.4			61.0	60.7	10.57	12.65	NSPS/EG CAI,Positive Static Press.,Reduced System Vacuum
CV-108-52	9/2/2026 7:36:35 AM	15.6	71.2	0.0	13.2			59.0	59.0	11.01	11.01	NSPS/EG CAI,Positive Static Press.,Reduced System Vacuum
CV-108-52	9/10/2026 3:44:09 PM	48.6	51.3	0.0	0.1			107.3	108.9	1.07	-1.86	Valve Adjustment:NSPS/EG CAC,Increased Flow/Vacuum,Barely Open
CV-108-52	9/10/2026 3:44:53 PM	49.6	50.4	0.0	0.0			108.7	108.6	-2.85	-2.89	
CV-108-52	9/22/2026 11:11:22 AM	40.7	35.6	4.5	19.2			97.8	97.9	-9.72	-9.17	,
CV-113	9/4/2026 7:00:00 AM					37						AirTech Lab
CV-113	9/4/2026 7:00:00 AM						0					AirTech Lab; [User entered 0%]
CV-113	9/14/2026 9:34:21 AM	0.3	1.6	18.7	79.4			97.6	97.8	-0.02	-0.02	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In)
CV-113	9/14/2026 9:35:35 AM	2.4	1.9	18.0	77.7			98.9	98.9	-0.03	-0.02	
CV-113	9/25/2026 10:33:54 AM	12.8	19.1	13.0	55.1			106.0	106.1	-0.01	-0.01	Valve Adjustment:High O2,Barely Open
CV-114	9/4/2026 8:22:00 AM					2200						AirTech Lab
CV-114	9/4/2026 8:22:00 AM						180000					AirTech Lab; [User entered 18%]
CV-114	9/8/2026 9:33:48 AM	0.8	81.3	0.0	17.9			189.9	189.8	-4.74	-4.61	Valve Adjustment:No Flow Measurement,High Temp
CV-114	9/8/2026 9:39:00 AM					3460						AtmAA
CV-114	9/14/2026 8:28:09 AM	1.5	82.9	0.0	15.6			188.9	189.0	-7.52	-7.31	Valve Adjustment:No Flow Measurement,High Temp
CV-114	9/14/2026 8:30:00 AM					3730						AtmAA
CV-114	9/21/2026 8:22:00 AM	3.0	79.4	0.0	17.6			189.0	189.0	-4.77	-4.56	Valve Adjustment:No Flow Measurement,High Temp
CV-114	9/28/2026 8:16:00 AM	2.6	0.0	0.0	97.4			188.8	188.8	-8.17	-8.17	Valve Adjustment:No Flow Measurement,High Temp
CV-1532A	9/1/2026 7:30:00 AM					1400						Air Tech Lab
CV-1532A	9/1/2026 7:30:00 AM						230000					AirTech Lab; [User entered 23%]
CV-1532A	9/1/2026 1:33:46 PM	1.2	70.8	1.1	26.9			101.4	102.1	-3.50	-3.64	Valve Adjustment:No Flow Measurement

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-1532A	9/30/2026 3:06:52 PM	0.7	75.5	0.9	22.9			167.0	167.2	-7.59	-7.76	
CV-1535	9/1/2026 9:18:24 AM	45.5	48.3	0.0	6.2			105.4	105.5	-0.58	-0.53	,
CV-1535	9/4/2026 7:22:00 AM					2800						AirTech Lab
CV-1535	9/4/2026 7:22:00 AM						180000					AirTech Lab; [User entered 18%]
CV-1535	9/22/2026 11:06:11 AM	28.1	36.2	0.0	35.7			125.6	125.5	-6.94	-5.60	,
CV-1535	9/24/2026 2:43:07 PM	29.6	40.2	0.0	30.2			126.1	125.8	-5.40	-4.58	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header
CV-1902A	9/1/2026 7:35:00 AM					310						Air Tech Lab
CV-1902A	9/1/2026 7:35:00 AM						43000					Air Tech Lab; [User entered 4.3%]
CV-1902A	9/8/2026 10:47:01 AM	2.5	75.0	0.2	22.3			158.4	159.4	-5.70	-5.63	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-1902A	9/8/2026 10:50:00 AM					1290						AtmAA
CV-1902A	9/16/2026 2:32:50 PM	12.4	72.3	1.3	14.0			157.7	157.8	-6.63	-6.42	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-1902A	9/23/2026 2:32:08 PM	10.3	77.5	0.0	12.2			182.5	181.6	-7.43	-7.12	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-1902A	9/30/2026 2:40:44 PM	9.6	64.4	2.6	23.4			154.5	155.0	-6.05	-6.02	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2001	9/2/2026 8:39:57 AM	9.5	69.9	2.0	18.6			79.4	79.5	-8.38	-8.03	Reduced System Vacuum,
CV-2001	9/9/2026 7:20:00 AM					1100						AirTech Lab
CV-2001	9/9/2026 7:20:00 AM						100000					AirTech Lab; [User entered 10%]
CV-2001	9/23/2026 8:47:00 AM	4.6	54.5	7.5	33.4			85.7	86.5	-11.67	-11.60	Valve Comment:Well too tall
CV-2002	9/1/2026 2:10:00 PM					3900						AtmAA
CV-2002	9/1/2026 2:10:00 PM						117100					AtmAA; [User entered 11.71%]
CV-2002	9/1/2026 2:10:13 PM	12.4	71.4	0.3	15.9			185.8	185.8	-6.92	-6.94	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2002	9/8/2026 1:42:58 PM	15.2	73.0	0.6	11.2			185.6	185.6	-5.92	-5.00	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-2002	9/8/2026 1:45:00 PM					4130						AtmAA
CV-2002	9/9/2026 7:25:00 AM					2900						AirTech Lab

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2002	9/9/2026 7:25:00 AM						140000					AirTech Lab; [User entered 14%]
CV-2002	9/17/2026 8:11:35 AM	24.9	67.9	0.4	6.8			183.5	183.4	-6.40	-6.23	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	9/24/2026 9:58:49 AM	9.8	72.3	0.0	17.9			184.2	184.3	-10.65	-10.45	Valve Adjustment:No Flow Measurement,High Temp
CV-2007	9/3/2026 10:00:55 AM	16.8	76.7	0.0	6.5			126.2	126.3	-1.12	-1.15	Valve Adjustment:Barely Open
CV-2007	9/4/2026 7:48:00 AM					470						AirTech Lab
CV-2007	9/4/2026 7:48:00 AM						62000					AirTech Lab; [User entered 6.2%]
CV-2007	9/25/2026 2:05:13 PM	9.6	40.3	2.3	47.8			147.0	147.2	-1.11	-1.15	Valve Adjustment:High Temp,Barely Open
CV-2007	9/28/2026 10:15:15 AM	8.3	37.5	2.7	51.5			152.5	152.5	-2.02	-2.02	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2007	9/30/2026 10:12:39 AM	8.3	36.1	3.0	52.6			150.5	148.3	-1.88	-1.23	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-2007	9/30/2026 10:14:47 AM	8.0	36.4	3.3	52.3			146.5	146.4	-1.14	-1.13	Valve Adjustment:High Temp;Well Comment:Bad valve on well head;Well Condition:Fair;Well Repairs:Valve
CV-2301	9/2/2026 9:11:34 AM	20.2	64.6	0.0	15.2			179.1	179.0	-9.44	-9.27	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	9/2/2026 9:13:00 AM					775						AtmAA
CV-2301	9/2/2026 9:13:00 AM						55700					AtmAA; [User entered 5.57%]
CV-2301	9/3/2026 6:40:00 AM					470						AirTech Lab
CV-2301	9/3/2026 6:40:00 AM						55000					AirTech Lab; [User entered 5.5%]
CV-2301	9/8/2026 9:59:02 AM	22.0	48.9	3.9	25.2			167.1	167.3	-6.41	-6.37	NSPS/EG CAI,High Temp
CV-2301	9/8/2026 10:00:00 AM					1170						AtmAA
CV-2301	9/16/2026 1:46:53 PM	25.4	69.6	0.0	5.0			179.6	177.6	-5.55	-5.05	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	9/23/2026 1:27:45 PM	44.1	55.9	0.0	0.0			175.3	174.9	-6.56	-6.44	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	9/30/2026 10:14:35 AM	43.3	46.5	10.2	0.0			174.4	174.6	-9.58	-8.80	Valve Adjustment:No Flow Measurement,High Temp
CV-2302	9/2/2026 8:56:46 AM	43.0	45.2	1.1	10.7			125.8	125.7	-12.16	-12.16	Valve Comment:Valve stuck open;Valve Adjustment:Valve 100% Open
CV-2302	9/3/2026 6:45:00 AM					0						AirTech Lab

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2302	9/3/2026 6:45:00 AM						35000					AirTech Lab; [User entered 3.5%]
CV-2302	9/17/2026 10:41:57 AM	44.5	45.0	1.1	9.4			113.0	113.3	-11.03	-12.03	
CV-2303	9/3/2026 6:50:00 AM					1700						AirTech Lab
CV-2303	9/3/2026 6:50:00 AM						190000					AirTech Lab; [User entered 19%]
CV-2303	9/3/2026 7:49:00 AM					2165						AtmAA
CV-2303	9/3/2026 7:49:00 AM						187500					AtmAA; [User entered 18.75%]
CV-2303	9/3/2026 7:52:16 AM	2.1	73.6	0.0	24.3			190.5		0.45		Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2303	9/3/2026 7:53:05 AM	3.2	79.0	0.0	17.8			188.1	189.1	0.46	0.41	Valve Adjustment:No Flow Measurement,High O2;Well Condition:Lorentz Pump Installed
CV-2303	9/9/2026 8:46:47 AM	8.8	39.4	0.2	51.6			188.7	188.8	-0.25	-0.23	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2303	9/9/2026 8:50:00 AM					2470						AtmAA
CV-2303	9/15/2026 9:24:00 AM	9.7	61.8	0.0	28.5			188.5	189.6	0.43	0.44	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2303	9/15/2026 9:25:00 AM					2620						AtmAA
CV-2303	9/22/2026 9:19:07 AM	6.4	78.9	0.0	14.7			192.6	193.1	0.26	0.22	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2305	9/1/2026 10:04:00 AM					2310						AtmAA
CV-2305	9/1/2026 10:04:00 AM						50300					AtmAA; [User entered 5.03%]
CV-2305	9/1/2026 10:04:41 AM	36.5	59.2	0.0	4.3			158.7	158.8	-4.76	-4.73	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2305	9/9/2026 8:05:00 AM					1200						AirTech Lab
CV-2305	9/9/2026 8:05:00 AM						47000					AirTech Lab; [User entered 4.7%]
CV-2305	9/9/2026 10:42:39 AM	27.0	71.2	0.0	1.8			155.5	155.6	-4.99	-3.44	Valve Adjustment:High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2305	9/9/2026 10:43:11 AM	35.9	57.4	0.0	6.7			155.7	155.7	-2.38	-2.34	

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2305	9/9/2026 11:00:00 AM					2760						AtmAA
CV-2305	9/15/2026 2:00:00 PM					2740						AtmAA
CV-2305	9/15/2026 2:02:20 PM	26.5	73.5	0.0	0.0			163.4	163.8	0.86	-1.38	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-2305	9/15/2026 2:04:55 PM	26.3	73.7	0.0	0.0			163.6	163.7	-1.56	-1.51	Valve Adjustment:NSPS/EG CAC,High Temp;Well Condition:Lorentz Pump Installed
CV-2305	9/22/2026 2:28:38 PM	16.0	81.6	0.0	2.4			157.9	157.9	-5.10	-5.10	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2305	9/29/2026 1:49:58 PM	35.5	60.1	0.0	4.4			158.9	159.0	-6.52	-6.61	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2305	9/30/2026 10:01:12 AM	20.9	51.5	0.0	27.6			157.5	157.6	-8.45	-8.56	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2312-PLR	9/2/2026 8:09:16 AM	3.5	83.0	0.0	13.5			168.3	168.3	-3.87	-3.44	Valve Adjustment:No Flow Measurement,High Temp
CV-2312-PLR	9/3/2026 7:00:00 AM					2600						AirTech Lab
CV-2312-PLR	9/3/2026 7:00:00 AM						160000					AirTech Lab; [User entered 16%]
CV-2312-PLR	9/9/2026 1:24:41 PM	17.4	71.0	0.1	11.5			169.7	169.6	-3.71	-3.72	Valve Adjustment:No Flow Measurement,High Temp
CV-2312-PLR	9/9/2026 1:35:00 PM					3410						AtmAA
CV-2312-PLR	9/16/2026 10:44:19 AM	5.0	79.9	0.0	15.1			169.6	169.5	-2.65	-2.15	Valve Adjustment:No Flow Measurement,High Temp
CV-2312-PLR	9/23/2026 10:29:16 AM	43.9	53.5	2.6	0.0			170.0	170.1	-34.37	-34.04	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2312-PLR	9/23/2026 1:10:56 PM	6.8	79.1	0.0	14.1			169.8	169.8	-4.53	-4.39	Valve Adjustment:No Flow Measurement,High Temp
CV-2312-PLR	9/30/2026 9:44:29 AM	6.4	79.0	0.0	14.6			169.9	170.0	-9.62	-9.44	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PLR	9/1/2026 1:32:37 PM	11.3	76.9	0.0	11.8			187.2	187.3	-13.88	-13.98	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PLR	9/1/2026 1:38:00 PM					4010						AtmAA
CV-2314-PLR	9/1/2026 1:38:00 PM						120100					AtmAA; [User entered 12.01%]
CV-2314-PLR	9/4/2026 7:56:00 AM					2700						AirTech Lab
CV-2314-PLR	9/4/2026 7:56:00 AM						130000					AirTech Lab; [User entered 13%]

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2314-PLR	9/9/2026 1:40:13 PM	23.0	76.3	0.0	0.7			188.1	188.1	-7.74	-7.41	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PLR	9/9/2026 1:46:00 PM					2810						AtmAA
CV-2314-PLR	9/16/2026 9:39:58 AM	6.1	84.0	0.1	9.8			187.9	187.8	-4.97	-5.18	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PLR	9/23/2026 9:37:50 AM	9.3	79.1	0.6	11.0			186.3	186.2	-12.90	-12.87	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PLR	9/30/2026 8:54:14 AM	5.1	82.0	0.2	12.7			185.5	185.5	-11.15	-11.08	Valve Adjustment:No Flow Measurement,High Temp
CV-2315	9/3/2026 9:13:05 AM	14.8	74.0	0.1	11.1			184.9	185.1	-2.07	-2.39	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2315	9/3/2026 9:17:00 AM					2450						AtmAA
CV-2315	9/3/2026 9:17:00 AM						123800					AtmAA; [User entered 12.38%]
CV-2315	9/4/2026 8:04:00 AM					2200						AirTech Lab
CV-2315	9/4/2026 8:04:00 AM						170000					AirTech Lab; [User entered 17%]
CV-2315	9/8/2026 1:48:37 PM	4.4	79.7	0.0	15.9			179.1	180.6	-0.43	-0.46	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2315	9/8/2026 1:51:00 PM					2730						AtmAA
CV-2315	9/14/2026 10:40:35 AM	17.7	69.7	0.0	12.6			191.7	191.8	-1.77	-1.67	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2315	9/14/2026 10:44:00 AM					1710						AtmAA
CV-2315	9/21/2026 10:37:20 AM	29.6	64.3	0.0	6.1			187.2	187.3	-4.79	-4.52	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2315	9/28/2026 10:36:48 AM	23.8	66.4	0.0	9.8			187.5	187.5	-5.20	-4.66	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2328	9/1/2026 2:21:10 PM	43.1	56.9	0.0	0.0			152.5	152.9	-3.85	-3.75	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2328	9/1/2026 2:25:00 PM					1690						AtmAA
CV-2328	9/1/2026 2:25:00 PM						2600					AtmAA; [User entered 0.26%]
CV-2328	9/9/2026 7:45:00 AM					630						AirTech Lab
CV-2328	9/9/2026 7:45:00 AM						62000					AirTech Lab; [User entered 6.2%]

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2328	9/9/2026 1:45:59 PM	50.5	49.5	0.0	0.0			119.1	119.1	-2.47	-2.38	Well Condition:Lorentz Pump Installed
CV-2328	9/24/2026 10:56:47 AM	37.6	56.8	0.1	5.5			151.3	151.3	-7.73	-7.05	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-2328	9/24/2026 10:58:35 AM	36.2	57.1	0.0	6.7			151.1	151.3	-7.05	-7.05	
CV-2328	9/28/2026 2:24:07 PM	35.2	63.1	0.0	1.7			148.1	148.4	-7.55	-7.56	Valve Adjustment:High Temp
CV-2328	9/30/2026 8:52:17 AM	38.1	55.8	0.0	6.1			145.4	145.4	-8.94	-8.94	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2333	9/3/2026 7:45:00 AM					2700						AirTech Lab
CV-2333	9/3/2026 7:45:00 AM						190000					AirTech Lab; [User entered 19%]
CV-2333	9/8/2026 9:30:41 AM	1.2	65.8	0.0	33.0			184.2	184.4	-5.48	-5.22	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2333	9/8/2026 9:35:00 AM					4040						AtmAA
CV-2333	9/14/2026 8:23:05 AM	1.9	84.2	0.0	13.9			186.5	186.6	-7.65	-7.58	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2333	9/14/2026 8:25:00 AM					5050						AtmAA
CV-2333	9/21/2026 8:18:24 AM	2.4	80.9	0.0	16.7			187.9	187.9	-5.73	-5.73	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2333	9/28/2026 8:08:07 AM	1.0	78.3	0.0	20.7			189.0	189.0	-9.52	-9.10	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2334	9/3/2026 7:50:00 AM					2600						AirTech Lab
CV-2334	9/3/2026 7:50:00 AM						140000					AirTech Lab; [User entered 14%]
CV-2334	9/9/2026 12:10:26 PM	9.0	77.9	0.2	12.9			145.6	145.6	-1.32	-1.44	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2334	9/9/2026 12:10:43 PM	8.5	79.4	0.3	11.8			145.6	145.6	-1.49	-1.49	Valve Adjustment:High Temp,Barely Open
CV-2334	9/17/2026 12:59:56 PM	13.2	73.2	0.0	13.6			147.7	147.7	-3.43	-3.44	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2334	9/24/2026 1:44:17 PM	13.3	77.9	0.0	8.8			154.5	154.5	0.96	-0.98	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2334	9/24/2026 1:45:33 PM	11.5	74.4	0.0	14.1			154.7	154.7	-1.01	-1.00	Valve Adjustment:NSPS/EG CAC,High Temp;Well Condition:Lorentz Pump Installed

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2337	9/8/2026 10:57:52 AM	4.7	79.0	0.1	16.2			153.3	153.4	-1.73	-1.72	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-2337	9/8/2026 11:00:00 AM					4780						AtmAA
CV-2337	9/10/2026 9:00:00 AM					2000						AirTech Lab
CV-2337	9/10/2026 9:00:00 AM						100000					AirTech Lab; [User entered 10%]
CV-2337	9/16/2026 2:19:44 PM	15.3	0.0	0.0	84.7			153.7	153.8	-1.09	-1.06	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2337	9/23/2026 2:21:55 PM	13.4	75.9	0.0	10.7			144.7	144.6	-7.37	-7.16	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2337	9/30/2026 2:20:16 PM	7.9	76.1	0.0	16.0			138.8	138.7	-7.92	-7.71	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2341	9/10/2026 8:29:15 AM	1.5	75.0	0.1	23.4			87.3	87.7	4.01	-1.90	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open
CV-2341	9/10/2026 8:30:27 AM	1.4	75.5	0.0	23.1			88.0	88.0	-2.28	-2.26	Valve Adjustment:NSPS/EG CAC
CV-2341	9/10/2026 8:45:00 AM					1500						AirTech Lab
CV-2341	9/10/2026 8:45:00 AM						220000					AirTech Lab; [User entered 22.%]
CV-2341	9/24/2026 2:48:06 PM	5.5	69.3	0.4	24.8			102.0	102.0	-8.55	-8.44	Valve Adjustment:Decreased Flow/Vacuum
CV-2344	9/1/2026 7:15:00 AM					1500						Air Tech Lab
CV-2344	9/1/2026 12:55:13 PM	10.7	76.2	0.0	13.1			141.6	142.2	-3.39	-3.41	Valve Adjustment:No Flow Measurement;Well Condition:Lorentz Pump Installed
CV-2344	9/1/2026 7:15:00 PM						110000					Air Tech Lab; [User entered 11%]
CV-2344	9/8/2026 1:49:02 PM	12.4	80.3	0.0	7.3			150.4	150.5	-1.60	-1.56	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-2344	9/8/2026 1:50:00 PM					2700						AtmAA
CV-2344	9/8/2026 1:50:10 PM	12.1	80.1	0.0	7.8			150.8	150.8	-1.50	-1.50	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-2344	9/14/2026 10:26:52 AM	12.3	67.3	0.0	20.4			147.1	147.4	-5.64	-5.66	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2344	9/14/2026 10:32:00 AM					2050						AtmAA
CV-2344	9/24/2026 9:12:30 AM	11.1	69.4	0.0	19.5			158.7	158.9	-6.09	-6.07	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2345	9/1/2026 7:10:00 AM					450						Air Tech Lab
CV-2345	9/1/2026 7:10:00 AM						33000					Air Tech Lab; [User entered 3.3%]
CV-2345	9/2/2026 7:32:38 AM	19.8	65.4	0.0	14.8			93.5	93.6	-3.62	-3.60	Reduced System Vacuum,
CV-2345	9/22/2026 11:32:10 AM	17.6	65.8	0.3	16.3			109.5	109.5	-3.85	-3.85	,
CV-2346	9/1/2026 7:05:00 AM					540						Air Tech Lab
CV-2346	9/1/2026 7:05:00 AM						53000					Air Tech Lab; [User entered 5.3%]
CV-2346	9/1/2026 10:35:00 AM					532						AtmAA
CV-2346	9/1/2026 10:35:00 AM						16600					AtmAA; [User entered 1.66%]
CV-2346	9/1/2026 10:36:56 AM	2.2	78.3	0.0	19.5			180.8	180.2	-7.84	-7.85	Valve Adjustment:No Flow Measurement,High Temp
CV-2346	9/8/2026 2:30:00 PM					2740						AtmAA
CV-2346	9/8/2026 2:32:55 PM	11.4	81.2	0.1	7.3			179.4	179.6	-4.99	-4.97	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-2346	9/14/2026 10:07:15 AM	2.2	74.4	0.0	23.5			184.5	184.6	-6.55	-6.54	Valve Adjustment:No Adjustments Made
CV-2346	9/14/2026 10:09:25 AM	1.6	76.0	0.0	22.4			184.7	184.6	-7.13	-6.89	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2346	9/14/2026 10:10:00 AM					1720						AtmAA
CV-2346	9/24/2026 9:07:33 AM	4.5	81.8	0.0	13.7			187.3	187.2	-6.30	-6.14	Valve Adjustment:No Flow Measurement,High Temp
CV-2347	9/1/2026 6:55:00 AM					610						Air Tech Lab
CV-2347	9/1/2026 6:55:00 AM						46000					Air Tech Lab; [User entered 4.6%]
CV-2347	9/2/2026 7:17:45 AM	14.4	48.6	0.2	36.8			91.2	91.0	-3.87	-3.88	,
CV-2347	9/22/2026 12:05:58 PM	14.6	47.0	1.1	37.3			117.6	117.7	-3.52	-3.53	,
CV-2348	9/1/2026 6:50:00 AM						28000					Air Tech Lab; [User entered 2.8%]
CV-2348	9/1/2026 6:50:00 PM					380						Air Tech Lab
CV-2348	9/2/2026 7:12:27 AM	19.9	51.5	0.1	28.5			131.4	131.4	-9.05	-9.02	NSPS/EG CAI,High Temp
CV-2348	9/2/2026 7:13:13 AM	19.9	51.7	0.1	28.3			131.4	131.5	-9.18	-9.11	NSPS/EG CAI,High Temp
CV-2348	9/22/2026 12:12:09 PM	19.0	51.4	0.0	29.6			137.6	137.6	-8.62	-8.65	NSPS/EG CAI,High Temp
CV-2348	9/22/2026 12:13:11 PM	18.8	53.3	0.0	27.9			137.9	137.9	-8.79	-8.76	NSPS/EG CAI,High Temp
CV-2349	9/1/2026 2:05:00 AM						151900					AtmAA; [User entered 15.19%]

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2349	9/1/2026 2:02:58 PM	3.1	71.2	0.7	25.0			162.2	161.7	-2.58	-2.59	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2349	9/1/2026 2:05:00 PM					2770						AtmAA
CV-2349	9/2/2026 7:50:00 AM					2900						AirTech Lab
CV-2349	9/2/2026 7:50:00 AM						200000					AirTech Lab; [User entered 20%]
CV-2349	9/8/2026 1:35:00 PM					3020						AtmAA
CV-2349	9/8/2026 1:37:23 PM	9.1	77.3	0.7	12.9			164.0	163.8	2.35	1.83	NSPS/EG CAI,High Temp,Positive Static Press.,Reduced System Vacuum
CV-2349	9/8/2026 1:38:01 PM	9.5	80.8	0.3	9.4			163.4	163.5	1.50	1.56	NSPS/EG CAI,High Temp,Positive Static Press.,Reduced System Vacuum
CV-2349	9/17/2026 9:37:56 AM	10.3	75.6	0.0	14.1			176.9	178.0	1.36	0.12	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Valve 100% Open,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-2349	9/24/2026 9:55:30 AM	10.2	72.1	0.0	17.7			181.6	181.7	-1.34	-1.31	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2350	9/1/2026 7:20:00 AM					3400						Air Tech Lab
CV-2350	9/1/2026 7:20:00 AM						170000					Air Tech Lab; [User entered 17%]
CV-2350	9/2/2026 8:27:52 AM	6.2	69.6	1.0	23.2			75.8	75.6	-8.15	-7.24	Reduced System Vacuum,
CV-2350	9/23/2026 9:06:15 AM	5.1	79.7	0.3	14.9			117.3	117.4	-11.21	-11.98	Well Comment:valve stuck open
CV-2351	9/2/2026 7:15:00 AM					220						AirTech Lab
CV-2351	9/2/2026 7:15:00 AM						27000					AirTech Lab; [User entered 2.7%]
CV-2351	9/10/2026 12:26:23 PM	19.0	47.9	5.4	27.7			118.4	118.2	-4.07	-3.88	Valve Adjustment:NSPS/EG CAI,High O2,Surging Liquid in Well (Watered In)
CV-2351	9/10/2026 12:27:25 PM	18.2	45.7	5.5	30.6			118.0	117.9	-3.76	-4.02	
CV-2351	9/23/2026 9:53:22 AM	0.0	9.2	19.0	71.8			96.7	96.6	-7.22	-7.02	Valve Adjustment:High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected;Well Comment:valve stuck open
CV-2352	9/2/2026 7:20:00 AM					820						AirTech Lab
CV-2352	9/2/2026 7:20:00 AM						190000					AirTech Lab; [User entered 19%]

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2352	9/10/2026 11:57:24 AM	3.8	73.5	0.6	22.1			146.1	144.6	-3.85	-2.44	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed
CV-2352	9/10/2026 11:59:11 AM	3.7	74.6	0.2	21.5			144.6	144.6	-2.47	-2.61	
CV-2352	9/30/2026 3:26:31 PM	18.1	68.1	0.1	13.7			189.3	190.5	-2.82	-2.85	Valve Adjustment:High Temp
CV-2353-PLR	9/2/2026 7:54:07 AM	4.1	68.4	1.0	26.5			90.4	91.2	-5.78	-5.73	Reduced System Vacuum,
CV-2353-PLR	9/10/2026 8:40:00 AM					560						AirTech Lab
CV-2353-PLR	9/10/2026 8:40:00 AM						230000					AirTech Lab; [User entered 23%]
CV-2353-PLR	9/30/2026 4:20:22 PM	1.9	39.9	8.9	49.3			140.6	142.2	-9.79	-9.79	Valve Adjustment:High Temp,High O2
CV-2354	9/2/2026 7:45:00 AM					1400						AirTech Lab
CV-2354	9/2/2026 7:45:00 AM						150000					AirTech Lab; [User entered 15%]
CV-2354	9/2/2026 8:05:50 AM	7.2	73.8	0.0	19.0			163.2	163.4	5.27	4.47	NSPS/EG CAI,High Temp,Positive Static Press.
CV-2354	9/2/2026 8:06:24 AM	7.4	74.5	0.1	18.0			162.5	162.2	2.07	4.58	NSPS/EG CAI,High Temp,Positive Static Press.
CV-2354	9/8/2026 8:08:52 AM	5.4	74.5	0.0	20.1			187.3	188.2	1.40	-0.48	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2354	9/8/2026 8:10:05 AM	5.3	70.3	0.0	24.4			188.7	188.0	-0.13	-0.10	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2354	9/8/2026 9:08:00 AM					1530						AtmAA
CV-2354	9/17/2026 9:46:30 AM	11.4	75.6	0.0	13.0			187.6	188.0	-4.82	-4.72	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2354	9/24/2026 9:34:17 AM	9.4	72.7	0.0	17.9			182.2	182.3	-9.36	-8.93	Valve Adjustment:No Flow Measurement,High Temp
CV-2354	9/24/2026 9:47:15 AM	7.7	71.3	0.3	20.7			110.3	110.5	-10.53	-10.30	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24002	9/10/2026 8:53:47 AM	35.4	49.0	0.0	15.6			112.6	111.9	-4.31	-3.21	Valve Adjustment:Decreased Flow/Vacuum
CV-24002	9/16/2026 2:44:36 PM	35.4	49.1	0.1	15.4			111.0	110.3	-3.19	-3.18	Valve Adjustment:Barely Open
CV-24003	9/14/2026 9:33:43 AM	26.1	40.5	0.6	32.8			104.8	105.0	-2.27	-2.27	Valve Adjustment:Barely Open

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24003	9/16/2026 2:48:11 PM	30.2	54.6	0.2	15.0			106.5	106.6	-1.52	-1.53	Valve Adjustment:Barely Open
CV-24007	9/1/2026 1:41:17 PM	26.5	46.2	0.1	27.2			145.5	145.7	-3.05	-2.88	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-24007	9/3/2026 7:10:00 AM					400						AirTech Lab
CV-24007	9/3/2026 7:10:00 AM						51000					AirTech Lab; [User entered 5.1%]
CV-24007	9/8/2026 3:13:15 PM	16.2	67.7	0.0	16.1			166.8	166.8	-1.82	-1.79	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-24007	9/8/2026 3:15:00 PM					1040						AtmAA
CV-24007	9/15/2026 8:10:00 AM					283						AtmAA
CV-24007	9/15/2026 8:12:16 AM	28.1	41.7	0.0	30.2			144.4	144.3	-3.30	-3.30	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-24007	9/29/2026 9:01:50 AM	20.3	40.7	0.1	38.9			145.4	145.5	-4.55	-2.04	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down;Well Condition:Pnumatic Pump Installed
CV-24007	9/29/2026 9:03:57 AM	13.4	65.5	0.0	21.1			146.3	146.5	-1.74	-1.75	
CV-24017	9/9/2026 7:35:00 AM					1400						AirTech Lab
CV-24017	9/9/2026 7:35:00 AM						160000					AirTech Lab; [User entered 16%]
CV-24017	9/9/2026 8:19:35 AM	20.9	71.3	0.4	7.4			176.0	176.4	-5.05	-4.88	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	9/9/2026 8:21:00 AM					1095						AtmAA
CV-24017	9/15/2026 8:47:21 AM	17.7	52.5	0.0	29.8			186.7	186.8	-4.81	-4.72	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	9/15/2026 8:51:00 AM					1110						AtmAA
CV-24017	9/22/2026 8:31:48 AM	19.7	69.8	0.7	9.8			174.5	174.0	-4.46	-4.45	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	9/29/2026 8:02:00 AM	19.2	66.5	0.9	13.4			167.3	167.1	-7.79	-7.85	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24049	9/10/2026 9:20:00 AM					1700						AirTech Lab
CV-24049	9/10/2026 9:20:00 AM						150000					AirTech Lab; [User entered 15%]
CV-24049	9/14/2026 9:39:50 AM	4.0	77.2	0.0	18.8			183.4	183.4	-5.97	-5.97	NSPS/EG CAI,High Temp

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24049	9/14/2026 9:40:16 AM	4.2	78.7	0.0	17.1			183.8	183.8	-5.71	-5.78	NSPS/EG CAI,High Temp
CV-24049	9/14/2026 10:45:00 AM					2200						AtmAA
CV-24049	9/21/2026 9:40:32 AM	4.5	71.0	0.0	24.5			187.6	188.7	-10.06	-4.11	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24049	9/21/2026 9:41:36 AM	4.5	74.2	0.0	21.3			189.2	189.3	-5.33	-5.26	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24049	9/28/2026 2:11:38 PM	8.0	78.8	0.0	13.2			187.9	187.8	-4.47	-4.46	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24053	9/8/2026 7:40:00 AM					58						AirTech Lab
CV-24053	9/8/2026 7:40:00 AM						8800					AirTech Lab; [User entered 0.88%]
CV-24053	9/14/2026 10:03:36 AM	31.7	46.1	0.0	22.2			106.3	106.7	-7.56	-6.96	,
CV-24053	9/23/2026 1:26:37 PM	28.6	49.0	0.2	22.2			118.6	119.2	-8.20	-7.30	Valve Adjustment:Decreased Flow/Vacuum
CV-24055	9/10/2026 9:25:00 AM					1400						AirTech Lab
CV-24055	9/10/2026 9:25:00 AM						85000					AirTech Lab; [User entered 8.5%]
CV-24055	9/14/2026 9:36:06 AM	4.9	55.9	3.0	36.2			122.0	122.3	-0.89	-0.88	,
CV-24055	9/30/2026 8:16:47 AM	4.6	41.3	5.3	48.8			151.0	151.0	-1.29	-1.28	Valve Adjustment:NSPS/EG CAI,High Temp,High O2;Well Condition:Lorentz Pump Installed
CV-24055	9/30/2026 8:17:55 AM	4.5	41.9	5.1	48.5			151.0	151.0	-1.27	-1.27	
CV-24062	9/1/2026 2:14:11 PM	35.7	64.2	0.0	0.1			175.4	175.7	-4.89	-4.89	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24062	9/1/2026 2:15:00 PM					942.5						AtmAA
CV-24062	9/1/2026 2:15:00 PM						102100					AtmAA; [User entered 10.21%]
CV-24062	9/3/2026 7:20:00 AM					840						AirTech Lab
CV-24062	9/3/2026 7:20:00 AM						110000					AirTech Lab; [User entered 11%]
CV-24062	9/10/2026 8:48:00 AM					1200						AtmAA
CV-24062	9/16/2026 10:09:38 AM	29.5	65.0	0.0	5.5			173.3	173.7	-3.86	-3.78	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24062	9/23/2026 10:16:47 AM	40.6	59.4	0.0	0.0			178.3	178.8	-9.64	-9.56	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24062	9/30/2026 9:17:26 AM	19.7	75.5	0.0	4.8			170.1	170.4	-9.06	-9.06	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24063	9/1/2026 2:00:39 PM	8.4	79.6	0.0	12.0			186.3	186.3	-4.86	-4.53	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24063	9/1/2026 2:05:00 PM					1970						AtmAA
CV-24063	9/1/2026 2:05:00 PM						96900					AtmAA; [User entered 9.69%]
CV-24063	9/3/2026 7:20:00 AM					1400						AirTech Lab
CV-24063	9/3/2026 7:20:00 AM						110000					AirTech Lab; [User entered 11%]
CV-24063	9/10/2026 8:38:00 AM					1230						AtmAA
CV-24063	9/10/2026 8:38:14 AM	17.9	79.7	0.0	2.4			188.1	185.2	9.05	-3.06	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24063	9/10/2026 8:39:09 AM	17.9	76.6	0.0	5.5			184.9	184.7	-3.25	-3.27	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24063	9/14/2026 2:32:38 PM	11.5	76.5	0.0	12.0			183.6	183.7	-1.34	-1.21	Valve Comment:Installed new flow device well head;Valve Adjustment:Orifice Plate Changed (See OP Log),Valve 100% Open
CV-24063	9/15/2026 10:47:20 AM	11.5	74.0	0.0	14.5			183.9	184.0	-3.66	-3.66	
CV-24063	9/17/2026 12:22:16 PM	9.6	75.9	0.0	14.5					-4.20	-4.22	
CV-24063	9/17/2026 1:33:24 PM	21.7	70.2	0.0	8.1			167.8	167.7	-3.30	-3.27	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24063	9/23/2026 10:11:45 AM	32.2	67.7	0.0	0.1			167.4	167.5	-6.71	-6.44	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24063	9/30/2026 9:08:35 AM	24.7	75.3	0.0	0.0			133.5	133.1	-5.16	-5.14	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24064-PLR	9/1/2026 1:18:43 PM	37.6	58.3	0.0	4.1			191.4	191.5	-12.71	-12.97	Valve Adjustment:No Flow Measurement,High Temp

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24064-PLR	9/1/2026 1:25:00 PM					2350						AtmAA
CV-24064-PLR	9/1/2026 1:25:00 PM						121100					AtmAA; [User entered 12.11%]
CV-24064-PLR	9/3/2026 7:30:00 AM					1600						AirTech Lab
CV-24064-PLR	9/3/2026 7:30:00 AM						140000					AirTech Lab; [User entered 14%]
CV-24064-PLR	9/9/2026 1:28:11 PM	47.8	52.2	0.0	0.0			191.7	192.6	-6.37	-5.83	Valve Adjustment:No Flow Measurement,High Temp
CV-24064-PLR	9/9/2026 1:32:00 PM					1940						AtmAA
CV-24064-PLR	9/10/2026 8:45:01 AM	18.7	75.7	0.0	5.6			175.2	175.6	-5.39	-5.10	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24064-PLR	9/16/2026 9:05:32 AM	35.8	64.2	0.0	0.0			190.2	191.1	-3.71	-3.34	Valve Adjustment:No Flow Measurement,High Temp
CV-24064-PLR	9/23/2026 9:22:59 AM	46.5	53.5	0.0	0.0			188.2	189.7	-11.55	-11.46	Valve Adjustment:No Flow Measurement,High Temp
CV-24064-PLR	9/30/2026 8:38:49 AM	37.9	56.7	0.0	5.4			188.1	188.5	-9.75	-9.65	Valve Adjustment:No Flow Measurement,High Temp
CV-24065-TP1	9/3/2026 8:57:02 AM	12.8	53.4	2.0	31.8			113.3	113.3	-4.29	-3.61	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24065-TP1	9/8/2026 7:50:00 AM					290						AirTech Lab
CV-24065-TP1	9/8/2026 7:50:00 AM						15000					AirTech Lab; [User entered 1.5%]
CV-24065-TP1	9/22/2026 10:39:59 AM	14.0	42.9	0.9	42.2			126.3	126.5	-5.40	-4.94	Valve Adjustment:Decreased Flow/Vacuum
CV-24066	9/1/2026 9:11:21 AM	21.0	41.6	0.1	37.3			89.1	89.3	-1.60	-1.58	,
CV-24066	9/10/2026 8:15:00 AM					250						AirTech Lab
CV-24066	9/10/2026 8:15:00 AM						23000					AirTech Lab; [User entered 2.3%]
CV-24066	9/22/2026 11:00:28 AM	16.9	44.9	0.0	38.2			102.6	103.9	-1.50	-1.52	,
CV-24066	9/24/2026 2:36:50 PM	18.0	42.6	0.0	39.4			123.0	122.8	-1.48	-1.48	Valve Adjustment:Barely Open
CV-24069	9/2/2026 8:53:53 AM	21.7	49.7	0.1	28.5			117.5	116.7	-1.22	-1.22	Valve Adjustment:Barely Open
CV-24069	9/8/2026 7:00:00 AM					580						AirTech Lab
CV-24069	9/8/2026 7:00:00 AM						64000					AirTech Lab; [User entered 6.4%]
CV-24069	9/28/2026 10:46:59 AM	11.9	44.8	0.2	43.1			126.3	126.4	-1.48	-1.49	Valve Adjustment:Barely Open
CV-24070	9/2/2026 8:55:00 AM					1590						AtmAA
CV-24070	9/2/2026 8:55:00 AM						64200					AtmAA; [User entered 6.42%]

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24070	9/2/2026 8:55:24 AM	29.3	64.5	0.0	6.2			149.4	149.4	-2.30	-2.33	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24070	9/8/2026 7:10:00 AM					1000						AirTech Lab
CV-24070	9/8/2026 7:10:00 AM						82000					AirTech Lab; [User entered 8.2%]
CV-24070	9/9/2026 1:57:00 PM	32.2	67.7	0.1	0.0			119.1	119.1	0.69	-0.97	Valve Adjustment:Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24070	9/9/2026 1:57:46 PM	30.7	69.2	0.1	0.0			119.1	119.1	-1.05	-1.04	
CV-24070	9/10/2026 1:57:00 PM					1370						AtmAA
CV-24070	9/10/2026 1:59:57 PM	33.6	66.4	0.0	0.0			150.7	150.7	-2.40	-2.47	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24070	9/16/2026 1:30:24 PM	42.9	57.1	0.0	0.0			144.7	144.7	-3.79	-4.01	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24071	9/2/2026 9:40:06 AM	24.9	68.0	0.0	7.1			138.4	138.3	-0.53	-0.72	Valve Adjustment:High Temp,Barely Open;Well Condition:Lorentz Pump Installed
CV-24071	9/8/2026 7:15:00 AM					550						AirTech Lab
CV-24071	9/8/2026 7:15:00 AM						74000					AirTech Lab; [User entered 7.4%]
CV-24071	9/17/2026 2:19:48 PM	33.7	60.4	0.0	5.9			134.7	134.0	-3.15	-1.97	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open
CV-24075-TP1	9/1/2026 1:27:41 PM	25.5	71.0	1.0	2.5			178.5	178.4	-10.56	-10.32	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24075-TP1	9/1/2026 1:34:00 PM					1740						AtmAA
CV-24075-TP1	9/1/2026 1:34:00 PM						67500					AtmAA; [User entered 6.75%]
CV-24075-TP1	9/9/2026 1:36:18 PM	31.9	66.8	1.3	0.0			181.5	181.6	-6.76	-6.40	Valve Adjustment:Other - See Daily Log,High Temp;Well Condition:Lorentz Pump Installed
CV-24075-TP1	9/9/2026 1:41:00 PM					2030						AtmAA
CV-24075-TP1	9/16/2026 9:26:05 AM	10.8	82.6	0.0	6.6			182.3	182.3	-4.13	-4.11	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24075-TP1	9/23/2026 9:31:50 AM	37.0	62.2	0.8	0.0			181.4	181.5	-11.74	-11.50	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24075-TP1	9/30/2026 8:50:15 AM	27.7	66.7	1.3	4.3			179.1	179.2	-10.45	-10.45	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24077	9/1/2026 9:39:47 AM	22.7	57.4	0.0	19.9			143.9	140.9	-3.28	-3.34	NSPS/EG CAI,High Temp
CV-24077	9/1/2026 11:02:58 AM	21.6	66.2	0.0	12.2			136.0	136.1	-3.57	-3.57	NSPS/EG CAI,High Temp
CV-24077	9/1/2026 2:25:00 PM					1330						AtmAA
CV-24077	9/1/2026 2:25:00 PM						40000					AtmAA; [User entered 4%]
CV-24077	9/1/2026 2:29:54 PM	26.5	69.3	0.0	4.2			154.1	153.7	-3.11	-3.11	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24077	9/8/2026 10:33:07 AM	13.8	68.9	0.0	17.3			157.3	157.6	-1.79	-1.81	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-24077	9/8/2026 10:35:00 AM					1800						AtmAA
CV-24077	9/14/2026 9:40:00 AM					1290						AtmAA
CV-24077	9/14/2026 9:41:46 AM	15.5	60.1	0.0	24.4			157.7	157.8	-3.28	-3.34	Valve Adjustment:No Adjustments Made;Well Comment:lorentz pump installed
CV-24077	9/14/2026 10:22:00 AM	14.6	65.1	0.0	20.3			157.5	157.3	-3.03	-2.95	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24077	9/22/2026 12:59:33 PM	11.5	75.8	0.0	12.7			154.3	154.5	-3.37	-3.38	NSPS/EG CAI,High Temp
CV-24077	9/22/2026 1:00:24 PM	12.5	78.5	0.0	9.0			155.1	155.1	-3.33	-3.33	NSPS/EG CAI,High Temp
CV-24077	9/23/2026 1:52:12 PM	25.8	60.5	0.0	13.7			156.0	156.2	-3.53	-3.53	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24077	9/30/2026 1:57:09 PM	24.7	63.6	0.0	11.7			156.0	156.0	-3.20	-3.15	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24079-TP8	9/1/2026 10:56:25 AM	0.8	83.0	0.0	16.2			94.4	94.4	-0.50	-0.48	,
CV-24079-TP8	9/21/2026 11:00:53 AM	18.8	68.1	0.1	13.0			170.4	169.1	-2.37	-1.20	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24079-TP8	9/21/2026 11:03:19 AM	8.1	76.6	0.1	15.2			169.1	170.4	-1.08	-1.10	
CV-24079-TP8	9/28/2026 10:34:01 AM	19.0	75.6	0.0	5.4			166.5	166.1	-1.73	-1.75	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24079-TP8	9/30/2026 9:17:09 AM	20.2	64.4	0.0	15.4			162.3	163.3	-2.12	-2.11	Valve Adjustment:No Flow Measurement,High Temp

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24082	9/2/2026 9:30:43 AM	43.2	54.8	0.0	2.0			122.8	122.5	-6.42	-5.74	Valve Adjustment:Decreased Flow/Vacuum
CV-24082	9/17/2026 1:53:48 PM	43.3	53.8	0.0	2.9			126.1	125.2	-4.92	-3.79	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24083	9/2/2026 8:49:34 AM	30.6	66.2	0.0	3.2			157.9	158.8	-2.59	-2.56	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24083	9/2/2026 8:50:00 AM					1430						AtmAA
CV-24083	9/2/2026 8:50:00 AM						76700					AtmAA; [User entered 7.67%]
CV-24083	9/8/2026 10:18:45 AM	19.3	68.8	0.1	11.8			152.8	153.8	-0.46	-0.44	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-24083	9/8/2026 10:20:00 AM					1360						AtmAA
CV-24083	9/17/2026 1:55:13 PM	40.8	59.2	0.0	0.0			154.0	152.8	-2.29	-2.23	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24083	9/23/2026 1:23:41 PM	7.6	74.2	0.0	18.2			149.5	148.0	-7.12	-7.08	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24083	9/30/2026 10:01:53 AM	39.9	60.1	0.0	0.0			137.8	138.2	-9.44	-9.38	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24084-TP1	9/2/2026 8:41:51 AM	28.3	71.2	0.0	0.5			185.2	185.4	-7.28	-6.82	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24084-TP1	9/2/2026 8:45:00 AM					2215						AtmAA
CV-24084-TP1	9/2/2026 8:45:00 AM						106300					AtmAA; [User entered 10.63%]
CV-24084-TP1	9/8/2026 10:20:41 AM	2.3	80.9	0.0	16.8			187.2	187.4	-4.28	-3.40	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-24084-TP1	9/8/2026 10:25:00 AM					3620						AtmAA
CV-24084-TP1	9/17/2026 1:59:08 PM	39.8	60.2	0.0	0.0			186.2	186.0	-5.27	-4.79	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24084-TP1	9/23/2026 1:16:20 PM	7.0	79.8	0.0	13.2			186.1	186.3	-4.81	-4.46	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24084-TP1	9/30/2026 9:57:04 AM	8.2	79.0	0.0	12.8			185.3	185.2	-8.02	-7.08	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24088	9/2/2026 1:21:22 PM	47.4	52.6	0.0	0.0			112.6	113.1	-2.03	-2.03	Valve Adjustment:Barely Open
CV-24088	9/17/2026 3:03:53 PM	44.8	51.9	0.1	3.2			104.5	104.8	-2.43	-2.40	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24095	9/1/2026 1:57:31 PM	5.3	71.6	0.0	23.1			186.0	186.2	-2.41	-2.42	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24095	9/1/2026 2:00:00 PM					2620						AtmAA
CV-24095	9/1/2026 2:00:00 PM						159300					AtmAA; [User entered 15.93%]
CV-24095	9/8/2026 1:30:00 PM					2940						AtmAA
CV-24095	9/8/2026 1:31:41 PM	7.6	78.1	0.1	14.2			191.3	191.3	-1.91	-1.95	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-24095	9/10/2026 8:30:00 AM					2200						AirTech Lab
CV-24095	9/10/2026 8:30:00 AM						180000					AirTech Lab; [User entered 18%]
CV-24095	9/17/2026 9:42:47 AM	11.4	79.9	0.0	8.7			192.0	192.1	-5.15	-5.10	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24095	9/24/2026 9:52:08 AM	12.9	68.7	0.0	18.4			191.8	191.6	-7.41	-7.41	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24096	9/2/2026 8:14:01 AM	32.6	53.7	2.6	11.1			65.8	65.8	-2.39	-2.37	,
CV-24096	9/23/2026 9:26:01 AM	30.5	40.7	4.5	24.3			87.7	88.4	-5.61	-5.44	Valve Adjustment:Decreased Flow/Vacuum
CV-24097	9/2/2026 8:18:03 AM	50.5	44.4	0.4	4.7			66.2	66.2	-3.21	-3.23	Reduced System Vacuum,
CV-24097	9/30/2026 3:17:38 PM	41.6	40.3	0.0	18.1			99.3	99.4	2.75	0.67	Valve Adjustment:Positive Static Press.,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24098	9/2/2026 8:23:38 AM	43.7	51.6	0.3	4.4			72.3	72.3	-7.95	-7.38	Reduced System Vacuum,
CV-24098	9/23/2026 9:16:20 AM	43.9	48.5	1.3	6.3			88.4	89.4	-11.66	-11.49	Well Comment:Valve stuck open
CV-24099	9/2/2026 8:32:12 AM	23.3	50.2	4.6	21.9			67.0	66.4	-7.76	-7.91	Reduced System Vacuum,

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24099	9/23/2026 9:11:30 AM	0.0	4.8	19.5	75.7			79.8	80.5	-11.20	-11.53	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected;Well Comment:Valve stuck open
CV-24099	9/23/2026 9:13:00 AM	0.1	2.0	19.9	78.0			81.1	81.2	-10.68	-11.35	Valve Adjustment:High O2,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected;Well Comment:Valve stuck open
CV-24100	9/2/2026 8:50:27 AM	44.1	52.5	0.3	3.1			97.3	97.3	-8.85	-8.87	,
CV-24100	9/2/2026 1:05:00 PM					144						AtmAA
CV-24100	9/2/2026 1:05:00 PM						5600					AtmAA; [User entered 0.56%]
CV-24100	9/2/2026 1:12:10 PM	33.8	66.2	0.0	0.0			151.7	153.7	0.52	-2.38	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24100	9/2/2026 1:16:31 PM	33.4	66.6	0.0	0.0			152.1	152.6	-2.41	-2.42	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24100	9/8/2026 7:35:00 AM					38						AirTech Lab
CV-24100	9/8/2026 7:35:00 AM						6300					AirTech Lab; [User entered 0.63%]
CV-24100	9/8/2026 2:53:01 PM	29.5	70.4	0.1	0.0			147.6	148.4	-1.51	-1.48	NSPS/EG CAI,High Temp
CV-24100	9/8/2026 2:55:00 PM					192						AtmAA
CV-24100	9/17/2026 2:19:56 PM	35.9	64.1	0.0	0.0			148.6	148.5	-8.62	-8.47	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24100	9/17/2026 2:21:00 PM	35.6	64.4	0.0	0.0			148.7	149.0	-9.31	-8.93	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24100	9/24/2026 10:19:50 AM	29.3	70.3	0.3	0.1			142.1	133.8	-12.64	-12.13	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24100	9/28/2026 1:58:23 PM	17.4	80.9	1.1	0.6			122.3	125.7	-12.00	-5.25	Valve Adjustment:No Flow Measurement,Decreased Flow/Vacuum
CV-24101	9/8/2026 7:30:00 AM					0						AirTech Lab
CV-24101	9/8/2026 7:30:00 AM						1200					AirTech Lab; [User entered 0.12%]

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24101	9/8/2026 2:50:19 PM		47.9	1.9				109.7	109.9	-7.19	-7.18	Reduced System Vacuum,
CV-24101	9/28/2026 1:59:13 PM	17.6	80.4	0.5	1.5			127.9	128.1	-6.06	-5.97	
CV-24102	9/2/2026 9:21:46 AM	43.1	47.1	0.0	9.8			101.0	101.1	-2.00	-1.95	,
CV-24102	9/22/2026 12:22:15 PM	40.3	52.4	0.0	7.3			101.9	101.7	-0.44	-0.40	,
CV-24120	9/9/2026 8:10:00 AM					680						AirTech Lab
CV-24120	9/9/2026 8:10:00 AM						42000					AirTech Lab; [User entered 4.2%]
CV-24120	9/14/2026 10:25:29 AM	3.3	39.8	10.8	46.1			97.7	97.7	-6.64	-3.05	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In)
CV-24120	9/14/2026 10:27:15 AM	2.5	29.5	12.9	55.1			97.7	97.7	-4.09	-4.04	
CV-24120	9/25/2026 10:26:04 AM	1.7	18.2	15.1	65.0			92.2	92.0	-4.70	-4.28	Valve Adjustment:Decreased Flow/Vacuum
CV-24120	9/28/2026 9:41:44 AM	7.8	92.2	0.0	0.0			89.4	84.7	4.93	-1.78	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open
CV-24120	9/28/2026 9:50:35 AM	6.9	89.6	0.9	2.6			91.6	91.5	-6.03	-6.00	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-24121	9/3/2026 9:37:51 AM	23.6	52.8	2.6	21.1			99.9	125.5	120.52	-1.09	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
CV-24121	9/3/2026 9:43:25 AM	31.6	51.2	3.6	13.7			125.7	125.5	-1.67	-1.70	Valve Adjustment:NSPS/EG CAC
CV-24121	9/10/2026 9:45:00 AM					25						AirTech Lab
CV-24121	9/10/2026 9:45:00 AM						1600					AirTech Lab; [User entered 0.16%]
CV-24121	9/25/2026 10:30:06 AM	31.7	67.5	0.0	0.8			127.2	127.4	-7.31	-5.47	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24122	9/8/2026 8:20:00 AM					200						AirTech Lab
CV-24122	9/8/2026 8:20:00 AM						15000					AirTech Lab; [User entered 1.5%]
CV-24122	9/15/2026 7:57:25 AM	27.9	24.0	10.3	37.8			67.3	67.4	-7.11	-7.11	Valve Adjustment:NSPS/EG CAI,High O2
CV-24122	9/15/2026 7:58:33 AM	27.9	24.0	10.3	37.8			67.5	67.5	-7.05	-7.39	

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24122	9/25/2026 10:38:50 AM	32.8	27.6	7.3	32.3			99.6	100.1	-4.96	-5.06	Valve Adjustment:High O2,Opened for Sample,Increased Flow/Vacuum,Plugged/Pinched Suspected
CV-24123	9/3/2026 9:17:50 AM	45.4	50.6	0.0	3.9			117.1	117.3	-3.49	-3.67	Valve Adjustment:Increased Flow/Vacuum
CV-24123	9/11/2026 3:37:45 PM	50.5	49.5	0.0	0.0			117.0		-3.32	-3.47	Valve Adjustment:Increased Flow/Vacuum
CV-24123	9/11/2026 3:38:20 PM	50.9	49.1	0.0	0.0			117.0		-3.52	-3.53	
CV-24123	9/23/2026 8:27:33 AM	46.6	49.4	0.0	4.0			117.0	116.6	-6.11	-5.29	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-24125-TP2	9/9/2026 8:20:00 AM					0						AirTech Lab
CV-24125-TP2	9/9/2026 8:20:00 AM						1400					AirTech Lab; [User entered 0.14%]
CV-24125-TP2	9/14/2026 9:25:49 AM	37.6	48.1	1.5	12.8			124.2	121.4	-8.02	-4.23	Valve Adjustment:Decreased Flow/Vacuum
CV-24125-TP2	9/29/2026 8:05:16 AM	44.1	51.3	0.0	4.6			90.0	89.9	-6.08	-6.08	Well Condition:Pnumatic Pump Installed
CV-24126	9/8/2026 2:01:24 PM	15.0	63.4	0.0	21.6			189.3	189.4	-2.35	-2.34	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24126	9/8/2026 2:04:00 PM					3490						AtmAA
CV-24126	9/14/2026 1:36:52 PM	16.3	40.1	2.3	41.3			177.6	177.7	-3.54	-3.14	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24126	9/14/2026 1:40:00 PM					1340						AtmAA
CV-24126	9/21/2026 1:17:21 PM	19.1	34.2	3.2	43.5			174.2	174.1	-4.85	-4.87	Valve Adjustment:No Flow Measurement,High Temp
CV-24126	9/28/2026 1:36:03 PM	13.4	35.4	2.7	48.5			174.0	174.2	-5.83	-5.39	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24127	9/8/2026 8:00:00 AM					2600						AirTech Lab
CV-24127	9/8/2026 8:00:00 AM						180000					AirTech Lab; [User entered 18%]
CV-24127	9/8/2026 2:06:28 PM	8.9	69.4	0.0	21.7			177.2	177.2	-2.91	-2.77	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24127	9/8/2026 2:09:00 PM					3930						AtmAA
CV-24127	9/14/2026 1:33:01 PM	28.2	67.5	0.0	4.3			160.3	160.3	-3.99	-3.92	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24127	9/14/2026 1:36:00 PM					1620						AtmAA
CV-24127	9/21/2026 1:12:42 PM	34.5	65.5	0.0	0.0			164.0	164.3	-4.83	-4.80	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24127	9/28/2026 1:25:09 PM	26.7	40.6	0.5	32.2			151.6	151.4	-6.07	-6.07	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24128	9/9/2026 12:13:22 PM	23.5	70.8	0.3	5.4			145.6	123.0	-0.61	-0.59	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-24128	9/9/2026 12:14:49 PM	24.0	69.7	0.3	6.0			122.3	122.3	-0.50	-0.51	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-24128	9/10/2026 9:35:00 AM					2700						AirTech Lab
CV-24128	9/10/2026 9:35:00 AM						110000					AirTech Lab; [User entered 11%]
CV-24128	9/25/2026 9:55:31 AM	23.1	58.8	0.3	17.8			127.8	127.8	-1.07	-1.10	Valve Adjustment:Barely Open
CV-24134-TP1	9/10/2026 1:06:47 PM	21.9	70.2	0.1	7.8			153.2	153.0	-1.75	-1.78	Valve Adjustment:High Temp,Barely Open
CV-24134-TP1	9/14/2026 1:29:38 PM	25.7	68.2	0.0	6.1			152.3	152.0	-2.57	-2.55	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24134-TP1	9/14/2026 1:32:00 PM					2890						AtmAA
CV-24134-TP1	9/21/2026 1:09:25 PM	36.4	63.5	0.0	0.1			151.7	152.2	-2.66	-2.63	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24134-TP1	9/28/2026 1:06:51 PM	25.8	69.5	0.0	4.7			150.0	150.1	-0.91	-0.89	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24138	9/2/2026 7:35:00 AM					160						AirTech Lab
CV-24138	9/2/2026 7:35:00 AM						25000					AirTech Lab; [User entered 2.5%]
CV-24138	9/2/2026 7:58:13 AM	0.5	10.2	17.4	71.9			65.6	65.5	-3.91	-3.90	NSPS/EG CAI,High O2
CV-24138	9/2/2026 7:59:07 AM	0.5	10.2	17.3	72.0			65.3	65.3	-4.08	-4.07	NSPS/EG CAI,High O2
CV-24138	9/30/2026 2:54:56 PM	2.3	72.3	0.2	25.2			162.2	161.4	-4.34	-4.38	Valve Adjustment:High Temp,Barely Open
CV-24139	9/1/2026 1:45:00 PM					1070						AtmAA
CV-24139	9/1/2026 1:45:00 PM						180100					AtmAA; [User entered 18.01%]
CV-24139	9/1/2026 1:48:41 PM	5.5	70.8	0.4	23.3			145.4	145.4	-5.52	-5.53	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24139	9/2/2026 7:30:00 AM					720						AirTech Lab
CV-24139	9/2/2026 7:30:00 AM						210000					AirTech Lab; [User entered 21%]
CV-24139	9/8/2026 1:22:11 PM	8.7	58.3	4.3	28.7			110.5	110.5	-5.34	-4.90	NSPS/EG CAC,Reduced System Vacuum
CV-24139	9/10/2026 2:55:48 PM	1.9	2.1	20.3	75.7			132.1	129.5	-4.74	-2.49	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-24139	9/10/2026 3:13:23 PM	9.3	16.2	15.6	58.9			127.2	125.3	-1.12	-1.10	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-24139	9/10/2026 3:15:24 PM	8.9	18.3	15.0	57.8			125.4	125.4	-0.67	-0.67	Valve Adjustment:No Flow Measurement;Well Condition:Pnumatic Pump Installed
CV-24139	9/30/2026 2:51:42 PM	4.2	53.0	7.8	35.0			128.4	129.2	-7.90	-7.71	Valve Adjustment:High O2,Barely Open
CV-24140	9/1/2026 1:40:00 PM					2160						AtmAA
CV-24140	9/1/2026 1:40:00 PM						182800					AtmAA; [User entered 18.28%]
CV-24140	9/1/2026 1:44:48 PM	3.8	74.8	0.0	21.4			164.0	164.0	-4.96	-4.94	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24140	9/2/2026 7:25:00 AM					1400						AirTech Lab
CV-24140	9/2/2026 7:25:00 AM						210000					AirTech Lab; [User entered 21%]
CV-24140	9/8/2026 1:16:52 PM	3.4	73.7	0.6	22.3			165.9	166.0	-4.55	-4.56	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-24140	9/8/2026 1:20:00 PM					2140						AtmAA
CV-24140	9/17/2026 9:53:55 AM	7.1	72.3	0.3	20.3			154.7	153.3	-8.42	-8.13	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24140	9/24/2026 9:42:13 AM	7.8	72.8	0.3	19.1			145.3	145.5	-9.47	-9.32	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24141	9/2/2026 7:10:00 AM					26						AirTech Lab
CV-24141	9/2/2026 7:10:00 AM						1900					AirTech Lab; [User entered 0.19%]

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24141	9/15/2026 9:57:58 AM	2.1	6.4	17.6	73.9			90.4	91.6	-4.95	-5.12	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In)
CV-24141	9/15/2026 9:59:24 AM	2.1	5.6	17.7	74.6			92.2	92.1	-5.25	-5.27	
CV-24141	9/23/2026 9:57:06 AM	0.9	6.1	18.4	74.6			95.9	94.6	-7.13	-3.58	Valve Adjustment:High O2,Decreased Flow/Vacuum,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-24142	9/1/2026 1:54:21 PM	4.0	65.9	2.7	27.4			128.0	128.2	-1.61	-1.61	Valve Adjustment:No Flow Measurement;Well Condition:Pnumatic Pump Installed
CV-24142	9/2/2026 7:40:00 AM					1200						AirTech Lab
CV-24142	9/2/2026 7:40:00 AM						170000					AirTech Lab; [User entered 17%]
CV-24142	9/30/2026 2:58:57 PM	1.6	52.9	7.2	38.3			130.5	130.5	-3.40	-3.42	Valve Adjustment:High O2
CV-24143	9/1/2026 7:40:00 AM					660						Air Tech Lab
CV-24143	9/1/2026 7:40:00 AM						94000					Air Tech Lab; [User entered 9.4%]
CV-24143	9/10/2026 12:19:01 PM	4.8	62.0	5.2	28.0			125.2	124.2	-1.95	-2.19	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:No pump
CV-24143	9/10/2026 12:20:07 PM	3.9	61.0	5.3	29.8			123.9	124.1	-2.23	-1.93	
CV-24143	9/23/2026 9:50:14 AM	1.7	71.2	2.9	24.2			100.3	100.4	-7.99	-4.25	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-24144	9/2/2026 8:20:25 AM	55.9	41.0	0.0	3.1			68.7	68.8	-0.90	-0.86	Reduced System Vacuum,
CV-99	9/4/2026 7:05:00 AM					900						AirTech Lab
CV-99	9/4/2026 7:05:00 AM						64000					AirTech Lab; [User entered 6.4%]
CV-99	9/14/2026 9:15:48 AM	3.0	6.5	17.8	72.7			85.9	86.7	-9.69	-10.08	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In)
CV-99	9/14/2026 9:19:46 AM	31.6	48.3	3.5	16.6			88.0	88.3	-2.53	-2.53	Valve Adjustment:NSPS/EG CAC
CV-99	9/25/2026 10:42:18 AM	40.9	54.1	0.3	4.7			105.0	98.8	-0.47	-0.67	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
H-1770N	9/1/2026 11:22:05 AM	29.2	63.7	0.0	7.1			105.0	105.2	-1.01	-0.93	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
H-1770N	9/10/2026 9:10:00 AM					320						AirTech Lab
H-1770N	9/10/2026 9:10:00 AM						23000					AirTech Lab; [User entered 2.3%]
H-1770N	9/16/2026 2:50:15 PM	27.2	65.6	0.2	7.0			97.3	97.4	-1.43	-1.44	Valve Adjustment:Barely Open
H-2165W	9/2/2026 8:43:14 AM	31.1	65.0	0.1	3.8			139.4	136.6	-0.88	-0.31	Reduced System Vacuum,
H-2165W	9/2/2026 8:45:08 AM	14.3	76.0	0.0	9.7			135.9	137.6	-0.10	-0.09	NSPS/EG CAI,High Temp,Reduced System Vacuum
H-2165W	9/9/2026 7:00:00 AM					680						AirTech Lab
H-2165W	9/9/2026 7:00:00 AM						51000					AirTech Lab; [User entered 5.1%]
H-2165W	9/23/2026 8:49:44 AM	8.9	88.0	0.0	3.1			147.2	147.2	-0.90	-0.92	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-2165W	9/30/2026 10:38:31 AM	10.1	73.5	0.0	16.4			148.0	146.0	-0.25	-1.32	Valve Adjustment:High Temp,Increased Flow/Vacuum
H-2165W	9/30/2026 10:39:18 AM	19.4	75.3	0.0	5.3			144.9	145.2	-1.47	-1.42	Valve Adjustment:High Temp
H-2273W	9/2/2026 7:21:33 AM	21.3	40.8	0.0	37.9			120.7	120.7	-0.91	-0.70	Reduced System Vacuum,
H-2273W	9/4/2026 8:32:00 AM					160						AirTech Lab
H-2273W	9/4/2026 8:32:00 AM						18000					AirTech Lab; [User entered 1.8%]
H-2273W	9/9/2026 7:10:00 AM					78						AirTech Lab
H-2273W	9/9/2026 7:10:00 AM						10000					AirTech Lab; [User entered 1.0%]
H-2273W	9/22/2026 12:09:18 PM	31.8	42.0	0.0	26.2			123.2	123.0	-0.30	-0.26	,

Attachment B

Down Well Temperatures

And

List of Wells for Monitoring

LEA Selected Wells for Down Hole Temperature Monitoring
September 2026

Well Number	Down Well Temp Monitoring Monthly	Last Date Monitored for Downwell Temperatures - 2025	2026 Downwell Temperature Monitoring Date	Comments
CV-100	NA	NA	NA	Abandoned Well
CV-103	NA	3/3/2025	NA	Abandoned Well
CV-108-52	Yes	3/4/2025	3/2/2026 and 7/6/2026	
CV-113	Yes	3/10/2025	3/2/2026	
CV-1532	NA	NA	NA	Abandoned Well
CV-1532A	Yes	3/10/2025	2/6/2026 , 3/25/2026 and 6/17/2026	
CV-1535	Yes	3/4/2025	3/2/2026 and 7/6/2026	
CV-1902A	Yes	3/18/2025	2/6/2026, 3/2/2026 and 6/12/2026	
CV-2001	Yes	3/4/2025	3/3/2026 and 6/24/2026	
CV-2002	Yes	6/2/2025	3/4/2026 and 7/6/2026	
CV-2007	Yes	3/5/2025	3/4/2026	
CV-2202	NA	NA	NA	Abandoned Well
CV-2301	Yes	3/11/2025	2/6/2026, 3/5/2026 and 6/12/2026	Lorentz pump removed, no graph possible
CV-2302	Yes	3/11/2025	6/25/2026	Graph Attached 8-1 to 8-31-2026
CV-2303	Yes	3/11/2025	9/29/2026	Graph Attached 8-1 to 8-31-2026
CV-2312	Yes	3/5/2025	TBD - Pump Installed	
CV-2315	Yes	3/19/2025	6/25/2026	Pump Offline
CV-2341	Yes	3/5/2025	TBD - Pump Installed	


LEA Selected Wells for Down Hole Temperature Monitoring
September 2026


Well Number	Down Well Temp Monitoring Monthly	Last Date Monitored for Downwell Temperatures - 2025	2026 Downwell Temperature Monitoring Date	Comments
CV-2350	Yes	3/12/2025	TBD - Pump Installed	Lorentz pump is damaged and unable to be removed for repairs, no graphing possible.
CV-2351	Yes	3/12/2025	3/10/2026	
CV-2352	Yes	3/12/2025	4/24/2026 and 4/30/2026	Lorentz pump removed, no graph possible
CV-2353	Yes	5/30/2025	3/10/2026, 4/30/2026 and 6/12/2026	
CV-24007	Yes	3/6/2025	3/10/2026 and 6/12/2026	
CV-24017	Yes	3/6/2025	7/21/2026	Graph Attached 8-1 to 8-31-2026
CV-24053	Yes	3/6/2025	TBD - Pump Installed	
CV-24065	Yes	3/6/2025	7/16/2026	Graph Attached 8-1 to 8-31-2026
CV-24095	Yes	3/7/2025	TBD - Pump Installed	Graph Attached 8-1 to 8-31-2026
CV-24101	Yes	3/7/2025	7/1/2026	
CV-24122	Yes	3/7/2025	3/10/2026	
CV-24127	Yes	3/7/2025	3/10/2026	
CV-24138	Yes	4/1/2025	8/6/2026	
CV-24139	Yes	8/18/2025	8/6/2026	
CV-24143	Yes	3/10/2025	6/12/2026	


Liquid Data Report
Date Range: 09/01/2026 to 09/30/2026


Report Date: 10/02/2026
Site Name: Chiquita Canyon Landfill

Point Name	Record Date	Pump Installed	Pump Status	Liquid Comments	Temp (F) @ 0 FT from BOW	Temp (F) @ 10 FT from BOW	Temp (F) @ 20 FT from BOW	Temp (F) @ 30 FT from BOW	Temp (F) @ 40 FT from BOW	Temp (F) @ 50 FT from BOW	Temp (F) @ 60 FT from BOW	Temp (F) @ 70 FT from BOW	Temp (F) @ 80 FT from BOW	Temp (F) @ 90 FT from BOW	Temp (F) @ 100 FT from BOW
CV-2303	9/29/2026 2:32:26 PM	Y	Online	91.00°C:BOW;94.00°C:10ft;89.00°C:20ft;89.00°C:30ft;89.00°C:40ft;90.00°C:50ft;90.00°C:60ft;90.00°C:70ft;90.00°C:80ft;90.00°C:90ft;90.00°C:100ft	195.80	201.20	192.20	192.20	192.20	194.00	194.00	194.00	194.00	194.00	194.00



14 Sep 2026 17:25 (UTC -7)
Temp. Sensor [Analog 1]: 169.6 °F
CV-2302
September 2, 2026
September 4, 2026
September 6, 2026
September 8, 2026
September 10, 2026
September 12, 2026
September 14, 2026
September 16, 2026
September 18, 2026
September 20, 2026
September 22, 2026
September 24, 2026
September 26, 2026
September 28, 2026
September 30, 2026


CV-2303
25 Sep 2026 08:30 (UTC -7)
Temperature sensor [Analog 1]: 209 °F
September 2, 2026
September 4, 2026
September 6, 2026
September 8, 2026
September 10, 2026
September 12, 2026
September 14, 2026
September 16, 2026
September 18, 2026
September 20, 2026
September 22, 2026
September 24, 2026
September 26, 2026
September 28, 2026
September 30, 2026


19 Sep 2026 21:21 (UTC -7)
Lorentz Temp. Sensor [Analog 1]: 142.9 °F
CV-24065
September 2, 2026
September 4, 2026
September 6, 2026
September 8, 2026
September 10, 2026
September 12, 2026
September 14, 2026
September 16, 2026
September 18, 2026
September 20, 2026
September 22, 2026
September 24, 2026
September 26, 2026
September 28, 2026
September 30, 2026



17 Sep 2026 19:14 (UTC -7)
Lorentz Temp. Sensor [Analog 1]: 184.9 °F

Events:
CV-24095
September 2, 2026
September 4, 2026
September 6, 2026
September 8, 2026
September 10, 2026
September 12, 2026
September 14, 2026
September 16, 2026
September 18, 2026
September 20, 2026
September 22, 2026
September 24, 2026
September 26, 2026
September 28, 2026
September 30, 2026


14 Sep 2026 04:03 (UTC -7)
Temperature sensor [Analog 1]: 196.9 °F
CV-24017
September 2, 2026
September 4, 2026
September 6, 2026
September 8, 2026
September 10, 2026
September 12, 2026
September 14, 2026
September 16, 2026
September 18, 2026
September 20, 2026
September 22, 2026
September 24, 2026
September 26, 2026
September 28, 2026
September 30, 2026

Attachment C

Item 7 – Well Location Map



GENERAL DRAWING NOTES:

1. EXISTING GCCS AS-BUILT DATED OCTOBER 07, 2026.
2. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER AERIAL PHOTOGRAPHY DATED OCTOBER 7, 2026.
3. APPROXIMATED REACTION MITIGATION AREA BOUNDARY ADJUSTMENTS DATED OCTOBER 10, 2026, BASED ON SEPTEMBER 2026 DATA.
4. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.
5. THE LOCATION OF ANY EXISTING PIPING, VALVES, TIE-IN LOCATIONS AND OTHER FEATURES ARE APPROXIMATE AND SHOULD BE USED FOR INFORMATION PURPOSES ONLY. ACTUAL FIELD CONDITIONS MAY VARY AND ARE SUBJECT TO CHANGE BASED ON TOPOGRAPHIC FEATURES AND SITE-SPECIFIC FACTORS.

NO.	REVISION	DATE

SHEET TITLE: EXISTING GCCS MASTER AS-BUILT MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544


DRN. BY:	APB	ACAD FILE:	NA-CAD\ASBUILT\MASTER\S
CHK. BY:	-	APP. BY:	-
PROJ. NO.	01204123.45		
SGN. BY:	SRM / RNH		

DATE: 10/07/2026

SCALE: AS SHOWN

1 of 1

N:\CAD\ASBUILT – MASTERS\CHIQUITA\GCCS\2026 ACAD\2026-10-07_CCLF MASTER EXISTING GCCS MAP – (Fully Restored).dwg Oct 12, 2026 – 9:43am By: raulramirez



N

GRAPHIC SCALE

150 75 0 150 300 150

SCALE: 1"=150'

LEGEND

- 1150 — TOPOGRAPHIC CONTOUR
- EXISTING CELL LIMITS (APPROXIMATE)
- REACTION MITIGATION AREA BOUNDARY (APPOXIMATE, BASED ON DATA ANALYSIS)
- REACTION MITIGATION AREA BOUNDARY - CONDITION 9A
- EXISTING HORIZONTAL COLLECTOR PERFORATED PIPE
- ● H-XX EXISTING HORIZONTAL COLLECTOR
- ◆ CV-XX EXISTING VERTICAL LFG EXTRACTION WELL

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER, DATED OCTOBER 7, 2026.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.
3. THE LOCATION OF ANY EXISTING GCCS COMPONENTS AND OTHER FEATURES ARE APPROXIMATE AND SHOULD BE USED FOR INFORMATION PURPOSES ONLY.
4. APPROXIMATED REACTION MITIGATION AREA BOUNDARY ADJUSTMENTS DATED OCTOBER 9, 2026, BASED ON SEPTEMBER 2026 DATA.

DATE | REVISION | NO.

SHEET TITLE: EXISTING VERTICAL & HORIZONTAL LFG EXTRACTION WELL MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3800 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544

PROJ. NO. 01204123.45 | DSN. BY: - | DWN. BY: RR | CHK. BY: RNH | ACAD FILE: FIELD SERVICES | APP. BY: RNH

DATE: 10/09/2026


SCALE: AS SHOWN

SHEET: 1

F:\Engineers\Waste Connections\Chiquita Canyon LF\2026 LEA Correspondence\Monthly Existing Well Map\01_DWG\2026-10-09_CCLF_Existing Well Map-For LEA Response.dwg Oct 09, 2026 12:25pm By: rautramirez

Attachment D

Milestone 5 Compliance Data



Ranges Mapped

						# Points
	>=	0	and	<	25	53
	>=	25	and	<	48	28
	>=	48	and	<	52	
	>=	52	and	<	58	
	>=	58	and	<	101	
		N/A			N/A	

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill


Range Map

Parameter: CH4 (mid range)

Analysis Method: MostRecent

Date Range: 09/01/2026 - 09/30/2026

Map generation date : 10/09/2026



Ranges Mapped

						# Points
	>=	0	and	<	25	5
	>=	25	and	<	45	14
	>=	45	and	<	55	18
	>=	55	and	<	65	9
	>=	65	and	<	101	35
		N/A			N/A	

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill


Range Map

Parameter: CO2 (mid range)

Analysis Method: MostRecent

Date Range: 09/01/2026 - 09/30/2026

Map generation date : 10/09/2026



Ranges Mapped

						# Points
	>=	0	and	<	0.5	41
	>=	0.5	and	<	2	17
	>=	2	and	<	3.5	5
	>=	3.5	and	<	5	3
	>=	5	and	<	101	15
		N/A			N/A	

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill


Range Map

Parameter: O2 (mid range)

Analysis Method: Maximum

Date Range: 09/01/2026 - 09/30/2026

Map generation date : 10/09/2026



Ranges Mapped

						# Points
	>=	0	and	<	0.5	65
	>=	0.5	and	<	0.9	12
	>=	0.9	and	<	1.1	3
	>=	1.1	and	<	1.5	1
	>=	1.5	and	<	101	
		N/A			N/A	

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill


Range Map

Parameter: CH4/CO2 Ratio (high range)

Analysis Method: Minimum

Date Range: 09/01/2026 - 09/30/2026

Map generation date : 10/09/2026



Ranges Mapped

						# Points
	>=	0	and	<	2000	5
	>=	2000	and	<	5000	
	>=	5000	and	<	10000	2
	>=	10000	and	<	50000	16
	>=	50000	and	<	100000	13
	>=	100000	and	<	150000	12
	>=	150000	and	<	1000000	20

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill


Range Map

Parameter: H2 LAB (mid range)

Analysis Method: MostRecent

Date Range: 09/01/2026 - 09/30/2026

Map generation date : 10/09/2026



Ranges Mapped

						# Points
	>=	0	and	<	500	23
	>=	500	and	<	1000	12
	>=	1000	and	<	1500	13
	>=	1500	and	<	2000	8
	>=	2000	and	<	10000	15

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill


Range Map

Parameter: CO LAB (mid range)

Analysis Method: MostRecent

Date Range: 09/01/2026 - 09/30/2026

Map generation date : 10/09/2026



Ranges Mapped

						# Points
	>=	-50	and	<	131	36
	>=	131	and	<	150	5
	>=	150	and	<	165	13
	>=	165	and	<	180	8
	>=	180	and	<	999	19
		N/A			N/A	

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill


Range Map


Parameter: Adj Temp (high range)

Analysis Method: Maximum

Date Range: 09/01/2026 - 09/30/2026

Map generation date : 10/09/2026





Point ID / Name


CHIWCV99 / CV-99

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/06/2026


Point IDs / Names

CV-99 / CV-99

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Point IDs / Names


CV-99 / CV-99


Parameter / Unit

Hydrogen / % v/v

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/06/2026





Point ID / Name


CV108-52 / CV-108-52

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Point IDs / Names


CV-108-52 / CV-108-52

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/06/2026



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/06/2026


Point IDs / Names


CV-108-52 / CV-108-52

Parameter / Unit

Hydrogen / % v/v

SCSeTools





Point ID / Name


CHWCV113 / CV-113

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/06/2026

Point IDs / Names

CV-113 / CV-113

Parameter / Unit

Carbon Monoxide / ppmv



Point IDs / Names


CV-113 / CV-113


Parameter / Unit

Hydrogen / % v/v

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/06/2026





Point ID / Name


CHWCV114 / CV-114

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/06/2026

Point IDs / Names

CV-114 / CV-114

Parameter / Unit

Carbon Monoxide / ppmv



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/06/2026


Point IDs / Names

CV-114 / CV-114

Parameter / Unit

Hydrogen / % v/v





Point ID / Name


CCV1532A / CV-1532A

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/06/2026

Point IDs / Names

CV-1532A / CV-1532A

Parameter / Unit

Carbon Monoxide / ppmv



Point IDs / Names


CV-1532A / CV-1532A


Parameter / Unit

Hydrogen / % v/v

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/06/2026





Point ID / Name


CHCV1535 / CV-1535

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/06/2026

Point IDs / Names

CV-1535 / CV-1535

Parameter / Unit

Carbon Monoxide / ppmv



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/06/2026


Point IDs / Names

CV-1535 / CV-1535

Parameter / Unit

Hydrogen / % v/v

SCSeTools



Point ID / Name


CCV1902A / CV-1902A

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Point IDs / Names


CV-1902A / CV-1902A

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/06/2026



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/06/2026


Point IDs / Names

CV-1902A / CV-1902A

Parameter / Unit

Hydrogen / % v/v





Point ID / Name


CHCV2001 / CV-2001

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Point IDs / Names


CV-2001 / CV-2001

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026


Point IDs / Names

CV-2001 / CV-2001

Parameter / Unit

Hydrogen / % v/v





Point ID / Name


CHCV2002 / CV-2002

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-2002 / CV-2002

Parameter / Unit

Carbon Monoxide / ppmv



Point IDs / Names


CV-2002 / CV-2002


Parameter / Unit

Hydrogen / % v/v

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026





Point ID / Name


CHCV2007 / CV-2007

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Point IDs / Names


CV-2007 / CV-2007

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-2007 / CV-2007

Parameter / Unit

Hydrogen / % v/v



Point ID / Name


CHCV2301 / CV-2301

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Point IDs / Names


CV-2301 / CV-2301

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026



Point IDs / Names


CV-2301 / CV-2301


Parameter / Unit

Hydrogen / % v/v

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026





Point ID / Name


CHCV2302 / CV-2302

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-2302 / CV-2302

Parameter / Unit

Carbon Monoxide / ppmv



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026


Point IDs / Names


CV-2302 / CV-2302

Parameter / Unit

Hydrogen / % v/v

SCSeTools





Point ID / Name


CHCV2303 / CV-2303

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-2303 / CV-2303

Parameter / Unit

Carbon Monoxide / ppmv



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-2303 / CV-2303

Parameter / Unit

Hydrogen / % v/v



Point ID / Name


CHCV2305 / CV-2305

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-2305 / CV-2305

Parameter / Unit

Carbon Monoxide / ppmv



Point IDs / Names


CV-2305 / CV-2305


Parameter / Unit

Hydrogen / % v/v

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026





Point ID / Name


CHCV2312 / CV-2312-PLR

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-2312 / CV-2312

Parameter / Unit

Carbon Monoxide /



Point IDs / Names


CV-2312 / CV-2312


Parameter / Unit

Hydrogen / % v/v

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026





Point ID / Name


CHCV2314 / CV-2314-PLR

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-2314 / CV-2314

Parameter / Unit

Carbon Monoxide / ppmv



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026


Point IDs / Names

CV-2314 / CV-2314

Parameter / Unit

Hydrogen / % v/v





Point ID / Name


CHCV2315 / CV-2315

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-2315 / CV-2315

Parameter / Unit

Carbon Monoxide / ppmv



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026


Point IDs / Names

CV-2315 / CV-2315

Parameter / Unit

Hydrogen / % v/v





Point ID / Name


CHCV2328 / CV-2328

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-2328 / CV-2328

Parameter / Unit

Carbon Monoxide / ppmv



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026


Point IDs / Names

CV-2328 / CV-2328

Parameter / Unit

Hydrogen / % v/v





Point ID / Name


CHCV2333 / CV-2333

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-2333 / CV-2333

Parameter / Unit

Carbon Monoxide / ppmv



Point IDs / Names


CV-2333 / CV-2333


Parameter / Unit

Hydrogen / % v/v

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026





Point ID / Name


CHCV2334 / CV-2334

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Point IDs / Names


CV-2334 / CV-2334

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-2334 / CV-2334

Parameter / Unit

Hydrogen / % v/v



Point ID / Name


CHCV2337 / CV-2337

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-2337 / CV-2337

Parameter / Unit

Carbon Monoxide / ppmv



Point IDs / Names

CV-2337 / CV-2337


Parameter / Unit


Hydrogen / % v/v

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026

SCSeTools





Point ID / Name


CHCV2341 / CV-2341

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-2341 / CV-2341

Parameter / Unit

Carbon Monoxide /



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026


Point IDs / Names

CV-2341 / CV-2341

Parameter / Unit

Hydrogen / % v/v





Point ID / Name


CHCV2344 / CV-2344

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Point IDs / Names


CV-2344 / CV-2344

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026


Point IDs / Names

CV-2344 / CV-2344

Parameter / Unit

Hydrogen / % v/v





Point ID / Name


CHCV2345 / CV-2345

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-2345 / CV-2345

Parameter / Unit

Carbon Monoxide / ppmv



Point IDs / Names


CV-2345 / CV-2345


Parameter / Unit

Hydrogen / % v/v

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026





Point ID / Name


CHCV2346 / CV-2346

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-2346 / CV-2346

Parameter / Unit

Carbon Monoxide / ppmv



Point IDs / Names


CV-2346 / CV-2346


Parameter / Unit

Hydrogen / % v/v

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026





Point ID / Name


CHCV2347 / CV-2347

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026


Point IDs / Names

CV-2347 / CV-2347

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026


Point IDs / Names

CV-2347 / CV-2347

Parameter / Unit

Hydrogen / % v/v





Point ID / Name


CHCV2348 / CV-2348

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026


Point IDs / Names

CV-2348 / CV-2348

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026


Point IDs / Names

CV-2348 / CV-2348

Parameter / Unit

Hydrogen / % v/v





Point ID / Name


CHCV2349 / CV-2349

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-2349 / CV-2349

Parameter / Unit

Carbon Monoxide / ppmv



Point IDs / Names


CV-2349 / CV-2349


Parameter / Unit

Hydrogen / % v/v

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026





Point ID / Name


CHCV2350 / CV-2350

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-2350 / CV-2350

Parameter / Unit

Carbon Monoxide / ppmv



Point IDs / Names


CV-2350 / CV-2350


Parameter / Unit

Hydrogen / % v/v

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026





Point ID / Name


CHCV2351 / CV-2351

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-2351 / CV-2351

Parameter / Unit

Carbon Monoxide / ppmv



Point IDs / Names


CV-2351 / CV-2351


Parameter / Unit

Hydrogen / % v/v

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026





Point ID / Name


CHCV2352 / CV-2352

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026


Point IDs / Names

CV-2352 / CV-2352

Parameter / Unit

Carbon Monoxide /

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026


Point IDs / Names


CV-2352 / CV-2352

Parameter / Unit

Hydrogen / % v/v

SCSeTools





Point ID / Name


CHCV2353 / CV-2353-PLR

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Point IDs / Names


CV-2353 / CV-2353

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026



Point IDs / Names


CV-2353 / CV-2353


Parameter / Unit

Hydrogen / % v/v

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026





Point ID / Name


CHCV2354 / CV-2354

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026


Point IDs / Names

CV-2354 / CV-2354

Parameter / Unit

Carbon Monoxide /

SCSeTools



Point IDs / Names


CV-2354 / CV-2354


Parameter / Unit

Hydrogen / % v/v

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026





Point ID / Name


CCV24002 / CV-24002


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools





Point ID / Name


CCV24003 / CV-24003

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Point ID / Name


CCV24007 / CV-24007

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-24007 / CV-24007

Parameter / Unit

Carbon Monoxide /



Point IDs / Names

CV-24007 / CV-24007


Parameter / Unit


Hydrogen / % v/v

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026

SCSeTools





Point ID / Name


CCV24017 / CV-24017

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Point IDs / Names


CV-24017 / CV-24017

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026


Point IDs / Names

CV-24017 / CV-24017

Parameter / Unit

Hydrogen / % v/v





Point ID / Name


CCV24049 / CV-24049

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Point IDs / Names


CV-24049 / CV-24049

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026


Point IDs / Names


CV-24049 / CV-24049

Parameter / Unit

Hydrogen / % v/v

SCSeTools





Point ID / Name


CCV24053 / CV-24053

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-24053 / CV-24053

Parameter / Unit

Carbon Monoxide / ppmv



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026


Point IDs / Names

CV-24053 / CV-24053

Parameter / Unit

Hydrogen / % v/v





Point ID / Name


CCV24055 / CV-24055

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Point IDs / Names


CV-24055 / CV-24055

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026


Point IDs / Names

CV-24055 / CV-24055

Parameter / Unit

Hydrogen / % v/v





Point ID / Name


CCV24062 / CV-24062

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026


Point IDs / Names

CV-24062 / CV-24062

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026


Point IDs / Names

CV-24062 / CV-24062

Parameter / Unit

Hydrogen / % v/v

SCSeTools



Point ID / Name


CCV24063 / CV-24063

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Point IDs / Names


CV-24063 / CV-24063

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026



Point IDs / Names


CV-24063 / CV-24063

Parameter / Unit

Hydrogen / % v/v

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026



Point ID / Name


CCV24064 / CV-24064-PLR

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-24064 / CV-24064

Parameter / Unit

Carbon Monoxide / ppmv



Point IDs / Names


CV-24064 / CV-24064


Parameter / Unit

Hydrogen / % v/v

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026





Point ID / Name


CCV24065 / CV-24065-TP17

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026


Point IDs / Names

CV-24065 / CV-24065

Parameter / Unit

Carbon Monoxide /

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026


Point IDs / Names

CV-24065 / CV-24065

Parameter / Unit

Hydrogen / % v/v





Point ID / Name


CCV24066 / CV-24066

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-24066 / CV-24066

Parameter / Unit

Carbon Monoxide / ppmv



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026


Point IDs / Names


CV-24066 / CV-24066

Parameter / Unit

Hydrogen / % v/v

SCSeTools





Point ID / Name


CCV24069 / CV-24069

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-24069 / CV-24069

Parameter / Unit

Carbon Monoxide / ppmv



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026


Point IDs / Names


CV-24069 / CV-24069

Parameter / Unit

Hydrogen / % v/v

SCSeTools





Point ID / Name


CCV24070 / CV-24070

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-24070 / CV-24070

Parameter / Unit

Carbon Monoxide / ppmv



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026


Point IDs / Names

CV-24070 / CV-24070

Parameter / Unit

Hydrogen / % v/v





Point ID / Name


CCV24071 / CV-24071

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-24071 / CV-24071

Parameter / Unit

Carbon Monoxide / ppmv



Point IDs / Names

CV-24071 / CV-24071

Parameter / Unit

Hydrogen / % v/v

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026



Point ID / Name


CCV24075 / CV-24075-TP15


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools





Point ID / Name


CCV24077 / CV-24077


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools





Point ID / Name


CCV24079 / CV-24079-TP8


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools





Point ID / Name


CCV24082 / CV-24082


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools





Point ID / Name


CCV24083 / CV-24083

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Point ID / Name


CCV24084 / CV-24084-TP11

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Point IDs / Names


CV-24084-TP11 / CV-24084-TP11

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026



Point IDs / Names


CV-24084-TP11 / CV-24084-TP11


Parameter / Unit

Hydrogen / % v/v

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026





Point ID / Name


CCV24088 / CV-24088


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools





Point ID / Name


CCV24095 / CV-24095

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Point IDs / Names


CV-24095 / CV-24095

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026



Point IDs / Names


CV-24095 / CV-24095


Parameter / Unit

Hydrogen / % v/v

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026





Point ID / Name


CCV24096 / CV-24096


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools





Point ID / Name


CCV24097 / CV-24097


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools





Point ID / Name


CCV24098 / CV-24098


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools





Point ID / Name


CCV24099 / CV-24099


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools





Point ID / Name


CCV24100 / CV-24100

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Point IDs / Names


CV-24100 / CV-24100

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026



Point IDs / Names


CV-24100 / CV-24100


Parameter / Unit

Hydrogen / % v/v

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026





Point ID / Name


CCV24101 / CV-24101

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-24101 / CV-24101

Parameter / Unit

Carbon Monoxide / ppmv



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026


Point IDs / Names


CV-24101 / CV-24101

Parameter / Unit

Hydrogen / % v/v

SCSeTools





Point ID / Name


CCV24102 / CV-24102


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools





Point ID / Name


CCV24120 / CV-24120

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-24120 / CV-24120

Parameter / Unit

Carbon Monoxide / ppmv



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026


Point IDs / Names

CV-24120 / CV-24120

Parameter / Unit

Hydrogen / % v/v





Point ID / Name


CCV24121 / CV-24121

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-24121 / CV-24121

Parameter / Unit

Carbon Monoxide / ppmv



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026


Point IDs / Names

CV-24121 / CV-24121

Parameter / Unit

Hydrogen / % v/v





Point ID / Name


CCV24122 / CV-24122

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-24122 / CV-24122

Parameter / Unit

Carbon Monoxide / ppmv



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026


Point IDs / Names

CV-24122 / CV-24122

Parameter / Unit

Hydrogen / % v/v





Point ID / Name


CCV24123 / CV-24123


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools





Point ID / Name


CCV24125 / CV-24125-TP20

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026


Point IDs / Names

CV-24125 / CV-24125

Parameter / Unit

Carbon Monoxide / ppmv

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026


Point IDs / Names

CV-24125 / CV-24125

Parameter / Unit

Hydrogen / % v/v





Point ID / Name


CCV24126 / CV-24126

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Point IDs / Names


CV-24126 / CV-24126

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026



Point IDs / Names


CV-24126 / CV-24126


Parameter / Unit

Hydrogen / % v/v

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026





Point ID / Name


CCV24127 / CV-24127

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-24127 / CV-24127

Parameter / Unit

Carbon Monoxide / ppmv



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026


Point IDs / Names

CV-24127 / CV-24127

Parameter / Unit

Hydrogen / % v/v





Point ID / Name


CCV24128 / CV-24128

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-24128 / CV-24128

Parameter / Unit

Carbon Monoxide / ppmv



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026


Point IDs / Names


CV-24128 / CV-24128

Parameter / Unit

Hydrogen / % v/v

SCSeTools





Point ID / Name


CCV24134 / CV-24134-TP19


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools





Point ID / Name


CCV24138 / CV-24138

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-24138 / CV-24138

Parameter / Unit

Carbon Monoxide / ppmv



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026


Point IDs / Names


CV-24138 / CV-24138

Parameter / Unit

Hydrogen / % v/v

SCSeTools





Point ID / Name


CCV24139 / CV-24139

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-24139 / CV-24139

Parameter / Unit

Carbon Monoxide / ppmv



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026


Point IDs / Names


CV-24139 / CV-24139

Parameter / Unit

Hydrogen / % v/v

SCSeTools





Point ID / Name


CCV24140 / CV-24140

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-24140 / CV-24140

Parameter / Unit

Carbon Monoxide / ppmv



Point IDs / Names

CV-24140 / CV-24140


Parameter / Unit


Hydrogen / % v/v

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026

SCSeTools





Point ID / Name


CCV24141 / CV-24141

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Point IDs / Names


CV-24141 / CV-24141

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026



Point IDs / Names


CV-24141 / CV-24141

Parameter / Unit

Hydrogen / % v/v

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026



Point ID / Name


CCV24142 / CV-24142

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

CV-24142 / CV-24142

Parameter / Unit

Carbon Monoxide / ppmv



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026


Point IDs / Names

CV-24142 / CV-24142

Parameter / Unit

Hydrogen / % v/v





Point ID / Name


CCV24143 / CV-24143

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Point IDs / Names


CV-24143 / CV-24143

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026


Point IDs / Names

CV-24143 / CV-24143

Parameter / Unit

Hydrogen / % v/v





Point ID / Name


CCV24144 / CV-24144


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools





Point ID / Name


CHH1770N / H-1770N

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Point IDs / Names


H-1770N / H-1770N

Parameter / Unit

Carbon Monoxide / ppmv

Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

H-1770N / H-1770N

Parameter / Unit

Hydrogen / % v/v



Point ID / Name


CHH2165W / H-2165W

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

H-2165W / H-2165W

Parameter / Unit

Carbon Monoxide /



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

H-2165W / H-2165W

Parameter / Unit

Hydrogen / % v/v



Point ID / Name


CHH2273W / H-2273W

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 10/01/2025 - 09/30/2026
Chart generation date: 10/5/26

SCSeTools



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026


Chart generation date : 10/07/2026

Point IDs / Names

H-2273W / H-2273W

Parameter / Unit

Carbon Monoxide /



Chiquita Canyon Landfill - LAB DATA
Points Chart
Date Range : 10/01/2025 to 09/30/2026

Chart generation date : 10/07/2026


Point IDs / Names

H-2273W / H-2273W

Parameter / Unit

Hydrogen / % v/v

Thirty Day Maximum Vertical TemperatureMap from Temperature Probes (TP)
at the Chiquita Canyon Landfill - September 2026



Max Temps - 20:55:48 09-30-2026

Current | 7 Day | 30 Day

BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	179	100
TP02	158	60
TP03	233	45
TP04	160	60
TP05	170	75
TP06	143	100
TP07	208	100
TP08	183	45
TP09	209	125
TP10	160	125
TP11	217	125
TP12	150	125
TP13	181	140
TP14	174	150
TP15	200	100
TP16	160	30
TP17	154	125
TP18	213	45
TP19	250	150
TP20	144	45
TP21	250	110
TP22	199	15
TP23	258	75
TP24	251	265
TP25	274	130
TP26	180	150
TP27	157	100
TP28	145	170
TP29	192	240
TP30	176	190
TP31	194	180
TP32	171	130
TP33	199	45
TP34	153	120
TP35	175	140
TP36	174	165
TP37	186	180
TP38	172	165
TP39	160	160
TP40	150	185

Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM

SCS ENGINEERS

07224053.00 | September 3, 2026

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

From August 27, 2026, through September 2, 2026, there were four recorded temperature increases and two recorded temperature decreases that triggered the notification limits set forth in the LEA's October 4, 2024, letter.

Chiquita provides the following updates:

- TP-07
    - The 100-foot thermocouple showed an increase in maximum temperature of 40°F from 155°F to 195°F from August 16th to September 2nd. One potential factor contributing to the observed temperature increase is the removal of liquids from wells near TP-07.

- TP-08
    - The 30-foot and 45-foot thermocouples exhibited temperature increases of 27°F and 29°F, respectively, between July 12, 2026, and July 22, 2026. In response, Site personnel observed the temperature changes and conducted an investigation from July 23, 2026, through July 29, 2026. Following the investigation, temperatures continued to decline at the 30-foot thermocouple from July 30th, 2026, through August 19, 2026, and then temperatures started to increase at the 15, 30, and 45-foot thermocouples from August 20, 2026, through September 2, 2026.
    - TP-08 is installed within extraction well CV-24079, which is equipped with a liquid extraction pump. The investigation determined that the existing pump is experiencing a power-related issue and requires removal. Site personnel have identified the need for a replacement pump and plan to complete the replacement when the road to the well is completed. One potential factor contributing to the observed temperature increase is the removal of liquids from wells near TP-08.
    - The 15-foot thermocouple showed an increase in maximum temperature of 39°F from 113°F to 152°F from August 22nd to September 2nd.
    - The 30-foot thermocouple showed an increase in maximum temperature of 33°F from 144°F to 177°F from August 21st to September 2nd.
    - The 45-foot thermocouple showed an increase in maximum temperature of 21°F from 162°F to 183°F from August 21st to September 2nd.


- TP-19
    - A discrepancy was identified during the review of data from five weeks prior. Upon investigation, the Site determined that the associated battery had failed and subsequently replaced it. During this inspection, the temperature reading from the 125-foot thermocouple was observed to be anomalously low. Further evaluation indicated that the 125-foot thermocouple required replacement. As an interim measure, the Site installed a 120-foot

thermocouple that was available onsite and ordered a replacement 125-foot thermocouple. The replacement 125-foot thermocouple is anticipated to be installed upon receipt in October 2026.
    - The 75-foot thermocouple showed a decrease in maximum temperature of 13°F from 166°F to 153°F from August 27th to September 2nd.
    - The 150-foot thermocouple showed a decrease in maximum temperature of 31°F from 269°F to 238°F from August 26th to September 2nd.

- TP-25
    - The Site conducted a follow-up camera inspection of the TP-25 temperature probe casing last week to evaluate potential liquid infiltration and assess the condition of the casing interior. The inspection indicated that no liquid was present at the bottom of the casing. Instead, pressurized gas was observed upon opening the probe casing. The temperature probes inside TP-25 are thus no longer correctly reporting in-situ waste temperatures and are instead reporting gas temperatures traveling to and up the temperature probe casing. The Site will continue to monitor TP-25.
    - The 110-foot thermocouple remained consistent with previously recorded temperatures. As described above, the Site is continuing to assess the condition of this probe equipment and will continue to monitor the temperature on the thermocouples.

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39


Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS


Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40

Maximum data for 7/23/2026 12:00 AM to 9/2/2026 12:00 AM



SCS ENGINEERS

Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill




BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	176	15
TP02	158	60
TP03	233	45
TP04	159	60
TP05	169	75
TP06	140	100
TP07	195	100
TP08	182	45
TP09	209	125
TP10	158	125
TP11	214	125
TP12	150	125
TP13	179	140
TP14	173	150
TP15	200	100
TP16	161	30
TP17	154	125
TP18	212	45
TP19	267	150
TP20	143	45
TP21	248	110
TP22	200	15
TP23	258	75
TP24	216	265
TP25	260	130
TP26	179	150
TP27	156	100
TP28	145	170
TP29	187	240
TP30	175	190
TP31	193	180
TP32	171	130
TP33	198	45
TP34	153	120
TP35	175	140
TP36	173	165
TP37	185	180
TP38	172	165
TP39	160	160
TP40	150	185

TP-07
One potential factor contributing to the observed temperature increase is the removal of liquids from wells near TP-07.

TP-08
The 30-foot and 45-foot thermocouples exhibited temperature increases of 27°F and 29°F, respectively, between July 12, 2026, and July 22, 2026. In response, Site personnel observed the temperature changes and conducted an investigation from July 23, 2026, through July 29, 2026. Following the investigation, temperatures continued to decline at the 30-foot thermocouple from July 30th, 2026, through August 19, 2026, and then temperatures started to increase at the 15, 30, and 45-foot thermocouples from August 20, 2026, through September 2, 2026.
TP-08 is installed within extraction well CV-24079, which is equipped with a liquid extraction pump. The investigation determined that the existing pump is experiencing a power-related issue and requires removal. Site personnel have identified the need for a replacement pump and plan to complete the replacement when the road to the well is completed. One potential factor contributing to the observed temperature increase is the removal of liquids from wells near TP-08.

TP-19
A discrepancy was identified during the review of data from five weeks prior. Upon investigation, the Site determined that the associated battery had failed and subsequently replaced it. During this inspection, the temperature reading from the 125-foot thermocouple was observed to be anomalously low. Further evaluation indicated that the 125-foot thermocouple required replacement. As an interim measure, the Site installed a 120-foot thermocouple that was available onsite and ordered a replacement 125-foot thermocouple. The replacement 125-foot thermocouple is anticipated to be installed upon receipt in October 2026.

TP-25
The Site conducted a follow-up camera inspection of the TP-25 temperature probe casing last week to evaluate potential liquid infiltration and assess the condition of the casing interior. The inspection indicated that no liquid was present at the bottom of the casing. Instead, pressurized gas was observed upon opening the probe casing. The temperature probes inside TP-25 are thus no longer correctly reporting in-situ waste temperatures and are instead reporting gas temperatures traveling to and up the temperature probe casing. The Site will continue to monitor TP-25.



N

GRAPHIC SCALE

140 70 0 140 280 420

SCALE: 1"=140'

LEGEND

- 1150 — EXISTING TOPOGRAPHIC CONTOUR
- EXISTING CELL LIMITS (APPROXIMATE)
- REACTION MITIGATION AREA BOUNDARY
- REACTION MITIGATION AREA BOUNDARY - CONDITION 9A
- TP-XX — EXISTING TEMPERATURE PROBE - STANDALONE
- TP-XX — EXISTING TEMPERATURE PROBES - INSTALLED WITHIN WELL CASING

GENERAL DRAWING NOTES:

1. REACTION MITIGATION AREA BOUNDARY ADJUSTMENTS UPDATED AUGUST 10, 2026, BASED ON JULY 2026 DATA.
2. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER DATED AUGUST 12, 2026.
3. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

DATE

REVISION

NO.

SHEET TITLE: EXISTING TEMPERATURE PROBE MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544

PROJ. NO: 01204123.45 | DSN. BY: RNH | DWN. BY: CNW | CHK. BY: RNH | ACAD FILE: - | APP. BY: -

DATE: 8/10/2026

SCALE: AS SHOWN

SHEET: 1

Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM

SCS ENGINEERS

07224053.00 | September 10, 2026

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

From September 3, 2026, through September 9, 2026, there were seven recorded temperature increases and two recorded temperature decreases that triggered the notification limits set forth in the LEA's October 4, 2024, letter.

Chiquita provides the following updates:

- TP-07
    - The 100-foot thermocouple showed an increase in maximum temperature of 48°F from 160°F to 208°F from August 21st to September 9th. One potential factor contributing to the observed temperature increase is the removal of liquids from wells near TP-07.

- TP-08
    - The 30-foot and 45-foot thermocouples exhibited temperature increases of 27°F and 29°F, respectively, between July 12, 2026, and July 22, 2026. In response, Site personnel observed the temperature changes and conducted an investigation from July 23, 2026, through July 29, 2026. Following the investigation, temperatures continued to decline at the 30-foot thermocouple from July 30th, 2026, through August 19, 2026, and then temperatures started to increase at the 15, 30, and 45-foot thermocouples from August 20, 2026, through September 2, 2026.
    - TP-08 is installed within extraction well CV-24079, which is equipped with a liquid extraction pump. The investigation determined that the existing pump is experiencing a power-related issue and requires removal. Site personnel have constructed the road to TP-08 this week and the pump is on the schedule for maintenance this week. One potential factor contributing to the observed temperature increase is the removal of liquids from wells near TP-08.
    - The 15-foot thermocouple showed an increase in maximum temperature of 46°F from 113°F to 159°F from August 22nd to September 9th.
    - The 30-foot thermocouple showed an increase in maximum temperature of 34°F from 144°F to 178°F from August 21st to September 4th.
    - The 45-foot thermocouple remained consistent with previously recorded temperatures.

- TP-13
    - The 100-foot thermocouple showed an increase in maximum temperature of 10°F from 162°F to 172°F from September 4th to September 9th.

- TP-19
    - A discrepancy was identified during the review of data from six weeks prior. Upon investigation, the Site determined that the associated battery had failed and subsequently replaced it. During this inspection, the temperature

reading from the 125-foot thermocouple was observed to be anomalously low. Further evaluation indicated that the 125-foot thermocouple required replacement. As an interim measure, the Site installed a 120-foot thermocouple that was available onsite and ordered a replacement 125-foot thermocouple. The replacement 125-foot thermocouple is anticipated to be installed upon receipt in October 2026.
    - The 75-foot thermocouple remained consistent with previously recorded temperatures.
    - The 150-foot thermocouple showed an increase in maximum temperature of 13°F from 238°F to 251°F from September 3rd to September 9th.


- TP-24
    - The 265-foot thermocouple showed an increase in maximum temperature of 34°F from 217°F to 251°F from September 6th to September 7th, and then a decrease in maximum temperature of 34°F from 251°F to 217°F from September 7th to September 8th. Potential factors contributing to the observed temperature increase are the flow changes in the wellfield and removal of liquids from wells near TP-24.

- TP-25
    - The Site recently conducted a follow-up camera inspection of the TP-25 temperature probe casing to evaluate potential liquid infiltration and assess the condition of the casing interior. The inspection confirmed that no liquid was present at the bottom of the casing. Pressurized landfill gas (LFG) was observed, however, when the probe casing was opened. Based on these observations, the Site believes that the temperature readings at TP-25 may be influenced by LFG entering and moving within the casing and, therefore, may not be representative of in-situ waste temperatures. The elevated temperatures recorded at TP-25 are most likely attributable, at least in part, to LFG intrusion associated with a compromised casing seal. The Site is continuing to monitor TP-25 and evaluate the condition of the probe casing and is assessing appropriate next steps to address the observed conditions and obtain reliable in-situ waste temperature measurements.

- TP-33
    - The 30-foot thermocouple showed a decrease in maximum temperature of 18°F from 175°F to 157°F from September 5th to September 7th, and then an increase in maximum temperature of 13°F from 157°F to 170°F from September 7th to September 9th.

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39


Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS


Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40

Maximum data for 7/30/2026 12:00 AM to 9/9/2026 12:00 AM



SCS ENGINEERS

Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill



Max Temps - 04:58:45 09-10-2026

Current | 7 Day | 30 Day

BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	177	15
TP02	158	60
TP03	233	45
TP04	159	60
TP05	168	75
TP06	140	100
TP07	208	100
TP08	183	45
TP09	209	125
TP10	158	125
TP11	217	125
TP12	149	125
TP13	181	140
TP14	174	150
TP15	194	100
TP16	160	30
TP17	154	125
TP18	212	45
TP19	250	150
TP20	144	45
TP21	246	110
TP22	199	15
TP23	258	75
TP24	251	265
TP25	261	130
TP26	180	150
TP27	156	100
TP28	145	170
TP29	192	240
TP30	176	190
TP31	193	180
TP32	170	130
TP33	198	45
TP34	152	120
TP35	175	140
TP36	173	165
TP37	185	180
TP38	172	165
TP39	160	160
TP40	150	185


TP-07
Potential factors contributing to the observed temperature increase are the flow changes in the wellfield and removal of liquids from wells near TP-07.

TP-08
The 30-foot and 45-foot thermocouples exhibited temperature increases of 27°F and 29°F, respectively, between July 12, 2026, and July 22, 2026. In response, Site personnel observed the temperature changes and conducted an investigation from July 23, 2026, through July 29, 2026. Following the investigation, temperatures continued to decline at the 30-foot thermocouple from July 30th, 2026, through August 19, 2026, and then temperatures started to increase at the 15, 30, and 45-foot thermocouples from August 20, 2026, through September 9, 2026.
TP-08 is installed within extraction well CV-24079, which is equipped with a liquid extraction pump. The investigation determined that the existing pump is experiencing a power-related issue and requires removal. Site personnel have constructed the road to TP-08 this week and the pump is on the schedule for maintenance this week. One potential factor contributing to the observed temperature increase is the removal of liquids from wells near TP-08.

TP-19
A discrepancy was identified during the review of data from six weeks prior. Upon investigation, the Site determined that the associated battery had failed and subsequently replaced it. During this inspection, the temperature reading from the 125-foot thermocouple was observed to be anomalously low. Further evaluation indicated that the 125-foot thermocouple required replacement. As an interim measure, the Site installed a 120-foot thermocouple that was available onsite and ordered a replacement 125-foot thermocouple. The replacement 125-foot thermocouple is anticipated to be installed upon receipt in October 2026.

TP-24
Potential factors contributing to the observed temperature increase is the flow changes in the wellfield and removal of liquids from wells near TP-24.

TP-25
The Site recently conducted a follow-up camera inspection of the TP-25 temperature probe casing to evaluate potential liquid infiltration and assess the condition of the casing interior. The inspection confirmed that no liquid was present at the bottom of the casing. Pressurized landfill gas (LFG) was observed, however, when the probe casing was opened. Based on these observations, the Site believes that the temperature readings at TP-25 may be influenced by LFG entering and moving within the casing and, therefore, may not be representative of in-situ waste temperatures. The elevated temperatures recorded at TP-25 are most likely attributable, at least in part, to LFG intrusion associated with a compromised casing seal. The Site is continuing to monitor TP-25 and evaluate the condition of the probe casing and is assessing appropriate next steps to address the observed conditions and obtain reliable in-situ waste temperature measurements.



N

GRAPHIC SCALE

150 75 0 150 300 450

SCALE: 1"=150'

LEGEND

- 1150 — EXISTING TOPOGRAPHIC CONTOUR
- EXISTING CELL LIMITS (APPROXIMATE)
- REACTION MITIGATION AREA BOUNDARY
- REACTION MITIGATION AREA BOUNDARY - CONDITION 9A
- TP-XX — EXISTING TEMPERATURE PROBE - STANDALONE
- TP-XX — EXISTING TEMPERATURE PROBES - INSTALLED WITHIN WELL CASING

GENERAL DRAWING NOTES:

1. REACTION MITIGATION AREA BOUNDARY ADJUSTMENTS UPDATED AUGUST 10, 2026, BASED ON JULY 2026 DATA.
2. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER DATED AUGUST 5, 2026.
3. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

DATE

REVISION

NO.

SHEET TITLE: EXISTING TEMPERATURE PROBE MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544

ACAD FILE: E_ENGINEERS
APP. BY: -
DWN. BY: CNW
CHK. BY: RNH
PROJ. NO: 01204123.45
DSN. BY: RNH

DATE: 8/10/2026

SCALE: AS SHOWN

SHEET: 1

Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM

SCS ENGINEERS

07224053.00 | September 17, 2026

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

Privileged & Confidential
Attorney-Work Product
9/17/2026

In accordance with the LEA's June 6, 2024, Compliance Order and related LEA correspondence, Chiquita Canyon, LLC (Chiquita) submits the attached weekly temperature graphs of all temperature monitoring probes (TMPs) with weekly maximum trends plotted over six weeks from August 6, 2026, through September 16, 2026, with a map of the maximum temperatures recorded in the past week and the below narrative on recorded temperature data. We included a separate map demonstrating the locations of the 40 temperature monitoring probes in relation to the reaction area boundary because the real time data monitoring software that is used to display the probe data is not able to import a geolocated boundary delineated in CAD.

From September 10, 2026, through September 16, 2026, there were five recorded temperature increases and seven recorded temperature decreases that triggered the notification limits set forth in the LEA's October 4, 2024, letter.

Chiquita provides the following updates:

- TP-07
    - The 100-foot thermocouple remained consistent with previously recorded temperatures.

- TP-08
    - The 30-foot and 45-foot thermocouples exhibited temperature increases of 27°F and 29°F, respectively, between July 12, 2026, and July 22, 2026. In response, Site personnel observed the temperature changes and conducted an investigation from July 23, 2026, through July 29, 2026. Following the investigation, temperatures continued to decline at the 30-foot thermocouple from July 30th, 2026, through August 19, 2026, and then temperatures started to increase at the 15, 30, and 45-foot thermocouples from August 20, 2026, through September 12, 2026, then a decrease was observed in the 30 and 45-foot thermocouples from September 12, 2026, through September 16,2026.
    - TP-08 is installed within extraction well CV-24079, which is equipped with a liquid extraction pump. The investigation determined that the existing pump is experiencing a power-related issue and requires removal. Site personnel removed the existing pump this week, and cleaned, repaired, reset, and reinstalled it. One potential factor contributing to the observed temperature increase and subsequent decrease is the removal of liquids from wells near TP-08 and in well CV-24079.
    - The 15-foot thermocouple remained consistent with previously recorded temperatures.
    - The 30-foot thermocouple showed a decrease in maximum temperature of 15°F from 177°F to 162°F from September 10th to September12th, and then

an increase in maximum temperature of 10°F from 162°F to 172°F from September 12th to September 14th.
    - The 45-foot thermocouple showed a decrease in maximum temperature of 25°F from 184°F to 159°F from September 9th to September 13th, then an increase in maximum temperature of 22°F from 159°F to 181°F from September 13th to September 14th, and then a decrease in maximum temperature of 22°F from 181°F to 159°F from September 14th to September 16th.

- TP-13
    - The 100-foot thermocouple remained consistent with previously recorded temperatures.

- TP-19
    - A discrepancy was identified during the review of data from six weeks prior. Upon investigation, the Site determined that the associated battery had failed and subsequently replaced it. During this inspection, the temperature reading from the 125-foot thermocouple was observed to be anomalously low. Further evaluation indicated that the 125-foot thermocouple required replacement. As an interim measure, the Site installed a 120-foot thermocouple that was available onsite and ordered a replacement 125-foot thermocouple. The replacement 125-foot thermocouple is anticipated to be installed upon receipt in October 2026.
    - The 150-foot thermocouple showed a decrease in maximum temperature of 15°F from 251°F to 236°F from September 9th to September 14th.

- TP-24
    - The 100-foot thermocouple showed an increase in maximum temperature of 13°F from 149°F to 162°F from September 11th to September 14th, and then a decrease in maximum temperature of 14°F from 162°F to 148°F from September 14th to September 16th.
    - The 155-foot thermocouple showed an increase in maximum temperature of 18°F from 170°F to 188°F from September 9th to September 13th, and then a decrease in maximum temperature of 19°F from 188°F to 169°F from September 13th to September 16th.
    - The 210-foot thermocouple showed an increase in maximum temperature of 12°F from 197°F to 209°F from September 9th to September 13th, and then a decrease in maximum temperature of 15°F from 209°F to 194°F from September 13th to September 16th.
    - The 265-foot thermocouple remained consistent with previously recorded temperatures.

- TP-25
    - The Site recently conducted a follow-up camera inspection of the TP-25 temperature probe casing to evaluate potential liquid infiltration and assess the condition of the casing interior. The inspection confirmed that no liquid was present at the bottom of the casing. Pressurized landfill gas (LFG) was observed, however, when the probe casing was opened. Based on these observations, the Site believes that the temperature readings at TP-25 may be influenced by LFG entering and moving within the casing and, therefore, may not be representative of in-situ waste temperatures. The elevated temperatures recorded at TP-25 are most likely attributable, at least in part, to LFG intrusion associated with a compromised casing seal. The Site is continuing to monitor TP-25. Temperatures remained consistent with previously recorded temperatures.

- TP-33
    - The 30-foot thermocouple remained consistent with previously recorded temperatures.

We also included an Excel file of the daily maximum temperatures with any high temperatures that triggered the above notification limits highlighted, as requested in the LEA's September 3, 2024, letter.


No other sensors showed major sustained increases or decreases in temperature within the landfill per the LEA's reporting limits and no other sensors showed an anomaly, outlier, data gap, or malfunction, as discussed above. In the past week there were no other recorded temperature increases in the TMP field of greater than 10°F within 7 days or less, greater than 20°F within 14 days or less, or greater than 30°F within 21 days or less.

As stated in Chiquita's response to the LEA's September 3, 2024, and October 4, 2024, adjustments of the temperature notification criteria, we do not believe these notification limits correspond to actual conditions present in a reaction landfill. Temperature is a primary factor in determining the reaction area but increases in temperature from relatively cool temperatures to normal landfill temperatures are not indicative of reaction area movement. As stated in CalRecycle's response to the soil barrier reaction plan received September 24, 2024, presence of in-situ waste temperatures in excess of 230°F would be criteria indicative of a reaction; increases in shallow temperatures below this CalRecycle-suggested threshold are not indicative of a reaction. Additionally, all data and evidence at the landfill continue to show that reaction conditions are present and there is no "smoldering" event as suggested in CalRecycle's September 25, 2024, response that was used as a basis for the LEA's October 4, 2024, letter.

We will continue to update the LEA on the TMP readings.

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS


Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40


Maximum data for 8/6/2026 12:00 AM to 9/16/2026 12:00 AM



SCS ENGINEERS

Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill






BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	179	15
TP02	158	60
TP03	233	45
TP04	159	60
TP05	169	75
TP06	143	100
TP07	208	100
TP08	182	45
TP09	209	125
TP10	159	125
TP11	217	125
TP12	150	125
TP13	180	140
TP14	173	150
TP15	196	100
TP16	160	30
TP17	154	125
TP18	211	45
TP19	239	150
TP20	144	45
TP21	246	110
TP22	199	15
TP23	258	75
TP24	218	265
TP25	268	130
TP26	180	150
TP27	156	100
TP28	145	170
TP29	188	240
TP30	176	190
TP31	193	180
TP32	170	130
TP33	199	45
TP34	153	120
TP35	175	140
TP36	173	165
TP37	185	180
TP38	172	165
TP39	159	160
TP40	150	185

TP-08
The 30-foot and 45-foot thermocouples exhibited temperature increases of 27°F and 29°F, respectively, between July 12, 2026, and July 22, 2026. In response, Site personnel observed the temperature changes and conducted an investigation from July 23, 2026, through July 29, 2026. Following the investigation, temperatures continued to decline at the 30-foot thermocouple from July 30th, 2026, through August 19, 2026, and then temperatures started to increase at the 15, 30, and 45-foot thermocouples from August 20, 2026, through September 12, 2026, then a decrease was observed in the 30 and 45-foot thermocouples from September 12, 2026, through September 16,2026.
TP-08 is installed within extraction well CV-24079, which is equipped with a liquid extraction pump. The investigation determined that the existing pump is experiencing a power-related issue and requires removal. Site personnel were able to remove the pump this week, and cleaned, repaired, reset, and reinstalled it. One potential factor contributing to the observed temperature increase and subsequent decrease is the removal of liquids from wells near TP-08 and in well CV-24079.

TP-19
A discrepancy was identified during the review of data from six weeks prior. Upon investigation, the Site determined that the associated battery had failed and subsequently replaced it. During this inspection, the temperature reading from the 125-foot thermocouple was observed to be anomalously low. Further evaluation indicated that the 125-foot thermocouple required replacement. As an interim measure, the Site installed a 120-foot thermocouple that was available onsite and ordered a replacement 125-foot thermocouple. The replacement 125-foot thermocouple is anticipated to be installed upon receipt in October 2026.

TP-25
The Site recently conducted a follow-up camera inspection of the TP-25 temperature probe casing to evaluate potential liquid infiltration and assess the condition of the casing interior. The inspection confirmed that no liquid was present at the bottom of the casing. Pressurized landfill gas (LFG) was observed, however, when the probe casing was opened. Based on these observations, the Site believes that the temperature readings at TP-25 may be influenced by LFG entering and moving within the casing and, therefore, may not be representative of in-situ waste temperatures. The elevated temperatures recorded at TP-25 are most likely attributable, at least in part, to LFG intrusion associated with a compromised casing seal. The Site is continuing to monitor TP-25. Temperatures remained consistent with previously recorded temperatures.



N

GRAPHIC SCALE

140 70 0 140 280 420

SCALE: 1"=140'

LEGEND

- 1150 — EXISTING TOPOGRAPHIC CONTOUR
- EXISTING CELL LIMITS (APPROXIMATE)
- REACTION MITIGATION AREA BOUNDARY (APPROXIMATE)
- REACTION MITIGATION AREA BOUNDARY - CONDITION 9A
- TP-XX — EXISTING TEMPERATURE PROBE - STANDALONE
- TP-XX — EXISTING TEMPERATURE PROBES - INSTALLED WITHIN WELL CASING

GENERAL DRAWING NOTES:

1. REACTION MITIGATION AREA BOUNDARY ADJUSTMENTS UPDATED SEPTEMBER 10, 2026, BASED ON AUGUST 2026 DATA.
2. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER DATED SEPTEMBER 2, 2026.
3. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

DATE

REVISION

NO.

SHEET TITLE: EXISTING TEMPERATURE PROBE MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544

PROJ. NO. 01204123.45 | DSN. BY: RNH | DWN. BY: CNW | CHK. BY: RNH | ACAD FILE: | APP. BY: RNH

DATE: 09/10/2026

SCALE: AS SHOWN

SHEET: 1

\\san-fs02\Data\Files\Engineers\Waste Connections\Chiquita Canyon LF\2026 TMP Reports\TMP Map Updates\2026-09-10_CCLF_Existing Temperature Probe Map.dwg Sep 10, 2026 - 4:10pm By: cway

Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM

SCS ENGINEERS

07224053.00 | September 24, 2026

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

From September 17, 2026, through September 23, 2026, there were three recorded temperature increases and three recorded temperature decreases that triggered the notification limits set forth in the LEA's October 4, 2024, letter.

Chiquita provides the following updates:

- TP-08
  - The 30-foot thermocouple remained consistent with previously recorded temperatures.
  - The 45-foot thermocouple showed an increase in maximum temperature of 21°F from 158°F to 179°F from September 17th to September 22nd, and then a decrease in maximum temperature of 12°F from 179°F to 167°F from September 22nd to September 23rd.

- TP-13
  - The 100-foot thermocouple showed an increase in maximum temperature of 12°F from 161°F to 173°F from September 18th to September 23rd.


- TP-19
  - A discrepancy was identified during the review of data from seven weeks prior. Upon investigation, the Site determined that the associated battery had failed and subsequently replaced it. During this inspection, the temperature reading from the 125-foot thermocouple was observed to be anomalously low. Further evaluation indicated that the 125-foot thermocouple required replacement. As an interim measure, the Site installed a 120-foot thermocouple that was available onsite and ordered a replacement 125-foot thermocouple. The replacement 125-foot thermocouple is anticipated to be installed upon receipt in October 2026.
  - The 150-foot thermocouple remained consistent with previously recorded temperatures.

- TP-24
  - The 100-foot thermocouple remained consistent with previously recorded temperatures.
  - The 155-foot thermocouple showed a decrease in maximum temperature of 20°F from 188°F to 168°F from September 14th to September 20th.
  - The 210-foot thermocouple showed an increase in maximum temperature of 16°F from 193°F to 209°F from September 18th to September 21st, and then a decrease in maximum temperature of 15°F from 209°F to 194°F from September 21st to September 22nd.

- TP-25
    - The Site recently conducted a follow-up camera inspection of the TP-25 temperature probe casing to evaluate potential liquid infiltration and assess the condition of the casing interior. The inspection confirmed that no liquid was present at the bottom of the casing. Pressurized landfill gas (LFG) was observed, however, when the probe casing was opened. Based on these observations, the Site believes that the temperature readings at TP-25 may be influenced by LFG entering and moving within the casing and, therefore, may not be representative of in-situ waste temperatures. The elevated temperatures recorded at TP-25 are most likely attributable, at least in part, to LFG intrusion associated with a compromised casing seal. The Site is continuing to monitor TP-25. Temperatures remained consistent with previously recorded temperatures.

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39


Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS


Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40

Maximum data for 8/13/2026 12:00 AM to 9/23/2026 12:00 AM



SCS ENGINEERS

Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill




Max Temps - 04:58:45 09-24-2026

Current | 7 Day | 30 Day

BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	177	100
TP02	158	60
TP03	233	45
TP04	159	60
TP05	170	75
TP06	143	100
TP07	208	100
TP08	178	45
TP09	208	125
TP10	159	125
TP11	217	125
TP12	149	125
TP13	179	140
TP14	174	150
TP15	197	100
TP16	160	30
TP17	154	125
TP18	211	45
TP19	239	150
TP20	144	45
TP21	250	110
TP22	199	15
TP23	257	75
TP24	219	265
TP25	272	130
TP26	180	150
TP27	156	100
TP28	145	170
TP29	189	240
TP30	176	190
TP31	194	180
TP32	170	130
TP33	199	45
TP34	153	120
TP35	175	140
TP36	174	165
TP37	186	180
TP38	172	165
TP39	160	160
TP40	150	185

TP-19
A discrepancy was identified during the review of data from seven weeks prior. Upon investigation, the Site determined that the associated battery had failed and subsequently replaced it. During this inspection, the temperature reading from the 125-foot thermocouple was observed to be anomalously low. Further evaluation indicated that the 125-foot thermocouple required replacement. As an interim measure, the Site installed a 120-foot thermocouple that was available onsite and ordered a replacement 125-foot thermocouple. The replacement 125-foot thermocouple is anticipated to be installed upon receipt in October 2026.

TP-25
The Site recently conducted a follow-up camera inspection of the TP-25 temperature probe casing to evaluate potential liquid infiltration and assess the condition of the casing interior. The inspection confirmed that no liquid was present at the bottom of the casing. Pressurized landfill gas (LFG) was observed, however, when the probe casing was opened. Based on these observations, the Site believes that the temperature readings at TP-25 may be influenced by LFG entering and moving within the casing and, therefore, may not be representative of in-situ waste temperatures. The elevated temperatures recorded at TP-25 are most likely attributable, at least in part, to LFG intrusion associated with a compromised casing seal. The Site is continuing to monitor TP-25. Temperatures remained consistent with previously recorded temperatures.



N

GRAPHIC SCALE

140 70 0 140 280 420

SCALE: 1"=140'

LEGEND

- 1150 — EXISTING TOPOGRAPHIC CONTOUR
- EXISTING CELL LIMITS (APPROXIMATE)
- REACTION MITIGATION AREA BOUNDARY (APPROXIMATE)
- REACTION MITIGATION AREA BOUNDARY - CONDITION 9A
- TP-XX — EXISTING TEMPERATURE PROBE - STANDALONE
- TP-XX — EXISTING TEMPERATURE PROBES - INSTALLED WITHIN WELL CASING

GENERAL DRAWING NOTES:

1. REACTION MITIGATION AREA BOUNDARY ADJUSTMENTS UPDATED SEPTEMBER 10, 2026, BASED ON AUGUST 2026 DATA.
2. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER DATED SEPTEMBER 2, 2026.
3. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

DATE

REVISION

NO.

SHEET TITLE: EXISTING TEMPERATURE PROBE MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544

PROJ. NO. 01204123.45 | DSN. BY: RNH | DWN. BY: CNW | CHK. BY: RNH | ACAD FILE: | APP. BY: RNH

DATE: 09/10/2026

SCALE: AS SHOWN

SHEET: 1

\\san-fs02\Data\Files\Engineers\Waste Connections\Chiquita Canyon LF\2026 TMP Reports\TMP Map Updates\2026-09-10_CCLF_Existing Temperature Probe Map.dwg Sep 10, 2026 - 4:10pm By: cway

Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM

SCS ENGINEERS

07224053.00 | October 1, 2026

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

From September 24, 2026, through September 30, 2026, there were no recorded temperature increases and one recorded temperature decrease that triggered the notification limits set forth in the LEA's October 4, 2024, letter.

Chiquita provides the following updates:

- TP-08
  - The 45-foot thermocouple showed a decrease in maximum temperature of 22°F from 179°F to 157°F from September 22nd to September 26th.

- TP-13
  - The 100-foot thermocouple remained consistent with previously recorded temperatures.


- TP-19
  - A discrepancy was identified during the review of data from seven weeks prior. Upon investigation, the Site determined that the associated battery had failed and subsequently replaced it. During this inspection, the temperature reading from the 125-foot thermocouple was observed to be anomalously low. Further evaluation indicated that the 125-foot thermocouple required replacement. As an interim measure, the Site installed a 120-foot thermocouple that was available onsite and ordered a replacement 125-foot thermocouple. The replacement 125-foot thermocouple is anticipated to be installed upon receipt in October 2026.

- TP-24
  - The 155-foot thermocouple remained consistent with previously recorded temperatures.
  - The 210-foot thermocouple remained consistent with previously recorded temperatures.

- TP-25
  - All thermocouples remained consistent with previously recorded temperatures.

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39


Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS


Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40

Maximum data for 8/20/2026 12:00 AM to 9/30/2026 12:00 AM



SCS ENGINEERS

Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill




Max Temps - 04:58:46 10-01-2026

Current | 7 Day | 30 Day

BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	179	100
TP02	158	60
TP03	233	45
TP04	160	60
TP05	170	75
TP06	141	100
TP07	208	100
TP08	170	45
TP09	208	125
TP10	160	125
TP11	217	125
TP12	150	125
TP13	173	140
TP14	174	150
TP15	197	100
TP16	158	30
TP17	154	125
TP18	213	45
TP19	237	150
TP20	144	45
TP21	250	110
TP22	199	15
TP23	257	75
TP24	219	265
TP25	274	130
TP26	180	150
TP27	157	100
TP28	145	170
TP29	188	240
TP30	176	190
TP31	194	180
TP32	171	130
TP33	199	45
TP34	153	120
TP35	175	140
TP36	174	165
TP37	186	180
TP38	172	165
TP39	160	160
TP40	150	185

TP-19
A discrepancy was identified during the review of data from seven weeks prior. Upon investigation, the Site determined that the associated battery had failed and subsequently replaced it. During this inspection, the temperature reading from the 125-foot thermocouple was observed to be anomalously low. Further evaluation indicated that the 125-foot thermocouple required replacement. As an interim measure, the Site installed a 120-foot thermocouple that was available onsite and ordered a replacement 125-foot thermocouple. The replacement 125-foot thermocouple is anticipated to be installed upon receipt in October 2026.



GRAPHIC SCALE

140 70 0 140 280 420

SCALE: 1"=140'

/(*(1'

- EXISTING TOPOGRAPHIC CONTOUR
- EXISTING CELL LIMITS (APPROXIMATE)
- REACTION MITIGATION AREA BOUNDARY (APPROXIMATE)
- REACTION MITIGATION AREA BOUNDARY - CONDITION 9A
- 73 :: EXISTING TEMPERATURE PROBE - STANDALONE
- 73 :: EXISTING TEMPERATURE PROBES - INSTALLED WITHIN WELL CASING

(1(5$/ '5$:,1 127(6

5($&7,21 0,7,*$7,21 $5($ %281'$5< $'-8670(176

83'$7(' 6(37(0%(5 ˇ %$6(' 21 $8*867 ˇ '$7$

(;,67,1* 7232*5$3+,& 6859(< ,1)250$7,21 6+2:1 :$6

3529,'(' %< 3523(///(5 '$7(' 6(37(0%(5 ˇ

1257+ $552: 6+2:1 +(5(,6 5()(5(1&(72 7+(&$/,)251,$

67$7(3/$1(=21(9 &225',1$7(6<67(0 1$' `

DATE

REVISION

NO.

SHEET TITLE: EXISTING TEMPERATURE PROBE MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544

ACAD FILE: PE ENGINEERS

DWN. BY: CNW

CHK. BY: RNH

APP. BY: RNH

PROJ. NO. 01204123.45

DSN. BY: RNH

DATE: 09/10/2026

SCALE: AS SHOWN

SHEET:

Attachment E

October 9, 2026

Reaction Mitigation Area Boundary Determination

October 9, 2026
File No. 01204123.21-13

Mr. Baitong Chen
South Coast Air Quality Management District
21865 Copley Drive
Diamond Bar, California 91765

Subject: Monthly Reaction Mitigation Area Boundary Determination
Chiquita Canyon Landfill – Castaic, California

Dear Mr. Chen:

In accordance with Condition Nos. 9(a) and 9(b) of the Modified Stipulated Order for Abatement (SOFA) pertaining to the Chiquita Canyon Landfill (Landfill or Facility) (Case No. 6177-4), as last modified on June 3, 2026, SCS Engineers (SCS), on behalf of Chiquita Canyon, LLC (Chiquita), has prepared this data-determined Reaction Mitigation Area boundary determination for September 2026 considering the following criteria:

- Vertical landfill gas (LFG) wellhead temperatures (greater than 160 degrees Fahrenheit).
- Temperature monitoring probe (TMP) measurements (greater than 170 degrees Fahrenheit for more than 3-weeks at any depth).
- Landfill gas quality and methane to CO_2 ratio (CH_4:CO_2) (methane concentrations of less than 30 percent in conjunction with CH_4:CO_2 ratios less than 1.0).
- Landfill gas concentration of carbon monoxide (CO) (greater than 1,500 ppm), to the extent measured.
- Landfill gas concentration of hydrogen (H_2) (greater than 2 percent by volume), to the extent measured.
- Landfill settlement (18 inches or greater within a 60-day period).
- Pressurized leachate releases.

These parameters have been subjected to a cumulative evaluation within each individual landfill surface grid within the Main Canyon (i.e., excluding grids 1 through 29 as well as grids 105 through 144), including all landfill gas wells, temperature probes, and other characteristics within that grid's area. For each individual landfill grid that is contiguous to the prior month's Reaction Mitigation Area, where any three or more parameters listed above are present at the time of evaluation, including any combination of wells, temperature probes, or areas within the grid, the Reaction Mitigation Area boundary depicted on the Reaction Mitigation Area map (**Attachment A**) includes such landfill grid(s).

For each individual landfill grid that is not contiguous to the prior month's Reaction Mitigation Area, if the three parameters present include a temperature parameter (the first or second parameter listed above), then the grid has been added to the Reaction Mitigation Area. For each individual landfill grid that is not contiguous to the prior month's Reaction Mitigation Area, if the three parameters present do not include a temperature parameter, then Chiquita conducted field testing for CO using colorimetric tubes and for H2 using field instrumentation. If field testing confirmed the presence of either CO or H2 at concentrations in excess of the lower limits of the instrumentation (100 ppm for

CO and 1 percent by volume for H2), then a sample of the LFG was obtained from the wellhead and subjected to lab analytical testing using U.S. EPA Method ALT-144 for CO and ASTM Method D-1946 for H2. If the lab testing confirmed that either of these parameters exceed the values listed above, then the grid has been added to the Reaction Mitigation Area.

In addition to the parameters listed above, the following factors were also considered in determining the Reaction Mitigation Area boundary, applying the same individual landfill grid-based methodology described above:

- Leachate seeps;
- Odor characteristics;
- Wellheads experiencing conditions which would be expected to result in a pressurized leachate release (e.g., elevated pressure, elevated temperature, liquid flow through wellhead); and,
- Waste cuttings according to borehole drilling logs.

Supporting evidence, including documentation of which parameters were met or exceeded for each individual landfill grid, field testing and laboratory results (if applicable), explanation for the determination, Reaction Mitigation Area boundary, Reaction Mitigation Area map (if applicable), isothermal gradient range map consisting of wellhead temperature measurements, wellhead carbon monoxide range map, wellhead hydrogen range map, wellhead CH_4:CO_2 ratio range map, monthly landfill settlement isopach maps and 60-day isopach map, wellhead and temperature probe map with surface grids displayed, and vertical temperature profiles for temperature probes is being hereby submitted to the South Coast Air Quality Management District.

Attachment A presents the Drawing, titled “Reaction Mitigation Area Map”, which depicts the Reaction Mitigation Area boundary as prescribed in Condition No. 9(a), which corresponds to the limits of Cells 1/2A, 2B/3, 4, and Module 2B/3/4 P2, as a solid black line. The Drawing also depicts the Condition No. 9(b) data-determined Reaction Mitigation Area as a dashed magenta line.

REACTION MITIGATION AREA BOUNDARY

Based on the parameters and considerations above, the Reaction Mitigation Area boundary includes those grids corresponding to the area encompassed by last month’s data-driven Reaction Mitigation Area boundary determination, excluding Grid Nos. 33, 34, 163, and 170, and including Grid Nos. 39, 155, 169, 194, and 195.

Reaction Gas Movement

Based on input from Chiquita, the gas composition exhibited at wells and collectors positioned within surface grids on the eastern portion of the waste mass could be influenced by the presence of reaction gas originating from the northwestern portion of the Landfill. The migration of reaction gas toward the east and south is occurring through horizontal collectors that serve as preferential pathways within the waste matrix. The extensive dewatering efforts have demonstrated to be successful in lowering the elevation of leachate levels measured within the buried waste, which is facilitating more permeable pathways for this movement of reaction gas to the east and south.

Settlement Evaluation

Based on input from Chiquita, the changes in landfill surface elevations that occurred between July 29, 2026 and September 30, 2026 in the following select grids were affiliated with various circumstances other than actual settlement, as described below:

- Grid Nos. 160, 161, 162, 172, 196, 212, and 214 – Attributed to earthwork, grading, and stripping of intermediate cover in preparation for ethylene vinyl alcohol (EVOH) geomembrane cover deployment, or EVOH geomembrane cover repairs, or other related construction activity.
- Grid No. 83, 84, 90, 155, and 163 – Attributed to LFG header pipe regrading or other LFG collection system construction or maintenance.
- Grid Nos. 87, 96, and 97 – Attributed to earthwork and grading affiliated with road construction.
- Grid Nos. 100, 102, 198, 199, 213, 217, and 218 – Attributed to daily cover soil material movement at the working face for internally generated waste or other stockpile activities.

While it is recognized that some settlement in these areas may have occurred, the factors identified above are believed to be the predominant contributors to the elevation changes experienced during August and September. Accordingly, the changes in landfill surface elevations in these grids were not considered to exhibit the landfill settlement criteria during this monthly exercise.

Parameters in Contiguous Grids

- Grid No. 33 is positioned north of Grid No. 34, west of Grid No. 37, northwest of Grid No. 38, and southeast of Grid No. 82. All five of these grids were included in last month's Reaction Mitigation Area boundary. During September, the monitoring data demonstrated that only two parameters conformed to the criteria, one of which was methane concentrations of less than 30 percent in conjunction with CH4:CO2 ratios less than 1.0 at horizontal collector H-1956B. Grid No. 33 also contains TP-37, which exhibited a temperature of greater than 170 degrees Fahrenheit for more than three weeks. Accordingly, Grid No. 33 is being excluded in the Reaction Mitigation Area boundary for this month.
- Grid No. 34 is positioned south of Grid No. 33, southwest of Grid No. 37, and west of Grid No. 38. All four of these grids were included in last month's Reaction Mitigation Area boundary. During September, the monitoring data demonstrated that only two parameters conformed to the criteria, one of which was methane concentrations of less than 30 percent in conjunction with CH4:CO2 ratios less than 1.0 at well CV-24163. Grid No. 34 also contains TP-38, which exhibited a temperature of greater than 170 degrees Fahrenheit for more than three weeks. Accordingly, Grid No. 34 is being excluded in the Reaction Mitigation Area boundary for this month.
- Grid No. 39 is positioned south of Grid No. 38 and southeast of Grid No. 34, and Grid Nos. 38 and 34 were included in last month's Reaction Mitigation Area boundary. The grid contains two wells (CV-24212 and CV-2689) that exhibited methane concentrations of less than 30 percent in conjunction with CH4:CO2 ratios less than 1.0. Well CV-2689 also exhibited H2 concentrations greater than 2 percent by volume. Accordingly, Grid No. 39 is

being included in the Reaction Mitigation Area boundary for this month as a continuous surface grid.

- Grid No. 155 is positioned south of Grid Nos. 149, 154, and 159 and north of Grid No. 160, all of which were included in last month's Reaction Mitigation Area boundary. The grid contains three wells (CV-24093, CV-24159, and CV-2545) that exhibited methane concentrations of less than 30 percent in conjunction with CH4:CO2 ratios less than 1.0. Accordingly, Grid No. 155 is being included in the Reaction Mitigation Area boundary for this month as a continuous surface grid.
- Grid No. 163 is positioned east of Grid No. 164, south of Grid No. 165, and southwest of Grid No. 160. All four of these grids were included in last month's Reaction Mitigation Area boundary. During September, the monitoring data demonstrated that only two parameters conformed to the criteria, one of which was methane concentrations of less than 30 percent in conjunction with CH4:CO2 ratios less than 1.0 at well CV-24173. Grid No. 163 also contains TP-24, which exhibited a temperature of greater than 170 degrees Fahrenheit for more than three weeks. Accordingly, Grid No. 163 is being excluded in the Reaction Mitigation Area boundary for this month.
- Grid No. 169 is surrounded by Grid Nos. 168, 170, 174, and 203, all of which were included in last month's Reaction Mitigation Area boundary. The grid contains two wells (CV-2341 and CV-24050) that exhibited methane concentrations of less than 30 percent in conjunction with CH4:CO2 ratios less than 1.0. Well CV-2341 also exhibited H2 concentrations greater than 2 percent by volume and CO concentrations equal to 1,500 ppmv. Accordingly, Grid No. 169 is being included in the Reaction Mitigation Area boundary for this month as a contiguous grid.
- Grid No. 170 is surrounded by Grid Nos. 166 through 169 and 171 through 174. Of these nine grids, all except Grid No. 169 were included in last month's Reaction Mitigation Area boundary. During September, the monitoring data demonstrated that only two parameters conformed to the criteria, one of which was methane concentrations of less than 30 percent in conjunction with CH4:CO2 ratios less than 1.0 at well CV-2302. Grid No. 170 also contains TP-09, which exhibited a temperature of greater than 170 degrees Fahrenheit for more than three weeks. Accordingly, Grid No. 170 is being excluded in the Reaction Mitigation Area boundary for this month since only two parameters were present.

Parameters in Non-Contiguous Grids

No non-contiguous surface grids were included or excluded as compared to the previous month's boundary.

CONCLUSION

As presented on the Drawing included as **Attachment A**, and for the reasons described above, the extent of the data-determined Reaction Mitigation Area (dashed magenta line) includes Cells 1/2A, 2B/3, 4, and Module 2B/3/4 P2 as decreed in the SOFA (solid black line), and Grid Nos. 37, 38, 39, 41, 53, 76, 77, 79, 81, 82, 145 through 149, and 155.

The maximum temperature measurements recorded at the 40 in-situ waste temperature monitoring probes during the month are presented in **Attachment B** in graphical format. The LFG wellhead temperatures recorded at the extraction wells for the entire Landfill footprint are reflected on the

isothermal gradient range map presented as **Attachment C**. The CH_4:CO_2 ratios measured at the LFG wellheads in the vicinity of the data-driven Reaction Mitigation Area boundary are depicted on the range map presented as **Attachment D**. The H_2 concentrations measured at the LFG wellheads in the vicinity of the data-driven Reaction Mitigation Area boundary are depicted on the range map presented as **Attachment E**. The CO concentrations measured at the LFG wellheads in the vicinity of the data-driven Reaction Mitigation Area boundary are depicted on the range map presented as **Attachment F**. The landfill surface settlement isopach values measured on a monthly basis and 60-day basis in the vicinity of the data-driven Reaction Mitigation Area boundary are depicted on the range map presented as **Attachment G**.

Please contact either of the undersigned if you have questions or require additional information.

Sincerely,

Robert E. Dick, PE, BCEE
Senior Vice President
SCS Engineers

Patrick S. Sullivan, BCES, CCP
Senior Vice President
SCS Engineers

RED/PSS

cc: Nathaniel Dickel, SCAQMD
Christina Ojeda, SCAQMD

Enclosures:


Attachment A – Reaction Mitigation Area Map
Attachment B – In-Situ Waste Temperature Monitoring Probe Data
Attachment C – Isothermal Gradient Range Map
Attachment D – Wellhead Methane-to-Carbon Dioxide Ratio Range Map
Attachment E – Wellhead Hydrogen Range Map
Attachment F – Wellhead Carbon Monoxide Range Map
Attachment G – Settlement Isopach Range Maps

A

Attachment

Reaction Mitigation Area Map

Reaction Mitigation Area Boundary Determination
Chiquita Canyon Landfill
10/09/2026



GENERAL DRAWING NOTES:

1. EXISTING GCCS AS-BUILT DATED SEPTEMBER 30, 2026.
2. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER AERIAL PHOTOGRAPHY DATED SEPTEMBER 30, 2026.
3. APPROXIMATED REACTION MITIGATION AREA BOUNDARY ADJUSTMENTS DATED OCTOBER 10, 2026, BASED ON SEPTEMBER 2026 DATA.
4. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.
5. THE LOCATION OF ANY EXISTING PIPING, VALVES, TIE-IN LOCATIONS AND OTHER FEATURES ARE APPROXIMATE AND SHOULD BE USED FOR INFORMATION PURPOSES ONLY. ACTUAL FIELD CONDITIONS MAY VARY AND ARE SUBJECT TO CHANGE BASED ON TOPOGRAPHIC FEATURES AND SITE-SPECIFIC FACTORS.

NO.	REVISION	DATE

SHEET TITLE: REACTION MITIGATION AREA - SEPTEMBER 2026

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 100
LONG BEACH, CA 90806
PH: (562) 426-9544

PROJ. NO.	01204123.45
DSN. BY:	-
DWN. BY:	RR
CHK. BY:	-
APP. BY:	-

ACAD: R17_CCADASBUILT-MASTER5

DATE: 10/09/2026

SCALE: AS SHOWN

1 of 1

\\asb-fs01\Midlothian\Project\01204123\Reaction Committee\Reaction Area Boundary Determination\2026\2026-10\DWGs\CCLF 2026 Reaction Mitigation Area with Settlement Area & Data Analysis - September 2026_2026-10-07.dwg Oct 08, 2026 - 4:35pm By: raulramirez

B


Attachment

In-Situ Waste Temperature Monitoring Probe Data

Reaction Mitigation Area Boundary Determination
Chiquita Canyon Landfill
10/09/2026

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Apr 15, 2024 Apr 22, 2024 Apr 29, 2024 May 6, 2024 Jul 28, 2026 Aug 4, 2026 Aug 11, 2026
Aug 18, 2026 Aug 25, 2026 Sep 1, 2026 Sep 8, 2026 Sep 15, 2026 Sep 22, 2026
Sep 29, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



Apr 15, 2024 Apr 22, 2024 Apr 29, 2024 May 6, 2024 Jul 28, 2026 Aug 4, 2026 Aug 11, 2026
Aug 18, 2026 Aug 25, 2026 Sep 1, 2026 Sep 8, 2026 Sep 15, 2026 Sep 22, 2026
Sep 29, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Apr 15, 2024
Apr 22, 2024
Apr 29, 2024
May 6, 2024
Jul 28, 2026
Aug 4, 2026
Aug 11, 2026
Aug 18, 2026
Aug 25, 2026
Sep 1, 2026
Sep 8, 2026
Sep 15, 2026
Sep 22, 2026
Sep 29, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Apr 15, 2024 Apr 22, 2024 Apr 29, 2024 May 6, 2024 Jul 28, 2026 Aug 4, 2026 Aug 11, 2026
Aug 18, 2026 Aug 25, 2026 Sep 1, 2026 Sep 8, 2026 Sep 15, 2026 Sep 22, 2026
Sep 29, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Apr 15, 2024 Apr 22, 2024 Apr 29, 2024 May 6, 2024 Jul 28, 2026 Aug 4, 2026 Aug 11, 2026
Aug 18, 2026 Aug 25, 2026 Sep 1, 2026 Sep 8, 2026 Sep 15, 2026 Sep 22, 2026
Sep 29, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Apr 15, 2024 Apr 22, 2024 Apr 29, 2024 May 6, 2024 Jul 28, 2026 Aug 4, 2026 Aug 11, 2026
Aug 18, 2026 Aug 25, 2026 Sep 1, 2026 Sep 8, 2026 Sep 15, 2026 Sep 22, 2026
Sep 29, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Apr 15, 2024 Apr 22, 2024 Apr 29, 2024 May 6, 2024 Jul 28, 2026 Aug 4, 2026 Aug 11, 2026
Aug 18, 2026 Aug 25, 2026 Sep 1, 2026 Sep 8, 2026 Sep 15, 2026 Sep 22, 2026
Sep 29, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Apr 15, 2024 Apr 22, 2024 Apr 29, 2024 May 6, 2024 Jul 28, 2026 Aug 4, 2026 Aug 11, 2026
Aug 18, 2026 Aug 25, 2026 Sep 1, 2026 Sep 8, 2026 Sep 15, 2026 Sep 22, 2026
Sep 29, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Apr 15, 2024 Apr 22, 2024 Apr 29, 2024 May 6, 2024 Jul 28, 2026 Aug 4, 2026 Aug 11, 2026
Aug 18, 2026 Aug 25, 2026 Sep 1, 2026 Sep 8, 2026 Sep 15, 2026 Sep 22, 2026
Sep 29, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Feb 16, 2026 Feb 23, 2026 Mar 2, 2026 Mar 9, 2026 Jul 28, 2026 Aug 4, 2026 Aug 11, 2026
Aug 18, 2026 Aug 25, 2026 Sep 1, 2026 Sep 8, 2026 Sep 15, 2026 Sep 22, 2026
Sep 29, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Feb 16, 2026 Feb 23, 2026 Mar 2, 2026 Mar 9, 2026 Jul 28, 2026 Aug 4, 2026 Aug 11, 2026
Aug 18, 2026 Aug 25, 2026 Sep 1, 2026 Sep 8, 2026 Sep 15, 2026 Sep 22, 2026
Sep 29, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Apr 7, 2025 Apr 14, 2025 Apr 21, 2025 Apr 28, 2025 Jul 28, 2026 Aug 4, 2026 Aug 11, 2026
Aug 18, 2026 Aug 25, 2026 Sep 1, 2026 Sep 8, 2026 Sep 15, 2026 Sep 22, 2026
Sep 29, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Feb 10, 2025 Feb 17, 2025 Feb 24, 2025 Mar 3, 2025 Jul 28, 2026 Aug 4, 2026 Aug 11, 2026
Aug 18, 2026 Aug 25, 2026 Sep 1, 2026 Sep 8, 2026 Sep 15, 2026 Sep 22, 2026
Sep 29, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Feb 10, 2025 Feb 17, 2025 Feb 24, 2025 Mar 3, 2025 Jul 28, 2026 Aug 4, 2026 Aug 11, 2026
Aug 18, 2026 Aug 25, 2026 Sep 1, 2026 Sep 8, 2026 Sep 15, 2026 Sep 22, 2026
Sep 29, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




Feb 10, 2025 Feb 17, 2025 Feb 24, 2025 Mar 3, 2025 Jul 28, 2026 Aug 4, 2026 Aug 11, 2026
Aug 18, 2026 Aug 25, 2026 Sep 1, 2026 Sep 8, 2026 Sep 15, 2026 Sep 22, 2026
Sep 29, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



Dec 15, 2025 Dec 22, 2025 Dec 29, 2025 Jan 5, 2026 Jul 28, 2026 Aug 4, 2026 Aug 11, 2026
Aug 18, 2026 Aug 25, 2026 Sep 1, 2026 Sep 8, 2026 Sep 15, 2026 Sep 22, 2026
Sep 29, 2026

SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39


Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40

Maximum weekly data for initial 4-weeks of operation compared to the latest 10-weeks




SCS ENGINEERS

C

Attachment

Isothermal Gradient Range Map

Reaction Mitigation Area Boundary Determination
Chiquita Canyon Landfill
10/09/2026



GENERAL DRAWING NOTES:

1. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

DATE

REVISION

NO.

SHEET TITLE: ISOTHERMAL GRADIENT MAP SEPTEMBER 2026

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH. (562) 426-9544

ACAD FILE: -
APP. BY: -
DWN. BY: RR
CHK. BY:
PROJ. NO. 01204123.45
DSN. BY: -

DATE: 10/09/2026

SCALE: AS SHOWN

SHEET: 1


F:\Engineers\Waste Connections\Chiquita Canyon LF\2026 Temp Probe Data\Isothermal Gradient Maps\09-September 2026\2026 CCLF Isothermal Map-September 2026_V1.0_2026-10-08.dwg Oct 08, 2026 - 3:46pm By: raulramirez

D

Attachment

Wellhead Methane-to-Carbon Dioxide Ratio Range Map

Reaction Mitigation Area Boundary Determination
Chiquita Canyon Landfill
10/09/2026



Ranges Mapped

						# Points
	>=	0	and	<	0.5	289
	>=	0.5	and	<	0.9	181
	>=	0.9	and	<	1.1	114
	>=	1.1	and	<	1.5	275
	>=	1.5	and	<	100	22

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill

Range Map

Parameter: CH4/CO2 Ratio (mid range)

Analysis Method: Maximum

Date Range: 09/01/2026 - 09/30/2026


Map generation date : 10/09/2026

E

Attachment

Wellhead Hydrogen Range Map

Reaction Mitigation Area Boundary Determination
Chiquita Canyon Landfill
10/09/2026



Ranges Mapped

						# Points
	>=	0	and	<	20000	16
	>=	20000	and	<	50000	19
	>=	50000	and	<	100000	28
	>=	100000	and	<	999999	53

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

The range values noted above are in units of parts per million (ppm). Divide by 10,000 to convert these values to units of percent by volume

N

SCSeTools

Chiquita Canyon Landfill

Range Map

Parameter: H2 (mid range)

Analysis Method: Maximum

Date Range: 09/01/2026 - 09/30/2026


Map generation date : 10/09/2026

F

Attachment

Wellhead Carbon Monoxide Range Map

Reaction Mitigation Area Boundary Determination
Chiquita Canyon Landfill
10/09/2026



Ranges Mapped

						# Points
	>=	0	and	<	500	30
	>=	500	and	<	1000	14
	>=	1000	and	<	1500	26
	>=	1500	and	<	2000	25
	>=	2000	and	<	5000	58
	>=	5000	and	<	100000	1

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill

Range Map

Parameter: CO LAB (mid range)

Analysis Method: Maximum

Date Range: 09/01/2026 - 09/30/2026

Map generation date : 10/09/2026

G

Attachment

Settlement Isopach Range Maps

Reaction Mitigation Area Boundary Determination
Chiquita Canyon Landfill
10/09/2026



N

GRAPHIC SCALE

200 100 0 200 400 600

SCALE: 1"=200'

LEGEND

EXISTING CELL LIMITS (APPROXIMATE)

REACTION MITIGATION AREA BOUNDARY (APPOXIMATE, BASED ON DATA ANALYSIS)

August 26 2026 vs September 30 2026

-10	ft
-1.5	ft
1.5	ft
10	ft

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER, DATED OCTOBER 7, 2026.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.
3. THE LOCATION OF ANY EXISTING GCCS COMPONENTS AND OTHER FEATURES ARE APPROXIMATE AND SHOULD BE USED FOR INFORMATION PURPOSES ONLY.
4. APPROXIMATED REACTION MITIGATION AREA BOUNDARY ADJUSTMENTS DATED OCTOBER 9, 2026, BASED ON SEPTEMBER 2026 DATA.

NO.	REVISION	DATE

SHEET TITLE: 30 DAY SETTLEMENT MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544

PROJ. NO: 01204123.45 | DWN. BY: RR | ACAD FILE: NO RECORD/ASBUILT-MASTERS
DSN. BY: - | CHK. BY: - | APP. BY: -

DATE: 10/09/2025

SCALE: AS SHOWN

SHEET: 1

D:\My Stuff_SCSer's\R: Huber\Chiquita LF\2026 30 and 60 Day Settlement (Isopach)\01-DWG\CCLF MASTER EXISTING GCCS MAP_2026-10-09_(30 Day Isopach).dwg Oct 09, 2026 - 1:25pm By: raultramirez



N

GRAPHIC SCALE

200 100 0 200 400 600


SCALE: 1"=200'

LEGEND

EXISTING CELL LIMITS (APPROXIMATE)

REACTION MITIGATION AREA BOUNDARY (APPOXIMATE, BASED ON DATA ANALYSIS)

July 29 2026 vs September 30 2026



GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER, DATED OCTOBER 7, 2026.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.
3. THE LOCATION OF ANY EXISTING GCCS COMPONENTS AND OTHER FEATURES ARE APPROXIMATE AND SHOULD BE USED FOR INFORMATION PURPOSES ONLY.
4. APPROXIMATED REACTION MITIGATION AREA BOUNDARY ADJUSTMENTS DATED OCTOBER 9, 2026, BASED ON SEPTEMBER 2026 DATA.

NO.	REVISION	DATE

SHEET TITLE: 60 DAY SETTLEMENT MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544

PROJ. NO: 01204123.45 | DWN. BY: RR | ACAD FILE: NOCAD/ASBUILT-MASTERS
DSN. BY: - | CHK. BY: - | APP. BY: -

DATE: 10/09/2025

SCALE: AS SHOWN


SHEET: 1


D:\My Stuff_SCSer's\R: Huber\Chiquita LF\2026 30 and 60 Day Settlement (Isopach)\01-DWG\CCLF MASTER EXISTING GCCS MAP_2026-10-09_(60 Day Isopach).dwg Oct 09, 2026 - 1:27pm By: raultamirez

Attachment F

September 2026 Isopach Map

Chiquita Canyon Landfill -Isopach





Sep 30, 2026 Survey Image. Sep 2, 2026 vs Sep 30, 2026