SCS ENGINEERS

15 de junio de 2026

Karen Gork
Jefa Especialista en Salud Ambiental
Agencia de Aplicación Local del Condado de Los Ángeles
5050 Commerce Drive
Baldwin Park, California 91706

Asunto: Informe Mensual de mayo de 2026 Conforme a los Objetivos 1A-3 y 5 de la Orden de Cumplimiento de la LEA del 6 de junio de 2024 y a la Carta del 30 de julio de 2024, Vertedero de Chiquita Canyon, Castaic, California

Estimada Sra. Gork:

SCS Engineers (SCS), en nombre de Chiquita Canyon, LLC (Chiquita), mediante el presente le proporciona al Programa de Gestión de Desechos Sólidos del Departamento de Salud Pública del Condado de Los Ángeles, que actúa como Agencia de Cumplimiento Local (LEA), un informe mensual, en cumplimiento con los Objetivos 1A-3 y 5 de la Orden de Cumplimiento de la LEA con fecha 6 de junio de 2024 (Orden de Cumplimiento) y la correspondencia posterior relacionada recibida de la LEA. Este informe abarca el período mensual de mayo de 2026.

Chiquita Canyon Landfill (CCL o el Vertedero) es un vertedero/centro de disposición de desechos sólido, ubicado en 29201 Henry Mayo Drive en Castaic, California. Con relación al Vertedero, Chiquita opera un sistema de recolección y control de biogás. SCS elaboró y presentó el Informe Resumido sobre las Lecturas de Monóxido de Carbono e Hidrógeno (Informe Resumido) a la LEA el 6 de junio de 2024 en nombre de Chiquita, en respuesta a las directivas indicadas en las cartas de la LEA con fecha 5 de abril de 2024 y 28 de mayo de 2024, sobre la toma de datos de biogás y conforme al Objetivo 1A-2 de la Orden de Cumplimiento. La LEA, en colaboración con el Departamento de Recursos, Reciclaje y Recuperación de California (CalRecycle), revisó el Informe Resumido y determinó que cumplía con el Objetivo 1A-2. La LEA estableció varios requerimientos nuevos para que Chiquita cumpla con el Objetivo 1A-3 en la correspondencia de seguimiento con fecha 30 de julio de 2024.

Este informe fue elaborado según los Objetivos 1A-3 y 5 de la Orden de Cumplimiento, la correspondencia de seguimiento de la LEA con fecha 30 de julio de 2024, la carta de Chiquita con fecha 3 de septiembre de 2024, la reunión del 12 de septiembre de 2024 con la LEA y la correspondencia de seguimiento de la LEA con fecha 19 y 27 de noviembre y 3 de diciembre de 2024.

Puntos de Cumplimiento con el Objetivo 1A-3

1. Presentar los resultados de los análisis de laboratorio de las muestras mensuales de monóxido de carbono (CO) e hidrógeno (H2) tomadas de un set de pozos de biogás (LFG) seleccionados por la LEA. Consulte en la Tabla 1, las columnas rotuladas "CO" y "H2".

Los resultados de los pozos monitoreados se muestran en el **Adjunto A**.[1] Los datos se están presentando a la LEA en un informe independiente firmado por un ingeniero matriculado, conforme al Objetivo 1A-3 de la Orden de Cumplimiento. Como se indicó en correspondencias previas de Chiquita y en los informes mensuales, este informe no incluye datos de los pozos CV-100, CV-103, CV-1420, CV-1423, CV-1532, CV-2202, H-1403W, H-1560S, H-1774S, SC-2001W, TC-2383S, TC-2385A y TC-2385S,
ya que esos pozos fueron abandonados, ni tampoco del pozo CV-2332, ya que no se instaló nunca. Todos los demás pozos se evaluaron durante el mes de mayo de 2026.

Como se trató en la reunión del 12 de septiembre de 2024 y como se informó previamente, los gráficos que muestran las tendencias de CO y H2 se proporcionan en el **Adjunto D** y se tratan en mayor detalle a continuación.

2. Proporcionar datos de lecturas de gases fijos (CH4, O2 y CO2) entre un set de pozos de LFG seleccionado por la LEA. Consulte en la Tabla 1 la columna rotulada "Gas Fijo CH4, O2, CO2".

Los resultados de los pozos monitoreados se proporcionan en el **Adjunto A**.

3. Tomar temperaturas pozo abajo en 34 pozos, para confirmar las lecturas de las temperaturas de los cabezales de los pozos de gas según el requerimiento de los Estándares de Rendimiento de Fuentes Nuevas (NSPS). Consulte en la Tabla 1 en la columna rotulada "Monitoreo de Temperatura Pozo Abajo".

Chiquita entiende de la correspondencia de la LEA del 27 de noviembre de 2024 y como se indica en los informes mensuales previos, que en este momento solo debe tomar muestras de los pozos a la frecuencia anual indicada en los protocolos NSPS, pero que la LEA podrá requerir monitoreos más frecuentes de hasta diez (10) pozos seleccionados por la LEA. Chiquita está a la espera de la selección de la LEA de esos pozos.

Chiquita proporciona de todos modos en el **Adjunto B** los gráficos de las temperaturas pozo abajo[2] relacionados con los siguientes pozos, desde lugares fijos, que contienen el Sistema de Bombeo Lorentz con los sensores de temperatura integrales mientras estaban en operación durante mayo de 2026: CV-2302, CV-2315, CV-24017, CV-24065 y CV-24095

Se debe tener en cuenta que la bomba Lorentz y/o el sistema de monitoreo de temperatura de las bombas en CV-2301, CV-2303, CV-2350, CV-2351 y CV-2352 estuvieron fuera de línea durante este período de informe debido al despliegue de la geomembrana aprobada de EVOH de 60 milésimas de pulgada, y estuvieron en proceso

[1] Los laboratorios informaron datos de otros pozos de LFG fuera de los seleccionados para que la LEA tome muestras; los datos adicionales están relacionados con requerimientos de informes separados del Distrito de Gestión de la Calidad del Aire de la Costa Sur (AQMD de la Costa Sur) y por lo tanto pueden desestimarse para los propósitos de este informe.
[2] Cada gráfico indica un punto de datos de temperatura único debido a cambios en el software.

de reparación o estuvieron fuera de línea debido a una reducción en las instalaciones de disposición de líquidos fuera del sitio. (Consulte la Lista de Monitoreos del **Adjunto B**).

SCS continuará tomando las temperaturas pozo abajo todos los años e informará los resultados a medida que vaya obteniendo datos de cada lugar. SCS ha realizado el monitoreo anual de las temperaturas pozo abajo en 15 ubicaciones hasta fines de mayo de 2026, como se informó en el último informe mensual (Los resultados se muestran en el **Adjunto B**). El resto de los catorce (14) pozos se va a monitorear según los requerimientos anuales y a medida que se vayan reparando o cambiando las bombas (Consulte **en el Adjunto B las fechas y los lugares restantes de los monitoreos de los pozos**).

4. Tomar muestras de los 40 pozos seleccionados para analizar VOCs utilizando el método TO-15. Consulte en la Tabla 1, la columna rotulada "VOC (TO-15)".

Los resultados de los pozos monitoreados se proporcionan en el **Adjunto A**.[3]. Se debe tener en cuenta que las 31 ubicaciones de toma de muestras de VOC se testearon durante mayo de 2026. No se tomaron muestras en nueve ubicaciones (CV-100, CV-103, CV-1532, CV-2202, H-1403W, H-1560S, H-1758N, H-1774S y TC-2385A) ya que fueron abandonadas.

5. Continuar tomando muestras y monitoreando los 6 pozos horizontales indicados en el Adjunto 1 donde los números de los pozos están resaltados en amarillo. En este momento podrán liberarse 42 pozos horizontales de las tomas de muestras continuas, pero estos pozos podrán ser incluidos más adelante, dependiendo de las futuras presentaciones de datos. Consulte en la Tabla 1 los números de pozo resaltados en azul.

Como se indicó en la carta del 3 de septiembre de 2024 y se informó en los informes mensuales previos, dos (2) de los seis (6) pozos horizontales (H-1774S y H-1560S) fueron abandonados cuando se instalaron los nuevos pozos de extracción vertical. Además, desde ese momento se abandonó H-1403W. Por lo tanto, no están incluidos los datos de esos pozos. Los datos de los otros tres (3) pozos horizontales están en el **Adjunto A**.

6. Agregar 20 pozos verticales a los protocolos de toma de muestras mensuales de temperatura en el cabezal y de LFG. Consulte la Tabla 1.

Como lo transmitió la LEA durante nuestra reunión del 12 de septiembre de 2024 y se volvió a indicar en nuestro informe mensual, comprendemos que la LEA está requiriendo datos analíticos de laboratorio para gases fijos, CO y H2, como también datos de campo. Los resultados del laboratorio están en el **Adjunto A**. Los datos de campo con las temperaturas del gas en el cabezal del pozo se muestran en la Tabla 2 en el **Adjunto A**.

Comprendemos de la correspondencia de la LEA del 27 de noviembre de 2024 que se requerirán datos analíticos del laboratorio para los gases fijos especificados.

Se debe tener en cuenta que nuevamente no se volvieron a tomar muestras en los siguientes pozos en mayo de 2026 por los siguientes motivos indicados en los informes mensuales previos:

[3] El Pozo CV-24142 aparece dos veces en la Tabla 1 de la carta de la LEA del 30 de julio de 2024 - uno requiere tomas de muestras de VOC y el otro no. Chiquita tomó muestras de este pozo para analizar los VOCs.

CV-1420 – Abandonado durante la Expansión del GCCS en 2024 debido a la reducción de los flujos de gas.
CV-2202 – Abandonado durante la Expansión del GCCS en 2024 debido a la reducción de los flujos de gas.
CV-2332 – Este pozo no existe. Este pozo fue propuesto para instalación en otoño de 2023, pero se instalaron otros pozos en la zona en lugar del CV-2332 cuando la cantidad de pozos aumentó según la Orden de Depuración Estipulada (la Orden Estipulada) del Distrito de Gestión de la Calidad del Aire de la Costa Sur (AQMD de la Costa Sur)

7. Trazar en el mapa del sitio denominado "Mapa de GCCS Existentes - Pozos de Extracción Vertical de LFG" con fecha 06/06/2024 las ubicaciones de los siguientes 19 pozos: CV-24002, CV-24003, CV-24007, CV-24017, CV-24053, CV-24055, CV-24065, CV-24071, CV-24075, CV-24077, CV-24079, CV-24082, CV-24083, CV-24088, CV-24095, CV-24096, CV-24097, CV-24098 y H-1403W. Para el pozo H-1403W, proporcionar la ubicación horizontal de las tuberías y un estimativo sobre dónde es más probable que ocurran temperaturas elevadas (195 °F). Consultar en la Tabla 1 los números de pozo resaltados en rojo y H-1403W (resaltado en amarillo).

Las ubicaciones de los pozos arriba identificados se muestran en el Mapa en el **Adjunto C**.[4]

8. Incluir en el informe mensual un mapa del asentamiento/calor como se muestra a continuación, comenzando con los datos del mapa de calor más antiguo disponible para cada mes hasta el presente. Si es posible, los mapas topográficos deberán mostrar intervalos de contornos de 2 pies.

La LEA le indicó a Chiquita el 2 de junio de 2025 que presente mapas isopáquicos mensualmente para cumplir con esta solicitud. Para facilidad de referencia, estamos presentando el 9 de junio de 2026 como **Adjunto F** una copia del mapa isopáquico de mayo de 2026, que se presentó inicialmente a la LEA con los registros de cubiertas semanales.

9. Proporcionar los resultados de las tomas de muestras en un informe independiente apropiado con el análisis, tablas, AQ/QC y métodos, firmado por un profesional registrado, etc., como se describe en los Objetivos 1A-2 y 1A-3 de la Orden de Cumplimiento.

CCL ha proporcionado la información arriba solicitada y los datos crudos en el **Adjunto A**, como también una figura con la zona reactiva indicada en base a datos, que incorpora datos de asentamientos (consulte el **Adjunto F**). Se proporcionan los gráficos de las temperaturas de los pozos con bombas Lorentz (4 lugares).

Se debe tener en cuenta que además de los pozos indicados en respuesta a la solicitud con fecha 30 de julio de 2024 (en la Tabla 1) que no pudieron ser testeados, tampoco pudieron testearse los siguientes pozos que solo requerían datos analíticos, como se informó previamente, porque fueron abandonados durante la expansión del GCCS de 2024 y 2025 debido a la reducción de flujos de gas, conforme a los requerimientos del NSPS: CV-100, CV-103, CV-1420, CV-1423, CV-1532, CV-2202,

[4] La LEA reconoció en su correspondencia del 20 de noviembre de 2024 que no están ocurriendo temperaturas altas en el pozo H-1403W. Por lo tanto, no trazamos la temperatura máxima en el pozo H-1403W.

H-1403W, H-1560S, H-1774S, SC-2001W, TC-2383S, TC-2385A y TC-2385S. Finalmente, como también se informó previamente, nunca se instaló el CV-2332.

Procedimientos para la Toma de Muestras

Se tomaron muestras de gas utilizando bolsas Tedlar o Mylar, como se describe en la carta del Chiquita del 3 de septiembre de 2024 y en los informes mensuales que se entregaron a laboratorios certificados para su análisis. Todos los datos de gases permanentes (CH4, CO2, O2, N2, CO y H2) fueron analizados dentro de las 24 horas solicitadas desde la toma de las muestras. SCS continúa creyendo que el uso del tiempo de retención de 72 horas aprobado por EPA para estas muestras sería apropiado y correcto. Sin embargo, en respuesta a la correspondencia de la LEA del 17 de marzo de 2025, SCS continuará solicitando tiempos de retención de 24 horas para todos los gases fijos, que incluyen CO, H2 y VOCs tomados utilizando bolsas Mylar o Tedlar. No obstante, si se requieren más muestras o si los laboratorios tienen un cambio en la carga de trabajo, este tiempo de retención podrá cambiar, caso en el que se le informará a la LEA como corresponda. Durante mayo de 2026, se testearon los VOCs de todos los pozos (método TO-15 de la EPA) y los gases permanentes (métodos 1946 y Alt-144 de la EPA) dentro de las 24 horas, proporcionándole al laboratorio muestras en bolsas duplicadas como se requiere para análisis VOCs.

Se tomaron otros datos de los gases y las presiones utilizando un Medidor de Gas Envision Irwin o un dispositivo de monitoreo de Gases Landtec GEM 5000. Estos instrumentos miden las concentraciones de gas combustible en el aire, directamente en una de dos escalas: la primera, como un porcentaje por volumen del límite explosivo inferior (LEL) de gas metano en el aire (0 a 5 por ciento) y el otro como un porcentaje por volumen (0 a 100 por ciento) en el gas tomado como muestra. El límite de detección de estos instrumentos es de aproximadamente 0.10 por ciento por volumen.

Los procedimientos para testear el monitoreo de gases fueron los siguientes:

- Conectar la tubería de toma de muestras, abrir la válvula de prueba, observar la presión y registrar los datos.
- Encender la bomba de las muestras, purgar un mínimo de un volumen de la sonda y observar y registrar las concentraciones de metano, oxígeno y dióxido de carbono en el gas cuando se hayan estabilizado las lecturas.
- Cerrar la válvula de prueba, desconectar los instrumentos de toma de muestras y resguardar la ubicación de la muestra.

Conclusiones del Objetivo 1A-3

En mayo de 2026 se realizó el vigésimo segundo monitoreo en cumplimiento con el Objetivo 1A-3 de la Orden de Cumplimiento. Los datos tomados en mayo de 2026 y evaluados para este informe son consistentes con los datos tomados los meses anteriores desde agosto de 2024 hasta abril de 2026, como también los datos tomados y evaluados por peritos técnicos de Chiquita en cumplimiento con la Orden Estipulada para evaluar el Área de Mitigación de Reacciones, que incluyen los datos de mayo de 2026 más recientemente evaluados el 10 de junio de 2026 como lo requieren las Condiciones 9(a) y 9(b) de la Orden Estipulada, modificada más recientemente el 4 de junio de 2026. (Consulte el **Adjunto E**.)

Por los motivos descritos en la determinación del límite adjunta del 10 de junio de 2026, el alcance del Área de Mitigación de Reacciones determinado por datos (línea de puntos magenta) está completamente contenido dentro del límite del Área de Mitigación de Reacciones decretado en la SOFA (línea sólida negra), excepto para las Cuadrículas No. 38, 41, 53, 76, 77, 82 y 145 a 149, de las que todo o parte sobresale hacia el este, más allá del límite de la Celda 1/2A. Como el Área de Mitigación de Reacciones dirigida por datos no está completamente contenida dentro del límite del Área de Mitigación de Reacciones, se modifica el límite del Área de Mitigación de Reacciones como lo indica la Condición No. 9a para incluir partes de estas Cuadrículas que se extienden más allá del límite de la Celda 1/2A.

- Se está incorporando la Cuadrícula No. 38 en base al criterio de mala calidad del LFG;
- Se está incorporando la Cuadrícula No. 41 en base a los criterios de mala calidad del LFG y de hidrógeno;
- Se está incorporando la Cuadrícula No. 53 en base a los criterios para la temperatura en las TMP y a la mala calidad del LFG;
- Se está incorporando la Cuadrícula No. 77 en base a los criterios para la temperatura en las TMP, a la mala calidad del LFG y a la concentración de CO;
- Se está incorporando la Cuadrícula No. 82 en base a los criterios de mala calidad del LFG, hidrógeno y CO;

Como los niveles de líquido fluctúan debido al corte y el actual reinicio de varias Bombas Eléctricas y Neumáticas Lorentz, hemos observado los porcentajes de los Gases Permanentes, del Monóxido de Carbono y de Hidrógeno y el cambio de temperatura a medida que estos gases van moviéndose hacia los pozos de extracción para su remoción. Esto se continúa demostrando en los gráficos de los pozos a varias escalas en el **Adjunto D**, que incluyen gráficos de los gases permanentes, temperatura y otras tendencias en un período de doce (12) meses. Se debe tener en cuenta que los gráficos fueron creados utilizando resultados de equipos de monitoreo de biogás estándar y los resultados no contienen datos de laboratorio. SCS también incluyó gráficos de Hidrógeno y Monóxido de Carbono separados utilizando los resultados del laboratorio, para su uso y revisión de cada pozo.

Además, la instalación de tuberías de mayor diámetro ha mejorado la recolección de otros gases de todo el Vertedero. Desde marzo de 2025, los índices de flujo de biogás que queman los dispositivos de depuración variaron de 13,500 cfm a 16,700 cfm. Durante mayo de 2026, la extracción de gas general del Vertedero fue de aproximadamente 645.851.520 pies cúbicos. El ritmo de extracción de biogás diario de mayo fue levemente menor al ritmo de abril debido a problemas con el soplador, a que se limpió la antorcha y a otras mejoras del GCCS. Se prevén futuros aumentos de este índice de extracción a medida que los sistemas de recolección continúen expandiéndose y se espera que la composición del gas de los pozos de la zona reactiva mejore a medida vaya habiendo más vacío, se vaya removiendo el líquido y el movimiento de gas resultante permita más reacción y se extraiga biogás normal.

Chiquita continuará evaluando los datos en futuros informes mensuales, a medida que se vayan tomando más datos.

Puntos de Cumplimiento con el Objetivo 5

Este informe incluye en el **Adjunto D** mapas individuales superpuestos con los siguientes datos para mayo de 2026, en un formato fácil de comprender, conforme al Objetivo 5 de la Orden de Cumplimiento.

- Zona reactiva definida;
- Expansión de la zona reactiva, si hubiera;
- Datos semanales de TMP; y
- Datos de LFG que incluyen, de forma enunciativa más no limitativa, datos de CH4, CO2, O2, Temperatura CO y de H2.

El Objetivo 5 además requiere "asentamiento con mapas de calor", pero como se analizó al principio de este informe y conforme a la correspondencia de la LEA con fecha 27 de noviembre y 3 de diciembre de 2024, este requerimiento se cumple con la presentación de Chiquita de sus mapas isopáquicos mensuales, presentados a la LEA, que se realizaron el 9 de junio de 2026. Para practicidad de la LEA, el mapa isopáquico de mayo de 2026 se incluye aquí como **Adjunto F**.

Los abajo firmantes son un profesional matriculado/vicepresidente superior, el gerente de proyectos del sitio y un Gerente Regional, Vicepresidente de SCS Engineers.

Atentamente,

Rachelle Huber
Administrador del Proyecto
SCS Engineers

Arthur E Jones Jr.
Vicepresidente
SCS Engineers

Srividhya Viswanathan, P.E.*
Vicepresidente Sénior
SCS Engineers

Adjuntos:

Adjunto A - Análisis de Laboratorio y Datos de los Instrumentos de Extracción de LFG de los Pozos y de los Datos de las Temperaturas
Adjunto B – Temperaturas Pozo Abajo y Lista de Pozos para Monitoreo
Adjunto C – Punto 7 - Mapa de Ubicación de Pozos

Adjunto D - Datos de Cumplimiento con el Objetivo 5
Adjunto E - Informe del Área de Mitigación de Reacciones del 10 de Junio de 2026
Adjunto F - Mapa Isopáquico de Mayo de 2026

Los Datos Electrónicos de los Resultados del Laboratorio y los datos de los Pozos de Extracción están en formato Excel, con PDFs adicionales para los datos de los pozos de gas.

cc: John Perkey, Chiquita Canyon
Kevin Green, Chiquita Canyon
William Haley, Chiquita Canyon
Dylan Smith, Chiquita Canyon
Sarah Phillips, Chiquita Canyon
Pat Sullivan, SCS Engineers
Liza Frías, Departamento de Salud Pública del Condado de Los Ángeles
Nichole Quick, M.D., Departamento de Salud Pública del Condado de Los Ángeles
Beverly Tway, LEA del Condado de Los Ángeles
Eric Morofuji, LEA del Condado de Los Ángeles
Renee Jensen, Asesor de LEA
Blaine McPhillips, Asesor Suplente Sénior del Condado
Emiko Thompson, Departamento de Obras Públicas del Condado de Los Ángeles
Alex Garcia, Departamento de Planificación Regional del Condado de Los Ángeles
Phillip Chen, Departamento de Planificación Regional del Condado de Los Ángeles
Steven Jareb, Departamento de Planificación Regional del Condado de Los Ángeles
Wes Mindermann, CalRecycle
Todd Thalhamer, CalRecycle
Emel Wadhwani, CalRecycle
Jeff Linberg, Junta de Recursos de Aire de California
Nancy Fletcher, Junta de Recursos de Aire de California
Jack Cheng, Consejo de Gestión de la Calidad del Aire de la Costa Sur
Larry Israel, Consejo de Gestión de la Calidad del Aire de la Costa Sur
Enrique Casas, Junta Regional de Control de Calidad del Agua de Los Ángeles
Joshua Wirtschafter, Agencia de Protección Ambiental de Estados Unidos
Laura Friedli, Agencia de Protección Ambiental de Estados Unidos
Tyler Holybee, Agencia de Protección Ambiental de Estados Unidos
Mark Anthony Relon, Agencia de Protección Ambiental de Estados Unidos
Gregory Schaffer, Departamento de Control de Sustancias Tóxicas
Natasha DiPietro, Departamento de Control de Sustancias Tóxicas
Gregory Gentile, Departamento de Control de Sustancias Tóxicas

Attachment A

Laboratory Analysis

And

LFG Extraction Well Instrument and Temperature Data

SGS

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175

TX Cert T104704450-14-6
EPA Methods TO14A, TO15

ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

May 19, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T050401-01/10

Enclosed are the results for sample(s) received 5/4/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags. High recovery was exhibited for chlorobenzene in the internal standard indicating a possible low bias. Effected results are flagged with the Q qualifier.
- High recovery was exhibited in the continuing calibration verification for 4-ethyl toluene and isopropanol indicating a possible bias. Results are flagged with the Q qualifier.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

Preliminary results were e-mailed to Cornelius Fong, Jenny Kim, Art Jones and Ali Ferrara on 5/18/26.

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐ No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐ No ☐
Other:				Level 4	☐	Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:	
Bill to:	07FSAccountspayable@scsengineers.com
	3900 Kilroy Airport Way, Suite 300
	Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T050401-01	CV-113	05/04/26	7:50am	2-1L	Gas	N	X	X	X	X		
-02	CV-2007	05/04/26	8:10am	2-1L	Gas	N	X	X	X	X		
-03	CV-24122	05/04/26	8:20am	2-1L	Gas	N	X	X	X	X		
-04	CV-24127	05/04/26	8:15am	2-1L	Gas	N	X	X	X	X		
-05	H-1770N	05/04/26	8:50am	2-1L	Gas	N	X	X	X	X		
-06	CV-24121	05/04/26	7:55am	1L	Gas	N	X	X	X			
-07	CV-24123	05/04/26	7:40am	1L	Gas	N	X					
-08	CV-99	05/04/26	7:45am	1L	Gas	N	X	X	X			
-09	CV-114	05/04/26	8:05am	1L	Gas	N	X	X	X			
-10	CV-24120	05/04/26	8:00am	1L	Gas	N	X	X	X			

	COMPANY	DATE/TIME			
AUTHORIZATION TO PERFORM WORK	SCS				
SAMPLED BY: Fabian Chavez	SCS	5/4/26			
RELINQUISHED BY	DATE/TIME 5/4/26 9:15am	RECEIVED BY	DATE/TIME 5/4/26 9:16		
RELINQUISHED BY	DATE/TIME 5/4/26 11:29	RECEIVED BY	DATE/TIME 5/4/26 11:29		
RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME		

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: H=HCl N=None / Container: B=Bag C=Can V=VOA O=Other *Rev. 03 - 5/7/09*

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/04/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T050401-01		T050401-02		T050401-03		T050401-04	
Client Sample I.D.:	CV-113		CV-2007		CV-24122		CV-24127	
Date/Time Sampled:	5/4/26 7:50		5/4/26 8:10		5/4/26 8:20		5/4/26 8:15	
Date/Time Analyzed:	5/4/26 18:14		5/4/26 18:52		5/4/26 19:31		5/4/26 20:09	
QC Batch No.:	260504MS2A1		260504MS2A1		260504MS2A1		260504MS2A1	
Analyst Initials:	AS/GD		AS/GD		AS/GD		AS/GD	
Dilution Factor:	5,000		1,000		1,500		5,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	5,000	ND	1,000	ND	1,500	ND	5,000
Chloromethane	ND	5,000	ND	1,000	ND	1,500	**11,000**	5,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	5,000	ND	1,000	ND	1,500	ND	5,000
Vinyl Chloride	ND	5,000	ND	1,000	ND	1,500	ND	5,000
Bromomethane	ND	5,000	ND	1,000	ND	1,500	ND	5,000
Chloroethane	ND	25,000	ND	5,000	ND	7,500	ND	25,000
Trichlorofluoromethane (11)	ND	5,000	ND	1,000	ND	1,500	ND	5,000
1,1-Dichloroethene	ND	5,000	ND	1,000	ND	1,500	ND	5,000
Carbon Disulfide	ND	5,000	ND	1,000	ND	1,500	ND	5,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	5,000	ND	1,000	ND	1,500	ND	5,000
Acetone	**68,000**	25,000	**86,000**	5,000	**120,000**	7,500	**370,000**	25,000
Methylene Chloride	ND	5,000	ND	1,000	ND	1,500	ND	5,000
t-1,2-Dichloroethene	ND	5,000	ND	1,000	ND	1,500	ND	5,000
1,1-Dichloroethane	ND	5,000	ND	1,000	ND	1,500	ND	5,000
Vinyl Acetate	ND	5,000	ND	1,000	ND	1,500	ND	5,000
c-1,2-Dichloroethene	ND	5,000	ND	1,000	ND	1,500	ND	5,000
2-Butanone	**49,000**	25,000	**110,000**	5,000	**120,000**	7,500	**380,000**	25,000
t-Butyl Methyl Ether (MTBE)	ND	5,000	**1,400**	1,000	ND	1,500	ND	5,000
Chloroform	ND	5,000	ND	1,000	ND	1,500	ND	5,000
1,1,1-Trichloroethane	ND	5,000	ND	1,000	ND	1,500	ND	5,000
Carbon Tetrachloride	ND	5,000	ND	1,000	ND	1,500	ND	5,000
Benzene	**110,000**	5,000	**150,000**	1,000	**31,000**	1,500	**250,000**	5,000
1,2-Dichloroethane	ND	5,000	ND	1,000	ND	1,500	ND	5,000
Trichloroethene	ND	5,000	ND	1,000	ND	1,500	ND	5,000
1,2-Dichloropropane	ND	5,000	ND	1,000	ND	1,500	ND	5,000
Bromodichloromethane	ND	5,000	ND	1,000	ND	1,500	ND	5,000
c-1,3-Dichloropropene	ND	5,000	ND	1,000	ND	1,500	ND	5,000
4-Methyl-2-Pentanone	ND	5,000	**4,100**	1,000	**2,400**	1,500	**6,300**	5,000
Toluene	ND	5,000	**8,000**	1,000	**3,100**	1,500	**12,000**	5,000
t-1,3-Dichloropropene	ND	10,000	ND Q	2,000	ND Q	3,000	ND Q	10,000
1,1,2-Trichloroethane	ND	5,000	ND Q	1,000	ND Q	1,500	ND Q	5,000
Tetrachloroethene	ND	5,000	ND Q	1,000	ND Q	1,500	ND Q	5,000
2-Hexanone	ND	5,000	**1,300** Q	1,000	ND Q	1,500	ND Q	5,000
Dibromochloromethane	ND	5,000	ND Q	1,000	ND Q	1,500	ND Q	5,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/04/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T050401-01		T050401-02		T050401-03		T050401-04	
Client Sample I.D.:	CV-113		CV-2007		CV-24122		CV-24127	
Date/Time Sampled:	5/4/26 7:50		5/4/26 8:10		5/4/26 8:20		5/4/26 8:15	
Date/Time Analyzed:	5/4/26 18:14		5/4/26 18:52		5/4/26 19:31		5/4/26 20:09	
QC Batch No.:	260504MS2A1		260504MS2A1		260504MS2A1		260504MS2A1	
Analyst Initials:	AS/GD		AS/GD		AS/GD		AS/GD	
Dilution Factor:	5,000		1,000		1,500		5,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	5,000	ND Q	1,000	ND Q	1,500	ND Q	5,000
Chlorobenzene	ND	5,000	ND Q	1,000	ND Q	1,500	ND Q	5,000
Ethylbenzene	ND	5,000	ND Q	1,000	ND Q	1,500	ND Q	5,000
p,&m-Xylene	ND	10,000	ND Q	2,000	ND Q	3,000	ND Q	10,000
o-Xylene	ND	5,000	ND Q	1,000	ND Q	1,500	ND Q	5,000
Styrene	ND	5,000	ND Q	1,000	ND Q	1,500	ND Q	5,000
Bromoform	ND	5,000	ND Q	1,000	ND Q	1,500	ND Q	5,000
1,1,2,2-Tetrachloroethane	ND	5,000	ND Q	1,000	ND Q	1,500	ND Q	5,000
Benzyl Chloride	ND	5,000	ND Q	1,000	ND Q	1,500	ND Q	5,000
4-Ethyl Toluene	ND	5,000	ND Q	1,000	ND Q	1,500	ND Q	5,000
1,3,5-Trimethylbenzene	ND	5,000	ND Q	1,000	ND Q	1,500	ND Q	5,000
1,2,4-Trimethylbenzene	ND	5,000	ND Q	1,000	ND Q	1,500	ND Q	5,000
1,3-Dichlorobenzene	ND	5,000	ND Q	1,000	ND Q	1,500	ND Q	5,000
1,4-Dichlorobenzene	ND	5,000	ND Q	1,000	ND Q	1,500	ND Q	5,000
1,2-Dichlorobenzene	ND	5,000	ND Q	1,000	ND Q	1,500	ND Q	5,000
1,2,4-Trichlorobenzene	ND	5,000	ND Q	1,000	ND Q	1,500	ND Q	5,000
Hexachlorobutadiene	ND	5,000	ND Q	1,000	ND Q	1,500	ND Q	5,000
1,3-Butadiene	ND	25,000	6,700	5,000	ND	7,500	ND	25,000
Isopropanol	68,000 Q	25,000	98,000 Q	5,000	110,000 Q	7,500	120,000 Q	25,000
n-Hexane	ND	25,000	ND	5,000	ND	7,500	ND	25,000
Ethyl Acetate	ND	25,000	16,000	5,000	9,100	7,500	69,000	25,000
Tetrahydrofuran	61,000 Q	25,000	160,000 Q	5,000	86,000 Q	7,500	330,000 Q	25,000
Cyclohexane	ND	25,000	ND	5,000	ND	7,500	ND	25,000
Heptane	ND	25,000	8,800	5,000	ND	7,500	ND	25,000
1,4-Dioxane	ND	25,000	ND	5,000	ND	7,500	ND	25,000

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Refer to report narrative

Reviewed/Approved By: _____ Date 5-18-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/04/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T050401-05
Client Sample I.D.:	H-1770N
Date/Time Sampled:	5/4/26 8:50
Date/Time Analyzed:	5/4/26 20:48
QC Batch No.:	260504MS2A1
Analyst Initials:	AS/GD
Dilution Factor:	1,200

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	1,200
Chloromethane	ND	1,200
1,2-Cl-1,1,2,2-F ethane (114)	ND	1,200
Vinyl Chloride	ND	1,200
Bromomethane	ND	1,200
Chloroethane	ND	6,000
Trichlorofluoromethane (11)	ND	1,200
1,1-Dichloroethene	ND	1,200
Carbon Disulfide	ND	1,200
1,1,2-Cl 1,2,2-F ethane (113)	ND	1,200
Acetone	95,000	6,000
Methylene Chloride	ND	1,200
t-1,2-Dichloroethene	ND	1,200
1,1-Dichloroethane	ND	1,200
Vinyl Acetate	ND	1,200
c-1,2-Dichloroethene	ND	1,200
2-Butanone	120,000	6,000
t-Butyl Methyl Ether (MTBE)	ND	1,200
Chloroform	ND	1,200
1,1,1-Trichloroethane	ND	1,200
Carbon Tetrachloride	ND	1,200
Benzene	150,000	1,200
1,2-Dichloroethane	ND	1,200
Trichloroethene	ND	1,200
1,2-Dichloropropane	ND	1,200
Bromodichloromethane	ND	1,200
c-1,3-Dichloropropene	ND	1,200
4-Methyl-2-Pentanone	4,000	1,200
Toluene	8,600	1,200
t-1,3-Dichloropropene	ND	2,400
1,1,2-Trichloroethane	ND	1,200
Tetrachloroethene	ND	1,200
2-Hexanone	ND	1,200
Dibromochloromethane	ND	1,200

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/04/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T050401-05
Client Sample I.D.:	H-1770N
Date/Time Sampled:	5/4/26 8:50
Date/Time Analyzed:	5/4/26 20:48
QC Batch No.:	260504MS2A1
Analyst Initials:	AS/GD
Dilution Factor:	1,200

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	1,200
Chlorobenzene	ND	1,200
Ethylbenzene	ND	1,200
p,&m-Xylene	ND	2,400
o-Xylene	ND	1,200
Styrene	ND	1,200
Bromoform	ND	1,200
1,1,2,2-Tetrachloroethane	ND	1,200
Benzyl Chloride	ND	1,200
4-Ethyl Toluene	ND	1,200
1,3,5-Trimethylbenzene	ND	1,200
1,2,4-Trimethylbenzene	ND	1,200
1,3-Dichlorobenzene	ND	1,200
1,4-Dichlorobenzene	ND	1,200
1,2-Dichlorobenzene	ND	1,200
1,2,4-Trichlorobenzene	ND	1,200
Hexachlorobutadiene	ND	1,200
1,3-Butadiene	ND	6,000
Isopropanol	100,000 Q	6,000
n-Hexane	ND	6,000
Ethyl Acetate	14,000	6,000
Tetrahydrofuran	170,000 Q	6,000
Cyclohexane	ND	6,000
Heptane	11,000	6,000
1,4-Dioxane	ND	6,000

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Refer to report narrative

Reviewed/Approved By: _____ Date 5-18-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/04/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	Method Blank							
Client Sample I.D.:	-							
Date/Time Sampled:	-							
Date/Time Analyzed:	5/4/26 14:01							
QC Batch No.:	260504MS2A1							
Analyst Initials:	AS/GD							
Dilution Factor:	0.20							

ANALYTE	Result ppbv	RL ppbv						
Dichlorodifluoromethane (12)	ND	0.20						
Chloromethane	ND	0.20						
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20						
Vinyl Chloride	ND	0.20						
Bromomethane	ND	0.20						
Chloroethane	ND	1.0						
Trichlorofluoromethane (11)	ND	0.20						
1,1-Dichloroethene	ND	0.20						
Carbon Disulfide	ND	0.20						
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20						
Acetone	ND	1.0						
Methylene Chloride	ND	0.20						
t-1,2-Dichloroethene	ND	0.20						
1,1-Dichloroethane	ND	0.20						
Vinyl Acetate	ND	0.20						
c-1,2-Dichloroethene	ND	0.20						
2-Butanone	ND	1.0						
t-Butyl Methyl Ether (MTBE)	ND	0.20						
Chloroform	ND	0.20						
1,1,1-Trichloroethane	ND	0.20						
Carbon Tetrachloride	ND	0.20						
Benzene	ND	0.20						
1,2-Dichloroethane	ND	0.20						
Trichloroethene	ND	0.20						
1,2-Dichloropropane	ND	0.20						
Bromodichloromethane	ND	0.20						
c-1,3-Dichloropropene	ND	0.20						
4-Methyl-2-Pentanone	ND	0.20						
Toluene	ND	0.20						
t-1,3-Dichloropropene	ND	0.40						
1,1,2-Trichloroethane	ND	0.20						
Tetrachloroethene	ND	0.20						
2-Hexanone	ND	0.20						
Dibromochloromethane	ND	0.20						

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/04/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	Method Blank
Client Sample I.D.:	-
Date/Time Sampled:	-
Date/Time Analyzed:	5/4/26 14:01
QC Batch No.:	260504MS2A1
Analyst Initials:	AS/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	0.20
Chlorobenzene	ND	0.20
Ethylbenzene	ND	0.20
p,&m-Xylene	ND	0.40
o-Xylene	ND	0.20
Styrene	ND	0.20
Bromoform	ND	0.20
1,1,2,2-Tetrachloroethane	ND	0.20
Benzyl Chloride	ND	0.20
4-Ethyl Toluene	ND	0.20
1,3,5-Trimethylbenzene	ND	0.20
1,2,4-Trimethylbenzene	ND	0.20
1,3-Dichlorobenzene	ND	0.20
1,4-Dichlorobenzene	ND	0.20
1,2-Dichlorobenzene	ND	0.20
1,2,4-Trichlorobenzene	ND	0.20
Hexachlorobutadiene	ND	0.20
1,3-Butadiene	ND	1.0
Isopropanol	ND	1.0
n-Hexane	ND	1.0
Ethyl Acetate	ND	1.0
Tetrahydrofuran	ND	1.0
Cyclohexane	ND	1.0
Heptane	ND	1.0
1,4-Dioxane	ND	1.0

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 5-18-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 260504MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	5/4/26 14:01			5/4/26 12:45		5/4/26 13:23					
Analyst Initials:	AS/GD			AS/GD		AS/GD					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	0.20	10	12.6	126	12.4	124	1.7	70	130	30
Methylene Chloride	ND	0.20	10	11.6	116	11.7	117	0.4	70	130	30
Trichloroethene	ND	0.20	10	12.1	121	11.9	119	1.8	70	130	30
Toluene	ND	0.20	10	11.9	119	12.0	120	0.4	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	9.79	98	9.93	99	1.4	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date: 5-18-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/04/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T050401-01		T050401-02		T050401-03		T050401-04	
Client Sample I.D.:	CV-113		CV-2007		CV-24122		CV-24127	
Date/Time Sampled:	5/4/26 7:50		5/4/26 8:10		5/4/26 8:20		5/4/26 8:15	
Date/Time Analyzed:	5/4/26 14:46		5/4/26 15:01		5/4/26 15:15		5/4/26 15:30	
QC Batch No.:	260504GC8A1		260504GC8A1		260504GC8A1		260504GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	1,400	10	810	10	180	10	3,300	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-12-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/04/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T050401-05		T050401-06		T050401-08		T050401-09	
Client Sample I.D.:	H-1770N		CV-24121		CV-99		CV-114	
Date/Time Sampled:	5/4/26 8:50		5/4/26 7:55		5/4/26 7:45		5/4/26 8:05	
Date/Time Analyzed:	5/4/26 15:44		5/4/26 15:58		5/4/26 16:27		5/4/26 16:42	
QC Batch No.:	260504GC8A1		260504GC8A1		260504GC8A1		260504GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	81	10	120	10	110	10	ND	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-12-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com

Member of the SGS Group (SGS SA)

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/04/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T050401-10							
Client Sample I.D.:	CV-24120							
Date/Time Sampled:	5/4/26 8:00							
Date/Time Analyzed:	5/4/26 16:56							
QC Batch No.:	260504GC8A1							
Analyst Initials:	KD							
Dilution Factor:	1.0							
ANALYTE	**Result ppmv**	**RL ppmv**						
Carbon Monoxide	1,400	10						

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-12-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com
Member of the SGS Group (SGS SA)

QC Batch No: 260504GC8A1
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	5/4/26 11:08			5/4/26 11:23		5/4/26 11:37					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,020	101	1,010	100	0.7	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 5-12-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/04/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T050401-05			T050401-06			T050401-08			T050401-09		
Client Sample I.D.:	H-1770N			CV-24121			CV-99			CV-114		
Date/Time Sampled:	5/4/26 8:50			5/4/26 7:55			5/4/26 7:45			5/4/26 8:05		
Date/Time Analyzed:	5/4/26 15:44			5/4/26 15:58			5/4/26 16:27			5/4/26 16:42		
QC Batch No.:	260504GC8A1			260504GC8A1			260504GC8A1			260504GC8A1		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	1.2	1.0	0.059	0.27 J	1.0	0.059	0.26 J	1.0	0.059	0.28 J	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-12-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/04/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	**T050401-10**											
Client Sample I.D.:	**CV-24120**											
Date/Time Sampled:	**5/4/26 8:00**											
Date/Time Analyzed:	**5/4/26 16:56**											
QC Batch No.:	**260504GC8A1**											
Analyst Initials:	**KD**											
Dilution Factor:	**1.0**											
ANALYTE	**Result % v/v**	**RL % v/v**	**MDL % v/v**									
Hydrogen	11	1.0	0.059									

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 5-12-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com
Member of the SGS Group (SGS SA)

QC Batch No: 260504GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	5/4/26 11:08				5/4/26 11:23		5/4/26 11:37					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	3.73	75	3.69	74	1.2	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 5-12-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/04/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T050401-01			T050401-02			T050401-03			T050401-04		
Client Sample I.D.:	CV-113			CV-2007			CV-24122			CV-24127		
Date/Time Sampled:	5/4/26 7:50			5/4/26 8:10			5/4/26 8:20			5/4/26 8:15		
Date/Time Analyzed:	5/4/26 14:46			5/4/26 15:01			5/4/26 15:15			5/4/26 15:30		
QC Batch No.:	260504GC8A1			260504GC8A1			260504GC8A1			260504GC8A1		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	2.4	1.0	0.059	5.9	1.0	0.059	0.91 J	1.0	0.059	16	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-12-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/04/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T050401-01		T050401-02		T050401-03		T050401-04	
Client Sample I.D.:	CV-113		CV-2007		CV-24122		CV-24127	
Date/Time Sampled:	5/4/26 7:50		5/4/26 8:10		5/4/26 8:20		5/4/26 8:15	
Date/Time Analyzed:	5/4/26 14:46		5/4/26 15:01		5/4/26 15:15		5/4/26 15:30	
QC Batch No.:	260504GC8A1		260504GC8A1		260504GC8A1		260504GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**
Carbon Dioxide	**83**	0.010	**73**	0.010	**38**	0.010	**67**	0.010
Oxygen/Argon	**0.61**	0.50	**0.72**	0.50	**5.0**	0.50	**3.0**	0.50
Nitrogen	**2.3**	1.0	**2.7**	1.0	**19**	1.0	**11**	1.0
Methane	**11**	0.0010	**17**	0.0010	37	0.0010	**1.7**	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-12-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com

Member of the SGS Group (SGS SA)

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/04/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T050401-05		T050401-06		T050401-07		T050401-08	
Client Sample I.D.:	H-1770N		CV-24121		CV-24123		CV-99	
Date/Time Sampled:	5/4/26 8:50		5/4/26 7:55		5/4/26 7:40		5/4/26 7:45	
Date/Time Analyzed:	5/4/26 15:44		5/4/26 15:58		5/4/26 16:13		5/4/26 16:27	
QC Batch No.:	260504GC8A1		260504GC8A1		260504GC8A1		260504GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	59	0.010	6.9	0.010	58	0.010	53	0.010
Oxygen/Argon	0.62	0.50	19	0.50	1.9	0.50	4.7	0.50
Nitrogen	2.8	1.0	72	1.0	7.1	1.0	18	1.0
Methane	36	0.0010	0.99	0.0010	32	0.0010	24	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-12-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com

Member of the SGS Group (SGS SA)

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/04/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T050401-09		T050401-10					
Client Sample I.D.:	CV-114		CV-24120					
Date/Time Sampled:	5/4/26 8:05		5/4/26 8:00					
Date/Time Analyzed:	5/4/26 16:42		5/4/26 16:56					
QC Batch No.:	260504GC8A1		260504GC8A1					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**				
Carbon Dioxide	0.55	0.010	55	0.010				
Oxygen/Argon	21	0.50	6.4	0.50				
Nitrogen	78	1.0	24	1.0				
Methane	0.034	0.0010	3.1	0.0010				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-12-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260504GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	5/4/26 11:08			5/4/26 11:23		5/4/26 11:37					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	8.82	88	8.80	88	0.2	70	130	30
Oxygen/Argon	ND	0.50	15	15.3	102	15.2	101	0.5	70	130	30
Nitrogen	ND	1.0	70	72.2	104	71.9	103	0.4	70	130	30
Methane	ND	0.0010	0.10	0.0996	99	0.0989	98	0.7	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-12-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175
TX Cert T104704450-14-6
EPA Methods TO14A, TO15
ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

May 29, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T050503-01/10

Enclosed are the results for sample(s) received 5/5/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐ No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐ No ☐
Other:				Level 4	☐	Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:

Bill to: 07FSAccountspayable@scsengineers.com
3900 Kilroy Airport Way, Suite 300
Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T050503-01	CV-24141	05/05/26	7:45AM	1L	Gas	N	X	X	X			
-02	CV-2351	05/05/26	7:50AM	2-1L	Gas	N	X	X	X	X		
-03	CV-24143	05/05/26	7:55AM	2-1L	Gas	N	X	X	X	X		
-04	CV-2352	05/05/26	8:00AM	1L	Gas	N	X	X	X			
-05	CV-24140	05/05/26	8:05AM	2-1L	Gas	N	X	X	X	X		
-06	CV-24139	05/05/26	8:10AM	2-1L	Gas	N	X	X	X	X		
-07	CV-24138	05/05/26	8:15AM	2-1L	Gas	N	X	X	X	X		
-08	CV-2354	05/05/26	8:20AM	1L	Gas	N	X	X	X			
-09	CV-2349	05/05/26	8:25AM	1L	Gas	N	X	X	X			
-10	CV-24144	05/05/26	8:30AM	1L	Gas	N	X					

AUTHORIZATION TO PERFORM WORK	COMPANY		DATE/TIME
SAMPLED BY Fabian Chavez	COMPANY scs		DATE/TIME
RELINQUISHED BY Fabian chavez	DATE/TIME 5-5-26 8:55 am	RECEIVED BY AMEC Highway	DATE/TIME 5-5-26 8:55AM
RELINQUISHED BY AMEC Highway	DATE/TIME 5-5-26 9:10	RECEIVED BY Fabian Chavez	DATE/TIME 5/5/26 9:10
RELINQUISHED BY Fabian Chavez	DATE/TIME 5/5/26 11:28	RECEIVED BY [signature]	DATE/TIME 5/5/26 11:28

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/05/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T050503-02		T050503-03		T050503-05		T050503-06	
Client Sample I.D.:	CV-2351		CV-24143		CV-24140		CV-24139	
Date/Time Sampled:	5/5/26 7:50		5/5/26 7:55		5/5/26 8:05		5/5/26 8:10	
Date/Time Analyzed:	5/5/26 18:35		5/5/26 19:14		5/5/26 19:53		5/6/26 6:47	
QC Batch No.:	260505MS2A1		260505MS2A1		260505MS2A1		260505MS2A1	
Analyst Initials:	AS/GD		AS/GD		AS/GD		AS/GD	
Dilution Factor:	800		6,000		8,000		7,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	800	ND	6,000	ND	8,000	ND	7,000
Chloromethane	ND	800	ND	6,000	ND	8,000	ND	7,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	800	ND	6,000	ND	8,000	ND	7,000
Vinyl Chloride	ND	800	ND	6,000	ND	8,000	ND	7,000
Bromomethane	ND	800	ND	6,000	ND	8,000	ND	7,000
Chloroethane	ND	800	ND	6,000	ND	8,000	ND	7,000
Trichlorofluoromethane (11)	ND	800	ND	6,000	ND	8,000	ND	7,000
1,1-Dichloroethene	ND	800	ND	6,000	ND	8,000	ND	7,000
Carbon Disulfide	ND	800	ND	6,000	ND	8,000	ND	7,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	800	ND	6,000	ND	8,000	ND	7,000
Acetone	53,000	800	480,000	6,000	650,000	8,000	490,000	7,000
Methylene Chloride	ND	800	ND	6,000	ND	8,000	ND	7,000
t-1,2-Dichloroethene	ND	800	ND	6,000	ND	8,000	ND	7,000
1,1-Dichloroethane	ND	800	ND	6,000	ND	8,000	ND	7,000
Vinyl Acetate	ND	800	ND	6,000	ND	8,000	ND	7,000
c-1,2-Dichloroethene	ND	800	ND	6,000	ND	8,000	ND	7,000
2-Butanone	44,000	1,600	400,000	12,000	640,000	16,000	450,000	14,000
t-Butyl Methyl Ether (MTBE)	ND	800	ND	6,000	ND	8,000	ND	7,000
Chloroform	ND	800	ND	6,000	ND	8,000	ND	7,000
1,1,1-Trichloroethane	ND	800	ND	6,000	ND	8,000	ND	7,000
Carbon Tetrachloride	ND	800	ND	6,000	ND	8,000	ND	7,000
Benzene	5,700	800	66,000	6,000	190,000	8,000	110,000	7,000
1,2-Dichloroethane	ND	800	ND	6,000	ND	8,000	ND	7,000
Trichloroethene	ND	800	ND	6,000	ND	8,000	ND	7,000
1,2-Dichloropropane	ND	800	ND	6,000	ND	8,000	ND	7,000
Bromodichloromethane	ND	800	ND	6,000	ND	8,000	ND	7,000
c-1,3-Dichloropropene	ND	800	ND	6,000	ND	8,000	ND	7,000
4-Methyl-2-Pentanone	830	800	ND	6,000	8,800	8,000	ND	7,000
Toluene	ND	800	ND	6,000	11,000	8,000	7,200	7,000
t-1,3-Dichloropropene	ND	800	ND	6,000	ND	8,000	ND	7,000
1,1,2-Trichloroethane	ND	800	ND	6,000	ND	8,000	ND	7,000
Tetrachloroethene	ND	800	ND	6,000	ND	8,000	ND	7,000
2-Hexanone	2,100	800	ND	6,000	ND	8,000	ND	7,000
Dibromochloromethane	ND	800	ND	6,000	ND	8,000	ND	7,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/05/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T050503-02		T050503-03		T050503-05		T050503-06	
Client Sample I.D.:	CV-2351		CV-24143		CV-24140		CV-24139	
Date/Time Sampled:	5/5/26 7:50		5/5/26 7:55		5/5/26 8:05		5/5/26 8:10	
Date/Time Analyzed:	5/5/26 18:35		5/5/26 19:14		5/5/26 19:53		5/6/26 6:47	
QC Batch No.:	260505MS2A1		260505MS2A1		260505MS2A1		260505MS2A1	
Analyst Initials:	AS/GD		AS/GD		AS/GD		AS/GD	
Dilution Factor:	800		6,000		8,000		7,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	800	ND	6,000	ND	8,000	ND	7,000
Chlorobenzene	ND	800	ND	6,000	ND	8,000	ND	7,000
Ethylbenzene	ND	800	ND	6,000	ND	8,000	ND	7,000
p,&m-Xylene	ND	800	ND	6,000	ND	8,000	ND	7,000
o-Xylene	ND	800	ND	6,000	ND	8,000	ND	7,000
Styrene	ND	800	ND	6,000	ND	8,000	ND	7,000
Bromoform	ND	800	ND	6,000	ND	8,000	ND	7,000
1,1,2,2-Tetrachloroethane	ND	800	ND	6,000	ND	8,000	ND	7,000
Benzyl Chloride	ND	800	ND	6,000	ND	8,000	ND	7,000
4-Ethyl Toluene	ND	800	ND	6,000	ND	8,000	ND	7,000
1,3,5-Trimethylbenzene	ND	800	ND	6,000	ND	8,000	ND	7,000
1,2,4-Trimethylbenzene	ND	800	ND	6,000	ND	8,000	ND	7,000
1,3-Dichlorobenzene	ND	800	ND	6,000	ND	8,000	ND	7,000
1,4-Dichlorobenzene	ND	800	ND	6,000	ND	8,000	ND	7,000
1,2-Dichlorobenzene	ND	800	ND	6,000	ND	8,000	ND	7,000
1,2,4-Trichlorobenzene	ND	5,600	ND	42,000	ND	56,000	ND	49,000
Hexachlorobutadiene	ND	800	ND	6,000	ND	8,000	ND	7,000
1,3-Butadiene	ND	4,000	ND	30,000	ND	40,000	ND	35,000
Isopropanol	37,000	4,000	61,000	30,000	110,000	40,000	100,000	35,000
n-Hexane	ND	4,000	ND	30,000	ND	40,000	ND	35,000
Ethyl Acetate	ND	4,000	ND	30,000	ND	40,000	ND	35,000
Tetrahydrofuran	32,000	4,000	350,000	30,000	590,000	40,000	320,000	35,000
Cyclohexane	ND	4,000	ND	30,000	ND	40,000	ND	35,000
Heptane	ND	4,000	ND	30,000	ND	40,000	ND	35,000
1,4-Dioxane	ND	4,000	ND	30,000	ND	40,000	ND	35,000

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 5/29/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/05/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T050503-02		T050503-03		T050503-05		T050503-06	
Client Sample I.D.:	CV-2351		CV-24143		CV-24140		CV-24139	
Date/Time Sampled:	5/5/26 7:50		5/5/26 7:55		5/5/26 8:05		5/5/26 8:10	
Date/Time Analyzed:	5/5/26 18:35		5/5/26 19:14		5/5/26 19:53		5/6/26 6:47	
QC Batch No.:	260505MS2A1		260505MS2A1		260505MS2A1		260505MS2A1	
Analyst Initials:	AS/GD		AS/GD		AS/GD		AS/GD	
Dilution Factor:	800		6,000		8,000		7,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	800	ND	6,000	ND	8,000	ND	7,000
Chloromethane	ND Q	800	ND Q	6,000	ND Q	8,000	ND Q	7,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	800	ND	6,000	ND	8,000	ND	7,000
Vinyl Chloride	ND Q	800	ND Q	6,000	ND Q	8,000	ND Q	7,000
Bromomethane	ND	800	ND	6,000	ND	8,000	ND	7,000
Chloroethane	ND	800	ND	6,000	ND	8,000	ND	7,000
Trichlorofluoromethane (11)	ND	800	ND	6,000	ND	8,000	ND	7,000
1,1-Dichloroethene	ND	800	ND	6,000	ND	8,000	ND	7,000
Carbon Disulfide	ND	800	ND	6,000	ND	8,000	ND	7,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	800	ND	6,000	ND	8,000	ND	7,000
Acetone	53,000 Q	800	480,000 Q	6,000	650,000 Q	8,000	490,000 Q	7,000
Methylene Chloride	ND	800	ND	6,000	ND	8,000	ND	7,000
t-1,2-Dichloroethene	ND	800	ND	6,000	ND	8,000	ND	7,000
1,1-Dichloroethane	ND	800	ND	6,000	ND	8,000	ND	7,000
Vinyl Acetate	ND	800	ND	6,000	ND	8,000	ND	7,000
c-1,2-Dichloroethene	ND	800	ND	6,000	ND	8,000	ND	7,000
2-Butanone	44,000	1,600	400,000	12,000	640,000	16,000	450,000	14,000
t-Butyl Methyl Ether (MTBE)	ND	800	ND	6,000	ND	8,000	ND	7,000
Chloroform	ND	800	ND	6,000	ND	8,000	ND	7,000
1,1,1-Trichloroethane	ND	800	ND	6,000	ND	8,000	ND	7,000
Carbon Tetrachloride	ND	800	ND	6,000	ND	8,000	ND	7,000
Benzene	5,700	800	66,000	6,000	190,000	8,000	110,000	7,000
1,2-Dichloroethane	ND	800	ND	6,000	ND	8,000	ND	7,000
Trichloroethene	ND	800	ND	6,000	ND	8,000	ND	7,000
1,2-Dichloropropane	ND	800	ND	6,000	ND	8,000	ND	7,000
Bromodichloromethane	ND	800	ND	6,000	ND	8,000	ND	7,000
c-1,3-Dichloropropene	ND	800	ND	6,000	ND	8,000	ND	7,000
4-Methyl-2-Pentanone	830	800	ND	6,000	8,800	8,000	ND	7,000
Toluene	ND	800	ND	6,000	11,000	8,000	7,200	7,000
t-1,3-Dichloropropene	ND	800	ND	6,000	ND	8,000	ND	7,000
1,1,2-Trichloroethane	ND	800	ND	6,000	ND	8,000	ND	7,000
Tetrachloroethene	ND	800	ND	6,000	ND	8,000	ND	7,000
2-Hexanone	2,100	800	ND	6,000	ND	8,000	ND	7,000
Dibromochloromethane	ND	800	ND	6,000	ND	8,000	ND	7,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/05/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T050503-02		T050503-03		T050503-05		T050503-06	
Client Sample I.D.:	CV-2351		CV-24143		CV-24140		CV-24139	
Date/Time Sampled:	5/5/26 7:50		5/5/26 7:55		5/5/26 8:05		5/5/26 8:10	
Date/Time Analyzed:	5/5/26 18:35		5/5/26 19:14		5/5/26 19:53		5/6/26 6:47	
QC Batch No.:	260505MS2A1		260505MS2A1		260505MS2A1		260505MS2A1	
Analyst Initials:	AS/GD		AS/GD		AS/GD		AS/GD	
Dilution Factor:	800		6,000		8,000		7,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	800	ND	6,000	ND	8,000	ND	7,000
Chlorobenzene	ND	800	ND	6,000	ND	8,000	ND	7,000
Ethylbenzene	ND	800	ND	6,000	ND	8,000	ND	7,000
p,&m-Xylene	ND	800	ND	6,000	ND	8,000	ND	7,000
o-Xylene	ND	800	ND	6,000	ND	8,000	ND	7,000
Styrene	ND	800	ND	6,000	ND	8,000	ND	7,000
Bromoform	ND	800	ND	6,000	ND	8,000	ND	7,000
1,1,2,2-Tetrachloroethane	ND	800	ND	6,000	ND	8,000	ND	7,000
Benzyl Chloride	ND	800	ND	6,000	ND	8,000	ND	7,000
4-Ethyl Toluene	ND	800	ND	6,000	ND	8,000	ND	7,000
1,3,5-Trimethylbenzene	ND	800	ND	6,000	ND	8,000	ND	7,000
1,2,4-Trimethylbenzene	ND	800	ND	6,000	ND	8,000	ND	7,000
1,3-Dichlorobenzene	ND	800	ND	6,000	ND	8,000	ND	7,000
1,4-Dichlorobenzene	ND	800	ND	6,000	ND	8,000	ND	7,000
1,2-Dichlorobenzene	ND	800	ND	6,000	ND	8,000	ND	7,000
1,2,4-Trichlorobenzene	ND	5,600	ND	42,000	ND	56,000	ND	49,000
Hexachlorobutadiene	ND	800	ND	6,000	ND	8,000	ND	7,000
1,3-Butadiene	ND Q	4,000	ND Q	30,000	ND Q	40,000	ND Q	35,000
Isopropanol	37,000	4,000	61,000	30,000	110,000	40,000	100,000	35,000
n-Hexane	ND	4,000	ND	30,000	ND	40,000	ND	35,000
Ethyl Acetate	ND	4,000	ND	30,000	ND	40,000	ND	35,000
Tetrahydrofuran	32,000	4,000	350,000	30,000	590,000	40,000	320,000	35,000
Cyclohexane	ND	4,000	ND	30,000	ND	40,000	ND	35,000
Heptane	ND	4,000	ND	30,000	ND	40,000	ND	35,000
1,4-Dioxane	ND	4,000	ND	30,000	ND	40,000	ND	35,000

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited low recovery in the continuing calibration verification indicating possible low bias

Reviewed/Approved By: _____ Date 5/29/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/05/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T050503-07
Client Sample I.D.:	CV-24138
Date/Time Sampled:	5/5/26 8:15
Date/Time Analyzed:	5/6/26 7:25
QC Batch No.:	260505MS2A1
Analyst Initials:	AS/GD
Dilution Factor:	6,000

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	6,000
Chloromethane	ND Q	6,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	6,000
Vinyl Chloride	ND Q	6,000
Bromomethane	ND	6,000
Chloroethane	ND	6,000
Trichlorofluoromethane (11)	ND	6,000
1,1-Dichloroethene	ND	6,000
Carbon Disulfide	ND	6,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	6,000
Acetone	430,000 Q	6,000
Methylene Chloride	ND	6,000
t-1,2-Dichloroethene	ND	6,000
1,1-Dichloroethane	ND	6,000
Vinyl Acetate	ND	6,000
c-1,2-Dichloroethene	ND	6,000
2-Butanone	480,000	12,000
t-Butyl Methyl Ether (MTBE)	ND	6,000
Chloroform	ND	6,000
1,1,1-Trichloroethane	ND	6,000
Carbon Tetrachloride	ND	6,000
Benzene	150,000	6,000
1,2-Dichloroethane	ND	6,000
Trichloroethene	ND	6,000
1,2-Dichloropropane	ND	6,000
Bromodichloromethane	ND	6,000
c-1,3-Dichloropropene	ND	6,000
4-Methyl-2-Pentanone	6,600	6,000
Toluene	11,000	6,000
t-1,3-Dichloropropene	ND	6,000
1,1,2-Trichloroethane	ND	6,000
Tetrachloroethene	ND	6,000
2-Hexanone	ND	6,000
Dibromochloromethane	ND	6,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/05/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T050503-07
Client Sample I.D.:	CV-24138
Date/Time Sampled:	5/5/26 8:15
Date/Time Analyzed:	5/6/26 7:25
QC Batch No.:	260505MS2A1
Analyst Initials:	AS/GD
Dilution Factor:	6,000

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	6,000
Chlorobenzene	ND	6,000
Ethylbenzene	ND	6,000
p,&m-Xylene	ND	6,000
o-Xylene	ND	6,000
Styrene	ND	6,000
Bromoform	ND	6,000
1,1,2,2-Tetrachloroethane	ND	6,000
Benzyl Chloride	ND	6,000
4-Ethyl Toluene	ND	6,000
1,3,5-Trimethylbenzene	ND	6,000
1,2,4-Trimethylbenzene	ND	6,000
1,3-Dichlorobenzene	ND	6,000
1,4-Dichlorobenzene	ND	6,000
1,2-Dichlorobenzene	ND	6,000
1,2,4-Trichlorobenzene	ND	42,000
Hexachlorobutadiene	ND	6,000
1,3-Butadiene	ND Q	30,000
Isopropanol	86,000	30,000
n-Hexane	ND	30,000
Ethyl Acetate	40,000	30,000
Tetrahydrofuran	420,000	30,000
Cyclohexane	ND	30,000
Heptane	ND	30,000
1,4-Dioxane	ND	30,000

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited low recovery in the continuing calibration verification indicating possible low bias

Reviewed/Approved By: Mark Johnson
Operations Manager

Date 5/9/26

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/05/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK
Client Sample I.D.:	--
Date/Time Sampled:	--
Date/Time Analyzed:	5/5/26 17:17
QC Batch No.:	260505MS2A1
Analyst Initials:	AS/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv		RL ppbv
Dichlorodifluoromethane (12)	ND		0.20
Chloromethane	ND	Q	0.20
1,2-Cl-1,1,2,2-F ethane (114)	ND		0.20
Vinyl Chloride	ND	Q	0.20
Bromomethane	ND		0.20
Chloroethane	ND		0.20
Trichlorofluoromethane (11)	ND		0.20
1,1-Dichloroethene	ND		0.20
Carbon Disulfide	ND		0.20
1,1,2-Cl 1,2,2-F ethane (113)	ND		0.20
Acetone	ND	Q	0.20
Methylene Chloride	ND		0.20
t-1,2-Dichloroethene	ND		0.20
1,1-Dichloroethane	ND		0.20
Vinyl Acetate	ND		0.20
c-1,2-Dichloroethene	ND		0.20
2-Butanone	ND		0.40
t-Butyl Methyl Ether (MTBE)	ND		0.20
Chloroform	ND		0.20
1,1,1-Trichloroethane	ND		0.20
Carbon Tetrachloride	ND		0.20
Benzene	ND		0.20
1,2-Dichloroethane	ND		0.20
Trichloroethene	ND		0.20
1,2-Dichloropropane	ND		0.20
Bromodichloromethane	ND		0.20
c-1,3-Dichloropropene	ND		0.20
4-Methyl-2-Pentanone	ND		0.20
Toluene	ND		0.20
t-1,3-Dichloropropene	ND		0.20
1,1,2-Trichloroethane	ND		0.20
Tetrachloroethene	ND		0.20
2-Hexanone	ND		0.20
Dibromochloromethane	ND		0.20

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/05/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK
Client Sample I.D.:	--
Date/Time Sampled:	--
Date/Time Analyzed:	5/5/26 17:17
QC Batch No.:	260505MS2A1
Analyst Initials:	AS/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	0.20
Chlorobenzene	ND	0.20
Ethylbenzene	ND	0.20
p,&m-Xylene	ND	0.20
o-Xylene	ND	0.20
Styrene	ND	0.20
Bromoform	ND	0.20
1,1,2,2-Tetrachloroethane	ND	0.20
Benzyl Chloride	ND	0.20
4-Ethyl Toluene	ND	0.20
1,3,5-Trimethylbenzene	ND	0.20
1,2,4-Trimethylbenzene	ND	0.20
1,3-Dichlorobenzene	ND	0.20
1,4-Dichlorobenzene	ND	0.20
1,2-Dichlorobenzene	ND	0.20
1,2,4-Trichlorobenzene	ND	1.4
Hexachlorobutadiene	ND	0.20
1,3-Butadiene	ND Q	1.0
Isopropanol	ND	1.0
n-Hexane	ND	1.0
Ethyl Acetate	ND	1.0
Tetrahydrofuran	ND	1.0
Cyclohexane	ND	1.0
Heptane	ND	1.0
1,4-Dioxane	ND	1.0

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited low recovery in the continuing calibration verification indicating possible low bias

Reviewed/Approved By: _____ Date 5/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 260505MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	5/5/26 17:17			5/5/26 15:59		5/5/26 16:38					
Analyst Initials:	AS/GD			AS/GD		AS/GD					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	**Result ppbv**	**RL ppbv**	**AMT. ppbv**	**Result ppbv**	**% Rec.**	**Result ppbv**	**% Rec.**	**RPD**	**Low %Rec**	**High %Rec**	**Max. RPD**
1,1-Dichloroethene	ND	0.20	10	9.98	100	9.38	94	6.2	70	130	30
Methylene Chloride	ND	0.20	10	9.53	95	9.00	90	5.6	70	130	30
Trichloroethene	ND	0.20	10	10.1	101	10.3	103	1.7	70	130	30
Toluene	ND	0.20	10	9.83	98	10.2	102	3.8	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	8.92	89	9.37	94	4.9	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date: 5/29/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/05/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T050503-01		T050503-02		T050503-03		T050503-04	
Client Sample I.D.:	CV-24141		CV-2351		CV-24143		CV-2352	
Date/Time Sampled:	5/5/26 7:45		5/5/26 7:50		5/5/26 7:55		5/5/26 8:00	
Date/Time Analyzed:	5/5/26 16:56		5/5/26 17:10		5/5/26 17:25		5/5/26 17:39	
QC Batch No.:	260505GC8A1		260505GC8A1		260505GC8A1		260505GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	94	10	ND	10	460	10	1,100	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-14-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com
Member of the SGS Group (SGS SA)

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/05/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T050503-05		T050503-06		T050503-07		T050503-08	
Client Sample I.D.:	CV-24140		CV-24139		CV-24138		CV-2354	
Date/Time Sampled:	5/5/26 8:05		5/5/26 8:10		5/5/26 8:15		5/5/26 8:20	
Date/Time Analyzed:	5/5/26 17:54		5/5/26 18:08		5/5/26 18:23		5/5/26 18:37	
QC Batch No.:	260505GC8A1		260505GC8A1		260505GC8A1		260505GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	1,000	10	630	10	820	10	2,500	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-14-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/05/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	**T050503-09**							
Client Sample I.D.:	**CV-2349**							
Date/Time Sampled:	**5/5/26 8:25**							
Date/Time Analyzed:	**5/5/26 18:52**							
QC Batch No.:	**260505GC8A1**							
Analyst Initials:	**KD**							
Dilution Factor:	**1.0**							
ANALYTE	**Result ppmv**	**RL ppmv**						
Carbon Monoxide	2,600	10						

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-14-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260505GC8A1
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	5/5/26 9:55			5/5/26 11:22		5/5/26 11:36					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,100	108	1,090	108	0.3	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-14-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/05/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T050503-01			T050503-02			T050503-03			T050503-04		
Client Sample I.D.:	CV-24141			CV-2351			CV-24143			CV-2352		
Date/Time Sampled:	5/5/26 7:45			5/5/26 7:50			5/5/26 7:55			5/5/26 8:00		
Date/Time Analyzed:	5/5/26 16:56			5/5/26 17:10			5/5/26 17:25			5/5/26 17:39		
QC Batch No.:	260505GC8A1			260505GC8A1			260505GC8A1			260505GC8A1		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	0.12 J	1.0	0.059	0.16 J	1.0	0.059	6.1	1.0	0.059	19	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-14-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/05/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T050503-05			T050503-06			T050503-07			T050503-08		
Client Sample I.D.:	CV-24140			CV-24139			CV-24138			CV-2354		
Date/Time Sampled:	5/5/26 8:05			5/5/26 8:10			5/5/26 8:15			5/5/26 8:20		
Date/Time Analyzed:	5/5/26 17:54			5/5/26 18:08			5/5/26 18:23			5/5/26 18:37		
QC Batch No.:	260505GC8A1			260505GC8A1			260505GC8A1			260505GC8A1		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	21	1.0	0.059	18	1.0	0.059	21	1.0	0.059	17	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-14-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/05/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T050503-09		
Client Sample I.D.:	CV-2349		
Date/Time Sampled:	5/5/26 8:25		
Date/Time Analyzed:	5/5/26 18:52		
QC Batch No.:	260505GC8A1		
Analyst Initials:	KD		
Dilution Factor:	1.0		

ANALYTE	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	15	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-14-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260505GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	5/5/26 9:55				5/5/26 11:22		5/5/26 11:36					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	5.59	112	5.59	112	0.1	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 5-14-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/05/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T050503-01		T050503-02		T050503-03		T050503-04	
Client Sample I.D.:	CV-24141		CV-2351		CV-24143		CV-2352	
Date/Time Sampled:	5/5/26 7:45		5/5/26 7:50		5/5/26 7:55		5/5/26 8:00	
Date/Time Analyzed:	5/5/26 16:56		5/5/26 17:10		5/5/26 17:25		5/5/26 17:39	
QC Batch No.:	260505GC8A1		260505GC8A1		260505GC8A1		260505GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	34	0.010	1.7	0.010	24	0.010	66	0.010
Oxygen/Argon	5.0	0.50	20	0.50	15	0.50	2.5	0.50
Nitrogen	39	1.0	77	1.0	55	1.0	9.3	1.0
Methane	22	0.0010	0.87	0.0010	0.58	0.0010	1.8	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 5-14-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/05/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T050503-05		T050503-06		T050503-07		T050503-08	
Client Sample I.D.:	CV-24140		CV-24139		CV-24138		CV-2354	
Date/Time Sampled:	5/5/26 8:05		5/5/26 8:10		5/5/26 8:15		5/5/26 8:20	
Date/Time Analyzed:	5/5/26 17:54		5/5/26 18:08		5/5/26 18:23		5/5/26 18:37	
QC Batch No.:	260505GC8A1		260505GC8A1		260505GC8A1		260505GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	65	0.010	53	0.010	57	0.010	72	0.010
Oxygen/Argon	2.4	0.50	4.4	0.50	3.9	0.50	0.95	0.50
Nitrogen	8.6	1.0	18	1.0	14	1.0	3.3	1.0
Methane	1.8	0.0010	4.7	0.0010	2.0	0.0010	4.7	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-14-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com
Member of the SGS Group (SGS SA)

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/05/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T050503-09		T050503-10					
Client Sample I.D.:	CV-2349		CV-24144					
Date/Time Sampled:	5/5/26 8:25		5/5/26 8:30					
Date/Time Analyzed:	5/5/26 18:52		5/5/26 19:06					
QC Batch No.:	260505GC8A1		260505GC8A1					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**				
Carbon Dioxide	78	0.010	34	0.010				
Oxygen/Argon	0.74	0.50	2.6	0.50				
Nitrogen	2.6	1.0	9.6	1.0				
Methane	2.6	0.0010	53	0.0010				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-14-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com
Member of the SGS Group (SGS SA)

QC Batch No: 260505GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	5/5/26 9:55			5/5/26 11:22		5/5/26 11:36					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	9.86	98	9.87	98	0.1	70	130	30
Oxygen/Argon	ND	0.50	15	14.6	97	14.6	97	0.0	70	130	30
Nitrogen	ND	1.0	70	70.5	101	70.6	101	0.1	70	130	30
Methane	ND	0.0010	0.10	0.104	103	0.104	103	0.3	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-14-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175

TX Cert T104704450-14-6
EPA Methods TO14A, TO15

ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

May 29, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T050603-01/10

Enclosed are the results for sample(s) received 5/6/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME: Standard ■ 48 hours ☐ | Same Day ☐ 72 hours ☐ | 24 hours ☐ 96 hours ☐ | Other:

DELIVERABLES: EDD ■ | EDF ☐ | Level 3 ☐ | Level 4 ☐

PAGE: 1 OF

Condition upon receipt: Sealed Yes ☐ No ☐ | Intact Yes ☐ No ☐ | Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:	
Bill to:	07FSAccountspayable@scsengineers.com
	3900 Kilroy Airport Way, Suite 300
	Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T050603-01	CV-24102	05/06/26	7:30AM	1L	Gas	N	X					
-02	CV-24101	05/06/26	7:40M	2-1L	Gas	N	X	X	X	X		
-03	CV-2001	05/06/26	7:50AM	2-1L	Gas	N	X	X	X	X		
-04	CV-24099	05/06/26	7:55AM	1L	Gas	N	X					
-05	CV-24095	05/06/26	8:05AM	2-1L	Gas	N	X	X	X	X		
-06	CV-24142	05/06/26	8:10AM	2-1L	Gas	N	X	X	X	X		
-07	CV-2348	05/06/26	8:15AM	1L	Gas	N	X	X	X			
-08	CV-2347	05/06/26	8:20M	1L	Gas	N	X	X	X			
-09	CV-2346	05/06/26	8:25AM	1L	Gas	N	X	X	X			
-10	CV-108-52	05/06/26	8:30AM	2-1L	Gas	N	X	X	X	X		

AUTHORIZATION TO PERFORM WORK	COMPANY: Eric Navarro SCS	DATE/TIME: 5-6-26 9:10	
SAMPLED BY	COMPANY: SCS	DATE/TIME: 5-6-26 9:10	
RELINQUISHED BY	DATE/TIME: 5-6-26 9:10	RECEIVED BY	DATE/TIME: 5/6/26 11:34
RELINQUISHED BY	DATE/TIME: 5/6/26 12:52	RECEIVED BY	DATE/TIME: 5/6/26 1252
RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: H=HCl N=None / Container: B=Bag C=Can V=VOA O=Other

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/06/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T050603-02		T050603-03		T050603-05		T050603-06	
Client Sample I.D.:	CV-24101		CV-2001		CV-24095		CV-24142	
Date/Time Sampled:	5/6/26 7:40		5/6/26 7:50		5/6/26 8:05		5/6/26 8:10	
Date/Time Analyzed:	5/6/26 17:32		5/6/26 18:10		5/6/26 18:48		5/6/26 19:27	
QC Batch No.:	260506MS2A1		260506MS2A1		260506MS2A1		260506MS2A1	
Analyst Initials:	AS/GD		AS/GD		AS/GD		AS/GD	
Dilution Factor:	5,000		600		10,000		5,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	5,000	ND	600	ND	10,000	ND	5,000
Chloromethane	ND	5,000	ND	600	ND	10,000	ND	5,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	5,000	ND	600	ND	10,000	ND	5,000
Vinyl Chloride	ND	5,000	ND	600	ND	10,000	ND	5,000
Bromomethane	ND	5,000	ND	600	ND	10,000	ND	5,000
Chloroethane	ND	5,000	ND	600	ND	10,000	ND	5,000
Trichlorofluoromethane (11)	ND	5,000	ND	600	ND	10,000	ND	5,000
1,1-Dichloroethene	ND	5,000	ND	600	ND	10,000	ND	5,000
Carbon Disulfide	ND	5,000	ND	600	ND	10,000	ND	5,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	5,000	ND	600	ND	10,000	ND	5,000
Acetone	46,000	5,000	41,000	600	860,000	10,000	320,000	5,000
Methylene Chloride	ND	5,000	ND	600	ND	10,000	ND	5,000
t-1,2-Dichloroethene	ND	5,000	ND	600	ND	10,000	ND	5,000
1,1-Dichloroethane	ND	5,000	ND	600	ND	10,000	ND	5,000
Vinyl Acetate	ND	5,000	ND	600	ND	10,000	ND	5,000
c-1,2-Dichloroethene	ND	5,000	ND	600	ND	10,000	ND	5,000
2-Butanone	37,000	10,000	57,000	1,200	670,000	20,000	290,000	10,000
t-Butyl Methyl Ether (MTBE)	ND	5,000	1,200	600	ND	10,000	ND	5,000
Chloroform	ND	5,000	ND	600	ND	10,000	ND	5,000
1,1,1-Trichloroethane	ND	5,000	ND	600	ND	10,000	ND	5,000
Carbon Tetrachloride	ND	5,000	ND	600	ND	10,000	ND	5,000
Benzene	8,000	5,000	67,000	600	280,000	10,000	100,000	5,000
1,2-Dichloroethane	ND	5,000	ND	600	ND	10,000	ND	5,000
Trichloroethene	ND	5,000	ND	600	ND	10,000	ND	5,000
1,2-Dichloropropane	ND	5,000	ND	600	ND	10,000	ND	5,000
Bromodichloromethane	ND	5,000	ND	600	ND	10,000	ND	5,000
c-1,3-Dichloropropene	ND	5,000	ND	600	ND	10,000	ND	5,000
4-Methyl-2-Pentanone	ND	5,000	2,200	600	ND	10,000	ND	5,000
Toluene	ND	5,000	3,000	600	11,000	10,000	5,600	5,000
t-1,3-Dichloropropene	ND	5,000	ND	600	ND	10,000	ND	5,000
1,1,2-Trichloroethane	ND	5,000	ND	600	ND	10,000	ND	5,000
Tetrachloroethene	ND	5,000	ND	600	ND	10,000	ND	5,000
2-Hexanone	ND	5,000	ND	600	ND	10,000	ND	5,000
Dibromochloromethane	ND	5,000	ND	600	ND	10,000	ND	5,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/06/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T050603-02		T050603-03		T050603-05		T050603-06	
Client Sample I.D.:	CV-24101		CV-2001		CV-24095		CV-24142	
Date/Time Sampled:	5/6/26 7:40		5/6/26 7:50		5/6/26 8:05		5/6/26 8:10	
Date/Time Analyzed:	5/6/26 17:32		5/6/26 18:10		5/6/26 18:48		5/6/26 19:27	
QC Batch No.:	260506MS2A1		260506MS2A1		260506MS2A1		260506MS2A1	
Analyst Initials:	AS/GD		AS/GD		AS/GD		AS/GD	
Dilution Factor:	5,000		600		10,000		5,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	5,000	ND	600	ND	10,000	ND	5,000
Chlorobenzene	ND	5,000	ND	600	ND	10,000	ND	5,000
Ethylbenzene	ND	5,000	ND	600	ND	10,000	ND	5,000
p,&m-Xylene	ND	5,000	ND	600	ND	10,000	ND	5,000
o-Xylene	ND	5,000	ND	600	ND	10,000	ND	5,000
Styrene	ND	5,000	ND	600	ND	10,000	ND	5,000
Bromoform	ND	5,000	ND	600	ND	10,000	ND	5,000
1,1,2,2-Tetrachloroethane	ND	5,000	ND	600	ND	10,000	ND	5,000
Benzyl Chloride	ND	5,000	ND	600	ND	10,000	ND	5,000
4-Ethyl Toluene	ND	5,000	ND	600	ND	10,000	ND	5,000
1,3,5-Trimethylbenzene	ND	5,000	ND	600	ND	10,000	ND	5,000
1,2,4-Trimethylbenzene	ND	5,000	ND	600	ND	10,000	ND	5,000
1,3-Dichlorobenzene	ND	5,000	ND	600	ND	10,000	ND	5,000
1,4-Dichlorobenzene	ND	5,000	ND	600	ND	10,000	ND	5,000
1,2-Dichlorobenzene	ND	5,000	ND	600	ND	10,000	ND	5,000
1,2,4-Trichlorobenzene	ND	35,000	ND	4,200	ND	70,000	ND	35,000
Hexachlorobutadiene	ND	5,000	ND	600	ND	10,000	ND	5,000
1,3-Butadiene	ND	25,000	6,700	3,000	ND	50,000	ND	25,000
Isopropanol	47,000	25,000	30,000	3,000	160,000	50,000	130,000	25,000
n-Hexane	ND	25,000	3,400	3,000	ND	50,000	ND	25,000
Ethyl Acetate	ND	25,000	10,000	3,000	92,000	50,000	48,000	25,000
Tetrahydrofuran	ND	25,000	59,000	3,000	570,000	50,000	300,000	25,000
Cyclohexane	ND	25,000	ND	3,000	ND	50,000	ND	25,000
Heptane	ND	25,000	4,100	3,000	ND	50,000	ND	25,000
1,4-Dioxane	ND	25,000	ND	3,000	ND	50,000	ND	25,000

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 5/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/06/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T050603-10
Client Sample I.D.:	CV-108-52
Date/Time Sampled:	5/6/26 8:30
Date/Time Analyzed:	5/6/26 20:06
QC Batch No.:	260506MS2A1
Analyst Initials:	AS/GD
Dilution Factor:	3,600

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	3,600
Chloromethane	ND	3,600
1,2-Cl-1,1,2,2-F ethane (114)	ND	3,600
Vinyl Chloride	ND	3,600
Bromomethane	ND	3,600
Chloroethane	ND	3,600
Trichlorofluoromethane (11)	ND	3,600
1,1-Dichloroethene	ND	3,600
Carbon Disulfide	ND	3,600
1,1,2-Cl 1,2,2-F ethane (113)	ND	3,600
Acetone	250,000	3,600
Methylene Chloride	ND	3,600
t-1,2-Dichloroethene	ND	3,600
1,1-Dichloroethane	ND	3,600
Vinyl Acetate	ND	3,600
c-1,2-Dichloroethene	ND	3,600
2-Butanone	230,000	7,200
t-Butyl Methyl Ether (MTBE)	ND	3,600
Chloroform	ND	3,600
1,1,1-Trichloroethane	ND	3,600
Carbon Tetrachloride	ND	3,600
Benzene	41,000	3,600
1,2-Dichloroethane	ND	3,600
Trichloroethene	ND	3,600
1,2-Dichloropropane	ND	3,600
Bromodichloromethane	ND	3,600
c-1,3-Dichloropropene	ND	3,600
4-Methyl-2-Pentanone	ND	3,600
Toluene	3,800	3,600
t-1,3-Dichloropropene	ND	3,600
1,1,2-Trichloroethane	ND	3,600
Tetrachloroethene	ND	3,600
2-Hexanone	ND	3,600
Dibromochloromethane	ND	3,600

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/06/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T050603-10
Client Sample I.D.:	CV-108-52
Date/Time Sampled:	5/6/26 8:30
Date/Time Analyzed:	5/6/26 20:06
QC Batch No.:	260506MS2A1
Analyst Initials:	AS/GD
Dilution Factor:	3,600

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	3,600
Chlorobenzene	ND	3,600
Ethylbenzene	ND	3,600
p,&m-Xylene	ND	3,600
o-Xylene	ND	3,600
Styrene	ND	3,600
Bromoform	ND	3,600
1,1,2,2-Tetrachloroethane	ND	3,600
Benzyl Chloride	ND	3,600
4-Ethyl Toluene	ND	3,600
1,3,5-Trimethylbenzene	ND	3,600
1,2,4-Trimethylbenzene	ND	3,600
1,3-Dichlorobenzene	ND	3,600
1,4-Dichlorobenzene	ND	3,600
1,2-Dichlorobenzene	ND	3,600
1,2,4-Trichlorobenzene	ND	25,000
Hexachlorobutadiene	ND	3,600
1,3-Butadiene	ND	18,000
Isopropanol	200,000	18,000
n-Hexane	ND	18,000
Ethyl Acetate	ND	18,000
Tetrahydrofuran	180,000	18,000
Cyclohexane	ND	18,000
Heptane	ND	18,000
1,4-Dioxane	ND	18,000

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 5/29/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/06/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK							
Client Sample I.D.:	--							
Date/Time Sampled:	--							
Date/Time Analyzed:	5/6/26 15:34							
QC Batch No.:	260506MS2A1							
Analyst Initials:	AS/GD							
Dilution Factor:	0.20							

ANALYTE	Result ppbv	RL ppbv						
Dichlorodifluoromethane (12)	ND	0.20						
Chloromethane	ND	0.20						
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20						
Vinyl Chloride	ND	0.20						
Bromomethane	ND	0.20						
Chloroethane	ND	0.20						
Trichlorofluoromethane (11)	ND	0.20						
1,1-Dichloroethene	ND	0.20						
Carbon Disulfide	ND	0.20						
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20						
Acetone	ND	0.20						
Methylene Chloride	ND	0.20						
t-1,2-Dichloroethene	ND	0.20						
1,1-Dichloroethane	ND	0.20						
Vinyl Acetate	ND	0.20						
c-1,2-Dichloroethene	ND	0.20						
2-Butanone	ND	0.40						
t-Butyl Methyl Ether (MTBE)	ND	0.20						
Chloroform	ND	0.20						
1,1,1-Trichloroethane	ND	0.20						
Carbon Tetrachloride	ND	0.20						
Benzene	ND	0.20						
1,2-Dichloroethane	ND	0.20						
Trichloroethene	ND	0.20						
1,2-Dichloropropane	ND	0.20						
Bromodichloromethane	ND	0.20						
c-1,3-Dichloropropene	ND	0.20						
4-Methyl-2-Pentanone	ND	0.20						
Toluene	ND	0.20						
t-1,3-Dichloropropene	ND	0.20						
1,1,2-Trichloroethane	ND	0.20						
Tetrachloroethene	ND	0.20						
2-Hexanone	ND	0.20						
Dibromochloromethane	ND	0.20						

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/06/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK
Client Sample I.D.:	--
Date/Time Sampled:	--
Date/Time Analyzed:	5/6/26 15:34
QC Batch No.:	260506MS2A1
Analyst Initials:	AS/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	0.20
Chlorobenzene	ND	0.20
Ethylbenzene	ND	0.20
p,&m-Xylene	ND	0.20
o-Xylene	ND	0.20
Styrene	ND	0.20
Bromoform	ND	0.20
1,1,2,2-Tetrachloroethane	ND	0.20
Benzyl Chloride	ND	0.20
4-Ethyl Toluene	ND	0.20
1,3,5-Trimethylbenzene	ND	0.20
1,2,4-Trimethylbenzene	ND	0.20
1,3-Dichlorobenzene	ND	0.20
1,4-Dichlorobenzene	ND	0.20
1,2-Dichlorobenzene	ND	0.20
1,2,4-Trichlorobenzene	ND	1.4
Hexachlorobutadiene	ND	0.20
1,3-Butadiene	ND	1.0
Isopropanol	ND	1.0
n-Hexane	ND	1.0
Ethyl Acetate	ND	1.0
Tetrahydrofuran	ND	1.0
Cyclohexane	ND	1.0
Heptane	ND	1.0
1,4-Dioxane	ND	1.0

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 5/29/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 260506MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	5/6/26 15:34			5/6/26 14:19		5/6/26 14:57					
Analyst Initials:	AS/GD			AS/GD		AS/GD					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	**Result ppbv**	**RL ppbv**	**AMT. ppbv**	**Result ppbv**	**% Rec.**	**Result ppbv**	**% Rec.**	**RPD**	**Low %Rec**	**High %Rec**	**Max. RPD**
1,1-Dichloroethene	ND	0.20	10	**10.9**	109	**10.6**	106	2.9	**70**	**130**	30
Methylene Chloride	ND	0.20	10	**10.2**	102	**10.3**	103	0.2	**70**	**130**	30
Trichloroethene	ND	0.20	10	**11.3**	113	**11.0**	110	2.6	**70**	**130**	30
Toluene	ND	0.20	10	**10.9**	109	**10.9**	109	0.1	**70**	**130**	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	**9.91**	99	**10.2**	102	2.9	**70**	**130**	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date:** 5/7/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/06/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T050603-02		T050603-03		T050603-05		T050603-06	
Client Sample I.D.:	CV-24101		CV-2001		CV-24095		CV-24142	
Date/Time Sampled:	5/6/26 7:40		5/6/26 7:50		5/6/26 8:05		5/6/26 8:10	
Date/Time Analyzed:	5/6/26 16:07		5/6/26 16:21		5/6/26 16:50		5/6/26 17:05	
QC Batch No.:	260506GC8A2		260506GC8A2		260506GC8A2		260506GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	ND	10	780	10	2,800	10	1,500	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-14-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/06/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T050603-07		T050603-08		T050603-09		T050603-10	
Client Sample I.D.:	CV-2348		CV-2347		CV-2346		CV-108-52	
Date/Time Sampled:	5/6/26 8:15		5/6/26 8:20		5/6/26 8:25		5/6/26 8:30	
Date/Time Analyzed:	5/6/26 17:19		5/6/26 17:34		5/6/26 17:48		5/6/26 18:03	
QC Batch No.:	260506GC8A2		260506GC8A2		260506GC8A2		260506GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	460	10	1,100	10	2,200	10	100	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-14-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260506GC8A2
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	5/6/26 15:38			5/6/26 14:54		5/6/26 15:09					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,110	110	1,100	109	0.3	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-14-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/06/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T050603-02			T050603-03			T050603-05			T050603-06		
Client Sample I.D.:	CV-24101			CV-2001			CV-24095			CV-24142		
Date/Time Sampled:	5/6/26 7:40			5/6/26 7:50			5/6/26 8:05			5/6/26 8:10		
Date/Time Analyzed:	5/6/26 16:07			5/6/26 16:21			5/6/26 16:50			5/6/26 17:05		
QC Batch No.:	260506GC8A2			260506GC8A2			260506GC8A2			260506GC8A2		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	0.094 J	1.0	0.059	8.2	1.0	0.059	16	1.0	0.059	12	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-14-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/06/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T050603-07			T050603-08			T050603-09			T050603-10		
Client Sample I.D.:	CV-2348			CV-2347			CV-2346			CV-108-52		
Date/Time Sampled:	5/6/26 8:15			5/6/26 8:20			5/6/26 8:25			5/6/26 8:30		
Date/Time Analyzed:	5/6/26 17:19			5/6/26 17:34			5/6/26 17:48			5/6/26 18:03		
QC Batch No.:	260506GC8A2			260506GC8A2			260506GC8A2			260506GC8A2		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	2.7	1.0	0.059	5.6	1.0	0.059	13	1.0	0.059	0.66 J	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-14-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260506GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	5/6/26 15:38				5/6/26 14:54		5/6/26 15:09					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	4.86	98	4.85	98	0.2	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-14-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/06/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T050603-01		T050603-02		T050603-03		T050603-04	
Client Sample I.D.:	CV-24102		CV-24101		CV-2001		CV-24099	
Date/Time Sampled:	5/6/26 7:30		5/6/26 7:40		5/6/26 7:50		5/6/26 7:55	
Date/Time Analyzed:	5/6/26 15:52		5/6/26 16:07		5/6/26 16:21		5/6/26 16:36	
QC Batch No.:	260506GC8A2		260506GC8A2		260506GC8A2		260506GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**
Carbon Dioxide	48	0.010	54	0.010	73	0.010	86	0.010
Oxygen/Argon	1.5	0.50	0.69	0.50	1.3	0.50	0.55	0.50
Nitrogen	5.6	1.0	2.5	1.0	4.7	1.0	2.2	1.0
Methane	44	0.0010	43	0.0010	12	0.0010	10	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-14-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/06/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T050603-05		T050603-06		T050603-07		T050603-08	
Client Sample I.D.:	CV-24095		CV-24142		CV-2348		CV-2347	
Date/Time Sampled:	5/6/26 8:05		5/6/26 8:10		5/6/26 8:15		5/6/26 8:20	
Date/Time Analyzed:	5/6/26 16:50		5/6/26 17:05		5/6/26 17:19		5/6/26 17:34	
QC Batch No.:	260506GC8A2		260506GC8A2		260506GC8A2		260506GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**
Carbon Dioxide	76	0.010	46	0.010	46	0.010	57	0.010
Oxygen/Argon	0.63	0.50	8.3	0.50	2.9	0.50	1.8	0.50
Nitrogen	2.2	1.0	31	1.0	32	1.0	24	1.0
Methane	3.4	0.0010	1.6	0.0010	16	0.0010	11	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-14-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com
Member of the SGS Group (SGS SA)

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/06/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T050603-09		T050603-10					
Client Sample I.D.:	CV-2346		CV-108-52					
Date/Time Sampled:	5/6/26 8:25		5/6/26 8:30					
Date/Time Analyzed:	5/6/26 17:48		5/6/26 18:03					
QC Batch No.:	260506GC8A2		260506GC8A2					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**				
Carbon Dioxide	77	0.010	47	0.010				
Oxygen/Argon	0.79	0.50	0.95	0.50				
Nitrogen	3.8	1.0	3.5	1.0				
Methane	3.4	0.0010	47	0.0010				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-14-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com

Member of the SGS Group (SGS SA)

QC Batch No: 260506GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	5/6/26 15:38			5/6/26 14:54		5/6/26 15:09					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	9.48	95	9.48	95	0.0	70	130	30
Oxygen/Argon	ND	0.50	15	14.7	98	14.6	97	0.3	70	130	30
Nitrogen	ND	1.0	70	70.4	101	70.2	101	0.3	70	130	30
Methane	ND	0.0010	0.10	0.103	102	0.103	102	0.1	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-14-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175
TX Cert T104704450-14-6
EPA Methods TO14A, TO15
ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

May 29, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T050706-01/10

Enclosed are the results for sample(s) received 5/7/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME
Standard ■ 48 hours ☐
Same Day ☐ 72 hours ☐
24 hours ☐ 96 hours ☐
Other:

DELIVERABLES
EDD ■
EDF ☐
Level 3 ☐
Level 4 ☐

PAGE: 1 OF

Condition upon receipt:
Sealed Yes ☐ No ☐
Intact Yes ☐ No ☐
Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING
P.O. No.:
Bill to: 07FSAccountspayable@scsengineers.com
3900 Kilroy Airport Way, Suite 300
Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T050706-01	CV-2301	05/07/26	7:55AM	2-1L	Gas	N	X	X	X	X		
-02	CV-2302	05/07/26	8:05am	2-1L	Gas	N	X	X	X	X		
-03	CV-24071	05/07/26	8:10AM	1L	Gas	N	X	X	X			
-04	CV-2328	05/07/26	8:15AM	1L	Gas	N	X	X	X			
-05	CV-24062	05/07/26	8:17AM	1L	Gas	N	X	X	X			
-06	CV-24070	05/07/26	8:20AM	1L	Gas	N	X	X	X			
-07	CV-24084	05/07/26	8:25AM	1L	Gas	N	X					
-08	CV-2315	05/07/26	8:30AM	2-1L	Gas	N	X	X	X	X		
-09	CV-24065	05/07/26	8:35AM	2-1L	Gas	N	X	X	X	X		
-10	CV-24053	05/07/26	8:40AM	2-1L	Gas	N	X	X	X	X		

AUTHORIZATION TO PERFORM WORK	COMPANY SCS	DATE/TIME 5-7-26 9:20AM	
SAMPLED BY Erik Navrro	COMPANY SCS	DATE/TIME 5-7-26 9:20AM	
RELINQUISHED BY Erik Navrro	DATE/TIME 5/7/26 9:20AM	RECEIVED BY Ruben G	DATE/TIME 5/7/26 9:30
RELINQUISHED BY Ruben G	DATE/TIME 5/7/26 11:55	RECEIVED BY	DATE/TIME 5/7/26 1155
RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/07/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T050706-01		T050706-02		T050706-08		T050706-09	
Client Sample I.D.:	CV-2301		CV-2302		CV-2315		CV-24065	
Date/Time Sampled:	5/7/26 7:55		5/7/26 8:05		5/7/26 8:30		5/7/26 8:35	
Date/Time Analyzed:	5/7/26 17:58		5/7/26 18:37		5/7/26 19:15		5/7/26 19:54	
QC Batch No.:	260507MS2A1		260507MS2A1		260507MS2A1		260507MS2A1	
Analyst Initials:	AS/GD		AS/GD		AS/GD		AS/GD	
Dilution Factor:	4,000		4,800		4,000		1,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	4,000	ND	4,800	ND	4,000	ND	1,000
Chloromethane	ND Q	4,000	ND Q	4,800	14,000 Q	4,000	ND Q	1,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	4,000	ND	4,800	ND	4,000	ND	1,000
Vinyl Chloride	ND Q	4,000	ND Q	4,800	ND Q	4,000	ND Q	1,000
Bromomethane	ND	4,000	ND	4,800	ND	4,000	ND	1,000
Chloroethane	ND	20,000	ND	24,000	ND	20,000	ND	5,000
Trichlorofluoromethane (11)	ND	4,000	ND	4,800	ND	4,000	ND	1,000
1,1-Dichloroethene	ND	4,000	ND	4,800	ND	4,000	ND	1,000
Carbon Disulfide	14,000	4,000	ND	4,800	9,900	4,000	3,600	1,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	4,000	ND	4,800	ND	4,000	ND	1,000
Acetone	610,000 E	20,000	130,000	24,000	770,000 E	20,000	210,000 E	5,000
Methylene Chloride	ND	4,000	ND	4,800	ND	4,000	ND	1,000
t-1,2-Dichloroethene	ND	4,000	ND	4,800	ND	4,000	ND	1,000
1,1-Dichloroethane	ND	4,000	ND	4,800	ND	4,000	ND	1,000
Vinyl Acetate	ND	4,000	ND	4,800	ND	4,000	ND	1,000
c-1,2-Dichloroethene	ND	4,000	ND	4,800	ND	4,000	ND	1,000
2-Butanone	750,000	20,000	130,000	24,000	820,000	20,000	310,000 E	5,000
t-Butyl Methyl Ether (MTBE)	ND	4,000	ND	4,800	ND	4,000	1,600	1,000
Chloroform	ND	4,000	ND	4,800	ND	4,000	ND	1,000
1,1,1-Trichloroethane	ND	4,000	ND	4,800	ND	4,000	ND	1,000
Carbon Tetrachloride	ND	4,000	ND	4,800	ND	4,000	ND	1,000
Benzene	210,000	4,000	77,000	4,800	280,000	4,000	130,000	1,000
1,2-Dichloroethane	ND	4,000	ND	4,800	ND	4,000	ND	1,000
Trichloroethene	ND	4,000	ND	4,800	ND	4,000	ND	1,000
1,2-Dichloropropane	ND	4,000	ND	4,800	ND	4,000	ND	1,000
Bromodichloromethane	ND	4,000	ND	4,800	ND	4,000	ND	1,000
c-1,3-Dichloropropene	ND	4,000	ND	4,800	ND	4,000	ND	1,000
4-Methyl-2-Pentanone	8,900	4,000	ND	4,800	9,000	4,000	6,700	1,000
Toluene	9,800	4,000	ND	4,800	14,000	4,000	8,200	1,000
t-1,3-Dichloropropene	ND	8,000	ND	9,600	ND	8,000	ND	2,000
1,1,2-Trichloroethane	ND	4,000	ND	4,800	ND	4,000	ND	1,000
Tetrachloroethene	ND	4,000	ND	4,800	ND	4,000	ND	1,000
2-Hexanone	ND	4,000	ND	4,800	ND	4,000	1,700	1,000
Dibromochloromethane	ND	4,000	ND	4,800	ND	4,000	ND	1,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/07/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T050706-01		T050706-02		T050706-08		T050706-09	
Client Sample I.D.:	CV-2301		CV-2302		CV-2315		CV-24065	
Date/Time Sampled:	5/7/26 7:55		5/7/26 8:05		5/7/26 8:30		5/7/26 8:35	
Date/Time Analyzed:	5/7/26 17:58		5/7/26 18:37		5/7/26 19:15		5/7/26 19:54	
QC Batch No.:	260507MS2A1		260507MS2A1		260507MS2A1		260507MS2A1	
Analyst Initials:	AS/GD		AS/GD		AS/GD		AS/GD	
Dilution Factor:	4,000		4,800		4,000		1,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	4,000	ND	4,800	ND	4,000	ND	1,000
Chlorobenzene	ND	4,000	ND	4,800	ND	4,000	ND	1,000
Ethylbenzene	ND	4,000	ND	4,800	ND	4,000	**1,600**	1,000
p,&m-Xylene	ND	8,000	ND	9,600	ND	8,000	ND	2,000
o-Xylene	ND	4,000	ND	4,800	ND	4,000	ND	1,000
Styrene	ND	4,000	ND	4,800	ND	4,000	ND	1,000
Bromoform	ND	4,000	ND	4,800	ND	4,000	ND	1,000
1,1,2,2-Tetrachloroethane	ND	4,000	ND	4,800	ND	4,000	ND	1,000
Benzyl Chloride	ND	4,000	ND	4,800	ND	4,000	ND	1,000
4-Ethyl Toluene	ND	4,000	ND	4,800	ND	4,000	ND	1,000
1,3,5-Trimethylbenzene	ND	4,000	ND	4,800	ND	4,000	ND	1,000
1,2,4-Trimethylbenzene	ND	4,000	ND	4,800	ND	4,000	ND	1,000
1,3-Dichlorobenzene	ND	4,000	ND	4,800	ND	4,000	ND	1,000
1,4-Dichlorobenzene	ND	4,000	ND	4,800	ND	4,000	ND	1,000
1,2-Dichlorobenzene	ND	4,000	ND	4,800	ND	4,000	ND	1,000
1,2,4-Trichlorobenzene	ND	28,000	ND	34,000	ND	28,000	ND	7,000
Hexachlorobutadiene	ND	4,000	ND	4,800	ND	4,000	ND	1,000
1,3-Butadiene	ND	20,000	ND	24,000	ND	20,000	**8,200**	5,000
Isopropanol	**160,000**	20,000	**82,000**	24,000	**230,000**	20,000	**160,000**	5,000
n-Hexane	ND	20,000	ND	24,000	ND	20,000	ND	5,000
Ethyl Acetate	**46,000**	20,000	ND	24,000	**80,000**	20,000	**14,000**	5,000
Tetrahydrofuran	**550,000**	20,000	**110,000**	24,000	**670,000**	20,000	**220,000**	5,000
Cyclohexane	ND	20,000	ND	24,000	ND	20,000	ND	5,000
Heptane	ND	20,000	ND	24,000	**22,000**	20,000	**11,000**	5,000
1,4-Dioxane	ND	20,000	ND	24,000	ND	20,000	**6,500**	5,000

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited low recovery in the continuing calibration verification indicating possible low bias
E = Estimated. Analyte exceeded the upper calibration range

Reviewed/Approved By: _____ **Date** 5/9/26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/07/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T050706-10
Client Sample I.D.:	CV-24053
Date/Time Sampled:	5/7/26 8:40
Date/Time Analyzed:	5/7/26 20:34
QC Batch No.:	260507MS2A1
Analyst Initials:	AS/GD
Dilution Factor:	960

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	960
Chloromethane	ND Q	960
1,2-Cl-1,1,2,2-F ethane (114)	ND	960
Vinyl Chloride	ND Q	960
Bromomethane	ND	960
Chloroethane	ND	4,800
Trichlorofluoromethane (11)	ND	960
1,1-Dichloroethene	ND	960
Carbon Disulfide	2,200	960
1,1,2-Cl 1,2,2-F ethane (113)	ND	960
Acetone	110,000 E	4,800
Methylene Chloride	ND	960
t-1,2-Dichloroethene	ND	960
1,1-Dichloroethane	ND	960
Vinyl Acetate	ND	960
c-1,2-Dichloroethene	ND	960
2-Butanone	160,000	4,800
t-Butyl Methyl Ether (MTBE)	ND	960
Chloroform	ND	960
1,1,1-Trichloroethane	ND	960
Carbon Tetrachloride	ND	960
Benzene	46,000	960
1,2-Dichloroethane	ND	960
Trichloroethene	ND	960
1,2-Dichloropropane	ND	960
Bromodichloromethane	ND	960
c-1,3-Dichloropropene	ND	960
4-Methyl-2-Pentanone	3,600	960
Toluene	3,900	960
t-1,3-Dichloropropene	ND	1,900
1,1,2-Trichloroethane	ND	960
Tetrachloroethene	ND	960
2-Hexanone	1,200	960
Dibromochloromethane	ND	960

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/07/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T050706-10
Client Sample I.D.:	CV-24053
Date/Time Sampled:	5/7/26 8:40
Date/Time Analyzed:	5/7/26 20:34
QC Batch No.:	260507MS2A1
Analyst Initials:	AS/GD
Dilution Factor:	960

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	960
Chlorobenzene	ND	960
Ethylbenzene	ND	960
p,&m-Xylene	ND	1,900
o-Xylene	ND	960
Styrene	ND	960
Bromoform	ND	960
1,1,2,2-Tetrachloroethane	ND	960
Benzyl Chloride	ND	960
4-Ethyl Toluene	ND	960
1,3,5-Trimethylbenzene	ND	960
1,2,4-Trimethylbenzene	ND	960
1,3-Dichlorobenzene	ND	960
1,4-Dichlorobenzene	ND	960
1,2-Dichlorobenzene	ND	960
1,2,4-Trichlorobenzene	ND	6,700
Hexachlorobutadiene	ND	960
1,3-Butadiene	ND	4,800
Isopropanol	84,000	4,800
n-Hexane	ND	4,800
Ethyl Acetate	6,300	4,800
Tetrahydrofuran	120,000	4,800
Cyclohexane	ND	4,800
Heptane	ND	4,800
1,4-Dioxane	ND	4,800

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited low recovery in the continuing calibration verification indicating possible low bias
E = Estimated. Analyte exceeded the upper calibration range

Reviewed/Approved By: _____ Date 5/29/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/07/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK							
Client Sample I.D.:	--							
Date/Time Sampled:	--							
Date/Time Analyzed:	5/7/26 16:14							
QC Batch No.:	260507MS2A1							
Analyst Initials:	AS/GD							
Dilution Factor:	0.20							

ANALYTE	Result ppbv		RL ppbv						
Dichlorodifluoromethane (12)	ND		0.20						
Chloromethane	ND	Q	0.20						
1,2-Cl-1,1,2,2-F ethane (114)	ND		0.20						
Vinyl Chloride	ND	Q	0.20						
Bromomethane	ND		0.20						
Chloroethane	ND		1.0						
Trichlorofluoromethane (11)	ND		0.20						
1,1-Dichloroethene	ND		0.20						
Carbon Disulfide	ND		0.20						
1,1,2-Cl 1,2,2-F ethane (113)	ND		0.20						
Acetone	ND		1.0						
Methylene Chloride	ND		0.20						
t-1,2-Dichloroethene	ND		0.20						
1,1-Dichloroethane	ND		0.20						
Vinyl Acetate	ND		0.20						
c-1,2-Dichloroethene	ND		0.20						
2-Butanone	ND		1.0						
t-Butyl Methyl Ether (MTBE)	ND		0.20						
Chloroform	ND		0.20						
1,1,1-Trichloroethane	ND		0.20						
Carbon Tetrachloride	ND		0.20						
Benzene	ND		0.20						
1,2-Dichloroethane	ND		0.20						
Trichloroethene	ND		0.20						
1,2-Dichloropropane	ND		0.20						
Bromodichloromethane	ND		0.20						
c-1,3-Dichloropropene	ND		0.20						
4-Methyl-2-Pentanone	ND		0.20						
Toluene	ND		0.20						
t-1,3-Dichloropropene	ND		0.40						
1,1,2-Trichloroethane	ND		0.20						
Tetrachloroethene	ND		0.20						
2-Hexanone	ND		0.20						
Dibromochloromethane	ND		0.20						

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/07/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK
Client Sample I.D.:	--
Date/Time Sampled:	--
Date/Time Analyzed:	5/7/26 16:14
QC Batch No.:	260507MS2A1
Analyst Initials:	AS/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	0.20
Chlorobenzene	ND	0.20
Ethylbenzene	ND	0.20
p,&m-Xylene	ND	0.40
o-Xylene	ND	0.20
Styrene	ND	0.20
Bromoform	ND	0.20
1,1,2,2-Tetrachloroethane	ND	0.20
Benzyl Chloride	ND	0.20
4-Ethyl Toluene	ND	0.20
1,3,5-Trimethylbenzene	ND	0.20
1,2,4-Trimethylbenzene	ND	0.20
1,3-Dichlorobenzene	ND	0.20
1,4-Dichlorobenzene	ND	0.20
1,2-Dichlorobenzene	ND	0.20
1,2,4-Trichlorobenzene	ND	1.4
Hexachlorobutadiene	ND	0.20
1,3-Butadiene	ND	1.0
Isopropanol	ND	1.0
n-Hexane	ND	1.0
Ethyl Acetate	ND	1.0
Tetrahydrofuran	ND	1.0
Cyclohexane	ND	1.0
Heptane	ND	1.0
1,4-Dioxane	ND	1.0

RL = Reporting Limit
ND = Not Detected (below RL)
Q = Analyte exhibited low recovery in the continuing calibration verification indicating possible low bias

Reviewed/Approved By: _____ Date 5/7/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 260507MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	5/7/26 16:14			5/7/26 11:02		5/7/26 11:40					
Analyst Initials:	AS/GD			AS/GD		AS/GD					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	0.20	10	11.4	114	11.4	114	0.3	70	130	30
Methylene Chloride	ND	0.20	10	10.5	105	10.5	105	0.1	70	130	30
Trichloroethene	ND	0.20	10	11.4	114	11.3	113	0.8	70	130	30
Toluene	ND	0.20	10	11.1	111	11.3	113	1.2	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	10.1	101	10.3	103	1.4	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date:** 5/29/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/07/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T050706-01		T050706-02		T050706-03		T050706-04	
Client Sample I.D.:	CV-2301		CV-2302		CV-24071		CV-2328	
Date/Time Sampled:	5/7/26 7:55		5/7/26 8:05		5/7/26 8:10		5/7/26 8:15	
Date/Time Analyzed:	5/7/26 16:41		5/7/26 16:56		5/7/26 17:10		5/7/26 17:25	
QC Batch No.:	260507GC8A2		260507GC8A2		260507GC8A2		260507GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	2,200	10	320	10	190	10	980	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-20-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/07/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T050706-05		T050706-06		T050706-08		T050706-09	
Client Sample I.D.:	CV-24062		CV-24070		CV-2315		CV-24065	
Date/Time Sampled:	5/7/26 8:17		5/7/26 8:20		5/7/26 8:30		5/7/26 8:35	
Date/Time Analyzed:	5/7/26 17:39		5/7/26 17:54		5/7/26 18:23		5/7/26 18:37	
QC Batch No.:	260507GC8A2		260507GC8A2		260507GC8A2		260507GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	890	10	1,300	10	3,900	10	530	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com
Member of the SGS Group (SGS SA)

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/07/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	**T050706-10**							
Client Sample I.D.:	**CV-24053**							
Date/Time Sampled:	**5/7/26 8:40**							
Date/Time Analyzed:	**5/7/26 18:52**							
QC Batch No.:	**260507GC8A2**							
Analyst Initials:	**KD**							
Dilution Factor:	**1.0**							
ANALYTE	**Result ppmv**	**RL ppmv**						
Carbon Monoxide	88	10						

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-20-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260507GC8A2
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	5/7/26 14:02			5/7/26 13:04		5/7/26 13:18					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,080	107	1,080	107	0.6	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-20-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/07/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T050706-01			T050706-02			T050706-03			T050706-04		
Client Sample I.D.:	CV-2301			CV-2302			CV-24071			CV-2328		
Date/Time Sampled:	5/7/26 7:55			5/7/26 8:05			5/7/26 8:10			5/7/26 8:15		
Date/Time Analyzed:	5/7/26 16:41			5/7/26 16:56			5/7/26 17:10			5/7/26 17:25		
QC Batch No.:	260507GC8A2			260507GC8A2			260507GC8A2			260507GC8A2		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	15	1.0	0.059	5.3	1.0	0.059	2.4	1.0	0.059	11	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/07/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T050706-05			T050706-06			T050706-08			T050706-09		
Client Sample I.D.:	CV-24062			CV-24070			CV-2315			CV-24065		
Date/Time Sampled:	5/7/26 8:17			5/7/26 8:20			5/7/26 8:30			5/7/26 8:35		
Date/Time Analyzed:	5/7/26 17:39			5/7/26 17:54			5/7/26 18:23			5/7/26 18:37		
QC Batch No.:	260507GC8A2			260507GC8A2			260507GC8A2			260507GC8A2		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	8.0	1.0	0.059	11	1.0	0.059	14	1.0	0.059	0.98 J	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/07/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T050706-10		
Client Sample I.D.:	CV-24053		
Date/Time Sampled:	5/7/26 8:40		
Date/Time Analyzed:	5/7/26 18:52		
QC Batch No.:	260507GC8A2		
Analyst Initials:	KD		
Dilution Factor:	1.0		

ANALYTE	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	0.53 J	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260507GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	5/7/26 14:02				5/7/26 13:04		5/7/26 13:18					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	4.31	87	4.33	87	0.4	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/07/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T050706-01		T050706-02		T050706-03		T050706-04	
Client Sample I.D.:	CV-2301		CV-2302		CV-24071		CV-2328	
Date/Time Sampled:	5/7/26 7:55		5/7/26 8:05		5/7/26 8:10		5/7/26 8:15	
Date/Time Analyzed:	5/7/26 16:41		5/7/26 16:56		5/7/26 17:10		5/7/26 17:25	
QC Batch No.:	260507GC8A2		260507GC8A2		260507GC8A2		260507GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	76	0.010	52	0.010	50	0.010	77	0.010
Oxygen/Argon	1.3	0.50	1.4	0.50	0.66	0.50	0.59	0.50
Nitrogen	4.6	1.0	5.1	1.0	2.4	1.0	2.1	1.0
Methane	0.71	0.0010	36	0.0010	44	0.0010	8.0	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-20-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/07/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T050706-05		T050706-06		T050706-07		T050706-08	
Client Sample I.D.:	CV-24062		CV-24070		CV-24084		CV-2315	
Date/Time Sampled:	5/7/26 8:17		5/7/26 8:20		5/7/26 8:25		5/7/26 8:30	
Date/Time Analyzed:	5/7/26 17:39		5/7/26 17:54		5/7/26 18:08		5/7/26 18:23	
QC Batch No.:	260507GC8A2		260507GC8A2		260507GC8A2		260507GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	61	0.010	73	0.010	81	0.010	79	0.010
Oxygen/Argon	0.77	0.50	0.51	0.50	0.56	0.50	0.75	0.50
Nitrogen	2.8	1.0	1.9	1.0	1.9	1.0	2.6	1.0
Methane	26	0.0010	13	0.0010	2.4	0.0010	1.1	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 5-20-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/07/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T050706-09		T050706-10					
Client Sample I.D.:	CV-24065		CV-24053					
Date/Time Sampled:	5/7/26 8:35		5/7/26 8:40					
Date/Time Analyzed:	5/7/26 18:37		5/7/26 18:52					
QC Batch No.:	260507GC8A2		260507GC8A2					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**				
Carbon Dioxide	83	0.010	38	0.010				
Oxygen/Argon	0.79	0.50	4.1	0.50				
Nitrogen	2.9	1.0	18	1.0				
Methane	11	0.0010	39	0.0010				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260507GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	5/7/26 14:02			5/7/26 13:04		5/7/26 13:18					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	9.16	91	9.16	91	0.1	70	130	30
Oxygen/Argon	ND	0.50	15	14.9	99	14.9	99	0.1	70	130	30
Nitrogen	ND	1.0	70	70.8	102	70.8	102	0.0	70	130	30
Methane	ND	0.0010	0.10	0.101	100	0.101	100	0.4	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-20-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C,
ASTM D1946, RSK-175

TX Cert T104704450-14-6
EPA Methods TO14A, TO15

ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

May 31, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T051102-01/10

Enclosed are the results for sample(s) received 5/11/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AIR TECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME				DELIVERABLES		PAGE: 1 OF
Standard	■	48 hours	☐	EDD	■	Condition upon receipt:
Same Day	☐	72 hours	☐	EDF	☐	Sealed Yes ☐ No ☐
24 hours	☐	96 hours	☐	Level 3	☐	Intact Yes ☐ No ☐
Other:				Level 4	☐	Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:	
Bill to:	
	[redacted]@scsengineers.com
	3900 Kilroy Airport Way, Suite 300
	Long Beach, CA 90806-6816

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T051102-01	CV-2345	05/11/26	7:30am	1L	Gas	N	X	X	X			
-02	CV-2344	05/11/26	7:35am	1L	Gas	N	X	X	X			
-03	CV-2350	05/11/26	7:40m	2-1L	Gas	N	X	X	X	X		
-04	CV-24066	05/11/26	7:45am	1L	Gas	N	X	X	X			
-05	CV-2341	05/11/26	7:50m	1L	Gas	N	X	X	X			
-06	CV-1902A	05/11/26	7:55am	2-1L	Gas	N	X	X	X	X		
-07	CV-2337	05/11/26	8:05am	1L	Gas	N	X	X	X			
-08	CV-2002	05/11/26	8:10am	2-1L	Gas	N	X	X	X	X		
-09	CV-1532A	05/11/26	8:15am	2-1L	Gas	N	X	X	X	X		
-10	CV-1535	05/11/26	8:25am	2-1L	Gas	N	X	X	X	X		

AUTHORIZATION TO PERFORM WORK	COMPANY	05/11/26 9:11am	DATE/TIME
SAMPLED BY: Erik Navarro	COMPANY 05/11/26 9:11am		DATE/TIME
RELINQUISHED BY: Erik Navarro	DATE/TIME 5/11/2026 10:27	RECEIVED BY: Juan G.	DATE/TIME 5-11-26 10:27
RELINQUISHED BY: Juan Gutierrez	DATE/TIME 5-11-26 11:40	RECEIVED BY: [signature]	DATE/TIME 5/11/26 11:40
RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/11/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T051102-03		T051102-06		T051102-08		T051102-09	
Client Sample I.D.:	CV-2350		CV-1902A		CV-2002		CV-1532A	
Date/Time Sampled:	5/11/26 7:40		5/11/26 7:55		5/11/26 8:10		5/11/26 8:15	
Date/Time Analyzed:	5/11/26 18:36		5/11/26 19:14		5/11/26 19:52		5/11/26 20:30	
QC Batch No.:	260511MS2A1		260511MS2A1		260511MS2A1		260511MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	9,000		8,800		4,000		10,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	9,000	ND	8,800	ND	4,000	ND	10,000
Chloromethane	ND	9,000	ND	8,800	ND	4,000	ND	10,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	9,000	ND	8,800	ND	4,000	ND	10,000
Vinyl Chloride	ND	9,000	ND	8,800	ND	4,000	ND	10,000
Bromomethane	ND	9,000	ND	8,800	ND	4,000	ND	10,000
Chloroethane	ND	45,000	ND	44,000	ND	20,000	ND	50,000
Trichlorofluoromethane (11)	ND	9,000	ND	8,800	ND	4,000	ND	10,000
1,1-Dichloroethene	ND	9,000	ND	8,800	ND	4,000	ND	10,000
Carbon Disulfide	ND	9,000	ND	8,800	ND	4,000	ND	10,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	9,000	ND	8,800	ND	4,000	ND	10,000
Acetone	280,000	45,000	910,000	44,000	130,000	20,000	530,000	50,000
Methylene Chloride	ND	9,000	ND	8,800	ND	4,000	ND	10,000
t-1,2-Dichloroethene	ND	9,000	ND	8,800	ND	4,000	ND	10,000
1,1-Dichloroethane	ND	9,000	ND	8,800	ND	4,000	ND	10,000
Vinyl Acetate	ND	9,000	ND	8,800	ND	4,000	ND	10,000
c-1,2-Dichloroethene	ND	9,000	ND	8,800	ND	4,000	ND	10,000
2-Butanone	210,000	45,000	630,000	44,000	110,000	20,000	390,000	50,000
t-Butyl Methyl Ether (MTBE)	ND	9,000	ND	8,800	ND	4,000	ND	10,000
Chloroform	ND	9,000	ND	8,800	ND	4,000	ND	10,000
1,1,1-Trichloroethane	ND	9,000	ND	8,800	ND	4,000	ND	10,000
Carbon Tetrachloride	ND	9,000	ND	8,800	ND	4,000	ND	10,000
Benzene	290,000	9,000	160,000	8,800	73,000	4,000	220,000	10,000
1,2-Dichloroethane	ND	9,000	ND	8,800	ND	4,000	ND	10,000
Trichloroethene	ND	9,000	ND	8,800	ND	4,000	ND	10,000
1,2-Dichloropropane	ND	9,000	ND	8,800	ND	4,000	ND	10,000
Bromodichloromethane	ND	9,000	ND	8,800	ND	4,000	ND	10,000
c-1,3-Dichloropropene	ND	9,000	ND	8,800	ND	4,000	ND	10,000
4-Methyl-2-Pentanone	ND	9,000	ND	8,800	ND	4,000	ND	10,000
Toluene	10,000	9,000	8,900	8,800	ND	4,000	10,000	10,000
t-1,3-Dichloropropene	ND	18,000	ND	18,000	ND	8,000	ND	20,000
1,1,2-Trichloroethane	ND	9,000	ND	8,800	ND	4,000	ND	10,000
Tetrachloroethene	ND	9,000	ND	8,800	ND	4,000	ND	10,000
2-Hexanone	ND	9,000	ND	8,800	ND	4,000	ND	10,000
Dibromochloromethane	ND	9,000	ND	8,800	ND	4,000	ND	10,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/11/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T051102-03		T051102-06		T051102-08		T051102-09	
Client Sample I.D.:	CV-2350		CV-1902A		CV-2002		CV-1532A	
Date/Time Sampled:	5/11/26 7:40		5/11/26 7:55		5/11/26 8:10		5/11/26 8:15	
Date/Time Analyzed:	5/11/26 18:36		5/11/26 19:14		5/11/26 19:52		5/11/26 20:30	
QC Batch No.:	260511MS2A1		260511MS2A1		260511MS2A1		260511MS2A1	
Analyst Initials:	VM/GD		VM/GD		VM/GD		VM/GD	
Dilution Factor:	9,000		8,800		4,000		10,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	9,000	ND	8,800	ND	4,000	ND	10,000
Chlorobenzene	ND	9,000	ND	8,800	ND	4,000	ND	10,000
Ethylbenzene	ND	9,000	ND	8,800	ND	4,000	ND	10,000
p,&m-Xylene	ND	18,000	ND	18,000	ND	8,000	ND	20,000
o-Xylene	ND	9,000	ND	8,800	ND	4,000	ND	10,000
Styrene	ND	9,000	ND	8,800	ND	4,000	ND	10,000
Bromoform	ND	9,000	ND	8,800	ND	4,000	ND	10,000
1,1,2,2-Tetrachloroethane	ND	9,000	ND	8,800	ND	4,000	ND	10,000
Benzyl Chloride	ND	9,000	ND	8,800	ND	4,000	ND	10,000
4-Ethyl Toluene	ND	9,000	ND	8,800	ND	4,000	ND	10,000
1,3,5-Trimethylbenzene	ND	9,000	ND	8,800	ND	4,000	ND	10,000
1,2,4-Trimethylbenzene	ND	9,000	ND	8,800	ND	4,000	ND	10,000
1,3-Dichlorobenzene	ND	9,000	ND	8,800	ND	4,000	ND	10,000
1,4-Dichlorobenzene	ND	9,000	ND	8,800	ND	4,000	ND	10,000
1,2-Dichlorobenzene	ND	9,000	ND	8,800	ND	4,000	ND	10,000
1,2,4-Trichlorobenzene	ND	9,000	ND	8,800	ND	4,000	ND	10,000
Hexachlorobutadiene	ND	9,000	ND	8,800	ND	4,000	ND	10,000
1,3-Butadiene	ND	45,000	ND	44,000	ND	20,000	ND	50,000
Isopropanol	220,000	45,000	190,000	44,000	200,000	20,000	210,000	50,000
n-Hexane	ND	45,000	ND	44,000	ND	20,000	ND	50,000
Ethyl Acetate	ND	45,000	ND	44,000	ND	20,000	ND	50,000
Tetrahydrofuran	280,000	45,000	370,000	44,000	85,000	20,000	260,000	50,000
Cyclohexane	ND	45,000	ND	44,000	ND	20,000	ND	50,000
Heptane	ND	45,000	ND	44,000	ND	20,000	ND	50,000
1,4-Dioxane	ND	45,000	ND	44,000	ND	20,000	ND	50,000

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 5/26/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/11/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T051102-10
Client Sample I.D.:	CV-1535
Date/Time Sampled:	5/11/26 8:25
Date/Time Analyzed:	5/11/26 21:08
QC Batch No.:	260511MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	160

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	160
Chloromethane	340	160
1,2-Cl-1,1,2,2-F ethane (114)	ND	160
Vinyl Chloride	ND	160
Bromomethane	ND	160
Chloroethane	ND	800
Trichlorofluoromethane (11)	ND	160
1,1-Dichloroethene	ND	160
Carbon Disulfide	380	160
1,1,2-Cl 1,2,2-F ethane (113)	ND	160
Acetone	69,000 E	800
Methylene Chloride	ND	160
t-1,2-Dichloroethene	ND	160
1,1-Dichloroethane	ND	160
Vinyl Acetate	ND	160
c-1,2-Dichloroethene	ND	160
2-Butanone	100,000 E	800
t-Butyl Methyl Ether (MTBE)	580	160
Chloroform	ND	160
1,1,1-Trichloroethane	ND	160
Carbon Tetrachloride	ND	160
Benzene	43,000 E	160
1,2-Dichloroethane	ND	160
Trichloroethene	ND	160
1,2-Dichloropropane	ND	160
Bromodichloromethane	ND	160
c-1,3-Dichloropropene	ND	160
4-Methyl-2-Pentanone	4,300	160
Toluene	4,700	160
t-1,3-Dichloropropene	ND	320
1,1,2-Trichloroethane	ND	160
Tetrachloroethene	ND	160
2-Hexanone	780	160
Dibromochloromethane	ND	160

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/11/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T051102-10
Client Sample I.D.:	CV-1535
Date/Time Sampled:	5/11/26 8:25
Date/Time Analyzed:	5/11/26 21:08
QC Batch No.:	260511MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	160

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	160
Chlorobenzene	ND	160
Ethylbenzene	930	160
p,&m-Xylene	560	320
o-Xylene	170	160
Styrene	ND	160
Bromoform	ND	160
1,1,2,2-Tetrachloroethane	ND	160
Benzyl Chloride	ND	160
4-Ethyl Toluene	ND	160
1,3,5-Trimethylbenzene	ND	160
1,2,4-Trimethylbenzene	ND	160
1,3-Dichlorobenzene	ND	160
1,4-Dichlorobenzene	ND	160
1,2-Dichlorobenzene	ND	160
1,2,4-Trichlorobenzene	ND	160
Hexachlorobutadiene	ND	160
1,3-Butadiene	1,800	800
Isopropanol	71,000 E	800
n-Hexane	1,900	800
Ethyl Acetate	10,000	800
Tetrahydrofuran	91,000 E	800
Cyclohexane	1,300	800
Heptane	7,300	800
1,4-Dioxane	3,500	800

RL = Reporting Limit
ND = Not Detected (below RL)
E = Estimated. Result exceeded the upper calibration range

Reviewed/Approved By: _____ Date 5/26/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/11/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK							
Client Sample I.D.:	--							
Date/Time Sampled:	--							
Date/Time Analyzed:	5/11/26 13:18							
QC Batch No.:	260511MS2A1							
Analyst Initials:	VM/GD							
Dilution Factor:	0.20							

ANALYTE	Result ppbv	RL ppbv						
Dichlorodifluoromethane (12)	ND	0.20						
Chloromethane	ND	0.20						
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20						
Vinyl Chloride	ND	0.20						
Bromomethane	ND	0.20						
Chloroethane	ND	1.0						
Trichlorofluoromethane (11)	ND	0.20						
1,1-Dichloroethene	ND	0.20						
Carbon Disulfide	ND	0.20						
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20						
Acetone	ND	1.0						
Methylene Chloride	ND	0.20						
t-1,2-Dichloroethene	ND	0.20						
1,1-Dichloroethane	ND	0.20						
Vinyl Acetate	ND	0.20						
c-1,2-Dichloroethene	ND	0.20						
2-Butanone	ND	1.0						
t-Butyl Methyl Ether (MTBE)	ND	0.20						
Chloroform	ND	0.20						
1,1,1-Trichloroethane	ND	0.20						
Carbon Tetrachloride	ND	0.20						
Benzene	ND	0.20						
1,2-Dichloroethane	ND	0.20						
Trichloroethene	ND	0.20						
1,2-Dichloropropane	ND	0.20						
Bromodichloromethane	ND	0.20						
c-1,3-Dichloropropene	ND	0.20						
4-Methyl-2-Pentanone	ND	0.20						
Toluene	ND	0.20						
t-1,3-Dichloropropene	ND	0.40						
1,1,2-Trichloroethane	ND	0.20						
Tetrachloroethene	ND	0.20						
2-Hexanone	ND	0.20						
Dibromochloromethane	ND	0.20						

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/11/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK
Client Sample I.D.:	--
Date/Time Sampled:	--
Date/Time Analyzed:	5/11/26 13:18
QC Batch No.:	260511MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	0.20
Chlorobenzene	ND	0.20
Ethylbenzene	ND	0.20
p,&m-Xylene	ND	0.40
o-Xylene	ND	0.20
Styrene	ND	0.20
Bromoform	ND	0.20
1,1,2,2-Tetrachloroethane	ND	0.20
Benzyl Chloride	ND	0.20
4-Ethyl Toluene	ND	0.20
1,3,5-Trimethylbenzene	ND	0.20
1,2,4-Trimethylbenzene	ND	0.20
1,3-Dichlorobenzene	ND	0.20
1,4-Dichlorobenzene	ND	0.20
1,2-Dichlorobenzene	ND	0.20
1,2,4-Trichlorobenzene	ND	0.20
Hexachlorobutadiene	ND	0.20
1,3-Butadiene	ND	1.0
Isopropanol	ND	1.0
n-Hexane	ND	1.0
Ethyl Acetate	ND	1.0
Tetrahydrofuran	ND	1.0
Cyclohexane	ND	1.0
Heptane	ND	1.0
1,4-Dioxane	ND	1.0

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 5/9/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 260511MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	5/11/26 13:18			5/11/26 11:26		5/11/26 12:03					
Analyst Initials:	VM/GD			VM/GD		VM/GD					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	**Result ppbv**	**RL ppbv**	**AMT. ppbv**	**Result ppbv**	**% Rec.**	**Result ppbv**	**% Rec.**	**RPD**	**Low %Rec**	**High %Rec**	**Max. RPD**
1,1-Dichloroethene	ND	0.20	10	11.6	116	11.8	118	1.7	70	130	30
Methylene Chloride	ND	0.20	10	12.0	120	12.0	120	0.7	70	130	30
Trichloroethene	ND	0.20	10	11.6	116	11.8	118	1.4	70	130	30
Toluene	ND	0.20	10	12.0	120	11.9	119	0.2	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	11.4	114	11.4	114	0.1	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date:** 5/12/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/11/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T051102-01		T051102-02		T051102-03		T051102-04	
Client Sample I.D.:	CV-2345		CV-2344		CV-2350		CV-24066	
Date/Time Sampled:	5/11/26 7:30		5/11/26 7:35		5/11/26 7:40		5/11/26 7:45	
Date/Time Analyzed:	5/11/26 16:26		5/11/26 16:40		5/11/26 16:55		5/11/26 17:09	
QC Batch No.:	260511GC8A3		260511GC8A3		260511GC8A3		260511GC8A3	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	580	10	2,900	10	3,700	10	390	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-20-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com
Member of the SGS Group (SGS SA)

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/11/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T051102-05		T051102-06		T051102-07		T051102-08	
Client Sample I.D.:	CV-2341		CV-1902A		CV-2337		CV-2002	
Date/Time Sampled:	5/11/26 7:50		5/11/26 7:55		5/11/26 8:05		5/11/26 8:10	
Date/Time Analyzed:	5/11/26 17:24		5/11/26 17:38		5/11/26 17:53		5/11/26 18:07	
QC Batch No.:	260511GC8A3		260511GC8A3		260511GC8A3		260511GC8A3	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	850	10	930	10	3,500	10	860	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-20-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/11/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T051102-09		T051102-10					
Client Sample I.D.:	CV-1532A		CV-1535					
Date/Time Sampled:	5/11/26 8:15		5/11/26 8:25					
Date/Time Analyzed:	5/11/26 18:22		5/11/26 18:36					
QC Batch No.:	260511GC8A3		260511GC8A3					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv				
Carbon Monoxide	580	10	100	10				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260511GC8A3
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	5/11/26 15:42			5/11/26 15:13		5/11/26 15:28					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,050	104	1,040	103	0.8	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-20-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/11/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T051102-01			T051102-02			T051102-03			T051102-04		
Client Sample I.D.:	CV-2345			CV-2344			CV-2350			CV-24066		
Date/Time Sampled:	5/11/26 7:30			5/11/26 7:35			5/11/26 7:40			5/11/26 7:45		
Date/Time Analyzed:	5/11/26 16:26			5/11/26 16:40			5/11/26 16:55			5/11/26 17:09		
QC Batch No.:	260511GC8A3			260511GC8A3			260511GC8A3			260511GC8A3		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	2.8	1.0	0.059	16	1.0	0.059	17	1.0	0.059	3.2	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/11/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T051102-05			T051102-06			T051102-07			T051102-08		
Client Sample I.D.:	CV-2341			CV-1902A			CV-2337			CV-2002		
Date/Time Sampled:	5/11/26 7:50			5/11/26 7:55			5/11/26 8:05			5/11/26 8:10		
Date/Time Analyzed:	5/11/26 17:24			5/11/26 17:38			5/11/26 17:53			5/11/26 18:07		
QC Batch No.:	260511GC8A3			260511GC8A3			260511GC8A3			260511GC8A3		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	9.4	1.0	0.059	19	1.0	0.059	13	1.0	0.059	8.3	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/11/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T051102-09			T051102-10								
Client Sample I.D.:	CV-1532A			CV-1535								
Date/Time Sampled:	5/11/26 8:15			5/11/26 8:25								
Date/Time Analyzed:	5/11/26 18:22			5/11/26 18:36								
QC Batch No.:	260511GC8A3			260511GC8A3								
Analyst Initials:	KD			KD								
Dilution Factor:	1.0			1.0								
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v						
Hydrogen	6.1	1.0	0.059	0.98 J	1.0	0.059						

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260511GC8A3
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	5/11/26 15:42				5/11/26 15:13		5/11/26 15:28					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	4.22	85	4.12	83	2.3	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/11/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T051102-01		T051102-02		T051102-03		T051102-04	
Client Sample I.D.:	CV-2345		CV-2344		CV-2350		CV-24066	
Date/Time Sampled:	5/11/26 7:30		5/11/26 7:35		5/11/26 7:40		5/11/26 7:45	
Date/Time Analyzed:	5/11/26 16:26		5/11/26 16:40		5/11/26 16:55		5/11/26 17:09	
QC Batch No.:	260511GC8A3		260511GC8A3		260511GC8A3		260511GC8A3	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	75	0.010	76	0.010	75	0.010	49	0.010
Oxygen/Argon	1.4	0.50	1.3	0.50	ND	0.50	0.73	0.50
Nitrogen	5.9	1.0	4.6	1.0	1.5	1.0	21	1.0
Methane	14	0.0010	1.0	0.0010	3.9	0.0010	25	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/11/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T051102-05		T051102-06		T051102-07		T051102-08	
Client Sample I.D.:	CV-2341		CV-1902A		CV-2337		CV-2002	
Date/Time Sampled:	5/11/26 7:50		5/11/26 7:55		5/11/26 8:05		5/11/26 8:10	
Date/Time Analyzed:	5/11/26 17:24		5/11/26 17:38		5/11/26 17:53		5/11/26 18:07	
QC Batch No.:	260511GC8A3		260511GC8A3		260511GC8A3		260511GC8A3	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**
Carbon Dioxide	45	0.010	74	0.010	72	0.010	75	0.010
Oxygen/Argon	8.7	0.50	ND	0.50	2.0	0.50	0.93	0.50
Nitrogen	33	1.0	1.3	1.0	7.3	1.0	3.4	1.0
Methane	3.7	0.0010	1.9	0.0010	4.1	0.0010	11	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 5-20-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/11/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T051102-09		T051102-10					
Client Sample I.D.:	CV-1532A		CV-1535					
Date/Time Sampled:	5/11/26 8:15		5/11/26 8:25					
Date/Time Analyzed:	5/11/26 18:22		5/11/26 18:36					
QC Batch No.:	260511GC8A3		260511GC8A3					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**				
Carbon Dioxide	75	0.010	51	0.010				
Oxygen/Argon	ND	0.50	ND	0.50				
Nitrogen	1.8	1.0	1.7	1.0				
Methane	15	0.0010	46	0.0010				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-20-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

SGS North America Inc. | 18501 Gale Ave, Ste 130, City Of Industry, CA 91748 t +1 (626) 964-4032 www.sgs.com
Member of the SGS Group (SGS SA)

QC Batch No: 260511GC8A3
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	5/11/26 15:42			5/11/26 15:13		5/11/26 15:28					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	9.12	91	9.09	91	0.4	70	130	30
Oxygen/Argon	ND	0.50	15	15.0	100	15.0	100	0.0	70	130	30
Nitrogen	ND	1.0	70	71.5	102	71.4	102	0.1	70	130	30
Methane	ND	0.0010	0.10	0.102	101	0.101	100	0.5	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-20-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175
TX Cert T104704450-14-6
EPA Methods TO14A, TO15
ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

May 31, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T051203-01/10

Enclosed are the results for sample(s) received 5/12/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME
Standard ■ 48 hours ☐
Same Day ☐ 72 hours ☐
24 hours ☐ 96 hours ☐
Other:

DELIVERABLES
EDD ■
EDF ☐
Level 3 ☐
Level 4 ☐

PAGE: 1 OF

Condition upon receipt:
Sealed Yes ☐ No ☐
Intact Yes ☐ No ☐
Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING
P.O. No.:
Bill to:
[redacted]@scsengineers.com
3900 Kilroy Airport Way, Suite 300
Long Beach, CA 90806-6816

ANALYSIS REQUEST

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T051203-01	CV-2353	05/12/26	7:35AM	1L	Gas	N	X	X	X			
-02	H-2165W	05/12/26	7:45AM	2-1L	Gas	N	X	X	X	X		
-03	H-2273W	05/12/26	7:50AM	2-1L	Gas	N	X	X	X	X		
-04	CV-2314	05/12/26	8:05AM	1L	Gas	N	X	X	X			
-05	CV-2305	05/12/26	8:10AM	1L	Gas	N	X	X	X			
-06	CV-24064	05/12/26	8:15AM	1L	Gas	N	X	X	X			
-07	CV-24063	05/12/26	8:20AM	1L	Gas	N	X	X	X			
-08	CV-2303	05/12/26	8:30AM	2-1L	Gas	N	X	X	X	X		
-09	CV-24017	05/12/26	8:35AM	2-1L	Gas	N	X	X	X	X		
-10	CV-24007	05/12/26	8:40AM	2-1L	Gas	N	X	X	X	X		

AUTHORIZATION TO PERFORM WORK		COMPANY SCS	DATE/TIME 5-12-26 9:08
SAMPLED BY	ERIK NAVARRO	COMPANY SCS	DATE/TIME 5-12-26 9:08
RELINQUISHED BY	ERIK NAVARRO	DATE/TIME 5-12-26 9:08	RECEIVED BY [signature] DATE/TIME 5/12/26 9:08
RELINQUISHED BY	[signature]	DATE/TIME 5/12/26 11:58	RECEIVED BY [signature] DATE/TIME 5/12/26 11:58
RELINQUISHED BY		DATE/TIME	RECEIVED BY DATE/TIME

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/12/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T051203-02		T051203-03		T051203-08		T051203-09	
Client Sample I.D.:	H-2165W		H-2273W		CV-2303		CV-24017	
Date/Time Sampled:	5/12/26 7:45		5/12/26 7:50		5/12/26 8:30		5/12/26 8:35	
Date/Time Analyzed:	5/12/26 18:03		5/12/26 18:41		5/12/26 19:19		5/12/26 19:58	
QC Batch No.:	260512MS2A1		260512MS2A1		260512MS2A1		260512MS2A1	
Analyst Initials:	VM		VM		VM		VM	
Dilution Factor:	10,000		2,000		10,000		10,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	10,000	ND	2,000	ND	10,000	ND	10,000
Chloromethane	ND	10,000	ND	2,000	ND	10,000	**12,000**	10,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	10,000	ND	2,000	ND	10,000	ND	10,000
Vinyl Chloride	ND	10,000	ND	2,000	ND	10,000	ND	10,000
Bromomethane	ND	10,000	ND	2,000	ND	10,000	ND	10,000
Chloroethane	ND	10,000	ND	2,000	ND	10,000	ND	10,000
Trichlorofluoromethane (11)	ND	10,000	ND	2,000	ND	10,000	ND	10,000
1,1-Dichloroethene	ND	10,000	ND	2,000	ND	10,000	ND	10,000
Carbon Disulfide	ND	10,000	ND	2,000	ND	10,000	ND	10,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	10,000	ND	2,000	ND	10,000	ND	10,000
Acetone	**350,000**	10,000	**200,000**	2,000	**1,200,000 E**	10,000	**950,000**	10,000
Methylene Chloride	ND	10,000	ND	2,000	ND	10,000	ND	10,000
t-1,2-Dichloroethene	ND	10,000	ND	2,000	ND	10,000	ND	10,000
1,1-Dichloroethane	ND	10,000	ND	2,000	ND	10,000	ND	10,000
Vinyl Acetate	ND	10,000	ND	2,000	ND	10,000	ND	10,000
c-1,2-Dichloroethene	ND	10,000	ND	2,000	ND	10,000	ND	10,000
2-Butanone	**260,000**	20,000	**200,000**	4,000	**1,100,000**	20,000	**700,000**	20,000
t-Butyl Methyl Ether (MTBE)	ND	10,000	ND	2,000	ND	10,000	ND	10,000
Chloroform	ND	10,000	ND	2,000	ND	10,000	ND	10,000
1,1,1-Trichloroethane	ND	10,000	ND	2,000	ND	10,000	ND	10,000
Carbon Tetrachloride	ND	10,000	ND	2,000	ND	10,000	ND	10,000
Benzene	**120,000**	10,000	**98,000**	2,000	**290,000**	10,000	**210,000**	10,000
1,2-Dichloroethane	ND	10,000	ND	2,000	ND	10,000	ND	10,000
Trichloroethene	ND	10,000	ND	2,000	ND	10,000	ND	10,000
1,2-Dichloropropane	ND	10,000	ND	2,000	ND	10,000	ND	10,000
Bromodichloromethane	ND	10,000	ND	2,000	ND	10,000	ND	10,000
c-1,3-Dichloropropene	ND	10,000	ND	2,000	ND	10,000	ND	10,000
4-Methyl-2-Pentanone	ND	10,000	**4,600**	2,000	**20,000**	10,000	ND	10,000
Toluene	ND	10,000	**4,400**	2,000	**26,000**	10,000	**10,000**	10,000
t-1,3-Dichloropropene	ND	10,000	ND	2,000	ND	10,000	ND	10,000
1,1,2-Trichloroethane	ND	10,000	ND	2,000	ND	10,000	ND	10,000
Tetrachloroethene	ND	10,000	ND	2,000	ND	10,000	ND	10,000
2-Hexanone	ND	10,000	ND	2,000	ND	10,000	ND	10,000
Dibromochloromethane	ND	10,000	ND	2,000	ND	10,000	ND	10,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/12/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T051203-02		T051203-03		T051203-08		T051203-09	
Client Sample I.D.:	H-2165W		H-2273W		CV-2303		CV-24017	
Date/Time Sampled:	5/12/26 7:45		5/12/26 7:50		5/12/26 8:30		5/12/26 8:35	
Date/Time Analyzed:	5/12/26 18:03		5/12/26 18:41		5/12/26 19:19		5/12/26 19:58	
QC Batch No.:	260512MS2A1		260512MS2A1		260512MS2A1		260512MS2A1	
Analyst Initials:	VM		VM		VM		VM	
Dilution Factor:	10,000		2,000		10,000		10,000	
ANALYTE	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	10,000	ND	2,000	ND	10,000	ND	10,000
Chlorobenzene	ND	10,000	ND	2,000	ND	10,000	ND	10,000
Ethylbenzene	ND	10,000	ND	2,000	ND	10,000	ND	10,000
p,&m-Xylene	ND	10,000	ND	2,000	ND	10,000	ND	10,000
o-Xylene	ND	10,000	ND	2,000	ND	10,000	ND	10,000
Styrene	ND	10,000	ND	2,000	ND	10,000	ND	10,000
Bromoform	ND	10,000	ND	2,000	ND	10,000	ND	10,000
1,1,2,2-Tetrachloroethane	ND	10,000	ND	2,000	ND	10,000	ND	10,000
Benzyl Chloride	ND	10,000	ND	2,000	ND	10,000	ND	10,000
4-Ethyl Toluene	ND	10,000	ND	2,000	ND	10,000	ND	10,000
1,3,5-Trimethylbenzene	ND	10,000	ND	2,000	ND	10,000	ND	10,000
1,2,4-Trimethylbenzene	ND	10,000	ND	2,000	ND	10,000	ND	10,000
1,3-Dichlorobenzene	ND	10,000	ND	2,000	ND	10,000	ND	10,000
1,4-Dichlorobenzene	ND	10,000	ND	2,000	ND	10,000	ND	10,000
1,2-Dichlorobenzene	ND	10,000	ND	2,000	ND	10,000	ND	10,000
1,2,4-Trichlorobenzene	ND	10,000	ND	2,000	ND	10,000	ND	10,000
Hexachlorobutadiene	ND	10,000	ND	2,000	ND	10,000	ND	10,000
1,3-Butadiene	ND	50,000	ND	10,000	ND	50,000	ND	50,000
Isopropanol	140,000	50,000	110,000	10,000	160,000	50,000	150,000	50,000
n-Hexane	ND	50,000	ND	10,000	ND	50,000	ND	50,000
Ethyl Acetate	ND	50,000	21,000	10,000	98,000	50,000	62,000	50,000
Tetrahydrofuran	180,000	50,000	130,000	10,000	770,000	50,000	490,000	50,000
Cyclohexane	ND	50,000	ND	10,000	ND	50,000	ND	50,000
Heptane	ND	50,000	ND	10,000	ND	50,000	ND	50,000
1,4-Dioxane	ND	50,000	ND	10,000	ND	50,000	ND	50,000

RL = Reporting Limit
ND = Not Detected (below RL)
E = Estimated. Result exceeds the upper calibration limit

Reviewed/Approved By: _____ Date 5/31/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/12/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T051203-10
Client Sample I.D.:	CV-24007
Date/Time Sampled:	5/12/26 8:40
Date/Time Analyzed:	5/12/26 20:36
QC Batch No.:	260512MS2A1
Analyst Initials:	VM
Dilution Factor:	10,000

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	10,000
Chloromethane	ND	10,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	10,000
Vinyl Chloride	ND	10,000
Bromomethane	ND	10,000
Chloroethane	ND	10,000
Trichlorofluoromethane (11)	ND	10,000
1,1-Dichloroethene	ND	10,000
Carbon Disulfide	ND	10,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	10,000
Acetone	700,000	10,000
Methylene Chloride	ND	10,000
t-1,2-Dichloroethene	ND	10,000
1,1-Dichloroethane	ND	10,000
Vinyl Acetate	ND	10,000
c-1,2-Dichloroethene	ND	10,000
2-Butanone	510,000	20,000
t-Butyl Methyl Ether (MTBE)	ND	10,000
Chloroform	ND	10,000
1,1,1-Trichloroethane	ND	10,000
Carbon Tetrachloride	ND	10,000
Benzene	270,000	10,000
1,2-Dichloroethane	ND	10,000
Trichloroethene	ND	10,000
1,2-Dichloropropane	ND	10,000
Bromodichloromethane	ND	10,000
c-1,3-Dichloropropene	ND	10,000
4-Methyl-2-Pentanone	ND	10,000
Toluene	31,000	10,000
t-1,3-Dichloropropene	ND	10,000
1,1,2-Trichloroethane	ND	10,000
Tetrachloroethene	ND	10,000
2-Hexanone	ND	10,000
Dibromochloromethane	ND	10,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/12/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T051203-10
Client Sample I.D.:	CV-24007
Date/Time Sampled:	5/12/26 8:40
Date/Time Analyzed:	5/12/26 20:36
QC Batch No.:	260512MS2A1
Analyst Initials:	VM
Dilution Factor:	10,000

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	10,000
Chlorobenzene	ND	10,000
Ethylbenzene	ND	10,000
p,&m-Xylene	ND	10,000
o-Xylene	ND	10,000
Styrene	ND	10,000
Bromoform	ND	10,000
1,1,2,2-Tetrachloroethane	ND	10,000
Benzyl Chloride	ND	10,000
4-Ethyl Toluene	ND	10,000
1,3,5-Trimethylbenzene	ND	10,000
1,2,4-Trimethylbenzene	ND	10,000
1,3-Dichlorobenzene	ND	10,000
1,4-Dichlorobenzene	ND	10,000
1,2-Dichlorobenzene	ND	10,000
1,2,4-Trichlorobenzene	ND	10,000
Hexachlorobutadiene	ND	10,000
1,3-Butadiene	ND	50,000
Isopropanol	200,000	50,000
n-Hexane	ND	50,000
Ethyl Acetate	57,000	50,000
Tetrahydrofuran	560,000	50,000
Cyclohexane	ND	50,000
Heptane	ND	50,000
1,4-Dioxane	ND	50,000

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ 5/31/26 Date _____
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/12/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK			
Client Sample I.D.:	--			
Date/Time Sampled:	--			
Date/Time Analyzed:	5/12/26 17:25			
QC Batch No.:	260512MS2A1			
Analyst Initials:	VM			
Dilution Factor:	0.20			

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	0.20
Chloromethane	ND	0.20
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20
Vinyl Chloride	ND	0.20
Bromomethane	ND	0.20
Chloroethane	ND	0.20
Trichlorofluoromethane (11)	ND	0.20
1,1-Dichloroethene	ND	0.20
Carbon Disulfide	ND	0.20
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20
Acetone	ND	0.20
Methylene Chloride	ND	0.20
t-1,2-Dichloroethene	ND	0.20
1,1-Dichloroethane	ND	0.20
Vinyl Acetate	ND	0.20
c-1,2-Dichloroethene	ND	0.20
2-Butanone	ND	0.40
t-Butyl Methyl Ether (MTBE)	ND	0.20
Chloroform	ND	0.20
1,1,1-Trichloroethane	ND	0.20
Carbon Tetrachloride	ND	0.20
Benzene	ND	0.20
1,2-Dichloroethane	ND	0.20
Trichloroethene	ND	0.20
1,2-Dichloropropane	ND	0.20
Bromodichloromethane	ND	0.20
c-1,3-Dichloropropene	ND	0.20
4-Methyl-2-Pentanone	ND	0.20
Toluene	ND	0.20
t-1,3-Dichloropropene	ND	0.20
1,1,2-Trichloroethane	ND	0.20
Tetrachloroethene	ND	0.20
2-Hexanone	ND	0.20
Dibromochloromethane	ND	0.20

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/12/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK
Client Sample I.D.:	--
Date/Time Sampled:	--
Date/Time Analyzed:	5/12/26 17:25
QC Batch No.:	260512MS2A1
Analyst Initials:	VM
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	0.20
Chlorobenzene	ND	0.20
Ethylbenzene	ND	0.20
p,&m-Xylene	ND	0.20
o-Xylene	ND	0.20
Styrene	ND	0.20
Bromoform	ND	0.20
1,1,2,2-Tetrachloroethane	ND	0.20
Benzyl Chloride	ND	0.20
4-Ethyl Toluene	ND	0.20
1,3,5-Trimethylbenzene	ND	0.20
1,2,4-Trimethylbenzene	ND	0.20
1,3-Dichlorobenzene	ND	0.20
1,4-Dichlorobenzene	ND	0.20
1,2-Dichlorobenzene	ND	0.20
1,2,4-Trichlorobenzene	ND	0.20
Hexachlorobutadiene	ND	0.20
1,3-Butadiene	ND	1.0
Isopropanol	ND	1.0
n-Hexane	ND	1.0
Ethyl Acetate	ND	1.0
Tetrahydrofuran	ND	1.0
Cyclohexane	ND	1.0
Heptane	ND	1.0
1,4-Dioxane	ND	1.0

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 5/12/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 260512MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	5/12/26 17:25			5/12/26 12:58		5/12/26 13:37					
Analyst Initials:	VM/GD			VM/GD		VM/GD					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	**Result ppbv**	**RL ppbv**	**AMT. ppbv**	**Result ppbv**	**% Rec.**	**Result ppbv**	**% Rec.**	**RPD**	**Low %Rec**	**High %Rec**	**Max. RPD**
1,1-Dichloroethene	ND	0.20	10	11.8	118	11.3	113	4.0	70	130	30
Methylene Chloride	ND	0.20	10	11.5	115	11.2	112	2.5	70	130	30
Trichloroethene	ND	0.20	10	11.1	111	11.1	111	0.4	70	130	30
Toluene	ND	0.20	10	11.3	113	11.2	112	0.8	70	130	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	10.5	105	10.6	106	0.9	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date: 5/13/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/12/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T051203-01		T051203-02		T051203-03		T051203-04	
Client Sample I.D.:	CV-2353		H-2165W		H-2273W		CV-2314	
Date/Time Sampled:	5/12/26 7:35		5/12/26 7:45		5/12/26 7:50		5/12/26 8:05	
Date/Time Analyzed:	5/12/26 13:58		5/12/26 14:12		5/12/26 14:27		5/12/26 14:41	
QC Batch No.:	260512GC8A1		260512GC8A1		260512GC8A1		260512GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	760	10	720	10	76	10	3,400	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/12/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T051203-05		T051203-06		T051203-07		T051203-08	
Client Sample I.D.:	CV-2305		CV-24064		CV-24063		CV-2303	
Date/Time Sampled:	5/12/26 8:10		5/12/26 8:15		5/12/26 8:20		5/12/26 8:30	
Date/Time Analyzed:	5/12/26 14:56		5/12/26 15:10		5/12/26 15:25		5/12/26 15:39	
QC Batch No.:	260512GC8A1		260512GC8A1		260512GC8A1		260512GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	1,700	10	2,000	10	2,400	10	2,000	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/12/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T051203-09		T051203-10					
Client Sample I.D.:	CV-24017		CV-24007					
Date/Time Sampled:	5/12/26 8:35		5/12/26 8:40					
Date/Time Analyzed:	5/12/26 15:54		5/12/26 16:08					
QC Batch No.:	260512GC8A1		260512GC8A1					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv				
Carbon Monoxide	2,100	10	1,800	10				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-20-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260512GC8A1
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	5/12/26 13:43			5/12/26 12:59		5/12/26 13:14					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,060	105	1,060	105	0.1	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/12/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T051203-01			T051203-02			T051203-03			T051203-04		
Client Sample I.D.:	CV-2353			H-2165W			H-2273W			CV-2314		
Date/Time Sampled:	5/12/26 7:35			5/12/26 7:45			5/12/26 7:50			5/12/26 8:05		
Date/Time Analyzed:	5/12/26 13:58			5/12/26 14:12			5/12/26 14:27			5/12/26 14:41		
QC Batch No.:	260512GC8A1			260512GC8A1			260512GC8A1			260512GC8A1		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	21	1.0	0.059	4.8	1.0	0.059	0.59 J	1.0	0.059	14	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/12/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T051203-05			T051203-06			T051203-07			T051203-08		
Client Sample I.D.:	CV-2305			CV-24064			CV-24063			CV-2303		
Date/Time Sampled:	5/12/26 8:10			5/12/26 8:15			5/12/26 8:20			5/12/26 8:30		
Date/Time Analyzed:	5/12/26 14:56			5/12/26 15:10			5/12/26 15:25			5/12/26 15:39		
QC Batch No.:	260512GC8A1			260512GC8A1			260512GC8A1			260512GC8A1		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	8.2	1.0	0.059	13	1.0	0.059	12	1.0	0.059	19	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____
Mark Johnson
Operations Manager

Date 5-20-26

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/12/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T051203-09			T051203-10								
Client Sample I.D.:	CV-24017			CV-24007								
Date/Time Sampled:	5/12/26 8:35			5/12/26 8:40								
Date/Time Analyzed:	5/12/26 15:54			5/12/26 16:08								
QC Batch No.:	260512GC8A1			260512GC8A1								
Analyst Initials:	KD			KD								
Dilution Factor:	1.0			1.0								
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v						
Hydrogen	19	1.0	0.059	17	1.0	0.059						

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____
Mark Johnson
Operations Manager

Date 5-20-26

The cover letter is an integral part of this analytical report

QC Batch No: 260512GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	5/12/26 13:43				5/12/26 12:59		5/12/26 13:14					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	3.75	75	3.79	76	1.1	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/12/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T051203-01		T051203-02		T051203-03		T051203-04	
Client Sample I.D.:	CV-2353		H-2165W		H-2273W		CV-2314	
Date/Time Sampled:	5/12/26 7:35		5/12/26 7:45		5/12/26 7:50		5/12/26 8:05	
Date/Time Analyzed:	5/12/26 13:58		5/12/26 14:12		5/12/26 14:27		5/12/26 14:41	
QC Batch No.:	260512GC8A1		260512GC8A1		260512GC8A1		260512GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	67	0.010	79	0.010	42	0.010	80	0.010
Oxygen/Argon	1.4	0.50	ND	0.50	1.4	0.50	0.62	0.50
Nitrogen	5.2	1.0	1.8	1.0	38	1.0	3.0	1.0
Methane	2.3	0.0010	12	0.0010	17	0.0010	0.92	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/12/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T051203-05		T051203-06		T051203-07		T051203-08	
Client Sample I.D.:	CV-2305		CV-24064		CV-24063		CV-2303	
Date/Time Sampled:	5/12/26 8:10		5/12/26 8:15		5/12/26 8:20		5/12/26 8:30	
Date/Time Analyzed:	5/12/26 14:56		5/12/26 15:10		5/12/26 15:25		5/12/26 15:39	
QC Batch No.:	260512GC8A1		260512GC8A1		260512GC8A1		260512GC8A1	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	72	0.010	79	0.010	79	0.010	69	0.010
Oxygen/Argon	0.51	0.50	0.78	0.50	0.93	0.50	1.8	0.50
Nitrogen	1.9	1.0	2.8	1.0	3.3	1.0	6.7	1.0
Methane	16	0.0010	2.2	0.0010	2.8	0.0010	1.3	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-20-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/12/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T051203-09		T051203-10					
Client Sample I.D.:	CV-24017		CV-24007					
Date/Time Sampled:	5/12/26 8:35		5/12/26 8:40					
Date/Time Analyzed:	5/12/26 15:54		5/12/26 16:08					
QC Batch No.:	260512GC8A1		260512GC8A1					
Analyst Initials:	KD		KD					
Dilution Factor:	1.0		1.0					
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**				
Carbon Dioxide	72	0.010	75	0.010				
Oxygen/Argon	0.92	0.50	ND	0.50				
Nitrogen	3.3	1.0	1.3	1.0				
Methane	1.9	0.0010	5.0	0.0010				

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ Date 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260512GC8A1
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	5/12/26 13:43			5/12/26 12:59		5/12/26 13:14					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	8.98	90	8.98	90	0.1	70	130	30
Oxygen/Argon	ND	0.50	15	15.2	101	15.2	101	0.2	70	130	30
Nitrogen	ND	1.0	70	72.4	104	72.3	104	0.1	70	130	30
Methane	ND	0.0010	0.10	0.100	99	0.1000	99	0.1	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LA Cert #04140
EPA Methods TO3, TO14A, TO15, 25C/3C, ASTM D1946, RSK-175
TX Cert T104704450-14-6
EPA Methods TO14A, TO15
ALASKA CS-LAP 24-002
EPA Methods TO14A, TO15

June 1, 2026

SCS Field Services
ATTN: Cornelius Fong
3900 Kilroy Airport Way, Suite 100
Long Beach, CA 90806

LABORATORY TEST RESULTS

Project Reference: Chiquita Canyon Landfill
Project Number: 07224200.24 Task 1
Lab Number: T051302-01/11

Enclosed are the results for sample(s) received 5/13/26 by SGS North America, Inc. Samples were received intact. Analyses were performed according to specifications on the chain of custody provided with the sample(s).

Report Narrative:

- Modifications to EPA TO-15 – samples were collected in Mylar bags.
- Unless otherwise noted in the report, sample analyses were performed within method performance criteria and meet all requirements of the TNI Standards.
- The enclosed results relate only to the sample(s).

SGS appreciates the opportunity to provide testing services to your company. If you have any questions regarding these results, please call me at (626) 964-4032.

Sincerely,

Mark Johnson
Operations Manager
Mark.Johnson2@sgs.com

Note: The cover letter is an integral part of this analytical report.

AirTECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME: Standard ■ 48 hours ☐ | Same Day ☐ 72 hours ☐ | 24 hours ☐ 96 hours ☐ | Other:

DELIVERABLES: EDD ■ | EDF ☐ | Level 3 ☐ | Level 4 ☐

PAGE: 1 OF

Condition upon receipt: Sealed Yes ☐ No ☐ | Intact Yes ☐ No ☐ | Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:

Bill to: [illegible]@scsengineers.com

3900 Kilroy Airport Way, Suite 300
Long Beach, CA 90806-6816

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	ANALYSIS REQUEST: CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T051302-01	CV-2333	05/13/26	7:40M	1L	Gas	N	X	X	X			
-02	CV-2334	05/13/26	7:45AM	1L	Gas	N	X	X	X			
-03	CV-24128	05/13/26	7:50AM	1L	Gas	N	X	X	X			
-04	CV-24125	05/13/26	7:55AM	1L	Gas	N	X	X	X			
-05	CV-24134	05/13/26	8:00AM	1L	Gas	N	X					
-06	CV-24126	05/13/26	8:05AM	1L	Gas	N	X					
-07	CV-24049	05/13/26	8:10AM	1L	Gas	N	X	X	X			
-08	CV-24055	05/13/26	8:15AM	1L	Gas	N	X	X	X			
-09	CV-24100	05/13/26	8:25AM	1L	Gas	N	X	X	X			
-10	CV-24069	05/13/26	8:20AM	1L	Gas	N	X	X	X			

AUTHORIZATION TO PERFORM WORK	COMPANY SCS	5-13-26	DATE/TIME 9:11A
SAMPLED BY ERIK NAVARRO	COMPANY SCS	5-13-26	DATE/TIME 9:11A
RELINQUISHED BY ERIK NAVARRO	DATE/TIME 5-13-26 9:11A	RECEIVED BY [signature]	DATE/TIME 5/13/26 9:19
RELINQUISHED BY [signature]	DATE/TIME 5/13/26 11:34	RECEIVED BY [signature]	DATE/TIME 5/13/26 11:34
RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

Air TECHNOLOGY Laboratories, Inc.
18501 E. Gale Ave., Suite 130
City of Industry, CA 91748
Ph: 626-964-4032
Fx: 626-964-5832

CHAIN OF CUSTODY RECORD

TURNAROUND TIME: Standard ■ 48 hours ☐ | Same Day ☐ 72 hours ☐ | 24 hours ☐ 96 hours ☐ | Other:

DELIVERABLES: EDD ■ | EDF ☐ | Level 3 ☐ | Level 4 ☐

PAGE: 2 **OF**

Condition upon receipt: Sealed Yes ☐ No ☐ | Intact Yes ☐ No ☐ | Chilled _____ deg C

Project No.:	07224200.24 Task 1
Project Name:	Chiquita Canyon Landfill
Report To:	Cornelius Fong
Company:	SCS Engineers
Street:	3900 Kilroy Airport Way, Suite 300
City/State/Zip:	Long Beach, CA 90806-6816
Phone& Fax:	562-743-7895
e-mail:	cfong@scsengineers.com

BILLING

P.O. No.:

Bill to: [illegible]SAccountspayable@scsengineers.com
3900 Kilroy Airport Way, Suite 300
Long Beach, CA 90806-6816

LAB USE ONLY	SAMPLE IDENTIFICATION	SAMPLE DATE	SAMPLE TIME	CONTAINER QTY/TYPE	MATRIX	PRESERVATION	ANALYSIS REQUEST: CH4, CO2, O2, N2 ASTM D1946	Carbon Monoxide EPA ALT-144	Hydrogen ASTM D1946	VOCs EPA TO-15		
T051302-11	CV-2312	05/13/26	8:30AM	2L ~~1L~~	Gas	N	X	X	X	X		
				1L	Gas	N						
				1L	Gas	N						
				1L	Gas	N						
				1L	Gas	N						
				1L	Gas	N						
				1L	Gas	N						
				1L	Gas	N						
				1L	Gas	N						
				1L	Gas	N						

AUTHORIZATION TO PERFORM WORK	COMPANY SCS	5-13-26	DATE/TIME 9:11
SAMPLED BY ERIK NAVARRO	COMPANY SCS	5-13-26	DATE/TIME 9:11
RELINQUISHED BY ERIK NAVARRO	DATE/TIME 5-13-26 9:11	RECEIVED BY [signature] 5/13/26	DATE/TIME 9:19 AM
RELINQUISHED BY [signature]	DATE/TIME 5/13/26 11:34	RECEIVED BY [signature] 5/13/26	DATE/TIME 11:34
RELINQUISHED BY	DATE/TIME	RECEIVED BY	DATE/TIME

METHOD OF TRANSPORT (circle one): Walk-In FedEx UPS **Courier** ATLI Other_____

COMMENTS
Report full list of TO-15 compounds
Raw landfill gas samples
FLAMMABLE

DISTRIBUTION: White & Yellow - Lab Copies / Pink - Customer Copy

Preservation: **H**=HCl **N**=None / Container: **B**=Bag **C**=Can **V**=VOA **O**=Other *Rev. 03 - 5/7/09*

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/13/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T051302-11
Client Sample I.D.:	CV-2312
Date/Time Sampled:	5/13/26 8:30
Date/Time Analyzed:	5/13/26 20:16
QC Batch No.:	260513MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	1,000

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	1,000
Chloromethane	ND	1,000
1,2-Cl-1,1,2,2-F ethane (114)	ND	1,000
Vinyl Chloride	ND	1,000
Bromomethane	ND	1,000
Chloroethane	ND	5,000
Trichlorofluoromethane (11)	ND	1,000
1,1-Dichloroethene	ND	1,000
Carbon Disulfide	ND	1,000
1,1,2-Cl 1,2,2-F ethane (113)	ND	1,000
Acetone	75,000	5,000
Methylene Chloride	ND	1,000
t-1,2-Dichloroethene	ND	1,000
1,1-Dichloroethane	ND	1,000
Vinyl Acetate	ND	1,000
c-1,2-Dichloroethene	ND	1,000
2-Butanone	62,000	5,000
t-Butyl Methyl Ether (MTBE)	ND	1,000
Chloroform	ND	1,000
1,1,1-Trichloroethane	ND	1,000
Carbon Tetrachloride	ND	1,000
Benzene	48,000	1,000
1,2-Dichloroethane	ND	1,000
Trichloroethene	ND	1,000
1,2-Dichloropropane	ND	1,000
Bromodichloromethane	ND	1,000
c-1,3-Dichloropropene	ND	1,000
4-Methyl-2-Pentanone	1,500	1,000
Toluene	2,100	1,000
t-1,3-Dichloropropene	ND	2,000
1,1,2-Trichloroethane	ND	1,000
Tetrachloroethene	ND	1,000
2-Hexanone	ND	1,000
Dibromochloromethane	ND	1,000

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/13/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	T051302-11
Client Sample I.D.:	CV-2312
Date/Time Sampled:	5/13/26 8:30
Date/Time Analyzed:	5/13/26 20:16
QC Batch No.:	260513MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	1,000

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	1,000
Chlorobenzene	ND	1,000
Ethylbenzene	ND	1,000
p,&m-Xylene	ND	2,000
o-Xylene	ND	1,000
Styrene	ND	1,000
Bromoform	ND	1,000
1,1,2,2-Tetrachloroethane	ND	1,000
Benzyl Chloride	ND	1,000
4-Ethyl Toluene	ND	1,000
1,3,5-Trimethylbenzene	ND	1,000
1,2,4-Trimethylbenzene	ND	1,000
1,3-Dichlorobenzene	ND	1,000
1,4-Dichlorobenzene	ND	1,000
1,2-Dichlorobenzene	ND	1,000
1,2,4-Trichlorobenzene	ND	1,000
Hexachlorobutadiene	ND	1,000
1,3-Butadiene	ND	5,000
Isopropanol	14,000	5,000
n-Hexane	ND	5,000
Ethyl Acetate	6,200	5,000
Tetrahydrofuran	53,000	5,000
Cyclohexane	ND	5,000
Heptane	ND	5,000
1,4-Dioxane	ND	5,000

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 6/1/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/13/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK
Client Sample I.D.:	--
Date/Time Sampled:	--
Date/Time Analyzed:	5/13/26 6:48
QC Batch No.:	260513MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
Dichlorodifluoromethane (12)	ND	0.20
Chloromethane	ND	0.20
1,2-Cl-1,1,2,2-F ethane (114)	ND	0.20
Vinyl Chloride	ND	0.20
Bromomethane	ND	0.20
Chloroethane	ND	1.0
Trichlorofluoromethane (11)	ND	0.20
1,1-Dichloroethene	ND	0.20
Carbon Disulfide	ND	0.20
1,1,2-Cl 1,2,2-F ethane (113)	ND	0.20
Acetone	ND	1.0
Methylene Chloride	ND	0.20
t-1,2-Dichloroethene	ND	0.20
1,1-Dichloroethane	ND	0.20
Vinyl Acetate	ND	0.20
c-1,2-Dichloroethene	ND	0.20
2-Butanone	ND	1.0
t-Butyl Methyl Ether (MTBE)	ND	0.20
Chloroform	ND	0.20
1,1,1-Trichloroethane	ND	0.20
Carbon Tetrachloride	ND	0.20
Benzene	ND	0.20
1,2-Dichloroethane	ND	0.20
Trichloroethene	ND	0.20
1,2-Dichloropropane	ND	0.20
Bromodichloromethane	ND	0.20
c-1,3-Dichloropropene	ND	0.20
4-Methyl-2-Pentanone	ND	0.20
Toluene	ND	0.20
t-1,3-Dichloropropene	ND	0.40
1,1,2-Trichloroethane	ND	0.20
Tetrachloroethene	ND	0.20
2-Hexanone	ND	0.20
Dibromochloromethane	ND	0.20

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/13/26
Matrix: Air
Reporting Units: ppbv

EPA Method TO-15

Lab No.:	METHOD BLANK
Client Sample I.D.:	--
Date/Time Sampled:	--
Date/Time Analyzed:	5/13/26 6:48
QC Batch No.:	260513MS2A1
Analyst Initials:	VM/GD
Dilution Factor:	0.20

ANALYTE	Result ppbv	RL ppbv
1,2-Dibromoethane	ND	0.20
Chlorobenzene	ND	0.20
Ethylbenzene	ND	0.20
p,&m-Xylene	ND	0.40
o-Xylene	ND	0.20
Styrene	ND	0.20
Bromoform	ND	0.20
1,1,2,2-Tetrachloroethane	ND	0.20
Benzyl Chloride	ND	0.20
4-Ethyl Toluene	ND	0.20
1,3,5-Trimethylbenzene	ND	0.20
1,2,4-Trimethylbenzene	ND	0.20
1,3-Dichlorobenzene	ND	0.20
1,4-Dichlorobenzene	ND	0.20
1,2-Dichlorobenzene	ND	0.20
1,2,4-Trichlorobenzene	ND	0.20
Hexachlorobutadiene	ND	0.20
1,3-Butadiene	ND	1.0
Isopropanol	ND	1.0
n-Hexane	ND	1.0
Ethyl Acetate	ND	1.0
Tetrahydrofuran	ND	1.0
Cyclohexane	ND	1.0
Heptane	ND	1.0
1,4-Dioxane	ND	1.0

RL = Reporting Limit
ND = Not Detected (below RL)

Reviewed/Approved By: _____ Date 6/1/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

LCS/LCSD Recovery and RPD Summary Report

QC Batch #: 260513MS2A1

Matrix: Air

Reporting Units: ppbv

EPA Method TO-15
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date/Time Analyzed:	5/13/26 6:48			5/13/26 5:32		5/13/26 6:10					
Analyst Initials:	VM/GD			VM/GD		VM/GD					
Dilution Factor:	0.20			1.0		1.0					
ANALYTE	Result ppbv	RL ppbv	AMT. ppbv	Result ppbv	% Rec.	Result ppbv	% Rec.	RPD	Low %Rec	High %Rec	Max. RPD
1,1-Dichloroethene	ND	0.20	10	**10.9**	109	**10.9**	109	0.3	**70**	**130**	30
Methylene Chloride	ND	0.20	10	**10.7**	107	**11.0**	110	3.4	**70**	**130**	30
Trichloroethene	ND	0.20	10	**10.8**	108	**10.5**	105	2.6	**70**	**130**	30
Toluene	ND	0.20	10	**10.6**	106	**10.5**	105	0.6	**70**	**130**	30
1,1,2,2-Tetrachloroethane	ND	0.20	10	**9.68**	97	**9.83**	98	1.6	**70**	**130**	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date:** 6/1/26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/13/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T051302-01		T051302-02		T051302-03		T051302-04	
Client Sample I.D.:	CV-2333		CV-2334		CV-24128		CV-24125	
Date/Time Sampled:	5/13/26 7:40		5/13/26 7:45		5/13/26 7:50		5/13/26 7:55	
Date/Time Analyzed:	5/14/26 5:41		5/14/26 5:55		5/14/26 6:10		5/14/26 6:24	
QC Batch No.:	260513GC8A2		260513GC8A2		260513GC8A2		260513GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	3,600	10	660	10	210	10	30	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-20-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/13/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	T051302-07		T051302-08		T051302-09		T051302-10	
Client Sample I.D.:	CV-24049		CV-24055		CV-24100		CV-24069	
Date/Time Sampled:	5/13/26 8:10		5/13/26 8:15		5/13/26 8:25		5/13/26 8:20	
Date/Time Analyzed:	5/14/26 7:08		5/14/26 7:22		5/14/26 7:37		5/14/26 7:51	
QC Batch No.:	260513GC8A2		260513GC8A2		260513GC8A2		260513GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv	Result ppmv	RL ppmv
Carbon Monoxide	2,800	10	930	10	83	10	470	10

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/13/26
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)

Lab No.:	**T051302-11**							
Client Sample I.D.:	**CV-2312**							
Date/Time Sampled:	**5/13/26 8:30**							
Date/Time Analyzed:	**5/14/26 8:06**							
QC Batch No.:	**260513GC8A2**							
Analyst Initials:	**KD**							
Dilution Factor:	**1.0**							
ANALYTE	**Result ppmv**	**RL ppmv**						
Carbon Monoxide	1,800	10						

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-20-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260513GC8A2
Matrix: Air
Reporting Units: ppmv

EPA ALT-144 (CO by FID)
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	5/14/26 2:08			5/14/26 3:21		5/14/26 3:35					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result ppmv	RL ppmv	SPIKE AMT. ppmv	Result ppmv	% Rec.	Result ppmv	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Monoxide	ND	10	1,010	1,290	127	1,260	125	1.9	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-20-26

Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/13/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T051302-01			T051302-02			T051302-03			T051302-04		
Client Sample I.D.:	CV-2333			CV-2334			CV-24128			CV-24125		
Date/Time Sampled:	5/13/26 7:40			5/13/26 7:45			5/13/26 7:50			5/13/26 7:55		
Date/Time Analyzed:	5/14/26 5:41			5/14/26 5:55			5/14/26 6:10			5/14/26 6:24		
QC Batch No.:	260513GC8A2			260513GC8A2			260513GC8A2			260513GC8A2		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	16	1.0	0.059	1.1	1.0	0.059	1.1	1.0	0.059	0.13 J	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/13/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T051302-07			T051302-08			T051302-09			T051302-10		
Client Sample I.D.:	CV-24049			CV-24055			CV-24100			CV-24069		
Date/Time Sampled:	5/13/26 8:10			5/13/26 8:15			5/13/26 8:25			5/13/26 8:20		
Date/Time Analyzed:	5/14/26 7:08			5/14/26 7:22			5/14/26 7:37			5/14/26 7:51		
QC Batch No.:	260513GC8A2			260513GC8A2			260513GC8A2			260513GC8A2		
Analyst Initials:	KD			KD			KD			KD		
Dilution Factor:	1.0			1.0			1.0			1.0		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	16	1.0	0.059	5.1	1.0	0.059	0.88 J	1.0	0.059	4.0	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/13/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T051302-11		
Client Sample I.D.:	CV-2312		
Date/Time Sampled:	5/13/26 8:30		
Date/Time Analyzed:	5/14/26 8:06		
QC Batch No.:	260513GC8A2		
Analyst Initials:	KD		
Dilution Factor:	1.0		

ANALYTE	Result % v/v	RL % v/v	MDL % v/v
Hydrogen	9.0	1.0	0.059

Results normalized including non-methane hydrocarbons

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ Date 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260513GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK				LCS		LCSD					
Date Analyzed:	5/14/26 2:08				5/14/26 3:21		5/14/26 3:35					
Analyst Initials:	KD				KD		KD					
Dilution Factor:	1.0				1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	MDL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Hydrogen	ND	1.0	0.059	5.0	5.27	106	5.30	107	0.6	70	130	30

MDL = Method Detection Limit
ND= Not Detected (below MDL)
RL = Reporting Limit
J = Trace amount. Analyte concentration between RL and MDL.

Reviewed/Approved By: _____ **Date** 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/13/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T051302-01		T051302-02		T051302-03		T051302-04	
Client Sample I.D.:	CV-2333		CV-2334		CV-24128		CV-24125	
Date/Time Sampled:	5/13/26 7:40		5/13/26 7:45		5/13/26 7:50		5/13/26 7:55	
Date/Time Analyzed:	5/14/26 5:41		5/14/26 5:55		5/14/26 6:10		5/14/26 6:24	
QC Batch No.:	260513GC8A2		260513GC8A2		260513GC8A2		260513GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v	Result % v/v	RL % v/v
Carbon Dioxide	66	0.010	74	0.010	40	0.010	55	0.010
Oxygen/Argon	3.3	0.50	2.0	0.50	3.2	0.50	3.2	0.50
Nitrogen	12	1.0	7.6	1.0	25	1.0	13	1.0
Methane	0.49	0.0010	14	0.0010	31	0.0010	29	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/13/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T051302-05		T051302-06		T051302-07		T051302-08	
Client Sample I.D.:	CV-24134		CV-24126		CV-24049		CV-24055	
Date/Time Sampled:	5/13/26 8:00		5/13/26 8:05		5/13/26 8:10		5/13/26 8:15	
Date/Time Analyzed:	5/14/26 6:39		5/14/26 6:53		5/14/26 7:08		5/14/26 7:22	
QC Batch No.:	260513GC8A2		260513GC8A2		260513GC8A2		260513GC8A2	
Analyst Initials:	KD		KD		KD		KD	
Dilution Factor:	1.0		1.0		1.0		1.0	
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**
Carbon Dioxide	**68**	0.010	**74**	0.010	**74**	0.010	**55**	0.010
Oxygen/Argon	**0.92**	0.50	**0.77**	0.50	**1.4**	0.50	**3.0**	0.50
Nitrogen	**3.4**	1.0	**2.7**	1.0	**5.3**	1.0	**28**	1.0
Methane	**13**	0.0010	**1.00**	0.0010	**0.89**	0.0010	**7.9**	0.0010

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

Client: SCS Engineers
Attn: Cornelius Fong
Project Name: Chiquita Canyon Landfill
Project No.: 07224200.24 Task 1
Date Received: 05/13/26
Matrix: Air
Reporting Units: % v/v

ASTM D1946

Lab No.:	T051302-09		T051302-10		T051302-11			
Client Sample I.D.:	CV-24100		CV-24069		CV-2312			
Date/Time Sampled:	5/13/26 8:25		5/13/26 8:20		5/13/26 8:30			
Date/Time Analyzed:	5/14/26 7:37		5/14/26 7:51		5/14/26 8:06			
QC Batch No.:	260513GC8A2		260513GC8A2		260513GC8A2			
Analyst Initials:	KD		KD		KD			
Dilution Factor:	1.0		1.0		1.0			
ANALYTE	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**	**Result % v/v**	**RL % v/v**		
Carbon Dioxide	68	0.010	46	0.010	47	0.010		
Oxygen/Argon	1.8	0.50	1.3	0.50	8.9	0.50		
Nitrogen	7.2	1.0	11	1.0	34	1.0		
Methane	22	0.0010	37	0.0010	1.5	0.0010		

Results normalized including non-methane hydrocarbons

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

QC Batch No: 260513GC8A2
Matrix: Air
Reporting Units: % v/v

ASTM D1946
LABORATORY CONTROL SAMPLE SUMMARY

Lab No.:	METHOD BLANK			LCS		LCSD					
Date Analyzed:	5/14/26 2:08			5/14/26 3:21		5/14/26 3:35					
Analyst Initials:	KD			KD		KD					
Dilution Factor:	1.0			1.0		1.0			Limits		
ANALYTE	Result % v/v	RL % v/v	SPIKE AMT. % v/v	Result % v/v	% Rec.	Result % v/v	% Rec.	RPD %	Low %Rec	High %Rec	Max. RPD
Carbon Dioxide	ND	0.010	10	9.89	99	9.89	99	0.0	70	130	30
Oxygen/Argon	ND	0.50	15	14.8	98	14.7	98	0.3	70	130	30
Nitrogen	ND	1.0	70	72.1	103	72.1	103	0.1	70	130	30
Methane	ND	0.0010	0.10	0.109	108	0.108	107	0.2	70	130	30

ND = Not Detected (below RL)
RL = Reporting Limit

Reviewed/Approved By: _____ **Date** 5-20-26
Mark Johnson
Operations Manager

The cover letter is an integral part of this analytical report

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]
A-01	5/15/2026 8:51:04 AM	56.1	40.2	0.1	3.6			1.4	36.0	79.4
A-02	5/11/2026 7:44:04 AM	58.8	38.3	0.2	2.7			1.5	13.5	92.7
A-03	5/11/2026 7:56:41 AM	55.0	41.7	0.0	3.3			1.3	0.0	75.5
A-04	5/11/2026 8:06:12 AM	57.4	40.9	0.0	1.7			1.4	0.0	94.4
A-05	5/11/2026 8:01:26 AM	57.3	40.1	0.2	2.4			1.4	12.0	76.1
B-01	5/11/2026 10:37:28 AM	18.0	20.1	0.0	61.9			0.9	0.0	89.4
B-02R	5/11/2026 10:34:40 AM	34.5	27.0	0.3	38.2			1.3	127.3	100.2
B-03R	5/11/2026 10:04:48 AM	31.2	28.8	0.0	40.0			1.1	0.0	83.7
B-05	5/11/2026 10:25:34 AM	27.2	27.6	0.0	45.2			1.0	0.0	88.7
B-06	5/11/2026 10:19:19 AM	24.1	23.7	0.0	52.2			1.0	0.0	80.0
B-07R	5/11/2026 9:31:57 AM	50.1	35.0	0.0	14.9			1.4	0.0	91.1
B-08	5/11/2026 10:15:29 AM	22.4	22.5	0.0	55.1			1.0	0.0	88.5
B-09	5/11/2026 9:37:05 AM	44.3	32.4	0.0	23.3			1.4	0.0	92.5
B-10	5/11/2026 9:24:54 AM	33.5	30.1	0.0	36.4			1.1	0.0	88.4
B-11	5/29/2026 3:03:30 PM	42.2	34.4	0.0	23.4			1.2	0.0	96.7
B-12	5/11/2026 10:00:30 AM	25.7	27.8	0.1	46.4			0.9	464.0	92.9
B-13	5/11/2026 9:49:42 AM	39.4	30.5	0.0	30.1			1.3	0.0	87.5
B-14	5/29/2026 3:07:12 PM	35.6	31.9	0.0	32.5			1.1	0.0	92.0
C-03	5/11/2026 7:49:46 AM	56.3	41.8	0.0	1.9			1.3	0.0	66.8
C-07	5/1/2026 3:11:09 PM	49.6	36.4	1.6	12.4			1.4	7.8	88.7
C-08	5/8/2026 1:03:42 PM	57.6	38.1	0.0	4.3			1.5	0.0	98.5
C-10	5/11/2026 9:07:51 AM	55.2	38.8	0.2	5.8			1.4	29.0	89.1
C-11	5/11/2026 8:38:28 AM	53.8	37.5	0.0	8.7			1.4	0.0	82.6
C-12	5/29/2026 12:20:26 PM	57.3	38.7	0.0	4.0			1.5	0.0	83.5
C-12	5/11/2026 1:57:43 PM	55.4	41.7	0.0	2.9			1.3	0.0	99.4
C-15	5/11/2026 2:07:31 PM	38.0	27.8	5.9	28.3			1.4	4.8	95.0
C-17B	5/12/2026 10:45:10 AM	55.4	41.5	0.0	3.1			1.3	0.0	109.9
C-18	5/12/2026 1:08:06 PM	55.5	40.4	0.0	4.1			1.4	0.0	103.3
C-19	5/12/2026 12:49:10 PM	55.4	40.4	0.0	4.2			1.4	0.0	99.0
C-20	5/12/2026 12:57:51 PM	55.4	40.6	0.0	4.0			1.4	0.0	98.9
C-23	5/12/2026 11:00:46 AM	48.4	44.0	0.0	7.6			1.1	0.0	128.5
C-24	5/15/2026 9:17:41 AM	42.5	34.3	3.1	20.1			1.2	6.5	103.1
C-25	5/11/2026 2:14:04 PM	50.4	42.5	0.0	7.1			1.2	0.0	127.0

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [ ]
C-26	5/29/2026 12:46:54 PM	52.9	34.7	1.7	10.7			1.5	6.3	103.0
C-26	5/15/2026 9:07:37 AM	47.6	42.6	0.5	9.3			1.1	18.6	78.2
C-27	5/11/2026 2:04:38 PM	56.3	40.5	0.0	3.2			1.4	0.0	96.3
C-28	5/29/2026 12:16:57 PM	56.0	40.6	0.0	3.4			1.4	0.0	98.9
C-28	5/11/2026 8:35:54 AM	56.4	40.7	0.0	2.9			1.4	0.0	100.1
C-29	5/11/2026 8:54:46 AM	42.8	44.4	0.0	12.8			1.0	0.0	107.3
C-30	5/11/2026 8:49:08 AM	52.2	43.0	0.0	4.8			1.2	0.0	126.5
CV-02	5/11/2026 8:21:58 AM	49.6	41.5	0.0	8.9			1.2	0.0	120.2
CV-03	5/11/2026 8:18:37 AM	53.2	40.4	0.0	6.4			1.3	0.0	118.9
CV-04	5/11/2026 8:14:52 AM	52.3	41.0	0.6	6.1			1.3	10.2	108.8
CV-05	5/8/2026 12:41:33 PM	57.0	39.9	0.0	3.1			1.4	0.0	98.8
CV-06	5/12/2026 8:03:49 AM	48.3	49.2	0.0	2.5			1.0	0.0	90.3
CV-108-52	5/19/2026 1:02:47 PM	50.4	48.9	0.0	0.7			1.0	0.0	101.2
CV-108-52	5/18/2026 11:07:16 AM						6600			
CV-108-52	5/6/2026 8:30:00 AM					100				
CV-108-52	5/1/2026 10:29:07 AM	47.7	51.3	0.0	1.0			0.9	0.0	98.6
CV-113	5/26/2026 2:01:29 PM	9.9	88.1	0.0	2.0			0.1	0.0	72.8
CV-113	5/15/2026 9:28:02 AM	9.6	85.1	0.0	5.3			0.1	0.0	65.9
CV-113	5/4/2026 7:50:00 AM						24000			
CV-114	5/26/2026 8:58:28 AM	1.0	78.6	0.0	20.4			0.0	0.0	170.5
CV-114	5/18/2026 9:20:17 AM	14.4	78.4	0.0	7.2			0.2	0.0	164.5
CV-114	5/18/2026 9:20:00 AM					4380				
CV-114	5/18/2026 9:17:57 AM	14.0	75.7	0.0	10.3			0.2	0.0	160.9
CV-114	5/12/2026 9:25:00 AM					1750				
CV-114	5/12/2026 9:22:16 AM	18.6	81.4	0.0	0.0			0.2	0.0	173.1
CV-114	5/5/2026 8:35:00 AM					3350				
CV-114	5/5/2026 8:35:00 AM						161800			
CV-114	5/5/2026 8:32:18 AM	2.2	80.1	0.0	17.7			0.0	0.0	174.3
CV-114	5/4/2026 8:05:00 AM						2800			
CV-1424	5/1/2026 11:22:59 AM	50.7	40.1	0.0	9.2			1.3	0.0	105.2

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-1532A	5/28/2026 8:54:46 AM	6.7	68.0	4.2	21.1			0.1	5.0	66.9
CV-1532A	5/13/2026 1:09:52 PM	8.2	38.6	11.4	41.8			0.2	3.7	81.8
CV-1532A	5/13/2026 1:07:32 PM	11.9	58.0	6.5	23.6			0.2	3.6	81.9
CV-1532A	5/11/2026 8:15:00 AM					580				
CV-1532A	5/11/2026 8:15:00 AM						61000			
CV-1534A-PLR	5/28/2026 1:23:27 PM	1.9	62.9	4.8	30.4			0.0	6.3	183.9
CV-1534A-PLR	5/28/2026 1:20:34 PM	1.7	34.7	10.2	53.4			0.0	5.2	188.7
CV-1534A-PLR	5/20/2026 9:03:59 AM	19.4	77.3	0.0	3.3			0.3	0.0	186.4
CV-1534A-PLR	5/13/2026 9:42:40 AM	12.4	79.0	1.3	7.3			0.2	5.6	180.9
CV-1534A-PLR	5/6/2026 10:03:56 AM	14.6	74.8	1.7	8.9			0.2	5.2	181.2
CV-1534A-PLR	5/6/2026 9:55:00 AM					2250				
CV-1534A-PLR	5/6/2026 9:55:00 AM						123400			
CV-1535	5/19/2026 12:55:31 PM	44.5	49.2	0.0	6.3			0.9	0.0	119.7
CV-1535	5/11/2026 8:25:00 AM					100				
CV-1535	5/11/2026 8:25:00 AM						9800			
CV-1535	5/1/2026 10:31:55 AM	45.2	51.2	0.0	3.6			0.9	0.0	120.4
CV-1601D	5/22/2026 10:03:49 AM	53.3	44.6	0.0	2.1			1.2	0.0	109.2
CV-1601D	5/4/2026 10:02:19 AM	52.5	45.1	0.0	2.4			1.2	0.0	108.7
CV-1601S	5/22/2026 10:00:47 AM	53.0	43.8	0.2	3.0			1.2	15.0	103.0
CV-1601S	5/4/2026 9:59:23 AM	49.8	45.9	0.0	4.3			1.1	0.0	101.2
CV-1604	5/4/2026 11:02:38 AM	51.7	44.6	0.0	3.7			1.2	0.0	125.5
CV-1701D	5/8/2026 1:23:50 PM	9.9	60.8	0.0	29.3			0.2	0.0	105.3
CV-1701D	5/8/2026 1:22:18 PM	9.0	63.1	0.0	27.9			0.1	0.0	101.2
CV-1701D	5/7/2026 11:12:23 AM	7.5	50.4	0.0	42.1			0.1	0.0	90.9
CV-1701S	5/7/2026 11:16:55 AM	24.4	67.2	0.0	8.4			0.4	0.0	137.2
CV-1701S	5/7/2026 11:15:22 AM	25.0	65.9	0.0	9.1			0.4	0.0	138.9
CV-1901	5/19/2026 10:20:41 AM	13.9	74.3	0.0	11.8			0.2	0.0	107.3
CV-1901	5/19/2026 10:18:56 AM	15.8	72.2	0.0	12.0			0.2	0.0	107.3

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-1901	5/12/2026 10:20:03 AM	13.4	78.1	0.0	8.5			0.2	0.0	106.6
CV-1901	5/12/2026 10:17:30 AM	13.8	77.8	0.0	8.4			0.2	0.0	105.7
CV-1902A	5/28/2026 8:49:43 AM	1.8	79.3	0.0	18.9			0.0	0.0	174.2
CV-1902A	5/20/2026 8:10:11 AM	8.0	77.7	0.0	14.3			0.1	0.0	156.7
CV-1902A	5/14/2026 1:48:17 PM	2.1	79.7	0.0	18.2			0.0	0.0	167.2
CV-1902A	5/11/2026 1:48:31 PM	9.5	80.8	0.0	9.7			0.1	0.0	149.5
CV-1902A	5/11/2026 7:55:00 AM					930				
CV-1902A	5/11/2026 7:55:00 AM						190000			
CV-1902A	5/6/2026 9:06:28 AM	10.5	78.0	0.0	11.5			0.1	0.0	160.9
CV-1902A	5/6/2026 9:05:00 AM					1130				
CV-1902A	5/6/2026 9:05:00 AM						161050			
CV-1905	5/6/2026 12:45:38 PM	56.2	42.9	0.0	0.9			1.3	0.0	109.2
CV-1905	5/6/2026 10:44:14 AM	52.8	45.1	0.0	2.1			1.2	0.0	103.4
CV-2001	5/20/2026 9:55:23 AM	11.8	79.2	0.0	9.0			0.1	0.0	103.2
CV-2001	5/12/2026 8:45:06 AM	12.0	76.2	1.0	10.8			0.2	10.8	76.1
CV-2001	5/6/2026 7:50:00 AM					780				
CV-2001	5/6/2026 7:50:00 AM						82000			
CV-2001	5/1/2026 10:12:38 AM	10.4	78.3	2.1	9.2			0.1	4.4	85.8
CV-2002	5/28/2026 10:15:53 AM	9.6	74.7	0.0	15.7			0.1	0.0	183.5
CV-2002	5/28/2026 10:12:21 AM	9.3	74.6	0.0	16.1			0.1	0.0	183.5
CV-2002	5/20/2026 9:42:31 AM	43.3	54.7	2.0	0.0			0.8	0.0	178.6
CV-2002	5/20/2026 9:41:05 AM	42.1	55.6	2.3	0.0			0.8	0.0	177.9
CV-2002	5/13/2026 10:09:19 AM	9.0	64.5	2.4	24.1			0.1	10.0	181.6
CV-2002	5/11/2026 8:10:00 AM					860				
CV-2002	5/11/2026 8:10:00 AM						83000			
CV-2002	5/6/2026 1:05:00 PM					3900				
CV-2002	5/6/2026 1:05:00 PM						137200			
CV-2002	5/6/2026 1:02:03 PM	35.3	64.7	0.0	0.0			0.5	0.0	181.7
CV-2003	5/19/2026 1:11:41 PM	17.2	69.4	0.8	12.6			0.2	15.8	110.7
CV-2003	5/19/2026 1:06:11 PM	21.8	68.9	0.0	9.3			0.3	0.0	120.8

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [ ]
CV-2003	5/1/2026 10:27:07 AM	16.7	73.2	0.2	9.9			0.2	49.5	118.6
CV-2006	5/28/2026 8:42:46 AM	0.9	80.6	0.2	18.3			0.0	91.5	187.3
CV-2006	5/20/2026 8:18:51 AM	8.2	77.1	0.0	14.7			0.1	0.0	187.6
CV-2006	5/14/2026 2:04:55 PM	1.8	84.4	0.0	13.8			0.0	0.0	184.9
CV-2006	5/14/2026 2:03:40 PM	1.3	83.8	0.0	14.9			0.0	0.0	185.2
CV-2006	5/11/2026 1:55:37 PM	20.8	75.0	0.0	4.2			0.3	0.0	188.0
CV-2006	5/6/2026 9:20:00 AM					3010				
CV-2006	5/6/2026 9:20:00 AM						173400			
CV-2006	5/6/2026 9:17:48 AM	11.6	81.7	0.0	6.7			0.1	0.0	187.7
CV-2007	5/20/2026 2:00:34 PM	19.9	75.6	0.0	4.5			0.3	0.0	111.1
CV-2007	5/8/2026 9:48:29 AM	20.5	75.0	0.0	4.5			0.3	0.0	93.2
CV-2007	5/4/2026 8:10:00 AM						59000			
CV-2008	5/11/2026 2:03:03 PM	26.3	71.4	0.0	2.3			0.4	0.0	110.1
CV-2009	5/8/2026 9:02:48 AM	41.0	59.0	0.0	0.0			0.7	0.0	136.0
CV-2009	5/8/2026 9:00:33 AM	41.0	58.4	0.0	0.6			0.7	0.0	135.5
CV-2009A	5/11/2026 1:51:42 PM	38.9	58.1	0.0	3.0			0.7	0.0	129.8
CV-2010	5/4/2026 1:15:27 PM	37.3	48.6	0.0	14.1			0.8	0.0	116.0
CV-2010A	5/21/2026 10:29:08 AM	42.7	46.3	0.0	11.0			0.9	0.0	141.6
CV-2010A	5/14/2026 9:40:00 AM					235.5				
CV-2010A	5/14/2026 9:38:44 AM	31.3	54.8	0.0	13.9			0.6	0.0	74.7
CV-2010A	5/5/2026 1:03:57 PM	33.6	49.8	0.0	16.6			0.7	0.0	146.4
CV-2010A	5/5/2026 1:03:17 PM	34.4	49.2	0.0	16.4			0.7	0.0	146.2
CV-2010A	5/4/2026 1:29:04 PM	30.9	52.7	0.0	16.4			0.6	0.0	148.1
CV-2010A	5/4/2026 1:27:58 PM	30.1	53.0	0.0	16.9			0.6	0.0	148.7
CV-2010A	5/4/2026 1:26:56 PM	28.3	51.1	0.0	20.6			0.6	0.0	146.0
CV-2011	5/11/2026 3:39:24 PM	47.9	51.3	0.0	0.8			0.9	0.0	108.0
CV-2011	5/11/2026 3:38:18 PM	49.0	51.0	0.0	0.0			1.0	0.0	99.3
CV-2011A	5/28/2026 8:38:45 AM	4.6	80.9	0.3	14.2			0.1	47.3	150.3
CV-2011A	5/27/2026 3:15:12 PM	14.4	55.2	0.0	30.4			0.3	0.0	148.1
CV-2011A	5/27/2026 3:14:19 PM	15.2	60.5	0.0	24.3			0.3	0.0	147.5

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [ ]
CV-2011A	5/21/2026 9:16:00 AM	20.0	54.6	0.0	25.4			0.4	0.0	151.5
CV-2011A	5/20/2026 8:33:37 AM	19.9	56.1	0.0	24.0			0.4	0.0	151.7
CV-2011A	5/20/2026 8:30:13 AM	20.0	55.8	0.0	24.2			0.4	0.0	152.0
CV-2011A	5/14/2026 9:40:27 AM	41.6	58.4	0.0	0.0			0.7	0.0	153.6
CV-2011A	5/11/2026 10:58:37 AM	43.5	56.5	0.0	0.0			0.8	0.0	153.7
CV-2011A	5/4/2026 8:20:00 AM					1040				
CV-2011A	5/4/2026 8:20:00 AM						199300			
CV-2011A	5/4/2026 8:19:12 AM	22.3	58.4	0.0	19.3			0.4	0.0	151.1
CV-2012	5/11/2026 3:24:22 PM	40.0	54.3	0.0	5.7			0.7	0.0	136.9
CV-2012	5/11/2026 3:23:03 PM	38.9	54.8	0.0	6.3			0.7	0.0	137.6
CV-2201-PLR	5/19/2026 11:02:27 AM	3.0	80.1	0.0	16.9			0.0	0.0	130.6
CV-2201-PLR	5/19/2026 10:46:55 AM	28.2	71.8	0.0	0.0			0.4	0.0	130.8
CV-2201-PLR	5/13/2026 1:54:50 PM	2.6	77.8	0.0	19.6			0.0	0.0	132.9
CV-2201-PLR	5/13/2026 1:53:35 PM	2.5	78.6	0.1	18.8			0.0	188.0	133.0
CV-2204-PLR	5/26/2026 1:23:17 PM	11.0	82.7	0.0	6.3			0.1	0.0	148.6
CV-2204-PLR	5/18/2026 11:00:00 AM					2500				
CV-2204-PLR	5/18/2026 10:51:06 AM	17.6	76.0	0.0	6.4			0.2	0.0	188.4
CV-2204-PLR	5/12/2026 10:45:00 AM					728				
CV-2204-PLR	5/12/2026 10:44:05 AM	23.4	76.6	0.0	0.0			0.3	0.0	190.1
CV-2204-PLR	5/5/2026 9:48:20 AM	12.3	85.4	0.0	2.3			0.1	0.0	189.9
CV-2204-PLR	5/5/2026 9:45:00 AM					2700				
CV-2204-PLR	5/5/2026 9:45:00 AM						137900			
CV-2205	5/1/2026 2:09:09 PM	34.2	48.9	0.0	16.9			0.7	0.0	120.4
CV-2207	5/11/2026 1:42:35 PM	44.7	51.2	0.1	4.0			0.9	40.0	125.8
CV-2207	5/11/2026 1:19:38 PM	43.2	54.8	0.0	2.0			0.8	0.0	127.3
CV-2208A	5/11/2026 11:49:32 AM	31.7	66.0	0.0	2.3			0.5	0.0	134.0
CV-2208A	5/11/2026 11:47:10 AM	29.9	59.5	0.0	10.6			0.5	0.0	134.8
CV-2301	5/27/2026 10:38:04 AM	13.5	69.3	0.0	17.2			0.2	0.0	158.0
CV-2301	5/27/2026 10:36:57 AM	21.7	65.2	0.1	13.0			0.3	130.0	160.0

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]
CV-2301	5/19/2026 10:16:23 AM	47.8	52.2	0.0	0.0			0.9	0.0	164.0
CV-2301	5/19/2026 10:15:36 AM	48.3	51.4	0.3	0.0			0.9	0.0	165.0
CV-2301	5/19/2026 10:15:00 AM					990				
CV-2301	5/14/2026 11:20:00 AM					1170				
CV-2301	5/14/2026 10:53:50 AM	31.1	62.4	0.0	6.5			0.5	0.0	182.0
CV-2301	5/14/2026 10:52:08 AM	30.7	61.8	0.0	7.5			0.5	0.0	182.0
CV-2301	5/7/2026 7:55:00 AM					2200				
CV-2301	5/7/2026 7:55:00 AM						150000			
CV-2302	5/22/2026 3:57:06 PM	42.2	50.6	0.7	6.5			0.8	9.3	120.2
CV-2302	5/7/2026 8:05:00 AM					320				
CV-2302	5/7/2026 8:05:00 AM						53000			
CV-2302	5/4/2026 9:06:38 AM	42.4	51.8	0.1	5.7			0.8	57.0	121.6
CV-2303	5/27/2026 9:02:45 AM	1.3	77.6	0.0	21.1			0.0	0.0	181.2
CV-2303	5/19/2026 8:40:00 AM					2480				
CV-2303	5/19/2026 8:36:23 AM	14.0	79.4	0.0	6.6			0.2	0.0	187.2
CV-2303	5/13/2026 2:13:55 PM	2.0	75.5	0.0	22.5			0.0	0.0	188.9
CV-2303	5/12/2026 8:30:00 AM					2000				
CV-2303	5/12/2026 8:30:00 AM						190000			
CV-2303	5/5/2026 2:25:00 PM					2170				
CV-2303	5/5/2026 2:25:00 PM						165800			
CV-2303	5/5/2026 2:21:44 PM	14.0	80.9	0.0	5.1			0.2	0.0	189.5
CV-2304	5/19/2026 9:15:00 AM					1650				
CV-2304	5/19/2026 9:14:49 AM	20.7	74.7	0.0	4.6			0.3	0.0	167.0
CV-2304	5/13/2026 3:03:41 PM	7.1	76.4	0.0	16.5			0.1	0.0	163.5
CV-2304	5/13/2026 3:02:59 PM	9.0	74.3	0.0	16.7			0.1	0.0	162.5
CV-2304	5/8/2026 12:51:34 PM	1.1	79.4	0.0	19.5			0.0	0.0	168.1
CV-2304	5/8/2026 12:50:06 PM	1.5	79.5	0.0	19.0			0.0	0.0	165.9
CV-2304	5/6/2026 3:00:04 PM	1.7	79.1	0.0	19.2			0.0	0.0	162.7
CV-2304	5/6/2026 3:00:00 PM					1605				
CV-2304	5/6/2026 3:00:00 PM						180600			

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [ ]
CV-2304	5/6/2026 2:59:41 PM	1.9	69.7	0.0	28.4			0.0	0.0	162.3
CV-2305	5/27/2026 2:24:19 PM	17.7	79.8	0.0	2.5			0.2	0.0	149.7
CV-2305	5/27/2026 2:23:44 PM	16.2	77.8	0.0	6.0			0.2	0.0	149.1
CV-2305	5/19/2026 1:20:00 PM					2420				
CV-2305	5/19/2026 1:19:18 PM	38.8	61.2	0.0	0.0			0.6	0.0	148.9
CV-2305	5/14/2026 10:11:00 AM					2380				
CV-2305	5/14/2026 10:09:35 AM	31.0	69.0	0.0	0.0			0.4	0.0	150.0
CV-2305	5/12/2026 8:10:00 AM					1700				
CV-2305	5/12/2026 8:10:00 AM						82000			
CV-2305	5/4/2026 8:50:00 AM	16.1	73.3	0.0	10.6			0.2	0.0	149.9
CV-2306	5/26/2026 1:28:47 PM	10.3	77.4	0.1	12.2			0.1	122.0	150.4
CV-2306	5/18/2026 11:00:16 AM	24.1	66.6	0.0	9.3			0.4	0.0	133.7
CV-2306	5/18/2026 10:56:22 AM	18.9	69.8	0.0	11.3			0.3	0.0	101.4
CV-2306	5/12/2026 10:50:18 AM	25.0	75.0	0.0	0.0			0.3	0.0	178.8
CV-2306	5/12/2026 10:50:00 AM					381				
CV-2306	5/5/2026 9:52:13 AM	15.8	81.6	0.0	2.6			0.2	0.0	173.6
CV-2306	5/5/2026 9:50:00 AM					1800				
CV-2306	5/5/2026 9:50:00 AM						161900			
CV-2308-PLR	5/19/2026 10:58:26 AM	3.2	81.1	0.0	15.7			0.0	0.0	134.2
CV-2308-PLR	5/19/2026 10:56:56 AM	3.7	77.8	0.0	18.5			0.0	0.0	133.5
CV-2308-PLR	5/13/2026 2:03:12 PM	4.0	78.4	0.0	17.6			0.1	0.0	144.6
CV-2308-PLR	5/13/2026 2:01:38 PM	3.6	77.9	0.1	18.4			0.0	184.0	146.7
CV-2310-PLR	5/27/2026 9:22:17 AM	1.5	77.1	0.0	21.4			0.0	0.0	196.0
CV-2310-PLR	5/19/2026 8:56:41 AM	14.0	74.0	0.0	12.0			0.2	0.0	196.7
CV-2310-PLR	5/19/2026 8:55:00 AM					1920				
CV-2310-PLR	5/13/2026 2:22:47 PM	3.1	75.3	0.0	21.6			0.0	0.0	197.6
CV-2310-PLR	5/6/2026 2:40:00 PM						100700			

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-2310-PLR	5/6/2026 2:30:00 PM					1270				
CV-2310-PLR	5/6/2026 2:26:12 PM	1.9	79.7	0.8	17.6			0.0	22.0	197.3
CV-2310-PLR	5/1/2026 11:45:33 AM	1.7	74.3	0.0	24.0			0.0	0.0	197.2
CV-2310-PLR	5/1/2026 11:44:42 AM	2.0	80.9	0.0	17.1			0.0	0.0	197.1
CV-2311	5/26/2026 2:01:48 PM	22.4	71.6	0.0	6.0			0.3	0.0	163.6
CV-2311	5/18/2026 2:25:36 PM	15.6	71.5	0.0	12.9			0.2	0.0	169.1
CV-2311	5/18/2026 2:25:00 PM					2730				
CV-2311	5/18/2026 2:24:18 PM	25.3	70.4	0.0	4.3			0.4	0.0	167.0
CV-2311	5/12/2026 2:05:46 PM	32.0	66.0	2.0	0.0			0.5	0.0	167.1
CV-2311	5/12/2026 2:03:19 PM	29.0	70.7	0.3	0.0			0.4	0.0	166.1
CV-2311	5/12/2026 2:00:00 PM					915				
CV-2311	5/5/2026 10:25:04 AM	23.3	73.8	0.0	2.9			0.3	0.0	168.2
CV-2311	5/5/2026 10:25:00 AM					1620				
CV-2311	5/5/2026 10:25:00 AM						139700			
CV-2312	5/27/2026 11:01:39 AM	3.5	80.0	0.1	16.4			0.0	164.0	167.9
CV-2312	5/19/2026 10:35:25 AM	16.8	78.0	0.0	5.2			0.2	0.0	168.5
CV-2312	5/19/2026 10:35:00 AM					3070				
CV-2312	5/13/2026 11:08:10 AM	2.5	78.9	0.4	18.2			0.0	45.5	169.2
CV-2312	5/13/2026 9:06:06 AM	7.7	81.8	0.2	10.3			0.1	51.5	168.2
CV-2312	5/13/2026 8:30:00 AM					1800				
CV-2312	5/13/2026 8:30:00 AM						90000			
CV-2312	5/4/2026 10:29:04 AM	1.8	78.3	0.0	19.9			0.0	0.0	167.9
CV-2312	5/4/2026 10:27:12 AM	1.5	62.9	3.1	32.5			0.0	10.5	168.1
CV-2312	5/4/2026 10:15:00 AM					3840				
CV-2312	5/4/2026 10:15:00 AM						120300			
CV-2314	5/27/2026 1:46:16 PM	1.4	85.2	0.0	13.4			0.0	0.0	179.7
CV-2314	5/27/2026 1:45:46 PM	1.3	84.1	0.0	14.6			0.0	0.0	179.8

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-2314	5/19/2026 2:00:00 PM					3840				
CV-2314	5/19/2026 1:53:23 PM	23.9	76.1	0.0	0.0			0.3	0.0	179.3
CV-2314	5/14/2026 1:50:56 PM	0.7	90.4	0.0	8.9			0.0	0.0	178.0
CV-2314	5/14/2026 1:49:32 PM	0.9	90.5	0.1	8.5			0.0	85.0	177.6
CV-2314	5/12/2026 8:05:00 AM					3400				
CV-2314	5/12/2026 8:05:00 AM						140000			
CV-2314	5/11/2026 10:32:15 AM	8.2	88.6	0.0	3.2			0.1	0.0	180.2
CV-2314	5/4/2026 9:40:25 AM	7.3	77.6	0.0	15.1			0.1	0.0	177.9
CV-2314	5/4/2026 9:40:00 AM					4010				
CV-2314	5/4/2026 9:40:00 AM						110000			
CV-2315	5/26/2026 10:35:23 AM	10.0	79.9	0.1	10.0			0.1	100.0	182.5
CV-2315	5/19/2026 1:35:00 PM					4320				
CV-2315	5/19/2026 1:31:37 PM	22.0	75.5	0.0	2.5			0.3	0.0	184.8
CV-2315	5/13/2026 1:43:34 PM	5.2	78.4	0.0	16.4			0.1	0.0	177.6
CV-2315	5/13/2026 1:42:47 PM	5.1	79.0	0.1	15.8			0.1	158.0	177.4
CV-2315	5/11/2026 8:41:37 AM	2.8	85.7	0.0	11.5			0.0	0.0	158.8
CV-2315	5/7/2026 8:30:00 AM					3900				
CV-2315	5/7/2026 8:30:00 AM						140000			
CV-2315	5/6/2026 3:30:00 PM					2530				
CV-2315	5/6/2026 3:30:00 PM						83300			
CV-2315	5/6/2026 3:27:40 PM	4.6	80.6	0.6	14.2			0.1	23.7	183.9
CV-2315	5/6/2026 3:25:58 PM	3.1	92.1	0.0	4.8			0.0	0.0	183.6
CV-2316	5/11/2026 1:59:13 PM	22.5	66.1	0.0	11.4			0.3	0.0	142.0
CV-2316	5/11/2026 1:57:51 PM	24.2	65.7	0.0	10.1			0.4	0.0	141.7
CV-2319	5/12/2026 8:28:11 AM	11.2	78.5	0.0	10.3			0.1	0.0	142.0
CV-2319	5/12/2026 8:26:00 AM	12.1	78.5	0.0	9.4			0.2	0.0	142.0
CV-2321	5/27/2026 2:51:44 PM	25.2	74.6	0.2	0.0			0.3	0.0	145.7
CV-2321	5/27/2026 2:50:12 PM	25.6	73.7	0.3	0.4			0.3	1.3	145.8
CV-2321	5/19/2026 1:00:00 PM					3560				
CV-2321	5/19/2026 12:59:11 PM	26.1	73.9	0.0	0.0			0.4	0.0	149.0

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-2321	5/19/2026 12:56:22 PM	21.2	78.8	0.0	0.0			0.3	0.0	147.4
CV-2321	5/11/2026 9:19:14 AM	13.5	81.6	0.0	4.9			0.2	0.0	146.6
CV-2321	5/11/2026 9:16:26 AM	35.5	64.2	0.3	0.0			0.6	0.0	144.3
CV-2321	5/7/2026 9:50:36 AM	12.2	82.2	0.0	5.6			0.1	0.0	149.3
CV-2321	5/7/2026 9:50:00 AM					2785				
CV-2321	5/7/2026 9:50:00 AM						76800			
CV-2321	5/7/2026 9:49:06 AM	6.3	84.1	0.0	9.6			0.1	0.0	148.0
CV-2321	5/1/2026 10:23:30 AM	4.9	87.2	0.0	7.9			0.1	0.0	147.8
CV-2321	5/1/2026 10:20:34 AM	5.2	84.1	0.0	10.7			0.1	0.0	147.7
CV-2322	5/26/2026 9:22:23 AM	2.2	69.4	3.6	24.8			0.0	6.9	60.6
CV-2322	5/4/2026 1:40:46 PM	2.4	77.2	0.0	20.4			0.0	0.0	137.1
CV-2324	5/6/2026 2:05:45 PM	50.1	46.6	0.0	3.3			1.1	0.0	117.4
CV-2324	5/1/2026 11:00:44 AM	43.1	41.8	0.0	15.1			1.0	0.0	123.0
CV-2326	5/19/2026 10:26:12 AM	1.5	83.6	0.0	14.9			0.0	0.0	134.2
CV-2326	5/19/2026 10:25:24 AM	1.6	81.3	0.0	17.1			0.0	0.0	134.0
CV-2326	5/1/2026 11:33:29 AM	7.1	75.9	1.0	16.0			0.1	16.0	124.2
CV-2327	5/28/2026 1:44:39 PM	1.9	83.4	0.0	14.7			0.0	0.0	185.5
CV-2327	5/20/2026 2:15:58 PM	2.1	81.9	0.0	16.0			0.0	0.0	172.7
CV-2327	5/14/2026 10:00:04 AM	6.5	81.0	0.5	12.0			0.1	24.0	181.4
CV-2327	5/14/2026 9:57:08 AM	5.6	78.4	1.4	14.6			0.1	10.4	179.5
CV-2327	5/14/2026 9:50:00 AM					3630				
CV-2327	5/4/2026 1:23:07 PM	2.8	86.5	0.0	10.7			0.0	0.0	185.1
CV-2327	5/4/2026 1:20:00 PM					1500				
CV-2327	5/4/2026 1:20:00 PM						48100			
CV-2328	5/28/2026 1:37:05 PM	13.1	76.8	0.0	10.1			0.2	0.0	164.9
CV-2328	5/20/2026 2:06:30 PM	13.2	72.4	0.0	14.4			0.2	0.0	167.3
CV-2328	5/20/2026 2:05:13 PM	13.2	74.3	0.0	12.5			0.2	0.0	167.2
CV-2328	5/11/2026 1:26:04 PM	34.7	65.3	0.0	0.0			0.5	0.0	144.6

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [ ]
CV-2328	5/7/2026 8:15:00 AM					980				
CV-2328	5/7/2026 8:15:00 AM						110000			
CV-2328	5/4/2026 1:07:16 PM	5.4	87.3	0.0	7.3			0.1	0.0	172.5
CV-2328	5/4/2026 1:06:42 PM	5.8	82.6	0.0	11.6			0.1	0.0	171.5
CV-2328	5/4/2026 1:05:00 PM					661				
CV-2328	5/4/2026 1:05:00 PM						53600			
CV-2333	5/29/2026 9:43:07 AM	0.9	77.1	0.0	22.0			0.0	0.0	188.6
CV-2333	5/26/2026 8:54:11 AM	0.7	76.3	0.0	23.0			0.0	0.0	163.1
CV-2333	5/18/2026 9:15:00 AM					4360				
CV-2333	5/18/2026 9:12:06 AM	8.1	75.1	0.0	16.8			0.1	0.0	157.9
CV-2333	5/13/2026 7:40:00 AM					3600				
CV-2333	5/13/2026 7:40:00 AM						160000			
CV-2333	5/12/2026 9:35:00 AM					2400				
CV-2333	5/12/2026 9:28:21 AM	13.6	81.1	0.0	5.3			0.2	0.0	177.0
CV-2333	5/6/2026 9:45:24 AM	0.6	82.4	0.0	17.0			0.0	0.0	191.3
CV-2333	5/6/2026 9:44:40 AM	0.6	82.8	0.0	16.6			0.0	0.0	191.2
CV-2333	5/5/2026 8:30:00 AM					4590				
CV-2333	5/5/2026 8:30:00 AM						160100			
CV-2333	5/5/2026 8:26:49 AM	1.3	85.7	0.0	13.0			0.0	0.0	165.9
CV-2334	5/26/2026 2:23:32 PM	7.2	92.8	0.0	0.0			0.1	0.0	127.6
CV-2334	5/13/2026 7:45:00 AM					660				
CV-2334	5/13/2026 7:45:00 AM						11000			
CV-2335	5/19/2026 10:11:09 AM	47.4	48.7	0.0	3.9			1.0	0.0	91.5
CV-2335	5/12/2026 10:45:40 AM	46.3	48.7	0.7	4.3			1.0	6.1	89.1
CV-2336	5/19/2026 10:14:30 AM	45.3	50.4	0.0	4.3			0.9	0.0	79.6
CV-2336	5/12/2026 10:27:38 AM	43.5	49.4	0.0	7.1			0.9	0.0	73.9
CV-2337	5/20/2026 8:23:36 AM	18.5	80.9	0.0	0.6			0.2	0.0	150.2
CV-2337	5/11/2026 2:00:37 PM	33.1	66.9	0.0	0.0			0.5	0.0	149.0
CV-2337	5/11/2026 8:05:00 AM					3500				
CV-2337	5/11/2026 8:05:00 AM						130000			
CV-2337	5/6/2026 9:26:13 AM	18.7	81.3	0.0	0.0			0.2	0.0	149.3
CV-2337	5/6/2026 9:25:00 AM					5500				
CV-2337	5/6/2026 9:25:00 AM						122300			
CV-2338	5/28/2026 8:46:22 AM	1.3	78.1	0.0	20.6			0.0	0.0	189.7
CV-2338	5/20/2026 8:15:49 AM	9.6	79.0	0.0	11.4			0.1	0.0	169.1
CV-2338	5/12/2026 10:09:33 AM	1.8	82.4	0.0	15.8			0.0	0.0	168.3

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-2338	5/12/2026 10:05:03 AM	1.7	77.8	0.0	20.5			0.0	0.0	187.0
CV-2338	5/11/2026 1:52:50 PM	22.3	77.7	0.0	0.0			0.3	0.0	172.3
CV-2338	5/11/2026 1:52:06 PM	17.9	80.9	0.0	1.2			0.2	0.0	174.6
CV-2338	5/6/2026 9:15:00 AM					1330				
CV-2338	5/6/2026 9:15:00 AM						174100			
CV-2338	5/6/2026 9:13:21 AM	14.4	85.6	0.0	0.0			0.2	0.0	155.1
CV-2338	5/6/2026 9:12:07 AM	17.6	78.1	0.4	3.9			0.2	9.8	156.1
CV-2339	5/29/2026 10:41:08 AM	0.4	8.0	18.5	73.1			0.1	4.0	82.2
CV-2339	5/29/2026 10:39:26 AM	0.6	12.6	17.3	69.5			0.0	4.0	79.3
CV-2339	5/14/2026 2:06:48 PM	11.7	72.7	0.0	15.6			0.2	0.0	88.2
CV-2339	5/14/2026 2:04:49 PM	16.0	72.5	0.0	11.5			0.2	0.0	88.3
CV-2341	5/29/2026 10:30:39 AM	9.1	67.8	1.3	21.8			0.1	16.8	86.6
CV-2341	5/14/2026 1:47:09 PM	8.8	69.3	1.1	20.8			0.1	18.9	92.2
CV-2341	5/11/2026 7:50:00 AM					850				
CV-2341	5/11/2026 7:50:00 AM						94000			
CV-2342A-PLR	5/28/2026 1:15:25 PM	4.2	71.5	0.0	24.3			0.1	0.0	187.6
CV-2342A-PLR	5/20/2026 9:08:28 AM	24.7	67.8	0.0	7.5			0.4	0.0	167.4
CV-2342A-PLR	5/13/2026 9:52:01 AM	18.4	72.7	0.0	8.9			0.3	0.0	168.7
CV-2342A-PLR	5/6/2026 10:10:00 AM	19.8	72.5	0.0	7.7			0.3	0.0	170.6
CV-2343	5/26/2026 2:33:45 PM	9.9	78.6	0.0	11.5			0.1	0.0	134.6
CV-2343	5/19/2026 2:04:37 PM	1.1	78.4	0.0	20.5			0.0	0.0	175.7
CV-2343	5/19/2026 2:03:22 PM	1.2	79.2	0.0	19.6			0.0	0.0	174.9
CV-2343	5/6/2026 9:56:02 AM	8.9	76.9	0.0	14.2			0.1	0.0	139.8
CV-2344	5/20/2026 8:51:25 AM	12.2	77.4	0.6	9.8			0.2	16.3	141.7
CV-2344	5/13/2026 9:31:33 AM	7.3	81.0	0.5	11.2			0.1	22.4	146.2
CV-2344	5/13/2026 9:30:38 AM	6.7	80.2	0.6	12.5			0.1	20.8	147.1
CV-2344	5/11/2026 7:35:00 AM					2900				

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [ ]
CV-2344	5/11/2026 7:35:00 AM						160000			
CV-2344	5/6/2026 9:52:20 AM	10.9	84.8	0.5	3.8			0.1	7.6	157.7
CV-2344	5/6/2026 9:50:00 AM					4020				
CV-2344	5/6/2026 9:50:00 AM						139400			
CV-2345	5/19/2026 2:17:28 PM	14.6	77.6	0.0	7.8			0.2	0.0	142.7
CV-2345	5/19/2026 2:15:18 PM	12.4	83.4	0.0	4.2			0.1	0.0	143.3
CV-2345	5/11/2026 7:30:00 AM					580				
CV-2345	5/11/2026 7:30:00 AM						28000			
CV-2345	5/1/2026 10:20:11 AM	14.2	79.3	0.1	6.4			0.2	64.0	138.1
CV-2345	5/1/2026 10:19:42 AM	14.6	78.8	0.1	6.5			0.2	65.0	137.8
CV-2346	5/28/2026 9:28:07 AM	1.3	78.6	0.9	19.2			0.0	21.3	187.1
CV-2346	5/20/2026 8:47:59 AM	17.4	80.5	0.0	2.1			0.2	0.0	183.1
CV-2346	5/13/2026 9:20:50 AM	10.9	84.3	0.0	4.8			0.1	0.0	182.1
CV-2346	5/6/2026 9:47:10 AM	17.2	82.8	0.0	0.0			0.2	0.0	182.1
CV-2346	5/6/2026 9:45:00 AM					3400				
CV-2346	5/6/2026 9:45:00 AM						118500			
CV-2346	5/6/2026 8:25:00 AM					2200				
CV-2346	5/6/2026 8:25:00 AM						130000			
CV-2346	5/4/2026 1:29:13 PM	3.5	77.6	0.0	19.0			0.0	0.0	178.9
CV-2346	5/4/2026 1:27:19 PM	3.8	76.4	0.0	19.9			0.0	0.0	179.5
CV-2347	5/20/2026 8:26:42 AM	15.0	64.8	0.0	20.2			0.2	0.0	121.6
CV-2347	5/6/2026 8:20:00 AM					1100				
CV-2347	5/6/2026 8:20:00 AM						56000			
CV-2347	5/1/2026 10:09:08 AM	10.7	68.3	0.1	20.9			0.2	209.0	116.7
CV-2348	5/20/2026 8:15:56 AM	20.4	54.1	0.0	25.5			0.4	0.0	107.8
CV-2348	5/13/2026 12:35:31 PM	19.8	56.6	0.3	23.3			0.3	77.7	128.7
CV-2348	5/6/2026 8:15:00 AM					460				
CV-2348	5/6/2026 8:15:00 AM						27000			
CV-2349	5/28/2026 10:20:04 AM	2.3	79.8	0.0	17.9			0.0	0.0	172.2
CV-2349	5/20/2026 10:27:38 AM	14.1	75.3	0.0	10.6			0.2	0.0	162.7
CV-2349	5/13/2026 10:48:12 AM	4.1	77.3	0.0	18.6			0.1	0.0	152.3

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [ ]
CV-2349	5/7/2026 11:16:23 AM	5.3	87.9	0.0	6.8			0.1	0.0	147.6
CV-2349	5/7/2026 11:15:19 AM	5.4	87.4	0.0	7.2			0.1	0.0	148.3
CV-2349	5/7/2026 11:15:00 AM					3350				
CV-2349	5/7/2026 11:15:00 AM						117000			
CV-2349	5/5/2026 8:25:00 AM					2600				
CV-2349	5/5/2026 8:25:00 AM						150000			
CV-2350	5/20/2026 10:03:44 AM	4.0	79.6	0.0	16.4			0.1	0.0	110.9
CV-2350	5/13/2026 12:57:10 PM	4.5	85.3	0.0	10.2			0.1	0.0	116.3
CV-2350	5/13/2026 12:56:01 PM	4.7	77.8	0.0	17.5			0.1	0.0	121.4
CV-2350	5/11/2026 7:40:00 AM					3700				
CV-2350	5/11/2026 7:40:00 AM						170000			
CV-2351	5/28/2026 9:25:03 AM	2.8	0.1	21.1	76.0			28.0	3.6	68.1
CV-2351	5/28/2026 9:24:00 AM	2.8	0.1	21.2	75.9			28.0	3.6	62.3
CV-2351	5/5/2026 7:50:00 AM					0				
CV-2351	5/5/2026 7:50:00 AM						1600			
CV-2351	5/1/2026 9:05:14 AM	0.0	1.8	21.2	77.0			0.0	3.6	83.8
CV-2352	5/28/2026 9:16:38 AM	5.7	29.9	13.0	51.4			0.2	4.0	108.7
CV-2352	5/28/2026 9:12:47 AM	2.6	25.4	15.5	56.5			0.1	3.6	99.0
CV-2352	5/5/2026 8:00:00 AM					1100				
CV-2352	5/5/2026 8:00:00 AM						190000			
CV-2352	5/1/2026 9:13:24 AM	0.0	0.5	21.4	78.1			0.0	3.6	115.6
CV-2353-PLR	5/20/2026 9:13:57 AM	26.1	68.8	0.5	4.6			0.4	9.2	131.8
CV-2353-PLR	5/20/2026 9:13:10 AM	25.8	66.6	1.1	6.5			0.4	5.9	129.5
CV-2353-PLR	5/15/2026 8:29:12 AM	2.7	78.1	0.0	19.2			0.0	0.0	147.6
CV-2353-PLR	5/15/2026 8:27:25 AM	2.6	77.8	0.0	19.6			0.0	0.0	147.9
CV-2353-PLR	5/14/2026 8:40:00 AM					924				
CV-2353-PLR	5/12/2026 7:35:00 AM					760				
CV-2353-PLR	5/12/2026 7:35:00 AM						210000			
CV-2354	5/28/2026 10:36:46 AM	4.2	78.4	0.0	17.4			0.1	0.0	183.8

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [ ]
CV-2354	5/20/2026 10:42:07 AM	35.4	64.6	0.0	0.0			0.5	0.0	179.6
CV-2354	5/20/2026 10:40:36 AM	35.6	64.4	0.0	0.0			0.6	0.0	179.4
CV-2354	5/13/2026 11:03:49 AM	4.8	81.5	0.4	13.3			0.1	33.3	166.6
CV-2354	5/13/2026 11:01:08 AM	4.5	77.9	1.4	16.2			0.1	11.6	166.8
CV-2354	5/6/2026 10:50:20 AM	24.8	75.2	0.0	0.0			0.3	0.0	174.0
CV-2354	5/6/2026 10:50:00 AM					3190				
CV-2354	5/6/2026 10:50:00 AM						148000			
CV-2354	5/5/2026 8:20:00 AM					2500				
CV-2354	5/5/2026 8:20:00 AM						170000			
CV-24001	5/19/2026 10:02:44 AM	42.5	57.5	0.0	0.0			0.7	0.0	91.2
CV-24001	5/12/2026 10:38:27 AM	43.6	56.3	0.0	0.1			0.8	0.0	102.5
CV-24002	5/19/2026 9:53:36 AM	45.8	53.6	0.0	0.6			0.9	0.0	89.2
CV-24002	5/19/2026 9:51:18 AM	47.3	51.9	0.0	0.8			0.9	0.0	87.8
CV-24002	5/1/2026 2:39:31 PM	44.4	53.9	0.0	1.7			0.8	0.0	92.4
CV-24003	5/19/2026 9:12:06 AM	45.8	52.7	0.0	1.5			0.9	0.0	107.1
CV-24003	5/1/2026 2:37:02 PM	39.9	57.4	0.0	2.7			0.7	0.0	101.6
CV-24004	5/19/2026 9:02:30 AM	42.7	56.4	0.0	0.9			0.8	0.0	115.2
CV-24004	5/1/2026 2:33:11 PM	40.4	58.6	0.0	1.0			0.7	0.0	115.2
CV-24006	5/19/2026 10:36:49 AM	38.4	56.6	0.0	5.0			0.7	0.0	127.2
CV-24006	5/1/2026 11:40:45 AM	37.2	59.6	0.0	3.2			0.6	0.0	127.7
CV-24007	5/29/2026 9:33:56 AM	27.8	66.3	0.0	5.9			0.4	0.0	148.0
CV-24007	5/26/2026 1:56:22 PM	33.7	66.3	0.0	0.0			0.5	0.0	150.7
CV-24007	5/26/2026 1:55:46 PM	28.1	71.9	0.0	0.0			0.4	0.0	150.2
CV-24007	5/19/2026 10:46:37 AM	18.2	71.0	0.0	10.8			0.3	0.0	150.9
CV-24007	5/19/2026 10:45:21 AM	19.9	70.8	0.0	9.3			0.3	0.0	150.9
CV-24007	5/15/2026 9:10:41 AM	4.8	66.5	0.0	28.7			0.1	0.0	138.6
CV-24007	5/15/2026 9:09:54 AM	5.6	77.6	0.0	16.8			0.1	0.0	132.2

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-24007	5/12/2026 8:40:00 AM					1800				
CV-24007	5/12/2026 8:40:00 AM						170000			
CV-24008	5/26/2026 1:50:27 PM	7.3	76.2	0.3	16.2			0.1	54.0	168.9
CV-24008	5/18/2026 2:25:00 PM					2220				
CV-24008	5/18/2026 2:17:05 PM	19.6	72.9	0.0	7.5			0.3	0.0	170.5
CV-24008	5/12/2026 1:41:31 PM	22.1	76.7	0.4	0.8			0.3	2.0	171.4
CV-24008	5/12/2026 1:40:00 PM					1380				
CV-24008	5/5/2026 10:20:00 AM					831.5				
CV-24008	5/5/2026 10:20:00 AM						86600			
CV-24008	5/5/2026 10:14:56 AM	11.9	78.3	0.0	9.8			0.2	0.0	172.4
CV-24009	5/26/2026 1:46:14 PM	16.4	77.9	0.0	5.7			0.2	0.0	155.5
CV-24009	5/18/2026 2:20:00 PM					1480				
CV-24009	5/18/2026 2:13:29 PM	34.9	65.1	0.0	0.0			0.5	0.0	155.7
CV-24009	5/12/2026 1:35:00 PM					384				
CV-24009	5/12/2026 1:31:36 PM	27.2	72.5	0.3	0.0			0.4	0.0	156.7
CV-24009	5/5/2026 10:15:00 AM					1300				
CV-24009	5/5/2026 10:15:00 AM						135300			
CV-24009	5/5/2026 10:10:10 AM	24.6	75.4	0.0	0.0			0.3	0.0	156.0
CV-24010	5/26/2026 9:45:36 AM	7.3	58.5	7.3	26.9			0.1	3.7	61.0
CV-24010	5/13/2026 1:57:52 PM	5.4	49.1	8.0	37.5			0.1	4.7	89.1
CV-24011	5/27/2026 8:51:05 AM	6.7	74.3	0.1	18.9			0.1	189.0	188.3
CV-24011	5/27/2026 8:49:35 AM	4.2	76.0	0.1	19.7			0.1	197.0	188.5
CV-24011	5/19/2026 10:30:22 AM	6.9	78.8	0.0	14.3			0.1	0.0	186.9
CV-24011	5/18/2026 2:55:00 PM					3180				
CV-24011	5/18/2026 2:48:57 PM	25.9	67.2	0.0	6.9			0.4	0.0	187.6
CV-24011	5/12/2026 2:43:10 PM	33.6	66.4	0.0	0.0			0.5	0.0	184.2
CV-24011	5/12/2026 2:25:00 PM					1890				
CV-24011	5/5/2026 1:10:54 PM	26.3	73.6	0.0	0.1			0.4	0.0	185.2
CV-24011	5/5/2026 1:10:00 PM					2020				
CV-24011	5/5/2026 1:10:00 PM						107700			
CV-24012	5/26/2026 2:14:33 PM	12.8	77.0	0.0	10.2			0.2	0.0	151.8
CV-24012	5/18/2026 2:56:25 PM	24.9	71.8	0.0	3.3			0.3	0.0	161.9
CV-24012	5/18/2026 2:50:00 PM					1555				
CV-24012	5/18/2026 2:41:34 PM	24.6	73.4	0.0	2.0			0.3	0.0	156.5
CV-24012	5/12/2026 2:38:30 PM	25.0	74.9	0.0	0.1			0.3	0.0	174.4

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-24012	5/12/2026 2:20:00 PM					1230				
CV-24012	5/5/2026 1:30:00 PM					2270				
CV-24012	5/5/2026 1:30:00 PM						164700			
CV-24012	5/5/2026 1:26:23 PM	9.7	81.5	0.0	8.8			0.1	0.0	156.8
CV-24013	5/26/2026 9:51:46 AM	1.2	42.2	11.4	45.2			0.0	4.0	93.4
CV-24013	5/13/2026 10:06:33 AM	1.5	42.5	10.7	45.3			0.0	4.2	99.4
CV-24014	5/26/2026 1:42:04 PM	8.6	75.3	0.0	16.1			0.1	0.0	177.2
CV-24014	5/18/2026 2:15:00 PM					2220				
CV-24014	5/18/2026 2:07:26 PM	25.0	72.5	0.0	2.5			0.3	0.0	175.7
CV-24014	5/12/2026 1:30:00 PM					1800				
CV-24014	5/12/2026 1:26:38 PM	18.5	75.5	0.5	5.5			0.2	11.0	176.3
CV-24014	5/12/2026 1:25:28 PM	20.9	72.3	0.8	6.0			0.3	7.5	176.2
CV-24014	5/5/2026 10:10:00 AM					2130				
CV-24014	5/5/2026 10:10:00 AM						190100			
CV-24014	5/5/2026 10:06:41 AM	18.2	78.3	0.0	3.5			0.2	0.0	176.1
CV-24015	5/26/2026 9:48:59 AM	4.0	74.0	0.0	22.0			0.1	0.0	186.4
CV-24015	5/18/2026 10:08:30 AM	17.5	72.6	0.0	9.9			0.2	0.0	183.6
CV-24015	5/18/2026 10:06:48 AM	17.8	72.8	0.0	9.4			0.2	0.0	183.6
CV-24015	5/18/2026 10:05:03 AM	19.0	71.5	0.0	9.5			0.3	0.0	183.9
CV-24015	5/18/2026 10:05:00 AM					1850				
CV-24015	5/12/2026 9:01:20 AM	13.7	74.4	0.5	11.4			0.2	22.8	184.0
CV-24015	5/12/2026 9:00:00 AM					396				
CV-24015	5/12/2026 8:59:57 AM	12.6	71.7	1.5	14.2			0.2	9.5	183.9
CV-24015	5/5/2026 9:14:20 AM	6.8	77.9	0.0	15.3			0.1	0.0	169.8
CV-24015	5/5/2026 9:05:00 AM					2140				
CV-24015	5/5/2026 9:05:00 AM						203600			
CV-24016	5/29/2026 9:27:07 AM	14.3	66.1	0.0	19.6			0.2	0.0	178.3
CV-24016	5/27/2026 8:54:06 AM	9.5	72.3	0.0	18.2			0.1	0.0	170.6

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-24016	5/19/2026 10:04:01 AM	13.6	67.4	0.0	19.0			0.2	0.0	182.9
CV-24016	5/19/2026 10:02:01 AM	14.0	67.1	0.0	19.0			0.2	0.0	182.0
CV-24016	5/18/2026 3:00:00 PM					2200				
CV-24016	5/18/2026 2:51:00 PM	48.1	51.9	0.0	0.0			0.9	0.0	168.0
CV-24016	5/12/2026 2:44:41 PM	38.6	61.4	0.0	0.0			0.6	0.0	160.6
CV-24016	5/12/2026 2:30:00 PM					1330				
CV-24016	5/6/2026 1:26:28 PM	8.3	74.9	0.0	16.8			0.1	0.0	170.2
CV-24016	5/6/2026 1:25:16 PM	9.2	73.8	0.0	17.0			0.1	0.0	169.5
CV-24016	5/5/2026 1:15:29 PM	30.4	69.6	0.0	0.0			0.4	0.0	161.7
CV-24016	5/5/2026 1:15:00 PM					1980				
CV-24016	5/5/2026 1:15:00 PM						96600			
CV-24017	5/26/2026 2:08:15 PM	19.6	76.0	0.6	3.8			0.3	6.3	170.4
CV-24017	5/26/2026 2:07:20 PM	17.6	76.3	0.8	5.3			0.2	6.6	172.4
CV-24017	5/18/2026 2:40:00 PM					2520				
CV-24017	5/18/2026 2:35:18 PM	25.5	74.5	0.0	0.0			0.3	0.0	171.6
CV-24017	5/12/2026 2:47:32 PM	25.5	74.5	0.0	0.0			0.3	0.0	172.2
CV-24017	5/12/2026 2:25:14 PM	18.0	72.7	0.6	8.7			0.2	14.5	181.0
CV-24017	5/12/2026 2:10:00 PM					1230				
CV-24017	5/12/2026 8:35:00 AM					2100				
CV-24017	5/12/2026 8:35:00 AM						190000			
CV-24017	5/5/2026 1:20:00 PM					2760				
CV-24017	5/5/2026 1:20:00 PM						155500			
CV-24017	5/5/2026 1:19:34 PM	10.8	78.7	0.6	9.9			0.1	16.5	159.0
CV-24018	5/29/2026 11:06:53 AM	9.3	73.2	1.8	15.7			0.1	8.7	113.7
CV-24018	5/13/2026 3:41:42 PM	22.3	71.1	0.9	5.7			0.3	6.3	109.4
CV-24019	5/27/2026 8:57:49 AM	1.6	81.3	0.0	17.1			0.0	0.0	169.8
CV-24019	5/19/2026 8:35:00 AM					1570				
CV-24019	5/19/2026 8:31:39 AM	13.8	81.4	0.0	4.8			0.2	0.0	168.0
CV-24019	5/13/2026 2:09:27 PM	1.8	75.9	0.0	22.3			0.0	0.0	178.7

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [ ]
CV-24019	5/5/2026 2:30:00 PM					2030				
CV-24019	5/5/2026 2:30:00 PM						141800			
CV-24019	5/5/2026 2:26:07 PM	16.0	80.8	0.0	3.2			0.2	0.0	182.8
CV-24020	5/26/2026 10:31:13 AM	0.2	62.7	7.2	29.9			0.0	4.2	60.3
CV-24020	5/13/2026 1:39:38 PM	0.7	67.6	4.2	27.5			0.0	6.5	84.0
CV-24021	5/26/2026 10:19:45 AM	0.8	57.4	0.0	41.8			0.0	0.0	63.1
CV-24021	5/13/2026 10:19:21 AM	1.5	58.5	1.5	38.5			0.0	25.7	74.5
CV-24022-PLR	5/26/2026 1:34:59 PM	7.4	76.1	0.3	16.2			0.1	54.0	194.3
CV-24022-PLR	5/18/2026 2:10:00 PM					2100				
CV-24022-PLR	5/18/2026 2:04:39 PM	26.0	72.9	0.0	1.1			0.4	0.0	194.7
CV-24022-PLR	5/12/2026 1:25:00 PM					762				
CV-24022-PLR	5/12/2026 1:18:18 PM	20.0	76.4	0.2	3.4			0.3	17.0	191.4
CV-24022-PLR	5/5/2026 10:05:00 AM					2550				
CV-24022-PLR	5/5/2026 10:05:00 AM						199200			
CV-24022-PLR	5/5/2026 10:03:55 AM	14.6	78.4	0.0	7.0			0.2	0.0	192.4
CV-24023	5/26/2026 10:02:11 AM	5.0	68.9	2.2	23.9			0.1	10.9	174.0
CV-24023	5/26/2026 9:58:22 AM	2.8	51.1	7.4	38.7			0.1	5.2	166.4
CV-24023	5/18/2026 10:19:04 AM	15.9	70.8	0.4	12.9			0.2	32.3	157.4
CV-24023	5/18/2026 10:15:00 AM	14.9	70.7	0.2	14.2			0.2	71.0	159.8
CV-24023	5/12/2026 8:52:20 AM	9.9	78.0	0.0	12.1			0.1	0.0	179.7
CV-24023	5/12/2026 8:51:10 AM	7.0	75.0	0.2	17.8			0.1	89.0	179.2
CV-24023	5/12/2026 8:50:00 AM					220.5				
CV-24023	5/6/2026 9:28:29 AM	1.5	77.6	0.0	20.9			0.0	0.0	168.4
CV-24023	5/6/2026 9:27:29 AM	1.6	76.5	0.0	21.9			0.0	0.0	168.4

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-24023	5/5/2026 9:36:54 AM	6.7	77.2	0.0	16.1			0.1	0.0	180.0
CV-24023	5/5/2026 9:35:20 AM	6.9	75.4	0.0	17.7			0.1	0.0	178.4
CV-24023	5/5/2026 9:27:58 AM	6.0	76.8	0.0	17.2			0.1	0.0	157.5
CV-24023	5/5/2026 9:25:00 AM					1925				
CV-24023	5/5/2026 9:25:00 AM						215750			
CV-24024-PLR	5/18/2026 9:51:23 AM	15.4	72.4	0.1	12.1			0.2	121.0	131.2
CV-24024-PLR	5/15/2026 9:22:07 AM	1.2	77.5	0.3	21.0			0.0	70.0	157.4
CV-24024-PLR	5/15/2026 9:20:22 AM	1.3	75.2	0.2	23.3			0.0	116.5	155.8
CV-24025	5/28/2026 2:28:43 PM	2.3	82.3	0.0	15.4			0.0	0.0	188.2
CV-24025	5/19/2026 9:27:53 AM	16.7	80.0	0.0	3.3			0.2	0.0	186.5
CV-24025	5/19/2026 9:26:52 AM	19.7	78.0	0.0	2.3			0.3	0.0	184.2
CV-24025	5/19/2026 9:25:00 AM					2300				
CV-24025	5/13/2026 2:30:31 PM	1.8	77.5	0.0	20.7			0.0	0.0	187.2
CV-24025	5/6/2026 8:57:31 AM	1.6	79.7	0.0	18.7			0.0	0.0	186.2
CV-24025	5/6/2026 8:56:37 AM	1.8	77.5	0.0	20.7			0.0	0.0	186.3
CV-24025	5/5/2026 2:13:13 PM	13.0	84.0	0.0	3.0			0.2	0.0	185.0
CV-24025	5/5/2026 2:10:00 PM					3280				
CV-24025	5/5/2026 2:10:00 PM						110700			
CV-24026	5/22/2026 12:25:54 PM	2.7	74.6	2.1	20.6			0.0	9.8	92.5
CV-24026	5/13/2026 1:43:47 PM	0.5	76.1	0.9	22.5			0.0	25.0	88.7
CV-24027	5/26/2026 10:11:09 AM	2.4	71.7	2.2	23.7			0.0	10.8	63.6
CV-24027	5/13/2026 10:15:50 AM	2.6	52.6	7.9	36.9			0.0	4.7	74.6
CV-24027	5/6/2026 9:11:56 AM	2.9	65.8	3.6	27.7			0.0	7.7	81.7
CV-24028	5/26/2026 1:15:48 PM	2.7	73.7	0.0	23.6			0.0	0.0	187.3
CV-24028	5/26/2026 1:13:13 PM	2.6	72.6	0.0	24.8			0.0	0.0	188.1

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-24028	5/18/2026 2:05:00 PM					1015				
CV-24028	5/18/2026 2:01:26 PM	33.7	66.3	0.0	0.0			0.5	0.0	189.1
CV-24028	5/12/2026 1:20:00 PM					440				
CV-24028	5/12/2026 1:14:56 PM	21.1	75.5	0.4	3.0			0.3	7.5	187.8
CV-24028	5/5/2026 10:00:52 AM	16.0	75.4	0.0	8.6			0.2	0.0	193.4
CV-24028	5/5/2026 10:00:00 AM					1320				
CV-24028	5/5/2026 10:00:00 AM						186700			
CV-24029	5/29/2026 11:19:30 AM	0.3	10.8	17.9	71.0			0.0	4.0	87.9
CV-24029	5/29/2026 11:15:41 AM	0.4	11.1	17.7	70.8			0.0	4.0	86.3
CV-24029	5/13/2026 2:06:48 PM	0.5	8.7	18.0	72.8			0.1	4.0	85.2
CV-24030	5/26/2026 9:14:08 AM	1.8	73.9	0.0	24.3			0.0	0.0	192.1
CV-24030	5/26/2026 9:07:52 AM	2.1	74.3	1.1	22.5			0.0	20.5	192.2
CV-24030	5/18/2026 9:35:03 AM	11.3	74.3	0.3	14.1			0.2	47.0	190.7
CV-24030	5/18/2026 9:35:00 AM					1760				
CV-24030	5/12/2026 9:18:44 AM	19.0	78.0	0.2	2.8			0.2	14.0	193.0
CV-24030	5/12/2026 9:15:00 AM					93.6				
CV-24030	5/5/2026 8:46:48 AM	3.0	78.0	1.3	17.7			0.0	13.6	191.0
CV-24030	5/5/2026 8:45:00 AM					2080				
CV-24030	5/5/2026 8:45:00 AM						172600			
CV-24030	5/5/2026 8:44:58 AM	2.8	75.0	2.1	20.1			0.0	9.6	191.2
CV-24031	5/29/2026 1:15:41 PM	39.9	60.1	0.0	0.0			0.7	0.0	116.9
CV-24031	5/22/2026 12:15:48 PM	25.8	71.0	0.0	3.2			0.4	0.0	131.7
CV-24031	5/22/2026 12:14:13 PM	25.2	71.1	0.0	3.7			0.4	0.0	133.3
CV-24031	5/12/2026 1:32:07 PM	20.7	70.8	0.0	8.5			0.3	0.0	121.3
CV-24032	5/27/2026 9:19:07 AM	1.2	79.2	0.0	19.6			0.0	0.0	191.6
CV-24032	5/27/2026 9:17:20 AM	1.3	81.9	0.0	16.8			0.0	0.0	191.9

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [ ]
CV-24032	5/27/2026 9:09:02 AM	1.3	85.0	0.1	13.6			0.0	136.0	193.5
CV-24032	5/24/2026 12:06:03 PM	0.6	38.1	12.6	48.7			0.0	3.9	147.4
CV-24032	5/24/2026 12:02:54 PM	0.6	36.7	12.7	50.0			0.0	3.9	140.3
CV-24032	5/19/2026 8:41:47 AM	15.2	80.5	0.0	4.3			0.2	0.0	137.9
CV-24032	5/14/2026 10:31:39 AM	1.1	86.8	0.0	12.1			0.0	0.0	180.5
CV-24032	5/13/2026 2:37:29 PM	3.5	81.6	0.0	14.9			0.0	0.0	151.2
CV-24032	5/5/2026 2:20:00 PM					1855				
CV-24032	5/5/2026 2:20:00 PM						129050			
CV-24032	5/5/2026 2:17:41 PM	16.4	83.6	0.0	0.0			0.2	0.0	150.1
CV-24033	5/28/2026 2:24:12 PM	1.7	77.5	0.0	20.8			0.0	0.0	190.8
CV-24033	5/19/2026 8:45:00 AM					2240				
CV-24033	5/19/2026 8:39:24 AM	13.9	73.3	0.0	12.8			0.2	0.0	183.8
CV-24033	5/13/2026 2:17:00 PM	2.3	75.5	0.0	22.2			0.0	0.0	185.4
CV-24033	5/7/2026 1:00:00 PM						171000			
CV-24033	5/7/2026 12:59:49 PM	5.6	79.7	0.4	14.3			0.1	35.8	188.1
CV-24033	5/7/2026 1:00:00 AM					2300				
CV-24034	5/18/2026 11:08:37 AM	25.1	66.8	3.2	4.9			0.4	1.5	108.1
CV-24034	5/18/2026 11:06:51 AM	25.2	66.9	3.0	4.9			0.4	1.6	109.5
CV-24034	5/12/2026 10:57:45 AM	24.2	75.5	0.3	0.0			0.3	0.0	165.5
CV-24034	5/12/2026 10:55:50 AM	26.3	72.9	0.8	0.0			0.4	0.0	170.4
CV-24034	5/12/2026 10:55:00 AM					247.5				
CV-24034	5/5/2026 9:57:30 AM	13.6	83.8	0.0	2.6			0.2	0.0	185.0
CV-24034	5/5/2026 9:56:30 AM	14.3	81.5	0.0	4.2			0.2	0.0	185.4
CV-24034	5/5/2026 9:55:00 AM					1730				
CV-24034	5/5/2026 9:55:00 AM						166300			

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-24035	5/26/2026 8:50:47 AM	1.8	80.2	0.0	18.0			0.0	0.0	181.1
CV-24035	5/18/2026 9:10:00 AM					1735				
CV-24035	5/18/2026 9:05:47 AM	10.9	76.7	0.4	12.0			0.1	30.0	193.5
CV-24035	5/18/2026 9:03:47 AM	8.3	81.8	0.0	9.9			0.1	0.0	189.5
CV-24035	5/12/2026 9:40:00 AM					2255				
CV-24035	5/12/2026 9:31:35 AM	14.8	83.4	0.0	1.8			0.2	0.0	177.3
CV-24035	5/5/2026 8:25:00 AM					2305				
CV-24035	5/5/2026 8:25:00 AM						142450			
CV-24035	5/5/2026 8:24:01 AM	2.2	82.1	0.0	15.7			0.0	0.0	178.7
CV-24036	5/29/2026 2:20:04 PM	62.3	37.0	0.7	0.0			1.7	0.0	82.5
CV-24036	5/24/2026 11:45:25 AM	53.2	40.4	0.6	5.9			1.3	10.3	73.3
CV-24036	5/13/2026 10:53:14 AM	55.5	42.1	0.1	2.3			1.3	23.0	77.2
CV-24036	5/6/2026 8:46:55 AM	46.2	36.5	3.1	14.2			1.3	4.6	68.0
CV-24037	5/26/2026 9:09:53 AM	0.5	25.3	15.3	58.9			0.0	3.8	59.2
CV-24037	5/26/2026 9:08:28 AM	0.5	23.4	15.7	60.4			0.0	3.8	58.7
CV-24037	5/12/2026 1:53:15 PM	1.9	61.5	4.8	31.8			0.0	6.6	80.2
CV-24038	5/27/2026 9:29:33 AM	1.9	77.0	0.6	20.5			0.0	34.2	178.6
CV-24038	5/27/2026 9:27:49 AM	1.6	72.4	2.0	24.0			0.0	12.0	176.7
CV-24038	5/19/2026 9:05:00 AM					1240				
CV-24038	5/19/2026 9:04:35 AM	18.1	76.9	0.0	5.0			0.2	0.0	170.8
CV-24038	5/19/2026 9:04:12 AM	16.8	71.9	0.0	11.3			0.2	0.0	171.1
CV-24038	5/13/2026 2:51:36 PM	8.5	72.6	1.0	17.9			0.1	17.9	172.0
CV-24038	5/13/2026 2:48:58 PM	7.6	72.8	1.2	18.4			0.1	15.3	175.2

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-24038	5/6/2026 3:05:00 PM					1840				
CV-24038	5/6/2026 3:05:00 PM						170600			
CV-24038	5/6/2026 3:04:57 PM	2.9	80.4	0.0	16.7			0.0	0.0	182.3
CV-24038	5/6/2026 3:04:21 PM	3.1	80.3	0.0	16.6			0.0	0.0	181.8
CV-24039	5/22/2026 12:04:33 PM	1.3	69.8	0.0	28.9			0.0	0.0	144.7
CV-24039	5/22/2026 12:01:47 PM	0.9	69.8	0.0	29.3			0.0	0.0	149.7
CV-24039	5/22/2026 11:58:20 AM	4.6	65.2	0.0	30.2			0.1	0.0	118.9
CV-24039	5/14/2026 1:31:24 PM	0.6	1.1	19.6	78.7			0.5	4.0	87.8
CV-24039	5/14/2026 1:29:39 PM	0.4	2.1	19.6	77.9			0.2	4.0	86.4
CV-24040	5/29/2026 9:07:46 AM	0.4	79.7	0.0	19.9			0.0	0.0	172.6
CV-24040	5/29/2026 9:07:06 AM	0.5	79.9	0.0	19.6			0.0	0.0	172.3
CV-24040	5/29/2026 9:05:56 AM	0.6	78.5	0.0	20.9			0.0	0.0	171.2
CV-24040	5/19/2026 10:40:23 AM	4.5	48.6	9.1	37.8			0.1	4.2	86.6
CV-24040	5/19/2026 10:38:38 AM	4.0	43.2	11.0	41.8			0.1	3.8	85.8
CV-24040	5/13/2026 1:35:35 PM	0.0	11.8	16.7	71.5			0.0	4.3	82.2
CV-24040	5/13/2026 1:32:34 PM	0.0	11.4	16.8	71.8			0.0	4.3	81.7
CV-24041	5/26/2026 10:04:46 AM	8.2	45.5	8.4	37.9			0.2	4.5	65.0
CV-24041	5/8/2026 8:06:27 AM	17.8	55.5	4.2	22.5			0.3	5.4	70.8
CV-24042	5/26/2026 11:03:38 AM	13.0	75.4	0.0	11.6			0.2	0.0	181.8
CV-24042	5/26/2026 11:02:42 AM	20.7	71.0	0.0	8.3			0.3	0.0	184.9
CV-24042	5/18/2026 10:55:00 AM					2040				
CV-24042	5/18/2026 10:47:52 AM	17.1	78.4	0.0	4.5			0.2	0.0	189.6
CV-24042	5/12/2026 10:15:58 AM	28.7	71.3	0.0	0.0			0.4	0.0	184.3

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [ ]
CV-24042	5/12/2026 10:15:09 AM	30.9	69.1	0.0	0.0			0.4	0.0	180.3
CV-24042	5/12/2026 10:15:00 AM					45.4				
CV-24042	5/7/2026 10:08:18 AM	3.1	81.3	0.0	15.6			0.0	0.0	190.6
CV-24042	5/7/2026 10:06:45 AM	2.9	86.2	0.0	10.9			0.0	0.0	191.5
CV-24042	5/7/2026 10:05:00 AM					2930				
CV-24042	5/7/2026 10:05:00 AM						139400			
CV-24043	5/22/2026 2:06:15 PM	41.3	56.0	0.4	2.3			0.7	5.8	91.4
CV-24043	5/15/2026 8:55:16 AM	41.1	57.2	0.1	1.6			0.7	16.0	84.7
CV-24044	5/26/2026 8:46:58 AM	20.0	76.6	0.0	3.4			0.3	0.0	130.0
CV-24044	5/26/2026 8:42:07 AM	20.7	75.5	0.0	3.8			0.3	0.0	129.1
CV-24044	5/8/2026 12:36:24 PM	30.9	58.6	0.4	10.1			0.5	25.3	87.2
CV-24045	5/27/2026 9:33:35 AM	1.0	81.8	0.0	17.2			0.0	0.0	155.6
CV-24045	5/27/2026 9:32:48 AM	1.1	80.9	0.0	18.0			0.0	0.0	152.9
CV-24045	5/19/2026 9:11:34 AM	20.0	69.4	0.9	9.7			0.3	10.8	149.7
CV-24045	5/19/2026 9:10:36 AM	18.5	72.9	1.5	7.1			0.3	4.7	151.2
CV-24045	5/19/2026 9:10:00 AM					1880				
CV-24045	5/13/2026 2:58:14 PM	6.9	72.5	0.8	19.8			0.1	24.8	149.9
CV-24045	5/13/2026 2:56:09 PM	6.6	73.0	2.0	18.4			0.1	9.2	150.8
CV-24045	5/6/2026 2:55:47 PM	1.3	80.6	0.1	18.0			0.0	180.0	161.9
CV-24045	5/6/2026 2:54:58 PM	1.4	80.6	0.5	17.5			0.0	35.0	162.2
CV-24045	5/6/2026 2:45:00 PM					2510				
CV-24045	5/6/2026 2:45:00 PM						161800			
CV-24046	5/29/2026 1:33:04 PM	4.0	77.6	0.0	18.4			0.1	0.0	126.8
CV-24046	5/29/2026 1:30:24 PM	2.7	73.4	0.0	23.9			0.0	0.0	132.5

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [ ]
CV-24046	5/28/2026 11:56:16 AM	0.2	47.1	9.3	43.4			0.0	4.7	73.3
CV-24046	5/28/2026 11:54:22 AM	0.2	46.4	9.5	43.9			0.0	4.6	72.4
CV-24046	5/13/2026 10:32:28 AM	0.9	66.4	3.3	29.4			0.0	8.9	96.0
CV-24048	5/20/2026 2:12:35 PM	2.2	54.6	5.1	38.1			0.0	7.5	97.3
CV-24048	5/19/2026 10:25:00 AM					2320				
CV-24048	5/8/2026 8:14:16 AM	2.2	69.1	2.5	26.2			0.0	10.5	83.0
CV-24049	5/26/2026 10:45:00 AM	3.5	81.4	0.0	15.1			0.0	0.0	179.0
CV-24049	5/26/2026 10:43:34 AM	4.4	78.6	0.0	17.0			0.1	0.0	179.9
CV-24049	5/18/2026 10:35:00 AM					3260				
CV-24049	5/18/2026 10:30:56 AM	18.5	77.4	0.0	4.1			0.2	0.0	179.6
CV-24049	5/13/2026 8:10:00 AM					2800				
CV-24049	5/13/2026 8:10:00 AM						160000			
CV-24049	5/11/2026 8:49:25 AM	2.9	84.8	0.0	12.3			0.0	0.0	186.0
CV-24049	5/11/2026 8:47:07 AM	2.8	83.6	0.0	13.6			0.0	0.0	186.2
CV-24049	5/4/2026 2:40:00 PM					705				
CV-24049	5/4/2026 2:40:00 PM						25900			
CV-24049	5/4/2026 2:36:19 PM	2.0	88.0	0.0	10.0			0.0	0.0	188.6
CV-24050	5/22/2026 2:16:54 PM	47.4	52.5	0.0	0.1			0.9	0.0	103.5
CV-24050	5/11/2026 12:53:12 PM	46.1	47.9	0.0	6.0			1.0	0.0	109.5
CV-24051	5/26/2026 8:54:30 AM	14.7	73.1	1.2	11.0			0.2	9.2	101.9
CV-24051	5/8/2026 12:45:09 PM	0.4	1.8	19.4	78.4			0.2	4.0	83.5
CV-24052	5/20/2026 2:26:23 PM	30.3	48.6	2.5	18.6			0.6	7.4	93.6
CV-24052	5/13/2026 10:05:26 AM	28.4	51.2	1.0	19.4			0.6	19.4	73.3
CV-24053	5/20/2026 2:23:25 PM	50.4	48.4	0.0	1.2			1.0	0.0	100.2
CV-24053	5/8/2026 8:18:44 AM	39.3	43.1	2.5	15.1			0.9	6.0	75.4
CV-24053	5/7/2026 8:40:00 AM					88				
CV-24053	5/7/2026 8:40:00 AM						5300			

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-24054	5/26/2026 10:39:35 AM	6.9	82.5	0.0	10.6			0.1	0.0	153.4
CV-24054	5/26/2026 10:39:02 AM	8.7	83.3	0.0	8.0			0.1	0.0	154.0
CV-24054	5/18/2026 10:30:00 AM					2560				
CV-24054	5/18/2026 10:27:38 AM	23.7	76.3	0.0	0.0			0.3	0.0	145.7
CV-24054	5/18/2026 10:26:19 AM	23.7	76.3	0.0	0.0			0.3	0.0	146.7
CV-24054	5/11/2026 8:39:09 AM	3.6	88.3	0.0	8.1			0.0	0.0	163.9
CV-24054	5/11/2026 8:36:54 AM	3.4	86.9	0.0	9.7			0.0	0.0	163.3
CV-24054	5/4/2026 2:35:00 PM					2310				
CV-24054	5/4/2026 2:35:00 PM						105800			
CV-24054	5/4/2026 2:34:03 PM	3.0	90.5	0.0	6.5			0.0	0.0	174.6
CV-24054	5/4/2026 1:54:35 PM	2.2	77.0	0.0	20.8			0.0	0.0	147.2
CV-24054	5/4/2026 1:51:53 PM	2.5	76.4	0.0	21.1			0.0	0.0	150.7
CV-24055	5/26/2026 9:28:17 AM	14.4	66.0	1.1	18.5			0.2	16.8	137.4
CV-24055	5/26/2026 9:27:16 AM	14.3	66.2	1.1	18.4			0.2	16.7	137.4
CV-24055	5/13/2026 8:15:00 AM					930				
CV-24055	5/13/2026 8:15:00 AM						51000			
CV-24055	5/12/2026 1:49:20 PM	9.1	62.3	1.6	27.0			0.1	16.9	137.8
CV-24055	5/12/2026 1:47:04 PM	9.0	65.6	2.2	23.2			0.1	10.5	136.9
CV-24056	5/19/2026 12:46:55 PM	38.9	56.8	0.0	4.3			0.7	0.0	126.5
CV-24056	5/1/2026 10:37:33 AM	37.8	57.6	0.0	4.6			0.7	0.0	125.0
CV-24057	5/22/2026 2:21:55 PM	21.0	70.8	0.0	8.2			0.3	0.0	144.2
CV-24057	5/11/2026 1:01:48 PM	29.8	57.3	0.0	12.9			0.5	0.0	139.5
CV-24057	5/11/2026 1:00:44 PM	29.8	57.3	0.0	13.0			0.5	0.0	139.4
CV-24058	5/22/2026 1:59:19 PM	39.5	44.4	0.0	16.1			0.9	0.0	105.7
CV-24058	5/11/2026 12:33:09 PM	40.2	44.8	0.0	14.9			0.9	0.0	109.8
CV-24059	5/22/2026 2:29:34 PM	34.5	55.8	0.0	9.7			0.6	0.0	114.1

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-24059	5/4/2026 9:02:50 AM	44.9	48.0	0.0	7.1			0.9	0.0	124.0
CV-24059	5/4/2026 9:01:40 AM	44.7	48.6	0.0	6.7			0.9	0.0	132.9
CV-24060	5/20/2026 1:29:27 PM	34.9	55.3	0.5	9.3			0.6	18.6	112.7
CV-24060	5/4/2026 9:39:35 AM	36.7	55.7	0.2	7.4			0.7	37.0	110.4
CV-24061	5/26/2026 11:38:49 AM	55.3	44.7	0.0	0.0			1.2	0.0	99.6
CV-24061	5/8/2026 12:59:31 PM	50.6	47.5	0.0	1.9			1.1	0.0	97.7
CV-24062	5/22/2026 11:10:33 AM	29.1	63.7	0.4	6.8			0.5	17.0	144.9
CV-24062	5/22/2026 11:08:48 AM	28.1	59.3	1.3	11.3			0.5	8.7	140.5
CV-24062	5/8/2026 1:05:26 PM	28.8	63.9	0.0	7.3			0.5	0.0	133.9
CV-24062	5/7/2026 8:17:00 AM					890				
CV-24062	5/7/2026 8:17:00 AM						80000			
CV-24062	5/4/2026 1:16:07 PM	28.3	66.3	0.0	5.4			0.4	0.0	145.5
CV-24062	5/4/2026 1:15:00 PM					1080				
CV-24062	5/4/2026 1:15:00 PM						56100			
CV-24063	5/28/2026 1:49:33 PM	6.8	84.2	0.0	9.0			0.1	0.0	184.1
CV-24063	5/20/2026 2:20:53 PM	5.1	80.1	0.0	14.8			0.1	0.0	171.8
CV-24063	5/14/2026 11:02:15 AM	11.4	83.8	0.0	4.8			0.1	0.0	172.8
CV-24063	5/14/2026 11:01:37 AM	10.7	83.6	0.0	5.7			0.1	0.0	174.9
CV-24063	5/14/2026 11:00:00 AM					3230				
CV-24063	5/12/2026 8:20:00 AM					2400				
CV-24063	5/12/2026 8:20:00 AM						120000			
CV-24063	5/4/2026 1:35:00 PM					2470				
CV-24063	5/4/2026 1:35:00 PM						71600			
CV-24063	5/4/2026 1:34:44 PM	3.7	86.5	0.0	9.8			0.0	0.0	183.9
CV-24063	5/4/2026 1:33:24 PM	3.7	84.4	0.6	11.3			0.0	18.8	182.4
CV-24064	5/28/2026 2:15:41 PM	1.9	79.7	0.0	18.4			0.0	0.0	165.5
CV-24064	5/27/2026 1:55:09 PM	3.2	80.3	0.0	16.5			0.0	0.0	191.7

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-24064	5/19/2026 1:40:00 PM					2470				
CV-24064	5/19/2026 1:36:22 PM	14.8	76.2	0.0	9.0			0.2	0.0	192.0
CV-24064	5/12/2026 8:15:00 AM						130000			
CV-24064	5/11/2026 10:07:41 AM	9.0	87.1	0.6	3.3			0.1	5.5	192.5
CV-24064	5/4/2026 9:10:00 AM					2680				
CV-24064	5/4/2026 9:10:00 AM						111000			
CV-24064	5/4/2026 9:09:33 AM	2.9	78.6	0.0	18.5			0.0	0.0	191.9
CV-24065-TP1	5/22/2026 10:27:26 AM	15.0	83.3	0.4	1.3			0.2	3.3	82.9
CV-24065-TP1	5/12/2026 8:15:00 AM					2000				
CV-24065-TP1	5/11/2026 1:07:25 PM	21.6	73.3	0.0	5.1			0.3	0.0	100.0
CV-24065-TP1	5/7/2026 8:35:00 AM					530				
CV-24065-TP1	5/7/2026 8:35:00 AM						9800			
CV-24066	5/19/2026 12:41:10 PM	25.0	45.2	0.0	29.8			0.6	0.0	109.2
CV-24066	5/11/2026 7:45:00 AM					390				
CV-24066	5/11/2026 7:45:00 AM						32000			
CV-24066	5/1/2026 10:40:05 AM	23.9	49.4	0.0	26.7			0.5	0.0	116.8
CV-24067	5/26/2026 2:27:02 PM	46.1	53.9	0.0	0.0			0.9	0.0	152.5
CV-24067	5/26/2026 2:26:30 PM	46.5	53.5	0.0	0.0			0.9	0.0	151.9
CV-24067	5/19/2026 8:57:43 AM	22.4	63.3	0.0	14.3			0.4	0.0	160.7
CV-24067	5/19/2026 8:55:05 AM	22.9	62.9	0.0	14.2			0.4	0.0	161.3
CV-24067	5/14/2026 11:37:11 AM	1.5	89.6	0.0	8.9			0.0	0.0	134.5
CV-24067	5/14/2026 11:35:44 AM	1.4	88.2	0.0	10.4			0.0	0.0	134.4
CV-24068	5/26/2026 12:08:57 PM	32.9	44.5	0.0	22.6			0.7	0.0	129.6
CV-24068	5/26/2026 12:06:40 PM	35.2	40.4	0.0	24.4			0.9	0.0	133.8
CV-24068	5/1/2026 11:18:00 AM	29.8	49.8	0.0	20.4			0.6	0.0	115.0
CV-24069	5/28/2026 9:36:45 AM	31.0	44.0	0.3	24.7			0.7	82.4	93.4
CV-24069	5/28/2026 9:35:46 AM	31.9	43.5	0.4	24.2			0.7	69.2	94.5
CV-24069	5/28/2026 9:30:09 AM	35.8	42.0	0.3	21.9			0.9	70.5	96.1
CV-24069	5/13/2026 8:20:00 AM					470				

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [ ]
CV-24069	5/13/2026 8:20:00 AM						40000			
CV-24069	5/4/2026 8:56:06 AM	40.8	48.8	0.0	10.4			0.8	0.0	93.2
CV-24070	5/20/2026 2:35:15 PM	11.4	77.9	0.0	10.7			0.1	0.0	136.2
CV-24070	5/20/2026 2:34:29 PM	10.7	77.6	0.0	11.7			0.1	0.0	136.2
CV-24070	5/20/2026 2:33:43 PM	10.2	74.7	0.0	15.1			0.1	0.0	133.9
CV-24070	5/7/2026 8:20:00 AM					1300				
CV-24070	5/7/2026 8:20:00 AM						110000			
CV-24070	5/4/2026 9:12:35 AM	22.4	63.4	0.0	14.2			0.4	0.0	130.4
CV-24070	5/4/2026 9:11:52 AM	23.2	65.8	1.9	9.1			0.4	4.8	131.6
CV-24071	5/20/2026 1:35:21 PM	42.5	52.0	0.0	5.5			0.8	0.0	123.3
CV-24071	5/7/2026 8:10:00 AM					190				
CV-24071	5/7/2026 8:10:00 AM						24000			
CV-24071	5/4/2026 9:43:04 AM	43.3	55.1	0.0	1.6			0.8	0.0	121.6
CV-24072	5/22/2026 2:05:23 PM	44.2	49.9	0.0	5.9			0.9	0.0	110.0
CV-24072	5/4/2026 2:18:34 PM	46.1	52.5	0.0	1.4			0.9	0.0	88.1
CV-24072	5/4/2026 2:17:08 PM	45.4	52.9	0.0	1.7			0.9	0.0	87.1
CV-24073-TP1	5/26/2026 8:45:28 AM	3.8	86.1	0.0	10.1			0.0	0.0	132.2
CV-24073-TP1	5/26/2026 8:40:41 AM	3.6	85.9	0.0	10.5			0.0	0.0	133.1
CV-24073-TP1	5/8/2026 1:15:17 PM	2.2	84.6	0.0	13.2			0.0	0.0	128.3
CV-24073-TP1	5/6/2026 2:09:30 PM	2.1	82.8	0.0	15.1			0.0	0.0	126.2
CV-24074	5/22/2026 11:17:05 AM	2.4	88.1	0.0	9.5			0.0	0.0	110.1
CV-24074	5/6/2026 2:14:23 PM	1.7	86.3	0.0	12.0			0.0	0.0	108.1
CV-24075-TP1	5/29/2026 4:03:35 PM	1.0	76.4	2.8	19.8			0.0	7.1	186.8
CV-24075-TP1	5/29/2026 4:02:17 PM	0.9	72.9	2.6	23.6			0.0	9.1	186.7

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-24075-TP1	5/11/2026 10:25:13 AM	10.2	84.1	0.8	4.9			0.1	6.1	109.5
CV-24075-TP1	5/4/2026 9:21:41 AM	1.0	82.0	0.8	16.2			0.0	20.3	187.2
CV-24075-TP1	5/4/2026 9:20:10 AM	1.0	81.8	0.8	16.4			0.0	20.5	61.7
CV-24075-TP1	5/4/2026 9:20:00 AM					2260				
CV-24075-TP1	5/4/2026 9:20:00 AM						114700			
CV-24076	5/27/2026 2:11:24 PM	18.4	77.4	0.0	4.2			0.2	0.0	171.8
CV-24076	5/19/2026 1:30:00 PM					1590				
CV-24076	5/19/2026 1:22:53 PM	33.9	66.0	0.0	0.1			0.5	0.0	167.7
CV-24076	5/14/2026 10:30:00 AM					1750				
CV-24076	5/14/2026 10:29:35 AM	33.9	66.1	0.0	0.0			0.5	0.0	174.4
CV-24076	5/4/2026 9:06:09 AM	10.7	68.0	0.2	21.1			0.2	105.5	176.8
CV-24076	5/4/2026 9:05:00 AM					1650				
CV-24076	5/4/2026 9:05:00 AM						62700			
CV-24077	5/28/2026 9:18:10 AM	10.1	65.9	0.0	24.0			0.2	0.0	146.7
CV-24077	5/28/2026 9:16:41 AM	12.2	59.5	0.0	28.3			0.2	0.0	143.6
CV-24077	5/20/2026 8:03:01 AM	19.8	53.5	0.0	26.7			0.4	0.0	142.7
CV-24077	5/11/2026 1:38:12 PM	18.6	77.2	0.0	4.2			0.2	0.0	146.5
CV-24077	5/7/2026 10:50:33 AM	7.9	86.4	0.1	5.6			0.1	56.0	149.0
CV-24077	5/7/2026 10:50:00 AM					2820				
CV-24077	5/7/2026 10:50:00 AM						72200			
CV-24077	5/1/2026 10:03:08 AM	4.6	87.3	0.0	8.1			0.1	0.0	151.0
CV-24077	5/1/2026 10:01:59 AM	5.0	82.0	0.0	13.0			0.1	0.0	150.8
CV-24078	5/19/2026 8:40:05 AM	30.6	56.6	0.0	12.9			0.5	0.0	130.6
CV-24078	5/19/2026 8:35:10 AM	31.3	56.0	0.0	12.7			0.6	0.0	130.8
CV-24078	5/19/2026 8:34:05 AM	31.8	55.9	0.0	12.3			0.6	0.0	130.6
CV-24078	5/19/2026 8:31:45 AM	31.4	56.2	0.0	12.5			0.6	0.0	132.3
CV-24078	5/1/2026 10:43:48 AM	29.1	62.6	0.0	8.3			0.5	0.0	126.2
CV-24079-TP8	5/26/2026 12:13:32 PM	37.3	49.5	0.0	13.2			0.8	0.0	137.7
CV-24079-TP8	5/26/2026 12:12:54 PM	37.0	50.4	0.1	12.5			0.7	125.0	137.8
CV-24079-TP8	5/11/2026 1:15:47 PM	52.0	48.0	0.0	0.0			1.1	0.0	140.1
CV-24079-TP8	5/7/2026 10:41:06 AM	2.3	87.0	0.0	10.7			0.0	0.0	170.5

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-24079-TP8	5/7/2026 10:40:00 AM					2450				
CV-24079-TP8	5/7/2026 10:40:00 AM						111700			
CV-24079-TP8	5/7/2026 10:38:33 AM	2.0	89.4	0.0	8.6			0.0	0.0	153.6
CV-24079-TP8	5/1/2026 11:22:57 AM	18.3	70.1	0.0	11.6			0.3	0.0	152.4
CV-24079-TP8	5/1/2026 11:22:12 AM	18.3	65.8	0.0	15.9			0.3	0.0	156.5
CV-24080	5/21/2026 9:36:06 AM	9.3	81.5	0.0	9.2			0.1	0.0	117.1
CV-24080	5/1/2026 11:09:29 AM	30.9	64.8	0.0	4.3			0.5	0.0	122.9
CV-24081-TP1	5/20/2026 2:26:51 PM	45.3	53.1	0.0	1.6			0.9	0.0	118.2
CV-24081-TP1	5/20/2026 2:25:55 PM	46.0	52.8	0.0	1.2			0.9	0.0	117.7
CV-24081-TP1	5/14/2026 10:40:33 AM	48.3	51.7	0.0	0.0			0.9	0.0	119.9
CV-24082	5/20/2026 11:24:26 AM	30.9	69.1	0.0	0.0			0.4	0.0	124.3
CV-24082	5/4/2026 10:11:50 AM	28.2	68.8	0.0	3.0			0.4	0.0	110.9
CV-24083	5/20/2026 1:53:17 PM	42.6	55.2	0.0	2.2			0.8	0.0	126.8
CV-24083	5/4/2026 9:58:27 AM	41.5	56.2	0.0	2.3			0.7	0.0	108.0
CV-24083	5/4/2026 9:56:08 AM	40.4	57.1	0.0	2.5			0.7	0.0	104.4
CV-24084-TP1	5/27/2026 10:49:57 AM	2.9	76.5	0.0	20.6			0.0	0.0	180.2
CV-24084-TP1	5/19/2026 10:24:00 AM	18.9	81.1	0.0	0.0			0.2	0.0	180.6
CV-24084-TP1	5/11/2026 1:05:39 PM	11.7	61.3	0.0	27.0			0.2	0.0	179.6
CV-24084-TP1	5/4/2026 2:08:40 PM	3.7	91.0	0.0	5.3			0.0	0.0	180.6
CV-24084-TP1	5/4/2026 2:05:00 PM					2420				
CV-24084-TP1	5/4/2026 2:05:00 PM						77400			
CV-24085	5/20/2026 10:07:30 AM	30.3	38.8	0.2	30.7			0.8	153.5	127.9
CV-24085	5/1/2026 10:47:32 AM	37.5	41.5	0.0	21.0			0.9	0.0	126.5
CV-24086	5/21/2026 9:49:26 AM	50.8	47.9	0.0	1.3			1.1	0.0	114.8
CV-24086	5/1/2026 11:00:38 AM	46.9	48.2	0.0	4.9			1.0	0.0	115.7
CV-24087	5/20/2026 1:36:05 PM	44.6	46.5	0.0	9.0			1.0	0.0	119.0
CV-24087	5/5/2026 10:43:05 AM	44.2	46.2	0.0	9.7			1.0	0.0	115.8

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-24088	5/28/2026 9:04:04 AM	41.7	53.9	0.0	4.4			0.8	0.0	99.1
CV-24088	5/4/2026 1:51:55 PM	38.8	59.1	0.0	2.1			0.7	0.0	100.0
CV-24089	5/20/2026 11:52:44 AM	4.1	7.2	17.8	70.9			0.6	4.0	99.0
CV-24089	5/20/2026 11:51:37 AM	2.5	7.4	18.4	71.7			0.3	3.9	99.1
CV-24089	5/4/2026 11:15:57 AM	1.8	5.2	19.0	74.0			0.3	3.9	71.8
CV-24089	5/4/2026 11:14:40 AM	6.5	13.0	15.6	64.9			0.5	4.2	73.5
CV-24090	5/20/2026 11:45:41 AM	38.1	60.9	0.0	1.0			0.6	0.0	120.1
CV-24090	5/11/2026 1:42:21 PM	40.4	50.2	0.0	9.4			0.8	0.0	113.1
CV-24090	5/6/2026 1:52:09 PM	28.5	69.1	0.0	2.4			0.4	0.0	115.8
CV-24091	5/21/2026 9:33:38 AM	55.6	44.4	0.0	0.0			1.3	0.0	99.3
CV-24091	5/4/2026 2:15:54 PM	52.7	44.3	0.2	2.8			1.2	14.0	77.1
CV-24092	5/6/2026 10:10:24 AM	51.5	43.3	0.0	5.2			1.2	0.0	120.5
CV-24093	5/22/2026 12:11:17 PM	45.0	55.0	0.0	0.0			0.8	0.0	119.2
CV-24093	5/1/2026 3:13:57 PM	42.6	57.4	0.0	0.0			0.7	0.0	118.5
CV-24094	5/22/2026 11:49:38 AM	10.9	80.1	2.0	7.0			0.1	3.5	88.9
CV-24094	5/22/2026 11:48:00 AM	7.9	59.7	6.8	25.6			0.1	3.8	88.3
CV-24094	5/1/2026 2:32:48 PM	15.0	77.5	2.1	5.4			0.2	2.6	88.4
CV-24095	5/28/2026 10:32:51 AM	2.9	83.5	0.0	13.6			0.0	0.0	179.1
CV-24095	5/28/2026 10:30:18 AM	2.3	83.9	0.3	13.5			0.0	45.0	179.6
CV-24095	5/20/2026 10:30:33 AM	27.6	72.4	0.0	0.0			0.4	0.0	178.6
CV-24095	5/14/2026 1:28:11 PM	3.5	81.5	0.0	15.0			0.0	0.0	178.8
CV-24095	5/13/2026 10:56:02 AM	2.2	71.8	2.8	23.2			0.0	8.3	178.3
CV-24095	5/13/2026 10:53:04 AM	3.2	82.3	0.0	14.5			0.0	0.0	177.8
CV-24095	5/6/2026 10:46:15 AM	19.2	80.8	0.0	0.0			0.2	0.0	176.2
CV-24095	5/6/2026 10:45:00 AM					2700				
CV-24095	5/6/2026 10:45:00 AM						108400			
CV-24095	5/6/2026 8:05:00 AM					2800				
CV-24095	5/6/2026 8:05:00 AM						160000			
CV-24096	5/20/2026 10:19:24 AM	37.6	55.4	0.3	6.7			0.7	22.3	95.9

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-24096	5/12/2026 9:25:00 AM	25.3	37.4	7.2	30.1			0.7	4.2	82.9
CV-24096	5/12/2026 9:22:51 AM	23.5	34.9	8.4	33.2			0.7	4.0	74.1
CV-24097	5/20/2026 10:29:27 AM	46.8	46.8	1.3	5.1			1.0	3.9	86.7
CV-24097	5/20/2026 10:28:10 AM	42.7	45.7	2.3	9.3			0.9	4.0	88.4
CV-24097	5/12/2026 9:16:39 AM	44.2	50.8	0.4	4.6			0.9	11.5	81.1
CV-24097	5/12/2026 9:13:02 AM	48.0	51.4	0.0	0.6			0.9	0.0	78.9
CV-24098	5/20/2026 10:43:25 AM	42.4	38.2	4.4	15.0			1.1	3.4	95.4
CV-24098	5/3/2026 11:01:16 AM	48.9	43.0	0.4	7.8			1.1	20.9	70.4
CV-24098	5/3/2026 11:00:24 AM	48.8	41.9	0.8	8.5			1.2	10.8	69.0
CV-24098	5/1/2026 10:01:03 AM	42.9	39.3	3.2	14.6			1.1	4.6	92.6
CV-24099	5/20/2026 10:48:09 AM	24.4	66.0	0.0	9.6			0.4	0.0	97.5
CV-24099	5/3/2026 10:28:51 AM	12.3	75.2	0.0	12.5			0.2	0.0	61.5
CV-24099	5/3/2026 10:28:19 AM	11.4	75.4	0.0	13.2			0.2	0.0	61.2
CV-24099	5/3/2026 10:27:26 AM	11.8	76.1	0.0	12.1			0.2	0.0	61.8
CV-24099	5/1/2026 10:08:04 AM	9.4	35.2	8.1	47.3			0.3	5.8	83.2
CV-24100	5/28/2026 10:02:06 AM	21.1	74.5	0.0	4.4			0.3	0.0	147.5
CV-24100	5/20/2026 10:01:19 AM	46.0	54.0	0.0	0.0			0.9	0.0	150.0
CV-24100	5/20/2026 10:00:42 AM	46.9	53.1	0.0	0.0			0.9	0.0	149.8
CV-24100	5/20/2026 9:37:52 AM	21.4	75.4	0.0	3.2			0.3	0.0	151.2
CV-24100	5/20/2026 9:36:36 AM	21.3	73.8	0.0	4.9			0.3	0.0	150.8
CV-24100	5/13/2026 10:42:49 AM	21.8	78.0	0.1	0.1			0.3	1.0	143.5
CV-24100	5/13/2026 10:41:16 AM	21.9	77.3	0.2	0.6			0.3	3.0	143.4
CV-24100	5/13/2026 8:25:00 AM					83				
CV-24100	5/13/2026 8:25:00 AM						8800			

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-24100	5/7/2026 11:06:06 AM	25.4	74.4	0.2	0.0			0.3	0.0	146.0
CV-24100	5/7/2026 11:05:00 AM					228				
CV-24100	5/7/2026 11:05:00 AM						8500			
CV-24100	5/7/2026 11:04:29 AM	25.0	75.0	0.0	0.0			0.3	0.0	144.3
CV-24100	5/1/2026 10:25:18 AM	19.0	80.8	0.1	0.1			0.2	1.0	143.7
CV-24101	5/20/2026 9:41:50 AM	41.4	54.8	0.0	3.8			0.8	0.0	112.0
CV-24101	5/12/2026 8:51:03 AM	38.8	53.6	1.3	6.3			0.7	4.8	112.6
CV-24101	5/6/2026 7:40:00 AM					0				
CV-24101	5/6/2026 7:40:00 AM						940			
CV-24101	5/1/2026 10:20:22 AM	42.6	57.1	0.3	0.0			0.7	0.0	106.9
CV-24102	5/19/2026 10:30:38 AM	47.8	50.6	0.0	1.6			0.9	0.0	103.0
CV-24102	5/4/2026 9:42:22 AM	46.9	48.6	0.0	4.5			1.0	0.0	89.0
CV-24103	5/20/2026 9:42:52 AM	51.2	46.6	0.3	1.9			1.1	6.3	95.8
CV-24103	5/4/2026 9:28:18 AM	45.1	47.3	0.0	7.6			1.0	0.0	95.3
CV-24104	5/20/2026 12:16:58 PM	38.2	61.8	0.0	0.0			0.6	0.0	96.4
CV-24104	5/4/2026 9:39:11 AM	47.2	49.7	0.0	3.1			0.9	0.0	93.5
CV-24105	5/20/2026 11:35:42 AM	49.1	47.9	0.0	3.0			1.0	0.0	109.2
CV-24105	5/4/2026 9:49:47 AM	48.8	44.1	0.0	7.1			1.1	0.0	102.2
CV-24106	5/28/2026 12:51:23 PM	41.2	35.5	0.0	23.3			1.2	0.0	127.7
CV-24106	5/20/2026 2:33:03 PM	42.1	41.2	0.0	16.7			1.0	0.0	129.0
CV-24106	5/8/2026 11:07:42 AM	45.0	41.9	0.0	13.1			1.1	0.0	126.9
CV-24107	5/4/2026 11:30:05 AM	49.4	44.0	0.0	6.6			1.1	0.0	121.4
CV-24108	5/28/2026 12:33:54 PM	52.8	41.3	0.0	5.9			1.3	0.0	128.9
CV-24108	5/4/2026 1:40:16 PM	51.4	42.1	0.0	6.5			1.2	0.0	128.7
CV-24109	5/4/2026 11:58:26 AM	31.3	38.9	1.2	28.6			0.8	23.8	104.9
CV-24110	5/1/2026 10:54:33 AM	41.0	52.3	0.0	6.7			0.8	0.0	128.1
CV-24111	5/1/2026 11:14:00 AM	46.5	44.4	0.0	9.1			1.0	0.0	111.1
CV-24112	5/1/2026 11:04:34 AM	45.6	39.1	0.1	15.2			1.2	152.0	128.0
CV-24114	5/5/2026 2:47:36 PM	54.3	44.2	0.0	1.5			1.2	0.0	119.9
CV-24116	5/11/2026 9:58:53 AM	46.5	45.0	0.2	8.3			1.0	41.5	125.3
CV-24117	5/28/2026 12:44:53 PM	45.1	40.4	0.0	14.5			1.1	0.0	100.9
CV-24117	5/4/2026 10:48:48 AM	44.0	42.9	0.0	13.1			1.0	0.0	90.5
CV-24118	5/11/2026 1:37:44 PM	24.3	68.8	0.0	6.9			0.4	0.0	129.0

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-24119	5/8/2026 2:33:20 PM	47.0	46.0	0.0	7.0			1.0	0.0	144.0
CV-24119	5/8/2026 2:32:34 PM	47.6	45.4	0.0	7.0			1.0	0.0	144.4
CV-24119	5/7/2026 10:38:27 AM	42.1	47.6	0.0	10.3			0.9	0.0	135.9
CV-24119	5/7/2026 10:35:25 AM	42.2	45.0	0.0	12.8			0.9	0.0	137.1
CV-24120	5/26/2026 2:15:09 PM	4.8	80.5	0.6	14.1			0.1	23.5	88.0
CV-24120	5/11/2026 10:28:50 AM	4.7	71.6	0.4	23.4			0.1	58.4	98.1
CV-24120	5/4/2026 8:00:00 AM						110000			
CV-24121	5/26/2026 2:08:29 PM	0.6	5.5	20.0	73.9			0.1	3.7	75.9
CV-24121	5/11/2026 10:33:56 AM	2.8	15.0	16.1	66.2			0.2	4.1	101.4
CV-24121	5/11/2026 10:33:18 AM	2.7	15.3	16.4	65.6			0.2	4.0	101.3
CV-24121	5/4/2026 7:55:00 AM						2700			
CV-24122	5/29/2026 9:40:41 AM	35.0	40.3	4.3	20.4			0.9	4.7	81.1
CV-24122	5/29/2026 9:33:20 AM	27.0	31.6	7.9	33.5			0.9	4.2	76.1
CV-24122	5/6/2026 10:31:06 AM	42.7	42.2	3.2	11.9			1.0	3.7	84.9
CV-24122	5/4/2026 8:20:00 AM						9100			
CV-24123	5/28/2026 11:46:50 AM	37.2	57.7	0.0	5.1			0.6	0.0	116.6
CV-24123	5/28/2026 11:46:25 AM	38.4	57.2	0.0	4.4			0.7	0.0	116.1
CV-24123	5/15/2026 11:28:22 AM	31.9	66.2	0.0	1.9			0.5	0.0	113.9
CV-24123	5/15/2026 11:24:46 AM	26.4	69.8	0.0	3.8			0.4	0.0	84.7
CV-24123	5/14/2026 10:54:34 AM	32.0	67.3	0.0	0.7			0.5	0.0	117.2
CV-24123	5/14/2026 10:53:53 AM	30.9	69.1	0.0	0.0			0.4	0.0	116.7
CV-24124	5/29/2026 11:28:31 AM	5.9	81.4	0.2	12.5			0.1	62.5	127.0
CV-24125-TP2	5/26/2026 1:56:27 PM	28.5	67.0	1.1	3.4			0.4	3.1	99.9

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-24125-TP2	5/13/2026 7:55:00 AM					30				
CV-24125-TP2	5/13/2026 7:55:00 AM						1300			
CV-24126	5/26/2026 10:58:38 AM	4.1	73.0	0.0	22.9			0.1	0.0	186.7
CV-24126	5/22/2026 12:29:20 PM	1.6	76.9	0.0	21.5			0.0	0.0	188.7
CV-24126	5/22/2026 12:28:40 PM	1.3	75.6	0.0	23.1			0.0	0.0	188.3
CV-24126	5/18/2026 10:50:00 AM					4310				
CV-24126	5/18/2026 10:44:28 AM	14.0	77.0	0.0	9.0			0.2	0.0	186.7
CV-24126	5/18/2026 10:43:37 AM	21.8	71.7	0.0	6.5			0.3	0.0	186.3
CV-24126	5/12/2026 10:30:00 AM					2330				
CV-24126	5/12/2026 10:28:41 AM	20.1	79.9	0.0	0.0			0.3	0.0	188.0
CV-24126	5/4/2026 2:50:00 PM					3200				
CV-24126	5/4/2026 2:50:00 PM						135800			
CV-24126	5/4/2026 2:40:40 PM	1.9	85.1	0.0	13.0			0.0	0.0	186.0
CV-24127	5/7/2026 10:22:55 AM	2.9	83.5	0.0	13.6			0.0	0.0	141.8
CV-24127	5/7/2026 10:21:43 AM	2.7	82.2	0.0	15.1			0.0	0.0	141.6
CV-24127	5/7/2026 10:20:00 AM					5180				
CV-24127	5/7/2026 10:20:00 AM						152600			
CV-24127	5/4/2026 8:15:00 AM						160000			
CV-24128	5/26/2026 2:25:15 PM	33.4	51.7	1.2	13.7			0.6	11.4	91.8
CV-24128	5/13/2026 7:50:00 AM					210				
CV-24128	5/13/2026 7:50:00 AM						11000			
CV-24128	5/8/2026 9:33:23 AM	34.4	43.9	1.2	20.5			0.8	17.1	99.5
CV-24129	5/26/2026 1:33:50 PM	41.4	57.8	0.3	0.5			0.7	1.7	119.2
CV-24129	5/8/2026 9:24:27 AM	45.2	52.9	0.0	1.9			0.9	0.0	121.8
CV-24130	5/26/2026 1:42:41 PM	20.1	69.3	0.0	10.6			0.3	0.0	108.8
CV-24131	5/29/2026 1:47:07 PM	45.4	49.7	0.2	4.7			0.9	23.5	120.4
CV-24132	5/6/2026 10:15:34 AM	52.7	44.1	0.0	3.2			1.2	0.0	129.2
CV-24133	5/7/2026 9:28:04 AM	51.8	40.2	0.0	8.0			1.3	0.0	121.5
CV-24134-TP1	5/26/2026 10:55:47 AM	23.2	68.7	0.0	8.1			0.3	0.0	151.0
CV-24134-TP1	5/18/2026 10:45:00 AM					3300				
CV-24134-TP1	5/18/2026 10:39:38 AM	33.1	64.1	0.0	2.8			0.5	0.0	151.5
CV-24134-TP1	5/12/2026 10:35:00 AM					2470				

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-24134-TP1	5/12/2026 10:33:32 AM	38.2	61.8	0.0	0.0			0.6	0.0	150.6
CV-24134-TP1	5/12/2026 10:32:12 AM	36.7	63.3	0.0	0.0			0.6	0.0	150.1
CV-24134-TP1	5/11/2026 2:33:48 PM	16.6	73.9	0.0	9.5			0.2	0.0	146.9
CV-24134-TP1	5/11/2026 2:29:03 PM	18.3	65.8	0.0	15.9			0.3	0.0	146.2
CV-24134-TP1	5/7/2026 1:15:00 PM					1220				
CV-24134-TP1	5/7/2026 1:14:04 PM	22.6	74.7	0.0	2.7			0.3	0.0	150.0
CV-24135	5/11/2026 2:17:55 PM	24.6	71.2	0.0	4.2			0.3	0.0	140.6
CV-24135	5/11/2026 2:15:34 PM	20.1	74.1	0.0	5.8			0.3	0.0	139.7
CV-24136	5/11/2026 11:29:51 AM	30.1	46.4	0.0	23.5			0.6	0.0	125.7
CV-24137	5/4/2026 1:08:31 PM	25.3	54.6	0.0	20.1			0.5	0.0	75.0
CV-24137	5/4/2026 1:07:02 PM	26.1	54.1	0.0	19.8			0.5	0.0	73.4
CV-24138	5/28/2026 9:03:38 AM	0.3	0.2	21.5	78.0			1.5	3.6	95.8
CV-24138	5/28/2026 9:02:31 AM	0.3	0.2	21.6	77.9			1.5	3.6	96.3
CV-24138	5/13/2026 1:14:42 PM	2.4	68.4	0.0	29.2			0.0	0.0	131.5
CV-24138	5/6/2026 11:00:00 AM					1010				
CV-24138	5/6/2026 11:00:00 AM						171800			
CV-24138	5/6/2026 10:58:19 AM	17.2	74.8	0.0	8.0			0.2	0.0	158.7
CV-24138	5/5/2026 8:15:00 AM					820				
CV-24138	5/5/2026 8:15:00 AM						210000			
CV-24139	5/28/2026 9:08:34 AM	4.1	58.6	4.7	32.6			0.1	6.9	127.4
CV-24139	5/15/2026 8:22:50 AM	0.7	30.7	13.2	55.4			0.0	4.2	144.2
CV-24139	5/15/2026 8:12:50 AM	0.1	3.3	20.8	75.8			0.0	3.6	111.7
CV-24139	5/5/2026 8:10:00 AM					630				
CV-24139	5/5/2026 8:10:00 AM						180000			
CV-24140	5/28/2026 10:52:29 AM	1.9	72.1	0.4	25.6			0.0	64.0	171.1
CV-24140	5/28/2026 10:50:34 AM	1.9	75.0	0.0	23.1			0.0	0.0	168.4
CV-24140	5/20/2026 1:28:20 PM	5.1	71.3	0.2	23.4			0.1	117.0	148.6
CV-24140	5/20/2026 1:26:41 PM	3.6	73.1	0.3	23.0			0.0	76.7	146.3
CV-24140	5/13/2026 1:18:30 PM	2.2	69.8	0.0	28.0			0.0	0.0	156.3

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-24140	5/6/2026 11:05:00 AM					1350				
CV-24140	5/6/2026 11:05:00 AM						203000			
CV-24140	5/6/2026 11:04:58 AM	14.4	78.6	0.0	7.0			0.2	0.0	163.7
CV-24140	5/5/2026 8:05:00 AM					1000				
CV-24140	5/5/2026 8:05:00 AM						210000			
CV-24141	5/28/2026 9:31:07 AM	10.8	6.8	18.3	64.1			1.6	3.5	66.1
CV-24141	5/28/2026 9:30:26 AM	10.7	6.5	18.4	64.4			1.6	3.5	65.6
CV-24141	5/5/2026 7:45:00 AM					94				
CV-24141	5/5/2026 7:45:00 AM						1200			
CV-24141	5/1/2026 8:57:18 AM	20.8	33.2	5.1	40.9			0.6	8.0	79.1
CV-24142	5/28/2026 10:41:54 AM	2.3	72.2	0.6	24.9			0.0	41.5	100.6
CV-24142	5/28/2026 10:40:43 AM	2.3	72.4	0.6	24.7			0.0	41.2	100.2
CV-24142	5/20/2026 1:14:55 PM	2.6	59.0	3.6	34.8			0.0	9.7	152.3
CV-24142	5/20/2026 1:02:37 PM	3.8	58.4	2.6	35.2			0.1	13.5	153.3
CV-24142	5/15/2026 8:03:40 AM	0.0	0.2	21.9	77.9			0.0	3.6	174.7
CV-24142	5/15/2026 7:59:13 AM	0.0	1.3	21.7	77.0			0.0	3.5	174.3
CV-24142	5/14/2026 8:35:00 AM					2300				
CV-24142	5/6/2026 8:10:00 AM					1500				
CV-24142	5/6/2026 8:10:00 AM						120000			
CV-24143	5/28/2026 9:20:03 AM	4.3	24.2	15.2	56.3			0.2	3.7	72.5
CV-24143	5/28/2026 9:19:15 AM	4.2	23.6	15.2	57.0			0.2	3.8	73.4
CV-24143	5/5/2026 7:55:00 AM					460				
CV-24143	5/5/2026 7:55:00 AM						61000			
CV-24143	5/1/2026 2:16:44 PM	0.7	23.5	14.9	60.9			0.0	4.1	96.9
CV-24143	5/1/2026 2:15:01 PM	0.7	23.9	14.4	61.0			0.0	4.2	95.5
CV-24144	5/20/2026 10:35:16 AM	56.8	40.5	0.0	2.7			1.4	0.0	103.0
CV-24144	5/12/2026 9:03:44 AM	58.5	40.0	0.0	1.5			1.5	0.0	79.1
CV-24145	5/26/2026 2:12:30 PM	11.7	62.3	4.4	21.6			0.2	4.9	99.2
CV-24145	5/18/2026 2:54:25 PM	21.9	73.1	0.0	5.0			0.3	0.0	145.7
CV-24145	5/18/2026 2:45:00 PM					2450				

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-24145	5/18/2026 2:38:58 PM	20.7	71.9	0.0	7.4			0.3	0.0	146.3
CV-24145	5/12/2026 2:40:29 PM	20.6	70.7	0.0	8.7			0.3	0.0	162.9
CV-24145	5/12/2026 2:34:47 PM	17.1	74.6	0.5	7.8			0.2	15.6	162.6
CV-24145	5/12/2026 2:32:19 PM	17.0	66.9	1.2	14.9			0.3	12.4	160.8
CV-24145	5/12/2026 2:15:00 PM					915				
CV-24145	5/5/2026 1:25:00 PM					2480				
CV-24145	5/5/2026 1:25:00 PM						165900			
CV-24145	5/5/2026 1:22:41 PM	8.2	81.3	0.0	10.5			0.1	0.0	170.8
CV-24146	5/28/2026 10:15:05 AM	49.7	47.0	0.0	3.3			1.1	0.0	106.1
CV-24146	5/28/2026 10:14:14 AM	50.3	46.6	0.0	3.1			1.1	0.0	108.1
CV-24146	5/11/2026 9:52:43 AM	49.8	45.5	0.0	4.6			1.1	0.0	115.1
CV-24147	5/28/2026 11:28:34 AM	55.9	37.9	0.6	5.6			1.5	9.3	102.7
CV-24147	5/26/2026 9:21:12 AM	55.0	41.9	0.9	2.2			1.3	2.4	100.4
CV-24147	5/14/2026 2:08:02 PM	51.2	42.5	1.5	4.8			1.2	3.2	108.2
CV-24147	5/11/2026 10:06:39 AM	52.6	41.4	0.2	5.8			1.3	29.0	110.9
CV-24147	5/11/2026 10:05:05 AM	55.0	41.0	0.0	4.0			1.3	0.0	110.0
CV-24147	5/11/2026 10:02:23 AM	54.5	41.3	0.0	4.2			1.3	0.0	108.8
CV-24148	5/27/2026 1:49:59 PM	2.4	83.0	0.0	14.6			0.0	0.0	169.1
CV-24148	5/19/2026 1:50:00 PM					2320				
CV-24148	5/19/2026 1:44:57 PM	22.2	77.8	0.0	0.0			0.3	0.0	171.5
CV-24148	5/19/2026 1:43:50 PM	17.6	77.8	0.2	4.4			0.2	22.0	173.0
CV-24148	5/11/2026 10:02:23 AM	5.4	88.3	0.1	6.2			0.1	62.0	178.1
CV-24148	5/4/2026 9:31:25 AM	0.8	80.7	0.0	18.5			0.0	0.0	180.4
CV-24148	5/4/2026 9:30:00 AM					3480				
CV-24148	5/4/2026 9:30:00 AM						106200			
CV-24149	5/28/2026 12:48:18 PM	3.7	81.4	2.4	12.5			0.0	5.2	82.2
CV-24149	5/6/2026 2:58:21 PM	3.5	86.0	0.5	10.0			0.0	20.0	96.0
CV-24150	5/22/2026 11:53:52 AM	41.7	58.3	0.0	0.0			0.7	0.0	111.7
CV-24150	5/1/2026 10:15:37 AM	45.9	52.7	0.3	1.1			0.9	3.7	111.1

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [ ]
CV-24151	5/21/2026 1:59:13 PM	50.6	49.4	0.0	0.0			1.0	0.0	103.2
CV-24151	5/6/2026 2:05:59 PM	48.0	48.0	0.1	3.9			1.0	39.0	87.9
CV-24152	5/26/2026 8:32:21 AM	25.4	70.6	0.0	4.0			0.4	0.0	129.7
CV-24152	5/26/2026 8:31:06 AM	25.4	68.9	0.0	5.7			0.4	0.0	130.3
CV-24152	5/6/2026 2:21:42 PM	20.4	72.7	0.0	6.9			0.3	0.0	131.4
CV-24152	5/6/2026 2:21:09 PM	20.2	74.2	0.0	5.6			0.3	0.0	130.7
CV-24153	5/22/2026 11:40:23 AM	41.3	54.6	0.0	4.1			0.8	0.0	114.9
CV-24153	5/1/2026 3:03:06 PM	49.9	50.1	0.0	0.0			1.0	0.0	104.2
CV-24153	5/1/2026 3:02:03 PM	51.9	48.1	0.1				1.1		98.8
CV-24154	5/22/2026 11:58:09 AM	44.0	53.0	0.3	2.7			0.8	9.0	112.9
CV-24154	5/1/2026 3:20:22 PM	47.7	52.0	0.3	0.0			0.9	0.0	104.1
CV-24155	5/26/2026 8:18:02 AM	34.1	65.9	0.0	0.0			0.5	0.0	119.1
CV-24155	5/1/2026 3:09:53 PM	32.8	67.2	0.0	0.0			0.5	0.0	118.8
CV-24155	5/1/2026 3:08:32 PM	32.0	68.0	0.0	0.0			0.5	0.0	98.2
CV-24156	5/22/2026 2:00:28 PM	43.2	52.5	0.2	4.1			0.8	20.5	124.0
CV-24156	5/4/2026 2:11:53 PM	42.8	54.5	0.0	2.7			0.8	0.0	122.5
CV-24157	5/21/2026 2:09:04 PM	48.6	51.4	0.0	0.0			0.9	0.0	105.5
CV-24157	5/21/2026 2:08:15 PM	48.7	51.3	0.0	0.0			0.9	0.0	104.5
CV-24157	5/4/2026 2:00:15 PM	47.2	50.8	0.0	2.0			0.9	0.0	94.3
CV-24158	5/21/2026 10:58:26 AM	43.6	56.3	0.1	0.0			0.8	0.0	128.3
CV-24158	5/6/2026 10:59:56 AM	38.9	61.1	0.0	0.0			0.6	0.0	125.4
CV-24159	5/21/2026 9:02:31 AM	41.8	58.2	0.0	0.0			0.7	0.0	131.8
CV-24159	5/21/2026 9:01:50 AM	42.0	58.0	0.0	0.0			0.7	0.0	131.7
CV-24159	5/6/2026 10:49:41 AM	42.9	54.6	0.0	2.5			0.8	0.0	126.4
CV-24160	5/22/2026 12:06:28 PM	46.7	53.1	0.1	0.1			0.9	1.0	127.4

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [ ]
CV-24160	5/6/2026 12:39:52 PM	46.7	52.2	0.0	1.1			0.9	0.0	125.0
CV-24160	5/6/2026 10:29:54 AM	43.4	54.3	0.0	2.3			0.8	0.0	122.4
CV-24161	5/6/2026 10:20:39 AM	20.3	76.5	0.0	3.2			0.3	0.0	111.1
CV-24161	5/6/2026 10:19:18 AM	18.6	76.5	0.0	4.9			0.2	0.0	104.4
CV-24162	5/4/2026 12:02:44 PM	37.0	52.0	0.5	10.5			0.7	21.0	86.4
CV-24163	5/1/2026 2:33:25 PM	33.2	57.8	0.0	9.0			0.6	0.0	129.6
CV-24163	5/1/2026 2:32:24 PM	32.1	57.6	0.0	10.3			0.6	0.0	132.2
CV-24164	5/20/2026 2:08:15 PM	33.5	65.0	0.0	1.5			0.5	0.0	131.9
CV-24164	5/20/2026 2:06:56 PM	35.4	64.6	0.0	0.0			0.5	0.0	132.3
CV-24164	5/20/2026 11:14:31 AM	40.0	60.0	0.0	0.0			0.7	0.0	100.1
CV-24164	5/4/2026 10:23:58 AM	27.2	72.4	0.0	0.4			0.4	0.0	126.8
CV-24165	5/20/2026 11:18:42 AM	42.5	57.5	0.0	0.0			0.7	0.0	121.3
CV-24165	5/14/2026 11:24:07 AM	21.4	78.6	0.0	0.0			0.3	0.0	132.5
CV-24165	5/14/2026 11:22:03 AM	20.9	78.1	0.0	1.0			0.3	0.0	134.4
CV-24166	5/21/2026 9:08:04 AM	52.8	47.2	0.0	0.0			1.1	0.0	123.3
CV-24166	5/20/2026 11:21:55 AM	45.9	54.1	0.0	0.0			0.8	0.0	128.8
CV-24166	5/6/2026 10:54:07 AM	49.3	46.5	0.0	4.2			1.1	0.0	106.6
CV-24167	5/28/2026 8:45:13 AM	47.8	39.6	0.0	12.6			1.2	0.0	110.2
CV-24167	5/6/2026 9:59:13 AM	50.1	40.3	0.2	9.4			1.2	47.0	112.3
CV-24168	5/28/2026 8:59:25 AM	26.5	49.6	2.3	21.6			0.5	9.2	104.7
CV-24168	5/6/2026 10:55:15 AM	28.6	55.8	2.7	12.9			0.5	4.8	111.0
CV-24169	5/20/2026 11:11:16 AM	41.2	58.8	0.0	0.0			0.7	0.0	100.1
CV-24169	5/4/2026 10:19:18 AM	32.8	64.3	0.0	2.9			0.5	0.0	115.5
CV-24170	5/21/2026 9:20:08 AM	9.5	82.3	0.0	8.2			0.1	0.0	126.9
CV-24170	5/6/2026 8:37:17 AM	14.6	81.3	0.0	4.1			0.2	0.0	125.8
CV-24170	5/1/2026 10:56:54 AM	15.1	76.1	0.0	8.8			0.2	0.0	126.7
CV-24171	5/21/2026 9:23:58 AM	53.8	46.2	0.0	0.0			1.2	0.0	127.3
CV-24171	5/6/2026 10:03:52 AM	52.3	45.2	0.0	2.5			1.2	0.0	123.2
CV-24172	5/21/2026 10:00:21 AM	42.7	41.8	2.5	13.0			1.0	5.2	121.6

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-24172	5/4/2026 2:28:48 PM	35.4	35.6	3.6	25.4			1.0	7.1	116.2
CV-24173	5/21/2026 10:06:44 AM	49.1	41.3	0.9	8.7			1.2	9.7	115.4
CV-24173	5/6/2026 1:00:35 PM	46.2	40.1	0.9	12.8			1.2	14.2	113.5
CV-24174	5/21/2026 10:15:48 AM	26.6	50.1	0.0	23.3			0.5	0.0	111.2
CV-24174	5/11/2026 1:20:08 PM	30.3	40.0	0.0	29.7			0.8	0.0	111.2
CV-24175	5/21/2026 10:19:57 AM	25.7	63.6	0.0	10.7			0.4	0.0	121.2
CV-24175	5/5/2026 1:28:08 PM	26.9	54.6	0.0	18.5			0.5	0.0	120.8
CV-24175	5/5/2026 1:26:42 PM	25.7	55.1	0.0	19.3			0.5	0.0	121.6
CV-24175	5/5/2026 1:21:04 PM	23.8	56.4	0.4	19.5			0.4	52.6	121.9
CV-24175	5/5/2026 1:13:21 PM	24.1	57.2	0.3	18.4			0.4	57.6	122.2
CV-24176	5/20/2026 10:16:41 AM	23.0	72.2	0.5	4.3			0.3	8.6	130.6
CV-24176	5/20/2026 10:14:10 AM	29.7	60.2	0.0	10.1			0.5	0.0	132.4
CV-24176	5/8/2026 11:05:11 AM	17.9	80.5	0.0	1.6			0.2	0.0	137.8
CV-24176	5/8/2026 11:03:01 AM	15.5	81.6	0.0	2.9			0.2	0.0	130.2
CV-24177	5/20/2026 8:06:52 AM	13.9	42.9	4.7	38.5			0.3	8.2	131.7
CV-24177	5/20/2026 7:56:33 AM	11.9	24.8	8.5	54.8			0.5	6.4	135.2
CV-24177	5/8/2026 11:20:50 AM	16.9	28.3	5.5	49.3			0.6	9.0	126.2
CV-24177	5/8/2026 11:19:26 AM	17.2	27.3	5.5	50.0			0.6	9.1	126.8
CV-24178	5/20/2026 12:02:57 PM	28.7	53.7	0.0	17.6			0.5	0.0	130.5
CV-24178	5/20/2026 12:01:45 PM	29.7	54.5	0.0	15.8			0.5	0.0	131.6
CV-24178	5/8/2026 10:58:25 AM	31.5	56.1	0.0	12.4			0.6	0.0	129.3
CV-24179	5/20/2026 9:55:47 AM	27.8	51.1	0.0	21.1			0.5	0.0	130.2
CV-24179	5/4/2026 1:09:48 PM	17.5	69.0	0.0	13.4			0.3	0.0	123.9
CV-24179	5/4/2026 1:08:00 PM	14.4	72.0	0.0	13.6			0.2	0.0	113.0
CV-24179	5/4/2026 1:03:56 PM	13.3	67.7	2.4	16.5			0.2	6.8	77.6
CV-24180	5/20/2026 10:03:08 AM	26.5	38.5	0.2	34.8			0.7	174.0	126.6
CV-24180	5/8/2026 10:53:15 AM	24.8	40.0	0.0	35.2			0.6	0.0	124.7
CV-24181	5/20/2026 12:05:54 PM	37.8	62.1	0.0	0.1			0.6	0.0	111.7

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-24181	5/4/2026 11:08:54 AM	35.3	53.6	0.0	11.1			0.7	0.0	107.1
CV-24182	5/22/2026 10:34:25 AM	38.9	55.3	0.5	5.3			0.7	10.6	112.1
CV-24182	5/4/2026 11:12:00 AM	37.1	54.9	0.0	8.0			0.7	0.0	99.1
CV-24183	5/20/2026 11:42:38 AM	48.3	51.6	0.1	0.0			0.9	0.0	107.0
CV-24183	5/4/2026 11:26:46 AM	48.9	47.5	0.0	3.6			1.0	0.0	84.8
CV-24184	5/28/2026 1:18:12 PM	22.4	29.5	5.7	42.4			0.8	7.4	135.6
CV-24184	5/28/2026 1:16:04 PM	23.0	31.0	5.7	40.3			0.7	7.1	139.9
CV-24184	5/20/2026 11:25:50 AM	38.1	61.9	0.0	0.0			0.6	0.0	133.7
CV-24184	5/20/2026 11:24:32 AM	37.1	62.9	0.0	0.0			0.6	0.0	132.0
CV-24184	5/20/2026 11:22:55 AM	39.0	61.0	0.0	0.0			0.6	0.0	118.5
CV-24184	5/4/2026 1:19:41 PM	33.3	32.5	4.6	29.6			1.0	6.4	133.2
CV-24184	5/4/2026 1:18:22 PM	34.6	33.2	4.3	27.9			1.0	6.5	135.0
CV-24185	5/20/2026 2:14:16 PM	38.2	59.9	0.0	1.9			0.6	0.0	128.3
CV-24185	5/20/2026 2:12:58 PM	36.2	63.8	0.0	0.0			0.6	0.0	127.0
CV-24185	5/4/2026 1:26:49 PM	39.0	59.6	0.0	1.4			0.7	0.0	123.2
CV-24186	5/20/2026 2:18:02 PM	44.2	48.6	0.1	7.1			0.9	71.0	128.5
CV-24186	5/4/2026 2:56:41 PM	43.6	44.7	0.4	11.3			1.0	28.3	125.3
CV-24187	5/19/2026 10:36:55 AM	48.1	47.8	0.0	4.0			1.0	0.0	125.1
CV-24187	5/4/2026 10:28:37 AM	48.5	47.7	0.0	3.8			1.0	0.0	124.2
CV-24187	5/4/2026 10:27:50 AM	48.9	47.9	0.0	3.2			1.0	0.0	123.4
CV-24187	5/4/2026 10:19:29 AM	49.4	47.4	0.0	3.2			1.0	0.0	67.2
CV-24188	5/20/2026 12:45:56 PM	50.8	43.7	0.0	5.5			1.2	0.0	118.9
CV-24188	5/20/2026 8:59:37 AM	51.4	43.2	0.0	5.4			1.2	0.0	118.0
CV-24188	5/4/2026 9:36:30 AM	50.4	43.9	0.0	5.7			1.1	0.0	117.7
CV-24188	5/4/2026 9:34:45 AM	50.7	43.6	0.0	5.7			1.2	0.0	117.1
CV-24189	5/20/2026 8:49:58 AM	47.3	39.8	0.0	12.9			1.2	0.0	118.0
CV-24189	5/4/2026 9:28:20 AM	49.2	40.2	0.0	10.6			1.2	0.0	117.5
CV-24190	5/19/2026 10:21:44 AM	51.1	47.0	0.0	1.9			1.1	0.0	123.1
CV-24190	5/4/2026 10:10:47 AM	51.3	44.4	0.0	4.3			1.2	0.0	122.5
CV-24192	5/22/2026 10:15:13 AM	55.3	44.2	0.0	0.5			1.3	0.0	115.2
CV-24192	5/4/2026 10:02:40 AM	52.3	43.0	0.0	4.7			1.2	0.0	117.5
CV-24192	5/4/2026 10:01:48 AM	52.5	43.0	0.0	4.6			1.2	0.0	116.9
CV-24192	5/4/2026 9:58:01 AM	53.4	42.3	0.0	4.3			1.3	0.0	116.3
CV-24193	5/19/2026 2:15:47 PM	51.4	42.5	0.0	6.2			1.2	0.0	116.3

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [ ]
CV-24193	5/4/2026 9:13:38 AM	51.8	43.2	0.0	5.0			1.2	0.0	112.5
CV-24194	5/20/2026 12:10:04 PM	39.7	37.1	4.6	18.6			1.1	4.0	103.7
CV-24194	5/5/2026 1:47:55 PM	53.0	43.0	0.0	4.0			1.2	0.0	92.6
CV-24194	5/4/2026 9:33:10 AM	52.2	43.8	0.0	4.0			1.2	0.0	89.4
CV-24195	5/28/2026 1:01:56 PM	50.2	44.6	0.0	5.2			1.1	0.0	118.2
CV-24195	5/20/2026 12:23:03 PM	50.0	49.9	0.0	0.1			1.0	0.0	118.2
CV-24195	5/4/2026 9:46:22 AM	50.0	46.1	0.0	3.9			1.1	0.0	114.9
CV-24196	5/28/2026 12:55:54 PM	49.2	44.1	0.0	6.7			1.1	0.0	123.3
CV-24196	5/20/2026 11:31:51 AM	50.0	50.0	0.0	0.0			1.0	0.0	125.3
CV-24196	5/4/2026 11:32:25 AM	48.7	47.4	0.0	3.9			1.0	0.0	122.2
CV-24197	5/22/2026 10:52:22 AM	51.6	44.6	0.0	3.8			1.2	0.0	124.0
CV-24197	5/8/2026 11:18:02 AM	52.5	45.3	0.0	2.2			1.2	0.0	125.3
CV-24198	5/22/2026 10:50:58 AM	45.6	43.1	0.0	11.3			1.1	0.0	118.4
CV-24198	5/8/2026 10:50:53 AM	53.3	42.9	0.0	3.8			1.2	0.0	117.4
CV-24199	5/22/2026 10:41:08 AM	48.4	46.0	0.0	5.6			1.1	0.0	128.3
CV-24199	5/8/2026 10:55:45 AM	52.5	44.5	0.0	3.0			1.2	0.0	127.3
CV-24200	5/22/2026 9:57:47 AM	51.8	42.6	0.0	5.6			1.2	0.0	118.3
CV-24200	5/6/2026 2:43:38 PM	52.4	41.9	0.1	5.6			1.3	56.0	117.6
CV-24201	5/22/2026 10:05:48 AM	49.1	40.5	0.2	10.2			1.2	51.0	119.7
CV-24201	5/6/2026 3:11:02 PM	48.8	43.1	0.2	7.9			1.1	39.5	121.8
CV-24202	5/22/2026 10:29:59 AM	43.3	48.4	0.0	8.3			0.9	0.0	114.6
CV-24202	5/6/2026 3:17:39 PM	38.0	49.4	0.0	12.6			0.8	0.0	117.1
CV-24203	5/22/2026 9:36:46 AM	52.8	45.4	0.2	1.6			1.2	8.0	126.7
CV-24203	5/11/2026 10:07:30 AM	50.4	45.5	0.0	4.1			1.1	0.0	125.9
CV-24204	5/22/2026 9:39:46 AM	50.0	48.6	0.1	1.3			1.0	13.0	126.4
CV-24204	5/11/2026 10:10:41 AM	47.5	48.6	0.0	3.9			1.0	0.0	125.8
CV-24205	5/22/2026 9:45:39 AM	55.7	43.4	0.0	0.9			1.3	0.0	122.6
CV-24205	5/6/2026 12:13:07 PM	49.5	42.8	0.0	7.7			1.2	0.0	121.1
CV-24206	5/22/2026 10:00:36 AM	46.8	40.8	0.0	12.4			1.1	0.0	92.1
CV-24206	5/6/2026 3:04:18 PM	42.5	40.7	0.0	16.8			1.0	0.0	86.6
CV-24207	5/21/2026 9:17:20 AM	52.4	43.6	1.3	2.7			1.2	2.1	130.6

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [ ]
CV-24207	5/21/2026 9:15:43 AM	49.8	42.7	2.4	5.1			1.2	2.1	131.6
CV-24207	5/4/2026 2:35:22 PM	51.4	48.2	0.0	0.4			1.1	0.0	126.2
CV-24208	5/4/2026 10:58:55 AM	43.9	49.9	0.0	6.2			0.9	0.0	125.5
CV-24209	5/4/2026 11:15:06 AM	13.7	72.3	0.0	14.0			0.2	0.0	125.0
CV-24210	5/5/2026 1:26:15 PM	44.4	51.1	0.0	4.5			0.9	0.0	101.3
CV-24210	5/4/2026 11:34:40 AM	46.5	47.4	0.0	6.1			1.0	0.0	121.4
CV-24211	5/7/2026 10:23:15 AM	18.7	79.7	0.0	1.6			0.2	0.0	117.6
CV-24212	5/11/2026 9:45:09 AM	7.4	67.7	0.4	24.5			0.1	61.3	136.6
CV-24212	5/11/2026 9:43:52 AM	7.4	68.1	0.6	23.9			0.1	39.8	135.2
CV-24213	5/1/2026 1:55:50 PM	43.1	46.8	0.0	10.1			0.9	0.0	117.9
CV-24213	5/1/2026 1:54:28 PM	43.6	46.0	0.0	10.4			0.9	0.0	122.1
CV-24213	5/1/2026 1:34:20 PM	38.4	50.0	0.0	11.6			0.8	0.0	108.6
CV-24213	5/1/2026 1:32:27 PM	38.4	50.7	0.0	10.9			0.8	0.0	108.7
CV-24214	5/26/2026 12:44:02 PM	40.3	41.4	0.0	18.3			1.0	0.0	108.4
CV-24214	5/26/2026 12:41:30 PM	40.8	41.4	0.0	17.9			1.0	0.0	110.1
CV-24215	5/29/2026 9:58:57 AM	31.5	49.7	0.0	18.8			0.6	0.0	96.2
CV-24216	5/1/2026 1:59:49 PM	48.0	41.3	1.2	9.5			1.2	7.9	105.0
CV-24217	5/11/2026 1:45:32 PM	38.4	55.9	0.0	5.7			0.7	0.0	115.7
CV-24217	5/11/2026 1:25:59 PM	39.3	56.1	0.0	4.6			0.7	0.0	110.4
CV-24217	5/11/2026 10:19:12 AM	43.1	50.5	0.0	6.4			0.9	0.0	121.6
CV-24218	5/8/2026 8:42:59 AM	43.0	56.1	0.0	0.9			0.8	0.0	123.6
CV-24219	5/27/2026 2:44:32 PM	15.5	82.2	0.3	2.0			0.2	6.7	180.1
CV-24219	5/19/2026 1:10:00 PM					2820				
CV-24219	5/19/2026 1:07:47 PM	24.4	75.6	0.0	0.0			0.3	0.0	182.4
CV-24219	5/19/2026 1:07:21 PM	22.1	77.9	0.0	0.0			0.3	0.0	181.5
CV-24219	5/11/2026 9:27:37 AM	5.4	83.9	0.0	10.7			0.1	0.0	188.3

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-24219	5/11/2026 9:26:02 AM	5.5	88.0	0.0	6.5			0.1	0.0	188.6
CV-24219	5/4/2026 8:40:00 AM					3760				
CV-24219	5/4/2026 8:40:00 AM						105700			
CV-24219	5/4/2026 8:37:52 AM	2.4	92.8	0.0	4.8			0.0	0.0	187.1
CV-24220	5/1/2026 2:28:38 PM	14.9	58.2	0.9	26.0			0.3	28.9	131.7
CV-24220	5/1/2026 2:26:20 PM	18.1	50.2	1.2	30.5			0.4	25.4	135.4
CV-24221	5/7/2026 10:47:53 AM	37.4	46.4	0.0	16.2			0.8	0.0	91.5
CV-24222	5/11/2026 9:28:59 AM	55.9	40.4	0.2	3.5			1.4	17.5	122.5
CV-24223	5/11/2026 9:35:14 AM	28.0	46.3	0.0	25.7			0.6	0.0	130.3
CV-24224	5/1/2026 2:36:53 PM	41.3	39.9	0.3	18.5			1.0	61.7	114.4
CV-24225	5/4/2026 10:44:54 AM	49.6	42.4	0.7	7.3			1.2	10.4	105.0
CV-24226	5/7/2026 10:18:42 AM	50.9	44.4	0.0	4.7			1.1	0.0	112.5
CV-24227	5/8/2026 11:27:46 AM	53.8	41.9	0.0	4.3			1.3	0.0	114.8
CV-24231	5/5/2026 2:20:38 PM	44.6	39.6	0.3	15.5			1.1	51.7	123.6
CV-24236	5/7/2026 9:58:34 AM	53.9	40.0	0.0	6.1			1.3	0.0	102.6
CV-24237	5/7/2026 10:03:50 AM	52.1	38.1	0.0	9.8			1.4	0.0	111.5
CV-24243	5/8/2026 10:05:46 AM	54.3	41.5	0.0	4.2			1.3	0.0	114.6
CV-24244	5/7/2026 11:23:42 AM	51.9	42.4	0.1	5.6			1.2	56.0	112.1
CV-24245	5/7/2026 2:21:55 PM	43.5	37.6	0.0	18.9			1.2	0.0	115.3
CV-24246	5/7/2026 2:17:13 PM	52.8	42.8	0.0	4.4			1.2	0.0	116.4
CV-24253	5/7/2026 2:35:07 PM	53.0	42.6	0.1	4.3			1.2	43.0	115.4
CV-25	5/13/2026 1:44:59 PM	51.7	41.4	0.4	6.5			1.2	16.7	92.9
CV-2501	5/4/2026 9:55:50 AM	51.2	46.4	0.0	2.4			1.1	0.0	120.3
CV-2502	5/4/2026 10:08:04 AM	50.0	43.5	0.0	6.5			1.1	0.0	119.0
CV-2503	5/6/2026 2:52:46 PM	51.6	45.3	0.0	3.1			1.1	0.0	125.8
CV-2504	5/5/2026 2:41:25 PM	47.0	41.9	0.0	11.1			1.1	0.0	125.8
CV-2505	5/5/2026 2:55:39 PM	50.1	42.6	0.0	7.3			1.2	0.0	117.4
CV-2506	5/5/2026 3:55:25 PM	50.1	43.4	0.0	6.5			1.2	0.0	119.7
CV-2507	5/8/2026 1:37:11 PM	55.3	42.3	0.0	2.4			1.3	0.0	122.7
CV-2507	5/5/2026 3:50:55 PM	55.9	42.0	0.0	2.1			1.3	0.0	120.1

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-2508	5/5/2026 3:46:09 PM	55.4	43.4	0.0	1.2			1.3	0.0	118.5
CV-2509	5/8/2026 1:42:52 PM	55.2	41.8	0.0	3.0			1.3	0.0	115.3
CV-2509	5/5/2026 3:31:32 PM	52.0	42.7	0.0	5.3			1.2	0.0	113.5
CV-2510	5/8/2026 1:46:50 PM	56.1	41.2	0.0	2.7			1.4	0.0	113.8
CV-2510	5/5/2026 2:25:18 PM	56.1	41.7	0.0	2.2			1.3	0.0	113.4
CV-25100D	5/18/2026 10:35:31 AM	37.2	62.8	0.0	0.0			0.6	0.0	118.5
CV-25100D	5/12/2026 10:22:21 AM	30.8	69.2	0.0	0.0			0.4	0.0	147.0
CV-25100D	5/12/2026 10:20:00 AM					504				
CV-25100D	5/8/2026 9:54:19 AM	5.0	80.5	0.0	14.5			0.1	0.0	177.5
CV-25100D	5/8/2026 9:52:49 AM	5.7	74.0	0.2	20.1			0.1	100.5	177.3
CV-25100S	5/26/2026 10:48:42 AM	4.0	80.8	0.0	15.2			0.0	0.0	160.8
CV-25100S	5/26/2026 10:48:08 AM	4.0	78.6	0.0	17.4			0.1	0.0	158.1
CV-25100S	5/18/2026 10:40:00 AM					3960				
CV-25100S	5/18/2026 10:33:27 AM	16.7	75.9	0.0	7.4			0.2	0.0	151.8
CV-25100S	5/12/2026 10:25:18 AM	18.8	81.2	0.0	0.0			0.2	0.0	163.6
CV-25100S	5/12/2026 10:25:00 AM					1030				
CV-25100S	5/8/2026 10:01:43 AM	1.2	83.1	0.0	15.7			0.0	0.0	182.3
CV-25100S	5/8/2026 10:00:14 AM	1.2	76.1	0.0	22.7			0.0	0.0	182.8
CV-25100S	5/4/2026 2:45:00 PM					3650				
CV-25100S	5/4/2026 2:45:00 PM						138200			
CV-25100S	5/4/2026 2:38:27 PM	1.8	86.7	0.0	11.5			0.0	0.0	181.2
CV-25101D	5/22/2026 10:43:56 AM	5.2	68.1	4.0	22.7			0.1	5.7	80.3
CV-25101D	5/12/2026 1:33:31 PM	5.4	76.9	1.0	16.7			0.1	16.7	82.6
CV-25101S	5/22/2026 10:46:24 AM	24.4	64.4	0.0	11.2			0.4	0.0	112.3
CV-25101S	5/12/2026 1:23:51 PM	18.7	59.6	0.2	21.5			0.3	107.5	122.9
CV-25102_	5/20/2026 2:05:47 PM	12.0	55.1	6.5	26.4			0.2	4.1	100.1
CV-25102_	5/8/2026 10:11:54 AM	4.5	28.4	13.0	54.1			0.2	4.2	83.2
CV-25102_	5/8/2026 10:09:29 AM	6.9	44.3	8.7	40.1			0.2	4.6	83.6

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [ ]
CV-25103	5/22/2026 11:13:05 AM	2.7	87.1	0.0	10.2			0.0	0.0	127.7
CV-25103	5/20/2026 1:53:20 PM	51.3	48.7	0.0	0.0			1.1	0.0	106.0
CV-25103	5/12/2026 10:47:21 AM	21.7	41.1	0.0	37.2			0.5	0.0	125.2
CV-25103	5/12/2026 10:45:57 AM	22.3	42.5	0.0	35.2			0.5	0.0	141.3
CV-25104D	5/20/2026 2:32:23 PM	9.2	72.7	1.8	16.3			0.1	9.1	94.7
CV-25104D	5/13/2026 9:49:44 AM	4.6	75.6	1.7	18.1			0.1	10.6	94.5
CV-25104S	5/20/2026 2:35:06 PM	8.7	78.5	0.0	12.8			0.1	0.0	104.5
CV-25104S	5/13/2026 9:54:31 AM	3.8	82.8	0.0	13.4			0.0	0.0	120.8
CV-25105D	5/22/2026 10:19:59 AM	15.8	35.6	2.7	45.9			0.4	17.0	93.0
CV-25105D	5/8/2026 8:27:56 AM	22.6	50.6	0.9	25.9			0.4	28.8	74.3
CV-25105S	5/20/2026 1:43:43 PM	22.9	38.0	0.7	38.4			0.6	54.9	128.3
CV-25105S	5/8/2026 8:30:20 AM	17.5	41.5	1.3	39.7			0.4	30.5	128.5
CV-25106D	5/26/2026 9:05:29 AM	0.7	3.8	20.6	74.9			0.2	3.6	60.0
CV-25106D	5/26/2026 9:03:18 AM	0.6	3.3	20.9	75.2			0.2	3.6	59.9
CV-25106D	5/12/2026 2:19:11 PM	1.8	9.1	17.8	71.3			0.2	4.0	87.1
CV-25106D	5/12/2026 2:18:07 PM	1.7	9.9	17.7	70.7			0.2	4.0	87.2
CV-25106S	5/26/2026 9:12:30 AM	7.5	10.5	18.1	63.9			0.7	3.5	66.6
CV-25106S	5/26/2026 9:11:40 AM	7.5	10.4	18.1	64.0			0.7	3.5	66.0
CV-25106S	5/12/2026 2:25:06 PM	5.3	7.4	18.0	69.3			0.7	3.9	87.8
CV-25106S	5/12/2026 2:23:49 PM	5.6	8.9	17.7	67.8			0.6	3.8	87.4
CV-25107D	5/1/2026 2:47:38 PM	2.6	70.5	4.5	22.4			0.0	5.0	89.4
CV-25107S	5/1/2026 2:50:28 PM	47.4	52.6	0.0	0.0			0.9	0.0	100.3
CV-2511	5/5/2026 2:33:06 PM	48.1	42.6	0.0	9.3			1.1	0.0	124.0
CV-2512	5/5/2026 2:28:36 PM	46.3	42.2	0.0	11.5			1.1	0.0	122.8
CV-2513	5/7/2026 3:05:57 PM	53.0	43.7	0.0	3.3			1.2	0.0	119.1

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]
CV-2514	5/8/2026 2:58:55 PM	53.9	42.0	0.0	4.1			1.3	0.0	122.4
CV-2515	5/7/2026 9:16:53 AM	54.2	38.5	0.0	7.3			1.4	0.0	114.6
CV-2516	5/11/2026 11:15:10 AM	51.3	43.9	0.0	4.8			1.2	0.0	125.7
CV-2517	5/7/2026 9:40:45 AM	45.9	39.4	0.0	14.7			1.2	0.0	111.5
CV-2518	5/7/2026 10:00:08 AM	53.0	42.8	0.0	4.2			1.2	0.0	104.6
CV-2518	5/7/2026 9:57:35 AM	53.3	42.7	0.0	4.0			1.2	0.0	92.3
CV-2519	5/1/2026 1:11:22 PM	48.9	42.1	0.0	9.0			1.2	0.0	125.2
CV-2520	5/1/2026 1:26:15 PM	26.2	53.4	0.0	20.4			0.5	0.0	140.9
CV-2520	5/1/2026 1:25:06 PM	25.9	53.8	0.0	20.3			0.5	0.0	139.7
CV-2521	5/26/2026 12:24:46 PM	35.8	48.5	0.0	15.8			0.7	0.0	109.3
CV-2522	5/5/2026 12:53:32 PM	38.3	44.4	0.0	17.3			0.9	0.0	129.7
CV-2522	5/1/2026 10:59:06 AM	38.9	46.1	0.0	15.0			0.8	0.0	135.3
CV-2522	5/1/2026 10:57:27 AM	35.4	45.7	0.0	18.9			0.8	0.0	128.6
CV-2523	5/4/2026 2:07:42 PM	54.4	40.3	0.0	5.3			1.3	0.0	124.5
CV-2524	5/1/2026 10:45:46 AM	32.2	47.2	0.0	20.6			0.7	0.0	141.2
CV-2524	5/1/2026 10:44:23 AM	33.2	46.7	0.0	20.1			0.7	0.0	139.4
CV-2525	5/4/2026 2:13:54 PM	55.7	42.1	0.0	2.2			1.3	0.0	120.2
CV-2525	5/4/2026 2:13:24 PM	55.5	39.6	0.0	4.9			1.4	0.0	116.1
CV-2526	5/4/2026 2:18:08 PM	54.0	42.3	0.0	3.7			1.3	0.0	119.7
CV-2527	5/15/2026 11:27:42 AM	42.4	45.8	0.2	11.6			0.9	58.0	126.2
CV-2528	5/11/2026 8:25:29 AM	52.7	39.3	0.0	8.0			1.3	0.0	109.3
CV-2529	5/8/2026 12:47:59 PM	56.6	41.3	0.2	1.9			1.4	9.5	87.9
CV-2530	5/12/2026 7:58:10 AM	42.2	49.9	0.0	7.9			0.8	0.0	122.8
CV-2531	5/8/2026 12:35:03 PM	31.5	54.9	0.0	13.6			0.6	0.0	118.0

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-2531	5/8/2026 12:34:13 PM	31.1	54.6	0.0	14.3			0.6	0.0	98.2
CV-2532	5/12/2026 7:54:00 AM	50.4	42.4	1.1	6.1			1.2	5.5	73.4
CV-2533	5/12/2026 7:48:32 AM	52.7	44.9	0.2	2.2			1.2	11.0	128.4
CV-2534	5/11/2026 2:17:18 PM	53.0	43.3	0.0	3.7			1.2	0.0	123.0
CV-2535	5/5/2026 2:52:23 PM	37.7	35.2	0.0	27.1			1.1	0.0	107.4
CV-2536	5/14/2026 10:27:30 AM	40.5	36.0	4.1	19.4			1.1	4.7	89.0
CV-2537	5/6/2026 12:17:48 PM	45.7	39.3	0.1	14.9			1.2	149.0	113.7
CV-2538	5/6/2026 12:25:17 PM	50.4	40.8	0.0	8.8			1.2	0.0	118.6
CV-2539	5/20/2026 9:49:24 AM	42.4	43.7	0.0	13.9			1.0	0.0	122.2
CV-2539	5/4/2026 9:17:28 AM	38.2	42.2	0.0	19.6			0.9	0.0	116.6
CV-2540	5/20/2026 2:18:42 PM	2.6	84.3	0.0	13.1			0.0	0.0	128.9
CV-2540	5/20/2026 2:15:08 PM	1.5	76.2	0.0	22.3			0.0	0.0	131.1
CV-2540	5/14/2026 1:17:10 PM	4.3	80.5	0.4	14.8			0.1	37.0	129.8
CV-2540	5/14/2026 1:13:24 PM	5.1	79.6	0.6	14.7			0.1	24.5	134.7
CV-2541	5/19/2026 9:38:49 AM	28.5	56.4	0.0	15.1			0.5	0.0	130.9
CV-2541	5/19/2026 9:36:57 AM	29.6	55.8	0.0	14.6			0.5	0.0	133.3
CV-2541	5/1/2026 11:15:47 AM	4.6	84.3	0.0	11.1			0.1	0.0	84.8
CV-2541	5/1/2026 11:15:26 AM	4.8	76.3	0.0	18.9			0.1	0.0	84.9
CV-2542	5/21/2026 2:04:28 PM	49.7	50.3	0.0	0.0			1.0	0.0	92.0
CV-2542	5/4/2026 1:56:22 PM	44.6	53.2	0.0	2.2			0.8	0.0	70.6
CV-2543-PLR	5/20/2026 1:43:43 PM	20.5	66.9	0.5	12.1			0.3	24.2	104.5
CV-2543-PLR	5/4/2026 9:50:49 AM	26.7	60.3	1.2	11.8			0.4	9.8	83.0
CV-2544	5/21/2026 1:52:17 PM	13.5	77.0	0.0	9.5			0.2	0.0	94.3
CV-2544	5/21/2026 1:51:00 PM	13.1	78.8	0.0	8.1			0.2	0.0	95.5
CV-2544	5/6/2026 11:06:39 AM	12.3	81.6	0.0	6.1			0.2	0.0	83.4
CV-2545	5/22/2026 12:19:27 PM	31.1	68.9	0.0	0.0			0.5	0.0	127.4
CV-2545	5/22/2026 12:15:46 PM	32.5	65.2	0.0	2.3			0.5	0.0	131.2
CV-2545	5/6/2026 2:44:01 PM	31.1	64.9	0.0	4.0			0.5	0.0	115.4

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-2545	5/6/2026 2:43:10 PM	31.2	66.0	0.0	2.8			0.5	0.0	116.2
CV-2546	5/22/2026 12:25:12 PM	18.1	80.2	0.0	1.7			0.2	0.0	129.8
CV-2546	5/22/2026 12:24:00 PM	18.1	81.7	0.1	0.1			0.2	1.0	132.1
CV-2546	5/6/2026 2:35:53 PM	13.3	79.5	0.0	7.2			0.2	0.0	120.1
CV-2547	5/28/2026 12:23:14 PM	51.5	43.9	0.1	4.5			1.2	45.0	94.3
CV-2547	5/22/2026 12:03:11 PM	52.1	46.2	0.0	1.7			1.1	0.0	95.7
CV-2547	5/6/2026 10:25:52 AM	48.8	47.4	0.0	3.8			1.0	0.0	102.4
CV-2548	5/13/2026 9:58:56 AM	12.6	76.5	0.0	10.9			0.2	0.0	127.3
CV-2548	5/1/2026 10:34:59 AM	12.0	81.1	0.0	6.9			0.1	0.0	128.0
CV-2549	5/28/2026 12:13:13 PM	49.3	41.5	0.0	9.2			1.2	0.0	110.0
CV-2549	5/13/2026 9:51:28 AM	49.4	46.4	0.0	4.2			1.1	0.0	110.8
CV-2549	5/6/2026 12:31:15 PM	48.7	48.6	0.0	2.7			1.0	0.0	109.5
CV-2549	5/1/2026 10:30:41 AM	44.2	50.4	0.3	5.1			0.9	17.0	111.6
CV-2550	5/27/2026 1:19:05 PM	3.1	80.0	0.0	16.9			0.0	0.0	168.2
CV-2550	5/21/2026 10:06:57 AM	5.1	78.6	0.0	16.3			0.1	0.0	183.4
CV-2550	5/21/2026 10:04:40 AM	5.0	75.9	0.0	19.1			0.1	0.0	182.1
CV-2550	5/11/2026 9:52:55 AM	9.6	84.0	0.9	5.5			0.1	6.1	179.9
CV-2550	5/4/2026 9:00:00 AM					2670				
CV-2550	5/4/2026 8:59:59 AM	3.4	77.8	0.0	18.8			0.0	0.0	183.8
CV-2551	5/1/2026 2:40:59 PM	13.9	84.0	0.0	2.1			0.2	0.0	134.9
CV-2551	5/1/2026 2:39:32 PM	14.2	79.8	0.1	5.9			0.2	59.0	135.5
CV-2552	5/19/2026 1:50:38 PM	53.6	46.4	0.0	0.0			1.2	0.0	115.0
CV-2552	5/19/2026 1:49:24 PM	50.9	49.1	0.0	0.0			1.0	0.0	112.0
CV-2552	5/11/2026 9:58:44 AM	34.9	64.8	0.3	0.0			0.5	0.0	176.5
CV-2552	5/4/2026 9:36:17 AM	23.7	63.1	0.0	13.2			0.4	0.0	173.8
CV-2552	5/4/2026 9:35:00 AM					2130				
CV-2552	5/4/2026 9:35:00 AM						67100			
CV-2553	5/20/2026 1:24:17 PM	43.3	51.7	0.2	4.8			0.8	24.0	112.9

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]
CV-2553	5/4/2026 9:36:18 AM	47.2	51.3	0.0	1.5			0.9	0.0	87.3
CV-2554	5/28/2026 1:40:06 PM	25.3	70.7	0.0	4.0			0.4	0.0	148.6
CV-2554	5/20/2026 2:11:24 PM	24.3	69.4	0.1	6.2			0.4	62.0	148.5
CV-2554	5/14/2026 11:13:27 AM	33.9	66.0	0.1	0.0			0.5	0.0	158.2
CV-2554	5/14/2026 11:12:34 AM	31.9	68.0	0.1	0.0			0.5	0.0	159.4
CV-2554	5/14/2026 11:10:00 AM					1040				
CV-2554	5/4/2026 1:13:35 PM	4.7	95.0	0.3	0.0			0.0	0.0	168.5
CV-2554	5/4/2026 1:12:59 PM	4.5	82.2	0.0	13.3			0.1	0.0	169.3
CV-2554	5/4/2026 1:10:00 PM					928				
CV-2554	5/4/2026 1:10:00 PM						70800			
CV-2555	5/22/2026 11:41:33 AM	4.2	8.8	20.1	66.9			0.5	3.3	92.3
CV-2555	5/22/2026 11:39:04 AM	6.9	10.2	18.6	64.3			0.7	3.5	83.4
CV-2555	5/8/2026 1:12:17 PM	12.8	26.0	12.4	48.8			0.5	3.9	83.2
CV-2556	5/27/2026 2:02:24 PM	3.3	82.4	0.0	14.3			0.0	0.0	177.0
CV-2556	5/19/2026 1:45:00 PM					2070				
CV-2556	5/19/2026 1:38:41 PM	16.0	79.2	0.0	4.8			0.2	0.0	179.4
CV-2556	5/11/2026 10:20:58 AM	7.9	86.8	0.0	5.3			0.1	0.0	179.2
CV-2556	5/4/2026 9:15:00 AM					2935				
CV-2556	5/4/2026 9:15:00 AM						110800			
CV-2556	5/4/2026 9:13:52 AM	1.5	82.5	0.0	16.0			0.0	0.0	175.8
CV-2557	5/20/2026 1:47:47 PM	30.2	61.2	0.0	8.6			0.5	0.0	125.9
CV-2557	5/8/2026 8:36:19 AM	23.3	66.3	0.0	10.4			0.4	0.0	121.2
CV-2558	5/27/2026 2:34:42 PM	8.3	76.3	1.2	14.2			0.1	11.8	179.6
CV-2558	5/27/2026 2:33:21 PM	8.5	75.8	1.6	14.1			0.1	8.8	179.7
CV-2558	5/19/2026 1:15:50 PM	21.0	76.1	0.2	2.7			0.3	13.5	179.4
CV-2558	5/19/2026 1:15:00 PM					2790				
CV-2558	5/14/2026 10:19:35 AM	16.1	79.8	0.0	4.1			0.2	0.0	183.9

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-2558	5/14/2026 10:18:44 AM	17.2	80.2	0.2	2.4			0.2	12.0	181.4
CV-2558	5/14/2026 10:15:00 AM					3750				
CV-2558	5/4/2026 8:47:30 AM	3.8	74.2	0.9	21.1			0.1	23.4	186.9
CV-2558	5/4/2026 8:45:31 AM	3.6	71.4	2.4	22.6			0.1	9.4	186.2
CV-2558	5/4/2026 8:45:00 AM					4000				
CV-2559	5/8/2026 8:53:26 AM	17.8	81.1	0.0	1.1			0.2	0.0	124.9
CV-2559	5/8/2026 8:49:36 AM	19.7	79.2	0.0	1.1			0.2	0.0	123.6
CV-2560	5/22/2026 10:39:45 AM	23.0	44.9	0.5	31.6			0.5	63.2	111.4
CV-2560	5/12/2026 1:09:28 PM	19.0	36.8	0.5	43.7			0.5	87.4	125.4
CV-2561	5/11/2026 2:38:47 PM	13.6	35.2	0.0	51.2			0.4	0.0	128.6
CV-2562	5/11/2026 2:10:20 PM	39.3	53.9	0.0	6.8			0.7	0.0	125.0
CV-2563	5/28/2026 11:37:21 AM	37.3	53.7	0.0	9.0			0.7	0.0	113.1
CV-2563	5/28/2026 11:36:57 AM	37.6	49.1	0.0	13.3			0.8	0.0	109.5
CV-2563	5/15/2026 11:37:25 AM	33.5	60.6	0.1	5.8			0.6	58.0	111.3
CV-2563	5/15/2026 11:35:25 AM	33.8	60.6	0.0	5.6			0.6	0.0	107.1
CV-2564	5/21/2026 9:30:21 AM	20.3	75.1	0.0	4.6			0.3	0.0	129.1
CV-2564	5/21/2026 9:29:15 AM	19.7	77.3	0.0	3.0			0.3	0.0	128.4
CV-2564	5/1/2026 11:06:39 AM	23.6	70.1	0.0	6.3			0.3	0.0	128.0
CV-2565	5/20/2026 9:51:50 AM	33.5	37.6	0.0	28.9			0.9	0.0	113.5
CV-2565	5/4/2026 9:20:17 AM	31.0	38.6	0.0	30.4			0.8	0.0	111.0
CV-2566	5/20/2026 9:46:01 AM	51.5	48.5	0.1				1.1		108.2
CV-2566	5/4/2026 9:24:42 AM	48.7	46.3	0.0	5.0			1.1	0.0	100.7
CV-2567	5/20/2026 12:20:18 PM	48.6	48.7	0.1	2.6			1.0	26.0	109.2
CV-2567	5/4/2026 9:43:22 AM	49.6	46.8	0.0	3.6			1.1	0.0	99.5
CV-2568	5/20/2026 11:39:12 AM	44.0	50.3	0.0	5.7			0.9	0.0	109.3
CV-2568	5/4/2026 11:23:44 AM	42.5	45.6	0.0	11.9			0.9	0.0	91.4
CV-2569	5/20/2026 11:29:23 AM	45.4	54.6	0.0	0.0			0.8	0.0	110.3
CV-2569	5/4/2026 11:29:19 AM	45.4	47.9	0.0	6.7			0.9	0.0	92.7
CV-2570	5/20/2026 11:15:26 AM	50.8	49.2	0.0	0.0			1.0	0.0	112.6
CV-2570	5/4/2026 11:34:49 AM	49.8	45.3	0.0	4.9			1.1	0.0	98.5
CV-2571	5/7/2026 1:00:36 PM	51.2	41.2	0.0	7.6			1.2	0.0	96.5

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
CV-2572	5/7/2026 1:32:16 PM	52.6	42.0	0.0	5.4			1.3	0.0	121.9
CV-48R	5/28/2026 11:41:20 AM	51.7	43.5	0.0	4.8			1.2	0.0	116.4
CV-48R	5/28/2026 11:40:34 AM	50.6	41.0	0.0	8.4			1.2	0.0	116.0
CV-48R	5/15/2026 11:44:42 AM	49.0	50.2	0.0	0.8			1.0	0.0	116.1
CV-48R	5/6/2026 10:23:03 AM	53.1	46.8	0.0	0.1			1.1	0.0	119.9
CV-52D	5/1/2026 1:17:29 PM	30.1	50.2	1.3	18.4			0.6	14.2	94.8
CV-55R	5/27/2026 3:07:28 PM	33.0	48.7	0.4	17.9			0.7	44.8	142.0
CV-55R	5/21/2026 9:11:16 AM	20.8	54.1	0.0	25.1			0.4	0.0	133.4
CV-55R	5/21/2026 9:10:09 AM	14.0	46.3	0.0	39.7			0.3	0.0	90.1
CV-55R	5/11/2026 11:02:29 AM	49.6	50.4	0.0	0.0			1.0	0.0	153.3
CV-55R	5/4/2026 8:05:00 AM					181.5				
CV-55R	5/4/2026 8:05:00 AM						140550			
CV-55R	5/4/2026 8:04:21 AM	37.3	44.5	0.0	18.2			0.8	0.0	149.7
CV-56D	5/7/2026 11:25:28 AM	4.1	4.7	18.5	72.7			0.9	3.9	92.3
CV-56D	5/7/2026 11:22:51 AM	18.5	20.7	11.8	49.0			0.9	4.2	92.4
CV-56S	5/7/2026 11:32:33 AM	2.6	32.0	7.5	57.9			0.1	7.7	89.2
CV-56S	5/7/2026 11:29:21 AM	2.9	33.4	6.9	56.8			0.1	8.2	90.9
CV-57R	5/1/2026 2:21:40 PM	52.1	41.9	0.0	6.0			1.2	0.0	87.9
CV-79R	5/1/2026 2:41:23 PM	52.3	43.5	0.0	4.2			1.2	0.0	125.4
CV-94	5/11/2026 3:29:38 PM	51.7	42.4	0.0	5.9			1.2	0.0	114.0
CV-94	5/11/2026 3:28:29 PM	54.9	43.4	0.0	1.7			1.3	0.0	108.3
CV-95	5/1/2026 2:19:24 PM	52.4	39.5	0.0	8.1			1.3	0.0	104.3
CV-95	5/1/2026 2:18:38 PM	51.3	38.6	0.0	10.1			1.3	0.0	93.6
CV-99	5/26/2026 1:51:48 PM	26.1	73.9	0.0	0.0			0.4	0.0	77.4
CV-99	5/4/2026 7:45:00 AM						2600			
D-02	5/28/2026 3:29:22 PM	57.8	42.2	0.0	0.0			1.4	0.0	84.9

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init °F Temp [ ]
D-03	5/28/2026 3:32:52 PM	53.1	41.6	1.6	3.7			1.3	2.3	86.8
D-04	5/28/2026 3:41:09 PM	58.5	41.5	0.0	0.0			1.4	0.0	76.9
D-09	5/7/2026 1:18:48 PM	52.1	40.6	0.0	7.3			1.3	0.0	111.4
D-10	5/7/2026 1:08:35 PM	45.6	35.0	2.7	16.7			1.3	6.2	107.3
FP-001	5/8/2026 9:19:36 AM	9.3	21.4	4.7	64.6			0.4	13.7	81.0
FP-002	5/8/2026 9:28:39 AM	16.5	25.5	4.0	54.0			0.6	13.5	78.6
FP-003	5/8/2026 9:39:47 AM	8.7	16.6	8.1	66.6			0.5	8.2	79.4
FP-003	5/8/2026 9:36:36 AM	8.4	16.6	8.3	66.7			0.5	8.0	79.6
FP-005	5/15/2026 2:55:43 PM	6.0	23.1	12.4	58.5			0.3	4.7	82.4
FP-006	5/15/2026 2:51:55 PM	20.7	78.2	0.0	1.1			0.3	0.0	82.4
FP-008	5/15/2026 3:10:45 PM	14.7	70.2	1.4	13.7			0.2	9.8	88.4
FP-008	5/6/2026 9:22:39 AM	18.8	76.7	0.0	4.5			0.2	0.0	80.2
FP-009	5/13/2026 10:12:04 AM	11.7	79.4	0.0	8.9			0.1	0.0	94.3
FP-010	5/13/2026 10:03:04 AM	17.6	79.9	0.0	2.5			0.2	0.0	105.2
FP-011	5/13/2026 10:00:11 AM	30.2	62.9	1.4	5.5			0.5	3.9	73.6
FP-012	5/19/2026 8:39:03 AM	13.1	18.8	14.6	53.5			0.7	3.7	82.2
FP-012	5/1/2026 11:49:02 AM	9.4	10.5	17.4	62.7			0.9	3.6	83.7
FP-013	5/19/2026 9:34:22 AM	25.1	35.6	6.1	33.2			0.7	5.4	77.7
FP-013	5/13/2026 9:55:27 AM	19.9	25.3	9.2	45.6			0.8	5.0	75.1
FP-014	5/13/2026 2:03:06 PM	19.4	72.7	0.0	7.9			0.3	0.0	85.0
FP-015	5/15/2026 2:35:16 PM	1.7	49.5	8.1	40.7			0.0	5.0	79.6
FP-015	5/14/2026 2:08:49 PM	2.5	70.5	0.7	26.3			0.0	38.1	171.9
FP-015	5/13/2026 2:12:26 PM	4.7	75.2	0.8	19.3			0.1	24.1	175.6
FP-016	5/15/2026 2:43:10 PM	11.5	54.8	6.2	27.5			0.2	4.4	88.6
FP-016	5/13/2026 2:15:57 PM	13.7	55.9	6.6	23.8			0.2	3.6	88.7
FP-017	5/8/2026 12:57:34 PM	45.4	33.2	3.2	18.2			1.4	5.7	88.5
FP-018	5/8/2026 12:40:54 PM	22.4	17.2	11.4	49.0			1.3	4.3	87.3
FP-019	5/12/2026 1:48:27 PM	53.7	42.4	0.0	3.9			1.3	0.0	79.3
FP-020	5/12/2026 1:57:00 PM	14.5	71.5	0.0	14.0			0.2	0.0	83.0
FP-021	5/13/2026 10:41:14 AM	29.1	63.4	0.0	7.5			0.5	0.0	90.8

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [ ]
FP-021	5/12/2026 1:59:43 PM	21.8	70.3	0.0	7.9			0.3	0.0	95.6
FP-022	5/13/2026 10:32:37 AM	18.1	66.0	0.7	15.2			0.3	21.7	90.2
FP-023	5/13/2026 1:46:18 PM	22.6	58.6	3.6	15.2			0.4	4.2	84.5
FP-024	5/20/2026 2:16:33 PM	33.1	65.0	0.6	1.3			0.5	2.2	96.6
FP-025	5/20/2026 2:19:20 PM	27.3	51.6	2.0	19.1			0.5	9.6	84.1
FP-026	5/29/2026 4:20:14 PM	12.5	39.6	8.4	39.5			0.3	4.7	78.0
FP-027	5/29/2026 4:24:24 PM	12.6	29.6	10.1	47.7			0.4	4.7	88.0
FP-028	5/28/2026 11:39:27 AM	0.3	0.4	20.7	78.6			0.8	3.8	81.3
FP-029	5/28/2026 11:31:57 AM	0.0	0.3	20.9	78.8			0.0	3.8	74.2
FP-030	5/12/2026 1:41:15 PM	52.2	47.8	0.0	0.0			1.1	0.0	76.4
FP-031	5/29/2026 9:22:16 AM	33.3	55.8	1.3	9.6			0.6	7.4	76.3
FP-031	5/12/2026 1:37:06 PM	31.5	53.2	1.3	14.0			0.6	10.8	77.9
FP-032	5/12/2026 1:28:30 PM	23.9	53.3	4.5	18.3			0.4	4.1	80.6
FP-033	5/12/2026 1:23:05 PM	6.3	35.3	10.9	47.5			0.2	4.4	86.3
FP-034	5/12/2026 1:19:44 PM	19.7	37.5	5.9	36.9			0.5	6.3	84.6
FP-035	5/12/2026 1:16:01 PM	34.1	48.9	2.3	14.7			0.7	6.4	76.8
FP-036	5/1/2026 11:36:11 AM	31.3	49.3	2.7	16.7			0.6	6.2	77.8
FP-037	5/19/2026 10:33:25 AM	6.2	18.7	16.7	58.4			0.3	3.5	84.7
FP-037	5/1/2026 11:38:38 AM	2.9	7.0	19.5	70.6			0.4	3.6	83.2
FP-038	5/14/2026 2:24:47 PM	44.8	37.9	3.0	14.3			1.2	4.8	86.9
FP-039	5/14/2026 2:15:09 PM	52.9	44.8	0.1	2.2			1.2	22.0	89.9
FP-040	5/29/2026 2:30:36 PM	16.6	68.3	1.6	13.5			0.2	8.4	104.5
FP-041	5/13/2026 1:16:55 PM	20.7	33.1	4.0	42.2			0.6	10.6	88.1
FP-042	5/20/2026 10:11:54 AM	19.2	61.9	3.6	15.3			0.3	4.3	97.0
FP-043	5/13/2026 1:22:06 PM	14.0	33.0	6.4	46.6			0.4	7.3	89.9
FP-044	5/13/2026 1:25:38 PM	4.0	21.3	14.0	60.7			0.2	4.3	91.6
FP-045	5/11/2026 1:04:40 PM	29.5	38.9	2.8	28.8			0.8	10.2	121.6
FP-046	5/15/2026 3:02:41 PM	22.0	73.7	1.2	3.1			0.3	2.6	81.9
FP-047	5/29/2026 11:36:35 AM	19.3	51.2	2.5	27.0			0.4	10.8	86.1
FP-050	5/6/2026 2:53:31 PM	16.4	41.9	4.9	36.8			0.4	7.5	87.3
FP-051	5/6/2026 2:48:25 PM	36.4	48.1	1.0	14.5			0.8	14.5	92.2
FP-052	5/22/2026 2:09:54 PM	11.2	15.2	11.6	62.0			0.7	5.3	89.0
FP-052	5/4/2026 2:20:50 PM	16.2	21.0	9.8	53.0			0.8	5.4	80.4
FP-053	5/21/2026 2:19:03 PM	45.7	54.3	0.0	0.0			0.8	0.0	100.2
FP-053	5/4/2026 2:08:41 PM	37.2	36.6	3.4	22.8			1.0	6.7	85.2
FP-054	5/1/2026 11:30:37 AM	36.6	34.7	0.9	27.8			1.1	30.9	86.0

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
FP-055	5/20/2026 2:00:54 PM	52.4	41.8	0.0	5.8			1.3	0.0	103.6
FP-055	5/4/2026 10:03:30 AM	48.5	39.7	1.2	10.6			1.2	8.8	78.7
FP-056	5/4/2026 9:15:22 AM	47.3	40.3	0.4	12.0			1.2	30.0	74.3
FP-057	5/4/2026 9:17:47 AM	39.7	45.5	0.0	14.8			0.9	0.0	104.8
FP-057	5/1/2026 11:34:44 AM	40.1	33.2	2.5	24.2			1.2	9.7	79.6
FP-058	5/29/2026 3:51:49 PM	41.8	38.7	1.3	18.2			1.1	14.0	85.7
FP-059	5/1/2026 2:35:49 PM	50.1	40.3	1.5	8.1			1.2	5.4	92.7
FP-060	5/1/2026 2:53:38 PM	43.2	35.8	3.1	17.9			1.2	5.8	91.0
FP-061	5/15/2026 2:38:19 PM	5.3	76.0	0.8	17.9			0.1	22.4	148.5
FP-061	5/14/2026 2:22:44 PM	4.0	70.6	0.5	24.9			0.1	47.9	158.1
FP-061	5/14/2026 2:19:38 PM	4.4	64.7	2.3	28.6			0.1	12.4	161.6
H-01 (EXP-01)	5/26/2026 8:45:19 AM	17.8	46.9	0.0	35.3			0.4	0.0	61.8
H-01 (EXP-01)	5/12/2026 1:49:58 PM	15.8	46.3	0.0	38.0			0.3	0.0	96.9
H-02 (EXP-02)	5/26/2026 8:27:48 AM	16.7	48.7	0.0	34.6			0.3	0.0	84.1
H-02 (EXP-02)	5/12/2026 1:55:38 PM	12.8	48.1	0.0	39.2			0.3	0.0	110.4
H-03 (EXP-03)	5/26/2026 8:31:53 AM	56.5	43.5	0.0	0.0			1.3	0.0	112.6
H-03 (EXP-03)	5/12/2026 2:02:02 PM	50.8	45.2	0.0	4.1			1.1	0.0	118.9
H-04 (EXP-04)	5/26/2026 8:34:46 AM	3.6	55.1	0.0	41.3			0.1	0.0	124.2
H-04 (EXP-04)	5/14/2026 10:16:02 AM	3.0	55.2	0.0	41.8			0.1	0.0	131.1
H-04 (EXP-04)	5/14/2026 10:14:56 AM	3.0	54.1	0.0	42.9			0.1	0.0	131.2
H-04 (EXP-04)	5/14/2026 10:13:50 AM	3.4	55.1	0.0	41.5			0.1	0.0	130.7
H-08 (EXP-08)	5/26/2026 8:55:13 AM	52.1	47.9	0.0	0.0			1.1	0.0	119.2
H-08 (EXP-08)	5/11/2026 9:46:50 AM	48.8	46.1	0.0	5.1			1.1	0.0	88.4
H-10 (EXP-10)	5/26/2026 9:06:45 AM	12.5	72.3	0.0	15.2			0.2	0.0	130.8
H-10 (EXP-10)	5/11/2026 9:40:46 AM	10.6	66.8	0.0	22.6			0.2	0.0	130.8
H-10 (EXP-10)	5/11/2026 9:40:06 AM	10.8	66.1	0.0	23.0			0.2	0.0	130.8
H-101W	5/13/2026 8:32:50 AM	22.3	15.9	13.6	48.2			1.4	3.5	65.5
H-101W	5/13/2026 8:24:13 AM	24.1	18.7	12.8	44.4			1.3	3.5	64.3
H-102A	5/13/2026 8:17:41 AM	56.3	35.3	1.4	7.0			1.6	5.0	66.5
H-1401W	5/13/2026 8:48:53 AM	54.9	33.8	2.2	9.1			1.6	4.1	70.1
H-1404C	5/20/2026 11:55:54 AM	27.5	36.8	0.1	35.6			0.7	356.0	129.2
H-1404C	5/4/2026 11:20:18 AM	25.8	32.1	0.0	42.1			0.8	0.0	124.8

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
H-1405C	5/20/2026 8:39:42 AM	26.3	38.0	0.0	35.7			0.7	0.0	94.7
H-1405C	5/1/2026 10:13:01 AM	42.8	46.0	0.0	11.2			0.9	0.0	87.5
H-1406W	5/20/2026 9:30:46 AM	40.6	41.7	3.6	14.1			1.0	3.9	88.8
H-1406W	5/1/2026 10:30:28 AM	35.6	50.7	3.1	10.6			0.7	3.4	80.7
H-1408CR	5/6/2026 2:48:15 PM	28.1	37.4	0.0	34.5			0.8	0.0	125.8
H-1408CR	5/6/2026 2:46:51 PM	37.4	42.1	0.0	20.5			0.9	0.0	118.0
H-1408E	5/20/2026 2:13:20 PM	49.3	42.6	0.0	8.1			1.2	0.0	111.7
H-1408E	5/4/2026 2:44:00 PM	36.9	37.6	0.1	25.4			1.0	254.0	107.3
H-1408E	5/4/2026 2:42:19 PM	39.8	38.2	0.1	21.9			1.0	219.0	103.3
H-1408W	5/7/2026 10:26:18 AM	52.7	42.9	0.0	4.4			1.2	0.0	102.9
H-1409N	5/20/2026 2:26:47 PM	37.7	36.9	0.0	25.4			1.0	0.0	116.1
H-1409N	5/4/2026 2:02:48 PM	36.0	34.1	0.0	29.9			1.1	0.0	111.5
H-1410S	5/6/2026 12:22:14 PM	41.2	35.3	2.3	21.2			1.2	9.2	87.5
H-1563N	5/22/2026 2:12:17 PM	49.7	44.6	0.0	5.7			1.1	0.0	115.7
H-1563N	5/11/2026 12:47:48 PM	47.3	45.1	0.0	7.6			1.0	0.0	114.9
H-1563S	5/20/2026 8:43:45 AM	10.4	25.8	0.0	63.8			0.4	0.0	89.3
H-1563S	5/1/2026 10:06:27 AM	18.4	38.6	0.0	43.0			0.5	0.0	93.5
H-1565E	5/21/2026 10:26:51 AM	54.0	40.3	0.0	5.7			1.3	0.0	116.3
H-1565E	5/6/2026 10:50:58 AM	49.1	48.8	0.0	2.1			1.0	0.0	114.8
H-1568N	5/21/2026 10:57:34 AM	44.2	55.8	0.0	0.0			0.8	0.0	124.8
H-1568N	5/20/2026 2:05:18 PM	46.5	41.0	0.0	12.5			1.1	0.0	113.8
H-1568N	5/4/2026 2:46:50 PM	33.8	34.3	0.0	31.9			1.0	0.0	107.3
H-1571S	5/4/2026 11:05:46 AM	47.5	43.5	0.0	9.0			1.1	0.0	81.3
H-1572N	5/1/2026 2:47:42 PM	42.4	36.3	0.4	20.9			1.2	52.3	101.0
H-1572S	5/4/2026 10:51:40 AM	40.0	38.4	0.0	21.6			1.0	0.0	96.0
H-1574N	5/20/2026 10:38:18 AM	47.2	43.4	0.0	9.4			1.1	0.0	103.6
H-1574N	5/13/2026 9:52:29 AM	8.7	79.6	0.0	11.7			0.1	0.0	140.4

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [ ]
H-1574N	5/12/2026 8:59:40 AM	43.3	43.8	1.1	11.8			1.0	10.7	98.5
H-1753N	5/26/2026 9:00:32 AM	47.7	47.2	0.8	4.3			1.0	5.4	66.7
H-1753N	5/12/2026 1:45:21 PM	40.8	32.4	4.7	22.1			1.3	4.7	84.5
H-1753S	5/22/2026 2:02:07 PM	53.8	39.6	0.0	6.6			1.4	0.0	111.9
H-1753S	5/11/2026 12:40:59 PM	52.9	41.3	0.0	5.8			1.3	0.0	107.2
H-1756S	5/19/2026 1:28:24 PM	36.4	61.1	0.0	2.5			0.6	0.0	129.8
H-1756S	5/19/2026 1:25:39 PM	36.1	62.4	0.0	1.5			0.6	0.0	131.0
H-1756S	5/13/2026 12:47:50 PM	32.3	58.2	0.1	9.4			0.6	94.0	127.6
H-1757S	5/20/2026 8:35:55 AM	45.9	45.3	0.0	8.8			1.0	0.0	80.8
H-1757S	5/1/2026 10:14:46 AM	46.1	44.3	0.0	9.6			1.0	0.0	81.3
H-1760S	5/21/2026 10:10:39 AM	38.7	48.8	0.0	12.5			0.8	0.0	115.9
H-1760S	5/11/2026 1:37:59 PM	38.2	45.2	0.0	16.6			0.8	0.0	119.0
H-1762N	5/20/2026 1:57:03 PM	51.7	42.3	0.0	6.0			1.2	0.0	108.7
H-1762N	5/20/2026 1:55:17 PM	51.5	42.7	0.0	5.8			1.2	0.0	108.6
H-1762N	5/4/2026 2:38:51 PM	51.2	40.6	0.0	8.2			1.3	0.0	100.5
H-1763N	5/6/2026 10:36:14 AM	26.5	66.5	0.0	7.0			0.4	0.0	104.7
H-1763N	5/6/2026 10:34:51 AM	23.5	67.8	0.0	8.7			0.3	0.0	95.6
H-1763S	5/4/2026 11:26:50 AM	43.0	40.8	0.0	16.2			1.1	0.0	102.6
H-1764N	5/28/2026 12:39:39 PM	54.1	40.7	0.0	5.2			1.3	0.0	116.8
H-1764N	5/5/2026 1:16:30 PM	53.8	39.4	0.0	6.8			1.4	0.0	117.3
H-1764N	5/4/2026 11:45:03 AM	55.1	40.1	0.0	4.8			1.4	0.0	117.2
H-1764S	5/4/2026 11:08:05 AM	48.3	45.4	0.0	6.3			1.1	0.0	91.0
H-1767N	5/11/2026 9:51:22 AM	39.0	54.5	0.0	6.5			0.7	0.0	101.8
H-1769N	5/19/2026 8:53:05 AM	24.1	65.8	0.0	10.1			0.4	0.0	107.8
H-1769N	5/1/2026 2:30:15 PM	20.8	52.8	0.9	25.5			0.4	28.3	110.1
H-1770N	5/19/2026 9:18:49 AM	36.3	61.0	0.0	2.7			0.6	0.0	99.2
H-1770N	5/4/2026 8:50:00 AM						12000			
H-1770N	5/1/2026 2:42:44 PM	35.3	62.8	0.0	1.9			0.6	0.0	100.2
H-1770S	5/19/2026 12:50:46 PM	31.2	59.0	0.0	9.8			0.5	0.0	102.4
H-1770S	5/1/2026 10:34:30 AM	17.2	41.1	1.6	40.1			0.4	25.1	101.2

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
H-1771A	5/11/2026 2:21:58 PM	43.9	39.4	0.0	16.7			1.1	0.0	113.2
H-1771B	5/13/2026 11:22:20 AM	45.2	53.4	0.0	1.4			0.8	0.0	130.4
H-1771B	5/13/2026 11:19:01 AM	40.2	59.1	0.0	0.7			0.7	0.0	132.7
H-1771B	5/11/2026 1:05:25 PM	51.3	46.2	0.0	2.5			1.1	0.0	104.5
H-1771B	5/11/2026 1:04:43 PM	50.8	46.8	0.0	2.4			1.1	0.0	104.3
H-1774N	5/19/2026 9:58:15 AM	29.2	68.7	0.0	2.1			0.4	0.0	115.8
H-1774N	5/12/2026 10:34:14 AM	29.8	70.2	0.0	0.0			0.4	0.0	115.8
H-1801S	5/11/2026 11:15:54 AM	42.9	33.8	2.5	20.8			1.3	8.3	101.8
H-1802S	5/1/2026 2:44:17 PM	54.5	41.1	0.0	4.4			1.3	0.0	104.8
H-1803N	5/26/2026 9:42:57 AM	4.0	76.7	0.0	19.3			0.1	0.0	196.0
H-1803N	5/18/2026 10:00:00 AM					1730				
H-1803N	5/18/2026 9:58:45 AM	17.7	72.4	0.0	9.9			0.2	0.0	196.5
H-1803N	5/12/2026 9:08:34 AM	15.5	77.5	0.0	7.0			0.2	0.0	196.4
H-1803N	5/12/2026 9:05:00 AM					242				
H-1803N	5/5/2026 9:07:24 AM	5.3	78.3	0.0	16.4			0.1	0.0	196.0
H-1803N	5/5/2026 9:00:00 AM					1840				
H-1803N	5/5/2026 9:00:00 AM						170700			
H-1804B	5/1/2026 10:39:08 AM	54.1	44.4	0.0	1.5			1.2	0.0	108.4
H-1804N	5/8/2026 9:11:50 AM	59.4	39.5	0.0	1.1			1.5	0.0	88.4
H-1804S	5/4/2026 11:47:34 AM	56.1	41.6	0.0	2.3			1.3	0.0	98.1
H-1805A	5/1/2026 11:19:57 AM	42.5	52.7	0.1	4.7			0.8	47.0	102.6
H-1805B	5/4/2026 11:52:01 AM	49.7	42.8	0.0	7.5			1.2	0.0	70.9
H-1805S	5/4/2026 11:39:55 AM	53.5	43.6	0.0	2.9			1.2	0.0	127.6
H-1806A	5/1/2026 11:08:54 AM	47.7	38.6	0.0	13.7			1.2	0.0	98.8
H-1806B	5/1/2026 2:52:26 PM	17.6	27.9	0.0	54.5			0.6	0.0	114.0
H-1806N	5/11/2026 11:37:48 AM	44.4	51.7	0.0	3.9			0.9	0.0	129.3
H-1806S	5/4/2026 10:39:51 AM	40.3	47.2	0.0	12.5			0.9	0.0	117.6
H-1807A	5/4/2026 1:18:09 PM	54.3	42.8	0.0	2.9			1.3	0.0	102.7
H-1807N	5/29/2026 10:10:34 AM	28.3	33.1	0.0	38.6			0.9	0.0	80.6

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
H-1807S	5/7/2026 11:08:13 AM	47.7	46.3	0.0	6.0			1.0	0.0	91.7
H-1952S	5/21/2026 2:14:50 PM	54.3	45.7	0.0	0.0			1.2	0.0	126.2
H-1952S	5/21/2026 2:13:14 PM	54.9	45.1	0.0	0.0			1.2	0.0	125.3
H-1952S	5/4/2026 2:04:02 PM	50.4	48.2	0.0	1.4			1.0	0.0	121.7
H-1955C	5/1/2026 11:26:41 AM	29.9	28.7	4.5	36.9			1.0	8.2	82.4
H-1955N	5/8/2026 9:07:44 AM	52.9	41.9	0.1	5.1			1.3	51.0	88.3
H-1956B	5/1/2026 10:44:44 AM	35.7	53.3	0.0	11.0			0.7	0.0	120.7
H-1956N	5/11/2026 11:40:47 AM	52.5	43.8	0.0	3.7			1.2	0.0	107.0
H-1956S	5/1/2026 2:39:31 PM	45.8	38.4	0.0	15.8			1.2	0.0	112.1
H-1957B	5/6/2026 2:10:22 PM	50.9	40.5	0.0	8.6			1.3	0.0	101.1
H-1957B	5/1/2026 2:13:12 PM	41.5	37.0	0.0	21.5			1.1	0.0	102.6
H-1957N	5/11/2026 11:33:03 AM	45.0	42.2	0.0	12.8			1.1	0.0	121.9
H-1957S	5/11/2026 11:18:08 AM	37.9	49.6	0.1	12.4			0.8	124.0	114.6
H-1958C	5/4/2026 1:20:33 PM	51.1	40.6	0.0	8.3			1.3	0.0	122.5
H-1958N	5/28/2026 1:56:37 PM	57.8	42.2	0.0	0.0			1.4	0.0	90.6
H-1958S	5/7/2026 11:03:31 AM	48.9	39.0	0.0	12.1			1.3	0.0	122.4
H-1962N	5/19/2026 9:28:05 AM	22.8	52.2	4.5	20.5			0.4	4.6	123.2
H-1962N	5/19/2026 9:26:00 AM	23.4	53.4	4.1	19.1			0.4	4.7	127.1
H-1962N	5/1/2026 2:46:00 PM	15.4	69.2	0.0	15.4			0.2	0.0	113.7
H-1963N	5/19/2026 8:46:36 AM	23.4	68.5	0.0	8.1			0.3	0.0	140.0
H-1963N	5/19/2026 8:44:46 AM	24.1	67.7	0.0	8.2			0.4	0.0	140.2
H-1963N	5/1/2026 12:06:22 PM	24.0	72.5	0.0	3.5			0.3	0.0	141.4
H-1963N	5/1/2026 12:04:32 PM	22.1	72.6	0.0	5.3			0.3	0.0	135.1
H-1966N	5/19/2026 10:06:37 AM	46.8	50.3	0.0	2.9			0.9	0.0	105.5
H-1966N	5/12/2026 10:42:28 AM	46.9	48.2	0.0	4.9			1.0	0.0	105.7
H-1967E	5/7/2026 1:04:55 PM	52.6	40.6	0.0	6.8			1.3	0.0	105.5
H-1967W	5/7/2026 9:49:11 AM	56.1	39.9	0.0	4.0			1.4	0.0	94.4

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
H-1967W	5/7/2026 9:47:56 AM	56.2	39.7	0.0	4.1			1.4	0.0	93.7
H-2050E	5/14/2026 9:38:59 AM	55.2	41.0	0.3	3.5			1.3	11.7	85.0
H-2050W	5/5/2026 3:39:36 PM	47.7	41.7	0.0	10.6			1.1	0.0	100.7
H-2051W	5/7/2026 9:44:33 AM	56.7	40.5	0.0	2.8			1.4	0.0	85.2
H-2053E	5/7/2026 1:13:15 PM	47.8	39.9	0.0	12.3			1.2	0.0	119.2
H-2053W	5/13/2026 8:39:25 AM	60.0	38.5	0.0	1.5			1.6	0.0	91.3
H-2055E	5/22/2026 10:10:19 AM	30.3	33.3	0.0	36.4			0.9	0.0	107.8
H-2055E	5/6/2026 3:07:33 PM	30.8	33.7	0.0	35.5			0.9	0.0	107.4
H-2056B	5/8/2026 3:07:26 PM	28.8	29.8	0.0	41.4			1.0	0.0	90.4
H-2056W	5/7/2026 9:41:29 AM	56.9	39.8	0.0	3.3			1.4	0.0	95.6
H-2057E	5/7/2026 1:10:46 PM	50.6	37.7	0.0	11.7			1.3	0.0	125.6
H-2057W	5/28/2026 8:44:04 AM	55.9	37.4	1.0	5.7			1.5	5.7	80.9
H-2057W	5/13/2026 8:09:16 AM	46.0	31.6	3.6	18.8			1.5	5.2	80.3
H-2057W	5/13/2026 8:05:12 AM	43.6	28.5	4.1	23.8			1.5	5.8	82.1
H-2058E	5/7/2026 1:22:33 PM	50.9	40.0	0.0	9.1			1.3	0.0	110.1
H-2058W	5/7/2026 9:34:28 AM	55.9	39.8	0.0	4.3			1.4	0.0	94.7
H-2058W	5/7/2026 9:33:03 AM	57.3	38.9	0.1	3.7			1.5	37.0	93.7
H-2059E	5/6/2026 12:36:07 PM	54.5	42.2	0.0	3.3			1.3	0.0	116.6
H-2059W	5/7/2026 10:12:44 AM	50.6	46.1	0.0	3.3			1.1	0.0	126.5
H-2161E	5/6/2026 12:32:34 PM	51.0	42.1	0.0	6.9			1.2	0.0	123.6
H-2161W	5/7/2026 10:08:23 AM	57.4	39.7	0.0	2.9			1.4	0.0	106.7
H-2163C	5/22/2026 10:05:49 AM	50.3	44.1	0.0	5.6			1.1	0.0	90.0
H-2163C	5/4/2026 10:05:22 AM	51.8	44.1	0.0	4.1			1.2	0.0	83.7
H-2163W	5/7/2026 10:22:23 AM	39.4	58.7	0.0	1.9			0.7	0.0	125.5
H-2164E	5/22/2026 10:41:07 AM	34.9	62.7	0.0	2.4			0.6	0.0	125.3
H-2164E	5/6/2026 3:22:38 PM	31.3	68.7	0.0	0.0			0.5	0.0	127.2
H-2164E	5/6/2026 3:21:24 PM	32.1	67.9	0.0	0.0			0.5	0.0	124.4
H-2165E	5/4/2026 10:55:10 AM	48.3	46.7	0.0	5.0			1.0	0.0	109.8
H-2165W	5/20/2026 9:46:57 AM	12.9	79.8	0.0	7.3			0.2	0.0	119.8
H-2165W	5/12/2026 7:45:00 AM					720				
H-2165W	5/12/2026 7:45:00 AM						48000			

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
H-2165W	5/1/2026 10:16:24 AM	10.9	86.4	0.0	2.7			0.1	0.0	118.0
H-2166E	5/4/2026 1:12:58 PM	54.2	40.8	0.2	4.8			1.3	24.0	101.5
H-2168C	5/1/2026 10:48:38 AM	56.3	41.3	0.0	2.4			1.4	0.0	84.9
H-2168E	5/28/2026 12:08:16 PM	37.9	37.6	0.0	24.5			1.0	0.0	118.3
H-2168E	5/6/2026 2:36:05 PM	45.5	40.3	0.0	14.2			1.1	0.0	120.1
H-2168E	5/5/2026 10:39:26 AM	39.5	34.5	0.2	25.8			1.1	129.0	71.4
H-2168E	5/5/2026 10:37:49 AM	22.7	21.3	9.6	46.4			1.1	4.8	70.1
H-2168E	5/1/2026 2:15:28 PM	42.4	38.7	0.0	18.9			1.1	0.0	120.0
H-2169C	5/4/2026 11:55:39 AM	53.1	41.0	0.0	5.9			1.3	0.0	104.4
H-2169E	5/1/2026 2:05:32 PM	44.3	39.2	0.0	16.5			1.1	0.0	114.8
H-2170N	5/4/2026 2:04:41 PM	51.0	40.4	0.0	8.6			1.3	0.0	117.3
H-2170S	5/11/2026 8:29:12 AM	50.7	40.2	0.0	9.1			1.3	0.0	101.9
H-2171A	5/14/2026 8:58:08 AM	43.5	37.1	0.0	19.4			1.2	0.0	94.8
H-2171A	5/14/2026 8:54:11 AM	43.8	36.9	0.0	19.3			1.2	0.0	95.9
H-2171A	5/13/2026 10:13:53 AM	43.2	38.0	0.0	18.7			1.1	0.0	94.7
H-2171A	5/13/2026 10:08:18 AM	43.1	37.0	0.0	19.9			1.2	0.0	97.6
H-2171A	5/7/2026 9:32:22 AM	50.6	38.4	0.0	11.0			1.3	0.0	91.9
H-2171B	5/13/2026 2:00:46 PM	51.0	40.8	0.0	8.2			1.2	0.0	119.6
H-2171N	5/7/2026 9:22:04 AM	43.3	37.9	0.0	18.8			1.1	0.0	108.4
H-2171S	5/4/2026 2:02:33 PM	48.7	41.7	0.0	9.6			1.2	0.0	119.2
H-2272W	5/19/2026 10:27:12 AM	38.3	43.8	0.0	17.9			0.9	0.0	124.4
H-2272W	5/4/2026 9:50:05 AM	33.4	40.5	0.0	26.2			0.8	0.0	122.9
H-2272W	5/4/2026 9:47:59 AM	34.8	39.9	0.0	25.3			0.9	0.0	122.0
H-2273W	5/20/2026 8:21:56 AM	25.2	50.1	0.0	24.7			0.5	0.0	129.9
H-2273W	5/13/2026 12:42:00 PM	17.2	42.0	0.1	40.7			0.4	407.0	125.4
H-2273W	5/12/2026 7:50:00 AM					76				
H-2273W	5/12/2026 7:50:00 AM						5900			
H-2274B	5/20/2026 2:09:49 PM	50.6	46.7	0.1	2.6			1.1	26.0	96.3
H-2274B	5/4/2026 1:23:52 PM	49.7	45.6	0.0	4.7			1.1	0.0	82.5
H-2274W	5/19/2026 1:17:54 PM	27.7	68.7	0.0	3.6			0.4	0.0	125.2
H-2274W	5/1/2026 10:22:35 AM	24.0	60.6	0.3	15.1			0.4	50.3	129.9
H-2275E	5/4/2026 11:24:01 AM	38.1	59.7	0.0	2.2			0.6	0.0	121.7

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [ ]
H-2275W	5/20/2026 7:50:11 AM	15.6	33.8	1.9	48.7			0.5	25.6	126.0
H-2275W	5/8/2026 11:15:19 AM	33.9	63.2	0.0	2.9			0.5	0.0	112.5
H-2275W	5/8/2026 11:13:59 AM	34.3	64.3	0.0	1.4			0.5	0.0	82.9
H-2276A	5/20/2026 1:13:04 PM	38.5	36.8	0.1	24.6			1.0	223.6	108.2
H-2276A	5/11/2026 1:32:34 PM	41.1	37.1	0.0	21.8			1.1	0.0	106.7
H-2276B	5/20/2026 2:22:12 PM	51.4	43.3	0.0	5.3			1.2	0.0	117.5
H-2276B	5/4/2026 2:06:44 PM	53.5	41.4	0.0	5.1			1.3	0.0	114.0
H-2276E	5/4/2026 11:37:57 AM	46.8	41.4	0.0	11.8			1.1	0.0	116.2
H-2276W	5/20/2026 8:32:50 AM	37.9	54.7	0.0	7.4			0.7	0.0	92.8
H-2276W	5/1/2026 10:16:43 AM	24.8	62.0	0.0	13.2			0.4	0.0	101.3
H-2277A	5/21/2026 9:41:03 AM	46.0	54.0	0.0	0.0			0.9	0.0	92.3
H-2277A	5/1/2026 11:04:15 AM	42.2	44.2	2.7	10.9			1.0	4.0	79.1
H-2277B	5/21/2026 9:35:16 AM	55.1	43.4	0.0	1.5			1.3	0.0	117.5
H-2277B	5/4/2026 2:19:04 PM	48.2	40.6	0.0	11.2			1.2	0.0	115.3
H-23 (EXP-23)	5/13/2026 1:17:40 PM	8.0	4.3	17.8	69.9			1.9	3.9	93.9
H-23 (EXP-23)	5/13/2026 1:13:21 PM	8.1	4.1	17.7	70.1			1.9	4.0	91.9
H-23 (EXP-23)	5/13/2026 10:53:27 AM	7.4	4.7	18.0	69.8			1.6	3.9	85.0
H-23 (EXP-23)	5/13/2026 10:40:54 AM	5.5	4.6	18.9	71.0			1.2	3.8	76.3
H-2301E	5/13/2026 9:05:55 AM	48.3	39.3	0.0	12.4			1.2	0.0	105.3
H-2301W	5/15/2026 10:14:58 AM	23.6	19.3	11.2	45.9			1.2	4.1	73.0
H-2301W	5/15/2026 10:13:21 AM	22.3	16.5	11.2	50.0			1.4	4.5	72.6
H-2302C	5/7/2026 2:47:12 PM	53.8	40.8	0.0	5.4			1.3	0.0	116.8
H-2302E	5/8/2026 12:55:32 PM	55.9	40.9	0.1	3.1			1.4	31.0	105.2
H-2303E	5/8/2026 1:01:15 PM	55.3	41.8	0.0	2.9			1.3	0.0	88.8
H-2303N	5/7/2026 2:55:44 PM	54.3	41.9	0.0	3.8			1.3	0.0	102.4
H-2304E	5/8/2026 1:05:45 PM	56.4	41.7	0.0	1.9			1.4	0.0	95.6
H-2304S	5/8/2026 1:30:30 PM	54.0	43.5	0.0	2.5			1.2	0.0	123.3
H-2305N	5/7/2026 3:01:47 PM	54.7	41.3	0.0	4.0			1.3	0.0	97.5
H-2305S	5/8/2026 1:14:11 PM	54.8	43.0	0.0	2.2			1.3	0.0	125.8

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
H-2306N	5/15/2026 10:33:03 AM	50.7	40.5	0.0	8.8			1.3	0.0	116.5
H-2307S	5/22/2026 11:53:04 AM	53.3	39.2	0.3	7.2			1.4	24.0	114.7
H-2307S	5/7/2026 2:41:47 PM	52.4	43.3	0.0	4.3			1.2	0.0	119.9
H-2307S	5/7/2026 2:40:20 PM	53.9	42.6	0.0	3.5			1.3	0.0	114.6
H-2308S	5/7/2026 2:29:52 PM	50.8	42.0	0.0	7.2			1.2	0.0	118.8
H-2309N	5/4/2026 10:13:40 AM	51.4	43.8	0.0	4.8			1.2	0.0	83.6
H-2309S	5/8/2026 1:53:32 PM	55.0	42.5	0.0	2.5			1.3	0.0	108.9
H-2310N	5/8/2026 3:03:25 PM	54.5	40.5	0.0	5.0			1.3	0.0	109.7
H-2310S	5/22/2026 12:06:57 PM	52.1	39.4	0.0	8.5			1.3	0.0	102.7
H-2310S	5/14/2026 9:47:40 AM	40.7	37.1	0.2	22.0			1.1	110.0	101.3
H-2401S	5/7/2026 11:32:52 AM	54.8	42.7	0.0	2.5			1.3	0.0	108.7
H-2402N	5/8/2026 9:47:00 AM	47.4	43.4	0.0	9.2			1.1	0.0	105.9
H-2402S	5/8/2026 9:58:19 AM	52.1	40.8	0.0	7.1			1.3	0.0	109.5
H-2403N	5/8/2026 9:51:09 AM	53.4	42.6	0.0	4.0			1.3	0.0	110.9
H-2403S	5/8/2026 9:35:34 AM	39.5	33.9	3.3	23.3			1.2	7.1	80.3
H-2404N	5/5/2026 3:35:40 PM	53.3	42.6	0.0	4.1			1.3	0.0	107.6
H-2404S	5/8/2026 8:59:38 AM	56.7	41.0	0.1	2.2			1.4	22.0	111.3
H-2405N	5/5/2026 2:23:59 PM	22.7	31.6	0.0	45.7			0.7	0.0	111.7
H-29	5/29/2026 12:05:20 PM	17.4	45.3	0.0	37.3			0.4	0.0	92.4
H-29	5/29/2026 12:00:31 PM	17.5	44.9	0.0	37.6			0.4	0.0	78.6
H-29	5/4/2026 1:58:42 PM	19.9	47.7	0.0	32.4			0.4	0.0	71.3
H-29	5/4/2026 1:55:50 PM	20.0	45.7	0.0	34.3			0.4	0.0	76.8
H-72	5/29/2026 9:51:57 AM	52.9	41.3	0.4	5.4			1.3	13.5	80.9
H-74	5/11/2026 11:20:34 AM	52.5	41.8	0.0	5.7			1.3	0.0	101.6
H-75	5/14/2026 11:59:28 AM	46.1	46.1	0.0	7.8			1.0	0.0	90.5
H-79	5/15/2026 11:24:44 AM	45.6	48.2	0.1	6.1			0.9	61.0	128.7
P-02R	5/13/2026 8:15:30 AM	28.4	31.1	0.0	40.5			0.9	0.0	82.2
P-03R	5/13/2026 8:26:58 AM	37.8	33.0	0.0	29.1			1.1	0.0	87.6
P-04	5/5/2026 7:38:51 AM	52.6	39.3	0.0	8.1			1.3	0.0	91.5
P-05	5/5/2026 7:46:02 AM	35.6	35.8	0.0	28.6			1.0	0.0	102.6
P-06R	5/5/2026 7:49:46 AM	41.8	36.3	0.0	21.9			1.2	0.0	105.9
P-07R	5/12/2026 8:59:48 AM	32.9	30.2	0.0	36.9			1.1	0.0	83.4
P-08R	5/11/2026 10:46:01 AM	53.4	37.2	0.0	9.4			1.4	0.0	101.8
P-09	5/5/2026 8:01:21 AM	46.5	38.0	0.0	15.5			1.2	0.0	94.6

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [ ]
P-10	5/5/2026 7:56:04 AM	42.5	36.6	0.0	20.9			1.2	0.0	85.8
P-11	5/12/2026 9:25:09 AM	48.6	37.1	0.0	14.4			1.3	0.0	104.3
P-12	5/15/2026 7:59:36 AM	57.4	40.4	0.0	2.2			1.4	0.0	74.1
P-13	5/15/2026 8:05:44 AM	47.7	34.6	0.0	17.7			1.4	0.0	78.0
P-14	5/5/2026 8:13:25 AM	24.8	28.2	0.7	46.3			0.9	66.1	73.0
P-15R	5/5/2026 8:17:20 AM	48.7	36.8	0.0	14.5			1.3	0.0	70.6
P-16	5/5/2026 8:25:52 AM	51.0	36.4	0.0	12.6			1.4	0.0	79.0
P-17	5/5/2026 8:30:43 AM	35.8	34.5	0.0	29.7			1.0	0.0	109.1
P-18RD	5/5/2026 8:41:50 AM	51.2	38.3	0.0	10.5			1.3	0.0	81.1
P-18RS	5/5/2026 8:36:36 AM	38.7	35.6	0.0	25.7			1.1	0.0	91.1
P-19	5/4/2026 11:16:30 AM	33.6	28.9	0.0	37.5			1.2	0.0	84.0
P-20R	5/5/2026 8:45:27 AM	48.6	37.5	0.0	13.9			1.3	0.0	96.3
P-21	5/5/2026 8:49:59 AM	34.2	33.5	0.0	32.3			1.0	0.0	89.6
P-21RD	5/4/2026 10:03:26 AM	39.4	33.8	0.1	26.7			1.2	267.0	99.0
P-21RS	5/4/2026 10:00:38 AM	47.7	30.3	0.3	21.7			1.6	72.3	107.1
P-22RD	5/4/2026 10:32:00 AM	54.0	43.0	0.0	3.0			1.3	0.0	114.4
P-22RS	5/4/2026 10:28:52 AM	29.5	29.6	0.0	40.9			1.0	0.0	119.2
P-23	5/5/2026 8:59:25 AM	3.1	22.0	0.8	74.1			0.1	92.6	82.3
P-24	5/6/2026 8:17:07 AM	19.2	25.1	0.0	55.7			0.8	0.0	88.3
P-26	5/6/2026 8:34:09 AM	43.9	34.3	0.0	21.8			1.3	0.0	80.7
P-27	5/6/2026 8:43:29 AM	4.9	18.8	1.2	75.1			0.3	62.6	73.0
P-28	5/6/2026 8:51:00 AM	31.8	31.0	0.0	37.2			1.0	0.0	95.1
P-29R	5/6/2026 8:57:44 AM	19.9	26.6	0.4	53.1			0.7	132.8	90.8
P-30R	5/6/2026 9:04:44 AM	16.4	24.2	0.0	59.4			0.7	0.0	83.5
P-32R1	5/6/2026 9:10:45 AM	22.0	28.8	0.4	48.8			0.8	122.0	109.6
P-32R2	5/6/2026 9:14:09 AM	23.8	28.8	0.3	47.1			0.8	157.0	110.8
P-33	5/6/2026 9:19:40 AM	30.5	30.1	2.0	37.4			1.0	18.7	93.1
P-36	5/6/2026 9:31:05 AM	21.1	23.8	0.4	54.7			0.9	136.8	69.7
P-37	5/6/2026 9:35:20 AM	9.1	22.3	0.8	67.8			0.4	84.8	82.6
P-38RD	5/6/2026 9:48:07 AM	38.9	33.9	0.0	27.2			1.1	0.0	106.4
P-38RS	5/6/2026 9:44:32 AM	31.4	28.9	0.0	39.7			1.1	0.0	104.3
P-39	5/6/2026 9:55:17 AM	43.5	36.9	0.8	18.8			1.2	23.5	78.9
P-41	5/6/2026 10:07:48 AM	14.8	16.3	8.2	60.7			0.9	7.4	108.3
P-41	5/6/2026 10:06:10 AM	14.7	16.3	8.2	60.8			0.9	7.4	108.6
P-42R	5/6/2026 10:15:47 AM	51.6	36.1	0.2	12.1			1.4	60.5	111.5
P-43	5/6/2026 10:22:56 AM	20.6	24.0	0.8	54.6			0.9	68.3	116.8
P-44RD	5/6/2026 10:37:00 AM	47.3	33.6	0.0	19.1			1.4	0.0	90.1
P-44RS	5/6/2026 10:33:49 AM	18.5	22.4	0.1	59.0			0.8	590.0	121.7
P-45RD	5/6/2026 10:50:26 AM	40.0	34.6	0.0	25.4			1.2	0.0	114.9
P-45RS	5/6/2026 10:47:34 AM	2.9	17.7	0.1	79.3			0.2	793.0	90.4

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [ ]
P-46RD	5/6/2026 11:02:37 AM	48.2	34.9	0.0	16.9			1.4	0.0	99.1
P-46RS	5/6/2026 10:55:16 AM	15.2	21.5	0.0	63.3			0.7	0.0	120.7
P-47	5/4/2026 10:21:39 AM	10.6	21.7	1.2	66.5			0.5	55.4	96.4
P-48	5/4/2026 10:38:03 AM	17.3	24.8	0.0	57.9			0.7	0.0	113.0
P-49RD	5/4/2026 10:58:34 AM	52.0	38.1	0.4	9.5			1.4	23.8	112.6
P-49RS	5/4/2026 10:55:41 AM	33.7	28.3	0.2	37.8			1.2	189.0	113.8
P-52	5/28/2026 2:38:45 PM	33.1	33.7	0.0	33.2			1.0	0.0	117.0
P-53	5/15/2026 8:37:53 AM	20.7	25.3	0.0	54.0			0.8	0.0	114.6
P-54	5/15/2026 8:35:38 AM	29.8	31.3	0.0	38.9			1.0	0.0	100.9
P-55	5/15/2026 8:24:48 AM	29.5	29.5	0.0	41.0			1.0	0.0	93.9
P-56	5/26/2026 9:15:49 AM	19.8	28.9	0.0	51.3			0.7	0.0	101.7
P-57	5/13/2026 9:14:04 AM	17.1	22.5	4.0	56.4			0.8	14.2	76.5
P-60R	5/7/2026 8:52:45 AM	13.9	9.1	15.5	61.5			1.5	4.0	76.0
P-60R	5/7/2026 8:48:07 AM	3.4	3.5	19.3	73.8			1.0	3.8	75.1
P-61	5/7/2026 8:30:07 AM	41.3	35.7	0.0	23.0			1.2	0.0	83.4
P-65	5/7/2026 8:25:21 AM	29.5	27.2	0.0	43.3			1.1	0.0	71.4
P-71	5/4/2026 10:47:48 AM	30.4	27.4	0.2	42.0			1.1	210.0	72.3
P-75	5/6/2026 11:19:49 AM	51.7	33.5	0.0	14.8			1.5	0.0	92.0
P-76	5/6/2026 9:41:27 AM	17.4	22.8	0.1	59.7			0.8	597.0	91.4
P-79	5/4/2026 11:21:51 AM	17.5	22.2	1.6	58.7			0.8	36.7	86.4
SC-2000E	5/6/2026 12:28:45 PM	44.1	37.1	0.0	18.8			1.2	0.0	118.8
SC-2501E	5/26/2026 9:21:31 AM	3.2	78.4	0.0	18.4			0.0	0.0	189.1
SC-2501E	5/18/2026 9:40:35 AM	15.6	75.2	0.0	9.2			0.2	0.0	189.0
SC-2501E	5/18/2026 9:40:00 AM					211				
SC-2501E	5/18/2026 9:38:11 AM	15.0	73.0	0.0	12.0			0.2	0.0	189.0
SC-2501E	5/18/2026 9:29:29 AM	15.4	75.0	0.0	9.6			0.2	0.0	190.7
SC-2501E	5/12/2026 9:13:45 AM	21.2	78.8	0.0	0.0			0.3	0.0	188.9
SC-2501E	5/12/2026 9:10:00 AM					743				
SC-2501E	5/5/2026 8:56:40 AM	5.0	80.7	0.0	14.3			0.1	0.0	188.8
SC-2501E	5/5/2026 8:51:59 AM	4.7	82.8	0.0	12.5			0.1	0.0	188.5
SC-2501E	5/5/2026 8:50:00 AM					1400				
SC-2501E	5/5/2026 8:50:00 AM						177700			
SC-2501W	5/5/2026 9:19:42 AM	6.2	76.9	0.0	16.9			0.1	0.0	91.3
SW-10	5/28/2026 9:37:50 AM	35.2	33.3	1.5	30.0			1.1	20.0	71.5
SW-115	5/11/2026 8:59:04 AM	48.4	39.9	0.0	11.7			1.2	0.0	87.1

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
SW-1445	5/22/2026 7:39:28 AM	26.5	29.3	0.0	44.2			0.9	0.0	61.8
SW-1445	5/4/2026 7:53:57 AM	0.9	12.6	17.2	69.3			0.1	4.0	80.8
SW-1455	5/22/2026 7:44:18 AM	19.4	26.2	0.0	54.4			0.7	0.0	66.3
SW-1455	5/4/2026 7:57:56 AM	8.6	11.3	15.1	65.0			0.8	4.3	83.4
SW-154	5/15/2026 9:34:29 AM	0.0	1.1	20.0	78.9			0.0	3.9	66.7
SW-154	5/15/2026 9:31:56 AM	0.1	1.7	19.7	78.5			0.1	4.0	67.1
SW-17-135	5/22/2026 7:41:29 AM	30.1	29.3	0.0	40.6			1.0	0.0	65.4
SW-17-135	5/4/2026 7:56:03 AM	19.5	19.6	5.3	55.6			1.0	10.5	72.2
SW-187	5/4/2026 9:31:29 AM	15.9	27.5	5.5	51.1			0.6	9.3	81.2
SW-1930	5/1/2026 7:51:05 AM	33.2	51.7	2.7	12.4			0.6	4.6	81.3
SW-20	5/12/2026 9:06:57 AM	0.0	5.4	14.0	80.6			0.0	5.8	80.3
SW-25	5/1/2026 7:53:15 AM	0.6	0.6	21.5	77.3			1.0	3.6	65.8
SW-2501D	5/29/2026 7:21:12 AM	21.1	76.6	0.0	2.3			0.3	0.0	71.9
SW-2501D	5/28/2026 6:16:27 AM	22.8	76.5	0.0	0.7			0.3	0.0	71.6
SW-2501D	5/27/2026 6:04:20 AM	23.7	76.3	0.0	0.0			0.3	0.0	68.6
SW-2501D	5/26/2026 6:11:29 AM	23.0	76.3	0.0	0.7			0.3	0.0	72.6
SW-2501D	5/22/2026 6:19:43 AM	21.1	77.0	0.0	1.9			0.3	0.0	70.5
SW-2501D	5/21/2026 6:35:47 AM	21.4	78.0	0.0	0.6			0.3	0.0	76.9
SW-2501D	5/20/2026 8:30:45 AM	22.8	77.2	0.0	0.0			0.3	0.0	78.9
SW-2501D	5/19/2026 9:01:29 AM	20.3	79.4	0.0	0.3			0.3	0.0	80.0
SW-2501D	5/18/2026 8:44:45 AM	20.8	74.8	0.0	4.4			0.3	0.0	76.1
SW-2501D	5/15/2026 9:25:43 AM	14.5	33.0	11.9	40.6			0.4	3.4	77.8
SW-2501D	5/14/2026 8:19:05 AM	20.5	78.2	0.0	1.3			0.3	0.0	75.4
SW-2501D	5/13/2026 8:08:49 AM	21.3	78.4	0.0	0.3			0.3	0.0	75.4
SW-2501D	5/12/2026 9:15:23 AM	20.9	78.5	0.0	0.6			0.3	0.0	79.4
SW-2501D	5/11/2026 8:24:00 AM	21.0	77.7	0.0	1.3			0.3	0.0	77.2
SW-2501D	5/8/2026 9:35:42 AM	20.6	79.4	0.0	0.0			0.3	0.0	75.7
SW-2501D	5/7/2026 8:55:20 AM	20.7	79.2	0.0	0.1			0.3	0.0	74.7
SW-2501D	5/6/2026 8:47:06 AM	20.5	79.5	0.0	0.0			0.3	0.0	72.8
SW-2501D	5/5/2026 8:31:57 AM	20.3	78.4	0.0	1.3			0.3	0.0	72.1
SW-2501D	5/4/2026 8:20:15 AM	22.6	72.7	0.0	4.7			0.3	0.0	71.3
SW-2501D	5/1/2026 8:28:56 AM	26.9	73.1	0.0	0.0			0.4	0.0	71.7
SW-2501M	5/29/2026 7:24:25 AM	29.9	57.8	0.2	12.1			0.5	60.5	61.8

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
SW-2501M	5/28/2026 6:12:29 AM	33.6	51.8	0.6	14.0			0.6	23.3	62.8
SW-2501M	5/27/2026 5:59:22 AM	37.7	56.6	0.0	5.7			0.7	0.0	66.1
SW-2501M	5/26/2026 6:01:33 AM	34.3	54.8	0.0	10.9			0.6	0.0	67.5
SW-2501M	5/22/2026 6:14:16 AM	33.5	52.7	0.3	13.5			0.6	45.0	64.4
SW-2501M	5/21/2026 6:30:13 AM	33.2	55.4	0.2	11.2			0.6	56.0	69.4
SW-2501M	5/20/2026 8:25:51 AM	33.7	58.2	0.5	7.6			0.6	15.2	76.7
SW-2501M	5/19/2026 8:55:12 AM	30.6	56.0	0.4	13.0			0.5	32.5	76.3
SW-2501M	5/18/2026 8:38:11 AM	36.4	0.0	0.0	63.6				0.0	73.9
SW-2501M	5/15/2026 9:19:11 AM	33.3	58.4	0.5	7.8			0.6	15.6	71.9
SW-2501M	5/14/2026 8:13:12 AM	32.4	54.9	0.4	12.3			0.6	30.8	71.6
SW-2501M	5/13/2026 8:03:42 AM	31.3	55.3	0.6	12.8			0.6	21.3	70.4
SW-2501M	5/12/2026 9:11:04 AM	32.2	57.2	0.2	10.4			0.6	52.0	76.0
SW-2501M	5/11/2026 8:20:03 AM	32.1	59.0	0.0	8.9			0.5	0.0	78.4
SW-2501M	5/8/2026 9:30:13 AM	33.7	61.9	0.0	4.4			0.5	0.0	75.7
SW-2501M	5/7/2026 8:50:28 AM	36.4	61.4	0.0	2.2			0.6	0.0	73.4
SW-2501M	5/6/2026 8:42:31 AM	31.6	57.5	0.4	10.5			0.5	26.3	66.5
SW-2501M	5/5/2026 8:23:44 AM	30.0	58.9	0.6	10.5			0.5	17.5	64.8
SW-2501M	5/4/2026 8:14:55 AM	33.3	53.2	0.4	13.1			0.6	32.8	67.6
SW-2501M	5/1/2026 8:25:32 AM	39.5	53.8	0.6	6.1			0.7	10.2	66.1
SW-2501MD	5/29/2026 7:15:49 AM	13.2	40.0	11.4	35.4			0.3	3.1	76.5
SW-2501MD	5/28/2026 6:14:16 AM	15.7	38.7	10.7	34.9			0.4	3.3	74.9
SW-2501MD	5/27/2026 6:02:25 AM	17.8	40.7	9.7	31.8			0.4	3.3	75.7
SW-2501MD	5/26/2026 6:05:27 AM	15.9	40.1	10.0	34.0			0.4	3.4	72.4
SW-2501MD	5/22/2026 6:16:46 AM	15.0	38.1	10.3	36.6			0.4	3.6	70.5
SW-2501MD	5/21/2026 6:32:26 AM	14.7	39.6	10.1	35.6			0.4	3.5	76.6
SW-2501MD	5/20/2026 8:28:56 AM	17.0	39.6	9.9	33.5			0.4	3.4	78.9
SW-2501MD	5/19/2026 8:58:19 AM	12.8	36.0	10.5	40.7			0.4	3.9	79.9
SW-2501MD	5/18/2026 8:41:43 AM	13.1	36.2	11.1	39.6			0.4	3.6	77.5
SW-2501MD	5/14/2026 8:16:25 AM	13.8	38.5	10.0	37.7			0.4	3.8	77.9
SW-2501MD	5/13/2026 8:06:36 AM	11.7	31.3	12.5	44.5			0.4	3.6	77.1
SW-2501MD	5/12/2026 9:12:49 AM	13.1	32.7	11.1	43.1			0.4	3.9	77.3

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
SW-2501MD	5/11/2026 8:21:50 AM	11.6	31.1	11.8	45.5			0.4	3.9	78.1
SW-2501MD	5/8/2026 9:32:28 AM	13.3	36.4	10.9	39.4			0.4	3.6	76.7
SW-2501MD	5/7/2026 8:53:13 AM	13.9	37.1	10.4	38.6			0.4	3.7	77.1
SW-2501MD	5/6/2026 8:45:13 AM	11.7	31.4	12.5	44.4			0.4	3.6	76.6
SW-2501MD	5/5/2026 8:27:56 AM	12.1	33.1	12.4	42.4			0.4	3.4	76.4
SW-2501MD	5/4/2026 8:17:07 AM	12.4	32.3	12.3	43.0			0.4	3.5	76.4
SW-2501MD	5/1/2026 8:27:27 AM	16.5	31.0	12.2	40.3			0.5	3.3	76.7
SW-2501S	5/29/2026 7:18:48 AM	0.4	7.1	21.0	71.5			0.1	3.4	66.2
SW-2501S	5/28/2026 6:18:35 AM	0.2	0.3	22.3	77.2			0.7	3.5	65.4
SW-2501S	5/27/2026 6:06:12 AM	0.4	0.9	21.4	77.3			0.4	3.6	68.3
SW-2501S	5/26/2026 6:14:28 AM	0.1	0.3	21.9	77.7			0.3	3.5	68.3
SW-2501S	5/22/2026 6:22:20 AM	0.0	1.4	21.8	76.8			0.0	3.5	69.5
SW-2501S	5/21/2026 6:38:09 AM	0.1	1.5	21.4	77.0			0.1	3.6	71.2
SW-2501S	5/20/2026 8:33:18 AM	0.4	0.3	20.7	78.6			1.3	3.8	72.6
SW-2501S	5/19/2026 9:04:28 AM	0.1	5.2	19.6	75.1			0.0	3.8	72.4
SW-2501S	5/18/2026 8:47:27 AM	0.1	5.5	20.3	74.1			0.0	3.7	70.4
SW-2501S	5/15/2026 9:27:58 AM	23.0	75.7	0.0	1.3			0.3	0.0	75.8
SW-2501S	5/15/2026 9:22:25 AM	1.0	5.0	21.2	72.8			0.2	3.4	71.8
SW-2501S	5/14/2026 8:22:49 AM	0.1	7.0	19.4	73.5			0.0	3.8	71.3
SW-2501S	5/13/2026 8:12:06 AM	0.0	1.9	21.5	76.6			0.0	3.6	72.6
SW-2501S	5/12/2026 9:17:43 AM	0.1	2.3	20.4	77.2			0.0	3.8	74.8
SW-2501S	5/11/2026 8:26:36 AM	0.1	3.1	20.5	76.3			0.0	3.7	73.3
SW-2501S	5/8/2026 9:39:11 AM	0.1	0.8	21.1	78.0			0.1	3.7	73.0
SW-2501S	5/7/2026 9:00:17 AM	0.0	0.3	21.1	78.6			0.0	3.7	70.2
SW-2501S	5/6/2026 8:51:41 AM	0.0	1.5	21.6	76.9			0.0	3.6	66.4
SW-2501S	5/5/2026 8:36:07 AM	0.0	2.6	21.8	75.6			0.0	3.5	66.3
SW-2501S	5/4/2026 8:22:18 AM	0.2	7.4	20.6	71.8			0.0	3.5	67.3
SW-2501S	5/1/2026 8:30:42 AM	0.5	0.7	21.2	77.6			0.7	3.7	68.6

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
SW-2502D	5/29/2026 7:02:56 AM	9.9	87.3	0.0	2.8			0.1	0.0	71.6
SW-2502D	5/28/2026 6:27:56 AM	9.1	72.6	1.0	17.3			0.1	17.3	64.5
SW-2502D	5/27/2026 6:15:12 AM	12.4	86.3	0.0	1.3			0.1	0.0	70.4
SW-2502D	5/26/2026 6:28:54 AM	11.6	85.6	0.0	2.8			0.1	0.0	69.2
SW-2502D	5/22/2026 6:34:30 AM	10.6	86.3	0.0	3.1			0.1	0.0	68.6
SW-2502D	5/21/2026 6:50:59 AM	10.8	86.3	0.0	2.9			0.1	0.0	71.1
SW-2502D	5/20/2026 8:15:28 AM	11.8	88.2	0.0	0.0			0.1	0.0	75.0
SW-2502D	5/19/2026 9:17:49 AM	9.5	88.5	0.0	2.0			0.1	0.0	77.8
SW-2502D	5/18/2026 8:59:18 AM	9.9	85.2	0.0	4.9			0.1	0.0	74.1
SW-2502D	5/15/2026 9:08:52 AM	11.8	88.2	0.0	0.0			0.1	0.0	73.2
SW-2502D	5/14/2026 8:37:14 AM	10.0	87.2	0.0	2.8			0.1	0.0	72.3
SW-2502D	5/13/2026 8:21:57 AM	10.1	89.5	0.0	0.4			0.1	0.0	74.4
SW-2502D	5/12/2026 9:27:18 AM	10.7	87.7	0.0	1.6			0.1	0.0	77.1
SW-2502D	5/11/2026 8:36:30 AM	9.8	87.9	0.0	2.3			0.1	0.0	76.6
SW-2502D	5/8/2026 9:49:11 AM	9.9	89.8	0.0	0.3			0.1	0.0	74.6
SW-2502D	5/7/2026 9:13:11 AM	10.0	88.9	0.0	1.1			0.1	0.0	74.3
SW-2502D	5/6/2026 9:03:29 AM	9.9	90.1	0.0	0.0			0.1	0.0	72.1
SW-2502D	5/5/2026 8:48:17 AM	10.1	88.4	0.0	1.5			0.1	0.0	72.4
SW-2502D	5/4/2026 8:29:47 AM	11.1	80.2	0.0	8.7			0.1	0.0	69.9
SW-2502D	5/1/2026 8:39:01 AM	15.4	84.2	0.0	0.4			0.2	0.0	72.6
SW-2502M	5/29/2026 6:58:21 AM	16.0	73.8	0.0	10.2			0.2	0.0	72.9
SW-2502M	5/28/2026 6:26:04 AM	16.6	75.4	0.0	8.0			0.2	0.0	71.9
SW-2502M	5/27/2026 6:13:20 AM	18.0	75.9	0.0	6.1			0.2	0.0	73.9
SW-2502M	5/26/2026 6:25:59 AM	16.8	76.1	0.0	7.1			0.2	0.0	76.0
SW-2502M	5/22/2026 6:31:26 AM	16.0	76.2	0.0	7.8			0.2	0.0	70.3
SW-2502M	5/21/2026 6:48:59 AM	17.1	77.0	0.0	5.9			0.2	0.0	77.6
SW-2502M	5/20/2026 8:13:58 AM	18.1	81.3	0.0	0.6			0.2	0.0	77.7
SW-2502M	5/19/2026 9:14:46 AM	15.2	83.9	0.0	0.9			0.2	0.0	79.8
SW-2502M	5/18/2026 8:56:28 AM	15.4	79.4	0.0	5.2			0.2	0.0	76.6
SW-2502M	5/15/2026 9:04:47 AM	17.5	82.5	0.0	0.0			0.2	0.0	75.9
SW-2502M	5/14/2026 8:34:30 AM	16.2	79.3	0.0	4.5			0.2	0.0	76.3
SW-2502M	5/13/2026 8:19:53 AM	16.1	82.2	0.0	1.7			0.2	0.0	77.1

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
SW-2502M	5/12/2026 9:25:33 AM	16.2	82.8	0.0	1.0			0.2	0.0	78.7
SW-2502M	5/11/2026 8:34:43 AM	15.5	82.6	0.0	1.9			0.2	0.0	77.3
SW-2502M	5/8/2026 9:47:15 AM	15.4	84.5	0.0	0.1			0.2	0.0	74.7
SW-2502M	5/7/2026 9:10:36 AM	16.1	82.5	0.0	1.4			0.2	0.0	72.4
SW-2502M	5/6/2026 9:01:23 AM	16.5	82.0	0.0	1.5			0.2	0.0	71.0
SW-2502M	5/5/2026 8:46:24 AM	16.1	82.3	0.0	1.6			0.2	0.0	71.8
SW-2502M	5/4/2026 8:28:19 AM	17.1	79.1	0.0	3.8			0.2	0.0	71.9
SW-2502M	5/1/2026 8:36:49 AM	22.4	76.5	0.0	1.1			0.3	0.0	72.2
SW-2502MD	5/29/2026 7:08:57 AM	7.6	39.7	12.2	40.5			0.2	3.3	77.6
SW-2502MD	5/28/2026 6:29:56 AM	9.6	37.6	11.3	41.5			0.3	3.7	75.6
SW-2502MD	5/27/2026 6:16:47 AM	11.6	43.5	9.2	35.7			0.3	3.9	75.2
SW-2502MD	5/26/2026 6:31:21 AM	10.0	42.2	10.0	37.8			0.2	3.8	77.6
SW-2502MD	5/22/2026 6:36:17 AM	9.1	41.7	10.5	38.7			0.2	3.7	76.9
SW-2502MD	5/21/2026 6:52:38 AM	9.0	40.5	10.4	40.1			0.2	3.9	77.0
SW-2502MD	5/20/2026 8:17:46 AM	10.3	42.1	9.8	37.8			0.2	3.9	79.6
SW-2502MD	5/19/2026 9:20:34 AM	7.7	43.5	10.4	38.4			0.2	3.7	82.2
SW-2502MD	5/18/2026 9:02:05 AM	6.5	39.1	11.7	42.7			0.2	3.6	79.7
SW-2502MD	5/15/2026 9:12:10 AM	7.1	33.5	13.6	45.8			0.2	3.4	78.6
SW-2502MD	5/14/2026 8:39:47 AM	8.7	44.9	9.3	37.1			0.2	4.0	79.1
SW-2502MD	5/13/2026 8:24:00 AM	5.2	33.1	13.7	48.0			0.2	3.5	78.8
SW-2502MD	5/12/2026 9:28:53 AM	6.7	38.1	11.6	43.6			0.2	3.8	80.0
SW-2502MD	5/11/2026 8:38:07 AM	6.4	40.6	11.1	41.9			0.2	3.8	78.9
SW-2502MD	5/8/2026 9:51:10 AM	8.8	49.1	9.3	32.8			0.2	3.5	79.1
SW-2502MD	5/7/2026 9:14:39 AM	9.0	53.0	8.6	29.4			0.2	3.4	77.2
SW-2502MD	5/6/2026 9:05:22 AM	5.5	34.6	13.2	46.7			0.2	3.5	77.1
SW-2502MD	5/5/2026 8:50:15 AM	5.8	35.0	13.2	46.0			0.2	3.5	77.5
SW-2502MD	5/4/2026 8:31:32 AM	5.8	36.0	12.9	45.3			0.2	3.5	77.9

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
SW-2502MD	5/1/2026 8:41:00 AM	9.1	32.9	13.1	44.9			0.3	3.4	77.8
SW-2502S	5/29/2026 6:54:54 AM	0.1	9.6	20.8	69.5			0.0	3.3	73.3
SW-2502S	5/28/2026 6:24:10 AM	0.2	0.1	22.2	77.5			2.0	3.5	65.1
SW-2502S	5/27/2026 6:11:24 AM	0.4	0.2	21.4	78.0			2.0	3.6	70.6
SW-2502S	5/26/2026 6:23:43 AM	0.1	0.1	21.9	77.9			1.0	3.6	70.5
SW-2502S	5/22/2026 6:29:06 AM	0.0	0.3	21.9	77.8			0.0	3.6	69.4
SW-2502S	5/21/2026 6:47:21 AM	0.0	0.2	21.7	78.1			0.0	3.6	75.0
SW-2502S	5/20/2026 8:12:10 AM	0.3	0.9	20.6	78.2			0.3	3.8	73.8
SW-2502S	5/19/2026 9:11:46 AM	0.0	0.8	20.4	78.8			0.0	3.9	73.4
SW-2502S	5/18/2026 8:53:31 AM	0.0	1.1	21.1	77.8			0.0	3.7	74.8
SW-2502S	5/15/2026 9:00:33 AM	0.2	0.6	21.8	77.4			0.3	3.6	74.8
SW-2502S	5/14/2026 8:31:19 AM	0.0	1.6	20.3	78.1			0.0	3.8	74.6
SW-2502S	5/13/2026 8:17:54 AM	0.0	0.4	21.8	77.8			0.0	3.6	75.5
SW-2502S	5/12/2026 9:23:35 AM	0.0	0.4	20.6	79.0			0.0	3.8	75.0
SW-2502S	5/11/2026 8:32:32 AM	0.0	1.0	20.7	78.3			0.0	3.8	75.6
SW-2502S	5/8/2026 9:44:33 AM	0.1	0.3	21.2	78.4			0.3	3.7	73.8
SW-2502S	5/7/2026 9:08:55 AM	0.0	0.1	21.1	78.8			0.0	3.7	71.8
SW-2502S	5/6/2026 8:59:15 AM	0.0	0.4	21.7	77.9			0.0	3.6	68.9
SW-2502S	5/5/2026 8:44:34 AM	0.0	1.5	21.8	76.7			0.0	3.5	68.8
SW-2502S	5/4/2026 8:26:37 AM	0.0	2.0	21.4	76.6			0.0	3.6	69.0
SW-2502S	5/1/2026 8:35:09 AM	0.6	0.2	21.1	78.1			3.0	3.7	68.7
SW-2503D	5/12/2026 8:21:40 AM	3.9	6.6	18.6	70.9			0.6	3.8	80.5
SW-2503D	5/4/2026 8:56:42 AM	13.2	9.3	10.4	67.1			1.4	6.5	69.8
SW-2503M	5/12/2026 8:27:21 AM	25.9	53.2	0.0	20.9			0.5	0.0	75.2
SW-2503M	5/4/2026 9:01:03 AM	23.9	45.6	0.0	30.5			0.5	0.0	73.9
SW-2503MD	5/12/2026 8:24:48 AM	15.9	7.2	9.0	67.9			2.2	7.5	77.0
SW-2503MD	5/4/2026 8:58:22 AM	4.0	5.2	19.5	71.3			0.8	3.7	76.2
SW-2503S	5/12/2026 8:35:33 AM	0.2	0.6	20.5	78.7			0.3	3.8	80.5
SW-2503S	5/4/2026 9:03:12 AM	0.6	5.7	20.4	73.3			0.1	3.6	79.7

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
SW-2504D	5/12/2026 8:47:37 AM	0.1	0.5	20.3	79.1			0.2	3.9	82.3
SW-2504D	5/4/2026 9:08:28 AM	0.1	1.2	21.1	77.6			0.1	3.7	78.9
SW-2504M	5/12/2026 8:49:55 AM	25.6	3.3	9.5	61.6			7.8	6.5	79.9
SW-2504M	5/4/2026 9:18:12 AM	21.4	2.4	11.6	64.6			8.9	5.6	80.5
SW-2504MD	5/20/2026 1:56:54 PM	13.0	62.0	1.3	23.7			0.2	18.2	132.1
SW-2504MD	5/12/2026 8:55:07 AM	2.1	8.3	16.9	72.7			0.3	4.3	78.2
SW-2504MD	5/4/2026 9:22:21 AM	1.4	7.1	18.1	73.4			0.2	4.1	73.0
SW-2504S	5/12/2026 8:51:59 AM	3.1	0.8	19.3	76.8			3.9	4.0	81.1
SW-2504S	5/4/2026 9:20:08 AM	2.6	0.7	20.4	76.3			3.7	3.7	75.4
SW-30	5/22/2026 6:43:04 AM	3.2	22.7	16.3	57.8			0.1	3.5	52.9
SW-30	5/21/2026 7:02:29 AM	7.9	46.6	10.6	34.9			0.2	3.3	60.0
SW-30	5/20/2026 8:03:41 AM	5.9	25.8	14.5	53.8			0.2	3.7	73.3
SW-30	5/19/2026 9:31:23 AM	0.0	0.6	20.7	78.7			0.0	3.8	83.3
SW-30	5/18/2026 9:09:16 AM	12.7	54.3	1.1	31.9			0.2	29.0	79.8
SW-30	5/15/2026 8:48:17 AM	13.5	55.0	1.6	29.9			0.2	18.7	71.6
SW-30	5/14/2026 8:48:35 AM	2.3	24.5	15.8	57.4			0.1	3.6	75.7
SW-30	5/13/2026 8:34:30 AM	11.3	52.2	1.6	34.9			0.2	21.8	67.7
SW-30	5/12/2026 9:39:11 AM	12.2	53.2	1.5	33.1			0.2	22.1	81.8
SW-30	5/11/2026 8:48:10 AM	11.6	51.2	1.5	35.7			0.2	23.8	85.6
SW-30	5/8/2026 10:07:17 AM	12.3	55.3	1.3	31.1			0.2	23.9	83.2
SW-30	5/7/2026 9:27:26 AM	11.2	54.6	1.4	32.8			0.2	23.4	85.5
SW-30	5/6/2026 9:14:39 AM	10.1	52.9	1.9	35.1			0.2	18.5	78.3
SW-30	5/5/2026 9:02:34 AM	10.1	51.9	2.0	36.0			0.2	18.0	66.8
SW-30	5/4/2026 8:36:47 AM	11.0	44.9	2.0	42.1			0.2	21.1	69.8
SW-30	5/1/2026 8:52:33 AM	13.8	46.8	2.0	37.4			0.3	18.7	77.5
SW-32	5/22/2026 6:47:07 AM	38.8	49.8	2.7	8.7			0.8	3.2	52.4
SW-32	5/21/2026 7:10:28 AM	40.3	50.7	1.4	7.6			0.8	5.4	69.1
SW-32	5/20/2026 7:45:31 AM	28.3	35.3	8.5	27.9			0.8	3.3	73.0
SW-32	5/19/2026 9:36:21 AM	1.4	1.6	19.8	77.2			0.9	3.9	90.2

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [ ]
SW-32	5/18/2026 9:14:33 AM	39.4	52.2	0.8	7.6			0.8	9.5	83.5
SW-32	5/15/2026 8:38:38 AM	40.8	54.3	1.0	3.9			0.8	3.9	71.0
SW-32	5/14/2026 8:53:16 AM	11.2	16.5	13.6	58.7			0.7	4.3	82.8
SW-32	5/13/2026 8:29:37 AM	31.4	47.0	2.3	19.3			0.7	8.4	64.2
SW-32	5/12/2026 9:35:51 AM	38.7	52.2	1.1	8.0			0.7	7.3	86.0
SW-32	5/11/2026 8:43:32 AM	36.0	53.6	1.2	9.2			0.7	7.7	76.0
SW-32	5/8/2026 10:02:48 AM	36.5	52.7	1.4	9.4			0.7	6.7	85.0
SW-32	5/7/2026 9:20:49 AM	33.4	50.9	0.9	14.8			0.7	16.4	88.0
SW-32	5/6/2026 9:10:33 AM	13.3	34.6	5.4	46.7			0.4	8.6	80.0
SW-32	5/5/2026 8:56:30 AM	29.4	45.3	2.9	22.4			0.6	7.7	62.9
SW-32	5/4/2026 8:41:26 AM	33.7	47.7	1.0	17.6			0.7	17.6	82.3
SW-32	5/1/2026 8:45:18 AM	35.3	43.3	2.6	18.8			0.8	7.2	75.0
SW-64	5/22/2026 6:40:52 AM	14.0	81.6	0.2	4.2			0.2	21.0	55.3
SW-64	5/21/2026 6:58:46 AM	14.0	82.9	0.1	3.0			0.2	30.0	62.7
SW-64	5/20/2026 8:05:22 AM	15.9	83.3	0.8	0.0			0.2	0.0	75.2
SW-64	5/19/2026 9:28:23 AM	0.6	3.6	19.7	76.1			0.2	3.9	88.2
SW-64	5/18/2026 9:06:40 AM	10.5	66.2	4.7	18.6			0.2	4.0	78.7
SW-64	5/15/2026 8:53:43 AM	11.0	65.5	5.6	17.9			0.2	3.2	67.8
SW-64	5/15/2026 8:43:20 AM	11.2	65.1	5.5	18.2			0.2	3.3	68.3
SW-64	5/14/2026 8:44:43 AM	13.6	81.2	0.9	4.3			0.2	4.8	77.6
SW-64	5/13/2026 8:36:34 AM	7.7	54.1	8.4	29.8			0.1	3.5	64.9
SW-64	5/12/2026 9:41:18 AM	9.2	57.2	6.8	26.8			0.2	3.9	86.0
SW-64	5/11/2026 8:51:06 AM	7.9	54.4	7.7	30.0			0.1	3.9	88.6
SW-64	5/8/2026 10:09:00 AM	9.1	61.0	6.2	23.7			0.1	3.8	84.0
SW-64	5/7/2026 9:29:18 AM	8.9	60.9	6.4	23.8			0.1	3.7	86.9
SW-64	5/6/2026 9:16:27 AM	7.4	52.5	9.6	30.5			0.1	3.2	78.6
SW-64	5/5/2026 9:04:48 AM	7.8	55.6	8.0	28.6			0.1	3.6	64.0

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
SW-64	5/4/2026 8:34:50 AM	7.9	47.7	9.1	35.3			0.2	3.9	66.7
SW-64	5/1/2026 8:47:28 AM	9.8	46.9	9.8	33.5			0.2	3.4	76.3
SW-65	5/11/2026 9:04:20 AM	49.8	37.6	0.0	12.6			1.3	0.0	86.8
SW-66	5/15/2026 9:29:15 AM	12.3	14.8	9.9	63.0			0.8	6.4	86.2
SW-66	5/15/2026 9:27:52 AM	12.2	14.8	9.9	63.1			0.8	6.4	86.3
SW-68	5/22/2026 6:45:28 AM	10.3	43.5	10.0	36.2			0.2	3.6	52.3
SW-68	5/21/2026 7:08:10 AM	8.8	30.1	13.1	48.0			0.3	3.7	65.1
SW-68	5/20/2026 7:47:12 AM	3.7	10.4	18.6	67.3			0.4	3.6	72.0
SW-68	5/19/2026 9:34:10 AM	0.0	0.3	20.7	79.0			0.0	3.8	88.3
SW-68	5/18/2026 9:11:53 AM	22.7	72.6	0.0	4.7			0.3	0.0	78.5
SW-68	5/15/2026 8:34:05 AM	25.3	74.2	0.3	0.2			0.3	0.7	72.3
SW-68	5/14/2026 8:50:57 AM	1.2	9.5	18.8	70.5			0.1	3.8	80.7
SW-68	5/13/2026 8:31:50 AM	22.2	73.8	0.1	3.9			0.3	39.0	68.7
SW-68	5/12/2026 9:37:18 AM	23.7	72.0	0.1	4.2			0.3	42.0	80.7
SW-68	5/11/2026 8:45:53 AM	21.9	71.8	0.5	5.8			0.3	11.6	83.4
SW-68	5/8/2026 10:04:26 AM	23.0	75.2	0.0	1.8			0.3	0.0	82.4
SW-68	5/7/2026 9:24:55 AM	22.2	76.5	0.0	1.3			0.3	0.0	84.4
SW-68	5/6/2026 9:12:20 AM	22.8	74.8	0.1	2.3			0.3	23.0	78.9
SW-68	5/5/2026 8:59:48 AM	21.8	74.4	0.5	3.3			0.3	6.6	67.9
SW-68	5/4/2026 8:39:10 AM	23.3	70.8	0.5	5.4			0.3	10.8	70.5
SW-68	5/1/2026 8:43:53 AM	28.6	67.6	0.3	3.5			0.4	11.7	75.4
SW-7	5/1/2026 7:54:58 AM	0.6	0.5	20.9	78.0			1.2	3.7	66.7
SW-70	5/4/2026 9:33:46 AM	17.0	68.8	0.0	14.2			0.2	0.0	73.2
SW-71	5/6/2026 8:31:08 AM	10.7	17.4	7.2	64.7			0.6	9.0	73.2
SW-71	5/6/2026 8:23:03 AM	11.1	18.8	7.1	63.0			0.6	8.9	73.3
SW-72	5/6/2026 9:25:28 AM	6.8	18.9	3.3	71.0			0.4	21.5	78.8
SW-80	5/12/2026 1:23:15 PM	34.2	32.0	0.0	33.8			1.1	1691.0	82.8
SW-9	5/4/2026 9:35:40 AM	1.8	28.1	10.0	60.1			0.1	6.0	81.4
TC-1961C	5/4/2026 11:11:27 AM	27.3	36.3	0.0	36.4			0.8	0.0	92.5
TC-1961E	5/4/2026 10:42:18 AM	51.9	44.5	0.0	3.6			1.2	0.0	114.5
TC-2174	5/26/2026 9:02:15 AM	2.6	76.4	0.0	21.0			0.0	0.0	183.1
TC-2174	5/18/2026 9:25:30 AM	18.3	75.6	0.0	6.1			0.2	0.0	182.9

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
TC-2174	5/18/2026 9:25:00 AM					1900				
TC-2174	5/18/2026 9:24:46 AM	19.0	75.0	0.0	6.0			0.3	0.0	183.2
TC-2174	5/12/2026 9:30:00 AM					854				
TC-2174	5/12/2026 9:24:37 AM	21.9	78.1	0.0	0.0			0.3	0.0	183.1
TC-2174	5/5/2026 8:40:00 AM					2130				
TC-2174	5/5/2026 8:40:00 AM						159000			
TC-2174	5/5/2026 8:34:39 AM	4.5	81.5	0.0	14.0			0.1	0.0	182.7
VL-02	5/28/2026 3:26:30 PM	53.9	35.0	2.4	8.7			1.5	3.6	88.4
WTD-01	5/21/2026 5:51:51 AM	15.3	33.9	10.4	40.4			0.5	3.9	139.9
WTD-01	5/21/2026 5:51:17 AM	15.5	32.4	10.5	41.6			0.5	4.0	140.0
WTD-01	5/1/2026 7:48:21 AM	20.7	38.7	8.5	32.1			0.5	3.8	141.4
WTD-01	5/1/2026 7:47:42 AM	20.5	37.5	8.5	33.5			0.5	3.9	141.3
WTD-02	5/21/2026 5:58:44 AM	9.4	47.2	7.5	35.9			0.2	4.8	155.3
WTD-02	5/21/2026 5:58:19 AM	9.4	45.7	7.5	37.4			0.2	5.0	155.3
WTD-02	5/13/2026 1:51:34 PM	11.2	46.7	7.2	34.9			0.2	4.8	154.9
WTD-02	5/13/2026 1:50:30 PM	11.0	46.5	7.3	35.2			0.2	4.8	154.8
WTD-02	5/6/2026 1:50:52 PM	13.2	52.4	5.2	29.2			0.3	5.6	156.2
WTD-02	5/6/2026 1:50:00 PM					1080				
WTD-02	5/6/2026 1:50:00 PM						76800			
WTD-02	5/6/2026 1:49:41 PM	13.5	52.1	5.2	29.2			0.3	5.6	156.2
WTD-03	5/21/2026 6:07:17 AM	1.5	11.6	18.2	68.7			0.1	3.8	112.5
WTD-03	5/21/2026 6:06:19 AM	1.5	12.3	18.5	67.7			0.1	3.7	112.5
WTD-03	5/1/2026 8:09:37 AM	4.1	11.7	17.9	66.3			0.4	3.7	119.0
WTD-03	5/1/2026 8:08:56 AM	4.0	11.2	18.0	66.8			0.4	3.7	118.8
WTD-04	5/21/2026 6:19:17 AM	0.3	1.4	20.9	77.4			0.2	3.7	60.1
WTD-04	5/21/2026 6:16:55 AM	0.3	1.4	21.1	77.2			0.2	3.7	60.2
WTD-04	5/1/2026 8:15:02 AM	0.6	0.8	21.2	77.4			0.8	3.7	64.3
WTD-04	5/1/2026 8:14:32 AM	0.6	0.8	21.2	77.4			0.8	3.7	63.9
WTD-05	5/21/2026 6:13:19 AM	0.9	4.1	19.8	75.2			0.2	3.8	67.3
WTD-05	5/21/2026 6:12:45 AM	0.9	4.0	19.9	75.2			0.2	3.8	67.2
WTD-05	5/1/2026 8:12:57 AM	2.0	3.4	20.0	74.6			0.6	3.7	71.9
WTD-05	5/1/2026 8:12:16 AM	1.8	2.7	20.0	75.5			0.7	3.8	72.6
WTD-06	5/21/2026 6:21:19 AM	2.4	6.6	18.1	72.9			0.4	4.0	110.8
WTD-06	5/21/2026 6:20:59 AM	2.3	6.3	18.2	73.2			0.4	4.0	110.8

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]
WTD-06	5/1/2026 8:20:07 AM	5.2	9.7	17.2	67.9			0.5	3.9	116.8
WTD-06	5/1/2026 8:17:56 AM	5.1	9.2	17.3	68.4			0.6	4.0	116.6
WTD-07	5/21/2026 6:25:15 AM	0.0	0.0	21.5	78.5				3.7	67.4
WTD-07	5/21/2026 6:24:46 AM	0.0	0.0	21.6	78.4				3.6	67.5
WTD-07	5/1/2026 8:22:32 AM	1.7	2.3	20.2	75.8			0.7	3.8	65.8
WTD-07	5/1/2026 8:21:58 AM	1.5	2.2	20.4	75.9			0.7	3.7	65.6
WTD-10	5/21/2026 7:17:44 AM	15.7	25.4	10.4	48.5			0.6	4.7	110.2
WTD-10	5/21/2026 7:17:13 AM	15.7	25.0	10.4	48.9			0.6	4.7	110.1
WTD-10	5/4/2026 8:01:28 AM	16.9	26.8	10.0	46.3			0.6	4.6	106.3
WTD-10	5/4/2026 8:00:56 AM	16.9	26.0	10.1	47.0			0.7	4.7	106.4

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj °F Temp [ ]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
A-01	5/15/2026 8:51:04 AM	79.4	-16.59	-16.50	0.0	0.0				
A-02	5/11/2026 7:44:04 AM	92.7	-12.16	-12.14	0.0	0.0				
A-03	5/11/2026 7:56:41 AM	75.5	-12.00	-12.18	0.0	0.0				
A-04	5/11/2026 8:06:12 AM	94.6	-8.29	-8.28	0.0	0.0	8.488	7.453		
A-05	5/11/2026 8:01:26 AM	76.3	-11.36	-11.37	0.0	0.0				
B-01	5/11/2026 10:37:28 AM	89.7	-0.19	-0.17	0.0	0.0	-0.042	-0.034	-12.42	
B-02R	5/11/2026 10:34:40 AM	100.0	-0.26	-0.19	0.0	0.0	-0.126	-0.101	-12.25	
B-03R	5/11/2026 10:04:48 AM	83.7	-0.78	-0.73	1.9	1.9	0.372	0.374	-11.95	
B-05	5/11/2026 10:25:34 AM	89.0	-0.34	-0.28	3.5	3.5	0.072	0.072	-11.63	
B-06	5/11/2026 10:19:19 AM	80.0	-0.39	-0.36	5.9	5.8	0.197	0.190	-11.66	
B-07R	5/11/2026 9:31:57 AM	91.1	-0.36	-0.36	2.6	3.6	1.624	3.016	-10.29	
B-08	5/11/2026 10:15:29 AM	88.6	-0.37	-0.32	0.0	0.0	0.226	0.219	-11.76	
B-09	5/11/2026 9:37:05 AM	92.6	-0.21	-0.20	0.0	0.0	0.212	0.210	-12.04	
B-10	5/11/2026 9:24:54 AM	88.5	-0.13	-0.11	0.0	0.0	0.177	0.167	-11.69	
B-11	5/29/2026 3:03:30 PM	96.7	-0.24	-0.24			0.000	0.000	-16.52	-16.24
B-12	5/11/2026 10:00:30 AM	92.9	-0.16	-0.16	2.8	2.4	2.009	1.505	-11.34	
B-13	5/11/2026 9:49:42 AM	87.5	-0.21	-0.17	16.3	15.4	0.078	0.070	-12.09	
B-14	5/29/2026 3:07:12 PM	92.1	-0.98	-0.92	2.5	2.3	0.622	0.562	-15.07	-15.17
C-03	5/11/2026 7:49:46 AM	69.1	-11.67	-12.12	0.0	0.0				
C-07	5/1/2026 3:11:09 PM	88.3	-13.31	-13.32			13.300	13.300	-13.09	-13.08
C-08	5/8/2026 1:03:42 PM	100.4	-7.77	-7.78			7.816	7.877	-7.79	-7.81
C-10	5/11/2026 9:07:51 AM	89.3	-12.95	-12.90	0.0	0.0				
C-11	5/11/2026 8:38:28 AM	83.7	-11.49	-11.48	0.0	0.0	0.069	0.049		
C-12	5/29/2026 12:20:26 PM	84.3	-7.18	-7.52	12.3	12.4	0.909	0.935	-9.22	-9.16
C-12	5/11/2026 1:57:43 PM	99.7	-7.09	-7.09	3.3	3.2	0.067	0.064	-7.73	-7.41
C-15	5/11/2026 2:07:31 PM	95.3	-7.52	-7.53	0.5	0.9	0.000	0.002	-7.42	-7.42
C-17B	5/12/2026 10:45:10 AM	109.9	-7.60	-7.72			7.507	7.592	-8.43	-8.40
C-18	5/12/2026 1:08:06 PM	103.5	-8.73	-8.73			8.844	8.821	-9.06	-9.06
C-19	5/12/2026 12:49:10 PM	99.2	-8.39	-8.39			8.465	8.440	-9.06	-9.06
C-20	5/12/2026 12:57:51 PM	99.0	-8.75	-8.73			8.909	8.882	-8.72	-8.72
C-23	5/12/2026 11:00:46 AM	128.4	-4.39	-4.39			4.422	4.420	-9.49	-9.56
C-24	5/15/2026 9:17:41 AM	103.1	-1.52	-1.50	0.0	0.0	1.557	1.547		
C-25	5/11/2026 2:14:04 PM	97.9	-7.17	-7.09			7.754	7.720	0.67	0.67

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
C-26	5/29/2026 12:46:54 PM	103.6	-7.09	-7.14			7.011	7.119	0.00	0.00
C-26	5/15/2026 9:07:37 AM	78.1	-10.30	-10.20	0.0	0.0				
C-27	5/11/2026 2:04:38 PM	97.2	-2.03	-2.47	0.9	1.6	0.002	0.006	-7.44	-7.43
C-28	5/29/2026 12:16:57 PM	98.9	-10.85	-10.98	28.1	28.3	1.013	1.028	-10.84	-11.09
C-28	5/11/2026 8:35:54 AM	100.1	-11.30	-11.28	0.0	0.0	-0.049	-0.041		
C-29	5/11/2026 8:54:46 AM	107.7	-7.99	-7.98	0.0	0.0	8.136	8.112		
C-30	5/11/2026 8:49:08 AM	126.7	-3.58	-3.56	0.0	0.0	-0.030	-0.015	-9.14	
CV-02	5/11/2026 8:21:58 AM	120.1	-0.36	-0.36	0.0	0.0	-0.038	-0.024	-13.25	
CV-03	5/11/2026 8:18:37 AM	118.9	-5.68	-5.73	15.3	16.6	1.412	1.657	-13.44	
CV-04	5/11/2026 8:14:52 AM	109.1	-1.69	-1.78	14.1	11.8	0.055	0.039		
CV-05	5/8/2026 12:41:33 PM	100.0	-8.11	-8.13	7.5	7.5	1.154	1.171	-8.09	-8.16
CV-06	5/12/2026 8:03:49 AM	90.3	-10.30	-10.28	3.4	3.4	0.072	0.073	-12.49	
CV-108-52	5/19/2026 1:02:47 PM	101.6	-2.70	-2.78			0.563	0.567	-2.90	-3.03
CV-108-52	5/18/2026 11:07:16 AM									
CV-108-52	5/6/2026 8:30:00 AM									
CV-108-52	5/1/2026 10:29:07 AM	99.7	-6.51	-6.42			1.173	1.296	-7.71	-7.62
CV-113	5/26/2026 2:01:29 PM	72.9	-0.39	-0.35	2.2	1.8	0.030	0.019	-3.32	-2.61
CV-113	5/15/2026 9:28:02 AM	66.6	-0.24	-0.23	3.0	2.9	0.052	0.050	-3.12	-3.43
CV-113	5/4/2026 7:50:00 AM									
CV-114	5/26/2026 8:58:28 AM	170.7	-0.17	-0.65			0.154	0.821	0.23	0.24
CV-114	5/18/2026 9:20:17 AM	164.4	1.25	1.34			0.000	0.000	-1.86	-1.82
CV-114	5/18/2026 9:20:00 AM									
CV-114	5/18/2026 9:17:57 AM	163.8	1.57	1.59			0.000	0.000	-1.83	-1.83
CV-114	5/12/2026 9:25:00 AM									
CV-114	5/12/2026 9:22:16 AM	174.3	-1.52	-1.56			1.658	1.701	-5.10	-5.10
CV-114	5/5/2026 8:35:00 AM									
CV-114	5/5/2026 8:35:00 AM									
CV-114	5/5/2026 8:32:18 AM	173.1	-2.04	-2.13			1.906	2.157	-5.67	-5.62
CV-114	5/4/2026 8:05:00 AM									
CV-1424	5/1/2026 11:22:59 AM	105.2	-2.80	-2.79	19.7	19.7	2.280	2.280	-12.70	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-1532A	5/28/2026 8:54:46 AM	66.6	-6.50	-6.24			6.772	6.518	-5.83	-5.42
CV-1532A	5/13/2026 1:09:52 PM	81.7	-4.01	-5.13	0.0	0.0	3.625	5.054	-5.14	
CV-1532A	5/13/2026 1:07:32 PM	81.9	-3.42	-3.87	0.0	0.0	4.299	3.752	-5.11	
CV-1532A	5/11/2026 8:15:00 AM									
CV-1532A	5/11/2026 8:15:00 AM									
CV-1534A-PLR	5/28/2026 1:23:27 PM	185.1	4.04	3.77			0.000	0.000	0.00	0.00
CV-1534A-PLR	5/28/2026 1:20:34 PM	185.9	4.04	4.19			0.000	0.000	0.00	0.00
CV-1534A-PLR	5/20/2026 9:03:59 AM	185.1	3.27	4.63			0.000	0.000	0.21	0.21
CV-1534A-PLR	5/13/2026 9:42:40 AM	184.4	1.96	1.90			0.000	0.000	0.28	0.28
CV-1534A-PLR	5/6/2026 10:03:56 AM	179.3	-0.84	-0.51			0.893	0.473	0.27	0.30
CV-1534A-PLR	5/6/2026 9:55:00 AM									
CV-1534A-PLR	5/6/2026 9:55:00 AM									
CV-1535	5/19/2026 12:55:31 PM	119.5	-0.23	-0.22			0.058	0.050	-3.25	-3.43
CV-1535	5/11/2026 8:25:00 AM									
CV-1535	5/11/2026 8:25:00 AM									
CV-1535	5/1/2026 10:31:55 AM	120.4	-0.90	-0.82			0.638	0.551	-8.20	-8.13
CV-1601D	5/22/2026 10:03:49 AM	111.4	-0.35	-0.40	2.5	9.9	0.120	1.968	-8.77	
CV-1601D	5/4/2026 10:02:19 AM	110.2	-0.38	-0.41	6.0	9.0	0.721	1.636	-10.41	
CV-1601S	5/22/2026 10:00:47 AM	104.5	-0.10	-0.17	2.1	4.0	0.085	0.320	-8.46	
CV-1601S	5/4/2026 9:59:23 AM	101.4	-0.26	-0.27	3.7	3.7	0.281	0.268	-10.85	
CV-1604	5/4/2026 11:02:38 AM	125.5	-1.55	-1.37	3.3	2.2	0.240	0.099	-14.41	-14.37
CV-1701D	5/8/2026 1:23:50 PM	100.5	-0.25	-0.26	0.5	0.8	0.062	0.177	-14.14	-14.23
CV-1701D	5/8/2026 1:22:18 PM	99.0	0.71	-0.25	0.7	0.5	0.118	0.059	-13.11	-13.13
CV-1701D	5/7/2026 11:12:23 AM	91.6	-1.01	-0.98	0.2	0.2	0.008	0.010	-4.74	
CV-1701S	5/7/2026 11:16:55 AM	137.1	-0.83	-0.82	0.0	0.0	-0.029	-0.023	-4.86	
CV-1701S	5/7/2026 11:15:22 AM	138.6	-1.21	-1.11	0.0	0.0	-0.051	-0.010	-4.95	
CV-1901	5/19/2026 10:20:41 AM	107.6	-0.19	-0.18	1.1	1.1	0.027	0.026	-5.38	-5.32
CV-1901	5/19/2026 10:18:56 AM	106.7	0.39	-0.11	1.4	0.9	0.041	0.018	-5.24	-5.29

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-1901	5/12/2026 10:20:03 AM	106.6	-0.11	-0.12	0.0	0.0	-0.029	-0.027	-6.42	
CV-1901	5/12/2026 10:17:30 AM	106.4	0.54	-0.02	0.0	0.0	-0.178	-0.049	-5.88	
CV-1902A	5/28/2026 8:49:43 AM	172.3	-7.63	-7.66			7.675	7.692	-7.45	-7.48
CV-1902A	5/20/2026 8:10:11 AM	157.4	-5.28	-5.26			5.281	5.258	-5.00	-4.98
CV-1902A	5/14/2026 1:48:17 PM	168.6	-5.46	-5.64			5.491	5.604	-5.50	-5.69
CV-1902A	5/11/2026 1:48:31 PM	152.7	-3.48	-3.32			3.400	3.318	9.42	9.42
CV-1902A	5/11/2026 7:55:00 AM									
CV-1902A	5/11/2026 7:55:00 AM									
CV-1902A	5/6/2026 9:06:28 AM	159.6	-6.78	-6.73			6.742	6.696	-6.80	-6.80
CV-1902A	5/6/2026 9:05:00 AM									
CV-1902A	5/6/2026 9:05:00 AM									
CV-1905	5/6/2026 12:45:38 PM	109.4	-1.57	-1.83	3.4	7.0	0.072	0.309	-8.17	-8.09
CV-1905	5/6/2026 10:44:14 AM	104.5	-1.10	-2.17	5.3	8.4	0.169	0.420	-13.38	
CV-2001	5/20/2026 9:55:23 AM	103.3	-4.03	-4.05	21.5	20.7	0.590	0.548	-4.19	-4.10
CV-2001	5/12/2026 8:45:06 AM	76.2	-2.86	-3.81	0.0	0.0	-0.083	-0.092	-4.37	
CV-2001	5/6/2026 7:50:00 AM									
CV-2001	5/6/2026 7:50:00 AM									
CV-2001	5/1/2026 10:12:38 AM	86.2	-6.24	-5.48	5.0	6.4	0.031	0.051	-6.26	-6.58
CV-2002	5/28/2026 10:15:53 AM	182.2	-0.75	-0.81	15.8	16.5	0.749	0.818	-0.97	-1.05
CV-2002	5/28/2026 10:12:21 AM	183.6	0.35	-0.67	3.9	13.4	0.045	0.541	-2.10	-1.90
CV-2002	5/20/2026 9:42:31 AM	178.6	-2.21	-2.02	23.7	21.5	1.686	1.389	-3.82	-3.64
CV-2002	5/20/2026 9:41:05 AM	178.0	-3.15	-2.83	32.8	31.2	3.238	2.938	-4.07	-4.27
CV-2002	5/13/2026 10:09:19 AM	181.8	-0.82	-1.05	23.7	23.4	1.684	1.645	0.23	0.22
CV-2002	5/11/2026 8:10:00 AM									
CV-2002	5/11/2026 8:10:00 AM									
CV-2002	5/6/2026 1:05:00 PM									
CV-2002	5/6/2026 1:05:00 PM									
CV-2002	5/6/2026 1:02:03 PM	181.8	-1.14	-1.31	22.9	21.2	1.571	1.350	-4.81	-4.69
CV-2003	5/19/2026 1:11:41 PM	119.2	-0.07	-0.06	0.4	0.8	0.020	0.064	-4.50	-4.50
CV-2003	5/19/2026 1:06:11 PM	121.5	0.11	-0.10	1.8	1.6	0.341	0.287	-3.61	-3.65

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2003	5/1/2026 10:27:07 AM	118.7	-0.21	-0.20	1.7	1.7	0.305	0.298	-7.82	-7.83
CV-2006	5/28/2026 8:42:46 AM	187.4	-5.22	-5.43	15.8	10.9	0.367	0.174	-8.22	-8.48
CV-2006	5/20/2026 8:18:51 AM	187.5	-3.64	-3.64	17.2	17.2	0.435	0.435	-6.85	-6.85
CV-2006	5/14/2026 2:04:55 PM	184.9	-2.55	-2.56	1.9	8.7	0.007	0.146	-6.01	
CV-2006	5/14/2026 2:03:40 PM	185.4	-4.31	-2.22	7.7	7.7	0.114	0.113	-6.52	
CV-2006	5/11/2026 1:55:37 PM	188.2	2.57	2.99	11.7	10.1	0.198	0.147	4.05	4.05
CV-2006	5/6/2026 9:20:00 AM									
CV-2006	5/6/2026 9:20:00 AM									
CV-2006	5/6/2026 9:17:48 AM	187.5	-2.10	-2.23	5.6	6.1	0.046	0.054	-6.57	-7.38
CV-2007	5/20/2026 2:00:34 PM	112.8	-0.10	-0.11	0.7	3.5	0.001	0.033	-7.42	-9.01
CV-2007	5/8/2026 9:48:29 AM	93.8	-0.01	-0.03	0.0	0.0	-0.055	-0.054	-3.18	
CV-2007	5/4/2026 8:10:00 AM									
CV-2008	5/11/2026 2:03:03 PM	111.4	-0.88	-0.44	2.1	0.4	0.106	0.005	-4.49	
CV-2009	5/8/2026 9:02:48 AM	136.0	-0.11	-0.07	16.0	15.6	0.355	0.336	-1.36	
CV-2009	5/8/2026 9:00:33 AM	136.1	0.54	-0.02	14.4	16.6	0.285	0.380	-1.11	
CV-2009A	5/11/2026 1:51:42 PM	129.8	-0.16	-0.16	6.2	6.2	0.905	0.909	-6.01	
CV-2010	5/4/2026 1:15:27 PM	117.5	-1.88	-1.68	14.1	12.3	0.257	0.196	-12.95	-12.97
CV-2010A	5/21/2026 10:29:08 AM	142.2	-8.80	-8.78	27.0	25.1	2.110	1.833	-9.92	-9.96
CV-2010A	5/14/2026 9:40:00 AM									
CV-2010A	5/14/2026 9:38:44 AM	153.5	11.78	-2.01	2.3	55.1	0.012	8.896	-11.74	-11.83
CV-2010A	5/5/2026 1:03:57 PM	146.5	-1.94	-1.94	11.0	9.8	0.348	0.275	-10.88	-11.65
CV-2010A	5/5/2026 1:03:17 PM	146.3	-1.85	-1.89	8.7	13.1	0.215	0.493	-11.24	-11.37
CV-2010A	5/4/2026 1:29:04 PM	148.2	-0.10	-0.10	16.9	17.7	0.816	0.894	-12.87	-13.21
CV-2010A	5/4/2026 1:27:58 PM	148.1	-0.20	-0.21	14.5	14.6	0.600	0.605	-13.13	-13.24
CV-2010A	5/4/2026 1:26:56 PM	148.6	1.36	-0.10	13.4	19.6	0.510	1.095	-13.13	-13.20
CV-2011	5/11/2026 3:39:24 PM	108.1	-0.31	-0.30	0.0	0.0	-0.014	-0.012	-12.72	
CV-2011	5/11/2026 3:38:18 PM	105.7	0.48	-0.18	0.0	1.7	-0.020	0.004	-12.31	
CV-2011A	5/28/2026 8:38:45 AM	150.4	-4.82	-4.96	130.9	132.4	4.809	4.927	0.27	0.29
CV-2011A	5/27/2026 3:15:12 PM	148.0	-1.15	-1.14	47.9	47.5	0.634	0.623	-3.04	-3.15
CV-2011A	5/27/2026 3:14:19 PM	147.7	-0.62	-1.13	49.1	47.7	0.664	0.628	-3.51	-3.05

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2011A	5/21/2026 9:16:00 AM	151.7	-4.56	-4.52	24.0	22.5	0.160	0.141	-6.65	-6.38
CV-2011A	5/20/2026 8:33:37 AM	151.6	-7.72	-7.72	20.3	18.9	0.283	0.247	-12.73	-11.91
CV-2011A	5/20/2026 8:30:13 AM	151.7	-7.72	-7.73	19.5	20.1	0.263	0.279	-11.84	-12.06
CV-2011A	5/14/2026 9:40:27 AM	153.6	-2.67	-2.53	175.1	169.1	8.637	8.049	-12.33	-11.47
CV-2011A	5/11/2026 10:58:37 AM	153.9	-1.57	-1.56	41.3	41.0	0.472	0.466	-11.42	-11.44
CV-2011A	5/4/2026 8:20:00 AM									
CV-2011A	5/4/2026 8:20:00 AM									
CV-2011A	5/4/2026 8:19:12 AM	151.7	-2.86	-2.86	32.7	31.0	0.295	0.266	-13.16	-13.19
CV-2012	5/11/2026 3:24:22 PM	136.9	-3.75	-3.75	7.6	7.7	0.080	0.082	-10.91	
CV-2012	5/11/2026 3:23:03 PM	137.3	-5.88	-4.36	13.0	6.2	0.235	0.053	-10.83	
CV-2201-PLR	5/19/2026 11:02:27 AM	130.4	-0.73	-0.71			0.503	0.507	-2.13	-2.18
CV-2201-PLR	5/19/2026 10:46:55 AM	130.5	-0.77	-0.47			0.684	0.419	-1.67	-1.74
CV-2201-PLR	5/13/2026 1:54:50 PM	133.1	-0.96	-0.97			0.940	0.949	-2.53	-1.90
CV-2201-PLR	5/13/2026 1:53:35 PM	133.2	-1.08	-0.80			1.008	0.772	-2.56	-2.66
CV-2204-PLR	5/26/2026 1:23:17 PM	155.6	-7.79	-7.07			7.904	7.098	0.71	0.67
CV-2204-PLR	5/18/2026 11:00:00 AM									
CV-2204-PLR	5/18/2026 10:51:06 AM	189.1	-2.25	-2.22			2.310	2.305	0.35	0.35
CV-2204-PLR	5/12/2026 10:45:00 AM									
CV-2204-PLR	5/12/2026 10:44:05 AM	190.0	-7.01	-7.28			7.123	7.387	0.34	0.34
CV-2204-PLR	5/5/2026 9:48:20 AM	190.1	-7.29	-8.83			7.395	8.865	0.01	0.00
CV-2204-PLR	5/5/2026 9:45:00 AM									
CV-2204-PLR	5/5/2026 9:45:00 AM									
CV-2205	5/1/2026 2:09:09 PM		-0.36	-0.36	15.9	15.9	0.065	0.065	-12.64	-12.64
CV-2207	5/11/2026 1:42:35 PM	125.0	-0.94	-0.56	18.1	16.1	0.083	0.066	-8.87	
CV-2207	5/11/2026 1:19:38 PM	127.2	-1.08	-1.02	8.3	11.2	0.018	0.033	0.64	0.61
CV-2208A	5/11/2026 11:49:32 AM	134.0	-1.31	-1.32	12.2	12.3	0.043	0.044	-6.59	
CV-2208A	5/11/2026 11:47:10 AM	134.7	-1.27	-1.27	13.3	13.5	0.050	0.052	-6.64	
CV-2301	5/27/2026 10:38:04 AM	158.0	-2.47	-2.44			2.434	2.430	-6.22	-6.32
CV-2301	5/27/2026 10:36:57 AM	158.0	-4.82	-1.81			4.791	1.802	-6.24	-6.22

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2301	5/19/2026 10:16:23 AM		-5.72				5.799		-6.88	
CV-2301	5/19/2026 10:15:36 AM	165.0	-7.06	-5.74			7.053	5.875	-6.74	-6.82
CV-2301	5/19/2026 10:15:00 AM									
CV-2301	5/14/2026 11:20:00 AM									
CV-2301	5/14/2026 10:53:50 AM	182.0	-7.32	-7.34			7.376	7.366	-7.59	-7.56
CV-2301	5/14/2026 10:52:08 AM	182.0	-7.30	-7.24			7.276	7.189	-7.47	-7.33
CV-2301	5/7/2026 7:55:00 AM									
CV-2301	5/7/2026 7:55:00 AM									
CV-2302	5/22/2026 3:57:06 PM	121.0	-5.04	-5.07			5.135	5.088	-5.32	-5.35
CV-2302	5/7/2026 8:05:00 AM									
CV-2302	5/7/2026 8:05:00 AM									
CV-2302	5/4/2026 9:06:38 AM	121.6	-9.44	-9.45			9.620	9.648	-9.66	-9.82
CV-2303	5/27/2026 9:02:45 AM	179.8	-2.09	-2.13			2.014	2.067	0.01	0.01
CV-2303	5/19/2026 8:40:00 AM									
CV-2303	5/19/2026 8:36:23 AM	187.5	-4.52	-4.52			4.498	4.501	-4.26	-4.28
CV-2303	5/13/2026 2:13:55 PM	190.0	-4.70	-4.13			4.721	4.208	-4.68	-4.07
CV-2303	5/12/2026 8:30:00 AM									
CV-2303	5/12/2026 8:30:00 AM									
CV-2303	5/5/2026 2:25:00 PM									
CV-2303	5/5/2026 2:25:00 PM									
CV-2303	5/5/2026 2:21:44 PM	187.7	-3.85	-3.77			3.847	3.710	0.27	0.30
CV-2304	5/19/2026 9:15:00 AM									
CV-2304	5/19/2026 9:14:49 AM	168.5	-2.38	-2.51			2.314	2.356	0.34	0.34
CV-2304	5/13/2026 3:03:41 PM	163.9	-5.65	-5.66			5.854	5.852	0.00	0.00
CV-2304	5/13/2026 3:02:59 PM	161.2	-7.61	-5.44			7.765	5.595	0.00	0.00
CV-2304	5/8/2026 12:51:34 PM	169.9	-5.70	-5.54			5.691	5.519	0.00	0.00
CV-2304	5/8/2026 12:50:06 PM	167.5	-5.71	-5.43			5.760	5.433	-5.64	0.00
CV-2304	5/6/2026 3:00:04 PM	163.7	11.07	11.19			0.000	0.000	11.51	11.50
CV-2304	5/6/2026 3:00:00 PM									
CV-2304	5/6/2026 3:00:00 PM									

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2304	5/6/2026 2:59:41 PM	163.1	11.46	11.51			0.000	0.000	11.63	11.66
CV-2305	5/27/2026 2:24:19 PM	149.4	2.23	2.20			0.000	0.000	2.14	2.09
CV-2305	5/27/2026 2:23:44 PM	149.3	2.27	1.95			0.000	0.000	2.18	2.16
CV-2305	5/19/2026 1:20:00 PM									
CV-2305	5/19/2026 1:19:18 PM	149.2	-0.17	-0.60			0.119	0.826	-0.74	-1.01
CV-2305	5/14/2026 10:11:00 AM									
CV-2305	5/14/2026 10:09:35 AM	150.3	-1.47	-1.47			1.475	1.475	-1.89	-1.89
CV-2305	5/12/2026 8:10:00 AM									
CV-2305	5/12/2026 8:10:00 AM									
CV-2305	5/4/2026 8:50:00 AM	149.9	-1.66	-1.01			1.681	1.122	-1.61	-1.69
CV-2306	5/26/2026 1:28:47 PM	149.1	-8.35	-8.35			8.434	8.434	0.99	0.99
CV-2306	5/18/2026 11:00:16 AM	133.9	-4.06	-4.67			4.078	4.575	0.34	0.35
CV-2306	5/18/2026 10:56:22 AM	102.9	-3.87	-4.19			4.155	4.690	0.42	0.34
CV-2306	5/12/2026 10:50:18 AM	178.3	-9.29	-9.23			9.437	9.385	0.33	0.33
CV-2306	5/12/2026 10:50:00 AM									
CV-2306	5/5/2026 9:52:13 AM	173.6	-9.33	-9.36			9.490	9.527	0.00	0.00
CV-2306	5/5/2026 9:50:00 AM									
CV-2306	5/5/2026 9:50:00 AM									
CV-2308-PLR	5/19/2026 10:58:26 AM	136.5	-1.76	-1.81			1.750	1.724	-4.15	-4.72
CV-2308-PLR	5/19/2026 10:56:56 AM	133.9	-2.27	-1.43			2.121	1.440	-4.38	-4.16
CV-2308-PLR	5/13/2026 2:03:12 PM	143.9	-1.71	-1.66			1.608	1.593	-3.86	-3.96
CV-2308-PLR	5/13/2026 2:01:38 PM	146.4	-3.18	-1.58			3.087	1.533	-3.98	-4.25
CV-2310-PLR	5/27/2026 9:22:17 AM	196.1	-1.24	-1.24			1.216	1.216	0.19	0.19
CV-2310-PLR	5/19/2026 8:56:41 AM	197.9	-0.21	-2.46			0.099	2.350	0.34	0.34
CV-2310-PLR	5/19/2026 8:55:00 AM									
CV-2310-PLR	5/13/2026 2:22:47 PM	197.5	-1.78	-2.08			1.813	2.337	-0.04	0.00
CV-2310-PLR	5/6/2026 2:40:00 PM									

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2310-PLR	5/6/2026 2:30:00 PM									
CV-2310-PLR	5/6/2026 2:26:12 PM	197.3	-1.08	-2.54			1.010	2.676	0.08	0.00
CV-2310-PLR	5/1/2026 11:45:33 AM	197.2	-4.35	-4.06			4.114	3.201	0.67	0.65
CV-2310-PLR	5/1/2026 11:44:42 AM	197.3	-4.23	-4.10			4.033	4.799	0.65	0.69
CV-2311	5/26/2026 2:01:48 PM	162.4	-3.39	-3.36			3.396	3.358	0.86	0.83
CV-2311	5/18/2026 2:25:36 PM	183.3	-3.81	-3.81			3.993	3.993	0.33	0.33
CV-2311	5/18/2026 2:25:00 PM									
CV-2311	5/18/2026 2:24:18 PM	163.7	4.39	4.34			0.000	0.000	2.33	2.31
CV-2311	5/12/2026 2:05:46 PM	165.1	-1.78	-1.81			1.722	1.717	-7.19	-6.93
CV-2311	5/12/2026 2:03:19 PM	163.6	-2.48	-2.01			2.409	1.934	-7.09	-7.20
CV-2311	5/12/2026 2:00:00 PM									
CV-2311	5/5/2026 10:25:04 AM	166.9	-2.53	-2.52			2.525	2.518	-8.39	-8.32
CV-2311	5/5/2026 10:25:00 AM									
CV-2311	5/5/2026 10:25:00 AM									
CV-2312	5/27/2026 11:01:39 AM	167.7	-3.07	-5.30	31.2	41.4	2.922	5.179	-3.98	-4.28
CV-2312	5/19/2026 10:35:25 AM	168.5	-2.64	-1.13	34.1	14.8	3.468	0.647	-5.08	-3.40
CV-2312	5/19/2026 10:35:00 AM									
CV-2312	5/13/2026 11:08:10 AM	169.3	-16.73	-16.28	73.7	72.9	17.149	16.742	-7.70	-6.29
CV-2312	5/13/2026 9:06:06 AM	168.2	-6.54	-4.12	46.2	35.3	6.431	3.725	-8.03	-8.48
CV-2312	5/13/2026 8:30:00 AM									
CV-2312	5/13/2026 8:30:00 AM									
CV-2312	5/4/2026 10:29:04 AM	168.0	27.20	23.82	97.2	90.7	27.050	23.636	-8.85	-9.06
CV-2312	5/4/2026 10:27:12 AM	168.1	23.02	25.84	89.1	94.9	22.809	25.782	-9.17	-9.23
CV-2312	5/4/2026 10:15:00 AM									
CV-2312	5/4/2026 10:15:00 AM									
CV-2314	5/27/2026 1:46:16 PM	179.8	-3.66	-3.61			3.627	3.552	-7.85	-7.78
CV-2314	5/27/2026 1:45:46 PM	179.5	-0.26	-3.78			0.286	3.790	-7.67	-7.11

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2314	5/19/2026 2:00:00 PM									
CV-2314	5/19/2026 1:53:23 PM	180.1	-3.30	-3.03			3.257	3.147	0.00	0.00
CV-2314	5/14/2026 1:50:56 PM	178.0	-2.53	-2.89	0.0	0.0	2.499	2.861	-11.70	
CV-2314	5/14/2026 1:49:32 PM	178.0	-8.65	-2.73	0.0	0.0	8.764	2.495	-11.53	
CV-2314	5/12/2026 8:05:00 AM									
CV-2314	5/12/2026 8:05:00 AM									
CV-2314	5/11/2026 10:32:15 AM	180.2	-2.16	-1.11			2.126	1.008	-13.13	-14.46
CV-2314	5/4/2026 9:40:25 AM	178.1	-2.93	-2.18			2.960	2.480	-13.31	-13.49
CV-2314	5/4/2026 9:40:00 AM									
CV-2314	5/4/2026 9:40:00 AM									
CV-2315	5/26/2026 10:35:23 AM	182.5	-5.71	-5.70			5.715	5.794	0.34	0.36
CV-2315	5/19/2026 1:35:00 PM									
CV-2315	5/19/2026 1:31:37 PM	184.8	-1.16	-1.16			1.126	1.126	0.00	0.00
CV-2315	5/13/2026 1:43:34 PM	178.3	-2.68	-2.67			2.600	2.574	-3.16	-3.11
CV-2315	5/13/2026 1:42:47 PM	177.7	-2.57	-3.27			2.444	3.279	-3.13	-3.76
CV-2315	5/11/2026 8:41:37 AM	156.4	0.34	0.79			0.000	0.000	1.38	1.90
CV-2315	5/7/2026 8:30:00 AM									
CV-2315	5/7/2026 8:30:00 AM									
CV-2315	5/6/2026 3:30:00 PM									
CV-2315	5/6/2026 3:30:00 PM									
CV-2315	5/6/2026 3:27:40 PM	183.9	-2.69	-2.61			2.781	2.680	-4.69	-4.54
CV-2315	5/6/2026 3:25:58 PM	183.9	-0.26	-1.85			0.284	1.822	-5.72	-4.32
CV-2316	5/11/2026 1:59:13 PM	142.0	-0.67	-0.67	11.4	11.4	0.100	0.100	-4.74	
CV-2316	5/11/2026 1:57:51 PM	141.7	-0.66	-0.66	11.5	11.5	0.100	0.100	-5.16	
CV-2319	5/12/2026 8:28:11 AM	142.0	-0.48	-0.47	0.0	0.0			-11.34	
CV-2319	5/12/2026 8:26:00 AM	142.0	-0.51	-0.45	0.0	0.0			-11.08	
CV-2321	5/27/2026 2:51:44 PM	145.7	-3.34	-3.32			0.374	0.314	-9.07	-9.07
CV-2321	5/27/2026 2:50:12 PM	145.8	-4.11	-2.31			1.105	0.702	-9.07	-9.07
CV-2321	5/19/2026 1:00:00 PM									
CV-2321	5/19/2026 12:59:11 PM	149.0	-1.10	-1.07			0.071	0.084	-6.36	-6.22

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2321	5/19/2026 12:56:22 PM	148.9	2.31	-2.14	53.5	5.1	8.196	0.074	-6.06	-5.52
CV-2321	5/11/2026 9:19:14 AM	146.6	-2.88	-2.79	65.7	66.0	12.614	12.724	-15.85	-15.37
CV-2321	5/11/2026 9:16:26 AM	146.2	-13.09	-1.90			2.309	13.293	-15.13	-15.92
CV-2321	5/7/2026 9:50:36 AM	149.3	-2.94	-2.94			0.337	0.342	-7.77	-7.77
CV-2321	5/7/2026 9:50:00 AM									
CV-2321	5/7/2026 9:50:00 AM									
CV-2321	5/7/2026 9:49:06 AM	149.3	2.87	-2.50	57.0	5.5	9.304	0.088	-5.20	-7.39
CV-2321	5/1/2026 10:23:30 AM	147.7	-0.16	-0.15					-13.29	
CV-2321	5/1/2026 10:20:34 AM	147.8	0.14	-0.14					-13.21	
CV-2322	5/26/2026 9:22:23 AM	60.6	-5.96	-5.96			6.023	6.017	0.09	0.08
CV-2322	5/4/2026 1:40:46 PM	138.7	-8.58	-8.35			8.534	8.316	-0.30	-0.34
CV-2324	5/6/2026 2:05:45 PM	118.4	-0.10	-0.10	12.0	12.2	0.092	0.094	-9.25	-9.27
CV-2324	5/1/2026 11:00:44 AM	120.9	-2.28	-1.17	16.3	0.0	0.165	-0.040	-13.37	
CV-2326	5/19/2026 10:26:12 AM	134.2	-5.62	-5.41			6.172	5.928	0.63	0.63
CV-2326	5/19/2026 10:25:24 AM	134.2	-5.65	-5.25			6.202	5.855	0.63	0.62
CV-2326	5/1/2026 11:33:29 AM	124.2	-7.58	-7.21			7.765	7.443	0.07	0.04
CV-2327	5/28/2026 1:44:39 PM	185.6	-3.56	-3.52			3.576	3.537	-6.47	-6.48
CV-2327	5/20/2026 2:15:58 PM	182.8	-2.57	-2.53			2.461	2.370	-6.03	-6.05
CV-2327	5/14/2026 10:00:04 AM	181.6	-2.34	-2.47			2.550	2.582	-6.47	-6.51
CV-2327	5/14/2026 9:57:08 AM	181.6	-6.87	-4.24			6.955	4.245	0.34	0.34
CV-2327	5/14/2026 9:50:00 AM									
CV-2327	5/4/2026 1:23:07 PM	185.7	-7.67	-7.76			7.701	7.744	-0.13	-0.25
CV-2327	5/4/2026 1:20:00 PM									
CV-2327	5/4/2026 1:20:00 PM									
CV-2328	5/28/2026 1:37:05 PM	164.9	-3.56	-3.67	41.3	41.8	4.346	4.447	-8.49	-8.86
CV-2328	5/20/2026 2:06:30 PM	167.3	-1.36	-1.29	44.5	42.0	5.048	4.500	-6.96	-7.10
CV-2328	5/20/2026 2:05:13 PM	167.4	-0.64	-1.43	42.2	45.5	4.527	5.277	-7.41	-7.41
CV-2328	5/11/2026 1:26:04 PM	146.7	-0.54	-0.53	12.0	11.7	0.351	0.333	-1.24	-1.21

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2328	5/7/2026 8:15:00 AM									
CV-2328	5/7/2026 8:15:00 AM									
CV-2328	5/4/2026 1:07:16 PM	172.4	-2.16	-2.13	42.0	43.2	4.543	4.815	-10.37	-11.40
CV-2328	5/4/2026 1:06:42 PM	172.4	8.45	-2.28	24.9	38.5	1.538	3.814	-11.61	-10.53
CV-2328	5/4/2026 1:05:00 PM									
CV-2328	5/4/2026 1:05:00 PM									
CV-2333	5/29/2026 9:43:07 AM	188.5	-3.29	-3.45	67.4	68.9	3.259	3.408	-3.28	-3.68
CV-2333	5/26/2026 8:54:11 AM	170.3	-2.38	-2.72			2.363	2.781	-2.18	-2.52
CV-2333	5/18/2026 9:15:00 AM									
CV-2333	5/18/2026 9:12:06 AM	158.1	-1.10	-0.47			0.918	0.296	-1.03	-0.63
CV-2333	5/13/2026 7:40:00 AM									
CV-2333	5/13/2026 7:40:00 AM									
CV-2333	5/12/2026 9:35:00 AM									
CV-2333	5/12/2026 9:28:21 AM	178.1	-5.29	-4.99			5.253	4.892	-4.80	-4.50
CV-2333	5/6/2026 9:45:24 AM	191.3	-3.95	-3.93			3.700	4.121	-3.32	-3.65
CV-2333	5/6/2026 9:44:40 AM	191.2	-3.78	-3.83			3.663	3.720	-2.94	-2.94
CV-2333	5/5/2026 8:30:00 AM									
CV-2333	5/5/2026 8:30:00 AM									
CV-2333	5/5/2026 8:26:49 AM	165.9	-6.44	-6.41			6.272	6.226	-5.79	-5.75
CV-2334	5/26/2026 2:23:32 PM	127.2	-1.36	-1.68	2.3	7.0	0.015	0.138	-1.14	-1.28
CV-2334	5/13/2026 7:45:00 AM									
CV-2334	5/13/2026 7:45:00 AM									
CV-2335	5/19/2026 10:11:09 AM	92.6	-1.21	-1.19			1.242	1.228	-3.94	-3.84
CV-2335	5/12/2026 10:45:40 AM	88.9	-1.53	-1.51	0.0	0.0	1.577	1.564	-4.57	
CV-2336	5/19/2026 10:14:30 AM	79.7	-0.11	-0.12			0.104	0.081	-5.36	-5.51
CV-2336	5/12/2026 10:27:38 AM	73.8	-0.43	-0.18	0.0	0.0	0.275	0.163	-5.93	
CV-2337	5/20/2026 8:23:36 AM	150.2	-3.45	-3.45	29.1	29.6	2.441	2.539	0.25	0.21
CV-2337	5/11/2026 2:00:37 PM	149.4	-0.74	-0.82	15.6	16.7	0.699	0.796	6.97	6.97
CV-2337	5/11/2026 8:05:00 AM									
CV-2337	5/11/2026 8:05:00 AM									
CV-2337	5/6/2026 9:26:13 AM	149.9	-2.47	-2.48	18.7	19.1	1.006	1.040	-3.11	-3.14
CV-2337	5/6/2026 9:25:00 AM									
CV-2337	5/6/2026 9:25:00 AM									
CV-2338	5/28/2026 8:46:22 AM	190.5	-3.58	-3.60			3.569	3.591	0.03	0.04
CV-2338	5/20/2026 8:15:49 AM	169.5	-2.73	-2.00			2.779	2.031	0.00	0.00
CV-2338	5/12/2026 10:09:33 AM	168.6	-1.98	-1.94	0.0	0.0	2.117	1.971	-2.57	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2338	5/12/2026 10:05:03 AM	188.6	-1.72	-1.15	0.0	0.0	1.855	1.481	-2.14	
CV-2338	5/11/2026 1:52:50 PM	172.5	0.09	0.03			0.000	0.000	9.80	9.80
CV-2338	5/11/2026 1:52:06 PM	172.5	0.72	0.72			0.000	0.000	9.64	9.64
CV-2338	5/6/2026 9:15:00 AM									
CV-2338	5/6/2026 9:15:00 AM									
CV-2338	5/6/2026 9:13:21 AM	155.1	-2.02	-2.00			1.997	1.981	0.01	0.01
CV-2338	5/6/2026 9:12:07 AM	155.3	-4.99	-1.81			4.749	1.797	0.00	0.00
CV-2339	5/29/2026 10:41:08 AM	82.3	-1.15	-1.03	0.0	0.0	0.866	0.770	-5.79	
CV-2339	5/29/2026 10:39:26 AM	80.2	-4.95	-1.00	0.0	0.0	4.634	1.081	-6.02	
CV-2339	5/14/2026 2:06:48 PM	88.1	-4.84	-4.97			4.999	4.873	-5.64	-6.42
CV-2339	5/14/2026 2:04:49 PM	88.6	118.78	-4.78			0.000	4.716	-5.80	-5.95
CV-2341	5/29/2026 10:30:39 AM	86.4	-1.16	-1.13	0.0	0.0	1.062	1.064	-6.04	
CV-2341	5/14/2026 1:47:09 PM	92.1	-0.94	-0.93			0.921	0.917	-5.13	-5.32
CV-2341	5/11/2026 7:50:00 AM									
CV-2341	5/11/2026 7:50:00 AM									
CV-2342A-PLR	5/28/2026 1:15:25 PM	187.8	-6.59	-6.65			6.627	6.717	-6.59	-6.60
CV-2342A-PLR	5/20/2026 9:08:28 AM	168.1	-6.26	-6.11			6.431	6.236	-5.66	-5.56
CV-2342A-PLR	5/13/2026 9:52:01 AM	168.6	-6.73	-6.73			6.799	6.754	-6.40	-6.38
CV-2342A-PLR	5/6/2026 10:10:00 AM	170.2	-11.74	-11.62			4.753	4.753	0.31	0.32
CV-2343	5/26/2026 2:33:45 PM	132.2	-7.97	-7.99			8.064	8.091	0.21	0.21
CV-2343	5/19/2026 2:04:37 PM	175.4	-4.36	-4.32			4.335	4.345	-4.86	-4.73
CV-2343	5/19/2026 2:03:22 PM	177.0	-4.24	-4.15			4.260	4.021	-4.70	-4.77
CV-2343	5/6/2026 9:56:02 AM	143.0	-7.81	-7.84			4.753	4.753	0.31	0.32
CV-2344	5/20/2026 8:51:25 AM	141.9	-6.82	-6.73			6.842	6.799	-7.55	-7.52
CV-2344	5/13/2026 9:31:33 AM	146.1	-5.39	-5.33			5.158	5.112	-7.71	-7.64
CV-2344	5/13/2026 9:30:38 AM	147.2	-8.12	-5.43			8.076	5.329	-7.90	-7.79
CV-2344	5/11/2026 7:35:00 AM									

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2344	5/11/2026 7:35:00 AM									
CV-2344	5/6/2026 9:52:20 AM	157.4	-8.39	-8.35			4.753	4.753	0.30	0.34
CV-2344	5/6/2026 9:50:00 AM									
CV-2344	5/6/2026 9:50:00 AM									
CV-2345	5/19/2026 2:17:28 PM	142.7	-0.14	-0.12			0.159	0.150	-4.50	-4.34
CV-2345	5/19/2026 2:15:18 PM	143.5	0.40	-0.05			0.000	0.058	-4.66	-4.46
CV-2345	5/11/2026 7:30:00 AM									
CV-2345	5/11/2026 7:30:00 AM									
CV-2345	5/1/2026 10:20:11 AM	138.4	-0.71	-0.71			0.707	0.706	0.36	0.36
CV-2345	5/1/2026 10:19:42 AM	138.2	-0.71	-0.68			0.708	0.674	0.50	0.39
CV-2346	5/28/2026 9:28:07 AM	186.9	-8.63	-8.69			8.630	8.688	-9.37	-9.36
CV-2346	5/20/2026 8:47:59 AM	184.4	-5.63	-5.72			5.602	5.722	-7.17	-7.48
CV-2346	5/13/2026 9:20:50 AM	182.1	-1.84	-1.95			1.850	1.966	-7.41	-7.20
CV-2346	5/6/2026 9:47:10 AM	182.2	-3.78	-3.77			3.748	3.734	-6.82	-6.71
CV-2346	5/6/2026 9:45:00 AM									
CV-2346	5/6/2026 9:45:00 AM									
CV-2346	5/6/2026 8:25:00 AM									
CV-2346	5/6/2026 8:25:00 AM									
CV-2346	5/4/2026 1:29:13 PM	178.7	-2.59	-2.58			2.537	2.469	-5.77	-5.75
CV-2346	5/4/2026 1:27:19 PM	179.2	-2.10	-2.04			2.077	2.033	-5.67	-5.79
CV-2347	5/20/2026 8:26:42 AM	124.3	-2.67	-2.69			2.647	2.657	-7.58	-7.46
CV-2347	5/6/2026 8:20:00 AM									
CV-2347	5/6/2026 8:20:00 AM									
CV-2347	5/1/2026 10:09:08 AM	116.7	-2.15	-2.07			2.127	2.047	-6.86	-6.71
CV-2348	5/20/2026 8:15:56 AM	108.3	-7.53	-7.47			7.779	7.724	0.03	0.03
CV-2348	5/13/2026 12:35:31 PM	128.8	-3.81	-3.82	0.0	0.0	3.808	3.809	-5.97	
CV-2348	5/6/2026 8:15:00 AM									
CV-2348	5/6/2026 8:15:00 AM									
CV-2349	5/28/2026 10:20:04 AM	172.5	-1.12	-0.52			1.107	0.372	-1.79	-1.26
CV-2349	5/20/2026 10:27:38 AM	163.1	-2.00	-2.00			2.287	2.251	-0.29	-0.29
CV-2349	5/13/2026 10:48:12 AM	150.2	-0.05	-0.13			0.000	0.205	0.13	-0.34

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2349	5/7/2026 11:16:23 AM	147.7	0.29	0.40			0.000	0.000	0.33	0.34
CV-2349	5/7/2026 11:15:19 AM	147.8	0.27	0.59			0.000	0.000	0.33	0.34
CV-2349	5/7/2026 11:15:00 AM									
CV-2349	5/7/2026 11:15:00 AM									
CV-2349	5/5/2026 8:25:00 AM									
CV-2349	5/5/2026 8:25:00 AM									
CV-2350	5/20/2026 10:03:44 AM	112.1	-4.09	-4.05			4.103	3.992	-4.09	-4.08
CV-2350	5/13/2026 12:57:10 PM	116.4	-0.49	-1.29	0.0	0.0	0.524	1.059	-3.38	
CV-2350	5/13/2026 12:56:01 PM	116.6	8.91	-3.00	0.0	0.0	-8.618	2.220	-3.98	
CV-2350	5/11/2026 7:40:00 AM									
CV-2350	5/11/2026 7:40:00 AM									
CV-2351	5/28/2026 9:25:03 AM	77.5	-6.12	-6.08			6.525	6.308	-5.97	-5.30
CV-2351	5/28/2026 9:24:00 AM	65.4	-6.82	-6.66			7.176	6.961	-6.76	-6.67
CV-2351	5/5/2026 7:50:00 AM									
CV-2351	5/5/2026 7:50:00 AM									
CV-2351	5/1/2026 9:05:14 AM	77.5	-6.60	-6.39			6.687	6.457	-6.56	-6.21
CV-2352	5/28/2026 9:16:38 AM	108.9	-0.77	-0.76			0.752	0.747	-6.25	-6.44
CV-2352	5/28/2026 9:12:47 AM	97.8	-5.81	-2.75			6.088	2.734	-6.36	-6.28
CV-2352	5/5/2026 8:00:00 AM									
CV-2352	5/5/2026 8:00:00 AM									
CV-2352	5/1/2026 9:13:24 AM	116.7	-0.02	-5.72			0.000	5.794	-6.40	-6.63
CV-2353-PLR	5/20/2026 9:13:57 AM	131.5	-5.36	-5.36			5.452	5.458	-5.45	-5.40
CV-2353-PLR	5/20/2026 9:13:10 AM	131.4	-5.82	-5.04			5.928	5.201	-5.65	-5.64
CV-2353-PLR	5/15/2026 8:29:12 AM	147.9	-6.86	-6.79			7.058	7.011	-7.01	-6.98
CV-2353-PLR	5/15/2026 8:27:25 AM	149.2	-7.01	-6.99			7.162	7.127	-6.87	-6.76
CV-2353-PLR	5/14/2026 8:40:00 AM									
CV-2353-PLR	5/12/2026 7:35:00 AM									
CV-2353-PLR	5/12/2026 7:35:00 AM									
CV-2354	5/28/2026 10:36:46 AM	183.9	-0.52	-0.52			0.502	0.502	-2.81	-2.81

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2354	5/20/2026 10:42:07 AM	180.2	1.88	1.91			0.000	0.000	-0.10	-0.46
CV-2354	5/20/2026 10:40:36 AM	178.6	1.82	1.87			0.000	0.000	0.29	-0.11
CV-2354	5/13/2026 11:03:49 AM	167.4	-1.06	-1.11			1.021	1.091	-2.62	-2.74
CV-2354	5/13/2026 11:01:08 AM	166.8	-0.98	-0.98			0.980	0.901	-2.75	-2.98
CV-2354	5/6/2026 10:50:20 AM	175.3	-3.33	-3.39			3.289	3.344	0.34	0.32
CV-2354	5/6/2026 10:50:00 AM									
CV-2354	5/6/2026 10:50:00 AM									
CV-2354	5/5/2026 8:20:00 AM									
CV-2354	5/5/2026 8:20:00 AM									
CV-24001	5/19/2026 10:02:44 AM	90.8	-1.05	-1.10			1.083	1.105	-3.92	-4.14
CV-24001	5/12/2026 10:38:27 AM	102.6	-1.40	-1.41	0.0	0.0	1.501	1.497		
CV-24002	5/19/2026 9:53:36 AM	89.1	-0.13	-0.15			0.094	0.064	-5.87	-5.88
CV-24002	5/19/2026 9:51:18 AM	88.6	0.11	-0.04			0.000	0.023	-5.90	-5.88
CV-24002	5/1/2026 2:39:31 PM	93.2	-0.06	-0.01			0.029	0.000	0.28	0.29
CV-24003	5/19/2026 9:12:06 AM	101.3	-0.41	-0.43	7.2	6.8	0.031	0.028	-5.97	-5.97
CV-24003	5/1/2026 2:37:02 PM	101.6	-0.76	-0.63	12.6	8.4	0.098	0.043	-6.86	-6.54
CV-24004	5/19/2026 9:02:30 AM	113.1	-0.70	-0.49	5.9	8.0	0.093	0.171	-6.47	-6.58
CV-24004	5/1/2026 2:33:11 PM	115.3	-1.05	-1.05	4.7	4.8	0.059	0.063	-7.35	-7.39
CV-24006	5/19/2026 10:36:49 AM	127.3	-0.58	-0.58	11.3	11.3	0.348	0.348	-2.65	-2.65
CV-24006	5/1/2026 11:40:45 AM	127.9	-0.65	-0.68	15.2	14.9	0.634	0.610	-3.87	-3.94
CV-24007	5/29/2026 9:33:56 AM	148.2	-1.32	-1.34	29.9	30.7	2.551	2.693	-6.72	-6.61
CV-24007	5/26/2026 1:56:22 PM	150.8	-1.44	-1.44	25.2	25.2	1.836	1.836	0.88	0.88
CV-24007	5/26/2026 1:55:46 PM	150.9	-0.79	-1.05	13.8	28.1	0.548	2.288	1.01	0.87
CV-24007	5/19/2026 10:46:37 AM	150.7	-0.16	-0.16	12.4	14.7	0.436	0.618	-3.26	-4.40
CV-24007	5/19/2026 10:45:21 AM	150.7	-0.31	-0.18	16.3	13.6	0.764	0.530	-3.87	-3.95
CV-24007	5/15/2026 9:10:41 AM	138.7	-0.12	-0.14	5.0	6.7	0.071	0.125	-0.21	-0.49
CV-24007	5/15/2026 9:09:54 AM	132.4	0.04	-0.02	3.5	4.7	0.035	0.062	-0.36	0.04

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24007	5/12/2026 8:40:00 AM									
CV-24007	5/12/2026 8:40:00 AM									
CV-24008	5/26/2026 1:50:27 PM	170.0	-9.70	-9.59	11.5	13.1	0.093	0.123	-8.95	-9.16
CV-24008	5/18/2026 2:25:00 PM									
CV-24008	5/18/2026 2:17:05 PM	170.7	-4.49	-3.38	81.0	71.5	4.637	3.595	-4.10	-3.36
CV-24008	5/12/2026 1:41:31 PM	171.5	-7.21	-6.93	10.0	4.5	0.070	0.014	-7.41	-7.08
CV-24008	5/12/2026 1:40:00 PM									
CV-24008	5/5/2026 10:20:00 AM									
CV-24008	5/5/2026 10:20:00 AM									
CV-24008	5/5/2026 10:14:56 AM	172.4	-8.88	-8.90	17.4	15.6	0.214	0.172	-9.66	-9.68
CV-24009	5/26/2026 1:46:14 PM	155.7	-6.44	-6.40			0.179	0.171	-9.20	-9.08
CV-24009	5/18/2026 2:20:00 PM									
CV-24009	5/18/2026 2:13:29 PM	155.9	-1.22	-1.13			1.376	1.346	-0.92	-1.01
CV-24009	5/12/2026 1:35:00 PM									
CV-24009	5/12/2026 1:31:36 PM	156.8	-3.74	-3.79			0.185	0.146	-7.09	-7.09
CV-24009	5/5/2026 10:15:00 AM									
CV-24009	5/5/2026 10:15:00 AM									
CV-24009	5/5/2026 10:10:10 AM	156.7	-4.14	-4.16			0.221	0.207	-8.98	-8.80
CV-24010	5/26/2026 9:45:36 AM	61.0	-4.66	-4.84			4.590	4.734	-4.43	-4.58
CV-24010	5/13/2026 1:57:52 PM	89.2	-6.88	-7.43			6.921	7.524	-6.64	-7.30
CV-24011	5/27/2026 8:51:05 AM	188.2	-1.27	-1.22	30.5	32.5	2.865	3.242	-4.35	-4.66
CV-24011	5/27/2026 8:49:35 AM	188.3	-0.73	-0.88	26.2	32.8	2.112	3.312	-4.49	-4.37
CV-24011	5/19/2026 10:30:22 AM	186.7	-0.69	-0.78	27.1	28.2	2.235	2.422	-5.10	-5.66
CV-24011	5/18/2026 2:55:00 PM									
CV-24011	5/18/2026 2:48:57 PM	187.7	-3.47	-3.70	25.6	25.9	2.010	2.065	0.46	0.34
CV-24011	5/12/2026 2:43:10 PM	185.6	-1.13	-1.13	30.9	31.1	2.906	2.933	0.10	0.09
CV-24011	5/12/2026 2:25:00 PM									
CV-24011	5/5/2026 1:10:54 PM	185.1	-2.55	-2.53	25.1	25.1	1.925	1.923	-7.21	-7.17
CV-24011	5/5/2026 1:10:00 PM									
CV-24011	5/5/2026 1:10:00 PM									
CV-24012	5/26/2026 2:14:33 PM	154.3	-7.03	-7.03			7.171	7.071	-0.13	-0.13
CV-24012	5/18/2026 2:56:25 PM	162.0	-0.20	-0.24			0.177	0.207	0.24	0.25
CV-24012	5/18/2026 2:50:00 PM									
CV-24012	5/18/2026 2:41:34 PM	157.1	-1.83	-1.72			1.810	1.802	0.28	0.34
CV-24012	5/12/2026 2:38:30 PM	173.9	-4.67	-4.65			4.498	4.499	0.00	0.00

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24012	5/12/2026 2:20:00 PM									
CV-24012	5/5/2026 1:30:00 PM									
CV-24012	5/5/2026 1:30:00 PM									
CV-24012	5/5/2026 1:26:23 PM	157.4	-7.01	-7.01			6.757	6.745	0.00	0.00
CV-24013	5/26/2026 9:51:46 AM	92.1	-0.21	-0.12			0.212	0.121	-5.91	-6.41
CV-24013	5/13/2026 10:06:33 AM	99.1	-0.34	-0.31			0.323	0.307	-7.83	-8.05
CV-24014	5/26/2026 1:42:04 PM	176.9	-8.52	-8.71	52.5	53.0	8.560	8.719	-8.19	-8.48
CV-24014	5/18/2026 2:15:00 PM									
CV-24014	5/18/2026 2:07:26 PM	176.9	-0.58	-0.53	18.6	28.3	1.031	2.402	0.97	2.03
CV-24014	5/12/2026 1:30:00 PM									
CV-24014	5/12/2026 1:26:38 PM	176.2	-2.90	-2.01	30.3	25.4	2.757	1.930	-5.00	-6.80
CV-24014	5/12/2026 1:25:28 PM	176.4	-3.55	-1.48	33.8	21.3	3.448	1.364	-5.95	-5.51
CV-24014	5/5/2026 10:10:00 AM									
CV-24014	5/5/2026 10:10:00 AM									
CV-24014	5/5/2026 10:06:41 AM	176.1	-3.60	-3.60	34.4	34.4	3.580	3.580	-6.08	-6.08
CV-24015	5/26/2026 9:48:59 AM	186.5	-1.07	-1.07			1.074	1.071	-3.23	-3.32
CV-24015	5/18/2026 10:08:30 AM	183.6	-0.79	-0.74			0.649	0.664	-3.75	-3.57
CV-24015	5/18/2026 10:06:48 AM	184.2	0.47	-0.96			0.000	0.935	-4.09	-4.07
CV-24015	5/18/2026 10:05:03 AM	183.6	0.66	0.63			0.000	0.000	0.29	0.33
CV-24015	5/18/2026 10:05:00 AM									
CV-24015	5/12/2026 9:01:20 AM	183.7	-3.88	-3.88			3.844	3.843	-7.97	-8.00
CV-24015	5/12/2026 9:00:00 AM									
CV-24015	5/12/2026 8:59:57 AM	183.8	-8.33	-5.00			8.403	5.082	-8.44	-8.31
CV-24015	5/5/2026 9:14:20 AM	170.0	-8.67	-8.47			8.672	8.636	-8.72	-8.83
CV-24015	5/5/2026 9:05:00 AM									
CV-24015	5/5/2026 9:05:00 AM									
CV-24016	5/29/2026 9:27:07 AM	178.1	-3.74	-3.67			3.685	3.614	-5.13	-5.11
CV-24016	5/27/2026 8:54:06 AM	171.8	-2.49	-2.24			2.477	2.212	-2.81	-2.98

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24016	5/19/2026 10:04:01 AM	182.8	-2.48	-2.49			2.449	2.395	-3.65	-3.81
CV-24016	5/19/2026 10:02:01 AM	182.2	-2.51	-2.41			2.486	2.343	-4.04	-3.80
CV-24016	5/18/2026 3:00:00 PM									
CV-24016	5/18/2026 2:51:00 PM	169.0	-2.29	-2.36			2.255	2.308	-2.42	-2.65
CV-24016	5/12/2026 2:44:41 PM	161.1	-2.53	-2.50			2.540	2.510	-6.21	-6.63
CV-24016	5/12/2026 2:30:00 PM									
CV-24016	5/6/2026 1:26:28 PM	170.1	-0.10	-0.10			0.103	0.101	-2.08	-2.04
CV-24016	5/6/2026 1:25:16 PM	170.1	-0.06	-0.21			0.074	0.215	-2.08	-2.16
CV-24016	5/5/2026 1:15:29 PM	163.4	-2.76	-2.74			2.760	2.744	-6.84	-6.84
CV-24016	5/5/2026 1:15:00 PM									
CV-24016	5/5/2026 1:15:00 PM									
CV-24017	5/26/2026 2:08:15 PM	171.5	-3.75	-3.69			4.049	3.793	0.21	0.21
CV-24017	5/26/2026 2:07:20 PM	172.6	-7.16	-5.22			7.241	5.251	0.21	0.21
CV-24017	5/18/2026 2:40:00 PM									
CV-24017	5/18/2026 2:35:18 PM	170.6	-2.24	-2.10			2.273	2.078	0.34	0.34
CV-24017	5/12/2026 2:47:32 PM	174.6	-2.11	-2.05			2.017	1.912	0.00	0.00
CV-24017	5/12/2026 2:25:14 PM	180.5	-4.81	-1.21			4.666	1.101	-0.05	-0.02
CV-24017	5/12/2026 2:10:00 PM									
CV-24017	5/12/2026 8:35:00 AM									
CV-24017	5/12/2026 8:35:00 AM									
CV-24017	5/5/2026 1:20:00 PM									
CV-24017	5/5/2026 1:20:00 PM									
CV-24017	5/5/2026 1:19:34 PM	159.6	-3.14	-3.12			3.132	3.122	0.00	0.00
CV-24018	5/29/2026 11:06:53 AM	114.0	-0.87	-0.87	0.0	0.0	0.874	0.876	-6.41	
CV-24018	5/13/2026 3:41:42 PM	109.4	-0.69	-0.67			0.703	0.665	-7.07	-6.05
CV-24019	5/27/2026 8:57:49 AM	171.6	-2.95	-2.96			2.916	3.043	-2.50	-2.60
CV-24019	5/19/2026 8:35:00 AM									
CV-24019	5/19/2026 8:31:39 AM	168.5	-4.35	-4.33			4.361	4.368	-4.60	-4.58
CV-24019	5/13/2026 2:09:27 PM	179.5	-2.41	-2.95			2.997	3.048	-3.07	-3.25

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24019	5/5/2026 2:30:00 PM									
CV-24019	5/5/2026 2:30:00 PM									
CV-24019	5/5/2026 2:26:07 PM	182.5	-3.66	-3.76			3.567	3.674	-3.67	-3.69
CV-24020	5/26/2026 10:31:13 AM	59.9	-3.65	-3.98	1.9	1.8	0.009	0.008	-3.57	-3.96
CV-24020	5/13/2026 1:39:38 PM	83.0	-0.64	-0.74	0.5	1.2	0.001	0.004	-1.33	-1.03
CV-24021	5/26/2026 10:19:45 AM	62.3	-2.20	-2.25			2.065	2.162	-2.77	-2.63
CV-24021	5/13/2026 10:19:21 AM	75.7	-4.87	-4.74			5.121	5.071	-4.90	-5.06
CV-24022-PLR	5/26/2026 1:34:59 PM	194.1	-8.42	-8.21			8.257	8.035	1.01	0.90
CV-24022-PLR	5/18/2026 2:10:00 PM									
CV-24022-PLR	5/18/2026 2:04:39 PM	194.9	-2.81	-1.08			2.700	1.305	0.34	0.34
CV-24022-PLR	5/12/2026 1:25:00 PM									
CV-24022-PLR	5/12/2026 1:18:18 PM	191.3	-6.27	-6.67			6.041	6.412	-0.18	-0.34
CV-24022-PLR	5/5/2026 10:05:00 AM									
CV-24022-PLR	5/5/2026 10:05:00 AM									
CV-24022-PLR	5/5/2026 10:03:55 AM	192.3	-6.02	-6.12			6.095	6.197	0.23	0.23
CV-24023	5/26/2026 10:02:11 AM	175.5	-2.17	-2.29			2.157	2.273	0.67	0.67
CV-24023	5/26/2026 9:58:22 AM	167.2	-5.34	-3.29			5.399	3.268	0.34	0.36
CV-24023	5/18/2026 10:19:04 AM	159.0	-2.05	-2.52			2.024	2.485	0.34	0.34
CV-24023	5/18/2026 10:15:00 AM	157.6	-2.04	-1.46			1.990	1.458	0.34	0.36
CV-24023	5/12/2026 8:52:20 AM	181.3	-7.39	-7.38			7.445	7.366	0.74	0.55
CV-24023	5/12/2026 8:51:10 AM	179.8	-9.09	-7.68			9.203	7.582	0.78	0.84
CV-24023	5/12/2026 8:50:00 AM									
CV-24023	5/6/2026 9:28:29 AM	168.5	-3.01	-3.00			2.979	2.940	-2.31	-2.26
CV-24023	5/6/2026 9:27:29 AM	168.6	-2.70	-2.68			2.672	2.642	-1.97	-1.93

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24023	5/5/2026 9:36:54 AM	181.2	-9.52	-9.49			9.638	9.611	-9.12	-9.12
CV-24023	5/5/2026 9:35:20 AM	177.0	0.71	-8.56			0.000	8.648	-9.01	-9.03
CV-24023	5/5/2026 9:27:58 AM	157.0	-9.45	-9.40			9.590	9.536	-8.93	-9.12
CV-24023	5/5/2026 9:25:00 AM									
CV-24023	5/5/2026 9:25:00 AM									
CV-24024-PLR	5/18/2026 9:51:23 AM	131.0	-4.84	-4.17			4.856	4.210	-4.45	-4.03
CV-24024-PLR	5/15/2026 9:22:07 AM	157.6	-8.10	-8.11			8.419	8.389	-8.02	-8.06
CV-24024-PLR	5/15/2026 9:20:22 AM	157.0	-7.92	-7.85			8.243	8.172	-7.86	-7.98
CV-24025	5/28/2026 2:28:43 PM	187.2	-4.29	-4.29			4.298	4.294	0.00	0.00
CV-24025	5/19/2026 9:27:53 AM	186.5	-1.60	-1.64			1.570	1.662	-4.93	-5.19
CV-24025	5/19/2026 9:26:52 AM	186.3	2.20	-1.58			0.000	1.577	-5.14	-4.88
CV-24025	5/19/2026 9:25:00 AM									
CV-24025	5/13/2026 2:30:31 PM	187.3	-1.45	-1.45			1.359	1.356	-5.49	-5.50
CV-24025	5/6/2026 8:57:31 AM	186.2	-1.81	-1.77			1.738	1.728	-7.66	-6.75
CV-24025	5/6/2026 8:56:37 AM	186.3	-1.61	-1.77			1.557	1.768	-6.82	-7.10
CV-24025	5/5/2026 2:13:13 PM	185.0	-2.61	-2.26			2.644	2.308	-6.26	-5.24
CV-24025	5/5/2026 2:10:00 PM									
CV-24025	5/5/2026 2:10:00 PM									
CV-24026	5/22/2026 12:25:54 PM	92.2	-3.02	-0.38			2.942	0.329	-7.33	-8.07
CV-24026	5/13/2026 1:43:47 PM	88.8	-1.30	-1.24			1.195	1.153	-6.78	-5.98
CV-24027	5/26/2026 10:11:09 AM	63.5	-6.23	-6.11			6.243	6.223	-6.22	-5.93
CV-24027	5/13/2026 10:15:50 AM	74.6	-8.36	-8.45			8.607	8.662	-8.49	-8.41
CV-24027	5/6/2026 9:11:56 AM	81.7	-8.74	-8.95			8.972	9.158	-8.46	-8.66
CV-24028	5/26/2026 1:15:48 PM	189.1	-9.51	-9.07			9.601	9.178	-9.85	-9.16
CV-24028	5/26/2026 1:13:13 PM	185.8	-8.17	-8.19			8.311	8.341	-8.54	-8.60

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24028	5/18/2026 2:05:00 PM									
CV-24028	5/18/2026 2:01:26 PM	188.8	2.34	1.97			0.000	0.000	0.91	0.64
CV-24028	5/12/2026 1:20:00 PM									
CV-24028	5/12/2026 1:14:56 PM	188.0	-5.15	-4.97			4.939	4.808	-6.23	-5.74
CV-24028	5/5/2026 10:00:52 AM	193.0	-6.04	-6.04			6.141	6.141	-8.78	-8.78
CV-24028	5/5/2026 10:00:00 AM									
CV-24028	5/5/2026 10:00:00 AM									
CV-24029	5/29/2026 11:19:30 AM	87.8	-4.30	-3.01	0.0	0.0	4.479	2.855	-6.48	
CV-24029	5/29/2026 11:15:41 AM	87.1	-6.28	-5.73	0.0	0.0	6.916	5.774	-6.88	
CV-24029	5/13/2026 2:06:48 PM	85.9	-7.47	-7.31			7.585	7.394	-7.45	-7.24
CV-24030	5/26/2026 9:14:08 AM	192.7	-1.22	-1.23			1.208	1.220	-3.42	-3.41
CV-24030	5/26/2026 9:07:52 AM	193.0	-3.16	-1.62			3.139	1.658	-3.06	-3.31
CV-24030	5/18/2026 9:35:03 AM	190.8	-1.75	-1.75			1.794	1.802	-1.85	-1.87
CV-24030	5/18/2026 9:35:00 AM									
CV-24030	5/12/2026 9:18:44 AM	193.2	-0.90	-0.93			0.000	0.000	0.14	0.13
CV-24030	5/12/2026 9:15:00 AM									
CV-24030	5/5/2026 8:46:48 AM	190.7	-2.22	-2.04			2.164	2.073	-5.87	-5.87
CV-24030	5/5/2026 8:45:00 AM									
CV-24030	5/5/2026 8:45:00 AM									
CV-24030	5/5/2026 8:44:58 AM	190.9	-6.38	-4.42			6.141	4.485	-6.08	-6.01
CV-24031	5/29/2026 1:15:41 PM	116.1	-6.98	-7.00			7.051	7.058	-6.68	-6.72
CV-24031	5/22/2026 12:15:48 PM	131.4	-0.35	-0.34			0.216	0.243	-7.99	-8.00
CV-24031	5/22/2026 12:14:13 PM	132.8	-0.55	-0.34			0.350	0.230	-7.90	-8.18
CV-24031	5/12/2026 1:32:07 PM	121.9	-0.26	-0.19			0.190	0.135	-5.85	-6.42
CV-24032	5/27/2026 9:19:07 AM	192.1	2.10	2.67			0.000	0.000	1.93	2.23
CV-24032	5/27/2026 9:17:20 AM	192.0	0.54	0.29			0.000	0.000	2.23	1.91

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24032	5/27/2026 9:09:02 AM	193.3	-0.94	-1.08			0.930	1.104	0.99	1.54
CV-24032	5/24/2026 12:06:03 PM	147.9	-3.53	-3.43			3.562	3.484	-3.52	-3.38
CV-24032	5/24/2026 12:02:54 PM	140.3	-3.68	-3.36			3.719	3.410	-3.74	-3.36
CV-24032	5/19/2026 8:41:47 AM	137.2	-3.91	-3.77			3.769	3.670	-3.68	-3.40
CV-24032	5/14/2026 10:31:39 AM	178.8	-4.64	-4.80			4.539	4.696	-3.86	-4.03
CV-24032	5/13/2026 2:37:29 PM	150.7	-2.50	-2.63			2.433	2.583	-2.52	-2.69
CV-24032	5/5/2026 2:20:00 PM									
CV-24032	5/5/2026 2:20:00 PM									
CV-24032	5/5/2026 2:17:41 PM	169.6	-0.43	-0.63			0.482	0.685	0.39	0.68
CV-24033	5/28/2026 2:24:12 PM	191.1	-1.54	-1.54			1.451	1.513	-1.75	-1.81
CV-24033	5/19/2026 8:45:00 AM									
CV-24033	5/19/2026 8:39:24 AM	184.7	-3.21	-3.22			3.198	3.205	-3.70	-3.73
CV-24033	5/13/2026 2:17:00 PM	185.3	-3.26	-3.28			3.265	3.281	-4.01	-4.05
CV-24033	5/7/2026 1:00:00 PM									
CV-24033	5/7/2026 12:59:49 PM	188.3	-0.99	-0.91			0.913	0.852	-0.31	-0.30
CV-24033	5/7/2026 1:00:00 AM									
CV-24034	5/18/2026 11:08:37 AM	105.9	-1.53	-1.57			1.490	1.498	-2.02	-2.02
CV-24034	5/18/2026 11:06:51 AM	108.0	-3.76	-1.48			3.784	1.470	-3.19	-3.48
CV-24034	5/12/2026 10:57:45 AM	166.6	-2.34	-2.32			2.322	2.304	-9.40	-9.41
CV-24034	5/12/2026 10:55:50 AM	168.0	-9.52	-7.24			9.563	7.234	-9.16	-9.29
CV-24034	5/12/2026 10:55:00 AM									
CV-24034	5/5/2026 9:57:30 AM	185.4	-8.10	-8.10			8.251	8.251	-10.00	-10.00
CV-24034	5/5/2026 9:56:30 AM	185.4	-8.02	-6.96			8.186	7.056	-9.25	-9.28
CV-24034	5/5/2026 9:55:00 AM									
CV-24034	5/5/2026 9:55:00 AM									

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24035	5/26/2026 8:50:47 AM	180.7	-3.40	-3.28			3.494	3.095	-0.01	0.00
CV-24035	5/18/2026 9:10:00 AM									
CV-24035	5/18/2026 9:05:47 AM	193.0	-0.63	-2.91			0.000	0.757	0.00	0.00
CV-24035	5/18/2026 9:03:47 AM	198.1	30.95	0.76			0.000	0.000	-0.31	-0.01
CV-24035	5/12/2026 9:40:00 AM									
CV-24035	5/12/2026 9:31:35 AM	177.3	-5.39	-5.33			5.402	5.403	-4.84	-5.28
CV-24035	5/5/2026 8:25:00 AM									
CV-24035	5/5/2026 8:25:00 AM									
CV-24035	5/5/2026 8:24:01 AM	179.2	-6.09	-5.70			5.877	5.502	-5.68	-6.00
CV-24036	5/29/2026 2:20:04 PM	83.1	-4.43	-4.39			4.301	4.190	-8.25	-8.74
CV-24036	5/24/2026 11:45:25 AM	73.3	-8.22	-7.95			8.039	7.899	-8.17	-7.85
CV-24036	5/13/2026 10:53:14 AM	77.0	-7.49	-7.44			7.925	7.887	-7.44	-7.46
CV-24036	5/6/2026 8:46:55 AM	68.6	-7.62	-7.69			7.706	7.837	-7.23	-6.64
CV-24037	5/26/2026 9:09:53 AM	59.2	-3.83	-3.74			3.758	3.664	-6.15	-5.73
CV-24037	5/26/2026 9:08:28 AM	58.8	-6.41	-3.51			6.474	3.423	-6.41	-6.23
CV-24037	5/12/2026 1:53:15 PM	80.6	-4.98	-4.77			5.298	4.976	-4.79	-4.67
CV-24038	5/27/2026 9:29:33 AM	177.8	-0.91	-0.99			1.162	1.178	-4.07	-4.20
CV-24038	5/27/2026 9:27:49 AM	178.8	-2.38	-1.72			2.425	1.800	-5.78	-5.77
CV-24038	5/19/2026 9:05:00 AM									
CV-24038	5/19/2026 9:04:35 AM	170.6	-1.93	-2.00			1.858	1.991	-5.24	-5.54
CV-24038	5/19/2026 9:04:12 AM	171.4	-0.08	-2.09			0.234	2.042	-5.87	-5.44
CV-24038	5/13/2026 2:51:36 PM	171.0	-3.36	-3.17			3.294	2.997	-8.13	-7.39
CV-24038	5/13/2026 2:48:58 PM	172.7	-7.66	-3.26			7.860	3.364	-7.52	-8.16

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24038	5/6/2026 3:05:00 PM									
CV-24038	5/6/2026 3:05:00 PM									
CV-24038	5/6/2026 3:04:57 PM	182.8	-4.92	-4.46			4.757	3.554	0.00	0.00
CV-24038	5/6/2026 3:04:21 PM	183.2	0.83	-0.06			0.000	0.000	0.00	0.00
CV-24039	5/22/2026 12:04:33 PM	143.8	-7.62	-7.77			7.664	7.868	-8.33	-8.72
CV-24039	5/22/2026 12:01:47 PM	149.1	-6.16	-6.16			6.220	6.226	-8.77	-8.76
CV-24039	5/22/2026 11:58:20 AM	137.0	50.09	-5.15			0.000	5.244	-8.49	-8.18
CV-24039	5/14/2026 1:31:24 PM	86.9	-7.81	-7.97			7.882	7.917	-8.95	-8.59
CV-24039	5/14/2026 1:29:39 PM	87.3	-7.91	-8.04			8.039	8.097	-8.11	-8.27
CV-24040	5/29/2026 9:07:46 AM	172.2	-0.72	-0.72			0.717	0.687	-8.74	-9.06
CV-24040	5/29/2026 9:07:06 AM	171.2	-0.59	-0.59			0.569	0.599	-8.09	-8.68
CV-24040	5/29/2026 9:05:56 AM		25.41				0.000		-7.68	
CV-24040	5/19/2026 10:40:23 AM	86.6	-8.40	-8.40			8.480	8.478	-9.24	-9.26
CV-24040	5/19/2026 10:38:38 AM	85.9	-8.40	-8.40			8.383	8.421	-9.20	-9.42
CV-24040	5/13/2026 1:35:35 PM	82.3	-7.88	-7.85			7.997	7.964	-7.80	-7.78
CV-24040	5/13/2026 1:32:34 PM	81.8	-8.50	-8.90			8.545	8.953	-8.95	-9.73
CV-24041	5/26/2026 10:04:46 AM	65.4	-6.50	-5.72			6.603	5.698	-6.37	-6.18
CV-24041	5/8/2026 8:06:27 AM	71.8	-5.22	-5.19	0.0	0.0	5.202	5.194	-5.37	
CV-24042	5/26/2026 11:03:38 AM	185.6	-5.74	-5.39			5.708	5.432	-11.16	-11.17
CV-24042	5/26/2026 11:02:42 AM	184.2	-10.01	-6.36			10.042	6.373	-11.18	-11.15
CV-24042	5/18/2026 10:55:00 AM									
CV-24042	5/18/2026 10:47:52 AM	188.5	-2.89	-2.92			2.665	2.633	-5.08	-4.96
CV-24042	5/12/2026 10:15:58 AM	183.3	-6.96	-6.97			6.966	6.985	-11.66	-11.55

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24042	5/12/2026 10:15:09 AM	182.5	-10.36	-7.21			10.386	7.200	-11.36	-11.61
CV-24042	5/12/2026 10:15:00 AM									
CV-24042	5/7/2026 10:08:18 AM	191.5	-2.88	-2.79			2.712	2.774	-3.80	-3.67
CV-24042	5/7/2026 10:06:45 AM	190.4	2.93	-3.17			0.000	3.143	-3.96	-3.97
CV-24042	5/7/2026 10:05:00 AM									
CV-24042	5/7/2026 10:05:00 AM									
CV-24043	5/22/2026 2:06:15 PM	91.6	-2.26	-4.48			2.209	4.284	-2.41	-5.77
CV-24043	5/15/2026 8:55:16 AM	85.7	-5.29	-5.11			5.492	5.318	-5.27	-4.93
CV-24044	5/26/2026 8:46:58 AM	130.2	-2.80	-2.40			2.740	2.354	-6.52	-7.02
CV-24044	5/26/2026 8:42:07 AM	129.2	2.24	-1.62			0.000	1.590	-6.84	-6.38
CV-24044	5/8/2026 12:36:24 PM	87.5	-6.31	-5.90			6.315	5.948	-6.22	-6.34
CV-24045	5/27/2026 9:33:35 AM	157.7	-2.10	-2.08			2.128	2.114	-2.79	-2.79
CV-24045	5/27/2026 9:32:48 AM	156.8	-0.60	-2.14			0.639	2.114	-2.60	-2.74
CV-24045	5/19/2026 9:11:34 AM	152.4	-3.47	-3.46			3.468	3.458	-5.72	-5.51
CV-24045	5/19/2026 9:10:36 AM	151.1	-6.96	-3.44			7.055	3.452	-6.83	-5.38
CV-24045	5/19/2026 9:10:00 AM									
CV-24045	5/13/2026 2:58:14 PM	150.1	-4.34	-4.44			4.294	4.476	-7.81	-8.74
CV-24045	5/13/2026 2:56:09 PM	149.6	-7.29	-3.98			7.415	3.972	-7.41	-8.39
CV-24045	5/6/2026 2:55:47 PM	161.0	-3.53	-3.49			3.536	3.537	-5.86	-5.76
CV-24045	5/6/2026 2:54:58 PM	162.2	-5.61	-3.47			5.525	3.335	-5.49	-6.27
CV-24045	5/6/2026 2:45:00 PM									
CV-24045	5/6/2026 2:45:00 PM									
CV-24046	5/29/2026 1:33:04 PM	125.7	-2.98	-2.94			2.990	2.894	-3.35	-2.71
CV-24046	5/29/2026 1:30:24 PM	124.4	132.32	-1.93			0.000	1.934	9.74	-2.60

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24046	5/28/2026 11:56:16 AM	73.2	-7.10	-7.13	0.0	0.0	7.116	7.297	-7.89	
CV-24046	5/28/2026 11:54:22 AM	71.7	-7.75	-6.99	0.0	0.0	7.986	7.182	-7.74	
CV-24046	5/13/2026 10:32:28 AM	93.1	-7.60	-7.87			7.925	8.185	-7.73	-8.03
CV-24048	5/20/2026 2:12:35 PM	97.2	-8.02	-7.73			7.729	7.666	-7.96	-7.66
CV-24048	5/19/2026 10:25:00 AM									
CV-24048	5/8/2026 8:14:16 AM	83.3	-5.18	-5.07	0.0	0.0	5.283	4.841	-5.26	
CV-24049	5/26/2026 10:45:00 AM	179.6	-5.95	-5.74			5.960	5.690	-11.49	-12.01
CV-24049	5/26/2026 10:43:34 AM	179.2	-11.36	-5.97			11.387	5.903	-11.24	-11.51
CV-24049	5/18/2026 10:35:00 AM									
CV-24049	5/18/2026 10:30:56 AM	180.2	-4.87	-4.90			5.071	5.059	-4.97	-4.95
CV-24049	5/13/2026 8:10:00 AM									
CV-24049	5/13/2026 8:10:00 AM									
CV-24049	5/11/2026 8:49:25 AM	185.0	-1.84	-1.69			1.846	1.839	-0.36	-0.08
CV-24049	5/11/2026 8:47:07 AM	186.6	3.00	-0.64			0.000	0.600	-0.87	-0.63
CV-24049	5/4/2026 2:40:00 PM									
CV-24049	5/4/2026 2:40:00 PM									
CV-24049	5/4/2026 2:36:19 PM	189.2	-4.01	-3.94			3.706	3.731	-10.48	-10.49
CV-24050	5/22/2026 2:16:54 PM	103.0	-2.05	-2.06			1.991	2.002	-8.30	-8.24
CV-24050	5/11/2026 12:53:12 PM	109.5	-1.58	-1.57			1.421	1.381	-5.74	-5.70
CV-24051	5/26/2026 8:54:30 AM	102.2	-4.70	-0.74			4.616	0.722	-5.94	-6.75
CV-24051	5/8/2026 12:45:09 PM	83.3	-6.10	-5.57			6.044	5.631	-5.82	-5.61
CV-24052	5/20/2026 2:26:23 PM	94.2	-4.19	-4.19			4.128	4.120	-4.25	-4.25
CV-24052	5/13/2026 10:05:26 AM	73.4	-6.11	-6.22			6.384	6.466	-6.22	-6.31
CV-24053	5/20/2026 2:23:25 PM	100.5	-4.32	-4.99			4.201	4.770	-4.39	-5.14
CV-24053	5/8/2026 8:18:44 AM	75.5	-3.03	-3.04	0.0	0.0	3.012	3.166	-3.36	
CV-24053	5/7/2026 8:40:00 AM									
CV-24053	5/7/2026 8:40:00 AM									

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24054	5/26/2026 10:39:35 AM	153.1	-4.69	-4.61			4.676	4.634	-12.19	-12.31
CV-24054	5/26/2026 10:39:02 AM	154.4	-10.28	-4.08			10.280	4.069	-11.31	-11.75
CV-24054	5/18/2026 10:30:00 AM									
CV-24054	5/18/2026 10:27:38 AM	145.6	-4.41	-4.48			4.080	4.118	-4.89	-4.92
CV-24054	5/18/2026 10:26:19 AM	146.6	-5.95	-4.75			5.826	4.606	-5.85	-5.54
CV-24054	5/11/2026 8:39:09 AM	160.1	-2.69	-2.67			2.666	2.649	-2.19	-2.32
CV-24054	5/11/2026 8:36:54 AM	164.1	1.50	-2.55			0.000	2.520	-2.36	-2.21
CV-24054	5/4/2026 2:35:00 PM									
CV-24054	5/4/2026 2:35:00 PM									
CV-24054	5/4/2026 2:34:03 PM	173.8	-1.43	-1.39			1.333	1.385	-11.00	-11.11
CV-24054	5/4/2026 1:54:35 PM	147.1	-2.12	-2.13			2.120	2.128	-11.31	-11.31
CV-24054	5/4/2026 1:51:53 PM	148.2	-4.62	-3.41			4.646	3.449	-11.47	-11.45
CV-24055	5/26/2026 9:28:17 AM	136.8	-0.35	-0.35			0.350	0.356	-7.59	-7.86
CV-24055	5/26/2026 9:27:16 AM	137.2	-0.44	-0.34			0.431	0.340	-8.47	-8.01
CV-24055	5/13/2026 8:15:00 AM									
CV-24055	5/13/2026 8:15:00 AM									
CV-24055	5/12/2026 1:49:20 PM	137.3	-0.58	-0.57			0.534	0.504	-9.05	-8.62
CV-24055	5/12/2026 1:47:04 PM	137.9	-0.52	-0.62			0.514	0.629	-11.04	-10.68
CV-24056	5/19/2026 12:46:55 PM	122.8	-0.58	-0.38			0.573	0.379	-4.46	-4.66
CV-24056	5/1/2026 10:37:33 AM	124.8	-0.96	-0.96			0.942	0.936	-6.07	-6.08
CV-24057	5/22/2026 2:21:55 PM	144.2	-0.27	-0.25	17.2	17.5	0.838	0.873	-7.07	-7.35
CV-24057	5/11/2026 1:01:48 PM	139.5	-0.82	-0.84	15.0	15.0	0.635	0.629	-5.37	-5.49
CV-24057	5/11/2026 1:00:44 PM	139.4	-0.84	-0.83	15.1	15.0	0.642	0.631	-5.60	-5.72
CV-24058	5/22/2026 1:59:19 PM	105.3	-2.87	-3.28			2.819	3.187	-4.29	-5.12
CV-24058	5/11/2026 12:33:09 PM	110.0	-0.33	-1.50			0.316	1.508	-1.15	-2.80
CV-24059	5/22/2026 2:29:34 PM	114.1	-1.32	-1.32	0.4	0.7	0.000	0.001	-8.29	-8.40

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24059	5/4/2026 9:02:50 AM	123.9	-2.37	-2.31	3.7	1.4	0.037	0.006	-10.18	-9.78
CV-24059	5/4/2026 9:01:40 AM	121.0	-5.28	-2.38	3.0	1.3	0.025	0.005	-9.80	-9.95
CV-24060	5/20/2026 1:29:27 PM	113.6	-5.44	-4.61			5.359	4.575	-6.69	-6.80
CV-24060	5/4/2026 9:39:35 AM	109.2	-9.42	-7.94			9.679	8.217	-9.50	-9.28
CV-24061	5/26/2026 11:38:49 AM	100.6	-5.98	-6.96			6.087	7.055	-11.07	-11.15
CV-24061	5/8/2026 12:59:31 PM	97.8	-2.99	-2.95			2.900	2.886	-6.74	-6.06
CV-24062	5/22/2026 11:10:33 AM	143.7	-1.88	-1.78	0.0	0.0	1.829	1.760	-8.22	
CV-24062	5/22/2026 11:08:48 AM	140.3	-3.49	-3.46	0.0	0.0	3.461	3.337	-8.26	
CV-24062	5/8/2026 1:05:26 PM	134.2	-2.10	-2.02			2.018	1.948	-6.46	-5.92
CV-24062	5/7/2026 8:17:00 AM									
CV-24062	5/7/2026 8:17:00 AM									
CV-24062	5/4/2026 1:16:07 PM	148.7	-6.22	-6.38			6.249	6.276	-10.23	-10.14
CV-24062	5/4/2026 1:15:00 PM									
CV-24062	5/4/2026 1:15:00 PM									
CV-24063	5/28/2026 1:49:33 PM	183.7	-2.47	-2.43			2.461	2.410	-7.15	-7.17
CV-24063	5/20/2026 2:20:53 PM	173.7	-2.92	-2.92			3.045	3.045	0.00	0.00
CV-24063	5/14/2026 11:02:15 AM	171.9	-3.36	-3.31			3.386	3.216	-8.44	-8.43
CV-24063	5/14/2026 11:01:37 AM	173.4	0.65	-3.17			0.000	3.171	0.34	-8.71
CV-24063	5/14/2026 11:00:00 AM									
CV-24063	5/12/2026 8:20:00 AM									
CV-24063	5/12/2026 8:20:00 AM									
CV-24063	5/4/2026 1:35:00 PM									
CV-24063	5/4/2026 1:35:00 PM									
CV-24063	5/4/2026 1:34:44 PM	182.5	-3.44	-3.34			3.362	3.318	-11.05	-10.94
CV-24063	5/4/2026 1:33:24 PM	181.7	-7.10	-3.43			7.018	3.326	-11.01	-10.81
CV-24064	5/28/2026 2:15:41 PM	165.7	-7.85	-7.85			7.902	7.905	-8.16	-8.16
CV-24064	5/27/2026 1:55:09 PM	192.0	-6.74	-6.78			6.851	6.944	-6.68	-7.14

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24064	5/19/2026 1:40:00 PM									
CV-24064	5/19/2026 1:36:22 PM	192.5	-5.48	-4.27			4.594	4.805	-9.16	-9.07
CV-24064	5/12/2026 8:15:00 AM									
CV-24064	5/11/2026 10:07:41 AM	192.5	-10.46	-10.56			10.565	10.676	-13.49	-13.40
CV-24064	5/4/2026 9:10:00 AM									
CV-24064	5/4/2026 9:10:00 AM									
CV-24064	5/4/2026 9:09:33 AM	191.8	-11.35	-10.47			11.611	10.682	-12.85	-13.23
CV-24065-TP1	5/22/2026 10:27:26 AM	83.8	-0.33	-0.32			0.319	0.319	-10.19	-10.50
CV-24065-TP1	5/12/2026 8:15:00 AM									
CV-24065-TP1	5/11/2026 1:07:25 PM	100.2	-0.10	-0.03			0.054	0.001	0.48	0.67
CV-24065-TP1	5/7/2026 8:35:00 AM									
CV-24065-TP1	5/7/2026 8:35:00 AM									
CV-24066	5/19/2026 12:41:10 PM	110.5	-0.94	-0.93			0.940	0.926	-6.12	-5.98
CV-24066	5/11/2026 7:45:00 AM									
CV-24066	5/11/2026 7:45:00 AM									
CV-24066	5/1/2026 10:40:05 AM	117.5	-1.19	-1.18			1.198	1.180	-8.39	-7.76
CV-24067	5/26/2026 2:27:02 PM	152.4	-6.42	-6.45			0.056	0.048	-7.79	-7.77
CV-24067	5/26/2026 2:26:30 PM	152.4	-7.13	-6.63			0.000	0.000	-7.71	-7.51
CV-24067	5/19/2026 8:57:43 AM	160.7	-6.62	-6.65	5.8	5.6	0.099	0.093	-7.16	-7.16
CV-24067	5/19/2026 8:55:05 AM	160.8	-6.96	-6.65	5.2	6.1	0.079	0.110	-7.16	-7.27
CV-24067	5/14/2026 11:37:11 AM	134.5	0.40	0.37	0.0	0.0	-0.043	-0.038	0.35	
CV-24067	5/14/2026 11:35:44 AM	134.5	0.29	0.30	0.0	0.0	-0.018	-0.021	0.31	
CV-24068	5/26/2026 12:08:57 PM	129.1	-2.40	-2.40			2.342	2.342	-9.23	-8.68
CV-24068	5/26/2026 12:06:40 PM	129.7	-5.07	-3.21			4.947	3.150	-8.52	-8.94
CV-24068	5/1/2026 11:18:00 AM	116.0	-5.07	-4.88			5.611	5.406	-7.76	-7.74
CV-24069	5/28/2026 9:36:45 AM	93.4	-1.66	-1.65			1.681	1.663	-9.09	-8.46
CV-24069	5/28/2026 9:35:46 AM	93.7	-1.98	-1.68			2.008	1.703	-8.97	-8.90
CV-24069	5/28/2026 9:30:09 AM	96.2	-2.80	-2.08			2.836	2.106	-9.63	-10.08
CV-24069	5/13/2026 8:20:00 AM									

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24069	5/13/2026 8:20:00 AM									
CV-24069	5/4/2026 8:56:06 AM	93.4	-1.42	-1.43			1.390	1.399	0.01	0.00
CV-24070	5/20/2026 2:35:15 PM	136.2	-0.15	-0.10	3.3	3.2	0.230	0.220	-3.35	-3.53
CV-24070	5/20/2026 2:34:29 PM	136.1	-0.13	-0.15	4.8	5.8	0.493	0.736	-3.49	-3.63
CV-24070	5/20/2026 2:33:43 PM	135.6	0.95	-0.10	5.3	4.9	0.601	0.513	-3.46	-3.51
CV-24070	5/7/2026 8:20:00 AM									
CV-24070	5/7/2026 8:20:00 AM									
CV-24070	5/4/2026 9:12:35 AM	130.3	-1.21	-1.13	6.5	6.6	0.903	0.932	-10.00	-9.79
CV-24070	5/4/2026 9:11:52 AM	130.3	-1.65	-1.07	6.8	6.5	1.010	0.923	-10.01	-9.90
CV-24071	5/20/2026 1:35:21 PM	123.2	-3.74	-3.33	8.7	8.5	0.491	0.462	-6.65	-6.63
CV-24071	5/7/2026 8:10:00 AM									
CV-24071	5/7/2026 8:10:00 AM									
CV-24071	5/4/2026 9:43:04 AM	121.4	-5.57	-5.24	14.9	15.1	1.428	1.465	-9.94	-10.58
CV-24072	5/22/2026 2:05:23 PM	108.9	-2.50	-1.94	0.0	0.0	2.372	1.785	-8.01	
CV-24072	5/4/2026 2:18:34 PM	87.9	-0.66	-0.66			0.732	0.642	-10.14	-11.51
CV-24072	5/4/2026 2:17:08 PM	87.8	1.80	-0.35			0.000	0.319	-10.27	-10.18
CV-24073-TP1	5/26/2026 8:45:28 AM	132.6	-0.34	-0.30			0.327	0.283	-4.46	-4.51
CV-24073-TP1	5/26/2026 8:40:41 AM	133.5	-0.39	-0.34			0.388	0.334	-4.05	-4.01
CV-24073-TP1	5/8/2026 1:15:17 PM	128.9	-1.69	-1.61			1.673	1.558	-5.57	-4.83
CV-24073-TP1	5/6/2026 2:09:30 PM	125.8	-0.53	-0.56			0.526	0.516	-4.50	-4.20
CV-24074	5/22/2026 11:17:05 AM	111.0	-6.04	-3.69			6.001	3.582	-7.29	-7.39
CV-24074	5/6/2026 2:14:23 PM	107.0	-5.18	-4.71			5.207	4.588	-5.82	-5.79
CV-24075-TP1	5/29/2026 4:03:35 PM	187.0	-13.96	-14.01			14.314	14.356	-14.15	-14.30
CV-24075-TP1	5/29/2026 4:02:17 PM	186.7	-14.48	-14.48			14.792	14.792	-15.16	-15.16

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24075-TP1	5/11/2026 10:25:13 AM	99.5	-11.66	-11.98			11.789	12.211	0.04	0.04
CV-24075-TP1	5/4/2026 9:21:41 AM	187.2	-13.08	-13.16			13.372	13.398	0.04	0.04
CV-24075-TP1	5/4/2026 9:20:10 AM	60.6	-13.32	-13.51			13.587	13.736	0.07	0.04
CV-24075-TP1	5/4/2026 9:20:00 AM									
CV-24075-TP1	5/4/2026 9:20:00 AM									
CV-24076	5/27/2026 2:11:24 PM	172.3	-2.33	-2.17			2.219	2.125	-4.45	-4.54
CV-24076	5/19/2026 1:30:00 PM									
CV-24076	5/19/2026 1:22:53 PM	169.0	-3.53	-3.49			3.539	3.433	-6.72	-6.55
CV-24076	5/14/2026 10:30:00 AM									
CV-24076	5/14/2026 10:29:35 AM	174.6	-4.43	-4.29			4.392	4.275	-7.93	-7.35
CV-24076	5/4/2026 9:06:09 AM	176.9	-6.12	-5.74			6.253	5.927	0.00	0.00
CV-24076	5/4/2026 9:05:00 AM									
CV-24076	5/4/2026 9:05:00 AM									
CV-24077	5/28/2026 9:18:10 AM	147.0	-2.62	-2.61			2.611	2.602	-9.05	-9.02
CV-24077	5/28/2026 9:16:41 AM	144.5	-4.76	-4.77			4.761	4.767	-9.14	-9.16
CV-24077	5/20/2026 8:03:01 AM	142.4	-4.52	-4.48			4.525	4.494	-6.99	-7.10
CV-24077	5/11/2026 1:38:12 PM	146.1	-2.00	-2.00			1.956	1.960	5.79	6.10
CV-24077	5/7/2026 10:50:33 AM	148.8	-0.95	-0.98			0.957	0.990	-2.92	-3.04
CV-24077	5/7/2026 10:50:00 AM									
CV-24077	5/7/2026 10:50:00 AM									
CV-24077	5/1/2026 10:03:08 AM	151.0	-1.23	-1.24			1.237	1.244	-6.62	-6.63
CV-24077	5/1/2026 10:01:59 AM	151.0	-1.95	-1.20			1.941	1.188	-5.89	-6.33
CV-24078	5/19/2026 8:40:05 AM	130.7	-2.01	-2.00	8.6	9.4	0.207	0.243	-6.99	-7.34
CV-24078	5/19/2026 8:35:10 AM	130.8	-2.24	-2.23	8.1	8.3	0.182	0.191	-7.00	-6.90
CV-24078	5/19/2026 8:34:05 AM	130.8	-2.13	-2.21	7.9	8.2	0.173	0.189	-7.05	-7.02
CV-24078	5/19/2026 8:31:45 AM	130.9	-2.77	-2.21	12.1	8.8	0.407	0.217	-6.95	-7.18
CV-24078	5/1/2026 10:43:48 AM	126.2	-0.94	-0.83	8.1	6.9	0.178	0.131	-5.99	-5.70
CV-24079-TP8	5/26/2026 12:13:32 PM	135.9	-5.41	-5.41			5.321	5.294	-0.27	-0.14
CV-24079-TP8	5/26/2026 12:12:54 PM	137.0	-7.80	-5.70			7.727	5.474	-0.06	-0.04
CV-24079-TP8	5/11/2026 1:15:47 PM	141.7	-5.34	-5.34			5.190	5.193	0.02	0.02
CV-24079-TP8	5/7/2026 10:41:06 AM	172.6	-1.59	-1.63			1.581	1.594	0.33	0.32

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24079-TP8	5/7/2026 10:40:00 AM									
CV-24079-TP8	5/7/2026 10:40:00 AM									
CV-24079-TP8	5/7/2026 10:38:33 AM	168.1	0.98	-1.80			0.000	1.777	0.33	0.33
CV-24079-TP8	5/1/2026 11:22:57 AM	152.4	-0.16	-0.16			0.148	0.150	0.68	0.65
CV-24079-TP8	5/1/2026 11:22:12 AM	154.7	-0.62	-0.25			0.618	0.246	0.66	0.67
CV-24080	5/21/2026 9:36:06 AM	117.0	-0.38	-0.36	2.8	3.2	0.021	0.028	-1.24	-0.96
CV-24080	5/1/2026 11:09:29 AM	123.0	-0.56	-0.58	2.5	5.1	0.017	0.071	-5.24	-8.14
CV-24081-TP1	5/20/2026 2:26:51 PM	117.4	-0.23	-0.22			0.220	0.206	-3.04	-2.89
CV-24081-TP1	5/20/2026 2:25:55 PM	118.7	0.33	-0.12			0.000	0.126	-3.10	-3.13
CV-24081-TP1	5/14/2026 10:40:33 AM	120.2	-0.76	-0.75			0.745	0.743	-7.68	-7.55
CV-24082	5/20/2026 11:24:26 AM	124.4	-0.20	-0.13			0.167	0.107	-6.11	-6.36
CV-24082	5/4/2026 10:11:50 AM	111.4	-0.42	-0.44			0.390	0.411	-8.93	-9.09
CV-24083	5/20/2026 1:53:17 PM	125.0	-0.17	-0.17			0.171	0.181	-6.95	-7.14
CV-24083	5/4/2026 9:58:27 AM	108.4	-0.80	-0.81			0.780	0.787	-10.17	-10.44
CV-24083	5/4/2026 9:56:08 AM	105.9	0.60	-0.69			0.000	0.674	-10.39	-10.34
CV-24084-TP1	5/27/2026 10:49:57 AM	180.7	-2.12	-2.36			1.995	2.378	-5.06	-5.12
CV-24084-TP1	5/19/2026 10:24:00 AM	180.9	-3.47	-3.40			3.626	3.026	-6.08	-5.94
CV-24084-TP1	5/11/2026 1:05:39 PM	181.3	-1.83	-1.69			1.848	1.723	-4.96	-4.94
CV-24084-TP1	5/4/2026 2:08:40 PM	180.8	-1.49	-1.39			1.341	1.272	-8.12	-8.12
CV-24084-TP1	5/4/2026 2:05:00 PM									
CV-24084-TP1	5/4/2026 2:05:00 PM									
CV-24085	5/20/2026 10:07:30 AM	128.5	-0.76	-0.86	12.3	17.0	0.429	0.818	-7.52	
CV-24085	5/1/2026 10:47:32 AM	126.8	-0.59	-0.58	10.0	10.2	0.277	0.284	-7.83	-7.72
CV-24086	5/21/2026 9:49:26 AM	114.5	-0.24	-0.23	9.4	9.5	0.239	0.242	-4.68	-4.61
CV-24086	5/1/2026 11:00:38 AM	116.2	-0.61	-0.40	13.2	11.5	0.468	0.355	-7.80	-7.55
CV-24087	5/20/2026 1:36:05 PM	119.0	-1.12	-1.13	38.9	39.1	4.144	4.189	-5.49	-5.55
CV-24087	5/5/2026 10:43:05 AM	115.8	-0.76	-0.78	22.3	21.8	1.345	1.284	-9.08	-9.18

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24088	5/28/2026 9:04:04 AM	99.2	-1.94	-1.94			1.943	1.949	-8.79	-8.56
CV-24088	5/4/2026 1:51:55 PM	100.1	-2.03	-1.98			1.968	1.927	-7.61	-7.59
CV-24089	5/20/2026 11:52:44 AM	99.0	-7.28	-7.29	0.0	0.0	-0.012	-0.010	-7.30	
CV-24089	5/20/2026 11:51:37 AM	99.1	-7.33	-7.34	0.0	0.5	-0.001	0.001	-7.33	
CV-24089	5/4/2026 11:15:57 AM	71.8	-8.91	-8.88	0.0	0.0	-0.019	-0.017	-8.82	
CV-24089	5/4/2026 11:14:40 AM	73.5	-8.85	-8.81	0.0	0.0	-0.008	-0.008	-8.89	
CV-24090	5/20/2026 11:45:41 AM	120.2	-0.70	-0.70	0.0	0.0	0.698	0.698	-7.71	
CV-24090	5/11/2026 1:42:21 PM	113.1	-0.71	-0.68			0.781	0.765	-6.31	-6.38
CV-24090	5/6/2026 1:52:09 PM	116.9	-0.03	-0.11			0.032	0.116	-4.41	-4.40
CV-24091	5/21/2026 9:33:38 AM	99.6	-0.60	-0.59	5.4	5.3	0.076	0.073	-6.07	-6.78
CV-24091	5/4/2026 2:15:54 PM	79.3	-0.57	-0.69	10.5	9.5	0.024	0.020	-7.57	
CV-24092	5/6/2026 10:10:24 AM	120.7	-2.34	-2.42	0.0	0.0	-2.306	-3.024	-9.10	
CV-24093	5/22/2026 12:11:17 PM	118.3	-0.90	-0.66	16.0	10.2	1.694	0.684	-13.31	
CV-24093	5/1/2026 3:13:57 PM	118.5	-0.06	-0.07	14.2	14.2	1.362	1.363	-12.91	
CV-24094	5/22/2026 11:49:38 AM	88.3	-1.91	-1.97	1.0	1.0	0.149	0.150	-11.94	
CV-24094	5/22/2026 11:48:00 AM	87.0	-4.45	-2.49	1.4	1.0	0.255	0.120	-11.15	
CV-24094	5/1/2026 2:32:48 PM	88.6	-1.42	-1.45	1.0	1.0	0.137	0.137	-12.58	
CV-24095	5/28/2026 10:32:51 AM	179.1	0.32	0.14			0.000	0.000	0.16	-0.59
CV-24095	5/28/2026 10:30:18 AM	179.3	0.50	0.47			0.000	0.000	-0.54	-0.22
CV-24095	5/20/2026 10:30:33 AM	178.7	-2.17	-2.41			2.175	2.373	-4.22	-4.45
CV-24095	5/14/2026 1:28:11 PM	178.7	1.35	0.75			0.000	0.000	0.24	0.81
CV-24095	5/13/2026 10:56:02 AM	178.3	0.59	0.95			0.000	0.000	0.62	1.83
CV-24095	5/13/2026 10:53:04 AM	177.9	0.91	1.66			0.000	0.000	0.65	1.13
CV-24095	5/6/2026 10:46:15 AM	176.2	-1.28	-1.30			1.269	1.290	0.34	0.34
CV-24095	5/6/2026 10:45:00 AM									
CV-24095	5/6/2026 10:45:00 AM									
CV-24095	5/6/2026 8:05:00 AM									
CV-24095	5/6/2026 8:05:00 AM									
CV-24096	5/20/2026 10:19:24 AM	98.5	-2.34	-1.97			2.330	1.963	-3.33	-3.16

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24096	5/12/2026 9:25:00 AM	81.9	-2.06	-2.02	0.0	0.0	2.089	2.087	-3.71	
CV-24096	5/12/2026 9:22:51 AM	81.8	-2.99	-1.86	0.0	0.0	3.021	1.991	-3.62	
CV-24097	5/20/2026 10:29:27 AM	86.8	-1.19	-1.19			1.181	1.189	-4.94	-4.90
CV-24097	5/20/2026 10:28:10 AM	91.2	-3.87	-1.12			3.844	1.117	-4.95	-4.95
CV-24097	5/12/2026 9:16:39 AM	81.2	-0.10	-0.10	0.0	0.0	0.206	0.119	-5.64	
CV-24097	5/12/2026 9:13:02 AM	87.4	0.02	-0.04	0.0	0.0	-0.237	-0.349	-5.38	
CV-24098	5/20/2026 10:43:25 AM	95.9	-4.18	-4.01			4.188	3.970	-3.80	-3.67
CV-24098	5/3/2026 11:01:16 AM	70.5	-6.65	-6.20			4.952	4.889	-6.53	-6.36
CV-24098	5/3/2026 11:00:24 AM	69.7	-7.60	-7.39			7.739	7.492	-7.81	-7.58
CV-24098	5/1/2026 10:01:03 AM	93.8	-4.22	-4.01			3.841	3.605	-4.30	-4.12
CV-24099	5/20/2026 10:48:09 AM	97.6	-0.54	-0.48			0.549	0.494	-3.60	-3.52
CV-24099	5/3/2026 10:28:51 AM	61.5	-1.09	-1.03			1.101	1.051	-6.43	-3.83
CV-24099	5/3/2026 10:28:19 AM	61.4	-0.90	-1.00			0.905	1.013	-7.63	-7.22
CV-24099	5/3/2026 10:27:26 AM	61.4	-0.01	-1.06			0.000	1.044	-7.32	-6.38
CV-24099	5/1/2026 10:08:04 AM	83.2	-4.81	-4.58			4.424	4.479	-4.91	-5.27
CV-24100	5/28/2026 10:02:06 AM	148.5	-0.47	-0.51			0.459	0.512	-4.78	-4.75
CV-24100	5/20/2026 10:01:19 AM	149.5	-2.99	-2.99			3.025	3.008	-6.69	-6.55
CV-24100	5/20/2026 10:00:42 AM	150.4	0.10	-2.39			0.000	2.400	-6.84	-6.73
CV-24100	5/20/2026 9:37:52 AM	151.5	-0.21	-0.23			0.219	0.240	-7.51	-7.54
CV-24100	5/20/2026 9:36:36 AM	150.9	-1.42	-0.31			1.419	0.310	-7.43	-7.41
CV-24100	5/13/2026 10:42:49 AM	143.8	-2.64	-2.64			2.642	2.642	-7.80	-7.80
CV-24100	5/13/2026 10:41:16 AM	141.9	-7.76	-2.95			7.702	2.953	-7.76	-7.70
CV-24100	5/13/2026 8:25:00 AM									
CV-24100	5/13/2026 8:25:00 AM									

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24100	5/7/2026 11:06:06 AM	146.9	-3.18	-3.18			3.160	3.159	-3.06	-3.06
CV-24100	5/7/2026 11:05:00 AM									
CV-24100	5/7/2026 11:05:00 AM									
CV-24100	5/7/2026 11:04:29 AM	146.0	2.22	-2.88			0.000	2.849	-3.06	-3.22
CV-24100	5/1/2026 10:25:18 AM	147.6	-0.61	-0.60			0.582	0.572	-8.60	-8.69
CV-24101	5/20/2026 9:41:50 AM	115.3	-7.37	-7.22			7.534	7.438	-7.34	-7.38
CV-24101	5/12/2026 8:51:03 AM	112.4	-7.47	-7.36	0.0	0.0	7.674	7.698	-7.01	
CV-24101	5/6/2026 7:40:00 AM									
CV-24101	5/6/2026 7:40:00 AM									
CV-24101	5/1/2026 10:20:22 AM		-7.56				7.603		-7.94	
CV-24102	5/19/2026 10:30:38 AM	103.0	-0.48	-0.48			0.478	0.482	-6.89	-6.89
CV-24102	5/4/2026 9:42:22 AM	89.0	-0.59	-0.59			0.596	0.590	-8.51	-8.62
CV-24103	5/20/2026 9:42:52 AM	95.8	-0.95	-0.95	5.0	4.6	0.488	0.412	-8.39	
CV-24103	5/4/2026 9:28:18 AM	95.4	-1.15	-1.13	5.6	5.1	0.631	0.529	-9.08	
CV-24104	5/20/2026 12:16:58 PM	96.5	-1.12	-0.95	2.8	2.2	0.931	0.571	-6.94	
CV-24104	5/4/2026 9:39:11 AM	93.1	-3.25	-2.75	3.5	1.2	0.247	0.032	-8.54	
CV-24105	5/20/2026 11:35:42 AM	109.2	-0.32	-0.30	8.9	8.9	0.488	0.489	-7.40	
CV-24105	5/4/2026 9:49:47 AM	102.3	-0.52	-0.52	10.3	12.2	0.631	0.893	-8.73	
CV-24106	5/28/2026 12:51:23 PM	127.9	-1.50	-1.50	10.7	10.8	0.316	0.320	-13.59	-13.68
CV-24106	5/20/2026 2:33:03 PM	128.8	-0.83	-0.70	0.0	0.0	-0.963	-1.111	-8.97	
CV-24106	5/8/2026 11:07:42 AM	127.2	-0.57	-0.54	8.0	5.2	0.171	0.072	-6.25	
CV-24107	5/4/2026 11:30:05 AM	122.5	-4.33	-4.05			4.316	4.037	-8.71	-8.89
CV-24108	5/28/2026 12:33:54 PM	128.9	-13.62	-13.83	49.4	47.9	1.641	1.544	-14.69	-15.53
CV-24108	5/4/2026 1:40:16 PM	128.1	-12.38	-12.37	55.1	54.9	0.820	0.813	-13.71	-13.71
CV-24109	5/4/2026 11:58:26 AM	106.0	-8.47	-7.77			9.014	8.273	-12.23	-12.53
CV-24110	5/1/2026 10:54:33 AM	127.3	-1.44	-1.13	29.6	16.0	2.547	0.737	-13.24	
CV-24111	5/1/2026 11:14:00 AM	111.5	-7.44	-6.42	0.0	0.0	7.382	6.288	-11.95	
CV-24112	5/1/2026 11:04:34 AM	127.7	-1.05	-0.90	14.3	10.8	0.542	0.310	-12.39	
CV-24114	5/5/2026 2:47:36 PM	119.9	-9.32	-9.32	4.6	4.6	0.057	0.057	-9.46	
CV-24116	5/11/2026 9:58:53 AM	126.6	-7.93	-5.48	0.0	0.0	7.987	5.245	-10.77	
CV-24117	5/28/2026 12:44:53 PM	101.7	-1.33	-1.33			1.317	1.317	-15.47	-15.56
CV-24117	5/4/2026 10:48:48 AM	90.0	-1.32	-1.32			1.305	1.306	-14.35	-14.47
CV-24118	5/11/2026 1:37:44 PM	128.9	-1.81	-1.84			1.750	1.762	-12.57	-12.23

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24119	5/8/2026 2:33:20 PM	144.1	-4.47	-4.45			4.365	4.288	-12.29	-12.35
CV-24119	5/8/2026 2:32:34 PM	143.9	-5.72	-5.09			5.665	5.068	-11.98	-12.29
CV-24119	5/7/2026 10:38:27 AM	137.4	-0.12	-0.14	0.0	0.0	0.105	0.223	-3.72	
CV-24119	5/7/2026 10:35:25 AM	137.3	-0.27	-0.29	0.0	0.0	0.247	0.320	-4.00	
CV-24120	5/26/2026 2:15:09 PM	89.0	-8.11	-7.69			8.054	7.880	-7.45	-7.59
CV-24120	5/11/2026 10:28:50 AM	98.1	-1.16	-1.18			1.186	1.219	-1.37	-1.37
CV-24120	5/4/2026 8:00:00 AM									
CV-24121	5/26/2026 2:08:29 PM	78.2	-8.13	-0.55			8.299	0.533	-8.06	-8.01
CV-24121	5/11/2026 10:33:56 AM	101.4	-1.05	-0.86			1.054	0.869	-1.27	-0.87
CV-24121	5/11/2026 10:33:18 AM	101.3	-0.80	-0.82			0.812	0.830	-0.89	-0.97
CV-24121	5/4/2026 7:55:00 AM									
CV-24122	5/29/2026 9:40:41 AM	81.5	-2.22	-2.27	0.7	0.0	0.028	-0.023	-4.97	
CV-24122	5/29/2026 9:33:20 AM	76.9	-4.68	-2.41	0.5	0.0	0.015	-0.017	-5.20	
CV-24122	5/6/2026 10:31:06 AM	85.9	-2.43	-2.92	1.8	2.8	0.156	0.396	-0.81	-1.19
CV-24122	5/4/2026 8:20:00 AM									
CV-24123	5/28/2026 11:46:50 AM	116.7	0.63	0.60	6.3	5.6	0.107	0.084	0.47	0.33
CV-24123	5/28/2026 11:46:25 AM	116.6	0.65	0.67	8.9	5.9	0.215	0.094	0.42	0.29
CV-24123	5/15/2026 11:28:22 AM	113.9	-0.16	-0.16	3.7	3.7	0.042	0.043	-0.44	
CV-24123	5/15/2026 11:24:46 AM	112.5	3.24	-0.20	3.5	2.0	0.038	0.013	-2.56	
CV-24123	5/14/2026 10:54:34 AM	117.3	0.18	0.18	19.2	20.5	0.994	1.128	0.29	0.00
CV-24123	5/14/2026 10:53:53 AM	117.1	0.40	0.33	18.5	21.3	0.925	1.222	0.34	0.04
CV-24124	5/29/2026 11:28:31 AM	127.0	-1.49	-1.46	0.0	0.0	1.486	1.529	-5.53	
CV-24125-TP2	5/26/2026 1:56:27 PM	99.8	-1.35	-1.41			1.297	1.385	-3.85	-3.22

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24125-TP2	5/13/2026 7:55:00 AM									
CV-24125-TP2	5/13/2026 7:55:00 AM									
CV-24126	5/26/2026 10:58:38 AM	187.1	-2.02	-1.91			2.452	1.770	-2.13	-1.68
CV-24126	5/22/2026 12:29:20 PM	188.6	-0.30	-0.38			0.276	0.835	-1.18	-1.26
CV-24126	5/22/2026 12:28:40 PM	188.5	-0.20	-0.22			0.265	0.416	-1.11	-1.07
CV-24126	5/18/2026 10:50:00 AM									
CV-24126	5/18/2026 10:44:28 AM	186.3	1.42	1.36			0.000	0.000	1.78	1.71
CV-24126	5/18/2026 10:43:37 AM	187.2	1.28	1.80			0.000	0.000	1.52	1.93
CV-24126	5/12/2026 10:30:00 AM									
CV-24126	5/12/2026 10:28:41 AM	188.4	-2.83	-2.62			2.743	2.583	-2.72	-2.45
CV-24126	5/4/2026 2:50:00 PM									
CV-24126	5/4/2026 2:50:00 PM									
CV-24126	5/4/2026 2:40:40 PM	187.1	-2.12	-2.63			1.963	2.083	-2.27	-2.45
CV-24127	5/7/2026 10:22:55 AM	141.2	2.20	2.31			0.000	0.000	0.32	0.34
CV-24127	5/7/2026 10:21:43 AM	141.1	5.40	2.26			0.000	0.000	0.32	0.33
CV-24127	5/7/2026 10:20:00 AM									
CV-24127	5/7/2026 10:20:00 AM									
CV-24127	5/4/2026 8:15:00 AM									
CV-24128	5/26/2026 2:25:15 PM	91.7	-1.98	-1.98			1.926	1.931	-10.24	-10.61
CV-24128	5/13/2026 7:50:00 AM									
CV-24128	5/13/2026 7:50:00 AM									
CV-24128	5/8/2026 9:33:23 AM	99.5	-0.86	-0.77	0.0	0.0	0.748	0.739	-3.16	
CV-24129	5/26/2026 1:33:50 PM	121.1	-5.09	-5.15			5.194	5.324	-12.17	-12.90
CV-24129	5/8/2026 9:24:27 AM	122.5	-1.60	-1.58	0.0	0.0	1.696	1.645	-3.75	
CV-24130	5/26/2026 1:42:41 PM	109.0	-9.86	-7.80			10.033	7.913	-11.29	-11.40
CV-24131	5/29/2026 1:47:07 PM	120.1	-1.78	-1.09	16.4	11.1	0.744	0.340	-8.14	
CV-24132	5/6/2026 10:15:34 AM	129.4	-4.57	-4.74	42.2	43.0	0.469	0.486	-7.48	-7.96
CV-24133	5/7/2026 9:28:04 AM	121.5	-2.04	-2.05	12.5	12.7	0.402	0.418	-3.18	
CV-24134-TP1	5/26/2026 10:55:47 AM	151.4	-3.84	-3.90			3.849	3.874	-5.03	-5.38
CV-24134-TP1	5/18/2026 10:45:00 AM									
CV-24134-TP1	5/18/2026 10:39:38 AM	151.6	-0.11	-0.08			0.000	0.000	-1.01	-1.22
CV-24134-TP1	5/12/2026 10:35:00 AM									

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24134-TP1	5/12/2026 10:33:32 AM	150.9	-2.75	-2.74			2.745	2.735	-4.05	-4.05
CV-24134-TP1	5/12/2026 10:32:12 AM	150.8	0.95	-2.25			0.000	2.255	-4.10	-3.95
CV-24134-TP1	5/11/2026 2:33:48 PM	146.9	-1.74	-1.76	0.0	0.0	1.833	1.831	-5.30	
CV-24134-TP1	5/11/2026 2:29:03 PM	146.4	-4.14	-1.81	0.0	0.0	4.209	1.833	-5.22	
CV-24134-TP1	5/7/2026 1:15:00 PM									
CV-24134-TP1	5/7/2026 1:14:04 PM	149.5	-0.65	-0.62			0.632	0.602	-0.30	-0.30
CV-24135	5/11/2026 2:17:55 PM	140.7	-0.51	-0.52	0.0	0.0	0.565	0.568	-5.20	
CV-24135	5/11/2026 2:15:34 PM	140.7	2.11	-0.33	0.0	0.0	-2.031	0.558	-5.32	
CV-24136	5/11/2026 11:29:51 AM	125.6	-4.72	-4.08	0.0	0.0	4.598	3.945	-6.96	
CV-24137	5/4/2026 1:08:31 PM	75.6	-0.10	-0.12			0.147	0.134	0.17	0.29
CV-24137	5/4/2026 1:07:02 PM	74.0	3.07	-0.10			0.000	0.179	0.19	0.22
CV-24138	5/28/2026 9:03:38 AM	96.9	-2.02	-1.80			2.744	1.725	-1.85	-1.33
CV-24138	5/28/2026 9:02:31 AM	95.5	-2.69	-2.09			2.751	2.112	-2.20	-1.67
CV-24138	5/13/2026 1:14:42 PM	131.6	-0.58	-0.38			0.568	0.314	-0.52	-0.30
CV-24138	5/6/2026 11:00:00 AM									
CV-24138	5/6/2026 11:00:00 AM									
CV-24138	5/6/2026 10:58:19 AM	160.2	-3.80	-3.60			3.840	3.429	0.32	0.34
CV-24138	5/5/2026 8:15:00 AM									
CV-24138	5/5/2026 8:15:00 AM									
CV-24139	5/28/2026 9:08:34 AM	125.5	-6.44	-6.10			6.765	6.401	-6.76	-6.69
CV-24139	5/15/2026 8:22:50 AM	139.8	-0.21	-0.20			0.213	0.202	-6.72	-6.33
CV-24139	5/15/2026 8:12:50 AM	136.1	25.00	-0.23			0.000	0.227	-6.42	-6.14
CV-24139	5/5/2026 8:10:00 AM									
CV-24139	5/5/2026 8:10:00 AM									
CV-24140	5/28/2026 10:52:29 AM	170.8	-1.75	-1.97			1.726	1.959	-5.22	-4.88
CV-24140	5/28/2026 10:50:34 AM	170.8	5.74	-1.38			0.000	1.356	-4.68	-4.83
CV-24140	5/20/2026 1:28:20 PM	148.4	-2.42	-2.47			2.416	2.451	-3.40	-3.74
CV-24140	5/20/2026 1:26:41 PM	148.5	-3.62	-2.56			3.630	2.558	-3.60	-3.62
CV-24140	5/13/2026 1:18:30 PM	157.7	-2.58	-2.53			2.565	2.555	-4.54	-4.03

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24140	5/6/2026 11:05:00 AM									
CV-24140	5/6/2026 11:05:00 AM									
CV-24140	5/6/2026 11:04:58 AM	164.9	-5.03	-5.03			4.753	4.753	-5.22	-5.24
CV-24140	5/5/2026 8:05:00 AM									
CV-24140	5/5/2026 8:05:00 AM									
CV-24141	5/28/2026 9:31:07 AM	65.9	-5.95	-5.76			6.238	6.176	-5.94	-5.76
CV-24141	5/28/2026 9:30:26 AM	65.7	-6.76	-5.94			7.127	6.330	-7.11	-5.99
CV-24141	5/5/2026 7:45:00 AM									
CV-24141	5/5/2026 7:45:00 AM									
CV-24141	5/1/2026 8:57:18 AM	76.3	-0.08	-0.95			0.073	0.928	-6.86	-6.53
CV-24142	5/28/2026 10:41:54 AM	100.8	-1.89	-1.89			1.876	1.890	-1.58	-1.60
CV-24142	5/28/2026 10:40:43 AM	100.7	-1.92	-1.91			1.912	1.936	-1.66	-1.68
CV-24142	5/20/2026 1:14:55 PM	151.1	-2.68	-2.87			2.629	2.780	0.00	-0.04
CV-24142	5/20/2026 1:02:37 PM	151.5	-3.36	-2.50			3.313	2.494	-3.07	-2.49
CV-24142	5/15/2026 8:03:40 AM	174.7	-3.95	-3.94			3.946	3.985	-4.77	-4.78
CV-24142	5/15/2026 7:59:13 AM	174.0	-4.10	-4.10			4.115	4.115	-4.96	-4.96
CV-24142	5/14/2026 8:35:00 AM									
CV-24142	5/6/2026 8:10:00 AM									
CV-24142	5/6/2026 8:10:00 AM									
CV-24143	5/28/2026 9:20:03 AM	72.4	-6.42	-6.44			6.724	6.767	-6.31	-6.38
CV-24143	5/28/2026 9:19:15 AM	72.9	-7.01	-6.42			7.249	6.661	-6.80	-6.27
CV-24143	5/5/2026 7:55:00 AM									
CV-24143	5/5/2026 7:55:00 AM									
CV-24143	5/1/2026 2:16:44 PM	96.8	-2.80	-2.85	0.0	0.0	2.808	2.964	-4.29	
CV-24143	5/1/2026 2:15:01 PM	97.6	-4.24	-2.26	0.0	0.0	4.120	2.401	-4.36	
CV-24144	5/20/2026 10:35:16 AM	100.3	-4.49	-4.52			4.462	4.516	-4.27	-4.34
CV-24144	5/12/2026 9:03:44 AM	88.3	-4.85	-4.84	0.0	0.0	4.953	4.881	-4.77	
CV-24145	5/26/2026 2:12:30 PM	105.8	-8.40	-8.38			0.000	0.000	-9.24	-8.44
CV-24145	5/18/2026 2:54:25 PM	145.7	-2.63	-2.56			0.000	0.141	-3.22	-3.74
CV-24145	5/18/2026 2:45:00 PM									

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24145	5/18/2026 2:38:58 PM	146.8	-0.66	-0.63			2.650	2.653	-0.40	-0.38
CV-24145	5/12/2026 2:40:29 PM	163.8	-4.56	-4.58			0.000	0.000	-7.74	-7.43
CV-24145	5/12/2026 2:34:47 PM	161.5	-4.85	-4.85			0.851	0.822	-7.28	-7.14
CV-24145	5/12/2026 2:32:19 PM	162.7	-6.13	-5.73			2.042	1.210	-6.49	-6.94
CV-24145	5/12/2026 2:15:00 PM									
CV-24145	5/5/2026 1:25:00 PM									
CV-24145	5/5/2026 1:25:00 PM									
CV-24145	5/5/2026 1:22:41 PM	171.5	-7.02	-7.01			0.876	0.868	-8.22	-9.16
CV-24146	5/28/2026 10:15:05 AM	106.4	1.38	1.31	4.3	7.4	0.024	0.070	1.49	1.48
CV-24146	5/28/2026 10:14:14 AM	107.5	1.16	1.34	6.3	2.1	0.051	0.006	1.35	1.59
CV-24146	5/11/2026 9:52:43 AM	115.2	-0.09	-0.10	13.8	13.8	0.246	0.246	-0.46	-0.38
CV-24147	5/28/2026 11:28:34 AM	102.6	-0.31	-0.37	22.3	23.8	0.124	0.141	-0.23	-0.38
CV-24147	5/26/2026 9:21:12 AM	100.4	-1.00	-0.99	1.7	0.6	0.001	0.000	-1.02	-1.02
CV-24147	5/14/2026 2:08:02 PM	108.2	-1.51	-1.53	13.4	5.4	0.045	0.007	-1.59	-1.71
CV-24147	5/11/2026 10:06:39 AM		-0.66	-0.73	6.9	11.5	0.012	0.034	-0.81	-0.96
CV-24147	5/11/2026 10:05:05 AM	110.6	-0.58	-0.71	6.9	8.0	0.012	0.016	-0.78	-0.96
CV-24147	5/11/2026 10:02:23 AM	109.5	0.56	-0.07	6.0	5.2	0.009	0.007	-0.93	-0.77
CV-24148	5/27/2026 1:49:59 PM	168.8	-3.52	-3.48			3.481	3.361	-7.43	-7.35
CV-24148	5/19/2026 1:50:00 PM									
CV-24148	5/19/2026 1:44:57 PM	171.8	-3.45	-3.56			3.468	3.577	-9.45	-9.38
CV-24148	5/19/2026 1:43:50 PM	172.7	-7.79	-4.26			7.808	4.299	-9.07	-9.22
CV-24148	5/11/2026 10:02:23 AM	178.6	-4.29	-3.94			4.261	3.909	-13.74	-13.72
CV-24148	5/4/2026 9:31:25 AM	177.6	-6.99	-6.93			7.121	6.900	-13.43	-13.36
CV-24148	5/4/2026 9:30:00 AM									
CV-24148	5/4/2026 9:30:00 AM									
CV-24149	5/28/2026 12:48:18 PM	85.3	-8.23	-7.68	8.8	9.2	0.025	0.027		
CV-24149	5/6/2026 2:58:21 PM	96.1	-8.33	-8.37	14.3	5.5	0.051	0.008	-10.23	-10.08
CV-24150	5/22/2026 11:53:52 AM	108.5	-1.38	-1.05	0.0	0.0	1.294	0.967	-11.23	
CV-24150	5/1/2026 10:15:37 AM	110.5	-1.00	-0.82	0.0	0.0	1.058	0.892	-13.50	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24151	5/21/2026 1:59:13 PM	102.8	-2.29	-2.19			2.205	2.163	-4.47	-4.44
CV-24151	5/6/2026 2:05:59 PM	88.0	-4.39	-4.28			4.287	4.203	-6.52	-5.75
CV-24152	5/26/2026 8:32:21 AM	129.7	-0.10	-0.11	17.9	17.1	0.765	0.696	-3.96	-4.00
CV-24152	5/26/2026 8:31:06 AM	129.8	-0.43	-0.12	19.9	17.2	0.941	0.707	-3.78	-3.81
CV-24152	5/6/2026 2:21:42 PM	131.4	-0.22	-0.13	29.0	29.6	1.996	2.088	-3.33	-3.30
CV-24152	5/6/2026 2:21:09 PM	131.3	0.31	-0.07	23.7	28.6	1.327	1.939	-3.29	-3.40
CV-24153	5/22/2026 11:40:23 AM	111.9	-1.17	-0.94	0.0	0.0	1.108	0.879	-11.73	
CV-24153	5/1/2026 3:03:06 PM	104.1	-0.20	-0.20	0.0	0.0	0.183	0.172	-12.52	
CV-24153	5/1/2026 3:02:03 PM	103.9	0.45	-0.05	0.0	0.0	-0.485	0.024	-12.49	
CV-24154	5/22/2026 11:58:09 AM	111.5	-2.26	-1.99	0.0	0.0	2.165	1.946	-7.87	
CV-24154	5/1/2026 3:20:22 PM	103.0	-1.41	-0.76	0.0	0.0	1.453	0.854	-7.55	
CV-24155	5/26/2026 8:18:02 AM	119.3	-0.44	-0.44			0.428	0.427	-7.66	-7.66
CV-24155	5/1/2026 3:09:53 PM	119.0	-0.07	-0.07	0.0	0.0	0.058	0.052	-9.99	
CV-24155	5/1/2026 3:08:32 PM	115.8	0.33	-0.02	0.0	0.0	-0.386	-0.020	-10.00	
CV-24156	5/22/2026 2:00:28 PM	123.0	-0.79	-0.56	20.3	20.4	0.106	0.107	-0.55	
CV-24156	5/4/2026 2:11:53 PM	122.4	-0.29	-0.24	13.7	19.0	0.049	0.094	-8.06	-8.06
CV-24157	5/21/2026 2:09:04 PM	105.6	-0.20	-0.19			0.084	0.095	-2.79	-3.13
CV-24157	5/21/2026 2:08:15 PM	105.2	0.28	-0.14			0.000	0.000	-2.80	-2.85
CV-24157	5/4/2026 2:00:15 PM	93.6	-0.76	-0.76			0.819	0.700	-8.45	-8.27
CV-24158	5/21/2026 10:58:26 AM	128.4	-0.38	-0.38	32.7	32.8	2.978	2.989	-2.56	-2.62
CV-24158	5/6/2026 10:59:56 AM	125.3	-0.15	-0.14	14.8	14.9	0.602	0.608	-8.17	-8.04
CV-24159	5/21/2026 9:02:31 AM	131.6	-0.29	-0.29	23.9	23.8	1.361	1.350	-12.32	-12.71
CV-24159	5/21/2026 9:01:50 AM	131.7	-0.38	-0.30	26.4	24.2	1.669	1.401	-12.90	-13.30
CV-24159	5/6/2026 10:49:41 AM	125.5	-0.80	-0.39	23.3	16.0	1.309	0.618	-13.79	
CV-24160	5/22/2026 12:06:28 PM	127.0	-3.82	-3.36	31.7	27.8	2.393	1.835	-12.52	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24160	5/6/2026 12:39:52 PM	124.8	-2.59	-2.80	19.2	21.6	0.874	1.100	-11.29	-11.10
CV-24160	5/6/2026 10:29:54 AM	122.5	-4.90	-3.86	40.1	29.9	3.869	2.157	-14.16	
CV-24161	5/6/2026 10:20:39 AM	111.3	-0.26	-0.26	0.0	0.0	0.254	0.252	-14.46	
CV-24161	5/6/2026 10:19:18 AM	108.8	0.05	-0.14	0.0	0.0	-0.094	0.190	-14.32	
CV-24162	5/4/2026 12:02:44 PM	86.5	-0.45	-0.34			0.416	0.317	-13.70	-13.52
CV-24163	5/1/2026 2:33:25 PM	129.3	-0.37	-0.37			0.411	0.374	-12.81	-12.47
CV-24163	5/1/2026 2:32:24 PM	131.4	-2.55	-1.37			2.539	1.302	-12.74	-12.76
CV-24164	5/20/2026 2:08:15 PM	132.0	-0.14	-0.13			0.092	0.078	-6.78	-6.96
CV-24164	5/20/2026 2:06:56 PM	132.1	-0.65	-0.12			0.705	0.124	-6.75	-6.87
CV-24164	5/20/2026 11:14:31 AM	100.1	-0.99	-0.92			0.955	0.903	-6.39	-6.61
CV-24164	5/4/2026 10:23:58 AM	130.5	-0.38	-1.29			0.374	1.251	-9.01	-8.95
CV-24165	5/20/2026 11:18:42 AM	122.0	-1.44	-0.89			1.378	0.850	-5.52	-5.75
CV-24165	5/14/2026 11:24:07 AM	132.6	-0.35	-0.37	0.0	0.0	0.426	0.586	-2.22	
CV-24165	5/14/2026 11:22:03 AM	133.2	11.87	-0.25	0.0	0.0	-10.037	0.779	-2.07	
CV-24166	5/21/2026 9:08:04 AM	123.2	-4.53	-4.54			4.427	4.420	-5.21	-4.93
CV-24166	5/20/2026 11:21:55 AM	128.2	-0.25	-0.25			0.224	0.224	-6.06	-6.06
CV-24166	5/6/2026 10:54:07 AM	106.9	-5.34	-5.32	0.0	0.0	5.252	5.163	-6.56	
CV-24167	5/28/2026 8:45:13 AM	110.3	-3.01	-3.02			3.032	3.038	-7.54	-7.60
CV-24167	5/6/2026 9:59:13 AM	112.4	-1.44	-1.43	0.0	0.0	1.485	1.476	-7.35	
CV-24168	5/28/2026 8:59:25 AM	104.4	-1.66	-1.66			1.665	1.677	-7.37	-7.38
CV-24168	5/6/2026 10:55:15 AM		-0.71				0.693		-3.97	
CV-24169	5/20/2026 11:11:16 AM	100.1	-0.20	-0.18			0.173	0.156	-6.69	-6.69
CV-24169	5/4/2026 10:19:18 AM	115.0	-0.26	-0.26			0.270	0.270	-8.88	-8.59
CV-24170	5/21/2026 9:20:08 AM	127.0	-0.14	-0.14	24.1	24.1	0.145	0.145	-4.05	-4.21
CV-24170	5/6/2026 8:37:17 AM	125.6	-0.53	-0.54	12.2	13.7	0.037	0.046	-8.49	-8.45
CV-24170	5/1/2026 10:56:54 AM	126.9	-0.04	-0.04	11.9	12.5	0.035	0.039	-8.20	-8.14
CV-24171	5/21/2026 9:23:58 AM	127.2	-0.96	-0.94	16.0	14.5	0.339	0.279	0.46	0.36
CV-24171	5/6/2026 10:03:52 AM	123.6	-0.59	-0.69	15.5	17.4	0.290	0.369	-8.38	
CV-24172	5/21/2026 10:00:21 AM	121.6	-0.26	-0.27	9.7	9.7	0.257	0.259	-5.50	-5.92

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24172	5/4/2026 2:28:48 PM	116.3	-0.47	-0.45	0.0	0.0	-0.468	-0.465	-8.13	
CV-24173	5/21/2026 10:06:44 AM	115.4	-1.20	-1.19	21.8	21.4	1.110	1.066	0.67	0.67
CV-24173	5/6/2026 1:00:35 PM	113.8	-0.74	-0.83	14.9	16.4	0.513	0.620	-4.90	-5.46
CV-24174	5/21/2026 10:15:48 AM	111.1	-1.79	-1.79			1.741	1.753	-5.11	-5.08
CV-24174	5/11/2026 1:20:08 PM	111.9	-2.10	-2.10			2.103	2.090	-6.22	-6.17
CV-24175	5/21/2026 10:19:57 AM	121.4	-0.72	-0.70	13.0	13.3	0.459	0.482	-5.09	-4.91
CV-24175	5/5/2026 1:28:08 PM	120.6	-1.01	-1.00	30.7	31.3	0.607	0.628	-8.48	-8.48
CV-24175	5/5/2026 1:26:42 PM	121.3	-0.89	-0.89	32.8	32.6	0.694	0.683	-8.54	-7.89
CV-24175	5/5/2026 1:21:04 PM	121.8	-0.66	-0.75	28.4	30.5	0.519	0.599	-8.23	-8.22
CV-24175	5/5/2026 1:13:21 PM	122.7	-0.49	-0.55	25.2	28.1	1.739	2.167	-8.39	-8.38
CV-24176	5/20/2026 10:16:41 AM	130.7	-0.71	-0.71	8.2	8.2	0.230	0.228	-7.23	
CV-24176	5/20/2026 10:14:10 AM	130.8	-1.92	-0.82	15.8	8.5	0.796	0.230	-7.29	
CV-24176	5/8/2026 11:05:11 AM	137.8	-0.23	-0.22	16.4	16.4	0.979	0.978	-3.35	
CV-24176	5/8/2026 11:03:01 AM	136.7	0.92	-0.10	10.6	17.8	0.403	1.164	-3.26	
CV-24177	5/20/2026 8:06:52 AM	131.5	-0.57	-0.55			0.563	0.547	-8.42	-8.49
CV-24177	5/20/2026 7:56:33 AM	134.2	-2.20	-1.01			2.175	0.996	-9.06	-9.12
CV-24177	5/8/2026 11:20:50 AM	126.2	-1.17	-1.16	0.0	0.0	1.178	1.178	-4.57	
CV-24177	5/8/2026 11:19:26 AM	126.5	-2.80	-1.42	0.0	0.0	2.765	1.314	-4.47	
CV-24178	5/20/2026 12:02:57 PM	130.6	-0.63	-0.60	8.1	8.1	0.199	0.201	-6.74	
CV-24178	5/20/2026 12:01:45 PM	130.9	-1.01	-0.56	15.7	9.3	0.760	0.263	-6.71	
CV-24178	5/8/2026 10:58:25 AM	129.4	-0.11	-0.10	13.0	12.4	0.518	0.473	-3.42	
CV-24179	5/20/2026 9:55:47 AM	130.2	-1.03	-1.01	6.9	7.0	0.143	0.148	-7.95	
CV-24179	5/4/2026 1:09:48 PM	123.9	-1.03	-1.01	9.4	9.2	0.240	0.230	-8.67	-8.26
CV-24179	5/4/2026 1:08:00 PM	119.4	-1.00	-1.02	9.2	9.2	0.225	0.228	-8.59	-8.43
CV-24179	5/4/2026 1:03:56 PM	78.1	-0.61	-0.57	3.0	2.9	0.023	0.021	-8.43	-8.51
CV-24180	5/20/2026 10:03:08 AM	126.6	-3.18	-3.18	56.7	57.5	2.098	2.162	-8.02	
CV-24180	5/8/2026 10:53:15 AM	124.9	-1.60	-1.60	37.4	37.5	0.918	0.926	-3.70	
CV-24181	5/20/2026 12:05:54 PM	111.7	-0.49	-0.48	2.6	3.3	0.829	1.314	-7.28	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24181	5/4/2026 11:08:54 AM	107.4	-1.03	-0.93	4.4	3.7	2.280	1.554	-8.81	
CV-24182	5/22/2026 10:34:25 AM	112.1	-0.57	-0.52	0.0	0.0	0.499	0.494	-8.06	
CV-24182	5/4/2026 11:12:00 AM	99.0	-0.62	-0.62	0.0	0.0	0.568	0.570	-9.05	
CV-24183	5/20/2026 11:42:38 AM	106.9	-0.53	-0.53	0.0	0.0	0.513	0.512	-7.29	
CV-24183	5/4/2026 11:26:46 AM	84.8	-0.90	-0.90	0.0	0.0	0.856	0.861	-8.77	
CV-24184	5/28/2026 1:18:12 PM	135.1	-0.16	-0.11	2.5	3.1	0.133	0.203	-10.10	-10.11
CV-24184	5/28/2026 1:16:04 PM	139.3	-0.41	-0.17	10.0	4.5	2.217	0.438	-9.81	-10.06
CV-24184	5/20/2026 11:25:50 AM	133.8	-0.09	-0.08	4.1	4.1	0.403	0.400	-7.95	
CV-24184	5/20/2026 11:24:32 AM	132.1	-0.05	-0.05	4.2	4.2	0.420	0.421	-7.83	
CV-24184	5/20/2026 11:22:55 AM	125.5	0.07	-0.02	0.0	4.5	-0.017	0.474	-7.75	
CV-24184	5/4/2026 1:19:41 PM	133.2	-0.23	-0.23	6.6	6.6	0.928	0.924	-8.60	
CV-24184	5/4/2026 1:18:22 PM	133.9	-0.40	-0.21	11.5	6.3	2.789	0.843	-8.56	
CV-24185	5/20/2026 2:14:16 PM	128.3	-0.21	-0.20	19.3	19.3	1.133	1.133	-7.67	
CV-24185	5/20/2026 2:12:58 PM	128.0	0.05	-0.05	12.4	19.2	0.477	1.150	-7.55	
CV-24185	5/4/2026 1:26:49 PM	123.2	-0.21	-0.21	14.0	14.0	0.585	0.588	-8.57	
CV-24186	5/20/2026 2:18:02 PM	128.5	-0.29	-0.29	16.7	16.8	0.788	0.789	-7.36	
CV-24186	5/4/2026 2:56:41 PM	124.0	-0.87	-0.52	23.1	13.9	1.461	0.531	-8.51	
CV-24187	5/19/2026 10:36:55 AM	124.9	-0.39	-0.36	4.3	5.4	0.050	0.079	-6.56	-6.63
CV-24187	5/4/2026 10:28:37 AM	124.3	-0.20	-0.16	9.9	10.5	0.266	0.300	-7.99	-8.10
CV-24187	5/4/2026 10:27:50 AM	124.0	-0.10	-0.21	7.9	9.7	0.169	0.259	-8.17	-8.06
CV-24187	5/4/2026 10:19:29 AM	67.9	-0.32	-0.33	7.0	7.8	0.121	0.150	-7.99	-7.99
CV-24188	5/20/2026 12:45:56 PM	117.0	-2.84	-2.83	32.2	32.2	2.842	2.835	-7.57	-7.50
CV-24188	5/20/2026 8:59:37 AM	118.4	-3.18	-3.38	12.9	13.9	0.451	0.526	-8.73	-8.70
CV-24188	5/4/2026 9:36:30 AM	117.6	-3.10	-3.10	14.0	14.0	0.534	0.532	-9.27	-9.06
CV-24188	5/4/2026 9:34:45 AM	117.5	-2.61	-2.98	11.8	14.0	0.375	0.534	-8.82	-9.10
CV-24189	5/20/2026 8:49:58 AM	118.0	-1.88	-1.87	9.0	9.0	1.702	1.710	-8.75	-8.73
CV-24189	5/4/2026 9:28:20 AM	117.6	-1.79	-1.79	9.1	9.1	1.761	1.746	-9.10	-8.93
CV-24190	5/19/2026 10:21:44 AM	123.2	-3.56	-3.56	17.1	17.1	0.804	0.802	-6.76	-6.64
CV-24190	5/4/2026 10:10:47 AM	122.5	-4.08	-4.09	20.2	20.2	1.127	1.126	-8.32	-8.27
CV-24192	5/22/2026 10:15:13 AM	116.1	-6.39	-7.26	14.5	18.1	0.454	0.712	-7.81	
CV-24192	5/4/2026 10:02:40 AM	117.4	-6.38	-6.48	14.5	14.5	0.497	0.497	-8.93	-8.92
CV-24192	5/4/2026 10:01:48 AM	117.3	-6.12	-6.38	13.5	14.7	0.427	0.509	-8.63	-8.77
CV-24192	5/4/2026 9:58:01 AM	116.8	-5.60	-5.92	11.2	13.3	0.165	0.232	-8.95	-8.74
CV-24193	5/19/2026 2:15:47 PM	116.4	-5.05	-5.04	10.9	11.2	0.156	0.164	-5.48	-5.45

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24193	5/4/2026 9:13:38 AM	113.0	-7.77	-7.88	17.8	18.0	0.380	0.389	-8.74	
CV-24194	5/20/2026 12:10:04 PM	102.8	-4.95	-3.58	4.6	1.7	0.439	0.062	-7.11	
CV-24194	5/5/2026 1:47:55 PM	92.6	-3.78	-3.85	13.1	13.5	0.385	0.409	-5.71	-5.67
CV-24194	5/4/2026 9:33:10 AM	91.8	-4.34	-5.02	4.0	5.7	0.095	0.191	-8.88	
CV-24195	5/28/2026 1:01:56 PM	118.3	-0.91	-0.94	12.5	13.6	3.336	3.917	-9.42	-9.74
CV-24195	5/20/2026 12:23:03 PM	118.2	-0.55	-0.55	12.5	12.5	3.299	3.303	-7.13	
CV-24195	5/4/2026 9:46:22 AM	115.0	-0.97	-0.97	13.7	13.1	3.853	3.542	-8.73	
CV-24196	5/28/2026 12:55:54 PM	123.1	-1.57	-1.85			1.357	1.676	-9.64	-9.64
CV-24196	5/20/2026 11:31:51 AM	125.4	-1.36	-1.34	15.6	14.5	0.306	0.267	-7.75	
CV-24196	5/4/2026 11:32:25 AM	122.7	-1.96	-1.86	15.8	12.1	0.310	0.183	-8.52	
CV-24197	5/22/2026 10:52:22 AM	123.9	-1.11	-1.11	22.3	22.4	1.317	1.333	-5.23	
CV-24197	5/8/2026 11:18:02 AM	125.3	-0.62	-0.62	22.1	22.1	1.298	1.294	-4.95	
CV-24198	5/22/2026 10:50:58 AM	118.4	-0.22	-0.21	7.1	7.1	1.051	1.054	-5.47	
CV-24198	5/8/2026 10:50:53 AM	119.2	-0.14	-0.07	5.7	10.2	0.651	2.074	-5.14	
CV-24199	5/22/2026 10:41:08 AM	128.1	-0.78	-0.44	28.3	23.4	0.998	0.683	-5.36	
CV-24199	5/8/2026 10:55:45 AM	127.3	-0.43	-0.45	27.8	27.7	0.940	0.933	-5.81	
CV-24200	5/22/2026 9:57:47 AM	118.3	-0.74	-0.64	13.2	13.4	1.057	1.079	-6.06	
CV-24200	5/6/2026 2:43:38 PM	117.7	-0.31	-0.42	14.7	18.0	1.288	1.946	-11.64	
CV-24201	5/22/2026 10:05:48 AM	119.9	-1.00	-1.01	9.2	9.3	0.220	0.224		
CV-24201	5/6/2026 3:11:02 PM	121.5	-1.35	-1.24	12.4	10.8	0.407	0.309		
CV-24202	5/22/2026 10:29:59 AM	113.7	-3.37	-3.38	0.0	0.0	3.478	3.453	-11.87	
CV-24202	5/6/2026 3:17:39 PM	118.7	-4.97	-3.53	0.0	0.0	4.924	3.585	-11.80	
CV-24203	5/22/2026 9:36:46 AM	126.6	-1.38	-1.33	21.6	22.3	2.886	3.085		
CV-24203	5/11/2026 10:07:30 AM	125.9	-1.32	-1.31	20.2	20.2	2.548	2.551	-10.37	
CV-24204	5/22/2026 9:39:46 AM	126.5	-1.10	-1.09	13.1	12.7	0.391	0.366	-11.61	
CV-24204	5/11/2026 10:10:41 AM	125.9	-1.37	-0.91	14.0	11.9	0.447	0.325	-10.51	
CV-24205	5/22/2026 9:45:39 AM	122.6	-2.73	-2.71	27.2	28.6	0.880	0.970	-11.33	
CV-24205	5/6/2026 12:13:07 PM	121.1	-2.21	-2.20	22.4	22.5	0.605	0.611	-8.56	
CV-24206	5/22/2026 10:00:36 AM	92.2	-0.86	-0.87	0.0	0.0	0.904	0.914	-7.02	
CV-24206	5/6/2026 3:04:18 PM	86.5	-0.79	-0.79	0.0	0.0	0.564	0.564	-0.02	
CV-24207	5/21/2026 9:17:20 AM	130.6	-2.38	-2.39	10.1	9.9	0.135	0.132	-5.52	-5.76

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24207	5/21/2026 9:15:43 AM	130.7	-4.87	-2.81	16.3	8.9	0.358	0.106	-5.26	-5.08
CV-24207	5/4/2026 2:35:22 PM	126.3	-5.80	-5.79	21.6	20.5	0.589	0.526	-6.38	
CV-24208	5/4/2026 10:58:55 AM	125.4	-1.90	-1.49	27.2	22.7	1.745	1.209	-9.20	-9.17
CV-24209	5/4/2026 11:15:06 AM	124.7	-0.29	-0.31			0.302	0.310	-14.09	-14.30
CV-24210	5/5/2026 1:26:15 PM	101.2	-0.16	-0.35			0.146	0.350	-9.13	-9.17
CV-24210	5/4/2026 11:34:40 AM	119.8	-0.51	-0.48			0.553	0.484	-8.86	-8.83
CV-24211	5/7/2026 10:23:15 AM	118.1	-2.98	-2.91	0.0	0.0	3.039	2.730	-4.55	
CV-24212	5/11/2026 9:45:09 AM	136.8	-0.86	-0.87	0.0	0.0	0.896	0.897	-12.79	
CV-24212	5/11/2026 9:43:52 AM	135.1	-0.88	-0.88	0.0	0.0	0.893	0.893	-12.71	
CV-24213	5/1/2026 1:55:50 PM	111.8	-0.71	-0.92			0.711	0.945	-1.45	-1.47
CV-24213	5/1/2026 1:54:28 PM	121.8	-0.94	-1.01			0.910	0.988	-1.10	-1.16
CV-24213	5/1/2026 1:34:20 PM	109.6	1.46	1.48			0.000	0.000	0.06	1.14
CV-24213	5/1/2026 1:32:27 PM	109.4	1.44	1.45			0.000	0.000	-0.01	0.12
CV-24214	5/26/2026 12:44:02 PM	108.7	-3.43	-3.42			3.477	3.459	-4.39	-4.31
CV-24214	5/26/2026 12:41:30 PM	109.1	-3.61	-3.47			3.654	3.505	-4.08	-4.33
CV-24215	5/29/2026 9:58:57 AM	96.2	-0.25	-0.25	13.7	13.7	0.120	0.120	-7.83	
CV-24216	5/1/2026 1:59:49 PM	104.2	-3.65	-3.64			3.587	3.559	-8.90	-8.98
CV-24217	5/11/2026 1:45:32 PM	115.7	-0.16	-0.16	0.0	0.0	0.145	0.150		
CV-24217	5/11/2026 1:25:59 PM	110.5	-0.22	-0.21			0.205	0.192	-8.73	-8.68
CV-24217	5/11/2026 10:19:12 AM	121.5	-0.44	-0.32			0.431	0.316	-10.32	-10.42
CV-24218	5/8/2026 8:42:59 AM	124.1	-0.48	-0.52	0.0	0.0	0.555	0.571		
CV-24219	5/27/2026 2:44:32 PM	179.3	-4.70	-4.39			4.685	4.386	-5.96	-5.96
CV-24219	5/19/2026 1:10:00 PM									
CV-24219	5/19/2026 1:07:47 PM	182.4	-2.55	-2.46			2.583	2.396	-4.09	-4.07
CV-24219	5/19/2026 1:07:21 PM	182.1	6.06	-2.11			0.000	2.130	-4.70	-3.83
CV-24219	5/11/2026 9:27:37 AM	188.3	-6.96	-6.50			6.916	6.475	-13.85	-13.07

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-24219	5/11/2026 9:26:02 AM	188.2	1.54	-5.97			0.000	5.945	-13.82	-13.34
CV-24219	5/4/2026 8:40:00 AM									
CV-24219	5/4/2026 8:40:00 AM									
CV-24219	5/4/2026 8:37:52 AM	187.1	-1.73	-1.64			1.908	1.772	-11.22	-11.52
CV-24220	5/1/2026 2:28:38 PM	131.1	-0.57	-0.56			0.547	0.534	-13.06	-12.81
CV-24220	5/1/2026 2:26:20 PM	133.5	-5.99	-2.52			5.986	2.502	-12.46	-12.78
CV-24221	5/7/2026 10:47:53 AM	91.5	-0.02	-0.03	0.0	0.0	-0.026	-0.026	-3.82	
CV-24222	5/11/2026 9:28:59 AM	122.8	-10.04	-10.78	20.8	23.4	1.119	1.423	-12.00	
CV-24223	5/11/2026 9:35:14 AM	129.6	-4.99	-3.40	0.0	0.0	5.000	3.346		
CV-24224	5/1/2026 2:36:53 PM	116.0	-6.80	-5.00			6.882	4.991	-13.15	-11.52
CV-24225	5/4/2026 10:44:54 AM	105.0	-0.36	-0.35			0.346	0.351	-13.59	-13.84
CV-24226	5/7/2026 10:18:42 AM	112.6	-4.57	-4.58	0.0	3.4	-0.054	0.007	-4.51	
CV-24227	5/8/2026 11:27:46 AM	115.3	-1.95	-2.05	19.0	23.2	0.764	1.145		
CV-24231	5/5/2026 2:20:38 PM	123.6	-1.09	-0.70	36.4	24.7	0.803	0.368	-9.44	
CV-24236	5/7/2026 9:58:34 AM	103.0	-0.32	-0.47	8.1	10.8	0.375	0.666	-3.40	
CV-24237	5/7/2026 10:03:50 AM	111.8	-0.12	-0.21	12.8	15.9	0.343	0.526	-3.09	
CV-24243	5/8/2026 10:05:46 AM	116.4	-0.03	-0.12	32.7	50.3	0.244	0.579	-4.54	
CV-24244	5/7/2026 11:23:42 AM	112.4	-0.42	-0.51	0.0	13.8	-0.030	0.044	-3.27	
CV-24245	5/7/2026 2:21:55 PM	115.1	-1.51	-0.50	24.7	13.7	1.319	0.404	-4.99	
CV-24246	5/7/2026 2:17:13 PM	116.5	-0.10	-0.07	3.1	3.0	0.025	0.023	-1.05	
CV-24253	5/7/2026 2:35:07 PM	116.0	-0.12	-0.22	27.6	30.8	1.621	2.018	-7.27	
CV-25	5/13/2026 1:44:59 PM	93.3	-7.02	-6.95	4.8	5.3	0.029	0.035	-8.94	-8.83
CV-2501	5/4/2026 9:55:50 AM	120.3	-0.84	-0.83	0.0	0.0	-0.035	-0.042	-11.08	
CV-2502	5/4/2026 10:08:04 AM	119.1	-0.69	-0.68	15.3	16.3	0.056	0.063	-10.41	
CV-2503	5/6/2026 2:52:46 PM	125.8	-0.41	-0.52	50.2	38.8	0.607	0.363	-10.74	
CV-2504	5/5/2026 2:41:25 PM	125.9	-1.02	-0.87	142.0	120.9	4.865	3.530	-9.25	
CV-2505	5/5/2026 2:55:39 PM	117.5	-3.03	-3.04	35.9	35.8	0.769	0.766	-10.96	
CV-2506	5/5/2026 3:55:25 PM	119.8	-1.88	-1.88	52.0	51.9	1.624	1.621	-10.08	
CV-2507	5/8/2026 1:37:11 PM	122.8	-3.77	-3.89	58.9	58.4	4.489	4.403	-11.33	-11.59
CV-2507	5/5/2026 3:50:55 PM	120.1	-2.97	-3.34	54.5	59.2	3.486	4.103	-10.12	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2508	5/5/2026 3:46:09 PM	118.6	-6.15	-6.47	74.9	82.7	1.317	1.607	-10.13	
CV-2509	5/8/2026 1:42:52 PM	115.2	-7.11	-7.40	56.6	60.7	2.048	2.363	-13.04	-12.96
CV-2509	5/5/2026 3:31:32 PM	113.5	-5.20	-5.41	54.4	59.3	1.749	2.081	-8.99	
CV-2510	5/8/2026 1:46:50 PM	113.9	-3.81	-4.15	29.1	31.3	2.283	2.653	-12.36	-12.55
CV-2510	5/5/2026 2:25:18 PM	113.5	-2.48	-2.75	19.4	22.6	1.014	1.372	-9.32	-8.83
CV-25100D	5/18/2026 10:35:31 AM	121.0	-1.88	-1.87			1.881	1.885	-4.03	-4.37
CV-25100D	5/12/2026 10:22:21 AM	146.4	-1.69	-1.55			1.721	1.599	-10.57	-10.60
CV-25100D	5/12/2026 10:20:00 AM									
CV-25100D	5/8/2026 9:54:19 AM	178.2	-0.07	-0.04	0.0	0.0	0.107	0.098	-3.41	
CV-25100D	5/8/2026 9:52:49 AM	177.5	-0.05	-0.03	0.0	0.0	0.107	0.035	-3.51	
CV-25100S	5/26/2026 10:48:42 AM	161.0	-7.04	-7.04			7.116	7.116	-11.52	-11.52
CV-25100S	5/26/2026 10:48:08 AM	160.7	-10.08	-7.27			10.084	7.236	-11.19	-11.47
CV-25100S	5/18/2026 10:40:00 AM									
CV-25100S	5/18/2026 10:33:27 AM	157.2	-3.42	-3.47			3.376	3.533	-4.42	-4.41
CV-25100S	5/12/2026 10:25:18 AM	164.4	-8.85	-9.07			8.818	8.985	-10.53	-10.55
CV-25100S	5/12/2026 10:25:00 AM									
CV-25100S	5/8/2026 10:01:43 AM	181.9	-0.43	-0.28	0.0	0.0	0.677	1.154	-3.20	
CV-25100S	5/8/2026 10:00:14 AM	182.3	-1.16	-0.95	0.0	0.0	1.307	1.194	-3.29	
CV-25100S	5/4/2026 2:45:00 PM									
CV-25100S	5/4/2026 2:45:00 PM									
CV-25100S	5/4/2026 2:38:27 PM	182.8	-6.31	-6.71			6.165	6.596	-10.21	-10.05
CV-25101D	5/22/2026 10:43:56 AM	80.5	-8.07	-7.89			7.928	7.721	-8.05	-7.92
CV-25101D	5/12/2026 1:33:31 PM	83.3	-10.20	-9.13			10.328	9.173	-10.30	-9.38
CV-25101S	5/22/2026 10:46:24 AM	112.0	-1.50	-1.48			1.458	1.442	-7.23	-7.13
CV-25101S	5/12/2026 1:23:51 PM		-3.23				3.181		-10.20	
CV-25102_	5/20/2026 2:05:47 PM	100.0	-9.04	-9.04			8.735	8.876	-9.42	-9.42
CV-25102_	5/8/2026 10:11:54 AM	83.1	-4.06	-3.97	0.0	0.0	3.871	3.864	-3.84	
CV-25102_	5/8/2026 10:09:29 AM	83.5	-4.02	-3.93	0.0	0.0	3.957	3.944	-3.62	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-25103	5/22/2026 11:13:05 AM	127.2	-2.07	-2.02			2.013	1.938	-5.83	-8.08
CV-25103	5/20/2026 1:53:20 PM	106.5	-0.01	-0.12			0.000	0.083	-8.79	-8.66
CV-25103	5/12/2026 10:47:21 AM	124.9	-0.62	-0.61			0.598	0.597	-11.88	-11.73
CV-25103	5/12/2026 10:45:57 AM	127.6	-3.74	-0.66			3.671	0.657	-12.20	-11.84
CV-25104D	5/20/2026 2:32:23 PM	94.7	-5.28	-5.66	7.0	7.2	5.255	5.589	-5.52	-5.68
CV-25104D	5/13/2026 9:49:44 AM	94.6	-9.27	-8.86			9.549	9.102	-9.40	-8.91
CV-25104S	5/20/2026 2:35:06 PM	104.6	-5.20	-4.98			5.120	4.965	-5.44	-5.60
CV-25104S	5/13/2026 9:54:31 AM	121.4	-9.95	-9.37			10.253	9.646	-10.34	-9.89
CV-25105D	5/22/2026 10:19:59 AM		-4.93				4.642		-5.29	
CV-25105D	5/8/2026 8:27:56 AM	74.1	-0.64	-0.69	0.0	0.0	0.838	0.728	-1.19	
CV-25105S	5/20/2026 1:43:43 PM	128.5	-1.63	-1.66			1.529	1.515	-3.43	-3.67
CV-25105S	5/8/2026 8:30:20 AM	129.3	-0.39	-0.36	0.0	0.0	0.676	0.393	-0.82	
CV-25106D	5/26/2026 9:05:29 AM	60.2	-1.16	-1.15			1.153	1.134	-7.55	-7.57
CV-25106D	5/26/2026 9:03:18 AM	60.0	-4.03	-1.06			4.001	1.043	-8.42	-8.14
CV-25106D	5/12/2026 2:19:11 PM	87.0	-3.62	-3.65			3.500	3.498	-8.82	-8.79
CV-25106D	5/12/2026 2:18:07 PM	87.3	-4.23	-4.27			4.097	4.151	-10.44	-10.29
CV-25106S	5/26/2026 9:12:30 AM	66.4	-4.62	-4.62			4.580	4.577	-7.75	-7.51
CV-25106S	5/26/2026 9:11:40 AM	66.7	-7.39	-4.62			7.439	4.585	-7.90	-7.38
CV-25106S	5/12/2026 2:25:06 PM	87.8	-7.99	-8.06			8.093	8.159	-8.66	-8.92
CV-25106S	5/12/2026 2:23:49 PM	84.6	-7.93	-8.03			8.084	8.186	-8.79	-8.74
CV-25107D	5/1/2026 2:47:38 PM	89.4	-11.51	-11.52	0.0	0.0			-11.43	
CV-25107S	5/1/2026 2:50:28 PM	100.3	-0.49	-0.49	0.0	0.0	0.518	0.520	-11.48	
CV-2511	5/5/2026 2:33:06 PM	124.5	-0.72	-0.61	23.5	23.3	0.133	0.131	-7.27	
CV-2512	5/5/2026 2:28:36 PM	122.8	-0.63	-0.62	28.3	28.1	0.192	0.189	-7.67	
CV-2513	5/7/2026 3:05:57 PM	119.1	-0.65	-0.74	32.6	35.8	2.292	2.761	-8.74	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2514	5/8/2026 2:58:55 PM	122.2	-1.51	-1.61	38.0	40.2	1.707	1.910	-4.15	
CV-2515	5/7/2026 9:16:53 AM	115.0	-0.30	-0.33	9.0	14.3	0.092	0.232	-3.72	
CV-2516	5/11/2026 11:15:10 AM	126.3	-1.75	-1.97	11.4	14.9	0.808	1.385	-7.13	
CV-2517	5/7/2026 9:40:45 AM	111.7	-0.63	-0.63	0.0	0.0	-0.038	-0.037	-3.95	
CV-2518	5/7/2026 10:00:08 AM	104.9	-0.01	-0.08	0.0	0.0	-0.044	-0.042	-3.78	
CV-2518	5/7/2026 9:57:35 AM	102.0	1.64	-0.03	0.0	0.0	-0.059	-0.035	-3.50	
CV-2519	5/1/2026 1:11:22 PM	125.2	-0.68	-0.86	20.4	25.1	1.136	1.730	-11.17	-10.96
CV-2520	5/1/2026 1:26:15 PM	141.0	-0.13	-0.13	5.3	5.3	0.078	0.079	-10.84	-10.84
CV-2520	5/1/2026 1:25:06 PM	141.0	0.42	-0.09	4.1	5.5	0.046	0.086	-10.84	-10.84
CV-2521	5/26/2026 12:24:46 PM	109.8	-1.07	-1.06			1.075	1.061	-12.77	-12.92
CV-2522	5/5/2026 12:53:32 PM	129.6	-0.05	-0.13	4.8	2.5	0.054	0.014	-11.53	-11.44
CV-2522	5/1/2026 10:59:06 AM	134.7	-0.15	-0.12	5.0	5.5	0.069	0.084	-11.46	-11.51
CV-2522	5/1/2026 10:57:27 AM	134.8	0.59	-0.16	4.7	6.8	0.061	0.130	-11.50	-11.41
CV-2523	5/4/2026 2:07:42 PM	124.6	-2.25	-2.37	22.3	22.9	3.217	3.413	-12.09	-11.42
CV-2524	5/1/2026 10:45:46 AM	140.6	-0.19	-0.18	8.6	8.3	0.210	0.193	-11.58	-11.57
CV-2524	5/1/2026 10:44:23 AM	141.0	0.22	-0.14	8.5	7.0	0.203	0.139	-11.67	-11.61
CV-2525	5/4/2026 2:13:54 PM	120.2	-0.23	-0.23	23.3	23.4	1.268	1.269	-11.18	-11.17
CV-2525	5/4/2026 2:13:24 PM	120.0	0.25	-0.11	8.9	22.9	0.182	1.214	-11.44	-10.62
CV-2526	5/4/2026 2:18:08 PM	120.0	-0.03	-0.15	19.5	21.0	0.094	0.108	-11.59	-11.46
CV-2527	5/15/2026 11:27:42 AM	126.6	-3.71	-3.66	0.0	0.0	-3.662	-3.649	-13.67	
CV-2528	5/11/2026 8:25:29 AM	108.8	-2.81	-2.82	12.1	14.6	0.085	0.122	-13.34	
CV-2529	5/8/2026 12:47:59 PM	88.1	-6.53	-6.78	2.7	3.0	0.781	0.924	-6.87	-6.71
CV-2530	5/12/2026 7:58:10 AM	124.1	-1.38	-1.36	0.0	0.0	1.373	1.371	-12.17	
CV-2531	5/8/2026 12:35:03 PM	118.6	-0.14	-0.13			0.107	0.093	-8.56	-8.42

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2531	5/8/2026 12:34:13 PM	117.4	45.23	-0.13			0.000	0.074	-8.24	-8.35
CV-2532	5/12/2026 7:54:00 AM	73.6	-13.68	-13.64	0.0	0.0			-13.52	
CV-2533	5/12/2026 7:48:32 AM	128.4	-11.82	-11.81	20.5	20.7	1.147	1.173	-13.28	
CV-2534	5/11/2026 2:17:18 PM	123.0	-3.20	-3.97	40.7	44.5	2.169	2.604	-16.17	-16.36
CV-2535	5/5/2026 2:52:23 PM	107.5	-0.37	-0.37	7.2	7.2	1.053	1.053	-8.37	
CV-2536	5/14/2026 10:27:30 AM	89.2	-9.77	-3.58	3.0	2.7	0.906	0.760	-10.58	
CV-2537	5/6/2026 12:17:48 PM	109.4	-1.71	-0.64	0.0	0.0	1.663	0.561	-6.21	
CV-2538	5/6/2026 12:25:17 PM	118.6	-0.55	-0.54	11.2	10.9	2.500	2.366	-7.02	
CV-2539	5/20/2026 9:49:24 AM	122.3	-3.41	-3.15	0.0	0.0	3.410	3.065	-7.24	
CV-2539	5/4/2026 9:17:28 AM	116.5	-1.88	-1.88	0.0	0.0	1.896	1.894	-8.37	
CV-2540	5/20/2026 2:18:42 PM	129.7	-1.92	-2.09			1.659	2.068	-6.97	-6.42
CV-2540	5/20/2026 2:15:08 PM	128.9	-1.83	-1.93			1.813	1.913	-6.87	-7.00
CV-2540	5/14/2026 1:17:10 PM	129.2	-0.97	-1.09			0.952	1.029	-6.70	-6.67
CV-2540	5/14/2026 1:13:24 PM	129.8	-6.29	-0.92			6.286	0.904	-6.35	-6.58
CV-2541	5/19/2026 9:38:49 AM	130.6	-2.43	-2.43			2.413	2.413	-6.33	-6.50
CV-2541	5/19/2026 9:36:57 AM	130.8	-3.08	-2.47			3.055	2.423	-6.36	-6.35
CV-2541	5/1/2026 11:15:47 AM	85.1	0.06	0.06			0.000	0.000	0.65	0.65
CV-2541	5/1/2026 11:15:26 AM	82.5	0.06	0.06			0.000	0.000	0.66	0.65
CV-2542	5/21/2026 2:04:28 PM	92.0	-0.23	-0.25			0.197	0.147	-3.07	-2.89
CV-2542	5/4/2026 1:56:22 PM	72.7	-3.26	-2.51			3.106	2.296	-8.29	-8.49
CV-2543-PLR	5/20/2026 1:43:43 PM	101.3	-5.07	-3.98			5.041	3.962	-7.22	-6.84
CV-2543-PLR	5/4/2026 9:50:49 AM	82.0	-9.93	-8.29			10.180	8.654	-9.85	-10.37
CV-2544	5/21/2026 1:52:17 PM	94.3	-0.22	-0.23			0.140	0.137	-3.69	-3.53
CV-2544	5/21/2026 1:51:00 PM	94.3	0.39	-0.12			0.000	0.069	-3.39	-3.40
CV-2544	5/6/2026 11:06:39 AM	77.1	-0.37	-0.45			0.351	0.432	-6.35	-7.34
CV-2545	5/22/2026 12:19:27 PM	127.4	-0.39	-0.40	0.0	0.0	0.399	0.394	-3.83	
CV-2545	5/22/2026 12:15:46 PM	127.5	-0.96	-0.53	0.0	0.0	0.854	0.488	-3.39	
CV-2545	5/6/2026 2:44:01 PM	115.2	-0.07	-0.07			0.055	0.048	-2.98	-3.01

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2545	5/6/2026 2:43:10 PM	115.3	0.17	-0.01			0.000	0.000	-2.90	-2.94
CV-2546	5/22/2026 12:25:12 PM	129.8	-0.52	-0.50	0.0	0.0	0.483	0.477	-3.71	
CV-2546	5/22/2026 12:24:00 PM	130.1	-0.87	-0.59	0.0	0.0	0.879	0.511	-3.57	
CV-2546	5/6/2026 2:35:53 PM	121.1	-0.36	-0.36			0.341	0.359	-2.47	-2.65
CV-2547	5/28/2026 12:23:14 PM	95.7	-1.39	-1.53			1.381	1.513	-14.29	-13.09
CV-2547	5/22/2026 12:03:11 PM	97.0	-1.05	-1.13	0.0	0.0	0.932	1.091	-11.83	
CV-2547	5/6/2026 10:25:52 AM	102.5	-1.12	-0.92	0.0	0.0	1.074	0.777	-12.92	
CV-2548	5/13/2026 9:58:56 AM	127.8	-0.79	-0.84	9.9	11.2	2.108	2.699	-9.91	-9.81
CV-2548	5/1/2026 10:34:59 AM	127.9	-0.88	-0.78	0.0	0.0	-2.413	-2.210		
CV-2549	5/28/2026 12:13:13 PM	110.2	-1.60	-1.62	34.8	37.4	3.268	3.782	-15.17	-12.91
CV-2549	5/13/2026 9:51:28 AM	111.4	-0.89	-0.93	25.9	32.0	1.790	2.748	-11.33	-12.41
CV-2549	5/6/2026 12:31:15 PM	111.3	-0.25	-0.32	26.2	28.9	1.832	2.237	-12.30	-11.48
CV-2549	5/1/2026 10:30:41 AM	110.7	-1.04	-0.92	0.0	0.0	-2.740	-1.298		
CV-2550	5/27/2026 1:19:05 PM	168.9	-6.90	-6.70			6.973	6.774	-7.16	-7.17
CV-2550	5/21/2026 10:06:57 AM	183.7	-1.39	-2.69			1.503	2.106	-5.87	-8.40
CV-2550	5/21/2026 10:04:40 AM	182.9	1.27	-2.02			0.000	2.043	-7.38	-8.67
CV-2550	5/11/2026 9:52:55 AM	180.6	-2.36	-2.41			2.348	2.403	-13.58	-13.66
CV-2550	5/4/2026 9:00:00 AM									
CV-2550	5/4/2026 8:59:59 AM	185.0	-5.13	-5.53			4.927	5.545	-13.66	-14.54
CV-2551	5/1/2026 2:40:59 PM	135.0	-0.78	-0.77	0.0	0.0	0.742	0.747	-11.81	
CV-2551	5/1/2026 2:39:32 PM	135.5	-0.90	-0.91	0.0	0.0	0.963	0.856	-11.84	
CV-2552	5/19/2026 1:50:38 PM	114.0	-5.61	-5.73			5.816	5.895	-8.50	-8.54
CV-2552	5/19/2026 1:49:24 PM	112.0	0.99	-2.00			0.000	2.003	-8.75	-8.66
CV-2552	5/11/2026 9:58:44 AM	176.5	-0.28	-0.27			0.296	0.262	-13.69	-12.71
CV-2552	5/4/2026 9:36:17 AM	173.8	-0.72	-0.71			0.744	0.751	0.11	0.08
CV-2552	5/4/2026 9:35:00 AM									
CV-2552	5/4/2026 9:35:00 AM									
CV-2553	5/20/2026 1:24:17 PM	114.2	-0.28	-0.28			0.276	0.277	-6.84	-6.69

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2553	5/4/2026 9:36:18 AM	88.1	-3.77	-2.95			3.689	2.876	0.30	0.33
CV-2554	5/28/2026 1:40:06 PM	149.2	-4.27	-4.20			4.267	4.190	0.00	0.00
CV-2554	5/20/2026 2:11:24 PM	148.6	-3.24	-3.25			3.202	3.211	-3.80	-3.79
CV-2554	5/14/2026 11:13:27 AM	158.7	-4.55	-4.67			4.543	4.646	0.00	0.00
CV-2554	5/14/2026 11:12:34 AM	157.5	-10.10	-4.42			10.104	4.388	-0.34	-0.01
CV-2554	5/14/2026 11:10:00 AM									
CV-2554	5/4/2026 1:13:35 PM	167.6	-7.05	-7.01			7.105	7.105	10.47	10.56
CV-2554	5/4/2026 1:12:59 PM	168.5	-9.63	-6.34			9.822	6.489	-8.61	4.94
CV-2554	5/4/2026 1:10:00 PM									
CV-2554	5/4/2026 1:10:00 PM									
CV-2555	5/22/2026 11:41:33 AM	93.6	-6.23	-6.04	0.0	0.0	6.285	6.130	-6.83	
CV-2555	5/22/2026 11:39:04 AM	86.7	-5.88	-5.62	0.0	0.0	6.006	5.623	-6.48	
CV-2555	5/8/2026 1:12:17 PM	83.2	-1.66	-1.01			1.607	0.987	-4.74	-4.48
CV-2556	5/27/2026 2:02:24 PM	176.8	-7.61	-7.45			7.627	7.488	0.25	0.25
CV-2556	5/19/2026 1:45:00 PM									
CV-2556	5/19/2026 1:38:41 PM	179.5	-10.11	-9.43			10.267	9.552	0.00	0.00
CV-2556	5/11/2026 10:20:58 AM	179.2	-12.62	-13.42			12.753	13.579	0.04	0.02
CV-2556	5/4/2026 9:15:00 AM									
CV-2556	5/4/2026 9:15:00 AM									
CV-2556	5/4/2026 9:13:52 AM	175.8	-14.12	-14.12			14.419	14.430	0.01	0.01
CV-2557	5/20/2026 1:47:47 PM	126.4	-1.45	-1.54			1.436	1.436	-3.75	-4.32
CV-2557	5/8/2026 8:36:19 AM	121.7	-0.36	-0.35	0.0	0.0	0.471	0.431	-1.39	
CV-2558	5/27/2026 2:34:42 PM	179.5	7.37	7.37			0.000	0.000	0.25	0.25
CV-2558	5/27/2026 2:33:21 PM	179.4	1.98	2.48			0.000	0.000	0.25	0.25
CV-2558	5/19/2026 1:15:50 PM	179.5	7.93	9.09			0.000	0.000	0.00	0.00
CV-2558	5/19/2026 1:15:00 PM									
CV-2558	5/14/2026 10:19:35 AM	184.0	1.32	1.81			0.000	0.000	0.34	0.34

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2558	5/14/2026 10:18:44 AM	183.6	-1.14	3.49			0.769	0.000	0.34	0.34
CV-2558	5/14/2026 10:15:00 AM									
CV-2558	5/4/2026 8:47:30 AM	187.0	3.58	3.70			0.000	0.000	1.06	0.00
CV-2558	5/4/2026 8:45:31 AM	187.6	3.99	12.53			0.000	0.000	0.70	11.42
CV-2558	5/4/2026 8:45:00 AM									
CV-2559	5/8/2026 8:53:26 AM	125.6	-0.04	-0.02	0.0	0.0	-0.038	0.184	-1.14	
CV-2559	5/8/2026 8:49:36 AM	123.8	0.04	-0.02	0.0	0.0	0.063	0.218	-1.29	
CV-2560	5/22/2026 10:39:45 AM	111.8	-2.41	-1.38			2.357	1.353	-8.96	-9.13
CV-2560	5/12/2026 1:09:28 PM	124.4	-6.11	-3.21			6.179	3.074	-8.83	-10.13
CV-2561	5/11/2026 2:38:47 PM	128.9	-0.74	-0.85	0.0	0.0	0.720	0.901	-4.85	
CV-2562	5/11/2026 2:10:20 PM	121.0	-3.33	-0.80	0.0	0.0	-3.199	-1.003	-5.04	
CV-2563	5/28/2026 11:37:21 AM	113.5	-0.15	-0.11	2.3	0.7	0.111	0.011	-0.17	-0.26
CV-2563	5/28/2026 11:36:57 AM	112.4	0.34	-0.08	1.4	1.7	0.043	0.057	-0.31	-0.38
CV-2563	5/15/2026 11:37:25 AM	111.3	-0.13	-0.12	0.0	0.0	-0.002	-0.006	-1.14	
CV-2563	5/15/2026 11:35:25 AM	110.7	0.18	-0.07	2.7	0.0	0.895	-0.209	-0.08	
CV-2564	5/21/2026 9:30:21 AM	129.3	-0.06	-0.05			0.070	0.054	-1.31	-1.48
CV-2564	5/21/2026 9:29:15 AM	129.4	0.14	-0.03			0.000	0.028	-1.60	-1.19
CV-2564	5/1/2026 11:06:39 AM	128.1	-0.14	-0.15			0.141	0.154	-6.15	-6.04
CV-2565	5/20/2026 9:51:50 AM	113.6	-3.93	-3.92	0.0	0.0	3.926	3.924	-6.86	
CV-2565	5/4/2026 9:20:17 AM	111.1	-4.23	-4.21	0.0	0.0	4.199	4.197	-7.69	
CV-2566	5/20/2026 9:46:01 AM	108.3	-1.67	-1.67	0.0	0.0	1.740	1.736	-8.44	
CV-2566	5/4/2026 9:24:42 AM	100.3	-2.33	-2.07	0.0	0.0	2.368	2.075	-8.80	
CV-2567	5/20/2026 12:20:18 PM	108.4	-1.65	-1.32	0.0	0.0	1.613	1.198	-7.36	
CV-2567	5/4/2026 9:43:22 AM	99.5	-2.39	-2.38	0.0	0.0	2.354	2.350	-8.74	
CV-2568	5/20/2026 11:39:12 AM	109.2	-0.42	-0.41	0.0	0.0	0.367	0.365	-7.78	
CV-2568	5/4/2026 11:23:44 AM	91.4	-0.66	-0.65	0.0	0.0	0.546	0.546	-8.69	
CV-2569	5/20/2026 11:29:23 AM	110.3	-0.30	-0.30	0.0	0.0	0.335	0.333	-7.93	
CV-2569	5/4/2026 11:29:19 AM	92.7	-0.50	-0.50	0.0	0.0	0.496	0.496	-8.77	
CV-2570	5/20/2026 11:15:26 AM	112.6	-0.76	-0.73	0.0	0.0	0.636	0.636	-7.88	
CV-2570	5/4/2026 11:34:49 AM	98.5	-0.96	-0.95	0.0	0.0	0.875	0.874	-9.10	
CV-2571	5/7/2026 1:00:36 PM	96.5	-1.42	-1.46	32.4	32.1	0.599	0.587	-4.59	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
CV-2572	5/7/2026 1:32:16 PM	121.9	-0.07	-0.06	0.0	0.0	-0.006	-0.006	-0.87	
CV-48R	5/28/2026 11:41:20 AM	115.8	0.41	0.47	4.8	1.3	0.147	0.011	0.39	0.67
CV-48R	5/28/2026 11:40:34 AM	115.9	0.29	0.26	4.6	3.1	0.135	0.060	0.33	0.29
CV-48R	5/15/2026 11:44:42 AM	116.1	-0.15	-0.14	0.0	0.0	-0.130	-0.131	-0.10	
CV-48R	5/6/2026 10:23:03 AM	120.0	-0.82	-0.92	3.4	2.8	0.073	0.051	-0.96	-0.64
CV-52D	5/1/2026 1:17:29 PM	94.5	-3.26	-2.86	0.6	2.9	0.002	0.050	-10.84	-10.84
CV-55R	5/27/2026 3:07:28 PM	142.1	-2.73	-2.73	12.0	12.2	0.964	0.994	-6.68	-7.31
CV-55R	5/21/2026 9:11:16 AM	134.1	-3.92	-3.90	7.3	7.0	0.352	0.327	-10.65	-10.36
CV-55R	5/21/2026 9:10:09 AM	118.0	3.03	-3.56	1.1	8.9	0.008	0.503	-11.24	-10.14
CV-55R	5/11/2026 11:02:29 AM	153.5	-3.01	-3.01	6.3	6.4	0.268	0.281	-11.12	-11.17
CV-55R	5/4/2026 8:05:00 AM									
CV-55R	5/4/2026 8:05:00 AM									
CV-55R	5/4/2026 8:04:21 AM	149.2	-7.05	-7.05	4.8	4.4	0.157	0.129	-13.02	-13.32
CV-56D	5/7/2026 11:25:28 AM	92.3	-2.18	-2.17	0.0	0.0	-0.055	-0.052	-4.76	
CV-56D	5/7/2026 11:22:51 AM	92.4	-4.91	-4.82	0.0	0.0	-0.053	-0.047	-4.76	
CV-56S	5/7/2026 11:32:33 AM	89.0	-0.59	-0.51	0.0	0.0	-0.065	-0.058	-4.78	
CV-56S	5/7/2026 11:29:21 AM	90.4	-0.92	-0.82	0.0	0.0	-0.076	-0.063	-4.51	
CV-57R	5/1/2026 2:21:40 PM	93.4	-0.05	-0.10	1.2	1.1	0.030	0.027	-12.51	-12.49
CV-79R	5/1/2026 2:41:23 PM	125.3	-0.83	-0.83	6.9	6.8	0.111	0.109	-13.27	-12.96
CV-94	5/11/2026 3:29:38 PM	114.0	-8.74	-8.75	2.3	2.2	0.032	0.029	-11.57	
CV-94	5/11/2026 3:28:29 PM	110.8	2.14	-9.33	0.0	1.9	-0.011	0.022	-12.07	
CV-95	5/1/2026 2:19:24 PM	105.0	-0.10	-0.11	2.6	2.3	0.143	0.109	-12.64	-12.54
CV-95	5/1/2026 2:18:38 PM	99.1	0.05	-0.07	1.1	1.8	0.024	0.064	-7.32	-7.34
CV-99	5/26/2026 1:51:48 PM	77.4	-3.43	-2.93	0.7	1.3	0.009	0.035	-3.44	-2.72
CV-99	5/4/2026 7:45:00 AM									
D-02	5/28/2026 3:29:22 PM	85.0	-10.41	-10.47	4.9	7.9	0.030	0.078	-10.09	-10.34

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
D-03	5/28/2026 3:32:52 PM	87.1	-3.36	-4.87	8.6	6.5	0.061	0.035	-3.10	-4.83
D-04	5/28/2026 3:41:09 PM	77.8	-14.97	-14.91	4.5	6.3	0.025	0.049	-14.64	-14.53
D-09	5/7/2026 1:18:48 PM	111.7	-3.08	-3.31	9.8	11.5	0.569	0.785	-3.67	
D-10	5/7/2026 1:08:35 PM	107.5	-4.73	-4.64	0.0	0.0	-0.024	-0.012	-4.49	
FP-001	5/8/2026 9:19:36 AM	81.1	-0.01	-0.02	1.3	1.3	0.165	0.179	-4.83	
FP-002	5/8/2026 9:28:39 AM	78.7	-0.03	-0.02	1.6	0.9	0.272	0.089	-3.77	
FP-003	5/8/2026 9:39:47 AM	79.4	-0.01	-0.01	6.6	6.6	0.865	0.865	-3.48	
FP-003	5/8/2026 9:36:36 AM	79.6	-0.03	-0.03	1.7	1.8	0.059	0.062	-3.15	
FP-005	5/15/2026 2:55:43 PM	82.4	-0.08	-0.08	13.5	14.5	3.780	4.343	-0.08	
FP-006	5/15/2026 2:51:55 PM	81.5	-1.37	-1.02	1.7	1.0	0.072	0.027	-4.06	
FP-008	5/15/2026 3:10:45 PM	87.8	-0.76	-0.19	4.1	2.7	0.414	0.182	-3.06	
FP-008	5/6/2026 9:22:39 AM	79.7	0.20	-0.02	0.3	0.2	0.020	0.007	0.77	0.62
FP-009	5/13/2026 10:12:04 AM	94.3	-0.15	-0.11	4.0	3.4	0.324	0.233	-6.98	-5.41
FP-010	5/13/2026 10:03:04 AM	105.2	-0.08	-0.06	8.6	8.3	1.537	1.406	-8.89	-7.82
FP-011	5/13/2026 10:00:11 AM	74.5	-1.72	-1.12	5.8	4.4	0.646	0.381	-8.15	-8.36
FP-012	5/19/2026 8:39:03 AM	82.4	-0.10	-0.11	0.9	0.8	0.015	0.013	-6.15	-6.30
FP-012	5/1/2026 11:49:02 AM	83.8	-0.10	-0.12	1.0	0.7	0.020	0.009	-7.02	-7.22
FP-013	5/19/2026 9:34:22 AM	76.5	-0.13	-0.18	6.1	9.8	0.722	1.876	-5.96	-5.82
FP-013	5/13/2026 9:55:27 AM	75.1	-0.17	-0.14	6.6	6.8	0.836	0.897	-7.27	-7.29
FP-014	5/13/2026 2:03:06 PM	91.0	-0.08	-0.07	2.0	2.3	0.420	0.530	-2.40	-3.03
FP-015	5/15/2026 2:35:16 PM	79.7	-0.25	-0.29	1.1	1.1	0.027	0.027	-3.55	
FP-015	5/14/2026 2:08:49 PM	127.4	-2.20	-2.07	2.2	0.2	0.556	0.004	-2.58	-2.69
FP-015	5/13/2026 2:12:26 PM	176.4	-2.19	-2.20	2.4	2.2	0.135	0.108	-2.28	-2.33
FP-016	5/15/2026 2:43:10 PM	84.3	-1.81	-1.27	11.0	2.0	2.904	0.093	-3.97	
FP-016	5/13/2026 2:15:57 PM	89.7	-1.28	-1.25	2.1	2.0	1.129	1.002	-2.17	-2.02
FP-017	5/8/2026 12:57:34 PM	88.7	-0.09	-0.11	2.6	2.3	0.138	0.107	0.02	0.29
FP-018	5/8/2026 12:40:54 PM	87.6	-0.25	-0.26	0.3	0.5	0.002	0.004	-5.90	-5.73
FP-019	5/12/2026 1:48:27 PM	79.4	-0.12	-0.13	1.4	1.2	0.041	0.026	-3.05	-4.57
FP-020	5/12/2026 1:57:00 PM	83.2	-1.09	-1.05			0.054	0.000	-4.30	-4.23
FP-021	5/13/2026 10:41:14 AM	90.9	-6.85	-6.93	7.5	7.7	1.138	1.213	-7.46	-7.61

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
FP-021	5/12/2026 1:59:43 PM	95.7	-4.27	-3.67			0.000	0.000	-5.51	-5.40
FP-022	5/13/2026 10:32:37 AM	90.5	-3.57	-4.07	2.5	3.6	0.130	0.258	-7.96	-8.10
FP-023	5/13/2026 1:46:18 PM	84.7	-1.24	-1.17	1.7	1.9	0.059	0.069	-3.99	-4.40
FP-024	5/20/2026 2:16:33 PM	96.9	-0.22	-0.19	2.4	1.7	0.113	0.056	-7.09	-7.20
FP-025	5/20/2026 2:19:20 PM	84.5	-2.99	-2.62	1.6	0.6	0.051	0.008	-7.58	-7.49
FP-026	5/29/2026 4:20:14 PM	77.8	-7.05	-7.05	19.2	19.2	7.419	7.464	0.20	0.11
FP-027	5/29/2026 4:24:24 PM	88.1	-8.01	-8.01	20.1	20.1	8.355	8.366	0.03	0.02
FP-028	5/28/2026 11:39:27 AM	80.7	-0.78	-0.59	14.5	2.7	3.991	0.140	-8.46	
FP-029	5/28/2026 11:31:57 AM	74.2	-0.07	-0.08	0.0	0.0	-0.348	-0.338	-0.11	
FP-030	5/12/2026 1:41:15 PM	76.4	-0.31	-0.36	13.8	14.5	3.736	4.133	-6.65	-7.41
FP-031	5/29/2026 9:22:16 AM	76.4	-1.86	-1.81	9.1	9.5	1.629	1.770	-7.91	-8.09
FP-031	5/12/2026 1:37:06 PM	77.7	-1.63	-1.49	2.6	2.6	1.628	1.641	-5.82	-6.08
FP-032	5/12/2026 1:28:30 PM	77.8	-4.17	-3.93	2.7	3.4	0.746	1.211	-6.50	-6.71
FP-033	5/12/2026 1:23:05 PM	86.9	-2.64	-1.10	5.0	1.8	0.493	0.061	-6.37	-6.46
FP-034	5/12/2026 1:19:44 PM	84.6	-0.14	-0.13	6.1	5.8	0.729	0.673	-7.56	-6.34
FP-035	5/12/2026 1:16:01 PM	76.7	-3.36	-2.54	6.0	4.9	0.713	0.478	-6.74	-6.54
FP-036	5/1/2026 11:36:11 AM	77.8	-1.03	-1.00	3.1	3.2	2.468	2.506	-6.86	-6.82
FP-037	5/19/2026 10:33:25 AM	84.8	-0.15	-0.14	0.2	0.2	0.005	0.004	-5.65	-5.62
FP-037	5/1/2026 11:38:38 AM	83.4	-0.12	-0.11			0.022	0.023	-7.74	-7.73
FP-038	5/14/2026 2:24:47 PM	86.7	-0.73	-0.21	25.8	22.7	0.753	0.745	-4.85	
FP-039	5/14/2026 2:15:09 PM	90.1	-0.10	-0.14	16.8	15.9	5.474	4.864	-4.74	
FP-040	5/29/2026 2:30:36 PM	104.5	-0.29	-0.30	23.1	26.6	4.048	5.386	-4.67	
FP-041	5/13/2026 1:16:55 PM	88.3	-0.02	-0.11	9.7	9.7	1.949	1.935	-6.01	
FP-042	5/20/2026 10:11:54 AM	88.7	-0.02	-0.03	9.7	11.2	1.903	2.497	-2.81	-2.52
FP-043	5/13/2026 1:22:06 PM	90.0	-0.20	-0.21	8.6	8.6	1.591	1.579	-6.21	
FP-044	5/13/2026 1:25:38 PM	91.7	-0.32	-0.17	18.2	8.4	2.089	0.442	-5.69	
FP-045	5/11/2026 1:04:40 PM	122.1	-0.20	-0.22	10.9	10.8	2.516	2.490	-5.55	-5.58
FP-046	5/15/2026 3:02:41 PM	81.9	-0.25	-0.25	7.1	7.1	1.253	1.250	-4.12	
FP-047	5/29/2026 11:36:35 AM	86.1	-0.11	-0.04	0.0	0.0	-0.029	-0.017	-0.06	
FP-050	5/6/2026 2:53:31 PM	88.3	-1.86	-1.49	15.3	13.7	1.426	1.137	-11.04	-10.41
FP-051	5/6/2026 2:48:25 PM	92.3	-4.47	-3.58	6.5	7.7	0.052	0.074	-10.60	-11.17
FP-052	5/22/2026 2:09:54 PM	89.0	-0.37	-0.25	8.9	4.1	8.135	1.706	-8.36	
FP-052	5/4/2026 2:20:50 PM	80.4	-0.24	-0.30	41.0	41.8	10.194	10.597	-4.06	-4.16
FP-053	5/21/2026 2:19:03 PM	106.2	-0.11	-0.54	6.0	1.0	0.740	0.019	-2.34	-1.81
FP-053	5/4/2026 2:08:41 PM	85.3	-0.40	-0.38	10.3	10.6	2.118	2.241	-7.93	-8.06
FP-054	5/1/2026 11:30:37 AM	86.1	-0.74	-0.74	29.1	29.2	1.763	1.766	-12.41	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
FP-055	5/20/2026 2:00:54 PM	105.9	-0.02	-0.11	11.0	17.1	2.495	6.107	-6.89	-6.90
FP-055	5/4/2026 10:03:30 AM	79.3	-0.12	-0.12	2.9	2.9	0.167	0.167	-9.14	-9.03
FP-056	5/4/2026 9:15:22 AM	74.3	-0.28	-0.27	4.0	4.0	3.898	3.925	-9.54	-9.46
FP-057	5/4/2026 9:17:47 AM	105.9	-0.98	-0.94	6.8	6.7	0.967	0.922	0.25	0.29
FP-057	5/1/2026 11:34:44 AM	79.6	-0.58	-0.58	23.7	23.7	3.162	3.157	-12.43	
FP-058	5/29/2026 3:51:49 PM	85.7	-0.68	-0.67	31.2	31.8	2.021	2.104	-13.04	
FP-059	5/1/2026 2:35:49 PM	92.8	-0.36	-0.36	12.9	12.9	0.953	0.954	-12.83	
FP-060	5/1/2026 2:53:38 PM	91.0	-0.46	-0.46	16.1	16.1	1.491	1.488	-12.50	
FP-061	5/15/2026 2:38:19 PM	148.5	-0.66	-0.67	0.0	0.0	-0.310	-0.490	-4.59	
FP-061	5/14/2026 2:22:44 PM	158.2	-0.51	-0.48	3.9	4.1	0.335	0.379	-3.89	-3.32
FP-061	5/14/2026 2:19:38 PM	158.9	-2.22	-0.41	3.5	1.5	1.476	0.273	-3.41	-3.52
H-01 (EXP-01)	5/26/2026 8:45:19 AM	61.8	-4.15	-4.15			4.087	4.087	-7.84	-7.79
H-01 (EXP-01)	5/12/2026 1:49:58 PM	97.1	-3.72	-3.71			3.728	3.724	-7.74	-7.65
H-02 (EXP-02)	5/26/2026 8:27:48 AM	83.7	-1.22	-1.23			1.197	1.212	-7.60	-7.63
H-02 (EXP-02)	5/12/2026 1:55:38 PM	110.3	-0.42	-0.42			0.362	0.343	-7.26	-7.42
H-03 (EXP-03)	5/26/2026 8:31:53 AM	112.6	-6.85	-6.88			6.954	6.971	-7.50	-7.55
H-03 (EXP-03)	5/12/2026 2:02:02 PM	119.0	-7.34	-7.33			7.332	7.340	-8.07	-8.07
H-04 (EXP-04)	5/26/2026 8:34:46 AM	124.1	-0.80	-0.80			0.786	0.784	-7.63	-7.65
H-04 (EXP-04)	5/14/2026 10:16:02 AM	131.1	-0.16	-0.15			0.167	0.152	-7.86	-7.76
H-04 (EXP-04)	5/14/2026 10:14:56 AM	131.2	-0.14	-0.14			0.142	0.143	-8.01	-8.03
H-04 (EXP-04)	5/14/2026 10:13:50 AM	131.5	1.83	-0.15			0.000	0.157	-7.87	-7.86
H-08 (EXP-08)	5/26/2026 8:55:13 AM	119.3	-4.97	-5.00			4.978	4.958	-6.70	-6.75
H-08 (EXP-08)	5/11/2026 9:46:50 AM	88.4	-4.09	-4.08			4.120	4.107	-5.61	-5.49
H-10 (EXP-10)	5/26/2026 9:06:45 AM	130.8	-1.09	-0.67			1.071	0.655	-6.60	-6.61
H-10 (EXP-10)	5/11/2026 9:40:46 AM	130.8	-0.17	-0.17			0.166	0.165	-5.41	-5.41
H-10 (EXP-10)	5/11/2026 9:40:06 AM	130.9	1.20	-0.01			0.000	0.013	-5.25	-5.32
H-101W	5/13/2026 8:32:50 AM	65.3	-4.22	-4.18	16.8	16.8	0.333	0.333	-8.30	-8.32
H-101W	5/13/2026 8:24:13 AM	64.3	-8.12	-7.62	22.5	22.0	0.603	0.574	-8.32	-8.31
H-102A	5/13/2026 8:17:41 AM	66.5	-8.25	-8.37	10.3	10.3	0.622	0.628	-8.33	-8.38
H-1401W	5/13/2026 8:48:53 AM	70.2	-8.15	-8.21	11.0	11.3	0.715	0.748	-8.41	-8.20
H-1404C	5/20/2026 11:55:54 AM	129.1	-0.66	-0.66	9.2	8.8	1.852	1.695	-7.16	
H-1404C	5/4/2026 11:20:18 AM	124.8	-0.87	-0.86	9.8	9.8	2.047	2.050	-8.56	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
H-1405C	5/20/2026 8:39:42 AM	94.2	-0.68	-0.65	2.9	2.4	0.050	0.035	-0.99	-1.17
H-1405C	5/1/2026 10:13:01 AM	90.1	-2.46	-1.56	7.6	6.6	0.351	0.266	-2.28	-3.10
H-1406W	5/20/2026 9:30:46 AM	94.2	-7.35	-0.96	13.8	5.5	1.170	0.184	-7.47	-7.47
H-1406W	5/1/2026 10:30:28 AM	80.8	-8.43	-8.32	2.6	2.8	0.041	0.049	-8.65	-8.74
H-1408CR	5/6/2026 2:48:15 PM	125.8	-0.11	-0.11	1.7	3.5	0.331	1.387	-11.69	
H-1408CR	5/6/2026 2:46:51 PM	122.4	0.14	-0.04	0.0	6.0	-0.095	4.011	-11.69	
H-1408E	5/20/2026 2:13:20 PM	111.8	-0.01	-0.03	1.7	1.5	0.062	0.046	-2.73	-3.06
H-1408E	5/4/2026 2:44:00 PM	107.3	-0.10	-0.09	4.1	3.6	0.352	0.272	-5.56	
H-1408E	5/4/2026 2:42:19 PM	105.4	0.02	-0.10	2.5	3.3	0.122	0.222	-6.11	
H-1408W	5/7/2026 10:26:18 AM	103.9	-0.02	-0.11	0.0	0.0	-0.269	-0.010	-3.06	
H-1409N	5/20/2026 2:26:47 PM	116.4	-0.95	-1.06	2.4	2.7	0.124	0.150	-6.38	
H-1409N	5/4/2026 2:02:48 PM	112.0	-1.74	-2.90	2.0	3.8	0.084	0.294	-8.06	
H-1410S	5/6/2026 12:22:14 PM	87.5	-7.42	-7.39	1.2	1.4	0.008	0.011	-8.07	
H-1563N	5/22/2026 2:12:17 PM	115.9	-2.58	-2.76	5.6	6.7	0.202	0.289	-3.88	-4.39
H-1563N	5/11/2026 12:47:48 PM	114.1	-0.59	-1.23	13.1	13.8	0.222	0.245	-1.72	-2.53
H-1563S	5/20/2026 8:43:45 AM	89.4	-0.32	-0.32	0.5	0.5	0.024	0.029	-8.23	-8.15
H-1563S	5/1/2026 10:06:27 AM	93.9	-0.30	-0.29	0.3	0.3	0.008	0.010	-7.20	-6.82
H-1565E	5/21/2026 10:26:51 AM	116.5	-0.42	-0.33	3.1	1.0	0.060	0.007	-2.39	-1.92
H-1565E	5/6/2026 10:50:58 AM	114.9	-0.85	-0.92	2.5	4.8	0.040	0.145	-4.46	-6.57
H-1568N	5/21/2026 10:57:34 AM	128.0	0.88	-0.28	4.2	11.9	0.372	3.078	-2.69	-2.51
H-1568N	5/20/2026 2:05:18 PM	113.9	-1.13	-1.15	5.2	5.4	0.567	0.625	-3.67	-3.60
H-1568N	5/4/2026 2:46:50 PM	108.0	-1.25	-1.35	5.7	5.9	0.654	0.701	-4.35	
H-1571S	5/4/2026 11:05:46 AM	82.8	-0.68	-0.57	6.1	5.2	0.081	0.059	-14.29	-14.18
H-1572N	5/1/2026 2:47:42 PM	109.8	-0.02	-0.08	0.6	2.0	0.008	0.086	-9.57	-9.23
H-1572S	5/4/2026 10:51:40 AM	96.5	-3.07	-2.07	15.4	13.2	0.532	0.390	-13.67	-14.28
H-1574N	5/20/2026 10:38:18 AM	104.7	-0.06	-0.06	9.6	10.0	0.115	0.125	-4.92	-4.96
H-1574N	5/13/2026 9:52:29 AM	140.3	-0.15	-0.04	6.4	4.9	0.056	0.033	-1.24	-1.32

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
H-1574N	5/12/2026 8:59:40 AM	98.6	-0.11	-0.11	7.1	9.9	0.059	0.117	-5.56	
H-1753N	5/26/2026 9:00:32 AM	66.7	-0.10	-0.08	1.5	1.2	0.004	0.003	-6.49	-6.41
H-1753N	5/12/2026 1:45:21 PM	84.5	-0.58	-0.59	5.0	4.1	0.054	0.037	-7.12	-8.21
H-1753S	5/22/2026 2:02:07 PM	112.2	-3.95	-3.80	3.4	3.4	0.252	0.246	-4.34	-4.17
H-1753S	5/11/2026 12:40:59 PM	107.0	-2.14	-1.05	4.3	6.6	0.389	0.910	-2.46	-1.93
H-1756S	5/19/2026 1:28:24 PM	128.7	-0.05	-0.04	4.8	4.2	0.031	0.024	-2.74	-2.73
H-1756S	5/19/2026 1:25:39 PM	130.5	-0.19	-0.01	9.0	19.6	0.108	0.506	-2.56	-2.36
H-1756S	5/13/2026 12:47:50 PM	127.8	-0.49	-0.50	8.1	8.2	0.168	0.174	-5.44	
H-1757S	5/20/2026 8:35:55 AM	81.0	-0.54	-0.53	5.6	5.1	0.068	0.057	-7.64	-7.77
H-1757S	5/1/2026 10:14:46 AM	83.0	-0.14	-0.15	1.4	2.2	0.005	0.011	-7.51	-6.79
H-1760S	5/21/2026 10:10:39 AM	115.9	-1.37	-1.36	3.3	3.8	0.070	0.090	-5.03	-5.25
H-1760S	5/11/2026 1:37:59 PM	119.1	-1.27	-1.31	3.3	3.7	0.069	0.089	-6.02	-6.17
H-1762N	5/20/2026 1:57:03 PM	108.6	-0.08	-0.06	4.6	4.5	2.260	2.147	-5.63	-5.41
H-1762N	5/20/2026 1:55:17 PM	108.6	0.01	-0.09	4.6	4.6	2.230	2.303	-5.47	-5.57
H-1762N	5/4/2026 2:38:51 PM	100.5	-0.07	-0.07	5.0	5.1	2.507	2.668	-6.15	
H-1763N	5/6/2026 10:36:14 AM	104.8	-0.12	-0.12	6.6	6.6	0.316	0.317	-13.92	
H-1763N	5/6/2026 10:34:51 AM	100.8	0.01	-0.09	1.5	5.8	0.016	0.251	-13.79	
H-1763S	5/4/2026 11:26:50 AM	102.5	-0.41	-0.25	5.4	4.6	0.036	0.027	-9.15	-9.00
H-1764N	5/28/2026 12:39:39 PM	117.8	-4.20	-4.76	3.1	2.6	0.208	0.149	-14.48	-15.76
H-1764N	5/5/2026 1:16:30 PM	116.7	-3.77	-3.99	1.1	2.1	0.025	0.092	-13.78	-13.67
H-1764N	5/4/2026 11:45:03 AM	117.5	-4.13	-4.47	3.6	4.8	0.278	0.488	-13.62	-13.42
H-1764S	5/4/2026 11:08:05 AM	94.2	-1.75	-1.70	5.7	5.5	0.197	0.183	-14.09	-14.15
H-1767N	5/11/2026 9:51:22 AM	102.4	-1.89	-1.62	19.9	18.5	0.934	0.801	-13.53	
H-1769N	5/19/2026 8:53:05 AM	105.1	-0.08	-0.03	21.0	20.5	1.175	1.115	-7.01	-6.78
H-1769N	5/1/2026 2:30:15 PM	110.2	-0.45	-0.49	36.7	38.8	3.638	4.054	-7.49	-8.25
H-1770N	5/19/2026 9:18:49 AM	98.4	-0.44	-0.37	14.2	6.5	4.118	0.866	-6.73	-5.92
H-1770N	5/4/2026 8:50:00 AM									
H-1770N	5/1/2026 2:42:44 PM	100.2	-0.68	-0.60	9.9	9.2	2.030	1.743	-6.48	-6.39
H-1770S	5/19/2026 12:50:46 PM	102.4	-0.18	-0.18	1.1	0.9	0.026	0.017	-4.80	-4.79
H-1770S	5/1/2026 10:34:30 AM	101.9	-0.39	-0.33	1.6	1.2	0.051	0.032	-6.81	-6.73

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
H-1771A	5/11/2026 2:21:58 PM	113.2	-0.48	-0.48	9.3	9.3	0.530	0.527	-4.99	
H-1771B	5/13/2026 11:22:20 AM	130.5	-3.08	-2.96	4.0	3.3	0.343	0.234	-11.09	-9.94
H-1771B	5/13/2026 11:19:01 AM	132.6	-4.92	-4.05	4.4	2.4	0.423	0.129	-11.13	-10.87
H-1771B	5/11/2026 1:05:25 PM	104.5	0.02	0.07	1.6	0.7	0.052	0.010	0.89	0.67
H-1771B	5/11/2026 1:04:43 PM	104.4	0.02	0.04	1.0	0.9	0.020	0.018	0.44	0.67
H-1774N	5/19/2026 9:58:15 AM	116.0	-0.11	-0.07	8.4	8.9	1.484	1.677	-5.71	-5.81
H-1774N	5/12/2026 10:34:14 AM	115.8	-0.82	-0.72	24.8	32.9	0.907	1.596	-6.40	
H-1801S	5/11/2026 11:15:54 AM	101.8	-0.20	-0.20	0.0	0.0	-0.105	-0.100	-12.22	
H-1802S	5/1/2026 2:44:17 PM	114.0	-0.02	-0.42	7.2	5.4	0.066	0.037	-11.24	-11.22
H-1803N	5/26/2026 9:42:57 AM	196.0	-1.69	-0.89	39.7	29.7	2.347	1.312	0.34	0.31
H-1803N	5/18/2026 10:00:00 AM									
H-1803N	5/18/2026 9:58:45 AM	196.4	-0.27	-0.11	21.8	17.5	0.700	0.450	0.34	0.34
H-1803N	5/12/2026 9:08:34 AM	196.4	-2.79	-2.79	43.4	43.4	2.806	2.806	0.68	0.68
H-1803N	5/12/2026 9:05:00 AM									
H-1803N	5/5/2026 9:07:24 AM	196.0	-2.95	-2.52	46.7	43.8	3.260	2.858	0.00	0.00
H-1803N	5/5/2026 9:00:00 AM									
H-1803N	5/5/2026 9:00:00 AM									
H-1804B	5/1/2026 10:39:08 AM	108.5	-10.92	-11.22	12.6	16.3	0.955	1.618	-12.91	
H-1804N	5/8/2026 9:11:50 AM	90.8	-1.00	-0.99	0.0	0.0	-0.063	-0.021	-1.42	
H-1804S	5/4/2026 11:47:34 AM	99.8	-4.58	-5.79	8.4	8.7	0.435	0.473	-10.88	-11.32
H-1805A	5/1/2026 11:19:57 AM	98.3	-2.19	-2.07	3.6	3.0	1.420	0.996	-13.55	
H-1805B	5/4/2026 11:52:01 AM	71.2	-0.43	-0.43	2.4	2.5	0.116	0.116	-13.66	-13.57
H-1805S	5/4/2026 11:39:55 AM	127.9	-4.88	-4.89	17.6	18.0	0.736	0.772	-13.69	-13.74
H-1806A	5/1/2026 11:08:54 AM	98.9	-0.31	-0.32	1.7	1.7	0.057	0.058	-12.14	
H-1806B	5/1/2026 2:52:26 PM	115.7	-0.03	-0.08	0.5	2.8	0.006	0.162	-12.22	-12.04
H-1806N	5/11/2026 11:37:48 AM	129.4	-3.18	-2.60	11.6	6.4	0.177	0.055	-9.02	
H-1806S	5/4/2026 10:39:51 AM	116.7	-4.73	-3.93	14.5	10.8	0.490	0.273	-13.81	-13.81
H-1807A	5/4/2026 1:18:09 PM	103.6	-8.49	-8.66	26.2	28.1	0.887	1.019	-10.90	-13.04
H-1807N	5/29/2026 10:10:34 AM	80.6	-0.45	-0.43	0.0	0.0	-0.029	-0.028	-5.31	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
H-1807S	5/7/2026 11:08:13 AM	91.7	-0.13	-0.13	0.0	0.0	-0.064	-0.064	-4.72	
H-1952S	5/21/2026 2:14:50 PM	126.1	-0.04	-0.04	7.0	6.9	1.058	1.013	-2.73	-2.80
H-1952S	5/21/2026 2:13:14 PM	125.9	0.26	-0.04	5.4	6.6	0.626	0.944	-2.46	-2.81
H-1952S	5/4/2026 2:04:02 PM	122.3	-0.34	-0.58	6.4	7.2	0.861	1.112	-8.23	-8.35
H-1955C	5/1/2026 11:26:41 AM	82.6	-0.48	-0.49	7.9	7.9	1.209	1.211	-13.30	
H-1955N	5/8/2026 9:07:44 AM	88.6	-0.03	-0.03	0.0	0.0	-0.025	-0.009	-1.38	
H-1956B	5/1/2026 10:44:44 AM	119.3	-1.89	-1.29	13.1	5.8	0.420	0.081	-12.25	
H-1956N	5/11/2026 11:40:47 AM	107.3	-0.23	-0.33	3.2	4.5	0.061	0.118	-6.20	
H-1956S	5/1/2026 2:39:31 PM	111.8	-11.04	-10.52	3.7	3.5	1.535	1.321	-12.99	-12.56
H-1957B	5/6/2026 2:10:22 PM	102.8	-0.15	-0.10	19.3	18.9	2.304	2.215	-9.70	-9.77
H-1957B	5/1/2026 2:13:12 PM	102.7	-0.12	-0.11	14.1	14.2	1.234	1.249	-12.58	-12.58
H-1957N	5/11/2026 11:33:03 AM	121.8	-2.42	-2.12	6.1	0.0	0.231	-0.019	-7.94	
H-1957S	5/11/2026 11:18:08 AM	114.9	-0.46	-0.41	0.0	0.0	-0.083	-0.076	-11.49	
H-1958C	5/4/2026 1:20:33 PM	123.0	-0.88	-0.91	4.8	5.9	0.149	0.225	-12.87	-12.96
H-1958N	5/28/2026 1:56:37 PM	90.7	-0.01	-0.01	33.9	43.8	1.428	2.380	-4.34	-4.19
H-1958S	5/7/2026 11:03:31 AM	122.7	-0.41	-0.39	6.7	7.0	0.283	0.295	-4.69	
H-1962N	5/19/2026 9:28:05 AM	122.8	-0.43	-0.31			0.042	0.033	-5.73	-5.99
H-1962N	5/19/2026 9:26:00 AM	124.9	-0.64	-0.58			0.058	0.043	-5.81	-5.84
H-1962N	5/1/2026 2:46:00 PM	126.9	-0.02	-0.03			0.000	0.000	-6.42	-6.76
H-1963N	5/19/2026 8:46:36 AM	140.2	-0.07	-0.11	4.4	4.9	0.053	0.068	-6.73	-6.93
H-1963N	5/19/2026 8:44:46 AM	139.9	-0.24	-0.22	5.5	4.5	0.086	0.056	-6.87	-7.30
H-1963N	5/1/2026 12:06:22 PM	141.6	-0.31	-0.30	8.2	8.2	0.190	0.189	-8.11	-7.82
H-1963N	5/1/2026 12:04:32 PM	141.3	0.49	-0.23	2.6	9.3	0.019	0.246	-7.82	-7.86
H-1966N	5/19/2026 10:06:37 AM	105.4	-0.29	-0.30	3.7	3.6	1.442	1.416	-4.18	-4.11
H-1966N	5/12/2026 10:42:28 AM	105.7	-0.29	-0.27	4.0	3.9	1.684	1.681	-4.50	
H-1967E	5/7/2026 1:04:55 PM	105.5	-2.08	-2.10	2.9	2.8	0.009	0.009	-3.70	
H-1967W	5/7/2026 9:49:11 AM	94.4	-0.15	-0.15	48.2	48.2	2.554	2.555	-3.45	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
H-1967W	5/7/2026 9:47:56 AM	94.1	1.20	-0.07	32.9	49.0	1.182	2.624	-2.55	
H-2050E	5/14/2026 9:38:59 AM	86.5	-10.17	-10.30	0.0	0.0	-0.023	-0.009	-10.26	
H-2050W	5/5/2026 3:39:36 PM	100.5	-0.84	-0.73	5.7	6.8	0.639	0.911	-4.87	
H-2051W	5/7/2026 9:44:33 AM	85.8	-0.15	-1.35	0.0	3.2	-0.013	0.011	-3.43	
H-2053E	5/7/2026 1:13:15 PM	119.4	-2.16	-1.48	31.4	26.0	1.177	0.806	-4.01	
H-2053W	5/13/2026 8:39:25 AM	91.6	-7.55	-7.81	20.7	22.1	0.534	0.612	-7.88	-7.91
H-2055E	5/22/2026 10:10:19 AM	107.7	-1.34	-1.32	2.9	2.6	2.279	1.801	-11.77	
H-2055E	5/6/2026 3:07:33 PM	107.6	-1.27	-1.25	2.7	2.7	1.911	1.909	-11.91	
H-2056B	5/8/2026 3:07:26 PM	91.2	-1.33	-1.34	0.8	1.0	0.072	0.095	-4.44	
H-2056W	5/7/2026 9:41:29 AM	95.7	-0.05	-0.51	54.4	54.1	3.235	3.205	-3.64	
H-2057E	5/7/2026 1:10:46 PM	125.6	-1.32	-1.78	6.1	6.3	0.749	0.798	-4.35	
H-2057W	5/28/2026 8:44:04 AM	82.1	-0.24	-0.66			0.319	0.690	-7.05	-7.02
H-2057W	5/13/2026 8:09:16 AM	79.4	-4.45	-4.48			4.417	4.465	-7.78	-7.92
H-2057W	5/13/2026 8:05:12 AM	80.1	-7.28	-6.22			7.360	6.348	-7.97	-7.83
H-2058E	5/7/2026 1:22:33 PM	110.1	-1.20	-1.20	26.6	23.3	0.817	0.626	-2.15	
H-2058W	5/7/2026 9:34:28 AM	94.7	-0.16	-0.15	24.0	23.9	0.633	0.628	-3.74	
H-2058W	5/7/2026 9:33:03 AM	94.1	0.36	-0.18	11.6	24.8	0.145	0.666	-3.33	
H-2059E	5/6/2026 12:36:07 PM	117.7	-9.28	-9.30	5.8	5.2	0.684	0.541	-10.03	
H-2059W	5/7/2026 10:12:44 AM	126.7	-1.02	-1.02	38.5	38.5	1.827	1.824	-3.03	
H-2161E	5/6/2026 12:32:34 PM	124.0	-2.77	-3.35	39.0	42.2	1.829	2.152	-9.76	
H-2161W	5/7/2026 10:08:23 AM	107.3	-3.37	-3.28	0.0	3.5	-0.001	0.013	-3.33	
H-2163C	5/22/2026 10:05:49 AM	90.0	-0.49	-0.48	0.8	0.9	0.072	0.078	-9.13	
H-2163C	5/4/2026 10:05:22 AM	83.7	-0.34	-0.34	0.4	0.4	0.019	0.020	-10.46	
H-2163W	5/7/2026 10:22:23 AM	125.5	-0.06	-0.06	17.8	17.8	2.214	2.210	-3.09	
H-2164E	5/22/2026 10:41:07 AM	125.4	-0.04	-0.07	3.8	4.0	0.105	0.115	-5.30	
H-2164E	5/6/2026 3:22:38 PM	127.2	-0.14	-0.13	7.5	7.5	0.426	0.428	-12.25	
H-2164E	5/6/2026 3:21:24 PM	126.2	0.01	-0.06	0.0	5.7	-0.022	0.240	-11.72	
H-2165E	5/4/2026 10:55:10 AM	109.5	-1.70	-1.54	12.3	13.9	0.955	1.216	-8.79	-8.82
H-2165W	5/20/2026 9:46:57 AM	120.0	-0.68	-0.55	4.5	3.9	0.127	0.096	-7.28	-7.30
H-2165W	5/12/2026 7:45:00 AM									
H-2165W	5/12/2026 7:45:00 AM									

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
H-2165W	5/1/2026 10:16:24 AM	117.5	-0.09	-0.05	2.2	2.5	0.032	0.040	-8.60	-8.63
H-2166E	5/4/2026 1:12:58 PM	101.5	-0.36	-0.31	1.6	0.7	0.016	0.003	-2.12	-2.10
H-2168C	5/1/2026 10:48:38 AM	85.4	-12.70	-12.64			0.010	0.016	-12.62	
H-2168E	5/28/2026 12:08:16 PM	120.1	-0.92	-1.00	5.8	6.0	0.218	0.233	-14.91	-15.02
H-2168E	5/6/2026 2:36:05 PM	120.0	-0.16	-0.17	4.0	4.1	0.099	0.105	-13.97	-14.71
H-2168E	5/5/2026 10:39:26 AM	71.5	-0.24	-0.24	6.4	6.5	0.237	0.244	0.13	0.14
H-2168E	5/5/2026 10:37:49 AM	70.2	-0.23	-0.22	6.2	6.1	0.226	0.216	0.08	0.12
H-2168E	5/1/2026 2:15:28 PM	120.2	-0.11	-0.11	4.2	4.2	0.113	0.113	-12.59	-12.59
H-2169C	5/4/2026 11:55:39 AM	104.8	-2.56	-2.69	17.7	18.8	0.401	0.453	-12.16	-12.25
H-2169E	5/1/2026 2:05:32 PM	114.9	-0.12	-0.12	10.9	11.1	0.153	0.160	-12.60	-12.71
H-2170N	5/4/2026 2:04:41 PM	117.2	-0.65	-0.66	14.1	15.2	1.266	1.472	-10.39	-10.55
H-2170S	5/11/2026 8:29:12 AM	102.0	-2.15	-2.03	1.9	3.9	0.016	0.088	-13.92	
H-2171A	5/14/2026 8:58:08 AM	94.8	-0.70	-0.70	0.7	0.8	0.054	0.058	-1.60	-1.59
H-2171A	5/14/2026 8:54:11 AM	94.4	-0.80	-0.69	2.7	0.7	0.778	0.049	-1.26	-1.59
H-2171A	5/13/2026 10:13:53 AM	94.5	-0.88	-0.88	2.4	2.4	0.035	0.035	-1.98	-2.03
H-2171A	5/13/2026 10:08:18 AM	96.6	-1.07	-0.92	4.2	1.3	0.108	0.011	-1.19	-1.62
H-2171A	5/7/2026 9:32:22 AM	93.3	-0.76	-0.76	0.0	0.0	-0.016	-0.033	-0.72	
H-2171B	5/13/2026 2:00:46 PM	119.7	-1.16	-1.16	16.3	16.0	1.690	1.619	-2.44	-2.26
H-2171N	5/7/2026 9:22:04 AM	111.0	-0.03	-0.09	0.0	3.2	-0.073	0.061	-3.61	
H-2171S	5/4/2026 2:02:33 PM	119.2	-1.27	-1.15	21.2	19.1	2.864	2.341	-10.59	-10.85
H-2272W	5/19/2026 10:27:12 AM	124.1	-0.57	-0.57	7.0	6.9	1.049	1.003	-6.71	-6.71
H-2272W	5/4/2026 9:50:05 AM	122.9	-0.55	-0.56	5.5	5.5	0.632	0.633	-8.46	-8.60
H-2272W	5/4/2026 9:47:59 AM	122.7	-0.56	-0.59	4.6	6.0	0.455	0.759	-8.44	-8.57
H-2273W	5/20/2026 8:21:56 AM	129.3	-0.77	-0.67	10.7	10.1	0.749	0.665	-8.30	-8.16
H-2273W	5/13/2026 12:42:00 PM	127.0	-0.53	-0.64	1.2	5.0	0.010	0.176	-7.48	
H-2273W	5/12/2026 7:50:00 AM									
H-2273W	5/12/2026 7:50:00 AM									
H-2274B	5/20/2026 2:09:49 PM	96.2	-0.78	-0.80	10.8	10.8	0.299	0.298	-7.77	
H-2274B	5/4/2026 1:23:52 PM	82.5	-1.96	-1.96	2.5	2.5	0.015	0.015	-8.60	
H-2274W	5/19/2026 1:17:54 PM	125.3	-0.22	-0.20	1.7	2.1	0.020	0.029	-2.88	-2.67
H-2274W	5/1/2026 10:22:35 AM	129.6	-0.45	-0.36	8.4	5.5	0.458	0.193	-8.39	-6.58
H-2275E	5/4/2026 11:24:01 AM	121.8	-1.01	-0.70	6.3	1.5	0.253	0.015	-8.83	-8.96

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
H-2275W	5/20/2026 7:50:11 AM	122.8	-0.93	-0.85	12.1	11.5	0.944	0.846	-9.28	-9.20
H-2275W	5/8/2026 11:15:19 AM	112.5	-0.08	-0.08	2.5	2.5	0.148	0.146	-4.76	
H-2275W	5/8/2026 11:13:59 AM	116.4	0.26	-0.13	4.0	1.0	0.355	0.026	-4.77	
H-2276A	5/20/2026 1:13:04 PM	107.9	-2.91	-2.87	13.0	12.8	0.216	0.212	-3.30	-3.28
H-2276A	5/11/2026 1:32:34 PM	106.7	-4.99	-4.92	20.5	20.2	0.544	0.525	-5.72	-5.58
H-2276B	5/20/2026 2:22:12 PM	118.3	-2.11	-2.16	17.0	19.4	0.625	0.822	-7.61	
H-2276B	5/4/2026 2:06:44 PM	114.3	-2.00	-2.21	14.2	19.5	0.427	0.806	-8.27	
H-2276E	5/4/2026 11:37:57 AM	115.6	-0.55	-0.53	10.0	7.7	0.129	0.076	-13.75	-14.05
H-2276W	5/20/2026 8:32:50 AM	92.7	-5.75	-4.89	10.5	9.2	0.675	0.519	-7.71	-7.68
H-2276W	5/1/2026 10:16:43 AM	102.9	-6.28	-5.79	14.9	12.7	1.388	1.011	-7.54	-7.30
H-2277A	5/21/2026 9:41:03 AM	93.8	-0.14	-0.11	1.5	1.5	0.013	0.014	-3.79	-3.86
H-2277A	5/1/2026 11:04:15 AM	79.9	-7.45	-7.10	15.2	13.0	1.403	1.021	-7.38	-7.52
H-2277B	5/21/2026 9:35:16 AM	117.5	-2.16	-2.13	1.6	1.6	0.673	0.725	-5.27	-5.23
H-2277B	5/4/2026 2:19:04 PM	115.5	-3.28	-2.60	19.9	16.6	2.414	1.673	-7.85	
H-23 (EXP-23)	5/13/2026 1:17:40 PM	94.1	-0.99	-0.90	1.9	2.1	0.004	0.006	-8.68	-8.71
H-23 (EXP-23)	5/13/2026 1:13:21 PM	92.2	-4.99	-4.99	0.4	0.1	0.003	0.000	-8.93	-8.69
H-23 (EXP-23)	5/13/2026 10:53:27 AM	86.9	-1.06	-0.91	0.2	0.6	0.001	0.006	-9.66	-9.39
H-23 (EXP-23)	5/13/2026 10:40:54 AM	77.4	-9.82	-9.65	3.5	2.7	0.027	0.016	-10.06	-10.09
H-2301E	5/13/2026 9:05:55 AM	105.3	-3.31	-3.31	14.6	16.4	0.270	0.340	-9.93	-10.12
H-2301W	5/15/2026 10:14:58 AM	73.0	-10.51	-10.46	0.0	0.0	-0.056	-0.039	-10.50	
H-2301W	5/15/2026 10:13:21 AM	72.5	-10.39	-10.37	0.0	0.0	-0.019	-0.022	-10.64	
H-2302C	5/7/2026 2:47:12 PM	117.4	-0.50	-0.75	9.9	14.4	0.576	1.232	-5.42	
H-2302E	5/8/2026 12:55:32 PM	105.2	-1.88	-1.87	31.7	31.6	1.136	1.130	-3.30	
H-2303E	5/8/2026 1:01:15 PM	88.7	-2.57	-2.57	0.0	0.0	-0.009	-0.009	-2.49	
H-2303N	5/7/2026 2:55:44 PM	102.5	-0.10	-0.21	12.9	16.6	3.195	5.298	-7.43	
H-2304E	5/8/2026 1:05:45 PM	95.6	-1.26	-1.27	40.9	32.9	0.366	0.236	-1.84	
H-2304S	5/8/2026 1:30:30 PM	123.8	-0.18	-0.29	18.0	19.7	6.591	7.878	-9.97	
H-2305N	5/7/2026 3:01:47 PM	98.7	-3.09	-3.64	3.6	4.6	0.027	0.043	-7.43	
H-2305S	5/8/2026 1:14:11 PM	126.4	-0.11	-0.24	21.2	23.5	2.715	3.344		

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
H-2306N	5/15/2026 10:33:03 AM	116.5	-2.83	-2.83	39.7	39.7	3.374	3.374	-11.44	
H-2307S	5/22/2026 11:53:04 AM	115.0	-2.02	-2.02	36.1	36.1	3.027	3.031	-9.85	-9.80
H-2307S	5/7/2026 2:41:47 PM	120.0	-0.23	-0.22	37.7	38.2	3.066	3.148	-6.93	
H-2307S	5/7/2026 2:40:20 PM	118.6	0.84	-0.04	10.2	38.5	0.218	3.157	-6.80	
H-2308S	5/7/2026 2:29:52 PM	120.3	-1.54	-1.44	42.9	39.9	2.189	1.903	-7.18	
H-2309N	5/4/2026 10:13:40 AM	83.7	-1.30	-1.29	0.0	0.0	-0.157	-0.158	-10.55	
H-2309S	5/8/2026 1:53:32 PM	109.3	-0.19	-0.40	18.4	23.2	0.388	0.622	-11.11	
H-2310N	5/8/2026 3:03:25 PM	110.2	-0.41	-0.52	7.3	13.1	0.306	0.998	-4.08	
H-2310S	5/22/2026 12:06:57 PM	102.8	-1.16	-0.55	2.3	1.3	0.552	0.180	-10.32	-10.02
H-2310S	5/14/2026 9:47:40 AM	100.9	-2.64	-1.71			0.193	0.091	-10.07	
H-2401S	5/7/2026 11:32:52 AM	108.8	-1.35	-1.62	4.6	5.7	0.424	0.638	-3.74	
H-2402N	5/8/2026 9:47:00 AM	105.9	-0.34	-0.33	1.5	1.5	0.239	0.238	-4.36	
H-2402S	5/8/2026 9:58:19 AM	109.7	-0.39	-0.50	15.8	19.5	0.288	0.439	-4.72	
H-2403N	5/8/2026 9:51:09 AM	112.3	-0.03	-0.13	0.0	4.1	-0.126	0.339	-4.34	
H-2403S	5/8/2026 9:35:34 AM	80.3	-0.53	-0.51	1.3	1.3	0.169	0.174	-4.16	
H-2404N	5/5/2026 3:35:40 PM	109.0	-1.26	-2.14	7.2	11.0	1.019	2.417	-9.28	
H-2404S	5/8/2026 8:59:38 AM	111.4	-3.40	-3.39	6.9	25.8	0.054	0.762	-3.81	
H-2405N	5/5/2026 2:23:59 PM	111.8	-0.59	-0.58	14.0	14.0	4.131	4.133	-8.69	
H-29	5/29/2026 12:05:20 PM	84.1	-0.10	-0.10	1.0	0.9	0.019	0.017	-10.76	-10.76
H-29	5/29/2026 12:00:31 PM	89.1	0.93	-0.13	2.3	3.7	0.101	0.271	-10.71	-11.09
H-29	5/4/2026 1:58:42 PM	71.0	-0.31	-0.31	1.0	1.0	0.020	0.020	-11.23	-11.23
H-29	5/4/2026 1:55:50 PM	71.1	1.61	-0.20	2.5	6.0	0.119	0.706	-11.13	-11.23
H-72	5/29/2026 9:51:57 AM	82.2	-0.37	-0.45	0.0	0.0	-0.096	-0.016	-4.60	
H-74	5/11/2026 11:20:34 AM	101.6	-1.20	-1.23	5.2	6.2	0.534	0.755	0.02	
H-75	5/14/2026 11:59:28 AM	90.5	-0.23	-0.23	2.2	2.2	1.230	1.233	-10.58	
H-79	5/15/2026 11:24:44 AM	128.6	-2.71	-2.70	2.4	1.9	0.007	0.005	-14.33	
P-02R	5/13/2026 8:15:30 AM	82.2	-0.65	-0.64	8.9	10.4	0.465	0.644	-20.57	-21.01
P-03R	5/13/2026 8:26:58 AM	87.7	-1.65	-1.65	3.0	2.9	0.899	0.873	-19.68	-19.72
P-04	5/5/2026 7:38:51 AM	91.5	-0.50	-0.50			0.502	0.503	-17.63	-17.65
P-05	5/5/2026 7:46:02 AM	102.1	-0.27	-0.27			0.272	0.272	-16.42	-16.56
P-06R	5/5/2026 7:49:46 AM	106.2	-0.69	-0.69	0.2	0.3	0.003	0.011	-15.79	-15.62
P-07R	5/12/2026 8:59:48 AM	83.4	-0.88	-0.88	4.5	4.5	2.046	2.066	-19.06	-19.13
P-08R	5/11/2026 10:46:01 AM	101.9	-15.23	-15.52	1.7	5.9	0.018	0.220	-16.37	-16.59
P-09	5/5/2026 8:01:21 AM	94.5	-0.61	-0.61			0.609	0.608	-11.96	-11.91

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
P-10	5/5/2026 7:56:04 AM	85.8	-0.34	-0.33	3.1	3.1	0.983	1.007	-11.51	-11.93
P-11	5/12/2026 9:25:09 AM	104.2	-0.43	-0.43	6.3	6.4	4.248	4.419	-11.64	-12.06
P-12	5/15/2026 7:59:36 AM	74.1	-11.34	-11.89	4.0	1.4	0.292	0.036	-14.20	
P-13	5/15/2026 8:05:44 AM	78.1	-1.24	-1.26	8.3	8.3	1.250	1.266	-14.84	
P-14	5/5/2026 8:13:25 AM	73.0	-0.40	-0.34			0.394	0.342	-13.69	-13.02
P-15R	5/5/2026 8:17:20 AM	71.3	-1.20	-1.21	0.8	0.9	0.066	0.075	-12.57	-12.71
P-16	5/5/2026 8:25:52 AM	79.3	-2.73	-2.73	3.7	3.6	3.369	3.292	-12.19	-12.14
P-17	5/5/2026 8:30:43 AM	109.2	-1.08	-1.08			1.065	1.068	-11.59	-12.12
P-18RD	5/5/2026 8:41:50 AM	81.6	-9.67	-9.66	3.5	3.5	1.281	1.274	-10.96	-11.09
P-18RS	5/5/2026 8:36:36 AM	91.2	-1.43	-1.42	5.3	5.2	2.871	2.769	-11.48	-11.00
P-19	5/4/2026 11:16:30 AM	84.0	-1.13	-1.07	7.6	5.8	0.325	0.189	-11.82	
P-20R	5/5/2026 8:45:27 AM	96.2	-1.36	-1.36	8.2	8.3	7.101	7.187	-10.85	-10.90
P-21	5/5/2026 8:49:59 AM	89.3	-0.67	-0.67			0.666	0.665	-10.65	-10.38
P-21RD	5/4/2026 10:03:26 AM	98.9	-4.27	-4.27	21.0	20.7	2.614	2.525	-8.94	
P-21RS	5/4/2026 10:00:38 AM	107.1	-4.23	-4.12	11.2	11.2	0.712	0.714	-9.22	
P-22RD	5/4/2026 10:32:00 AM	114.2	-4.38	-4.37	4.5	4.4	5.289	5.075	-8.95	
P-22RS	5/4/2026 10:28:52 AM	119.1	-1.28	-1.25	40.5	39.3	1.946	1.828	-9.30	
P-23	5/5/2026 8:59:25 AM	82.4	-0.68	-0.68	6.3	6.3	0.250	0.253	-9.81	-9.79
P-24	5/6/2026 8:17:07 AM	88.3	-2.34	-2.32	11.7	11.2	2.738	2.506	-10.03	
P-26	5/6/2026 8:34:09 AM	80.9	-6.27	-6.31	0.0	0.0	6.235	6.447		
P-27	5/6/2026 8:43:29 AM	72.3	-0.94	-0.84	0.0	0.0	0.961	0.820		
P-28	5/6/2026 8:51:00 AM	95.1	-5.34	-5.27	0.0	0.0	5.370	5.256		
P-29R	5/6/2026 8:57:44 AM	90.8	-1.53	-1.53	1.5	0.6	0.014	0.002	-7.84	
P-30R	5/6/2026 9:04:44 AM	83.5	-6.22	-6.14	10.2	9.9	2.085	1.984	-7.66	
P-32R1	5/6/2026 9:10:45 AM	109.7	-1.92	-1.89	2.8	2.3	8.334	5.730	-7.14	
P-32R2	5/6/2026 9:14:09 AM	110.5	-2.36	-2.32	11.3	10.1	2.670	2.131	-7.35	
P-33	5/6/2026 9:19:40 AM	93.1	-2.79	-2.69	0.0	0.0	2.778	2.631		
P-36	5/6/2026 9:31:05 AM	69.6	-0.44	-0.47	0.0	0.0	0.513	0.513		
P-37	5/6/2026 9:35:20 AM	84.4	-0.50	-0.47	0.9	0.9	0.232	0.233	-4.56	
P-38RD	5/6/2026 9:48:07 AM	106.4	-4.18	-4.19	32.6	17.1	1.255	0.346	-4.19	
P-38RS	5/6/2026 9:44:32 AM	104.4	-1.44	-1.40	10.7	12.3	0.688	0.897	-4.30	
P-39	5/6/2026 9:55:17 AM	78.9	-6.11	-6.96	2.2	0.0	0.094	-0.016	-7.06	
P-41	5/6/2026 10:07:48 AM	108.2	-2.99	-2.89	0.0	0.0	-0.154	-0.007		
P-41	5/6/2026 10:06:10 AM	108.6	-3.22	-3.14	0.0	0.0	-0.019	0.139		
P-42R	5/6/2026 10:15:47 AM	111.6	-6.82	-6.76	3.6	3.1	1.292	0.951	-8.60	
P-43	5/6/2026 10:22:56 AM	116.6	-4.38	-4.34	0.0	0.0	4.403	4.303		
P-44RD	5/6/2026 10:37:00 AM	90.4	-7.70	-7.71	0.0	0.0	-0.038	-0.020	-8.41	
P-44RS	5/6/2026 10:33:49 AM	121.8	-5.71	-5.69	18.4	18.6	2.145	2.188	-7.72	
P-45RD	5/6/2026 10:50:26 AM	114.9	-7.01	-7.06	3.7	3.5	0.287	0.247	-7.72	
P-45RS	5/6/2026 10:47:34 AM	92.2	-0.64	-0.61	0.0	0.0	-0.084	-0.003	-7.62	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
P-46RD	5/6/2026 11:02:37 AM	102.4	-7.60	-7.66	2.0	0.8	0.023	0.003	-7.60	
P-46RS	5/6/2026 10:55:16 AM	120.7	-2.42	-2.34	24.6	21.9	3.805	3.028	-7.77	
P-47	5/4/2026 10:21:39 AM	96.9	-0.16	-0.12	0.0	0.0	0.170	0.166		
P-48	5/4/2026 10:38:03 AM	111.5	-0.17	-0.12	0.0	0.0	0.011	0.000		
P-49RD	5/4/2026 10:58:34 AM	112.8	-10.02	-10.06	16.0	16.4	1.525	1.595	-11.71	
P-49RS	5/4/2026 10:55:41 AM	113.7	-1.23	-1.18	18.1	18.7	0.699	0.745	-12.10	
P-52	5/28/2026 2:38:45 PM	117.0	-0.42	-0.38			0.000	0.000	-13.73	-13.98
P-53	5/15/2026 8:37:53 AM	114.6	-2.32	-2.20	0.0	0.0	-0.013	-0.009	-17.38	
P-54	5/15/2026 8:35:38 AM	100.8	-1.22	-1.14	0.0	0.0	1.161	0.999		
P-55	5/15/2026 8:24:48 AM	94.0	-0.74	-0.65	0.0	0.0	0.710	0.695		
P-56	5/26/2026 9:15:49 AM	101.8	-0.31	-0.31			0.302	0.301	-15.62	-15.63
P-57	5/13/2026 9:14:04 AM	76.4	-0.54	-0.53	3.6	3.4	0.015	0.014	-19.39	-19.13
P-60R	5/7/2026 8:52:45 AM	76.5	-2.40	-2.29	0.0	0.0	-0.060	-0.075	-2.82	
P-60R	5/7/2026 8:48:07 AM	75.5	-2.46	-2.37	0.0	0.0	0.000	-0.014	-2.78	
P-61	5/7/2026 8:30:07 AM	83.4	-0.34	-0.31	5.0	5.0	2.472	2.502	-2.75	
P-65	5/7/2026 8:25:21 AM	71.5	-0.61	-0.62	2.0	1.9	0.999	0.853	-2.88	
P-71	5/4/2026 10:47:48 AM	72.3	-0.39	-0.38	0.0	0.0	0.373	0.377		
P-75	5/6/2026 11:19:49 AM	92.0	-3.99	-4.02	17.4	17.5	1.669	1.689	-4.37	
P-76	5/6/2026 9:41:27 AM	97.2	-1.85	-1.78	0.0	0.0	-1.760	-1.750	-4.17	
P-79	5/4/2026 11:21:51 AM	86.4	-0.35	-0.30	0.0	0.0	0.261	0.264	-10.40	
SC-2000E	5/6/2026 12:28:45 PM	119.4	-3.42	-3.22	5.2	5.9	0.553	0.703	-7.89	
SC-2501E	5/26/2026 9:21:31 AM	189.2	-0.77	-0.88	14.2	13.0	0.531	0.441	-4.08	-4.41
SC-2501E	5/18/2026 9:40:35 AM		0.16		10.5		0.288		-2.97	
SC-2501E	5/18/2026 9:40:00 AM									
SC-2501E	5/18/2026 9:38:11 AM	189.1	0.65	0.72	44.0	41.7	5.079	4.563	-3.93	-3.49
SC-2501E	5/18/2026 9:29:29 AM	190.6	1.07	-0.76	20.4	16.6	1.086	0.722	-2.01	-2.32
SC-2501E	5/12/2026 9:13:45 AM	188.9	-1.07	-1.13	53.0	52.5	7.423	7.294	-8.18	-8.02
SC-2501E	5/12/2026 9:10:00 AM									
SC-2501E	5/5/2026 8:56:40 AM	188.8	-1.63	-1.63	52.3	51.7	7.247	7.078	-8.76	-8.66
SC-2501E	5/5/2026 8:51:59 AM	188.6	-0.64	-1.24	38.7	32.1	10.915	7.472	-9.63	-8.78
SC-2501E	5/5/2026 8:50:00 AM									
SC-2501E	5/5/2026 8:50:00 AM									
SC-2501W	5/5/2026 9:19:42 AM	94.4	-0.04	-0.01	3.7	3.2	0.083	0.064	-7.23	-7.22
SW-10	5/28/2026 9:37:50 AM	71.4	-7.45	-7.43			0.975	0.954	-7.45	-7.32
SW-115	5/11/2026 8:59:04 AM	88.6	-6.65	-6.61	12.4	14.1	0.892	1.160	-11.97	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
SW-1445	5/22/2026 7:39:28 AM	61.4	-0.03	-0.03	5.3	4.9	0.033	0.028	0.22	0.21
SW-1445	5/4/2026 7:53:57 AM	80.9	-5.41	-5.41	22.8	23.1	0.640	0.653	-5.26	-5.17
SW-1455	5/22/2026 7:44:18 AM	67.3	0.02	0.02	2.1	2.3	0.005	0.006	0.32	0.08
SW-1455	5/4/2026 7:57:56 AM	83.5	-5.75	-5.75	25.4	25.0	0.795	0.772	-5.37	-5.42
SW-154	5/15/2026 9:34:29 AM	66.8	-8.39	-8.34	0.0	0.0	8.477	8.394		
SW-154	5/15/2026 9:31:56 AM	67.0	-8.11	-8.06	0.0	0.0	8.020	8.115		
SW-17-135	5/22/2026 7:41:29 AM	65.9	-0.06	-0.05	8.1	7.4	0.077	0.065	0.29	0.30
SW-17-135	5/4/2026 7:56:03 AM	72.4	-5.36	-5.39	23.3	22.9	0.655	0.635	-5.22	-5.27
SW-187	5/4/2026 9:31:29 AM	81.6	-7.79	-7.79	69.8	68.8	1.149	1.115	-7.52	-7.54
SW-1930	5/1/2026 7:51:05 AM	81.3	-8.39	-8.45	81.4	81.2	8.347	8.317	-8.44	-8.44
SW-20	5/12/2026 9:06:57 AM	80.3	-0.07	-0.06	0.4	0.4	0.016	0.013	-19.34	-19.19
SW-25	5/1/2026 7:53:15 AM	65.9	-0.81	-0.81	25.9	25.7	0.791	0.782	-8.44	-8.39
SW-2501D	5/29/2026 7:21:12 AM	72.0	-7.73	-7.72	7.6	8.6	0.069	0.090	-7.44	-7.19
SW-2501D	5/28/2026 6:16:27 AM	71.7	-8.11	-8.11	2.5	2.5	0.643	0.628	-8.29	-8.29
SW-2501D	5/27/2026 6:04:20 AM	68.7	-5.23	-5.22	2.5	2.5	0.649	0.647	-5.09	-5.09
SW-2501D	5/26/2026 6:11:29 AM	72.7	-6.63	-6.63	3.0	3.0	0.941	0.935	-6.31	-6.40
SW-2501D	5/22/2026 6:19:43 AM	70.5	-8.32	-8.32	2.9	2.9	0.835	0.839	-8.18	-8.15
SW-2501D	5/21/2026 6:35:47 AM	77.0	-7.73	-7.73	2.2	2.3	0.519	0.528	-7.74	-7.74
SW-2501D	5/20/2026 8:30:45 AM	78.9	-7.46	-7.43	0.7	0.5	0.048	0.024	-7.59	-7.45
SW-2501D	5/19/2026 9:01:29 AM	79.8	-6.08	-6.08	0.4	0.4	0.018	0.015	-6.08	-6.08
SW-2501D	5/18/2026 8:44:45 AM	76.1	-4.74	-4.74	0.4	0.5	0.017	0.024	-4.85	-4.82
SW-2501D	5/15/2026 9:25:43 AM	77.9	-7.43	-7.14	1.5	0.4	0.239	0.015	-7.12	-7.41
SW-2501D	5/14/2026 8:19:05 AM	75.6	-6.67	-6.67	0.7	0.7	0.052	0.053	-6.74	-6.74
SW-2501D	5/13/2026 8:08:49 AM	75.6	-7.62	-7.77	0.5	0.4	0.021	0.016	-7.69	-7.88
SW-2501D	5/12/2026 9:15:23 AM	79.3	-6.64	-6.76	0.8	0.8	0.061	0.070	-6.76	-6.76
SW-2501D	5/11/2026 8:24:00 AM	77.2	-5.46	-5.11	1.1	0.8	0.120	0.070	-5.40	-5.21
SW-2501D	5/8/2026 9:35:42 AM	75.7	-3.41	-3.29	0.6	0.4	0.040	0.013	-3.22	-3.16
SW-2501D	5/7/2026 8:55:20 AM	74.7	-3.60	-3.68	0.8	0.8	0.061	0.063	-3.17	-3.22
SW-2501D	5/6/2026 8:47:06 AM	72.8	-7.47	-7.43	2.7	2.7	0.737	0.732	-7.62	-7.68
SW-2501D	5/5/2026 8:31:57 AM	72.1	-8.28	-8.32	1.2	0.7	0.154	0.050	-8.14	-8.08
SW-2501D	5/4/2026 8:20:15 AM	71.5	-8.15	-8.11	3.7	3.8	1.430	1.432	-7.97	-7.95
SW-2501D	5/1/2026 8:28:56 AM	71.9	-8.31	-8.35	9.0	9.1	8.452	8.495	-8.41	-8.42
SW-2501M	5/29/2026 7:24:25 AM	62.3	-7.56	-7.72	2.7	0.8	0.009	0.001	-7.40	-7.52

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
SW-2501M	5/28/2026 6:12:29 AM	62.8	-8.10	-8.11	3.2	3.1	1.001	0.966	-8.03	-8.04
SW-2501M	5/27/2026 5:59:22 AM	66.2	-5.29	-5.35	2.4	2.3	0.577	0.511	-5.08	-5.20
SW-2501M	5/26/2026 6:01:33 AM	68.2	-6.63	-6.63	3.0	3.0	0.897	0.900	-6.40	-6.40
SW-2501M	5/22/2026 6:14:16 AM	64.9	-8.27	-8.27	2.4	2.4	0.577	0.579	-8.18	-8.17
SW-2501M	5/21/2026 6:30:13 AM	69.6	-7.73	-7.73	2.7	2.7	0.742	0.762	-7.68	-7.40
SW-2501M	5/20/2026 8:25:51 AM	76.4	-7.46	-7.43	0.2	0.2	0.003	0.004	-7.44	-7.36
SW-2501M	5/19/2026 8:55:12 AM	76.2	-6.13	-6.23	0.4	0.2	0.016	0.002	-6.26	-6.40
SW-2501M	5/18/2026 8:38:11 AM	73.8	-4.97	-5.00	0.5	0.4	0.027	0.018	-4.66	-4.88
SW-2501M	5/15/2026 9:19:11 AM	72.0	-7.43	-7.24	0.9	0.8	0.080	0.059	-7.41	-7.31
SW-2501M	5/14/2026 8:13:12 AM	71.6	-6.68	-6.68	0.8	0.8	0.069	0.070	-6.69	-6.69
SW-2501M	5/13/2026 8:03:42 AM	70.9	-7.74	-7.73	0.7	0.4	0.050	0.016	-7.53	-7.53
SW-2501M	5/12/2026 9:11:04 AM	75.7	-6.77	-6.76	0.1	0.1	0.001	0.001	-6.85	-6.76
SW-2501M	5/11/2026 8:20:03 AM	77.8	-5.11	-5.19	0.4	0.4	0.017	0.014	-4.85	-4.90
SW-2501M	5/8/2026 9:30:13 AM	73.5	-3.41	-3.42	0.1	0.5	0.001	0.025	-3.22	-3.18
SW-2501M	5/7/2026 8:50:28 AM	73.3	-3.77	-3.68	1.0	0.6	0.109	0.032	-3.27	-3.28
SW-2501M	5/6/2026 8:42:31 AM	66.6	-7.47	-7.72	0.4	0.3	0.012	0.011	-7.67	-7.92
SW-2501M	5/5/2026 8:23:44 AM	64.9	-8.43	-8.40	1.0	0.3	0.099	0.008	-8.14	-8.34
SW-2501M	5/4/2026 8:14:55 AM	67.6	-8.11	-8.11	3.7	3.6	1.368	1.273	-7.95	-7.99
SW-2501M	5/1/2026 8:25:32 AM	66.4	-8.26	-8.28	9.1	9.1	8.403	8.471	-8.39	-8.44
SW-2501MD	5/29/2026 7:15:49 AM	76.6	-7.78	-7.72	0.8	1.2	0.004	0.009	-7.69	-7.52
SW-2501MD	5/28/2026 6:14:16 AM	74.9	-8.35	-8.36	13.0	13.0	1.010	1.009	-8.27	-8.27
SW-2501MD	5/27/2026 6:02:25 AM	75.8	-5.35	-5.36	10.3	10.3	0.637	0.636	-5.17	-5.17
SW-2501MD	5/26/2026 6:05:27 AM	72.5	-6.63	-6.68	12.7	12.6	0.957	0.952	-6.74	-6.54
SW-2501MD	5/22/2026 6:16:46 AM	70.6	-8.34	-8.33	13.1	13.1	1.030	1.032	-8.16	-8.15
SW-2501MD	5/21/2026 6:32:26 AM	76.8	-7.71	-7.71	9.1	9.2	0.495	0.508	-7.45	-7.43
SW-2501MD	5/20/2026 8:28:56 AM	79.0	-7.43	-7.43	2.2	0.6	0.030	0.002	-7.57	-7.56
SW-2501MD	5/19/2026 8:58:19 AM	80.0	-6.08	-6.08	0.7	0.7	0.003	0.003	-6.15	-6.15
SW-2501MD	5/18/2026 8:41:43 AM	77.9	-4.78	-4.78	0.5	0.5	0.002	0.002	-4.72	-4.72
SW-2501MD	5/14/2026 8:16:25 AM	78.1	-6.50	-6.49	1.2	1.2	0.008	0.008	-6.72	-6.72
SW-2501MD	5/13/2026 8:06:36 AM	77.1	-7.47	-7.60	1.9	1.7	0.021	0.018	-7.67	-7.73
SW-2501MD	5/12/2026 9:12:49 AM	77.4	-6.74	-6.76	2.2	4.9	0.030	0.141	-6.94	-6.88

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
SW-2501MD	5/11/2026 8:21:50 AM	78.2	-4.92	-4.74	1.9	1.5	0.021	0.013	-4.67	-4.55
SW-2501MD	5/8/2026 9:32:28 AM	76.8	-3.40	-3.45	1.4	1.9	0.012	0.022	-3.27	-3.31
SW-2501MD	5/7/2026 8:53:13 AM	77.2	-3.65	-3.57	3.0	0.0	0.054	0.000	-3.29	-3.30
SW-2501MD	5/6/2026 8:45:13 AM	76.6	-7.70	-7.62	2.3	0.9	0.032	0.004	-7.77	-7.81
SW-2501MD	5/5/2026 8:27:56 AM	76.5	-8.39	-8.40	4.2	1.1	0.107	0.007	-8.18	-8.13
SW-2501MD	5/4/2026 8:17:07 AM	76.4	-8.11	-8.15	12.6	12.9	0.957	0.998	-8.01	-7.99
SW-2501MD	5/1/2026 8:27:27 AM	76.8	-8.11	-8.11	36.8	36.8	8.244	8.247	-8.16	-8.18
SW-2501S	5/29/2026 7:18:48 AM	66.2	-7.61	-7.58	12.5	11.8	0.186	0.167	-7.66	-7.57
SW-2501S	5/28/2026 6:18:35 AM	65.4	-8.11	-8.11	2.9	3.0	0.855	0.884	-8.29	-8.29
SW-2501S	5/27/2026 6:06:12 AM	68.4	-5.11	-5.11	2.6	2.6	0.662	0.662	-5.32	-5.32
SW-2501S	5/26/2026 6:14:28 AM	68.3	-6.63	-6.71	3.1	3.1	0.940	0.957	-6.59	-6.74
SW-2501S	5/22/2026 6:22:20 AM	69.5	-7.98	-7.96	2.1	2.1	0.464	0.449	-8.08	-8.10
SW-2501S	5/21/2026 6:38:09 AM	71.2	-7.63	-7.64	1.9	1.7	0.361	0.293	-7.51	-7.49
SW-2501S	5/20/2026 8:33:18 AM	72.5	-7.09	-7.09	1.2	1.3	0.144	0.162	-7.41	-7.45
SW-2501S	5/19/2026 9:04:28 AM	72.4	-5.74	-5.74	1.2	1.1	0.139	0.129	-6.03	-6.06
SW-2501S	5/18/2026 8:47:27 AM	70.4	-4.72	-4.72	1.0	1.0	0.106	0.106	-4.47	-4.49
SW-2501S	5/15/2026 9:27:58 AM	75.8	-7.77	-7.66	0.8	0.7	0.059	0.048	-8.08	-7.75
SW-2501S	5/15/2026 9:22:25 AM	71.8	-6.42	-6.42	0.7	1.2	0.052	0.138	-6.40	-6.74
SW-2501S	5/14/2026 8:22:49 AM	71.3	-6.09	-6.10	1.2	1.2	0.154	0.153	-6.44	-6.47
SW-2501S	5/13/2026 8:12:06 AM	72.6	-7.40	-7.45	1.4	1.4	0.189	0.189	-7.74	-7.74
SW-2501S	5/12/2026 9:17:43 AM	74.8	-6.51	-6.52	1.0	1.3	0.107	0.166	-6.76	-6.76
SW-2501S	5/11/2026 8:26:36 AM	73.3	-5.07	-5.01	0.6	1.0	0.038	0.103	-5.39	-5.23
SW-2501S	5/8/2026 9:39:11 AM	73.0	-3.39	-3.31	0.5	0.8	0.027	0.069	-3.22	-3.17
SW-2501S	5/7/2026 9:00:17 AM	70.2	-3.45	-3.47	0.7	0.7	0.056	0.053	-3.05	-3.08
SW-2501S	5/6/2026 8:51:41 AM	66.3	-7.30	-7.43	1.3	1.3	0.173	0.179	-7.64	-7.75
SW-2501S	5/5/2026 8:36:07 AM	66.3	-8.07	-8.07	1.2	1.4	0.136	0.189	-8.10	-8.08
SW-2501S	5/4/2026 8:22:18 AM	67.3	-7.84	-7.83	2.6	2.6	0.686	0.694	-8.06	-8.01
SW-2501S	5/1/2026 8:30:42 AM	68.5	-8.05	-8.11	8.9	8.9	8.112	8.154	-8.39	-8.39

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
SW-2502D	5/29/2026 7:02:56 AM	71.6	-7.88	-7.88	0.7	0.7	0.044	0.044	-7.71	-7.71
SW-2502D	5/28/2026 6:27:56 AM	64.5	-8.11	-8.09	3.1	3.1	0.953	0.952	-8.08	-8.12
SW-2502D	5/27/2026 6:15:12 AM	70.6	-5.07	-5.07	2.1	2.1	0.447	0.435	-5.24	-5.26
SW-2502D	5/26/2026 6:28:54 AM	69.5	-6.78	-6.79	2.4	2.4	0.579	0.559	-6.57	-6.59
SW-2502D	5/22/2026 6:34:30 AM	68.7	-8.33	-8.32	2.7	2.7	0.726	0.724	-8.01	-8.02
SW-2502D	5/21/2026 6:50:59 AM	71.1	-7.61	-7.64	2.3	2.2	0.553	0.496	-7.29	-7.40
SW-2502D	5/20/2026 8:15:28 AM	75.1	-7.50	-7.46	0.5	0.4	0.026	0.018	-7.28	-7.33
SW-2502D	5/19/2026 9:17:49 AM	77.8	-5.78	-5.79	0.5	0.1	0.025	0.001	-5.88	-5.89
SW-2502D	5/18/2026 8:59:18 AM	74.1	-4.90	-4.85	0.5	0.5	0.025	0.026	-4.54	-4.48
SW-2502D	5/15/2026 9:08:52 AM	73.2	-5.74	-5.76	0.9	0.8	0.077	0.067	-5.77	-5.92
SW-2502D	5/14/2026 8:37:14 AM	72.5	-6.42	-6.42	0.6	0.9	0.033	0.081	-6.41	-6.40
SW-2502D	5/13/2026 8:21:57 AM	74.7	-7.77	-7.77	0.3	0.2	0.011	0.006	-7.76	-7.91
SW-2502D	5/12/2026 9:27:18 AM	77.2	-6.74	-6.76	0.8	0.6	0.061	0.033	-6.75	-6.76
SW-2502D	5/11/2026 8:36:30 AM	76.6	-5.11	-5.07	0.5	0.5	0.027	0.030	-5.09	-5.18
SW-2502D	5/8/2026 9:49:11 AM	74.6	-3.68	-3.64	0.7	0.3	0.046	0.010	-3.63	-3.64
SW-2502D	5/7/2026 9:13:11 AM	74.4	-3.53	-3.45	0.8	0.6	0.068	0.041	-3.04	-3.02
SW-2502D	5/6/2026 9:03:29 AM	72.2	-7.45	-7.63	0.8	1.1	0.062	0.132	-7.47	-7.46
SW-2502D	5/5/2026 8:48:17 AM	72.6	-8.14	-8.34	0.6	0.6	0.042	0.040	-7.99	-8.08
SW-2502D	5/4/2026 8:29:47 AM	70.0	-8.45	-8.45	3.4	3.5	1.158	1.215	-8.21	-8.14
SW-2502D	5/1/2026 8:39:01 AM	72.7	-8.17	-8.16	9.0	9.0	8.328	8.326	-8.33	-8.33
SW-2502M	5/29/2026 6:58:21 AM	73.3	-7.91	-7.93	0.8	0.8	0.071	0.071	-7.83	-7.83
SW-2502M	5/28/2026 6:26:04 AM	72.6	-8.11	-8.11	2.4	2.5	0.568	0.625	-8.29	-8.29
SW-2502M	5/27/2026 6:13:20 AM	73.9	-5.31	-5.38	2.5	2.5	0.632	0.632	-5.21	-5.16
SW-2502M	5/26/2026 6:25:59 AM	76.0	-6.65	-6.63	2.4	2.3	0.585	0.538	-6.36	-6.57
SW-2502M	5/22/2026 6:31:26 AM	70.2	-8.32	-8.32	2.7	2.6	0.721	0.705	-8.08	-8.12
SW-2502M	5/21/2026 6:48:59 AM	77.7	-7.98	-7.98	2.4	2.3	0.583	0.565	-7.74	-7.74
SW-2502M	5/20/2026 8:13:58 AM	77.9	-6.80	-6.76	0.6	0.3	0.032	0.010	-6.85	-6.85
SW-2502M	5/19/2026 9:14:46 AM	79.9	-5.75	-5.75	0.8	0.7	0.058	0.056	-5.76	-5.77
SW-2502M	5/18/2026 8:56:28 AM	76.7	-4.87	-4.97	0.8	0.8	0.063	0.060	-4.42	-4.46
SW-2502M	5/15/2026 9:04:47 AM	75.9	-7.43	-7.22	1.5	0.5	0.221	0.028	-7.58	-7.42
SW-2502M	5/14/2026 8:34:30 AM	76.7	-6.42	-6.42	0.7	0.6	0.048	0.033	-6.48	-6.44
SW-2502M	5/13/2026 8:19:53 AM	77.2	-7.62	-7.64	0.6	0.2	0.031	0.002	-7.66	-7.86

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
SW-2502M	5/12/2026 9:25:33 AM	78.8	-6.59	-6.64	0.6	0.6	0.037	0.031	-6.74	-6.74
SW-2502M	5/11/2026 8:34:43 AM	77.3	-5.07	-5.07	1.0	0.6	0.097	0.038	-5.05	-5.07
SW-2502M	5/8/2026 9:47:15 AM	74.8	-3.45	-3.50	0.8	0.6	0.072	0.035	-3.37	-3.46
SW-2502M	5/7/2026 9:10:36 AM	72.4	-3.55	-3.52	0.9	0.8	0.080	0.068	-3.07	-3.05
SW-2502M	5/6/2026 9:01:23 AM	71.2	-7.42	-7.44	1.0	0.7	0.096	0.052	-7.56	-7.53
SW-2502M	5/5/2026 8:46:24 AM	71.8	-8.29	-8.29	1.0	0.9	0.101	0.089	-8.00	-8.07
SW-2502M	5/4/2026 8:28:19 AM	71.9	-8.40	-8.41	3.4	3.4	1.202	1.174	-7.98	-7.98
SW-2502M	5/1/2026 8:36:49 AM	72.5	-8.23	-8.23	9.0	9.0	8.407	8.403	-8.39	-8.39
SW-2502MD	5/29/2026 7:08:57 AM	77.7	-21.95	-21.88	11.2	11.1	13.657	13.520	-7.81	-8.21
SW-2502MD	5/28/2026 6:29:56 AM	75.5	-7.77	-7.77	2.2	2.2	0.514	0.510	-7.93	-7.91
SW-2502MD	5/27/2026 6:16:47 AM	75.4	-5.42	-5.41	2.6	2.6	0.704	0.681	-5.30	-5.18
SW-2502MD	5/26/2026 6:31:21 AM	77.6	-6.67	-6.67	2.3	2.3	0.560	0.558	-6.48	-6.47
SW-2502MD	5/22/2026 6:36:17 AM	77.0	-8.33	-8.32	2.7	2.6	0.746	0.684	-8.08	-8.16
SW-2502MD	5/21/2026 6:52:38 AM	77.1	-7.86	-7.83	2.7	2.7	0.777	0.763	-7.63	-7.60
SW-2502MD	5/20/2026 8:17:46 AM	80.0	-7.47	-7.46	0.0	0.2	0.000	0.005	-7.38	-7.37
SW-2502MD	5/19/2026 9:20:34 AM	82.3	-5.73	-5.73	0.2	0.2	0.004	0.004	-5.76	-5.76
SW-2502MD	5/18/2026 9:02:05 AM	80.0	-4.98	-4.89	0.2	0.1	0.003	0.001	-4.66	-4.48
SW-2502MD	5/15/2026 9:12:10 AM	78.8	-7.43	-7.32	0.7	0.3	0.053	0.010	-7.41	-7.34
SW-2502MD	5/14/2026 8:39:47 AM	79.2	-6.55	-6.54	0.4	0.4	0.016	0.015	-6.71	-6.71
SW-2502MD	5/13/2026 8:24:00 AM	79.0	-7.77	-7.77	0.4	0.6	0.013	0.040	-7.74	-7.78
SW-2502MD	5/12/2026 9:28:53 AM	80.2	-6.77	-6.65	0.4	0.5	0.017	0.021	-6.85	-6.90
SW-2502MD	5/11/2026 8:38:07 AM	79.0	-5.11	-5.08	0.7	0.2	0.044	0.005	-5.15	-5.15
SW-2502MD	5/8/2026 9:51:10 AM	79.3	-3.82	-3.80	0.3	0.4	0.009	0.013	-3.68	-3.68
SW-2502MD	5/7/2026 9:14:39 AM	77.6	-3.60	-3.55	0.5	0.1	0.024	0.002	-3.07	-3.06
SW-2502MD	5/6/2026 9:05:22 AM	77.2	-7.40	-7.47	0.7	0.2	0.049	0.002	-7.42	-7.54
SW-2502MD	5/5/2026 8:50:15 AM	77.6	-8.31	-8.46	0.6	0.0	0.040	0.000	-8.07	-8.19
SW-2502MD	5/4/2026 8:31:32 AM	78.0	-8.11	-8.11	2.9	2.9	0.875	0.882	-8.29	-7.99

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
SW-2502MD	5/1/2026 8:41:00 AM	77.9	-7.93	-7.94	8.8	8.8	8.091	8.094	-7.98	-7.98
SW-2502S	5/29/2026 6:54:54 AM	73.1	-21.47	-21.66	11.0	11.4	13.144	13.994	-8.54	-10.89
SW-2502S	5/28/2026 6:24:10 AM	65.5	-7.83	-7.83	2.1	2.1	0.439	0.431	-8.17	-8.17
SW-2502S	5/27/2026 6:11:24 AM	71.6	-5.07	-5.08	2.1	2.2	0.448	0.486	-5.21	-5.32
SW-2502S	5/26/2026 6:23:43 AM	70.8	-6.51	-6.53	1.9	1.9	0.356	0.356	-6.49	-6.50
SW-2502S	5/22/2026 6:29:06 AM	69.9	-7.96	-7.96	2.1	2.1	0.436	0.428	-8.00	-8.01
SW-2502S	5/21/2026 6:47:21 AM	75.3	-7.47	-7.46	1.3	1.3	0.168	0.166	-7.72	-7.69
SW-2502S	5/20/2026 8:12:10 AM	73.8	-6.42	-6.42	1.6	1.5	0.244	0.230	-6.51	-6.54
SW-2502S	5/19/2026 9:11:46 AM	73.4	-5.53	-5.53	1.5	1.5	0.216	0.213	-5.89	-5.81
SW-2502S	5/18/2026 8:53:31 AM	74.8	-4.92	-4.95	1.2	1.2	0.153	0.152	-4.73	-4.76
SW-2502S	5/15/2026 9:00:33 AM	74.8	-6.78	-6.90	1.6	1.7	0.267	0.294	-7.29	-7.42
SW-2502S	5/14/2026 8:31:19 AM	74.6	-6.08	-6.08	1.5	1.5	0.236	0.231	-6.54	-6.65
SW-2502S	5/13/2026 8:17:54 AM	75.6	-7.23	-7.28	1.7	1.8	0.296	0.320	-7.70	-7.79
SW-2502S	5/12/2026 9:23:35 AM	75.0	-6.42	-6.76	1.5	1.6	0.230	0.250	-7.09	-7.09
SW-2502S	5/11/2026 8:32:32 AM	75.4	-4.90	-4.77	1.4	1.3	0.190	0.166	-5.22	-5.05
SW-2502S	5/8/2026 9:44:33 AM	73.7	-3.29	-3.41	0.6	1.0	0.036	0.092	-3.16	-3.43
SW-2502S	5/7/2026 9:08:55 AM	71.8	-3.66	-3.61	0.8	0.8	0.064	0.068	-3.37	-3.13
SW-2502S	5/6/2026 8:59:15 AM	68.7	-7.37	-6.76	1.5	1.5	0.232	0.215	-7.81	-7.12
SW-2502S	5/5/2026 8:44:34 AM	69.1	-7.84	-7.88	1.8	1.7	0.315	0.307	-8.06	-8.07
SW-2502S	5/4/2026 8:26:37 AM	69.1	-7.58	-7.56	2.3	2.2	0.550	0.499	-7.85	-7.99
SW-2502S	5/1/2026 8:35:09 AM	68.7	-7.77	-7.77	8.8	8.8	7.864	7.891	-8.10	-8.10
SW-2503D	5/12/2026 8:21:40 AM	80.8	-6.59	-6.47	0.4	0.3	0.014	0.012	-6.38	-6.34
SW-2503D	5/4/2026 8:56:42 AM	70.0	-7.69	-7.69	2.9	2.9	0.824	0.824	-7.61	-7.61
SW-2503M	5/12/2026 8:27:21 AM	75.3	-6.63	-6.57	0.7	0.8	0.053	0.059	-6.59	-6.59
SW-2503M	5/4/2026 9:01:03 AM	73.8	-7.77	-7.77	2.9	2.9	0.849	0.848	-7.61	-7.61
SW-2503MD	5/12/2026 8:24:48 AM	76.9	-6.49	-6.44	0.7	0.3	0.047	0.011	-6.53	-6.63
SW-2503MD	5/4/2026 8:58:22 AM	76.4	-7.81	-7.80	3.2	3.2	1.063	1.021	-7.61	-7.61
SW-2503S	5/12/2026 8:35:33 AM	81.0	-6.53	-6.55	0.2	0.4	0.003	0.020	-6.70	-6.69
SW-2503S	5/4/2026 9:03:12 AM	79.7	-7.47	-7.47	2.6	2.6	0.675	0.686	-7.61	-7.61

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
SW-2504D	5/12/2026 8:47:37 AM	82.3	-6.69	-6.44	0.6	0.6	0.007	0.007	-6.73	-6.69
SW-2504D	5/4/2026 9:08:28 AM	79.3	-7.47	-7.47	6.1	6.0	0.756	0.723	-7.44	-7.61
SW-2504M	5/12/2026 8:49:55 AM	79.9	-6.76	-6.76			0.086	0.054	-6.69	-6.69
SW-2504M	5/4/2026 9:18:12 AM	80.4	-7.32	-7.30			1.177	1.171	-7.21	-7.22
SW-2504MD	5/20/2026 1:56:54 PM	132.4	-0.48	-0.38	4.6	4.2	0.451	0.393	-9.04	-8.87
SW-2504MD	5/12/2026 8:55:07 AM	78.2	-6.59	-6.46	1.2	1.4	0.028	0.037	-6.54	-6.69
SW-2504MD	5/4/2026 9:22:21 AM	73.1	-7.45	-7.43	7.4	7.2	1.076	1.027	-7.33	-7.28
SW-2504S	5/12/2026 8:51:59 AM	81.2	-6.57	-6.57	1.0	1.5	0.021	0.043	-6.56	-6.63
SW-2504S	5/4/2026 9:20:08 AM	75.4	-7.42	-7.47	7.8	7.5	1.213	1.123	-7.28	-7.49
SW-30	5/22/2026 6:43:04 AM	52.8	-0.17	-0.16	12.1	12.0	0.168	0.166	0.00	0.00
SW-30	5/21/2026 7:02:29 AM	59.8	-0.08	-0.08	2.0	1.9	0.005	0.004	0.04	0.04
SW-30	5/20/2026 8:03:41 AM	74.0	0.00	0.00	0.0	0.0	0.000	0.000	0.01	0.00
SW-30	5/19/2026 9:31:23 AM	83.3	-0.19	-0.18	0.9	1.1	0.001	0.001	0.34	0.34
SW-30	5/18/2026 9:09:16 AM	79.9	-4.70	-4.71	1.6	1.1	0.003	0.002	-4.29	-4.33
SW-30	5/15/2026 8:48:17 AM	71.5	-6.79	-6.63	2.0	1.7	0.005	0.004	-6.95	-6.77
SW-30	5/14/2026 8:48:35 AM	75.8	0.00	0.00	4.8	4.7	0.028	0.027	0.36	0.34
SW-30	5/13/2026 8:34:30 AM	67.9	-7.14	-7.14	8.7	5.2	0.090	0.033	-7.40	-7.40
SW-30	5/12/2026 9:39:11 AM	82.1	-6.53	-6.42	6.1	4.1	0.046	0.021	-6.53	-6.39
SW-30	5/11/2026 8:48:10 AM	85.5	-3.91	-3.93	3.3	3.0	0.013	0.011	-3.71	-3.73
SW-30	5/8/2026 10:07:17 AM	83.3	-3.63	-3.57	6.7	3.5	0.055	0.015	-3.67	-3.68
SW-30	5/7/2026 9:27:26 AM	85.9	-3.06	-3.17	3.5	4.1	0.015	0.021	-3.11	-3.11
SW-30	5/6/2026 9:14:39 AM	78.5	-7.18	-7.11	6.2	10.6	0.047	0.136	-7.30	-7.14
SW-30	5/5/2026 9:02:34 AM	67.1	-8.01	-8.01	4.0	4.0	0.019	0.019	-7.94	-7.94
SW-30	5/4/2026 8:36:47 AM	69.9	-8.11	-8.11	26.5	26.6	0.848	0.860	-8.17	-7.95
SW-30	5/1/2026 8:52:33 AM	78.3	-8.08	-8.11	27.8	27.0	0.947	0.899	-8.08	-8.10
SW-32	5/22/2026 6:47:07 AM	53.2	-0.14	-0.14			0.140	0.142	0.00	0.00
SW-32	5/21/2026 7:10:28 AM	68.7	-0.16	-0.16			0.160	0.158	0.00	0.00
SW-32	5/20/2026 7:45:31 AM	73.0	0.00	0.00			0.004	0.004	0.00	-0.01
SW-32	5/19/2026 9:36:21 AM	90.3	-0.18	-0.19			0.180	0.160	0.34	0.34

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
SW-32	5/18/2026 9:14:33 AM	83.6	-4.82	-4.83			4.790	4.789	-4.35	-4.38
SW-32	5/15/2026 8:38:38 AM	71.0	-6.66	-6.86			7.032	7.202	-6.83	-6.94
SW-32	5/14/2026 8:53:16 AM	83.6	-0.02	-0.02			0.022	0.021	0.34	0.34
SW-32	5/13/2026 8:29:37 AM	64.4	-7.71	-7.87			7.719	7.932	-7.68	-7.95
SW-32	5/12/2026 9:35:51 AM	77.2	-6.71	-6.46			6.844	6.826	-6.76	-6.76
SW-32	5/11/2026 8:43:32 AM	78.3	-4.26	-4.28			4.190	4.176	-4.06	-4.08
SW-32	5/8/2026 10:02:48 AM	85.0	-3.41	-3.36			3.348	3.277	-3.36	-3.49
SW-32	5/7/2026 9:20:49 AM	81.6	-3.06	-3.17			2.996	3.113	-3.01	-3.11
SW-32	5/6/2026 9:10:33 AM	81.4	-7.15	-7.12			7.552	7.494	-7.28	-7.24
SW-32	5/5/2026 8:56:30 AM	60.6	-8.01	-7.98			8.112	8.045	-7.80	-7.77
SW-32	5/4/2026 8:41:26 AM	82.7	-8.17	-8.11			8.452	8.398	-7.97	-7.99
SW-32	5/1/2026 8:45:18 AM	74.4	-7.88	-7.87			8.147	8.149	-7.99	-7.99
SW-64	5/22/2026 6:40:52 AM	55.0	-0.13	-0.12	10.4	10.1	0.125	0.119	0.02	0.00
SW-64	5/21/2026 6:58:46 AM	62.3	-0.20	-0.20	4.5	4.2	0.023	0.021	0.00	0.00
SW-64	5/20/2026 8:05:22 AM	75.2	0.00	0.00	1.6	1.4	0.003	0.002	-0.03	0.01
SW-64	5/19/2026 9:28:23 AM	88.3	-0.20	-0.20	2.3	2.3	0.007	0.006	0.34	0.34
SW-64	5/18/2026 9:06:40 AM	78.7	-4.78	-4.77	5.4	5.5	0.035	0.037	-4.32	-4.30
SW-64	5/15/2026 8:53:43 AM	67.8	-6.78	-6.98	2.1	2.3	0.005	0.007	-6.99	-7.07
SW-64	5/15/2026 8:43:20 AM		-6.67		8.1		0.079		-6.84	
SW-64	5/14/2026 8:44:43 AM	77.9	-0.09	-0.09	7.1	7.1	0.060	0.060	0.35	0.35
SW-64	5/13/2026 8:36:34 AM	65.0	-7.65	-7.14	5.6	1.6	0.038	0.003	-7.68	-7.32
SW-64	5/12/2026 9:41:18 AM	86.5	-6.42	-6.42	2.8	3.1	0.010	0.012	-6.51	-6.42
SW-64	5/11/2026 8:51:06 AM	89.5	-3.88	-3.87	4.4	6.6	0.024	0.053	-3.71	-3.71
SW-64	5/8/2026 10:09:00 AM	84.2	-3.31	-3.40	7.0	6.1	0.060	0.045	-3.35	-3.35
SW-64	5/7/2026 9:29:18 AM	87.8	-3.16	-3.08	0.6	2.1	0.000	0.005	-3.09	-3.11
SW-64	5/6/2026 9:16:27 AM	79.1	-6.42	-6.42	2.3	0.6	0.007	0.000	-6.57	-6.54
SW-64	5/5/2026 9:04:48 AM	64.0	-8.12	-8.17	3.9	6.5	0.018	0.050	-8.14	-8.13

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
SW-64	5/4/2026 8:34:50 AM	66.8	-8.00	-8.00	27.5	27.5	0.910	0.910	-7.94	-7.94
SW-64	5/1/2026 8:47:28 AM	76.7	-8.11	-8.11	81.5	81.7	8.253	8.308	-8.39	-8.10
SW-65	5/11/2026 9:04:20 AM	87.2	-10.99	-10.91	0.9	0.8	0.005	0.003	-12.38	
SW-66	5/15/2026 9:29:15 AM	86.2	-7.79	-7.80	0.0	0.0	7.831	7.879		
SW-66	5/15/2026 9:27:52 AM	86.3	-8.19	-8.11	0.0	0.0	8.302	7.972		
SW-68	5/22/2026 6:45:28 AM	52.3	-0.17	-0.17	12.5	12.3	0.179	0.174	0.00	0.00
SW-68	5/21/2026 7:08:10 AM	63.5	-0.13	-0.13	2.5	1.6	0.007	0.003	0.00	0.00
SW-68	5/20/2026 7:47:12 AM	72.4	0.00	0.00	2.4	2.8	0.007	0.009	0.01	0.03
SW-68	5/19/2026 9:34:10 AM	88.4	-0.19	-0.19	1.0	0.0	0.001	0.000	0.34	0.34
SW-68	5/18/2026 9:11:53 AM	78.8	-4.71	-4.70	5.3	1.6	0.035	0.003	-4.28	-4.29
SW-68	5/15/2026 8:34:05 AM	72.3	-6.91	-6.95	1.6	3.4	0.003	0.014	-7.05	-7.10
SW-68	5/14/2026 8:50:57 AM	80.7	-0.02	-0.02	3.3	3.3	0.013	0.013	0.36	0.34
SW-68	5/13/2026 8:31:50 AM	68.7	-7.77	-7.77	0.0	1.9	0.000	0.004	-7.74	-7.78
SW-68	5/12/2026 9:37:18 AM	81.4	-6.46	-6.59	5.6	10.7	0.038	0.141	-6.51	-6.46
SW-68	5/11/2026 8:45:53 AM	84.2	-4.19	-4.21	6.4	2.9	0.049	0.010	-4.03	-4.01
SW-68	5/8/2026 10:04:26 AM	82.7	-3.32	-3.33	8.3	7.9	0.084	0.076	-3.25	-3.35
SW-68	5/7/2026 9:24:55 AM	86.5	-3.27	-3.30	3.8	3.1	0.018	0.012	-3.15	-3.11
SW-68	5/6/2026 9:12:20 AM	79.1	-7.28	-7.43	6.8	7.2	0.056	0.064	-7.42	-7.41
SW-68	5/5/2026 8:59:48 AM	68.1	-8.07	-8.07	5.4	2.4	0.036	0.007	-8.08	-8.08
SW-68	5/4/2026 8:39:10 AM	70.5	-8.11	-8.11	29.2	29.1	1.033	1.025	-7.89	-7.91
SW-68	5/1/2026 8:43:53 AM	75.7	-8.02	-8.03	81.2	81.2	8.191	8.199	-8.16	-8.15
SW-7	5/1/2026 7:54:58 AM	66.9	-0.20	-0.20	13.2	13.0	0.204	0.198	-8.46	-8.46
SW-70	5/4/2026 9:33:46 AM	72.6	-7.74	-7.74	62.4	62.1	0.902	0.895	-7.58	-7.58
SW-71	5/6/2026 8:31:08 AM	73.0	-5.74	-5.70	2.1	1.9	0.435	0.356	-10.24	
SW-71	5/6/2026 8:23:03 AM	73.2	-5.74	-5.67	1.9	2.0	0.386	0.397	-9.33	
SW-72	5/6/2026 9:25:28 AM	79.8	-1.36	-1.28	0.0	0.0	0.030	0.026	-3.64	
SW-80	5/12/2026 1:23:15 PM	82.8	-6.04	-6.04	1.4	1.5	0.040	0.046	-8.61	-8.54
SW-9	5/4/2026 9:35:40 AM	81.4	-7.72	-7.68	66.2	65.8	1.033	1.021	-7.59	-7.59
TC-1961C	5/4/2026 11:11:27 AM	93.9	-0.50	-0.35	4.9	4.6	0.053	0.047	-14.09	-14.28
TC-1961E	5/4/2026 10:42:18 AM	114.6	-1.72	-1.69	8.9	10.5	0.182	0.254	-14.36	-14.09
TC-2174	5/26/2026 9:02:15 AM	183.2	-1.18	-1.20			3.904	4.034	-1.61	-1.68
TC-2174	5/18/2026 9:25:30 AM	182.9	-0.04	-0.07			3.111	3.007	-0.46	-0.55

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
TC-2174	5/18/2026 9:25:00 AM									
TC-2174	5/18/2026 9:24:46 AM	182.9	0.91	0.00			2.560	3.348	-1.42	-0.49
TC-2174	5/12/2026 9:30:00 AM									
TC-2174	5/12/2026 9:24:37 AM	183.1	-1.35	-1.33			4.089	4.047	-4.98	-4.61
TC-2174	5/5/2026 8:40:00 AM									
TC-2174	5/5/2026 8:40:00 AM									
TC-2174	5/5/2026 8:34:39 AM	182.7	-2.63	-2.45			6.162	6.051	-5.01	-5.36
VL-02	5/28/2026 3:26:30 PM	91.0	-14.89	-14.86	14.3	14.9	0.251	0.274	-14.61	-15.20
WTD-01	5/21/2026 5:51:51 AM	140.0	-3.65	-3.65			3.622	3.618	-7.40	-7.36
WTD-01	5/21/2026 5:51:17 AM	139.9	-3.71	-3.70			3.709	3.695	-7.24	-7.27
WTD-01	5/1/2026 7:48:21 AM	141.4	-4.94	-4.93			4.892	4.881	-8.39	-8.34
WTD-01	5/1/2026 7:47:42 AM	141.3	-4.93	-4.93			4.887	4.884	-8.41	-8.41
WTD-02	5/21/2026 5:58:44 AM	155.4	-3.90	-3.89			3.865	3.866	-3.76	-3.79
WTD-02	5/21/2026 5:58:19 AM	155.3	-3.90	-3.91			3.874	3.872	-3.74	-3.74
WTD-02	5/13/2026 1:51:34 PM	154.8	-3.63	-3.62			3.635	3.620	0.00	0.00
WTD-02	5/13/2026 1:50:30 PM	154.8	-3.61	-3.61			3.587	3.588	0.00	0.00
WTD-02	5/6/2026 1:50:52 PM	156.2	-1.76	-1.79			1.739	1.758	0.00	0.00
WTD-02	5/6/2026 1:50:00 PM									
WTD-02	5/6/2026 1:50:00 PM									
WTD-02	5/6/2026 1:49:41 PM	82.9	-1.74	-1.69			1.726	1.647	-0.01	0.00
WTD-03	5/21/2026 6:07:17 AM	112.5	-4.20	-4.20			4.169	4.164	-4.14	-4.11
WTD-03	5/21/2026 6:06:19 AM	112.5	-4.20	-4.20			4.173	4.177	-4.27	-4.26
WTD-03	5/1/2026 8:09:37 AM	119.0	-5.11	-5.11			5.367	5.385	-5.41	-5.36
WTD-03	5/1/2026 8:08:56 AM	118.8	-5.21	-5.11			5.430	5.385	-5.36	-5.36
WTD-04	5/21/2026 6:19:17 AM	60.1	-3.87	-3.87			3.842	3.855	-5.38	-5.43
WTD-04	5/21/2026 6:16:55 AM	60.1	-3.87	-3.87			3.843	3.842	-5.43	-5.38
WTD-04	5/1/2026 8:15:02 AM	64.4	-4.77	-4.77			4.990	4.996	-6.39	-6.37
WTD-04	5/1/2026 8:14:32 AM	64.0	-4.97	-4.98			4.984	4.978	-6.40	-6.39
WTD-05	5/21/2026 6:13:19 AM	67.4	-3.87	-3.87			3.840	3.840	-5.33	-5.34
WTD-05	5/21/2026 6:12:45 AM	67.4	-3.87	-3.87			3.845	3.843	-5.32	-5.33
WTD-05	5/1/2026 8:12:57 AM	73.8	-4.79	-4.77			4.946	4.995	-6.23	-6.23
WTD-05	5/1/2026 8:12:16 AM	72.8	-4.79	-4.78			4.928	4.951	-6.28	-6.22
WTD-06	5/21/2026 6:21:19 AM	110.8	-3.94	-3.94			3.897	3.899	-5.47	-5.51
WTD-06	5/21/2026 6:20:59 AM	110.8	-3.92	-3.93			3.892	3.897	-5.47	-5.51

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]
WTD-06	5/1/2026 8:20:07 AM	117.1	-4.96	-4.90			5.164	5.090	-6.79	-6.90
WTD-06	5/1/2026 8:17:56 AM	116.7	-5.00	-4.86			5.105	5.023	-6.85	-6.71
WTD-07	5/21/2026 6:25:15 AM	67.4	-5.62	-5.62			5.578	5.593	-5.60	-5.57
WTD-07	5/21/2026 6:24:46 AM	67.5	-5.60	-5.61			5.498	5.525	-5.41	-5.41
WTD-07	5/1/2026 8:22:32 AM	65.8	-6.76	-6.76			6.974	6.986	-6.74	-6.73
WTD-07	5/1/2026 8:21:58 AM	65.7	-6.76	-6.76			6.929	6.928	-6.72	-6.73
WTD-10	5/21/2026 7:17:44 AM	110.2	-3.99	-3.99			3.974	3.948	-6.30	-6.23
WTD-10	5/21/2026 7:17:13 AM	110.2	-4.00	-4.01			3.968	3.950	-6.31	-6.23
WTD-10	5/4/2026 8:01:28 AM	106.3	-4.77	-4.77			5.005	5.018	-7.28	-7.26
WTD-10	5/4/2026 8:00:56 AM	106.3	-4.77	-4.77			5.032	5.018	-7.24	-7.11

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
A-01	5/15/2026 8:51:04 AM	28.78	1198	34.4312780	-118.6438358	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
A-02	5/11/2026 7:44:04 AM	28.75	1184	34.4315883	-118.6433073	No Flow Measurement,No Adjustment Made
A-03	5/11/2026 7:56:41 AM	28.74	1171	34.4318593	-118.6428253	No Flow Measurement
A-04	5/11/2026 8:06:12 AM	28.74	1184	34.4321948	-118.6422235	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,Audible Flow,No Flow Measurement
A-05	5/11/2026 8:01:26 AM	28.74	1165	34.4324613	-118.6416893	No Flow Measurement
B-01	5/11/2026 10:37:28 AM	28.73				
B-02R	5/11/2026 10:34:40 AM	28.72	1191	34.4333675	-118.6396157	
B-03R	5/11/2026 10:04:48 AM	28.73	1211	34.4338248	-118.6388093	
B-05	5/11/2026 10:25:34 AM	28.73	1253	34.4336600	-118.6383268	
B-06	5/11/2026 10:19:19 AM	28.73	1217	34.4340717	-118.6378192	
B-07R	5/11/2026 9:31:57 AM	28.73	1188	34.4342770	-118.6374250	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
B-08	5/11/2026 10:15:29 AM	28.73	1181	34.4338193	-118.6373255	No Flow Measurement
B-09	5/11/2026 9:37:05 AM	28.74	1191	34.4342012	-118.6370725	
B-10	5/11/2026 9:24:54 AM	28.73	1224	34.4339978	-118.6365650	No Flow Measurement
B-11	5/29/2026 3:03:30 PM	28.81	1150	34.4348343	-118.6369015	
B-12	5/11/2026 10:00:30 AM	28.73	1211	34.4340375	-118.6385235	
B-13	5/11/2026 9:49:42 AM	28.73	1211	34.4344310	-118.6379303	
B-14	5/29/2026 3:07:12 PM	28.82	1133	34.4349390	-118.6370690	
C-03	5/11/2026 7:49:46 AM	28.77	1198	34.4313543	-118.6435513	No Flow Measurement,No Adjustment Made
C-07	5/1/2026 3:11:09 PM	28.64	1190	34.4326408	-118.6414288	Valve Adjustment:Reconnected this Date,Valve 100% Open
C-08	5/8/2026 1:03:42 PM	28.74	1198	34.4336587	-118.6408628	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum
C-10	5/11/2026 9:07:51 AM	28.73	1145	34.4347607	-118.6411188	No Flow Measurement,No Adjustment Made
C-11	5/11/2026 8:38:28 AM	28.72	1198	34.4352575	-118.6413622	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
C-12	5/29/2026 12:20:26 PM	28.74	1225	34.4359885	-118.6408897	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum
C-12	5/11/2026 1:57:43 PM	28.67	1235	34.4359890	-118.6408977	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
C-15	5/11/2026 2:07:31 PM	28.67	1223	34.4362840	-118.6410517	Valve Adjustment:Valve 100% Open
C-17B	5/12/2026 10:45:10 AM	28.7	1226	34.4373525	-118.6419448	
C-18	5/12/2026 1:08:06 PM	28.72	1230	34.4379865	-118.6426292	
C-19	5/12/2026 12:49:10 PM	28.72	1226	34.4375570	-118.6421588	
C-20	5/12/2026 12:57:51 PM	28.72	1234	34.4377843	-118.6424115	
C-23	5/12/2026 11:00:46 AM	28.71	1213	34.4370875	-118.6416698	Well Repairs:Sample Port
C-24	5/15/2026 9:17:41 AM	28.74	1201	34.4375270	-118.6421700	
C-25	5/11/2026 2:14:04 PM	28.67	1235	34.4371358	-118.6416700	Valve Adjustment:Valve 100% Open

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
C-26	5/29/2026 12:46:54 PM	28.74	1227	34.4366562	-118.6412765	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum
C-26	5/15/2026 9:07:37 AM	28.75	1230	34.4366148	-118.6412708	
C-27	5/11/2026 2:04:38 PM	28.67	1238	34.4362008	-118.6409862	Valve Adjustment:Increased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
C-28	5/29/2026 12:16:57 PM	28.72	1239	34.4354523	-118.6413823	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum
C-28	5/11/2026 8:35:54 AM	28.71	1247	34.4354155	-118.6413187	No Adjustment Made
C-29	5/11/2026 8:54:46 AM	28.73	1270	34.4347552	-118.6411677	Audible Flow,No Flow Measurement
C-30	5/11/2026 8:49:08 AM	28.7	1224	34.4342760	-118.6413048	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-02	5/11/2026 8:21:58 AM	28.64	1240	34.4335742	-118.6413765	No Adjustment Made
CV-03	5/11/2026 8:18:37 AM	28.7	1234	34.4333008	-118.6414685	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-04	5/11/2026 8:14:52 AM	28.7	1207	34.4331483	-118.6416422	Increased Flow/Vacuum
CV-05	5/8/2026 12:41:33 PM	28.74	1203	34.4328332	-118.6422098	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Valve 100% Open
CV-06	5/12/2026 8:03:49 AM	28.69	1247	34.4326172	-118.6428073	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-108-52	5/19/2026 1:02:47 PM	28.67	1280	34.4334190	-118.6506818	Valve Adjustment:Barely Open,Surging Liquid in Header
CV-108-52	5/18/2026 11:07:16 AM					
CV-108-52	5/6/2026 8:30:00 AM					Air Tech Lab
CV-108-52	5/1/2026 10:29:07 AM	28.65	1285	34.4334083	-118.6506870	Valve Adjustment:Barely Open
CV-113	5/26/2026 2:01:29 PM	28.39	1330	34.4369985	-118.6467360	Valve Adjustment:Barely Open
CV-113	5/15/2026 9:28:02 AM	28.59	1344	34.4369835	-118.6467223	
CV-113	5/4/2026 7:50:00 AM					Air Tech Lab; [User entered 2.4%]
CV-114	5/26/2026 8:58:28 AM	28.47	1362	34.4367389	-118.6476076	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-114	5/18/2026 9:20:17 AM	28.52	1365	34.4367361	-118.6476114	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down
CV-114	5/18/2026 9:20:00 AM					AtmAA
CV-114	5/18/2026 9:17:57 AM	28.51	1365	34.4367354	-118.6476131	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum,Valve 100% Open,Reduce Sys. Vac. - Flare Down
CV-114	5/12/2026 9:25:00 AM					AtmAA
CV-114	5/12/2026 9:22:16 AM	28.55	1386	34.4367167	-118.6476261	Valve Adjustment:High Temp
CV-114	5/5/2026 8:35:00 AM					AtmAA
CV-114	5/5/2026 8:35:00 AM					AtmAA; [User entered 16.18%]
CV-114	5/5/2026 8:32:18 AM	28.53	1336	34.4367155	-118.6476129	Valve Adjustment:No Flow Measurement,High Temp
CV-114	5/4/2026 8:05:00 AM					Air Tech Lab; [User entered 0.28%]
CV-1424	5/1/2026 11:22:59 AM	28.45	1358	34.4350948	-118.6450823	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-1532A	5/28/2026 8:54:46 AM	28.6	1277	34.4338675	-118.6508340	Valve Adjustment:Barely Open;Well Comment:System surging
CV-1532A	5/13/2026 1:09:52 PM	28.61	1257	34.4339078	-118.6507662	
CV-1532A	5/13/2026 1:07:32 PM	28.68	1289	34.4339437	-118.6508210	
CV-1532A	5/11/2026 8:15:00 AM					Air Tech Lab
CV-1532A	5/11/2026 8:15:00 AM					Air Tech Lab; [User entered 6.1%]
CV-1534A-PLR	5/28/2026 1:23:27 PM	28.62	1290	34.4336179	-118.6508080	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Surging Liquid in Header
CV-1534A-PLR	5/28/2026 1:20:34 PM	28.62	1283	34.4336241	-118.6507961	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Surging Liquid in Header
CV-1534A-PLR	5/20/2026 9:03:59 AM	28.63	1283	34.4336324	-118.6508042	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Surging Liquid in Well (Watered In)
CV-1534A-PLR	5/13/2026 9:42:40 AM	28.77	1291	34.4336253	-118.6507774	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In)
CV-1534A-PLR	5/6/2026 10:03:56 AM	28.73	1286	34.4336278	-118.6507907	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Well (Watered In)
CV-1534A-PLR	5/6/2026 9:55:00 AM					AtmAA
CV-1534A-PLR	5/6/2026 9:55:00 AM					AtmAA; [User entered 12.34%]
CV-1535	5/19/2026 12:55:31 PM	28.63	1298	34.4333412	-118.6503412	Valve Adjustment:Barely Open
CV-1535	5/11/2026 8:25:00 AM					Air Tech Lab
CV-1535	5/11/2026 8:25:00 AM					Air Tech Lab; [User entered 0.98%]
CV-1535	5/1/2026 10:31:55 AM	28.59	1318	34.4333060	-118.6503550	Valve Adjustment:Audible Flow;Well Condition:Good
CV-1601D	5/22/2026 10:03:49 AM	28.43	1322	34.4311242	-118.6486432	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-1601D	5/4/2026 10:02:19 AM	28.54	1296	34.4311578	-118.6487380	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-1601S	5/22/2026 10:00:47 AM	28.58	1316	34.4311025	-118.6486852	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-1601S	5/4/2026 9:59:23 AM	28.53	1329	34.4311523	-118.6486630	
CV-1604	5/4/2026 11:02:38 AM	28.63	1279	34.4321760	-118.6450297	Valve Adjustment:Decreased Flow/Vacuum
CV-1701D	5/8/2026 1:23:50 PM	28.63	1283	34.4335962	-118.6433443	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAC
CV-1701D	5/8/2026 1:22:18 PM	28.63	1280	34.4335972	-118.6433448	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum;Well Condition:Fair;Well Repairs:Flex Hose
CV-1701D	5/7/2026 11:12:23 AM	28.69	1276	34.4335535	-118.6433258	Reduced System Vacuum
CV-1701S	5/7/2026 11:16:55 AM	28.68	1214	34.4335183	-118.6433695	Reduced System Vacuum,High Temp,NSPS/EG CAI
CV-1701S	5/7/2026 11:15:22 AM	28.68	1260	34.4335477	-118.6433292	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-1901	5/19/2026 10:20:41 AM	28.63	1338	34.4357227	-118.6508190	Valve Adjustment:NSPS/EG CAC
CV-1901	5/19/2026 10:18:56 AM	28.63	1336	34.4357087	-118.6508223	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-1901	5/12/2026 10:20:03 AM	28.61	1325	34.4357342	-118.6508607	NSPS/EG CAC,No Adjustment Made
CV-1901	5/12/2026 10:17:30 AM	28.61	1335	34.4357073	-118.6506798	NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-1902A	5/28/2026 8:49:43 AM	28.58	1315	34.4346018	-118.6502966	Valve Adjustment:NSPS/EG CAI,High Temp
CV-1902A	5/20/2026 8:10:11 AM	28.59	1329	34.4346010	-118.6503184	Valve Adjustment:No Flow Measurement,High Temp
CV-1902A	5/14/2026 1:48:17 PM	28.63	1311	34.4346105	-118.6503170	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum
CV-1902A	5/11/2026 1:48:31 PM	28.59	1312	34.4346165	-118.6503003	Valve Adjustment:No Flow Measurement,High Temp
CV-1902A	5/11/2026 7:55:00 AM					Air Tech Lab
CV-1902A	5/11/2026 7:55:00 AM					Air Tech Lab; [User entered 19%]
CV-1902A	5/6/2026 9:06:28 AM	28.67	1330	34.4345924	-118.6503030	Valve Adjustment:No Flow Measurement,High Temp
CV-1902A	5/6/2026 9:05:00 AM					AtmAA
CV-1902A	5/6/2026 9:05:00 AM					AtmAA; [User entered 16.105%]
CV-1905	5/6/2026 12:45:38 PM	28.63	1393	34.4334975	-118.6460023	Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum
CV-1905	5/6/2026 10:44:14 AM	28.56	1348	34.4334800	-118.6459913	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-2001	5/20/2026 9:55:23 AM	28.63	1259	34.4322752	-118.6505602	Valve Adjustment:Barely Open
CV-2001	5/12/2026 8:45:06 AM	28.62	1289	34.4323085	-118.6505502	No Adjustment Made
CV-2001	5/6/2026 7:50:00 AM					Air Tech Lab
CV-2001	5/6/2026 7:50:00 AM					Air Tech Lab; [User entered 8.2%]
CV-2001	5/1/2026 10:12:38 AM	28.64	1273	34.4322787	-118.6505635	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2002	5/28/2026 10:15:53 AM	28.64	1276	34.4327983	-118.6511690	Valve Adjustment:NSPS/EG CAC,High Temp
CV-2002	5/28/2026 10:12:21 AM	28.64	1273	34.4328116	-118.6511672	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum,Plugged/Pinched Suspected;Well Comment:Pinched in the vacuum line
CV-2002	5/20/2026 9:42:31 AM	28.67	1275	34.4328174	-118.6511816	Valve Adjustment:High Temp
CV-2002	5/20/2026 9:41:05 AM	28.66	1274	34.4328116	-118.6511773	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-2002	5/13/2026 10:09:19 AM	28.8	1271	34.4328016	-118.6511663	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	5/11/2026 8:10:00 AM					Air Tech Lab
CV-2002	5/11/2026 8:10:00 AM					Air Tech Lab; [User entered 8.3%]
CV-2002	5/6/2026 1:05:00 PM					AtmAA
CV-2002	5/6/2026 1:05:00 PM					AtmAA; [User entered 13.72%]
CV-2002	5/6/2026 1:02:03 PM	28.7	1266	34.4327936	-118.6511792	Valve Adjustment:High Temp,Surging Liquid in Well (Watered In)
CV-2003	5/19/2026 1:11:41 PM	28.67	1280	34.4334358	-118.6507350	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-2003	5/19/2026 1:06:11 PM	28.67	1278	34.4334113	-118.6507280	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-2003	5/1/2026 10:27:07 AM	28.63	1285	34.4334052	-118.6507277	Valve Adjustment:Barely Open
CV-2006	5/28/2026 8:42:46 AM	28.58	1327	34.4352391	-118.6506276	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2006	5/20/2026 8:18:51 AM	28.58	1318	34.4352464	-118.6506517	Valve Adjustment:No Flow Measurement,High Temp
CV-2006	5/14/2026 2:04:55 PM	28.53	1293	34.4352200	-118.6507065	
CV-2006	5/14/2026 2:03:40 PM	28.53	1227	34.4351588	-118.6506133	High Temp
CV-2006	5/11/2026 1:55:37 PM	28.59	1326	34.4352436	-118.6506369	Valve Adjustment:No Flow Measurement,High Temp,Reduce Sys. Vac. - Flare Down
CV-2006	5/6/2026 9:20:00 AM					AtmAA
CV-2006	5/6/2026 9:20:00 AM					AtmAA; [User entered 17.34%]
CV-2006	5/6/2026 9:17:48 AM	28.66	1323	34.4352251	-118.6506474	Valve Adjustment:Orifice Plate Changed (See OP Log),High Temp
CV-2007	5/20/2026 2:00:34 PM	28.41	1371	34.4361610	-118.6469898	Valve Adjustment:Barely Open
CV-2007	5/8/2026 9:48:29 AM	28.59	1398	34.4360997	-118.6469230	Reduced System Vacuum
CV-2007	5/4/2026 8:10:00 AM					Air Tech Lab; [User entered 5.9%]
CV-2008	5/11/2026 2:03:03 PM	28.48	1411	34.4362800	-118.6463063	
CV-2009	5/8/2026 9:02:48 AM	28.6	1365	34.4362193	-118.6452257	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-2009	5/8/2026 9:00:33 AM	28.6	1371	34.4363270	-118.6453092	NSPS/EG CAI,High Temp,Positive Static Press.,Reduced System Vacuum
CV-2009A	5/11/2026 1:51:42 PM	28.47	1404	34.4359782	-118.6452695	
CV-2010	5/4/2026 1:15:27 PM	28.58	1352	34.4356558	-118.6435827	Valve Adjustment:Decreased Flow/Vacuum
CV-2010A	5/21/2026 10:29:08 AM	28.51	1360	34.4357273	-118.6436773	Valve Adjustment:Audible Flow
CV-2010A	5/14/2026 9:40:00 AM					AtmAA
CV-2010A	5/14/2026 9:38:44 AM	28.58	1361	34.4357452	-118.6436314	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum
CV-2010A	5/5/2026 1:03:57 PM	28.52	1362	34.4357605	-118.6436593	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp
CV-2010A	5/5/2026 1:03:17 PM	28.52	1356	34.4357552	-118.6436610	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Increased Flow/Vacuum
CV-2010A	5/4/2026 1:29:04 PM	28.54	1369	34.4357562	-118.6436638	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-2010A	5/4/2026 1:27:58 PM	28.54	1366	34.4357503	-118.6436622	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-2010A	5/4/2026 1:26:56 PM	28.54	1363	34.4357462	-118.6436527	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2011	5/11/2026 3:39:24 PM	28.53	1381	34.4341870	-118.6435198	
CV-2011	5/11/2026 3:38:18 PM	28.53	1345	34.4342182	-118.6434168	NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-2011A	5/28/2026 8:38:45 AM	28.55	1334	34.4354559	-118.6507572	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2011A	5/27/2026 3:15:12 PM	28.43	1333	34.4345451	-118.6431606	Valve Adjustment:High Temp
CV-2011A	5/27/2026 3:14:19 PM	28.45	1332	34.4345381	-118.6431537	Valve Adjustment:High Temp,Increased Flow/Vacuum

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-2011A	5/21/2026 9:16:00 AM	28.54	1340	34.4345424	-118.6431436	Valve Adjustment:High Temp
CV-2011A	5/20/2026 8:33:37 AM	28.57	1318	34.4345460	-118.6431632	Valve Adjustment:High Temp,Barely Open;Well Comment:pump turned off;Well Condition:Lorentz Pump Installed
CV-2011A	5/20/2026 8:30:13 AM	28.57	1345	34.4345285	-118.6431620	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Comment:Lorentz pump activated;Well Condition:Lorentz Pump Installed;Well Repairs:Sample Port
CV-2011A	5/14/2026 9:40:27 AM	28.62	1362	34.4357199	-118.6436604	Valve Comment:Lorentz pump offline due to limber expansion;Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2011A	5/11/2026 10:58:37 AM	28.59	1328	34.4345080	-118.6431584	Valve Adjustment:High Temp
CV-2011A	5/4/2026 8:20:00 AM					AtmAA
CV-2011A	5/4/2026 8:20:00 AM					AtmAA; [User entered 19.93%]
CV-2011A	5/4/2026 8:19:12 AM	28.59	1322	34.4345241	-118.6431850	Valve Adjustment:High Temp
CV-2012	5/11/2026 3:24:22 PM	28.51	1345	34.4351362	-118.6432447	
CV-2012	5/11/2026 3:23:03 PM	28.51	1332	34.4351127	-118.6433065	NSPS/EG CAI,High Temp
CV-2201-PLR	5/19/2026 11:02:27 AM	28.71	1348	34.4355533	-118.6488568	Valve Adjustment:Barely Open,Surging Liquid in Header
CV-2201-PLR	5/19/2026 10:46:55 AM	28.71	1344	34.4355575	-118.6488530	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header
CV-2201-PLR	5/13/2026 1:54:50 PM	28.75	1354	34.4355558	-118.6488543	
CV-2201-PLR	5/13/2026 1:53:35 PM	28.74	1352	34.4355668	-118.6488530	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header
CV-2204-PLR	5/26/2026 1:23:17 PM	28.43	1365	34.4357832	-118.6474838	Valve Adjustment:No Flow Measurement,High Temp
CV-2204-PLR	5/18/2026 11:00:00 AM					AtmAA
CV-2204-PLR	5/18/2026 10:51:06 AM	28.51	1373	34.4357649	-118.6474788	Valve Adjustment:No Flow Measurement,High Temp
CV-2204-PLR	5/12/2026 10:45:00 AM					AtmAA
CV-2204-PLR	5/12/2026 10:44:05 AM	28.55	1348	34.4357681	-118.6474664	Valve Adjustment:No Flow Measurement,High Temp
CV-2204-PLR	5/5/2026 9:48:20 AM	28.51	1362	34.4357712	-118.6474761	Valve Adjustment:No Flow Measurement,High Temp
CV-2204-PLR	5/5/2026 9:45:00 AM					AtmAA
CV-2204-PLR	5/5/2026 9:45:00 AM					AtmAA; [User entered 13.79%]
CV-2205	5/1/2026 2:09:09 PM	28.48	1374	34.4342773	-118.6441135	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Fair
CV-2207	5/11/2026 1:42:35 PM	28.65	1424	34.4360663	-118.6441428	
CV-2207	5/11/2026 1:19:38 PM	28.52	1384	34.4359988	-118.6442250	Valve Comment:well too tall for system
CV-2208A	5/11/2026 11:49:32 AM	28.53	1312	34.4365748	-118.6449385	
CV-2208A	5/11/2026 11:47:10 AM	28.53	1309	34.4364772	-118.6449732	High Temp
CV-2301	5/27/2026 10:38:04 AM	28.43	1342	34.4334932	-118.6492167	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	5/27/2026 10:36:57 AM	28.43	1341	34.4334943	-118.6492188	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-2301	5/19/2026 10:16:23 AM	28.65	1343	34.4334867	-118.6492477	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	5/19/2026 10:15:36 AM	28.63	1343	34.4334866	-118.6492474	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2301	5/19/2026 10:15:00 AM					AtmAA
CV-2301	5/14/2026 11:20:00 AM					AtmAA
CV-2301	5/14/2026 10:53:50 AM	28.71	1355	34.4335122	-118.6492387	
CV-2301	5/14/2026 10:52:08 AM	28.71	1357	34.4335168	-118.6492318	Valve Comment:Valve too high to adjust;Valve Adjustment:NSPS/EG CAI,High Temp;Well Comment:No Pump
CV-2301	5/7/2026 7:55:00 AM					Air Tech Lab
CV-2301	5/7/2026 7:55:00 AM					Air Tech Lab; [User entered 15%]
CV-2302	5/22/2026 3:57:06 PM	30	1348	34.4340720	-118.6492185	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2302	5/7/2026 8:05:00 AM					Air Tech Lab
CV-2302	5/7/2026 8:05:00 AM					Air Tech Lab; [User entered 5.3%]
CV-2302	5/4/2026 9:06:38 AM	28.56	1342	34.4340388	-118.6492105	Valve Adjustment:Valve 100% Open;Well Comment:valve stuck open
CV-2303	5/27/2026 9:02:45 AM	28.4	1356	34.4353757	-118.6496996	Valve Adjustment:No Flow Measurement,High Temp
CV-2303	5/19/2026 8:40:00 AM					AtmAA
CV-2303	5/19/2026 8:36:23 AM	28.59	1354	34.4353850	-118.6496840	Valve Adjustment:No Flow Measurement,High Temp
CV-2303	5/13/2026 2:13:55 PM	28.66	1372	34.4353776	-118.6497053	Valve Adjustment:No Flow Measurement,High Temp
CV-2303	5/12/2026 8:30:00 AM					Air Tech Lab
CV-2303	5/12/2026 8:30:00 AM					Air Tech Lab; [User entered 19%]
CV-2303	5/5/2026 2:25:00 PM					AtmAA
CV-2303	5/5/2026 2:25:00 PM					AtmAA; [User entered 16.58%]
CV-2303	5/5/2026 2:21:44 PM	28.51	1356	34.4353789	-118.6497006	Valve Adjustment:No Flow Measurement,High Temp
CV-2304	5/19/2026 9:15:00 AM					AtmAA
CV-2304	5/19/2026 9:14:49 AM	28.64	1339	34.4345563	-118.6487464	Valve Adjustment:No Flow Measurement,High Temp
CV-2304	5/13/2026 3:03:41 PM	28.67	1341	34.4345633	-118.6487399	Valve Adjustment:No Flow Measurement,High Temp
CV-2304	5/13/2026 3:02:59 PM	28.67	1341	34.4345654	-118.6487425	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2304	5/8/2026 12:51:34 PM	28.56	1309	34.4345933	-118.6487710	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2304	5/8/2026 12:50:06 PM	28.56	1323	34.4345802	-118.6487640	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2304	5/6/2026 3:00:04 PM	28.59	1344	34.4345532	-118.6487415	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Surging Liquid in Header
CV-2304	5/6/2026 3:00:00 PM					AtmAA
CV-2304	5/6/2026 3:00:00 PM					AtmAA; [User entered 18.06%]

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-2304	5/6/2026 2:59:41 PM	28.59	1344	34.4345533	-118.6487415	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Surging Liquid in Header
CV-2305	5/27/2026 2:24:19 PM	28.39	1389	34.4352222	-118.6465334	Valve Adjustment:High Temp,Positive Static Press.,Surging Liquid in Header
CV-2305	5/27/2026 2:23:44 PM	28.39	1389	34.4352225	-118.6465340	Valve Adjustment:High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Header
CV-2305	5/19/2026 1:20:00 PM					AtmAA
CV-2305	5/19/2026 1:19:18 PM	28.58	1393	34.4352347	-118.6465351	Valve Adjustment:High Temp,Valve 100% Open,Surging Liquid in Header
CV-2305	5/14/2026 10:11:00 AM					AtmAA
CV-2305	5/14/2026 10:09:35 AM	28.58	1397	34.4352173	-118.6465290	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2305	5/12/2026 8:10:00 AM					Air Tech Lab
CV-2305	5/12/2026 8:10:00 AM					Air Tech Lab; [User entered 8.2%]
CV-2305	5/4/2026 8:50:00 AM	28.53	1383	34.4352262	-118.6465321	Valve Adjustment:High Temp
CV-2306	5/26/2026 1:28:47 PM	28.42	1364	34.4360980	-118.6478160	Valve Adjustment:No Flow Measurement,High Temp
CV-2306	5/18/2026 11:00:16 AM	28.51	1375	34.4360822	-118.6478078	Valve Adjustment:No Flow Measurement,Surging Liquid in Well (Watered In)
CV-2306	5/18/2026 10:56:22 AM	28.52	1369	34.4360784	-118.6478269	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In)
CV-2306	5/12/2026 10:50:18 AM	28.55	1360	34.4360887	-118.6478090	Valve Adjustment:No Flow Measurement,High Temp
CV-2306	5/12/2026 10:50:00 AM					AtmAA
CV-2306	5/5/2026 9:52:13 AM	28.51	1360	34.4360792	-118.6478149	Valve Adjustment:No Flow Measurement,High Temp
CV-2306	5/5/2026 9:50:00 AM					AtmAA
CV-2306	5/5/2026 9:50:00 AM					AtmAA; [User entered 16.19%]
CV-2308-PLR	5/19/2026 10:58:26 AM	28.71	1348	34.4358842	-118.6488933	
CV-2308-PLR	5/19/2026 10:56:56 AM	28.7	1338	34.4358738	-118.6489067	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In)
CV-2308-PLR	5/13/2026 2:03:12 PM	28.74	1344	34.4358813	-118.6489105	
CV-2308-PLR	5/13/2026 2:01:38 PM	28.74	1351	34.4358865	-118.6489180	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header
CV-2310-PLR	5/27/2026 9:22:17 AM	28.43	1356	34.4353188	-118.6491328	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header
CV-2310-PLR	5/19/2026 8:56:41 AM	28.62	1353	34.4353190	-118.6491396	Valve Comment:Surging in well;Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In);Well Repairs:Surging
CV-2310-PLR	5/19/2026 8:55:00 AM					AtmAA
CV-2310-PLR	5/13/2026 2:22:47 PM	28.66	1365	34.4353284	-118.6491404	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In)
CV-2310-PLR	5/6/2026 2:40:00 PM					AtmAA; [User entered 10.07%]

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-2310-PLR	5/6/2026 2:30:00 PM					AtmAA
CV-2310-PLR	5/6/2026 2:26:12 PM	28.59	1350	34.4353306	-118.6491158	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In)
CV-2310-PLR	5/1/2026 11:45:33 AM	28.52	1368	34.4353170	-118.6491418	Valve Adjustment:NSPS/EG CAI,High Temp,Valve 100% Open,Surging Liquid in Header
CV-2310-PLR	5/1/2026 11:44:42 AM	28.52	1368	34.4353170	-118.6491418	Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Valve 100% Open
CV-2311	5/26/2026 2:01:48 PM	28.41	1376	34.4363199	-118.6498953	Valve Adjustment:No Flow Measurement,High Temp
CV-2311	5/18/2026 2:25:36 PM	28.47	1370	34.4363289	-118.6498830	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Valve 100% Open
CV-2311	5/18/2026 2:25:00 PM					AtmAA
CV-2311	5/18/2026 2:24:18 PM	28.51	1369	34.4363298	-118.6498817	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open
CV-2311	5/12/2026 2:05:46 PM	28.55	1362	34.4363119	-118.6498960	Valve Adjustment:No Flow Measurement,High Temp
CV-2311	5/12/2026 2:03:19 PM	28.55	1360	34.4363189	-118.6498914	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-2311	5/12/2026 2:00:00 PM					AtmAA
CV-2311	5/5/2026 10:25:04 AM	28.51	1371	34.4363116	-118.6498841	Valve Adjustment:No Flow Measurement,High Temp
CV-2311	5/5/2026 10:25:00 AM					AtmAA
CV-2311	5/5/2026 10:25:00 AM					AtmAA; [User entered 13.97%]
CV-2312	5/27/2026 11:01:39 AM	28.41	1373	34.4342058	-118.6473544	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Well (Watered In)
CV-2312	5/19/2026 10:35:25 AM	28.62	1378	34.4342068	-118.6473721	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In)
CV-2312	5/19/2026 10:35:00 AM					AtmAA
CV-2312	5/13/2026 11:08:10 AM	28.67	1377	34.4342078	-118.6473685	Valve Adjustment:NSPS/EG CAI,Audible Flow,No Flow Measurement,High Temp
CV-2312	5/13/2026 9:06:06 AM	28.62	1392	34.4342185	-118.6473540	Valve Comment:ACTIVE PLR;Valve Adjustment:No Flow Measurement,High Temp;Well Comment:Installed sample ports on now hard pipe well
CV-2312	5/13/2026 8:30:00 AM					Air Tech Lab
CV-2312	5/13/2026 8:30:00 AM					Air Tech Lab; [User entered 9.0%]
CV-2312	5/4/2026 10:29:04 AM	28.53	1387	34.4342201	-118.6473614	Valve Comment:Active PLR;Valve Adjustment:No Flow Measurement,High Temp
CV-2312	5/4/2026 10:27:12 AM	28.56	1387	34.4342224	-118.6473626	Valve Comment:Active plr;Valve Adjustment:No Flow Measurement
CV-2312	5/4/2026 10:15:00 AM					AtmAA
CV-2312	5/4/2026 10:15:00 AM					AtmAA; [User entered 12.03%]
CV-2314	5/27/2026 1:46:16 PM	28.38	1386	34.4347126	-118.6466876	Valve Adjustment:High Temp
CV-2314	5/27/2026 1:45:46 PM	28.38	1384	34.4347176	-118.6466899	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-2314	5/19/2026 2:00:00 PM					AtmAA
CV-2314	5/19/2026 1:53:23 PM	28.58	1392	34.4346978	-118.6467182	Valve Adjustment:No Flow Measurement,High Temp
CV-2314	5/14/2026 1:50:56 PM	28.67	1371	34.4347190	-118.6467362	
CV-2314	5/14/2026 1:49:32 PM	28.67	1398	34.4345485	-118.6465587	NSPS/EG CAI,High Temp
CV-2314	5/12/2026 8:05:00 AM					Air Tech Lab
CV-2314	5/12/2026 8:05:00 AM					Air Tech Lab; [User entered 14%]
CV-2314	5/11/2026 10:32:15 AM	28.53	1385	34.4346920	-118.6467260	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header
CV-2314	5/4/2026 9:40:25 AM	28.56	1384	34.4346873	-118.6467112	Valve Adjustment:High Temp
CV-2314	5/4/2026 9:40:00 AM					AtmAA
CV-2314	5/4/2026 9:40:00 AM					AtmAA; [User entered 11%]
CV-2315	5/26/2026 10:35:23 AM	28.43	1397	34.4354928	-118.6472032	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2315	5/19/2026 1:35:00 PM					AtmAA
CV-2315	5/19/2026 1:31:37 PM	28.58	1382	34.4355198	-118.6472000	Valve Comment:Lorentz pump disconnected;Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2315	5/13/2026 1:43:34 PM	28.74	1386	34.4355063	-118.6472078	
CV-2315	5/13/2026 1:42:47 PM	28.71	1380	34.4355038	-118.6471995	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header
CV-2315	5/11/2026 8:41:37 AM	28.51	1388	34.4355101	-118.6471938	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open
CV-2315	5/7/2026 8:30:00 AM					Air Tech Lab
CV-2315	5/7/2026 8:30:00 AM					Air Tech Lab; [User entered 14%]
CV-2315	5/6/2026 3:30:00 PM					AtmAA
CV-2315	5/6/2026 3:30:00 PM					AtmAA; [User entered 8.33%]
CV-2315	5/6/2026 3:27:40 PM	28.55	1379	34.4355252	-118.6472020	Valve Comment:LORENTZ PUMP DISCONECTED;Valve Adjustment:No Flow Measurement,High Temp
CV-2315	5/6/2026 3:25:58 PM	28.55	1379	34.4355265	-118.6471998	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-2316	5/11/2026 1:59:13 PM	28.47	1467	34.4361423	-118.6464818	
CV-2316	5/11/2026 1:57:51 PM	28.47	1463	34.4361048	-118.6464438	High Temp
CV-2319	5/12/2026 8:28:11 AM	28.5	1417	34.4353043	-118.6458277	NSPS/EG CAI,High Temp
CV-2319	5/12/2026 8:26:00 AM	28.5	1427	34.4352733	-118.6458283	
CV-2321	5/27/2026 2:51:44 PM	28.36	1397	34.4346293	-118.6453636	Valve Comment:Lorentz pump on upon arrival;Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2321	5/27/2026 2:50:12 PM	28.36	1396	34.4346303	-118.6453635	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-2321	5/19/2026 1:00:00 PM					AtmAA
CV-2321	5/19/2026 12:59:11 PM	28.58	1395	34.4346305	-118.6453974	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-2321	5/19/2026 12:56:22 PM	28.58	1393	34.4346333	-118.6454210	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-2321	5/11/2026 9:19:14 AM	28.53	1389	34.4346294	-118.6453868	Valve Adjustment:High Temp
CV-2321	5/11/2026 9:16:26 AM	28.52	1388	34.4346288	-118.6453930	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-2321	5/7/2026 9:50:36 AM	28.53	1380	34.4346396	-118.6453619	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-2321	5/7/2026 9:50:00 AM					AtmAA
CV-2321	5/7/2026 9:50:00 AM					AtmAA; [User entered 7.68%]
CV-2321	5/7/2026 9:49:06 AM	28.54	1371	34.4346431	-118.6453347	Valve Adjustment:NSPS/EG CAI,Orifice Plate Changed (See OP Log),No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-2321	5/1/2026 10:23:30 AM	28.44	1434	34.4345733	-118.6453842	
CV-2321	5/1/2026 10:20:34 AM	28.44	1417	34.4346207	-118.6453583	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,NSPS/EG CAI,NSPS/EG CAC,Audible Flow,High Temp,Positive Static Press.,
CV-2322	5/26/2026 9:22:23 AM	28.41	1376	34.4352687	-118.6475092	Valve Adjustment:Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
CV-2322	5/4/2026 1:40:46 PM	28.51	1362	34.4352915	-118.6475316	Valve Adjustment:NSPS/EG CAC,No Flow Measurement
CV-2324	5/6/2026 2:05:45 PM	28.61	1389	34.4345107	-118.6442275	Valve Adjustment:Barely Open
CV-2324	5/1/2026 11:00:44 AM	28.46	1385	34.4345068	-118.6442455	
CV-2326	5/19/2026 10:26:12 AM	28.59	1377	34.4361458	-118.6504698	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2326	5/19/2026 10:25:24 AM	28.59	1375	34.4361437	-118.6504750	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2326	5/1/2026 11:33:29 AM	28.52	1377	34.4361170	-118.6504862	Valve Comment:no system port;Valve Adjustment:Valve 100% Open
CV-2327	5/28/2026 1:44:39 PM	28.55	1368	34.4349085	-118.6479494	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2327	5/20/2026 2:15:58 PM	28.52	1367	34.4348793	-118.6479346	Valve Adjustment:No Flow Measurement,High Temp
CV-2327	5/14/2026 10:00:04 AM	28.62	1368	34.4349305	-118.6479449	Valve Comment:Installed sample port on system side;Valve Adjustment:No Flow Measurement,High Temp
CV-2327	5/14/2026 9:57:08 AM	28.61	1365	34.4349206	-118.6479368	Valve Comment:Going to drill port on system side;Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2327	5/14/2026 9:50:00 AM					AtmAA
CV-2327	5/4/2026 1:23:07 PM	28.52	1364	34.4348905	-118.6479357	Valve Adjustment:High Temp
CV-2327	5/4/2026 1:20:00 PM					AtmAA
CV-2327	5/4/2026 1:20:00 PM					AtmAA; [User entered 4.81%]
CV-2328	5/28/2026 1:37:05 PM	28.53	1369	34.4343299	-118.6483422	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header
CV-2328	5/20/2026 2:06:30 PM	28.53	1355	34.4343211	-118.6483402	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2328	5/20/2026 2:05:13 PM	28.53	1354	34.4343222	-118.6483424	Valve Adjustment:High Temp,Increased Flow/Vacuum
CV-2328	5/11/2026 1:26:04 PM	28.55	1357	34.4343503	-118.6483110	Valve Adjustment:High Temp,Reduce Sys. Vac. - Flare Down

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-2328	5/7/2026 8:15:00 AM					Air Tech Lab
CV-2328	5/7/2026 8:15:00 AM					Air Tech Lab; [User entered 11%]
CV-2328	5/4/2026 1:07:16 PM	28.51	1358	34.4343214	-118.6483639	Valve Adjustment:NSPS/EG CAC,Audible Flow,High Temp
CV-2328	5/4/2026 1:06:42 PM	28.52	1358	34.4343212	-118.6483640	Valve Adjustment:NSPS/EG CAI,Audible Flow,Increased Flow/Vacuum
CV-2328	5/4/2026 1:05:00 PM					AtmAA
CV-2328	5/4/2026 1:05:00 PM					AtmAA; [User entered 5.36%]
CV-2333	5/29/2026 9:43:07 AM	28.66	1362	34.4365133	-118.6473637	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2333	5/26/2026 8:54:11 AM	28.44	1377	34.4365219	-118.6473562	Valve Adjustment:No Flow Measurement,High Temp
CV-2333	5/18/2026 9:15:00 AM					AtmAA
CV-2333	5/18/2026 9:12:06 AM	28.47	1377	34.4365329	-118.6473685	Valve Adjustment:No Flow Measurement,High Temp
CV-2333	5/13/2026 7:40:00 AM					Air Tech Lab
CV-2333	5/13/2026 7:40:00 AM					Air Tech Lab; [User entered 16%]
CV-2333	5/12/2026 9:35:00 AM					AtmAA
CV-2333	5/12/2026 9:28:21 AM	28.52	1381	34.4365299	-118.6473812	Valve Adjustment:No Flow Measurement,High Temp
CV-2333	5/6/2026 9:45:24 AM	28.64	1370	34.4365270	-118.6473628	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2333	5/6/2026 9:44:40 AM	28.64	1366	34.4365335	-118.6473665	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp
CV-2333	5/5/2026 8:30:00 AM					AtmAA
CV-2333	5/5/2026 8:30:00 AM					AtmAA; [User entered 16.01%]
CV-2333	5/5/2026 8:26:49 AM	28.51	1358	34.4365039	-118.6473630	Valve Adjustment:Audible Flow,High Temp
CV-2334	5/26/2026 2:23:32 PM	28.37	1357	34.4366867	-118.6466828	Valve Adjustment:Barely Open
CV-2334	5/13/2026 7:45:00 AM					Air Tech Lab
CV-2334	5/13/2026 7:45:00 AM					Air Tech Lab; [User entered 1.1%]
CV-2335	5/19/2026 10:11:09 AM	28.63	1323	34.4364060	-118.6509820	
CV-2335	5/12/2026 10:45:40 AM	28.6	1329	34.4363798	-118.6509515	No Flow Measurement
CV-2336	5/19/2026 10:14:30 AM	28.63	1354	34.4359915	-118.6508988	
CV-2336	5/12/2026 10:27:38 AM	28.61	1362	34.4359502	-118.6509048	No Flow Measurement
CV-2337	5/20/2026 8:23:36 AM	28.58	1328	34.4354665	-118.6507628	Valve Adjustment:High Temp
CV-2337	5/11/2026 2:00:37 PM	28.59	1327	34.4354710	-118.6507658	Valve Adjustment:No Flow Measurement,High Temp,Reduce Sys. Vac. - Flare Down
CV-2337	5/11/2026 8:05:00 AM					Air Tech Lab
CV-2337	5/11/2026 8:05:00 AM					Air Tech Lab; [User entered 13%]
CV-2337	5/6/2026 9:26:13 AM	28.66	1331	34.4354664	-118.6507838	Valve Adjustment:High Temp,Valve 100% Open
CV-2337	5/6/2026 9:25:00 AM					AtmAA
CV-2337	5/6/2026 9:25:00 AM					AtmAA; [User entered 12.23%]
CV-2338	5/28/2026 8:46:22 AM	28.58	1316	34.4348679	-118.6504584	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2338	5/20/2026 8:15:49 AM	28.6	1327	34.4348565	-118.6504794	Valve Adjustment:No Flow Measurement,High Temp
CV-2338	5/12/2026 10:09:33 AM	28.63	1293	34.4349470	-118.6503273	NSPS/EG CAI,High Temp

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-2338	5/12/2026 10:05:03 AM	28.63	1309	34.4348593	-118.6504292	NSPS/EG CAI,High Temp
CV-2338	5/11/2026 1:52:50 PM	28.6	1315	34.4348633	-118.6504710	Valve Adjustment:High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down
CV-2338	5/11/2026 1:52:06 PM	28.59	1315	34.4348630	-118.6504678	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Valve 100% Open,Reduce Sys. Vac. - Flare Down
CV-2338	5/6/2026 9:15:00 AM					AtmAA
CV-2338	5/6/2026 9:15:00 AM					AtmAA; [User entered 17.41%]
CV-2338	5/6/2026 9:13:21 AM	28.7	1319	34.4348462	-118.6504661	Valve Adjustment:No Flow Measurement,High Temp
CV-2338	5/6/2026 9:12:07 AM	28.7	1321	34.4348350	-118.6504678	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2339	5/29/2026 10:41:08 AM	28.65	1309	34.4341757	-118.6502638	NSPS/EG CAI,High O2
CV-2339	5/29/2026 10:39:26 AM	28.65	1309	34.4341957	-118.6502310	NSPS/EG CAI,High O2
CV-2339	5/14/2026 2:06:48 PM	28.71	1302	34.4342078	-118.6502873	Valve Adjustment:NSPS/EG CAC
CV-2339	5/14/2026 2:04:49 PM	28.72	1305	34.4342002	-118.6502865	Valve Comment:pump off;Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed
CV-2341	5/29/2026 10:30:39 AM	28.65	1319	34.4336450	-118.6501882	
CV-2341	5/14/2026 1:47:09 PM	28.71	1312	34.4336342	-118.6501662	Valve Adjustment:Audible Flow
CV-2341	5/11/2026 7:50:00 AM					Air Tech Lab
CV-2341	5/11/2026 7:50:00 AM					Air Tech Lab; [User entered 9.4%]
CV-2342A-PLR	5/28/2026 1:15:25 PM	28.59	1300	34.4342446	-118.6508500	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2342A-PLR	5/20/2026 9:08:28 AM	28.65	1288	34.4342158	-118.6508593	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2342A-PLR	5/13/2026 9:52:01 AM	28.77	1288	34.4341971	-118.6508514	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2342A-PLR	5/6/2026 10:10:00 AM	28.7	1279	34.4342109	-118.6508438	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2343	5/26/2026 2:33:45 PM	28.49	1293	34.4332428	-118.6507077	Valve Adjustment:NSPS/EG CAC,No Flow Measurement
CV-2343	5/19/2026 2:04:37 PM	28.67	1279	34.4332542	-118.6507110	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2343	5/19/2026 2:03:22 PM	28.67	1276	34.4332587	-118.6507070	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2343	5/6/2026 9:56:02 AM	28.7	1296	34.4332304	-118.6506766	Valve Adjustment:No Flow Measurement,High Temp
CV-2344	5/20/2026 8:51:25 AM	28.62	1301	34.4329875	-118.6504420	Valve Adjustment:NSPS/EG CAC,No Flow Measurement
CV-2344	5/13/2026 9:31:33 AM	28.73	1306	34.4329877	-118.6504541	Valve Adjustment:No Flow Measurement,High Temp
CV-2344	5/13/2026 9:30:38 AM	28.73	1306	34.4329844	-118.6504537	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2344	5/11/2026 7:35:00 AM					Air Tech Lab

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-2344	5/11/2026 7:35:00 AM					Air Tech Lab; [User entered 16%]
CV-2344	5/6/2026 9:52:20 AM	28.7	1303	34.4329593	-118.6504426	Valve Adjustment:No Flow Measurement,High Temp
CV-2344	5/6/2026 9:50:00 AM					AtmAA
CV-2344	5/6/2026 9:50:00 AM					AtmAA; [User entered 13.94%]
CV-2345	5/19/2026 2:17:28 PM	28.63	1302	34.4327340	-118.6501765	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2345	5/19/2026 2:15:18 PM	28.63	1297	34.4327320	-118.6501865	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-2345	5/11/2026 7:30:00 AM					Air Tech Lab
CV-2345	5/11/2026 7:30:00 AM					Air Tech Lab; [User entered 2.8%]
CV-2345	5/1/2026 10:20:11 AM	28.62	1302	34.4327270	-118.6501633	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2345	5/1/2026 10:19:42 AM	28.62	1297	34.4327213	-118.6501513	Valve Adjustment:NSPS/EG CAI,High Temp;Well Repairs:Sample Port
CV-2346	5/28/2026 9:28:07 AM	28.58	1313	34.4326182	-118.6500469	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2346	5/20/2026 8:47:59 AM	28.61	1312	34.4326111	-118.6500938	Valve Adjustment:No Flow Measurement,High Temp
CV-2346	5/13/2026 9:20:50 AM	28.73	1315	34.4325988	-118.6500877	Valve Adjustment:No Flow Measurement,High Temp
CV-2346	5/6/2026 9:47:10 AM	28.7	1322	34.4325727	-118.6500511	Valve Adjustment:No Flow Measurement,High Temp
CV-2346	5/6/2026 9:45:00 AM					AtmAA
CV-2346	5/6/2026 9:45:00 AM					AtmAA; [User entered 11.85%]
CV-2346	5/6/2026 8:25:00 AM					Air Tech Lab
CV-2346	5/6/2026 8:25:00 AM					Air Tech Lab; [User entered 13%]
CV-2346	5/4/2026 1:29:13 PM	28.61	1303	34.4326202	-118.6500715	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2346	5/4/2026 1:27:19 PM	28.6	1304	34.4326235	-118.6500738	Valve Adjustment:NSPS/EG CAC,High Temp;Well Condition:Lorentz Pump Installed
CV-2347	5/20/2026 8:26:42 AM	28.59	1314	34.4323538	-118.6498270	Valve Comment:well needs lowering;Valve Adjustment:Audible Flow
CV-2347	5/6/2026 8:20:00 AM					Air Tech Lab
CV-2347	5/6/2026 8:20:00 AM					Air Tech Lab; [User entered 5.6%]
CV-2347	5/1/2026 10:09:08 AM	28.6	1314	34.4323262	-118.6498575	Valve Adjustment:Decreased Flow/Vacuum
CV-2348	5/20/2026 8:15:56 AM	28.58	1322	34.4321423	-118.6496170	Valve Comment:Well needs lowering;Valve Adjustment:Audible Flow,Surging Liquid in Header
CV-2348	5/13/2026 12:35:31 PM	28.86				
CV-2348	5/6/2026 8:15:00 AM					Air Tech Lab
CV-2348	5/6/2026 8:15:00 AM					Air Tech Lab; [User entered 2.7%]
CV-2349	5/28/2026 10:20:04 AM	28.62	1284	34.4331432	-118.6512616	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2349	5/20/2026 10:27:38 AM	28.66	1261	34.4331426	-118.6512625	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-2349	5/13/2026 10:48:12 AM	28.79	1261	34.4331521	-118.6512689	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-2349	5/7/2026 11:16:23 AM	28.66	1260	34.4331361	-118.6512844	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down
CV-2349	5/7/2026 11:15:19 AM	28.66	1260	34.4331350	-118.6512776	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-2349	5/7/2026 11:15:00 AM					AtmAA
CV-2349	5/7/2026 11:15:00 AM					AtmAA; [User entered 11.7%]
CV-2349	5/5/2026 8:25:00 AM					Air Tech Lab
CV-2349	5/5/2026 8:25:00 AM					Air Tech Lab; [User entered 15%]
CV-2350	5/20/2026 10:03:44 AM	28.63	1270	34.4327675	-118.6508973	Valve Adjustment:Decreased Flow/Vacuum
CV-2350	5/13/2026 12:57:10 PM	28.68	1319	34.4327625	-118.6509237	
CV-2350	5/13/2026 12:56:01 PM	28.68	1296	34.4327222	-118.6508528	NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-2350	5/11/2026 7:40:00 AM					Air Tech Lab
CV-2350	5/11/2026 7:40:00 AM					Air Tech Lab; [User entered 17%]
CV-2351	5/28/2026 9:25:03 AM	28.62	1284	34.4351297	-118.6511445	Valve Adjustment:NSPS/EG CAI,High O2
CV-2351	5/28/2026 9:24:00 AM	28.62	1287	34.4351405	-118.6511518	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-2351	5/5/2026 7:50:00 AM					Air Tech Lab
CV-2351	5/5/2026 7:50:00 AM					Air Tech Lab; [User entered 0.16%]
CV-2351	5/1/2026 9:05:14 AM	28.61	1281	34.4350955	-118.6511857	Valve Adjustment:Valve 100% Closed,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:Valve stuck open
CV-2352	5/28/2026 9:16:38 AM	28.6	1286	34.4348563	-118.6510468	Valve Adjustment:NSPS/EG CAI,High O2
CV-2352	5/28/2026 9:12:47 AM	28.6	1284	34.4348652	-118.6510425	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-2352	5/5/2026 8:00:00 AM					Air Tech Lab
CV-2352	5/5/2026 8:00:00 AM					Air Tech Lab; [User entered 19%]
CV-2352	5/1/2026 9:13:24 AM	28.61	1284	34.4348275	-118.6510687	Valve Adjustment:Increased Flow/Vacuum,Barely Open;Well Comment:Possible damaged valve
CV-2353-PLR	5/20/2026 9:13:57 AM	28.65	1296	34.4345360	-118.6509304	Valve Adjustment:NSPS/EG CAC,No Flow Measurement
CV-2353-PLR	5/20/2026 9:13:10 AM	28.63	1296	34.4345359	-118.6509308	Valve Adjustment:No Flow Measurement,Decreased Flow/Vacuum
CV-2353-PLR	5/15/2026 8:29:12 AM	28.63	1290	34.4345350	-118.6509228	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-2353-PLR	5/15/2026 8:27:25 AM	28.62	1285	34.4345260	-118.6509185	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-2353-PLR	5/14/2026 8:40:00 AM					AtmAA
CV-2353-PLR	5/12/2026 7:35:00 AM					Air Tech Lab
CV-2353-PLR	5/12/2026 7:35:00 AM					Air Tech Lab; [User entered 21%]
CV-2354	5/28/2026 10:36:46 AM	28.66	1270	34.4336740	-118.6513429	Valve Adjustment:NSPS/EG CAI,High Temp

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-2354	5/20/2026 10:42:07 AM	28.66	1278	34.4336917	-118.6513670	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header;Well Condition:Lorentz Pump Installed;Well Repairs:Surging
CV-2354	5/20/2026 10:40:36 AM	28.66	1277	34.4336809	-118.6513640	Valve Comment:Header watered in;Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Header;Well Condition:Lorentz Pump Installed;Well Repairs:Surging
CV-2354	5/13/2026 11:03:49 AM	28.81	1253	34.4336904	-118.6513663	Valve Comment:LORENTZ pump started after last read so cleared some 02;Valve Adjustment:No Flow Measurement,High Temp
CV-2354	5/13/2026 11:01:08 AM	28.8	1254	34.4336905	-118.6513642	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-2354	5/6/2026 10:50:20 AM	28.74	1259	34.4336848	-118.6513483	Valve Adjustment:No Flow Measurement,High Temp
CV-2354	5/6/2026 10:50:00 AM					AtmAA
CV-2354	5/6/2026 10:50:00 AM					AtmAA; [User entered 14.8%]
CV-2354	5/5/2026 8:20:00 AM					Air Tech Lab
CV-2354	5/5/2026 8:20:00 AM					Air Tech Lab; [User entered 17%]
CV-24001	5/19/2026 10:02:44 AM	28.62	1351	34.4366327	-118.6509302	
CV-24001	5/12/2026 10:38:27 AM	28.59	1385	34.4366077	-118.6510030	
CV-24002	5/19/2026 9:53:36 AM	28.63	1353	34.4367335	-118.6504768	Valve Adjustment:NSPS/EG CAC,Barely Open;Well Comment:Sample port installed
CV-24002	5/19/2026 9:51:18 AM	28.63	1344	34.4367297	-118.6504578	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open
CV-24002	5/1/2026 2:39:31 PM	28.47	1341	34.4367492	-118.6504717	Well Comment:no system port
CV-24003	5/19/2026 9:12:06 AM	28.59	1373	34.4368667	-118.6500807	Valve Adjustment:Barely Open;Well Repairs:Valve
CV-24003	5/1/2026 2:37:02 PM	28.45	1347	34.4368643	-118.6500682	
CV-24004	5/19/2026 9:02:30 AM	28.59	1368	34.4370670	-118.6496833	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24004	5/1/2026 2:33:11 PM	28.45	1361	34.4370727	-118.6496892	Valve Adjustment:Barely Open
CV-24006	5/19/2026 10:36:49 AM	28.59	1365	34.4363533	-118.6504565	Valve Adjustment:Barely Open
CV-24006	5/1/2026 11:40:45 AM	28.5	1391	34.4363850	-118.6504893	
CV-24007	5/29/2026 9:33:56 AM	28.63	1381	34.4365195	-118.6501157	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum
CV-24007	5/26/2026 1:56:22 PM	28.4	1377	34.4365219	-118.6501221	Valve Adjustment:High Temp
CV-24007	5/26/2026 1:55:46 PM	28.4	1377	34.4365234	-118.6501195	Valve Adjustment:High Temp,Increased Flow/Vacuum
CV-24007	5/19/2026 10:46:37 AM	28.59	1355	34.4365007	-118.6500992	Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Barely Open
CV-24007	5/19/2026 10:45:21 AM	28.59	1366	34.4365215	-118.6501223	Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Increased Flow/Vacuum
CV-24007	5/15/2026 9:10:41 AM	28.53	1376	34.4365388	-118.6500990	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header
CV-24007	5/15/2026 9:09:54 AM	28.53	1373	34.4365295	-118.6501087	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum,Surging Liquid in Header

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24007	5/12/2026 8:40:00 AM					Air Tech Lab
CV-24007	5/12/2026 8:40:00 AM					Air Tech Lab; [User entered 17%]
CV-24008	5/26/2026 1:50:27 PM	28.4	1379	34.4366982	-118.6496973	Valve Adjustment:No Flow Measurement,High Temp
CV-24008	5/18/2026 2:25:00 PM					AtmAA
CV-24008	5/18/2026 2:17:05 PM	28.51	1370	34.4366822	-118.6496978	Valve Adjustment:High Temp
CV-24008	5/12/2026 1:41:31 PM	28.55	1381	34.4366814	-118.6497041	Valve Adjustment:High Temp,Decreased Flow/Vacuum;Well Comment:Valve on well head does nit adjust input a maintance form
CV-24008	5/12/2026 1:40:00 PM					AtmAA
CV-24008	5/5/2026 10:20:00 AM					AtmAA
CV-24008	5/5/2026 10:20:00 AM					AtmAA; [User entered 8.66%]
CV-24008	5/5/2026 10:14:56 AM	28.51	1374	34.4366809	-118.6496833	Valve Adjustment:High Temp
CV-24009	5/26/2026 1:46:14 PM	28.4	1374	34.4368956	-118.6493814	Valve Adjustment:High Temp
CV-24009	5/18/2026 2:20:00 PM					AtmAA
CV-24009	5/18/2026 2:13:29 PM	28.51	1373	34.4368830	-118.6493610	Valve Adjustment:No Flow Measurement,High Temp
CV-24009	5/12/2026 1:35:00 PM					AtmAA
CV-24009	5/12/2026 1:31:36 PM	28.54	1373	34.4368941	-118.6493668	Valve Adjustment:No Flow Measurement,High Temp
CV-24009	5/5/2026 10:15:00 AM					AtmAA
CV-24009	5/5/2026 10:15:00 AM					AtmAA; [User entered 13.53%]
CV-24009	5/5/2026 10:10:10 AM	28.51	1369	34.4368615	-118.6493551	Valve Adjustment:High Temp
CV-24010	5/26/2026 9:45:36 AM	28.43	1373	34.4370698	-118.6489448	Valve Adjustment:High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24010	5/13/2026 1:57:52 PM	28.63	1349	34.4370955	-118.6489555	
CV-24011	5/27/2026 8:51:05 AM	28.4	1377	34.4362140	-118.6501631	Valve Adjustment:High Temp
CV-24011	5/27/2026 8:49:35 AM	28.39	1378	34.4362009	-118.6501779	Valve Adjustment:High Temp,Increased Flow/Vacuum
CV-24011	5/19/2026 10:30:22 AM	28.59	1364	34.4361915	-118.6501875	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24011	5/18/2026 2:55:00 PM					AtmAA
CV-24011	5/18/2026 2:48:57 PM	28.51	1373	34.4362109	-118.6501841	Valve Adjustment:No Flow Measurement,High Temp
CV-24011	5/12/2026 2:43:10 PM	28.57	1368	34.4362031	-118.6502022	Valve Adjustment:No Flow Measurement,High Temp
CV-24011	5/12/2026 2:25:00 PM					AtmAA
CV-24011	5/5/2026 1:10:54 PM	28.51	1378	34.4361917	-118.6502091	Valve Adjustment:High Temp
CV-24011	5/5/2026 1:10:00 PM					AtmAA
CV-24011	5/5/2026 1:10:00 PM					AtmAA; [User entered 10.77%]
CV-24012	5/26/2026 2:14:33 PM	28.42	1360	34.4361780	-118.6493885	Valve Adjustment:No Flow Measurement,High Temp
CV-24012	5/18/2026 2:56:25 PM	28.51	1358	34.4361784	-118.6493749	Valve Adjustment:High Temp
CV-24012	5/18/2026 2:50:00 PM					AtmAA
CV-24012	5/18/2026 2:41:34 PM	28.52	1348	34.4361953	-118.6493735	Valve Adjustment:No Flow Measurement,High Temp
CV-24012	5/12/2026 2:38:30 PM	28.58	1375	34.4361821	-118.6493490	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24012	5/12/2026 2:20:00 PM					AtmAA
CV-24012	5/5/2026 1:30:00 PM					AtmAA
CV-24012	5/5/2026 1:30:00 PM					AtmAA; [User entered 16.47%]
CV-24012	5/5/2026 1:26:23 PM	28.51	1358	34.4361692	-118.6493705	Valve Adjustment:No Flow Measurement,High Temp
CV-24013	5/26/2026 9:51:46 AM	28.43	1382	34.4366035	-118.6492483	Valve Adjustment:High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24013	5/13/2026 10:06:33 AM	28.67	1364	34.4366058	-118.6492207	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24014	5/26/2026 1:42:04 PM	28.4	1383	34.4367773	-118.6489526	Valve Adjustment:No Flow Measurement,High Temp
CV-24014	5/18/2026 2:15:00 PM					AtmAA
CV-24014	5/18/2026 2:07:26 PM	28.52	1375	34.4367798	-118.6489571	Valve Adjustment:No Flow Measurement,High Temp,Reduce Sys. Vac. - Flare Down
CV-24014	5/12/2026 1:30:00 PM					AtmAA
CV-24014	5/12/2026 1:26:38 PM	28.55	1362	34.4367858	-118.6489631	Valve Adjustment:No Flow Measurement,High Temp
CV-24014	5/12/2026 1:25:28 PM	28.55	1363	34.4367876	-118.6489603	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24014	5/5/2026 10:10:00 AM					AtmAA
CV-24014	5/5/2026 10:10:00 AM					AtmAA; [User entered 19.01%]
CV-24014	5/5/2026 10:06:41 AM	28.51	1367	34.4367698	-118.6489586	Valve Adjustment:No Flow Measurement,High Temp
CV-24015	5/26/2026 9:48:59 AM	28.44	1373	34.4368709	-118.6486048	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24015	5/18/2026 10:08:30 AM	28.51	1358	34.4368805	-118.6486172	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-24015	5/18/2026 10:06:48 AM	28.51	1358	34.4368807	-118.6486171	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum
CV-24015	5/18/2026 10:05:03 AM	28.51	1357	34.4368852	-118.6486148	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down
CV-24015	5/18/2026 10:05:00 AM					AtmAA
CV-24015	5/12/2026 9:01:20 AM	28.51	1364	34.4368432	-118.6486216	Valve Adjustment:No Flow Measurement,High Temp
CV-24015	5/12/2026 9:00:00 AM					AtmAA
CV-24015	5/12/2026 8:59:57 AM	28.51	1364	34.4368432	-118.6486216	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24015	5/5/2026 9:14:20 AM	28.5	1358	34.4368716	-118.6486138	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-24015	5/5/2026 9:05:00 AM					AtmAA
CV-24015	5/5/2026 9:05:00 AM					AtmAA; [User entered 20.36%]
CV-24016	5/29/2026 9:27:07 AM	28.64	1370	34.4359133	-118.6502473	Valve Adjustment:NSPS/EG CAI,High Temp,Valve 100% Open
CV-24016	5/27/2026 8:54:06 AM	28.4	1366	34.4359104	-118.6502344	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24016	5/19/2026 10:04:01 AM	28.61	1345	34.4359238	-118.6502128	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24016	5/19/2026 10:02:01 AM	28.6	1348	34.4359177	-118.6502413	Valve Adjustment:NSPS/EG CAI,High Temp;Well Condition:Lorentz Pump Installed
CV-24016	5/18/2026 3:00:00 PM					AtmAA
CV-24016	5/18/2026 2:51:00 PM	28.51	1367	34.4359217	-118.6502495	Valve Adjustment:No Flow Measurement,High Temp
CV-24016	5/12/2026 2:44:41 PM	28.56	1368	34.4359272	-118.6502615	Valve Adjustment:No Flow Measurement,High Temp
CV-24016	5/12/2026 2:30:00 PM					AtmAA
CV-24016	5/6/2026 1:26:28 PM	28.63	1368	34.4359207	-118.6502510	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp
CV-24016	5/6/2026 1:25:16 PM	28.63	1371	34.4359275	-118.6502513	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp
CV-24016	5/5/2026 1:15:29 PM	28.51	1368	34.4359142	-118.6502632	Valve Adjustment:Audible Flow,No Flow Measurement,High Temp
CV-24016	5/5/2026 1:15:00 PM					AtmAA
CV-24016	5/5/2026 1:15:00 PM					AtmAA; [User entered 9.66%]
CV-24017	5/26/2026 2:08:15 PM	28.4	1368	34.4361184	-118.6498213	Valve Adjustment:No Flow Measurement,High Temp
CV-24017	5/26/2026 2:07:20 PM	28.4	1368	34.4361151	-118.6498173	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24017	5/18/2026 2:40:00 PM					AtmAA
CV-24017	5/18/2026 2:35:18 PM	28.51	1364	34.4361053	-118.6498081	Valve Adjustment:No Flow Measurement,High Temp;Well Repairs:Surging
CV-24017	5/12/2026 2:47:32 PM	28.56	1368	34.4361035	-118.6498030	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header
CV-24017	5/12/2026 2:25:14 PM	28.59	1378	34.4361164	-118.6498165	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24017	5/12/2026 2:10:00 PM					AtmAA
CV-24017	5/12/2026 8:35:00 AM					Air Tech Lab
CV-24017	5/12/2026 8:35:00 AM					Air Tech Lab; [User entered 19%]
CV-24017	5/5/2026 1:20:00 PM					AtmAA
CV-24017	5/5/2026 1:20:00 PM					AtmAA; [User entered 15.55%]
CV-24017	5/5/2026 1:19:34 PM	28.51	1369	34.4361090	-118.6498195	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-24018	5/29/2026 11:06:53 AM	28.61	1362	34.4358020	-118.6501282	No Flow Measurement
CV-24018	5/13/2026 3:41:42 PM	28.65	1362	34.4356148	-118.6500517	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-24019	5/27/2026 8:57:49 AM	28.4	1361	34.4357838	-118.6497704	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24019	5/19/2026 8:35:00 AM					AtmAA
CV-24019	5/19/2026 8:31:39 AM	28.59	1376	34.4357821	-118.6497718	Valve Adjustment:No Flow Measurement,High Temp
CV-24019	5/13/2026 2:09:27 PM	28.67	1371	34.4357829	-118.6497628	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24019	5/5/2026 2:30:00 PM					AtmAA
CV-24019	5/5/2026 2:30:00 PM					AtmAA; [User entered 14.18%]
CV-24019	5/5/2026 2:26:07 PM	28.51	1364	34.4357752	-118.6497640	Valve Adjustment:No Flow Measurement,High Temp
CV-24020	5/26/2026 10:31:13 AM	28.45	1352	34.4359950	-118.6493380	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24020	5/13/2026 1:39:38 PM	28.64	1337	34.4359825	-118.6493598	Valve Adjustment:Barely Open
CV-24021	5/26/2026 10:19:45 AM	28.43	1365	34.4361505	-118.6490217	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24021	5/13/2026 10:19:21 AM	28.67	1355	34.4361580	-118.6490435	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:valve possibly damaged
CV-24022-PLR	5/26/2026 1:34:59 PM	28.4	1377	34.4365365	-118.6487855	Valve Adjustment:No Flow Measurement,High Temp
CV-24022-PLR	5/18/2026 2:10:00 PM					AtmAA
CV-24022-PLR	5/18/2026 2:04:39 PM	28.51	1377	34.4365219	-118.6487899	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header
CV-24022-PLR	5/12/2026 1:25:00 PM					AtmAA
CV-24022-PLR	5/12/2026 1:18:18 PM	28.55	1367	34.4365285	-118.6487914	Valve Adjustment:No Flow Measurement,High Temp
CV-24022-PLR	5/5/2026 10:05:00 AM					AtmAA
CV-24022-PLR	5/5/2026 10:05:00 AM					AtmAA; [User entered 19.92%]
CV-24022-PLR	5/5/2026 10:03:55 AM	28.51	1368	34.4365105	-118.6488020	Valve Adjustment:No Flow Measurement,High Temp
CV-24023	5/26/2026 10:02:11 AM	28.47	1383	34.4365975	-118.6484405	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-24023	5/26/2026 9:58:22 AM	28.47	1377	34.4365949	-118.6484358	Valve Comment:LORENTZ PUMP ON UPON ARRIVAL;Valve Adjustment:No Flow Measurement,High Temp,High O2,Decreased Flow/Vacuum
CV-24023	5/18/2026 10:19:04 AM	28.51	1364	34.4365803	-118.6484551	Valve Adjustment:No Flow Measurement,High Temp
CV-24023	5/18/2026 10:15:00 AM	28.51	1363	34.4365788	-118.6484547	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24023	5/12/2026 8:52:20 AM	28.51	1364	34.4365324	-118.6484561	Valve Adjustment:No Flow Measurement,High Temp
CV-24023	5/12/2026 8:51:10 AM	28.51	1364	34.4365424	-118.6484653	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24023	5/12/2026 8:50:00 AM					AtmAA
CV-24023	5/6/2026 9:28:29 AM	28.63	1372	34.4366013	-118.6484405	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp,Valve 100% Open
CV-24023	5/6/2026 9:27:29 AM	28.63	1373	34.4365940	-118.6484368	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp,Valve 100% Open

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24023	5/5/2026 9:36:54 AM	28.51	1361	34.4365952	-118.6484455	Valve Comment:Valve open 100 percent due to gas order around well head;Valve Adjustment:No Flow Measurement,Valve 100% Open
CV-24023	5/5/2026 9:35:20 AM	28.51	1363	34.4365944	-118.6484474	Valve Comment:Valve open due to string gas order around well;Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24023	5/5/2026 9:27:58 AM	28.51	1362	34.4366107	-118.6484539	Valve Adjustment:No Flow Measurement,High Temp
CV-24023	5/5/2026 9:25:00 AM					AtmAA
CV-24023	5/5/2026 9:25:00 AM					AtmAA; [User entered 21.575%]
CV-24024-PLR	5/18/2026 9:51:23 AM	28.54	1362	34.4367984	-118.6481306	Valve Adjustment:NSPS/EG CAC,No Flow Measurement
CV-24024-PLR	5/15/2026 9:22:07 AM	28.58	1346	34.4368165	-118.6481413	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open,Surging Liquid in Header
CV-24024-PLR	5/15/2026 9:20:22 AM	28.58	1343	34.4368210	-118.6481447	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open,Surging Liquid in Header
CV-24025	5/28/2026 2:28:43 PM	28.51	1380	34.4352795	-118.6499510	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24025	5/19/2026 9:27:53 AM	28.62	1358	34.4352678	-118.6500158	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-24025	5/19/2026 9:26:52 AM	28.62	1357	34.4352661	-118.6500248	Valve Adjustment:No Flow Measurement,High Temp
CV-24025	5/19/2026 9:25:00 AM					AtmAA
CV-24025	5/13/2026 2:30:31 PM	28.66	1356	34.4352715	-118.6499506	Valve Adjustment:No Flow Measurement,High Temp
CV-24025	5/6/2026 8:57:31 AM	28.63	1359	34.4352857	-118.6499268	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header
CV-24025	5/6/2026 8:56:37 AM	28.63	1353	34.4352748	-118.6499408	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum,Surging Liquid in Header
CV-24025	5/5/2026 2:13:13 PM	28.51	1364	34.4352774	-118.6499214	Valve Adjustment:Audible Flow,No Flow Measurement,High Temp
CV-24025	5/5/2026 2:10:00 PM					AtmAA
CV-24025	5/5/2026 2:10:00 PM					AtmAA; [User entered 11.07%]
CV-24026	5/22/2026 12:25:54 PM	28.54	1346	34.4356472	-118.6492438	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Well (Watered In)
CV-24026	5/13/2026 1:43:47 PM	28.64	1355	34.4356627	-118.6492732	Valve Adjustment:Barely Open
CV-24027	5/26/2026 10:11:09 AM	28.45	1355	34.4361000	-118.6487237	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24027	5/13/2026 10:15:50 AM	28.68	1354	34.4361152	-118.6487245	Valve Adjustment:Barely Open;Well Comment:Possible damaged valve
CV-24027	5/6/2026 9:11:56 AM	28.63	1355	34.4361057	-118.6487228	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-24028	5/26/2026 1:15:48 PM	28.39	1366	34.4363415	-118.6484647	Valve Adjustment:High Temp
CV-24028	5/26/2026 1:13:13 PM	28.4	1363	34.4363513	-118.6484733	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24028	5/18/2026 2:05:00 PM					AtmAA
CV-24028	5/18/2026 2:01:26 PM	28.52	1380	34.4363509	-118.6484771	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down
CV-24028	5/12/2026 1:20:00 PM					AtmAA
CV-24028	5/12/2026 1:14:56 PM	28.55	1355	34.4363597	-118.6484690	Valve Adjustment:No Flow Measurement,High Temp
CV-24028	5/5/2026 10:00:52 AM	28.51	1365	34.4363421	-118.6484743	Valve Adjustment:No Flow Measurement,High Temp
CV-24028	5/5/2026 10:00:00 AM					AtmAA
CV-24028	5/5/2026 10:00:00 AM					AtmAA; [User entered 18.67%]
CV-24029	5/29/2026 11:19:30 AM	28.6	1348	34.4364658	-118.6480740	NSPS/EG CAI,No Flow Measurement,High O2
CV-24029	5/29/2026 11:15:41 AM	28.6	1322	34.4364502	-118.6480705	NSPS/EG CAI,High O2
CV-24029	5/13/2026 2:06:48 PM	28.63	1358	34.4364448	-118.6480895	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24030	5/26/2026 9:14:08 AM	28.47	1371	34.4366543	-118.6478634	Valve Adjustment:No Flow Measurement,High Temp
CV-24030	5/26/2026 9:07:52 AM	28.47	1368	34.4366572	-118.6478750	Valve Comment:Lorentz pump running upon arrival;Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24030	5/18/2026 9:35:03 AM	28.52	1356	34.4366520	-118.6478828	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-24030	5/18/2026 9:35:00 AM					AtmAA
CV-24030	5/12/2026 9:18:44 AM	28.55	1350	34.4366654	-118.6479217	Valve Adjustment:No Flow Measurement,High Temp
CV-24030	5/12/2026 9:15:00 AM					AtmAA
CV-24030	5/5/2026 8:46:48 AM	28.51	1340	34.4366447	-118.6478811	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header
CV-24030	5/5/2026 8:45:00 AM					AtmAA
CV-24030	5/5/2026 8:45:00 AM					AtmAA; [User entered 17.26%]
CV-24030	5/5/2026 8:44:58 AM	28.51	1337	34.4366473	-118.6478843	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24031	5/29/2026 1:15:41 PM	28.58	1347	34.4349001	-118.6498244	Valve Comment:LORENTZ pump installed 052726;Valve Adjustment:No Flow Measurement,Valve 100% Open
CV-24031	5/22/2026 12:15:48 PM	28.55	1352	34.4349038	-118.6498248	
CV-24031	5/22/2026 12:14:13 PM	28.55	1355	34.4349185	-118.6498527	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24031	5/12/2026 1:32:07 PM	28.58	1336	34.4349093	-118.6498243	Valve Adjustment:Barely Open
CV-24032	5/27/2026 9:19:07 AM	28.43	1339	34.4351168	-118.6496457	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Header
CV-24032	5/27/2026 9:17:20 AM	28.43	1340	34.4351132	-118.6496448	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Surging Liquid in Header

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24032	5/27/2026 9:09:02 AM	28.43	1340	34.4351199	-118.6496367	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum,Valve 100% Open,Surging Liquid in Header
CV-24032	5/24/2026 12:06:03 PM	28.61	1358	34.4351178	-118.6496545	Valve Adjustment:High Temp,High O2;Well Condition:Lorentz Pump Installed
CV-24032	5/24/2026 12:02:54 PM	28.61	1346	34.4351428	-118.6496432	Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24032	5/19/2026 8:41:47 AM	28.62	1339	34.4351149	-118.6496034	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24032	5/14/2026 10:31:39 AM	28.6	1352	34.4351008	-118.6496090	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum
CV-24032	5/13/2026 2:37:29 PM	28.66	1352	34.4351149	-118.6496664	Valve Adjustment:No Flow Measurement,High Temp
CV-24032	5/5/2026 2:20:00 PM					AtmAA
CV-24032	5/5/2026 2:20:00 PM					AtmAA; [User entered 12.905%]
CV-24032	5/5/2026 2:17:41 PM	28.51	1357	34.4351042	-118.6496337	Valve Adjustment:No Flow Measurement,High Temp
CV-24033	5/28/2026 2:24:12 PM	28.55	1367	34.4353491	-118.6494775	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24033	5/19/2026 8:45:00 AM					AtmAA
CV-24033	5/19/2026 8:39:24 AM	28.62	1341	34.4353456	-118.6494733	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed;Well Repairs:None
CV-24033	5/13/2026 2:17:00 PM	28.69	1364	34.4353370	-118.6494871	Valve Adjustment:No Flow Measurement,High Temp
CV-24033	5/7/2026 1:00:00 PM					AtmAA; [User entered 17.1%]
CV-24033	5/7/2026 12:59:49 PM	28.55	1350	34.4353420	-118.6494736	Valve Adjustment:No Flow Measurement,High Temp
CV-24033	5/7/2026 1:00:00 AM					AtmAA
CV-24034	5/18/2026 11:08:37 AM	28.54	1364	34.4361225	-118.6481087	Valve Adjustment:No Flow Measurement
CV-24034	5/18/2026 11:06:51 AM	28.54	1365	34.4361207	-118.6481114	Valve Adjustment:No Flow Measurement,Decreased Flow/Vacuum
CV-24034	5/12/2026 10:57:45 AM	28.55	1359	34.4361182	-118.6481212	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24034	5/12/2026 10:55:50 AM	28.55	1358	34.4361142	-118.6481226	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24034	5/12/2026 10:55:00 AM					AtmAA
CV-24034	5/5/2026 9:57:30 AM	28.51	1358	34.4360973	-118.6481208	Valve Adjustment:No Flow Measurement,High Temp
CV-24034	5/5/2026 9:56:30 AM	28.51	1358	34.4360973	-118.6481207	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24034	5/5/2026 9:55:00 AM					AtmAA
CV-24034	5/5/2026 9:55:00 AM					AtmAA; [User entered 16.63%]

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24035	5/26/2026 8:50:47 AM	28.46	1378	34.4363895	-118.6477156	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header
CV-24035	5/18/2026 9:10:00 AM					AtmAA
CV-24035	5/18/2026 9:05:47 AM	28.49	1379	34.4364010	-118.6477240	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In)
CV-24035	5/18/2026 9:03:47 AM	28.47	1379	34.4363958	-118.6477166	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum,Surging Liquid in Well (Watered In)
CV-24035	5/12/2026 9:40:00 AM					AtmAA
CV-24035	5/12/2026 9:31:35 AM	28.51	1375	34.4363782	-118.6477294	Valve Adjustment:No Flow Measurement,High Temp
CV-24035	5/5/2026 8:25:00 AM					AtmAA
CV-24035	5/5/2026 8:25:00 AM					AtmAA; [User entered 14.245%]
CV-24035	5/5/2026 8:24:01 AM	28.51	1366	34.4363744	-118.6477236	Valve Adjustment:No Flow Measurement,High Temp
CV-24036	5/29/2026 2:20:04 PM	28.62	1345	34.4345244	-118.6496871	Valve Adjustment:No Flow Measurement
CV-24036	5/24/2026 11:45:25 AM	28.64	1343	34.4344598	-118.6497053	Valve Comment:Pump active;Valve Adjustment:Valve 100% Open;Well Comment:loose lorentz fittings;Well Condition:Lorentz Pump Installed
CV-24036	5/13/2026 10:53:14 AM	28.7	1340	34.4344478	-118.6497045	Valve Adjustment:Valve 100% Open
CV-24036	5/6/2026 8:46:55 AM	28.65	1347	34.4344562	-118.6497137	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Valve 100% Open
CV-24037	5/26/2026 9:09:53 AM	28.45	1357	34.4347505	-118.6494295	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24037	5/26/2026 9:08:28 AM	28.45	1352	34.4347423	-118.6494345	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In)
CV-24037	5/12/2026 1:53:15 PM	28.57	1331	34.4347705	-118.6494507	Valve Adjustment:Decreased Flow/Vacuum
CV-24038	5/27/2026 9:29:33 AM	28.44	1341	34.4350164	-118.6488705	Valve Adjustment:No Flow Measurement,High Temp
CV-24038	5/27/2026 9:27:49 AM	28.43	1340	34.4350122	-118.6488679	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24038	5/19/2026 9:05:00 AM					AtmAA
CV-24038	5/19/2026 9:04:35 AM	28.63	1337	34.4350133	-118.6488771	Valve Adjustment:No Flow Measurement,High Temp
CV-24038	5/19/2026 9:04:12 AM	28.63	1337	34.4350135	-118.6488774	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24038	5/13/2026 2:51:36 PM	28.69	1340	34.4350189	-118.6488679	Valve Comment:Lorentz pump disconnected;Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-24038	5/13/2026 2:48:58 PM	28.68	1342	34.4350140	-118.6488769	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24038	5/6/2026 3:05:00 PM					AtmAA
CV-24038	5/6/2026 3:05:00 PM					AtmAA; [User entered 17.06%]
CV-24038	5/6/2026 3:04:57 PM	28.59	1345	34.4350175	-118.6488795	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Surging Liquid in Header
CV-24038	5/6/2026 3:04:21 PM	28.59	1346	34.4350157	-118.6488745	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header
CV-24039	5/22/2026 12:04:33 PM	28.55	1352	34.4352908	-118.6486837	Valve Comment:Noticed temp going down when pump stopped pumping;Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-24039	5/22/2026 12:01:47 PM	28.54	1348	34.4352890	-118.6486822	Valve Adjustment:NSPS/EG CAC,High Temp;Well Condition:Lorentz Pump Installed
CV-24039	5/22/2026 11:58:20 AM	28.55	1350	34.4352938	-118.6486770	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum,Barely Open;Well Comment:Pump is currently running;Well Condition:Lorentz Pump Installed
CV-24039	5/14/2026 1:31:24 PM	28.68	1356	34.4352930	-118.6486885	
CV-24039	5/14/2026 1:29:39 PM	28.7	1356	34.4353073	-118.6486835	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In);Well Comment:no pump
CV-24040	5/29/2026 9:07:46 AM	28.66	1356	34.4356347	-118.6483737	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24040	5/29/2026 9:07:06 AM	28.65	1359	34.4356512	-118.6483928	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24040	5/29/2026 9:05:56 AM	28.63	1358	34.4356437	-118.6483768	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-24040	5/19/2026 10:40:23 AM	28.71	1331	34.4356267	-118.6483830	
CV-24040	5/19/2026 10:38:38 AM	28.69	1339	34.4356322	-118.6483722	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In)
CV-24040	5/13/2026 1:35:35 PM	28.75	1353	34.4356472	-118.6483613	
CV-24040	5/13/2026 1:32:34 PM	28.74	1368	34.4356482	-118.6483772	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24041	5/26/2026 10:04:46 AM	28.44	1340	34.4358410	-118.6480238	Valve Adjustment:High O2,Decreased Flow/Vacuum
CV-24041	5/8/2026 8:06:27 AM	28.67	1378	34.4358953	-118.6480235	No Flow Measurement
CV-24042	5/26/2026 11:03:38 AM	28.47	1374	34.4362450	-118.6474583	Valve Adjustment:No Flow Measurement,High Temp
CV-24042	5/26/2026 11:02:42 AM	28.47	1373	34.4362468	-118.6474609	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24042	5/18/2026 10:55:00 AM					AtmAA
CV-24042	5/18/2026 10:47:52 AM	28.51	1377	34.4362378	-118.6474643	Valve Adjustment:No Flow Measurement,High Temp
CV-24042	5/12/2026 10:15:58 AM	28.51	1375	34.4362586	-118.6474732	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24042	5/12/2026 10:15:09 AM	28.52	1373	34.4362525	-118.6474630	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24042	5/12/2026 10:15:00 AM					AtmAA
CV-24042	5/7/2026 10:08:18 AM	28.57	1372	34.4362599	-118.6474627	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-24042	5/7/2026 10:06:45 AM	28.55	1370	34.4362605	-118.6474585	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Positive Static Press.
CV-24042	5/7/2026 10:05:00 AM					AtmAA
CV-24042	5/7/2026 10:05:00 AM					AtmAA; [User entered 13.94%]
CV-24043	5/22/2026 2:06:15 PM	28.41	1332	34.4341498	-118.6497102	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24043	5/15/2026 8:55:16 AM	28.58	1335	34.4341002	-118.6497133	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24044	5/26/2026 8:46:58 AM	28.45	1346	34.4343868	-118.6493960	Valve Adjustment:Decreased Flow/Vacuum
CV-24044	5/26/2026 8:42:07 AM	28.45	1353	34.4343945	-118.6493898	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24044	5/8/2026 12:36:24 PM	28.58	1355	34.4343787	-118.6494215	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24045	5/27/2026 9:33:35 AM	28.43	1344	34.4347487	-118.6490565	Valve Adjustment:No Flow Measurement,High Temp
CV-24045	5/27/2026 9:32:48 AM	28.43	1345	34.4347501	-118.6490543	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24045	5/19/2026 9:11:34 AM	28.64	1344	34.4347503	-118.6490607	Valve Adjustment:No Flow Measurement,High Temp
CV-24045	5/19/2026 9:10:36 AM	28.62	1344	34.4347378	-118.6490730	Valve Comment:Lorentz pump was off upon arrival;Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24045	5/19/2026 9:10:00 AM					AtmAA
CV-24045	5/13/2026 2:58:14 PM	28.66	1340	34.4347495	-118.6490602	Valve Comment:LORENTZ pump disconnected;Valve Adjustment:No Flow Measurement,High Temp
CV-24045	5/13/2026 2:56:09 PM	28.69	1341	34.4347492	-118.6490622	Valve Adjustment:No Flow Measurement,Decreased Flow/Vacuum
CV-24045	5/6/2026 2:55:47 PM	28.62	1348	34.4347539	-118.6490799	Valve Adjustment:High Temp
CV-24045	5/6/2026 2:54:58 PM	28.59	1346	34.4347537	-118.6490797	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-24045	5/6/2026 2:45:00 PM					AtmAA
CV-24045	5/6/2026 2:45:00 PM					AtmAA; [User entered 16.18%]
CV-24046	5/29/2026 1:33:04 PM	28.59	1354	34.4350982	-118.6483655	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,Undersized Lateral
CV-24046	5/29/2026 1:30:24 PM	28.59	1352	34.4351048	-118.6483724	Valve Comment:Lorentz pump reconnect 0;Valve Adjustment:NSPS/EG CAI,No Flow Measurement,Increased Flow/Vacuum,Undersized Lateral;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24046	5/28/2026 11:56:16 AM	28.5	1434	34.4350508	-118.6483830	
CV-24046	5/28/2026 11:54:22 AM	28.5	1398	34.4350515	-118.6483538	
CV-24046	5/13/2026 10:32:28 AM	28.77	1360	34.4350777	-118.6483772	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24048	5/20/2026 2:12:35 PM	28.45	1361	34.4355523	-118.6477917	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24048	5/19/2026 10:25:00 AM					AtmAA
CV-24048	5/8/2026 8:14:16 AM	28.61	1348	34.4355390	-118.6477927	Reduced System Vacuum,No Flow Measurement
CV-24049	5/26/2026 10:45:00 AM	28.44	1380	34.4359386	-118.6471949	Valve Adjustment:No Flow Measurement,High Temp
CV-24049	5/26/2026 10:43:34 AM	28.45	1380	34.4359428	-118.6471880	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24049	5/18/2026 10:35:00 AM					AtmAA
CV-24049	5/18/2026 10:30:56 AM	28.51	1388	34.4359384	-118.6471848	Valve Adjustment:No Flow Measurement,High Temp
CV-24049	5/13/2026 8:10:00 AM					Air Tech Lab
CV-24049	5/13/2026 8:10:00 AM					Air Tech Lab; [User entered 16%]
CV-24049	5/11/2026 8:49:25 AM	28.55	1385	34.4359557	-118.6471904	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Valve 100% Open
CV-24049	5/11/2026 8:47:07 AM	28.54	1383	34.4359487	-118.6471819	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum,Valve 100% Open
CV-24049	5/4/2026 2:40:00 PM					AtmAA
CV-24049	5/4/2026 2:40:00 PM					AtmAA; [User entered 2.59%]
CV-24049	5/4/2026 2:36:19 PM	28.51	1388	34.4359470	-118.6471999	Valve Adjustment:No Flow Measurement,High Temp
CV-24050	5/22/2026 2:16:54 PM	28.45	1317	34.4337317	-118.6499540	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24050	5/11/2026 12:53:12 PM	28.64	1302	34.4337362	-118.6499635	Well Comment:pump is off;Well Condition:Lorentz Pump Installed
CV-24051	5/26/2026 8:54:30 AM	28.45	1350	34.4344503	-118.6490243	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24051	5/8/2026 12:45:09 PM	28.56	1336	34.4344557	-118.6490413	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
CV-24052	5/20/2026 2:26:23 PM	28.45	1374	34.4350675	-118.6480750	Valve Adjustment:Valve 100% Open
CV-24052	5/13/2026 10:05:26 AM	28.74	1371	34.4350958	-118.6480640	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:No pump
CV-24053	5/20/2026 2:23:25 PM	28.45	1356	34.4352577	-118.6478027	Valve Adjustment:Valve 100% Open
CV-24053	5/8/2026 8:18:44 AM	28.6	1352	34.4352325	-118.6477467	No Flow Measurement
CV-24053	5/7/2026 8:40:00 AM					Air Tech Lab
CV-24053	5/7/2026 8:40:00 AM					Air Tech Lab; [User entered 0.53%]

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24054	5/26/2026 10:39:35 AM	28.44	1392	34.4356337	-118.6471827	Valve Adjustment:No Flow Measurement,High Temp
CV-24054	5/26/2026 10:39:02 AM	28.44	1392	34.4356330	-118.6471816	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24054	5/18/2026 10:30:00 AM					AtmAA
CV-24054	5/18/2026 10:27:38 AM	28.51	1385	34.4356310	-118.6471775	Valve Adjustment:No Flow Measurement,High Temp
CV-24054	5/18/2026 10:26:19 AM	28.51	1384	34.4356370	-118.6471819	Valve Adjustment:No Flow Measurement,Decreased Flow/Vacuum
CV-24054	5/11/2026 8:39:09 AM	28.52	1382	34.4356357	-118.6471822	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-24054	5/11/2026 8:36:54 AM	28.53	1382	34.4356346	-118.6471817	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24054	5/4/2026 2:35:00 PM					AtmAA
CV-24054	5/4/2026 2:35:00 PM					AtmAA; [User entered 10.58%]
CV-24054	5/4/2026 2:34:03 PM	28.51	1391	34.4356452	-118.6471699	Valve Adjustment:High Temp
CV-24054	5/4/2026 1:54:35 PM	28.53	1378	34.4356480	-118.6471992	Valve Adjustment:High Temp
CV-24054	5/4/2026 1:51:53 PM	28.53	1362	34.4356435	-118.6471943	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp,Decreased Flow/Vacuum;Well Comment:secured flange
CV-24055	5/26/2026 9:28:17 AM	28.41	1405	34.4358782	-118.6469018	Valve Adjustment:NSPS/EG CAI,High Temp,Reduce Sys. Vac. - Flare Down
CV-24055	5/26/2026 9:27:16 AM	28.41	1410	34.4358615	-118.6469028	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
CV-24055	5/13/2026 8:15:00 AM					Air Tech Lab
CV-24055	5/13/2026 8:15:00 AM					Air Tech Lab; [User entered 5.1%]
CV-24055	5/12/2026 1:49:20 PM	28.63	1392	34.4358725	-118.6469142	Valve Adjustment:Surging Liquid in Header
CV-24055	5/12/2026 1:47:04 PM	28.63	1385	34.4358793	-118.6469185	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24056	5/19/2026 12:46:55 PM	28.63	1319	34.4332672	-118.6501688	Valve Adjustment:Decreased Flow/Vacuum
CV-24056	5/1/2026 10:37:33 AM	28.59	1321	34.4332728	-118.6501477	
CV-24057	5/22/2026 2:21:55 PM	28.41	1331	34.4334750	-118.6496503	Valve Adjustment:High Temp
CV-24057	5/11/2026 1:01:48 PM	28.64	1312	34.4334530	-118.6496648	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24057	5/11/2026 1:00:44 PM	28.63	1312	34.4334618	-118.6496457	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Comment:pump is off;Well Condition:Lorentz Pump Installed
CV-24058	5/22/2026 1:59:19 PM	28.41	1349	34.4338122	-118.6494655	Valve Adjustment:Barely Open
CV-24058	5/11/2026 12:33:09 PM	28.61	1318	34.4338030	-118.6494458	Valve Adjustment:Reduce Sys. Vac. - Flare Down;Well Comment:pump is on;Well Condition:Lorentz Pump Installed
CV-24059	5/22/2026 2:29:34 PM	28.41	1339	34.4338205	-118.6490560	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24059	5/4/2026 9:02:50 AM	28.55	1341	34.4337565	-118.6490662	Valve Adjustment:NSPS/EG CAC,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24059	5/4/2026 9:01:40 AM	28.54	1341	34.4337645	-118.6490708	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24060	5/20/2026 1:29:27 PM	28.5	1357	34.4340282	-118.6488037	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24060	5/4/2026 9:39:35 AM	28.56	1339	34.4340373	-118.6487870	Valve Adjustment:Decreased Flow/Vacuum
CV-24061	5/26/2026 11:38:49 AM	28.52	1354	34.4343495	-118.6486107	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-24061	5/8/2026 12:59:31 PM	28.56	1340	34.4343577	-118.6486282	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
CV-24062	5/22/2026 11:10:33 AM	28.47	1378	34.4345898	-118.6480770	High Temp,NSPS/EG CAI
CV-24062	5/22/2026 11:08:48 AM	28.47	1319	34.4346125	-118.6479535	NSPS/EG CAI,High Temp
CV-24062	5/8/2026 1:05:26 PM	28.53	1364	34.4345762	-118.6481078	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
CV-24062	5/7/2026 8:17:00 AM					Air Tech Lab
CV-24062	5/7/2026 8:17:00 AM					Air Tech Lab; [User entered 8.0%]
CV-24062	5/4/2026 1:16:07 PM	28.51	1358	34.4345824	-118.6480800	Valve Adjustment:High Temp
CV-24062	5/4/2026 1:15:00 PM					AtmAA
CV-24062	5/4/2026 1:15:00 PM					AtmAA; [User entered 5.61%]
CV-24063	5/28/2026 1:49:33 PM	28.53	1380	34.4349771	-118.6475687	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24063	5/20/2026 2:20:53 PM	28.51	1378	34.4349368	-118.6475152	Valve Adjustment:No Flow Measurement,High Temp
CV-24063	5/14/2026 11:02:15 AM	28.63	1385	34.4349507	-118.6474972	Valve Adjustment:No Flow Measurement,High Temp
CV-24063	5/14/2026 11:01:37 AM	28.62	1385	34.4349488	-118.6474944	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24063	5/14/2026 11:00:00 AM					AtmAA
CV-24063	5/12/2026 8:20:00 AM					Air Tech Lab
CV-24063	5/12/2026 8:20:00 AM					Air Tech Lab; [User entered 12%]
CV-24063	5/4/2026 1:35:00 PM					AtmAA
CV-24063	5/4/2026 1:35:00 PM					AtmAA; [User entered 7.16%]
CV-24063	5/4/2026 1:34:44 PM	28.51	1366	34.4349530	-118.6475245	Valve Adjustment:No Flow Measurement,High Temp
CV-24063	5/4/2026 1:33:24 PM	28.51	1367	34.4349536	-118.6475298	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-24064	5/28/2026 2:15:41 PM	28.55				Valve Adjustment:NSPS/EG CAI,High Temp
CV-24064	5/27/2026 1:55:09 PM	28.4	1370	34.4352364	-118.6471357	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Well (Watered In)

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24064	5/19/2026 1:40:00 PM					AtmAA
CV-24064	5/19/2026 1:36:22 PM	28.6	1383	34.4352506	-118.6471800	Valve Comment:Active PLR observed;Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In)
CV-24064	5/12/2026 8:15:00 AM					Air Tech Lab; [User entered 13%]
CV-24064	5/11/2026 10:07:41 AM	28.55	1377	34.4352204	-118.6471643	Valve Adjustment:No Flow Measurement,High Temp
CV-24064	5/4/2026 9:10:00 AM					AtmAA
CV-24064	5/4/2026 9:10:00 AM					AtmAA; [User entered 11.1%]
CV-24064	5/4/2026 9:09:33 AM	28.55	1376	34.4352502	-118.6471611	Valve Adjustment:High Temp,Valve 100% Open
CV-24065-TP1	5/22/2026 10:27:26 AM	28.37	1384	34.4356133	-118.6467967	Valve Adjustment:Barely Open
CV-24065-TP1	5/12/2026 8:15:00 AM					Air Tech Lab
CV-24065-TP1	5/11/2026 1:07:25 PM	28.52	1384	34.4356297	-118.6468193	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
CV-24065-TP1	5/7/2026 8:35:00 AM					Air Tech Lab
CV-24065-TP1	5/7/2026 8:35:00 AM					Air Tech Lab; [User entered 0.98%]
CV-24066	5/19/2026 12:41:10 PM	28.6	1317	34.4330187	-118.6498118	Valve Adjustment:Decreased Flow/Vacuum
CV-24066	5/11/2026 7:45:00 AM					Air Tech Lab
CV-24066	5/11/2026 7:45:00 AM					Air Tech Lab; [User entered 3.2%]
CV-24066	5/1/2026 10:40:05 AM	28.59	1331	34.4330032	-118.6498153	Valve Adjustment:Audible Flow;Well Condition:Good
CV-24067	5/26/2026 2:27:02 PM	28.43	1343	34.4332042	-118.6497463	Valve Adjustment:High Temp
CV-24067	5/26/2026 2:26:30 PM	28.43	1342	34.4332086	-118.6497617	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-24067	5/19/2026 8:57:43 AM	28.64	1327	34.4331898	-118.6497188	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24067	5/19/2026 8:55:05 AM	28.63	1332	34.4331923	-118.6497198	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Comment:Lorentz deactivated;Well Condition:Pnumatic Pump Installed
CV-24067	5/14/2026 11:37:11 AM	28.54	1257	34.4332052	-118.6499145	
CV-24067	5/14/2026 11:35:44 AM	28.54	1296	34.4331593	-118.6496722	High Temp,Positive Static Press.
CV-24068	5/26/2026 12:08:57 PM	28.44	1369	34.4332578	-118.6493013	Valve Adjustment:NSPS/EG CAC,Reduce Sys. Vac. - Flare Down
CV-24068	5/26/2026 12:06:40 PM	28.44	1368	34.4332655	-118.6493125	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down
CV-24068	5/1/2026 11:18:00 AM	28.57	1334	34.4332443	-118.6493508	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-24069	5/28/2026 9:36:45 AM	28.53	1354	34.4334167	-118.6489192	
CV-24069	5/28/2026 9:35:46 AM	28.53	1352	34.4334167	-118.6489207	Valve Adjustment:Decreased Flow/Vacuum
CV-24069	5/28/2026 9:30:09 AM	28.53	1347	34.4334175	-118.6489218	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum;Well Comment:Needs silicone for lorentz fittings;Well Condition:Lorentz Pump Installed;Well Repairs:Sample Port
CV-24069	5/13/2026 8:20:00 AM					Air Tech Lab

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24069	5/13/2026 8:20:00 AM					Air Tech Lab; [User entered 4.0%]
CV-24069	5/4/2026 8:56:06 AM	28.56	1355	34.4334273	-118.6489272	Valve Comment:No system port;Valve Adjustment:Barely Open
CV-24070	5/20/2026 2:35:15 PM	28.48	1350	34.4337308	-118.6486893	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24070	5/20/2026 2:34:29 PM	28.48	1350	34.4337250	-118.6486983	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24070	5/20/2026 2:33:43 PM	28.49	1349	34.4337250	-118.6486995	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum,Decreased Flow/Vacuum
CV-24070	5/7/2026 8:20:00 AM					Air Tech Lab
CV-24070	5/7/2026 8:20:00 AM					Air Tech Lab; [User entered 11%]
CV-24070	5/4/2026 9:12:35 AM	28.53	1349	34.4337133	-118.6487107	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24070	5/4/2026 9:11:52 AM	28.55	1339	34.4337148	-118.6486890	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24071	5/20/2026 1:35:21 PM	28.5	1355	34.4340125	-118.6484803	Valve Adjustment:Decreased Flow/Vacuum
CV-24071	5/7/2026 8:10:00 AM					Air Tech Lab
CV-24071	5/7/2026 8:10:00 AM					Air Tech Lab; [User entered 2.4%]
CV-24071	5/4/2026 9:43:04 AM	28.55	1335	34.4340043	-118.6484677	Valve Adjustment:Decreased Flow/Vacuum
CV-24072	5/22/2026 2:05:23 PM	28.37	1358	34.4341827	-118.6480535	
CV-24072	5/4/2026 2:18:34 PM	28.51	1365	34.4342068	-118.6480500	Valve Adjustment:NSPS/EG CAC,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24072	5/4/2026 2:17:08 PM	28.51	1372	34.4342030	-118.6480527	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24073-TP1	5/26/2026 8:45:28 AM	28.41	1368	34.4346367	-118.6477108	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
CV-24073-TP1	5/26/2026 8:40:41 AM	28.41	1377	34.4346343	-118.6476967	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
CV-24073-TP1	5/8/2026 1:15:17 PM	28.52	1365	34.4346693	-118.6477383	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
CV-24073-TP1	5/6/2026 2:09:30 PM	28.57	1381	34.4346688	-118.6476972	Valve Adjustment:Barely Open,Surging Liquid in Header
CV-24074	5/22/2026 11:17:05 AM	28.41	1377	34.4347428	-118.6473987	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24074	5/6/2026 2:14:23 PM	28.59	1395	34.4347680	-118.6474127	Valve Adjustment:Decreased Flow/Vacuum
CV-24075-TP1	5/29/2026 4:03:35 PM	28.6	1366	34.4350455	-118.6471355	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24075-TP1	5/29/2026 4:02:17 PM	28.59	1377	34.4350263	-118.6471377	Valve Adjustment:NSPS/EG CAI,High Temp

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24075-TP1	5/11/2026 10:25:13 AM	28.55	1381	34.4350370	-118.6471396	Valve Adjustment:No Flow Measurement,High Temp
CV-24075-TP1	5/4/2026 9:21:41 AM	28.53	1378	34.4350223	-118.6471194	Valve Adjustment:No Flow Measurement,High Temp
CV-24075-TP1	5/4/2026 9:20:10 AM	28.54	1377	34.4350236	-118.6471164	Valve Comment:Updated photo on etools;Valve Adjustment:Audible Flow,High Temp
CV-24075-TP1	5/4/2026 9:20:00 AM					AtmAA
CV-24075-TP1	5/4/2026 9:20:00 AM					AtmAA; [User entered 11.47%]
CV-24076	5/27/2026 2:11:24 PM	28.39	1380	34.4353005	-118.6468888	Valve Adjustment:No Flow Measurement,High Temp
CV-24076	5/19/2026 1:30:00 PM					AtmAA
CV-24076	5/19/2026 1:22:53 PM	28.58	1390	34.4353297	-118.6468739	Valve Adjustment:High Temp
CV-24076	5/14/2026 10:30:00 AM					AtmAA
CV-24076	5/14/2026 10:29:35 AM	28.61	1388	34.4353232	-118.6468753	Valve Adjustment:High Temp
CV-24076	5/4/2026 9:06:09 AM	28.5	1388	34.4353236	-118.6468707	Valve Adjustment:High Temp
CV-24076	5/4/2026 9:05:00 AM					AtmAA
CV-24076	5/4/2026 9:05:00 AM					AtmAA; [User entered 6.27%]
CV-24077	5/28/2026 9:18:10 AM	28.55	1332	34.4326474	-118.6493044	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24077	5/28/2026 9:16:41 AM	28.55	1328	34.4326327	-118.6493094	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24077	5/20/2026 8:03:01 AM	28.55	1334	34.4326904	-118.6493079	Valve Adjustment:No Flow Measurement,High Temp
CV-24077	5/11/2026 1:38:12 PM	28.56	1342	34.4327189	-118.6493015	Valve Adjustment:No Flow Measurement,High Temp
CV-24077	5/7/2026 10:50:33 AM	28.6	1335	34.4327056	-118.6493251	Valve Adjustment:No Flow Measurement,High Temp
CV-24077	5/7/2026 10:50:00 AM					AtmAA
CV-24077	5/7/2026 10:50:00 AM					AtmAA; [User entered 7.22%]
CV-24077	5/1/2026 10:03:08 AM	28.59	1345	34.4326660	-118.6493097	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24077	5/1/2026 10:01:59 AM	28.59	1339	34.4326713	-118.6492955	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24078	5/19/2026 8:40:05 AM	28.62	1328	34.4328908	-118.6494320	Well Condition:Pnumatic Pump Installed
CV-24078	5/19/2026 8:35:10 AM	28.64	1330	34.4329108	-118.6494308	
CV-24078	5/19/2026 8:34:05 AM	28.61	1331	34.4329042	-118.6494297	Valve Adjustment:Increased Flow/Vacuum
CV-24078	5/19/2026 8:31:45 AM	28.62	1340	34.4328927	-118.6494255	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp,Decreased Flow/Vacuum
CV-24078	5/1/2026 10:43:48 AM	28.59	1324	34.4328913	-118.6494548	Valve Adjustment:Decreased Flow/Vacuum
CV-24079-TP8	5/26/2026 12:13:32 PM	28.42	1355	34.4329835	-118.6491168	Valve Adjustment:NSPS/EG CAI,High Temp,Reduce Sys. Vac. - Flare Down
CV-24079-TP8	5/26/2026 12:12:54 PM	28.43	1359	34.4329778	-118.6491177	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down;Well Comment:no system port
CV-24079-TP8	5/11/2026 1:15:47 PM	28.55	1356	34.4329902	-118.6491389	Valve Adjustment:No Flow Measurement,High Temp
CV-24079-TP8	5/7/2026 10:41:06 AM	28.59	1358	34.4329826	-118.6491345	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24079-TP8	5/7/2026 10:40:00 AM					AtmAA
CV-24079-TP8	5/7/2026 10:40:00 AM					AtmAA; [User entered 11.17%]
CV-24079-TP8	5/7/2026 10:38:33 AM	28.59	1355	34.4329762	-118.6491333	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24079-TP8	5/1/2026 11:22:57 AM	28.58	1344	34.4329862	-118.6491275	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open;Well Comment:no system port;Well Repairs:Sample Port
CV-24079-TP8	5/1/2026 11:22:12 AM	28.59	1347	34.4329890	-118.6491312	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24080	5/21/2026 9:36:06 AM	28.5	1362	34.4331173	-118.6488748	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-24080	5/1/2026 11:09:29 AM	28.56	1348	34.4331390	-118.6488647	Valve Adjustment:Barely Open
CV-24081-TP1	5/20/2026 2:26:51 PM	28.48	1356	34.4334105	-118.6485840	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-24081-TP1	5/20/2026 2:25:55 PM	28.48	1363	34.4334093	-118.6485960	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
CV-24081-TP1	5/14/2026 10:40:33 AM	28.71	1371	34.4334155	-118.6485893	Valve Adjustment:Audible Flow
CV-24082	5/20/2026 11:24:26 AM	28.49	1368	34.4334317	-118.6483515	Valve Adjustment:Barely Open
CV-24082	5/4/2026 10:11:50 AM	28.52	1365	34.4334228	-118.6483313	Valve Adjustment:Barely Open
CV-24083	5/20/2026 1:53:17 PM	28.48	1353	34.4337110	-118.6483582	Valve Adjustment:Barely Open
CV-24083	5/4/2026 9:58:27 AM	28.54	1346	34.4337138	-118.6483420	Valve Adjustment:NSPS/EG CAC,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24083	5/4/2026 9:56:08 AM	28.52	1345	34.4337090	-118.6483427	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24084-TP1	5/27/2026 10:49:57 AM	28.41	1368	34.4338457	-118.6480631	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24084-TP1	5/19/2026 10:24:00 AM	28.62	1364	34.4338432	-118.6480344	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24084-TP1	5/11/2026 1:05:39 PM	28.55	1373	34.4338529	-118.6480455	Valve Adjustment:No Flow Measurement,High Temp
CV-24084-TP1	5/4/2026 2:08:40 PM	28.52	1368	34.4338595	-118.6480247	Valve Adjustment:Audible Flow,High Temp
CV-24084-TP1	5/4/2026 2:05:00 PM					AtmAA
CV-24084-TP1	5/4/2026 2:05:00 PM					[User entered 7.74%]
CV-24085	5/20/2026 10:07:30 AM	28.5	1355	34.4323445	-118.6490410	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24085	5/1/2026 10:47:32 AM	28.58	1342	34.4323853	-118.6490165	Valve Adjustment:Audible Flow,Barely Open
CV-24086	5/21/2026 9:49:26 AM	28.48	1364	34.4328970	-118.6486888	Valve Adjustment:Barely Open,Reduce Sys. Vac. - Flare Down
CV-24086	5/1/2026 11:00:38 AM	28.52	1368	34.4328965	-118.6486832	Valve Adjustment:Decreased Flow/Vacuum
CV-24087	5/20/2026 1:36:05 PM	28.49	1376	34.4329980	-118.6481118	Valve Adjustment:Reduce Sys. Vac. - Flare Down;Well Repairs:Sample Port
CV-24087	5/5/2026 10:43:05 AM	28.53	1382	34.4329827	-118.6481162	Valve Adjustment:Increased Flow/Vacuum;Well Comment:Pump powered off;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24088	5/28/2026 9:04:04 AM	28.49	1375	34.4335852	-118.6476383	
CV-24088	5/4/2026 1:51:55 PM	28.49	1378	34.4335923	-118.6476597	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24089	5/20/2026 11:52:44 AM	28.47	1352	34.4324820	-118.6480715	
CV-24089	5/20/2026 11:51:37 AM	28.47	1362	34.4323997	-118.6480543	
CV-24089	5/4/2026 11:15:57 AM	28.5	1302	34.4323563	-118.6481493	
CV-24089	5/4/2026 11:14:40 AM	28.5	1332	34.4323818	-118.6481067	
CV-24090	5/20/2026 11:45:41 AM	28.47	1322	34.4326190	-118.6475223	
CV-24090	5/11/2026 1:42:21 PM	28.6	1374	34.4327105	-118.6475508	Valve Adjustment:Reduce Sys. Vac. - Flare Down;Well Comment:Pump is off;Well Condition:Lorentz Pump Installed
CV-24090	5/6/2026 1:52:09 PM	28.63	1370	34.4326720	-118.6475278	Valve Adjustment:Increased Flow/Vacuum,Barely Open
CV-24091	5/21/2026 9:33:38 AM	28.43	1382	34.4329842	-118.6469030	Valve Adjustment:Barely Open,Surging Liquid in Header
CV-24091	5/4/2026 2:15:54 PM	28.47	1371	34.4330193	-118.6468302	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24092	5/6/2026 10:10:24 AM	28.55	1424	34.4332727	-118.6460750	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24093	5/22/2026 12:11:17 PM	28.37	1417	34.4340752	-118.6463935	
CV-24093	5/1/2026 3:13:57 PM	28.4	1388	34.4340903	-118.6463495	
CV-24094	5/22/2026 11:49:38 AM	28.38	1421	34.4346182	-118.6461232	
CV-24094	5/22/2026 11:48:00 AM	28.38	1470	34.4345230	-118.6460360	NSPS/EG CAI,High O2
CV-24094	5/1/2026 2:32:48 PM	28.48	1391	34.4346042	-118.6461873	
CV-24095	5/28/2026 10:32:51 AM	28.66	1272	34.4334012	-118.6513128	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Surging Liquid in Header
CV-24095	5/28/2026 10:30:18 AM	28.66	1269	34.4334028	-118.6513053	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.
CV-24095	5/20/2026 10:30:33 AM	28.66	1266	34.4333957	-118.6513129	Valve Adjustment:No Flow Measurement,High Temp
CV-24095	5/14/2026 1:28:11 PM	28.67	1252	34.4334130	-118.6512927	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Header
CV-24095	5/13/2026 10:56:02 AM	28.8	1255	34.4334041	-118.6512937	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-24095	5/13/2026 10:53:04 AM	28.8	1255	34.4334028	-118.6512965	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Positive Static Press.,Surging Liquid in Header
CV-24095	5/6/2026 10:46:15 AM	28.74	1258	34.4334102	-118.6512981	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header
CV-24095	5/6/2026 10:45:00 AM					AtmAA
CV-24095	5/6/2026 10:45:00 AM					AtmAA; [User entered 10.84%]
CV-24095	5/6/2026 8:05:00 AM					Air Tech Lab
CV-24095	5/6/2026 8:05:00 AM					Air Tech Lab; [User entered 16%]
CV-24096	5/20/2026 10:19:24 AM	28.67	1246	34.4332235	-118.6515798	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24096	5/12/2026 9:25:00 AM	28.66	1253	34.4332257	-118.6515815	NSPS/EG CAI,High O2
CV-24096	5/12/2026 9:22:51 AM	28.66	1253	34.4331845	-118.6515720	NSPS/EG CAI,High O2
CV-24097	5/20/2026 10:29:27 AM	28.66	1248	34.4327990	-118.6515542	Valve Adjustment:Barely Open
CV-24097	5/20/2026 10:28:10 AM	28.64	1250	34.4327950	-118.6515487	Valve Adjustment:Decreased Flow/Vacuum
CV-24097	5/12/2026 9:16:39 AM	28.65	1257	34.4327837	-118.6516297	NSPS/EG CAC,No Adjustment Made
CV-24097	5/12/2026 9:13:02 AM	28.65	1253	34.4327735	-118.6515830	NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 to 1 Turn
CV-24098	5/20/2026 10:43:25 AM	28.66	1253	34.4325087	-118.6513128	Valve Adjustment:Decreased Flow/Vacuum
CV-24098	5/3/2026 11:01:16 AM	28.67	1254	34.4325280	-118.6512995	Valve Adjustment:Surging Liquid in Header;Well Condition:Pnumatic Pump Installed
CV-24098	5/3/2026 11:00:24 AM	28.65	1266	34.4324950	-118.6513277	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header;Well Comment:pump fitting needs silicone to cover hole;Well Condition:Pnumatic Pump Installed
CV-24098	5/1/2026 10:01:03 AM	28.67	1248	34.4325082	-118.6513058	Valve Adjustment:Valve 100% Open,Surging Liquid in Header;Well Comment:valve stuck open
CV-24099	5/20/2026 10:48:09 AM	28.65	1256	34.4323452	-118.6509390	
CV-24099	5/3/2026 10:28:51 AM	28.67	1255	34.4323340	-118.6509515	Well Condition:Lorentz Pump Installed
CV-24099	5/3/2026 10:28:19 AM	28.68	1249	34.4323572	-118.6509205	Valve Adjustment:Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24099	5/3/2026 10:27:26 AM	28.65	1250	34.4323625	-118.6509200	Valve Adjustment:NSPS/EG CAC,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24099	5/1/2026 10:08:04 AM	28.64	1263	34.4323107	-118.6509303	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:valve stuck open
CV-24100	5/28/2026 10:02:06 AM	28.66	1264	34.4320513	-118.6504732	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24100	5/20/2026 10:01:19 AM	28.66	1264	34.4320458	-118.6504860	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-24100	5/20/2026 10:00:42 AM	28.67	1264	34.4320402	-118.6504845	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24100	5/20/2026 9:37:52 AM	28.64	1268	34.4320515	-118.6504765	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header
CV-24100	5/20/2026 9:36:36 AM	28.63	1265	34.4320508	-118.6504777	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header
CV-24100	5/13/2026 10:42:49 AM	28.8	1266	34.4320420	-118.6504906	Valve Adjustment:No Flow Measurement;Well Condition:Lorentz Pump Installed
CV-24100	5/13/2026 10:41:16 AM	28.8	1264	34.4320422	-118.6505012	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24100	5/13/2026 8:25:00 AM					Air Tech Lab
CV-24100	5/13/2026 8:25:00 AM					Air Tech Lab; [User entered 0.88%]

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24100	5/7/2026 11:06:06 AM	28.66	1272	34.4320301	-118.6504915	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-24100	5/7/2026 11:05:00 AM					AtmAA
CV-24100	5/7/2026 11:05:00 AM					AtmAA; [User entered 0.85%]
CV-24100	5/7/2026 11:04:29 AM	28.66	1273	34.4320234	-118.6504902	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24100	5/1/2026 10:25:18 AM	28.64	1261	34.4320483	-118.6504928	Valve Adjustment:High Temp,Barely Open
CV-24101	5/20/2026 9:41:50 AM	28.64	1261	34.4318263	-118.6502997	Valve Adjustment:Decreased Flow/Vacuum
CV-24101	5/12/2026 8:51:03 AM	28.65	1270	34.4318035	-118.6502830	No Flow Measurement
CV-24101	5/6/2026 7:40:00 AM					Air Tech Lab
CV-24101	5/6/2026 7:40:00 AM					Air Tech Lab; [User entered 0.094%]
CV-24101	5/1/2026 10:20:22 AM	28.64	1261	34.4318222	-118.6502932	Valve Adjustment:Valve 100% Open
CV-24102	5/19/2026 10:30:38 AM	28.69	1269	34.4316293	-118.6497903	
CV-24102	5/4/2026 9:42:22 AM	28.64	1267	34.4316275	-118.6497782	Valve Adjustment:Barely Open
CV-24103	5/20/2026 9:42:52 AM	28.6	1234	34.4316590	-118.6488628	
CV-24103	5/4/2026 9:28:18 AM	28.53	1322	34.4316217	-118.6488557	
CV-24104	5/20/2026 12:16:58 PM	28.47	1325	34.4318087	-118.6479883	
CV-24104	5/4/2026 9:39:11 AM	28.5	1283	34.4318737	-118.6481208	
CV-24105	5/20/2026 11:35:42 AM	28.48	1368	34.4318890	-118.6476013	
CV-24105	5/4/2026 9:49:47 AM	28.51	1319	34.4318910	-118.6475968	
CV-24106	5/28/2026 12:51:23 PM	28.56	1335	34.4321138	-118.6467300	Valve Comment:RES SEM;Well Comment:Cover compaction
CV-24106	5/20/2026 2:33:03 PM	28.42	1352	34.4320953	-118.6465760	
CV-24106	5/8/2026 11:07:42 AM	28.64	1388	34.4322112	-118.6467370	Reduced System Vacuum
CV-24107	5/4/2026 11:30:05 AM	28.59	1322	34.4325508	-118.6461547	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-24108	5/28/2026 12:33:54 PM	28.52	1359	34.4331548	-118.6454345	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-24108	5/4/2026 1:40:16 PM	28.56	1363	34.4331720	-118.6454428	Valve Adjustment:Orifice Plate Changed (See OP Log),Audible Flow,Barely Open
CV-24109	5/4/2026 11:58:26 AM	28.52	1380	34.4340122	-118.6448770	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-24110	5/1/2026 10:54:33 AM	28.46	1378	34.4345913	-118.6446387	
CV-24111	5/1/2026 11:14:00 AM	28.45	1391	34.4352950	-118.6450367	
CV-24112	5/1/2026 11:04:34 AM	28.46	1362	34.4351683	-118.6441708	
CV-24114	5/5/2026 2:47:36 PM	28.55	1234	34.4308157	-118.6485657	
CV-24116	5/11/2026 9:58:53 AM	28.62	1266	34.4317012	-118.6458438	
CV-24117	5/28/2026 12:44:53 PM	28.59	1298	34.4323422	-118.6449403	Valve Comment:RES SEM;Valve Adjustment:Audible Flow;Well Comment:Cover compaction
CV-24117	5/4/2026 10:48:48 AM	28.64	1294	34.4323543	-118.6449448	Valve Adjustment:Audible Flow,Barely Open;Well Condition:Good
CV-24118	5/11/2026 1:37:44 PM	28.6	1309	34.4333127	-118.6438447	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24119	5/8/2026 2:33:20 PM	28.64	1253	34.4337265	-118.6423345	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-24119	5/8/2026 2:32:34 PM	28.64	1253	34.4337367	-118.6423297	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24119	5/7/2026 10:38:27 AM	28.73	1253	34.4337712	-118.6422773	NSPS/EG CAI,High Temp
CV-24119	5/7/2026 10:35:25 AM	28.73	1266	34.4337382	-118.6423242	High Temp,NSPS/EG CAI
CV-24120	5/26/2026 2:15:09 PM	28.41	1343	34.4369008	-118.6472950	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24120	5/11/2026 10:28:50 AM	28.6	1325	34.4368377	-118.6472678	Valve Adjustment:Reduce Sys. Vac. - Flare Down;Well Comment:Pump is off;Well Condition:Lorentz Pump Installed
CV-24120	5/4/2026 8:00:00 AM					Air Tech Lab; [User entered 11%]
CV-24121	5/26/2026 2:08:29 PM	28.4	1321	34.4369917	-118.6470098	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24121	5/11/2026 10:33:56 AM	28.61	1326	34.4369493	-118.6470013	Valve Adjustment:High O2,Barely Open
CV-24121	5/11/2026 10:33:18 AM	28.61	1334	34.4369455	-118.6470150	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Reduce Sys. Vac. - Flare Down
CV-24121	5/4/2026 7:55:00 AM					Air Tech Lab; [User entered 0.27%]
CV-24122	5/29/2026 9:40:41 AM	28.67	1348	34.4371873	-118.6466763	NSPS/EG CAC,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24122	5/29/2026 9:33:20 AM	28.7	1280	34.4372067	-118.6465517	NSPS/EG CAI,High O2
CV-24122	5/6/2026 10:31:06 AM	28.68	1317	34.4371738	-118.6465920	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Surging Liquid in Header
CV-24122	5/4/2026 8:20:00 AM					Air Tech Lab; [User entered 0.91%]
CV-24123	5/28/2026 11:46:50 AM	28.59	1307	34.4373075	-118.6462547	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Well (Watered In)
CV-24123	5/28/2026 11:46:25 AM	28.59	1309	34.4373132	-118.6462478	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Well (Watered In)
CV-24123	5/15/2026 11:28:22 AM	28.69	1296	34.4373435	-118.6463497	
CV-24123	5/15/2026 11:24:46 AM	28.69	1289	34.4372963	-118.6462287	NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 to 1 Turn
CV-24123	5/14/2026 10:54:34 AM	28.67	1296	34.4373023	-118.6462322	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Valve 100% Open
CV-24123	5/14/2026 10:53:53 AM	28.66	1313	34.4373012	-118.6462247	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Valve 100% Open,Reduce Sys. Vac. - Flare Down
CV-24124	5/29/2026 11:28:31 AM	28.61	1325	34.4366833	-118.6470370	No Flow Measurement
CV-24125-TP2	5/26/2026 1:56:27 PM	28.41	1297	34.4369842	-118.6463480	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24125-TP2	5/13/2026 7:55:00 AM					Air Tech Lab
CV-24125-TP2	5/13/2026 7:55:00 AM					Air Tech Lab; [User entered 0.13%]
CV-24126	5/26/2026 10:58:38 AM	28.44	1378	34.4363846	-118.6471352	Valve Adjustment:High Temp
CV-24126	5/22/2026 12:29:20 PM	28.43	1378	34.4363843	-118.6471382	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24126	5/22/2026 12:28:40 PM	28.41	1369	34.4363798	-118.6471328	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24126	5/18/2026 10:50:00 AM					AtmAA
CV-24126	5/18/2026 10:44:28 AM	28.5	1382	34.4363798	-118.6471235	Valve Adjustment:High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down
CV-24126	5/18/2026 10:43:37 AM	28.51	1382	34.4363799	-118.6471235	Valve Adjustment:High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down
CV-24126	5/12/2026 10:30:00 AM					AtmAA
CV-24126	5/12/2026 10:28:41 AM	28.51	1372	34.4363758	-118.6471297	Valve Adjustment:High Temp
CV-24126	5/4/2026 2:50:00 PM					AtmAA
CV-24126	5/4/2026 2:50:00 PM					AtmAA; [User entered 13.58%]
CV-24126	5/4/2026 2:40:40 PM	28.48	1380	34.4363804	-118.6471332	Valve Adjustment:High Temp
CV-24127	5/7/2026 10:22:55 AM	28.56	1376	34.4364671	-118.6468331	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open
CV-24127	5/7/2026 10:21:43 AM	28.57	1376	34.4364622	-118.6468224	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum,Valve 100% Open
CV-24127	5/7/2026 10:20:00 AM					AtmAA
CV-24127	5/7/2026 10:20:00 AM					AtmAA; [User entered 15.26%]
CV-24127	5/4/2026 8:15:00 AM					Air Tech Lab; [User entered 16%]
CV-24128	5/26/2026 2:25:15 PM	28.37	1342	34.4367235	-118.6464333	Valve Adjustment:Barely Open
CV-24128	5/13/2026 7:50:00 AM					Air Tech Lab
CV-24128	5/13/2026 7:50:00 AM					Air Tech Lab; [User entered 1.1%]
CV-24128	5/8/2026 9:33:23 AM	28.61	1342	34.4367072	-118.6465008	Reduced System Vacuum
CV-24129	5/26/2026 1:33:50 PM	28.37	1361	34.4367435	-118.6461525	Valve Adjustment:Barely Open
CV-24129	5/8/2026 9:24:27 AM	28.62	1355	34.4368125	-118.6461097	Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24130	5/26/2026 1:42:41 PM	28.41	1321	34.4368173	-118.6457212	Valve Adjustment:Decreased Flow/Vacuum
CV-24131	5/29/2026 1:47:07 PM	28.69	1417	34.4368227	-118.6450578	
CV-24132	5/6/2026 10:15:34 AM	28.71	1282	34.4372393	-118.6440080	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Barely Open
CV-24133	5/7/2026 9:28:04 AM	28.7	1266	34.4374198	-118.6427065	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24134-TP1	5/26/2026 10:55:47 AM	28.47	1369	34.4363655	-118.6465137	Valve Adjustment:No Flow Measurement,High Temp
CV-24134-TP1	5/18/2026 10:45:00 AM					AtmAA
CV-24134-TP1	5/18/2026 10:39:38 AM	28.51	1389	34.4363597	-118.6465047	Valve Adjustment:No Flow Measurement,High Temp,Reduce Sys. Vac. - Flare Down
CV-24134-TP1	5/12/2026 10:35:00 AM					AtmAA

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24134-TP1	5/12/2026 10:33:32 AM	28.52	1364	34.4363682	-118.6465123	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-24134-TP1	5/12/2026 10:32:12 AM	28.51	1363	34.4363686	-118.6465143	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High O2,Increased Flow/Vacuum
CV-24134-TP1	5/11/2026 2:33:48 PM	28.5	1463	34.4358975	-118.6469445	
CV-24134-TP1	5/11/2026 2:29:03 PM	28.5	1306	34.4364227	-118.6465933	NSPS/EG CAI,High Temp
CV-24134-TP1	5/7/2026 1:15:00 PM					AtmAA
CV-24134-TP1	5/7/2026 1:14:04 PM	28.52	1365	34.4363836	-118.6465279	Valve Adjustment:No Flow Measurement,High Temp
CV-24135	5/11/2026 2:17:55 PM	28.5	1437	34.4365893	-118.6460023	
CV-24135	5/11/2026 2:15:34 PM	28.5	1476	34.4366117	-118.6459615	NSPS/EG CAI,NSPS/EG CAC,High Temp,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24136	5/11/2026 11:29:51 AM	28.56	1312	34.4366663	-118.6442622	
CV-24137	5/4/2026 1:08:31 PM	28.53	1364	34.4361537	-118.6434742	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-24137	5/4/2026 1:07:02 PM	28.52	1366	34.4361527	-118.6434890	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
CV-24138	5/28/2026 9:03:38 AM	28.63	1259	34.4342632	-118.6512275	Valve Adjustment:NSPS/EG CAI,High O2,Surging Liquid in Header
CV-24138	5/28/2026 9:02:31 AM	28.63	1259	34.4342632	-118.6512275	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-24138	5/13/2026 1:14:42 PM	28.77	1269	34.4342657	-118.6512554	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header;Well Condition:Pnumatic Pump Installed
CV-24138	5/6/2026 11:00:00 AM					AtmAA
CV-24138	5/6/2026 11:00:00 AM					AtmAA; [User entered 17.18%]
CV-24138	5/6/2026 10:58:19 AM	28.71	1267	34.4342542	-118.6512505	Valve Adjustment:No Flow Measurement,High Temp
CV-24138	5/5/2026 8:15:00 AM					Air Tech Lab
CV-24138	5/5/2026 8:15:00 AM					Air Tech Lab; [User entered 21%]
CV-24139	5/28/2026 9:08:34 AM	28.62	1271	34.4344895	-118.6511280	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum
CV-24139	5/15/2026 8:22:50 AM	28.63	1277	34.4344970	-118.6511408	Valve Adjustment:NSPS/EG CAI,High Temp,High O2;Well Comment:sensitive valve;Well Repairs:Valve
CV-24139	5/15/2026 8:12:50 AM	28.63	1269	34.4344985	-118.6511383	Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Positive Static Press.,Increased Flow/Vacuum
CV-24139	5/5/2026 8:10:00 AM					Air Tech Lab
CV-24139	5/5/2026 8:10:00 AM					Air Tech Lab; [User entered 18%]
CV-24140	5/28/2026 10:52:29 AM	28.63	1290	34.4346606	-118.6511161	Valve Adjustment:High Temp
CV-24140	5/28/2026 10:50:34 AM	28.62	1289	34.4346622	-118.6511122	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum
CV-24140	5/20/2026 1:28:20 PM	28.61	1281	34.4346751	-118.6511126	Valve Adjustment:No Flow Measurement,High Temp
CV-24140	5/20/2026 1:26:41 PM	28.62	1283	34.4346784	-118.6511216	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24140	5/13/2026 1:18:30 PM	28.76	1277	34.4346840	-118.6511326	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24140	5/6/2026 11:05:00 AM					AtmAA
CV-24140	5/6/2026 11:05:00 AM					AtmAA; [User entered 20.3%]
CV-24140	5/6/2026 11:04:58 AM	28.71	1273	34.4346804	-118.6511081	Valve Adjustment:No Flow Measurement,High Temp
CV-24140	5/5/2026 8:05:00 AM					Air Tech Lab
CV-24140	5/5/2026 8:05:00 AM					Air Tech Lab; [User entered 21%]
CV-24141	5/28/2026 9:31:07 AM	28.59	1299	34.4354908	-118.6513087	Valve Adjustment:NSPS/EG CAI,High O2
CV-24141	5/28/2026 9:30:26 AM	28.59	1296	34.4354957	-118.6513018	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum;Well Comment:no pump installed
CV-24141	5/5/2026 7:45:00 AM					Air Tech Lab
CV-24141	5/5/2026 7:45:00 AM					Air Tech Lab; [User entered 0.12%]
CV-24141	5/1/2026 8:57:18 AM	28.6	1281	34.4354885	-118.6512937	Valve Adjustment:Increased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
CV-24142	5/28/2026 10:41:54 AM	28.65	1270	34.4339722	-118.6513273	
CV-24142	5/28/2026 10:40:43 AM	28.66	1270	34.4339743	-118.6513278	Valve Adjustment:NSPS/EG CAI
CV-24142	5/20/2026 1:14:55 PM	28.62	1271	34.4339962	-118.6513468	Valve Comment:Pneumatic pump not working;Valve Adjustment:No Flow Measurement,High Temp
CV-24142	5/20/2026 1:02:37 PM	28.64	1270	34.4339787	-118.6513463	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed
CV-24142	5/15/2026 8:03:40 AM	28.63	1259	34.4339805	-118.6513398	Valve Adjustment:NSPS/EG CAI,High Temp,Valve 100% Open,Surging Liquid in Header
CV-24142	5/15/2026 7:59:13 AM	28.63	1255	34.4339758	-118.6513298	Valve Adjustment:NSPS/EG CAI,High Temp,Valve 100% Open,Surging Liquid in Header
CV-24142	5/14/2026 8:35:00 AM					AtmAA
CV-24142	5/6/2026 8:10:00 AM					Air Tech Lab
CV-24142	5/6/2026 8:10:00 AM					Air Tech Lab; [User entered 12%]
CV-24143	5/28/2026 9:20:03 AM	28.6	1286	34.4349775	-118.6512110	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open
CV-24143	5/28/2026 9:19:15 AM	28.6	1285	34.4349643	-118.6511857	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-24143	5/5/2026 7:55:00 AM					Air Tech Lab
CV-24143	5/5/2026 7:55:00 AM					Air Tech Lab; [User entered 6.1%]
CV-24143	5/1/2026 2:16:44 PM	28.52	1296	34.4350570	-118.6513283	
CV-24143	5/1/2026 2:15:01 PM	28.52	1289	34.4349098	-118.6512402	NSPS/EG CAI,High O2
CV-24144	5/20/2026 10:35:16 AM	28.66	1250	34.4325475	-118.6515890	Valve Adjustment:Valve 100% Open
CV-24144	5/12/2026 9:03:44 AM	28.67	1257	34.4324108	-118.6519563	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,No Flow Measurement
CV-24145	5/26/2026 2:12:30 PM	28.4	1362	34.4362272	-118.6496586	Valve Adjustment:NSPS/EG CAC,No Flow Measurement
CV-24145	5/18/2026 2:54:25 PM	28.51	1365	34.4362193	-118.6496297	Valve Adjustment:No Flow Measurement,High Temp
CV-24145	5/18/2026 2:45:00 PM					AtmAA

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24145	5/18/2026 2:38:58 PM	28.53	1356	34.4362236	-118.6496363	Valve Adjustment:No Flow Measurement,High Temp
CV-24145	5/12/2026 2:40:29 PM	28.58	1374	34.4362303	-118.6496176	Valve Adjustment:No Flow Measurement,High Temp
CV-24145	5/12/2026 2:34:47 PM	28.58	1373	34.4362229	-118.6496211	Valve Adjustment:No Flow Measurement,High Temp
CV-24145	5/12/2026 2:32:19 PM	28.58	1371	34.4362174	-118.6496221	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24145	5/12/2026 2:15:00 PM					AtmAA
CV-24145	5/5/2026 1:25:00 PM					AtmAA
CV-24145	5/5/2026 1:25:00 PM					AtmAA; [User entered 16.59%]
CV-24145	5/5/2026 1:22:41 PM	28.51	1363	34.4362207	-118.6496456	Valve Adjustment:High Temp
CV-24146	5/28/2026 10:15:05 AM	28.59	1314	34.4374078	-118.6463857	Valve Adjustment:Positive Static Press.,Undersized Lateral
CV-24146	5/28/2026 10:14:14 AM	28.59	1305	34.4374012	-118.6463870	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Valve 100% Open
CV-24146	5/11/2026 9:52:43 AM	28.64	1284	34.4374268	-118.6463657	Valve Adjustment:Valve 100% Open
CV-24147	5/28/2026 11:28:34 AM	28.63	1280	34.4375317	-118.6459378	Valve Comment:RES SEM;Well Comment:No system pressure
CV-24147	5/26/2026 9:21:12 AM	28.58	1287	34.4375215	-118.6459190	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-24147	5/14/2026 2:08:02 PM	28.64	1266	34.4375410	-118.6459490	Valve Comment:RES SEM;Valve Adjustment:Valve 100% Open
CV-24147	5/11/2026 10:06:39 AM	28.64	1265	34.4375288	-118.6459283	
CV-24147	5/11/2026 10:05:05 AM	28.65	1287	34.4375157	-118.6459288	Valve Adjustment:Increased Flow/Vacuum,Valve 100% Open
CV-24147	5/11/2026 10:02:23 AM	28.64	1289	34.4375118	-118.6459487	Valve Comment:Valve closed upon arrival;Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Plugged/Pinched Suspected
CV-24148	5/27/2026 1:49:59 PM	28.4	1377	34.4350742	-118.6466626	Valve Adjustment:No Flow Measurement,High Temp
CV-24148	5/19/2026 1:50:00 PM					AtmAA
CV-24148	5/19/2026 1:44:57 PM	28.58	1382	34.4350894	-118.6466738	Valve Adjustment:No Flow Measurement,High Temp
CV-24148	5/19/2026 1:43:50 PM	28.58	1381	34.4350896	-118.6466740	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24148	5/11/2026 10:02:23 AM	28.52	1394	34.4350592	-118.6466624	Valve Adjustment:No Flow Measurement,High Temp
CV-24148	5/4/2026 9:31:25 AM	28.56	1381	34.4350509	-118.6466784	Valve Adjustment:High Temp
CV-24148	5/4/2026 9:30:00 AM					AtmAA
CV-24148	5/4/2026 9:30:00 AM					AtmAA; [User entered 10.62%]
CV-24149	5/28/2026 12:48:18 PM	28.47	1434	34.4347898	-118.6469502	
CV-24149	5/6/2026 2:58:21 PM	28.56	1376	34.4347945	-118.6469973	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header
CV-24150	5/22/2026 11:53:52 AM	28.37	1375	34.4346357	-118.6456373	
CV-24150	5/1/2026 10:15:37 AM	28.61	1414	34.4346062	-118.6455488	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24151	5/21/2026 1:59:13 PM	28.41	1367	34.4344122	-118.6476300	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24151	5/6/2026 2:05:59 PM	28.6	1386	34.4344128	-118.6476310	Valve Adjustment:Surging Liquid in Header
CV-24152	5/26/2026 8:32:21 AM	28.41	1387	34.4344520	-118.6471523	Valve Adjustment:NSPS/EG CAC,Reduce Sys. Vac. - Flare Down
CV-24152	5/26/2026 8:31:06 AM	28.41	1387	34.4344575	-118.6471328	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down
CV-24152	5/6/2026 2:21:42 PM	28.56	1411	34.4344763	-118.6471860	Valve Adjustment:NSPS/EG CAC,High Temp,Barely Open,Surging Liquid in Header
CV-24152	5/6/2026 2:21:09 PM	28.56	1391	34.4344915	-118.6471960	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum,Surging Liquid in Header
CV-24153	5/22/2026 11:40:23 AM	28.41	1407	34.4344045	-118.6463667	
CV-24153	5/1/2026 3:03:06 PM	28.41	1365	34.4344288	-118.6465135	
CV-24153	5/1/2026 3:02:03 PM	28.41	1398	34.4344655	-118.6464518	NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24154	5/22/2026 11:58:09 AM	28.37	1440	34.4343248	-118.6460817	
CV-24154	5/1/2026 3:20:22 PM	28.4	1339	34.4343657	-118.6460868	
CV-24155	5/26/2026 8:18:02 AM	28.41	1389	34.4342782	-118.6467312	Valve Adjustment:Audible Flow,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
CV-24155	5/1/2026 3:09:53 PM	28.41	1424	34.4343630	-118.6468045	
CV-24155	5/1/2026 3:08:32 PM	28.41	1388	34.4343065	-118.6467873	NSPS/EG CAI,NSPS/EG CAC,Audible Flow,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24156	5/22/2026 2:00:28 PM	28.38	1427	34.4341015	-118.6477328	
CV-24156	5/4/2026 2:11:53 PM	28.51	1364	34.4340843	-118.6476997	Valve Adjustment:Barely Open
CV-24157	5/21/2026 2:09:04 PM	28.41	1393	34.4338020	-118.6473238	Valve Adjustment:NSPS/EG CAC,Barely Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
CV-24157	5/21/2026 2:08:15 PM	28.41	1389	34.4338040	-118.6473370	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Barely Open,Surging Liquid in Header
CV-24157	5/4/2026 2:00:15 PM	28.45	1387	34.4338397	-118.6473362	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24158	5/21/2026 10:58:26 AM	28.41	1393	34.4339078	-118.6470818	Valve Adjustment:NSPS/EG CAI,Barely Open
CV-24158	5/6/2026 10:59:56 AM	28.6	1396	34.4338992	-118.6470452	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24159	5/21/2026 9:02:31 AM	28.41	1401	34.4337822	-118.6466368	Valve Adjustment:High Temp,Surging Liquid in Header
CV-24159	5/21/2026 9:01:50 AM	28.41	1403	34.4337750	-118.6466390	Valve Adjustment:NSPS/EG CAI,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header
CV-24159	5/6/2026 10:49:41 AM	28.38	1371	34.4337905	-118.6465662	
CV-24160	5/22/2026 12:06:28 PM	28.37	1460	34.4337483	-118.6462070	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24160	5/6/2026 12:39:52 PM	28.63	1399	34.4338072	-118.6462550	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-24160	5/6/2026 10:29:54 AM	28.56	1388	34.4338240	-118.6461872	
CV-24161	5/6/2026 10:20:39 AM	28.56	1381	34.4338940	-118.6454970	
CV-24161	5/6/2026 10:19:18 AM	28.56	1362	34.4338600	-118.6455383	NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24162	5/4/2026 12:02:44 PM	28.52	1365	34.4335793	-118.6451230	Valve Adjustment:Decreased Flow/Vacuum
CV-24163	5/1/2026 2:33:25 PM	28.52	1338	34.4334712	-118.6444877	Valve Adjustment:NSPS/EG CAC,Barely Open;Well Condition:Lorentz Pump Installed
CV-24163	5/1/2026 2:32:24 PM	28.53	1336	34.4334823	-118.6444873	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24164	5/20/2026 2:08:15 PM	28.48	1374	34.4334770	-118.6479875	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24164	5/20/2026 2:06:56 PM	28.48	1379	34.4334703	-118.6479778	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24164	5/20/2026 11:14:31 AM	28.49	1369	34.4334945	-118.6479757	Valve Adjustment:Barely Open
CV-24164	5/4/2026 10:23:58 AM	28.52	1361	34.4334943	-118.6479645	Valve Adjustment:Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24165	5/20/2026 11:18:42 AM	28.49	1374	34.4335912	-118.6476822	Valve Adjustment:Decreased Flow/Vacuum
CV-24165	5/14/2026 11:24:07 AM	28.67	1371	34.4334927	-118.6473035	
CV-24165	5/14/2026 11:22:03 AM	28.67	1440	34.4335542	-118.6473277	NSPS/EG CAI,NSPS/EG CAC,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,High Temp,Positive Static Press.
CV-24166	5/21/2026 9:08:04 AM	28.42	1405	34.4335958	-118.6468947	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24166	5/20/2026 11:21:55 AM	28.51	1355	34.4337010	-118.6483662	Valve Adjustment:Barely Open
CV-24166	5/6/2026 10:54:07 AM	28.55	1289	34.4337443	-118.6468000	
CV-24167	5/28/2026 8:45:13 AM	28.47	1386	34.4334667	-118.6464515	Well Condition:Lorentz Pump Installed
CV-24167	5/6/2026 9:59:13 AM	28.76	1453	34.4334527	-118.6464858	
CV-24168	5/28/2026 8:59:25 AM	28.49	1389	34.4332990	-118.6472985	Well Condition:Lorentz Pump Installed
CV-24168	5/6/2026 10:55:15 AM	28.61	1406	34.4333458	-118.6473238	Valve Adjustment:Barely Open,Surging Liquid in Header
CV-24169	5/20/2026 11:11:16 AM	28.49	1383	34.4332078	-118.6477205	Valve Adjustment:Barely Open
CV-24169	5/4/2026 10:19:18 AM	28.52	1375	34.4331917	-118.6477157	Valve Adjustment:Barely Open
CV-24170	5/21/2026 9:20:08 AM	28.48	1368	34.4331183	-118.6485037	Valve Adjustment:Barely Open
CV-24170	5/6/2026 8:37:17 AM	28.63	1372	34.4331162	-118.6485155	Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum,Barely Open
CV-24170	5/1/2026 10:56:54 AM	28.56	1363	34.4331005	-118.6484957	Valve Adjustment:Barely Open
CV-24171	5/21/2026 9:23:58 AM	28.45	1406	34.4331897	-118.6466525	Valve Comment:well too tall
CV-24171	5/6/2026 10:03:52 AM	28.55	1411	34.4332255	-118.6466338	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24172	5/21/2026 10:00:21 AM	28.41	1377	34.4329367	-118.6473203	Valve Adjustment:Barely Open

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24172	5/4/2026 2:28:48 PM	28.46	1404	34.4330085	-118.6473612	
CV-24173	5/21/2026 10:06:44 AM	28.45	1383	34.4328933	-118.6476563	Valve Comment:well too tall for system read
CV-24173	5/6/2026 1:00:35 PM	28.63	1387	34.4328932	-118.6476568	Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum
CV-24174	5/21/2026 10:15:48 AM	28.44	1379	34.4327447	-118.6480342	Valve Adjustment:Barely Open
CV-24174	5/11/2026 1:20:08 PM	28.63	1375	34.4327227	-118.6480538	Valve Adjustment:Reduce Sys. Vac. - Flare Down;Well Comment:pump is off;Well Condition:Lorentz Pump Installed
CV-24175	5/21/2026 10:19:57 AM	28.45	1362	34.4326887	-118.6484998	Valve Adjustment:Barely Open
CV-24175	5/5/2026 1:28:08 PM	28.53	1382	34.4326552	-118.6484768	Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24175	5/5/2026 1:26:42 PM	28.52	1382	34.4326533	-118.6484855	Valve Comment:secured lorentz fitting;Valve Adjustment:Increased Flow/Vacuum;Well Comment:pump is active.;Well Condition:Lorentz Pump Installed
CV-24175	5/5/2026 1:21:04 PM	28.53	1382	34.4326548	-118.6484853	Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum;Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24175	5/5/2026 1:13:21 PM	28.53	1362	34.4326723	-118.6484765	Valve Adjustment:Increased Flow/Vacuum;Well Comment:Pump is active;Well Condition:Lorentz Pump Installed
CV-24176	5/20/2026 10:16:41 AM	28.5	1391	34.4326228	-118.6489318	
CV-24176	5/20/2026 10:14:10 AM	28.5	1404	34.4326493	-118.6489970	NSPS/EG CAI,NSPS/EG CAC,High Temp
CV-24176	5/8/2026 11:05:11 AM	28.54	1322	34.4326280	-118.6489067	
CV-24176	5/8/2026 11:03:01 AM	28.54	1352	34.4325257	-118.6489255	NSPS/EG CAI,NSPS/EG CAC,Audible Flow,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 to 1 Turn
CV-24177	5/20/2026 8:06:52 AM	28.56	1306	34.4322462	-118.6494580	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-24177	5/20/2026 7:56:33 AM	28.57	1320	34.4322548	-118.6494448	Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Decreased Flow/Vacuum
CV-24177	5/8/2026 11:20:50 AM	28.57	1332	34.4322813	-118.6494228	
CV-24177	5/8/2026 11:19:26 AM	28.57	1355	34.4322503	-118.6493363	Reduced System Vacuum,NSPS/EG CAI,NSPS/EG CAC,High O2
CV-24178	5/20/2026 12:02:57 PM	28.48	1385	34.4323280	-118.6486115	
CV-24178	5/20/2026 12:01:45 PM	28.48	1417	34.4323233	-118.6486002	NSPS/EG CAI,NSPS/EG CAC,High Temp
CV-24178	5/8/2026 10:58:25 AM	28.55	1430	34.4324165	-118.6486865	Reduced System Vacuum
CV-24179	5/20/2026 9:55:47 AM	28.51	1286	34.4320667	-118.6492728	
CV-24179	5/4/2026 1:09:48 PM	28.57	1340	34.4321117	-118.6492078	
CV-24179	5/4/2026 1:08:00 PM	28.6	1330	34.4321170	-118.6492072	Valve Adjustment:Increased Flow/Vacuum
CV-24179	5/4/2026 1:03:56 PM	28.58	1341	34.4321288	-118.6492127	Valve Adjustment:Barely Open
CV-24180	5/20/2026 10:03:08 AM	28.53	1348	34.4321713	-118.6488025	
CV-24180	5/8/2026 10:53:15 AM	28.65	1335	34.4321552	-118.6487778	Reduced System Vacuum
CV-24181	5/20/2026 12:05:54 PM	28.48	1421	34.4321825	-118.6483900	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24181	5/4/2026 11:08:54 AM	28.53	1276	34.4321710	-118.6484342	
CV-24182	5/22/2026 10:34:25 AM	28.4	1358	34.4323000	-118.6481662	
CV-24182	5/4/2026 11:12:00 AM	28.5	1299	34.4322548	-118.6480292	
CV-24183	5/20/2026 11:42:38 AM	28.48	1375	34.4323228	-118.6476718	
CV-24183	5/4/2026 11:26:46 AM	28.51	1362	34.4324333	-118.6476603	
CV-24184	5/28/2026 1:18:12 PM	28.52	1378	34.4325162	-118.6472783	Valve Adjustment:NSPS/EG CAI,High Temp,High O2
CV-24184	5/28/2026 1:16:04 PM	28.52	1373	34.4325148	-118.6472750	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Decreased Flow/Vacuum
CV-24184	5/20/2026 11:25:50 AM	28.48	1362	34.4325758	-118.6472723	
CV-24184	5/20/2026 11:24:32 AM	28.48	1417	34.4325943	-118.6472117	High Temp
CV-24184	5/20/2026 11:22:55 AM	28.48	1250	34.4325003	-118.6471720	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.
CV-24184	5/4/2026 1:19:41 PM	28.65	1309	34.4325610	-118.6473778	
CV-24184	5/4/2026 1:18:22 PM	28.65	1322	34.4325152	-118.6473015	NSPS/EG CAI,High Temp
CV-24185	5/20/2026 2:14:16 PM	28.43	1385	34.4327108	-118.6468708	
CV-24185	5/20/2026 2:12:58 PM	28.43	1368	34.4323010	-118.6466718	NSPS/EG CAI,NSPS/EG CAC,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,Positive Static Press.
CV-24185	5/4/2026 1:26:49 PM	28.49	1371	34.4326090	-118.6469768	
CV-24186	5/20/2026 2:18:02 PM	28.42	1398	34.4327695	-118.6464922	
CV-24186	5/4/2026 2:56:41 PM	28.47	1385	34.4328797	-118.6466523	
CV-24187	5/19/2026 10:36:55 AM	28.65	1311	34.4318815	-118.6495770	
CV-24187	5/4/2026 10:28:37 AM	28.63	1302	34.4318867	-118.6495672	
CV-24187	5/4/2026 10:27:50 AM	28.62	1302	34.4318867	-118.6495672	Valve Adjustment:Increased Flow/Vacuum
CV-24187	5/4/2026 10:19:29 AM	28.61	1297	34.4318708	-118.6495668	Valve Adjustment:Barely Open
CV-24188	5/20/2026 12:45:56 PM	28.61	1242	34.4315378	-118.6501282	Well Repairs:Sample Port
CV-24188	5/20/2026 8:59:37 AM	28.64	1239	34.4315653	-118.6500917	Valve Adjustment:Increased Flow/Vacuum
CV-24188	5/4/2026 9:36:30 AM	28.66	1241	34.4315288	-118.6501175	
CV-24188	5/4/2026 9:34:45 AM	28.64	1241	34.4315468	-118.6501070	Valve Adjustment:Increased Flow/Vacuum
CV-24189	5/20/2026 8:49:58 AM	28.64	1252	34.4313387	-118.6499855	
CV-24189	5/4/2026 9:28:20 AM	28.64	1253	34.4312907	-118.6500002	
CV-24190	5/19/2026 10:21:44 AM	28.68	1294	34.4316022	-118.6494635	
CV-24190	5/4/2026 10:10:47 AM	28.61	1295	34.4316097	-118.6494683	
CV-24192	5/22/2026 10:15:13 AM	28.29	1388	34.4312343	-118.6494792	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24192	5/4/2026 10:02:40 AM	28.62	1280	34.4313497	-118.6494815	
CV-24192	5/4/2026 10:01:48 AM	28.62	1291	34.4313327	-118.6494998	Valve Comment:Reduced system vacuum;Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum
CV-24192	5/4/2026 9:58:01 AM	28.62	1288	34.4313643	-118.6494618	Valve Adjustment:Increased Flow/Vacuum
CV-24193	5/19/2026 2:15:47 PM	28.63	1301	34.4315485	-118.6490550	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24193	5/4/2026 9:13:38 AM	28.63				Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24194	5/20/2026 12:10:04 PM	28.47	1358	34.4317543	-118.6484903	Orifice Plate Changed (See OP Log)
CV-24194	5/5/2026 1:47:55 PM	28.55	1349	34.4318795	-118.6485242	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-24194	5/4/2026 9:33:10 AM	28.51	1348	34.4318285	-118.6484785	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24195	5/28/2026 1:01:56 PM	28.54	1335	34.4318083	-118.6478583	Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum
CV-24195	5/20/2026 12:23:03 PM	28.47	1427	34.4318705	-118.6479115	
CV-24195	5/4/2026 9:46:22 AM	28.5	1339	34.4318115	-118.6479018	
CV-24196	5/28/2026 12:55:54 PM	28.55	1341	34.4320625	-118.6471805	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-24196	5/20/2026 11:31:51 AM	28.49	1325	34.4320827	-118.6471262	
CV-24196	5/4/2026 11:32:25 AM	28.52	1348	34.4320408	-118.6471408	
CV-24197	5/22/2026 10:52:22 AM	28.49	1345	34.4323348	-118.6465855	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24197	5/8/2026 11:18:02 AM	28.64	1362	34.4325160	-118.6463473	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24198	5/22/2026 10:50:58 AM	28.43	1362	34.4318115	-118.6472943	
CV-24198	5/8/2026 10:50:53 AM	28.66	1332	34.4315565	-118.6475795	Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24199	5/22/2026 10:41:08 AM	28.41	1355	34.4317905	-118.6472448	
CV-24199	5/8/2026 10:55:45 AM	28.65	1296	34.4317453	-118.6473035	Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,Audible Flow
CV-24200	5/22/2026 9:57:47 AM	28.55	1283	34.4314867	-118.6471573	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24200	5/6/2026 2:43:38 PM	28.72	1368	34.4314878	-118.6471517	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24201	5/22/2026 10:05:48 AM	28.56	1247	34.4317160	-118.6466007	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24201	5/6/2026 3:11:02 PM	28.63	1280	34.4318032	-118.6466470	
CV-24202	5/22/2026 10:29:59 AM	28.55	1247	34.4319450	-118.6462482	No Flow Measurement
CV-24202	5/6/2026 3:17:39 PM	28.62	1309	34.4319817	-118.6462840	
CV-24203	5/22/2026 9:36:46 AM	28.63	1250	34.4315252	-118.6460367	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24203	5/11/2026 10:07:30 AM	28.62	1217	34.4314643	-118.6462402	
CV-24204	5/22/2026 9:39:46 AM	28.61	1227	34.4314417	-118.6462805	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24204	5/11/2026 10:10:41 AM	28.63	1270	34.4314382	-118.6462517	
CV-24205	5/22/2026 9:45:39 AM	28.61	1237	34.4312217	-118.6464452	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24205	5/6/2026 12:13:07 PM	28.63	1198	34.4313107	-118.6465557	
CV-24206	5/22/2026 10:00:36 AM	28.55	1302	34.4314912	-118.6467710	No Flow Measurement,No Adjustment Made
CV-24206	5/6/2026 3:04:18 PM	28.6	1299	34.4315113	-118.6467672	
CV-24207	5/21/2026 9:17:20 AM	28.45	1412	34.4332568	-118.6469433	Valve Adjustment:NSPS/EG CAC,Surging Liquid in Header

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24207	5/21/2026 9:15:43 AM	28.44	1392	34.4332723	-118.6469215	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24207	5/4/2026 2:35:22 PM	28.45	1421	34.4333115	-118.6469225	
CV-24208	5/4/2026 10:58:55 AM	28.67	1246	34.4319048	-118.6451103	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-24209	5/4/2026 11:15:06 AM	28.63	1300	34.4321958	-118.6456132	Valve Adjustment:Audible Flow,Barely Open
CV-24210	5/5/2026 1:26:15 PM	28.56	1334	34.4326427	-118.6455938	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-24210	5/4/2026 11:34:40 AM	28.59	1334	34.4326327	-118.6455760	Valve Adjustment:Barely Open
CV-24211	5/7/2026 10:23:15 AM	28.73	1260	34.4327410	-118.6437678	
CV-24212	5/11/2026 9:45:09 AM	28.6	1273	34.4331760	-118.6431025	
CV-24212	5/11/2026 9:43:52 AM	28.6	1224	34.4331448	-118.6431658	High Temp
CV-24213	5/1/2026 1:55:50 PM	28.56	1319	34.4366047	-118.6429695	Valve Comment:belly was cleared;Valve Adjustment:NSPS/EG CAC
CV-24213	5/1/2026 1:54:28 PM	28.56	1322	34.4366003	-118.6429628	Valve Adjustment:NSPS/EG CAC
CV-24213	5/1/2026 1:34:20 PM	28.67	1321	34.4365922	-118.6429718	
CV-24213	5/1/2026 1:32:27 PM	28.65	1321	34.4366045	-118.6429675	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Header;Well Comment:Lateral is bellied and watered in. Created a maintenance form for well.
CV-24214	5/26/2026 12:44:02 PM	28.45	1305	34.4367725	-118.6434542	
CV-24214	5/26/2026 12:41:30 PM	28.45	1322	34.4367697	-118.6434888	Valve Adjustment:Decreased Flow/Vacuum
CV-24215	5/29/2026 9:58:57 AM	28.67	1302	34.4368545	-118.6448328	No Adjustment Made
CV-24216	5/1/2026 1:59:49 PM	28.66	1303	34.4368142	-118.6423178	Valve Adjustment:Audible Flow,No Flow Measurement
CV-24217	5/11/2026 1:45:32 PM	28.48	1381	34.4359698	-118.6446735	
CV-24217	5/11/2026 1:25:59 PM	28.52	1388	34.4359297	-118.6444033	Valve Adjustment:Barely Open
CV-24217	5/11/2026 10:19:12 AM	28.63	1387	34.4359400	-118.6443795	Valve Adjustment:Decreased Flow/Vacuum
CV-24218	5/8/2026 8:42:59 AM	28.6	1385	34.4358460	-118.6457933	Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,No Flow Measurement
CV-24219	5/27/2026 2:44:32 PM	28.39	1386	34.4350911	-118.6462439	Valve Comment:Lorentz pump on upon arrival;Valve Adjustment:No Flow Measurement,High Temp,Barely Open;Well Condition:Lorentz Pump Installed
CV-24219	5/19/2026 1:10:00 PM					AtmAA
CV-24219	5/19/2026 1:07:47 PM	28.58	1398	34.4350971	-118.6462268	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Valve 100% Open
CV-24219	5/19/2026 1:07:21 PM	28.59	1397	34.4350970	-118.6462269	Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Increased Flow/Vacuum,Valve 100% Open
CV-24219	5/11/2026 9:27:37 AM	28.53	1397	34.4351058	-118.6462183	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24219	5/11/2026 9:26:02 AM	28.52	1396	34.4351090	-118.6462179	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24219	5/4/2026 8:40:00 AM					AtmAA
CV-24219	5/4/2026 8:40:00 AM					AtmAA; [User entered 10.57%]
CV-24219	5/4/2026 8:37:52 AM	28.5	1386	34.4351322	-118.6462394	Valve Adjustment:Audible Flow,High Temp
CV-24220	5/1/2026 2:28:38 PM	28.52	1350	34.4339808	-118.6439567	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24220	5/1/2026 2:26:20 PM	28.52	1347	34.4339868	-118.6439660	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24221	5/7/2026 10:47:53 AM	28.73	1270	34.4341442	-118.6420920	Reduced System Vacuum,No Adjustment Made
CV-24222	5/11/2026 9:28:59 AM	28.69	1263	34.4336818	-118.6419815	Increased Flow/Vacuum,Opened Valve 1/2 to 1 Turn
CV-24223	5/11/2026 9:35:14 AM	28.6	1224	34.4334745	-118.6425050	
CV-24224	5/1/2026 2:36:53 PM	28.54	1337	34.4331895	-118.6448165	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum;Well Condition:Good,Lorentz Pump Installed
CV-24225	5/4/2026 10:44:54 AM	28.66	1283	34.4327052	-118.6444193	Valve Adjustment:Audible Flow;Well Condition:Fair
CV-24226	5/7/2026 10:18:42 AM	28.74	1247	34.4325075	-118.6443080	No Adjustment Made
CV-24227	5/8/2026 11:27:46 AM	28.59	1224	34.4308177	-118.6498410	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24231	5/5/2026 2:20:38 PM	28.68	1260	34.4302390	-118.6496235	
CV-24236	5/7/2026 9:58:34 AM	28.7	1273	34.4300488	-118.6503772	
CV-24237	5/7/2026 10:03:50 AM	28.68	1270	34.4307407	-118.6503562	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24243	5/8/2026 10:05:46 AM	28.7	1201	34.4287652	-118.6506448	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24244	5/7/2026 11:23:42 AM	28.67	1194	34.4290022	-118.6513967	Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-24245	5/7/2026 2:21:55 PM	28.69	1148	34.4284755	-118.6500290	Reduced System Vacuum
CV-24246	5/7/2026 2:17:13 PM	28.69	1178	34.4287440	-118.6494585	Reduced System Vacuum
CV-24253	5/7/2026 2:35:07 PM	28.72	1227	34.4283225	-118.6499175	Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-25	5/13/2026 1:44:59 PM	28.76	1266	34.4370112	-118.6420990	Valve Comment:Tighten valve;Well Repairs:Sample Port
CV-2501	5/4/2026 9:55:50 AM	28.51	1355	34.4313038	-118.6484687	
CV-2502	5/4/2026 10:08:04 AM	28.54	1375	34.4308270	-118.6490368	
CV-2503	5/6/2026 2:52:46 PM	28.61	1339	34.4312688	-118.6476768	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-2504	5/5/2026 2:41:25 PM	28.58	1152	34.4303907	-118.6489443	
CV-2505	5/5/2026 2:55:39 PM	28.59	1240	34.4308042	-118.6471923	
CV-2506	5/5/2026 3:55:25 PM	28.6	1152	34.4305400	-118.6475997	
CV-2507	5/8/2026 1:37:11 PM	28.72	1188	34.4301410	-118.6481617	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-2507	5/5/2026 3:50:55 PM	28.59	1198	34.4301758	-118.6481212	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-2508	5/5/2026 3:46:09 PM	28.63	1188	34.4297138	-118.6487778	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-2509	5/8/2026 1:42:52 PM	28.74	1164	34.4292580	-118.6491703	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-2509	5/5/2026 3:31:32 PM	28.6	1148	34.4293525	-118.6491663	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-2510	5/8/2026 1:46:50 PM	28.74	1180	34.4290760	-118.6498257	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-2510	5/5/2026 2:25:18 PM	28.71	1185	34.4290762	-118.6498040	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum;Well Condition:Good
CV-25100D	5/18/2026 10:35:31 AM	28.51	1385	34.4361625	-118.6471403	Valve Adjustment:No Flow Measurement
CV-25100D	5/12/2026 10:22:21 AM	28.52	1373	34.4361728	-118.6471453	Valve Adjustment:No Flow Measurement,High Temp
CV-25100D	5/12/2026 10:20:00 AM					AtmAA
CV-25100D	5/8/2026 9:54:19 AM	28.6	1381	34.4361410	-118.6471367	
CV-25100D	5/8/2026 9:52:49 AM	28.6	1398	34.4361082	-118.6470927	
CV-25100S	5/26/2026 10:48:42 AM	28.47	1375	34.4361484	-118.6471281	Valve Adjustment:No Flow Measurement,High Temp
CV-25100S	5/26/2026 10:48:08 AM	28.47	1376	34.4361512	-118.6471268	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-25100S	5/18/2026 10:40:00 AM					AtmAA
CV-25100S	5/18/2026 10:33:27 AM	28.51	1384	34.4361428	-118.6471385	Valve Adjustment:No Flow Measurement,High Temp
CV-25100S	5/12/2026 10:25:18 AM	28.52	1375	34.4361666	-118.6471482	Valve Adjustment:No Flow Measurement,High Temp
CV-25100S	5/12/2026 10:25:00 AM					AtmAA
CV-25100S	5/8/2026 10:01:43 AM	28.6	1362	34.4362412	-118.6471998	
CV-25100S	5/8/2026 10:00:14 AM	28.6	1371	34.4361457	-118.6471048	
CV-25100S	5/4/2026 2:45:00 PM					AtmAA
CV-25100S	5/4/2026 2:45:00 PM					AtmAA; [User entered 13.82%]
CV-25100S	5/4/2026 2:38:27 PM	28.51	1384	34.4361628	-118.6471271	Valve Adjustment:No Flow Measurement,High Temp
CV-25101D	5/22/2026 10:43:56 AM	28.37	1394	34.4359927	-118.6467905	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25101D	5/12/2026 1:33:31 PM	28.63	1392	34.4359830	-118.6467840	Valve Comment:Well is suspected to be watered in;Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Well (Watered In);Well Comment:No pump installed
CV-25101S	5/22/2026 10:46:24 AM	28.37	1398	34.4359848	-118.6467945	Valve Adjustment:Barely Open
CV-25101S	5/12/2026 1:23:51 PM	28.63	1391	34.4359960	-118.6467880	Valve Adjustment:Decreased Flow/Vacuum
CV-25102_	5/20/2026 2:05:47 PM	28.44	1375	34.4357913	-118.6471962	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25102_	5/8/2026 10:11:54 AM	28.6	1375	34.4357355	-118.6472145	
CV-25102_	5/8/2026 10:09:29 AM	28.6	1394	34.4357597	-118.6471285	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-25103	5/22/2026 11:13:05 AM	28.41	1367	34.4346380	-118.6477068	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25103	5/20/2026 1:53:20 PM	28.41	1396	34.4356702	-118.6466980	Valve Adjustment:Increased Flow/Vacuum,Barely Open
CV-25103	5/12/2026 10:47:21 AM	28.61	1385	34.4356583	-118.6467003	Valve Adjustment:NSPS/EG CAC
CV-25103	5/12/2026 10:45:57 AM	28.59	1382	34.4356737	-118.6466958	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-25104D	5/20/2026 2:32:23 PM	28.44	1380	34.4353553	-118.6472522	
CV-25104D	5/13/2026 9:49:44 AM	28.71	1379	34.4353555	-118.6472503	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:No pump
CV-25104S	5/20/2026 2:35:06 PM	28.44	1380	34.4353553	-118.6472522	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25104S	5/13/2026 9:54:31 AM	28.71	1372	34.4353733	-118.6472362	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:No pump
CV-25105D	5/22/2026 10:19:59 AM	28.37	1404	34.4353722	-118.6466995	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25105D	5/8/2026 8:27:56 AM	28.58	1371	34.4352940	-118.6467577	
CV-25105S	5/20/2026 1:43:43 PM	28.41	1392	34.4353708	-118.6467107	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25105S	5/8/2026 8:30:20 AM	28.5	1378	34.4353882	-118.6467118	
CV-25106D	5/26/2026 9:05:29 AM	28.43	1379	34.4350615	-118.6473708	Valve Adjustment:NSPS/EG CAI,High O2,Reduce Sys. Vac. - Flare Down
CV-25106D	5/26/2026 9:03:18 AM	28.43	1384	34.4350633	-118.6473718	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down
CV-25106D	5/12/2026 2:19:11 PM	28.67	1359	34.4350400	-118.6473762	
CV-25106D	5/12/2026 2:18:07 PM	28.67	1357	34.4350470	-118.6473775	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In);Well Comment:No pump installed
CV-25106S	5/26/2026 9:12:30 AM	28.42	1375	34.4350495	-118.6473688	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Reduce Sys. Vac. - Flare Down
CV-25106S	5/26/2026 9:11:40 AM	28.42	1379	34.4350568	-118.6473650	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down
CV-25106S	5/12/2026 2:25:06 PM	28.67	1366	34.4350378	-118.6473582	
CV-25106S	5/12/2026 2:23:49 PM	28.67	1367	34.4350492	-118.6473735	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In);Well Comment:No pump installed
CV-25107D	5/1/2026 2:47:38 PM	28.4	1375	34.4351265	-118.6459852	
CV-25107S	5/1/2026 2:50:28 PM	28.4	1358	34.4350663	-118.6458963	
CV-2511	5/5/2026 2:33:06 PM	28.59	1230	34.4296735	-118.6501605	
CV-2512	5/5/2026 2:28:36 PM	28.59	1250	34.4292710	-118.6506313	
CV-2513	5/7/2026 3:05:57 PM	28.69	1125	34.4288815	-118.6487923	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-2514	5/8/2026 2:58:55 PM	28.71	1129	34.4296507	-118.6479342	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-2515	5/7/2026 9:16:53 AM	28.7	1266	34.4379218	-118.6432498	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-2516	5/11/2026 11:15:10 AM	28.63	1306	34.4374927	-118.6432372	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-2517	5/7/2026 9:40:45 AM	28.72	1273	34.4369217	-118.6420542	No Adjustment Made
CV-2518	5/7/2026 10:00:08 AM	28.75	1234	34.4363728	-118.6414252	NSPS/EG CAC,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-2518	5/7/2026 9:57:35 AM	28.75	1243	34.4363833	-118.6414300	NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 to 1 Turn
CV-2519	5/1/2026 1:11:22 PM	28.67	1299	34.4361448	-118.6420415	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-2520	5/1/2026 1:26:15 PM	28.67	1309	34.4358838	-118.6428112	Valve Adjustment:NSPS/EG CAC,High Temp
CV-2520	5/1/2026 1:25:06 PM	28.65	1318	34.4358822	-118.6427960	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-2521	5/26/2026 12:24:46 PM	28.45	1320	34.4354940	-118.6430322	
CV-2522	5/5/2026 12:53:32 PM	28.63	1293	34.4355363	-118.6424013	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-2522	5/1/2026 10:59:06 AM	28.71	1293	34.4355315	-118.6423892	Valve Adjustment:NSPS/EG CAC,High Temp
CV-2522	5/1/2026 10:57:27 AM	28.71	1283	34.4355267	-118.6423915	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-2523	5/4/2026 2:07:42 PM	28.63	1278	34.4357013	-118.6416728	Valve Adjustment:Audible Flow,Increased Flow/Vacuum;Well Condition:Good
CV-2524	5/1/2026 10:45:46 AM	28.71	1282	34.4348065	-118.6425145	Valve Adjustment:NSPS/EG CAC,High Temp
CV-2524	5/1/2026 10:44:23 AM	28.71	1277	34.4348058	-118.6425205	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-2525	5/4/2026 2:13:54 PM	28.64	1276	34.4350133	-118.6417385	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-2525	5/4/2026 2:13:24 PM	28.64	1272	34.4350155	-118.6417368	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
CV-2526	5/4/2026 2:18:08 PM	28.65	1269	34.4345572	-118.6415907	Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Barely Open
CV-2527	5/15/2026 11:27:42 AM	28.64	1325	34.4341018	-118.6428870	
CV-2528	5/11/2026 8:25:29 AM	28.69	1243	34.4338085	-118.6412588	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-2529	5/8/2026 12:47:59 PM	28.71	1222	34.4331330	-118.6423445	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-2530	5/12/2026 7:58:10 AM	28.68	1260	34.4327550	-118.6429390	No Flow Measurement
CV-2531	5/8/2026 12:35:03 PM	28.71	1207	34.4325265	-118.6433380	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAC,Audible Flow,Barely Open,Surging Liquid in Header

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-2531	5/8/2026 12:34:13 PM	28.71	1219	34.4325375	-118.6433560	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
CV-2532	5/12/2026 7:54:00 AM	28.68	1247	34.4322183	-118.6437638	No Flow Measurement
CV-2533	5/12/2026 7:48:32 AM	28.69	1230	34.4319207	-118.6441120	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-2534	5/11/2026 2:17:18 PM	28.84	1221	34.4317063	-118.6444812	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-2535	5/5/2026 2:52:23 PM	28.56	1201	34.4310167	-118.6469827	
CV-2536	5/14/2026 10:27:30 AM	28.81	1125	34.4309465	-118.6458117	
CV-2537	5/6/2026 12:17:48 PM	28.71	1270	34.4310645	-118.6466235	
CV-2538	5/6/2026 12:25:17 PM	28.71	1184	34.4308127	-118.6467563	
CV-2539	5/20/2026 9:49:24 AM	28.51	1339	34.4317478	-118.6491623	
CV-2539	5/4/2026 9:17:28 AM	28.53				
CV-2540	5/20/2026 2:18:42 PM	28.46	1370	34.4332802	-118.6480973	Valve Adjustment:NSPS/EG CAI,Barely Open
CV-2540	5/20/2026 2:15:08 PM	28.48	1373	34.4332657	-118.6480898	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open
CV-2540	5/14/2026 1:17:10 PM	28.67	1370	34.4332643	-118.6481005	Valve Adjustment:NSPS/EG CAC
CV-2540	5/14/2026 1:13:24 PM	28.67	1373	34.4332743	-118.6481005	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Well (Watered In)
CV-2541	5/19/2026 9:38:49 AM	28.63	1346	34.4332705	-118.6490412	Well Repairs:Sample Port
CV-2541	5/19/2026 9:36:57 AM	28.62	1350	34.4332710	-118.6490418	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp,Decreased Flow/Vacuum
CV-2541	5/1/2026 11:15:47 AM	28.58	1333	34.4332740	-118.6490530	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Well (Watered In)
CV-2541	5/1/2026 11:15:26 AM	28.59	1335	34.4332715	-118.6490500	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Well (Watered In)
CV-2542	5/21/2026 2:04:28 PM	28.4	1393	34.4337050	-118.6471915	Valve Adjustment:Barely Open,Surging Liquid in Header
CV-2542	5/4/2026 1:56:22 PM	28.48	1381	34.4337153	-118.6471642	Valve Adjustment:Decreased Flow/Vacuum
CV-2543-PLR	5/20/2026 1:43:43 PM	28.5	1351	34.4338193	-118.6484695	Valve Comment:sensitive valve;Valve Adjustment:Decreased Flow/Vacuum
CV-2543-PLR	5/4/2026 9:50:49 AM	28.56	1337	34.4338390	-118.6484637	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:Possible damaged valve
CV-2544	5/21/2026 1:52:17 PM	28.41	1387	34.4340332	-118.6472325	Valve Adjustment:NSPS/EG CAC,Surging Liquid in Header
CV-2544	5/21/2026 1:51:00 PM	28.41	1378	34.4340130	-118.6472433	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Header
CV-2544	5/6/2026 11:06:39 AM	28.6	1406	34.4340442	-118.6472338	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2545	5/22/2026 12:19:27 PM	28.36	1404	34.4339908	-118.6466957	
CV-2545	5/22/2026 12:15:46 PM	28.36	1407	34.4340295	-118.6467170	NSPS/EG CAI,NSPS/EG CAC,High Temp
CV-2545	5/6/2026 2:44:01 PM	28.54	1393	34.4340488	-118.6467080	Valve Adjustment:NSPS/EG CAC,Barely Open,Surging Liquid in Header

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-2545	5/6/2026 2:43:10 PM	28.54	1404	34.4340650	-118.6467367	Valve Adjustment:Increased Flow/Vacuum,Reduce Sys. Vac. - Flare Down
CV-2546	5/22/2026 12:25:12 PM	28.37	1358	34.4341263	-118.6470320	
CV-2546	5/22/2026 12:24:00 PM	28.37	1391	34.4341160	-118.6470045	NSPS/EG CAI,NSPS/EG CAC,High Temp
CV-2546	5/6/2026 2:35:53 PM	28.56	1388	34.4341570	-118.6469667	Valve Adjustment:Barely Open
CV-2547	5/28/2026 12:23:14 PM	28.48	1390	34.4339535	-118.6459753	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-2547	5/22/2026 12:03:11 PM	28.37	1385	34.4338917	-118.6459037	
CV-2547	5/6/2026 10:25:52 AM	28.56	1381	34.4338955	-118.6459930	
CV-2548	5/13/2026 9:58:56 AM	28.65	1397	34.4343410	-118.6455860	Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum,Barely Open
CV-2548	5/1/2026 10:34:59 AM	28.46	1404	34.4344290	-118.6456162	
CV-2549	5/28/2026 12:13:13 PM	28.48	1396	34.4343867	-118.6452610	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-2549	5/13/2026 9:51:28 AM	28.63	1395	34.4343673	-118.6452592	Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum,Barely Open;Well Condition:Good
CV-2549	5/6/2026 12:31:15 PM	28.62	1395	34.4343742	-118.6452492	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Barely Open;Well Condition:Good
CV-2549	5/1/2026 10:30:41 AM	28.45	1424	34.4344408	-118.6452425	
CV-2550	5/27/2026 1:19:05 PM	28.36	1388	34.4348365	-118.6462116	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header
CV-2550	5/21/2026 10:06:57 AM	28.5	1388	34.4348114	-118.6461624	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Surging Liquid in Well (Watered In)
CV-2550	5/21/2026 10:04:40 AM	28.5	1389	34.4348143	-118.6461615	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-2550	5/11/2026 9:52:55 AM	28.53	1390	34.4347874	-118.6461669	Valve Adjustment:No Flow Measurement,High Temp
CV-2550	5/4/2026 9:00:00 AM					AtmAA
CV-2550	5/4/2026 8:59:59 AM	28.52	1386	34.4348107	-118.6461652	Valve Adjustment:Audible Flow,No Flow Measurement,High Temp
CV-2551	5/1/2026 2:40:59 PM	28.29	1411	34.4349613	-118.6458458	
CV-2551	5/1/2026 2:39:32 PM	28.29	1417	34.4349245	-118.6458108	High Temp,Audible Flow
CV-2552	5/19/2026 1:50:38 PM	28.58	1391	34.4348880	-118.6465470	Valve Adjustment:NSPS/EG CAC,No Flow Measurement
CV-2552	5/19/2026 1:49:24 PM	28.58	1387	34.4348881	-118.6465428	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,Increased Flow/Vacuum
CV-2552	5/11/2026 9:58:44 AM	28.52	1402	34.4348833	-118.6465278	Valve Adjustment:No Flow Measurement,High Temp
CV-2552	5/4/2026 9:36:17 AM	28.55	1388	34.4348703	-118.6465369	Valve Adjustment:High Temp
CV-2552	5/4/2026 9:35:00 AM					AtmAA
CV-2552	5/4/2026 9:35:00 AM					AtmAA; [User entered 6.71%]
CV-2553	5/20/2026 1:24:17 PM	28.52	1343	34.4341850	-118.6489165	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-2553	5/4/2026 9:36:18 AM	28.56	1340	34.4341713	-118.6489133	Valve Adjustment:Decreased Flow/Vacuum
CV-2554	5/28/2026 1:40:06 PM	28.54	1370	34.4344472	-118.6482645	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2554	5/20/2026 2:11:24 PM	28.53	1372	34.4344643	-118.6482583	Valve Adjustment:No Flow Measurement,High Temp
CV-2554	5/14/2026 11:13:27 AM	28.62	1362	34.4344647	-118.6482595	Valve Adjustment:No Flow Measurement,High Temp
CV-2554	5/14/2026 11:12:34 AM	28.65	1362	34.4344691	-118.6482616	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2554	5/14/2026 11:10:00 AM					AtmAA
CV-2554	5/4/2026 1:13:35 PM	28.54	1358	34.4344623	-118.6482596	Valve Adjustment:High Temp
CV-2554	5/4/2026 1:12:59 PM	28.53	1358	34.4344687	-118.6482578	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-2554	5/4/2026 1:10:00 PM					AtmAA
CV-2554	5/4/2026 1:10:00 PM					AtmAA; [User entered 7.08%]
CV-2555	5/22/2026 11:41:33 AM	28.47	1352	34.4348518	-118.6476733	NSPS/EG CAI,High O2
CV-2555	5/22/2026 11:39:04 AM	28.47	1388	34.4348375	-118.6476383	NSPS/EG CAI,High O2
CV-2555	5/8/2026 1:12:17 PM	28.52	1351	34.4348410	-118.6477207	Valve Adjustment:High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
CV-2556	5/27/2026 2:02:24 PM	28.41	1368	34.4351675	-118.6472263	Valve Adjustment:No Flow Measurement,High Temp
CV-2556	5/19/2026 1:45:00 PM					AtmAA
CV-2556	5/19/2026 1:38:41 PM	28.6	1386	34.4351709	-118.6472403	Valve Adjustment:No Flow Measurement,High Temp
CV-2556	5/11/2026 10:20:58 AM	28.55	1383	34.4351541	-118.6472084	Valve Adjustment:No Flow Measurement,High Temp
CV-2556	5/4/2026 9:15:00 AM					AtmAA
CV-2556	5/4/2026 9:15:00 AM					AtmAA; [User entered 11.08%]
CV-2556	5/4/2026 9:13:52 AM	28.54	1375	34.4351796	-118.6472120	Valve Adjustment:High Temp
CV-2557	5/20/2026 1:47:47 PM	28.41	1380	34.4354737	-118.6464625	Valve Adjustment:Surging Liquid in Header
CV-2557	5/8/2026 8:36:19 AM	28.57	1319	34.4354630	-118.6466022	No Flow Measurement,Reduced System Vacuum
CV-2558	5/27/2026 2:34:42 PM	28.37	1390	34.4353057	-118.6463321	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2558	5/27/2026 2:33:21 PM	28.38	1390	34.4353058	-118.6463320	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Well (Watered In)
CV-2558	5/19/2026 1:15:50 PM	28.58	1393	34.4353069	-118.6463261	Valve Comment:ACTIVE PLR;Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Well (Watered In)
CV-2558	5/19/2026 1:15:00 PM					AtmAA
CV-2558	5/14/2026 10:19:35 AM	28.58	1396	34.4353019	-118.6463204	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In)

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-2558	5/14/2026 10:18:44 AM	28.58	1395	34.4352979	-118.6463215	Valve Comment:Active plr;Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In)
CV-2558	5/14/2026 10:15:00 AM					AtmAA
CV-2558	5/4/2026 8:47:30 AM	28.49	1388	34.4353080	-118.6463220	Valve Comment:Active PLR;Valve Adjustment:Audible Flow,High Temp,Positive Static Press.
CV-2558	5/4/2026 8:45:31 AM	28.49	1388	34.4353098	-118.6463183	Valve Comment:Active plr;Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.
CV-2558	5/4/2026 8:45:00 AM					AtmAA
CV-2559	5/8/2026 8:53:26 AM	28.57	1391	34.4357650	-118.6454850	NSPS/EG CAC,No Flow Measurement,Reduced System Vacuum
CV-2559	5/8/2026 8:49:36 AM	28.57	1388	34.4357823	-118.6454995	Positive Static Press.,Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,NSPS/EG CAI
CV-2560	5/22/2026 10:39:45 AM	28.37	1405	34.4359152	-118.6466632	Valve Adjustment:Decreased Flow/Vacuum
CV-2560	5/12/2026 1:09:28 PM	28.63	1390	34.4359102	-118.6466652	Valve Adjustment:Decreased Flow/Vacuum
CV-2561	5/11/2026 2:38:47 PM	28.47	1381	34.4360695	-118.6467007	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-2562	5/11/2026 2:10:20 PM	28.49	1414	34.4360810	-118.6459618	
CV-2563	5/28/2026 11:37:21 AM	28.59	1299	34.4372952	-118.6457702	Valve Adjustment:NSPS/EG CAC
CV-2563	5/28/2026 11:36:57 AM	28.59	1292	34.4373098	-118.6457650	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
CV-2563	5/15/2026 11:37:25 AM	28.58	1224	34.4373225	-118.6458008	
CV-2563	5/15/2026 11:35:25 AM	28.58	1280	34.4373478	-118.6457748	Reduced System Vacuum,Opened Valve 1/2 to 1 Turn,Positive Static Press.,NSPS/EG CAI,NSPS/EG CAC
CV-2564	5/21/2026 9:30:21 AM	28.48	1361	34.4331228	-118.6487310	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-2564	5/21/2026 9:29:15 AM	28.48	1365	34.4331245	-118.6487238	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
CV-2564	5/1/2026 11:06:39 AM	28.55	1356	34.4331307	-118.6487373	Valve Adjustment:Audible Flow,Barely Open
CV-2565	5/20/2026 9:51:50 AM	28.52	1339	34.4319638	-118.6490453	
CV-2565	5/4/2026 9:20:17 AM	28.52				
CV-2566	5/20/2026 9:46:01 AM	28.51	1358	34.4317583	-118.6487145	
CV-2566	5/4/2026 9:24:42 AM	28.52	1371	34.4317735	-118.6487802	
CV-2567	5/20/2026 12:20:18 PM	28.47	1306	34.4318887	-118.6480480	
CV-2567	5/4/2026 9:43:22 AM	28.51	1339	34.4319670	-118.6480845	
CV-2568	5/20/2026 11:39:12 AM	28.48	1339	34.4322255	-118.6478610	
CV-2568	5/4/2026 11:23:44 AM	28.51	1325	34.4321435	-118.6477993	
CV-2569	5/20/2026 11:29:23 AM	28.48	1398	34.4322323	-118.6472882	
CV-2569	5/4/2026 11:29:19 AM	28.51	1365	34.4322860	-118.6473918	
CV-2570	5/20/2026 11:15:26 AM	28.5	1440	34.4325052	-118.6471118	
CV-2570	5/4/2026 11:34:49 AM	28.51	1329	34.4324603	-118.6470415	
CV-2571	5/7/2026 1:00:36 PM	28.75	1125	34.4299732	-118.6457783	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-2572	5/7/2026 1:32:16 PM	28.73	1211	34.4298968	-118.6470793	
CV-48R	5/28/2026 11:41:20 AM	28.59	1304	34.4373368	-118.6458555	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Well (Watered In)
CV-48R	5/28/2026 11:40:34 AM	28.59	1287	34.4373452	-118.6458597	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Well (Watered In)
CV-48R	5/15/2026 11:44:42 AM	28.58	1312	34.4373598	-118.6459028	
CV-48R	5/6/2026 10:23:03 AM	28.7	1310	34.4373213	-118.6458787	Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum
CV-52D	5/1/2026 1:17:29 PM	28.66	1318	34.4359397	-118.6424802	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In)
CV-55R	5/27/2026 3:07:28 PM	28.47	1316	34.4343666	-118.6427811	Valve Comment:Lorentz disconnected due to liner expansion;Valve Adjustment:High Temp
CV-55R	5/21/2026 9:11:16 AM	28.58	1324	34.4343888	-118.6427691	Valve Adjustment:NSPS/EG CAC
CV-55R	5/21/2026 9:10:09 AM	28.55	1306	34.4343699	-118.6427853	Valve Adjustment:NSPS/EG CAI,Increased Flow/Vacuum
CV-55R	5/11/2026 11:02:29 AM	28.61	1314	34.4343506	-118.6427855	Valve Adjustment:High Temp
CV-55R	5/4/2026 8:05:00 AM					AtmAA
CV-55R	5/4/2026 8:05:00 AM					AtmAA; [User entered 14.055%]
CV-55R	5/4/2026 8:04:21 AM	28.61	1319	34.4343259	-118.6428242	Valve Adjustment:High Temp
CV-56D	5/7/2026 11:25:28 AM	28.67	1286	34.4337902	-118.6431927	Reduced System Vacuum,NSPS/EG CAI,High O2
CV-56D	5/7/2026 11:22:51 AM	28.67	1270	34.4338063	-118.6432998	NSPS/EG CAI,High O2,Reduced System Vacuum
CV-56S	5/7/2026 11:32:33 AM	28.67	1299	34.4337373	-118.6431910	Reduced System Vacuum,NSPS/EG CAI,High O2
CV-56S	5/7/2026 11:29:21 AM	28.67	1329	34.4339453	-118.6432662	Reduced System Vacuum,NSPS/EG CAI,High O2
CV-57R	5/1/2026 2:21:40 PM	28.52	1350	34.4343442	-118.6435822	Valve Adjustment:Increased Flow/Vacuum;Well Condition:Fair
CV-79R	5/1/2026 2:41:23 PM	28.54	1329	34.4332500	-118.6448550	Valve Adjustment:Audible Flow;Well Condition:Fair
CV-94	5/11/2026 3:29:38 PM	28.52	1342	34.4349648	-118.6436033	
CV-94	5/11/2026 3:28:29 PM	28.52	1332	34.4349903	-118.6436197	NSPS/EG CAI,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
CV-95	5/1/2026 2:19:24 PM	28.52	1358	34.4343250	-118.6436185	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-95	5/1/2026 2:18:38 PM	28.52	1353	34.4343223	-118.6436080	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open;Well Condition:Fair
CV-99	5/26/2026 1:51:48 PM	28.43	1318	34.4370692	-118.6463438	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-99	5/4/2026 7:45:00 AM					Air Tech Lab; [User entered 0.26%]
D-02	5/28/2026 3:29:22 PM	28.68	1190	34.4311713	-118.6443112	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
D-03	5/28/2026 3:32:52 PM	28.67	1189	34.4311658	-118.6443082	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
D-04	5/28/2026 3:41:09 PM	28.68	1180	34.4311697	-118.6443112	Valve Adjustment:Valve 100% Open,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
D-09	5/7/2026 1:18:48 PM	28.73	1168	34.4301310	-118.6463358	Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
D-10	5/7/2026 1:08:35 PM	28.72	1109	34.4303733	-118.6456953	
FP-001	5/8/2026 9:19:36 AM	28.62	1345	34.4366018	-118.6458813	Reduced System Vacuum,Audible Flow
FP-002	5/8/2026 9:28:39 AM	28.61	1385	34.4366048	-118.6462237	Reduced System Vacuum
FP-003	5/8/2026 9:39:47 AM	28.61	1381	34.4366380	-118.6466182	NSPS/EG CAI,High O2,Reduced System Vacuum
FP-003	5/8/2026 9:36:36 AM	28.61	1355	34.4366733	-118.6464832	NSPS/EG CAI,High O2,Reduced System Vacuum
FP-005	5/15/2026 2:55:43 PM	28.49	1385	34.4365253	-118.6472332	
FP-006	5/15/2026 2:51:55 PM	28.5	1365	34.4364152	-118.6476607	
FP-008	5/15/2026 3:10:45 PM	28.48	1391	34.4362947	-118.6481520	
FP-008	5/6/2026 9:22:39 AM	28.63	1366	34.4363213	-118.6481603	Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum;Well Comment:Possibly watered in no system pressure
FP-009	5/13/2026 10:12:04 AM	28.67	1370	34.4366912	-118.6489365	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
FP-010	5/13/2026 10:03:04 AM	28.66	1359	34.4365998	-118.6492362	Valve Adjustment:Decreased Flow/Vacuum
FP-011	5/13/2026 10:00:11 AM	28.67	1354	34.4365362	-118.6495148	
FP-012	5/19/2026 8:39:03 AM	28.58	1394	34.4366645	-118.6499508	
FP-012	5/1/2026 11:49:02 AM	28.49	1420	34.4366962	-118.6499643	
FP-013	5/19/2026 9:34:22 AM	28.59	1375	34.4365733	-118.6502487	Valve Adjustment:Increased Flow/Vacuum
FP-013	5/13/2026 9:55:27 AM	28.67	1370	34.4365755	-118.6502437	Valve Adjustment:Barely Open
FP-014	5/13/2026 2:03:06 PM	28.63	1359	34.4364897	-118.6482270	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
FP-015	5/15/2026 2:35:16 PM	28.53	1368	34.4364350	-118.6478748	
FP-015	5/14/2026 2:08:49 PM	28.61	1345	34.4364805	-118.6479392	Valve Adjustment:Decreased Flow/Vacuum,Valve 100% Closed
FP-015	5/13/2026 2:12:26 PM	28.63	1349	34.4364387	-118.6479168	Valve Adjustment:High Temp
FP-016	5/15/2026 2:43:10 PM	28.5	1335	34.4365703	-118.6476573	
FP-016	5/13/2026 2:15:57 PM	28.64	1360	34.4364905	-118.6477060	Valve Adjustment:Barely Open
FP-017	5/8/2026 12:57:34 PM	28.57	1336	34.4344060	-118.6486553	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
FP-018	5/8/2026 12:40:54 PM	28.57	1355	34.4344607	-118.6490808	
FP-019	5/12/2026 1:48:27 PM	28.58	1324	34.4346590	-118.6491418	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
FP-020	5/12/2026 1:57:00 PM	28.6	1328	34.4349558	-118.6492892	Valve Adjustment:Barely Open
FP-021	5/13/2026 10:41:14 AM	28.7	1341	34.4352002	-118.6491838	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
FP-021	5/12/2026 1:59:43 PM	28.57	1331	34.4351600	-118.6495498	Valve Adjustment:Decreased Flow/Vacuum
FP-022	5/13/2026 10:32:37 AM	28.7	1358	34.4352390	-118.6491458	Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum
FP-023	5/13/2026 1:46:18 PM	28.64	1345	34.4355123	-118.6494168	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
FP-024	5/20/2026 2:16:33 PM	28.45	1362	34.4354970	-118.6477955	Valve Adjustment:Barely Open
FP-025	5/20/2026 2:19:20 PM	28.45	1361	34.4353510	-118.6477598	Valve Adjustment:Decreased Flow/Vacuum
FP-026	5/29/2026 4:20:14 PM	28.63	1352	34.4350803	-118.6481360	
FP-027	5/29/2026 4:24:24 PM	28.63	1359	34.4348312	-118.6482373	
FP-028	5/28/2026 11:39:27 AM	28.5	1371	34.4346913	-118.6483355	
FP-029	5/28/2026 11:31:57 AM	28.51	1296	34.4343368	-118.6488995	
FP-030	5/12/2026 1:41:15 PM	28.59	1307	34.4345017	-118.6496773	Valve Adjustment:Barely Open
FP-031	5/29/2026 9:22:16 AM	28.66	1347	34.4348340	-118.6497520	
FP-031	5/12/2026 1:37:06 PM	28.59	1320	34.4348330	-118.6497772	Valve Adjustment:Decreased Flow/Vacuum
FP-032	5/12/2026 1:28:30 PM	28.58	1334	34.4351075	-118.6498378	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum
FP-033	5/12/2026 1:23:05 PM	28.58	1346	34.4353872	-118.6499523	Valve Adjustment:Decreased Flow/Vacuum
FP-034	5/12/2026 1:19:44 PM	28.55	1357	34.4356307	-118.6500237	Valve Adjustment:Barely Open
FP-035	5/12/2026 1:16:01 PM	28.56	1362	34.4358548	-118.6501185	Valve Adjustment:Decreased Flow/Vacuum
FP-036	5/1/2026 11:36:11 AM	28.52	1401	34.4361558	-118.6502323	Valve Adjustment:Barely Open
FP-037	5/19/2026 10:33:25 AM	28.61	1366	34.4362913	-118.6502602	
FP-037	5/1/2026 11:38:38 AM	28.49	1388	34.4362773	-118.6503153	Valve Adjustment:Barely Open
FP-038	5/14/2026 2:24:47 PM	28.55	1348	34.4342242	-118.6499053	
FP-039	5/14/2026 2:15:09 PM	28.57	1306	34.4341813	-118.6498180	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
FP-040	5/29/2026 2:30:36 PM	28.58	1325	34.4353275	-118.6510755	
FP-041	5/13/2026 1:16:55 PM	28.66	1237	34.4339895	-118.6506525	
FP-042	5/20/2026 10:11:54 AM	28.63	1251	34.4332757	-118.6512885	
FP-043	5/13/2026 1:22:06 PM	28.66	1211	34.4342865	-118.6506492	
FP-044	5/13/2026 1:25:38 PM	28.66	1224	34.4346217	-118.6507967	
FP-045	5/11/2026 1:04:40 PM	28.63	1322	34.4334380	-118.6496432	
FP-046	5/15/2026 3:02:41 PM	28.49	1329	34.4365908	-118.6471652	
FP-047	5/29/2026 11:36:35 AM	28.62	1312	34.4366965	-118.6469575	
FP-050	5/6/2026 2:53:31 PM	28.57	1364	34.4348978	-118.6472845	Valve Adjustment:Decreased Flow/Vacuum
FP-051	5/6/2026 2:48:25 PM	28.56	1380	34.4347007	-118.6470228	Valve Adjustment:Decreased Flow/Vacuum
FP-052	5/22/2026 2:09:54 PM	28.37	1335	34.4343828	-118.6481260	
FP-052	5/4/2026 2:20:50 PM	28.52	1366	34.4342270	-118.6481385	
FP-053	5/21/2026 2:19:03 PM	28.41	1382	34.4340420	-118.6477340	Valve Adjustment:Increased Flow/Vacuum,Valve 100% Open
FP-053	5/4/2026 2:08:41 PM	28.5	1380	34.4340587	-118.6477530	Valve Adjustment:Barely Open
FP-054	5/1/2026 11:30:37 AM	28.45	1394	34.4349998	-118.6457865	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
FP-055	5/20/2026 2:00:54 PM	28.48	1364	34.4336087	-118.6481788	Valve Adjustment:Increased Flow/Vacuum
FP-055	5/4/2026 10:03:30 AM	28.53	1350	34.4336195	-118.6481682	
FP-056	5/4/2026 9:15:22 AM	28.52	1356	34.4334657	-118.6486362	
FP-057	5/4/2026 9:17:47 AM	28.52	1353	34.4333977	-118.6485917	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:no system port
FP-057	5/1/2026 11:34:44 AM	28.45	1358	34.4347868	-118.6454630	
FP-058	5/29/2026 3:51:49 PM	28.51	1427	34.4350023	-118.6458712	
FP-059	5/1/2026 2:35:49 PM	28.41	1322	34.4345693	-118.6459352	
FP-060	5/1/2026 2:53:38 PM	28.4	1371	34.4349418	-118.6461343	
FP-061	5/15/2026 2:38:19 PM	28.5	1375	34.4364535	-118.6480250	
FP-061	5/14/2026 2:22:44 PM	28.61	1347	34.4364610	-118.6479475	Valve Adjustment:Orifice Plate Changed (See OP Log)
FP-061	5/14/2026 2:19:38 PM	28.61	1343	34.4364735	-118.6479645	Valve Adjustment:Decreased Flow/Vacuum
H-01 (EXP-01)	5/26/2026 8:45:19 AM	28.63	1238	34.4376920	-118.6441722	Valve Adjustment:Audible Flow,Barely Open
H-01 (EXP-01)	5/12/2026 1:49:58 PM	28.72	1218	34.4376842	-118.6441523	
H-02 (EXP-02)	5/26/2026 8:27:48 AM	28.62	1250	34.4377123	-118.6445873	Valve Adjustment:Barely Open,Surging Liquid in Well (Watered In)
H-02 (EXP-02)	5/12/2026 1:55:38 PM	28.72	1226	34.4376910	-118.6445842	
H-03 (EXP-03)	5/26/2026 8:31:53 AM	28.59	1250	34.4377153	-118.6446182	Valve Adjustment:Audible Flow
H-03 (EXP-03)	5/12/2026 2:02:02 PM	28.73	1231	34.4377085	-118.6446410	
H-04 (EXP-04)	5/26/2026 8:34:46 AM	28.61	1250	34.4377263	-118.6446790	Valve Adjustment:Barely Open
H-04 (EXP-04)	5/14/2026 10:16:02 AM	28.8	1272	34.4376853	-118.6447197	Valve Adjustment:NSPS/EG CAI,High Temp
H-04 (EXP-04)	5/14/2026 10:14:56 AM	28.82	1273	34.4376952	-118.6446813	Valve Adjustment:NSPS/EG CAC,High Temp
H-04 (EXP-04)	5/14/2026 10:13:50 AM	28.82	1242	34.4377102	-118.6447060	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum
H-08 (EXP-08)	5/26/2026 8:55:13 AM	28.59	1294	34.4378447	-118.6465338	Valve Adjustment:Audible Flow
H-08 (EXP-08)	5/11/2026 9:46:50 AM	28.64	1271	34.4378388	-118.6465160	
H-10 (EXP-10)	5/26/2026 9:06:45 AM	28.56	1307	34.4374403	-118.6470750	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
H-10 (EXP-10)	5/11/2026 9:40:46 AM	28.64	1297	34.4374428	-118.6470835	Valve Adjustment:Barely Open
H-10 (EXP-10)	5/11/2026 9:40:06 AM	28.64	1291	34.4374607	-118.6470725	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum
H-101W	5/13/2026 8:32:50 AM	28.82	1199	34.4310828	-118.6505710	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In);Well Repairs:Valve
H-101W	5/13/2026 8:24:13 AM	28.82	1204	34.4310752	-118.6505745	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
H-102A	5/13/2026 8:17:41 AM	28.81	1210	34.4310967	-118.6505652	Valve Adjustment:Increased Flow/Vacuum;Well Repairs:Sample Port
H-1401W	5/13/2026 8:48:53 AM	28.82	1200	34.4310877	-118.6505600	Valve Adjustment:Increased Flow/Vacuum,Surging Liquid in Header
H-1404C	5/20/2026 11:55:54 AM	28.48	1394	34.4323593	-118.6482932	
H-1404C	5/4/2026 11:20:18 AM	28.51	1407	34.4324288	-118.6483063	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
H-1405C	5/20/2026 8:39:42 AM	28.58	1312	34.4325898	-118.6497317	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header
H-1405C	5/1/2026 10:13:01 AM	28.6	1301	34.4325790	-118.6497293	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum,Surging Liquid in Header
H-1406W	5/20/2026 9:30:46 AM	28.63	1256	34.4321807	-118.6507710	Valve Adjustment:Decreased Flow/Vacuum
H-1406W	5/1/2026 10:30:28 AM	28.65	1255	34.4321702	-118.6507820	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:Valve damaged
H-1408CR	5/6/2026 2:48:15 PM	28.62	1260	34.4314735	-118.6473962	
H-1408CR	5/6/2026 2:46:51 PM	28.62	1263	34.4314803	-118.6473372	NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-1408E	5/20/2026 2:13:20 PM	28.49	1396	34.4333353	-118.6471580	Valve Adjustment:Surging Liquid in Header
H-1408E	5/4/2026 2:44:00 PM	28.45	1417	34.4334305	-118.6473195	
H-1408E	5/4/2026 2:42:19 PM	28.45	1407	34.4334643	-118.6471968	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.
H-1408W	5/7/2026 10:26:18 AM	28.64	1257	34.4311628	-118.6500330	Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-1409N	5/20/2026 2:26:47 PM	28.41	1434	34.4327785	-118.6468967	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-1409N	5/4/2026 2:02:48 PM	28.48	1434	34.4328577	-118.6469445	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-1410S	5/6/2026 12:22:14 PM	28.71	1158	34.4310043	-118.6467432	
H-1563N	5/22/2026 2:12:17 PM	28.44	1318	34.4338717	-118.6498188	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1563N	5/11/2026 12:47:48 PM	28.63	1320	34.4338583	-118.6498358	Valve Adjustment:Reduce Sys. Vac. - Flare Down
H-1563S	5/20/2026 8:43:45 AM	28.58	1309	34.4323993	-118.6496597	
H-1563S	5/1/2026 10:06:27 AM	28.59	1317	34.4323920	-118.6496645	Valve Adjustment:Barely Open
H-1565E	5/21/2026 10:26:51 AM	28.41	1403	34.4335533	-118.6472303	Valve Adjustment:Barely Open,Surging Liquid in Header
H-1565E	5/6/2026 10:50:58 AM	28.6	1387	34.4335490	-118.6471893	Valve Adjustment:Barely Open,Surging Liquid in Header
H-1568N	5/21/2026 10:57:34 AM	28.44	1387	34.4339032	-118.6470792	Valve Adjustment:Barely Open
H-1568N	5/20/2026 2:05:18 PM	28.49	1388	34.4333292	-118.6471738	
H-1568N	5/4/2026 2:46:50 PM	28.42	1381	34.4333778	-118.6471675	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-1571S	5/4/2026 11:05:46 AM	28.63	1273	34.4321600	-118.6452273	Valve Adjustment:Decreased Flow/Vacuum
H-1572N	5/1/2026 2:47:42 PM	28.48	1358	34.4336958	-118.6447368	Valve Adjustment:Increased Flow/Vacuum
H-1572S	5/4/2026 10:51:40 AM	28.67	1263	34.4321853	-118.6447270	Valve Adjustment:Decreased Flow/Vacuum
H-1574N	5/20/2026 10:38:18 AM	28.67	1224	34.4325223	-118.6517647	Valve Adjustment:Barely Open
H-1574N	5/13/2026 9:52:29 AM	28.65	1369	34.4365228	-118.6501082	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
H-1574N	5/12/2026 8:59:40 AM	28.68	1270	34.4324318	-118.6518578	
H-1753N	5/26/2026 9:00:32 AM	28.45	1347	34.4347247	-118.6493153	Valve Adjustment:Barely Open
H-1753N	5/12/2026 1:45:21 PM	28.58	1327	34.4347443	-118.6493200	Valve Adjustment:Barely Open
H-1753S	5/22/2026 2:02:07 PM	28.41	1343	34.4339337	-118.6495725	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1753S	5/11/2026 12:40:59 PM	28.61	1325	34.4339465	-118.6495767	Valve Adjustment:Reduce Sys. Vac. - Flare Down
H-1756S	5/19/2026 1:28:24 PM	28.65	1289	34.4325650	-118.6502857	Valve Adjustment:NSPS/EG CAI,Barely Open
H-1756S	5/19/2026 1:25:39 PM	28.66	1295	34.4325747	-118.6502920	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum
H-1756S	5/13/2026 12:47:50 PM	28.67	1247	34.4325943	-118.6502308	
H-1757S	5/20/2026 8:35:55 AM	28.59	1313	34.4327182	-118.6497730	
H-1757S	5/1/2026 10:14:46 AM	28.61	1308	34.4327065	-118.6497760	Valve Adjustment:Audible Flow;Well Condition:Fair
H-1760S	5/21/2026 10:10:39 AM	28.44	1388	34.4327248	-118.6479115	Valve Adjustment:Barely Open
H-1760S	5/11/2026 1:37:59 PM	28.57	1387	34.4327687	-118.6479202	Valve Adjustment:Reduce Sys. Vac. - Flare Down
H-1762N	5/20/2026 1:57:03 PM	28.49	1387	34.4334418	-118.6468622	
H-1762N	5/20/2026 1:55:17 PM	28.47	1390	34.4334503	-118.6468817	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Increased Flow/Vacuum
H-1762N	5/4/2026 2:38:51 PM	28.45	1421	34.4335587	-118.6469227	
H-1763N	5/6/2026 10:36:14 AM	28.56	1375	34.4335967	-118.6461747	
H-1763N	5/6/2026 10:34:51 AM	28.56	1339	34.4336130	-118.6461267	NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-1763S	5/4/2026 11:26:50 AM	28.61	1319	34.4323963	-118.6460432	Valve Adjustment:Decreased Flow/Vacuum
H-1764N	5/28/2026 12:39:39 PM	28.52	1367	34.4331603	-118.6456347	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum
H-1764N	5/5/2026 1:16:30 PM	28.52	1369	34.4331572	-118.6456352	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum
H-1764N	5/4/2026 11:45:03 AM	28.55	1357	34.4331618	-118.6456243	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
H-1764S	5/4/2026 11:08:05 AM	28.63	1295	34.4321740	-118.6454062	
H-1767N	5/11/2026 9:51:22 AM	28.62	1224	34.4326290	-118.6435573	
H-1769N	5/19/2026 8:53:05 AM	28.59	1365	34.4370255	-118.6494768	Valve Adjustment:Audible Flow,Barely Open
H-1769N	5/1/2026 2:30:15 PM	28.46	1358	34.4370625	-118.6495027	
H-1770N	5/19/2026 9:18:49 AM	28.59	1368	34.4368203	-118.6500283	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
H-1770N	5/4/2026 8:50:00 AM					Air Tech Lab; [User entered 1.2%]
H-1770N	5/1/2026 2:42:44 PM	28.45	1342	34.4368195	-118.6500292	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1770S	5/19/2026 12:50:46 PM	28.63	1315	34.4331262	-118.6501585	Valve Adjustment:Barely Open
H-1770S	5/1/2026 10:34:30 AM	28.6	1320	34.4331097	-118.6501593	Valve Adjustment:Decreased Flow/Vacuum

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
H-1771A	5/11/2026 2:21:58 PM	28.5	1381	34.4363332	-118.6463698	
H-1771B	5/13/2026 11:22:20 AM	28.67	1392	34.4355247	-118.6466602	Valve Adjustment:NSPS/EG CAI,High Temp
H-1771B	5/13/2026 11:19:01 AM	30	1397	34.4355318	-118.6466588	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
H-1771B	5/11/2026 1:05:25 PM	28.52	1379	34.4355532	-118.6466608	Valve Adjustment:Positive Static Press.,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1771B	5/11/2026 1:04:43 PM	28.52	1380	34.4355432	-118.6466587	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1774N	5/19/2026 9:58:15 AM	28.62	1352	34.4367243	-118.6508037	Valve Adjustment:Barely Open
H-1774N	5/12/2026 10:34:14 AM	28.59	1355	34.4366473	-118.6509118	
H-1801S	5/11/2026 11:15:54 AM	28.66	1299	34.4338058	-118.6441812	No Adjustment Made
H-1802S	5/1/2026 2:44:17 PM	28.51	1350	34.4335672	-118.6447667	Valve Adjustment:Increased Flow/Vacuum
H-1803N	5/26/2026 9:42:57 AM	28.47	1373	34.4370350	-118.6485700	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In)
H-1803N	5/18/2026 10:00:00 AM					AtmAA
H-1803N	5/18/2026 9:58:45 AM	28.52	1354	34.4370325	-118.6485770	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In)
H-1803N	5/12/2026 9:08:34 AM	28.55	1345	34.4370158	-118.6486076	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
H-1803N	5/12/2026 9:05:00 AM					AtmAA
H-1803N	5/5/2026 9:07:24 AM	28.51	1349	34.4370299	-118.6486000	Valve Comment:ACTIVE PLR;Valve Adjustment:No Flow Measurement,High Temp
H-1803N	5/5/2026 9:00:00 AM					AtmAA
H-1803N	5/5/2026 9:00:00 AM					AtmAA; [User entered 17.07%]
H-1804B	5/1/2026 10:39:08 AM	28.46	1391	34.4342722	-118.6456027	
H-1804N	5/8/2026 9:11:50 AM	28.61	1348	34.4363567	-118.6457242	Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-1804S	5/4/2026 11:47:34 AM	28.56	1365	34.4330883	-118.6456972	Valve Adjustment:Increased Flow/Vacuum,Surging Liquid in Header
H-1805A	5/1/2026 11:19:57 AM	28.46	1368	34.4351310	-118.6450843	
H-1805B	5/4/2026 11:52:01 AM	28.53	1379	34.4337287	-118.6451562	
H-1805S	5/4/2026 11:39:55 AM	28.59	1326	34.4329170	-118.6451598	Valve Adjustment:Audible Flow
H-1806A	5/1/2026 11:08:54 AM	28.46	1385	34.4353900	-118.6442890	
H-1806B	5/1/2026 2:52:26 PM	28.48	1365	34.4339000	-118.6444555	
H-1806N	5/11/2026 11:37:48 AM	28.52	1398	34.4364753	-118.6449213	
H-1806S	5/4/2026 10:39:51 AM	28.64	1285	34.4328797	-118.6444580	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
H-1807A	5/4/2026 1:18:09 PM	28.58	1344	34.4353387	-118.6436233	Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Surging Liquid in Header
H-1807N	5/29/2026 10:10:34 AM	28.63	1325	34.4364860	-118.6435677	No Adjustment Made

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
H-1807S	5/7/2026 11:08:13 AM	28.67	1266	34.4337920	-118.6433665	Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-1952S	5/21/2026 2:14:50 PM	28.41	1387	34.4338018	-118.6476160	Valve Adjustment:NSPS/EG CAC,Barely Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
H-1952S	5/21/2026 2:13:14 PM	28.41	1386	34.4338123	-118.6476157	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
H-1952S	5/4/2026 2:04:02 PM	28.49	1364	34.4338018	-118.6476148	Valve Adjustment:Increased Flow/Vacuum
H-1955C	5/1/2026 11:26:41 AM	28.44	1388	34.4350727	-118.6454042	
H-1955N	5/8/2026 9:07:44 AM	28.62	1339	34.4364617	-118.6455018	Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-1956B	5/1/2026 10:44:44 AM	28.46	1391	34.4342613	-118.6447408	
H-1956N	5/11/2026 11:40:47 AM	28.53	1329	34.4365163	-118.6449683	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-1956S	5/1/2026 2:39:31 PM	28.54	1338	34.4332363	-118.6448778	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
H-1957B	5/6/2026 2:10:22 PM	28.61	1381	34.4345577	-118.6440863	
H-1957B	5/1/2026 2:13:12 PM	28.48	1374	34.4345740	-118.6440963	
H-1957N	5/11/2026 11:33:03 AM	28.54	1342	34.4364202	-118.6443038	
H-1957S	5/11/2026 11:18:08 AM	28.61	1339	34.4338067	-118.6441572	
H-1958C	5/4/2026 1:20:33 PM	28.59	1333	34.4353942	-118.6434847	Valve Adjustment:Audible Flow
H-1958N	5/28/2026 1:56:37 PM	28.52	1354	34.4364505	-118.6435238	Valve Adjustment:Barely Open
H-1958S	5/7/2026 11:03:31 AM	28.67	1299	34.4339642	-118.6433052	Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-1962N	5/19/2026 9:28:05 AM	28.59	1369	34.4366552	-118.6501363	Valve Adjustment:Decreased Flow/Vacuum
H-1962N	5/19/2026 9:26:00 AM	28.6	1364	34.4366772	-118.6501218	Valve Adjustment:Decreased Flow/Vacuum
H-1962N	5/1/2026 2:46:00 PM	28.45	1347	34.4366583	-118.6501298	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1963N	5/19/2026 8:46:36 AM	28.59	1378	34.4369248	-118.6495362	Valve Adjustment:NSPS/EG CAI,High Temp
H-1963N	5/19/2026 8:44:46 AM	28.59	1379	34.4369250	-118.6495370	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
H-1963N	5/1/2026 12:06:22 PM	28.49	1383	34.4369102	-118.6495877	Valve Adjustment:NSPS/EG CAC,High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1963N	5/1/2026 12:04:32 PM	28.51	1362	34.4368882	-118.6495335	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1966N	5/19/2026 10:06:37 AM	28.62	1344	34.4365543	-118.6507988	
H-1966N	5/12/2026 10:42:28 AM	28.59	1339	34.4365167	-118.6507485	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-1967E	5/7/2026 1:04:55 PM	28.72	1152	34.4302350	-118.6459632	Reduced System Vacuum
H-1967W	5/7/2026 9:49:11 AM	28.71	1257	34.4298232	-118.6507763	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
H-1967W	5/7/2026 9:47:56 AM	28.71	1201	34.4298152	-118.6507190	Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-2050E	5/14/2026 9:38:59 AM	28.8	1119	34.4291773	-118.6475780	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-2050W	5/5/2026 3:39:36 PM	28.63	1188	34.4291558	-118.6491385	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-2051W	5/7/2026 9:44:33 AM	28.61	1204	34.4299358	-118.6507733	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-2053E	5/7/2026 1:13:15 PM	28.73	1115	34.4302400	-118.6459330	Reduced System Vacuum
H-2053W	5/13/2026 8:39:25 AM	28.81	1205	34.4310888	-118.6505722	Valve Adjustment:Increased Flow/Vacuum
H-2055E	5/22/2026 10:10:19 AM	28.55	1276	34.4318162	-118.6465767	
H-2055E	5/6/2026 3:07:33 PM	28.63	1322	34.4319158	-118.6466957	
H-2056B	5/8/2026 3:07:26 PM	28.68	1119	34.4297018	-118.6474618	
H-2056W	5/7/2026 9:41:29 AM	28.66	1201	34.4299912	-118.6505983	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-2057E	5/7/2026 1:10:46 PM	28.72	1125	34.4302735	-118.6459342	Reduced System Vacuum
H-2057W	5/28/2026 8:44:04 AM	28.7	1195	34.4306532	-118.6506315	Valve Comment:RES SEM;Valve Adjustment:Increased Flow/Vacuum
H-2057W	5/13/2026 8:09:16 AM	28.82	1194	34.4306418	-118.6506340	Valve Adjustment:Barely Open;Well Repairs:Sample Port
H-2057W	5/13/2026 8:05:12 AM	28.82	1193	34.4306693	-118.6506338	Valve Adjustment:NSPS/EG CAI,Decreased Flow/Vacuum;Well Repairs:Sample Port
H-2058E	5/7/2026 1:22:33 PM	28.72	1096	34.4300088	-118.6465828	Reduced System Vacuum
H-2058W	5/7/2026 9:34:28 AM	28.77	1211	34.4299087	-118.6508643	
H-2058W	5/7/2026 9:33:03 AM	28.77	1181	34.4299318	-118.6509787	NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-2059E	5/6/2026 12:36:07 PM	28.75	1142	34.4306302	-118.6462412	
H-2059W	5/7/2026 10:12:44 AM	28.67	1184	34.4311415	-118.6502280	
H-2161E	5/6/2026 12:32:34 PM	28.73	1181	34.4308358	-118.6463493	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-2161W	5/7/2026 10:08:23 AM	28.67	1283	34.4309113	-118.6502148	
H-2163C	5/22/2026 10:05:49 AM	28.44	1296	34.4310082	-118.6486600	
H-2163C	5/4/2026 10:05:22 AM	28.54	1293	34.4311252	-118.6486480	
H-2163W	5/7/2026 10:22:23 AM	28.66	1240	34.4311995	-118.6498642	Reduced System Vacuum
H-2164E	5/22/2026 10:41:07 AM	28.55	1280	34.4318698	-118.6460668	No Adjustment Made
H-2164E	5/6/2026 3:22:38 PM	28.62	1276	34.4319407	-118.6460057	
H-2164E	5/6/2026 3:21:24 PM	28.62	1296	34.4319637	-118.6460188	NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-2165E	5/4/2026 10:55:10 AM	28.67	1243	34.4318965	-118.6451208	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
H-2165W	5/20/2026 9:46:57 AM	28.63	1288	34.4321328	-118.6504533	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header
H-2165W	5/12/2026 7:45:00 AM					Air Tech Lab
H-2165W	5/12/2026 7:45:00 AM					Air Tech Lab; [User entered 4.8%]

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
H-2165W	5/1/2026 10:16:24 AM	28.64	1271	34.4321427	-118.6504262	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-2166E	5/4/2026 1:12:58 PM	28.55	1371	34.4356305	-118.6438722	
H-2168C	5/1/2026 10:48:38 AM	28.47	1375	34.4344292	-118.6448553	
H-2168E	5/28/2026 12:08:16 PM	28.52	1377	34.4345323	-118.6439110	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum
H-2168E	5/6/2026 2:36:05 PM	28.63	1372	34.4345347	-118.6439215	Valve Adjustment:Audible Flow;Well Condition:Fair
H-2168E	5/5/2026 10:39:26 AM	28.51	1370	34.4345318	-118.6439165	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAC
H-2168E	5/5/2026 10:37:49 AM	28.51	1375	34.4345350	-118.6438788	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Surging Liquid in Well (Watered In)
H-2168E	5/1/2026 2:15:28 PM	28.48	1373	34.4345518	-118.6439033	
H-2169C	5/4/2026 11:55:39 AM	28.52	1394	34.4340773	-118.6450443	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
H-2169E	5/1/2026 2:05:32 PM	28.49	1376	34.4342528	-118.6442070	Valve Adjustment:Audible Flow;Well Condition:Fair
H-2170N	5/4/2026 2:04:41 PM	28.63	1269	34.4358222	-118.6414655	Valve Adjustment:Audible Flow
H-2170S	5/11/2026 8:29:12 AM	28.69	1273	34.4336432	-118.6414673	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-2171A	5/14/2026 8:58:08 AM	28.7	1280	34.4373700	-118.6425202	Valve Adjustment:Barely Open
H-2171A	5/14/2026 8:54:11 AM	28.69	1274	34.4373835	-118.6425463	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum
H-2171A	5/13/2026 10:13:53 AM	28.78	1255	34.4374078	-118.6425213	
H-2171A	5/13/2026 10:08:18 AM	28.79	1248	34.4373908	-118.6425195	Valve Adjustment:Decreased Flow/Vacuum
H-2171A	5/7/2026 9:32:22 AM	28.72	1250	34.4373920	-118.6425143	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-2171B	5/13/2026 2:00:46 PM	28.76	1274	34.4364970	-118.6416663	
H-2171N	5/7/2026 9:22:04 AM	28.71	1214	34.4380093	-118.6432513	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-2171S	5/4/2026 2:02:33 PM	28.64	1271	34.4358292	-118.6414683	Valve Adjustment:Decreased Flow/Vacuum
H-2272W	5/19/2026 10:27:12 AM	28.68	1287	34.4317278	-118.6497595	
H-2272W	5/4/2026 9:50:05 AM	28.63	1277	34.4317415	-118.6497550	
H-2272W	5/4/2026 9:47:59 AM	28.63	1279	34.4317347	-118.6497605	Valve Adjustment:Increased Flow/Vacuum,Barely Open
H-2273W	5/20/2026 8:21:56 AM	28.59	1306	34.4321578	-118.6499555	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
H-2273W	5/13/2026 12:42:00 PM	28.65	1322	34.4321628	-118.6499317	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-2273W	5/12/2026 7:50:00 AM					Air Tech Lab
H-2273W	5/12/2026 7:50:00 AM					Air Tech Lab; [User entered 0.59%]
H-2274B	5/20/2026 2:09:49 PM	28.58	1362	34.4327818	-118.6469517	
H-2274B	5/4/2026 1:23:52 PM	28.49	1322	34.4326350	-118.6469175	
H-2274W	5/19/2026 1:17:54 PM	28.63	1294	34.4327928	-118.6503735	Valve Adjustment:Barely Open
H-2274W	5/1/2026 10:22:35 AM	28.63	1298	34.4327832	-118.6503647	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
H-2275E	5/4/2026 11:24:01 AM	28.59	1322	34.4324075	-118.6461940	Valve Adjustment:Decreased Flow/Vacuum

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
H-2275W	5/20/2026 7:50:11 AM	28.55	1325	34.4322360	-118.6493985	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
H-2275W	5/8/2026 11:15:19 AM	28.55	1329	34.4321810	-118.6493895	
H-2275W	5/8/2026 11:13:59 AM	28.55	1306	34.4322273	-118.6494392	NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 to 1 Turn
H-2276A	5/20/2026 1:13:04 PM	28.5	1377	34.4328658	-118.6483068	Valve Adjustment:Reduce Sys. Vac. - Flare Down
H-2276A	5/11/2026 1:32:34 PM	28.57	1380	34.4328820	-118.6482900	Valve Adjustment:Reduce Sys. Vac. - Flare Down
H-2276B	5/20/2026 2:22:12 PM	28.41	1316	34.4329953	-118.6468977	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-2276B	5/4/2026 2:06:44 PM	28.46	1407	34.4328373	-118.6468900	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-2276E	5/4/2026 11:37:57 AM	28.59	1341	34.4328007	-118.6453388	Valve Adjustment:Barely Open
H-2276W	5/20/2026 8:32:50 AM	28.58	1320	34.4326735	-118.6499695	Valve Adjustment:Decreased Flow/Vacuum
H-2276W	5/1/2026 10:16:43 AM	28.59	1305	34.4326583	-118.6499853	Valve Adjustment:Decreased Flow/Vacuum
H-2277A	5/21/2026 9:41:03 AM	28.48	1362	34.4330293	-118.6487417	Valve Adjustment:Barely Open,Reduce Sys. Vac. - Flare Down
H-2277A	5/1/2026 11:04:15 AM	28.55	1351	34.4330352	-118.6487232	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum;Well Condition:Good
H-2277B	5/21/2026 9:35:16 AM	28.44	1389	34.4330752	-118.6469062	Valve Adjustment:Surging Liquid in Header
H-2277B	5/4/2026 2:19:04 PM	28.46	1473	34.4331148	-118.6469048	
H-23 (EXP-23)	5/13/2026 1:17:40 PM	28.76	1263	34.4370082	-118.6420873	Valve Adjustment:High O2,Plugged/Pinched Suspected
H-23 (EXP-23)	5/13/2026 1:13:21 PM	28.76	1252	34.4370062	-118.6420955	Valve Comment:Clear liquid from flex hose;Valve Adjustment:Orifice Plate Changed (See OP Log),High O2
H-23 (EXP-23)	5/13/2026 10:53:27 AM	28.79	1301	34.4370460	-118.6421150	Valve Adjustment:NSPS/EG CAI,Orifice Plate Changed (See OP Log),High O2,Decreased Flow/Vacuum
H-23 (EXP-23)	5/13/2026 10:40:54 AM	28.79	1251	34.4370065	-118.6421048	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Valve 100% Closed
H-2301E	5/13/2026 9:05:55 AM	29.02	1035	34.4270647	-118.6479965	
H-2301W	5/15/2026 10:14:58 AM	28.76	1165	34.4282912	-118.6508605	
H-2301W	5/15/2026 10:13:21 AM	28.76	1181	34.4283080	-118.6508505	High O2
H-2302C	5/7/2026 2:47:12 PM	28.72	1178	34.4284913	-118.6490545	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-2302E	5/8/2026 12:55:32 PM	28.77	1010	34.4275620	-118.6473168	
H-2303E	5/8/2026 1:01:15 PM	28.79	1086	34.4279038	-118.6470848	
H-2303N	5/7/2026 2:55:44 PM	28.71	1270	34.4290517	-118.6485457	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-2304E	5/8/2026 1:05:45 PM	28.79	1066	34.4282910	-118.6469717	
H-2304S	5/8/2026 1:30:30 PM	28.77	1102	34.4275005	-118.6489317	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-2305N	5/7/2026 3:01:47 PM	28.69	1234	34.4290775	-118.6486402	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-2305S	5/8/2026 1:14:11 PM	28.78	1040	34.4274637	-118.6484590	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
H-2306N	5/15/2026 10:33:03 AM	28.74	1171	34.4294673	-118.6475270	
H-2307S	5/22/2026 11:53:04 AM	28.67	1127	34.4282258	-118.6498862	Valve Adjustment:Audible Flow
H-2307S	5/7/2026 2:41:47 PM	28.72	1184	34.4283230	-118.6499335	
H-2307S	5/7/2026 2:40:20 PM	28.72	1214	34.4282598	-118.6498622	NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 to 1 Turn
H-2308S	5/7/2026 2:29:52 PM	28.72	1109	34.4283483	-118.6498983	Reduced System Vacuum
H-2309N	5/4/2026 10:13:40 AM	28.55	1312	34.4316015	-118.6489425	
H-2309S	5/8/2026 1:53:32 PM	28.74	1099	34.4281668	-118.6488530	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-2310N	5/8/2026 3:03:25 PM	28.68	1115	34.4299800	-118.6478832	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-2310S	5/22/2026 12:06:57 PM	28.71	1120	34.4291798	-118.6475352	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
H-2310S	5/14/2026 9:47:40 AM	28.8	1102	34.4291448	-118.6476128	
H-2401S	5/7/2026 11:32:52 AM	28.68	1178	34.4289090	-118.6512467	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-2402N	5/8/2026 9:47:00 AM	28.71	1237	34.4290415	-118.6501617	
H-2402S	5/8/2026 9:58:19 AM	28.7	1184	34.4287787	-118.6504880	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-2403N	5/8/2026 9:51:09 AM	28.68	1178	34.4293443	-118.6502303	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-2403S	5/8/2026 9:35:34 AM	28.74	1191	34.4287068	-118.6498640	
H-2404N	5/5/2026 3:35:40 PM	28.63	1217	34.4292643	-118.6494898	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-2404S	5/8/2026 8:59:38 AM	28.77	1191	34.4287530	-118.6493000	
H-2405N	5/5/2026 2:23:59 PM	28.56	1247	34.4299727	-118.6495100	
H-29	5/29/2026 12:05:20 PM	28.67	1283	34.4354267	-118.6417648	Valve Adjustment:NSPS/EG CAC
H-29	5/29/2026 12:00:31 PM	28.7	1281	34.4354368	-118.6417790	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
H-29	5/4/2026 1:58:42 PM	28.63	1273	34.4354442	-118.6417735	Valve Adjustment:NSPS/EG CAC
H-29	5/4/2026 1:55:50 PM	28.63	1278	34.4354300	-118.6417690	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
H-72	5/29/2026 9:51:57 AM	28.67	1325	34.4368798	-118.6448662	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
H-74	5/11/2026 11:20:34 AM	28.57	1257	34.4370635	-118.6431107	
H-75	5/14/2026 11:59:28 AM	28.59	1345	34.4363457	-118.6420747	
H-79	5/15/2026 11:24:44 AM	28.65	1325	34.4340572	-118.6428650	No Adjustment Made,Audible Flow
P-02R	5/13/2026 8:15:30 AM	28.87	1157	34.4297442	-118.6439258	
P-03R	5/13/2026 8:26:58 AM	28.87	1173	34.4298598	-118.6442158	
P-04	5/5/2026 7:38:51 AM	28.71	1176	34.4294557	-118.6445353	
P-05	5/5/2026 7:46:02 AM	28.73	1146	34.4291723	-118.6447730	Well Condition:Fair;Well Repairs:Flex Hose
P-06R	5/5/2026 7:49:46 AM	28.72	1139	34.4288705	-118.6450635	Well Condition:Fair
P-07R	5/12/2026 8:59:48 AM	28.72	1169	34.4298372	-118.6432867	
P-08R	5/11/2026 10:46:01 AM	28.86	1153	34.4294120	-118.6437068	Valve Adjustment:Audible Flow
P-09	5/5/2026 8:01:21 AM	28.71	1162	34.4290035	-118.6442565	Valve Adjustment:Audible Flow;Well Condition:Fair;Well Repairs:Flex Hose

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
P-10	5/5/2026 7:56:04 AM	28.71	1145	34.4287117	-118.6446435	Well Condition:Good
P-11	5/12/2026 9:25:09 AM	28.76	1134	34.4285110	-118.6449670	
P-12	5/15/2026 7:59:36 AM	28.82	1115	34.4288363	-118.6456393	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
P-13	5/15/2026 8:05:44 AM	28.83	1135	34.4285183	-118.6457337	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
P-14	5/5/2026 8:13:25 AM	28.78	1106	34.4280348	-118.6460672	Valve Adjustment:Decreased Flow/Vacuum
P-15R	5/5/2026 8:17:20 AM	28.77	1107	34.4277893	-118.6459260	
P-16	5/5/2026 8:25:52 AM	28.78	1103	34.4275337	-118.6456078	
P-17	5/5/2026 8:30:43 AM	28.77	1096	34.4273773	-118.6453377	
P-18RD	5/5/2026 8:41:50 AM	28.78	1103	34.4271108	-118.6450018	
P-18RS	5/5/2026 8:36:36 AM	28.78	1099	34.4271123	-118.6450190	
P-19	5/4/2026 11:16:30 AM	28.84	1089	34.4268377	-118.6451812	
P-20R	5/5/2026 8:45:27 AM	28.78	1101	34.4268247	-118.6448280	
P-21	5/5/2026 8:49:59 AM	28.78	1110	34.4265067	-118.6447967	
P-21RD	5/4/2026 10:03:26 AM	28.81	1142	34.4263675	-118.6443280	No Adjustment Made
P-21RS	5/4/2026 10:00:38 AM	28.83	1138	34.4264085	-118.6443853	
P-22RD	5/4/2026 10:32:00 AM	28.77	1171	34.4269110	-118.6438215	Increased Flow/Vacuum
P-22RS	5/4/2026 10:28:52 AM	28.76	1178	34.4269142	-118.6437452	
P-23	5/5/2026 8:59:25 AM	28.78	1110	34.4261428	-118.6447117	Valve Adjustment:Orifice Plate Changed (See OP Log)
P-24	5/6/2026 8:17:07 AM	28.91	1109	34.4260808	-118.6442818	
P-26	5/6/2026 8:34:09 AM	28.89	1148	34.4265393	-118.6431935	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
P-27	5/6/2026 8:43:29 AM	28.89	1155	34.4268782	-118.6427508	
P-28	5/6/2026 8:51:00 AM	28.88	1148	34.4270348	-118.6422415	
P-29R	5/6/2026 8:57:44 AM	28.87	1171	34.4271623	-118.6418718	
P-30R	5/6/2026 9:04:44 AM	28.87	1184	34.4274230	-118.6415790	
P-32R1	5/6/2026 9:10:45 AM	28.85	1161	34.4282355	-118.6410790	
P-32R2	5/6/2026 9:14:09 AM	28.85	1175	34.4284572	-118.6410243	
P-33	5/6/2026 9:19:40 AM	28.84	1211	34.4287705	-118.6407780	No Flow Measurement
P-36	5/6/2026 9:31:05 AM	28.83	1217	34.4302865	-118.6400428	No Adjustment Made
P-37	5/6/2026 9:35:20 AM	28.81	1243	34.4305062	-118.6404012	
P-38RD	5/6/2026 9:48:07 AM	28.8	1207	34.4299953	-118.6406215	No Adjustment Made
P-38RS	5/6/2026 9:44:32 AM	28.81	1217	34.4299980	-118.6406513	
P-39	5/6/2026 9:55:17 AM	28.81	1220	34.4294320	-118.6409958	No Adjustment Made
P-41	5/6/2026 10:07:48 AM	28.81	1214	34.4288583	-118.6413945	NSPS/EG CAI,High O2
P-41	5/6/2026 10:06:10 AM	28.81	1240	34.4288862	-118.6414418	NSPS/EG CAI,High O2
P-42R	5/6/2026 10:15:47 AM	28.81	1194	34.4284612	-118.6417320	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
P-43	5/6/2026 10:22:56 AM	28.82	1224	34.4282822	-118.6418015	
P-44RD	5/6/2026 10:37:00 AM	28.81	1155	34.4280457	-118.6421608	Increased Flow/Vacuum
P-44RS	5/6/2026 10:33:49 AM	28.82	1188	34.4281768	-118.6418202	
P-45RD	5/6/2026 10:50:26 AM	28.82	1204	34.4276827	-118.6424397	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
P-45RS	5/6/2026 10:47:34 AM	28.81	1184	34.4277275	-118.6424702	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
P-46RD	5/6/2026 11:02:37 AM	28.81	1201	34.4277323	-118.6427357	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
P-46RS	5/6/2026 10:55:16 AM	28.82	1211	34.4276638	-118.6426433	
P-47	5/4/2026 10:21:39 AM	28.73	1214	34.4274452	-118.6432183	No Flow Measurement
P-48	5/4/2026 10:38:03 AM	28.74	1204	34.4275840	-118.6435617	
P-49RD	5/4/2026 10:58:34 AM	28.74	1201	34.4279272	-118.6438430	Increased Flow/Vacuum
P-49RS	5/4/2026 10:55:41 AM	28.74	1194	34.4279627	-118.6438450	
P-52	5/28/2026 2:38:45 PM	28.64	1219	34.4287193	-118.6432857	Valve Adjustment:Barely Open
P-53	5/15/2026 8:37:53 AM	28.73	1234	34.4291410	-118.6431228	Audible Flow
P-54	5/15/2026 8:35:38 AM	28.72	1220	34.4292002	-118.6431255	
P-55	5/15/2026 8:24:48 AM	28.71	1234	34.4297752	-118.6426818	Audible Flow,No Flow Measurement
P-56	5/26/2026 9:15:49 AM	28.57	1220	34.4300997	-118.6428133	
P-57	5/13/2026 9:14:04 AM	28.8	1253	34.4299728	-118.6424557	
P-60R	5/7/2026 8:52:45 AM	28.74	1263	34.4307783	-118.6415790	NSPS/EG CAI,High O2
P-60R	5/7/2026 8:48:07 AM	28.74	1207	34.4307893	-118.6415645	NSPS/EG CAI,High O2
P-61	5/7/2026 8:30:07 AM	28.72	1289	34.4311355	-118.6411517	Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less
P-65	5/7/2026 8:25:21 AM	28.76	1263	34.4304160	-118.6409915	
P-71	5/4/2026 10:47:48 AM	28.73	1220	34.4279280	-118.6431523	No Adjustment Made
P-75	5/6/2026 11:19:49 AM	28.8	1217	34.4302853	-118.6415073	No Adjustment Made,Increased Flow/Vacuum
P-76	5/6/2026 9:41:27 AM	28.8	1230	34.4300573	-118.6406000	
P-79	5/4/2026 11:21:51 AM	28.92	1004	34.4271028	-118.6460305	No Flow Measurement
SC-2000E	5/6/2026 12:28:45 PM	28.72	1204	34.4307167	-118.6467057	
SC-2501E	5/26/2026 9:21:31 AM	28.47	1367	34.4366668	-118.6478788	Valve Adjustment:High Temp,Valve 100% Open;Well Repairs:Valve
SC-2501E	5/18/2026 9:40:35 AM	28.51	1360	34.4366875	-118.6478968	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open;Well Repairs:Valve
SC-2501E	5/18/2026 9:40:00 AM					AtmAA
SC-2501E	5/18/2026 9:38:11 AM	28.52	1358	34.4366869	-118.6478978	Valve Adjustment:High Temp,Reduce Sys. Vac. - Flare Down
SC-2501E	5/18/2026 9:29:29 AM	28.53	1357	34.4366436	-118.6478826	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down
SC-2501E	5/12/2026 9:13:45 AM	28.55	1341	34.4367005	-118.6479329	Valve Adjustment:High Temp
SC-2501E	5/12/2026 9:10:00 AM					AtmAA
SC-2501E	5/5/2026 8:56:40 AM	28.52	1344	34.4366786	-118.6479108	Valve Adjustment:High Temp
SC-2501E	5/5/2026 8:51:59 AM	28.51	1341	34.4366711	-118.6479123	Valve Adjustment:Orifice Plate Changed (See OP Log),High Temp
SC-2501E	5/5/2026 8:50:00 AM					AtmAA
SC-2501E	5/5/2026 8:50:00 AM					AtmAA; [User entered 17.77%]
SC-2501W	5/5/2026 9:19:42 AM	28.51	1358	34.4367915	-118.6485240	Valve Comment:Bad well heat valve does not open;Valve Adjustment:NSPS/EG CAC,Increased Flow/Vacuum,Valve 100% Open
SW-10	5/28/2026 9:37:50 AM	28.57	1343	34.4370242	-118.6503695	
SW-115	5/11/2026 8:59:04 AM	28.73	1214	34.4348128	-118.6412347	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
SW-1445	5/22/2026 7:39:28 AM	28.59	1228	34.4325033	-118.6519762	
SW-1445	5/4/2026 7:53:57 AM	28.7	1216	34.4325060	-118.6520183	
SW-1455	5/22/2026 7:44:18 AM	28.59	1204	34.4323960	-118.6519070	
SW-1455	5/4/2026 7:57:56 AM	28.7	1199	34.4324083	-118.6519080	
SW-154	5/15/2026 9:34:29 AM	28.7	1243	34.4379895	-118.6456350	NSPS/EG CAI,No Flow Measurement,High O2
SW-154	5/15/2026 9:31:56 AM	28.7	1289	34.4379950	-118.6456550	NSPS/EG CAI,No Flow Measurement,High O2
SW-17-135	5/22/2026 7:41:29 AM	28.59	1195	34.4324443	-118.6519940	
SW-17-135	5/4/2026 7:56:03 AM	28.7	1216	34.4324535	-118.6520098	
SW-187	5/4/2026 9:31:29 AM	28.6	1319	34.4372602	-118.6473498	
SW-1930	5/1/2026 7:51:05 AM	28.6	1265	34.4353082	-118.6516128	Valve Adjustment:Audible Flow
SW-20	5/12/2026 9:06:57 AM	28.72	1168	34.4302393	-118.6436463	
SW-25	5/1/2026 7:53:15 AM	28.63	1253	34.4351710	-118.6516867	Valve Adjustment:Valve 100% Closed
SW-2501D	5/29/2026 7:21:12 AM	28.77	1208	34.4335080	-118.6519720	Valve Adjustment:Valve 100% Open
SW-2501D	5/28/2026 6:16:27 AM	28.63	1212	34.4335467	-118.6519558	
SW-2501D	5/27/2026 6:04:20 AM	28.52	1214	34.4334993	-118.6519592	Valve Adjustment:Reduce Sys. Vac. - Flare Down
SW-2501D	5/26/2026 6:11:29 AM	28.59	1194	34.4335195	-118.6519752	
SW-2501D	5/22/2026 6:19:43 AM	28.56	1198	34.4335292	-118.6519572	
SW-2501D	5/21/2026 6:35:47 AM	28.61	1204	34.4335218	-118.6519610	
SW-2501D	5/20/2026 8:30:45 AM	28.67	1199	34.4334947	-118.6519580	Valve Adjustment:Valve 100% Open
SW-2501D	5/19/2026 9:01:29 AM	28.75	1209	34.4334962	-118.6519523	Valve Adjustment:Valve 100% Open
SW-2501D	5/18/2026 8:44:45 AM	28.66	1207	34.4335105	-118.6519608	
SW-2501D	5/15/2026 9:25:43 AM	28.71	1211	34.4335195	-118.6519642	
SW-2501D	5/14/2026 8:19:05 AM	28.75	1202	34.4335260	-118.6519660	Valve Adjustment:Valve 100% Open
SW-2501D	5/13/2026 8:08:49 AM	28.82	1202	34.4334913	-118.6519685	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
SW-2501D	5/12/2026 9:15:23 AM	28.67	1208	34.4335090	-118.6519602	Valve Adjustment:Valve 100% Open,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
SW-2501D	5/11/2026 8:24:00 AM	28.71	1220	34.4335182	-118.6519562	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
SW-2501D	5/8/2026 9:35:42 AM	28.71	1209	34.4334960	-118.6519422	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
SW-2501D	5/7/2026 8:55:20 AM	28.75	1202	34.4335105	-118.6519538	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
SW-2501D	5/6/2026 8:47:06 AM	28.78	1230	34.4335140	-118.6519823	Valve Adjustment:Valve 100% Open,Surging Liquid in Header
SW-2501D	5/5/2026 8:31:57 AM	28.67	1209	34.4335015	-118.6519653	Valve Adjustment:Barely Open,Surging Liquid in Header
SW-2501D	5/4/2026 8:20:15 AM	28.7	1188	34.4335058	-118.6519633	Valve Adjustment:Audible Flow
SW-2501D	5/1/2026 8:28:56 AM	28.68	1206	34.4335202	-118.6519598	Valve Adjustment:Audible Flow;Well Condition:Good
SW-2501M	5/29/2026 7:24:25 AM	28.78	1212	34.4335182	-118.6519538	Valve Adjustment:Valve 100% Open

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
SW-2501M	5/28/2026 6:12:29 AM	28.63	1209	34.4335263	-118.6519477	
SW-2501M	5/27/2026 5:59:22 AM	28.52	1221	34.4335113	-118.6519733	Valve Adjustment:Reduce Sys. Vac. - Flare Down
SW-2501M	5/26/2026 6:01:33 AM	28.59	1209	34.4335222	-118.6519473	
SW-2501M	5/22/2026 6:14:16 AM	28.56	1206	34.4335062	-118.6519473	
SW-2501M	5/21/2026 6:30:13 AM	28.63	1202	34.4335080	-118.6519493	
SW-2501M	5/20/2026 8:25:51 AM	28.7	1205	34.4335122	-118.6519752	Valve Adjustment:Valve 100% Open
SW-2501M	5/19/2026 8:55:12 AM	28.75	1216	34.4335108	-118.6519538	Valve Adjustment:Valve 100% Open
SW-2501M	5/18/2026 8:38:11 AM	28.63	1208	34.4335058	-118.6519498	
SW-2501M	5/15/2026 9:19:11 AM	28.72	1216	34.4335352	-118.6519838	
SW-2501M	5/14/2026 8:13:12 AM	28.75	1232	34.4335345	-118.6519475	
SW-2501M	5/13/2026 8:03:42 AM	28.79	1202	34.4335012	-118.6519710	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
SW-2501M	5/12/2026 9:11:04 AM	28.67	1208	34.4335005	-118.6519717	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
SW-2501M	5/11/2026 8:20:03 AM	28.71	1241	34.4335292	-118.6519752	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
SW-2501M	5/8/2026 9:30:13 AM	28.71	1205	34.4334985	-118.6519497	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
SW-2501M	5/7/2026 8:50:28 AM	28.75	1205	34.4335083	-118.6519487	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
SW-2501M	5/6/2026 8:42:31 AM	28.78	1236	34.4335165	-118.6519673	Valve Adjustment:Valve 100% Open,Surging Liquid in Header
SW-2501M	5/5/2026 8:23:44 AM	28.67	1213	34.4335072	-118.6519787	Valve Adjustment:Barely Open,Surging Liquid in Header
SW-2501M	5/4/2026 8:14:55 AM	28.7	1195	34.4335072	-118.6519662	Valve Adjustment:Audible Flow
SW-2501M	5/1/2026 8:25:32 AM	28.7	1213	34.4335257	-118.6519562	Valve Adjustment:Audible Flow;Well Condition:Good
SW-2501MD	5/29/2026 7:15:49 AM	28.76	1214	34.4335063	-118.6519613	Valve Adjustment:Valve 100% Open
SW-2501MD	5/28/2026 6:14:16 AM	28.63	1216	34.4335208	-118.6519582	
SW-2501MD	5/27/2026 6:02:25 AM	28.52	1210	34.4335200	-118.6519492	Valve Adjustment:Reduce Sys. Vac. - Flare Down
SW-2501MD	5/26/2026 6:05:27 AM	28.59	1216	34.4335238	-118.6519560	
SW-2501MD	5/22/2026 6:16:46 AM	28.56	1204	34.4335067	-118.6519538	
SW-2501MD	5/21/2026 6:32:26 AM	28.6	1215	34.4335160	-118.6519452	
SW-2501MD	5/20/2026 8:28:56 AM	28.7	1197	34.4335013	-118.6519777	Valve Adjustment:Valve 100% Open
SW-2501MD	5/19/2026 8:58:19 AM	28.75	1205	34.4335145	-118.6519443	Valve Adjustment:Valve 100% Open
SW-2501MD	5/18/2026 8:41:43 AM	28.65	1211	34.4335008	-118.6519532	
SW-2501MD	5/14/2026 8:16:25 AM	28.75	1220	34.4335148	-118.6519580	Valve Adjustment:High O2,Valve 100% Open
SW-2501MD	5/13/2026 8:06:36 AM	28.82	1209	34.4335015	-118.6519472	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
SW-2501MD	5/12/2026 9:12:49 AM	28.67	1208	34.4335060	-118.6519697	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
SW-2501MD	5/11/2026 8:21:50 AM	28.71	1233	34.4335238	-118.6519727	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
SW-2501MD	5/8/2026 9:32:28 AM	28.75	1204	34.4334947	-118.6519282	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
SW-2501MD	5/7/2026 8:53:13 AM	28.75	1206	34.4335125	-118.6519475	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
SW-2501MD	5/6/2026 8:45:13 AM	28.78	1238	34.4335165	-118.6519718	Valve Adjustment:Valve 100% Open,Surging Liquid in Header
SW-2501MD	5/5/2026 8:27:56 AM	28.67	1203	34.4335097	-118.6519517	Valve Adjustment:Valve 100% Closed,Surging Liquid in Header
SW-2501MD	5/4/2026 8:17:07 AM	28.67	1207	34.4335143	-118.6519833	Valve Adjustment:Audible Flow
SW-2501MD	5/1/2026 8:27:27 AM	28.67	1204	34.4335243	-118.6519692	Valve Adjustment:Audible Flow;Well Condition:Good
SW-2501S	5/29/2026 7:18:48 AM	28.78	1202	34.4335062	-118.6519753	Valve Adjustment:Valve 100% Open
SW-2501S	5/28/2026 6:18:35 AM	28.63	1207	34.4335115	-118.6519555	
SW-2501S	5/27/2026 6:06:12 AM	28.52	1202	34.4335105	-118.6519705	Valve Adjustment:Reduce Sys. Vac. - Flare Down
SW-2501S	5/26/2026 6:14:28 AM	28.59	1210	34.4335415	-118.6519715	
SW-2501S	5/22/2026 6:22:20 AM	28.56	1203	34.4335172	-118.6519550	
SW-2501S	5/21/2026 6:38:09 AM	28.61	1201	34.4334975	-118.6519645	
SW-2501S	5/20/2026 8:33:18 AM	28.67	1201	34.4335063	-118.6519662	Valve Adjustment:Valve 100% Open
SW-2501S	5/19/2026 9:04:28 AM	28.75	1210	34.4335102	-118.6519533	Valve Adjustment:Valve 100% Open
SW-2501S	5/18/2026 8:47:27 AM	28.66	1210	34.4335008	-118.6519640	
SW-2501S	5/15/2026 9:27:58 AM	28.71	1209	34.4335302	-118.6519562	
SW-2501S	5/15/2026 9:22:25 AM	28.71	1201	34.4335372	-118.6519382	
SW-2501S	5/14/2026 8:22:49 AM	28.75	1213	34.4335095	-118.6519472	Valve Adjustment:High O2,Valve 100% Open
SW-2501S	5/13/2026 8:12:06 AM	28.81	1205	34.4335047	-118.6519632	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
SW-2501S	5/12/2026 9:17:43 AM	28.67	1205	34.4334968	-118.6519437	Valve Adjustment:Valve 100% Open,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
SW-2501S	5/11/2026 8:26:36 AM	28.71	1223	34.4335232	-118.6519632	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
SW-2501S	5/8/2026 9:39:11 AM	28.73	1208	34.4334922	-118.6519465	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
SW-2501S	5/7/2026 9:00:17 AM	28.75	1206	34.4335225	-118.6519500	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
SW-2501S	5/6/2026 8:51:41 AM	28.78	1227	34.4335092	-118.6519708	Valve Adjustment:Valve 100% Open,Surging Liquid in Header
SW-2501S	5/5/2026 8:36:07 AM	28.67	1212	34.4335002	-118.6519537	Valve Adjustment:Valve 100% Open,Surging Liquid in Header
SW-2501S	5/4/2026 8:22:18 AM	28.68	1205	34.4335283	-118.6519558	Valve Adjustment:Audible Flow
SW-2501S	5/1/2026 8:30:42 AM	28.69	1206	34.4335170	-118.6519717	Valve Adjustment:Audible Flow;Well Condition:Good

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
SW-2502D	5/29/2026 7:02:56 AM	28.78	1203	34.4337180	-118.6518868	Valve Adjustment:Valve 100% Open
SW-2502D	5/28/2026 6:27:56 AM	28.63	1217	34.4337380	-118.6518905	
SW-2502D	5/27/2026 6:15:12 AM	28.51	1217	34.4337258	-118.6518730	Valve Adjustment:Reduce Sys. Vac. - Flare Down
SW-2502D	5/26/2026 6:28:54 AM	28.59	1212	34.4337275	-118.6518903	
SW-2502D	5/22/2026 6:34:30 AM	28.59	1214	34.4337385	-118.6518817	
SW-2502D	5/21/2026 6:50:59 AM	28.62	1207	34.4337337	-118.6518865	
SW-2502D	5/20/2026 8:15:28 AM	28.69	1206	34.4337277	-118.6518858	Valve Adjustment:Valve 100% Open
SW-2502D	5/19/2026 9:17:49 AM	28.75	1216	34.4337280	-118.6518860	Valve Adjustment:Valve 100% Open
SW-2502D	5/18/2026 8:59:18 AM	28.63	1216	34.4337255	-118.6518978	
SW-2502D	5/15/2026 9:08:52 AM	28.71	1216	34.4337363	-118.6518468	
SW-2502D	5/14/2026 8:37:14 AM	28.75	1214	34.4337347	-118.6518788	Valve Adjustment:Valve 100% Open
SW-2502D	5/13/2026 8:21:57 AM	28.82	1219	34.4337202	-118.6519083	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
SW-2502D	5/12/2026 9:27:18 AM	28.67	1213	34.4337305	-118.6518858	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
SW-2502D	5/11/2026 8:36:30 AM	28.71	1210	34.4337307	-118.6518923	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
SW-2502D	5/8/2026 9:49:11 AM	28.72	1214	34.4337170	-118.6518773	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
SW-2502D	5/7/2026 9:13:11 AM	28.75	1212	34.4337435	-118.6519035	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
SW-2502D	5/6/2026 9:03:29 AM	28.79	1223	34.4337280	-118.6518957	Valve Adjustment:Valve 100% Open,Surging Liquid in Header
SW-2502D	5/5/2026 8:48:17 AM	28.67	1230	34.4337398	-118.6518983	Valve Adjustment:Valve 100% Open,Surging Liquid in Header
SW-2502D	5/4/2026 8:29:47 AM	28.67	1205	34.4337345	-118.6518757	Valve Adjustment:Audible Flow
SW-2502D	5/1/2026 8:39:01 AM	28.67	1214	34.4337297	-118.6518810	Valve Adjustment:Audible Flow;Well Condition:Good
SW-2502M	5/29/2026 6:58:21 AM	28.77	1216	34.4337387	-118.6518822	Valve Adjustment:Valve 100% Open
SW-2502M	5/28/2026 6:26:04 AM	28.63	1218	34.4337358	-118.6518773	
SW-2502M	5/27/2026 6:13:20 AM	28.52	1205	34.4337292	-118.6518858	Valve Adjustment:Reduce Sys. Vac. - Flare Down
SW-2502M	5/26/2026 6:25:59 AM	28.59	1213	34.4337368	-118.6518747	
SW-2502M	5/22/2026 6:31:26 AM	28.56	1203	34.4337455	-118.6518742	
SW-2502M	5/21/2026 6:48:59 AM	28.61	1210	34.4337555	-118.6518850	
SW-2502M	5/20/2026 8:13:58 AM	28.68	1214	34.4337308	-118.6519055	Valve Adjustment:Valve 100% Open
SW-2502M	5/19/2026 9:14:46 AM	28.75	1220	34.4337343	-118.6518632	Valve Adjustment:Valve 100% Open
SW-2502M	5/18/2026 8:56:28 AM	28.63	1209	34.4337413	-118.6518853	
SW-2502M	5/15/2026 9:04:47 AM	28.71	1217	34.4337558	-118.6518752	
SW-2502M	5/14/2026 8:34:30 AM	28.75	1219	34.4337393	-118.6518742	Valve Adjustment:Valve 100% Open
SW-2502M	5/13/2026 8:19:53 AM	28.81	1213	34.4337283	-118.6518945	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
SW-2502M	5/12/2026 9:25:33 AM	28.67	1214	34.4337280	-118.6518818	Valve Adjustment:Valve 100% Open,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
SW-2502M	5/11/2026 8:34:43 AM	28.71	1220	34.4337318	-118.6518887	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
SW-2502M	5/8/2026 9:47:15 AM	28.73	1211	34.4337167	-118.6518817	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
SW-2502M	5/7/2026 9:10:36 AM	28.75	1215	34.4337353	-118.6519033	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
SW-2502M	5/6/2026 9:01:23 AM	28.79	1220	34.4337372	-118.6518923	Valve Adjustment:Valve 100% Open,Surging Liquid in Header
SW-2502M	5/5/2026 8:46:24 AM	28.67	1228	34.4337390	-118.6518992	Valve Adjustment:Valve 100% Open,Surging Liquid in Header
SW-2502M	5/4/2026 8:28:19 AM	28.69	1203	34.4337417	-118.6518647	Valve Adjustment:Audible Flow
SW-2502M	5/1/2026 8:36:49 AM	28.67	1203	34.4337415	-118.6518992	Valve Adjustment:Audible Flow;Well Condition:Good
SW-2502MD	5/29/2026 7:08:57 AM	28.75	1204	34.4337250	-118.6518942	Valve Adjustment:Valve 100% Open
SW-2502MD	5/28/2026 6:29:56 AM	28.63	1219	34.4337292	-118.6518797	
SW-2502MD	5/27/2026 6:16:47 AM	28.49	1215	34.4337263	-118.6518863	Valve Adjustment:Reduce Sys. Vac. - Flare Down
SW-2502MD	5/26/2026 6:31:21 AM	28.59	1210	34.4337317	-118.6518855	
SW-2502MD	5/22/2026 6:36:17 AM	28.59	1209	34.4337372	-118.6518950	
SW-2502MD	5/21/2026 6:52:38 AM	28.61	1206	34.4337335	-118.6518958	
SW-2502MD	5/20/2026 8:17:46 AM	28.68	1214	34.4337253	-118.6518992	Valve Adjustment:Valve 100% Open
SW-2502MD	5/19/2026 9:20:34 AM	28.75	1211	34.4337235	-118.6518815	Valve Adjustment:Valve 100% Open
SW-2502MD	5/18/2026 9:02:05 AM	28.63	1206	34.4337208	-118.6518838	
SW-2502MD	5/15/2026 9:12:10 AM	28.71	1204	34.4337573	-118.6518592	
SW-2502MD	5/14/2026 8:39:47 AM	28.75	1210	34.4337373	-118.6518768	Valve Adjustment:Valve 100% Open
SW-2502MD	5/13/2026 8:24:00 AM	28.81	1219	34.4337222	-118.6518988	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
SW-2502MD	5/12/2026 9:28:53 AM	28.67	1206	34.4337260	-118.6518780	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
SW-2502MD	5/11/2026 8:38:07 AM	28.71	1215	34.4337275	-118.6518900	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
SW-2502MD	5/8/2026 9:51:10 AM	28.73	1209	34.4337140	-118.6518795	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
SW-2502MD	5/7/2026 9:14:39 AM	28.75	1214	34.4337330	-118.6518933	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
SW-2502MD	5/6/2026 9:05:22 AM	28.8	1218	34.4337258	-118.6518817	Valve Adjustment:Valve 100% Open,Surging Liquid in Header
SW-2502MD	5/5/2026 8:50:15 AM	28.67	1215	34.4337330	-118.6519118	
SW-2502MD	5/4/2026 8:31:32 AM	28.68	1207	34.4337338	-118.6518708	Valve Adjustment:Audible Flow

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
SW-2502MD	5/1/2026 8:41:00 AM	28.68	1208	34.4337288	-118.6518977	Valve Adjustment:Audible Flow;Well Condition:Good
SW-2502S	5/29/2026 6:54:54 AM	28.74	1212	34.4337433	-118.6518830	Valve Adjustment:Valve 100% Open
SW-2502S	5/28/2026 6:24:10 AM	28.61	1248	34.4337530	-118.6518642	
SW-2502S	5/27/2026 6:11:24 AM	28.52	1207	34.4337375	-118.6518813	Valve Adjustment:Reduce Sys. Vac. - Flare Down
SW-2502S	5/26/2026 6:23:43 AM	28.59	1210	34.4337423	-118.6518857	
SW-2502S	5/22/2026 6:29:06 AM	28.56	1208	34.4337463	-118.6518768	
SW-2502S	5/21/2026 6:47:21 AM	28.6	1216	34.4337362	-118.6518680	
SW-2502S	5/20/2026 8:12:10 AM	28.67	1206	34.4337157	-118.6519175	Valve Adjustment:Valve 100% Open
SW-2502S	5/19/2026 9:11:46 AM	28.75	1211	34.4337440	-118.6518923	Valve Adjustment:Valve 100% Open
SW-2502S	5/18/2026 8:53:31 AM	28.64	1216	34.4337287	-118.6518823	
SW-2502S	5/15/2026 9:00:33 AM	28.71	1219	34.4337487	-118.6518757	
SW-2502S	5/14/2026 8:31:19 AM	28.75	1209	34.4337353	-118.6518602	Valve Adjustment:Valve 100% Open
SW-2502S	5/13/2026 8:17:54 AM	28.81	1207	34.4337320	-118.6519045	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
SW-2502S	5/12/2026 9:23:35 AM	28.67	1211	34.4337322	-118.6518982	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
SW-2502S	5/11/2026 8:32:32 AM	28.71	1220	34.4337297	-118.6518908	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
SW-2502S	5/8/2026 9:44:33 AM	28.72	1221	34.4337133	-118.6518933	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
SW-2502S	5/7/2026 9:08:55 AM	28.75	1215	34.4337305	-118.6518963	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
SW-2502S	5/6/2026 8:59:15 AM	28.79	1224	34.4337393	-118.6518947	Valve Adjustment:Valve 100% Open,Surging Liquid in Header
SW-2502S	5/5/2026 8:44:34 AM	28.67	1233	34.4337382	-118.6519108	Valve Adjustment:Valve 100% Open,Surging Liquid in Header
SW-2502S	5/4/2026 8:26:37 AM	28.67	1210	34.4337507	-118.6518850	Valve Adjustment:Audible Flow
SW-2502S	5/1/2026 8:35:09 AM	28.68	1219	34.4337523	-118.6518728	Valve Adjustment:Audible Flow;Well Condition:Good
SW-2503D	5/12/2026 8:21:40 AM	28.64	1264	34.4351480	-118.6516022	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
SW-2503D	5/4/2026 8:56:42 AM	28.64	1255	34.4351298	-118.6516002	
SW-2503M	5/12/2026 8:27:21 AM	28.64	1281	34.4351567	-118.6516085	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
SW-2503M	5/4/2026 9:01:03 AM	28.65	1252	34.4351233	-118.6516122	
SW-2503MD	5/12/2026 8:24:48 AM	28.64	1288	34.4351615	-118.6515915	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
SW-2503MD	5/4/2026 8:58:22 AM	28.64	1250	34.4351277	-118.6516077	
SW-2503S	5/12/2026 8:35:33 AM	28.64	1268	34.4351488	-118.6516155	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
SW-2503S	5/4/2026 9:03:12 AM	28.66	1253	34.4351183	-118.6515878	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
SW-2504D	5/12/2026 8:47:37 AM	28.63	1258	34.4353063	-118.6516675	Valve Adjustment:Valve 100% Open,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
SW-2504D	5/4/2026 9:08:28 AM	28.64	1273	34.4353260	-118.6516635	
SW-2504M	5/12/2026 8:49:55 AM	28.64	1254	34.4353062	-118.6516587	Valve Adjustment:Valve 100% Open,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
SW-2504M	5/4/2026 9:18:12 AM	28.66	1261	34.4353227	-118.6516630	
SW-2504MD	5/20/2026 1:56:54 PM	28.41	1395	34.4358698	-118.6469320	Valve Adjustment:High Temp,Barely Open
SW-2504MD	5/12/2026 8:55:07 AM	28.63	1260	34.4353003	-118.6516498	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
SW-2504MD	5/4/2026 9:22:21 AM	28.63	1266	34.4353153	-118.6516580	
SW-2504S	5/12/2026 8:51:59 AM	28.63	1252	34.4353105	-118.6516642	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
SW-2504S	5/4/2026 9:20:08 AM	28.66	1262	34.4353177	-118.6516593	
SW-30	5/22/2026 6:43:04 AM	28.56	1216	34.4336823	-118.6519708	
SW-30	5/21/2026 7:02:29 AM	28.62	1207	34.4336915	-118.6519930	
SW-30	5/20/2026 8:03:41 AM	28.67	1212	34.4336927	-118.6519757	Valve Comment:no system vacuum
SW-30	5/19/2026 9:31:23 AM	28.75	1208	34.4336892	-118.6519593	Valve Adjustment:Valve 100% Open
SW-30	5/18/2026 9:09:16 AM	28.63	1220	34.4336838	-118.6519710	
SW-30	5/15/2026 8:48:17 AM	28.71	1225	34.4336832	-118.6519693	
SW-30	5/14/2026 8:48:35 AM	28.75	1214	34.4336768	-118.6519695	Valve Adjustment:High O2,Valve 100% Open
SW-30	5/13/2026 8:34:30 AM	28.82	1212	34.4336890	-118.6519803	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
SW-30	5/12/2026 9:39:11 AM	28.67	1214	34.4336703	-118.6519803	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
SW-30	5/11/2026 8:48:10 AM	28.71	1211	34.4336732	-118.6519857	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
SW-30	5/8/2026 10:07:17 AM	28.72	1197	34.4336805	-118.6519480	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
SW-30	5/7/2026 9:27:26 AM	28.75	1209	34.4336878	-118.6519507	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
SW-30	5/6/2026 9:14:39 AM	28.8	1212	34.4336675	-118.6519720	Valve Adjustment:Valve 100% Open,Surging Liquid in Header
SW-30	5/5/2026 9:02:34 AM	28.67	1228	34.4336890	-118.6519735	Valve Adjustment:Valve 100% Open,Surging Liquid in Header
SW-30	5/4/2026 8:36:47 AM	28.67	1208	34.4336903	-118.6519523	Valve Adjustment:Audible Flow
SW-30	5/1/2026 8:52:33 AM	28.69	1202	34.4336797	-118.6519770	
SW-32	5/22/2026 6:47:07 AM	28.56	1214	34.4335298	-118.6520503	
SW-32	5/21/2026 7:10:28 AM	28.63	1217	34.4335582	-118.6520647	
SW-32	5/20/2026 7:45:31 AM	28.67	1212	34.4335388	-118.6520643	Valve Comment:no system vacuum
SW-32	5/19/2026 9:36:21 AM	28.77	1212	34.4335622	-118.6520468	

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
SW-32	5/18/2026 9:14:33 AM	28.67	1213	34.4335360	-118.6520607	
SW-32	5/15/2026 8:38:38 AM	28.71	1223	34.4335537	-118.6520568	
SW-32	5/14/2026 8:53:16 AM	28.75	1197	34.4335608	-118.6520255	Valve Adjustment:High O2,Valve 100% Open
SW-32	5/13/2026 8:29:37 AM	28.82	1210	34.4335567	-118.6520807	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
SW-32	5/12/2026 9:35:51 AM	28.67	1207	34.4335182	-118.6520840	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
SW-32	5/11/2026 8:43:32 AM	28.71	1215	34.4335192	-118.6520655	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
SW-32	5/8/2026 10:02:48 AM	28.74	1204	34.4335547	-118.6520470	
SW-32	5/7/2026 9:20:49 AM	28.75	1211	34.4335408	-118.6520157	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
SW-32	5/6/2026 9:10:33 AM	28.78	1212	34.4335333	-118.6520437	Valve Adjustment:Valve 100% Open,Surging Liquid in Header
SW-32	5/5/2026 8:56:30 AM	28.67	1242	34.4335462	-118.6520752	Valve Adjustment:Valve 100% Open,Surging Liquid in Header
SW-32	5/4/2026 8:41:26 AM	28.7	1210	34.4335462	-118.6520488	Valve Adjustment:Audible Flow
SW-32	5/1/2026 8:45:18 AM	28.7	1213	34.4335513	-118.6520683	
SW-64	5/22/2026 6:40:52 AM	28.56	1213	34.4336812	-118.6519742	
SW-64	5/21/2026 6:58:46 AM	28.63	1212	34.4336817	-118.6519637	
SW-64	5/20/2026 8:05:22 AM	28.68	1211	34.4336778	-118.6519713	Valve Comment:no system vacuum
SW-64	5/19/2026 9:28:23 AM	28.75	1215	34.4336788	-118.6519550	Valve Adjustment:Valve 100% Open
SW-64	5/18/2026 9:06:40 AM	28.64	1217	34.4336830	-118.6519823	
SW-64	5/15/2026 8:53:43 AM	28.72	1221	34.4336715	-118.6519645	
SW-64	5/15/2026 8:43:20 AM	28.71	1211	34.4336890	-118.6519610	
SW-64	5/14/2026 8:44:43 AM	28.75	1215	34.4336845	-118.6519588	Valve Adjustment:Valve 100% Open
SW-64	5/13/2026 8:36:34 AM	28.82	1224	34.4336830	-118.6519827	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
SW-64	5/12/2026 9:41:18 AM	28.67	1222	34.4336523	-118.6520035	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
SW-64	5/11/2026 8:51:06 AM	28.71	1209	34.4336463	-118.6519725	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
SW-64	5/8/2026 10:09:00 AM	28.73	1200	34.4336888	-118.6519588	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
SW-64	5/7/2026 9:29:18 AM	28.75	1211	34.4336797	-118.6519615	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
SW-64	5/6/2026 9:16:27 AM	28.78	1212	34.4336663	-118.6519708	Valve Adjustment:Valve 100% Open,Surging Liquid in Header
SW-64	5/5/2026 9:04:48 AM	28.67	1217	34.4336845	-118.6519618	Valve Adjustment:Valve 100% Open,Surging Liquid in Header

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
SW-64	5/4/2026 8:34:50 AM	28.7	1205	34.4337058	-118.6519478	
SW-64	5/1/2026 8:47:28 AM	28.7	1208	34.4336820	-118.6519668	
SW-65	5/11/2026 9:04:20 AM	28.72	1230	34.4348140	-118.6412388	
SW-66	5/15/2026 9:29:15 AM	28.7	1224	34.4380090	-118.6456853	NSPS/EG CAI,No Flow Measurement,High O2
SW-66	5/15/2026 9:27:52 AM	28.7	1224	34.4379907	-118.6456665	NSPS/EG CAI,No Flow Measurement,High O2
SW-68	5/22/2026 6:45:28 AM	28.56	1208	34.4335205	-118.6520510	
SW-68	5/21/2026 7:08:10 AM	28.63	1220	34.4335510	-118.6520482	
SW-68	5/20/2026 7:47:12 AM	28.67	1219	34.4335522	-118.6520465	Valve Comment:no system vacuum
SW-68	5/19/2026 9:34:10 AM	28.76	1204	34.4335455	-118.6520410	
SW-68	5/18/2026 9:11:53 AM	28.67	1214	34.4335280	-118.6520707	
SW-68	5/15/2026 8:34:05 AM	28.71	1222	34.4335485	-118.6520492	
SW-68	5/14/2026 8:50:57 AM	28.75	1219	34.4335452	-118.6520222	Valve Adjustment:Valve 100% Open
SW-68	5/13/2026 8:31:50 AM	28.82	1214	34.4335455	-118.6520567	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
SW-68	5/12/2026 9:37:18 AM	28.67	1206	34.4335397	-118.6520948	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
SW-68	5/11/2026 8:45:53 AM	28.71	1207	34.4335247	-118.6520480	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
SW-68	5/8/2026 10:04:26 AM	28.72	1199	34.4335387	-118.6520443	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
SW-68	5/7/2026 9:24:55 AM	28.75	1209	34.4335365	-118.6520248	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
SW-68	5/6/2026 9:12:20 AM	28.8	1210	34.4335297	-118.6520338	Valve Adjustment:Valve 100% Open,Surging Liquid in Header
SW-68	5/5/2026 8:59:48 AM	28.67	1264	34.4335412	-118.6520715	Valve Adjustment:Valve 100% Open,Surging Liquid in Header
SW-68	5/4/2026 8:39:10 AM	28.7	1217	34.4335490	-118.6520633	Valve Adjustment:Audible Flow
SW-68	5/1/2026 8:43:53 AM	28.67	1199	34.4335320	-118.6520537	
SW-7	5/1/2026 7:54:58 AM	28.63	1260	34.4352020	-118.6517087	Valve Adjustment:Valve 100% Closed
SW-70	5/4/2026 9:33:46 AM	28.59	1305	34.4372625	-118.6473485	
SW-71	5/6/2026 8:31:08 AM	28.89	1148	34.4264685	-118.6431520	NSPS/EG CAI,High O2
SW-71	5/6/2026 8:23:03 AM	28.89	1161	34.4260092	-118.6437895	NSPS/EG CAI,High O2
SW-72	5/6/2026 9:25:28 AM	28.82	1207	34.4296255	-118.6402233	
SW-80	5/12/2026 1:23:15 PM	28.72	1200	34.4383478	-118.6433552	
SW-9	5/4/2026 9:35:40 AM	28.59	1301	34.4372647	-118.6473453	
TC-1961C	5/4/2026 11:11:27 AM	28.63	1293	34.4321622	-118.6454215	Valve Adjustment:Decreased Flow/Vacuum
TC-1961E	5/4/2026 10:42:18 AM	28.65	1279	34.4328602	-118.6444918	Valve Adjustment:Audible Flow;Well Condition:Good
TC-2174	5/26/2026 9:02:15 AM	28.47	1361	34.4367612	-118.6476127	Valve Adjustment:High Temp
TC-2174	5/18/2026 9:25:30 AM	28.52	1358	34.4367364	-118.6476178	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Valve 100% Open,Reduce Sys. Vac. - Flare Down

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
TC-2174	5/18/2026 9:25:00 AM					AtmAA
TC-2174	5/18/2026 9:24:46 AM	28.53	1359	34.4367335	-118.6476142	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down
TC-2174	5/12/2026 9:30:00 AM					AtmAA
TC-2174	5/12/2026 9:24:37 AM	28.55	1375	34.4367281	-118.6476308	Valve Adjustment:High Temp
TC-2174	5/5/2026 8:40:00 AM					AtmAA
TC-2174	5/5/2026 8:40:00 AM					AtmAA; [User entered 15.9%]
TC-2174	5/5/2026 8:34:39 AM	28.55	1331	34.4367353	-118.6476258	Valve Adjustment:High Temp
VL-02	5/28/2026 3:26:30 PM	28.67	1199	34.4311807	-118.6442960	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
WTD-01	5/21/2026 5:51:51 AM	28.52	1245	34.4350053	-118.6514630	Valve Adjustment:NSPS/EG CAI,High Temp,High O2
WTD-01	5/21/2026 5:51:17 AM	28.52	1247	34.4350058	-118.6514597	Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,High O2
WTD-01	5/1/2026 7:48:21 AM	28.62	1262	34.4350075	-118.6514362	Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,High O2,Surging Liquid in Header
WTD-01	5/1/2026 7:47:42 AM	28.62	1255	34.4350090	-118.6514338	Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Surging Liquid in Header
WTD-02	5/21/2026 5:58:44 AM	28.56	1256	34.4346255	-118.6513182	Valve Adjustment:NSPS/EG CAI,High Temp,High O2
WTD-02	5/21/2026 5:58:19 AM	28.56	1238	34.4346337	-118.6512968	Valve Comment:Enhanced Monitoring;Valve Adjustment:NSPS/EG CAI,High Temp,High O2
WTD-02	5/13/2026 1:51:34 PM	28.77	1318	34.4345837	-118.6513707	Valve Adjustment:No Flow Measurement,High Temp
WTD-02	5/13/2026 1:50:30 PM	28.77	1320	34.4345898	-118.6513641	Valve Adjustment:No Flow Measurement,High Temp
WTD-02	5/6/2026 1:50:52 PM	28.7	1248	34.4346817	-118.6513428	Valve Adjustment:High Temp,High O2,Valve 100% Open
WTD-02	5/6/2026 1:50:00 PM					AtmAA
WTD-02	5/6/2026 1:50:00 PM					AtmAA; [User entered 7.68%]
WTD-02	5/6/2026 1:49:41 PM	28.7	1247	34.4346819	-118.6513428	Valve Adjustment:High Temp,High O2
WTD-03	5/21/2026 6:07:17 AM	28.56	1239	34.4344147	-118.6514263	Valve Adjustment:NSPS/EG CAI,High O2
WTD-03	5/21/2026 6:06:19 AM	28.56	1243	34.4344167	-118.6514338	Valve Adjustment:NSPS/EG CAI,High O2
WTD-03	5/1/2026 8:09:37 AM	28.63	1245	34.4344027	-118.6514297	Valve Adjustment:NSPS/EG CAI,High O2
WTD-03	5/1/2026 8:08:56 AM	28.63	1245	34.4343962	-118.6514357	Valve Adjustment:NSPS/EG CAI,High O2,Surging Liquid in Header
WTD-04	5/21/2026 6:19:17 AM	28.59	1223	34.4340143	-118.6516873	Valve Adjustment:NSPS/EG CAI,High O2
WTD-04	5/21/2026 6:16:55 AM	28.59	1217	34.4340173	-118.6516852	Valve Adjustment:NSPS/EG CAI,High O2
WTD-04	5/1/2026 8:15:02 AM	28.67	1215	34.4340045	-118.6516995	Valve Adjustment:NSPS/EG CAI,High O2
WTD-04	5/1/2026 8:14:32 AM	28.66	1215	34.4340052	-118.6517005	Valve Adjustment:NSPS/EG CAI,High O2
WTD-05	5/21/2026 6:13:19 AM	28.59	1222	34.4339415	-118.6517192	Valve Adjustment:NSPS/EG CAI,High O2
WTD-05	5/21/2026 6:12:45 AM	28.59	1233	34.4339420	-118.6517235	Valve Adjustment:NSPS/EG CAI,High O2
WTD-05	5/1/2026 8:12:57 AM	28.66	1199	34.4339320	-118.6517167	Valve Adjustment:NSPS/EG CAI,High O2
WTD-05	5/1/2026 8:12:16 AM	28.63	1216	34.4339352	-118.6517073	Valve Adjustment:NSPS/EG CAI,High O2
WTD-06	5/21/2026 6:21:19 AM	28.6	1214	34.4335052	-118.6519012	Valve Adjustment:NSPS/EG CAI,High O2
WTD-06	5/21/2026 6:20:59 AM	28.6	1215	34.4334972	-118.6518953	Valve Adjustment:NSPS/EG CAI,High O2

All LFG Extraction Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	Baro Press [”Hg]	Elev [ft]	Latitude	Longitude	Comments
WTD-06	5/1/2026 8:20:07 AM	28.67	1196	34.4334278	-118.6518478	Valve Adjustment:NSPS/EG CAI,High O2
WTD-06	5/1/2026 8:17:56 AM	28.67	1202	34.4335033	-118.6518977	Valve Adjustment:NSPS/EG CAI,High O2
WTD-07	5/21/2026 6:25:15 AM	28.59	1215	34.4334962	-118.6519032	Valve Adjustment:NSPS/EG CAI,High O2
WTD-07	5/21/2026 6:24:46 AM	28.6	1210	34.4334957	-118.6518975	Valve Adjustment:NSPS/EG CAI,High O2
WTD-07	5/1/2026 8:22:32 AM	28.67	1207	34.4334967	-118.6518982	Valve Adjustment:NSPS/EG CAI,High O2
WTD-07	5/1/2026 8:21:58 AM	28.67	1207	34.4334967	-118.6518982	Valve Adjustment:NSPS/EG CAI,High O2
WTD-10	5/21/2026 7:17:44 AM	28.63	1203	34.4324603	-118.6518485	Valve Adjustment:NSPS/EG CAI,High O2
WTD-10	5/21/2026 7:17:13 AM	28.63	1211	34.4324672	-118.6518500	Valve Adjustment:NSPS/EG CAI,High O2
WTD-10	5/4/2026 8:01:28 AM	28.69	1224	34.4324627	-118.6518968	Valve Adjustment:NSPS/EG CAI,High O2
WTD-10	5/4/2026 8:00:56 AM	28.7	1210	34.4324545	-118.6518852	Valve Adjustment:NSPS/EG CAI,High O2

Table 2. Monthly LEA Selected Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°R]	Adj Temp [°R]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Sys Pressure ["H2O]	Comments
CV-108-52	5/1/2026 10:29:07 AM	47.7	51.3	0.0	1.0			98.6	99.7	-6.51	-6.42	-7.71	Valve Adjustment:Barely Open
CV-108-52	5/6/2026 8:30:00 AM					100	6600						Air Tech Lab
CV-108-52	5/19/2026 1:02:47 PM	50.4	48.9	0.0	0.7			101.2	101.6	-2.70	-2.78	-2.90	Valve Adjustment:Barely Open,Surging Liquid in Header
CV-113	5/4/2026 7:50:00 AM						24000						Air Tech Lab; [User entered 2.4%]
CV-113	5/15/2026 9:28:02 AM	9.6	85.1	0.0	5.3			65.9	66.6	-0.24	-0.23	-3.12	
CV-113	5/26/2026 2:01:29 PM	9.9	88.1	0.0	2.0			72.8	72.9	-0.39	-0.35	-3.32	Valve Adjustment:Barely Open
CV-114	5/4/2026 8:05:00 AM						2800						Air Tech Lab; [User entered 0.28%]
CV-114	5/5/2026 8:32:18 AM	2.2	80.1	0.0	17.7			174.3	173.1	-2.04	-2.13	-5.67	Valve Adjustment:No Flow Measurement,High Temp
CV-114	5/5/2026 8:35:00 AM						161800						AtmAA; [User entered 16.18%]
CV-114	5/5/2026 8:35:00 AM					3350							AtmAA
CV-114	5/12/2026 9:22:16 AM	18.6	81.4	0.0	0.0			173.1	174.3	-1.52	-1.56	-5.10	Valve Adjustment:High Temp
CV-114	5/12/2026 9:25:00 AM					1750							AtmAA
CV-114	5/18/2026 9:17:57 AM	14.0	75.7	0.0	10.3			160.9	163.8	1.57	1.59	-1.83	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum,Valve 100% Open,Reduce Sys. Vac. - Flare Down
CV-114	5/18/2026 9:20:00 AM					4380							AtmAA
CV-114	5/18/2026 9:20:17 AM	14.4	78.4	0.0	7.2			164.5	164.4	1.25	1.34	-1.86	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down
CV-114	5/26/2026 8:58:28 AM	1.0	78.6	0.0	20.4			170.5	170.7	-0.17	-0.65	0.23	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-1532A	5/11/2026 8:15:00 AM						61000						Air Tech Lab; [User entered 6.1%]
CV-1532A	5/11/2026 8:15:00 AM					580							Air Tech Lab
CV-1532A	5/13/2026 1:07:32 PM	11.9	58.0	6.5	23.6			81.9	81.9	-3.42	-3.87	-5.11	Comments:,,,,,,,
CV-1532A	5/13/2026 1:09:52 PM	8.2	38.6	11.4	41.8			81.8	81.7	-4.01	-5.13	-5.14	Comments:,,,,,,,
CV-1532A	5/28/2026 8:54:46 AM	6.7	68.0	4.2	21.1			66.9	66.6	-6.50	-6.24	-5.83	Valve Adjustment:Barely Open;Well Comment:System surging
CV-1535	5/1/2026 10:31:55 AM	45.2	51.2	0.0	3.6			120.4	120.4	-0.90	-0.82	-8.20	Valve Adjustment:Audible Flow;Well Condition:Good
CV-1535	5/11/2026 8:25:00 AM						9800						Air Tech Lab; [User entered 0.98%]
CV-1535	5/11/2026 8:25:00 AM					100							Air Tech Lab
CV-1535	5/19/2026 12:55:31 PM	44.5	49.2	0.0	6.3			119.7	119.5	-0.23	-0.22	-3.25	Valve Adjustment:Barely Open
CV-1902A	5/6/2026 9:05:00 AM						161050						AtmAA; [User entered 16.105%]
CV-1902A	5/6/2026 9:05:00 AM					1130							AtmAA
CV-1902A	5/6/2026 9:06:28 AM	10.5	78.0	0.0	11.5			160.9	159.6	-6.78	-6.73	-6.80	Valve Adjustment:No Flow Measurement,High Temp
CV-1902A	5/11/2026 7:55:00 AM						190000						Air Tech Lab; [User entered 19%]
CV-1902A	5/11/2026 7:55:00 AM					930							Air Tech Lab
CV-1902A	5/11/2026 1:48:31 PM	9.5	80.8	0.0	9.7			149.5	152.7	-3.48	-3.32	9.42	Valve Adjustment:No Flow Measurement,High Temp
CV-1902A	5/14/2026 1:48:17 PM	2.1	79.7	0.0	18.2			167.2	168.6	-5.46	-5.64	-5.50	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum
CV-1902A	5/20/2026 8:10:11 AM	8.0	77.7	0.0	14.3			156.7	157.4	-5.28	-5.26	-5.00	Valve Adjustment:No Flow Measurement,High Temp
CV-1902A	5/28/2026 8:49:43 AM	1.8	79.3	0.0	18.9			174.2	172.3	-7.63	-7.66	-7.45	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2001	5/1/2026 10:12:38 AM	10.4	78.3	2.1	9.2			85.8	86.2	-6.24	-5.48	-6.26	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2001	5/6/2026 7:50:00 AM						82000						Air Tech Lab; [User entered 8.2%]
CV-2001	5/6/2026 7:50:00 AM					780							Air Tech Lab
CV-2001	5/12/2026 8:45:06 AM	12.0	76.2	1.0	10.8			76.1	76.2	-2.86	-3.81	-4.37	Comments:No Adjustment Made,,,,,,,
CV-2001	5/20/2026 9:55:23 AM	11.8	79.2	0.0	9.0			103.2	103.3	-4.03	-4.05	-4.19	Valve Adjustment:Barely Open

Table 2. Monthly LEA Selected Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Sys Pressure ["H2O]	Comments
CV-2002	5/6/2026 1:02:03 PM	35.3	64.7	0.0	0.0			181.7	181.8	-1.14	-1.31	-4.81	Valve Adjustment:High Temp,Surging Liquid in Well (Watered In)
CV-2002	5/6/2026 1:05:00 PM						137200						AtmAA; [User entered 13.72%]
CV-2002	5/6/2026 1:05:00 PM					3900							AtmAA
CV-2002	5/11/2026 8:10:00 AM						83000						Air Tech Lab; [User entered 8.3%]
CV-2002	5/11/2026 8:10:00 AM					860							Air Tech Lab
CV-2002	5/13/2026 10:09:19 AM	9.0	64.5	2.4	24.1			181.6	181.8	-0.82	-1.05	0.23	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	5/20/2026 9:41:05 AM	42.1	55.6	2.3	0.0			177.9	178.0	-3.15	-2.83	-4.07	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-2002	5/20/2026 9:42:31 AM	43.3	54.7	2.0	0.0			178.6	178.6	-2.21	-2.02	-3.82	Valve Adjustment:High Temp
CV-2002	5/28/2026 10:12:21 AM	9.3	74.6	0.0	16.1			183.5	183.6	0.35	-0.67	-2.10	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum,Plugged/Pinched Suspected;Well Comment:Pinched in the vacuum line
CV-2002	5/28/2026 10:15:53 AM	9.6	74.7	0.0	15.7			183.5	182.2	-0.75	-0.81	-0.97	Valve Adjustment:NSPS/EG CAC,High Temp
CV-2007	5/4/2026 8:10:00 AM						59000						Air Tech Lab; [User entered 5.9%]
CV-2007	5/8/2026 9:48:29 AM	20.5	75.0	0.0	4.5			93.2	93.8	-0.01	-0.03	-3.18	Comments:Reduced System Vacuum,,,,,,,
CV-2007	5/20/2026 2:00:34 PM	19.9	75.6	0.0	4.5			111.1	112.8	-0.10	-0.11	-7.42	Valve Adjustment:Barely Open
CV-2301	5/7/2026 7:55:00 AM						150000						Air Tech Lab; [User entered 15%]
CV-2301	5/7/2026 7:55:00 AM					2200							Air Tech Lab
CV-2301	5/14/2026 10:52:08 AM	30.7	61.8	0.0	7.5			182.0	182.0	-7.30	-7.24	-7.47	Valve Comment:Valve too high to adjust;Valve Adjustment:NSPS/EG CAI,High Temp;Well Comment:No Pump
CV-2301	5/14/2026 10:53:50 AM	31.1	62.4	0.0	6.5			182.0	182.0	-7.32	-7.34	-7.59	
CV-2301	5/14/2026 11:20:00 AM					1170							AtmAA
CV-2301	5/19/2026 10:15:00 AM					990							AtmAA
CV-2301	5/19/2026 10:15:36 AM	48.3	51.4	0.3	0.0			165.0	165.0	-7.06	-5.74	-6.74	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2301	5/19/2026 10:16:23 AM	47.8	52.2	0.0	0.0			164.0		-5.72		-6.88	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	5/27/2026 10:36:57 AM	21.7	65.2	0.1	13.0			160.0	158.0	-4.82	-1.81	-6.24	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2301	5/27/2026 10:38:04 AM	13.5	69.3	0.0	17.2			158.0	158.0	-2.47	-2.44	-6.22	Valve Adjustment:No Flow Measurement,High Temp
CV-2302	5/4/2026 9:06:38 AM	42.4	51.8	0.1	5.7			121.6	121.6	-9.44	-9.45	-9.66	Valve Adjustment:Valve 100% Open;Well Comment:valve stuck open
CV-2302	5/7/2026 8:05:00 AM						53000						Air Tech Lab; [User entered 5.3%]
CV-2302	5/7/2026 8:05:00 AM					320							Air Tech Lab
CV-2302	5/22/2026 3:57:06 PM	42.2	50.6	0.7	6.5			120.2	121.0	-5.04	-5.07	-5.32	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2303	5/5/2026 2:21:44 PM	14.0	80.9	0.0	5.1			189.5	187.7	-3.85	-3.77	0.27	Valve Adjustment:No Flow Measurement,High Temp
CV-2303	5/5/2026 2:25:00 PM						165800						AtmAA; [User entered 16.58%]
CV-2303	5/5/2026 2:25:00 PM					2170							AtmAA
CV-2303	5/12/2026 8:30:00 AM						190000						Air Tech Lab; [User entered 19%]
CV-2303	5/12/2026 8:30:00 AM					2000							Air Tech Lab
CV-2303	5/13/2026 2:13:55 PM	2.0	75.5	0.0	22.5			188.9	190.0	-4.70	-4.13	-4.68	Valve Adjustment:No Flow Measurement,High Temp
CV-2303	5/19/2026 8:36:23 AM	14.0	79.4	0.0	6.6			187.2	187.5	-4.52	-4.52	-4.26	Valve Adjustment:No Flow Measurement,High Temp
CV-2303	5/19/2026 8:40:00 AM					2480							AtmAA
CV-2303	5/27/2026 9:02:45 AM	1.3	77.6	0.0	21.1			181.2	179.8	-2.09	-2.13	0.01	Valve Adjustment:No Flow Measurement,High Temp
CV-2305	5/4/2026 8:50:00 AM	16.1	73.3	0.0	10.6			149.9	149.9	-1.66	-1.01	-1.61	Valve Adjustment:High Temp
CV-2305	5/12/2026 8:10:00 AM						82000						Air Tech Lab; [User entered 8.2%]
CV-2305	5/12/2026 8:10:00 AM					1700							Air Tech Lab

Table 2. Monthly LEA Selected Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Well Temp [°F]	Adj Well Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Sys Pressure ["H2O]	Comments
CV-2305	5/14/2026 10:09:35 AM	31.0	69.0	0.0	0.0			150.0	150.3	-1.47	-1.47	-1.89	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2305	5/14/2026 10:11:00 AM					2380							AtmAA
CV-2305	5/19/2026 1:19:18 PM	38.8	61.2	0.0	0.0			148.9	149.2	-0.17	-0.60	-0.74	Valve Adjustment:High Temp,Valve 100% Open,Surging Liquid in Header
CV-2305	5/19/2026 1:20:00 PM					2420							AtmAA
CV-2305	5/27/2026 2:23:44 PM	16.2	77.8	0.0	6.0			149.1	149.3	2.27	1.95	2.18	Valve Adjustment:High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Header
CV-2305	5/27/2026 2:24:19 PM	17.7	79.8	0.0	2.5			149.7	149.4	2.23	2.20	2.14	Valve Adjustment:High Temp,Positive Static Press.,Surging Liquid in Header
CV-2312	5/4/2026 10:15:00 AM						120300						AtmAA; [User entered 12.03%]
CV-2312	5/4/2026 10:15:00 AM					3840							AtmAA
CV-2312	5/4/2026 10:27:12 AM	1.5	62.9	3.1	32.5			168.1	168.1	23.02	25.84	-9.17	Valve Comment:Active plr;Valve Adjustment:No Flow Measurement
CV-2312	5/4/2026 10:29:04 AM	1.8	78.3	0.0	19.9			167.9	168.0	27.20	23.82	-8.85	Valve Comment:Active PLR;Valve Adjustment:No Flow Measurement,High Temp
CV-2312	5/13/2026 8:30:00 AM						90000						Air Tech Lab; [User entered 9.0%]
CV-2312	5/13/2026 8:30:00 AM					1800							Air Tech Lab
CV-2312	5/13/2026 9:06:06 AM	7.7	81.8	0.2	10.3			168.2	168.2	-6.54	-4.12	-8.03	Valve Comment:ACTIVE PLR;Valve Adjustment:No Flow Measurement,High Temp;Well Comment:Installed sample ports on now hard pipe well
CV-2312	5/13/2026 11:08:10 AM	2.5	78.9	0.4	18.2			169.2	169.3	-16.73	-16.28	-7.70	Valve Adjustment:NSPS/EG CAI,Audible Flow,No Flow Measurement,High Temp
CV-2312	5/19/2026 10:35:00 AM					3070							AtmAA
CV-2312	5/19/2026 10:35:25 AM	16.8	78.0	0.0	5.2			168.5	168.5	-2.64	-1.13	-5.08	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In)
CV-2312	5/27/2026 11:01:39 AM	3.5	80.0	0.1	16.4			167.9	167.7	-3.07	-5.30	-3.98	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Well (Watered In)
CV-2314	5/4/2026 9:40:00 AM						110000						AtmAA; [User entered 11%]
CV-2314	5/4/2026 9:40:00 AM					4010							AtmAA
CV-2314	5/4/2026 9:40:25 AM	7.3	77.6	0.0	15.1			177.9	178.1	-2.93	-2.18	-13.31	Valve Adjustment:High Temp
CV-2314	5/11/2026 10:32:15 AM	8.2	88.6	0.0	3.2			180.2	180.2	-2.16	-1.11	-13.13	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header
CV-2314	5/12/2026 8:05:00 AM						140000						Air Tech Lab; [User entered 14%]
CV-2314	5/12/2026 8:05:00 AM					3400							Air Tech Lab
CV-2314	5/14/2026 1:49:32 PM	0.9	90.5	0.1	8.5			177.6	178.0	-8.65	-2.73	-11.53	Comments:NSPS/EG CAI,High Temp,,,,,,
CV-2314	5/14/2026 1:50:56 PM	0.7	90.4	0.0	8.9			178.0	178.0	-2.53	-2.89	-11.70	Comments:,,,,,,,
CV-2314	5/19/2026 1:53:23 PM	23.9	76.1	0.0	0.0			179.3	180.1	-3.30	-3.03	0.00	Valve Adjustment:No Flow Measurement,High Temp
CV-2314	5/19/2026 2:00:00 PM					3840							AtmAA
CV-2314	5/27/2026 1:45:46 PM	1.3	84.1	0.0	14.6			179.8	179.5	-0.26	-3.78	-7.67	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-2314	5/27/2026 1:46:16 PM	1.4	85.2	0.0	13.4			179.7	179.8	-3.66	-3.61	-7.85	Valve Adjustment:High Temp
CV-2315	5/6/2026 3:25:58 PM	3.1	92.1	0.0	4.8			183.6	183.9	-0.26	-1.85	-5.72	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-2315	5/6/2026 3:27:40 PM	4.6	80.6	0.6	14.2			183.9	183.9	-2.69	-2.61	-4.69	Valve Comment:LORENTZ PUMP DISCONECTED;Valve Adjustment:No Flow Measurement,High Temp
CV-2315	5/6/2026 3:30:00 PM						83300						AtmAA; [User entered 8.33%]
CV-2315	5/6/2026 3:30:00 PM					2530							AtmAA
CV-2315	5/7/2026 8:30:00 AM						140000						Air Tech Lab; [User entered 14%]
CV-2315	5/7/2026 8:30:00 AM					3900							Air Tech Lab

Table 2. Monthly LEA Selected Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Sys Pressure ["H2O]	Comments
CV-2315	5/11/2026 8:41:37 AM	2.8	85.7	0.0	11.5			158.8	156.4	0.34	0.79	1.38	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open
CV-2315	5/13/2026 1:42:47 PM	5.1	79.0	0.1	15.8			177.4	177.7	-2.57	-3.27	-3.13	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header
CV-2315	5/13/2026 1:43:34 PM	5.2	78.4	0.0	16.4			177.6	178.3	-2.68	-2.67	-3.16	
CV-2315	5/19/2026 1:31:37 PM	22.0	75.5	0.0	2.5			184.8	184.8	-1.16	-1.16	0.00	Valve Comment:Lorentz pump disconnected;Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2315	5/19/2026 1:35:00 PM					4320							AtmAA
CV-2315	5/26/2026 10:35:23 AM	10.0	79.9	0.1	10.0			182.5	182.5	-5.71	-5.70	0.34	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-2328	5/4/2026 1:05:00 PM						53600						AtmAA; [User entered 5.36%]
CV-2328	5/4/2026 1:05:00 PM					661							AtmAA
CV-2328	5/4/2026 1:06:42 PM	5.8	82.6	0.0	11.6			171.5	172.4	8.45	-2.28	-11.61	Valve Adjustment:NSPS/EG CAI,Audible Flow,Increased Flow/Vacuum
CV-2328	5/4/2026 1:07:16 PM	5.4	87.3	0.0	7.3			172.5	172.4	-2.16	-2.13	-10.37	Valve Adjustment:NSPS/EG CAC,Audible Flow,High Temp
CV-2328	5/7/2026 8:15:00 AM						110000						Air Tech Lab; [User entered 11%]
CV-2328	5/7/2026 8:15:00 AM					980							Air Tech Lab
CV-2328	5/11/2026 1:26:04 PM	34.7	65.3	0.0	0.0			144.6	146.7	-0.54	-0.53	-1.24	Valve Adjustment:High Temp,Reduce Sys. Vac. - Flare Down
CV-2328	5/20/2026 2:05:13 PM	13.2	74.3	0.0	12.5			167.2	167.4	-0.64	-1.43	-7.41	Valve Adjustment:High Temp,Increased Flow/Vacuum
CV-2328	5/20/2026 2:06:30 PM	13.2	72.4	0.0	14.4			167.3	167.3	-1.36	-1.29	-6.96	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2328	5/28/2026 1:37:05 PM	13.1	76.8	0.0	10.1			164.9	164.9	-3.56	-3.67	-8.49	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header
CV-2333	5/5/2026 8:26:49 AM	1.3	85.7	0.0	13.0			165.9	165.9	-6.44	-6.41	-5.79	Valve Adjustment:Audible Flow,High Temp
CV-2333	5/5/2026 8:30:00 AM						160100						AtmAA; [User entered 16.01%]
CV-2333	5/5/2026 8:30:00 AM					4590							AtmAA
CV-2333	5/6/2026 9:44:40 AM	0.6	82.8	0.0	16.6			191.2	191.2	-3.78	-3.83	-2.94	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp
CV-2333	5/6/2026 9:45:24 AM	0.6	82.4	0.0	17.0			191.3	191.3	-3.95	-3.93	-3.32	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2333	5/12/2026 9:28:21 AM	13.6	81.1	0.0	5.3			177.0	178.1	-5.29	-4.99	-4.80	Valve Adjustment:No Flow Measurement,High Temp
CV-2333	5/12/2026 9:35:00 AM					2400							AtmAA
CV-2333	5/13/2026 7:40:00 AM						160000						Air Tech Lab; [User entered 16%]
CV-2333	5/13/2026 7:40:00 AM					3600							Air Tech Lab
CV-2333	5/18/2026 9:12:06 AM	8.1	75.1	0.0	16.8			157.9	158.1	-1.10	-0.47	-1.03	Valve Adjustment:No Flow Measurement,High Temp
CV-2333	5/18/2026 9:15:00 AM					4360							AtmAA
CV-2333	5/26/2026 8:54:11 AM	0.7	76.3	0.0	23.0			163.1	170.3	-2.38	-2.72	-2.18	Valve Adjustment:No Flow Measurement,High Temp
CV-2333	5/29/2026 9:43:07 AM	0.9	77.1	0.0	22.0			188.6	188.5	-3.29	-3.45	-3.28	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2334	5/13/2026 7:45:00 AM						11000						Air Tech Lab; [User entered 1.1%]
CV-2334	5/13/2026 7:45:00 AM					660							Air Tech Lab
CV-2334	5/26/2026 2:23:32 PM	7.2	92.8	0.0	0.0			127.6	127.2	-1.36	-1.68	-1.14	Valve Adjustment:Barely Open
CV-2337	5/6/2026 9:25:00 AM						122300						AtmAA; [User entered 12.23%]
CV-2337	5/6/2026 9:25:00 AM					5500							AtmAA
CV-2337	5/6/2026 9:26:13 AM	18.7	81.3	0.0	0.0			149.3	149.9	-2.47	-2.48	-3.11	Valve Adjustment:High Temp,Valve 100% Open
CV-2337	5/11/2026 8:05:00 AM						130000						Air Tech Lab; [User entered 13%]
CV-2337	5/11/2026 8:05:00 AM					3500							Air Tech Lab
CV-2337	5/11/2026 2:00:37 PM	33.1	66.9	0.0	0.0			149.0	149.4	-0.74	-0.82	6.97	Valve Adjustment:No Flow Measurement,High Temp,Reduce Sys. Vac. - Flare Down

Table 2. Monthly LEA Selected Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°R]	Adj Temp [°R]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Sys Pressure ["H2O]	Comments
CV-2337	5/20/2026 8:23:36 AM	18.5	80.9	0.0	0.6			150.2	150.2	-3.45	-3.45	0.25	Valve Adjustment:High Temp
CV-2341	5/11/2026 7:50:00 AM						94000						Air Tech Lab; [User entered 9.4%]
CV-2341	5/11/2026 7:50:00 AM					850							Air Tech Lab
CV-2341	5/14/2026 1:47:09 PM	8.8	69.3	1.1	20.8			92.2	92.1	-0.94	-0.93	-5.13	Valve Adjustment:Audible Flow
CV-2341	5/29/2026 10:30:39 AM	9.1	67.8	1.3	21.8			86.6	86.4	-1.16	-1.13	-6.04	Comments:,,,,,,,
CV-2344	5/6/2026 9:50:00 AM						139400						AtmAA; [User entered 13.94%]
CV-2344	5/6/2026 9:50:00 AM					4020							AtmAA
CV-2344	5/6/2026 9:52:20 AM	10.9	84.8	0.5	3.8			157.7	157.4	-8.39	-8.35	0.30	Valve Adjustment:No Flow Measurement,High Temp
CV-2344	5/11/2026 7:35:00 AM						160000						Air Tech Lab; [User entered 16%]
CV-2344	5/11/2026 7:35:00 AM					2900							Air Tech Lab
CV-2344	5/13/2026 9:30:38 AM	6.7	80.2	0.6	12.5			147.1	147.2	-8.12	-5.43	-7.90	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2344	5/13/2026 9:31:33 AM	7.3	81.0	0.5	11.2			146.2	146.1	-5.39	-5.33	-7.71	Valve Adjustment:No Flow Measurement,High Temp
CV-2344	5/20/2026 8:51:25 AM	12.2	77.4	0.6	9.8			141.7	141.9	-6.82	-6.73	-7.55	Valve Adjustment:NSPS/EG CAC,No Flow Measurement
CV-2345	5/1/2026 10:19:42 AM	14.6	78.8	0.1	6.5			137.8	138.2	-0.71	-0.68	0.50	Valve Adjustment:NSPS/EG CAI,High Temp;Well Repairs:Sample Port
CV-2345	5/1/2026 10:20:11 AM	14.2	79.3	0.1	6.4			138.1	138.4	-0.71	-0.71	0.36	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2345	5/11/2026 7:30:00 AM						28000						Air Tech Lab; [User entered 2.8%]
CV-2345	5/11/2026 7:30:00 AM					580							Air Tech Lab
CV-2345	5/19/2026 2:15:18 PM	12.4	83.4	0.0	4.2			143.3	143.5	0.40	-0.05	-4.66	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-2345	5/19/2026 2:17:28 PM	14.6	77.6	0.0	7.8			142.7	142.7	-0.14	-0.12	-4.50	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2346	5/4/2026 1:27:19 PM	3.8	76.4	0.0	19.9			179.5	179.2	-2.10	-2.04	-5.67	Valve Adjustment:NSPS/EG CAC,High Temp;Well Condition:Lorentz Pump Installed
CV-2346	5/4/2026 1:29:13 PM	3.5	77.6	0.0	19.0			178.9	178.7	-2.59	-2.58	-5.77	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2346	5/6/2026 8:25:00 AM						130000						Air Tech Lab; [User entered 13%]
CV-2346	5/6/2026 8:25:00 AM					2200							Air Tech Lab
CV-2346	5/6/2026 9:45:00 AM						118500						AtmAA; [User entered 11.85%]
CV-2346	5/6/2026 9:45:00 AM					3400							AtmAA
CV-2346	5/6/2026 9:47:10 AM	17.2	82.8	0.0	0.0			182.1	182.2	-3.78	-3.77	-6.82	Valve Adjustment:No Flow Measurement,High Temp
CV-2346	5/13/2026 9:20:50 AM	10.9	84.3	0.0	4.8			182.1	182.1	-1.84	-1.95	-7.41	Valve Adjustment:No Flow Measurement,High Temp
CV-2346	5/20/2026 8:47:59 AM	17.4	80.5	0.0	2.1			183.1	184.4	-5.63	-5.72	-7.17	Valve Adjustment:No Flow Measurement,High Temp
CV-2346	5/28/2026 9:28:07 AM	1.3	78.6	0.9	19.2			187.1	186.9	-8.63	-8.69	-9.37	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2347	5/1/2026 10:09:08 AM	10.7	68.3	0.1	20.9			116.7	116.7	-2.15	-2.07	-6.86	Valve Adjustment:Decreased Flow/Vacuum
CV-2347	5/6/2026 8:20:00 AM						56000						Air Tech Lab; [User entered 5.6%]
CV-2347	5/6/2026 8:20:00 AM					1100							Air Tech Lab
CV-2347	5/20/2026 8:26:42 AM	15.0	64.8	0.0	20.2			121.6	124.3	-2.67	-2.69	-7.58	Valve Comment:well needs lowering;Valve Adjustment:Audible Flow
CV-2348	5/6/2026 8:15:00 AM						27000						Air Tech Lab; [User entered 2.7%]
CV-2348	5/6/2026 8:15:00 AM					460							Air Tech Lab
CV-2348	5/13/2026 12:35:31 PM	19.8	56.6	0.3	23.3			128.7	128.8	-3.81	-3.82	-5.97	Comments:,,,,,,,
CV-2348	5/20/2026 8:15:56 AM	20.4	54.1	0.0	25.5			107.8	108.3	-7.53	-7.47	0.03	Valve Comment:Well needs lowering;Valve Adjustment:Audible Flow,Surging Liquid in Header
CV-2349	5/5/2026 8:25:00 AM						150000						Air Tech Lab; [User entered 15%]
CV-2349	5/5/2026 8:25:00 AM					2600							Air Tech Lab
CV-2349	5/7/2026 11:15:00 AM						117000						AtmAA; [User entered 11.7%]

Table 2. Monthly LEA Selected Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Well Temp [°F]	Adj Well Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Sys Pressure ["H2O]	Comments
CV-2349	5/7/2026 11:15:00 AM					3350							AtmAA
CV-2349	5/7/2026 11:15:19 AM	5.4	87.4	0.0	7.2			148.3	147.8	0.27	0.59	0.33	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-2349	5/7/2026 11:16:23 AM	5.3	87.9	0.0	6.8			147.6	147.7	0.29	0.40	0.33	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down
CV-2349	5/13/2026 10:48:12 AM	4.1	77.3	0.0	18.6			152.3	150.2	-0.05	-0.13	0.13	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-2349	5/20/2026 10:27:38 AM	14.1	75.3	0.0	10.6			162.7	163.1	-2.00	-2.00	-0.29	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-2349	5/28/2026 10:20:04 AM	2.3	79.8	0.0	17.9			172.2	172.5	-1.12	-0.52	-1.79	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2350	5/11/2026 7:40:00 AM						170000						Air Tech Lab; [User entered 17%]
CV-2350	5/11/2026 7:40:00 AM					3700							Air Tech Lab
CV-2350	5/13/2026 12:56:01 PM	4.7	77.8	0.0	17.5			121.4	116.6	8.91	-3.00	-3.98	Comments:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,,,
CV-2350	5/13/2026 12:57:10 PM	4.5	85.3	0.0	10.2			116.3	116.4	-0.49	-1.29	-3.38	Comments:,,,,,,,
CV-2350	5/20/2026 10:03:44 AM	4.0	79.6	0.0	16.4			110.9	112.1	-4.09	-4.05	-4.09	Valve Adjustment:Decreased Flow/Vacuum
CV-2351	5/1/2026 9:05:14 AM	0.0	1.8	21.2	77.0			83.8	77.5	-6.60	-6.39	-6.56	Valve Adjustment:Valve 100% Closed,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:Valve stuck open
CV-2351	5/5/2026 7:50:00 AM						1600						Air Tech Lab; [User entered 0.16%]
CV-2351	5/5/2026 7:50:00 AM					0							Air Tech Lab
CV-2351	5/28/2026 9:24:00 AM	2.8	0.1	21.2	75.9			62.3	65.4	-6.82	-6.66	-6.76	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-2351	5/28/2026 9:25:03 AM	2.8	0.1	21.1	76.0			68.1	77.5	-6.12	-6.08	-5.97	Valve Adjustment:NSPS/EG CAI,High O2
CV-2352	5/1/2026 9:13:24 AM	0.0	0.5	21.4	78.1			115.6	116.7	-0.02	-5.72	-6.40	Valve Adjustment:Increased Flow/Vacuum,Barely Open;Well Comment:Possible damaged valve
CV-2352	5/5/2026 8:00:00 AM						190000						Air Tech Lab; [User entered 19%]
CV-2352	5/5/2026 8:00:00 AM					1100							Air Tech Lab
CV-2352	5/28/2026 9:12:47 AM	2.6	25.4	15.5	56.5			99.0	97.8	-5.81	-2.75	-6.36	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-2352	5/28/2026 9:16:38 AM	5.7	29.9	13.0	51.4			108.7	108.9	-0.77	-0.76	-6.25	Valve Adjustment:NSPS/EG CAI,High O2
CV-2353-PLR	5/12/2026 7:35:00 AM						210000						Air Tech Lab; [User entered 21%]
CV-2353-PLR	5/12/2026 7:35:00 AM					760							Air Tech Lab
CV-2353-PLR	5/14/2026 8:40:00 AM					924							AtmAA
CV-2353-PLR	5/15/2026 8:27:25 AM	2.6	77.8	0.0	19.6			147.9	149.2	-7.01	-6.99	-6.87	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-2353-PLR	5/15/2026 8:29:12 AM	2.7	78.1	0.0	19.2			147.6	147.9	-6.86	-6.79	-7.01	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-2353-PLR	5/20/2026 9:13:10 AM	25.8	66.6	1.1	6.5			129.5	131.4	-5.82	-5.04	-5.65	Valve Adjustment:No Flow Measurement,Decreased Flow/Vacuum
CV-2353-PLR	5/20/2026 9:13:57 AM	26.1	68.8	0.5	4.6			131.8	131.5	-5.36	-5.36	-5.45	Valve Adjustment:NSPS/EG CAC,No Flow Measurement
CV-2354	5/5/2026 8:20:00 AM						170000						Air Tech Lab; [User entered 17%]
CV-2354	5/5/2026 8:20:00 AM					2500							Air Tech Lab
CV-2354	5/6/2026 10:50:00 AM						148000						AtmAA; [User entered 14.8%]
CV-2354	5/6/2026 10:50:00 AM					3190							AtmAA
CV-2354	5/6/2026 10:50:20 AM	24.8	75.2	0.0	0.0			174.0	175.3	-3.33	-3.39	0.34	Valve Adjustment:No Flow Measurement,High Temp
CV-2354	5/13/2026 11:01:08 AM	4.5	77.9	1.4	16.2			166.8	166.8	-0.98	-0.98	-2.75	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-2354	5/13/2026 11:03:49 AM	4.8	81.5	0.4	13.3			166.6	167.4	-1.06	-1.11	-2.62	Valve Comment:LORENTZ pump started after last read so cleared some 02;Valve Adjustment:No Flow Measurement,High Temp

Table 2. Monthly LEA Selected Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Well Temp [°R]	Adj Well Temp [°R]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Sys Pressure ["H2O]	Comments
CV-2354	5/20/2026 10:40:36 AM	35.6	64.4	0.0	0.0			179.4	178.6	1.82	1.87	0.29	Valve Comment:Header watered in;Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Header;Well Condition:Lorentz Pump Installed;Well Repairs:Surging
CV-2354	5/20/2026 10:42:07 AM	35.4	64.6	0.0	0.0			179.6	180.2	1.88	1.91	-0.10	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header;Well Condition:Lorentz Pump Installed;Well Repairs:Surging
CV-2354	5/28/2026 10:36:46 AM	4.2	78.4	0.0	17.4			183.8	183.9	-0.52	-0.52	-2.81	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24002	5/1/2026 2:39:31 PM	44.4	53.9	0.0	1.7			92.4	93.2	-0.06	-0.01	0.28	Well Comment:no system port
CV-24002	5/19/2026 9:51:18 AM	47.3	51.9	0.0	0.8			87.8	88.6	0.11	-0.04	-5.90	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open
CV-24002	5/19/2026 9:53:36 AM	45.8	53.6	0.0	0.6			89.2	89.1	-0.13	-0.15	-5.87	Valve Adjustment:NSPS/EG CAC,Barely Open;Well Comment:Sample port installed
CV-24003	5/1/2026 2:37:02 PM	39.9	57.4	0.0	2.7			101.6	101.6	-0.76	-0.63	-6.86	
CV-24003	5/19/2026 9:12:06 AM	45.8	52.7	0.0	1.5			107.1	101.3	-0.41	-0.43	-5.97	Valve Adjustment:Barely Open;Well Repairs:Valve
CV-24007	5/12/2026 8:40:00 AM						170000						Air Tech Lab; [User entered 17%]
CV-24007	5/12/2026 8:40:00 AM					1800							Air Tech Lab
CV-24007	5/15/2026 9:09:54 AM	5.6	77.6	0.0	16.8			132.2	132.4	0.04	-0.02	-0.36	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum,Surging Liquid in Header
CV-24007	5/15/2026 9:10:41 AM	4.8	66.5	0.0	28.7			138.6	138.7	-0.12	-0.14	-0.21	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header
CV-24007	5/19/2026 10:45:21 AM	19.9	70.8	0.0	9.3			150.9	150.7	-0.31	-0.18	-3.87	Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Increased Flow/Vacuum
CV-24007	5/19/2026 10:46:37 AM	18.2	71.0	0.0	10.8			150.9	150.7	-0.16	-0.16	-3.26	Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Barely Open
CV-24007	5/26/2026 1:55:46 PM	28.1	71.9	0.0	0.0			150.2	150.9	-0.79	-1.05	1.01	Valve Adjustment:High Temp,Increased Flow/Vacuum
CV-24007	5/26/2026 1:56:22 PM	33.7	66.3	0.0	0.0			150.7	150.8	-1.44	-1.44	0.88	Valve Adjustment:High Temp
CV-24007	5/29/2026 9:33:56 AM	27.8	66.3	0.0	5.9			148.0	148.2	-1.32	-1.34	-6.72	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum
CV-24017	5/5/2026 1:19:34 PM	10.8	78.7	0.6	9.9			159.0	159.6	-3.14	-3.12	0.00	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
CV-24017	5/5/2026 1:20:00 PM						155500						AtmAA; [User entered 15.55%]
CV-24017	5/5/2026 1:20:00 PM					2760							AtmAA
CV-24017	5/12/2026 8:35:00 AM						190000						Air Tech Lab; [User entered 19%]
CV-24017	5/12/2026 8:35:00 AM					2100							Air Tech Lab
CV-24017	5/12/2026 2:10:00 PM					1230							AtmAA
CV-24017	5/12/2026 2:25:14 PM	18.0	72.7	0.6	8.7			181.0	180.5	-4.81	-1.21	-0.05	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24017	5/12/2026 2:47:32 PM	25.5	74.5	0.0	0.0			172.2	174.6	-2.11	-2.05	0.00	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header
CV-24017	5/18/2026 2:35:18 PM	25.5	74.5	0.0	0.0			171.6	170.6	-2.24	-2.10	0.34	Valve Adjustment:No Flow Measurement,High Temp;Well Repairs:Surging
CV-24017	5/18/2026 2:40:00 PM					2520							AtmAA
CV-24017	5/26/2026 2:07:20 PM	17.6	76.3	0.8	5.3			172.4	172.6	-7.16	-5.22	0.21	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24017	5/26/2026 2:08:15 PM	19.6	76.0	0.6	3.8			170.4	171.5	-3.75	-3.69	0.21	Valve Adjustment:No Flow Measurement,High Temp
CV-24049	5/4/2026 2:36:19 PM	2.0	88.0	0.0	10.0			188.6	189.2	-4.01	-3.94	-10.48	Valve Adjustment:No Flow Measurement,High Temp
CV-24049	5/4/2026 2:40:00 PM						25900						AtmAA; [User entered 2.59%]
CV-24049	5/4/2026 2:40:00 PM					705							AtmAA
CV-24049	5/11/2026 8:47:07 AM	2.8	83.6	0.0	13.6			186.2	186.6	3.00	-0.64	-0.87	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum,Valve 100% Open

Table 2. Monthly LEA Selected Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Sys Pressure ["H2O]	Comments
CV-24049	5/11/2026 8:49:25 AM	2.9	84.8	0.0	12.3			186.0	185.0	-1.84	-1.69	-0.36	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Valve 100% Open
CV-24049	5/13/2026 8:10:00 AM						160000						Air Tech Lab; [User entered 16%]
CV-24049	5/13/2026 8:10:00 AM					2800							Air Tech Lab
CV-24049	5/18/2026 10:30:56 AM	18.5	77.4	0.0	4.1			179.6	180.2	-4.87	-4.90	-4.97	Valve Adjustment:No Flow Measurement,High Temp
CV-24049	5/18/2026 10:35:00 AM					3260							AtmAA
CV-24049	5/26/2026 10:43:34 AM	4.4	78.6	0.0	17.0			179.9	179.2	-11.36	-5.97	-11.24	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24049	5/26/2026 10:45:00 AM	3.5	81.4	0.0	15.1			179.0	179.6	-5.95	-5.74	-11.49	Valve Adjustment:No Flow Measurement,High Temp
CV-24053	5/7/2026 8:40:00 AM						5300						Air Tech Lab; [User entered 0.53%]
CV-24053	5/7/2026 8:40:00 AM					88							Air Tech Lab
CV-24053	5/8/2026 8:18:44 AM	39.3	43.1	2.5	15.1			75.4	75.5	-3.03	-3.04	-3.36	Comments:No Flow Measurement,,,,,,,
CV-24053	5/20/2026 2:23:25 PM	50.4	48.4	0.0	1.2			100.2	100.5	-4.32	-4.99	-4.39	Valve Adjustment:Valve 100% Open
CV-24055	5/12/2026 1:47:04 PM	9.0	65.6	2.2	23.2			136.9	137.9	-0.52	-0.62	-11.04	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24055	5/12/2026 1:49:20 PM	9.1	62.3	1.6	27.0			137.8	137.3	-0.58	-0.57	-9.05	Valve Adjustment:Surging Liquid in Header
CV-24055	5/13/2026 8:15:00 AM						51000						Air Tech Lab; [User entered 5.1%]
CV-24055	5/13/2026 8:15:00 AM					930							Air Tech Lab
CV-24055	5/26/2026 9:27:16 AM	14.3	66.2	1.1	18.4			137.4	137.2	-0.44	-0.34	-8.47	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down
CV-24055	5/26/2026 9:28:17 AM	14.4	66.0	1.1	18.5			137.4	136.8	-0.35	-0.35	-7.59	Valve Adjustment:NSPS/EG CAI,High Temp,Reduce Sys. Vac. - Flare Down
CV-24062	5/4/2026 1:15:00 PM						56100						AtmAA; [User entered 5.61%]
CV-24062	5/4/2026 1:15:00 PM					1080							AtmAA
CV-24062	5/4/2026 1:16:07 PM	28.3	66.3	0.0	5.4			145.5	148.7	-6.22	-6.38	-10.23	Valve Adjustment:High Temp
CV-24062	5/7/2026 8:17:00 AM						80000						Air Tech Lab; [User entered 8.0%]
CV-24062	5/7/2026 8:17:00 AM					890							Air Tech Lab
CV-24062	5/8/2026 1:05:26 PM	28.8	63.9	0.0	7.3			133.9	134.2	-2.10	-2.02	-6.46	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
CV-24062	5/22/2026 11:08:48 AM	28.1	59.3	1.3	11.3			140.5	140.3	-3.49	-3.46	-8.26	Comments:NSPS/EG CAI,High Temp,,,,,,
CV-24062	5/22/2026 11:10:33 AM	29.1	63.7	0.4	6.8			144.9	143.7	-1.88	-1.78	-8.22	Comments:High Temp,NSPS/EG CAI,,,,,,
CV-24063	5/4/2026 1:33:24 PM	3.7	84.4	0.6	11.3			182.4	181.7	-7.10	-3.43	-11.01	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-24063	5/4/2026 1:34:44 PM	3.7	86.5	0.0	9.8			183.9	182.5	-3.44	-3.34	-11.05	Valve Adjustment:No Flow Measurement,High Temp
CV-24063	5/4/2026 1:35:00 PM						71600						AtmAA; [User entered 7.16%]
CV-24063	5/4/2026 1:35:00 PM					2470							AtmAA
CV-24063	5/12/2026 8:20:00 AM						120000						Air Tech Lab; [User entered 12%]
CV-24063	5/12/2026 8:20:00 AM					2400							Air Tech Lab
CV-24063	5/14/2026 11:00:00 AM					3230							AtmAA
CV-24063	5/14/2026 11:01:37 AM	10.7	83.6	0.0	5.7			174.9	173.4	0.65	-3.17	0.34	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24063	5/14/2026 11:02:15 AM	11.4	83.8	0.0	4.8			172.8	171.9	-3.36	-3.31	-8.44	Valve Adjustment:No Flow Measurement,High Temp
CV-24063	5/20/2026 2:20:53 PM	5.1	80.1	0.0	14.8			171.8	173.7	-2.92	-2.92	0.00	Valve Adjustment:No Flow Measurement,High Temp
CV-24063	5/28/2026 1:49:33 PM	6.8	84.2	0.0	9.0			184.1	183.7	-2.47	-2.43	-7.15	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24064	5/4/2026 9:09:33 AM	2.9	78.6	0.0	18.5			191.9	191.8	-11.35	-10.47	-12.85	Valve Adjustment:High Temp,Valve 100% Open
CV-24064	5/4/2026 9:10:00 AM						111000						AtmAA; [User entered 11.1%]
CV-24064	5/4/2026 9:10:00 AM					2680							AtmAA

Table 2. Monthly LEA Selected Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Well Temp [°F]	Adj Well Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Sys Pressure ["H2O]	Comments
CV-24064	5/11/2026 10:07:41 AM	9.0	87.1	0.6	3.3			192.5	192.5	-10.46	-10.56	-13.49	Valve Adjustment:No Flow Measurement,High Temp
CV-24064	5/12/2026 8:15:00 AM						130000						Air Tech Lab; [User entered 13%]
CV-24064	5/19/2026 1:36:22 PM	14.8	76.2	0.0	9.0			192.0	192.5	-5.48	-4.27	-9.16	Valve Comment:Active PLR observed;Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In)
CV-24064	5/19/2026 1:40:00 PM					2470							AtmAA
CV-24064	5/27/2026 1:55:09 PM	3.2	80.3	0.0	16.5			191.7	192.0	-6.74	-6.78	-6.68	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Well (Watered In)
CV-24064	5/28/2026 2:15:41 PM	1.9	79.7	0.0	18.4			165.5	165.7	-7.85	-7.85	-8.16	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24065-TP1	5/7/2026 8:35:00 AM						9800						Air Tech Lab; [User entered 0.98%]
CV-24065-TP1	5/7/2026 8:35:00 AM					530							Air Tech Lab
CV-24065-TP1	5/11/2026 1:07:25 PM	21.6	73.3	0.0	5.1			100.0	100.2	-0.10	-0.03	0.48	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
CV-24065-TP1	5/12/2026 8:15:00 AM					2000							Air Tech Lab
CV-24065-TP1	5/22/2026 10:27:26 AM	15.0	83.3	0.4	1.3			82.9	83.8	-0.33	-0.32	-10.19	Valve Adjustment:Barely Open
CV-24066	5/1/2026 10:40:05 AM	23.9	49.4	0.0	26.7			116.8	117.5	-1.19	-1.18	-8.39	Valve Adjustment:Audible Flow;Well Condition:Good
CV-24066	5/11/2026 7:45:00 AM						32000						Air Tech Lab; [User entered 3.2%]
CV-24066	5/11/2026 7:45:00 AM					390							Air Tech Lab
CV-24066	5/19/2026 12:41:10 PM	25.0	45.2	0.0	29.8			109.2	110.5	-0.94	-0.93	-6.12	Valve Adjustment:Decreased Flow/Vacuum
CV-24069	5/4/2026 8:56:06 AM	40.8	48.8	0.0	10.4			93.2	93.4	-1.42	-1.43	0.01	Valve Comment:No system port;Valve Adjustment:Barely Open
CV-24069	5/13/2026 8:20:00 AM						40000						Air Tech Lab; [User entered 4.0%]
CV-24069	5/13/2026 8:20:00 AM					470							Air Tech Lab
CV-24069	5/28/2026 9:30:09 AM	35.8	42.0	0.3	21.9			96.1	96.2	-2.80	-2.08	-9.63	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum;Well Comment:Needs silicone for lorentz fittings;Well Condition:Lorentz Pump Installed;Well Repairs:Sample Port
CV-24069	5/28/2026 9:35:46 AM	31.9	43.5	0.4	24.2			94.5	93.7	-1.98	-1.68	-8.97	Valve Adjustment:Decreased Flow/Vacuum
CV-24069	5/28/2026 9:36:45 AM	31.0	44.0	0.3	24.7			93.4	93.4	-1.66	-1.65	-9.09	
CV-24070	5/4/2026 9:11:52 AM	23.2	65.8	1.9	9.1			131.6	130.3	-1.65	-1.07	-10.01	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24070	5/4/2026 9:12:35 AM	22.4	63.4	0.0	14.2			130.4	130.3	-1.21	-1.13	-10.00	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24070	5/7/2026 8:20:00 AM						110000						Air Tech Lab; [User entered 11%]
CV-24070	5/7/2026 8:20:00 AM					1300							Air Tech Lab
CV-24070	5/20/2026 2:33:43 PM	10.2	74.7	0.0	15.1			133.9	135.6	0.95	-0.10	-3.46	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum,Decreased Flow/Vacuum
CV-24070	5/20/2026 2:34:29 PM	10.7	77.6	0.0	11.7			136.2	136.1	-0.13	-0.15	-3.49	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24070	5/20/2026 2:35:15 PM	11.4	77.9	0.0	10.7			136.2	136.2	-0.15	-0.10	-3.35	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24071	5/4/2026 9:43:04 AM	43.3	55.1	0.0	1.6			121.6	121.4	-5.57	-5.24	-9.94	Valve Adjustment:Decreased Flow/Vacuum
CV-24071	5/7/2026 8:10:00 AM						24000						Air Tech Lab; [User entered 2.4%]
CV-24071	5/7/2026 8:10:00 AM					190							Air Tech Lab
CV-24071	5/20/2026 1:35:21 PM	42.5	52.0	0.0	5.5			123.3	123.2	-3.74	-3.33	-6.65	Valve Adjustment:Decreased Flow/Vacuum
CV-24075-TP1	5/4/2026 9:20:00 AM						114700						AtmAA; [User entered 11.47%]
CV-24075-TP1	5/4/2026 9:20:00 AM					2260							AtmAA
CV-24075-TP1	5/4/2026 9:20:10 AM	1.0	81.8	0.8	16.4			61.7	60.6	-13.32	-13.51	0.07	Valve Comment:Updated photo on etools;Valve Adjustment:Audible Flow,High Temp
CV-24075-TP1	5/4/2026 9:21:41 AM	1.0	82.0	0.8	16.2			187.2	187.2	-13.08	-13.16	0.04	Valve Adjustment:No Flow Measurement,High Temp

Table 2. Monthly LEA Selected Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Sys Pressure ["H2O]	Comments
CV-24075-TP1	5/11/2026 10:25:13 AM	10.2	84.1	0.8	4.9			109.5	99.5	-11.66	-11.98	0.04	Valve Adjustment:No Flow Measurement,High Temp
CV-24075-TP1	5/29/2026 4:02:17 PM	0.9	72.9	2.6	23.6			186.7	186.7	-14.48	-14.48	-15.16	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24075-TP1	5/29/2026 4:03:35 PM	1.0	76.4	2.8	19.8			186.8	187.0	-13.96	-14.01	-14.15	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24077	5/1/2026 10:01:59 AM	5.0	82.0	0.0	13.0			150.8	151.0	-1.95	-1.20	-5.89	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24077	5/1/2026 10:03:08 AM	4.6	87.3	0.0	8.1			151.0	151.0	-1.23	-1.24	-6.62	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24077	5/7/2026 10:50:00 AM						72200						AtmAA; [User entered 7.22%]
CV-24077	5/7/2026 10:50:00 AM					2820							AtmAA
CV-24077	5/7/2026 10:50:33 AM	7.9	86.4	0.1	5.6			149.0	148.8	-0.95	-0.98	-2.92	Valve Adjustment:No Flow Measurement,High Temp
CV-24077	5/11/2026 1:38:12 PM	18.6	77.2	0.0	4.2			146.5	146.1	-2.00	-2.00	5.79	Valve Adjustment:No Flow Measurement,High Temp
CV-24077	5/20/2026 8:03:01 AM	19.8	53.5	0.0	26.7			142.7	142.4	-4.52	-4.48	-6.99	Valve Adjustment:No Flow Measurement,High Temp
CV-24077	5/28/2026 9:16:41 AM	12.2	59.5	0.0	28.3			143.6	144.5	-4.76	-4.77	-9.14	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24077	5/28/2026 9:18:10 AM	10.1	65.9	0.0	24.0			146.7	147.0	-2.62	-2.61	-9.05	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24079-TP8	5/1/2026 11:22:12 AM	18.3	65.8	0.0	15.9			156.5	154.7	-0.62	-0.25	0.66	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24079-TP8	5/1/2026 11:22:57 AM	18.3	70.1	0.0	11.6			152.4	152.4	-0.16	-0.16	0.68	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open;Well Comment:no system port;Well Repairs:Sample Port
CV-24079-TP8	5/7/2026 10:38:33 AM	2.0	89.4	0.0	8.6			153.6	168.1	0.98	-1.80	0.33	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24079-TP8	5/7/2026 10:40:00 AM						111700						AtmAA; [User entered 11.17%]
CV-24079-TP8	5/7/2026 10:40:00 AM					2450							AtmAA
CV-24079-TP8	5/7/2026 10:41:06 AM	2.3	87.0	0.0	10.7			170.5	172.6	-1.59	-1.63	0.33	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-24079-TP8	5/11/2026 1:15:47 PM	52.0	48.0	0.0	0.0			140.1	141.7	-5.34	-5.34	0.02	Valve Adjustment:No Flow Measurement,High Temp
CV-24079-TP8	5/26/2026 12:12:54 PM	37.0	50.4	0.1	12.5			137.8	137.0	-7.80	-5.70	-0.06	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down;Well Comment:no system port
CV-24079-TP8	5/26/2026 12:13:32 PM	37.3	49.5	0.0	13.2			137.7	135.9	-5.41	-5.41	-0.27	Valve Adjustment:NSPS/EG CAI,High Temp,Reduce Sys. Vac. - Flare Down
CV-24082	5/4/2026 10:11:50 AM	28.2	68.8	0.0	3.0			110.9	111.4	-0.42	-0.44	-8.93	Valve Adjustment:Barely Open
CV-24082	5/20/2026 11:24:26 AM	30.9	69.1	0.0	0.0			124.3	124.4	-0.20	-0.13	-6.11	Valve Adjustment:Barely Open
CV-24083	5/4/2026 9:56:08 AM	40.4	57.1	0.0	2.5			104.4	105.9	0.60	-0.69	-10.39	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24083	5/4/2026 9:58:27 AM	41.5	56.2	0.0	2.3			108.0	108.4	-0.80	-0.81	-10.17	Valve Adjustment:NSPS/EG CAC,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24083	5/20/2026 1:53:17 PM	42.6	55.2	0.0	2.2			126.8	125.0	-0.17	-0.17	-6.95	Valve Adjustment:Barely Open
CV-24084-TP1	5/4/2026 2:05:00 PM						77400						[User entered 7.74%]
CV-24084-TP1	5/4/2026 2:05:00 PM					2420							AtmAA
CV-24084-TP1	5/4/2026 2:08:40 PM	3.7	91.0	0.0	5.3			180.6	180.8	-1.49	-1.39	-8.12	Valve Adjustment:Audible Flow,High Temp
CV-24084-TP1	5/11/2026 1:05:39 PM	11.7	61.3	0.0	27.0			179.6	181.3	-1.83	-1.69	-4.96	Valve Adjustment:No Flow Measurement,High Temp
CV-24084-TP1	5/19/2026 10:24:00 AM	18.9	81.1	0.0	0.0			180.6	180.9	-3.47	-3.40	-6.08	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24084-TP1	5/27/2026 10:49:57 AM	2.9	76.5	0.0	20.6			180.2	180.7	-2.12	-2.36	-5.06	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24088	5/4/2026 1:51:55 PM	38.8	59.1	0.0	2.1			100.0	100.1	-2.03	-1.98	-7.61	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24088	5/28/2026 9:04:04 AM	41.7	53.9	0.0	4.4			99.1	99.2	-1.94	-1.94	-8.79	
CV-24095	5/6/2026 8:05:00 AM						160000						Air Tech Lab; [User entered 16%]

Table 2. Monthly LEA Selected Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Well Temp [°F]	Adj Well Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Sys Pressure ["H2O]	Comments
CV-24095	5/6/2026 8:05:00 AM					2800							Air Tech Lab
CV-24095	5/6/2026 10:45:00 AM						108400						AtmAA; [User entered 10.84%]
CV-24095	5/6/2026 10:45:00 AM					2700							AtmAA
CV-24095	5/6/2026 10:46:15 AM	19.2	80.8	0.0	0.0			176.2	176.2	-1.28	-1.30	0.34	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header
CV-24095	5/13/2026 10:53:04 AM	3.2	82.3	0.0	14.5			177.8	177.9	0.91	1.66	0.65	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Positive Static Press.,Surging Liquid in Header
CV-24095	5/13/2026 10:56:02 AM	2.2	71.8	2.8	23.2			178.3	178.3	0.59	0.95	0.62	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-24095	5/14/2026 1:28:11 PM	3.5	81.5	0.0	15.0			178.8	178.7	1.35	0.75	0.24	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Header
CV-24095	5/20/2026 10:30:33 AM	27.6	72.4	0.0	0.0			178.6	178.7	-2.17	-2.41	-4.22	Valve Adjustment:No Flow Measurement,High Temp
CV-24095	5/28/2026 10:30:18 AM	2.3	83.9	0.3	13.5			179.6	179.3	0.50	0.47	-0.54	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.
CV-24095	5/28/2026 10:32:51 AM	2.9	83.5	0.0	13.6			179.1	179.1	0.32	0.14	0.16	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Surging Liquid in Header
CV-24096	5/12/2026 9:22:51 AM	23.5	34.9	8.4	33.2			74.1	81.8	-2.99	-1.86	-3.62	Comments:NSPS/EG CAI,High O2,,,,,,
CV-24096	5/12/2026 9:25:00 AM	25.3	37.4	7.2	30.1			82.9	81.9	-2.06	-2.02	-3.71	Comments:NSPS/EG CAI,High O2,,,,,,
CV-24096	5/20/2026 10:19:24 AM	37.6	55.4	0.3	6.7			95.9	98.5	-2.34	-1.97	-3.33	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum
CV-24097	5/12/2026 9:13:02 AM	48.0	51.4	0.0	0.6			78.9	87.4	0.02	-0.04	-5.38	Comments:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Opened Valve 1/2 to 1 Turn,,,,
CV-24097	5/12/2026 9:16:39 AM	44.2	50.8	0.4	4.6			81.1	81.2	-0.10	-0.10	-5.64	Comments:NSPS/EG CAC,No Adjustment Made,,,,,,
CV-24097	5/20/2026 10:28:10 AM	42.7	45.7	2.3	9.3			88.4	91.2	-3.87	-1.12	-4.95	Valve Adjustment:Decreased Flow/Vacuum
CV-24097	5/20/2026 10:29:27 AM	46.8	46.8	1.3	5.1			86.7	86.8	-1.19	-1.19	-4.94	Valve Adjustment:Barely Open
CV-24098	5/1/2026 10:01:03 AM	42.9	39.3	3.2	14.6			92.6	93.8	-4.22	-4.01	-4.30	Valve Adjustment:Valve 100% Open,Surging Liquid in Header;Well Comment:valve stuck open
CV-24098	5/3/2026 11:00:24 AM	48.8	41.9	0.8	8.5			69.0	69.7	-7.60	-7.39	-7.81	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header;Well Comment:pump fitting needs silicone to cover hole;Well Condition:Pnumatic Pump Installed
CV-24098	5/3/2026 11:01:16 AM	48.9	43.0	0.4	7.8			70.4	70.5	-6.65	-6.20	-6.53	Valve Adjustment:Surging Liquid in Header;Well Condition:Pnumatic Pump Installed
CV-24098	5/20/2026 10:43:25 AM	42.4	38.2	4.4	15.0			95.4	95.9	-4.18	-4.01	-3.80	Valve Adjustment:Decreased Flow/Vacuum
CV-24099	5/1/2026 10:08:04 AM	9.4	35.2	8.1	47.3			83.2	83.2	-4.81	-4.58	-4.91	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:valve stuck open
CV-24099	5/3/2026 10:27:26 AM	11.8	76.1	0.0	12.1			61.8	61.4	-0.01	-1.06	-7.32	Valve Adjustment:NSPS/EG CAC,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24099	5/3/2026 10:28:19 AM	11.4	75.4	0.0	13.2			61.2	61.4	-0.90	-1.00	-7.63	Valve Adjustment:Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24099	5/3/2026 10:28:51 AM	12.3	75.2	0.0	12.5			61.5	61.5	-1.09	-1.03	-6.43	Well Condition:Lorentz Pump Installed
CV-24099	5/20/2026 10:48:09 AM	24.4	66.0	0.0	9.6			97.5	97.6	-0.54	-0.48	-3.60	
CV-24100	5/1/2026 10:25:18 AM	19.0	80.8	0.1	0.1			143.7	147.6	-0.61	-0.60	-8.60	Valve Adjustment:High Temp,Barely Open
CV-24100	5/7/2026 11:04:29 AM	25.0	75.0	0.0	0.0			144.3	146.0	2.22	-2.88	-3.06	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24100	5/7/2026 11:05:00 AM						8500						AtmAA; [User entered 0.85%]
CV-24100	5/7/2026 11:05:00 AM					228							AtmAA
CV-24100	5/7/2026 11:06:06 AM	25.4	74.4	0.2	0.0			146.0	146.9	-3.18	-3.18	-3.06	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-24100	5/13/2026 8:25:00 AM						8800						Air Tech Lab; [User entered 0.88%]
CV-24100	5/13/2026 8:25:00 AM					83							Air Tech Lab

Table 2. Monthly LEA Selected Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Well Temp [°F]	Adj Well Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Sys Pressure ["H2O]	Comments
CV-24100	5/13/2026 10:41:16 AM	21.9	77.3	0.2	0.6			143.4	141.9	-7.76	-2.95	-7.76	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24100	5/13/2026 10:42:49 AM	21.8	78.0	0.1	0.1			143.5	143.8	-2.64	-2.64	-7.80	Valve Adjustment:No Flow Measurement;Well Condition:Lorentz Pump Installed
CV-24100	5/20/2026 9:36:36 AM	21.3	73.8	0.0	4.9			150.8	150.9	-1.42	-0.31	-7.43	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header
CV-24100	5/20/2026 9:37:52 AM	21.4	75.4	0.0	3.2			151.2	151.5	-0.21	-0.23	-7.51	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header
CV-24100	5/20/2026 10:00:42 AM	46.9	53.1	0.0	0.0			149.8	150.4	0.10	-2.39	-6.84	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-24100	5/20/2026 10:01:19 AM	46.0	54.0	0.0	0.0			150.0	149.5	-2.99	-2.99	-6.69	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-24100	5/28/2026 10:02:06 AM	21.1	74.5	0.0	4.4			147.5	148.5	-0.47	-0.51	-4.78	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24101	5/1/2026 10:20:22 AM	42.6	57.1	0.3	0.0			106.9		-7.56		-7.94	Valve Adjustment:Valve 100% Open
CV-24101	5/6/2026 7:40:00 AM						940						Air Tech Lab; [User entered 0.094%]
CV-24101	5/6/2026 7:40:00 AM					0							Air Tech Lab
CV-24101	5/12/2026 8:51:03 AM	38.8	53.6	1.3	6.3			112.6	112.4	-7.47	-7.36	-7.01	Comments:No Flow Measurement,,,,,,,
CV-24101	5/20/2026 9:41:50 AM	41.4	54.8	0.0	3.8			112.0	115.3	-7.37	-7.22	-7.34	Valve Adjustment:Decreased Flow/Vacuum
CV-24102	5/4/2026 9:42:22 AM	46.9	48.6	0.0	4.5			89.0	89.0	-0.59	-0.59	-8.51	Valve Adjustment:Barely Open
CV-24102	5/19/2026 10:30:38 AM	47.8	50.6	0.0	1.6			103.0	103.0	-0.48	-0.48	-6.89	
CV-24120	5/4/2026 8:00:00 AM						110000						Air Tech Lab; [User entered 11%]
CV-24120	5/11/2026 10:28:50 AM	4.7	71.6	0.4	23.4			98.1	98.1	-1.16	-1.18	-1.37	Valve Adjustment:Reduce Sys. Vac. - Flare Down;Well Comment:Pump is off;Well Condition:Lorentz Pump Installed
CV-24120	5/26/2026 2:15:09 PM	4.8	80.5	0.6	14.1			88.0	89.0	-8.11	-7.69	-7.45	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24121	5/4/2026 7:55:00 AM						2700						Air Tech Lab; [User entered 0.27%]
CV-24121	5/11/2026 10:33:18 AM	2.7	15.3	16.4	65.6			101.3	101.3	-0.80	-0.82	-0.89	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Reduce Sys. Vac. - Flare Down
CV-24121	5/11/2026 10:33:56 AM	2.8	15.0	16.1	66.2			101.4	101.4	-1.05	-0.86	-1.27	Valve Adjustment:High O2,Barely Open
CV-24121	5/26/2026 2:08:29 PM	0.6	5.5	20.0	73.9			75.9	78.2	-8.13	-0.55	-8.06	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24122	5/4/2026 8:20:00 AM						9100						Air Tech Lab; [User entered 0.91%]
CV-24122	5/6/2026 10:31:06 AM	42.7	42.2	3.2	11.9			84.9	85.9	-2.43	-2.92	-0.81	Valve Comment:RES SEM;Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Surging Liquid in Header
CV-24122	5/29/2026 9:33:20 AM	27.0	31.6	7.9	33.5			76.1	76.9	-4.68	-2.41	-5.20	Comments:NSPS/EG CAI,High O2,,,,,,
CV-24122	5/29/2026 9:40:41 AM	35.0	40.3	4.3	20.4			81.1	81.5	-2.22	-2.27	-4.97	Comments:NSPS/EG CAC,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,,,,,
CV-24123	5/14/2026 10:53:53 AM	30.9	69.1	0.0	0.0			116.7	117.1	0.40	0.33	0.34	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Valve 100% Open,Reduce Sys. Vac. - Flare Down
CV-24123	5/14/2026 10:54:34 AM	32.0	67.3	0.0	0.7			117.2	117.3	0.18	0.18	0.29	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Valve 100% Open
CV-24123	5/15/2026 11:24:46 AM	26.4	69.8	0.0	3.8			84.7	112.5	3.24	-0.20	-2.56	Comments:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Reduced System Vacuum,Increased Flow/Vacuum,Opened Valve 1/2 to 1 Turn,,
CV-24123	5/15/2026 11:28:22 AM	31.9	66.2	0.0	1.9			113.9	113.9	-0.16	-0.16	-0.44	Comments:,,,,,,,
CV-24123	5/28/2026 11:46:25 AM	38.4	57.2	0.0	4.4			116.1	116.6	0.65	0.67	0.42	Valve Comment:RES SEM;Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Well (Watered In)
CV-24123	5/28/2026 11:46:50 AM	37.2	57.7	0.0	5.1			116.6	116.7	0.63	0.60	0.47	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Well (Watered In)
CV-24125-TP2(	5/13/2026 7:55:00 AM						1300						Air Tech Lab; [User entered 0.13%]
CV-24125-TP2(	5/13/2026 7:55:00 AM					30							Air Tech Lab
CV-24125-TP2(	5/26/2026 1:56:27 PM	28.5	67.0	1.1	3.4			99.9	99.8	-1.35	-1.41	-3.85	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)

Table 2. Monthly LEA Selected Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Sys Pressure ["H2O]	Comments
CV-24126	5/4/2026 2:40:40 PM	1.9	85.1	0.0	13.0			186.0	187.1	-2.12	-2.63	-2.27	Valve Adjustment:High Temp
CV-24126	5/4/2026 2:50:00 PM						135800						AtmAA; [User entered 13.58%]
CV-24126	5/4/2026 2:50:00 PM					3200							AtmAA
CV-24126	5/12/2026 10:28:41 AM	20.1	79.9	0.0	0.0			188.0	188.4	-2.83	-2.62	-2.72	Valve Adjustment:High Temp
CV-24126	5/12/2026 10:30:00 AM					2330							AtmAA
CV-24126	5/18/2026 10:43:37 AM	21.8	71.7	0.0	6.5			186.3	187.2	1.28	1.80	1.52	Valve Adjustment:High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down
CV-24126	5/18/2026 10:44:28 AM	14.0	77.0	0.0	9.0			186.7	186.3	1.42	1.36	1.78	Valve Adjustment:High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down
CV-24126	5/18/2026 10:50:00 AM					4310							AtmAA
CV-24126	5/22/2026 12:28:40 PM	1.3	75.6	0.0	23.1			188.3	188.5	-0.20	-0.22	-1.11	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24126	5/22/2026 12:29:20 PM	1.6	76.9	0.0	21.5			188.7	188.6	-0.30	-0.38	-1.18	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24126	5/26/2026 10:58:38 AM	4.1	73.0	0.0	22.9			186.7	187.1	-2.02	-1.91	-2.13	Valve Adjustment:High Temp
CV-24127	5/4/2026 8:15:00 AM						160000						Air Tech Lab; [User entered 16%]
CV-24127	5/7/2026 10:20:00 AM						152600						AtmAA; [User entered 15.26%]
CV-24127	5/7/2026 10:20:00 AM					5180							AtmAA
CV-24127	5/7/2026 10:21:43 AM	2.7	82.2	0.0	15.1			141.6	141.1	5.40	2.26	0.32	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum,Valve 100% Open
CV-24127	5/7/2026 10:22:55 AM	2.9	83.5	0.0	13.6			141.8	141.2	2.20	2.31	0.32	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open
CV-24128	5/8/2026 9:33:23 AM	34.4	43.9	1.2	20.5			99.5	99.5	-0.86	-0.77	-3.16	Comments:Reduced System Vacuum,,,,,,,
CV-24128	5/13/2026 7:50:00 AM						11000						Air Tech Lab; [User entered 1.1%]
CV-24128	5/13/2026 7:50:00 AM					210							Air Tech Lab
CV-24128	5/26/2026 2:25:15 PM	33.4	51.7	1.2	13.7			91.8	91.7	-1.98	-1.98	-10.24	Valve Adjustment:Barely Open
CV-24134-TP1	5/7/2026 1:14:04 PM	22.6	74.7	0.0	2.7			150.0	149.5	-0.65	-0.62	-0.30	Valve Adjustment:No Flow Measurement,High Temp
CV-24134-TP1	5/7/2026 1:15:00 PM					1220							AtmAA
CV-24134-TP1	5/11/2026 2:29:03 PM	18.3	65.8	0.0	15.9			146.2	146.4	-4.14	-1.81	-5.22	Comments:NSPS/EG CAI,High Temp,,,,,,
CV-24134-TP1	5/11/2026 2:33:48 PM	16.6	73.9	0.0	9.5			146.9	146.9	-1.74	-1.76	-5.30	Comments:,,,,,,,
CV-24134-TP1	5/12/2026 10:32:12 AM	36.7	63.3	0.0	0.0			150.1	150.8	0.95	-2.25	-4.10	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High O2,Increased Flow/Vacuum
CV-24134-TP1	5/12/2026 10:33:32 AM	38.2	61.8	0.0	0.0			150.6	150.9	-2.75	-2.74	-4.05	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-24134-TP1	5/12/2026 10:35:00 AM					2470							AtmAA
CV-24134-TP1	5/18/2026 10:39:38 AM	33.1	64.1	0.0	2.8			151.5	151.6	-0.11	-0.08	-1.01	Valve Adjustment:No Flow Measurement,High Temp,Reduce Sys. Vac. - Flare Down
CV-24134-TP1	5/18/2026 10:45:00 AM					3300							AtmAA
CV-24134-TP1	5/26/2026 10:55:47 AM	23.2	68.7	0.0	8.1			151.0	151.4	-3.84	-3.90	-5.03	Valve Adjustment:No Flow Measurement,High Temp
CV-24138	5/5/2026 8:15:00 AM						210000						Air Tech Lab; [User entered 21%]
CV-24138	5/5/2026 8:15:00 AM					820							Air Tech Lab
CV-24138	5/6/2026 10:58:19 AM	17.2	74.8	0.0	8.0			158.7	160.2	-3.80	-3.60	0.32	Valve Adjustment:No Flow Measurement,High Temp
CV-24138	5/6/2026 11:00:00 AM						171800						AtmAA; [User entered 17.18%]
CV-24138	5/6/2026 11:00:00 AM					1010							AtmAA
CV-24138	5/13/2026 1:14:42 PM	2.4	68.4	0.0	29.2			131.5	131.6	-0.58	-0.38	-0.52	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header;Well Condition:Pnumatic Pump Installed
CV-24138	5/28/2026 9:02:31 AM	0.3	0.2	21.6	77.9			96.3	95.5	-2.69	-2.09	-2.20	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-24138	5/28/2026 9:03:38 AM	0.3	0.2	21.5	78.0			95.8	96.9	-2.02	-1.80	-1.85	Valve Adjustment:NSPS/EG CAI,High O2,Surging Liquid in Header
CV-24139	5/5/2026 8:10:00 AM						180000						Air Tech Lab; [User entered 18%]

Table 2. Monthly LEA Selected Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Sys Pressure ["H2O]	Comments
CV-24139	5/5/2026 8:10:00 AM					630							Air Tech Lab
CV-24139	5/15/2026 8:12:50 AM	0.1	3.3	20.8	75.8			111.7	136.1	25.00	-0.23	-6.42	Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Positive Static Press.,Increased Flow/Vacuum
CV-24139	5/15/2026 8:22:50 AM	0.7	30.7	13.2	55.4			144.2	139.8	-0.21	-0.20	-6.72	Valve Adjustment:NSPS/EG CAI,High Temp,High O2;Well Comment:sensitive valve;Well Repairs:Valve
CV-24139	5/28/2026 9:08:34 AM	4.1	58.6	4.7	32.6			127.4	125.5	-6.44	-6.10	-6.76	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum
CV-24140	5/5/2026 8:05:00 AM						210000						Air Tech Lab; [User entered 21%]
CV-24140	5/5/2026 8:05:00 AM					1000							Air Tech Lab
CV-24140	5/6/2026 11:04:58 AM	14.4	78.6	0.0	7.0			163.7	164.9	-5.03	-5.03	-5.22	Valve Adjustment:No Flow Measurement,High Temp
CV-24140	5/6/2026 11:05:00 AM						203000						AtmAA; [User entered 20.3%]
CV-24140	5/6/2026 11:05:00 AM					1350							AtmAA
CV-24140	5/13/2026 1:18:30 PM	2.2	69.8	0.0	28.0			156.3	157.7	-2.58	-2.53	-4.54	Valve Adjustment:No Flow Measurement,High Temp
CV-24140	5/20/2026 1:26:41 PM	3.6	73.1	0.3	23.0			146.3	148.5	-3.62	-2.56	-3.60	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-24140	5/20/2026 1:28:20 PM	5.1	71.3	0.2	23.4			148.6	148.4	-2.42	-2.47	-3.40	Valve Adjustment:No Flow Measurement,High Temp
CV-24140	5/28/2026 10:50:34 AM	1.9	75.0	0.0	23.1			168.4	170.8	5.74	-1.38	-4.68	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum
CV-24140	5/28/2026 10:52:29 AM	1.9	72.1	0.4	25.6			171.1	170.8	-1.75	-1.97	-5.22	Valve Adjustment:High Temp
CV-24141	5/1/2026 8:57:18 AM	20.8	33.2	5.1	40.9			79.1	76.3	-0.08	-0.95	-6.86	Valve Adjustment:Increased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
CV-24141	5/5/2026 7:45:00 AM						1200						Air Tech Lab; [User entered 0.12%]
CV-24141	5/5/2026 7:45:00 AM					94							Air Tech Lab
CV-24141	5/28/2026 9:30:26 AM	10.7	6.5	18.4	64.4			65.6	65.7	-6.76	-5.94	-7.11	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum;Well Comment:no pump installed
CV-24141	5/28/2026 9:31:07 AM	10.8	6.8	18.3	64.1			66.1	65.9	-5.95	-5.76	-5.94	Valve Adjustment:NSPS/EG CAI,High O2
CV-24142	5/6/2026 8:10:00 AM						120000						Air Tech Lab; [User entered 12%]
CV-24142	5/6/2026 8:10:00 AM					1500							Air Tech Lab
CV-24142	5/14/2026 8:35:00 AM					2300							AtmAA
CV-24142	5/15/2026 7:59:13 AM	0.0	1.3	21.7	77.0			174.3	174.0	-4.10	-4.10	-4.96	Valve Adjustment:NSPS/EG CAI,High Temp,Valve 100% Open,Surging Liquid in Header
CV-24142	5/15/2026 8:03:40 AM	0.0	0.2	21.9	77.9			174.7	174.7	-3.95	-3.94	-4.77	Valve Adjustment:NSPS/EG CAI,High Temp,Valve 100% Open,Surging Liquid in Header
CV-24142	5/20/2026 1:02:37 PM	3.8	58.4	2.6	35.2			153.3	151.5	-3.36	-2.50	-3.07	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed
CV-24142	5/20/2026 1:14:55 PM	2.6	59.0	3.6	34.8			152.3	151.1	-2.68	-2.87	0.00	Valve Comment:Pneumatic pump not working;Valve Adjustment:No Flow Measurement,High Temp
CV-24142	5/28/2026 10:40:43 AM	2.3	72.4	0.6	24.7			100.2	100.7	-1.92	-1.91	-1.66	Valve Adjustment:NSPS/EG CAI
CV-24142	5/28/2026 10:41:54 AM	2.3	72.2	0.6	24.9			100.6	100.8	-1.89	-1.89	-1.58	
CV-24143	5/1/2026 2:15:01 PM	0.7	23.9	14.4	61.0			95.5	97.6	-4.24	-2.26	-4.36	Comments:NSPS/EG CAI,High O2,,,,,,
CV-24143	5/1/2026 2:16:44 PM	0.7	23.5	14.9	60.9			96.9	96.8	-2.80	-2.85	-4.29	Comments:,,,,,,,
CV-24143	5/5/2026 7:55:00 AM						61000						Air Tech Lab; [User entered 6.1%]
CV-24143	5/5/2026 7:55:00 AM					460							Air Tech Lab
CV-24143	5/28/2026 9:19:15 AM	4.2	23.6	15.2	57.0			73.4	72.9	-7.01	-6.42	-6.80	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-24143	5/28/2026 9:20:03 AM	4.3	24.2	15.2	56.3			72.5	72.4	-6.42	-6.44	-6.31	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open
CV-24144	5/12/2026 9:03:44 AM	58.5	40.0	0.0	1.5			79.1	88.3	-4.85	-4.84	-4.77	Comments:Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,No Flow Measurement,,,,,
CV-24144	5/20/2026 10:35:16 AM	56.8	40.5	0.0	2.7			103.0	100.3	-4.49	-4.52	-4.27	Valve Adjustment:Valve 100% Open

Table 2. Monthly LEA Selected Wells - May 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Well Temp [°F]	Adj Well Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Sys Pressure ["H2O]	Comments
CV-99	5/4/2026 7:45:00 AM						2600						Air Tech Lab; [User entered 0.26%]
CV-99	5/26/2026 1:51:48 PM	26.1	73.9	0.0	0.0			77.4	77.4	-3.43	-2.93	-3.44	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1770N	5/1/2026 2:42:44 PM	35.3	62.8	0.0	1.9			100.2	100.2	-0.68	-0.60	-6.48	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1770N	5/4/2026 8:50:00 AM						12000						Air Tech Lab; [User entered 1.2%]
H-1770N	5/19/2026 9:18:49 AM	36.3	61.0	0.0	2.7			99.2	98.4	-0.44	-0.37	-6.73	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
H-2165W	5/1/2026 10:16:24 AM	10.9	86.4	0.0	2.7			118.0	117.5	-0.09	-0.05	-8.60	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-2165W	5/12/2026 7:45:00 AM						48000						Air Tech Lab; [User entered 4.8%]
H-2165W	5/12/2026 7:45:00 AM					720							Air Tech Lab
H-2165W	5/20/2026 9:46:57 AM	12.9	79.8	0.0	7.3			119.8	120.0	-0.68	-0.55	-7.28	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header
H-2273W	5/12/2026 7:50:00 AM						5900						Air Tech Lab; [User entered 0.59%]
H-2273W	5/12/2026 7:50:00 AM					76							Air Tech Lab
H-2273W	5/13/2026 12:42:00 PM	17.2	42.0	0.1	40.7			125.4	127.0	-0.53	-0.64	-7.48	Comments:Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,,,,,,
H-2273W	5/20/2026 8:21:56 AM	25.2	50.1	0.0	24.7			129.9	129.3	-0.77	-0.67	-8.30	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum

Attachment B


Down Well Temperatures


And

List of Wells for Monitoring


LEA Selected Wells for Down Hole Temperature Monitoring
April 2026


Well Number	Down Well Temp Monitoring Monthly	Last Date Monitored for Downwell Temperatures - 2025	2026 Downwell Temperature Monitoring Date	Comments
CV-100	NA	NA	NA	Abandoned Well
CV-103	NA	3/3/2025	NA	Abandoned Well
CV-108-52	Yes	3/4/2025	3/2/2026	
CV-113	Yes	3/10/2025	3/2/2026	
CV-1532	NA	NA	NA	Abandoned Well
CV-1532A	Yes	3/10/2025	2/6/2026 and 3/25/2026	
CV-1535	Yes	3/4/2025	3/2/2026	
CV-1902A	Yes	3/18/2025	2/6/2026 and 3/2/2026	
CV-2001	Yes	3/4/2025	3/3/2026	
CV-2002	Yes	6/2/2025	3/4/2026	
CV-2007	Yes	3/5/2025	3/4/2026	
CV-2202	NA	NA	NA	Abandoned Well
CV-2301	Yes	3/11/2025	2/6/2026 and 3/5/2026	Pump Offline
CV-2302	Yes	3/11/2025	TBD - Pump Installed	Graph Attached 5-1 to 5-31-2026
CV-2303	Yes	3/11/2025	TBD - Pump Installed	Pump/Sensor Offline in May
CV-2312	Yes	3/5/2025	TBD - Pump Installed	
CV-2315	Yes	3/19/2025	TBD - Pump Installed	Graph Attached 5-1 to 5-31-2026
CV-2341	Yes	3/5/2025	TBD - Pump Installed	
CV-2350	Yes	3/12/2025	TBD - Pump Installed	Pump/Sensor Offline in May
CV-2351	Yes	3/12/2025	3/10/2026	Now a Pnuematic Pump no sensors
CV-2352	Yes	3/12/2025	4/24/2026 and 4/30/2026	Now a Pnuematic Pump no sensors
CV-2353	Yes	5/30/2025	3/10/2026 and 4/30/2026	
CV-24007	Yes	3/6/2025	3/10/2026	
CV-24017	Yes	3/6/2025	TBD - Pump Installed	Graph attached 5-1 to 5-31-2026
CV-24053	Yes	3/6/2025	TBD - Pump Installed	
CV-24065	Yes	3/6/2025	TBD - Pump Installed	Graph Attached 5-1 to 5-31-2026
CV-24095	Yes	3/7/2025	TBD - Pump Installed	Graph Attached 5-1 to 5-31-2026
CV-24101	Yes	3/7/2025	TBD - Pump Installed	
CV-24122	Yes	3/7/2025	3/10/2026	
CV-24127	Yes	3/7/2025	3/10/2027	
CV-24138	Yes	4/1/2025	TBD - Pump Installed	
CV-23139	Yes	8/18/2025	TBD - Pump Installed	
CV-24143	Yes	3/10/2025	TBD - Pump Installed	
TC-2385A	NA	NA	NA	Abandoned Well



CV-2302
18 May 2026 10:25 (UTC -7)
Temp. Sensor [Analog 1]: 164.2 °F
May 2, 2026
May 4, 2026
May 6, 2026
May 8, 2026
May 10, 2026
May 12, 2026
May 14, 2026
May 16, 2026
May 18, 2026
May 20, 2026
May 22, 2026
May 24, 2026
May 26, 2026
May 28, 2026
May 30, 2026


15 May 2026 10:12 (UTC -7)
Lorentz Temp. Sensor [Analog 1]: 150.7 °F
May 2, 2026
May 4, 2026
May 6, 2026
May 8, 2026
May 10, 2026
May 12, 2026
May 14, 2026
May 16, 2026
May 18, 2026
May 20, 2026
May 22, 2026
May 24, 2026
May 26, 2026
May 28, 2026
May 30, 2026
June

CV-2315



13 May 2026 19:18 (UTC -7)
Temperature sensor [Analog 1]: 225.6 °F
CV-24017
May 2, 2026
May 4, 2026
May 6, 2026
May 8, 2026
May 10, 2026
May 12, 2026
May 14, 2026
May 16, 2026
May 18, 2026
May 20, 2026
May 22, 2026
May 24, 2026
May 26, 2026
May 28, 2026
May 30, 2026
June 1


17 May 2026 13:06 (UTC -7)
Lorentz Temp. Sensor [Analog 1]: 150.5 °F
CV-24065
May 2, 2026
May 4, 2026
May 6, 2026
May 8, 2026
May 10, 2026
May 12, 2026
May 14, 2026
May 16, 2026
May 18, 2026
May 20, 2026
May 22, 2026
May 24, 2026
May 26, 2026
May 28, 2026
May 30, 2026
June


12 May 2026 00:45 (UTC -7)
Lorentz Temp. Sensor [Analog 1]: 175.1 °F
CV-2495
May 2, 2026
May 4, 2026
May 6, 2026
May 8, 2026
May 10, 2026
May 12, 2026
May 14, 2026
May 16, 2026
May 18, 2026
May 20, 2026
May 22, 2026
May 24, 2026
May 26, 2026
May 28, 2026
May 30, 2026
June 1

Attachment C

Item 7 – Well Location Map



N

GRAPHIC SCALE

150 75 0 150 300 150

SCALE: 1"=150'

LEGEND

- 1150 — TOPOGRAPHIC CONTOUR
- EXISTING CELL LIMITS (APPROXIMATE)
- CV-XX — EXISTING VERTICAL LFG EXTRACTION WELL
- H-XX — EXISTING HORIZONTAL COLLECTOR
- EXISTING HORIZONTAL COLLECTOR PERFORATED PIPE
- REACTION AREA BOUNDARY (APPROXIMATE) - BASED ON DATA REVIEW
- REACTION AREA BOUNDARY - CONDITION 9A

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLOR. AERIAL PHOTOGRAPHY DATED JUNE 02, 2026.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.
3. THE LOCATION OF ANY EXISTING GCCS COMPONENTS AND OTHER FEATURES ARE APPROXIMATE AND SHOULD BE USED FOR INFORMATION PURPOSES ONLY.

DATE | REVISION | NO.

SHEET TITLE: EXISTING VERTICAL & HORIZONTAL LFG EXTRACTION WELL MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544


PROJ. NO. 01204123.45 | DSN. BY: - | DWN. BY: RR | CHK. BY: - | ACAD FILE: FIELD SERVICES | APP. BY: -

DATE: 06/11/2026

SCALE: AS SHOWN

SHEET: 1

N:\CAD\ASBUILT – MASTERS\CHIQUITA\GCCS\2026 ACAD\2026 CCLF_Existing Well Map For LEA Response_2026-06-11.dwg Jun 15, 2026 5:04pm By: raulramirez



GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLOR. AERIAL PHOTOGRAPHY DATED MAY 06, 2026.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.
3. THE LOCATION OF ANY EXISTING PIPING, VALVES, TIE-IN LOCATIONS AND OTHER FEATURES ARE APPROXIMATE AND SHOULD BE USED FOR INFORMATION PURPOSES ONLY. ACTUAL FIELD CONDITIONS MAY VARY AND SUBJECT TO CHANGE BASED ON TOPOGRAPHIC FEATURES AND OTHER SITE-SPECIFIC FACTORS.
4. EXISTING GCCS AS-BUILT DATED JUNE 3, 2026.

DATE | REVISION | NO.

SHEET TITLE: EXISTING GCCS MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3711 LONG BEACH BLVD., THIRD FLOOR
LONG BEACH, CA 90807
PH. (562) 426-9544

PROJ. NO. - | DWN. BY: SRM | ACAD. FILE: N:\CAD\ASBUILT-MASTERS\CHIQUITA\GCCS\CCLF MASTER EXISTING GCCS MAP_2026-06-03.dwg
DSN. BY: - | CHK. BY: - | APP. BY: -

DATE: 06/03/2026


SCALE: AS SHOWN

1 of 1

N:\CAD\ASBUILT - MASTERS\CHIQUITA\GCCS\CCLF MASTER EXISTING GCCS MAP_2026-06-03.dwg Jun 03, 2026 - 2:01pm By: raulramirez

Attachment D

Milestone 5 Compliance Data



Ranges Mapped

						# Points
	>=	0	and	<	25	53
	>=	25	and	<	48	26
	>=	48	and	<	52	2
	>=	52	and	<	58	1
	>=	58	and	<	101	
		N/A			N/A	

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill


Range Map

Parameter: CH4 (mid range)

Analysis Method: MostRecent

Date Range: 05/01/2026 - 05/31/2026

Map generation date : 06/11/2026



Ranges Mapped

						# Points
	>=	0	and	<	25	5
	>=	25	and	<	45	5
	>=	45	and	<	55	16
	>=	55	and	<	65	7
	>=	65	and	<	101	49
		N/A			N/A	

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill


Range Map

Parameter: CO2 (mid range)

Analysis Method: MostRecent

Date Range: 05/01/2026 - 05/31/2026

Map generation date : 06/11/2026



Ranges Mapped

						# Points
	>=	0	and	<	0.5	
	>=	0.5	and	<	2	
	>=	2	and	<	3.5	
	>=	3.5	and	<	5	
	>=	5	and	<	101	
		N/A			N/A	

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill


Range Map

Parameter: O2 (mid range)

Analysis Method: MostRecent

Date Range: 05/01/2026 - 05/31/2026

Map generation date : 06/11/2026



Ranges Mapped

						# Points
	>=	-50	and	<	131	46
	>=	131	and	<	150	12
	>=	150	and	<	165	4
	>=	165	and	<	180	11
	>=	180	and	<	999	9
		N/A			N/A	

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill


Range Map

Parameter: Adj Temp (high range)

Analysis Method: MostRecent

Date Range: 05/01/2026 - 05/31/2026

Map generation date : 06/11/2026



Ranges Mapped

						# Points
	>=	0	and	<	0.5	56
	>=	0.5	and	<	0.9	16
	>=	0.9	and	<	1.1	5
	>=	1.1	and	<	1.5	2
	>=	1.5	and	<	101	3
		N/A			N/A	

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill


Range Map

Parameter: CH4/CO2 Ratio (high range)

Analysis Method: MostRecent

Date Range: 05/01/2026 - 05/31/2026

Map generation date : 06/11/2026



Ranges Mapped

						# Points
	>=	0	and	<	500	18
	>=	500	and	<	1000	15
	>=	1000	and	<	1500	6
	>=	1500	and	<	2000	3
	>=	2000	and	<	10000	21

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill


Range Map

Parameter: CO LAB (mid range)

Analysis Method: MostRecent

Date Range: 05/01/2026 - 05/31/2026

Map generation date : 06/11/2026



Ranges Mapped

					# Points
	>= 0	and	<	2000	4
	>= 2000	and	<	5000	2
	>= 5000	and	<	10000	6
	>= 10000	and	<	50000	10
	>= 50000	and	<	100000	14
	>= 100000	and	<	150000	16
	>= 150000	and	<	1000000	16

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill


Range Map


Parameter: H2 LAB (mid range)

Analysis Method: MostRecent

Date Range: 05/01/2026 - 05/31/2026

Map generation date : 06/11/2026





Point ID / Name


CHIWCV99 / CV-99

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-99 / CV-99

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-99 / CV-99


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CHWCV103 / CV-103

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name

CV-103 / CV-103

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-103 / CV-103


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools





Point ID / Name


CV108-52 / CV-108-52

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-108-52 / CV-108-52

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-108-52 / CV-108-52

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-1902A / CV-1902A

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-2001 / CV-2001

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-2001 / CV-2001


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CHWCV113 / CV-113

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-113 / CV-113

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-113 / CV-113


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CHWCV114 / CV-114

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-114 / CV-114

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-114 / CV-114


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name

CHCV1423 / CV-1423

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name

CV-1423 / CV-1423

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-1423 / CV-1423


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools





Point ID / Name


CCV1532A / CV-1532A

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-1532A / CV-1532A

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-1532A / CV-1532A


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CHCV1535 / CV-1535

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-1535 / CV-1535

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-1535 / CV-1535


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CCV1902A / CV-1902A

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-1902A / CV-1902A


Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CHCV2001 / CV-2001

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CHCV2002 / CV-2002

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-2002 / CV-2002

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-2002 / CV-2002


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CHCV2007 / CV-2007

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-2007 / CV-2007

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-2007 / CV-2007


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CHCV2301 / CV-2301

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-2301 / CV-2301

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-2301 / CV-2301


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CHCV2302 / CV-2302

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-2302 / CV-2302

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name

CV-2302 / CV-2302

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CHCV2303 / CV-2303

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-2303 / CV-2303

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-2303 / CV-2303

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CHCV2305 / CV-2305

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-2305 / CV-2305

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-2305 / CV-2305

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CHCV2312 / CV-2312

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-2312 / CV-2312

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-2312 / CV-2312


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CHCV2314 / CV-2314

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-2314 / CV-2314

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-2314 / CV-2314


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CHCV2315 / CV-2315

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-2315 / CV-2315

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-2315 / CV-2315


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CHCV2328 / CV-2328

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-2328 / CV-2328

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-2328 / CV-2328


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CHCV2333 / CV-2333

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-2333 / CV-2333

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-2333 / CV-2333


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CHCV2334 / CV-2334

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-2334 / CV-2334

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-2334 / CV-2334


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CHCV2337 / CV-2337

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-2337 / CV-2337

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-2337 / CV-2337


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CHCV2341 / CV-2341

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-2341 / CV-2341

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-2341 / CV-2341


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CHCV2344 / CV-2344

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-2344 / CV-2344

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-2344 / CV-2344


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CHCV2345 / CV-2345

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-2345 / CV-2345

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-2345 / CV-2345


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CHCV2346 / CV-2346

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-2346 / CV-2346

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-2346 / CV-2346


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CHCV2347 / CV-2347

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-2347 / CV-2347

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-2347 / CV-2347


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CHCV2348 / CV-2348

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-2348 / CV-2348

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-2348 / CV-2348

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CHCV2349 / CV-2349

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-2349 / CV-2349

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-2349 / CV-2349


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CHCV2350 / CV-2350

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-2350 / CV-2350

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-2350 / CV-2350


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CHCV2351 / CV-2351

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-2351 / CV-2351

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-2351 / CV-2351


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CHCV2352 / CV-2352

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-2352 / CV-2352

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-2352 / CV-2352


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CHCV2353 / CV-2353-PLR

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-2353 / CV-2353

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools




Point ID / Name


CV-2353 / CV-2353

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26





Point ID / Name


CHCV2354 / CV-2354

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-2354 / CV-2354

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-2354 / CV-2354

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CCV24002 / CV-24002


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools





Point ID / Name


CCV24003 / CV-24003


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools





Point ID / Name


CCV24007 / CV-24007

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24007 / CV-24007

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24007 / CV-24007


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CCV24017 / CV-24017

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24017 / CV-24017

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24017 / CV-24017


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CCV24049 / CV-24049

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24049 / CV-24049

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24049 / CV-24049

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CCV24053 / CV-24053

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24053 / CV-24053

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24053 / CV-24053


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CCV24055 / CV-24055

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24055 / CV-24055

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24055 / CV-24055


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CCV24062 / CV-24062

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24062 / CV-24062

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24062 / CV-24062


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CCV24063 / CV-24063

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24063 / CV-24063

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24063 / CV-24063


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CCV24064 / CV-24064

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24064 / CV-24064

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24064 / CV-24064

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CCV24065 / CV-24065-TP17

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24065 / CV-24065

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24065 / CV-24065


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CCV24066 / CV-24066

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24066 / CV-24066

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24066 / CV-24066

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CCV24069 / CV-24069

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24069 / CV-24069

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24069 / CV-24069


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CCV24070 / CV-24070

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24070 / CV-24070

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24070 / CV-24070

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CCV24071 / CV-24071

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24071 / CV-24071

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24071 / CV-24071


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CCV24075 / CV-24075-TP15

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24075 / CV-24075

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24075 / CV-24075


Parameter / Unit

Hydrogen /%,v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CCV24077 / CV-24077

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name

CV-24079 / CV-24079

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24079 / CV-24079


Parameter / Unit

Hydrogen /%,v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CCV24079 / CV-24079-TP8

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CCV24082 / CV-24082


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools





Point ID / Name


CCV24083 / CV-24083

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name

CV-24083 / CV-24083

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24083 / CV-24083

Parameter / Unit

Hydrogen /%,v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CCV24084 / CV-24084-TP11

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24084-TP11 / CV-24084-TP11

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24084-TP11 / CV-24084-TP11


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CCV24088 / CV-24088


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools





Point ID / Name


CCV24095 / CV-24095

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24095 / CV-24095

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24095 / CV-24095


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CCV24096 / CV-24096

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CCV24097 / CV-24097


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools





Point ID / Name


CCV24098 / CV-24098


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools





Point ID / Name


CCV24099 / CV-24099


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools





Point ID / Name


CCV24100 / CV-24100

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24100 / CV-24100

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24100 / CV-24100


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CCV24101 / CV-24101

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24101 / CV-24101

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24101 / CV-24101


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CCV24102 / CV-24102

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CCV24120 / CV-24120

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24120 / CV-24120

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24120 / CV-24120


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CCV24121 / CV-24121

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24121 / CV-24121

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24121 / CV-24121


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CCV24122 / CV-24122

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24122 / CV-24122

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24122 / CV-24122


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools





Point ID / Name


CCV24123 / CV-24123


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools





Point ID / Name


CCV24125 / CV-24125-TP20

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24125 / CV-24125

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24125 / CV-24125


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CCV24126 / CV-24126

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24126 / CV-24126

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name

CV-24126 / CV-24126

Parameter / Unit

Hydrogen /% v/v


Chiquita Canyon Landfill - LAB DATA


Parameter Chart: Uniscale

Date Range: 06/01/2025 - 05/31/2026

Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CCV24127 / CV-24127

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24127 / CV-24127

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24127 / CV-24127


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CCV24128 / CV-24128

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24128 / CV-24128

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24128 / CV-24128

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CCV24134 / CV-24134-TP19

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name

CV-24134 / CV-24134

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24134 / CV-24134


Parameter / Unit

Hydrogen /%,v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CCV24138 / CV-24138

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24138 / CV-24138

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24138 / CV-24138


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CCV24139 / CV-24139

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24139 / CV-24139

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24139 / CV-24139


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CCV24140 / CV-24140

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24140 / CV-24140

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24140 / CV-24140


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CCV24141 / CV-24141

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24141 / CV-24141

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24141 / CV-24141


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CCV24142 / CV-24142

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24142 / CV-24142

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24142 / CV-24142


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CCV24143 / CV-24143

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


CV-24143 / CV-24143

Parameter / Unit

Carbon Monoxide

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CV-24143 / CV-24143


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CCV24144 / CV-24144


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools





Point ID / Name


CHH1770N / H-1770N

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


H-1770N / H-1770N

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


H-1770N / H-1770N


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name


CHH2165W / H-2165W

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


H-2165W / H-2165W

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


H-2165W / H-2165W

Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


CHH2273W / H-2273W

Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools



Point ID / Name


H-2273W / H-2273W

Parameter / Unit

Carbon Monoxide /ppmv

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools



Point ID / Name


H-2273W / H-2273W


Parameter / Unit

Hydrogen /% v/v

Chiquita Canyon Landfill - LAB DATA
Parameter Chart: Uniscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/2/26

SCSeTools





Point ID / Name

CTC2383S / TC-2383S


Parameter / Unit

- Init. Flow / scfm
- % CH4 / %
- % CO2 / %
- % O2 / %
- % Bal Gas / %
- Init. Static Press / in. H2O
- Init. Temp / Deg. F
- Adj. Temp / Deg. F

Chiquita Canyon Landfill
Parameter Chart: Multiscale
Date Range: 06/01/2025 - 05/31/2026
Chart generation date: 6/3/26

SCSeTools

Thirty Day Maximum Vertical Temperature Map from the Temperature Probes at the Chiquita Canyon Landfill -May 2026



Max Temps - 20:55:42 05-31-2026

Current | 7 Day | 30 Day

BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	151	100
TP02	158	60
TP03	234	45
TP04	158	30
TP05	167	45
TP06	139	100
TP07	154	100
TP08	177	45
TP09	208	125
TP10	156	125
TP11	210	125
TP12	150	125
TP13	174	140
TP14	2,508	150
TP15	203	100
TP16	181	30
TP17	161	125
TP18	208	45
TP19	232	150
TP20	141	45
TP21	258	110
TP22	197	15
TP23	2,508	30
TP24	210	265
TP25	210	130
TP26	177	150
TP27	157	100
TP28	144	170
TP29	194	240
TP30	174	190
TP31	192	180
TP32	170	130
TP33	198	45
TP34	151	120
TP35	175	140
TP36	172	165
TP37	184	180
TP38	172	165
TP39	159	160
TP40	149	185

TP-14- The 150 foot thermocouple reported a maximum temperature of 2305 o May 10th, which was anomalous and likely associated with a potential thermocouple malfunction. As a result the report temperatures from May 11 to 15th are considered anomalous also. The 150 foot thermocouple was replaced on May 16thand temperature were consistent with previously recorded values.

TP -23 The reported maximum temperature reading of 2508 at the 30 foot thermocouple is considered anomolous and is believed to associated with a potential thermocouple sensor malfunction. The 30-foot thermocouple temperatures remained consistent with previously recorded values with the thermocouple functioning as normal.

Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 3/26/2026 12:00 AM to 5/6/2026 11:59 PM

SCS ENGINEERS

07224053.00 | May 7, 2026

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

From April 30, 2026, through May 6, 2026, there were three recorded temperature increases and one recorded temperature decrease that triggered the notification limits set forth in the LEA's October 4, 2024 letter.

Chiquita provides the following updates:


- TP-08
  - The 125-foot thermocouple went offline on March 3rd and TP-8 was offline between March 6th and March 9th for evaluation and maintenance. Upon removing the thermocouples, the casing for TP-08 was found to be damaged due to differential settlement beyond 45-feet, thus preventing the installation of the 100-foot, 125-foot, and 150-foot thermocouples. The 15-foot, 30-foot, and 45-foot thermocouples are active and reporting data.
  - The 30-foot thermocouple showed an increase in maximum temperature of 14°F from 159°F to 173°F from April 30th to May 6th.
  - The 45-foot thermocouple showed an increase in maximum temperature of 12°F from 166°F to 178°F from April 30th to May 6th.

- TP-19
  - The 150-foot thermocouple remained consistent with previous recorded temperatures.

- TP-23
  - TP-23 reported maximum values of 2508°F on March 31st, due to being taken offline for pumping liquids from the probe casing prior to thermocouples being re-installed, causing the single day erroneous readings.
  - The 15-foot thermocouple showed a decrease in maximum temperature of 26°F from 214°F to 188°F from April 30th to May 3rd and then an increase in maximum temperature of 26°F from 188°F to 214°F from May 3rd to May 6th.


- TP-36
  - The 250-foot thermocouple was evaluated due to low temperatures on April 6th and wiring that had come loose was corrected. After fixing the wiring issues temperatures returned to 136°F as previously recorded prior to March 21st.

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3



SCS ENGINEERS


Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4



SCS ENGINEERS


Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5

Maximum data for 3/26/2026 12:00 AM to 5/6/2026 11:59 PM




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16



SCS ENGINEERS


Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17



SCS ENGINEERS


Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18

Maximum data for 3/26/2026 12:00 AM to 5/6/2026 11:59 PM




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20



SCS ENGINEERS


Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21



SCS ENGINEERS


Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22

Maximum data for 3/26/2026 12:00 AM to 5/6/2026 11:59 PM




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39




SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40



SCS ENGINEERS


Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill



Max Temps - 04:58:45 05-07-2026

Current | 7 Day | 30 Day

BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	151	100
TP02	158	60
TP03	233	45
TP04	158	30
TP05	167	45
TP06	138	120
TP07	154	100
TP08	177	45
TP09	208	125
TP10	155	125
TP11	207	125
TP12	149	125
TP13	173	140
TP14	172	150
TP15	202	100
TP16	181	30
TP17	161	125
TP18	204	45
TP19	217	150
TP20	140	45
TP21	258	110
TP22	196	15
TP23	260	75
TP24	207	265
TP25	209	130
TP26	177	150
TP27	157	100
TP28	143	170
TP29	189	240
TP30	174	190
TP31	192	180
TP32	169	130
TP33	198	45
TP34	151	120
TP35	174	140
TP36	172	165
TP37	184	180
TP38	171	165
TP39	158	160
TP40	149	185



N

GRAPHIC SCALE

130 65 0 130 260 390

SCALE: 1"=130'

LEGEND

1150	EXISTING TOPOGRAPHIC CONTOUR
	EXISTING CELL LIMITS (APPROXIMATE)
TP-XX	INSTALLED TEMPERATURE PROBES - STANDALONE
TP-XX	INSTALLED TEMPERATURE PROBES - INSTALLED WITHIN WELL CASING
	REACTION AREA BOUNDARY (APPROXIMATE) - BASED ON DATA REVIEW
	REACTION AREA BOUNDARY - CONDITION 9A

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER. AERIAL PHOTOGRAPHY DATED JANUARY 28, 2026.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

DATE

REVISION

NO.

SHEET TITLE: EXISTING TEMPERATURE PROBE MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544

ACAD FILE: -
DWN: BY: -
CHK: BY: -
APP: BY: -
PROJ. NO. 01204123.41
DSN: BY: -

DATE: 02/10/2026

SCALE: AS SHOWN

SHEET: 1

Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM

SCS ENGINEERS

07224053.00 | May 14, 2026

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

From May 7, 2026, through May 13, 2026, there were three recorded temperature decreases that triggered the notification limits set forth in the LEA's October 4, 2024 letter.

Chiquita provides the following updates:


- TP-08
  - The 125-foot thermocouple went offline on March 3rd and TP-8 was offline between March 6th and March 9th for evaluation and maintenance. Upon removing the thermocouples, the casing for TP-08 was found to be damaged due to differential settlement beyond 45-feet, thus preventing the installation of the 100-foot, 125-foot, and 150-foot thermocouples. The 15-foot, 30-foot, and 45-foot thermocouples are active and reporting data.
  - The 15-foot thermocouple showed a decrease in maximum temperature of 19°F from 156°F to 137°F from May 7th to May 13th.
  - The 30-foot thermocouple showed a decrease in maximum temperature of 35°F from 175°F to 140°F from May 7th to May 13th.
  - The 45-foot thermocouple showed a decrease in maximum temperature of 36°F from 177°F to 141°F from May 7th to May 13th.

- TP-14
  - The 150-foot thermocouple showed a single hour anomalous temperature increase on May 10th.
  - The reported maximum temperature reading of 2508°F is considered anomalous and is believed to be associated with a potential thermocouple sensor malfunction. The sensor remains under evaluation and investigation.

- TP-23
  - The 15-foot thermocouple remained consistent with previous recorded temperatures.
  - The reported maximum temperature reading of 2508°F is considered anomalous and is believed to be associated with a potential thermocouple sensor malfunction. The sensor remains under evaluation and investigation.
- TP-36
  - The 250-foot thermocouple was evaluated due to low temperatures on April 6th and wiring that had come loose was corrected. After fixing the wiring issues, temperatures returned to 136°F as previously recorded prior to March 21st.

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39


Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS


Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40

Maximum data for 4/2/2026 12:00 AM to 5/13/2026 12:00 AM



SCS ENGINEERS

Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill




Max Temps - 04:58:43 05-14-2026

Current | 7 Day | 30 Day

BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	151	100
TP02	158	60
TP03	234	45
TP04	158	30
TP05	167	45
TP06	139	100
TP07	154	100
TP08	176	45
TP09	208	125
TP10	156	125
TP11	209	100
TP12	150	125
TP13	174	140
TP14	2,508	150
TP15	202	100
TP16	181	30
TP17	161	125
TP18	206	45
TP19	231	150
TP20	140	45
TP21	258	110
TP22	197	15
TP23	2,508	30
TP24	208	265
TP25	209	130
TP26	177	150
TP27	157	100
TP28	143	170
TP29	188	240
TP30	174	190
TP31	192	180
TP32	169	130
TP33	198	45
TP34	151	120
TP35	174	140
TP36	172	165
TP37	184	180
TP38	171	165
TP39	159	160
TP40	149	185

*The reported maximum temperature reading of 2508°F for TP-14 and TP-23 is considered anomalous and is believed to be associated with a potential thermocouple sensor malfunction. The sensors remain under evaluation and investigation.



N

GRAPHIC SCALE

130 65 0 130 260 390

SCALE: 1"=130'

LEGEND

- 1150 — EXISTING TOPOGRAPHIC CONTOUR
- EXISTING CELL LIMITS (APPROXIMATE)
- TP-XX — INSTALLED TEMPERATURE PROBES - STANDALONE
- TP-XX — INSTALLED TEMPERATURE PROBES - INSTALLED WITHIN WELL CASING
- REACTION AREA BOUNDARY (APPROXIMATE) - BASED ON DATA REVIEW
- REACTION AREA BOUNDARY - CONDITION 9A

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER. AERIAL PHOTOGRAPHY DATED APRIL 30, 2026.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

NO.	REVISION	DATE

SHEET TITLE: EXISTING TEMPERATURE PROBE MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544

PROJ. NO. 01204123.41 | DWN. BY: - | CHK. BY: - | ACAD FILE: - | APP. BY: - | DSN. BY: -

DATE: 05/07/2026

SCALE: AS SHOWN

SHEET: 1

Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM

SCS ENGINEERS

07224053.00 | May 21, 2026

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

From May 14, 2026, through May 20, 2026, there were one recorded temperature increase and three recorded temperature decreases that triggered the notification limits set forth in the LEA's October 4, 2024 letter.

Chiquita provides the following updates:

- TP-08
  - The 125-foot thermocouple went offline on March 3rd and TP-8 was offline between March 6th and March 9th for evaluation and maintenance. Upon removing the thermocouples, the casing for TP-08 was found to be damaged due to differential settlement beyond 45-feet, thus preventing the installation of the 100-foot, 125-foot, and 150-foot thermocouples. The 15-foot, 30-foot, and 45-foot thermocouples are active and reporting data.
  - The 15-foot thermocouple remained consistent with previous recorded temperatures..
  - The 30-foot thermocouple remained consistent with previous recorded temperatures. The 45-foot thermocouple maximum temperature increased by 15°F from 141°F to 156°F between May 14th and May 16th, and then decreased by 18°F from 156°F to 138°F between May 16th and May 20th.
- TP-14
  - The 150-foot thermocouple reported a maximum temperature of 249°F on May 10th, which was anomalous and likely associated with a potential thermocouple sensor malfunction. As a result, the reported temperatures of 0°F from May 11th to May 15th are also considered anomalous. The 150-foot thermocouple maximum temperature decreased by 77°F from 249°F to 172°F between May 10th and May 16th Temperatures remained consistent with previous recorded values from May 16th through May 20th with the thermocouple under evaluation and investigation.
  - The reported maximum temperature reading of 2508°F at the 150-foot thermocouple is considered anomalous and is believed to be associated with a potential thermocouple sensor malfunction. The sensor remains under evaluation and investigation.


- TP-23
  - The 15-foot thermocouple reported temperatures of 0°F from May 13th to May 18th, which were anomalous and likely associated with a potential thermocouple sensor malfunction. On May 19th, a temperature of 189°F was reported, with temperatures remaining consistent with previous recorded values through May 20th with the thermocouple functioning as normal.
  - The 30-foot thermocouple reported temperatures of 0°F from May 13th to May 18th, which were anomalous and likely associated with a potential thermocouple sensor malfunction. On May 19th, a

temperature of 221°F was reported, with temperatures remaining consistent with previous recorded values through May 20th with the thermocouple under evaluation and investigation.

- The reported maximum temperature reading of 2508°F at the 30-foot thermocouple is considered anomalous and is believed to be associated with a potential thermocouple sensor malfunction. The sensor remains under evaluation and investigation.

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39


Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS


Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40

Maximum data for 4/9/2026 12:00 AM to 5/20/2026 12:00 AM



SCS ENGINEERS

Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill




Max Temps - 04:58:44 05-21-2026

Current | 7 Day | 30 Day

BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	151	100
TP02	158	60
TP03	233	45
TP04	158	30
TP05	166	45
TP06	139	100
TP07	154	100
TP08	156	45
TP09	208	125
TP10	154	125
TP11	209	125
TP12	150	125
TP13	174	140
TP14	2,508	150
TP15	203	100
TP16	181	30
TP17	161	125
TP18	206	45
TP19	228	150
TP20	140	45
TP21	258	110
TP22	197	15
TP23	2,508	30
TP24	209	265
TP25	209	130
TP26	177	150
TP27	157	100
TP28	144	170
TP29	194	240
TP30	174	190
TP31	192	180
TP32	169	130
TP33	198	45
TP34	151	120
TP35	174	140
TP36	172	165
TP37	184	180
TP38	172	165
TP39	159	160
TP40	149	185

*The reported maximum temperature readings of 2508°F for TP-14 and TP-23 are considered anomalous and are believed to be associated with potential thermocouple sensor malfunctions. The sensors remain under evaluation and investigation.



N

GRAPHIC SCALE

130 65 0 130 260 390

SCALE: 1"=130'

LEGEND

- 1150 — EXISTING TOPOGRAPHIC CONTOUR
- EXISTING CELL LIMITS (APPROXIMATE)
- TP-XX — INSTALLED TEMPERATURE PROBES - STANDALONE
- TP-XX — INSTALLED TEMPERATURE PROBES - INSTALLED WITHIN WELL CASING
- REACTION AREA BOUNDARY (APPROXIMATE) - BASED ON DATA REVIEW
- REACTION AREA BOUNDARY - CONDITION 9A

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER. AERIAL PHOTOGRAPHY DATED APRIL 30, 2026.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

NO.	REVISION	DATE

SHEET TITLE: EXISTING TEMPERATURE PROBE MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544

PROJ. NO. 01204123.41 | DWN. BY: - | CHK. BY: - | ACAD FILE: - | APP. BY: - | DSN. BY: -

DATE: 05/07/2026

SCALE: AS SHOWN

SHEET: 1

Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM

SCS ENGINEERS

07224053.00 | May 28, 2026

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330


From May 21, 2026, through May 27, 2026, there were no recorded temperature increases or decreases that triggered the notification limits set forth in the LEA's October 4, 2024 letter.

Chiquita provides the following updates:

- TP-08
  - The 125-foot thermocouple went offline on March 3rd and TP-8 was offline between March 6th and March 9th for evaluation and maintenance. Upon removing the thermocouples, the casing for TP-08 was found to be damaged due to differential settlement beyond 45-feet, thus preventing the installation of the 100-foot, 125-foot, and 150-foot thermocouples. The 15-foot, 30-foot, and 45-foot thermocouples are active and reporting data.
  - The 45-foot thermocouple remained consistent with previous recoded temperatures.
- TP-14
  - The 150-foot thermocouple reported a maximum temperature of 249°F on May 10th, which was anomalous and likely associated with a potential thermocouple sensor malfunction. As a result, the reported temperatures of 0°F from May 11th to May 15th are also considered anomalous. The 150-foot thermocouple was replaced on May 16th and temperatures were consistent with previous recorded values.
- TP-23
  - The 15-foot thermocouple reported temperatures of 0°F from May 13th to May 18th, which were anomalous and likely associated with a potential thermocouple sensor malfunction. On May 19th, a temperature of 189°F was reported, with temperatures remaining consistent with previous recorded values through May 27th with the thermocouple functioning as normal.
  - The 30-foot thermocouple reported temperatures of 0°F from May 13th to May 18th, which were anomalous and likely associated with a potential thermocouple sensor malfunction. On May 19th, a temperature of 221°F was reported, with temperatures remaining consistent with previous recorded values through May 27th with the thermocouple functioning as normal.
  - The reported maximum temperature reading of 2508°F at the 30-foot thermocouple is considered anomalous and is believed to be associated with a potential thermocouple sensor malfunction. The 30-foot thermocouple temperatures remained consistent with previous recorded values with the thermocouple functioning as normal.

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39


Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS


Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40

Maximum data for 4/16/2026 12:00 AM to 5/27/2026 12:00 AM



SCS ENGINEERS


Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill



Max Temps - 04:58:38 05-28-2026

Current | 7 Day | 30 Day

BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	151	100
TP02	157	60
TP03	233	45
TP04	158	30
TP05	166	45
TP06	139	100
TP07	154	100
TP08	146	30
TP09	208	125
TP10	155	125
TP11	210	100
TP12	150	125
TP13	174	140
TP14	172	150
TP15	203	100
TP16	179	30
TP17	161	125
TP18	207	45
TP19	232	150
TP20	140	45
TP21	257	110
TP22	197	15
TP23	260	75
TP24	209	265
TP25	210	130
TP26	177	150
TP27	156	100
TP28	143	170
TP29	190	240
TP30	174	190
TP31	192	180
TP32	169	130
TP33	198	45
TP34	151	120
TP35	175	140
TP36	172	165
TP37	184	180
TP38	171	165
TP39	159	160
TP40	149	185



N

GRAPHIC SCALE

130 65 0 130 260 390

SCALE: 1"=130'

LEGEND

- 1150 — EXISTING TOPOGRAPHIC CONTOUR
- EXISTING CELL LIMITS (APPROXIMATE)
- TP-XX — INSTALLED TEMPERATURE PROBES - STANDALONE
- TP-XX — INSTALLED TEMPERATURE PROBES - INSTALLED WITHIN WELL CASING
- REACTION AREA BOUNDARY (APPROXIMATE) - BASED ON DATA REVIEW
- REACTION AREA BOUNDARY - CONDITION 9A

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER. AERIAL PHOTOGRAPHY DATED APRIL 30, 2026.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

NO.	REVISION	DATE

SHEET TITLE: EXISTING TEMPERATURE PROBE MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544

PROJ. NO. 01204123.41 | DWN. BY: - | CHK. BY: - | ACAD FILE: - | APP. BY: - | DSN. BY: -

DATE: 05/07/2026

SCALE: AS SHOWN

SHEET: 1

Solid Waste Borehole Maximum Temperature Profiles Over 6 Weeks

for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM

SCS ENGINEERS

07224053.00 | June 4, 2026

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

From May 28, 2026, through June 3, 2026, there were three recorded temperature increases and one recorded temperature decrease that triggered the notification limits set forth in the LEA's October 4, 2024 letter.

Chiquita provides the following updates:

- TP-08
  - The 125-foot thermocouple went offline on March 3rd and TP-8 was offline between March 6th and March 9th for evaluation and maintenance. Upon removing the thermocouples, the casing for TP-08 was found to be damaged due to differential settlement beyond 45-feet, thus preventing the installation of the 100-foot, 125-foot, and 150-foot thermocouples. The 15-foot, 30-foot, and 45-foot thermocouples are active and reporting data.
  - The 45-foot thermocouple showed an increasein maximum temperature of 18°F from 139°F to 157°F from May 31st to June 3rd.


- TP-14
  - The 150-foot thermocouple reported a maximum temperature of 249°F on May 10th, which was anomalous and likely associated with a potential thermocouple sensor malfunction. As a result, the reported temperatures of 0°F from May 11th to May 15th are also considered anomalous. The 150-foot thermocouple was replaced on May 16th and temperatures were consistent with previous recorded values.

- TP-23
  - The 15-foot thermocouple reported temperatures of 0°F from May 13th to May 18th, which were anomalous and likely associated with a potential thermocouple sensor malfunction. On May 19th, a temperature of 189°F was reported, with temperatures remaining consistent with previous recorded values through May 27th with the thermocouple functioning as normal.
  - The 30-foot thermocouple reported temperatures of 0°F from May 13th to May 18th, which were anomalous and likely associated with a potential thermocouple sensor malfunction. On May 19th, a temperature of 221°F was reported, with temperatures remaining consistent with previously recorded values through May 27th with the thermocouple functioning as normal.
  - The reported maximum temperature reading of 2508°F at the 30-foot thermocouple is considered anomalous and is believed to be associated with a potential thermocouple sensor malfunction. The 30-foot thermocouple temperatures remained consistent with previous recorded values with the thermocouple functioning as normal.
  - The 15-foot thermocouple showed an increasein maximum temperature of 22°F from 188°F to 210°F from June 1st to June 3rd.

- TP-29
  - The 240-foot thermocouple showed an increasein maximum temperature of 22°F from 186°F to 203°F from May 26th to June 2nd and then a decrease in maximum temperature of 22°F from 203°F to 188°F from June 2nd to June 3rd.

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39


Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS


Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40

Maximum data for 4/23/2026 12:00 AM to 6/3/2026 12:00 AM



SCS ENGINEERS


Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill



Max Temps - 04:58:39 06-04-2026

Current | 7 Day | 30 Day

BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	151	100
TP02	157	60
TP03	233	45
TP04	158	30
TP05	166	45
TP06	139	100
TP07	154	100
TP08	157	45
TP09	208	125
TP10	155	125
TP11	210	125
TP12	150	125
TP13	174	140
TP14	172	150
TP15	202	100
TP16	179	30
TP17	161	125
TP18	208	45
TP19	233	150
TP20	141	45
TP21	256	110
TP22	197	15
TP23	260	75
TP24	210	265
TP25	209	130
TP26	177	150
TP27	156	100
TP28	144	170
TP29	203	240
TP30	174	190
TP31	192	180
TP32	170	130
TP33	198	45
TP34	151	120
TP35	175	140
TP36	172	165
TP37	184	180
TP38	172	165
TP39	159	160
TP40	149	185



N

GRAPHIC SCALE

130 65 0 130 260 390

SCALE: 1"=130'

LEGEND

- 1150 — EXISTING TOPOGRAPHIC CONTOUR
- EXISTING CELL LIMITS (APPROXIMATE)
- TP-XX — INSTALLED TEMPERATURE PROBES - STANDALONE
- TP-XX — INSTALLED TEMPERATURE PROBES - INSTALLED WITHIN WELL CASING
- REACTION AREA BOUNDARY (APPROXIMATE) - BASED ON DATA REVIEW
- REACTION AREA BOUNDARY - CONDITION 9A

GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLER. AERIAL PHOTOGRAPHY DATED APRIL 30, 2026.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

NO.	REVISION	DATE

SHEET TITLE: EXISTING TEMPERATURE PROBE MAP

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544

PROJ. NO. 01204123.41 | DWN. BY: - | CHK. BY: - | ACAD FILE: - | APP. BY: - | DSN. BY: -

DATE: 05/07/2026

SCALE: AS SHOWN

SHEET: 1

Attachment E

June 10, 2026

Reaction Committee Report

June 10, 2026
File No. 01204123.21-13

Mr. Baitong Chen
South Coast Air Quality Management District
21865 Copley Drive
Diamond Bar, California 91765

Subject: Monthly Reaction Mitigation Area Boundary Determination
Chiquita Canyon Landfill – Castaic, California

Dear Mr. Chen:

In accordance with Condition Nos. 9a and 9b of the Modified Stipulated Order for Abatement (SOFA) pertaining to the Chiquita Canyon Landfill (Landfill or Facility) (Case No. 6177-4), SCS Engineers (SCS), on behalf of Chiquita Canyon, LLC (Chiquita) has prepared the data-determined Reaction Mitigation Area boundary for May 2026 considering the following criteria:

- Vertical landfill gas (LFG) wellhead temperatures (greater than 160 degrees Fahrenheit).
- Temperature monitoring probe (TMP) measurements (greater than 170 degrees Fahrenheit for more than 3-weeks at any depth).
- Landfill gas quality and methane to CO2 ratio (CH_4:CO_2) (methane concentrations of less than 30 percent in conjunction with CH_4:CO_2 ratios less than 1.0).
- Landfill gas concentration of carbon monoxide (CO) (greater than 1,500 ppm) to the extent measured.
- Landfill gas concentration of hydrogen (H_2) (greater than 2 percent by volume), to the extent measured.
- Landfill settlement (18 inches or greater within a 60-day period).
- Pressurized leachate releases.

These parameters have been subjected to a cumulative evaluation within each individual landfill surface grid within the Main Canyon (i.e., excluding grids 1 through 29 as well as grids 105 through 144), including all landfill gas wells, temperature probes, and other characteristics within that grid's area. For each individual landfill grid that is contiguous to the prior month's Reaction Mitigation Area, where any three or more parameters listed above indicating reaction conditions are present at the time of evaluation, including any combination of wells, temperature probes, or areas within the grid, the data-determined Reaction Mitigation Area boundary depicted on the Reaction Mitigation Area map will be adjusted to include such landfill grid(s).

For each individual landfill grid that is not contiguous to the prior month's Reaction Mitigation Area, if the three parameters present include a temperature parameter, then the grid will be added to the Reaction Mitigation Area.

In addition to the listed parameters, the following have been considered for the determination of the Reaction Mitigation Area boundary, also using an individual landfill grid-based evaluation:

- Leachate seeps;
- Odor characteristics;
- Wellheads experiencing conditions which would be expected to result in a PLR (e.g. elevated pressure, elevated temperature, liquid flow through wellhead); and
- Waste cuttings according to borehole drilling logs.

Supporting evidence, including documentation of which parameters were met or exceeded for each individual landfill grid, field testing and laboratory results (if applicable), explanation for the determination, revised Reaction Mitigation Area boundary, Reaction Mitigation Area map (if applicable), isothermal gradient range map consisting of wellhead temperature measurements, wellhead carbon monoxide range map, wellhead hydrogen range map, wellhead CH4:CO2 ratio range map, monthly landfill settlement isopach maps and 60-day isopach map, wellhead and temperature probe map with surface grids displayed, and vertical temperature profiles for temperature probes is being hereby submitted to the South Coast Air Quality Management District.

Attachment A presents the Drawing, titled "Reaction Mitigation Area Map", which depicts the Reaction Mitigation Area boundary as prescribed in Condition No. 9a, which corresponds to the limits of Cells 1/2A, 2B/3, 4, and Module 2B/3/4 P2, as a solid black line. The Drawing also depicts the Condition No. 9b data-determined Reaction Mitigation Area as a dashed magenta line.

CONCLUSION

As presented on the Drawing included as Attachment A, the extent of the data-determined Reaction Mitigation Area (dashed magenta line) is fully contained within the Reaction Mitigation Area boundary decreed in the SOFA (solid black line), except for Grid Nos. 38, 41, 53, 76, 77, 82n and 145 through 149, of which all or a portion protrudes east beyond the Cell 1/2A boundary. Because the data-driven Reaction Mitigation Area is not fully contained within the Reaction Mitigation Area boundary, the Reaction Mitigation Area boundary as prescribed in Condition No. 9a is modified to include portions of these Grids that extend beyond the Cell 1/2A boundary.

- Grid No. 38 is being incorporated based on the poor LFG quality criterium;
- Grid No. 41 is being incorporated based on the poor LFG quality and hydrogen criteria;
- Grid No. 53 is being incorporated based on the TMP temperature and poor LFG quality criteria;
- Grid No. 77 is being incorporated based on the TMP temperature, poor LFG quality, and CO concentration criteria;
- Grid No. 82 is being incorporated based on the poor LFG quality, hydrogen, and CO criteria.

The maximum temperature measurements recorded at the 40 in-situ waste temperature monitoring probes (both 7-Day and 30-Day values) during May 2026 are presented in **Attachment B** in graphical format. The LFG wellhead temperatures recorded at the extraction wells for the entire Landfill footprint are reflected on the isothermal gradient range map presented as **Attachment C**. The CH_4:CO_2 ratios measured at the LFG wellheads in the vicinity of the data-driven Reaction Mitigation Area boundary are depicted on the range map presented as **Attachment D**. The H_2 concentrations measured at the LFG wellheads in the vicinity of the data-driven Reaction Mitigation Area boundary are depicted on the range map presented as **Attachment E**. The CO concentrations measured at the LFG wellheads in the vicinity of the data-driven Reaction Mitigation Area boundary are depicted on the range map presented as **Attachment F**. The landfill surface settlement isopach values measured on a monthly basis and 60-day basis in the vicinity of the data-driven Reaction Mitigation Area boundary are depicted on the range map presented as **Attachment G**.
Please contact either of the undersigned if you have questions or require additional information.

Sincerely,

Robert E. Dick, PE, BCEE
Senior Vice President
SCS Engineers


Patrick S. Sullivan, BCES, CCP
Senior Vice President
SCS Engineers

RED/PSS

cc: Nathaniel Dickel, SCAQMD
Christina Ojeda, SCAQMD

Enclosures:

Attachment A – Reaction Mitigation Area Map
Attachment B – In-Situ Waste Temperature Monitoring Probe Data
Attachment C – Isothermal Gradient Range Map
Attachment D – Wellhead Methane-to-Carbon Dioxide Range Map
Attachment E – Wellhead Hydrogen Range Map
Attachment F – Wellhead Carbon Monoxide Range Map
Attachment G – Settlement Isopach Range Map



GENERAL DRAWING NOTES:

1. EXISTING TOPOGRAPHIC SURVEY INFORMATION SHOWN WAS PROVIDED BY PROPELLOR. AERIAL PHOTOGRAPHY DATED MAY 27, 2026.
2. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

DATE | REVISION | NO.

REACTION MITIGATION AREA

CHIQUITA CANYON LANDFILL
CASTAIC, CALIFORNIA

SHEET TITLE:

PROJECT TITLE:

CLIENT:

CHIQUITA CANYON LANDFILL
CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3900 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH: (562) 426-9544

PROJ. NO: 01234123.45
DSN. BY: -
DWN. BY: HA
CHK. BY: -
APP. BY: -
AS-BUILT-MASTERS

DATE: 06/10/2026

SCALE: AS SHOWN

1 of 1

\\SAN-FS02\Data\Files\Engineers\Waste Connections\Chiquita Canyon LF\2026 Reaction Area Maps\05-May\Grid Map\CCLF MASTER EXISTING GCCS MAP_2026-06-05_(PLR Map).dwg Jun 11, 2026 - 12:04am By: holl

Solid Waste Borehole Maximum Temperature Profiles Over 10 Weeks

for 3/16/202612:00AM to 5/31/202612:00AM


SCS ENGINEERS

07224053.00 | June 10, 2026

274 Granite Run Drive
Lancaster, PA 17601
717-550-6330

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-1


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-2


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-3


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-4


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-5


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-6


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-7


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-8


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-9


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-10


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-11


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-12


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-13


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-14


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-15


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-16


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-17


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-18


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-19


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-20


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-21


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-22


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-23


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-24


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-25


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-26


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-27


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-28


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-29


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-30


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-31


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-32


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-33


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-34


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-35


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-36


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-37


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-38


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS

Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-39


Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS


Vertical Temperature Profiles from Temperature Probes at Chiquita Landfill for TP-40

Maximum data for 3/16/2026 12:00 AM to 5/31/2026 12:00 AM



SCS ENGINEERS


Maximum Vertical Temperature Map from Temperature Probes at Chiquita Landfill



Max Temps - 04:58:39 06-04-2026

Current | 7 Day | 30 Day

BOREHOLE	MAX TEMP (°F)	@ DEPTH (FT)
TP01	151	100
TP02	157	60
TP03	233	45
TP04	158	30
TP05	166	45
TP06	139	100
TP07	154	100
TP08	157	45
TP09	208	125
TP10	155	125
TP11	210	125
TP12	150	125
TP13	174	140
TP14	172	150
TP15	202	100
TP16	179	30
TP17	161	125
TP18	208	45
TP19	233	150
TP20	141	45
TP21	256	110
TP22	197	15
TP23	260	75
TP24	210	265
TP25	209	130
TP26	177	150
TP27	156	100
TP28	144	170
TP29	203	240
TP30	174	190
TP31	192	180
TP32	170	130
TP33	198	45
TP34	151	120
TP35	175	140
TP36	172	165
TP37	184	180
TP38	172	165
TP39	159	160
TP40	149	185



GENERAL DRAWING NOTES:

1. NORTH ARROW SHOWN HERE IS REFERENCE TO THE CALIFORNIA STATE PLANE ZONE V COORDINATE SYSTEM, NAD 83.

DATE
REVISION
NO.

SHEET TITLE: ISOTHERMAL GRADIENT MAP APRIL 2026

PROJECT TITLE: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

CLIENT: CHIQUITA CANYON LANDFILL CASTAIC, CALIFORNIA

SCS ENGINEERS
ENVIRONMENTAL CONSULTANTS
3800 KILROY AIRPORT WAY, SUITE 300
LONG BEACH, CA 90806
PH. (562) 426-9544


PROJ. NO. 01204123.41
DSN. BY: -
DWN. BY: HA
CHK. BY:
APP. BY: -
ACAD FILE: ENGINEERS

DATE: 06/10/2026

SCALE: AS SHOWN

SHEET: 1

\\SAN-FS02\Data\Files\Engineers\Waste Connections\Chiquita Canyon LF\2026 Temp Probe Data\Isothermal Gradient Maps\04-April 2026\CCLF Isothermal Map-April 2026_V1.0_2026-05-08.dwg Jun 10, 2026 8:57pm By: hali



Ranges Mapped

						# Points
	>=	0	and	<	0.5	316
	>=	0.5	and	<	0.9	166
	>=	0.9	and	<	1.1	98
	>=	1.1	and	<	1.5	259
	>=	1.5	and	<	101	19

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill


Range Map

Parameter: CH4/CO2 Ratio (high range)

Analysis Method: MostRecent

Date Range: 05/01/2026 - 05/31/2026

Map generation date : 06/10/2026



Ranges Mapped

						# Points
	>=	0	and	<	20000	18
	>=	20000	and	<	50000	8
	>=	50000	and	<	100000	20
	>=	100000	and	<	999999	69

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill


Range Map

Parameter: H2 (mid range)

Analysis Method: MostRecent

Date Range: 05/01/2026 - 05/31/2026

Map generation date : 06/10/2026



Ranges Mapped

						# Points
	>=	0	and	<	500	21
	>=	500	and	<	1000	23
	>=	1000	and	<	1500	12
	>=	1500	and	<	2000	15
	>=	2000	and	<	5000	42
	>=	5000	and	<	100000	1

Point Type Legend

- calibration record
- flare-engine-ghg
- monitoring probe
- sample port
- well

N

SCSeTools

Chiquita Canyon Landfill

Range Map


Parameter: CO LAB (mid range)


Analysis Method: MostRecent

Date Range: 05/01/2026 - 05/31/2026

Map generation date : 06/10/2026

Chiquita Canyon Landfill -Isopach





May 27, 2026 Survey Image. April 1, 2026 vs May 27, 2026


Attachment F

Monthly Isopach Map June

9, 2026

Chiquita Canyon Landfill -Isopach





May 27, 2026 Survey Image. May 6, 2026 vs May 27, 2026