



Alteryx Automotive
17200 Laguna Canyon Road
Irvine, CA 92618
(888) 836-4274
Putting the data in your day-to-day drive!



DATE	2022-03-07		ORDER NO	92082	
NAME	Marlin Michelmores				
ADDRESS	05 Hooker Lane				
CITY	Wichita	STATE	KS	COUNTRY	United States
MAKE	Suzuki	MODEL	Swift	YEAR	1991
VIN	SALWG2WF4EA809007		MECHANIC	William	

QTY	PART NO	DESCRIPTION	SALES AMOUNT	TOTAL
9	BAES-86173-MY	Starter	\$374.01	\$3,366.09
6	DYHU-50879-OE	Bell housing	\$854.98	\$5,129.88
8	BJIT-59638-FY	Coil wire	\$809.15	\$6,473.20
7	CAJS-92406-JE	Fuse box	\$586.72	\$4,107.04
10	JAIM-38425-IP	Crankshaft	\$890.97	\$8,909.70
4	ZORU-40685-WP	Gear pump	\$450.64	\$1,802.56
2	JDMP-36172-DZ	Starter ring	\$142.23	\$284.46
TOTAL PARTS			\$4,108.70	\$30,072.93

DESCRIPTION OF WORK	NO. HOURS	LABOR RATE	TOTAL
Inspection	1	70	\$70.00
Parts Installation	2	150	\$300.00
TOTAL LABOR		220	\$370.00

I hereby authorize the above repair work to be done with the necessary material and grant permission to operate equipment for purpose of testing and inspection. An express mechanic's lien is acknowledged to secure the amount of repairs. <div><div>Marlin Michelmores</div><div>SIGNATURE</div></div> <div><div>2022-03-07</div><div>DATE</div></div>	TOTAL PARTS	\$30,072.93
	TOTAL LABOR	\$370.00
	TAX	7.25%
	TOTAL	\$32,650.04