



Alteryx Automotive
17200 Laguna Canyon Road
Irvine, CA 92618
(888) 836-4274
Putting the data in your day-to-day drive!



DATE	2021-07-24	ORDER NO	99129
NAME	Maia Theseira		
ADDRESS	30835 Rigney Way		
CITY	Albuquerque	STATE	NM
		COUNTRY	United States
MAKE	Subaru	MODEL	Outback
		YEAR	2001
VIN	SCFAD02A37G336288	MECHANIC	Deanna

QTY	PART NO	DESCRIPTION	SALES AMOUNT	TOTAL
4	QJIS-82094-QU	Halogen	\$871.07	\$3,484.28
8	REIP-80923-ZR	ABS steel pin	\$694.13	\$5,553.04
10	HTMD-31042-IL	Flywheel	\$75.80	\$758.00
2	RECN-83571-TH	Bucket seat	\$397.43	\$794.86
7	RGIE-46298-KD	Bolt cap	\$353.35	\$2,473.45
TOTAL PARTS			\$2,391.78	\$13,063.63

DESCRIPTION OF WORK	NO. HOURS	LABOR RATE	TOTAL
Inspection	2	70	\$140.00
Parts Installation	8	150	\$1,200.00
TOTAL LABOR		220	\$1,340.00

I hereby authorize the above repair work to be done with the necessary material and grant permission to operate equipment for purpose of testing and inspection. An express mechanic's lien is acknowledged to secure the amount of repairs.	TOTAL PARTS	\$13,063.63
	TOTAL LABOR	\$1,340.00
	TAX	7.25%
	TOTAL	\$15,447.89

SIGNATURE

2021-07-24

DATE