



Alteryx Automotive
17200 Laguna Canyon Road
Irvine, CA 92618
(888) 836-4274
Putting the data in your day-to-day drive!




DATE	2021-10-14	ORDER NO	15168
NAME	Vikki MacInnes		
ADDRESS	687 Lake View Pass		
CITY	Denton	STATE	TX
		COUNTRY	United States
MAKE	Buick	MODEL	Roadmaster
		YEAR	1995
VIN	4T1BF3EKXBU829023	MECHANIC	Beverly

QTY	PART NO	DESCRIPTION	SALES AMOUNT	TOTAL
4	EFTQ-70698-PB	Oil pan	\$176.35	\$705.40
1	HGYZ-01984-VY	Tappet	\$562.90	\$562.90
4	KJYG-91756-TE	Rocker cover	\$287.16	\$1,148.64
TOTAL PARTS			\$1,026.41	\$2,416.94

DESCRIPTION OF WORK	NO. HOURS	LABOR RATE	TOTAL
Inspection	3	70	\$210.00
Parts Installation	1	150	\$150.00
TOTAL LABOR		220	\$360.00

I hereby authorize the above repair work to be done with the necessary material and grant permission to operate equipment for purpose of testing and inspection. An express mechanic's lien is acknowledged to secure the amount of repairs.	TOTAL PARTS	\$2,416.94
	TOTAL LABOR	\$360.00
	TAX	7.25%
	TOTAL	\$2,978.27

	2021-10-14
SIGNATURE	DATE