



Alteryx Automotive

17200 Laguna Canyon Road
Irvine, CA 92618
(888) 836-4274

Putting the data in your day-to-day drive!



DATE 2021-03-30

ORDER NO 22056

NAME Pacorro Urlin

ADDRESS 8074 Buhler Drive

CITY Houston

STATE TX

COUNTRY United States

MAKE Ford

MODEL F-350 Super Duty

YEAR 2006

VIN 3GYFNDE31FS453593

MECHANIC Jean-Luc

QTY	PART NO	DESCRIPTION	SALES AMOUNT	TOTAL
1	EOKN-60839-WV	Output shaft	\$722.18	\$722.18
7	CMYL-54321-WF	Clutch shoe	\$953.80	\$6,676.60
4	PWGX-63472-IV	Other belts	\$896.79	\$3,587.16
3	FSTG-47231-XD	Starter drive	\$793.96	\$2,381.88
3	LKJH-08954-TF	Brake roll	\$763.16	\$2,289.48
1	HGDW-74652-FP	Cables	\$66.37	\$66.37
TOTAL PARTS			\$4,196.26	\$15,723.67

DESCRIPTION OF WORK	NO. HOURS	LABOR RATE	TOTAL
Inspection	4	70	\$280.00
Parts Installation	4	150	\$600.00
TOTAL LABOR		220	\$880.00

I hereby authorize the above repair work to be done with the necessary material and grant permission to operate equipment for purpose of testing and inspection. An express mechanic's lien is acknowledged to secure the amount of repairs.

Pacorro Urlin

SIGNATURE

2021-03-30

DATE

TOTAL PARTS	\$15,723.67
TOTAL LABOR	\$880.00
TAX	7.25%
TOTAL	\$17,807.44