



Alteryx Automotive
17200 Laguna Canyon Road
Irvine, CA 92618
(888) 836-4274
Putting the data in your day-to-day drive!



DATE	2021-10-29	ORDER NO	39777
NAME	See Buscher		
ADDRESS	635 Jay Place		
CITY	Boca Raton	STATE	FL
		COUNTRY	United States
MAKE	Ford	MODEL	Bronco
		YEAR	1991
VIN	YV440MBD1F1168044		MECHANIC
			William

QTY	PART NO	DESCRIPTION	SALES AMOUNT	TOTAL
6	NJHV-62430-RC	Ball joint	\$452.43	\$2,714.58
1	QSDC-63428-DU	ABS steel pin	\$835.97	\$835.97
4	ZVOF-23691-RH	Center console	\$192.19	\$768.76
8	QGWC-84920-QZ	profiled	\$271.03	\$2,168.24
2	ZGYV-64230-RO	Mirror	\$608.24	\$1,216.48
2	JFMI-95782-DH	Antenna cable	\$169.61	\$339.22
5	LSKP-68321-LC	Camshaft	\$972.61	\$4,863.05
TOTAL PARTS			\$3,502.08	\$12,906.30

DESCRIPTION OF WORK	NO. HOURS	LABOR RATE	TOTAL
Inspection	3	70	\$210.00
Parts Installation	11	150	\$1,650.00
TOTAL LABOR		220	\$1,860.00

I hereby authorize the above repair work to be done with the necessary material and grant permission to operate equipment for purpose of testing and inspection. An express mechanic's lien is acknowledged to secure the amount of repairs.	TOTAL PARTS	\$12,906.30
	TOTAL LABOR	\$1,860.00
	TAX	7.25%
	TOTAL	\$15,836.86

See Buscher

SIGNATURE

2021-10-29

DATE