



Alteryx Automotive
17200 Laguna Canyon Road
Irvine, CA 92618
(888) 836-4274
Putting the data in your day-to-day drive!



DATE	2021-05-14	ORDER NO	49033
NAME	Ermina Tear		
ADDRESS	02 Rockefeller Parkway		
CITY	Sioux Falls	STATE	SD
		COUNTRY	United States
MAKE	Volkswagen	MODEL	rio
		YEAR	1997
VIN	WAUXG74F89N973576	MECHANIC	William

QTY	PART NO	DESCRIPTION	SALES AMOUNT	TOTAL
5	DAKW-49532-AB	Ignition coil	\$977.34	\$4,886.70
6	UZHJ-56418-ZE	Battery	\$319.34	\$1,916.04
8	RNIM-73926-IO	Knuckle	\$990.55	\$7,924.40
10	KRVG-35068-FE	Piston	\$417.59	\$4,175.90
TOTAL PARTS			\$2,704.82	\$18,903.04

DESCRIPTION OF WORK	NO. HOURS	LABOR RATE	TOTAL
Inspection	4	70	\$280.00
Parts Installation	3	150	\$450.00
TOTAL LABOR		220	\$730.00

I hereby authorize the above repair work to be done with the necessary material and grant permission to operate equipment for purpose of testing and inspection. An express mechanic's lien is acknowledged to secure the amount of repairs.	TOTAL PARTS	\$18,903.04
	TOTAL LABOR	\$730.00
	TAX	7.25%
	TOTAL	\$21,056.44

<i>Ermina Tear</i>	2021-05-14
SIGNATURE	DATE