



Alteryx Automotive

17200 Laguna Canyon Road
Irvine, CA 92618
(888) 836-4274

Putting the data in your day-to-day drive!



DATE 2021-09-28

ORDER NO 55080

NAME Richmond Lill

ADDRESS 90449 Maple Wood Way

CITY Orlando

STATE FL

COUNTRY United States

MAKE Ford

MODEL Crown Victoria

YEAR 2002

VIN 1FTWW3A52AE593706

MECHANIC Beverly

QTY	PART NO	DESCRIPTION	SALES AMOUNT	TOTAL
4	LKPD-80165-IA	cardan joint)	\$694.43	\$2,777.72
9	HWVQ-09246-OI	Washer	\$385.09	\$3,465.81
5	XHBL-87691-QN	Halogen	\$755.76	\$3,778.80
8	TVWB-45681-DR	Oil gasket	\$26.98	\$215.84
3	XION-72416-DT	Brake lining	\$898.23	\$2,694.69
4	PZQM-21750-SK	Alternator fan	\$680.24	\$2,720.96
TOTAL PARTS			\$3,440.73	\$15,653.82

DESCRIPTION OF WORK	NO. HOURS	LABOR RATE	TOTAL
Inspection	2	70	\$140.00
Parts Installation	13	150	\$1,950.00
TOTAL LABOR		220	\$2,090.00

I hereby authorize the above repair work to be done with the necessary material and grant permission to operate equipment for purpose of testing and inspection. An express mechanic's lien is acknowledged to secure the amount of repairs.

Richmond Lill

SIGNATURE

2021-09-28

DATE

TOTAL PARTS	\$15,653.82
TOTAL LABOR	\$2,090.00
TAX	7.25%
TOTAL	\$19,030.25