



Alteryx Automotive
17200 Laguna Canyon Road
Irvine, CA 92618
(888) 836-4274
Putting the data in your day-to-day drive!




DATE	2021-04-21	ORDER NO	62380
NAME	Wendell Isaq		
ADDRESS	62 Vahlen Way		
CITY	Fort Worth	STATE	TX
		COUNTRY	United States
MAKE	GMC	MODEL	Safari
		YEAR	1998
VIN	JN8AE2KP9B9633207	MECHANIC	Jean-Luc

QTY	PART NO	DESCRIPTION	SALES AMOUNT	TOTAL
2	RHKA-79153-DZ	Knock sensor	\$375.57	\$751.14
7	RFOQ-94185-TE	Speed reducer	\$832.44	\$5,827.08
1	EUKH-65432-EA	Glass	\$21.47	\$21.47
1	KCWD-87249-NZ	Bonnet/hood	\$747.14	\$747.14
TOTAL PARTS			\$1,976.62	\$7,346.83

DESCRIPTION OF WORK	NO. HOURS	LABOR RATE	TOTAL
Inspection	2	70	\$140.00
Parts Installation	10	150	\$1,500.00
TOTAL LABOR		220	\$1,640.00

I hereby authorize the above repair work to be done with the necessary material and grant permission to operate equipment for purpose of testing and inspection. An express mechanic's lien is acknowledged to secure the amount of repairs.	TOTAL PARTS	\$7,346.83
	TOTAL LABOR	\$1,640.00
	TAX	7.25%
	TOTAL	\$9,638.38


SIGNATURE

2021-04-21
DATE