



Alteryx Automotive
17200 Laguna Canyon Road
Irvine, CA 92618
(888) 836-4274
Putting the data in your day-to-day drive!




DATE	2021-12-03	ORDER NO	77606
NAME	Tessie Walter		
ADDRESS	53318 La Follette Park		
CITY	Orlando	STATE	FL
		COUNTRY	United States
MAKE	Lexus	MODEL	RX
		YEAR	2001
VIN	JHMFB4F28CS308822	MECHANIC	Jean-Luc

QTY	PART NO	DESCRIPTION	SALES AMOUNT	TOTAL
5	UCEG-18023-LB	Camshaft	\$218.07	\$1,090.35
8	OBQV-32819-YF	Drive belt	\$680.27	\$5,442.16
1	BVHO-51792-HZ	Bolt cap	\$304.43	\$304.43
TOTAL PARTS			\$1,202.77	\$6,836.94

DESCRIPTION OF WORK	NO. HOURS	LABOR RATE	TOTAL
Inspection	3	70	\$210.00
Parts Installation	1	150	\$150.00
TOTAL LABOR		220	\$360.00

I hereby authorize the above repair work to be done with the necessary material and grant permission to operate equipment for purpose of testing and inspection. An express mechanic's lien is acknowledged to secure the amount of repairs.	TOTAL PARTS	\$6,836.94
	TOTAL LABOR	\$360.00
	TAX	7.25%
	TOTAL	\$7,718.72

	2021-12-03
SIGNATURE	DATE