



Alteryx Automotive

17200 Laguna Canyon Road
Irvine, CA 92618
(888) 836-4274

Putting the data in your day-to-day drive!



DATE 2021-11-01

ORDER NO 87911

NAME Care Daleman

ADDRESS 00 Larry Crossing

CITY San Francisco

STATE CA

COUNTRY United States

MAKE Land Rover

MODEL Range Rover

YEAR 2008

VIN 1C3BCBFGXCN262717

MECHANIC Worf

QTY	PART NO	DESCRIPTION	SALES AMOUNT	TOTAL
7	VAZR-16594-SL	Clutch hose	\$783.44	\$5,484.08
7	DZEX-50963-EM	Speaker	\$545.11	\$3,815.77
9	BNHC-32768-QK	Valance	\$940.79	\$8,467.11
7	FREU-28316-DC	A/C kit	\$648.68	\$4,540.76
9	LAJS-57026-QS	EGR valve	\$621.80	\$5,596.20
TOTAL PARTS			\$3,539.82	\$27,903.92

DESCRIPTION OF WORK	NO. HOURS	LABOR RATE	TOTAL
Inspection	2	70	\$140.00
Parts Installation	3	150	\$450.00
TOTAL LABOR		220	\$590.00

I hereby authorize the above repair work to be done with the necessary material and grant permission to operate equipment for purpose of testing and inspection. An express mechanic's lien is acknowledged to secure the amount of repairs.

Care Daleman

SIGNATURE

2021-11-01

DATE

TOTAL PARTS	\$27,903.92
TOTAL LABOR	\$590.00
TAX	7.25%
TOTAL	\$30,559.73