



Alteryx Automotive
17200 Laguna Canyon Road
Irvine, CA 92618
(888) 836-4274
Putting the data in your day-to-day drive!



DATE	2021-11-19	ORDER NO	16962
NAME	Ginnifer Maylour		
ADDRESS	85 Heffernan Road		
CITY	Melbourne	STATE	FL
		COUNTRY	United States
MAKE	Land Rover	MODEL	Range Rover
		YEAR	2001
VIN	WUAW2AFC9FN220733	MECHANIC	Beverly

QTY	PART NO	DESCRIPTION	SALES AMOUNT	TOTAL
7	SGQO-68437-LK	Main harness	\$534.26	\$3,739.82
7	KAND-47615-AF	Fastener	\$409.71	\$2,867.97
5	MPUV-34108-KH	Water pump	\$84.56	\$422.80
TOTAL PARTS			\$1,028.53	\$7,030.59

DESCRIPTION OF WORK	NO. HOURS	LABOR RATE	TOTAL
Inspection	4	70	\$280.00
Parts Installation	5	150	\$750.00
TOTAL LABOR		220	\$1,030.00

I hereby authorize the above repair work to be done with the necessary material and grant permission to operate equipment for purpose of testing and inspection. An express mechanic's lien is acknowledged to secure the amount of repairs.	TOTAL PARTS	\$7,030.59
	TOTAL LABOR	\$1,030.00
	TAX	7.25%
	TOTAL	\$8,644.98

SIGNATURE

DATE

2021-11-19