



Alteryx Automotive
17200 Laguna Canyon Road
Irvine, CA 92618
(888) 836-4274
Putting the data in your day-to-day drive!



DATE	2022-03-09	ORDER NO	20549	
NAME	Stu Olifard			
ADDRESS	2 Farmco Hill			
CITY	Richmond	STATE	VA	
		COUNTRY	United States	
MAKE	Saab	MODEL	9000	
		YEAR	1998	
VIN	WDDPK5HA1FF630107		MECHANIC	Beverly

QTY	PART NO	DESCRIPTION	SALES AMOUNT	TOTAL
9	ZWYA-87692-UA	cardan joint)	\$599.02	\$5,391.18
5	TLDE-23158-VT	Bonnet/hood	\$647.01	\$3,235.05
5	JVSU-90148-XF	Starter ring	\$288.40	\$1,442.00
5	BSYX-98350-FR	Tire/Tyre	\$25.67	\$128.35
5	ZFJU-95724-MS	Vacuum gauge	\$792.17	\$3,960.85
TOTAL PARTS			\$2,352.27	\$14,157.43

DESCRIPTION OF WORK	NO. HOURS	LABOR RATE	TOTAL
Inspection	4	70	\$280.00
Parts Installation	5	150	\$750.00
TOTAL LABOR		220	\$1,030.00

I hereby authorize the above repair work to be done with the necessary material and grant permission to operate equipment for purpose of testing and inspection. An express mechanic's lien is acknowledged to secure the amount of repairs.	TOTAL PARTS	\$14,157.43
	TOTAL LABOR	\$1,030.00
	TAX	7.25%
	TOTAL	\$16,288.52

SIGNATURE

DATE

2022-03-09