



ORDER NO 87436

NAME Jorge Dreger

ADDRESS 9660 Merchant Hill

CITY Boulder

STATE CO

COUNTRY United States

MAKE Kia

MODEL **Sephia**

YEAR 2000

VIN JTEBC3EHXC2800308

MECHANIC Wurf

DESCRIPTION OF WORK	NO. HOURS	LABOR RATE	TOTAL
Inspection	1	70	\$70.00
Parts Installation	5	150	\$750.00
TOTAL LABOR		220	\$820.00

I hereby authorize the above repair work to be done with the necessary material and grant permission to operate equipment for purpose of testing and inspection. An express mechanic's lien is acknowledged to secure the amount of repairs.

SIGNATURE

DATE _____

TOTAL PARTS	\$127.01
TOTAL LABOR	\$820.00
TAX	7.25%
TOTAL	\$1,015.67