



December 23, 2025

*Via E-Mail*

Baitong Chen, Air Quality Engineer, [bchen@aqmd.gov](mailto:bchen@aqmd.gov)  
Nathaniel Dickel, Senior Air Quality Engineer, [ndickel@aqmd.gov](mailto:ndickel@aqmd.gov)  
Christina Ojeda, Air Quality Inspector, [cojeda@aqmd.gov](mailto:cojeda@aqmd.gov)  
South Coast Air Quality Management District  
21865 East Copley Drive  
Diamond Bar, California 91765-4182

**Re: Chiquita Canyon, LLC's Weekly Leachate Inspection Report for Stipulated Order for Abatement (Case No. 6177-4), Condition 27(c)**

All:

Pursuant to Condition 27(c) of the Stipulated Order for Abatement with the South Coast Air Quality Management District in Case No. 6177-4 (the “Order”), Chiquita Canyon, LLC (“Chiquita”) encloses a compilation of the twice daily leachate seep inspection logs for the dates of December 15, 2025 through December 21, 2025. No leachate seepage or pooling was observed at the Chiquita Canyon Landfill during these inspections. There is no additional information to provide under Condition 27(c).

Regards,

*Amanda Froman*

Amanda Froman  
Compliance Manager  
Chiquita Canyon, LLC

Attachment: Leachate Inspection Logs from December 15 – December 21, 2025

# 4050 - Chiquita Leachate Seep/Pooling Inspection

15 Dec 2025 / Tom Roe

Complete

Conducted on

15 Dec 2025 7:01 AM PST

Prepared by

Tom Roe

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

**Has a leachate seep/pooling been located?**

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road.

# 4050 - Chiquita Leachate Seep/Pooling Inspection

15 Dec 2025 / Tom Roe

Complete

Conducted on

15 Dec 2025 2:20 PM PST

Prepared by

Tom Roe

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

**Has a leachate seep/pooling been located?**

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

North perimeter road.

# 4050 - Chiquita Leachate Seep/Pooling Inspection

16 Dec 2025 / Tom Roe

Complete

Conducted on

16 Dec 2025 7:12 AM PST

Prepared by

Tom Roe

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

**Has a leachate seep/pooling been located?**

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road.

# 4050 - Chiquita Leachate Seep/Pooling Inspection

16 Dec 2025 / Tom Roe

Complete

Conducted on

16 Dec 2025 1:58 PM PST

Prepared by

Tom Roe

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

**Has a leachate seep/pooling been located?**

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

North perimeter road.

# 4050 - Chiquita Leachate Seep/Pooling Inspection

17 Dec 2025 / Tom Roe

Complete

Conducted on

17 Dec 2025 7:33 AM PST

Prepared by

Tom Roe

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

**Has a leachate seep/pooling been located?**

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road.

# 4050 - Chiquita Leachate Seep/Pooling Inspection

17 Dec 2025 / Tom Roe

Complete

Conducted on

17 Dec 2025 2:31 PM PST

Prepared by

Tom Roe

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

**Has a leachate seep/pooling been located?**

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

North perimeter road

## Discharge Observations

# 4050 - Chiquita Leachate Seep/Pooling Inspection

18 Dec 2025 / John Boucher

Complete

Conducted on

18 Dec 2025 7:33 AM PST

Prepared by

John Boucher

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

**Has a leachate seep/pooling been located?**

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

West side perimeter road

# 4050 - Chiquita Leachate Seep/Pooling Inspection

18 Dec 2025 / John Boucher

Complete

Conducted on

18 Dec 2025 2:16 PM PST

Prepared by

John Boucher

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

**Has a leachate seep/pooling been located?**

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

North side perimeter road

# 4050 - Chiquita Leachate Seep/Pooling Inspection

19 Dec 2025 / John Boucher

Complete

Conducted on

19 Dec 2025 7:50 AM PST

Prepared by

John Boucher

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

**Has a leachate seep/pooling been located?**

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

West side perimeter road

# 4050 - Chiquita Leachate Seep/Pooling Inspection

19 Dec 2025 / John Boucher

Complete

Conducted on

19 Dec 2025 1:48 PM PST

Prepared by

John Boucher

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

**Has a leachate seep/pooling been located?**

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

North side perimeter road

# 4050 - Chiquita Leachate Seep/Pooling Inspection

20 Dec 2025 / John Boucher

Complete

Conducted on

20 Dec 2025 7:36 AM PST

Prepared by

John Boucher

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

**Has a leachate seep/pooling been located?**

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

West side perimeter road

# 4050 - Chiquita Leachate Seep/Pooling Inspection

20 Dec 2025 / John Boucher

Complete

Conducted on

20 Dec 2025 1:00 PM PST

Prepared by

John Boucher

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

**Has a leachate seep/pooling been located?**

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

North side perimeter road

# 4050 - Chiquita Leachate Seep/Pooling Inspection

21 Dec 2025 / Tom Roe

Complete

Conducted on

21 Dec 2025 7:17 AM PST

Prepared by

Tom Roe

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

**Has a leachate seep/pooling been located?**

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road.

# 4050 - Chiquita Leachate Seep/Pooling Inspection

21 Dec 2025 / Tom Roe

Complete

Conducted on

21 Dec 2025 1:06 PM PST

Prepared by

Tom Roe

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

**Has a leachate seep/pooling been located?**

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

North perimeter road.