



December 30, 2025

*Via E-Mail*

Baitong Chen, Air Quality Engineer, [bchen@aqmd.gov](mailto:bchen@aqmd.gov)  
Nathaniel Dickel, Senior Air Quality Engineer, [ndickel@aqmd.gov](mailto:ndickel@aqmd.gov)  
Christina Ojeda, Air Quality Inspector, [cojeda@aqmd.gov](mailto:cojeda@aqmd.gov)  
South Coast Air Quality Management District  
21865 East Copley Drive  
Diamond Bar, California 91765-4182

**Re: Chiquita Canyon, LLC's Weekly Leachate Inspection Report for Stipulated Order for Abatement (Case No. 6177-4), Condition 27(c)**

All:

Pursuant to Condition 27(c) of the Stipulated Order for Abatement with the South Coast Air Quality Management District in Case No. 6177-4 (the “Order”), Chiquita Canyon, LLC (“Chiquita”) encloses a compilation of the twice daily leachate seep inspection logs for the dates of December 22, 2025 through December 28, 2025. No leachate seepage or pooling was observed at the Chiquita Canyon Landfill during these inspections. There is no additional information to provide under Condition 27(c).

Regards,

*Amanda Froman*

Amanda Froman  
Compliance Manager  
Chiquita Canyon, LLC

Attachment: Leachate Inspection Logs from December 22 – December 28, 2025

# 4050 - Chiquita Leachate Seep/Pooling Inspection

22 Dec 2025 / Tom Roe

Complete

Conducted on

22 Dec 2025 6:30 AM PST

Prepared by

Tom Roe

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

**Has a leachate seep/pooling been located?**

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road.

# 4050 - Chiquita Leachate Seep/Pooling Inspection

22 Dec 2025 / Tom Roe

Complete

Conducted on

22 Dec 2025 1:26 PM PST

Prepared by

Tom Roe

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

**Has a leachate seep/pooling been located?**

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

North perimeter road.

# 4050 - Chiquita Leachate Seep/Pooling Inspection

23 Dec 2025 / Tom Roe

Complete

Conducted on

23 Dec 2025 7:32 AM PST

Prepared by

Tom Roe

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

**Has a leachate seep/pooling been located?**

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road.

# 4050 - Chiquita Leachate Seep/Pooling Inspection

23 Dec 2025 / Tom Roe

Complete

Conducted on

23 Dec 2025 1:43 PM PST

Prepared by

Tom Roe

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

**Has a leachate seep/pooling been located?**

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

North perimeter road.

# 4050 - Chiquita Leachate Seep/Pooling Inspection

24 Dec 2025 / John Boucher

Complete

Conducted on

24 Dec 2025 8:10 AM PST

Prepared by

John Boucher

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

**Has a leachate seep/pooling been located?**

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

West side perimeter road

# 4050 - Chiquita Leachate Seep/Pooling Inspection

24 Dec 2025 / John Boucher

Complete

Conducted on

24 Dec 2025 1:00 PM PST

Prepared by

John Boucher

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

**Has a leachate seep/pooling been located?**

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

North side perimeter road

# 4050 - Chiquita Leachate Seep/Pooling Inspection

25 Dec 2025 / John Boucher

Complete

Conducted on

25 Dec 2025 8:47 AM PST

Prepared by

John Boucher

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

**Has a leachate seep/pooling been located?**

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

West side perimeter road

# 4050 - Chiquita Leachate Seep/Pooling Inspection

25 Dec 2025 / John Boucher

Complete

Conducted on

25 Dec 2025 1:01 PM PST

Prepared by

John Boucher

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

**Has a leachate seep/pooling been located?**

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

North side perimeter road

# 4050 - Chiquita Leachate Seep/Pooling Inspection

26 Dec 2025 / John Boucher

Complete

Conducted on

26 Dec 2025 7:58 AM PST

Prepared by

John Boucher

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

**Has a leachate seep/pooling been located?**

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

West side perimeter road

# 4050 - Chiquita Leachate Seep/Pooling Inspection

26 Dec 2025 / John Boucher

Complete

Conducted on

26 Dec 2025 1:00 PM PST

Prepared by

John Boucher

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

**Has a leachate seep/pooling been located?**

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

North side perimeter road

# 4050 - Chiquita Leachate Seep/Pooling Inspection

27 Dec 2025 / John Boucher

Complete

Conducted on

27 Dec 2025 7:25 AM PST

Prepared by

John Boucher

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

**Has a leachate seep/pooling been located?**

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

West side perimeter road

# 4050 - Chiquita Leachate Seep/Pooling Inspection

27 Dec 2025 / John Boucher

Complete

Conducted on

27 Dec 2025 1:00 PM PST

Prepared by

John Boucher

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

**Has a leachate seep/pooling been located?**

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

North side perimeter road

# 4050 - Chiquita Leachate Seep/Pooling Inspection

28 Dec 2025 / Tom Roe

Complete

Conducted on

28 Dec 2025 6:48 AM PST

Prepared by

Tom Roe

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

**Has a leachate seep/pooling been located?**

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

Westside perimeter road.

# 4050 - Chiquita Leachate Seep/Pooling Inspection

28 Dec 2025 / Tom Roe

Complete

Conducted on

28 Dec 2025 1:02 PM PST

Prepared by

Tom Roe

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

**Has a leachate seep/pooling been located?**

No



Photo 1

**Description of area in photo where there is no leachate seepage or pooling.**

North perimeter road.