

Table 2. Monthly LEA Selected Wells - August 2026

Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-108-52	8/4/2026 7:50:00 AM					160						AirTech Lab
CV-108-52	8/4/2026 7:50:00 AM						9400					AirTech Lab; [User entered 0.94%]
CV-108-52	8/5/2026 8:14:59 AM	45.8	52.3	0.0	1.9			86.0	86.5	-1.33	-1.20	,
CV-108-52	8/17/2026 10:15:53 AM	17.9	69.8	0.0	12.3			103.0	103.3	7.41	7.42	Valve Adjustment: NSPS/EG CAI, Positive Static Press., Valve 100% Open
CV-108-52	8/17/2026 10:16:18 AM	18.0	70.0	0.0	12.0			103.5	103.6	6.94	6.79	Valve Adjustment: NSPS/EG CAI, Positive Static Press., Valve 100% Open
CV-113	8/10/2026 8:00:00 AM					35						AirTech Lab
CV-113	8/10/2026 8:00:00 AM						0					AirTech Lab; [User entered 0%]
CV-113	8/11/2026 9:30:06 AM	28.0	48.2	4.0	19.8			102.8	103.2	-0.59	-0.58	Valve Adjustment: Barely Open
CV-113	8/14/2026 8:10:00 AM					33						AirTech Lab
CV-113	8/14/2026 8:10:00 AM						1500					AirTech Lab; [User entered 0.15%]
CV-113	8/18/2026 9:46:41 AM	31.1	41.2	4.4	23.3			110.0	110.0	-0.83	-0.81	Valve Adjustment: Barely Open, Surging Liquid in Header
CV-114	8/3/2026 8:11:24 AM	0.5	76.8	0.0	22.7			190.8	190.9	-5.98	-5.39	Valve Adjustment: No Flow Measurement, High Temp
CV-114	8/3/2026 8:15:00 AM					3090						AtmAA
CV-114	8/3/2026 8:15:00 AM						158900					AtmAA; [User entered 15.89%]
CV-114	8/6/2026 8:05:00 AM					1800						AirTech Lab
CV-114	8/6/2026 8:05:00 AM						120000					AirTech Lab; [User entered 12%]
CV-114	8/10/2026 8:18:57 AM	1.1	74.5	0.0	24.4			190.9	190.9	-4.53	-4.43	Valve Adjustment: No Flow Measurement, High Temp
CV-114	8/10/2026 8:25:00 AM					4420						AtmAA
CV-114	8/17/2026 7:45:33 AM	3.1	79.9	0.0	17.0			190.3	190.6	-4.98	-5.05	Valve Adjustment: No Flow Measurement, High Temp
CV-114	8/17/2026 7:50:00 AM					2570						AtmAA
CV-114	8/24/2026 8:12:00 AM	3.7	81.3	0.0	15.0			191.4	191.4	-3.98	-3.84	Valve Adjustment: No Flow Measurement, High Temp
CV-114	8/31/2026 7:59:29 AM	1.2	84.0	0.0	14.8			190.1	190.1	-4.81	-4.71	Valve Adjustment: No Flow Measurement, High Temp
CV-1532A	8/4/2026 7:55:00 AM					1200						AirTech Lab
CV-1532A	8/4/2026 7:55:00 AM						140000					AirTech Lab; [User entered 14%]
CV-1532A	8/14/2026 8:47:40 AM	0.7	76.7	0.8	21.8			177.7	178.5	-4.73	-4.98	Valve Adjustment: NSPS/EG CAI, High Temp, Barely Open, Surging Liquid in Header, Surging Liquid in Well (Watered In)
CV-1532A	8/14/2026 8:48:40 AM	0.7	81.4	0.2	17.7			179.2	179.6	-8.03	-5.19	Valve Adjustment: High Temp, Surging Liquid in Header, Surging Liquid in Well (Watered In); Well Condition: Pneumatic Pump Installed

Table 2. Monthly LEA Selected Wells - August 2026

Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-1532A	8/17/2026 9:54:52 AM	4.7	80.2	0.1	15.0			185.4	185.8	-4.46	-4.26	No Flow Measurement,High Temp,No Adjustment Made
CV-1532A	8/17/2026 9:56:00 AM					1235						AtmAA
CV-1532A	8/20/2026 10:40:38 AM	0.5	64.0	1.5	34.0			183.4	181.9	-2.93	-3.15	Valve Adjustment:Increased Flow/Vacuum
CV-1532A	8/25/2026 10:00:55 AM	19.7	68.9	0.4	11.0			133.2	132.2	-4.93	-5.08	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-1532A	8/25/2026 10:03:58 AM	19.2	67.4	0.6	12.8			181.2	181.6	-5.21	-5.57	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-1532A	8/25/2026 10:06:21 AM	23.2	70.6	0.1	6.1			183.1	183.1	-3.42	-2.94	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-1535	8/5/2026 8:08:53 AM	43.4	49.3	0.0	7.3			121.5	121.4	-2.10	-2.00	,
CV-1535	8/13/2026 9:30:00 AM					55						AirTech Lab
CV-1535	8/13/2026 9:30:00 AM						7000					AirTech Lab; [User entered 0.70%]
CV-1535	8/17/2026 10:19:00 AM	53.2	45.9	0.0	0.9			124.0	124.1	-1.20	-1.21	
CV-1902A	8/4/2026 1:45:00 PM					850						AtmAA
CV-1902A	8/4/2026 1:45:00 PM						125500					AtmAA; [User entered 12.55%]
CV-1902A	8/4/2026 1:45:01 PM	4.0	81.1	0.0	14.9			180.4	180.2	1.81	-4.20	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-1902A	8/4/2026 1:45:57 PM	2.0	76.7	0.0	21.3			179.2	179.4	-4.38	-4.34	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-1902A	8/11/2026 1:30:00 PM					1720						AtmAA
CV-1902A	8/11/2026 1:35:08 PM	8.6	74.5	0.0	16.9			179.1	178.4	-7.89	-7.81	Valve Adjustment:No Flow Measurement,High Temp
CV-1902A	8/12/2026 8:50:00 AM					1100						AirTech Lab
CV-1902A	8/12/2026 8:50:00 AM						190000					AirTech Lab; [User entered 19%]
CV-1902A	8/18/2026 1:39:43 PM	25.2	71.6	0.3	2.9			187.0	187.3	-6.77	-6.77	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-1902A	8/18/2026 1:45:00 PM					1360						AtmAA
CV-1902A	8/24/2026 1:33:07 PM	25.2	73.5	0.0	1.3			169.5		-6.01		Valve Adjustment:No Flow Measurement,High Temp
CV-1902A	8/31/2026 1:58:14 PM	1.6	72.7	0.0	25.7			167.2	168.7	-5.05	-5.05	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2001	8/5/2026 7:15:00 AM					170						AirTech Lab
CV-2001	8/5/2026 7:15:00 AM						16000					AirTech Lab; [User entered 1.6%]

Table 2. Monthly LEA Selected Wells - August 2026

Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2001	8/5/2026 9:13:08 AM	10.3	75.9	2.2	11.6			82.1	82.1	-6.52	-5.98	,
CV-2001	8/11/2026 8:35:00 AM					660						AirTech Lab
CV-2001	8/11/2026 8:35:00 AM						56000					AirTech Lab; [User entered 5.6%]
CV-2001	8/25/2026 1:44:30 PM	5.7	60.9	4.0	29.4			116.7	117.1	-5.61	-6.75	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2002	8/5/2026 7:35:00 AM					1600						AirTech Lab
CV-2002	8/5/2026 7:35:00 AM						79000					AirTech Lab; [User entered 7.9%]
CV-2002	8/6/2026 8:11:00 AM					2865						AtmAA
CV-2002	8/6/2026 8:11:00 AM						93100					AtmAA; [User entered 9.31%]
CV-2002	8/6/2026 9:37:47 AM	17.8	68.5	0.3	13.4			185.7	185.7	-10.76	-10.78	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	8/11/2026 8:30:00 AM					3500						AirTech Lab
CV-2002	8/11/2026 8:30:00 AM						150000					AirTech Lab; [User entered 15%]
CV-2002	8/13/2026 7:57:34 AM	21.5	74.7	0.0	3.8			186.0	186.0	-3.03	-3.03	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	8/13/2026 8:05:00 AM					4725						AtmAA
CV-2002	8/20/2026 10:08:08 AM	47.0	53.0	0.0	0.0			187.4	187.4	-5.87	-5.73	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	8/26/2026 2:16:28 PM	19.8	67.1	0.5	12.6			185.6	185.8	-7.08	-6.78	Valve Adjustment:No Flow Measurement,High Temp
CV-2007	8/6/2026 8:30:00 AM					300						AirTech Lab
CV-2007	8/6/2026 8:30:00 AM						21000					AirTech Lab; [User entered 2.1%]
CV-2007	8/11/2026 10:26:06 AM	25.2	55.4	0.8	18.6			138.1	138.1	-0.51	-0.50	Valve Adjustment:High Temp,Barely Open
CV-2007	8/24/2026 11:27:05 AM	19.8	74.6	0.2	5.4			130.9	130.9	-0.34	-0.33	Valve Adjustment:Barely Open
CV-2301	8/5/2026 1:20:00 PM					2840						AtmAA
CV-2301	8/5/2026 1:20:00 PM						131400					AtmAA; [User entered 13.14%]
CV-2301	8/10/2026 8:11:28 AM	2.8	79.3	0.5	17.4			189.7	189.3	-0.94	-0.94	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-2301	8/10/2026 8:13:26 AM	2.7	78.8	0.5	18.0			189.4	189.8	-0.99	-0.95	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-2301	8/11/2026 10:00:00 AM					2470						AtmAA
CV-2301	8/11/2026 10:04:43 AM	19.6	75.2	0.0	5.2			188.2	189.1	-0.88	-0.87	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	8/12/2026 8:35:00 AM					1600						AirTech Lab
CV-2301	8/12/2026 8:35:00 AM						97000					AirTech Lab; [User entered 9.7%]
CV-2301	8/19/2026 2:28:43 PM	32.3	67.7	0.0	0.0			183.4	186.0	0.03	0.03	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down

Table 2. Monthly LEA Selected Wells - August 2026

Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2301	8/19/2026 3:08:38 PM	28.9	56.4	0.3	14.4			165.9	175.8	-1.18	-1.18	Valve Adjustment:No Flow Measurement,High Temp,Barely Open
CV-2301	8/26/2026 10:10:29 AM	22.7	69.4	0.0	7.9			181.6	181.8	-10.45	-10.45	Valve Adjustment:Audible Flow,High Temp
CV-2302	8/6/2026 10:01:38 AM	42.1	45.3	1.0	11.6			128.8	129.0	-17.55	-17.55	Valve Adjustment:Valve 100% Open;Well Comment:valve stuck open
CV-2302	8/12/2026 8:30:00 AM					150						AirTech Lab
CV-2302	8/12/2026 8:30:00 AM						31000					AirTech Lab; [User entered 3.1%]
CV-2302	8/19/2026 10:46:20 AM	50.9	48.2	0.9	0.0			132.3	132.1	-13.16	-13.33	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:Valve stuck open
CV-2302	8/19/2026 10:46:51 AM	52.1	46.7	1.2	0.0			132.4	132.5	-12.51	-12.83	Valve Adjustment:High Temp,Valve 100% Open
CV-2303	8/4/2026 8:20:00 AM					2035						AtmAA
CV-2303	8/4/2026 8:20:00 AM						190550					AtmAA; [User entered 19.055%]
CV-2303	8/4/2026 8:26:13 AM	1.7	76.0	0.6	21.7			188.6	190.1	-2.50	-2.33	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2303	8/12/2026 10:45:00 AM					2480						AtmAA
CV-2303	8/12/2026 10:49:02 AM	18.7	64.4	0.0	16.9			190.9	190.8	0.83	0.69	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2303	8/12/2026 2:05:55 PM	11.0	75.3	0.0	13.7			190.8	191.1	0.53	0.46	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2303	8/13/2026 9:50:00 AM					1900						AirTech Lab
CV-2303	8/13/2026 9:50:00 AM						190000					AirTech Lab; [User entered 19%]
CV-2303	8/13/2026 12:16:13 PM	1.2	70.7	0.1	28.0			188.6	189.9	-0.71	-0.74	Valve Adjustment:NSPS/EG CAI,High Temp,Valve 100% Open,Undersized Lateral;Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-2303	8/13/2026 12:19:56 PM	1.2	70.6	0.1	28.2			188.8	188.6	-0.44	-0.45	Valve Adjustment:High Temp,Valve 100% Open,Undersized Lateral;Well Condition:Lorentz Pump Installed
CV-2303	8/18/2026 8:25:00 AM					1795						AtmAA
CV-2303	8/18/2026 8:32:01 AM	9.2	66.0	0.0	24.8			191.7	191.7	0.24	0.18	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open;Well Condition:Lorentz Pump Installed

Table 2. Monthly LEA Selected Wells - August 2026

Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2303	8/18/2026 8:35:57 AM	8.3	81.8	0.0	9.9			192.6	192.6	0.44	0.38	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2303	8/25/2026 8:09:51 AM	12.5	64.0	0.0	23.5			191.0				Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2305	8/5/2026 9:00:00 AM					2310						AtmAA
CV-2305	8/5/2026 9:00:00 AM						45000					AtmAA; [User entered 4.5%]
CV-2305	8/11/2026 8:15:00 AM					1770						AtmAA
CV-2305	8/11/2026 8:18:34 AM	24.3	59.7	0.0	16.0			156.2	156.2	-4.12	-4.15	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2305	8/14/2026 7:40:00 AM					1400						AirTech Lab
CV-2305	8/14/2026 7:40:00 AM						58000					AirTech Lab; [User entered 5.8%]
CV-2305	8/18/2026 10:37:57 AM	36.0	53.6	0.0	10.4			156.9	156.9	-4.71	-4.71	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2305	8/18/2026 10:40:00 AM					1930						AtmAA
CV-2305	8/25/2026 2:29:55 PM	42.0	57.7	0.2	0.1			157.6	157.6	-4.11	-4.11	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2312-PLR	8/5/2026 10:07:00 AM					2875						AtmAA
CV-2312-PLR	8/5/2026 10:07:00 AM						149500					AtmAA; [User entered 14.95%]
CV-2312-PLR	8/11/2026 9:27:14 AM	9.4	79.0	0.1	11.5			168.1	168.0	-2.70	-3.05	Valve Adjustment:No Flow Measurement,High Temp
CV-2312-PLR	8/11/2026 9:30:00 AM					3640						AtmAA
CV-2312-PLR	8/12/2026 9:10:00 AM					2800						AirTech Lab
CV-2312-PLR	8/12/2026 9:10:00 AM						160000					AirTech Lab; [User entered 16%]
CV-2312-PLR	8/19/2026 10:34:14 AM	2.8	81.3	0.0	15.9			169.0	168.9	0.93	-2.51	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum
CV-2312-PLR	8/19/2026 10:55:23 AM	5.4	78.3	0.1	16.2			168.7	168.7	-6.79	-7.08	Valve Adjustment:No Flow Measurement,High Temp
CV-2312-PLR	8/26/2026 9:43:39 AM	1.2	79.2	0.0	19.6			169.2	169.2	-8.17	-8.09	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PLR	8/13/2026 2:35:00 PM					4450						AtmAA
CV-2314-PLR	8/13/2026 2:42:37 PM	6.3	77.6	0.0	16.1			186.7	188.1	-12.36	-12.01	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PLR	8/14/2026 7:25:00 AM					3200						AirTech Lab
CV-2314-PLR	8/14/2026 7:25:00 AM						120000					AirTech Lab; [User entered 12%]
CV-2314-PLR	8/19/2026 9:10:21 AM	6.2	81.9	0.0	11.9			187.5	187.6	-15.45	-15.50	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PLR	8/26/2026 8:32:14 AM	4.7	82.7	0.0	12.6			186.9	186.8	-16.06	-15.54	Valve Adjustment:No Flow Measurement,High Temp

Table 2. Monthly LEA Selected Wells - August 2026

Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2315	8/3/2026 10:07:01 AM	2.2	75.2	0.0	22.6			177.0	177.1	-3.72	-3.81	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2315	8/3/2026 10:10:00 AM					1280						AtmAA
CV-2315	8/3/2026 10:10:00 AM						106800					AtmAA; [User entered 10.68%]
CV-2315	8/6/2026 8:40:00 AM					1100						AirTech Lab
CV-2315	8/6/2026 8:40:00 AM						85000					AirTech Lab; [User entered 8.5%]
CV-2315	8/10/2026 1:05:49 PM	28.9	71.0	0.0	0.1			177.9	176.9	-2.62	-2.37	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2315	8/10/2026 1:10:00 PM					2530						AtmAA
CV-2315	8/19/2026 8:39:29 AM	12.9	78.2	0.1	8.8			171.2	172.6	-2.03	-1.86	Valve Adjustment:No Flow Measurement,High Temp
CV-2315	8/24/2026 9:40:11 AM	32.2	67.8	0.0	0.0			189.6	189.8	-3.00	-2.86	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2315	8/31/2026 1:55:04 PM	18.3	71.8	0.0	9.9			177.2	179.7	-0.96	-0.80	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2328	8/5/2026 10:12:00 AM					1040						AtmAA
CV-2328	8/5/2026 10:12:00 AM						48200					AtmAA; [User entered 4.82%]
CV-2328	8/11/2026 8:55:00 AM					1200						AirTech Lab
CV-2328	8/11/2026 8:55:00 AM						110000					AirTech Lab; [User entered 11%]
CV-2328	8/11/2026 9:13:16 AM	30.9	69.1	0.0	0.0			177.3	177.4	-0.47	-0.47	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2328	8/11/2026 9:20:00 AM					1770						AtmAA
CV-2328	8/19/2026 9:45:37 AM	42.4	57.6	0.0	0.0			154.6	154.5	-4.33	-4.31	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2328	8/26/2026 9:18:53 AM	24.6	67.5	0.0	7.9			151.7	151.7	-6.57	-6.40	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2333	8/3/2026 8:06:27 AM	0.8	77.9	0.0	21.3			185.2	185.4	-7.64	-6.42	Valve Adjustment:No Flow Measurement,High Temp
CV-2333	8/3/2026 8:10:00 AM					5310						AtmAA
CV-2333	8/3/2026 8:10:00 AM						189600					AtmAA; [User entered 18.96%]
CV-2333	8/6/2026 8:00:00 AM					1700						AirTech Lab
CV-2333	8/6/2026 8:00:00 AM						110000					AirTech Lab; [User entered 11%]
CV-2333	8/10/2026 8:13:41 AM	1.5	68.2	0.0	30.3			185.8	185.8	-6.48	-6.39	Valve Adjustment:No Flow Measurement,High O2
CV-2333	8/10/2026 8:18:00 AM					4870						AtmAA
CV-2333	8/17/2026 7:40:00 AM					4830						AtmAA

Table 2. Monthly LEA Selected Wells - August 2026

Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2333	8/17/2026 7:40:02 AM	3.3	78.3	0.0	18.4			184.8	184.9	-6.73	-6.76	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2333	8/24/2026 8:09:19 AM	3.5	80.0	0.0	16.5			194.8	194.9	-3.25	-3.28	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2333	8/31/2026 7:56:50 AM	1.0	72.9	0.0	26.1			193.5	193.5	-3.56	-3.56	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2334	8/6/2026 8:10:00 AM					950						AirTech Lab
CV-2334	8/6/2026 8:10:00 AM						60000					AirTech Lab; [User entered 6.0%]
CV-2334	8/13/2026 12:45:25 PM	7.0	79.7	0.0	13.3			136.0	136.0	-0.92	-0.98	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header
CV-2334	8/13/2026 12:46:31 PM	6.5	80.9	0.0	12.6			136.0	136.0	-0.81	-0.71	
CV-2334	8/18/2026 9:23:38 AM	2.6	76.6	0.0	20.7			134.2	134.6	-0.76	-0.82	Valve Adjustment:High Temp,Surging Liquid in Header
CV-2334	8/18/2026 9:24:29 AM	2.6	78.4	0.0	19.1			134.6	134.3	-0.97	-0.65	Valve Adjustment:High Temp
CV-2337	8/4/2026 2:00:15 PM	5.0	77.1	0.0	17.9			153.5	153.4	-5.00	-5.00	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2337	8/4/2026 2:15:00 PM					2440						AtmAA
CV-2337	8/4/2026 2:15:00 PM						81600					AtmAA; [User entered 8.16%]
CV-2337	8/11/2026 1:46:38 PM	17.5	71.7	0.6	10.2			140.5	140.3	-8.77	-8.76	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2337	8/12/2026 9:00:00 AM					2000						AirTech Lab
CV-2337	8/12/2026 9:00:00 AM						92000					AirTech Lab; [User entered 9.2%]
CV-2337	8/13/2026 10:10:00 AM					5490						AtmAA
CV-2337	8/18/2026 1:54:21 PM	25.3	74.5	0.2	0.0			153.3	153.2	-3.03	-3.05	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2337	8/18/2026 2:10:00 PM					3910						AtmAA
CV-2337	8/24/2026 1:53:59 PM	25.6	74.4	0.0	0.0			145.9	146.3	-2.15	-2.08	Valve Adjustment:High Temp
CV-2337	8/31/2026 2:10:00 PM	4.5	72.1	0.0	23.4			153.7	154.2	-1.73	-1.64	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2341	8/6/2026 9:30:31 AM	20.9	62.0	1.1	16.0			150.0	91.8	-17.08	-4.95	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed
CV-2341	8/6/2026 9:32:29 AM	21.2	60.2	1.3	17.3			150.0	150.0	-1.96	-1.88	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed

Table 2. Monthly LEA Selected Wells - August 2026

Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2341	8/6/2026 1:23:53 PM	21.1	68.8	0.0	10.1			119.5	122.2	1.18	-3.51	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2341	8/6/2026 1:25:52 PM	18.7	68.3	0.0	13.0			122.9	123.2	-3.84	-3.83	Valve Adjustment:No Flow Measurement;Well Condition:Pnumatic Pump Installed
CV-2341	8/12/2026 8:55:00 AM					0						AirTech Lab
CV-2341	8/12/2026 8:55:00 AM						2100					AirTech Lab; [User entered 0.21%]
CV-2341	8/25/2026 9:53:17 AM	23.4	52.8	1.0	22.8			135.0	101.9	-8.81	-0.56	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2341	8/25/2026 9:54:29 AM	24.2	54.3	0.9	20.6			135.0	135.0	-0.96	-0.92	Valve Adjustment:High Temp,Barely Open,Valve 100% Closed,Surging Liquid in Header
CV-2344	8/4/2026 7:40:00 AM					210						AirTech Lab
CV-2344	8/4/2026 7:40:00 AM						16000					AirTech Lab; [User entered 1.6%]
CV-2344	8/4/2026 2:18:08 PM	8.6	74.6	0.0	16.8			145.5	145.3	-5.70	-5.71	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2344	8/4/2026 2:30:00 PM					184						AtmAA
CV-2344	8/4/2026 2:30:00 PM						13400					AtmAA; [User entered 1.34%]
CV-2344	8/12/2026 8:05:00 AM					2510						AtmAA
CV-2344	8/12/2026 8:10:00 AM	19.0	73.9	0.0	7.1			153.8	153.9	-5.37	-5.39	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2344	8/18/2026 2:17:23 PM	35.5	64.3	0.2	0.0			153.1	153.1	-4.75	-4.74	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2344	8/18/2026 2:20:00 PM					2700						AtmAA
CV-2344	8/25/2026 9:06:11 AM	27.3	70.4	0.0	2.3			147.6	148.7	-4.95	-4.90	Valve Adjustment:No Flow Measurement,High Temp
CV-2345	8/4/2026 7:35:00 AM					180						AirTech Lab
CV-2345	8/4/2026 7:35:00 AM						16000					AirTech Lab; [User entered 1.6%]
CV-2345	8/5/2026 9:49:45 AM	22.1	64.5	0.4	13.0			136.0	136.1	-6.20	-6.18	NSPS/EG CAI,High Temp
CV-2345	8/5/2026 9:50:34 AM	21.7	64.6	0.4	13.3			135.8	135.8	-6.23	-6.22	NSPS/EG CAI,High Temp
CV-2345	8/17/2026 10:05:19 AM	18.6	62.3	0.0	19.1			141.3	141.4	-5.39	-5.39	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2345	8/17/2026 10:05:37 AM	18.8	62.7	0.0	18.5			141.9	141.9	-5.39	-5.39	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2346	8/4/2026 7:30:00 AM					630						AirTech Lab
CV-2346	8/4/2026 7:30:00 AM						61000					AirTech Lab; [User entered 6.1%]

Table 2. Monthly LEA Selected Wells - August 2026

Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2346	8/4/2026 2:16:37 PM	2.1	80.7	0.0	17.2			185.3	185.6	-11.47	-11.34	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2346	8/4/2026 2:25:00 PM					1510						AtmAA
CV-2346	8/4/2026 2:25:00 PM						74700					AtmAA; [User entered 7.47%]
CV-2346	8/12/2026 7:53:58 AM	5.5	80.9	0.2	13.4			185.8	185.6	-10.30	-10.15	Valve Adjustment:No Flow Measurement,High Temp
CV-2346	8/12/2026 7:55:00 AM					1965						AtmAA
CV-2346	8/18/2026 2:11:48 PM	15.2	76.2	0.3	8.3			177.9	177.3	-10.49	-9.95	Valve Adjustment:No Flow Measurement,High Temp
CV-2346	8/18/2026 2:15:00 PM					3230						AtmAA
CV-2346	8/25/2026 8:58:33 AM	11.7	74.6	0.0	13.7			180.9	178.8	-9.91	-9.44	Valve Adjustment:No Flow Measurement,High Temp
CV-2347	8/4/2026 7:25:00 AM					250						AirTech Lab
CV-2347	8/4/2026 7:25:00 AM						21000					AirTech Lab; [User entered 2.1%]
CV-2347	8/5/2026 10:16:04 AM	17.5	43.9	0.4	38.2			113.5	112.8	-7.12	-6.92	,
CV-2347	8/17/2026 9:44:20 AM	13.0	40.0	0.0	47.0			137.5	137.7	-5.72	-5.68	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2347	8/17/2026 9:44:46 AM	13.4	42.7	0.0	43.9			138.0	138.3	-5.72	-5.72	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2348	8/4/2026 7:20:00 AM					28						AirTech Lab
CV-2348	8/4/2026 7:20:00 AM						3900					AirTech Lab; [User entered 0.39%]
CV-2348	8/5/2026 10:19:12 AM	22.6	44.0	0.0	33.4			131.6	131.7	-14.39	-14.32	NSPS/EG CAI,High Temp
CV-2348	8/5/2026 10:19:46 AM	22.8	46.3	0.0	30.9			131.7	131.7	-14.15	-14.18	NSPS/EG CAI,High Temp
CV-2348	8/17/2026 9:38:46 AM	16.3	41.7	0.0	42.0			133.8	133.8	-12.79	-12.79	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2348	8/17/2026 9:39:22 AM	17.8	45.6	0.0	36.6			133.8	133.8	-12.46	-12.56	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2349	8/3/2026 9:20:00 AM					580						AirTech Lab
CV-2349	8/3/2026 9:20:00 AM						45000					AirTech Lab; [User entered 4.5%]
CV-2349	8/5/2026 8:08:00 AM						1000					AtmAA <0.10; [User entered 0.10%]
CV-2349	8/6/2026 8:08:00 AM					2.21						AtmAA
CV-2349	8/6/2026 9:33:43 AM	5.0	74.1	0.0	20.9			177.1	177.5	-8.58	-8.42	Valve Adjustment:No Flow Measurement,High O2;Well Condition:Lorentz Pump Installed
CV-2349	8/13/2026 8:00:36 AM	12.8	73.5	0.1	13.6			179.7	179.9	-3.26	-2.94	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2349	8/13/2026 8:10:00 AM					4420						AtmAA

Table 2. Monthly LEA Selected Wells - August 2026

Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2349	8/20/2026 10:25:53 AM	44.9	55.0	0.0	0.1			182.6	179.9	0.43	0.42	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.;Well Condition:Lorentz Pump Installed
CV-2349	8/25/2026 10:38:45 AM	27.7	71.2	0.0	1.1			171.4	171.7	0.49	1.05	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2350	8/4/2026 7:45:00 AM					1600						AirTech Lab
CV-2350	8/4/2026 7:45:00 AM						88000					AirTech Lab; [User entered 8.8%]
CV-2350	8/5/2026 8:38:12 AM	4.7	80.2	0.4	14.7			118.5	119.0	-11.92	-13.57	,
CV-2350	8/25/2026 1:40:22 PM	4.5	76.5	0.3	18.7			116.7	116.9	-6.16	-6.08	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-2351	8/3/2026 7:50:00 AM					440						AirTech Lab
CV-2351	8/3/2026 7:50:00 AM						58000					AirTech Lab; [User entered 5.8%]
CV-2351	8/14/2026 8:13:45 AM	6.2	41.5	9.2	43.1			72.9	72.8	-1.12	-1.06	Valve Adjustment:NSPS/EG CAI,High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2351	8/14/2026 8:14:16 AM	6.4	40.6	9.3	43.7			73.1	73.0	-1.36	-1.08	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2351	8/19/2026 8:02:10 AM	3.8	15.1	15.8	65.3			89.3	89.4	-4.64	-4.55	Valve Adjustment:High O2,Surging Liquid in Well (Watered In)
CV-2351	8/19/2026 8:03:16 AM	3.5	15.3	15.8	65.5			89.7	89.8	-4.16	-4.43	Valve Adjustment:High O2
CV-2352	8/3/2026 7:55:00 AM					97						AirTech Lab
CV-2352	8/3/2026 7:55:00 AM						15000					AirTech Lab; [User entered 1.5%]
CV-2352	8/14/2026 8:08:45 AM	2.1	77.2	0.4	20.3			194.6	194.5	-1.90	-1.97	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open,Surging Liquid in Header;Well Condition:Pnumatic Pump Installed
CV-2352	8/14/2026 8:09:18 AM	2.1	78.5	0.3	19.1			195.1	195.3	-2.03	-2.13	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2352	8/17/2026 12:59:08 PM	14.8	85.0	0.2	0.0			136.2	135.5	-5.91	-5.92	No Flow Measurement,
CV-2352	8/19/2026 8:19:01 AM	6.6	67.5	1.3	24.6			127.6	127.6	-5.35	-5.30	Well Comment:Pump is off;Well Condition:Pnumatic Pump Installed
CV-2353-PLR	8/5/2026 8:05:00 AM					330						AirTech Lab
CV-2353-PLR	8/5/2026 8:05:00 AM						130000					AirTech Lab; [User entered 13%]
CV-2353-PLR	8/13/2026 9:50:13 AM	2.9	72.0	1.8	23.3			148.4	146.6	-6.08	-5.72	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-2353-PLR	8/17/2026 12:51:09 PM	18.9	81.1	0.0	0.0			138.9	139.9	-6.69	-6.28	No Flow Measurement,

Table 2. Monthly LEA Selected Wells - August 2026

Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2354	8/3/2026 9:15:00 AM					720						AirTech Lab
CV-2354	8/3/2026 9:15:00 AM						81000					AirTech Lab; [User entered 8.1%]
CV-2354	8/6/2026 7:50:00 AM					2330						AtmAA
CV-2354	8/6/2026 7:50:00 AM						161100					AtmAA; [User entered 16.11%]
CV-2354	8/6/2026 8:51:11 AM	7.2	65.6	1.9	25.3			124.6	128.1	-6.55	-3.85	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2354	8/6/2026 9:21:29 AM	7.4	65.0	1.7	25.9			122.4	125.3	-2.88	-1.45	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum,Barely Open
CV-2354	8/6/2026 9:27:51 AM	7.4	68.3	1.0	23.3			125.8	125.3	-1.26	-1.25	Valve Adjustment:No Flow Measurement,Barely Open;Well Condition:Lorentz Pump Installed
CV-2354	8/12/2026 8:59:52 AM	21.8	65.4	0.6	12.2			109.8	109.7	-0.51	-0.45	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2354	8/13/2026 8:24:35 AM	18.2	71.9	0.0	9.9			104.7	104.6	-7.01	-6.91	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2354	8/25/2026 10:25:34 AM	21.6	54.9	4.5	19.0			129.2	128.9	-4.71	-1.86	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24002	8/3/2026 8:46:25 AM	42.8	51.2	0.0	6.0			113.4	113.5	-3.81	-3.82	Valve Adjustment:Barely Open
CV-24002	8/17/2026 9:02:33 AM	44.1	44.6	0.0	11.3			112.1	112.1	-3.67	-3.66	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24003	8/3/2026 8:33:09 AM	38.4	56.2	0.0	5.4			122.2	121.8	-1.20	-1.11	Valve Adjustment:Decreased Flow/Vacuum
CV-24003	8/17/2026 8:54:22 AM	38.1	55.3	0.0	6.6			114.9	114.9	-0.86	-0.85	Valve Adjustment:Barely Open
CV-24007	8/3/2026 9:21:31 AM	19.4	56.0	3.3	21.3			147.4	147.6	-0.82	-0.82	Valve Adjustment:High Temp,Barely Open
CV-24007	8/3/2026 9:21:57 AM	19.7	56.0	3.3	21.0			147.5	147.6	-0.83	-0.83	Valve Adjustment:High Temp,Barely Open
CV-24007	8/6/2026 7:50:00 AM					820						AirTech Lab
CV-24007	8/6/2026 7:50:00 AM						99000					AirTech Lab; [User entered 9.9%]
CV-24007	8/12/2026 10:00:00 AM					1380						AtmAA
CV-24007	8/12/2026 10:09:00 AM	28.4	71.5	0.1	0.0			167.0	167.1	0.03	-0.80	Valve Comment:Water in;Valve Adjustment:High Temp,Increased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-24007	8/12/2026 10:12:04 AM	37.7	60.4	1.9	0.0			167.0	167.0	-0.79	-0.79	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed

Table 2. Monthly LEA Selected Wells - August 2026

Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24007	8/17/2026 8:38:48 AM	18.7	58.5	2.2	20.6			157.1	157.3	-1.25	-1.25	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24007	8/17/2026 2:05:00 PM					438						AtmAA
CV-24007	8/17/2026 2:23:05 PM	39.0	57.0	1.7	2.3			158.5	154.5	-0.73	-1.38	Valve Adjustment:High Temp,Increased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-24007	8/17/2026 2:25:42 PM	41.3	50.4	1.9	6.4			154.2	154.2	-1.39	-1.39	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-24007	8/24/2026 2:15:04 PM	11.0	70.6	0.0	18.4			145.1	145.1	-3.63	-3.62	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-24007	8/31/2026 2:28:42 PM	37.7	50.1	0.0	12.2			146.2	146.2	-3.89	-3.88	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-24017	8/4/2026 7:38:00 AM					1030						AtmAA
CV-24017	8/4/2026 7:38:00 AM						121050					AtmAA; [User entered 12.105%]
CV-24017	8/4/2026 7:45:06 AM	15.1	70.6	0.5	13.8			179.5	179.9	-7.79	-7.98	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	8/10/2026 2:06:01 PM	33.5	66.2	0.3	0.0			188.9	188.9	-4.56	-4.50	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	8/10/2026 2:08:00 PM					1810						AtmAA
CV-24017	8/13/2026 9:40:00 AM					1300						AirTech Lab
CV-24017	8/13/2026 9:40:00 AM						160000					AirTech Lab; [User entered 16%]
CV-24017	8/18/2026 7:55:00 AM					1780						AtmAA
CV-24017	8/18/2026 7:55:27 AM	20.0	70.1	0.3	9.6			179.8	179.9	-5.02	-4.95	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	8/25/2026 7:37:48 AM	20.6	70.1	0.3	9.0			188.7	188.5	-5.11	-5.05	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	8/31/2026 2:36:27 PM	28.9	68.5	0.2	2.4			178.0	178.0	-3.51	-3.46	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24049	8/3/2026 10:14:35 AM	4.6	65.2	0.0	30.2			191.9	192.1	-7.41	-7.41	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24049	8/3/2026 10:16:00 AM					2860						AtmAA
CV-24049	8/3/2026 10:16:00 AM						151700					AtmAA; [User entered 15.17%]
CV-24049	8/10/2026 8:35:00 AM					1800						AirTech Lab
CV-24049	8/10/2026 8:35:00 AM						160000					AirTech Lab; [User entered 16%]

Table 2. Monthly LEA Selected Wells - August 2026

Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24049	8/10/2026 10:35:06 AM	31.3	55.9	0.0	12.8			193.1	193.0	-4.75	-4.74	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24049	8/10/2026 10:50:00 AM					2690						AtmAA
CV-24049	8/17/2026 10:00:00 AM					2900						AtmAA
CV-24049	8/17/2026 10:01:45 AM	23.8	71.2	0.0	5.0			192.5	192.5	-5.15	-5.05	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24049	8/19/2026 9:13:13 AM	34.3	50.9	0.2	14.6			109.0	108.3	-7.30	-6.94	Valve Adjustment:Decreased Flow/Vacuum
CV-24053	8/11/2026 8:32:30 AM	28.4	41.4	0.0	30.2			110.2	111.7	-10.94	-10.73	Valve Adjustment:Decreased Flow/Vacuum
CV-24053	8/13/2026 10:00:00 AM					65						AirTech Lab
CV-24053	8/13/2026 10:00:00 AM						6900					AirTech Lab; [User entered 0.69%]
CV-24053	8/24/2026 12:25:50 PM	32.4	49.1	0.0	18.5			123.6	123.5	-6.67	-6.01	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-24055	8/10/2026 8:30:00 AM					1000						AirTech Lab
CV-24055	8/10/2026 8:30:00 AM						62000					AirTech Lab; [User entered 6.2%]
CV-24055	8/12/2026 11:19:25 AM	10.5	53.1	2.9	33.5			144.8	144.7	-0.48	-0.48	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-24055	8/12/2026 11:20:04 AM	10.1	52.7	2.5	34.7			144.8	144.7	-0.49	-0.49	
CV-24055	8/17/2026 2:09:12 PM	6.6	49.7	3.3	40.4			131.5	131.9	-0.45	-0.47	Valve Adjustment:High Temp,Barely Open
CV-24062	8/5/2026 9:25:00 AM					1390						AtmAA
CV-24062	8/5/2026 9:25:00 AM						99200					AtmAA; [User entered 9.92%]
CV-24062	8/11/2026 9:00:00 AM					800						AirTech Lab
CV-24062	8/11/2026 9:00:00 AM						110000					AirTech Lab; [User entered 11%]
CV-24062	8/11/2026 9:02:17 AM	37.4	62.6	0.0	0.0			179.6	179.1	-5.39	-5.39	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24062	8/11/2026 9:10:00 AM					1170						AtmAA
CV-24062	8/19/2026 9:36:51 AM	36.1	63.9	0.0	0.0			179.0	178.9	-5.01	-5.05	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24062	8/26/2026 9:11:37 AM	9.3	77.6	0.0	13.1			177.8	178.0	-8.47	-8.42	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24063	8/5/2026 9:06:00 AM					2010						AtmAA
CV-24063	8/5/2026 9:06:00 AM						82600					AtmAA; [User entered 8.26%]
CV-24063	8/11/2026 8:49:07 AM	25.0	75.0	0.0	0.0			183.2	183.4	-5.39	-5.39	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed

Table 2. Monthly LEA Selected Wells - August 2026

Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24063	8/11/2026 8:55:00 AM					2060						AtmAA
CV-24063	8/11/2026 9:10:00 AM					1400						AirTech Lab
CV-24063	8/11/2026 9:10:00 AM						100000					AirTech Lab; [User entered 10%]
CV-24063	8/19/2026 8:57:44 AM	15.3	84.7	0.0	0.0			180.8	180.9	-4.95	-4.86	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24063	8/26/2026 9:05:54 AM	5.4	79.8	0.0	14.8			186.6	186.6	-9.10	-8.89	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24064-PLR	8/4/2026 1:38:00 PM					2600						AtmAA
CV-24064-PLR	8/4/2026 1:38:00 PM						125500					AtmAA; [User entered 12.55%]
CV-24064-PLR	8/4/2026 1:40:41 PM	11.8	80.0	0.0	8.2			191.3	191.5	-13.44	-11.46	Valve Adjustment:No Flow Measurement,High Temp
CV-24064-PLR	8/10/2026 8:45:00 AM					1500						AirTech Lab
CV-24064-PLR	8/10/2026 8:45:00 AM						130000					AirTech Lab; [User entered 13%]
CV-24064-PLR	8/11/2026 8:34:13 AM	11.0	79.7	0.1	9.2			192.1	192.1	-14.33	-13.91	Valve Adjustment:No Flow Measurement,High Temp
CV-24064-PLR	8/11/2026 8:40:00 AM					2340						AtmAA
CV-24064-PLR	8/18/2026 1:38:23 PM	45.5	53.3	0.0	1.2			191.4	191.4	-13.02	-13.02	Valve Adjustment:No Flow Measurement,High Temp
CV-24064-PLR	8/18/2026 1:50:00 PM					2460						AtmAA
CV-24064-PLR	8/26/2026 8:14:44 AM	19.0	55.8	0.0	25.2			191.9	191.9	-14.42	-14.45	Valve Adjustment:No Flow Measurement,High Temp
CV-24065-TP17	8/6/2026 8:35:00 AM					180						AirTech Lab
CV-24065-TP17	8/6/2026 8:35:00 AM						9300					AirTech Lab; [User entered 0.93%]
CV-24065-TP17	8/7/2026 2:17:18 PM	11.6	50.4	4.8	33.2			126.2	126.1	-5.19	-4.71	Valve Adjustment:Decreased Flow/Vacuum
CV-24065-TP17	8/17/2026 1:30:12 PM	12.9	61.1	1.4	24.6			120.3	120.7	-3.77	-3.33	Valve Adjustment:Barely Open,Valve 100% Closed
CV-24066	8/5/2026 7:49:09 AM	17.3	42.8	0.0	39.9			115.0	115.7	-2.55	-2.43	,
CV-24066	8/12/2026 8:45:00 AM					130						AirTech Lab
CV-24066	8/12/2026 8:45:00 AM						15000					AirTech Lab; [User entered 1.5%]
CV-24066	8/17/2026 10:25:54 AM	24.0	40.5	0.0	35.5			125.0	125.2	-1.54	-1.53	
CV-24069	8/6/2026 10:10:17 AM	14.8	46.2	0.6	38.4			124.6	124.7	-4.35	-2.57	Valve Adjustment:Decreased Flow/Vacuum,Barely Open;Well Condition:Lorentz Pump Installed
CV-24069	8/12/2026 8:40:00 AM					680						AirTech Lab
CV-24069	8/12/2026 8:40:00 AM						61000					AirTech Lab; [User entered 6.1%]
CV-24069	8/17/2026 11:15:26 AM	19.1	39.9	0.0	41.0			126.1	125.2	-2.56	-1.85	Valve Adjustment:Decreased Flow/Vacuum
CV-24070	8/5/2026 1:15:00 PM					1350						AtmAA

Table 2. Monthly LEA Selected Wells - August 2026

Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24070	8/5/2026 1:15:00 PM						51500					AtmAA; [User entered 5.15%]
CV-24070	8/6/2026 10:16:11 AM	28.3	66.4	0.1	5.2			145.3	144.8	-9.45	-3.44	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open
CV-24070	8/11/2026 9:50:00 AM					1980						AtmAA
CV-24070	8/11/2026 9:58:05 AM	22.2	75.5	0.0	2.3			150.5	151.4	0.20	-3.58	Valve Adjustment:High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24070	8/11/2026 9:59:08 AM	19.9	73.9	0.0	6.2			151.5	151.5	-3.85	-3.82	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24070	8/12/2026 9:05:00 AM					1000						AirTech Lab
CV-24070	8/12/2026 9:05:00 AM						74000					AirTech Lab; [User entered 7.4%]
CV-24070	8/19/2026 2:15:36 PM	29.3	66.6	0.0	4.1			148.9	148.9	-2.14	-2.12	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24070	8/26/2026 10:01:22 AM	19.2	72.8	0.0	8.0			149.3	149.2	-3.53	-3.55	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24071	8/6/2026 2:29:21 PM	27.8	64.1	0.2	7.9			130.6	130.5	-0.68	-0.67	Valve Adjustment:Barely Open
CV-24071	8/11/2026 9:25:00 AM					620						AirTech Lab
CV-24071	8/11/2026 9:25:00 AM						74000					AirTech Lab; [User entered 7.4%]
CV-24071	8/18/2026 1:36:23 PM	30.7	63.1	0.2	6.0			135.5	135.1	-1.35	-0.76	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-24071	8/18/2026 1:37:29 PM	30.5	63.5	0.2	5.8			134.9	134.9	-0.63	-0.64	Valve Adjustment:High Temp,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-24075-TP15	8/3/2026 1:45:00 PM					1960						AtmAA
CV-24075-TP15	8/4/2026 1:44:39 PM	11.3	82.9	0.0	5.8			187.3	187.4	-5.73	-5.76	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24075-TP15	8/4/2026 1:45:00 PM						112900					AtmAA; [User entered 11.29%]
CV-24075-TP15	8/11/2026 8:45:54 AM	21.3	78.5	0.2	0.0			187.9	188.0	-5.39	-5.35	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24075-TP15	8/11/2026 8:50:00 AM					1550						AtmAA
CV-24075-TP15	8/18/2026 1:49:32 PM	25.7	73.7	0.6	0.0			187.3	187.3	-6.38	-6.36	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24075-TP15	8/18/2026 2:00:00 PM					1960						AtmAA
CV-24075-TP15	8/26/2026 8:27:04 AM	8.6	78.1	0.3	13.0			186.2	186.2	-8.30	-8.32	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed

Table 2. Monthly LEA Selected Wells - August 2026

Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24077	8/4/2026 1:28:38 PM	16.3	61.4	0.0	22.3			150.6	150.6	-4.86	-4.85	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24077	8/4/2026 1:30:00 PM					778						AtmAA
CV-24077	8/4/2026 1:30:00 PM						32200					AtmAA; [User entered 3.22%]
CV-24077	8/5/2026 10:23:13 AM	20.5	56.7	0.0	22.8			150.4	149.5	-5.52	-2.84	NSPS/EG CAI,High Temp
CV-24077	8/5/2026 10:25:00 AM	17.3	73.5	0.0	9.2			148.1	148.3	-2.21	-2.14	NSPS/EG CAI,High Temp
CV-24077	8/11/2026 1:10:00 PM					1530						AtmAA
CV-24077	8/11/2026 1:12:06 PM	32.5	48.6	0.1	18.8			144.3	144.5	-4.72	-4.61	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24077	8/27/2026 10:58:50 AM	12.8	80.8	0.1	6.3			155.7	155.5	-0.60	-0.59	NSPS/EG CAI,High Temp
CV-24077	8/27/2026 10:59:50 AM	12.8	80.8	0.1	6.3			155.9	155.9	-0.39	-0.36	NSPS/EG CAI,High Temp
CV-24077	8/31/2026 1:48:05 PM	12.8	74.6	0.0	12.6			160.5	160.6	-0.24	-2.17	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24077	8/31/2026 1:48:55 PM	14.6	73.0	0.0	12.4			160.4	160.4	-2.17	-2.45	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24079-TP8	8/6/2026 9:13:08 AM	1.2	58.3	7.9	32.6			91.0	91.1	-1.22	-1.20	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24079-TP8	8/17/2026 10:59:50 AM	2.8	83.7	0.0	13.5			110.7	110.8	-0.46	-0.42	Valve Adjustment:Barely Open
CV-24082	8/6/2026 2:11:52 PM	33.9	59.8	0.2	6.1			122.3	122.2	-5.40	-5.40	
CV-24082	8/18/2026 1:00:54 PM	42.3	53.8	0.1	3.8			123.1	122.9	-7.61	-7.59	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24083	8/5/2026 1:05:00 AM					1170						AtmAA
CV-24083	8/5/2026 1:05:00 PM						62500					AtmAA; [User entered 6.25%]
CV-24083	8/11/2026 9:40:00 AM					1170						AtmAA
CV-24083	8/11/2026 9:49:55 AM	39.0	61.0	0.0	0.0			156.1	158.0	-4.03	-3.77	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24083	8/18/2026 1:09:10 PM	45.1	50.2	0.1	4.6			123.0	122.8	-7.47	-6.63	Valve Adjustment:Decreased Flow/Vacuum
CV-24083	8/19/2026 2:01:26 PM	26.9	72.9	0.0	0.2			159.6	159.4	0.50	-0.27	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24083	8/19/2026 2:02:16 PM	27.6	70.8	0.0	1.6			159.5	159.0	-0.19	-0.19	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed

Table 2. Monthly LEA Selected Wells - August 2026

Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24083	8/26/2026 9:56:45 AM	2.1	81.1	0.1	16.7			158.0	158.1	-3.98	-3.84	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24084-TP11	8/5/2026 10:30:00 AM					3590						AtmAA
CV-24084-TP11	8/5/2026 10:30:00 AM						102600					AtmAA; [User entered 10.26%]
CV-24084-TP11	8/11/2026 9:32:01 AM	8.7	79.2	0.0	12.1			184.5	184.4	-7.75	-7.46	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24084-TP11	8/11/2026 9:35:00 AM					2510						AtmAA
CV-24084-TP11	8/19/2026 1:53:18 PM	8.4	80.3	0.0	11.3			185.3	185.3	-5.69	-5.22	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24084-TP11	8/26/2026 9:51:07 AM	1.6	80.6	0.0	17.8			184.7	184.7	-7.99	-7.74	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24088	8/7/2026 8:14:51 AM	47.7	49.3	0.0	3.0			114.5	115.6	-5.40	-5.40	Valve Adjustment:Surging Liquid in Header
CV-24088	8/18/2026 1:57:15 PM	48.7	51.1	0.2	0.0			116.1	116.2	-2.82	-2.82	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24095	8/4/2026 8:05:00 AM					1400						AirTech Lab
CV-24095	8/4/2026 8:05:00 AM						110000					AirTech Lab; [User entered 11%]
CV-24095	8/6/2026 7:45:00 AM					2390						AtmAA
CV-24095	8/6/2026 7:45:00 AM						126900					AtmAA; [User entered 12.69%]
CV-24095	8/6/2026 9:31:02 AM	6.7	70.4	0.0	22.9			188.2	188.3	-6.51	-6.40	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24095	8/13/2026 8:03:42 AM	8.8	75.7	0.0	15.5			188.5	188.6	-3.66	-3.51	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24095	8/13/2026 8:15:00 AM					3850						AtmAA
CV-24095	8/20/2026 10:28:48 AM	35.7	64.3	0.0	0.0			189.9	189.9	-0.55	-0.58	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24095	8/25/2026 10:34:52 AM	28.2	66.4	0.0	5.4			190.5	190.4	2.09	1.76	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24096	8/14/2026 8:14:02 AM	1.4	6.0	19.0	73.6			71.0	71.0	-5.58	-1.31	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:Lorentz not pumping at time of read;Well Condition:Lorentz Pump Installed
CV-24096	8/14/2026 8:15:43 AM	1.3	3.1	19.5	76.1			71.1	71.1	-1.49	-1.50	

Table 2. Monthly LEA Selected Wells - August 2026

Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24096	8/31/2026 9:05:44 AM	33.8	57.7	1.4	7.1			83.8	83.8	-2.02	-1.64	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-24097	8/14/2026 8:06:13 AM	51.8	42.8	0.1	5.3			92.3	93.1	-6.51	-6.26	Valve Adjustment:Surging Liquid in Header
CV-24097	8/25/2026 2:12:37 PM	48.6	45.9	0.8	4.7			117.6	118.0	-2.88	-2.85	Valve Adjustment:Barely Open
CV-24098	8/5/2026 8:50:46 AM	42.8	55.0	0.2	2.0			97.3	98.5	-12.68	-10.25	NSPS/EG CAC,
CV-24098	8/25/2026 2:09:42 PM	36.8	63.0	0.2	0.0			111.4	113.4	-4.92	-5.07	Valve Comment:Valve stuck open
CV-24099	8/5/2026 9:03:48 AM	9.5	18.6	14.0	57.9			81.9	82.0	-3.86	-1.27	NSPS/EG CAI,High O2
CV-24099	8/5/2026 9:07:26 AM	10.2	19.7	13.6	56.5			81.3	81.4	-1.37	-0.16	NSPS/EG CAI,High O2
CV-24099	8/25/2026 2:05:42 PM	22.1	73.4	0.5	4.0			113.7	113.6	-0.18	-0.17	Valve Adjustment:Barely Open
CV-24100	8/5/2026 7:20:00 AM					40						AirTech Lab
CV-24100	8/5/2026 7:20:00 AM						6600					AirTech Lab; [User entered 0.66%]
CV-24100	8/5/2026 9:22:38 AM	22.8	77.0	0.1	0.1			155.0	155.3	-4.68	-1.72	NSPS/EG CAI,High Temp
CV-24100	8/5/2026 9:25:30 AM	18.9	81.1	0.0	0.0			154.6	154.2	-1.89	-1.47	NSPS/EG CAI,High Temp
CV-24100	8/6/2026 7:30:00 AM					46.1						AtmAA
CV-24100	8/6/2026 7:30:00 AM						4200					AtmAA; [User entered 0.42%]
CV-24100	8/6/2026 7:40:22 AM	22.1	77.9	0.0	0.0			153.9	154.2	-4.53	-4.54	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24100	8/13/2026 8:35:00 AM					195						AtmAA
CV-24100	8/13/2026 8:51:07 AM	31.4	68.6	0.0	0.0			155.2	154.5	0.12	-3.17	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24100	8/13/2026 8:53:27 AM	33.0	67.0	0.0	0.0			154.4	155.2	-3.22	-3.21	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24100	8/20/2026 12:49:12 PM	45.8	54.1	0.0	0.1			155.5	155.2	-3.69	-3.68	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24101	8/4/2026 8:15:00 AM					0						AirTech Lab
CV-24101	8/4/2026 8:15:00 AM						1700					AirTech Lab; [User entered 0.17%]
CV-24101	8/5/2026 9:32:33 AM	41.9	54.1	0.9	3.1			118.2	119.0	-16.65	-15.37	,
CV-24101	8/25/2026 1:55:01 PM	31.9	42.7	4.8	20.6			116.7	110.3	-7.43	-7.16	Valve Adjustment:Decreased Flow/Vacuum
CV-24102	8/3/2026 9:30:09 AM	3.0	2.5	16.9	77.6			103.6	104.4	0.61	-0.56	Valve Comment:valve closed upon arrival;Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High O2,Positive Static Press.,Increased Flow/Vacuum;Well Comment:pump is active;Well Condition:Pnumatic Pump Installed

Table 2. Monthly LEA Selected Wells - August 2026

Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24102	8/3/2026 9:33:08 AM	48.3	47.2	0.0	4.5			106.1	106.9	-0.99	-0.89	Valve Adjustment: NSPS/EG CAC, Decreased Flow/Vacuum; Well Condition: Pneumatic Pump Installed
CV-24102	8/3/2026 9:36:16 AM	47.2	48.2	0.0	4.6			107.2	107.8	-0.86	-0.86	Well Condition: Pneumatic Pump Installed
CV-24102	8/17/2026 9:28:29 AM	47.5	46.7	0.3	5.5			99.3	99.2	0.94	-0.65	Valve Adjustment: NSPS/EG CAI, NSPS/EG CAC, Positive Static Press., Increased Flow/Vacuum; Well Condition: Pneumatic Pump Installed
CV-24102	8/17/2026 9:29:26 AM	48.1	47.0	0.0	4.9			99.7	99.8	-0.93	-0.92	
CV-24120	8/13/2026 12:29:20 PM	8.2	26.4	13.6	51.8			95.5	96.2	-5.86	-5.98	Valve Adjustment: NSPS/EG CAI, High O2, Decreased Flow/Vacuum, Barely Open; Well Condition: Lorentz Pump Installed
CV-24120	8/13/2026 12:31:03 PM	8.2	28.5	13.2	50.1			93.8	93.4	-5.24	-4.86	
CV-24120	8/14/2026 8:00:00 AM					440						AirTech Lab
CV-24120	8/14/2026 8:00:00 AM						35000					AirTech Lab; [User entered 3.5%]
CV-24120	8/18/2026 9:13:19 AM	3.6	38.0	12.6	45.9			88.9	89.0	-6.43	-6.42	Valve Adjustment: NSPS/EG CAI, High O2; Well Condition: Lorentz Pump Installed
CV-24120	8/18/2026 9:13:57 AM	3.5	36.9	12.5	47.2			89.0	88.9	-6.42	-6.42	Valve Adjustment: High O2
CV-24120	8/24/2026 9:14:22 AM	10.5	73.1	0.0	16.4			122.4	129.7	58.71	-2.97	Valve Adjustment: NSPS/EG CAI, NSPS/EG CAC, Positive Static Press., Increased Flow/Vacuum; Well Comment: Pump is active; Well Condition: Lorentz Pump Installed
CV-24120	8/24/2026 9:17:28 AM	12.5	73.0	0.0	14.5			130.1	130.3	-3.27	-3.27	Well Comment: pump is active; Well Condition: Lorentz Pump Installed
CV-24121	8/10/2026 8:05:00 AM					12						AirTech Lab
CV-24121	8/10/2026 8:05:00 AM						2800					AirTech Lab; [User entered 0.28%]
CV-24121	8/11/2026 9:37:10 AM	1.0	3.7	19.2	76.1			93.1	94.1	-7.05	-5.99	Valve Adjustment: High O2, Decreased Flow/Vacuum, Barely Open, Surging Liquid in Header, Surging Liquid in Well (Watered In)
CV-24121	8/18/2026 9:50:10 AM	2.3	3.6	18.6	75.5			99.5	99.7	-5.72	-5.75	Valve Adjustment: NSPS/EG CAI, High O2, Barely Open, Surging Liquid in Well (Watered In); Well Comment: no pump
CV-24121	8/18/2026 9:50:57 AM	2.4	3.8	18.6	75.2			100.0	99.9	-5.80	-5.80	Valve Adjustment: High O2
CV-24122	8/10/2026 7:55:00 AM					0						AirTech Lab
CV-24122	8/10/2026 7:55:00 AM						0					AirTech Lab; [User entered 0%]
CV-24122	8/11/2026 9:26:26 AM	21.7	24.2	10.7	43.4			95.3	97.8	-3.73	-3.65	Valve Adjustment: NSPS/EG CAI, High O2, Decreased Flow/Vacuum, Barely Open
CV-24122	8/11/2026 9:27:22 AM	22.0	25.7	11.1	41.2			98.3	98.4	-3.22	-3.35	Valve Adjustment: High O2, Surging Liquid in Header, Surging Liquid in Well (Watered In)

Table 2. Monthly LEA Selected Wells - August 2026

Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24122	8/14/2026 8:05:00 AM					0						AirTech Lab
CV-24122	8/14/2026 8:05:00 AM						2100					AirTech Lab; [User entered 0.21%]
CV-24122	8/18/2026 9:56:31 AM	33.9	36.4	5.9	23.8			105.0	105.1	-2.37	-2.43	Valve Adjustment: NSPS/EG CAI, High O2, Surging Liquid in Header
CV-24122	8/18/2026 9:57:24 AM	34.7	37.5	5.7	22.1			105.8	106.0	-1.56	-1.57	Valve Adjustment: High O2, Surging Liquid in Header
CV-24123	8/5/2026 12:15:03 PM	45.8	54.2	0.0	0.0			117.3	116.8	-5.60	-4.99	,
CV-24125-TP20	8/10/2026 8:10:00 AM					0						AirTech Lab
CV-24125-TP20	8/10/2026 8:10:00 AM						0					AirTech Lab; [User entered 0%]
CV-24125-TP20	8/11/2026 9:18:03 AM	30.5	66.5	0.9	2.1			133.0	130.3	-10.50	-5.50	Valve Adjustment: NSPS/EG CAI, High Temp, Decreased Flow/Vacuum, Surging Liquid in Header, Surging Liquid in Well (Watered In); Well Condition: Pneumatic Pump Installed
CV-24125-TP20	8/11/2026 9:19:45 AM	28.7	67.4	0.8	3.1			133.0	133.0	-5.08	-5.08	Valve Adjustment: High Temp, Surging Liquid in Header, Surging Liquid in Well (Watered In)
CV-24125-TP20	8/18/2026 9:41:43 AM	35.0	54.6	0.9	9.5			130.7	130.8	-5.94	-5.80	
CV-24125-TP20	8/18/2026 9:42:30 AM	34.8	54.4	0.8	10.0			130.8	130.7	-6.04	-6.04	Well Condition: Pneumatic Pump Installed
CV-24126	8/3/2026 10:21:16 AM	3.1	74.6	0.0	22.3			191.6	191.7	-0.65	-0.61	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed
CV-24126	8/3/2026 10:25:00 AM					2120						AtmAA
CV-24126	8/3/2026 10:25:00 AM						115000					AtmAA; [User entered 11.5%]
CV-24126	8/10/2026 1:15:00 PM					3880						AtmAA
CV-24126	8/10/2026 1:26:10 PM	17.7	77.0	0.0	5.3			192.9	192.6	-0.31	-0.17	Valve Adjustment: No Flow Measurement, High Temp, Valve 100% Open; Well Condition: Lorentz Pump Installed
CV-24126	8/17/2026 9:45:56 AM	31.0	49.7	0.9	18.4			181.4	181.4	-1.12	-1.06	Valve Adjustment: High Temp
CV-24126	8/17/2026 9:50:00 AM					2420						AtmAA
CV-24126	8/24/2026 9:25:50 AM	36.6	63.4	0.0	0.0			187.3	187.5	-0.87	-0.89	Valve Adjustment: High Temp; Well Condition: Lorentz Pump Installed
CV-24126	8/31/2026 1:40:04 PM	8.9	69.9	0.0	21.2			163.5	165.7	0.55	0.53	Valve Adjustment: No Flow Measurement, High Temp, Positive Static Press., Valve 100% Open; Well Condition: Lorentz Pump Installed
CV-24126	8/31/2026 1:40:38 PM	8.4	76.2	0.0	15.4			169.5	168.1	0.60	0.58	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed
CV-24127	8/3/2026 12:50:00 PM					288						AtmAA
CV-24127	8/3/2026 12:50:00 PM						12700					AtmAA; [User entered 1.27%]

Table 2. Monthly LEA Selected Wells - August 2026

Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24127	8/3/2026 12:56:02 PM	12.8	66.6	0.1	20.5			162.4	163.1	-2.07	-2.26	Valve Adjustment:No Flow Measurement,High Temp
CV-24127	8/6/2026 8:20:00 AM					1500						AirTech Lab
CV-24127	8/6/2026 8:20:00 AM						99000					AirTech Lab; [User entered 9.9%]
CV-24127	8/10/2026 1:20:00 PM					2770						AtmAA
CV-24127	8/10/2026 1:32:33 PM	27.9	70.9	0.3	0.9			165.8	164.6	-0.44	-0.40	Valve Adjustment:No Flow Measurement,High Temp
CV-24127	8/17/2026 1:15:00 PM					4420						AtmAA
CV-24127	8/17/2026 1:25:00 PM	21.8	76.1	0.0	2.1			174.4	173.8	0.16	-0.09	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-24127	8/17/2026 1:27:59 PM	16.2	73.2	0.0	10.6			174.0	174.6	-0.17	-0.15	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24127	8/25/2026 7:19:15 AM	11.1	77.5	0.1	11.3			174.8	174.3	-0.82	-0.73	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24127	8/31/2026 1:36:18 PM	16.9	74.9	0.0	8.2			176.2	177.3	0.58	0.60	Valve Adjustment:High Temp,Positive Static Press.,Valve 100% Open;Well Condition:Pnumatic Pump Installed
CV-24127	8/31/2026 1:37:14 PM	7.9	75.1	0.0	17.0			176.7	177.4	0.54	0.54	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24128	8/6/2026 8:15:00 AM					1700						AirTech Lab
CV-24128	8/6/2026 8:15:00 AM						73000					AirTech Lab; [User entered 7.3%]
CV-24128	8/11/2026 2:38:10 PM	19.1	68.7	0.3	11.9			125.4	125.0	-0.48	-0.48	
CV-24128	8/18/2026 9:28:34 AM	15.3	67.5	0.0	17.2			126.2	126.2	-0.38	-0.37	Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24134-TP19	8/3/2026 12:45:00 AM						81700					AtmAA; [User entered 8.17%]
CV-24134-TP19	8/3/2026 12:45:00 PM					1790						AtmAA
CV-24134-TP19	8/3/2026 12:47:19 PM	13.5	70.7	0.0	15.8			152.6	153.2	-2.31	-2.31	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24134-TP19	8/10/2026 1:30:00 PM					2940						AtmAA
CV-24134-TP19	8/10/2026 1:36:07 PM	32.6	67.4	0.0	0.0			152.8	152.9	-1.70	-1.72	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24134-TP19	8/17/2026 1:05:00 PM					1280						AtmAA
CV-24134-TP19	8/17/2026 1:06:23 PM	45.4	54.6	0.0	0.0			144.7	145.0	-2.84	-2.81	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24138	8/3/2026 9:05:00 AM					560						AirTech Lab

Table 2. Monthly LEA Selected Wells - August 2026

Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24138	8/3/2026 9:05:00 AM						180000					AirTech Lab; [User entered 18%]
CV-24138	8/5/2026 7:50:00 AM					630						AirTech Lab
CV-24138	8/5/2026 7:50:00 AM						190000					AirTech Lab; [User entered 19%]
CV-24138	8/11/2026 7:40:00 AM					340						AirTech Lab
CV-24138	8/11/2026 7:40:00 AM						89000					AirTech Lab; [User entered 8.9%]
CV-24138	8/14/2026 8:33:40 AM	2.4	23.0	13.7	60.9			84.9	85.1	-2.76	-3.16	Valve Adjustment:High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-24138	8/26/2026 5:04:54 PM	3.7	27.4	11.3	57.6			121.2	121.1	-3.88	-3.87	Valve Comment:Watered in;Valve Adjustment:NSPS/EG CAI;Well Comment:pump is off;Well Condition:Pnumatic Pump Installed
CV-24138	8/26/2026 5:09:09 PM	3.3	24.4	11.8	60.5			120.9	121.0	-3.85	-3.84	Valve Adjustment:NSPS/EG CAI,High O2,Surging Liquid in Well (Watered In);Well Comment:Pump not active;Well Condition:Pnumatic Pump Installed
CV-24139	8/3/2026 9:00:00 AM					190						AirTech Lab
CV-24139	8/3/2026 9:00:00 AM						56000					AirTech Lab; [User entered 5.6%]
CV-24139	8/6/2026 8:00:00 AM					958						AtmAA
CV-24139	8/6/2026 8:00:00 AM						190600					AtmAA; [User entered 19.06%]
CV-24139	8/6/2026 8:20:30 AM	3.7	70.9	0.6	24.8			168.3	168.3	-7.89	-7.87	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24139	8/12/2026 8:30:00 AM					925						AtmAA
CV-24139	8/12/2026 8:30:51 AM	15.7	71.8	0.4	12.1			164.1	164.2	-5.39	-5.29	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24139	8/14/2026 8:27:08 AM	3.5	73.1	0.6	22.8			174.8	170.5	-5.89	-5.64	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24139	8/14/2026 8:30:50 AM	3.3	76.4	0.4	19.9			180.1	180.6	-5.73	-5.57	Valve Adjustment:High Temp,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
CV-24139	8/20/2026 10:44:52 AM	40.5	58.9	0.6	0.0			156.5	156.6	-5.05	-5.05	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24139	8/26/2026 1:26:15 PM	7.5	68.7	0.4	23.4			178.8	178.8	-5.32	-5.39	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24140	8/3/2026 8:55:00 AM					850						AirTech Lab
CV-24140	8/3/2026 8:55:00 AM						130000					AirTech Lab; [User entered 13%]

Table 2. Monthly LEA Selected Wells - August 2026

Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24140	8/14/2026 8:05:23 AM	1.9	77.0	0.8	20.3			150.7	150.8	-4.76	-4.56	Valve Adjustment: NSPS/EG CAI, High Temp, Surging Liquid in Header, Surging Liquid in Well (Watered In)
CV-24140	8/14/2026 8:05:55 AM	1.9	75.9	0.9	21.3			150.8	150.9	-4.55	-4.49	Valve Adjustment: High Temp, Surging Liquid in Header, Surging Liquid in Well (Watered In)
CV-24140	8/17/2026 12:53:30 PM	16.5	83.5	0.0	0.0			169.3	169.3	-6.27	-6.28	No Flow Measurement, High Temp
CV-24140	8/17/2026 1:05:00 PM					2510						AtmAA
CV-24140	8/20/2026 10:48:35 AM	40.1	59.9	0.0	0.0			165.5	165.9	-4.89	-4.91	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Pneumatic Pump Installed
CV-24140	8/26/2026 1:20:59 PM	4.7	71.1	0.0	24.2			166.9	169.0	-4.79	-4.98	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Pneumatic Pump Installed
CV-24141	8/5/2026 7:55:00 AM					26						AirTech Lab
CV-24141	8/5/2026 7:55:00 AM						7400					AirTech Lab; [User entered 0.74%]
CV-24141	8/14/2026 8:18:01 AM	0.3	6.4	19.2	74.1			72.5	72.6	-0.69	-0.71	Valve Adjustment: High O2
CV-24141	8/19/2026 8:10:32 AM	0.1	3.6	20.4	75.9			78.6	79.8	-4.70	-4.32	Valve Adjustment: NSPS/EG CAI, High O2, Decreased Flow/Vacuum, Surging Liquid in Well (Watered In)
CV-24141	8/19/2026 8:11:24 AM	0.1	2.3	20.5	77.2			80.1	80.2	-4.79	-4.79	Valve Adjustment: High O2, Surging Liquid in Well (Watered In)
CV-24142	8/3/2026 9:10:00 AM					790						AirTech Lab
CV-24142	8/3/2026 9:10:00 AM						130000					AirTech Lab; [User entered 13%]
CV-24142	8/5/2026 7:45:00 AM					1100						AirTech Lab
CV-24142	8/5/2026 7:45:00 AM						150000					AirTech Lab; [User entered 15%]
CV-24142	8/6/2026 7:55:00 AM					1290						AtmAA
CV-24142	8/6/2026 7:55:00 AM						130700					AtmAA; [User entered 13.07%]
CV-24142	8/6/2026 8:12:12 AM	4.7	68.4	1.3	25.6			168.1	168.0	-2.18	-2.28	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Pneumatic Pump Installed
CV-24142	8/11/2026 7:45:00 AM					490						AirTech Lab
CV-24142	8/11/2026 7:45:00 AM						75000					AirTech Lab; [User entered 7.5%]
CV-24142	8/12/2026 8:35:00 AM					2030						AtmAA
CV-24142	8/12/2026 8:39:33 AM	13.8	65.1	2.5	18.6			152.6	152.6	-1.09	-1.35	Valve Adjustment: No Flow Measurement, High Temp; Well Comment: Construction working on vacuum line
CV-24142	8/14/2026 8:23:00 AM	2.8	73.8	0.4	23.0			182.2	182.9	-1.21	-1.20	Valve Adjustment: NSPS/EG CAI, High Temp, Surging Liquid in Header, Plugged/Pinched Suspected; Well Condition: Pneumatic Pump Installed

Table 2. Monthly LEA Selected Wells - August 2026

Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24142	8/14/2026 8:24:52 AM	2.9	73.9	0.4	22.8			181.5	181.0	-1.45	-1.45	
CV-24142	8/20/2026 10:34:18 AM	35.3	64.7	0.0	0.0			173.3	174.0	-0.51	-0.52	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24142	8/26/2026 1:44:20 PM	5.6	55.6	5.2	33.6			150.0	146.6	-1.98	-1.05	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-24142	8/26/2026 1:47:24 PM	5.6	59.5	4.0	30.9			146.6	146.2	-1.15	-1.09	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24143	8/3/2026 7:50:00 AM					610						AirTech Lab
CV-24143	8/3/2026 7:50:00 AM						87000					AirTech Lab; [User entered 8.7%]
CV-24143	8/13/2026 2:58:30 PM	1.2	39.3	11.3	48.3			109.0	108.9	-1.89	-2.12	Valve Adjustment:NSPS/EG CAI,High O2,Valve 100% Open;Well Comment:no pump installed;Well Repairs:Sample Port
CV-24143	8/13/2026 3:00:34 PM	1.1	39.1	11.1	48.7			108.2	108.2	-2.01	-2.30	Valve Adjustment:High O2,Surging Liquid in Well (Watered In)
CV-24143	8/19/2026 8:25:27 AM	2.8	17.4	15.8	64.0			105.1	105.2	-5.52	-5.31	Valve Adjustment:High O2,Surging Liquid in Well (Watered In)
CV-24143	8/19/2026 8:26:07 AM	2.7	17.3	15.8	64.2			105.4	105.4	-4.95	-5.41	Valve Adjustment:High O2,Surging Liquid in Well (Watered In)
CV-24144	8/14/2026 8:01:18 AM	57.4	38.9	0.0	3.7			83.3	97.6	-1.66	-1.26	Valve Adjustment:Surging Liquid in Header,Plugged/Pinched Suspected
CV-24144	8/25/2026 2:15:55 PM	54.1	43.0	0.1	2.8			117.2	117.3	-0.50	-0.60	Valve Adjustment:Barely Open
CV-99	8/10/2026 8:15:00 AM					0						AirTech Lab
CV-99	8/11/2026 9:13:37 AM	0.8	6.0	19.0	74.2			87.8	90.1	-11.43	-11.16	Valve Adjustment:Decreased Flow/Vacuum
CV-99	8/11/2026 9:14:07 AM	1.1	6.3	18.6	74.0			90.4	90.4	-11.14	-11.14	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1770N	8/3/2026 8:36:19 AM	30.9	62.1	0.0	7.0			107.5	107.6	-0.88	-0.83	Valve Adjustment:Barely Open
H-1770N	8/14/2026 8:15:00 AM					150						AirTech Lab
H-1770N	8/14/2026 8:15:00 AM						18000					AirTech Lab; [User entered 1.8%]
H-1770N	8/17/2026 8:56:56 AM	29.3	62.5	0.0	8.2			106.1	106.1	-0.76	-0.79	Valve Adjustment:Barely Open
H-2165W	8/5/2026 9:14:44 AM	11.0	88.4	0.0	0.6							,
H-2165W	8/5/2026 9:14:45 AM	11.0	88.4	0.0	0.6							,
H-2165W	8/5/2026 9:16:03 AM	11.1	88.9	0.0	0.0			143.6	142.2	-0.91	-0.58	NSPS/EG CAI,High Temp
H-2165W	8/5/2026 9:17:25 AM	10.9	88.4	0.0	0.7			143.3	143.3	-0.55	-0.55	NSPS/EG CAI,High Temp
H-2165W	8/13/2026 9:00:00 AM					870						AirTech Lab
H-2165W	8/13/2026 9:00:00 AM						67000					AirTech Lab; [User entered 6.7%]

Table 2. Monthly LEA Selected Wells - August 2026

Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
H-2165W	8/25/2026 1:49:37 PM	14.6	82.2	0.2	3.0			146.4	143.2	0.32	-0.07	Valve Adjustment: NSPS/EG CAI, High Temp, Positive Static Press., Increased Flow/Vacuum, Barely Open
H-2165W	8/25/2026 1:50:21 PM	19.2	76.8	0.2	3.8			141.8	142.6	-0.16	-0.18	Valve Adjustment: High Temp, Barely Open
H-2273W	8/5/2026 7:10:00 AM					42						AirTech Lab
H-2273W	8/5/2026 7:10:00 AM						6100					AirTech Lab; [User entered 0.61%]
H-2273W	8/5/2026 9:37:15 AM	24.6	43.3	0.0	32.1			116.4	116.4	-1.32	-1.29	,
H-2273W	8/11/2026 8:45:00 AM					71						AirTech Lab
H-2273W	8/11/2026 8:45:00 AM						9300					AirTech Lab; [User entered 0.93%]
H-2273W	8/17/2026 9:56:01 AM	21.6	35.4	0.0	43.0			127.5	127.3	-1.25	-1.14	Valve Adjustment: Decreased Flow/Vacuum