

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init Flow<br>[scfm] | Adj Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                        |
|------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|---------------------|--------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|-----------------------------------------------------------------------------------------------------------------|
| A-01       | 8/5/2026 7:45:50 AM   | 59.5       | 35.7       | 0.6       | 4.2            |                         |                         | 1.7     | 7.0          | 84.4                 | 84.4                | -25.19                       | -25.15                      | 0.0                 | 0.0                |                              |                             |                           |                              | 28.73                  | 1168         | 34.4311913 | -118.6437667 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less                                                             |
| A-02       | 8/5/2026 7:52:54 AM   | 57.2       | 41.1       | 0.0       | 1.7            |                         |                         | 1.4     | 0.0          | 95.7                 | 95.7                | -24.39                       | -24.41                      | 0.0                 | 0.0                |                              |                             |                           |                              | 28.69                  | 1168         | 34.4315983 | -118.6433197 | No Adjustment Made,No Flow Measurement                                                                          |
| A-03       | 8/5/2026 7:55:16 AM   | 52.6       | 40.1       | 0.1       | 7.2            |                         |                         | 1.3     | 72.0         | 92.8                 | 92.9                | -18.21                       | -17.72                      | 0.0                 | 0.0                |                              |                             |                           |                              | 28.7                   | 1207         | 34.4319538 | -118.6428290 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,No Flow Measurement                                         |
| A-04       | 8/5/2026 7:57:37 AM   | 57.1       | 40.4       | 0.1       | 2.4            |                         |                         | 1.4     | 24.0         | 82.6                 | 82.6                | -17.52                       | -17.54                      | 0.0                 | 0.0                |                              |                             |                           |                              | 28.69                  | 1191         | 34.4321917 | -118.6422072 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less,No Flow Measurement                                         |
| A-05       | 8/5/2026 8:00:43 AM   | 55.8       | 40.4       | 0.1       | 3.7            |                         |                         | 1.4     | 37.0         | 87.9                 | 88.1                | -23.74                       | -23.36                      | 0.0                 | 0.0                |                              |                             |                           |                              | 28.69                  | 1188         | 34.4324740 | -118.6416590 | No Adjustment Made,No Flow Measurement                                                                          |
| B-01       | 8/5/2026 10:11:56 AM  | 22.8       | 24.6       | 0.0       | 52.6           |                         |                         | 0.9     | 0.0          | 89.3                 | 86.4                | -0.35                        | -1.19                       | 0.3                 | 3.2                | 0.023                        | 2.648                       | -19.88                    | -20.26                       | 28.68                  | 1225         | 34.4338893 | -118.6396202 | Valve Adjustment: NSPS/EG CAI, NSPS/EG CAC, No Flow Measurement, Increased Flow/Vacuum, Barely Open             |
| B-02R      | 8/5/2026 9:54:46 AM   | 42.0       | 32.8       | 1.0       | 24.2           |                         |                         | 1.3     | 25.0         | 94.0                 | 83.8                | -0.28                        | -3.62                       | 0.2                 | 3.7                | 0.002                        | 1.442                       | -20.46                    | -20.07                       | 28.67                  | 1235         | 34.4335662 | -118.6394910 | Valve Adjustment: NSPS/EG CAI, NSPS/EG CAC, No Flow Measurement, Increased Flow/Vacuum                          |
| B-02R      | 8/5/2026 10:05:18 AM  | 35.5       | 28.3       | 4.7       | 31.6           |                         |                         | 1.3     | 6.8          | 82.6                 | 81.8                | -2.24                        | -2.37                       | 2.2                 | 2.3                | 0.504                        | 0.559                       | -20.13                    | -20.22                       | 28.66                  | 1233         | 34.4335717 | -118.6395180 |                                                                                                                 |
| B-03R      | 8/5/2026 9:42:23 AM   | 34.5       | 33.5       | 0.0       | 32.1           |                         |                         | 1.0     | 0.0          | 87.5                 | 88.5                | -0.89                        | -0.88                       | 2.6                 | 2.6                | 0.706                        | 0.717                       | -19.16                    | -19.27                       | 28.68                  | 1229         | 34.4337923 | -118.6388067 |                                                                                                                 |
| B-05       | 8/5/2026 9:34:32 AM   | 26.5       | 32.3       | 0.2       | 41.0           |                         |                         | 0.8     | 170.8        | 94.3                 | 94.3                | -0.49                        | -0.48                       | 6.5                 | 6.3                | 0.256                        | 0.240                       | -19.63                    | -19.61                       | 28.68                  | 1229         | 34.4336383 | -118.6382570 |                                                                                                                 |
| B-06       | 8/20/2026 9:16:11 AM  | 26.3       | 27.9       | 0.0       | 45.8           |                         |                         | 0.9     | 0.0          | 83.7                 | 83.7                | -0.81                        | -0.81                       | 5.6                 | 5.6                | 0.608                        | 0.613                       | -17.25                    | -17.25                       | 28.79                  | 1225         | 34.4340123 | -118.6377370 | Valve Adjustment: Audible Flow                                                                                  |
| B-06       | 8/25/2026 11:07:03 AM | 26.4       | 28.6       | 0.0       | 45.0           |                         |                         | 0.9     | 0.0          | 81.5                 | 81.5                | -0.75                        | -0.75                       | 7.2                 | 7.2                | 0.305                        | 0.310                       | -17.59                    | -17.57                       | 28.73                  | 1225         | 34.4339834 | -118.6377565 |                                                                                                                 |
| B-07R      | 8/20/2026 8:55:48 AM  | 41.7       | 34.7       | 0.0       | 23.6           |                         |                         | 1.2     | 0.0          | 96.5                 | 97.0                | -0.53                        | -0.44                       | 4.3                 | 2.0                | 4.731                        | 1.058                       | -13.91                    | -16.13                       | 28.78                  | 1211         | 34.4342722 | -118.6374218 | Valve Adjustment: Audible Flow, Decreased Flow/Vacuum                                                           |
| B-07R      | 8/25/2026 10:37:11 AM | 43.9       | 35.0       | 0.0       | 21.1           |                         |                         | 1.3     | 0.0          | 91.3                 | 91.5                | -0.40                        | -0.39                       | 2.2                 | 2.3                | 1.240                        | 1.303                       | -19.18                    | -18.91                       | 28.74                  | 1213         | 34.4342631 | -118.6374381 |                                                                                                                 |
| B-08       | 8/20/2026 9:24:49 AM  | 0.2        | 2.3        | 18.1      | 79.4           |                         |                         | 0.1     | 4.4          | 93.6                 | 94.6                | -16.75                       | -16.83                      | 0.1                 | 0.2                | 0.003                        | 0.013                       | -16.72                    | -16.89                       | 28.78                  | 1233         | 34.4337665 | -118.6373512 | Valve Adjustment: NSPS/EG CAI, High O2, Decreased Flow/Vacuum, Barely Open, Surging Liquid in Well (Watered In) |
| B-08       | 8/20/2026 9:25:57 AM  | 0.1        | 1.8        | 17.8      | 80.3           |                         |                         | 0.1     | 4.5          | 95.3                 | 95.3                | -16.75                       | -16.75                      | 0.2                 | 0.2                | 0.011                        | 0.007                       | -16.66                    | -16.61                       | 28.78                  | 1228         | 34.4337687 | -118.6373438 |                                                                                                                 |
| B-08       | 8/25/2026 11:12:51 AM | 0.0        | 0.8        | 21.2      | 78.0           |                         |                         | 0.0     | 3.7          | 84.6                 | 84.8                | -17.82                       | -17.82                      | 0.1                 | 0.1                | 0.001                        | 0.004                       | -17.54                    | -17.54                       | 28.71                  | 1222         | 34.4337569 | -118.6373428 | Valve Adjustment: NSPS/EG CAI, No Flow Measurement, High O2                                                     |
| B-09       | 8/20/2026 8:50:04 AM  | 34.5       | 33.1       | 0.0       | 32.4           |                         |                         | 1.0     | 0.0          | 96.8                 | 96.8                | -0.42                        | -0.42                       |                     |                    | 0.417                        | 0.414                       | -17.13                    | -17.10                       | 28.79                  | 1215         | 34.4342142 | -118.6370530 | Valve Adjustment: Barely Open                                                                                   |
| B-09       | 8/25/2026 10:33:23 AM | 36.0       | 33.9       | 0.0       | 30.1           |                         |                         | 1.1     | 0.0          | 94.6                 | 94.6                | -0.41                        | -0.41                       |                     |                    | 0.413                        | 0.415                       | -19.91                    | -19.85                       | 28.72                  | 1218         | 34.4341988 | -118.6370492 |                                                                                                                 |
| B-10       | 8/20/2026 8:44:25 AM  | 27.3       | 31.0       | 0.0       | 41.7           |                         |                         | 0.9     | 0.0          | 92.6                 | 92.7                | -0.29                        | -0.29                       |                     |                    | 0.291                        | 0.288                       | -16.73                    | -16.89                       | 28.78                  | 1226         | 34.4340117 | -118.6365563 | Valve Adjustment: Barely Open                                                                                   |
| B-10       | 8/25/2026 10:29:12 AM | 29.4       | 28.9       | 0.0       | 41.7           |                         |                         | 1.0     | 0.0          | 92.6                 | 92.7                | -0.27                        | -0.27                       |                     |                    | 0.272                        | 0.270                       | -19.60                    | -19.85                       | 28.71                  | 1229         | 34.4340131 | -118.6365516 |                                                                                                                 |
| B-11       | 8/3/2026 9:07:32 AM   | 41.4       | 35.5       | 0.0       | 23.1           |                         |                         | 1.2     | 0.0          | 98.3                 | 98.4                | -0.17                        | -0.17                       | 11.5                | 11.7               | 0.344                        | 0.358                       | -9.97                     | -10.03                       | 28.64                  | 1135         | 34.4348202 | -118.6369032 |                                                                                                                 |
| B-12       | 8/20/2026 9:09:34 AM  | 18.7       | 27.6       | 1.4       | 52.3           |                         |                         | 0.7     | 37.4         | 96.5                 | 97.0                | -0.76                        | -0.52                       | 9.4                 | 3.5                | 9.394                        | 1.288                       | -17.20                    | -17.26                       | 28.78                  | 1222         | 34.4340382 | -118.6385348 | Valve Adjustment: Audible Flow, Decreased Flow/Vacuum                                                           |
| B-12       | 8/25/2026 10:51:57 AM | 19.2       | 26.7       | 1.6       | 52.5           |                         |                         | 0.7     | 32.8         | 94.4                 | 95.9                | -0.90                        | -2.86                       | 8.6                 | 4.4                | 19.272                       | 4.933                       | -18.84                    | -18.87                       | 28.71                  | 1224         | 34.4340603 | -118.6385278 | Valve Adjustment: Orifice Plate Changed (See OP Log)                                                            |
| B-12       | 8/25/2026 10:54:18 AM | 21.3       | 28.6       | 0.0       | 50.1           |                         |                         | 0.7     | 0.0          | 95.8                 | 96.2                | -2.93                        | -2.93                       | 27.5                | 27.7               | 4.671                        | 4.735                       | -18.47                    | -18.29                       | 28.71                  | 1230         | 34.4340573 | -118.6385304 |                                                                                                                 |
| B-13       | 8/20/2026 9:00:58 AM  | 34.8       | 33.8       | 0.0       | 31.4           |                         |                         | 1.0     | 0.0          | 91.2                 | 91.2                | -0.41                        | -0.41                       | 10.6                | 10.0               | 0.023                        | 0.020                       | -18.02                    | -17.96                       | 28.79                  | 1220         | 34.4344122 | -118.6379020 | Valve Adjustment: Barely Open                                                                                   |
| B-13       | 8/25/2026 10:41:49 AM | 36.4       | 31.3       | 0.0       | 32.3           |                         |                         | 1.2     | 0.0          | 90.9                 | 90.9                | -0.84                        | -0.85                       |                     |                    | 0.846                        | 0.842                       | -20.24                    | -20.29                       | 28.71                  | 1221         | 34.4344215 | -118.6379023 |                                                                                                                 |
| B-14       | 8/3/2026 9:14:35 AM   | 36.3       | 33.4       | 0.0       | 30.3           |                         |                         | 1.1     | 0.0          | 99.4                 | 99.7                | -1.13                        | -1.12                       | 8.0                 | 7.9                | 6.779                        | 6.659                       | -9.39                     | -9.25                        | 28.66                  | 1141         | 34.4349285 | -118.6370613 |                                                                                                                 |
| C-03       | 8/5/2026 7:49:08 AM   | 51.5       | 37.0       | 1.5       | 10.0           |                         |                         | 1.4     | 6.7          | 73.1                 | 74.2                | -24.37                       | -24.42                      | 0.0                 | 0.0                |                              |                             |                           |                              | 28.7                   | 1161         | 34.4314323 | -118.6435638 | No Adjustment Made,                                                                                             |
| C-07       | 8/28/2026 9:44:23 AM  | 50.9       | 40.8       | 0.2       | 8.1            |                         |                         | 1.2     | 40.5         | 100.7                | 100.7               | -17.91                       | -17.90                      |                     |                    | 18.412                       | 18.411                      | -17.58                    | -17.56                       | 28.67                  | 1206         | 34.4326388 | -118.6414267 | Well Comment: Hard piped                                                                                        |
| C-08       | 8/17/2026 10:44:05 AM | 10.0       | 9.5        | 15.0      | 65.5           |                         |                         | 1.1     | 4.4          | 105.2                | 107.1               | -18.56                       | -18.58                      |                     |                    | 18.946                       | 18.919                      | -18.24                    | -18.24                       | 28.79                  | 1212         | 34.4336529 | -118.6409013 | Valve Adjustment: NSPS/EG CAI, High O2                                                                          |
| C-08       | 8/20/2026 12:53:10 PM | 8.8        | 8.6        | 15.0      | 67.6           |                         |                         | 1.0     | 4.5          | 111.6                | 114.4               | -16.18                       | -16.26                      |                     |                    | 16.287                       | 16.326                      | -16.07                    | -16.14                       | 28.75                  | 1210         | 34.4336417 | -118.6408650 | Valve Adjustment: Increased Flow/Vacuum                                                                         |
| C-10       | 8/5/2026 8:24:39 AM   | 54.3       | 39.2       | 0.6       | 5.9            |                         |                         | 1.4     | 9.8          | 88.0                 | 88.0                | -21.81                       | -21.82                      | 0.0                 | 0.0                |                              |                             |                           |                              | 28.67                  | 1243         | 34.4347145 | -118.6411735 | Increased Flow/Vacuum, No Flow Measurement                                                                      |
| C-11       | 8/17/2026 4:11:48 PM  | 58.7       | 35.1       | 0.0       | 6.2            |                         |                         | 1.7     | 0.0          | 112.9                | 113.0               | -16.22                       | -16.30                      |                     |                    | 0.048                        | 0.036                       | -16.12                    | -16.15                       | 28.74                  | 1233         | 34.4352344 | -118.6413101 |                                                                                                                 |
| C-11       | 8/21/2026 1:16:42 PM  | 57.3       | 42.7       | 0.0       | 0.0            |                         |                         | 1.3     | 0.0          | 113.0                | 113.0               | -13.55                       | -13.55                      |                     |                    | 0.001                        | 0.000                       | -13.53                    | -13.50                       | 28.75                  | 1220         | 34.4352422 | -118.6413307 |                                                                                                                 |
| C-12       | 8/17/2026 4:25:18 PM  | 58.7       | 37.3       | 0.0       | 4.0            |                         |                         | 1.6     | 0.0          | 102.7                | 103.7               | -14.11                       | -14.08                      | 2.3                 | 2.3                | 0.032                        | 0.033                       | -14.10                    | -14.10                       | 28.74                  | 1220         | 34.4359540 | -118.6408917 |                                                                                                                 |
| C-12       | 8/19/2026 10:42:16 AM | 54.6       | 43.3       | 0.0       | 2.1            |                         |                         | 1.3     | 0.0          | 105.5                | 106.0               | -13.38                       | -13.51                      | 0.9                 | 2.6                | 0.006                        | 0.044                       | -14.42                    | -14.41                       | 28.75                  | 1227         | 34.4359675 | -118.6408902 | Valve Adjustment: Increased Flow/Vacuum                                                                         |
| C-15       | 8/17/2026 4:58:30 PM  | 56.1       | 36.9       | 0.0       | 7.0            |                         |                         | 1.5     | 0.0          | 104.6                | 101.6               | 25.63                        | -13.98                      | 5.6                 | 2.1                | 0.067                        | 0.011                       | -13.87                    | -13.82                       | 28.74                  | 1228         | 34.4362602 | -118.6410767 | Valve Adjustment: NSPS/EG CAI, NSPS/EG CAC, Positive Static Press.                                              |
| C-15       | 8/17/2026 4:59:41 PM  | 55.7       | 36.4       | 0.0       | 7.9            |                         |                         | 1.5     | 0.0          | 102.7                | 102.8               | -14.06                       | -14.10                      | 3.3                 | 4.5                | 0.025                        | 0.047                       | -14.03                    | -14.14                       | 28.74                  | 1227         | 34.4362701 | -118.6410687 |                                                                                                                 |
| C-17B      | 8/18/2026 4:21:29 PM  | 56.5       | 38.3       | 0.0       | 5.2            |                         |                         | 1.5     | 0.0          | 110.6                | 110.6               | -13.77                       | -13.68                      |                     |                    | 13.935                       | 13.894                      | -12.90                    | -12.80                       | 28.71                  | 1213         | 34.4373478 | -118.6419240 |                                                                                                                 |
| C-18       | 8/25/2026 8:37:10 AM  | 56.3       | 40.6       | 0.0       | 3.1            |                         |                         | 1.4     | 0.0          | 95.8                 | 96.0                | -16.10                       | -16.07                      |                     |                    | 16.053                       | 16.045                      | 0.01                      | 0.03                         | 28.78                  | 1243         | 34.4379693 | -118.6425890 | Valve Adjustment: Valve 100% Open, Well Comment: Unable to install system sample port                           |
| C-19       | 8/18/2026 4:33:30 PM  | 56.4       | 38.2       | 0.0       | 5.4            |                         |                         | 1.5     | 0.0          | 111.6                | 111.7               | -13.79                       | -13.85                      |                     |                    | 13.928                       | 13.967                      | -13.61                    | -13.76                       | 28.7                   | 1216         | 34.4375755 | -118.6421566 |                                                                                                                 |
| C-20       | 8/25/2026 8:51:06 AM  | 56.0       | 41.2       | 0.0       | 2.8            |                         |                         | 1.4     | 0.0          | 101.9                | 104.2               | -15.62                       | -15.68                      |                     |                    | 15.677                       | 15.736                      | -15.57                    | -15.57                       | 28.78                  | 1226         | 34.4377775 | -118.6423945 | Valve Adjustment: Valve 100% Open                                                                               |
| C-24       | 8/18/2026 4:28:31 PM  | 1.7        | 1.1        | 19.3      | 77.9           |                         |                         | 1.5     | 4.0          | 122.0                | 122.0               | -13.82                       | -13.80                      |                     |                    | 13.938                       | 13.928                      | -0.01                     | 0.00                         | 28.71                  | 1216         | 34.4375210 | -118.6421359 |                                                                                                                 |
| C-25       | 8/18/2026 4:15:51 PM  | 49.8       | 33.3       | 0.0       | 16.9           |                         |                         | 1.5     | 0.0          | 116.1                | 116.1               | -5.75                        | -5.77                       |                     |                    | 5.880                        | 5.879                       | -5.69                     | -5.68                        | 28.72                  | 1201         | 34.4370850 | -118.6416584 |                                                                                                                 |
| C-26       | 8/18/2026 3:51:55 PM  | 56.9       | 25.3       | 2.9       | 14.9           |                         |                         | 2.2     | 5.1          | 120.0                | 120.0               | -14.23                       | -14.24                      |                     |                    | 14.332                       | 14.347                      | -14.10                    | -14.12                       | 28.74                  | 1221         | 34.4366292 | -118.6412819 |                                                                                                                 |
| C-27       | 8/17/2026 4:32:08 PM  | 0.6        | 3.7        | 19.8      | 75.9           |                         |                         | 0.2     | 3.8          | 103.8                | 104.3               | -14.07                       | -14.12                      | 0.9                 | 0.8                | 0.017                        | 0.013                       | -14.05                    | -14.11                       | 28.74                  | 1213         | 34.4361383 | -118.6409949 | Valve Adjustment: NSPS/EG CAI, High O2                                                                          |
| C-28       | 8/26/2026 11:51:50 AM | 47.9       | 49.6       | 0.0       | 2.5            |                         |                         | 1.0     | 0.0          | 108.3                | 105.2               | 0.80                         | -6.04                       | 0.5                 | 4.4                | 0.052                        | 5.167                       | -16.94                    | -17.92                       | 28.67                  | 1239         | 34.4354484 | -118.6413601 | Valve Adjustment: NSPS/EG CAI, Orifice Plate Changed (See OP Log), Positive Static Press.                       |
| C-28       | 8/26/2026 11:52:48 AM | 47.5       | 46.7       | 0.0       | 5.8            |                         |                         | 1.0     | 0.0          | 105.3                | 105.4               | -6.82                        | -6.84                       | 4.1                 | 4.2                | 4.549                        | 4.615                       | -17.25                    | -17.                         |                        |              |            |              |                                                                                                                 |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name  | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init Flow<br>[scfm] | Adj Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                       |                                   |
|-------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|---------------------|--------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|--------------------------------------------------------------------------------------------------------------------------------|-----------------------------------|
| C-29        | 8/5/2026 8:31:37 AM   | 44.1       | 49.7       | 0.1       | 6.1            |                         |                         | 0.9     | 61.0         | 109.1                | 109.3               | -7.41                        | -7.38                       | 0.0                 | 0.0                | 7.367                        | 7.364                       |                           |                              | 28.67                  | 1217         | 34.4348520 | -118.6412168 | No Flow Measurement,No Adjustment Made                                                                                         |                                   |
| C-30        | 8/17/2026 10:35:47 AM | 55.0       | 38.9       | 0.0       | 6.1            |                         |                         | 1.4     | 0.0          | 128.0                | 128.0               | -3.92                        | -3.91                       | 4.0                 | 5.6                | 0.101                        | 0.201                       | -18.20                    | -18.01                       | 28.78                  | 1235         | 34.4342685 | -118.6412715 |                                                                                                                                |                                   |
| CV-02       | 8/5/2026 8:15:36 AM   | 26.3       | 30.7       | 0.0       | 43.0           |                         |                         | 0.9     | 0.0          | 122.5                | 122.5               | -1.49                        | -1.39                       | 0.0                 | 0.0                | -0.061                       | -0.058                      | -22.63                    |                              | 28.64                  | 1201         | 34.4335480 | -118.6413545 |                                                                                                                                |                                   |
| CV-03       | 8/5/2026 8:10:33 AM   | 38.1       | 35.6       | 0.0       | 26.3           |                         |                         | 1.1     | 0.0          | 117.3                | 118.9               | -11.15                       | -11.22                      | 24.0                | 22.9               | 3.634                        | 3.305                       | -22.76                    |                              | 28.66                  | 1227         | 34.4333105 | -118.6414940 |                                                                                                                                |                                   |
| CV-04       | 8/5/2026 8:07:49 AM   | 30.8       | 29.9       | 2.3       | 37.0           |                         |                         | 1.0     | 16.1         | 127.9                | 127.4               | -3.71                        | -2.45                       | 13.3                | 23.1               | 0.053                        | 0.154                       |                           |                              | 28.67                  | 1224         | 34.4331852 | -118.6417118 |                                                                                                                                |                                   |
| CV-05       | 8/5/2026 10:35:05 AM  | 55.0       | 42.7       | 0.0       | 2.3            |                         |                         | 1.3     | 0.0          | 108.1                | 108.0               | -21.42                       | -21.59                      | 1.7                 | 0.9                | 0.061                        | 0.018                       | -21.70                    | -21.82                       | 28.68                  | 1196         | 34.4328312 | -118.6421977 |                                                                                                                                |                                   |
| CV-06       | 8/13/2026 1:22:51 PM  | 54.5       | 40.2       | 0.0       | 5.3            |                         |                         | 1.4     | 0.0          | 98.9                 | 98.9                | -14.40                       | -14.22                      | 3.8                 | 4.3                | 0.091                        | 0.119                       | -15.68                    | -15.68                       | 28.66                  | 1204         | 34.4326517 | -118.6428470 | Valve Adjustment:Valve 100% Open                                                                                               |                                   |
| CV-108-52   | 8/4/2026 7:50:00 AM   |            |            |           |                |                         | 9400                    |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                | AirTech Lab; [User entered 0.94%] |
| CV-108-52   | 8/4/2026 7:50:00 AM   |            |            |           |                | 160                     |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                | AirTech Lab                       |
| CV-108-52   | 8/5/2026 8:14:59 AM   | 45.8       | 52.3       | 0.0       | 1.9            |                         |                         | 0.9     | 0.0          | 86.0                 | 86.5                | -1.33                        | -1.20                       |                     |                    | 0.116                        | 0.012                       | -1.60                     |                              | 28.6                   | 1286         | 34.4333513 | -118.6507533 |                                                                                                                                |                                   |
| CV-108-52   | 8/17/2026 10:15:53 AM | 17.9       | 69.8       | 0.0       | 12.3           |                         |                         | 0.3     | 0.0          | 103.0                | 103.3               | 7.41                         | 7.42                        |                     |                    | 0.000                        | 0.074                       | 7.73                      | 7.88                         | 28.75                  | 1272         | 34.4334037 | -118.6506953 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Valve 100% Open                                                            |                                   |
| CV-108-52   | 8/17/2026 10:16:18 AM | 18.0       | 70.0       | 0.0       | 12.0           |                         |                         | 0.3     | 0.0          | 103.5                | 103.6               | 6.94                         | 6.79                        |                     |                    | 0.117                        | 0.049                       | 7.50                      | 7.45                         | 28.75                  | 1272         | 34.4334037 | -118.6506953 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Valve 100% Open                                                            |                                   |
| CV-113      | 8/10/2026 8:00:00 AM  |            |            |           |                |                         | 0                       |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                | AirTech Lab; [User entered 0%]    |
| CV-113      | 8/10/2026 8:00:00 AM  |            |            |           |                | 35                      |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                | AirTech Lab                       |
| CV-113      | 8/11/2026 9:30:06 AM  | 28.0       | 48.2       | 4.0       | 19.8           |                         |                         | 0.6     | 5.0          | 102.8                | 103.2               | -0.59                        | -0.58                       | 1.4                 | 1.1                | 0.012                        | 0.007                       | -4.58                     | -2.49                        | 28.63                  | 1321         | 34.4369388 | -118.6467468 | Valve Adjustment:Barely Open                                                                                                   |                                   |
| CV-113      | 8/14/2026 8:10:00 AM  |            |            |           |                |                         | 1500                    |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                | AirTech Lab; [User entered 0.15%] |
| CV-113      | 8/14/2026 8:10:00 AM  |            |            |           |                | 33                      |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                | AirTech Lab                       |
| CV-113      | 8/18/2026 9:46:41 AM  | 31.1       | 41.2       | 4.4       | 23.3           |                         |                         | 0.8     | 5.3          | 110.0                | 110.0               | -0.83                        | -0.81                       | 2.3                 | 1.8                | 0.032                        | 0.021                       | -1.20                     | -1.76                        | 28.64                  | 1331         | 34.4369662 | -118.6467242 | Valve Adjustment:Barely Open,Surging Liquid in Header                                                                          |                                   |
| CV-114      | 8/3/2026 8:11:24 AM   | 0.5        | 76.8       | 0.0       | 22.7           |                         |                         | 0.0     | 0.0          | 190.8                | 190.9               | -5.98                        | -5.39                       |                     |                    | 6.228                        | 5.732                       | 0.03                      | 0.06                         | 28.46                  | 1350         | 34.4367324 | -118.6476453 | Valve Adjustment:No Flow Measurement,High Temp                                                                                 |                                   |
| CV-114      | 8/3/2026 8:15:00 AM   |            |            |           |                |                         | 158900                  |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                | AtmAA; [User entered 15.89%]      |
| CV-114      | 8/3/2026 8:15:00 AM   |            |            |           |                | 3090                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                | AtmAA                             |
| CV-114      | 8/6/2026 8:05:00 AM   |            |            |           |                |                         | 120000                  |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                | AirTech Lab; [User entered 12%]   |
| CV-114      | 8/6/2026 8:05:00 AM   |            |            |           |                | 1800                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                | AirTech Lab                       |
| CV-114      | 8/10/2026 8:18:57 AM  | 1.1        | 74.5       | 0.0       | 24.4           |                         |                         | 0.0     | 0.0          | 190.9                | 190.9               | -4.53                        | -4.43                       |                     |                    | 4.577                        | 4.461                       | 0.34                      | 0.34                         | 28.57                  | 1366         | 34.4367489 | -118.6476473 | Valve Adjustment:No Flow Measurement,High Temp                                                                                 |                                   |
| CV-114      | 8/10/2026 8:25:00 AM  |            |            |           |                | 4420                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                | AtmAA                             |
| CV-114      | 8/17/2026 7:45:33 AM  | 3.1        | 79.9       | 0.0       | 17.0           |                         |                         | 0.0     | 0.0          | 190.3                | 190.6               | -4.98                        | -5.05                       |                     |                    | 5.091                        | 5.243                       | -6.15                     | -6.06                        | 28.64                  | 1349         | 34.4367352 | -118.6476429 | Valve Adjustment:No Flow Measurement,High Temp                                                                                 |                                   |
| CV-114      | 8/17/2026 7:50:00 AM  |            |            |           |                | 2570                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                | AtmAA                             |
| CV-114      | 8/24/2026 8:12:00 AM  | 3.7        | 81.3       | 0.0       | 15.0           |                         |                         | 0.0     | 0.0          | 191.4                | 191.4               | -3.98                        | -3.84                       |                     |                    | 4.091                        | 3.715                       | -6.17                     | -5.33                        | 28.63                  | 1356         | 34.4367109 | -118.6476455 | Valve Adjustment:No Flow Measurement,High Temp                                                                                 |                                   |
| CV-114      | 8/31/2026 7:59:29 AM  | 1.2        | 84.0       | 0.0       | 14.8           |                         |                         | 0.0     | 0.0          | 190.1                | 190.1               | -4.81                        | -4.71                       |                     |                    | 4.848                        | 4.737                       | -5.92                     | -6.21                        | 28.57                  | 1333         | 34.4367268 | -118.6476201 | Valve Adjustment:No Flow Measurement,High Temp                                                                                 |                                   |
| CV-1424     | 8/11/2026 1:54:10 PM  | 50.0       | 36.8       | 0.0       | 13.2           |                         |                         | 1.4     | 0.0          | 105.5                | 105.5               | -4.59                        | -4.59                       | 29.2                | 29.2               | 5.393                        | 5.398                       | -20.20                    | -20.34                       | 28.62                  | 1394         | 34.4351415 | -118.6450775 |                                                                                                                                |                                   |
| CV-1532A    | 8/4/2026 7:55:00 AM   |            |            |           |                |                         | 140000                  |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                | AirTech Lab; [User entered 14%]   |
| CV-1532A    | 8/4/2026 7:55:00 AM   |            |            |           |                | 1200                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                | AirTech Lab                       |
| CV-1532A    | 8/14/2026 8:47:40 AM  | 0.7        | 76.7       | 0.8       | 21.8           |                         |                         | 0.0     | 27.3         | 177.7                | 178.5               | -4.73                        | -4.98                       |                     |                    | 4.712                        | 5.120                       | -4.83                     | -5.71                        | 28.67                  | 1292         | 34.4338738 | -118.6508187 | Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)                |                                   |
| CV-1532A    | 8/14/2026 8:48:40 AM  | 0.7        | 81.4       | 0.2       | 17.7           |                         |                         | 0.0     | 88.5         | 179.2                | 179.6               | -8.03                        | -5.19                       |                     |                    | 8.291                        | 5.544                       | -7.58                     | -5.08                        | 28.67                  | 1288         | 34.4338805 | -118.6508432 | Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed |                                   |
| CV-1532A    | 8/17/2026 9:54:52 AM  | 4.7        | 80.2       | 0.1       | 15.0           |                         |                         | 0.1     | 150.0        | 185.4                | 185.8               | -4.46                        | -4.26                       | 0.0                 | 0.0                | 4.381                        | 5.246                       | -7.83                     |                              | 28.71                  | 1198         | 34.4338978 | -118.6509243 | No Flow Measurement,High Temp,No Adjustment Made                                                                               |                                   |
| CV-1532A    | 8/17/2026 9:56:00 AM  |            |            |           |                | 1235                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                | AtmAA                             |
| CV-1532A    | 8/20/2026 10:40:38 AM | 0.5        | 64.0       | 1.5       | 34.0           |                         |                         | 0.0     | 22.7         | 183.4                | 181.9               | -2.93                        | -3.15                       |                     |                    | 2.896                        | 3.075                       | -3.06                     | -3.39                        | 28.69                  | 1281         | 34.4338895 | -118.6508172 | Valve Adjustment:Increased Flow/Vacuum                                                                                         |                                   |
| CV-1532A    | 8/25/2026 10:00:55 AM | 19.7       | 68.9       | 0.4       | 11.0           |                         |                         | 0.3     | 27.5         | 133.2                | 132.2               | -4.93                        | -5.08                       |                     |                    | 4.879                        | 5.139                       | -5.21                     | -4.70                        | 28.71                  | 1280         | 34.4338837 | -118.6508412 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed                                          |                                   |
| CV-1532A    | 8/25/2026 10:03:58 AM | 19.2       | 67.4       | 0.6       | 12.8           |                         |                         | 0.3     | 21.3         | 181.2                | 181.6               | -5.21                        | -5.57                       |                     |                    | 5.298                        | 5.603                       | -5.72                     | -6.19                        | 28.71                  | 1282         | 34.4338853 | -118.6508312 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed                                          |                                   |
| CV-1532A    | 8/25/2026 10:06:21 AM | 23.2       | 70.6       | 0.1       | 6.1            |                         |                         | 0.3     | 61.0         | 183.1                | 183.1               | -3.42                        | -2.94                       |                     |                    | 3.477                        | 2.965                       | -2.63                     | -2.29                        | 28.7                   | 1287         | 34.4338722 | -118.6508382 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed                                          |                                   |
| CV-1534A-P1 | 8/14/2026 8:50:04 AM  | 1.8        | 82.3       | 0.0       | 15.9           |                         |                         | 0.0     | 0.0          | 148.8                | 148.9               | -9.73                        | -9.57                       |                     |                    | 9.772                        | 9.662                       | 0.00                      | 0.02                         | 28.75                  | 1278         | 34.4336423 | -118.6507873 | Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)                            |                                   |
| CV-1534A-P1 | 8/14/2026 8:56:46 AM  | 1.7        | 82.9       | 0.0       | 15.4           |                         |                         | 0.0     | 0.0          | 146.0                | 150.5               | -10.01                       | -9.32                       |                     |                    | 10.131                       | 9.362                       | 0.06                      | 0.04                         | 28.75                  | 1280         | 34.4336542 | -118.6507990 |                                                                                                                                |                                   |
| CV-1534A-P1 | 8/17/2026 10:00:00 AM |            |            |           |                | 1500                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                | AtmAA                             |
| CV-1534A-P1 | 8/17/2026 12:16:38 PM | 12.5       | 82.6       | 0.7       | 4.2            |                         |                         | 0.2     | 6.0          | 152.0                | 149.9               | -4.77                        | -4.35                       | 0.0                 | 0.0                | 6.922                        | 7.819                       | -0.02                     |                              | 28.72                  | 1181         | 34.4293663 | -118.6445060 | No Flow Measurement,High Temp                                                                                                  |                                   |
| CV-1534A-P1 | 8/25/2026 9:59:08 AM  | 19.3       | 75.3       | 0.0       | 5.4            |                         |                         | 0.3     | 0.0          | 145.5                | 144.9               | -5.71                        | -6.50                       |                     |                    | 4.581                        | 7.068                       | 0.67                      | 0.60                         | 28.68                  | 1285         | 34.4336402 | -118.6507820 | Valve Adjustment:Decom Well (Temporary),No Flow Measurement,High Temp                                                          |                                   |
| CV-1535     | 8/5/2026 8:08:53 AM   | 43.4       | 49.3       | 0.0       | 7.3            |                         |                         | 0.9     | 0.0          | 121.5                | 121.4               | -2.10                        | -2.00                       | 0.0                 | 0.0                | 0.588                        | 0.448                       | -17.49                    |                              | 28.57                  | 1302         | 34.4333782 | -118.6503483 |                                                                                                                                |                                   |
| CV-1535     | 8/13/2026 9:30:00 AM  |            |            |           |                |                         | 7000                    |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                | AirTech Lab; [User entered 0.70%] |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init<br>Flow<br>[scfm] | Adj<br>Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                |
|------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|------------------------|-----------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|-------------------------------------------------------------------------------------------------------------------------|
| CV-1535    | 8/13/2026 9:30:00 AM  |            |            |           |                | 55                      |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab                                                                                                             |
| CV-1535    | 8/17/2026 10:19:00 AM | 53.2       | 45.9       | 0.0       | 0.9            |                         |                         | 1.2     | 0.0          | 124.0                | 124.1               | -1.20                        | -1.21                       |                        |                       | 1.269                        | 1.265                       | -11.25                    | -11.23                       | 28.71                  | 1306         | 34.433293  | -118.6503482 | Valve Adjustment:Audible Flow,Increased Flow/Vacuum                                                                     |
| CV-1601D   | 8/11/2026 10:03:00 AM | 55.3       | 42.6       | 0.0       | 2.1            |                         |                         | 1.3     | 0.0          | 116.0                | 116.4               | -1.26                        | -1.59                       | 8.6                    | 15.1                  | 1.572                        | 4.865                       | -18.96                    | -18.74                       | 28.68                  | 1322         | 34.4310858 | -118.6486657 | Valve Adjustment:Decreased Flow/Vacuum                                                                                  |
| CV-1601D   | 8/17/2026 10:00:38 AM | 43.2       | 42.9       | 0.0       | 13.9           |                         |                         | 1.0     | 0.0          | 116.8                | 116.3               | -1.58                        | -1.34                       | 15.4                   | 12.0                  | 5.035                        | 3.041                       | -18.97                    | -18.82                       | 28.68                  | 1319         | 34.4311178 | -118.6486513 | Valve Adjustment:Decreased Flow/Vacuum                                                                                  |
| CV-1601D   | 8/17/2026 10:02:16 AM | 42.6       | 43.3       | 0.0       | 14.1           |                         |                         | 1.0     | 0.0          | 116.3                | 116.2               | -1.32                        | -1.33                       | 11.8                   | 11.9                  | 2.921                        | 2.984                       | -18.10                    | -18.79                       | 28.71                  | 1308         | 34.4311027 | -118.6486667 | Valve Adjustment:Audible Flow,Increased Flow/Vacuum                                                                     |
| CV-1601S   | 8/11/2026 9:58:27 AM  | 50.9       | 42.1       | 0.0       | 7.0            |                         |                         | 1.2     | 0.0          | 114.6                | 116.7               | -0.97                        | -1.21                       | 2.9                    | 8.8                   | 0.171                        | 1.626                       | -18.78                    | -18.85                       | 28.68                  | 1322         | 34.4310877 | -118.6486650 | Valve Adjustment:Decreased Flow/Vacuum                                                                                  |
| CV-1601S   | 8/17/2026 9:52:38 AM  | 42.2       | 41.4       | 0.0       | 16.4           |                         |                         | 1.0     | 0.0          | 116.9                | 116.4               | -1.73                        | -1.61                       | 9.0                    | 6.2                   | 1.696                        | 0.803                       | -18.52                    | -18.62                       | 28.69                  | 1309         | 34.4311228 | -118.6486503 | Valve Adjustment:Decreased Flow/Vacuum                                                                                  |
| CV-1601S   | 8/17/2026 9:54:50 AM  | 40.5       | 43.3       | 0.0       | 16.1           |                         |                         | 0.9     | 0.0          | 116.4                | 116.1               | -1.52                        | -1.51                       | 6.2                    | 6.2                   | 0.808                        | 0.797                       | -18.87                    | -18.75                       | 28.68                  | 1305         | 34.4311197 | -118.6486558 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum                                                            |
| CV-1604    | 8/18/2026 9:59:44 AM  | 47.1       | 44.0       | 0.0       | 8.9            |                         |                         | 1.1     | 0.0          | 130.6                | 129.5               | -2.05                        | -1.73                       | 1.3                    | 0.6                   | 0.037                        | 0.008                       | -20.26                    | -19.74                       | 28.7                   | 1262         | 34.4321715 | -118.6450253 | Valve Adjustment:NSPS/EG CAC                                                                                            |
| CV-1604    | 8/18/2026 10:00:04 AM | 47.0       | 44.2       | 0.0       | 8.8            |                         |                         | 1.1     | 0.0          | 129.0                | 129.0               | -1.68                        | -1.67                       | 0.5                    | 0.5                   | 0.006                        | 0.006                       | -20.15                    | -20.03                       | 28.69                  | 1276         | 34.4321688 | -118.6450310 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)                               |
| CV-1701D   | 8/20/2026 2:25:02 PM  | 25.0       | 65.5       | 0.9       | 8.6            |                         |                         | 0.4     | 9.6          | 122.5                | 124.1               | -4.89                        | -4.73                       | 0.8                    | 0.6                   | 0.157                        | 0.094                       | -14.71                    | -14.76                       | 28.6                   | 1287         | 34.4335652 | -118.6433388 | Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum,Barely Open                         |
| CV-1701S   | 8/20/2026 2:20:25 PM  | 28.8       | 68.9       | 0.0       | 2.3            |                         |                         | 0.4     | 0.0          | 130.9                | 140.2               | 1.50                         | -0.39                       | 3.5                    | 5.6                   | 0.077                        | 0.207                       | -14.87                    | -14.88                       | 28.57                  | 1291         | 34.4335740 | -118.6433108 | Valve Adjustment:NSPS/EG CAC,High Temp,Barely Open,Surging Liquid in Header                                             |
| CV-1701S   | 8/20/2026 2:21:41 PM  | 28.5       | 69.1       | 0.0       | 2.4            |                         |                         | 0.4     | 0.0          | 142.1                | 142.1               | -0.89                        | -0.89                       | 4.1                    | 4.2                   | 0.109                        | 0.116                       | -14.96                    | -14.51                       | 28.6                   | 1291         | 34.4336033 | -118.6433030 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open                                                                      |
| CV-1901    | 8/3/2026 9:10:01 AM   | 24.7       | 67.4       | 0.3       | 7.6            |                         |                         | 0.4     | 25.3         | 121.2                | 119.8               | -7.38                        | -1.03                       | 1.3                    | 1.3                   | 0.035                        | 0.035                       | -10.09                    | -9.85                        | 28.43                  | 1322         | 34.4357168 | -118.6508000 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open                                                                      |
| CV-1901    | 8/17/2026 9:22:23 AM  | 22.4       | 70.5       | 0.1       | 7.0            |                         |                         | 0.3     | 70.0         | 119.7                | 118.4               | -6.37                        | -4.34                       | 0.9                    | 1.3                   | 0.016                        | 0.038                       | -7.48                     | -7.66                        | 28.67                  | 1300         | 34.4357157 | -118.6507873 | AtmAA; [User entered 12.55%]                                                                                            |
| CV-1902A   | 8/4/2026 1:45:00 PM   |            |            |           |                |                         | 125500                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                   |
| CV-1902A   | 8/4/2026 1:45:00 PM   |            |            |           |                | 850                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                   |
| CV-1902A   | 8/4/2026 1:45:01 PM   | 4.0        | 81.1       | 0.0       | 14.9           |                         |                         | 0.0     | 0.0          | 180.4                | 180.2               | 1.81                         | -4.20                       |                        |                       | 0.000                        | 4.110                       | -8.36                     | -8.16                        | 28.59                  | 1315         | 34.4346222 | -118.6502750 | Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Pnumatic Pump Installed |
| CV-1902A   | 8/4/2026 1:45:57 PM   | 2.0        | 76.7       | 0.0       | 21.3           |                         |                         | 0.0     | 0.0          | 179.2                | 179.4               | -4.38                        | -4.34                       |                        |                       | 4.314                        | 4.271                       | -8.26                     | -8.47                        | 28.59                  | 1304         | 34.4346163 | -118.6502890 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed                       |
| CV-1902A   | 8/11/2026 1:30:00 PM  |            |            |           |                | 1720                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                   |
| CV-1902A   | 8/11/2026 1:35:08 PM  | 8.6        | 74.5       | 0.0       | 16.9           |                         |                         | 0.1     | 0.0          | 179.1                | 178.4               | -7.89                        | -7.81                       |                        |                       | 8.180                        | 8.168                       | -8.49                     | -8.59                        | 28.66                  | 1319         | 34.4346236 | -118.6503203 | Valve Adjustment:No Flow Measurement,High Temp                                                                          |
| CV-1902A   | 8/12/2026 8:50:00 AM  |            |            |           |                |                         | 190000                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab; [User entered 19%]                                                                                         |
| CV-1902A   | 8/12/2026 8:50:00 AM  |            |            |           |                | 1100                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab                                                                                                             |
| CV-1902A   | 8/18/2026 1:39:43 PM  | 25.2       | 71.6       | 0.3       | 2.9            |                         |                         | 0.4     | 9.7          | 187.0                | 187.3               | -6.77                        | -6.77                       |                        |                       | 7.137                        | 7.085                       | -7.20                     | -7.11                        | 28.64                  | 1318         | 34.4345855 | -118.6503178 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed                                   |
| CV-1902A   | 8/18/2026 1:45:00 PM  |            |            |           |                | 1360                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                   |
| CV-1902A   | 8/24/2026 1:33:07 PM  | 25.2       | 73.5       | 0.0       | 1.3            |                         |                         | 0.3     | 0.0          | 169.5                |                     | -6.01                        |                             |                        |                       | 6.062                        |                             | -5.82                     |                              | 28.64                  | 1313         | 34.4346063 | -118.6503198 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed                                   |
| CV-1902A   | 8/31/2026 1:58:14 PM  | 1.6        | 72.7       | 0.0       | 25.7           |                         |                         | 0.0     | 0.0          | 167.2                | 168.7               | -5.05                        | -5.05                       |                        |                       | 5.152                        | 5.070                       | -5.31                     | -5.14                        | 28.62                  | 1323         | 34.4345863 | -118.6503093 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed                                   |
| CV-1905    | 8/1/2026 10:04:36 AM  | 52.2       | 45.4       | 0.0       | 2.4            |                         |                         | 1.1     | 0.0          | 116.4                | 116.3               | -9.42                        | -9.45                       | 28.8                   | 29.3                  | 5.446                        | 5.616                       | -21.09                    | -20.67                       | 28.55                  | 1381         | 34.4334950 | -118.6459822 |                                                                                                                         |
| CV-1905    | 8/20/2026 9:52:54 AM  | 50.5       | 44.4       | 0.0       | 5.1            |                         |                         | 1.1     | 0.0          | 116.2                | 116.3               | -8.44                        | -8.62                       | 29.6                   | 29.9                  | 5.716                        | 5.836                       | -19.84                    | -19.75                       | 28.6                   | 1400         | 34.4335025 | -118.6459583 | Valve Adjustment:Increased Flow/Vacuum                                                                                  |
| CV-2001    | 8/5/2026 7:15:00 AM   |            |            |           |                |                         | 16000                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab; [User entered 1.6%]                                                                                        |
| CV-2001    | 8/5/2026 7:15:00 AM   |            |            |           |                | 170                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab                                                                                                             |
| CV-2001    | 8/5/2026 9:13:08 AM   | 10.3       | 75.9       | 2.2       | 11.6           |                         |                         | 0.1     | 5.3          | 82.1                 | 82.1                | -6.52                        | -5.98                       | 16.1                   | 15.5                  | 6.758                        | 6.274                       | -15.60                    |                              | 28.63                  | 1260         | 34.4321848 | -118.6504160 |                                                                                                                         |
| CV-2001    | 8/11/2026 8:35:00 AM  |            |            |           |                |                         | 56000                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab; [User entered 5.6%]                                                                                        |
| CV-2001    | 8/11/2026 8:35:00 AM  |            |            |           |                | 660                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab                                                                                                             |
| CV-2001    | 8/25/2026 1:44:30 PM  | 5.7        | 60.9       | 4.0       | 29.4           |                         |                         | 0.1     | 7.4          | 116.7                | 117.1               | -5.61                        | -6.75                       | 0.0                    | 8.1                   | 0.000                        | 0.086                       | -5.27                     | -6.60                        | 28.62                  | 1262         | 34.4322807 | -118.6505835 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)                                           |
| CV-2002    | 8/5/2026 7:35:00 AM   |            |            |           |                |                         | 79000                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab; [User entered 7.9%]                                                                                        |
| CV-2002    | 8/5/2026 7:35:00 AM   |            |            |           |                | 1600                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab                                                                                                             |
| CV-2002    | 8/6/2026 8:11:00 AM   |            |            |           |                |                         | 93100                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA; [User entered 9.31%]                                                                                             |
| CV-2002    | 8/6/2026 8:11:00 AM   |            |            |           |                | 2865                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                   |
| CV-2002    | 8/6/2026 9:37:47 AM   | 17.8       | 68.5       | 0.3       | 13.4           |                         |                         | 0.3     | 44.7         | 185.7                | 185.7               | -10.76                       | -10.78                      |                        |                       | 11.296                       | 11.365                      | -15.97                    | -16.91                       | 28.68                  | 1294         | 34.4327986 | -118.6511892 | Valve Adjustment:No Flow Measurement,High Temp                                                                          |
| CV-2002    | 8/11/2026 8:30:00 AM  |            |            |           |                |                         | 150000                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab; [User entered 15%]                                                                                         |
| CV-2002    | 8/11/2026 8:30:00 AM  |            |            |           |                | 3500                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab                                                                                                             |
| CV-2002    | 8/13/2026 7:57:34 AM  | 21.5       | 74.7       | 0.0       | 3.8            |                         |                         | 0.3     | 0.0          | 186.0                | 186.0               | -3.03                        | -3.03                       |                        |                       | 3.031                        | 3.052                       | -13.28                    | -12.32                       | 28.64                  | 1275         | 34.4327960 | -118.6511802 | Valve Adjustment:No Flow Measurement,High Temp                                                                          |
| CV-2002    | 8/13/2026 8:05:00 AM  |            |            |           |                | 4725                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                   |
| CV-2002    | 8/20/2026 10:08:08 AM | 47.0       | 53.0       | 0.0       | 0.0            |                         |                         | 0.9     | 0.0          | 187.4                | 187.4               | -5.87                        | -5.73                       |                        |                       | 6.506                        | 6.327                       | -10.04                    | -9.18                        | 28.7                   | 1286         | 34.4328144 | -118.6511753 | Valve Adjustment:No Flow Measurement,High Temp                                                                          |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name  | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init Flow<br>[scfm] | Adj Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                                  |                                  |
|-------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|---------------------|--------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|-------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|
| CV-2002     | 8/26/2026 2:16:28 PM  | 19.8       | 67.1       | 0.5       | 12.6           |                         |                         | 0.3     | 25.2         | 185.6                | 185.8               | -7.08                        | -6.78                       |                     |                    | 6.996                        | 6.893                       | -7.34                     | -7.07                        | 28.57                  | 1289         | 34.4328179 | -118.6511799 | Valve Adjustment:No Flow Measurement,High Temp                                                                                            |                                  |
| CV-2003     | 8/14/2026 9:04:38 AM  | 14.3       | 73.1       | 0.0       | 12.6           |                         |                         | 0.2     | 0.0          | 119.4                | 119.0               | 5.05                         | 5.50                        | 3.7                 | 3.3                | 1.455                        | 1.149                       | 6.13                      | 5.71                         | 28.74                  | 1270         | 34.4334290 | -118.6507230 | Valve Adjustment: NSPS/EG CAI,Positive Static Press.,Surging Liquid in Header,Plugged/Pinched Suspected;Well Comment:Header is watered in |                                  |
| CV-2003     | 8/14/2026 9:06:34 AM  | 14.5       | 73.4       | 0.0       | 12.1           |                         |                         | 0.2     | 0.0          | 120.4                | 119.8               | 5.88                         | 5.88                        | 2.4                 | 2.4                | 0.608                        | 0.626                       | 5.97                      | 5.98                         | 28.74                  | 1271         | 34.4334258 | -118.6507267 |                                                                                                                                           |                                  |
| CV-2003     | 8/17/2026 10:12:34 AM | 18.6       | 70.8       | 0.0       | 10.6           |                         |                         | 0.3     | 0.0          | 124.5                | 123.4               | 8.89                         | 8.86                        | 0.9                 | 1.8                | 0.085                        | 0.352                       | 9.15                      | 8.86                         | 28.74                  | 1272         | 34.4334192 | -118.6507272 | Valve Adjustment: NSPS/EG CAI,Positive Static Press.,Valve 100% Open,Surging Liquid in Header                                             |                                  |
| CV-2003     | 8/17/2026 10:12:58 AM | 18.2       | 71.0       | 0.0       | 10.8           |                         |                         | 0.3     | 0.0          | 124.3                | 124.6               | 7.41                         | 7.41                        | 2.2                 | 2.5                | 0.540                        | 0.653                       | 7.29                      | 7.21                         | 28.74                  | 1280         | 34.4334135 | -118.6507307 | Valve Adjustment: NSPS/EG CAI,Positive Static Press.,Surging Liquid in Header                                                             |                                  |
| CV-2006     | 8/4/2026 1:52:43 PM   | 2.3        | 76.2       | 0.0       | 21.5           |                         |                         | 0.0     | 0.0          | 187.8                | 187.8               | -4.08                        | -4.05                       | 1.8                 | 10.8               | 0.005                        | 0.170                       | -8.64                     | -9.02                        | 28.59                  | 1288         | 34.4352285 | -118.6506548 | Valve Adjustment:No Flow Measurement,High Temp                                                                                            |                                  |
| CV-2006     | 8/4/2026 2:10:00 PM   |            |            |           |                |                         | 109200                  |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AtmAA; [User entered 10.92%]     |
| CV-2006     | 8/4/2026 2:10:00 PM   |            |            |           |                | 1930                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AtmAA                            |
| CV-2006     | 8/11/2026 1:39:57 PM  | 9.7        | 73.0       | 0.0       | 17.3           |                         |                         | 0.1     | 0.0          | 186.9                | 186.9               | -4.39                        | -4.05                       | 9.5                 | 3.0                | 0.131                        | 0.013                       | -8.76                     | -9.12                        | 28.67                  | 1322         | 34.4352342 | -118.6506477 | Valve Adjustment:High Temp                                                                                                                |                                  |
| CV-2006     | 8/18/2026 1:45:05 PM  | 27.5       | 72.4       | 0.1       | 0.0            |                         |                         | 0.4     | 0.0          | 187.2                | 187.2               | -2.74                        | -2.80                       | 7.1                 | 7.5                | 0.074                        | 0.081                       | -6.64                     | -6.65                        | 28.64                  | 1320         | 34.4352117 | -118.6506532 | Valve Adjustment:High Temp                                                                                                                |                                  |
| CV-2006     | 8/18/2026 2:05:00 PM  |            |            |           |                | 3860                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AtmAA                            |
| CV-2006     | 8/24/2026 1:44:47 PM  | 24.4       | 74.8       | 0.0       | 0.8            |                         |                         | 0.3     | 0.0          | 187.7                | 187.6               | -2.15                        | -2.19                       | 5.1                 | 1.3                | 0.038                        | 0.002                       | -5.83                     | -5.83                        | 28.64                  | 1325         | 34.4352098 | -118.6506722 | Valve Adjustment:High Temp                                                                                                                |                                  |
| CV-2006     | 8/31/2026 2:06:15 PM  | 2.9        | 71.3       | 0.0       | 25.8           |                         |                         | 0.0     | 0.0          | 186.8                | 186.9               | -3.55                        | -3.56                       | 4.9                 | 1.4                | 0.035                        | 0.003                       | -5.95                     | -6.01                        | 28.62                  | 1322         | 34.4352173 | -118.6506719 | Valve Adjustment:No Flow Measurement,High Temp                                                                                            |                                  |
| CV-2007     | 8/6/2026 8:30:00 AM   |            |            |           |                |                         | 21000                   |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AirTech Lab; [User entered 2.1%] |
| CV-2007     | 8/6/2026 8:30:00 AM   |            |            |           |                | 300                     |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AirTech Lab                      |
| CV-2007     | 8/11/2026 10:26:06 AM | 25.2       | 55.4       | 0.8       | 18.6           |                         |                         | 0.5     | 23.3         | 138.1                | 138.1               | -0.51                        | -0.50                       | 1.8                 | 2.1                | 0.009                        | 0.012                       | -8.15                     | -8.15                        | 28.59                  | 1390         | 34.4361597 | -118.6469805 | Valve Adjustment:High Temp,Barely Open                                                                                                    |                                  |
| CV-2007     | 8/24/2026 11:27:05 AM | 19.8       | 74.6       | 0.2       | 5.4            |                         |                         | 0.3     | 27.0         | 130.9                | 130.9               | -0.34                        | -0.33                       | 3.2                 | 3.0                | 0.029                        | 0.024                       | -5.71                     | -5.71                        | 28.56                  | 1369         | 34.4361680 | -118.6469702 | Valve Adjustment:Barely Open                                                                                                              |                                  |
| CV-2008     | 8/11/2026 10:30:29 AM | 24.6       | 75.2       | 0.2       | 0.0            |                         |                         | 0.3     | 0.0          | 112.8                | 113.5               | -0.53                        | -0.53                       | 0.1                 | 0.0                | 0.005                        | 0.000                       | -2.42                     | -2.42                        | 28.59                  | 1395         | 34.4362118 | -118.6462312 | Valve Adjustment:Barely Open                                                                                                              |                                  |
| CV-2008     | 8/24/2026 11:30:36 AM | 24.8       | 73.7       | 0.2       | 1.3            |                         |                         | 0.3     | 6.5          | 117.0                | 117.0               | -2.25                        | -2.17                       | 0.6                 | 0.2                | 0.086                        | 0.007                       | -3.52                     | -3.56                        | 28.56                  | 1360         | 34.4362460 | -118.6462268 | Valve Adjustment:Barely Open                                                                                                              |                                  |
| CV-2009     | 8/18/2026 11:41:11 AM | 24.6       | 33.2       | 7.9       | 34.3           |                         |                         | 0.7     | 4.3          | 123.4                | 113.3               | -2.92                        | -0.92                       | 23.4                | 11.4               | 0.722                        | 0.169                       | -3.61                     | -3.99                        | 28.62                  | 1359         | 34.4362445 | -118.6452845 | Valve Adjustment: NSPS/EG CAI,High O2,Decreased Flow/Vacuum                                                                               |                                  |
| CV-2009     | 8/18/2026 11:47:57 AM | 25.9       | 32.9       | 4.5       | 36.7           |                         |                         | 0.8     | 8.2          | 120.4                | 118.6               | -0.73                        | -0.73                       | 4.8                 | 5.1                | 0.031                        | 0.034                       | -3.93                     | -3.91                        | 28.62                  | 1362         | 34.4362525 | -118.6452748 | Valve Adjustment: NSPS/EG CAC                                                                                                             |                                  |
| CV-2009A    | 8/3/2026 2:08:43 PM   | 34.5       | 56.4       | 0.0       | 9.1            |                         |                         | 0.6     | 0.0          | 141.7                | 141.6               | -3.83                        | -3.69                       | 2.1                 | 1.1                | 0.028                        | 0.008                       | -4.39                     | -4.38                        | 28.38                  | 1388         | 34.4359851 | -118.6452557 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                                                                          |                                  |
| CV-2010     | 8/11/2026 1:14:24 PM  | 45.9       | 42.4       | 0.0       | 11.7           |                         |                         | 1.1     | 0.0          | 122.3                | 120.4               | -17.12                       | -16.84                      | 1.3                 | 6.7                | 0.002                        | 0.061                       | -16.93                    | -16.97                       | 28.66                  | 1348         | 34.4356562 | -118.6435628 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                    |                                  |
| CV-2010A    | 8/11/2026 1:11:50 PM  | 55.6       | 44.3       | 0.1       | 0.0            |                         |                         | 1.3     | 0.0          | 136.9                | 136.9               | -15.19                       | -15.23                      | 26.0                | 26.2               | 1.962                        | 2.000                       | -16.89                    | -16.94                       | 28.66                  | 1354         | 34.4357180 | -118.6436572 | Valve Adjustment: NSPS/EG CAI,High Temp                                                                                                   |                                  |
| CV-2010A    | 8/11/2026 1:12:24 PM  | 55.0       | 44.9       | 0.1       | 0.0            |                         |                         | 1.2     | 0.0          | 136.9                | 136.9               | -15.31                       | -15.21                      | 24.4                | 26.1               | 1.738                        | 1.975                       | -16.72                    | -16.87                       | 28.66                  | 1359         | 34.4357253 | -118.6436457 | Valve Adjustment: NSPS/EG CAI,High Temp                                                                                                   |                                  |
| CV-2011     | 8/17/2026 12:39:53 PM | 44.7       | 38.5       | 0.0       | 16.8           |                         |                         | 1.2     | 0.0          | 128.9                | 128.9               | -11.45                       | -10.44                      | 23.9                | 20.3               | 0.776                        | 0.557                       | -16.10                    | -16.06                       | 28.66                  | 1334         | 34.4341973 | -118.6434772 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                    |                                  |
| CV-2011A    | 8/4/2026 2:00:00 AM   |            |            |           |                |                         | 40700                   |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AtmAA; [User entered 4.07%]      |
| CV-2011A    | 8/4/2026 2:00:00 PM   |            |            |           |                | 252                     |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AtmAA                            |
| CV-2011A    | 8/4/2026 2:00:33 PM   | 29.8       | 58.8       | 0.0       | 11.4           |                         |                         | 0.5     | 0.0          | 152.0                | 152.2               | -4.56                        | -4.53                       | 43.1                | 49.9               | 0.518                        | 0.697                       | -13.58                    | -14.00                       | 28.51                  | 1337         | 34.4345339 | -118.6431619 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                                                                          |                                  |
| CV-2011A    | 8/13/2026 1:05:00 PM  |            |            |           |                | 1310                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AtmAA                            |
| CV-2011A    | 8/13/2026 1:06:38 PM  | 52.9       | 47.1       | 0.0       | 0.0            |                         |                         | 1.1     | 0.0          | 152.2                | 152.1               | -5.37                        | -5.42                       | 74.7                | 72.8               | 1.564                        | 1.484                       | -0.55                     | -0.59                        | 28.56                  | 1326         | 34.4345410 | -118.6431777 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                                                                          |                                  |
| CV-2011A    | 8/20/2026 7:28:01 AM  | 27.5       | 54.2       | 0.0       | 18.3           |                         |                         | 0.5     | 0.0          | 151.8                | 152.1               | -5.32                        | -5.18                       | 60.4                | 71.2               | 1.018                        | 1.416                       | -15.04                    | -15.58                       | 28.6                   | 1338         | 34.4345454 | -118.6431693 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                                                                          |                                  |
| CV-2012     | 8/20/2026 2:43:03 PM  | 46.3       | 53.7       | 0.0       | 0.0            |                         |                         | 0.9     | 0.0          | 138.3                | 136.2               | -9.77                        | -7.76                       | 3.4                 | 3.3                | 0.016                        | 0.015                       | -10.19                    | -12.31                       | 28.56                  | 1335         | 34.4350063 | -118.6433088 | Valve Adjustment:High Temp,Decreased Flow/Vacuum                                                                                          |                                  |
| CV-2201-PLF | 8/4/2026 9:50:37 AM   | 5.9        | 72.3       | 0.8       | 21.0           |                         |                         | 0.1     | 26.3         | 122.1                | 123.0               | -5.09                        | -5.09                       |                     |                    | 5.659                        | 5.635                       | -5.35                     | -5.32                        | 28.49                  | 1339         | 34.4355528 | -118.6488234 | Valve Adjustment:No Flow Measurement,High Temp                                                                                            |                                  |
| CV-2201-PLF | 8/11/2026 8:54:06 AM  | 1.8        | 66.8       | 3.2       | 28.2           |                         |                         | 0.0     | 8.8          | 141.9                | 142.1               | -10.82                       | -10.73                      |                     |                    | 10.958                       | 10.865                      | -10.64                    | -10.21                       | 28.63                  | 1351         | 34.4355460 | -118.6488572 | Valve Adjustment: NSPS/EG CAI,High Temp                                                                                                   |                                  |
| CV-2201-PLF | 8/11/2026 8:54:26 AM  | 1.9        | 67.6       | 3.2       | 27.3           |                         |                         | 0.0     | 8.5          | 142.2                | 141.7               | -10.73                       | -10.73                      |                     |                    | 10.987                       | 10.970                      | -10.54                    | -10.57                       | 28.63                  | 1351         | 34.4355460 | -118.6488572 | Valve Adjustment: NSPS/EG CAI,High Temp                                                                                                   |                                  |
| CV-2201-PLF | 8/19/2026 8:41:34 AM  | 3.6        | 76.6       | 0.7       | 19.1           |                         |                         | 0.0     | 27.3         | 142.6                | 142.6               | -8.31                        | -8.31                       |                     |                    | 8.394                        | 8.394                       | -8.46                     | -8.55                        | 28.63                  | 1357         | 34.4355433 | -118.6488437 | Valve Adjustment: NSPS/EG CAI,High Temp,Barely Open,Surging Liquid in Well (Watered In)                                                   |                                  |
| CV-2201-PLF | 8/19/2026 8:42:27 AM  | 3.8        | 76.0       | 0.7       | 19.5           |                         |                         | 0.1     | 27.9         | 142.7                | 143.1               | -8.40                        | -8.31                       |                     |                    | 8.435                        | 8.339                       | -8.37                     | -8.46                        | 28.63                  | 1360         | 34.4355450 | -118.6488543 |                                                                                                                                           |                                  |
| CV-2204-PLF | 8/3/2026 9:59:27 AM   | 1.9        | 65.3       | 0.0       | 32.8           |                         |                         | 0.0     | 0.0          | 191.8                | 191.9               | -6.20                        | -6.08                       |                     |                    | 6.745                        | 6.624                       | 0.34                      | 0.34                         | 28.46                  | 1364         | 34.4357750 | -118.6474762 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                      |                                  |
| CV-2204-PLF | 8/3/2026 10:02:00 AM  |            |            |           |                |                         | 159700                  |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AtmAA; [User entered 15.97%]     |
| CV-2204-PLF | 8/3/2026 10:02:00 AM  |            |            |           |                | 1670                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AtmAA                            |
| CV-2204-PLF | 8/10/2026 10:31:11 AM | 34.0       | 63.4       | 0.0       | 2.6            |                         |                         | 0.5     | 0.0          | 191.8                | 192.1               | -5.09                        | -4.72                       |                     |                    | 5.718                        | 5.324                       | 0.67                      | 0.67                         | 28.6                   | 1373         | 34.4357637 | -118.6474755 | Valve Adjustment:No Flow Measurement,High Temp                                                                                            |                                  |
| CV-2204-PLF | 8/10/2026 10:40:00 AM |            |            |           |                | 1220                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AtmAA                            |
| CV-2204-PLF | 8/20/2026 1:36:32 PM  | 22.0       | 75.4       | 0.0       | 2.6            |                         |                         | 0.3     | 0.0          | 192.1                | 192.1               | -3.82                        | -3.59                       |                     |                    | 3.840                        | 3.819                       | -0.01                     | 0.00                         | 28.57                  | 1356         | 34.4357624 | -118.6474754 | Valve Adjustment:No Flow Measurement,High Temp                                                                                            |                                  |
| CV-2204-PLF | 8/24/2026 9:43:40 AM  | 31.9       | 68.1       | 0.0       | 0.0            |                         |                         | 0.5     | 0.0          | 191.8                | 192.1               | -4.92                        | -4.55                       |                     |                    | 4.341                        | 4.923                       | 0.38                      | 0.38                         | 28.61                  | 1359         | 34.4357635 | -118.6474856 | Valve Adjustment:No Flow Measurement,High Temp                                                                                            |                                  |
| CV-2204-PLF | 8/31/2026 1:47:02 PM  | 8.0        | 75.8       | 0.0       | 16.2           |                         |                         | 0.1     | 0.0          | 190.3                | 191.1               | -1.46                        | -1.31                       |                     |                    | 1.419                        | 1.286                       | 0.00                      | 0.00                         | 28.53                  | 1366         | 34.4357670 | -118.6475204 | Valve Adjustment:No Flow Measurement,High Temp                                                                                            |                                  |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name  | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init Temp<br>[°F] | Adj Temp<br>[°F] | Init Stat Press<br>["H2O] | Adj Stat Press<br>["H2O] | Init Flow<br>[scfm] | Adj Flow<br>[scfm] | Init Diff Press<br>["H2O] | Adj Diff Press<br>["H2O] | Sys Pressure<br>["H2O] | Adj Avail Press<br>["H2O] | Baro Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                                            |
|-------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|-------------------|------------------|---------------------------|--------------------------|---------------------|--------------------|---------------------------|--------------------------|------------------------|---------------------------|---------------------|--------------|------------|--------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|
| CV-2205     | 8/17/2026 12:24:35 PM | 36.2       | 42.0       | 0.0       | 21.8           |                         |                         | 0.9     | 0.0          | 131.4             | 129.9            | -2.00                     | -1.33                    | 10.1                | 7.8                | 0.027                     | 0.016                    | -15.04                 | -15.07                    | 28.62               | 1380         | 34.4342443 | -118.6441303 | Valve Adjustment: NSPS/EG CAI, High Temp, Decreased Flow/Vacuum                                                                                     |
| CV-2205     | 8/17/2026 12:25:03 PM | 36.0       | 42.3       | 0.0       | 21.7           |                         |                         | 0.9     | 0.0          | 129.5             | 129.6            | -1.22                     | -1.22                    | 8.7                 | 11.5               | 0.020                     | 0.034                    | -15.14                 | -15.13                    | 28.62               | 1377         | 34.4342442 | -118.6441163 | Valve Adjustment: NSPS/EG CAC                                                                                                                       |
| CV-2207     | 8/11/2026 1:37:59 PM  | 49.3       | 46.8       | 0.0       | 3.9            |                         |                         | 1.1     | 0.0          | 122.9             | 123.9            | -0.92                     | -0.92                    | 7.3                 | 7.7                | 0.014                     | 0.015                    | -14.60                 | -14.53                    | 28.62               | 1389         | 34.4360075 | -118.6442167 | Valve Adjustment: Barely Open                                                                                                                       |
| CV-2208A    | 8/18/2026 11:57:11 AM | 16.3       | 61.3       | 0.0       | 22.4           |                         |                         | 0.3     | 0.0          | 156.4             | 156.3            | -3.86                     | -3.81                    | 18.4                | 10.7               | 0.094                     | 0.032                    | 0.67                   | 0.67                      | 28.65               | 1334         | 34.4365342 | -118.6449478 | Valve Adjustment: NSPS/EG CAI, High Temp; Well Comment: unable to reach system port safely                                                          |
| CV-2208A    | 8/18/2026 11:57:28 AM | 16.3       | 61.6       | 0.0       | 22.1           |                         |                         | 0.3     | 0.0          | 156.2             | 156.3            | -3.84                     | -3.78                    | 17.8                | 7.7                | 0.089                     | 0.017                    | 0.67                   | 0.67                      | 28.65               | 1330         | 34.4365410 | -118.6449542 | Valve Adjustment: NSPS/EG CAI, High Temp                                                                                                            |
| CV-2208A    | 8/18/2026 2:10:00 PM  |            |            |           |                | 829                     |                         |         |              |                   |                  |                           |                          |                     |                    |                           |                          |                        |                           |                     |              |            |              | AtmAA                                                                                                                                               |
| CV-2208A    | 8/24/2026 10:26:05 AM | 46.5       | 53.3       | 0.2       | 0.0            |                         |                         | 0.9     | 0.0          | 157.7             | 157.6            | -4.44                     | -4.32                    | 20.7                | 19.6               | 0.121                     | 0.107                    | -7.93                  | -8.38                     | 28.66               | 1337         | 34.4365629 | -118.6449678 | Valve Adjustment: High Temp; Well Condition: Lorentz Pump Installed                                                                                 |
| CV-2208A    | 8/31/2026 1:22:39 PM  | 36.4       | 63.1       | 0.0       | 0.5            |                         |                         | 0.6     | 0.0          | 157.1             | 157.2            | -2.78                     | -2.78                    | 16.2                | 21.0               | 0.073                     | 0.124                    | -6.78                  | -6.74                     | 28.53               |              |            |              | Valve Adjustment: High Temp; Well Condition: Lorentz Pump Installed                                                                                 |
| CV-2301     | 8/5/2026 1:20:00 PM   |            |            |           |                |                         | 131400                  |         |              |                   |                  |                           |                          |                     |                    |                           |                          |                        |                           |                     |              |            |              | AtmAA; [User entered 13.14%]                                                                                                                        |
| CV-2301     | 8/5/2026 1:20:00 PM   |            |            |           |                | 2840                    |                         |         |              |                   |                  |                           |                          |                     |                    |                           |                          |                        |                           |                     |              |            |              | AtmAA                                                                                                                                               |
| CV-2301     | 8/10/2026 8:11:28 AM  | 2.8        | 79.3       | 0.5       | 17.4           |                         |                         | 0.0     | 34.8         | 189.7             | 189.3            | -0.94                     | -0.94                    |                     |                    | 0.921                     | 0.924                    | -13.92                 | -14.05                    | 28.63               | 1354         | 34.4335198 | -118.6492490 | Valve Adjustment: NSPS/EG CAI, High Temp, Barely Open                                                                                               |
| CV-2301     | 8/10/2026 8:13:26 AM  | 2.7        | 78.8       | 0.5       | 18.0           |                         |                         | 0.0     | 36.0         | 189.4             | 189.8            | -0.99                     | -0.95                    |                     |                    | 0.962                     | 0.927                    | -13.91                 | -13.80                    | 28.63               | 1353         | 34.4335280 | -118.6492402 | Valve Adjustment: NSPS/EG CAI, High Temp, Barely Open                                                                                               |
| CV-2301     | 8/11/2026 10:00:00 AM |            |            |           |                | 2470                    |                         |         |              |                   |                  |                           |                          |                     |                    |                           |                          |                        |                           |                     |              |            |              | AtmAA                                                                                                                                               |
| CV-2301     | 8/11/2026 10:04:43 AM | 19.6       | 75.2       | 0.0       | 5.2            |                         |                         | 0.3     | 0.0          | 188.2             | 189.1            | -0.88                     | -0.87                    |                     |                    | 0.873                     | 0.850                    | -13.07                 | -13.04                    | 28.64               | 1354         | 34.4335183 | -118.6492424 | Valve Adjustment: No Flow Measurement, High Temp                                                                                                    |
| CV-2301     | 8/12/2026 8:35:00 AM  |            |            |           |                |                         | 97000                   |         |              |                   |                  |                           |                          |                     |                    |                           |                          |                        |                           |                     |              |            |              | AirTech Lab; [User entered 9.7%]                                                                                                                    |
| CV-2301     | 8/12/2026 8:35:00 AM  |            |            |           |                | 1600                    |                         |         |              |                   |                  |                           |                          |                     |                    |                           |                          |                        |                           |                     |              |            |              | AirTech Lab                                                                                                                                         |
| CV-2301     | 8/19/2026 2:28:43 PM  | 32.3       | 67.7       | 0.0       | 0.0            |                         |                         | 0.5     | 0.0          | 183.4             | 186.0            | 0.03                      | 0.03                     | 0.0                 | 0.0                | 0.015                     | 0.023                    | -12.54                 | -12.56                    | 28.51               | 1353         | 34.4335310 | -118.6492345 | Valve Adjustment: No Flow Measurement, High Temp, Positive Static Press., Reduce Sys. Vac. - Flare Down                                             |
| CV-2301     | 8/19/2026 3:08:38 PM  | 28.9       | 56.4       | 0.3       | 14.4           |                         |                         | 0.5     | 48.0         | 165.9             | 175.8            | -1.18                     | -1.18                    |                     |                    | 1.186                     | 1.187                    | -12.63                 | -12.64                    | 28.51               | 1353         | 34.4335030 | -118.6492400 | Valve Adjustment: No Flow Measurement, High Temp, Barely Open                                                                                       |
| CV-2301     | 8/26/2026 10:10:29 AM | 22.7       | 69.4       | 0.0       | 7.9            |                         |                         | 0.3     | 0.0          | 181.6             | 181.8            | -10.45                    | -10.45                   |                     |                    | 11.036                    | 11.039                   | -12.55                 | -12.46                    | 28.57               | 1361         | 34.4335162 | -118.6492756 | Valve Adjustment: Audible Flow, High Temp                                                                                                           |
| CV-2302     | 8/6/2026 10:01:38 AM  | 42.1       | 45.3       | 1.0       | 11.6           |                         |                         | 0.9     | 11.6         | 128.8             | 129.0            | -17.55                    | -17.55                   |                     |                    | 17.959                    | 17.833                   | -17.84                 | -17.50                    | 28.6                | 1352         | 34.4340602 | -118.6492008 | Valve Adjustment: Valve 100% Open; Well Comment: valve stuck open                                                                                   |
| CV-2302     | 8/12/2026 8:30:00 AM  |            |            |           |                |                         | 31000                   |         |              |                   |                  |                           |                          |                     |                    |                           |                          |                        |                           |                     |              |            |              | AirTech Lab; [User entered 3.1%]                                                                                                                    |
| CV-2302     | 8/12/2026 8:30:00 AM  |            |            |           |                | 150                     |                         |         |              |                   |                  |                           |                          |                     |                    |                           |                          |                        |                           |                     |              |            |              | AirTech Lab                                                                                                                                         |
| CV-2302     | 8/19/2026 10:46:20 AM | 50.9       | 48.2       | 0.9       | 0.0            |                         |                         | 1.1     | 0.0          | 132.3             | 132.1            | -13.16                    | -13.33                   |                     |                    | 13.503                    | 13.643                   | -13.64                 | -13.75                    | 28.55               | 1348         | 34.4340260 | -118.6492113 | Valve Adjustment: NSPS/EG CAI, High Temp, Surging Liquid in Header, Surging Liquid in Well (Watered In); Well Comment: Valve stuck open             |
| CV-2302     | 8/19/2026 10:46:51 AM | 52.1       | 46.7       | 1.2       | 0.0            |                         |                         | 1.1     | 0.0          | 132.4             | 132.5            | -12.51                    | -12.83                   |                     |                    | 12.957                    | 13.093                   | -12.63                 | -12.63                    | 28.55               | 1334         | 34.4340167 | -118.6492193 | Valve Adjustment: High Temp, Valve 100% Open                                                                                                        |
| CV-2303     | 8/4/2026 8:20:00 AM   |            |            |           |                |                         | 190550                  |         |              |                   |                  |                           |                          |                     |                    |                           |                          |                        |                           |                     |              |            |              | AtmAA; [User entered 19.055%]                                                                                                                       |
| CV-2303     | 8/4/2026 8:20:00 AM   |            |            |           |                | 2035                    |                         |         |              |                   |                  |                           |                          |                     |                    |                           |                          |                        |                           |                     |              |            |              | AtmAA                                                                                                                                               |
| CV-2303     | 8/4/2026 8:26:13 AM   | 1.7        | 76.0       | 0.6       | 21.7           |                         |                         | 0.0     | 36.2         | 188.6             | 190.1            | -2.50                     | -2.33                    |                     |                    | 2.507                     | 2.331                    | -3.13                  | -2.94                     | 28.49               | 1358         | 34.4353709 | -118.6496969 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                                            |
| CV-2303     | 8/12/2026 10:45:00 AM |            |            |           |                | 2480                    |                         |         |              |                   |                  |                           |                          |                     |                    |                           |                          |                        |                           |                     |              |            |              | AtmAA                                                                                                                                               |
| CV-2303     | 8/12/2026 10:49:02 AM | 18.7       | 64.4       | 0.0       | 16.9           |                         |                         | 0.3     | 0.0          | 190.9             | 190.8            | 0.83                      | 0.69                     |                     |                    | 0.000                     | 0.000                    | 1.32                   | 1.12                      | 28.57               | 1358         | 34.4353642 | -118.6496795 | Valve Adjustment: No Flow Measurement, High Temp, Valve 100% Open; Well Condition: Lorentz Pump Installed                                           |
| CV-2303     | 8/12/2026 2:05:55 PM  | 11.0       | 75.3       | 0.0       | 13.7           |                         |                         | 0.1     | 0.0          | 190.8             | 191.1            | 0.53                      | 0.46                     |                     |                    | 0.000                     | 0.000                    | 0.12                   | -0.06                     | 28.49               | 1358         | 34.4353656 | -118.6497017 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                                            |
| CV-2303     | 8/13/2026 9:50:00 AM  |            |            |           |                |                         | 190000                  |         |              |                   |                  |                           |                          |                     |                    |                           |                          |                        |                           |                     |              |            |              | AirTech Lab; [User entered 19%]                                                                                                                     |
| CV-2303     | 8/13/2026 9:50:00 AM  |            |            |           |                | 1900                    |                         |         |              |                   |                  |                           |                          |                     |                    |                           |                          |                        |                           |                     |              |            |              | AirTech Lab                                                                                                                                         |
| CV-2303     | 8/13/2026 12:16:13 PM | 1.2        | 70.7       | 0.1       | 28.0           |                         |                         | 0.0     | 199.6        | 188.6             | 189.9            | -0.71                     | -0.74                    |                     |                    | 0.712                     | 0.738                    | -0.68                  | -0.72                     | 28.57               | 1358         | 34.4353770 | -118.6496653 | Valve Adjustment: NSPS/EG CAI, High Temp, Valve 100% Open, Undersized Lateral; Well Comment: pump is active; Well Condition: Lorentz Pump Installed |
| CV-2303     | 8/13/2026 12:19:56 PM | 1.2        | 70.6       | 0.1       | 28.2           |                         |                         | 0.0     | 563.2        | 188.8             | 188.6            | -0.44                     | -0.45                    |                     |                    | 0.429                     | 0.461                    | -0.81                  | -0.81                     | 28.57               | 1366         | 34.4353615 | -118.6496703 | Valve Adjustment: High Temp, Valve 100% Open, Undersized Lateral; Well Condition: Lorentz Pump Installed                                            |
| CV-2303     | 8/18/2026 8:25:00 AM  |            |            |           |                | 1795                    |                         |         |              |                   |                  |                           |                          |                     |                    |                           |                          |                        |                           |                     |              |            |              | AtmAA                                                                                                                                               |
| CV-2303     | 8/18/2026 8:32:01 AM  | 9.2        | 66.0       | 0.0       | 24.8           |                         |                         | 0.1     | 0.0          | 191.7             | 191.7            | 0.24                      | 0.18                     |                     |                    | 0.000                     | 0.000                    | 0.07                   | -0.16                     | 28.6                | 1362         | 34.4353805 | -118.6496995 | Valve Adjustment: No Flow Measurement, High Temp, Positive Static Press., Valve 100% Open; Well Condition: Lorentz Pump Installed                   |
| CV-2303     | 8/18/2026 8:35:57 AM  | 8.3        | 81.8       | 0.0       | 9.9            |                         |                         | 0.1     | 0.0          | 192.6             | 192.6            | 0.44                      | 0.38                     |                     |                    | 0.000                     | 0.000                    | 0.35                   | 0.34                      | 28.6                | 1363         | 34.4353778 | -118.6496963 | Valve Adjustment: No Flow Measurement, High Temp, Positive Static Press., Valve 100% Open; Well Condition: Lorentz Pump Installed                   |
| CV-2303     | 8/25/2026 8:09:51 AM  | 12.5       | 64.0       | 0.0       | 23.5           |                         |                         | 0.2     | 0.0          | 191.0             |                  |                           |                          |                     |                    |                           |                          |                        |                           | 28.6                | 1355         | 34.4353799 | -118.6497117 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                                            |
| CV-2304-PLF | 8/1/2026 10:16:15 AM  | 1.3        | 83.4       | 0.0       | 15.3           |                         |                         | 0.0     | 0.0          | 177.3             | 177.4            | -3.74                     | -3.70                    |                     |                    | 3.741                     | 3.689                    | -3.34                  | -3.25                     | 28.59               | 1343         | 34.4345523 | -118.6487378 | Valve Adjustment: NSPS/EG CAI, High Temp, Surging Liquid in Header; Well Comment: RES SEM                                                           |
| CV-2304-PLF | 8/1/2026 10:16:56 AM  | 1.4        | 82.8       | 0.0       | 15.8           |                         |                         | 0.0     | 0.0          | 177.4             | 177.6            | -3.93                     | -3.91                    |                     |                    | 3.953                     | 3.837                    | -3.54                  | -3.50                     | 28.6                | 1346         | 34.4345570 | -118.6487392 | Valve Adjustment: NSPS/EG CAI, High Temp                                                                                                            |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name  | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init Flow<br>[scfm] | Adj Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                    |
|-------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|---------------------|--------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|-------------------------------------------------------------------------------------------------------------|
| CV-2304-PLF | 8/4/2026 8:45:00 AM   |            |            |           |                |                         | 184500                  |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA; [User entered 18.45%]                                                                                |
| CV-2304-PLF | 8/4/2026 8:45:00 AM   |            |            |           |                | 1860                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                       |
| CV-2304-PLF | 8/4/2026 9:16:56 AM   | 2.5        | 69.8       | 0.0       | 27.7           |                         |                         | 0.0     | 0.0          | 176.9                | 176.6               | -8.17                        | -8.07                       |                     |                    | 8.655                        | 8.593                       | -9.72                     | -9.74                        | 28.49                  | 1353         | 34.4345557 | -118.6487647 | Valve Adjustment:No Flow Measurement,High Temp                                                              |
| CV-2304-PLF | 8/5/2026 1:17:34 PM   | 0.9        | 78.0       | 0.0       | 21.1           |                         |                         | 0.0     | 0.0          | 170.4                | 170.7               | -10.15                       | -10.25                      |                     |                    | 0.031                        | 0.000                       | -9.92                     | -10.13                       | 28.68                  | 1333         | 34.4345537 | -118.6487515 | Valve Adjustment:Increased Flow/Vacuum                                                                      |
| CV-2304-PLF | 8/12/2026 2:26:53 PM  | 48.1       | 51.9       | 0.0       | 0.0            |                         |                         | 0.9     | 0.0          | 171.4                | 171.8               | -3.77                        | -3.53                       |                     |                    | 3.667                        | 3.520                       | -3.93                     | -3.72                        | 28.49                  | 1345         | 34.4345566 | -118.6487654 | Valve Adjustment:No Flow Measurement,High Temp                                                              |
| CV-2304-PLF | 8/12/2026 2:30:00 PM  |            |            |           |                | 2230                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                       |
| CV-2304-PLF | 8/18/2026 9:02:49 AM  | 14.5       | 68.6       | 0.0       | 16.9           |                         |                         | 0.2     | 0.0          | 177.8                | 177.8               | -7.25                        | -7.47                       |                     |                    | 7.837                        | 8.066                       | -7.54                     | -7.69                        | 28.62                  | 1343         | 34.4345554 | -118.6487562 | Valve Adjustment:No Flow Measurement,High Temp                                                              |
| CV-2304-PLF | 8/18/2026 9:05:00 AM  |            |            |           |                | 2220                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                       |
| CV-2304-PLF | 8/20/2026 10:26:20 AM | 10.8       | 65.3       | 0.0       | 23.9           |                         |                         | 0.2     | 0.0          | 177.5                | 177.5               | -6.17                        | -6.27                       |                     |                    | 0.000                        | 0.000                       | -6.14                     | -6.14                        | 28.64                  | 1341         | 34.4345597 | -118.6487327 | Valve Adjustment:High Temp,Increased Flow/Vacuum                                                            |
| CV-2304-PLF | 8/25/2026 8:52:06 AM  | 18.0       | 71.4       | 0.0       | 10.6           |                         |                         | 0.3     | 0.0          | 177.3                | 177.2               | -7.75                        | -7.41                       |                     |                    | 8.317                        | 7.977                       | -8.08                     | -7.62                        | 28.6                   | 1360         | 34.4345656 | -118.6487491 | Valve Adjustment:No Flow Measurement,High Temp                                                              |
| CV-2305     | 8/5/2026 9:00:00 AM   |            |            |           |                |                         | 45000                   |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA; [User entered 4.5%]                                                                                  |
| CV-2305     | 8/5/2026 9:00:00 AM   |            |            |           |                | 2310                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                       |
| CV-2305     | 8/11/2026 8:15:00 AM  |            |            |           |                | 1770                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                       |
| CV-2305     | 8/11/2026 8:18:34 AM  | 24.3       | 59.7       | 0.0       | 16.0           |                         |                         | 0.4     | 0.0          | 156.2                | 156.2               | -4.12                        | -4.15                       |                     |                    | 2.044                        | 2.006                       | -17.75                    | -17.56                       | 28.6                   | 1409         | 34.4352211 | -118.6465506 | Valve Adjustment:High Temp,Well Condition:Lorentz Pump Installed                                            |
| CV-2305     | 8/14/2026 7:40:00 AM  |            |            |           |                |                         | 58000                   |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AirTech Lab; [User entered 5.8%]                                                                            |
| CV-2305     | 8/14/2026 7:40:00 AM  |            |            |           |                | 1400                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AirTech Lab                                                                                                 |
| CV-2305     | 8/18/2026 10:37:57 AM | 36.0       | 53.6       | 0.0       | 10.4           |                         |                         | 0.7     | 0.0          | 156.9                | 156.9               | -4.71                        | -4.71                       |                     |                    | 0.525                        | 0.546                       | -15.12                    | -15.24                       | 28.58                  | 1390         | 34.4352159 | -118.6465389 | Valve Adjustment:High Temp,Well Condition:Lorentz Pump Installed                                            |
| CV-2305     | 8/18/2026 10:40:00 AM |            |            |           |                | 1930                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                       |
| CV-2305     | 8/25/2026 2:29:55 PM  | 42.0       | 57.7       | 0.2       | 0.1            |                         |                         | 0.7     | 0.5          | 157.6                | 157.6               | -4.11                        | -4.11                       | 7.0                 | 7.4                | 0.034                        | 0.037                       | -12.58                    | -13.26                       | 28.55                  | 1382         | 34.4352162 | -118.6465492 | Valve Adjustment:High Temp,Well Condition:Lorentz Pump Installed                                            |
| CV-2306-PLF | 8/3/2026 9:55:00 AM   |            |            |           |                |                         | 180200                  |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA; [User entered 18.02%]                                                                                |
| CV-2306-PLF | 8/3/2026 9:55:00 AM   |            |            |           |                | 1330                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                       |
| CV-2306-PLF | 8/3/2026 9:56:38 AM   | 1.9        | 77.7       | 0.0       | 20.4           |                         |                         | 0.0     | 0.0          | 165.1                | 165.1               | -2.51                        | -3.40                       |                     |                    | 1.868                        | 3.064                       | 0.52                      | 0.34                         | 28.46                  | 1382         | 34.4360804 | -118.6478269 | Valve Adjustment:No Flow Measurement,High Temp                                                              |
| CV-2306-PLF | 8/10/2026 9:35:00 AM  |            |            |           |                | 1270                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                       |
| CV-2306-PLF | 8/17/2026 9:35:00 AM  |            |            |           |                | 1440                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                       |
| CV-2306-PLF | 8/17/2026 9:37:12 AM  | 23.6       | 71.6       | 0.3       | 4.5            |                         |                         | 0.3     | 15.0         | 155.5                | 156.3               | -5.43                        | -5.73                       |                     |                    | 5.834                        | 6.395                       | 0.34                      | 0.34                         | 28.68                  | 1366         | 34.4361016 | -118.6478088 | Valve Adjustment:No Flow Measurement,High Temp,Well Condition:Lorentz Pump Installed                        |
| CV-2306-PLF | 8/24/2026 9:16:41 AM  | 27.6       | 65.7       | 2.7       | 4.0            |                         |                         | 0.4     | 1.5          | 161.9                | 162.8               | -7.96                        | -7.89                       |                     |                    | 8.516                        | 8.568                       | 0.35                      | 0.34                         | 28.6                   | 1377         | 34.4360966 | -118.6478108 | Valve Adjustment:No Flow Measurement,High Temp                                                              |
| CV-2306-PLF | 8/31/2026 9:53:35 AM  | 16.5       | 72.0       | 0.3       | 11.2           |                         |                         | 0.2     | 37.3         | 188.4                | 188.4               | -6.64                        | -5.73                       |                     |                    | 7.162                        | 6.449                       | 0.34                      | 0.34                         | 28.57                  | 1349         | 34.4360993 | -118.6477973 | Valve Adjustment:No Flow Measurement,High Temp                                                              |
| CV-2308-PLF | 8/10/2026 9:07:43 AM  | 3.4        | 76.4       | 0.4       | 19.8           |                         |                         | 0.0     | 49.5         | 139.6                | 138.9               | -7.55                        | -7.72                       |                     |                    | 7.519                        | 7.717                       | -8.55                     | -8.46                        | 28.64                  | 1343         | 34.4359017 | -118.6489190 | Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open,Surging Liquid in Well (Watered In);Well Comment:No pump |
| CV-2308-PLF | 8/10/2026 9:11:23 AM  | 3.7        | 75.9       | 0.2       | 20.2           |                         |                         | 0.0     | 101.0        | 139.7                | 140.0               | -7.72                        | -7.72                       |                     |                    | 7.646                        | 7.685                       | -8.53                     | -8.46                        | 28.65                  | 1351         | 34.4358853 | -118.6489205 | Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open,Surging Liquid in Well (Watered In);Well Comment:No pump |
| CV-2308-PLF | 8/19/2026 8:47:17 AM  | 6.8        | 71.7       | 1.4       | 20.1           |                         |                         | 0.1     | 14.4         | 134.2                | 135.1               | -7.57                        | -7.52                       |                     |                    | 7.531                        | 7.524                       | -8.28                     | -7.84                        | 28.63                  | 1323         | 34.4359042 | -118.6489297 | Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open,Surging Liquid in Well (Watered In);Well Comment:No pump |
| CV-2308-PLF | 8/19/2026 8:48:27 AM  | 7.7        | 73.8       | 0.8       | 17.7           |                         |                         | 0.1     | 22.1         | 135.7                | 134.4               | -7.57                        | -7.64                       |                     |                    | 7.604                        | 7.622                       | -8.29                     | -8.29                        | 28.63                  | 1338         | 34.4358798 | -118.6489088 | Valve Adjustment:No Flow Measurement,High Temp                                                              |
| CV-2310-PLF | 8/4/2026 8:34:50 AM   | 1.8        | 73.8       | 0.0       | 24.4           |                         |                         | 0.0     | 0.0          | 195.5                | 195.5               | -10.17                       | -9.49                       |                     |                    | 10.636                       | 9.902                       | 0.34                      | 0.34                         | 28.47                  | 1352         | 34.4353237 | -118.6491397 | Valve Adjustment:No Flow Measurement,High Temp                                                              |
| CV-2310-PLF | 8/4/2026 8:35:00 AM   |            |            |           |                |                         | 181200                  |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA; [User entered 18.12%]                                                                                |
| CV-2310-PLF | 8/4/2026 8:35:00 AM   |            |            |           |                | 2180                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                       |
| CV-2310-PLF | 8/12/2026 2:10:00 PM  |            |            |           |                | 2140                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                       |
| CV-2310-PLF | 8/12/2026 2:10:18 PM  | 11.5       | 76.3       | 0.0       | 12.2           |                         |                         | 0.2     | 0.0          | 194.0                | 194.3               | -6.82                        | -6.74                       |                     |                    | 6.854                        | 6.662                       | -0.01                     | 0.04                         | 28.49                  | 1376         | 34.4353056 | -118.6491042 | Valve Adjustment:No Flow Measurement,High Temp                                                              |
| CV-2310-PLF | 8/18/2026 8:35:00 AM  |            |            |           |                | 1710                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                       |
| CV-2310-PLF | 8/18/2026 8:37:33 AM  | 8.4        | 75.8       | 0.0       | 15.8           |                         |                         | 0.1     | 0.0          | 189.4                | 190.5               | -6.44                        | -6.57                       |                     |                    | 6.874                        | 7.086                       | 0.36                      | 0.36                         | 28.6                   | 1358         | 34.4353237 | -118.6491229 | Valve Adjustment:No Flow Measurement,High Temp                                                              |
| CV-2310-PLF | 8/25/2026 8:13:49 AM  | 9.0        | 73.8       | 0.0       | 17.2           |                         |                         | 0.1     | 0.0          | 194.4                | 194.5               | -7.26                        | -6.59                       |                     |                    | 7.834                        | 7.016                       | 0.34                      | 0.34                         | 28.6                   | 1356         | 34.4353172 | -118.6491296 | Valve Adjustment:No Flow Measurement,High Temp                                                              |
| CV-2311     | 8/3/2026 1:12:00 PM   |            |            |           |                |                         | 114000                  |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA; [User entered 11.4%]                                                                                 |
| CV-2311     | 8/3/2026 1:12:00 PM   |            |            |           |                | 1260                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                       |
| CV-2311     | 8/3/2026 1:12:08 PM   | 5.1        | 75.1       | 0.0       | 19.8           |                         |                         | 0.1     | 0.0          | 171.3                | 171.5               | -4.62                        | -4.62                       |                     |                    | 0.000                        | 0.000                       | 0.22                      | 0.18                         | 28.42                  | 1376         | 34.4363123 | -118.6498784 | Valve Adjustment:No Flow Measurement,High Temp,Well Condition:Lorentz Pump Installed                        |
| CV-2311     | 8/10/2026 1:54:01 PM  | 25.2       | 74.7       | 0.0       | 0.1            |                         |                         | 0.3     | 0.0          | 169.7                | 169.3               | -3.65                        | -3.62                       |                     |                    | 3.645                        | 3.605                       | -8.22                     | -8.17                        | 28.53                  | 1363         | 34.4363283 | -118.6498514 | Valve Adjustment:No Flow Measurement,High Temp,Well Condition:Lorentz Pump Installed                        |
| CV-2311     | 8/10/2026 2:00:00 PM  |            |            |           |                | 1920                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                       |
| CV-2311     | 8/17/2026 2:25:00 PM  |            |            |           |                | 1275                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                       |
| CV-2311     | 8/17/2026 2:30:18 PM  | 35.0       | 60.8       | 0.0       | 4.2            |                         |                         | 0.6     | 0.0          | 173.3                | 173.1               | -2.38                        | -2.42                       |                     |                    | 2.342                        | 2.299                       | -6.71                     | -6.46                        | 28.57                  | 1357         | 34.4363158 | -118.6498895 | Valve Adjustment:No Flow Measurement,High Temp,Well Condition:Lorentz Pump Installed                        |

### Chiquita Canyon Landfill

| Point Name  | Record Date           | CH4  | CO2  | O2  | Bal Gas | CO Reading (ppmv) | H2 Reading (ppmv) | CH4:CO2 | BalO2 | Init Temp (°F) | Adj Temp (°F) | Init Stat Press (\"H2O) | Adj Stat Press (\"H2O) | Init Flow (scfm) | Adj Flow (scfm) | Init Diff Press (\"H2O) | Adj Diff Press (\"H2O) | Sys Pressure (\"H2O) | Adj Avail Press (\"H2O) | Baro Press (\"Hg) | Elev (ft) | Latitude   | Longitude    | Comments                                                                             |
|-------------|-----------------------|------|------|-----|---------|-------------------|-------------------|---------|-------|----------------|---------------|-------------------------|------------------------|------------------|-----------------|-------------------------|------------------------|----------------------|-------------------------|-------------------|-----------|------------|--------------|--------------------------------------------------------------------------------------|
|             |                       | [%]  | [%]  | [%] | [%]     |                   |                   |         | [%]   | [°F]           | [°F]          | [\"H2O]                 | [\"H2O]                | [scfm]           | [scfm]          | [\"H2O]                 | [\"H2O]                | [\"H2O]              | [\"H2O]                 | [\"Hg]            | [ft]      |            |              |                                                                                      |
| CV-2311     | 8/24/2026 2:17:51 PM  | 17.8 | 71.4 | 0.0 | 10.8    |                   |                   | 0.2     | 0.0   | 168.9          | 169.7         | -0.35                   | -0.36                  |                  |                 | 0.359                   | 0.354                  | -2.55                | -2.69                   | 28.54             | 1373      | 34.4363003 | -118.6498939 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed |
| CV-2311     | 8/31/2026 2:32:08 PM  | 47.3 | 48.4 | 0.0 | 4.3     |                   |                   | 1.0     | 0.0   | 165.1          | 166.7         | -2.75                   | -2.78                  |                  |                 | 2.749                   | 2.791                  | -6.09                | -6.27                   | 28.5              | 1367      | 34.4363026 | -118.6498889 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed |
| CV-2312-PLF | 8/5/2026 10:07:00 AM  |      |      |     |         |                   | 149500            |         |       |                |               |                         |                        |                  |                 |                         |                        |                      |                         |                   |           |            |              | AtmA; [User entered 14.95%]                                                          |
| CV-2312-PLF | 8/5/2026 10:07:00 AM  |      |      |     |         | 2875              |                   |         |       |                |               |                         |                        |                  |                 |                         |                        |                      |                         |                   |           |            |              | AtmA                                                                                 |
| CV-2312-PLF | 8/11/2026 9:27:14 AM  | 9.4  | 79.0 | 0.1 | 11.5    |                   |                   | 0.1     | 115.0 | 168.1          | 168.0         | -2.70                   | -3.05                  | 29.8             | 34.8            | 2.645                   | 3.613                  | -7.04                | -7.39                   | 28.6              |           |            |              | Valve Adjustment:No Flow Measurement,High Temp                                       |
| CV-2312-PLF | 8/11/2026 9:30:00 AM  |      |      |     |         | 3640              |                   |         |       |                |               |                         |                        |                  |                 |                         |                        |                      |                         |                   |           |            |              | AtmA                                                                                 |
| CV-2312-PLF | 8/12/2026 9:10:00 AM  |      |      |     |         |                   | 160000            |         |       |                |               |                         |                        |                  |                 |                         |                        |                      |                         |                   |           |            |              | AirTech Lab; [User entered 16%]                                                      |
| CV-2312-PLF | 8/12/2026 9:10:00 AM  |      |      |     |         | 2800              |                   |         |       |                |               |                         |                        |                  |                 |                         |                        |                      |                         |                   |           |            |              | AirTech Lab                                                                          |
| CV-2312-PLF | 8/19/2026 10:34:14 AM | 2.8  | 81.3 | 0.0 | 15.9    |                   |                   | 0.0     | 0.0   | 169.0          | 168.9         | 0.93                    | -2.51                  | 16.7             | 28.2            | 0.826                   | 2.370                  | -3.95                | -3.51                   | 28.55             | 1373      | 34.4342058 | -118.6473902 | Valve Adjustment:No Flow Measurement,High Temp;Increased Flow/Vacuum                 |
| CV-2312-PLF | 8/19/2026 10:55:23 AM | 5.4  | 78.3 | 0.1 | 16.2    |                   |                   | 0.1     | 162.0 | 168.7          | 168.7         | -6.79                   | -7.08                  | 49.4             | 50.5            | 7.408                   | 7.753                  | -3.96                | -3.87                   | 28.53             | 1392      | 34.4342058 | -118.6473850 | Valve Adjustment:No Flow Measurement,High Temp                                       |
| CV-2312-PLF | 8/26/2026 9:43:39 AM  | 1.2  | 79.2 | 0.0 | 19.6    |                   |                   | 0.0     | 0.0   | 169.2          | 169.2         | -8.17                   | -8.09                  | 53.6             | 53.4            | 8.771                   | 8.707                  | -7.03                | -7.37                   | 28.53             | 1389      | 34.4342242 | -118.6473903 | Valve Adjustment:No Flow Measurement,High Temp                                       |
| CV-2314-PLF | 8/13/2026 2:35:00 PM  |      |      |     |         | 4450              |                   |         |       |                |               |                         |                        |                  |                 |                         |                        |                      |                         |                   |           |            |              | AtmA                                                                                 |
| CV-2314-PLF | 8/13/2026 2:42:37 PM  | 6.3  | 77.6 | 0.0 | 16.1    |                   |                   | 0.1     | 0.0   | 186.7          | 188.1         | -12.36                  | -12.01                 |                  |                 | 12.430                  | 12.118                 | -12.53               | -12.40                  | 28.49             | 1380      | 34.4346948 | -118.6467467 | Valve Adjustment:No Flow Measurement,High Temp                                       |
| CV-2314-PLF | 8/14/2026 7:25:00 AM  |      |      |     |         |                   | 120000            |         |       |                |               |                         |                        |                  |                 |                         |                        |                      |                         |                   |           |            |              | AirTech Lab; [User entered 12%]                                                      |
| CV-2314-PLF | 8/14/2026 7:25:00 AM  |      |      |     |         | 3200              |                   |         |       |                |               |                         |                        |                  |                 |                         |                        |                      |                         |                   |           |            |              | AirTech Lab                                                                          |
| CV-2314-PLF | 8/19/2026 9:10:21 AM  | 6.2  | 81.9 | 0.0 | 11.9    |                   |                   | 0.1     | 0.0   | 187.5          | 187.6         | -15.45                  | -15.50                 |                  |                 | 16.088                  | 16.091                 | -15.98               | -15.54                  | 28.53             | 1383      | 34.4346742 | -118.6467017 | Valve Adjustment:No Flow Measurement,High Temp                                       |
| CV-2314-PLF | 8/26/2026 8:32:14 AM  | 4.7  | 82.7 | 0.0 | 12.6    |                   |                   | 0.1     | 0.0   | 186.9          | 186.8         | -16.06                  | -15.54                 |                  |                 | 16.586                  | 16.181                 | -16.73               | -16.00                  | 28.51             | 1391      | 34.4347152 | -118.6467021 | Valve Adjustment:No Flow Measurement,High Temp                                       |
| CV-2315     | 8/3/2026 10:07:01 AM  | 2.2  | 75.2 | 0.0 | 22.6    |                   |                   | 0.0     | 0.0   | 177.0          | 177.1         | -3.72                   | -3.81                  |                  |                 | 3.817                   | 3.717                  | -4.48                | -4.19                   | 28.42             | 1383      | 34.4355060 | -118.6471910 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init<br>Flow<br>[scfm] | Adj<br>Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                             |
|------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|------------------------|-----------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|--------------------------------------------------------------------------------------|
| CV-2321    | 8/11/2026 7:55:00 AM  |            |            |           |                | 3340                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                |
| CV-2321    | 8/11/2026 8:00:41 AM  | 25.3       | 72.6       | 0.4       | 1.7            |                         |                         | 0.3     | 4.3          | 146.5                | 146.5               | -3.78                        | -3.81                       |                        |                       | 0.537                        | 0.534                       | -21.77                    | -21.71                       | 28.55                  | 1406         | 34.4346378 | -118.6453679 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                     |
| CV-2321    | 8/17/2026 2:19:43 PM  | 19.0       | 73.0       | 0.2       | 7.8            |                         |                         | 0.3     | 39.0         | 147.2                | 147.6               | -3.66                        | -2.73                       | 39.2                   | 33.8                  | 4.447                        | 3.292                       | -15.53                    | -16.04                       | 28.52                  | 1396         | 34.4352940 | -118.6458200 | Valve Adjustment:High Temp;Decreased Flow/Vacuum,Barely Open                         |
| CV-2321    | 8/18/2026 10:21:52 AM | 35.0       | 64.7       | 0.3       | 0.0            |                         |                         | 0.5     | 0.0          | 146.9                | 147.0               | -3.14                        | -3.14                       |                        |                       | 0.175                        | 0.212                       | -18.48                    | -18.67                       | 28.58                  | 1392         | 34.4346440 | -118.6453595 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                     |
| CV-2321    | 8/18/2026 10:25:00 AM |            |            |           |                | 4270                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                |
| CV-2321    | 8/25/2026 1:57:55 PM  | 32.9       | 66.9       | 0.2       | 0.0            |                         |                         | 0.5     | 0.0          | 147.8                | 147.8               | -1.66                        | -1.58                       | 9.3                    | 9.6                   | 0.058                        | 0.062                       | -17.80                    | -17.73                       | 28.54                  | 1394         | 34.4346417 | -118.6453937 | Valve Adjustment:High Temp                                                           |
| CV-2322    | 8/5/2026 9:55:00 AM   |            |            |           |                |                         | 107900                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA; [User entered 10.79%]                                                         |
| CV-2322    | 8/6/2026 9:54:39 AM   | 6.3        | 74.1       | 0.0       | 19.6           |                         |                         | 0.1     | 0.0          | 175.6                | 175.5               | -11.67                       | -11.68                      |                        |                       | 12.371                       | 12.275                      | -11.91                    | -11.81                       | 28.6                   | 1377         | 34.4353059 | -118.6475518 | Valve Adjustment:No Flow Measurement,High Temp                                       |
| CV-2322    | 8/6/2026 9:55:00 AM   |            |            |           |                |                         | 107900                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA; [User entered 10.79%]                                                         |
| CV-2322    | 8/6/2026 9:55:00 AM   |            |            |           |                | 1970                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                |
| CV-2322    | 8/11/2026 10:19:00 AM | 7.1        | 73.9       | 0.8       | 18.2           |                         |                         | 0.1     | 22.8         | 184.0                | 184.2               | -9.83                        | -9.76                       |                        |                       | 10.111                       | 10.002                      | -9.20                     | -9.25                        | 28.64                  | 1367         | 34.4352545 | -118.6475522 | Valve Adjustment:NSPS/EG CAI,High Temp                                               |
| CV-2322    | 8/11/2026 10:20:04 AM | 7.7        | 76.7       | 0.8       | 14.8           |                         |                         | 0.1     | 18.5         | 182.5                | 185.2               | -9.76                        | -9.76                       |                        |                       | 10.032                       | 10.063                      | -9.07                     | -9.18                        | 28.62                  | 1379         | 34.4352637 | -118.6475202 | Valve Adjustment:NSPS/EG CAI,High Temp                                               |
| CV-2322    | 8/13/2026 9:37:10 AM  | 13.9       | 81.2       | 0.1       | 4.8            |                         |                         | 0.2     | 48.0         | 183.7                | 183.2               | -7.41                        | -7.33                       |                        |                       | 7.852                        | 7.737                       | -7.72                     | -7.75                        | 28.57                  | 1393         | 34.4352819 | -118.6475213 | Valve Adjustment:No Flow Measurement,High Temp                                       |
| CV-2322    | 8/13/2026 9:40:00 AM  |            |            |           |                | 2610                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                |
| CV-2322    | 8/19/2026 8:51:11 AM  | 9.0        | 83.0       | 0.0       | 8.0            |                         |                         | 0.1     | 0.0          | 182.9                | 184.4               | -7.68                        | -7.53                       |                        |                       | 7.922                        | 7.888                       | -7.83                     | -7.81                        | 28.53                  | 1367         | 34.4352734 | -118.6475404 | Valve Adjustment:No Flow Measurement,High Temp                                       |
| CV-2322    | 8/26/2026 8:58:55 AM  | 2.7        | 79.0       | 0.0       | 18.3           |                         |                         | 0.0     | 0.0          | 175.0                | 174.9               | -9.24                        | -9.44                       |                        |                       | 9.840                        | 9.991                       | -9.46                     | -9.87                        | 28.53                  | 1380         | 34.4352719 | -118.6475405 | Valve Adjustment:No Flow Measurement,High Temp                                       |
| CV-2324    | 8/17/2026 12:27:25 PM | 46.2       | 43.1       | 0.0       | 10.7           |                         |                         | 1.1     | 0.0          | 125.0                | 125.0               | -1.08                        | -1.07                       | 5.4                    | 5.9                   | 0.019                        | 0.023                       | -16.46                    | -16.21                       | 28.62                  | 1391         | 34.4344950 | -118.6442588 | Valve Adjustment:Audible Flow,Barely Open                                            |
| CV-2326    | 8/4/2026 7:50:00 AM   |            |            |           |                |                         | 137700                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA; [User entered 13.77%]                                                         |
| CV-2326    | 8/4/2026 7:50:00 AM   |            |            |           |                | 3080                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                |
| CV-2326    | 8/4/2026 7:55:27 AM   | 13.0       | 58.8       | 0.0       | 28.2           |                         |                         | 0.2     | 0.0          | 166.9                | 166.9               | -7.16                        | -7.12                       |                        |                       | 7.440                        | 7.447                       | -11.61                    | -11.49                       | 28.45                  | 1367         | 34.4361126 | -118.6504150 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed |
| CV-2326    | 8/12/2026 10:25:00 AM |            |            |           |                | 2480                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                |
| CV-2326    | 8/12/2026 10:25:46 AM | 34.1       | 65.9       | 0.0       | 0.0            |                         |                         | 0.5     | 0.0          | 170.3                | 170.3               | -5.39                        | -5.39                       |                        |                       | 5.723                        | 5.923                       | -7.07                     | -7.07                        | 28.55                  | 1384         | 34.4361290 | -118.6504428 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed |
| CV-2326    | 8/17/2026 2:35:00 PM  |            |            |           |                | 3470                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                |
| CV-2326    | 8/17/2026 2:37:57 PM  | 31.1       | 62.9       | 0.0       | 6.0            |                         |                         | 0.5     | 0.0          | 167.7                | 167.8               | -4.72                        | -4.68                       |                        |                       | 4.997                        | 4.953                       | -7.09                     | -7.12                        | 28.57                  | 1367         | 34.4361229 | -118.6504754 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed |
| CV-2326    | 8/24/2026 2:35:50 PM  | 20.8       | 68.3       | 0.0       | 10.9           |                         |                         | 0.3     | 0.0          | 172.0                | 171.9               | -3.65                        | -3.56                       |                        |                       | 3.560                        | 3.525                       | -5.96                     | -5.98                        | 28.53                  | 1366         | 34.4361081 | -118.6504325 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed |
| CV-2326    | 8/31/2026 2:32:01 PM  | 10.1       | 66.1       | 0.0       | 23.8           |                         |                         | 0.2     | 0.0          | 170.0                | 168.8               | -4.52                        | -2.17                       |                        |                       | 4.497                        | 2.133                       | -6.34                     | -6.27                        | 28.55                  | 1366         | 34.4361168 | -118.6504574 | Valve Adjustment:No Flow Measurement,High O2,Decreased Flow/Vacuum                   |
| CV-2326    | 8/31/2026 2:32:45 PM  | 10.1       | 69.0       | 0.0       | 20.9           |                         |                         | 0.1     | 0.0          | 170.2                | 170.2               | -3.20                        | -3.09                       |                        |                       | 3.117                        | 3.013                       | -6.35                     | -6.34                        | 28.55                  | 1367         | 34.4361160 | -118.6504561 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed |
| CV-2327    | 8/11/2026 8:57:51 AM  | 11.3       | 75.4       | 1.2       | 12.1           |                         |                         | 0.1     | 10.1         | 184.1                | 184.0               | -5.05                        | -5.05                       |                        |                       | 5.460                        | 5.424                       | -8.78                     | -8.78                        | 28.62                  | 1364         | 34.4348918 | -118.6479333 | Valve Adjustment:No Flow Measurement,High Temp                                       |
| CV-2327    | 8/11/2026 9:00:00 AM  |            |            |           |                | 2900                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                |
| CV-2327    | 8/19/2026 9:24:15 AM  | 12.5       | 78.5       | 0.2       | 8.8            |                         |                         | 0.2     | 44.0         | 111.7                | 111.7               | -3.44                        | -3.35                       |                        |                       | 3.432                        | 3.349                       | -5.97                     | -5.83                        | 28.57                  | 1364         | 34.4349018 | -118.6479525 | Valve Adjustment:No Flow Measurement,High Temp                                       |
| CV-2328    | 8/5/2026 10:12:00 AM  |            |            |           |                |                         | 48200                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA; [User entered 4.82%]                                                          |
| CV-2328    | 8/5/2026 10:12:00 AM  |            |            |           |                | 1040                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                |
| CV-2328    | 8/11/2026 8:55:00 AM  |            |            |           |                |                         | 110000                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab; [User entered 11%]                                                      |
| CV-2328    | 8/11/2026 8:55:00 AM  |            |            |           |                | 1200                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab                                                                          |
| CV-2328    | 8/11/2026 9:13:16 AM  | 30.9       | 69.1       | 0.0       | 0.0            |                         |                         | 0.4     | 0.0          | 177.3                | 177.4               | -0.47                        | -0.47                       | 23.5                   | 23.3                  | 1.407                        | 1.385                       | -10.48                    | -10.36                       | 28.63                  | 1362         | 34.4343414 | -118.6483276 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                     |
| CV-2328    | 8/11/2026 9:20:00 AM  |            |            |           |                | 1770                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                |
| CV-2328    | 8/19/2026 9:45:37 AM  | 42.4       | 57.6       | 0.0       | 0.0            |                         |                         | 0.7     | 0.0          | 154.6                | 154.5               | -4.33                        | -4.31                       | 16.5                   | 11.5                  | 0.681                        | 0.329                       | -6.46                     | -6.40                        | 28.58                  | 1353         | 34.4343148 | -118.6483360 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                     |
| CV-2328    | 8/26/2026 9:18:53 AM  | 24.6       | 67.5       | 0.0       | 7.9            |                         |                         | 0.4     | 0.0          | 151.7                | 151.7               | -6.57                        | -6.40                       | 10.9                   | 13.5                  | 0.299                        | 0.457                       | -9.60                     | -9.14                        | 28.56                  | 1366         | 34.4343252 | -118.6483798 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                     |
| CV-2333    | 8/3/2026 8:06:27 AM   | 0.8        | 77.9       | 0.0       | 21.3           |                         |                         | 0.0     | 0.0          | 185.2                | 185.4               | -7.64                        | -6.42                       |                        |                       | 7.832                        | 6.590                       | -8.72                     | -7.37                        | 28.42                  | 1367         | 34.4365200 | -118.6473853 | Valve Adjustment:No Flow Measurement,High Temp                                       |
| CV-2333    | 8/3/2026 8:10:00 AM   |            |            |           |                |                         | 189600                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA; [User entered 18.96%]                                                         |
| CV-2333    | 8/3/2026 8:10:00 AM   |            |            |           |                | 5310                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                |
| CV-2333    | 8/6/2026 8:00:00 AM   |            |            |           |                |                         | 110000                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab; [User entered 11%]                                                      |
| CV-2333    | 8/6/2026 8:00:00 AM   |            |            |           |                | 1700                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab                                                                          |
| CV-2333    | 8/10/2026 8:13:41 AM  | 1.5        | 68.2       | 0.0       | 30.3           |                         |                         | 0.0     | 0.0          | 185.8                | 185.8               | -6.48                        | -6.39                       |                        |                       | 6.726                        | 6.700                       | -6.92                     | -6.69                        | 28.54                  | 1374         | 34.4365279 | -118.6473863 | Valve Adjustment:No Flow Measurement,High O2                                         |
| CV-2333    | 8/10/2026 8:18:00 AM  |            |            |           |                | 4870                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                |
| CV-2333    | 8/17/2026 7:40:00 AM  |            |            |           |                | 4830                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                |
| CV-2333    | 8/17/2026 7:40:02 AM  | 3.3        | 78.3       | 0.0       | 18.4           |                         |                         | 0.0     | 0.0          | 184.8                | 184.9               | -6.73                        | -6.76                       |                        |                       | 6.802                        | 6.771                       | -7.58                     | -7.07                        | 28.64                  | 1364         | 34.4365079 | -118.6473844 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init<br>Flow<br>[scfm] | Adj<br>Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                                            |
|------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|------------------------|-----------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|
| CV-2333    | 8/24/2026 8:09:19 AM  | 3.5        | 80.0       | 0.0       | 16.5           |                         |                         | 0.0     | 0.0          | 194.8                | 194.9               | -3.25                        | -3.28                       |                        |                       | 3.226                        | 3.282                       | -6.36                     | -6.51                        | 28.6                   | 1366         | 34.4365082 | -118.6473788 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                |
| CV-2333    | 8/31/2026 7:56:50 AM  | 1.0        | 72.9       | 0.0       | 26.1           |                         |                         | 0.0     | 0.0          | 193.5                | 193.5               | -3.56                        | -3.56                       |                        |                       | 3.565                        | 3.555                       | -6.27                     | -6.13                        | 28.49                  | 1378         | 34.4365129 | -118.6473489 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                |
| CV-2334    | 8/6/2026 8:10:00 AM   |            |            |           |                |                         | 60000                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab; [User entered 6.0%]                                                                                                                    |
| CV-2334    | 8/6/2026 8:10:00 AM   |            |            |           |                | 950                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab                                                                                                                                         |
| CV-2334    | 8/13/2026 12:45:25 PM | 7.0        | 79.7       | 0.0       | 13.3           |                         |                         | 0.1     | 0.0          | 136.0                | 136.0               | -0.92                        | -0.98                       | 2.4                    | 6.1                   | 0.015                        | 0.104                       | -2.30                     | -2.07                        | 28.61                  | 1356         | 34.4366673 | -118.6467135 | Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header                                                                                     |
| CV-2334    | 8/13/2026 12:46:31 PM | 6.5        | 80.9       | 0.0       | 12.6           |                         |                         | 0.1     | 0.0          | 136.0                | 136.0               | -0.81                        | -0.71                       | 7.1                    | 7.3                   | 0.143                        | 0.149                       | -2.33                     | -1.91                        | 28.61                  | 1354         | 34.4366978 | -118.6466987 |                                                                                                                                                     |
| CV-2334    | 8/18/2026 9:23:38 AM  | 2.6        | 76.6       | 0.0       | 20.7           |                         |                         | 0.0     | 0.0          | 134.2                | 134.6               | -0.76                        | -0.82                       | 5.0                    | 3.1                   | 0.071                        | 0.027                       | -1.71                     | -1.64                        | 28.61                  | 1348         | 34.4367218 | -118.6467432 | Valve Adjustment:High Temp,Surging Liquid in Header                                                                                                 |
| CV-2334    | 8/18/2026 9:24:29 AM  | 2.6        | 78.4       | 0.0       | 19.1           |                         |                         | 0.0     | 0.0          | 134.6                | 134.3               | -0.97                        | -0.65                       | 9.4                    | 7.8                   | 0.246                        | 0.171                       | -2.64                     | -2.01                        | 28.61                  | 1362         | 34.4367105 | -118.6467465 | Valve Adjustment:High Temp                                                                                                                          |
| CV-2335    | 8/3/2026 8:58:45 AM   | 53.1       | 44.8       | 0.0       | 2.1            |                         |                         | 1.2     | 0.0          | 100.0                | 100.7               | -0.47                        | -0.47                       |                        |                       | 0.461                        | 0.457                       | -8.14                     | -8.07                        | 28.42                  | 1346         | 34.4363842 | -118.6509633 | Valve Adjustment:Barely Open                                                                                                                        |
| CV-2335    | 8/17/2026 9:13:33 AM  | 53.7       | 44.5       | 0.0       | 1.8            |                         |                         | 1.2     | 0.0          | 94.3                 | 94.6                | -0.19                        | -0.18                       |                        |                       | 0.176                        | 0.175                       | -6.19                     | -6.31                        | 28.64                  | 1329         | 34.4364252 | -118.6509850 | Valve Adjustment:Barely Open                                                                                                                        |
| CV-2336    | 8/3/2026 9:01:52 AM   | 2.2        | 9.0        | 18.5      | 70.3           |                         |                         | 0.2     | 3.8          | 83.8                 | 84.2                | -9.97                        | -10.04                      |                        |                       | 10.253                       | 10.278                      | -10.04                    | -10.02                       | 28.42                  | 1351         | 34.4359870 | -118.6508947 | Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)                                                   |
| CV-2336    | 8/17/2026 9:18:09 AM  | 9.9        | 19.0       | 16.4      | 54.7           |                         |                         | 0.5     | 3.3          | 80.6                 | 80.7                | -7.68                        | -6.71                       |                        |                       | 7.947                        | 6.993                       | -7.58                     | -7.38                        | 28.65                  | 1336         | 34.4360053 | -118.6508915 | Valve Adjustment:High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In)                                                               |
| CV-2337    | 8/4/2026 2:00:15 PM   | 5.0        | 77.1       | 0.0       | 17.9           |                         |                         | 0.1     | 0.0          | 153.5                | 153.4               | -5.00                        | -5.00                       |                        |                       | 0.000                        | 0.000                       | -8.50                     | -8.52                        | 28.58                  | 1321         | 34.4354627 | -118.6507510 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                |
| CV-2337    | 8/4/2026 2:15:00 PM   |            |            |           |                |                         | 81600                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA; [User entered 8.16%]                                                                                                                         |
| CV-2337    | 8/4/2026 2:15:00 PM   |            |            |           |                | 2440                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                               |
| CV-2337    | 8/11/2026 1:46:38 PM  | 17.5       | 71.7       | 0.6       | 10.2           |                         |                         | 0.2     | 17.0         | 140.5                | 140.3               | -8.77                        | -8.76                       | 8.0                    | 9.7                   | 0.185                        | 0.270                       | -9.34                     | -9.43                        | 28.64                  | 1331         | 34.4354702 | -118.6507708 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                                                                                    |
| CV-2337    | 8/12/2026 9:00:00 AM  |            |            |           |                |                         | 92000                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab; [User entered 9.2%]                                                                                                                    |
| CV-2337    | 8/12/2026 9:00:00 AM  |            |            |           |                | 2000                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab                                                                                                                                         |
| CV-2337    | 8/13/2026 10:10:00 AM |            |            |           |                | 5490                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                               |
| CV-2337    | 8/18/2026 1:54:21 PM  | 25.3       | 74.5       | 0.2       | 0.0            |                         |                         | 0.3     | 0.0          | 153.3                | 153.2               | -3.03                        | -3.05                       |                        |                       | 0.000                        | 0.000                       | -6.02                     | -6.27                        | 28.61                  | 1339         | 34.4354492 | -118.6507548 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                                                                                    |
| CV-2337    | 8/18/2026 2:10:00 PM  |            |            |           |                | 3910                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                               |
| CV-2337    | 8/24/2026 1:53:59 PM  | 25.6       | 74.4       | 0.0       | 0.0            |                         |                         | 0.3     | 0.0          | 145.9                | 146.3               | -2.15                        | -2.08                       |                        |                       | 0.000                        | 0.000                       | 0.34                      | 0.34                         | 28.62                  | 1336         | 34.4354682 | -118.6507883 | Valve Adjustment:High Temp                                                                                                                          |
| CV-2337    | 8/31/2026 2:10:00 PM  | 4.5        | 72.1       | 0.0       | 23.4           |                         |                         | 0.1     | 0.0          | 153.7                | 154.2               | -1.73                        | -1.64                       | 28.6                   | 28.1                  | 2.365                        | 2.282                       | -5.42                     | -5.19                        | 28.62                  | 1331         | 34.4354688 | -118.6507867 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                                                                                    |
| CV-2338    | 8/4/2026 1:49:19 PM   | 2.1        | 80.3       | 0.0       | 17.6           |                         |                         | 0.0     | 0.0          | 155.7                | 158.1               | -2.02                        | -2.28                       |                        |                       | 1.974                        | 2.187                       | -2.01                     | -2.04                        | 28.6                   | 1292         | 34.4348607 | -118.6504628 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                |
| CV-2338    | 8/4/2026 2:00:00 PM   |            |            |           |                |                         | 136000                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA; [User entered 13.6%]                                                                                                                         |
| CV-2338    | 8/4/2026 2:00:00 PM   |            |            |           |                | 940                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                               |
| CV-2338    | 8/11/2026 1:35:00 PM  |            |            |           |                | 1390                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                               |
| CV-2338    | 8/11/2026 1:36:38 PM  | 9.6        | 74.9       | 0.0       | 15.5           |                         |                         | 0.1     | 0.0          | 181.7                | 181.6               | -3.03                        | -3.06                       |                        |                       | 3.036                        | 3.058                       | -3.12                     | -3.35                        | 28.68                  | 1318         | 34.4348477 | -118.6504652 | Valve Adjustment:No Flow Measurement,High O2;Well Condition:Lorentz Pump Installed                                                                  |
| CV-2338    | 8/18/2026 1:42:24 PM  | 28.9       | 70.9       | 0.1       | 0.1            |                         |                         | 0.4     | 1.0          | 158.1                | 159.9               | -5.74                        | -5.69                       |                        |                       | 6.066                        | 5.981                       | -5.87                     | -5.74                        | 28.65                  | 1310         | 34.4348473 | -118.6504798 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                |
| CV-2338    | 8/18/2026 1:54:00 PM  |            |            |           |                | 1480                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                               |
| CV-2338    | 8/24/2026 1:39:37 PM  | 27.5       | 71.0       | 0.0       | 1.5            |                         |                         | 0.4     | 0.0          | 182.3                |                     | -3.03                        |                             |                        |                       | 3.033                        |                             | -2.66                     |                              | 28.64                  | 1314         | 34.4348352 | -118.6504850 | Valve Adjustment:No Flow Measurement,High Temp                                                                                                      |
| CV-2338    | 8/31/2026 2:04:29 PM  | 2.3        | 70.4       | 0.2       | 27.1           |                         |                         | 0.0     | 135.5        | 158.3                | 158.6               | -4.09                        | -4.14                       |                        |                       | 3.963                        | 4.107                       | -3.71                     | -3.99                        | 28.62                  | 1320         | 34.4348460 | -118.6504726 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                |
| CV-2339    | 8/14/2026 8:56:34 AM  | 2.2        | 65.5       | 3.6       | 28.7           |                         |                         | 0.0     | 8.0          | 83.8                 | 77.9                | -9.73                        | -9.59                       |                        |                       | 9.986                        | 9.843                       | -9.77                     | -9.85                        | 28.64                  | 1306         | 34.4342222 | -118.6502625 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                              |
| CV-2339    | 8/19/2026 10:39:34 AM | 2.9        | 66.5       | 3.3       | 27.3           |                         |                         | 0.0     | 8.3          | 127.3                | 128.3               | -5.79                        | -5.77                       |                        |                       | 6.256                        | 6.191                       | -5.87                     | -5.84                        | 28.59                  | 1309         | 34.4341808 | -118.6502563 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed                                |
| CV-2341    | 8/6/2026 9:30:31 AM   | 20.9       | 62.0       | 1.1       | 16.0           |                         |                         | 0.3     | 14.5         | 150.0                | 91.8                | -17.08                       | -4.95                       |                        |                       | 17.371                       | 5.227                       | -17.48                    | -17.68                       | 28.63                  | 1323         | 34.4336468 | -118.6501858 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed |
| CV-2341    | 8/6/2026 9:32:29 AM   | 21.2       | 60.2       | 1.3       | 17.3           |                         |                         | 0.4     | 13.3         | 150.0                | 150.0               | -1.96                        | -1.88                       |                        |                       | 1.948                        | 1.868                       | -17.72                    | -17.52                       | 28.62                  | 1322         | 34.4336383 | -118.6501838 | Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed                      |
| CV-2341    | 8/6/2026 1:23:53 PM   | 21.1       | 68.8       | 0.0       | 10.1           |                         |                         | 0.3     | 0.0          | 119.5                | 122.2               | 1.18                         | -3.51                       |                        |                       | 0.000                        | 3.503                       | -13.69                    | -13.73                       | 28.6                   | 1303         | 34.4336246 | -118.6501858 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum                                                                                |
| CV-2341    | 8/6/2026 1:25:52 PM   | 18.7       | 68.3       | 0.0       | 13.0           |                         |                         | 0.3     | 0.0          | 122.9                | 123.2               | -3.84                        | -3.83                       |                        |                       | 3.826                        | 3.828                       | -13.66                    | -13.56                       | 28.6                   | 1308         | 34.4336250 | -118.6501827 | Valve Adjustment:No Flow Measurement;Well Condition:Pnumatic Pump Installed                                                                         |
| CV-2341    | 8/12/2026 8:55:00 AM  |            |            |           |                |                         | 2100                    |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab; [User entered 0.21%]                                                                                                                   |
| CV-2341    | 8/12/2026 8:55:00 AM  |            |            |           |                | 0                       |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab                                                                                                                                         |
| CV-2341    | 8/25/2026 9:53:17 AM  | 23.4       | 52.8       | 1.0       | 22.8           |                         |                         | 0.4     | 22.8         | 135.0                | 101.9               | -8.81                        | -0.56                       |                        |                       | 9.258                        | 0.546                       | -10.55                    | -10.51                       | 28.63                  | 1304         | 34.4336262 | -118.6501837 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)                           |
| CV-2341    | 8/25/2026 9:54:29 AM  | 24.2       | 54.3       | 0.9       | 20.6           |                         |                         | 0.4     | 22.9         | 135.0                | 135.0               | -0.96                        | -0.92                       |                        |                       | 0.944                        | 0.899                       | -10.53                    | -10.51                       | 28.64                  | 1319         | 34.4336248 | -118.6501920 | Valve Adjustment:High Temp,Barely Open,Valve 100% Closed,Surging Liquid in Header                                                                   |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name  | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init<br>Flow<br>[scfm] | Adj<br>Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                             |                                   |
|-------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|------------------------|-----------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|--------------------------------------------------------------------------------------|-----------------------------------|
| CV-2342A-PL | 8/4/2026 2:33:56 PM   | 3.0        | 74.8       | 0.0       | 22.2           |                         |                         | 0.0     | 0.0          | 159.9                | 141.7               | -9.88                        | -10.03                      |                        |                       | 10.009                       | 10.244                      | -9.08                     | -9.10                        | 28.63                  | 1284         | 34.4342193 | -118.6508288 | Valve Adjustment:No Flow Measurement,High Temp                                       |                                   |
| CV-2342A-PL | 8/4/2026 2:40:00 PM   |            |            |           |                |                         | 107600                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                      | AtmAA; [User entered 10.76%]      |
| CV-2342A-PL | 8/4/2026 2:40:00 PM   |            |            |           |                | 340                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                      | AtmAA                             |
| CV-2342A-PL | 8/12/2026 8:20:00 AM  |            |            |           |                | 1070                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                      | AtmAA                             |
| CV-2342A-PL | 8/12/2026 8:21:06 AM  | 10.7       | 73.2       | 0.0       | 16.1           |                         |                         | 0.1     | 0.0          | 154.0                | 154.5               | -7.48                        | -7.31                       |                        |                       | 7.752                        | 7.660                       | -11.02                    | -11.16                       | 28.64                  | 1290         | 34.4342262 | -118.6508403 | Valve Adjustment:No Flow Measurement,High Temp                                       |                                   |
| CV-2342A-PL | 8/20/2026 9:51:59 AM  | 35.1       | 64.9       | 0.0       | 0.0            |                         |                         | 0.5     | 0.0          | 173.4                | 173.4               | -4.79                        | -4.74                       |                        |                       | 4.725                        | 4.765                       | -7.01                     | -6.93                        | 28.68                  | 1279         | 34.4342310 | -118.6508266 | Valve Adjustment:No Flow Measurement,High Temp                                       |                                   |
| CV-2342A-PL | 8/25/2026 10:19:56 AM | 30.9       | 64.0       | 0.0       | 5.1            |                         |                         | 0.5     | 0.0          | 161.6                | 161.6               | -1.80                        | -1.80                       |                        |                       | 1.816                        | 1.816                       | -3.97                     | -3.97                        | 28.71                  | 1285         | 34.4342283 | -118.6508382 | Valve Adjustment:No Flow Measurement,High Temp                                       |                                   |
| CV-2343-PLF | 8/4/2026 2:24:06 PM   | 3.1        | 78.0       | 0.0       | 18.9           |                         |                         | 0.0     | 0.0          | 143.8                | 144.3               | -8.25                        | -8.17                       |                        |                       | 8.444                        | 8.389                       | -11.51                    | -11.50                       | 28.63                  | 1279         | 34.4332347 | -118.6506727 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed |                                   |
| CV-2343-PLF | 8/4/2026 2:35:00 PM   |            |            |           |                |                         | 80500                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                      | AtmAA; [User entered 8.05%]       |
| CV-2343-PLF | 8/4/2026 2:35:00 PM   |            |            |           |                | 1600                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                      | AtmAA                             |
| CV-2343-PLF | 8/17/2026 10:09:23 AM | 2.0        | 72.6       | 0.9       | 24.5           |                         |                         | 0.0     | 27.2         | 155.6                | 157.1               | -6.40                        | -5.89                       |                        |                       | 6.818                        | 6.089                       | -6.43                     | -5.92                        | 28.73                  | 1279         | 34.4332330 | -118.6506935 | Valve Adjustment: NSPS/EG CAI,High Temp                                              |                                   |
| CV-2343-PLF | 8/17/2026 10:09:54 AM | 2.2        | 73.8       | 0.6       | 23.4           |                         |                         | 0.0     | 39.0         | 159.5                | 156.1               | -6.42                        | -5.39                       |                        |                       | 6.732                        | 5.686                       | -6.22                     | -5.92                        | 28.74                  | 1279         | 34.4332400 | -118.6506842 | Valve Adjustment: NSPS/EG CAI,High Temp                                              |                                   |
| CV-2343-PLF | 8/17/2026 10:56:00 AM |            |            |           |                | 4080                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                      | AtmAA                             |
| CV-2343-PLF | 8/25/2026 9:36:57 AM  | 10.1       | 73.3       | 0.4       | 16.2           |                         |                         | 0.1     | 40.5         | 160.1                | 159.8               | -6.25                        | -5.08                       |                        |                       | 6.286                        | 5.157                       | -0.09                     | -0.17                        | 28.71                  | 1290         | 34.4332433 | -118.6506828 | Valve Adjustment:No Flow Measurement,High Temp                                       |                                   |
| CV-2344     | 8/4/2026 7:40:00 AM   |            |            |           |                | 210                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                      | AirTech Lab                       |
| CV-2344     | 8/4/2026 7:40:00 AM   |            |            |           |                |                         |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                      | AirTech Lab                       |
| CV-2344     | 8/4/2026 2:18:08 PM   | 8.6        | 74.6       | 0.0       | 16.8           |                         |                         | 0.1     | 0.0          | 145.5                | 145.3               | -5.70                        | -5.71                       |                        |                       | 5.892                        | 5.894                       | -13.02                    | -13.10                       | 28.63                  | 1280         | 34.4329727 | -118.6504115 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed |                                   |
| CV-2344     | 8/4/2026 2:30:00 PM   |            |            |           |                |                         | 13400                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                      | AtmAA; [User entered 1.34%]       |
| CV-2344     | 8/4/2026 2:30:00 PM   |            |            |           |                | 184                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                      | AtmAA                             |
| CV-2344     | 8/12/2026 8:05:00 AM  |            |            |           |                | 2510                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                      | AtmAA                             |
| CV-2344     | 8/12/2026 8:10:00 AM  | 19.0       | 73.9       | 0.0       | 7.1            |                         |                         | 0.3     | 0.0          | 153.8                | 153.9               | -5.37                        | -5.39                       |                        |                       | 5.525                        | 5.624                       | -15.02                    | -15.17                       | 28.64                  | 1280         | 34.4329745 | -118.6504405 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed |                                   |
| CV-2344     | 8/18/2026 2:17:23 PM  | 35.5       | 64.3       | 0.2       | 0.0            |                         |                         | 0.6     | 0.0          | 153.1                | 153.1               | -4.75                        | -4.74                       |                        |                       | 5.152                        | 5.089                       | -11.93                    | -11.97                       | 28.64                  | 1302         | 34.4329678 | -118.6504455 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed |                                   |
| CV-2344     | 8/18/2026 2:20:00 PM  |            |            |           |                | 2700                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                      | AtmAA                             |
| CV-2344     | 8/25/2026 9:06:11 AM  | 27.3       | 70.4       | 0.0       | 2.3            |                         |                         | 0.4     | 0.0          | 147.6                | 148.7               | -4.95                        | -4.90                       |                        |                       | 4.957                        | 4.913                       | -11.82                    | -12.33                       | 28.69                  | 1295         | 34.4329873 | -118.6504345 | Valve Adjustment:No Flow Measurement,High Temp                                       |                                   |
| CV-2345     | 8/4/2026 7:35:00 AM   |            |            |           |                |                         | 16000                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                      | AirTech Lab; [User entered 1.6%]  |
| CV-2345     | 8/4/2026 7:35:00 AM   |            |            |           |                | 180                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                      | AirTech Lab                       |
| CV-2345     | 8/5/2026 9:49:45 AM   | 22.1       | 64.5       | 0.4       | 13.0           |                         |                         | 0.3     | 32.5         | 136.0                | 136.1               | -6.20                        | -6.18                       | 73.4                   | 73.4                  | 6.061                        | 6.051                       |                           |                              | 28.58                  | 1276         | 34.4327515 | -118.6501038 | NSPS/EG CAI,High Temp                                                                |                                   |
| CV-2345     | 8/5/2026 9:50:34 AM   | 21.7       | 64.6       | 0.4       | 13.3           |                         |                         | 0.3     | 33.3         | 135.8                | 135.8               | -6.23                        | -6.22                       | 73.3                   | 73.2                  | 6.039                        | 6.035                       |                           |                              | 28.58                  | 1273         | 34.4327320 | -118.6501713 | NSPS/EG CAI,High Temp                                                                |                                   |
| CV-2345     | 8/17/2026 10:05:19 AM | 18.6       | 62.3       | 0.0       | 19.1           |                         |                         | 0.3     | 0.0          | 141.3                | 141.4               | -5.39                        | -5.39                       |                        |                       | 5.570                        | 5.516                       | -12.62                    | -12.64                       | 28.73                  | 1300         | 34.4327350 | -118.6501817 | Valve Adjustment: NSPS/EG CAI,High Temp                                              |                                   |
| CV-2345     | 8/17/2026 10:05:37 AM | 18.8       | 62.7       | 0.0       | 18.5           |                         |                         | 0.3     | 0.0          | 141.9                | 141.9               | -5.39                        | -5.39                       |                        |                       | 5.595                        | 5.577                       | -12.96                    | -12.81                       | 28.72                  | 1297         | 34.4327312 | -118.6501762 | Valve Adjustment: NSPS/EG CAI,High Temp                                              |                                   |
| CV-2346     | 8/4/2026 7:30:00 AM   |            |            |           |                |                         | 61000                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                      | AirTech Lab; [User entered 6.1%]  |
| CV-2346     | 8/4/2026 7:30:00 AM   |            |            |           |                | 630                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                      | AirTech Lab                       |
| CV-2346     | 8/4/2026 2:16:37 PM   | 2.1        | 80.7       | 0.0       | 17.2           |                         |                         | 0.0     | 0.0          | 185.3                | 185.6               | -11.47                       | -11.34                      |                        |                       | 11.620                       | 11.516                      | -13.38                    | -13.38                       | 28.62                  | 1297         | 34.4325825 | -118.6500545 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed |                                   |
| CV-2346     | 8/4/2026 2:25:00 PM   |            |            |           |                |                         | 74700                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                      | AtmAA; [User entered 7.47%]       |
| CV-2346     | 8/4/2026 2:25:00 PM   |            |            |           |                | 1510                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                      | AtmAA                             |
| CV-2346     | 8/12/2026 7:53:58 AM  | 5.5        | 80.9       | 0.2       | 13.4           |                         |                         | 0.1     | 67.0         | 185.8                | 185.6               | -10.30                       | -10.15                      |                        |                       | 10.517                       | 10.431                      | -15.54                    | -15.49                       | 28.6                   | 1315         | 34.4325973 | -118.6500536 | Valve Adjustment:No Flow Measurement,High Temp                                       |                                   |
| CV-2346     | 8/12/2026 7:55:00 AM  |            |            |           |                | 1965                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                      | AtmAA                             |
| CV-2346     | 8/18/2026 2:11:48 PM  | 15.2       | 76.2       | 0.3       | 8.3            |                         |                         | 0.2     | 27.7         | 177.9                | 177.3               | -10.49                       | -9.95                       |                        |                       | 10.921                       | 10.288                      | -12.54                    | -12.41                       | 28.64                  | 1301         | 34.4325780 | -118.6500777 | Valve Adjustment:No Flow Measurement,High Temp                                       |                                   |
| CV-2346     | 8/18/2026 2:15:00 PM  |            |            |           |                | 3230                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                      | AtmAA                             |
| CV-2346     | 8/25/2026 8:58:33 AM  | 11.7       | 74.6       | 0.0       | 13.7           |                         |                         | 0.2     | 0.0          | 180.9                | 178.8               | -9.91                        | -9.44                       |                        |                       | 9.945                        | 9.386                       | -12.33                    | -12.37                       | 28.67                  | 1316         | 34.4326138 | -118.6500538 | Valve Adjustment:No Flow Measurement,High Temp                                       |                                   |
| CV-2347     | 8/4/2026 7:25:00 AM   |            |            |           |                |                         | 21000                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                      | AirTech Lab; [User entered 2.1%]  |
| CV-2347     | 8/4/2026 7:25:00 AM   |            |            |           |                | 250                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                      | AirTech Lab                       |
| CV-2347     | 8/5/2026 10:16:04 AM  | 17.5       | 43.9       | 0.4       | 38.2           |                         |                         | 0.4     | 95.5         | 113.5                | 112.8               | -7.12                        | -6.92                       | 81.6                   | 81.6                  | 6.669                        | 6.649                       |                           |                              | 28.57                  | 1263         | 34.4323465 | -118.6498732 | ,                                                                                    |                                   |
| CV-2347     | 8/17/2026 9:44:20 AM  | 13.0       | 40.0       | 0.0       | 47.0           |                         |                         | 0.3     | 0.0          | 137.5                | 137.7               | -5.72                        | -5.68                       |                        |                       | 5.785                        | 5.767                       | -12.68                    | -11.59                       | 28.69                  | 1303         | 34.4323532 | -118.6498330 | Valve Adjustment: NSPS/EG CAI,High Temp                                              |                                   |
| CV-2347     | 8/17/2026 9:44:46 AM  | 13.4       | 42.7       | 0.0       | 43.9           |                         |                         | 0.3     | 0.0          | 138.0                | 138.3               | -5.72                        | -5.72                       |                        |                       | 5.867                        | 5.885                       | -13.69                    | -14.03                       | 28.69                  | 1303         | 34.4323562 | -118.6498240 | Valve Adjustment: NSPS/EG CAI,High Temp                                              |                                   |
| CV-2348     | 8/4/2026 7:20:00 AM   |            |            |           |                |                         | 3900                    |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                      | AirTech Lab; [User entered 0.39%] |
| CV-2348     | 8/4/2026 7:20:00 AM   |            |            |           |                | 28                      |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                      | AirTech Lab                       |
| CV-2348     | 8/5/2026 10:19:12 AM  | 22.6       | 44.0       | 0.0       | 33.4           |                         |                         | 0.5     | 0.0          | 131.6                | 131.7               | -14.39                       | -14.32                      | 0.0                    | 0.0                   |                              |                             | -14.32                    |                              | 28.57                  | 1299         | 34.4321600 | -118.6496803 | NSPS/EG CAI,High Temp                                                                |                                   |
| CV-2348     | 8/5/2026 10:19:46 AM  | 22.8       | 46.3       | 0.0       | 30.9           |                         |                         | 0.5     | 0.0          | 131.7                | 131.7               | -14.15                       | -14.18                      | 0.0                    | 0.0                   |                              |                             | -14.21                    |                              | 28.57                  | 1299         | 34.4320763 | -118.6496157 | NSPS/EG CAI,High Temp                                                                |                                   |
| CV-2348     | 8/17/2026 9:38:46 AM  | 16.3       | 41.7       | 0.0       | 42.0           |                         |                         | 0.4     | 0.0          | 133.8                | 133.8               | -12.79                       | -12.79                      |                        |                       | 12.938                       | 12.974                      | 0.34                      | 0.34                         | 28.69                  | 1311         | 34.4321492 | -118.6496088 | Valve Adjustment: NSPS/EG CAI,High Temp                                              |                                   |
| CV-2348     | 8/17/2026 9:39:22 AM  | 17.8       | 45.6       | 0.0       | 36.6           |                         |                         | 0.4     | 0.0          | 133.8                | 133.8               | -12.46                       | -12.56                      |                        |                       | 12.633                       | 12.666                      | 0.34                      | 0.34                         | 28.69                  | 1323         | 34.4321508 | -118.6495935 | Valve Adjustment: NSPS/EG CAI,High Temp                                              |                                   |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name  | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init Flow<br>[scfm] | Adj Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                      |
|-------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|---------------------|--------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|-------------------------------------------------------------------------------------------------------------------------------|
| CV-2349     | 8/3/2026 9:20:00 AM   |            |            |           |                |                         | 45000                   |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AirTech Lab; [User entered 4.5%]                                                                                              |
| CV-2349     | 8/3/2026 9:20:00 AM   |            |            |           |                | 580                     |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AirTech Lab                                                                                                                   |
| CV-2349     | 8/5/2026 8:08:00 AM   |            |            |           |                |                         | 1000                    |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA<br>&it;0.10; [User entered 0.10%]                                                                                       |
| CV-2349     | 8/6/2026 8:08:00 AM   |            |            |           |                | 2.21                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                         |
| CV-2349     | 8/6/2026 9:33:43 AM   | 5.0        | 74.1       | 0.0       | 20.9           |                         |                         | 0.1     | 0.0          | 177.1                | 177.5               | -8.58                        | -8.42                       |                     |                    | 9.169                        | 9.016                       | -9.55                     | -9.39                        | 28.72                  | 1266         | 34.4331451 | -118.6512477 | Valve Adjustment:No Flow Measurement,High O2;Well Condition:Lorentz Pump Installed                                            |
| CV-2349     | 8/13/2026 8:00:36 AM  | 12.8       | 73.5       | 0.1       | 13.6           |                         |                         | 0.2     | 136.0        | 179.7                | 179.9               | -3.26                        | -2.94                       |                     |                    | 3.405                        | 2.906                       | -4.10                     | -3.62                        | 28.64                  | 1276         | 34.4331303 | -118.6512678 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                          |
| CV-2349     | 8/13/2026 8:10:00 AM  |            |            |           |                | 4420                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                         |
| CV-2349     | 8/20/2026 10:25:53 AM | 44.9       | 55.0       | 0.0       | 0.1            |                         |                         | 0.8     | 0.0          | 182.6                | 179.9               | 0.43                         | 0.42                        |                     |                    | 0.000                        | 0.000                       | 0.91                      | 0.93                         | 28.71                  | 1273         | 34.4331498 | -118.6512310 | Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.;Well Condition:Lorentz Pump Installed                   |
| CV-2349     | 8/25/2026 10:38:45 AM | 27.7       | 71.2       | 0.0       | 1.1            |                         |                         | 0.4     | 0.0          | 171.4                | 171.7               | 0.49                         | 1.05                        |                     |                    | 0.000                        | 0.000                       | 0.91                      | 0.48                         | 28.7                   | 1254         | 34.4331556 | -118.6512542 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                          |
| CV-2350     | 8/4/2026 7:45:00 AM   |            |            |           |                |                         | 88000                   |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AirTech Lab; [User entered 8.8%]                                                                                              |
| CV-2350     | 8/4/2026 7:45:00 AM   |            |            |           |                | 1600                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AirTech Lab                                                                                                                   |
| CV-2350     | 8/5/2026 8:38:12 AM   | 4.7        | 80.2       | 0.4       | 14.7           |                         |                         | 0.1     | 36.8         | 118.5                | 119.0               | -11.92                       | -13.57                      | 0.0                 | 0.0                |                              |                             | -12.24                    |                              | 28.62                  | 1289         | 34.4327475 | -118.6508855 |                                                                                                                               |
| CV-2350     | 8/25/2026 1:40:22 PM  | 4.5        | 76.5       | 0.3       | 18.7           |                         |                         | 0.1     | 62.3         | 116.7                | 116.9               | -6.16                        | -6.08                       |                     |                    | 6.221                        | 6.257                       | -6.26                     | -6.55                        | 28.63                  | 1277         | 34.4327952 | -118.6509222 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected           |
| CV-2351     | 8/3/2026 7:50:00 AM   |            |            |           |                |                         | 58000                   |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AirTech Lab; [User entered 5.8%]                                                                                              |
| CV-2351     | 8/3/2026 7:50:00 AM   |            |            |           |                | 440                     |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AirTech Lab                                                                                                                   |
| CV-2351     | 8/14/2026 8:13:45 AM  | 6.2        | 41.5       | 9.2       | 43.1           |                         |                         | 0.1     | 4.7          | 72.9                 | 72.8                | -1.12                        | -1.06                       |                     |                    | 1.116                        | 1.135                       | -1.05                     | -0.98                        | 28.67                  | 1288         | 34.4351545 | -118.6511562 | Valve Adjustment:NSPS/EG CAI,High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In)                             |
| CV-2351     | 8/14/2026 8:14:16 AM  | 6.4        | 40.6       | 9.3       | 43.7           |                         |                         | 0.2     | 4.7          | 73.1                 | 73.0                | -1.36                        | -1.08                       |                     |                    | 1.295                        | 1.136                       | -1.21                     | -1.05                        | 28.67                  | 1284         | 34.4351543 | -118.6511545 | Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)                             |
| CV-2351     | 8/19/2026 8:02:10 AM  | 3.8        | 15.1       | 15.8      | 65.3           |                         |                         | 0.3     | 4.1          | 89.3                 | 89.4                | -4.64                        | -4.55                       |                     |                    | 4.804                        | 4.632                       | -4.79                     | -4.59                        | 28.61                  | 1270         | 34.4351400 | -118.6511505 | Valve Adjustment:High O2,Surging Liquid in Well (Watered In)                                                                  |
| CV-2351     | 8/19/2026 8:03:16 AM  | 3.5        | 15.3       | 15.8      | 65.5           |                         |                         | 0.2     | 4.1          | 89.7                 | 89.8                | -4.16                        | -4.43                       |                     |                    | 4.362                        | 4.551                       | -4.26                     | -4.51                        | 28.61                  | 1283         | 34.4351382 | -118.6511572 | Valve Adjustment:High O2                                                                                                      |
| CV-2352     | 8/3/2026 7:55:00 AM   |            |            |           |                |                         | 15000                   |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AirTech Lab; [User entered 1.5%]                                                                                              |
| CV-2352     | 8/3/2026 7:55:00 AM   |            |            |           |                | 97                      |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AirTech Lab                                                                                                                   |
| CV-2352     | 8/14/2026 8:08:45 AM  | 2.1        | 77.2       | 0.4       | 20.3           |                         |                         | 0.0     | 50.8         | 194.6                | 194.5               | -1.90                        | -1.97                       |                     |                    | 1.912                        | 1.939                       | -2.10                     | -2.25                        | 28.67                  | 1297         | 34.4348678 | -118.6510448 | Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open,Surging Liquid in Header;Well Condition:Pnumatic Pump Installed            |
| CV-2352     | 8/14/2026 8:09:18 AM  | 2.1        | 78.5       | 0.3       | 19.1           |                         |                         | 0.0     | 63.7         | 195.1                | 195.3               | -2.03                        | -2.13                       |                     |                    | 1.984                        | 2.100                       | -2.20                     | -2.40                        | 28.67                  | 1298         | 34.4348657 | -118.6510533 | Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)                                       |
| CV-2352     | 8/17/2026 12:59:08 PM | 14.8       | 85.0       | 0.2       | 0.0            |                         |                         | 0.2     | 0.0          | 136.2                | 135.5               | -5.91                        | -5.92                       | 66.7                | 68.9               | 5.573                        | 5.940                       |                           |                              | 28.65                  | 1293         | 34.4348630 | -118.6510652 | No Flow Measurement,                                                                                                          |
| CV-2352     | 8/19/2026 8:19:01 AM  | 6.6        | 67.5       | 1.3       | 24.6           |                         |                         | 0.1     | 19.6         | 127.6                | 127.6               | -5.35                        | -5.30                       |                     |                    | 5.487                        | 5.491                       | -5.45                     | -5.37                        | 28.64                  | 1283         | 34.4348618 | -118.6510570 | Well Comment:Pump is off;Well Condition:Pnumatic Pump Installed                                                               |
| CV-2353-PLF | 8/5/2026 8:05:00 AM   |            |            |           |                |                         | 130000                  |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AirTech Lab; [User entered 13%]                                                                                               |
| CV-2353-PLF | 8/5/2026 8:05:00 AM   |            |            |           |                | 330                     |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AirTech Lab                                                                                                                   |
| CV-2353-PLF | 8/13/2026 9:50:13 AM  | 2.9        | 72.0       | 1.8       | 23.3           |                         |                         | 0.0     | 12.9         | 148.4                | 146.6               | -6.08                        | -5.72                       |                     |                    | 6.348                        | 5.995                       | -6.08                     | -5.79                        | 28.62                  | 1281         | 34.4345515 | -118.6509115 | Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected |
| CV-2353-PLF | 8/17/2026 12:51:09 PM | 18.9       | 81.1       | 0.0       | 0.0            |                         |                         | 0.2     | 0.0          | 138.9                | 139.9               | -6.69                        | -6.28                       | 0.0                 | 0.0                | 6.499                        | 6.167                       | -7.32                     |                              | 28.73                  | 1276         | 34.4346800 | -118.6511180 | No Flow Measurement,                                                                                                          |
| CV-2354     | 8/3/2026 9:15:00 AM   |            |            |           |                |                         | 81000                   |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AirTech Lab; [User entered 8.1%]                                                                                              |
| CV-2354     | 8/3/2026 9:15:00 AM   |            |            |           |                | 720                     |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AirTech Lab                                                                                                                   |
| CV-2354     | 8/6/2026 7:50:00 AM   |            |            |           |                |                         | 161100                  |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA; [User entered 16.11%]                                                                                                  |
| CV-2354     | 8/6/2026 7:50:00 AM   |            |            |           |                | 2330                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                         |
| CV-2354     | 8/6/2026 8:51:11 AM   | 7.2        | 65.6       | 1.9       | 25.3           |                         |                         | 0.1     | 13.3         | 124.6                | 128.1               | -6.55                        | -3.85                       |                     |                    | 6.928                        | 3.831                       | -6.69                     | -6.25                        | 28.72                  | 1267         | 34.4337072 | -118.6513668 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed                    |
| CV-2354     | 8/6/2026 9:21:29 AM   | 7.4        | 65.0       | 1.7       | 25.9           |                         |                         | 0.1     | 15.2         | 122.4                | 125.3               | -2.88                        | -1.45                       |                     |                    | 2.858                        | 1.439                       | -5.80                     | -4.67                        | 28.72                  | 1273         | 34.4337018 | -118.6513691 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum,Barely Open                                              |
| CV-2354     | 8/6/2026 9:27:51 AM   | 7.4        | 68.3       | 1.0       | 23.3           |                         |                         | 0.1     | 23.3         | 125.8                | 125.3               | -1.26                        | -1.25                       |                     |                    | 1.249                        | 1.240                       | -4.37                     | -4.59                        | 28.72                  | 1276         | 34.4336952 | -118.6513661 | Valve Adjustment:No Flow Measurement,Barely Open;Well Condition:Lorentz Pump Installed                                        |
| CV-2354     | 8/12/2026 8:59:52 AM  | 21.8       | 65.4       | 0.6       | 12.2           |                         |                         | 0.3     | 20.3         | 109.8                | 109.7               | -0.51                        | -0.45                       |                     |                    | 0.510                        | 0.431                       | -0.37                     | -0.34                        | 28.68                  |              |            |              | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                          |
| CV-2354     | 8/13/2026 8:24:35 AM  | 18.2       | 71.9       | 0.0       | 9.9            |                         |                         | 0.3     | 0.0          | 104.7                | 104.6               | -7.01                        | -6.91                       |                     |                    | 7.274                        | 7.232                       | -7.19                     | -7.19                        | 28.68                  |              |            |              | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                          |
| CV-2354     | 8/25/2026 10:25:34 AM | 21.6       | 54.9       | 4.5       | 19.0           |                         |                         | 0.4     | 4.2          | 129.2                | 128.9               | -4.71                        | -1.86                       |                     |                    | 0.473                        | 0.109                       | 0.67                      | 0.67                         | 28.72                  |              |            |              | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed                    |
| CV-24001    | 8/3/2026 8:52:32 AM   | 52.8       | 47.2       | 0.0       | 0.0            |                         |                         | 1.1     | 0.0          | 112.6                | 112.6               | -1.46                        | -1.46                       |                     |                    | 1.448                        | 1.450                       | -7.75                     | -7.84                        | 28.41                  | 1359         | 34.4366668 | -118.6509285 | Valve Adjustment:Barely Open                                                                                                  |
| CV-24001    | 8/17/2026 9:08:27 AM  | 52.4       | 47.6       | 0.0       | 0.0            |                         |                         | 1.1     | 0.0          | 107.7                | 107.9               | -1.05                        | -1.06                       |                     |                    | 1.045                        | 1.046                       | -6.14                     | -6.40                        | 28.64                  | 1345         | 34.4366755 | -118.6509178 | Valve Adjustment:Barely Open                                                                                                  |
| CV-24002    | 8/3/2026 8:46:25 AM   | 42.8       | 51.2       | 0.0       | 6.0            |                         |                         | 0.8     | 0.0          | 113.4                | 113.5               | -3.81                        | -3.82                       |                     |                    | 3.813                        | 3.816                       | -14.76                    | -14.73                       | 28.41                  | 1363         | 34.4367268 | -118.6504998 | Valve Adjustment:Barely Open                                                                                                  |

**All LFG Extraction Wells - August 2020**  
**Chiquita Canyon Landfill**

| Point Name | Record Date           | CH4  | CO2  | O2  | Bal Gas | CO Reading (ppmv) | H2 Reading (ppmv) | CH4:CO2 | BalO2 | Init Temp (°F) | Adj Temp (°F) | Init Stat Press (\"H2O) | Adj Stat Press (\"H2O) | Init Flow (scfm) | Adj Flow (scfm) | Init Diff Press (\"H2O) | Adj Diff Press (\"H2O) | Sys Pressure (\"H2O) | Adj Avail Press (\"H2O) | Baro Press (\"Hg) | Elev (ft) | Latitude   | Longitude    | Comments                                                                                                       |
|------------|-----------------------|------|------|-----|---------|-------------------|-------------------|---------|-------|----------------|---------------|-------------------------|------------------------|------------------|-----------------|-------------------------|------------------------|----------------------|-------------------------|-------------------|-----------|------------|--------------|----------------------------------------------------------------------------------------------------------------|
|            |                       | [%]  | [%]  | [%] | [%]     |                   |                   |         | [%]   | [°F]           | [°F]          | [\"H2O]                 | [\"H2O]                | [scfm]           | [scfm]          | [\"H2O]                 | [\"H2O]                | [\"H2O]              | [\"H2O]                 | [\"Hg]            | [ft]      |            |              |                                                                                                                |
| CV-24002   | 8/17/2026 9:02:33 AM  | 44.1 | 44.6 | 0.0 | 11.3    |                   |                   | 1.0     | 0.0   | 112.1          | 112.1         | -3.67                   | -3.66                  |                  |                 | 3.677                   | 3.670                  | -12.70               | -12.58                  | 28.64             | 1356      | 34.4367417 | -118.6504138 | Valve Adjustment-Surging Liquid in Header,Surging Liquid in Well (Watered In)                                  |
| CV-24003   | 8/3/2026 8:33:09 AM   | 38.4 | 56.2 | 0.0 | 5.4     |                   |                   | 0.7     | 0.0   | 122.2          | 121.8         | -1.20                   | -1.11                  | 7.1              | 5.6             | 0.139                   | 0.086                  | -15.33               | -13.79                  | 28.41             | 1365      | 34.4368862 | -118.6501057 | Valve Adjustment-Decreased Flow/Vacuum                                                                         |
| CV-24003   | 8/17/2026 8:54:22 AM  | 38.1 | 55.3 | 0.0 | 6.6     |                   |                   | 0.7     | 0.0   | 114.9          | 114.9         | -0.86                   | -0.85                  | 1.5              | 0.8             | 0.006                   | 0.002                  | -12.90               | -12.85                  | 28.63             | 1360      | 34.4368760 | -118.6500753 | Valve Adjustment:Barely Open                                                                                   |
| CV-24004   | 8/3/2026 8:28:34 AM   | 26.0 | 44.9 | 0.1 | 29.0    |                   |                   | 0.6     | 290.0 | 119.4          | 122.6         | -2.14                   | -2.01                  | 13.3             | 12.3            | 0.485                   | 0.414                  | -11.79               | -11.42                  | 28.41             | 1350      | 34.4370462 | -118.6496885 | Valve Adjustment-Decreased Flow/Vacuum                                                                         |
| CV-24004   | 8/17/2026 8:51:23 AM  | 35.4 | 55.9 | 0.0 | 8.7     |                   |                   | 0.6     | 0.0   | 122.2          | 121.1         | -1.87                   | -1.65                  | 6.6              | 11.1            | 0.120                   | 0.333                  | -9.09                | -9.06                   | 28.63             | 1361      | 34.4370808 | -118.6496847 | Valve Adjustment-Decreased Flow/Vacuum,Barely Open                                                             |
| CV-24006   | 8/3/2026 9:18:31 AM   | 21.6 | 72.1 | 0.8 | 5.5     |                   |                   | 0.3     | 6.9   | 126.2          | 127.1         | -0.89                   | -0.88                  | 12.6             | 11.9            | 0.440                   | 0.392                  | -5.74                | -5.73                   | 28.41             | 1377      | 34.4363682 | -118.6504607 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)                      |
| CV-24006   | 8/17/2026 8:34:18 AM  | 27.1 | 62.9 | 0.7 | 9.3     |                   |                   | 0.4     | 13.3  | 133.4          | 133.2         | -1.07                   | -0.97                  | 11.9             | 12.2            | 0.395                   | 0.416                  | -4.66                | -4.79                   | 28.6              | 1379      | 34.4363622 | -118.6504560 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open                                       |
| CV-24006   | 8/17/2026 8:35:00 AM  | 26.8 | 64.2 | 0.6 | 8.4     |                   |                   | 0.4     | 14.0  | 133.2          | 133.1         | -0.95                   | -0.97                  | 10.8             | 14.0            | 0.321                   | 0.541                  | -4.85                | -4.78                   | 28.6              | 1379      | 34.4363487 | -118.6504503 | Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)            |
| CV-24007   | 8/3/2026 9:21:31 AM   | 19.4 | 56.0 | 3.3 | 21.3    |                   |                   | 0.3     | 6.5   | 147.4          | 147.6         | -0.82                   | -0.82                  | 25.3             | 25.3            | 1.835                   | 1.836                  | -14.23               | -14.69                  | 28.4              | 1379      | 34.4365130 | -118.6501117 | Valve Adjustment:High Temp,Barely Open                                                                         |
| CV-24007   | 8/3/2026 9:21:57 AM   | 19.7 | 56.0 | 3.3 | 21.0    |                   |                   | 0.4     | 6.4   | 147.5          | 147.6         | -0.83                   | -0.83                  | 25.2             | 25.0            | 1.827                   | 1.796                  | -14.53               | -14.34                  | 28.4              | 1381      | 34.4365192 | -118.6501080 | Valve Adjustment:High Temp,Barely Open                                                                         |
| CV-24007   | 8/6/2026 7:50:00 AM   |      |      |     |         |                   | 99000             |         |       |                |               |                         |                        |                  |                 |                         |                        |                      |                         |                   |           |            |              | AirTech Lab; [User entered 9.9%]                                                                               |
| CV-24007   | 8/6/2026 7:50:00 AM   |      |      |     |         | 820               |                   |         |       |                |               |                         |                        |                  |                 |                         |                        |                      |                         |                   |           |            |              | AirTech Lab                                                                                                    |
| CV-24007   | 8/12/2026 10:00:00 AM |      |      |     |         | 1380              |                   |         |       |                |               |                         |                        |                  |                 |                         |                        |                      |                         |                   |           |            |              | AtmAA                                                                                                          |
| CV-24007   | 8/12/2026 10:09:00 AM | 28.4 | 71.5 | 0.1 | 0.0     |                   |                   | 0.4     | 0.0   | 167.0          | 167.1         | 0.03                    | -0.80                  | 4.0              | 49.1            | 0.048                   | 7.167                  | -12.90               | -12.31                  | 28.54             | 1393      | 34.4365216 | -118.6501244 | Valve Comment:Water in;Valve Adjustment:High Temp,Increased Flow/Vacuum;Well Condition:Pnumatic Pump Installed |
| CV-24007   | 8/12/2026 10:12:04 AM | 37.7 | 60.4 | 1.9 | 0.0     |                   |                   | 0.6     | 0.0   | 167.0          | 167.0         | -0.79                   | -0.79                  | 49.9             | 49.9            | 7.423                   | 7.413                  | -12.05               | -12.03                  | 28.53             | 1396      | 34.4365231 | -118.6501365 | Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed                                              |
| CV-24007   | 8/17/2026 8:38:48 AM  | 18.7 | 58.5 | 2.2 | 20.6    |                   |                   | 0.3     | 9.4   | 157.1          | 157.3         | -1.25                   | -1.25                  | 53.1             | 52.0            | 8.262                   | 7.910                  | -13.68               | -13.26                  | 28.61             | 1376      | 34.4365468 | -118.6501285 | Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)                        |
| CV-24007   | 8/17/2026 2:05:00 PM  |      |      |     |         | 438               |                   |         |       |                |               |                         |                        |                  |                 |                         |                        |                      |                         |                   |           |            |              | AtmAA                                                                                                          |
| CV-24007   | 8/17/2026 2:23:05 PM  | 39.0 | 57.0 | 1.7 | 2.3     |                   |                   | 0.7     | 1.4   | 158.5          | 154.5         | -0.73                   | -1.38                  | 47.1             | 60.7            | 6.496                   | 10.799                 | -11.31               | -10.81                  | 28.59             | 1384      | 34.4365118 | -118.6501133 | Valve Adjustment:High Temp,Increased Flow/Vacuum;Well Condition:Pnumatic Pump Installed                        |
| CV-24007   | 8/17/2026 2:25:42 PM  | 41.3 | 50.4 | 1.9 | 6.4     |                   |                   | 0.8     | 3.4   | 154.2          | 154.2         | -1.39                   | -1.39                  | 61.1             | 61.1            | 10.960                  | 10.936                 | -10.83               | -10.86                  | 28.57             | 1382      | 34.4365127 | -118.6501189 | Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed                                              |
| CV-24007   | 8/24/2026 2:15:04 PM  | 11.0 | 70.6 | 0.0 | 18.4    |                   |                   | 0.2     | 0.0   | 145.1          | 145.1         | -3.63                   | -3.62                  | 49.3             | 48.9            | 7.026                   | 6.921                  | -10.27               | -10.15                  | 28.53             | 1369      | 34.4365111 | -118.6501189 | Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed                                              |
| CV-24007   | 8/31/2026 2:28:42 PM  | 37.7 | 50.1 | 0.0 | 12.2    |                   |                   | 0.8     | 0.0   | 146.2          | 146.2         | -3.89                   | -3.88                  | 50.7             | 50.7            | 7.470                   | 7.483                  | -10.40               | -10.40                  | 28.49             | 1374      | 34.4365144 | -118.6501223 | Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed                                              |
| CV-24008   | 8/3/2026 1:06:00 AM   |      |      |     |         | 1940              |                   |         |       |                |               |                         |                        |                  |                 |                         |                        |                      |                         |                   |           |            |              | AtmAA                                                                                                          |
| CV-24008   | 8/3/2026 1:06:00 PM   |      |      |     |         |                   | 181600            |         |       |                |               |                         |                        |                  |                 |                         |                        |                      |                         |                   |           |            |              | AtmAA; [User entered 18.16%]                                                                                   |
| CV-24008   | 8/3/2026 1:08:47 PM   | 5.1  | 77.5 | 0.0 | 17.4    |                   |                   | 0.1     | 0.0   | 178.2          | 178.2         | -8.51                   | -8.45                  | 38.1             | 47.7            | 1.048                   | 1.645                  | 0.34                 | 0.32                    | 28.39             | 1378      | 34.4366755 | -118.6496840 | Valve Adjustment:No Flow Measurement,High Temp                                                                 |
| CV-24008   | 8/10/2026 1:50:19 PM  | 31.2 | 68.8 | 0.0 | 0.0     |                   |                   | 0.5     | 0.0   | 178.3          | 178.6         | -8.07                   | -8.07                  | 106.2            | 106.5           | 8.184                   | 8.222                  | -8.74                | -8.76                   | 28.53             | 1371      | 34.4366786 | -118.6497087 | Valve Adjustment:No Flow Measurement,High Temp                                                                 |
| CV-24008   | 8/10/2026 1:55:00 PM  |      |      |     |         | 2420              |                   |         |       |                |               |                         |                        |                  |                 |                         |                        |                      |                         |                   |           |            |              | AtmAA                                                                                                          |
| CV-24008   | 8/17/2026 1:55:00 PM  |      |      |     |         | 2120              |                   |         |       |                |               |                         |                        |                  |                 |                         |                        |                      |                         |                   |           |            |              | AtmAA                                                                                                          |
| CV-24008   | 8/17/2026 2:01:05 PM  | 12.5 | 71.7 | 0.0 | 15.8    |                   |                   | 0.2     | 0.0   | 178.2          | 177.9         | -6.74                   | -6.44                  | 98.9             | 97.5            | 7.040                   | 6.830                  | -7.39                | -7.07                   | 28.57             | 1373      | 34.4366910 | -118.6497164 | Valve Adjustment:High Temp                                                                                     |
| CV-24008   | 8/24/2026 2:10:47 PM  | 12.3 | 71.1 | 0.0 | 16.6    |                   |                   | 0.2     | 0.0   | 185.7          | 185.8         | -3.22                   | -3.20                  | 66.9             | 66.7            | 3.213                   | 3.196                  | -3.39                | -3.37                   | 28.54             | 1377      | 34.4366769 | -118.6497065 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed                          |
| CV-24008   | 8/31/2026 2:24:04 PM  | 22.8 | 67.7 | 0.0 | 9.5     |                   |                   | 0.3     | 0.0   | 187.9          | 187.8         | -6.02                   | -6.02                  | 91.2             | 91.4            | 6.063                   | 6.095                  | -6.66                | -6.74                   | 28.53             | 1366      | 34.4366765 | -118.6496872 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed                          |
| CV-24009   | 8/3/2026 1:02:00 AM   |      |      |     |         |                   | 58650             |         |       |                |               |                         |                        |                  |                 |                         |                        |                      |                         |                   |           |            |              | AtmAA; [User entered 5.865%]                                                                                   |
| CV-24009   | 8/3/2026 1:02:00 PM   |      |      |     |         | 410               |                   |         |       |                |               |                         |                        |                  |                 |                         |                        |                      |                         |                   |           |            |              | AtmAA                                                                                                          |
| CV-24009   | 8/3/2026 1:05:02 PM   | 8.5  | 74.0 | 0.0 | 17.5    |                   |                   | 0.1     | 0.0   | 177.6          | 178.7         | 1.96                    | -2.09                  |                  |                 | 1.924                   | 0.000                  | -10.49               | -9.81                   | 28.42             | 1380      | 34.4368748 | -118.6493625 | Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum                               |
| CV-24009   | 8/3/2026 1:05:36 PM   | 5.1  | 78.4 | 0.0 | 16.5    |                   |                   | 0.1     | 0.0   | 178.7          | 178.7         | -2.17                   | -2.20                  |                  |                 | 0.000                   | 0.000                  | -9.53                | -9.77                   | 28.41             | 1379      | 34.4368889 | -118.6493530 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp                                                     |
| CV-24009   | 8/10/2026 1:45:00 PM  |      |      |     |         | 1080              |                   |         |       |                |               |                         |                        |                  |                 |                         |                        |                      |                         |                   |           |            |              | AtmAA                                                                                                          |
| CV-24009   | 8/10/2026 1:46:57 PM  | 35.1 | 64.9 | 0.0 | 0.0     |                   |                   | 0.5     | 0.0   | 161.4          | 161.4         | -6.61                   | -6.59                  |                  |                 | 0.000                   | 0.000                  | -8.71                | -8.42                   | 28.53             |           |            |              | Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed                                              |
| CV-24009   | 8/17/2026 1:45:00 PM  |      |      |     |         | 1290              |                   |         |       |                |               |                         |                        |                  |                 |                         |                        |                      |                         |                   |           |            |              | AtmAA                                                                                                          |
| CV-24009   | 8/17/2026 1:52:08 PM  | 18.8 | 74.2 | 0.0 | 7.0     |                   |                   | 0.3     | 0.0   | 172.1          | 172.1         | -3.84                   | -3.88                  |                  |                 | 0.059                   | 0.056                  | -7.55                | -7.79                   | 28.58             | 1375      | 34.4368674 | -118.6493593 | Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed                                              |
| CV-24009   | 8/24/2026 1:24:24 PM  | 15.8 | 73.8 | 0.2 | 10.2    |                   |                   | 0.2     | 51.0  | 164.8          | 164.8         | -4.88                   | -4.87                  |                  |                 | 0.240                   | 0.215                  | -7.22                | -7.41                   | 28.53             | 1368      | 34.4368650 | -118.6493579 | Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed                                              |
| CV-24009   | 8/31/2026 2:04:20 PM  | 18.5 | 73.2 | 0.1 | 8.2     |                   |                   | 0.3     | 82.0  | 164.7          | 164.7         | -4.86                   | -4.96                  |                  |                 | 0.050                   | 0.068                  | -6.52                | -6.78                   | 28.49             | 1365      | 34.4368709 | -118.6493625 | Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed                                              |
| CV-24010   | 8/11/2026 10:09:19 AM | 30.1 | 55.3 | 0.3 | 14.3    |                   |                   | 0.5     | 47.7  | 111.2          | 111.4         | -0.81                   | -0.80                  |                  |                 | 0.799                   | 0.789                  | -6.31                | -7.10                   | 28.6              | 1358      | 34.4370653 | -118.6489778 | Valve Adjustment:Barely Open                                                                                   |
| CV-24010   | 8/18/2026 12:32:45 PM | 35.2 | 49.2 | 0.1 | 15.6    |                   |                   | 0.7     | 194.6 | 108.3          | 108.1         | -1.23                   | -1.23                  |                  |                 | 1.232                   | 1.228                  | -4.85                | -4.44                   | 28.61             | 1335      | 34.4370505 | -118.6489757 |                                                                                                                |
| CV-24011   | 8/4/2026 7:55:00 AM   |      |      |     |         |                   | 155500            |         |       |                |               |                         |                        |                  |                 |                         |                        |                      |                         |                   |           |            |              | AtmAA; [User entered 15.55%]                                                                                   |
| CV-24011   | 8/4/2026 7:55:00 AM   |      |      |     |         | 2000              |                   |         |       |                |               |                         |                        |                  |                 |                         |                        |                      |                         |                   |           |            |              | AtmAA                                                                                                          |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init Flow<br>[scfm] | Adj Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                            |
|------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|---------------------|--------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|---------------------------------------------------------------------------------------------------------------------|
| CV-24011   | 8/4/2026 7:59:01 AM   | 11.8       | 66.4       | 0.0       | 21.8           |                         |                         | 0.2     | 0.0          | 187.3                | 187.4               | -3.10                        | -3.13                       | 43.7                | 46.8               | 5.911                        | 6.785                       | -10.30                    | -11.31                       | 28.45                  | 1363         | 34.4362080 | -118.6501714 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                                                    |
| CV-24011   | 8/11/2026 9:14:41 AM  | 13.3       | 65.3       | 0.0       | 21.4           |                         |                         | 0.2     | 0.0          | 187.3                | 187.5               | -2.45                        | -2.36                       | 45.4                | 41.7               | 6.323                        | 5.333                       | -8.44                     | -7.56                        | 28.62                  | 1371         | 34.4361865 | -118.6501802 | Valve Adjustment:NSPS/EG CAI,High Temp                                                                              |
| CV-24011   | 8/11/2026 9:15:00 AM  | 13.6       | 66.9       | 0.0       | 19.5           |                         |                         | 0.2     | 0.0          | 187.6                | 187.6               | -2.55                        | -2.55                       | 44.1                | 44.1               | 5.980                        | 5.980                       | -8.74                     | -8.74                        | 28.62                  | 1379         | 34.4361757 | -118.6501907 | Valve Adjustment:NSPS/EG CAI,High Temp                                                                              |
| CV-24011   | 8/12/2026 10:20:00 AM |            |            |           |                | 1940                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                               |
| CV-24011   | 8/12/2026 10:20:17 AM | 33.9       | 66.1       | 0.0       | 0.0            |                         |                         | 0.5     | 0.0          | 187.8                | 187.7               | -1.36                        | -1.34                       | 40.5                | 43.7               | 5.036                        | 5.875                       | -7.34                     | -8.15                        | 28.55                  | 1384         | 34.4362008 | -118.6501888 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                                                    |
| CV-24011   | 8/18/2026 7:45:00 AM  |            |            |           |                | 2090                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                               |
| CV-24011   | 8/18/2026 7:45:50 AM  | 16.6       | 70.9       | 0.0       | 12.5           |                         |                         | 0.2     | 0.0          | 187.9                | 187.9               | -1.64                        | -1.65                       | 39.5                | 39.2               | 4.782                        | 4.699                       | -8.02                     | -7.97                        | 28.57                  | 1369         | 34.4362021 | -118.6501902 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                                                    |
| CV-24011   | 8/24/2026 2:31:47 PM  | 25.7       | 64.8       | 0.0       | 9.5            |                         |                         | 0.4     | 0.0          | 189.0                | 188.8               | -0.31                        | -0.25                       | 39.8                | 38.8               | 4.865                        | 4.613                       | -5.08                     | -4.85                        | 28.53                  | 1372         | 34.4361945 | -118.6501861 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                                                    |
| CV-24011   | 8/31/2026 2:25:02 PM  | 8.2        | 61.6       | 0.0       | 30.2           |                         |                         | 0.1     | 0.0          | 187.7                | 187.8               | -1.34                        | -1.28                       | 39.2                | 39.4               | 4.695                        | 4.740                       | -5.40                     | -5.38                        | 28.58                  | 1364         | 34.4361807 | -118.6502071 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                                                    |
| CV-24012   | 8/4/2026 8:05:00 AM   |            |            |           |                |                         | 188800                  |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA; [User entered 18.88%]                                                                                        |
| CV-24012   | 8/4/2026 8:05:00 AM   |            |            |           |                | 2390                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                               |
| CV-24012   | 8/4/2026 8:05:35 AM   | 15.6       | 64.7       | 0.0       | 19.7           |                         |                         | 0.2     | 0.0          | 176.1                | 176.9               | -11.93                       | -11.82                      |                     |                    | 12.255                       | 12.159                      | -12.08                    | -12.15                       | 28.49                  | 1350         | 34.4361704 | -118.6493563 | Valve Adjustment:No Flow Measurement,High Temp                                                                      |
| CV-24012   | 8/10/2026 2:12:58 PM  | 17.5       | 76.9       | 0.1       | 5.5            |                         |                         | 0.2     | 55.0         | 177.9                | 178.5               | -8.36                        | -8.42                       |                     |                    | 8.369                        | 8.426                       | -8.95                     | -8.95                        | 28.53                  | 1357         | 34.4361674 | -118.6493445 | Valve Adjustment:No Flow Measurement,High Temp                                                                      |
| CV-24012   | 8/10/2026 2:20:00 PM  |            |            |           |                | 2540                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                               |
| CV-24012   | 8/18/2026 8:03:17 AM  | 8.7        | 66.1       | 0.0       | 25.2           |                         |                         | 0.1     | 0.0          | 180.8                | 181.9               | -8.37                        | -8.13                       |                     |                    | 8.727                        | 8.608                       | -8.66                     | -8.55                        | 28.6                   | 1365         | 34.4361959 | -118.6493798 | Valve Adjustment:No Flow Measurement,High Temp                                                                      |
| CV-24012   | 8/18/2026 8:05:00 AM  |            |            |           |                | 2140                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                               |
| CV-24012   | 8/25/2026 7:45:01 AM  | 6.6        | 79.1       | 0.0       | 14.3           |                         |                         | 0.1     | 0.0          | 183.4                | 183.5               | -8.88                        | -8.59                       |                     |                    | 9.186                        | 9.034                       | -9.54                     | -9.31                        | 28.6                   | 1362         | 34.4361769 | -118.6493767 | Valve Adjustment:No Flow Measurement,High Temp                                                                      |
| CV-24012   | 8/31/2026 2:42:42 PM  | 16.0       | 73.4       | 0.0       | 10.6           |                         |                         | 0.2     | 0.0          | 179.2                | 179.9               | -6.86                        | -6.70                       |                     |                    | 6.939                        | 6.694                       | -6.92                     | -6.74                        | 28.52                  | 1365         | 34.4361652 | -118.6493774 | Valve Adjustment:No Flow Measurement,High Temp                                                                      |
| CV-24013   | 8/10/2026 12:37:20 PM | 3.4        | 43.9       | 10.0      | 42.7           |                         |                         | 0.1     | 4.3          | 151.1                | 151.9               | -8.80                        | -8.40                       |                     |                    | 8.984                        | 8.592                       | -8.94                     | -8.80                        | 28.67                  | 1363         | 34.4366052 | -118.6492253 | Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Barely Open,Surging Liquid in Well (Watered In);Well Comment:No pump |
| CV-24013   | 8/10/2026 12:39:23 PM | 3.6        | 44.8       | 10.5      | 41.1           |                         |                         | 0.1     | 3.9          | 150.9                | 150.5               | -8.68                        | -8.73                       |                     |                    | 8.810                        | 8.863                       | -9.07                     | -9.14                        | 28.67                  | 1372         | 34.4366003 | -118.6492310 |                                                                                                                     |
| CV-24013   | 8/10/2026 1:50:00 PM  |            |            |           |                | 1750                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                               |
| CV-24013   | 8/20/2026 1:51:03 PM  | 15.5       | 61.6       | 4.4       | 18.5           |                         |                         | 0.3     | 4.2          | 165.1                | 164.8               | -5.87                        | -5.94                       |                     |                    | 5.986                        | 6.168                       | -6.57                     | -6.74                        | 28.53                  | 1370         | 34.4366035 | -118.6492366 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                |
| CV-24013   | 8/24/2026 2:02:09 PM  | 12.0       | 49.2       | 6.7       | 32.1           |                         |                         | 0.2     | 4.8          | 168.9                | 166.8               | -6.02                        | -2.97                       |                     |                    | 6.102                        | 2.895                       | -6.83                     | -6.40                        | 28.56                  | 1380         | 34.4366107 | -118.6492538 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed          |
| CV-24013   | 8/31/2026 2:15:15 PM  | 9.9        | 37.1       | 11.3      | 41.7           |                         |                         | 0.3     | 3.7          | 152.2                | 153.5               | -6.51                        | -2.59                       |                     |                    | 6.606                        | 2.586                       | -6.54                     | -6.68                        | 28.51                  | 1362         | 34.4366110 | -118.6492364 | Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed          |
| CV-24013   | 8/31/2026 2:20:29 PM  | 13.5       | 39.9       | 10.1      | 36.5           |                         |                         | 0.3     | 3.6          | 152.9                | 153.3               | -3.08                        | -3.04                       |                     |                    | 3.079                        | 3.048                       | -6.49                     | -6.50                        | 28.51                  | 1363         | 34.4366099 | -118.6492363 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                |
| CV-24014   | 8/3/2026 8:55:06 AM   | 1.5        | 64.5       | 0.0       | 34.0           |                         |                         | 0.0     | 0.0          | 180.7                | 180.6               | -4.63                        | -3.96                       | 38.8                | 35.8               | 4.619                        | 3.919                       | -8.37                     | -5.40                        | 28.44                  | 1384         | 34.4367783 | -118.6489599 | Valve Adjustment:No Flow Measurement,High Temp                                                                      |
| CV-24014   | 8/3/2026 9:00:00 AM   |            |            |           |                |                         | 182300                  |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA; [User entered 18.23%]                                                                                        |
| CV-24014   | 8/3/2026 9:00:00 AM   |            |            |           |                | 1310                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                               |
| CV-24014   | 8/10/2026 8:58:17 AM  | 4.4        | 71.3       | 0.0       | 24.3           |                         |                         | 0.1     | 0.0          | 180.2                | 180.4               | -4.31                        | -4.30                       | 37.5                | 37.5               | 4.292                        | 4.284                       | -7.95                     | -7.76                        | 28.57                  | 1366         | 34.4367781 | -118.6489464 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed                               |
| CV-24014   | 8/10/2026 9:10:00 AM  |            |            |           |                | 1440                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                               |
| CV-24014   | 8/17/2026 8:55:00 AM  |            |            |           |                | 1500                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                               |
| CV-24014   | 8/17/2026 8:56:15 AM  | 19.5       | 71.4       | 0.0       | 9.1            |                         |                         | 0.3     | 0.0          | 180.6                | 180.8               | -4.69                        | -4.69                       | 39.1                | 39.2               | 4.663                        | 4.671                       | -8.46                     | -8.44                        | 28.65                  | 1374         | 34.4367934 | -118.6489709 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed                               |
| CV-24014   | 8/24/2026 8:05:50 AM  | 4.2        | 82.1       | 0.1       | 13.6           |                         |                         | 0.1     | 136.0        | 184.0                | 183.6               | -4.82                        | -4.93                       | 39.6                | 40.0               | 4.827                        | 4.910                       | -6.75                     | -6.74                        | 28.58                  | 1376         | 34.4363852 | -118.6477172 | Valve Adjustment:No Flow Measurement,High Temp                                                                      |
| CV-24014   | 8/24/2026 8:45:28 AM  | 12.0       | 69.8       | 1.2       | 17.0           |                         |                         | 0.2     | 14.2         | 181.2                | 182.0               | -3.20                        | -3.20                       | 32.4                | 32.4               | 3.193                        | 3.190                       | -8.74                     | -8.79                        | 28.59                  | 1383         | 34.4367786 | -118.6489374 |                                                                                                                     |
| CV-24014   | 8/31/2026 9:14:56 AM  | 4.7        | 79.7       | 0.0       | 15.6           |                         |                         | 0.1     | 0.0          | 183.0                | 183.0               | -2.22                        | -2.15                       | 27.0                | 26.6               | 2.213                        | 2.146                       | -6.79                     | -6.23                        | 28.53                  | 1373         | 34.4367929 | -118.6489478 | Valve Adjustment:No Flow Measurement,High Temp                                                                      |
| CV-24015   | 8/3/2026 8:44:26 AM   | 1.2        | 69.7       | 0.0       | 29.1           |                         |                         | 0.0     | 0.0          | 188.4                | 188.3               | -2.65                        | -2.84                       |                     |                    | 2.625                        | 2.819                       | -7.05                     | -6.99                        | 28.45                  | 1376         | 34.4368769 | -118.6486329 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                |
| CV-24015   | 8/3/2026 8:46:00 AM   |            |            |           |                |                         | 188950                  |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA; [User entered 18.895%]                                                                                       |
| CV-24015   | 8/3/2026 8:46:00 AM   |            |            |           |                | 1095                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                               |
| CV-24015   | 8/10/2026 8:45:24 AM  | 5.0        | 72.2       | 0.2       | 22.6           |                         |                         | 0.1     | 113.0        | 187.7                | 187.9               | -2.30                        | -2.20                       |                     |                    | 2.288                        | 2.199                       | -6.11                     | -5.18                        | 28.57                  | 1359         | 34.4368868 | -118.6486282 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                |
| CV-24015   | 8/10/2026 8:55:00 AM  |            |            |           |                | 1665                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                               |
| CV-24015   | 8/17/2026 8:18:21 AM  | 11.3       | 73.3       | 0.0       | 15.4           |                         |                         | 0.2     | 0.0          | 183.5                | 183.0               | -2.99                        | -2.99                       |                     |                    | 2.979                        | 2.974                       | -6.96                     | -7.16                        | 28.64                  | 1369         | 34.4368637 | -118.6486279 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                |
| CV-24015   | 8/17/2026 8:20:00 AM  |            |            |           |                | 1480                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                               |
| CV-24015   | 8/24/2026 8:33:19 AM  | 10.6       | 71.9       | 0.0       | 17.5           |                         |                         | 0.1     | 0.0          | 185.8                | 186.3               | -3.24                        | -3.23                       |                     |                    | 3.245                        | 3.226                       | -6.54                     | -7.05                        | 28.6                   | 1362         | 34.4368740 | -118.6486024 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init<br>Flow<br>[scfm] | Adj<br>Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                        |                                 |
|------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|------------------------|-----------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|---------------------------------------------------------------------------------------------------------------------------------|---------------------------------|
| CV-24015   | 8/31/2026 9:00:30 AM  | 3.4        | 77.1       | 0.0       | 19.5           |                         |                         | 0.0     | 0.0          | 182.7                | 183.4               | -2.43                        | -2.20                       |                        |                       | 2.403                        | 2.171                       | -5.98                     | -5.05                        | 28.57                  | 1368         | 34.4368901 | -118.6486237 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                            |                                 |
| CV-24016   | 8/3/2026 2:35:11 PM   | 21.0       | 41.7       | 4.8       | 32.5           |                         |                         | 0.5     | 6.8          | 96.7                 | 96.7                | -1.99                        | -2.03                       |                        |                       | 0.000                        | 0.000                       | -8.16                     | -8.93                        | 28.37                  | 1360         | 34.4359140 | -118.6500997 | Valve Adjustment:Barely Open                                                                                                    |                                 |
| CV-24016   | 8/4/2026 7:45:00 AM   |            |            |           |                |                         | 85100                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                 | AtmAA; [User entered 8.51%]     |
| CV-24016   | 8/4/2026 7:45:00 AM   |            |            |           |                | 1270                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                 | AtmAA                           |
| CV-24016   | 8/4/2026 7:52:24 AM   | 13.4       | 64.8       | 0.0       | 21.8           |                         |                         | 0.2     | 0.0          | 173.1                | 173.3               | -7.08                        | -7.08                       |                        |                       | 7.398                        | 7.351                       | -8.61                     | -8.63                        | 28.45                  | 1368         | 34.4359322 | -118.6502191 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                            |                                 |
| CV-24016   | 8/5/2026 1:03:59 PM   | 13.9       | 54.9       | 0.0       | 31.2           |                         |                         | 0.3     | 0.0          | 141.3                | 143.1               | -6.48                        | -6.56                       |                        |                       | 6.462                        | 6.592                       | -7.51                     | -7.51                        | 28.56                  | 1364         | 34.4359060 | -118.6502513 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                            |                                 |
| CV-24016   | 8/11/2026 9:18:05 AM  | 12.2       | 45.3       | 0.0       | 42.5           |                         |                         | 0.3     | 0.0          | 91.4                 | 90.7                | -10.40                       | -8.47                       |                        |                       | 10.707                       | 8.821                       | -8.50                     | -8.48                        | 28.62                  | 1375         | 34.4358893 | -118.6502522 | Valve Adjustment:Decreased Flow/Vacuum                                                                                          |                                 |
| CV-24016   | 8/12/2026 10:29:01 AM | 40.8       | 41.6       | 0.0       | 17.6           |                         |                         | 1.0     | 0.0          | 159.4                | 159.4               | -4.47                        | -4.49                       |                        |                       | 5.034                        | 5.034                       | -7.41                     | -7.26                        | 28.55                  | 1376         | 34.4359074 | -118.6502443 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                            |                                 |
| CV-24016   | 8/12/2026 10:30:00 AM |            |            |           |                | 965                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                 | AtmAA                           |
| CV-24016   | 8/18/2026 7:50:00 AM  |            |            |           |                | 1000                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                 | AtmAA                           |
| CV-24016   | 8/18/2026 7:50:26 AM  | 16.1       | 69.0       | 0.0       | 14.9           |                         |                         | 0.2     | 0.0          | 159.8                | 159.8               | -6.43                        | -6.28                       |                        |                       | 6.558                        | 6.440                       | -7.75                     | -7.75                        | 28.57                  | 1375         | 34.4359158 | -118.6502579 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                            |                                 |
| CV-24016   | 8/25/2026 7:33:15 AM  | 19.5       | 47.5       | 0.0       | 33.0           |                         |                         | 0.4     | 0.0          | 162.2                | 162.0               | -6.68                        | -6.49                       |                        |                       | 6.893                        | 6.821                       | -8.09                     | -8.17                        | 28.59                  | 1366         | 34.4359112 | -118.6502619 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                            |                                 |
| CV-24016   | 8/31/2026 2:38:41 PM  | 14.0       | 42.5       | 0.1       | 43.4           |                         |                         | 0.3     | 434.0        | 149.9                | 150.0               | -5.35                        | -5.39                       |                        |                       | 5.458                        | 5.456                       | -5.41                     | -5.43                        | 28.58                  | 1368         | 34.4359073 | -118.6502610 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                            |                                 |
| CV-24017   | 8/4/2026 7:38:00 AM   |            |            |           |                | 121050                  |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                 | AtmAA; [User entered 12.105%]   |
| CV-24017   | 8/4/2026 7:38:00 AM   |            |            |           |                | 1030                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                 | AtmAA                           |
| CV-24017   | 8/4/2026 7:45:06 AM   | 15.1       | 70.6       | 0.5       | 13.8           |                         |                         | 0.2     | 27.6         | 179.5                | 179.9               | -7.79                        | -7.98                       |                        |                       | 7.973                        | 8.145                       | -11.62                    | -12.44                       | 28.45                  | 1363         | 34.4361121 | -118.6498225 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                            |                                 |
| CV-24017   | 8/10/2026 2:06:01 PM  | 33.5       | 66.2       | 0.3       | 0.0            |                         |                         | 0.5     | 0.0          | 188.9                | 188.9               | -4.56                        | -4.50                       |                        |                       | 4.554                        | 4.508                       | -7.77                     | -7.52                        | 28.53                  | 1364         | 34.4361339 | -118.6498156 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                            |                                 |
| CV-24017   | 8/10/2026 2:08:00 PM  |            |            |           |                | 1810                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                 | AtmAA                           |
| CV-24017   | 8/13/2026 9:40:00 AM  |            |            |           |                | 160000                  |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                 | AirTech Lab; [User entered 16%] |
| CV-24017   | 8/13/2026 9:40:00 AM  |            |            |           |                | 1300                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                 | AirTech Lab                     |
| CV-24017   | 8/18/2026 7:55:00 AM  |            |            |           |                | 1780                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                 | AtmAA                           |
| CV-24017   | 8/18/2026 7:55:27 AM  | 20.0       | 70.1       | 0.3       | 9.6            |                         |                         | 0.3     | 32.0         | 179.8                | 179.9               | -5.02                        | -4.95                       |                        |                       | 5.205                        | 5.079                       | -8.13                     | -8.88                        | 28.6                   | 1375         | 34.4361035 | -118.6498332 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                            |                                 |
| CV-24017   | 8/25/2026 7:37:48 AM  | 20.6       | 70.1       | 0.3       | 9.0            |                         |                         | 0.3     | 30.0         | 188.7                | 188.5               | -5.11                        | -5.05                       |                        |                       | 5.326                        | 5.234                       | -8.89                     | -8.72                        | 28.57                  | 1369         | 34.4361026 | -118.6498076 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                            |                                 |
| CV-24017   | 8/31/2026 2:36:27 PM  | 28.9       | 68.5       | 0.2       | 2.4            |                         |                         | 0.4     | 12.0         | 178.0                | 178.0               | -3.51                        | -3.46                       |                        |                       | 3.501                        | 3.510                       | -5.67                     | -6.06                        | 28.52                  | 1367         | 34.4360934 | -118.6498015 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                            |                                 |
| CV-24018   | 8/3/2026 2:39:12 PM   | 12.2       | 62.3       | 0.2       | 25.3           |                         |                         | 0.2     | 126.5        | 130.3                | 130.1               | -2.41                        | -2.26                       |                        |                       | 2.407                        | 2.247                       | -8.36                     | -8.44                        | 28.37                  | 1376         | 34.4356167 | -118.6500373 | Valve Adjustment:Decreased Flow/Vacuum                                                                                          |                                 |
| CV-24018   | 8/19/2026 9:15:18 AM  | 22.5       | 61.6       | 0.0       | 15.9           |                         |                         | 0.4     | 0.0          | 147.0                | 146.6               | -1.96                        | -1.20                       |                        |                       | 1.923                        | 1.174                       | -7.19                     | -7.29                        | 28.63                  | 1363         | 34.4355858 | -118.6500703 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed                              |                                 |
| CV-24018   | 8/19/2026 9:16:23 AM  | 17.9       | 64.5       | 0.0       | 17.6           |                         |                         | 0.3     | 0.0          | 146.4                | 146.5               | -1.13                        | -1.13                       |                        |                       | 1.106                        | 1.108                       | -7.11                     | -7.13                        | 28.63                  | 1373         | 34.4355885 | -118.6500645 |                                                                                                                                 |                                 |
| CV-24018   | 8/24/2026 1:18:06 PM  | 29.1       | 63.6       | 0.0       | 7.3            |                         |                         | 0.5     | 0.0          | 137.8                | 138.3               | -0.63                        | -1.26                       |                        |                       | 0.660                        | 1.295                       | -6.44                     | -6.21                        | 28.57                  | 1370         | 34.4356217 | -118.6500588 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                            |                                 |
| CV-24018   | 8/25/2026 8:01:13 AM  | 8.4        | 76.7       | 0.0       | 14.9           |                         |                         | 0.1     | 0.0          | 130.6                | 130.9               | -2.22                        | -2.21                       |                        |                       | 2.200                        | 2.187                       | -8.81                     | -8.63                        | 28.59                  | 1365         | 34.4356034 | -118.6500605 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                            |                                 |
| CV-24019   | 8/4/2026 8:10:00 AM   |            |            |           |                |                         | 182100                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                 | AtmAA; [User entered 18.21%]    |
| CV-24019   | 8/4/2026 8:10:00 AM   |            |            |           |                | 2500                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                 | AtmAA                           |
| CV-24019   | 8/4/2026 8:11:30 AM   | 7.4        | 70.3       | 0.0       | 22.3           |                         |                         | 0.1     | 0.0          | 176.1                | 176.3               | -7.75                        | -8.01                       |                        |                       | 8.036                        | 8.328                       | -11.06                    | -11.26                       | 28.46                  | 1356         | 34.4357710 | -118.6497480 | Valve Adjustment:No Flow Measurement,High Temp                                                                                  |                                 |
| CV-24019   | 8/11/2026 9:20:30 AM  | 2.7        | 73.7       | 0.0       | 23.6           |                         |                         | 0.0     | 0.0          | 186.5                | 184.5               | -11.41                       | -10.90                      |                        |                       | 11.589                       | 11.172                      | -8.90                     | -9.20                        | 28.62                  | 1369         | 34.4357623 | -118.6497737 | Valve Adjustment:NSPS/EG CAI,High Temp                                                                                          |                                 |
| CV-24019   | 8/11/2026 9:21:06 AM  | 2.6        | 75.2       | 0.0       | 22.2           |                         |                         | 0.0     | 0.0          | 187.4                | 186.9               | -7.03                        | -7.03                       |                        |                       | 7.388                        | 7.388                       | -9.70                     | -9.70                        | 28.62                  | 1371         | 34.4357638 | -118.6497673 | Valve Adjustment:NSPS/EG CAI,High Temp                                                                                          |                                 |
| CV-24019   | 8/12/2026 10:35:00 AM |            |            |           |                | 2300                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                 | AtmAA                           |
| CV-24019   | 8/12/2026 10:36:43 AM | 28.9       | 71.1       | 0.0       | 0.0            |                         |                         | 0.4     | 0.0          | 181.1                | 180.9               | -4.53                        | -4.42                       |                        |                       | 5.005                        | 4.913                       | 0.34                      | 0.34                         | 28.57                  | 1361         | 34.4357739 | -118.6497604 | Valve Adjustment:No Flow Measurement,High Temp                                                                                  |                                 |
| CV-24019   | 8/18/2026 8:12:34 AM  | 4.4        | 76.0       | 0.0       | 19.6           |                         |                         | 0.1     | 0.0          | 182.5                | 182.6               | -5.19                        | -4.72                       |                        |                       | 5.478                        | 5.143                       | -8.11                     | -7.92                        | 28.6                   | 1363         | 34.4357798 | -118.6497715 | Valve Adjustment:No Flow Measurement,High Temp                                                                                  |                                 |
| CV-24019   | 8/18/2026 8:15:00 AM  |            |            |           |                | 2160                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                 | AtmAA                           |
| CV-24019   | 8/25/2026 7:57:26 AM  | 7.5        | 77.9       | 0.0       | 14.6           |                         |                         | 0.1     | 0.0          | 183.7                | 183.8               | -5.06                        | -4.96                       |                        |                       | 5.391                        | 4.961                       | -8.24                     | -7.58                        | 28.59                  | 1375         | 34.4357822 | -118.6497780 | Valve Adjustment:No Flow Measurement,High Temp                                                                                  |                                 |
| CV-24020   | 8/10/2026 12:00:21 PM | 0.4        | 15.3       | 15.8      | 68.5           |                         |                         | 0.0     | 4.3          | 110.2                | 110.3               | -8.70                        | -8.64                       | 8.2                    | 8.7                   | 0.181                        | 0.207                       | -8.94                     | -8.85                        | 28.67                  | 1356         | 34.4359890 | -118.6493772 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In);Well Comment:No pump |                                 |
| CV-24020   | 8/10/2026 12:01:21 PM | 0.4        | 11.1       | 16.8      | 71.7           |                         |                         | 0.0     | 4.3          | 110.2                | 110.2               | -8.65                        | -8.40                       | 12.7                   | 11.6                  | 0.436                        | 0.363                       | -8.56                     | -8.46                        | 28.68                  | 1358         | 34.4359945 | -118.6493757 |                                                                                                                                 |                                 |
| CV-24020   | 8/19/2026 8:57:47 AM  | 1.7        | 8.4        | 16.3      | 73.6           |                         |                         | 0.2     | 4.5          | 95.1                 | 95.7                | -7.96                        | -7.98                       | 8.4                    | 8.8                   | 0.187                        | 0.206                       | -7.99                     | -7.96                        | 28.63                  | 1351         | 34.4359998 | -118.6493678 | Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In);Well Comment:No pump                       |                                 |
| CV-24020   | 8/19/2026 8:58:35 AM  | 1.7        | 10.2       | 15.7      | 72.4           |                         |                         | 0.2     | 4.6          | 98.8                 | 99.0                | -7.99                        | -7.98                       | 8.2                    | 8.2                   | 0.181                        | 0.179                       | -7.93                     | -8.25                        | 28.63                  | 1357         | 34.4359942 | -118.6493775 |                                                                                                                                 |                                 |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name  | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init Flow<br>[scfm] | Adj Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                               |
|-------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|---------------------|--------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|----------------------------------------------------------------------------------------------------------------------------------------|
| CV-24021    | 8/10/2026 12:06:18 PM | 1.0        | 6.6        | 17.1      | 75.3           |                         |                         | 0.2     | 4.4          | 111.2                | 110.8               | -8.77                        | -8.74                       |                     |                    | 8.917                        | 8.850                       | -8.99                     | -8.88                        | 28.67                  | 1358         | 34.4361472 | -118.6490507 | Valve Adjustment: NSPS/EG CAI, High O2, Decreased Flow/Vacuum, Barely Open, Surging Liquid in Well (Watered In); Well Comment: No pump |
| CV-24021    | 8/10/2026 12:07:24 PM | 1.2        | 7.9        | 16.5      | 74.4           |                         |                         | 0.2     | 4.5          | 110.8                | 110.7               | -8.71                        | -8.71                       |                     |                    | 8.813                        | 8.819                       | -8.81                     | -8.81                        | 28.68                  | 1359         | 34.4361545 | -118.6490495 |                                                                                                                                        |
| CV-24021    | 8/19/2026 8:52:25 AM  | 4.0        | 15.0       | 13.7      | 67.3           |                         |                         | 0.3     | 4.9          | 96.3                 | 96.8                | -7.92                        | -7.81                       |                     |                    | 8.005                        | 7.879                       | -7.86                     | -7.83                        | 28.63                  | 1366         | 34.4361397 | -118.6490310 | Valve Adjustment: NSPS/EG CAI, High O2, Barely Open, Surging Liquid in Well (Watered In); Well Comment: No pump                        |
| CV-24021    | 8/19/2026 8:53:28 AM  | 4.7        | 13.9       | 13.6      | 67.8           |                         |                         | 0.3     | 5.0          | 96.9                 | 96.8                | -7.98                        | -8.00                       |                     |                    | 8.109                        | 8.114                       | -7.93                     | -8.13                        | 28.63                  | 1367         | 34.4361307 | -118.6490082 |                                                                                                                                        |
| CV-24022-PL | 8/3/2026 8:59:34 AM   | 2.0        | 50.6       | 0.0       | 47.4           |                         |                         | 0.0     | 0.0          | 194.7                | 194.5               | -9.68                        | -9.60                       |                     |                    | 10.203                       | 10.104                      | -10.27                    | -10.11                       | 28.45                  | 1384         | 34.4365096 | -118.6488192 | Valve Adjustment: No Flow Measurement, High Temp                                                                                       |
| CV-24022-PL | 8/3/2026 9:05:00 AM   |            |            |           |                |                         | 183800                  |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA; [User entered 18.38%]                                                                                                           |
| CV-24022-PL | 8/3/2026 9:05:00 AM   |            |            |           |                | 2310                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                  |
| CV-24022-PL | 8/10/2026 9:02:17 AM  | 4.6        | 71.8       | 0.0       | 23.6           |                         |                         | 0.1     | 0.0          | 194.8                | 194.9               | -7.43                        | -7.47                       |                     |                    | 7.978                        | 8.059                       | -7.75                     | -7.78                        | 28.56                  | 1360         | 34.4365238 | -118.6488122 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                               |
| CV-24022-PL | 8/10/2026 9:15:00 AM  |            |            |           |                | 2740                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                  |
| CV-24022-PL | 8/17/2026 9:00:28 AM  | 17.5       | 67.8       | 0.0       | 14.7           |                         |                         | 0.3     | 0.0          | 195.0                | 195.0               | -7.88                        | -7.76                       |                     |                    | 8.325                        | 8.325                       | -8.17                     | -8.08                        | 28.66                  | 1360         | 34.4365354 | -118.6488380 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                               |
| CV-24022-PL | 8/17/2026 9:05:00 AM  |            |            |           |                | 2770                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                  |
| CV-24022-PL | 8/24/2026 8:49:03 AM  | 10.8       | 73.1       | 0.0       | 16.1           |                         |                         | 0.1     | 0.0          | 195.3                | 195.2               | -8.42                        | -8.42                       |                     |                    | 8.983                        | 8.934                       | -8.77                     | -8.76                        | 28.6                   | 1376         | 34.4365132 | -118.6487916 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                               |
| CV-24022-PL | 8/31/2026 9:23:55 AM  | 4.5        | 72.1       | 0.5       | 22.9           |                         |                         | 0.1     | 45.8         | 194.6                | 194.6               | -7.14                        | -6.40                       |                     |                    | 7.690                        | 7.007                       | -6.42                     | -6.40                        | 28.53                  | 1369         | 34.4365185 | -118.6487976 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                               |
| CV-24023    | 8/3/2026 8:51:00 AM   |            |            |           |                |                         | 182400                  |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA; [User entered 18.24%]                                                                                                           |
| CV-24023    | 8/3/2026 8:51:00 AM   |            |            |           |                | 993                     |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                  |
| CV-24023    | 8/3/2026 8:53:03 AM   | 1.4        | 73.3       | 0.0       | 25.3           |                         |                         | 0.0     | 0.0          | 188.7                | 187.9               | -8.48                        | -7.82                       |                     |                    | 8.965                        | 8.206                       | -8.77                     | -8.11                        | 28.45                  | 1377         | 34.4366030 | -118.6484444 | Valve Adjustment: No Flow Measurement, High Temp                                                                                       |
| CV-24023    | 8/10/2026 8:53:28 AM  | 4.3        | 71.5       | 0.0       | 24.2           |                         |                         | 0.1     | 0.0          | 196.3                | 196.3               | -4.67                        | -4.67                       |                     |                    | 4.643                        | 4.694                       | -5.93                     | -6.33                        | 28.57                  | 1367         | 34.4366028 | -118.6484394 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                               |
| CV-24023    | 8/10/2026 9:03:00 AM  |            |            |           |                | 1600                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                  |
| CV-24023    | 8/17/2026 8:45:00 AM  |            |            |           |                | 150                     |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                  |
| CV-24023    | 8/17/2026 8:45:38 AM  | 16.7       | 70.8       | 0.0       | 12.5           |                         |                         | 0.2     | 0.0          | 196.1                | 196.0               | -4.68                        | -4.55                       |                     |                    | 5.069                        | 5.025                       | -6.56                     | -7.07                        | 28.66                  | 1367         | 34.4366111 | -118.6484443 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                               |
| CV-24023    | 8/24/2026 8:38:58 AM  | 11.2       | 70.6       | 0.9       | 17.3           |                         |                         | 0.2     | 19.2         | 194.4                | 194.6               | -7.09                        | -7.16                       |                     |                    | 7.566                        | 7.737                       | -7.49                     | -7.75                        | 28.6                   | 1367         | 34.4366254 | -118.6484205 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                               |
| CV-24023    | 8/31/2026 9:06:28 AM  | 3.3        | 76.8       | 0.0       | 19.9           |                         |                         | 0.0     | 0.0          | 194.5                | 194.5               | -4.81                        | -4.81                       |                     |                    | 4.787                        | 4.786                       | -6.18                     | -5.97                        | 28.57                  | 1365         | 34.4366143 | -118.6484134 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                               |
| CV-24024-PL | 8/3/2026 8:35:00 AM   |            |            |           |                |                         | 194400                  |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA; [User entered 19.44%]                                                                                                           |
| CV-24024-PL | 8/3/2026 8:35:00 AM   |            |            |           |                | 1150                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                  |
| CV-24024-PL | 8/3/2026 8:39:24 AM   | 1.3        | 71.3       | 0.0       | 27.4           |                         |                         | 0.0     | 0.0          | 163.9                | 164.0               | -5.05                        | -5.05                       |                     |                    | 5.363                        | 5.351                       | -7.69                     | -7.64                        | 28.46                  | 1358         | 34.4367805 | -118.6481516 | Valve Adjustment: No Flow Measurement, High Temp                                                                                       |
| CV-24024-PL | 8/10/2026 8:34:31 AM  | 3.4        | 73.3       | 0.0       | 23.3           |                         |                         | 0.0     | 0.0          | 163.9                | 164.8               | -3.42                        | -3.40                       |                     |                    | 3.420                        | 3.401                       | -6.53                     | -6.65                        | 28.6                   | 1351         | 34.4368078 | -118.6481478 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                               |
| CV-24024-PL | 8/10/2026 8:46:00 AM  |            |            |           |                | 1530                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                  |
| CV-24024-PL | 8/17/2026 8:09:11 AM  | 12.0       | 71.5       | 0.1       | 16.4           |                         |                         | 0.2     | 164.0        | 141.2                | 141.1               | -5.44                        | -5.39                       |                     |                    | 5.624                        | 5.515                       | -7.40                     | -7.31                        | 28.66                  | 1351         | 34.4367976 | -118.6481544 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                               |
| CV-24024-PL | 8/17/2026 8:10:00 AM  |            |            |           |                | 1370                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                  |
| CV-24025    | 8/4/2026 8:15:00 AM   |            |            |           |                |                         | 127400                  |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA; [User entered 12.74%]                                                                                                           |
| CV-24025    | 8/4/2026 8:15:00 AM   |            |            |           |                | 2490                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                  |
| CV-24025    | 8/4/2026 8:15:55 AM   | 4.2        | 75.8       | 0.0       | 20.0           |                         |                         | 0.1     | 0.0          | 164.0                | 166.4               | -2.68                        | -2.62                       |                     |                    | 2.662                        | 2.601                       | -5.74                     | -5.45                        | 28.46                  | 1363         | 34.4352755 | -118.6499407 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                               |
| CV-24025    | 8/11/2026 9:25:11 AM  | 3.4        | 61.0       | 0.1       | 35.5           |                         |                         | 0.1     | 355.0        | 186.3                | 186.1               | -2.29                        | -2.28                       |                     |                    | 2.380                        | 2.392                       | -4.32                     | -4.32                        | 28.62                  | 1372         | 34.4352625 | -118.6499587 | Valve Adjustment: NSPS/EG CAI, Audible Flow, High Temp                                                                                 |
| CV-24025    | 8/11/2026 9:26:00 AM  | 3.4        | 60.0       | 0.0       | 36.6           |                         |                         | 0.1     | 0.0          | 186.2                | 186.2               | -2.30                        | -2.26                       |                     |                    | 2.422                        | 2.382                       | -4.44                     | -4.28                        | 28.62                  | 1370         | 34.4352578 | -118.6499530 | Valve Adjustment: NSPS/EG CAI, High Temp                                                                                               |
| CV-24025    | 8/12/2026 10:40:00 AM |            |            |           |                | 3000                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                  |
| CV-24025    | 8/12/2026 10:41:45 AM | 19.6       | 62.0       | 0.2       | 18.2           |                         |                         | 0.3     | 91.0         | 182.8                | 183.0               | -1.42                        | -1.40                       |                     |                    | 1.416                        | 1.384                       | -3.18                     | -3.12                        | 28.57                  | 1364         | 34.4352718 | -118.6499502 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                               |
| CV-24025    | 8/18/2026 8:18:27 AM  | 8.9        | 70.7       | 0.0       | 20.4           |                         |                         | 0.1     | 0.0          | 174.3                | 174.5               | -1.59                        | -1.58                       |                     |                    | 1.576                        | 1.568                       | -3.79                     | -3.62                        | 28.6                   | 1359         | 34.4352891 | -118.6499511 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                               |
| CV-24025    | 8/18/2026 8:20:00 AM  |            |            |           |                | 2470                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                  |
| CV-24025    | 8/25/2026 8:06:23 AM  | 14.1       | 62.9       | 0.0       | 23.0           |                         |                         | 0.2     | 0.0          | 181.2                |                     |                              |                             |                     |                    |                              |                             |                           |                              | 28.6                   | 1361         | 34.4352832 | -118.6499364 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                               |
| CV-24026    | 8/10/2026 8:55:44 AM  | 0.9        | 78.4       | 0.0       | 20.7           |                         |                         | 0.0     | 0.0          | 180.7                | 181.2               | -8.02                        | -2.65                       |                     |                    | 8.009                        | 2.597                       | -7.97                     | -7.45                        | 28.63                  | 1339         | 34.4356865 | -118.6492710 | Valve Adjustment: NSPS/EG CAI, High Temp, Decreased Flow/Vacuum                                                                        |
| CV-24026    | 8/10/2026 8:58:30 AM  | 1.0        | 77.8       | 0.0       | 21.2           |                         |                         | 0.0     | 0.0          | 180.9                | 181.0               | -3.25                        | -3.22                       |                     |                    | 3.195                        | 3.159                       | -8.08                     | -6.50                        | 28.63                  | 1340         | 34.4356653 | -118.6492758 | Well Condition: Lorentz Pump Installed                                                                                                 |
| CV-24026    | 8/18/2026 8:10:00 AM  |            |            |           |                | 2190                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                  |
| CV-24026    | 8/18/2026 8:10:51 AM  | 4.4        | 73.8       | 0.0       | 21.8           |                         |                         | 0.1     | 0.0          | 176.5                | 176.6               | -2.56                        | -2.38                       |                     |                    | 2.550                        | 2.367                       | -8.04                     | -8.42                        | 28.6                   | 1361         | 34.4356578 | -118.6492853 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                               |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init<br>Flow<br>[scfm] | Adj<br>Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                                                                             |                              |
|------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|------------------------|-----------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------|
| CV-24026   | 8/18/2026 2:34:56 PM  | 18.5       | 73.5       | 0.2       | 7.8            |                         |                         | 0.3     | 39.0         | 178.0                | 178.0               | 0.29                         | -2.40                       |                        |                       | 0.000                        | 2.406                       | -4.40                     | -5.26                        | 28.57                  | 1350         | 34.4356493 | -118.6492780 | Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed                                                                           |                              |
| CV-24026   | 8/18/2026 2:37:15 PM  | 20.6       | 74.1       | 0.2       | 5.1            |                         |                         | 0.3     | 25.5         | 177.7                | 178.4               | -2.74                        | -2.61                       |                        |                       | 2.732                        | 2.584                       | -5.50                     | -5.75                        | 28.56                  | 1360         | 34.4356693 | -118.6492667 | Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                                     |                              |
| CV-24026   | 8/25/2026 7:52:48 AM  | 5.3        | 75.1       | 0.0       | 19.6           |                         |                         | 0.1     | 0.0          | 175.1                | 175.0               | -4.34                        | -4.31                       |                        |                       | 4.333                        | 4.316                       | -7.50                     | -6.53                        | 28.6                   | 1361         | 34.4356688 | -118.6492857 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                                                 |                              |
| CV-24027   | 8/10/2026 12:18:55 PM | 3.3        | 76.2       | 0.2       | 20.3           |                         |                         | 0.0     | 101.5        | 164.6                | 163.4               | -8.40                        | -8.29                       |                        |                       | 8.384                        | 8.421                       | -8.97                     | -9.03                        | 28.67                  | 1370         | 34.4360875 | -118.6487372 | Valve Adjustment:NSPS/EG CAC,High Temp,Decreased Flow/Vacuum,Barely Open,Surgig Liquid in Well (Watered In);Well Comment:Pump was not cycling;Well Condition:Pnumatic Pump Installed |                              |
| CV-24027   | 8/10/2026 12:20:14 PM | 2.6        | 77.0       | 0.1       | 20.3           |                         |                         | 0.0     | 203.0        | 163.2                | 162.9               | -8.31                        | -8.27                       |                        |                       | 8.442                        | 8.482                       | -9.03                     | -9.06                        | 28.67                  | 1365         | 34.4360990 | -118.6487413 |                                                                                                                                                                                      |                              |
| CV-24027   | 8/18/2026 2:42:10 PM  | 25.0       | 72.5       | 0.8       | 1.7            |                         |                         | 0.3     | 2.1          | 138.3                | 138.5               | -5.38                        | -5.42                       |                        |                       | 5.625                        | 5.662                       | -6.02                     | -6.14                        | 28.56                  | 1351         | 34.4361092 | -118.6487282 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed                                                                                                |                              |
| CV-24028   | 8/3/2026 9:43:51 AM   | 1.9        | 85.1       | 0.0       | 13.0           |                         |                         | 0.0     | 0.0          | 194.4                | 194.3               | -8.24                        | -8.32                       |                        |                       | 8.827                        | 8.871                       | -9.29                     | -9.14                        | 28.44                  | 1361         | 34.4363355 | -118.6484705 | Valve Adjustment:No Flow Measurement,High Temp                                                                                                                                       |                              |
| CV-24028   | 8/3/2026 9:45:00 AM   |            |            |           |                |                         | 183100                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                                      | AtmAA; [User entered 18.31%] |
| CV-24028   | 8/3/2026 9:45:00 AM   |            |            |           |                | 812                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                                      | AtmAA                        |
| CV-24028   | 8/10/2026 9:07:39 AM  | 4.8        | 70.5       | 0.0       | 24.7           |                         |                         | 0.1     | 0.0          | 194.7                | 194.8               | -7.13                        | -7.06                       |                        |                       | 7.739                        | 7.625                       | -8.35                     | -8.21                        | 28.57                  | 1362         | 34.4363686 | -118.6484878 | Valve Adjustment:High Temp                                                                                                                                                           |                              |
| CV-24028   | 8/10/2026 9:20:00 AM  |            |            |           |                | 1190                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                                      | AtmAA                        |
| CV-24028   | 8/17/2026 9:06:40 AM  | 15.0       | 70.8       | 0.0       | 14.2           |                         |                         | 0.2     | 0.0          | 193.9                | 194.0               | -7.74                        | -7.71                       |                        |                       | 8.161                        | 8.127                       | -8.61                     | -8.46                        | 28.66                  | 1358         | 34.4363452 | -118.6484788 | Valve Adjustment:No Flow Measurement,High Temp                                                                                                                                       |                              |
| CV-24028   | 8/17/2026 9:10:00 AM  |            |            |           |                | 1390                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                                      | AtmAA                        |
| CV-24028   | 8/24/2026 9:05:51 AM  | 16.4       | 74.8       | 0.0       | 8.8            |                         |                         | 0.2     | 0.0          | 204.4                | 201.5               | 23.63                        | -3.52                       |                        |                       | 0.000                        | 3.505                       | -9.38                     | -8.22                        | 28.6                   | 1373         | 34.4363450 | -118.6484677 | Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Pnumatic Pump Installed                                                                          |                              |
| CV-24028   | 8/24/2026 9:06:33 AM  | 25.7       | 73.7       | 0.0       | 0.6            |                         |                         | 0.3     | 0.0          | 201.5                | 201.5               | -8.06                        | -7.75                       |                        |                       | 8.587                        | 8.354                       | -8.31                     | -8.13                        | 28.6                   | 1374         | 34.4363352 | -118.6484582 |                                                                                                                                                                                      |                              |
| CV-24028   | 8/31/2026 9:30:36 AM  | 4.8        | 71.9       | 0.0       | 23.3           |                         |                         | 0.1     | 0.0          | 196.0                | 195.8               | -5.29                        | -5.05                       |                        |                       | 5.743                        | 5.596                       | -5.63                     | -5.56                        | 28.55                  | 1371         | 34.4363467 | -118.6484777 | Valve Adjustment:No Flow Measurement,High Temp                                                                                                                                       |                              |
| CV-24029   | 8/11/2026 10:05:11 AM | 0.9        | 32.2       | 11.9      | 55.0           |                         |                         | 0.0     | 4.6          | 104.9                | 110.4               | -8.12                        | -5.77                       |                        |                       | 8.589                        | 6.199                       | -7.96                     | -7.89                        | 28.61                  | 1379         | 34.4364538 | -118.6480808 | Valve Adjustment:Barely Open,Surgig Liquid in Header,Surgig Liquid in Well (Watered In),Plugged/Pinched Suspected                                                                    |                              |
| CV-24029   | 8/19/2026 9:32:59 AM  | 3.0        | 61.9       | 4.6       | 30.5           |                         |                         | 0.0     | 6.6          | 114.3                | 114.6               | -5.40                        | -5.40                       |                        |                       | 5.738                        | 5.707                       | -5.92                     | -6.09                        | 28.53                  | 1351         | 34.4364337 | -118.6480857 | Valve Adjustment:Surgig Liquid in Header,Surgig Liquid in Well (Watered In),Plugged/Pinched Suspected                                                                                |                              |
| CV-24030   | 8/3/2026 8:25:00 AM   |            |            |           |                |                         | 117400                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                                      | AtmAA; [User entered 11.74%] |
| CV-24030   | 8/3/2026 8:25:00 AM   |            |            |           |                | 1570                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                                      | AtmAA                        |
| CV-24030   | 8/3/2026 8:29:15 AM   | 1.2        | 71.3       | 0.0       | 27.5           |                         |                         | 0.0     | 0.0          | 182.9                | 179.5               | 2.08                         | -3.91                       |                        |                       | 0.000                        | 3.898                       | -7.58                     | -7.71                        | 28.46                  | 1353         | 34.4366699 | -118.6478813 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                                                 |                              |
| CV-24030   | 8/3/2026 8:30:34 AM   | 1.2        | 80.9       | 0.0       | 17.9           |                         |                         | 0.0     | 0.0          | 178.9                | 178.5               | -3.82                        | -3.69                       |                        |                       | 3.776                        | 3.643                       | -7.58                     | -8.21                        | 28.46                  | 1354         | 34.4366735 | -118.6478828 | Valve Adjustment:No Flow Measurement,High Temp                                                                                                                                       |                              |
| CV-24030   | 8/10/2026 8:25:10 AM  | 2.1        | 73.5       | 0.0       | 24.4           |                         |                         | 0.0     | 0.0          | 178.2                | 178.8               | -3.93                        | -3.97                       |                        |                       | 3.868                        | 3.893                       | -5.49                     | -5.98                        | 28.57                  | 1359         | 34.4366659 | -118.6478905 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                                                 |                              |
| CV-24030   | 8/10/2026 8:35:00 AM  |            |            |           |                | 1510                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                                      | AtmAA                        |
| CV-24030   | 8/17/2026 7:55:20 AM  | 4.4        | 77.9       | 0.0       | 17.7           |                         |                         | 0.1     | 0.0          | 177.6                | 177.7               | -4.36                        | -4.29                       |                        |                       | 4.296                        | 4.078                       | -6.58                     | -6.91                        | 28.65                  | 1356         | 34.4366526 | -118.6478767 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                                                 |                              |
| CV-24030   | 8/17/2026 8:00:00 AM  |            |            |           |                | 1440                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                                      | AtmAA                        |
| CV-24030   | 8/24/2026 8:18:36 AM  | 7.1        | 73.4       | 0.0       | 19.5           |                         |                         | 0.1     | 0.0          | 178.5                | 179.1               | -4.76                        | -4.57                       |                        |                       | 4.601                        | 4.394                       | -6.59                     | -6.61                        | 28.61                  | 1344         | 34.4366476 | -118.6478864 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                                                 |                              |
| CV-24030   | 8/31/2026 8:28:13 AM  | 1.9        | 61.2       | 5.6       | 31.3           |                         |                         | 0.0     | 5.6          | 183.0                | 114.5               | -5.73                        | -3.70                       |                        |                       | 6.095                        | 3.608                       | 0.08                      | 0.26                         | 28.57                  | 1350         | 34.4366597 | -118.6478891 | Valve Adjustment:NSPS/EG CAC,High Temp,Decreased Flow/Vacuum,Barely Open;Well Condition:Lorentz Pump Installed                                                                       |                              |
| CV-24030   | 8/31/2026 8:35:56 AM  | 2.3        | 56.5       | 4.4       | 36.8           |                         |                         | 0.0     | 8.4          | 105.8                | 105.3               | -2.20                        | -1.05                       |                        |                       | 2.112                        | 1.220                       | 0.27                      | 0.29                         | 28.57                  | 1350         | 34.4366597 | -118.6478891 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                                                 |                              |
| CV-24031   | 8/4/2026 8:41:54 AM   | 26.9       | 63.9       | 0.0       | 9.2            |                         |                         | 0.4     | 0.0          | 148.6                | 148.7               | -6.74                        | -6.62                       |                        |                       | 7.091                        | 7.050                       | -12.95                    | -12.26                       | 28.49                  | 1345         | 34.4348841 | -118.6498029 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                                                 |                              |
| CV-24031   | 8/5/2026 2:00:00 PM   |            |            |           |                |                         | 57900                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                                      | AtmAA; [User entered 5.79%]  |
| CV-24031   | 8/5/2026 2:00:00 PM   |            |            |           |                | 822                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                                      | AtmAA                        |
| CV-24031   | 8/12/2026 2:18:33 PM  | 40.3       | 59.6       | 0.1       | 0.0            |                         |                         | 0.7     | 0.0          | 150.4                | 150.0               | -5.39                        | -5.39                       |                        |                       | 5.270                        | 5.293                       | -8.02                     | -8.04                        | 28.49                  | 1367         | 34.4348675 | -118.6498117 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                                                 |                              |
| CV-24031   | 8/12/2026 2:20:00 PM  |            |            |           |                | 2560                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                                      | AtmAA                        |
| CV-24031   | 8/18/2026 8:43:41 AM  | 7.8        | 75.1       | 0.0       | 17.1           |                         |                         | 0.1     | 0.0          | 156.8                | 157.1               | -5.05                        | -5.05                       |                        |                       | 5.526                        | 5.442                       | -7.78                     | -7.75                        | 28.61                  | 1342         | 34.4348811 | -118.6498287 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                                                 |                              |
| CV-24031   | 8/18/2026 8:50:00 AM  |            |            |           |                | 611                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                                      | AtmAA                        |
| CV-24031   | 8/25/2026 8:21:56 AM  | 42.3       | 57.7       | 0.0       | 0.0            |                         |                         | 0.7     | 0.0          | 146.4                | 146.4               | -5.39                        | -5.39                       |                        |                       | 5.760                        | 5.773                       | -8.44                     | -8.55                        | 28.6                   | 1350         | 34.4348819 | -118.6497945 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                                                 |                              |
| CV-24032   | 8/4/2026 8:38:24 AM   | 2.0        | 67.7       | 0.0       | 30.3           |                         |                         | 0.0     | 0.0          | 171.3                | 171.3               | -4.97                        | -4.65                       |                        |                       | 4.922                        | 4.998                       | -8.09                     | -8.13                        | 28.49                  | 1351         | 34.4351037 | -118.6496169 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                                                 |                              |
| CV-24032   | 8/4/2026 8:40:00 AM   |            |            |           |                |                         | 97400                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                                      | AtmAA; [User entered 9.74%]  |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name  | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init<br>Flow<br>[scfm] | Adj<br>Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                            |
|-------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|------------------------|-----------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|-------------------------------------------------------------------------------------------------------------------------------------|
| CV-24032    | 8/4/2026 8:40:00 AM   |            |            |           |                | 505                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                               |
| CV-24032    | 8/11/2026 9:31:02 AM  | 2.1        | 80.4       | 0.0       | 17.5           |                         |                         | 0.0     | 0.0          | 200.5                | 200.5               | 1.82                         | -0.05                       |                        |                       | 0.000                        | 0.000                       | -2.97                     | -0.46                        | 28.65                  | 1351         | 34.4351140 | -118.6496408 | Valve Adjustment: NSPS/EG CAI, High Temp, Positive Static Press., Increased Flow/Vacuum                                             |
| CV-24032    | 8/11/2026 9:31:28 AM  | 2.2        | 81.0       | 0.0       | 16.8           |                         |                         | 0.0     | 0.0          | 200.5                | 200.5               | -0.04                        | -0.09                       |                        |                       | 0.147                        | 0.176                       | -1.07                     | -0.97                        | 28.65                  | 1356         | 34.4350908 | -118.6496290 | Valve Adjustment: NSPS/EG CAI, High Temp                                                                                            |
| CV-24032    | 8/11/2026 9:32:06 AM  | 2.2        | 80.2       | 0.0       | 17.6           |                         |                         | 0.0     | 0.0          | 200.5                | 200.6               | -0.07                        | -0.07                       |                        |                       | 0.234                        | 0.175                       | -0.52                     | -0.84                        | 28.65                  | 1355         | 34.4350938 | -118.6496358 | Valve Adjustment: NSPS/EG CAI, High Temp                                                                                            |
| CV-24032    | 8/12/2026 2:15:00 PM  |            |            |           |                | 1510                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                               |
| CV-24032    | 8/12/2026 2:15:09 PM  | 13.5       | 81.1       | 0.0       | 5.4            |                         |                         | 0.2     | 0.0          | 198.1                | 198.1               | -0.23                        | -0.12                       |                        |                       | 0.232                        | 0.101                       | -1.45                     | -1.52                        | 28.5                   | 1369         | 34.4350953 | -118.6496321 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                            |
| CV-24032    | 8/13/2026 11:56:31 AM | 16.3       | 61.7       | 0.0       | 22.1           |                         |                         | 0.3     | 0.0          | 102.7                | 102.2               | -3.77                        | -3.75                       |                        |                       | 3.809                        | 3.736                       | -4.07                     | -4.03                        | 28.58                  | 1346         | 34.4350817 | -118.6495973 |                                                                                                                                     |
| CV-24032    | 8/13/2026 11:59:26 AM | 15.9       | 61.5       | 0.0       | 22.7           |                         |                         | 0.3     | 0.0          | 173.8                | 174.2               | -3.73                        | -3.48                       |                        |                       | 3.764                        | 3.506                       | -4.05                     | -3.47                        | 28.59                  | 1344         | 34.4351070 | -118.6496033 | Valve Adjustment: NSPS/EG CAI, High Temp, Increased Flow/Vacuum                                                                     |
| CV-24032    | 8/18/2026 8:40:40 AM  | 7.9        | 75.7       | 0.0       | 16.4           |                         |                         | 0.1     | 0.0          | 172.2                | 172.6               | -3.65                        | -3.64                       |                        |                       | 3.667                        | 3.622                       | -3.39                     | -3.44                        | 28.62                  | 1344         | 34.4351028 | -118.6495912 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                            |
| CV-24032    | 8/18/2026 8:45:00 AM  |            |            |           |                | 597                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                               |
| CV-24032    | 8/25/2026 8:17:49 AM  | 10.1       | 74.8       | 0.0       | 15.1           |                         |                         | 0.1     | 0.0          | 152.6                | 153.8               | -3.65                        | -3.74                       |                        |                       | 3.650                        | 3.757                       | -3.63                     | -3.62                        | 28.6                   | 1347         | 34.4350929 | -118.6496026 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                            |
| CV-24033    | 8/10/2026 8:38:00 AM  | 0.6        | 80.5       | 0.0       | 18.9           |                         |                         | 0.0     | 0.0          | 197.6                | 197.7               | 1.49                         | -0.70                       |                        |                       | 0.000                        | 0.682                       | -0.85                     | -1.26                        | 28.63                  | 1335         | 34.4353562 | -118.6494815 | Valve Adjustment: NSPS/EG CAI, High Temp, Positive Static Press., Increased Flow/Vacuum, Surging Liquid in Header                   |
| CV-24033    | 8/10/2026 8:40:08 AM  | 0.5        | 81.0       | 0.0       | 18.5           |                         |                         | 0.0     | 0.0          | 197.7                | 197.7               | -0.84                        | -1.02                       |                        |                       | 0.828                        | 0.993                       | -0.92                     | -1.48                        | 28.64                  | 1342         | 34.4353628 | -118.6494627 | Valve Adjustment: NSPS/EG CAC, High Temp, Surging Liquid in Header                                                                  |
| CV-24033    | 8/13/2026 12:04:43 PM | 0.2        | 16.6       | 16.9      | 66.3           |                         |                         | 0.0     | 3.9          | 94.3                 | 94.3                | -3.33                        | -3.19                       |                        |                       | 3.373                        | 3.222                       | -3.27                     | -3.06                        | 28.57                  | 1347         | 34.4353372 | -118.6494473 | Valve Adjustment: NSPS/EG CAI, High O2, Surging Liquid in Header, Plugged/Pinched Suspected; Well Condition: Lorentz Pump Installed |
| CV-24033    | 8/13/2026 12:07:13 PM | 0.1        | 12.6       | 17.5      | 69.8           |                         |                         | 0.0     | 4.0          | 94.4                 | 94.4                | -3.76                        | -4.09                       |                        |                       | 3.789                        | 4.117                       | -3.73                     | -4.03                        | 28.58                  | 1338         | 34.4353327 | -118.6494652 | Valve Adjustment: High O2, Surging Liquid in Header, Surging Liquid in Well (Watered In); Well Condition: Lorentz Pump Installed    |
| CV-24033    | 8/20/2026 11:19:01 AM | 0.7        | 77.9       | 0.1       | 21.3           |                         |                         | 0.0     | 213.0        | 198.0                | 198.0               | -0.22                        | -0.28                       |                        |                       | 0.197                        | 0.261                       | -0.52                     | -0.66                        | 28.7                   | 1341         | 34.4353400 | -118.6494535 | Valve Adjustment: NSPS/EG CAI, High Temp, Plugged/Pinched Suspected                                                                 |
| CV-24033    | 8/20/2026 11:21:17 AM | 0.7        | 81.1       | 0.1       | 18.1           |                         |                         | 0.0     | 181.0        | 198.2                | 198.4               | -0.25                        | -0.18                       |                        |                       | 0.276                        | 0.160                       | -0.65                     | -0.58                        | 28.7                   | 1347         | 34.4353415 | -118.6494550 | Well Condition: Lorentz Pump Installed                                                                                              |
| CV-24034    | 8/3/2026 9:47:58 AM   | 2.2        | 74.3       | 0.0       | 23.5           |                         |                         | 0.0     | 0.0          | 160.0                | 159.4               | -9.84                        | -9.44                       |                        |                       | 10.418                       | 9.973                       | -10.01                    | -9.73                        | 28.46                  | 1366         | 34.4361035 | -118.6481260 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                            |
| CV-24034    | 8/3/2026 9:50:00 AM   |            |            |           |                |                         | 113100                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA; [User entered 11.31%]                                                                                                        |
| CV-24034    | 8/3/2026 9:50:00 AM   |            |            |           |                | 669                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                               |
| CV-24034    | 8/10/2026 9:20:53 AM  | 11.8       | 74.8       | 1.0       | 12.4           |                         |                         | 0.2     | 12.4         | 163.0                | 165.2               | -7.59                        | -5.69                       |                        |                       | 8.151                        | 6.148                       | -8.09                     | -7.85                        | 28.58                  | 1356         | 34.4361110 | -118.6481273 | Valve Adjustment: No Flow Measurement, High O2, Decreased Flow/Vacuum; Well Condition: Lorentz Pump Installed                       |
| CV-24034    | 8/10/2026 9:22:11 AM  | 18.6       | 72.9       | 0.9       | 7.6            |                         |                         | 0.3     | 8.4          | 162.8                | 163.8               | -4.93                        | -4.92                       |                        |                       | 4.903                        | 4.890                       | -7.72                     | -8.42                        | 28.59                  | 1356         | 34.4361118 | -118.6481273 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                            |
| CV-24034    | 8/10/2026 9:25:00 AM  |            |            |           |                | 1110                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                               |
| CV-24034    | 8/17/2026 9:15:00 AM  |            |            |           |                | 2772                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                               |
| CV-24034    | 8/17/2026 9:18:08 AM  | 15.4       | 70.8       | 0.3       | 13.5           |                         |                         | 0.2     | 45.0         | 162.9                | 162.6               | -0.13                        | -0.09                       |                        |                       | 0.117                        | 0.080                       | -8.53                     | -8.45                        | 28.67                  | 1373         | 34.4361081 | -118.6481295 | Valve Adjustment: No Flow Measurement, High Temp                                                                                    |
| CV-24034    | 8/17/2026 9:31:16 AM  | 14.4       | 69.2       | 0.0       | 16.4           |                         |                         | 0.2     | 0.0          | 162.3                | 177.1               | 1.94                         | -3.64                       |                        |                       | 0.000                        | 3.617                       | -8.17                     | -8.36                        | 28.67                  | 1371         | 34.4361054 | -118.6481305 | Valve Adjustment: No Flow Measurement, High Temp, Increased Flow/Vacuum; Well Condition: Lorentz Pump Installed                     |
| CV-24034    | 8/19/2026 8:49:43 AM  | 1.6        | 71.7       | 3.1       | 23.6           |                         |                         | 0.0     | 7.6          | 170.8                | 164.5               | -5.72                        | -3.77                       |                        |                       | 5.900                        | 3.786                       | -7.86                     | -8.17                        | 28.53                  | 1361         | 34.4360922 | -118.6481235 | Valve Adjustment: High Temp, Decreased Flow/Vacuum, Barely Open                                                                     |
| CV-24034    | 8/24/2026 9:11:55 AM  | 27.2       | 72.8       | 0.0       | 0.0            |                         |                         | 0.4     | 0.0          | 154.5                | 159.7               | -5.69                        | -5.43                       |                        |                       | 6.085                        | 5.995                       | 0.34                      | 0.34                         | 28.6                   | 1363         | 34.4361327 | -118.6481094 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                            |
| CV-24034    | 8/31/2026 9:46:05 AM  | 15.6       | 74.0       | 1.0       | 9.4            |                         |                         | 0.2     | 9.4          | 167.2                | 167.6               | -3.90                        | -3.90                       |                        |                       | 3.883                        | 3.888                       | -7.51                     | -7.45                        | 28.57                  | 1366         | 34.4361039 | -118.6481298 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                            |
| CV-24035-Pl | 8/3/2026 8:00:00 AM   |            |            |           |                |                         | 146700                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA; [User entered 14.67%]                                                                                                        |
| CV-24035-Pl | 8/3/2026 8:00:00 AM   |            |            |           |                | 1440                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                               |
| CV-24035-Pl | 8/3/2026 8:00:40 AM   | 1.5        | 75.5       | 0.0       | 23.0           |                         |                         | 0.0     | 0.0          | 184.1                | 184.6               | -6.40                        | -6.47                       |                        |                       | 6.566                        | 6.621                       | -7.99                     | -8.25                        | 28.42                  | 1374         | 34.4363839 | -118.6477310 | Valve Adjustment: No Flow Measurement, High Temp                                                                                    |
| CV-24035-Pl | 8/10/2026 8:10:40 AM  | 2.2        | 76.8       | 0.0       | 21.0           |                         |                         | 0.0     | 0.0          | 183.4                | 183.5               | -5.91                        | -5.94                       |                        |                       | 6.206                        | 6.240                       | -6.48                     | -6.40                        | 28.55                  | 1375         | 34.4363810 | -118.6477435 | Valve Adjustment: No Flow Measurement, High Temp                                                                                    |
| CV-24035-Pl | 8/10/2026 8:13:00 AM  |            |            |           |                | 1690                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                               |
| CV-24035-Pl | 8/17/2026 7:35:00 AM  |            |            |           |                | 1600                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                               |
| CV-24035-Pl | 8/17/2026 7:35:38 AM  | 3.7        | 81.4       | 0.0       | 14.9           |                         |                         | 0.0     | 0.0          | 179.5                | 179.1               | -6.58                        | -6.58                       |                        |                       | 6.670                        | 6.653                       | -7.15                     | -7.10                        | 28.64                  | 1370         | 34.4363801 | -118.6477173 | Valve Adjustment: No Flow Measurement, High Temp                                                                                    |
| CV-24035-Pl | 8/31/2026 7:52:59 AM  | 2.2        | 85.0       | 0.0       | 12.8           |                         |                         | 0.0     | 0.0          | 183.3                | 183.1               | -6.18                        | -5.77                       |                        |                       | 6.313                        | 5.803                       | -6.71                     | -6.54                        | 28.54                  | 1384         | 34.4363712 | -118.6477131 | Valve Adjustment: No Flow Measurement, High Temp                                                                                    |
| CV-24036    | 8/1/2026 10:32:16 AM  | 51.5       | 46.5       | 0.2       | 1.8            |                         |                         | 1.1     | 9.0          | 108.6                | 108.8               | -7.17                        | -7.23                       |                        |                       | 7.634                        | 7.697                       | -7.35                     | -7.30                        | 28.6                   | 1349         | 34.4344492 | -118.6496802 | Valve Adjustment: Barely Open                                                                                                       |
| CV-24036    | 8/20/2026 10:07:58 AM | 52.5       | 40.7       | 0.5       | 6.3            |                         |                         | 1.3     | 12.6         | 106.4                | 106.5               | -7.00                        | -7.13                       |                        |                       | 7.217                        | 7.290                       | -7.01                     | -7.12                        | 28.64                  | 1346         | 34.4344442 | -118.6496933 | Valve Adjustment: Increased Flow/Vacuum                                                                                             |
| CV-24037    | 8/3/2026 3:03:19 PM   | 21.9       | 66.5       | 0.5       | 11.1           |                         |                         | 0.3     | 22.2         | 147.0                | 146.5               | -7.70                        | -3.12                       |                        |                       | 7.832                        | 3.099                       | -8.27                     | -7.73                        | 28.41                  | 1357         | 34.4347592 | -118.6494315 | Valve Adjustment: High Temp, Decreased Flow/Vacuum                                                                                  |

## Chiquita Canyon Landfill

| Point Name | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init<br>Flow<br>[scfm] | Adj<br>Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                                                    |
|------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|------------------------|-----------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------|
| CV-24037   | 8/13/2026 1:46:00 PM  | 36.2       | 62.8       | 0.0       | 1.0            |                         |                         | 0.6     | 0.0          | 135.2                | 135.2               | -5.31                        | -5.27                       |                        |                       | 5.422                        | 5.294                       | -10.04                    | -10.04                       | 28.53                  | 1335         | 34.4347448 | -118.6494445 | Valve Adjustment-No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                        |
| CV-24037   | 8/25/2026 10:00:11 AM | 17.8       | 61.0       | 1.5       | 19.7           |                         |                         | 0.3     | 13.1         | 138.9                | 141.4               | -4.77                        | -4.37                       |                        |                       | 4.786                        | 4.397                       | -5.05                     | -4.87                        | 28.6                   | 1346         | 34.4347508 | -118.6494318 | Valve Adjustment:NSPS/EG CAI,High Temp,Valve 100% Closed,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed |
| CV-24038   | 8/3/2026 3:05:34 PM   | 19.7       | 65.3       | 0.4       | 14.6           |                         |                         | 0.3     | 36.5         | 146.5                | 147.1               | -2.32                        | -2.25                       |                        |                       | 2.265                        | 2.163                       | -6.30                     | -6.47                        | 28.41                  | 1345         | 34.4347482 | -118.6494358 | Valve Adjustment-Surging Liquid in Header                                                                                                                   |
| CV-24038   | 8/4/2026 9:25:00 AM   |            |            |           |                |                         | 184800                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmA; [User entered 18.48%]                                                                                                                                 |
| CV-24038   | 8/4/2026 9:25:00 AM   |            |            |           |                | 1510                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmA                                                                                                                                                        |
| CV-24038   | 8/4/2026 9:39:08 AM   | 4.0        | 72.8       | 0.7       | 22.5           |                         |                         | 0.1     | 32.1         | 189.5                | 189.2               | -5.35                        | -5.39                       |                        |                       | 5.814                        | 6.050                       | -11.87                    | -11.56                       | 28.45                  | 1324         | 34.4350266 | -118.6488387 | Valve Adjustment-No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                        |
| CV-24038   | 8/12/2026 2:37:13 PM  | 26.6       | 72.9       | 0.5       | 0.0            |                         |                         | 0.4     | 0.0          | 191.6                | 191.1               | -3.28                        | -3.04                       |                        |                       | 3.247                        | 3.074                       | -8.03                     | -8.08                        | 28.5                   | 1345         | 34.4350302 | -118.6488913 | Valve Adjustment-No Flow Measurement,High Temp                                                                                                              |
| CV-24038   | 8/12/2026 2:40:00 PM  |            |            |           |                | 1490                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmA                                                                                                                                                        |
| CV-24038   | 8/18/2026 9:07:29 AM  | 11.2       | 73.6       | 0.0       | 15.2           |                         |                         | 0.2     | 0.0          | 192.4                | 192.2               | -4.33                        | -4.24                       |                        |                       | 4.482                        | 4.410                       | -7.65                     | -7.35                        | 28.63                  | 1335         | 34.4350410 | -118.6488645 | Valve Adjustment-No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                        |
| CV-24038   | 8/18/2026 9:10:00 AM  |            |            |           |                | 1728                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmA                                                                                                                                                        |
| CV-24038   | 8/25/2026 9:00:20 AM  | 16.4       | 72.0       | 0.0       | 11.6           |                         |                         | 0.2     | 0.0          | 204.2                | 202.3               | 29.04                        | -3.20                       |                        |                       | 0.000                        | 3.193                       | -8.13                     | -6.88                        | 28.64                  | 1353         | 34.4350158 | -118.6488706 | Valve Adjustment-No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                        |
| CV-24038   | 8/25/2026 9:01:30 AM  | 20.5       | 73.8       | 0.0       | 5.7            |                         |                         | 0.3     | 0.0          | 202.1                | 202.0               | -3.56                        | -3.48                       |                        |                       | 3.538                        | 3.477                       | -6.91                     | -6.69                        | 28.62                  | 1357         | 34.4350133 | -118.6488710 | Valve Adjustment-No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                        |
| CV-24038   | 8/25/2026 10:02:17 AM | 19.2       | 60.9       | 2.5       | 17.4           |                         |                         | 0.3     | 7.0          | 139.3                | 140.1               | -4.42                        | -4.90                       |                        |                       | 4.396                        | 4.905                       | -4.92                     | -4.98                        | 28.6                   | 1350         | 34.4347532 | -118.6494237 | Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open                                                                                                          |
| CV-24039   | 8/4/2026 9:30:00 AM   |            |            |           |                |                         | 239400                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmA; [User entered 23.94%]                                                                                                                                 |
| CV-24039   | 8/4/2026 9:30:00 AM   |            |            |           |                | 1710                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmA                                                                                                                                                        |
| CV-24039   | 8/4/2026 9:41:31 AM   | 2.8        | 69.4       | 0.0       | 27.8           |                         |                         | 0.0     | 0.0          | 189.3                | 189.6               | -8.10                        | -8.09                       |                        |                       | 8.786                        | 8.717                       | -11.09                    | -11.16                       | 28.49                  | 1342         | 34.4352856 | -118.6486419 | Valve Adjustment-No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                        |
| CV-24039   | 8/11/2026 8:57:26 AM  | 1.0        | 69.3       | 0.7       | 29.0           |                         |                         | 0.0     | 41.4         | 178.0                | 168.9               | -8.40                        | -8.02                       |                        |                       | 8.737                        | 8.133                       | -10.41                    | -10.32                       | 28.62                  | 1347         | 34.4352760 | -118.6486778 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum                                                                                                |
| CV-24039   | 8/11/2026 8:58:15 AM  | 1.0        | 71.8       | 0.4       | 26.8           |                         |                         | 0.0     | 67.0         | 170.4                | 173.1               | -7.73                        | -7.70                       |                        |                       | 8.043                        | 7.886                       | -10.53                    | -10.54                       | 28.62                  | 1347         | 34.4352760 | -118.6486778 | Valve Adjustment:NSPS/EG CAI,High Temp                                                                                                                      |
| CV-24039   | 8/12/2026 2:40:10 PM  | 24.5       | 69.8       | 0.0       | 5.7            |                         |                         | 0.4     | 0.0          | 187.1                | 187.2               | -6.07                        | -6.07                       |                        |                       | 6.048                        | 6.018                       | -8.26                     | -8.40                        | 28.49                  | 1352         | 34.4352915 | -118.6486971 | Valve Adjustment-Other - See Daily Log,High Temp;Well Condition:Lorentz Pump Installed                                                                      |
| CV-24039   | 8/12/2026 2:45:00 PM  |            |            |           |                | 2262                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmA                                                                                                                                                        |
| CV-24039   | 8/18/2026 9:11:44 AM  | 13.9       | 69.6       | 0.1       | 16.4           |                         |                         | 0.2     | 164.0        | 189.3                | 189.4               | -5.39                        | -5.39                       |                        |                       | 5.912                        | 5.896                       | -7.84                     | -7.83                        | 28.62                  | 1355         | 34.4352883 | -118.6486862 | Valve Adjustment-No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                        |
| CV-24039   | 8/18/2026 9:15:00 AM  |            |            |           |                | 1370                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmA                                                                                                                                                        |
| CV-24039   | 8/25/2026 9:05:16 AM  | 19.4       | 75.1       | 0.0       | 5.5            |                         |                         | 0.3     | 0.0          | 189.9                | 190.7               | -38.66                       | -37.74                      |                        |                       | 33.306                       | 33.306                      | -7.89                     | -7.45                        | 28.61                  | 1353         | 34.4352928 | -118.6486689 | Valve Adjustment-No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                        |
| CV-24039   | 8/25/2026 9:06:27 AM  | 18.5       | 74.3       | 0.0       | 7.2            |                         |                         | 0.2     | 0.0          | 191.6                | 190.8               | -6.07                        | -6.07                       |                        |                       | 6.557                        | 6.585                       | -8.00                     | -8.08                        | 28.61                  | 1354         | 34.4352923 | -118.6486682 | Valve Adjustment-No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                        |
| CV-24040   | 8/4/2026 9:50:00 AM   |            |            |           |                |                         | 212600                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmA; [User entered 21.26%]                                                                                                                                 |
| CV-24040   | 8/4/2026 9:50:00 AM   |            |            |           |                | 2250                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmA                                                                                                                                                        |
| CV-24040   | 8/4/2026 9:57:05 AM   | 3.8        | 71.3       | 0.4       | 24.5           |                         |                         | 0.1     | 61.3         | 173.0                | 173.0               | -4.66                        | -4.60                       |                        |                       | 4.632                        | 4.553                       | -11.39                    | -11.20                       | 28.49                  | 1354         | 34.4356260 | -118.6483852 | Valve Adjustment-No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                        |
| CV-24040   | 8/11/2026 8:49:03 AM  | 0.5        | 68.5       | 1.1       | 29.9           |                         |                         | 0.0     | 27.2         | 175.0                | 174.6               | -4.03                        | -0.49                       |                        |                       | 4.058                        | 0.521                       | -9.65                     | -10.42                       | 28.62                  | 1351         | 34.4356435 | -118.6483853 | Valve Adjustment:NSPS/EG CAI,High Temp                                                                                                                      |
| CV-24040   | 8/11/2026 8:49:35 AM  | 0.5        | 70.6       | 0.3       | 28.6           |                         |                         | 0.0     | 95.3         | 177.1                | 176.9               | -0.73                        | -0.69                       |                        |                       | 0.768                        | 0.715                       | -9.44                     | -10.68                       | 28.63                  | 1351         | 34.4356312 | -118.6483978 | Valve Adjustment:NSPS/EG CAI,High Temp                                                                                                                      |
| CV-24040   | 8/12/2026 2:44:26 PM  | 22.5       | 72.4       | 0.0       | 5.1            |                         |                         | 0.3     | 0.0          | 167.7                | 169.1               | 0.94                         | -2.98                       |                        |                       | 0.000                        | 2.981                       | -7.05                     | -7.21                        | 28.48                  | 1354         | 34.4356235 | -118.6484013 | Valve Adjustment-No Flow Measurement,High Temp,Increased Flow/Vacuum,Well Condition:Lorentz Pump Installed                                                  |
| CV-24040   | 8/12/2026 2:50:00 PM  |            |            |           |                | 2890                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmA                                                                                                                                                        |
| CV-24040   | 8/18/2026 9:20:00 AM  |            |            |           |                | 2560                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmA                                                                                                                                                        |
| CV-24040   | 8/18/2026 9:20:26 AM  | 12.9       | 69.8       | 0.5       | 16.8           |                         |                         | 0.2     | 33.6         | 176.4                | 176.0               | -4.84                        | -4.71                       |                        |                       | 4.824                        | 4.716                       | 0.48                      | 0.42                         | 28.63                  | 1351         | 34.4356598 | -118.6483960 | Valve Adjustment-No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                        |
| CV-24040   | 8/25/2026 9:16:44 AM  | 26.7       | 69.4       | 0.3       | 3.6            |                         |                         | 0.4     | 12.0         | 176.7                | 176.2               | -4.13                        | -3.95                       |                        |                       | 4.132                        | 3.900                       | -6.89                     | -7.54                        | 28.6                   | 1361         | 34.4356646 | -118.6483931 | Valve Adjustment-No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                        |
| CV-24041   | 8/11/2026 8:43:30 AM  | 0.1        | 31.1       | 13.2      | 55.6           |                         |                         | 0.0     | 4.2          | 180.1                | 176.9               | -9.93                        | -8.02                       |                        |                       | 10.154                       | 8.231                       | -10.21                    | -10.10                       | 28.62                  | 1344         | 34.4358657 | -118.6480630 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum                                                                                                |
| CV-24041   | 8/11/2026 8:44:51 AM  | 0.1        | 30.7       | 13.4      | 55.8           |                         |                         | 0.0     | 4.2          | 176.8                | 179.7               | -8.13                        | -8.04                       |                        |                       | 8.365                        | 8.302                       | -10.39                    | -10.54                       | 28.63                  | 1352         | 34.4358680 | -118.6480623 | Valve Adjustment:NSPS/EG CAI,High Temp                                                                                                                      |
| CV-24041   | 8/17/2026 2:27:04 PM  | 24.9       | 34.7       | 9.4       | 31.0           |                         |                         | 0.7     | 3.3          | 103.6                | 108.2               | -7.49                        | -3.68                       | 0.0                    | 0.0                   | 7.268                        | 3.549                       | -7.54                     |                              | 28.59                  | 1352         | 34.4358665 | -118.6480437 | No Flow Measurement,                                                                                                                                        |
| CV-24041   | 8/17/2026 2:31:09 PM  | 38.5       | 54.1       | 5.4       | 2.0            |                         |                         | 0.7     | 0.4          | 108.4                | 108.4               | -3.32                        | -3.30                       | 0.0                    | 0.0                   | 3.078                        | 3.082                       | -3.28                     |                              | 28.59                  | 1352         | 34.4361083 | -118.6487197 | ,                                                                                                                                                           |
| CV-24041   | 8/19/2026 8:59:05 AM  | 0.6        | 31.7       | 1.8       | 65.9           |                         |                         | 0.0     | 36.6         | 126.7                | 129.7               | -4.77                        | -2.42                       |                        |                       | 4.650                        | 2.418                       | -7.93                     | -8.02                        | 28.54                  | 1355         | 34.4358602 | -118.6480465 | Valve Adjustment-Decreased Flow/Vacuum,Barely Open                                                                                                          |
| CV-24042   | 8/3/2026 10:02:20 AM  | 2.2        | 90.4       | 0.0       | 7.4            |                         |                         | 0.0     | 0.0          | 180.6                | 180.2               | -7.01                        | -6.74                       |                        |                       | 7.592                        | 7.211                       | -7.33                     | -7.07                        | 28.42                  | 1371         | 34.4362284 | -118.6474874 | Valve Adjustment-No Flow Measurement,High Temp                                                                                                              |
| CV-24042   | 8/3/2026 10:08:00 AM  |            |            |           |                |                         | 78300                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmA; [User entered 7.83%]                                                                                                                                  |
| CV-24042   | 8/3/2026 10:08:00 AM  |            |            |           |                | 734                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmA                                                                                                                                                        |
| CV-24042   | 8/10/2026 10:27:42 AM | 25.9       | 74.1       | 0.0       | 0.0            |                         |                         | 0.3     | 0.0          | 178.5                | 178.0               | -5.31                        | -5.62                       |                        |                       | 5.995                        | 6.271                       | -6.38                     | -6.57                        | 28.57                  | 1373         | 34.4362543 | -118.6474687 | Valve Adjustment-No Flow Measurement,High Temp                                                                                                              |
| CV-24042   | 8/10/2026 10:35:00 AM |            |            |           |                | 1730                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmA                                                                                                                                                        |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init<br>Flow<br>[scfm] | Adj<br>Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                |                                                |
|------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|------------------------|-----------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|---------------------------------------------------------------------------------------------------------|------------------------------------------------|
| CV-24042   | 8/17/2026 9:40:34 AM  | 30.1       | 67.7       | 0.0       | 2.2            |                         |                         | 0.4     | 0.0          | 179.3                | 178.9               | -6.96                        | -6.82                       |                        |                       | 7.476                        | 7.365                       | -7.46                     | -7.41                        | 28.65                  | 1378         | 34.4362539 | -118.6474850 | Valve Adjustment:No Flow Measurement,High Temp                                                          |                                                |
| CV-24042   | 8/17/2026 9:45:00 AM  |            |            |           |                | 1510                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                         | AtmAA                                          |
| CV-24042   | 8/24/2026 9:20:59 AM  | 35.6       | 64.4       | 0.0       | 0.0            |                         |                         | 0.6     | 0.0          | 179.3                | 181.8               | -6.69                        | -6.28                       |                        |                       | 7.202                        | 6.766                       | -8.09                     | -7.87                        | 28.6                   | 1375         | 34.4362475 | -118.6474762 | Valve Adjustment:No Flow Measurement,High Temp                                                          |                                                |
| CV-24042   | 8/31/2026 10:24:01 AM | 32.1       | 67.9       | 0.0       | 0.0            |                         |                         | 0.5     | 0.0          | 180.5                | 183.3               | -4.86                        | -4.83                       |                        |                       | 4.749                        | 5.403                       | -6.08                     | -6.26                        | 28.57                  |              |            |              |                                                                                                         | Valve Adjustment:No Flow Measurement,High Temp |
| CV-24043   | 8/6/2026 9:50:16 AM   | 40.5       | 55.2       | 0.1       | 4.2            |                         |                         | 0.7     | 42.0         | 122.6                | 122.7               | -7.53                        | -7.48                       |                        |                       | 7.901                        | 7.868                       | 0.32                      | 0.33                         | 28.6                   | 1333         | 34.4341003 | -118.6497167 | Well Comment:well construction unstable                                                                 |                                                |
| CV-24043   | 8/27/2026 11:19:30 AM | 31.4       | 52.5       | 0.0       | 16.1           |                         |                         | 0.6     | 0.0          | 108.4                | 108.7               | -1.46                        | -0.87                       | 34.3                   | 30.8                  | 1.372                        | 0.948                       |                           |                              | 28.56                  | 1312         | 34.4339750 | -118.6497428 | .                                                                                                       |                                                |
| CV-24044   | 8/1/2026 10:27:33 AM  | 20.6       | 73.1       | 0.1       | 6.2            |                         |                         | 0.3     | 62.0         | 157.3                | 157.4               | -2.38                        | -1.48                       |                        |                       | 2.352                        | 1.440                       | -7.21                     | -7.27                        | 28.6                   | 1344         | 34.4344023 | -118.6493887 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum                                            |                                                |
| CV-24044   | 8/1/2026 10:28:30 AM  | 20.0       | 73.4       | 0.0       | 6.6            |                         |                         | 0.3     | 0.0          | 157.5                | 157.8               | -1.50                        | -1.53                       |                        |                       | 1.459                        | 1.492                       | -7.42                     | -7.31                        | 28.6                   | 1346         | 34.4344097 | -118.6493957 | Valve Adjustment:NSPS/EG CAI,High Temp                                                                  |                                                |
| CV-24044   | 8/3/2026 10:40:00 AM  |            |            |           |                | 394                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                         | AtmAA                                          |
| CV-24044   | 8/4/2026 10:40:00 AM  |            |            |           |                |                         | 65050                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                         | AtmAA; [User entered 6.505%]                   |
| CV-24044   | 8/4/2026 10:40:49 AM  | 2.2        | 61.8       | 0.0       | 36.0           |                         |                         | 0.0     | 0.0          | 150.7                | 151.4               | -4.73                        | -4.71                       |                        |                       | 5.404                        | 5.258                       | -9.10                     | -9.00                        | 28.49                  | 1337         | 34.4343740 | -118.6494016 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                    |                                                |
| CV-24044   | 8/12/2026 2:25:00 PM  |            |            |           |                | 629                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                         | AtmAA                                          |
| CV-24044   | 8/12/2026 2:25:36 PM  | 48.2       | 51.8       | 0.0       | 0.0            |                         |                         | 0.9     | 0.0          | 149.9                | 148.8               | -3.75                        | -3.74                       |                        |                       | 3.749                        | 3.743                       | -8.15                     | -7.87                        | 28.53                  | 1345         | 34.4343866 | -118.6493873 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                    |                                                |
| CV-24044   | 8/18/2026 8:49:26 AM  | 36.0       | 62.1       | 0.0       | 1.9            |                         |                         | 0.6     | 0.0          | 153.7                | 153.9               | -4.01                        | -4.05                       |                        |                       | 3.997                        | 4.026                       | -8.17                     | -8.13                        | 28.63                  | 1342         | 34.4344066 | -118.6493943 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                    |                                                |
| CV-24044   | 8/18/2026 8:55:00 AM  |            |            |           |                | 629                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                         | AtmAA                                          |
| CV-24044   | 8/25/2026 8:42:01 AM  | 36.9       | 63.0       | 0.0       | 0.1            |                         |                         | 0.6     | 0.0          | 152.9                | 153.0               | -4.17                        | -4.11                       |                        |                       | 4.163                        | 4.096                       | -8.40                     | -8.29                        | 28.64                  | 1343         | 34.4343988 | -118.6493747 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                    |                                                |
| CV-24044   | 8/25/2026 10:12:11 AM | 20.0       | 71.3       | 0.0       | 8.7            |                         |                         | 0.3     | 0.0          | 161.4                | 161.3               | -2.64                        | -2.52                       |                        |                       | 2.617                        | 2.513                       | -5.86                     | -6.07                        | 28.6                   | 1341         | 34.4343908 | -118.6493877 | Valve Adjustment:High Temp,Barely Open                                                                  |                                                |
| CV-24045   | 8/3/2026 8:50:00 AM   |            |            |           |                | 2060                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                         | AtmAA                                          |
| CV-24045   | 8/4/2026 8:50:00 AM   |            |            |           |                |                         | 183100                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                         | AtmAA; [User entered 18.31%]                   |
| CV-24045   | 8/4/2026 8:50:00 AM   |            |            |           |                | 2060                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                         | AtmAA                                          |
| CV-24045   | 8/4/2026 9:21:19 AM   | 1.8        | 71.5       | 0.0       | 26.7           |                         |                         | 0.0     | 0.0          | 193.8                | 193.8               | -7.53                        | -7.66                       |                        |                       | 8.083                        | 8.201                       | -9.59                     | -9.57                        | 28.49                  | 1337         | 34.4347334 | -118.6490705 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                    |                                                |
| CV-24045   | 8/12/2026 2:30:42 PM  | 27.0       | 72.3       | 0.7       | 0.0            |                         |                         | 0.4     | 0.0          | 190.7                | 190.3               | -7.31                        | -7.08                       |                        |                       | 7.243                        | 7.111                       | -7.68                     | -7.54                        | 28.49                  | 1340         | 34.4347419 | -118.6490779 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                    |                                                |
| CV-24045   | 8/12/2026 2:35:00 PM  |            |            |           |                | 2230                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                         | AtmAA                                          |
| CV-24045   | 8/18/2026 8:58:17 AM  | 17.1       | 70.7       | 0.9       | 11.3           |                         |                         | 0.2     | 12.6         | 193.1                | 192.7               | -7.25                        | -7.33                       |                        |                       | 7.760                        | 7.782                       | -7.69                     | -7.75                        | 28.62                  | 1348         | 34.4347347 | -118.6490786 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                    |                                                |
| CV-24045   | 8/18/2026 9:00:00 AM  |            |            |           |                | 1800                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                         | AtmAA                                          |
| CV-24045   | 8/25/2026 8:49:09 AM  | 36.4       | 63.6       | 0.0       | 0.0            |                         |                         | 0.6     | 0.0          | 186.5                | 186.7               | -7.41                        | -6.93                       |                        |                       | 7.837                        | 7.469                       | -7.81                     | -7.28                        | 28.61                  | 1359         | 34.4347590 | -118.6490741 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                    |                                                |
| CV-24046   | 8/4/2026 10:29:26 AM  | 3.6        | 69.9       | 0.0       | 26.5           |                         |                         | 0.1     | 0.0          | 120.2                | 120.1               | -2.22                        | -2.22                       |                        |                       | 2.231                        | 2.199                       | -1.83                     | -1.77                        | 28.49                  | 1361         | 34.4350681 | -118.6484002 | Valve Adjustment:No Flow Measurement,High Temp                                                          |                                                |
| CV-24046   | 8/11/2026 9:48:37 AM  | 1.6        | 56.4       | 2.5       | 39.5           |                         |                         | 0.0     | 15.8         | 162.2                | 167.6               | -7.03                        | -6.69                       |                        |                       | 7.397                        | 7.180                       | -6.75                     | -6.72                        | 28.64                  | 1347         | 34.4350593 | -118.6483738 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum                                            |                                                |
| CV-24046   | 8/11/2026 9:49:27 AM  | 1.7        | 63.3       | 2.1       | 32.9           |                         |                         | 0.0     | 15.7         | 167.2                | 166.1               | -6.69                        | -6.69                       |                        |                       | 6.953                        | 6.926                       | -6.51                     | -6.55                        | 28.64                  | 1343         | 34.4350652 | -118.6483750 | Valve Adjustment:NSPS/EG CAI,High Temp                                                                  |                                                |
| CV-24046   | 8/17/2026 2:08:34 PM  | 16.1       | 75.8       | 1.4       | 6.7            |                         |                         | 0.2     | 4.8          | 183.8                | 184.7               | -4.05                        | -3.12                       | 57.2                   | 47.0                  | 4.269                        | 2.906                       |                           |                              | 28.59                  | 1352         | 34.4350702 | -118.6483798 | High Temp,No Flow Measurement,Reduced System Vacuum                                                     |                                                |
| CV-24046   | 8/17/2026 2:09:48 PM  | 16.6       | 76.6       | 1.1       | 5.7            |                         |                         | 0.2     | 5.2          | 185.2                | 184.9               | -2.86                        | -2.93                       | 48.7                   | 48.2                  | 3.012                        | 3.061                       |                           |                              | 28.59                  | 1348         | 34.4350803 | -118.6483820 | .                                                                                                       |                                                |
| CV-24046   | 8/17/2026 2:10:00 PM  |            |            |           |                | 2460                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                         | AtmAA                                          |
| CV-24046   | 8/18/2026 9:28:35 AM  | 14.7       | 60.2       | 2.2       | 22.9           |                         |                         | 0.2     | 10.4         | 137.6                | 137.8               | -4.98                        | -4.38                       |                        |                       | 4.974                        | 5.088                       | -4.66                     | -4.72                        | 28.6                   | 1343         | 34.4350807 | -118.6483921 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                    |                                                |
| CV-24048   | 8/11/2026 8:38:57 AM  | 2.4        | 63.4       | 2.8       | 31.4           |                         |                         | 0.0     | 11.2         | 88.3                 | 88.9                | -7.37                        | -6.73                       |                        |                       | 7.610                        | 6.955                       | -10.31                    | -10.38                       | 28.62                  | 1351         | 34.4355473 | -118.6477960 | Valve Adjustment:Decreased Flow/Vacuum                                                                  |                                                |
| CV-24048   | 8/19/2026 9:04:05 AM  | 4.2        | 78.0       | 0.3       | 17.5           |                         |                         | 0.1     | 58.3         | 104.4                | 99.0                | -6.47                        | -6.24                       |                        |                       | 6.714                        | 6.454                       | -7.60                     | -7.77                        | 28.52                  | 1361         | 34.4355448 | -118.6478048 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected |                                                |
| CV-24049   | 8/3/2026 10:14:35 AM  | 4.6        | 65.2       | 0.0       | 30.2           |                         |                         | 0.1     | 0.0          | 191.9                | 192.1               | -7.41                        | -7.41                       |                        |                       | 7.946                        | 8.000                       | -9.52                     | -9.98                        | 28.42                  | 1382         | 34.4359568 | -118.6471943 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                    |                                                |
| CV-24049   | 8/3/2026 10:16:00 AM  |            |            |           |                |                         | 151700                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                         | AtmAA; [User entered 15.17%]                   |
| CV-24049   | 8/3/2026 10:16:00 AM  |            |            |           |                | 2860                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                         | AtmAA                                          |
| CV-24049   | 8/10/2026 8:35:00 AM  |            |            |           |                |                         | 160000                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                         | AirTech Lab; [User entered 16%]                |
| CV-24049   | 8/10/2026 8:35:00 AM  |            |            |           |                | 1800                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                         | AirTech Lab                                    |
| CV-24049   | 8/10/2026 10:35:06 AM | 31.3       | 55.9       | 0.0       | 12.8           |                         |                         | 0.6     | 0.0          | 193.1                | 193.0               | -4.75                        | -4.74                       |                        |                       | 5.508                        | 5.501                       | -7.19                     | -7.33                        | 28.58                  | 1385         | 34.4359479 | -118.6472009 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                    |                                                |
| CV-24049   | 8/10/2026 10:50:00 AM |            |            |           |                | 2690                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                         | AtmAA                                          |
| CV-24049   | 8/17/2026 10:00:00 AM |            |            |           |                | 2900                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                         | AtmAA                                          |
| CV-24049   | 8/17/2026 10:01:45 AM | 23.8       | 71.2       | 0.0       | 5.0            |                         |                         | 0.3     | 0.0          | 192.5                | 192.5               | -5.15                        | -5.05                       |                        |                       | 5.675                        | 5.705                       | -7.15                     | -7.01                        | 28.67                  | 1377         | 34.4359539 | -118.6471660 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                    |                                                |
| CV-24049   | 8/19/2026 9:13:13 AM  | 34.3       | 50.9       | 0.2       | 14.6           |                         |                         | 0.7     | 73.0         | 109.0                | 108.3               | -7.30                        | -6.94                       |                        |                       | 7.571                        | 7.276                       | -7.31                     | -7.12                        | 28.54                  | 1358         | 34.4352355 | -118.6477982 | Valve Adjustment:Decreased Flow/Vacuum                                                                  |                                                |
| CV-24050   | 8/6/2026 9:36:12 AM   | 26.3       | 35.1       | 0.4       | 38.2           |                         |                         | 0.7     | 95.5         | 115.0                | 92.0                | -16.35                       | -16.32                      |                        |                       | 16.740                       | 16.743                      | -16.77                    | -16.73                       | 28.63                  | 1327         | 34.4337520 | -118.6499605 | Valve Adjustment:Valve 100% Open                                                                        |                                                |
| CV-24050   | 8/27/2026 11:09:50 AM | 31.9       | 39.1       | 0.0       | 29.0           |                         |                         | 0.8     | 0.0          | 123.2                | 123.3               | -9.81                        | -9.79                       | 0.0                    | 0.0                   | 9.899                        | 9.714                       | -9.53                     |                              | 28.58                  | 1319         | 34.4336885 | -118.6499032 | .                                                                                                       |                                                |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init<br>Flow<br>[scfm] | Adj<br>Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                            |                                   |
|------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|------------------------|-----------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|---------------------------------------------------------------------------------------------------------------------|-----------------------------------|
| CV-24051   | 8/1/2026 10:21:11 AM  | 16.1       | 60.7       | 2.5       | 20.7           |                         |                         | 0.3     | 8.3          | 118.8                | 121.3               | -1.60                        | -1.52                       |                        |                       | 1.570                        | 1.487                       | -7.54                     | -7.58                        | 28.6                   | 1348         | 34.4344605 | -118.6490105 | Valve Adjustment:Decreased Flow/Vacuum                                                                              |                                   |
| CV-24051   | 8/24/2026 12:46:15 PM | 21.8       | 56.8       | 3.1       | 18.3           |                         |                         | 0.4     | 5.9          | 124.8                | 125.1               | -1.34                        | -1.35                       |                        |                       | 1.323                        | 1.316                       | -2.94                     | -2.94                        | 28.71                  | 1346         | 34.4344640 | -118.6490325 | Valve Adjustment:Surging Liquid in Header                                                                           |                                   |
| CV-24051   | 8/25/2026 10:15:16 AM | 19.3       | 56.4       | 3.8       | 20.5           |                         |                         | 0.3     | 5.4          | 123.0                | 123.1               | -4.74                        | -4.73                       |                        |                       | 5.192                        | 5.183                       | -6.23                     | -6.07                        | 28.6                   | 1340         | 34.4344633 | -118.6490212 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed |                                   |
| CV-24052   | 8/11/2026 9:54:30 AM  | 44.3       | 45.9       | 1.7       | 8.1            |                         |                         | 1.0     | 4.8          | 111.9                | 113.0               | -7.47                        | -6.75                       |                        |                       | 7.736                        | 7.059                       | -7.28                     | -7.78                        | 28.64                  | 1370         | 34.4350683 | -118.6480790 | Valve Adjustment:Decreased Flow/Vacuum                                                                              |                                   |
| CV-24052   | 8/24/2026 12:14:30 PM | 44.0       | 43.7       | 0.8       | 11.5           |                         |                         | 1.0     | 14.4         | 122.2                | 121.4               | -5.54                        | -0.38                       |                        |                       | 5.635                        | 0.365                       | -5.68                     | -5.68                        | 28.7                   | 1356         | 34.4351053 | -118.6480582 | Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Pnumatic Pump Installed                                       |                                   |
| CV-24053   | 8/11/2026 8:32:30 AM  | 28.4       | 41.4       | 0.0       | 30.2           |                         |                         | 0.7     | 0.0          | 110.2                | 111.7               | -10.94                       | -10.73                      |                        |                       | 11.129                       | 10.865                      | -10.93                    | -10.54                       | 28.62                  | 1369         | 34.4352543 | -118.6477888 | Valve Adjustment:Decreased Flow/Vacuum                                                                              |                                   |
| CV-24053   | 8/13/2026 10:00:00 AM |            |            |           |                |                         | 6900                    |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                     | AirTech Lab; [User entered 0.69%] |
| CV-24053   | 8/13/2026 10:00:00 AM |            |            |           |                | 65                      |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                     | AirTech Lab                       |
| CV-24053   | 8/24/2026 12:25:50 PM | 32.4       | 49.1       | 0.0       | 18.5           |                         |                         | 0.7     | 0.0          | 123.6                | 123.5               | -6.67                        | -6.01                       |                        |                       | 6.799                        | 6.013                       | -6.91                     | -6.73                        | 28.7                   | 1372         | 34.4352632 | -118.6477750 | Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Pnumatic Pump Installed                                       |                                   |
| CV-24054   | 8/3/2026 10:11:02 AM  | 2.3        | 74.0       | 0.0       | 23.7           |                         |                         | 0.0     | 0.0          | 168.5                | 172.4               | -10.41                       | -10.89                      |                        |                       | 10.995                       | 11.392                      | -11.01                    | -11.71                       | 28.42                  | 1384         | 34.4356151 | -118.6471892 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                |                                   |
| CV-24054   | 8/3/2026 10:13:00 AM  |            |            |           |                |                         | 108000                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                     | AtmAA; [User entered 10.8%]       |
| CV-24054   | 8/3/2026 10:13:00 AM  |            |            |           |                | 1430                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                     | AtmAA                             |
| CV-24054   | 8/10/2026 1:02:22 PM  | 31.4       | 68.6       | 0.0       | 0.0            |                         |                         | 0.5     | 0.0          | 173.3                | 173.5               | -7.71                        | -7.69                       |                        |                       | 7.696                        | 7.680                       | -8.75                     | -8.76                        | 28.53                  | 1339         | 34.4356267 | -118.6471712 | Valve Adjustment:No Flow Measurement,High Temp                                                                      |                                   |
| CV-24054   | 8/10/2026 1:05:00 PM  |            |            |           |                | 1700                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                     | AtmAA                             |
| CV-24054   | 8/17/2026 10:06:49 AM | 28.1       | 71.8       | 0.0       | 0.1            |                         |                         | 0.4     | 0.0          | 177.1                | 177.3               | -7.22                        | -7.27                       |                        |                       | 7.779                        | 7.803                       | -7.64                     | -7.67                        | 28.64                  | 1377         | 34.4356195 | -118.6471779 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed                               |                                   |
| CV-24054   | 8/17/2026 10:10:00 AM |            |            |           |                | 1640                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                     | AtmAA                             |
| CV-24054   | 8/24/2026 9:36:55 AM  | 32.0       | 68.0       | 0.0       | 0.0            |                         |                         | 0.5     | 0.0          | 176.3                | 176.3               | -7.75                        | -7.41                       |                        |                       | 8.231                        | 7.964                       | -8.08                     | -7.85                        | 28.6                   | 1394         | 34.4356490 | -118.6471684 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed                               |                                   |
| CV-24054   | 8/31/2026 1:51:01 PM  | 20.2       | 74.7       | 0.0       | 5.1            |                         |                         | 0.3     | 0.0          | 177.4                | 177.4               | -5.67                        | -5.69                       |                        |                       | 5.751                        | 5.787                       | -6.09                     | -6.06                        | 28.49                  | 1374         | 34.4356449 | -118.6472068 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed                               |                                   |
| CV-24055   | 8/10/2026 8:30:00 AM  |            |            |           |                |                         | 62000                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                     | AirTech Lab; [User entered 6.2%]  |
| CV-24055   | 8/10/2026 8:30:00 AM  |            |            |           |                | 1000                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                     | AirTech Lab                       |
| CV-24055   | 8/12/2026 11:19:25 AM | 10.5       | 53.1       | 2.9       | 33.5           |                         |                         | 0.2     | 11.6         | 144.8                | 144.7               | -0.48                        | -0.48                       |                        |                       | 0.481                        | 0.494                       | -8.27                     | -8.51                        | 28.59                  | 1394         | 34.4358733 | -118.6469285 | Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open                                                                  |                                   |
| CV-24055   | 8/12/2026 11:20:04 AM | 10.1       | 52.7       | 2.5       | 34.7           |                         |                         | 0.2     | 13.9         | 144.8                | 144.7               | -0.49                        | -0.49                       |                        |                       | 0.497                        | 0.491                       | -8.29                     | -8.45                        | 28.6                   | 1399         | 34.4358653 | -118.6469352 |                                                                                                                     |                                   |
| CV-24055   | 8/17/2026 2:09:12 PM  | 6.6        | 49.7       | 3.3       | 40.4           |                         |                         | 0.1     | 12.2         | 131.5                | 131.9               | -0.45                        | -0.47                       |                        |                       | 0.421                        | 0.373                       | -6.57                     | -6.65                        | 28.53                  | 1381         | 34.4358558 | -118.6469428 | Valve Adjustment:High Temp,Barely Open                                                                              |                                   |
| CV-24056   | 8/5/2026 7:56:43 AM   | 19.4       | 59.4       | 2.8       | 18.4           |                         |                         | 0.3     | 6.6          | 107.9                | 107.8               | -1.32                        | -1.31                       | 0.0                    | 0.0                   | 1.299                        | 1.298                       |                           |                              | 28.55                  | 1312         | 34.4332798 | -118.6501563 | .                                                                                                                   |                                   |
| CV-24056   | 8/17/2026 10:23:23 AM | 28.8       | 62.7       | 0.0       | 8.5            |                         |                         | 0.5     | 0.0          | 131.4                | 132.3               | -0.38                        | -0.37                       |                        |                       | 0.371                        | 0.365                       | -10.06                    | -10.21                       | 28.69                  | 1319         | 34.4332768 | -118.6501598 | Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open                                                                  |                                   |
| CV-24056   | 8/17/2026 10:23:40 AM | 28.8       | 62.7       | 0.0       | 8.5            |                         |                         | 0.5     | 0.0          | 132.1                | 132.3               | -0.39                        | -0.38                       |                        |                       | 0.381                        | 0.377                       | -10.23                    | -10.46                       | 28.69                  | 1317         | 34.4332720 | -118.6501633 | Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open                                                                  |                                   |
| CV-24057   | 8/6/2026 1:20:00 AM   |            |            |           |                |                         | 103200                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                     | AtmAA; [User entered 10.32%]      |
| CV-24057   | 8/6/2026 9:23:04 AM   | 19.4       | 69.0       | 0.0       | 11.6           |                         |                         | 0.3     | 0.0          | 149.5                | 148.0               | -2.94                        | -1.46                       | 6.0                    | 8.4                   | 0.104                        | 0.200                       | -16.47                    | -16.46                       | 28.6                   | 1340         | 34.4334895 | -118.6496663 | Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open                                                        |                                   |
| CV-24057   | 8/6/2026 9:24:23 AM   | 15.3       | 72.3       | 0.0       | 12.4           |                         |                         | 0.2     | 0.0          | 147.6                | 147.6               | -1.24                        | -1.21                       | 7.4                    | 8.0                   | 0.155                        | 0.182                       | -16.36                    | -16.45                       | 28.6                   | 1341         | 34.4334735 | -118.6496643 | Valve Adjustment:Barely Open                                                                                        |                                   |
| CV-24057   | 8/6/2026 1:20:00 PM   |            |            |           |                | 1110                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                     | AtmAA                             |
| CV-24057   | 8/6/2026 1:40:27 PM   | 21.7       | 70.2       | 0.0       | 8.1            |                         |                         | 0.3     | 0.0          | 147.9                | 150.0               | 0.60                         | -3.17                       | 14.7                   | 32.8                  | 0.615                        | 3.113                       | -12.54                    | -11.82                       | 28.56                  | 1325         | 34.4334549 | -118.6496625 | Valve Adjustment:High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed                              |                                   |
| CV-24057   | 8/6/2026 1:42:08 PM   | 30.6       | 69.4       | 0.0       | 0.0            |                         |                         | 0.4     | 0.0          | 149.9                | 149.8               | -3.32                        | -3.33                       | 33.8                   | 33.9                  | 3.311                        | 3.315                       | -12.44                    | -12.14                       | 28.58                  | 1327         | 34.4334600 | -118.6496620 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                                                    |                                   |
| CV-24057   | 8/11/2026 10:12:53 AM | 34.7       | 57.3       | 0.7       | 7.3            |                         |                         | 0.6     | 10.4         | 143.7                | 143.7               | -4.89                        | -4.80                       | 26.2                   | 25.5                  | 1.960                        | 1.851                       | -7.70                     | -7.41                        | 28.68                  | 1346         | 34.4334532 | -118.6496539 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                                                    |                                   |
| CV-24057   | 8/25/2026 9:44:46 AM  | 28.1       | 54.4       | 0.2       | 17.3           |                         |                         | 0.5     | 86.5         | 144.1                | 144.0               | -4.49                        | -3.65                       | 20.0                   | 17.3                  | 1.145                        | 0.857                       | -8.28                     | -8.70                        | 28.6                   | 1341         | 34.4334663 | -118.6496542 | Valve Adjustment:High Temp,Decreased Flow/Vacuum                                                                    |                                   |
| CV-24058   | 8/6/2026 9:56:07 AM   | 18.0       | 28.4       | 0.4       | 53.2           |                         |                         | 0.6     | 133.0        | 113.0                | 113.4               | -7.09                        | -7.09                       |                        |                       | 7.511                        | 7.451                       | -9.19                     | -9.29                        | 28.6                   | 1353         | 34.4338195 | -118.6494513 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)                                       |                                   |
| CV-24058   | 8/19/2026 10:21:39 AM | 30.2       | 36.3       | 0.2       | 33.3           |                         |                         | 0.8     | 166.5        | 120.4                | 120.6               | -2.54                        | -2.59                       |                        |                       | 2.507                        | 2.561                       | -3.69                     | -2.51                        | 28.56                  | 1339         | 34.4337758 | -118.6494660 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)                           |                                   |
| CV-24059   | 8/6/2026 10:05:39 AM  | 26.7       | 62.2       | 0.3       | 10.8           |                         |                         | 0.4     | 36.0         | 156.5                | 156.0               | -7.43                        | -7.09                       | 9.0                    | 8.4                   | 0.237                        | 0.206                       | -17.63                    | -17.67                       | 28.59                  | 1347         | 34.4337922 | -118.6490628 | Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open                                                        |                                   |
| CV-24059   | 8/6/2026 10:06:00 AM  |            |            |           |                |                         | 93800                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                     | AtmAA; [User entered 9.38%]       |
| CV-24059   | 8/6/2026 10:06:00 AM  |            |            |           |                | 703                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                     | AtmAA                             |
| CV-24059   | 8/13/2026 2:29:27 PM  | 6.6        | 66.6       | 2.3       | 24.5           |                         |                         | 0.1     | 10.7         | 112.4                | 113.6               | -8.32                        | -8.31                       | 7.3                    | 7.2                   | 0.146                        | 0.143                       | -14.07                    | -14.11                       | 28.56                  | 1341         | 34.4337642 | -118.6490953 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                                                    |                                   |
| CV-24059   | 8/20/2026 1:19:59 PM  | 29.7       | 70.2       | 0.0       | 0.1            |                         |                         | 0.4     | 0.0          | 150.4                | 154.9               | -1.63                        | -3.34                       | 6.5                    | 4.1                   | 0.119                        | 0.049                       | -11.79                    | -13.27                       | 28.58                  | 1339         | 34.4337676 | -118.6490834 | Valve Adjustment:High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed                              |                                   |
| CV-24059   | 8/20/2026 1:20:59 PM  | 33.0       | 67.0       | 0.0       | 0.0            |                         |                         | 0.5     | 0.0          | 154.8                | 154.8               | -3.29                        | -3.28                       | 4.5                    | 5.0                   | 0.059                        | 0.071                       | -13.21                    | -12.99                       | 28.58                  | 1345         | 34.4337616 | -118.6490785 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                                                    |                                   |
| CV-24059   | 8/26/2026 10:06:48 AM | 21.6       | 68.3       | 0.0       | 10.1           |                         |                         | 0.3     | 0.0          | 154.3                | 154.2               | -6.92                        | -6.97                       | 15.9                   | 16.7                  | 0.738                        | 0.819                       | -12.41                    | -11.47                       | 28.56                  | 1361         | 34.4337513 | -118.6490791 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                                                    |                                   |

**All LFG Extraction Wells - August 2020**  
**Chiquita Canyon Landfill**

| Point Name  | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init Flow<br>[scfm] | Adj Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                                  |                                   |
|-------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|---------------------|--------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|-------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------|
| CV-24060    | 8/6/2026 2:39:05 PM   | 31.7       | 62.1       | 0.3       | 5.9            |                         |                         | 0.5     | 19.7         | 144.3                | 146.0               | -13.88                       | -12.80                      |                     |                    | 14.051                       | 12.771                      | -14.16                    | -14.28                       | 28.51                  | 1360         | 34.4340490 | -118.6487837 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header;Well Condition:Lorentz Pump Installed   |                                   |
| CV-24060    | 8/6/2026 2:40:36 PM   | 32.1       | 62.1       | 0.4       | 5.4            |                         |                         | 0.5     | 13.5         | 144.2                | 144.8               | -12.58                       | -12.60                      |                     |                    | 12.691                       | 12.689                      | -14.10                    | -14.21                       | 28.51                  | 1357         | 34.4340518 | -118.6487882 | Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed |                                   |
| CV-24060    | 8/18/2026 1:28:22 PM  | 41.3       | 54.4       | 0.3       | 4.0            |                         |                         | 0.8     | 13.3         | 135.1                | 132.5               | -12.41                       | -11.40                      |                     |                    | 12.430                       | 11.341                      | -13.86                    | -13.78                       | 28.56                  | 1344         | 34.4340252 | -118.6487933 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                    |                                   |
| CV-24061    | 8/11/2026 8:22:04 AM  | 24.4       | 60.4       | 0.0       | 15.2           |                         |                         | 0.4     | 0.0          | 142.8                | 143.3               | -1.39                        | -0.50                       |                     |                    | 1.417                        | 0.532                       | -10.79                    | -10.65                       | 28.62                  | 1361         | 34.4343417 | -118.6486372 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum                                                                              |                                   |
| CV-24061    | 8/11/2026 8:22:30 AM  | 24.1       | 62.4       | 0.0       | 13.5           |                         |                         | 0.4     | 0.0          | 142.6                | 142.1               | -0.34                        | -0.34                       |                     |                    | 0.352                        | 0.356                       | -10.84                    | -10.88                       | 28.62                  | 1366         | 34.4343467 | -118.6486378 | Valve Adjustment:NSPS/EG CAI,High Temp                                                                                                    |                                   |
| CV-24061    | 8/26/2026 8:45:29 AM  | 49.4       | 46.5       | 0.0       | 4.1            |                         |                         | 1.1     | 0.0          | 104.7                | 104.7               | -4.17                        | -3.27                       |                     |                    | 4.178                        | 3.242                       | -9.58                     | -9.91                        | 28.52                  | 1355         | 34.4343657 | -118.6486210 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                    |                                   |
| CV-24062    | 8/5/2026 9:25:00 AM   |            |            |           |                |                         | 99200                   |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AtmAA; [User entered 9.92%]       |
| CV-24062    | 8/5/2026 9:25:00 AM   |            |            |           |                | 1390                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AtmAA                             |
| CV-24062    | 8/11/2026 9:00:00 AM  |            |            |           |                |                         | 110000                  |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AirTech Lab; [User entered 11%]   |
| CV-24062    | 8/11/2026 9:00:00 AM  |            |            |           |                | 800                     |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AirTech Lab                       |
| CV-24062    | 8/11/2026 9:02:17 AM  | 37.4       | 62.6       | 0.0       | 0.0            |                         |                         | 0.6     | 0.0          | 179.6                | 179.1               | -5.39                        | -5.39                       |                     |                    | 5.837                        | 5.887                       | -9.73                     | -9.81                        | 28.62                  | 1365         | 34.4345877 | -118.6480798 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                      |                                   |
| CV-24062    | 8/11/2026 9:10:00 AM  |            |            |           |                | 1170                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AtmAA                             |
| CV-24062    | 8/19/2026 9:36:51 AM  | 36.1       | 63.9       | 0.0       | 0.0            |                         |                         | 0.6     | 0.0          | 179.0                | 178.9               | -5.01                        | -5.05                       |                     |                    | 5.488                        | 5.497                       | -6.43                     | -6.40                        | 28.57                  | 1361         | 34.4345903 | -118.6480930 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                      |                                   |
| CV-24062    | 8/26/2026 9:11:37 AM  | 9.3        | 77.6       | 0.0       | 13.1           |                         |                         | 0.1     | 0.0          | 177.8                | 178.0               | -8.47                        | -8.42                       |                     |                    | 9.145                        | 9.039                       | -9.94                     | -9.89                        | 28.56                  | 1380         | 34.4345951 | -118.6481154 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                      |                                   |
| CV-24063    | 8/5/2026 9:06:00 AM   |            |            |           |                |                         | 82600                   |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AtmAA; [User entered 8.26%]       |
| CV-24063    | 8/5/2026 9:06:00 AM   |            |            |           |                | 2010                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AtmAA                             |
| CV-24063    | 8/11/2026 8:49:07 AM  | 25.0       | 75.0       | 0.0       | 0.0            |                         |                         | 0.3     | 0.0          | 183.2                | 183.4               | -5.39                        | -5.39                       |                     |                    | 5.769                        | 5.832                       | -9.43                     | -9.14                        | 28.61                  | 1377         | 34.4349348 | -118.6475390 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                      |                                   |
| CV-24063    | 8/11/2026 8:55:00 AM  |            |            |           |                | 2060                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AtmAA                             |
| CV-24063    | 8/11/2026 9:10:00 AM  |            |            |           |                |                         | 100000                  |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AirTech Lab; [User entered 10%]   |
| CV-24063    | 8/11/2026 9:10:00 AM  |            |            |           |                | 1400                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AirTech Lab                       |
| CV-24063    | 8/19/2026 8:57:44 AM  | 15.3       | 84.7       | 0.0       | 0.0            |                         |                         | 0.2     | 0.0          | 180.8                | 180.9               | -4.95                        | -4.86                       |                     |                    | 5.274                        | 5.209                       | -5.90                     | -6.67                        | 28.57                  | 1362         | 34.4349619 | -118.6475037 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                      |                                   |
| CV-24063    | 8/26/2026 9:05:54 AM  | 5.4        | 79.8       | 0.0       | 14.8           |                         |                         | 0.1     | 0.0          | 186.6                | 186.6               | -9.10                        | -8.89                       |                     |                    | 9.672                        | 9.488                       | -10.02                    | -9.94                        | 28.53                  | 1370         | 34.4349845 | -118.6475361 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                      |                                   |
| CV-24064-PL | 8/4/2026 1:38:00 AM   |            |            |           |                |                         | 125500                  |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AtmAA; [User entered 12.55%]      |
| CV-24064-PL | 8/4/2026 1:38:00 PM   |            |            |           |                | 2600                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AtmAA                             |
| CV-24064-PL | 8/4/2026 1:40:41 PM   | 11.8       | 80.0       | 0.0       | 8.2            |                         |                         | 0.1     | 0.0          | 191.3                | 191.5               | -13.44                       | -11.46                      |                     |                    | 13.832                       | 11.737                      | -15.51                    | -15.49                       | 28.47                  | 1382         | 34.4352233 | -118.6471512 | Valve Adjustment:No Flow Measurement,High Temp                                                                                            |                                   |
| CV-24064-PL | 8/10/2026 8:45:00 AM  |            |            |           |                |                         | 130000                  |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AirTech Lab; [User entered 13%]   |
| CV-24064-PL | 8/10/2026 8:45:00 AM  |            |            |           |                | 1500                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AirTech Lab                       |
| CV-24064-PL | 8/11/2026 8:34:13 AM  | 11.0       | 79.7       | 0.1       | 9.2            |                         |                         | 0.1     | 92.0         | 192.1                | 192.1               | -14.33                       | -13.91                      |                     |                    | 14.790                       | 14.383                      | -18.21                    | -18.01                       | 28.61                  | 1383         | 34.4352077 | -118.6471685 | Valve Adjustment:No Flow Measurement,High Temp                                                                                            |                                   |
| CV-24064-PL | 8/11/2026 8:40:00 AM  |            |            |           |                | 2340                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AtmAA                             |
| CV-24064-PL | 8/18/2026 1:38:23 PM  | 45.5       | 53.3       | 0.0       | 1.2            |                         |                         | 0.9     | 0.0          | 191.4                | 191.4               | -13.02                       | -13.02                      |                     |                    | 13.218                       | 13.118                      | -14.72                    | -15.03                       | 28.55                  | 1368         | 34.4352115 | -118.6471657 | Valve Adjustment:No Flow Measurement,High Temp                                                                                            |                                   |
| CV-24064-PL | 8/18/2026 1:50:00 PM  |            |            |           |                | 2460                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AtmAA                             |
| CV-24064-PL | 8/26/2026 8:14:44 AM  | 19.0       | 55.8       | 0.0       | 25.2           |                         |                         | 0.3     | 0.0          | 191.9                | 191.9               | -14.42                       | -14.45                      |                     |                    | 14.862                       | 14.776                      | -17.23                    | -17.52                       | 28.53                  | 1376         | 34.4352220 | -118.6471759 | Valve Adjustment:No Flow Measurement,High Temp                                                                                            |                                   |
| CV-24065-TR | 8/6/2026 8:35:00 AM   |            |            |           |                |                         | 9300                    |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AirTech Lab; [User entered 0.93%] |
| CV-24065-TR | 8/6/2026 8:35:00 AM   |            |            |           |                | 180                     |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AirTech Lab                       |
| CV-24065-TR | 8/7/2026 2:17:18 PM   | 11.6       | 50.4       | 4.8       | 33.2           |                         |                         | 0.2     | 6.9          | 126.2                | 126.1               | -5.19                        | -4.71                       |                     |                    | 5.366                        | 4.748                       | -9.73                     | -9.62                        | 28.52                  | 1386         | 34.4356198 | -118.6467997 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                    |                                   |
| CV-24065-TR | 8/17/2026 1:30:12 PM  | 12.9       | 61.1       | 1.4       | 24.6           |                         |                         | 0.2     | 17.6         | 120.3                | 120.7               | -3.77                        | -3.33                       |                     |                    | 3.739                        | 3.227                       | -7.13                     | -6.94                        | 28.54                  | 1376         | 34.4356145 | -118.6468287 | Valve Adjustment:Barely Open,Valve 100% Closed                                                                                            |                                   |
| CV-24066    | 8/5/2026 7:49:09 AM   | 17.3       | 42.8       | 0.0       | 39.9           |                         |                         | 0.4     | 0.0          | 115.0                | 115.7               | -2.55                        | -2.43                       | 0.0                 | 0.0                | 2.568                        | 2.414                       | -17.15                    |                              | 28.55                  | 1355         | 34.4330320 | -118.6498607 |                                                                                                                                           |                                   |
| CV-24066    | 8/12/2026 8:45:00 AM  |            |            |           |                |                         | 15000                   |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AirTech Lab; [User entered 1.5%]  |
| CV-24066    | 8/12/2026 8:45:00 AM  |            |            |           |                | 130                     |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AirTech Lab                       |
| CV-24066    | 8/17/2026 10:25:54 AM | 24.0       | 40.5       | 0.0       | 35.5           |                         |                         | 0.6     | 0.0          | 125.0                | 125.2               | -1.54                        | -1.53                       |                     |                    | 1.528                        | 1.490                       | -11.56                    | -11.13                       | 28.69                  | 1324         | 34.4330155 | -118.6498008 |                                                                                                                                           |                                   |
| CV-24067    | 8/4/2026 1:33:17 PM   | 16.6       | 55.8       | 0.0       | 27.6           |                         |                         | 0.3     | 0.0          | 159.4                | 159.5               | -3.67                        | -3.67                       |                     |                    | 0.000                        | 0.000                       | -7.37                     | -7.38                        | 28.59                  | 1300         | 34.4332088 | -118.6496948 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                      |                                   |
| CV-24067    | 8/4/2026 1:35:00 PM   |            |            |           |                |                         | 36150                   |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AtmAA; [User entered 3.615%]      |
| CV-24067    | 8/4/2026 1:35:00 PM   |            |            |           |                | 468.5                   |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AtmAA                             |
| CV-24067    | 8/5/2026 7:42:19 AM   | 19.1       | 52.8       | 0.1       | 28.0           |                         |                         | 0.4     | 280.0        | 153.2                | 152.0               | -1.87                        | -1.83                       | 0.0                 | 0.0                | -0.045                       | -0.023                      | -12.29                    |                              | 28.55                  | 1335         | 34.4331933 | -118.6497168 | NSPS/EG CAI,High Temp                                                                                                                     |                                   |
| CV-24067    | 8/5/2026 7:45:01 AM   | 19.3       | 52.0       | 0.0       | 28.7           |                         |                         | 0.4     | 0.0          | 146.4                | 146.6               | -1.74                        | -1.75                       |                     |                    | 0.022                        | 0.024                       | -12.66                    |                              | 28.55                  | 1325         | 34.4331703 | -118.6497540 | NSPS/EG CAI,High Temp                                                                                                                     |                                   |
| CV-24067    | 8/11/2026 1:15:00 PM  |            |            |           |                | 3100                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                           | AtmAA                             |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name  | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init<br>Flow<br>[scfm] | Adj<br>Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                                |                                  |
|-------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|------------------------|-----------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|-----------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|
| CV-24067    | 8/11/2026 1:19:24 PM  | 15.7       | 77.9       | 0.0       | 6.4            |                         |                         | 0.2     | 0.0          | 151.4                | 159.5               | 0.08                         | -3.71                       |                        |                       | 0.013                        | 0.000                       | -10.16                    | -9.20                        | 28.67                  | 1325         | 34.4331839 | -118.6497360 | Valve Adjustment:High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed                                                  |                                  |
| CV-24067    | 8/11/2026 1:21:35 PM  | 7.6        | 78.6       | 0.1       | 13.7           |                         |                         | 0.1     | 137.0        | 165.6                | 166.2               | -3.16                        | -3.06                       |                        |                       | 0.000                        | 0.000                       | -8.42                     | -8.27                        | 28.67                  | 1326         | 34.4331902 | -118.6497396 | Valve Adjustment:High Temp                                                                                                              |                                  |
| CV-24067    | 8/17/2026 10:28:06 AM | 1.7        | 77.6       | 0.0       | 20.7           |                         |                         | 0.0     | 0.0          | 121.0                | 121.2               | 2.48                         | 1.79                        |                        |                       | 0.033                        | 0.009                       | 3.36                      | 2.02                         | 28.69                  | 1310         | 34.4331977 | -118.6497393 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.                                                                                     |                                  |
| CV-24067    | 8/17/2026 10:28:29 AM | 1.7        | 78.5       | 0.0       | 19.8           |                         |                         | 0.0     | 0.0          | 121.8                | 121.3               | 2.73                         | 2.54                        |                        |                       | 0.000                        | 0.000                       | 3.36                      | 3.02                         | 28.69                  | 1308         | 34.4331988 | -118.6497457 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.                                                                                     |                                  |
| CV-24067    | 8/18/2026 1:33:25 PM  | 16.7       | 75.5       | 0.1       | 7.7            |                         |                         | 0.2     | 77.0         | 109.6                | 110.2               | 2.96                         | 2.61                        |                        |                       | 0.000                        | 0.003                       | 3.34                      | 2.09                         | 28.64                  | 1313         | 34.4331843 | -118.6497395 | Valve Adjustment:Positive Static Press.,Surging Liquid in Header;Well Condition:Lorentz Pump Installed                                  |                                  |
| CV-24067    | 8/18/2026 1:34:22 PM  | 12.8       | 76.9       | 0.0       | 10.3           |                         |                         | 0.2     | 0.0          | 110.0                | 110.0               | 3.08                         | 3.15                        |                        |                       | 0.025                        | 0.000                       | 3.46                      | 3.47                         | 28.64                  | 1318         | 34.4331800 | -118.6497442 | Well Condition:Lorentz Pump Installed                                                                                                   |                                  |
| CV-24068    | 8/6/2026 9:17:03 AM   | 20.5       | 38.5       | 0.6       | 40.4           |                         |                         | 0.5     | 67.3         | 124.7                | 124.0               | -5.40                        | -4.87                       |                        |                       | 5.694                        | 5.175                       | -15.54                    | -15.65                       | 28.6                   | 1347         | 34.4332592 | -118.6493468 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open                                                                                      |                                  |
| CV-24068    | 8/17/2026 11:03:53 AM | 11.9       | 70.0       | 0.0       | 18.1           |                         |                         | 0.2     | 0.0          | 175.2                | 176.7               | 0.51                         | -0.11                       |                        |                       | 0.000                        | 0.209                       | -4.50                     | -3.95                        | 28.69                  | 1329         | 34.4332497 | -118.6493707 | Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum                                                     |                                  |
| CV-24068    | 8/17/2026 11:04:36 AM | 13.5       | 74.8       | 0.0       | 11.7           |                         |                         | 0.2     | 0.0          | 176.8                | 177.2               | -0.25                        | -0.24                       |                        |                       | 0.384                        | 0.371                       | -4.41                     | -4.12                        | 28.67                  | 1341         | 34.4332462 | -118.6493533 | Valve Adjustment:NSPS/EG CAI,High Temp                                                                                                  |                                  |
| CV-24068    | 8/24/2026 1:04:07 PM  | 49.3       | 50.7       | 0.0       | 0.0            |                         |                         | 1.0     | 0.0          | 146.8                | 148.7               | -1.64                        | -2.63                       |                        |                       | 1.636                        | 2.617                       | -7.62                     | -6.63                        | 28.6                   | 1352         | 34.4332802 | -118.6493497 | Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum                                                                    |                                  |
| CV-24068    | 8/24/2026 1:05:06 PM  | 52.6       | 47.4       | 0.0       | 0.0            |                         |                         | 1.1     | 0.0          | 145.9                | 147.1               | -3.20                        | -3.20                       |                        |                       | 3.183                        | 3.181                       | -7.03                     | -7.06                        | 28.63                  | 1345         | 34.4332362 | -118.6493582 | Valve Adjustment:No Flow Measurement,High Temp                                                                                          |                                  |
| CV-24069    | 8/6/2026 10:10:17 AM  | 14.8       | 46.2       | 0.6       | 38.4           |                         |                         | 0.3     | 64.0         | 124.6                | 124.7               | -4.35                        | -2.57                       |                        |                       | 4.358                        | 2.544                       | -17.69                    | -17.65                       | 28.6                   | 1342         | 34.4334467 | -118.6489117 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open;Well Condition:Lorentz Pump Installed                                                |                                  |
| CV-24069    | 8/12/2026 8:40:00 AM  |            |            |           |                |                         | 61000                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                         | AirTech Lab; [User entered 6.1%] |
| CV-24069    | 8/12/2026 8:40:00 AM  |            |            |           |                | 680                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                         | AirTech Lab                      |
| CV-24069    | 8/17/2026 11:15:26 AM | 19.1       | 39.9       | 0.0       | 41.0           |                         |                         | 0.5     | 0.0          | 126.1                | 125.2               | -2.56                        | -1.85                       |                        |                       | 2.543                        | 1.834                       | -12.39                    | -12.20                       | 28.67                  | 1349         | 34.4334393 | -118.6489378 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                  |                                  |
| CV-24070    | 8/5/2026 1:15:00 PM   |            |            |           |                |                         | 51500                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                         | AtmAA; [User entered 5.15%]      |
| CV-24070    | 8/5/2026 1:15:00 PM   |            |            |           |                | 1350                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                         | AtmAA                            |
| CV-24070    | 8/6/2026 10:16:11 AM  | 28.3       | 66.4       | 0.1       | 5.2            |                         |                         | 0.4     | 52.0         | 145.3                | 144.8               | -9.45                        | -3.44                       | 17.2                   | 7.1                   | 6.741                        | 1.132                       | -18.29                    | -17.70                       | 28.58                  | 1349         | 34.4337475 | -118.6486930 | Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open                                                                            |                                  |
| CV-24070    | 8/11/2026 9:50:00 AM  |            |            |           |                | 1980                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                         | AtmAA                            |
| CV-24070    | 8/11/2026 9:58:05 AM  | 22.2       | 75.5       | 0.0       | 2.3            |                         |                         | 0.3     | 0.0          | 150.5                | 151.4               | 0.20                         | -3.58                       | 15.8                   | 25.8                  | 1.682                        | 4.550                       | -14.86                    | -14.67                       | 28.64                  | 1369         | 34.4337168 | -118.6486994 | Valve Adjustment:High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed                                                  |                                  |
| CV-24070    | 8/11/2026 9:59:08 AM  | 19.9       | 73.9       | 0.0       | 6.2            |                         |                         | 0.3     | 0.0          | 151.5                | 151.5               | -3.85                        | -3.82                       | 25.4                   | 25.4                  | 4.381                        | 4.396                       | -14.80                    | -14.61                       | 28.63                  | 1368         | 34.4337218 | -118.6486876 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                                                                        |                                  |
| CV-24070    | 8/12/2026 9:05:00 AM  |            |            |           |                |                         | 74000                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                         | AirTech Lab; [User entered 7.4%] |
| CV-24070    | 8/12/2026 9:05:00 AM  |            |            |           |                | 1000                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                         | AirTech Lab                      |
| CV-24070    | 8/19/2026 2:15:36 PM  | 29.3       | 66.6       | 0.0       | 4.1            |                         |                         | 0.4     | 0.0          | 148.9                | 148.9               | -2.14                        | -2.12                       | 22.0                   | 21.9                  | 3.269                        | 3.252                       | -13.28                    | -12.21                       | 28.52                  | 1351         | 34.4337129 | -118.6486681 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                                                                        |                                  |
| CV-24070    | 8/26/2026 10:01:22 AM | 19.2       | 72.8       | 0.0       | 8.0            |                         |                         | 0.3     | 0.0          | 149.3                | 149.2               | -3.53                        | -3.55                       | 22.1                   | 22.5                  | 3.305                        | 3.443                       | -13.01                    | -13.36                       | 28.55                  | 1369         | 34.4337309 | -118.6487032 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                                                                        |                                  |
| CV-24071    | 8/6/2026 2:29:21 PM   | 27.8       | 64.1       | 0.2       | 7.9            |                         |                         | 0.4     | 39.5         | 130.6                | 130.5               | -0.68                        | -0.67                       | 10.2                   | 10.4                  | 0.671                        | 0.696                       | -8.02                     | -7.92                        | 28.51                  | 1358         | 34.4340032 | -118.6484642 | Valve Adjustment:Barely Open                                                                                                            |                                  |
| CV-24071    | 8/11/2026 9:25:00 AM  |            |            |           |                |                         | 74000                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                         | AirTech Lab; [User entered 7.4%] |
| CV-24071    | 8/11/2026 9:25:00 AM  |            |            |           |                | 620                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                         | AirTech Lab                      |
| CV-24071    | 8/18/2026 1:36:23 PM  | 30.7       | 63.1       | 0.2       | 6.0            |                         |                         | 0.5     | 30.0         | 135.5                | 135.1               | -1.35                        | -0.76                       | 10.5                   | 8.1                   | 0.724                        | 0.431                       | -7.37                     | -7.40                        | 28.56                  | 1344         | 34.4339840 | -118.6484828 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header;Well Condition:Lorentz Pump Installed |                                  |
| CV-24071    | 8/18/2026 1:37:29 PM  | 30.5       | 63.5       | 0.2       | 5.8            |                         |                         | 0.5     | 29.0         | 134.9                | 134.9               | -0.63                        | -0.64                       | 8.3                    | 7.6                   | 0.446                        | 0.377                       | -7.35                     | -7.40                        | 28.56                  | 1350         | 34.4339920 | -118.6484765 | Valve Adjustment:High Temp,Surging Liquid in Header;Well Condition:Lorentz Pump Installed                                               |                                  |
| CV-24072    | 8/6/2026 2:55:45 PM   | 35.7       | 62.7       | 0.1       | 1.5            |                         |                         | 0.6     | 15.0         | 116.5                | 117.3               | -0.30                        | -0.30                       |                        |                       | 0.233                        | 0.226                       | -7.53                     | -7.34                        | 28.5                   | 1364         | 34.4341753 | -118.6480360 | Valve Adjustment:Barely Open                                                                                                            |                                  |
| CV-24072    | 8/18/2026 1:41:42 PM  | 46.1       | 53.8       | 0.1       | 0.0            |                         |                         | 0.9     | 0.0          | 112.2                | 112.2               | -3.79                        | -3.94                       |                        |                       | 3.783                        | 3.954                       | -7.19                     | -7.53                        | 28.53                  | 1360         | 34.4341710 | -118.6480413 | Valve Adjustment:No Flow Measurement,Surging Liquid in Header,Surging Liquid in Well (Watered In)                                       |                                  |
| CV-24073-TF | 8/5/2026 10:00:00 AM  |            |            |           |                |                         | 46900                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                         | AtmAA; [User entered 4.69%]      |
| CV-24073-TF | 8/5/2026 10:00:00 AM  |            |            |           |                | 1290                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                         | AtmAA                            |
| CV-24073-TF | 8/11/2026 9:17:35 AM  | 17.0       | 79.6       | 0.0       | 3.4            |                         |                         | 0.2     | 0.0          | 157.3                | 157.6               | -4.01                        | -3.99                       |                        |                       | 3.988                        | 3.973                       | -9.24                     | -9.22                        | 28.61                  | 1381         | 34.4346312 | -118.6477037 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                    |                                  |
| CV-24073-TF | 8/11/2026 9:25:00 AM  |            |            |           |                | 1970                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                         | AtmAA                            |
| CV-24073-TF | 8/18/2026 9:48:54 AM  | 24.6       | 75.3       | 0.1       | 0.0            |                         |                         | 0.3     | 0.0          | 158.6                | 156.6               | -3.93                        | -3.39                       |                        |                       | 3.930                        | 3.385                       | -6.48                     | -6.57                        | 28.58                  | 1358         | 34.4346417 | -118.6477092 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header;Well Condition:Lorentz Pump Installed |                                  |
| CV-24073-TF | 8/18/2026 9:53:21 AM  | 24.6       | 72.0       | 0.1       | 3.3            |                         |                         | 0.3     | 33.0         | 159.0                | 159.1               | -3.44                        | -3.44                       |                        |                       | 3.424                        | 3.432                       | -6.73                     | -6.67                        | 28.57                  | 1340         | 34.4346203 | -118.6477288 | Valve Adjustment:High Temp                                                                                                              |                                  |
| CV-24073-TF | 8/19/2026 9:55:33 AM  | 36.8       | 63.2       | 0.0       | 0.0            |                         |                         | 0.6     | 0.0          | 159.9                | 159.8               | -2.58                        | -2.57                       |                        |                       | 2.582                        | 2.549                       | -6.13                     | -6.11                        | 28.56                  | 1357         | 34.4346240 | -118.6476891 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                    |                                  |
| CV-24073-TF | 8/26/2026 9:23:18 AM  | 32.1       | 62.2       | 0.0       | 5.7            |                         |                         | 0.5     | 0.0          | 158.1                | 158.3               | -4.70                        | -4.64                       |                        |                       | 4.675                        | 4.623                       | -8.52                     | -8.69                        | 28.53                  | 1374         | 34.4346441 | -118.6477236 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                    |                                  |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name  | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init Flow<br>[scfm] | Adj Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                   |                              |
|-------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|---------------------|--------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|------------------------------------------------------------------------------------------------------------|------------------------------|
| CV-24074    | 8/7/2026 8:43:14 AM   | 15.3       | 75.8       | 0.5       | 8.4            |                         |                         | 0.2     | 16.8         | 124.8                | 125.5               | -8.44                        | -5.27                       |                     |                    | 8.780                        | 5.522                       | -10.80                    | -10.59                       | 28.6                   | 1374         | 34.4347428 | -118.6473992 | Valve Adjustment:Decreased Flow/Vacuum                                                                     |                              |
| CV-24074    | 8/18/2026 9:44:47 AM  | 1.4        | 83.3       | 0.2       | 15.1           |                         |                         | 0.0     | 75.5         | 123.7                | 122.8               | -1.49                        | -1.30                       |                     |                    | 1.472                        | 1.289                       | -6.42                     | -6.65                        | 28.56                  | 1375         | 34.4347498 | -118.6473975 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open                                                         |                              |
| CV-24075-TF | 8/3/2026 1:45:00 PM   |            |            |           |                | 1960                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                            | AtmAA                        |
| CV-24075-TF | 8/4/2026 1:44:39 PM   | 11.3       | 82.9       | 0.0       | 5.8            |                         |                         | 0.1     | 0.0          | 187.3                | 187.4               | -5.73                        | -5.76                       |                     |                    | 6.002                        | 6.161                       | -13.54                    | -14.06                       | 28.47                  | 1384         | 34.4350423 | -118.6470933 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                       |                              |
| CV-24075-TF | 8/4/2026 1:45:00 PM   |            |            |           |                |                         | 112900                  |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                            | AtmAA; [User entered 11.29%] |
| CV-24075-TF | 8/11/2026 8:45:54 AM  | 21.3       | 78.5       | 0.2       | 0.0            |                         |                         | 0.3     | 0.0          | 187.9                | 188.0               | -5.39                        | -5.35                       |                     |                    | 5.850                        | 5.719                       | -16.17                    | -15.45                       | 28.61                  | 1385         | 34.4350178 | -118.6471299 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                       |                              |
| CV-24075-TF | 8/11/2026 8:50:00 AM  |            |            |           |                | 1550                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                            | AtmAA                        |
| CV-24075-TF | 8/18/2026 1:49:32 PM  | 25.7       | 73.7       | 0.6       | 0.0            |                         |                         | 0.3     | 0.0          | 187.3                | 187.3               | -6.38                        | -6.36                       |                     |                    | 6.499                        | 6.494                       | -13.71                    | -13.81                       | 28.53                  | 1356         | 34.4350124 | -118.6471384 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                       |                              |
| CV-24075-TF | 8/18/2026 2:00:00 PM  |            |            |           |                | 1960                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                            | AtmAA                        |
| CV-24075-TF | 8/26/2026 8:27:04 AM  | 8.6        | 78.1       | 0.3       | 13.0           |                         |                         | 0.1     | 43.3         | 186.2                | 186.2               | -8.30                        | -8.32                       |                     |                    | 8.697                        | 8.639                       | -15.93                    | -15.35                       | 28.52                  | 1374         | 34.4350275 | -118.6471118 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                       |                              |
| CV-24076    | 8/3/2026 1:30:00 PM   |            |            |           |                |                         | 33100                   |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                            | AtmAA; [User entered 3.31%]  |
| CV-24076    | 8/3/2026 1:30:00 PM   |            |            |           |                | 851                     |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                            | AtmAA                        |
| CV-24076    | 8/3/2026 1:35:28 PM   | 12.2       | 55.4       | 1.2       | 31.2           |                         |                         | 0.2     | 26.0         | 175.7                | 175.2               | -4.62                        | -3.74                       |                     |                    | 4.601                        | 3.708                       | -8.25                     | -8.35                        | 28.4                   | 1382         | 34.4353334 | -118.6468746 | Valve Adjustment:High Temp,Decreased Flow/Vacuum                                                           |                              |
| CV-24076    | 8/3/2026 1:36:26 PM   | 12.2       | 55.7       | 1.1       | 31.0           |                         |                         | 0.2     | 28.2         | 175.4                | 175.2               | -3.44                        | -3.42                       |                     |                    | 3.440                        | 3.457                       | -7.54                     | -7.66                        | 28.38                  | 1384         | 34.4353324 | -118.6468741 | Valve Adjustment:High Temp                                                                                 |                              |
| CV-24076    | 8/13/2026 1:30:00 PM  |            |            |           |                | 1390                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                            | AtmAA                        |
| CV-24076    | 8/13/2026 1:37:35 PM  | 25.4       | 56.5       | 0.9       | 17.2           |                         |                         | 0.4     | 19.1         | 176.6                | 176.4               | -3.88                        | -3.91                       |                     |                    | 3.900                        | 3.847                       | -9.22                     | -9.73                        | 28.51                  | 1364         | 34.4353173 | -118.6468869 | Valve Adjustment:High Temp                                                                                 |                              |
| CV-24076    | 8/18/2026 10:43:06 AM | 38.4       | 54.0       | 0.0       | 7.6            |                         |                         | 0.7     | 0.0          | 180.0                | 179.9               | -2.43                        | -2.44                       |                     |                    | 2.395                        | 2.436                       | -5.67                     | -6.11                        | 28.58                  | 1387         | 34.4353085 | -118.6468712 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                                           |                              |
| CV-24076    | 8/18/2026 10:45:00 AM |            |            |           |                | 1570                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                            | AtmAA                        |
| CV-24076    | 8/26/2026 8:48:21 AM  | 10.0       | 40.0       | 4.7       | 45.3           |                         |                         | 0.3     | 9.6          | 165.8                | 166.1               | -6.46                        | -6.23                       |                     |                    | 6.993                        | 6.762                       | -10.15                    | -8.88                        | 28.49                  | 1399         | 34.4353454 | -118.6468825 | Valve Adjustment:High Temp                                                                                 |                              |
| CV-24077    | 8/4/2026 1:28:38 PM   | 16.3       | 61.4       | 0.0       | 22.3           |                         |                         | 0.3     | 0.0          | 150.6                | 150.6               | -4.86                        | -4.85                       |                     |                    | 4.664                        | 4.628                       | -12.84                    | -12.76                       | 28.58                  | 1310         | 34.4326963 | -118.6492850 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                       |                              |
| CV-24077    | 8/4/2026 1:30:00 PM   |            |            |           |                |                         | 32200                   |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                            | AtmAA; [User entered 3.22%]  |
| CV-24077    | 8/4/2026 1:30:00 PM   |            |            |           |                | 778                     |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                            | AtmAA                        |
| CV-24077    | 8/5/2026 10:23:13 AM  | 20.5       | 56.7       | 0.0       | 22.8           |                         |                         | 0.4     | 0.0          | 150.4                | 149.5               | -5.52                        | -2.84                       | 0.0                 | 0.0                | 5.432                        | 2.621                       | -15.41                    |                              | 28.56                  | 1316         | 34.4326778 | -118.6492415 | NSPS/EG CAI,High Temp                                                                                      |                              |
| CV-24077    | 8/5/2026 10:25:00 AM  | 17.3       | 73.5       | 0.0       | 9.2            |                         |                         | 0.2     | 0.0          | 148.1                | 148.3               | -2.21                        | -2.14                       | 0.0                 | 0.0                | 2.081                        | 2.081                       | -15.26                    |                              | 28.56                  | 1316         | 34.4327280 | -118.6493080 | NSPS/EG CAI,High Temp                                                                                      |                              |
| CV-24077    | 8/11/2026 1:10:00 PM  |            |            |           |                | 1530                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                            | AtmAA                        |
| CV-24077    | 8/11/2026 1:12:06 PM  | 32.5       | 48.6       | 0.1       | 18.8           |                         |                         | 0.7     | 188.0        | 144.3                | 144.5               | -4.72                        | -4.61                       |                     |                    | 4.764                        | 4.648                       | -14.15                    | -13.98                       | 28.64                  | 1312         | 34.4327001 | -118.6492899 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                       |                              |
| CV-24077    | 8/27/2026 10:58:50 AM | 12.8       | 80.8       | 0.1       | 6.3            |                         |                         | 0.2     | 63.0         | 155.7                | 155.5               | -0.60                        | -0.59                       | 0.0                 | 0.0                | 0.441                        | 0.443                       | -8.58                     |                              | 28.57                  | 1348         | 34.4326918 | -118.6493323 | NSPS/EG CAI,High Temp                                                                                      |                              |
| CV-24077    | 8/27/2026 10:59:50 AM | 12.8       | 80.8       | 0.1       | 6.3            |                         |                         | 0.2     | 63.0         | 155.9                | 155.9               | -0.39                        | -0.36                       | 0.0                 | 0.0                | 0.244                        | 0.221                       | -9.65                     |                              | 28.57                  | 1322         | 34.4326648 | -118.6492630 | NSPS/EG CAI,High Temp                                                                                      |                              |
| CV-24077    | 8/31/2026 1:48:05 PM  | 12.8       | 74.6       | 0.0       | 12.6           |                         |                         | 0.2     | 0.0          | 160.5                | 160.6               | -0.24                        | -2.17                       |                     |                    | 0.187                        | 2.177                       | -8.38                     | -8.53                        | 28.61                  | 1332         | 34.4326986 | -118.6493135 | Valve Adjustment:No Flow Measurement,High Temp;Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed |                              |
| CV-24077    | 8/31/2026 1:48:55 PM  | 14.6       | 73.0       | 0.0       | 12.4           |                         |                         | 0.2     | 0.0          | 160.4                | 160.4               | -2.17                        | -2.45                       |                     |                    | 2.149                        | 2.411                       | -8.31                     | -8.99                        | 28.61                  | 1334         | 34.4326837 | -118.6493061 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                       |                              |
| CV-24078    | 8/5/2026 7:37:40 AM   | 15.4       | 61.1       | 3.6       | 19.9           |                         |                         | 0.3     | 5.5          | 103.7                | 94.6                | -2.72                        | -1.91                       | 16.3                | 0.0                | 0.077                        | -0.004                      | -17.80                    |                              | 28.54                  | 1345         | 34.4328882 | -118.6494453 | Audible Flow,                                                                                              |                              |
| CV-24078    | 8/17/2026 10:31:53 AM | 11.2       | 72.6       | 0.7       | 15.5           |                         |                         | 0.2     | 22.1         | 116.7                | 117.0               | -0.22                        | -0.22                       | 2.6                 | 2.6                | 0.018                        | 0.018                       | -12.77                    | -12.77                       | 28.69                  | 1320         | 34.4329090 | -118.6494460 | Valve Adjustment:Barely Open                                                                               |                              |
| CV-24079-TF | 8/6/2026 9:13:08 AM   | 1.2        | 58.3       | 7.9       | 32.6           |                         |                         | 0.0     | 4.1          | 91.0                 | 91.1                | -1.22                        | -1.20                       |                     |                    | 1.214                        | 1.190                       | -9.25                     | -9.27                        | 28.6                   | 1356         | 34.4330060 | -118.6491285 | Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)          |                              |
| CV-24079-TF | 8/17/2026 10:59:50 AM | 2.8        | 83.7       | 0.0       | 13.5           |                         |                         | 0.0     | 0.0          | 110.7                | 110.8               | -0.46                        | -0.42                       |                     |                    | 0.464                        | 0.431                       | -3.33                     | -3.58                        | 28.69                  | 1343         | 34.4329865 | -118.6491353 | Valve Adjustment:Barely Open                                                                               |                              |
| CV-24080    | 8/6/2026 9:05:17 AM   | 38.5       | 55.9       | 0.1       | 5.5            |                         |                         | 0.7     | 55.0         | 121.9                | 121.6               | -3.22                        | -3.12                       | 6.5                 | 6.2                | 0.117                        | 0.106                       | -18.38                    | -16.68                       | 28.6                   | 1358         | 34.4331497 | -118.6488785 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open                                                         |                              |
| CV-24080    | 8/17/2026 10:55:14 AM | 40.7       | 52.5       | 0.0       | 6.8            |                         |                         | 0.8     | 0.0          | 123.4                | 123.7               | -1.25                        | -1.19                       | 3.8                 | 3.3                | 0.039                        | 0.029                       | -8.46                     | -11.46                       | 28.66                  | 1357         | 34.4331402 | -118.6488578 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open                                                         |                              |
| CV-24081-TF | 8/6/2026 10:22:24 AM  | 45.5       | 51.1       | 0.2       | 3.2            |                         |                         | 0.9     | 16.0         | 116.8                | 117.9               | -4.86                        | -4.86                       |                     |                    | 4.861                        | 4.863                       | -17.50                    | -17.50                       | 28.59                  | 1353         | 34.434368  | -118.6485895 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)                  |                              |
| CV-24081-TF | 8/17/2026 11:22:14 AM | 23.7       | 60.4       | 0.0       | 15.9           |                         |                         | 0.4     | 0.0          | 122.0                | 122.6               | -1.49                        | -1.34                       |                     |                    | 1.471                        | 1.333                       | -13.03                    | -13.42                       | 28.66                  | 1346         | 34.434202  | -118.6485938 | Valve Adjustment:Decreased Flow/Vacuum                                                                     |                              |
| CV-24082    | 8/6/2026 2:11:52 PM   | 33.9       | 59.8       | 0.2       | 6.1            |                         |                         | 0.6     | 30.5         | 122.3                | 122.2               | -5.40                        | -5.40                       |                     |                    | 5.499                        | 5.494                       | -12.29                    | -12.50                       | 28.5                   | 1375         | 34.434252  | -118.6483323 |                                                                                                            |                              |
| CV-24082    | 8/18/2026 1:00:54 PM  | 42.3       | 53.8       | 0.1       | 3.8            |                         |                         | 0.8     | 38.0         | 123.1                | 122.9               | -7.61                        | -7.59                       |                     |                    | 7.830                        | 7.792                       | -13.42                    | -13.89                       | 28.56                  | 1356         | 34.433955  | -118.6483312 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)                              |                              |
| CV-24083    | 8/5/2026 1:05:00 AM   |            |            |           |                | 1170                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                            | AtmAA                        |
| CV-24083    | 8/5/2026 1:05:00 PM   |            |            |           |                |                         | 62500                   |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                            | AtmAA; [User entered 6.25%]  |
| CV-24083    | 8/11/2026 9:40:00 AM  |            |            |           |                | 1170                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                            | AtmAA                        |
| CV-24083    | 8/11/2026 9:49:55 AM  | 39.0       | 61.0       | 0.0       | 0.0            |                         |                         | 0.6     | 0.0          | 156.1                | 158.0               | -4.03                        | -3.77                       |                     |                    | 4.001                        | 3.764                       | -4.38                     | -4.08                        | 28.64                  | 1368         | 34.4337007 | -118.6483445 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                       |                              |
| CV-24083    | 8/18/2026 1:09:10 PM  | 45.1       | 50.2       | 0.1       | 4.6            |                         |                         | 0.9     | 46.0         | 123.0                | 122.8               | -7.47                        | -6.63                       |                     |                    | 7.702                        | 6.706                       | -12.71                    | -13.22                       | 28.53                  | 1354         | 34.4338822 | -118.6483282 | Valve Adjustment:Decreased Flow/Vacuum                                                                     |                              |
| CV-24083    | 8/19/2026 2:01:26 PM  | 26.9       | 72.9       | 0.0       | 0.2            |                         |                         | 0.4     | 0.0          | 159.6                | 159.4               | 0.50                         | -0.27                       |                     |                    | 0.000                        | 0.338                       | -0.37                     | -0.55                        | 28.49                  | 1358         | 34.4337165 | -118.6483189 | Valve Adjustment:No Flow Measurement,High Temp;Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed |                              |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name  | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init<br>Flow<br>[scfm] | Adj<br>Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                                          |                              |
|-------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|------------------------|-----------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|---------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------|
| CV-24083    | 8/19/2026 2:02:16 PM  | 27.6       | 70.8       | 0.0       | 1.6            |                         |                         | 0.4     | 0.0          | 159.5                | 159.0               | -0.19                        | -0.19                       |                        |                       | 0.154                        | 0.134                       | -0.44                     | -0.29                        | 28.5                   | 1359         | 34.4337144 | -118.6483227 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                              |                              |
| CV-24083    | 8/26/2026 9:56:45 AM  | 2.1        | 81.1       | 0.1       | 16.7           |                         |                         | 0.0     | 167.0        | 158.0                | 158.1               | -3.98                        | -3.84                       |                        |                       | 4.018                        | 3.794                       | -3.72                     | -3.58                        | 28.53                  | 1359         | 34.4337122 | -118.6483482 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                              |                              |
| CV-24084-TF | 8/5/2026 10:30:00 AM  |            |            |           |                |                         | 102600                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                   | AtmAA; [User entered 10.26%] |
| CV-24084-TF | 8/5/2026 10:30:00 AM  |            |            |           |                | 3590                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                   | AtmAA                        |
| CV-24084-TF | 8/11/2026 9:32:01 AM  | 8.7        | 79.2       | 0.0       | 12.1           |                         |                         | 0.1     | 0.0          | 184.5                | 184.4               | -7.75                        | -7.46                       |                        |                       | 8.354                        | 8.127                       | -13.50                    | -13.47                       | 28.63                  | 1369         | 34.4338552 | -118.6480119 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                              |                              |
| CV-24084-TF | 8/11/2026 9:35:00 AM  |            |            |           |                | 2510                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                   | AtmAA                        |
| CV-24084-TF | 8/19/2026 1:53:18 PM  | 8.4        | 80.3       | 0.0       | 11.3           |                         |                         | 0.1     | 0.0          | 185.3                | 185.3               | -5.69                        | -5.22                       |                        |                       | 5.725                        | 5.229                       | -8.46                     | -8.55                        | 28.49                  | 1341         | 34.4338816 | -118.6480451 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                              |                              |
| CV-24084-TF | 8/26/2026 9:51:07 AM  | 1.6        | 80.6       | 0.0       | 17.8           |                         |                         | 0.0     | 0.0          | 184.7                | 184.7               | -7.99                        | -7.74                       |                        |                       | 8.659                        | 8.415                       | -11.38                    | -11.47                       | 28.53                  | 1372         | 34.4338606 | -118.6480365 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                              |                              |
| CV-24085    | 8/10/2026 1:51:36 PM  | 46.0       | 48.9       | 0.0       | 5.1            |                         |                         | 0.9     | 0.0          | 122.4                | 128.8               | -0.06                        | -0.04                       |                        |                       | 0.012                        | 0.000                       | -0.10                     | -0.33                        | 28.6                   | 1365         | 34.4323563 | -118.6490475 | Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum;Well Comment:pump is active;Well Condition:Lorentz Pump Installed       |                              |
| CV-24085    | 8/10/2026 1:53:42 PM  | 46.6       | 47.4       | 0.0       | 6.0            |                         |                         | 1.0     | 0.0          | 129.4                | 129.5               | -0.05                        | -0.06                       |                        |                       | 0.037                        | 0.042                       | -0.27                     | -0.37                        | 28.59                  | 1358         | 34.4323735 | -118.6490263 | Well Condition:Lorentz Pump Installed                                                                                                             |                              |
| CV-24085    | 8/12/2026 8:46:00 AM  | 24.9       | 35.6       | 0.0       | 39.6           |                         |                         | 0.7     | 0.0          | 132.6                | 130.9               | -3.04                        | -1.66                       | 42.0                   | 16.3                  | 4.969                        | 0.738                       | -10.78                    | -11.46                       | 28.57                  | 1355         | 34.4324055 | -118.6490043 | Valve Adjustment:NSPS/EG CAC,NSPS/EG CAC,Orifice Plate Changed (See OP Log),High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed |                              |
| CV-24085    | 8/12/2026 8:51:32 AM  | 22.1       | 35.7       | 0.0       | 42.2           |                         |                         | 0.6     | 0.0          | 130.6                | 124.5               | -1.23                        | -0.84                       | 6.6                    | 3.4                   | 0.120                        | 0.032                       | -11.24                    | -11.98                       | 28.57                  | 1354         | 34.4324010 | -118.6490082 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open;Well Condition:Lorentz Pump Installed                                                          |                              |
| CV-24085    | 8/12/2026 8:53:29 AM  | 22.6       | 35.9       | 0.0       | 41.6           |                         |                         | 0.6     | 0.0          | 122.6                | 122.4               | -0.72                        | -0.72                       | 1.3                    | 0.7                   | 0.005                        | 0.002                       | -10.33                    | -11.37                       | 28.57                  | 1349         | 34.4324057 | -118.6489927 | Valve Adjustment:Barely Open;Well Condition:Lorentz Pump Installed                                                                                |                              |
| CV-24085    | 8/27/2026 11:34:49 AM | 44.0       | 48.2       | 0.8       | 7.0            |                         |                         | 0.9     | 8.8          | 105.2                | 103.6               | 0.33                         | -0.11                       | 0.0                    | 0.0                   | 0.027                        | 0.414                       | -0.12                     |                              | 28.56                  | 1332         | 34.4323102 | -118.6490175 | NSPS/EG CAC,Positive Static Press.                                                                                                                |                              |
| CV-24085    | 8/27/2026 11:36:28 AM | 43.6       | 49.7       | 0.1       | 6.6            |                         |                         | 0.9     | 66.0         | 103.2                | 103.3               | -0.29                        | -0.24                       | 0.0                    | 0.0                   | 0.429                        | 0.425                       | -0.20                     |                              | 28.56                  | 1358         | 34.4322935 | -118.6489590 | NSPS/EG CAC,                                                                                                                                      |                              |
| CV-24086    | 8/6/2026 9:01:15 AM   | 38.5       | 52.6       | 0.0       | 8.9            |                         |                         | 0.7     | 0.0          | 123.8                | 123.8               | -0.75                        | -0.71                       | 6.8                    | 8.1                   | 0.126                        | 0.178                       | -13.80                    | -13.81                       | 28.59                  | 1362         | 34.4328880 | -118.6487160 | Valve Adjustment:Barely Open                                                                                                                      |                              |
| CV-24086    | 8/17/2026 10:42:11 AM | 50.8       | 46.4       | 0.0       | 2.8            |                         |                         | 1.1     | 0.0          | 118.4                | 119.4               | -0.59                        | -0.58                       | 8.6                    | 8.4                   | 0.198                        | 0.189                       | -5.37                     | -5.38                        | 28.66                  | 1363         | 34.4329155 | -118.6486965 | Valve Adjustment:Barely Open                                                                                                                      |                              |
| CV-24087    | 8/4/2026 1:42:39 PM   | 34.5       | 39.1       | 1.6       | 24.8           |                         |                         | 0.9     | 15.5         | 121.7                | 121.6               | -0.49                        | -0.49                       | 7.7                    | 7.7                   | 0.161                        | 0.161                       | -10.05                    | -10.05                       | 28.45                  | 1356         | 34.4330220 | -118.6481105 | Valve Adjustment:Barely Open                                                                                                                      |                              |
| CV-24087    | 8/27/2026 11:59:07 AM | 33.5       | 54.4       | 0.0       | 12.1           |                         |                         | 0.6     | 0.0          | 119.8                | 120.1               | -0.40                        | -0.30                       | 6.9                    | 6.9                   | 0.143                        | 0.143                       | -8.10                     |                              | 28.52                  | 1394         | 34.4329337 | -118.6481183 | .                                                                                                                                                 |                              |
| CV-24088    | 8/7/2026 8:14:51 AM   | 47.7       | 49.3       | 0.0       | 3.0            |                         |                         | 1.0     | 0.0          | 114.5                | 115.6               | -5.40                        | -5.40                       |                        |                       | 5.691                        | 5.688                       | -16.46                    | -16.52                       | 28.6                   | 1391         | 34.4336092 | -118.6476623 | Valve Adjustment:Surging Liquid in Header                                                                                                         |                              |
| CV-24088    | 8/18/2026 1:57:15 PM  | 48.7       | 51.1       | 0.2       | 0.0            |                         |                         | 1.0     | 0.0          | 116.1                | 116.2               | -2.82                        | -2.82                       |                        |                       | 2.815                        | 2.813                       | -12.19                    | -12.16                       | 28.52                  | 1388         | 34.4335727 | -118.6476650 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)                                                                     |                              |
| CV-24089    | 8/10/2026 1:01:41 PM  | 0.6        | 1.4        | 19.6      | 78.5           |                         |                         | 0.5     | 4.0          | 101.3                | 102.4               | -9.12                        | -9.11                       | 2.4                    | 2.5                   | 0.015                        | 0.017                       | -9.11                     | -9.07                        | 28.61                  | 1357         | 34.4324358 | -118.6481122 | Valve Adjustment:NSPS/EG CAC,High O2,Plugged/Pinched Suspected;Well Condition:Lorentz Pump Installed                                              |                              |
| CV-24089    | 8/10/2026 1:03:09 PM  | 0.5        | 1.1        | 19.7      | 78.7           |                         |                         | 0.5     | 4.0          | 102.4                | 102.3               | -9.24                        | -9.06                       | 2.4                    | 0.8                   | 0.015                        | 0.002                       | -9.20                     | -8.98                        | 28.61                  | 1345         | 34.4324545 | -118.6480810 | Valve Adjustment:High O2,Plugged/Pinched Suspected;Well Condition:Fair,Lorentz Pump Installed                                                     |                              |
| CV-24089    | 8/10/2026 1:04:21 PM  | 0.5        | 1.1        | 19.7      | 78.7           |                         |                         | 0.5     | 4.0          | 102.5                | 102.6               | -8.83                        | -8.73                       | 2.8                    | 3.5                   | 0.021                        | 0.033                       | -8.86                     | -8.72                        | 28.61                  | 1348         | 34.4324538 | -118.6480868 | Valve Comment:Closed valve;Valve Adjustment:High O2,Valve 100% Closed;Well Condition:Lorentz Pump Installed                                       |                              |
| CV-24089    | 8/12/2026 9:07:17 AM  | 39.1       | 37.5       | 1.4       | 22.0           |                         |                         | 1.0     | 15.9         | 84.5                 | 84.6                | -12.37                       | -12.55                      | 4.1                    | 3.1                   | 0.044                        | 0.026                       | -12.31                    | -12.33                       | 28.57                  | 1371         | 34.4324235 | -118.6480760 | Valve Adjustment:NSPS/EG CAC,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed                                            |                              |
| CV-24089    | 8/12/2026 9:10:11 AM  | 41.4       | 39.2       | 0.2       | 19.1           |                         |                         | 1.1     | 83.2         | 86.3                 | 86.3                | -12.84                       | -13.22                      | 2.4                    | 7.7                   | 0.016                        | 0.157                       | -12.85                    | -13.80                       | 28.57                  | 1378         | 34.4324295 | -118.6480735 | Valve Adjustment:Barely Open,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed                                            |                              |
| CV-24089    | 8/21/2026 7:42:05 AM  | 0.0        | 0.1        | 21.0      | 78.9           |                         |                         | 0.0     | 3.8          | 78.5                 | 79.6                | -9.69                        | -9.56                       | 3.9                    | 1.7                   | 0.040                        | 0.007                       | -9.61                     | -9.55                        | 28.6                   | 1365         | 34.4324333 | -118.6480938 | Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected                       |                              |
| CV-24089    | 8/21/2026 7:42:31 AM  | 0.0        | 0.1        | 20.9      | 79.0           |                         |                         | 0.0     | 3.8          | 79.8                 | 79.8                | -9.54                        | -9.60                       | 6.7                    | 4.8                   | 0.117                        | 0.059                       | -9.26                     | -9.86                        | 28.6                   | 1368         | 34.4324295 | -118.6480837 | Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected                       |                              |
| CV-24089    | 8/26/2026 1:14:18 PM  | 0.8        | 3.7        | 20.0      | 75.5           |                         |                         | 0.2     | 3.8          | 110.0                | 111.7               | -7.02                        | -6.94                       | 0.3                    | 2.6                   | 0.000                        | 0.018                       | -6.99                     | -6.85                        | 28.48                  | 1353         | 34.4324292 | -118.6480970 | Valve Adjustment:High O2,Valve 100% Closed,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:valve possibly damaged       |                              |
| CV-24089    | 8/28/2026 11:53:45 AM | 46.7       | 49.3       | 0.0       | 4.0            |                         |                         | 0.9     | 0.0          | 125.2                | 125.3               | -0.37                        | -0.36                       | 5.4                    | 5.4                   | 0.641                        | 0.637                       | -6.00                     | -5.80                        | 28.53                  | 1344         | 34.4324418 | -118.6480790 | Valve Adjustment:Orifice Plate Changed (See OP Log)                                                                                               |                              |
| CV-24090    | 8/10/2026 12:54:28 PM | 43.9       | 45.1       | 0.0       | 11.0           |                         |                         | 1.0     | 0.0          | 117.1                | 117.3               | -0.63                        | -0.63                       |                        |                       | 0.653                        | 0.653                       | -9.02                     | -9.02                        | 28.57                  | 1383         | 34.4326802 | -118.6475488 | Well Condition:Lorentz Pump Installed                                                                                                             |                              |
| CV-24090    | 8/21/2026 8:29:26 AM  | 43.4       | 37.1       | 0.0       | 19.5           |                         |                         | 1.2     | 0.0          | 115.1                | 115.7               | -0.85                        | -0.83                       |                        |                       | 0.844                        | 0.820                       | -8.82                     | -8.56                        | 28.6                   | 1369         | 34.4327023 | -118.6475168 | Valve Adjustment:Barely Open                                                                                                                      |                              |
| CV-24091    | 8/4/2026 3:47:22 PM   | 15.8       | 44.4       | 8.8       | 31.0           |                         |                         | 0.4     | 3.5          | 100.7                | 100.9               | -8.78                        | -8.78                       | 1.8                    | 3.0                   | 0.009                        | 0.024                       | -8.24                     | -8.65                        | 28.41                  | 1374         | 34.4329888 | -118.6469035 | Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:well to tall to adjust             |                              |
| CV-24091    | 8/16/2026 2:12:47 PM  | 16.1       | 40.1       | 8.9       | 35.0           |                         |                         | 0.4     | 3.9          | 100.4                | 100.4               | -6.79                        | -6.85                       | 2.9                    | 2.7                   | 0.022                        | 0.019                       | -6.89                     | -6.99                        | 28.64                  | 1365         | 34.4329805 | -118.6469205 | Valve Adjustment:NSPS/EG CAC,High O2;Well Condition:Lorentz Pump Installed                                                                        |                              |
| CV-24091    | 8/16/2026 2:18:30 PM  | 16.4       | 40.5       | 8.8       | 34.3           |                         |                         | 0.4     | 3.9          | 100.4                | 100.2               | -1.74                        | -1.78                       | 1.7                    | 1.6                   | 0.008                        | 0.007                       | -7.31                     | -7.36                        | 28.64                  | 1378         | 34.4329922 | -118.6469305 | Valve Adjustment:High O2;Well Comment:pump is active;Well Condition:Lorentz Pump Installed                                                        |                              |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init Flow<br>[scfm] | Adj Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                                                                                                       |                                   |
|------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|---------------------|--------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------|
| CV-24092   | 8/31/2026 9:43:47 AM  | 51.7       | 46.0       | 0.0       | 2.3            |                         |                         | 1.1     | 0.0          | 118.6                | 118.7               | -3.29                        | -3.29                       | 21.6                | 21.7               | 1.279                        | 1.291                       | -6.22                     | -6.36                        | 28.49                  | 1402         | 34.4332998 | -118.6461368 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected                                                                                                        |                                   |
| CV-24093   | 8/1/2026 9:50:12 AM   | 52.1       | 44.8       | 0.3       | 2.8            |                         |                         | 1.2     | 9.3          | 119.1                | 119.1               | -1.79                        | -1.79                       | 16.8                | 16.8               | 0.657                        | 0.660                       | -21.55                    | -21.39                       | 28.52                  | 1411         | 34.4340480 | -118.6463293 | Valve Adjustment:Barely Open                                                                                                                                                                                   |                                   |
| CV-24093   | 8/16/2026 10:28:02 AM | 50.6       | 42.8       | 0.1       | 6.4            |                         |                         | 1.2     | 58.5         | 119.4                | 119.4               | -1.66                        | -1.65                       | 14.8                | 15.7               | 0.507                        | 0.573                       | -19.36                    | -19.59                       | 28.65                  | 1397         | 34.4340472 | -118.6463500 | Well Comment:pump is active;Well Condition:Lorentz Pump Installed                                                                                                                                              |                                   |
| CV-24094   | 8/9/2026 1:42:38 PM   | 14.1       | 53.0       | 6.0       | 27.1           |                         |                         | 0.3     | 4.5          | 109.4                | 109.4               | -3.54                        | -3.57                       | 1.6                 | 1.6                | 0.283                        | 0.288                       | -13.70                    | -13.64                       | 28.48                  | 1366         | 34.4345588 | -118.6461175 | Valve Adjustment:NSPS/EG CAI,High O2,Barely Open;Well Comment:disconnected pump causing air intrusion through old union                                                                                        |                                   |
| CV-24094   | 8/9/2026 1:48:35 PM   | 19.3       | 68.0       | 0.2       | 12.6           |                         |                         | 0.3     | 57.1         | 109.4                | 110.3               | 1.96                         | -0.29                       | 0.4                 | 1.6                | 0.019                        | 0.289                       | -13.72                    | -13.82                       | 28.49                  | 1372         | 34.4345673 | -118.6461013 | Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Orifice Plate Changed (See OP Log),Positive Static Press.,Increased Flow/Vacuum                                                                                       |                                   |
| CV-24094   | 8/9/2026 1:52:37 PM   | 19.3       | 67.0       | 0.7       | 13.0           |                         |                         | 0.3     | 17.8         | 110.2                | 110.0               | -1.74                        | -0.33                       | 1.0                 | 0.9                | 0.020                        | 0.016                       | -13.82                    | -13.63                       | 28.49                  | 1366         | 34.4345722 | -118.6461023 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                                                                                         |                                   |
| CV-24094   | 8/9/2026 1:53:11 PM   | 19.0       | 67.1       | 1.3       | 12.7           |                         |                         | 0.3     | 10.1         | 110.3                | 110.4               | -0.76                        | -0.76                       | 0.7                 | 0.8                | 0.011                        | 0.014                       | -13.57                    | -13.68                       | 28.5                   | 1370         | 34.4345652 | -118.6460873 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open                                                                                                                                                             |                                   |
| CV-24094   | 8/24/2026 2:03:52 PM  | 7.4        | 64.0       | 4.9       | 23.7           |                         |                         | 0.1     | 4.8          | 109.1                | 109.4               | -5.06                        | -3.06                       | 0.6                 | 0.6                | 0.043                        | 0.033                       | -14.42                    | -14.33                       | 28.52                  | 1379         | 34.4345902 | -118.6460887 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open                                                                                                                                                             |                                   |
| CV-24095   | 8/4/2026 8:05:00 AM   |            |            |           |                |                         | 110000                  |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                                                                | AirTech Lab; [User entered 11%]   |
| CV-24095   | 8/4/2026 8:05:00 AM   |            |            |           |                | 1400                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                                                                | AirTech Lab                       |
| CV-24095   | 8/6/2026 7:45:00 AM   |            |            |           |                |                         | 126900                  |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                                                                | AtmAA; [User entered 12.69%]      |
| CV-24095   | 8/6/2026 7:45:00 AM   |            |            |           |                | 2390                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                                                                | AtmAA                             |
| CV-24095   | 8/6/2026 9:31:02 AM   | 6.7        | 70.4       | 0.0       | 22.9           |                         |                         | 0.1     | 0.0          | 188.2                | 188.3               | -6.51                        | -6.40                       |                     |                    | 7.134                        | 7.084                       | -9.22                     | -9.01                        | 28.72                  | 1266         | 34.4334192 | -118.6513042 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                                                                           |                                   |
| CV-24095   | 8/13/2026 8:03:42 AM  | 8.8        | 75.7       | 0.0       | 15.5           |                         |                         | 0.1     | 0.0          | 188.5                | 188.6               | -3.66                        | -3.51                       |                     |                    | 3.676                        | 3.495                       | -7.39                     | -6.78                        | 28.64                  | 1267         | 34.4333928 | -118.6513000 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                                                                           |                                   |
| CV-24095   | 8/13/2026 8:15:00 AM  |            |            |           |                | 3850                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                                                                | AtmAA                             |
| CV-24095   | 8/20/2026 10:28:48 AM | 35.7       | 64.3       | 0.0       | 0.0            |                         |                         | 0.6     | 0.0          | 189.9                | 189.9               | -0.55                        | -0.58                       |                     |                    | 0.465                        | 0.560                       | -3.58                     | -3.85                        | 28.71                  | 1264         | 34.4334016 | -118.6513018 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                                                                           |                                   |
| CV-24095   | 8/25/2026 10:34:52 AM | 28.2       | 66.4       | 0.0       | 5.4            |                         |                         | 0.4     | 0.0          | 190.5                | 190.4               | 2.09                         | 1.76                        |                     |                    | 0.000                        | 0.000                       | 2.62                      | 0.86                         | 28.72                  | 1256         | 34.4333942 | -118.6512943 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                                                                           |                                   |
| CV-24096   | 8/14/2026 8:14:02 AM  | 1.4        | 6.0        | 19.0      | 73.6           |                         |                         | 0.2     | 3.9          | 71.0                 | 71.0                | -5.58                        | -1.31                       |                     |                    | 5.641                        | 1.292                       | -5.46                     | -4.93                        | 28.77                  | 1261         | 34.4332467 | -118.6515902 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:Lorentz not pumping at time of read;Well Condition:Lorentz Pump Installed |                                   |
| CV-24096   | 8/14/2026 8:15:43 AM  | 1.3        | 3.1        | 19.5      | 76.1           |                         |                         | 0.4     | 3.9          | 71.1                 | 71.1                | -1.49                        | -1.50                       |                     |                    | 1.474                        | 1.478                       | -4.95                     | -4.99                        | 28.78                  | 1249         | 34.4332312 | -118.6515967 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected                                                                                            |                                   |
| CV-24096   | 8/31/2026 9:05:44 AM  | 33.8       | 57.7       | 1.4       | 7.1            |                         |                         | 0.6     | 5.1          | 83.8                 | 83.8                | -2.02                        | -1.64                       |                     |                    | 1.991                        | 1.580                       | -1.81                     | -1.45                        | 28.65                  | 1252         | 34.4332077 | -118.6515928 | Valve Adjustment:Surging Liquid in Header                                                                                                                                                                      |                                   |
| CV-24097   | 8/14/2026 8:06:13 AM  | 51.8       | 42.8       | 0.1       | 5.3            |                         |                         | 1.2     | 53.0         | 92.3                 | 93.1                | -6.51                        | -6.26                       |                     |                    | 6.481                        | 6.218                       | -6.59                     | -6.18                        | 28.78                  | 1264         | 34.4328235 | -118.6515568 | Valve Adjustment:Surging Liquid in Header                                                                                                                                                                      |                                   |
| CV-24097   | 8/25/2026 2:12:37 PM  | 48.6       | 45.9       | 0.8       | 4.7            |                         |                         | 1.1     | 5.9          | 117.6                | 118.0               | -2.88                        | -2.85                       |                     |                    | 2.821                        | 2.783                       | -2.40                     | -2.51                        | 28.64                  | 1257         | 34.4328187 | -118.6515727 | Valve Adjustment:Barely Open                                                                                                                                                                                   |                                   |
| CV-24098   | 8/5/2026 8:50:46 AM   | 42.8       | 55.0       | 0.2       | 2.0            |                         |                         | 0.8     | 10.0         | 97.3                 | 98.5                | -12.68                       | -10.25                      | 0.0                 | 0.0                |                              |                             | -10.27                    |                              | 28.64                  | 1299         | 34.4325482 | -118.6513333 | NSPS/EG CAC,                                                                                                                                                                                                   |                                   |
| CV-24098   | 8/25/2026 2:09:42 PM  | 36.8       | 63.0       | 0.2       | 0.0            |                         |                         | 0.6     | 0.0          | 111.4                | 113.4               | -4.92                        | -5.07                       |                     |                    | 4.845                        | 5.259                       | -5.24                     | -5.54                        | 28.62                  | 1249         | 34.4325155 | -118.6513165 | Valve Comment:Valve stuck open                                                                                                                                                                                 |                                   |
| CV-24099   | 8/5/2026 9:03:48 AM   | 9.5        | 18.6       | 14.0      | 57.9           |                         |                         | 0.5     | 4.1          | 81.9                 | 82.0                | -3.86                        | -1.27                       | 0.0                 | 0.0                | 3.561                        | 1.315                       | -15.58                    |                              | 28.63                  | 1207         | 34.4322903 | -118.6508997 | NSPS/EG CAI,High O2                                                                                                                                                                                            |                                   |
| CV-24099   | 8/5/2026 9:07:26 AM   | 10.2       | 19.7       | 13.6      | 56.5           |                         |                         | 0.5     | 4.2          | 81.3                 | 81.4                | -1.37                        | -0.16                       | 0.0                 | 0.0                | 0.379                        | 0.084                       | -15.14                    |                              | 28.63                  | 1280         | 34.4323515 | -118.6509368 | NSPS/EG CAI,High O2                                                                                                                                                                                            |                                   |
| CV-24099   | 8/25/2026 2:05:42 PM  | 22.1       | 73.4       | 0.5       | 4.0            |                         |                         | 0.3     | 8.0          | 113.7                | 113.6               | -0.18                        | -0.17                       |                     |                    | 0.171                        | 0.158                       | -5.43                     | -5.49                        | 28.64                  | 1250         | 34.4323467 | -118.6509382 | Valve Adjustment:Barely Open                                                                                                                                                                                   |                                   |
| CV-24100   | 8/5/2026 7:20:00 AM   |            |            |           |                |                         | 6600                    |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                                                                | AirTech Lab; [User entered 0.66%] |
| CV-24100   | 8/5/2026 7:20:00 AM   |            |            |           |                | 40                      |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                                                                | AirTech Lab                       |
| CV-24100   | 8/5/2026 9:22:38 AM   | 22.8       | 77.0       | 0.1       | 0.1            |                         |                         | 0.3     | 1.0          | 155.0                | 155.3               | -4.68                        | -1.72                       | 0.0                 | 0.0                | 4.634                        | 1.719                       | -16.49                    |                              | 28.63                  | 1240         | 34.4320853 | -118.6505212 | NSPS/EG CAI,High Temp                                                                                                                                                                                          |                                   |
| CV-24100   | 8/5/2026 9:25:30 AM   | 18.9       | 81.1       | 0.0       | 0.0            |                         |                         | 0.2     | 0.0          | 154.6                | 154.2               | -1.89                        | -1.47                       | 0.0                 | 0.0                | 1.526                        | 1.450                       | -16.07                    |                              | 28.63                  | 1240         | 34.4320593 | -118.6505402 | NSPS/EG CAI,High Temp                                                                                                                                                                                          |                                   |
| CV-24100   | 8/6/2026 7:30:00 AM   |            |            |           |                |                         | 4200                    |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                                                                | AtmAA; [User entered 0.42%]       |
| CV-24100   | 8/6/2026 7:30:00 AM   |            |            |           |                | 46.1                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                                                                | AtmAA                             |
| CV-24100   | 8/6/2026 7:40:22 AM   | 22.1       | 77.9       | 0.0       | 0.0            |                         |                         | 0.3     | 0.0          | 153.9                | 154.2               | -4.53                        | -4.54                       |                     |                    | 4.524                        | 4.536                       | -18.50                    | -18.62                       | 28.7                   | 1266         | 34.4320503 | -118.6505028 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                                                                           |                                   |
| CV-24100   | 8/13/2026 8:35:00 AM  |            |            |           |                | 195                     |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                                                                | AtmAA                             |
| CV-24100   | 8/13/2026 8:51:07 AM  | 31.4       | 68.6       | 0.0       | 0.0            |                         |                         | 0.5     | 0.0          | 155.2                | 154.5               | 0.12                         | -3.17                       |                     |                    | 0.000                        | 3.170                       | -15.17                    | -11.63                       | 28.66                  | 1280         | 34.4320575 | -118.6504821 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                                                                           |                                   |
| CV-24100   | 8/13/2026 8:53:27 AM  | 33.0       | 67.0       | 0.0       | 0.0            |                         |                         | 0.5     | 0.0          | 154.4                | 155.2               | -3.22                        | -3.21                       |                     |                    | 3.222                        | 3.213                       | -11.64                    | -11.66                       | 28.68                  | 1279         | 34.4320504 | -118.6504803 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                                                                           |                                   |
| CV-24100   | 8/20/2026 12:49:12 PM | 45.8       | 54.1       | 0.0       | 0.1            |                         |                         | 0.8     | 0.0          | 155.5                | 155.2               | -3.69                        | -3.68                       |                     |                    | 3.696                        | 3.691                       | -0.05                     | -0.04                        | 28.68                  | 1273         | 34.4320568 | -118.6504910 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                                                                           |                                   |
| CV-24101   | 8/4/2026 8:15:00 AM   |            |            |           |                |                         | 1700                    |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                                                                | AirTech Lab; [User entered 0.17%] |
| CV-24101   | 8/4/2026 8:15:00 AM   |            |            |           |                | 0                       |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                                                                | AirTech Lab                       |
| CV-24101   | 8/5/2026 9:32:33 AM   | 41.9       | 54.1       | 0.9       | 3.1            |                         |                         | 0.8     | 3.4          | 118.2                | 119.0               | -16.65                       | -15.37                      | 0.0                 | 0.0                |                              |                             | -16.47                    |                              | 28.63                  | 1260         | 34.4318408 | -118.6502900 | ,                                                                                                                                                                                                              |                                   |
| CV-24101   | 8/25/2026 1:55:01 PM  | 31.9       | 42.7       | 4.8       | 20.6           |                         |                         | 0.7     | 4.3          | 116.7                | 110.3               | -7.43                        | -7.16                       |                     |                    | 7.602                        | 7.334                       | -7.49                     | -7.47                        | 28.64                  | 1273         | 34.4318477 | -118.6502988 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                                                                                         |                                   |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init<br>Flow<br>[scfm] | Adj<br>Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                                                                                                 |                              |
|------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|------------------------|-----------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------|
| CV-24102   | 8/3/2026 9:30:09 AM   | 3.0        | 2.5        | 16.9      | 77.6           |                         |                         | 1.2     | 4.6          | 103.6                | 104.4               | 0.61                         | -0.56                       |                        |                       | 0.000                        | 0.558                       | -15.29                    | -15.34                       | 28.53                  | 1271         | 34.4316150 | -118.6497802 | Valve Comment:valve closed upon arrival;Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High O2,Positive Static Press.,Increased Flow/Vacuum;Well Comment:pump is active;Well Condition:Pnumatic Pump Installed |                              |
| CV-24102   | 8/3/2026 9:33:08 AM   | 48.3       | 47.2       | 0.0       | 4.5            |                         |                         | 1.0     | 0.0          | 106.1                | 106.9               | -0.99                        | -0.89                       |                        |                       | 0.991                        | 0.891                       | -15.37                    | -15.38                       | 28.52                  | 1280         | 34.4316230 | -118.6497887 | Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum;Well Condition:Pnumatic Pump Installed                                                                                                                |                              |
| CV-24102   | 8/3/2026 9:36:16 AM   | 47.2       | 48.2       | 0.0       | 4.6            |                         |                         | 1.0     | 0.0          | 107.2                | 107.8               | -0.86                        | -0.86                       |                        |                       | 0.865                        | 0.861                       | -15.44                    | -15.40                       | 28.53                  | 1270         | 34.4316248 | -118.6497757 | Well Condition:Pnumatic Pump Installed                                                                                                                                                                   |                              |
| CV-24102   | 8/17/2026 9:28:29 AM  | 47.5       | 46.7       | 0.3       | 5.5            |                         |                         | 1.0     | 19.0         | 99.3                 | 99.2                | 0.94                         | -0.65                       |                        |                       | 0.000                        | 0.658                       | -14.80                    | -12.68                       | 28.72                  | 1277         | 34.4316318 | -118.6497767 | Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum;Well Condition:Pnumatic Pump Installed                                                                             |                              |
| CV-24102   | 8/17/2026 9:29:26 AM  | 48.1       | 47.0       | 0.0       | 4.9            |                         |                         | 1.0     | 0.0          | 99.7                 | 99.8                | -0.93                        | -0.92                       |                        |                       | 0.933                        | 0.925                       | -17.45                    | -13.99                       | 28.72                  | 1273         | 34.4316262 | -118.6497673 |                                                                                                                                                                                                          |                              |
| CV-24103   | 8/11/2026 9:42:33 AM  | 1.2        | 0.1        | 20.2      | 78.5           |                         |                         | 19.5    | 3.9          | 95.6                 | 96.0                | -0.92                        | -0.92                       | 1.5                    | 1.5                   | 0.044                        | 0.045                       | -14.87                    | -14.47                       | 28.67                  | 1325         | 34.4316235 | -118.6488295 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open;Well Comment:Well needs to be replaced;Well Condition:Poor                                                                        |                              |
| CV-24103   | 8/11/2026 9:47:02 AM  | 13.3       | 8.4        | 15.5      | 62.7           |                         |                         | 1.6     | 4.1          | 93.4                 | 93.1                | -1.00                        | -1.00                       | 1.2                    | 1.3                   | 0.031                        | 0.032                       | -14.87                    | -14.77                       | 28.65                  | 1328         | 34.4316242 | -118.6488262 |                                                                                                                                                                                                          |                              |
| CV-24103   | 8/18/2026 7:52:44 AM  | 42.9       | 42.8       | 0.0       | 14.3           |                         |                         | 1.0     | 0.0          | 91.7                 | 91.5                | -1.04                        | -1.01                       | 6.0                    | 5.3                   | 0.737                        | 0.556                       | -15.27                    | -14.30                       | 28.61                  | 1316         | 34.4316550 | -118.6488332 | Valve Adjustment:Decreased Flow/Vacuum;Well Repairs:Flex Hose,Valve                                                                                                                                      |                              |
| CV-24103   | 8/18/2026 7:53:40 AM  | 42.9       | 42.7       | 0.0       | 14.5           |                         |                         | 1.0     | 0.0          | 91.3                 | 91.4                | -1.01                        | -1.01                       | 5.0                    | 5.2                   | 0.514                        | 0.546                       | -14.42                    | -14.69                       | 28.62                  | 1313         | 34.4316450 | -118.6488405 |                                                                                                                                                                                                          |                              |
| CV-24104   | 8/5/2026 10:09:23 AM  | 38.6       | 50.5       | 0.0       | 10.9           |                         |                         | 0.8     | 0.0          | 100.1                | 100.1               | -0.88                        | -0.85                       | 2.9                    | 0.5                   | 0.948                        | 0.033                       | -15.07                    |                              | 28.56                  | 1329         | 34.4319063 | -118.6480483 |                                                                                                                                                                                                          |                              |
| CV-24104   | 8/18/2026 8:35:29 AM  | 38.9       | 54.2       | 0.0       | 6.9            |                         |                         | 0.7     | 0.0          | 99.8                 | 100.1               | -0.66                        | -0.86                       | 1.8                    | 2.7                   | 0.340                        | 0.759                       | -14.20                    | -13.90                       | 28.61                  | 1343         | 34.4318872 | -118.6480953 | Valve Adjustment:Increased Flow/Vacuum,Barely Open                                                                                                                                                       |                              |
| CV-24104   | 8/18/2026 8:36:12 AM  | 38.4       | 55.1       | 0.0       | 6.5            |                         |                         | 0.7     | 0.0          | 100.5                | 100.6               | -1.08                        | -1.06                       | 2.2                    | 2.4                   | 0.500                        | 0.627                       | -12.37                    | -14.44                       | 28.61                  | 1340         | 34.4318848 | -118.6480892 |                                                                                                                                                                                                          |                              |
| CV-24105   | 8/3/2026 10:27:40 AM  | 41.5       | 39.5       | 1.3       | 17.7           |                         |                         | 1.1     | 13.8         | 120.4                | 120.4               | -0.83                        | -0.82                       | 15.8                   | 15.9                  | 1.612                        | 1.632                       | -15.20                    | -15.23                       | 28.46                  | 1352         | 34.4319063 | -118.6476575 |                                                                                                                                                                                                          |                              |
| CV-24105   | 8/17/2026 1:40:57 PM  | 43.9       | 38.9       | 0.8       | 16.4           |                         |                         | 1.1     | 20.5         | 120.4                | 120.5               | -0.59                        | -0.58                       | 15.0                   | 13.7                  | 1.431                        | 1.205                       | -13.04                    | -12.83                       | 28.64                  | 1341         | 34.4319185 | -118.6476973 |                                                                                                                                                                                                          |                              |
| CV-24106   | 8/5/2026 9:41:57 AM   | 49.5       | 43.9       | 0.4       | 6.2            |                         |                         | 1.1     | 15.5         | 93.5                 | 97.4                | -0.18                        | -0.22                       | 0.0                    | 9.0                   | -0.076                       | 0.206                       | -20.13                    |                              | 28.56                  | 1322         | 34.4321330 | -118.6467530 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less                                                                                                                                                      |                              |
| CV-24106   | 8/26/2026 12:44:40 PM | 43.5       | 39.4       | 0.1       | 17.0           |                         |                         | 1.1     | 170.0        | 130.6                | 130.4               | -0.89                        | -0.88                       | 7.2                    | 7.1                   | 0.144                        | 0.140                       | -15.40                    | -15.55                       | 28.52                  | 1353         | 34.4321390 | -118.6467322 | Valve Adjustment:Barely Open                                                                                                                                                                             |                              |
| CV-24107   | 8/18/2026 9:24:43 AM  | 37.3       | 44.3       | 0.4       | 18.0           |                         |                         | 0.8     | 45.0         | 131.7                | 129.2               | -6.41                        | -4.84                       |                        |                       | 6.684                        | 4.837                       | -7.36                     | -8.31                        | 28.62                  | 1330         | 34.4325642 | -118.6461600 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum                                                                                                                                             |                              |
| CV-24107   | 8/18/2026 9:25:31 AM  | 37.2       | 45.2       | 0.3       | 17.3           |                         |                         | 0.8     | 57.7         | 129.5                | 129.5               | -4.47                        | -4.52                       |                        |                       | 4.471                        | 4.511                       | -8.37                     | -8.86                        | 28.62                  | 1328         | 34.4325592 | -118.6461695 | Valve Adjustment:NSPS/EG CAC                                                                                                                                                                             |                              |
| CV-24108   | 8/18/2026 9:01:25 AM  | 46.0       | 44.6       | 0.0       | 9.4            |                         |                         | 1.0     | 0.0          | 131.0                | 132.3               | 0.22                         | -0.11                       | 6.0                    | 5.2                   | 0.023                        | 0.017                       | -20.42                    | -20.32                       | 28.6                   | 1359         | 34.4331608 | -118.6454557 | Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum                                                                                                                      |                              |
| CV-24108   | 8/18/2026 9:02:12 AM  | 47.3       | 46.2       | 0.0       | 6.5            |                         |                         | 1.0     | 0.0          | 132.2                | 132.2               | -0.18                        | -0.18                       | 2.2                    | 3.2                   | 0.003                        | 0.007                       | -20.23                    | -20.25                       | 28.59                  | 1357         | 34.4331612 | -118.6454368 | Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open                                                                                                                                                       |                              |
| CV-24108   | 8/18/2026 9:02:34 AM  | 47.4       | 45.8       | 0.0       | 6.8            |                         |                         | 1.0     | 0.0          | 132.4                | 132.3               | -0.13                        | -0.13                       | 1.7                    | 1.9                   | 0.002                        | 0.002                       | -20.39                    | -20.39                       | 28.6                   | 1348         | 34.4331632 | -118.6454328 | Valve Adjustment:NSPS/EG CAI,High Temp                                                                                                                                                                   |                              |
| CV-24109   | 8/1/2026 9:24:53 AM   | 27.9       | 40.6       | 0.0       | 31.5           |                         |                         | 0.7     | 0.0          | 114.7                | 115.5               | -5.77                        | -4.73                       |                        |                       | 6.153                        | 5.035                       | -18.62                    | -18.89                       | 28.55                  | 1377         | 34.4340035 | -118.6448848 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                                                                                   |                              |
| CV-24110   | 8/24/2026 2:10:13 PM  | 34.0       | 65.2       | 0.0       | 0.8            |                         |                         | 0.5     | 0.0          | 132.2                | 132.2               | -0.90                        | -0.89                       | 35.6                   | 37.4                  | 0.827                        | 0.915                       | -19.12                    | -18.61                       | 28.5                   | 1366         | 34.4346340 | -118.6447133 | Valve Adjustment:High Temp,Barely Open;Well Condition:Lorentz Pump Installed                                                                                                                             |                              |
| CV-24111   | 8/11/2026 2:00:09 PM  | 45.3       | 45.7       | 0.0       | 9.0            |                         |                         | 1.0     | 0.0          | 125.6                | 125.8               | -10.10                       | -9.50                       |                        |                       | 9.932                        | 9.558                       | -14.26                    | -14.58                       | 28.61                  | 1397         | 34.4353367 | -118.6449488 | Valve Adjustment:Audible Flow,Decreased Flow/Vacuum                                                                                                                                                      |                              |
| CV-24112   | 8/11/2026 1:24:48 PM  | 51.3       | 37.2       | 0.0       | 11.5           |                         |                         | 1.4     | 0.0          | 129.8                | 129.3               | -2.47                        | -2.41                       | 19.2                   | 19.0                  | 0.868                        | 0.846                       | -17.30                    | -17.20                       | 28.62                  | 1390         | 34.4352183 | -118.6441567 | Valve Adjustment:Audible Flow,Decreased Flow/Vacuum                                                                                                                                                      |                              |
| CV-24114   | 8/12/2026 9:57:12 AM  | 54.2       | 41.8       | 0.0       | 4.1            |                         |                         | 1.3     | 0.0          | 122.3                | 122.4               | -17.46                       | -17.46                      | 13.9                   | 14.5                  | 0.547                        | 0.597                       | -17.97                    | -17.91                       | 28.65                  | 1297         | 34.4307735 | -118.6485395 | Valve Adjustment:Plugged/Pinched Suspected                                                                                                                                                               |                              |
| CV-24114   | 8/12/2026 10:00:35 AM | 54.2       | 41.8       | 0.0       | 4.1            |                         |                         | 1.3     | 0.0          |                      | 122.2               | -19.14                       | -19.14                      | 14.7                   | 14.8                  | 0.130                        | 0.148                       | -19.09                    | -19.09                       | 28.65                  | 1291         | 34.4308028 | -118.6485293 | Valve Adjustment:Orifice Plate Changed (See OP Log)                                                                                                                                                      |                              |
| CV-24116   | 8/13/2026 2:14:02 PM  | 49.8       | 46.6       | 0.2       | 3.4            |                         |                         | 1.1     | 17.0         | 124.3                | 124.9               | -2.07                        | -2.06                       |                        |                       | 2.038                        | 2.045                       | -16.39                    | -16.06                       | 28.64                  | 1249         | 34.4316575 | -118.6457355 | Valve Adjustment:Barely Open                                                                                                                                                                             |                              |
| CV-24116   | 8/18/2026 10:48:30 AM | 48.1       | 41.8       | 0.3       | 9.8            |                         |                         | 1.2     | 32.7         | 125.4                | 125.5               | -3.30                        | -2.84                       |                        |                       | 3.293                        | 2.836                       | -16.74                    | -16.57                       | 28.73                  | 1241         | 34.4316553 | -118.6457382 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                                                                                   |                              |
| CV-24117   | 8/18/2026 10:02:38 AM | 20.1       | 29.2       | 0.0       | 50.7           |                         |                         | 0.7     | 0.0          | 124.2                | 124.3               | -2.41                        | -1.94                       |                        |                       | 2.400                        | 1.908                       | -20.03                    | -20.00                       | 28.68                  | 1275         | 34.4323318 | -118.6449655 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                                                                                   |                              |
| CV-24118   | 8/6/2026 2:00:00 PM   |            |            |           |                |                         | 112400                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                                                          | AtmAA; [User entered 11.24%] |
| CV-24118   | 8/6/2026 2:00:00 PM   |            |            |           |                | 2390                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                                                          | AtmAA                        |
| CV-24118   | 8/6/2026 2:15:53 PM   | 20.9       | 75.8       | 0.0       | 3.3            |                         |                         | 0.3     | 0.0          | 150.7                | 150.6               | -0.55                        | -0.53                       |                        |                       | 0.480                        | 0.472                       | -15.44                    | -15.81                       | 28.61                  | 1303         | 34.4330668 | -118.6438485 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                                                                     |                              |
| CV-24118   | 8/13/2026 1:16:05 PM  | 39.1       | 60.9       | 0.0       | 0.0            |                         |                         | 0.6     | 0.0          | 149.5                | 149.4               | -0.90                        | -0.89                       |                        |                       | 0.849                        | 0.828                       | -17.13                    | -17.08                       | 28.59                  | 1277         | 34.4333016 | -118.6438649 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                                                                     |                              |
| CV-24118   | 8/13/2026 1:20:00 PM  |            |            |           |                | 2560                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                                                          | AtmAA                        |
| CV-24118   | 8/20/2026 7:24:50 AM  | 11.2       | 77.0       | 0.0       | 11.8           |                         |                         | 0.1     | 0.0          | 149.8                | 150.0               | -1.16                        | -1.14                       |                        |                       | 1.161                        | 1.163                       | -18.86                    | -19.14                       | 28.64                  | 1337         | 34.4333174 | -118.6438892 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                                                                                                                                         |                              |
| CV-24118   | 8/20/2026 2:29:12 PM  | 11.2       | 81.2       | 0.0       | 7.6            |                         |                         | 0.1     | 0.0          | 151.1                | 150.9               | -0.48                        | -0.38                       |                        |                       | 0.388                        | 0.331                       | -14.62                    | -14.72                       | 28.6                   | 1288         | 34.4332803 | -118.6438443 | Valve Adjustment:High Temp,Barely Open                                                                                                                                                                   |                              |
| CV-24119   | 8/25/2026 8:36:13 AM  | 44.4       | 45.5       | 0.0       | 10.1           |                         |                         | 1.0     | 0.0          | 143.0                | 140.2               | -2.55                        | -1.40                       |                        |                       | 2.564                        | 1.407                       | -17.56                    | -17.78                       | 28.68                  | 1269         | 34.4337468 | -118.6423070 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed                                                                                                       |                              |
| CV-24119   | 8/25/2026 8:37:18 AM  | 44.0       | 45.5       | 0.0       | 10.5           |                         |                         | 1.0     | 0.0          | 139.4                | 139.1               | -1.23                        | -1.22                       |                        |                       | 1.231                        | 1.223                       | -17.83                    | -18.10                       | 28.68                  | 1263         | 34.4337433 | -118.6423060 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                                                                                                                                         |                              |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name  | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init<br>Flow<br>[scfm] | Adj<br>Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                                                                 |                                   |
|-------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|------------------------|-----------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------|
| CV-24120    | 8/13/2026 12:29:20 PM | 8.2        | 26.4       | 13.6      | 51.8           |                         |                         | 0.3     | 3.8          | 95.5                 | 96.2                | -5.86                        | -5.98                       |                        |                       | 5.877                        | 5.990                       | -5.77                     | -6.31                        | 28.63                  | 1344         | 34.4368390 | -118.6472975 | Valve Adjustment: NSPS/EG CAI, High O2, Decreased Flow/Vacuum, Barely Open; Well Condition: Lorentz Pump Installed                                                       |                                   |
| CV-24120    | 8/13/2026 12:31:03 PM | 8.2        | 28.5       | 13.2      | 50.1           |                         |                         | 0.3     | 3.8          | 93.8                 | 93.4                | -5.24                        | -4.86                       |                        |                       | 5.282                        | 4.783                       | -5.25                     | -4.79                        | 28.63                  | 1346         | 34.4368300 | -118.6472787 |                                                                                                                                                                          |                                   |
| CV-24120    | 8/14/2026 8:00:00 AM  |            |            |           |                |                         | 35000                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                          | AirTech Lab; [User entered 3.5%]  |
| CV-24120    | 8/14/2026 8:00:00 AM  |            |            |           |                | 440                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                          | AirTech Lab                       |
| CV-24120    | 8/18/2026 9:13:19 AM  | 3.6        | 38.0       | 12.6      | 45.9           |                         |                         | 0.1     | 3.6          | 88.9                 | 89.0                | -6.43                        | -6.42                       |                        |                       | 6.759                        | 6.700                       | -7.21                     | -7.69                        | 28.64                  | 1326         | 34.4368647 | -118.6472855 | Valve Adjustment: NSPS/EG CAI, High O2; Well Condition: Lorentz Pump Installed                                                                                           |                                   |
| CV-24120    | 8/18/2026 9:13:57 AM  | 3.5        | 36.9       | 12.5      | 47.2           |                         |                         | 0.1     | 3.8          | 89.0                 | 88.9                | -6.42                        | -6.42                       |                        |                       | 6.673                        | 6.718                       | -5.38                     | -6.39                        | 28.64                  | 1331         | 34.4368705 | -118.6472867 | Valve Adjustment: High O2                                                                                                                                                |                                   |
| CV-24120    | 8/24/2026 9:14:22 AM  | 10.5       | 73.1       | 0.0       | 16.4           |                         |                         | 0.1     | 0.0          | 122.4                | 129.7               | 58.71                        | -2.97                       |                        |                       | 0.000                        | 2.992                       | -7.48                     | -6.91                        | 28.64                  | 1372         | 34.4368382 | -118.6472673 | Valve Adjustment: NSPS/EG CAI, NSPS/EG CAC, Positive Static Press., Increased Flow/Vacuum; Well Comment: Pump is active; Well Condition: Lorentz Pump Installed          |                                   |
| CV-24120    | 8/24/2026 9:17:28 AM  | 12.5       | 73.0       | 0.0       | 14.5           |                         |                         | 0.2     | 0.0          | 130.1                | 130.3               | -3.27                        | -3.27                       |                        |                       | 3.290                        | 3.298                       | -7.00                     | -7.32                        | 28.63                  | 1363         | 34.4368307 | -118.6472658 | Well Comment: pump is active; Well Condition: Lorentz Pump Installed                                                                                                     |                                   |
| CV-24121    | 8/10/2026 8:05:00 AM  |            |            |           |                |                         | 2800                    |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                          | AirTech Lab; [User entered 0.28%] |
| CV-24121    | 8/10/2026 8:05:00 AM  |            |            |           |                | 12                      |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                          | AirTech Lab                       |
| CV-24121    | 8/11/2026 9:37:10 AM  | 1.0        | 3.7        | 19.2      | 76.1           |                         |                         | 0.3     | 4.0          | 93.1                 | 94.1                | -7.05                        | -5.99                       |                        |                       | 7.440                        | 6.257                       | -6.49                     | -7.09                        | 28.63                  | 1331         | 34.4369790 | -118.6470235 | Valve Adjustment: High O2, Decreased Flow/Vacuum, Barely Open, Surging Liquid in Header, Surging Liquid in Well (Watered In)                                             |                                   |
| CV-24121    | 8/18/2026 9:50:10 AM  | 2.3        | 3.6        | 18.6      | 75.5           |                         |                         | 0.6     | 4.0          | 99.5                 | 99.7                | -5.72                        | -5.75                       |                        |                       | 5.852                        | 5.825                       | -6.53                     | -5.37                        | 28.64                  | 1323         | 34.4369740 | -118.6470283 | Valve Adjustment: NSPS/EG CAI, High O2, Barely Open, Surging Liquid in Well (Watered In); Well Comment: no pump                                                          |                                   |
| CV-24121    | 8/18/2026 9:50:57 AM  | 2.4        | 3.8        | 18.6      | 75.2           |                         |                         | 0.6     | 4.0          | 100.0                | 99.9                | -5.80                        | -5.80                       |                        |                       | 5.865                        | 5.865                       | -6.33                     | -6.33                        | 28.64                  | 1328         | 34.4369558 | -118.6470500 | Valve Adjustment: High O2                                                                                                                                                |                                   |
| CV-24122    | 8/10/2026 7:55:00 AM  |            |            |           |                |                         | 0                       |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                          | AirTech Lab; [User entered 0%]    |
| CV-24122    | 8/10/2026 7:55:00 AM  |            |            |           |                | 0                       |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                          | AirTech Lab                       |
| CV-24122    | 8/11/2026 9:26:26 AM  | 21.7       | 24.2       | 10.7      | 43.4           |                         |                         | 0.9     | 4.1          | 95.3                 | 97.8                | -3.73                        | -3.65                       | 2.2                    | 0.9                   | 0.240                        | 0.040                       | -3.39                     | -2.97                        | 28.67                  | 1320         | 34.4371482 | -118.6466003 | Valve Adjustment: NSPS/EG CAI, High O2, Decreased Flow/Vacuum, Barely Open                                                                                               |                                   |
| CV-24122    | 8/11/2026 9:27:22 AM  | 22.0       | 25.7       | 11.1      | 41.2           |                         |                         | 0.9     | 3.7          | 98.3                 | 98.4                | -3.22                        | -3.35                       | 1.6                    | 2.2                   | 0.123                        | 0.250                       | -3.54                     | -4.53                        | 28.64                  | 1325         | 34.4371145 | -118.6466037 | Valve Adjustment: High O2, Surging Liquid in Header, Surging Liquid in Well (Watered In)                                                                                 |                                   |
| CV-24122    | 8/14/2026 8:05:00 AM  |            |            |           |                |                         | 2100                    |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                          | AirTech Lab; [User entered 0.21%] |
| CV-24122    | 8/14/2026 8:05:00 AM  |            |            |           |                | 0                       |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                          | AirTech Lab                       |
| CV-24122    | 8/18/2026 9:56:31 AM  | 33.9       | 36.4       | 5.9       | 23.8           |                         |                         | 0.9     | 4.0          | 105.0                | 105.1               | -2.37                        | -2.43                       | 5.2                    | 5.7                   | 0.579                        | 0.686                       | -2.43                     | -1.43                        | 28.68                  | 1307         | 34.4371790 | -118.6466230 | Valve Adjustment: NSPS/EG CAI, High O2, Surging Liquid in Header                                                                                                         |                                   |
| CV-24122    | 8/18/2026 9:57:24 AM  | 34.7       | 37.5       | 5.7       | 22.1           |                         |                         | 0.9     | 3.9          | 105.8                | 106.0               | -1.56                        | -1.57                       | 3.1                    | 3.1                   | 0.201                        | 0.196                       | -1.41                     | -1.48                        | 28.67                  | 1298         | 34.4371838 | -118.6466230 | Valve Adjustment: High O2, Surging Liquid in Header                                                                                                                      |                                   |
| CV-24123    | 8/5/2026 12:15:03 PM  | 45.8       | 54.2       | 0.0       | 0.0            |                         |                         | 0.8     | 0.0          | 117.3                | 116.8               | -5.60                        | -4.99                       | 0.0                    | 0.0                   | 0.017                        | -0.206                      | -8.32                     |                              | 28.6                   | 1253         | 34.4373460 | -118.6462362 |                                                                                                                                                                          |                                   |
| CV-24124    | 8/14/2026 12:22:27 PM | 8.1        | 81.0       | 0.0       | 10.9           |                         |                         | 0.1     | 0.0          | 134.6                | 134.1               | -1.40                        | -1.28                       |                        |                       | 1.538                        | 1.242                       | -8.02                     | -6.53                        | 28.6                   | 1364         | 34.4366393 | -118.6470202 | Valve Adjustment: NSPS/EG CAI, High Temp, Decreased Flow/Vacuum, Barely Open, Surging Liquid in Header; Well Condition: Lorentz Pump Installed                           |                                   |
| CV-24124    | 8/14/2026 12:23:40 PM | 9.6        | 80.3       | 0.0       | 10.1           |                         |                         | 0.1     | 0.0          | 134.4                | 134.0               | -1.44                        | -1.38                       |                        |                       | 1.430                        | 1.299                       | -6.57                     | -6.90                        | 28.6                   | 1366         | 34.4366330 | -118.6470288 | Valve Adjustment: High Temp, Barely Open, Surging Liquid in Header, Surging Liquid in Well (Watered In); Well Condition: Lorentz Pump Installed                          |                                   |
| CV-24124    | 8/28/2026 1:21:46 PM  | 6.3        | 75.4       | 0.1       | 18.2           |                         |                         | 0.1     | 182.0        | 134.7                | 134.4               | -0.37                        | -0.22                       |                        |                       | 0.402                        | 0.245                       | -5.54                     | -4.74                        | 28.63                  | 1366         | 34.4366328 | -118.6470248 | Valve Adjustment: High Temp                                                                                                                                              |                                   |
| CV-24125-TF | 8/10/2026 8:10:00 AM  |            |            |           |                |                         | 0                       |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                          | AirTech Lab; [User entered 0%]    |
| CV-24125-TF | 8/10/2026 8:10:00 AM  |            |            |           |                | 0                       |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                          | AirTech Lab                       |
| CV-24125-TF | 8/11/2026 9:18:03 AM  | 30.5       | 66.5       | 0.9       | 2.1            |                         |                         | 0.5     | 2.3          | 133.0                | 130.3               | -10.50                       | -5.50                       |                        |                       | 10.824                       | 5.892                       | -10.82                    | -10.87                       | 28.64                  | 1335         | 34.4369700 | -118.6463262 | Valve Adjustment: NSPS/EG CAI, High Temp, Decreased Flow/Vacuum, Surging Liquid in Header, Surging Liquid in Well (Watered In); Well Condition: Pneumatic Pump Installed |                                   |
| CV-24125-TF | 8/11/2026 9:19:45 AM  | 28.7       | 67.4       | 0.8       | 3.1            |                         |                         | 0.4     | 3.9          | 133.0                | 133.0               | -5.08                        | -5.08                       |                        |                       | 5.553                        | 5.553                       | -10.74                    | -10.69                       | 28.64                  | 1339         | 34.4369602 | -118.6463392 | Valve Adjustment: High Temp, Surging Liquid in Header, Surging Liquid in Well (Watered In)                                                                               |                                   |
| CV-24125-TF | 8/18/2026 9:41:43 AM  | 35.0       | 54.6       | 0.9       | 9.5            |                         |                         | 0.6     | 10.8         | 130.7                | 130.8               | -5.94                        | -5.80                       |                        |                       | 5.915                        | 5.907                       | -8.26                     | -8.23                        | 28.65                  | 1317         | 34.4369670 | -118.6463590 |                                                                                                                                                                          |                                   |
| CV-24125-TF | 8/18/2026 9:42:30 AM  | 34.8       | 54.4       | 0.8       | 10.0           |                         |                         | 0.6     | 12.5         | 130.8                | 130.7               | -6.04                        | -6.04                       |                        |                       | 5.911                        | 5.915                       | -8.35                     | -8.36                        | 28.64                  | 1319         | 34.4369697 | -118.6463660 | Well Condition: Pneumatic Pump Installed                                                                                                                                 |                                   |
| CV-24126    | 8/3/2026 10:21:16 AM  | 3.1        | 74.6       | 0.0       | 22.3           |                         |                         | 0.0     | 0.0          | 191.6                | 191.7               | -0.65                        | -0.61                       |                        |                       | 0.727                        | 0.766                       | 0.42                      | 0.44                         | 28.42                  | 1376         | 34.4363656 | -118.6471422 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                                                                 |                                   |
| CV-24126    | 8/3/2026 10:25:00 AM  |            |            |           |                |                         | 115000                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                          | AtmAA; [User entered 11.5%]       |
| CV-24126    | 8/3/2026 10:25:00 AM  |            |            |           |                | 2120                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                          | AtmAA                             |
| CV-24126    | 8/10/2026 1:15:00 PM  |            |            |           |                | 3880                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                          | AtmAA                             |
| CV-24126    | 8/10/2026 1:26:10 PM  | 17.7       | 77.0       | 0.0       | 5.3            |                         |                         | 0.2     | 0.0          | 192.9                | 192.6               | -0.31                        | -0.17                       |                        |                       | 0.121                        | 0.313                       | -0.08                     | -0.04                        | 28.53                  | 1369         | 34.4363677 | -118.6471275 | Valve Adjustment: No Flow Measurement, High Temp, Valve 100% Open; Well Condition: Lorentz Pump Installed                                                                |                                   |
| CV-24126    | 8/17/2026 9:45:56 AM  | 31.0       | 49.7       | 0.9       | 18.4           |                         |                         | 0.6     | 20.4         | 181.4                | 181.4               | -1.12                        | -1.06                       |                        |                       | 0.947                        | 0.585                       | 0.57                      | 0.48                         | 28.67                  | 1390         | 34.4363929 | -118.6471653 | Valve Adjustment: High Temp                                                                                                                                              |                                   |
| CV-24126    | 8/17/2026 9:50:00 AM  |            |            |           |                | 2420                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                                          | AtmAA                             |
| CV-24126    | 8/24/2026 9:25:50 AM  | 36.6       | 63.4       | 0.0       | 0.0            |                         |                         | 0.6     | 0.0          | 187.3                | 187.5               | -0.87                        | -0.89                       |                        |                       | 0.812                        | 1.026                       | 0.47                      | 0.42                         | 28.6                   | 1376         | 34.4363909 | -118.6471228 | Valve Adjustment: High Temp; Well Condition: Lorentz Pump Installed                                                                                                      |                                   |

**All LFG Extraction Wells - August 2020**  
**Chiquita Canyon Landfill**

| Point Name  | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init<br>Flow<br>[scfm] | Adj<br>Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                                              |                                  |
|-------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|------------------------|-----------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|-------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|
| CV-24126    | 8/31/2026 1:40:04 PM  | 8.9        | 69.9       | 0.0       | 21.2           |                         |                         | 0.1     | 0.0          | 163.5                | 165.7               | 0.55                         | 0.53                        |                        |                       | 0.000                        | 0.000                       | 0.00                      | 0.00                         | 28.53                  | 1375         | 34.4363950 | -118.6471394 | Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open;Well Condition:Lorentz Pump Installed                           |                                  |
| CV-24126    | 8/31/2026 1:40:38 PM  | 8.4        | 76.2       | 0.0       | 15.4           |                         |                         | 0.1     | 0.0          | 169.5                | 168.1               | 0.60                         | 0.58                        |                        |                       | 0.000                        | 0.000                       | 0.01                      | 0.04                         | 28.5                   | 1375         | 34.4363950 | -118.6471394 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                  |                                  |
| CV-24127    | 8/3/2026 12:50:00 PM  |            |            |           |                |                         | 12700                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                       | AtmAA; [User entered 1.27%]      |
| CV-24127    | 8/3/2026 12:50:00 PM  |            |            |           |                | 288                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                       | AtmAA                            |
| CV-24127    | 8/3/2026 12:56:02 PM  | 12.8       | 66.6       | 0.1       | 20.5           |                         |                         | 0.2     | 205.0        | 162.4                | 163.1               | -2.07                        | -2.26                       |                        |                       | 2.144                        | 1.983                       | -3.96                     | -3.37                        | 28.42                  | 1362         | 34.4364864 | -118.6468266 | Valve Adjustment:No Flow Measurement,High Temp                                                                                                        |                                  |
| CV-24127    | 8/6/2026 8:20:00 AM   |            |            |           |                |                         | 99000                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                       | AirTech Lab; [User entered 9.9%] |
| CV-24127    | 8/6/2026 8:20:00 AM   |            |            |           |                | 1500                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                       | AirTech Lab                      |
| CV-24127    | 8/10/2026 1:20:00 PM  |            |            |           |                | 2770                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                       | AtmAA                            |
| CV-24127    | 8/10/2026 1:32:33 PM  | 27.9       | 70.9       | 0.3       | 0.9            |                         |                         | 0.4     | 3.0          | 165.8                | 164.6               | -0.44                        | -0.40                       |                        |                       | 0.389                        | 0.290                       | -2.17                     | -1.52                        | 28.53                  | 1382         | 34.4364289 | -118.6468168 | Valve Adjustment:No Flow Measurement,High Temp                                                                                                        |                                  |
| CV-24127    | 8/17/2026 1:15:00 PM  |            |            |           |                | 4420                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                       | AtmAA                            |
| CV-24127    | 8/17/2026 1:25:00 PM  | 21.8       | 76.1       | 0.0       | 2.1            |                         |                         | 0.3     | 0.0          | 174.4                | 173.8               | 0.16                         | -0.09                       |                        |                       | 0.000                        | 0.194                       | -0.35                     | -0.46                        | 28.59                  | 1361         | 34.4364739 | -118.6468371 | Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Pnumatic Pump Installed                                           |                                  |
| CV-24127    | 8/17/2026 1:27:59 PM  | 16.2       | 73.2       | 0.0       | 10.6           |                         |                         | 0.2     | 0.0          | 174.0                | 174.6               | -0.17                        | -0.15                       |                        |                       | 0.158                        | 0.156                       | -0.54                     | -0.50                        | 28.6                   | 1365         | 34.4364619 | -118.6468274 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed                                                                 |                                  |
| CV-24127    | 8/25/2026 7:19:15 AM  | 11.1       | 77.5       | 0.1       | 11.3           |                         |                         | 0.1     | 113.0        | 174.8                | 174.3               | -0.82                        | -0.73                       |                        |                       | 0.884                        | 0.979                       | -1.43                     | -1.68                        | 28.57                  | 1390         | 34.4364730 | -118.6468272 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed                                                                 |                                  |
| CV-24127    | 8/31/2026 1:36:18 PM  | 16.9       | 74.9       | 0.0       | 8.2            |                         |                         | 0.2     | 0.0          | 176.2                | 177.3               | 0.58                         | 0.60                        |                        |                       | 0.000                        | 0.000                       | 1.05                      | 1.09                         | 28.52                  | 1380         | 34.4364657 | -118.6468446 | Valve Adjustment:High Temp,Positive Static Press.,Valve 100% Open;Well Condition:Pnumatic Pump Installed                                              |                                  |
| CV-24127    | 8/31/2026 1:37:14 PM  | 7.9        | 75.1       | 0.0       | 17.0           |                         |                         | 0.1     | 0.0          | 176.7                | 177.4               | 0.54                         | 0.54                        |                        |                       | 0.000                        | 0.000                       | 0.93                      | 0.93                         | 28.49                  | 1381         | 34.4364661 | -118.6468425 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed                                                                 |                                  |
| CV-24128    | 8/6/2026 8:15:00 AM   |            |            |           |                |                         | 73000                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                       | AirTech Lab; [User entered 7.3%] |
| CV-24128    | 8/6/2026 8:15:00 AM   |            |            |           |                | 1700                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                       | AirTech Lab                      |
| CV-24128    | 8/11/2026 2:38:10 PM  | 19.1       | 68.7       | 0.3       | 11.9           |                         |                         | 0.3     | 39.7         | 125.4                | 125.0               | -0.48                        | -0.48                       |                        |                       | 0.458                        | 0.455                       | -9.44                     | -9.06                        | 28.56                  | 1375         | 34.4366920 | -118.6463865 |                                                                                                                                                       |                                  |
| CV-24128    | 8/18/2026 9:28:34 AM  | 15.3       | 67.5       | 0.0       | 17.2           |                         |                         | 0.2     | 0.0          | 126.2                | 126.2               | -0.38                        | -0.37                       |                        |                       | 0.397                        | 0.386                       | -8.88                     | -9.23                        | 28.61                  | 1352         | 34.4367050 | -118.6464885 | Well Comment:pump is active;Well Condition:Lorentz Pump Installed                                                                                     |                                  |
| CV-24129    | 8/11/2026 2:35:34 PM  | 47.9       | 51.9       | 0.2       | 0.0            |                         |                         | 0.9     | 0.0          | 129.5                | 129.3               | -9.01                        | -8.90                       |                        |                       | 9.037                        | 8.966                       | -9.33                     | -9.15                        | 28.59                  | 1373         | 34.4366728 | -118.6461363 | Valve Adjustment:Barely Open                                                                                                                          |                                  |
| CV-24129    | 8/18/2026 9:33:13 AM  | 43.6       | 50.4       | 0.0       | 6.0            |                         |                         | 0.9     | 0.0          | 131.3                | 131.4               | -8.09                        | -8.06                       |                        |                       | 8.173                        | 8.155                       | -8.47                     | -8.42                        | 28.6                   | 1350         | 34.4367027 | -118.6461638 | Valve Adjustment:NSPS/EG CAC,High Temp;Well Condition:Pnumatic Pump Installed                                                                         |                                  |
| CV-24129    | 8/18/2026 9:36:02 AM  | 44.5       | 51.1       | 0.0       | 4.4            |                         |                         | 0.9     | 0.0          | 131.4                | 130.9               | -8.06                        | -6.80                       |                        |                       | 8.115                        | 6.825                       | -8.45                     | -8.36                        | 28.64                  | 1360         | 34.4367305 | -118.6461582 | Valve Adjustment:NSPS/EG CAC,High Temp,Decreased Flow/Vacuum;Well Condition:Pnumatic Pump Installed                                                   |                                  |
| CV-24129    | 8/18/2026 9:36:46 AM  | 44.6       | 50.9       | 0.0       | 4.5            |                         |                         | 0.9     | 0.0          | 130.9                | 130.9               | -6.69                        | -6.57                       |                        |                       | 6.668                        | 6.637                       | -8.44                     | -8.31                        | 28.62                  | 1341         | 34.4367118 | -118.6461862 | Well Condition:Pnumatic Pump Installed                                                                                                                |                                  |
| CV-24130    | 8/11/2026 9:07:15 AM  | 22.3       | 68.2       | 0.1       | 9.4            |                         |                         | 0.3     | 94.0         | 121.4                | 120.9               | -5.04                        | -5.06                       |                        |                       | 5.239                        | 5.332                       | -5.07                     | -5.12                        | 28.63                  | 1337         | 34.4367957 | -118.6457028 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)                                                                         |                                  |
| CV-24131    | 8/26/2026 9:32:29 AM  | 43.4       | 53.3       | 0.0       | 3.3            |                         |                         | 0.8     | 0.0          | 127.2                | 127.0               | -0.91                        | -0.92                       | 11.9                   | 12.1                  | 0.391                        | 0.405                       | -12.72                    | -12.38                       | 28.56                  | 1346         | 34.4367190 | -118.6450783 | Valve Adjustment:Barely Open                                                                                                                          |                                  |
| CV-24132    | 8/24/2026 1:35:03 PM  | 50.3       | 43.0       | 0.0       | 6.8            |                         |                         | 1.2     | 675.0        | 130.9                | 130.9               | -8.06                        | -8.06                       | 7.7                    | 15.5                  | 0.016                        | 0.065                       | -11.45                    | -11.07                       | 28.68                  | 1269         | 34.4372365 | -118.6440452 |                                                                                                                                                       |                                  |
| CV-24133    | 8/25/2026 1:17:08 PM  | 50.6       | 33.5       | 0.0       | 15.9           |                         |                         | 1.5     | 0.0          | 125.2                | 125.2               | -6.23                        | -6.23                       | 19.6                   | 20.0                  | 1.065                        | 1.109                       | -10.27                    | -10.36                       | 28.67                  | 1279         | 34.4374116 | -118.6427000 |                                                                                                                                                       |                                  |
| CV-24134-TF | 8/3/2026 12:45:00 AM  |            |            |           |                |                         | 81700                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                       | AtmAA; [User entered 8.17%]      |
| CV-24134-TF | 8/3/2026 12:45:00 PM  |            |            |           |                | 1790                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                       | AtmAA                            |
| CV-24134-TF | 8/3/2026 12:47:19 PM  | 13.5       | 70.7       | 0.0       | 15.8           |                         |                         | 0.2     | 0.0          | 152.6                | 153.2               | -2.31                        | -2.31                       |                        |                       | 2.322                        | 2.323                       | -3.03                     | -3.03                        | 28.42                  | 1356         | 34.4363844 | -118.6464996 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                  |                                  |
| CV-24134-TF | 8/10/2026 1:30:00 PM  |            |            |           |                | 2940                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                       | AtmAA                            |
| CV-24134-TF | 8/10/2026 1:36:07 PM  | 32.6       | 67.4       | 0.0       | 0.0            |                         |                         | 0.5     | 0.0          | 152.8                | 152.9               | -1.70                        | -1.72                       |                        |                       | 1.701                        | 1.712                       | -2.67                     | -2.69                        | 28.53                  | 1375         | 34.4363646 | -118.6464960 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                  |                                  |
| CV-24134-TF | 8/17/2026 1:05:00 PM  |            |            |           |                | 1280                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                       | AtmAA                            |
| CV-24134-TF | 8/17/2026 1:06:23 PM  | 45.4       | 54.6       | 0.0       | 0.0            |                         |                         | 0.8     | 0.0          | 144.7                | 145.0               | -2.84                        | -2.81                       |                        |                       | 2.850                        | 2.827                       | -3.30                     | -3.16                        | 28.6                   | 1353         | 34.4363537 | -118.6464931 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                  |                                  |
| CV-24135    | 8/11/2026 10:34:12 AM | 8.9        | 76.3       | 0.2       | 14.6           |                         |                         | 0.1     | 73.0         | 150.3                | 150.4               | -1.30                        | -1.29                       |                        |                       | 1.288                        | 1.282                       | -2.80                     | -2.85                        | 28.61                  | 1361         | 34.4363620 | -118.6459593 | Valve Adjustment:NSPS/EG CAC,High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed |                                  |
| CV-24135    | 8/11/2026 10:34:35 AM | 8.9        | 77.8       | 0.3       | 13.0           |                         |                         | 0.1     | 43.3         | 150.5                | 150.6               | -1.30                        | -1.30                       |                        |                       | 1.268                        | 1.252                       | -2.76                     | -2.76                        | 28.61                  | 1363         | 34.4363752 | -118.6459477 | Valve Adjustment:High Temp,Barely Open                                                                                                                |                                  |
| CV-24135    | 8/17/2026 2:55:35 PM  |            | 77.9       | 0.0       |                |                         |                         |         |              | 150.7                | 150.5               | -0.87                        | -0.86                       | 0.0                    | 0.0                   | 0.830                        | 0.817                       | -3.35                     |                              | 28.57                  | 1362         | 34.4363775 | -118.6459528 | ,                                                                                                                                                     |                                  |
| CV-24135    | 8/18/2026 2:25:00 PM  |            |            |           |                | 3700                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                       | AtmAA                            |
| CV-24135    | 8/18/2026 2:26:08 PM  | 27.0       | 64.1       | 0.0       | 8.9            |                         |                         | 0.4     | 0.0          | 150.6                | 150.6               | -1.18                        | -1.17                       |                        |                       | 1.175                        | 1.182                       | -4.00                     | -4.04                        | 28.54                  | 1365         | 34.4363803 | -118.6459664 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                  |                                  |
| CV-24136    | 8/18/2026 12:05:04 PM | 27.1       | 49.8       | 0.0       | 23.1           |                         |                         | 0.5     | 0.0          | 132.5                | 132.3               | -2.35                        | -0.53                       |                        |                       | 2.335                        | 0.527                       | -8.29                     | -9.90                        | 28.66                  | 1322         | 34.4366083 | -118.6442883 | Valve Adjustment:NSPS/EG CAC,High Temp,Decreased Flow/Vacuum                                                                                          |                                  |
| CV-24136    | 8/18/2026 12:06:06 PM | 27.4       | 50.4       | 0.0       | 22.2           |                         |                         | 0.5     | 0.0          | 129.2                | 129.5               | -0.52                        | -0.52                       |                        |                       | 0.523                        | 0.555                       | -10.09                    | -9.74                        | 28.66                  | 1319         | 34.4366215 | -118.6442825 | Valve Adjustment:NSPS/EG CAC,Barely Open                                                                                                              |                                  |
| CV-24137    | 8/17/2026 1:38:42 PM  | 38.9       | 41.2       | 0.0       | 19.9           |                         |                         | 0.9     | 0.0          | 118.8                | 119.0               | -5.39                        | -5.05                       |                        |                       | 5.301                        | 4.984                       | -18.03                    | -18.08                       | 28.65                  | 1360         | 34.4361480 | -118.6434727 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                                |                                  |
| CV-24138    | 8/3/2026 9:05:00 AM   |            |            |           |                |                         | 180000                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                       | AirTech Lab; [User entered 18%]  |
| CV-24138    | 8/3/2026 9:05:00 AM   |            |            |           |                | 560                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                                                       | AirTech Lab                      |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init<br>Flow<br>[scfm] | Adj<br>Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                                     |
|------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|------------------------|-----------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|----------------------------------------------------------------------------------------------------------------------------------------------|
| CV-24138   | 8/5/2026 7:50:00 AM   |            |            |           |                |                         | 190000                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab; [User entered 19%]                                                                                                              |
| CV-24138   | 8/5/2026 7:50:00 AM   |            |            |           |                | 630                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab                                                                                                                                  |
| CV-24138   | 8/11/2026 7:40:00 AM  |            |            |           |                |                         | 89000                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab; [User entered 8.9%]                                                                                                             |
| CV-24138   | 8/11/2026 7:40:00 AM  |            |            |           |                | 340                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab                                                                                                                                  |
| CV-24138   | 8/14/2026 8:33:40 AM  | 2.4        | 23.0       | 13.7      | 60.9           |                         |                         | 0.1     | 4.4          | 84.9                 | 85.1                | -2.76                        | -3.16                       |                        |                       | 2.697                        | 3.173                       | -2.95                     | -3.02                        | 28.71                  | 1279         | 34.4342732 | -118.6512595 | Valve Adjustment:High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected                              |
| CV-24138   | 8/26/2026 5:04:54 PM  | 3.7        | 27.4       | 11.3      | 57.6           |                         |                         | 0.1     | 5.1          | 121.2                | 121.1               | -3.88                        | -3.87                       |                        |                       | 3.802                        | 3.838                       | -3.74                     | -3.74                        | 28.61                  | 1273         | 34.4342550 | -118.6512582 | Valve Comment:Watered in;Valve Adjustment:NSPS/EG CAI;Well Comment:pump is off;Well Condition:Pnumatic Pump Installed                        |
| CV-24138   | 8/26/2026 5:09:09 PM  | 3.3        | 24.4       | 11.8      | 60.5           |                         |                         | 0.1     | 5.1          | 120.9                | 121.0               | -3.85                        | -3.84                       |                        |                       | 3.857                        | 3.769                       | -3.74                     | -3.67                        | 28.6                   | 1276         | 34.4342622 | -118.6512566 | Valve Adjustment:NSPS/EG CAI,High O2,Surging Liquid in Well (Watered In);Well Comment:Pump not active;Well Condition:Pnumatic Pump Installed |
| CV-24139   | 8/3/2026 9:00:00 AM   |            |            |           |                |                         | 56000                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab; [User entered 5.6%]                                                                                                             |
| CV-24139   | 8/3/2026 9:00:00 AM   |            |            |           |                | 190                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab                                                                                                                                  |
| CV-24139   | 8/6/2026 8:00:00 AM   |            |            |           |                |                         | 190600                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA; [User entered 19.06%]                                                                                                                 |
| CV-24139   | 8/6/2026 8:00:00 AM   |            |            |           |                | 958                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                        |
| CV-24139   | 8/6/2026 8:20:30 AM   | 3.7        | 70.9       | 0.6       | 24.8           |                         |                         | 0.1     | 41.3         | 168.3                | 168.3               | -7.89                        | -7.87                       |                        |                       | 8.333                        | 8.236                       | -8.49                     | -8.33                        | 28.7                   | 1274         | 34.4345037 | -118.6511424 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed                                                        |
| CV-24139   | 8/12/2026 8:30:00 AM  |            |            |           |                | 925                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                        |
| CV-24139   | 8/12/2026 8:30:51 AM  | 15.7       | 71.8       | 0.4       | 12.1           |                         |                         | 0.2     | 30.3         | 164.1                | 164.2               | -5.39                        | -5.29                       |                        |                       | 5.672                        | 5.574                       | -8.06                     | -7.81                        | 28.65                  | 1288         | 34.4345091 | -118.6511450 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed                                                        |
| CV-24139   | 8/14/2026 8:27:08 AM  | 3.5        | 73.1       | 0.6       | 22.8           |                         |                         | 0.0     | 38.0         | 174.8                | 170.5               | -5.89                        | -5.64                       |                        |                       | 6.063                        | 5.843                       | -6.18                     | -6.36                        | 28.68                  | 1267         | 34.4345363 | -118.6511287 | Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)                              |
| CV-24139   | 8/14/2026 8:30:50 AM  | 3.3        | 76.4       | 0.4       | 19.9           |                         |                         | 0.0     | 49.8         | 180.1                | 180.6               | -5.73                        | -5.57                       |                        |                       | 5.955                        | 5.815                       | -6.61                     | -5.99                        | 28.7                   | 1264         | 34.4342742 | -118.6512438 | Valve Adjustment:High Temp,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down                                                 |
| CV-24139   | 8/20/2026 10:44:52 AM | 40.5       | 58.9       | 0.6       | 0.0            |                         |                         | 0.7     | 0.0          | 156.5                | 156.6               | -5.05                        | -5.05                       |                        |                       | 5.690                        | 5.732                       | -5.45                     | -6.06                        | 28.7                   | 1270         | 34.4345175 | -118.6510961 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed                                                        |
| CV-24139   | 8/26/2026 1:26:15 PM  | 7.5        | 68.7       | 0.4       | 23.4           |                         |                         | 0.1     | 58.5         | 178.8                | 178.8               | -5.32                        | -5.39                       |                        |                       | 5.396                        | 5.506                       | -5.69                     | -5.73                        | 28.59                  | 1277         | 34.4345126 | -118.6511233 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                         |
| CV-24140   | 8/3/2026 8:55:00 AM   |            |            |           |                |                         | 130000                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab; [User entered 13%]                                                                                                              |
| CV-24140   | 8/3/2026 8:55:00 AM   |            |            |           |                | 850                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab                                                                                                                                  |
| CV-24140   | 8/14/2026 8:05:23 AM  | 1.9        | 77.0       | 0.8       | 20.3           |                         |                         | 0.0     | 25.4         | 150.7                | 150.8               | -4.76                        | -4.56                       |                        |                       | 4.788                        | 4.578                       | -4.80                     | -4.65                        | 28.67                  | 1303         | 34.4346848 | -118.6511298 | Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)                                          |
| CV-24140   | 8/14/2026 8:05:55 AM  | 1.9        | 75.9       | 0.9       | 21.3           |                         |                         | 0.0     | 23.7         | 150.8                | 150.9               | -4.55                        | -4.49                       |                        |                       | 4.665                        | 4.489                       | -4.60                     | -4.56                        | 28.67                  | 1297         | 34.4346737 | -118.6511180 | Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)                                                      |
| CV-24140   | 8/17/2026 12:53:30 PM | 16.5       | 83.5       | 0.0       | 0.0            |                         |                         | 0.2     | 0.0          | 169.3                | 169.3               | -6.27                        | -6.28                       | 0.0                    | 0.0                   | 6.012                        | 6.139                       | -6.46                     |                              | 28.66                  | 1280         | 34.4346808 | -118.6511132 | No Flow Measurement,High Temp                                                                                                                |
| CV-24140   | 8/17/2026 1:05:00 PM  |            |            |           |                | 2510                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                        |
| CV-24140   | 8/20/2026 10:48:35 AM | 40.1       | 59.9       | 0.0       | 0.0            |                         |                         | 0.7     | 0.0          | 165.5                | 165.9               | -4.89                        | -4.91                       |                        |                       | 5.563                        | 5.619                       | -5.31                     | -5.22                        | 28.68                  | 1275         | 34.4346750 | -118.6511173 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed                                                        |
| CV-24140   | 8/26/2026 1:20:59 PM  | 4.7        | 71.1       | 0.0       | 24.2           |                         |                         | 0.1     | 0.0          | 166.9                | 169.0               | -4.79                        | -4.98                       |                        |                       | 4.785                        | 5.075                       | -5.17                     | -5.58                        | 28.6                   | 1280         | 34.4346709 | -118.6511249 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed                                                        |
| CV-24141   | 8/5/2026 7:55:00 AM   |            |            |           |                |                         | 7400                    |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab; [User entered 0.74%]                                                                                                            |
| CV-24141   | 8/5/2026 7:55:00 AM   |            |            |           |                | 26                      |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab                                                                                                                                  |
| CV-24141   | 8/14/2026 8:18:01 AM  | 0.3        | 6.4        | 19.2      | 74.1           |                         |                         | 0.0     | 3.9          | 72.5                 | 72.6                | -0.69                        | -0.71                       |                        |                       | 0.668                        | 0.689                       | -0.65                     | -0.65                        | 28.67                  | 1302         | 34.4355113 | -118.6513003 | Valve Adjustment:High O2                                                                                                                     |
| CV-24141   | 8/19/2026 8:10:32 AM  | 0.1        | 3.6        | 20.4      | 75.9           |                         |                         | 0.0     | 3.7          | 78.6                 | 79.8                | -4.70                        | -4.32                       |                        |                       | 4.729                        | 4.344                       | -4.62                     | -4.58                        | 28.61                  | 1276         | 34.4355098 | -118.6513307 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Surging Liquid in Well (Watered In)                                               |
| CV-24141   | 8/19/2026 8:11:24 AM  | 0.1        | 2.3        | 20.5      | 77.2           |                         |                         | 0.0     | 3.8          | 80.1                 | 80.2                | -4.79                        | -4.79                       |                        |                       | 4.820                        | 4.822                       | -4.76                     | -4.74                        | 28.63                  | 1285         | 34.4355110 | -118.6513203 | Valve Adjustment:High O2,Surging Liquid in Well (Watered In)                                                                                 |
| CV-24142   | 8/3/2026 9:10:00 AM   |            |            |           |                |                         | 130000                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab; [User entered 13%]                                                                                                              |
| CV-24142   | 8/3/2026 9:10:00 AM   |            |            |           |                | 790                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab                                                                                                                                  |
| CV-24142   | 8/5/2026 7:45:00 AM   |            |            |           |                |                         | 150000                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab; [User entered 15%]                                                                                                              |
| CV-24142   | 8/5/2026 7:45:00 AM   |            |            |           |                | 1100                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab                                                                                                                                  |
| CV-24142   | 8/6/2026 7:55:00 AM   |            |            |           |                |                         | 130700                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA; [User entered 13.07%]                                                                                                                 |
| CV-24142   | 8/6/2026 7:55:00 AM   |            |            |           |                | 1290                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                        |
| CV-24142   | 8/6/2026 8:12:12 AM   | 4.7        | 68.4       | 1.3       | 25.6           |                         |                         | 0.1     | 19.7         | 168.1                | 168.0               | -2.18                        | -2.28                       |                        |                       | 2.340                        | 2.067                       | -2.24                     | -2.19                        | 28.71                  | 1275         | 34.4339795 | -118.6513577 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed                                                        |
| CV-24142   | 8/11/2026 7:45:00 AM  |            |            |           |                |                         | 75000                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab; [User entered 7.5%]                                                                                                             |
| CV-24142   | 8/11/2026 7:45:00 AM  |            |            |           |                | 490                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab                                                                                                                                  |
| CV-24142   | 8/12/2026 8:35:00 AM  |            |            |           |                | 2030                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                        |
| CV-24142   | 8/12/2026 8:39:33 AM  | 13.8       | 65.1       | 2.5       | 18.6           |                         |                         | 0.2     | 7.4          | 152.6                | 152.6               | -1.09                        | -1.35                       |                        |                       | 1.090                        | 1.364                       | -1.94                     | -2.38                        | 28.66                  | 1282         | 34.4339906 | -118.6513666 | Valve Adjustment:No Flow Measurement,High Temp;Well Comment:Construction working on vacuum line                                              |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init<br>Flow<br>[scfm] | Adj<br>Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                                                      |
|------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|------------------------|-----------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------|
| CV-24142   | 8/14/2026 8:23:00 AM  | 2.8        | 73.8       | 0.4       | 23.0           |                         |                         | 0.0     | 57.5         | 182.2                | 182.9               | -1.21                        | -1.20                       |                        |                       | 1.197                        | 1.196                       | -1.53                     | -1.55                        | 28.78                  | 1263         | 34.4339858 | -118.6513487 | Valve Adjustment: NSPS/EG CAI, High Temp, Surging Liquid in Header, Plugged/Pinched Suspected; Well Condition: Pneumatic Pump Installed                       |
| CV-24142   | 8/14/2026 8:24:52 AM  | 2.9        | 73.9       | 0.4       | 22.8           |                         |                         | 0.0     | 57.0         | 181.5                | 181.0               | -1.45                        | -1.45                       |                        |                       | 1.384                        | 1.384                       | -1.43                     | -1.45                        | 28.77                  | 1264         | 34.4339928 | -118.6513510 |                                                                                                                                                               |
| CV-24142   | 8/20/2026 10:34:18 AM | 35.3       | 64.7       | 0.0       | 0.0            |                         |                         | 0.5     | 0.0          | 173.3                | 174.0               | -0.51                        | -0.52                       |                        |                       | 0.443                        | 0.438                       | -0.27                     | -0.18                        | 28.7                   | 1256         | 34.4340011 | -118.6513324 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Pneumatic Pump Installed                                                                    |
| CV-24142   | 8/26/2026 1:44:20 PM  | 5.6        | 55.6       | 5.2       | 33.6           |                         |                         | 0.1     | 6.5          | 150.0                | 146.6               | -1.98                        | -1.05                       |                        |                       | 2.008                        | 1.067                       | -2.27                     | -2.23                        | 28.57                  | 1264         | 34.4339922 | -118.6513392 | Valve Adjustment: No Flow Measurement, High Temp, Decreased Flow/Vacuum; Well Condition: Pneumatic Pump Installed                                             |
| CV-24142   | 8/26/2026 1:47:24 PM  | 5.6        | 59.5       | 4.0       | 30.9           |                         |                         | 0.1     | 7.7          | 146.6                | 146.2               | -1.15                        | -1.09                       |                        |                       | 1.174                        | 1.114                       | -2.26                     | -2.15                        | 28.58                  | 1265         | 34.4339921 | -118.6513392 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Pneumatic Pump Installed                                                                    |
| CV-24143   | 8/3/2026 7:50:00 AM   |            |            |           |                |                         | 87000                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab; [User entered 8.7%]                                                                                                                              |
| CV-24143   | 8/3/2026 7:50:00 AM   |            |            |           |                | 610                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab                                                                                                                                                   |
| CV-24143   | 8/13/2026 2:58:30 PM  | 1.2        | 39.3       | 11.3      | 48.3           |                         |                         | 0.0     | 4.3          | 109.0                | 108.9               | -1.89                        | -2.12                       |                        |                       | 1.706                        | 1.836                       | -1.92                     | -2.25                        | 28.61                  | 1288         | 34.4349938 | -118.6512292 | Valve Adjustment: NSPS/EG CAI, High O2, Valve 100% Open; Well Comment: no pump installed; Well Repairs: Sample Port                                           |
| CV-24143   | 8/13/2026 3:00:34 PM  | 1.1        | 39.1       | 11.1      | 48.7           |                         |                         | 0.0     | 4.4          | 108.2                | 108.2               | -2.01                        | -2.30                       |                        |                       | 1.656                        | 2.112                       | -2.11                     | -2.53                        | 28.62                  | 1289         | 34.4349863 | -118.6512285 | Valve Adjustment: High O2, Surging Liquid in Well (Watered In)                                                                                                |
| CV-24143   | 8/19/2026 8:25:27 AM  | 2.8        | 17.4       | 15.8      | 64.0           |                         |                         | 0.2     | 4.0          | 105.1                | 105.2               | -5.52                        | -5.31                       |                        |                       | 5.755                        | 5.509                       | -5.59                     | -5.58                        | 28.64                  | 1293         | 34.4349870 | -118.6512090 | Valve Adjustment: High O2, Surging Liquid in Well (Watered In)                                                                                                |
| CV-24143   | 8/19/2026 8:26:07 AM  | 2.7        | 17.3       | 15.8      | 64.2           |                         |                         | 0.2     | 4.1          | 105.4                | 105.4               | -4.95                        | -5.41                       |                        |                       | 5.173                        | 5.532                       | -5.01                     | -5.56                        | 28.64                  | 1291         | 34.4349898 | -118.6512083 | Valve Adjustment: High O2, Surging Liquid in Well (Watered In)                                                                                                |
| CV-24144   | 8/14/2026 8:01:18 AM  | 57.4       | 38.9       | 0.0       | 3.7            |                         |                         | 1.5     | 0.0          | 83.3                 | 97.6                | -1.66                        | -1.26                       |                        |                       | 1.653                        | 1.224                       | -1.74                     | -1.20                        | 28.78                  | 1256         | 34.4325730 | -118.6515692 | Valve Adjustment: Surging Liquid in Header, Plugged/Pinched Suspected                                                                                         |
| CV-24144   | 8/25/2026 2:15:55 PM  | 54.1       | 43.0       | 0.1       | 2.8            |                         |                         | 1.3     | 28.0         | 117.2                | 117.3               | -0.50                        | -0.60                       | 2.1                    | 2.4                   | 0.472                        | 0.607                       | -0.15                     | -0.26                        | 28.64                  | 1232         | 34.4325603 | -118.6515912 | Valve Adjustment: Barely Open                                                                                                                                 |
| CV-24145   | 8/4/2026 8:00:00 AM   |            |            |           |                |                         | 230000                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA; [User entered 23%]                                                                                                                                     |
| CV-24145   | 8/4/2026 8:00:00 AM   |            |            |           |                | 2530                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                                         |
| CV-24145   | 8/4/2026 8:02:30 AM   | 14.8       | 68.0       | 0.0       | 17.2           |                         |                         | 0.2     | 0.0          | 187.0                | 187.2               | -7.79                        | -7.79                       |                        |                       | 0.910                        | 0.892                       | -12.49                    | -12.44                       | 28.46                  | 1351         | 34.4362271 | -118.6496093 | Valve Adjustment: High Temp                                                                                                                                   |
| CV-24145   | 8/10/2026 2:09:48 PM  | 32.8       | 66.9       | 0.3       | 0.0            |                         |                         | 0.5     | 0.0          | 188.3                | 188.1               | -4.80                        | -4.79                       |                        |                       | 0.000                        | 0.000                       | -8.58                     | -8.72                        | 28.53                  | 1364         | 34.4362307 | -118.6496305 | Valve Adjustment: High Temp                                                                                                                                   |
| CV-24145   | 8/10/2026 2:15:00 PM  |            |            |           |                | 2010                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                                         |
| CV-24145   | 8/18/2026 7:59:10 AM  | 14.7       | 61.2       | 0.0       | 24.1           |                         |                         | 0.2     | 0.0          | 187.5                | 187.7               | -5.24                        | -5.05                       |                        |                       | 0.589                        | 0.459                       | -9.23                     | -9.09                        | 28.59                  | 1368         | 34.4362341 | -118.6496304 | Valve Adjustment: High Temp                                                                                                                                   |
| CV-24145   | 8/18/2026 8:00:00 AM  |            |            |           |                | 573                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                                         |
| CV-24145   | 8/25/2026 7:42:10 AM  | 15.9       | 62.4       | 0.0       | 21.7           |                         |                         | 0.3     | 0.0          | 188.8                | 188.6               | -5.07                        | -5.05                       |                        |                       | 0.207                        | 0.104                       | -9.65                     | -9.98                        | 28.57                  | 1365         | 34.4362269 | -118.6496310 | Valve Adjustment: High Temp                                                                                                                                   |
| CV-24145   | 8/31/2026 2:39:44 PM  | 21.7       | 61.8       | 0.0       | 16.5           |                         |                         | 0.4     | 0.0          | 188.0                | 188.5               | -3.41                        | -3.41                       |                        |                       | 0.016                        | 0.014                       | -6.82                     | -6.91                        | 28.53                  | 1368         | 34.4362053 | -118.6496204 | Valve Adjustment: High Temp                                                                                                                                   |
| CV-24146   | 8/5/2026 12:11:13 PM  | 50.4       | 40.8       | 1.4       | 7.4            |                         |                         | 1.2     | 5.3          | 114.4                | 114.3               | -7.06                        | -6.54                       | 22.1                   | 24.6                  | 1.063                        | 1.285                       | -7.74                     |                              | 28.6                   | 1299         | 34.4373528 | -118.6464427 | ,                                                                                                                                                             |
| CV-24146   | 8/18/2026 8:55:23 AM  | 53.6       | 42.6       | 0.0       | 3.8            |                         |                         | 1.3     | 0.0          | 115.1                | 115.1               | -5.06                        | -5.14                       | 23.2                   | 23.9                  | 0.702                        | 0.746                       | -6.48                     | -6.68                        | 28.64                  | 1274         | 34.4374365 | -118.6464042 | Valve Adjustment: Increased Flow/Vacuum                                                                                                                       |
| CV-24146   | 8/18/2026 8:56:13 AM  | 52.5       | 42.9       | 0.0       | 4.6            |                         |                         | 1.2     | 0.0          | 115.1                | 115.1               | -5.33                        | -5.33                       | 24.3                   | 24.3                  | 0.774                        | 0.774                       | -6.93                     | -6.93                        | 28.64                  | 1284         | 34.4374337 | -118.6463878 |                                                                                                                                                               |
| CV-24147   | 8/5/2026 12:07:54 PM  | 49.3       | 43.1       | 0.0       | 7.6            |                         |                         | 1.1     | 0.0          | 116.0                | 116.0               | -8.30                        | -8.30                       | 39.9                   | 39.7                  | 0.384                        | 0.380                       | -8.91                     |                              | 28.62                  | 1273         | 34.4373640 | -118.6464110 | ,                                                                                                                                                             |
| CV-24147   | 8/18/2026 9:01:02 AM  | 51.5       | 40.4       | 0.1       | 8.0            |                         |                         | 1.3     | 88.6         | 116.0                | 116.0               | -6.64                        | -6.64                       | 10.9                   | 10.9                  | 0.031                        | 0.031                       | -7.18                     | -7.18                        | 28.68                  | 1271         | 34.4375323 | -118.6459518 |                                                                                                                                                               |
| CV-24148   | 8/4/2026 1:25:00 PM   |            |            |           |                |                         | 71100                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA; [User entered 7.11%]                                                                                                                                   |
| CV-24148   | 8/4/2026 1:25:00 PM   |            |            |           |                | 1540                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                                         |
| CV-24148   | 8/4/2026 1:31:05 PM   | 35.7       | 63.9       | 0.0       | 0.4            |                         |                         | 0.6     | 0.0          | 179.9                | 179.8               | -12.52                       | -12.47                      |                        |                       | 12.877                       | 12.735                      | -15.08                    | -15.79                       | 28.46                  | 1373         | 34.4350680 | -118.6466752 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                                                      |
| CV-24148   | 8/11/2026 8:31:22 AM  | 28.3       | 60.7       | 0.0       | 11.0           |                         |                         | 0.5     | 0.0          | 179.1                | 179.1               | -9.38                        | -9.87                       |                        |                       | 9.878                        | 10.334                      | -18.21                    | -18.25                       | 28.6                   | 1388         | 34.4350708 | -118.6466613 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                                                      |
| CV-24148   | 8/11/2026 8:35:00 AM  |            |            |           |                | 1410                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                                         |
| CV-24148   | 8/18/2026 1:35:00 PM  | 42.6       | 57.3       | 0.0       | 0.1            |                         |                         | 0.7     | 0.0          | 171.1                | 171.2               | -12.39                       | -12.43                      |                        |                       | 12.511                       | 12.490                      | -14.78                    | -14.82                       | 28.53                  | 1369         | 34.4350595 | -118.6466527 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                                                      |
| CV-24148   | 8/18/2026 1:40:00 PM  |            |            |           |                | 931                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                                                                                         |
| CV-24148   | 8/26/2026 8:11:22 AM  | 15.2       | 70.9       | 0.0       | 13.9           |                         |                         | 0.2     | 0.0          | 173.6                | 173.5               | -13.48                       | -13.48                      |                        |                       | 13.831                       | 13.814                      | -17.96                    | -18.02                       | 28.49                  | 1391         | 34.4350501 | -118.6466756 | Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed                                                                      |
| CV-24149   | 8/7/2026 10:19:03 AM  | 29.4       | 65.1       | 0.0       | 5.5            |                         |                         | 0.5     | 0.0          | 129.3                | 129.5               | -0.59                        | -0.59                       | 12.0                   | 12.0                  | 0.038                        | 0.038                       | -6.13                     | -6.23                        | 28.6                   | 1373         | 34.4347658 | -118.6470165 | Valve Adjustment: Barely Open                                                                                                                                 |
| CV-24149   | 8/9/2026 1:04:18 PM   | 33.6       | 55.5       | 0.0       | 10.9           |                         |                         | 0.6     | 0.0          | 129.3                | 129.4               | -0.12                        | -0.16                       | 33.7                   | 31.8                  | 0.301                        | 0.269                       | -7.64                     | -7.71                        | 28.5                   | 1360         | 34.4347567 | -118.6469843 | Valve Adjustment: Barely Open                                                                                                                                 |
| CV-24149   | 8/18/2026 9:35:12 AM  | 34.4       | 59.1       | 0.2       | 6.3            |                         |                         | 0.6     | 31.5         | 129.3                | 129.3               | -1.04                        | -1.02                       | 20.3                   | 18.9                  | 0.108                        | 0.093                       | -7.64                     | -7.22                        | 28.56                  | 1365         | 34.4347980 | -118.6469970 | Valve Adjustment: Barely Open                                                                                                                                 |
| CV-24150   | 8/9/2026 2:03:12 PM   | 47.8       | 47.7       | 0.0       | 4.5            |                         |                         | 1.0     | 0.0          | 113.3                | 113.5               | -0.62                        | -0.63                       |                        |                       | 0.602                        | 0.600                       | -16.21                    | -16.20                       | 28.46                  | 1379         | 34.4345952 | -118.6457610 |                                                                                                                                                               |
| CV-24150   | 8/18/2026 8:51:40 AM  | 52.3       | 47.0       | 0.1       | 0.6            |                         |                         | 1.1     | 6.0          | 113.3                | 113.4               | -2.57                        | -2.57                       |                        |                       | 2.572                        | 2.568                       | -20.81                    | -20.55                       | 28.54                  | 1379         | 34.4346052 | -118.6457378 | Valve Adjustment: Barely Open, Surging Liquid in Header                                                                                                       |
| CV-24151   | 8/7/2026 8:30:46 AM   | 39.6       | 56.3       | 0.0       | 4.1            |                         |                         | 0.7     | 0.0          | 114.9                | 121.4               | 4.83                         | -0.38                       |                        |                       | 0.000                        | 0.366                       | -10.87                    | -10.77                       | 28.6                   | 1380         | 34.4344322 | -118.6476433 | Valve Adjustment: NSPS/EG CAI, Positive Static Press., Increased Flow/Vacuum, Barely Open, Surging Liquid in Header; Well Condition: Pneumatic Pump Installed |
| CV-24151   | 8/7/2026 8:31:30 AM   | 42.7       | 54.7       | 0.0       | 2.6            |                         |                         | 0.8     | 0.0          | 122.1                | 122.1               | -0.50                        | -0.49                       |                        |                       | 0.488                        | 0.481                       | -11.05                    | -10.94                       | 28.61                  | 1380         | 34.4344367 | -118.6476407 | Valve Adjustment: Barely Open, Surging Liquid in Header; Well Condition: Pneumatic Pump Installed                                                             |
| CV-24151   | 8/18/2026 9:57:58 AM  | 44.5       | 54.4       | 0.2       | 0.9            |                         |                         | 0.8     | 4.5          | 135.9                | 135.9               | -1.32                        | -1.09                       |                        |                       | 1.299                        | 1.066                       | -6.51                     | -6.65                        | 28.59                  | 1353         | 34.4344070 | -118.6476415 | Valve Adjustment: NSPS/EG CAI, High Temp, Decreased Flow/Vacuum, Barely Open                                                                                  |
| CV-24152   | 8/7/2026 8:53:59 AM   | 21.1       | 71.3       | 0.0       | 7.6            |                         |                         | 0.3     | 0.0          | 142.6                | 142.6               | -1.41                        | -1.41                       | 33.6                   | 34.0                  | 2.742                        | 2.812                       | -8.29                     | -8.44                        | 28.6                   | 1379         | 34.4344635 | -118.6471717 | Valve Adjustment: High Temp, Barely Open; Well Condition: Lorentz Pump Installed                                                                              |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init<br>Flow<br>[scfm] | Adj<br>Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                                                        |
|------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|------------------------|-----------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------|
| CV-24152   | 8/18/2026 9:38:38 AM  | 35.5       | 60.9       | 1.8       | 1.8            |                         |                         | 0.6     | 1.0          | 143.0                | 143.0               | -0.81                        | -0.84                       | 28.8                   | 28.7                  | 2.014                        | 1.995                       | -5.38                     | -5.51                        | 28.59                  | 1375         | 34.4344805 | -118.6471788 | Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed                       |
| CV-24153   | 8/9/2026 1:28:08 PM   | 36.8       | 59.2       | 0.0       | 4.0            |                         |                         | 0.6     | 0.0          | 116.3                | 116.4               | -0.28                        | -0.29                       |                        |                       | 0.292                        | 0.272                       | -14.03                    | -13.98                       | 28.49                  | 1338         | 34.4343525 | -118.6464220 | Valve Adjustment:Barely Open;Well Condition:Lorentz Pump Installed                                                                                              |
| CV-24153   | 8/18/2026 9:13:41 AM  | 38.5       | 61.4       | 0.0       | 0.1            |                         |                         | 0.6     | 0.0          | 121.3                | 122.1               | -2.08                        | -1.94                       |                        |                       | 2.076                        | 1.931                       | -16.97                    | -16.92                       | 28.56                  | 1380         | 34.4343973 | -118.6464145 | Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed                                                                                    |
| CV-24154   | 8/9/2026 1:33:06 PM   | 39.6       | 56.5       | 0.0       | 3.9            |                         |                         | 0.7     | 0.0          | 110.0                | 110.1               | 0.04                         | -0.03                       |                        |                       | 0.000                        | 0.000                       | -0.56                     | -0.31                        | 28.49                  | 1377         | 34.4342422 | -118.6461045 | Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Surging Liquid in Header,Plugged/Pinched Suspected;Well Condition:Lorentz Pump Installed        |
| CV-24154   | 8/9/2026 1:34:11 PM   | 39.4       | 56.0       | 0.0       | 4.5            |                         |                         | 0.7     | 0.0          | 110.2                | 110.2               | -0.07                        | -0.07                       |                        |                       | 0.110                        | 0.110                       | -0.34                     | -0.34                        | 28.5                   | 1376         | 34.4342432 | -118.6461043 | Valve Adjustment:Surging Liquid in Header,Plugged/Pinched Suspected;Well Condition:Lorentz Pump Installed                                                       |
| CV-24154   | 8/16/2026 10:46:25 AM | 45.8       | 48.8       | 0.0       | 5.3            |                         |                         | 0.9     | 0.0          | 115.9                | 116.1               | -4.96                        | -4.83                       |                        |                       | 4.993                        | 4.864                       | -10.90                    | -9.14                        | 28.68                  | 1404         | 34.4342640 | -118.6460503 | Well Condition:Lorentz Pump Installed                                                                                                                           |
| CV-24155   | 8/7/2026 10:08:03 AM  | 26.4       | 68.3       | 0.0       | 5.3            |                         |                         | 0.4     | 0.0          | 140.5                | 140.7               | -0.87                        | -0.77                       |                        |                       | 0.850                        | 0.746                       | -10.12                    | -10.28                       | 28.59                  | 1385         | 34.4342817 | -118.6467178 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open;Well Condition:Lorentz Pump Installed                                                  |
| CV-24155   | 8/7/2026 10:09:06 AM  | 24.7       | 70.7       | 0.0       | 4.6            |                         |                         | 0.3     | 0.0          | 140.9                | 140.9               | -0.65                        | -0.63                       |                        |                       | 0.619                        | 0.596                       | -6.79                     | -6.75                        | 28.6                   | 1376         | 34.4342535 | -118.6467128 | Valve Adjustment:High Temp,Surging Liquid in Header;Well Condition:Lorentz Pump Installed                                                                       |
| CV-24155   | 8/9/2026 1:23:49 PM   | 20.9       | 67.7       | 0.0       | 11.4           |                         |                         | 0.3     | 0.0          | 133.2                | 133.8               | 0.17                         | -0.17                       |                        |                       | 0.000                        | 0.185                       | -7.70                     | -7.14                        | 28.49                  | 1353         | 34.4342427 | -118.6467322 | Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum;Well Comment:pump is active;Well Condition:Lorentz Pump Installed         |
| CV-24155   | 8/9/2026 1:25:08 PM   | 26.5       | 65.6       | 0.0       | 7.9            |                         |                         | 0.4     | 0.0          | 133.8                | 133.7               | -0.29                        | -0.26                       |                        |                       | 0.290                        | 0.274                       | -7.41                     | -7.06                        | 28.49                  | 1401         | 34.4342540 | -118.6467305 | Valve Adjustment:NSPS/EG CAI,High Temp;Well Comment:pump is active;Well Condition:Lorentz Pump Installed                                                        |
| CV-24155   | 8/18/2026 9:10:39 AM  | 32.3       | 62.3       | 0.1       | 5.3            |                         |                         | 0.5     | 53.0         | 126.6                | 127.2               | -2.09                        | -1.97                       |                        |                       | 2.069                        | 1.961                       | -7.61                     | -7.74                        | 28.56                  | 1377         | 34.4343017 | -118.6467205 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open                                                                                                              |
| CV-24156   | 8/6/2026 3:01:01 PM   | 26.6       | 70.3       | 0.1       | 3.0            |                         |                         | 0.4     | 30.0         | 135.9                | 135.8               | -1.26                        | -1.22                       | 50.3                   | 55.4                  | 0.672                        | 0.815                       | -13.06                    | -13.13                       | 28.49                  | 1376         | 34.4340700 | -118.6477062 | Valve Adjustment:Barely Open                                                                                                                                    |
| CV-24156   | 8/18/2026 1:44:50 PM  | 28.0       | 68.2       | 0.2       | 3.6            |                         |                         | 0.4     | 18.0         | 136.5                | 136.5               | -1.49                        | -1.39                       | 50.3                   | 49.6                  | 0.673                        | 0.655                       | -12.49                    | -12.27                       | 28.52                  | 1368         | 34.4340508 | -118.6477130 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                                          |
| CV-24157   | 8/7/2026 8:09:32 AM   | 50.5       | 45.4       | 0.0       | 4.1            |                         |                         | 1.1     | 0.0          | 100.0                | 100.4               | -1.58                        | -2.35                       |                        |                       | 1.566                        | 2.341                       | -17.08                    | -16.98                       | 28.6                   | 1383         | 34.4337978 | -118.6473343 | Valve Adjustment:Increased Flow/Vacuum,Barely Open                                                                                                              |
| CV-24157   | 8/18/2026 1:49:29 PM  | 44.2       | 55.6       | 0.2       | 0.0            |                         |                         | 0.8     | 0.0          | 113.4                | 113.3               | -1.98                        | -1.97                       |                        |                       | 1.936                        | 1.961                       | -12.86                    | -12.88                       | 28.49                  | 1380         | 34.4338173 | -118.6473352 | Valve Adjustment:Barely Open                                                                                                                                    |
| CV-24158   | 8/7/2026 7:55:49 AM   | 44.2       | 54.4       | 0.0       | 1.4            |                         |                         | 0.8     | 0.0          | 128.1                | 128.2               | -2.30                        | -2.29                       | 15.9                   | 15.6                  | 0.702                        | 0.677                       | -17.13                    | -16.94                       | 28.59                  | 1400         | 34.4339147 | -118.6470660 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)                                                                                   |
| CV-24158   | 8/18/2026 9:04:08 AM  | 41.0       | 58.9       | 0.0       | 0.1            |                         |                         | 0.7     | 0.0          | 129.7                | 129.7               | -1.73                        | -1.72                       | 15.2                   | 14.9                  | 0.643                        | 0.616                       | -13.90                    | -13.97                       | 28.54                  | 1390         | 34.4339015 | -118.6470622 | Valve Adjustment:Barely Open                                                                                                                                    |
| CV-24159   | 8/4/2026 12:56:29 PM  | 47.3       | 51.9       | 0.0       | 0.8            |                         |                         | 0.9     | 0.0          | 129.3                | 129.5               | -0.93                        | -1.01                       | 14.7                   | 13.8                  | 0.513                        | 0.454                       | -15.96                    | -16.35                       | 28.41                  | 1389         | 34.4338255 | -118.6465998 |                                                                                                                                                                 |
| CV-24159   | 8/16/2026 10:33:47 AM | 47.4       | 47.7       | 0.0       | 4.9            |                         |                         | 1.0     | 0.0          | 126.5                | 126.5               | -1.43                        | -1.44                       | 16.8                   | 17.3                  | 0.665                        | 0.704                       | -19.47                    | -19.29                       | 28.65                  | 1404         | 34.4337870 | -118.6466003 | Well Condition:Lorentz Pump Installed                                                                                                                           |
| CV-24160   | 8/1/2026 9:53:03 AM   | 45.8       | 53.3       | 0.0       | 0.9            |                         |                         | 0.9     | 0.0          | 128.4                | 128.4               | -3.71                        | -3.34                       | 16.1                   | 9.0                   | 0.621                        | 0.192                       | -21.83                    | -20.99                       | 28.53                  | 1394         | 34.4338213 | -118.6462552 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                                          |
| CV-24160   | 8/16/2026 10:38:46 AM | 48.6       | 47.0       | 0.0       | 4.5            |                         |                         | 1.0     | 0.0          | 127.7                | 127.5               | -2.62                        | -2.62                       | 8.5                    | 8.6                   | 0.171                        | 0.177                       | -19.35                    | -19.60                       | 28.67                  | 1402         | 34.4337982 | -118.6462342 | Well Condition:Lorentz Pump Installed                                                                                                                           |
| CV-24160   | 8/16/2026 10:40:42 AM | 47.9       | 47.1       | 0.0       | 5.0            |                         |                         | 1.0     | 0.0          | 127.3                | 127.2               | -2.58                        | -2.55                       | 11.0                   | 9.9                   | 0.781                        | 0.630                       | -20.32                    | -19.35                       | 28.67                  | 1403         | 34.4337940 | -118.6462422 | Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum                                                                                       |
| CV-24160   | 8/16/2026 10:42:39 AM | 47.6       | 47.8       | 0.0       | 4.6            |                         |                         | 1.0     | 0.0          | 127.1                | 126.9               | -2.44                        | -2.48                       | 10.4                   | 10.1                  | 0.699                        | 0.659                       | -19.32                    | -18.50                       | 28.65                  | 1404         | 34.4337982 | -118.6462245 | Well Condition:Lorentz Pump Installed                                                                                                                           |
| CV-24161   | 8/1/2026 10:07:33 AM  | 32.1       | 42.5       | 0.0       | 25.4           |                         |                         | 0.8     | 0.0          | 122.9                | 125.4               | -15.19                       | -14.16                      |                        |                       | 15.530                       | 14.459                      | 0.20                      | 0.20                         | 28.52                  | 1393         | 34.4338688 | -118.6456010 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                                          |
| CV-24162   | 8/18/2026 8:51:50 AM  | 33.9       | 35.6       | 0.9       | 29.6           |                         |                         | 1.0     | 32.9         | 116.4                | 116.1               | -1.62                        | -1.62                       |                        |                       | 1.621                        | 1.621                       | -18.27                    | -18.90                       | 28.58                  | 1360         | 34.4335685 | -118.6451213 | Valve Adjustment:Barely Open                                                                                                                                    |
| CV-24163   | 8/17/2026 1:04:00 PM  | 28.1       | 64.4       | 0.0       | 7.5            |                         |                         | 0.4     | 0.0          | 139.5                | 140.8               | -0.05                        | -0.05                       |                        |                       | 0.091                        | 0.061                       | -17.41                    | -17.24                       | 28.66                  | 1338         | 34.4334520 | -118.6445292 | Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open                                                                                                              |
| CV-24163   | 8/17/2026 1:04:31 PM  | 28.1       | 65.8       | 0.0       | 6.1            |                         |                         | 0.4     | 0.0          | 140.3                | 140.8               | -0.08                        | -0.06                       |                        |                       | 0.081                        | 0.024                       | -17.09                    | -17.23                       | 28.66                  | 1342         | 34.4334408 | -118.6445238 | Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open                                                                                                              |
| CV-24164   | 8/6/2026 2:07:32 PM   | 29.2       | 67.3       | 0.2       | 3.3            |                         |                         | 0.4     | 16.5         | 128.3                | 127.1               | -0.80                        | -0.78                       |                        |                       | 0.739                        | 0.721                       | -12.84                    | -12.75                       | 28.51                  | 1374         | 34.4334885 | -118.6479427 | Valve Adjustment:Barely Open                                                                                                                                    |
| CV-24164   | 8/18/2026 1:14:57 PM  | 18.6       | 78.4       | 0.2       | 2.8            |                         |                         | 0.2     | 14.0         | 136.1                | 136.9               | -0.13                        | -0.11                       |                        |                       | 0.036                        | 0.024                       | -13.45                    | -13.11                       | 28.55                  | 1367         | 34.4334643 | -118.6480033 | Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed           |
| CV-24164   | 8/18/2026 1:18:27 PM  | 19.1       | 77.3       | 0.2       | 3.4            |                         |                         | 0.2     | 17.0         | 136.6                | 137.0               | -0.19                        | -0.20                       |                        |                       | 0.113                        | 0.145                       | -13.32                    | -13.66                       | 28.55                  | 1368         | 34.4334842 | -118.6479855 | Valve Adjustment:Audible Flow,Barely Open                                                                                                                       |
| CV-24165   | 8/4/2026 1:29:11 PM   | 25.3       | 69.5       | 0.0       | 5.2            |                         |                         | 0.4     | 0.0          | 127.4                | 127.6               | -4.73                        | -4.85                       |                        |                       | 5.079                        | 4.839                       | -4.98                     | -5.28                        | 28.41                  | 1356         | 34.4334952 | -118.6471935 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)                                                                       |
| CV-24165   | 8/19/2026 9:11:07 AM  | 34.7       | 65.3       | 0.0       | 0.0            |                         |                         | 0.5     | 0.0          | 135.8                | 135.7               | -0.81                        | -0.26                       |                        |                       | 0.811                        | 0.473                       | -1.35                     | -1.23                        | 28.53                  | 1387         | 34.4335232 | -118.6472685 | Valve Adjustment:NSPS/EG CAI,High Temp;Well Comment:pump is active;Well Condition:Lorentz Pump Installed                                                        |
| CV-24165   | 8/19/2026 9:12:19 AM  | 31.0       | 64.5       | 0.0       | 4.5            |                         |                         | 0.5     | 0.0          | 135.9                | 135.8               | -1.10                        | -1.28                       |                        |                       | 1.144                        | 1.346                       | -2.02                     | -1.64                        | 28.53                  | 1386         | 34.4335212 | -118.6472782 | Valve Adjustment:High Temp,Surging Liquid in Header;Well Condition:Lorentz Pump Installed                                                                       |
| CV-24165   | 8/21/2026 9:48:04 AM  | 28.8       | 67.0       | 0.0       | 4.2            |                         |                         | 0.4     | 0.0          | 125.8                | 126.1               | -4.71                        | -4.80                       |                        |                       | 4.678                        | 4.775                       | -4.96                     | -5.05                        | 28.56                  | 1394         | 34.4335407 | -118.6472152 | Valve Adjustment:Barely Open                                                                                                                                    |
| CV-24166   | 8/4/2026 1:01:21 PM   | 15.8       | 13.8       | 14.2      | 56.2           |                         |                         | 1.1     | 4.0          | 118.1                | 117.9               | -4.81                        | -4.81                       |                        |                       | 4.789                        | 4.828                       | -6.20                     | -6.22                        | 28.41                  | 1382         | 34.4336158 | -118.6468562 | Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:Well construction uneven cant reach valve handle |
| CV-24166   | 8/4/2026 1:03:07 PM   | 35.7       | 28.7       | 7.2       | 28.4           |                         |                         | 1.2     | 3.9          | 117.4                | 117.1               | -4.73                        | -4.73                       |                        |                       | 5.057                        | 5.005                       | -6.54                     | -6.33                        | 28.41                  | 1384         | 34.4336162 | -118.6468365 | Valve Adjustment:Barely Open                                                                                                                                    |
| CV-24166   | 8/16/2026 1:21:55 PM  | 51.8       | 42.5       | 0.0       | 5.7            |                         |                         | 1.2     | 0.0          | 110.0                | 109.9               | -4.31                        | -4.08                       |                        |                       | 4.392                        | 4.139                       | -5.92                     | -5.24                        | 28.63                  | 1375         | 34.4336383 | -118.6469472 | Well Condition:Lorentz Pump Installed                                                                                                                           |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init<br>Flow<br>[scfm] | Adj<br>Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                                 |
|------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|------------------------|-----------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|------------------------------------------------------------------------------------------------------------------------------------------|
| CV-24167   | 8/12/2026 8:55:22 AM  | 46.4       | 39.8       | 0.0       | 13.8           |                         |                         | 1.2     | 0.0          | 113.9                | 114.0               | -4.97                        | -5.05                       |                        |                       | 5.172                        | 5.228                       | -10.36                    | -11.20                       | 28.51                  | 1388         | 34.4334538 | -118.6464995 | Valve Adjustment:Barely Open                                                                                                             |
| CV-24167   | 8/16/2026 1:00:45 PM  | 46.6       | 38.1       | 0.0       | 15.4           |                         |                         | 1.2     | 0.0          | 115.6                | 115.7               | -3.14                        | -3.14                       |                        |                       | 3.157                        | 3.157                       | -6.29                     | -6.29                        | 28.65                  | 1392         | 34.4334882 | -118.6464725 | Well Condition:Lorentz Pump Installed                                                                                                    |
| CV-24168   | 8/4/2026 1:35:34 PM   | 24.2       | 54.6       | 0.2       | 21.0           |                         |                         | 0.4     | 105.0        | 95.6                 | 92.3                | -4.79                        | -3.96                       |                        |                       | 5.177                        | 3.940                       | -5.77                     | -6.03                        | 28.41                  | 1358         | 34.4332863 | -118.6472965 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                   |
| CV-24168   | 8/21/2026 9:41:47 AM  | 21.5       | 71.7       | 0.0       | 6.8            |                         |                         | 0.3     | 0.0          | 141.0                | 141.0               | -2.56                        | -1.69                       |                        |                       | 2.523                        | 1.668                       | -4.57                     | -5.06                        | 28.56                  | 1385         | 34.4333312 | -118.6473187 | Valve Adjustment: NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header;Well Condition:Lorentz Pump Installed |
| CV-24168   | 8/21/2026 9:42:18 AM  | 21.0       | 73.4       | 0.2       | 5.4            |                         |                         | 0.3     | 27.0         | 141.0                | 89.8                | -1.65                        | -1.60                       |                        |                       | 1.627                        | 1.592                       | -5.23                     | -5.15                        | 28.57                  | 1399         | 34.4333113 | -118.6472870 | Valve Adjustment:High Temp,Barely Open;Well Condition:Lorentz Pump Installed                                                             |
| CV-24169   | 8/4/2026 1:38:18 PM   | 29.5       | 38.3       | 0.3       | 31.9           |                         |                         | 0.8     | 106.3        | 116.8                | 116.6               | -4.03                        | -3.62                       |                        |                       | 4.016                        | 3.588                       | -13.41                    | -13.55                       | 28.42                  | 1375         | 34.4332112 | -118.6476950 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open                                                                                       |
| CV-24169   | 8/18/2026 2:00:47 PM  | 34.6       | 43.5       | 0.2       | 21.7           |                         |                         | 0.8     | 108.5        | 115.3                | 115.3               | -2.91                        | -2.91                       |                        |                       | 2.900                        | 2.876                       | -13.18                    | -13.16                       | 28.52                  | 1388         | 34.4332092 | -118.6477405 | Valve Adjustment:Surging Liquid in Header;Surging Liquid in Well (Watered In)                                                            |
| CV-24170   | 8/6/2026 10:25:18 AM  | 18.0       | 73.8       | 0.1       | 8.1            |                         |                         | 0.2     | 81.0         | 134.8                | 135.0               | -2.77                        | -2.56                       | 9.0                    | 8.9                   | 0.053                        | 0.052                       | -15.08                    | -14.66                       | 28.58                  | 1366         | 34.4331335 | -118.6485040 | Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open;Surging Liquid in Header;Surging Liquid in Well (Watered In)                |
| CV-24170   | 8/6/2026 10:25:54 AM  | 17.3       | 76.6       | 0.3       | 5.8            |                         |                         | 0.2     | 19.3         | 134.7                | 134.8               | -2.49                        | -2.49                       | 0.0                    | 2.1                   | 0.000                        | 0.003                       | -14.68                    | -14.51                       | 28.57                  | 1367         | 34.4331348 | -118.6484970 | Valve Adjustment:High Temp;Surging Liquid in Header;Surging Liquid in Well (Watered In)                                                  |
| CV-24170   | 8/17/2026 11:25:45 AM | 10.3       | 81.8       | 0.0       | 7.9            |                         |                         | 0.1     | 0.0          | 131.4                | 130.9               | -0.68                        | -0.57                       | 41.3                   | 45.0                  | 0.429                        | 0.510                       | -4.38                     | -4.16                        | 28.66                  | 1359         | 34.4331055 | -118.6485215 | Valve Adjustment: NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open                                                                |
| CV-24170   | 8/17/2026 11:26:08 AM | 10.5       | 82.0       | 0.0       | 7.5            |                         |                         | 0.1     | 0.0          | 130.7                | 130.5               | -0.28                        | -0.35                       | 30.8                   | 34.4                  | 0.239                        | 0.298                       | -3.42                     | -4.29                        | 28.66                  | 1358         | 34.4331182 | -118.6485140 | Valve Adjustment: NSPS/EG CAI,High Temp                                                                                                  |
| CV-24171   | 8/4/2026 3:41:15 PM   | 52.3       | 45.6       | 0.1       | 2.0            |                         |                         | 1.1     | 20.0         | 128.6                | 128.7               | -0.82                        | -0.80                       | 18.2                   | 19.6                  | 0.443                        | 0.512                       | 0.86                      | 0.86                         | 28.41                  | 1385         | 34.4331952 | -118.6466515 | Valve Adjustment:Barely Open                                                                                                             |
| CV-24171   | 8/16/2026 2:02:07 PM  | 51.6       | 43.6       | 0.0       | 4.8            |                         |                         | 1.2     | 0.0          | 129.4                | 129.4               | -0.27                        | -0.25                       | 15.9                   | 15.5                  | 0.332                        | 0.317                       | -6.62                     | -6.37                        | 28.64                  | 1379         | 34.4331530 | -118.6466563 |                                                                                                                                          |
| CV-24171   | 8/16/2026 2:04:44 PM  | 51.2       | 44.0       | 0.0       | 4.8            |                         |                         | 1.2     | 0.0          | 129.3                | 129.3               | -0.23                        | -0.21                       | 15.8                   | 15.4                  | 0.591                        | 0.557                       | -6.93                     | -6.39                        | 28.64                  | 1377         | 34.4331817 | -118.6466665 | Valve Adjustment:Orifice Plate Changed (See OP Log);Well Repairs:Sample Port                                                             |
| CV-24171   | 8/24/2026 10:05:21 AM | 54.1       | 44.6       | 0.0       | 1.3            |                         |                         | 1.2     | 0.0          | 130.1                | 130.1               | -1.06                        | -1.02                       | 20.3                   | 20.8                  | 0.546                        | 0.573                       | -7.76                     | -7.46                        | 28.56                  | 1394         | 34.4331730 | -118.6466435 | Valve Adjustment:Barely Open;Well Condition:Lorentz Pump Installed                                                                       |
| CV-24172   | 8/4/2026 3:58:35 PM   | 39.0       | 36.9       | 3.7       | 20.4           |                         |                         | 1.1     | 5.5          | 125.2                | 125.2               | -0.23                        | -0.23                       | 7.9                    | 8.6                   | 0.174                        | 0.202                       | -8.86                     | -8.92                        | 28.41                  | 1383         | 34.4329643 | -118.6472762 | Valve Adjustment:Barely Open                                                                                                             |
| CV-24172   | 8/24/2026 10:12:15 AM | 46.0       | 39.3       | 2.1       | 12.6           |                         |                         | 1.2     | 6.0          | 127.1                | 127.2               | -0.16                        | -0.14                       | 7.2                    | 6.8                   | 0.142                        | 0.128                       | -8.17                     | -8.09                        | 28.58                  | 1397         | 34.4329767 | -118.6472933 | Valve Adjustment:Barely Open                                                                                                             |
| CV-24173   | 8/4/2026 4:05:28 PM   | 21.6       | 72.9       | 0.1       | 5.4            |                         |                         | 0.3     | 54.0         | 0.0                  | 0.0                 | -0.53                        | -0.54                       | 15.4                   | 16.6                  | 0.438                        | 0.511                       | 0.86                      | 0.88                         | 28.41                  | 1375         | 34.4328865 | -118.6476670 | Valve Comment:well construction needs backfill cant get a proper read                                                                    |
| CV-24173   | 8/24/2026 10:16:24 AM | 15.1       | 80.5       | 0.0       | 4.4            |                         |                         | 0.2     | 0.0          | 137.3                | 137.5               | -0.45                        | -0.46                       | 13.6                   | 13.4                  | 0.445                        | 0.430                       | 0.31                      | 0.31                         | 28.59                  | 1391         | 34.4329012 | -118.6476512 | Valve Comment:well construction too tall;Valve Adjustment: NSPS/EG CAI,High Temp,Barely Open                                             |
| CV-24173   | 8/24/2026 10:17:40 AM | 15.0       | 82.4       | 0.1       | 2.5            |                         |                         | 0.2     | 25.0         | 137.6                | 137.5               | -0.46                        | -0.43                       | 13.2                   | 13.1                  | 0.421                        | 0.412                       | 0.35                      | 0.34                         | 28.58                  | 1393         | 34.4328943 | -118.6476492 | Valve Adjustment:High Temp,Barely Open                                                                                                   |
| CV-24174   | 8/10/2026 2:24:04 PM  | 12.8       | 69.2       | 0.0       | 18.1           |                         |                         | 0.2     | 0.0          | 111.6                | 111.6               | -0.31                        | -0.30                       |                        |                       | 0.356                        | 0.334                       | -9.10                     | -9.05                        | 28.56                  | 1391         | 34.4327052 | -118.6480372 | Well Condition:Lorentz Pump Installed                                                                                                    |
| CV-24174   | 8/28/2026 1:03:44 PM  | 10.8       | 77.5       | 0.0       | 11.7           |                         |                         | 0.1     | 0.0          | 121.1                | 126.4               | 0.20                         | -0.02                       |                        |                       | 0.000                        | 0.000                       | -6.07                     | -6.02                        | 28.59                  | 1395         | 34.4326948 | -118.6480358 | Valve Adjustment: NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open                                                   |
| CV-24174   | 8/28/2026 1:04:34 PM  | 10.9       | 78.7       | 0.0       | 10.4           |                         |                         | 0.1     | 0.0          | 126.9                | 126.9               | -0.02                        | -0.05                       |                        |                       | 0.000                        | 0.000                       | -5.76                     | -5.76                        | 28.6                   | 1388         | 34.4326918 | -118.6480515 | Valve Adjustment:Barely Open;Surging Liquid in Header;Surging Liquid in Well (Watered In)                                                |
| CV-24175   | 8/4/2026 4:13:24 PM   | 16.0       | 80.7       | 0.2       | 3.1            |                         |                         | 0.2     | 15.5         | 121.1                | 121.8               | 0.05                         | -0.04                       | 4.1                    | 5.9                   | 0.045                        | 0.094                       | -8.90                     | -8.86                        | 28.41                  | 1352         | 34.4326513 | -118.6484908 | Valve Adjustment: NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum                                                               |
| CV-24175   | 8/4/2026 4:14:20 PM   | 15.7       | 83.2       | 0.2       | 0.9            |                         |                         | 0.2     | 4.5          | 122.5                | 122.4               | -0.12                        | -0.10                       | 5.7                    | 5.2                   | 0.090                        | 0.075                       | -9.01                     | -8.69                        | 28.42                  | 1353         | 34.4326457 | -118.6484862 | Valve Adjustment: NSPS/EG CAC,Barely Open;Surging Liquid in Header                                                                       |
| CV-24175   | 8/21/2026 9:30:19 AM  | 14.2       | 85.8       | 0.0       | 0.0            |                         |                         | 0.2     | 0.0          | 121.4                | 122.3               | -0.08                        | -0.08                       | 5.9                    | 5.1                   | 0.093                        | 0.072                       | -7.48                     | -7.63                        | 28.6                   | 1374         | 34.4326847 | -118.6484728 | Valve Adjustment:Barely Open                                                                                                             |
| CV-24176   | 8/10/2026 1:58:59 PM  | 36.2       | 54.7       | 0.0       | 9.1            |                         |                         | 0.7     | 0.0          | 112.1                | 112.1               | -0.19                        | -0.20                       | 27.5                   | 27.2                  | 0.476                        | 0.468                       | -0.57                     | -0.85                        | 28.6                   | 1346         | 34.4326230 | -118.6488628 | Well Comment:pump is active;Well Condition:Lorentz Pump Installed                                                                        |
| CV-24176   | 8/27/2026 11:41:37 AM | 31.6       | 58.7       | 0.0       | 9.7            |                         |                         | 0.5     | 0.0          | 108.9                | 108.9               | 0.18                         | 0.22                        | 2.3                    | 0.9                   | 0.016                        | 0.002                       | 0.15                      |                              | 28.56                  | 1312         | 34.4326275 | -118.6488987 | NSPS/EG CAI,Positive Static Press.                                                                                                       |
| CV-24176   | 8/27/2026 11:43:13 AM | 30.1       | 64.5       | 0.0       | 5.4            |                         |                         | 0.5     | 0.0          | 109.1                | 109.1               | 0.18                         | 0.19                        | 0.0                    | 0.0                   | -0.006                       | -0.006                      | 0.19                      |                              | 28.56                  | 1342         | 34.4325987 | -118.6490162 | NSPS/EG CAI,Positive Static Press.                                                                                                       |
| CV-24177   | 8/3/2026 9:50:11 AM   | 8.6        | 73.0       | 1.1       | 17.2           |                         |                         | 0.1     | 15.4         | 128.9                | 128.9               | -0.23                        | -0.23                       |                        |                       | 0.223                        | 0.221                       | -14.97                    | -15.10                       | 28.49                  | 1320         | 34.4322622 | -118.6494637 | Valve Adjustment:Barely Open;Well Condition:Lorentz Pump Installed                                                                       |
| CV-24177   | 8/17/2026 9:36:14 AM  | 8.4        | 71.6       | 1.9       | 18.1           |                         |                         | 0.1     | 9.5          | 137.2                | 137.2               | -0.24                        | -0.22                       |                        |                       | 0.239                        | 0.229                       | -16.72                    | -13.48                       | 28.69                  | 1308         | 34.4322465 | -118.6494577 | Valve Adjustment: NSPS/EG CAI,High Temp,Barely Open                                                                                      |
| CV-24177   | 8/17/2026 9:36:29 AM  | 8.5        | 73.9       | 1.9       | 15.7           |                         |                         | 0.1     | 8.3          | 138.0                | 138.2               | -0.22                        | -0.22                       |                        |                       | 0.216                        | 0.220                       | -13.52                    | -16.21                       | 28.69                  | 1308         | 34.4322468 | -118.6494465 | Valve Adjustment: NSPS/EG CAI,High Temp                                                                                                  |
| CV-24178   | 8/10/2026 1:37:56 PM  | 27.1       | 62.0       | 0.0       | 10.9           |                         |                         | 0.4     | 0.0          | 120.7                | 132.3               | 0.59                         | -0.17                       | 2.3                    | 1.9                   | 0.015                        | 0.010                       | -1.23                     | -0.25                        | 28.6                   | 1361         | 34.4323785 | -118.6486075 | Valve Adjustment: NSPS/EG CAI,NSPS/EG CAC,High Temp,Positive Static Press.,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed   |
| CV-24178   | 8/10/2026 1:39:20 PM  | 28.1       | 60.9       | 0.0       | 11.0           |                         |                         | 0.5     | 0.0          | 132.8                | 132.6               | -0.13                        | -0.13                       |                        |                       | 0.076                        | 0.076                       | -0.22                     | -0.22                        | 28.61                  | 1356         | 34.4323502 | -118.6485853 | Valve Adjustment:High Temp,Valve 100% Open;Well Condition:Lorentz Pump Installed                                                         |
| CV-24178   | 8/12/2026 8:35:00 AM  | 37.9       | 43.3       | 0.0       | 18.8           |                         |                         | 0.9     | 0.0          | 132.7                | 131.9               | -4.95                        | -2.83                       | 48.3                   | 19.3                  | 6.621                        | 1.040                       | -10.38                    | -10.41                       | 28.56                  | 1366         | 34.4323897 | -118.6485842 | Valve Adjustment: NSPS/EG CAI,Orifice Plate Changed (See OP Log),High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed   |
| CV-24178   | 8/12/2026 8:37:27 AM  | 36.3       | 43.4       | 0.0       | 20.2           |                         |                         | 0.8     | 0.0          | 132.4                | 132.5               | -2.63                        | -2.63                       | 22.2                   | 21.9                  | 1.383                        | 1.344                       | -10.81                    | -10.67                       | 28.57                  | 1379         | 34.4323628 | -118.6485775 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                                                                         |
| CV-24178   | 8/19/2026 1:50:28 PM  | 34.7       | 65.2       | 0.1       | 0.0            |                         |                         | 0.5     | 0.0          | 131.8                | 132.1               | 0.16                         | -0.07                       | 15.4                   | 0.4                   | 0.655                        | 0.001                       | 0.07                      | 0.06                         | 28.49                  | 1365         | 34.4323690 | -118.6485947 | Valve Adjustment: NSPS/EG CAI,High Temp,High O2,Barely Open                                                                              |
| CV-24178   | 8/19/2026 1:54:18 PM  | 31.5       | 56.2       | 0.2       | 12.1           |                         |                         | 0.6     | 60.5         | 132.3                | 132.4               | -0.06                        | -0.09                       | 6.7                    | 1.5                   | 0.123                        | 0.006                       | 0.09                      | 0.09                         | 30                     | 1366         | 34.4323873 | -118.6485520 | Valve Adjustment:High Temp,Barely Open                                                                                                   |
| CV-24179   | 8/3/2026 10:01:58 AM  | 26.2       | 51.9       | 0.0       | 21.9           |                         |                         | 0.5     | 0.0          | 133.5                | 132.9               | -0.52                        | -0.45                       | 4.4                    | 4.7                   | 0.054                        | 0.061                       | -15.60                    | -15.12                       | 28.48                  | 1314         | 34.4320850 | -118.6492093 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                   |
| CV-24179   | 8/3/2026 10:03:37 AM  | 25.6       | 53.0       | 0.0       | 21.4           |                         |                         | 0.5     | 0.0          | 132.0                | 131.9               | -0.41                        | -0.41                       | 1.5                    | 2.7                   | 0.006                        | 0.020                       | -9.26                     | -9.11                        | 28.46                  | 1328         | 34.4321012 | -118.6492287 | Valve Adjustment: NSPS/EG CAI,High Temp,Barely Open                                                                                      |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init Flow<br>[scfm] | Adj Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                     |
|------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|---------------------|--------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|------------------------------------------------------------------------------|
| CV-24179   | 8/17/2026 10:23:35 AM | 21.0       | 52.2       | 0.0       | 26.8           |                         |                         | 0.4     | 0.0          | 131.1                | 131.0               | -0.43                        | -0.44                       | 3.7                 | 4.6                | 0.038                        | 0.057                       | -13.65                    | -16.07                       | 28.68                  | 1322         | 34.4321057 | -118.6491953 | Valve Adjustment:High Temp,Barely Open                                       |
| CV-24179   | 8/17/2026 10:24:05 AM | 20.8       | 52.5       | 0.0       | 26.7           |                         |                         | 0.4     | 0.0          | 131.1                | 131.1               | -0.44                        | -0.44                       | 3.6                 | 5.2                | 0.036                        | 0.076                       | -13.68                    | -16.15                       | 28.68                  | 1323         | 34.4321003 | -118.6491947 |                                                                              |
| CV-24180   | 8/10/2026 1:21:22 PM  | 20.3       | 63.9       | 0.0       | 15.8           |                         |                         | 0.3     | 790.5        | 115.5                | 115.5               | -0.08                        | -0.07                       | 4.8                 | 2.0                | 0.062                        | 0.011                       | -1.28                     | -1.34                        | 28.61                  | 1365         | 34.4321270 | -118.6488098 | Valve Adjustment:Barely Open;Well Condition:Pnumatic Pump Installed          |
| CV-24180   | 8/27/2026 11:50:28 AM | 16.6       | 74.8       | 0.7       | 7.9            |                         |                         | 0.2     | 11.3         | 102.8                | 102.8               | 0.41                         | 0.40                        | 0.0                 | 0.3                | -0.002                       | 0.000                       | 0.39                      |                              | 28.54                  | 1283         | 34.4321233 | -118.6487665 | NSPS/EG CAI,Positive Static Press.                                           |
| CV-24180   | 8/27/2026 11:51:10 AM | 16.7       | 75.9       | 0.9       | 6.5            |                         |                         | 0.2     | 7.2          | 102.6                | 102.8               | 0.32                         | 0.33                        | 0.0                 | 0.0                | -0.021                       | -0.012                      | 0.34                      |                              | 28.54                  | 1266         | 34.4321597 | -118.6487425 | NSPS/EG CAI,Positive Static Press.                                           |
| CV-24181   | 8/10/2026 1:14:12 PM  | 28.8       | 55.8       | 0.0       | 15.4           |                         |                         | 0.5     | 0.0          | 111.5                | 111.6               | -0.16                        | -0.13                       | 1.1                 | 1.0                | 0.139                        | 0.104                       | -1.30                     | -1.07                        | 28.6                   | 1374         | 34.4321822 | -118.6484215 |                                                                              |
| CV-24181   | 8/21/2026 7:47:46 AM  | 41.0       | 46.5       | 0.0       | 12.5           |                         |                         | 0.9     | 0.0          | 114.9                | 114.9               | -1.34                        | -1.35                       |                     |                    | 0.000                        | 0.000                       | -5.86                     | -10.26                       | 28.61                  | 1342         | 34.4321602 | -118.6483900 | Valve Adjustment:Barely Open                                                 |
| CV-24182   | 8/10/2026 12:50:34 PM | 39.9       | 40.4       | 0.0       | 19.7           |                         |                         | 1.0     | 0.0          | 117.6                | 119.0               | -2.86                        | -2.84                       |                     |                    | 2.867                        | 2.832                       | -8.59                     | -8.34                        | 28.61                  | 1373         | 34.4322315 | -118.6480925 |                                                                              |
| CV-24182   | 8/21/2026 8:39:04 AM  | 36.2       | 49.3       | 0.0       | 14.5           |                         |                         | 0.7     | 0.0          | 122.1                | 121.8               | -3.53                        | -3.51                       |                     |                    | 3.515                        | 3.498                       | -8.21                     | -8.09                        | 28.6                   | 1350         | 34.4322817 | -118.6480333 | Valve Adjustment:Surging Liquid in Header                                    |
| CV-24183   | 8/5/2026 9:12:37 AM   | 41.2       | 30.6       | 1.6       | 26.6           |                         |                         | 1.3     | 16.6         | 92.2                 | 92.4                | -0.70                        | -0.62                       | 0.0                 | 0.0                | 0.507                        | 0.508                       | -11.29                    |                              | 28.58                  | 1335         | 34.4323737 | -118.6476603 |                                                                              |
| CV-24183   | 8/21/2026 8:04:55 AM  | 28.9       | 28.9       | 4.8       | 37.4           |                         |                         | 1.0     | 7.8          | 85.3                 | 86.1                | -0.66                        | -0.66                       |                     |                    | 0.643                        | 0.642                       | -9.61                     | -9.13                        | 28.61                  | 1363         | 34.4323520 | -118.6476490 | Valve Adjustment:Barely Open                                                 |
| CV-24184   | 8/5/2026 9:22:19 AM   | 15.8       | 17.6       | 9.5       | 57.1           |                         |                         | 0.9     | 6.0          | 118.7                | 120.1               | -0.13                        | -0.01                       | 1.3                 | 1.8                | 0.032                        | 0.066                       | -11.16                    |                              | 28.54                  | 1345         | 34.4325760 | -118.6472463 | NSPS/EG CAI,High O2                                                          |
| CV-24184   | 8/5/2026 9:25:59 AM   | 16.3       | 17.4       | 9.3       | 57.0           |                         |                         | 0.9     | 6.1          | 121.0                | 121.8               | -0.01                        | -0.01                       | 3.5                 | 3.5                | 0.252                        | 0.252                       | -10.84                    |                              | 28.54                  | 1362         | 34.4324853 | -118.6472407 | NSPS/EG CAI,High O2,No Adjustment Made                                       |
| CV-24184   | 8/21/2026 8:09:35 AM  | 40.9       | 35.4       | 0.3       | 23.4           |                         |                         | 1.2     | 78.0         | 105.2                | 117.8               | -0.02                        | -0.12                       | 1.6                 | 4.3                | 0.055                        | 0.385                       | -9.48                     | -9.50                        | 28.61                  | 1357         | 34.4325342 | -118.6472643 | Valve Adjustment:Increased Flow/Vacuum,Barely Open                           |
| CV-24185   | 8/13/2026 1:54:21 PM  | 50.4       | 45.6       | 0.0       | 4.0            |                         |                         | 1.1     | 0.0          | 124.6                | 124.6               | -0.29                        | -0.29                       | 14.9                | 15.4               | 0.612                        | 0.652                       | -12.45                    | -12.07                       | 28.56                  | 1358         | 34.4326797 | -118.6469612 | Well Condition:Lorentz Pump Installed                                        |
| CV-24185   | 8/21/2026 8:15:00 AM  | 47.4       | 52.4       | 0.0       | 0.2            |                         |                         | 0.9     | 0.0          | 124.9                | 124.7               | -0.32                        | -0.32                       | 14.5                | 15.3               | 0.577                        | 0.642                       | 0.20                      | 0.20                         | 28.61                  | 1367         | 34.4326795 | -118.6469515 | Valve Comment:well too tall                                                  |
| CV-24186   | 8/13/2026 1:49:55 PM  | 48.1       | 39.9       | 0.6       | 11.4           |                         |                         | 1.2     | 18.3         | 127.6                | 127.6               | -1.07                        | -1.06                       | 20.2                | 20.9               | 1.131                        | 1.207                       | -11.53                    | -11.88                       | 28.55                  | 1376         | 34.4328200 | -118.6465698 | Well Comment:pump is active;Well Condition:Lorentz Pump Installed            |
| CV-24186   | 8/31/2026 9:16:19 AM  | 51.3       | 46.3       | 0.0       | 2.4            |                         |                         | 1.1     | 0.0          | 125.0                | 125.0               | -0.74                        | -0.73                       | 33.6                | 33.7               | 0.727                        | 0.730                       | -6.90                     | -6.90                        | 28.52                  | 1368         | 34.4328255 | -118.6465488 | Valve Adjustment:Barely Open                                                 |
| CV-24187   | 8/3/2026 9:44:41 AM   | 48.5       | 46.7       | 0.0       | 4.8            |                         |                         | 1.0     | 0.0          | 127.8                | 127.9               | -0.37                        | -0.38                       | 2.6                 | 3.6                | 0.018                        | 0.036                       | -15.44                    | -15.27                       | 28.49                  | 1294         | 34.4318513 | -118.6495813 | Valve Adjustment:Plugged/Pinched Suspected                                   |
| CV-24187   | 8/17/2026 8:53:01 AM  | 48.0       | 45.5       | 0.0       | 6.5            |                         |                         | 1.1     | 0.0          | 127.2                | 127.3               | -0.54                        | -0.54                       | 9.7                 | 9.7                | 0.257                        | 0.256                       | -16.00                    | -15.82                       | 28.69                  | 1292         | 34.4318807 | -118.6495567 |                                                                              |
| CV-24188   | 8/3/2026 9:14:22 AM   | 48.7       | 43.1       | 0.0       | 8.2            |                         |                         | 1.1     | 0.0          | 88.6                 | 89.7                | -4.54                        | -4.51                       | 15.7                | 15.2               | 0.644                        | 0.606                       | -15.51                    | -15.55                       | 28.55                  | 1257         | 34.4314960 | -118.6501335 | Valve Adjustment:Decreased Flow/Vacuum                                       |
| CV-24188   | 8/3/2026 9:17:05 AM   | 47.6       | 44.5       | 0.0       | 7.9            |                         |                         | 1.1     | 0.0          | 89.0                 | 94.1                | -4.10                        | -4.09                       | 13.9                | 13.8               | 0.502                        | 0.501                       | -15.47                    | -15.18                       | 28.54                  | 1253         | 34.4315203 | -118.6501482 |                                                                              |
| CV-24188   | 8/3/2026 9:19:03 AM   | 47.1       | 44.0       | 0.0       | 8.9            |                         |                         | 1.1     | 0.0          | 119.5                | 119.5               | -4.01                        | -4.00                       | 13.7                | 13.8               | 0.516                        | 0.526                       | -15.44                    | -15.44                       | 28.54                  | 1251         | 34.4315202 | -118.6501208 | Valve Comment:Previous reads had temp probe disconnected                     |
| CV-24188   | 8/31/2026 8:50:09 AM  | 51.7       | 45.9       | 0.0       | 2.4            |                         |                         | 1.1     | 0.0          | 119.5                | 119.6               | -3.02                        | -3.02                       | 12.6                | 12.1               | 0.436                        | 0.399                       | -13.18                    | -13.13                       | 28.64                  | 1254         | 34.4315103 | -118.6501188 | Valve Adjustment:Surging Liquid in Header                                    |
| CV-24189   | 8/3/2026 9:09:02 AM   | 48.0       | 39.3       | 1.8       | 11.0           |                         |                         | 1.2     | 6.2          | 116.5                | 116.1               | -0.62                        | -0.62                       | 4.9                 | 5.0                | 0.509                        | 0.528                       | -15.66                    | -15.60                       | 28.53                  | 1251         | 34.4313188 | -118.6500053 | Valve Comment:hole in ferroc                                                 |
| CV-24189   | 8/31/2026 8:54:24 AM  | 41.7       | 35.3       | 4.3       | 18.7           |                         |                         | 1.2     | 4.3          | 108.5                | 109.0               | -0.38                        | -0.42                       | 6.4                 | 4.2                | 0.838                        | 0.374                       | -11.59                    | -12.98                       | 28.64                  | 1261         | 34.4313047 | -118.6499988 | Valve Adjustment:Barely Open                                                 |
| CV-24190   | 8/3/2026 8:56:16 AM   | 49.6       | 43.9       | 0.2       | 6.2            |                         |                         | 1.1     | 32.8         | 124.0                | 124.1               | -4.85                        | -4.83                       | 21.0                | 20.3               | 1.223                        | 1.152                       | -15.59                    | -15.84                       | 28.48                  | 1305         | 34.4315957 | -118.6494732 | Valve Adjustment:Decreased Flow/Vacuum                                       |
| CV-24190   | 8/3/2026 8:56:58 AM   | 49.5       | 43.8       | 0.2       | 6.5            |                         |                         | 1.1     | 38.2         | 124.1                | 124.0               | -4.96                        | -4.96                       | 20.5                | 20.4               | 1.169                        | 1.158                       | -15.76                    | -15.77                       | 28.49                  | 1310         | 34.4315798 | -118.6494892 |                                                                              |
| CV-24190   | 8/17/2026 8:47:39 AM  | 50.4       | 44.1       | 0.0       | 5.5            |                         |                         | 1.1     | 0.0          | 123.2                | 123.0               | -3.32                        | -3.32                       | 14.9                | 14.9               | 0.607                        | 0.607                       | -13.41                    | -13.41                       | 28.68                  | 1305         | 34.4315863 | -118.6494770 |                                                                              |
| CV-24192   | 8/3/2026 9:00:24 AM   | 52.3       | 41.2       | 0.0       | 6.5            |                         |                         | 1.3     | 0.0          | 120.4                | 120.4               | -13.35                       | -13.13                      | 21.5                | 21.3               | 1.119                        | 1.101                       | -14.71                    | -14.81                       | 28.49                  | 1307         | 34.4313363 | -118.6495257 |                                                                              |
| CV-24192   | 8/3/2026 9:02:39 AM   | 51.1       | 42.1       | 0.0       | 6.8            |                         |                         | 1.2     | 0.0          | 120.3                | 120.3               | -13.43                       | -13.47                      | 20.9                | 21.9               | 0.591                        | 0.647                       | -14.70                    | -15.02                       | 28.5                   | 1303         | 34.4313288 | -118.6495250 | Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum    |
| CV-24192   | 8/3/2026 9:03:26 AM   | 50.7       | 42.3       | 0.0       | 7.0            |                         |                         | 1.2     | 0.0          | 120.4                | 120.3               | -13.66                       | -13.47                      | 22.2                | 22.0               | 0.668                        | 0.656                       | -14.85                    | -14.60                       | 28.5                   | 1299         | 34.4313268 | -118.6495108 |                                                                              |
| CV-24192   | 8/17/2026 8:37:01 AM  | 52.3       | 40.5       | 0.0       | 7.2            |                         |                         | 1.3     | 0.0          | 119.9                | 119.3               | -14.10                       | -12.99                      | 26.4                | 27.0               | 0.939                        | 0.975                       | -15.77                    | -14.70                       | 28.69                  | 1298         | 34.4313358 | -118.6494907 | Valve Adjustment:Increased Flow/Vacuum,Plugged/Pinched Suspected             |
| CV-24192   | 8/17/2026 8:39:20 AM  | 51.0       | 40.9       | 0.0       | 8.2            |                         |                         | 1.2     | 0.0          | 119.9                | 119.4               | -13.76                       | -12.65                      | 26.4                | 23.4               | 0.939                        | 0.735                       | -15.39                    | -13.89                       | 28.72                  | 1294         | 34.4313213 | -118.6494783 | Valve Adjustment:Plugged/Pinched Suspected                                   |
| CV-24193   | 8/11/2026 9:52:12 AM  | 57.7       | 42.3       | 0.0       | 0.0            |                         |                         | 1.4     | 0.0          | 119.8                | 119.9               | -11.67                       | -11.54                      | 15.0                | 14.7               | 0.300                        | 0.287                       | -15.02                    | -14.91                       | 28.68                  | 1323         | 34.4315065 | -118.6490723 | Valve Adjustment:Audible Flow                                                |
| CV-24193   | 8/17/2026 8:26:22 AM  | 51.4       | 40.7       | 0.0       | 7.9            |                         |                         | 1.3     | 0.0          | 119.1                | 118.9               | -10.67                       | -10.67                      | 20.4                | 20.5               | 0.553                        | 0.558                       | -14.02                    | -14.06                       | 28.68                  | 1325         | 34.4315102 | -118.6490617 |                                                                              |
| CV-24194   | 8/5/2026 10:06:33 AM  | 50.3       | 43.6       | 0.0       | 6.1            |                         |                         | 1.2     | 0.0          | 105.4                | 105.5               | -5.24                        | -5.21                       | 24.6                | 25.9               | 1.318                        | 1.450                       | -15.79                    |                              | 28.55                  | 1325         | 34.4318847 | -118.6484813 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less                          |
| CV-24194   | 8/18/2026 8:22:08 AM  | 51.0       | 43.7       | 0.0       | 5.3            |                         |                         | 1.2     | 0.0          | 104.6                | 104.7               | -4.88                        | -4.85                       | 3.6                 | 3.3                | 1.393                        | 1.164                       | -14.65                    | -13.29                       | 28.61                  | 1337         | 34.4318740 | -118.6485180 | Valve Adjustment:Orifice Plate Changed (See OP Log)                          |
| CV-24194   | 8/18/2026 8:28:55 AM  | 50.8       | 42.5       | 0.0       | 6.6            |                         |                         | 1.2     | 0.0          | 102.6                | 104.0               | -4.91                        | -5.09                       | 4.2                 | 5.2                | 1.934                        | 2.908                       | -14.57                    | -14.76                       | 28.61                  | 1343         | 34.4318753 | -118.6485123 | Valve Adjustment:Increased Flow/Vacuum                                       |
| CV-24194   | 8/18/2026 8:30:02 AM  | 51.1       | 43.4       | 0.0       | 5.5            |                         |                         | 1.2     | 0.0          | 104.9                | 104.9               | -5.75                        | -5.75                       | 4.7                 | 4.8                | 2.427                        | 2.439                       | -14.39                    | -14.54                       | 28.61                  | 1346         | 34.4318798 | -118.6485098 |                                                                              |
| CV-24194   | 8/26/2026 2:57:06 PM  | 49.8       | 46.4       | 0.0       | 3.8            |                         |                         | 1.1     | 0.0          | 115.6                | 115.6               | -4.60                        | -4.66                       | 3.3                 | 4.1                | 1.201                        | 1.861                       | -8.96                     | -11.11                       | 28.61                  | 1349         | 34.4318595 | -118.6484978 | Valve Adjustment:Increased Flow/Vacuum                                       |
| CV-24195   | 8/5/2026 10:12:44 AM  | 49.9       | 45.9       | 0.0       | 4.2            |                         |                         | 1.1     | 0.0          | 119.1                | 119.1               | -0.88                        | -0.87                       | 9.1                 | 9.6                | 1.768                        | 1.901                       | -15.82                    |                              | 28.55                  | 1345         | 34.4318558 | -118.6478618 | No Adjustment Made,                                                          |
| CV-24195   | 8/17/2026 1:37:16 PM  | 50.7       | 43.8       | 0.0       | 5.5            |                         |                         | 1.2     | 0.0          | 120.4                | 120.5               | -0.31                        | -0.33                       | 6.8                 | 7.2                | 0.991                        | 1.089                       | -9.55                     | -10.75                       | 28.64                  | 1339         | 34.4318105 | -118.6479140 |                                                                              |
| CV-24196   | 8/5/2026 9:38:10 AM   | 45.6       | 45.3       | 0.0       | 9.1            |                         |                         | 1.0     | 0.0          | 126.4                | 126.4               | -1.48                        | -1.46                       | 9.7                 | 9.8                | 0.120                        | 0.120                       | -16.21                    |                              | 28.56                  | 1352         | 34.4320338 | -118.6471398 |                                                                              |
| CV-24196   | 8/17/2026 2:02:50 PM  | 47.1       | 46.4       | 0.0       | 6.5            |                         |                         | 1.0     | 0.0          | 125.9                | 125.8               | -0.97                        | -0.96                       | 6.8                 | 7.7                | 0.061                        | 0.078                       | -12.58                    | -11.82                       | 28.64                  | 1338         | 34.4320542 | -118.6472315 |                                                                              |
| CV-24197   | 8/13/2026 1:43:21 PM  | 51.7       | 42.9       | 0.0       | 5.5            |                         |                         | 1.2     | 0.0          | 126.2                | 126.2               | -1.01                        | -1.10                       | 19.3                | 20.0               | 1.025                        | 1.099                       | -12.35                    | -12.12                       | 28.57                  | 1329         | 34.4323582 | -118.6465998 | Valve Adjustment:Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed |
| CV-24197   | 8/13/2026 1:43:59 PM  | 51.2       | 43.1       | 0.0       | 5.7            |                         |                         | 1.2     | 0.0          | 126.3                | 126.2               | -1.12                        | -1.13                       | 20.7                | 20.8               | 1.184                        | 1.187                       | -12.01                    | -11.98                       | 28.58                  | 1341         | 34.4323597 | -118.6465987 | Well Condition:Lorentz Pump Installed                                        |
| CV-24197   | 8/25/2026 1:19:32 PM  | 49.3       | 45.3       | 0.1       | 5.3            |                         |                         | 1.1     | 53.0         | 129.1                | 129                 |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                              |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init Temp<br>[°F] | Adj Temp<br>[°F] | Init Stat Press<br>[\"H2O] | Adj Stat Press<br>[\"H2O] | Init Flow<br>[scfm] | Adj Flow<br>[scfm] | Init Diff Press<br>[\"H2O] | Adj Diff Press<br>[\"H2O] | Sys Pressure<br>[\"H2O] | Adj Avail Press<br>[\"H2O] | Baro Press<br>[\"Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                                             |                     |
|------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|-------------------|------------------|----------------------------|---------------------------|---------------------|--------------------|----------------------------|---------------------------|-------------------------|----------------------------|----------------------|--------------|------------|--------------|------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------|
| CV-24198   | 8/17/2026 1:51:27 PM  | 53.4       | 41.6       | 0.0       | 5.0            |                         |                         | 1.3     | 0.0          | 124.7             | 124.7            | -0.23                      | -0.23                     | 8.9                 | 8.9                | 0.507                      | 0.507                     | -16.79                  | -16.79                     | 28.67                | 1341         | 34.4315583 | -118.6476152 | Valve Adjustment:Barely Open                                                                                                                         |                     |
| CV-24198   | 8/25/2026 1:28:32 PM  | 53.7       | 42.3       | 0.0       | 4.0            |                         |                         | 1.3     | 0.0          | 127.5             | 127.4            | -0.36                      | -0.34                     | 5.6                 | 5.8                | 0.674                      | 0.735                     | -6.55                   | -6.58                      | 28.52                | 1356         | 34.4328530 | -118.6456753 | Valve Adjustment:Barely Open;Well Condition:Lorentz Pump Installed                                                                                   |                     |
| CV-24199   | 8/5/2026 9:47:51 AM   | 45.3       | 39.8       | 0.0       | 14.9           |                         |                         | 1.1     | 0.0          | 128.4             | 128.4            | -0.83                      | -0.81                     |                     | 21.3               | 22.6                       | 0.556                     | 0.623                   | -19.67                     |                      | 28.57        | 1339       | 34.4317857   | -118.6472672                                                                                                                                         | No Adjustment Made, |
| CV-24199   | 8/10/2026 8:15:00 AM  |            |            |           |                |                         | 0                       |         |              |                   |                  |                            |                           |                     |                    |                            |                           |                         |                            |                      |              |            |              | AirTech Lab; [User entered 0%]                                                                                                                       |                     |
| CV-24199   | 8/17/2026 1:57:26 PM  | 44.8       | 39.8       | 1.0       | 14.4           |                         |                         | 1.1     | 14.6         | 128.1             | 128.0            | -0.82                      | -0.82                     | 20.2                | 20.7               | 0.540                      | 0.565                     | -16.78                  | -16.13                     | 28.65                | 1339         | 34.4317697 | -118.6473375 |                                                                                                                                                      |                     |
| CV-24200   | 8/13/2026 2:30:25 PM  | 52.0       | 40.8       | 0.0       | 7.3            |                         |                         | 1.3     | 0.0          | 120.5             | 120.5            | -0.55                      | -0.55                     | 14.2                | 14.2               | 1.292                      | 1.289                     | -16.37                  | -16.38                     | 28.63                | 1283         | 34.4314620 | -118.6472298 |                                                                                                                                                      |                     |
| CV-24200   | 8/31/2026 1:45:48 PM  | 39.1       | 38.4       | 1.4       | 21.1           |                         |                         | 1.0     | 15.1         | 127.6             | 127.5            | -1.66                      | -2.13                     | 20.0                | 24.0               | 2.601                      | 3.767                     | -13.64                  | -13.82                     | 28.57                | 1321         | 34.4315723 | -118.6475930 |                                                                                                                                                      |                     |
| CV-24201   | 8/5/2026 11:02:26 AM  | 46.8       | 44.2       | 0.8       | 8.2            |                         |                         | 1.1     | 10.3         | 103.2             | 103.6            | -0.04                      | -0.10                     | 0.0                 | 0.0                | -0.417                     | -0.391                    |                         |                            | 28.64                | 1266         | 34.4317473 | -118.6466247 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less                                                                                                  |                     |
| CV-24201   | 8/27/2026 9:50:52 AM  | 52.8       | 43.9       | 0.0       | 3.3            |                         |                         | 1.2     | 0.0          | 104.0             | 113.2            | -0.10                      | -0.78                     | 1.8                 | 8.0                | 0.008                      | 0.170                     | -15.17                  | -14.97                     | 28.58                | 1279         | 34.4317398 | -118.6466372 | Valve Adjustment:Increased Flow/Vacuum,Barely Open                                                                                                   |                     |
| CV-24202   | 8/5/2026 10:49:39 AM  | 15.6       | 27.5       | 2.3       | 54.6           |                         |                         | 0.6     | 23.7         | 124.0             | 124.3            | -18.70                     | -17.72                    | 0.0                 | 0.0                |                            |                           | -19.09                  |                            | 28.62                | 1250         | 34.4319725 | -118.6462848 | ,                                                                                                                                                    |                     |
| CV-24202   | 8/27/2026 9:41:40 AM  | 23.1       | 29.3       | 0.0       | 47.6           |                         |                         | 0.8     | 0.0          | 127.6             | 126.6            | -13.83                     | -10.79                    |                     |                    | 14.056                     | 10.877                    | -14.23                  | -14.18                     | 28.6                 | 1288         | 34.4319313 | -118.6462782 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                               |                     |
| CV-24203   | 8/13/2026 2:17:52 PM  | 47.4       | 41.7       | 0.1       | 10.8           |                         |                         | 1.1     | 108.0        | 124.6             | 124.8            | -2.66                      | -2.55                     | 37.6                | 34.9               | 3.342                      | 2.884                     | -17.39                  | -16.43                     | 28.64                | 1245         | 34.4315407 | -118.6460048 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                               |                     |
| CV-24203   | 8/18/2026 10:44:52 AM | 46.8       | 41.4       | 0.0       | 11.8           |                         |                         | 1.1     | 0.0          | 125.5             | 125.3            | -2.66                      | -2.21                     | 31.9                | 23.0               | 2.400                      | 1.247                     | -16.38                  | -17.05                     | 28.73                | 1241         | 34.4315355 | -118.6460042 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                               |                     |
| CV-24204   | 8/13/2026 2:24:17 PM  | 49.0       | 44.4       | 0.0       | 6.6            |                         |                         | 1.1     | 0.0          | 127.5             | 127.8            | -6.08                      | -6.24                     | 28.3                | 30.5               | 1.073                      | 1.244                     | -16.65                  | -16.35                     | 28.63                | 1239         | 34.4314195 | -118.6462463 | Valve Adjustment:Increased Flow/Vacuum                                                                                                               |                     |
| CV-24204   | 8/18/2026 10:42:07 AM | 46.0       | 43.5       | 0.0       | 10.5           |                         |                         | 1.1     | 0.0          | 128.1             | 128.1            | -6.73                      | -5.83                     | 31.9                | 25.8               | 1.357                      | 0.889                     | -17.16                  | -17.84                     | 28.73                | 1228         | 34.4314188 | -118.6462513 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                               |                     |
| CV-24205   | 8/14/2026 10:16:11 AM | 45.6       | 43.7       | 0.1       | 10.6           |                         |                         | 1.0     | 106.0        | 124.5             | 124.5            | -5.75                      | -5.26                     | 35.1                | 31.7               | 1.638                      | 1.328                     | -18.40                  | -18.18                     | 28.74                | 1225         | 34.4322362 | -118.6464648 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                               |                     |
| CV-24205   | 8/19/2026 7:39:29 AM  | 46.4       | 38.5       | 0.0       | 15.1           |                         |                         | 1.2     | 0.0          | 124.3             | 124.4            | -5.08                      | -5.08                     | 32.7                | 32.5               | 1.419                      | 1.397                     | -19.65                  | -19.95                     | 28.66                | 1231         | 34.4312572 | -118.6464755 | Well Condition:Lorentz Pump Installed                                                                                                                |                     |
| CV-24206   | 8/13/2026 2:20:45 PM  | 28.3       | 30.4       | 3.6       | 37.7           |                         |                         | 0.9     | 10.6         | 108.6             |                  | -8.06                      | -4.25                     |                     |                    | 7.984                      | 4.234                     | -12.06                  | -13.02                     | 28.64                | 1275         | 34.4315320 | -118.6468008 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                               |                     |
| CV-24206   | 8/13/2026 2:26:18 PM  | 28.7       | 31.1       | 3.4       | 36.9           |                         |                         | 0.9     | 10.9         | 108.6             | 109.0            | -8.78                      | -8.81                     |                     |                    | 8.840                      | 8.900                     | -11.51                  | -11.50                     | 28.66                | 1271         | 34.4315357 | -118.6468048 | Valve Adjustment:Increased Flow/Vacuum                                                                                                               |                     |
|            |                       |            |            |           |                |                         |                         |         |              |                   |                  |                            |                           |                     |                    |                            |                           |                         |                            |                      |              |            |              | Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected                          |                     |
| CV-24206   | 8/27/2026 9:53:59 AM  | 23.3       | 25.8       | 6.9       | 44.0           |                         |                         | 0.9     | 6.4          | 106.0             | 106.0            | -2.64                      | -2.61                     |                     |                    | 2.630                      | 2.586                     | -2.49                   | -2.59                      | 28.6                 | 1286         | 34.4315165 | -118.6467792 |                                                                                                                                                      |                     |
| CV-24206   | 8/27/2026 9:54:46 AM  | 23.0       | 24.7       | 6.9       | 45.4           |                         |                         | 0.9     | 6.6          | 106.0             | 106.1            | -2.68                      | -2.51                     |                     |                    | 2.658                      | 2.535                     | -2.59                   | -2.09                      | 28.61                | 1287         | 34.4315190 | -118.6467635 | Valve Adjustment:High O2                                                                                                                             |                     |
| CV-24207   | 8/4/2026 1:11:12 PM   | 45.5       | 54.5       | 0.0       | 0.0            |                         |                         | 0.8     | 0.0          | 136.5             | 136.9            | -0.18                      | -0.20                     | 16.4                | 17.8               | 0.360                      | 0.429                     | -6.77                   | -6.63                      | 28.41                | 1383         | 34.4332755 | -118.6469193 | Valve Adjustment:Barely Open                                                                                                                         |                     |
|            |                       |            |            |           |                |                         |                         |         |              |                   |                  |                            |                           |                     |                    |                            |                           |                         |                            |                      |              |            |              | Valve Adjustment:NSPS/EG CAL,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Surging Liquid in Header;Well Condition:Lorentz Pump Installed |                     |
| CV-24207   | 8/16/2026 1:08:31 PM  | 47.8       | 46.8       | 0.0       | 5.4            |                         |                         | 1.0     | 0.0          | 137.0             | 137.4            | 0.60                       | -0.45                     | 16.7                | 20.0               | 0.372                      | 0.534                     | -6.22                   | -8.39                      | 28.64                | 1390         | 34.4332923 | -118.6469463 | Valve Adjustment:NSPS/EG CAL,High Temp;Well Condition:Lorentz Pump Installed                                                                         |                     |
| CV-24207   | 8/16/2026 1:09:55 PM  | 47.4       | 46.9       | 0.0       | 5.7            |                         |                         | 1.0     | 0.0          | 137.7             | 137.7            | -0.67                      | -0.69                     | 19.3                | 19.9               | 0.498                      | 0.530                     | -7.20                   | -7.33                      | 28.64                | 1397         | 34.4333115 | -118.6469515 |                                                                                                                                                      |                     |
|            |                       |            |            |           |                |                         |                         |         |              |                   |                  |                            |                           |                     |                    |                            |                           |                         |                            |                      |              |            |              | Valve Adjustment:High Temp;Well Comment:Pump is active;Well Condition:Lorentz Pump Installed                                                         |                     |
| CV-24207   | 8/16/2026 1:10:56 PM  | 46.9       | 47.6       | 0.0       | 5.5            |                         |                         | 1.0     | 0.0          | 137.7             | 137.7            | -0.67                      | -0.68                     | 20.8                | 20.8               | 0.579                      | 0.580                     | -7.45                   | -6.98                      | 28.64                | 1401         | 34.4332997 | -118.6469420 | Valve Adjustment:NSPS/EG CAL,High Temp,Barely Open                                                                                                   |                     |
| CV-24208   | 8/13/2026 1:56:39 PM  | 40.8       | 57.4       | 0.0       | 1.8            |                         |                         | 0.7     | 0.0          | 131.4             | 131.4            | -0.62                      | -0.60                     | 8.2                 | 6.7                | 0.438                      | 0.290                     | -10.95                  | -9.56                      | 28.62                | 1255         | 34.4318792 | -118.6450890 | Valve Adjustment:High Temp,Barely Open                                                                                                               |                     |
| CV-24208   | 8/13/2026 1:58:00 PM  | 40.6       | 58.2       | 0.0       | 1.2            |                         |                         | 0.7     | 0.0          | 131.6             | 131.6            | -0.74                      | -0.71                     | 19.1                | 19.5               | 0.849                      | 0.885                     | -11.48                  | -11.56                     | 28.62                | 1259         | 34.4318878 | -118.6450877 | Valve Adjustment:High Temp,Barely Open                                                                                                               |                     |
|            |                       |            |            |           |                |                         |                         |         |              |                   |                  |                            |                           |                     |                    |                            |                           |                         |                            |                      |              |            |              | Valve Adjustment:NSPS/EG CAL,High Temp,Positive Static Press.,Increased Flow/Vacuum                                                                  |                     |
| CV-24208   | 8/18/2026 9:53:06 AM  | 39.3       | 53.4       | 0.0       | 7.3            |                         |                         | 0.7     | 0.0          | 132.0             | 132.0            | 0.13                       | -0.11                     | 13.4                | 16.2               | 0.426                      | 0.616                     | -8.23                   | -8.04                      | 28.73                | 1251         | 34.4318942 | -118.6451097 | Valve Adjustment:NSPS/EG CAL,High Temp                                                                                                               |                     |
| CV-24208   | 8/18/2026 9:53:57 AM  | 39.9       | 54.2       | 0.0       | 5.9            |                         |                         | 0.7     | 0.0          | 132.0             | 132.1            | -0.17                      | -0.16                     | 18.2                | 18.7               | 0.785                      | 0.829                     | -7.71                   | -7.95                      | 28.73                | 1237         | 34.4318958 | -118.6450987 | Valve Adjustment:NSPS/EG CAL,High Temp                                                                                                               |                     |
| CV-24208   | 8/18/2026 9:55:24 AM  | 40.1       | 53.5       | 0.0       | 6.4            |                         |                         | 0.7     | 0.0          | 132.1             | 132.2            | -0.11                      | -0.10                     | 20.7                | 20.1               | 1.010                      | 0.958                     | -8.29                   | -8.36                      | 28.73                | 1238         | 34.4318887 | -118.6450992 | Valve Adjustment:NSPS/EG CAL,High Temp                                                                                                               |                     |
| CV-24209   | 8/5/2026 10:43:28 AM  | 11.7       | 58.5       | 0.5       | 29.3           |                         |                         | 0.2     | 58.6         | 118.1             | 117.9            | -1.36                      | -1.32                     | 0.0                 | 0.0                | 2.109                      | 2.095                     | -20.18                  |                            | 28.61                | 1280         | 34.4321750 | -118.6455563 | ,                                                                                                                                                    |                     |
| CV-24210   | 8/18/2026 9:10:36 AM  | 28.3       | 32.6       | 0.3       | 38.8           |                         |                         | 0.9     | 129.3        | 127.9             | 125.6            | -5.55                      | -5.05                     |                     |                    | 5.775                      | 5.097                     | -8.15                   | -8.63                      | 28.62                | 1333         | 34.4326762 | -118.6456010 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                               |                     |
| CV-24211   | 8/20/2026 9:14:45 AM  | 19.6       | 72.6       | 0.0       | 7.8            |                         |                         | 0.3     | 0.0          | 130.1             | 129.9            | -17.11                     | -17.16                    |                     |                    | 17.309                     | 17.385                    | -17.46                  | -17.41                     | 28.72                | 1258         | 34.4327045 | -118.6438527 | Valve Adjustment:Increased Flow/Vacuum                                                                                                               |                     |
| CV-24212   | 8/24/2026 12:58:45 PM | 15.1       | 64.5       | 0.2       | 20.3           |                         |                         | 0.2     | 112.5        | 130.4             | 130.8            | -9.22                      | -7.72                     |                     |                    | 9.254                      | 7.818                     | -15.29                  | -15.18                     | 28.72                | 1252         | 34.4331742 | -118.6430698 | Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed                                                                         |                     |
| CV-24213   | 8/19/2026 8:18:40 AM  | 47.1       | 45.2       | 0.0       | 7.7            |                         |                         | 1.0     | 0.0          | 126.3             | 125.8            | -0.47                      | -0.47                     |                     |                    | 0.455                      | 0.456                     | -12.21                  | -12.20                     | 28.66                | 1323         | 34.4365930 | -118.6429642 | Valve Adjustment:Barely Open                                                                                                                         |                     |
| CV-24214   | 8/18/2026 11:08:44 AM | 29.7       | 35.3       | 0.0       | 35.0           |                         |                         | 0.8     | 0.0          | 121.5             | 121.8            | -4.60                      | -3.05                     | 40.7                | 33.3               | 4.582                      | 3.047                     | -5.26                   | -9.91                      | 28.66                | 1314         | 34.4367368 | -118.6435080 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                               |                     |
| CV-24214   | 8/19/2026 8:24:21 AM  | 29.6       | 38.9       | 0.1       | 31.4           |                         |                         | 0.8     | 314.0        | 126.8             | 126.1            | -1.47                      | -1.46                     |                     |                    | 1.441                      | 1.426                     | -11.25                  | -11.25                     | 28.66                | 1324         | 34.4367413 | -118.6435148 | Valve Adjustment:Barely Open                                                                                                                         |                     |
| CV-24215   | 8/28/2026 9:22:25 AM  | 43.5       | 54.1       | 0.1       | 2.3            |                         |                         | 0.8     | 23.0         | 113.5             | 113.7            | -1.29                      | -1.26                     | 23.1                | 33.6               | 0.337                      | 0.713                     | -9.90                   | -13.30                     | 28.56                | 1305         | 34.4369348 | -118.6448017 | Valve Adjustment:Barely Open                                                                                                                         |                     |
| CV-24216   | 8/5/2026 11:55:31 AM  | 39.2       | 39.0       | 0.1       | 21.7           |                         |                         | 1.0     | 217.0        | 120.4             | 120.8            | -8.46                      | -7.85                     | 0.0                 | 0.0                | 8.244                      | 7.444                     |                         |                            | 28.6                 | 1247         | 34.4368378 | -118.6423052 | ,                                                                                                                                                    |                     |
| CV-24217   | 8/11/2026 1:35:32 PM  | 47.0       | 48.4       | 0.0       | 4.6            |                         |                         | 1.0     | 0.0          | 117.5             | 117.9            | -0.49                      | -0.49                     |                     |                    | 0.514                      | 0.511                     | -14.53                  | -14.41                     | 28.62                | 1390         | 34.4359485 | -118.6443817 |                                                                                                                                                      |                     |
| CV-24218   | 8/11/2026 1:12:17 PM  | 53.0       | 46.3       | 0.0       | 0.7            |                         |                         | 1.1     | 23.7         | 126.8             | 124.4            | -2.45                      | -1.63                     |                     |                    | 0.263                      | 1.629                     | -4.71                   | -4.84                      | 28.61                | 1389         | 34.4358225 | -118.6457665 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                               |                     |
| CV-24219   | 8/5/2026 8:25:00 AM   |            |            |           |                |                         | 86700                   |         |              |                   |                  |                            |                           |                     |                    |                            |                           |                         |                            |                      |              |            |              | AtmA; [User entered 8.67%]                                                                                                                           |                     |
| CV-24219   | 8/5/2026 8:25:00 AM   |            |            |           |                | 2610                    |                         |         |              |                   |                  |                            |                           |                     |                    |                            |                           |                         |                            |                      |              |            |              | AtmA                                                                                                                                                 |                     |
| CV-24219   | 8/11/2026 8:10:00 AM  |            |            |           |                | 2490                    |                         |         |              |                   |                  |                            |                           |                     |                    |                            |                           |                         |                            |                      |              |            |              | AtmA                                                                                                                                                 |                     |
|            |                       |            |            |           |                |                         |                         |         |              |                   |                  |                            |                           |                     |                    |                            |                           |                         |                            |                      |              |            |              | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                 |                     |
| CV-24219   | 8/11/2026 8:11:20 AM  | 30.8       | 68.2       | 0.0       | 1.0            |                         |                         | 0.5     | 0.0          | 181.7             | 181.7            | -8.16                      | -8.21                     |                     |                    | 8.574                      | 8.580                     | -16.00                  | -16.17                     | 28.57                | 1410         | 34.4350843 | -118.6462270 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                 |                     |
| CV-24219   | 8/18/2026 10:30:36 AM | 40.0       | 60.0       | 0.0       | 0.0            |                         |                         | 0.7     | 0.0          | 181.9             | 182.3            | -0.01                      | -0.01                     |                     |                    | 0.000                      | 0.000                     | 0.55                    | 0.60                       | 28.59                | 1389         | 34.4350811 | -118.6462382 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                 |                     |
| CV-24219   | 8/18/2026 10:32:51 AM | 40.3       | 59.7       | 0.0       | 0.0            |                         |                         | 0.7     | 0.0          | 182.4             | 182.4            | -11.07                     | -11.42                    |                     |                    | 11.679                     | 12.023                    | -13.78                  | -14.44                     | 28.58                | 1389         | 34.4350779 | -118.6462415 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                                                 |                     |
| CV-24219   | 8/18/2026 10:35:      |            |            |           |                |                         |                         |         |              |                   |                  |                            |                           |                     |                    |                            |                           |                         |                            |                      |              |            |              |                                                                                                                                                      |                     |

## Chiquita Canyon Landfill

| Point Name | Record Date           | CH4  | CO2  | O2  | Bal Gas | CO Reading (ppmv) | H2 Reading (ppmv) | CH4:CO2 | BalO2 | Init Temp (°F) | Adj Temp (°F) | Init Stat Press (\"H2O) | Adj Stat Press (\"H2O) | Init Flow (scfm) | Adj Flow (scfm) | Init Diff Press (\"H2O) | Adj Diff Press (\"H2O) | Sys Pressure (\"H2O) | Adj Avail Press (\"H2O) | Baro Press (\"Hg) | Elev (ft) | Latitude   | Longitude    | Comments                                                                                                            |
|------------|-----------------------|------|------|-----|---------|-------------------|-------------------|---------|-------|----------------|---------------|-------------------------|------------------------|------------------|-----------------|-------------------------|------------------------|----------------------|-------------------------|-------------------|-----------|------------|--------------|---------------------------------------------------------------------------------------------------------------------|
|            |                       | [%]  | [%]  | [%] | [%]     |                   |                   |         | [%]   | Temp (°F)      | Temp (°F)     | \"H2O)                  | \"H2O)                 | scfm)            | scfm)           | \"H2O)                  | \"H2O)                 | \"H2O)               | \"H2O)                  | \"Hg)             |           |            |              |                                                                                                                     |
| CV-24219   | 8/25/2026 2:22:36 PM  | 44.0 | 0.0  | 0.0 | 56.0    |                   |                   |         | 0.0   | 170.3          | 170.3         | -11.19                  | -10.84                 |                  |                 | 11.308                  | 10.846                 | -12.47               | -11.50                  | 28.55             | 1386      | 34.4350710 | -118.6462313 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                |
| CV-24220   | 8/17/2026 12:50:37 PM | 14.2 | 41.0 | 1.2 | 43.6    |                   |                   | 0.3     | 36.3  | 141.8          | 139.1         | -15.45                  | -15.49                 |                  |                 | 15.383                  | 15.355                 | -15.83               | -15.79                  | 28.66             | 1342      | 34.4339417 | -118.6440040 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum                                                        |
| CV-24220   | 8/17/2026 12:51:28 PM | 44.4 | 41.8 | 1.1 | 42.7    |                   |                   | 0.3     | 38.8  | 139.8          | 141.3         | -15.49                  | -15.46                 |                  |                 | 15.324                  | 15.321                 | -15.79               | -15.80                  | 28.65             | 1343      | 34.4339365 | -118.6439965 | Valve Adjustment:NSPS/EG CAI,High Temp                                                                              |
| CV-24221   | 8/3/2026 1:07:29 PM   | 19.9 | 41.5 | 0.0 | 8.6     |                   |                   | 1.2     | 0.0   | 130.8          | 130.7         | -7.06                   | -7.05                  | 16.2             | 16.7            | 0.738                   | 0.792                  | -16.03               | -15.14                  | 28.53             | 1279      | 34.4341363 | -118.6421092 | Well Comment:pump removed                                                                                           |
| CV-24222   | 8/25/2026 8:26:06 AM  | 51.0 | 40.6 | 0.0 | 8.4     |                   |                   | 1.3     | 0.0   | 123.0          | 123.1         | -15.92                  | -15.80                 | 27.2             | 26.8            | 2.102                   | 2.041                  | -17.86               | -17.63                  | 28.68             | 1259      | 34.4336087 | -118.6419858 |                                                                                                                     |
| CV-24222   | 8/25/2026 8:26:45 AM  | 50.5 | 40.7 | 0.0 | 8.7     |                   |                   | 1.2     | 0.0   | 123.1          | 123.1         | -15.95                  | -15.90                 | 28.8             | 26.8            | 2.356                   | 2.041                  | -18.02               | -17.76                  | 28.71             | 1259      | 34.4336087 | -118.6419858 | Well Condition:Lorentz Pump Installed                                                                               |
| CV-24223   | 8/25/2026 8:47:34 AM  | 37.0 | 51.1 | 0.1 | 11.7    |                   |                   | 0.7     | 90.1  | 123.3          | 123.3         | -1.40                   | -1.39                  |                  |                 | 1.402                   | 1.399                  | -17.45               | -17.28                  | 28.69             | 1252      | 34.4334250 | -118.6425372 | Well Condition:Pnuematic Pump Installed                                                                             |
| CV-24224   | 8/17/2026 1:07:51 PM  | 48.3 | 43.1 | 0.0 | 8.6     |                   |                   | 1.1     | 0.0   | 107.3          | 108.5         | -1.30                   | -0.63                  |                  |                 | 1.283                   | 0.605                  | -16.80               | -17.39                  | 28.66             | 1321      | 34.4331538 | -118.6448533 | Valve Adjustment:Decreased Flow/Vacuum                                                                              |
| CV-24225   | 8/18/2026 9:41:07 AM  | 45.6 | 39.4 | 1.0 | 14.0    |                   |                   | 1.2     | 14.0  | 129.8          | 128.6         | -1.34                   | -0.59                  |                  |                 | 1.326                   | 0.588                  | -18.82               | -18.82                  | 28.69             | 1291      | 34.4327138 | -118.6444335 | Valve Adjustment:Decreased Flow/Vacuum                                                                              |
| CV-24226   | 8/18/2026 9:44:35 AM  | 50.4 | 41.6 | 0.0 | 8.0     |                   |                   | 1.2     | 0.0   | 118.7          | 118.7         | -8.73                   | -8.74                  | 11.0             | 10.7            | 0.030                   | 0.028                  | -18.98               | -18.82                  | 28.71             | 1264      | 34.4325222 | -118.6442992 | Valve Adjustment:Audible Flow,Barely Open                                                                           |
| CV-24227   | 8/12/2026 9:59:39 AM  | 52.6 | 42.7 | 0.0 | 4.7     |                   |                   | 1.2     | 0.0   | 118.2          | 118.2         | -2.97                   | -3.35                  | 20.2             | 23.6            | 0.956                   | 1.298                  | -15.41               | -15.54                  | 28.64             | 1286      | 34.4309332 | -118.6498322 | Valve Adjustment:Barely Open                                                                                        |
| CV-24231   | 8/12/2026 10:18:52 AM | 41.8 | 42.5 | 0.0 | 15.7    |                   |                   | 1.0     | 0.0   | 126.5          | 126.7         | -1.27                   | -1.48                  | 23.0             | 27.9            | 0.341                   | 0.504                  | -18.98               | -18.51                  | 28.65             | 1277      | 34.4302872 | -118.6496112 | Valve Adjustment:Increased Flow/Vacuum                                                                              |
| CV-24231   | 8/12/2026 10:21:22 AM | 41.2 | 42.6 | 0.0 | 16.2    |                   |                   | 1.0     | 0.0   | 126.7          | 126.7         | -1.45                   | -1.44                  | 28.1             | 27.8            | 0.511                   | 0.500                  | -17.80               | -18.31                  | 28.67             | 1282      | 34.4302790 | -118.6496347 |                                                                                                                     |
| CV-24236   | 8/5/2026 8:55:28 AM   | 28.8 | 30.0 | 1.1 | 40.1    |                   |                   | 1.0     | 36.5  | 107.1          | 107.2         | -3.65                   | -3.63                  | 12.1             | 10.8            | 0.894                   | 0.720                  | -18.79               |                         | 28.68             | 1220      | 34.4301283 | -118.6505215 |                                                                                                                     |
| CV-24237   | 8/5/2026 8:59:37 AM   | 29.8 | 29.6 | 1.8 | 38.8    |                   |                   | 1.0     | 21.6  | 110.7          | 110.9         | -1.87                   | -1.80                  | 18.7             | 18.7            | 0.761                   | 0.759                  | -17.79               |                         | 28.67             | 1220      | 34.4306408 | -118.6502643 |                                                                                                                     |
| CV-24243   | 8/6/2026 10:54:09 AM  | 63.7 | 36.3 | 0.0 | 0.0     |                   |                   | 1.8     | 0.0   | 117.3          | 120.9         | 0.02                    | -0.10                  | 2.5              | 13.2            | 0.016                   | 0.471                  | -17.77               | -17.82                  | 28.78             | 1211      | 34.4287720 | -118.6506532 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open,Surging Liquid in Header      |
| CV-24243   | 8/6/2026 10:55:06 AM  | 62.8 | 37.2 | 0.0 | 0.0     |                   |                   | 1.7     | 0.0   | 121.0          | 121.0         | -0.11                   | -0.11                  | 13.6             | 13.8            | 0.499                   | 0.515                  | -17.85               | -17.69                  | 28.78             | 1202      | 34.4287668 | -118.6506632 | Valve Adjustment:NSPS/EG CAC,Surging Liquid in Header                                                               |
| CV-24244   | 8/12/2026 10:11:02 AM | 48.0 | 39.4 | 0.5 | 12.1    |                   |                   | 1.2     | 24.2  | 113.5          | 113.6         | -1.55                   | -1.55                  | 45.0             | 44.4            | 0.515                   | 0.503                  | -17.42               | -17.35                  | 28.68             | 1255      | 34.4289702 | -118.6512690 | Valve Adjustment:Barely Open,Surging Liquid in Header                                                               |
| CV-24245   | 8/12/2026 1:00:42 PM  | 52.4 | 41.7 | 0.0 | 5.9     |                   |                   | 1.3     | 0.0   | 117.5          | 117.6         | -0.44                   | -0.46                  | 16.7             | 17.2            | 0.643                   | 0.687                  | -16.40               | -16.68                  | 28.7              | 1158      | 34.4285057 | -118.6500707 | Valve Adjustment:Barely Open                                                                                        |
| CV-24246   | 8/12/2026 1:04:38 PM  | 52.8 | 41.1 | 0.5 | 5.6     |                   |                   | 1.3     | 11.2  | 120.4          | 120.4         | -0.04                   | -0.04                  | 9.9              | 11.0            | 0.267                   | 0.325                  | -10.90               | -13.52                  | 28.69             | 1152      | 34.4286877 | -118.6494177 | Valve Adjustment:Barely Open                                                                                        |
| CV-24253   | 8/9/2026 10:15:21 AM  | 52.1 | 42.6 | 0.0 | 5.3     |                   |                   | 1.2     | 0.0   | 121.9          | 122.0         | -0.85                   | -0.86                  | 19.6             | 20.7            | 0.892                   | 0.993                  | -16.56               | -16.58                  | 28.74             | 1140      | 34.4286975 | -118.6498168 | Valve Adjustment:Increased Flow/Vacuum                                                                              |
| CV-25      | 8/18/2026 4:02:28 PM  | 50.4 | 37.9 | 0.0 | 11.7    |                   |                   | 1.3     | 0.0   | 117.4          | 117.3         | -6.21                   | -6.17                  |                  |                 | 6.368                   | 6.368                  | -6.35                | -6.35                   | 28.73             | 1194      | 34.4370794 | -118.6416939 |                                                                                                                     |
| CV-2501    | 8/19/2026 2:02:37 PM  | 59.0 | 41.0 | 0.0 | 0.0     |                   |                   | 1.4     | 0.0   | 129.5          | 129.6         | -1.17                   | -1.17                  | 5.9              | 7.2             | 0.009                   | 0.014                  | -10.88               | -10.61                  | 28.52             | 1324      | 34.4313360 | -118.6484453 | Valve Adjustment:Barely Open                                                                                        |
| CV-2502    | 8/12/2026 9:32:55 AM  | 47.7 | 42.2 | 0.0 | 10.2    |                   |                   | 1.1     | 0.0   | 124.2          | 124.2         | -1.15                   | -1.14                  | 30.2             | 30.1            | 0.240                   | 0.238                  | -18.41               | -18.41                  | 28.61             | 1329      | 34.4308797 | -118.6490838 | Well Condition:Lorentz Pump Installed                                                                               |
| CV-2502    | 8/12/2026 9:36:44 AM  | 47.4 | 42.5 | 0.0 | 10.1    |                   |                   | 1.1     | 0.0   | 124.0          | 123.8         | -1.15                   | -1.06                  | 30.8             | 28.0            | 0.611                   | 0.505                  | -18.41               | -19.02                  | 28.61             | 1327      | 34.4308835 | -118.6490775 | Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum                                           |
| CV-2502    | 8/12/2026 9:41:10 AM  | 46.5 | 43.3 | 0.0 | 10.2    |                   |                   | 1.1     | 0.0   | 123.5          | 123.3         | -0.97                   | -0.80                  | 26.7             | 20.8            | 0.460                   | 0.278                  | -19.04               | -19.13                  | 28.6              | 1335      | 34.4308758 | -118.6490923 | Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed                                        |
| CV-2503    | 8/20/2026 11:12:34 AM | 47.3 | 46.2 | 0.0 | 6.5     |                   |                   | 1.0     | 0.0   | 131.1          | 131.1         | -1.00                   | -1.02                  | 32.8             | 34.8            | 0.356                   | 0.401                  | -13.50               | -13.67                  | 28.69             | 1281      | 34.4312432 | -118.6477338 | Valve Adjustment:Audible Flow,Increased Flow/Vacuum                                                                 |
| CV-2503    | 8/20/2026 11:13:22 AM | 47.7 | 44.5 | 0.0 | 7.8     |                   |                   | 1.1     | 0.0   | 131.1          | 131.1         | -1.05                   | -1.06                  | 34.6             | 34.5            | 0.397                   | 0.396                  | -13.60               | -14.53                  | 28.68             | 1284      | 34.4312328 | -118.6477317 | Valve Adjustment:High Temp                                                                                          |
| CV-2503    | 8/31/2026 1:09:26 PM  | 51.1 | 38.2 | 0.0 | 10.7    |                   |                   | 1.3     | 0.0   | 130.3          | 130.4         | -0.64                   | -0.65                  | 33.0             | 33.3            | 0.285                   | 0.290                  | -11.92               | -11.89                  | 28.62             | 1306      | 34.4312145 | -118.6477527 | Valve Adjustment:NSPS/EG CAI,High Temp                                                                              |
| CV-2503    | 8/31/2026 1:15:12 PM  | 49.5 | 40.2 | 0.0 | 10.3    |                   |                   | 1.2     | 0.0   | 130.4          | 130.3         | -0.49                   | -1.13                  | 32.0             | 45.5            | 0.268                   | 0.542                  | -12.32               | -11.00                  | 28.61             | 1298      | 34.4312082 | -118.6477572 |                                                                                                                     |
| CV-2504    | 8/12/2026 10:06:40 AM | 49.2 | 41.8 | 0.0 | 9.1     |                   |                   | 1.2     | 0.0   | 129.4          | 129.4         | -1.40                   | -1.40                  | 39.9             | 39.9            | 4.419                   | 4.425                  | -19.23               | -19.23                  | 28.68             | 1295      | 34.4303675 | -118.6489203 |                                                                                                                     |
| CV-2505    | 8/19/2026 2:11:35 PM  | 59.5 | 40.5 | 0.0 | 0.0     |                   |                   | 1.5     | 0.0   | 126.4          | 127.0         | -2.15                   | -2.15                  | 57.4             | 56.9            | 0.859                   | 0.846                  | -15.96               | -15.73                  | 28.63             | 1254      | 34.4308023 | -118.6471753 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed |
| CV-2506    | 8/19/2026 2:17:29 PM  | 58.2 | 41.7 | 0.0 | 0.1     |                   |                   | 1.4     | 0.0   | 122.9          | 122.9         | -1.70                   | -1.69                  | 42.9             | 43.9            | 1.183                   | 1.234                  | -15.35               | -15.15                  | 28.63             | 1234      | 34.4304533 | -118.6475810 | Valve Adjustment:Barely Open                                                                                        |
| CV-2507    | 8/19/2026 2:22:18 PM  | 59.6 | 40.2 | 0.2 | 0.0     |                   |                   | 1.5     | 0.0   | 127.5          | 127.4         | -0.07                   | -0.23                  | 31.8             | 36.1            | 1.331                   | 1.721                  | -15.57               | -16.31                  | 28.64             | 1206      | 34.4301232 | -118.6481435 | Valve Adjustment:Increased Flow/Vacuum,Barely Open                                                                  |
| CV-2507    | 8/21/2026 1:47:10 PM  | 51.1 | 48.9 | 0.0 | 0.0     |                   |                   | 1.0     | 0.0   | 112.5          | 126.9         | -0.62                   | -0.70                  | 29.1             | 30.6            | 1.412                   | 1.598                  | -14.19               | -14.34                  | 28.78             | 1210      | 34.4301248 | -118.6481720 | Valve Adjustment:Increased Flow/Vacuum                                                                              |
| CV-2508    | 8/21/2026 1:53:46 PM  | 51.3 | 45.4 | 0.0 | 3.3     |                   |                   | 1.1     | 0.0   | 121.4          | 121.4         | -11.18                  | -11.19                 | 48.6             | 51.2            | 1.541                   | 1.713                  | -14.03               | -14.26                  | 28.78             | 1204      | 34.4297083 | -118.6487553 | Valve Adjustment:Increased Flow/Vacuum                                                                              |
| CV-2509    | 8/12/2026 12:51:35 PM | 48.3 | 39.6 | 0.0 | 12.1    |                   |                   | 1.2     | 0.0   | 116.9          | 116.9         | -11.15                  | -11.17                 | 74.0             | 74.0            | 3.569                   | 3.570                  | -17.68               | -17.44                  | 28.69             | 1177      | 34.4292647 | -118.6491673 | Valve Adjustment:Barely Open                                                                                        |
| CV-2510    | 8/12/2026 12:36:16 PM | 56.6 | 41.0 | 0.0 | 2.4     |                   |                   | 1.4     | 0.0   | 115.5          | 115.5         | -9.17                   | -9.11                  | 43.3             | 43.3            | 5.198                   | 5.183                  | -17.48               | -17.82                  | 28.69             | 1168      | 34.4290820 | -118.6498108 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)                                       |
| CV-2510    | 8/21/2026 10:52:09 AM | 56.0 | 41.4 | 0.0 | 2.6     |                   |                   | 1.4     | 0.0   | 116.5          | 116.5         | -9.14                   | -9.40                  | 40.5             | 43.3            | 4.520                   | 5.173                  | -16.20               | -16.19                  | 28.82             | 1163      | 34.4290862 | -118.6498292 | Valve Adjustment:Increased Flow/Vacuum                                                                              |
| CV-25100D  | 8/11/2026 10:21:55 AM | 12.1 | 52.4 | 0.3 | 35.2    |                   |                   | 0.2     | 117.3 | 139.9          | 144.6         | -5.12                   | -4.71                  |                  |                 | 5.583                   | 5.006                  | -7.99                | -8.08                   | 28.6              | 1377      | 34.4361513 | -118.6471312 | Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header                               |
| CV-25100D  | 8/24/2026 11:24:42 AM | 14.4 | 56.8 | 0.4 | 28.4    |                   |                   | 0.3     | 71.0  | 126.2          | 127.1         | -4.96                   | -4.91                  |                  |                 | 4.959                   | 4.910                  | -5.93                | -5.84                   | 28.59             | 1363      | 34.4361880 | -118.6471123 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)                           |
| CV-25100S  | 8/3/2026 10:18:08 AM  | 4.1  | 72.4 | 0.0 | 23.5    |                   |                   | 0.1     | 0.0   | 184.0          | 184.9         | -9.38                   | -8.95                  |                  |                 | 9.969                   | 9.546                  | -11.88               | -10.67                  | 28.42             | 1376      | 34.4361440 | -118.6471390 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed                                |
| CV-25100S  | 8/10/2026 10:38:43 AM | 22.7 | 64.8 | 0.0 | 12.5    |                   |                   | 0.4     | 0.0   | 189.0          | 188.3         | 0.18                    | -2.80                  |                  |                 | 0.000                   | 2.846                  | -7.06                | -6.88                   | 28.59             | 1388      | 34.4361566 | -118.6471480 | Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum                                                |
| CV-25100S  | 8/10/2026 10:39:23 AM | 19.9 | 72.8 | 0.0 | 7.3     |                   |                   | 0.3     | 0.0   | 187.9          | 188.3         | -2.65                   | -2.41                  |                  |                 | 2.630                   | 2.416                  | -6.98                | -7.07                   | 28.57             | 1387      | 34.4361492 | -118.6471518 | Valve Adjustment:No Flow Measurement,High Temp                                                                      |
| CV-25100S  | 8/10/2026 10:55:00 AM |      |      |     |         | 3480              |                   |         |       |                |               |                         |                        |                  |                 |                         |                        |                      |                         |                   |           |            |              | AtmAA                                                                                                               |
| CV-25100S  | 8/17/2026 9:50:12 AM  | 26.2 | 55.0 | 0.0 | 18.8    |                   |                   | 0.5     | 0.0   | 185.7          | 185.9         | -5.47                   | -5.62                  |                  |                 | 5.968                   | 6.171                  | -7.06                | -7.19                   | 28.66             | 1384      | 34.4361691 | -118.6471424 | Valve Adjustment:No Flow Measurement,High Temp                                                                      |
| CV-25100S  | 8/17/2026 9:55:00 AM  |      |      |     |         | 2880              |                   |         |       |                |               |                         |                        |                  |                 |                         |                        |                      |                         |                   |           |            |              | AtmAA                                                                                                               |

### Chiquita Canyon Landfill

| Point Name | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init Flow<br>[scfm] | Adj Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                                                      |
|------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|---------------------|--------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------|
| CV-25100S  | 8/24/2026 9:28:49 AM  | 38.4       | 61.6       | 0.0       | 0.0            |                         |                         | 0.6     | 0.0          | 183.9                | 184.5               | -6.28                        | -6.23                       |                     |                    | 6.748                        | 6.730                       | -7.41                     | -7.47                        | 28.6                   | 1378         | 34.4361543 | -118.6471321 | Valve Adjustment:No Flow Measurement,High Temp                                                                                                                |
| CV-25100S  | 8/31/2026 1:44:11 PM  | 8.2        | 75.9       | 0.0       | 15.9           |                         |                         | 0.1     | 0.0          | 185.2                | 186.3               | -2.17                        | -2.20                       |                     |                    | 2.085                        | 2.295                       | -5.46                     | -5.39                        | 28.52                  | 1378         | 34.4361553 | -118.6471434 | Valve Adjustment:No Flow Measurement,High Temp                                                                                                                |
| CV-25101D  | 8/7/2026 2:43:15 PM   | 3.5        | 58.6       | 7.0       | 30.9           |                         |                         | 0.1     | 4.4          | 102.9                | 102.9               | -9.29                        | -8.82                       |                     |                    | 9.519                        | 9.084                       | -9.28                     | -8.84                        | 28.52                  | 1388         | 34.4359815 | -118.6467795 | Valve Adjustment:High O2                                                                                                                                      |
| CV-25101D  | 8/12/2026 1:44:51 PM  | 5.4        | 40.0       | 10.0      | 44.7           |                         |                         | 0.1     | 4.5          | 95.0                 | 95.0                | -7.79                        | -7.74                       |                     |                    | 7.802                        | 7.833                       | -7.83                     | -7.84                        | 28.49                  | 1400         | 34.4359935 | -118.6467927 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open;Well Repairs:Sample Port                                                               |
| CV-25101D  | 8/17/2026 2:02:46 PM  | 9.6        | 59.7       | 4.7       | 26.0           |                         |                         | 0.2     | 5.5          | 98.3                 | 98.4                | -6.42                        | -6.41                       |                     |                    | 6.526                        | 6.470                       | -6.30                     | -6.31                        | 28.52                  | 1387         | 34.4359687 | -118.6468065 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected                                                       |
| CV-25101S  | 8/7/2026 2:45:07 PM   | 25.1       | 55.5       | 0.1       | 19.3           |                         |                         | 0.5     | 193.0        | 112.8                | 112.7               | -0.35                        | -0.31                       |                     |                    | 0.345                        | 0.244                       | -9.24                     | -9.42                        | 28.52                  | 1386         | 34.4359998 | -118.6467910 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)                                                                     |
| CV-25101S  | 8/17/2026 2:04:37 PM  | 27.5       | 68.6       | 0.2       | 3.7            |                         |                         | 0.4     | 18.5         | 106.5                | 106.6               | -0.27                        | -0.24                       |                     |                    | 0.108                        | 0.178                       | -6.31                     | -6.61                        | 28.52                  | 1399         | 34.4359980 | -118.6468173 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)                                                                     |
| CV-25102   | 8/12/2026 11:48:58 AM | 4.9        | 13.3       | 15.3      | 66.5           |                         |                         | 0.4     | 4.3          | 100.1                | 100.2               | -8.63                        | -8.48                       |                     |                    | 8.765                        | 8.616                       | -8.63                     | -8.54                        | 28.63                  | 1369         | 34.4357895 | -118.6471867 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In);Well Comment:No pump                               |
| CV-25102   | 8/12/2026 11:49:57 AM | 4.6        | 10.3       | 15.6      | 69.5           |                         |                         | 0.4     | 4.5          | 100.6                | 100.6               | -8.40                        | -8.44                       |                     |                    | 8.503                        | 8.592                       | -8.42                     | -8.55                        | 28.63                  | 1369         | 34.4357895 | -118.6471867 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In);Well Comment:No pump                               |
| CV-25102   | 8/24/2026 11:21:46 AM | 7.4        | 64.4       | 5.0       | 23.2           |                         |                         | 0.1     | 4.6          | 119.5                | 120.0               | -6.81                        | -6.80                       |                     |                    | 7.306                        | 7.204                       | -6.85                     | -6.69                        | 28.57                  | 1350         | 34.4358142 | -118.6471622 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected                                           |
| CV-25103   | 8/7/2026 2:21:26 PM   | 23.9       | 34.4       | 2.0       | 39.7           |                         |                         | 0.7     | 19.9         | 127.7                | 127.8               | -0.30                        | -0.28                       |                     |                    | 0.277                        | 0.262                       | -9.69                     | -9.85                        | 28.52                  | 1390         | 34.4356693 | -118.6466872 | Valve Adjustment:Barely Open                                                                                                                                  |
| CV-25103   | 8/17/2026 1:36:53 PM  | 35.7       | 40.1       | 0.1       | 24.1           |                         |                         | 0.9     | 241.0        | 118.9                | 118.9               | -0.14                        | -0.14                       |                     |                    | 0.111                        | 0.130                       | -7.18                     | -7.09                        | 28.54                  | 1385         | 34.4356512 | -118.6467272 | Valve Adjustment:Barely Open                                                                                                                                  |
| CV-25104D  | 8/11/2026 10:15:35 AM | 2.7        | 29.0       | 13.5      | 54.8           |                         |                         | 0.1     | 4.1          | 94.4                 | 94.8                | -9.43                        | -9.28                       |                     |                    | 9.501                        | 9.425                       | -9.37                     | -9.37                        | 28.63                  | 1384         | 34.4353662 | -118.6472455 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum                                                                                                    |
| CV-25104D  | 8/11/2026 10:16:18 AM | 3.1        | 29.2       | 13.3      | 54.4           |                         |                         | 0.1     | 4.1          | 92.7                 | 92.4                | -8.92                        | -8.92                       |                     |                    | 9.058                        | 9.057                       | -9.34                     | -9.31                        | 28.64                  | 1382         | 34.4353685 | -118.6472477 | Valve Adjustment:NSPS/EG CAI,High O2,Barely Open                                                                                                              |
| CV-25104D  | 8/17/2026 1:22:59 PM  | 19.3       | 57.1       | 3.4       | 20.2           |                         |                         | 0.3     | 5.9          | 100.0                | 95.7                | -0.36                        | -0.37                       |                     |                    | 0.358                        | 0.414                       | -14.70                    | -14.18                       | 28.54                  | 1387         | 34.4353592 | -118.6467327 | Valve Adjustment:Barely Open                                                                                                                                  |
| CV-25104D  | 8/18/2026 9:26:18 AM  | 0.3        | 20.3       | 16.1      | 63.3           |                         |                         | 0.0     | 3.9          | 96.4                 | 96.6                | -8.44                        | -8.13                       |                     |                    | 8.795                        | 8.482                       | -8.23                     | -8.06                        | 28.58                  | 1359         | 34.4353793 | -118.6472452 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed |
| CV-25104S  | 8/11/2026 10:11:37 AM | 4.4        | 69.9       | 0.8       | 24.9           |                         |                         | 0.1     | 31.1         | 140.5                | 140.5               | -9.49                        | -9.39                       |                     |                    | 9.602                        | 9.556                       | -9.43                     | -9.31                        | 28.64                  | 1383         | 34.4353670 | -118.6472462 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Repairs:Valve                                                                               |
| CV-25104S  | 8/11/2026 10:12:55 AM | 3.9        | 71.4       | 0.8       | 23.9           |                         |                         | 0.1     | 29.9         | 140.5                | 140.5               | -9.26                        | -9.26                       |                     |                    | 9.579                        | 9.591                       | -9.24                     | -9.31                        | 28.62                  | 1384         | 34.4353518 | -118.6472645 | Valve Adjustment:NSPS/EG CAI,High Temp                                                                                                                        |
| CV-25104S  | 8/24/2026 11:17:33 AM | 10.0       | 74.9       | 0.2       | 14.9           |                         |                         | 0.1     | 74.5         | 129.0                |                     | -4.50                        |                             |                     |                    | 4.506                        |                             | -5.74                     |                              | 28.57                  | 1350         | 34.4353887 | -118.6472022 |                                                                                                                                                               |
| CV-25105D  | 8/14/2026 9:53:12 AM  | 15.3       | 82.3       | 0.1       | 2.3            |                         |                         | 0.2     | 23.0         | 79.4                 | 82.1                | 0.28                         | -2.60                       |                     |                    | 0.000                        | 2.597                       | -14.82                    | -14.40                       | 28.56                  | 1397         | 34.4353743 | -118.6467063 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)                                  |
| CV-25105D  | 8/14/2026 9:55:09 AM  | 15.7       | 82.1       | 0.1       | 2.1            |                         |                         | 0.2     | 21.0         | 81.3                 | 81.0                | -3.10                        | -3.09                       |                     |                    | 3.088                        | 3.085                       | -13.20                    | -15.31                       | 28.57                  | 1406         | 34.4353687 | -118.6467090 | Valve Adjustment:NSPS/EG CAC,Barely Open                                                                                                                      |
| CV-25105D  | 8/24/2026 11:11:20 AM | 14.9       | 79.9       | 0.2       | 5.0            |                         |                         | 0.2     | 25.0         | 111.0                | 94.5                | -13.88                       | -13.88                      |                     |                    | 14.312                       | 14.321                      | -15.47                    | -13.33                       | 28.56                  | 1383         | 34.4353905 | -118.6466943 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected                                           |
| CV-25105S  | 8/7/2026 2:07:43 PM   | 0.6        | 0.9        | 20.1      | 78.4           |                         |                         | 0.7     | 3.9          | 101.5                | 101.7               | -0.22                        | -0.20                       |                     |                    | 0.154                        | 0.148                       | -16.19                    | -15.70                       | 28.53                  | 1403         | 34.4353872 | -118.6467000 | Valve Adjustment:High O2,Barely Open                                                                                                                          |
| CV-25105S  | 8/7/2026 2:09:12 PM   | 0.2        | 0.7        | 20.7      | 78.4           |                         |                         | 0.3     | 3.8          | 107.3                | 107.6               | -0.11                        | -0.08                       |                     |                    | 0.042                        | 0.003                       | -16.16                    | -16.83                       | 28.52                  | 1399         | 34.4353848 | -118.6467000 | Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected                                   |
| CV-25105S  | 8/17/2026 1:20:35 PM  | 0.9        | 1.4        | 18.9      | 78.8           |                         |                         | 0.6     | 4.2          | 104.2                | 104.1               | -0.17                        | -0.14                       |                     |                    | 0.092                        | 0.087                       | -14.78                    | -14.65                       | 28.53                  | 1378         | 34.4353748 | -118.6467580 | Valve Adjustment:High O2,Barely Open                                                                                                                          |
| CV-25105S  | 8/18/2026 9:21:29 AM  | 2.1        | 77.7       | 1.4       | 18.8           |                         |                         | 0.0     | 13.4         | 107.0                | 108.1               | -8.21                        | -8.34                       |                     |                    | 8.614                        | 8.679                       | -8.12                     | -8.19                        | 28.6                   | 1362         | 34.4353830 | -118.6472463 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)                                                                     |
| CV-25106D  | 8/11/2026 10:06:27 AM | 10.9       | 25.1       | 13.6      | 50.4           |                         |                         | 0.4     | 3.7          | 93.0                 | 92.5                | -9.28                        | -8.75                       |                     |                    | 9.493                        | 9.018                       | -9.36                     | -9.39                        | 28.63                  | 1375         | 34.4350668 | -118.6473752 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum                                                                                                    |
| CV-25106D  | 8/11/2026 10:06:50 AM | 11.3       | 26.8       | 13.5      | 48.4           |                         |                         | 0.4     | 3.6          | 92.1                 | 92.0                | -7.74                        | -7.74                       |                     |                    | 7.850                        | 7.861                       | -9.41                     | -9.41                        | 28.64                  | 1380         | 34.4350705 | -118.6473700 | Valve Adjustment:NSPS/EG CAI,High O2                                                                                                                          |
| CV-25106D  | 8/18/2026 9:31:41 AM  | 17.0       | 57.0       | 4.9       | 21.1           |                         |                         | 0.3     | 4.3          | 96.1                 | 95.6                | -7.59                        | -7.47                       |                     |                    | 7.946                        | 7.937                       | -7.96                     | -8.10                        | 28.6                   | 1358         | 34.4350672 | -118.6473898 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)                                                                     |
| CV-25106S  | 8/11/2026 10:01:57 AM | 13.5       | 31.6       | 10.6      | 44.3           |                         |                         | 0.4     | 4.2          | 100.4                | 100.7               | -9.54                        | -9.09                       |                     |                    | 9.817                        | 9.452                       | -9.53                     | -8.82                        | 28.62                  | 1373         | 34.4350433 | -118.6473735 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum                                                                                                    |
| CV-25106S  | 8/11/2026 10:04:13 AM | 12.7       | 24.8       | 12.3      | 50.2           |                         |                         | 0.5     | 4.1          | 101.0                | 101.0               | -9.51                        | -9.48                       |                     |                    | 9.724                        | 9.676                       | -9.09                     | -9.20                        | 28.63                  | 1376         | 34.4350408 | -118.6473755 | Valve Adjustment:NSPS/EG CAI,High O2,Barely Open                                                                                                              |
| CV-25106S  | 8/18/2026 9:29:12 AM  | 4.7        | 24.8       | 11.3      | 59.2           |                         |                         | 0.2     | 5.2          | 98.9                 | 99.0                | -8.04                        | -8.10                       |                     |                    | 8.352                        | 8.420                       | -7.87                     | -8.00                        | 28.57                  | 1356         | 34.4350595 | -118.6473855 | Valve Adjustment:High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected                                               |
| CV-25107D  | 8/12/2026 8:59:03 AM  | 2.3        | 84.2       | 0.0       | 13.5           |                         |                         | 0.0     | 0.0          | 172.0                | 172.0               | -11.05                       | -10.62                      |                     |                    | 11.173                       | 10.770                      | -13.69                    | -15.40                       | 28.59                  | 1393         | 34.4350453 | -118.6459703 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In);Well Comment:No pump                             |
| CV-25107D  | 8/12/2026 9:01:02 AM  | 2.8        | 84.9       | 0.0       | 12.3           |                         |                         | 0.0     | 0.0          | 172.0                | 172.0               | -10.39                       | -10.67                      |                     |                    | 10.587                       | 10.849                      | -14.28                    | -15.30                       | 28.59                  | 1395         | 34.4350482 | -118.6459737 |                                                                                                                                                               |
| CV-25107D  | 8/12/2026 2:07:00 PM  |            |            |           |                | 5230                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              | AtmA                                                                                                                                                          |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init<br>Flow<br>[scfm] | Adj<br>Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                                 |
|------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|------------------------|-----------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|------------------------------------------------------------------------------------------------------------------------------------------|
| CV-25107D  | 8/17/2026 2:27:16 PM  | 1.7        | 81.9       | 0.2       | 16.2           |                         |                         | 0.0     | 81.0         | 152.0                | 152.0               | -8.96                        | -4.16                       |                        |                       | 9.223                        | 4.187                       | -12.07                    | -11.07                       | 28.53                  | 1393         | 34.4350637 | -118.6459855 | Valve Adjustment: NSPS/EG CAI, High Temp, Decreased Flow/Vacuum, Barely Open, Surging Liquid in Header                                   |
| CV-25107D  | 8/17/2026 2:28:20 PM  | 1.6        | 84.5       | 0.2       | 13.7           |                         |                         | 0.0     | 68.5         | 152.0                | 152.0               | -4.82                        | -4.93                       |                        |                       | 4.776                        | 4.949                       | -13.46                    | -11.37                       | 28.53                  | 1394         | 34.4350563 | -118.6459725 | Valve Adjustment: High Temp, Barely Open, Surging Liquid in Header                                                                       |
| CV-25107D  | 8/20/2026 8:57:15 AM  | 11.0       | 55.1       | 5.7       | 28.2           |                         |                         | 0.2     | 4.9          | 164.5                | 164.4               | -3.10                        | -1.20                       |                        |                       | 3.089                        | 1.192                       | -12.37                    | -9.85                        | 28.56                  | 1416         | 34.4350605 | -118.6459765 | Valve Adjustment: No Flow Measurement, High Temp, Decreased Flow/Vacuum                                                                  |
| CV-25107D  | 8/20/2026 8:59:23 AM  | 13.3       | 77.8       | 0.0       | 8.9            |                         |                         | 0.2     | 0.0          | 164.8                | 164.8               | -2.98                        | -2.98                       |                        |                       | 2.980                        | 3.050                       | -12.04                    | -10.06                       | 28.57                  | 1416         | 34.4350683 | -118.6459652 | Valve Adjustment: No Flow Measurement, High Temp                                                                                         |
| CV-25107D  | 8/25/2026 2:15:42 PM  | 32.5       | 65.8       | 0.0       | 1.7            |                         |                         | 0.5     | 0.0          | 157.5                | 157.5               | 1.95                         | 1.87                        |                        |                       | 0.000                        | 0.000                       | -8.45                     | -7.22                        | 28.55                  | 1384         | 34.4350585 | -118.6459702 | Valve Adjustment: No Flow Measurement, High Temp                                                                                         |
| CV-25107S  | 8/11/2026 2:05:17 PM  | 50.3       | 45.7       | 0.0       | 4.0            |                         |                         | 1.1     | 0.0          | 133.8                | 131.1               | -1.84                        | -1.56                       |                        |                       | 1.846                        | 1.589                       | -15.37                    | -16.38                       | 28.62                  | 1404         | 34.4350765 | -118.6459422 | Valve Adjustment: NSPS/EG CAI, High Temp, Decreased Flow/Vacuum                                                                          |
| CV-25107S  | 8/11/2026 2:08:17 PM  | 50.3       | 47.9       | 0.1       | 1.7            |                         |                         | 1.1     | 17.0         | 126.4                | 125.1               | -1.26                        | -1.21                       |                        |                       | 1.287                        | 1.305                       | -16.15                    | -15.67                       | 28.62                  | 1409         | 34.4350818 | -118.6459493 | Valve Adjustment: NSPS/EG CAC, Barely Open                                                                                               |
| CV-25107S  | 8/17/2026 2:23:38 PM  | 11.4       | 76.2       | 0.5       | 11.9           |                         |                         | 0.1     | 23.8         | 107.0                | 107.0               | -0.64                        | -0.65                       |                        |                       | 0.620                        | 0.621                       | -12.47                    | -11.45                       | 28.54                  | 1389         | 34.4350533 | -118.6459753 | Valve Adjustment: Barely Open                                                                                                            |
| CV-2511    | 8/12/2026 10:39:01 AM | 47.4       | 42.7       | 0.0       | 9.8            |                         |                         | 1.1     | 0.0          | 128.2                | 128.4               | -1.35                        | -1.35                       | 26.6                   | 28.1                  | 0.188                        | 0.209                       | -18.59                    | -18.54                       | 28.68                  | 1257         | 34.4296928 | -118.6501457 |                                                                                                                                          |
| CV-2512    | 8/21/2026 10:27:05 AM | 46.5       | 39.5       | 0.0       | 14.0           |                         |                         | 1.2     | 0.0          | 125.5                | 125.6               | -0.76                        | -0.77                       | 22.9                   | 29.2                  | 0.136                        | 0.219                       | -17.65                    | -16.60                       | 28.78                  | 1245         | 34.4292443 | -118.6506353 | Valve Adjustment: Increased Flow/Vacuum                                                                                                  |
| CV-2513    | 8/12/2026 1:26:37 PM  | 47.7       | 40.4       | 0.0       | 11.9           |                         |                         | 1.2     | 0.0          | 121.2                | 121.3               | -2.96                        | -2.66                       | 37.9                   | 31.7                  | 3.383                        | 2.355                       | -13.47                    | -14.09                       | 28.71                  | 1164         | 34.4287957 | -118.6487757 | Valve Adjustment: Barely Open                                                                                                            |
| CV-2514    | 8/17/2026 12:29:03 PM | 53.4       | 40.3       | 0.0       | 6.3            |                         |                         | 1.3     | 0.0          | 126.2                | 126.1               | -1.00                        | -1.09                       | 25.1                   | 26.8                  | 1.475                        | 1.675                       | -8.58                     | -8.86                        | 28.84                  | 1164         | 34.4296025 | -118.6478172 | Valve Adjustment: Increased Flow/Vacuum                                                                                                  |
| CV-2514    | 8/17/2026 12:31:07 PM | 52.8       | 41.1       | 0.0       | 6.1            |                         |                         | 1.3     | 0.0          | 125.9                | 125.8               | -1.20                        | -1.21                       | 27.9                   | 28.4                  | 1.824                        | 1.883                       | -9.35                     | -9.52                        | 28.83                  | 1154         | 34.4295920 | -118.6478200 |                                                                                                                                          |
| CV-2515    | 8/1/2026 8:31:35 AM   | 44.5       | 37.4       | 0.0       | 18.1           |                         |                         | 1.2     | 0.0          | 115.4                | 115.5               | -2.82                        | -2.65                       | 12.8                   | 11.0                  | 0.378                        | 0.281                       | -16.03                    | -15.94                       | 28.67                  | 1277         | 34.4378623 | -118.6432212 | Valve Adjustment: Audible Flow, Decreased Flow/Vacuum                                                                                    |
| CV-2516    | 8/1/2026 8:49:09 AM   | 50.6       | 42.3       | 0.0       | 7.1            |                         |                         | 1.2     | 0.0          | 127.5                | 127.7               | -5.74                        | -5.76                       | 16.2                   | 16.6                  | 1.717                        | 1.799                       | -11.39                    | -11.62                       | 28.64                  | 1307         | 34.4374102 | -118.6431913 | Valve Adjustment: Audible Flow                                                                                                           |
| CV-2517    | 8/25/2026 1:36:44 PM  | 47.8       | 39.1       | 0.0       | 13.1           |                         |                         | 1.2     | 0.0          | 114.1                | 113.5               | -10.70                       | -10.74                      |                        |                       | 0.059                        | 0.135                       | -12.31                    | -12.56                       | 28.7                   | 1267         | 34.4370248 | -118.6421007 |                                                                                                                                          |
| CV-2517    | 8/26/2026 11:09:47 AM | 46.0       | 35.4       | 0.0       | 18.6           |                         |                         | 1.3     | 0.0          | 118.5                | 118.6               | -4.05                        | -4.05                       | 8.5                    | 8.9                   | 0.198                        | 0.214                       | -16.08                    | -16.32                       | 28.63                  | 1269         | 34.4369458 | -118.6420635 |                                                                                                                                          |
| CV-2518    | 8/26/2026 11:32:46 AM | 50.1       | 37.6       | 0.0       | 12.3           |                         |                         | 1.3     | 0.0          | 111.5                | 111.8               | -3.49                        | -3.75                       | 23.4                   | 25.5                  | 0.140                        | 0.166                       | 0.25                      | 0.41                         | 28.65                  | 1260         | 34.4364005 | -118.6414445 |                                                                                                                                          |
| CV-2519    | 8/17/2026 1:51:01 PM  | 42.3       | 41.5       | 0.0       | 16.2           |                         |                         | 1.0     | 0.0          | 123.7                | 123.6               | -1.26                        | -1.08                       | 25.6                   | 18.9                  | 1.531                        | 0.833                       | -15.23                    | -14.87                       | 28.68                  | 1314         | 34.4361335 | -118.6420587 | Valve Adjustment: Audible Flow, Decreased Flow/Vacuum                                                                                    |
| CV-2520    | 8/17/2026 1:44:25 PM  | 37.1       | 48.8       | 0.0       | 14.1           |                         |                         | 0.8     | 0.0          | 143.8                | 142.1               | -4.99                        | -3.74                       | 8.1                    | 5.8                   | 0.161                        | 0.081                       | -14.83                    | -14.99                       | 28.69                  | 1318         | 34.4358612 | -118.6428098 | Valve Adjustment: NSPS/EG CAI, High Temp, Decreased Flow/Vacuum                                                                          |
| CV-2520    | 8/17/2026 1:44:52 PM  | 37.3       | 49.2       | 0.0       | 13.5           |                         |                         | 0.8     | 0.0          | 141.6                | 141.7               | -3.46                        | -3.45                       | 7.8                    | 7.7                   | 0.149                        | 0.143                       | -15.11                    | -15.08                       | 28.69                  | 1315         | 34.4358688 | -118.6428072 | Valve Adjustment: NSPS/EG CAI, High Temp, Barely Open                                                                                    |
| CV-2521    | 8/20/2026 2:46:52 PM  | 41.1       | 48.3       | 0.0       | 10.6           |                         |                         | 0.9     | 0.0          | 125.0                | 125.0               | -9.39                        | -6.75                       |                        |                       | 9.526                        | 7.078                       | -13.80                    | -14.27                       | 28.54                  | 1350         | 34.4354622 | -118.6430493 | Valve Adjustment: Decreased Flow/Vacuum                                                                                                  |
| CV-2522    | 8/2/2026 1:55:41 PM   | 39.4       | 44.7       | 0.0       | 15.9           |                         |                         | 0.9     | 0.0          | 133.5                | 135.8               | 0.01                         | -0.51                       | 1.7                    | 7.4                   | 0.008                        | 0.155                       | -17.11                    | -16.98                       | 28.53                  | 1297         | 34.4355302 | -118.6423720 | Valve Adjustment: NSPS/EG CAI, NSPS/EG CAC, Positive Static Press., Increased Flow/Vacuum                                                |
| CV-2522    | 8/2/2026 1:57:56 PM   | 40.8       | 44.3       | 0.0       | 14.9           |                         |                         | 0.9     | 0.0          | 137.2                | 138.8               | -0.76                        | -1.29                       | 8.2                    | 11.0                  | 0.187                        | 0.342                       | -17.02                    | -17.09                       | 28.54                  | 1279         | 34.4355032 | -118.6423917 | Valve Adjustment: NSPS/EG CAC, High Temp                                                                                                 |
| CV-2523    | 8/25/2026 7:59:02 AM  | 57.7       | 39.7       | 0.0       | 2.6            |                         |                         | 1.5     | 0.0          | 84.6                 | 84.6                | 3.72                         | 3.74                        | 1.8                    | 4.2                   | 0.008                        | 0.043                       | 3.72                      | 3.72                         | 28.74                  | 1287         | 34.4356773 | -118.6416688 | Valve Adjustment: NSPS/EG CAI, Positive Static Press., Plugged/Pinched Suspected                                                         |
| CV-2523    | 8/25/2026 7:59:59 AM  | 56.9       | 40.2       | 0.0       | 2.9            |                         |                         | 1.4     | 0.0          | 84.7                 | 84.7                | 3.69                         | 3.75                        | 1.5                    | 5.2                   | 0.006                        | 0.069                       | 3.72                      | 3.72                         | 28.73                  | 1295         | 34.4356590 | -118.6416530 |                                                                                                                                          |
| CV-2524    | 8/2/2026 2:13:55 PM   | 43.2       | 42.3       | 0.0       | 14.5           |                         |                         | 1.0     | 0.0          | 142.2                | 141.7               | -5.95                        | -4.76                       | 21.5                   | 14.9                  | 1.325                        | 0.631                       | -14.96                    | -15.37                       | 28.53                  | 1286         | 34.4347963 | -118.6425177 | Valve Adjustment: NSPS/EG CAI, NSPS/EG CAC, High Temp, Decreased Flow/Vacuum                                                             |
| CV-2524    | 8/2/2026 2:14:50 PM   | 41.6       | 42.0       | 0.0       | 16.4           |                         |                         | 1.0     | 0.0          | 141.9                | 141.9               | -4.43                        | -4.41                       | 15.4                   | 15.2                  | 0.673                        | 0.659                       | -15.68                    | -15.42                       | 28.55                  | 1284         | 34.4347880 | -118.6425152 |                                                                                                                                          |
| CV-2525    | 8/19/2026 12:41:01 PM | 33.7       | 33.8       | 1.4       | 31.1           |                         |                         | 1.0     | 22.2         | 119.5                | 119.6               | -7.94                        | -8.01                       | 47.5                   | 48.3                  | 6.285                        | 6.512                       | -13.70                    | -13.68                       | 28.72                  | 1265         | 34.4349720 | -118.6417288 | Valve Adjustment: Decreased Flow/Vacuum, Barely Open, Surging Liquid in Well (Watered In); Well Comment: No pump                         |
| CV-2526    | 8/19/2026 12:31:23 PM | 49.0       | 39.8       | 0.0       | 11.2           |                         |                         | 1.2     | 0.0          | 122.9                | 122.8               | -1.03                        | -1.02                       | 11.4                   | 11.2                  | 0.084                        | 0.081                       | -13.83                    | -13.93                       | 28.74                  | 1258         | 34.4345105 | -118.6415887 | Valve Adjustment: Audible Flow                                                                                                           |
| CV-2527    | 8/11/2026 10:47:53 AM | 52.4       | 45.9       | 0.0       | 1.8            |                         |                         | 1.1     | 0.0          | 135.3                | 135.6               | -4.59                        | -4.59                       |                        |                       | 4.610                        | 4.615                       | -15.43                    | -15.86                       | 28.7                   | 1309         | 34.4340932 | -118.6428747 | Valve Adjustment: NSPS/EG CAI, High Temp, Decreased Flow/Vacuum, Barely Open, Surging Liquid in Well (Watered In); Well Comment: No pump |
| CV-2527    | 8/11/2026 10:49:04 AM | 51.7       | 45.8       | 0.0       | 2.6            |                         |                         | 1.1     | 0.0          | 135.1                | 135.4               | -4.61                        | -4.61                       |                        |                       | 4.642                        | 4.648                       | -15.45                    | -15.94                       | 28.69                  | 1314         | 34.4340932 | -118.6428542 |                                                                                                                                          |
| CV-2527    | 8/27/2026 11:04:02 AM | 44.4       | 45.6       | 0.0       | 10.0           |                         |                         | 1.0     | 0.0          | 132.6                | 132.3               | -4.25                        | -4.27                       |                        |                       | 4.181                        | 4.196                       | -13.51                    | -13.80                       | 28.67                  | 1313         | 34.4340995 | -118.6428723 | Valve Adjustment: NSPS/EG CAI, High Temp, Barely Open, Surging Liquid in Well (Watered In); Well Comment: No pump                        |
| CV-2527    | 8/27/2026 11:06:00 AM | 44.3       | 45.5       | 0.0       | 10.2           |                         |                         | 1.0     | 0.0          | 132.7                | 132.2               | -4.35                        | -4.34                       |                        |                       | 4.290                        | 4.274                       | -13.88                    | -14.02                       | 28.67                  | 1310         | 34.4341022 | -118.6428732 |                                                                                                                                          |
| CV-2528    | 8/5/2026 8:18:27 AM   | 40.3       | 36.2       | 0.0       | 23.5           |                         |                         | 1.1     | 0.0          | 110.4                | 110.4               | -5.43                        | -5.44                       | 19.0                   | 19.0                  | 0.217                        | 0.216                       | -22.67                    |                              | 28.65                  | 1250         | 34.4337923 | -118.6412998 | No Adjustment Made,                                                                                                                      |
| CV-2529    | 8/13/2026 1:19:48 PM  | 52.7       | 33.0       | 2.1       | 12.2           |                         |                         | 1.6     | 5.8          | 109.4                | 109.6               | -5.18                        | -5.25                       | 3.0                    | 2.8                   | 0.972                        | 0.878                       | -15.26                    | -15.39                       | 28.64                  | 1222         | 34.4330943 | -118.6423358 |                                                                                                                                          |
| CV-2529    | 8/19/2026 8:52:11 AM  | 53.1       | 38.5       | 0.6       | 7.8            |                         |                         | 1.4     | 13.0         | 101.4                | 101.7               | -3.30                        | -3.65                       | 2.4                    | 2.7                   | 0.634                        | 0.746                       | -16.76                    | -17.20                       | 28.71                  | 1230         | 34.4331297 | -118.6423467 | Valve Adjustment: Increased Flow/Vacuum, Barely Open                                                                                     |
| CV-2530    | 8/13/2026 1:26:21 PM  | 37.1       | 53.0       | 0.0       | 9.9            |                         |                         | 0.7     | 0.0          | 114.9                | 115.2               | -13.84                       | -13.84                      |                        |                       | 13.756                       | 13.661                      | -15.35                    | -15.68                       | 28.67                  | 1202         | 34.4327487 | -118.6429520 | Valve Adjustment: Valve 100% Open                                                                                                        |
| CV-2530    | 8/19/2026 9:02:12 AM  | 39.5       | 48.6       | 0.0       | 11.9           |                         |                         | 0.8     | 0.0          | 113.7                | 113.9               | -15.28                       | -15.58                      |                        |                       | 15.665                       | 15.871                      | -17.33                    | -17.58                       | 28.73                  | 1224         | 34.4327413 | -118.6429285 | Valve Adjustment: Increased Flow/Vacuum                                                                                                  |
| CV-2531    | 8/6/2026 1:24:59 PM   | 50.2       | 49.8       | 0.0       | 0.0            |                         |                         | 1.0     | 0.0          | 131.7                | 131.7               | -0.32                        | -0.50                       |                        |                       | 0.339                        | 0.507                       | -15.32                    | -15.50                       | 28.79                  | 1230         | 34.4325292 | -118.6433540 | Valve Adjustment: Increased Flow/Vacuum, Barely Open                                                                                     |
| CV-2531    | 8/13/2026 1:29:45 PM  | 36.0       | 54.0       | 0.0       | 10.0           |                         |                         | 0.7     | 0.0          | 118.4                | 118.4               | -0.72                        | -0.71                       |                        |                       | 0.589                        | 0.594                       | -16.13                    | -16.03                       | 28.64                  | 1199         | 34.4325307 | -118.6433498 | Valve Adjustment: Barely Open                                                                                                            |
| CV-2531    | 8/19/2026 9:18:09 AM  | 34.1       | 51.8       | 0.0       | 14.1           |                         |                         | 0.7     | 0.0          | 128.0                | 127.3               | -6.44                        | -6.87                       |                        |                       | 6.700                        | 7.225                       | -17.47                    | -17.41                       | 28.71                  | 1228         | 34.4325258 | -118.6433380 | Valve Adjustment: Increased Flow/Vacuum, Barely Open                                                                                     |
| CV-2532    | 8/6/2026 1:31:23 PM   | 59.3       | 40.7       | 0.0       | 0.0            |                         |                         | 1.5     | 0.0          | 116.6                | 117.0               | -16.46                       | -16.57                      |                        |                       | 17.010                       | 17.084                      | -16.98                    | -17.14                       | 28.78                  | 1224         | 34.4322392 | -118.6437173 | Valve Adjustment: Increased Flow/Vacuum                                                                                                  |

**All LFG Extraction Wells - August 2020**  
**Chiquita Canyon Landfill**

| Point Name  | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>[\"H2O] | Adj Stat<br>Press<br>[\"H2O] | Init<br>Flow<br>[scfm] | Adj<br>Flow<br>[scfm] | Init Diff<br>Press<br>[\"H2O] | Adj Diff<br>Press<br>[\"H2O] | Sys<br>Pressure<br>[\"H2O] | Adj Avail<br>Press<br>[\"H2O] | Baro<br>Press<br>[\"Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                        |                             |
|-------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|-------------------------------|------------------------------|------------------------|-----------------------|-------------------------------|------------------------------|----------------------------|-------------------------------|-------------------------|--------------|------------|--------------|-----------------------------------------------------------------------------------------------------------------|-----------------------------|
| CV-2532     | 8/13/2026 1:36:57 PM  | 50.5       | 47.3       | 0.0       | 2.2            |                         |                         | 1.1     | 0.0          | 101.8                | 101.6               | -16.93                        | -16.88                       |                        |                       | 17.052                        | 17.011                       | -17.41                     | -17.28                        | 28.67                   | 1198         | 34.4322292 | -118.6437287 | Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)                   |                             |
| CV-2533     | 8/13/2026 1:41:31 PM  | 51.9       | 44.9       | 0.1       | 3.1            |                         |                         | 1.2     | 31.0         | 130.1                | 128.4               | -12.14                        | -7.49                        | 44.3                   | 59.2                  | 5.623                         | 9.973                        | -14.24                     | -8.53                         | 28.67                   | 1205         | 34.4318897 | -118.6441028 | Valve Adjustment:Decreased Flow/Vacuum                                                                          |                             |
| CV-2533     | 8/19/2026 9:29:38 AM  | 50.5       | 46.0       | 0.1       | 3.4            |                         |                         | 1.1     | 34.0         | 131.6                | 131.6               | -8.17                         | -8.18                        | 20.3                   | 20.7                  | 0.995                         | 1.033                        | -18.68                     | -18.76                        | 28.71                   | 1231         | 34.4319030 | -118.6440993 | Valve Adjustment:High Temp,Increased Flow/Vacuum                                                                |                             |
| CV-2533     | 8/19/2026 9:30:21 AM  | 50.7       | 44.5       | 0.0       | 4.8            |                         |                         | 1.1     | 0.0          | 131.6                | 131.5               | -8.17                         | -8.17                        | 20.9                   | 21.2                  | 1.057                         | 1.088                        | -18.81                     | -18.86                        | 28.72                   | 1237         | 34.4318978 | -118.6441155 | Valve Adjustment:High Temp                                                                                      |                             |
| CV-2534     | 8/13/2026 1:46:18 PM  | 52.8       | 45.0       | 0.0       | 2.2            |                         |                         | 1.2     | 0.0          | 107.9                | 108.0               | -8.62                         | -8.78                        | 51.9                   | 52.0                  | 3.515                         | 3.536                        | -20.74                     | -20.38                        | 28.67                   | 1204         | 34.4316768 | -118.6444917 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)                                   |                             |
| CV-2535     | 8/26/2026 3:55:06 PM  | 53.9       | 38.8       | 0.0       | 7.3            |                         |                         | 1.4     | 0.0          | 117.4                | 118.2               | 0.16                          | -0.17                        | 3.8                    | 11.9                  | 0.304                         | 3.006                        | -3.33                      | -2.84                         | 28.63                   | 1247         | 34.4309886 | -118.6469119 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.                                                             |                             |
| CV-2535     | 8/26/2026 3:56:07 PM  | 54.2       | 41.9       | 0.0       | 3.9            |                         |                         | 1.3     | 0.0          | 119.0                | 119.1               | -0.24                         | -0.25                        | 12.5                   | 12.2                  | 3.332                         | 3.172                        | -3.09                      | -2.96                         | 28.65                   | 1247         | 34.4309871 | -118.6469133 | Valve Adjustment:NSPS/EG CAC,increased Flow/Vacuum,Valve 100% Open                                              |                             |
| CV-2536     | 8/1/2026 10:48:57 AM  | 47.2       | 42.3       | 2.0       | 8.5            |                         |                         | 1.1     | 4.3          | 106.5                | 107.1               | -9.45                         | -8.48                        | 6.3                    | 5.2                   | 0.826                         | 0.572                        | -11.58                     | -11.25                        | 28.75                   | 1188         | 34.4309938 | -118.6458688 | Valve Comment:RES SEM;Valve Adjustment:Decreased Flow/Vacuum                                                    |                             |
| CV-2537     | 8/18/2026 10:27:49 AM | 44.4       | 37.1       | 0.0       | 18.5           |                         |                         | 1.2     | 0.0          | 116.7                | 117.5               | -1.42                         | -1.42                        |                        |                       | 1.420                         | 1.418                        | -11.17                     | -11.63                        | 28.74                   | 1210         | 34.4310338 | -118.6466582 | Valve Adjustment:Barely Open                                                                                    |                             |
| CV-2538     | 8/18/2026 10:32:39 AM | 42.4       | 38.4       | 0.0       | 19.2           |                         |                         | 1.1     | 0.0          | 124.7                | 124.6               | -1.54                         | -1.51                        | 13.1                   | 12.4                  | 3.673                         | 3.301                        | -12.22                     | -12.60                        | 28.76                   | 1206         | 34.4308118 | -118.6467408 |                                                                                                                 |                             |
| CV-2539     | 8/3/2026 8:50:39 AM   | 42.9       | 41.1       | 0.0       | 16.0           |                         |                         | 1.0     | 0.0          | 119.5                | 119.5               | -1.66                         | -1.66                        |                        |                       | 1.678                         | 1.675                        | -15.68                     | -15.59                        | 28.49                   | 1336         | 34.4317083 | -118.6492247 |                                                                                                                 |                             |
| CV-2539     | 8/17/2026 8:31:58 AM  | 41.7       | 41.0       | 0.0       | 17.4           |                         |                         | 1.0     | 0.0          | 119.3                | 120.0               | -1.65                         | -1.61                        |                        |                       | 1.633                         | 1.617                        | -15.98                     | -15.90                        | 28.68                   | 1322         | 34.4317110 | -118.6492007 |                                                                                                                 |                             |
| CV-2540     | 8/11/2026 8:16:00 AM  | 26.5       | 60.9       | 0.0       | 12.6           |                         |                         | 0.4     | 0.0          | 127.4                | 126.9               | -14.44                        | -13.65                       |                        |                       | 14.717                        | 13.798                       | -17.53                     | -17.28                        | 28.58                   | 1380         | 34.4332505 | -118.6480868 | Valve Adjustment:Audible Flow,Decreased Flow/Vacuum                                                             |                             |
| CV-2540     | 8/18/2026 12:58:19 PM | 30.3       | 63.6       | 0.2       | 5.9            |                         |                         | 0.5     | 29.5         | 118.0                | 110.9               | -9.70                         | -8.35                        |                        |                       | 9.887                         | 8.492                        | -13.19                     | -13.16                        | 28.55                   | 1363         | 34.4332575 | -118.6481138 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |                             |
| CV-2541     | 8/6/2026 9:10:23 AM   | 24.2       | 45.5       | 0.4       | 29.9           |                         |                         | 0.5     | 74.8         | 124.5                | 124.8               | -4.09                         | -3.41                        |                        |                       | 4.092                         | 3.399                        | -13.73                     | -11.40                        | 28.6                    | 1345         | 34.4332988 | -118.6490625 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open                                                              |                             |
| CV-2541     | 8/17/2026 11:11:47 AM | 36.9       | 42.8       | 0.2       | 20.1           |                         |                         | 0.9     | 100.5        | 134.4                | 133.5               | -3.09                         | -2.12                        |                        |                       | 3.081                         | 2.106                        | -3.60                      | -3.46                         | 28.66                   | 1345         | 34.4332783 | -118.6490625 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum                                                    |                             |
| CV-2541     | 8/17/2026 11:12:39 AM | 36.1       | 42.0       | 0.2       | 21.7           |                         |                         | 0.9     | 108.5        | 132.4                | 132.0               | -2.00                         | -2.00                        |                        |                       | 1.987                         | 1.986                        | -4.02                      | -4.42                         | 28.69                   | 1345         | 34.4332875 | -118.6490710 | Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open                                                              |                             |
| CV-2542     | 8/7/2026 8:02:47 AM   | 51.4       | 44.0       | 0.0       | 4.6            |                         |                         | 1.2     | 0.0          | 86.1                 | 86.1                | -3.97                         | -4.54                        |                        |                       | 3.986                         | 4.559                        | -16.84                     | -17.21                        | 28.6                    | 1395         | 34.4337477 | -118.6471902 | Valve Adjustment:Increased Flow/Vacuum,Barely Open                                                              |                             |
| CV-2542     | 8/18/2026 1:52:37 PM  | 47.5       | 52.3       | 0.2       | 0.0            |                         |                         | 0.9     | 0.0          | 98.0                 | 96.6                | -10.80                        | -10.78                       |                        |                       | 10.712                        | 10.763                       | -12.84                     | -12.88                        | 28.5                    | 1381         | 34.4337210 | -118.6471875 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)                                   |                             |
| CV-2543-PLR | 8/6/2026 2:26:06 PM   | 23.2       | 55.6       | 3.3       | 17.9           |                         |                         | 0.4     | 5.4          | 130.6                | 129.9               | -4.26                         | -3.46                        |                        |                       | 4.202                         | 3.398                        | -3.70                      | -4.73                         | 28.51                   | 1354         | 34.4338312 | -118.6484688 | Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)             |                             |
| CV-2543-PLR | 8/18/2026 1:22:58 PM  | 23.1       | 56.9       | 3.0       | 17.0           |                         |                         | 0.4     | 5.7          | 127.7                | 127.3               | -2.55                         | -2.08                        |                        |                       | 2.499                         | 1.956                        | -2.28                      | -2.06                         | 28.56                   | 1355         | 34.4338243 | -118.6484883 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)                       |                             |
| CV-2544     | 8/12/2026 9:31:24 AM  | 7.9        | 86.5       | 0.0       | 5.6            |                         |                         | 0.1     | 0.0          | 83.8                 | 83.1                | -2.08                         | -2.05                        |                        |                       | 2.071                         | 2.085                        | -7.46                      | -7.38                         | 28.52                   | 1386         | 34.4340250 | -118.6472295 | Valve Adjustment:Barely Open                                                                                    |                             |
| CV-2544     | 8/18/2026 10:03:53 AM | 8.3        | 84.5       | 0.2       | 7.0            |                         |                         | 0.1     | 35.0         | 100.0                | 100.0               | -1.39                         | -1.38                        |                        |                       | 1.381                         | 1.354                        | -5.61                      | -5.58                         | 28.56                   | 1366         | 34.4340052 | -118.6472372 | Valve Adjustment:Barely Open                                                                                    |                             |
| CV-2545     | 8/7/2026 9:12:32 AM   | 31.6       | 62.8       | 1.2       | 4.4            |                         |                         | 0.5     | 3.7          | 130.9                | 130.9               | -0.97                         | -1.02                        |                        |                       | 0.959                         | 1.007                        | -7.76                      | -7.98                         | 28.6                    | 1385         | 34.4340312 | -118.6467448 | Valve Adjustment:Barely Open                                                                                    |                             |
| CV-2545     | 8/18/2026 9:07:16 AM  | 30.9       | 63.8       | 1.3       | 4.0            |                         |                         | 0.5     | 3.1          | 125.6                | 125.8               | -0.82                         | -0.81                        |                        |                       | 0.812                         | 0.799                        | -5.84                      | -5.79                         | 28.56                   | 1379         | 34.4340532 | -118.6467365 | Valve Adjustment:Barely Open                                                                                    |                             |
| CV-2546     | 8/7/2026 9:05:45 AM   | 26.7       | 68.6       | 0.0       | 4.7            |                         |                         | 0.4     | 0.0          | 135.0                | 136.1               | -1.85                         | -1.68                        |                        |                       | 1.830                         | 1.682                        | -8.09                      | -8.24                         | 28.59                   | 1384         | 34.4341305 | -118.6469800 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open                                        |                             |
| CV-2546     | 8/7/2026 9:09:38 AM   | 26.2       | 70.2       | 0.0       | 3.6            |                         |                         | 0.4     | 0.0          | 136.3                | 136.3               | -0.93                         | -0.93                        |                        |                       | 0.912                         | 0.907                        | -7.77                      | -8.09                         | 28.6                    | 1384         | 34.4341317 | -118.6469847 | Valve Adjustment:Barely Open                                                                                    |                             |
| CV-2546     | 8/26/2026 1:44:46 PM  | 25.1       | 69.4       | 0.3       | 5.2            |                         |                         | 0.4     | 17.3         | 130.5                | 131.2               | -0.01                         | -0.02                        |                        |                       | 0.000                         | 0.000                        | -3.98                      | -4.33                         | 28.45                   | 1390         | 34.4341360 | -118.6469643 |                                                                                                                 |                             |
| CV-2547     | 8/1/2026 9:46:40 AM   | 50.6       | 48.9       | 0.1       | 0.4            |                         |                         | 1.0     | 4.0          | 112.3                | 112.7               | -4.45                         | -4.45                        |                        |                       | 4.448                         | 4.440                        | -21.17                     | -20.84                        | 28.53                   | 1398         | 34.4339312 | -118.6459810 | Valve Adjustment:Audible Flow,Barely Open;Well Comment:RES SEM                                                  |                             |
| CV-2548     | 8/1/2026 9:14:03 AM   | 9.0        | 82.4       | 0.0       | 8.6            |                         |                         | 0.1     | 0.0          | 141.5                | 141.5               | -2.87                         | -2.87                        | 10.5                   | 10.5                  | 2.451                         | 2.451                        | -20.42                     | -20.42                        | 28.52                   | 1398         | 34.4343578 | -118.6455922 | Valve Adjustment:NSPS/EG CAI,High Temp;Well Comment:RES SEM                                                     |                             |
| CV-2548     | 8/1/2026 9:14:45 AM   | 8.7        | 84.8       | 0.0       | 6.5            |                         |                         | 0.1     | 0.0          | 141.4                | 141.4               | -2.86                         | -2.88                        | 10.5                   | 10.5                  | 2.457                         | 2.440                        | -21.60                     | -21.73                        | 28.53                   | 1394         | 34.4343385 | -118.6455843 | Valve Adjustment:NSPS/EG CAI,High Temp                                                                          |                             |
| CV-2548     | 8/5/2026 12:59:49 PM  | 7.6        | 75.1       | 0.0       | 17.3           |                         |                         | 0.1     | 0.0          | 110.6                | 110.6               | -1.63                         | -1.69                        | 4.4                    | 4.6                   | 2.080                         | 2.332                        | -16.47                     | -18.73                        | 28.63                   | 1381         | 34.4343440 | -118.6455828 | Valve Adjustment:Audible Flow,Increased Flow/Vacuum                                                             |                             |
| CV-2548     | 8/16/2026 12:48:58 PM | 7.1        | 72.7       | 0.0       | 20.3           |                         |                         | 0.1     | 0.0          | 140.3                | 140.2               | -0.51                         | -0.83                        | 37.1                   | 42.5                  | 1.858                         | 2.444                        | -13.54                     | -16.74                        | 28.64                   | 1387         | 34.4343570 | -118.6455942 | Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header;Well Condition:Lorentz Pump Installed           |                             |
| CV-2548     | 8/16/2026 12:50:04 PM | 7.1        | 73.5       | 0.0       | 19.4           |                         |                         | 0.1     | 0.0          | 140.4                | 140.4               | -0.90                         | -0.91                        | 41.9                   | 42.4                  | 2.379                         | 2.429                        | -15.00                     | -15.27                        | 28.64                   | 1395         | 34.4343628 | -118.6455912 | Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed                                                |                             |
| CV-2549     | 8/1/2026 9:10:41 AM   | 42.8       | 52.4       | 0.0       | 4.8            |                         |                         | 0.8     | 0.0          | 117.4                | 117.2               | -3.71                         | -3.47                        | 19.4                   | 11.8                  | 1.034                         | 0.378                        | -18.20                     | -18.32                        | 28.54                   | 1407         | 34.4343802 | -118.6452528 | Valve Adjustment:Audible Flow,Decreased Flow/Vacuum                                                             |                             |
| CV-2549     | 8/16/2026 12:42:01 PM | 43.8       | 48.1       | 0.0       | 8.1            |                         |                         | 0.9     | 0.0          | 117.1                | 117.1               | -1.73                         | -1.74                        | 12.6                   | 15.2                  | 0.365                         | 0.536                        | -13.52                     | -14.93                        | 28.66                   | 1409         | 34.4344028 | -118.6452333 | Valve Adjustment:Increased Flow/Vacuum                                                                          |                             |
| CV-2549     | 8/16/2026 12:42:50 PM | 43.2       | 48.0       | 0.0       | 8.8            |                         |                         | 0.9     | 0.0          | 117.2                | 117.3               | -1.78                         | -1.78                        | 15.1                   | 15.4                  | 0.530                         | 0.552                        | -16.10                     | -16.15                        | 28.65                   | 1398         | 34.4343847 | -118.6452630 |                                                                                                                 |                             |
| CV-2550     | 8/3/2026 1:40:00 PM   |            |            |           |                |                         | 65300                   |         |              |                      |                     |                               |                              |                        |                       |                               |                              |                            |                               |                         |              |            |              |                                                                                                                 | AtmAA; [User entered 6.53%] |
| CV-2550     | 8/3/2026 1:40:00 PM   |            |            |           |                | 1330                    |                         |         |              |                      |                     |                               |                              |                        |                       |                               |                              |                            |                               |                         |              |            |              |                                                                                                                 | AtmAA                       |
| CV-2550     | 8/3/2026 1:48:07 PM   | 1.7        | 64.7       | 1.3       | 32.3           |                         |                         | 0.0     | 24.8         | 211.6                | 206.2               | -0.02                         | -0.02                        |                        |                       | 0.004                         | 0.004                        | 0.16                       | 0.13                          | 28.39                   | 1382         | 34.4348163 | -118.6461585 | Valve Comment:Active PLR;Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Well (Watered In)     |                             |
| CV-2550     | 8/11/2026 8:27:32 AM  | 6.4        | 81.2       | 0.0       | 12.4           |                         |                         | 0.1     | 0.0          | 178.1                | 178.6               | -16.82                        | -16.51                       |                        |                       | 17.253                        | 16.798                       | -18.43                     | -17.85                        | 28.6                    | 1392         | 34.4348211 | -118.6461700 | Valve Adjustment:No Flow Measurement,High Temp                                                                  |                             |
| CV-2550     | 8/11/2026 8:30:00 AM  |            |            |           |                | 3080                    |                         |         |              |                      |                     |                               |                              |                        |                       |                               |                              |                            |                               |                         |              |            |              |                                                                                                                 | AtmAA                       |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name  | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init<br>Flow<br>[scfm] | Adj<br>Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                  |                                                                                                                                                         |
|-------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|------------------------|-----------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|-------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------|
| CV-2550     | 8/19/2026 8:30:01 AM  | 7.1        | 85.6       | 0.1       | 7.2            |                         |                         | 0.1     | 72.0         | 187.3                | 187.5               | -14.38                       | -13.90                      |                        |                       | 14.661                       | 14.231                      | -16.25                    | -15.52                       | 28.52                  | 1385         | 34.4348237 | -118.6461537 | Valve Adjustment:No Flow Measurement,High Temp                                            |                                                                                                                                                         |
| CV-2550     | 8/26/2026 8:00:58 AM  | 1.8        | 84.6       | 0.0       | 13.6           |                         |                         | 0.0     | 0.0          | 176.1                | 176.2               | -14.78                       | -14.49                      |                        |                       | 15.027                       | 14.730                      | -18.75                    | -18.40                       | 28.49                  | 1408         | 34.4347938 | -118.6461664 | Valve Adjustment:No Flow Measurement,High Temp                                            |                                                                                                                                                         |
| CV-2551     | 8/5/2026 8:20:00 AM   |            |            |           |                |                         | 64200                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                           | AtmAA; [User entered 6.42%]                                                                                                                             |
| CV-2551     | 8/5/2026 8:20:00 AM   |            |            |           |                | 2250                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                           | AtmAA                                                                                                                                                   |
| CV-2551     | 8/11/2026 8:05:00 AM  |            |            |           |                | 3000                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                           | AtmAA                                                                                                                                                   |
| CV-2551     | 8/11/2026 8:07:46 AM  | 30.2       | 67.5       | 0.0       | 2.3            |                         |                         | 0.4     | 0.0          | 160.2                | 160.4               | -7.76                        | -7.75                       |                        |                       | 8.166                        | 8.159                       | -19.31                    | -18.76                       | 28.59                  | 1396         | 34.4349337 | -118.6458222 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed     |                                                                                                                                                         |
| CV-2551     | 8/18/2026 10:27:16 AM | 39.2       | 60.8       | 0.0       | 0.0            |                         |                         | 0.6     | 0.0          | 162.2                | 162.0               | -6.53                        | -6.49                       |                        |                       | 7.001                        | 7.111                       | -15.43                    | -15.45                       | 28.6                   | 1392         | 34.4349410 | -118.6458088 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed     |                                                                                                                                                         |
| CV-2551     | 8/18/2026 10:30:00 AM |            |            |           |                | 1010                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                           | AtmAA                                                                                                                                                   |
| CV-2551     | 8/25/2026 2:09:30 PM  | 33.6       | 66.4       | 0.0       | 0.0            |                         |                         | 0.5     | 0.0          | 146.4                | 146.5               | -6.10                        | -6.14                       |                        |                       | 6.214                        | 6.303                       | -15.05                    | -13.52                       | 28.54                  | 1391         | 34.4349432 | -118.6458475 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed     |                                                                                                                                                         |
|             |                       |            |            |           |                |                         |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                           | Valve Adjustment:NSPS/EG CAI,High Temp;Well Comment:No sample ports on well side. Reading taken from system side.;Well Condition:Lorentz Pump Installed |
| CV-2552     | 8/12/2026 8:30:47 AM  | 15.3       | 74.2       | 1.3       | 9.2            |                         |                         | 0.2     | 7.1          | 176.7                | 176.9               | -18.11                       | -18.89                      |                        |                       | 18.209                       | 18.962                      | 0.00                      | 0.00                         | 28.59                  | 1387         | 34.4348645 | -118.6465415 |                                                                                           |                                                                                                                                                         |
| CV-2552     | 8/12/2026 8:32:40 AM  | 13.8       | 75.9       | 0.5       | 9.8            |                         |                         | 0.2     | 19.6         | 177.2                | 177.2               | -15.64                       | -15.27                      |                        |                       | 15.727                       | 15.310                      | 0.00                      | 0.00                         | 28.58                  | 1393         | 34.4348465 | -118.6465440 |                                                                                           |                                                                                                                                                         |
| CV-2552     | 8/18/2026 1:30:00 PM  |            |            |           |                | 1810                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                           | AtmAA                                                                                                                                                   |
| CV-2552     | 8/18/2026 1:32:07 PM  | 32.6       | 66.7       | 0.7       | 0.0            |                         |                         | 0.5     | 0.0          | 175.4                | 175.4               | -14.98                       | -14.79                      |                        |                       | 15.151                       | 15.048                      | 0.00                      | 0.00                         | 28.53                  | 1367         | 34.4348847 | -118.6465324 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed      |                                                                                                                                                         |
| CV-2552     | 8/26/2026 8:07:27 AM  | 11.9       | 78.3       | 0.8       | 9.0            |                         |                         | 0.2     | 11.3         | 174.2                | 174.2               | -15.13                       | -15.15                      |                        |                       | 15.471                       | 15.459                      | 0.04                      | 0.04                         | 28.5                   | 1398         | 34.4348731 | -118.6465346 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed      |                                                                                                                                                         |
| CV-2553     | 8/6/2026 2:44:31 PM   | 33.9       | 56.9       | 0.2       | 9.0            |                         |                         | 0.6     | 45.0         | 117.0                | 117.0               | -5.40                        | -5.36                       |                        |                       | 5.571                        | 5.563                       | -14.30                    | -14.21                       | 28.52                  | 1358         | 34.4341690 | -118.6489137 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In) |                                                                                                                                                         |
| CV-2553     | 8/18/2026 1:32:15 PM  | 36.9       | 56.8       | 0.2       | 6.1            |                         |                         | 0.6     | 30.5         | 110.0                | 97.4                | -5.07                        | -4.80                       |                        |                       | 5.268                        | 4.812                       | -13.94                    | -13.85                       | 28.55                  | 1342         | 34.4341723 | -118.6489205 | Valve Adjustment:Decreased Flow/Vacuum                                                    |                                                                                                                                                         |
| CV-2554     | 8/5/2026 9:30:00 AM   |            |            |           |                |                         | 54500                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                           | AtmAA; [User entered 5.45%]                                                                                                                             |
| CV-2554     | 8/5/2026 9:30:00 AM   |            |            |           |                | 678                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                           | AtmAA                                                                                                                                                   |
| CV-2554     | 8/11/2026 9:08:32 AM  | 48.1       | 51.4       | 0.4       | 0.1            |                         |                         | 0.9     | 0.3          | 165.8                | 166.6               | -9.44                        | -9.44                       |                        |                       | 10.012                       | 10.122                      | -9.71                     | -9.77                        | 28.64                  | 1361         | 34.4344613 | -118.6482497 | Valve Adjustment:No Flow Measurement,High Temp                                            |                                                                                                                                                         |
| CV-2554     | 8/11/2026 9:15:00 AM  |            |            |           |                | 529                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                           | AtmAA                                                                                                                                                   |
| CV-2554     | 8/12/2026 1:35:00 PM  |            |            |           |                | 1740                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                           | AtmAA                                                                                                                                                   |
| CV-2554     | 8/19/2026 9:39:49 AM  | 35.7       | 64.2       | 0.0       | 0.1            |                         |                         | 0.6     | 0.0          | 155.7                | 155.9               | -6.28                        | -6.07                       |                        |                       | 6.830                        | 6.730                       | -6.30                     | -6.15                        | 28.57                  | 1353         | 34.4344798 | -118.6482537 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed      |                                                                                                                                                         |
| CV-2554     | 8/26/2026 9:14:20 AM  | 9.9        | 76.2       | 0.0       | 13.9           |                         |                         | 0.1     | 0.0          | 164.9                | 165.2               | -9.93                        | -9.81                       |                        |                       | 10.558                       | 10.317                      | -10.06                    | -9.92                        | 28.57                  | 1375         | 34.4344799 | -118.6482981 | Valve Adjustment:No Flow Measurement,High Temp                                            |                                                                                                                                                         |
| CV-2555     | 8/11/2026 9:56:58 AM  | 34.7       | 62.0       | 0.0       | 3.3            |                         |                         | 0.6     | 0.0          | 137.5                | 137.3               | -2.35                        | -1.97                       |                        |                       | 0.000                        | 0.000                       | -8.19                     | -8.01                        | 28.64                  | 1367         | 34.4348153 | -118.6477032 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum                              |                                                                                                                                                         |
| CV-2555     | 8/11/2026 9:57:25 AM  | 35.9       | 64.1       | 0.0       | 0.0            |                         |                         | 0.6     | 0.0          | 137.1                | 137.3               | -1.78                        | -1.77                       |                        |                       | 0.000                        | 0.000                       | -8.19                     | -8.14                        | 28.64                  | 1371         | 34.4348182 | -118.6477075 | Valve Adjustment:NSPS/EG CAI,High Temp                                                    |                                                                                                                                                         |
| CV-2555     | 8/24/2026 12:20:10 PM | 32.7       | 64.1       | 0.0       | 3.2            |                         |                         | 0.5     | 0.0          | 139.1                | 138.6               | -0.24                        | -0.24                       | 10.9                   | 11.0                  | 0.787                        | 0.787                       | -6.06                     | -6.06                        | 28.69                  | 1359         | 34.4348258 | -118.6476922 | Valve Adjustment:NSPS/EG CAI,High Temp                                                    |                                                                                                                                                         |
| CV-2555     | 8/24/2026 12:20:59 PM | 32.2       | 64.7       | 0.0       | 3.1            |                         |                         | 0.5     | 0.0          | 138.7                | 138.6               | -0.37                        | -0.37                       | 10.7                   | 10.6                  | 0.748                        | 0.737                       | -5.91                     | -5.88                        | 28.71                  | 1367         | 34.4348108 | -118.6477032 |                                                                                           |                                                                                                                                                         |
| CV-2556-PLF | 8/4/2026 1:30:00 PM   |            |            |           |                |                         | 94900                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                           | AtmAA; [User entered 9.49%]                                                                                                                             |
| CV-2556-PLF | 8/4/2026 1:30:00 PM   |            |            |           |                | 3060                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                           | AtmAA                                                                                                                                                   |
| CV-2556-PLF | 8/4/2026 1:37:57 PM   | 32.9       | 63.6       | 0.0       | 3.5            |                         |                         | 0.5     | 0.0          | 184.2                | 184.7               | -5.49                        | -4.89                       |                        |                       | 5.826                        | 5.206                       | 0.20                      | 0.17                         | 28.49                  | 1375         | 34.4351415 | -118.6472042 | Valve Adjustment:No Flow Measurement,High Temp                                            |                                                                                                                                                         |
| CV-2556-PLF | 8/11/2026 8:37:19 AM  | 9.2        | 79.8       | 0.2       | 10.8           |                         |                         | 0.1     | 54.0         | 190.4                | 190.5               | -0.49                        | -0.50                       |                        |                       | 0.501                        | 0.486                       | 0.34                      | 0.34                         | 28.62                  | 1384         | 34.4351483 | -118.6472252 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed      |                                                                                                                                                         |
| CV-2556-PLF | 8/11/2026 8:45:00 AM  |            |            |           |                | 3310                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                           | AtmAA                                                                                                                                                   |
| CV-2556-PLF | 8/18/2026 1:40:59 PM  | 44.5       | 53.1       | 0.0       | 2.4            |                         |                         | 0.8     | 0.0          | 187.2                | 187.4               | -0.19                        | -0.19                       |                        |                       | 0.195                        | 0.204                       | 0.00                      | 0.00                         | 28.56                  | 1368         | 34.4351441 | -118.6472163 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed      |                                                                                                                                                         |
| CV-2556-PLF | 8/18/2026 1:55:00 PM  |            |            |           |                | 2550                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                           | AtmAA                                                                                                                                                   |
| CV-2556-PLF | 8/26/2026 8:20:38 AM  | 6.9        | 65.0       | 3.4       | 24.7           |                         |                         | 0.1     | 7.3          | 183.6                | 183.6               | -0.84                        | -0.80                       |                        |                       | 0.847                        | 0.857                       | 0.34                      | 0.34                         | 28.55                  | 1370         | 34.4351590 | -118.6472279 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed      |                                                                                                                                                         |
| CV-2557     | 8/14/2026 9:48:07 AM  | 4.4        | 83.1       | 0.2       | 12.3           |                         |                         | 0.1     | 61.5         | 133.0                | 133.3               | -0.29                        | -0.28                       |                        |                       | 0.278                        | 0.267                       | -15.90                    | -15.52                       | 28.56                  | 1389         | 34.4354907 | -118.6464945 |                                                                                           |                                                                                                                                                         |
| CV-2557     | 8/28/2026 8:51:17 AM  | 3.4        | 84.8       | 0.0       | 11.8           |                         |                         | 0.0     | 0.0          | 134.2                | 134.0               | -0.42                        | -0.42                       |                        |                       | 0.412                        | 0.414                       | -16.25                    | -15.28                       | 28.45                  | 1393         | 34.4354827 | -118.6464810 | Valve Adjustment:High Temp                                                                |                                                                                                                                                         |
| CV-2558-PLF | 8/6/2026 10:20:00 AM  |            |            |           |                |                         | 132300                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                           | AtmAA; [User entered 13.23%]                                                                                                                            |
| CV-2558-PLF | 8/6/2026 10:20:00 AM  |            |            |           |                | 1580                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                           | AtmAA                                                                                                                                                   |
| CV-2558-PLF | 8/13/2026 2:45:00 PM  |            |            |           |                | 3500                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                           | AtmAA                                                                                                                                                   |
|             |                       |            |            |           |                |                         |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                           | Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open,Surging Liquid in Well (Watered In)                                                      |
| CV-2558-PLF | 8/13/2026 2:57:59 PM  | 16.7       | 76.7       | 0.0       | 6.6            |                         |                         | 0.2     | 0.0          | 193.0                | 192.0               | 1.34                         | 1.54                        |                        |                       | 0.000                        | 0.000                       | 0.08                      | -0.17                        | 28.49                  | 1386         | 34.4352876 | -118.6463034 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed     |                                                                                                                                                         |
| CV-2558-PLF | 8/20/2026 9:31:02 AM  | 32.3       | 67.7       | 0.0       | 0.0            |                         |                         | 0.5     | 0.0          | 199.1                | 199.3               | -36.72                       | -36.44                      |                        |                       | 33.370                       | 33.370                      | 0.35                      | 0.34                         | 28.6                   | 1408         | 34.4353024 | -118.6462907 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed     |                                                                                                                                                         |
| CV-2558-PLF | 8/20/2026 9:35:43 AM  | 31.8       | 68.2       | 0.0       | 0.0            |                         |                         | 0.5     | 0.0          | 198.3                | 198.3               | 9.57                         | 9.35                        |                        |                       | 0.000                        | 0.000                       | 0.34                      | 0.34                         | 28.57                  | 1408         | 34.4352916 | -118.6462930 | Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed     |                                                                                                                                                         |
|             |                       |            |            |           |                |                         |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                           | Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Well (Watered In)                               |
| CV-2558-PLF | 8/25/2026 2:35:31 PM  | 30.7       | 69.3       | 0.0       | 0.0            |                         |                         | 0.4     | 0.0          | 188.7                | 188.5               | 18.19                        | 24.09                       |                        |                       | 0.000                        | 0.000                       | 0.30                      | 0.30                         | 28.53                  | 1391         | 34.4353040 | -118.6463068 |                                                                                           |                                                                                                                                                         |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name  | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init<br>Flow<br>[scfm] | Adj<br>Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                                           |
|-------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|------------------------|-----------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|----------------------------------------------------------------------------------------------------------------------------------------------------|
| CV-2558-PLF | 8/25/2026 2:36:30 PM  | 32.3       | 67.7       | 0.0       | 0.0            |                         |                         | 0.5     | 0.0          | 189.2                | 189.6               | 16.51                        | 15.92                       |                        |                       | 0.000                        | 0.000                       | 0.30                      | 0.30                         | 28.52                  | 1392         | 34.4353020 | -118.6463067 | Valve Comment:Active plr;Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Well (Watered In) |
| CV-2559     | 8/11/2026 1:18:33 PM  | 24.6       | 63.1       | 0.0       | 12.3           |                         |                         | 0.4     | 0.0          | 139.4                | 139.7               | -2.50                        | -0.51                       |                        |                       | 2.507                        | 0.486                       | -4.68                     | -4.90                        | 28.6                   | 1386         | 34.4357617 | -118.6454607 | Valve Adjustment: NSPS/EG CAI,High O2,Decreased Flow/Vacuum                                                                                        |
| CV-2559     | 8/11/2026 1:19:59 PM  | 6.7        | 74.0       | 0.0       | 19.2           |                         |                         | 0.1     | 0.0          | 139.0                | 139.4               | -0.64                        | -0.68                       |                        |                       | 0.614                        | 0.705                       | -4.86                     | -4.90                        | 28.61                  | 1395         | 34.4357478 | -118.6454615 |                                                                                                                                                    |
| CV-2559     | 8/24/2026 11:43:25 AM | 13.7       | 79.2       | 0.2       | 6.9            |                         |                         | 0.2     | 34.5         | 136.1                | 136.2               | -1.72                        | -1.22                       |                        |                       | 1.681                        | 1.173                       | -4.73                     | -4.85                        | 28.56                  | 1382         | 34.4357745 | -118.6454507 | Valve Adjustment: NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open                                                                          |
| CV-2559     | 8/24/2026 11:44:06 AM | 13.5       | 79.9       | 0.2       | 6.4            |                         |                         | 0.2     | 32.0         | 136.5                | 136.5               | -1.15                        | -1.14                       |                        |                       | 1.119                        | 1.133                       | -4.80                     | -4.85                        | 28.56                  | 1383         | 34.4357747 | -118.6454683 | Valve Adjustment:High Temp,Barely Open                                                                                                             |
| CV-2560     | 8/7/2026 2:27:06 PM   | 12.1       | 47.8       | 1.7       | 38.4           |                         |                         | 0.3     | 22.6         | 120.5                | 120.7               | -0.84                        | -0.88                       |                        |                       | 0.809                        | 0.811                       | -9.39                     | -9.18                        | 28.51                  | 1409         | 34.4359327 | -118.6466408 | Valve Adjustment:Barely Open                                                                                                                       |
| CV-2560     | 8/17/2026 1:49:19 PM  | 9.8        | 79.5       | 0.1       | 10.6           |                         |                         | 0.1     | 106.0        | 134.3                | 134.8               | 1.12                         | -0.04                       |                        |                       | 0.000                        | 0.027                       | -6.13                     | -5.42                        | 28.54                  | 1392         | 34.4359187 | -118.6466657 | Valve Adjustment: NSPS/EG CAI,Positive Static Press.,Surging Liquid in Header,Surging Liquid in Well (Watered In)                                  |
| CV-2560     | 8/17/2026 1:50:51 PM  | 10.3       | 79.4       | 0.2       | 10.1           |                         |                         | 0.1     | 50.5         | 133.0                | 132.7               | -0.85                        | -0.84                       |                        |                       | 0.842                        | 0.849                       | -5.83                     | -5.56                        | 28.52                  | 1402         | 34.4359133 | -118.6466705 | Valve Adjustment: NSPS/EG CAC,High Temp,Barely Open                                                                                                |
| CV-2561     | 8/7/2026 2:39:07 PM   | 9.5        | 43.3       | 0.5       | 46.7           |                         |                         | 0.2     | 93.4         | 110.0                | 110.0               | -0.37                        | -0.38                       |                        |                       | 0.355                        | 0.353                       | -2.40                     | -2.40                        | 28.52                  | 1400         | 34.4360838 | -118.6465923 |                                                                                                                                                    |
| CV-2561     | 8/17/2026 1:54:54 PM  | 16.2       | 72.7       | 0.2       | 10.9           |                         |                         | 0.2     | 54.5         | 150.2                | 150.1               | -2.31                        | -2.20                       |                        |                       | 2.112                        | 2.087                       | -2.97                     | -2.93                        | 28.53                  | 1391         | 34.4360510 | -118.6464075 | Valve Adjustment: NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header                                                 |
| CV-2561     | 8/17/2026 2:00:27 PM  | 14.6       | 53.5       | 0.3       | 31.6           |                         |                         | 0.3     | 105.3        | 115.0                | 116.0               | -0.24                        | -0.25                       |                        |                       | 0.203                        | 0.221                       | -2.76                     | -2.78                        | 28.52                  | 1387         | 34.4360870 | -118.6466350 | Valve Adjustment:Barely Open                                                                                                                       |
| CV-2562     | 8/24/2026 11:33:40 AM | 34.1       | 60.2       | 0.1       | 5.6            |                         |                         | 0.6     | 56.0         | 133.5                | 133.5               | -1.71                        | -1.51                       |                        |                       | 0.000                        | 0.000                       | -3.86                     | -3.96                        | 28.56                  | 1382         | 34.4360817 | -118.6459173 | Valve Adjustment: NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header                                                             |
| CV-2562     | 8/24/2026 11:34:20 AM | 34.1       | 60.1       | 0.2       | 5.6            |                         |                         | 0.6     | 28.0         | 133.5                | 133.6               | -1.44                        | -1.46                       |                        |                       | 0.000                        | 0.000                       | -3.93                     | -3.82                        | 28.56                  | 1378         | 34.4361077 | -118.6459227 | Valve Adjustment:High Temp,Surging Liquid in Header                                                                                                |
| CV-2563     | 8/5/2026 12:01:02 PM  | 44.2       | 51.2       | 0.0       | 4.6            |                         |                         | 0.9     | 0.0          | 123.6                | 122.8               | -6.28                        | -5.34                       | 0.8                    | 1.1                   | 0.013                        | 0.027                       | -8.79                     |                              | 28.6                   | 1253         | 34.4372812 | -118.6457553 |                                                                                                                                                    |
| CV-2564     | 8/6/2026 8:51:33 AM   | 38.1       | 56.7       | 0.1       | 5.1            |                         |                         | 0.7     | 51.0         | 118.6                | 118.7               | -5.71                        | -4.98                       |                        |                       | 5.869                        | 5.189                       | -17.22                    | -17.21                       | 28.6                   | 1357         | 34.4331477 | -118.6487413 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                             |
| CV-2564     | 8/17/2026 10:53:34 AM | 36.9       | 57.7       | 0.0       | 5.4            |                         |                         | 0.6     | 0.0          | 126.8                | 126.4               | -4.10                        | -3.63                       |                        |                       | 4.068                        | 3.652                       | -11.31                    | -9.72                        | 28.66                  | 1366         | 34.4331168 | -118.6487500 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                             |
| CV-2565     | 8/3/2026 10:08:20 AM  | 31.0       | 39.6       | 0.0       | 29.4           |                         |                         | 0.8     | 0.0          | 116.0                | 116.1               | -0.85                        | -0.50                       |                        |                       | 0.856                        | 0.489                       | -15.44                    | -15.46                       | 28.46                  | 1323         | 34.4319712 | -118.6490075 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                             |
| CV-2565     | 8/3/2026 10:09:18 AM  | 30.6       | 39.5       | 0.0       | 29.9           |                         |                         | 0.8     | 0.0          | 115.7                | 115.6               | -0.62                        | -0.62                       |                        |                       | 0.620                        | 0.620                       | -15.48                    | -15.47                       | 28.49                  | 1336         | 34.4319810 | -118.6490073 |                                                                                                                                                    |
| CV-2565     | 8/17/2026 10:18:31 AM | 36.9       | 42.3       | 0.0       | 20.8           |                         |                         | 0.9     | 0.0          | 112.5                | 112.6               | -0.55                        | -0.55                       |                        |                       | 0.558                        | 0.558                       | -14.32                    | -14.52                       | 28.68                  | 1322         | 34.4319887 | -118.6489928 |                                                                                                                                                    |
| CV-2566     | 8/11/2026 9:35:42 AM  | 58.2       | 41.8       | 0.0       | 0.0            |                         |                         | 1.4     | 0.0          | 119.7                | 120.1               | -4.30                        | -4.91                       |                        |                       | 4.340                        | 4.944                       | -14.97                    | -14.84                       | 28.67                  | 1332         | 34.4317912 | -118.6487605 | Valve Adjustment:Increased Flow/Vacuum                                                                                                             |
| CV-2566     | 8/17/2026 10:14:52 AM | 45.5       | 43.1       | 0.0       | 11.4           |                         |                         | 1.1     | 0.0          | 112.7                | 113.2               | -4.62                        | -3.93                       |                        |                       | 4.649                        | 3.957                       | -12.74                    | -15.06                       | 28.69                  | 1312         | 34.4318117 | -118.6487635 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                             |
| CV-2566     | 8/17/2026 10:16:01 AM | 45.0       | 43.6       | 0.0       | 11.4           |                         |                         | 1.0     | 0.0          | 113.4                | 113.4               | -3.73                        | -3.72                       |                        |                       | 3.760                        | 3.742                       | -13.52                    | -14.28                       | 28.68                  | 1315         | 34.4318538 | -118.6487495 |                                                                                                                                                    |
| CV-2567     | 8/5/2026 10:03:59 AM  | 47.8       | 42.2       | 0.0       | 10.0           |                         |                         | 1.1     | 0.0          | 116.6                | 116.4               | -2.88                        | -2.85                       | 0.0                    | 0.0                   | 2.843                        | 2.842                       | -14.99                    |                              | 28.55                  | 1335         | 34.4320060 | -118.6481185 |                                                                                                                                                    |
| CV-2567     | 8/21/2026 7:52:51 AM  | 50.0       | 45.9       | 0.0       | 4.1            |                         |                         | 1.1     | 0.0          | 106.4                | 106.9               | -3.01                        | -3.01                       |                        |                       | 3.008                        | 3.011                       | -13.84                    | -14.64                       | 28.6                   | 1357         | 34.4319615 | -118.6480833 | Valve Adjustment:Barely Open                                                                                                                       |
| CV-2568     | 8/5/2026 9:15:10 AM   | 37.6       | 37.9       | 0.4       | 24.1           |                         |                         | 1.0     | 60.3         | 105.9                | 105.9               | -1.02                        | -0.99                       | 0.0                    | 0.0                   | 0.955                        | 0.953                       | -11.03                    |                              | 28.54                  | 1332         | 34.4322103 | -118.6476982 |                                                                                                                                                    |
| CV-2568     | 8/26/2026 12:55:37 PM | 41.2       | 40.5       | 0.1       | 18.2           |                         |                         | 1.0     | 182.0        | 122.0                | 122.0               | -0.34                        | -0.29                       |                        |                       | 0.328                        | 0.283                       | -6.94                     | -6.79                        | 28.49                  | 1353         | 34.4321713 | -118.6477307 | Valve Adjustment:Barely Open                                                                                                                       |
| CV-2569     | 8/5/2026 9:17:20 AM   | 41.0       | 41.7       | 0.1       | 17.2           |                         |                         | 1.0     | 172.0        | 122.0                | 120.9               | -0.87                        | -0.82                       | 0.0                    | 0.0                   | 0.851                        | 0.828                       | -11.08                    |                              | 28.55                  | 1335         | 34.4322205 | -118.6473910 |                                                                                                                                                    |
| CV-2569     | 8/17/2026 2:07:39 PM  | 46.8       | 45.3       | 0.0       | 7.9            |                         |                         | 1.0     | 0.0          | 106.2                | 106.2               | -0.31                        | -0.30                       |                        |                       | 0.288                        | 0.288                       | -6.57                     | -6.86                        | 28.64                  | 1342         | 34.4322355 | -118.6474240 | Valve Adjustment:Barely Open                                                                                                                       |
| CV-2570     | 8/5/2026 9:33:18 AM   | 53.4       | 43.2       | 0.1       | 3.3            |                         |                         | 1.2     | 33.0         | 114.4                | 115.8               | -0.83                        | -0.84                       | 0.0                    | 0.0                   | 0.742                        | 0.901                       | -10.27                    |                              | 28.55                  | 1342         | 34.4324005 | -118.6469865 |                                                                                                                                                    |
| CV-2570     | 8/17/2026 2:10:01 PM  | 42.6       | 41.6       | 0.0       | 15.8           |                         |                         | 1.0     | 0.0          | 106.5                | 106.6               | -0.35                        | -0.34                       |                        |                       | 0.335                        | 0.304                       | -7.63                     | -6.54                        | 28.64                  | 1340         | 34.4321782 | -118.6477733 | Valve Adjustment:Barely Open                                                                                                                       |
| CV-2571     | 8/18/2026 2:09:31 PM  | 45.1       | 37.9       | 0.0       | 17.0           |                         |                         | 1.2     | 0.0          | 97.9                 | 97.9                | -11.15                       | -11.11                      | 107.6                  | 106.9                 | 2.827                        | 2.789                       | -16.92                    | -16.78                       | 28.83                  | 1138         | 34.4299418 | -118.6457378 |                                                                                                                                                    |
| CV-2572     | 8/6/2026 12:11:12 PM  | 64.5       | 35.5       | 0.0       | 0.0            |                         |                         | 1.8     | 0.0          | 126.1                | 126.2               | -1.74                        | -1.85                       |                        |                       | 0.000                        | 0.000                       | -7.74                     | -8.08                        | 28.86                  | 1148         | 34.4298033 | -118.6470543 | Valve Adjustment:Increased Flow/Vacuum                                                                                                             |
| CV-2572     | 8/17/2026 1:02:07 PM  | 49.4       | 39.1       | 0.0       | 11.5           |                         |                         | 1.3     | 0.0          | 122.5                | 122.6               | -4.25                        | -4.15                       | 44.7                   | 42.5                  | 5.504                        | 4.965                       | -10.50                    | -10.55                       | 28.83                  | 1141         | 34.4297938 | -118.6470853 | Valve Adjustment:Decreased Flow/Vacuum                                                                                                             |
| CV-2572     | 8/17/2026 1:04:31 PM  | 48.9       | 39.2       | 0.0       | 11.9           |                         |                         | 1.2     | 0.0          | 122.7                | 122.6               | -4.03                        | -4.00                       | 42.3                   | 41.8                  | 4.930                        | 4.819                       | -10.69                    | -10.44                       | 28.83                  | 1151         | 34.4297987 | -118.6470707 |                                                                                                                                                    |
| CV-2602     | 8/9/2026 10:06:57 AM  | 20.1       | 15.1       | 12.9      | 51.8           |                         |                         | 1.3     | 4.0          | 101.5                | 100.9               | -16.79                       | -7.74                       | 0.8                    | 0.7                   | 0.012                        | 0.011                       | -16.97                    |                              | 28.75                  | 1129         | 34.4284837 | -118.6497653 | Valve Adjustment: NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Valve 100% Closed,Plugged/Pinched Suspected                                            |
| CV-2602     | 8/9/2026 10:08:01 AM  | 11.4       | 8.9        | 16.3      | 63.4           |                         |                         | 1.3     | 3.9          | 100.4                | 100.4               | -7.72                        | -7.72                       | 0.9                    | 0.7                   | 0.018                        | 0.011                       | -16.63                    | -16.61                       | 28.75                  | 1147         | 34.4284540 | -118.6497843 | Valve Adjustment:High O2                                                                                                                           |
| CV-2602     | 8/10/2026 2:04:19 PM  | 24.6       | 18.9       | 11.0      | 45.5           |                         |                         | 1.3     | 4.1          | 105.2                | 108.0               | -8.45                        | -8.45                       | 0.4                    | 0.4                   | 0.004                        | 0.003                       | -16.36                    | -16.46                       | 28.79                  | 1144         | 34.4284673 | -118.6498028 |                                                                                                                                                    |
| CV-2602     | 8/16/2026 1:41:36 PM  | 58.9       | 39.8       | 0.0       | 1.3            |                         |                         | 1.5     | 0.0          | 123.7                | 126.6               | 0.73                         | -0.41                       | 6.1                    | 27.4                  | 0.774                        | 16.346                      | -15.59                    | -15.37                       | 28.85                  | 1140         | 34.4284575 | -118.6498010 | Valve Adjustment: NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum                                                             |
| CV-2602     | 8/16/2026 1:46:35 PM  | 59.2       | 40.8       | 0.0       | 0.0            |                         |                         | 1.5     | 0.0          | 128.3                | 128.8               | -3.08                        | -3.15                       | 57.7                   | 58.6                  | 4.427                        | 4.572                       | -8.66                     | -9.25                        | 28.85                  | 1144         | 34.4284843 | -118.6498130 | Valve Adjustment: NSPS/EG CAC,Orifice Plate Changed (See OP Log)                                                                                   |
| CV-2603     | 8/30/2026 8:44:12 AM  | 54.4       | 41.3       | 0.0       | 4.4            |                         |                         | 1.3     | 0.0          | 115.0                | 118.2               | 0.20                         | -0.08                       | 3.1                    | 2.0                   | 0.203                        | 0.082                       | -5.27                     | -5.06                        | 28.74                  | 1121         | 34.4283618 | -118.6487735 | Valve Adjustment: NSPS/EG CAI,NSPS/EG CAC,Reconnected this Date,Positive Static Press.,Increased Flow/Vacuum                                       |
| CV-2603     | 8/30/2026 8:45:25 AM  | 54.7       | 40.8       | 0.0       | 4.5            |                         |                         | 1.3     | 0.0          | 118.6                | 118.5               | -0.13                        | -0.15                       | 2.4                    | 2.5                   | 0.124                        | 0.134                       | -4.78                     | -5.04                        | 28.75                  | 1134         | 34.4283348 | -118.6487723 |                                                                                                                                                    |
| CV-2605     | 8/5/2026 1:24:59 PM   | 55.5       | 43.3       | 0.0       | 1.2            |                         |                         | 1.3     | 0.0          | 102.4                | 99.2                | 0.36                         | 0.43                        | 2.8                    | 2.4                   | 0.804                        | 0.596                       | -2.28                     | -2.21                        | 28.81                  | 1095         | 34.4275102 | -118.6489385 | Valve Adjustment: Orifice Plate Changed (See OP Log),Reconnected this Date,Well Comment:Well start up                                              |
| CV-2605     | 8/6/2026 12:20:39 PM  | 56.1       | 43.3       | 0.0       | 0.6            |                         |                         | 1.3     | 0.0          | 110.0                | 101.2               | 0.31                         | -0.10                       | 3.8                    | 2.4                   | 0.298                        | 0.113                       | -10.63                    | -10.63                       | 28.82                  | 1095         | 34.4275565 | -118.6489743 | Valve Adjustment: NSPS/EG CAI,Orifice Plate Changed (See OP Log),Positive Static Press.,Increased Flow/Vacuum                                      |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init Flow<br>[scfm] | Adj Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                                                             |
|------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|---------------------|--------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| CV-2605    | 8/6/2026 12:24:25 PM  | 56.1       | 42.6       | 0.0       | 1.3            |                         |                         | 1.3     | 0.0          | 104.7                | 104.1               | -0.14                        | -0.25                       | 2.7                 | 3.6                | 0.147                        | 0.258                       | -10.48                    | -10.59                       | 28.83                  | 1104         | 34.4275193 | -118.6489625 | Valve Adjustment: NSPS/EG CAC, Increased Flow/Vacuum                                                                                                                 |
| CV-2605    | 8/10/2026 1:46:21 PM  | 51.6       | 45.6       | 0.0       | 2.8            |                         |                         | 1.1     | 0.0          | 123.3                | 124.8               | -0.81                        | -0.81                       | 18.8                | 18.8               | 7.591                        | 7.590                       | -12.50                    | -12.42                       | 28.82                  | 1102         | 34.4275327 | -118.6489598 |                                                                                                                                                                      |
| CV-2605    | 8/31/2026 12:17:46 PM | 50.9       | 41.1       | 0.0       | 8.0            |                         |                         | 1.2     | 0.0          | 131.7                | 131.8               | -0.14                        | -0.13                       | 8.4                 | 8.4                | 1.520                        | 1.524                       | -2.75                     | -2.73                        | 28.85                  | 1187         | 34.4276813 | -118.6490032 | Valve Adjustment: NSPS/EG CAI, High Temp, Decreased Flow/Vacuum, Surging Liquid in Header                                                                            |
| CV-2605    | 8/31/2026 12:19:27 PM | 50.2       | 41.3       | 0.0       | 8.5            |                         |                         | 1.2     | 0.0          | 131.9                | 131.8               | -0.08                        | -0.09                       | 9.3                 | 9.1                | 1.867                        | 1.768                       | -2.86                     | -2.71                        | 28.83                  | 1024         | 34.4274725 | -118.6490453 | Valve Adjustment: High Temp, Barely Open                                                                                                                             |
| CV-2606    | 8/2/2026 8:53:33 AM   | 58.2       | 41.0       | 0.0       | 0.0            |                         | 0.8                     | 1.4     | 0.0          | 112.3                | 114.0               | 0.93                         | 0.73                        | 7.8                 | 12.0               | 1.257                        | 2.991                       | -1.84                     | -2.55                        | 28.74                  | 1146         | 34.4289113 | -118.6484422 | Valve Adjustment: NSPS/EG CAI, Reconnected this Date, Positive Static Press., Increased Flow/Vacuum                                                                  |
| CV-2606    | 8/2/2026 8:58:04 AM   | 55.6       | 40.1       | 0.0       | 3.3            | 0                       | 1                       | 1.4     | 0.0          | 116.9                | 117.4               | 0.02                         | -0.11                       | 18.1                | 18.7               | 0.756                        | 0.808                       | -2.36                     | -2.38                        | 28.74                  | 1141         | 34.4289057 | -118.6484233 | Valve Adjustment: NSPS/EG CAC, Orifice Plate Changed (See OP Log), Increased Flow/Vacuum                                                                             |
| CV-2606    | 8/2/2026 1:11:21 PM   | 53.7       | 40.6       | 0.0       | 4.6            |                         | 1.1                     | 1.3     | 0.0          | 119.0                | 119.0               | -0.05                        | -0.12                       | 18.3                | 19.3               | 0.771                        | 0.859                       | -2.21                     | -2.05                        | 28.71                  | 1159         | 34.4288918 | -118.6484183 | Valve Adjustment: Increased Flow/Vacuum                                                                                                                              |
| CV-2606    | 8/2/2026 1:12:26 PM   | 52.5       | 39.5       | 0.0       | 6.6            | 0                       |                         | 1.4     | 1.3          | 119.1                | 119.1               | -0.14                        | -0.09                       | 19.9                | 19.2               | 0.914                        | 0.851                       | -1.99                     | -2.06                        | 28.71                  | 1153         | 34.4288992 | -118.6484330 |                                                                                                                                                                      |
| CV-2606    | 8/17/2026 12:24:02 PM | 49.0       | 38.3       | 0.0       | 12.8           |                         |                         | 1.3     | 0.0          | 119.6                | 119.3               | -0.26                        | -0.10                       | 7.7                 | 5.7                | 1.252                        | 0.686                       | -13.69                    | -14.06                       | 28.85                  | 1161         | 34.4288998 | -118.6484520 | Valve Adjustment: Orifice Plate Changed (See OP Log), Reconnected this Date, Decreased Flow/Vacuum, Barely Open                                                      |
| CV-2608    | 8/9/2026 8:47:40 AM   | 54.4       | 40.4       | 0.0       | 5.3            |                         |                         | 1.3     | 0.0          | 117.6                | 117.8               | -0.41                        | -0.44                       | 6.5                 | 7.9                | 0.891                        | 1.316                       | -15.64                    | -15.75                       | 28.72                  | 1159         | 34.4293568 | -118.6480515 | Valve Adjustment: Orifice Plate Changed (See OP Log), Reconnected this Date, Increased Flow/Vacuum                                                                   |
| CV-2608    | 8/9/2026 8:48:37 AM   | 53.4       | 40.7       | 0.0       | 5.8            |                         |                         | 1.3     | 0.0          | 118.3                | 118.3               | -0.47                        | -0.46                       | 7.9                 | 8.0                | 1.318                        | 1.340                       | -15.77                    | -16.36                       | 28.72                  | 1165         | 34.4293302 | -118.6480445 |                                                                                                                                                                      |
| CV-2610    | 8/6/2026 11:59:39 AM  | 64.1       | 35.9       | 0.0       | 0.0            |                         |                         | 1.8     | 0.0          | 116.5                | 116.6               | -0.02                        | -0.34                       | 18.9                | 22.2               | 2.383                        | 3.310                       | -15.64                    | -16.27                       | 28.86                  | 1148         | 34.4298302 | -118.6465830 | Valve Adjustment: NSPS/EG CAI, Orifice Plate Changed (See OP Log), Increased Flow/Vacuum, Well Comment: Main header value was found 100 percent closed               |
| CV-2610    | 8/6/2026 12:03:16 PM  | 64.0       | 36.0       | 0.0       | 0.0            |                         |                         | 1.8     | 0.0          | 116.7                | 116.7               | -0.55                        | -0.69                       | 21.6                | 23.5               | 3.126                        | 3.702                       | -15.96                    | -15.27                       | 28.88                  | 1151         | 34.4298192 | -118.6465772 | Valve Comment: 48 hour SEM CAI; Valve Adjustment: NSPS/EG CAI, Increased Flow/Vacuum                                                                                 |
| CV-2610    | 8/17/2026 12:55:38 PM | 41.1       | 35.4       | 0.0       | 23.4           |                         |                         | 1.2     | 0.0          | 116.7                | 116.9               | -2.55                        | -2.04                       | 25.8                | 20.1               | 4.247                        | 2.559                       | -16.11                    | -16.26                       | 28.86                  | 1147         | 34.4298425 | -118.6465740 | Valve Adjustment: Decreased Flow/Vacuum                                                                                                                              |
| CV-2610    | 8/17/2026 12:56:45 PM | 41.4       | 36.0       | 0.0       | 22.6           |                         |                         | 1.2     | 0.0          | 116.9                | 116.9               | -2.02                        | -2.01                       | 19.8                | 18.8               | 2.476                        | 2.248                       | -16.21                    | -16.31                       | 28.85                  | 1156         | 34.4298390 | -118.6465958 |                                                                                                                                                                      |
| CV-2611    | 8/13/2026 11:04:19 AM | 56.1       | 41.1       | 0.0       | 2.9            |                         |                         | 1.4     | 0.0          | 96.1                 | 96.5                | -1.14                        | -1.36                       | 5.0                 | 6.4                | 0.503                        | 0.827                       | -18.18                    | -17.43                       | 28.76                  | 1169         | 34.4303503 | -118.6458940 | Valve Adjustment: Reconnected this Date, Increased Flow/Vacuum                                                                                                       |
| CV-2611    | 8/13/2026 11:05:20 AM | 55.2       | 41.7       | 0.0       | 3.2            |                         |                         | 1.3     | 0.0          | 96.8                 | 96.9                | -1.52                        | -1.52                       | 6.4                 | 6.4                | 0.827                        | 0.833                       | -18.09                    | -17.69                       | 28.76                  | 1156         | 34.4303542 | -118.6459423 |                                                                                                                                                                      |
| CV-2612    | 8/31/2026 1:23:56 PM  | 52.0       | 43.3       | 0.0       | 4.7            |                         |                         | 1.2     | 0.0          | 113.2                | 113.4               | 1.60                         | 1.59                        | 3.2                 | 0.9                | 0.028                        | 0.002                       | 1.49                      | 1.42                         | 28.68                  | 1265         | 34.4311698 | -118.6470965 | Valve Comment: Liquid in lateral; Valve Adjustment: NSPS/EG CAI, Reconnected this Date, Positive Static Press.                                                       |
| CV-2612    | 8/31/2026 1:25:10 PM  | 52.3       | 42.8       | 0.0       | 4.9            |                         |                         | 1.2     | 0.0          | 113.5                | 113.4               | 1.62                         | 1.62                        | 2.3                 | 1.3                | 0.015                        | 0.005                       | 1.57                      | 1.34                         | 28.68                  | 1253         | 34.4311713 | -118.6471083 | Valve Adjustment: Positive Static Press.                                                                                                                             |
| CV-2627    | 8/26/2026 3:28:31 PM  | 50.4       | 43.4       | 0.0       | 6.2            |                         |                         | 1.2     | 0.0          | 115.8                | 116.7               | 1.69                         | 0.80                        | 8.2                 | 10.6               | 1.396                        | 2.359                       | -5.94                     | -7.00                        | 28.68                  | 1183         | 34.4309927 | -118.6461628 | Valve Adjustment: NSPS/EG CAI, Orifice Plate Changed (See OP Log), Reconnected this Date, Positive Static Press., Increased Flow/Vacuum                              |
| CV-2627    | 8/26/2026 3:31:36 PM  | 51.0       | 42.9       | 0.0       | 6.2            |                         |                         | 1.2     | 0.0          | 117.6                | 117.8               | 0.00                         | -0.04                       | 11.1                | 11.6               | 0.777                        | 0.856                       | -7.07                     | -8.00                        | 28.68                  | 1204         | 34.4310157 | -118.6461603 | Valve Adjustment: NSPS/EG CAC, Increased Flow/Vacuum                                                                                                                 |
| CV-2627    | 8/26/2026 3:32:50 PM  | 50.4       | 43.4       | 0.0       | 6.3            |                         |                         | 1.2     | 0.0          | 118.0                | 118.0               | -0.09                        | -0.05                       | 11.3                | 11.0               | 0.804                        | 0.765                       | -7.71                     | -7.53                        | 28.68                  | 1205         | 34.4310230 | -118.6461620 |                                                                                                                                                                      |
| CV-2634    | 8/24/2026 10:00:54 AM | 13.9       | 46.5       | 8.2       | 31.5           |                         |                         | 0.3     | 3.9          | 103.1                | 104.0               | -4.78                        | -1.44                       | 1.3                 | 0.6                | 0.036                        | 0.008                       | -4.49                     | -4.68                        | 28.76                  | 1205         | 34.4313943 | -118.6454503 | Valve Adjustment: NSPS/EG CAI, Orifice Plate Changed (See OP Log), Reconnected this Date, High O2, Decreased Flow/Vacuum                                             |
| CV-2634    | 8/24/2026 10:10:21 AM | 11.6       | 42.4       | 9.5       | 36.6           |                         |                         | 0.3     | 3.9          | 102.9                | 102.8               | -3.85                        | -3.47                       | 0.3                 | 0.5                | 0.002                        | 0.005                       | -3.86                     | -3.36                        | 28.77                  | 1217         | 34.4313958 | -118.6454553 | Valve Adjustment: High O2, Plugged/Pinched Suspected                                                                                                                 |
| CV-2634    | 8/24/2026 10:12:14 AM | 10.4       | 38.3       | 11.1      | 40.2           |                         |                         | 0.3     | 3.6          | 104.4                | 104.5               | -3.35                        | -3.33                       | 1.5                 | 0.5                | 0.044                        | 0.005                       | -3.31                     | -3.36                        | 28.76                  | 1205         | 34.4313947 | -118.6454615 | Valve Adjustment: High O2, Plugged/Pinched Suspected                                                                                                                 |
| CV-2634    | 8/26/2026 8:10:00 AM  | 1.9        | 6.4        | 19.0      | 72.6           |                         |                         | 0.3     | 3.8          | 84.9                 | 85.1                | -2.55                        | -2.56                       | 0.8                 | 1.1                | 0.014                        | 0.024                       | -2.46                     | -2.46                        | 28.68                  | 1204         | 34.4314018 | -118.6454828 | Valve Adjustment: High O2, Valve 100% Open, Surging Liquid in Well (Watered In)                                                                                      |
| CV-2634    | 8/26/2026 12:58:27 PM | 19.1       | 32.0       | 8.4       | 40.5           |                         |                         | 0.6     | 4.8          | 126.0                | 113.8               | 0.04                         | 0.24                        | 1.2                 | 0.5                | 0.028                        | 0.004                       | 0.15                      | 0.42                         | 28.74                  | 1213         | 34.4314047 | -118.6454710 |                                                                                                                                                                      |
| CV-2663    | 8/2/2026 10:01:30 AM  | 32.4       | 55.2       | 0.0       | 0.0            |                         | 12.4                    | 0.6     | 0.0          | 143.5                | 143.4               | -11.50                       | -11.58                      | 11.1                | 10.4               | 0.843                        | 0.734                       | -15.27                    | -15.02                       | 28.54                  | 1329         | 34.4350752 | -118.6433335 | Valve Adjustment: NSPS/EG CAI, High Temp                                                                                                                             |
| CV-2663    | 8/2/2026 10:11:40 AM  | 32.7       | 53.8       | 0.0       | 0.0            |                         | 13.5                    | 0.6     | 0.0          | 143.2                | 143.3               | -11.14                       | -11.27                      | 10.5                | 10.7               | 0.755                        | 0.790                       | -15.04                    | -15.27                       | 28.54                  | 1338         | 34.4350732 | -118.6433318 | Valve Adjustment: High Temp                                                                                                                                          |
| CV-2663    | 8/21/2026 1:30:21 PM  | 36.1       | 56.1       | 0.0       | 7.8            |                         |                         | 0.6     | 0.0          | 143.0                | 143.7               | -7.71                        | -7.89                       | 9.9                 | 11.2               | 0.663                        | 0.844                       | -11.07                    | -11.27                       | 28.64                  | 1338         | 34.4350677 | -118.6433358 | Valve Adjustment: High Temp, Increased Flow/Vacuum                                                                                                                   |
| CV-2676    | 8/31/2026 3:05:31 PM  | 25.1       | 62.0       | 0.0       | 12.9           |                         |                         | 0.4     | 0.0          | 132.4                | 128.0               | -5.25                        | -3.58                       |                     |                    | 5.719                        | 3.589                       | -15.40                    | -15.54                       | 28.55                  | 1307         | 34.4335987 | -118.6434925 | Valve Adjustment: NSPS/EG CAI, High Temp, Decreased Flow/Vacuum, Surging Liquid in Header                                                                            |
| CV-2676    | 8/31/2026 3:06:50 PM  | 23.2       | 65.0       | 0.0       | 11.8           |                         |                         | 0.4     | 0.0          | 128.0                | 127.4               | -3.14                        | -3.13                       |                     |                    | 3.146                        | 3.129                       | -15.46                    | -15.66                       | 28.52                  | 1306         | 34.4335958 | -118.6434923 | Valve Adjustment: NSPS/EG CAC, Surging Liquid in Header                                                                                                              |
| CV-2680    | 8/2/2026 2:25:49 PM   | 36.5       | 41.0       | 0.0       | 22.5           |                         |                         | 0.9     | 0.0          | 104.9                | 113.7               | 0.77                         | -1.56                       | 1.4                 | 14.9               | 0.038                        | 4.720                       | -17.03                    | -16.96                       | 28.55                  | 1266         | 34.4353647 | -118.6421237 | Valve Adjustment: NSPS/EG CAI, NSPS/EG CAC, Positive Static Press., Increased Flow/Vacuum                                                                            |
| CV-2680    | 8/2/2026 2:27:15 PM   | 34.0       | 43.7       | 0.0       | 22.3           |                         |                         | 0.8     | 0.0          | 123.0                | 123.3               | -2.07                        | -2.06                       | 13.7                | 13.5               | 4.031                        | 3.955                       | -16.70                    | -16.80                       | 28.54                  | 1283         | 34.4353482 | -118.6421155 |                                                                                                                                                                      |
| CV-2681    | 8/11/2026 2:24:08 PM  | 20.6       | 44.0       | 0.0       | 35.4           |                         |                         | 0.5     | 0.0          | 99.4                 | 101.0               | 1.00                         | 1.05                        |                     |                    | 0.000                        | 0.000                       | 0.99                      | 1.00                         | 28.68                  | 1290         | 34.4353015 | -118.6426173 | Valve Comment: header grade incorrect; Valve Adjustment: NSPS/EG CAI, Reconnected this Date, Positive Static Press., Decreased Flow/Vacuum, Surging Liquid in Header |
| CV-2681    | 8/11/2026 2:26:34 PM  | 19.9       | 45.3       | 0.0       | 34.8           |                         |                         | 0.4     | 0.0          | 100.7                | 100.8               | 1.07                         | 1.07                        |                     |                    | 0.000                        | 0.000                       | 1.01                      | 1.01                         | 28.67                  | 1293         | 34.4352953 | -118.6426043 |                                                                                                                                                                      |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init Temp<br>[°F] | Adj Temp<br>[°F] | Init Stat Press<br>["H2O] | Adj Stat Press<br>["H2O] | Init Flow<br>[scfm] | Adj Flow<br>[scfm] | Init Diff Press<br>["H2O] | Adj Diff Press<br>["H2O] | Sys Pressure<br>["H2O] | Adj Avail Press<br>["H2O] | Baro Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                                        |                              |
|------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|-------------------|------------------|---------------------------|--------------------------|---------------------|--------------------|---------------------------|--------------------------|------------------------|---------------------------|---------------------|--------------|------------|--------------|-------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------|
| CV-2681    | 8/26/2026 1:43:07 PM  | 36.1       | 40.9       | 0.0       | 23.0           |                         |                         | 0.9     | 0.0          | 133.4             | 132.3            | -10.06                    | -5.60                    |                     |                    | 10.169                    | 5.627                    | -10.83                 | -13.74                    | 28.57               | 1283         | 34.4353005 | -118.6425987 | Valve Adjustment: NSPS/EG CAI, NSPS/EG CAC, High Temp, Decreased Flow/Vacuum                                                                    |                              |
| CV-2681    | 8/26/2026 1:48:15 PM  | 35.6       | 41.1       | 0.0       | 23.3           |                         |                         | 0.9     | 0.0          | 130.8             | 128.9            | -3.61                     | -2.98                    |                     |                    | 3.701                     | 3.020                    | -13.69                 | -13.72                    | 28.57               | 1286         | 34.4353125 | -118.6426095 | Valve Adjustment: NSPS/EG CAC, Decreased Flow/Vacuum                                                                                            |                              |
| CV-2681    | 8/26/2026 1:48:52 PM  |            |            |           |                |                         | 109000                  |         |              |                   |                  |                           |                          |                     |                    |                           |                          |                        |                           |                     |              |            |              |                                                                                                                                                 | [User entered 10.9%]         |
| CV-2681    | 8/26/2026 1:52:17 PM  | 35.2       | 41.1       | 0.0       | 23.7           |                         |                         | 0.9     | 1184.5       | 127.6             | 127.5            | -2.25                     | -2.23                    |                     |                    | 2.311                     | 2.295                    | -13.75                 | -13.76                    | 28.58               | 1302         | 34.4352890 | -118.6426005 |                                                                                                                                                 |                              |
| CV-2683    | 8/3/2026 12:41:29 PM  | 33.9       | 43.8       | 0.0       | 22.3           |                         |                         | 0.8     | 0.0          | 120.6             | 120.6            | -7.62                     | -4.93                    | 10.5                | 6.0                | 2.416                     | 0.763                    | -15.70                 | -15.84                    | 28.53               | 1294         | 34.4346805 | -118.6424525 | Valve Adjustment: Orifice Plate Changed (See OP Log), Reconnected this Date, Decreased Flow/Vacuum                                              |                              |
| CV-2683    | 8/3/2026 12:43:49 PM  | 33.5       | 45.1       | 0.0       | 21.4           |                         |                         | 0.7     | 0.0          | 120.5             | 120.5            | -5.17                     | -5.27                    | 6.1                 | 5.9                | 0.801                     | 0.757                    | -15.74                 | -15.75                    | 28.53               | 1294         | 34.4346942 | -118.6424578 | Valve Adjustment: Barely Open                                                                                                                   |                              |
| CV-2684    | 8/24/2026 9:39:51 AM  | 42.9       | 41.3       | 0.0       | 15.8           |                         |                         | 1.0     | 0.0          | 123.1             | 121.0            | -4.77                     | -3.58                    |                     |                    | 4.805                     | 3.604                    | -16.41                 | -16.95                    | 28.7                | 1281         | 34.4342003 | -118.6421805 | Valve Adjustment: Reconnected this Date, Decreased Flow/Vacuum; Well Comment: knife valve corrected                                             |                              |
| CV-2687    | 8/3/2026 1:32:49 PM   | 52.6       | 41.4       | 0.0       | 6.1            |                         |                         | 1.3     | 0.0          | 102.4             | 98.4             | -0.63                     | -1.08                    | 1.3                 | 5.2                | 0.033                     | 0.544                    | -19.35                 | -19.37                    | 28.56               | 1261         | 34.4336015 | -118.6415535 | Valve Adjustment: Increased Flow/Vacuum                                                                                                         |                              |
| CV-2687    | 8/3/2026 1:34:22 PM   | 53.2       | 41.7       | 0.0       | 5.2            |                         |                         | 1.3     | 0.0          | 97.2              | 97.2             | -1.44                     | -1.47                    | 5.7                 | 5.8                | 0.671                     | 0.682                    | -19.14                 | -19.17                    | 28.56               | 1249         | 34.4336027 | -118.6415467 |                                                                                                                                                 |                              |
| CV-2688    | 8/3/2026 1:55:29 PM   | 52.9       | 41.3       | 0.0       | 5.8            |                         |                         | 1.3     | 0.0          | 123.2             | 123.3            | -2.67                     | -2.68                    | 12.7                | 12.9               | 3.466                     | 3.611                    | -19.92                 | -20.04                    | 28.57               | 1222         | 34.4327228 | -118.6423660 | Valve Adjustment: Increased Flow/Vacuum                                                                                                         |                              |
| CV-2688    | 8/3/2026 1:58:58 PM   | 53.2       | 41.6       | 0.0       | 5.2            |                         |                         | 1.3     | 0.0          | 123.4             | 123.5            | -2.80                     | -2.96                    | 12.8                | 13.7               | 1.054                     | 1.205                    | -20.04                 | -19.98                    | 28.58               | 1212         | 34.4327238 | -118.6423867 | Valve Adjustment: Orifice Plate Changed (See OP Log), Increased Flow/Vacuum                                                                     |                              |
| CV-2688    | 8/3/2026 1:59:54 PM   | 53.0       | 41.7       | 0.0       | 5.3            |                         |                         | 1.3     | 0.0          | 123.6             | 123.6            | -3.23                     | -3.23                    | 13.5                | 13.6               | 1.189                     | 1.194                    | -20.31                 | -20.36                    | 28.57               | 1212         | 34.4327418 | -118.6423993 |                                                                                                                                                 |                              |
| CV-2688    | 8/6/2026 1:14:08 PM   | 63.4       | 36.6       | 0.0       | 0.0            |                         |                         | 1.7     | 0.0          | 124.7             | 124.8            | -4.20                     | -4.79                    | 7.7                 | 9.4                | 0.413                     | 0.613                    | -18.56                 | -18.30                    | 28.79               | 1233         | 34.4327507 | -118.6423987 | Valve Adjustment: Increased Flow/Vacuum                                                                                                         |                              |
| CV-2688    | 8/19/2026 8:39:42 AM  | 57.5       | 39.1       | 0.0       | 3.4            |                         |                         | 1.5     | 0.0          | 124.6             | 124.7            | -6.10                     | -6.44                    | 8.0                 | 8.8                | 1.397                     | 1.664                    | -20.95                 | -20.93                    | 28.71               | 1215         | 34.4327250 | -118.6424070 | Valve Adjustment: Audible Flow, Increased Flow/Vacuum, Barely Open                                                                              |                              |
| CV-2689    | 8/19/2026 9:57:33 AM  | 1.6        | 65.7       | 0.0       | 32.7           |                         |                         | 0.0     | 0.0          | 130.3             | 130.9            | -4.54                     | -4.97                    |                     |                    | 4.529                     | 4.956                    | -13.32                 | -13.45                    | 28.71               | 1234         | 34.4328140 | -118.6433697 | Valve Adjustment: Increased Flow/Vacuum                                                                                                         |                              |
| CV-2690    | 8/2/2026 1:48:32 PM   | 53.7       | 42.5       | 0.1       | 2.2            | 0                       | 1.5                     | 1.3     | 22.0         | 126.8             | 127.2            | -4.30                     | -5.28                    | 5.0                 | 7.3                | 0.542                     | 1.169                    | -14.42                 | -13.77                    | 28.62               | 1209         | 34.4323775 | -118.6429142 | Valve Adjustment: Increased Flow/Vacuum                                                                                                         |                              |
| CV-2690    | 8/2/2026 1:51:15 PM   | 53.4       | 41.7       | 0.0       | 3.5            | 0                       | 1.4                     | 1.3     | 0.0          | 128.1             | 128.1            | -6.68                     | -6.63                    | 7.3                 | 6.7                | 1.162                     | 0.971                    | -13.95                 | -13.87                    | 28.63               | 1223         | 34.4323987 | -118.6429015 |                                                                                                                                                 |                              |
| CV-2691    | 8/2/2026 1:37:50 PM   | 54.4       | 40.0       | 0.0       | 4.6            | 0                       | 1                       | 1.4     | 0.0          | 127.9             | 128.0            | -2.55                     | -2.60                    | 15.0                | 15.1               | 4.886                     | 4.953                    | -15.25                 | -15.49                    | 28.63               | 1234         | 34.4321052 | -118.6431892 |                                                                                                                                                 |                              |
| CV-2691    | 8/2/2026 1:40:49 PM   | 54.3       | 39.9       | 0.0       | 4.7            | 0                       | 1.1                     | 1.4     | 0.0          | 128.5             | 128.5            | -2.75                     | -2.75                    | 16.6                | 17.0               | 1.794                     | 1.879                    | -15.44                 | -14.35                    | 28.64               | 1221         | 34.4321237 | -118.6431805 | Valve Adjustment: Orifice Plate Changed (See OP Log)                                                                                            |                              |
| CV-2692    | 8/26/2026 8:00:49 AM  | 55.3       | 41.4       | 0.0       | 3.3            |                         |                         | 1.3     | 0.0          | 125.3             | 125.4            | 6.27                      | 6.07                     | 13.3                | 15.7               | 3.715                     | 5.191                    | -23.14                 | -22.82                    | 28.68               | 1224         | 34.4316493 | -118.6444922 | Valve Adjustment: NSPS/EG CAI, Orifice Plate Changed (See OP Log), Reconnected this Date, Positive Static Press., Increased Flow/Vacuum         |                              |
| CV-2692    | 8/26/2026 8:05:20 AM  | 52.8       | 42.7       | 0.0       | 4.5            |                         |                         | 1.2     | 0.0          | 126.1             | 126.4            | 5.67                      | 4.94                     | 15.4                | 19.8               | 0.307                     | 0.505                    | -23.12                 | -23.28                    | 28.68               | 1216         | 34.4316522 | -118.6444888 | Valve Adjustment: Positive Static Press., Increased Flow/Vacuum                                                                                 |                              |
| CV-2692    | 8/26/2026 8:18:14 AM  | 54.7       | 41.8       | 0.0       | 3.6            |                         |                         | 1.3     | 0.0          | 126.5             | 126.7            | 4.66                      | 4.14                     | 20.6                | 24.5               | 0.551                     | 0.781                    | -22.76                 | -22.21                    | 28.67               | 1210         | 34.4316630 | -118.6445000 | Valve Adjustment: Positive Static Press., Increased Flow/Vacuum                                                                                 |                              |
| CV-2692    | 8/26/2026 11:52:57 AM | 52.8       | 41.1       | 0.0       | 6.2            |                         |                         | 1.3     | 0.0          | 128.7             | 128.7            | 3.60                      | 3.12                     | 22.9                | 27.8               | 0.684                     | 1.009                    | -19.85                 | -20.54                    | 28.72               | 1230         | 34.4316465 | -118.6445087 | Valve Adjustment: Positive Static Press., Increased Flow/Vacuum                                                                                 |                              |
| CV-2692    | 8/26/2026 3:15:34 PM  | 53.0       | 41.6       | 0.0       | 5.4            |                         |                         | 1.3     | 0.0          | 127.8             | 128.1            | 2.83                      | -0.11                    | 26.5                | 41.4               | 0.920                     | 2.269                    | -19.20                 | -19.24                    | 28.65               | 1209         | 34.4316515 | -118.6444475 | Valve Adjustment: NSPS/EG CAC                                                                                                                   |                              |
| CV-2695    | 8/31/2026 12:59:49 PM | 54.6       | 40.5       | 0.0       | 4.8            |                         |                         | 1.3     | 0.0          | 112.6             | 112.5            | -0.01                     | -0.02                    | 8.8                 | 9.2                | 1.613                     | 1.766                    | -13.21                 | -13.51                    | 28.75               | 1188         | 34.4288813 | -118.6501568 | Valve Adjustment: Reconnected this Date                                                                                                         |                              |
| CV-2695    | 8/31/2026 1:02:50 PM  | 54.1       | 41.0       | 0.0       | 4.9            |                         |                         | 1.3     | 0.0          | 113.0             | 113.2            | -0.13                     | -0.23                    | 10.7                | 12.6               | 0.714                     | 0.998                    | -13.29                 | -13.14                    | 28.75               | 1194         | 34.4288665 | -118.6501475 | Valve Adjustment: Orifice Plate Changed (See OP Log), Increased Flow/Vacuum                                                                     |                              |
| CV-2695    | 8/31/2026 1:04:07 PM  | 53.7       | 41.1       | 0.0       | 5.2            |                         |                         | 1.3     | 0.0          | 113.4             | 113.4            | -0.27                     | -0.27                    | 12.4                | 12.2               | 0.971                     | 0.932                    | -12.97                 | -12.96                    | 28.76               | 1191         | 34.4288590 | -118.6501417 |                                                                                                                                                 |                              |
| CV-48R     | 8/5/2026 12:03:09 PM  | 50.9       | 44.0       | 0.0       | 5.1            |                         |                         | 1.2     | 0.0          | 122.8             | 122.8            | -7.43                     | -7.42                    | 9.2                 | 8.1                | 0.533                     | 0.409                    | -8.85                  |                           | 28.6                | 1247         | 34.4373215 | -118.6458367 | ,                                                                                                                                               |                              |
| CV-52D     | 8/17/2026 1:47:35 PM  | 31.4       | 51.3       | 0.0       | 17.3           |                         |                         | 0.6     | 0.0          | 103.5             | 104.1            | -10.73                    | -10.54                   | 1.0                 | 2.2                | 0.007                     | 0.031                    | -14.93                 | -14.95                    | 28.69               | 1306         | 34.4359553 | -118.6425010 | Valve Adjustment: Decreased Flow/Vacuum                                                                                                         |                              |
| CV-52D     | 8/25/2026 12:56:23 PM | 33.5       | 50.6       | 0.0       | 15.9           |                         |                         | 0.7     | 0.0          | 133.0             | 130.0            | -13.34                    | -2.77                    | 4.1                 | 10.6               | 0.111                     | 0.736                    | -15.72                 | -14.92                    | 28.71               | 1302         | 34.4359373 | -118.6424785 | Valve Adjustment: NSPS/EG CAI, Orifice Plate Changed (See OP Log), High Temp, Decreased Flow/Vacuum; Well Comment: Changed OP from 1.00 to 0.40 |                              |
| CV-52D     | 8/25/2026 12:58:19 PM | 32.3       | 50.8       | 0.0       | 16.9           |                         |                         | 0.6     | 0.0          | 130.0             | 130.0            | -3.02                     | -3.04                    | 1.7                 | 1.7                | 0.765                     | 0.745                    | -15.30                 | -15.07                    | 28.71               | 1308         | 34.4359533 | -118.6424803 | Valve Adjustment: NSPS/EG CAC                                                                                                                   |                              |
| CV-55R     | 8/1/2026 8:17:33 AM   | 34.6       | 50.1       | 0.4       | 14.9           |                         |                         | 0.7     | 37.3         | 152.7             | 152.6            | -6.92                     | -7.00                    | 2.6                 | 3.7                | 0.045                     | 0.092                    | -16.38                 | -16.68                    | 28.63               | 1310         | 34.4343715 | -118.6427893 | Valve Adjustment: NSPS/EG CAI, High Temp, Increased Flow/Vacuum, Surging Liquid in Header; Well Comment: RES SEM                                |                              |
| CV-55R     | 8/1/2026 8:18:47 AM   | 34.8       | 49.5       | 0.1       | 15.6           |                         |                         | 0.7     | 156.0        | 152.7             | 152.6            | -7.08                     | -7.09                    | 5.0                 | 6.1                | 0.170                     | 0.257                    | -16.57                 | -18.61                    | 28.64               | 1313         | 34.4343842 | -118.6427778 | Valve Adjustment: NSPS/EG CAI, High Temp, Surging Liquid in Header                                                                              |                              |
| CV-55R     | 8/4/2026 2:04:33 PM   | 36.8       | 55.9       | 0.0       | 7.3            |                         |                         | 0.7     | 0.0          | 152.0             | 152.3            | -5.73                     | -5.73                    | 5.4                 | 5.9                | 0.202                     | 0.241                    | -14.27                 | -14.06                    | 28.53               | 1326         | 34.4343784 | -118.6427800 | Valve Adjustment: High Temp; Well Condition: Lorentz Pump Installed                                                                             |                              |
| CV-55R     | 8/4/2026 2:10:00 PM   |            |            |           |                |                         | 175600                  |         |              |                   |                  |                           |                          |                     |                    |                           |                          |                        |                           |                     |              |            |              |                                                                                                                                                 | AtmAA; [User entered 17.56%] |
| CV-55R     | 8/4/2026 2:10:00 PM   |            |            |           |                | 290                     |                         |         |              |                   |                  |                           |                          |                     |                    |                           |                          |                        |                           |                     |              |            |              |                                                                                                                                                 | AtmAA                        |
| CV-55R     | 8/13/2026 1:10:00 PM  |            |            |           |                | 286                     |                         |         |              |                   |                  |                           |                          |                     |                    |                           |                          |                        |                           |                     |              |            |              |                                                                                                                                                 | AtmAA                        |
| CV-55R     | 8/13/2026 1:10:20 PM  | 52.1       | 47.9       | 0.0       | 0.0            |                         |                         | 1.1     | 0.0          | 151.9             | 151.5            | -6.28                     | -6.28                    | 6.3                 | 2.9                | 0.267                     | 0.056                    | -15.34                 | -15.58                    | 28.6                | 1306         | 34.4343781 | -118.6427750 | Valve Adjustment: High Temp; Well Condition: Lorentz Pump Installed                                                                             |                              |
| CV-55R     | 8/20/2026 7:32:37 AM  | 27.3       | 51.6       | 0.0       | 21.1           |                         |                         | 0.5     | 0.0          | 151.1             | 151.1            | -6.74                     | -6.74                    | 6.7                 | 8.2                | 0.306                     | 0.456                    | -16.42                 | -16.21                    | 28.64               | 1314         | 34.4343752 | -118.6427887 | Valve Adjustment: High Temp; Well Condition: Lorentz Pump Installed                                                                             |                              |
| CV-56D     | 8/20/2026 2:10:11 PM  | 35.4       | 29.8       | 3.7       | 31.1           |                         |                         | 1.2     | 8.4          | 121.4             | 121.4            | -3.50                     | -3.29                    | 6.7                 | 5.8                | 0.952                     | 0.714                    | -14.92                 | -14.94                    | 28.56               | 1313         | 34.4337942 | -118.6431847 | Valve Adjustment: Decreased Flow/Vacuum                                                                                                         |                              |
| CV-56S     | 8/20/2026 2:12:56 PM  | 47.0       | 41.2       | 1.0       | 10.8           |                         |                         | 1.1     | 10.8         | 123.6             | 123.7            | -3.29                     | -3.09                    | 6.3                 | 6.0                | 11.084                    | 9.893                    | -14.84                 | -14.77                    | 28.59               | 1308         | 34.4337938 | -118.6431732 | Valve Adjustment: Decreased Flow/Vacuum                                                                                                         |                              |
| CV-57R     | 8/17/2026 12:37:25 PM | 42.1       | 34.6       | 0.0       | 23.3           |                         |                         | 1.2     | 0.0          | 123.5             | 122.8            | -3.28                     | -1.34                    | 10.3                | 1.1                | 2.274                     | 0.024                    | -16.19                 | -16.17                    | 28.65               | 1351         | 34.4342948 | -118.6436170 | Valve Adjustment: Decreased Flow/Vacuum                                                                                                         |                              |
| CV-79R     | 8/17/2026 1:12:45 PM  | 51.6       | 42.2       | 0.0       | 6.2            |                         |                         | 1.2     | 0.0          | 123.4             | 124.1            | -6.06                     | -6.06                    | 9.4                 | 9.5                | 0.208                     | 0.212                    | -17.68                 | -17.62                    | 28.66               | 1324         | 34.4332397 | -118.6448902 |                                                                                                                                                 |                              |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init Flow<br>[scfm] | Adj Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>[psi] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                         |             |
|------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|---------------------|--------------------|------------------------------|-----------------------------|--------------------------|------------------------------|------------------------|--------------|------------|--------------|------------------------------------------------------------------------------------------------------------------|-------------|
| CV-94      | 8/17/2026 1:34:46 PM  | 32.5       | 34.1       | 0.0       | 33.4           |                         |                         | 1.0     | 0.0          | 119.1                | 119.5               | -12.56                       | -10.77                      | 0.9                 | 1.4                | 0.006                        | 0.012                       | -15.76                   | -15.64                       | 28.65                  | 1344         | 34.4348798 | -118.6436840 | Valve Adjustment:Decreased Flow/Vacuum                                                                           |             |
| CV-95      | 8/17/2026 12:35:02 PM | 26.5       | 28.3       | 0.0       | 45.2           |                         |                         | 0.9     | 0.0          | 104.3                | 104.4               | -0.51                        | -0.46                       | 0.2                 | 0.9                | 0.001                        | 0.017                       | -15.99                   | -16.00                       | 28.65                  | 1352         | 34.4342775 | -118.6436405 |                                                                                                                  |             |
| CV-99      | 8/10/2026 8:15:00 AM  |            |            |           |                | 0                       |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                          |                              |                        |              |            |              |                                                                                                                  | AirTech Lab |
| CV-99      | 8/11/2026 9:13:37 AM  | 0.8        | 6.0        | 19.0      | 74.2           |                         |                         | 0.1     | 3.9          | 87.8                 | 90.1                | -11.43                       | -11.16                      | 1.1                 | 0.8                | 0.027                        | 0.012                       | -11.03                   | -10.93                       | 28.64                  | 1305         | 34.4370152 | -118.6463662 | Valve Adjustment:Decreased Flow/Vacuum                                                                           |             |
| CV-99      | 8/11/2026 9:14:07 AM  | 1.1        | 6.3        | 18.6      | 74.0           |                         |                         | 0.2     | 4.0          | 90.4                 | 90.4                | -11.14                       | -11.14                      | 1.0                 | 0.5                | 0.022                        | 0.006                       | -10.93                   | -10.80                       | 28.64                  | 1327         | 34.4370307 | -118.6463445 | Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)                |             |
| D-02       | 8/24/2026 11:37:51 AM | 58.8       | 39.6       | 0.0       | 1.6            |                         |                         | 1.5     | 0.0          | 105.6                | 105.6               | -6.22                        | -6.05                       | 15.1                | 19.4               | 0.195                        | 0.320                       | -6.33                    | -6.01                        | 28.87                  | 1166         | 34.4311782 | -118.6442972 | Valve Adjustment:Audible Flow,Surging Liquid in Header                                                           |             |
| D-03       | 8/28/2026 10:04:22 AM | 55.3       | 38.5       | 0.0       | 6.2            |                         |                         | 1.4     | 0.0          | 105.8                | 105.2               | 1.02                         | 1.01                        | 2.7                 | 8.0                | 0.006                        | 0.055                       | 2.04                     | 2.03                         | 28.69                  | 1180         | 34.4311728 | -118.6443072 | Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Header,Surging Liquid in Well (Watered In) |             |
| D-03       | 8/28/2026 10:05:07 AM | 55.3       | 40.3       | 0.0       | 4.4            |                         |                         | 1.4     | 0.0          | 105.7                | 105.7               | 0.96                         | 1.00                        | 5.2                 | 11.9               | 0.023                        | 0.119                       | 2.05                     | 1.96                         | 28.7                   | 1177         | 34.4311775 | -118.6442930 | Valve Adjustment:Positive Static Press.                                                                          |             |
| D-03       | 8/31/2026 9:32:55 AM  | 55.9       | 39.7       | 0.0       | 4.4            |                         |                         | 1.4     | 0.0          | 99.8                 | 99.8                | 1.23                         | 1.22                        | 4.9                 | 5.4                | 0.030                        | 0.036                       | 1.58                     | 1.32                         | 28.73                  | 1194         | 34.4311810 | -118.6443300 | Valve Adjustment:Positive Static Press.,Valve 100% Open,Surging Liquid in Header                                 |             |
| D-03       | 8/31/2026 9:34:11 AM  | 55.3       | 41.2       | 0.0       | 3.6            |                         |                         | 1.3     | 0.0          | 99.7                 | 99.7                | 1.23                         | 1.24                        | 1.6                 | 1.1                | 0.003                        | 0.002                       | 1.63                     | 1.65                         | 28.72                  | 1195         | 34.4311740 | -118.6443102 | Valve Adjustment:Positive Static Press.,Valve 100% Open,Surging Liquid in Header                                 |             |
| D-04       | 8/28/2026 9:58:45 AM  | 57.0       | 38.5       | 0.0       | 4.5            |                         |                         | 1.5     | 0.0          | 101.8                | 102.5               | -16.54                       | -16.20                      | 7.6                 | 9.0                | 0.075                        | 0.105                       | -18.35                   | -18.39                       | 28.69                  | 1179         | 34.4311818 | -118.6443127 | Valve Adjustment:Valve 100% Open                                                                                 |             |
| D-09       | 8/6/2026 12:18:33 PM  | 63.8       | 36.2       | 0.0       | 0.0            |                         |                         | 1.8     | 0.0          | 113.7                | 114.9               | -10.83                       | -10.86                      | 12.9                | 16.3               | 0.219                        | 0.349                       | -12.46                   | -12.56                       | 28.85                  | 1142         | 34.4301087 | -118.6463205 | Valve Adjustment:Increased Flow/Vacuum                                                                           |             |
| D-09       | 8/12/2026 1:54:35 PM  | 53.7       | 39.8       | 0.0       | 6.5            |                         |                         | 1.3     | 0.0          | 116.2                | 116.2               | -11.70                       | -11.81                      | 20.8                | 18.7               | 0.574                        | 0.465                       | -12.50                   | -12.14                       | 28.71                  | 1143         | 34.4301198 | -118.6462902 | Valve Adjustment:Valve 100% Open                                                                                 |             |
| D-10       | 8/18/2026 2:15:49 PM  | 51.7       | 40.0       | 0.4       | 7.9            |                         |                         | 1.3     | 19.8         | 107.2                | 107.3               | -15.83                       | -15.84                      |                     |                    | 0.000                        | 0.010                       | -17.44                   | -16.95                       | 28.84                  | 1139         | 34.4302007 | -118.6458168 |                                                                                                                  |             |
| FP-001     | 8/11/2026 2:52:52 PM  | 16.8       | 22.6       | 5.0       | 55.6           |                         |                         | 0.7     | 11.1         | 95.6                 | 97.5                | -0.19                        | -0.18                       | 8.5                 | 8.4                | 0.437                        | 0.432                       | -12.54                   | -12.64                       | 28.58                  | 1363         | 34.4366115 | -118.6458238 |                                                                                                                  |             |
| FP-002     | 8/11/2026 2:48:19 PM  | 27.3       | 30.8       | 3.3       | 38.6           |                         |                         | 0.9     | 11.7         | 102.7                | 102.8               | -0.14                        | -0.16                       | 18.4                | 18.3               | 7.054                        | 6.989                       | -8.94                    | -8.94                        | 28.56                  | 1367         | 34.4366460 | -118.6462072 | Valve Adjustment:Barely Open                                                                                     |             |
| FP-003     | 8/11/2026 2:44:08 PM  | 43.1       | 51.1       | 0.9       | 4.9            |                         |                         | 0.8     | 5.4          | 97.9                 | 98.4                | -0.10                        | -0.10                       | 2.3                 | 2.3                | 0.554                        | 0.557                       | -8.01                    | -8.33                        | 28.56                  | 1372         | 34.4366327 | -118.6465130 |                                                                                                                  |             |
| FP-005     | 8/11/2026 9:42:59 AM  | 0.6        | 9.3        | 14.7      | 75.4           |                         |                         | 0.1     | 5.1          | 97.5                 | 97.5                | -0.45                        | -0.46                       | 4.7                 | 4.7                | 2.288                        | 2.279                       | -7.18                    | -7.31                        | 28.6                   | 1366         | 34.4364405 | -118.6472492 |                                                                                                                  |             |
| FP-006     | 8/11/2026 9:48:50 AM  | 15.1       | 68.4       | 1.0       | 15.5           |                         |                         | 0.2     | 15.5         | 100.3                | 100.4               | -1.80                        | -1.78                       | 1.2                 | 1.4                | 0.030                        | 0.042                       | -5.45                    | -5.68                        | 28.6                   | 1369         | 34.4363648 | -118.6476550 | Well Comment:Valve stuck                                                                                         |             |
| FP-008     | 8/11/2026 10:16:35 AM | 4.1        | 38.6       | 7.9       | 49.4           |                         |                         | 0.1     | 6.3          | 109.2                | 108.7               | -3.08                        | -2.74                       | 0.6                 | 0.3                | 0.079                        | 0.021                       | -9.08                    | -8.96                        | 28.6                   | 1369         | 34.4363308 | -118.6481673 | Valve Adjustment:Decreased Flow/Vacuum                                                                           |             |
| FP-009     | 8/11/2026 10:12:02 AM | 11.6       | 71.2       | 1.1       | 16.1           |                         |                         | 0.2     | 14.6         | 115.2                | 115.2               | -1.06                        | -1.06                       | 4.8                 | 4.8                | 0.475                        | 0.486                       | -8.36                    | -8.44                        | 28.6                   | 1371         | 34.4366593 | -118.6489325 |                                                                                                                  |             |
| FP-010     | 8/10/2026 12:43:14 PM | 25.6       | 72.7       | 0.4       | 1.3            |                         |                         | 0.4     | 3.3          | 118.3                | 118.3               | -0.61                        | -0.71                       | 11.5                | 11.1               | 2.780                        | 2.609                       | -9.09                    | -9.06                        | 28.66                  | 1379         | 34.4366182 | -118.6492527 |                                                                                                                  |             |
| FP-011     | 8/26/2026 9:16:16 AM  | 16.2       | 29.2       | 9.5       | 45.1           |                         |                         | 0.6     | 4.7          | 94.3                 | 94.4                | -1.25                        | -1.25                       | 3.3                 | 3.5                | 0.219                        | 0.252                       | -9.45                    | -9.65                        | 28.52                  | 1370         | 34.4365477 | -118.6495192 |                                                                                                                  |             |
| FP-012     | 8/3/2026 8:19:42 AM   | 3.8        | 1.1        | 19.2      | 75.9           |                         |                         | 3.5     | 4.0          | 84.8                 | 85.4                | -0.29                        | -0.28                       | 0.6                 | 0.4                | 0.008                        | 0.003                       | -15.46                   | -15.86                       | 28.41                  | 1381         | 34.4366737 | -118.6499447 | Valve Adjustment:Barely Open                                                                                     |             |
| FP-013     | 8/3/2026 8:42:22 AM   | 3.0        | 4.7        | 16.2      | 76.1           |                         |                         | 0.6     | 4.7          | 89.8                 | 89.8                | -0.44                        | -0.44                       | 15.1                | 15.3               | 4.649                        | 4.754                       | -12.71                   | -12.97                       | 28.41                  | 1351         | 34.4365702 | -118.6502772 | Valve Adjustment:Barely Open                                                                                     |             |
| FP-014     | 8/13/2026 1:12:35 PM  | 21.3       | 53.6       | 5.6       | 19.5           |                         |                         | 0.4     | 3.5          | 115.4                | 115.4               | -2.63                        | -2.61                       | 13.6                | 13.3               | 3.902                        | 3.755                       | -6.83                    | -6.63                        | 28.63                  | 1359         | 34.4364803 | -118.6482095 |                                                                                                                  |             |
| FP-014     | 8/24/2026 2:06:31 PM  | 14.7       | 66.9       | 2.0       | 16.4           |                         |                         | 0.2     | 8.2          | 166.7                | 165.4               | -1.03                        | -0.84                       | 2.8                 | 2.5                | 0.931                        | 0.749                       | -3.42                    | -3.53                        | 28.53                  | 1382         | 34.4366168 | -118.6492632 | Valve Adjustment:No Flow Measurement,High Temp,Well Condition:Lorentz Pump Installed                             |             |
| FP-015     | 8/11/2026 9:57:56 AM  | 0.6        | 4.5        | 17.9      | 77.0           |                         |                         | 0.1     | 4.3          | 96.9                 | 99.9                | -3.43                        | -3.44                       | 0.7                 | 0.7                | 0.011                        | 0.011                       | -4.87                    | -5.20                        | 28.6                   | 1366         | 34.4364443 | -118.6479340 | Well Comment:valve stuck open                                                                                    |             |
| FP-016     | 8/11/2026 9:53:59 AM  | 0.8        | 3.8        | 19.3      | 76.1           |                         |                         | 0.2     | 3.9          | 94.4                 | 96.3                | -1.69                        | -1.66                       | 0.3                 | 0.4                | 0.021                        | 0.046                       | -5.37                    | -5.41                        | 28.6                   | 1350         | 34.4364490 | -118.6477138 |                                                                                                                  |             |
| FP-017     | 8/11/2026 8:24:57 AM  | 30.4       | 29.8       | 4.2       | 35.6           |                         |                         | 1.0     | 8.5          | 82.6                 | 82.4                | -0.95                        | -0.96                       | 2.3                 | 2.4                | 0.102                        | 0.114                       | -0.17                    | -0.19                        | 28.62                  | 1351         | 34.4343972 | -118.6486557 |                                                                                                                  |             |
| FP-018     | 8/1/2026 10:22:30 AM  | 40.8       | 43.0       | 1.0       | 15.2           |                         |                         | 0.9     | 15.2         | 94.9                 | 95.2                | -3.28                        | -4.03                       | 6.0                 | 8.5                | 0.745                        | 1.497                       | -7.40                    | -7.46                        | 28.6                   | 1356         | 34.4344602 | -118.6490643 | Valve Adjustment:Increased Flow/Vacuum                                                                           |             |
| FP-018     | 8/11/2026 9:11:12 AM  | 15.5       | 44.5       | 5.0       | 35.0           |                         |                         | 0.3     | 7.0          | 88.8                 | 88.8                | -0.96                        | -0.94                       | 7.0                 | 7.2                | 0.973                        | 1.033                       | -9.60                    | -9.95                        | 28.62                  | 1358         | 34.4359733 | -118.6496102 |                                                                                                                  |             |
| FP-019     | 8/3/2026 2:56:57 PM   | 52.7       | 40.5       | 0.2       | 6.6            |                         |                         | 1.3     | 33.0         | 100.1                | 100.3               | -0.48                        | -0.46                       | 2.5                 | 2.6                | 0.126                        | 0.138                       | -9.20                    | -9.03                        | 28.39                  | 1355         | 34.4346800 | -118.6491058 |                                                                                                                  |             |
| FP-019     | 8/11/2026 9:08:56 AM  | 28.7       | 45.1       | 1.2       | 25.0           |                         |                         | 0.6     | 20.8         | 93.9                 | 93.9                | -7.45                        | -7.37                       | 8.1                 | 7.0                | 1.354                        | 0.999                       | -9.07                    | -8.48                        | 28.65                  | 1353         | 34.4357127 | -118.6495083 |                                                                                                                  |             |
| FP-020     | 8/11/2026 9:46:01 AM  | 8.1        | 8.3        | 16.6      | 67.0           |                         |                         | 1.0     | 4.0          | 100.8                | 101.7               | -1.18                        | -1.17                       | 1.1                 | 1.4                | 0.025                        | 0.043                       | -9.66                    | -9.24                        | 28.66                  | 1347         | 34.4347480 | -118.6483838 |                                                                                                                  |             |
| FP-021     | 8/11/2026 9:35:15 AM  | 1.8        | 63.6       | 8.4       | 26.2           |                         |                         | 0.0     | 3.1          | 190.3                | 190.8               | -3.41                        | -3.44                       | 7.8                 | 7.4                | 1.467                        | 1.310                       | -1.69                    | -1.89                        | 28.66                  | 1345         | 34.4351377 | -118.6495765 | Valve Adjustment:High Temp                                                                                       |             |
| FP-021     | 8/11/2026 9:35:59 AM  | 1.7        | 63.6       | 2.9       | 31.8           |                         |                         | 0.0     | 11.0         | 191.2                | 191.1               | -3.15                        | -3.13                       | 6.7                 | 6.6                | 1.059                        | 1.043                       | -1.81                    | -1.81                        | 28.65                  | 1343         | 34.4351437 | -118.6495660 | Valve Adjustment:High Temp                                                                                       |             |
| FP-021     | 8/13/2026 11:53:17 AM | 3.4        | 4.9        | 16.8      | 75.0           |                         |                         | 0.7     | 4.5          | 101.9                | 102.0               | -4.05                        | -3.98                       | 14.0                | 14.7               | 0.248                        | 0.275                       | -4.03                    | -3.92                        | 28.6                   | 1348         | 34.4351627 | -118.6495585 | Valve Adjustment:Valve 100% Open                                                                                 |             |
| FP-022     | 8/11/2026 9:03:17 AM  | 7.9        | 28.0       | 9.7       | 54.4           |                         |                         | 0.3     | 5.6          | 103.0                | 103.3               | -6.69                        | -6.36                       | 6.4                 | 4.9                | 0.850                        | 0.500                       | -8.08                    | -6.97                        | 28.64                  | 1356         | 34.4352440 | -118.6491428 |                                                                                                                  |             |
| FP-022     | 8/11/2026 9:38:52 AM  | 3.5        | 23.2       | 5.4       | 67.9           |                         |                         | 0.2     | 12.6         | 97.8                 | 99.3                | -5.01                        | -5.01                       | 3.7                 | 4.0                | 0.286                        | 0.327                       | -7.18                    | -7.22                        | 28.65                  | 1348         | 34.4351985 | -118.6491833 |                                                                                                                  |             |
| FP-023     | 8/11/2026 9:06:26 AM  | 1.1        | 8.0        | 16.9      | 74.0           |                         |                         | 0.1     | 4.4          | 84.3                 | 84.8                | -0.23                        | -0.24                       | 0.6                 | 0.7                | 0.008                        | 0.009                       | -0.13                    | -0.13                        | 28.65                  | 1348         | 34.4350582 | -118.6494328 |                                                                                                                  |             |
| FP-024     | 8/11/2026 8:36:55 AM  | 6.7        | 25.8       | 11.0      | 56.5           |                         |                         | 0.3     | 5.1          | 89.7                 | 89.7                | -0.88                        | -0.86                       | 2.7                 | 3.2                | 0.148                        | 0.204                       | -10.54                   | -10.58                       | 28.62                  | 1347         | 34.4350000 | -118.6477995 |                                                                                                                  |             |
| FP-025     | 8/11/2026 8:34:52 AM  | 7.3        | 21.9       | 9.4       | 61.4           |                         |                         | 0.3     | 6.5          | 91.2                 | 92.0                | -3.81                        | -2.98                       | 2.0                 | 0.8                | 0.082                        | 0.013                       | -11.06                   | -11.05                       | 28.62                  | 1356         | 34.4353452 | -118.6477698 | Valve Adjustment:Decreased Flow/Vacuum                                                                           |             |
| FP-026     | 8/11/2026 9:51:41 AM  | 15.4       | 27.9       | 9.6       | 47.1           |                         |                         | 0.6     | 4.9          | 94.4                 | 94.3                | -7.67                        | -7.58                       | 19.4                | 19.4               | 7.883                        | 7.868                       | -7.55                    | -7.52                        | 28.63                  | 1363         | 34.4307655 | -118.6481442 |                                                                                                                  |             |
| FP-027     | 8/26/2026 8:54:12 AM  | 14.3       | 24.2       | 8.8       | 52.7           |                         |                         | 0.6     | 6.0          | 93.5                 | 93.6                | -8.77                        | -8.68                       |                     |                    | 9.130                        | 9.047                       | 0.39                     | 0.41                         | 28.52                  | 1362         | 34.4348418 | -118.6482435 | Well Comment:Hard pipped                                                                                         |             |
| FP-028     | 8/26/2026 8:49:51 AM  | 3.2        | 6.3        | 18.1      | 72.4           |                         |                         | 0.5     | 4.0          | 96.3                 | 96.3                | -1.29                        | -1.28                       | 2.5                 | 2.9                | 0.132                        | 0.170                       | -9.60                    | -10.24                       | 28.52                  | 1349         | 34.4347495 | -118.6483947 |                                                                                                                  |             |
| FP-029     | 8/11/2026 8:26:55 AM  | 51.1       | 36.6       | 0.1       | 12.2           |                         |                         | 1.4     | 122.0        | 89.6                 | 90.6                | -0.26                        | -0.19                       | 18.3                | 16.3               | 0.413                        | 0.328                       | -8.13                    | -0.13                        | 28.63                  | 1348         | 34.4343818 | -118.6488958 |                                                                                                                  |             |
| FP-030     | 8/3/2026 2:53:43 PM   | 42.2       | 34.5       | 3.8       | 19.5           |                         |                         | 1.2     | 5.1          | 93.1                 | 93.1                | -0.60                        | -0.68                       | 12.4                | 12.4               | 3.130                        | 3.138                       | -8.90                    | -9.08                        | 28.38                  | 1357         | 34.4345287 | -118.6496770 | Valve Adjustment:Barely Open                                                                                     |             |
| FP-031     | 8/3/2026 2:50:38 PM   | 4.3        | 4.8        | 17.0      | 73.9           |                         |                         | 0.9     | 4.3          | 99.2                 | 100.1               | -                            |                             |                     |                    |                              |                             |                          |                              |                        |              |            |              |                                                                                                                  |             |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name    | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init<br>Flow<br>[scfm] | Adj<br>Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                      |                      |
|---------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|------------------------|-----------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|-------------------------------------------------------------------------------|----------------------|
| FP-036        | 8/3/2026 2:29:32 PM   | 15.9       | 22.4       | 8.9       | 52.8           |                         |                         | 0.7     | 5.9          | 99.8                 | 99.8                | -1.13                        | -1.15                       | 2.3                    | 2.5                   | 1.343                        | 1.570                       | -8.60                     | -9.41                        | 28.37                  | 1379         | 34.4361535 | -118.6502052 |                                                                               |                      |
| FP-037        | 8/3/2026 9:15:00 AM   | 1.7        | 3.5        | 18.1      | 76.7           |                         |                         | 0.5     | 4.2          | 97.3                 | 97.4                | -0.61                        | -0.60                       |                        |                       | 0.000                        | 0.000                       | -10.93                    | -10.22                       | 28.41                  | 1362         | 34.4362492 | -118.6502940 | Valve Adjustment:Barely Open                                                  |                      |
| FP-038        | 8/6/2026 9:41:51 AM   | 12.8       | 16.3       | 11.5      | 59.4           |                         |                         | 0.8     | 5.2          | 91.2                 | 91.3                | -0.84                        | -0.80                       | 12.8                   | 12.8                  | 3.305                        | 3.331                       | -10.85                    | -10.86                       | 28.6                   | 1334         | 34.4340848 | -118.6498037 |                                                                               |                      |
| FP-038        | 8/13/2026 9:53:41 AM  | 2.2        | 32.7       | 10.4      | 54.7           |                         |                         | 0.1     | 5.3          | 96.0                 | 96.1                | -0.01                        | -0.01                       | 0.4                    | 0.5                   | 0.003                        | 0.005                       | 0.54                      | 0.51                         | 28.61                  | 1287         | 34.4348590 | -118.6509275 |                                                                               |                      |
| FP-039        | 8/6/2026 9:47:16 AM   | 0.0        | 0.2        | 20.6      | 79.2           |                         |                         | 0.0     | 3.8          | 90.2                 | 90.5                | -0.04                        | -0.01                       | 23.6                   | 23.5                  | 11.351                       | 11.325                      | -9.32                     | -9.37                        | 28.61                  | 1322         | 34.4341718 | -118.6498375 |                                                                               |                      |
| FP-040        | 8/14/2026 8:22:06 AM  | 18.0       | 74.8       | 0.1       | 7.1            |                         |                         | 0.2     | 71.0         | 104.9                | 105.0               | -0.09                        | -0.10                       |                        |                       | 0.000                        | 0.000                       | -0.44                     | -0.58                        | 28.67                  | 1296         | 34.4353163 | -118.6510622 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In) |                      |
| FP-041        | 8/13/2026 9:37:50 AM  | 16.0       | 23.9       | 4.9       | 55.2           |                         |                         | 0.7     | 11.3         | 83.1                 |                     | -0.25                        |                             | 11.1                   |                       | 2.452                        |                             | -6.07                     |                              | 28.63                  | 1302         | 34.4340390 | -118.6506243 |                                                                               |                      |
| FP-041        | 8/14/2026 8:51:50 AM  | 15.9       | 31.4       | 4.4       | 48.3           |                         |                         | 0.5     | 11.0         | 81.6                 | 81.5                | -0.20                        | -0.25                       | 11.6                   | 11.7                  | 2.649                        | 2.716                       | -6.72                     | -7.14                        | 28.67                  | 1279         | 34.4340457 | -118.6506487 |                                                                               |                      |
| FP-042        | 8/5/2026 8:42:34 AM   | 2.3        | 16.4       | 15.0      | 66.3           |                         |                         | 0.1     | 4.4          | 84.3                 | 84.3                | -0.24                        | -0.21                       | 16.8                   | 16.8                  | 5.815                        | 5.811                       | -4.63                     |                              | 28.63                  | 1286         | 34.4332937 | -118.6513123 |                                                                               |                      |
| FP-043        | 8/13/2026 9:40:58 AM  | 5.6        | 17.5       | 10.0      | 66.9           |                         |                         | 0.3     | 6.7          | 92.9                 | 93.0                | -0.28                        | -0.28                       | 16.1                   | 15.7                  | 5.292                        | 5.002                       | -6.78                     | -6.49                        | 28.63                  | 1278         | 34.4342525 | -118.6508032 |                                                                               |                      |
| FP-044        | 8/13/2026 9:44:28 AM  | 0.1        | 0.5        | 19.9      | 79.5           |                         |                         | 0.2     | 4.0          | 90.0                 | 90.0                | -0.09                        | -0.09                       | 5.2                    | 5.3                   | 0.540                        | 0.563                       | -5.96                     | -6.02                        | 28.63                  | 1289         | 34.4345377 | -118.6507828 |                                                                               |                      |
| FP-045        | 8/31/2026 2:40:07 PM  | 0.0        | 0.1        | 19.7      | 80.2           |                         |                         | 0.0     | 4.1          | 110.6                | 110.6               | -0.47                        | -0.47                       | 40.4                   | 40.2                  | 3.767                        | 3.735                       | -8.13                     | -8.06                        | 28.52                  | 1319         | 34.4334480 | -118.6496632 | Valve Adjustment:Barely Open                                                  |                      |
| FP-046        | 8/11/2026 9:40:56 AM  | 13.5       | 43.9       | 6.8       | 35.8           |                         |                         | 0.3     | 5.3          | 95.7                 | 95.6                | -0.81                        | -0.82                       | 13.9                   | 13.8                  | 3.929                        | 3.912                       | -5.90                     | -5.75                        | 28.6                   | 1369         | 34.4365468 | -118.6473070 | Valve Adjustment:Barely Open                                                  |                      |
| FP-047        | 8/13/2026 12:38:26 PM | 26.1       | 31.2       | 3.4       | 39.3           |                         |                         | 0.8     | 11.6         | 100.0                | 100.3               | -0.02                        | -0.02                       | 1.6                    | 1.2                   | 0.051                        | 0.030                       | -0.20                     | -0.20                        | 28.63                  | 1350         | 34.4367085 | -118.6469338 |                                                                               |                      |
| FP-047        | 8/18/2026 9:19:33 AM  | 12.4       | 16.6       | 10.1      | 60.9           |                         |                         | 0.8     | 6.0          | 94.2                 | 98.1                | -0.06                        | -0.06                       | 1.2                    | 1.2                   | 0.030                        | 0.027                       | 0.00                      | 0.00                         | 28.6                   | 1348         | 34.4367370 | -118.6469263 | Valve Adjustment:Surging Liquid in Header                                     |                      |
| FP-050        | 8/9/2026 1:07:02 PM   | 39.3       | 47.8       | 0.0       | 12.9           |                         |                         | 0.8     | 0.0          | 112.9                | 114.7               | -0.05                        | -0.05                       | 5.1                    | 5.1                   | 0.167                        | 0.167                       | -8.06                     | -7.99                        | 28.5                   | 1358         | 34.4348885 | -118.6472772 |                                                                               |                      |
| FP-051        | 8/26/2026 1:49:02 PM  | 35.1       | 59.6       | 0.7       | 4.6            |                         |                         | 0.6     | 6.6          | 121.4                | 121.4               | -0.24                        | -0.23                       | 25.1                   | 24.4                  | 0.824                        | 0.784                       | -5.17                     | -5.12                        | 28.45                  | 1375         | 34.4345635 | -118.6473528 |                                                                               |                      |
| FP-052        | 8/6/2026 2:49:32 PM   | 1.8        | 5.8        | 16.5      | 75.9           |                         |                         | 0.3     | 4.6          | 102.1                | 102.3               | -0.09                        | -0.09                       | 12.5                   | 12.0                  | 0.964                        | 0.893                       | -4.92                     | -4.52                        | 28.51                  | 1371         | 34.4342150 | -118.6481045 | Valve Adjustment:Barely Open                                                  |                      |
| FP-053        | 8/6/2026 2:58:16 PM   | 9.1        | 12.1       | 13.2      | 65.6           |                         |                         | 0.8     | 5.0          | 106.4                | 106.5               | -0.22                        | -0.25                       | 3.5                    | 3.5                   | 0.257                        | 0.250                       | -12.83                    | -13.40                       | 28.49                  | 1369         | 34.4340670 | -118.6477472 | Valve Adjustment:Barely Open                                                  |                      |
| FP-054        | 8/7/2026 8:59:29 AM   | 17.8       | 30.6       | 6.5       | 45.1           |                         |                         | 0.6     | 6.9          | 91.9                 | 91.6                | -0.62                        | -0.62                       |                        |                       | 0.000                        | 0.000                       | -7.96                     | -8.15                        | 28.61                  | 1377         | 34.4343420 | -118.6470948 | Valve Adjustment:Barely Open                                                  |                      |
| FP-055        | 8/6/2026 2:19:07 PM   | 1.0        | 5.2        | 17.1      | 76.7           |                         |                         | 0.2     | 4.5          | 112.4                | 113.5               | -0.10                        | -0.08                       | 9.1                    | 8.9                   | 1.751                        | 1.653                       | -12.89                    | -12.92                       | 28.51                  | 1367         | 34.4335992 | -118.6481680 |                                                                               |                      |
| FP-056        | 8/6/2026 10:19:12 AM  | 2.8        | 12.3       | 17.8      | 67.1           |                         |                         | 0.2     | 3.8          | 103.3                | 103.4               | -0.50                        | -0.46                       | 4.0                    | 4.1                   | 4.238                        | 4.334                       | -17.81                    | -17.77                       | 28.59                  | 1353         | 34.4334882 | -118.6486345 |                                                                               |                      |
| FP-057        | 8/11/2026 1:48:36 PM  | 46.2       | 33.3       | 1.2       | 19.3           |                         |                         | 1.4     | 16.1         | 98.0                 | 97.8                | -0.71                        | -0.97                       | 15.0                   | 21.0                  | 4.599                        | 9.153                       | -18.94                    | -18.94                       | 28.62                  | 1392         | 34.4347905 | -118.6455768 | Valve Adjustment:Increased Flow/Vacuum                                        |                      |
| FP-058        | 8/11/2026 2:10:52 PM  | 25.5       | 23.7       | 4.0       | 46.8           |                         |                         | 1.1     | 11.7         | 100.3                | 100.4               | -0.79                        | -0.80                       | 9.1                    | 9.0                   | 1.715                        | 1.670                       | -17.64                    | -18.90                       | 28.62                  | 1405         | 34.4349883 | -118.6458170 |                                                                               |                      |
| FP-059        | 8/9/2026 1:59:26 PM   | 33.8       | 31.5       | 5.9       | 28.8           |                         |                         | 1.1     | 4.9          | 120.0                | 120.0               | -0.47                        | -0.46                       | 32.5                   | 32.6                  | 2.482                        | 2.485                       | -15.24                    | -15.23                       | 28.47                  | 1374         | 34.4345968 | -118.6458962 | Valve Adjustment:Orifice Plate Changed (See OP Log)                           |                      |
| FP-060        | 8/17/2026 11:08:17 AM | 17.6       | 19.6       | 5.1       | 57.7           |                         |                         | 0.9     | 11.3         | 109.5                | 106.0               | -0.07                        | -0.34                       | 10.4                   | 11.8                  | 2.263                        | 2.879                       | -3.57                     | -3.88                        | 28.69                  | 1344         | 34.4332293 | -118.6493725 | Valve Adjustment:Increased Flow/Vacuum                                        |                      |
| FP-061        | 8/11/2026 10:00:58 AM | 5.4        | 33.5       | 8.7       | 52.4           |                         |                         | 0.2     | 6.0          | 128.4                | 125.7               | -3.46                        | -2.94                       | 2.6                    | 0.6                   | 0.149                        | 0.008                       | -5.17                     | -5.39                        | 28.6                   | 1370         | 34.4364452 | -118.6479375 | Valve Adjustment:Barely Open                                                  |                      |
| FP-062        | 8/13/2026 3:10:39 PM  | 8.3        | 68.8       | 0.0       | 22.9           |                         |                         | 0.1     | 0.0          | 146.4                | 146.9               | -0.16                        | -0.19                       | 12.0                   | 12.5                  | 0.954                        | 1.049                       | -0.44                     | -0.14                        | 28.61                  | 1299         | 34.4349140 | -118.6512032 | Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum     |                      |
| FP-062        | 8/13/2026 3:12:09 PM  | 8.1        | 67.5       | 0.0       | 24.4           |                         |                         | 0.1     | 0.0          | 147.1                | 147.1               | -0.35                        | -0.34                       | 20.3                   | 26.6                  | 0.561                        | 0.966                       | -0.64                     | -0.92                        | 28.63                  | 1306         | 34.4349215 | -118.6512067 | Valve Adjustment:Valve 100% Open                                              |                      |
| FP-063        | 8/13/2026 3:17:15 PM  | 0.3        | 5.8        | 20.7      | 73.3           |                         |                         | 0.0     | 3.5          | 92.6                 | 93.2                | -1.55                        | -0.32                       | 1.4                    | 3.2                   | 0.012                        | 0.060                       | -1.66                     | -1.60                        | 28.63                  | 1303         | 34.4349628 | -118.6511920 | Valve Adjustment:Decreased Flow/Vacuum                                        |                      |
| H-01 (EXP-01) | 8/11/2026 1:58:16 PM  | 11.6       | 45.6       | 0.1       | 42.7           |                         |                         | 0.3     | 427.0        | 101.6                | 102.1               | -4.38                        | -4.38                       |                        |                       | 4.387                        | 4.387                       | -14.16                    | -14.16                       | 28.71                  | 1227         | 34.4376663 | -118.6441315 | Valve Adjustment:Surging Liquid in Header                                     |                      |
| H-01 (EXP-01) | 8/18/2026 12:13:44 PM | 11.7       | 45.7       | 0.0       | 42.7           |                         |                         | 0.3     | 0.0          | 110.2                | 110.8               | -3.65                        | -3.65                       |                        |                       | 3.649                        | 3.677                       | -13.17                    | -13.16                       | 28.72                  | 1276         | 34.4376593 | -118.6441950 |                                                                               |                      |
| H-01 (EXP-01) | 8/25/2026 9:41:00 AM  |            |            |           |                |                         | 407000                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                               | [User entered 40.7%] |
| H-01 (EXP-01) | 8/25/2026 9:41:53 AM  | 11.8       | 47.0       | 0.0       | 41.2           |                         |                         | 0.3     | 0.0          | 110.8                | 111.1               | -4.78                        | -4.78                       |                        |                       | 4.814                        | 4.810                       | -14.39                    | -14.30                       | 28.72                  | 1228         | 34.4376860 | -118.6441702 |                                                                               |                      |
| H-01 (EXP-01) | 8/25/2026 10:05:37 AM |            |            |           |                | 0                       |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                               |                      |
| H-02 (EXP-01) | 8/11/2026 1:54:43 PM  | 18.4       | 50.5       | 0.1       | 31.0           |                         |                         | 0.4     | 310.0        | 116.6                | 116.6               | -11.14                       | -11.14                      |                        |                       | 11.169                       | 11.061                      | -14.02                    | -13.97                       | 28.71                  | 1246         | 34.4377155 | -118.6446037 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In) |                      |
| H-02 (EXP-01) | 8/18/2026 12:11:07 PM | 17.2       | 46.2       | 0.0       | 36.6           |                         |                         | 0.4     | 0.0          | 123.1                | 123.4               | -4.35                        | -4.35                       |                        |                       | 4.395                        | 4.394                       | -13.03                    | -13.08                       | 28.72                  | 1255         | 34.4376790 | -118.6446198 |                                                                               |                      |
| H-02 (EXP-01) | 8/25/2026 9:36:00 AM  |            |            |           |                |                         | 332000                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                               | [User entered 33.2%] |
| H-02 (EXP-01) | 8/25/2026 9:36:27 AM  | 17.5       | 48.0       | 0.0       | 34.5           |                         |                         | 0.4     | 0.0          | 122.7                | 123.1               | -5.51                        | -5.50                       |                        |                       | 5.724                        | 5.744                       | -14.35                    | -14.32                       | 28.72                  | 1228         | 34.4376948 | -118.6446063 |                                                                               |                      |
| H-02 (EXP-01) | 8/25/2026 10:04:01 AM |            |            |           |                | 0                       |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                               |                      |
| H-03 (EXP-01) | 8/11/2026 1:52:02 PM  | 46.6       | 45.5       | 1.8       | 6.1            |                         |                         | 1.0     | 3.4          | 118.5                | 118.4               | -13.84                       | -13.84                      |                        |                       | 13.836                       | 13.788                      | -13.96                    | -13.87                       | 28.7                   | 1263         | 34.4377327 | -118.6446033 |                                                                               |                      |
| H-03 (EXP-01) | 8/18/2026 12:08:35 PM | 48.6       | 46.6       | 0.0       | 4.7            |                         |                         | 1.0     | 0.0          | 121.6                | 122.0               | -12.76                       | -12.76                      |                        |                       | 12.861                       | 12.894                      | -13.12                    | -13.16                       | 28.71                  | 1244         | 34.4376915 | -118.6446480 |                                                                               |                      |
| H-03 (EXP-01) | 8/25/2026 9:33:00 AM  |            |            |           |                |                         | 23000                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                               | [User entered 2.3%]  |
| H-03 (EXP-01) | 8/25/2026 9:33:25 AM  | 49.1       | 46.5       | 0.0       | 4.4            |                         |                         | 1.1     | 0.0          | 122.2                | 123.1               | -14.00                       | -13.89                      |                        |                       | 14.181                       | 14.139                      | -14.32                    | -14.26                       | 28.72                  | 1234         | 34.4377067 | -118.6446240 |                                                                               |                      |
| H-03 (EXP-01) | 8/25/2026 10:02:21 AM |            |            |           |                | 0                       |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                               |                      |
| H-04 (EXP-01) | 8/11/2026 1:46:46 PM  | 3.4        | 52.3       | 0.2       | 44.1           |                         |                         | 0.1     | 220.5        | 135.1                | 135.1               | -7.72                        | -7.72                       |                        |                       | 7.810                        | 7.779                       | -14.14                    | -14.12                       | 28.7                   | 1255         | 34.4377492 | -118.6446953 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In) |                      |
| H-04 (EXP-01) | 8/18/2026 12:04:32 PM | 2.5        | 52.0       | 0.0       | 45.5           |                         |                         | 0.0     | 0.0          | 136.7                | 136.6               | -7.39                        | -7.39                       |                        |                       | 7.523                        | 7.520                       | -13.16                    | -13.16                       | 28.72                  | 1248         | 34.4377038 | -118.6446978 | Valve Adjustment:NSPS/EG CAI,High Temp                                        |                      |
| H-04 (EXP-01) | 8/18/2026 12:05:19 PM | 2.4        | 52.0       | 0.0       | 45.6           |                         |                         | 0.0     | 0.0          | 136.6                | 136.6               | -7.39                        | -7.39                       |                        |                       | 7.520                        | 7.525                       | -13.16                    | -13.14                       | 28.72                  | 1241         | 34.4377130 | -118.6446892 | Valve Adjustment:High Temp                                                    |                      |
| H-04 (EXP-01) | 8/25/2026 9:47:31 AM  | 2.8        | 53.8       | 0.0       | 43.5           |                         |                         | 0.1     | 0.0          | 136.7                | 136.9               | -8.52                        | -9.23                       |                        |                       | 8.813                        | 9.585                       | -14.14                    | -14.20                       | 28.72                  | 1233         | 34.4377000 | -118.6447062 | Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum                  |                      |
| H-04 (EXP-01) | 8/25/2026 9:48:00 AM  |            |            |           |                |                         | 392000                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                               | [User entered 39.2%] |
| H-04 (EXP-01) | 8/25/2026 9:48:24 AM  | 2.7        | 53.8       | 0.0       | 43.5           |                         |                         | 0.0     | 0.0          | 137.1                | 137.1               | -9.86                        | -9.86                       |                        |                       | 10.194                       | 10.234                      | -14.10                    | -14.24                       | 28.72                  | 1235         | 34.4377083 | -118.6447103 | Valve Adjustment:High Temp                                                    |                      |
| H-04 (EXP-01) | 8/25/2026 10:00:43 AM |            |            |           |                | 0                       |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                               |                      |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name    | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init<br>Flow<br>[scfm] | Adj<br>Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                  |
|---------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|------------------------|-----------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|---------------------------------------------------------------------------------------------------------------------------|
| H-10 (EXP-10) | 8/18/2026 9:07:58 AM  | 11.2       | 66.8       | 0.0       | 22.0           |                         |                         | 0.2     | 0.0          | 130.5                | 130.5               | -0.83                        | -0.83                       |                        |                       | 0.837                        | 0.840                       | -13.24                    | -13.31                       | 28.65                  | 1295         | 34.4374482 | -118.6471182 |                                                                                                                           |
| H-1404C       | 8/14/2026 12:37:35 PM | 24.7       | 37.5       | 0.0       | 37.8           |                         |                         | 0.7     | 0.0          | 102.5                | 102.6               | -0.08                        | -0.07                       | 0.6                    | 0.8                   | 0.008                        | 0.014                       | -10.69                    | -8.61                        | 28.6                   | 1365         | 34.4323895 | -118.6483128 | Valve Adjustment:Barely Open                                                                                              |
| H-1404C       | 8/28/2026 12:50:34 PM | 37.0       | 59.8       | 0.0       | 3.2            |                         |                         | 0.6     | 0.0          | 114.5                | 124.2               | -0.03                        | -0.13                       | 1.9                    | 2.6                   | 0.387                        | 0.757                       | -5.91                     | -6.02                        | 28.65                  | 1367         | 34.4324090 | -118.6483010 | Valve Adjustment:Barely Open                                                                                              |
| H-1405C       | 8/5/2026 10:08:45 AM  | 22.6       | 66.6       | 1.0       | 9.8            |                         |                         | 0.3     | 9.8          | 97.0                 | 97.0                | -0.36                        | -0.39                       | 1.2                    | 1.5                   | 0.010                        | 0.015                       | -0.16                     |                              | 28.58                  | 1260         | 34.4326527 | -118.6496890 |                                                                                                                           |
| H-1405C       | 8/17/2026 9:47:46 AM  | 10.6       | 22.4       | 0.8       | 66.2           |                         |                         | 0.5     | 82.8         | 115.6                | 115.5               | -0.69                        | -0.62                       | 1.3                    | 1.1                   | 0.011                        | 0.008                       | -0.63                     | -0.67                        | 28.7                   | 1291         | 34.4325987 | -118.6497130 | Valve Adjustment:Surging Liquid in Header                                                                                 |
| H-1406W       | 8/5/2026 9:30:16 AM   | 24.2       | 54.9       | 4.2       | 16.7           |                         |                         | 0.4     | 4.0          | 91.8                 | 91.9                | -10.50                       | -3.62                       | 4.0                    | 6.1                   | 0.113                        | 0.252                       | -16.60                    |                              | 28.63                  | 1273         | 34.4317957 | -118.6502907 |                                                                                                                           |
| H-1406W       | 8/25/2026 2:01:20 PM  | 18.7       | 52.2       | 6.3       | 22.8           |                         |                         | 0.4     | 3.6          | 113.2                | 113.9               | -7.26                        | -7.08                       | 1.8                    | 0.3                   | 0.020                        | 0.001                       | -6.99                     | -6.98                        | 28.64                  | 1247         | 34.4321810 | -118.6507923 | Valve Adjustment: NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Surging Liquid in Header,Plugged/Pinched Suspected            |
| H-1406W       | 8/25/2026 2:02:38 PM  | 24.8       | 67.6       | 1.0       | 6.6            |                         |                         | 0.4     | 6.6          | 115.1                | 115.3               | -7.03                        | -6.88                       | 2.3                    | 1.8                   | 0.032                        | 0.021                       | -6.84                     | -6.60                        | 28.63                  | 1254         | 34.4321825 | -118.6507762 | Valve Adjustment:High O2,Surging Liquid in Header,Plugged/Pinched Suspected                                               |
| H-1408CR      | 8/31/2026 2:11:04 PM  | 50.3       | 38.2       | 0.0       | 11.5           |                         |                         | 1.3     | 0.0          | 121.6                | 121.8               | -0.33                        | -1.00                       | 19.7                   | 35.7                  | 0.907                        | 2.982                       | -13.28                    | -13.36                       | 28.62                  | 1266         | 34.4314583 | -118.6472443 |                                                                                                                           |
| H-1408E       | 8/4/2026 1:17:13 PM   | 54.1       | 45.5       | 0.0       | 0.4            |                         |                         | 1.2     | 0.0          | 116.7                | 121.5               | -0.03                        | -0.17                       | 8.0                    | 17.2                  | 0.407                        | 1.898                       | -6.33                     | -6.37                        | 28.44                  | 1384         | 34.4333547 | -118.6471283 | Valve Adjustment:Increased Flow/Vacuum,Barely Open                                                                        |
| H-1408E       | 8/16/2026 1:34:55 PM  | 53.8       | 42.1       | 0.0       | 4.1            |                         |                         | 1.3     | 0.0          | 94.4                 | 95.8                | 0.05                         | -0.01                       | 3.3                    | 2.3                   | 1.150                        | 0.546                       | -6.30                     | -6.15                        | 28.64                  | 1389         | 34.4333590 | -118.6471705 | Valve Adjustment: NSPS/EG CAI,NSPS/EG CAC,Orifice Plate Changed (See OP Log),Positive Static Press.,Increased Flow/Vacuum |
| H-1408E       | 8/16/2026 1:36:31 PM  | 53.1       | 42.1       | 0.0       | 4.9            |                         |                         | 1.3     | 0.0          | 95.6                 | 95.1                | -0.02                        | -0.09                       | 5.0                    | 6.3                   | 0.507                        | 0.810                       | -5.91                     | -6.33                        | 28.66                  | 1393         | 34.4333505 | -118.6471692 | Valve Adjustment:Increased Flow/Vacuum                                                                                    |
| H-1408E       | 8/16/2026 1:37:43 PM  | 52.8       | 42.8       | 0.0       | 4.4            |                         |                         | 1.2     | 0.0          | 96.7                 | 96.5                | -0.10                        | -0.10                       | 6.6                    | 6.2                   | 0.882                        | 0.791                       | -6.63                     | -5.79                        | 28.65                  | 1384         | 34.4333313 | -118.6471660 | Valve Adjustment:Surging Liquid in Header                                                                                 |
| H-1408W       | 8/27/2026 1:40:57 PM  | 54.1       | 39.2       | 0.0       | 6.7            |                         |                         | 1.4     | 0.0          | 110.0                | 110.0               | -0.05                        | -0.04                       | 5.1                    | 5.5                   | 0.033                        | 0.039                       | -10.62                    | -11.72                       | 28.62                  | 1247         | 34.4311860 | -118.6500083 | Valve Adjustment:Barely Open                                                                                              |
| H-1409N       | 8/4/2026 3:54:41 PM   | 40.9       | 35.7       | 0.0       | 23.4           |                         |                         | 1.1     | 0.0          | 122.4                | 122.4               | -0.60                        | -0.60                       | 0.8                    | 0.8                   | 0.185                        | 0.187                       | -8.63                     | -8.75                        | 28.41                  | 1341         | 34.4328402 | -118.6469433 | Valve Adjustment:Barely Open                                                                                              |
| H-1409N       | 8/21/2026 8:24:40 AM  | 44.0       | 37.4       | 0.0       | 18.6           |                         |                         | 1.2     | 0.0          | 119.0                | 119.5               | -0.56                        | -0.95                       | 0.8                    | 0.3                   | 0.174                        | 0.031                       | -8.83                     | -8.70                        | 28.6                   | 1376         | 34.4328932 | -118.6469412 | Valve Adjustment:Increased Flow/Vacuum,Barely Open                                                                        |
| H-1410S       | 8/18/2026 10:30:17 AM | 48.5       | 39.1       | 0.0       | 12.4           |                         |                         | 1.2     | 0.0          | 103.5                | 103.8               | -11.45                       | -11.45                      | 0.9                    | 1.9                   | 0.001                        | 0.005                       | -12.21                    | -12.10                       | 28.76                  | 1204         | 34.4309705 | -118.6467075 | Valve Adjustment:Barely Open                                                                                              |
| H-1563N       | 8/6/2026 9:39:27 AM   | 21.8       | 33.7       | 1.0       | 43.5           |                         |                         | 0.6     | 43.5         | 126.0                | 126.0               | -6.30                        | -5.07                       | 1.7                    | 3.7                   | 0.018                        | 0.091                       | -9.91                     | -9.49                        | 28.6                   | 1318         | 34.4338835 | -118.6498182 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open                                                                        |
| H-1563N       | 8/19/2026 10:29:24 AM | 47.5       | 37.5       | 0.2       | 14.8           |                         |                         | 1.3     | 74.0         | 127.6                | 127.5               | -1.53                        | -1.40                       | 2.7                    | 2.6                   | 0.046                        | 0.043                       | -1.99                     | -3.21                        | 28.58                  | 1331         | 34.4338505 | -118.6498215 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open                                                                        |
| H-1563S       | 8/5/2026 10:13:01 AM  | 13.9       | 23.3       | 0.0       | 62.8           |                         |                         | 0.6     | 0.0          | 98.3                 | 98.5                | -1.97                        | -1.29                       | 8.7                    | 1.8                   | 8.005                        | 0.344                       | -15.11                    |                              | 28.57                  | 1309         | 34.4323607 | -118.6496843 |                                                                                                                           |
| H-1563S       | 8/17/2026 9:41:28 AM  | 8.0        | 22.1       | 0.0       | 69.9           |                         |                         | 0.4     | 0.0          | 102.8                | 102.8               | -0.83                        | -0.74                       | 1.8                    | 1.1                   | 0.342                        | 0.136                       | -13.43                    | -13.13                       | 28.69                  | 1308         | 34.4324068 | -118.6496693 | Valve Adjustment:Decreased Flow/Vacuum                                                                                    |
| H-1565E       | 8/4/2026 1:23:39 PM   | 43.0       | 38.8       | 0.3       | 17.9           |                         |                         | 1.1     | 59.7         | 114.0                | 113.9               | -0.31                        | -0.29                       | 1.1                    | 2.0                   | 0.008                        | 0.026                       | -4.58                     | -4.69                        | 28.43                  | 1371         | 34.4335643 | -118.6472243 | Valve Adjustment:Barely Open                                                                                              |
| H-1565E       | 8/21/2026 9:45:23 AM  | 45.6       | 48.7       | 0.0       | 5.7            |                         |                         | 0.9     | 0.0          | 108.2                | 108.4               | -0.05                        | -0.05                       | 2.0                    | 2.4                   | 0.026                        | 0.035                       | -5.53                     | -4.94                        | 28.57                  | 1391         | 34.4335702 | -118.6471808 | Valve Adjustment:Barely Open                                                                                              |
| H-1568N       | 8/4/2026 1:20:25 PM   | 49.7       | 41.2       | 0.0       | 9.1            |                         |                         | 1.2     | 0.0          | 119.4                | 119.3               | -0.87                        | -0.78                       | 4.2                    | 4.7                   | 0.378                        | 0.476                       | -6.49                     | -6.31                        | 28.42                  | 1375         | 34.4333693 | -118.6471543 | Valve Adjustment:Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down                                                      |
| H-1568N       | 8/16/2026 1:27:37 PM  | 41.2       | 51.9       | 0.0       | 7.0            |                         |                         | 0.8     | 0.0          | 119.3                | 119.4               | -0.36                        | -0.35                       | 2.8                    | 2.6                   | 0.169                        | 0.142                       | -5.93                     | -5.63                        | 28.64                  | 1386         | 34.4333492 | -118.6471763 | Valve Adjustment:Orifice Plate Changed (See OP Log)                                                                       |
| H-1568N       | 8/16/2026 1:28:30 PM  | 40.4       | 52.3       | 0.0       | 7.3            |                         |                         | 0.8     | 0.0          | 117.1                | 117.2               | -0.27                        | -0.27                       | 2.7                    | 2.7                   | 0.786                        | 0.783                       | -6.31                     | -6.24                        | 28.65                  | 1386         | 34.4333605 | -118.6471688 |                                                                                                                           |
| H-1571S       | 8/18/2026 9:56:42 AM  | 37.2       | 38.3       | 0.0       | 24.5           |                         |                         | 1.0     | 0.0          | 101.8                | 103.9               | -0.96                        | -0.48                       | 2.1                    | 1.8                   | 0.010                        | 0.007                       | -19.77                    | -19.72                       | 28.69                  | 1267         | 34.4321482 | -118.6452522 | Valve Adjustment:Decreased Flow/Vacuum                                                                                    |
| H-1572N       | 8/17/2026 1:19:28 PM  | 40.0       | 33.1       | 2.6       | 24.3           |                         |                         | 1.2     | 9.3          | 127.2                | 124.8               | -0.82                        | -0.68                       | 0.5                    | 0.8                   | 0.005                        | 0.013                       | -16.88                    | -16.73                       | 28.64                  | 1342         | 34.4336973 | -118.6447612 | Valve Adjustment:Decreased Flow/Vacuum                                                                                    |
| H-1572S       | 8/18/2026 9:47:28 AM  | 32.6       | 34.3       | 0.0       | 33.1           |                         |                         | 1.0     | 0.0          | 114.7                | 114.7               | -1.40                        | -0.67                       | 7.1                    | 6.3                   | 0.116                        | 0.090                       | -16.00                    | -15.92                       | 28.7                   | 1270         | 34.4321868 | -118.6447418 | Valve Adjustment:Decreased Flow/Vacuum                                                                                    |
| H-1753N       | 8/3/2026 2:59:18 PM   | 46.4       | 38.2       | 2.0       | 13.4           |                         |                         | 1.2     | 6.7          | 100.9                | 101.8               | -0.12                        | -0.11                       | 2.7                    | 2.2                   | 0.017                        | 0.011                       | -8.80                     | -8.44                        | 28.41                  | 1363         | 34.4347560 | -118.6492938 | Valve Adjustment:Barely Open                                                                                              |
| H-1753N       | 8/11/2026 9:42:02 AM  | 54.2       | 37.2       | 0.0       | 8.6            |                         |                         | 1.5     | 0.0          | 97.8                 | 97.8                | -3.37                        | -3.59                       | 11.0                   | 11.5                  | 0.274                        | 0.299                       | -9.28                     | -8.86                        | 28.66                  | 1343         | 34.4347163 | -118.6493343 | Valve Adjustment:Increased Flow/Vacuum                                                                                    |
| H-1753N       | 8/25/2026 10:06:43 AM | 32.4       | 26.5       | 7.6       | 33.5           |                         |                         | 1.2     | 4.4          | 103.7                | 103.9               | -2.93                        | -1.81                       | 3.3                    | 3.0                   | 0.025                        | 0.020                       | -6.10                     | -6.22                        | 28.6                   | 1348         | 34.4347323 | -118.6493037 | Valve Adjustment:High O2,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)               |
| H-1753N       | 8/25/2026 10:07:22 AM | 32.6       | 25.8       | 7.7       | 33.9           |                         |                         | 1.3     | 4.4          | 104.4                | 104.4               | -1.87                        | -1.83                       | 2.3                    | 1.9                   | 0.012                        | 0.008                       | -6.24                     | -6.32                        | 28.6                   | 1346         | 34.4347130 | -118.6493212 | Valve Adjustment:High O2,Barely Open                                                                                      |
| H-1753S       | 8/6/2026 9:53:34 AM   | 23.2       | 31.3       | 0.0       | 45.5           |                         |                         | 0.7     | 0.0          | 118.2                | 118.2               | -4.91                        | -4.46                       | 4.9                    | 4.7                   | 0.519                        | 0.468                       | -9.24                     | -9.38                        | 28.6                   | 1341         | 34.4339405 | -118.6495730 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open                                                                        |
| H-1753S       | 8/19/2026 10:25:32 AM | 37.7       | 34.1       | 0.1       | 28.1           |                         |                         | 1.1     | 281.0        | 117.3                | 115.6               | -4.13                        | -3.70                       | 10.9                   | 11.6                  | 2.526                        | 2.885                       | -2.91                     | -3.32                        | 28.55                  | 1343         | 34.4339185 | -118.6495837 | Valve Adjustment:Barely Open;Well Comment:possibly damaged valve                                                          |
| H-1756S       | 8/5/2026 9:40:45 AM   | 39.3       | 49.8       | 0.8       | 10.1           |                         |                         | 0.8     | 12.6         | 124.0                | 124.6               | -0.86                        | -0.87                       | 12.9                   | 12.9                  | 0.218                        | 0.218                       | -15.42                    |                              | 28.6                   | 1319         | 34.4325860 | -118.6502343 |                                                                                                                           |
| H-1756S       | 8/17/2026 9:58:51 AM  | 32.5       | 42.7       | 2.4       | 22.4           |                         |                         | 0.8     | 9.3          | 125.0                | 124.5               | -0.89                        | -0.63                       | 17.9                   | 4.9                   | 0.419                        | 0.031                       | -10.69                    | -10.81                       | 28.72                  | 1285         | 34.4325755 | -118.6502862 | Valve Adjustment:Decreased Flow/Vacuum                                                                                    |
| H-1756S       | 8/17/2026 10:00:51 AM | 32.0       | 42.2       | 2.3       | 23.5           |                         |                         | 0.8     | 10.2         | 125.2                | 123.4               | -0.56                        | -0.56                       | 1.9                    | 2.1                   | 0.005                        | 0.006                       | -9.53                     | -8.23                        | 28.73                  | 1287         | 34.4325695 | -118.6502955 |                                                                                                                           |
| H-1757S       | 8/5/2026 9:58:36 AM   | 10.3       | 15.5       | 11.9      | 62.3           |                         |                         | 0.7     | 5.2          | 96.3                 | 96.4                | -0.87                        | -0.75                       | 2.2                    | 3.2                   | 0.010                        | 0.022                       | -15.21                    |                              | 28.58                  |              |            |              | NSPS/EG CAI,High O2                                                                                                       |
| H-1757S       | 8/5/2026 10:00:50 AM  | 26.6       | 31.1       | 0.0       | 42.3           |                         |                         | 0.9     | 0.0          | 99.5                 | 99.4                | -1.28                        | -1.25                       | 1.8                    | 1.3                   | 0.007                        | 0.004                       | -15.34                    |                              | 28.58                  | 1322         | 34.4327243 | -118.6497180 | NSPS/EG CAC,                                                                                                              |
| H-1757S       | 8/17/2026 9:50:12 AM  | 47.2       | 40.7       | 0.0       | 12.1           |                         |                         | 1.2     | 0.0          | 94.7                 | 94.9                | -0.59                        | -0.58                       | 3.2                    | 3.2                   | 0.022                        | 0.022                       | -12.36                    | -12.46                       | 28.69                  | 1307         | 34.4327130 | -118.6497867 | Valve Adjustment:Audible Flow                                                                                             |
| H-1760S       | 8/4/2026 4:08:51 PM   | 29.7       | 64.3       | 0.1       | 5.9            |                         |                         | 0.5     | 59.0         | 121.6                | 121.6               | -0.78                        | -0.78                       | 4.0                    | 4.1                   | 0.105                        | 0.106                       | -8.92                     | -8.92                        | 28.41                  | 1375         | 34.4327220 | -118.6479248 | Valve Adjustment:Barely Open                                                                                              |
| H-1760S       | 8/21/2026 8:33:24 AM  | 26.5       | 71.8       | 0.0       | 1.7            |                         |                         | 0.4     | 0.0          | 119.0                | 118.9               | -0.86                        | -0.81                       | 2.0                    | 3.7                   | 0.026                        | 0.088                       | -8.75                     | -8.95                        | 28.56                  | 1378         | 34.4327540 | -118.6478690 | Valve Adjustment:Barely Open                                                                                              |
| H-1760S       | 8/26/2026 1:41:04 PM  | 27.0       | 70.0       | 0.0       | 3.0            |                         |                         | 0.4     | 0.0          | 117.9                | 117.9               | -0.24                        | -0.44                       | 2.2                    | 3.6                   | 0.031                        | 0.081                       | -6.12                     | -6.09                        | 28.59                  | 1380         | 34.4327243 | -118.6478923 | Valve Adjustment:Increased Flow/Vacuum                                                                                    |
| H-1762N       | 8/4/2026 1:05:50 PM   | 42.9       | 38.1       | 0.0       | 19.0           |                         |                         | 1.1     | 0.0          | 117.3                | 117.3               | -0.20                        | -0.17                       | 4.7                    | 4.8                   | 0.474                        | 0.489                       | -6.73                     | -6.67                        | 28.42                  | 1374         | 34.4334640 | -118.6468253 | Valve Adjustment:Barely Open                                                                                              |
| H-1762N       | 8/16/2026 1:15:29 PM  | 47.9       | 37.1       | 0.0       | 15.1           |                         |                         | 1.3     | 0.0          | 119.0                | 119.0               | -0.15                        | -0.18                       | 4.1                    | 5.0                   | 0.356                        | 0.534                       | -6.51                     | -6.12                        | 28.64                  | 1387         | 34.4334522 | -118.6468713 | Valve Adjustment:Increased Flow/Vacuum                                                                                    |
| H-1762N       | 8/16/2026 1:16:12 PM  | 47.4       | 37.6       | 0.0       | 15.0           |                         |                         | 1.3     | 0.0          | 119.1                | 119.0               | -0.25                        | -0.24                       | 5.1                    | 5.2                   | 0.547                        | 0.577                       | -6.35                     | -6.28                        | 28.64                  | 1383         | 34.4334647 | -118.6468793 |                                                                                                                           |
| H-1763N       | 8/1/2026 9:56:55 AM   | 34.2       | 30.6       | 4.7       | 30.5           |                         |                         | 1.1     | 6.5          |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              |                                                                                                                           |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init<br>Flow<br>[scfm] | Adj<br>Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                  |
|------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|------------------------|-----------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|-------------------------------------------------------------------------------------------|
| H-1764N    | 8/18/2026 9:04:34 AM  | 51.2       | 39.8       | 0.0       | 9.0            |                         |                         | 1.3     | 0.0          | 121.4                | 121.0               | -4.34                        | -4.36                       | 8.3                    | 5.6                   | 1.476                        | 0.678                       | -20.33                    | -20.12                       | 28.58                  | 1357         | 34.4331663 | -118.6456385 |                                                                                           |
| H-1764S    | 8/5/2026 10:30:38 AM  | 38.3       | 44.1       | 0.0       | 17.6           |                         |                         | 0.9     | 0.0          | 91.0                 | 98.0                | -11.91                       | -12.57                      | 0.0                    | 0.0                   | -0.224                       | -0.372                      | -20.89                    |                              | 28.61                  | 1234         | 34.4321718 | -118.6454377 | No Adjustment Made,                                                                       |
| H-1767N    | 8/26/2026 1:02:20 PM  | 41.6       | 52.6       | 0.0       | 5.8            |                         |                         | 0.8     | 0.0          | 107.6                | 107.8               | -1.73                        | -1.61                       | 18.8                   | 19.3                  | 0.808                        | 0.845                       | -17.27                    | -17.23                       | 28.67                  | 1247         | 34.4326620 | -118.6436057 |                                                                                           |
| H-1769N    | 8/3/2026 8:25:46 AM   | 5.9        | 20.2       | 4.8       | 69.1           |                         |                         | 0.3     | 14.4         | 97.5                 | 97.7                | -0.42                        | -0.40                       | 4.4                    | 4.1                   | 0.051                        | 0.044                       | -11.17                    | -12.07                       | 28.41                  | 1361         | 34.4370188 | -118.6495152 | Valve Adjustment:Barely Open                                                              |
| H-1769N    | 8/17/2026 8:47:36 AM  | 3.2        | 20.1       | 4.8       | 71.9           |                         |                         | 0.2     | 15.0         | 92.6                 | 92.8                | -0.30                        | -0.30                       | 3.4                    | 3.1                   | 0.029                        | 0.024                       | -9.12                     | -9.09                        | 28.6                   | 1360         | 34.4370308 | -118.6495033 | Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered in) |
| H-1770N    | 8/3/2026 8:36:19 AM   | 30.9       | 62.1       | 0.0       | 7.0            |                         |                         | 0.5     | 0.0          | 107.5                | 107.6               | -0.88                        | -0.83                       | 10.3                   | 10.9                  | 2.230                        | 2.478                       | -13.50                    | -12.49                       | 28.41                  | 1363         | 34.4368057 | -118.6500397 | Valve Adjustment:Barely Open                                                              |
| H-1770N    | 8/14/2026 8:15:00 AM  |            |            |           |                |                         | 18000                   |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab; [User entered 1.8%]                                                          |
| H-1770N    | 8/14/2026 8:15:00 AM  |            |            |           |                | 150                     |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AirTech Lab                                                                               |
| H-1770N    | 8/17/2026 8:56:56 AM  | 29.3       | 62.5       | 0.0       | 8.2            |                         |                         | 0.5     | 0.0          | 106.1                | 106.1               | -0.76                        | -0.79                       | 9.5                    | 10.0                  | 1.871                        | 2.081                       | -12.79                    | -12.93                       | 28.62                  | 1361         | 34.4368237 | -118.6500115 | Valve Adjustment:Barely Open                                                              |
| H-1770S    | 8/5/2026 8:05:35 AM   | 18.2       | 33.6       | 1.9       | 46.3           |                         |                         | 0.5     | 24.4         | 101.9                | 102.3               | -1.45                        | -1.25                       | 4.4                    | 2.9                   | 2.184                        | 0.919                       | -14.89                    |                              | 28.56                  | 1316         | 34.4330943 | -118.6501247 |                                                                                           |
| H-1770S    | 8/17/2026 10:21:01 AM | 44.2       | 47.7       | 0.0       | 8.1            |                         |                         | 0.9     | 0.0          | 114.2                | 115.0               | -0.59                        | -0.59                       | 1.5                    | 1.5                   | 0.046                        | 0.046                       | -11.61                    | -11.61                       | 28.7                   | 1304         | 34.4331252 | -118.6501765 | Valve Adjustment:Barely Open                                                              |
| H-1771A    | 8/3/2026 2:30:14 PM   | 28.4       | 22.4       | 5.9       | 43.3           |                         |                         | 1.3     | 7.3          | 106.0                | 106.2               | -0.33                        | -0.21                       | 4.1                    | 2.6                   | 0.039                        | 0.015                       | -3.07                     | -3.19                        | 28.42                  | 1373         | 34.4363525 | -118.6463965 | Valve Adjustment:NSPS/EG CAI,Reconnected this Date,High O2,Decreased Flow/Vacuum          |
| H-1771A    | 8/3/2026 2:35:22 PM   | 30.6       | 23.9       | 5.2       | 40.4           |                         |                         | 1.3     | 7.8          | 105.2                | 105.2               | -0.32                        | -0.30                       | 2.8                    | 2.9                   | 0.166                        | 0.173                       | -3.11                     | -3.09                        | 28.42                  | 1368         | 34.4363490 | -118.6463545 | Valve Adjustment:High O2,Barely Open                                                      |
| H-1771B    | 8/7/2026 2:13:46 PM   | 14.8       | 75.9       | 0.3       | 9.0            |                         |                         | 0.2     | 30.0         | 118.7                | 118.8               | -0.40                        | -0.39                       | 0.6                    | 1.6                   | 0.008                        | 0.054                       | -9.58                     | -9.26                        | 28.52                  | 1394         | 34.4355433 | -118.6466605 | Valve Adjustment:Barely Open                                                              |
| H-1771B    | 8/17/2026 1:26:19 PM  | 17.8       | 73.2       | 0.2       | 8.8            |                         |                         | 0.2     | 44.0         | 111.3                | 111.4               | -0.26                        | -0.24                       | 1.7                    | 1.5                   | 0.057                        | 0.048                       | -6.88                     | -6.82                        | 28.54                  | 1388         | 34.4355112 | -118.6466718 | Valve Adjustment:Barely Open                                                              |
| H-1774N    | 8/3/2026 8:48:53 AM   | 38.2       | 61.5       | 0.0       | 0.3            |                         |                         | 0.6     | 0.0          | 118.3                | 118.3               | -1.18                        | -1.19                       | 12.7                   | 12.7                  | 3.431                        | 3.453                       | -14.65                    | -14.85                       | 28.43                  | 1341         | 34.4367468 | -118.6508032 | Valve Adjustment:Barely Open                                                              |
| H-1774N    | 8/17/2026 9:05:57 AM  | 39.6       | 59.7       | 0.0       | 0.7            |                         |                         | 0.7     | 0.0          | 118.5                | 118.4               | -0.98                        | -0.93                       | 11.5                   | 11.9                  | 2.822                        | 2.993                       | -13.04                    | -12.81                       | 28.64                  | 1341         | 34.4367478 | -118.6508108 | Valve Adjustment:Barely Open                                                              |
| H-1801S    | 8/17/2026 12:59:08 PM | 10.6       | 11.3       | 11.6      | 66.5           |                         |                         | 0.9     | 5.7          | 112.7                | 110.2               | -3.48                        | -0.48                       | 0.8                    | 0.9                   | 0.013                        | 0.018                       | -16.48                    | -16.51                       | 28.66                  | 1346         | 34.4337568 | -118.6441087 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum                                |
| H-1801S    | 8/17/2026 1:01:12 PM  | 15.3       | 18.1       | 4.5       | 62.1           |                         |                         | 0.8     | 13.8         | 126.8                | 113.7               | -0.99                        | -0.98                       | 0.4                    | 0.8                   | 0.004                        | 0.014                       | -16.40                    | -16.84                       | 28.66                  | 1336         | 34.4337815 | -118.6441120 | Valve Adjustment:NSPS/EG CAC                                                              |
| H-1802S    | 8/17/2026 1:14:56 PM  | 52.0       | 38.5       | 0.0       | 9.5            |                         |                         | 1.4     | 0.0          | 111.2                | 113.3               | -0.11                        | -0.10                       | 7.2                    | 6.7                   | 0.067                        | 0.058                       | -17.24                    | -16.63                       | 28.65                  | 1348         | 34.4335658 | -118.6447595 |                                                                                           |
| H-1803N-PL | 8/3/2026 8:42:00 AM   |            |            |           |                |                         | 176400                  |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA; [User entered 17.64%]                                                              |
| H-1803N-PL | 8/3/2026 8:42:00 AM   |            |            |           |                | 1990                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                     |
| H-1803N-PL | 8/3/2026 8:42:09 AM   | 1.3        | 73.4       | 0.0       | 25.3           |                         |                         | 0.0     | 0.0          | 197.0                | 197.8               | -5.76                        | -5.39                       | 64.0                   | 61.6                  | 6.219                        | 5.769                       | 0.34                      | 0.34                         | 28.46                  | 1366         | 34.4370427 | -118.6486152 | Valve Adjustment:No Flow Measurement,High Temp                                            |
| H-1803N-PL | 8/10/2026 8:39:09 AM  | 3.6        | 71.9       | 0.0       | 24.5           |                         |                         | 0.1     | 0.0          | 198.2                | 197.8               | -4.87                        | -4.65                       | 59.0                   | 55.2                  | 5.256                        | 4.593                       | 0.34                      | 0.31                         | 28.58                  | 1361         | 34.4370327 | -118.6486167 | Valve Adjustment:No Flow Measurement,High Temp                                            |
| H-1803N-PL | 8/10/2026 8:50:00 AM  |            |            |           |                | 1960                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                     |
| H-1803N-PL | 8/17/2026 8:13:10 AM  | 12.2       | 77.4       | 0.0       | 10.4           |                         |                         | 0.2     | 0.0          | 197.9                | 197.9               | -7.65                        | -7.60                       | 72.0                   | 72.4                  | 7.882                        | 7.977                       | 0.09                      | 0.04                         | 28.67                  | 1354         | 34.4370116 | -118.6485984 | Valve Adjustment:No Flow Measurement,High Temp                                            |
| H-1803N-PL | 8/17/2026 8:15:00 AM  |            |            |           |                | 1340                    |                         |         |              |                      |                     |                              |                             |                        |                       |                              |                             |                           |                              |                        |              |            |              | AtmAA                                                                                     |
| H-1803N-PL | 8/24/2026 8:27:42 AM  | 13.6       | 72.9       | 0.0       | 13.5           |                         |                         | 0.2     | 0.0          | 198.7                | 198.9               | -5.31                        | -5.56                       | 61.6                   | 62.2                  | 5.729                        | 5.846                       | 0.34                      | 0.34                         | 28.6                   | 1352         | 34.4370261 | -118.6485875 | Valve Adjustment:No Flow Measurement,High Temp                                            |
| H-1803N-PL | 8/31/2026 8:49:03 AM  | 3.9        | 76.8       | 0.0       | 19.3           |                         |                         | 0.1     | 0.0          | 198.2                | 198.3               | -5.07                        | -5.07                       | 59.6                   | 60.1                  | 5.370                        | 5.458                       | 0.31                      | 0.32                         | 28.57                  | 1343         | 34.4370456 | -118.6486043 | Valve Adjustment:No Flow Measurement,High Temp                                            |
| H-1804B    | 8/1/2026 9:18:43 AM   | 47.7       | 50.3       | 0.0       | 2.0            |                         |                         | 0.9     | 0.0          | 115.8                | 115.9               | -12.04                       | -12.49                      | 13.9                   | 20.4                  | 1.275                        | 2.750                       | -13.86                    | -15.12                       | 28.53                  | 1378         | 34.4342633 | -118.6456377 | Valve Adjustment:Audible Flow;Well Comment:RES SEM                                        |
| H-1804N    | 8/18/2026 11:51:34 AM | 53.7       | 40.8       | 0.0       | 5.5            |                         |                         | 1.3     | 0.0          | 105.4                | 105.8               | -1.72                        | -2.22                       | 0.9                    | 1.4                   | 0.016                        | 0.043                       | -4.03                     | -3.92                        | 28.62                  | 1351         | 34.4363430 | -118.6456953 | Valve Adjustment:Increased Flow/Vacuum                                                    |
| H-1804S    | 8/18/2026 9:07:35 AM  | 48.4       | 38.4       | 0.0       | 13.2           |                         |                         | 1.3     | 0.0          | 119.4                | 119.4               | -19.72                       | -18.52                      | 12.1                   | 12.4                  | 0.981                        | 1.030                       | -20.43                    | -18.86                       | 28.58                  | 1370         | 34.4331020 | -118.6456938 | Valve Adjustment:Decreased Flow/Vacuum                                                    |
| H-1805A    | 8/11/2026 1:56:34 PM  | 44.7       | 39.8       | 0.2       | 15.3           |                         |                         | 1.1     | 76.5         | 97.1                 | 96.3                | -3.12                        | -3.00                       | 10.5                   | 2.5                   | 0.139                        | 0.008                       | -19.95                    | -20.23                       | 28.62                  | 1402         | 34.4351430 | -118.6450820 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open                                        |
| H-1805B    | 8/18/2026 8:57:08 AM  | 15.9       | 26.5       | 0.0       | 57.6           |                         |                         | 0.6     | 0.0          | 101.1                | 92.9                | -2.12                        | -1.65                       | 0.6                    | 4.5                   | 0.007                        | 0.411                       | -17.98                    | -17.79                       | 28.58                  | 1378         | 34.4337175 | -118.6451673 | Valve Adjustment:Decreased Flow/Vacuum                                                    |
| H-1805S    | 8/18/2026 9:17:08 AM  | 47.5       | 40.9       | 0.0       | 11.6           |                         |                         | 1.2     | 0.0          | 135.7                | 125.6               | -17.42                       | -10.10                      | 36.4                   | 8.3                   | 3.322                        | 0.165                       | -20.75                    | -20.68                       | 28.62                  | 1335         | 34.4329405 | -118.6451753 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum                              |
| H-1805S    | 8/18/2026 9:17:28 AM  | 47.5       | 41.1       | 0.0       | 11.4           |                         |                         | 1.2     | 0.0          | 127.5                | 127.5               | -9.43                        | -9.43                       | 7.5                    | 8.5                   | 0.136                        | 0.174                       | -20.58                    | -20.96                       | 28.62                  | 1334         | 34.4329287 | -118.6451783 | Valve Adjustment:NSPS/EG CAC                                                              |
| H-1806A    | 8/11/2026 1:31:24 PM  | 53.5       | 37.5       | 0.0       | 9.0            |                         |                         | 1.4     | 0.0          | 117.3                | 117.6               | -1.16                        | -1.44                       | 26.9                   | 26.7                  | 1.682                        | 1.657                       | -16.93                    | -17.64                       | 28.62                  | 1389         | 34.4354745 | -118.6442080 | Valve Adjustment:Audible Flow,Increased Flow/Vacuum                                       |
| H-1806B    | 8/27/2026 11:27:18 AM | 24.8       | 33.0       | 0.0       | 42.2           |                         |                         | 0.8     | 0.0          | 115.7                | 114.5               | -2.00                        | -1.99                       | 4.3                    | 2.0                   | 0.384                        | 0.085                       | -15.46                    | -15.48                       | 28.64                  | 1364         | 34.4391115 | -118.6444380 | Valve Adjustment:Audible Flow,Decreased Flow/Vacuum                                       |
| H-1806N    | 8/18/2026 11:29:19 AM | 41.4       | 49.9       | 0.0       | 8.7            |                         |                         | 0.8     | 0.0          | 130.5                | 129.4               | -1.58                        | -1.19                       | 6.0                    | 6.4                   | 0.047                        | 0.054                       | -11.68                    | -11.33                       | 28.62                  | 1340         | 34.4363550 | -118.6443053 | Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum                              |
| H-1806N    | 8/18/2026 11:29:36 AM | 41.4       | 49.9       | 0.0       | 8.7            |                         |                         | 0.8     | 0.0          | 129.1                | 129.1               | -1.07                        | -1.08                       | 2.3                    | 1.5                   | 0.007                        | 0.003                       | -11.34                    | -11.38                       | 28.62                  | 1330         | 34.4363620 | -118.6443078 | Valve Adjustment:NSPS/EG CAC                                                              |
| H-1806S    | 8/18/2026 10:08:10 AM | 25.8       | 64.0       | 0.0       | 10.2           |                         |                         | 0.4     | 0.0          | 128.2                | 128.0               | -0.60                        | -0.41                       | 13.8                   | 12.8                  | 0.445                        | 0.387                       | -17.81                    | -17.68                       | 28.69                  | 1267         | 34.4328682 | -118.6444537 | Valve Adjustment:Decreased Flow/Vacuum                                                    |
| H-1807A    | 8/11/2026 1:19:23 PM  | 60.3       | 37.0       | 0.0       | 2.7            |                         |                         | 1.6     | 0.0          | 117.4                | 117.8               | -12.46                       | -12.71                      | 36.9                   | 41.4                  | 1.820                        | 2.302                       | -15.25                    | -16.46                       | 28.66                  | 1363         | 34.4353608 | -118.6435787 | Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Surging Liquid in Header              |
| H-1807N    | 8/18/2026 11:17:51 AM | 21.0       | 21.3       | 6.5       | 51.2           |                         |                         | 1.0     | 7.9          | 109.6                | 106.3               | -4.71                        | -3.80                       | 25.9                   | 7.9                   | 4.272                        | 0.389                       | -9.58                     | -10.00                       | 28.63                  | 1340         | 34.4364463 | -118.6435342 | Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum                                |
| H-1807N    | 8/18/2026 11:21:19 AM | 23.4       | 24.0       | 5.7       | 46.9           |                         |                         | 1.0     | 8.2          | 111.7                | 105.2               | -3.18                        | -3.15                       | 4.9                    | 4.9                   | 0.151                        | 0.152                       | -9.47                     | -9.45                        | 28.63                  | 1274         | 34.4364143 | -118.6435662 | Valve Adjustment:Audible Flow,Decreased Flow/Vacuum                                       |
| H-1807S    | 8/17/2026 12:46:14 PM | 42.1       | 35.2       | 0.0       | 22.7           |                         |                         | 1.2     | 0.0          | 100.0                | 100.5               | -10.77                       | -8.42                       | 2.2                    | 5.7                   | 0.006                        | 0.041                       | -16.47                    | -16.46                       | 28.69                  | 1289         | 34.4337978 | -118.6435057 | Valve Adjustment:Audible Flow,Increased Flow/Vacuum                                       |
| H-1952S    | 8/6/2026 3:05:38 PM   | 53.7       | 46.0       | 0.0       | 0.3            |                         |                         | 1.2     | 0.0          | 119.7                | 119.7               | -0.83                        | -0.84                       | 9.4                    | 9.3                   | 1.875                        | 1.833                       | -13.45                    | -13.47                       | 28.49                  | 1388         | 34.4338167 | -118.6476047 | Valve Adjustment:Barely Open                                                              |
| H-1952S    | 8/7/2026 8:18:01 AM   | 52.6       | 43.4       | 0.0       | 4.0            |                         |                         | 1.2     | 0.0          | 115.8                | 116.1               | -1.67                        | -2.72                       | 10.4                   | 14.5                  | 2.293                        | 4.504                       | -17.01                    | -16.67                       | 28.6                   | 1381         | 34.4338227 | -118.6476583 | Valve Adjustment:Increased Flow/Vacuum,Barely Open                                        |
| H-1952S    | 8/18/2026 1:54:48 PM  | 54.0       | 43.8       | 0.1       | 2.1            |                         |                         | 1.2     | 21.0         | 117.8                | 118.3               | -1.73                        | -2.48                       | 12.9                   | 16.1                  | 3.579                        | 5.580                       | -12.64                    | -12.62                       | 28.52                  | 1365         | 34.4338152 | -118.6476265 | Valve Adjustment:Increased Flow/Vacuum                                                    |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init Flow<br>[scfm] | Adj Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>[psi] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                   |
|------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|---------------------|--------------------|------------------------------|-----------------------------|--------------------------|------------------------------|------------------------|--------------|------------|--------------|------------------------------------------------------------------------------------------------------------|
| H-1955C    | 8/11/2026 1:51:47 PM  | 30.8       | 28.1       | 2.4       | 38.7           |                         |                         | 1.1     | 16.1         | 94.9                 | 95.1                | -1.01                        | -0.86                       | 9.2                 | 7.0                | 1.733                        | 0.983                       | -20.38                   | -20.50                       | 28.61                  | 1401         | 34.4350392 | -118.6454005 | Valve Adjustment:Decreased Flow/Vacuum                                                                     |
| H-1955N    | 8/18/2026 11:54:01 AM | 32.6       | 33.7       | 0.3       | 33.4           |                         |                         | 1.0     | 111.3        | 99.7                 | 99.9                | -1.77                        | -1.73                       | 5.5                 | 4.4                | 0.184                        | 0.120                       | -3.91                    | -3.72                        | 28.65                  | 1345         | 34.4364568 | -118.6455260 |                                                                                                            |
| H-1956B    | 8/1/2026 9:27:37 AM   | 25.5       | 65.6       | 0.0       | 8.9            |                         |                         | 0.4     | 0.0          | 124.1                | 123.8               | -2.43                        | -2.26                       | 4.0                 | 6.6                | 0.038                        | 0.102                       | -18.85                   | -18.32                       | 28.55                  | 1382         | 34.4342893 | -118.6447747 | Valve Adjustment:Decreased Flow/Vacuum                                                                     |
| H-1956N    | 8/18/2026 11:35:03 AM | 41.9       | 39.7       | 0.0       | 18.4           |                         |                         | 1.1     | 0.0          | 115.1                | 115.2               | -3.34                        | -3.32                       | 21.9                | 21.7               | 3.069                        | 2.998                       | -6.08                    | -5.92                        | 28.65                  | 1342         | 34.4364590 | -118.6448932 |                                                                                                            |
| H-1956S    | 8/17/2026 1:10:15 PM  | 54.9       | 40.6       | 0.0       | 4.5            |                         |                         | 1.4     | 0.0          | 113.8                | 114.3               | -7.15                        | -7.21                       | 0.4                 | 0.4                | 0.016                        | 0.014                       | -7.41                    | -7.35                        | 28.66                  | 1321         | 34.4331878 | -118.6449053 |                                                                                                            |
| H-1957B    | 8/17/2026 12:30:15 PM | 43.7       | 35.8       | 0.0       | 20.5           |                         |                         | 1.2     | 0.0          | 114.4                | 113.3               | -1.37                        | -1.13                       | 7.3                 | 10.4               | 0.334                        | 0.678                       | -16.13                   | -16.19                       | 28.62                  | 1378         | 34.4345463 | -118.6441333 | Valve Adjustment:Decreased Flow/Vacuum                                                                     |
| H-1957N    | 8/18/2026 11:26:07 AM | 45.2       | 41.9       | 0.0       | 12.9           |                         |                         | 1.1     | 0.0          | 123.3                | 123.1               | -2.48                        | -2.28                       | 6.6                 | 4.7                | 0.280                        | 0.141                       | -10.58                   | -10.84                       | 28.63                  | 1340         | 34.4364445 | -118.6442128 | Valve Adjustment:Decreased Flow/Vacuum                                                                     |
| H-1957S    | 8/17/2026 12:54:48 PM | 15.4       | 76.2       | 0.4       | 8.0            |                         |                         | 0.2     | 20.0         | 118.4                | 118.8               | -2.04                        | -1.50                       | 3.2                 | 3.2                | 0.211                        | 0.213                       | -16.38                   | -17.64                       | 28.66                  | 1338         | 34.4337657 | -118.6441318 | Valve Adjustment:Decreased Flow/Vacuum                                                                     |
| H-1958C    | 8/11/2026 1:16:54 PM  | 40.2       | 31.8       | 0.0       | 28.0           |                         |                         | 1.3     | 0.0          | 125.9                | 125.9               | -4.01                        | -3.73                       | 19.1                | 13.3               | 2.386                        | 1.152                       | -16.66                   | -17.64                       | 28.66                  | 1342         | 34.4353735 | -118.6434458 | Valve Adjustment:Audible Flow,Decreased Flow/Vacuum                                                        |
| H-1958C    | 8/31/2026 2:07:51 PM  | 55.1       | 39.9       | 0.0       | 5.1            |                         |                         | 1.4     | 0.0          | 112.5                | 117.3               | -0.13                        | -0.61                       | 1.2                 | 9.1                | 0.009                        | 0.527                       | -15.37                   | -15.10                       | 28.57                  | 1330         | 34.4353532 | -118.6434727 | Valve Adjustment:Reconnected this Date,Increased Flow/Vacuum                                               |
| H-1958C    | 8/31/2026 2:09:24 PM  | 53.9       | 41.5       | 0.0       | 4.7            |                         |                         | 1.3     | 0.0          | 118.1                | 118.1               | -0.82                        | -0.81                       | 9.0                 | 9.1                | 0.518                        | 0.522                       | -15.03                   | -15.04                       | 28.57                  | 1335         | 34.4353700 | -118.6434603 |                                                                                                            |
| H-1958N    | 8/18/2026 11:12:53 AM | 31.5       | 32.0       | 0.0       | 36.5           |                         |                         | 1.0     | 0.0          | 106.3                | 101.3               | -2.77                        | -1.19                       | 47.5                | 35.8               | 2.889                        | 1.620                       | -10.02                   | -10.13                       | 28.65                  | 1343         | 34.4364460 | -118.6435330 | Valve Adjustment:Decreased Flow/Vacuum                                                                     |
| H-1958S    | 8/17/2026 12:42:34 PM | 4.5        | 4.4        | 16.8      | 74.3           |                         |                         | 1.0     | 4.4          | 103.8                | 104.5               | -0.51                        | -0.55                       | 2.2                 | 2.1                | 0.029                        | 0.027                       | -16.39                   | -16.42                       | 28.68                  | 1317         | 34.4339917 | -118.6433530 | Valve Adjustment:NSPS/EG CAI,High O2                                                                       |
| H-1958S    | 8/17/2026 12:43:15 PM | 4.7        | 4.8        | 16.7      | 73.8           |                         |                         | 1.0     | 4.4          | 104.8                | 104.8               | -0.55                        | -0.59                       | 2.0                 | 2.0                | 0.025                        | 0.026                       | -16.59                   | -16.46                       | 28.67                  | 1316         | 34.4339985 | -118.6433637 | Repairs:Valve                                                                                              |
| H-1962N    | 8/3/2026 8:39:24 AM   | 0.1        | 3.6        | 20.0      | 76.3           |                         |                         | 0.0     | 3.8          | 83.4                 | 84.2                | -0.76                        | -0.76                       |                     |                    | 0.000                        | 0.000                       | -12.94                   | -13.08                       | 28.41                  | 1364         | 34.4366623 | -118.6501563 | Valve Adjustment:High O2,Barely Open                                                                       |
| H-1962N    | 8/17/2026 8:59:28 AM  | 0.3        | 6.7        | 19.6      | 73.4           |                         |                         | 0.0     | 3.7          | 80.1                 | 80.4                | -1.02                        | -1.02                       |                     |                    | 0.000                        | 0.000                       | -12.82                   | -12.79                       | 28.61                  | 1370         | 34.4366692 | -118.6501437 | Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)          |
| H-1963N    | 8/3/2026 8:23:35 AM   | 21.1       | 61.5       | 0.8       | 16.6           |                         |                         | 0.3     | 20.8         | 141.2                | 141.1               | -0.78                        | -0.76                       | 7.0                 | 6.8                | 0.139                        | 0.130                       | -12.30                   | -11.49                       | 28.38                  | 1375         | 34.4369382 | -118.6495450 | Valve Adjustment:High Temp,Barely Open                                                                     |
| H-1963N    | 8/17/2026 8:43:30 AM  | 18.6       | 64.5       | 0.5       | 16.4           |                         |                         | 0.3     | 32.8         | 144.5                | 144.5               | -0.56                        | -0.56                       | 5.2                 | 5.6                | 0.076                        | 0.087                       | -8.92                    | -8.52                        | 28.6                   | 1357         | 34.4369432 | -118.6495148 | Valve Adjustment:High Temp,Barely Open                                                                     |
| H-1966N    | 8/3/2026 8:55:17 AM   | 38.4       | 42.5       | 0.0       | 19.1           |                         |                         | 0.9     | 0.0          | 110.6                | 110.7               | -0.52                        | -0.50                       | 5.4                 | 5.4                | 3.135                        | 3.124                       | -8.15                    | -8.18                        | 28.41                  | 1348         | 34.4365512 | -118.6507770 | Valve Adjustment:Barely Open                                                                               |
| H-1966N    | 8/17/2026 9:10:54 AM  | 39.5       | 43.8       | 0.0       | 16.7           |                         |                         | 0.9     | 0.0          | 109.3                | 109.3               | -0.39                        | -0.39                       | 4.7                 | 4.7                | 2.349                        | 2.359                       | -6.23                    | -6.27                        | 28.64                  | 1343         | 34.4365728 | -118.6507772 | Valve Adjustment:Barely Open                                                                               |
| H-1967E    | 8/18/2026 2:13:45 PM  | 37.7       | 30.2       | 4.0       | 28.1           |                         |                         | 1.2     | 7.0          | 108.7                | 108.6               | -15.51                       | -14.81                      | 1.1                 | 2.8                | 0.002                        | 0.011                       | -17.07                   | -16.97                       | 28.81                  | 1142         | 34.4302037 | -118.6458230 | Valve Adjustment:Decreased Flow/Vacuum                                                                     |
| H-1967W    | 8/27/2026 2:08:41 PM  | 55.9       | 39.1       | 0.0       | 5.0            |                         |                         | 1.4     | 0.0          | 99.8                 | 100.1               | -2.14                        | -2.19                       | 57.9                | 58.9               | 4.256                        | 4.409                       | -7.11                    | -7.09                        | 28.68                  | 1189         | 34.4299273 | -118.6508243 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)                              |
| H-2050E    | 8/28/2026 10:26:38 AM | 55.5       | 41.0       | 0.0       | 3.5            |                         |                         | 1.4     | 0.0          | 105.4                | 106.8               | -4.43                        | -4.41                       | 3.1                 | 3.2                | 0.201                        | 0.210                       | -3.65                    | -3.63                        | 28.78                  | 1096         | 34.4291242 | -118.6474532 | Valve Adjustment:Valve 100% Open                                                                           |
| H-2050W    | 8/9/2026 8:59:53 AM   | 28.1       | 33.7       | 0.0       | 38.2           |                         |                         | 0.8     | 0.0          | 105.3                | 105.4               | -1.46                        | -1.49                       | 3.4                 | 3.9                | 0.245                        | 0.311                       | -7.03                    | -8.05                        | 28.69                  | 1186         | 34.4291037 | -118.6490842 | Valve Adjustment:Barely Open                                                                               |
| H-2050W    | 8/9/2026 9:02:18 AM   | 29.9       | 35.1       | 0.0       | 35.1           |                         |                         | 0.9     | 0.0          | 104.0                | 104.0               | -1.40                        | -1.40                       | 4.6                 | 4.5                | 2.201                        | 2.168                       | -8.36                    | -8.39                        | 28.7                   | 1188         | 34.4291217 | -118.6490895 | Valve Adjustment:Orifice Plate Changed (See OP Log)                                                        |
| H-2051W    | 8/27/2026 2:06:01 PM  | 51.6       | 37.0       | 0.3       | 11.1           |                         |                         | 1.4     | 37.0         | 100.2                | 101.2               | -7.23                        | -6.41                       | 9.9                 | 8.2                | 0.126                        | 0.086                       | -8.36                    | -6.48                        | 28.68                  | 1189         | 34.4299280 | -118.6508197 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)                              |
| H-2053E    | 8/18/2026 2:22:29 PM  | 36.6       | 36.3       | 0.0       | 27.1           |                         |                         | 1.0     | 0.0          | 121.4                | 121.4               | -2.44                        | -2.43                       | 19.9                | 18.5               | 0.516                        | 0.444                       | -17.09                   | -16.55                       | 28.81                  | 1143         | 34.4302103 | -118.6458183 |                                                                                                            |
| H-2055E    | 8/5/2026 11:06:36 AM  | 0.8        | 4.0        | 19.6      | 75.6           |                         |                         | 0.2     | 3.9          | 93.5                 | 93.8                | -0.24                        | -0.09                       | 0.0                 | 0.0                | -0.701                       | -0.700                      | -0.09                    |                              | 28.64                  | 1227         | 34.4317637 | -118.6466790 | NSPS/EG CAI,High O2                                                                                        |
| H-2055E    | 8/5/2026 11:09:52 AM  | 22.2       | 23.0       | 3.5       | 51.3           |                         |                         | 1.0     | 14.7         | 105.4                | 105.1               | -0.08                        | -0.15                       | 0.0                 | 0.0                | -0.125                       | -0.123                      | -19.55                   |                              | 28.64                  | 1253         | 34.4317725 | -118.6466302 | NSPS/EG CAC,Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less                                            |
| H-2055E    | 8/27/2026 9:45:35 AM  | 43.5       | 40.5       | 0.6       | 15.4           |                         |                         | 1.1     | 25.7         | 89.0                 | 89.1                | -0.41                        | -0.40                       | 2.8                 | 2.5                | 0.048                        | 0.036                       | -15.30                   | -15.35                       | 28.6                   | 1284         | 34.4317683 | -118.6466133 | Valve Adjustment:Barely Open                                                                               |
| H-2056B    | 8/26/2026 9:06:42 AM  | 54.2       | 41.1       | 0.0       | 4.8            |                         |                         | 1.3     | 0.0          | 100.5                | 103.3               | 0.29                         | -0.02                       | 0.5                 | 3.6                | 0.026                        | 1.386                       | -3.07                    | -2.62                        | 28.76                  | 1151         | 34.4297658 | -118.6474637 | Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum                      |
| H-2056B    | 8/26/2026 9:10:11 AM  | 53.0       | 42.6       | 0.0       | 4.4            |                         |                         | 1.2     | 0.0          | 104.7                | 105.3               | -0.36                        | -0.41                       | 4.9                 | 5.7                | 0.489                        | 0.676                       | -2.41                    | -2.76                        | 28.76                  | 1153         | 34.4297292 | -118.6474528 | Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum                                  |
| H-2056B    | 8/26/2026 9:11:36 AM  | 52.9       | 42.8       | 0.0       | 4.3            |                         |                         | 1.2     | 0.0          | 106.3                | 106.4               | -0.47                        | -0.52                       | 5.5                 | 5.6                | 0.615                        | 0.652                       | -2.53                    | -2.62                        | 28.76                  | 1151         | 34.4297257 | -118.6474440 |                                                                                                            |
| H-2056B    | 8/26/2026 3:29:14 PM  | 53.3       | 29.4       | 0.0       | 17.3           |                         |                         | 1.8     | 0.0          | 115.2                | 115.6               | -0.46                        | -0.48                       | 5.0                 | 5.2                | 0.522                        | 0.562                       | -2.60                    | -2.80                        | 28.74                  | 1149         | 34.4297281 | -118.6474747 |                                                                                                            |
| H-2056W    | 8/27/2026 2:03:39 PM  | 55.3       | 40.3       | 0.0       | 4.4            |                         |                         | 1.4     | 0.0          | 106.5                | 106.4               | -2.43                        | -2.26                       | 59.2                | 59.5               | 4.503                        | 4.550                       | -6.51                    | -6.58                        | 28.68                  | 1187         | 34.4299205 | -118.6508320 | Valve Adjustment:Decreased Flow/Vacuum                                                                     |
| H-2057E    | 8/6/2026 12:50:09 PM  | 65.6       | 34.4       | 0.0       | 0.0            |                         |                         | 1.9     | 0.0          | 117.5                | 117.5               | -9.91                        | -10.41                      | 8.2                 | 7.7                | 1.447                        | 1.281                       | -14.48                   | -14.97                       | 28.89                  | 1155         | 34.4301998 | -118.6458443 | Valve Adjustment:increased Flow/Vacuum                                                                     |
| H-2057E    | 8/18/2026 2:18:11 PM  | 51.7       | 40.6       | 0.3       | 7.4            |                         |                         | 1.3     | 24.7         | 127.8                | 127.8               | -12.57                       | -12.48                      | 36.8                | 36.6               | 1.839                        | 1.817                       | -16.99                   | -16.78                       | 28.82                  | 1137         | 34.4302038 | -118.6458227 |                                                                                                            |
| H-2058E    | 8/12/2026 1:57:42 PM  | 46.3       | 37.3       | 0.0       | 16.4           |                         |                         | 1.2     | 0.0          | 113.0                | 113.1               | -7.70                        | -7.58                       | 54.9                | 53.7               | 3.961                        | 3.784                       | -12.37                   | -12.37                       | 28.71                  | 1138         | 34.4300698 | -118.6464092 | Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)        |
| H-2058W    | 8/27/2026 2:01:18 PM  | 51.2       | 40.1       | 0.0       | 8.7            |                         |                         | 1.3     | 0.0          | 102.5                | 103.1               | -1.63                        | -1.58                       | 8.9                 | 10.4               | 0.100                        | 0.135                       | -4.97                    | -5.63                        | 28.67                  | 1188         | 34.4299228 | -118.6508555 | Valve Adjustment:Barely Open                                                                               |
| H-2059E    | 8/26/2026 8:51:57 AM  | 55.6       | 41.1       | 0.0       | 3.3            |                         |                         | 1.4     | 0.0          | 120.5                | 120.9               | -8.74                        | -8.75                       | 2.6                 | 2.7                | 0.149                        | 0.163                       | -8.88                    | -8.91                        | 28.72                  | 1160         | 34.4306903 | -118.6462922 | Valve Adjustment:Valve 100% Open,Plugged/Pinched Suspected                                                 |
| H-2059E    | 8/26/2026 1:40:51 PM  | 56.2       | 41.6       | 0.0       | 2.2            |                         |                         | 1.4     | 0.0          | 122.9                | 122.7               | -8.74                        | -8.18                       | 5.9                 | 9.0                | 0.230                        | 0.531                       | 0.25                     | 0.90                         | 28.71                  | 1183         | 34.4306622 | -118.6462778 |                                                                                                            |
| H-2059E    | 8/26/2026 1:49:04 PM  | 55.0       | 38.6       | 0.0       | 6.4            |                         |                         | 1.4     | 0.0          | 122.5                | 122.9               | -8.62                        | -8.53                       | 5.0                 | 8.9                | 0.161                        | 0.519                       | -8.54                    | -8.80                        | 28.74                  | 1181         | 34.4306632 | -118.6462831 |                                                                                                            |
| H-2059W    | 8/27/2026 1:47:41 PM  | 48.0       | 43.5       | 0.8       | 7.7            |                         |                         | 1.1     | 9.6          | 124.9                | 124.8               | -2.92                        | -3.03                       | 39.1                | 41.0               | 3.617                        | 3.980                       | -7.39                    | -7.49                        | 28.64                  | 1233         | 34.4310653 | -118.6502142 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)                              |
| H-2161E    | 8/18/2026 10:37:53 AM | 48.0       | 41.9       | 0.0       | 10.1           |                         |                         | 1.1     | 0.0          | 125.9                | 126.0               | -5.91                        | -5.72                       | 49.6                | 51.9               | 3.285                        | 3.590                       | -17.30                   | -16.93                       | 28.77                  | 1197         | 34.4308547 | -118.6464687 |                                                                                                            |
| H-2161W    | 8/27/2026 1:53:49 PM  | 44.1       | 37.8       | 0.0       | 18.1           |                         |                         | 1.2     | 0.0          | 107.0                | 107.2               | -5.42                        | -5.16                       | 51.6                | 49.7               | 3.446                        | 3.201                       | -9.28                    | -9.03                        | 28.64                  | 1239         | 34.4309443 | -118.6502270 | Valve Adjustment:Decreased Flow/Vacuum                                                                     |
| H-2163C    | 8/11/2026 10:11:51 AM | 45.7       | 39.3       | 0.0       | 15.1           |                         |                         | 1.2     | 0.0          | 101.8                | 94.8                | -1.34                        | -1.32                       | 1.7                 | 2.2                | 0.295                        | 0.525                       | -18.55                   | -18.50                       | 28.68                  | 1325         | 34.4310937 | -118.6486682 | Valve Comment:Changed OP from 0.50 to 0.40,Valve Adjustment:Orifice Plate Changed (See OP Log),Barely Open |
| H-2163C    | 8/11/2026 10:14:26 AM | 44.1       | 38.7       | 0.2       | 16.9           |                         |                         | 1.1     | 73.4         | 100.4                | 98.8                | -1.37                        | -1.36                       | 0.9                 | 0.8                | 0.220                        | 0.156                       | -18.42                   | -18.50                       | 28.68                  | 1320         | 34.4310980 | -118.6       |                                                                                                            |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init Flow<br>[scfm] | Adj Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>[psi] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                             |                                   |
|------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|---------------------|--------------------|------------------------------|-----------------------------|--------------------------|------------------------------|------------------------|--------------|------------|--------------|------------------------------------------------------------------------------------------------------|-----------------------------------|
| H-2163W    | 8/27/2026 1:28:25 PM  | 1.4        | 1.8        | 19.1      | 77.7           |                         |                         | 0.8     | 4.1          | 99.8                 | 100.0               | -0.03                        | -0.01                       | 1.4                 | 1.2                | 0.011                        | 0.009                       | -5.31                    | -5.04                        | 28.61                  | 1267         | 34.4311592 | -118.6498543 | Valve Adjustment: NSPS/EG CAI, High O2, Barely Open                                                  |                                   |
| H-2163W    | 8/27/2026 1:29:13 PM  | 1.6        | 1.4        | 19.1      | 77.9           |                         |                         | 1.1     | 4.1          | 101.0                | 101.2               | -0.05                        | -0.04                       | 2.0                 | 1.2                | 0.024                        | 0.009                       | -9.53                    | -10.44                       | 28.62                  | 1268         | 34.4311578 | -118.6498510 | Valve Adjustment: High O2, Barely Open                                                               |                                   |
| H-2165E    | 8/13/2026 2:03:30 PM  | 46.6       | 52.3       | 0.0       | 1.1            |                         |                         | 0.9     | 0.0          | 120.4                | 120.4               | -1.24                        | -1.21                       | 9.8                 | 9.7                | 0.618                        | 0.595                       | -11.72                   | -10.70                       | 28.63                  | 1245         | 34.4319082 | -118.6451345 |                                                                                                      |                                   |
| H-2165E    | 8/18/2026 9:50:08 AM  | 45.7       | 46.6       | 0.0       | 7.7            |                         |                         | 1.0     | 0.0          | 120.0                | 120.0               | -1.08                        | -0.87                       | 10.6                | 15.5               | 0.713                        | 1.534                       | -8.80                    | -8.59                        | 28.73                  | 1250         | 34.4319072 | -118.6451150 | Valve Adjustment: Decreased Flow/Vacuum                                                              |                                   |
| H-2165W    | 8/5/2026 9:14:44 AM   | 11.0       | 88.4       | 0.0       | 0.6            |                         |                         | 0.1     | 0.0          |                      |                     |                              |                             |                     |                    |                              |                             |                          |                              | 28.63                  | 1280         | 34.4321205 | -118.6503952 | .                                                                                                    |                                   |
| H-2165W    | 8/5/2026 9:14:45 AM   | 11.0       | 88.4       | 0.0       | 0.6            |                         |                         | 0.1     | 0.0          |                      |                     |                              |                             |                     |                    |                              |                             |                          |                              | 28.63                  | 1280         | 34.4321205 | -118.6503952 | .                                                                                                    |                                   |
| H-2165W    | 8/5/2026 9:16:03 AM   | 11.1       | 88.9       | 0.0       | 0.0            |                         |                         | 0.1     | 0.0          | 143.6                | 142.2               | -0.91                        | -0.58                       | 0.9                 | 0.8                | 0.122                        | 0.110                       | -17.07                   |                              | 28.63                  | 1257         | 34.4321655 | -118.6504580 | NSPS/EG CAI, High Temp                                                                               |                                   |
| H-2165W    | 8/5/2026 9:17:25 AM   | 10.9       | 88.4       | 0.0       | 0.7            |                         |                         | 0.1     | 0.0          | 143.3                | 143.3               | -0.55                        | -0.55                       | 0.6                 | 0.6                | 0.050                        | 0.055                       | -16.96                   |                              | 28.63                  | 1247         | 34.4321932 | -118.6504897 | NSPS/EG CAI, High Temp                                                                               |                                   |
| H-2165W    | 8/13/2026 9:00:00 AM  |            |            |           |                |                         | 67000                   |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                          |                              |                        |              |            |              |                                                                                                      | AirTech Lab; [User entered 6.7%]  |
| H-2165W    | 8/13/2026 9:00:00 AM  |            |            |           |                | 870                     |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                          |                              |                        |              |            |              |                                                                                                      | AirTech Lab                       |
| H-2165W    | 8/25/2026 1:49:37 PM  | 14.6       | 82.2       | 0.2       | 3.0            |                         |                         | 0.2     | 15.0         | 146.4                | 143.2               | 0.32                         | -0.07                       | 2.0                 | 20.7               | 0.028                        | 2.850                       | -9.79                    | -9.92                        | 28.63                  | 1263         | 34.4321505 | -118.6504373 | Valve Adjustment: NSPS/EG CAI, High Temp, Positive Static Press., Increased Flow/Vacuum, Barely Open |                                   |
| H-2165W    | 8/25/2026 1:50:21 PM  | 19.2       | 76.8       | 0.2       | 3.8            |                         |                         | 0.3     | 19.0         | 141.8                | 142.6               | -0.16                        | -0.18                       | 20.7                | 20.8               | 2.839                        | 2.872                       | -9.82                    | -9.54                        | 28.62                  | 1267         | 34.4321430 | -118.6504402 | Valve Adjustment: High Temp, Barely Open                                                             |                                   |
| H-2166E    | 8/11/2026 1:41:27 PM  | 44.7       | 36.5       | 0.0       | 18.8           |                         |                         | 1.2     | 0.0          | 117.1                | 117.1               | -0.77                        | -0.76                       | 10.2                | 10.0               | 0.666                        | 0.628                       | -9.95                    | -9.00                        | 28.63                  | 1374         | 34.4356507 | -118.6438572 |                                                                                                      |                                   |
| H-2168C    | 8/1/2026 9:30:20 AM   | 43.4       | 33.4       | 4.6       | 18.6           |                         |                         | 1.3     | 4.0          | 91.5                 | 92.8                | -15.35                       | -12.19                      | 18.2                | 18.4               | 0.428                        | 0.435                       | -18.97                   | -17.85                       | 28.53                  | 1381         | 34.4344238 | -118.6448017 | Valve Adjustment: Decreased Flow/Vacuum                                                              |                                   |
| H-2168E    | 8/17/2026 12:32:36 PM | 24.4       | 28.6       | 0.0       | 47.0           |                         |                         | 0.9     | 0.0          | 120.5                | 119.9               | -0.77                        | -0.67                       | 2.5                 | 1.8                | 0.040                        | 0.021                       | -16.08                   | -16.17                       | 28.62                  | 1366         | 34.4345233 | -118.6439402 | Valve Adjustment: Decreased Flow/Vacuum                                                              |                                   |
| H-2169C    | 8/1/2026 9:22:25 AM   | 35.6       | 34.7       | 1.1       | 28.6           |                         |                         | 1.0     | 26.0         | 117.4                | 117.5               | -12.89                       | -11.14                      | 55.3                | 49.4               | 4.129                        | 3.283                       | -18.60                   | -18.95                       | 28.54                  | 1381         | 34.4304582 | -118.6450448 | Valve Adjustment: Decreased Flow/Vacuum                                                              |                                   |
| H-2169E    | 8/17/2026 12:21:46 PM | 50.6       | 38.0       | 0.0       | 11.4           |                         |                         | 1.3     | 0.0          | 115.9                | 116.1               | -0.37                        | -0.38                       | 26.4                | 25.6               | 0.898                        | 0.845                       | -15.29                   | -15.25                       | 28.62                  | 1382         | 34.4342340 | -118.6442328 |                                                                                                      |                                   |
| H-2170N    | 8/25/2026 12:17:42 PM | 44.0       | 32.9       | 0.0       | 23.1           |                         |                         | 1.3     | 0.0          | 121.3                | 121.6               | -3.73                        | -3.15                       | 35.4                | 27.6               | 8.168                        | 4.910                       | -15.10                   | -15.53                       | 28.69                  | 1292         | 34.4358011 | -118.6414282 |                                                                                                      |                                   |
| H-2170S    | 8/3/2026 1:42:56 PM   | 50.3       | 41.4       | 0.0       | 8.3            |                         |                         | 1.2     | 0.0          | 110.2                | 110.9               | -0.82                        | -0.82                       | 2.1                 | 1.4                | 0.028                        | 0.013                       | -19.00                   | -18.26                       | 28.56                  | 1225         | 34.435807  | -118.6414885 | Valve Adjustment: Barely Open, Plugged/Pinched Suspected                                             |                                   |
| H-2171A    | 8/25/2026 1:22:00 PM  | 45.0       | 31.9       | 0.0       | 23.1           |                         |                         | 1.4     | 0.0          | 108.0                | 108.7               | -3.92                        | -3.54                       | 5.0                 | 4.7                | 2.746                        | 2.336                       | -0.86                    | -0.78                        | 28.7                   | 1269         | 34.4374044 | -118.6425365 |                                                                                                      |                                   |
| H-2171B    | 8/26/2026 11:22:10 AM | 44.8       | 35.2       | 0.0       | 20.0           |                         |                         | 1.3     | 0.0          | 120.7                | 120.8               | -2.55                        | -2.57                       | 8.8                 | 9.1                | 0.500                        | 0.534                       | -11.37                   | -10.63                       | 28.63                  | 1272         | 34.4365058 | -118.6416608 |                                                                                                      |                                   |
| H-2171N    | 8/1/2026 8:36:06 AM   | 21.0       | 30.9       | 0.0       | 48.1           |                         |                         | 0.7     | 0.0          | 116.8                | 117.1               | -0.84                        | -0.88                       | 7.9                 | 7.7                | 0.399                        | 0.377                       | -15.94                   | -15.93                       | 28.66                  | 1270         | 34.4379702 | -118.6432923 | Valve Adjustment: Audible Flow                                                                       |                                   |
| H-2171S    | 8/25/2026 12:13:12 PM | 44.7       | 34.1       | 0.0       | 21.2           |                         |                         | 1.3     | 0.0          | 124.5                | 124.6               | -4.48                        | -4.47                       | 46.7                | 46.6               | 14.468                       | 14.369                      | -15.06                   | -14.99                       | 28.7                   | 1292         | 34.4357943 | -118.6414472 |                                                                                                      |                                   |
| H-2272W    | 8/3/2026 9:40:07 AM   | 28.8       | 39.5       | 0.0       | 31.7           |                         |                         | 0.7     | 0.0          | 127.1                | 127.2               | -0.59                        | -0.58                       | 5.3                 | 5.2                | 0.593                        | 0.580                       | -15.37                   | -15.58                       | 28.53                  | 1279         | 34.4317273 | -118.6497767 | Valve Adjustment: Barely Open                                                                        |                                   |
| H-2272W    | 8/17/2026 8:58:10 AM  | 23.2       | 31.5       | 0.0       | 45.2           |                         |                         | 0.7     | 0.0          | 123.8                | 123.6               | -1.18                        | -1.19                       | 2.1                 | 1.8                | 0.096                        | 0.067                       | -15.67                   | -16.63                       | 28.72                  | 1284         | 34.4317227 | -118.6497712 |                                                                                                      |                                   |
| H-2272W    | 8/17/2026 9:03:29 AM  | 22.7       | 32.5       | 0.0       | 44.8           |                         |                         | 0.7     | 0.0          | 121.9                | 121.7               | -1.17                        | -1.17                       | 4.9                 | 5.4                | 2.639                        | 3.160                       | -13.87                   | -17.16                       | 28.7                   | 1274         | 34.4317407 | -118.6497607 | Valve Adjustment: Orifice Plate Changed (See OP Log)                                                 |                                   |
| H-2272W    | 8/17/2026 9:06:27 AM  | 22.1       | 32.1       | 0.0       | 45.7           |                         |                         | 0.7     | 0.0          | 121.3                | 122.3               | -1.16                        | -1.15                       | 6.6                 | 6.6                | 4.862                        | 4.804                       | -14.03                   | -13.99                       | 28.7                   | 1281         | 34.4317590 | -118.6497500 | Valve Adjustment: Increased Flow/Vacuum                                                              |                                   |
| H-2273W    | 8/5/2026 7:10:00 AM   |            |            |           |                |                         | 6100                    |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                          |                              |                        |              |            |              |                                                                                                      | AirTech Lab; [User entered 0.61%] |
| H-2273W    | 8/5/2026 7:10:00 AM   |            |            |           |                | 42                      |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                          |                              |                        |              |            |              |                                                                                                      | AirTech Lab                       |
| H-2273W    | 8/5/2026 9:37:15 AM   | 24.6       | 43.3       | 0.0       | 32.1           |                         |                         | 0.6     | 0.0          | 116.4                | 116.4               | -1.32                        | -1.29                       | 0.0                 | 0.0                | -0.017                       | -0.017                      | -17.10                   |                              | 28.59                  | 1306         | 34.4321565 | -118.6499533 | .                                                                                                    |                                   |
| H-2273W    | 8/11/2026 8:45:00 AM  |            |            |           |                |                         | 9300                    |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                          |                              |                        |              |            |              |                                                                                                      | AirTech Lab; [User entered 0.93%] |
| H-2273W    | 8/11/2026 8:45:00 AM  |            |            |           |                | 71                      |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                          |                              |                        |              |            |              |                                                                                                      | AirTech Lab                       |
| H-2273W    | 8/17/2026 9:56:01 AM  | 21.6       | 35.4       | 0.0       | 43.0           |                         |                         | 0.6     | 0.0          | 127.5                | 127.3               | -1.25                        | -1.14                       | 4.8                 | 2.8                | 0.150                        | 0.052                       | -12.67                   | -12.10                       | 28.7                   | 1294         | 34.4321513 | -118.6499492 | Valve Adjustment: Decreased Flow/Vacuum                                                              |                                   |
| H-2274B    | 8/13/2026 1:59:37 PM  | 54.9       | 41.5       | 0.0       | 3.7            |                         |                         | 1.3     | 0.0          | 106.6                | 107.1               | -3.23                        | -4.16                       | 6.8                 | 9.5                | 0.124                        | 0.243                       | -11.68                   | -11.64                       | 28.56                  | 1339         | 34.4326530 | -118.6469637 | Valve Adjustment: Increased Flow/Vacuum                                                              |                                   |
| H-2274B    | 8/13/2026 2:01:26 PM  | 53.7       | 41.9       | 0.0       | 4.4            |                         |                         | 1.3     | 0.0          | 107.4                | 107.3               | -4.27                        | -4.11                       | 9.3                 | 9.3                | 0.232                        | 0.231                       | -11.55                   | -11.46                       | 28.56                  | 1349         | 34.4326653 | -118.6469562 |                                                                                                      |                                   |
| H-2274B    | 8/21/2026 8:17:55 AM  | 52.1       | 46.0       | 0.0       | 1.9            |                         |                         | 1.1     | 0.0          | 107.3                | 107.4               | -3.81                        | -3.86                       | 7.2                 | 7.7                | 0.140                        | 0.160                       | -9.11                    | -9.50                        | 28.6                   | 1364         | 34.4326670 | -118.6469360 | Valve Adjustment: Surging Liquid in Header, Surging Liquid in Well (Watered In)                      |                                   |
| H-2274W    | 8/5/2026 9:46:19 AM   | 18.5       | 31.8       | 0.3       | 49.4           |                         |                         | 0.6     | 164.7        | 100.0                | 100.0               | -1.10                        | -1.09                       | 1.8                 | 2.0                | 0.021                        | 0.026                       | -13.39                   |                              | 28.59                  | 1309         | 34.4327843 | -118.6503452 | .                                                                                                    |                                   |
| H-2274W    | 8/17/2026 10:03:10 AM | 18.0       | 31.4       | 0.0       | 50.6           |                         |                         | 0.6     | 0.0          | 101.4                | 102.7               | -1.07                        | -1.06                       | 1.1                 | 0.4                | 0.007                        | 0.001                       | -10.66                   | -9.24                        | 28.71                  | 1293         | 34.4327813 | -118.6503640 | Valve Adjustment: Barely Open                                                                        |                                   |
| H-2275E    | 8/18/2026 9:28:52 AM  | 24.9       | 41.8       | 0.0       | 33.3           |                         |                         | 0.6     | 0.0          | 110.4                | 110.3               | -0.75                        | -0.59                       | 4.9                 | 0.6                | 0.148                        | 0.002                       | -8.13                    | -7.92                        | 28.63                  | 1321         | 34.4323885 | -118.6462055 | Valve Adjustment: Decreased Flow/Vacuum                                                              |                                   |
| H-2275W    | 8/3/2026 9:55:24 AM   | 6.9        | 23.4       | 1.8       | 68.0           |                         |                         | 0.3     | 38.8         | 130.7                | 130.5               | -0.42                        | -0.41                       | 2.8                 | 1.4                | 0.172                        | 0.042                       | -15.25                   | -15.12                       | 28.49                  | 1310         | 34.4321942 | -118.6494005 | Valve Adjustment: Decreased Flow/Vacuum, Barely Open, Plugged/Pinched Suspected                      |                                   |
| H-2275W    | 8/17/2026 9:30:12 AM  | 3.7        | 18.6       | 3.8       | 73.9           |                         |                         | 0.2     | 19.4         | 130.7                | 123.4               | -0.48                        | -0.44                       | 3.8                 | 0.5                | 0.094                        | 0.002                       | -13.71                   | -13.05                       | 28.69                  | 1314         | 34.4322262 | -118.6493880 | Valve Adjustment: NSPS/EG CAI, High Temp, Decreased Flow/Vacuum                                      |                                   |
| H-2275W    | 8/17/2026 9:33:49 AM  | 3.8        | 18.7       | 3.1       | 74.4           |                         |                         | 0.2     | 24.0         | 128.1                | 127.4               | -0.46                        | -0.45                       | 1.2                 | 1.2                | 0.010                        | 0.009                       | -13.99                   | -13.39                       | 28.69                  | 1322         | 34.4322263 | -118.6493947 | Valve Adjustment: NSPS/EG CAC                                                                        |                                   |
| H-2276A    | 8/4/2026 1:47:43 PM   | 37.5       | 37.4       | 0.7       | 24.4           |                         |                         | 1.0     | 34.9         | 116.7                | 116.7               | -5.74                        | -4.08                       | 16.0                | 11.9               | 0.605                        | 0.332                       | -9.75                    | -9.97                        | 28.45                  | 1366         | 34.4328742 | -118.6482663 | Valve Adjustment: Decreased Flow/Vacuum                                                              |                                   |
| H-2276A    | 8/21/2026 9:33:17 AM  | 35.7       | 34.9       | 0.3       | 9.1            |                         |                         | 0.7     | 30.3         | 116.5                | 116.4               | -3.46                        | -1.66                       | 11.0                | 6.7                | 0.281                        | 0.104                       | -8.62                    | -9.30                        | 28.58                  | 1369         | 34.4328903 | -118.6482795 | Valve Adjustment: Decreased Flow/Vacuum                                                              |                                   |
| H-2276B    | 8/4/2026 3:51:52 PM   | 55.8       | 43.9       | 0.0       | 0.3            |                         |                         | 1.3     | 0.0          | 120.2                | 120.3               | -4.82                        | -5.47                       | 25.6                | 32.1               | 1.553                        | 2.459                       | -8.71                    | -8.51                        | 28.41                  | 1377         | 34.4328728 | -118.6469112 | Valve Adjustment: Increased Flow/Vacuum                                                              |                                   |
| H-2276B    | 8/21/2026 8:21:09 AM  | 55.2       | 43.3       | 0.0       | 1.5            |                         |                         | 1.3     | 0.0          | 119.3                | 119.2               | -6.62                        | -6.50                       | 24.3                | 21.5               | 1.402                        | 1.092                       | -9.32                    | -8.26                        | 28.6                   | 1378         | 34.4328840 | -118.6469257 | Valve Adjustment: Surging Liquid in Header                                                           |                                   |
| H-2276B    | 8/21/2026 9:35:35 AM  | 39.5       | 59.1       | 0.0       | 1.4            |                         |                         | 0.7     | 0.0          | 121.8                | 121.5               | -0.05                        | -0.05                       | 6.3                 | 6.5                | 0.093                        | 0.099                       | -9.18                    | -9.57                        | 28.58                  | 1387         | 34.4330228 | -118.6481060 | Valve Adjustment: Barely Open                                                                        |                                   |
| H-2276E    | 8/18/2026 9:13:29 AM  | 30.3       | 31.3       | 0.0       | 38.4           |                         |                         | 1.0     | 0.0          | 108.4                | 113.3               | -0.93                        | -0.94                       | 3.2                 | 2.6                | 0.013                        | 0.009                       | -20.72                   | -20.54                       | 28.62                  | 1329         | 34.4328138 | -118.6453598 | Valve Adjustment: Barely Open                                                                        |                                   |
| H-2276W    | 8/5/2026 9:55:38 AM   | 20.8       | 48.6       | 0.0       | 30.6           |                         |                         | 0.4     | 0.0          | 109.9                | 105.7               | -9.93                        | -4.84                       | 3.4                 | 8.6                | 0.080                        | 0.513                       | -15.28                   |                              | 28.58                  | 1378         | 34.4325868 | -118.6499612 | .                                                                                                    |                                   |
| H-2276W    | 8/17/2026 9:52:25 AM  | 18.1       | 39.6       | 0.0       | 42.3           |                         |                         | 0.5     | 0.0          | 110.8                | 111.7               | -7.41                        | -7.07                       | 1.5                 | 0.7                | 0.014                        | 0.003                       | -13.43                   | -12.10                       | 28.7                   | 1305         | 34.4326747 | -118.6499805 | Valve Adjustment: Decreased Flow/Vacuum                                                              |                                   |
| H-2277A    | 8/6/2026 8            |            |            |           |                |                         |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                          |                              |                        |              |            |              |                                                                                                      |                                   |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name   | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init Flow<br>[scfm] | Adj Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>[psi] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                                                                      |
|--------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|---------------------|--------------------|------------------------------|-----------------------------|--------------------------|------------------------------|------------------------|--------------|------------|--------------|-------------------------------------------------------------------------------------------------------------------------------|
| H-2277A      | 8/17/2026 10:47:20 AM | 0.5        | 0.2        | 19.9      | 79.4           |                         |                         | 2.5     | 4.0          | 98.8                 | 102.0               | -4.92                        | -0.20                       | 3.0                 | 1.4                | 0.056                        | 0.012                       | -4.64                    | -4.81                        | 28.66                  | 1354         | 34.4330428 | -118.6487467 | Valve Adjustment: NSPS/EG CAI, High O2, Decreased Flow/Vacuum                                                                 |
| H-2277A      | 8/17/2026 10:49:15 AM | 5.4        | 3.2        | 18.2      | 73.2           |                         |                         | 1.7     | 4.0          | 102.6                | 102.6               | -0.50                        | -0.50                       | 1.2                 | 1.2                | 0.009                        | 0.008                       | -5.00                    | -4.92                        | 28.66                  | 1351         | 34.4330458 | -118.6487492 | Valve Adjustment: NSPS/EG CAI, High O2, Barely Open                                                                           |
| H-2277A      | 8/17/2026 10:50:27 AM | 6.6        | 4.3        | 17.6      | 71.5           |                         |                         | 1.5     | 4.1          | 102.9                | 103.0               | -0.50                        | -0.50                       | 0.9                 | 0.9                | 0.005                        | 0.005                       | -4.70                    | -4.41                        | 28.66                  | 1353         | 34.4330428 | -118.6487480 | Valve Adjustment: NSPS/EG CAI, High O2                                                                                        |
| H-2277B      | 8/4/2026 3:43:21 PM   | 44.8       | 39.0       | 0.0       | 16.2           |                         |                         | 1.1     | 0.0          | 113.8                | 113.9               | -2.15                        | -2.13                       | 1.7                 | 1.6                | 0.809                        | 0.674                       | -8.01                    | -8.02                        | 28.41                  | 1376         | 34.4330562 | -118.6469327 | Valve Adjustment: Reduce Sys. Vac. - Flare Down                                                                               |
| H-2277B      | 8/24/2026 10:08:41 AM | 50.9       | 41.5       | 0.0       | 7.6            |                         |                         | 1.2     | 0.0          | 112.6                | 112.5               | -1.83                        | -1.81                       | 1.4                 | 1.4                | 0.519                        | 0.541                       | -7.42                    | -7.41                        | 28.56                  | 1385         | 34.4330580 | -118.6469167 | Valve Adjustment: Barely Open                                                                                                 |
| H-23 (EXP-2) | 8/26/2026 11:01:45 AM | 3.3        | 72.7       | 0.0       | 24.0           |                         |                         | 0.0     | 0.0          | 93.1                 | 91.8                | -16.16                       | -16.12                      | 2.8                 | 4.7                | 0.018                        | 0.052                       | -15.84                   | -15.83                       | 28.63                  | 1270         | 34.4370013 | -118.6421192 |                                                                                                                               |
| H-2301E      | 8/20/2026 4:23:23 PM  | 54.7       | 42.1       | 0.0       | 3.2            |                         |                         | 1.3     | 0.0          | 112.9                | 113.0               | -0.18                        | -0.17                       | 11.2                | 11.5               | 0.284                        | 0.299                       | -12.04                   | -12.01                       | 28.92                  | 1022         | 34.4270674 | -118.6479995 |                                                                                                                               |
| H-2301W      | 8/28/2026 12:23:38 PM | 3.6        | 2.0        | 19.4      | 75.0           |                         |                         | 1.8     | 3.9          | 104.9                | 105.2               | -3.03                        | -3.02                       | 1.0                 | 1.0                | 0.099                        | 0.098                       | -3.37                    | -3.09                        | 28.86                  | 1145         | 34.4274975 | -118.6506098 | Valve Adjustment: NSPS/EG CAI, High O2, Barely Open, Surging Liquid in Well (Watered In)                                      |
| H-2301W      | 8/28/2026 12:24:39 PM | 2.7        | 1.5        | 19.8      | 76.0           |                         |                         | 1.8     | 3.8          | 106.0                | 106.1               | -2.91                        | -2.87                       | 1.2                 | 1.1                | 0.154                        | 0.129                       | -3.13                    | -3.39                        | 28.86                  | 1132         | 34.4274835 | -118.6506290 |                                                                                                                               |
| H-2302C      | 8/12/2026 1:11:26 PM  | 48.1       | 37.3       | 0.5       | 14.1           |                         |                         | 1.3     | 28.2         | 125.9                | 126.0               | -0.63                        | -0.64                       | 15.1                | 16.6               | 0.532                        | 0.644                       | -12.24                   | -12.35                       | 28.73                  | 1123         | 34.4284267 | -118.6488907 | Valve Adjustment: Barely Open                                                                                                 |
| H-2302E      | 8/20/2026 4:44:12 PM  | 53.1       | 38.0       | 0.0       | 8.9            |                         |                         | 1.4     | 0.0          | 117.0                | 117.9               | -9.53                        | -9.80                       | 14.7                | 14.4               | 0.284                        | 0.271                       | -10.00                   | -10.15                       | 28.86                  | 1074         | 34.4275147 | -118.6472421 |                                                                                                                               |
| H-2303E      | 8/20/2026 4:50:27 PM  | 58.2       | 41.2       | 0.0       | 0.6            |                         |                         | 1.4     | 0.0          | 107.9                | 108.0               | -8.47                        | -8.57                       | 5.1                 | 5.1                | 0.034                        | 0.033                       | -8.43                    | -8.55                        | 28.85                  | 1077         | 34.4279196 | -118.6471912 |                                                                                                                               |
| H-2303N      | 8/12/2026 1:16:22 PM  | 17.9       | 22.0       | 5.4       | 54.7           |                         |                         | 0.8     | 10.1         | 105.3                | 105.6               | -0.90                        | -0.78                       | 0.5                 | 1.1                | 0.006                        | 0.025                       | -13.57                   | -13.66                       | 28.71                  | 1140         | 34.4290475 | -118.6484228 | Valve Adjustment: NSPS/EG CAI, High O2, Decreased Flow/Vacuum, Barely Open                                                    |
| H-2303N      | 8/12/2026 1:19:09 PM  | 24.3       | 26.0       | 4.0       | 45.7           |                         |                         | 0.9     | 11.4         | 106.1                | 106.2               | -1.33                        | -1.34                       | 1.5                 | 1.6                | 0.048                        | 0.051                       | -13.68                   | -13.90                       | 28.71                  | 1144         | 34.4290437 | -118.6484400 | Valve Adjustment: Barely Open, Surging Liquid in Header                                                                       |
| H-2303S      | 8/28/2026 11:25:27 AM | 54.5       | 40.9       | 0.0       | 4.6            |                         |                         | 1.3     | 0.0          | 110.8                | 110.8               | -0.20                        | -0.75                       | 13.8                | 19.5               | 0.241                        | 0.482                       | -3.56                    | -3.64                        | 28.89                  | 1123         | 34.4272958 | -118.6495662 | Valve Adjustment: Audible Flow, Increased Flow/Vacuum                                                                         |
| H-2304E      | 8/27/2026 11:55:16 AM | 56.9       | 40.3       | 0.0       | 2.8            |                         |                         | 1.4     | 0.0          | 99.0                 | 98.7                | -0.08                        | -0.82                       | 9.8                 | 51.3               | 0.024                        | 0.643                       | -1.60                    | -1.54                        | 28.91                  | 1071         | 34.4282327 | -118.6468813 | Valve Adjustment: Increased Flow/Vacuum, Surging Liquid in Header, Plugged/Pinched Suspected                                  |
| H-2304S      | 8/28/2026 11:37:56 AM | 51.2       | 41.6       | 0.0       | 7.2            |                         |                         | 1.2     | 0.0          | 134.0                | 133.9               | -0.18                        | -0.03                       | 10.7                | 17.5               | 0.746                        | 1.980                       | 0.00                     | -0.01                        | 28.89                  | 1082         | 34.4275062 | -118.6489040 | Valve Adjustment: NSPS/EG CAI, Orifice Plate Changed (See OP Log), High Temp, Barely Open                                     |
| H-2304S      | 8/28/2026 11:40:02 AM | 52.4       | 42.5       | 0.0       | 5.1            |                         |                         | 1.2     | 0.0          | 134.0                | 134.0               | -0.02                        | -0.02                       | 8.9                 | 9.0                | 1.711                        | 1.724                       | -0.01                    | 0.00                         | 28.89                  | 1079         | 34.4275003 | -118.6489353 |                                                                                                                               |
| H-2304S      | 8/31/2026 12:25:12 PM | 53.1       | 41.3       | 0.0       | 5.6            |                         |                         | 1.3     | 0.0          | 126.1                | 126.3               | -0.86                        | -0.65                       | 5.7                 | 7.0                | 0.691                        | 1.044                       | -2.66                    | -2.98                        | 28.84                  | 1080         | 34.4274955 | -118.6489182 | Valve Adjustment: NSPS/EG CAC                                                                                                 |
| H-2304S      | 8/31/2026 12:38:33 PM | 52.9       | 41.7       | 0.0       | 5.4            |                         |                         | 1.3     | 0.0          | 124.5                | 124.6               | -0.04                        | -0.10                       | 8.7                 | 10.0               | 1.610                        | 2.117                       | -2.91                    | -2.84                        | 28.83                  | 1099         | 34.4274960 | -118.6488963 | Valve Comment: Remoted; Valve Adjustment: Increased Flow/Vacuum                                                               |
| H-2305N      | 8/12/2026 1:22:40 PM  | 39.3       | 36.3       | 0.0       | 24.4           |                         |                         | 1.1     | 0.0          | 102.0                | 102.1               | -0.33                        | -0.33                       | 0.7                 | 0.7                | 0.010                        | 0.009                       | -13.33                   | -13.50                       | 28.71                  | 1151         | 34.4290085 | -118.6485992 | Valve Adjustment: Barely Open                                                                                                 |
| H-2305S      | 8/30/2026 1:17:51 PM  | 52.4       | 42.6       | 0.0       | 5.0            |                         |                         | 1.2     | 0.0          | 128.8                | 129.5               | 0.38                         | -0.18                       | 11.6                | 14.7               | 0.312                        | 0.504                       | -3.47                    | -4.03                        | 28.83                  | 1053         | 34.4274590 | -118.6484840 | Valve Adjustment: NSPS/EG CAI, NSPS/EG CAC, Orifice Plate Changed (See OP Log), Positive Static Press., Increased Flow/Vacuum |
| H-2305S      | 8/30/2026 1:19:03 PM  | 52.5       | 42.5       | 0.0       | 5.0            |                         |                         | 1.2     | 0.0          | 129.6                | 129.6               | -0.32                        | -0.32                       | 19.9                | 19.9               | 0.520                        | 0.520                       | -3.80                    | -3.80                        | 28.83                  | 1052         | 34.4274575 | -118.6484598 |                                                                                                                               |
| H-2306N      | 8/28/2026 10:37:17 AM | 53.0       | 42.7       | 0.0       | 4.3            |                         |                         | 1.2     | 0.0          | 119.5                | 119.8               | -0.02                        | -0.01                       | 20.0                | 19.6               | 0.927                        | 0.892                       | -3.94                    | -3.62                        | 28.75                  | 1123         | 34.4294525 | -118.6475658 | Valve Adjustment: Barely Open                                                                                                 |
| H-2307S      | 8/9/2026 10:20:52 AM  | 49.6       | 41.7       | 0.1       | 8.6            |                         |                         | 1.2     | 95.3         | 117.1                | 118.0               | -0.92                        | -0.78                       | 27.8                | 25.0               | 1.791                        | 1.449                       | -17.09                   | -16.62                       | 28.75                  | 1146         | 34.4284383 | -118.6498232 | Valve Adjustment: Decreased Flow/Vacuum                                                                                       |
| H-2307S      | 8/9/2026 10:24:35 AM  | 49.7       | 41.9       | 0.1       | 8.3            |                         |                         | 1.2     | 92.7         | 120.3                | 120.5               | -0.72                        | -0.73                       | 24.3                | 24.3               | 1.372                        | 1.368                       | -16.73                   | -16.76                       | 28.76                  | 1130         | 34.4284473 | -118.6498035 |                                                                                                                               |
| H-2308S      | 8/9/2026 10:29:17 AM  | 50.6       | 43.1       | 0.1       | 6.3            |                         |                         | 1.2     | 78.1         | 123.3                | 123.5               | -0.24                        | -0.24                       | 24.1                | 24.0               | 0.756                        | 0.749                       | -16.54                   | -16.60                       | 28.75                  | 1145         | 34.4284730 | -118.6498183 |                                                                                                                               |
| H-2309N      | 8/12/2026 9:50:35 AM  | 34.6       | 36.5       | 0.0       | 29.0           |                         |                         | 0.9     | 0.0          | 105.1                | 104.7               | -13.89                       | -8.52                       | 2.1                 | 1.2                | 0.029                        | 0.008                       | -18.93                   | -18.79                       | 28.64                  | 1305         | 34.4308128 | -118.6489063 | Valve Adjustment: Decreased Flow/Vacuum, Plugged/Pinched Suspected                                                            |
| H-2309N      | 8/17/2026 9:48:06 AM  | 41.6       | 38.0       | 0.0       | 19.7           |                         |                         | 1.1     | 0.0          | 103.0                | 103.1               | -10.85                       | -11.08                      | 2.4                 | 2.8                | 0.036                        | 0.050                       | -19.23                   | -18.79                       | 28.71                  | 1279         | 34.4308250 | -118.6489225 | Valve Adjustment: Plugged/Pinched Suspected                                                                                   |
| H-2309S      | 8/30/2026 12:46:12 PM | 52.5       | 41.7       | 0.0       | 5.8            |                         |                         | 1.3     | 290.5        | 117.8                | 118.0               | -0.62                        | -1.06                       | 16.1                | 24.9               | 0.334                        | 0.802                       | -3.58                    | -3.72                        | 28.79                  | 1107         | 34.4281575 | -118.6487388 | Valve Adjustment: Increased Flow/Vacuum                                                                                       |
| H-2309S      | 8/30/2026 12:47:09 PM | 52.5       | 41.8       | 0.0       | 5.7            |                         |                         | 1.3     | 0.0          | 118.3                | 118.3               | -1.13                        | -1.01                       | 23.4                | 22.1               | 0.709                        | 0.631                       | -3.66                    | -3.31                        | 28.79                  | 1104         | 34.4281543 | -118.6487238 |                                                                                                                               |
| H-2310N      | 8/17/2026 12:35:28 PM | 55.0       | 40.0       | 0.0       | 5.0            |                         |                         | 1.4     | 0.0          | 116.1                | 116.2               | -0.25                        | -0.25                       | 4.9                 | 4.9                | 0.506                        | 0.497                       | -8.90                    | -8.85                        | 28.8                   | 1193         | 34.4298647 | -118.6478665 | Valve Adjustment: Orifice Plate Changed (See OP Log)                                                                          |
| H-2310N      | 8/17/2026 12:40:08 PM | 53.9       | 40.6       | 0.0       | 5.5            |                         |                         | 1.3     | 0.0          | 116.2                | 116.3               | -0.32                        | -0.33                       | 5.9                 | 6.3                | 0.719                        | 0.817                       | -8.87                    | -8.90                        | 28.81                  | 1217         | 34.4298625 | -118.6478628 | Valve Adjustment: Orifice Plate Changed (See OP Log), Increased Flow/Vacuum                                                   |
| H-2310N      | 8/17/2026 12:40:51 PM | 53.8       | 40.8       | 0.0       | 5.4            |                         |                         | 1.3     | 0.0          | 116.4                | 116.3               | -0.35                        | -0.33                       | 6.4                 | 6.4                | 0.869                        | 0.860                       | -8.91                    | -8.85                        | 28.82                  | 1190         | 34.4298752 | -118.6478780 |                                                                                                                               |
| H-2310S      | 8/28/2026 10:34:05 AM | 51.2       | 42.5       | 0.0       | 6.3            |                         |                         | 1.2     | 0.0          | 112.7                | 112.8               | -0.15                        | -0.23                       | 27.9                | 31.1               | 0.991                        | 1.237                       | -4.25                    | -3.49                        | 28.78                  | 1107         | 34.4291552 | -118.6475162 | Valve Adjustment: Barely Open                                                                                                 |
| H-2401S      | 8/12/2026 10:14:34 AM | 56.3       | 41.8       | 0.0       | 1.9            |                         |                         | 1.3     | 0.0          | 111.7                | 111.7               | -13.25                       | -13.29                      | 10.0                | 9.9                | 2.142                        | 2.128                       | -17.25                   | -17.14                       | 28.68                  | 1195         | 34.4288588 | -118.6512203 | Valve Adjustment: Valve 100% Open                                                                                             |
| H-2402N      | 8/12/2026 12:40:27 PM | 45.0       | 39.8       | 0.0       | 15.2           |                         |                         | 1.1     | 0.0          | 116.1                | 116.0               | -0.65                        | -0.67                       | 6.2                 | 6.8                | 0.799                        | 0.977                       | -17.27                   | -17.17                       | 28.64                  | 1203         | 34.4291578 | -118.6502533 | Valve Adjustment: Barely Open                                                                                                 |
| H-2402S      | 8/12/2026 10:33:21 AM | 51.2       | 41.4       | 0.0       | 7.4            |                         |                         | 1.2     | 0.0          | 114.0                | 114.0               | -0.31                        | -0.32                       | 19.1                | 19.9               | 0.466                        | 0.507                       | -15.88                   | -15.94                       | 28.69                  | 1188         | 34.4287470 | -118.6504917 | Valve Adjustment: Barely Open                                                                                                 |
| H-2403N      | 8/12/2026 12:43:15 PM | 39.0       | 36.3       | 1.7       | 23.0           |                         |                         | 1.1     | 13.5         | 118.9                | 118.9               | -0.58                        | -0.56                       | 6.5                 | 6.5                | 0.899                        | 0.888                       | -17.29                   | -17.35                       | 28.64                  | 1210         | 34.4293038 | -118.6501498 | Valve Adjustment: Barely Open                                                                                                 |
| H-2403S      | 8/12/2026 12:57:27 PM | 39.4       | 32.4       | 2.3       | 25.9           |                         |                         | 1.2     | 11.3         | 94.7                 | 95.2                | -4.85                        | -1.45                       | 0.7                 | 0.3                | 0.011                        | 0.002                       | -16.18                   | -16.07                       | 28.69                  | 1178         | 34.4287905 | -118.6498425 | Valve Adjustment: Decreased Flow/Vacuum, Barely Open                                                                          |
| H-2404N      | 8/12/2026 12:47:23 PM | 49.2       | 41.1       | 0.0       | 9.7            |                         |                         | 1.2     | 0.0          | 116.7                | 116.8               | -4.95                        | -4.43                       | 15.8                | 14.3               | 5.363                        | 4.359                       | -17.34                   | -17.23                       | 28.67                  | 1202         | 34.4292923 | -118.6495245 | Valve Adjustment: Decreased Flow/Vacuum                                                                                       |
| H-2404S      | 8/12/2026 1:07:56 PM  | 54.2       | 41.9       | 0.0       | 3.9            |                         |                         | 1.3     | 0.0          | 115.1                | 115.2               | -10.63                       | -10.35                      | 24.2                | 19.7               | 0.772                        | 0.511                       | -11.59                   | -11.08                       | 28.68                  | 1168         | 34.4287718 | -118.6493058 | Valve Adjustment: Valve 100% Open                                                                                             |
| H-2405N      | 8/12/2026 10:28:52 AM | 19.6       | 35.0       | 0.1       | 45.3           |                         |                         | 0.6     | 411.7        | 128.1                | 127.7               | -0.94                        | -0.67                       | 14.2                | 8.2                | 4.356                        | 1.437                       | -18.26                   | -18.52                       | 28.68                  | 1273         | 34.4300035 | -118.6495075 | Valve Adjustment: Decreased Flow/Vacuum                                                                                       |
| H-2405N      | 8/12/2026 10:32:20 AM | 21.7       | 35.4       | 0.1       | 42.8           |                         |                         | 0.6     | 611.4        | 127.4                | 127.2               | -0.63                        | -0.61                       | 6.0                 | 6.0                | 0.761                        | 0.774                       | -17.99                   | -18.02                       | 28.68                  | 1263         | 34.4299937 | -118.6495097 | Valve Adjustment: Decreased Flow/Vacuum                                                                                       |
| H-29         | 8/27/2026 10:44:04 AM | 31.6       | 41.2       | 1.0       | 26.2           |                         |                         | 0.8     | 26.2         | 118.4                | 118.5               | -1.02                        | -1.01                       | 1.2                 | 1.1                | 0.028                        | 0.025                       | -15.13                   | -14.73                       | 28.73                  | 1285         | 34.4354053 | -118.6417788 | Valve Adjustment: Audible Flow                                                                                                |
| H-72         | 8/26/2026 9:58:42 AM  | 28.4       | 66.0       | 0.0       | 5.6            |                         |                         | 0.4     | 0.0          | 100.8                | 100.8               | -1.06                        | -1.07                       | 4.0                 | 5.6                | 0.020                        | 0.039                       | -12.61                   | -14.57                       | 28.59                  | 1307         | 34.4369198 | -118.6448167 | Valve Adjustment: Barely Open                                                                                                 |
| H-74         | 8/1/2026 8:52:05 AM   | 49.7       | 41.8       | 0.0       | 8.5            |                         |                         | 1.2     | 0.0          | 109.7                | 109.8               | -8.40                        | -8.13                       | 11.5                | 8.4                | 2.820                        | 1.494                       | -11.16                   |                              |                        |              |            |              |                                                                                                                               |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init Flow<br>[scfm] | Adj Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>[psi] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                        |
|------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|---------------------|--------------------|------------------------------|-----------------------------|--------------------------|------------------------------|------------------------|--------------|------------|--------------|---------------------------------------------------------------------------------|
| H-79       | 8/11/2026 10:56:09 AM | 52.4       | 42.3       | 0.0       | 5.2            |                         |                         | 1.2     | 0.0          | 121.1                | 121.9               | -0.78                        | -1.03                       | 5.8                 | 4.3                | 0.044                        | 0.024                       | -15.76                   | -15.60                       | 28.69                  | 1310         | 34.4339370 | -118.6427992 | Valve Adjustment:Audible Flow,Increased Flow/Vacuum                             |
| H-79       | 8/19/2026 12:54:51 PM | 38.7       | 42.2       | 0.8       | 18.3           |                         |                         | 0.9     | 22.9         | 137.7                | 130.4               | -7.47                        | -2.78                       | 12.7                | 12.7               | 0.220                        | 0.214                       | -12.99                   | -12.92                       | 28.71                  | 1277         | 34.4354182 | -118.6417643 | Valve Adjustment: NSPS/EG CAI,High Temp,Decreased Flow/Vacuum                   |
| H-79       | 8/19/2026 12:56:10 PM | 38.7       | 39.3       | 2.2       | 19.8           |                         |                         | 1.0     | 9.0          | 130.2                | 130.1               | -2.55                        | -2.53                       | 15.9                | 16.7               | 0.334                        | 0.372                       | -12.77                   | -12.45                       | 28.71                  | 1266         | 34.4354273 | -118.6417513 | Valve Adjustment: NSPS/EG CAC                                                   |
| H-79       | 8/20/2026 9:32:22 AM  | 43.9       | 42.0       | 0.0       | 14.1           |                         |                         | 1.0     | 0.0          | 121.6                | 121.8               | -1.06                        | -1.16                       | 3.7                 | 5.0                | 0.018                        | 0.032                       | -14.63                   | -14.81                       | 28.67                  | 1308         | 34.4339325 | -118.6427892 | Valve Adjustment:increased Flow/Vacuum                                          |
| P-02R      | 8/5/2026 1:55:00 PM   | 27.5       | 30.8       | 0.0       | 41.7           |                         |                         | 0.9     | 0.0          | 90.0                 | 90.1                | -0.44                        | -0.44                       | 9.1                 | 9.1                | 0.502                        | 0.494                       | -20.32                   | -20.22                       | 28.76                  | 1157         | 34.4297303 | -118.6439335 |                                                                                 |
| P-03R      | 8/5/2026 2:02:14 PM   | 38.3       | 32.1       | 0.0       | 29.6           |                         |                         | 1.2     | 0.0          | 102.9                | 103.2               | -1.21                        | -1.20                       | 2.9                 | 3.0                | 0.908                        | 0.929                       | -18.92                   | -18.99                       | 28.76                  | 1180         | 34.4298663 | -118.6442307 |                                                                                 |
| P-04       | 8/5/2026 2:07:04 PM   | 37.4       | 34.4       | 0.0       | 28.2           |                         |                         | 1.1     | 0.0          | 103.7                | 103.8               | -1.14                        | -1.14                       |                     |                    | 1.154                        | 1.148                       | -17.93                   | -17.78                       | 28.76                  | 1168         | 34.4294618 | -118.6445850 |                                                                                 |
| P-05       | 8/6/2026 9:40:01 AM   | 29.4       | 33.1       | 0.0       | 37.5           |                         |                         | 0.9     | 0.0          | 103.6                | 103.6               | -0.26                        | -0.26                       |                     |                    | 0.272                        | 0.271                       | -17.76                   | -17.69                       | 28.8                   | 1148         | 34.4291915 | -118.6447517 |                                                                                 |
| P-06R      | 8/6/2026 9:47:29 AM   | 38.8       | 34.4       | 0.0       | 26.8           |                         |                         | 1.1     | 0.0          | 113.6                | 113.6               | -0.78                        | -0.77                       | 6.3                 | 5.8                | 0.247                        | 0.212                       | -16.55                   | -16.52                       | 28.8                   | 1137         | 34.4288808 | -118.6450468 |                                                                                 |
| P-07R      | 8/17/2026 10:01:53 AM | 32.2       | 26.8       | 0.0       | 41.0           |                         |                         | 1.2     | 0.0          | 90.3                 | 90.3                | -0.86                        | -0.86                       | 3.8                 | 3.9                | 1.490                        | 1.566                       | -19.92                   | -19.99                       | 28.82                  | 1204         | 34.4298579 | -118.6433202 |                                                                                 |
| P-08R      | 8/5/2026 10:52:06 AM  | 52.1       | 38.0       | 0.0       | 9.8            |                         |                         | 1.4     | 0.0          | 102.2                | 102.1               | -16.62                       | -16.76                      | 12.9                | 10.6               | 0.386                        | 0.262                       | -17.49                   | -17.15                       | 28.76                  | 1173         | 34.4294015 | -118.6437450 |                                                                                 |
| P-09       | 8/3/2026 1:57:38 PM   | 48.5       | 35.7       | 0.0       | 15.8           |                         |                         | 1.4     | 0.0          | 100.8                | 100.9               | -0.39                        | -0.38                       |                     |                    | 0.384                        | 0.371                       | -12.38                   | -12.20                       | 28.63                  | 1164         | 34.4290143 | -118.6442435 |                                                                                 |
| P-10       | 8/3/2026 2:02:31 PM   | 47.6       | 35.5       | 0.1       | 16.8           |                         |                         | 1.3     | 168.0        | 100.7                | 100.7               | -0.17                        | -0.16                       | 3.5                 | 3.6                | 1.292                        | 1.389                       | -11.59                   | -12.24                       | 28.63                  | 1159         | 34.4287338 | -118.6445952 |                                                                                 |
| P-11       | 8/6/2026 9:56:27 AM   | 46.5       | 35.9       | 0.0       | 17.6           |                         |                         | 1.3     | 0.0          | 107.5                | 107.5               | -0.59                        | -0.59                       | 7.8                 | 7.7                | 6.574                        | 6.344                       | -12.07                   | -11.72                       | 28.81                  | 1133         | 34.4285142 | -118.6449518 |                                                                                 |
| P-12       | 8/6/2026 10:07:09 AM  | 59.4       | 40.3       | 0.0       | 0.3            |                         |                         | 1.5     | 0.0          | 89.8                 | 89.8                | -14.15                       | -14.10                      | 7.8                 | 5.5                | 0.077                        | 0.038                       | -13.88                   | -13.85                       | 28.85                  | 1105         | 34.4288622 | -118.6456290 |                                                                                 |
| P-13       | 8/6/2026 10:11:26 AM  | 51.8       | 32.9       | 0.0       | 15.3           |                         |                         | 1.6     | 0.0          | 89.8                 | 89.5                | -0.69                        | -0.68                       | 9.3                 | 9.4                | 0.524                        | 0.529                       | -13.83                   | -13.84                       | 28.82                  | 1112         | 34.4285368 | -118.6457987 |                                                                                 |
| P-14       | 8/6/2026 10:17:59 AM  | 26.4       | 28.1       | 0.1       | 45.4           |                         |                         | 0.9     | 504.8        | 91.1                 | 91.4                | -0.21                        | -0.21                       |                     |                    | 0.214                        | 0.218                       | -13.37                   | -13.10                       | 28.85                  | 1110         | 34.4280870 | -118.6460697 |                                                                                 |
| P-15R      | 8/6/2026 10:23:44 AM  | 41.5       | 32.2       | 0.0       | 26.4           |                         |                         | 1.3     | 0.0          | 95.6                 | 96.0                | -1.43                        | -1.42                       | 2.6                 | 2.6                | 0.721                        | 0.728                       | -12.61                   | -12.70                       | 28.85                  | 1096         | 34.4278137 | -118.6459200 |                                                                                 |
| P-16       | 8/6/2026 10:43:32 AM  | 53.3       | 35.9       | 0.0       | 10.9           |                         |                         | 1.5     | 0.0          | 101.5                | 101.5               | -2.77                        | -2.77                       | 5.4                 | 5.4                | 3.138                        | 3.119                       | -10.73                   | -10.62                       | 28.86                  | 1068         | 34.4275202 | -118.6456320 |                                                                                 |
| P-17       | 8/6/2026 10:49:54 AM  | 34.4       | 32.2       | 0.1       | 33.4           |                         |                         | 1.1     | 278.1        | 114.6                | 114.7               | -1.02                        | -1.01                       |                     |                    | 1.023                        | 1.015                       | -11.06                   | -11.12                       | 28.85                  | 1087         | 34.4273997 | -118.6453215 |                                                                                 |
| P-18RD     | 8/9/2026 2:06:27 PM   | 49.1       | 35.0       | 0.0       | 15.9           |                         |                         | 1.4     | 0.0          | 111.1                | 111.2               | -5.88                        | -8.45                       | 2.1                 | 2.3                | 0.496                        | 0.573                       | -6.23                    | -9.07                        | 28.74                  | 1088         | 34.4270868 | -118.6450158 |                                                                                 |
| P-18RS     | 8/9/2026 2:03:31 PM   | 38.3       | 30.9       | 0.0       | 30.8           |                         |                         | 1.2     | 0.0          | 103.5                | 103.5               | -0.79                        | -0.75                       | 4.8                 | 4.2                | 2.402                        | 1.858                       | -7.87                    | -6.08                        | 28.74                  | 1070         | 34.4270770 | -118.6450180 |                                                                                 |
| P-19       | 8/10/2026 1:31:30 PM  | 35.0       | 30.4       | 0.0       | 34.6           |                         |                         | 1.2     | 0.0          | 97.7                 | 97.4                | -0.63                        | -0.63                       | 8.0                 | 8.1                | 0.394                        | 0.399                       | -6.70                    | -6.58                        | 28.82                  | 1079         | 34.4268863 | -118.6452035 |                                                                                 |
| P-20R      | 8/9/2026 2:19:46 PM   | 46.8       | 32.2       | 0.0       | 21.0           |                         |                         | 1.5     | 0.0          | 103.4                | 103.5               | -0.79                        | -0.76                       | 2.0                 | 2.0                | 0.434                        | 0.406                       | -6.49                    | -6.31                        | 28.74                  | 1096         | 34.4268297 | -118.6448408 |                                                                                 |
| P-21       | 8/9/2026 2:13:29 PM   | 33.3       | 30.0       | 0.0       | 36.5           |                         |                         | 1.1     | 0.0          | 102.4                | 101.4               | -0.11                        | -0.10                       |                     |                    | 0.114                        | 0.108                       | -6.73                    | -5.69                        | 28.74                  | 1103         | 34.4264883 | -118.6448122 |                                                                                 |
| P-21RD     | 8/10/2026 1:39:05 PM  | 41.2       | 34.7       | 0.0       | 24.1           |                         |                         | 1.2     | 0.0          | 106.0                | 106.4               | -3.09                        | -3.10                       | 9.0                 | 9.0                | 1.667                        | 1.694                       | -6.00                    | -5.99                        | 28.78                  | 1128         | 34.4264092 | -118.6444022 |                                                                                 |
| P-21RS     | 8/10/2026 1:42:30 PM  | 44.9       | 36.5       | 0.0       | 18.6           |                         |                         | 1.2     | 0.0          | 110.2                | 110.2               | -2.81                        | -2.83                       | 15.3                | 14.9               | 0.536                        | 0.509                       | -6.33                    | -6.38                        | 28.77                  | 1144         | 34.4263987 | -118.6444013 |                                                                                 |
| P-22RD     | 8/17/2026 10:39:55 AM | 53.9       | 42.0       | 0.0       | 4.1            |                         |                         | 1.3     | 0.0          | 119.2                | 119.5               | -4.45                        | -4.43                       | 4.8                 | 4.7                | 6.116                        | 5.900                       | -9.99                    | -9.76                        | 28.79                  | 1187         | 34.4269151 | -118.6438143 | Valve Adjustment: NSPS/EG CAI                                                   |
| P-22RS     | 8/17/2026 10:35:13 AM | 31.8       | 28.9       | 0.0       | 39.3           |                         |                         | 1.1     | 0.0          | 121.2                | 121.3               | -1.30                        | -1.29                       | 29.6                | 29.3               | 2.041                        | 1.998                       | -10.10                   | -9.91                        | 28.81                  | 1187         | 34.4269301 | -118.6438173 |                                                                                 |
| P-23       | 8/10/2026 1:56:28 PM  | 6.2        | 22.4       | 0.1       | 71.3           |                         |                         | 0.3     | 713.0        | 108.4                | 108.3               | -0.27                        | -0.26                       | 1.7                 | 1.6                | 0.017                        | 0.015                       | -6.01                    | -6.07                        | 28.8                   | 1112         | 34.4261467 | -118.6447045 |                                                                                 |
| P-24       | 8/11/2026 12:50:00 PM | 18.9       | 27.2       | 0.0       | 53.9           |                         |                         | 0.7     | 0.0          | 97.3                 | 97.4                | -1.99                        | -1.98                       | 5.6                 | 5.5                | 3.247                        | 3.148                       | -8.97                    | -8.88                        | 28.86                  | 1109         | 34.4260928 | -118.6442807 |                                                                                 |
| P-26       | 8/11/2026 1:06:02 PM  | 43.4       | 34.5       | 0.0       | 22.1           |                         |                         | 1.3     | 0.0          | 87.6                 | 87.5                | -5.77                        | -5.78                       |                     |                    | 5.777                        | 5.787                       | -8.34                    | -8.16                        | 28.85                  | 1131         | 34.4265188 | -118.6432292 |                                                                                 |
| P-27       | 8/12/2026 8:05:38 AM  | 4.6        | 21.0       | 0.5       | 73.9           |                         |                         | 0.2     | 147.8        | 84.8                 | 84.9                | -1.77                        | -1.50                       | 3.7                 | 2.6                | 3.431                        | 1.675                       | -9.15                    | -9.01                        | 28.75                  | 1137         | 34.4268262 | -118.6427893 | Valve Comment:swap well head,Valve Adjustment:Decreased Flow/Vacuum,Barely Open |
| P-27       | 8/13/2026 1:27:15 PM  | 6.9        | 19.1       | 0.3       | 73.7           |                         |                         | 0.4     | 245.7        | 94.5                 | 94.8                | -1.13                        | -1.13                       | 2.1                 | 2.1                | 1.102                        | 1.128                       | -6.49                    | -6.59                        | 28.75                  | 1126         | 34.4268223 | -118.6427908 |                                                                                 |
| P-28       | 8/12/2026 12:57:05 PM | 34.7       | 33.0       | 0.0       | 32.3           |                         |                         | 1.1     | 0.0          | 98.9                 | 98.9                | -3.74                        | -3.72                       |                     |                    | 3.698                        | 3.687                       | -6.50                    | -6.51                        | 28.74                  | 1143         | 34.4270432 | -118.6422672 |                                                                                 |
| P-29R      | 8/12/2026 8:47:04 AM  | 25.5       | 28.9       | 0.0       | 45.6           |                         |                         | 0.9     | 0.0          | 90.0                 | 90.1                | -1.01                        | -0.98                       | 0.9                 | 1.3                | 0.005                        | 0.010                       | -8.18                    | -8.19                        | 28.77                  | 1155         | 34.4272020 | -118.6418488 |                                                                                 |
| P-30R      | 8/12/2026 8:55:42 AM  | 22.1       | 28.0       | 0.0       | 49.9           |                         |                         | 0.8     | 0.0          | 88.2                 | 88.2                | -6.03                        | -5.82                       | 10.5                | 10.2               | 2.249                        | 2.103                       | -8.24                    | -8.04                        | 28.75                  | 1168         | 34.4274195 | -118.6415982 |                                                                                 |
| P-32R1     | 8/12/2026 9:30:14 AM  | 24.5       | 29.3       | 0.6       | 45.6           |                         |                         | 0.8     | 76.0         | 111.2                | 112.1               | -1.51                        | -1.53                       | 4.9                 | 4.7                | 6.487                        | 5.940                       | -7.03                    | -6.58                        | 28.74                  | 1181         | 34.4282208 | -118.6410555 |                                                                                 |
| P-32R2     | 8/12/2026 9:36:46 AM  | 28.8       | 30.5       | 0.1       | 40.6           |                         |                         | 0.9     | 406.0        | 111.3                | 111.3               | -1.83                        | -1.79                       | 10.1                | 9.4                | 2.126                        | 1.840                       | -6.87                    | -6.88                        | 28.74                  | 1190         | 34.4284427 | -118.6409438 |                                                                                 |
| P-32R2     | 8/25/2026 3:50:56 PM  | 30.0       | 23.6       | 0.0       | 46.4           |                         |                         | 1.3     | 0.0          | 111.9                | 111.8               | -1.43                        | -1.35                       | 7.0                 | 5.4                | 0.062                        | 0.037                       | -6.33                    | -5.28                        | 28.74                  | 1173         | 34.4284502 | -118.6409409 |                                                                                 |
| P-33       | 8/12/2026 9:44:10 AM  | 35.8       | 33.2       | 1.3       | 29.7           |                         |                         | 1.1     | 22.8         | 81.9                 | 83.8                | -1.35                        | -1.34                       |                     |                    | 0.008                        | 0.005                       | -0.95                    | -0.90                        | 28.73                  | 1193         | 34.4288402 | -118.6407945 |                                                                                 |
| P-36       | 8/12/2026 1:51:52 PM  | 21.3       | 28.7       | 0.0       | 50.0           |                         |                         | 0.7     | 0.0          | 100.4                | 100.6               | -0.08                        | -0.07                       |                     |                    | 0.085                        | 0.074                       | -3.72                    | -3.69                        | 28.67                  | 1212         | 34.4302285 | -118.6400872 |                                                                                 |
| P-37       | 8/3/2026 9:08:55 AM   | 9.7        | 21.5       | 0.4       | 68.4           |                         |                         | 0.5     | 171.0        | 99.7                 | 99.7                | -0.52                        | -0.43                       | 0.3                 | 0.3                | 0.017                        | 0.022                       | -6.11                    |                              | 28.58                  | 1211         | 34.4305178 | -118.6403720 |                                                                                 |
| P-38RD     | 8/3/2026 9:37:10 AM   | 41.1       | 34.9       | 0.0       | 24.0           |                         |                         | 1.2     | 0.0          | 107.8                | 107.8               | -4.39                        | -4.36                       | 34.0                | 35.7               | 1.362                        | 1.500                       | -5.68                    |                              | 28.56                  | 1211         | 34.4299900 | -118.6405735 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less                             |
| P-38RS     | 8/3/2026 9:34:21 AM   | 30.8       | 30.7       | 0.0       | 38.5           |                         |                         | 1.0     | 0.0          | 106.7                | 106.7               | -1.29                        | -1.27                       | 11.0                | 11.0               | 0.729                        | 0.731                       | -5.84                    |                              | 28.57                  | 1234         | 34.4299438 | -118.6406467 | No Adjustment Made,                                                             |
| P-39       | 8/3/2026 9:40:47 AM   | 50.1       | 41.0       | 0.3       | 8.6            |                         |                         | 1.2     | 28.7         | 95.6                 | 95.6                | -7.48                        | -7.48                       | 0.0                 | 0.0                | -0.165                       | -0.090                      | -7.30                    |                              | 28.56                  | 1194         | 34.4294752 | -118.6409963 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less                             |
| P-41       | 8/3/2026 9:46:05 AM   | 25.2       | 24.7       | 4.2       | 45.9           |                         |                         | 1.0     | 10.9         | 116.3                | 116.3               | -7.05                        | -6.92                       | 0.0                 | 0.0                | -0.414                       | -0.299                      |                          |                              | 28.57                  | 1207         | 34.4289418 | -118.6413793 |                                                                                 |
| P-42R      | 8/3/2026 9:53:05 AM   | 50.8       | 38.5       | 0.1       | 10.6           |                         |                         | 1.3     | 106.0        | 115.7                | 115.7               | -6.60                        | -6.51                       | 2.9                 | 3.2                | 0.874                        | 1.049                       | -7.23                    |                              | 28.57                  | 1198         | 34.4284440 | -118.6416385 | Increased Flow/Vacuum,Opened Valve 1/2 Turn or Less                             |
| P-43       | 8/3/2026 9:58:14 AM   | 22.3       | 25.2       | 0.8       | 51.7           |                         |                         | 0.9     | 64.6         | 117.6                | 117.6               | -3.88                        | -3.80                       | 0.0                 | 0.0                | 3.816                        | 3.815                       |                          |                              | 28.57                  | 1276         | 34.4282407 | -118.6418598 | ,                                                                               |
| P-44RD     | 8/3/2026 10:02:39 AM  | 42.6       | 32.7       | 0.0       | 24.7           |                         |                         | 1.3     | 0.0          | 104.2                | 104.2               |                              |                             |                     |                    |                              |                             |                          |                              |                        |              |            |              |                                                                                 |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name | Record Date           | CH4<br>[%] | CO2<br>[%] | O2<br>[%] | Bal Gas<br>[%] | CO<br>Reading<br>[ppmv] | H2<br>Reading<br>[ppmv] | CH4:CO2 | BalO2<br>[%] | Init<br>Temp<br>[°F] | Adj<br>Temp<br>[°F] | Init Stat<br>Press<br>["H2O] | Adj Stat<br>Press<br>["H2O] | Init Flow<br>[scfm] | Adj Flow<br>[scfm] | Init Diff<br>Press<br>["H2O] | Adj Diff<br>Press<br>["H2O] | Sys<br>Pressure<br>["H2O] | Adj Avail<br>Press<br>["H2O] | Baro<br>Press<br>["Hg] | Elev<br>[ft] | Latitude   | Longitude    | Comments                                                                     |                              |
|------------|-----------------------|------------|------------|-----------|----------------|-------------------------|-------------------------|---------|--------------|----------------------|---------------------|------------------------------|-----------------------------|---------------------|--------------------|------------------------------|-----------------------------|---------------------------|------------------------------|------------------------|--------------|------------|--------------|------------------------------------------------------------------------------|------------------------------|
| P-46RD     | 8/3/2026 10:41:13 AM  | 35.8       | 31.1       | 0.0       | 33.1           |                         |                         | 1.2     | 0.0          | 111.7                | 111.6               | -7.65                        | -7.39                       | 0.0                 | 0.0                | -0.049                       | -2.805                      | -2.33                     |                              | 28.59                  | 1204         | 34.4276548 | -118.6426797 | No Adjustment Made,                                                          |                              |
| P-46RS     | 8/3/2026 10:38:56 AM  | 19.0       | 25.4       | 0.0       | 55.6           |                         |                         | 0.7     | 0.0          | 121.8                | 121.7               | -2.27                        | -2.23                       | 21.2                | 20.6               | 2.849                        | 2.686                       | -7.89                     |                              | 28.58                  | 1178         | 34.4276615 | -118.6426515 | .                                                                            |                              |
| P-47       | 8/17/2026 10:25:36 AM | 2.5        | 17.9       | 1.5       | 78.1           |                         |                         | 0.1     | 52.1         | 76.9                 | 77.0                | -0.17                        | -0.18                       |                     |                    | 0.170                        | 0.175                       | -10.14                    | -9.77                        | 28.78                  | 1210         | 34.4274069 | -118.6432608 |                                                                              |                              |
| P-48       | 8/17/2026 10:59:26 AM | 12.7       | 23.8       | 0.0       | 63.5           |                         |                         | 0.5     | 0.0          | 121.8                | 121.9               | -0.30                        | -0.29                       | 1.7                 | 1.8                | 0.019                        | 0.021                       | -11.01                    | -10.78                       | 28.78                  | 1210         | 34.4275550 | -118.6435903 |                                                                              |                              |
| P-49RD     | 8/3/2026 10:17:37 AM  | 53.1       | 38.7       | 0.0       | 8.2            |                         |                         | 1.4     | 0.0          | 115.4                | 115.5               | -8.03                        | -8.06                       | 13.3                | 12.7               | 1.146                        | 1.049                       | -10.90                    | -10.71                       | 28.59                  | 1204         | 34.4279730 | -118.6438562 |                                                                              |                              |
| P-49RS     | 8/3/2026 10:13:44 AM  | 38.9       | 33.7       | 0.0       | 27.4           |                         |                         | 1.2     | 0.0          | 115.9                | 116.1               | -1.40                        | -1.42                       | 24.4                | 24.6               | 1.378                        | 1.403                       | -10.88                    | -10.98                       | 28.59                  | 1206         | 34.4279848 | -118.6438765 |                                                                              |                              |
| P-52       | 8/3/2026 10:53:58 AM  | 34.2       | 32.3       | 0.0       | 33.5           |                         |                         | 1.1     | 0.0          | 114.2                | 114.2               | -0.32                        | -0.30                       | 11.2                | 11.2               | 2.633                        | 2.636                       | -15.37                    | -15.67                       | 28.59                  | 1214         | 34.4287292 | -118.6433148 |                                                                              |                              |
| P-53       | 8/17/2026 11:54:22 AM | 20.2       | 27.2       | 0.0       | 52.6           |                         |                         | 0.7     | 0.0          | 114.6                | 114.6               | -0.80                        | -0.80                       | 9.2                 | 9.2                | 1.764                        | 1.772                       | -17.55                    | -17.44                       | 28.78                  | 1223         | 34.4291145 | -118.6430695 |                                                                              |                              |
| P-54       | 8/17/2026 12:05:19 PM | 26.9       | 30.7       | 0.0       | 42.4           |                         |                         | 0.9     | 0.0          | 103.8                | 103.3               | -8.08                        | -0.71                       | 22.4                | 13.4               | 10.671                       | 3.691                       | -15.52                    | -15.52                       | 28.78                  | 1226         | 34.4294152 | -118.6428993 | Valve Adjustment: NSPS/EG CAI, NSPS/EG CAC, Decreased Flow/Vacuum            |                              |
| P-54       | 8/17/2026 12:16:28 PM | 26.4       | 30.5       | 0.0       | 43.1           |                         |                         | 0.9     | 0.0          | 105.1                | 104.4               | -0.73                        | -0.58                       | 40.6                | 40.3               | 3.735                        | 3.675                       | -17.21                    | -17.21                       | 28.78                  | 1229         | 34.4294255 | -118.6429018 | Valve Adjustment: NSPS/EG CAC, On/Off Plate Changed (See Op Log)             |                              |
| P-55       | 8/17/2026 12:21:40 PM | 29.1       | 27.3       | 0.0       | 43.6           |                         |                         | 1.1     | 0.0          | 101.5                | 101.6               | -0.59                        | -0.59                       |                     |                    | 0.592                        | 0.589                       | -0.07                     | -0.07                        | 28.78                  | 1228         | 34.4297209 | -118.6427404 |                                                                              |                              |
| P-56       | 8/17/2026 12:31:15 PM | 15.3       | 24.9       | 0.2       | 59.6           |                         |                         | 0.6     | 298.0        | 103.8                | 103.8               | -0.45                        | -0.45                       |                     |                    | 0.437                        | 0.439                       | -20.19                    | -20.17                       | 28.77                  | 1233         | 34.4300992 | -118.6428200 |                                                                              |                              |
| P-57       | 8/17/2026 12:26:34 PM | 21.3       | 23.6       | 3.1       | 52.0           |                         |                         | 0.9     | 16.8         | 88.8                 | 88.9                | -0.51                        | -0.51                       | 4.6                 | 4.0                | 0.025                        | 0.020                       | -20.20                    | -20.22                       | 28.77                  | 1247         | 34.4299885 | -118.6424323 |                                                                              |                              |
| P-60R      | 8/13/2026 1:45:51 PM  | 58.7       | 36.7       | 0.0       | 4.6            |                         |                         | 1.6     | 0.0          | 95.2                 | 95.4                | -2.54                        | -2.56                       | 1.1                 | 1.0                | 0.024                        | 0.019                       | -3.71                     | -4.04                        | 28.67                  | 1230         | 34.4307722 | -118.6415547 |                                                                              |                              |
| P-61       | 8/13/2026 1:41:07 PM  | 42.9       | 34.3       | 0.0       | 22.8           |                         |                         | 1.3     | 0.0          | 88.8                 | 89.0                | -0.37                        | -0.36                       | 6.3                 | 6.1                | 4.141                        | 3.808                       | -4.18                     | -3.84                        | 28.67                  | 1243         | 34.4311088 | -118.6411372 |                                                                              |                              |
| P-65       | 8/13/2026 1:59:36 PM  | 30.8       | 28.9       | 0.0       | 40.3           |                         |                         | 1.1     | 0.0          | 88.9                 | 89.0                | -0.77                        | -0.80                       | 4.9                 | 5.1                | 0.473                        | 0.525                       | -3.75                     | -4.10                        | 28.67                  | 1245         | 34.4304112 | -118.6409787 |                                                                              |                              |
| P-71       | 8/17/2026 11:07:05 AM | 41.2       | 33.5       | 0.0       | 25.3           |                         |                         | 1.2     | 0.0          | 111.5                | 111.5               | -1.89                        | -1.92                       |                     |                    | 1.877                        | 1.906                       | -12.08                    | -12.05                       | 28.78                  | 1232         | 34.4279442 | -118.6432190 |                                                                              |                              |
| P-75       | 8/13/2026 1:52:23 PM  | 55.4       | 37.2       | 0.0       | 7.4            |                         |                         | 1.5     | 0.0          | 94.5                 | 94.5                | -3.35                        | -3.38                       | 13.8                | 14.2               | 1.171                        | 1.240                       | -4.16                     | -4.21                        | 28.67                  | 1227         | 34.4302760 | -118.6415272 |                                                                              |                              |
| P-76       | 8/3/2026 9:27:12 AM   | 17.3       | 23.4       | 1.0       | 58.3           |                         |                         | 0.7     | 58.3         | 96.8                 | 103.3               | -1.70                        | -1.63                       | 0.0                 | 0.0                | -1.756                       | -1.646                      | -5.87                     |                              | 28.56                  | 1224         | 34.4302528 | -118.6405412 | .                                                                            |                              |
| P-79       | 8/6/2026 10:33:27 AM  | 20.0       | 26.4       | 1.0       | 52.6           |                         |                         | 0.8     | 52.6         | 95.8                 | 95.9                | -0.24                        | -0.24                       |                     |                    | 0.261                        | 0.264                       | -11.27                    | -10.96                       | 28.93                  | 1007         | 34.4270367 | -118.6460662 |                                                                              |                              |
| SC-2000E   | 8/18/2026 10:35:27 AM | 38.7       | 36.5       | 0.0       | 24.8           |                         |                         | 1.1     | 0.0          | 123.6                | 123.6               | -5.05                        | -4.43                       | 5.1                 | 5.9                | 0.559                        | 0.746                       | -12.49                    | -12.60                       | 28.76                  | 1188         | 34.4307102 | -118.6467920 | Valve Adjustment: Decreased Flow/Vacuum                                      |                              |
| SC-2501E   | 8/3/2026 8:30:00 AM   |            |            |           |                |                         | 180200                  |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                              | AtmAA; [User entered 18.02%] |
| SC-2501E   | 8/3/2026 8:30:00 AM   |            |            |           |                | 1310                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                              | AtmAA                        |
| SC-2501E   | 8/3/2026 8:34:18 AM   | 1.2        | 78.3       | 0.0       | 20.5           |                         |                         | 0.0     | 0.0          | 189.2                | 189.1               | -3.86                        | -3.83                       |                     |                    | 3.835                        | 3.812                       | -8.28                     | -8.55                        | 28.46                  | 1354         | 34.4366908 | -118.6479216 | Valve Adjustment: No Flow Measurement, High Temp                             |                              |
| SC-2501E   | 8/10/2026 8:29:18 AM  | 4.3        | 72.8       | 0.5       | 22.4           |                         |                         | 0.1     | 44.8         | 189.3                | 189.3               | -2.98                        | -2.97                       |                     |                    | 2.996                        | 2.945                       | -7.22                     | -7.12                        | 28.59                  | 1358         | 34.4366930 | -118.6479175 | Valve Adjustment: No Flow Measurement, High Temp                             |                              |
| SC-2501E   | 8/10/2026 8:41:00 AM  |            |            |           |                | 1170                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                              | AtmAA                        |
| SC-2501E   | 8/17/2026 8:02:20 AM  | 13.9       | 69.5       | 1.3       | 15.3           |                         |                         | 0.2     | 11.8         | 188.6                | 188.5               | -3.40                        | -3.42                       |                     |                    | 3.398                        | 3.412                       | -7.91                     | -7.99                        | 28.65                  | 1356         | 34.4366827 | -118.6479151 | Valve Adjustment: No Flow Measurement, High Temp                             |                              |
| SC-2501E   | 8/17/2026 8:05:00 AM  |            |            |           |                | 1280                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                              | AtmAA                        |
| SC-2501E   | 8/24/2026 8:23:57 AM  | 15.4       | 69.7       | 1.2       | 13.7           |                         |                         | 0.2     | 11.4         | 189.1                | 189.1               | -3.90                        | -3.90                       |                     |                    | 3.894                        | 3.882                       | -7.96                     | -7.89                        | 28.63                  | 1347         | 34.4366794 | -118.6479121 | Valve Adjustment: No Flow Measurement, High Temp                             |                              |
| SC-2501E   | 8/31/2026 8:42:09 AM  | 4.7        | 69.8       | 0.8       | 24.7           |                         |                         | 0.1     | 30.9         | 189.0                | 188.9               | -3.89                        | -3.86                       |                     |                    | 3.872                        | 3.875                       | -7.25                     | -7.45                        | 28.57                  | 1343         | 34.4366888 | -118.6479201 | Valve Adjustment: No Flow Measurement, High Temp                             |                              |
| SC-2501W   | 8/13/2026 1:06:02 PM  | 16.9       | 68.0       | 0.8       | 14.3           |                         |                         | 0.2     | 17.9         | 169.0                | 168.6               | -2.39                        | -2.47                       |                     |                    | 2.327                        | 2.408                       | -6.38                     | -6.51                        | 28.62                  | 1351         | 34.4367602 | -118.6485232 | Valve Adjustment: NSPS/EG CAI, High Temp, Barely Open; Well Comment: No pump |                              |
| SC-2501W   | 8/13/2026 1:07:06 PM  | 16.2       | 68.9       | 0.4       | 14.5           |                         |                         | 0.2     | 36.3         | 168.6                | 168.6               | -2.40                        | -2.40                       |                     |                    | 2.328                        | 2.327                       | -5.53                     | -5.75                        | 28.63                  | 1360         | 34.4367577 | -118.6485275 |                                                                              |                              |
| SC-2501W   | 8/13/2026 3:00:00 PM  |            |            |           |                | 1240                    |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                              | AtmAA                        |
| SC-2501W   | 8/17/2026 8:30:29 AM  | 25.5       | 68.1       | 0.1       | 6.3            |                         |                         | 0.4     | 63.0         | 139.3                | 139.3               | -3.20                        | -3.18                       | 21.9                | 21.8               | 3.189                        | 3.169                       | -6.64                     | -6.61                        | 28.65                  | 1363         | 34.4367885 | -118.6485360 | Valve Adjustment: No Flow Measurement, High Temp                             |                              |
| SW-10      | 8/5/2026 12:56:57 PM  | 23.4       | 32.0       | 2.5       | 42.1           |                         |                         | 0.7     | 16.8         | 93.6                 | 93.6                | -14.29                       | -14.31                      | 10.0                | 10.1               | 0.122                        | 0.122                       | -14.32                    |                              | 28.57                  | 1325         | 34.4369645 | -118.6503190 | .                                                                            |                              |
| SW-10      | 8/12/2026 2:10:23 PM  | 17.3       | 30.4       | 4.3       | 48.0           |                         |                         | 0.6     | 11.2         | 98.3                 | 98.6                | -10.68                       | -10.49                      | 1.6                 | 1.7                | 0.016                        | 0.018                       | -11.90                    | -11.87                       | 28.56                  | 1341         | 34.4370202 | -118.6503758 | Valve Adjustment: Reconnected this Date                                      |                              |
| SW-115     | 8/5/2026 8:29:10 AM   | 40.1       | 35.4       | 0.0       | 24.5           |                         |                         | 1.1     | 0.0          | 89.0                 | 89.1                | -12.38                       | -12.36                      | 19.7                | 19.7               | 2.305                        | 2.309                       | -21.62                    |                              | 28.67                  | 1240         | 34.4348943 | -118.6412235 | No Adjustment Made,                                                          |                              |
| SW-154     | 8/11/2026 1:42:22 PM  | 0.1        | 1.0        | 19.4      | 79.5           |                         |                         | 0.1     | 4.1          | 100.0                | 100.2               | -13.81                       | -13.80                      |                     |                    | 13.854                       | 13.788                      | -13.52                    | -13.51                       | 28.68                  | 1281         | 34.4380207 | -118.6456005 | .                                                                            |                              |
| SW-187     | 8/5/2026 12:22:32 PM  | 19.8       | 34.0       | 5.2       | 41.0           |                         |                         | 0.6     | 7.9          | 97.4                 | 97.4                | -12.97                       | -12.96                      | 0.0                 | 0.0                | -0.531                       | -0.529                      |                           |                              | 28.59                  | 1276         | 34.4372302 | -118.6473348 | .                                                                            |                              |
| SW-20      | 8/17/2026 10:10:09 AM | 0.0        | 4.2        | 16.2      | 79.6           |                         |                         | 0.0     | 4.9          | 97.7                 | 98.5                | -0.76                        | -0.68                       | 2.4                 | 2.2                | 0.007                        | 0.006                       | -19.98                    | -20.14                       | 28.82                  | 1181         | 34.4302472 | -118.6436667 | Valve Adjustment: NSPS/EG CAI, Valve 100% Closed                             |                              |
| SW-2501D   | 8/5/2026 1:58:20 PM   | 1.3        | 5.3        | 20.3      | 73.1           |                         |                         | 0.2     | 3.6          | 99.3                 | 99.3                | -14.35                       | -14.30                      | 0.9                 | 0.9                | 0.091                        | 0.093                       | -14.29                    |                              | 28.65                  | 1198         | 34.4334913 | -118.6519722 | .                                                                            |                              |
| SW-2501M   | 8/5/2026 1:54:11 PM   | 10.4       | 12.4       | 14.1      | 63.1           |                         |                         | 0.8     | 4.5          | 95.9                 | 95.9                | -13.89                       | -13.86                      | 2.1                 | 2.1                | 0.456                        | 0.464                       | -13.84                    |                              | 28.65                  | 1204         | 34.4334877 | -118.6520237 | .                                                                            |                              |
| SW-2501MD  | 8/5/2026 1:56:24 PM   | 19.1       | 34.6       | 7.3       | 39.0           |                         |                         | 0.6     | 5.3          | 100.1                | 100.1               | -11.41                       | -11.40                      | 1.7                 | 1.7                | 0.317                        | 0.318                       | -13.76                    |                              | 28.65                  | 1191         | 34.4334672 | -118.6520158 | .                                                                            |                              |
| SW-2501S   | 8/5/2026 1:52:03 PM   | 1.4        | 7.1        | 14.2      | 77.3           |                         |                         | 0.2     | 5.4          | 98.0                 | 98.0                | -14.27                       | -14.21                      | 1.8                 | 1.8                | 0.340                        | 0.346                       | -14.18                    |                              | 28.65                  | 1270         | 34.4350993 | -118.6519782 | .                                                                            |                              |
| SW-2502D   | 8/5/2026 1:42:52 PM   | 9.2        | 90.0       | 0.8       | 0.0            |                         |                         | 0.1     | 0.0          | 101.2                | 101.2               | -14.27                       | -14.25                      | 1.2                 | 1.2                | 0.213                        | 0.213                       | -14.23                    |                              | 28.65                  | 1168         | 34.4337143 | -118.6519158 | .                                                                            |                              |
| SW-2502M   | 8/5/2026 1:40:28 PM   | 0.5        | 0.7        | 21.2      | 77.6           |                         |                         | 0.7     | 3.7          | 103.1                | 103.2               | -8.56                        | -8.50                       | 1.2                 | 1.2                | 0.146                        | 0.150                       | -14.08                    |                              | 28.65                  | 1161         | 34.4336775 | -118.6518943 | .                                                                            |                              |
| SW-2502MD  | 8/5/2026 1:34:59 PM   | 16.9       | 74.4       | 2.5       | 6.2            |                         |                         | 0.2     | 2.5          | 100.7                | 100.6               | -14.24                       | -14.22                      | 0.9                 | 1.0                | 0.124                        | 0.130                       | -14.20                    |                              | 28.65                  | 1178         | 34.4337462 | -118.6519755 | .                                                                            |                              |
| SW-2502S   | 8/5/2026 1:37:20 PM   | 5.0        | 15.2       | 11.7      | 68.1           |                         |                         | 0.3     | 5.8          | 93.1                 | 93.1                | -14.36                       | -14.32                      | 1.1                 | 1.1                | 0.134                        | 0.132                       | -14.31                    |                              | 28.65                  | 1138         | 34.4336890 | -118.6519427 | .                                                                            |                              |
| SW-2503D   | 8/5/2026 1:28:32 PM   | 3.9        | 7.1        | 18.2      | 70.8           |                         |                         | 0.5     | 3.9          | 100.3                | 100.3               | -14.29                       | -14.30                      | 0.6                 | 0.6                | 0.043                        | 0.041                       | -14.30                    |                              | 28.62                  | 1250         | 34.4351210 | -118.6516628 | .                                                                            |                              |
| SW-2503M   | 8/5/2026 1:25:28 PM   | 0.5        | 0.2        | 21.2      | 78.1           |                         |                         | 2.5     | 3.7          | 102.9                | 102.8               | -11.16                       | -11.13                      | 0.4                 | 0.4                | 0.020                        | 0.021                       | -14.14                    |                              | 28.62                  | 1243         | 34.4351303 | -118.6516097 | .                                                                            |                              |
| SW-2503MD  | 8/5/2026 1:18:25 PM   | 6.6        | 19.3       | 10.6      | 63.5           |                         |                         | 0.3     | 6.0          | 101.3                | 101.2               | -13.99                       | -13.99                      | 2.0                 | 2.0                | 0.473                        | 0.474                       | -13.79                    |                              | 28.62                  | 1257         | 34.4351168 | -118.6516943 | .                                                                            |                              |
| SW-2503S   | 8/5/2026 1:2          |            |            |           |                |                         |                         |         |              |                      |                     |                              |                             |                     |                    |                              |                             |                           |                              |                        |              |            |              |                                                                              |                              |

**All LFG Extraction Wells - August 2026**  
**Chiquita Canyon Landfill**

| Point Name | Record Date           | CH4  | CO2  | O2   | Bal Gas | CO Reading | H2 Reading | CH4:CO2 | BalO2 | Init Temp | Adj Temp | Init Stat Press | Adj Stat Press | Init Flow | Adj Flow | Init Diff Press | Adj Diff Press | Sys Pressure | Adj Avail Press | Baro Press | Elev | Latitude   | Longitude    | Comments                                                                      |
|------------|-----------------------|------|------|------|---------|------------|------------|---------|-------|-----------|----------|-----------------|----------------|-----------|----------|-----------------|----------------|--------------|-----------------|------------|------|------------|--------------|-------------------------------------------------------------------------------|
|            |                       | [%]  | [%]  | [%]  | [%]     | [ppmv]     | [ppmv]     |         | [%]   | [°F]      | [°F]     | [\"H2O]         | [\"H2O]        | [scfm]    | [scfm]   | [\"H2O]         | [\"H2O]        | [\"H2O]      | [\"H2O]         | [\"Hg]     | [ft] |            |              |                                                                               |
| SW-2504M   | 8/5/2026 1:15:32 PM   | 0.6  | 1.8  | 20.8 | 76.8    |            |            | 0.3     | 3.7   | 102.5     | 102.5    | -8.29           | -8.29          | 1.4       | 1.4      | 0.040           | 0.040          | -13.83       |                 | 28.62      | 1263 | 34.4352145 | -118.6516915 |                                                                               |
| SW-2504MD  | 8/5/2026 1:09:15 PM   | 15.1 | 25.7 | 7.0  | 52.2    |            |            | 0.6     | 7.5   | 98.3      | 98.3     | -14.18          | -14.22         | 1.2       | 1.1      | 0.033           | 0.024          | -14.24       |                 | 28.63      | 1270 | 34.4352723 | -118.6517973 |                                                                               |
| SW-2504S   | 8/5/2026 1:13:55 PM   | 13.4 | 17.0 | 10.8 | 58.8    |            |            | 0.8     | 5.4   | 101.7     | 101.7    | -14.21          | -14.17         | 3.2       | 4.2      | 0.218           | 0.362          | -14.15       |                 | 28.62      | 1263 | 34.4352535 | -118.6516688 |                                                                               |
| SW-30      | 8/5/2026 1:46:39 PM   | 6.6  | 31.0 | 8.7  | 53.7    |            |            | 0.2     | 6.2   | 94.9      | 94.9     | -14.22          | -14.21         | 0.0       | 0.0      | 0.054           | 0.048          |              |                 | 28.65      | 1188 | 34.4336533 | -118.6519913 |                                                                               |
| SW-32      | 8/5/2026 2:01:29 PM   | 22.1 | 53.4 | 6.8  | 17.7    |            |            | 0.4     | 2.6   | 99.3      | 99.3     | -14.27          | -14.25         | 0.0       | 0.0      | 0.035           | 0.032          |              |                 | 28.65      | 1230 | 34.4334413 | -118.6519153 |                                                                               |
| SW-64      | 8/5/2026 1:49:25 PM   | 17.6 | 79.8 | 2.4  | 0.2     |            |            | 0.2     | 0.1   | 95.2      | 95.2     | -14.03          | -14.01         | 0.0       | 0.0      | 0.111           | 0.102          |              |                 | 28.65      | 1175 | 34.4336525 | -118.6519477 |                                                                               |
| SW-65      | 8/5/2026 8:27:39 AM   | 38.1 | 33.4 | 0.5  | 28.0    |            |            | 1.1     | 56.0  | 86.8      | 87.2     | -17.78          | -17.72         | 0.3       | 4.3      | 0.001           | 0.111          | -21.24       |                 | 28.67      | 1227 | 34.4349718 | -118.6412130 |                                                                               |
| SW-66      | 8/11/2026 1:40:33 PM  | 7.7  | 10.5 | 12.5 | 69.3    |            |            | 0.7     | 5.5   | 90.9      | 90.9     | -12.56          | -12.66         |           |          | 12.603          | 12.677         | -12.57       | -12.56          | 28.67      | 1279 | 34.4379912 | -118.6456058 |                                                                               |
| SW-68      | 8/5/2026 2:03:59 PM   | 20.1 | 37.8 | 0.6  | 41.5    |            |            | 0.5     | 69.2  | 101.3     | 101.4    | -14.20          | -14.16         | 7.0       | 7.4      | 0.065           | 0.072          |              |                 | 28.65      | 1227 | 34.4334078 | -118.6519860 |                                                                               |
| SW-70      | 8/5/2026 12:31:23 PM  | 17.6 | 64.1 | 1.4  | 16.9    |            |            | 0.3     | 12.1  | 100.9     | 100.8    | -13.96          | -13.97         | 0.0       | 0.0      | -0.117          | -0.131         |              |                 | 28.58      | 1280 | 34.4372465 | -118.6473730 |                                                                               |
| SW-71      | 8/11/2026 12:58:26 PM | 12.2 | 17.4 | 7.1  | 63.3    |            |            | 0.7     | 8.9   | 92.8      | 93.0     | -5.46           | -5.81          | 2.5       | 2.6      | 0.662           | 0.704          | -8.61        | -8.75           | 28.85      | 1126 | 34.4259770 | -118.6438273 |                                                                               |
| SW-72      | 8/12/2026 1:45:10 PM  | 8.4  | 16.5 | 3.5  | 71.6    |            |            | 0.5     | 20.5  | 102.1     | 102.6    | -2.06           | -3.96          | 1.7       | 1.2      | 0.294           | 0.158          | -3.75        | -3.75           | 28.67      | 1201 | 34.4296452 | -118.6401885 |                                                                               |
| SW-80      | 8/25/2026 8:18:39 AM  | 27.0 | 27.0 | 1.8  | 44.2    |            |            | 1.0     | 24.6  | 87.6      | 88.1     | -9.76           | -9.76          | 0.7       | 0.7      | 0.003           | 0.003          | -15.80       | -15.80          | 28.78      | 1236 | 34.4382943 | -118.6433625 |                                                                               |
| SW-9       | 8/5/2026 12:36:05 PM  | 1.3  | 14.0 | 15.2 | 69.5    |            |            | 0.1     | 4.6   | 96.0      | 96.0     | -14.17          | -14.25         | 0.0       | 0.0      | 0.230           | 0.040          |              |                 | 28.59      | 1250 | 34.4372627 | -118.6473155 | Valve Adjustment:Decreased Flow/Vacuum,Barely Open                            |
| TC-1961C   | 8/27/2026 9:31:25 AM  | 7.1  | 19.8 | 0.0  | 73.1    |            |            | 0.4     | 0.0   | 117.5     | 116.8    | -3.58           | -1.93          | 17.7      | 6.7      | 0.731           | 0.104          | -14.31       | -14.19          | 28.6       | 1291 | 34.4321780 | -118.6454388 | Valve Adjustment:Decreased Flow/Vacuum                                        |
| TC-1961E   | 8/18/2026 10:05:57 AM | 39.5 | 39.3 | 0.0  | 21.2    |            |            | 1.0     | 0.0   | 128.8     | 128.8    | -10.44          | -7.07          | 35.2      | 12.9     | 3.001           | 0.398          | -19.15       | -18.61          | 28.69      | 1270 | 34.4328388 | -118.6445127 | Valve Adjustment:Decreased Flow/Vacuum                                        |
| TC-2174    | 8/3/2026 8:15:44 AM   | 0.4  | 69.0 | 0.0  | 30.6    |            |            | 0.0     | 0.0   | 185.2     | 185.2    | -3.33           | -3.28          |           |          | 3.288           | 3.213          | 0.08         | 0.04            | 28.46      | 1351 | 34.4367598 | -118.6476321 | Valve Adjustment:No Flow Measurement,High Temp                                |
| TC-2174    | 8/3/2026 8:20:00 AM   |      |      |      |         |            | 160900     |         |       |           |          |                 |                |           |          |                 |                |              |                 |            |      |            |              | AtmAA; [User entered 16.09%]                                                  |
| TC-2174    | 8/3/2026 8:20:00 AM   |      |      |      |         | 1880       |            |         |       |           |          |                 |                |           |          |                 |                |              |                 |            |      |            |              | AtmAA                                                                         |
| TC-2174    | 8/10/2026 8:22:42 AM  | 1.5  | 76.3 | 0.0  | 22.2    |            |            | 0.0     | 0.0   | 185.2     | 185.2    | -2.54           | -2.53          |           |          | 2.525           | 2.528          | 0.31         | 0.34            | 28.57      | 1357 | 34.4367603 | -118.6476345 | Valve Adjustment:No Flow Measurement,High Temp                                |
| TC-2174    | 8/10/2026 8:30:00 AM  |      |      |      |         | 2580       |            |         |       |           |          |                 |                |           |          |                 |                |              |                 |            |      |            |              | AtmAA                                                                         |
| TC-2174    | 8/17/2026 7:49:43 AM  | 3.5  | 78.5 | 0.0  | 18.0    |            |            | 0.0     | 0.0   | 185.3     | 185.3    | -2.82           | -2.75          |           |          | 2.830           | 2.786          | 0.00         | 0.00            | 28.65      | 1348 | 34.4367492 | -118.6476323 | Valve Adjustment:No Flow Measurement,High Temp                                |
| TC-2174    | 8/17/2026 7:55:00 AM  |      |      |      |         | 2470       |            |         |       |           |          |                 |                |           |          |                 |                |              |                 |            |      |            |              | AtmAA                                                                         |
| TC-2174    | 8/24/2026 8:15:18 AM  | 5.6  | 73.0 | 0.0  | 21.4    |            |            | 0.1     | 0.0   | 185.8     | 185.9    | -3.47           | -3.49          |           |          | 3.476           | 3.429          | 0.23         | 0.13            | 28.61      | 1344 | 34.4367445 | -118.6476254 | Valve Adjustment:No Flow Measurement,High Temp                                |
| TC-2174    | 8/31/2026 8:04:00 AM  | 1.5  | 74.1 | 0.0  | 24.4    |            |            | 0.0     | 0.0   | 185.5     | 185.5    | -2.95           | -2.93          |           |          | 2.980           | 2.953          | 0.00         | 0.00            | 28.57      | 1338 | 34.4367456 | -118.6476430 | Valve Adjustment:No Flow Measurement,High Temp                                |
| VL-02      | 8/24/2026 11:50:16 AM | 59.4 | 37.9 | 0.0  | 2.7     |            |            | 1.6     | 0.0   | 103.6     | 104.4    | -11.79          | -13.98         | 32.3      | 13.1     | 1.301           | 0.216          | -14.18       | -14.81          | 28.88      | 1169 | 34.4311663 | -118.6442817 | Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In) |